Attachment A. EDR Report

This attachment includes the Environmental Data Resources, Inc. (EDR) Report that provides details about potential hazardous materials sites within and adjacent to the study area.

Austin Light Rail Project - Phase 1
Austin Light Rail Project - Phase 1
Austin, TX 78704

Inquiry Number: 7418065.7s
August 16, 2023

EDR Area / Corridor Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Mapped Sites Summary	**2**
Key Map	**86**
Map Findings Summary	**87**
Focus Maps	**92**
Map Findings	**212**
Orphan Summary	**OR-1**
Government Records Searched/Data Currency Tracking	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

SUBJECT PROPERTY INFORMATION

ADDRESS

AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

TARGET PROPERTY SEARCH RESULTS

The Target Property was identified in the following databases.

Page Numbers and Map Identifcations refer to the EDR Area/Corridor Report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 06/22/2023 has revealed that there are 2 SEMS-ARCHIVE sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
HUNTSMAN PETROCHEMIC Site ID: 0601908 EPA Id: TXD041470980	***7114 N LAMAR BLVD***	***AC134 / 6***	***598***
ABM MACHINERY Site ID: 0604118 EPA Id: TXD987989340	4311 S. CONGRESS AVE	GY877 / 17	2709

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

A review of the CORRACTS list, as provided by EDR, and dated 07/24/2023 has revealed that there is 1 CORRACTS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
HUNTSMAN PETROCHEMIC	***7114 N LAMAR BLVD***	***AC134 / 6***	***598***

EPA ID:: TXD041470980

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

A review of the RCRA-TSDF list, as provided by EDR, and dated 07/24/2023 has revealed that there is 1 RCRA-TSDF site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
HUNTSMAN PETROCHEMIC EPA ID:: TXD041470980	***7114 N LAMAR BLVD***	***AC134 / 6***	***598***

Lists of Federal RCRA generators

RCRA-SQG: RCRA - Small Quantity Generators

A review of the RCRA-SQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 7 RCRA-SQG sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
KO MACHINE SHOP EPA ID:: TXD988023867	6721 N LAMAR	AF160 / 6	681
TARGET STORE T3250 EPA ID:: TXR000084233	2021 2021 GUADALUPE	CB376 / 11	1557
AUSTIN CITY ELECT UT EPA ID:: TXT490014578	***301 W AVE***	***DL513 / 11***	***1990***
WHITLEY COMPANY# EPA ID:: TXD008116857	***301-05 BRAZOS***	***DZ577 / 11***	***2127***
INNOVATIVE MEDICAL G EPA ID:: TXR000085887	1221 1221 S CONGRESS	EU667 / 14	2323
WALGREEN 2915 EPA ID:: TXR000020263	***2020 E RIVERSIDE DR***	***FO755 / 14***	***2443***
ANTIQUE STREET LAMPS EPA ID:: TXD988059879	***8412 S CONGRESS AVEW***	***HO940 / 21***	***2873***

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

A review of the RCRA-VSQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 5 RCRA-VSQG sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
BRIDENT DENTAL EPA ID:: TXR000081608	***9813 N. LAMAR BLVD.***	***47 / 3***	***346***
AUSTIN STATE HOSPITA	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***

EPA ID:: TXD120593165			
TEXACO STATION	***3016 GUADALUPE ST***	***BE292 / 8***	***1267***
EPA ID:: TX0000994756			
AUSTIN AMERICAN STAT	***305 CONGRESS AVE***	***EK622 / 14***	***2199***
EPA ID:: TXD982291569			
FAMILY DOLLAR #8248	***1508 MONTOPOLIS DR.***	***GJ825 / 15***	***2620***
EPA ID:: TXR000083077			

Federal ERNS list

ERNS: Emergency Response Notification System

A review of the ERNS list, as provided by EDR, and dated 06/12/2023 has revealed that there are 19 ERNS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
Not reported	8833 NORTH LAMAR	R63 / 6	388
NRC Report #: 776537			
Incident Date Time: 2005-10-18 09:00:00			
Not reported	7114 NORTH LAMAR BLV	AC107 / 6	458
NRC Report #: 548571			
Incident Date Time: 2000-11-18 02:00:00			
Not reported	7114 NORTH LAMAR BLV	AC110 / 6	569
NRC Report #: 405497			
Incident Date Time: 1997-09-29 12:20:00			
Not reported	7114 N. LAMAR BL.	AC118 / 6	585
NRC Report #: 324887			
Incident Date Time: 1996-02-08 10:50:00			
Not reported	7114 NORTH LAMAR BLV	AC119 / 6	585
NRC Report #: 39904			
Incident Date Time: 1990-09-16 17:00:00			
Not reported	7114 NORTH LAMAR BLV	AC124 / 6	594
NRC Report #: 538678			
Incident Date Time: 2000-08-12 18:46:00			
Not reported	7114 NORTH LAMAR BLV	AC126 / 6	595
NRC Report #: 382526			
Incident Date Time: 1997-04-03 11:02:00			
Not reported	7114 N LAMAR ST	AC128 / 6	596
Not reported	7114 N LAMAR BLVD	AC130 / 6	597
NRC Report #: 295771			
Incident Date Time: 1995-06-16 04:22:00			
Not reported	7114 N LAMAR BLVD	AC133 / 6	598
NRC Report #: 257490			
Incident Date Time: 1994-08-25 07:30:00			
Not reported	7114 NORTH LAMAR BLV	AC141 / 6	649
NRC Report #: 100538			
Incident Date Time: 1991-12-20 21:00:00			
Not reported	7114 N LAMAR BLVD	AC142 / 6	649

NRC Report #: 147966 Incident Date Time: 1992-12-07 08:00:00			
Not reported	7114 N. LAMAR	AC147 / 6	653
Not reported	4110 GUADALUPE	AV246 / 8	1069
Not reported	1901 GUDALPE ST	CD390 / 11	1640
NRC Report #: 548349 Incident Date Time: 2000-11-15 18:31:00			
Not reported	LBJ BLDG 111 EAST 17	CK420 / 11	1724
Not reported	802 SOUTH 1ST STREET	633 / 14	2236
NRC Report #: 1216746 Incident Date Time: 2018-06-28 17:25:00			
Not reported	1609 EAST RIVERSIDE	FF712 / 14	2349
NRC Report #: 69426 Incident Date Time: 1991-04-23 10:30:00			
Not reported	4703 SOUTH CONGRESS	HF898 / 17	2773
NRC Report #: 538677 Incident Date Time: 2000-08-14 12:00:00			

Lists of state and tribal landfills and solid waste disposal facilities

TX SWF/LF: Permitted Solid Waste Facilities

A review of the TX SWF/LF list, as provided by EDR, and dated 04/19/2023 has revealed that there is 1 TX SWF/LF site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
GABLES RESIDENTIAL T Facility Status: CLOSED Permit Number: 65003	4110 GUADALUPE ST	AV250 / 8	1171

TX CLI: Closed Landfill Inventory

A review of the TX CLI list, as provided by EDR, has revealed that there are 4 TX CLI sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
PLEASANT VALLEY & R Database: CLI, Date of Government Version: 08/30/1999 Date Closed: **********	SW CORNER OF PLEASAN	FP751 / 15	2439
PLEASANT VALLEY & R Database: CAPCOG LI, Date of Government Version: 11/11/2022	SW CORNER OF PLEASAN	FP752 / 15	2441
BERGSTROM AIRFORCE B Database: CLI, Date of Government Version: 08/30/1999 Date Closed: **********	N AREA OF BASE CLOSE	GT859 / 20	2687
BERGSTROM AIRFORCE B Database: CAPCOG LI, Date of Government Version: 11/11/2022	NORTH AREA OF FORMER	GT861 / 20	2690

EXECUTIVE SUMMARY

Lists of state and tribal leaking storage tanks

TX LPST: Leaking Petroleum Storage Tank Listing

A review of the TX LPST list, as provided by EDR, and dated 03/28/2023 has revealed that there are 24 TX LPST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
COXVILLE LPST Id: 107165 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0063631 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***12600 N LAMAR BLVD***	***A2 / 2***	***212***
DING DONG AUTO CENTE LPST Id: 107367 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0065041 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***6916 N LAMAR BLVD***	***AD149 / 6***	***654***
A-AABAT STORAGE LPST Id: 118958 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0085162 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***6705 N LAMAR BLVD***	***AF164 / 6***	***701***
WOODS HONDA LPST Id: 104753 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0004263 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***6509 N LAMAR BLVD***	***AH178 / 6***	***721***
SWANNS GARAGE RADIAT LPST Id: 104480 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0064126 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***6203 N LAMAR BLVD***	***AJ189 / 9***	***770***
TX. DEPT. OF PUBLIC LPST Id: 094079 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0002751 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***5805 N. LAMAR BLVD.***	***AK208 / 8***	***916***
AUSTIN STATE HOSPITA LPST Id: 109725 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0005228 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***4110 GUADALUPE***	***AV244 / 8***	***1032***
CIRCLE K STORE 27400 LPST Id: 091720 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0045186 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***3909 GUADALUPE ST***	***AY266 / 8***	***1181***
UNIVERSITY TEXACO LPST Id: 116474 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0003517	***3016 GUADALUPE ST***	***BE295 / 8***	***1271***

Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CHEVRON STATION 1071 ***2817 GUADALUPE ST*** ***BK328 / 11*** ***1351***
LPST Id: 093212
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0028643
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

U T SHELL ***1901 GUADALUPE ST*** ***CD388 / 11*** ***1616***
LPST Id: 111047
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0026119
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 23295 ***1814 GUADALUPE ST*** ***CF399 / 11*** ***1649***
LPST Id: 115013
LPST Id: 119942
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007173
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

NCNB TEXAS 219 E 6TH ST DP532 / 11 2071
LPST Id: 099342
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JUNIOR LEAGUE OF AUS ***524 E 6TH ST*** ***DR546 / 11*** ***2082***
LPST Id: 102489
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0061143
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER SETH ENGINE P 617 E 3RD ST ED592 / 11 2145
LPST Id: 094728
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0049597
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIAMOND SHAMROCK 206 160 E RIVERSIDE DR EK618 / 14 2194
LPST Id: 115780
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039559
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOPPERS MART 22 ***1609 E RIVERSIDE DR*** ***FF714 / 14*** ***2349***
LPST Id: 104746
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034930
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 22245 ***2103 S CONGRESS AVE*** ***FK738 / 14*** ***2402***
LPST Id: 104821
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007144
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SOUTHWESTERN BELL TE 201 CUMBERLAND RD GB801 / 14 2567
LPST Id: 105778
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019361
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOP N SAVE ***2204 WOODLAND AVE*** ***GC805 / 14*** ***2575***

LPST Id: 120177
CA Status: 6A - FINAL CONCURRENCE ISSUED

SUNBECK AUTOMOTIVE ***4139 S CONGRESS AVE*** ***GU864 / 18*** ***2693***
LPST Id: 105496
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063596
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AMERICAN TREE ***4311 S CONGRESS AVE*** ***GY878 / 17*** ***2710***
LPST Id: 096195
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0053804
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOP N CARRY FOOD ST 8514 S CONGRESS AVE HP942 / 21 2876
LPST Id: 092335
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010996
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOP N CARRY FOOD ST 8514 S CONGRESS AVE HP945 / 21 2878
LPST Id: 111287
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010996
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TX RDR: Release Determination Report Listing

A review of the TX RDR list, as provided by EDR, and dated 03/29/2023 has revealed that there are 22 TX RDR sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
A-AABAT STORAGE	***6705 N LAMAR BLVD***	***AF164 / 6***	***701***
AUSTIN STATE HOSPITA	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
DIAMOND SHAMROCK 80	3909 GUADALUPE ST	AY268 / 8	1235
UNIVERSITY TEXACO	3016 GUADALUPE	BE296 / 8	1285
TETCO 78	2819 GUADALUPE ST	BJ324 / 11	1343
FOODIES NO. 2	2400 RIO GRANDE STRE	BW361 / 11	1452
FORMER UT SHELL	1901 GUADALUPE ST	CD385 / 11	1608
U T SHELL	***1901 GUADALUPE ST***	***CD388 / 11***	***1616***
7 ELEVEN STORE NO 23	1814 GUADALUPE ST	CF398 / 11	1649
7-ELEVEN 23295	***1814 GUADALUPE ST***	***CF399 / 11***	***1649***
7-11 #23295	1814 GUADALUPE ST	CF400 / 11	1688
BLANTON MUSEUM LANDS	200 E MLK BLVD	CG406 / 11	1690
J HARPER STARR BLDG	106 W 6TH	DH496 / 11	1942
DIAMOND SHAMROCK 206	160 E RIVERSIDE	EK619 / 14	2195
SIGNATURE 9	900 E AVE	EN629 / 14	2233
7-ELEVEN INC 22245	2103 S CONGRESS AVE	FK734 / 14	2397
7 11 STORE 22245	2103 S CONGRESS AVE	FK736 / 14	2401
SHOP N SAVE	***2204 WOODLAND AVE***	***GC805 / 14***	***2575***
CIRCLE K 2741300	6306 E RIVERSIDE	GQ846 / 15	2653
CIRCLE K 2741300	6306 RIVERSIDE DR	GQ847 / 15	2653
CIRCLE K STORE #2741	6306 RIVERSIDE DR	GQ850 / 15	2656
JACKS NEW CONCEPT AU	***4703 S CONGRESS AVE***	***HF902 / 17***	***2775***

EXECUTIVE SUMMARY

Lists of state and tribal registered storage tanks

TX UST: Petroleum Storage Tank Database

A review of the TX UST list, as provided by EDR, and dated 03/02/2023 has revealed that there are 45 TX UST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
COXVILLE Facility Status: INACTIVE Facility Id: 63631 Facility Num: 94598 AI Number: 962439412002075	***12600 N LAMAR BLVD***	***A2 / 2***	***212***
GAREY CONSTRUCTION Facility Status: INACTIVE Facility Id: 21450 Facility Num: 58161 AI Number: 473855222002153	***11607 N LAMAR BLVD***	***E20 / 3***	***250***
KWIK STOP Facility Status: ACTIVE Facility Id: 83668 Facility Num: 128050 AI Number: 880438782010117	***11331 N LAMAR BLVD S***	***G25 / 3***	***262***
HEB 183 Facility Status: ACTIVE Facility Id: 75357 Facility Num: 115397 AI Number: 514742632003072	***9411B N LAMAR BLVD***	***P60 / 6***	***365***
AUSTIN BRAKE & CLUTC Facility Status: INACTIVE Facility Id: 3877 Facility Num: 42505 AI Number: 691280042003072	8151 N LAMAR BLVD	Y87 / 6	431
AUSTIN LABORATORIES Facility Status: INACTIVE Facility Id: 20048 Facility Num: 57152 AI Number: 495447012002075	***7114 N LAMAR BLVD***	***AC117 / 6***	***576***
DING DONG AUTO CENTE Facility Status: INACTIVE Facility Id: 65041 Facility Num: 96747 AI Number: 865652152003210	***6916 N LAMAR BLVD***	***AD149 / 6***	***654***
RAYS GARAGE Facility Status: INACTIVE Facility Id: 48798 Facility Num: 80539 AI Number: 849686242002057	***6517 N LAMAR BLVD***	***AH177 / 6***	***717***
WOODS HONDA Facility Status: INACTIVE Facility Id: 4263 Facility Num: 42953	***6509 N LAMAR BLVD***	***AH178 / 6***	***721***

AI Number: 955090002002069			
SWANNS GARAGE & RADI	***6203 N LAMAR BLVD***	***AJ187 / 9***	***737***
Facility Status: INACTIVE Facility Id: 64126 Facility Num: 95078 AI Number: 273741662002154			
TEXAS DEPT OF PUBLIC	5805 N LAMAR BLVD	AK211 / 8	953
Facility Status: ACTIVE Facility Id: 2751 Facility Num: 41292 AI Number: 696782462002205			
CENTRAL TEXAS REGION	5400 N LAMAR BLVD	AN219 / 8	1000
Facility Status: INACTIVE Facility Id: 41027 Facility Num: 70653 AI Number: 461370672002069			
AUSTIN STATE HOSPITA	***4110 GUADALUPE ST***	***AV249 / 8***	***1156***
Facility Status: ACTIVE Facility Id: 91655 Facility Num: 136752 AI Number: 438304252021007			
CIRCLE K STORE 27400	***3909 GUADALUPE ST***	***AY266 / 8***	***1181***
Facility Status: ACTIVE Facility Id: 45186 Facility Num: 74573 AI Number: 506847942002149			
CIRCLE K 3208	***3713 GUADALUPE ST***	***BB283 / 8***	***1249***
Facility Status: INACTIVE Facility Id: 36537 Facility Num: 44043 AI Number: 619600972002117			
UNIVERSITY TEXACO	***3016 GUADALUPE ST***	***BE295 / 8***	***1271***
Facility Status: INACTIVE Facility Id: 3517 Facility Num: 95508 AI Number: 518694212002152			
MARY E KOSH	3009 GUADALUPE ST	BF303 / 8	1292
Facility Status: INACTIVE Facility Id: 56470 Facility Num: 86332 AI Number: 485754352003204			
STAR STOP 74	***2819 GUADALUPE ST***	***BJ323 / 11***	***1313***
Facility Status: ACTIVE Facility Id: 28643 Facility Num: 63566 AI Number: 574685622002205			
FOODIES 2	***2400 RIO GRANDE ST***	***BW362 / 11***	***1452***
Facility Status: ACTIVE Facility Id: 38367 Facility Num: 69439 AI Number: 187378282002256			
AUSTIN MAIN POST OFF	2201 GUADALUPE ST	CA373 / 11	1535

Facility Status: INACTIVE Facility Id: 65994 Facility Num: 98513 AI Number: 706374152002075			
U T SHELL Facility Status: INACTIVE Facility Id: 26119 Facility Num: 47986 AI Number: 618606822002175	***1901 GUADALUPE ST***	***CD388 / 11***	***1616***
7-ELEVEN 23295 Facility Status: ACTIVE Facility Id: 7173 Facility Num: 46175 AI Number: 746137812002117	***1814 GUADALUPE ST***	***CF399 / 11***	***1649***
GUADALUPE MOTOR POOL Facility Status: INACTIVE Facility Id: 20854 Facility Num: 76710 AI Number: 125612332002150	***1616 GUADALUPE ST***	***CJ419 / 11***	***1721***
TRAVIS COUNTY COURTH Facility Status: INACTIVE Facility Id: 60042 Facility Num: 72700 AI Number: 835600912003202	1000 GUADALUPE ST	CS439 / 11	1785
KATZ & ATLAS Facility Status: INACTIVE Facility Id: 48781 Facility Num: 80508 AI Number: 974594802002053	***618 W 6TH ST***	***DA459 / 11***	***1906***
AUSTIN ENERGY WEST A Facility Status: INACTIVE Facility Id: 65201 Facility Num: 96600 AI Number: 249025772002150	***301 WEST AVE***	***DL515 / 11***	***1993***
JUNIOR LEAGUE OF AUS Facility Status: INACTIVE Facility Id: 61143 Facility Num: 91359 AI Number: 447715092002053	***524 E 6TH ST***	***DR546 / 11***	***2082***
SETH ENGINE PARTS Facility Status: INACTIVE Facility Id: 49597 Facility Num: 37585 AI Number: 231595552002152	***617 E 3RD ST***	***ED591 / 11***	***2141***
STOP N GO 2066 Facility Status: INACTIVE Facility Id: 39559 Facility Num: 61079 AI Number: 69753832002149	***160 E RIVERSIDE DR***	***EK617 / 14***	***2186***
AUSTIN AMERICAN STAT Facility Status: INACTIVE	***305 CONGRESS AVE***	***EK622 / 14***	***2199***

Facility Id: 19681 Facility Num: 56730 AI Number: 480521542002053			
SHOPPERS MART 22 Facility Status: INACTIVE Facility Id: 34930 Facility Num: 77359 AI Number: 820664942002225	***1609 E RIVERSIDE DR***	***FF714 / 14***	***2349***
RIVERSIDE GROCERY Facility Status: ACTIVE Facility Id: 86602 Facility Num: 131728 AI Number: 924407402014041	***1727 E RIVERSIDE DR***	***FI724 / 14***	***2361***
7-ELEVEN 23076 Facility Status: INACTIVE Facility Id: 7127 Facility Num: 46134 AI Number: 985133342002118	***1729 E RIVERSIDE DR***	***FI728 / 14***	***2390***
7-ELEVEN 22245 Facility Status: ACTIVE Facility Id: 7144 Facility Num: 46148 AI Number: 442439262002118	***2103 S CONGRESS AVE***	***FK738 / 14***	***2402***
KENNETH A ROBERTSON Facility Status: INACTIVE Facility Id: 33252 Facility Num: 45210 AI Number: 710058192002139	RIVERSIDE & BURTON	FR763 / 14	2464
GARDNER BETTS JUVENI Facility Status: INACTIVE Facility Id: 47174 Facility Num: 72699 AI Number: 592535412003097	***2515 S CONGRESS AVE***	***FZ793 / 14***	***2517***
AUSTIN HICKORY 442 C Facility Status: ACTIVE Facility Id: 19361 Facility Num: 76478 AI Number: 327651632002150	***201 CUMBERLAND RD***	***GB799 / 14***	***2530***
SHOP N SAVE Facility Status: INACTIVE Facility Id: 36105 Facility Num: 89538 AI Number: 4490462002054	***2204 WOODLAND AVE***	***GC805 / 14***	***2575***
CIRCLE K STORE 27413 Facility Status: ACTIVE Facility Id: 48561 Facility Num: 74704 AI Number: 901785062002149	***6306 E RIVERSIDE DR***	***GQ853 / 15***	***2658***
SUNBECK AUTOMOTIVE Facility Status: INACTIVE Facility Id: 63596	***4139 S CONGRESS AVE***	***GU864 / 18***	***2693***

Facility Num: 94510 AI Number: 592083672002118			
AMERICAN TREE Facility Status: INACTIVE Facility Id: 53804 Facility Num: 83615 AI Number: 900591822004293	***4311 S CONGRESS AVE***	***GY878 / 17***	***2710***
JACKS NEW CONCEPT AU Facility Status: ACTIVE Facility Id: 44890 Facility Num: 95291 AI Number: 773532182002075	***4703 S CONGRESS AVE***	***HF902 / 17***	***2775***
5503 S CONGRESS AVE Facility Status: INACTIVE Facility Id: 68959 Facility Num: 104457 AI Number: 711464802002175	***5503 S CONGRESS AVE***	***HI911 / 17***	***2803***
H & R FOOD MART Facility Status: ACTIVE Facility Id: 14277 Facility Num: 97214 AI Number: 522385872002117	***6400 S CONGRESS AVE***	***HK918 / 17***	***2812***
VACANT LOT Facility Status: INACTIVE Facility Id: 66264 Facility Num: 99328 AI Number: 683433552002075	***7307 S CONGRESS AVE***	***HM929 / 17***	***2843***

TX AST: Petroleum Storage Tank Database

A review of the TX AST list, as provided by EDR, and dated 03/02/2023 has revealed that there are 4 TX AST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
GAREY CONSTRUCTION Facility Id: 58161 Facility Id: 473855222002153 Facility Id: 21450 Facility Status: INACTIVE	11607 N LAMAR BLVD	E18 / 3	248
AUSTIN STATE HOSPITA Facility Id: 136752 Facility Id: 438304252021007 Facility Id: 91655 Facility Status: ACTIVE	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
DEAVERS CONSTRUCTION Facility Id: 112322 Facility Id: 914654692002053 Facility Id: 73702 Facility Status: INACTIVE	1601 RIO GRANDE ST	CI411 / 11	1694
AUSTIN HICKORY 442 C	201 CUMBERLAND RD	GB803 / 14	2570

Facility Id: 76478
Facility Id: 327651632002150
Facility Id: 19361
Facility Status: ACTIVE

TX TANKS: Petroleum Storage Tanks Listing

A review of the TX TANKS list, as provided by EDR, and dated 03/02/2023 has revealed that there are 3 TX TANKS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
A-AABAT STORAGE	***6705 N LAMAR BLVD***	***AF164 / 6***	***701***
GEDR AT UNION ON 24T	***2308 RIO GRANDE ST***	***BY368 / 11***	***1489***
FORMER GAS STATION P	***425 W RIVERSIDE DR***	***EH602 / 11***	***2181***

Lists of state and tribal voluntary cleanup sites

TX VCP: Voluntary Cleanup Program Database

A review of the TX VCP list, as provided by EDR, has revealed that there are 7 TX VCP sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
7121 N LAMAR BLVD	***7121 N LAMAR BLVD***	***AB103 / 6***	***451***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2481			
CRESTVIEW STATION	***7114 N LAMAR BLVD***	***AC136 / 6***	***641***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1830			
GEDR AT UNION ON 24T	***2308 RIO GRANDE ST***	***BY368 / 11***	***1489***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 371			
SCARBROUGH BUILDING	***101 W 6TH ST***	***DH508 / 11***	***1986***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 638			
AUSTIN ENERGY-ENERGY	301 WEST AVE	DL517 / 11	2004
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2485			
TOWN LAKE PLAZA SHOP	***1918 E RIVERSIDE DR***	***FL743 / 14***	***2435***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2113			
RIVERSIDE PLACE SHOP	***2410 E RIVERSIDE DR***	***GA797 / 14***	***2523***
Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 157			

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

A review of the US BROWNFIELDS list, as provided by EDR, and dated 04/06/2023 has revealed that there are 2 US BROWNFIELDS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
6705 N LAMAR BLVD, A ACRES property ID: 120301	***6705 N LAMAR BLVD,***	***AF163 / 6***	***698***
HOLLY SHORES FOOD FO ACRES property ID: 194661	COMAL STREET AND NAS	EX679 / 14	2332

Local Lists of Landfill / Solid Waste Disposal Sites

TX HIST LF: Historical Information About Municipal Solid Waste Facilities

A review of the TX HIST LF list, as provided by EDR, and dated 02/01/2022 has revealed that there are 2 TX HIST LF sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
PLEASANT VALLEY & R	SW CORNER OF PLEASAN	FP753 / 15	2442
BERGSTROM AIRFORCE B	N AREA OF BASE CLOSE	GT860 / 20	2689

Local Lists of Hazardous waste / Contaminated Sites

TX CENTRAL REGISTRY: CENTRAL REGISTRY

A review of the TX CENTRAL REGISTRY list, as provided by EDR, and dated 09/30/2022 has revealed that there are 155 TX CENTRAL REGISTRY sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
LOWES OF NE AUSTIN	12805 N LAMAR BLVD	1 / 2	211
COXVILLE	12600 N LAMAR BLVD	A3 / 2	229
NW CORNER OF IH-35 &	12501 N LAMAR BLVD	B5 / 2	231
NYOS CHARTER SCHOOL	***12333 N LAMAR BLVD***	***C8 / 2***	***233***
WALNUT PARK APARTMEN	12101 N LAMAR BLVD	D14 / 4	239
AMIGOS AUTO SALES	12100 N LAMAR BLVD	D15 / 4	241
GAREY CONSTRUCTION	***11607 N LAMAR BLVD***	***E21 / 3***	***256***
TRAILER COATING	11422 N LAMAR	F22 / 3	259
OREILLY AUTO PARTS 5	11423 N LAMAR BLVD	F23 / 3	260
KWIK STOP	11331 N LAMAR BLVD	G24 / 3	261
HERITAGE BODY & FRAM	11108 N LAMAR	H30 / 3	297
FOSTER HI-TECH FINIS	***10716 N LAMAR BLVD S***	***J33 / 3***	***329***
UNITED MOLDING	10714 N LAMAR	J36 / 3	337
LANGHAM GROUP CULTUR	***10712 N LAMAR BLVD S***	***J37 / 3***	***338***
LANGFORD CABINETS	10710 NORTH LAMAR	J38 / 3	339
AUSTEX AUTO PARTS	10101 N LAMAR BLVD	L43 / 3	341

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
AUTOZONE 1396	9905 N LAMAR BLVD	M46 / 3	344
DRY CLEAN CITY	***9626 N LAMAR BLVD***	***O52 / 6***	***354***
AUTO ZONE 1396	9620 N LAMAR BLVD	O53 / 6	360
HEB 183	9411B N LAMAR BLVD	P57 / 6	363
TARGA PORSCHE	***8833 N LAMAR BLVD***	***R65 / 6***	***389***
LACE	8829 N LAMAR BLVD	S67 / 6	394
LACE ENGINEERING	8825 N LAMAR	S69 / 6	395
TRIPLE JS TIRE CENTE	8821 N LAMAR BLVD	S70 / 6	396
ALLSTAR BODY SHOP	8703A N LAMAR BLVD	T71 / 6	396
DIP STICK	8601 N LAMAR BLVD	U76 / 6	405
FINELINE SPORTSWEAR	8451 N LAMAR BLVD	V79 / 6	408
THIRD COAST AUTO GRO	8316 N LAMAR BLVD	W82 / 6	419
AUSTIN BRAKE & CLUTC	***8151 N LAMAR BLVD***	***Y86 / 6***	***421***
D & L MOTORCYCLES	7535 N LAMAR BLVD	Z90 / 6	437
NORTH LAMAR AUTO BOD	7313 NORTH LAMAR BLV	AA94 / 6	442
JC TIRE & WHEELS	7313 N LAMAR BLVD	AA96 / 6	443
PATS LAWN MOWER SVC	***7201 N LAMAR BLVD***	***AB99 / 6***	***445***
7121 N LAMAR BLVD	7121 N LAMAR BLVD	AB101 / 6	449
AUSTIN LABORATORIES	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***
DING DONG AUTO CENTE	6916 N LAMAR BLVD	AD150 / 6	671
SOUTHCREST PARK	6811 N LAMAR BLVD	AE154 / 6	672
K O MACHINE	***6721 N LAMAR BLVD ST***	***AF157 / 6***	***674***
A-AABAT STORAGE	6705 N LAMAR BLVD	AF168 / 6	704
JEFFS CUSTOM BODY SH	***6616 N LAMAR BLVD***	***AG169 / 6***	***706***
VEHICLE REPAIR & REF	6614 N. LAMAR	AG171 / 6	712
RAYS GARAGE	6517 N LAMAR BLVD	AH175 / 6	716
WOODS HONDA	***6509 N LAMAR BLVD***	***AH178 / 6***	***721***
EARLS LAWN GARDEN EQ	***6216 N LAMAR BLVD***	***AJ181 / 9***	***732***
TJS CYCLE SALES & SE	6208 N LAMAR BLVD	AJ185 / 9	736
SWANNS GARAGE & RADI	6203 N LAMAR BLVD	AJ190 / 9	773
NORTH AUSTIN RESERVO	***5802 N LAMAR BOULEVA***	***AK193 / 8***	***785***
TEXAS DEPT OF PUBLIC	***5805 N LAMAR BLVD***	***AK207 / 8***	***906***
ATLAS AUTO AIR	***5408 N LAMAR BLVD***	***AN217 / 8***	***997***
CENTRAL TEXAS REGION	5400 N LAMAR BLVD	AN220 / 8	1004
MESA CLEANERS	4700 W GUADALUPE ST	AS231 / 8	1022
RAMPART CONSTRUCTION	4510 W GUADALUPE ST	233 / 8	1027
AUSTIN STATE HOSPITA	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
CORNER STORE 0080	3909 GUADALUPE ST	AY269 / 8	1236
CIRCLE K 3208	3713 GUADALUPE ST	BB282 / 8	1248
BUCKINGHAM INVESTMEN	711 W 32ND ST	BC289 / 8	1261
UNIVERSITY TEXACO	3016 GUADALUPE ST	BE297 / 8	1285
RETAIL CENTER 3004-3	3004-3010 GUADALUPE	BE301 / 8	1290
MARY E KOSH	3009 GUADALUPE ST	BF302 / 8	1291
HOBBY TRACT	***3000 GUADALUPE ST***	***BF306 / 8***	***1296***
STAR STOP 74	2819 GUADALUPE ST	BJ322 / 11	1309
CHEVRON 107149	2817 GUADALUPE ST	BK329 / 11	1353
AMERICAN CONSTRUCTOR	101 E 30TH ST	BL331 / 11	1354
LYDA SWINERTON BUILD	711 W 26TH ST	BP341 / 11	1394
SJL AD SPECIALTIES	2512 RIO GRANDE ST	BQ344 / 11	1398
FOODIES 2	2400 RIO GRANDE ST	BW363 / 11	1487
CORNERSTONE PLACE AP	2308 RIO GRANDE ST	BY369 / 11	1515
AUSTIN MAIN POST OFF	2201 GUADALUPE ST	CA372 / 11	1535
GINNYS COPYING SERVI	2021 GUADALUPE ST #	CB380 / 11	1604
TARGET STORE T3250	2021 GUADALUPE ST	CB381 / 11	1605
CITYVILLE AT PEARL	706 W MLK JR BLVD	CC383 / 11	1607
U T SHELL	1901 GUADALUPE ST	CD391 / 11	1641

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
7-ELEVEN 23295	***1814 GUADALUPE ST***	***CF399 / 11***	***1649***
SKANSKA USA BUILDING	200 E MARTIN LUTHER	CG407 / 11	1690
DEAVERS CONSTRUCTION	1601 RIO GRANDE ST	CI410 / 11	1693
GUADALUPE MOTOR POOL	1616 GUADALUPE ST	CJ416 / 11	1716
ENVIRONMENTAL CONTRA	***1405 RIO GRANDE ST***	***CL421 / 11***	***1724***
TRAVIS COUNTY COURTH	1000 GUADALUPE ST	CS437 / 11	1782
TEXAS DEPT OF TRANSP	125 E 11TH ST	CT442 / 11	1790
KATZ & ATLAS	618 W 6TH ST	DA458 / 11	1906
507 WEST AVENUE	507 WEST AVE	CZ463 / 11	1914
AMERICAN CLEANERS	511 RIO GRANDE ST	DA469 / 11	1919
MACONDA PARK	211 E 7TH ST STE 709	DK500 / 11	1953
SCARBROUGH BUILDING	101 W 6TH ST	DH510 / 11	1988
AUSTIN ENERGY WEST A	301 WEST AVE	DL521 / 11	2045
NCNB TEXAS	219 E 6TH ST	DP533 / 11	2072
THE REPUBLIC	401 W 4 STREET	DO537 / 11	2073
JUNIOR LEAGUE OF AUS	524 E 6TH ST	DR545 / 11	2081
AUSTIN MUSEUM OF ART	***400 W 3RD ST AUSTIN***	***DS556 / 11***	***2092***
504 5TH ST	***504 EAST 5TH ST***	***DU558 / 11***	***2093***
CATHYS DOWNTOWN CLEA	231 W 3RD ST	DV560 / 11	2098
THE WHITLEY	301 BRAZOS ST	DZ576 / 11	2125
THOMAS REPROGRAPHICS	304 E 3RD ST	EA582 / 11	2135
HOBART	404 E 2ND ST	EC587 / 11	2138
DAVIS SPRING BRANCH	151 S 1ST ST STE 200	EF597 / 11	2156
80 RAINEY STREET	78 80 82 AND 84 RAIN	EG599 / 11	2162
FORMER GAS STATION P	***425 W RIVERSIDE DR***	***EH602 / 11***	***2181***
STOP N GO 2066	160 E RIVERSIDE DR	EK620 / 14	2195
AUSTIN AMERICAN STAT	166 E RIVERSIDE DR	EK623 / 14	2222
SIGNATURE 9	900 EAST AVE	EN630 / 14	2234
CAPITOL CITY TRADE &	205 E RIVERSIDE DR	EP638 / 14	2244
INNOVATIVE MEDICAL G	***1221 S CONGRESS AVE***	***EU666 / 14***	***2317***
SAINT VINCENT	1333 S CONGRESS AVE	EY684 / 14	2336
AUSTIN COTTON	409 W MONROE ST	FA689 / 14	2337
STAR RIVERSIDE	1300 E RIVERSIDE DR	FD702 / 14	2343
SHOPPERS MART 22	1609 E RIVERSIDE DR	FF711 / 14	2348
CITY OF AUSTIN BOARD	1820 S LAKESHORE BLV	716 / 14	2359
SOUTHSHORE TOWNHOMES	1201 TOWN CREEK DR	717 / 14	2360
RIVERSIDE GROCERY	1727 E RIVERSIDE DR	FI726 / 14	2385
7 ELEVEN 23076	1729 E RIVERSIDE DR	FI730 / 14	2395
7 ELEVEN STORE 22245	2103 S CONGRESS AVE	FK735 / 14	2397
TOWN LAKE PLAZA SHOP	1918 E RIVERSIDE DR	FL744 / 14	2437
SOUTHSHORE RETAIL	1920 E RIVERSIDE DR	FL746 / 14	2438
WALGREENS 2915	2020 E RIVERSIDE DR	FO757 / 14	2460
EAST BOULDIN-EUCLID-	2400-2600 EUCLID, 24	FS765 / 14	2472
TEJAS WATER HAULERS	2405 FOREST AVE	FS766 / 14	2472
GARDNER BETTS JUVENI	2515 S CONGRESS AVE	FZ791 / 14	2515
RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	GA796 / 14	2521
HICKORY 442 XP2995	201 CUMBERLAND RD	GB802 / 14	2567
SHOP N SAVE	2204 WOODLAND AVE	GC804 / 14	2571
RIVERSIDE EAST TOWNH	5701 E RIVERSIDE DR	GL828 / 15	2628
RIVERSIDE EAST CONDO	5701 EAST RIVERSIDE	GL829 / 15	2629
RIVERSIDE EAST	5701 EAST RIVERSIDE	GL830 / 15	2629
GREYSTAR DEVELOPMENT	3801 S CONGRESS AVE	GN835 / 14	2631
SOCO CLEANERS & ALTE	3801 S CONGRESS AVE	GN836 / 14	2632
AURA RIVERSIDE	6107 EAST RIVERSIDE	GP843 / 15	2652
CIRCLE K STORE 27413	6306 E RIVERSIDE DR	GQ848 / 15	2654
IDEA PUBLIC SCHOOLS	1909 VARGAS ROAD	857 / 15	2687

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
SUNBECK AUTOMOTIVE	4139 S CONGRESS AVE	GU863 / 18	2691
GONZALEZ & LINDSEY P	1600 E HIGHWAY 71	GV867 / 20	2699
PIXELS & POWERTOOLS	4201 S CONGRESS AVE	GW868 / 18	2701
M C RIVER CITY AUTO	4201 S CONGRESS AVE	GW870 / 18	2703
4201 S CONGRESS	4201 S CONGRESS	GW872 / 18	2705
AMERICAN TREE	4311 S CONGRESS AVE	GY876 / 17	2708
THE TIRE WHAREHOUSE	***4323 S CONGRESS AVE***	***GY882 / 17***	***2720***
ST ELMO RESIDENTIAL	***4323 SOUTH CONGRESS***	***GY886 / 17***	***2726***
ELLIS AND SALAZAR	***4501 S CONGRESS AVE***	***HD893 / 17***	***2759***
OES EQUIPMENT	7900 E RIVERSIDE DR	HE897 / 19	2772
JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	HF899 / 17	2773
TITOS IMPORTS AUTO R	5310 S CONGRESS AVE	907 / 17	2801
VACANT	5503 S CONGRESS AVE	HI912 / 17	2809
SOUTHSIDE AUTO SALES	5609 1/2 S CONGRESS	914 / 17	2810
A PLUS AUTO & TRUCKS	5711 S CONGRESS AVE	HJ915 / 17	2810
H & R FOOD MART	6400 S CONGRESS AVE	HK919 / 17	2836
JACK BROWN CLEANERS	6650 S CONGRESS AVE	HL922 / 17	2839
PUBLIC STORAGE 20149	7112 S CONGRESS AVE	926 / 17	2841
VACANT LOT	7307 S CONGRESS AVE	HM928 / 17	2843
HIGHMARK	7440 S CONGRESS AVE	930 / 21	2847
SOCO SOUTH	8103 S CONGRESS AVE	HN932 / 21	2851
CAPITAL AREA FOOD BA	8201 S CONGRESS AVE	934 / 21	2852
AARONS AUTO PARTS	8409 S CONGRESS AVE	HO935 / 21	2852
HUMPHRYS HANSEN	8411 SOUTH CONGRESS	HO938 / 21	2872
ANTIQUE ST LAMPS S C	8412 SOUTH CONGRESS	HO939 / 21	2872
B AND L AUTO PART	8413 SOUTH CONGRESS	HO941 / 21	2876
OAKS AT SLAUGHTER BL	NORTHEAST CORNER OF	HP946 / 21	2879

Local Lists of Registered Storage Tanks

TX NON REGIST PST: Petroleum Storage Tank Non Registered

A review of the TX NON REGIST PST list, as provided by EDR, and dated 03/31/2023 has revealed that there is 1 TX NON REGIST PST site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
KWIK STOP	***11331 N LAMAR BLVD S***	***G25 / 3***	***262***

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

A review of the HMIRS list, as provided by EDR, and dated 03/19/2023 has revealed that there is 1 HMIRS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
6306 EAST RIVERSIDE System ID:: 521	6306 EAST RIVERSIDE	GQ849 / 15	2656

EXECUTIVE SUMMARY

TX SPILLS: Spills Database

A review of the TX SPILLS list, as provided by EDR, has revealed that there are 20 TX SPILLS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
RYDER TRUCK, IH-35 M Database: SPILLS, Date of Government Version: 04/10/2023	RYDER TRUCK, IH-35 M	W83 / 6	419
7114 N. LAMAR, AUSTI Database: SPILLS, Date of Government Version: 04/10/2023	7114 N. LAMAR, AUSTI	AC115 / 6	570
7114 NORTH LAMAR (SO Database: SPILLS, Date of Government Version: 04/10/2023	7114 NORTH LAMAR (SO	AC121 / 6	592
7114 N.LAMAR, AUSTIN Database: SPILLS, Date of Government Version: 04/10/2023	7114 N.LAMAR, AUSTIN	AC123 / 6	593
7114 NORTH LAMAR, AU Database: SPILLS, Date of Government Version: 04/10/2023	7114 NORTH LAMAR, AU	AC138 / 6	646
7114 N. LAMAR, AUSTI Database: SPILLS, Date of Government Version: 04/10/2023	7114 N. LAMAR, AUSTI	AC139 / 6	647
7114 NORTH LAMAR BLV Database: SPILLS, Date of Government Version: 04/10/2023	7114 NORTH LAMAR BLV	AC140 / 6	648
HUNTSMAN CORP. CHEMI Database: SPILLS, Date of Government Version: 04/10/2023	HUNTSMAN CORP. CHEMI	AC144 / 6	650
TEXACO CHEMICAL PLAN Database: SPILLS, Date of Government Version: 04/10/2023	TEXACO CHEMICAL PLAN	AC145 / 6	651
TEXACO CHEMICAL CO P Database: SPILLS, Date of Government Version: 04/10/2023	TEXACO CHEMICAL CO P	AC146 / 6	652
DEPARTMENT OF PUBLIC Database: SPILLS, Date of Government Version: 04/10/2023	DEPARTMENT OF PUBLIC	AK195 / 8	789
TEXAS DEPT OF PUBLIC Database: SPILLS, Date of Government Version: 04/10/2023 Incident Status: Closed Facility Id: RN101721728 Incident Number: 1323	***5805 N LAMAR, AUSTIN***	***AK198 / 8***	***791***
AUSTIN STATE HOSPITA Database: SPILLS, Date of Government Version: 04/10/2023	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
FOODIES 2 Database: SPILLS, Date of Government Version: 04/10/2023 Incident Status: Closed Facility Id: RN102866217 Incident Number: 158254	***2400 RIO GRANDE ST***	***BW358 / 11***	***1443***
PETTY LEASE-9 MILES Database: SPILLS, Date of Government Version: 04/10/2023	PETTY LEASE-9 MILES	CM423 / 11	1727
205 EAST RIVERSIDE, Database: SPILLS, Date of Government Version: 04/10/2023	205 EAST RIVERSIDE,	EP635 / 14	2239
109 JAMES STREET, SI Database: SPILLS, Date of Government Version: 04/10/2023	109 JAMES STREET, SI	EW674 / 14	2329
OAKS APARTMENTS, AUS Database: SPILLS, Date of Government Version: 04/10/2023	OAKS APARTMENTS, AUS	789 / 14	2513
MCSPADDEN AUTOMOTIVE Database: SPILLS, Date of Government Version: 04/10/2023	2716 SOUTH CONGRESS,	GE813 / 14	2596

Incident Status: Closed Facility Id: RN104146980 Incident Number: 35694			
FAIRWAY VILLAGE APTS Database: SPILLS, Date of Government Version: 04/10/2023	FAIRWAY VILLAGE APTS	GH820 / 15	2604

TX SPILLS 90: SPILLS 90 data from FirstSearch

A review of the TX SPILLS 90 list, as provided by EDR, and dated 10/23/2012 has revealed that there are 6 TX SPILLS 90 sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TEXACO CHEMICAL Site Id: TXSP1220199114	7114 N. LAMAR	AC112 / 6	569
HUNTSMAN CORP Site Id: TXSP110719945	7114 N. LAMAR	AC114 / 6	570
TEXACO CHEMICAL CO Site Id: TXSP050819908	7114 N.LAMAR	AC131 / 6	597
TEXACO CHEMICAL Site Id: TXSP031919917	7114 NORTH LAMAR (SO	AC132 / 6	597
UNKNOWN Site Id: TXSP0613199014	205 EAST RIVERSIDE	EP637 / 14	2244
FAIRWAY VILLAGE APTS Site Id: TXSP0415199116		GH821 / 15	2606

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 07/24/2023 has revealed that there are 17 RCRA NonGen / NLR sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
GAREY CONSTRUCTION C EPA ID:: TXD087309746	11607 N LAMAR	E17 / 3	246
HERITAGE BODY & FRAM EPA ID:: TXD066438946	***11108 N LAMAR BLVD***	***H29 / 3***	***291***
FOSTER HI TECH FINIS EPA ID:: TXD981146269	***10716 N LAMAR BLVD S***	***J34 / 3***	***333***
DRY CLEAN CITY EPA ID:: TXD988071395	***9626 N LAMAR BLVD***	***O51 / 6***	***350***
ALLSTAR BODY SHOP EPA ID:: TXD988059713	8703A N LAMAR BLVD	T73 / 6	400
AUSTIN BRAKE & CLUTC EPA ID:: TXD026009696	***8151 N LAMAR BLVD***	***Y86 / 6***	***421***
HUNTSMAN PETROCHEMIC	***7114 N LAMAR BLVD***	***AC134 / 6***	***598***

EPA ID:: TXD041470980			
K O MACHINE INC	***6721 N LAMAR BLVD ST***	***AF159 / 6***	***677***
EPA ID:: TXD988032884			
JEFFS CUSTOM BODY SH	***6616 N LAMAR BLVD***	***AG170 / 6***	***709***
EPA ID:: TXD102738960			
TEXAS DEPT OF PUBLIC	***5805 N LAMAR***	***AK199 / 8***	***795***
EPA ID:: TXD981901770			
CHEVRON USA INC	***2817 GUADALUPE ST***	***BK325 / 11***	***1343***
EPA ID:: TXD988035218			
GINNYS COPYING SERVI	***2021 GUADALUPE ST NO***	***CB379 / 11***	***1601***
EPA ID:: TXD063078984			
EXXON SHOP 67450	***1901 GUADALUPE***	***CD386 / 11***	***1609***
EPA ID:: TXD988031902			
HOLIDAY CLEANERS	***12300 INWOOD RD STE***	***ED593 / 11***	***2145***
EPA ID:: TXD080255581			
CFJ BARGE REFINING	***210 BARTON SPRINGS #***	***598 / 11***	***2159***
EPA ID:: TXD980865067			
CAPITAL CITY TRADE &	***205 E RIVERSIDE DR***	***EP636 / 14***	***2240***
EPA ID:: TXD982560716			
ELLIS AND SALAZAR	***4501 S CONGRESS AVE***	***HD894 / 17***	***2761***
EPA ID:: TXD981058274			

TSCA: Toxic Substances Control Act

A review of the TSCA list, as provided by EDR, and dated 12/31/2020 has revealed that there are 4 TSCA sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
AUSTIN LABORATORIES	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***
Chemical Number: 622402			
Chemical Number: 106581			
Chemical Number: 929599			
Chemical Number: 1005670			
Chemical Number: 3030475			
**Additional key fields are available in the Map Findings section*			
HUNTSMAN PETRO - AUS	7114 NORTH LAMAR BOU	AC109 / 6	568
Chemical Number: 83016700			
Chemical Number: 929599			
Chemical Number: 2752172			
Chemical Number: 10220232			
Chemical Number: 106581			
**Additional key fields are available in the Map Findings section*			
TEXACO-AUSTIN LABORA	7114 N LAMAR BLVD	AC111 / 6	569
Chemical Number: 63469238			
Chemical Number: 3312581			
Chemical Number: 2752172			
Chemical Number: 7209383			
Chemical Number: 10220232			
**Additional key fields are available in the Map Findings section*			
HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	AC113 / 6	569

EXECUTIVE SUMMARY

Chemical Number: 63469238
Chemical Number: 67151637
Chemical Number: 68909773
Chemical Number: 69493476
Chemical Number: 83016700
**Additional key fields are available in the Map Findings section*

RMP: Risk Management Plans

A review of the RMP list, as provided by EDR, and dated 04/27/2022 has revealed that there is 1 RMP site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	AC120 / 6	585

PRP: Potentially Responsible Parties

A review of the PRP list, as provided by EDR, and dated 06/22/2023 has revealed that there are 3 PRP sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TEXAS DEPARTMENT OF	5805 NORTH LAMAR	AK196 / 8	790
TEXAS DEPARTMENT OF	5805 NORTH LAMAR BLV	AK197 / 8	790
TEXAS DEPT. OF TRANS	125 E. 11TH ST.	CT440 / 11	1788

ICIS: Integrated Compliance Information System

A review of the ICIS list, as provided by EDR, and dated 11/18/2016 has revealed that there are 6 ICIS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
HUNTSMAN PETROCHEMIC FRS ID:: 110000465513	***7114 N. LAMAR BLVD.***	***AC135 / 6***	***637***
TXDOT FRS ID:: 110015748020	***125 E. 11TH STREET***	***CT441 / 11***	***1789***
KENEDY COUNTY REST A FRS ID:: 110033719073	125 E. 11TH STREET	CT443 / 11	1791
VIAWEST, INC. FRS ID:: 110043473737	***WEST 9TH STREET***	***CU448 / 11***	***1793***
SEMATECH CONSTRUCTIO FRS ID:: 110010653550	***550 OLTORF ST E***	***FY788 / 14***	***2512***
HAWTHORNE SUITES FRS ID:: 110013724256	***7800 E RIVERSIDE DR***	***HC891 / 19***	***2757***

EXECUTIVE SUMMARY

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A review of the FTTS list, as provided by EDR, has revealed that there are 3 FTTS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TEXACO CHEMICAL COMP Database: FTTS INSP, Date of Government Version: 04/09/2009	7114 N. LAMAR BOULEV	AC122 / 6	593
AUSTIN CITY OF Database: FTTS, Date of Government Version: 04/09/2009 Docket Number:: VI-306C-T Close Date:: / /	301 W AVE	DL520 / 11	2044
SOUTHSIDE RECYCLING Database: FTTS INSP, Date of Government Version: 04/09/2009	***4917 S CONGRESS AVE***	***HG906 / 17***	***2801***

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A review of the HIST FTTS list, as provided by EDR, has revealed that there are 3 HIST FTTS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
TEXACO CHEMICAL COMP Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	7114 N. LAMAR BOULEV	AC137 / 6	645
AUSTIN CITY OF Database: HIST FTTS, Date of Government Version: 10/19/2006 Close Date:: / / Docket Number:: VI-306C-T	301 W AVE	DL512 / 11	1989
SOUTHSIDE RECYCLING Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	***4917 S CONGRESS AVE***	***HG906 / 17***	***2801***

DOT OPS: Incident and Accident Data

A review of the DOT OPS list, as provided by EDR, and dated 01/02/2020 has revealed that there are 2 DOT OPS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
SOUTHERN UNION GAS C	6615 NORTH LAMAR	AG173 / 6	713
Not reported	2515 WILSON ST	785 / 14	2508

US AIRS: Aerometric Information Retrieval System Facility Subsystem

A review of the US AIRS list, as provided by EDR, has revealed that there is 1 US AIRS site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
JLR CLEANERS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110001875061	***612 BRAZOS STREET***	***DG488 / 11***	***1928***

EXECUTIVE SUMMARY

FINDS: Facility Index System/Facility Registry System

A review of the FINDS list, as provided by EDR, and dated 05/04/2023 has revealed that there are 105 FINDS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
NW CORNER OF IH-35 & Registry ID:: 110070566719	12501 N LAMAR BLVD	B4 / 2	231
NYOS CHARTER SCHOOL Registry ID:: 110070791504	12333 N LAMAR BLVD	C10 / 2	234
WALNUT PARK APARTMEN Registry ID:: 110070366169	***12101 N LAMAR BLVD***	***D13 / 4***	***239***
GAREY CONSTRUCTION Registry ID:: 110005065589	***11607 N LAMAR***	***E19 / 3***	***250***
POTOSINA MEAT MARKET Registry ID:: 110041725176	11331 N LAMAR BLVD	G27 / 3	290
PROGRESSIVE MILL WOR Registry ID:: 110070285393	11118 N LAMAR BOULEV	H28 / 3	290
HERITAGE BODY & FRAM Registry ID:: 110005058515	***11108 N LAMAR BLVD***	***H29 / 3***	***291***
FOSTER HI TECH FINIS Registry ID:: 110005086076	***10716 N LAMAR BLVD S***	***J34 / 3***	***333***
NAPA AUTO PARTS 22 Registry ID:: 110034776650	10101 N LAMAR BLVD	L42 / 3	341
AUTOZONE 1396 Registry ID:: 110033228736	9905 N LAMAR BLVD	M45 / 3	344
BRIDENT DENTAL Registry ID:: 110056335862	***9813 N. LAMAR BLVD.***	***47 / 3***	***346***
DRY CLEAN CITY Registry ID:: 110005150415	***9626 N LAMAR BLVD***	***O51 / 6***	***350***
AUTO ZONE 1396 Registry ID:: 110033457293	9620 N LAMAR BLVD	O54 / 6	361
HEB 183 Registry ID:: 110033900241	9411B N LAMAR BLVD	P59 / 6	365
ALLSTAR BODY SHOP Registry ID:: 110005145477	***8703A N LAMAR BLVD***	***T74 / 6***	***404***
UNIVAR USA ES -AUSTI Registry ID:: 110070198917	8402 N LAMAR	V81 / 6	419
AUSTIN BRAKE & CLUTC Registry ID:: 110005041392	***8151 N LAMAR BLVD***	***Y86 / 6***	***421***
HUNTSMAN PETROCHEMIC Registry ID:: 110070752608 Registry ID:: 110034407979	7114 N LAMAR BLVD	AC125 / 6	595
HUNTSMAN PETROCHEMIC Registry ID:: 110000465513	***7114 N. LAMAR BLVD.***	***AC135 / 6***	***637***
K O MACHINE INC Registry ID:: 110005133033	***6721 N LAMAR BLVD ST***	***AF159 / 6***	***677***
6705 N LAMAR BLVD, A	***6705 N LAMAR BLVD,***	***AF163 / 6***	***698***

Registry ID:: 110042111112			
JEFFS CUSTOM BODY SH Registry ID:: 110005070314	***6616 N LAMAR BLVD***	***AG170 / 6***	***709***
NORTH AUSTIN RESERVO Registry ID:: 110070816468	***5802 N LAMAR BOULEVA***	***AK192 / 8***	***785***
TEXAS DEPT OF PUBLIC Registry ID:: 110005097625	***5805 N LAMAR***	***AK199 / 8***	***795***
DPS HEADQUARTERS - D Registry ID:: 110070704357	5805 N LAMAR BLVD	AK202 / 8	808
MAXIM ENGINEERS INC Registry ID:: 110010774288	***106011 N LAMAR BLVD***	***AQ227 / 8***	***1009***
MESA CLEANERS Registry ID:: 110034710481	4700 W GUADALUPE ST	AS229 / 8	1016
AUSTIN STATE HOSPITA Registry ID:: 110028045005	***4110 GUADALUPE ST***	***AV242 / 8***	***1031***
GABLES RESIDENTIAL T Registry ID:: 110033766734	4110 GUADALUPE ST	AV243 / 8	1032
GUADALUPE HUBSITE Registry ID:: 110070198109	4201 GUADALUPE ST	AU252 / 8	1172
DIAMOND SHAMROCK 80 Registry ID:: 110034693794	3909 GUADALUPE ST	AY265 / 8	1181
CIRCLE K 3208 Registry ID:: 110070167224	3713 GUADALUPE ST	BB280 / 8	1245
INTEGRATED BUILDERS Registry ID:: 110033933064	711 N 32ND ST	BC288 / 8	1261
TEXACO STATION Registry ID:: 110005023465	***3016 GUADALUPE ST***	***BE292 / 8***	***1267***
SAGE-OCONNER ASSOCIA Registry ID:: 110035368447	3016 GUADALUPE ST	BE293 / 8	1269
RETAIL CENTER 3004-3 Registry ID:: 110034452116	3004-3010 GUADALUPE	BE300 / 8	1289
HOBBY TRACT Registry ID:: 110033884376	3000 GUADALUPE ST	BF304 / 8	1295
CHEVRON FAC 107149 Registry ID:: 110034674350	2819 GUADALUPE ST	BJ321 / 11	1309
CHEVRON USA INC Registry ID:: 110070165910 Registry ID:: 110005134684	***2817 GUADALUPE ST***	***BK325 / 11***	***1343***
AMERICAN CONSTRUCTOR Registry ID:: 110033449631	101 E 30TH ST	BL330 / 11	1354
WAG-A-BAG 24 Registry ID:: 110034348622	2400 RIO GRANDE ST	BW359 / 11	1451
CORNERSTONE PLACE AP Registry ID:: 110034372612	2308 RIO GRANDE ST	BY367 / 11	1489
TARGET STORE T3250 Registry ID:: 110070158146	***2021 2021 GUADALUPE***	***CB377 / 11***	***1561***
GINNYS COPYING SERVI	***2021 GUADALUPE ST NO***	***CB379 / 11***	***1601***

Registry ID:: 110005056946			
CITYVILLE AT PEARL Registry ID:: 110034670737	706 W MLK JR BLVD	CC382 / 11	1606
EXXON SHOP 67450 Registry ID:: 110005132356	***1901 GUADALUPE***	***CD386 / 11***	***1609***
TF AFFORDABLE HOUSIN Registry ID:: 110024279831	1717 WEST 67TH STREE	CE393 / 11	1645
7 ELEVEN STORE 23295 Registry ID:: 110033427414	1814 GUADALUPE ST	CF396 / 11	1648
UT BLANTON MUSEUM OF Registry ID:: 110071076671 Registry ID:: 110035174851	200 E MARTIN LUTHER	CG404 / 11	1689
ENVIRONMENTAL CONTRA Registry ID:: 110034231098	1405 RIO GRANDE ST	CL422 / 11	1727
TXDOT Registry ID:: 110070171136 Registry ID:: 110015748020	***125 E. 11TH STREET***	***CT441 / 11***	***1789***
VIAWEST, INC. Registry ID:: 110043473737	***WEST 9TH STREET***	***CU448 / 11***	***1793***
AMERICAN CLEANERS Registry ID:: 110033464542	511 RIO GRANDE ST	DA471 / 11	1923
JLR CLEANERS Registry ID:: 110001875061	***612 BRAZOS STREET***	***DG488 / 11***	***1928***
REEF SERVICES LLC/D/ Registry ID:: 110070132330	211 E. 7TH STREET, S	DK502 / 11	1960
SCARBROUGH BUILDING Registry ID:: 110035339746	101 W 6TH ST	DH509 / 11	1988
CARRINGTON ASSOCIATE Registry ID:: 110034193682	101 W 6TH ST	DH511 / 11	1989
AUSTIN CITY ELECT UT Registry ID:: 110005193557	***301 W AVE***	***DL513 / 11***	***1990***
CITY OF AUSTIN Registry ID:: 110034288919	301 WEST AVE	DL516 / 11	2004
THE REPUBLIC Registry ID:: 110071251726	401 W 4 STREET	DO535 / 11	2073
BLOCK 21 Registry ID:: 110033409103	201 GUADALUPE ST	DX568 / 11	2114
WHITLEY COMPANY# Registry ID:: 110005038324	***301-05 BRAZOS***	***DZ577 / 11***	***2127***
THOMAS REPROGRAPHICS Registry ID:: 110071158292	304 E 3RD ST	EA583 / 11	2136
HOLIDAY CLEANERS Registry ID:: 110005063723	***12300 INWOOD RD STE***	***ED593 / 11***	***2145***
CFJ BARGE REFINING Registry ID:: 110005080250	***210 BARTON SPRINGS #***	***598 / 11***	***2159***
TURNER CREST VILLAGE Registry ID:: 110030771010	***3.77 MI NE OF INTERX***	***621 / 14***	***2199***
AUSTIN AMERICAN STAT	***305 CONGRESS AVE***	***EK622 / 14***	***2199***

Registry ID:: 110005104083			
SHOPPERS MART 9 Registry ID:: 110035060359	900 EAST AVE	EN631 / 14	2235
JS MARKET-PLANT - 37 Registry ID:: 110049609688	611 S CONGRESS AVE S	EO632 / 14	2236
CAPITAL CITY TRADE & Registry ID:: 110005110030	***205 E RIVERSIDE DR***	***EP636 / 14***	***2240***
MUSIC LANE MIXED USE Registry ID:: 110070080495	***1100 SOUTH CONGRESS***	***ER641 / 14***	***2257***
CAMDEN SOUTH CONGRES Registry ID:: 110040157530	1007 S CONGRESS AVE	ER643 / 14	2296
INNOVATIVE MEDICAL G Registry ID:: 110071268893	1221 1221 S CONGRESS	EU665 / 14	2317
HOLLY SHORES FOOD FO Registry ID:: 110064564939	COMAL STREET AND NAS	EX680 / 14	2335
SAINT VINCENT Registry ID:: 110070362880	***1333 S CONGRESS AVE***	***EY683 / 14***	***2335***
RIVERSIDE GROCERY Registry ID:: 110056410325	***1727 E RIVERSIDE DR***	***FI727 / 14***	***2389***
7 ELEVEN 23076 Registry ID:: 110070167390	1729 E RIVERSIDE DR	FI729 / 14	2395
7 ELEVEN STORE 22245 Registry ID:: 110033437868	2103 S CONGRESS AVE	FK737 / 14	2402
WALGREEN 2915 Registry ID:: 110005176781	***2020 E RIVERSIDE DR***	***FO755 / 14***	***2443***
KENNETH A ROBERTSON Registry ID:: 110070168285	RIVERSIDE & BURTON	FR764 / 14	2471
SEMATECH CONSTRUCTIO Registry ID:: 110010653550	***550 OLTORF ST E***	***FY788 / 14***	***2512***
RIVERSIDE PLACE SHOP Registry ID:: 110037527183	2410 E RIVERSIDE DR	GA795 / 14	2521
HNQ INC DBA SHOP N S Registry ID:: 110034034373	2204 WOODLAND AVE	GC807 / 14	2594
MCSPADDEN AUTOMOTIVE Registry ID:: 110034376084	2716 S CONGRESS AVE	GE812 / 14	2595
FAMILY DOLLAR #8248 Registry ID:: 110064387015	***1508 MONTOPOLIS DR.***	***GJ825 / 15***	***2620***
GREYSTAR DEVELOPMENT Registry ID:: 110033847817	3801 S CONGRESS AVE	GN837 / 14	2635
AURA RIVERSIDE Registry ID:: 110070377437	***6107 EAST RIVERSIDE***	***GP844 / 15***	***2652***
VALERO CORNER STORE Registry ID:: 110035114275	6306 E RIVERSIDE DR	GQ851 / 15	2657
GONZALEZ & LINDSEY P Registry ID:: 110034024428	1600 E HIGHWAY 71	GV865 / 20	2699
PARKING SPOT PARKING	1600 E HIGHWAY 71	GV866 / 20	2699

Registry ID:: 110038487367			
PIXELS & POWERTOOLS Registry ID:: 110070358633 Registry ID:: 110034494205	***4201 S CONGRESS AVE***	***GW869 / 18***	***2702***
THE CONGRESS LOFTS Registry ID:: 110071347519	***4315 S CONGRESS AVE***	***GY879 / 17***	***2714***
ST ELMO RESIDENTIAL Registry ID:: 110070817606	4323 SOUTH CONGRESS	GY883 / 17	2725
THE TIRE WHAREHOUSE Registry ID:: 110035088357	4323 S CONGRESS AVE	GY885 / 17	2725
HAWTHORN SUITES LTD Registry ID:: 110013314289	***(MET CENTER)***	***HB890 / 19***	***2756***
HAWTHORNE SUITES Registry ID:: 110013724256	***7800 E RIVERSIDE DR***	***HC891 / 19***	***2757***
ELLIS AND SALAZAR Registry ID:: 110005084407	***4501 S CONGRESS AVE***	***HD894 / 17***	***2761***
JACKS NEW CONCEPT AU Registry ID:: 110033867457	4703 S CONGRESS AVE	HF900 / 17	2774
SOUTHSIDE RECYCLING Registry ID:: 110011418466	4917 S CONGRESS AVE	HG905 / 17	2800
SOCO II APARTMENTS Registry ID:: 110070356931	***6001 SOUTH CONGRESS***	***916 / 17***	***2811***
H & R FOOD MART Registry ID:: 110033919160	6400 S CONGRESS AVE	HK917 / 17	2811
JACK BROWN CLEANERS Registry ID:: 110033875625	6650 S CONGRESS AVE	HL925 / 17	2841
SOCO SOUTH Registry ID:: 110070547522	***8103 SOUTH CONGRESS***	***HN933 / 21***	***2851***
AARONS AUTO PARTS Registry ID:: 110033395813	8409 S CONGRESS AVE	HO936 / 21	2856
ANTIQUE STREET LAMPS Registry ID:: 110005145565	***8412 S CONGRESS AVEW***	***HO940 / 21***	***2873***

ECHO: Enforcement & Compliance History Information

A review of the ECHO list, as provided by EDR, and dated 03/25/2023 has revealed that there are 52 ECHO sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
NW CORNER OF IH-35 & Registry ID: 110070566719	12501 N LAMAR BLVD	B6 / 2	233
NYOS CHARTER SCHOOL Registry ID: 110070791504	12333 N LAMAR BLVD	C9 / 2	234
WALNUT PARK APARTMEN Registry ID: 110070366169	***12101 N LAMAR BLVD***	***D13 / 4***	***239***
GAREY CONSTRUCTION	***11607 N LAMAR***	***E19 / 3***	***250***

Registry ID: 110005065589			
HERITAGE BODY & FRAM Registry ID: 110005058515	***11108 N LAMAR BLVD***	***H29 / 3***	***291***
FOSTER HI TECH FINIS Registry ID: 110005086076	***10716 N LAMAR BLVD S***	***J34 / 3***	***333***
BRIDENT DENTAL Registry ID: 110056335862	***9813 N. LAMAR BLVD.***	***47 / 3***	***346***
DRY CLEAN CITY Registry ID: 110005150415	***9626 N LAMAR BLVD***	***O51 / 6***	***350***
ALLSTAR BODY SHOP Registry ID: 110005145477	***8703A N LAMAR BLVD***	***T74 / 6***	***404***
AUSTIN BRAKE & CLUTC Registry ID: 110005041392	***8151 N LAMAR BLVD***	***Y86 / 6***	***421***
HUNTSMAN PETROCHEMIC Registry ID: 110000465513	***7114 N. LAMAR BLVD.***	***AC135 / 6***	***637***
K O MACHINE INC Registry ID: 110005133033	***6721 N LAMAR BLVD ST***	***AF159 / 6***	***677***
JEFFS CUSTOM BODY SH Registry ID: 110005070314	***6616 N LAMAR BLVD***	***AG170 / 6***	***709***
NORTH AUSTIN RESERVO Registry ID: 110070816468	***5802 N LAMAR BOULEVA***	***AK192 / 8***	***785***
TEXAS DEPT OF PUBLIC Registry ID: 110005097625	***5805 N LAMAR***	***AK199 / 8***	***795***
DPS HEADQUARTERS - D Registry ID: 110070704357	5805 N LAMAR BLVD	AK201 / 8	807
MAXIM ENGINEERS INC Registry ID: 110010774288	***106011 N LAMAR BLVD***	***AQ227 / 8***	***1009***
AUSTIN STATE HOSPITA Registry ID: 110028045005	***4110 GUADALUPE ST***	***AV242 / 8***	***1031***
TEXACO STATION Registry ID: 110005023465	***3016 GUADALUPE ST***	***BE292 / 8***	***1267***
CHEVRON USA INC Registry ID: 110005134684	***2817 GUADALUPE ST***	***BK325 / 11***	***1343***
TARGET STORE T3250 Registry ID: 110070158146	***2021 2021 GUADALUPE***	***CB377 / 11***	***1561***
GINNYS COPYING SERVI Registry ID: 110005056946	***2021 GUADALUPE ST NO***	***CB379 / 11***	***1601***
EXXON SHOP 67450 Registry ID: 110005132356	***1901 GUADALUPE***	***CD386 / 11***	***1609***
UT BLANTON MUSEUM OF Registry ID: 110071076671	200 E MARTIN LUTHER	CG403 / 11	1689
TXDOT Registry ID: 110015748020	***125 E. 11TH STREET***	***CT441 / 11***	***1789***
JLR CLEANERS Registry ID: 110001875061	***612 BRAZOS STREET***	***DG488 / 11***	***1928***
AUSTIN CITY ELECT UT	***301 W AVE***	***DL513 / 11***	***1990***

Registry ID: 110005193557			
THE REPUBLIC Registry ID: 110071251726	401 W 4 STREET	DO536 / 11	2073
WHITLEY COMPANY# Registry ID: 110005038324	***301-05 BRAZOS***	***DZ577 / 11***	***2127***
THOMAS REPROGRAPHICS Registry ID: 110071158292	304 E 3RD ST	EA584 / 11	2136
HOLIDAY CLEANERS Registry ID: 110005063723	***12300 INWOOD RD STE***	***ED593 / 11***	***2145***
CFJ BARGE REFINING Registry ID: 110005080250	***210 BARTON SPRINGS #***	***598 / 11***	***2159***
TURNER CREST VILLAGE Registry ID: 110030771010	***3.77 MI NE OF INTERX***	***621 / 14***	***2199***
AUSTIN AMERICAN STAT Registry ID: 110005104083	***305 CONGRESS AVE***	***EK622 / 14***	***2199***
CAPITAL CITY TRADE & Registry ID: 110005110030	***205 E RIVERSIDE DR***	***EP636 / 14***	***2240***
MUSIC LANE MIXED USE Registry ID: 110070080495	***1100 SOUTH CONGRESS***	***ER641 / 14***	***2257***
INNOVATIVE MEDICAL G Registry ID: 110071268893	1221 1221 S CONGRESS	EU668 / 14	2326
SAINT VINCENT Registry ID: 110070362880	***1333 S CONGRESS AVE***	***EY683 / 14***	***2335***
RIVERSIDE GROCERY Registry ID: 110056410325	***1727 E RIVERSIDE DR***	***FI727 / 14***	***2389***
WALGREEN 2915 Registry ID: 110005176781	***2020 E RIVERSIDE DR***	***FO755 / 14***	***2443***
SEMATECH CONSTRUCTIO Registry ID: 110010653550	***550 OLTORF ST E***	***FY788 / 14***	***2512***
FAMILY DOLLAR #8248 Registry ID: 110064387015	***1508 MONTOPOLIS DR.***	***GJ825 / 15***	***2620***
AURA RIVERSIDE Registry ID: 110070377437	***6107 EAST RIVERSIDE***	***GP844 / 15***	***2652***
PIXELS & POWERTOOLS Registry ID: 110070358633	***4201 S CONGRESS AVE***	***GW869 / 18***	***2702***
THE CONGRESS LOFTS Registry ID: 110071347519	***4315 S CONGRESS AVE***	***GY879 / 17***	***2714***
ST ELMO RESIDENTIAL Registry ID: 110070817606	4323 SOUTH CONGRESS	GY884 / 17	2725
HAWTHORN SUITES LTD Registry ID: 110013314289	***(MET CENTER)***	***HB890 / 19***	***2756***
HAWTHORNE SUITES Registry ID: 110013724256	***7800 E RIVERSIDE DR***	***HC891 / 19***	***2757***
ELLIS AND SALAZAR Registry ID: 110005084407	***4501 S CONGRESS AVE***	***HD894 / 17***	***2761***
SOCO II APARTMENTS	***6001 SOUTH CONGRESS***	***916 / 17***	***2811***

Registry ID: 110070356931			
SOCO SOUTH	***8103 SOUTH CONGRESS***	***HN933 / 21***	***2851***
Registry ID: 110070547522			
ANTIQUE STREET LAMPS	***8412 S CONGRESS AVEW***	***HO940 / 21***	***2873***
Registry ID: 110005145565			

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

A review of the PFAS ECHO list, as provided by EDR, and dated 03/30/2023 has revealed that there are 5 PFAS ECHO sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
AUSTIN RESEARCH LABO		AB106 / 6	456
TEXAS AMERICAN 220 G		DB464 / 11	1916
BERGSTROM AIR FORCE		DB465 / 11	1917
SILICON LABORATORIES		EB585 / 11	2136
7901 E RIVERSIDE DR		HC896 / 19	2771

TX AIRS: Current Emission Inventory Data

A review of the TX AIRS list, as provided by EDR, and dated 03/09/2023 has revealed that there are 7 TX AIRS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
LANGHAM GROUP CULTUR	***10712 N LAMAR BLVD S***	***J37 / 3***	***338***
Permit Num: 141136			
Regulated Id: RN109241331			
Customer Id: CN605166214			
AUSTIN LABORATORIES	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***
Permit Num: 12995			
Permit Num: 29885			
Permit Num: 47338			
Permit Num: 47502			
Permit Num: 47509			
**Additional key fields are available in the Map Findings section*			
Regulated Id: RN100726215			
Customer Id: CN600632848			
DOWTHERM VAPOR GENER	7114 N LAMAR BLVD	AC127 / 6	595
Permit Num: 2839			
Regulated Id: RN100726215			
Customer Id: CN604173187			
STEAM GENERATOR - JC	7114 N LAMAR BLVD	AC129 / 6	596
Permit Num: 2838			
Regulated Id: RN100726215			
Customer Id: CN604173187			
TEXAS DEPT OF PUBLIC	***5805 N LAMAR BLVD***	***AK207 / 8***	***906***
Permit Num: 3141			
Regulated Id: RN101721728			
Customer Id: CN600610976			
THE TIRE WHAREHOUSE	***4323 S CONGRESS AVE***	***GY882 / 17***	***2720***

Permit Num: 37685
Regulated Id: RN100525443
Customer Id: CN600416010

ELLIS AND SALAZAR ***4501 S CONGRESS AVE*** ***HD893 / 17*** ***2759***
Permit Num: 25489
Regulated Id: RN100561968
Customer Id: CN600272736

TX ASBESTOS: ASBESTOS

A review of the TX ASBESTOS list, as provided by EDR, and dated 02/23/2023 has revealed that there are 150 TX ASBESTOS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
NYOS CHARTER SCHOOL-	12301 N. LAMAR BLVD.	11 / 4	235
WALNUT CREEK PARK MA	12138 N. LAMAR BLVD.	12 / 4	236
2 VACANT DUPLEXES	11708 N. LAMAR	16 / 3	244
KWIK STOP	***11331 N LAMAR BLVD S***	***G25 / 3***	***262***
AUTOZONE	9905 N LAMAR BLVD	M44 / 3	343
FAMILY DOLLAR	9719 N LAMAR BLVD	N48 / 6	348
DOLLAR TREE	9514 N LAMAR BLVD	56 / 6	361
ACEMART RESTAURANT S	***9411 N LAMAR BLVD***	***P58 / 6***	***363***
OUTPLAN	7121 NORTH LAMAR	AB104 / 6	453
QUICKY	6719 N LAMAR BLVD	AF161 / 6	683
NORTH LAMAR AND SHIR	6709 N LAMAR	AF162 / 6	686
TASTE OF INK	6541 N LAMAR BLVD #B	AH174 / 6	713
DEPARTMENT OF PUBLIC	5808 NORTH LAMAR BLV	AK191 / 8	776
NORTH AUSTIN RESERVO	5802 N. LAMAR	AK194 / 8	786
TEXAS DEPT OF PUBLIC	***5805 N LAMAR, AUSTIN***	***AK198 / 8***	***791***
TEXAS DEPARTMENT OF	***5805 N LAMAR BLVD***	***AK203 / 8***	***808***
DEPARTMENT OF PUBLIC	5805 NORTH LAMAR	AK204 / 8	870
TEXAS DEPARTMENT OF	5805 N. LAMAR	AK205 / 8	873
DPS HEADQUARTERS	5805 N LAMAR BLDG R	AK206 / 8	904
TEXAS DEPT OF PUBLIC	***5805 N LAMAR BLVD***	***AK207 / 8***	***906***
TX. DEPT. OF PUBLIC	***5805 N. LAMAR BLVD.***	***AK208 / 8***	***916***
TEXAS DEPARTMENT OF	5805 LAMAR BLVD	AK209 / 8	946
TEXASDEPARTMENT OF P	5805 NORTH LAMAR	AK210 / 8	948
DEPARTMENT OF PUBLIC	5801 NORTH LAMAR	AK212 / 8	975
DEPARTMENT OF PUBLIC	5801 N. LAMAR	AK213 / 8	981
CITY OF AUSTIN EMS S	5710 NORTH LAMAR BLV	AL214 / 8	987
NORTH SERVICE CENTER	5708 NORTH LAMAR BLV	AL215 / 8	993
CAMDEN LAMAR HEIGHTS	5400 N. LAMAR BLVD.	AN218 / 8	999
FORMER BUCKS FEED ST	5327 N. LAMAR	AO221 / 8	1004
VACANT BLDG. (FORMER	5242 NORTH LAMAR BLV	AP224 / 8	1007
STATE BUILDING	4900 NORTH LAMAR STR	AR228 / 8	1010
PROVISION DINING HOU	4600 W GUADALUPE STR	232 / 8	1025
PERFECTION TATTOO	4205 GUADALUPE ST	AU240 / 8	1029
AUSTIN STATE HOSPITA	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
AUSTIN STATE HOSPITA	***4110 GUADALUPE STREE***	***AV248 / 8***	***1069***
CIRCLE K STORE 27400	***3909 GUADALUPE ST***	***AY266 / 8***	***1181***
FORMER NATURAL GROCE	3901 GUADALUPE STREE	272 / 8	1240
AVENEL AT HYDE PARK	3815 GUADALUPE ST. #	BA275 / 8	1242
GOOD LUCK FOOD MART	3713 GUADALUPE ST	BB281 / 8	1246
MAC'S PIZZA	3701 GUADALUPE	BB284 / 8	1254
VACANT LEASE SPACE	3701 GUADALUPE	BB285 / 8	1257

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
WILDSIDE SMOKE SHOP	3701 GUADALUPE ST	BB286 / 8	1259
FOUNTAIN TERRACE UNI	601 W. 30TH STREET	BG310 / 8	1299
FIRST ENGLISH LUTHER	3001 WHITIS AVENUE	314 / 8	1301
PARD-ANNEX BUILDING	2818 SAN GABRIEL	BI316 / 8	1303
ANNEX BUILDING	2818 SAN GABRIEL ST.	BI317 / 8	1306
STAR STOP 74	***2819 GUADALUPE ST***	***BJ323 / 11***	***1313***
CHEVRON STATION 1071	***2817 GUADALUPE ST***	***BK328 / 11***	***1351***
MAC'S PIZZA	2701 GUADALUPE ST.	BN335 / 11	1356
FORMER FRAT HOUSE BU	2614 RIO GRANDE ST	337 / 11	1357
FRATERNITY HOUSE	800 W. 26TH ST.	BP339 / 11	1392
FRATERNITY HOUSE	800-804 WEST 26TH	BP340 / 11	1393
BRIDGEWAY	2616 WICHITA	BR345 / 11	1400
ALPHA EPSLION PHI SO	2500 RIO GRANDE ST.	BT349 / 11	1404
ALPHA EPSILON PHI SO	2500 RIO GRANDE ST.	BT350 / 11	1405
ALPHA EPSILON PHI HO	2500 RIO GRANDE	BT351 / 11	1406
STUDENT SERVICES BUI	100 W DEAN KEETON ST	BR352 / 11	1424
WALTER WEBB HALL	405 W. 25TH STREET	BU356 / 11	1426
UNIVERSITY UNITED ME	2409 GUADALUPE ST.	BV357 / 11	1442
FOODIES 2	***2400 RIO GRANDE ST***	***BW362 / 11***	***1452***
GEDR AT UNION ON 24T	***2308 RIO GRANDE ST***	***BY368 / 11***	***1489***
PARKING GARAGE	715 WEST 23RD STREET	370 / 11	1519
THE SHOPS AT DOBIE C	2021 GUADALUPE SUITE	CB375 / 11	1555
GINNYS COPYING SERVI	***2021 GUADALUPE ST #***	***CB378 / 11***	***1561***
7-ELEVEN 23295	***1814 GUADALUPE ST***	***CF399 / 11***	***1649***
VACANT RESTAURANT BL	1715 GUADALUPE ST.	CH408 / 11	1691
1705 GUADALUPE ST. B	1705 GUADALUPE ST.	CH412 / 11	1695
WILLIAM GAMON INSURA	1615 GUADALUPE STREE	CJ414 / 11	1696
UT ADMINISTRATION BU	1616 GUADALUPE	CJ415 / 11	1709
ACC RIO GRANDE ST	1215 RIO GRANDE ST	CO425 / 11	1729
ACC ATTACHE BUILDING	1209 RIO GRANDE	CO426 / 11	1735
ACC RIO GRANDE CAMPU	1209 RIO GRANDE STRE	CO427 / 11	1736
TEXAS WORKFORCE COMM	1215 GUADALUPE ST.	429 / 11	1744
VACANT BUILDING	1117 CONGRESS	CQ431 / 11	1748
MUSIC LANE SHOPPING	1109 CONGRESS	CQ433 / 11	1764
HEMAN MARION SWEATT	1000 GUADALUPE STREE	CS438 / 11	1782
COMMERCIAL BUILDING	916 CONGRESS AVE	CW449 / 11	1794
VACANT BUILDING	107 E. 10TH STREET	CV450 / 11	1812
707 WEST AVE.	707 WEST AVE.	453 / 11	1815
701 RIO GRANDE	701 RIO GRANDE ST	CX454 / 11	1856
FAULK LIBRARY BUILDI	800 GUADALUPE STREET	CY455 / 11	1897
JOHN HENRY FAULK BRA	800 GUADALUPE	CY456 / 11	1904
VACANT OFFICE BUILDI	612 BRAZOS	DG490 / 11	1929
LYM ARCHITECTURE BLD	610 BRAZOS	DJ493 / 11	1932
OFFICE BUILDING	610 BRAZOS	DJ494 / 11	1936
LYM ARCHITECTURE BUI	610 BRAZOS	DJ495 / 11	1940
SOUTHWEST TOWERS	211 E 7TH	DK497 / 11	1943
SOUTHWEST TOWERS	***211 E 7TH STREET***	***DK503 / 11***	***1961***
SCARBROUGH BUILDING	101 E. 6TH STREET	DH506 / 11	1976
SCARBROUGH BLDG.	101 E. 6TH STREET	DH507 / 11	1981
AUSTIN ENERGY CONTRO	***301 WEST AVE***	***DL519 / 11***	***2006***
515 CONGRESS OFFICE	515 CONGRESS AVE.	DN526 / 11	2066
13 MAG/ IN THE FLESH	211 E 6 STREET	DP530 / 11	2069
13 MAG/IN THE FLESH	211 E 6TH ST #B	DP531 / 11	2070
BLACK CAT TATTOO	315 E 6 STREET	DQ538 / 11	2074
TATTOOS FROM THE SOU	514 E 6TH ST	DR540 / 11	2075
TATTOOS FROM THE SOU	514 E 6TH STREET	DR541 / 11	2077

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
ALL SAINTS TATTOO	514 E 6TH ST	DR542 / 11	2078
ALL SAINTS TATTOOS	514 E 6TH STREET	DR543 / 11	2079
504 5TH ST	***504 EAST 5TH ST***	***DU558 / 11***	***2093***
GAS PIPE	701 E 5TH ST	574 / 11	2117
THIRD AND BRAZOS	201 EAST 3RD	DZ580 / 11	2130
VACAN SHED	80 RAINEY STREET	EG600 / 11	2163
HOOTER'S RESTAURANT	425 WEST RIVERSIDE D	EH601 / 11	2170
OFFICE BUILDING	48 EAST AVENUE	EL625 / 14	2223
VACANT BUILDING	901 S. CONGRESS AVE.	EQ639 / 14	2245
MUSE APARTMENTS	901 S CONGRESS	EQ640 / 14	2246
MUSE APARTMENTS	1007 S. CONGRESS AVE	ER642 / 14	2258
CRAWFORD RESIDENCE	500 EAST RIVERSIDE #	653 / 14	2299
AUSTIN MOTEL	1202 SOUTH CONGRESS	EU654 / 14	2300
AUSTIN MOTEL	1204 SOUTH CONGRESS	EU655 / 14	2303
AUSTIN HOTEL	1204 SOUTH CONGRESS	EU656 / 14	2305
AUSTIN HOTEL	1204 SOUTH CONGRESS	EU657 / 14	2307
1206 S CONGRESS	1206 S. CONGRESS AVE	EU658 / 14	2308
AUSTIN MOTEL	1224 S CONGRESS	EU664 / 14	2311
INNOVATIVE MEDICAL G	***1221 S CONGRESS AVE***	***EU666 / 14***	***2317***
STATE HOUSE ON CONGR	1221 SOUTH CONGRESS	EU669 / 14	2326
RIVERVIEW APARTMENTS	1300 E. RIVERSIDE DR	FD703 / 14	2345
RIVERSIDE GROCERY	***1727 E RIVERSIDE DR***	***FI724 / 14***	***2361***
7-ELEVEN 22245	***2103 S CONGRESS AVE***	***FK738 / 14***	***2402***
WALGREENS	***2020 E RIVERSIDE DR***	***FO756 / 14***	***2451***
INSPIRED MOVEMENT	2311 S CONGRESS AVE	FT774 / 14	2475
FORMER SUBWAY	2315 S CONGRESS AVE	FT775 / 14	2476
METROPOLITAN APTS #	2423 TOWN LAKE CIRCL	FV779 / 15	2478
METROPOLITAN APARTME	2423 TOWN LAKE CENTE	FV780 / 15	2482
METROPOLITAN APARTME	2423 TOWN LAKE CIRCL	FV781 / 15	2487
ACE MART RESTAURANT	2415 S CONGRESS AVE	FU782 / 14	2493
THE JEWEL APARTMENTS	1616 ROYAL CREST	FW783 / 14	2496
JEWEL APARTMENTS	1616 ROYAL CREST DRI	FW784 / 14	2501
2501 SOUTH CONGRESS	2501 SOUTH CONGRESS	786 / 14	2509
GARDNER BETTS JUVENI	2515 SOUTH CONGRESS	FZ792 / 14	2516
RIVERSIDE PLACE SHOP	***2410 E RIVERSIDE DR***	***GA797 / 14***	***2523***
SHOP N SAVE	***2204 WOODLAND AVE***	***GC805 / 14***	***2575***
ATX FOOD MART	3002 S CONGRESS AVE	GG816 / 14	2597
ST. JOSEPH HALL	3001 CONGRESS AVE.	GG818 / 14	2599
FAIRWAY VILLAGE APAR	6118 FAIRWAY STREET	822 / 15	2606
VERDE APARTMENTS	2310 WICKERSHAM DRIV	GI823 / 15	2607
VERDE APARTMENTS	2310 WICKERSHAM LANE	GI824 / 15	2615
FAMILY DOLLAR	1590 MONTOPOLIS DR	GJ826 / 15	2623
SOUTH CONGRESS FOOD	3602 S CONGRESS AVE	GK827 / 14	2626
TWO-STORY OFFICE / R	3804 S. CONGRESS AVE	GO841 / 14	2642
CONOCO FOOD MART	6220 EAST RIVERSIDE	GP842 / 15	2643
CIRCLE K STORE 27413	***6306 E RIVERSIDE DR***	***GQ853 / 15***	***2658***
JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	GW871 / 18	2704
JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	GW873 / 18	2706
MULTIPLE STORAGE BUI	4341 CONGRESS AVE.	887 / 17	2726
ROOSTERS PAINT & D C	5501 S CONGRESS AVE	HH909 / 17	2802
SOCO II	8100 S. CONGRESS AVE	931 / 21	2849
AARONS AUTO PARTS	***8409 S CONGRESS AVE***	***HO937 / 21***	***2856***
SHOP N CARRY	8514 S CONGRESS AVE	HP943 / 21	2877

EXECUTIVE SUMMARY

TX DRYCLEANERS: Drycleaner Registration Database Listing

A review of the TX DRYCLEANERS list, as provided by EDR, and dated 01/11/2023 has revealed that there are 5 TX DRYCLEANERS sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
MESA CLEANERS AR Number: 24006970 AR Number: 24000146 AR Number: 24005314 CN Number: CN604490060 CN Number: CN602459521 CN Number: CN603277187 RN Number: RN104994827 Site Status: ACTIVE Site Status: IN PROGRESS	4700 W GUADALUPE ST	AS230 / 8	1017
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN104955513 Site Status: ACTIVE	511 RIO GRANDE ST	DA470 / 11	1921
CATHYS DOWNTOWN CLEA AR Number: 24006560 CN Number: CN604038679 RN Number: RN106343353 Site Status: ACTIVE	231 W 3RD ST	DV561 / 11	2100
SOCO CLEANERS & ALTE AR Number: 24007063 AR Number: 24006412 CN Number: CN604578534 CN Number: CN603981283 RN Number: RN106265333 Site Status: ACTIVE	3801 S CONGRESS AVE	GN838 / 14	2636
JACK BROWN CLEANERS AR Number: 24000524 CN Number: CN600264543 RN Number: RN103980835 Site Status: ACTIVE Site Status: INACTIVE	6650 S CONGRESS AVE	HL924 / 17	2840

TX ENF: Notice of Violations Listing

A review of the TX ENF list, as provided by EDR, and dated 03/17/2023 has revealed that there are 9 TX ENF sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
KWIK STOP Unique TCEQ Ref# of Reg Entity: RN105916639 Status Code: RESOLVED Status of NOV: DAPPROVED	***11331 N LAMAR BLVD***	***G26 / 3***	***285***
D & L MOTORCYCLES Unique TCEQ Ref# of Reg Entity: RN108815648	***7535 N LAMAR BLVD***	***Z89 / 6***	***435***

Status Code: RESOLVED
Status of NOV: DAPPROVED

NORTH LAMAR AUTO BOD ***7313 NORTH LAMAR BLV*** ***AA92 / 6*** ***438***
Unique TCEQ Ref# of Reg Entity: RN100723436
Status of NOV: RESOLVED

A & A USED TIRES ***7313 N LAMAR BLVD*** ***AA93 / 6*** ***439***
Unique TCEQ Ref# of Reg Entity: RN105004477
Status Code: RESOLVED
Status of NOV: DAPPROVED

PATS LAWN MOWER SVC ***7201 N LAMAR BLVD*** ***AB99 / 6*** ***445***
Unique TCEQ Ref# of Reg Entity: RN100693332
Status Code: RESOLVED
Status of NOV: DAPPROVED

TEXAS DEPT OF PUBLIC ***5805 N LAMAR, AUSTIN*** ***AK198 / 8*** ***791***
Unique TCEQ Ref# of Reg Entity: RN101721728
Status of NOV: RESOLVED

FOODIES 2 ***2400 RIO GRANDE ST*** ***BW358 / 11*** ***1443***
Unique TCEQ Ref# of Reg Entity: RN102866217
Status Code: RESOLVED
Status of NOV: DAPPROVED

WCT WALLER BEACH SIT ***74 TRINITY ST*** ***596 / 11*** ***2151***
Unique TCEQ Ref# of Reg Entity: RN106664659
Status Code: RESOLVED
Status of NOV: DAPPROVED

RIVERSIDE GROCERY ***1727 E RIVERSIDE DR*** ***FI725 / 14*** ***2378***
Unique TCEQ Ref# of Reg Entity: RN107020703
Status Code: RESOLVED
Status of NOV: DAPPROVED

TX Financial Assurance: Financial Assurance Information Listing

A review of the TX Financial Assurance list, as provided by EDR, has revealed that there are 16 TX Financial Assurance sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
KWIK STOP	***11331 N LAMAR BLVD S***	***G25 / 3***	***262***

Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 128050
AI: 83668
Finass ID: 274206
Finass ID: 257116
Finass ID: 230628
Finass ID: 237561
Finass ID: 225451
**Additional key fields are available in the Map Findings section*

HEB 183 ***9411B N LAMAR BLVD*** ***P60 / 6*** ***365***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 115397
AI: 75357
Finass ID: 271405

Finass ID: 253867
Finass ID: 233967
Finass ID: 217078
Finass ID: 200279
**Additional key fields are available in the Map Findings section*

CIRCLE K STORE 27400 ***3909 GUADALUPE ST*** ***AY266 / 8*** ***1181***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 74573
AI: 45186
Finass ID: 275358
Finass ID: 257469
Finass ID: 220794
Finass ID: 227686
Finass ID: 204446
**Additional key fields are available in the Map Findings section*

STAR STOP 74 ***2819 GUADALUPE ST*** ***BJ323 / 11*** ***1313***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 63566
AI: 28643
Finass ID: 274806
Finass ID: 256447
Finass ID: 238808
Finass ID: 219541
Finass ID: 202607
**Additional key fields are available in the Map Findings section*

FOODIES 2 ***2400 RIO GRANDE ST*** ***BW362 / 11*** ***1452***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 69439
AI: 38367
Finass ID: 269875
Finass ID: 252191
Finass ID: 232473
Finass ID: 214807
Finass ID: 199117
**Additional key fields are available in the Map Findings section*

U T SHELL ***1901 GUADALUPE ST*** ***CD388 / 11*** ***1616***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 47986
AI: 26119
Finass ID: 2176
Finass ID: 31556
Finass ID: 31557
Finass ID: 31558
Finass ID: 31559
**Additional key fields are available in the Map Findings section*

7-ELEVEN 23295 ***1814 GUADALUPE ST*** ***CF399 / 11*** ***1649***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 46175
AI: 7173
Finass ID: 278703
Finass ID: 261552
Finass ID: 242259
Finass ID: 223522

Finass ID: 224122
**Additional key fields are available in the Map Findings section*

AUSTIN ENERGY WEST A ***301 WEST AVE*** ***DL515 / 11*** ***1993***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 96600
AI: 65201
Finass ID: 107480
Finass ID: 9966
Finass ID: 82788
Finass ID: 82789
Finass ID: 82790
**Additional key fields are available in the Map Findings section*

STOP N GO 2066 ***160 E RIVERSIDE DR*** ***EK617 / 14*** ***2186***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 61079
AI: 39559
Finass ID: 43449

RIVERSIDE GROCERY ***1727 E RIVERSIDE DR*** ***FI724 / 14*** ***2361***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 131728
AI: 86602
Finass ID: 271614
Finass ID: 255487
Finass ID: 227178
Finass ID: 236743
Finass ID: 216570
**Additional key fields are available in the Map Findings section*

7-ELEVEN 22245 ***2103 S CONGRESS AVE*** ***FK738 / 14*** ***2402***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 46148
AI: 7144
Finass ID: 278697
Finass ID: 261545
Finass ID: 242252
Finass ID: 223515
Finass ID: 224115
**Additional key fields are available in the Map Findings section*

AUSTIN HICKORY 442 C ***201 CUMBERLAND RD*** ***GB799 / 14*** ***2530***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 76478
AI: 19361
Finass ID: 278452
Finass ID: 251357
Finass ID: 240527
Finass ID: 203602
Finass ID: 166477
**Additional key fields are available in the Map Findings section*

SHOP N SAVE ***2204 WOODLAND AVE*** ***GC805 / 14*** ***2575***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 89538
AI: 36105
Finass ID: 142591
Finass ID: 125962

Finass ID: 106899
Finass ID: 9267
Finass ID: 74995
**Additional key fields are available in the Map Findings section*

CIRCLE K STORE 27413 ***6306 E RIVERSIDE DR*** ***GQ853 / 15*** ***2658***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 74704
AI: 48561
Finass ID: 275426
Finass ID: 257508
Finass ID: 220965
Finass ID: 204827
Finass ID: 185549
**Additional key fields are available in the Map Findings section*

JACKS NEW CONCEPT AU ***4703 S CONGRESS AVE*** ***HF902 / 17*** ***2775***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 95291
AI: 44890
Finass ID: 8487
Finass ID: 82973
Finass ID: 82974
Finass ID: 82975

H & R FOOD MART ***6400 S CONGRESS AVE*** ***HK918 / 17*** ***2812***
Database: Financial Assurance 2, Date of Government Version: 03/02/2023
Facility Id: 97214
AI: 14277
Finass ID: 276304
Finass ID: 259014
Finass ID: 240164
Finass ID: 212874
Finass ID: 220358
**Additional key fields are available in the Map Findings section*

TX GCC: Groundwater Contamination Cases

A review of the TX GCC list, as provided by EDR, and dated 12/31/2021 has revealed that there are 12 TX GCC sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
7121 N LAMAR BLVD	***7121 N LAMAR BLVD***	***AB103 / 6***	***451***
HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	AC116 / 6	571
A-AABAT STORAGE	***6705 N LAMAR BLVD***	***AF164 / 6***	***701***
CAPITAL CITY PARTNER	***3004- 3010 GUADALUPE***	***BE291 / 8***	***1262***
7-ELEVEN 23295	***1814 GUADALUPE ST***	***CF399 / 11***	***1649***
507 WEST AVENUE	507 WEST AVENUE	CZ460 / 11	1910
507 WEST AVENUE	507 WEST AVE	CZ462 / 11	1913
AUSTIN ENERGY - ENER	301 WEST AVENUE	DL514 / 11	1993
AUSTIN ENERGY - ENER	301 WEST AVE	DL518 / 11	2005
BLOCK 21 CITY OF AUS	***201 GUADALUPE STREET***	***DX569 / 11***	***2115***
TOWN LAKE PLAZA SHOP	***1918 E RIVERSIDE DR***	***FL743 / 14***	***2435***
TOWN LAKE PLAZA SHOP	1918 EAST RIVERSIDE	FL745 / 14	2437

EXECUTIVE SUMMARY

TX IOP: Innocent Owner/Operator Program

A review of the TX IOP list, as provided by EDR, and dated 03/24/2023 has revealed that there are 4 TX IOP sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
CAPITAL CITY PARTNER IOP ID: 481	***3004- 3010 GUADALUPE***	***BE291 / 8***	***1262***
HOBBY TRACT IOP ID: 183	***3000 GUADALUPE ST***	***BF306 / 8***	***1296***
507 WEST AVENUE IOP ID: 942 IOP ID: 1120	507 WEST AVE	CZ461 / 11	1911
BLOCK 21 CITY OF AUS IOP ID: 619	***201 GUADALUPE STREET***	***DX569 / 11***	***2115***

TX LEAD: LEAD

A review of the TX LEAD list, as provided by EDR, and dated 11/28/2022 has revealed that there are 2 TX LEAD sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
Not reported	2610 EUCLID AVE	FX787 / 14	2511
Not reported	2612 EUCLID AVE	FX790 / 14	2514

TX Ind. Haz Waste: Industrial & Hazardous Waste Database

A review of the TX Ind. Haz Waste list, as provided by EDR, and dated 03/14/2023 has revealed that there are 32 TX Ind. Haz Waste sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
GAREY CONSTRUCTION Registration Number: 61207	***11607 N LAMAR BLVD***	***E21 / 3***	***256***
HERITAGE BODY & FRAM Registration Number: 67299	***11108 N LAMAR BLVD***	***H29 / 3***	***291***
FOSTER HI-TECH FINIS Registration Number: 34984	***10716 N LAMAR BLVD S***	***J33 / 3***	***329***
DRY CLEAN CITY Registration Number: 77632	***9626 N LAMAR BLVD***	***O52 / 6***	***354***
TARGA PORSCHE Registration Number: 61294	***8833 N LAMAR BLVD***	***R65 / 6***	***389***
LACE Registration Number: 30456	8829 N LAMAR BLVD	S66 / 6	392
ALLSTAR BODY SHOP Registration Number: 76797	8703A N LAMAR BLVD	T72 / 6	397
FINELINE SPORTSWEAR Registration Number: 73876	8451 N LAMAR BLVD	V78 / 6	406
AUSTIN BRAKE & CLUTC	***8151 N LAMAR BLVD***	***Y86 / 6***	***421***

Registration Number: 69307			
PATS LAWN MOWER SVC Registration Number: 61261	***7201 N LAMAR BLVD***	***AB99 / 6***	***445***
AUSTIN LABORATORIES Registration Number: 30688	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***
K O MACHINE Registration Number: 76696	***6721 N LAMAR BLVD ST***	***AF157 / 6***	***674***
JEFFS CUSTOM BODY SH Registration Number: 66410	***6616 N LAMAR BLVD***	***AG169 / 6***	***706***
WOODS HONDA Registration Number: 61325	***6509 N LAMAR BLVD***	***AH178 / 6***	***721***
EARLS LAWN GARDEN EQ Registration Number: 61187	***6216 N LAMAR BLVD***	***AJ181 / 9***	***732***
SWANNS GARAGE RADIAT Registration Number: 61288	***6203 N LAMAR BLVD***	***AJ189 / 9***	***770***
TEXAS DEPARTMENT OF Registration Number: 70244	***5805 N LAMAR BLVD***	***AK203 / 8***	***808***
ATLAS AUTO AIR Registration Number: 72268	***5408 N LAMAR BLVD***	***AN217 / 8***	***997***
AUSTIN STATE HOSPITA Registration Number: 61330	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
CHEVRON FAC 107149 Registration Number: 79170	2817 GUADALUPE ST	BK327 / 11	1348
SJL AD SPECIALTIES Registration Number: 82668	2512 RIO GRANDE ST	BQ343 / 11	1396
GINNYS COPYING SERVI Registration Number: 66204 Registration Number: 96801	***2021 GUADALUPE ST #***	***CB378 / 11***	***1561***
EXXON SHOP 67450 Registration Number: 77156	1901 GUADALUPE ST	CD387 / 11	1613
AUSTIN HIGH SCHOOL Registration Number: 69662	1715 WEST AVE LOT ST	CE394 / 11	1645
ENVIRONMENTAL CONTRA Registration Number: 41860	***1405 RIO GRANDE ST***	***CL421 / 11***	***1724***
HOBART Registration Number: 73877	404 E 2ND ST	EC588 / 11	2138
HOLIDAY CLEANERS Registration Number: 61869	***12300 INWOOD RD STE***	***ED593 / 11***	***2145***
CAPITAL CITY TRADE & Registration Number: 69372	205 E RIVERSIDE DR	EP634 / 14	2236
INNOVATIVE MEDICAL G Registration Number: 98228	***1221 S CONGRESS AVE***	***EU666 / 14***	***2317***
AUSTIN COTTON Registration Number: 81595	409 W MONROE ST	FA690 / 14	2338
WALGREENS Registration Number: 85070	***2020 E RIVERSIDE DR***	***FO756 / 14***	***2451***
ELLIS AND SALAZAR	4501 S CONGRESS AVE	HD895 / 17	2765

EXECUTIVE SUMMARY

Registration Number: 66346

TX TIER 2: Tier 2 Chemical Inventory Reports

A review of the TX TIER 2 list, as provided by EDR, and dated 12/31/2012 has revealed that there are 20 TX TIER 2 sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
AIRGAS SOUTHWEST, IN Facility Id/Name: FATR201026L4QV03PBP4 Facility Id/Name: FATR200626L4QV03PBP4 Facility Id/Name: FATR200926L4QV03PBP4 Facility Id/Name: FATR200526L4QV03PBP4 Facility Id/Name: FATR201126L4QV03PBP4 **Additional key fields are available in the Map Findings section*	11111 N. LAMAR	I31 / 3	301
AIRGAS USA, LLC - SO Facility Id/Name: FATR201226L4QV03PBP4	11111 N. LAMAR	I32 / 3	320
UNIVAR USA - PP&S AU Facility Id/Name: FATR20128EAUGC01WFT8 Facility Id/Name: FATR20118EAUGC01WFT8	8402 N. LAMAR, SUITE	V80 / 6	409
TEXAS DEPARTMENT OF Facility Id/Name: FATR20124Z3ZHU01FQYJ Facility Id/Name: FATR20114Z3ZHU01FQYJ Facility Id/Name: FATR20064Z3ZHU01FQYJ Facility Id/Name: FATR20094Z3ZHU01FQYJ Facility Id/Name: FATR20074Z3ZHU01FQYJ **Additional key fields are available in the Map Findings section*	5805 N. LAMAR BLVD.	AK200 / 8	799
AUSTIN STATE HOSPITA Facility Id/Name: FATR20086CRR5F002F3W	4101GUADALUPE STREET	235 / 8	1028
AUSTIN STATE HOSPITA Facility Id/Name: FATR201049PVFJ002111 Facility Id/Name: FATR200849PVFJ002111 Facility Id/Name: FATR200949PVFJ002111 Facility Id/Name: FATR200549PVFJ002111	***4110 GUADALUPE***	***AV244 / 8***	***1032***
AUSTIN STATE HOSPITA Facility Id/Name: FATR201249PVFJ002111 Facility Id/Name: FATR201149PVFJ002111	***4110 GUADALUPE STREE***	***AV248 / 8***	***1069***
TX-13 TIME WARNER CA Facility Id/Name: FATR20118DEE610161AE	4201 GUADALUPE ST	AU253 / 8	1172
TX-13 - TIME WARNER Facility Id/Name: FATR20128DEE610161AE	4201 GUADALUPE ST.	AU254 / 8	1175
UT AUSTIN DAS Facility Id/Name: FATR201271PUVN002LK1	1616 GUADALUPE STREE	CJ418 / 11	1717
CITY OF AUSTIN - WAT Facility Id/Name: FATR20104ZXX6N015KJG Facility Id/Name: FATR20124ZXX6N015KJG Facility Id/Name: FATR20114ZXX6N015KJG	901 WEST KOENING LAN	CR434 / 11	1770
WATER/WASTEWATER NOR Facility Id/Name: FATR20064ZXX6N015KJG	901 WEST KOENING LAN	CR435 / 11	1778

Facility Id/Name: FATR20094ZXX6N015KJG			
MCI- AUSXTX (TXAUSXT	211 E 7TH ST FL 9	DK498 / 11	1945
Facility Id/Name: FATR2011TXAUSXTX			
Facility Id/Name: FATR2012TXAUSXTX			
MCI AUSXTX	211 EAST 7TH STREET,	DK501 / 11	1954
Facility Id/Name: FATR200723GHW50HESL9			
Facility Id/Name: FATR200923GHW50HESL9			
Facility Id/Name: FATR200623GHW50HESL9			
Facility Id/Name: FATR200823GHW50HESL9			
Facility Id/Name: FATR201023GHW50HESL9			
ENERGY CONTROL CENTE	301 WEST AVE.	DL522 / 11	2048
Facility Id/Name: FATR20101FZXQ800HW26			
Facility Id/Name: FATR20061FZXQ800HW26			
Facility Id/Name: FASAFTEC433856317420			
Facility Id/Name: FATR20051FZXQ800HW26			
Facility Id/Name: FATR20111FZXQ800HW26			
**Additional key fields are available in the Map Findings section*			
SUBSTATION; SEAHOLM	704 W CESAR CHAVEZ	DW564 / 11	2108
Facility Id/Name: FASAFTEC505880228410			
SEAHOLM SUBSTATION	704 WEST CESAR CHAVE	DW565 / 11	2111
Facility Id/Name: FATR201171MMKM010FR9			
AUSTIN HICKORY 442 C	201 CUMBERLAND RD	GB800 / 14	2554
Facility Id/Name: FA201045149ZXXXXXXXX			
Facility Id/Name: FATR20063SBCIDXP2995			
Facility Id/Name: FA200845149ZXXXXXXXX			
Facility Id/Name: FATR20053SBCIDXP2995			
Facility Id/Name: FA200945149ZXXXXXXXX			
**Additional key fields are available in the Map Findings section*			
BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	GZ880 / 20	2715
Facility Id/Name: FATR200971DJEA027HXF			
BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	GZ881 / 20	2717
Facility Id/Name: FATR201071DJEA027HXF			

TX UIC: Underground Injection Wells Database Listing

A review of the TX UIC list, as provided by EDR, and dated 08/09/2022 has revealed that there is 1 TX UIC site within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
CRESTVIEW STATION	***7114 N LAMAR BLVD***	***AC136 / 6***	***641***
Status: CANCELLED			
Authorization Number: 5X2600439			

TX IHW CORR ACTION: Industrial and Hazardous Waste Corrective Action Information

A review of the TX IHW CORR ACTION list, as provided by EDR, and dated 03/24/2023 has revealed that there are 4 TX IHW CORR ACTION sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
AUSTIN LABORATORIES	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***

RN NUM: RN100726215 Program Id: 30688 Status: INACTIVE			
TEXAS DEPT OF PUBLIC RN NUM: RN101721728 Program Id: 70244 Status: INACTIVE	***5805 N LAMAR BLVD***	***AK207 / 8***	***906***
AUSTIN STATE HOSPITA RN NUM: RN100553759 Program Id: 61330 Status: INACTIVE	***4110 GUADALUPE ST***	***AV245 / 8***	***1040***
AARONS AUTO PARTS RN NUM: RN103099990 Program Id: T1674 Status: INACTIVE	***8409 S CONGRESS AVE***	***HO937 / 21***	***2856***

TX COMP HIST: Compliance History Listing

A review of the TX COMP HIST list, as provided by EDR, and dated 11/21/2022 has revealed that there are 17 TX COMP HIST sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
NYOS CHARTER SCHOOL	***12333 N LAMAR BLVD***	***C8 / 2***	***233***
KWIK STOP	***11331 N LAMAR BLVD***	***G26 / 3***	***285***
LANGHAM GROUP CULTUR	***10712 N LAMAR BLVD S***	***J37 / 3***	***338***
D & L MOTORCYCLES	***7535 N LAMAR BLVD***	***Z89 / 6***	***435***
NORTH LAMAR AUTO BOD	***7313 NORTH LAMAR BLV***	***AA92 / 6***	***438***
A & A USED TIRES	***7313 N LAMAR BLVD***	***AA93 / 6***	***439***
PATS LAWN MOWER SVC	7201 N LAMAR BLVD	AB100 / 6	449
AUSTIN LABORATORIES	***7114 N LAMAR BLVD***	***AC108 / 6***	***459***
CRESTVIEW STATION	***7114 N LAMAR BLVD***	***AC136 / 6***	***641***
NORTH AUSTIN RESERVO	***5802 N LAMAR BOULEVA***	***AK193 / 8***	***785***
TEXAS DEPT OF PUBLIC	***5805 N LAMAR BLVD***	***AK207 / 8***	***906***
FOODIES 2	2400 RIO GRANDE ST	BW360 / 11	1451
WCT WALLER BEACH SIT	***74 TRINITY ST***	***596 / 11***	***2151***
RIVERSIDE GROCERY	***1727 E RIVERSIDE DR***	***FI725 / 14***	***2378***
THE TIRE WHAREHOUSE	***4323 S CONGRESS AVE***	***GY882 / 17***	***2720***
ST ELMO RESIDENTIAL	***4323 SOUTH CONGRESS***	***GY886 / 17***	***2726***
ELLIS AND SALAZAR	***4501 S CONGRESS AVE***	***HD893 / 17***	***2759***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR Exclusive Historical Auto Stations

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 186 EDR Hist Auto sites within the requested target property.

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
7-ELEVEN INC	12434 N LAMAR BLVD	7 / 2	233
AUSTIN PERFORMANCE S	10716 LAMAR BLVD N	J35 / 3	337
CAPITAL FINA OIL SER	8909 LAMAR BLVD N	R62 / 6	388
TARGA PORSCHE	8833 LAMAR BLVD N	R64 / 6	388
AUSTIN DATSUN REPAIR	8825 LAMAR BLVD N	S68 / 6	395
CULP SERV STA	8703 LAMAR BLVD	T75 / 6	404
DIP STICK	8601 LAMAR BLVD N	U77 / 6	405
RELIABLE AUTOM	8226 LAMAR BLVD N	X84 / 6	421
SCHEIDERS SIN	8224 LAMAR BLVD N	X85 / 6	421
D & L MOTORCYCLE INC	7535 LAMAR BLVD N	Z91 / 6	438
K W AUTO REPAIR	7313 LAMAR BLVD N	AA95 / 6	442
NORTHSIDE GARAGE AUT	7277 LAMAR BLVD N	AA97 / 6	444
A 1 TRANSMISSION	7227 LAMAR BLVD N	AB98 / 6	444
AUTOMETRICS INC AUTO	7121 LAMAR BLVD N	AB102 / 6	451
JIMS GULF STATION GA	7107 LAMAR BLVD N	AB105 / 6	455
BLACKBURN TEXACO SER	7006 LAMAR BLVD N	AC143 / 6	650
AUSTIN STANDARD TRAN	6916 LAMAR BLVD N	AD151 / 6	671
AUSTIN KAWASAKI MOTO	6801 LAMAR BLVD N	AE155 / 6	674
K 0 MACHINE CO	6721 LAMAR BLVD N	AF158 / 6	677
GLENN SERV STA	6705 LAMAR BLVD	AF166 / 6	704
RIVER CITY BULTACO M	6614 LAMAR BLVD N	AG172 / 6	712
RAYS GARAGE	6517 LAMAR BLVD N	AH176 / 6	716
WOODS HOND	6509 LAMAR BLVD N	AH179 / 6	732
JIFFV BRAKE SERVICE	6322 LAMAR BLVD N	AI180 / 6	732
EARLS AIR COOLED ENG	6218 LAMAR BLVD N	AJ182 / 9	735
NORTH LAMAR AUTOMOTI	6203 LAMAR BLVD N	AJ188 / 9	770
J&J GARAGE	5312 LAMAR BLVD	AO222 / 8	1007
DODD-HURT TEXACO	4300 GUADALUPE	AT234 / 8	1027
BARTLETTS SERVICE ST	4231 GUADALUPE	AT236 / 8	1028
PERFORMANCE SHOP NOR	4225 GUADALUPE ST	AT237 / 8	1029
HYDE PARK GPVAGE	4215 GUADALUPE ST	AU239 / 8	1029
JAMES HERSHEL R	4203 GUADALUPE ST	AU241 / 8	1031
NUNNELEE H W	4201 GUADALUPE ST	AU251 / 8	1172
AUSTIN SPORTCYCLES M	4117 GUADALUPE ST	AW255 / 8	1178
MIDAS MUFFLER SHOP	4001 GUADALUPE ST	262 / 8	1180
SIGMOR CORPOR	3915 GUADALUPE ST	AY263 / 8	1180
BALCAR HUMBLE SERV	3909 GUADALUPE	AY267 / 8	1234
NUNNELEE HARRY R	3907 GUADALUPE ST	AY270 / 8	1239
UNIVERSITY CAR WASH	3825 GUADALUPE ST	273 / 8	1241
C & H REPAIR SERVICE	3907 AVENUE C	AZ274 / 8	1241
C&H REPR SERV	3907 AVENUE C	AZ276 / 8	1244
HYDE PARK GULF	3801 GUADALUPE ST	BA277 / 8	1244
JAMES E P FILL STA	3710 GUADALUPE ST	BB278 / 8	1245
CIRCLE K CORPORATION	3713 GUADALUPE ST	BB279 / 8	1245
ASHFORDS GARAGE	3016 GUADALUPE ST	BE294 / 8	1270
NORTH AUSTIN GARAGE	3008 GUADALUPE ST	BE299 / 8	1289
MC GIRK J ARTH AUTO	3000 GUADALUPE	BF305 / 8	1295
MALLETT JACK SERVICE	2901 GUADALUPE	BH315 / 8	1302
MONTGOMERYS HUMBLE	2825 GUADALUPE ST	BJ318 / 8	1308
CHEVRON SELF SERVICE	2819 GUADALUPE ST	BJ320 / 11	1308
LICARI SAM GULF	2817 GUADALUPE ST	BK326 / 11	1348
MAGNOLIA PET CO STA	2810 GUADALUPE ST	BK332 / 11	1355
DUNBAR LOUIE FILL ST	2701 GUADALUPE ST	BN336 / 11	1357
LONGHORN GULF SERV	2601 GUADALUPE ST	BO342 / 11	1395
LEES SUPER SERVICE F	2533 GUADALUPE	BS346 / 11	1403
2412 UNIVERSITY SERV	2436 GUADALUPE ST	BU355 / 11	1425

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
SCHIEFFERS BEN	701 24TH W	BW364 / 11	1488
LOONEY L P FILLING	2323 RIO GRANDE	BW366 / 11	1489
CUTLERS MOTOR CO	2015 GUADALUPE ST	CB384 / 11	1608
EXXON SHOP GASOLINE	1901 GUADALUPE ST	CD389 / 11	1639
TENNISON PROPERTIES	19TH & GUADALUPE	CD392 / 11	1644
GULF OIL CORP	1814 GUADALUPE ST	CF397 / 11	1648
WHITING ROBT E	1809 GUADALUPE ST	CF401 / 11	1688
KNIGHT STEWART	1805 GUADALUPE	CF402 / 11	1688
BURCH H H SERV STA	1228 CONGRESS AVE	CP428 / 11	1744
BUTLERS TERRACE	1123 CONGRESS AVE	CQ430 / 11	1748
WEST 9TH STREET PART	704 W 9TH ST	CR436 / 11	1782
CARLSONS DAVE	915 GUADALUPE ST	CU444 / 11	1792
CARLSON DAVE GA	907 GUADALUPE ST	CU445 / 11	1792
COURT HOUSE SERV	905 GUADALUPE	CU446 / 11	1792
MOBIL CORPORATION	919 CONGRESS AVE STE	CV452 / 11	1815
FIX IT SHOP THE	123 7TH W	DF477 / 11	1925
120 22 NORWOOD MOTOR	120 7TH W	DF478 / 11	1925
MOTORAMP STORAGE	118 7TH W	DF479 / 11	1925
ALAMO HOTEL GARAGE	402 6TH W	DE483 / 11	1926
PATSCHKE ALAMO	400 6TH W	DE484 / 11	1927
GRAYBURG OIL CO STA	401 6TH W	DE485 / 11	1927
B & N AXEL SERV	503 GUADALUPE	DI492 / 11	1932
GENERAL MUFFLER CORP	211 E 7TH	DK499 / 11	1952
YOUNG 0 E AUTO REPR	613 TRINITY ST	DM523 / 11	2065
CENTEX AUTO REPAIR	405 E 7TH ST	DM525 / 11	2066
GUSS GARAGE AUTO	609 TRINITY ST	DM527 / 11	2068
JOHNSON HARRY E	605 TRINITY	DM528 / 11	2068
SOUTHERN SERVICE STA	403 GUADALUPE	DO529 / 11	2068
GREGG AUTO REPAIRS	610 RED RIVER	DR547 / 11	2090
CAIN RHONIE AUTO	608 RED RIVER CT	DR548 / 11	2090
MARX J W AUTO REPR	606 RED RIVER CT	DR549 / 11	2090
HERRING WALTER B AUT	606 6TH E	DR550 / 11	2091
HERRINGS GARAGE AUTO	610 6TH ST E	DR551 / 11	2091
HERRINGS GARAGE AUTO	610 6TH ST E	DR552 / 11	2091
BIG SIX GARAGE AUTO	610 6TH E	DR553 / 11	2091
STEARNS JACK AUTO	502 RED RIVER CT	DU559 / 11	2098
BETHKE WALTER AUTO	408 RED RIVER	DU570 / 11	2117
COVERT BUICK BODY SH	402 2ND ST W	DX572 / 11	2117
COVERT BUICK BODY SH	402 2ND ST W	DX573 / 11	2117
SMITH BROS AUTO DLR	301 BRAZOS	DZ575 / 11	2125
MUELLERS GAR AUTO	212 3RD E	DZ578 / 11	2129
MUELLERS GARAGE GR	212 3RD ST E	DZ579 / 11	2129
DEWEYS RADIATOR WORK	106 TRINITY ST	EE594 / 11	2150
GLENN SERVICE STATIO	10 CONGRESS AVE	595 / 11	2151
EDS AUTOMOTIVE	208 RIVERSIDE DR W	EI603 / 14	2182
MIDAS MUFFLER	207 RIVERSIDE DR W	EI604 / 14	2183
R&S GARAGE REPRS	205 RIVERSIDE DR W	EI605 / 14	2183
HAWKINS GARAGE AUTO	205 RIVERSIDE DR W	EI606 / 14	2183
REEDYS AUTO WAY	103 RIVERSIDE DR W	EJ608 / 14	2184
EDDIE SLACKS RIVERSI	400 CONGRESS AVE S	EJ609 / 14	2184
CHRISTIES CITIES	400 CONGRESS AVE S	EJ610 / 14	2184
BOHLS SERVICE STATIO	401 CONGRESS AVE S	EJ614 / 14	2185
TEXAS PACIFIC COAL	401 CONGRESS AVE S	EJ615 / 14	2185
GILBERTS AUTO ELEC	48 EAST AVE	EL624 / 14	2223
CAR WELL INC AUTO RE	205 RIVERSIDE DR E	EM626 / 14	2232
ELLIS & SALAZAR GARA	211 RIVERSIDE DR E	EM627 / 14	2232

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
TRIPLE S PETROLEUM C	900 EAST AVE	EN628 / 14	2233
BOBS GARAGE	1007 CONGRESS AVE S	ES644 / 14	2296
KOCUREKS MAGNOLIA	1007 CONGRESS AVE S	ES645 / 14	2297
CAPITAL SPRING & BRA	1009 CONGRESS AVE S	ES646 / 14	2297
HANCOCK SERVICE STAT	1101 CONGRESS AVE S	ES647 / 14	2297
MC COWN & LINDER	1123 CONGRESS AVE S	ET651 / 14	2298
BUTLERS TERRACE GULF	1123 CONGRESS AVE S	ET652 / 14	2298
SHELL IRVING FILLING	1228 CONGRESS AVE S	EU671 / 14	2329
BURCH H H CONOCO SER	1228 S CONGRESS	EU672 / 14	2329
BURCH H H SERV STA	1228 CONGRESS AVE S	EU673 / 14	2329
K T GARAGE & SER	1300 CONGRESS AVE S	EW675 / 14	2331
CITY WRECKER SERVICE	1300 CONGRESS AVE S	EW676 / 14	2331
BLUE FRONT FILLING S	1301 CONGRESS AVE S	EW677 / 14	2331
CARLSON C A FILLING	1301 CONGRESS AVE S	EW678 / 14	2331
WELLS SAML W AUTO	1606 CONGRESS AVE S	FC697 / 14	2342
BOBS GARAGE	1606 CONGRESS AVE S	FC698 / 14	2342
BOBS GARAGE REPRS	103 MILTON W	FE704 / 14	2346
RUTLANDS PHILLIPS 66	1610 RIVERSIDE DR E	FF708 / 14	2347
DYE A D FILL STA	1801 CONGRESS AVE S	FG709 / 14	2347
DYE SALES & SERVICE	1801 CONGRESS AVE S	FG710 / 14	2348
RUTLAND PHILLIPS 66	1609 E RIVERSIDE	FF713 / 14	2349
SIGMOR SHAMROCK SERV	1620 RIVERSIDE DR	FF715 / 14	2359
TEXAS AUTOMOTIVE SER	2006 CONGRESS AVE S	FH718 / 14	2360
KAVECKI TEXACO SE	1725 RIVERSIDE DR E	FI723 / 14	2361
JIMS RIVERSIDE GULF	1801 RIVERSIDE DR E	FJ733 / 14	2396
SIGMOR SHAMROCK SERV	2105 CONGRESS AVE S	FK739 / 14	2434
TUCKER & RILEY GARAG	2100 CONGRESS AVE S	FK740 / 14	2434
BOHLS SERVICE STATIO	2109 CONGRESS AVE S	FK741 / 14	2434
RILEYS LIVE OAK	2121 CONGRESS AVE S	FM747 / 14	2438
JOHNSON T J FILL STA	2201 CONGRESS AVE S	FM748 / 14	2439
HIGGINS AUTOMOTIVE	2202 CONGRESS AVE S	FN749 / 14	2439
RIVERSIDE TEXACO	2000 RIVERSIDE DR E	FO750 / 14	2439
BOHOT ENCO PRODUCTS	2300 CONGRESS AVE S	FQ758 / 14	2463
MASON BROS SERV	2300 CONGRESS AVE S	FQ759 / 14	2463
JOHNSON HUGO C	2215 CONGRESS AVE S	FQ760 / 14	2464
JOHNSON HUGO SERV	2215 CONGRESS AVE S	FQ761 / 14	2464
TWIN OAKS SERV STA	2315 CONGRESS AVE S	FT768 / 14	2473
TWIN OAKS GULF SERVI	2315 CONGRESS AVE S	FT769 / 14	2474
SOUTH AUSTIN CONOCO	2332 S CONGRESS	FT770 / 14	2474
ES 3S MC ANGUS MILFO	2323 CONGRESS AVE S	FT771 / 14	2474
SOUTH AUSTIN CONOCO	2336 CONGRESS AVE S	FT772 / 14	2474
S AUSTIN CONOCO	2336 CONGRESS AVE S	FT773 / 14	2475
TWIN OAKS SERV	2315 CONGRESS AVE	FT776 / 14	2477
TWIN OAKS MOBIL GAS	2401 CONGRESS AVE S	FU777 / 14	2478
KASSON BILL YAMAHA M	2603 CONGRESS AVE S	FZ798 / 14	2529
T M T INC	2204 WOODLAND DR	GC806 / 14	2594
HENDRICKS TOM AUTO B	2701 CONGRESS AVE S	GD808 / 14	2594
TWIN OAKS SHELL SERV	2704 CONGRESS AVE S	GD809 / 14	2595
WHITTS SERV STA	2704 CONGRESS AVE S	GD810 / 14	2595
SOULE MARK AUTOMOTIV	2716 CONGRESS AVE S	GD811 / 14	2595
STN ENTERPRISES INC	3002 S CONGRESS AVE	GG817 / 14	2599
A ONE RADIATOR SERVI	3405 CONGRESS AVE S	819 / 14	2604
SIGMOR SHAMROCK SERV	3630 CONGRESS AVE S	GM832 / 14	2630
MACHEN LEE SPECIAL A	3634 CONGRESS AVE S	GM833 / 14	2631
DYE BILL AUTOMOTIVE	3716 CONGRESS AVE S	GM834 / 14	2631
YOUNG TROY H GULF SE	3800 CONGRESS AVE S	GN840 / 14	2641

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
A A LOTUS AUTO CENTE	3822 CONGRESS AVE S	GO845 / 14	2653
DIAMOND SHAMROCK REF	6306 E RIVERSIDE DR	GQ852 / 15	2657
YOUNG TROY GULF	3900 CONGRESS AVE S	GR854 / 14	2686
KAYO SERVICE STATION	3903 CONGRESS AVE S	GR855 / 14	2686
REAR JOES GARAGE AUT	4014 CONGRESS AVE S	GS858 / 18	2687
RUDYS CAFE	4105 CONGRESS AVE S	GS862 / 18	2691
SUNDBECK GARAGE	4220 CONGRESS AVE S	GW874 / 17	2707
TENNISON PROPERTIES	4360 S CONGRESS AVE	888 / 17	2756
CAPITAL BUMPER EXCHA	4422 CONGRESS AVE S	HA889 / 17	2756
ELL IS & SALAZAR GAR	4501 CONGRESS AVE S	HD892 / 17	2758
INMAN F M SERV	4703 CONGRESS AVE S	HF901 / 17	2775
MC NEES HUMBLE	4703 CONGRESS AVE	HF903 / 17	2799
PHILLIPS SIXTY SIX G	4703 CONGRESS AVE S	HF904 / 17	2800
KOVAR ROY TEXACO	100 RED BIRD TRAIL	HH908 / 17	2802
RITTERS OF SOUTH	5503 CONGRESS AVE S	HI910 / 17	2803
RITTERS GASOLINE STA	5505 CONGRESS AVE S	HI913 / 17	2810
AUSTIN ENGINE WORKS	7305 CONGRESS AVE S	HM927 / 17	2842
TOSCO MARKETING COMP	8514 S CONGRESS AVE	HP944 / 21	2878

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 96 EDR Hist Cleaner sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
NU-WAY UPHOLSTERY	10721 N LAMAR	J39 / 3	340
SUPER CARE CLEANERS	10206 LAMAR BLVD N	K40 / 3	340
SUPER CARE CLEANERS	10205 N LAMAR	K41 / 3	341
LAUNDRY BASKET NO 1	9644 LAMAR BLVD N	O49 / 6	350
DRY CLEAN CITY 125	9626 N LAMAR BLVD	O50 / 6	350
ACME CLEANERS	9606 LAMAR BLVD N	O55 / 6	361
A ACME CLEANERS & LA	9302 LAMAR BLVD N	Q61 / 6	388
ACME DRY CLEANERS &	7541 LAMAR BLVD N	Z88 / 6	435
VIOLET CROWN CLNRS	6218 LAMAR BLVD	AJ183 / 9	735
FASHION FLOOR INC	5304 LAMAR BLVD N	AO223 / 8	1007
CLEAN & LEAN LAUNDRY	4225 GUADALUPE ST	AT238 / 8	1029
STATE CLEANERS	4115 GUADALUPE	AW256 / 8	1178
PARAMOUNT CLEANERS	4109 GUADALUPE ST	AW257 / 8	1179
MILES EDGAR P BARB	4103 GUADALUPE ST	AW258 / 8	1179
AUSTIN MATTRESS	4101 GUADALUPE	AW259 / 8	1179
WALLIS CLEANERS	4023 GUADALUPE ST	AX260 / 8	1179
HYDE PARK SHOE SHOP	4011 GUADALUPE ST	AX261 / 8	1180
BAKER LEONARD CLNR	3911 GUADALUPE ST	AY264 / 8	1181
AUSTIN MATTRESS & CA	3907 GUADALUPE ST	AY271 / 8	1239
AUSTIN DIAGNOSTIC CL	801 34TH ST W	287 / 8	1261
KWIK WASH COIN LAUND	3105 GUADALUPE ST	BD290 / 8	1262
OCONNELL & WORLEY	3012 GUADALUPE ST	BE298 / 8	1289
DICKEN 6 BROS CLNRS	2930 GUADALUPE	BG309 / 8	1299
DICKENS CLEANERS & S	2918 GUADALUPE ST	BG311 / 8	1300
RICKS CLEANERS INC	2908 GUADALUPE ST	BH312 / 8	1301
COMMUNITY CLNRS	2904 GUADALUPE ST	BH313 / 8	1301
A C LINEN SUPPLY	2822 GUADALUPE	BJ319 / 8	1308
LAUNDERETTE WASHATER	2706 GUADALUPE	BM333 / 11	1355
PARAMOUNT CLNRS	2704 GUADALUPE ST	BM334 / 11	1355

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
FORTY ACRES CLNS	2605 GUADALUPE ST	BO338 / 11	1392
UNIVERSITY CLEANERS	2520 GUADALUPE ST	BS347 / 11	1403
AUSTIN DRY CLEANERS	2516 GUADALUPE ST	BS348 / 11	1403
COWBOYS TAILOR	2505 GUADALUPE ST	BU353 / 11	1425
COUCH CLEANERS	2501 GUADALUPE	BU354 / 11	1425
B LONGHORN CLNS	705 24TH W	BX365 / 11	1488
WASH N FOLD INDRY	2202 RIO GRANDE ST	BZ371 / 11	1535
HODGES CLEANERS	107 21ST E	374 / 11	1555
0 K TAILORING CO	1814 GUADALUPE ST	CF395 / 11	1648
SPOTLESS CASH CLEAN	1703 GUADALUPE ST	CH413 / 11	1696
ABOUT TIME DRY CLEAN	1616 GUADALUPE ST	CJ417 / 11	1717
NO DELAY CLN &	1117 CONGRESS AVE	CQ432 / 11	1764
JOHNSON & LLOYD TAI	1001 CONGRESS ST	CV447 / 11	1792
MODEL LAUNDRY	919 CONGRESS AVE	CV451 / 11	1815
DICKERSON CINS	511 RIO GRANDE	DA468 / 11	1919
A CLEANERS & DYERS	119 7TH W	DF480 / 11	1926
SHIRLEY N A CLNRS	407 6TH W	DE481 / 11	1926
KOCH CLEANING & DYIN	405 6TH W	DE482 / 11	1926
MASTER VALET CLEANER	109 E 7TH ST	DG486 / 11	1927
DRISKILL HOTEL STEAM	113 E 7TH ST	DG487 / 11	1927
DAVIS MAX DCLO CLNR	612 BRAZOS ST	DG489 / 11	1929
DAVIS MAX DCLO CLNR	609 BRAZOS ST	DJ504 / 11	1976
EXCELSIOR LAUNDRY	117 6TH W	DH505 / 11	1976
STAGES PORT E TAILOR	521 CONGRESS AVE	DN524 / 11	2066
MAJESTIC CLEANERS	219 E SIXTH	DP534 / 11	2072
LEVI JOSEPH MERCHAN	315 E 6TH ST	DQ539 / 11	2075
CATHY CLEANER	231 W 3RD ST	DV562 / 11	2107
PARSLEY W L DCLO CLN	310 CONGRESS AVE E	DY571 / 11	2117
CHESNUTT DON N	401 S CONGRESS	EJ611 / 14	2184
TEXAS CLEANERS	401 CONGRESS AVE S	EJ612 / 14	2185
TEXAS CLEANERS	401 CONGRESS AVE S	EJ613 / 14	2185
NO DELAY CLEANERS	1117 CONGRESS AVE S	ET649 / 14	2298
NO DELAY CLEANERS CL	1117 CONGRESS AVE S	ET650 / 14	2298
SOUTH AUSTIN CLEAN	1210 CONGRESS AVE S	EU661 / 14	2310
LEONS CLEANERS INC	1221 S CONGRESS AVE	EU670 / 14	2328
PALACE CLEANERS	1313 CONGRESS AVE S	EW681 / 14	2335
HANSON HARRY A CLNR	1315 CONGRESS AVE S	EY682 / 14	2335
SOUTH AUSTIN BAR	1400 CONGRESS AVE S	EZ685 / 14	2336
MEARS DOC CLNRS	1415 CONGRESS AVE S	EZ686 / 14	2337
CAMPION COLOR	1423 CONGRESS AVE S	EZ687 / 14	2337
TOWN 6 COUNTRY CLEAN	1423 CONGRESS AVE S	EZ688 / 14	2337
A CLEANERS SUB STA	1507 CONGRESS AVE S	FB691 / 14	2341
GRIFFITH W G INDRY	1512 CONGRESS AVE S	FB692 / 14	2341
SOUTH MAIN CLEANERS	1518 CONGRESS AVE S	FB693 / 14	2341
SOUTH AUSTIN LAUN	1518 CONGRESS AVE S	FB694 / 14	2341
DOHERTY L W CLDO	1602 CONGRESS AVE S	FC695 / 14	2342
DOHERTY L W DCLO CLN	1602 CONGRESS AVE S	FC696 / 14	2342
SOUTH AUSTIN CLNRS	1608 CONGRESS AVE S	FC699 / 14	2342
SOUTH AUSTIN CLEANER	1608 CONGRESS AVE S	FC700 / 14	2343
HUGHES LAUNDERETTE	2006 CONGRESS AVE S	FH719 / 14	2360
ACME CLEANERS	1800 RIVERSIDE DR E	FI720 / 14	2360
KWIK WASH COIN LAUND	1723 RIVERSIDE DR E	FI721 / 14	2361
KWIK WASH COIN LAUND	1723 RIVERSIDE DR	FI722 / 14	2361
QUALITY WHOL LNDRY	2006 CONGRESS AVE	FH731 / 14	2396
TOWN LAKE PLAZA ASTR	1900 RIVERSIDE DR E	FJ732 / 14	2396
MAJESTIC CLEANERS	2114 CONGRESS AVE S	742 / 14	2434

EXECUTIVE SUMMARY

Site	Address	Map ID / Focus Map(s)	Page
KWIK WASH COIN LAUND	2209 CONGRESS AVE S	FN754 / 14	2443
BROWN JACK CLEANERS	2215 CONGRESS AVE S	FQ762 / 14	2464
ONE HOUR MARTINIZING	2326 CONGRESS AVE S	FT767 / 14	2473
DRY CLEAN USA	2410 E RIVERSIDE	GA794 / 14	2521
OXFORD FINE CLEANERS	4410 E RIVERSIDE DR	GF814 / 15	2597
KWIK WASH COIN LAUND	3004 CONGRESS AVE S	GG815 / 14	2597
FAIRWAY COIN LAUNDRY	1612 MONTOPOLIS DR	831 / 15	2630
SOCO CLEANER & ALTER	3801 S CONGRESS AVE	GN839 / 14	2641
KWIK WASH COIN LAUND	6500 CONGRESS AVE S	920 / 17	2838
ACME CLEANERS	6630 CONGRESS AVE S	HL921 / 17	2838
BROWN JACK CLEANERS	6650 S CONGRESS AVE	HL923 / 17	2839

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

TX RGA LF: Recovered Government Archive Solid Waste Facilities List

A review of the TX RGA LF list, as provided by EDR, has revealed that there are 3 TX RGA LF sites within the requested target property.

Site	Address	Map ID / Focus Map(s)	Page
GABLES RESIDENTIAL T	4110 GUADALUPE ST	AV247 / 8	1069
DONALDSON SAND GRAVE	.75 MILE NE OF FM 43	EV659 / 14	2309
Not reported	6MI E INTRSC FM973/S	EV660 / 14	2310

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Page Numbers and Map Identifcations refer to the EDR Area/Corridor Report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 06/22/2023 has revealed that there are 4 SEMS-ARCHIVE sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
LINCOLN PROPERTIES	FIRST AND CONGRESS	NNE 0 - 1/8 (0.056 mi.)	MN2194 / 11	6842

Site ID: 0603312 EPA Id: TXD981155971				
MABEL DAVIS PARK - C Site ID: 0602524 EPA Id: TXD980623219	INT. OF WOODWARD & B	SSW 1/8 - 1/4 (0.141 mi.)	2910 / 15	8909
AUSTIN GAS LIGHT COM Site ID: 0603536 EPA Id: TXD981918162	300 MEDINA STREET	ESE 1/8 - 1/4 (0.202 mi.)	SJ3040 / 11	9641
CAPITOL METAL FINISH Site ID: 0604124 EPA Id: TXD048452064	***3909 WAREHOUSE ROW***	***ESE 1/4 - 1/2 (0.395 mi.)***	***3226 / 18***	***11189***

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

A review of the CORRACTS list, as provided by EDR, and dated 07/24/2023 has revealed that there is 1 CORRACTS site within approximately1 mile of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CAPITOL METAL FINISH EPA ID:: TXD048452064	***3909 WAREHOUSE ROW***	***ESE 1/4 - 1/2 (0.395 mi.)***	***3226 / 18***	***11189***

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

A review of the RCRA-LQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ELECTRONINKS EPA ID:: TXR000085707	7901 E RIVERSIDE DR	SSW 0 - 1/8 (0.015 mi.)	HE1203 / 19	3839
THE UNIVERSITY OF TE EPA ID:: TXD980869184	***2617 SPEEDWAY STE 10***	***E 0 - 1/8 (0.027 mi.)***	***IV1636 / 11***	***5363***

RCRA-SQG: RCRA - Small Quantity Generators

A review of the RCRA-SQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 16 RCRA-SQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
HOME DEPOT USA HD655 EPA ID:: TXR000060608	13309 N IH 35	N 0 - 1/8 (0.012 mi.)	HX1001 / 2	3092
LAIDLAW TRANSIT EPA ID:: TXD988061685	***4300 S CONGRESS***	***WNW 0 - 1/8 (0.015 mi.)***	***GY1185 / 17***	***3817***
HEARTLAND AUTOMOTIVE	***3809 GUADALUPE***	***ESE 0 - 1/8 (0.016 mi.)***	***BA1252 / 8***	***3937***

EPA ID:: TXD988018420				
JACK BROWN CLEANERS EPA ID:: TXD981590664	615 W MARTIN LUTHER	E 0 - 1/8 (0.041 mi.)	LF1896 / 11	6312
LONGHORN CLNRS EPA ID:: TXD988081204	***510 W MARTIN LUTHUR***	***E 0 - 1/8 (0.068 mi.)***	***LF2412 / 11***	***7230***
AUTOMOTIVE REFINISH EPA ID:: TXR000040196	***6615 SHIRLEY AVENUE***	***ESE 0 - 1/8 (0.073 mi.)***	***OL2471 / 6***	***7315***
HEART HOSPITAL OF AU EPA ID:: TXR000081316	3801 N LAMAR BLVD	WNW 0 - 1/8 (0.086 mi.)	PH2636 / 8	7961
PENTAGON TECHNOLOGIE EPA ID:: TXR000031542	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2710 / 19***	***8135***
TRANSPORTATION SECUR EPA ID:: TXR000058446	3600 3600 PRESIDENTI	S 0 - 1/8 (0.109 mi.)	QL2814 / 20	8568
VERITIV CORPORATION EPA ID:: TXR000085481	210 E ST ELMO RD	ESE 1/8 - 1/4 (0.142 mi.)	RE2911 / 18	8910
VERITIV OPERATING EPA ID:: TXR000085559	210 210 E SAINT ELMO	ESE 1/8 - 1/4 (0.142 mi.)	RE2913 / 18	8917
TARGET STORE T3342 EPA ID:: TXR000085241	901 E 5TH ST STE 140	E 1/8 - 1/4 (0.159 mi.)	RJ2932 / 11	9003
DELSTAR TECHNOLOGIES EPA ID:: TXR000003426	***220 E SAINT ELMO RD***	***ESE 1/8 - 1/4 (0.205 mi.)***	***SL3046 / 18***	***9666***
ASCENSION SETON MEDI EPA ID:: TXD078495868	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***
PPD DEVELOPMENT EPA ID:: TXR000081554	***7551 7551 METRO CENT***	***SSW 1/8 - 1/4 (0.239 mi.)***	***TD3122 / 19***	***10278***
TEXAS DEPARTMENT OF EPA ID:: TXD980627228	***1100 W 49TH ST***	***WNW 1/8 - 1/4 (0.249 mi.)***	***TJ3158 / 8***	***10510***

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

A review of the RCRA-VSQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 23 RCRA-VSQG sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
FAMILY DOLLAR #6170 EPA ID:: TXR000082963	***9717 N. LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***N986 / 6***	***3009***
SAMS CLUB PLUS NO 62 EPA ID:: TXR000020867	***10601 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***1020 / 3***	***3223***
QUALITY ENGINE EXCHA EPA ID:: TXD160827978	***8807 B N LAMAR BLVD***	***SE 0 - 1/8 (0.014 mi.)***	***S1137 / 6***	***3642***
FURROW BUILDING MATE EPA ID:: TXD988078598	***4210 S CONGRESS***	***WNW 0 - 1/8 (0.015 mi.)***	***GW1213 / 17***	***3862***
FAMILY DOLLAR #1700 EPA ID:: TXR000082290	1917 E. RIVERSIDE DR	WSW 0 - 1/8 (0.018 mi.)	FL1311 / 14	4172
AUSTIN GATEWAY	***9401 CARGO AVENUE BA***	***SSW 0 - 1/8 (0.021 mi.)***	***IM1391 / 20***	***4377***

EPA ID:: TXR000034207				
ROUND2, INC. EPA ID:: TXR000080327	1340 AIRPORT COMMERC	S 0 - 1/8 (0.021 mi.)	JD1406 / 15	4445
TEXACO STATION EPA ID:: TX0000994889	***3120 GUADALUPE ST***	***WNW 0 - 1/8 (0.023 mi.)***	***JK1475 / 8***	***4691***
FAMILY DOLLAR #3834 EPA ID:: TXR000082522	118 E. OLTORF ST	SE 0 - 1/8 (0.038 mi.)	FU1845 / 14	6098
K AND S INTERCONNECT EPA ID:: TXR000002022	3709-B PROMONTORY PO	WNW 0 - 1/8 (0.062 mi.)	2300 / 8	6977
SEAHOLM POWER PLANT EPA ID:: TXD981049745	***800 W CESAR CHAVEZ S***	***W 0 - 1/8 (0.086 mi.)***	***PG2634 / 11***	***7930***
GENERAL MOTORS - AUS EPA ID:: TXR000083824	7401 E. BEN WHITE BL	SW 0 - 1/8 (0.087 mi.)	PI2644 / 19	7984
CVS PHARMACY 6945 EPA ID:: TXR000081004	***4405 E RIVERSIDE DR***	***SW 0 - 1/8 (0.090 mi.)***	***PM2679 / 15***	***8053***
FURROW BUILDING MATE EPA ID:: TXD988078606	***8319 N LAMAR***	***SE 0 - 1/8 (0.092 mi.)***	***2705 / 6***	***8114***
FOUR SEASONS HOTEL EPA ID:: TXD988033759	***98 SAN JACINTO BLVD***	***WNW 0 - 1/8 (0.095 mi.)***	***ND2731 / 11***	***8233***
COMMEMORATIVE BRANDS EPA ID:: TXD026028357	***7211 CIRCLE S RD***	***ESE 0 - 1/8 (0.104 mi.)***	***QB2781 / 17***	***8422***
GENERAL SERVICES COM EPA ID:: TXD988059598	***1518 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.109 mi.)***	***QK2809 / 11***	***8535***
US POSTAL SERVICE AU EPA ID:: TX8180000301	***300 E 9TH ST***	***ESE 1/8 - 1/4 (0.129 mi.)***	***RB2893 / 11***	***8842***
PENSKE TRUCK LEASING EPA ID:: TXR000079188	8800 S CONGRESS AVE	SW 1/8 - 1/4 (0.132 mi.)	RD2902 / 21	8894
AMERICAN CLEANERS EPA ID:: TXR000074021	907 W 12TH STREET	WNW 1/8 - 1/4 (0.143 mi.)	RH2916 / 11	8922
NATIONAL TIRE & BATT EPA ID:: TXR000063271	8002 RESEARCH BLVD	NW 1/8 - 1/4 (0.202 mi.)	3039 / 6	9638
WAL-MART SUPERCENTER EPA ID:: TXR000072363	12900 12900 N INTERS	E 1/8 - 1/4 (0.203 mi.)	SK3041 / 2	9642
TOKYO ELECTRON TEXAS EPA ID:: TXR000027524	***2500 MONTOPOLIS DRIV***	***SSW 1/8 - 1/4 (0.218 mi.)***	***ST3078 / 19***	***10063***

Lists of state and tribal landfills and solid waste disposal facilities

TX SWF/LF: Permitted Solid Waste Facilities

A review of the TX SWF/LF list, as provided by EDR, and dated 04/19/2023 has revealed that there are 8 TX SWF/LF sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ROUND2 INC. Facility Status: ACTIVE	***1340 AIRPORT COMMERC***	***S 0 - 1/8 (0.021 mi.)***	***JD1405 / 15***	***4441***

Permit Number: 100312				
SERVICE CENTER 2	***600 RIVER ST***	***WNW 0 - 1/8 (0.068 mi.)***	***OC2406 / 11***	***7215***
Facility Status: NOT CONSTRUCTED Permit Number: 67078 Permit Number: 67101				
5901 S CONGRESS	6001 S CONGRESS AVE	ESE 0 - 1/8 (0.077 mi.)	OS2518 / 17	7453
Facility Status: NOT CONSTRUCTED Permit Number: 67009				
HARMON PROPERTIES LA	1111 OLD BASTROP HWY	E 1/8 - 1/4 (0.167 mi.)	RO2953 / 16	9201
Facility Status: CLOSED Estimated Closure Date: 1/1/1988 Permit Number: 1569				
SB WINGFIELD LANDFIL	1111 OLD BASTROP HWY	E 1/8 - 1/4 (0.167 mi.)	RO2954 / 16	9202
Facility Status: CLOSED Estimated Closure Date: 5/1/1982 Permit Number: 1390				
ASCENSION SETON MEDI	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***
Facility Status: NOT CONSTRUCTED Estimated Closure Date: 1/1/1901 Permit Number: 2128				
AUSTIN LIQUID DISPOS	***751 BASTROP HWY***	***NNE 1/4 - 1/2 (0.273 mi.)***	***3168 / 15***	***10747***
Facility Status: CLOSED Permit Number: 1324				
DOUGHERTY ARTS CENTE	***1110 BARTON SPRINGS***	***WNW 1/4 - 1/2 (0.349 mi.)***	***3204 / 11***	***10957***
Facility Status: ACTIVE Permit Number: 65032				

TX CLI: Closed Landfill Inventory

A review of the TX CLI list, as provided by EDR, has revealed that there are 17 TX CLI sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CONGRESS AVE	1200 BLK CONGRESS AV	WNW 0 - 1/8 (0.013 mi.)	ET1074 / 14	3380
Database: CLI, Date of Government Version: 08/30/1999 Date Closed: 1930				
CONGRESS AVE	1200 BLK CONGRESS AV	WNW 0 - 1/8 (0.013 mi.)	ET1075 / 14	3381
Database: CAPCOG LI, Date of Government Version: 11/11/2022				
PARKER LN AND RIVERS	PARKER LN AND RIVERS	WSW 0 - 1/8 (0.036 mi.)	KN1820 / 14	6078
Database: CAPCOG LI, Date of Government Version: 11/11/2022				
PARKER LN & RIVERSID		WSW 0 - 1/8 (0.036 mi.)	KN1821 / 14	6079
Database: CLI, Date of Government Version: 08/30/1999 Date Closed: 1935				
PARKING LOT & BUILDI	206 CONGRESS AVE	SSW 0 - 1/8 (0.044 mi.)	KH1930 / 11	6416
Database: CAPCOG LI, Date of Government Version: 11/11/2022				
PARKING LOT & BUILDI	206 CONGRESS AVE	SSW 0 - 1/8 (0.044 mi.)	KH1932 / 11	6419
Database: CLI, Date of Government Version: 08/30/1999 Date Closed: **********				
BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	ESE 0 - 1/8 (0.087 mi.)	OS2647 / 17	7988
Database: CLI, Date of Government Version: 08/30/1999				

Date Closed: **********				
BRADSHERE-FLOURNOY Database: CAPCOG LI, Date of Government Version: 11/11/2022	EAST OF 6000 BLOCK O	ESE 0 - 1/8 (0.087 mi.)	OS2649 / 17	7990
TEXACO CHEMICALS Database: CLI, Date of Government Version: 08/30/1999 Date Closed: 1969	7114 N. LAMAR BLVD	WNW 1/8 - 1/4 (0.178 mi.)	RU2978 / 6	9324
TEXACO CHEMICALS Database: CAPCOG LI, Date of Government Version: 11/11/2022	7114 N. LAMAR BLVD	WNW 1/8 - 1/4 (0.178 mi.)	RU2979 / 6	9326
WHISENHUT Database: CAPCOG LI, Date of Government Version: 11/11/2022	NE INTERSECTION OF D	NNE 1/8 - 1/4 (0.216 mi.)	SQ3069 / 16	10023
WHISENHUT Database: CLI, Date of Government Version: 08/30/1999 Date Closed: **********		NNE 1/8 - 1/4 (0.216 mi.)	SQ3070 / 16	10024
Not reported Database: CAPCOG LI, Date of Government Version: 11/11/2022 Database: CLI, Date of Government Version: 08/30/1999 Facility Id: 1390 Last Date in Records Site Accepted Waste: 19840601 Permit Status: K	1111 OLD BASTROP HIG	NNE 1/4 - 1/2 (0.306 mi.)	3185 / 16	10871
BERGSTROM 2 Database: CLI, Date of Government Version: 08/30/1999 Date Closed: 1952	SITE AT N END OF BAS	SE 1/4 - 1/2 (0.431 mi.)	TX3242 / 20	11297
BERGSTROM 2 Database: CAPCOG LI, Date of Government Version: 11/11/2022	NORTH END OF FORMER	SE 1/4 - 1/2 (0.431 mi.)	TX3243 / 20	11298
BERGSTROM 1 Database: CAPCOG LI, Date of Government Version: 11/11/2022	NORTH END OF FORMER	SW 1/4 - 1/2 (0.465 mi.)	UF3275 / 20	11574
BERGSTROM 1 Database: CLI, Date of Government Version: 08/30/1999 Date Closed: 1946	SITE ON N END OF BAS	SW 1/4 - 1/2 (0.465 mi.)	UF3276 / 20	11575

Lists of state and tribal leaking storage tanks

TX LPST: Leaking Petroleum Storage Tank Listing

A review of the TX LPST list, as provided by EDR, and dated 03/28/2023 has revealed that there are 194 TX LPST sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
TEXAN MKT 5 LPST Id: 091135 CA Status: 6A - FINAL CONCURRENCE ISSUED Facility ID: 0019603 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	***2700 S CONGRESS AVE***	***WNW 0 - 1/8 (0.011 mi.)***	***GD947 / 14***	***2880***
IVORY CLEANERS & ALT LPST Id: 119160 CA Status: 6P - FINAL PENDING WELL PLUG Facility ID: 0007172 Status Code: PREASSESSMENT/RELEASE DETERMINATION	***1901 RIO GRANDE ST***	***E 0 - 1/8 (0.011 mi.)***	***HQ951 / 11***	***2900***
DODD AUTOMOTIVE	***4227 GUADALUPE ST***	***NNE 0 - 1/8 (0.012 mi.)***	***AT968 / 8***	***2947***

LPST Id: 104780
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0001832
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TETCO 1144 ***8911 N LAMAR BLVD*** ***ESE 0 - 1/8 (0.012 mi.)*** ***R972 / 6*** ***2988***
LPST Id: 118246
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014336
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ZIPPY FOOD STORE 6600 N LAMAR BLVD WNW 0 - 1/8 (0.012 mi.) AG984 / 6 3008
LPST Id: 091169
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FAMOUS FOOD MART ***6301 N LAMAR BLVD*** ***ESE 0 - 1/8 (0.012 mi.)*** ***AI992 / 6*** ***3045***
LPST Id: 112387
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019074
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TACO BELL ***2801 GUADALUPE ST*** ***ENE 0 - 1/8 (0.012 mi.)*** ***HY1006 / 11*** ***3181***
LPST Id: 093370
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0048720
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO ***2000 E RIVERSIDE DR*** ***NE 0 - 1/8 (0.012 mi.)*** ***FO1017 / 14*** ***3197***
LPST Id: 101251
CA Status: 6P - FINAL PENDING WELL PLUG
Facility ID: 0023200
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOP N CARRY FOODS ***8422 S CONGRESS AVE*** ***WNW 0 - 1/8 (0.013 mi.)*** ***HO1043 / 21*** ***3280***
LPST Id: 120751
CA Status: 2 - SITE ASSESSMENT

GASKINS REAL ESTATE ***2718 GUADALUPE ST*** ***WSW 0 - 1/8 (0.013 mi.)*** ***BM1055 / 11*** ***3315***
LPST Id: 094905
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0050186
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JOE DAYWOOD 3512 GUADALUPE ST WNW 0 - 1/8 (0.013 mi.) IC1063 / 8 3369
LPST Id: 102227
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0061457
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

RYDER TRUCK RENTAL 0 ***8305 N LAMAR BLVD*** ***SE 0 - 1/8 (0.013 mi.)*** ***W1077 / 6*** ***3383***
LPST Id: 094088
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0002651
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PACIFIC SOUTHWEST BA ***907 S CONGRESS AVE*** ***ESE 0 - 1/8 (0.013 mi.)*** ***EQ1087 / 14*** ***3458***
LPST Id: 102685
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0062968
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PHILLIPS 66 SS 26286 ***11100 N LAMAR BLVD*** ***WNW 0 - 1/8 (0.013 mi.)*** ***I1100 / 3*** ***3489***

LPST Id: 099432
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010901
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

LAMAR CORNER STORE ***7545 N LAMAR BLVD*** ***ESE 0 - 1/8 (0.013 mi.)*** ***Z1116 / 6*** ***3538***
LPST Id: 091422
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0011311
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

VACANT PROPERTY ***11902 N LAMAR BLVD*** ***WNW 0 - 1/8 (0.014 mi.)*** ***1121 / 4*** ***3574***
LPST Id: 104576
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063416
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JACK BROWN CLEANERS ***2215 S CONGRESS AVE*** ***E 0 - 1/8 (0.014 mi.)*** ***FQ1129 / 14*** ***3597***
LPST Id: 104533
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023302
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ENVIRONMENTAL IMPACT 3800 S CONGRESS AVE WNW 0 - 1/8 (0.014 mi.) GO1160 / 14 3751
LPST Id: 114811
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7 ELEVEN STORE 36653 ***5630 N LAMAR BLVD*** ***WNW 0 - 1/8 (0.014 mi.)*** ***AL1166 / 8*** ***3769***
LPST Id: 091290
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0015562
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7 ELEVEN STORE 36653 ***5630 N LAMAR BLVD*** ***WNW 0 - 1/8 (0.014 mi.)*** ***AL1170 / 8*** ***3799***
LPST Id: 120052
CA Status: 6A - FINAL CONCURRENCE ISSUED

LAIDLAW TRANSIT ***4300 S CONGRESS*** ***WNW 0 - 1/8 (0.015 mi.)*** ***GY1185 / 17*** ***3817***
LPST Id: 095787
LPST Id: 098480
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010025
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

BOOTHE PROPERTY VACA 508 E 6TH ST SW 0 - 1/8 (0.015 mi.) DR1215 / 11 3865
LPST Id: 107192
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0064808
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN CAT & DOG HOS ***506 E 5TH ST*** ***SW 0 - 1/8 (0.016 mi.)*** ***DU1235 / 11*** ***3916***
LPST Id: 102270
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0062072
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CASH AMERICAN PAWN S 3402 GUADALUPE WNW 0 - 1/8 (0.016 mi.) IB1241 / 8 3933
LPST Id: 104444
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 16996 ***2600 GUADALUPE ST*** ***W 0 - 1/8 (0.016 mi.)*** ***BO1259 / 11*** ***3963***

LPST Id: 102858
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007175
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIAMOND SHAMROCK 236	***1620 E RIVERSIDE DR***	***NE 0 - 1/8 (0.017 mi.)***	***FF1266 / 14***	***4032***

LPST Id: 116305
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045204
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

THURMAN WAREHOUSE	***4714 S CONGRESS AVE***	***WNW 0 - 1/8 (0.018 mi.)***	***IU1299 / 17***	***4154***

LPST Id: 099861
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0011319
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

STONES TEXACO	***2300 S CONGRESS AVE***	***W 0 - 1/8 (0.018 mi.)***	***FQ1302 / 14***	***4161***

LPST Id: 110045
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0022264
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EXXON SS6 0015	***343 S CONGRESS AVE***	***NE 0 - 1/8 (0.019 mi.)***	***EJ1337 / 14***	***4210***

LPST Id: 091595
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0026003
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FLOYDS AUTO SALES &	***5253 N LAMAR BLVD***	***ESE 0 - 1/8 (0.019 mi.)***	***AO1341 / 8***	***4241***

LPST Id: 100889
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0015637
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DOCS BACK YARD	***1123 SOUTH CONGRESS***	***ESE 0 - 1/8 (0.020 mi.)***	***ET1350 / 14***	***4264***

LPST Id: 120860
CA Status: 6A - FINAL CONCURRENCE ISSUED

MOBIL SS 12 D93	***2401 S CONGRESS AVE***	***SE 0 - 1/8 (0.020 mi.)***	***FU1374 / 14***	***4341***

LPST Id: 096497
LPST Id: 091811
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0017726
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FINLEY	***509 E 5TH ST***	***SW 0 - 1/8 (0.022 mi.)***	***DU1411 / 11***	***4448***

LPST Id: 096081
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0053521
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 24008	***5101 N LAMAR BLVD***	***ESE 0 - 1/8 (0.022 mi.)***	***AQ1417 / 8***	***4457***

LPST Id: 120589
CA Status: 6A - FINAL CONCURRENCE ISSUED

EVANS TEXACO	***4712 S CONGRESS AVE***	***WNW 0 - 1/8 (0.022 mi.)***	***IU1433 / 17***	***4556***

LPST Id: 095403
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018769
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JAMES DREW RENTAL	406 EAST AVE	ESE 0 - 1/8 (0.023 mi.)	1438 / 14	4574

LPST Id: 118788
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014512
Status Code: PREASSESSMENT/RELEASE DETERMINATION

MS EXPRESS 901	***2105 S CONGRESS AVE***	***ESE 0 - 1/8 (0.023 mi.)***	***FK1459 / 14***	***4637***

LPST Id: 115195
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045192
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 12683	***808 W KOENIG LN***	***WNW 0 - 1/8 (0.023 mi.)***	***AL1490 / 8***	***4724***

LPST Id: 099954
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007170
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PATS LAWNMOWER SERVI	***7205 N LAMAR BLVD***	***ESE 0 - 1/8 (0.024 mi.)***	***AB1499 / 6***	***4775***

LPST Id: 107259
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0035789
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SOCO CENTER	***3630 S CONGRESS AVE***	***WNW 0 - 1/8 (0.025 mi.)***	***GM1513 / 14***	***4826***

LPST Id: 109867
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045201
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO	***1900 GUADALUPE ST***	***W 0 - 1/8 (0.025 mi.)***	***CD1530 / 11***	***4909***

LPST Id: 097075
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023190
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

COTHRONS TEXACO SERV	***701 W 6TH ST***	***WNW 0 - 1/8 (0.025 mi.)***	***DA1546 / 11***	***4963***

LPST Id: 098124
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025280
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CEN-TEX NISSAN INC	***1400 S CONGRESS***	***WNW 0 - 1/8 (0.025 mi.)***	***EZ1549 / 14***	***4979***

LPST Id: 108915
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0040885
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

GIANT FOOD MART	***8700 N LAMAR BLVD***	***NW 0 - 1/8 (0.025 mi.)***	***T1553 / 6***	***4993***

LPST Id: 091369
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0013885
Status Code: FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING

DIAMOND SHAMROCK 963	***3706 GUADALUPE ST***	***WNW 0 - 1/8 (0.026 mi.)***	***BB1564 / 8***	***5045***

LPST Id: 115608
LPST Id: 091646
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045250
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EXPRESS FOOD MART	***10500 N LAMAR BLVD***	***WNW 0 - 1/8 (0.026 mi.)***	***JR1566 / 3***	***5064***

LPST Id: 104147
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034932
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7 ELEVEN STORE 30467 ***10111 N LAMAR BLVD*** ***ESE 0 - 1/8 (0.026 mi.)*** ***JS1572 / 3*** ***5096***
LPST Id: 117647
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045165
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

HEB 628 ***2512 E RIVERSIDE DR*** ***NE 0 - 1/8 (0.026 mi.)*** ***HS1578 / 15*** ***5128***
LPST Id: 114520
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0055951
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 25445 ***8900 N LAMAR BLVD*** ***WNW 0 - 1/8 (0.026 mi.)*** ***R1593 / 6*** ***5198***
LPST Id: 097544
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007161
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

STOP N SAVE 3 ***1800 BURTON DR*** ***ENE 0 - 1/8 (0.026 mi.)*** ***1595 / 14*** ***5226***
LPST Id: 091818
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039565
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

LITTLEFIELD DRISKILL ***106 E 6TH ST*** ***NNE 0 - 1/8 (0.027 mi.)*** ***DN1602 / 11*** ***5251***
LPST Id: 117973
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN COMMUNITY COL ***1212 RIO GRANDE ST*** ***WNW 0 - 1/8 (0.027 mi.)*** ***CO1632 / 11*** ***5285***
LPST Id: 113790
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

RIVERSIDE CHEVRON ***400 S CONGRESS AVE*** ***WNW 0 - 1/8 (0.027 mi.)*** ***EJ1640 / 14*** ***5443***
LPST Id: 121027
LPST Id: 107107
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0033141
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN TOYOTA ***1127 W 6TH STREET*** ***WNW 0 - 1/8 (0.028 mi.)*** ***DC1657 / 11*** ***5481***
LPST Id: 099907
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0044471
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ELECTRIC UTILITY ***300 WEST AVE*** ***WNW 0 - 1/8 (0.028 mi.)*** ***DL1667 / 11*** ***5508***
LPST Id: 096554
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018149
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CENTRAL TEXAS EQUIPM ***127 E RIVERSIDE DR*** ***SW 0 - 1/8 (0.029 mi.)*** ***EM1694 / 14*** ***5591***
LPST Id: 093963
CA Status: 6A - FINAL CONCURRENCE ISSUED

Facility ID: 0014486
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER 7 ELEVEN STOR	***6702 S CONGRESS AVE***	***WNW 0 - 1/8 (0.030 mi.)***	***JZ1707 / 17***	***5646***

LPST Id: 117722
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007124
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

BEVERAGE BARN	***2001 E RIVERSIDE DR***	***SW 0 - 1/8 (0.031 mi.)***	***KA1721 / 14***	***5676***

LPST Id: 104786
LPST Id: 093488
LPST Id: 121203
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019617
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXAS SCHOOL FOR THE	***1102 S CONGRESS AVE***	***ESE 0 - 1/8 (0.032 mi.)***	***KF1748 / 14***	***5801***

LPST Id: 108546
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0048216
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ALL STAR GROCERY 1	***4619 S CONGRESS AVE***	***ESE 0 - 1/8 (0.034 mi.)***	***KK1783 / 17***	***5940***

LPST Id: 109419
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010998
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

NORTH LAMAR QUICK ST	***8545 N LAMAR BLVD***	***SE 0 - 1/8 (0.034 mi.)***	***KM1787 / 6***	***5970***

LPST Id: 120073
CA Status: 6A - FINAL CONCURRENCE ISSUED

GPM STORE 4567	***2001 BASTROP HWY E***	***NNE 0 - 1/8 (0.034 mi.)***	***1792 / 20***	***5996***

LPST Id: 121207
CA Status: 2 - SITE ASSESSMENT

VACANT BUILDING	701 E 6TH ST	ENE 0 - 1/8 (0.036 mi.)	KQ1828 / 11	6084

LPST Id: 099450
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FURNITURE REJUVENATO	***605 W 37TH ST***	***WNW 0 - 1/8 (0.037 mi.)***	***IC1836 / 8***	***6087***

LPST Id: 119240
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0086176
Status Code: PREASSESSMENT/RELEASE DETERMINATION

ACC BOOK STORE	***801 W 12TH ST***	***WNW 0 - 1/8 (0.038 mi.)***	***JA1852 / 11***	***6146***

LPST Id: 104949
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0060134
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PERRY BROOKS BLDG	***720 BRAZOS ST***	***ESE 0 - 1/8 (0.038 mi.)***	***KW1862 / 11***	***6166***

LPST Id: 101630
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0062765
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FIRST NATIONAL BANK	***12800 N LAMAR BLVD***	***W 0 - 1/8 (0.039 mi.)***	***1868 / 2***	***6211***

LPST Id: 098946

CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0058316
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER RTC PROPERTY 206 CONGRESS AVE SSW 0 - 1/8 (0.039 mi.) KH1874 / 11 6233
LPST Id: 103123
CA Status: 6P - FINAL PENDING WELL PLUG
Facility ID: 0063160
Status Code: FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING

SUPERIOR DAIRIES 600 E 1ST ST WNW 0 - 1/8 (0.039 mi.) LB1878 / 11 6240
LPST Id: 093871
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0031210
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIAMOND SHAMROCK 207 628 E OLTORF ST SE 0 - 1/8 (0.040 mi.) LD1884 / 14 6255
LPST Id: 116084
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039561
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN STORE 38608 105 E STASSNEY LN ESE 0 - 1/8 (0.042 mi.) LL1916 / 17 6375
LPST Id: 120685
CA Status: 6A - FINAL CONCURRENCE ISSUED

RREEF HEMPHILL PARK 2810 HEMPHILL PARK ENE 0 - 1/8 (0.044 mi.) HY1928 / 11 6415
LPST Id: 117561
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WESTERN AUTO 9316 N LAMAR BLVD WNW 0 - 1/8 (0.046 mi.) 1966 / 6 6456
LPST Id: 097847
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0053408
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

STOP N GO MARKET 210 111 W WILLIAM CANNON WNW 0 - 1/8 (0.048 mi.) LZ2006 / 17 6503
LPST Id: 105550
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0044924
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIAMOND SHAMROCK 212 1516 TINNIN FORD RD NE 0 - 1/8 (0.050 mi.) MF2030 / 14 6559
LPST Id: 117256
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039564
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PROPOSED CVS PHARMAC 5526 S CONGRESS AVE WNW 0 - 1/8 (0.050 mi.) MH2043 / 17 6615
LPST Id: 116040
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045817
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN GREENWOOD CON 909 COLORADO ST WNW 0 - 1/8 (0.052 mi.) KL2073 / 11 6631
LPST Id: 105043
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019352
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JIMS CONOCO 1308 LAVACA ST ESE 0 - 1/8 (0.053 mi.) MR2113 / 11 6733

LPST Id: 097790
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0046616
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

MCMORRIS FORD ***808 W 6TH ST*** ***WNW 0 - 1/8 (0.053 mi.)*** ***LX2128 / 11*** ***6755***
LPST Id: 109726
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0068769
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

COMMERICAL TITLE BUI 910 LAVACA ST ESE 0 - 1/8 (0.054 mi.) IY2165 / 11 6776
LPST Id: 095340
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 12705 ***408 W 15TH ST*** ***WNW 0 - 1/8 (0.055 mi.)*** ***MV2173 / 11*** ***6781***
LPST Id: 118292
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007176
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

NEELLEY VENDING ***813 W NORTH LOOP BLV*** ***WNW 0 - 1/8 (0.055 mi.)*** ***LM2190 / 8*** ***6832***
LPST Id: 092244
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WESTERN AUTO ***137 W OLTORF ST*** ***SE 0 - 1/8 (0.057 mi.)*** ***2212 / 14*** ***6851***
LPST Id: 097478
LPST Id: 111290
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0056892
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

NCNB TEXAS 201 E 5TH ST SSW 0 - 1/8 (0.057 mi.) JP2233 / 11 6863
LPST Id: 099343
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIAMOND SHAMROCK 964 ***806 W RUNDBERG LN*** ***WNW 0 - 1/8 (0.058 mi.)*** ***NF2245 / 6*** ***6911***
LPST Id: 110737
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045251
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

KEMP PROPERTIES ***501 COLORADO ST*** ***W 0 - 1/8 (0.058 mi.)*** ***LA2257 / 11*** ***6933***
LPST Id: 118164
CA Status: 6P - FINAL PENDING WELL PLUG
Status Code: FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING

FIRESTONE TIRE & SER ***311 S CONGRESS AVE*** ***SSW 0 - 1/8 (0.061 mi.)*** ***NA2281 / 11*** ***6952***
LPST Id: 106686
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0064640
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FIRE STATION 1 ***401 E 5TH ST*** ***SSW 0 - 1/8 (0.062 mi.)*** ***2290 / 11*** ***6958***
LPST Id: 113612
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018162
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

DIANA D ZUMWALT ETAL ***1214 S 1ST ST*** ***WNW 0 - 1/8 (0.062 mi.)*** ***KZ2298 / 14*** ***6969***

LPST Id: 104920
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063598
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN STORE 36656	***620 W 29TH ST***	***WNW 0 - 1/8 (0.065 mi.)***	***LU2332 / 8***	***7042***

LPST Id: 119478
CA Status: 6A - FINAL CONCURRENCE ISSUED

BROADDUS CHEVRON	***30 N IH 35***	***NE 0 - 1/8 (0.066 mi.)***	***MO2347 / 14***	***7089***

LPST Id: 105305
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0028644
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EXXON STATION 67383	3807 EAST AVE	ENE 0 - 1/8 (0.067 mi.)	MQ2382 / 8	7150

LPST Id: 099887
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0026118
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

COLD	***704 W POWELL LN***	***SE 0 - 1/8 (0.067 mi.)***	***NR2392 / 6***	***7170***

LPST Id: 108068
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0038471
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SERVICE CENTER 2	***600 RIVER ST***	***WNW 0 - 1/8 (0.068 mi.)***	***OC2406 / 11***	***7215***

LPST Id: 091466
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018143
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

M D PHARMACY	***1701 LAVACA ST***	***ESE 0 - 1/8 (0.070 mi.)***	***MP2432 / 11***	***7247***

LPST Id: 103931
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063341
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SNAX BASKET 3 TX0297	***3515 N LAMAR BLVD***	***WNW 0 - 1/8 (0.078 mi.)***	***OT2527 / 8***	***7465***

LPST Id: 110658
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0045191
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN WATER WASTEWA	901 W KOENIG LN	WNW 0 - 1/8 (0.080 mi.)	OE2548 / 8	7560

LPST Id: 115765
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 018147
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

JIFFY LUBE #2925	***3401 N LAMAR BLVD***	***WNW 0 - 1/8 (0.082 mi.)***	***OY2566 / 8***	***7593***

LPST Id: 091708
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CIRCLE K 3245	***3201 N LAMAR BLVD***	***WNW 0 - 1/8 (0.082 mi.)***	***OZ2575 / 8***	***7640***

LPST Id: 105084
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0036614
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PECAN FOOD MART	***2101 S 1ST ST***	***WNW 0 - 1/8 (0.086 mi.)***	***OR2619 / 14***	***7760***

LPST Id: 120452
CA Status: 6A - FINAL CONCURRENCE ISSUED

FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	W 0 - 1/8 (0.086 mi.)	PA2625 / 11	7826

LPST Id: 117820
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014803
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN AMERICAN STAT	305 S CONGRESS AVE	SE 0 - 1/8 (0.089 mi.)	2659 / 11	8000

LPST Id: 104432
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019681
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN SALES	***825 PRAIRIE TRL***	***WNW 0 - 1/8 (0.089 mi.)***	***NN2668 / 3***	***8024***

LPST Id: 095261
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0053148
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER FUELING FACIL	1000 W 39TH ST	WNW 0 - 1/8 (0.094 mi.)	PR2725 / 8	8230

LPST Id: 121264
CA Status: 6A - FINAL CONCURRENCE ISSUED

SUB WAY	***3724 N LAMAR BLVD***	***WNW 0 - 1/8 (0.096 mi.)***	***OT2739 / 8***	***8251***

LPST Id: 106533
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0033138
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

RAILTON MANUFACTURIN	***906 JUSTIN LN***	***WNW 0 - 1/8 (0.099 mi.)***	***PV2751 / 6***	***8270***

LPST Id: 099116
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0031174
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SOUTHWESTERN BELL TE	817 W NORTH LOOP BLV	WNW 0 - 1/8 (0.104 mi.)	QA2773 / 8	8366

LPST Id: 091998
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019359
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

NORTH LOOP SOC	819 W NO LOOP BLVD	WNW 0 - 1/8 (0.104 mi.)	QA2775 / 8	8369

LPST Id: 091504
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0020853
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN HOMESTEAD 451	819 W NO LOOP BLVD	WNW 0 - 1/8 (0.104 mi.)	QA2776 / 8	8370

LPST Id: 104122
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0020853
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

COMMEMORATIVE BRANDS	***7211 CIRCLE S RD***	***ESE 0 - 1/8 (0.104 mi.)***	***QB2779 / 17***	***8389***

LPST Id: 105722
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0006726
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

MOBIL STATION	E 7TH ST	ENE 0 - 1/8 (0.105 mi.)	NZ2786 / 11	8491

LPST Id: 091022
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

GENERAL SERVICES COM ***1518 SAN JACINTO BLV*** ***ESE 0 - 1/8 (0.109 mi.)*** ***QK2810 / 11*** ***8541***
LPST Id: 111590
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

STATE SERVICE STATIO ***1502 SAN JACINTO BLV*** ***ESE 0 - 1/8 (0.109 mi.)*** ***PD2811 / 11*** ***8554***
LPST Id: 097342
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0048285
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

MOBIL OIL 00AFT ***717 E 7TH ST*** ***ENE 0 - 1/8 (0.122 mi.)*** ***QC2871 / 11*** ***8797***
LPST Id: 107633
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0017721
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SAFEWAY RENTAL EQUIP ***311 BOWIE ST*** ***WNW 1/8 - 1/4 (0.162 mi.)*** ***RL2939 / 11*** ***9073***
LPST Id: 095362
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0042881
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CLOSED GASOLINE STAT ***2803 SAN JACINTO BLV*** ***E 1/8 - 1/4 (0.164 mi.)*** ***2946 / 11*** ***9118***
LPST Id: 096737
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0055851
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SUNRISE MINI MART 8 ***539 W OLTORF ST*** ***W 1/8 - 1/4 (0.164 mi.)*** ***2947 / 14*** ***9150***
LPST Id: 113083
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039554
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN METAL IRON ***301 SAN MARCOS ST*** ***ESE 1/8 - 1/4 (0.168 mi.)*** ***RP2956 / 11*** ***9207***
LPST Id: 097147
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0015501
Status Code: MONITORING

SOUTH AUSTIN SERVICE ***3815 WOODBURY DR*** ***ESE 1/8 - 1/4 (0.171 mi.)*** ***RQ2963 / 14*** ***9263***
LPST Id: 102299
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0041137
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7 ELEVEN STO4RE 3664 ***814 E 7TH ST*** ***ENE 1/8 - 1/4 (0.176 mi.)*** ***RS2970 / 11*** ***9308***
LPST Id: 117501
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0073993
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SOUTHLAND REDDY ICE 901 RED RIVER ST NE 1/8 - 1/4 (0.181 mi.) RX2989 / 11 9428
LPST Id: 092275
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0024217

Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

OLD TOWNSENDS TEXACO	2511 SAN JACINTO	E 1/8 - 1/4 (0.185 mi.)	RY2992 / 11	9435

LPST Id: 106331
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

BEN WHITE U HAUL	***304 E BEN WHITE BLVD***	***ESE 1/8 - 1/4 (0.193 mi.)***	***3004 / 18***	***9483***

LPST Id: 110012
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0036411
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

KOLPACK PROPERTY	901-905 BARTON SPRIN	WNW 1/8 - 1/4 (0.193 mi.)	SB3005 / 11	9496

LPST Id: 112262
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO FOOD MART	701 EAST AVE	ENE 1/8 - 1/4 (0.196 mi.)	RS3012 / 11	9543

LPST Id: 097519
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023198
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO	701 N IH 35	ENE 1/8 - 1/4 (0.196 mi.)	RS3017 / 11	9549

LPST Id: 107988
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023198
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO	701 N IH 35	ENE 1/8 - 1/4 (0.196 mi.)	RS3018 / 11	9550

LPST Id: 091374
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023198
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TXDOT SPECIAL CREWS	***760 BASTROP HWY S***	***NNE 1/8 - 1/4 (0.198 mi.)***	***SH3027 / 15***	***9568***

LPST Id: 097012
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010054
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 21884	***917 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.199 mi.)***	***SF3035 / 11***	***9603***

LPST Id: 103888
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007174
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ASCENSION SETON MEDI	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***

LPST Id: 097017
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0056515
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CASTLEBERRY INSTRUMT	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3057 / 2***	***9930***

LPST Id: 095273
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014678
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SERVICE BUILDING VEH	***304 E 24TH ST***	***E 1/8 - 1/4 (0.214 mi.)***	***3068 / 11***	***10005***

LPST Id: 096480

CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0011352
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

KWIK MART 1	***1200 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.217 mi.)***	***SS3076 / 11***	***10033***

LPST Id: 103025
LPST Id: 121586
CA Status: 6A - FINAL CONCURRENCE ISSUED
CA Status: 1 - RELEASE DETERMINATION
Facility ID: 0038369
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

REDDY ICE OAK FARMS	***910 RED RIVER ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***3088 / 11***	***10139***

LPST Id: 091874
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0046016
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TERMINIX INTERNATION	***1206 PARKWAY***	***WNW 1/8 - 1/4 (0.229 mi.)***	***SS3103 / 11***	***10183***

LPST Id: 107715
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0065241
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TRAVIS COUNTY FLEET	***1000 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.241 mi.)***	***TE3128 / 11***	***10317***

LPST Id: 114336
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0044492
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CAPITOL CHEVROLET	***501 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.246 mi.)***	***TB3146 / 11***	***10412***

LPST Id: 095067
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025102
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN CULLIGAN	***505 W YAGER LANE***	***E 1/8 - 1/4 (0.246 mi.)***	***TI3148 / 4***	***10483***

LPST Id: 099146
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0058012
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SIGNATURE 9	***900 EAST AVE***	***NE 1/4 - 1/2 (0.256 mi.)***	***3163 / 11***	***10660***

LPST Id: 096329
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034918
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

AUSTIN ISD SNEED	***5901 GUADALUPE ST***	***ESE 1/4 - 1/2 (0.259 mi.)***	***TF3164 / 9***	***10696***

LPST Id: 101331
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0048091
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

BUTCH WOOTEN INVESTM	315 E SAINT ELMO RD	ESE 1/4 - 1/2 (0.269 mi.)	3166 / 18	10722

LPST Id: 104781
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0043179
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

HLD FOOD MART	1112 W KOENIG LN	WNW 1/4 - 1/2 (0.274 mi.)	TL3169 / 8	10752

LPST Id: 108443
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014326
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WEED-CORLEY FUNERAL ***1301 W 34TH ST*** ***WNW 1/4 - 1/2 (0.285 mi.)*** ***3172 / 8*** ***10782***
LPST Id: 102033
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0021445
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SPAW GLASS CONSTRUCT 1020 RED RIVER ST NNE 1/4 - 1/2 (0.287 mi.) 3174 / 11 10787
LPST Id: 093412
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0048597
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FIRE STATION 16 ***7000 REESE LN*** ***WNW 1/4 - 1/2 (0.294 mi.)*** ***3176 / 6*** ***10789***
LPST Id: 103200
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018164
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOPPERS MART 6 2453 HIGHWAY 71 E E 1/4 - 1/2 (0.296 mi.) TM3177 / 20 10810
LPST Id: 091829
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034915
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SHOPPERS MART 6 2453 HIGHWAY 71 E E 1/4 - 1/2 (0.296 mi.) TM3178 / 20 10811
LPST Id: 095400
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034915
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

CIRCLE K STORE 27405 ***2222 E OLTORF ST*** ***SW 1/4 - 1/2 (0.300 mi.)*** ***TN3183 / 14*** ***10815***
LPST Id: 096255
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0044708
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

GEORGE TORRES TEXACO ***301 W KOENIG LN*** ***ESE 1/4 - 1/2 (0.310 mi.)*** ***3188 / 9*** ***10876***
LPST Id: 116141
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0035774
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER BROADDUS KOEN 1200 W KOENIG LN WNW 1/4 - 1/2 (0.314 mi.) TL3189 / 8 10881
LPST Id: 117699
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0000710
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

KOENIG LANE 66 1200 W KOENIG LN WNW 1/4 - 1/2 (0.314 mi.) TL3191 / 8 10882
LPST Id: 096197
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0000710
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ST ELMO 502 W SAINT ELMO RD WNW 1/4 - 1/2 (0.328 mi.) 3194 / 17 10890
LPST Id: 104325

CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010995
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

MERCEDES BENZ OF AUS ***6757 AIRPORT BLVD*** ***ESE 1/4 - 1/2 (0.339 mi.)*** ***3196 / 6*** ***10892***
LPST Id: 105936
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0060930
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER AIRPORT EXXON 2511 HIGHWAY 71 E E 1/4 - 1/2 (0.339 mi.) TO3198 / 20 10906
LPST Id: 117952
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0067980
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

OLTORF FOOD MART ***2225 E OLTORF ST*** ***SW 1/4 - 1/2 (0.341 mi.)*** ***3200 / 14*** ***10915***
LPST Id: 117966
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025762
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

RED ARROW FREIGHT LI ***8080 PURNELL DR*** ***SE 1/4 - 1/2 (0.345 mi.)*** ***3202 / 6*** ***10942***
LPST Id: 094319
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0006440
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

G S TYPESETTERS 410 BAYLOR ST WNW 1/4 - 1/2 (0.361 mi.) 3206 / 11 10984
LPST Id: 091181
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0029436
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WALGREENS ***120 W SLAUGHTER LN*** ***SW 1/4 - 1/2 (0.362 mi.)*** ***TP3208 / 21*** ***10986***
LPST Id: 118297
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0075395
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FIRST TEXAS HONDA ***1301 W KOENIG LN*** ***WNW 1/4 - 1/2 (0.364 mi.)*** ***TQ3209 / 8*** ***10989***
LPST Id: 104653
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0060813
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

VARGAS FOOD STORE ***809 VARGAS RD*** ***NW 1/4 - 1/2 (0.364 mi.)*** ***3210 / 15*** ***10994***
LPST Id: 096413
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0029356
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER BRACKENRIDGE ***601 E 15TH ST*** ***ESE 1/4 - 1/2 (0.365 mi.)*** ***TR3212 / 11*** ***11007***
LPST Id: 109025
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0000006
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SS6 1483 ***530 W BEN WHITE BLVD*** ***WNW 1/4 - 1/2 (0.373 mi.)*** ***3218 / 13*** ***11095***
LPST Id: 096813
CA Status: 6A - FINAL CONCURRENCE ISSUED

Facility ID: 0026030
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SUNRISE MINI MART 7 ***102 W POWELL LN*** ***SE 1/4 - 1/2 (0.375 mi.)*** ***TS3220 / 6*** ***11114***
LPST Id: 091221
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039569
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

THE CORNER STORE ***525 W BEN WHITE BLVD*** ***WNW 1/4 - 1/2 (0.386 mi.)*** ***3222 / 13*** ***11141***
LPST Id: 097504
CA Status: 6P - FINAL PENDING WELL PLUG
Facility ID: 0034917
Status Code: MONITORING

SERVICE CENTER 11 ***3616 S 1ST ST*** ***WNW 1/4 - 1/2 (0.388 mi.)*** ***TT3223 / 13*** ***11180***
LPST Id: 093394
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0018148
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SOUTH 1ST STREET SER 3616A S 1ST ST WNW 1/4 - 1/2 (0.388 mi.) TT3224 / 13 11185
LPST Id: 109091
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0057732
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ATT AUSTIN FACILITY ***705 E 12TH ST*** ***NE 1/4 - 1/2 (0.394 mi.)*** ***3225 / 11*** ***11186***
LPST Id: 104852
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063615
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

RICK HOFF ***4333 S 1ST ST*** ***WNW 1/4 - 1/2 (0.395 mi.)*** ***3227 / 17*** ***11195***
LPST Id: 104510
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063366
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

BEKINS MOVING STORAG 201 E ANDERSON LN ESE 1/4 - 1/2 (0.397 mi.) 3228 / 6 11212
LPST Id: 093515
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0035428
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

OLD SEARS WAREHOUSE ***108 DENSON DR*** ***ESE 1/4 - 1/2 (0.414 mi.)*** ***3233 / 9*** ***11243***
LPST Id: 096481
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0055939
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER QUIKIE PICKIE ***600 W BEN WHITE*** ***WNW 1/4 - 1/2 (0.414 mi.)*** ***3234 / 13*** ***11247***
LPST Id: 105609
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0063839
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 35805 ***13641 N IH 35*** ***N 1/4 - 1/2 (0.425 mi.)*** ***3238 / 2*** ***11261***
LPST Id: 099597
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0049321

Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

FORMER TRUCK CITY DE	502 E BEN WHITE BLVD	ESE 1/4 - 1/2 (0.428 mi.)	TW3239 / 18	11289

LPST Id: 107201
CA Status: 6A - FINAL CONCURRENCE ISSUED
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

HYDE PARK TEXACO	***4500 DUVAL ST***	***E 1/4 - 1/2 (0.431 mi.)***	***3240 / 8***	***11290***

LPST Id: 102703
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014109
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EBENEZAR BAPTIST CHU	***1011 SAN MARCOS ST***	***ENE 1/4 - 1/2 (0.432 mi.)***	***3245 / 11***	***11300***

LPST Id: 107418
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0062742
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PHOENIX MOTOR WORKS	***1127 W 6TH ST***	***WNW 1/4 - 1/2 (0.433 mi.)***	***3246 / 11***	***11306***

LPST Id: 102019
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0065501
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TOWN FOOD MART	***800 E WILLIAM CANNON***	***ESE 1/4 - 1/2 (0.434 mi.)***	***TY3248 / 17***	***11319***

LPST Id: 096235
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0034931
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

USPS S AUSTIN STATIO	1806 S 5TH ST	WNW 1/4 - 1/2 (0.434 mi.)	3249 / 14	11349

LPST Id: 098418
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025438
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

ANDYS FOOD MART	***611 W STASSNEY LN***	***WNW 1/4 - 1/2 (0.434 mi.)***	***TZ3251 / 17***	***11352***

LPST Id: 117469
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0010999
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN 26353	***601 W BEN WHITE BLVD***	***WNW 1/4 - 1/2 (0.436 mi.)***	***UA3253 / 13***	***11364***

LPST Id: 100227
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0055616
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WENCO DISTRIBUTORS O	***600 INDUSTRIAL BLVD***	***ESE 1/4 - 1/2 (0.446 mi.)***	***3256 / 18***	***11400***

LPST Id: 100669
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0000803
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SUNRISE SUPER STOP	***4429 DUVAL ST***	***E 1/4 - 1/2 (0.451 mi.)***	***UC3259 / 9***	***11414***

LPST Id: 114818
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0039570
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

MR SAMS FOODMART	***6515 AIRPORT BLVD***	***ESE 1/4 - 1/2 (0.452 mi.)***	***3261 / 9***	***11445***

LPST Id: 101816
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0019629
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

WHIP IN 2 100148 ***1950 S IH 35*** ***WSW 1/4 - 1/2 (0.456 mi.)*** ***3267 / 14*** ***11480***
LPST Id: 108190
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0014317
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

SUNRISE MINI MART 2 ***915 W OLTORF ST*** ***WNW 1/4 - 1/2 (0.457 mi.)*** ***3268 / 14*** ***11486***
LPST Id: 103773
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0007135
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

E-Z STOP 2 ***1200 KRAMER LN STE 1*** ***WNW 1/4 - 1/2 (0.462 mi.)*** ***3272 / 3*** ***11537***
LPST Id: 102762
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0004054
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

B R CAPPS TEXACO ***520 BASTROP HWY N*** ***N 1/4 - 1/2 (0.463 mi.)*** ***UE3273 / 15*** ***11565***
LPST Id: 100595
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025063
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EXXON RS 67897 ***1104 EAST AVE*** ***ESE 1/4 - 1/2 (0.468 mi.)*** ***3279 / 11*** ***11581***
LPST Id: 094253
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0026131
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TEXACO ***5600 S 1ST ST*** ***WNW 1/4 - 1/2 (0.468 mi.)*** ***3280 / 17*** ***11598***
LPST Id: 105337
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0023197
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

PERRY ROSE TIRE HIGH ***6401 AIRPORT BLVD*** ***ESE 1/4 - 1/2 (0.481 mi.)*** ***3287 / 9*** ***11633***
LPST Id: 102170
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0022276
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

LESTER BROWN PHILLIP ***4500 BURNET RD*** ***NNW 1/4 - 1/2 (0.484 mi.)*** ***3289 / 8*** ***11641***
LPST Id: 103903
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0025353
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

EXXON MOBIL 67278 ***1320 E OLTORF ST*** ***ESE 1/4 - 1/2 (0.489 mi.)*** ***UG3290 / 14*** ***11656***
LPST Id: 111245
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0026115
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

7-ELEVEN STORE 36636 ***1320 E OLTORF ST*** ***ESE 1/4 - 1/2 (0.489 mi.)*** ***UG3293 / 14*** ***11662***
LPST Id: 121023

EXECUTIVE SUMMARY

CA Status: 6A - FINAL CONCURRENCE ISSUED

CONTINENTAL CARS ***200 W HUNTLAND*** ***ESE 1/4 - 1/2 (0.493 mi.)*** ***3295 / 9*** ***11710***
LPST Id: 101182
CA Status: 6A - FINAL CONCURRENCE ISSUED
Facility ID: 0015519
Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED

TX RDR: Release Determination Report Listing

A review of the TX RDR list, as provided by EDR, and dated 03/29/2023 has revealed that there are 197 TX RDR sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
HI TECH AUTOMOTIVE	1801 S CONGRESS AVE	ESE 0 - 1/8 (0.011 mi.)	FG952 / 14	2907
HEB GROCERY	2508 RIVERSIDE DR	NE 0 - 1/8 (0.012 mi.)	HS959 / 15	2917
FAMOUS FOOD MART	***6301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***AI992 / 6***	***3045***
SHELL FOOD MART	6301 N LAMAR BLVD	ESE 0 - 1/8 (0.012 mi.)	AI994 / 6	3071
WALGREENS	2000 E RIVERSIDE DR	NE 0 - 1/8 (0.012 mi.)	FO1015 / 14	3196
PREMIUM PARKING PUBL	415 E 7TH STREET	NNE 0 - 1/8 (0.013 mi.)	DM1040 / 11	3263
SHOP N CARRY FOODS	***8422 S CONGRESS AVE***	***WNW 0 - 1/8 (0.013 mi.)***	***HO1043 / 21***	***3280***
5TH AND WEST	***501 WEST AVE***	***WNW 0 - 1/8 (0.013 mi.)***	***DC1060 / 11***	***3358***
BEVERAGE BARN	2001 RIVERSIDE	SW 0 - 1/8 (0.013 mi.)	FO1067 / 14	3371
DIRTY MARTINS PLACE	2808 GUADALUPE	WSW 0 - 1/8 (0.013 mi.)	HY1083 / 11	3457
METRO STAR GROCERY	***10304 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***IF1092 / 3***	***3477***
NORTH LAMAR PHILLIPS	11100 NORTH LAMAR	WNW 0 - 1/8 (0.013 mi.)	I1103 / 3	3516
C A SCHUTZE AGENCY	1101 S CONGRESS AVE	ESE 0 - 1/8 (0.013 mi.)	ES1108 / 14	3517
FORMER TWOMEYS AUTO	1009 S CONGRESS AVE	ESE 0 - 1/8 (0.013 mi.)	ER1110 / 14	3522
LUU AUTO ELECTRIC	***8603 N. LAMAR BLVD.***	***SE 0 - 1/8 (0.013 mi.)***	***U1114 / 6***	***3537***
LAMAR CORNER STORE	***7545 N LAMAR BLVD***	***ESE 0 - 1/8 (0.013 mi.)***	***Z1116 / 6***	***3538***
OLMEDA TIRE & AUTO	8807 N LAMAR BLVD	SE 0 - 1/8 (0.014 mi.)	S1139 / 6	3660
CONOCO FOOD MART	6214 EAST RIVERSIDE	NNE 0 - 1/8 (0.014 mi.)	GQ1143 / 15	3694
FORMER AUTO SALES FA	118 E RIVERSIDE DR	NE 0 - 1/8 (0.014 mi.)	1151 / 14	3706
KISHAN FOOD STOP 417	5630 N LAMAR BLVD	WNW 0 - 1/8 (0.014 mi.)	AL1163 / 8	3767
BRITTS AUTOMOTIVE	5630 N LAMAR	WNW 0 - 1/8 (0.014 mi.)	AL1165 / 8	3768
7-ELEVEN INC STORE N	5630 N LAMAR BLVD	WNW 0 - 1/8 (0.014 mi.)	AL1168 / 8	3798
7 ELEVEN STORE 36653	***5630 N LAMAR BLVD***	***WNW 0 - 1/8 (0.014 mi.)***	***AL1170 / 8***	***3799***
AUTO SALVAGE YARD	6108 E. RIVERSIDE DR	NNE 0 - 1/8 (0.015 mi.)	IN1222 / 15	3883
AUTO SALVAGE YARD	6108 E. RIVERSIDE	NNE 0 - 1/8 (0.015 mi.)	IN1223 / 15	3884
JIFFY LUBE STORE #82	3809 GUADALUPE	ESE 0 - 1/8 (0.016 mi.)	BA1250 / 8	3936
JIFFY LUBE	3809 GUADALUPE	ESE 0 - 1/8 (0.016 mi.)	BA1251 / 8	3936
7 ELEVEN 16996	2600 GUADALUPE	W 0 - 1/8 (0.016 mi.)	BO1258 / 11	3962
7-ELEVEN 16996	***2600 GUADALUPE ST***	***W 0 - 1/8 (0.016 mi.)***	***BO1259 / 11***	***3963***
DIAMOND SHAMROCK 236	***1620 E RIVERSIDE DR***	***NE 0 - 1/8 (0.017 mi.)***	***FF1266 / 14***	***4032***
KLINGEMANN CAR CARE	6200 N LAMAR BLVD	WNW 0 - 1/8 (0.019 mi.)	AJ1321 / 9	4189
DALE'S AUTO	7544 N. LAMAR	WNW 0 - 1/8 (0.019 mi.)	Z1331 / 6	4205
DOCS AUTO WORKS	1123 S CONGRESS AVE	ESE 0 - 1/8 (0.020 mi.)	ET1347 / 14	4263
DOCS BACK YARD	***1123 SOUTH CONGRESS***	***ESE 0 - 1/8 (0.020 mi.)***	***ET1350 / 14***	***4264***
PHILLIPS 66 #27288	5301 NORTH LAMAR	ESE 0 - 1/8 (0.020 mi.)	AO1368 / 8	4308
PRET MANGER	***5301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.020 mi.)***	***AO1369 / 8***	***4308***
ANTOINE GROCERY	***11209 N LAMAR BLVD***	***ESE 0 - 1/8 (0.021 mi.)***	***IS1395 / 3***	***4415***
7-ELEVEN 24008	***5101 N LAMAR BLVD***	***ESE 0 - 1/8 (0.022 mi.)***	***AQ1417 / 8***	***4457***
7-ELEVEN #24008	5101 N LAMAR	ESE 0 - 1/8 (0.022 mi.)	AQ1418 / 8	4496
7 ELEVEN 24008	5101 N LAMAR	ESE 0 - 1/8 (0.022 mi.)	AQ1421 / 8	4497
SPEEDYS	6301 E RIVERSIDE	SSW 0 - 1/8 (0.023 mi.)	GQ1449 / 15	4577
SPEEDY'S	6301 EAST RIVERSIDE	SSW 0 - 1/8 (0.023 mi.)	GQ1451 / 15	4578

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SPEEDYS	***6301 E RIVERSIDE DR***	***SSW 0 - 1/8 (0.023 mi.)***	***GQ1452 / 15***	***4579***
MS EXPRESS 901	***2105 S CONGRESS AVE***	***ESE 0 - 1/8 (0.023 mi.)***	***FK1459 / 14***	***4637***
HOUSTON CONVENIENCE	2105 S CONGRESS AVE	ESE 0 - 1/8 (0.023 mi.)	FK1461 / 14	4666
WILLIAM TRAVIS STATE	1701 CONGRESS AVE	WNW 0 - 1/8 (0.023 mi.)	JL1478 / 11	4702
N/A	401 S FIRST STREET	NW 0 - 1/8 (0.023 mi.)	EH1489 / 11	4723
FORMER 7 ELEVEN 1781	12430 N LAMAR BLVD	W 0 - 1/8 (0.024 mi.)	JN1501 / 2	4783
TEXACO SHOPPERS MART	90 EAST AVE	ESE 0 - 1/8 (0.024 mi.)	JF1509 / 14	4825
SOCO CENTER	***3630 S CONGRESS AVE***	***WNW 0 - 1/8 (0.025 mi.)***	***GM1513 / 14***	***4826***
DIAMOND SHAMROCK NO	3630 S CONGRESS ST	WNW 0 - 1/8 (0.025 mi.)	GM1514 / 14	4870
SOUTH CONGRESS FOOD	3630 S CONGRESS AVE	WNW 0 - 1/8 (0.025 mi.)	GM1515 / 14	4871
FORMER TEXAC0	1900 GUADALUPE	W 0 - 1/8 (0.025 mi.)	CD1528 / 11	4885
TEXACO STATION	1900 GUADALUPE	W 0 - 1/8 (0.025 mi.)	CD1533 / 11	4913
GIANT FOOD MART	***8700 N LAMAR BLVD***	***NW 0 - 1/8 (0.025 mi.)***	***T1553 / 6***	***4993***
DIAMOND SHAMROCK 963	***3706 GUADALUPE ST***	***WNW 0 - 1/8 (0.026 mi.)***	***BB1564 / 8***	***5045***
EXPRESS MART 7	10500 N LAMAR BLVD	WNW 0 - 1/8 (0.026 mi.)	JR1567 / 3	5093
7 ELEVEN 30467	10111 N LAMAR	ESE 0 - 1/8 (0.026 mi.)	JS1570 / 3	5095
7 ELEVEN STORE 30467	10111 N LAMAR ST	ESE 0 - 1/8 (0.026 mi.)	JS1574 / 3	5126
7-11	10111 N LAMAR	ESE 0 - 1/8 (0.026 mi.)	JS1575 / 3	5127
EXXON #6-01033	2512 EAST RIVERSIDE	NE 0 - 1/8 (0.026 mi.)	HS1580 / 15	5190
7-ELEVEN 25445	8900 N LAMAR	WNW 0 - 1/8 (0.026 mi.)	R1591 / 6	5197
7 ELEVEN 25445	8900 N LAMAR	WNW 0 - 1/8 (0.026 mi.)	R1594 / 6	5225
DANNY LITTLE	106 E 6TH STREET	NNE 0 - 1/8 (0.027 mi.)	DN1601 / 11	5250
RIVERSIDE CHEVRON	400 SOUTH CONGRESS A	WNW 0 - 1/8 (0.027 mi.)	EJ1641 / 14	5475
SPEEDY STOP 405	7715 E BEN WHITE	WNW 0 - 1/8 (0.028 mi.)	JW1676 / 19	5532
7-ELEVEN STORE 36642	***7715 E BEN WHITE BLV***	***WNW 0 - 1/8 (0.028 mi.)***	***JW1678 / 19***	***5533***
OSF CONGRESS LP	2701 S CONGRESS	NNE 0 - 1/8 (0.029 mi.)	JX1696 / 14	5600
FORMER 7 ELEVEN 2007	6702 CONGRESS AVE	WNW 0 - 1/8 (0.030 mi.)	JZ1708 / 17	5647
BEVERAGE BARN	2001 E RIVERSIDE BLV	SW 0 - 1/8 (0.031 mi.)	KA1718 / 14	5672
BEVERAGE BARN	2001 EAST RIVERSIDE	SW 0 - 1/8 (0.031 mi.)	KA1719 / 14	5672
BEVERAGE BARN	2001 E RIVERSIDE	SW 0 - 1/8 (0.031 mi.)	KA1720 / 14	5675
BEVERAGE BARN	***2001 E RIVERSIDE DR***	***SW 0 - 1/8 (0.031 mi.)***	***KA1721 / 14***	***5676***
AUSTIN TENNYSON 836	11409 N LAMAR	ESE 0 - 1/8 (0.031 mi.)	KB1722 / 3	5714
SAME	11409 N LAMAR	ESE 0 - 1/8 (0.031 mi.)	KB1724 / 3	5722
SHELL	3906 S CONGRESS AVE	WNW 0 - 1/8 (0.032 mi.)	KD1739 / 14	5769
TEXACO SERVICE STATI	3906 S CONGRESS	WNW 0 - 1/8 (0.032 mi.)	KD1741 / 14	5769
AUSTIN MUSIC HALL	***208 NUECES ST***	***E 0 - 1/8 (0.033 mi.)***	***1766 / 11***	***5921***
VACANT PROPERTY BRAZ	501 BRAZOS ST	SSW 0 - 1/8 (0.033 mi.)	DP1768 / 11	5922
FORMER BANK DRIVE TH	501 BRAZOS	SSW 0 - 1/8 (0.033 mi.)	DP1770 / 11	5923
NORTH LAMAR QUICK ST	***8545 N LAMAR BLVD***	***SE 0 - 1/8 (0.034 mi.)***	***KM1787 / 6***	***5970***
TWIN LIQUORS	***519 E 7TH ST***	***NE 0 - 1/8 (0.034 mi.)***	***IL1796 / 11***	***6035***
FRANK HUNT PROPERTY	605 W 37TH ST	WNW 0 - 1/8 (0.037 mi.)	IC1834 / 8	6086
IMPORT CAR REPAIR	10631 N LAMAR	ESE 0 - 1/8 (0.038 mi.)	KV1859 / 3	6156
7 ELEVEN STORE 19097	***1705 S LAKESHORE BLV***	***ENE 0 - 1/8 (0.039 mi.)***	***KX1865 / 14***	***6182***
7 ELEVEN STORE NO 19	1705 S LAKESHORE BLV	ENE 0 - 1/8 (0.039 mi.)	KX1867 / 14	6210
FAIRMONT HOTEL	***600 E CESAR CHAVEZ S***	***WNW 0 - 1/8 (0.039 mi.)***	***LB1879 / 11***	***6250***
DIAMOND SHAMROCK 207	628 E OLTROF	SE 0 - 1/8 (0.040 mi.)	LD1883 / 14	6254
7-ELEVEN STORE 38608	***105 E STASSNEY LN***	***ESE 0 - 1/8 (0.042 mi.)***	***LL1916 / 17***	***6375***
QMART STASSNEY	105 E STASSNEY	ESE 0 - 1/8 (0.042 mi.)	LL1917 / 17	6399
2810 HEMPHILL	2810 HEMPHILL PK	ENE 0 - 1/8 (0.044 mi.)	HY1929 / 11	6416
HOMESTEAD 451 CENTRA	817 N LOOP	WNW 0 - 1/8 (0.044 mi.)	LM1934 / 8	6421
EXXON 6-9404	6721 S CONGRESS	ESE 0 - 1/8 (0.045 mi.)	LP1945 / 17	6427
AT&T SOC XU3382	819 N LOOP W	WNW 0 - 1/8 (0.046 mi.)	LM1965 / 8	6456
FORMER STATION	3706 SPEEDWAY	ESE 0 - 1/8 (0.047 mi.)	LV1986 / 8	6485
FORMER DOWNTOWN AUTO	***800 W 6TH ST***	***WNW 0 - 1/8 (0.048 mi.)***	***LX1998 / 11***	***6496***
DIAMOND SHAMROCK NO	1516 TINNIN FORD	NE 0 - 1/8 (0.050 mi.)	MF2031 / 14	6563
FAST STOP STORE 11	5526 S CONGRESS	WNW 0 - 1/8 (0.050 mi.)	MH2042 / 17	6614

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ABANDONED	400 LAVACA ST	ESE 0 - 1/8 (0.054 mi.)	KG2162 / 11	6774
7 ELEVEN 12705	408 W 15TH ST	WNW 0 - 1/8 (0.055 mi.)	MV2174 / 11	6818
AUSTIN CONV. CTR. EX	3RD & RED RIVER	WNW 0 - 1/8 (0.056 mi.)	MY2196 / 11	6843
BOWMAN RESIDENCE	***212 W 33RD ST***	***WNW 0 - 1/8 (0.057 mi.)***	***2237 / 8***	***6867***
STARR BLDG HISTORIC	501 COLORADO	W 0 - 1/8 (0.058 mi.)	LA2256 / 11	6932
FORMER GLO FAC	421 E 1ST	ESE 0 - 1/8 (0.060 mi.)	KS2269 / 11	6937
DIAMOND SHAMROCK 206	620 W 29TH ST	WNW 0 - 1/8 (0.065 mi.)	LU2333 / 8	7069
TP 2533	620 W 29TH ST	WNW 0 - 1/8 (0.065 mi.)	LU2334 / 8	7070
FROMER 7 ELEVEN 3665	620 W 29TH ST	WNW 0 - 1/8 (0.065 mi.)	LU2335 / 8	7070
520 W 6TH ST LLC	520 W 6TH	ESE 0 - 1/8 (0.067 mi.)	KR2390 / 11	7169
KENICHI RESTAURANT	***121 W 5TH ST***	***SW 0 - 1/8 (0.073 mi.)***	***OK2463 / 11***	***7309***
CITY STAR FOODS	***31 N I 35***	***NNE 0 - 1/8 (0.074 mi.)***	***OM2476 / 14***	***7355***
ST. EDWARDS UNIVERSI	3001 S CONGRESS	ESE 0 - 1/8 (0.075 mi.)	ON2480 / 14	7364
KOENIG LANE SERVICE	901 W KOENIG LN	WNW 0 - 1/8 (0.080 mi.)	OE2546 / 8	7533
TRAM STOP	***3201 N LAMAR BLVD***	***WNW 0 - 1/8 (0.082 mi.)***	***OZ2573 / 8***	***7628***
PECAN FOOD MART	***2101 S 1ST ST***	***WNW 0 - 1/8 (0.086 mi.)***	***OR2619 / 14***	***7760***
7 ELEVEN STORE 35069	6607 CIRCLE S RD	ESE 0 - 1/8 (0.086 mi.)	PF2621 / 17	7790
FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	W 0 - 1/8 (0.086 mi.)	PA2626 / 11	7827
CHOTES CHEVRON	500 W MARTIN LUTHER	W 0 - 1/8 (0.086 mi.)	PA2629 / 11	7841
TEXAS GOVERNORS MANS	***1010 COLORADO ST***	***WNW 0 - 1/8 (0.088 mi.)***	***PK2654 / 11***	***7993***
FORMER FUELING FACIL	1000 WEST 39TH ST	WNW 0 - 1/8 (0.094 mi.)	PR2726 / 8	8231
FOOD SPOT 2	***2538 ELMONT DR***	***NE 0 - 1/8 (0.105 mi.)***	***2783 / 15***	***8471***
UNIVERSITY SIGN SHOP	2920 SAN JACINTO	E 0 - 1/8 (0.111 mi.)	QM2820 / 11	8667
TXDOT RIGHT OF WAY	S MLK & E SAN JACINT	ESE 0 - 1/8 (0.120 mi.)	PT2858 / 11	8731
H A GUERRO CARPET CL	2313 S 1ST	W 0 - 1/8 (0.121 mi.)	QT2861 / 14	8733
TETCO #1167	717 E 7TH ST	ENE 0 - 1/8 (0.122 mi.)	QC2868 / 11	8753
7-ELEVEN 36422	***717 E 7TH ST***	***ENE 0 - 1/8 (0.122 mi.)***	***QC2870 / 11***	***8759***
7-ELEVEN INC STORE N	717 E 7TH ST	ENE 0 - 1/8 (0.122 mi.)	QC2873 / 11	8802
EXXON 6 2790	619 N IH 35	ESE 0 - 1/8 (0.125 mi.)	2887 / 8	8830
RBJ REDEVELOPMENT PR	***21 WALLER ST***	***NE 1/8 - 1/4 (0.130 mi.)***	***2895 / 14***	***8851***
RUDYS AUTOMOTIVE	***4431 LUCKSINGER LN***	***ESE 1/8 - 1/4 (0.132 mi.)***	***RC2897 / 17***	***8857***
PENSKE TRUCK RENTAL	8800 SOUTH CONGRESS	SW 1/8 - 1/4 (0.132 mi.)	RD2901 / 21	8894
SAFEWAY RENTAL TRACT	311 BOWIE ST	WNW 1/8 - 1/4 (0.162 mi.)	RL2940 / 11	9075
MOLINA AUTOMOTIVE	903 WAGON TRAIL	WNW 1/8 - 1/4 (0.165 mi.)	RA2949 / 3	9188
PERFERRED PUMP	3805 WOODBURY	ESE 1/8 - 1/4 (0.174 mi.)	RQ2967 / 14	9304
AUSTIN SHELL/STORE 4	814 E 7TH ST	ENE 1/8 - 1/4 (0.176 mi.)	RS2971 / 11	9309
TP 2519	814 E 7TH ST	ENE 1/8 - 1/4 (0.176 mi.)	RS2972 / 11	9310
ARMADILLO AUTOMOTIVE	901 E 6TH ST	E 1/8 - 1/4 (0.177 mi.)	RT2975 / 11	9317
SHELL FOOD MART	***4001 MEDICAL PKWY***	***WNW 1/8 - 1/4 (0.179 mi.)***	***RV2985 / 8***	***9389***
TCI COATINGS	***220 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.191 mi.)***	***SA2999 / 18***	***9466***
SOUTHSIDE BODY & FRA	2617 S. FIRST	W 1/8 - 1/4 (0.195 mi.)	SC3009 / 14	9533
FORMER UNLIMITED AUT	1023 W 24TH ST	W 1/8 - 1/4 (0.196 mi.)	SD3015 / 11	9548
TXDOT RIGHT OF AWAY	1250 BASTROP HWY	N 1/8 - 1/4 (0.197 mi.)	SE3022 / 16	9560
TXDOT OLD AUSTIN SPE	760 BASTROP HWY	NNE 1/8 - 1/4 (0.198 mi.)	SH3032 / 15	9597
7 ELEVEN 21884	917 N LAMAR BLVD	WNW 1/8 - 1/4 (0.199 mi.)	SF3033 / 11	9598
DON STEWART TEXACO	7110 E BEN WHITE	SSW 1/8 - 1/4 (0.214 mi.)	SP3065 / 19	9976
FORMER DON STEWART	7110 BEN WHITE BLVD	SSW 1/8 - 1/4 (0.214 mi.)	SP3067 / 19	10005
KWIK MART 1	***1200 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.217 mi.)***	***SS3076 / 11***	***10033***
AUSTIN LYRIC OPERA C	***905 BARTON SPRINGS R***	***WNW 1/8 - 1/4 (0.218 mi.)***	***SB3082 / 11***	***10090***
RIGHT OF WAY PARCEL	1240 OLD BASTROP HWY	N 1/8 - 1/4 (0.225 mi.)	SE3093 / 16	10158
PROPOSED CORAZON	1001 E 6TH ST	E 1/8 - 1/4 (0.226 mi.)	SW3096 / 11	10170
TEXAS DEPT PUBLIC SA	5710 GUADALUPE ST	ESE 1/8 - 1/4 (0.238 mi.)	TC3119 / 9	10252
FORMER TRAVIS CTY FL	1000 N LAMAR BLVD	WNW 1/8 - 1/4 (0.241 mi.)	TE3129 / 11	10319
CIRCLE K STORE 27046	8801 S I 35	SSE 1/8 - 1/4 (0.245 mi.)	3145 / 21	10412
TEXACO RETAIL FAC	2453 HWY 71	E 1/8 - 1/4 (0.247 mi.)	3153 / 20	10500
MONTOPOLIS GROCERY	***1211 MONTOPOLIS DR***	***NNE 1/4 - 1/2 (0.252 mi.)***	***TK3162 / 15***	***10657***

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SIGNATURE 9	***900 EAST AVE***	***NE 1/4 - 1/2 (0.256 mi.)***	***3163 / 11***	***10660***
PARKS & RECREATION M	***2525 S LAKESHORE BLV***	***ENE 1/4 - 1/2 (0.285 mi.)***	***3171 / 15***	***10754***
KING FOOD MART	2907 S FIRST ST	WSW 1/4 - 1/2 (0.286 mi.)	3173 / 14	10786
MOFFITT MAINTENANCE	11502 TITAN DR	WNW 1/4 - 1/2 (0.299 mi.)	3179 / 3	10812
CIRCLE K STORE 27405	2222 E OLTORF	SW 1/4 - 1/2 (0.300 mi.)	TN3180 / 14	10812
CIRCLE K STORE #2740	2222 E OLTORF ST	SW 1/4 - 1/2 (0.300 mi.)	TN3181 / 14	10813
CIRCLE K 2740552	2222 E OLTORF ST	SW 1/4 - 1/2 (0.300 mi.)	TN3182 / 14	10813
SIGNATURE 1	100 E SLAUGHTER LN	SSE 1/4 - 1/2 (0.303 mi.)	3184 / 21	10870
TXDOT	7901 N I 35 FRONTAGE	ESE 1/4 - 1/2 (0.308 mi.)	3187 / 21	10875
GEORGE TORRES TEXACO	***301 W KOENIG LN***	***ESE 1/4 - 1/2 (0.310 mi.)***	***3188 / 9***	***10876***
FORMER KOENIG CHEVRO	1200 KOENIG LN	WNW 1/4 - 1/2 (0.314 mi.)	TL3190 / 8	10882
TEXACO SERVICE STATI	616 WILLIAM CANNON	ESE 1/4 - 1/2 (0.314 mi.)	3192 / 17	10883
CAZARES PROPERTY	***1112 E 6TH ST***	***E 1/4 - 1/2 (0.334 mi.)***	***3195 / 11***	***10890***
OLTORF FOOD MART	***2225 E OLTORF ST***	***SW 1/4 - 1/2 (0.341 mi.)***	***3200 / 14***	***10915***
SOUTHWESTERN BELL	650 BASTROP HWY	N 1/4 - 1/2 (0.342 mi.)	3201 / 15	10941
JULIOS CAFE	***4220 DUVAL ST***	***E 1/4 - 1/2 (0.349 mi.)***	***3205 / 8***	***10984***
FORMER 7-ELEVEN 3906	120 W SLAUGHTER LN	SW 1/4 - 1/2 (0.362 mi.)	TP3207 / 21	10985
FORMER BRACKENRIDGE	601 E 15TH ST	ESE 1/4 - 1/2 (0.365 mi.)	TR3211 / 11	11007
FORMER BRACKENRIDGE	601 EAST 15TH ST	ESE 1/4 - 1/2 (0.365 mi.)	TR3214 / 11	11077
DIAMOND SHAMROCK 215	102 W POWELL LN	SE 1/4 - 1/2 (0.375 mi.)	TS3221 / 6	11140
C STORE	4111 S 1ST	WNW 1/4 - 1/2 (0.401 mi.)	3229 / 13	11212
PLAZA SALTILLO BLK 5	1301 E 5TH ST	E 1/4 - 1/2 (0.408 mi.)	TU3230 / 11	11213
MR MCS GROCERY & MAR	***2109 HOLLY ST***	***NE 1/4 - 1/2 (0.411 mi.)***	***3232 / 15***	***11216***
LUBE PIT STOP	1951 E OLTORF	SW 1/4 - 1/2 (0.420 mi.)	3235 / 14	11256
FORMER HAROLD TIEDT	302 S LAMAR BLVD	WSW 1/4 - 1/2 (0.423 mi.)	TV3236 / 11	11257
PATHMARK 34	609 BASTROP HWY	N 1/4 - 1/2 (0.432 mi.)	3244 / 15	11300
TEXACO RETAIL FAC	800 E WILLIAM CANNON	ESE 1/4 - 1/2 (0.434 mi.)	TY3247 / 17	11318
ANDYS FOOD MART	***611 W STASSNEY LN***	***WNW 1/4 - 1/2 (0.434 mi.)***	***TZ3250 / 17***	***11349***
7 ELEVEN 26353	601 W BEN WHITE BLVD	WNW 1/4 - 1/2 (0.436 mi.)	UA3252 / 13	11363
STOP N GO #2207	4429 DUVAL ST	E 1/4 - 1/2 (0.451 mi.)	UC3258 / 9	11414
MINIS FOOD MART	4429 DUVAL ST	E 1/4 - 1/2 (0.451 mi.)	UC3260 / 9	11444
CUTLER AUTOMOTIVE	***4416 BURNET RD***	***NNW 1/4 - 1/2 (0.453 mi.)***	***UD3262 / 8***	***11470***
TETCO #1169	1309 W. 45TH ST	NNW 1/4 - 1/2 (0.454 mi.)	UD3264 / 8	11475
ABANDONED	1401 W KOENIG LN	WNW 1/4 - 1/2 (0.455 mi.)	3265 / 8	11475
300-302 S LAMAR	300 S LAMAR	WSW 1/4 - 1/2 (0.460 mi.)	TV3269 / 11	11513
FORMER CAPPS TEXACO	520 BASTROP HWY	N 1/4 - 1/2 (0.463 mi.)	UE3274 / 15	11573
FORMER MUFFIN MUFFLE	4818 BURNET RD	WNW 1/4 - 1/2 (0.477 mi.)	3283 / 8	11617
7 ELEVEN STORE 36636	1320 E OLTORF ST	ESE 1/4 - 1/2 (0.489 mi.)	UG3291 / 14	11660
7-ELEVEN INC STORE N	1320 E OLTORF STREET	ESE 1/4 - 1/2 (0.489 mi.)	UG3292 / 14	11661
SHELL	500 W WILLIAM CANNON	WNW 1/4 - 1/2 (0.493 mi.)	3296 / 17	11720
SIGNATURE 2	608 S LAMAR AVE	WNW 1/4 - 1/2 (0.496 mi.)	UH3297 / 11	11721
TEXACO RETAIL FAC	608 S LAMAR	WNW 1/4 - 1/2 (0.496 mi.)	UH3298 / 11	11722
SIGNATURE 2	***608 S LAMAR BLVD***	***WNW 1/4 - 1/2 (0.496 mi.)***	***UH3299 / 11***	***11723***

Lists of state and tribal registered storage tanks

TX UST: Petroleum Storage Tank Database

A review of the TX UST list, as provided by EDR, and dated 03/02/2023 has revealed that there are 263 TX UST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
TEXAN MKT 5	***2700 S CONGRESS AVE***	***WNW 0 - 1/8 (0.011 mi.)***	***GD947 / 14***	***2880***

Facility Status: INACTIVE Facility Id: 19603 Facility Num: 75962 AI Number: 747690712002152				
7-ELEVEN 23630 Facility Status: INACTIVE Facility Id: 7172 Facility Num: 46174 AI Number: 732115942002117	***1901 RIO GRANDE ST***	***E 0 - 1/8 (0.011 mi.)***	***HQ950 / 11***	***2891***
HI TECH AUTOMOTIVE Facility Status: INACTIVE Facility Id: 78051 Facility Num: 120292 AI Number: 922276122006257	***1801 S CONGRESS AVE***	***ESE 0 - 1/8 (0.011 mi.)***	***FG953 / 14***	***2907***
DODD AUTOMOTIVE Facility Status: INACTIVE Facility Id: 1832 Facility Num: 39965 AI Number: 177625622002053	***4227 GUADALUPE ST***	***NNE 0 - 1/8 (0.012 mi.)***	***AT968 / 8***	***2947***
CAPITAL FOOD MART Facility Status: ACTIVE Facility Id: 14336 Facility Num: 92474 AI Number: 345145832002139	***8911 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***R971 / 6***	***2958***
ROTP 2 PROPERTY Facility Status: INACTIVE Facility Id: 62049 Facility Num: 97328 AI Number: 300473512002075	401 W 6TH ST	WNW 0 - 1/8 (0.012 mi.)	DE976 / 11	2993
PAYLESS GAS 866 Facility Status: INACTIVE Facility Id: 18930 Facility Num: 52591 AI Number: 185672102002150	6608 N LAMAR BLVD	WNW 0 - 1/8 (0.012 mi.)	AG989 / 6	3021
FUEL DISTRIBUTORS Facility Status: INACTIVE Facility Id: 44619 Facility Num: 52614 AI Number: 577632612002241	6608 N LAMAR BLVD	WNW 0 - 1/8 (0.012 mi.)	AG990 / 6	3038
FAMOUS FOOD MART Facility Status: ACTIVE Facility Id: 19074 Facility Num: 75960 AI Number: 781702572002150	***6301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***AI992 / 6***	***3045***
A & R CORNER STORE Facility Status: INACTIVE Facility Id: 36621 Facility Num: 87030 AI Number: 675373862002152	***4413 GUADALUPE ST***	***ESE 0 - 1/8 (0.012 mi.)***	***HW1000 / 8***	***3082***
TACO BELL Facility Status: INACTIVE	***2801 GUADALUPE ST***	***ENE 0 - 1/8 (0.012 mi.)***	***HY1006 / 11***	***3181***

Facility Id: 48720 Facility Num: 83898 AI Number: 480150662002156				
TEXACO Facility Status: INACTIVE Facility Id: 23200 Facility Num: 79651 AI Number: 101654032002207	***2000 E RIVERSIDE DR***	***NE 0 - 1/8 (0.012 mi.)***	***FO1017 / 14***	***3197***
WATKINS PROPERTY Facility Status: INACTIVE Facility Id: 60728 Facility Num: 91006 AI Number: 238518232002053	***3400 GUADALUPE ST***	***WNW 0 - 1/8 (0.012 mi.)***	***IB1018 / 8***	***3211***
RAINBO BAKING Facility Status: INACTIVE Facility Id: 1994 Facility Num: 74830 AI Number: 34362792002075	***6534 S CONGRESS AVE***	***WNW 0 - 1/8 (0.012 mi.)***	***HL1021 / 17***	***3225***
AUSTIN COMMUNITY COL Facility Status: INACTIVE Facility Id: 4105 Facility Num: 42803 AI Number: 99496822002054	5712 E RIVERSIDE DR	NNE 0 - 1/8 (0.013 mi.)	1041 / 15	3263
SHOP N CARRY FOODS Facility Status: INACTIVE Facility Id: 10996 Facility Num: 43997 AI Number: 16623652002053	***8422 S CONGRESS AVE***	***WNW 0 - 1/8 (0.013 mi.)***	***HO1044 / 21***	***3281***
GASKINS REAL ESTATE Facility Status: INACTIVE Facility Id: 50186 Facility Num: 81816 AI Number: 669559422002053	***2718 GUADALUPE ST***	***WSW 0 - 1/8 (0.013 mi.)***	***BM1055 / 11***	***3315***
FLAMINGO AUTOMOTIVE Facility Status: INACTIVE Facility Id: 61457 Facility Num: 91570 AI Number: 299697752002053	***3512 GUADALUPE ST***	***WNW 0 - 1/8 (0.013 mi.)***	***IC1062 / 8***	***3360***
RYDER TRUCK RENTAL 0 Facility Status: ACTIVE Facility Id: 2651 Facility Num: 75233 AI Number: 941807592002138	***8305 N LAMAR BLVD***	***SE 0 - 1/8 (0.013 mi.)***	***W1077 / 6***	***3383***
LAMAR FOOD MARKET Facility Status: ACTIVE Facility Id: 45723 Facility Num: 74633 AI Number: 714575392002053	***10810 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***HV1081 / 3***	***3416***
DIRTY MARTINS PLACE Facility Status: INACTIVE Facility Id: 77600	2808 GUADALUPE ST	WSW 0 - 1/8 (0.013 mi.)	HY1082 / 11	3444

Facility Num: 119395 AI Number: 125343862011158				
PACIFIC SOUTHWEST BA Facility Status: INACTIVE Facility Id: 62968 Facility Num: 91605 AI Number: 141766552002150	***907 S CONGRESS AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***EQ1087 / 14***	***3458***
METRO STAR GROCERY Facility Status: INACTIVE Facility Id: 11312 Facility Num: 87016 AI Number: 621618552002053	***10304 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***IF1091 / 3***	***3468***
THREADGILLS Facility Status: INACTIVE Facility Id: 66132 Facility Num: 99022 AI Number: 314713362002053	***6416 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***IE1097 / 6***	***3483***
NORTH LAMAR SERVICE Facility Status: ACTIVE Facility Id: 10901 Facility Num: 91891 AI Number: 86402942002154	***11100 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***I1102 / 3***	***3491***
LAMAR CORNER STORE Facility Status: ACTIVE Facility Id: 11311 Facility Num: 42486 AI Number: 874694062002068	***7545 N LAMAR BLVD***	***ESE 0 - 1/8 (0.013 mi.)***	***Z1116 / 6***	***3538***
FIRE STATION 22 Facility Status: INACTIVE Facility Id: 18167 Facility Num: 37571 AI Number: 782758622002138	***5307 E RIVERSIDE DR***	***SSW 0 - 1/8 (0.013 mi.)***	***1119 / 15***	***3567***
VACANT PROPERTY Facility Status: INACTIVE Facility Id: 63416 Facility Num: 94336 AI Number: 351393622002075	***11902 N LAMAR BLVD***	***WNW 0 - 1/8 (0.014 mi.)***	***1121 / 4***	***3574***
JACK BROWN CLEANERS Facility Status: INACTIVE Facility Id: 23302 Facility Num: 59332 AI Number: 387713422002207	***2215 S CONGRESS AVE***	***E 0 - 1/8 (0.014 mi.)***	***FQ1129 / 14***	***3597***
CONOCO FOOD MART Facility Status: INACTIVE Facility Id: 11000 Facility Num: 80208 AI Number: 15491982002054	***6214 E RIVERSIDE DR***	***NNE 0 - 1/8 (0.014 mi.)***	***GQ1142 / 15***	***3666***
LUCKY FOOD STORE Facility Status: ACTIVE Facility Id: 11001 Facility Num: 67437	***5800 S CONGRESS AVE***	***WNW 0 - 1/8 (0.014 mi.)***	***HJ1157 / 17***	***3717***

AI Number: 890794852002068				
U S P & F O FOR TX Facility Status: INACTIVE Facility Id: 34980 Facility Num: 63753 AI Number: 958609872002156	35TH	ESE 0 - 1/8 (0.014 mi.)	1159 / 8	3745
7 ELEVEN STORE 36653 Facility Status: ACTIVE Facility Id: 15562 Facility Num: 54258 AI Number: 486505372002053	***5630 N LAMAR BLVD***	***WNW 0 - 1/8 (0.014 mi.)***	***AL1166 / 8***	***3769***
WRECKER SERVICE Facility Status: INACTIVE Facility Id: 63402 Facility Num: 94317 AI Number: 116737792002053	***4506 S CONGRESS AVE***	***WNW 0 - 1/8 (0.014 mi.)***	***HD1181 / 17***	***3813***
LAIDLAW TRANSIT Facility Status: INACTIVE Facility Id: 10025 Facility Num: 67435 AI Number: 449270902002117	***4300 S CONGRESS***	***WNW 0 - 1/8 (0.015 mi.)***	***GY1185 / 17***	***3817***
TERRY E BOOTH Facility Status: INACTIVE Facility Id: 64808 Facility Num: 96369 AI Number: 998564422002053	508 E 6TH ST	SW 0 - 1/8 (0.015 mi.)	DR1216 / 11	3866
TUNEUP MASTERS STORE Facility Status: INACTIVE Facility Id: 24078 Facility Num: 39536 AI Number: 138669272002138	***5624 N LAMAR BLVD***	***WNW 0 - 1/8 (0.016 mi.)***	***IQ1231 / 8***	***3889***
AUSTIN CAT & DOG HOS Facility Status: INACTIVE Facility Id: 62072 Facility Num: 92277 AI Number: 129549932002053	***506 E 5TH ST***	***SW 0 - 1/8 (0.016 mi.)***	***DU1235 / 11***	***3916***
JIFFY LUBE Facility Status: INACTIVE Facility Id: 45667 Facility Num: 77183 AI Number: 683025632002149	***3809 GUADALUPE ST***	***ESE 0 - 1/8 (0.016 mi.)***	***BA1253 / 8***	***3939***
CECILS AUTO TRIM Facility Status: INACTIVE Facility Id: 45597 Facility Num: 77158 AI Number: 473715352002053	***4926 N LAMAR BLVD***	***WNW 0 - 1/8 (0.016 mi.)***	***AR1255 / 8***	***3954***
7-ELEVEN 16996 Facility Status: ACTIVE Facility Id: 7175 Facility Num: 46177 AI Number: 730180392002117	***2600 GUADALUPE ST***	***W 0 - 1/8 (0.016 mi.)***	***BO1259 / 11***	***3963***
ORACLE-AUSTIN DATA C	***11400 N LAMAR BLVD***	***WNW 0 - 1/8 (0.016 mi.)***	***F1262 / 3***	***4000***

Facility Status: ACTIVE Facility Id: 60088 Facility Num: 90583 AI Number: 58532632003161				
DIAMOND SHAMROCK 236 Facility Status: INACTIVE Facility Id: 45204 Facility Num: 74590 AI Number: 763051542002150	***1620 E RIVERSIDE DR***	***NE 0 - 1/8 (0.017 mi.)***	***FF1266 / 14***	***4032***
QUIKTRIP 4125 Facility Status: ACTIVE Facility Id: 92268 Facility Num: 137355 AI Number: 916473552021313	4402 S CONGRESS AVE	WNW 0 - 1/8 (0.017 mi.)	HA1285 / 17	4080
PETRICK FACILITY Facility Status: INACTIVE Facility Id: 50071 Facility Num: 83531 AI Number: 35705402002205	***1611 GUADALUPE ST***	***ESE 0 - 1/8 (0.018 mi.)***	***CJ1293 / 11***	***4138***
DEAN JOHNSTON Facility Status: INACTIVE Facility Id: 59396 Facility Num: 89819 AI Number: 893242782002139	207 SAN JACINTO BLVD	SSW 0 - 1/8 (0.018 mi.)	EA1298 / 11	4147
THURMAN WAREHOUSE Facility Status: INACTIVE Facility Id: 11319 Facility Num: 89964 AI Number: 998500812002053	***4714 S CONGRESS AVE***	***WNW 0 - 1/8 (0.018 mi.)***	***IU1299 / 17***	***4154***
STONES TEXACO Facility Status: INACTIVE Facility Id: 22264 Facility Num: 58888 AI Number: 886720552002053	***2300 S CONGRESS AVE***	***W 0 - 1/8 (0.018 mi.)***	***FQ1302 / 14***	***4161***
THE OIL EXCHANGE Facility Status: INACTIVE Facility Id: 21834 Facility Num: 88501 AI Number: 343251102003095	***1806 E RIVERSIDE DR***	***ENE 0 - 1/8 (0.019 mi.)***	***FI1318 / 14***	***4185***
DOC HOLLIDAYS PAWN S Facility Status: INACTIVE Facility Id: 64039 Facility Num: 94975 AI Number: 412586332002053	7544 N LAMAR BLVD	WNW 0 - 1/8 (0.019 mi.)	Z1332 / 6	4205
EXXON SS6 0015 Facility Status: INACTIVE Facility Id: 26003 Facility Num: 47901 AI Number: 87570382002175	***343 S CONGRESS AVE***	***NE 0 - 1/8 (0.019 mi.)***	***EJ1337 / 14***	***4210***
FLOYDS AUTO SALES & Facility Status: INACTIVE	***5253 N LAMAR BLVD***	***ESE 0 - 1/8 (0.019 mi.)***	***AO1341 / 8***	***4241***

Facility Id: 15637 Facility Num: 54280 AI Number: 562048392002149				
AUSTINS TINT CONNECT Facility Status: INACTIVE Facility Id: 67897 Facility Num: 102620 AI Number: 624330482002118	5319 N LAMAR BLVD	ESE 0 - 1/8 (0.020 mi.)	AO1362 / 8	4271
PRET MANGER Facility Status: ACTIVE Facility Id: 45524 Facility Num: 40958 AI Number: 548661292002205	***5301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.020 mi.)***	***AO1369 / 8***	***4308***
MOBIL SS 12 D93 Facility Status: INACTIVE Facility Id: 17726 Facility Num: 78961 AI Number: 308662722002053	***2401 S CONGRESS AVE***	***SE 0 - 1/8 (0.020 mi.)***	***FU1374 / 14***	***4341***
FIRE STATION 3 Facility Status: INACTIVE Facility Id: 18163 Facility Num: 37567 AI Number: 246804042002138	201 W 30TH ST	ENE 0 - 1/8 (0.020 mi.)	1378 / 11	4358
JOHN H WINTERS Facility Status: ACTIVE Facility Id: 76046 Facility Num: 116668 AI Number: 518333592003344	***701 W 51ST ST***	***ESE 0 - 1/8 (0.020 mi.)***	***AQ1380 / 8***	***4363***
ANTOINE GROCERY Facility Status: INACTIVE Facility Id: 65829 Facility Num: 98004 AI Number: 404520522002053	***11209 N LAMAR BLVD***	***ESE 0 - 1/8 (0.021 mi.)***	***IS1395 / 3***	***4415***
FINLEY Facility Status: INACTIVE Facility Id: 53521 Facility Num: 83382 AI Number: 599745282002053	***509 E 5TH ST***	***SW 0 - 1/8 (0.022 mi.)***	***DU1411 / 11***	***4448***
7-ELEVEN 24008 Facility Status: ACTIVE Facility Id: 7169 Facility Num: 46171 AI Number: 751041712002117	***5101 N LAMAR BLVD***	***ESE 0 - 1/8 (0.022 mi.)***	***AQ1417 / 8***	***4457***
LOOMIS ARMORED AUSTI Facility Status: INACTIVE Facility Id: 36668 Facility Num: 51389 AI Number: 707116112002117	78 EAST AVE	ESE 0 - 1/8 (0.022 mi.)	JF1432 / 14	4552
EVANS TEXACO Facility Status: INACTIVE Facility Id: 18769	***4712 S CONGRESS AVE***	***WNW 0 - 1/8 (0.022 mi.)***	***IU1433 / 17***	***4556***

Facility Num: 56596 AI Number: 13656422002053				
SPEEDYS Facility Status: ACTIVE Facility Id: 29155 Facility Num: 75966 AI Number: 968713862002057	***6301 E RIVERSIDE DR***	***SSW 0 - 1/8 (0.023 mi.)***	***GQ1452 / 15***	***4579***
TEXAS FOOD MART Facility Status: ACTIVE Facility Id: 19604 Facility Num: 75963 AI Number: 632026612002208	***720 LAMAR PL***	***ESE 0 - 1/8 (0.023 mi.)***	***JG1453 / 6***	***4610***
MS EXPRESS 901 Facility Status: INACTIVE Facility Id: 45192 Facility Num: 74578 AI Number: 784466262002075	***2105 S CONGRESS AVE***	***ESE 0 - 1/8 (0.023 mi.)***	***FK1459 / 14***	***4637***
AUSTIN QUALITY CAR W Facility Status: INACTIVE Facility Id: 149 Facility Num: 38071 AI Number: 391536442002053	***3120 GUADALUPE ST***	***WNW 0 - 1/8 (0.023 mi.)***	***JK1474 / 8***	***4681***
WILLIAM B TRAVIS Facility Status: INACTIVE Facility Id: 76047 Facility Num: 116669 AI Number: 597333752003344	***1701 CONGRESS AVE***	***WNW 0 - 1/8 (0.023 mi.)***	***JL1477 / 11***	***4694***
7-ELEVEN 12683 Facility Status: INACTIVE Facility Id: 7170 Facility Num: 46172 AI Number: 430339092002120	***808 W KOENIG LN***	***WNW 0 - 1/8 (0.023 mi.)***	***AL1490 / 8***	***4724***
CAPITAL FOOD STOP 2 Facility Status: ACTIVE Facility Id: 36623 Facility Num: 74020 AI Number: 455541512002054	***8201 N LAMAR BLVD***	***SE 0 - 1/8 (0.023 mi.)***	***JM1494 / 6***	***4747***
PATS LAWNMOWER SERVI Facility Status: INACTIVE Facility Id: 35789 Facility Num: 91913 AI Number: 583605162002053	***7205 N LAMAR BLVD***	***ESE 0 - 1/8 (0.024 mi.)***	***AB1499 / 6***	***4775***
PRIME MART Facility Status: ACTIVE Facility Id: 7164 Facility Num: 46166 AI Number: 695703732002116	***12430 N LAMAR BLVD***	***W 0 - 1/8 (0.024 mi.)***	***JN1502 / 2***	***4784***
SOCO CENTER Facility Status: ACTIVE Facility Id: 45201 Facility Num: 74587	***3630 S CONGRESS AVE***	***WNW 0 - 1/8 (0.025 mi.)***	***GM1513 / 14***	***4826***

AI Number: 231571092002259				
N LAMAR U HAUL CTR Facility Status: INACTIVE Facility Id: 36409 Facility Num: 43089 AI Number: 966374862002075	***5412 N LAMAR BLVD***	***WNW 0 - 1/8 (0.025 mi.)***	***AM1519 / 8***	***4872***
TEXACO Facility Status: INACTIVE Facility Id: 23190 Facility Num: 79642 AI Number: 610852742002138	***1900 GUADALUPE ST***	***W 0 - 1/8 (0.025 mi.)***	***CD1529 / 11***	***4886***
STAR STOP 73 Facility Status: ACTIVE Facility Id: 62266 Facility Num: 95659 AI Number: 991250192002156	***1919 S PLEASANT VALL***	***NE 0 - 1/8 (0.025 mi.)***	***GF1540 / 15***	***4927***
COTHRONS TEXACO SERV Facility Status: INACTIVE Facility Id: 25280 Facility Num: 61941 AI Number: 40514062002053	***701 W 6TH ST***	***WNW 0 - 1/8 (0.025 mi.)***	***DA1546 / 11***	***4963***
CEN TEX NISSAN Facility Status: INACTIVE Facility Id: 40885 Facility Num: 93163 AI Number: 963236982002156	***1400 S CONGRESS AVE***	***WNW 0 - 1/8 (0.025 mi.)***	***EZ1548 / 14***	***4971***
GIANT FOOD MART Facility Status: ACTIVE Facility Id: 13885 Facility Num: 93401 AI Number: 403738012002155	***8700 N LAMAR BLVD***	***NW 0 - 1/8 (0.025 mi.)***	***T1553 / 6***	***4993***
DIAMOND SHAMROCK 963 Facility Status: INACTIVE Facility Id: 45250 Facility Num: 74625 AI Number: 504752212002149	***3706 GUADALUPE ST***	***WNW 0 - 1/8 (0.026 mi.)***	***BB1564 / 8***	***5045***
EXPRESS FOOD MART Facility Status: ACTIVE Facility Id: 34932 Facility Num: 77360 AI Number: 991316872002255	***10500 N LAMAR BLVD***	***WNW 0 - 1/8 (0.026 mi.)***	***JR1566 / 3***	***5064***
7-ELEVEN 30467 Facility Status: INACTIVE Facility Id: 45165 Facility Num: 46524 AI Number: 866539252002117	***10111 N LAMAR BLVD***	***ESE 0 - 1/8 (0.026 mi.)***	***JS1573 / 3***	***5097***
HEB 628 Facility Status: ACTIVE Facility Id: 55951 Facility Num: 48586 AI Number: 764641652002175	***2512 E RIVERSIDE DR***	***NE 0 - 1/8 (0.026 mi.)***	***HS1578 / 15***	***5128***
7-ELEVEN 25445	***8900 N LAMAR BLVD***	***WNW 0 - 1/8 (0.026 mi.)***	***R1593 / 6***	***5198***

Facility Status: ACTIVE Facility Id: 7161 Facility Num: 46163 AI Number: 490562012002116				
STOP N SAVE 3 Facility Status: ACTIVE Facility Id: 39565 Facility Num: 87640 AI Number: 554547622002054	***1800 BURTON DR***	***ENE 0 - 1/8 (0.026 mi.)***	***1595 / 14***	***5226***
YOUNG & PRATT Facility Status: INACTIVE Facility Id: 22893 Facility Num: 59427 AI Number: 775576292002053	***702 E 3RD ST***	***WNW 0 - 1/8 (0.027 mi.)***	***JT1622 / 11***	***5269***
RIVERSIDE CHEVRON Facility Status: ACTIVE Facility Id: 33141 Facility Num: 45109 AI Number: 263595602003195	***400 S CONGRESS AVE***	***WNW 0 - 1/8 (0.027 mi.)***	***EJ1640 / 14***	***5443***
AUSTIN TOYOTA Facility Status: INACTIVE Facility Id: 44471 Facility Num: 72689 AI Number: 974697452002154	***1127 W 6TH STREET***	***WNW 0 - 1/8 (0.028 mi.)***	***DC1657 / 11***	***5481***
CITY OF AUSTIN ELECT Facility Status: INACTIVE Facility Id: 18149 Facility Num: 37553 AI Number: 390006192002156	300 WEST AVE	WNW 0 - 1/8 (0.028 mi.)	DL1670 / 11	5520
FIRST STATE BANK TOW Facility Status: INACTIVE Facility Id: 34800 Facility Num: 81132 AI Number: 839733452002053	***400 W 15TH ST STE 71***	***WNW 0 - 1/8 (0.028 mi.)***	***CM1673 / 11***	***5526***
7-ELEVEN STORE 36642 Facility Status: ACTIVE Facility Id: 76634 Facility Num: 117664 AI Number: 513525442004222	***7715 E BEN WHITE BLV***	***WNW 0 - 1/8 (0.028 mi.)***	***JW1678 / 19***	***5533***
HILL ELECTRIC Facility Status: INACTIVE Facility Id: 68149 Facility Num: 102902 AI Number: 517604132002053	***10100 N LAMAR BLVD***	***WNW 0 - 1/8 (0.029 mi.)***	***L1690 / 3***	***5577***
ROBERT E JOHNSON BUI Facility Status: ACTIVE Facility Id: 76048 Facility Num: 116670 AI Number: 635333862003344	***1501 CONGRESS AVE***	***WNW 0 - 1/8 (0.029 mi.)***	***CN1692 / 11***	***5581***
CENTRAL TEXAS EQUIPM Facility Status: INACTIVE	***127 E RIVERSIDE DR***	***SW 0 - 1/8 (0.029 mi.)***	***EM1694 / 14***	***5591***

Facility Id: 14486 Facility Num: 53158 AI Number: 826592582002053				
TEXAS EMPLOYMENT COM Facility Status: INACTIVE Facility Id: 53740 Facility Num: 83550 AI Number: 69692932002053	***101 E 15TH ST***	***ESE 0 - 1/8 (0.030 mi.)***	***CN1701 / 11***	***5615***
7-ELEVEN 20079 Facility Status: INACTIVE Facility Id: 7124 Facility Num: 46131 AI Number: 559037272002139	***6702 S CONGRESS AVE***	***WNW 0 - 1/8 (0.030 mi.)***	***JZ1706 / 17***	***5635***
JD MARKET 5 Facility Status: ACTIVE Facility Id: 84265 Facility Num: 129133 AI Number: 334464502011350	***7310 E RIVERSIDE DR***	***NE 0 - 1/8 (0.030 mi.)***	***1716 / 19***	***5650***
BEVERAGE BARN Facility Status: ACTIVE Facility Id: 19617 Facility Num: 56677 AI Number: 330727352002225	***2001 E RIVERSIDE DR***	***SW 0 - 1/8 (0.031 mi.)***	***KA1721 / 14***	***5676***
TENNYSON 836 Facility Status: ACTIVE Facility Id: 19360 Facility Num: 76477 AI Number: 273654602002150	***11409 N LAMAR BLVD***	***ESE 0 - 1/8 (0.031 mi.)***	***KB1723 / 3***	***5714***
7 ELEVEN 38289 Facility Status: ACTIVE Facility Id: 90329 Facility Num: 135435 AI Number: 925332512018354	***701 W BRAKER LN***	***ESE 0 - 1/8 (0.031 mi.)***	***IS1732 / 3***	***5725***
SHELL MINI MART 2 Facility Status: ACTIVE Facility Id: 69933 Facility Num: 106201 AI Number: 667025812002208	***3906 S CONGRESS AVE***	***WNW 0 - 1/8 (0.032 mi.)***	***KD1738 / 14***	***5741***
CONGRESS CHEVRON Facility Status: ACTIVE Facility Id: 44057 Facility Num: 72523 AI Number: 9108872002139	***3909 S CONGRESS AVE***	***ESE 0 - 1/8 (0.032 mi.)***	***KE1746 / 14***	***5771***
TEXAS SCHOOL FOR THE Facility Status: ACTIVE Facility Id: 48216 Facility Num: 79920 AI Number: 344705912002155	***1102 S CONGRESS AVE***	***ESE 0 - 1/8 (0.032 mi.)***	***KF1748 / 14***	***5801***
GREASERS Facility Status: INACTIVE Facility Id: 40439	***8415 N LAMAR BLVD***	***SE 0 - 1/8 (0.032 mi.)***	***1753 / 6***	***5875***

Facility Num: 89549 AI Number: 720614302002186				
7-ELEVEN STORE 36588 Facility Status: ACTIVE Facility Id: 72244 Facility Num: 109944 AI Number: 914631072002175	***1100 W PARMER LN***	***W 0 - 1/8 (0.033 mi.)***	***KI1760 / 2***	***5887***
VACANT PROPERTY Facility Status: INACTIVE Facility Id: 80009 Facility Num: 124160 AI Number: 685138232011075	***501 BRAZOS ST***	***SSW 0 - 1/8 (0.033 mi.)***	***DP1772 / 11***	***5924***
ALL STAR GROCERY 1 Facility Status: ACTIVE Facility Id: 10998 Facility Num: 43998 AI Number: 524005172002069	***4619 S CONGRESS AVE***	***ESE 0 - 1/8 (0.034 mi.)***	***KK1783 / 17***	***5940***
NORTH LAMAR QUICK ST Facility Status: ACTIVE Facility Id: 45196 Facility Num: 74582 AI Number: 55494242002054	***8545 N LAMAR BLVD***	***SE 0 - 1/8 (0.034 mi.)***	***KM1787 / 6***	***5970***
GPM STORE 4567 Facility Status: ACTIVE Facility Id: 45206 Facility Num: 74592 AI Number: 278615832002149	***2001 BASTROP HWY E***	***NNE 0 - 1/8 (0.034 mi.)***	***1792 / 20***	***5996***
TWIN LIQUORS Facility Status: INACTIVE Facility Id: 64661 Facility Num: 95995 AI Number: 346615062002053	519 E 7TH ST	NE 0 - 1/8 (0.034 mi.)	IL1795 / 11	6026
BEN HIBBETTS Facility Status: INACTIVE Facility Id: 23280 Facility Num: 87639 AI Number: 214155852002156	1725 E RIVERSIDE DR	WSW 0 - 1/8 (0.035 mi.)	KN1802 / 14	6037
ANN STUMPF Facility Status: INACTIVE Facility Id: 53738 Facility Num: 83552 AI Number: 582685532002053	***2815 FRUTH ST***	***ENE 0 - 1/8 (0.036 mi.)***	***BK1815 / 11***	***6071***
AUSTIN MUNICIPAL BUI Facility Status: INACTIVE Facility Id: 65899 Facility Num: 98273 AI Number: 44550902002138	***124 W 8TH ST***	***WNW 0 - 1/8 (0.037 mi.)***	***KT1841 / 11***	***6090***
7-ELEVEN STORE 36591 Facility Status: ACTIVE Facility Id: 72099 Facility Num: 109721	***201 W BEN WHITE BLVD***	***WNW 0 - 1/8 (0.038 mi.)***	***GS1850 / 14***	***6102***

AI Number: 658642402002175				
ACC BOOK STORE Facility Status: INACTIVE Facility Id: 60134 Facility Num: 77533 AI Number: 562848142002150	***801 W 12TH ST***	***WNW 0 - 1/8 (0.038 mi.)***	***JA1852 / 11***	***6146***
IMPORT CAR REPAIR Facility Status: INACTIVE Facility Id: 25401 Facility Num: 62043 AI Number: 581654322002205	***10631 N LAMAR BLVD***	***ESE 0 - 1/8 (0.038 mi.)***	***KV1860 / 3***	***6157***
GEORGES WAGON WORKS Facility Status: INACTIVE Facility Id: 48177 Facility Num: 79851 AI Number: 692795742002057	***1311 S 1ST ST***	***WNW 0 - 1/8 (0.038 mi.)***	***1861 / 14***	***6163***
PERRY BROOKS BLDG Facility Status: INACTIVE Facility Id: 62765 Facility Num: 93269 AI Number: 539648022002053	***720 BRAZOS ST***	***ESE 0 - 1/8 (0.038 mi.)***	***KW1862 / 11***	***6166***
7-ELEVEN 19097 Facility Status: INACTIVE Facility Id: 7143 Facility Num: 46147 AI Number: 364418012002118	***1705 S LAKESHORE BLV***	***ENE 0 - 1/8 (0.039 mi.)***	***KX1866 / 14***	***6185***
FIRST NATIONAL BANK Facility Status: INACTIVE Facility Id: 58316 Facility Num: 81968 AI Number: 208607612004211	***12800 N LAMAR BLVD***	***W 0 - 1/8 (0.039 mi.)***	***1868 / 2***	***6211***
206-214 CONGRESS AVE Facility Status: INACTIVE Facility Id: 63160 Facility Num: 94024 AI Number: 859612182002155	***206 CONGRESS AVE***	***SSW 0 - 1/8 (0.039 mi.)***	***KH1873 / 11***	***6216***
SUPERIOR DAIRIES Facility Status: INACTIVE Facility Id: 31210 Facility Num: 50478 AI Number: 148440462002186	***600 E 1ST ST***	***WNW 0 - 1/8 (0.039 mi.)***	***LB1878 / 11***	***6240***
TEXAS STATE ASSO OF Facility Status: INACTIVE Facility Id: 66434 Facility Num: 99653 AI Number: 94624752002053	***1000 BRAZOS ST***	***ESE 0 - 1/8 (0.040 mi.)***	***LC1882 / 11***	***6251***
QUAD FOOD MART Facility Status: ACTIVE Facility Id: 39561 Facility Num: 61081 AI Number: 88761582002149	***628 E OLTORF ST***	***SE 0 - 1/8 (0.040 mi.)***	***LD1886 / 14***	***6266***
TURK EQUIPMENT	400 NUECES ST	ESE 0 - 1/8 (0.040 mi.)	LE1895 / 11	6306

Facility Status: INACTIVE Facility Id: 71661 Facility Num: 109044 AI Number: 731510472002053				
7-ELEVEN STORE 38608 Facility Status: ACTIVE Facility Id: 85082 Facility Num: 130236 AI Number: 403623762012289	***105 E STASSNEY LN***	***ESE 0 - 1/8 (0.042 mi.)***	***LL1916 / 17***	***6375***
ALEX & IDA DOCHEN TR Facility Status: INACTIVE Facility Id: 29963 Facility Num: 64551 AI Number: 934446672005049	500 E 7TH ST	NNE 0 - 1/8 (0.043 mi.)	IL1922 / 11	6400
EXXON RS 69404 Facility Status: INACTIVE Facility Id: 58226 Facility Num: 48602 AI Number: 944487162002054	***6721 S CONGRESS AVE***	***ESE 0 - 1/8 (0.045 mi.)***	***LP1946 / 17***	***6427***
WESTERN AUTO Facility Status: INACTIVE Facility Id: 53408 Facility Num: 72446 AI Number: 384186332002156	***9316 N LAMAR BLVD***	***WNW 0 - 1/8 (0.046 mi.)***	***1966 / 6***	***6456***
F M PAULS CONCRETE C Facility Status: INACTIVE Facility Id: 30301 Facility Num: 64780 AI Number: 421520772002053	***6506 SHIRLEY AVE***	***ESE 0 - 1/8 (0.046 mi.)***	***LR1967 / 6***	***6460***
AUSTEX INTERIORS Facility Status: INACTIVE Facility Id: 75578 Facility Num: 115807 AI Number: 759577712003020	***6910 SHIRLEY AVE***	***ESE 0 - 1/8 (0.046 mi.)***	***IZ1978 / 6***	***6476***
FORMER DOWNTOWN AUTO Facility Status: INACTIVE Facility Id: 83660 Facility Num: 128034 AI Number: 763485032010133	800 W 6TH ST	WNW 0 - 1/8 (0.048 mi.)	LX1997 / 11	6491
STOP N GO MARKET 210 Facility Status: INACTIVE Facility Id: 44924 Facility Num: 61297 AI Number: 641844092002156	***111 W WILLIAM CANNON***	***WNW 0 - 1/8 (0.048 mi.)***	***LZ2006 / 17***	***6503***
1601 S 1ST ST Facility Status: INACTIVE Facility Id: 68903 Facility Num: 104324 AI Number: 401396472002075	1601 S 1ST ST	WNW 0 - 1/8 (0.049 mi.)	MB2013 / 14	6520
STOP N GO 2126 Facility Status: INACTIVE	***1516 TINNIN FORD RD***	***NE 0 - 1/8 (0.050 mi.)***	***MF2029 / 14***	***6548***

Facility Id: 39564 Facility Num: 61084 AI Number: 873774132002149				
GOODYEAR TIRE & RUBB Facility Status: INACTIVE Facility Id: 13174 Facility Num: 52267 AI Number: 875653592002241	115 E OLTORF ST	SE 0 - 1/8 (0.050 mi.)	MG2035 / 14	6571
FAST STOP 11 Facility Status: INACTIVE Facility Id: 45817 Facility Num: 93097 AI Number: 705285312002156	***5526 S CONGRESS AVE***	***WNW 0 - 1/8 (0.050 mi.)***	***MH2041 / 17***	***6602***
FORMER GLO FACILITY Facility Status: INACTIVE Facility Id: 63213 Facility Num: 94056 AI Number: 988546812002053	***421 E CESAR CHAVEZ S***	***ESE 0 - 1/8 (0.052 mi.)***	***KS2062 / 11***	***6622***
AUSTIN GREENWOOD CON Facility Status: ACTIVE Facility Id: 19352 Facility Num: 76469 AI Number: 101678402002150	***909 COLORADO ST***	***WNW 0 - 1/8 (0.052 mi.)***	***KL2073 / 11***	***6631***
BROADDUS CHEVRON RIV Facility Status: ACTIVE Facility Id: 28644 Facility Num: 87650 AI Number: 133264732002156	***30 IH 35 N***	***NE 0 - 1/8 (0.052 mi.)***	***MO2081 / 14***	***6662***
APPLE TRACT Facility Status: INACTIVE Facility Id: 4424 Facility Num: 93952 AI Number: 923561262002118	811-814 W 6TH	WNW 0 - 1/8 (0.053 mi.)	LX2093 / 11	6698
JIMS CONOCO Facility Status: INACTIVE Facility Id: 46616 Facility Num: 43892 AI Number: 976819302002117	***1308 LAVACA ST***	***ESE 0 - 1/8 (0.053 mi.)***	***MR2114 / 11***	***6735***
MCMORRIS FORD Facility Status: INACTIVE Facility Id: 68769 Facility Num: 104079 AI Number: 611852022002204	808 W 6TH ST	WNW 0 - 1/8 (0.053 mi.)	LX2127 / 11	6752
7-ELEVEN 12705 Facility Status: ACTIVE Facility Id: 7176 Facility Num: 46178 AI Number: 868202132002117	***408 W 15TH ST***	***WNW 0 - 1/8 (0.055 mi.)***	***MV2173 / 11***	***6781***
ACUNAS Facility Status: INACTIVE Facility Id: 63471	511 E 1ST ST	WNW 0 - 1/8 (0.055 mi.)	LB2188 / 11	6822

Facility Num: 94402 AI Number: 227532802003204				
WESTERN AUTO Facility Status: INACTIVE Facility Id: 56892 Facility Num: 72449 AI Number: 947144012002139	***137 W OLTORF ST***	***SE 0 - 1/8 (0.057 mi.)***	***2212 / 14***	***6851***
BANK63 Facility Status: INACTIVE Facility Id: 60035 Facility Num: 85722 AI Number: 821192582002139	CORNER OF 3RD BRAZOS	E 0 - 1/8 (0.057 mi.)	ND2236 / 11	6864
BROYHILL FURNITURE I Facility Status: INACTIVE Facility Id: 278 Facility Num: 38200 AI Number: 380655572003100	118 E ALPINE RD	ESE 0 - 1/8 (0.058 mi.)	NE2241 / 14	6891
DIAMOND SHAMROCK 964 Facility Status: INACTIVE Facility Id: 45251 Facility Num: 74626 AI Number: 430756082002149	***806 W RUNDBERG LN***	***WNW 0 - 1/8 (0.058 mi.)***	***NF2245 / 6***	***6911***
WHITLEY CO Facility Status: INACTIVE Facility Id: 17140 Facility Num: 55609 AI Number: 973043482002118	***801 BRAZOS TO 805***	***ESE 0 - 1/8 (0.060 mi.)***	***NH2272 / 11***	***6938***
FIRESTONE TIRE & SER Facility Status: INACTIVE Facility Id: 64640 Facility Num: 95965 AI Number: 990489392002054	***311 S CONGRESS AVE***	***SSW 0 - 1/8 (0.061 mi.)***	***NA2281 / 11***	***6952***
FIRE STATION 1 Facility Status: INACTIVE Facility Id: 18162 Facility Num: 37566 AI Number: 241809322002138	***401 E 5TH ST***	***SSW 0 - 1/8 (0.062 mi.)***	***2290 / 11***	***6958***
DIANA D ZUMWALT ETAL Facility Status: INACTIVE Facility Id: 63598 Facility Num: 94508 AI Number: 192695222002053	***1214 S 1ST ST***	***WNW 0 - 1/8 (0.062 mi.)***	***KZ2298 / 14***	***6969***
EXXON 6 8082 Facility Status: INACTIVE Facility Id: 38970 Facility Num: 48518 AI Number: 148477152002133	2324 N ST MARYS	ESE 0 - 1/8 (0.063 mi.)	LC2308 / 11	6987
RAYMOND RAMSEY & JER Facility Status: INACTIVE Facility Id: 38370 Facility Num: 95529	2415 BASTROP HWY E	NE 0 - 1/8 (0.064 mi.)	NP2317 / 20	7011

AI Number: 106406952003091				
7-ELEVEN STORE 36656 Facility Status: INACTIVE Facility Id: 39556 Facility Num: 61076 AI Number: 482740612002149	***620 W 29TH ST***	***WNW 0 - 1/8 (0.065 mi.)***	***LU2332 / 8***	***7042***
CAPITOL TIRE SERVICE Facility Status: INACTIVE Facility Id: 70342 Facility Num: 106879 AI Number: 229724922002053	301 E 5TH ST	SSW 0 - 1/8 (0.066 mi.)	LH2351 / 11	7092
HERMINE WILDE ESTATE Facility Status: INACTIVE Facility Id: 65235 Facility Num: 96988 AI Number: 245712452002053	***311 E 5TH ST***	***SSW 0 - 1/8 (0.066 mi.)***	***LH2356 / 11***	***7108***
FOWLER ELECTRIC Facility Status: INACTIVE Facility Id: 53154 Facility Num: 83025 AI Number: 463556372002053	***621 E 7TH ST***	***NE 0 - 1/8 (0.066 mi.)***	***NZ2369 / 11***	***7119***
APPLE MART Facility Status: ACTIVE Facility Id: 85576 Facility Num: 130837 AI Number: 863537082013011	***2101 WICKERSHAM LN***	***NNE 0 - 1/8 (0.067 mi.)***	***2379 / 15***	***7125***
SS 6 7383 Facility Status: INACTIVE Facility Id: 26118 Facility Num: 47985 AI Number: 644602322002175	3807 EAST AVE	ENE 0 - 1/8 (0.067 mi.)	MQ2384 / 8	7154
COLD Facility Status: INACTIVE Facility Id: 38471 Facility Num: 69515 AI Number: 453081232002069	***704 W POWELL LN***	***SE 0 - 1/8 (0.067 mi.)***	***NR2392 / 6***	***7170***
SERVICE CENTER 2 Facility Status: INACTIVE Facility Id: 18143 Facility Num: 37547 AI Number: 100293522002133	***600 RIVER ST***	***WNW 0 - 1/8 (0.068 mi.)***	***OC2403 / 11***	***7198***
29WAT R907222 Facility Status: INACTIVE Facility Id: 57898 Facility Num: 85716 AI Number: 391476382002133	4TH & COLORADO	NNE 0 - 1/8 (0.069 mi.)	JY2419 / 11	7241
M D PHARMACY Facility Status: INACTIVE Facility Id: 63341 Facility Num: 89743 AI Number: 645740392002138	***1701 LAVACA ST***	***ESE 0 - 1/8 (0.070 mi.)***	***MP2432 / 11***	***7247***
AUSTIN FEDERAL COURT	***501 W 5TH ST***	***WNW 0 - 1/8 (0.070 mi.)***	***OF2434 / 11***	***7259***

Facility Status: ACTIVE Facility Id: 4268 Facility Num: 42960 AI Number: 105057982002156				
TRAVIS COUNTY JAIL Facility Status: INACTIVE Facility Id: 69575 Facility Num: 105588 AI Number: 334830632002138	***1000 SAN ANTONIO ST***	***WNW 0 - 1/8 (0.071 mi.)***	***2444 / 11***	***7293***
HOWARD MCELROY Facility Status: INACTIVE Facility Id: 61655 Facility Num: 92156 AI Number: 745575882002053	***6607 SHIRLEY AVE***	***ESE 0 - 1/8 (0.073 mi.)***	***OL2470 / 6***	***7312***
REFUEL 329 Facility Status: ACTIVE Facility Id: 26067 Facility Num: 90370 AI Number: 360663632002053	***31 N IH 35***	***NNE 0 - 1/8 (0.074 mi.)***	***OM2473 / 14***	***7319***
CONANN DEVELOPMENT Facility Status: INACTIVE Facility Id: 38382 Facility Num: 69458 AI Number: 38354502003197	***11220 N LAMAR BLVD***	***WNW 0 - 1/8 (0.075 mi.)***	***2478 / 3***	***7356***
ST EDWARDS UNIVERSIT Facility Status: ACTIVE Facility Id: 3075 Facility Num: 41670 AI Number: 149799842002068	***3001 S CONGRESS AVE***	***ESE 0 - 1/8 (0.075 mi.)***	***ON2482 / 14***	***7366***
CATHERINE UMSTATTD Facility Status: INACTIVE Facility Id: 64107 Facility Num: 96486 AI Number: 840192622002139	213 W 5TH ST	ESE 0 - 1/8 (0.077 mi.)	OQ2514 / 11	7431
COVERT BUICK Facility Status: INACTIVE Facility Id: 34978 Facility Num: 63751 AI Number: 696619102002156	***500 W 5TH ST***	***WNW 0 - 1/8 (0.078 mi.)***	***OF2524 / 11***	***7457***
SNAX BASKET 3 TX0297 Facility Status: ACTIVE Facility Id: 45191 Facility Num: 74577 AI Number: 618863602002149	***3515 N LAMAR BLVD***	***WNW 0 - 1/8 (0.078 mi.)***	***OT2527 / 8***	***7465***
BARBARA LOVELESS HAR Facility Status: INACTIVE Facility Id: 65060 Facility Num: 96772 AI Number: 955750042002053	1900 S 1ST ST	WNW 0 - 1/8 (0.078 mi.)	NI2530 / 14	7490
KOENIG LANE SERVICE Facility Status: ACTIVE	***901 W KOENIG LN***	***WNW 0 - 1/8 (0.080 mi.)***	***OE2547 / 8***	***7533***

Facility Id: 18147 Facility Num: 37551 AI Number: 965388942003098				
AUSTIN CONVENTION CE Facility Status: INACTIVE Facility Id: 72576 Facility Num: 110466 AI Number: 768044302002139	THIRD ST RED RIVER	WNW 0 - 1/8 (0.081 mi.)	MY2555 / 11	7568
E-Z PAWN SHOP Facility Status: INACTIVE Facility Id: 27903 Facility Num: 87055 AI Number: 939211052002156	99 N INTERSTATE 35	ESE 0 - 1/8 (0.081 mi.)	OX2560 / 11	7573
ABIA FOOD & FUEL Facility Status: ACTIVE Facility Id: 88987 Facility Num: 134101 AI Number: 242336952017055	***2901 SPIRIT OF TEXAS***	***WNW 0 - 1/8 (0.081 mi.)***	***2561 / 20***	***7579***
TRAM STOP Facility Status: ACTIVE Facility Id: 36614 Facility Num: 44057 AI Number: 453768712002205	***3201 N LAMAR BLVD***	***WNW 0 - 1/8 (0.082 mi.)***	***OZ2572 / 8***	***7610***
CIRCLE K 3245 Facility Status: INACTIVE Facility Id: 63547 Facility Num: 94478 AI Number: 405536852002054	3201 N LAMAR BLVD	WNW 0 - 1/8 (0.082 mi.)	OZ2576 / 8	7641
DON LLOYDS TEXACO Facility Status: INACTIVE Facility Id: 31749 Facility Num: 88679 AI Number: 497823672002148	***3317 N LAMAR BLVD***	***WNW 0 - 1/8 (0.083 mi.)***	***OY2580 / 8***	***7680***
NEW CONVENTION CENTE Facility Status: INACTIVE Facility Id: 56024 Facility Num: 85875 AI Number: 273193602002118	500 E 1ST ST	ESE 0 - 1/8 (0.084 mi.)	PB2598 / 11	7716
FIELDON BERRY Facility Status: INACTIVE Facility Id: 9297 Facility Num: 48902 AI Number: 803585412003204	501 W 3RD ST	ESE 0 - 1/8 (0.085 mi.)	OH2613 / 11	7742
PECAN FOOD MART Facility Status: INACTIVE Facility Id: 27721 Facility Num: 91702 AI Number: 175420552002154	***2101 S 1ST ST***	***WNW 0 - 1/8 (0.086 mi.)***	***OR2619 / 14***	***7760***
7-ELEVEN 39069 Facility Status: ACTIVE Facility Id: 70378	***6607 CIRCLE S RD***	***ESE 0 - 1/8 (0.086 mi.)***	***PF2622 / 17***	***7790***

Facility Num: 106940 AI Number: 219033542002139				
CHOTES CHEVRON Facility Status: INACTIVE Facility Id: 14803 Facility Num: 53664 AI Number: 409665082002053	***500 W MARTIN LUTHER***	***W 0 - 1/8 (0.086 mi.)***	***PA2627 / 11***	***7828***
SEAHOLM POWER PLANT Facility Status: INACTIVE Facility Id: 20546 Facility Num: 37574 AI Number: 650721302002325	***800 W CESAR CHAVEZ S***	***W 0 - 1/8 (0.086 mi.)***	***PG2632 / 11***	***7845***
HEART HOSPITAL OF AU Facility Status: ACTIVE Facility Id: 75714 Facility Num: 116064 AI Number: 181386552003092	***3801 N LAMAR BLVD***	***WNW 0 - 1/8 (0.086 mi.)***	***PH2635 / 8***	***7940***
TEXAS GOVERNORS MANS Facility Status: INACTIVE Facility Id: 84275 Facility Num: 129148 AI Number: 763330302011131	***1010 COLORADO ST***	***WNW 0 - 1/8 (0.088 mi.)***	***PK2655 / 11***	***7994***
AUSTIN SALES Facility Status: INACTIVE Facility Id: 53148 Facility Num: 83019 AI Number: 789662532002057	***825 PRAIRIE TRL***	***WNW 0 - 1/8 (0.089 mi.)***	***NN2668 / 3***	***8024***
PARKING GARAGE N Facility Status: ACTIVE Facility Id: 72718 Facility Num: 110705 AI Number: 517234992002117	***300 SAN ANTONIO ST***	***WNW 0 - 1/8 (0.091 mi.)***	***OH2692 / 11***	***8094***
WILSON OXYGEN & SUPP Facility Status: INACTIVE Facility Id: 41712 Facility Num: 73761 AI Number: 591379572002075	***150 E BEN WHITE BLVD***	***ESE 0 - 1/8 (0.092 mi.)***	***2703 / 14***	***8108***
SUB WAY Facility Status: INACTIVE Facility Id: 33138 Facility Num: 96758 AI Number: 839499742002053	***3724 N LAMAR BLVD***	***WNW 0 - 1/8 (0.096 mi.)***	***OT2739 / 8***	***8251***
RAILTON MANUFACTURIN Facility Status: INACTIVE Facility Id: 31174 Facility Num: 65383 AI Number: 779560952002053	***906 JUSTIN LN***	***WNW 0 - 1/8 (0.099 mi.)***	***PV2751 / 6***	***8270***
KXAN TV STUDIO Facility Status: ACTIVE Facility Id: 87736 Facility Num: 132862	***908 W MARTIN LUTHER***	***W 0 - 1/8 (0.100 mi.)***	***2759 / 11***	***8286***

AI Number: 399509062015167				
J J PICKLE FEDERAL O	***300 E 8TH ST***	***NNE 0 - 1/8 (0.101 mi.)***	***2763 / 11***	***8295***
Facility Status: ACTIVE				
Facility Id: 64191				
Facility Num: 95131				
AI Number: 542413032002117				
BRYANT AUTOMOTIVE	***505 W OLTORF ST***	***NW 0 - 1/8 (0.102 mi.)***	***PJ2764 / 14***	***8311***
Facility Status: INACTIVE				
Facility Id: 66474				
Facility Num: 99718				
AI Number: 220573582005250				
HOMESTEAD 451 CO XP3	***817 W NORTH LOOP BLV***	***WNW 0 - 1/8 (0.104 mi.)***	***QA2770 / 8***	***8326***
Facility Status: ACTIVE				
Facility Id: 19359				
Facility Num: 76476				
AI Number: 961528002002085				
NORTH LOOP SOC PORT	***819 W NO LOOP BLVD***	***WNW 0 - 1/8 (0.104 mi.)***	***QA2777 / 8***	***8371***
Facility Status: INACTIVE				
Facility Id: 20853				
Facility Num: 76709				
AI Number: 210615462002150				
CJC HOLDINGS	***7211 CIRCLE S RD***	***ESE 0 - 1/8 (0.104 mi.)***	***QB2780 / 17***	***8418***
Facility Status: INACTIVE				
Facility Id: 6726				
Facility Num: 45729				
AI Number: 125612372003202				
FOOD SPOT 2	***2538 ELMONT DR***	***NE 0 - 1/8 (0.105 mi.)***	***2783 / 15***	***8471***
Facility Status: INACTIVE				
Facility Id: 52881				
Facility Num: 82902				
AI Number: 634207132002139				
7 ELEVEN 16084	***1700 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.105 mi.)***	***QD2792 / 11***	***8498***
Facility Status: INACTIVE				
Facility Id: 32373				
Facility Num: 46477				
AI Number: 197240962002118				
FLOWER STATION	***3100 N LAMAR BLVD***	***WNW 0 - 1/8 (0.106 mi.)***	***QE2795 / 8***	***8504***
Facility Status: INACTIVE				
Facility Id: 46163				
Facility Num: 77530				
AI Number: 167609202002150				
STATE SERVICE STATIO	***1502 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.109 mi.)***	***PD2811 / 11***	***8554***
Facility Status: INACTIVE				
Facility Id: 48285				
Facility Num: 79981				
AI Number: 174454832005353				
UNIVERSITY SIGN SHOP	***2920 SAN JACINTO BLV***	***E 0 - 1/8 (0.111 mi.)***	***QM2821 / 11***	***8668***
Facility Status: INACTIVE				
Facility Id: 83456				
Facility Num: 127703				
AI Number: 972499192011158				
7-ELEVEN 36422	***717 E 7TH ST***	***ENE 0 - 1/8 (0.122 mi.)***	***QC2870 / 11***	***8759***

Facility Status: ACTIVE Facility Id: 17721 Facility Num: 95647 AI Number: 975573522003345				
TEXAS ALLERGY & ASTH Facility Status: INACTIVE Facility Id: 60525 Facility Num: 90921 AI Number: 70146672002139	4150 N LAMAR BLVD	NW 0 - 1/8 (0.123 mi.)	QW2877 / 8	8806
HAIS AUTOMOTIVE Facility Status: INACTIVE Facility Id: 28185 Facility Num: 88500 AI Number: 180421562003020	842 SAGEBRUSH DR	WNW 0 - 1/8 (0.125 mi.)	QZ2889 / 3	8831
RUDYS AUTOMOTIVE Facility Status: INACTIVE Facility Id: 25515 Facility Num: 62112 AI Number: 458689222002152	4431 LUCKSINGER LN	ESE 1/8 - 1/4 (0.132 mi.)	RC2898 / 17	8859
PENSKE TRUCK LEASING Facility Status: ACTIVE Facility Id: 79443 Facility Num: 123066 AI Number: 248491372008253	***8800 S CONGRESS AVE***	***SW 1/8 - 1/4 (0.132 mi.)***	***RD2900 / 21***	***8870***
BUTLER PAPER Facility Status: INACTIVE Facility Id: 10844 Facility Num: 50151 AI Number: 11374962002075	200 E SAINT ELMO RD	ESE 1/8 - 1/4 (0.134 mi.)	RE2903 / 18	8898
CARMAX 7154 Facility Status: ACTIVE Facility Id: 76495 Facility Num: 117431 AI Number: 731446322006201	***13300 N IH 35***	***N 1/8 - 1/4 (0.158 mi.)***	***2928 / 2***	***8961***
EXXON RS 62790 Facility Status: INACTIVE Facility Id: 26050 Facility Num: 47936 AI Number: 956297932002175	***619 N IH 35***	***ENE 1/8 - 1/4 (0.159 mi.)***	***RG2931 / 11***	***8990***
PRIME FOOD MART Facility Status: ACTIVE Facility Id: 33136 Facility Num: 45105 AI Number: 762607152002053	***601 N IH 35***	***ENE 1/8 - 1/4 (0.162 mi.)***	***RG2935 / 11***	***9036***
WHITAKER FIELDS Facility Status: INACTIVE Facility Id: 11350 Facility Num: 50474 AI Number: 265500132005280	4901 N GUADALUPE	ESE 1/8 - 1/4 (0.162 mi.)	RK2936 / 8	9064
SAFEWAY RENTAL EQUIP Facility Status: INACTIVE	311 BOWIE ST	WNW 1/8 - 1/4 (0.162 mi.)	RL2941 / 11	9076

Facility Id: 42881 Facility Num: 71768 AI Number: 783040482002156				
POLICE DEPARTMENT HE Facility Status: ACTIVE Facility Id: 18169 Facility Num: 37573 AI Number: 566665092002149	***715 E 8TH ST***	***NE 1/8 - 1/4 (0.163 mi.)***	***RM2944 / 11***	***9100***
CLOSED GASOLINE STAT Facility Status: INACTIVE Facility Id: 55851 Facility Num: 85634 AI Number: 382601832002053	***2803 SAN JACINTO BLV***	***E 1/8 - 1/4 (0.164 mi.)***	***2946 / 11***	***9118***
SUNRISE MINI MART 8 Facility Status: ACTIVE Facility Id: 39554 Facility Num: 61074 AI Number: 410733132002149	***539 W OLTORF ST***	***W 1/8 - 1/4 (0.164 mi.)***	***2947 / 14***	***9150***
MOLINA AUTOMOTIVE Facility Status: INACTIVE Facility Id: 72869 Facility Num: 110952 AI Number: 277568412002053	***903 WAGON TRL***	***WNW 1/8 - 1/4 (0.165 mi.)***	***RA2948 / 3***	***9176***
AUSTIN METAL & IRON Facility Status: INACTIVE Facility Id: 15501 Facility Num: 54209 AI Number: 389193362002156	***301 SAN MARCOS ST***	***ESE 1/8 - 1/4 (0.168 mi.)***	***RP2955 / 11***	***9203***
AA AUTO & EQUIPMENT Facility Status: INACTIVE Facility Id: 56977 Facility Num: 80459 AI Number: 383337672003221	1115 OLD BASTROP HWY	E 1/8 - 1/4 (0.168 mi.)	RO2958 / 16	9221
SOUTH AUSTIN SERVICE Facility Status: INACTIVE Facility Id: 41137 Facility Num: 55549 AI Number: 954398502003357	***3815 WOODBURY DR***	***ESE 1/8 - 1/4 (0.171 mi.)***	***RQ2963 / 14***	***9263***
GEORGE COFFEY LINC-M Facility Status: INACTIVE Facility Id: 41953 Facility Num: 71307 AI Number: 354590992005285	900 W 6TH	WNW 1/8 - 1/4 (0.172 mi.)	RR2965 / 11	9269
PREFERRED PUMP Facility Status: INACTIVE Facility Id: 76675 Facility Num: 117717 AI Number: 215514282004239	3805 WOODBURY DR	ESE 1/8 - 1/4 (0.174 mi.)	RQ2966 / 14	9297
VES SERVICE CENTER 5 Facility Status: ACTIVE Facility Id: 18146	***714 E 8TH ST***	***NE 1/8 - 1/4 (0.179 mi.)***	***RM2983 / 11***	***9337***

Facility Num: 37550 AI Number: 936527342002246				
SHELL FOOD MART Facility Status: ACTIVE Facility Id: 19601 Facility Num: 56665 AI Number: 301700682002148	***4001 MEDICAL PKWY***	***WNW 1/8 - 1/4 (0.179 mi.)***	***RV2985 / 8***	***9389***
REDDY ICE Facility Status: INACTIVE Facility Id: 24217 Facility Num: 60317 AI Number: 873376262002118	***901 RED RIVER ST***	***NE 1/8 - 1/4 (0.181 mi.)***	***RX2990 / 11***	***9428***
TECHNICAL COATINGS Facility Status: INACTIVE Facility Id: 14685 Facility Num: 53343 AI Number: 430822092002068	220 INDUSTRIAL BLVD	ESE 1/8 - 1/4 (0.191 mi.)	SA2998 / 18	9443
BEN WHITE U HAUL Facility Status: INACTIVE Facility Id: 36411 Facility Num: 43091 AI Number: 454367822002075	***304 E BEN WHITE BLVD***	***ESE 1/8 - 1/4 (0.193 mi.)***	***3004 / 18***	***9483***
SPTCO Facility Status: INACTIVE Facility Id: 55193 Facility Num: 47343 AI Number: 262812212002150	SAN MARCOS & E 5TH	E 1/8 - 1/4 (0.194 mi.)	RJ3006 / 11	9497
7-ELEVEN STORE 36643 Facility Status: ACTIVE Facility Id: 73993 Facility Num: 112819 AI Number: 351554402002053	***701 N IH 35***	***ENE 1/8 - 1/4 (0.194 mi.)***	***RS3007 / 11***	***9504***
SOUTH SIDE MOTOR Facility Status: INACTIVE Facility Id: 31833 Facility Num: 65831 AI Number: 829681962002057	2617 S 1ST ST	W 1/8 - 1/4 (0.195 mi.)	SC3011 / 14	9534
FORMER UNLIMITED AUT Facility Status: INACTIVE Facility Id: 74979 Facility Num: 114640 AI Number: 373481802003020	1023 W 24TH ST	W 1/8 - 1/4 (0.196 mi.)	SD3013 / 11	9544
FORMER RITLER OIL Facility Status: INACTIVE Facility Id: 75974 Facility Num: 116539 AI Number: 459498912005280	1250 BASTROP HWY	N 1/8 - 1/4 (0.197 mi.)	SE3020 / 16	9552
B&B LAND CLEARING Facility Status: INACTIVE Facility Id: 47607 Facility Num: 79054	1212 OLD BASTROP HWY	ESE 1/8 - 1/4 (0.198 mi.)	SG3025 / 16	9562

AI Number: 715651442002053				
TXDOT SPECIAL CREWS Facility Status: INACTIVE Facility Id: 10054 Facility Num: 73754 AI Number: 904361522002075	***760 BASTROP HWY S***	***NNE 1/8 - 1/4 (0.198 mi.)***	***SH3027 / 15***	***9568***
7-ELEVEN 21884 Facility Status: ACTIVE Facility Id: 7174 Facility Num: 46176 AI Number: 781158282002117	***917 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.199 mi.)***	***SF3035 / 11***	***9603***
CIRCLE K 3213 Facility Status: INACTIVE Facility Id: 36539 Facility Num: 44044 AI Number: 647577282002117	6812 AIRPORT BLVD	ESE 1/8 - 1/4 (0.206 mi.)	3048 / 6	9678
ASCENSION SETON MEDI Facility Status: ACTIVE Facility Id: 56515 Facility Num: 86372 AI Number: 548071502002156	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***
GOODRICH AEROSPACE C Facility Status: ACTIVE Facility Id: 14678 Facility Num: 53337 AI Number: 644605812002053	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3055 / 2***	***9897***
MURPHY USA 6967 Facility Status: ACTIVE Facility Id: 76078 Facility Num: 116722 AI Number: 164634282003307	***13000 S IH 35***	***ESE 1/8 - 1/4 (0.210 mi.)***	***SI3060 / 2***	***9935***
WAL-MART SUPERCENTER Facility Status: ACTIVE Facility Id: 76874 Facility Num: 117999 AI Number: 954635462004328	***12900 N IH 35***	***E 1/8 - 1/4 (0.211 mi.)***	***SK3061 / 2***	***9958***
WALKER TIRE Facility Status: INACTIVE Facility Id: 64486 Facility Num: 95709 AI Number: 787105062002069	814 IH BLVD # 35	NE 1/8 - 1/4 (0.213 mi.)	SO3064 / 11	9969
CHAMELEON 71 Facility Status: INACTIVE Facility Id: 45535 Facility Num: 67610 AI Number: 364830692002152	***7110 E BEN WHITE BLV***	***SSW 1/8 - 1/4 (0.214 mi.)***	***SP3066 / 19***	***9976***
SERVICE BUILDING VEH Facility Status: INACTIVE Facility Id: 11352 Facility Num: 50476 AI Number: 187601122003202	***304 E 24TH ST***	***E 1/8 - 1/4 (0.214 mi.)***	***3068 / 11***	***10005***
STRAIT MUSIC	10TH & LAMAR	WNW 1/8 - 1/4 (0.217 mi.)	SF3072 / 11	10027

Facility Status: INACTIVE Facility Id: 34968 Facility Num: 63744 AI Number: 631653962002156				
KWIK MART 1 Facility Status: ACTIVE Facility Id: 38369 Facility Num: 69441 AI Number: 971497472002259	***1200 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.217 mi.)***	***SS3076 / 11***	***10033***
SUPER K GRO Facility Status: INACTIVE Facility Id: 11333 Facility Num: 87026 AI Number: 786576342002053	***6700 GUADALUPE ST ST***	***ESE 1/8 - 1/4 (0.219 mi.)***	***3083 / 6***	***10091***
REDDY ICE OAK FARMS Facility Status: INACTIVE Facility Id: 46016 Facility Num: 77385 AI Number: 466603332002053	***910 RED RIVER ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***3088 / 11***	***10139***
1001 E 6TH Facility Status: INACTIVE Facility Id: 71691 Facility Num: 109094 AI Number: 144501662002053	***1001 E 6TH ST***	***E 1/8 - 1/4 (0.226 mi.)***	***SW3095 / 11***	***10162***
TERMINIX INTERNATION Facility Status: INACTIVE Facility Id: 65241 Facility Num: 96998 AI Number: 404664162002152	***1206 PARKWAY***	***WNW 1/8 - 1/4 (0.229 mi.)***	***SS3103 / 11***	***10183***
ABIA CONSOLIDATED RE Facility Status: ACTIVE Facility Id: 86714 Facility Num: 131839 AI Number: 828346992014092	***3819 PRESIDENTIAL BL***	***E 1/8 - 1/4 (0.230 mi.)***	***3105 / 20***	***10193***
CAPITOL CHEVROLET MA Facility Status: INACTIVE Facility Id: 45654 Facility Num: 77176 AI Number: 801071142002117	***409 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.235 mi.)***	***TA3112 / 11***	***10219***
TEXAS DEPARTMENT OF Facility Status: ACTIVE Facility Id: 74167 Facility Num: 113114 AI Number: 716632952002156	***5710 GUADALUPE ST***	***ESE 1/8 - 1/4 (0.238 mi.)***	***TC3120 / 9***	***10252***
SATELLITE 5 FLEET MA Facility Status: INACTIVE Facility Id: 44492 Facility Num: 72698 AI Number: 859317852002156	***1000 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.241 mi.)***	***TE3130 / 11***	***10320***
TEXAS DEPT OF PUBLIC Facility Status: INACTIVE	***5900 GUADALUPE ST***	***ESE 1/8 - 1/4 (0.241 mi.)***	***TF3131 / 9***	***10347***

Facility Id: 10806 Facility Num: 50125 AI Number: 288652822002205				
RECREATIONAL EQUIPME Facility Status: INACTIVE Facility Id: 48979 Facility Num: 87568 AI Number: 419742782002053	***1112 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.242 mi.)***	***TG3134 / 11***	***10359***
STONE INDUSTRIAL SOL Facility Status: INACTIVE Facility Id: 66284 Facility Num: 99373 AI Number: 967000962002155	***301 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.244 mi.)***	***TH3144 / 18***	***10399***
CAPITOL CHEVROLET Facility Status: INACTIVE Facility Id: 25102 Facility Num: 61787 AI Number: 20403372003094	***501 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.246 mi.)***	***TB3146 / 11***	***10412***
CAPITOL CHEVROLET Facility Status: INACTIVE Facility Id: 45653 Facility Num: 77175 AI Number: 321104442002117	***501 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.246 mi.)***	***TB3147 / 11***	***10472***
YAGER Facility Status: INACTIVE Facility Id: 58012 Facility Num: 85717 AI Number: 134221292002139	505 W YAGER LN	E 1/8 - 1/4 (0.246 mi.)	TI3149 / 4	10491
TEXAS ALTERNATOR STA Facility Status: INACTIVE Facility Id: 41169 Facility Num: 70748 AI Number: 775543352005209	1230 E BEN WHITE BLV	N 1/8 - 1/4 (0.247 mi.)	SZ3152 / 16	10496

TX AST: Petroleum Storage Tank Database

A review of the TX AST list, as provided by EDR, and dated 03/02/2023 has revealed that there are 22 TX AST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ENTERPRISE RENT A CA Facility Id: 120195 Facility Id: 968569112006167 Facility Id: 77996 Facility Status: ACTIVE	4210 S CONGRESS AVE	WNW 0 - 1/8 (0.015 mi.)	GW1212 / 17	3861
LYNDON B JOHNSON BUI Facility Id: 123780 Facility Id: 616479882010130 Facility Id: 79795 Facility Status: ACTIVE	111 E 17TH ST	ESE 0 - 1/8 (0.022 mi.)	JE1426 / 11	4499
TENNYSON 836	***11409 N LAMAR BLVD***	***ESE 0 - 1/8 (0.031 mi.)***	***KB1723 / 3***	***5714***

Facility Id: 76477 Facility Id: 273654602002150 Facility Id: 19360 Facility Status: ACTIVE				
SAM HOUSTON BUILDING Facility Id: 124330 Facility Id: 917497782010006 Facility Id: 80103 Facility Status: ACTIVE	201 E 14TH ST	ESE 0 - 1/8 (0.051 mi.)	2055 / 11	6618
AUSTIN GREENWOOD CON Facility Id: 76469 Facility Id: 101678402002150 Facility Id: 19352 Facility Status: ACTIVE	909 COLORADO ST	WNW 0 - 1/8 (0.052 mi.)	KL2074 / 11	6658
ST EDWARDS UNIVERSIT Facility Id: 41670 Facility Id: 149799842002068 Facility Id: 3075 Facility Status: ACTIVE	3001 S CONGRESS AVE	ESE 0 - 1/8 (0.075 mi.)	ON2481 / 14	7364
AUSTIN BEN WHITE FAC Facility Id: 120529 Facility Id: 268557152006271 Facility Id: 78195 Facility Status: ACTIVE	7401 E BEN WHITE BLV	SW 0 - 1/8 (0.087 mi.)	PI2642 / 19	7981
CYRUSONE Facility Id: 127774 Facility Id: 344478432010130 Facility Id: 83527 Facility Status: ACTIVE	7401 E BEN WHITE BLV	SW 0 - 1/8 (0.087 mi.)	PI2643 / 19	7982
AUSTIN DATA CENTER A Facility Id: 111677 Facility Id: 15690562002150 Facility Id: 73308 Facility Status: ACTIVE	7401 E BEN WHITE BLV	SW 0 - 1/8 (0.087 mi.)	PI2645 / 19	7986
HID GLOBAL Facility Id: 132504 Facility Id: 693504022015020 Facility Id: 87380 Facility Status: ACTIVE	611 CENTER RIDGE DR	ESE 0 - 1/8 (0.094 mi.)	2727 / 2	8231
HERTZ RENT-A-CAR 163 Facility Id: 109681 Facility Id: 665074622002087 Facility Id: 72074 Facility Status: ACTIVE	9401 RENTAL CAR LN	WNW 1/8 - 1/4 (0.156 mi.)	RI2927 / 20	8959
ORACLE AMERICA WATER Facility Id: 134642 Facility Id: 456528352017293 Facility Id: 89530 Facility Status: ACTIVE	2300 CLOUD WAY	NE 1/8 - 1/4 (0.158 mi.)	2929 / 15	8987
AIRPORT FAST PARK Facility Id: 120449	2300 SPIRIT OF TEXAS	NE 1/8 - 1/4 (0.205 mi.)	3044 / 20	9665

Facility Id: 812663052006234 Facility Id: 78145 Facility Status: ACTIVE				
GOODRICH AEROSPACE C Facility Id: 53337 Facility Id: 644605812002053 Facility Id: 14678 Facility Status: ACTIVE	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3056 / 2***	***9913***
LOWES OF NE AUSTIN T Facility Id: 122565 Facility Id: 246617592008175 Facility Id: 79154 Facility Status: ACTIVE	13000 N IH 35	ESE 1/8 - 1/4 (0.210 mi.)	SI3059 / 2	9933
AUSTIN ENERGY SYSTEM Facility Id: 130316 Facility Id: 188402422012165 Facility Id: 85147 Facility Status: ACTIVE	2500 MONTOPOLIS DR	SSW 1/8 - 1/4 (0.218 mi.)	ST3080 / 19	10088
AVIS RENT A CAR SYST Facility Id: 109608 Facility Id: 512543392002054 Facility Id: 72022 Facility Status: ACTIVE	9320 RENTAL CAR LN	WNW 1/8 - 1/4 (0.231 mi.)	SY3106 / 20	10215
TEXAS DEPARTMENT OF Facility Id: 113114 Facility Id: 716632952002156 Facility Id: 74167 Facility Status: ACTIVE	***5710 GUADALUPE ST***	***ESE 1/8 - 1/4 (0.238 mi.)***	***TC3117 / 9***	***10242***
MET CENTER Facility Id: 111814 Facility Id: 757409142002075 Facility Id: 73387 Facility Status: ACTIVE	7551 METRO CENTER DR	SSW 1/8 - 1/4 (0.239 mi.)	TD3123 / 19	10284
ALAMO RENT-A-CAR Facility Id: 113942 Facility Id: 117640732002053 Facility Id: 74622 Facility Status: Inactive	9310 RENTAL CAR LN	WNW 1/8 - 1/4 (0.240 mi.)	SY3126 / 20	10311
GULF CLEANING AND LA Facility Id: 114588 Facility Id: 434727002002256 Facility Id: 74952 Facility Status: INACTIVE	301 INDUSTRIAL BLVD	ESE 1/8 - 1/4 (0.244 mi.)	TH3143 / 18	10396
TEXAS DEPARTMENT OF Facility Id: 124329 Facility Id: 381365902010159 Facility Id: 80102 Facility Status: ACTIVE	1100 W 49TH ST	WNW 1/8 - 1/4 (0.249 mi.)	TJ3159 / 8	10527

EXECUTIVE SUMMARY

TX TANKS: Petroleum Storage Tanks Listing

A review of the TX TANKS list, as provided by EDR, and dated 03/02/2023 has revealed that there are 16 TX TANKS sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
PREMIUM PARKING PUBL	***415 E 7TH ST***	***NNE 0 - 1/8 (0.013 mi.)***	***DM1037 / 11***	***3261***
5TH AND WEST	***501 WEST AVE***	***WNW 0 - 1/8 (0.013 mi.)***	***DC1060 / 11***	***3358***
TWOMEY AUTO WORKS AU	***1009 S CONGRESS AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***ER1111 / 14***	***3522***
OSF CONGRESS	***2701 S CONGRESS AVE***	***NNE 0 - 1/8 (0.029 mi.)***	***JX1695 / 14***	***5599***
FURNITURE REJUVENATO	***605 W 37TH ST***	***WNW 0 - 1/8 (0.037 mi.)***	***IC1836 / 8***	***6087***
400 LAVACA ST AUSTIN	***400 LAVACA ST***	***ESE 0 - 1/8 (0.054 mi.)***	***KG2163 / 11***	***6775***
BOWMAN RESIDENCE	***212 W 33RD ST***	***WNW 0 - 1/8 (0.057 mi.)***	***2237 / 8***	***6867***
CITY OF AUSTIN RIGHT	***3RD & SAN ANTONIO***	***WNW 0 - 1/8 (0.070 mi.)***	***OH2437 / 11***	***7286***
CHARLES T SIKES	***1000 W 39TH ST***	***WNW 0 - 1/8 (0.094 mi.)***	***PR2724 / 8***	***8226***
TX DOT ROW	***E MARTIN LUTHER KING***	***ESE 0 - 1/8 (0.120 mi.)***	***PT2859 / 11***	***8732***
RBJ REDEVELOPMENT PR	***21 WALLER ST***	***NE 1/8 - 1/4 (0.130 mi.)***	***2895 / 14***	***8851***
LAMAR VILLAGE SHOPPI	***3800 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.130 mi.)***	***2896 / 8***	***8856***
WHOLE FOODS MARKET	525 N LAMAR BLVD	WNW 1/8 - 1/4 (0.235 mi.)	TB3113 / 11	10237
MERCEDES BENZ OF AUS	***412 PAMPA DR***	***ESE 1/4 - 1/2 (0.349 mi.)***	***3203 / 6***	***10956***
CAPITOL CHEVROLET PA	***700 N BLUFF DR***	***ESE 1/4 - 1/2 (0.370 mi.)***	***3216 / 17***	***11082***
PLAZA SALTILLO	***1301 E 5TH ST***	***E 1/4 - 1/2 (0.408 mi.)***	***TU3231 / 11***	***11213***

State and tribal institutional control / engineering control registries

TX AUL: Sites with Controls

A review of the TX AUL list, as provided by EDR, and dated 04/06/2023 has revealed that there is 1 TX AUL site within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
DOWNTOWN RAILYARD PR Facility Id: 2601	***800 E 4TH ST***	***E 0 - 1/8 (0.108 mi.)***	***QI2806 / 11***	***8524***

Lists of state and tribal voluntary cleanup sites

TX VCP: Voluntary Cleanup Program Database

A review of the TX VCP list, as provided by EDR, has revealed that there are 33 TX VCP sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
IVORY CLEANERS & ALT Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2578	***1901 RIO GRANDE ST***	***E 0 - 1/8 (0.011 mi.)***	***HQ951 / 11***	***2900***
HYATT REGENCY HOTEL Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1872	208 BARTON SPRINGS R	S 0 - 1/8 (0.012 mi.)	975 / 11	2991
AARONS Database: VCP TCEQ, Date of Government Version: 06/23/2023	***9616 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***O1057 / 6***	***3348***

Facility ID: 406				
DRAKE CONDOMINIUMS Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2036	68 RAINEY ST	ESE 0 - 1/8 (0.015 mi.)	1188 / 14	3828
GREEN WATER TREATMEN Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2199	***600 W. CESAR CHAVEZ***	***ENE 0 - 1/8 (0.021 mi.)***	***JC1394 / 11***	***4403***
AMERICAN CLEANERS FA Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 188	***309 W 5TH ST***	***ESE 0 - 1/8 (0.021 mi.)***	***DI1404 / 11***	***4436***
SOCO CENTER Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2337	***3630 S CONGRESS AVE***	***WNW 0 - 1/8 (0.025 mi.)***	***GM1513 / 14***	***4826***
LITTLEFIELD PARKING Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 673	***508 BRAZOS ST***	***SSW 0 - 1/8 (0.025 mi.)***	***JP1555 / 11***	***5021***
LITTLEFIELD DRISKILL Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2172	***106 E 6TH ST***	***NNE 0 - 1/8 (0.027 mi.)***	***DN1602 / 11***	***5251***
AUSTIN TOYOTA Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1333	***1127 W 6TH STREET***	***WNW 0 - 1/8 (0.028 mi.)***	***DC1657 / 11***	***5481***
AUSTIN ENERGY POLE Y Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 880	300 WEST AVE	WNW 0 - 1/8 (0.028 mi.)	DL1669 / 11	5519
CENTRAL TEXAS EQUIPM Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1835	***127 E RIVERSIDE DR***	***SW 0 - 1/8 (0.029 mi.)***	***EM1694 / 14***	***5591***
JACK BROWN CLEANERS Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1658	***615 W MARTIN LUTHER***	***E 0 - 1/8 (0.041 mi.)***	***LF1897 / 11***	***6318***
SCARBROUGH HOUSE TRA Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1414	2612 WHITIS AVE	E 0 - 1/8 (0.052 mi.)	2080 / 11	6661
APPLE TRACT Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 780	811 W 6TH ST	WNW 0 - 1/8 (0.053 mi.)	LX2094 / 11	6727
BLOCK 4 Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1110	***100 COLORADO ST***	***NNE 0 - 1/8 (0.055 mi.)***	***MK2191 / 11***	***6832***
PHILLIPS BUILDING Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 690	***103 E 5TH ST***	***SSW 0 - 1/8 (0.062 mi.)***	***NL2302 / 11***	***6980***
PROPOSED CHICK FIL A Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2468	503 W MARTIN LUTHER	W 0 - 1/8 (0.065 mi.)	NS2331 / 11	7041
SEAHOLM POWER PLANT Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 283	***800 W CESAR CHAVEZ S***	***W 0 - 1/8 (0.086 mi.)***	***PG2633 / 11***	***7863***

Facility ID: 2324				
6909 RYAN DRIVE PROP Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 3152	906 JUSTIN LN	WNW 0 - 1/8 (0.099 mi.)	PV2752 / 6	8283
DOWNTOWN RAILYARD PR Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2601	***800 E 4TH ST***	***E 0 - 1/8 (0.108 mi.)***	***QI2806 / 11***	***8524***
SAFE WAY RENTAL TOWE Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2409	***311 BOWIE ST***	***WNW 1/8 - 1/4 (0.162 mi.)***	***RL2938 / 11***	***9068***
SAFEWAY RENTAL EQUIP Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1266	***311 BOWIE ST***	***WNW 1/8 - 1/4 (0.162 mi.)***	***RL2939 / 11***	***9073***
AUSTIN METAL IRON Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 646	***301 SAN MARCOS ST***	***ESE 1/8 - 1/4 (0.168 mi.)***	***RP2956 / 11***	***9207***
STONE INDUSTRIAL SOL Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 1138	***301 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.244 mi.)***	***TH3144 / 18***	***10399***
403 - 301 INDUSTRIAL Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 3214	403 INDUSTRIAL BLVD	ESE 1/8 - 1/4 (0.246 mi.)	TH3151 / 18	10495
AUSTIN EXECUTIVE AIR Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 941	811 W HOWARD LN	NE 1/4 - 1/2 (0.275 mi.)	3170 / 2	10752
MULDOON INTERESTS Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2074	6210 CROW LN	ESE 1/4 - 1/2 (0.291 mi.)	3175 / 17	10788
GARDNER IRON AND MET Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2796	***1201 E 4TH ST***	***ESE 1/4 - 1/2 (0.308 mi.)***	***3186 / 11***	***10873***
FORMER AIRPORT EXXON Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2672	2511 HWY 71 E	E 1/4 - 1/2 (0.339 mi.)	TO3197 / 20	10905
BIG LOTS Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 611	***801 E WILLIAM CANNON***	***ESE 1/4 - 1/2 (0.374 mi.)***	***3219 / 17***	***11106***
BEN WHITE LOTS 1,2,3 Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2025	***500 E BEN WHITE BLVD***	***ESE 1/4 - 1/2 (0.423 mi.)***	***TW3237 / 18***	***11257***
STENGER TRACT Database: VCP TCEQ, Date of Government Version: 06/23/2023 Facility ID: 2395	1406 N IH 35	WNW 1/4 - 1/2 (0.480 mi.)	3286 / 8	11632

EXECUTIVE SUMMARY

Lists of state and tribal brownfield sites

TX BROWNFIELDS: Brownfields Site Assessments

A review of the TX BROWNFIELDS list, as provided by EDR, and dated 03/27/2023 has revealed that there are 5 TX BROWNFIELDS sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
RESTORE RUNDBURG BF Grant Number: G158	SEC OF LAMAR AND BRA	ESE 0 - 1/8 (0.017 mi.)	IS1278 / 3	4075
SOUTH CENTRAL WATERF BF Grant Number: G157	NEC OF S FIRST ST AN	NE 0 - 1/8 (0.052 mi.)	2077 / 14	6659
DOWNTOWN RAILYARD PR BF Grant Number: G131	***800 E 4TH ST***	***E 0 - 1/8 (0.108 mi.)***	***QI2806 / 11***	***8524***
FESTIVAL BEACH FOOD BF Grant Number: G156	35 WALLER ST	NNE 0 - 1/8 (0.124 mi.)	QY2884 / 14	8819
SEAHOLM DISTRICT UPR BF Grant Number: G059	NO ADDRESS RAILROAD	W 0 - 1/8 (0.124 mi.)	2886 / 11	8829

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

A review of the US BROWNFIELDS list, as provided by EDR, and dated 04/06/2023 has revealed that there are 35 US BROWNFIELDS sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
GUADALUPE 4413 ACRES property ID: 67842 Cleanup Completion Date: 4/1/2010	***4413 GUADALUPE STREE***	***ESE 0 - 1/8 (0.012 mi.)***	***HW998 / 8***	***3073***
COLLEGE HOUSES ACRES property ID: 240348	***707 W. 21ST ST***	***E 0 - 1/8 (0.014 mi.)***	***1162 / 11***	***3752***
MARY LEE COMMUNITY ACRES property ID: 10899	***600 CONGRESS AVE***	***ESE 0 - 1/8 (0.014 mi.)***	***DH1178 / 11***	***3810***
CITY HALL ANNEX BLOC ACRES property ID: 11972 Cleanup Completion Date: 12/31/2001	***UNKNOWN***	***ESE 0 - 1/8 (0.033 mi.)***	***KJ1773 / 11***	***5930***
CHAMPION PROPERTIES ACRES property ID: 11981 ACRES property ID: 11980 ACRES property ID: 11975 ACRES property ID: 11977 ACRES property ID: 11970 **Additional key fields are available in the Map Findings section* Cleanup Completion Date: 3/31/2002	***UNKNOWN***	***WNW 0 - 1/8 (0.041 mi.)***	***1900 / 11***	***6338***
ESCUELA MONTESSORI	2013 MONTOPOLIS DRIV	SSW 0 - 1/8 (0.065 mi.)	NU2343 / 15	7073

ACRES property ID: 238654				
912 HWY 183 ACRES property ID: 237538	912 HWY 183	ENE 0 - 1/8 (0.067 mi.)	2380 / 15	7146
EMMA BARRIENTOS MEXI ACRES property ID: 253498	600 RIVER STREET	WNW 0 - 1/8 (0.068 mi.)	OC2407 / 11	7219
THE SALVATION ARMY C ACRES property ID: 231122	***501 E. 8TH***	***NNE 0 - 1/8 (0.087 mi.)***	***2640 / 11***	***7969***
MONTOPOLIS CDC ACRES property ID: 241993	2404 THRASHER	SSW 0 - 1/8 (0.111 mi.)	2819 / 19	8659
FESTIVAL BEACH FOOD ACRES property ID: 208792	35 WALLER STREET	NNE 0 - 1/8 (0.124 mi.)	QY2885 / 14	8820
SALVATION ARMY SOUTH ACRES property ID: 206321	4216 SOUTH CONGRESS	WNW 1/8 - 1/4 (0.161 mi.)	2934 / 17	9019
SEAHOLM DISTRICT UPR ACRES property ID: 10934	***S 3RD STREET BETWEEN***	***WNW 1/8 - 1/4 (0.174 mi.)***	***2968 / 11***	***9305***
SALTILLO PLAZA-DOWNT ACRES property ID: 135663	1000 E. 4TH STREET	E 1/8 - 1/4 (0.208 mi.)	SJ3053 / 11	9883
ROY AND MATIAS VELAS ACRES property ID: 219985	1020 E 5TH ST	E 1/8 - 1/4 (0.240 mi.)	3124 / 11	10288
LOPEZ PROPERTY ACRES property ID: 184541 Cleanup Completion Date: 4/1/2016 Cleanup Completion Date: 2/15/2016	809 E.9TH STREET	ENE 1/4 - 1/2 (0.268 mi.)	3165 / 11	10698
MONTOPOLIS PARK ACRES property ID: 220002 Cleanup Completion Date: 10/4/2019	***1200 MONTOPOLIS***	***NNE 1/4 - 1/2 (0.271 mi.)***	***TK3167 / 15***	***10723***
ELIZABET NEY MUSEUM ACRES property ID: 241059	304 E. 44TH STREET	E 1/4 - 1/2 (0.319 mi.)	3193 / 8	10883
STATE HIGHWAY 71 E 2 ACRES property ID: 67843 Cleanup Completion Date: 2/4/2010	***2511 HIGHWAY 71 E***	***E 1/4 - 1/2 (0.339 mi.)***	***TO3199 / 20***	***10907***
CENTRAL HEALTH - BRA ACRES property ID: 231321	601 E. 15TH STREET	ESE 1/4 - 1/2 (0.365 mi.)	TR3213 / 11	11060
FORMER FIRST TEXAS H ACRES property ID: 234521	1303 W. KOENIG	WNW 1/4 - 1/2 (0.365 mi.)	TQ3215 / 8	11078
ROOSEVELT GARDENS ACRES property ID: 241060 Cleanup Completion Date: 9/18/2020	***5606 ROOSEVELT AVENU***	***WNW 1/4 - 1/2 (0.371 mi.)***	***3217 / 8***	***11083***
908 E. 11TH ST (11TH ACRES property ID: 46681	***908 E. 11TH ST***	***NE 1/4 - 1/2 (0.438 mi.)***	***UB3254 / 11***	***11393***
912 E. 11TH STREET ACRES property ID: 40921	912 E. 11TH STREET	NE 1/4 - 1/2 (0.444 mi.)	UB3255 / 11	11397
916 E. 11TH STREET ACRES property ID: 42121	916 E. 11TH STREET	NE 1/4 - 1/2 (0.449 mi.)	UB3257 / 11	11411
920 E. 11TH ST (11TH ACRES property ID: 46701	***920 E. 11TH ST***	***ENE 1/4 - 1/2 (0.453 mi.)***	***UB3263 / 11***	***11471***
903 JUNIPER ST (11TH	***903 JUNIPER ST***	***NE 1/4 - 1/2 (0.456 mi.)***	***UB3266 / 11***	***11476***

ACRES property ID: 18581				
905 JUNIPER ST (11TH ACRES property ID: 46621	***905 JUNIPER ST.***	***NE 1/4 - 1/2 (0.461 mi.)***	***UB3270 / 11***	***11514***
HABITAT FOR HUMANITY ACRES property ID: 205061	***1407-1411 E. 4TH STR***	***ESE 1/4 - 1/2 (0.462 mi.)***	***3271 / 11***	***11517***
907 JUNIPER ST (11TH ACRES property ID: 46641	***907 JUNIPER ST***	***NE 1/4 - 1/2 (0.466 mi.)***	***UB3278 / 11***	***11578***
909 JUNIPER ST (11TH ACRES property ID: 46661	***909 JUNIPER ST***	***NE 1/4 - 1/2 (0.470 mi.)***	***UB3281 / 11***	***11610***
911 JUNIPER ST (11TH ACRES property ID: 46662	***911 JUNIPER ST***	***NE 1/4 - 1/2 (0.472 mi.)***	***UB3282 / 11***	***11613***
913 JUNIPER ST (11TH ACRES property ID: 46663	***913 JUNIPER ST***	***ENE 1/4 - 1/2 (0.479 mi.)***	***3284 / 11***	***11617***
6301 CIRCULO DE AMIS ACRES property ID: 242586	6301 CIRCULO DE AMIS	NNE 1/4 - 1/2 (0.480 mi.)	3285 / 15	11621
DOUGHERTY ARTS CENTE ACRES property ID: 253245	***1500 TOOMEY RD***	***WSW 1/4 - 1/2 (0.492 mi.)***	***3294 / 11***	***11701***

Local Lists of Landfill / Solid Waste Disposal Sites

TX SWRCY: Recycling Facility Listing

A review of the TX SWRCY list, as provided by EDR, and dated 05/08/2023 has revealed that there is 1 TX SWRCY site within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ROUND2 INC. Physical Site Status: ACTIVE Additional Id: 100312	***1340 AIRPORT COMMERC***	***S 0 - 1/8 (0.021 mi.)***	***JD1405 / 15***	***4441***

TX HIST LF: Historical Information About Municipal Solid Waste Facilities

A review of the TX HIST LF list, as provided by EDR, and dated 02/01/2022 has revealed that there are 8 TX HIST LF sites within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CONGRESS AVE	1200 BLK CONGRESS AV	WNW 0 - 1/8 (0.013 mi.)	ET1073 / 14	3379
PARKER LN & RIVERSID		WSW 0 - 1/8 (0.036 mi.)	KN1822 / 14	6081
PARKING LOT & BUILDI	206 CONGRESS AVE	SSW 0 - 1/8 (0.044 mi.)	KH1931 / 11	6418
BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	ESE 0 - 1/8 (0.087 mi.)	OS2648 / 17	7989
TEXACO CHEMICALS	7114 N. LAMAR BLVD	WNW 1/8 - 1/4 (0.178 mi.)	RU2980 / 6	9327
WHISENHUT		NNE 1/8 - 1/4 (0.216 mi.)	SQ3071 / 16	10026
BERGSTROM 2	SITE AT N END OF BAS	SE 1/4 - 1/2 (0.431 mi.)	TX3241 / 20	11296
BERGSTROM 1	SITE ON N END OF BAS	SW 1/4 - 1/2 (0.465 mi.)	UF3277 / 20	11577

EXECUTIVE SUMMARY

Local Lists of Hazardous waste / Contaminated Sites

TX PRIORITYCLEANERS: Dry Cleaner Remediation Program Prioritization List

A review of the TX PRIORITYCLEANERS list, as provided by EDR, and dated 09/01/2022 has revealed that there is 1 TX PRIORITYCLEANERS site within approximately 0.5 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
FORMER AMERICAN CLEA Priority Status: Closed DCRP App Number: DC0097	***309-311 WEST 5TH ST***	***ESE 0 - 1/8 (0.021 mi.)***	***DI1402 / 11***	***4435***

Local Lists of Registered Storage Tanks

TX NON REGIST PST: Petroleum Storage Tank Non Registered

A review of the TX NON REGIST PST list, as provided by EDR, and dated 03/31/2023 has revealed that there are 8 TX NON REGIST PST sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
HI TECH AUTOMOTIVE	***1801 S CONGRESS AVE***	***ESE 0 - 1/8 (0.011 mi.)***	***FG953 / 14***	***2907***
MORGAN AUTOMOTIVE	***6200 N LAMAR BLVD***	***WNW 0 - 1/8 (0.019 mi.)***	***AJ1322 / 9***	***4190***
DRISKILL HOTEL ALLEY	***604 BRAZOS ST***	***SSW 0 - 1/8 (0.023 mi.)***	***DJ1467 / 11***	***4668***
400 LAVACA ST AUSTIN	400 LAVACA ST	ESE 0 - 1/8 (0.054 mi.)	KG2161 / 11	6773
UT SIGN SHOP	2920 SAN JACINTO BLV	E 0 - 1/8 (0.111 mi.)	QM2822 / 11	8678
PENSKE TRUCK LEASING	8800 S CONGRESS AVE	SW 1/8 - 1/4 (0.132 mi.)	RD2899 / 21	8869
CARMAX 7154	***13300 N IH 35***	***N 1/8 - 1/4 (0.158 mi.)***	***2928 / 2***	***8961***
CHAMELEON 71	***7110 E BEN WHITE BLV***	***SSW 1/8 - 1/4 (0.214 mi.)***	***SP3066 / 19***	***9976***

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 07/24/2023 has revealed that there are 121 RCRA NonGen / NLR sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY 6892 EPA ID:: TXR000080904	2927 GUADALUPE ST	ESE 0 - 1/8 (0.012 mi.)	BG964 / 8	2920
WALGREEN CO EPA ID:: TXR000026096	***9717 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***N987 / 6***	***3012***
NORTH LAMAR AUTOMOTI EPA ID:: TXD051157949	***8807 A N LAMAR BLVD***	***NW 0 - 1/8 (0.012 mi.)***	***HZ1010 / 6***	***3189***
CVS PHARMACY 6844 EPA ID:: TXR000080991	***2301 2301 S CONGRESS***	***ESE 0 - 1/8 (0.012 mi.)***	***FT1023 / 14***	***3229***
QUALITY BODY SHOP IN	***10720 N LAMAR***	***WNW 0 - 1/8 (0.013 mi.)***	***J1050 / 3***	***3310***

EPA ID:: TXD030916472				
CHUCKS CUSTOM AUTO I EPA ID:: TXD051351187	***11000 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***ID1071 / 3***	***3374***
AUSTIN AMERICAN STAT EPA ID:: TXD008116089	***308 GUADALUPE***	***WNW 0 - 1/8 (0.013 mi.)***	***DS1089 / 11***	***3463***
TWOMEY AUTO WORKS EPA ID:: TX0000241430	***1009 S CONGRESS AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***ER1109 / 14***	***3518***
JACK BROWN CLEANERS EPA ID:: TXD981590706	***2215 S CONGRESS AVE***	***E 0 - 1/8 (0.014 mi.)***	***FQ1125 / 14***	***3579***
B & B BODY & FRAME I EPA ID:: TXD026010579	6518 N LAMAR	WNW 0 - 1/8 (0.014 mi.)	AH1149 / 6	3703
CALIBER COLLISION CE EPA ID:: TXD102730967	***8735 N LAMAR BLVD***	***SE 0 - 1/8 (0.014 mi.)***	***II1153 / 6***	***3709***
CITY OF AUSTIN EPA ID:: TXD981901481	***411 W 2ND ST***	***WNW 0 - 1/8 (0.014 mi.)***	***DX1176 / 11***	***3805***
TUNEUP MASTERS INC EPA ID:: TXD982286288	***5624 N LAMAR BLVD***	***WNW 0 - 1/8 (0.016 mi.)***	***IQ1232 / 8***	***3909***
CVS PHARMACY 7442 EPA ID:: TXR000081087	11300 11300 N LAMAR	WNW 0 - 1/8 (0.017 mi.)	G1268 / 3	4044
HERAEUS AMERSIL INC EPA ID:: TXD988071411	***7715 RIVERSIDE DRIVE***	***WSW 0 - 1/8 (0.017 mi.)***	***HB1274 / 19***	***4072***
RISING SUN JAPANESE EPA ID:: TXD982548430	***4930 S CONGRESS AVE***	***WNW 0 - 1/8 (0.019 mi.)***	***IO1315 / 17***	***4176***
JET ENVIRONMENTAL SE EPA ID:: TXR000083881	4930 S. CONGRESS AVE	WNW 0 - 1/8 (0.019 mi.)	IO1316 / 17	4180
CASTRO'S CLEANERS EPA ID:: TXD981610827	***502 EAST 6TH STREET***	***SW 0 - 1/8 (0.019 mi.)***	***DR1339 / 11***	***4232***
PHILLIPS PETROLEUM C EPA ID:: TXD988075834	***5301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.020 mi.)***	***AO1366 / 8***	***4300***
MOBIL OIL CORPORATIO EPA ID:: TXD988038428	***2401 S CONGRESS AVE***	***SE 0 - 1/8 (0.020 mi.)***	***FU1376 / 14***	***4351***
STATE OF TEXAS PRESE EPA ID:: TXD988039681	TEXAS STATE CAPITOL	ESE 0 - 1/8 (0.021 mi.)	1388 / 11	4370
GROUND SERVICES INTE EPA ID:: TXR000079335	***9401 CARGO AVE STE 4***	***SSW 0 - 1/8 (0.021 mi.)***	***IM1392 / 20***	***4389***
AMERICAN CLEANERS EPA ID:: TXD981904972	***309 W 5TH***	***ESE 0 - 1/8 (0.021 mi.)***	***DI1401 / 11***	***4429***
COMPTROLLER OF PUBLI EPA ID:: TXD981914955	***111 E 17TH ST***	***ESE 0 - 1/8 (0.022 mi.)***	***JE1427 / 11***	***4500***
THE SHERWIN-WILLIAMS EPA ID:: TXD000812503	***500 E OLTORF ST***	***NW 0 - 1/8 (0.023 mi.)***	***JJ1470 / 14***	***4669***
SWEET CLEANERS EPA ID:: TXD981586811	***613 CONGRESS AVE***	***W 0 - 1/8 (0.023 mi.)***	***DG1481 / 11***	***4703***
TRAVIS COUNTY EPA ID:: TXD982563264	***705 E 14TH ST STE B1***	***ESE 0 - 1/8 (0.024 mi.)***	***JO1507 / 11***	***4819***
AEGIS ASSOCIATES INC	***44 EAST AVE STE 100***	***ESE 0 - 1/8 (0.025 mi.)***	***EL1521 / 14***	***4876***

EPA ID:: TXD982557167				
STAR ENTERPRISES EPA ID:: TX0000994863	***1900 GUADALUPE ST***	***W 0 - 1/8 (0.025 mi.)***	***CD1534 / 11***	***4914***
MOBIL OIL CORPORATIO EPA ID:: TXD988038451	***1919 S PLEASANT VALL***	***NE 0 - 1/8 (0.025 mi.)***	***GF1541 / 15***	***4958***
CEN-TEX NISSAN INC EPA ID:: TXD982562829	***1400 S CONGRESS***	***WNW 0 - 1/8 (0.025 mi.)***	***EZ1549 / 14***	***4979***
EXXON MOBIL CORPORAT EPA ID:: TXD988032173	***2512 E RIVERSIDE DR***	***NE 0 - 1/8 (0.026 mi.)***	***HS1581 / 15***	***5190***
PAGE SOUTHERLAND PAG EPA ID:: TXD988019295	***606 WEST AVE***	***WNW 0 - 1/8 (0.027 mi.)***	***CZ1625 / 11***	***5278***
AUSTIN COMMUNITY COL EPA ID:: TXD980878078	***1212 RIO GRANDE ST***	***WNW 0 - 1/8 (0.027 mi.)***	***CO1632 / 11***	***5285***
AUSTIN TOYOTA EPA ID:: TXD052642477	***1127 W 6TH STREET***	***WNW 0 - 1/8 (0.028 mi.)***	***DC1657 / 11***	***5481***
POLE YARD EPA ID:: TXD981901499	***300 WEST AVE***	***WNW 0 - 1/8 (0.028 mi.)***	***DL1668 / 11***	***5514***
SUNBECK AUTOMOTIVE EPA ID:: TXD982759730	***4241 S CONGRESS AVE***	***ESE 0 - 1/8 (0.029 mi.)***	***GX1688 / 18***	***5570***
DALES AUTO PARTS & M EPA ID:: TXD080256993	***3600 S CONGRESS AVE***	***WNW 0 - 1/8 (0.029 mi.)***	***GK1697 / 14***	***5601***
TEXAS SCHOOL FOR THE EPA ID:: TXD100077478	***1102 S CONGRESS AVE***	***ESE 0 - 1/8 (0.032 mi.)***	***KF1749 / 14***	***5833***
EXXON RAS NO 60117 EPA ID:: TXR000034850	***1100 W PARMER***	***W 0 - 1/8 (0.033 mi.)***	***KI1759 / 2***	***5884***
7-ELEVEN STORE 36591 EPA ID:: TXR000034892	***201 W BEN WHITE***	***WNW 0 - 1/8 (0.038 mi.)***	***GS1851 / 14***	***6143***
COMPTROLLER OF PUBLI EPA ID:: TXD981914948	***111 W 6TH ST***	***W 0 - 1/8 (0.039 mi.)***	***LA1877 / 11***	***6237***
AUSTIN NURSING & CON EPA ID:: TXD010531176	***110 E LIVE OAK***	***ESE 0 - 1/8 (0.040 mi.)***	***FM1890 / 14***	***6292***
JIMS BODY SHOP EPA ID:: TXR000020610	***6324 N LAMAR BLVD***	***WNW 0 - 1/8 (0.040 mi.)***	***AI1892 / 6***	***6297***
CVS PHARMACY 7483 EPA ID:: TXR000081081	500 500 CONGRESS AVE	SSW 0 - 1/8 (0.041 mi.)	LG1902 / 11	6358
ORTEGON AUTO BODY RE EPA ID:: TXD117568808	***111 E WOODWARD ST***	***ESE 0 - 1/8 (0.041 mi.)***	***1905 / 14***	***6367***
EXXON MOBIL CORPORAT EPA ID:: TXD988031860	***6721 S CONGRESS AVE***	***ESE 0 - 1/8 (0.045 mi.)***	***LP1947 / 17***	***6442***
COMMUNICATION SPECIA EPA ID:: TXD988075248	***603 DAVIS ST***	***WNW 0 - 1/8 (0.046 mi.)***	***LS1969 / 11***	***6468***
CLASSY CLEANERS INC EPA ID:: TXD982555492	***111 W WILLIAM CANNON***	***WNW 0 - 1/8 (0.048 mi.)***	***LZ2008 / 17***	***6514***
STRUTS CLEANERS EPA ID:: TXD982759318	1106 S 1ST ST 1106-1	WNW 0 - 1/8 (0.049 mi.)	MC2022 / 14	6533
B&N AXLE SERV INC	***219 W 4TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***ME2028 / 11***	***6544***

EPA ID:: TXD026010702				
THE GOODYEAR TIRE & EPA ID:: TXD149980559	***115 E OLTORF ST***	***SE 0 - 1/8 (0.050 mi.)***	***MG2033 / 14***	***6565***
CVS PHARMACY 0213 EPA ID:: TXR000081076	***5526 5526 S CONGRESS***	***WNW 0 - 1/8 (0.050 mi.)***	***MH2038 / 17***	***6575***
MCMORRIS FORD EPA ID:: TXD981155153	***808 W 6TH***	***WNW 0 - 1/8 (0.053 mi.)***	***LX2129 / 11***	***6759***
MAJESTIC PRODUCTS CO EPA ID:: TX0000957415	118 E ALPINE RD	ESE 0 - 1/8 (0.058 mi.)	NE2242 / 14	6896
WHITLEY CO EPA ID:: TXD008143729	***801 BRAZOS TO 805***	***ESE 0 - 1/8 (0.060 mi.)***	***NH2272 / 11***	***6938***
AUSTIN COMPLETE AUTO EPA ID:: TXD981151939	***821 BRENTWOOD***	***WNW 0 - 1/8 (0.063 mi.)***	***NO2309 / 6***	***6994***
MINGOS BODY SHOP EPA ID:: TXD981145055	***811 MCPAUL***	***WNW 0 - 1/8 (0.063 mi.)***	***2311 / 3***	***7000***
REBREU BODY & FRAME EPA ID:: TXD982283772	***822 KRAMER LN***	***WNW 0 - 1/8 (0.064 mi.)***	***LJ2324 / 3***	***7019***
BUMPER-TO-BUMPER CAR EPA ID:: TXD981902612	***201 SAN JACINITO***	***WNW 0 - 1/8 (0.065 mi.)***	***KC2330 / 11***	***7038***
EXXON MOBIL CORPORAT EPA ID:: TXD988031910	3807 EAST AVE	ENE 0 - 1/8 (0.067 mi.)	MQ2383 / 8	7151
CAPITOL CLEANERS EPA ID:: TXD987988532	***1408 S 1ST STREET***	***WNW 0 - 1/8 (0.068 mi.)***	***OB2398 / 14***	***7180***
CITY OF AUSTIN FLEET EPA ID:: TXD981901523	***600 RIVER ST***	***WNW 0 - 1/8 (0.068 mi.)***	***OC2404 / 11***	***7209***
MORGAN PRINTING EPA ID:: TXR000025924	***900 OLD KOENIG LANE***	***WNW 0 - 1/8 (0.068 mi.)***	***2413 / 8***	***7233***
AUSTIN FEDERAL COURT EPA ID:: TX0000012161	***501 W 5TH ST***	***WNW 0 - 1/8 (0.070 mi.)***	***OF2435 / 11***	***7279***
EXXON MOBIL CORPORAT EPA ID:: TXD988032124	***619 N IH 35***	***SSW 0 - 1/8 (0.070 mi.)***	***2438 / 14***	***7287***
AUSTIN ISD EPA ID:: TXD981585292	***3908 AVENUE B***	***WNW 0 - 1/8 (0.075 mi.)***	***OO2485 / 8***	***7405***
WALLACE ENGRAVING CO EPA ID:: TXD000017970	***407 LAVACA STREET***	***ESE 0 - 1/8 (0.076 mi.)***	***OQ2498 / 11***	***7418***
MILLER BLUEPRINT COM EPA ID:: TXD981607088	***513 W 6TH STREET***	***ESE 0 - 1/8 (0.081 mi.)***	***OI2551 / 11***	***7564***
REIDS LAUNDRY & DRY EPA ID:: TX0000363747	3317 N LAMAR BLVD	WNW 0 - 1/8 (0.083 mi.)	OY2577 / 8	7659
THE CLOSET FACTORY EPA ID:: TXR000049577	113 INDUSTRIAL BLVD	ESE 0 - 1/8 (0.083 mi.)	PC2587 / 18	7691
DISCOUNT DRIVE AXLE EPA ID:: TXD988058111	***8204 N LAMAR BLVD SU***	***NW 0 - 1/8 (0.083 mi.)***	***OU2589 / 6***	***7695***
FLASHCARDS EPA ID:: TXD988024774	***8204 N LAMAR SUITE C***	***NW 0 - 1/8 (0.083 mi.)***	***OU2591 / 6***	***7699***
AUSTIN CONVENTION CE	500 E CESAR CHAVEZ S	ESE 0 - 1/8 (0.084 mi.)	PB2596 / 11	7710

EPA ID:: TXR000082023				
LABORATORY CORPORATI EPA ID:: TX0000933713	***3701 N LAMAR STE 200***	***WNW 0 - 1/8 (0.089 mi.)***	***OT2669 / 8***	***8028***
LINCOLN PROPERTY COM EPA ID:: TXD981058209	***100 CONGRESS AVE***	***NNE 0 - 1/8 (0.090 mi.)***	***MN2676 / 11***	***8043***
AUSTIN COMMUNITY COL EPA ID:: TXD981910078	***824 W 12TH***	***WNW 0 - 1/8 (0.090 mi.)***	***NW2686 / 11***	***8088***
HELIOVOLT EPA ID:: TXR000077969	8201 E RIVERSIDE DR	SE 0 - 1/8 (0.092 mi.)	PP2708 / 19	8117
EBARA TECHNOLOGIES I EPA ID:: TXR000036145	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2709 / 19***	***8130***
XBIOTECH USA EPA ID:: TXR000083744	8201 E RIVERSIDE DR	SE 0 - 1/8 (0.092 mi.)	PP2712 / 19	8205
AUSTIN ISD EPA ID:: TXD128098928	***201 E MARY***	***ESE 0 - 1/8 (0.093 mi.)***	***2715 / 14***	***8216***
JACK BROWN CLEANERS EPA ID:: TXD981590672	***907 W 24TH ST***	***W 0 - 1/8 (0.095 mi.)***	***PS2736 / 11***	***8245***
SBC EPA ID:: TXT490014826	817 N LOOP BLVD	WNW 0 - 1/8 (0.104 mi.)	QA2774 / 8	8367
CHATLEFF CONTROLS EPA ID:: TXD000352823	***205 INDUSTRIAL BLVD***	***ESE 0 - 1/8 (0.106 mi.)***	***PC2800 / 18***	***8519***
PLAZA SALTILLO EPA ID:: TXP490352566	800 E 4TH ST	E 0 - 1/8 (0.108 mi.)	QI2807 / 11	8528
DAVE TRANSPORTATION EPA ID:: TXD988064614	8300 IH 35 S ACCESS	ESE 0 - 1/8 (0.111 mi.)	2818 / 21	8656
CAPITAL PRINTING CO EPA ID:: TXD063101331	***213 E ALPINE RD***	***ESE 0 - 1/8 (0.114 mi.)***	***QP2833 / 14***	***8685***
A-TEX AUSTIN INC EPA ID:: TXD008126773	***4106 N LAMAR***	***NW 0 - 1/8 (0.114 mi.)***	***PX2835 / 8***	***8692***
COMET CLEANERS EPA ID:: TXD981590516	***9515 N LAMAR STE 108***	***ESE 0 - 1/8 (0.117 mi.)***	***QS2848 / 6***	***8708***
PRIME MOBILE LUBE EPA ID:: TXR000041160	***1405 MONTOPOLIS DRIV***	***NNE 0 - 1/8 (0.121 mi.)***	***2862 / 15***	***8734***
STATE PURCHASING AND EPA ID:: TXD982559908	***1711 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.122 mi.)***	***QD2865 / 11***	***8750***
MOBIL OIL 00AFT EPA ID:: TXD988038402	717 E 7TH ST	ENE 0 - 1/8 (0.122 mi.)	QC2869 / 11	8754
US DEPARTMENT OF JUS EPA ID:: TX0981903305	55 N IH 35	ESE 1/8 - 1/4 (0.137 mi.)	2907 / 14	8904
RED MCCOMBS COLLISIO EPA ID:: TXD980879795	***841 W 6TH STREET***	***WNW 1/8 - 1/4 (0.147 mi.)***	***QH2921 / 11***	***8929***
EXXON MOBIL CORPORAT EPA ID:: TXD988031936	***1004 W 24TH ST***	***W 1/8 - 1/4 (0.151 mi.)***	***RF2924 / 11***	***8941***
CITY OF AUSTIN EPA ID:: TXD981610637	***715 E 8TH ST***	***NE 1/8 - 1/4 (0.163 mi.)***	***RM2942 / 11***	***9085***
AUSTIN VEE DUB	***1111 OLD BASTROP HWY***	***E 1/8 - 1/4 (0.167 mi.)***	***RO2952 / 16***	***9194***

EPA ID:: TXD018778183				
UNIVAC OF TEXAS EPA ID:: TXD199840935	***1115 OLD BASTROP HWY***	***E 1/8 - 1/4 (0.168 mi.)***	***RO2957 / 16***	***9215***
MCCALLUM HIGH SCHOOL EPA ID:: TXD120710421	***5600 SUNSHINE DR***	***WNW 1/8 - 1/4 (0.170 mi.)***	***2961 / 8***	***9227***
THE LITHOPRINT CO EPA ID:: TX0000957423	1825 S IH 35	WSW 1/8 - 1/4 (0.171 mi.)	2962 / 14	9260
COFFEY LINCOLN MERCU EPA ID:: TXD030917090	***900 6TH ST***	***ENE 1/8 - 1/4 (0.176 mi.)***	***RT2973 / 11***	***9310***
CITY OF AUSTIN FLEET EPA ID:: TXD981901515	***714 E 8TH ST***	***NE 1/8 - 1/4 (0.179 mi.)***	***RM2982 / 11***	***9331***
KO MACHINE EPA ID:: TX0000141424	***620 CANION ST***	***ESE 1/8 - 1/4 (0.180 mi.)***	***RN2988 / 6***	***9422***
TCI COATINGS INC EPA ID:: TXD030927057	220 INDUSTRIAL BLVD	ESE 1/8 - 1/4 (0.191 mi.)	SA2997 / 18	9438
QUANTUM CLEAN EPA ID:: TXR000052944	***500 CENTER RIDGE DR***	***ESE 1/8 - 1/4 (0.192 mi.)***	***RZ3003 / 2***	***9478***
TEXAS DEPARTMENT OF EPA ID:: TXD981606338	***760 LOCKHART HWY***	***NNE 1/8 - 1/4 (0.198 mi.)***	***SH3028 / 15***	***9582***
TEXAS DEPARTMENT OF EPA ID:: TXD981908429	***760 US HIGHWAY 183 S***	***NNE 1/8 - 1/4 (0.198 mi.)***	***SH3029 / 15***	***9585***
AUSTIN NEURO DIAGNOS EPA ID:: TXD030930705	***1111 W 34TH STREET***	***WNW 1/8 - 1/4 (0.207 mi.)***	***3049 / 8***	***9684***
GOODRICH AEROSPACE C EPA ID:: TXD002775757	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3055 / 2***	***9897***
DOUG SCALES BODY SHO EPA ID:: TXD981058266	***2717 S 1ST ST***	***W 1/8 - 1/4 (0.220 mi.)***	***SU3086 / 14***	***10103***
AUSTIN ISD EPA ID:: TXD981585151	***1601 HASKELL ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***3087 / 14***	***10107***
J R BODY SHOP EPA ID:: TXD981145071	***1001 SAGEBRUSH***	***WNW 1/8 - 1/4 (0.224 mi.)***	***SV3090 / 3***	***10152***
UNIV OF TEXAS DEPT G EPA ID:: TXD988058236	CORNER OF 23RD AND S	E 1/8 - 1/4 (0.225 mi.)	3094 / 11	10159
UNICOPY CORP EPA ID:: TXD981594906	***1011 W ANDERSON LN***	***WNW 1/8 - 1/4 (0.228 mi.)***	***SX3098 / 6***	***10171***
TERMINIX COMPANY OF EPA ID:: TXD026031542	1206 PARKWAY	WNW 1/8 - 1/4 (0.229 mi.)	SS3102 / 11	10180
TEXAS DEPARTMENT OF EPA ID:: TXD981606361	***5710 GUADALUPE ST***	***ESE 1/8 - 1/4 (0.238 mi.)***	***TC3118 / 9***	***10247***
AUSTIN ISD EPA ID:: TXD982549354	***5900 GUADALUPE***	***ESE 1/8 - 1/4 (0.241 mi.)***	***TF3132 / 9***	***10353***
ONION CREEK VOLKSWAG EPA ID:: TXD980878870	***1014 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.242 mi.)***	***TE3137 / 11***	***10366***
STONE INDUSTRIAL SOL EPA ID:: TXD982284549	***301 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.244 mi.)***	***TH3142 / 18***	***10392***
CAPITOL CHEVROLET	***501 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.246 mi.)***	***TB3147 / 11***	***10472***

EPA ID:: TXD008944928				
DONS PAINT AND BODY	***1006 W 12TH***	***WNW 1/8 - 1/4 (0.248 mi.)***	***SS3156 / 11***	***10505***
EPA ID:: TXD981057920				

FUDS: Formerly Used Defense Sites

A review of the FUDS list, as provided by EDR, and dated 05/08/2023 has revealed that there is 1 FUDS site within approximately1 mile of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
MABRY ORDNANCE SHOP		S 1/8 - 1/4 (0.248 mi.)	3154 / 14	10500

DOD: Department of Defense Sites

A review of the DOD list, as provided by EDR, and dated 06/07/2021 has revealed that there is 1 DOD site within approximately1 mile of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ARMY FUTURES COMMAND		NNE 0 - 1/8 (0.047 mi.)	KW1989 / 11	6487

UXO: Unexploded Ordnance Sites

A review of the UXO list, as provided by EDR, and dated 11/09/2021 has revealed that there are 2 UXO sites within approximately1 mile of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
FORMER SKEET & TRAP		SSW 0 - 1/8 (0.073 mi.)	2465 / 20	7310
INDOOR SMALL ARMS RA		ESE 1/4 - 1/2 (0.483 mi.)	3288 / 20	11641

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

A review of the PFAS RCRA MANIFEST list, as provided by EDR, and dated 03/30/2023 has revealed that there is 1 PFAS RCRA MANIFEST site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
UT AUSTIN MAIN CAMPU		E 0 - 1/8 (0.025 mi.)	1550 / 11	4991

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

A review of the PFAS ECHO list, as provided by EDR, and dated 03/30/2023 has revealed that there are 15 PFAS ECHO sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ABIA AUS431		SSW 0 - 1/8 (0.015 mi.)	IM1195 / 20	3832
GROUND SERVICES INTE		SSW 0 - 1/8 (0.015 mi.)	IM1196 / 20	3833
GLOBAL AVIATION SERV		SSW 0 - 1/8 (0.015 mi.)	IM1197 / 20	3835
AUS STSLM		***SSW 0 - 1/8 (0.015 mi.)***	***1200 / 20***	***3836***
AMERICAN CLEANERS		ESE 0 - 1/8 (0.018 mi.)	DI1294 / 11	4145

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
MENZIES AVIATION ITP	***9401 CARGO AVE STE 2***	***SSW 0 - 1/8 (0.021 mi.)***	***IM1389 / 20***	***4374***
PRIMEFLIGHT AT AUS		***SSW 0 - 1/8 (0.021 mi.)***	***IM1390 / 20***	***4376***
CNANO TECHNOLOGY USA	***303 COLORADO ST***	***NNE 0 - 1/8 (0.030 mi.)***	***JY1703 / 11***	***5633***
SILICON LABRITORIES		NNE 0 - 1/8 (0.052 mi.)	MK2067 / 11	6628
AUSTIN BERGSTROM INT		NW 0 - 1/8 (0.074 mi.)	2474 / 20	7354
TEXAS AMERICAN RESOU		WSW 0 - 1/8 (0.084 mi.)	OK2601 / 11	7734
GAT AIRLINE GROUND S	***3600 PRESIDENTIAL BL***	***S 0 - 1/8 (0.109 mi.)***	***QL2815 / 20***	***8579***
DELSTAR TECHNOLOGIES		ESE 1/8 - 1/4 (0.141 mi.)	RE2909 / 18	8907
RAVEN INDUSTRIES INC		ESE 1/8 - 1/4 (0.188 mi.)	RZ2995 / 2	9436
TCI COATINGS INC		ESE 1/8 - 1/4 (0.243 mi.)	TH3141 / 18	10390

TX DRYCLEANERS: Drycleaner Registration Database Listing

A review of the TX DRYCLEANERS list, as provided by EDR, and dated 01/11/2023 has revealed that there are 33 TX DRYCLEANERS sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
IVORY CLEANERS & ALT AR Number: 24001637 CN Number: CN602511107 RN Number: RN102018033 Site Status: ACTIVE	***1901 RIO GRANDE ST***	***E 0 - 1/8 (0.011 mi.)***	***HQ951 / 11***	***2900***
MY CLEANERS & ALTERA AR Number: 24003737 CN Number: CN603002288 RN Number: RN105297667 Site Status: ACTIVE	3100 GUADALUPE ST	WNW 0 - 1/8 (0.012 mi.)	BD980 / 8	3001
JACK BROWN CLEANERS AR Number: 24000524 CN Number: CN600264543 RN Number: RN101445021 Site Status: ACTIVE	***2215 S CONGRESS AVE***	***E 0 - 1/8 (0.014 mi.)***	***FQ1129 / 14***	***3597***
ATLAS CLEANERS 2 AR Number: 24000992 CN Number: CN602463812 RN Number: RN104059803 Site Status: ACTIVE	6110 E RIVERSIDE DR	NNE 0 - 1/8 (0.015 mi.)	IN1206 / 15	3858
JACK BROWN CLEANERS AR Number: 24000713 AR Number: 24000524 CN Number: CN601536972 CN Number: CN600264543 RN Number: RN104416490 RN Number: RN103982518 Site Status: ACTIVE Site Status: INACTIVE	1901 E RIVERSIDE DR	WSW 0 - 1/8 (0.017 mi.)	FL1282 / 14	4077
FOUR SON'S QUALITY C AR Number: 24000524 AR Number: 24000432 CN Number: CN600264543	***3001 GUADALUPE***	***ESE 0 - 1/8 (0.019 mi.)***	***BF1325 / 8***	***4195***

EXECUTIVE SUMMARY

CN Number: CN602465189 RN Number: RN103967675 Site Status: ACTIVE				
ACE CLEANERS & ALTER AR Number: 24001229 CN Number: CN602482275 RN Number: RN103995502 Site Status: ACTIVE Site Status: INACTIVE	1117 S CONGRESS AVE	ESE 0 - 1/8 (0.020 mi.)	ET1343 / 14	4259
SWEET CLEANERS AR Number: 24000549 AR Number: 24000688 CN Number: CN602461147 CN Number: CN602463184 RN Number: RN100593409 Site Status: ACTIVE	***613 CONGRESS AVE***	***W 0 - 1/8 (0.023 mi.)***	***DG1482 / 11***	***4706***
WASHBURNS TOWN & COU AR Number: 24001686 AR Number: 24002648 CN Number: CN602513665 RN Number: RN104068432 Site Status: ACTIVE	1423 S CONGRESS AVE	ESE 0 - 1/8 (0.023 mi.)	FB1493 / 14	4745
GUTHRIE CLEANERS AR Number: 24001877 CN Number: CN602527186 RN Number: RN104090733 Site Status: ACTIVE	9200 N LAMAR BLVD ST	WNW 0 - 1/8 (0.027 mi.)	JU1633 / 6	5320
JACK BROWN CLEANERS AR Number: 24000524 CN Number: CN600264543 RN Number: RN102798402 Site Status: ACTIVE	***615 W MARTIN LUTHER***	***E 0 - 1/8 (0.041 mi.)***	***LF1897 / 11***	***6318***
LUCKY CLEANERS AR Number: 24004098 CN Number: CN603086448 RN Number: RN105029813 Site Status: ACTIVE	7601 N LAMAR BLVD ST	ESE 0 - 1/8 (0.044 mi.)	LN1941 / 6	6425
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN104410824 Site Status: ACTIVE Site Status: INACTIVE	1717 S PLEASANT VALL	SW 0 - 1/8 (0.047 mi.)	1992 / 15	6487
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN104409966 Site Status: ACTIVE	719A COLORADO ST	WNW 0 - 1/8 (0.052 mi.)	KT2070 / 11	6629
CAPITOL CLEANERS AR Number: 24000518 CN Number: CN602458135 RN Number: RN100654136	***1408 S 1ST STREET***	***WNW 0 - 1/8 (0.068 mi.)***	***OB2398 / 14***	***7180***

Site Status: ACTIVE				
WESTBANK DRY CLEANIN AR Number: 24007714 AR Number: 24001102 CN Number: CN605452960 CN Number: CN600381610 RN Number: RN104400213 Site Status: ACTIVE	112 E 4TH ST	NNE 0 - 1/8 (0.072 mi.)	MU2454 / 11	7299
MASTER VALET CLEANER AR Number: 24001773 CN Number: CN602523649 RN Number: RN104090568 Site Status: ACTIVE	3101 SPEEDWAY	ESE 0 - 1/8 (0.073 mi.)	NM2459 / 8	7307
DOLLARS & SENSE DRY AR Number: 24002565 CN Number: CN602616617 RN Number: RN103993713 Site Status: ACTIVE	***6929 AIRPORT BLVD ST***	***ESE 0 - 1/8 (0.075 mi.)***	***OP2488 / 6***	***7409***
REIDS CLEANERS 5 AR Number: 24000073 CN Number: CN600304638 RN Number: RN103955803 Site Status: ACTIVE	***3317 N LAMAR BLVD***	***WNW 0 - 1/8 (0.083 mi.)***	***OY2578 / 8***	***7664***
RICKS CLEANERS AR Number: 24007399 AR Number: 24000713 CN Number: CN605126432 CN Number: CN601536972 RN Number: RN107167249 Site Status: ACTIVE	3411 N LAMAR BLVD	WNW 0 - 1/8 (0.085 mi.)	OY2609 / 8	7737
STAR BRITE CLEANERS AR Number: 24007703 AR Number: 24007272 CN Number: CN605442177 CN Number: CN604848820 RN Number: RN103970935 Site Status: ACTIVE Site Status: IN PROGRESS	***501 W 15TH ST STE A***	***WNW 0 - 1/8 (0.085 mi.)***	***PE2614 / 11***	***7745***
MARTINIZING 94177 15 AR Number: 24007703 AR Number: 24002872 AR Number: 24000387 CN Number: CN605442177 CN Number: CN602462483 CN Number: CN600255533 RN Number: RN103970935 Site Status: ACTIVE	501 W 15TH ST STE A	WNW 0 - 1/8 (0.085 mi.)	PE2615 / 11	7751
CATHYS CLEANERS MLK AR Number: 24007052 CN Number: CN604567529 RN Number: RN107247181 Site Status: ACTIVE	***500 W MARTIN LUTHER***	***W 0 - 1/8 (0.086 mi.)***	***PA2630 / 11***	***7842***
TS CLEANERS AT TWIN	300 E OLTORF ST	NW 0 - 1/8 (0.090 mi.)	PL2673 / 14	8035

AR Number: 24006619 AR Number: 24000894 CN Number: CN604099226 CN Number: CN602476236 RN Number: RN103988093 Site Status: ACTIVE				
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN109983494 Site Status: ACTIVE	2201 S 1ST ST STE M	WNW 0 - 1/8 (0.093 mi.)	PQ2714 / 14	8215
THE SHORELINE BUILDI AR Number: 24002150 CN Number: CN600311765 RN Number: RN104101597 Site Status: ACTIVE	***98 SAN JACINTO BOULE***	***WNW 0 - 1/8 (0.095 mi.)***	***ND2732 / 11***	***8236***
BOSS MANUFACTURING AR Number: 24007743 CN Number: CN605478189 RN Number: RN100635911 Site Status: ACTIVE	***818 W YAGER LN***	***E 0 - 1/8 (0.103 mi.)***	***OA2767 / 4***	***8317***
FLOWER STATION AR Number: 24000524 CN Number: CN600264543 RN Number: RN102381365 Site Status: ACTIVE	***3100 N LAMAR BLVD***	***WNW 0 - 1/8 (0.106 mi.)***	***QE2795 / 8***	***8504***
STAR BRITE CLEANERS AR Number: 24007703 AR Number: 24003006 AR Number: 24007272 AR Number: 24000668 AR Number: 24003005 CN Number: CN605442177 CN Number: CN602776890 CN Number: CN600255533 CN Number: CN604848820 CN Number: CN602776833 RN Number: RN100712744 Site Status: ACTIVE	***9515 N LAMAR BLVD ST***	***ESE 0 - 1/8 (0.117 mi.)***	***QS2850 / 6***	***8712***
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN103961660 Site Status: ACTIVE Site Status: INACTIVE	907 W 12TH ST	WNW 1/8 - 1/4 (0.143 mi.)	RH2915 / 11	8920
AMERICAN CLEANERS AR Number: 24000170 CN Number: CN600404552 RN Number: RN103961173 Site Status: ACTIVE	407 N LAMAR BLVD	WNW 1/8 - 1/4 (0.237 mi.)	TA3114 / 11	10238
PTP OPERATING AR Number: 24007397	916A PRAIRIE TRL	WNW 1/8 - 1/4 (0.240 mi.)	3125 / 3	10303

AR Number: 24002374
CN Number: CN605126408
CN Number: CN602563447
RN Number: RN104467360
Site Status: ACTIVE

TIP TOP CLEANERS	***1014 N LAMAR BLVD ST***	***WNW 1/8 - 1/4 (0.242 mi.)***	***TE3138 / 11***	***10374***

AR Number: 24000073
AR Number: 24006422
AR Number: 24000670
CN Number: CN600304638
CN Number: CN603982570
CN Number: CN600306575
RN Number: RN100596766
Site Status: ACTIVE

TX Ind. Haz Waste: Industrial & Hazardous Waste Database

A review of the TX Ind. Haz Waste list, as provided by EDR, and dated 03/14/2023 has revealed that there are 197 TX Ind. Haz Waste sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CVS PHARMACY Registration Number: 95632	***2927 GUADALUPE ST***	***ESE 0 - 1/8 (0.012 mi.)***	***BG965 / 8***	***2935***
WALGREEN CO Registration Number: 85529	***9717 N LAMAR BLVD***	***ESE 0 - 1/8 (0.012 mi.)***	***N987 / 6***	***3012***
HOME DEPOT USA HD655 Registration Number: 87565	13309 N IH 35	N 0 - 1/8 (0.012 mi.)	HX1002 / 2	3113
RELIABLE AUTOMOTIVE Registration Number: 61401	***8225 N LAMAR BLVD***	***SE 0 - 1/8 (0.012 mi.)***	***X1012 / 6***	***3193***
CVS PHARMACY Registration Number: 91365	***2301 S CONGRESS AVE***	***ESE 0 - 1/8 (0.012 mi.)***	***FT1024 / 14***	***3240***
TUNE SMITHS Registration Number: 61814	***5405 N LAMAR BLVD***	***ESE 0 - 1/8 (0.013 mi.)***	***AN1032 / 8***	***3257***
CVS PHARMACY Registration Number: 91211	***2222 GUADALUPE ST***	***W 0 - 1/8 (0.013 mi.)***	***CA1042 / 11***	***3267***
QUALITY BODY SHOP Registration Number: 66345	***10720 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***J1049 / 3***	***3307***
CHUCKS CUSTOM AUTO Registration Number: 66336	11000 N LAMAR BLVD	WNW 0 - 1/8 (0.013 mi.)	ID1070 / 3	3372
THE CAR BAZAR Registration Number: 61759	***5540 N LAMAR BLVD***	***WNW 0 - 1/8 (0.013 mi.)***	***1078 / 8***	***3413***
AUSTIN AMERICAN STAT Registration Number: 66041	***308 GUADALUPE***	***WNW 0 - 1/8 (0.013 mi.)***	***DS1089 / 11***	***3463***
FINELINE SPORTSWEAR Registration Number: 76118	8407A N LAMAR BLVD	SE 0 - 1/8 (0.013 mi.)	V1095 / 6	3480
TWOMEY AUTO WORKS AU Registration Number: 81908	***1009 S CONGRESS AVE***	***ESE 0 - 1/8 (0.013 mi.)***	***ER1111 / 14***	***3522***
JACK BROWN CLEANERS	***2215 S CONGRESS AVE***	***E 0 - 1/8 (0.014 mi.)***	***FQ1129 / 14***	***3597***

Registration Number: 66313				
QUALITY ENGINE EXCHA Registration Number: 73608	***8807 B N LAMAR BLVD***	***SE 0 - 1/8 (0.014 mi.)***	***S1137 / 6***	***3642***
NORTH LAMAR AUTOMOTI Registration Number: 73603	***8807 N LAMAR BLVD ST***	***SE 0 - 1/8 (0.014 mi.)***	***S1140 / 6***	***3661***
B & B BODY & FRAME Registration Number: 66255	***6518 N LAMAR BLVD***	***WNW 0 - 1/8 (0.014 mi.)***	***AH1148 / 6***	***3696***
CALIBER COLLISION NO Registration Number: 76136	8735 N LAMAR BLVD	SE 0 - 1/8 (0.014 mi.)	II1152 / 6	3707
DUPLICATE OF 76136 Registration Number: 66257	8735 N LAMAR BLVD	SE 0 - 1/8 (0.014 mi.)	II1154 / 6	3713
MAACO Registration Number: 66188	8735 N LAMAR BLVD	SE 0 - 1/8 (0.014 mi.)	II1155 / 6	3715
GLENNS GARAGE Registration Number: 61203	***104 TRINITY ST***	***WNW 0 - 1/8 (0.014 mi.)***	***EE1174 / 11***	***3802***
DEPT OF PUBLIC WORKS Registration Number: 72382	411 W 2ND ST	WNW 0 - 1/8 (0.014 mi.)	DX1177 / 11	3808
ELECTRONINKS Registration Number: 98071	***7901 E RIVERSIDE DR***	***SSW 0 - 1/8 (0.015 mi.)***	***HE1204 / 19***	***3846***
MOBILE HOME HAVEN Registration Number: 68435	***11606 N LAMAR BLVD***	***WNW 0 - 1/8 (0.015 mi.)***	***E1227 / 3***	***3885***
TUNEUP MASTERS 1004 Registration Number: 74404	***5624 N LAMAR BLVD***	***WNW 0 - 1/8 (0.016 mi.)***	***IQ1233 / 8***	***3913***
CVS PHARMACY 7442 Registration Number: 95621	***11300 N LAMAR BLVD***	***WNW 0 - 1/8 (0.017 mi.)***	***G1269 / 3***	***4057***
HERAEUS AMERSIL Registration Number: 66140	***7715 E RIVERSIDE DR***	***WSW 0 - 1/8 (0.017 mi.)***	***HB1273 / 19***	***4068***
RISING SUN JAPANESE Registration Number: 74316	***4930 S CONGRESS AVE***	***WNW 0 - 1/8 (0.019 mi.)***	***IO1317 / 17***	***4182***
MORGAN AUTOMOTIVE Registration Number: 61249	***6200 N LAMAR BLVD***	***WNW 0 - 1/8 (0.019 mi.)***	***AJ1322 / 9***	***4190***
CASTROS CLEANERS Registration Number: 69773	***502 E 6TH ST***	***SW 0 - 1/8 (0.019 mi.)***	***DR1340 / 11***	***4236***
FLOYDS AUTO SALES & Registration Number: 73161	***5253 N LAMAR BLVD***	***ESE 0 - 1/8 (0.019 mi.)***	***AO1341 / 8***	***4241***
PHILLIPS PETROLEUM S Registration Number: 80689	***5301 N LAMAR BLVD***	***ESE 0 - 1/8 (0.020 mi.)***	***AO1367 / 8***	***4304***
MOBIL OIL Registration Number: 80648	2401 S CONGRESS AVE	SE 0 - 1/8 (0.020 mi.)	FU1377 / 14	4356
PINNACLE AIRLINES Registration Number: 88605	***9401 CARGO AVE STE 4***	***SSW 0 - 1/8 (0.021 mi.)***	***IM1393 / 20***	***4396***
AMERICAN CLEANERS FA Registration Number: 72367	***309 W 5TH ST***	***ESE 0 - 1/8 (0.021 mi.)***	***DI1404 / 11***	***4436***
COMPTROLLER OF PUBLI Registration Number: 72462	***111 E 17TH ST***	***ESE 0 - 1/8 (0.022 mi.)***	***JE1428 / 11***	***4503***
SHERWIN WILLIAMS	***500 E OLTORF ST***	***NW 0 - 1/8 (0.023 mi.)***	***JJ1471 / 14***	***4674***

EXECUTIVE SUMMARY

Registration Number: 66023				
SWEET CLEANERS Registration Number: 66873	***613 CONGRESS AVE***	***W 0 - 1/8 (0.023 mi.)***	***DG1482 / 11***	***4706***
TRAVIS COUNTY MEDICA Registration Number: 74706	705 E 14TH ST STE B1	ESE 0 - 1/8 (0.024 mi.)	JO1508 / 11	4823
AEGIS ASSOCIATES INC Registration Number: 72867	***44 EAST AVE STE 100***	***ESE 0 - 1/8 (0.025 mi.)***	***EL1521 / 14***	***4876***
TEXACO Registration Number: 75890	***1900 GUADALUPE ST***	***W 0 - 1/8 (0.025 mi.)***	***CD1530 / 11***	***4909***
MOBIL OIL 00AIX Registration Number: 80513	***1919 S PLEASANT VALL***	***NE 0 - 1/8 (0.025 mi.)***	***GF1538 / 15***	***4920***
CEN-TEX NISSAN INC Registration Number: 75002	***1400 S CONGRESS***	***WNW 0 - 1/8 (0.025 mi.)***	***EZ1549 / 14***	***4979***
AUSTIN AMERICAN STAT Registration Number: 30724	305 CONGRESS AVE	NNE 0 - 1/8 (0.026 mi.)	DY1559 / 11	5027
EXXON TIGERMART RS 6 Registration Number: 77278	2512 E RIVERSIDE DR	NE 0 - 1/8 (0.026 mi.)	HS1579 / 15	5188
METROLOGY LABORATORY Registration Number: 75088	119 CUMBERLAND RD	NE 0 - 1/8 (0.027 mi.)	1611 / 14	5260
C VAN R AUTOMOTIVE Registration Number: 69471	***604 W 6TH ST***	***ESE 0 - 1/8 (0.027 mi.)***	***DA1614 / 11***	***5264***
PAGE SOUTHERLAND PAG Registration Number: 75295	***606 WEST AVE***	***WNW 0 - 1/8 (0.027 mi.)***	***CZ1625 / 11***	***5278***
AUSTIN COMMUNITY COL Registration Number: 66189	***1212 RIO GRANDE ST***	***WNW 0 - 1/8 (0.027 mi.)***	***CO1632 / 11***	***5285***
THE UNIVERSITY OF TE Registration Number: 66154	***2617 SPEEDWAY STE 10***	***E 0 - 1/8 (0.027 mi.)***	***IV1635 / 11***	***5321***
MONTGOMERY WARD 2276 Registration Number: 66715	10600 N LAMAR BLVD	WNW 0 - 1/8 (0.028 mi.)	1651 / 3	5478
BEE BOP PRINTING Registration Number: 73873	***512 RIO GRANDE ST***	***WNW 0 - 1/8 (0.028 mi.)***	***DA1665 / 11***	***5505***
ELECTRIC UTILITY Registration Number: 72380	***300 WEST AVE***	***WNW 0 - 1/8 (0.028 mi.)***	***DL1667 / 11***	***5508***
SUNBECK AUTOMOTIVE Registration Number: 74906	***4241 S CONGRESS AVE***	***ESE 0 - 1/8 (0.029 mi.)***	***GX1688 / 18***	***5570***
DALES AUTO PARTS & M Registration Number: 72599	***3600 S CONGRESS AVE***	***WNW 0 - 1/8 (0.029 mi.)***	***GK1699 / 14***	***5605***
TEXAS SCHOOL FOR THE Registration Number: 74310	***1102 S CONGRESS AVE***	***ESE 0 - 1/8 (0.032 mi.)***	***KF1750 / 14***	***5837***
TEXAS HOUSE OF REPRE Registration Number: 84308	***105 W 15TH ST***	***WNW 0 - 1/8 (0.034 mi.)***	***CN1781 / 11***	***5936***
NORTH LAMAR SAFTI BR Registration Number: 61253	701 PROVINES DR STE	ESE 0 - 1/8 (0.035 mi.)	1803 / 3	6062
AUSTIN KAWASKI Registration Number: 61147	***10426 N LAMAR BLVD***	***WNW 0 - 1/8 (0.035 mi.)***	***JR1804 / 3***	***6064***
UNDELIVERABLE	10426 N LAMAR BLVD	WNW 0 - 1/8 (0.035 mi.)	JR1806 / 3	6068

Registration Number: 67348				
IMPORT CAR REPAIR Registration Number: 61222	***10631 N LAMAR BLVD***	***ESE 0 - 1/8 (0.038 mi.)***	***KV1860 / 3***	***6157***
31ST ST GARAGE Registration Number: 61879	***609 W 31ST ST***	***WNW 0 - 1/8 (0.039 mi.)***	***BE1863 / 8***	***6179***
COMPTROLLER OF PUBLI Registration Number: 72461	111 W 6TH ST	W 0 - 1/8 (0.039 mi.)	LA1876 / 11	6234
DALES AUTO PARTS Registration Number: 69418	602 W 34TH ST	WNW 0 - 1/8 (0.040 mi.)	IB1889 / 8	6290
AUSTIN NURSING & CON Registration Number: 66110	***110 E LIVE OAK***	***ESE 0 - 1/8 (0.040 mi.)***	***FM1890 / 14***	***6292***
JIMS BODY SHOP Registration Number: 61871	***6324 N LAMAR BLVD***	***WNW 0 - 1/8 (0.040 mi.)***	***AI1894 / 6***	***6302***
JACK BROWN CLEANERS Registration Number: 66309	***615 W MARTIN LUTHER***	***E 0 - 1/8 (0.041 mi.)***	***LF1897 / 11***	***6318***
CVS PHARMACY 7483 Registration Number: 96145	***500 CONGRESS AVE***	***SSW 0 - 1/8 (0.041 mi.)***	***LG1901 / 11***	***6350***
ORTEGON AUTO BODY RE Registration Number: 66356	***111 E WOODWARD ST***	***ESE 0 - 1/8 (0.041 mi.)***	***1905 / 14***	***6367***
EXXON RSL 69404 Registration Number: 77187	***6721 S CONGRESS AVE***	***ESE 0 - 1/8 (0.045 mi.)***	***LP1948 / 17***	***6446***
COMMUNICATION SPECIA Registration Number: 77588	603 DAVIS ST	WNW 0 - 1/8 (0.046 mi.)	LS1968 / 11	6464
PARAGON PRINTING & M Registration Number: 75720	***706 BRENTWOOD ST STE***	***ESE 0 - 1/8 (0.048 mi.)***	***LR2005 / 6***	***6500***
CLASSY CLEANERS SOUT Registration Number: 72344	111 W WILLIAM CANNON	WNW 0 - 1/8 (0.048 mi.)	LZ2007 / 17	6512
TQS Registration Number: 74633	111 W WILLIAM CANNON	WNW 0 - 1/8 (0.048 mi.)	LZ2009 / 17	6517
STRUTS CLEANERS Registration Number: 74797	1106 S 1ST ST	WNW 0 - 1/8 (0.049 mi.)	MC2023 / 14	6536
AUSTIN PAN AM CHEMIC Registration Number: 66145	***819 HOUSTON ST***	***WNW 0 - 1/8 (0.050 mi.)***	***MD2025 / 8***	***6539***
B&N AXLE SERV Registration Number: 72263	***219 W 4TH ST***	***NNE 0 - 1/8 (0.050 mi.)***	***ME2027 / 11***	***6541***
GOODYEAR AUTO SERVIC Registration Number: 73068	***115 E OLTORF ST***	***SE 0 - 1/8 (0.050 mi.)***	***MG2034 / 14***	***6568***
CVS PHARMACY Registration Number: 91424	***5526 S CONGRESS AVE***	***WNW 0 - 1/8 (0.050 mi.)***	***MH2039 / 17***	***6587***
JIMS CONOCO Registration Number: 61811	***1308 LAVACA ST***	***ESE 0 - 1/8 (0.053 mi.)***	***MR2113 / 11***	***6733***
MCMORRIS FORD Registration Number: 66293	***808 W 6TH***	***WNW 0 - 1/8 (0.053 mi.)***	***LX2129 / 11***	***6759***
EURO SPORT CYCLES Registration Number: 61158	616 W 34TH ST	WNW 0 - 1/8 (0.054 mi.)	2167 / 8	6777
PARKING GARAGE E	***1604 LAVACA ST***	***ESE 0 - 1/8 (0.056 mi.)***	***MZ2197 / 11***	***6844***

Registration Number: 75085				
MAJESTIC PRODUCTS Registration Number: 38485	***118 E ALPINE RD***	***ESE 0 - 1/8 (0.058 mi.)***	***NE2240 / 14***	***6870***
MAJESTIC PRODUCTS Registration Number: 30501	118 E ALPINE RD	ESE 0 - 1/8 (0.058 mi.)	NE2243 / 14	6900
WHITLEY Registration Number: 33359	801 BRAZOS TO 805	ESE 0 - 1/8 (0.060 mi.)	NH2273 / 11	6946
SOUTH FIRST CLEANERS Registration Number: 70592	***1905 S 1ST ST***	***WNW 0 - 1/8 (0.060 mi.)***	***NI2274 / 14***	***6948***
AUSTIN COMPLETE AUTO Registration Number: 69464	***821 BRENTWOOD***	***WNW 0 - 1/8 (0.063 mi.)***	***NO2309 / 6***	***6994***
I DEAL TIRE Registration Number: 61805	***2415 BASTROP HWY E***	***NE 0 - 1/8 (0.064 mi.)***	***NP2316 / 20***	***7005***
REBREU BODY & FRAME Registration Number: 74336	***822 KRAMER LN***	***WNW 0 - 1/8 (0.064 mi.)***	***LJ2324 / 3***	***7019***
BUMPER-TO-BUMPER CAR Registration Number: 72161	201 SAN JACINTO BLVD	WNW 0 - 1/8 (0.065 mi.)	KC2329 / 11	7035
BROADDUS CHEVRON Registration Number: 61306	***30 N IH 35***	***NE 0 - 1/8 (0.066 mi.)***	***MO2347 / 14***	***7089***
ACTION SCREEN GRAPHI Registration Number: 81596	305 E 5TH ST STE B	SSW 0 - 1/8 (0.066 mi.)	LH2353 / 11	7104
DYNA TUNE Registration Number: 61779	***3810 EAST AVE***	***ENE 0 - 1/8 (0.066 mi.)***	***MQ2366 / 8***	***7116***
EXXON MOBIL NO 67383 Registration Number: 77157	3807 EAST AVE	ENE 0 - 1/8 (0.067 mi.)	MQ2385 / 8	7165
CONCRETE CORING Registration Number: 66438	820 W YAGER LN	E 0 - 1/8 (0.067 mi.)	OA2395 / 4	7175
CONCRETE CORING Registration Number: 67361	820 W YAGER LN	E 0 - 1/8 (0.067 mi.)	OA2396 / 4	7177
CAPITOL CLEANERS Registration Number: 76060	1408 S 1ST ST	WNW 0 - 1/8 (0.068 mi.)	OB2399 / 14	7194
CITY OF AUSTIN SERVI Registration Number: 81211	600 RIVER ST	WNW 0 - 1/8 (0.068 mi.)	OC2405 / 11	7212
SERVICE CENTER 2 Registration Number: 72383	***600 RIVER ST***	***WNW 0 - 1/8 (0.068 mi.)***	***OC2406 / 11***	***7215***
MORGAN PRINTING Registration Number: 85575	***900 OLD KOENIG LANE***	***WNW 0 - 1/8 (0.068 mi.)***	***2413 / 8***	***7233***
AUSTIN FEDERAL COURT Registration Number: 81564	***501 W 5TH ST***	***WNW 0 - 1/8 (0.070 mi.)***	***OF2435 / 11***	***7279***
WR ROBBINS SECONDARY Registration Number: 69681	3908 AVENUE B	WNW 0 - 1/8 (0.075 mi.)	OO2484 / 8	7403
WALLACE ENGRAVING Registration Number: 33347	***407 LAVACA ST***	***ESE 0 - 1/8 (0.076 mi.)***	***OQ2499 / 11***	***7421***
POWELL OFFSET SERVIC Registration Number: 81992	2007 S 1ST ST	WNW 0 - 1/8 (0.077 mi.)	OR2510 / 14	7427
CERTIFIED BRAKES	***6507 SHIRLEY AVE***	***ESE 0 - 1/8 (0.078 mi.)***	***LR2522 / 6***	***7454***

Registration Number: 61168				
PALM HARBOR HOMES, I Registration Number: 81766	***830 BASTROP HIGHWAY***	***S 0 - 1/8 (0.080 mi.)***	***2545 / 15***	***7518***
MILLER BLUEPRINT Registration Number: 68813	***513 W 6TH ST***	***ESE 0 - 1/8 (0.081 mi.)***	***OI2550 / 11***	***7561***
REIDS CLEANERS 5 Registration Number: 82714	***3317 N LAMAR BLVD***	***WNW 0 - 1/8 (0.083 mi.)***	***OY2578 / 8***	***7664***
AUSTIN HWY TRK PARTS Registration Number: 61898	8204 N LAMAR BLVD	NW 0 - 1/8 (0.083 mi.)	OU2588 / 6	7693
FLASHCARDS Registration Number: 77714	***8204 N LAMAR BLVD ST***	***NW 0 - 1/8 (0.083 mi.)***	***OU2592 / 6***	***7703***
DISCOUNT DRIVE AXLE Registration Number: 20579	8204 N LAMAR BLVD ST	NW 0 - 1/8 (0.083 mi.)	OU2593 / 6	7705
AUSTIN CONVENTION CE Registration Number: 95778	***500 E CESAR CHAVEZ S***	***ESE 0 - 1/8 (0.084 mi.)***	***PB2597 / 11***	***7713***
ACCUGRAPHICS Registration Number: 66163	7801 N LAMAR BLVD ST	ESE 0 - 1/8 (0.086 mi.)	2616 / 6	7758
CHOTES CHEVRON Registration Number: 72409	***500 W MARTIN LUTHER***	***W 0 - 1/8 (0.086 mi.)***	***PA2627 / 11***	***7828***
SEAHOLM POWER PLANT Registration Number: 33939	***800 W CESAR CHAVEZ S***	***W 0 - 1/8 (0.086 mi.)***	***PG2633 / 11***	***7863***
HEART HOSPITAL OF AU Registration Number: 91603	***3801 N LAMAR BLVD***	***WNW 0 - 1/8 (0.086 mi.)***	***PH2635 / 8***	***7940***
AUSTIN FOREIGN CAR Registration Number: 61742	***510 W 6TH ST***	***ESE 0 - 1/8 (0.087 mi.)***	***OI2639 / 11***	***7966***
LABCORP AUSTIN Registration Number: 83603	3701 N LAMAR BLVD ST	WNW 0 - 1/8 (0.089 mi.)	OT2670 / 8	8031
LINCOLN PROPERTY COM Registration Number: 66361	***100 CONGRESS AVE***	***NNE 0 - 1/8 (0.090 mi.)***	***MN2676 / 11***	***8043***
CVS PHARMACY Registration Number: 91378	***4405 E RIVERSIDE DR***	***SW 0 - 1/8 (0.090 mi.)***	***PM2680 / 15***	***8068***
AUSTIN COMMUNITY COL Registration Number: 72452	***824 W 12TH ST***	***WNW 0 - 1/8 (0.090 mi.)***	***NW2685 / 11***	***8082***
PINNERGY Registration Number: 96523	111 CONGRESS AVE STE	NNE 0 - 1/8 (0.090 mi.)	MN2687 / 11	8091
PENTAGON TECHNOLOGIE Registration Number: 86110	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2710 / 19***	***8135***
PRODUCT RESEARCH FAC Registration Number: 86453	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2711 / 19***	***8188***
XBIOTECH USA Registration Number: 96348	8201 E RIVERSIDE DR	SE 0 - 1/8 (0.092 mi.)	PP2713 / 19	8209
AUSTIN ISD Registration Number: 69674	***201 E MARY***	***ESE 0 - 1/8 (0.093 mi.)***	***2715 / 14***	***8216***
JACK BROWN CLEANERS Registration Number: 66310	907 W 24TH ST	W 0 - 1/8 (0.095 mi.)	PS2735 / 11	8240
COASTAL STATES CRUDE	7901 E BEN WHITE BLV	E 0 - 1/8 (0.098 mi.)	2745 / 19	8267

Registration Number: 83388				
BOSS MANUFACTURING Registration Number: 66585	***818 W YAGER LN***	***E 0 - 1/8 (0.103 mi.)***	***OA2767 / 4***	***8317***
SBC HOMESTEAD 451 CE Registration Number: 66066	817 W NO LOOP BLVD	WNW 0 - 1/8 (0.104 mi.)	QA2772 / 8	8363
COMMEMORATIVE BRANDS Registration Number: 32601	***7211 CIRCLE S RD***	***ESE 0 - 1/8 (0.104 mi.)***	***QB2779 / 17***	***8389***
IMPORT MOTORS Registration Number: 61806	***3520 N LAMAR BLVD***	***WNW 0 - 1/8 (0.105 mi.)***	***OT2787 / 8***	***8491***
TEXAS GENERAL SERVIC Registration Number: 75087	***1500 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.105 mi.)***	***PD2790 / 11***	***8495***
CHATLEFF CONTROLS Registration Number: 30859	***205 INDUSTRIAL BLVD***	***ESE 0 - 1/8 (0.106 mi.)***	***PC2799 / 18***	***8516***
GENERAL SERVICES COM Registration Number: 75086	***1518 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.109 mi.)***	***QK2810 / 11***	***8541***
UNITED AIRLINES Registration Number: 96192	***3600 PRESIDENTIAL BL***	***S 0 - 1/8 (0.109 mi.)***	***QL2816 / 20***	***8581***
MINGOS BODY SHOP Registration Number: 66776	***811 MCPHAUL ST***	***WNW 0 - 1/8 (0.113 mi.)***	***QO2829 / 3***	***8680***
CAPITAL PRINTING CO Registration Number: 36353	***213 E ALPINE RD***	***ESE 0 - 1/8 (0.114 mi.)***	***QP2833 / 14***	***8685***
CAPITAL PRINTING Registration Number: 66229	213 E ALPINE RD	ESE 0 - 1/8 (0.114 mi.)	QP2834 / 14	8690
A-TEX AUSTIN INC Registration Number: 66043	***4106 N LAMAR***	***NW 0 - 1/8 (0.114 mi.)***	***PX2835 / 8***	***8692***
BLACK & DECKER Registration Number: 61752	***911 W ANDERSON LN***	***WNW 0 - 1/8 (0.115 mi.)***	***2836 / 6***	***8701***
STAR BRITE CLEANERS Registration Number: 61663	***9515 N LAMAR BLVD ST***	***ESE 0 - 1/8 (0.117 mi.)***	***QS2850 / 6***	***8712***
MCBRIDES GUNS Registration Number: 61835	***2913 N LAMAR BLVD***	***WNW 0 - 1/8 (0.117 mi.)***	***QJ2851 / 8***	***8725***
BRITISH MOTOR CAR SE Registration Number: 67321	***617 W POWELL LN # A***	***SE 0 - 1/8 (0.118 mi.)***	***QR2853 / 6***	***8728***
STATE PURCHASING AND Registration Number: 74655	***1711 SAN JACINTO BLV***	***ESE 0 - 1/8 (0.122 mi.)***	***QD2864 / 11***	***8737***
MOBIL OIL 00AFT Registration Number: 80296	***717 E 7TH ST***	***ENE 0 - 1/8 (0.122 mi.)***	***QC2871 / 11***	***8797***
BANNER SIGNS Registration Number: 82546	***650 CANION ST***	***ESE 0 - 1/8 (0.122 mi.)***	***QG2876 / 6***	***8803***
NETTLE WELDING WORKS Registration Number: 20506	***825 WAGON TRL***	***WNW 1/8 - 1/4 (0.127 mi.)***	***RA2890 / 3***	***8834***
NETTLE Registration Number: 78098	825 WAGON TRL	WNW 1/8 - 1/4 (0.127 mi.)	RA2891 / 3	8839
US POSTAL SERVICE AU Registration Number: 70524	300 E 9TH ST	ESE 1/8 - 1/4 (0.129 mi.)	RB2894 / 11	8847
FREEWHEELING	***2404 SAN GABRIEL ST***	***W 1/8 - 1/4 (0.136 mi.)***	***RF2906 / 11***	***8902***

Registration Number: 61193				
VERITIV OPERATING Registration Number: 97946	210 E SAINT ELMO RD	ESE 1/8 - 1/4 (0.142 mi.)	RE2912 / 18	8914
AUSTIN WASTE OIL SER Registration Number: 40706	7300B MARCELL ST	ESE 1/8 - 1/4 (0.146 mi.)	2919 / 6	8925
RED MCCOMBS COLLISDI Registration Number: 83309	841 W 6TH ST	WNW 1/8 - 1/4 (0.147 mi.)	QH2920 / 11	8927
RED MCCOMBS COLLISIO Registration Number: 66194	***841 W 6TH STREET***	***WNW 1/8 - 1/4 (0.147 mi.)***	***QH2921 / 11***	***8929***
EXXON CO. USA 64674 Registration Number: 77513	***1004 W 24TH ST***	***W 1/8 - 1/4 (0.151 mi.)***	***RF2922 / 11***	***8936***
EXXON MOBIL Registration Number: 77127	1004 W 24TH ST	W 1/8 - 1/4 (0.151 mi.)	RF2923 / 11	8938
CARMAX 7154 Registration Number: 87436	***13300 N IH 35***	***N 1/8 - 1/4 (0.158 mi.)***	***2928 / 2***	***8961***
GERMAN AUTOHAUS Registration Number: 68275	***902 SAGEBRUSH DR***	***WNW 1/8 - 1/4 (0.159 mi.)***	***QZ2930 / 3***	***8988***
TARGET STORE T3342 Registration Number: 97639	901 E 5TH ST STE 140	E 1/8 - 1/4 (0.159 mi.)	RJ2933 / 11	9009
CITY OF AUSTIN POLIC Registration Number: 69741	***715 E 8TH ST***	***NE 1/8 - 1/4 (0.163 mi.)***	***RM2943 / 11***	***9088***
AMERICAN PRINTERS EX Registration Number: 76533	***630 CANION ST***	***ESE 1/8 - 1/4 (0.166 mi.)***	***RN2950 / 6***	***9189***
SB WINGFIELD LANDFIL Registration Number: H1390	1111 OLD BASTROP HWY	E 1/8 - 1/4 (0.167 mi.)	RO2951 / 16	9192
AUSTIN VEE DUB Registration Number: 61743	***1111 OLD BASTROP HWY***	***E 1/8 - 1/4 (0.167 mi.)***	***RO2952 / 16***	***9194***
UNIVAC OF TEXAS Registration Number: 41484	***1115 OLD BASTROP HWY***	***E 1/8 - 1/4 (0.168 mi.)***	***RO2957 / 16***	***9215***
MCCALLUM HIGH SCHOOL Registration Number: 69668	***5600 SUNSHINE DR***	***WNW 1/8 - 1/4 (0.170 mi.)***	***2961 / 8***	***9227***
COFFEY LINCOLN MERCU Registration Number: 66260	***900 E 6TH ST***	***ENE 1/8 - 1/4 (0.176 mi.)***	***RT2974 / 11***	***9314***
BALCONES SPORTSWEAR Registration Number: 78307	***910 W 3RD ST***	***WNW 1/8 - 1/4 (0.178 mi.)***	***RL2981 / 11***	***9328***
CITY OF AUSTIN VES S Registration Number: 72378	***714 E 8TH ST***	***NE 1/8 - 1/4 (0.179 mi.)***	***RM2984 / 11***	***9375***
KO MACHINE Registration Number: 82064	***620 CANION ST***	***ESE 1/8 - 1/4 (0.180 mi.)***	***RN2988 / 6***	***9422***
TCI COATINGS Registration Number: 33277	***220 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.191 mi.)***	***SA2999 / 18***	***9466***
AUSTIN TECHNOLOGY CE Registration Number: 87221	500 CENTER RIDGE DR	ESE 1/8 - 1/4 (0.192 mi.)	RZ3002 / 2	9475
KWIK KOPY Registration Number: 66301	4011 MEDICAL PKWY	WNW 1/8 - 1/4 (0.197 mi.)	RV3019 / 8	9551
TEXAS DEPARTMENT OF	760 LOCKHART HWY	NNE 1/8 - 1/4 (0.198 mi.)	SH3030 / 15	9589

Registration Number: 66333				
TEXAS DEPT OF TRANSP Registration Number: 67567	760 US HIGHWAY 183 S	NNE 1/8 - 1/4 (0.198 mi.)	SH3031 / 15	9595
WAL-MART SUPERCENTER Registration Number: 88692	12900 N INTERSTATE 3	E 1/8 - 1/4 (0.203 mi.)	SK3042 / 2	9653
DELSTAR TECHNOLOGIES Registration Number: 23102	***220 E SAINT ELMO RD***	***ESE 1/8 - 1/4 (0.205 mi.)***	***SL3046 / 18***	***9666***
AUSTIN NEURO DIAGNOS Registration Number: 66008	***1111 W 34TH STREET***	***WNW 1/8 - 1/4 (0.207 mi.)***	***3049 / 8***	***9684***
ASCENSION SETON MEDI Registration Number: 70743	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***
GOODRICH AEROSPACE C Registration Number: 72925	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3056 / 2***	***9913***
BRYANT JANITORIAL SU Registration Number: 52136	305 E SAINT ELMO RD	ESE 1/8 - 1/4 (0.210 mi.)	SL3058 / 18	9932
SYSTEM CONTROL CENTE Registration Number: 85656	***2500 MONTOPOLIS DRIV***	***SSW 1/8 - 1/4 (0.218 mi.)***	***ST3079 / 19***	***10071***
DOUG SCALES BODY SHO Registration Number: 66355	***2717 S 1ST ST***	***W 1/8 - 1/4 (0.220 mi.)***	***SU3085 / 14***	***10099***
AUSTIN ISD Registration Number: 69676	***1601 HASKELL ST***	***NNE 1/8 - 1/4 (0.221 mi.)***	***3087 / 14***	***10107***
J R BODY SHOP Registration Number: 66413	***1001 SAGEBRUSH DR***	***WNW 1/8 - 1/4 (0.224 mi.)***	***SV3091 / 3***	***10155***
UNICOPY Registration Number: 70731	***1011 W ANDERSON LN***	***WNW 1/8 - 1/4 (0.228 mi.)***	***SX3099 / 6***	***10174***
TERMINIX OF AUSTIN Registration Number: 66069	1206 PARKWAY	WNW 1/8 - 1/4 (0.229 mi.)	SS3100 / 11	10177
TEXAS DEPARTMENT OF Registration Number: 70558	***5710 GUADALUPE ST***	***ESE 1/8 - 1/4 (0.238 mi.)***	***TC3117 / 9***	***10242***
PPD DEVELOPMENT Registration Number: 95475	7551 METRO CENTER DR	SSW 1/8 - 1/4 (0.239 mi.)	TD3121 / 19	10267
AUSTIN ISD Registration Number: 72711	5900 GUADALUPE ST	ESE 1/8 - 1/4 (0.241 mi.)	TF3133 / 9	10356
ONION CREEK VOLKSWAG Registration Number: 66195	***1014 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.242 mi.)***	***TE3137 / 11***	***10366***
TIP TOP CLEANERS LAU Registration Number: 70577	1014 N LAMAR BLVD ST	WNW 1/8 - 1/4 (0.242 mi.)	TE3139 / 11	10387
STONE INDUSTRIAL SOL Registration Number: 38205	***301 INDUSTRIAL BLVD***	***ESE 1/8 - 1/4 (0.244 mi.)***	***TH3144 / 18***	***10399***
CAPITOL CHEVROLET Registration Number: 66177	***501 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.246 mi.)***	***TB3146 / 11***	***10412***
DONS PAINT AND BODY Registration Number: 66335	***1006 W 12TH ST***	***WNW 1/8 - 1/4 (0.248 mi.)***	***SS3155 / 11***	***10501***
TEXAS DEPARTMENT OF Registration Number: 66101	***1100 W 49TH ST***	***WNW 1/8 - 1/4 (0.249 mi.)***	***TJ3160 / 8***	***10528***

EXECUTIVE SUMMARY

WI MANIFEST: Hazardous Waste Manifest Data

A review of the WI MANIFEST list, as provided by EDR, and dated 05/31/2018 has revealed that there is 1 WI MANIFEST site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ASCENSION SETON MEDI ACT Status: A FID: 0 EPA ID: TXD078495868	***1201 W 38TH STREET***	***WNW 1/8 - 1/4 (0.208 mi.)***	***SM3050 / 8***	***9691***

NY MANIFEST: Facility and Manifest Data

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there is 1 NY MANIFEST site within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
THE UNIVERSITY OF TE EPA ID: TXD980869184	***2617 SPEEDWAY STE 10***	***E 0 - 1/8 (0.027 mi.)***	***IV1636 / 11***	***5363***

TX IHW CORR ACTION: Industrial and Hazardous Waste Corrective Action Information

A review of the TX IHW CORR ACTION list, as provided by EDR, and dated 03/24/2023 has revealed that there are 19 TX IHW CORR ACTION sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
PINNACLE AIRLINES RN NUM: RN105586655 Program Id: 88605 Status: INACTIVE	***9401 CARGO AVE STE 4***	***SSW 0 - 1/8 (0.021 mi.)***	***IM1393 / 20***	***4396***
GREEN WATER TREATMEN RN NUM: RN105377568 Program Id: T2229 Status: INACTIVE	***600 W. CESAR CHAVEZ***	***ENE 0 - 1/8 (0.021 mi.)***	***JC1394 / 11***	***4403***
AUSTIN COMMUNITY COL RN NUM: RN100558378 Program Id: 66189 Status: INACTIVE	***1212 RIO GRANDE ST***	***WNW 0 - 1/8 (0.027 mi.)***	***CO1632 / 11***	***5285***
MAIN CAMPUS RN NUM: RN102797719 Program Id: 66154 Status: INACTIVE	2617 SPEEDWAY STE 10	E 0 - 1/8 (0.027 mi.)	IV1637 / 11	5442
5TH AND BRAZOS TOWER RN NUM: RN106100159 Program Id: T3489 Status: INACTIVE	501 BRAZOS ST	SSW 0 - 1/8 (0.033 mi.)	DP1771 / 11	5923
TRAMMELL CROW DAVIS RN NUM: RN104657903 Program Id: T2013	602 DAVIS ST	WNW 0 - 1/8 (0.047 mi.)	LS1982 / 11	6484

Status: INACTIVE				
PROPOSED CVS PHARMAC RN NUM: RN104921812 Program Id: T2087 Status: INACTIVE	***5526 S CONGRESS AVE***	***WNW 0 - 1/8 (0.050 mi.)***	***MH2043 / 17***	***6615***
MAJESTIC PRODUCTS RN NUM: RN100615277 Program Id: 38485 Status: INACTIVE	***118 E ALPINE RD***	***ESE 0 - 1/8 (0.058 mi.)***	***NE2240 / 14***	***6870***
LANDMARK ORGANIZATIO RN NUM: RN104646625 Program Id: T1783 Status: INACTIVE	401 NECHES ST	SW 0 - 1/8 (0.065 mi.)	KP2336 / 11	7071
AUBRY HILLS RN NUM: RN111679080 Program Id: T3789 Status: ACTIVE	8926 N LAMAR BLVD	WNW 0 - 1/8 (0.080 mi.)	2544 / 6	7517
SEAHOLM POWER PLANT RN NUM: RN100217348 Program Id: 33939 Status: INACTIVE	***800 W CESAR CHAVEZ S***	***W 0 - 1/8 (0.086 mi.)***	***PG2633 / 11***	***7863***
LINCOLN PROPERTY COM RN NUM: RN100594738 Program Id: 66361 Status: INACTIVE	***100 CONGRESS AVE***	***NNE 0 - 1/8 (0.090 mi.)***	***MN2676 / 11***	***8043***
PENTAGON TECHNOLOGIE RN NUM: RN108626706 Program Id: 96348 Status: INACTIVE	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2710 / 19***	***8135***
PRODUCT RESEARCH FAC RN NUM: RN101449874 Program Id: 86453 Status: INACTIVE	***8201 E RIVERSIDE DR***	***SE 0 - 1/8 (0.092 mi.)***	***PP2711 / 19***	***8188***
COMMEMORATIVE BRANDS RN NUM: RN102413382 Program Id: 32601 Status: INACTIVE	***7211 CIRCLE S RD***	***ESE 0 - 1/8 (0.104 mi.)***	***QB2779 / 17***	***8389***
PROPOSED SPRING COND RN NUM: RN105023113 Program Id: T2118 Status: ACTIVE	302 BOWIE ST	WNW 1/8 - 1/4 (0.176 mi.)	RL2969 / 11	9308
220 EAST ST ELMO ROA RN NUM: RN100665652 Program Id: T3648 Status: INACTIVE	***220 E SAINT ELMO RD***	***ESE 1/8 - 1/4 (0.205 mi.)***	***SL3047 / 18***	***9677***
GOODRICH AEROSPACE C RN NUM: RN101492189 Program Id: 72925 Program Id: T2902 Status: INACTIVE	***817 W HOWARD LN***	***NNE 1/8 - 1/4 (0.209 mi.)***	***SN3056 / 2***	***9913***
SYSTEM CONTROL CENTE	***2500 MONTOPOLIS DRIV***	***SSW 1/8 - 1/4 (0.218 mi.)***	***ST3079 / 19***	***10071***

EXECUTIVE SUMMARY

RN NUM: RN100615350
Program Id: 85656
Status: INACTIVE

TX PST STAGE 2: PST Stage 2

A review of the TX PST STAGE 2 list, as provided by EDR, and dated 07/17/2019 has revealed that there are 3 TX PST STAGE 2 sites within approximately 0.25 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
7-ELEVEN STORE 36642	***7715 E BEN WHITE BLV***	***WNW 0 - 1/8 (0.028 mi.)***	***JW1678 / 19***	***5533***
CARMAX 7154	***13300 N IH 35***	***N 1/8 - 1/4 (0.158 mi.)***	***2928 / 2***	***8961***
7 ELEVEN STORE 21884	***917 N LAMAR BLVD***	***WNW 1/8 - 1/4 (0.199 mi.)***	***SF3034 / 11***	***9598***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately1 mile of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
AUSTIN GAS LIGHT CO	100 COLORADO ST (COR	NNE 0 - 1/8 (0.055 mi.)	MK2192 / 11	6841
AUSTIN WATER LIGHT A	W. 5TH STREET	WNW 0 - 1/8 (0.107 mi.)	QF2803 / 11	8523

EDR Hist Auto: EDR Exclusive Historical Auto Stations

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 666 EDR Hist Auto sites within approximately 0.125 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
ADAMS SERVICE CO GAS	1901 RIO GRANDE ST	E 0 - 1/8 (0.011 mi.)	HQ949 / 11	2890
DYE CHARLES	1801 S CONGRESS	ESE 0 - 1/8 (0.011 mi.)	FG955 / 14	2915
FIEGEL GEO JR AUTO	606 GUADALUPE ST	WNW 0 - 1/8 (0.011 mi.)	HR958 / 11	2916
CIRCLE K CORPORATION	705 W 24TH ST	E 0 - 1/8 (0.012 mi.)	BX962 / 11	2918
GRAYBURG OIL CO STA	4301 GUADALUPE ST	ESE 0 - 1/8 (0.012 mi.)	AT966 / 8	2946
PAGS CARBURETOR	403 RIO GRANDE	WNW 0 - 1/8 (0.012 mi.)	967 / 11	2946
DODD & HURT TEXACO S	4227 GUADALUPE ST	NNE 0 - 1/8 (0.012 mi.)	AT969 / 8	2956
FRUZIA FINA SERVICE	8911 LAMAR BLVD N	ESE 0 - 1/8 (0.012 mi.)	R970 / 6	2957
FARRIS LUTHER L FILL	4401 GUADALUPE	ESE 0 - 1/8 (0.012 mi.)	HT974 / 8	2991
MARX W E MOTOR	4405 GUADALUPE ST	ESE 0 - 1/8 (0.012 mi.)	HT979 / 8	3000
UNIVERSITY TEXACO	3100 GUADALUPE	WNW 0 - 1/8 (0.012 mi.)	BD982 / 8	3007
PAYLESS GAS	6608 LAMAR BLVD N	WNW 0 - 1/8 (0.012 mi.)	AG991 / 6	3045
FOOD MART GAS & FOOD	6301 LAMAR BLVD N	ESE 0 - 1/8 (0.012 mi.)	AI993 / 6	3070
AUTOSYSTEMS WORKSHOP	10805 N LAMAR BLVD A	ESE 0 - 1/8 (0.012 mi.)	HV997 / 3	3072
PEARSON WESLEY H FIL	4413 GUADALUPE	ESE 0 - 1/8 (0.012 mi.)	HW999 / 8	3081
AUSTIN WATER METER	607 RIO GRANDE	WNW 0 - 1/8 (0.012 mi.)	DA1004 / 11	3181
KRENEK E J AUTO	5200 LAMAR BLVD	WNW 0 - 1/8 (0.012 mi.)	AP1008 / 8	3188
RELIABLE AUTOMOTIVE	8225 LAMAR BLVD N	SE 0 - 1/8 (0.012 mi.)	X1011 / 6	3193

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
UMPHRIES BILL TEXACO	2000 E RIVERSIDE	NE 0 - 1/8 (0.012 mi.)	FO1016 / 14	3197
POTTERS SERVICE STA	3400 GUADALUPE	WNW 0 - 1/8 (0.012 mi.)	IB1019 / 8	3222
GENOA TRANSMISSIONS	6534 S CONGRESS AVE	WNW 0 - 1/8 (0.012 mi.)	HL1022 / 17	3229
BOYEA ASSOCIATES INC	7530 N LAMAR	WNW 0 - 1/8 (0.012 mi.)	Z1027 / 6	3254
TEXAS PACIFIC COAL O	2714 GUADALUPE	WSW 0 - 1/8 (0.013 mi.)	BM1030 / 11	3256
WAYNE BARBEE MUFFLER	5405 LAMAR BLVD N	ESE 0 - 1/8 (0.013 mi.)	AN1033 / 8	3259
ADAMS HENRY J	1900 SPEEDWAY	ENE 0 - 1/8 (0.013 mi.)	1045 / 11	3305
RIO GRANDE GAS	701 W 24TH	E 0 - 1/8 (0.013 mi.)	BX1047 / 11	3306
SCOTTVS AUTOMOTIVE S	5922 LAMAR BLVD N	WNW 0 - 1/8 (0.013 mi.)	1048 / 8	3306
PIRRUNG MOBILE SERV	7400 CONGRESS AVE S	WNW 0 - 1/8 (0.013 mi.)	1051 / 21	3313
MONARCH TRANSMISSION	10409 LAMAR BLVD N	ESE 0 - 1/8 (0.013 mi.)	1052 / 3	3314
35TH AND GUADALUPE S	3508 GUADALUPE ST	WNW 0 - 1/8 (0.013 mi.)	IC1053 / 8	3314
RITTERS SERVICE STAT	2718 GUADALUPE ST	WSW 0 - 1/8 (0.013 mi.)	BM1054 / 11	3315
FLAMINGO AUTOMOTIVE	3512 GUADALUPE ST	WNW 0 - 1/8 (0.013 mi.)	IC1061 / 8	3359
HUDSON OIL CO NO 91	2001 RIVERSIDE DR E	SW 0 - 1/8 (0.013 mi.)	FO1066 / 14	3370
2800 02 SMITH J J GA	2800 GUADALUPE ST	WSW 0 - 1/8 (0.013 mi.)	HY1068 / 11	3371
SCHARFE DENNIS F BUI	11000 N LAMAR BLVD	WNW 0 - 1/8 (0.013 mi.)	ID1072 / 3	3378
DONCO TRUCK & AUTOMO	8305 LAMAR BLVD N	SE 0 - 1/8 (0.013 mi.)	W1076 / 6	3383
CENTRAL TEXAS HARLEY	6310 LAMAR BLVD N	WNW 0 - 1/8 (0.013 mi.)	AI1079 / 6	3415
SIGMOR SHAMROCK SERV	10810 LAMAR BLVD N	WNW 0 - 1/8 (0.013 mi.)	HV1080 / 3	3416
A LONDON BRIDGE AUTO	6406 LAMAR BLVD N	WNW 0 - 1/8 (0.013 mi.)	IE1084 / 6	3458
THREADGILLS FILL STA	6416 LAMAR BLVD	WNW 0 - 1/8 (0.013 mi.)	IE1098 / 6	3488
PHILLIPS SIXTY SIX S	11100 LAMAR BLVD N	WNW 0 - 1/8 (0.013 mi.)	I1101 / 3	3490
UNIVERSITY SERVICE C	2412 GUADALUPE	W 0 - 1/8 (0.013 mi.)	BV1107 / 11	3517
COURTNEY SIXTY SIX	8603 LAMAR BLVD	SE 0 - 1/8 (0.013 mi.)	U1115 / 6	3538
WALLACE TEXACO	2215 CONGRESS AVE	E 0 - 1/8 (0.014 mi.)	FQ1128 / 14	3597
RAMIREZ TEXACO STATI	2215 S CONGRESS	E 0 - 1/8 (0.014 mi.)	FQ1130 / 14	3640
A ME KANNIKS OTTO NE	11104 LAMAR BLVD N	WNW 0 - 1/8 (0.014 mi.)	H1133 / 3	3640
QUICK LUBE CAR SERV	10300 LAMAR BLVD N	WNW 0 - 1/8 (0.014 mi.)	K1134 / 3	3641
AUSTIN QUALITY ENGIN	8807 LAMAR BLVD N	SE 0 - 1/8 (0.014 mi.)	S1138 / 6	3660
CONOCO FOOD MART	6214 E RIVERSIDE DR	NNE 0 - 1/8 (0.014 mi.)	GQ1141 / 15	3666
YOUNG TROY H GULF	3900 CONGRESS AVE	WNW 0 - 1/8 (0.014 mi.)	GR1144 / 14	3695
FAIRLVIEW GARAGE	5804 CONGRESS AVE S	WNW 0 - 1/8 (0.014 mi.)	HJ1146 / 17	3695
CECILS WRECKER SERV	4404 CONGRESS AVE S	WNW 0 - 1/8 (0.014 mi.)	HA1150 / 17	3706
KLUGE M C AUTO REPR	214 6TH E	NNE 0 - 1/8 (0.014 mi.)	DP1158 / 11	3744
HEBERT MOBIL STA	5630 LAMAR BLVD N	WNW 0 - 1/8 (0.014 mi.)	AL1169 / 8	3799
TOLSON OIL CO NO	409 E 7TH ST	NNE 0 - 1/8 (0.014 mi.)	DM1172 / 11	3801
SCHWABE AUTOMOTIVE R	104 TRINITY ST	WNW 0 - 1/8 (0.014 mi.)	EE1173 / 11	3802
REID GEO W AUTO	503 NECHES	SW 0 - 1/8 (0.014 mi.)	DU1175 / 11	3804
GULF COAST COALITION	816 CONGRESS AVE	ESE 0 - 1/8 (0.014 mi.)	IK1183 / 11	3817
AVS FOOD SERVICE INC	611 NECHES	NE 0 - 1/8 (0.015 mi.)	IL1189 / 11	3830
B JATCO TRANSMISSION	8745 LAMAR BLVD N	SE 0 - 1/8 (0.015 mi.)	HZ1190 / 6	3830
MC CULLOUGHS SERV	5000 LAMAR BLVD	WNW 0 - 1/8 (0.015 mi.)	AQ1191 / 8	3831
JOHNSON J W SERVICE	510 E 5TH ST	SW 0 - 1/8 (0.015 mi.)	DU1192 / 11	3831
TIP TOP GARAGE AUTO	604 NECHES	SSW 0 - 1/8 (0.015 mi.)	IL1194 / 11	3832
BOWLES GARAGE AUTO R	306 INTERREGIONAL HW	ESE 0 - 1/8 (0.015 mi.)	1198 / 11	3836
WITTS SERV STA	2704 CONGRESS AVE	WNW 0 - 1/8 (0.015 mi.)	GE1199 / 14	3836
HARTUNG PHILLIPS 66	3106 GUADALUPE ST	WNW 0 - 1/8 (0.015 mi.)	BD1201 / 8	3838
SMITH ELMER L FILLIN	3711 GUADALUPE	ESE 0 - 1/8 (0.015 mi.)	BB1202 / 8	3838
WHITES GARAGE FILLIN	304 JOHANNA W	ESE 0 - 1/8 (0.015 mi.)	1211 / 14	3861
ACE AUTO REPAIR	6108 RIVERSIDE DR	NNE 0 - 1/8 (0.015 mi.)	IN1221 / 15	3883
AUS TEX BODY SHOP	6706 LAMAR BLVD N	WNW 0 - 1/8 (0.016 mi.)	AF1230 / 6	3888
GRIFFIN JACK SERV	5624 LAMAR BLVD N	WNW 0 - 1/8 (0.016 mi.)	IQ1234 / 8	3915
ROBBINS RUSSELL H AU	4311 AVENUE A	SW 0 - 1/8 (0.016 mi.)	IR1236 / 8	3929
DALES UNIVERSITY AUT	3402 GUADALUPE ST	WNW 0 - 1/8 (0.016 mi.)	IB1239 / 8	3930
ELLIOTT CARL L	300 CONGRESS AVE	NNE 0 - 1/8 (0.016 mi.)	DY1242 / 11	3934

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
SPIRES TIRE CO INC	3510 GUADALUPE	WNW 0 - 1/8 (0.016 mi.)	IC1243 / 8	3934
THOMPSON BILL INC	417 6TH W	WNW 0 - 1/8 (0.016 mi.)	DE1245 / 11	3934
CEARLEY E A FILL STA	3700 GUADALUPE ST	WNW 0 - 1/8 (0.016 mi.)	BB1248 / 8	3935
JIFFY LUBE AUTO REPR	3809 GUADALUPE ST	ESE 0 - 1/8 (0.016 mi.)	BA1249 / 8	3935
AUSTIN RADIATOR WORK	4926 LAMAR BLVD N	WNW 0 - 1/8 (0.016 mi.)	AR1256 / 8	3961
SHAFER C D SERVICE S	2600 GUADALUPE	W 0 - 1/8 (0.016 mi.)	BO1257 / 11	3962
JONES MACK SERVICE S	11400 N LAMAR	WNW 0 - 1/8 (0.016 mi.)	F1263 / 3	4032
AUTOMATIC TRANS	1300 CONGRESS AVE	WNW 0 - 1/8 (0.016 mi.)	CP1264 / 11	4032
DIAMOND SHAMROCK INC	1620 E RIVERSIDE	NE 0 - 1/8 (0.017 mi.)	FF1267 / 14	4044
KORNFUEHRER TEXACO S	701 6TH ST W	WNW 0 - 1/8 (0.017 mi.)	DA1275 / 11	4075
KORNFUEHRER TEXACO S	701 6TH ST W	WNW 0 - 1/8 (0.017 mi.)	DA1276 / 11	4075
AUSTIN GOODYEAR CO	701 6TH W	WNW 0 - 1/8 (0.017 mi.)	DA1277 / 11	4075
PETRIFIED SERV STA	4505 GUADALUPE	ESE 0 - 1/8 (0.017 mi.)	IT1280 / 8	4076
GAS A TERIA INC	3200 GUADALUPE	WNW 0 - 1/8 (0.017 mi.)	IJ1283 / 8	4080
CHRISTIES CONOCO SER	400 BARTON SPRINGS R	SE 0 - 1/8 (0.017 mi.)	EH1287 / 11	4099
CHTRISTIES CONOCO	400 BARTON SPRINGS R	SE 0 - 1/8 (0.017 mi.)	EH1288 / 11	4099
AUSTIN MOTORCYCLE CO	1611 GUADALUPE ST	ESE 0 - 1/8 (0.018 mi.)	CJ1292 / 11	4138
PEOPLES SINCLAIR	4926 LAMAR BLVD N	WNW 0 - 1/8 (0.018 mi.)	AR1295 / 8	4146
M & M SINCLAIR	4926 LAMAR BLVD	WNW 0 - 1/8 (0.018 mi.)	AR1296 / 8	4147
PDQ FOOD MART	4714 S CONGRESS	WNW 0 - 1/8 (0.018 mi.)	IU1300 / 17	4160
STONE BOB	2300 S CONGRESS AVE	W 0 - 1/8 (0.018 mi.)	FQ1301 / 14	4160
PIT STOP INC THE AUT	700 5TH ST W	WNW 0 - 1/8 (0.018 mi.)	DD1305 / 11	4171
N W COR GOAD MOTOR	104 GUADALUPE	ESE 0 - 1/8 (0.018 mi.)	EB1309 / 11	4172
SERVICE STATION	2500 SPEEDWAY	E 0 - 1/8 (0.018 mi.)	1313 / 11	4175
GULF REFG CO STA NO	26 GUADALUPE ST	NNE 0 - 1/8 (0.019 mi.)	IW1319 / 11	4189
NORTH LAMAR AUTOMOTI	6200 LAMAR BLVD N	WNW 0 - 1/8 (0.019 mi.)	AJ1323 / 9	4194
RIVERSIDE SERVICE ST	207 CONGRESS AVE S	WNW 0 - 1/8 (0.019 mi.)	IX1324 / 11	4195
MCWILLIAMS & FIEGEL	3001 GUADALUPE	ESE 0 - 1/8 (0.019 mi.)	BF1327 / 8	4204
PAUL SHERRILLS EXXON	343 S CONGRESS AVE	NE 0 - 1/8 (0.019 mi.)	EJ1336 / 14	4210
GARDNERS GULL SERVIC	5253 LAMAR BLVD N	ESE 0 - 1/8 (0.019 mi.)	AO1342 / 8	4259
BUTLER WILLIAM A	1123 S CONGRESS	ESE 0 - 1/8 (0.020 mi.)	ET1346 / 14	4262
BURNETTE L B O	118 31ST W	ESE 0 - 1/8 (0.020 mi.)	1351 / 8	4269
MIDAS MUFFLER SHOP	2828 GUADALUPE ST	WSW 0 - 1/8 (0.020 mi.)	BJ1353 / 8	4269
SCHRAMM SINCLAIR	301 CONGRESS AVE	NNE 0 - 1/8 (0.020 mi.)	DY1354 / 11	4269
KORNFUEHRER SERV	704 6TH W	WNW 0 - 1/8 (0.020 mi.)	DA1355 / 11	4270
MOTOR INN	118 7TH E	WNW 0 - 1/8 (0.020 mi.)	DF1358 / 11	4270
HARRIS A L AUTO REPR	119 8TH E	WNW 0 - 1/8 (0.020 mi.)	DB1359 / 11	4271
SPIGHT AUTOMOTIVE	6901 N LAMAR BLVD	ESE 0 - 1/8 (0.020 mi.)	IZ1361 / 6	4271
HUMBLE PRODUCTS SERV	5319 LAMAR BLVD N	ESE 0 - 1/8 (0.020 mi.)	AO1364 / 8	4299
AMERICAN MUFFLER SHO	5301 LAMAR BLVD N	ESE 0 - 1/8 (0.020 mi.)	AO1370 / 8	4339
TENNISON PROPERTIES	19TH GUADALUPE	NNE 0 - 1/8 (0.020 mi.)	IW1371 / 11	4340
CHARLES DIRK TALBOT	2401 S CONGRESS AVE	SE 0 - 1/8 (0.020 mi.)	FU1375 / 14	4351
HUMBLE OIL & REFG	800 12TH W	WNW 0 - 1/8 (0.021 mi.)	JA1382 / 11	4369
BREWER SERVICE	801 12TH W	WNW 0 - 1/8 (0.021 mi.)	JA1383 / 11	4369
DIAMOND SHAMROCK INC	6307 E RIVERSIDE DR	SSW 0 - 1/8 (0.021 mi.)	1386 / 15	4370
TEXACO WINDPOWER CO	823 CONGRESS AVE 515	WNW 0 - 1/8 (0.021 mi.)	IK1408 / 11	4447
PATTONS AUTO HOTEL	116 7TH E	WNW 0 - 1/8 (0.022 mi.)	DF1422 / 11	4498
MOTORCYCLE SALES	213 CONGRESS AVE	SSW 0 - 1/8 (0.022 mi.)	DY1431 / 11	4552
STEWART W T TEXACO	4712 CONGRESS AVE S	WNW 0 - 1/8 (0.022 mi.)	IU1434 / 17	4573
MURPHY R L TEX	4712 CONGRESS AVE	WNW 0 - 1/8 (0.022 mi.)	IU1435 / 17	4573
CLAWSONS TEXACO SERV	4712 CONGRESS AVE S	WNW 0 - 1/8 (0.022 mi.)	IU1436 / 17	4573
BEAR AUTOMOTIVE I EP	405 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1439 / 11	4575
BEAR AUTOMOTIVE REPR	405 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1440 / 11	4575
ELLIOTTS RADIATOR	406 7TH E	NNE 0 - 1/8 (0.023 mi.)	DM1441 / 11	4575
ELLIOTTS RADIATOR SH	406 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1442 / 11	4575
GAS MART GR	409 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1444 / 11	4576

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
AUTO REPAIRS CO	408 7TH E	NNE 0 - 1/8 (0.023 mi.)	DM1445 / 11	4576
JENSENS HARRY AUTO R	408 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1446 / 11	4576
ALANIZ LOUIS AUTO RE	408 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1447 / 11	4577
GAS A TERIA INC	409 7TH E	NNE 0 - 1/8 (0.023 mi.)	DM1448 / 11	4577
CITGO GRO	6301 RIVERSIDE DR	SSW 0 - 1/8 (0.023 mi.)	GQ1450 / 15	4578
ABC MOBILE BRAKE	519 S 1ST ST	WNW 0 - 1/8 (0.023 mi.)	1454 / 14	4635
ELLIS & SALAZAR GARA	403 7TH ST E	NNE 0 - 1/8 (0.023 mi.)	DM1456 / 11	4636
ELLIS BATTERY & AUTO	403 7TH E	NNE 0 - 1/8 (0.023 mi.)	DM1457 / 11	4636
RAVENS GARAGE	605 RED RIVER CT	NE 0 - 1/8 (0.023 mi.)	JH1458 / 11	4636
DIAMOND SHAMROCK	2105 S CONGRESS	ESE 0 - 1/8 (0.023 mi.)	FK1462 / 14	4667
REED OIL CO GAS STA	7135 LAMAR BLVD N	ESE 0 - 1/8 (0.023 mi.)	AC1465 / 6	4668
METZENTHIN BROS AUTO	102 7TH W	ESE 0 - 1/8 (0.023 mi.)	DF1468 / 11	4669
SANDGARTENS SERVICE	510 RED RIVER CT	NE 0 - 1/8 (0.023 mi.)	DU1472 / 11	4680
GILBERTS AUTO ELECTR	84 EAST AVE	ESE 0 - 1/8 (0.023 mi.)	JF1473 / 14	4680
CAR CARE CENTER	3120 GUADALUPE ST	WNW 0 - 1/8 (0.023 mi.)	JK1476 / 8	4693
RAILROAD COMMISSION	1701 CONGRESS AVE	WNW 0 - 1/8 (0.023 mi.)	JL1479 / 11	4703
BUSH NET	105 E ANNIE	ESE 0 - 1/8 (0.023 mi.)	FG1485 / 14	4722
ROSENTRITT H L GA	115 8TH E	WNW 0 - 1/8 (0.023 mi.)	DB1486 / 11	4723
DAY R L GARAGE AUTO	114 8TH E	WNW 0 - 1/8 (0.023 mi.)	DB1487 / 11	4723
DAY R L AUTO REPR	114 7TH E	WNW 0 - 1/8 (0.023 mi.)	DF1491 / 11	4744
CIRCLE K STORES INC	8201 N LAMAR BLVD	SE 0 - 1/8 (0.023 mi.)	JM1495 / 6	4774
LOTT C G FILL STA	711 6TH W	WNW 0 - 1/8 (0.024 mi.)	DA1498 / 11	4775
SCOGIN EXXON PRODUCT	7205 LAMAR BLVD N	ESE 0 - 1/8 (0.024 mi.)	AB1500 / 6	4783
7-ELEVEN INC	12430 N LAMAR BLVD	W 0 - 1/8 (0.024 mi.)	JN1503 / 2	4817
EXXON MOBIL CORP	1005 CONGRESS AVE ST	ESE 0 - 1/8 (0.024 mi.)	CV1506 / 11	4818
R & R SERVICE STA FI	214 CONGRESS AVE	SSW 0 - 1/8 (0.024 mi.)	DY1510 / 11	4825
LEGELTS FOREIGN SPOR	5412 LAMAR BLVD N	WNW 0 - 1/8 (0.025 mi.)	AM1518 / 8	4872
CURTIS GARAGE	602 NECHES ST	SW 0 - 1/8 (0.025 mi.)	DR1520 / 11	4876
ALFA OF AUSTIN	510 RIO GRANDE ST	WNW 0 - 1/8 (0.025 mi.)	DA1523 / 11	4884
BROWNS TWIN OAKS 66	620 OLTORF ST E	SE 0 - 1/8 (0.025 mi.)	FY1524 / 14	4884
BUSKES GARAGE	3208 GUADALUPE	WNW 0 - 1/8 (0.025 mi.)	IJ1526 / 8	4885
SPEEDY ALIGNMENT WHE	111 OLTORF ST E	SE 0 - 1/8 (0.025 mi.)	FU1527 / 14	4885
CAMPBELL A B SERVICE	1900 GUADALUPE	W 0 - 1/8 (0.025 mi.)	CD1531 / 11	4912
TETCO STORES INC	1919 S PLEASANT VALL	NE 0 - 1/8 (0.025 mi.)	GF1539 / 15	4927
DAY R L AUTO REPR	112 7TH E	WNW 0 - 1/8 (0.025 mi.)	DF1542 / 11	4962
KORNFUEHRER TEXACO S	701 W 6TH ST	WNW 0 - 1/8 (0.025 mi.)	DA1547 / 11	4971
NORTH LAMAR PHILLIPS	8700 LAMAR BLVD N	NW 0 - 1/8 (0.025 mi.)	T1552 / 6	4993
MASON IRA SERV STA	713 6TH W	WNW 0 - 1/8 (0.025 mi.)	DA1554 / 11	5020
DELZELL & DEMENT AUT	508 BRAZOS ST	SSW 0 - 1/8 (0.025 mi.)	JP1556 / 11	5027
DARES HUMBLE SERV	700 24TH W	W 0 - 1/8 (0.026 mi.)	BW1557 / 11	5027
GRAYBURG OIL CO STA	1601 CONGRESS AVE E	ESE 0 - 1/8 (0.026 mi.)	JQ1558 / 11	5027
AUSTIN MOTOR SALES C	503 SAN JACINTO ST	SSW 0 - 1/8 (0.026 mi.)	DQ1560 / 11	5044
HICKMAN HUMBLE SERVI	700 W 24TH ST	E 0 - 1/8 (0.026 mi.)	BW1562 / 11	5045
SIGMOR SHAMROCK SERV	3706 GUADALUPE ST	WNW 0 - 1/8 (0.026 mi.)	BB1563 / 8	5045
SLAUSONS TEXACO	10500 LAMAR BLVD N	WNW 0 - 1/8 (0.026 mi.)	JR1568 / 3	5094
B PAC PITSTOP AUTO M	10111 LAMAR BLVD N	ESE 0 - 1/8 (0.026 mi.)	JS1571 / 3	5096
EXXON MOBIL CORPORAT	2512 E RIVERSIDE DR	NE 0 - 1/8 (0.026 mi.)	HS1582 / 15	5194
MAGNOLIA PETROLEUM	220 CONGRESS AVE S	WNW 0 - 1/8 (0.026 mi.)	IX1583 / 11	5195
HYDE PARK GARAGE AUT	513 43RD W	SW 0 - 1/8 (0.026 mi.)	IR1586 / 8	5195
HYDE PARK GARAGE AUT	513 43RD ST W	SW 0 - 1/8 (0.026 mi.)	IR1587 / 8	5196
HYDE PARK GARAGE	513 43RD ST W	SW 0 - 1/8 (0.026 mi.)	IR1588 / 8	5196
GRIFFS TEXACO SERVIC	8900 LAMAR BLVD N	WNW 0 - 1/8 (0.026 mi.)	R1592 / 6	5197
COPELAND GARAGE	514 43RD ST W	SW 0 - 1/8 (0.027 mi.)	IR1606 / 8	5259
MURRAYS GAR AUTO	514 43RD W	SW 0 - 1/8 (0.027 mi.)	IR1607 / 8	5259
HYDE PARK GARAGE	514 43RD ST W	SW 0 - 1/8 (0.027 mi.)	IR1608 / 8	5260
AUSTIN LACQUER COMPA	604 W 6TH ST	ESE 0 - 1/8 (0.027 mi.)	DA1613 / 11	5263

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
GULF REFG CO STA NO	1811 CONGRESS AVE E	ESE 0 - 1/8 (0.027 mi.)	JI1615 / 11	5267
OHENRY GAR	110 8TH E	WNW 0 - 1/8 (0.027 mi.)	DB1617 / 11	5268
AXLE & WHEEL ALIGN	510 6TH E	NE 0 - 1/8 (0.027 mi.)	DR1627 / 11	5283
803 05 DEPENDABLE MT	803 5TH W	WNW 0 - 1/8 (0.027 mi.)	DC1629 / 11	5284
DEPENDABLE MOTORS IN	803 5TH ST W	WNW 0 - 1/8 (0.027 mi.)	DC1630 / 11	5284
BOZEMAN & HAGOOD SER	1811 CONGRESS AVE	WNW 0 - 1/8 (0.027 mi.)	1631 / 11	5284
RIVERSIDE SHELLSHAPE	400 S CONGRESS	WNW 0 - 1/8 (0.027 mi.)	EJ1642 / 14	5475
1801 03 DYE SLS & SE	1801 CONGRESS AVE	WNW 0 - 1/8 (0.027 mi.)	JI1645 / 11	5477
SHARPS SERVICE STA	512 6TH E	NE 0 - 1/8 (0.027 mi.)	DR1647 / 11	5477
D & S SERVICE STATIO	500 7TH ST E	NNE 0 - 1/8 (0.028 mi.)	IL1648 / 11	5477
D&S SERV STA	500 7TH E	NNE 0 - 1/8 (0.028 mi.)	IL1649 / 11	5478
D & S SERVICE STATIO	500 7TH ST E	NNE 0 - 1/8 (0.028 mi.)	IL1650 / 11	5478
BOBS GARAGE &	1007 CONGRESS AVE	WNW 0 - 1/8 (0.028 mi.)	CV1662 / 11	5504
SPRINKLES BODY SHOP	512 RIO GRANDE	WNW 0 - 1/8 (0.028 mi.)	DA1664 / 11	5505
TWIN OAKS PHILLIPS 6	620 E OLTORF	SE 0 - 1/8 (0.028 mi.)	FY1671 / 14	5525
CAPITAL CITY MOTOR	505 7TH ST E	NNE 0 - 1/8 (0.028 mi.)	IL1672 / 11	5526
EXXON MOBIL CORPORAT	7715 E BEN WHITE BLV	WNW 0 - 1/8 (0.028 mi.)	JW1677 / 19	5532
SOUTH AUSTIN CONOCO	2336 CONGRESS AVE	NW 0 - 1/8 (0.029 mi.)	FU1683 / 14	5568
NOWLIN R A AUTO REPR	602 TRINITY ST	SSW 0 - 1/8 (0.029 mi.)	DM1684 / 11	5568
NUZ FRANK GARAGE	4237 CONGRESS AVE S	ESE 0 - 1/8 (0.029 mi.)	GX1685 / 18	5569
SUNDBECK GAR	4241 CONGRESS AVE	ESE 0 - 1/8 (0.029 mi.)	GX1686 / 18	5569
SUNDBECK GARAGE	4241 CONGRESS AVE S	ESE 0 - 1/8 (0.029 mi.)	GX1687 / 18	5569
L & M GARAGE AUTO RE	301 BARTON SPRINGS R	NE 0 - 1/8 (0.029 mi.)	IA1689 / 11	5577
108 10 12 HENRV GARA	108 8TH E	WNW 0 - 1/8 (0.029 mi.)	DB1693 / 11	5591
SIGMOR NUMBER 232 IN	3600 S CONGRESS AVE	WNW 0 - 1/8 (0.029 mi.)	GK1698 / 14	5605
BARKER B M AUTOMO	105 10TH E	WNW 0 - 1/8 (0.029 mi.)	CV1700 / 11	5615
CENTRAL SEWING MACH	522 6TH E	NE 0 - 1/8 (0.030 mi.)	DR1702 / 11	5632
GRAYBURG OIL CO STAT	1601 CONGRESS AVE	WNW 0 - 1/8 (0.030 mi.)	JQ1704 / 11	5634
ZUAUTO PARTS LLC	701 BRAZOS ST STE 72	NNE 0 - 1/8 (0.030 mi.)	DJ1705 / 11	5635
MARSHALL BODY WORKS	515 7TH E	NNE 0 - 1/8 (0.030 mi.)	IL1709 / 11	5648
ELLIS SERVICE STATIO	524 6TH E	NE 0 - 1/8 (0.030 mi.)	DR1715 / 11	5650
GOLDIE CORPORATION	3822 S CONGRESS AVE	WNW 0 - 1/8 (0.031 mi.)	1726 / 14	5723
HAGOOD SERV STA	519 7TH E	NE 0 - 1/8 (0.031 mi.)	IL1727 / 11	5724
HAGOOD SERVICE STATI	519 7TH ST E	NE 0 - 1/8 (0.031 mi.)	IL1728 / 11	5724
AUS TEX ENGINE	304 COLORADO ST	NNE 0 - 1/8 (0.031 mi.)	DV1729 / 11	5724
PACKERY CHANNEL BAIT	308 CONGRESS AVE STE	NNE 0 - 1/8 (0.031 mi.)	DY1730 / 11	5724
CENTEX AUTO REPAIR	202 SAN JACINTO ST	SSW 0 - 1/8 (0.031 mi.)	KC1731 / 11	5725
B & M AUTOMOTIVE AUT	511 LIVE OAK ST W	WNW 0 - 1/8 (0.032 mi.)	1736 / 14	5740
BISHOP GARY	3906 S CONGRESS AVE	WNW 0 - 1/8 (0.032 mi.)	KD1740 / 14	5769
A & M TRAILER REPAIR	2702 SHERWOOD LN	SSE 0 - 1/8 (0.032 mi.)	1742 / 14	5770
SAVE WAY SERV	503 BRAZOS	SSW 0 - 1/8 (0.032 mi.)	DP1743 / 11	5770
STEWART DON A INC	3909 S CONGRESS AVE	ESE 0 - 1/8 (0.032 mi.)	KE1744 / 14	5771
MILLNER BROS SERVICE	813 12TH W	WNW 0 - 1/8 (0.032 mi.)	JA1752 / 11	5875
AUSTIN MOTOR INN	207 CONGRESS AVE	SSW 0 - 1/8 (0.032 mi.)	KH1756 / 11	5883
EXXON MOBIL CORPORAT	1100 W PARMER LN	W 0 - 1/8 (0.033 mi.)	KI1758 / 2	5884
SAFETY RIDE CAR CARE	9307 LAMAR BLVD N	ESE 0 - 1/8 (0.033 mi.)	Q1762 / 6	5920
DOCS SMALL ENGINE RE	104 KREBS LN	WNW 0 - 1/8 (0.033 mi.)	GO1763 / 14	5920
BELL JIM GARAGE AUTO	811 5TH ST W	WNW 0 - 1/8 (0.033 mi.)	DC1765 / 11	5921
BRADSHAW ED SERV	501 BRAZOS	SSW 0 - 1/8 (0.033 mi.)	DP1769 / 11	5922
AUSTIN BRAKE	506 TRINITY ST	SSW 0 - 1/8 (0.033 mi.)	DQ1774 / 11	5932
DUKES GAR REPRS	406 RED RIVER	WSW 0 - 1/8 (0.034 mi.)	1780 / 11	5936
CIRCLE K STORES INC	4619 S CONGRESS AVE	ESE 0 - 1/8 (0.034 mi.)	KK1782 / 17	5939
SIGMOR SHAMROCK SERV	8545 LAMAR BLVD N	SE 0 - 1/8 (0.034 mi.)	KM1788 / 6	5995
704 6 BUSTIN MC CUTC	704 BRAZOS ST	NNE 0 - 1/8 (0.034 mi.)	DJ1791 / 11	5996
EWINGS CONOCO SERVIC	519 E 7TH ST	NE 0 - 1/8 (0.034 mi.)	IL1793 / 11	6025
JOHNSON J W SERVICE	510 5TH ST E	SW 0 - 1/8 (0.034 mi.)	DU1799 / 11	6036

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CUNNINGHAM GEO L FIL	510 5TH E	SW 0 - 1/8 (0.034 mi.)	DU1800 / 11	6036
CUNNINGHAM G L	510 5TH ST E	SW 0 - 1/8 (0.034 mi.)	DU1801 / 11	6037
AUSTIN KAWASAKI	10426 LAMAR BLVD N	WNW 0 - 1/8 (0.035 mi.)	JR1805 / 3	6067
HART BUBBA SERVICE S	509 5TH E	SW 0 - 1/8 (0.035 mi.)	DU1810 / 11	6070
JOHNSONS SERVICE STA	508 5TH E	SW 0 - 1/8 (0.035 mi.)	DU1811 / 11	6070
B & M DISCOUNT TRANS	808 JUSTIN LN	WNW 0 - 1/8 (0.035 mi.)	AD1813 / 6	6070
T JS CYCLE SALES & S	6215 LAMAR BLVD N	ESE 0 - 1/8 (0.036 mi.)	KO1817 / 9	6077
GULF REFG CO STA NO	507 5TH ST E	SW 0 - 1/8 (0.036 mi.)	KP1818 / 11	6077
HALEY MALCOLM M FILL	507 5TH E	SW 0 - 1/8 (0.036 mi.)	KP1819 / 11	6078
AUSTIN RADIATOR CO	205 CONGRESS AVE	SSW 0 - 1/8 (0.036 mi.)	KH1824 / 11	6083
HUMBLE OIL & REFG	816 12TH W	WNW 0 - 1/8 (0.036 mi.)	JA1825 / 11	6083
B&N AXLE SERV	314 5TH W	ESE 0 - 1/8 (0.037 mi.)	DI1829 / 11	6085
ME MORRIS FORD INCOR	808 6TH ST W	WNW 0 - 1/8 (0.037 mi.)	CZ1830 / 11	6085
MC MORRIS FORD INCOR	808 6TH ST W	WNW 0 - 1/8 (0.037 mi.)	CZ1831 / 11	6085
JENSENS HARRY AUTO R	408 E 7TH ST	NNE 0 - 1/8 (0.037 mi.)	1832 / 11	6085
FRANKS FIX IT	4214 AVENUE A	SW 0 - 1/8 (0.037 mi.)	1833 / 8	6086
REDDS HUMBLE SERV FI	401 1ST E	ESE 0 - 1/8 (0.037 mi.)	KS1840 / 11	6090
MISSION CITY PONTIAC	312 5TH W	ESE 0 - 1/8 (0.037 mi.)	DI1844 / 11	6098
SMITH B C TIRE SHOP	500 5TH ST E	SW 0 - 1/8 (0.038 mi.)	KP1846 / 11	6101
WALLACE GARAGE AUTO	500 5TH E	SW 0 - 1/8 (0.038 mi.)	KP1847 / 11	6101
BALCARS HUMBLE	4501 GUADALUPE ST	ESE 0 - 1/8 (0.038 mi.)	IT1848 / 8	6101
EXXON MOBIL CORPORAT	201 W BEN WHITE BLVD	WNW 0 - 1/8 (0.038 mi.)	GS1849 / 14	6102
LANE AUTO & ELECTRIC	801 12TH ST W	WNW 0 - 1/8 (0.038 mi.)	JA1854 / 11	6154
BUSKES GARAGE	8609 LAMAR BLVD	SE 0 - 1/8 (0.038 mi.)	U1856 / 6	6155
FICKELS SERV STA	617 6TH W	ESE 0 - 1/8 (0.038 mi.)	KR1857 / 11	6155
IMPORT CAR REPAIR	10631 LAMAR BLVD N	ESE 0 - 1/8 (0.038 mi.)	KV1858 / 3	6155
CARLSONS GARAGE	609 31ST ST W	WNW 0 - 1/8 (0.039 mi.)	BE1864 / 8	6181
HAMS AUTO SERV	310 5TH W	ESE 0 - 1/8 (0.039 mi.)	KY1869 / 11	6215
FOSTERS GARAGE	504 BRAZOS ST	SSW 0 - 1/8 (0.039 mi.)	JP1871 / 11	6216
A 1 AUTO ELECTRIC AU	4408 CONGRESS AVE S	WNW 0 - 1/8 (0.039 mi.)	HA1875 / 17	6234
MAGNOLIA PET CO STA	615 6TH W	ESE 0 - 1/8 (0.039 mi.)	KR1881 / 11	6251
VALERO ENERGY STATIO	628 E OLTORF ST	SE 0 - 1/8 (0.040 mi.)	LD1885 / 14	6265
AUS TEX AUTOMOTIVE S	308 COLORADO ST	NNE 0 - 1/8 (0.040 mi.)	JY1891 / 11	6297
A CAR 4 YOU INC	6324 N LAMAR BLVD	WNW 0 - 1/8 (0.040 mi.)	AI1893 / 6	6301
TRAN RICHMOND	10800 N LAMAR BLVD	WNW 0 - 1/8 (0.041 mi.)	J1899 / 3	6338
ALLMANS GROCERY & SE	7207 E RIVERSIDE	SW 0 - 1/8 (0.041 mi.)	1906 / 19	6372
AUSTIN WELDIN E	304 5TH ST W	ESE 0 - 1/8 (0.041 mi.)	KY1907 / 11	6372
CLYDES WIDG	304 5TH W	ESE 0 - 1/8 (0.041 mi.)	KY1908 / 11	6373
ZADAS AUTOMOTIVE & C	816 KRAMER LN	WNW 0 - 1/8 (0.041 mi.)	LJ1909 / 3	6373
TYLER F A FILL STA	823 12TH W	WNW 0 - 1/8 (0.042 mi.)	JA1912 / 11	6374
LUCAS GULF STATION	1221 INTERREGIONAL H	NE 0 - 1/8 (0.042 mi.)	1914 / 14	6375
CARLSONS GARAGE AUTO	609 31ST W	WNW 0 - 1/8 (0.042 mi.)	1915 / 8	6375
MARTIN DELL BRAKE	302 5TH W	ESE 0 - 1/8 (0.043 mi.)	KY1918 / 11	6400
D & S SERVICE STATIO	500 E 7TH ST	NNE 0 - 1/8 (0.043 mi.)	IL1924 / 11	6413
BADGER WALTER H JR F	300 5TH W	ESE 0 - 1/8 (0.043 mi.)	KY1927 / 11	6415
GRIFFIN A C HUMBLE	800 W 12TH ST	WNW 0 - 1/8 (0.044 mi.)	JA1938 / 11	6425
CUNNINGHAM HENRY	403 16TH ST E	WNW 0 - 1/8 (0.045 mi.)	1942 / 11	6426
TRANS TECH AUTOMOTIV	805 CAPITOL ST	WNW 0 - 1/8 (0.045 mi.)	LO1943 / 8	6426
CONGRESS EXXON	6721 S CONGRESS AVE	ESE 0 - 1/8 (0.045 mi.)	LP1944 / 17	6427
RITTERS SERVICE STAT	301 W 19TH ST	E 0 - 1/8 (0.045 mi.)	LI1949 / 11	6451
CAPITOL SPRING & BRA	310 COLORADO ST	NNE 0 - 1/8 (0.045 mi.)	JY1950 / 11	6451
CPCG AUTO TX LP	408 W 17TH ST OFC 10	WNW 0 - 1/8 (0.045 mi.)	1951 / 11	6451
KEESES ENCO PRODUCTS	600 W 5TH	ESE 0 - 1/8 (0.045 mi.)	DD1954 / 11	6452
CAPITOL TRANSMISSION	7401 RIVERSIDE DR E	SW 0 - 1/8 (0.046 mi.)	1957 / 19	6453
BELL JIM AUTOS INC	201 BRAZOS ST	SSW 0 - 1/8 (0.046 mi.)	1958 / 11	6454
METCALF L A SERVICE	300 S CONGRESS	NE 0 - 1/8 (0.046 mi.)	LQ1961 / 14	6454

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
MILLNERS SERVICE STA	827 12TH W	WNW 0 - 1/8 (0.046 mi.)	JA1970 / 11	6473
CHAMBERLAIN S M GARA	7209 LAMAR BLVD N	ESE 0 - 1/8 (0.046 mi.)	1971 / 6	6473
MC KEAN W L R	1610 BRAZOS ST	ESE 0 - 1/8 (0.046 mi.)	JE1972 / 11	6473
RIVER CITY Z SHOP AU	604 6TH ST W	ESE 0 - 1/8 (0.046 mi.)	KR1974 / 11	6475
PIT SHOP THE AUTO RE	604 6TH ST W	ESE 0 - 1/8 (0.046 mi.)	KR1975 / 11	6475
TEXAS GLASS	808 CAPITOL CT	WNW 0 - 1/8 (0.046 mi.)	LO1976 / 8	6476
SIMPSON IRA AUTO	409 1ST E	ESE 0 - 1/8 (0.046 mi.)	KS1979 / 11	6483
BRODIE MARKET INC	812 THURMOND ST	NW 0 - 1/8 (0.047 mi.)	1981 / 6	6484
SPEEDWAY SER STA	3706 SPEEDWAY	ESE 0 - 1/8 (0.047 mi.)	LV1985 / 8	6485
STOCKTON J F	1501 S 1ST ST	WNW 0 - 1/8 (0.047 mi.)	LW1987 / 14	6486
UNIVERSITY WRECKER	2114 MAXWELL LN	NNE 0 - 1/8 (0.047 mi.)	1988 / 19	6486
GULF STATES POWER LT	800 BRAZOS ST STE 40	ESE 0 - 1/8 (0.047 mi.)	KW1991 / 11	6487
RUSHINGS SYLVAN W EN	800 W 6TH ST	WNW 0 - 1/8 (0.048 mi.)	LX1994 / 11	6490
CRANE & LOCK SERV	344 CONGRESS AVE S	NE 0 - 1/8 (0.048 mi.)	LY1999 / 14	6498
BESHEARS C A TEXACO	344 S CONGRESS	NE 0 - 1/8 (0.048 mi.)	LY2000 / 14	6498
LOCK SERVICE STA FIL	344 CONGRESS AVE S	NE 0 - 1/8 (0.048 mi.)	LY2001 / 14	6499
RUSHINGS SYLVAN W EX	800 6TH ST W	WNW 0 - 1/8 (0.048 mi.)	LX2002 / 11	6499
RUSHINGS SYLVAN W EN	800 6TH ST W	WNW 0 - 1/8 (0.048 mi.)	LX2003 / 11	6499
HUMBLE OIL & REF CO	800 6TH W	WNW 0 - 1/8 (0.048 mi.)	LX2004 / 11	6499
BRAKE SPECIALIST INC	111 W WILLIAM CANNON	WNW 0 - 1/8 (0.048 mi.)	LZ2010 / 17	6519
200 24 AVENUE SERVIC	200 CONGRESS AVE E	SSW 0 - 1/8 (0.048 mi.)	MA2011 / 11	6519
AUTO-FROST	1601 S 1ST ST	WNW 0 - 1/8 (0.049 mi.)	MB2015 / 14	6531
RUCKER CASS GULF SER	601 6TH W	ESE 0 - 1/8 (0.049 mi.)	KR2019 / 11	6532
FRENCH REVOLUTION AU	807 CAPITOL ST	WNW 0 - 1/8 (0.049 mi.)	LO2021 / 8	6533
KINSEYS AUTOMOTIVE	819 HOUSTON ST	WNW 0 - 1/8 (0.050 mi.)	MD2024 / 8	6538
0 K GARAGE	312 COLORADO ST	NNE 0 - 1/8 (0.050 mi.)	JY2026 / 11	6541
SPEEDWAY SERVICE STA	3714 SPEEDWAY	ESE 0 - 1/8 (0.050 mi.)	LV2036 / 8	6575
ROBINSON SAML	316 COLORADO	NNE 0 - 1/8 (0.050 mi.)	JY2037 / 11	6575
FAST STOP STORES INC	5526 S CONGRESS AVE	WNW 0 - 1/8 (0.050 mi.)	MH2040 / 17	6601
321 3 COVERT AUTO CO	321 6TH W	ESE 0 - 1/8 (0.050 mi.)	LK2045 / 11	6616
ALAMO TRANSMISSION S	200 CONGRESS AVE	SSW 0 - 1/8 (0.050 mi.)	KH2046 / 11	6616
KEESES ENCO HUMBLE S	600 5TH ST W	ESE 0 - 1/8 (0.050 mi.)	MJ2047 / 11	6616
WHEELERS ENCO HUMBLE	600 5TH ST W	ESE 0 - 1/8 (0.050 mi.)	MJ2048 / 11	6617
ACME SERVICE STA	600 5TH W	ESE 0 - 1/8 (0.050 mi.)	MJ2049 / 11	6617
ROGERS & SALYER FILL	204 BARTON SPRINGS R	NE 0 - 1/8 (0.051 mi.)	LQ2051 / 11	6618
ROOHI JOOHI INC	7700 E MRTN LTHR KIN	W 0 - 1/8 (0.051 mi.)	2054 / 8	6618
AUTOMOTIVE SPECIALIS	502 NUECES ST	ESE 0 - 1/8 (0.051 mi.)	MJ2056 / 11	6620
JERRYS GARAGE	1902 MONTOPOLIS DR	NNE 0 - 1/8 (0.051 mi.)	ML2058 / 15	6621
MIOTORAMP STGE	713 COLORADO	WNW 0 - 1/8 (0.052 mi.)	MM2060 / 11	6621
601 03 GAGE BROS	601 7TH E	NE 0 - 1/8 (0.052 mi.)	JH2068 / 11	6629
REDS GARAGE AUTO REP	600 7TH E	NE 0 - 1/8 (0.052 mi.)	JH2069 / 11	6629
SCHNELL BROS WHEEL	501 MONROE ST W	WNW 0 - 1/8 (0.052 mi.)	MB2071 / 14	6630
CAMPOS MANUEL	801 1ST E	ESE 0 - 1/8 (0.052 mi.)	KU2076 / 11	6659
JERRYS GARAGE AUTO	1900 MONTOPOLIS DR	NNE 0 - 1/8 (0.052 mi.)	ML2078 / 15	6660
TRAVIS COUNTY OIL	500 BRAZOS ST	SSW 0 - 1/8 (0.052 mi.)	JP2079 / 11	6661
RAYS REPAIR	6516 SHIRLEY AVE	ESE 0 - 1/8 (0.053 mi.)	LR2082 / 6	6695
BROADDUS ENTERPRISES	30 N I 35	NE 0 - 1/8 (0.053 mi.)	MO2083 / 14	6695
TEXAS CO THE FILLING	101 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2085 / 11	6696
EMPIRE AUTOMOTIVE SE	604 7TH ST E	NE 0 - 1/8 (0.053 mi.)	JH2086 / 11	6696
LOPEZ FRANK S	604 7TH E	NE 0 - 1/8 (0.053 mi.)	JH2087 / 11	6696
EMPIRE AUTOMOTIVE SE	604 7TH ST E	NE 0 - 1/8 (0.053 mi.)	JH2088 / 11	6697
STROBURG & BLOMQUIST	103 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2091 / 11	6697
GOSLIN J W T & CO	108 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LG2092 / 11	6698
NIEMAN ELECTRICAL	107 5TH W	SSW 0 - 1/8 (0.053 mi.)	LG2095 / 11	6728
NIEMAN ELEC SER	107 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2096 / 11	6729
TAYLOR VIVIEN REPR S	123 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2098 / 11	6729

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
B & N AXLE SERVICE	219 4TH ST W	NNE 0 - 1/8 (0.053 mi.)	ME2099 / 11	6729
B & N AXLE SERVICE	219 4TH ST W	NNE 0 - 1/8 (0.053 mi.)	ME2100 / 11	6730
DICKARD R AUTO REPR	104 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LG2101 / 11	6730
111 13 BARGE ROBT AU	111 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2103 / 11	6731
LUNCEFORD THOMAS J A	127 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2104 / 11	6731
111 15 BENSON MOTOR	111 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LG2105 / 11	6731
EPPLER J LAYTON REPR	115 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2106 / 11	6731
SE COR BLUE PENNANT	114 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2107 / 11	6732
TOSCO MARKETING COMP	3208 EAST AVE	ENE 0 - 1/8 (0.053 mi.)	MQ2108 / 8	6732
CITIES SERVICE STA	120 5TH E	SSW 0 - 1/8 (0.053 mi.)	LG2110 / 11	6732
BERGSTROM BROS	119 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2111 / 11	6733
NE COR COX REALIZATI	117 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LG2112 / 11	6733
OCONNERS JIM MOBIL G	1308 LAVACA ST	ESE 0 - 1/8 (0.053 mi.)	MR2115 / 11	6748
CRUZ AUTOMOTIVE	8827 LAMAR BLVD N	SE 0 - 1/8 (0.053 mi.)	2116 / 6	6749
ALEXANDER CLY D FILL	301 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2117 / 11	6749
302 12 FROMME MOTOR	302 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2118 / 11	6750
0 & M AUTO REPAIR GR	318 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2119 / 11	6750
D & M AUTO REPAIR	318 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2120 / 11	6750
ELLIOTT EUNICE E RAD	318 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2121 / 11	6750
DARTER HOWARD T	217 5TH E	SSW 0 - 1/8 (0.053 mi.)	JP2122 / 11	6751
DARTER H T AUTO	217 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2123 / 11	6751
PILAND & ELLIOTT SER	311 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2124 / 11	6751
TRAVIS MOTOR EXCHANG	311 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2125 / 11	6751
PILAND & ELLIOTT	311 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2126 / 11	6752
ME MORRIS FORD INC	808 W 6TH ST	WNW 0 - 1/8 (0.053 mi.)	LX2130 / 11	6766
316 18 DELZELL & DEM	316 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2131 / 11	6766
DELZELL & DEMENT AUT	316 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2132 / 11	6766
CULLEN HUGH H GARAGE	206 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2133 / 11	6766
RUMSEYS GARAGE	211 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2134 / 11	6767
D&M AUTO REPR	305 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2136 / 11	6767
REAR SMITH AUTO SERV	305 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2137 / 11	6767
FROMME MOTOR CO	304 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2138 / 11	6768
SAN JACINTO GARAGE	305 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2139 / 11	6768
DARTER SLIM	213 5TH E	SSW 0 - 1/8 (0.053 mi.)	JP2140 / 11	6768
LOCKE WILL MOTOR	306 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2141 / 11	6768
RIEGERS GARAGE	307 5TH E	SSW 0 - 1/8 (0.053 mi.)	LH2142 / 11	6769
WATT STUART SERVICE	200 5TH E	SSW 0 - 1/8 (0.053 mi.)	JP2144 / 11	6769
FIFTH & BRAZOS SERVI	200 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2145 / 11	6769
QUICK SERVICE GAR PI	204 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2147 / 11	6770
205 7 AUSTIN RUBBER	205 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2148 / 11	6770
CAPITOL CHEVROLET	218 5TH E	SSW 0 - 1/8 (0.053 mi.)	JP2149 / 11	6770
BOWDIN M L SPRING	218 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2150 / 11	6771
BEATY WELDING & RADI	219 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2151 / 11	6771
CAPITOL CHEVROLET CO	220 5TH E	SSW 0 - 1/8 (0.054 mi.)	JP2152 / 11	6771
ELECTRICAL SERVICE C	221 5TH ST E	SSW 0 - 1/8 (0.054 mi.)	JP2153 / 11	6771
BURKHALTER E E AUTO	223 5TH ST E	SSW 0 - 1/8 (0.054 mi.)	JP2154 / 11	6772
AUSTIN FRAME & WHEEL	526 1ST ST S	WNW 0 - 1/8 (0.054 mi.)	LB2155 / 11	6772
LINDSAY AUTO ELEC	504 LAVACA	ESE 0 - 1/8 (0.054 mi.)	KY2157 / 11	6772
AUSTIN FRAME & WHEEL	525 1ST ST S	WNW 0 - 1/8 (0.054 mi.)	LB2158 / 11	6773
MASSEVS GARAGE AUTO	6507 RIVERSIDE DR E	SSW 0 - 1/8 (0.054 mi.)	MS2159 / 15	6773
MASSEYS GARAGE	6507 RIVERSIDE DR E	SSW 0 - 1/8 (0.054 mi.)	MS2160 / 15	6773
KEALHOFER STARR TIRE	910 LAVACA ST	ESE 0 - 1/8 (0.054 mi.)	IY2164 / 11	6776
327 27 HICKS RUBBER	325 CONGRESS AVE	NNE 0 - 1/8 (0.054 mi.)	MU2169 / 11	6780
YOUNGS REPAIR SHOP	607 37TH W	WNW 0 - 1/8 (0.054 mi.)	2170 / 8	6780
LINDSAY AUTO ELEC	515 1ST S	WNW 0 - 1/8 (0.054 mi.)	LB2171 / 11	6780
B ALL AUTO SERVICE W	607 DEEN AVE	SE 0 - 1/8 (0.054 mi.)	2172 / 6	6781

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
TRAVIS MOTOR EX	611 7TH E	NE 0 - 1/8 (0.055 mi.)	JH2176 / 11	6819
B & L CLUTCH & BRAKE	611 7TH ST E	NE 0 - 1/8 (0.055 mi.)	JH2177 / 11	6819
B & L CLUTCH & BRAKE	611 7TH ST E	NE 0 - 1/8 (0.055 mi.)	JH2178 / 11	6820
AUSTIN RADIATOR WORK	810 CAPITOL CT	WNW 0 - 1/8 (0.055 mi.)	LO2181 / 8	6820
GARDNERS SERVICE STA	99 CONGRESS AVE	NNE 0 - 1/8 (0.055 mi.)	MN2182 / 11	6821
EKSTROM GUS AUTO REP	301 CROCKETT ST	ESE 0 - 1/8 (0.055 mi.)	MT2183 / 14	6821
AUTOMOTIVE SPECIA	837 12TH W	WNW 0 - 1/8 (0.055 mi.)	JA2184 / 11	6821
TRAVIS MTR EX	613 7TH E	NE 0 - 1/8 (0.055 mi.)	JH2185 / 11	6822
TRAVIS MOTOR EXCHANG	613 7TH ST E	NE 0 - 1/8 (0.055 mi.)	JH2186 / 11	6822
WELLS H P GARAGE	206 18TH E	ESE 0 - 1/8 (0.055 mi.)	MX2187 / 11	6822
TAYLORS SERIVCE	511 1ST E	WNW 0 - 1/8 (0.055 mi.)	LB2189 / 11	6831
LAVACA ST GARAGE	1404 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	MR2199 / 11	6847
MAGNOLIA PET CO STI	1312 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	MR2202 / 11	6848
LINDSAY AUTO ELEC	506 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	LK2204 / 11	6849
BEN AUTO REPAIR	5409 WASSON RD	ESE 0 - 1/8 (0.056 mi.)	2205 / 17	6849
PEARSON WESLEY	301 CONGRESS AVE S	SSW 0 - 1/8 (0.057 mi.)	NA2213 / 11	6857
SMITTY AUTO SERVICE	301 CONGRESS AVE S	SSW 0 - 1/8 (0.057 mi.)	NA2215 / 11	6858
CARLSONS T P SERV	500 LAVACA ST	ESE 0 - 1/8 (0.057 mi.)	KY2216 / 11	6858
BETHKE BRAKE SERVICE	617 7TH ST E	NE 0 - 1/8 (0.057 mi.)	JH2217 / 11	6858
BETHKE BRAKE SERVICE	617 7TH ST E	NE 0 - 1/8 (0.057 mi.)	JH2218 / 11	6859
DIAMOND SHAMROCK REF	2001 BASTROP HWY E	NNE 0 - 1/8 (0.057 mi.)	NB2219 / 20	6859
DIAMOND SHAMROCK REF	2001 BASTROP HWY	NNE 0 - 1/8 (0.057 mi.)	NB2220 / 20	6859
DIAMOND SHAMROCK REF	2001 BASTHROP HWY	NNE 0 - 1/8 (0.057 mi.)	NB2221 / 20	6860
SIGMORE DIAMOND SHAM	2001 BASTHROP HIGHWA	NNE 0 - 1/8 (0.057 mi.)	NB2222 / 20	6860
SIGMOR SHAMROCK SERV	2001 BASTROP HWY	NNE 0 - 1/8 (0.057 mi.)	NB2223 / 20	6860
502 04 WHITING ROBT	502 LAVACA ST	ESE 0 - 1/8 (0.057 mi.)	KY2224 / 11	6860
MARTIN J E SERVICE S	1710 1ST	WNW 0 - 1/8 (0.057 mi.)	NC2225 / 14	6861
HAYNES R E FILL STA	1710 1ST	WNW 0 - 1/8 (0.057 mi.)	NC2226 / 14	6861
AUSTIN GARAGE AUTOMO	511 COLORADO ST	W 0 - 1/8 (0.057 mi.)	LA2227 / 11	6861
NIELSON GULF SERVICE	329 CONGRESS AVE	NNE 0 - 1/8 (0.057 mi.)	MU2229 / 11	6862
505 11 BARKER MOTOR	505 COLORADO ST	W 0 - 1/8 (0.058 mi.)	LA2238 / 11	6869
MC GOWAN ED TEXACO	344 CONGRESS AVE	NNE 0 - 1/8 (0.058 mi.)	MU2239 / 11	6869
DIAMOND SHAMROCK	806 W RUNDBERG LN	WNW 0 - 1/8 (0.058 mi.)	NF2244 / 6	6911
STUDENT CO OPERATIVE	2412 SAN ANTONIO	W 0 - 1/8 (0.058 mi.)	2248 / 11	6931
VALENTA SERVICE STAT	5607 CONGRESS AVE S	ESE 0 - 1/8 (0.058 mi.)	LL2249 / 17	6931
VALENTA SERV STA	5607 CONGRESS AVE	ESE 0 - 1/8 (0.058 mi.)	LL2250 / 17	6931
PRATHER F H FILL STA	1601 1ST	WNW 0 - 1/8 (0.058 mi.)	LW2251 / 14	6931
NOACK BENJ FILL STA	3500 EAST AVE	ENE 0 - 1/8 (0.058 mi.)	MQ2254 / 8	6932
WOFFORD S D FILLING	501 COLORADO	W 0 - 1/8 (0.058 mi.)	LA2258 / 11	6934
Z TECH AUTO REPR	809 CAPITOL ST	WNW 0 - 1/8 (0.059 mi.)	LO2259 / 8	6934
SCHNEIDER ALBERT REP	310 2ND W	ESE 0 - 1/8 (0.059 mi.)	KJ2260 / 11	6935
GREGORY FENDER	815 6TH W	WNW 0 - 1/8 (0.059 mi.)	LX2263 / 11	6935
BELL AIRDOME FILLING	900 COLORADO	WNW 0 - 1/8 (0.060 mi.)	KL2267 / 11	6936
HOUGH ROY AUTO REPR	608 COLORADO ST	WNW 0 - 1/8 (0.060 mi.)	LA2271 / 11	6938
FAULKNER RUSSELL C	309 5TH W	ESE 0 - 1/8 (0.061 mi.)	KY2277 / 11	6951
MC CUTCHEON U S AUTO	106 1ST E	NNE 0 - 1/8 (0.061 mi.)	NJ2278 / 11	6951
GULF REFG CO STA NO	300 CONGRESS AVE S	SSW 0 - 1/8 (0.061 mi.)	NA2283 / 11	6956
KINGSLEY AUTOMOTIVE	300 CONGRESS AVE S	SSW 0 - 1/8 (0.061 mi.)	NA2284 / 11	6957
ALLEN RADIATORS	707 ST JOHNS AVE W	ESE 0 - 1/8 (0.061 mi.)	MW2286 / 6	6957
HUMBLE PRODUCTS SERV	343 CONGRESS AVE S	NE 0 - 1/8 (0.062 mi.)	LY2287 / 14	6957
RIVERSIDE SERVICE ST	343 CONGRESS AVE S	NE 0 - 1/8 (0.062 mi.)	LY2288 / 14	6958
WEBB J E TIRES	608 LAVACA ST	ESE 0 - 1/8 (0.062 mi.)	LK2289 / 11	6958
ALLMAN JESS	112 1ST E	NE 0 - 1/8 (0.062 mi.)	NJ2291 / 11	6967
AAMCO TRANSMISSIONS	307 5TH ST W	ESE 0 - 1/8 (0.062 mi.)	KY2292 / 11	6967
307 9 KNIGHT WHIPPET	307 5TH ST W	ESE 0 - 1/8 (0.062 mi.)	KY2293 / 11	6968
WARD HAROLD	703 BARTON SPGS RD	WNW 0 - 1/8 (0.062 mi.)	2295 / 11	6968

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
AVENUE GARAGE	205 CONGRESS AVE E	SSW 0 - 1/8 (0.062 mi.)	KH2296 / 11	6968
112 14 ALLMANS JESS	114 1ST E	NE 0 - 1/8 (0.062 mi.)	NJ2303 / 11	6985
BOUCHARD E A GARAGE	207 14TH W	WNW 0 - 1/8 (0.063 mi.)	2304 / 11	6986
MAGNOLIA PET CO STA	100 31ST E	ESE 0 - 1/8 (0.063 mi.)	NM2305 / 8	6986
AUTOMATIC TRANSMISSI	811 PRAIRIE TRL	WNW 0 - 1/8 (0.063 mi.)	NN2307 / 3	6986
B & B BODY & PAINT R	821 BRANTWOOD ST	WNW 0 - 1/8 (0.063 mi.)	NO2310 / 6	7000
ANDYS AUTO ELECTRIC	305 5TH ST W	ESE 0 - 1/8 (0.064 mi.)	KY2313 / 11	7004
S & D AUTO ELECTRIC	305 5TH ST W	ESE 0 - 1/8 (0.064 mi.)	KY2314 / 11	7004
ANDYS AUTO ELEC REPR	305 5TH W	ESE 0 - 1/8 (0.064 mi.)	KY2315 / 11	7005
LINDHOLM GARAGE	219 BARTON SPRINGS R	SSW 0 - 1/8 (0.064 mi.)	NA2318 / 11	7018
CAPITAL CITY AUTO CO	211 6TH W	WNW 0 - 1/8 (0.064 mi.)	NG2319 / 11	7018
JOHNSON ARVEL G	510 COLORADO	W 0 - 1/8 (0.064 mi.)	LA2320 / 11	7018
SODIES AUTO REPAIR	405 NECHES ST	SW 0 - 1/8 (0.064 mi.)	KP2326 / 11	7034
CAPITAL SPRING & BRA	403 NECHES ST	SW 0 - 1/8 (0.065 mi.)	KP2327 / 11	7034
NW COR SWEARINGEN AR	120 1ST W	NE 0 - 1/8 (0.065 mi.)	NJ2328 / 11	7035
TEXAS MOTORS	502 COLORADO ST	W 0 - 1/8 (0.065 mi.)	LA2337 / 11	7071
FORDEX SERVICE AUTO	201 2ND W	SSW 0 - 1/8 (0.065 mi.)	MA2338 / 11	7072
AUTOMATIC TRANSMISSI	303 5TH ST W	ESE 0 - 1/8 (0.065 mi.)	KY2339 / 11	7072
CAPITAL CITY REPAIR	213 6TH W	WNW 0 - 1/8 (0.065 mi.)	NG2341 / 11	7072
LONE STAR GARAGE AUT	500 COLORADO ST	W 0 - 1/8 (0.065 mi.)	LA2342 / 11	7073
UNITED MTR EXCH	111 SAN JACINTO ST	WNW 0 - 1/8 (0.065 mi.)	NV2345 / 11	7088
BRUNDRETT ARNOLD 0 A	404 32ND W	ESE 0 - 1/8 (0.066 mi.)	2354 / 8	7107
CAPITOL AUTO & TRANS	311 E 5TH ST	SSW 0 - 1/8 (0.066 mi.)	LH2355 / 11	7107
ELLIOTTS RADIATOR SH	102 2ND ST W	SSW 0 - 1/8 (0.066 mi.)	KH2358 / 11	7113
ELLIOTTS RADIATOR SH	102 2ND ST W	SSW 0 - 1/8 (0.066 mi.)	KH2359 / 11	7114
ALMQUIST SINCLAIR SE	700 RED RIVER	NE 0 - 1/8 (0.066 mi.)	NY2362 / 11	7114
NASH JOHN H MOTOR CO	215 6TH W	WNW 0 - 1/8 (0.066 mi.)	NG2368 / 11	7119
SMITH C B MOTORS	301 5TH W	ESE 0 - 1/8 (0.066 mi.)	KY2374 / 11	7124
301 3 TIRE SERVICE C	301 5TH ST W	ESE 0 - 1/8 (0.066 mi.)	KY2376 / 11	7124
DEWEYS WELDING & RAD	110 2ND W	SSW 0 - 1/8 (0.067 mi.)	KH2377 / 11	7125
108 10 0 0 K GARAGE	108 2ND W	SSW 0 - 1/8 (0.067 mi.)	KH2378 / 11	7125
MURPHYS GARAGE AUTO	3801 WADFORD ST	WNW 0 - 1/8 (0.067 mi.)	2381 / 14	7149
BALKOS HUMBLE	3807 EAST AVE	ENE 0 - 1/8 (0.067 mi.)	MQ2386 / 8	7168
MUD PPPIES SELF SERV	2015 E RIVERSIDE DR	SW 0 - 1/8 (0.067 mi.)	2387 / 14	7168
RPS TRANSMISSION & A	700 W APPLEGATE DR	ESE 0 - 1/8 (0.067 mi.)	2391 / 3	7170
COTTMAN TRANSMISSION	820 W YAGER LN	E 0 - 1/8 (0.067 mi.)	OA2397 / 4	7179
417 19 PATTON AUTO L	417 CONGRESS AVE	SSW 0 - 1/8 (0.068 mi.)	LG2408 / 11	7229
ESTES & CO AUTO	216 6TH W	WNW 0 - 1/8 (0.068 mi.)	NG2409 / 11	7229
FIEGELS GARAGE	217 6TH W	WNW 0 - 1/8 (0.068 mi.)	NG2410 / 11	7229
BETHKE BRAKE SERVICE	617 E 7TH ST	NE 0 - 1/8 (0.068 mi.)	NZ2411 / 11	7229
RIEGERS GARAGE AUTO	513 LAVACA	ESE 0 - 1/8 (0.069 mi.)	LK2416 / 11	7240
REIGER MOTOR SALES	505 LAVACA	ESE 0 - 1/8 (0.069 mi.)	LK2417 / 11	7240
EAST 9TH STREET COMP	115 E 5TH ST STE 200	SSW 0 - 1/8 (0.069 mi.)	NL2420 / 11	7244
MC CUTCHEON U S AUTO	503 LAVACA ST	ESE 0 - 1/8 (0.069 mi.)	LK2421 / 11	7244
AUSTIN BTRY & ELEC	501 LAVACA	ESE 0 - 1/8 (0.069 mi.)	LK2422 / 11	7245
AUTOMATIC TRANSMISSI	211 4TH ST W	NNE 0 - 1/8 (0.069 mi.)	2424 / 11	7245
COVERT BUICK INC	500 5TH ST W	WNW 0 - 1/8 (0.070 mi.)	OF2427 / 11	7246
PEARSON WESLEY H	313 CONGRESS AVE S	SSW 0 - 1/8 (0.070 mi.)	NA2429 / 11	7246
PEARSON WESLEY H FIL	313 CONGRESS AVE S	SSW 0 - 1/8 (0.070 mi.)	NA2430 / 11	7246
CORLEY & BERRY SERVI	1701 LAVACA	ESE 0 - 1/8 (0.070 mi.)	MP2431 / 11	7247
KUHLMAN HOW	501 6TH W	WNW 0 - 1/8 (0.070 mi.)	OI2440 / 11	7292
LINDHOLM TORSTEN	502 5TH W	WNW 0 - 1/8 (0.071 mi.)	OF2441 / 11	7292
NORTH AUSTIN FRAME &	825 KRAMER LN	WNW 0 - 1/8 (0.071 mi.)	2443 / 3	7292
TAYLORS DELWOOO CONO	4021 EAST AVE	ENE 0 - 1/8 (0.071 mi.)	MQ2447 / 8	7298
MUELLER & BENSON	403 BRAZOS	NNE 0 - 1/8 (0.072 mi.)	2450 / 11	7298
UNIVERSITY GARAGE AU	1806 SAN ANTONIO ST	WNW 0 - 1/8 (0.072 mi.)	2451 / 11	7299

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
JAMES W L GARAGE	703 38TH W	ESE 0 - 1/8 (0.072 mi.)	2453 / 8	7299
LINDHOLM T F AUTO	500 SAN ANTONIO ST	WNW 0 - 1/8 (0.072 mi.)	OF2455 / 11	7306
COVERT BUICK CO	505 5TH ST W	WNW 0 - 1/8 (0.072 mi.)	OF2456 / 11	7307
COVERT BUICK CO	505 5TH ST W	WNW 0 - 1/8 (0.072 mi.)	OF2457 / 11	7307
COR EZELLE JACK SERV	8 SAN JACINTO ST	WNW 0 - 1/8 (0.072 mi.)	2458 / 11	7307
COVERT AUTOMO	420 SAN ANTONIO ST	WNW 0 - 1/8 (0.073 mi.)	2466 / 11	7311
416 20 COVERT AUTO C	416 SAN ANTONIO ST	WNW 0 - 1/8 (0.073 mi.)	OH2467 / 11	7311
LARSONS GARAGE AUTO	504 6TH ST W	WNW 0 - 1/8 (0.073 mi.)	OI2468 / 11	7311
LARSONS GAR AUTO REP	504 6TH W	WNW 0 - 1/8 (0.073 mi.)	OI2469 / 11	7311
NATIONAL FINANCE CO	413 CONGRESS AVE	SSW 0 - 1/8 (0.073 mi.)	LG2472 / 11	7318
FAST N EASY SHELL	31 N HWY 35	NNE 0 - 1/8 (0.074 mi.)	OM2475 / 14	7355
GREENBERG GRANT & RI	80 RED RIVER ST	WNW 0 - 1/8 (0.074 mi.)	2477 / 11	7356
HASSE SERVICE STATIO	1511 LAVACA	ESE 0 - 1/8 (0.075 mi.)	MZ2479 / 11	7363
UNIVERSITY BODY	1409 LAVACA	ESE 0 - 1/8 (0.075 mi.)	2483 / 11	7402
LAVACA ST GARAGE	1417 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	LT2486 / 11	7409
EVANS DELWOOD CONOCO	4201 EAST AVE	ENE 0 - 1/8 (0.075 mi.)	MQ2487 / 8	7409
1311 13 YOUNG & SCHI	1311 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	MR2490 / 11	7415
SPRINKLES BODY SHOP	1305 LAVACA	ESE 0 - 1/8 (0.075 mi.)	MR2491 / 11	7416
BATTERY SERVICE CO	1603 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	MZ2492 / 11	7416
KING I B STOVE	1419 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	LT2494 / 11	7416
LUDER FRED AUTO REPR	1313 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	MR2495 / 11	7417
FERRIS FRAME ALLGNME	830 SAGEBRUSH DR	WNW 0 - 1/8 (0.075 mi.)	2496 / 3	7417
EXXON MOBIL CORPORAT	619 W NORTH LOOP 35	ESE 0 - 1/8 (0.076 mi.)	2497 / 8	7417
TOWN LAKE CHEVRON SE	30 INTERREGIONAL HWY	NE 0 - 1/8 (0.076 mi.)	MO2501 / 14	7425
DARTER WELDING	408 SAN JACINTO ST	NNE 0 - 1/8 (0.076 mi.)	NX2502 / 11	7425
MALMBERG H G AUTO	104 31ST E	ESE 0 - 1/8 (0.077 mi.)	NM2507 / 8	7426
GULF INTRACOASTAL CA	221 E 9TH ST STE 206	ESE 0 - 1/8 (0.077 mi.)	2509 / 11	7427
KNIGHT WM Y	207 MILTON E	ESE 0 - 1/8 (0.077 mi.)	2516 / 14	7452
J RS AUTO REPR	406 38 1/2 W	WNW 0 - 1/8 (0.077 mi.)	2517 / 8	7453
AUSTIN FOREIGN CAR C	510 6TH ST W	WNW 0 - 1/8 (0.078 mi.)	OI2519 / 11	7453
EUROPEAN SPECIALIZED	510 6TH ST W	WNW 0 - 1/8 (0.078 mi.)	OI2520 / 11	7454
510 12 AUSTIN AUTOMA	510 6TH W	WNW 0 - 1/8 (0.078 mi.)	OI2521 / 11	7454
OVERSEAS MOTORS AUTO	6507 SHIRLEY AVE	ESE 0 - 1/8 (0.078 mi.)	LR2523 / 6	7457
AUSTIN FOUNDRY	200 5TH ST W	WSW 0 - 1/8 (0.078 mi.)	OK2525 / 11	7464
SIGMOR SHAMROCK SERV	3515 LAMAR BLVD N	WNW 0 - 1/8 (0.078 mi.)	OT2526 / 8	7464
CITIES SERVICE OIL C	1601 LAVACA ST	ESE 0 - 1/8 (0.078 mi.)	MZ2528 / 11	7490
A PAYLESS AUTOMOTIVE	11116 LAMAR BLVD N	WNW 0 - 1/8 (0.078 mi.)	2533 / 3	7513
MORELL ARTH D	500 ACADEMY DR	SW 0 - 1/8 (0.078 mi.)	2535 / 14	7514
MR SERVICE CENTERS	10200 N LAMAR BLVD	WNW 0 - 1/8 (0.079 mi.)	2536 / 3	7514
PIERPOINT MOTORS	8140 LAMAR BLVD N	NW 0 - 1/8 (0.079 mi.)	OU2537 / 6	7514
CAPITOL SERVICE STAT	1301 LAVACA	ESE 0 - 1/8 (0.079 mi.)	OW2539 / 11	7515
EMPIRE AUTOMOTIVE SE	604 E 7TH ST	NE 0 - 1/8 (0.080 mi.)	NZ2540 / 11	7516
FISHER FRANK C AUTO	205 5TH ST W	WSW 0 - 1/8 (0.080 mi.)	OK2542 / 11	7517
STEINERS SERVICE	205 5TH W	WSW 0 - 1/8 (0.080 mi.)	OK2543 / 11	7517
SMITH MOTOR CO AUTO	119 CONGRESS AVE	SSW 0 - 1/8 (0.080 mi.)	OG2549 / 11	7561
VIOLET CROWN GARAGE	207 5TH ST W	WSW 0 - 1/8 (0.081 mi.)	OK2552 / 11	7567
FREUND ROLAND R	207 5TH W	WSW 0 - 1/8 (0.081 mi.)	OK2553 / 11	7567
417 21 PATTON TRANSF	417 CONGRESS AVE E	NNE 0 - 1/8 (0.081 mi.)	MU2556 / 11	7572
RUDYS PHILLIPS	400 CONGRESS AVE	NNE 0 - 1/8 (0.081 mi.)	NT2557 / 11	7573
AUSTIN GOODYEAR CO	101 CONGRESS AVE	NNE 0 - 1/8 (0.081 mi.)	MN2558 / 11	7573
ROBINSON A A AUTO	209 5TH ST W	WSW 0 - 1/8 (0.082 mi.)	OK2564 / 11	7592
LONE STAR SUPPLY CO	209 5TH ST W	WSW 0 - 1/8 (0.082 mi.)	OK2565 / 11	7593
QUICK LUBE AUTO LUBR	3401 LAMAR BLVD N	WNW 0 - 1/8 (0.082 mi.)	OY2568 / 8	7609
THOMSON PREMIER SERV	3201 LAMAR BLVD N	WNW 0 - 1/8 (0.082 mi.)	OZ2574 / 8	7640
MARKLAND EXXON SERVI	3317 LAMAR BLVD N	WNW 0 - 1/8 (0.083 mi.)	OY2579 / 8	7679
DEISON AUTO REPR	320 CONGRESS AVE S	NE 0 - 1/8 (0.083 mi.)	LY2583 / 14	7690

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
NE COR MAGNOLIA PET	211 5TH ST W	WSW 0 - 1/8 (0.083 mi.)	OK2586 / 11	7691
BEAVER & SON AUTO &	8204 LAMAR BLVD N	NW 0 - 1/8 (0.083 mi.)	OU2590 / 6	7699
AUTO SALVAGE CO	419 COLORADO ST	SW 0 - 1/8 (0.083 mi.)	OK2594 / 11	7709
GENES MAGNOLIA SER	500 1ST E	ESE 0 - 1/8 (0.084 mi.)	PB2599 / 11	7734
CONOCOPHILLIPS COMPA	1122 COLORADO ST STE	WNW 0 - 1/8 (0.084 mi.)	2602 / 11	7735
BEARD SPRING	213 5TH W	WSW 0 - 1/8 (0.084 mi.)	OK2603 / 11	7736
BEARD SPRING C BRAKE	213 5TH ST W	WSW 0 - 1/8 (0.084 mi.)	OK2604 / 11	7736
PURYEAR DEWEY	206 5TH W	WSW 0 - 1/8 (0.084 mi.)	OK2605 / 11	7736
WILBURN SINCLAIR SER	520 6TH ST W	WNW 0 - 1/8 (0.084 mi.)	OI2606 / 11	7737
BASS SERV STA	520 6TH W	WNW 0 - 1/8 (0.084 mi.)	OI2607 / 11	7737
CURTS OIL CO INC	2101 S FIRST	WNW 0 - 1/8 (0.086 mi.)	OR2620 / 14	7789
RACETRAC PETROLEUM I	6607 CIRCLE S RD	ESE 0 - 1/8 (0.086 mi.)	PF2623 / 17	7826
CHOTES CHEVRON SERVI	500 MARTIN LUTHER KI	W 0 - 1/8 (0.086 mi.)	PA2631 / 11	7845
TRATEX AUTO STORAGE	208 5TH W	WSW 0 - 1/8 (0.086 mi.)	OK2637 / 11	7966
SMITH & HUDLER BROS	406 BRAZOS ST	SSW 0 - 1/8 (0.086 mi.)	OD2638 / 11	7966
SCHRAMM GULF SERV	107 CONGRESS AVE	NNE 0 - 1/8 (0.087 mi.)	MN2641 / 11	7980
A CRENSHAW GARAGE AU	711 RED RIVER CT	NE 0 - 1/8 (0.087 mi.)	NY2646 / 11	7988
BRYANT AUTOMOTIVE	505 OLTORF ST W	W 0 - 1/8 (0.088 mi.)	PJ2650 / 14	7992
HERWICK DON PHILLIPS	4834 EAST AVE	ENE 0 - 1/8 (0.088 mi.)	MQ2653 / 8	7993
RAMIREZ GULF SERVICE	329 CONGRESS AVE S	NE 0 - 1/8 (0.088 mi.)	NA2656 / 14	7999
BUTLERS GULF SERV	329 CONGRESS AVE S	NE 0 - 1/8 (0.088 mi.)	NA2657 / 14	7999
DEWEYS RADIATOR	112 COLORADO ST	SSW 0 - 1/8 (0.089 mi.)	OJ2671 / 11	8034
GRAYBURG OIL CO NO	100 CONGRESS AVE E	NNE 0 - 1/8 (0.090 mi.)	MN2677 / 11	8052
SUPER TRANSMISSION	2704 WILSON ST	WSW 0 - 1/8 (0.090 mi.)	2678 / 14	8052
B & B GARAGE	117 CONGRESS AVE	SSW 0 - 1/8 (0.090 mi.)	OG2682 / 11	8081
MC CULLOUGH D T	116 CONGRESS AVE	SSW 0 - 1/8 (0.090 mi.)	OG2683 / 11	8081
HERMAN GARAGE	608 INTERREGIONAL HW	ENE 0 - 1/8 (0.090 mi.)	PN2684 / 11	8082
413 15 POWELL GARAGE	413 COLORADO ST	SW 0 - 1/8 (0.091 mi.)	OK2689 / 11	8094
MAGNOLIA PET CO NO	212 5TH ST W	WSW 0 - 1/8 (0.091 mi.)	OK2695 / 11	8106
ADAMS QUADRACYCLE	610 INTERREGIONAL HW	ENE 0 - 1/8 (0.091 mi.)	PN2697 / 11	8106
JOHNSONS GARAGE	504 7TH W	ESE 0 - 1/8 (0.091 mi.)	PO2698 / 11	8107
EAST 9TH STREET COMP	201 W 5TH ST STE 220	WSW 0 - 1/8 (0.091 mi.)	OK2701 / 11	8107
CHOTES SINCLAIR SERV	500 W 19TH ST	E 0 - 1/8 (0.092 mi.)	PA2704 / 11	8113
DARRELL ROYAL WORK S	104 CONGRESS AVE	NNE 0 - 1/8 (0.092 mi.)	OG2707 / 11	8117
113 15 GULF REFG CO	113 CONGRESS AVE E	NNE 0 - 1/8 (0.093 mi.)	OG2716 / 11	8224
LAKESICE EXXON PRODU	31 INTERREGIONAL HWY	NNE 0 - 1/8 (0.093 mi.)	OM2717 / 14	8224
DEWEY GARAGE	115 CONGRESS AVE	SSW 0 - 1/8 (0.093 mi.)	OG2719 / 11	8225
POWELL AUTO BODY	409 COLORADO	SW 0 - 1/8 (0.094 mi.)	OK2722 / 11	8226
MC FARLAND F H	404 BRAZOS ST	NNE 0 - 1/8 (0.095 mi.)	OD2729 / 11	8233
RIVERSIDE FINA SERVI	1100 INTERREGIONAL H	NNE 0 - 1/8 (0.095 mi.)	2730 / 14	8233
PATTERSONS GARAGE C	716 RED RIVER CT	NE 0 - 1/8 (0.095 mi.)	NY2733 / 11	8239
LAMAR VILLAGE SHELL	3724 LAMAR BLVD N	WNW 0 - 1/8 (0.096 mi.)	OT2738 / 8	8250
HICKMAN R L C AUTO	718 RED RIVER CT	NE 0 - 1/8 (0.096 mi.)	NY2740 / 11	8266
KEMAC CORPORATION	113 METEOR DR A	WNW 0 - 1/8 (0.097 mi.)	2742 / 17	8266
MOTORCYCLE RESSURECT	2209 S 1ST ST	WNW 0 - 1/8 (0.097 mi.)	PQ2743 / 14	8267
THOMSON PREMIER SERV	3201 LAMAR BLVD N	WNW 0 - 1/8 (0.098 mi.)	OZ2744 / 8	8267
INTERRIGIONAL CONOCO	901 1ST ST E	ESE 0 - 1/8 (0.098 mi.)	OX2747 / 11	8269
CUSTOM ENGINE RE	603 MARY W	WNW 0 - 1/8 (0.098 mi.)	PU2749 / 14	8269
AUSTIN AUTOMOTIVE	603 MARY ST W	WNW 0 - 1/8 (0.098 mi.)	PU2750 / 14	8270
HILES JOHN L WASHING	900 1ST ST E	ESE 0 - 1/8 (0.099 mi.)	OX2753 / 11	8285
RICHMOND AUTO	828 PRAIRIE TRL	WNW 0 - 1/8 (0.100 mi.)	PW2755 / 3	8285
FRANKES SLS &	4126 LAMAR BLVD N	NW 0 - 1/8 (0.100 mi.)	PX2756 / 8	8285
ROGERS BROS SERV STA	200 1ST E	ENE 0 - 1/8 (0.100 mi.)	PY2757 / 11	8286
GOODNIGHT SERV STA	4700 CONGRESS AVE S	WNW 0 - 1/8 (0.100 mi.)	PZ2760 / 17	8294
STA & GARAGE	3900 LAMAR BLVD N	WNW 0 - 1/8 (0.103 mi.)	PR2765 / 8	8317
TOWN LAKE GULF SERVI	901 CLERMONT AVE	NE 0 - 1/8 (0.104 mi.)	2778 / 14	8389

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
WALSH SERVICE STATIO	719 E 7TH ST	ENE 0 - 1/8 (0.105 mi.)	QC2785 / 11	8491
BANYON AUTOMOTIVE AU	916 BANYAN ST	WNW 0 - 1/8 (0.105 mi.)	2788 / 6	8494
BERANS CONOCO SERV S	1500 SAN JACINTO	ESE 0 - 1/8 (0.105 mi.)	PD2789 / 11	8494
T&T TRANSMISSION	601 FERGUSON DR	ESE 0 - 1/8 (0.105 mi.)	2791 / 3	8497
BURNETTE SERVICE STA	1700 SAN JACINTO	ESE 0 - 1/8 (0.105 mi.)	QD2793 / 11	8503
CAR CARE BV ISSAC	3100 LAMAR BLVD N	WNW 0 - 1/8 (0.106 mi.)	QE2798 / 8	8516
DOC & BUSTER SERV	1508 SAN JACINTO	ESE 0 - 1/8 (0.109 mi.)	QK2812 / 11	8568
SMITH JAY BODY SHOP	832 5TH ST W	WNW 0 - 1/8 (0.109 mi.)	QF2817 / 11	8656
BRAKE CHECK	3700 LAMAR BLVD N	WNW 0 - 1/8 (0.112 mi.)	OT2825 / 8	8679
MOBIL MART	717 7TH ST E	ENE 0 - 1/8 (0.113 mi.)	QC2826 / 11	8679
WALSH SERVICE CENTER	717 7TH ST E	ENE 0 - 1/8 (0.113 mi.)	QC2827 / 11	8680
Z CAR SHOP	811 MCPHAUL	WNW 0 - 1/8 (0.113 mi.)	QO2828 / 3	8680
HUMBLE OIL REFG CO	1800 SAN JACINTO ST	ESE 0 - 1/8 (0.115 mi.)	QQ2838 / 11	8705
KOCUREK WILLIE	1822 SAN JACINTO ST	ESE 0 - 1/8 (0.116 mi.)	QQ2839 / 11	8705
KOCUREKS SERVICE STA	1818 SAN JACINTO	ESE 0 - 1/8 (0.116 mi.)	QQ2841 / 11	8706
WALSH NORMAN SERVICE	719 7TH ST E	ENE 0 - 1/8 (0.116 mi.)	QC2842 / 11	8706
BROWN & WALSH SERV S	719 7TH E	ENE 0 - 1/8 (0.116 mi.)	QC2843 / 11	8706
PRONTO ENGINE & TRAN	830 PRAIRIE TRL	WNW 0 - 1/8 (0.116 mi.)	PW2844 / 3	8707
A E D AUTO UPHOLSTER	615 POWELL LN W	SE 0 - 1/8 (0.116 mi.)	QR2845 / 6	8707
LONE STAR CYCLE MOTI	4108 LAMAR BLVD N	NW 0 - 1/8 (0.117 mi.)	PX2846 / 8	8707
LES & MACS SERV	301 15TH E	ESE 0 - 1/8 (0.118 mi.)	PD2854 / 11	8730
B CAMERON AUTOMOTIVE	611 POWELL LN W	SE 0 - 1/8 (0.118 mi.)	QR2855 / 6	8731
STANFORD GUY REPR SH	508 JOAN OF ARC	ESE 0 - 1/8 (0.119 mi.)	2856 / 6	8731
RUTLAND AUTO PARTS	1127 BASTROP HWY	ENE 0 - 1/8 (0.120 mi.)	2857 / 16	8731
DEATHE TEXACO SERV	1701 SAN JACINTO	ESE 0 - 1/8 (0.122 mi.)	QD2863 / 11	8737
SAN JACINTO GARAGE	1511 SAN JACINTO ST	ESE 0 - 1/8 (0.122 mi.)	QK2867 / 11	8753
WALSH SERVICE CENTER	717 E 7TH ST	ENE 0 - 1/8 (0.122 mi.)	QC2872 / 11	8801
CULLEN SERVICE STA	1407 SAN JACINTO	ESE 0 - 1/8 (0.122 mi.)	QV2874 / 11	8803
EMMETT SINCLAIR SERV	1409 SAN JACINTO ST	ESE 0 - 1/8 (0.122 mi.)	QV2875 / 11	8803
PAYLESS GAS NO 657	2805 SAN JACINTO BLV	E 0 - 1/8 (0.123 mi.)	QM2880 / 11	8818
TRANSMISSION EVENTS	501 N INTERSTATE 35	E 0 - 1/8 (0.123 mi.)	QX2881 / 11	8818
DAY R L GARAGE	1301 SAN JACINTO ST	ESE 0 - 1/8 (0.123 mi.)	QU2882 / 11	8818

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 290 EDR Hist Cleaner sites within approximately 0.125 miles of the requested target property.

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
IVORY CLEANERS & ALT	1901 RIO GRANDE ST	E 0 - 1/8 (0.011 mi.)	HQ948 / 11	2890
WESLEY GEORGE CLEANE	606 GUADALUPE ST	WNW 0 - 1/8 (0.011 mi.)	HR957 / 11	2916
LONGHORN CLEANERS NO	705 W 24TH ST	E 0 - 1/8 (0.012 mi.)	BX961 / 11	2918
MY CLEANERS & ALTERA	3100 GUADALUPE ST	WNW 0 - 1/8 (0.012 mi.)	BD981 / 8	3006
KWIK WASH COIN LAUND	6606 CONGRESS AVE S	WNW 0 - 1/8 (0.012 mi.)	HL988 / 17	3021
BURTONS LNDRY	411 23RD W	W 0 - 1/8 (0.012 mi.)	HU995 / 11	3071
QUONG WAH CHINESE LA	115 E 7TH ST	NNE 0 - 1/8 (0.012 mi.)	DG996 / 11	3071
CUSTOM SERVICE CARPE	607 RIO GRANDE ST	WNW 0 - 1/8 (0.012 mi.)	DA1005 / 11	3181
DOLLARS AND CENTS	2268 GUADALUPE	W 0 - 1/8 (0.012 mi.)	HU1007 / 11	3188
HARDIN RICHD G CO	2200 RIO GRANDE ST	W 0 - 1/8 (0.012 mi.)	BZ1009 / 11	3189
B CO OP PRESSING	2304 GUADALUPE ST	W 0 - 1/8 (0.012 mi.)	HU1013 / 11	3196
REYES CLNRS	312 BARTON SPRINGS	NE 0 - 1/8 (0.012 mi.)	IA1014 / 11	3196
TEXAS CLEANERS	2236 GUADALUPE	W 0 - 1/8 (0.012 mi.)	1025 / 11	3254
TOWNLAKE CLEANERS	2017 RIVERSIDE DR E	SW 0 - 1/8 (0.012 mi.)	FR1026 / 14	3254
RIVER HILLS SHOPPING	1901 RIVERSIDE DR	WSW 0 - 1/8 (0.013 mi.)	FL1028 / 14	3254

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
TOWNE PARK LTD	611 S CONGRESS AVE	ESE 0 - 1/8 (0.013 mi.)	EO1031 / 14	3256
LOCKHART LNDRY	2612 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	BN1035 / 11	3260
BRANUM CLEANERS	2716 GUADALUPE	WSW 0 - 1/8 (0.013 mi.)	BM1036 / 11	3260
JONES JOHN H CLOTH	2214 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	CA1046 / 11	3305
MANAISH ENTERPRISES	9616 N LAMAR BLVD ST	WNW 0 - 1/8 (0.013 mi.)	O1056 / 6	3348
CAMPUS SHOP CLNRS	2332 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	1058 / 11	3357
T CLEANING & PRESSIN	2206 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	CA1064 / 11	3370
OXFORD CLEANERS	2928 GUADALUPE ST	WNW 0 - 1/8 (0.013 mi.)	BG1065 / 8	3370
RIOS BROS TAILORS	115 7TH W	ESE 0 - 1/8 (0.013 mi.)	DF1085 / 11	3458
C BYRD ROY CLN NO 2	2610 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	BN1090 / 11	3467
MONKEY SEE MONKEY DO	1712 S CONGRESS AVE	WNW 0 - 1/8 (0.013 mi.)	FE1093 / 14	3479
LONGHORN TAILOR SHOP	2424 GUADALUPE ST	W 0 - 1/8 (0.013 mi.)	BV1094 / 11	3479
WILLIAMS WESS	2102 GUADALUPE	W 0 - 1/8 (0.013 mi.)	IG1096 / 11	3482
MASON STEAM LNDRY	2006 SPEEDWAY	E 0 - 1/8 (0.013 mi.)	IH1099 / 11	3488
DICKERSON CLEANING	111 6TH W	NNE 0 - 1/8 (0.013 mi.)	DH1104 / 11	3516
UNIVERSITY CLNS	2004 SPEEDWAY	E 0 - 1/8 (0.013 mi.)	IH1105 / 11	3516
NEWSOME FRED C CLNR	106 6TH W	NNE 0 - 1/8 (0.013 mi.)	DH1117 / 11	3566
WILLIAMS WESS	2014 SPEEDWAY	E 0 - 1/8 (0.013 mi.)	IH1118 / 11	3567
PARIS CLEANING PARLO	102 6TH W	NNE 0 - 1/8 (0.013 mi.)	DH1120 / 11	3574
SMITH KELLEY TAILOR	109 6TH W	NNE 0 - 1/8 (0.014 mi.)	DH1122 / 11	3578
BROWN JACK CLEANERS	2215 S CONGRESS AVE	E 0 - 1/8 (0.014 mi.)	FQ1126 / 14	3596
LATTIMORE CLEANERS	129 6TH E	NNE 0 - 1/8 (0.014 mi.)	DN1131 / 11	3640
REYES CLNS	2504 GUADALUPE ST	W 0 - 1/8 (0.014 mi.)	BU1132 / 11	3640
MAJESTIC CLNRS	219 6TH E	NNE 0 - 1/8 (0.014 mi.)	DP1135 / 11	3641
MAJESTIC CLEANERS GR	219 6TH ST E	NNE 0 - 1/8 (0.014 mi.)	DP1136 / 11	3641
B LAMAR CINS NO	812 BRANTWOOD ST	WNW 0 - 1/8 (0.014 mi.)	AG1156 / 6	3717
RIOS ALPHONSO TAILO	706 CONGRESS AVE	ESE 0 - 1/8 (0.014 mi.)	DF1161 / 11	3752
BONILLA JOHN TAILOR	600 CONGRESS AVE	ESE 0 - 1/8 (0.014 mi.)	DH1179 / 11	3812
CAPITOL CARPET CLEAN	4506 CONGRESS AVE S	WNW 0 - 1/8 (0.014 mi.)	HD1180 / 17	3812
TIP TOP CLEANERS	3202 GUADALUPE ST	WNW 0 - 1/8 (0.014 mi.)	IJ1182 / 8	3816
HONG WAH CHINESE LAU	804 CONGRESS AVE	ESE 0 - 1/8 (0.014 mi.)	IK1184 / 11	3817
SHEEHAN DENNIS W. T	5014 CONGRESS AVE	WNW 0 - 1/8 (0.015 mi.)	1186 / 17	3828
T & T CLEANERS LAUND	3206 GUADALUPE ST	WNW 0 - 1/8 (0.015 mi.)	IJ1187 / 8	3828
ATLAS CLEANERS NO	6110 RIVERSIDE DR E	NNE 0 - 1/8 (0.015 mi.)	IN1205 / 15	3857
SCHEUMACK & HART TA	314 6TH E	NNE 0 - 1/8 (0.015 mi.)	DQ1208 / 11	3860
SANCHEZ BROS CLO CLN	312 6TH E	NNE 0 - 1/8 (0.015 mi.)	DQ1209 / 11	3860
UNIVERSITY TOGGERY M	2310 GUADALUPE ST	W 0 - 1/8 (0.015 mi.)	HU1210 / 11	3861
PASSON FRED W C TAI	407 6TH E	NNE 0 - 1/8 (0.015 mi.)	DQ1224 / 11	3885
LUDWIG ROBERT TAILO	406 6TH E	NNE 0 - 1/8 (0.015 mi.)	DQ1225 / 11	3885
SMITH DEE 0 TAILOR	410 6TH E	NNE 0 - 1/8 (0.015 mi.)	IP1226 / 11	3885
SMITH A T DCLO PRESS	318 6TH E	NNE 0 - 1/8 (0.016 mi.)	DQ1228 / 11	3888
DATSON ISHMAEL C DCL	412 6TH E	NNE 0 - 1/8 (0.016 mi.)	IP1229 / 11	3888
WING KEE	418 6TH E	NNE 0 - 1/8 (0.016 mi.)	IP1237 / 11	3930
SULLIVAN CARDINAL DC	3510 GUADALUPE ST	WNW 0 - 1/8 (0.016 mi.)	IC1244 / 8	3934
FELTON B F C CLDO	422 6TH E	NNE 0 - 1/8 (0.016 mi.)	IP1246 / 11	3935
WILLIAMS WESS	2100 GUADALUPE ST	W 0 - 1/8 (0.016 mi.)	IG1265 / 11	4032
COZY CLEANING AND	2402 GUADALUPE ST	W 0 - 1/8 (0.017 mi.)	BV1270 / 11	4066
LONGHORN CLEANERS	2538 GUADALUPE	W 0 - 1/8 (0.017 mi.)	BS1272 / 11	4068
BROWN JACK CLEANERS	2026 GUADALUPE ST	W 0 - 1/8 (0.017 mi.)	CB1279 / 11	4076
BROWN JACK CLEANERS	1901 E RIVERSIDE DR	WSW 0 - 1/8 (0.017 mi.)	FL1281 / 14	4077
VARSITY PRESSING SHO	2105 SPEEDWAY	E 0 - 1/8 (0.017 mi.)	IH1284 / 11	4080
HOME STEAM	118 10TH E	WNW 0 - 1/8 (0.017 mi.)	CV1286 / 11	4098
UNIVERSITY CLEANING	2109 SPEEDWAY	E 0 - 1/8 (0.017 mi.)	IH1289 / 11	4099
TROY BRANCH AUSTIN	806 CONGRESS AVE	ESE 0 - 1/8 (0.018 mi.)	IK1291 / 11	4138
COIN 00 MATIC LAUNDR	6607 LAMAR BLVD N	ESE 0 - 1/8 (0.018 mi.)	AG1307 / 6	4171
BYRD ROY CLEANERS	2002 GUADALUPE ST	W 0 - 1/8 (0.018 mi.)	CB1310 / 11	4172

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
DRISKILL HOTEL	121 7TH E	WNW 0 - 1/8 (0.018 mi.)	DF1312 / 11	4175
SPEEDWAY CLEANERS	2608 SPEEDWAY	E 0 - 1/8 (0.019 mi.)	IV1314 / 11	4176
LAWSHA LEE DCLO CLNR	215 CONGRESS AVE	SSW 0 - 1/8 (0.019 mi.)	DY1320 / 11	4189
CHING WONG CLEANERS	3001 GUADALUPE ST	ESE 0 - 1/8 (0.019 mi.)	BF1326 / 8	4202
CHAMBERS	1025 CONGRESS AVE	ESE 0 - 1/8 (0.019 mi.)	1329 / 11	4204
CASTRO CLEANERS	502 E 6TH ST	SW 0 - 1/8 (0.019 mi.)	DR1338 / 11	4232
NO DELAY CLEANERS	1117 S CONGRESS	ESE 0 - 1/8 (0.020 mi.)	ET1344 / 14	4262
GUTHRIE J C	1712 CONGRESS AVE	ESE 0 - 1/8 (0.020 mi.)	CK1345 / 11	4262
NORVELL MACHINERY CO	6535 LAMAR BLVD N	ESE 0 - 1/8 (0.020 mi.)	AG1352 / 6	4269
ACME DRY CLEANERS &	8901 LAMAR BLVD N	ESE 0 - 1/8 (0.020 mi.)	R1356 / 6	4270
DRISKILL LNDRY	119 7TH E	WNW 0 - 1/8 (0.020 mi.)	DF1357 / 11	4270
DURACLEAN ARTHOR CAR	6901 LAMAR BLVD N	ESE 0 - 1/8 (0.020 mi.)	IZ1360 / 6	4271
LINZ NICK TAILOR	611 CONGRESS AVE E	NNE 0 - 1/8 (0.020 mi.)	DH1381 / 11	4368
WESLEY G M DCLO CLNR	913 CONGRESS AVE	WNW 0 - 1/8 (0.021 mi.)	CW1384 / 11	4369
KOFAHL CHRIS BARBER	911 CONGRESS ST	WNW 0 - 1/8 (0.021 mi.)	JB1387 / 11	4370
LINZ GUST B CLNR	809 CONGRESS AVE	WNW 0 - 1/8 (0.021 mi.)	DB1398 / 11	4428
KWIK WASH COIN LAUND	7543 LAMAR BLVD N	ESE 0 - 1/8 (0.021 mi.)	Z1399 / 6	4429
VIP CLEANERS	805 N CONGRESS	WNW 0 - 1/8 (0.021 mi.)	DB1400 / 11	4429
UNITED STATES CLEANE	309 W 5TH ST	ESE 0 - 1/8 (0.021 mi.)	DI1403 / 11	4436
PEARL STEAM LAUNDRY	819 CONGRESS AVE	WNW 0 - 1/8 (0.021 mi.)	IK1407 / 11	4447
RAPP BROS NEWS DLR A	617 CONGRESS AVE	WNW 0 - 1/8 (0.021 mi.)	DF1409 / 11	4448
RAPP BROS NEWS DLRS	621 CONGRESS AVE	WNW 0 - 1/8 (0.022 mi.)	DF1416 / 11	4457
STADIUM DRY CLEANERS	2107 SPEEDWAY	E 0 - 1/8 (0.022 mi.)	1429 / 11	4551
WARDROBE CLNRS	213 CONGRESS AVE	SSW 0 - 1/8 (0.022 mi.)	DY1430 / 11	4551
MODEL STEAM LAUNDRY	112 10TH E	WNW 0 - 1/8 (0.022 mi.)	CV1437 / 11	4574
ONE DAY CLNS	407 7TH E	NNE 0 - 1/8 (0.023 mi.)	DM1443 / 11	4576
CAPITOL LAUNDRY & DR	806 KOENIG LN W	WNW 0 - 1/8 (0.023 mi.)	AL1455 / 8	4635
CHESNUTT CLNRS	103 18TH W	ESE 0 - 1/8 (0.023 mi.)	JI1464 / 11	4667
RIOS FRANK TAILOR	103 7TH W	ESE 0 - 1/8 (0.023 mi.)	DF1469 / 11	4669
GUEROS ADDL SP	616 OLTORF ST E	SE 0 - 1/8 (0.023 mi.)	FY1480 / 14	4703
SWEET ONE HOUR	613 CONGRESS AVE	W 0 - 1/8 (0.023 mi.)	DG1483 / 11	4721
JOE SING CHINESE LAU	104 E 6TH ST	NNE 0 - 1/8 (0.023 mi.)	DN1484 / 11	4722
WASHBURNS TOWN & COU	1423 S CONGRESS AVE	ESE 0 - 1/8 (0.023 mi.)	FB1492 / 14	4744
DEEP EDDY RUG CLEANE	418 BARTON SPRINGS	SE 0 - 1/8 (0.024 mi.)	EH1504 / 14	4818
A KISS CLEAN	418 BARTON SPRINGS	SE 0 - 1/8 (0.024 mi.)	EH1505 / 14	4818
RIOS FRANK TAILOR	101 7TH W	ESE 0 - 1/8 (0.025 mi.)	DF1516 / 11	4872
PAGE S F DCLO CLNR	802 CONGRESS AVE E	ESE 0 - 1/8 (0.025 mi.)	DB1517 / 11	4872
ROYAL THE CLNRS	703 CONGRESS AVE	WNW 0 - 1/8 (0.025 mi.)	DF1522 / 11	4883
WESLEY G M DCLO CLNR	913 CONGRESS AVE E	ESE 0 - 1/8 (0.025 mi.)	JB1525 / 11	4884
TEXAS TAILOR SHOP	1900 GUADALUPE ST	W 0 - 1/8 (0.025 mi.)	CD1532 / 11	4913
CASTROS CLEANERS	502 6TH ST E	NE 0 - 1/8 (0.025 mi.)	DR1535 / 11	4919
SANCHEZ BROS DCLO CL	502 6TH E	NE 0 - 1/8 (0.025 mi.)	DR1536 / 11	4919
HOOVER CLEANERS GR 8	502 6TH ST E	NE 0 - 1/8 (0.025 mi.)	DR1537 / 11	4920
DRISKILL STEAM LAUN	113 7TH E	WNW 0 - 1/8 (0.025 mi.)	DF1543 / 11	4962
HONG LEE LAUNDRY	113 8TH E	WNW 0 - 1/8 (0.025 mi.)	DB1544 / 11	4963
DEEP EDDY RUG CINS	414 BARTON SPRINGS	SE 0 - 1/8 (0.025 mi.)	EH1545 / 14	4963
DAVIS & CO TAILORS	1008 CONGRESS AVE	ESE 0 - 1/8 (0.025 mi.)	CV1551 / 11	4993
LINZ NICK TAILOR	611 CONGRESS AVE	WSW 0 - 1/8 (0.026 mi.)	DG1565 / 11	5064
GUTHTLRIE J C DCLO C	1712 CONGRESS AVE E	ESE 0 - 1/8 (0.026 mi.)	CK1569 / 11	5095
G F DURDEN C	504 6TH E	NE 0 - 1/8 (0.026 mi.)	DR1576 / 11	5128
KWIK WASH COIN LAUND	704 24TH ST W	E 0 - 1/8 (0.026 mi.)	BW1577 / 11	5128
DOYLE DARBY TAILOR	506 6TH E	NE 0 - 1/8 (0.026 mi.)	DR1589 / 11	5196
WASHTUB & PUB COIN O	1717 PLEASANT VALLE	NE 0 - 1/8 (0.026 mi.)	1597 / 15	5249
ALL-PRO CLEANERS INC	602 W 7TH ST	ESE 0 - 1/8 (0.026 mi.)	CX1598 / 11	5250
AUSTIN STEPHEN F HOT	102 7TH E	ESE 0 - 1/8 (0.027 mi.)	DF1599 / 11	5250
AUSTIN LAUNDRY & DRY	608 W 24TH ST	E 0 - 1/8 (0.027 mi.)	BW1600 / 11	5250

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
BROWN & ELLIOTT INC	2326 S CONGRESS	WNW 0 - 1/8 (0.027 mi.)	FT1605 / 14	5259
ACME CLEANERS	320 1ST E	WNW 0 - 1/8 (0.027 mi.)	EE1612 / 11	5263
SPICK SPAN LAUNDRY	1421 ARENA DR	ENE 0 - 1/8 (0.027 mi.)	FJ1618 / 14	5268
CASH AND CARRY	111 7TH E	WNW 0 - 1/8 (0.027 mi.)	DF1619 / 11	5268
KWIK WASH LAUNDRY	718 LAMAR PL	ESE 0 - 1/8 (0.027 mi.)	JG1621 / 6	5269
STEVENSON J C C DCLO	510 6TH E	NE 0 - 1/8 (0.027 mi.)	DR1626 / 11	5283
VACANT 2 CASTROS CLE	511 6TH ST E	NE 0 - 1/8 (0.027 mi.)	DR1628 / 11	5284
GUTHRIES CLEANERS	9200 LAMAR BLVD N	WNW 0 - 1/8 (0.027 mi.)	JU1634 / 6	5321
GALVAN IGNACIO CLDO	512 6TH E	NE 0 - 1/8 (0.027 mi.)	DR1646 / 11	5477
LUDWIG ROBERT W TAIL	402 E 6TH ST	NNE 0 - 1/8 (0.028 mi.)	IP1652 / 11	5480
FERDINANDTSEN G E N	2406 GUADALUPE ST	W 0 - 1/8 (0.028 mi.)	BV1653 / 11	5480
BIGGS & CO TAILORS	1007 CONGRESS AVE E	ESE 0 - 1/8 (0.028 mi.)	CV1655 / 11	5481
ATTAL THOS SHOE REPR	515 6TH E	NE 0 - 1/8 (0.028 mi.)	DR1659 / 11	5504
BIGGS & CO TAILOR	1007 CONGRESS AVE	WNW 0 - 1/8 (0.028 mi.)	CV1661 / 11	5504
DEEP EDDY RUG & CARP	512 RIO GRANDE ST	WNW 0 - 1/8 (0.028 mi.)	DA1663 / 11	5505
PEELER JOHN F TAILO	1003 CONGRESS AVE	WNW 0 - 1/8 (0.028 mi.)	CV1675 / 11	5532
2 RODRIGUEZ JOS CLDO	517 6TH E	NE 0 - 1/8 (0.028 mi.)	DR1679 / 11	5567
MASTER VALET CLNS	109 7TH E	WNW 0 - 1/8 (0.029 mi.)	DF1680 / 11	5567
MASTER VALET CLEANER	109 7TH ST E	WNW 0 - 1/8 (0.029 mi.)	DF1681 / 11	5568
SHIRLEY CLEANERS & H	310 W 6TH ST	ESE 0 - 1/8 (0.029 mi.)	DE1691 / 11	5581
AUSTIN STEPH F HOTEL	106 7TH E	ESE 0 - 1/8 (0.030 mi.)	DF1717 / 11	5672
GRANT JAMES C CLNR	505 BRAZOS ST	SSW 0 - 1/8 (0.031 mi.)	DP1725 / 11	5722
LINZ NICK TAILOR	607 CONGRESS AVE	WSW 0 - 1/8 (0.031 mi.)	DG1733 / 11	5739
UNITED STATES CLEANE	601 W 5TH ST	ESE 0 - 1/8 (0.031 mi.)	DD1734 / 11	5740
QUALITY CLEANERS GR	111 E 19TH ST	W 0 - 1/8 (0.031 mi.)	1735 / 11	5740
TWENTY NINTH STREET	604 W 29TH ST	WNW 0 - 1/8 (0.032 mi.)	BH1737 / 8	5740
NUNEZ BROS TAILORS	506 BRAZOS	SSW 0 - 1/8 (0.032 mi.)	JP1754 / 11	5883
MAJIK IRONERS INC	114 W 7TH ST	WNW 0 - 1/8 (0.033 mi.)	DF1767 / 11	5922
PARSLEY W L DCLO CLN	310 CONGRESS AVE	NNE 0 - 1/8 (0.034 mi.)	DY1786 / 11	5970
TEXAS PEST CONTROL	3510 CONGRESS AVE	WNW 0 - 1/8 (0.034 mi.)	1789 / 14	5995
DRY CIN VILLAGE	604 29TH W	WNW 0 - 1/8 (0.035 mi.)	BG1807 / 8	6069
MASTER DICKENS CLEAN	604 29TH ST W	WNW 0 - 1/8 (0.035 mi.)	BG1809 / 8	6070
WALKER J M CLDO CLNR	208 CONGRESS AVE	SSW 0 - 1/8 (0.035 mi.)	KH1812 / 11	6070
A MASTER DICKENS CLE	2815 FRUTH ST	ENE 0 - 1/8 (0.036 mi.)	BK1814 / 11	6071
HOME STEAM LAUNDRY	601 E 14TH ST	ESE 0 - 1/8 (0.036 mi.)	1826 / 11	6084
PEARL LAUNDRY	401 1ST E	ESE 0 - 1/8 (0.037 mi.)	KS1839 / 11	6090
WILLIE FOO CHINESE L	113 E 8TH ST	ESE 0 - 1/8 (0.039 mi.)	KW1870 / 11	6215
HOWARDS CLEANERS	804 1ST E	ESE 0 - 1/8 (0.039 mi.)	KU1880 / 11	6250
SMITH J B	821 12TH W	WNW 0 - 1/8 (0.040 mi.)	JA1887 / 11	6289
BROWN JACK CLEANERS	615 W MLK BLVD	E 0 - 1/8 (0.041 mi.)	LF1898 / 11	6337
REYES CLNRS	611 6TH W	ESE 0 - 1/8 (0.042 mi.)	KR1913 / 11	6374
CONVENIENCE COIN LAU	606 29TH ST W	WNW 0 - 1/8 (0.043 mi.)	BH1919 / 8	6400
CONVENIENCE COIN LAU	606 W 29TH ST	WNW 0 - 1/8 (0.043 mi.)	BH1920 / 8	6400
GUADALUPE LAUNDROMAT	606 29TH W	WNW 0 - 1/8 (0.043 mi.)	BH1921 / 8	6400
ASTRO CLEANERS	1900 E RIVERSIDE DR	ENE 0 - 1/8 (0.044 mi.)	1933 / 14	6420
LUCKY CLEANERS	7601 N LAMAR BLVD ST	ESE 0 - 1/8 (0.044 mi.)	LN1940 / 6	6425
ROAD RUNNERS COMMERC	1511 FARO DR	NNE 0 - 1/8 (0.045 mi.)	1952 / 15	6452
MARIES TAILOR SHOP	1708 S LAKESHORE BLV	ENE 0 - 1/8 (0.045 mi.)	KX1953 / 14	6452
NW COR WEAVER MARGT	612 4TH W	ESE 0 - 1/8 (0.045 mi.)	LE1956 / 11	6453
FRY JOHN L CLOTHES	202 CONGRESS AVE	SSW 0 - 1/8 (0.046 mi.)	KH1977 / 11	6476
TUXEDO JUNCTION CLEA	611 W 29TH ST	WNW 0 - 1/8 (0.047 mi.)	LU1983 / 8	6485
NISHIO INTERNATIONAL	8610 N LAMAR STE 101	NW 0 - 1/8 (0.047 mi.)	1993 / 6	6490
CAPITOL LAUNDRY 6 DR	301 W 8TH ST	ESE 0 - 1/8 (0.050 mi.)	MI2044 / 11	6616
OCONNELL & WORLEY	201 8TH E	ESE 0 - 1/8 (0.051 mi.)	KW2052 / 11	6618
NELSON CHESTER B	603 9TH W	ESE 0 - 1/8 (0.051 mi.)	2053 / 11	6618
GRAY CLEANERS	3912 SPEEDWAY	ESE 0 - 1/8 (0.052 mi.)	2061 / 8	6621

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
LAY WALLACE DCLO CLN	3808 SPEEDWAY	ESE 0 - 1/8 (0.052 mi.)	2072 / 8	6631
BROWNS JACK CLEANERS	615 MARTIN LUTHER K	E 0 - 1/8 (0.052 mi.)	LF2075 / 11	6659
THURMAN WAVERLY	120 5TH W	SSW 0 - 1/8 (0.053 mi.)	LG2089 / 11	6697
PAGE SAM F DCLO CLNR	109 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2090 / 11	6697
ABADIE & ROLAND TAI	107 5TH ST W	SSW 0 - 1/8 (0.053 mi.)	LG2097 / 11	6729
BAKER LEONARD	1700 LAVACA ST	ESE 0 - 1/8 (0.053 mi.)	MP2102 / 11	6730
HOME STEAM LNDY	211 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	JP2135 / 11	6767
CAMPBELL CLEANERS	1620 LAVACA	ESE 0 - 1/8 (0.053 mi.)	MP2143 / 11	6769
MILES DEAN DCLO CLNR	324 5TH ST E	SSW 0 - 1/8 (0.053 mi.)	LH2146 / 11	6770
SMITH LANDRY C CLDO	706 6TH E	ENE 0 - 1/8 (0.054 mi.)	KQ2156 / 11	6772
EKSTROM G A	303 CROCKETT	ESE 0 - 1/8 (0.054 mi.)	MT2166 / 14	6777
AUTOMATIC BENDIX	207 17TH E	ESE 0 - 1/8 (0.054 mi.)	JE2168 / 11	6780
BURTONS LAUNDRY & CL	615 W 19TH ST	E 0 - 1/8 (0.055 mi.)	LF2175 / 11	6819
LAWSHA LEE C DCLO CL	215 CONGRESS AVE E	SSW 0 - 1/8 (0.055 mi.)	KH2180 / 11	6820
SOUTH LAKESHORE BOUL	1717 LAKESHORE BLVD	ENE 0 - 1/8 (0.055 mi.)	KX2193 / 14	6841
GRAY CLNRS	209 17TH E	ESE 0 - 1/8 (0.056 mi.)	JE2195 / 11	6843
THRIFTY CLEANERS	1604 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	MZ2198 / 11	6847
DAVIS H R DCLO CLNR	1404 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	MR2200 / 11	6848
KALLGREN & HAMILTON	1402 LAVACA	ESE 0 - 1/8 (0.056 mi.)	MR2201 / 11	6848
BAKER LEONARD CLNR	1516 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	LT2203 / 11	6848
FRIENDLY PRESSING SH	1504 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	LT2206 / 11	6849
11 AUSTIN LAUNDRY	1514 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	LT2207 / 11	6850
1504 AUSTIN LAUNDRY	1510 LAVACA ST	ESE 0 - 1/8 (0.056 mi.)	LT2208 / 11	6850
QUINN & SMITH CLNRS	1506 LAVACA ST	ESE 0 - 1/8 (0.057 mi.)	LT2209 / 11	6850
SHIRLEYS HATTER	310 6TH W	ESE 0 - 1/8 (0.057 mi.)	LK2210 / 11	6851
SHIRLEY CLEANERS & H	310 6TH ST W	ESE 0 - 1/8 (0.057 mi.)	LK2211 / 11	6851
CONVENIENCE COIN LAU	101 38TH ST E	ESE 0 - 1/8 (0.058 mi.)	LV2246 / 8	6930
CONVENIENCE COIN LAU	101 38TH ST E	ESE 0 - 1/8 (0.058 mi.)	LV2247 / 8	6930
MC CLAIN HORACE C CD	1600 1ST	WNW 0 - 1/8 (0.058 mi.)	LW2252 / 14	6931
CINDERELLA CLNS	3500 EAST AVE	ENE 0 - 1/8 (0.058 mi.)	MQ2253 / 8	6932
203 5 SMITH KELLY DC	203 6TH W	WNW 0 - 1/8 (0.058 mi.)	LA2255 / 11	6932
SING FRANCES MRS LND	311 5TH ST W	ESE 0 - 1/8 (0.059 mi.)	KY2261 / 11	6935
M F ROUTE LAUNDRIES	103 38TH ST E	ESE 0 - 1/8 (0.059 mi.)	LV2264 / 8	6936
CONVENIENCE COIN LAU	103 38TH ST E	ESE 0 - 1/8 (0.059 mi.)	LV2265 / 8	6936
WALKERS LAUNDRY	1903 NEWTON ST	ESE 0 - 1/8 (0.060 mi.)	2266 / 14	6936
MEACHAM W W R	3104 KING ST	ESE 0 - 1/8 (0.060 mi.)	2268 / 8	6937
THURMAN WAVERLY	620 COLORADO ST	WNW 0 - 1/8 (0.060 mi.)	NG2270 / 11	6937
SOUTH FIRST CLEANERS	1905 S 1ST ST	WNW 0 - 1/8 (0.060 mi.)	NI2275 / 14	6950
AMERICAN CLEANERS	309 5TH ST W	ESE 0 - 1/8 (0.061 mi.)	KY2276 / 11	6951
DOWNS R L & CO	309 10TH W	ESE 0 - 1/8 (0.061 mi.)	NK2279 / 11	6951
WARDROBE CLNRS THE	207 CONGRESS AVE E	SSW 0 - 1/8 (0.061 mi.)	KH2280 / 11	6952
209 11 BLUE BONNET O	209 8TH W	WNW 0 - 1/8 (0.061 mi.)	KT2282 / 11	6956
GREGG J EARLE CLNR	1808 LAVACA ST	E 0 - 1/8 (0.061 mi.)	LI2285 / 11	6957
SMITH KELLY CLEANERS	209 6TH W	WNW 0 - 1/8 (0.062 mi.)	NG2301 / 11	6979
BROWN JACK CLEANERS	1109 W PARMER LN	W 0 - 1/8 (0.063 mi.)	KI2306 / 2	6986
WARREN CLNRS	3209 SPEEDWAY	ESE 0 - 1/8 (0.064 mi.)	NQ2321 / 8	7019
WARREN J A CLC CLNR	3207 SPEEDWAY	ESE 0 - 1/8 (0.064 mi.)	NQ2323 / 8	7019
BARRS BLUE BONNET	213 8TH W	WNW 0 - 1/8 (0.064 mi.)	KT2325 / 11	7034
PRO CLEAN CARPET CLN	6411 STARSTREAK DR	WNW 0 - 1/8 (0.066 mi.)	2348 / 17	7091
JONES JOHN H CLNR	212 17TH W	WNW 0 - 1/8 (0.066 mi.)	2352 / 11	7104
MC GINNIS & GRIMES	3810 E AVE	ENE 0 - 1/8 (0.066 mi.)	MQ2365 / 8	7116
CAPITOL LNDRY & CLN	301 8TH W	ESE 0 - 1/8 (0.066 mi.)	MI2367 / 11	7118
CARREON MARCIEL CLN	301 5TH ST W	ESE 0 - 1/8 (0.066 mi.)	KY2375 / 11	7124
TRIPLE L INC	1408 S FIRST ST	WNW 0 - 1/8 (0.068 mi.)	OB2400 / 14	7197
CONVENIENCE COIN LAU	817 12TH ST W	WNW 0 - 1/8 (0.068 mi.)	NW2414 / 11	7240
CONVENIENCE COIN LAU	101 E 38TH ST	ESE 0 - 1/8 (0.069 mi.)	LV2415 / 8	7240

EXECUTIVE SUMMARY

Site	Address	Direction / Distance	Map ID / Focus Map(s)	Page
CAPITOL LAUNDRY & DR	806 KOENIG LN W	WNW 0 - 1/8 (0.069 mi.)	OE2423 / 8	7245
DELWOOD CLNS	3925 EAST AVE	ENE 0 - 1/8 (0.070 mi.)	MQ2425 / 8	7245
KELLY SMITH CLEANERS	511 MARTIN LUTHER K	W 0 - 1/8 (0.070 mi.)	NS2426 / 11	7246
BATH CREST OF AUSTIN	111 RAMBLE LN	WNW 0 - 1/8 (0.070 mi.)	2428 / 17	7246
LONGHOM CLEANERS	510 MARTIN LUTHER K	E 0 - 1/8 (0.071 mi.)	LF2442 / 11	7292
ZIMMERMANH E E	503 6TH W	WNW 0 - 1/8 (0.072 mi.)	OI2449 / 11	7298
SWEET ONE HOUR DRY C	4100 EAST AVE	ENE 0 - 1/8 (0.072 mi.)	MQ2452 / 8	7299
MASTER VALET CLEANER	3101 SPEEDWAY ST	ESE 0 - 1/8 (0.073 mi.)	NM2460 / 8	7308
MITTAG WILLIAM O	3101 SPEEDWAY	ESE 0 - 1/8 (0.073 mi.)	NM2461 / 8	7308
AUSTIN LNDRY & DRY	608 24TH W	E 0 - 1/8 (0.073 mi.)	2464 / 11	7310
RAILYARD	6929 AIRPORT BLVD	ESE 0 - 1/8 (0.075 mi.)	OP2489 / 6	7415
KALLGREN & HAMILTON	1419 LAVACA ST	ESE 0 - 1/8 (0.075 mi.)	LT2493 / 11	7416
SAN JACINTO CLEANERS	408 SAN JACINTO BLV	NNE 0 - 1/8 (0.076 mi.)	NX2503 / 11	7425
AUSTINS HOME LNDRY	104 31ST E	ESE 0 - 1/8 (0.077 mi.)	NM2506 / 8	7426
HONG LEE MRS CHINESE	411 CONGRESS AVE	SSW 0 - 1/8 (0.077 mi.)	NL2508 / 11	7426
REX CLEANERS DCLO CL	200 MARY W	WNW 0 - 1/8 (0.077 mi.)	2512 / 14	7430
KELLY SMITH CLEANERS	509-511 W 19TH	W 0 - 1/8 (0.078 mi.)	NS2534 / 11	7513
KELLV SMITH CLEANERS	511 W 19TH ST	W 0 - 1/8 (0.082 mi.)	NS2563 / 11	7592
REIDS CLEANERS & LAU	3317 N LAMAR BLVD	WNW 0 - 1/8 (0.083 mi.)	OY2581 / 8	7689
JOASH ENTERPRISES IN	3419 N LAMAR BLVD	WNW 0 - 1/8 (0.083 mi.)	OY2582 / 8	7690
DISCOUNT CLEANERS	510 19TH ST W	E 0 - 1/8 (0.083 mi.)	PA2584 / 11	7690
CAPITOL LAUNDRY & DR	501 W 24TH ST	W 0 - 1/8 (0.084 mi.)	2595 / 11	7710
M F ROUTE LAUNDRIES	103 E 38TH ST	ESE 0 - 1/8 (0.084 mi.)	LV2600 / 8	7734
LEWIS PAUL C LAUNDRY	205 E 15TH ST	ESE 0 - 1/8 (0.085 mi.)	PD2610 / 11	7741
KOCH CHARLES J DYE	405 CONGRESS ST	SSW 0 - 1/8 (0.085 mi.)	NL2611 / 11	7741
SING LEE CHINESE LAU	403 CONGRESS AVE R	SSW 0 - 1/8 (0.088 mi.)	NL2652 / 11	7992
GAHAU CLEANERS	300 OLTORF ST E	NW 0 - 1/8 (0.090 mi.)	PL2674 / 14	8042
TWIN OAKS CLEANERS	300 E OLTORF	NW 0 - 1/8 (0.090 mi.)	PL2675 / 14	8043
ACME CLEANERS	504 1ST E	WNW 0 - 1/8 (0.090 mi.)	PB2681 / 11	8081
ONE HOUR MARTINIZING	704 W 29TH ST	ESE 0 - 1/8 (0.090 mi.)	2688 / 8	8093
GRAY P B DCLO CLNR	4413 AVENUE B	NE 0 - 1/8 (0.091 mi.)	2691 / 8	8094
LANG CLEANERS	208 13TH W	WNW 0 - 1/8 (0.091 mi.)	OW2693 / 11	8105
KASPER CHAS E CLNS	3810 LAMAR BLVD N	WNW 0 - 1/8 (0.091 mi.)	PH2694 / 8	8106
WESLEY GEORGE M TA	404 CONGRESS AVE	NNE 0 - 1/8 (0.092 mi.)	NT2706 / 11	8116
DOLLARS & SENSE DRY	3816 N LAMAR BLVD	WNW 0 - 1/8 (0.094 mi.)	PH2721 / 8	8225
ONE HOUR MARTINIZING	907 24TH ST W	W 0 - 1/8 (0.095 mi.)	PS2734 / 11	8239
CLEANING CO H	115 INDUSTRIAL BLVD	ESE 0 - 1/8 (0.096 mi.)	PC2737 / 18	8250
CONVENIENCE INC WASH	916 24TH ST W	W 0 - 1/8 (0.097 mi.)	PS2741 / 11	8266
GEST DUTCH CLEANERS	209 E 19TH	ESE 0 - 1/8 (0.098 mi.)	PT2746 / 11	8269
CHIEF CLEANERS	1001 W 34TH ST	WNW 0 - 1/8 (0.103 mi.)	2766 / 8	8317
AUSTIN LAUNDRY & DRY	911 W 24TH ST	W 0 - 1/8 (0.105 mi.)	PS2782 / 11	8471
SMS TRADING USA INC	9036 N LAMAR BLVD AP	WNW 0 - 1/8 (0.106 mi.)	2801 / 6	8523
A&B RUG & CARPET	654 CANION	ESE 0 - 1/8 (0.107 mi.)	QG2804 / 6	8524
AUSTIN LAUNDRY & DRY	913 W 24TH ST	W 0 - 1/8 (0.109 mi.)	PS2813 / 11	8568
CAPITOL LAUNDRY	801 BARTON SPRINGS	WNW 0 - 1/8 (0.112 mi.)	QN2823 / 11	8679
CAPITOL LAUNDRY & DR	801 BARTON SPRINGS	WNW 0 - 1/8 (0.112 mi.)	QN2824 / 11	8679
CONVENIENCE COIN LAU	915 W 24TH ST	W 0 - 1/8 (0.113 mi.)	PS2830 / 11	8684
BROWN BROS	1600 SAN JACINTO	ESE 0 - 1/8 (0.113 mi.)	2831 / 11	8684
WESLEY GEO DCLO CLNR	1818 SAN JACINTO	ESE 0 - 1/8 (0.116 mi.)	QQ2840 / 11	8706
COMET CLEANERS	9515 LAMAR BLVD N	ESE 0 - 1/8 (0.117 mi.)	QS2849 / 6	8712
SMITH J E R	305 13TH E	ESE 0 - 1/8 (0.122 mi.)	QU2866 / 11	8753

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
Reg / 8	NG CAMP MABRY		DOD	5487 1.039 WNW
1 / 2	LOWES OF NE AUSTIN	12805 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
A2 / 2	COXVILLE	12600 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	TP
A3 / 2	COXVILLE	12600 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
B4 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	FINDS	TP
B5 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
B6 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	ECHO	TP
7 / 2	7-ELEVEN INC	12434 N LAMAR BLVD	EDR Hist Auto	TP
C8 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	TX COMP HIST, TX CENTRAL REGISTRY	TP
C9 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	ECHO	TP
C10 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	FINDS	TP
11 / 4	NYOS CHARTER SCHOOL-	12301 N. LAMAR BLVD.	TX ASBESTOS	TP
12 / 4	WALNUT CREEK PARK MA	12138 N. LAMAR BLVD.	TX ASBESTOS	TP
D13 / 4	WALNUT PARK APARTMEN	12101 N LAMAR BLVD	FINDS, ECHO	TP
D14 / 4	WALNUT PARK APARTMEN	12101 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
D15 / 4	AMIGOS AUTO SALES	12100 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
16 / 3	2 VACANT DUPLEXES	11708 N. LAMAR	TX ASBESTOS	TP
E17 / 3	GAREY CONSTRUCTION C	11607 N LAMAR	RCRA NonGen / NLR	TP
E18 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX AST	TP
E19 / 3	GAREY CONSTRUCTION	11607 N LAMAR	FINDS, ECHO	TP
E20 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX UST, TX HIST UST	TP
E21 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
F22 / 3	TRAILER COATING	11422 N LAMAR	TX CENTRAL REGISTRY	TP
F23 / 3	OREILLY AUTO PARTS 5	11423 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
G24 / 3	KWIK STOP	11331 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
G25 / 3	KWIK STOP	11331 N LAMAR BLVD S	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
G26 / 3	KWIK STOP	11331 N LAMAR BLVD	TX ENF, TX COMP HIST	TP
G27 / 3	POTOSINA MEAT MARKET	11331 N LAMAR BLVD	FINDS	TP
H28 / 3	PROGRESSIVE MILL WOR	11118 N LAMAR BOULEV	FINDS	TP
H29 / 3	HERITAGE BODY & FRAM	11108 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP
H30 / 3	HERITAGE BODY & FRAM	11108 N LAMAR	TX CENTRAL REGISTRY	TP
I31 / 3	AIRGAS SOUTHWEST, IN	11111 N. LAMAR	TX TIER 2	TP
I32 / 3	AIRGAS USA, LLC - SO	11111 N. LAMAR	TX TIER 2	TP
J33 / 3	FOSTER HI-TECH FINIS	10716 N LAMAR BLVD S	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
J34 / 3	FOSTER HI TECH FINIS	10716 N LAMAR BLVD S	RCRA NonGen / NLR, FINDS, ECHO	TP
J35 / 3	AUSTIN PERFORMANCE S	10716 LAMAR BLVD N	EDR Hist Auto	TP
J36 / 3	UNITED MOLDING	10714 N LAMAR	TX CENTRAL REGISTRY	TP
J37 / 3	LANGHAM GROUP CULTUR	10712 N LAMAR BLVD S	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP
J38 / 3	LANGFORD CABINETS	10710 NORTH LAMAR	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
J39 / 3	NU-WAY UPHOLSTERY	10721 N LAMAR	EDR Hist Cleaner	TP
K40 / 3	SUPER CARE CLEANERS	10206 LAMAR BLVD N	EDR Hist Cleaner	TP
K41 / 3	SUPER CARE CLEANERS	10205 N LAMAR	EDR Hist Cleaner	TP
L42 / 3	NAPA AUTO PARTS 22	10101 N LAMAR BLVD	FINDS	TP
L43 / 3	AUSTEX AUTO PARTS	10101 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
M44 / 3	AUTOZONE	9905 N LAMAR BLVD	TX ASBESTOS	TP
M45 / 3	AUTOZONE 1396	9905 N LAMAR BLVD	FINDS	TP
M46 / 3	AUTOZONE 1396	9905 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
47 / 3	BRIDENT DENTAL	9813 N. LAMAR BLVD.	RCRA-VSQG, FINDS, ECHO	TP
N48 / 6	FAMILY DOLLAR	9719 N LAMAR BLVD	TX ASBESTOS	TP
O49 / 6	LAUNDRY BASKET NO 1	9644 LAMAR BLVD N	EDR Hist Cleaner	TP
O50 / 6	DRY CLEAN CITY 125	9626 N LAMAR BLVD	EDR Hist Cleaner	TP
O51 / 6	DRY CLEAN CITY	9626 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	TP
O52 / 6	DRY CLEAN CITY	9626 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
O53 / 6	AUTO ZONE 1396	9620 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
O54 / 6	AUTO ZONE 1396	9620 N LAMAR BLVD	FINDS	TP
O55 / 6	ACME CLEANERS	9606 LAMAR BLVD N	EDR Hist Cleaner	TP
56 / 6	DOLLAR TREE	9514 N LAMAR BLVD	TX ASBESTOS	TP
P57 / 6	HEB 183	9411B N LAMAR BLVD	TX CENTRAL REGISTRY	TP
P58 / 6	ACEMART RESTAURANT S	9411 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	TP
P59 / 6	HEB 183	9411B N LAMAR BLVD	FINDS	TP
P60 / 6	HEB 183	9411B N LAMAR BLVD	TX UST, TX Financial Assurance	TP
Q61 / 6	A ACME CLEANERS & LA	9302 LAMAR BLVD N	EDR Hist Cleaner	TP
R62 / 6	CAPITAL FINA OIL SER	8909 LAMAR BLVD N	EDR Hist Auto	TP
R63 / 6		8833 NORTH LAMAR	ERNS	TP
R64 / 6	TARGA PORSCHE	8833 LAMAR BLVD N	EDR Hist Auto	TP
R65 / 6	TARGA PORSCHE	8833 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
S66 / 6	LACE	8829 N LAMAR BLVD	TX Ind. Haz Waste	TP
S67 / 6	LACE	8829 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
S68 / 6	AUSTIN DATSUN REPAIR	8825 LAMAR BLVD N	EDR Hist Auto	TP
S69 / 6	LACE ENGINEERING	8825 N LAMAR	TX CENTRAL REGISTRY	TP
S70 / 6	TRIPLE JS TIRE CENTE	8821 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
T71 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	TX CENTRAL REGISTRY	TP
T72 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	TX Ind. Haz Waste	TP
T73 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	RCRA NonGen / NLR	TP
T74 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	FINDS, ECHO	TP
T75 / 6	CULP SERV STA	8703 LAMAR BLVD	EDR Hist Auto	TP
U76 / 6	DIP STICK	8601 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
U77 / 6	DIP STICK	8601 LAMAR BLVD N	EDR Hist Auto	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
V78 / 6	FINELINE SPORTSWEAR	8451 N LAMAR BLVD	TX Ind. Haz Waste	TP
V79 / 6	FINELINE SPORTSWEAR	8451 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
V80 / 6	UNIVAR USA - PP&S AU	8402 N. LAMAR, SUITE	TX TIER 2	TP
V81 / 6	UNIVAR USA ES -AUSTI	8402 N LAMAR	FINDS	TP
W82 / 6	THIRD COAST AUTO GRO	8316 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
W83 / 6	RYDER TRUCK, IH-35 M	RYDER TRUCK, IH-35 M	TX SPILLS	TP
X84 / 6	RELIABLE AUTOM	8226 LAMAR BLVD N	EDR Hist Auto	TP
X85 / 6	SCHEIDERS SIN	8224 LAMAR BLVD N	EDR Hist Auto	TP
Y86 / 6	AUSTIN BRAKE & CLUTC	8151 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP
Y87 / 6	AUSTIN BRAKE & CLUTC	8151 N LAMAR BLVD	TX UST	TP
Z88 / 6	ACME DRY CLEANERS &	7541 LAMAR BLVD N	EDR Hist Cleaner	TP
Z89 / 6	D & L MOTORCYCLES	7535 N LAMAR BLVD	TX ENF, TX COMP HIST	TP
Z90 / 6	D & L MOTORCYCLES	7535 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
Z91 / 6	D & L MOTORCYCLE INC	7535 LAMAR BLVD N	EDR Hist Auto	TP
AA92 / 6	NORTH LAMAR AUTO BOD	7313 NORTH LAMAR BLV	TX ENF, TX COMP HIST	TP
AA93 / 6	A & A USED TIRES	7313 N LAMAR BLVD	TX ENF, TX COMP HIST	TP
AA94 / 6	NORTH LAMAR AUTO BOD	7313 NORTH LAMAR BLV	TX CENTRAL REGISTRY	TP
AA95 / 6	K W AUTO REPAIR	7313 LAMAR BLVD N	EDR Hist Auto	TP
AA96 / 6	JC TIRE & WHEELS	7313 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AA97 / 6	NORTHSIDE GARAGE AUT	7277 LAMAR BLVD N	EDR Hist Auto	TP
AB98 / 6	A 1 TRANSMISSION	7227 LAMAR BLVD N	EDR Hist Auto	TP
AB99 / 6	PATS LAWN MOWER SVC	7201 N LAMAR BLVD	TX ENF, TX Ind. Haz Waste, TX CENTRAL RE...	TP
AB100 / 6	PATS LAWN MOWER SVC	7201 N LAMAR BLVD	TX COMP HIST	TP
AB101 / 6	7121 N LAMAR BLVD	7121 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AB102 / 6	AUTOMETRICS INC AUTO	7121 LAMAR BLVD N	EDR Hist Auto	TP
AB103 / 6	7121 N LAMAR BLVD	7121 N LAMAR BLVD	TX VCP, TX HIST UST, TX GCC	TP
AB104 / 6	OUTPLAN	7121 NORTH LAMAR	TX ASBESTOS	TP
AB105 / 6	JIMS GULF STATION GA	7107 LAMAR BLVD N	EDR Hist Auto	TP
AB106 / 6	AUSTIN RESEARCH LABO		PFAS ECHO	TP
AC107 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC108 / 6	AUSTIN LABORATORIES	7114 N LAMAR BLVD	TSCA, TX AIRS, TX Ind. Haz Waste, TX IHW...	TP
AC109 / 6	HUNTSMAN PETRO - AUS	7114 NORTH LAMAR BOU	TSCA	TP
AC110 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC111 / 6	TEXACO-AUSTIN LABORA	7114 N LAMAR BLVD	TSCA	TP
AC112 / 6	TEXACO CHEMICAL	7114 N. LAMAR	TX SPILLS 90	TP
AC113 / 6	HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	TSCA	TP
AC114 / 6	HUNTSMAN CORP	7114 N. LAMAR	TX SPILLS 90	TP
AC115 / 6	7114 N. LAMAR, AUSTI	7114 N. LAMAR, AUSTI	TX SPILLS	TP
AC116 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	TX GCC	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AC117 / 6	AUSTIN LABORATORIES	7114 N LAMAR BLVD	TX UST, TX HIST UST	TP
AC118 / 6		7114 N. LAMAR BL.	ERNS	TP
AC119 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC120 / 6	HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	RMP	TP
AC121 / 6	7114 NORTH LAMAR (SO	7114 NORTH LAMAR (SO	TX SPILLS	TP
AC122 / 6	TEXACO CHEMICAL COMP	7114 N. LAMAR BOULEV	FTTS	TP
AC123 / 6	7114 N.LAMAR, AUSTIN	7114 N.LAMAR, AUSTIN	TX SPILLS	TP
AC124 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC125 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	FINDS	TP
AC126 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC127 / 6	DOWTHERM VAPOR GENER	7114 N LAMAR BLVD	TX AIRS	TP
AC128 / 6		7114 N LAMAR ST	ERNS	TP
AC129 / 6	STEAM GENERATOR - JC	7114 N LAMAR BLVD	TX AIRS	TP
AC130 / 6		7114 N LAMAR BLVD	ERNS	TP
AC131 / 6	TEXACO CHEMICAL CO	7114 N.LAMAR	TX SPILLS 90	TP
AC132 / 6	TEXACO CHEMICAL	7114 NORTH LAMAR (SO	TX SPILLS 90	TP
AC133 / 6		7114 N LAMAR BLVD	ERNS	TP
AC134 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	SEMS-ARCHIVE, CORRACTS, RCRA-TSDF, RCRA I	TP
AC135 / 6	HUNTSMAN PETROCHEMIC	7114 N. LAMAR BLVD.	ICIS, FINDS, ECHO	TP
AC136 / 6	CRESTVIEW STATION	7114 N LAMAR BLVD	TX VCP, TX UIC, TX COMP HIST	TP
AC137 / 6	TEXACO CHEMICAL COMP	7114 N. LAMAR BOULEV	HIST FTTS	TP
AC138 / 6	7114 NORTH LAMAR, AU	7114 NORTH LAMAR, AU	TX SPILLS	TP
AC139 / 6	7114 N. LAMAR, AUSTI	7114 N. LAMAR, AUSTI	TX SPILLS	TP
AC140 / 6	7114 NORTH LAMAR BLV	7114 NORTH LAMAR BLV	TX SPILLS	TP
AC141 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC142 / 6		7114 N LAMAR BLVD	ERNS	TP
AC143 / 6	BLACKBURN TEXACO SER	7006 LAMAR BLVD N	EDR Hist Auto	TP
AC144 / 6	HUNTSMAN CORP. CHEMI	HUNTSMAN CORP. CHEMI	TX SPILLS	TP
AC145 / 6	TEXACO CHEMICAL PLAN	TEXACO CHEMICAL PLAN	TX SPILLS	TP
AC146 / 6	TEXACO CHEMICAL CO P	TEXACO CHEMICAL CO P	TX SPILLS	TP
AC147 / 6		7114 N. LAMAR	ERNS	TP
148 / 6	HEART-O-TEXAS FILM L	6929 N LAMAR BLVD	TX HIST UST	TP
AD149 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX LPST, TX UST	TP
AD150 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AD151 / 6	AUSTIN STANDARD TRAN	6916 LAMAR BLVD N	EDR Hist Auto	TP
AD152 / 6	JAMES EICHELBERGER J	6916 N LAMAR BLVD	TX HIST UST	TP
AD153 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX HIST UST	TP
AE154 / 6	SOUTHCREST PARK	6811 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AE155 / 6	AUSTIN KAWASAKI MOTO	6801 LAMAR BLVD N	EDR Hist Auto	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AE156 / 6	COLORPRESS INC	6801 N LAMAR BLVD	TX HIST UST	TP
AF157 / 6	K O MACHINE	6721 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AF158 / 6	K 0 MACHINE CO	6721 LAMAR BLVD N	EDR Hist Auto	TP
AF159 / 6	K O MACHINE INC	6721 N LAMAR BLVD ST	RCRA NonGen / NLR, FINDS, ECHO	TP
AF160 / 6	KO MACHINE SHOP	6721 N LAMAR	RCRA-SQG	TP
AF161 / 6	QUICKY	6719 N LAMAR BLVD	TX ASBESTOS	TP
AF162 / 6	NORTH LAMAR AND SHIR	6709 N LAMAR	TX ASBESTOS	TP
AF163 / 6	6705 N LAMAR BLVD, A	6705 N LAMAR BLVD,	US BROWNFIELDS, FINDS	TP
AF164 / 6	A-AABAT STORAGE	6705 N LAMAR BLVD	TX LPST, TX TANKS, TX GCC, TX RDR	TP
AF165 / 6	A-AABAT SEF STORAGE	6705 N LAMAR BLVD	TX HIST UST	TP
AF166 / 6	GLENN SERV STA	6705 LAMAR BLVD	EDR Hist Auto	TP
AF167 / 6	EARNEST E PANNELL JR	6705 N LAMAR BLVD	TX HIST UST	TP
AF168 / 6	A-AABAT STORAGE	6705 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AG169 / 6	JEFFS CUSTOM BODY SH	6616 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AG170 / 6	JEFFS CUSTOM BODY SH	6616 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	TP
AG171 / 6	VEHICLE REPAIR & REF	6614 N. LAMAR	TX CENTRAL REGISTRY	TP
AG172 / 6	RIVER CITY BULTACO M	6614 LAMAR BLVD N	EDR Hist Auto	TP
AG173 / 6	SOUTHERN UNION GAS C	6615 NORTH LAMAR	DOT OPS	TP
AH174 / 6	TASTE OF INK	6541 N LAMAR BLVD #B	TX ASBESTOS	TP
AH175 / 6	RAYS GARAGE	6517 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AH176 / 6	RAYS GARAGE	6517 LAMAR BLVD N	EDR Hist Auto	TP
AH177 / 6	RAYS GARAGE	6517 N LAMAR BLVD	TX UST, TX HIST UST	TP
AH178 / 6	WOODS HONDA	6509 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	TP
AH179 / 6	WOODS HOND	6509 LAMAR BLVD N	EDR Hist Auto	TP
AI180 / 6	JIFFV BRAKE SERVICE	6322 LAMAR BLVD N	EDR Hist Auto	TP
AJ181 / 9	EARLS LAWN GARDEN EQ	6216 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AJ182 / 9	EARLS AIR COOLED ENG	6218 LAMAR BLVD N	EDR Hist Auto	TP
AJ183 / 9	VIOLET CROWN CLNRS	6218 LAMAR BLVD	EDR Hist Cleaner	TP
AJ184 / 9	LYLES CHEMICAL & SUP	6208 N LAMAR BLVD	TX HIST UST	TP
AJ185 / 9	TJS CYCLE SALES & SE	6208 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AJ186 / 9	RICKS SALES CO.	6205 N LAMAR BLVD	TX HIST UST	TP
AJ187 / 9	SWANNS GARAGE & RADI	6203 N LAMAR BLVD	TX UST, TX HIST UST	TP
AJ188 / 9	NORTH LAMAR AUTOMOTI	6203 LAMAR BLVD N	EDR Hist Auto	TP
AJ189 / 9	SWANNS GARAGE RADIAT	6203 N LAMAR BLVD	TX LPST, TX Ind. Haz Waste	TP
AJ190 / 9	SWANNS GARAGE & RADI	6203 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AK191 / 8	DEPARTMENT OF PUBLIC	5808 NORTH LAMAR BLV	TX ASBESTOS	TP
AK192 / 8	NORTH AUSTIN RESERVO	5802 N LAMAR BOULEVA	FINDS, ECHO	TP
AK193 / 8	NORTH AUSTIN RESERVO	5802 N LAMAR BOULEVA	TX COMP HIST, TX CENTRAL REGISTRY	TP
AK194 / 8	NORTH AUSTIN RESERVO	5802 N. LAMAR	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AK195 / 8	DEPARTMENT OF PUBLIC	DEPARTMENT OF PUBLIC	TX SPILLS	TP
AK196 / 8	TEXAS DEPARTMENT OF	5805 NORTH LAMAR	PRP	TP
AK197 / 8	TEXAS DEPARTMENT OF	5805 NORTH LAMAR BLV	PRP	TP
AK198 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR, AUSTIN	TX SPILLS, TX ASBESTOS, TX ENF	TP
AK199 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO	TP
AK200 / 8	TEXAS DEPARTMENT OF	5805 N. LAMAR BLVD.	TX TIER 2	TP
AK201 / 8	DPS HEADQUARTERS - D	5805 N LAMAR BLVD	ECHO	TP
AK202 / 8	DPS HEADQUARTERS - D	5805 N LAMAR BLVD	FINDS	TP
AK203 / 8	TEXAS DEPARTMENT OF	5805 N LAMAR BLVD	TX ASBESTOS, TX Ind. Haz Waste	TP
AK204 / 8	DEPARTMENT OF PUBLIC	5805 NORTH LAMAR	TX ASBESTOS	TP
AK205 / 8	TEXAS DEPARTMENT OF	5805 N. LAMAR	TX ASBESTOS	TP
AK206 / 8	DPS HEADQUARTERS	5805 N LAMAR BLDG R	TX ASBESTOS	TP
AK207 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR BLVD	TX AIRS, TX ASBESTOS, TX IHW CORR ACTION...	TP
AK208 / 8	TX. DEPT. OF PUBLIC	5805 N. LAMAR BLVD.	TX LPST, TX ASBESTOS	TP
AK209 / 8	TEXAS DEPARTMENT OF	5805 LAMAR BLVD	TX ASBESTOS	TP
AK210 / 8	TEXASDEPARTMENT OF P	5805 NORTH LAMAR	TX ASBESTOS	TP
AK211 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR BLVD	TX UST	TP
AK212 / 8	DEPARTMENT OF PUBLIC	5801 NORTH LAMAR	TX ASBESTOS	TP
AK213 / 8	DEPARTMENT OF PUBLIC	5801 N. LAMAR	TX ASBESTOS	TP
AL214 / 8	CITY OF AUSTIN EMS S	5710 NORTH LAMAR BLV	TX ASBESTOS	TP
AL215 / 8	NORTH SERVICE CENTER	5708 NORTH LAMAR BLV	TX ASBESTOS	TP
AM216 / 8	TORN MACHINERY COMP.	5545 N LAMAR BLVD	TX HIST UST	TP
AN217 / 8	ATLAS AUTO AIR	5408 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AN218 / 8	CAMDEN LAMAR HEIGHTS	5400 N. LAMAR BLVD.	TX ASBESTOS	TP
AN219 / 8	CENTRAL TEXAS REGION	5400 N LAMAR BLVD	TX UST	TP
AN220 / 8	CENTRAL TEXAS REGION	5400 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AO221 / 8	FORMER BUCKS FEED ST	5327 N. LAMAR	TX ASBESTOS	TP
AO222 / 8	J&J GARAGE	5312 LAMAR BLVD	EDR Hist Auto	TP
AO223 / 8	FASHION FLOOR INC	5304 LAMAR BLVD N	EDR Hist Cleaner	TP
AP224 / 8	VACANT BLDG. (FORMER	5242 NORTH LAMAR BLV	TX ASBESTOS	TP
225 / 8	ROY R. WARNER	5201 N LAMAR BLVD	TX HIST UST	TP
AQ226 / 8	CECILS (SINCLAIR)	5100 N LAMAR BLVD	TX HIST UST	TP
AQ227 / 8	MAXIM ENGINEERS INC	106011 N LAMAR BLVD	FINDS, ECHO	TP
AR228 / 8	STATE BUILDING	4900 NORTH LAMAR STR	TX ASBESTOS	TP
AS229 / 8	MESA CLEANERS	4700 W GUADALUPE ST	FINDS	TP
AS230 / 8	MESA CLEANERS	4700 W GUADALUPE ST	TX DRYCLEANERS	TP
AS231 / 8	MESA CLEANERS	4700 W GUADALUPE ST	TX CENTRAL REGISTRY	TP
232 / 8	PROVISION DINING HOU	4600 W GUADALUPE STR	TX ASBESTOS	TP
233 / 8	RAMPART CONSTRUCTION	4510 W GUADALUPE ST	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AT234 / 8	DODD-HURT TEXACO	4300 GUADALUPE	EDR Hist Auto	TP
235 / 8	AUSTIN STATE HOSPITA	4101GUADALUPE STREET	TX TIER 2	TP
AT236 / 8	BARTLETTS SERVICE ST	4231 GUADALUPE	EDR Hist Auto	TP
AT237 / 8	PERFORMANCE SHOP NOR	4225 GUADALUPE ST	EDR Hist Auto	TP
AT238 / 8	CLEAN & LEAN LAUNDRY	4225 GUADALUPE ST	EDR Hist Cleaner	TP
AU239 / 8	HYDE PARK GPVAGE	4215 GUADALUPE ST	EDR Hist Auto	TP
AU240 / 8	PERFECTION TATTOO	4205 GUADALUPE ST	TX ASBESTOS	TP
AU241 / 8	JAMES HERSHEL R	4203 GUADALUPE ST	EDR Hist Auto	TP
AV242 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	FINDS, ECHO	TP
AV243 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	FINDS	TP
AV244 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE	TX LPST, TX TIER 2	TP
AV245 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	RCRA-VSQG, TX AST, TX SPILLS, TX ASBESTO...	TP
AV246 / 8		4110 GUADALUPE	ERNS	TP
AV247 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	TX RGA LF	TP
AV248 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE STREE	TX ASBESTOS, TX TIER 2	TP
AV249 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	TX UST, TX HIST UST	TP
AV250 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	TX SWF/LF	TP
AU251 / 8	NUNNELEE H W	4201 GUADALUPE ST	EDR Hist Auto	TP
AU252 / 8	GUADALUPE HUBSITE	4201 GUADALUPE ST	FINDS	TP
AU253 / 8	TX-13 TIME WARNER CA	4201 GUADALUPE ST	TX TIER 2	TP
AU254 / 8	TX-13 - TIME WARNER	4201 GUADALUPE ST.	TX TIER 2	TP
AW255 / 8	AUSTIN SPORTCYCLES M	4117 GUADALUPE ST	EDR Hist Auto	TP
AW256 / 8	STATE CLEANERS	4115 GUADALUPE	EDR Hist Cleaner	TP
AW257 / 8	PARAMOUNT CLEANERS	4109 GUADALUPE ST	EDR Hist Cleaner	TP
AW258 / 8	MILES EDGAR P BARB	4103 GUADALUPE ST	EDR Hist Cleaner	TP
AW259 / 8	AUSTIN MATTRESS	4101 GUADALUPE	EDR Hist Cleaner	TP
AX260 / 8	WALLIS CLEANERS	4023 GUADALUPE ST	EDR Hist Cleaner	TP
AX261 / 8	HYDE PARK SHOE SHOP	4011 GUADALUPE ST	EDR Hist Cleaner	TP
262 / 8	MIDAS MUFFLER SHOP	4001 GUADALUPE ST	EDR Hist Auto	TP
AY263 / 8	SIGMOR CORPOR	3915 GUADALUPE ST	EDR Hist Auto	TP
AY264 / 8	BAKER LEONARD CLNR	3911 GUADALUPE ST	EDR Hist Cleaner	TP
AY265 / 8	DIAMOND SHAMROCK 80	3909 GUADALUPE ST	FINDS	TP
AY266 / 8	CIRCLE K STORE 27400	3909 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
AY267 / 8	BALCAR HUMBLE SERV	3909 GUADALUPE	EDR Hist Auto	TP
AY268 / 8	DIAMOND SHAMROCK 80	3909 GUADALUPE ST	TX RDR	TP
AY269 / 8	CORNER STORE 0080	3909 GUADALUPE ST	TX CENTRAL REGISTRY	TP
AY270 / 8	NUNNELEE HARRY R	3907 GUADALUPE ST	EDR Hist Auto	TP
AY271 / 8	AUSTIN MATTRESS & CA	3907 GUADALUPE ST	EDR Hist Cleaner	TP
272 / 8	FORMER NATURAL GROCE	3901 GUADALUPE STREE	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
273 / 8	UNIVERSITY CAR WASH	3825 GUADALUPE ST	EDR Hist Auto	TP
AZ274 / 8	C & H REPAIR SERVICE	3907 AVENUE C	EDR Hist Auto	TP
BA275 / 8	AVENEL AT HYDE PARK	3815 GUADALUPE ST. #	TX ASBESTOS	TP
AZ276 / 8	C&H REPR SERV	3907 AVENUE C	EDR Hist Auto	TP
BA277 / 8	HYDE PARK GULF	3801 GUADALUPE ST	EDR Hist Auto	TP
BB278 / 8	JAMES E P FILL STA	3710 GUADALUPE ST	EDR Hist Auto	TP
BB279 / 8	CIRCLE K CORPORATION	3713 GUADALUPE ST	EDR Hist Auto	TP
BB280 / 8	CIRCLE K 3208	3713 GUADALUPE ST	FINDS	TP
BB281 / 8	GOOD LUCK FOOD MART	3713 GUADALUPE ST	TX ASBESTOS	TP
BB282 / 8	CIRCLE K 3208	3713 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BB283 / 8	CIRCLE K 3208	3713 GUADALUPE ST	TX UST, TX HIST UST	TP
BB284 / 8	MAC'S PIZZA	3701 GUADALUPE	TX ASBESTOS	TP
BB285 / 8	VACANT LEASE SPACE	3701 GUADALUPE	TX ASBESTOS	TP
BB286 / 8	WILDSIDE SMOKE SHOP	3701 GUADALUPE ST	TX ASBESTOS	TP
287 / 8	AUSTIN DIAGNOSTIC CL	801 34TH ST W	EDR Hist Cleaner	TP
BC288 / 8	INTEGRATED BUILDERS	711 N 32ND ST	FINDS	TP
BC289 / 8	BUCKINGHAM INVESTMEN	711 W 32ND ST	TX CENTRAL REGISTRY	TP
BD290 / 8	KWIK WASH COIN LAUND	3105 GUADALUPE ST	EDR Hist Cleaner	TP
BE291 / 8	CAPITAL CITY PARTNER	3004- 3010 GUADALUPE	TX GCC, TX IOP	TP
BE292 / 8	TEXACO STATION	3016 GUADALUPE ST	RCRA-VSQG, FINDS, ECHO	TP
BE293 / 8	SAGE-OCONNER ASSOCIA	3016 GUADALUPE ST	FINDS	TP
BE294 / 8	ASHFORDS GARAGE	3016 GUADALUPE ST	EDR Hist Auto	TP
BE295 / 8	UNIVERSITY TEXACO	3016 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	TP
BE296 / 8	UNIVERSITY TEXACO	3016 GUADALUPE	TX RDR	TP
BE297 / 8	UNIVERSITY TEXACO	3016 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BE298 / 8	OCONNELL & WORLEY	3012 GUADALUPE ST	EDR Hist Cleaner	TP
BE299 / 8	NORTH AUSTIN GARAGE	3008 GUADALUPE ST	EDR Hist Auto	TP
BE300 / 8	RETAIL CENTER 3004-3	3004-3010 GUADALUPE	FINDS	TP
BE301 / 8	RETAIL CENTER 3004-3	3004-3010 GUADALUPE	TX CENTRAL REGISTRY	TP
BF302 / 8	MARY E KOSH	3009 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BF303 / 8	MARY E KOSH	3009 GUADALUPE ST	TX UST	TP
BF304 / 8	HOBBY TRACT	3000 GUADALUPE ST	FINDS	TP
BF305 / 8	MC GIRK J ARTH AUTO	3000 GUADALUPE	EDR Hist Auto	TP
BF306 / 8	HOBBY TRACT	3000 GUADALUPE ST	TX IOP, TX CENTRAL REGISTRY	TP
BF307 / 8	VACANT LOT	3005 GUADALUPE ST	TX HIST UST	TP
BF308 / 8	JESSE J. SMITH	602 W 30TH ST	TX HIST UST	TP
BG309 / 8	DICKEN 6 BROS CLNRS	2930 GUADALUPE	EDR Hist Cleaner	TP
BG310 / 8	FOUNTAIN TERRACE UNI	601 W. 30TH STREET	TX ASBESTOS	TP
BG311 / 8	DICKENS CLEANERS & S	2918 GUADALUPE ST	EDR Hist Cleaner	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
BH312 / 8	RICKS CLEANERS INC	2908 GUADALUPE ST	EDR Hist Cleaner	TP
BH313 / 8	COMMUNITY CLNRS	2904 GUADALUPE ST	EDR Hist Cleaner	TP
314 / 8	FIRST ENGLISH LUTHER	3001 WHITIS AVENUE	TX ASBESTOS	TP
BH315 / 8	MALLETT JACK SERVICE	2901 GUADALUPE	EDR Hist Auto	TP
BI316 / 8	PARD-ANNEX BUILDING	2818 SAN GABRIEL	TX ASBESTOS	TP
BI317 / 8	ANNEX BUILDING	2818 SAN GABRIEL ST.	TX ASBESTOS	TP
BJ318 / 8	MONTGOMERYS HUMBLE	2825 GUADALUPE ST	EDR Hist Auto	TP
BJ319 / 8	A C LINEN SUPPLY	2822 GUADALUPE	EDR Hist Cleaner	TP
BJ320 / 11	CHEVRON SELF SERVICE	2819 GUADALUPE ST	EDR Hist Auto	TP
BJ321 / 11	CHEVRON FAC 107149	2819 GUADALUPE ST	FINDS	TP
BJ322 / 11	STAR STOP 74	2819 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BJ323 / 11	STAR STOP 74	2819 GUADALUPE ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
BJ324 / 11	TETCO 78	2819 GUADALUPE ST	TX RDR	TP
BK325 / 11	CHEVRON USA INC	2817 GUADALUPE ST	RCRA NonGen / NLR, FINDS, ECHO	TP
BK326 / 11	LICARI SAM GULF	2817 GUADALUPE ST	EDR Hist Auto	TP
BK327 / 11	CHEVRON FAC 107149	2817 GUADALUPE ST	TX Ind. Haz Waste	TP
BK328 / 11	CHEVRON STATION 1071	2817 GUADALUPE ST	TX LPST, TX ASBESTOS	TP
BK329 / 11	CHEVRON 107149	2817 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BL330 / 11	AMERICAN CONSTRUCTOR	101 E 30TH ST	FINDS	TP
BL331 / 11	AMERICAN CONSTRUCTOR	101 E 30TH ST	TX CENTRAL REGISTRY	TP
BK332 / 11	MAGNOLIA PET CO STA	2810 GUADALUPE ST	EDR Hist Auto	TP
BM333 / 11	LAUNDERETTE WASHATER	2706 GUADALUPE	EDR Hist Cleaner	TP
BM334 / 11	PARAMOUNT CLNRS	2704 GUADALUPE ST	EDR Hist Cleaner	TP
BN335 / 11	MAC'S PIZZA	2701 GUADALUPE ST.	TX ASBESTOS	TP
BN336 / 11	DUNBAR LOUIE FILL ST	2701 GUADALUPE ST	EDR Hist Auto	TP
337 / 11	FORMER FRAT HOUSE BU	2614 RIO GRANDE ST	TX ASBESTOS	TP
BO338 / 11	FORTY ACRES CLNS	2605 GUADALUPE ST	EDR Hist Cleaner	TP
BP339 / 11	FRATERNITY HOUSE	800 W. 26TH ST.	TX ASBESTOS	TP
BP340 / 11	FRATERNITY HOUSE	800-804 WEST 26TH	TX ASBESTOS	TP
BP341 / 11	LYDA SWINERTON BUILD	711 W 26TH ST	TX CENTRAL REGISTRY	TP
BO342 / 11	LONGHORN GULF SERV	2601 GUADALUPE ST	EDR Hist Auto	TP
BQ343 / 11	SJL AD SPECIALTIES	2512 RIO GRANDE ST	TX Ind. Haz Waste	TP
BQ344 / 11	SJL AD SPECIALTIES	2512 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
BR345 / 11	BRIDGEWAY	2616 WICHITA	TX ASBESTOS	TP
BS346 / 11	LEES SUPER SERVICE F	2533 GUADALUPE	EDR Hist Auto	TP
BS347 / 11	UNIVERSITY CLEANERS	2520 GUADALUPE ST	EDR Hist Cleaner	TP
BS348 / 11	AUSTIN DRY CLEANERS	2516 GUADALUPE ST	EDR Hist Cleaner	TP
BT349 / 11	ALPHA EPSLION PHI SO	2500 RIO GRANDE ST.	TX ASBESTOS	TP
BT350 / 11	ALPHA EPSILON PHI SO	2500 RIO GRANDE ST.	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
BT351 / 11	ALPHA EPSILON PHI HO	2500 RIO GRANDE	TX ASBESTOS	TP
BR352 / 11	STUDENT SERVICES BUI	100 W DEAN KEETON ST	TX ASBESTOS	TP
BU353 / 11	COWBOYS TAILOR	2505 GUADALUPE ST	EDR Hist Cleaner	TP
BU354 / 11	COUCH CLEANERS	2501 GUADALUPE	EDR Hist Cleaner	TP
BU355 / 11	2412 UNIVERSITY SERV	2436 GUADALUPE ST	EDR Hist Auto	TP
BU356 / 11	WALTER WEBB HALL	405 W. 25TH STREET	TX ASBESTOS	TP
BV357 / 11	UNIVERSITY UNITED ME	2409 GUADALUPE ST.	TX ASBESTOS	TP
BW358 / 11	FOODIES 2	2400 RIO GRANDE ST	TX SPILLS, TX ENF	TP
BW359 / 11	WAG-A-BAG 24	2400 RIO GRANDE ST	FINDS	TP
BW360 / 11	FOODIES 2	2400 RIO GRANDE ST	TX COMP HIST	TP
BW361 / 11	FOODIES NO. 2	2400 RIO GRANDE STRE	TX RDR	TP
BW362 / 11	FOODIES 2	2400 RIO GRANDE ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
BW363 / 11	FOODIES 2	2400 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
BW364 / 11	SCHIEFFERS BEN	701 24TH W	EDR Hist Auto	TP
BX365 / 11	B LONGHORN CLNS	705 24TH W	EDR Hist Cleaner	TP
BW366 / 11	LOONEY L P FILLING	2323 RIO GRANDE	EDR Hist Auto	TP
BY367 / 11	CORNERSTONE PLACE AP	2308 RIO GRANDE ST	FINDS	TP
BY368 / 11	GEDR AT UNION ON 24T	2308 RIO GRANDE ST	TX TANKS, TX VCP, TX ASBESTOS	TP
BY369 / 11	CORNERSTONE PLACE AP	2308 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
370 / 11	PARKING GARAGE	715 WEST 23RD STREET	TX ASBESTOS	TP
BZ371 / 11	WASH N FOLD INDRY	2202 RIO GRANDE ST	EDR Hist Cleaner	TP
CA372 / 11	AUSTIN MAIN POST OFF	2201 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CA373 / 11	AUSTIN MAIN POST OFF	2201 GUADALUPE ST	TX UST	TP
374 / 11	HODGES CLEANERS	107 21ST E	EDR Hist Cleaner	TP
CB375 / 11	THE SHOPS AT DOBIE C	2021 GUADALUPE SUITE	TX ASBESTOS	TP
CB376 / 11	TARGET STORE T3250	2021 2021 GUADALUPE	RCRA-SQG	TP
CB377 / 11	TARGET STORE T3250	2021 2021 GUADALUPE	FINDS, ECHO	TP
CB378 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST #	TX ASBESTOS, TX Ind. Haz Waste	TP
CB379 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST NO	RCRA NonGen / NLR, FINDS, ECHO	TP
CB380 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST #	TX CENTRAL REGISTRY	TP
CB381 / 11	TARGET STORE T3250	2021 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CC382 / 11	CITYVILLE AT PEARL	706 W MLK JR BLVD	FINDS	TP
CC383 / 11	CITYVILLE AT PEARL	706 W MLK JR BLVD	TX CENTRAL REGISTRY	TP
CB384 / 11	CUTLERS MOTOR CO	2015 GUADALUPE ST	EDR Hist Auto	TP
CD385 / 11	FORMER UT SHELL	1901 GUADALUPE ST	TX RDR	TP
CD386 / 11	EXXON SHOP 67450	1901 GUADALUPE	RCRA NonGen / NLR, FINDS, ECHO	TP
CD387 / 11	EXXON SHOP 67450	1901 GUADALUPE ST	TX Ind. Haz Waste	TP
CD388 / 11	U T SHELL	1901 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX Financi...	TP
CD389 / 11	EXXON SHOP GASOLINE	1901 GUADALUPE ST	EDR Hist Auto	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
CD390 / 11		1901 GUDALPE ST	ERNS	TP
CD391 / 11	U T SHELL	1901 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CD392 / 11	TENNISON PROPERTIES	19TH & GUADALUPE	EDR Hist Auto	TP
CE393 / 11	TF AFFORDABLE HOUSIN	1717 WEST 67TH STREE	FINDS	TP
CE394 / 11	AUSTIN HIGH SCHOOL	1715 WEST AVE LOT ST	TX Ind. Haz Waste	TP
CF395 / 11	0 K TAILORING CO	1814 GUADALUPE ST	EDR Hist Cleaner	TP
CF396 / 11	7 ELEVEN STORE 23295	1814 GUADALUPE ST	FINDS	TP
CF397 / 11	GULF OIL CORP	1814 GUADALUPE ST	EDR Hist Auto	TP
CF398 / 11	7 ELEVEN STORE NO 23	1814 GUADALUPE ST	TX RDR	TP
CF399 / 11	7-ELEVEN 23295	1814 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
CF400 / 11	7-11 #23295	1814 GUADALUPE ST	TX RDR	TP
CF401 / 11	WHITING ROBT E	1809 GUADALUPE ST	EDR Hist Auto	TP
CF402 / 11	KNIGHT STEWART	1805 GUADALUPE	EDR Hist Auto	TP
CG403 / 11	UT BLANTON MUSEUM OF	200 E MARTIN LUTHER	ECHO	TP
CG404 / 11	UT BLANTON MUSEUM OF	200 E MARTIN LUTHER	FINDS	TP
CG405 / 11	BLANTON MUSEUM	200 E MARTIN LUTHER	TX HIST UST	TP
CG406 / 11	BLANTON MUSEUM LANDS	200 E MLK BLVD	TX RDR	TP
CG407 / 11	SKANSKA USA BUILDING	200 E MARTIN LUTHER	TX CENTRAL REGISTRY	TP
CH408 / 11	VACANT RESTAURANT BL	1715 GUADALUPE ST.	TX ASBESTOS	TP
CG409 / 11	MAGNOLIA PETROLEUM C	105 W MARTIN LUTHER	TX HIST UST	TP
CI410 / 11	DEAVERS CONSTRUCTION	1601 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
CI411 / 11	DEAVERS CONSTRUCTION	1601 RIO GRANDE ST	TX AST	TP
CH412 / 11	1705 GUADALUPE ST. B	1705 GUADALUPE ST.	TX ASBESTOS	TP
CH413 / 11	SPOTLESS CASH CLEAN	1703 GUADALUPE ST	EDR Hist Cleaner	TP
CJ414 / 11	WILLIAM GAMON INSURA	1615 GUADALUPE STREE	TX ASBESTOS	TP
CJ415 / 11	UT ADMINISTRATION BU	1616 GUADALUPE	TX ASBESTOS	TP
CJ416 / 11	GUADALUPE MOTOR POOL	1616 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CJ417 / 11	ABOUT TIME DRY CLEAN	1616 GUADALUPE ST	EDR Hist Cleaner	TP
CJ418 / 11	UT AUSTIN DAS	1616 GUADALUPE STREE	TX TIER 2	TP
CJ419 / 11	GUADALUPE MOTOR POOL	1616 GUADALUPE ST	TX UST, TX HIST UST	TP
CK420 / 11		LBJ BLDG 111 EAST 17	ERNS	TP
CL421 / 11	ENVIRONMENTAL CONTRA	1405 RIO GRANDE ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
CL422 / 11	ENVIRONMENTAL CONTRA	1405 RIO GRANDE ST	FINDS	TP
CM423 / 11	PETTY LEASE-9 MILES	PETTY LEASE-9 MILES	TX SPILLS	TP
CN424 / 11	NOT AVAILABLE (ZONIN	101 W 15TH ST	TX HIST UST	TP
CO425 / 11	ACC RIO GRANDE ST	1215 RIO GRANDE ST	TX ASBESTOS	TP
CO426 / 11	ACC ATTACHE BUILDING	1209 RIO GRANDE	TX ASBESTOS	TP
CO427 / 11	ACC RIO GRANDE CAMPU	1209 RIO GRANDE STRE	TX ASBESTOS	TP
CP428 / 11	BURCH H H SERV STA	1228 CONGRESS AVE	EDR Hist Auto	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
429 / 11	TEXAS WORKFORCE COMM	1215 GUADALUPE ST.	TX ASBESTOS	TP
CQ430 / 11	BUTLERS TERRACE	1123 CONGRESS AVE	EDR Hist Auto	TP
CQ431 / 11	VACANT BUILDING	1117 CONGRESS	TX ASBESTOS	TP
CQ432 / 11	NO DELAY CLN &	1117 CONGRESS AVE	EDR Hist Cleaner	TP
CQ433 / 11	MUSIC LANE SHOPPING	1109 CONGRESS	TX ASBESTOS	TP
CR434 / 11	CITY OF AUSTIN - WAT	901 WEST KOENING LAN	TX TIER 2	TP
CR435 / 11	WATER/WASTEWATER NOR	901 WEST KOENING LAN	TX TIER 2	TP
CR436 / 11	WEST 9TH STREET PART	704 W 9TH ST	EDR Hist Auto	TP
CS437 / 11	TRAVIS COUNTY COURTH	1000 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CS438 / 11	HEMAN MARION SWEATT	1000 GUADALUPE STREE	TX ASBESTOS	TP
CS439 / 11	TRAVIS COUNTY COURTH	1000 GUADALUPE ST	TX UST	TP
CT440 / 11	TEXAS DEPT. OF TRANS	125 E. 11TH ST.	PRP	TP
CT441 / 11	TXDOT	125 E. 11TH STREET	ICIS, FINDS, ECHO	TP
CT442 / 11	TEXAS DEPT OF TRANSP	125 E 11TH ST	TX CENTRAL REGISTRY	TP
CT443 / 11	KENEDY COUNTY REST A	125 E. 11TH STREET	ICIS	TP
CU444 / 11	CARLSONS DAVE	915 GUADALUPE ST	EDR Hist Auto	TP
CU445 / 11	CARLSON DAVE GA	907 GUADALUPE ST	EDR Hist Auto	TP
CU446 / 11	COURT HOUSE SERV	905 GUADALUPE	EDR Hist Auto	TP
CV447 / 11	JOHNSON & LLOYD TAI	1001 CONGRESS ST	EDR Hist Cleaner	TP
CU448 / 11	VIAWEST, INC.	WEST 9TH STREET	ICIS, FINDS	TP
CW449 / 11	COMMERCIAL BUILDING	916 CONGRESS AVE	TX ASBESTOS	TP
CV450 / 11	VACANT BUILDING	107 E. 10TH STREET	TX ASBESTOS	TP
CV451 / 11	MODEL LAUNDRY	919 CONGRESS AVE	EDR Hist Cleaner	TP
CV452 / 11	MOBIL CORPORATION	919 CONGRESS AVE STE	EDR Hist Auto	TP
453 / 11	707 WEST AVE.	707 WEST AVE.	TX ASBESTOS	TP
CX454 / 11	701 RIO GRANDE	701 RIO GRANDE ST	TX ASBESTOS	TP
CY455 / 11	FAULK LIBRARY BUILDI	800 GUADALUPE STREET	TX ASBESTOS	TP
CY456 / 11	JOHN HENRY FAULK BRA	800 GUADALUPE	TX ASBESTOS	TP
CZ457 / 11	HUMBLE OIL & REFININ	719 W 6TH ST	TX HIST UST	TP
DA458 / 11	KATZ & ATLAS	618 W 6TH ST	TX CENTRAL REGISTRY	TP
DA459 / 11	KATZ & ATLAS	618 W 6TH ST	TX UST, TX HIST UST	TP
CZ460 / 11	507 WEST AVENUE	507 WEST AVENUE	TX GCC	TP
CZ461 / 11	507 WEST AVENUE	507 WEST AVE	TX IOP	TP
CZ462 / 11	507 WEST AVENUE	507 WEST AVE	TX GCC	TP
CZ463 / 11	507 WEST AVENUE	507 WEST AVE	TX CENTRAL REGISTRY	TP
DB464 / 11	TEXAS AMERICAN 220 G		PFAS ECHO	TP
DB465 / 11	BERGSTROM AIR FORCE		PFAS ECHO	TP
DA466 / 11	KELLY SMITH OWNER	617 W 6TH ST	TX HIST UST	TP
DA467 / 11	MAGNOLIA PETROLEUM C	617 W 6TH ST	TX HIST UST	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DA468 / 11	DICKERSON CINS	511 RIO GRANDE	EDR Hist Cleaner	TP
DA469 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
DA470 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	TX DRYCLEANERS	TP
DA471 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	FINDS	TP
DC472 / 11	DR PEPPER BOTTLING C	718 W 5TH ST	TX HIST UST	TP
DC473 / 11	DR PEPPER BOTTLING C	718 W 5TH ST	TX HIST UST	TP
DD474 / 11	AMERICAN TAXI CAB CO	610 W 5TH ST	TX HIST UST	TP
DD475 / 11	CAPITAL PETROLEUM PR	610 W 5TH ST	TX HIST UST	TP
DE476 / 11	RTC	400 W 6TH ST	TX HIST UST	TP
DF477 / 11	FIX IT SHOP THE	123 7TH W	EDR Hist Auto	TP
DF478 / 11	120 22 NORWOOD MOTOR	120 7TH W	EDR Hist Auto	TP
DF479 / 11	MOTORAMP STORAGE	118 7TH W	EDR Hist Auto	TP
DF480 / 11	A CLEANERS & DYERS	119 7TH W	EDR Hist Cleaner	TP
DE481 / 11	SHIRLEY N A CLNRS	407 6TH W	EDR Hist Cleaner	TP
DE482 / 11	KOCH CLEANING & DYIN	405 6TH W	EDR Hist Cleaner	TP
DE483 / 11	ALAMO HOTEL GARAGE	402 6TH W	EDR Hist Auto	TP
DE484 / 11	PATSCHKE ALAMO	400 6TH W	EDR Hist Auto	TP
DE485 / 11	GRAYBURG OIL CO STA	401 6TH W	EDR Hist Auto	TP
DG486 / 11	MASTER VALET CLEANER	109 E 7TH ST	EDR Hist Cleaner	TP
DG487 / 11	DRISKILL HOTEL STEAM	113 E 7TH ST	EDR Hist Cleaner	TP
DG488 / 11	JLR CLEANERS	612 BRAZOS STREET	US AIRS, FINDS, ECHO	TP
DG489 / 11	DAVIS MAX DCLO CLNR	612 BRAZOS ST	EDR Hist Cleaner	TP
DG490 / 11	VACANT OFFICE BUILDI	612 BRAZOS	TX ASBESTOS	TP
DH491 / 11	DICKERSON DRY CLEANI	600 N CONGRESS AVE	TX HIST UST	TP
DI492 / 11	B & N AXEL SERV	503 GUADALUPE	EDR Hist Auto	TP
DJ493 / 11	LYM ARCHITECTURE BLD	610 BRAZOS	TX ASBESTOS	TP
DJ494 / 11	OFFICE BUILDING	610 BRAZOS	TX ASBESTOS	TP
DJ495 / 11	LYM ARCHITECTURE BUI	610 BRAZOS	TX ASBESTOS	TP
DH496 / 11	J HARPER STARR BLDG	106 W 6TH	TX RDR	TP
DK497 / 11	SOUTHWEST TOWERS	211 E 7TH	TX ASBESTOS	TP
DK498 / 11	MCI- AUSXTX (TXAUSXT	211 E 7TH ST FL 9	TX TIER 2	TP
DK499 / 11	GENERAL MUFFLER CORP	211 E 7TH	EDR Hist Auto	TP
DK500 / 11	MACONDA PARK	211 E 7TH ST STE 709	TX CENTRAL REGISTRY	TP
DK501 / 11	MCI AUSXTX	211 EAST 7TH STREET,	TX TIER 2	TP
DK502 / 11	REEF SERVICES LLC/D/	211 E. 7TH STREET, S	FINDS	TP
DK503 / 11	SOUTHWEST TOWERS	211 E 7TH STREET	TX HIST UST, TX ASBESTOS	TP
DJ504 / 11	DAVIS MAX DCLO CLNR	609 BRAZOS ST	EDR Hist Cleaner	TP
DH505 / 11	EXCELSIOR LAUNDRY	117 6TH W	EDR Hist Cleaner	TP
DH506 / 11	SCARBROUGH BUILDING	101 E. 6TH STREET	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DH507 / 11	SCARBROUGH BLDG.	101 E. 6TH STREET	TX ASBESTOS	TP
DH508 / 11	SCARBROUGH BUILDING	101 W 6TH ST	TX VCP, TX HIST UST	TP
DH509 / 11	SCARBROUGH BUILDING	101 W 6TH ST	FINDS	TP
DH510 / 11	SCARBROUGH BUILDING	101 W 6TH ST	TX CENTRAL REGISTRY	TP
DH511 / 11	CARRINGTON ASSOCIATE	101 W 6TH ST	FINDS	TP
DL512 / 11	AUSTIN CITY OF	301 W AVE	HIST FTTS	TP
DL513 / 11	AUSTIN CITY ELECT UT	301 W AVE	RCRA-SQG, FINDS, ECHO	TP
DL514 / 11	AUSTIN ENERGY - ENER	301 WEST AVENUE	TX GCC	TP
DL515 / 11	AUSTIN ENERGY WEST A	301 WEST AVE	TX UST, TX Financial Assurance	TP
DL516 / 11	CITY OF AUSTIN	301 WEST AVE	FINDS	TP
DL517 / 11	AUSTIN ENERGY-ENERGY	301 WEST AVE	TX VCP	TP
DL518 / 11	AUSTIN ENERGY - ENER	301 WEST AVE	TX GCC	TP
DL519 / 11	AUSTIN ENERGY CONTRO	301 WEST AVE	TX HIST UST, TX ASBESTOS	TP
DL520 / 11	AUSTIN CITY OF	301 W AVE	FTTS	TP
DL521 / 11	AUSTIN ENERGY WEST A	301 WEST AVE	TX CENTRAL REGISTRY	TP
DL522 / 11	ENERGY CONTROL CENTE	301 WEST AVE.	TX TIER 2	TP
DM523 / 11	YOUNG 0 E AUTO REPR	613 TRINITY ST	EDR Hist Auto	TP
DN524 / 11	STAGES PORT E TAILOR	521 CONGRESS AVE	EDR Hist Cleaner	TP
DM525 / 11	CENTEX AUTO REPAIR	405 E 7TH ST	EDR Hist Auto	TP
DN526 / 11	515 CONGRESS OFFICE	515 CONGRESS AVE.	TX ASBESTOS	TP
DM527 / 11	GUSS GARAGE AUTO	609 TRINITY ST	EDR Hist Auto	TP
DM528 / 11	JOHNSON HARRY E	605 TRINITY	EDR Hist Auto	TP
DO529 / 11	SOUTHERN SERVICE STA	403 GUADALUPE	EDR Hist Auto	TP
DP530 / 11	13 MAG/ IN THE FLESH	211 E 6 STREET	TX ASBESTOS	TP
DP531 / 11	13 MAG/IN THE FLESH	211 E 6TH ST #B	TX ASBESTOS	TP
DP532 / 11	NCNB TEXAS	219 E 6TH ST	TX LPST	TP
DP533 / 11	NCNB TEXAS	219 E 6TH ST	TX CENTRAL REGISTRY	TP
DP534 / 11	MAJESTIC CLEANERS	219 E SIXTH	EDR Hist Cleaner	TP
DO535 / 11	THE REPUBLIC	401 W 4 STREET	FINDS	TP
DO536 / 11	THE REPUBLIC	401 W 4 STREET	ECHO	TP
DO537 / 11	THE REPUBLIC	401 W 4 STREET	TX CENTRAL REGISTRY	TP
DQ538 / 11	BLACK CAT TATTOO	315 E 6 STREET	TX ASBESTOS	TP
DQ539 / 11	LEVI JOSEPH MERCHAN	315 E 6TH ST	EDR Hist Cleaner	TP
DR540 / 11	TATTOOS FROM THE SOU	514 E 6TH ST	TX ASBESTOS	TP
DR541 / 11	TATTOOS FROM THE SOU	514 E 6TH STREET	TX ASBESTOS	TP
DR542 / 11	ALL SAINTS TATTOO	514 E 6TH ST	TX ASBESTOS	TP
DR543 / 11	ALL SAINTS TATTOOS	514 E 6TH STREET	TX ASBESTOS	TP
DR544 / 11	JUNIOR LEAGUE OF AUS	522 E 6TH ST	TX HIST UST	TP
DR545 / 11	JUNIOR LEAGUE OF AUS	524 E 6TH ST	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DR546 / 11	JUNIOR LEAGUE OF AUS	524 E 6TH ST	TX LPST, TX UST	TP
DR547 / 11	GREGG AUTO REPAIRS	610 RED RIVER	EDR Hist Auto	TP
DR548 / 11	CAIN RHONIE AUTO	608 RED RIVER CT	EDR Hist Auto	TP
DR549 / 11	MARX J W AUTO REPR	606 RED RIVER CT	EDR Hist Auto	TP
DR550 / 11	HERRING WALTER B AUT	606 6TH E	EDR Hist Auto	TP
DR551 / 11	HERRINGS GARAGE AUTO	610 6TH ST E	EDR Hist Auto	TP
DR552 / 11	HERRINGS GARAGE AUTO	610 6TH ST E	EDR Hist Auto	TP
DR553 / 11	BIG SIX GARAGE AUTO	610 6TH E	EDR Hist Auto	TP
DS554 / 11	WALKER OIL COMP.	300-400 GUADALUPE	TX HIST UST	TP
DS555 / 11	GUGENHEIM-GOLDSMITH	410 E 3RD ST	TX HIST UST	TP
DS556 / 11	AUSTIN MUSEUM OF ART	400 W 3RD ST AUSTIN	TX HIST UST, TX CENTRAL REGISTRY	TP
DT557 / 11	MAGNOLIA PETROLEUM C	617 E 6TH ST	TX HIST UST	TP
DU558 / 11	504 5TH ST	504 EAST 5TH ST	TX ASBESTOS, TX CENTRAL REGISTRY	TP
DU559 / 11	STEARNS JACK AUTO	502 RED RIVER CT	EDR Hist Auto	TP
DV560 / 11	CATHYS DOWNTOWN CLEA	231 W 3RD ST	TX CENTRAL REGISTRY	TP
DV561 / 11	CATHYS DOWNTOWN CLEA	231 W 3RD ST	TX DRYCLEANERS	TP
DV562 / 11	CATHY CLEANER	231 W 3RD ST	EDR Hist Cleaner	TP
DU563 / 11	YELLOW CAB	555 E 5TH ST	TX HIST UST	TP
DW564 / 11	SUBSTATION; SEAHOLM	704 W CESAR CHAVEZ	TX TIER 2	TP
DW565 / 11	SEAHOLM SUBSTATION	704 WEST CESAR CHAVE	TX TIER 2	TP
DU566 / 11	FOUND ON SANBORN MAP	601 E 5TH ST	TX HIST UST	TP
DU567 / 11	G W CUNNINGHAM	601 E 5TH ST	TX HIST UST	TP
DX568 / 11	BLOCK 21	201 GUADALUPE ST	FINDS	TP
DX569 / 11	BLOCK 21 CITY OF AUS	201 GUADALUPE STREET	TX GCC, TX IOP	TP
DU570 / 11	BETHKE WALTER AUTO	408 RED RIVER	EDR Hist Auto	TP
DY571 / 11	PARSLEY W L DCLO CLN	310 CONGRESS AVE E	EDR Hist Cleaner	TP
DX572 / 11	COVERT BUICK BODY SH	402 2ND ST W	EDR Hist Auto	TP
DX573 / 11	COVERT BUICK BODY SH	402 2ND ST W	EDR Hist Auto	TP
574 / 11	GAS PIPE	701 E 5TH ST	TX ASBESTOS	TP
DZ575 / 11	SMITH BROS AUTO DLR	301 BRAZOS	EDR Hist Auto	TP
DZ576 / 11	THE WHITLEY	301 BRAZOS ST	TX CENTRAL REGISTRY	TP
DZ577 / 11	WHITLEY COMPANY#	301-05 BRAZOS	RCRA-SQG, FINDS, ECHO	TP
DZ578 / 11	MUELLERS GAR AUTO	212 3RD E	EDR Hist Auto	TP
DZ579 / 11	MUELLERS GARAGE GR	212 3RD ST E	EDR Hist Auto	TP
DZ580 / 11	THIRD AND BRAZOS	201 EAST 3RD	TX ASBESTOS	TP
DZ581 / 11	BNK 63	201 E 3RD ST	TX HIST UST	TP
EA582 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	TX CENTRAL REGISTRY	TP
EA583 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	FINDS	TP
EA584 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	ECHO	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
EB585 / 11	SILICON LABORATORIES		PFAS ECHO	TP
EC586 / 11	CIRCLE SAW SHOP	201 TRINITY ST	TX HIST UST	TP
EC587 / 11	HOBART	404 E 2ND ST	TX CENTRAL REGISTRY	TP
EC588 / 11	HOBART	404 E 2ND ST	TX Ind. Haz Waste	TP
EC589 / 11	COVERT AUTOMOBILE CO	440 E 2ND ST	TX HIST UST	TP
EC590 / 11	M. SCHNEIDER ESTATE	440 E 2ND ST	TX HIST UST	TP
ED591 / 11	SETH ENGINE PARTS	617 E 3RD ST	TX UST, TX HIST UST	TP
ED592 / 11	FORMER SETH ENGINE P	617 E 3RD ST	TX LPST	TP
ED593 / 11	HOLIDAY CLEANERS	12300 INWOOD RD STE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP
EE594 / 11	DEWEYS RADIATOR WORK	106 TRINITY ST	EDR Hist Auto	TP
595 / 11	GLENN SERVICE STATIO	10 CONGRESS AVE	EDR Hist Auto	TP
596 / 11	WCT WALLER BEACH SIT	74 TRINITY ST	TX ENF, TX COMP HIST	TP
EF597 / 11	DAVIS SPRING BRANCH	151 S 1ST ST STE 200	TX CENTRAL REGISTRY	TP
598 / 11	CFJ BARGE REFINING	210 BARTON SPRINGS #	RCRA NonGen / NLR, FINDS, ECHO	TP
EG599 / 11	80 RAINEY STREET	78 80 82 AND 84 RAIN	TX CENTRAL REGISTRY	TP
EG600 / 11	VACAN SHED	80 RAINEY STREET	TX ASBESTOS	TP
EH601 / 11	HOOTER'S RESTAURANT	425 WEST RIVERSIDE D	TX ASBESTOS	TP
EH602 / 11	FORMER GAS STATION P	425 W RIVERSIDE DR	TX TANKS, TX CENTRAL REGISTRY	TP
EI603 / 14	EDS AUTOMOTIVE	208 RIVERSIDE DR W	EDR Hist Auto	TP
EI604 / 14	MIDAS MUFFLER	207 RIVERSIDE DR W	EDR Hist Auto	TP
EI605 / 14	R&S GARAGE REPRS	205 RIVERSIDE DR W	EDR Hist Auto	TP
EI606 / 14	HAWKINS GARAGE AUTO	205 RIVERSIDE DR W	EDR Hist Auto	TP
EJ607 / 14	C.A. ARMACOST	118 W RIVERSIDE DR	TX HIST UST	TP
EJ608 / 14	REEDYS AUTO WAY	103 RIVERSIDE DR W	EDR Hist Auto	TP
EJ609 / 14	EDDIE SLACKS RIVERSI	400 CONGRESS AVE S	EDR Hist Auto	TP
EJ610 / 14	CHRISTIES CITIES	400 CONGRESS AVE S	EDR Hist Auto	TP
EJ611 / 14	CHESNUTT DON N	401 S CONGRESS	EDR Hist Cleaner	TP
EJ612 / 14	TEXAS CLEANERS	401 CONGRESS AVE S	EDR Hist Cleaner	TP
EJ613 / 14	TEXAS CLEANERS	401 CONGRESS AVE S	EDR Hist Cleaner	TP
EJ614 / 14	BOHLS SERVICE STATIO	401 CONGRESS AVE S	EDR Hist Auto	TP
EJ615 / 14	TEXAS PACIFIC COAL	401 CONGRESS AVE S	EDR Hist Auto	TP
616 / 14	COVERT AUTOMOBILE CO	507 S 1ST ST	TX HIST UST	TP
EK617 / 14	STOP N GO 2066	160 E RIVERSIDE DR	TX UST, TX HIST UST, TX Financial Assura...	TP
EK618 / 14	DIAMOND SHAMROCK 206	160 E RIVERSIDE DR	TX LPST	TP
EK619 / 14	DIAMOND SHAMROCK 206	160 E RIVERSIDE	TX RDR	TP
EK620 / 14	STOP N GO 2066	160 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
621 / 14	TURNER CREST VILLAGE	3.77 MI NE OF INTERX	FINDS, ECHO	TP
EK622 / 14	AUSTIN AMERICAN STAT	305 CONGRESS AVE	RCRA-VSQG, TX UST, TX HIST UST, FINDS, E...	TP
EK623 / 14	AUSTIN AMERICAN STAT	166 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
EL624 / 14	GILBERTS AUTO ELEC	48 EAST AVE	EDR Hist Auto	TP
EL625 / 14	OFFICE BUILDING	48 EAST AVENUE	TX ASBESTOS	TP
EM626 / 14	CAR WELL INC AUTO RE	205 RIVERSIDE DR E	EDR Hist Auto	TP
EM627 / 14	ELLIS & SALAZAR GARA	211 RIVERSIDE DR E	EDR Hist Auto	TP
EN628 / 14	TRIPLE S PETROLEUM C	900 EAST AVE	EDR Hist Auto	TP
EN629 / 14	SIGNATURE 9	900 E AVE	TX RDR	TP
EN630 / 14	SIGNATURE 9	900 EAST AVE	TX CENTRAL REGISTRY	TP
EN631 / 14	SHOPPERS MART 9	900 EAST AVE	FINDS	TP
EO632 / 14	JS MARKET-PLANT - 37	611 S CONGRESS AVE S	FINDS	TP
633 / 14		802 SOUTH 1ST STREET	ERNS	TP
EP634 / 14	CAPITAL CITY TRADE &	205 E RIVERSIDE DR	TX Ind. Haz Waste	TP
EP635 / 14	205 EAST RIVERSIDE,	205 EAST RIVERSIDE,	TX SPILLS	TP
EP636 / 14	CAPITAL CITY TRADE &	205 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	TP
EP637 / 14	UNKNOWN	205 EAST RIVERSIDE	TX SPILLS 90	TP
EP638 / 14	CAPITOL CITY TRADE &	205 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
EQ639 / 14	VACANT BUILDING	901 S. CONGRESS AVE.	TX ASBESTOS	TP
EQ640 / 14	MUSE APARTMENTS	901 S CONGRESS	TX ASBESTOS	TP
ER641 / 14	MUSIC LANE MIXED USE	1100 SOUTH CONGRESS	FINDS, ECHO	TP
ER642 / 14	MUSE APARTMENTS	1007 S. CONGRESS AVE	TX ASBESTOS	TP
ER643 / 14	CAMDEN SOUTH CONGRES	1007 S CONGRESS AVE	FINDS	TP
ES644 / 14	BOBS GARAGE	1007 CONGRESS AVE S	EDR Hist Auto	TP
ES645 / 14	KOCUREKS MAGNOLIA	1007 CONGRESS AVE S	EDR Hist Auto	TP
ES646 / 14	CAPITAL SPRING & BRA	1009 CONGRESS AVE S	EDR Hist Auto	TP
ES647 / 14	HANCOCK SERVICE STAT	1101 CONGRESS AVE S	EDR Hist Auto	TP
ET648 / 14	RUBIOLA BROTHERS	1113 S CONGRESS AVE	TX HIST UST	TP
ET649 / 14	NO DELAY CLEANERS	1117 CONGRESS AVE S	EDR Hist Cleaner	TP
ET650 / 14	NO DELAY CLEANERS CL	1117 CONGRESS AVE S	EDR Hist Cleaner	TP
ET651 / 14	MC COWN & LINDER	1123 CONGRESS AVE S	EDR Hist Auto	TP
ET652 / 14	BUTLERS TERRACE GULF	1123 CONGRESS AVE S	EDR Hist Auto	TP
653 / 14	CRAWFORD RESIDENCE	500 EAST RIVERSIDE #	TX ASBESTOS	TP
EU654 / 14	AUSTIN MOTEL	1202 SOUTH CONGRESS	TX ASBESTOS	TP
EU655 / 14	AUSTIN MOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU656 / 14	AUSTIN HOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU657 / 14	AUSTIN HOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU658 / 14	1206 S CONGRESS	1206 S. CONGRESS AVE	TX ASBESTOS	TP
EV659 / 14	DONALDSON SAND GRAVE	.75 MILE NE OF FM 43	TX RGA LF	TP
EV660 / 14		6MI E INTRSC FM973/S	TX RGA LF	TP
EU661 / 14	SOUTH AUSTIN CLEAN	1210 CONGRESS AVE S	EDR Hist Cleaner	TP
EU662 / 14	E. C. STEWART	1224 S CONGRESS AVE	TX HIST UST	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
EU663 / 14	B. E. HOWELL	1224 S CONGRESS AVE	TX HIST UST	TP
EU664 / 14	AUSTIN MOTEL	1224 S CONGRESS	TX ASBESTOS	TP
EU665 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	FINDS	TP
EU666 / 14	INNOVATIVE MEDICAL G	1221 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	TP
EU667 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	RCRA-SQG	TP
EU668 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	ECHO	TP
EU669 / 14	STATE HOUSE ON CONGR	1221 SOUTH CONGRESS	TX ASBESTOS	TP
EU670 / 14	LEONS CLEANERS INC	1221 S CONGRESS AVE	EDR Hist Cleaner	TP
EU671 / 14	SHELL IRVING FILLING	1228 CONGRESS AVE S	EDR Hist Auto	TP
EU672 / 14	BURCH H H CONOCO SER	1228 S CONGRESS	EDR Hist Auto	TP
EU673 / 14	BURCH H H SERV STA	1228 CONGRESS AVE S	EDR Hist Auto	TP
EW674 / 14	109 JAMES STREET, SI	109 JAMES STREET, SI	TX SPILLS	TP
EW675 / 14	K T GARAGE & SER	1300 CONGRESS AVE S	EDR Hist Auto	TP
EW676 / 14	CITY WRECKER SERVICE	1300 CONGRESS AVE S	EDR Hist Auto	TP
EW677 / 14	BLUE FRONT FILLING S	1301 CONGRESS AVE S	EDR Hist Auto	TP
EW678 / 14	CARLSON C A FILLING	1301 CONGRESS AVE S	EDR Hist Auto	TP
EX679 / 14	HOLLY SHORES FOOD FO	COMAL STREET AND NAS	US BROWNFIELDS	TP
EX680 / 14	HOLLY SHORES FOOD FO	COMAL STREET AND NAS	FINDS	TP
EW681 / 14	PALACE CLEANERS	1313 CONGRESS AVE S	EDR Hist Cleaner	TP
EY682 / 14	HANSON HARRY A CLNR	1315 CONGRESS AVE S	EDR Hist Cleaner	TP
EY683 / 14	SAINT VINCENT	1333 S CONGRESS AVE	FINDS, ECHO	TP
EY684 / 14	SAINT VINCENT	1333 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
EZ685 / 14	SOUTH AUSTIN BAR	1400 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ686 / 14	MEARS DOC CLNRS	1415 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ687 / 14	CAMPION COLOR	1423 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ688 / 14	TOWN 6 COUNTRY CLEAN	1423 CONGRESS AVE S	EDR Hist Cleaner	TP
FA689 / 14	AUSTIN COTTON	409 W MONROE ST	TX CENTRAL REGISTRY	TP
FA690 / 14	AUSTIN COTTON	409 W MONROE ST	TX Ind. Haz Waste	TP
FB691 / 14	A CLEANERS SUB STA	1507 CONGRESS AVE S	EDR Hist Cleaner	TP
FB692 / 14	GRIFFITH W G INDRY	1512 CONGRESS AVE S	EDR Hist Cleaner	TP
FB693 / 14	SOUTH MAIN CLEANERS	1518 CONGRESS AVE S	EDR Hist Cleaner	TP
FB694 / 14	SOUTH AUSTIN LAUN	1518 CONGRESS AVE S	EDR Hist Cleaner	TP
FC695 / 14	DOHERTY L W CLDO	1602 CONGRESS AVE S	EDR Hist Cleaner	TP
FC696 / 14	DOHERTY L W DCLO CLN	1602 CONGRESS AVE S	EDR Hist Cleaner	TP
FC697 / 14	WELLS SAML W AUTO	1606 CONGRESS AVE S	EDR Hist Auto	TP
FC698 / 14	BOBS GARAGE	1606 CONGRESS AVE S	EDR Hist Auto	TP
FC699 / 14	SOUTH AUSTIN CLNRS	1608 CONGRESS AVE S	EDR Hist Cleaner	TP
FC700 / 14	SOUTH AUSTIN CLEANER	1608 CONGRESS AVE S	EDR Hist Cleaner	TP
FC701 / 14	A. F. HARACH	1610 S CONGRESS AVE	TX HIST UST	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
FD702 / 14	STAR RIVERSIDE	1300 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FD703 / 14	RIVERVIEW APARTMENTS	1300 E. RIVERSIDE DR	TX ASBESTOS	TP
FE704 / 14	BOBS GARAGE REPRS	103 MILTON W	EDR Hist Auto	TP
FE705 / 14	CALDWELL & MILLER	1700 S CONGRESS AVE	TX HIST UST	TP
FE706 / 14	CALDWELL & MILLER	1700 S CONGRESS AVE	TX HIST UST	TP
FE707 / 14	T. J. CALDWELL	1700 S CONGRESS AVE	TX HIST UST	TP
FF708 / 14	RUTLANDS PHILLIPS 66	1610 RIVERSIDE DR E	EDR Hist Auto	TP
FG709 / 14	DYE A D FILL STA	1801 CONGRESS AVE S	EDR Hist Auto	TP
FG710 / 14	DYE SALES & SERVICE	1801 CONGRESS AVE S	EDR Hist Auto	TP
FF711 / 14	SHOPPERS MART 22	1609 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FF712 / 14		1609 EAST RIVERSIDE	ERNS	TP
FF713 / 14	RUTLAND PHILLIPS 66	1609 E RIVERSIDE	EDR Hist Auto	TP
FF714 / 14	SHOPPERS MART 22	1609 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST	TP
FF715 / 14	SIGMOR SHAMROCK SERV	1620 RIVERSIDE DR	EDR Hist Auto	TP
716 / 14	CITY OF AUSTIN BOARD	1820 S LAKESHORE BLV	TX CENTRAL REGISTRY	TP
717 / 14	SOUTHSHORE TOWNHOMES	1201 TOWN CREEK DR	TX CENTRAL REGISTRY	TP
FH718 / 14	TEXAS AUTOMOTIVE SER	2006 CONGRESS AVE S	EDR Hist Auto	TP
FH719 / 14	HUGHES LAUNDERETTE	2006 CONGRESS AVE S	EDR Hist Cleaner	TP
FI720 / 14	ACME CLEANERS	1800 RIVERSIDE DR E	EDR Hist Cleaner	TP
FI721 / 14	KWIK WASH COIN LAUND	1723 RIVERSIDE DR E	EDR Hist Cleaner	TP
FI722 / 14	KWIK WASH COIN LAUND	1723 RIVERSIDE DR	EDR Hist Cleaner	TP
FI723 / 14	KAVECKI TEXACO SE	1725 RIVERSIDE DR E	EDR Hist Auto	TP
FI724 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
FI725 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX ENF, TX COMP HIST	TP
FI726 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FI727 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	FINDS, ECHO	TP
FI728 / 14	7-ELEVEN 23076	1729 E RIVERSIDE DR	TX UST, TX HIST UST	TP
FI729 / 14	7 ELEVEN 23076	1729 E RIVERSIDE DR	FINDS	TP
FI730 / 14	7 ELEVEN 23076	1729 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FH731 / 14	QUALITY WHOL LNDRY	2006 CONGRESS AVE	EDR Hist Cleaner	TP
FJ732 / 14	TOWN LAKE PLAZA ASTR	1900 RIVERSIDE DR E	EDR Hist Cleaner	TP
FJ733 / 14	JIMS RIVERSIDE GULF	1801 RIVERSIDE DR E	EDR Hist Auto	TP
FK734 / 14	7-ELEVEN INC 22245	2103 S CONGRESS AVE	TX RDR	TP
FK735 / 14	7 ELEVEN STORE 22245	2103 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
FK736 / 14	7 11 STORE 22245	2103 S CONGRESS AVE	TX RDR	TP
FK737 / 14	7 ELEVEN STORE 22245	2103 S CONGRESS AVE	FINDS	TP
FK738 / 14	7-ELEVEN 22245	2103 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
FK739 / 14	SIGMOR SHAMROCK SERV	2105 CONGRESS AVE S	EDR Hist Auto	TP
FK740 / 14	TUCKER & RILEY GARAG	2100 CONGRESS AVE S	EDR Hist Auto	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
FK741 / 14	BOHLS SERVICE STATIO	2109 CONGRESS AVE S	EDR Hist Auto	TP
742 / 14	MAJESTIC CLEANERS	2114 CONGRESS AVE S	EDR Hist Cleaner	TP
FL743 / 14	TOWN LAKE PLAZA SHOP	1918 E RIVERSIDE DR	TX VCP, TX GCC	TP
FL744 / 14	TOWN LAKE PLAZA SHOP	1918 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FL745 / 14	TOWN LAKE PLAZA SHOP	1918 EAST RIVERSIDE	TX GCC	TP
FL746 / 14	SOUTHSHORE RETAIL	1920 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FM747 / 14	RILEYS LIVE OAK	2121 CONGRESS AVE S	EDR Hist Auto	TP
FM748 / 14	JOHNSON T J FILL STA	2201 CONGRESS AVE S	EDR Hist Auto	TP
FN749 / 14	HIGGINS AUTOMOTIVE	2202 CONGRESS AVE S	EDR Hist Auto	TP
FO750 / 14	RIVERSIDE TEXACO	2000 RIVERSIDE DR E	EDR Hist Auto	TP
FP751 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX CLI	TP
FP752 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX CLI	TP
FP753 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX HIST LF	TP
FN754 / 14	KWIK WASH COIN LAUND	2209 CONGRESS AVE S	EDR Hist Cleaner	TP
FO755 / 14	WALGREEN 2915	2020 E RIVERSIDE DR	RCRA-SQG, FINDS, ECHO	TP
FO756 / 14	WALGREENS	2020 E RIVERSIDE DR	TX ASBESTOS, TX Ind. Haz Waste	TP
FO757 / 14	WALGREENS 2915	2020 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FQ758 / 14	BOHOT ENCO PRODUCTS	2300 CONGRESS AVE S	EDR Hist Auto	TP
FQ759 / 14	MASON BROS SERV	2300 CONGRESS AVE S	EDR Hist Auto	TP
FQ760 / 14	JOHNSON HUGO C	2215 CONGRESS AVE S	EDR Hist Auto	TP
FQ761 / 14	JOHNSON HUGO SERV	2215 CONGRESS AVE S	EDR Hist Auto	TP
FQ762 / 14	BROWN JACK CLEANERS	2215 CONGRESS AVE S	EDR Hist Cleaner	TP
FR763 / 14	KENNETH A ROBERTSON	RIVERSIDE & BURTON	TX UST	TP
FR764 / 14	KENNETH A ROBERTSON	RIVERSIDE & BURTON	FINDS	TP
FS765 / 14	EAST BOULDIN-EUCLID-	2400-2600 EUCLID, 24	TX CENTRAL REGISTRY	TP
FS766 / 14	TEJAS WATER HAULERS	2405 FOREST AVE	TX CENTRAL REGISTRY	TP
FT767 / 14	ONE HOUR MARTINIZING	2326 CONGRESS AVE S	EDR Hist Cleaner	TP
FT768 / 14	TWIN OAKS SERV STA	2315 CONGRESS AVE S	EDR Hist Auto	TP
FT769 / 14	TWIN OAKS GULF SERVI	2315 CONGRESS AVE S	EDR Hist Auto	TP
FT770 / 14	SOUTH AUSTIN CONOCO	2332 S CONGRESS	EDR Hist Auto	TP
FT771 / 14	ES 3S MC ANGUS MILFO	2323 CONGRESS AVE S	EDR Hist Auto	TP
FT772 / 14	SOUTH AUSTIN CONOCO	2336 CONGRESS AVE S	EDR Hist Auto	TP
FT773 / 14	S AUSTIN CONOCO	2336 CONGRESS AVE S	EDR Hist Auto	TP
FT774 / 14	INSPIRED MOVEMENT	2311 S CONGRESS AVE	TX ASBESTOS	TP
FT775 / 14	FORMER SUBWAY	2315 S CONGRESS AVE	TX ASBESTOS	TP
FT776 / 14	TWIN OAKS SERV	2315 CONGRESS AVE	EDR Hist Auto	TP
FU777 / 14	TWIN OAKS MOBIL GAS	2401 CONGRESS AVE S	EDR Hist Auto	TP
FU778 / 14	ODAS JUNG	104 E OLTORF ST	TX HIST UST	TP
FV779 / 15	METROPOLITAN APTS #	2423 TOWN LAKE CIRCL	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
FV780 / 15	METROPOLITAN APARTME	2423 TOWN LAKE CENTE	TX ASBESTOS	TP
FV781 / 15	METROPOLITAN APARTME	2423 TOWN LAKE CIRCL	TX ASBESTOS	TP
FU782 / 14	ACE MART RESTAURANT	2415 S CONGRESS AVE	TX ASBESTOS	TP
FW783 / 14	THE JEWEL APARTMENTS	1616 ROYAL CREST	TX ASBESTOS	TP
FW784 / 14	JEWEL APARTMENTS	1616 ROYAL CREST DRI	TX ASBESTOS	TP
785 / 14		2515 WILSON ST	DOT OPS	TP
786 / 14	2501 SOUTH CONGRESS	2501 SOUTH CONGRESS	TX ASBESTOS	TP
FX787 / 14		2610 EUCLID AVE	TX LEAD	TP
FY788 / 14	SEMATECH CONSTRUCTIO	550 OLTORF ST E	ICIS, FINDS, ECHO	TP
789 / 14	OAKS APARTMENTS, AUS	OAKS APARTMENTS, AUS	TX SPILLS	TP
FX790 / 14		2612 EUCLID AVE	TX LEAD	TP
FZ791 / 14	GARDNER BETTS JUVENI	2515 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
FZ792 / 14	GARDNER BETTS JUVENI	2515 SOUTH CONGRESS	TX ASBESTOS	TP
FZ793 / 14	GARDNER BETTS JUVENI	2515 S CONGRESS AVE	TX UST, TX HIST UST	TP
GA794 / 14	DRY CLEAN USA	2410 E RIVERSIDE	EDR Hist Cleaner	TP
GA795 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	FINDS	TP
GA796 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
GA797 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	TX VCP, TX ASBESTOS	TP
FZ798 / 14	KASSON BILL YAMAHA M	2603 CONGRESS AVE S	EDR Hist Auto	TP
GB799 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX UST, TX HIST UST, TX Financial Assura...	TP
GB800 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX TIER 2	TP
GB801 / 14	SOUTHWESTERN BELL TE	201 CUMBERLAND RD	TX LPST	TP
GB802 / 14	HICKORY 442 XP2995	201 CUMBERLAND RD	TX CENTRAL REGISTRY	TP
GB803 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX AST	TP
GC804 / 14	SHOP N SAVE	2204 WOODLAND AVE	TX CENTRAL REGISTRY	TP
GC805 / 14	SHOP N SAVE	2204 WOODLAND AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
GC806 / 14	T M T INC	2204 WOODLAND DR	EDR Hist Auto	TP
GC807 / 14	HNQ INC DBA SHOP N S	2204 WOODLAND AVE	FINDS	TP
GD808 / 14	HENDRICKS TOM AUTO B	2701 CONGRESS AVE S	EDR Hist Auto	TP
GD809 / 14	TWIN OAKS SHELL SERV	2704 CONGRESS AVE S	EDR Hist Auto	TP
GD810 / 14	WHITTS SERV STA	2704 CONGRESS AVE S	EDR Hist Auto	TP
GD811 / 14	SOULE MARK AUTOMOTIV	2716 CONGRESS AVE S	EDR Hist Auto	TP
GE812 / 14	MCSPADDEN AUTOMOTIVE	2716 S CONGRESS AVE	FINDS	TP
GE813 / 14	MCSPADDEN AUTOMOTIVE	2716 SOUTH CONGRESS,	TX SPILLS	TP
GF814 / 15	OXFORD FINE CLEANERS	4410 E RIVERSIDE DR	EDR Hist Cleaner	TP
GG815 / 14	KWIK WASH COIN LAUND	3004 CONGRESS AVE S	EDR Hist Cleaner	TP
GG816 / 14	ATX FOOD MART	3002 S CONGRESS AVE	TX ASBESTOS	TP
GG817 / 14	STN ENTERPRISES INC	3002 S CONGRESS AVE	EDR Hist Auto	TP
GG818 / 14	ST. JOSEPH HALL	3001 CONGRESS AVE.	TX ASBESTOS	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
819 / 14	A ONE RADIATOR SERVI	3405 CONGRESS AVE S	EDR Hist Auto	TP
GH820 / 15	FAIRWAY VILLAGE APTS	FAIRWAY VILLAGE APTS	TX SPILLS	TP
GH821 / 15	FAIRWAY VILLAGE APTS		TX SPILLS 90	TP
822 / 15	FAIRWAY VILLAGE APAR	6118 FAIRWAY STREET	TX ASBESTOS	TP
GI823 / 15	VERDE APARTMENTS	2310 WICKERSHAM DRIV	TX ASBESTOS	TP
GI824 / 15	VERDE APARTMENTS	2310 WICKERSHAM LANE	TX ASBESTOS	TP
GJ825 / 15	FAMILY DOLLAR #8248	1508 MONTOPOLIS DR.	RCRA-VSQG, FINDS, ECHO	TP
GJ826 / 15	FAMILY DOLLAR	1590 MONTOPOLIS DR	TX ASBESTOS	TP
GK827 / 14	SOUTH CONGRESS FOOD	3602 S CONGRESS AVE	TX ASBESTOS	TP
GL828 / 15	RIVERSIDE EAST TOWNH	5701 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
GL829 / 15	RIVERSIDE EAST CONDO	5701 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP
GL830 / 15	RIVERSIDE EAST	5701 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP
831 / 15	FAIRWAY COIN LAUNDRY	1612 MONTOPOLIS DR	EDR Hist Cleaner	TP
GM832 / 14	SIGMOR SHAMROCK SERV	3630 CONGRESS AVE S	EDR Hist Auto	TP
GM833 / 14	MACHEN LEE SPECIAL A	3634 CONGRESS AVE S	EDR Hist Auto	TP
GM834 / 14	DYE BILL AUTOMOTIVE	3716 CONGRESS AVE S	EDR Hist Auto	TP
GN835 / 14	GREYSTAR DEVELOPMENT	3801 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GN836 / 14	SOCO CLEANERS & ALTE	3801 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GN837 / 14	GREYSTAR DEVELOPMENT	3801 S CONGRESS AVE	FINDS	TP
GN838 / 14	SOCO CLEANERS & ALTE	3801 S CONGRESS AVE	TX DRYCLEANERS	TP
GN839 / 14	SOCO CLEANER & ALTER	3801 S CONGRESS AVE	EDR Hist Cleaner	TP
GN840 / 14	YOUNG TROY H GULF SE	3800 CONGRESS AVE S	EDR Hist Auto	TP
GO841 / 14	TWO-STORY OFFICE / R	3804 S. CONGRESS AVE	TX ASBESTOS	TP
GP842 / 15	CONOCO FOOD MART	6220 EAST RIVERSIDE	TX ASBESTOS	TP
GP843 / 15	AURA RIVERSIDE	6107 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP
GP844 / 15	AURA RIVERSIDE	6107 EAST RIVERSIDE	FINDS, ECHO	TP
GO845 / 14	A A LOTUS AUTO CENTE	3822 CONGRESS AVE S	EDR Hist Auto	TP
GQ846 / 15	CIRCLE K 2741300	6306 E RIVERSIDE	TX RDR	TP
GQ847 / 15	CIRCLE K 2741300	6306 RIVERSIDE DR	TX RDR	TP
GQ848 / 15	CIRCLE K STORE 27413	6306 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
GQ849 / 15	6306 EAST RIVERSIDE	6306 EAST RIVERSIDE	HMIRS	TP
GQ850 / 15	CIRCLE K STORE #2741	6306 RIVERSIDE DR	TX RDR	TP
GQ851 / 15	VALERO CORNER STORE	6306 E RIVERSIDE DR	FINDS	TP
GQ852 / 15	DIAMOND SHAMROCK REF	6306 E RIVERSIDE DR	EDR Hist Auto	TP
GQ853 / 15	CIRCLE K STORE 27413	6306 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
GR854 / 14	YOUNG TROY GULF	3900 CONGRESS AVE S	EDR Hist Auto	TP
GR855 / 14	KAYO SERVICE STATION	3903 CONGRESS AVE S	EDR Hist Auto	TP
GR856 / 14	FINANCIAL RESOURCE M	3905 S CONGRESS AVE	TX HIST UST	TP
857 / 15	IDEA PUBLIC SCHOOLS	1909 VARGAS ROAD	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
GS858 / 18	REAR JOES GARAGE AUT	4014 CONGRESS AVE S	EDR Hist Auto	TP
GT859 / 20	BERGSTROM AIRFORCE B	N AREA OF BASE CLOSE	TX CLI	TP
GT860 / 20	BERGSTROM AIRFORCE B	N AREA OF BASE CLOSE	TX HIST LF	TP
GT861 / 20	BERGSTROM AIRFORCE B	NORTH AREA OF FORMER	TX CLI	TP
GS862 / 18	RUDYS CAFE	4105 CONGRESS AVE S	EDR Hist Auto	TP
GU863 / 18	SUNBECK AUTOMOTIVE	4139 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GU864 / 18	SUNBECK AUTOMOTIVE	4139 S CONGRESS AVE	TX LPST, TX UST	TP
GV865 / 20	GONZALEZ & LINDSEY P	1600 E HIGHWAY 71	FINDS	TP
GV866 / 20	PARKING SPOT PARKING	1600 E HIGHWAY 71	FINDS	TP
GV867 / 20	GONZALEZ & LINDSEY P	1600 E HIGHWAY 71	TX CENTRAL REGISTRY	TP
GW868 / 18	PIXELS & POWERTOOLS	4201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GW869 / 18	PIXELS & POWERTOOLS	4201 S CONGRESS AVE	FINDS, ECHO	TP
GW870 / 18	M C RIVER CITY AUTO	4201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GW871 / 18	JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	TX ASBESTOS	TP
GW872 / 18	4201 S CONGRESS	4201 S CONGRESS	TX CENTRAL REGISTRY	TP
GW873 / 18	JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	TX ASBESTOS	TP
GW874 / 17	SUNDBECK GARAGE	4220 CONGRESS AVE S	EDR Hist Auto	TP
GX875 / 17	SUNBECK AUTOMOTIVE	4239 S CONGRESS AVE	TX HIST UST	TP
GY876 / 17	AMERICAN TREE	4311 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GY877 / 17	ABM MACHINERY	4311 S. CONGRESS AVE	SEMS-ARCHIVE	TP
GY878 / 17	AMERICAN TREE	4311 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	TP
GY879 / 17	THE CONGRESS LOFTS	4315 S CONGRESS AVE	FINDS, ECHO	TP
GZ880 / 20	BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	TX TIER 2	TP
GZ881 / 20	BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	TX TIER 2	TP
GY882 / 17	THE TIRE WHAREHOUSE	4323 S CONGRESS AVE	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP
GY883 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	FINDS	TP
GY884 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	ECHO	TP
GY885 / 17	THE TIRE WHAREHOUSE	4323 S CONGRESS AVE	FINDS	TP
GY886 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	TX COMP HIST, TX CENTRAL REGISTRY	TP
887 / 17	MULTIPLE STORAGE BUI	4341 CONGRESS AVE.	TX ASBESTOS	TP
888 / 17	TENNISON PROPERTIES	4360 S CONGRESS AVE	EDR Hist Auto	TP
HA889 / 17	CAPITAL BUMPER EXCHA	4422 CONGRESS AVE S	EDR Hist Auto	TP
HB890 / 19	HAWTHORN SUITES LTD	(MET CENTER)	FINDS, ECHO	TP
HC891 / 19	HAWTHORNE SUITES	7800 E RIVERSIDE DR	ICIS, FINDS, ECHO	TP
HD892 / 17	ELL IS & SALAZAR GAR	4501 CONGRESS AVE S	EDR Hist Auto	TP
HD893 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP
HD894 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	TP
HD895 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	TX Ind. Haz Waste	TP
HC896 / 19	7901 E RIVERSIDE DR		PFAS ECHO	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
HE897 / 19	OES EQUIPMENT	7900 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
HF898 / 17		4703 SOUTH CONGRESS	ERNS	TP
HF899 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HF900 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	FINDS	TP
HF901 / 17	INMAN F M SERV	4703 CONGRESS AVE S	EDR Hist Auto	TP
HF902 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	TP
HF903 / 17	MC NEES HUMBLE	4703 CONGRESS AVE	EDR Hist Auto	TP
HF904 / 17	PHILLIPS SIXTY SIX G	4703 CONGRESS AVE S	EDR Hist Auto	TP
HG905 / 17	SOUTHSIDE RECYCLING	4917 S CONGRESS AVE	FINDS	TP
HG906 / 17	SOUTHSIDE RECYCLING	4917 S CONGRESS AVE	FTTS, HIST FTTS	TP
907 / 17	TITOS IMPORTS AUTO R	5310 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HH908 / 17	KOVAR ROY TEXACO	100 RED BIRD TRAIL	EDR Hist Auto	TP
HH909 / 17	ROOSTERS PAINT & D C	5501 S CONGRESS AVE	TX ASBESTOS	TP
HI910 / 17	RITTERS OF SOUTH	5503 CONGRESS AVE S	EDR Hist Auto	TP
HI911 / 17	5503 S CONGRESS AVE	5503 S CONGRESS AVE	TX UST, TX HIST UST	TP
HI912 / 17	VACANT	5503 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HI913 / 17	RITTERS GASOLINE STA	5505 CONGRESS AVE S	EDR Hist Auto	TP
914 / 17	SOUTHSIDE AUTO SALES	5609 1/2 S CONGRESS	TX CENTRAL REGISTRY	TP
HJ915 / 17	A PLUS AUTO & TRUCKS	5711 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
916 / 17	SOCO II APARTMENTS	6001 SOUTH CONGRESS	FINDS, ECHO	TP
HK917 / 17	H & R FOOD MART	6400 S CONGRESS AVE	FINDS	TP
HK918 / 17	H & R FOOD MART	6400 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	TP
HK919 / 17	H & R FOOD MART	6400 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
920 / 17	KWIK WASH COIN LAUND	6500 CONGRESS AVE S	EDR Hist Cleaner	TP
HL921 / 17	ACME CLEANERS	6630 CONGRESS AVE S	EDR Hist Cleaner	TP
HL922 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HL923 / 17	BROWN JACK CLEANERS	6650 S CONGRESS AVE	EDR Hist Cleaner	TP
HL924 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	TX DRYCLEANERS	TP
HL925 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	FINDS	TP
926 / 17	PUBLIC STORAGE 20149	7112 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HM927 / 17	AUSTIN ENGINE WORKS	7305 CONGRESS AVE S	EDR Hist Auto	TP
HM928 / 17	VACANT LOT	7307 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HM929 / 17	VACANT LOT	7307 S CONGRESS AVE	TX UST, TX HIST UST	TP
930 / 21	HIGHMARK	7440 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
931 / 21	SOCO II	8100 S. CONGRESS AVE	TX ASBESTOS	TP
HN932 / 21	SOCO SOUTH	8103 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HN933 / 21	SOCO SOUTH	8103 SOUTH CONGRESS	FINDS, ECHO	TP
934 / 21	CAPITAL AREA FOOD BA	8201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HO935 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
HO936 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	FINDS	TP		
HO937 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	TX ASBESTOS, TX IHW CORR ACTION	TP		
HO938 / 21	HUMPHRYS HANSEN	8411 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HO939 / 21	ANTIQUE ST LAMPS S C	8412 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HO940 / 21	ANTIQUE STREET LAMPS	8412 S CONGRESS AVEW	RCRA-SQG, FINDS, ECHO	TP		
HO941 / 21	B AND L AUTO PART	8413 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HP942 / 21	SHOP N CARRY FOOD ST	8514 S CONGRESS AVE	TX LPST	TP		
HP943 / 21	SHOP N CARRY	8514 S CONGRESS AVE	TX ASBESTOS	TP		
HP944 / 21	TOSCO MARKETING COMP	8514 S CONGRESS AVE	EDR Hist Auto	TP		
HP945 / 21	SHOP N CARRY FOOD ST	8514 S CONGRESS AVE	TX LPST	TP		
HP946 / 21	OAKS AT SLAUGHTER BL	NORTHEAST CORNER OF	TX CENTRAL REGISTRY	TP		
GD947 / 14	TEXAN MKT 5	2700 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	60	0.011	WNW
HQ948 / 11	IVORY CLEANERS & ALT	1901 RIO GRANDE ST	EDR Hist Cleaner	60	0.011	East
HQ949 / 11	ADAMS SERVICE CO GAS	1901 RIO GRANDE ST	EDR Hist Auto	60	0.011	East
HQ950 / 11	7-ELEVEN 23630	1901 RIO GRANDE ST	TX UST, TX HIST UST	60	0.011	East
HQ951 / 11	IVORY CLEANERS & ALT	1901 RIO GRANDE ST	TX LPST, TX VCP, TX ASBESTOS, TX DRYCLEA...	60	0.011	East
FG952 / 14	HI TECH AUTOMOTIVE	1801 S CONGRESS AVE	TX RDR	60	0.011	ESE
FG953 / 14	HI TECH AUTOMOTIVE	1801 S CONGRESS AVE	TX UST, TX ENF, TX NON REGIST PST	60	0.011	ESE
FG954 / 14	A. D. DYE	1801 S CONGRESS AVE	TX HIST UST	60	0.011	ESE
FG955 / 14	DYE CHARLES	1801 S CONGRESS	EDR Hist Auto	60	0.011	ESE
FG956 / 14	DYE AUTOMOTIVE	1801 S CONGRESS AVE	TX HIST UST	60	0.011	ESE
HR957 / 11	WESLEY GEORGE CLEANE	606 GUADALUPE ST	EDR Hist Cleaner	60	0.011	WNW
HR958 / 11	FIEGEL GEO JR AUTO	606 GUADALUPE ST	EDR Hist Auto	60	0.011	WNW
HS959 / 15	HEB GROCERY	2508 RIVERSIDE DR	TX RDR	61	0.012	NE
DY960 / 11	OWL TAXI SERVICE	100 W 3RD ST	TX HIST UST	61	0.012	NNE
BX961 / 11	LONGHORN CLEANERS NO	705 W 24TH ST	EDR Hist Cleaner	61	0.012	East
BX962 / 11	CIRCLE K CORPORATION	705 W 24TH ST	EDR Hist Auto	61	0.012	East
DO963 / 11	GABLES RESIDENTIAL	401 GUADALUPE ST	TX HIST UST, TX GCC, TX IOP	61	0.012	ESE
BG964 / 8	CVS PHARMACY 6892	2927 GUADALUPE ST	RCRA NonGen / NLR	61	0.012	ESE
BG965 / 8	CVS PHARMACY	2927 GUADALUPE ST	TX ASBESTOS, TX Ind. Haz Waste	61	0.012	ESE
AT966 / 8	GRAYBURG OIL CO STA	4301 GUADALUPE ST	EDR Hist Auto	61	0.012	ESE
967 / 11	PAGS CARBURETOR	403 RIO GRANDE	EDR Hist Auto	61	0.012	WNW
AT968 / 8	DODD AUTOMOTIVE	4227 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	61	0.012	NNE
AT969 / 8	DODD & HURT TEXACO S	4227 GUADALUPE ST	EDR Hist Auto	61	0.012	NNE
R970 / 6	FRUZIA FINA SERVICE	8911 LAMAR BLVD N	EDR Hist Auto	61	0.012	ESE
R971 / 6	CAPITAL FOOD MART	8911 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	61	0.012	ESE
R972 / 6	TETCO 1144	8911 N LAMAR BLVD	TX LPST, TX GCC	61	0.012	ESE
HT973 / 8	THE NEON PLANT	4401 GUADALUPE ST	TX HIST UST, TX SPILLS	62	0.012	ESE
HT974 / 8	FARRIS LUTHER L FILL	4401 GUADALUPE	EDR Hist Auto	62	0.012	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
975 / 11	HYATT REGENCY HOTEL	208 BARTON SPRINGS R	TX VCP	62	0.012	South
DE976 / 11	ROTP 2 PROPERTY	401 W 6TH ST	TX UST	62	0.012	WNW
DE977 / 11	GRAYBURG OIL	401 W 6TH ST	TX HIST UST	62	0.012	WNW
DE978 / 11	US POST OFFICE	401 W 6TH ST	TX HIST UST	62	0.012	WNW
HT979 / 8	MARX W E MOTOR	4405 GUADALUPE ST	EDR Hist Auto	62	0.012	ESE
BD980 / 8	MY CLEANERS & ALTERA	3100 GUADALUPE ST	TX DRYCLEANERS	62	0.012	WNW
BD981 / 8	MY CLEANERS & ALTERA	3100 GUADALUPE ST	EDR Hist Cleaner	62	0.012	WNW
BD982 / 8	UNIVERSITY TEXACO	3100 GUADALUPE	EDR Hist Auto	62	0.012	WNW
AG983 / 6	ZIPPY FOOD STORE	6600 N LAMAR BLVD	TX HIST UST, TX CENTRAL REGISTRY	62	0.012	WNW
AG984 / 6	ZIPPY FOOD STORE	6600 N LAMAR BLVD	TX LPST	62	0.012	WNW
EW985 / 14	TOM E. SHORT	1301 S CONGRESS AVE	TX HIST UST	62	0.012	ESE
N986 / 6	FAMILY DOLLAR #6170	9717 N. LAMAR BLVD	RCRA-VSQG, FINDS	62	0.012	ESE
N987 / 6	WALGREEN CO	9717 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	62	0.012	ESE
HL988 / 17	KWIK WASH COIN LAUND	6606 CONGRESS AVE S	EDR Hist Cleaner	62	0.012	WNW
AG989 / 6	PAYLESS GAS 866	6608 N LAMAR BLVD	TX UST	63	0.012	WNW
AG990 / 6	FUEL DISTRIBUTORS	6608 N LAMAR BLVD	TX UST	63	0.012	WNW
AG991 / 6	PAYLESS GAS	6608 LAMAR BLVD N	EDR Hist Auto	63	0.012	WNW
AI992 / 6	FAMOUS FOOD MART	6301 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	63	0.012	ESE
AI993 / 6	FOOD MART GAS & FOOD	6301 LAMAR BLVD N	EDR Hist Auto	63	0.012	ESE
AI994 / 6	SHELL FOOD MART	6301 N LAMAR BLVD	TX RDR	63	0.012	ESE
HU995 / 11	BURTONS LNDRY	411 23RD W	EDR Hist Cleaner	63	0.012	West
DG996 / 11	QUONG WAH CHINESE LA	115 E 7TH ST	EDR Hist Cleaner	63	0.012	NNE
HV997 / 3	AUTOSYSTEMS WORKSHOP	10805 N LAMAR BLVD A	EDR Hist Auto	63	0.012	ESE
HW998 / 8	GUADALUPE 4413	4413 GUADALUPE STREE	US BROWNFIELDS, FINDS	63	0.012	ESE
HW999 / 8	PEARSON WESLEY H FIL	4413 GUADALUPE	EDR Hist Auto	63	0.012	ESE
HW1000 / 8	A & R CORNER STORE	4413 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	63	0.012	ESE
HX1001 / 2	HOME DEPOT USA HD655	13309 N IH 35	RCRA-SQG	63	0.012	North
HX1002 / 2	HOME DEPOT USA HD655	13309 N IH 35	TX Ind. Haz Waste	63	0.012	North
DX1003 / 11	J.P. SCHNEIDER	401 W 2ND ST	TX HIST UST	63	0.012	WNW
DA1004 / 11	AUSTIN WATER METER	607 RIO GRANDE	EDR Hist Auto	63	0.012	WNW
DA1005 / 11	CUSTOM SERVICE CARPE	607 RIO GRANDE ST	EDR Hist Cleaner	63	0.012	WNW
HY1006 / 11	TACO BELL	2801 GUADALUPE ST	TX LPST, TX UST, TX ASBESTOS	63	0.012	ENE
HU1007 / 11	DOLLARS AND CENTS	2268 GUADALUPE	EDR Hist Cleaner	64	0.012	West
AP1008 / 8	KRENEK E J AUTO	5200 LAMAR BLVD	EDR Hist Auto	64	0.012	WNW
BZ1009 / 11	HARDIN RICHD G CO	2200 RIO GRANDE ST	EDR Hist Cleaner	64	0.012	West
HZ1010 / 6	NORTH LAMAR AUTOMOTI	8807 A N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	64	0.012	NW
X1011 / 6	RELIABLE AUTOMOTIVE	8225 LAMAR BLVD N	EDR Hist Auto	65	0.012	SE
X1012 / 6	RELIABLE AUTOMOTIVE	8225 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	65	0.012	SE
HU1013 / 11	B CO OP PRESSING	2304 GUADALUPE ST	EDR Hist Cleaner	65	0.012	West

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
IA1014 / 11	REYES CLNRS	312 BARTON SPRINGS	EDR Hist Cleaner	65	0.012	NE
FO1015 / 14	WALGREENS	2000 E RIVERSIDE DR	TX RDR	65	0.012	NE
FO1016 / 14	UMPHRIES BILL TEXACO	2000 E RIVERSIDE	EDR Hist Auto	65	0.012	NE
FO1017 / 14	TEXACO	2000 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX GCC	65	0.012	NE
IB1018 / 8	WATKINS PROPERTY	3400 GUADALUPE ST	TX UST, TX HIST UST	65	0.012	WNW
IB1019 / 8	POTTERS SERVICE STA	3400 GUADALUPE	EDR Hist Auto	65	0.012	WNW
1020 / 3	SAMS CLUB PLUS NO 62	10601 N LAMAR BLVD	RCRA-VSQG, FINDS, ECHO	65	0.012	ESE
HL1021 / 17	RAINBO BAKING	6534 S CONGRESS AVE	TX UST, TX HIST UST	65	0.012	WNW
HL1022 / 17	GENOA TRANSMISSIONS	6534 S CONGRESS AVE	EDR Hist Auto	65	0.012	WNW
FT1023 / 14	CVS PHARMACY 6844	2301 2301 S CONGRESS	RCRA NonGen / NLR, FINDS, ECHO	65	0.012	ESE
FT1024 / 14	CVS PHARMACY	2301 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	65	0.012	ESE
1025 / 11	TEXAS CLEANERS	2236 GUADALUPE	EDR Hist Cleaner	65	0.012	West
FR1026 / 14	TOWNLAKE CLEANERS	2017 RIVERSIDE DR E	EDR Hist Cleaner	65	0.012	SW
Z1027 / 6	BOYEA ASSOCIATES INC	7530 N LAMAR	EDR Hist Auto	65	0.012	WNW
FL1028 / 14	RIVER HILLS SHOPPING	1901 RIVERSIDE DR	EDR Hist Cleaner	66	0.013	WSW
X1029 / 6	UNCLE BOB'S STORAGE	8227 N. LAMAR BLVD.	TX HIST UST, TX ASBESTOS	66	0.013	SE
BM1030 / 11	TEXAS PACIFIC COAL O	2714 GUADALUPE	EDR Hist Auto	66	0.013	WSW
EO1031 / 14	TOWNE PARK LTD	611 S CONGRESS AVE	EDR Hist Cleaner	66	0.013	ESE
AN1032 / 8	TUNE SMITHS	5405 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	66	0.013	ESE
AN1033 / 8	WAYNE BARBEE MUFFLER	5405 LAMAR BLVD N	EDR Hist Auto	66	0.013	ESE
1034 / 11	LOOMIS ARMORED INC	78 N I 35	TX HIST UST	66	0.013	ESE
BN1035 / 11	LOCKHART LNDRY	2612 GUADALUPE ST	EDR Hist Cleaner	66	0.013	West
BM1036 / 11	BRANUM CLEANERS	2716 GUADALUPE	EDR Hist Cleaner	66	0.013	WSW
DM1037 / 11	PREMIUM PARKING PUBL	415 E 7TH ST	TX TANKS, TX COMP HIST, TX CENTRAL REGIS...	66	0.013	NNE
DM1038 / 11	HENRY KNEMPEL	415 E 7TH ST	TX HIST UST	66	0.013	NNE
DM1039 / 11	ALLRIGHT PARKING	415 E. 7TH ST.	TX HIST UST	66	0.013	NNE
DM1040 / 11	PREMIUM PARKING PUBL	415 E 7TH STREET	TX RDR	66	0.013	NNE
1041 / 15	AUSTIN COMMUNITY COL	5712 E RIVERSIDE DR	TX UST	66	0.013	NNE
CA1042 / 11	CVS PHARMACY	2222 GUADALUPE ST	TX ASBESTOS, TX Ind. Haz Waste	66	0.013	West
HO1043 / 21	SHOP N CARRY FOODS	8422 S CONGRESS AVE	TX LPST, TX RDR	67	0.013	WNW
HO1044 / 21	SHOP N CARRY FOODS	8422 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	67	0.013	WNW
1045 / 11	ADAMS HENRY J	1900 SPEEDWAY	EDR Hist Auto	67	0.013	ENE
CA1046 / 11	JONES JOHN H CLOTH	2214 GUADALUPE ST	EDR Hist Cleaner	67	0.013	West
BX1047 / 11	RIO GRANDE GAS	701 W 24TH	EDR Hist Auto	67	0.013	East
1048 / 8	SCOTTVS AUTOMOTIVE S	5922 LAMAR BLVD N	EDR Hist Auto	67	0.013	WNW
J1049 / 3	QUALITY BODY SHOP	10720 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	67	0.013	WNW
J1050 / 3	QUALITY BODY SHOP IN	10720 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO	67	0.013	WNW
1051 / 21	PIRRUNG MOBILE SERV	7400 CONGRESS AVE S	EDR Hist Auto	67	0.013	WNW
1052 / 3	MONARCH TRANSMISSION	10409 LAMAR BLVD N	EDR Hist Auto	67	0.013	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
IC1053 / 8	35TH AND GUADALUPE S	3508 GUADALUPE ST	EDR Hist Auto	67	0.013	WNW
BM1054 / 11	RITTERS SERVICE STAT	2718 GUADALUPE ST	EDR Hist Auto	67	0.013	WSW
BM1055 / 11	GASKINS REAL ESTATE	2718 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	67	0.013	WSW
O1056 / 6	MANAISH ENTERPRISES	9616 N LAMAR BLVD ST	EDR Hist Cleaner	68	0.013	WNW
O1057 / 6	AARONS	9616 N LAMAR BLVD	TX VCP, TX ASBESTOS	68	0.013	WNW
1058 / 11	CAMPUS SHOP CLNRS	2332 GUADALUPE ST	EDR Hist Cleaner	68	0.013	West
DC1059 / 11	GHOST TANK	501 WEST AVE.	TX HIST UST	68	0.013	WNW
DC1060 / 11	5TH AND WEST	501 WEST AVE	TX TANKS, TX RDR, TX CENTRAL REGISTRY	68	0.013	WNW
IC1061 / 8	FLAMINGO AUTOMOTIVE	3512 GUADALUPE ST	EDR Hist Auto	68	0.013	WNW
IC1062 / 8	FLAMINGO AUTOMOTIVE	3512 GUADALUPE ST	TX UST, TX HIST UST	68	0.013	WNW
IC1063 / 8	JOE DAYWOOD	3512 GUADALUPE ST	TX LPST	68	0.013	WNW
CA1064 / 11	T CLEANING & PRESSIN	2206 GUADALUPE ST	EDR Hist Cleaner	68	0.013	West
BG1065 / 8	OXFORD CLEANERS	2928 GUADALUPE ST	EDR Hist Cleaner	68	0.013	WNW
FO1066 / 14	HUDSON OIL CO NO 91	2001 RIVERSIDE DR E	EDR Hist Auto	68	0.013	SW
FO1067 / 14	BEVERAGE BARN	2001 RIVERSIDE	TX RDR	68	0.013	SW
HY1068 / 11	2800 02 SMITH J J GA	2800 GUADALUPE ST	EDR Hist Auto	68	0.013	WSW
HY1069 / 11	TACO BELL	2800 GUADALUPE ST	TX HIST UST	68	0.013	WSW
ID1070 / 3	CHUCKS CUSTOM AUTO	11000 N LAMAR BLVD	TX Ind. Haz Waste	68	0.013	WNW
ID1071 / 3	CHUCKS CUSTOM AUTO I	11000 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	68	0.013	WNW
ID1072 / 3	SCHARFE DENNIS F BUI	11000 N LAMAR BLVD	EDR Hist Auto	68	0.013	WNW
ET1073 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX HIST LF	68	0.013	WNW
ET1074 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX CLI	68	0.013	WNW
ET1075 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX CLI	68	0.013	WNW
W1076 / 6	DONCO TRUCK & AUTOMO	8305 LAMAR BLVD N	EDR Hist Auto	69	0.013	SE
W1077 / 6	RYDER TRUCK RENTAL 0	8305 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	69	0.013	SE
1078 / 8	THE CAR BAZAR	5540 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	69	0.013	WNW
AI1079 / 6	CENTRAL TEXAS HARLEY	6310 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW
HV1080 / 3	SIGMOR SHAMROCK SERV	10810 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW
HV1081 / 3	LAMAR FOOD MARKET	10810 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	69	0.013	WNW
HY1082 / 11	DIRTY MARTINS PLACE	2808 GUADALUPE ST	TX UST	69	0.013	WSW
HY1083 / 11	DIRTY MARTINS PLACE	2808 GUADALUPE	TX RDR	69	0.013	WSW
IE1084 / 6	A LONDON BRIDGE AUTO	6406 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW
DF1085 / 11	RIOS BROS TAILORS	115 7TH W	EDR Hist Cleaner	69	0.013	ESE
EQ1086 / 14	SOUTH CONGRESS OFFIC	907 S CONGRESS AVE	TX HIST UST	69	0.013	ESE
EQ1087 / 14	PACIFIC SOUTHWEST BA	907 S CONGRESS AVE	TX LPST, TX UST	69	0.013	ESE
EQ1088 / 14	LON MARTIN	907 S CONGRESS AVE	TX HIST UST	69	0.013	ESE
DS1089 / 11	AUSTIN AMERICAN STAT	308 GUADALUPE	RCRA NonGen / NLR, TX Ind. Haz Waste	69	0.013	WNW
BN1090 / 11	C BYRD ROY CLN NO 2	2610 GUADALUPE ST	EDR Hist Cleaner	70	0.013	West
IF1091 / 3	METRO STAR GROCERY	10304 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	70	0.013	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
IF1092 / 3	METRO STAR GROCERY	10304 N LAMAR BLVD	TX RDR, TX CENTRAL REGISTRY	70	0.013	WNW
FE1093 / 14	MONKEY SEE MONKEY DO	1712 S CONGRESS AVE	EDR Hist Cleaner	70	0.013	WNW
BV1094 / 11	LONGHORN TAILOR SHOP	2424 GUADALUPE ST	EDR Hist Cleaner	70	0.013	West
V1095 / 6	FINELINE SPORTSWEAR	8407A N LAMAR BLVD	TX Ind. Haz Waste	70	0.013	SE
IG1096 / 11	WILLIAMS WESS	2102 GUADALUPE	EDR Hist Cleaner	70	0.013	West
IE1097 / 6	THREADGILLS	6416 N LAMAR BLVD	TX UST, TX HIST UST	70	0.013	WNW
IE1098 / 6	THREADGILLS FILL STA	6416 LAMAR BLVD	EDR Hist Auto	70	0.013	WNW
IH1099 / 11	MASON STEAM LNDRY	2006 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
I1100 / 3	PHILLIPS 66 SS 26286	11100 N LAMAR BLVD	TX LPST, TX SPILLS	71	0.013	WNW
I1101 / 3	PHILLIPS SIXTY SIX S	11100 LAMAR BLVD N	EDR Hist Auto	71	0.013	WNW
I1102 / 3	NORTH LAMAR SERVICE	11100 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	71	0.013	WNW
I1103 / 3	NORTH LAMAR PHILLIPS	11100 NORTH LAMAR	TX RDR	71	0.013	WNW
DH1104 / 11	DICKERSON CLEANING	111 6TH W	EDR Hist Cleaner	71	0.013	NNE
IH1105 / 11	UNIVERSITY CLNS	2004 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
FE1106 / 14	D. F. WRIGHT	1710 S CONGRESS AVE	TX HIST UST	71	0.013	WNW
BV1107 / 11	UNIVERSITY SERVICE C	2412 GUADALUPE	EDR Hist Auto	71	0.013	West
ES1108 / 14	C A SCHUTZE AGENCY	1101 S CONGRESS AVE	TX RDR	71	0.013	ESE
ER1109 / 14	TWOMEY AUTO WORKS	1009 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	71	0.013	ESE
ER1110 / 14	FORMER TWOMEYS AUTO	1009 S CONGRESS AVE	TX RDR	71	0.013	ESE
ER1111 / 14	TWOMEY AUTO WORKS AU	1009 S CONGRESS AVE	TX TANKS, TX ASBESTOS, TX Ind. Haz Waste...	71	0.013	ESE
ER1112 / 14	TWOMEY AUTO	1009 S. CONGRESS AVE	TX HIST UST	71	0.013	ESE
ER1113 / 14	MAGNOLIA PETROLEUM C	1009 S CONGRESS AVE	TX HIST UST	71	0.013	ESE
U1114 / 6	LUU AUTO ELECTRIC	8603 N. LAMAR BLVD.	TX HIST UST, TX RDR	71	0.013	SE
U1115 / 6	COURTNEY SIXTY SIX	8603 LAMAR BLVD	EDR Hist Auto	71	0.013	SE
Z1116 / 6	LAMAR CORNER STORE	7545 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	71	0.013	ESE
DH1117 / 11	NEWSOME FRED C CLNR	106 6TH W	EDR Hist Cleaner	71	0.013	NNE
IH1118 / 11	WILLIAMS WESS	2014 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
1119 / 15	FIRE STATION 22	5307 E RIVERSIDE DR	TX UST, TX HIST UST	71	0.013	SSW
DH1120 / 11	PARIS CLEANING PARLO	102 6TH W	EDR Hist Cleaner	71	0.013	NNE
1121 / 4	VACANT PROPERTY	11902 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	72	0.014	WNW
DH1122 / 11	SMITH KELLEY TAILOR	109 6TH W	EDR Hist Cleaner	72	0.014	NNE
1123 / 14	L. L. EARNEST	1822 S CONGRESS AVE	TX HIST UST	72	0.014	WNW
FQ1124 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	TX HIST UST	72	0.014	East
FQ1125 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	72	0.014	East
FQ1126 / 14	BROWN JACK CLEANERS	2215 S CONGRESS AVE	EDR Hist Cleaner	72	0.014	East
FQ1127 / 14	W. L. MOORE	2215 S CONGRESS AVE	TX HIST UST	72	0.014	East
FQ1128 / 14	WALLACE TEXACO	2215 CONGRESS AVE	EDR Hist Auto	72	0.014	East
FQ1129 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	TX LPST, TX UST, TX DRYCLEANERS, TX Ind....	72	0.014	East
FQ1130 / 14	RAMIREZ TEXACO STATI	2215 S CONGRESS	EDR Hist Auto	72	0.014	East

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
DN1131 / 11	LATTIMORE CLEANERS	129 6TH E	EDR Hist Cleaner	73	0.014	NNE
BU1132 / 11	REYES CLNS	2504 GUADALUPE ST	EDR Hist Cleaner	73	0.014	West
H1133 / 3	A ME KANNIKS OTTO NE	11104 LAMAR BLVD N	EDR Hist Auto	73	0.014	WNW
K1134 / 3	QUICK LUBE CAR SERV	10300 LAMAR BLVD N	EDR Hist Auto	73	0.014	WNW
DP1135 / 11	MAJESTIC CLNRS	219 6TH E	EDR Hist Cleaner	73	0.014	NNE
DP1136 / 11	MAJESTIC CLEANERS GR	219 6TH ST E	EDR Hist Cleaner	73	0.014	NNE
S1137 / 6	QUALITY ENGINE EXCHA	8807 B N LAMAR BLVD	RCRA-VSQG, FINDS, ECHO, TX Ind. Haz Wast...	73	0.014	SE
S1138 / 6	AUSTIN QUALITY ENGIN	8807 LAMAR BLVD N	EDR Hist Auto	73	0.014	SE
S1139 / 6	OLMEDA TIRE & AUTO	8807 N LAMAR BLVD	TX RDR	73	0.014	SE
S1140 / 6	NORTH LAMAR AUTOMOTI	8807 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	73	0.014	SE
GQ1141 / 15	CONOCO FOOD MART	6214 E RIVERSIDE DR	EDR Hist Auto	74	0.014	NNE
GQ1142 / 15	CONOCO FOOD MART	6214 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	74	0.014	NNE
GQ1143 / 15	CONOCO FOOD MART	6214 EAST RIVERSIDE	TX RDR	74	0.014	NNE
GR1144 / 14	YOUNG TROY H GULF	3900 CONGRESS AVE	EDR Hist Auto	74	0.014	WNW
CV1145 / 11	HOME STEAM LAUNDRY	120 E 10TH ST	TX HIST UST	74	0.014	WNW
HJ1146 / 17	FAIRLVIEW GARAGE	5804 CONGRESS AVE S	EDR Hist Auto	74	0.014	WNW
EF1147 / 11	BUD FOWLER	201 S 1ST ST	TX HIST UST	74	0.014	SSE
AH1148 / 6	B & B BODY & FRAME	6518 N LAMAR BLVD	TX AIRS, TX Ind. Haz Waste, TX COMP HIST...	74	0.014	WNW
AH1149 / 6	B & B BODY & FRAME I	6518 N LAMAR	RCRA NonGen / NLR	74	0.014	WNW
HA1150 / 17	CECILS WRECKER SERV	4404 CONGRESS AVE S	EDR Hist Auto	74	0.014	WNW
1151 / 14	FORMER AUTO SALES FA	118 E RIVERSIDE DR	TX RDR	74	0.014	NE
II1152 / 6	CALIBER COLLISION NO	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
II1153 / 6	CALIBER COLLISION CE	8735 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	74	0.014	SE
II1154 / 6	DUPLICATE OF 76136	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
II1155 / 6	MAACO	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
AG1156 / 6	B LAMAR CINS NO	812 BRANTWOOD ST	EDR Hist Cleaner	74	0.014	WNW
HJ1157 / 17	LUCKY FOOD STORE	5800 S CONGRESS AVE	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	74	0.014	WNW
DP1158 / 11	KLUGE M C AUTO REPR	214 6TH E	EDR Hist Auto	75	0.014	NNE
1159 / 8	U S P & F O FOR TX	35TH	TX UST	75	0.014	ESE
GO1160 / 14	ENVIRONMENTAL IMPACT	3800 S CONGRESS AVE	TX LPST	75	0.014	WNW
DF1161 / 11	RIOS ALPHONSO TAILO	706 CONGRESS AVE	EDR Hist Cleaner	75	0.014	ESE
1162 / 11	COLLEGE HOUSES	707 W. 21ST ST	US BROWNFIELDS, FINDS	75	0.014	East
AL1163 / 8	KISHAN FOOD STOP 417	5630 N LAMAR BLVD	TX RDR	75	0.014	WNW
AL1164 / 8	7-ELEVEN #36653	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
AL1165 / 8	BRITTS AUTOMOTIVE	5630 N LAMAR	TX RDR	75	0.014	WNW
AL1166 / 8	7 ELEVEN STORE 36653	5630 N LAMAR BLVD	TX LPST, TX UST, TX Financial Assurance	75	0.014	WNW
AL1167 / 8	GRAPETTE BOTTLING CO	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
AL1168 / 8	7-ELEVEN INC STORE N	5630 N LAMAR BLVD	TX RDR	75	0.014	WNW
AL1169 / 8	HEBERT MOBIL STA	5630 LAMAR BLVD N	EDR Hist Auto	75	0.014	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AL1170 / 8	7 ELEVEN STORE 36653	5630 N LAMAR BLVD	TX LPST, TX GCC, TX RDR	75	0.014	WNW
AL1171 / 8	SOCONY MOBIL OIL CO.	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
DM1172 / 11	TOLSON OIL CO NO	409 E 7TH ST	EDR Hist Auto	76	0.014	NNE
EE1173 / 11	SCHWABE AUTOMOTIVE R	104 TRINITY ST	EDR Hist Auto	76	0.014	WNW
EE1174 / 11	GLENNS GARAGE	104 TRINITY ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	76	0.014	WNW
DU1175 / 11	REID GEO W AUTO	503 NECHES	EDR Hist Auto	76	0.014	SW
DX1176 / 11	CITY OF AUSTIN	411 W 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	76	0.014	WNW
DX1177 / 11	DEPT OF PUBLIC WORKS	411 W 2ND ST	TX Ind. Haz Waste	76	0.014	WNW
DH1178 / 11	MARY LEE COMMUNITY	600 CONGRESS AVE	US BROWNFIELDS, FINDS	76	0.014	ESE
DH1179 / 11	BONILLA JOHN TAILOR	600 CONGRESS AVE	EDR Hist Cleaner	76	0.014	ESE
HD1180 / 17	CAPITOL CARPET CLEAN	4506 CONGRESS AVE S	EDR Hist Cleaner	76	0.014	WNW
HD1181 / 17	WRECKER SERVICE	4506 S CONGRESS AVE	TX UST, TX HIST UST	76	0.014	WNW
IJ1182 / 8	TIP TOP CLEANERS	3202 GUADALUPE ST	EDR Hist Cleaner	76	0.014	WNW
IK1183 / 11	GULF COAST COALITION	816 CONGRESS AVE	EDR Hist Auto	76	0.014	ESE
IK1184 / 11	HONG WAH CHINESE LAU	804 CONGRESS AVE	EDR Hist Cleaner	76	0.014	ESE
GY1185 / 17	LAIDLAW TRANSIT	4300 S CONGRESS	RCRA-SQG, TX LPST, TX UST, TX HIST UST, ...	77	0.015	WNW
1186 / 17	SHEEHAN DENNIS W. T	5014 CONGRESS AVE	EDR Hist Cleaner	77	0.015	WNW
IJ1187 / 8	T & T CLEANERS LAUND	3206 GUADALUPE ST	EDR Hist Cleaner	77	0.015	WNW
1188 / 14	DRAKE CONDOMINIUMS	68 RAINEY ST	TX VCP	77	0.015	ESE
IL1189 / 11	AVS FOOD SERVICE INC	611 NECHES	EDR Hist Auto	77	0.015	NE
HZ1190 / 6	B JATCO TRANSMISSION	8745 LAMAR BLVD N	EDR Hist Auto	78	0.015	SE
AQ1191 / 8	MC CULLOUGHS SERV	5000 LAMAR BLVD	EDR Hist Auto	79	0.015	WNW
DU1192 / 11	JOHNSON J W SERVICE	510 E 5TH ST	EDR Hist Auto	79	0.015	SW
DU1193 / 11	TEXAS CO.	510 E 5TH ST	TX HIST UST	79	0.015	SW
IL1194 / 11	TIP TOP GARAGE AUTO	604 NECHES	EDR Hist Auto	79	0.015	SSW
IM1195 / 20	ABIA AUS431		PFAS ECHO	79	0.015	SSW
IM1196 / 20	GROUND SERVICES INTE		PFAS ECHO	79	0.015	SSW
IM1197 / 20	GLOBAL AVIATION SERV		PFAS ECHO	79	0.015	SSW
1198 / 11	BOWLES GARAGE AUTO R	306 INTERREGIONAL HW	EDR Hist Auto	79	0.015	ESE
GE1199 / 14	WITTS SERV STA	2704 CONGRESS AVE	EDR Hist Auto	79	0.015	WNW
1200 / 20	AUS STSLM		ECHO, PFAS ECHO	80	0.015	SSW
BD1201 / 8	HARTUNG PHILLIPS 66	3106 GUADALUPE ST	EDR Hist Auto	80	0.015	WNW
BB1202 / 8	SMITH ELMER L FILLIN	3711 GUADALUPE	EDR Hist Auto	81	0.015	ESE
HE1203 / 19	ELECTRONINKS	7901 E RIVERSIDE DR	RCRA-LQG	81	0.015	SSW
HE1204 / 19	ELECTRONINKS	7901 E RIVERSIDE DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	81	0.015	SSW
IN1205 / 15	ATLAS CLEANERS NO	6110 RIVERSIDE DR E	EDR Hist Cleaner	81	0.015	NNE
IN1206 / 15	ATLAS CLEANERS 2	6110 E RIVERSIDE DR	TX DRYCLEANERS	81	0.015	NNE
IO1207 / 17	CALL'S SALES & SERVI	4900 S CONGRESS AVE	TX HIST UST	81	0.015	WNW
DQ1208 / 11	SCHEUMACK & HART TA	314 6TH E	EDR Hist Cleaner	81	0.015	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DQ1209 / 11	SANCHEZ BROS CLO CLN	312 6TH E	EDR Hist Cleaner	81	0.015	NNE
HU1210 / 11	UNIVERSITY TOGGERY M	2310 GUADALUPE ST	EDR Hist Cleaner	81	0.015	West
1211 / 14	WHITES GARAGE FILLIN	304 JOHANNA W	EDR Hist Auto	81	0.015	ESE
GW1212 / 17	ENTERPRISE RENT A CA	4210 S CONGRESS AVE	TX AST	81	0.015	WNW
GW1213 / 17	FURROW BUILDING MATE	4210 S CONGRESS	RCRA-VSQG, FINDS, ECHO	81	0.015	WNW
DR1214 / 11	VACANT BUILDING	508 E. 6TH ST.	TX HIST UST	81	0.015	SW
DR1215 / 11	BOOTHE PROPERTY VACA	508 E 6TH ST	TX LPST	81	0.015	SW
DR1216 / 11	TERRY E BOOTH	508 E 6TH ST	TX UST	81	0.015	SW
DR1217 / 11	FORMER UST FACILITY	508 E. 6TH	TX HIST UST	81	0.015	SW
DR1218 / 11	A. W. HARRIS	508 E 6TH ST	TX HIST UST	81	0.015	SW
DR1219 / 11	S. FERRIS	508 E 6TH ST	TX HIST UST	81	0.015	SW
IN1220 / 15	J&S BROTHERS TIRE SH	6108 E RIVERSIDE DR	TX HIST UST, TX ENF, TX COMP HIST	81	0.015	NNE
IN1221 / 15	ACE AUTO REPAIR	6108 RIVERSIDE DR	EDR Hist Auto	81	0.015	NNE
IN1222 / 15	AUTO SALVAGE YARD	6108 E. RIVERSIDE DR	TX RDR	81	0.015	NNE
IN1223 / 15	AUTO SALVAGE YARD	6108 E. RIVERSIDE	TX RDR	81	0.015	NNE
DQ1224 / 11	PASSON FRED W C TAI	407 6TH E	EDR Hist Cleaner	81	0.015	NNE
DQ1225 / 11	LUDWIG ROBERT TAILO	406 6TH E	EDR Hist Cleaner	81	0.015	NNE
IP1226 / 11	SMITH DEE 0 TAILOR	410 6TH E	EDR Hist Cleaner	81	0.015	NNE
E1227 / 3	MOBILE HOME HAVEN	11606 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	81	0.015	WNW
DQ1228 / 11	SMITH A T DCLO PRESS	318 6TH E	EDR Hist Cleaner	82	0.016	NNE
IP1229 / 11	DATSON ISHMAEL C DCL	412 6TH E	EDR Hist Cleaner	82	0.016	NNE
AF1230 / 6	AUS TEX BODY SHOP	6706 LAMAR BLVD N	EDR Hist Auto	82	0.016	WNW
IQ1231 / 8	TUNEUP MASTERS STORE	5624 N LAMAR BLVD	TX UST, TX HIST UST	83	0.016	WNW
IQ1232 / 8	TUNEUP MASTERS INC	5624 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	83	0.016	WNW
IQ1233 / 8	TUNEUP MASTERS 1004	5624 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste	83	0.016	WNW
IQ1234 / 8	GRIFFIN JACK SERV	5624 LAMAR BLVD N	EDR Hist Auto	83	0.016	WNW
DU1235 / 11	AUSTIN CAT & DOG HOS	506 E 5TH ST	TX LPST, TX UST, TX HIST UST, TX GCC	83	0.016	SW
IR1236 / 8	ROBBINS RUSSELL H AU	4311 AVENUE A	EDR Hist Auto	83	0.016	SW
IP1237 / 11	WING KEE	418 6TH E	EDR Hist Cleaner	83	0.016	NNE
DU1238 / 11	CHAS WOLF & O.G. WOL	535 E 5TH ST	TX HIST UST	83	0.016	WSW
IB1239 / 8	DALES UNIVERSITY AUT	3402 GUADALUPE ST	EDR Hist Auto	83	0.016	WNW
IB1240 / 8	PREVIOUS PAWN SHOP	3402 GUADALUPE STREE	TX HIST UST, TX ASBESTOS	83	0.016	WNW
IB1241 / 8	CASH AMERICAN PAWN S	3402 GUADALUPE	TX LPST	83	0.016	WNW
DY1242 / 11	ELLIOTT CARL L	300 CONGRESS AVE	EDR Hist Auto	83	0.016	NNE
IC1243 / 8	SPIRES TIRE CO INC	3510 GUADALUPE	EDR Hist Auto	83	0.016	WNW
IC1244 / 8	SULLIVAN CARDINAL DC	3510 GUADALUPE ST	EDR Hist Cleaner	83	0.016	WNW
DE1245 / 11	THOMPSON BILL INC	417 6TH W	EDR Hist Auto	83	0.016	WNW
IP1246 / 11	FELTON B F C CLDO	422 6TH E	EDR Hist Cleaner	84	0.016	NNE
Y1247 / 6	ALAMO BOILER & MACHI	8134 N LAMAR BLVD	TX HIST UST	84	0.016	NW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
BB1248 / 8	CEARLEY E A FILL STA	3700 GUADALUPE ST	EDR Hist Auto	84	0.016	WNW
BA1249 / 8	JIFFY LUBE AUTO REPR	3809 GUADALUPE ST	EDR Hist Auto	85	0.016	ESE
BA1250 / 8	JIFFY LUBE STORE #82	3809 GUADALUPE	TX RDR	85	0.016	ESE
BA1251 / 8	JIFFY LUBE	3809 GUADALUPE	TX RDR	85	0.016	ESE
BA1252 / 8	HEARTLAND AUTOMOTIVE	3809 GUADALUPE	RCRA-SQG, FINDS, ECHO	85	0.016	ESE
BA1253 / 8	JIFFY LUBE	3809 GUADALUPE ST	TX UST, TX HIST UST	85	0.016	ESE
GS1254 / 18	MCCOY'S LAWN EQUIPME	4140 S CONGRESS AVE	TX HIST UST, TX ASBESTOS	85	0.016	WNW
AR1255 / 8	CECILS AUTO TRIM	4926 N LAMAR BLVD	TX UST, TX HIST UST	85	0.016	WNW
AR1256 / 8	AUSTIN RADIATOR WORK	4926 LAMAR BLVD N	EDR Hist Auto	85	0.016	WNW
BO1257 / 11	SHAFER C D SERVICE S	2600 GUADALUPE	EDR Hist Auto	86	0.016	West
BO1258 / 11	7 ELEVEN 16996	2600 GUADALUPE	TX RDR	86	0.016	West
BO1259 / 11	7-ELEVEN 16996	2600 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	86	0.016	West
F1260 / 3	BARGAIN BARN	11400 N LAMAR BLVD	TX HIST UST	87	0.016	WNW
F1261 / 3	ORACLE AUSTIN DATA C	11400 N LAMAR BLVD	TX HIST UST	87	0.016	WNW
F1262 / 3	ORACLE-AUSTIN DATA C	11400 N LAMAR BLVD	TX UST, TX Financial Assurance	87	0.016	WNW
F1263 / 3	JONES MACK SERVICE S	11400 N LAMAR	EDR Hist Auto	87	0.016	WNW
CP1264 / 11	AUTOMATIC TRANS	1300 CONGRESS AVE	EDR Hist Auto	87	0.016	WNW
IG1265 / 11	WILLIAMS WESS	2100 GUADALUPE ST	EDR Hist Cleaner	87	0.016	West
FF1266 / 14	DIAMOND SHAMROCK 236	1620 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX Financi...	88	0.017	NE
FF1267 / 14	DIAMOND SHAMROCK INC	1620 E RIVERSIDE	EDR Hist Auto	88	0.017	NE
G1268 / 3	CVS PHARMACY 7442	11300 11300 N LAMAR	RCRA NonGen / NLR	88	0.017	WNW
G1269 / 3	CVS PHARMACY 7442	11300 N LAMAR BLVD	TX ASBESTOS, TX Ind. Haz Waste	88	0.017	WNW
BV1270 / 11	COZY CLEANING AND	2402 GUADALUPE ST	EDR Hist Cleaner	88	0.017	West
1271 / 11	W HOTEL BLOCK 21	200 LAVACA ST	TX HIST UST, TX NPDES	88	0.017	SSW
BS1272 / 11	LONGHORN CLEANERS	2538 GUADALUPE	EDR Hist Cleaner	88	0.017	West
HB1273 / 19	HERAEUS AMERSIL	7715 E RIVERSIDE DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	88	0.017	WSW
HB1274 / 19	HERAEUS AMERSIL INC	7715 RIVERSIDE DRIVE	RCRA NonGen / NLR, FINDS, ECHO	88	0.017	WSW
DA1275 / 11	KORNFUEHRER TEXACO S	701 6TH ST W	EDR Hist Auto	89	0.017	WNW
DA1276 / 11	KORNFUEHRER TEXACO S	701 6TH ST W	EDR Hist Auto	89	0.017	WNW
DA1277 / 11	AUSTIN GOODYEAR CO	701 6TH W	EDR Hist Auto	89	0.017	WNW
IS1278 / 3	RESTORE RUNDBURG	SEC OF LAMAR AND BRA	TX BROWNFIELDS	90	0.017	ESE
CB1279 / 11	BROWN JACK CLEANERS	2026 GUADALUPE ST	EDR Hist Cleaner	90	0.017	West
IT1280 / 8	PETRIFIED SERV STA	4505 GUADALUPE	EDR Hist Auto	90	0.017	ESE
FL1281 / 14	BROWN JACK CLEANERS	1901 E RIVERSIDE DR	EDR Hist Cleaner	91	0.017	WSW
FL1282 / 14	JACK BROWN CLEANERS	1901 E RIVERSIDE DR	TX DRYCLEANERS	91	0.017	WSW
IJ1283 / 8	GAS A TERIA INC	3200 GUADALUPE	EDR Hist Auto	91	0.017	WNW
IH1284 / 11	VARSITY PRESSING SHO	2105 SPEEDWAY	EDR Hist Cleaner	91	0.017	East
HA1285 / 17	QUIKTRIP 4125	4402 S CONGRESS AVE	TX UST	91	0.017	WNW
CV1286 / 11	HOME STEAM	118 10TH E	EDR Hist Cleaner	91	0.017	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
EH1287 / 11	CHRISTIES CONOCO SER	400 BARTON SPRINGS R	EDR Hist Auto	92	0.017	SE
EH1288 / 11	CHTRISTIES CONOCO	400 BARTON SPRINGS R	EDR Hist Auto	92	0.017	SE
IH1289 / 11	UNIVERSITY CLEANING	2109 SPEEDWAY	EDR Hist Cleaner	92	0.017	East
CB1290 / 11	ST. AUSTIN CATHOLIC	2010 GUADALUPE ST.	TX HIST UST, TX ASBESTOS	93	0.018	West
IK1291 / 11	TROY BRANCH AUSTIN	806 CONGRESS AVE	EDR Hist Cleaner	93	0.018	ESE
CJ1292 / 11	AUSTIN MOTORCYCLE CO	1611 GUADALUPE ST	EDR Hist Auto	93	0.018	ESE
CJ1293 / 11	PETRICK FACILITY	1611 GUADALUPE ST	TX UST, TX HIST UST	93	0.018	ESE
DI1294 / 11	AMERICAN CLEANERS		PFAS ECHO	93	0.018	ESE
AR1295 / 8	PEOPLES SINCLAIR	4926 LAMAR BLVD N	EDR Hist Auto	94	0.018	WNW
AR1296 / 8	M & M SINCLAIR	4926 LAMAR BLVD	EDR Hist Auto	94	0.018	WNW
DE1297 / 11		405 W 6TH	TX HIST UST	94	0.018	WNW
EA1298 / 11	DEAN JOHNSTON	207 SAN JACINTO BLVD	TX UST	94	0.018	SSW
IU1299 / 17	THURMAN WAREHOUSE	4714 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	94	0.018	WNW
IU1300 / 17	PDQ FOOD MART	4714 S CONGRESS	EDR Hist Auto	94	0.018	WNW
FQ1301 / 14	STONE BOB	2300 S CONGRESS AVE	EDR Hist Auto	94	0.018	West
FQ1302 / 14	STONES TEXACO	2300 S CONGRESS AVE	TX LPST, TX UST	94	0.018	West
FQ1303 / 14	STONE'S TEXACO	2300 S CONGRESS AVE	TX HIST UST	94	0.018	West
FQ1304 / 14	MRS. J. TADLOCK/ HUM	2300 S CONGRESS AVE	TX HIST UST	94	0.018	West
DD1305 / 11	PIT STOP INC THE AUT	700 5TH ST W	EDR Hist Auto	95	0.018	WNW
1306 / 11	TEXAS PUBLIC SERVICE	150 E. 6TH ST.	TX HIST UST	95	0.018	NNE
AG1307 / 6	COIN 00 MATIC LAUNDR	6607 LAMAR BLVD N	EDR Hist Cleaner	95	0.018	ESE
AG1308 / 6	STONE COMPANY	6607 N LAMAR BLVD	TX HIST UST	95	0.018	ESE
EB1309 / 11	N W COR GOAD MOTOR	104 GUADALUPE	EDR Hist Auto	95	0.018	ESE
CB1310 / 11	BYRD ROY CLEANERS	2002 GUADALUPE ST	EDR Hist Cleaner	95	0.018	West
FL1311 / 14	FAMILY DOLLAR #1700	1917 E. RIVERSIDE DR	RCRA-VSQG	96	0.018	WSW
DF1312 / 11	DRISKILL HOTEL	121 7TH E	EDR Hist Cleaner	97	0.018	WNW
1313 / 11	SERVICE STATION	2500 SPEEDWAY	EDR Hist Auto	97	0.018	East
IV1314 / 11	SPEEDWAY CLEANERS	2608 SPEEDWAY	EDR Hist Cleaner	98	0.019	East
IO1315 / 17	RISING SUN JAPANESE	4930 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	98	0.019	WNW
IO1316 / 17	JET ENVIRONMENTAL SE	4930 S. CONGRESS AVE	RCRA NonGen / NLR	98	0.019	WNW
IO1317 / 17	RISING SUN JAPANESE	4930 S CONGRESS AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	98	0.019	WNW
FI1318 / 14	THE OIL EXCHANGE	1806 E RIVERSIDE DR	TX UST, TX HIST UST	98	0.019	ENE
IW1319 / 11	GULF REFG CO STA NO	26 GUADALUPE ST	EDR Hist Auto	99	0.019	NNE
DY1320 / 11	LAWSHA LEE DCLO CLNR	215 CONGRESS AVE	EDR Hist Cleaner	99	0.019	SSW
AJ1321 / 9	KLINGEMANN CAR CARE	6200 N LAMAR BLVD	TX RDR	100	0.019	WNW
AJ1322 / 9	MORGAN AUTOMOTIVE	6200 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste, TX CENTR...	100	0.019	WNW
AJ1323 / 9	NORTH LAMAR AUTOMOTI	6200 LAMAR BLVD N	EDR Hist Auto	100	0.019	WNW
IX1324 / 11	RIVERSIDE SERVICE ST	207 CONGRESS AVE S	EDR Hist Auto	100	0.019	WNW
BF1325 / 8	FOUR SON'S QUALITY C	3001 GUADALUPE	US AIRS, FINDS, ECHO, TX DRYCLEANERS	100	0.019	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BF1326 / 8	CHING WONG CLEANERS	3001 GUADALUPE ST	EDR Hist Cleaner	100	0.019	ESE
BF1327 / 8	MCWILLIAMS & FIEGEL	3001 GUADALUPE	EDR Hist Auto	100	0.019	ESE
DW1328 / 11	CENTRAL LIBRARY	710 W. CESAR CHAVEZ	TX HIST UST	100	0.019	West
1329 / 11	CHAMBERS	1025 CONGRESS AVE	EDR Hist Cleaner	101	0.019	ESE
IY1330 / 11	TOM D. SMITH	307 W 10TH ST	TX HIST UST	101	0.019	ESE
Z1331 / 6	DALE'S AUTO	7544 N. LAMAR	TX RDR	101	0.019	WNW
Z1332 / 6	DOC HOLLIDAYS PAWN S	7544 N LAMAR BLVD	TX UST	101	0.019	WNW
EJ1333 / 14	SHERRILL'S EXXON	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1334 / 14	M. H. CROCKETT	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1335 / 14	M. H. CROCKETT	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1336 / 14	PAUL SHERRILLS EXXON	343 S CONGRESS AVE	EDR Hist Auto	102	0.019	NE
EJ1337 / 14	EXXON SS6 0015	343 S CONGRESS AVE	TX LPST, TX UST	102	0.019	NE
DR1338 / 11	CASTRO CLEANERS	502 E 6TH ST	EDR Hist Cleaner	102	0.019	SW
DR1339 / 11	CASTRO'S CLEANERS	502 EAST 6TH STREET	RCRA NonGen / NLR, US AIRS, FINDS, ECHO	102	0.019	SW
DR1340 / 11	CASTROS CLEANERS	502 E 6TH ST	TX HIST UST, TX ASBESTOS, TX Ind. Haz Wa...	102	0.019	SW
AO1341 / 8	FLOYDS AUTO SALES &	5253 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	102	0.019	ESE
AO1342 / 8	GARDNERS GULL SERVIC	5253 LAMAR BLVD N	EDR Hist Auto	102	0.019	ESE
ET1343 / 14	ACE CLEANERS & ALTER	1117 S CONGRESS AVE	TX DRYCLEANERS	103	0.020	ESE
ET1344 / 14	NO DELAY CLEANERS	1117 S CONGRESS	EDR Hist Cleaner	103	0.020	ESE
CK1345 / 11	GUTHRIE J C	1712 CONGRESS AVE	EDR Hist Cleaner	103	0.020	ESE
ET1346 / 14	BUTLER WILLIAM A	1123 S CONGRESS	EDR Hist Auto	103	0.020	ESE
ET1347 / 14	DOCS AUTO WORKS	1123 S CONGRESS AVE	TX RDR	103	0.020	ESE
ET1348 / 14	MUSIC LANE OWNER, LL	1123 S. CONGRESS AVE	TX HIST UST	103	0.020	ESE
ET1349 / 14	W. W. ROGERS	1123 S CONGRESS AVE	TX HIST UST	103	0.020	ESE
ET1350 / 14	DOCS BACK YARD	1123 SOUTH CONGRESS	TX LPST, TX ASBESTOS, TX GCC, TX RDR	103	0.020	ESE
1351 / 8	BURNETTE L B O	118 31ST W	EDR Hist Auto	103	0.020	ESE
AG1352 / 6	NORVELL MACHINERY CO	6535 LAMAR BLVD N	EDR Hist Cleaner	104	0.020	ESE
BJ1353 / 8	MIDAS MUFFLER SHOP	2828 GUADALUPE ST	EDR Hist Auto	104	0.020	WSW
DY1354 / 11	SCHRAMM SINCLAIR	301 CONGRESS AVE	EDR Hist Auto	104	0.020	NNE
DA1355 / 11	KORNFUEHRER SERV	704 6TH W	EDR Hist Auto	105	0.020	WNW
R1356 / 6	ACME DRY CLEANERS &	8901 LAMAR BLVD N	EDR Hist Cleaner	105	0.020	ESE
DF1357 / 11	DRISKILL LNDRY	119 7TH E	EDR Hist Cleaner	106	0.020	WNW
DF1358 / 11	MOTOR INN	118 7TH E	EDR Hist Auto	106	0.020	WNW
DB1359 / 11	HARRIS A L AUTO REPR	119 8TH E	EDR Hist Auto	106	0.020	WNW
IZ1360 / 6	DURACLEAN ARTHOR CAR	6901 LAMAR BLVD N	EDR Hist Cleaner	106	0.020	ESE
IZ1361 / 6	SPIGHT AUTOMOTIVE	6901 N LAMAR BLVD	EDR Hist Auto	106	0.020	ESE
AO1362 / 8	AUSTINS TINT CONNECT	5319 N LAMAR BLVD	TX UST	106	0.020	ESE
AO1363 / 8	AUSTIN TINT CONNECTI	5319 N LAMAR BLVD	TX HIST UST	106	0.020	ESE
AO1364 / 8	HUMBLE PRODUCTS SERV	5319 LAMAR BLVD N	EDR Hist Auto	106	0.020	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AO1365 / 8	HUMBLE OIL & REFININ	5319 N LAMAR BLVD	TX HIST UST	106	0.020	ESE
AO1366 / 8	PHILLIPS PETROLEUM C	5301 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	106	0.020	ESE
AO1367 / 8	PHILLIPS PETROLEUM S	5301 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste	106	0.020	ESE
AO1368 / 8	PHILLIPS 66 #27288	5301 NORTH LAMAR	TX RDR	106	0.020	ESE
AO1369 / 8	PRET MANGER	5301 N LAMAR BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	106	0.020	ESE
AO1370 / 8	AMERICAN MUFFLER SHO	5301 LAMAR BLVD N	EDR Hist Auto	106	0.020	ESE
IW1371 / 11	TENNISON PROPERTIES	19TH GUADALUPE	EDR Hist Auto	106	0.020	NNE
FU1372 / 14	MRS. JAS. R. HAMILTO	2401 S CONGRESS AVE	TX HIST UST	106	0.020	SE
FU1373 / 14	HARLESS MOBIL	2401 S CONGRESS AVE	TX HIST UST	106	0.020	SE
FU1374 / 14	MOBIL SS 12 D93	2401 S CONGRESS AVE	TX LPST, TX UST	106	0.020	SE
FU1375 / 14	CHARLES DIRK TALBOT	2401 S CONGRESS AVE	EDR Hist Auto	106	0.020	SE
FU1376 / 14	MOBIL OIL CORPORATIO	2401 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	106	0.020	SE
FU1377 / 14	MOBIL OIL	2401 S CONGRESS AVE	TX Ind. Haz Waste	106	0.020	SE
1378 / 11	FIRE STATION 3	201 W 30TH ST	TX UST	106	0.020	ENE
DI1379 / 11	JACK STABLEFORD PONT	311 W 5TH ST	TX HIST UST	107	0.020	ESE
AQ1380 / 8	JOHN H WINTERS	701 W 51ST ST	TX UST, TX HIST UST	108	0.020	ESE
DH1381 / 11	LINZ NICK TAILOR	611 CONGRESS AVE E	EDR Hist Cleaner	108	0.020	NNE
JA1382 / 11	HUMBLE OIL & REFG	800 12TH W	EDR Hist Auto	109	0.021	WNW
JA1383 / 11	BREWER SERVICE	801 12TH W	EDR Hist Auto	109	0.021	WNW
CW1384 / 11	WESLEY G M DCLO CLNR	913 CONGRESS AVE	EDR Hist Cleaner	109	0.021	WNW
CW1385 / 11		913 CONGRESS	TX HIST UST	109	0.021	WNW
1386 / 15	DIAMOND SHAMROCK INC	6307 E RIVERSIDE DR	EDR Hist Auto	109	0.021	SSW
JB1387 / 11	KOFAHL CHRIS BARBER	911 CONGRESS ST	EDR Hist Cleaner	109	0.021	WNW
1388 / 11	STATE OF TEXAS PRESE	TEXAS STATE CAPITOL	RCRA NonGen / NLR	110	0.021	ESE
IM1389 / 20	MENZIES AVIATION ITP	9401 CARGO AVE STE 2	FINDS, ECHO, PFAS ECHO	110	0.021	SSW
IM1390 / 20	PRIMEFLIGHT AT AUS		ECHO, PFAS ECHO	110	0.021	SSW
IM1391 / 20	AUSTIN GATEWAY	9401 CARGO AVENUE BA	RCRA-VSQG, FINDS, ECHO	110	0.021	SSW
IM1392 / 20	GROUND SERVICES INTE	9401 CARGO AVE STE 4	RCRA NonGen / NLR, FINDS, ECHO	110	0.021	SSW
IM1393 / 20	PINNACLE AIRLINES	9401 CARGO AVE STE 4	TX Ind. Haz Waste, TX IHW CORR ACTION	110	0.021	SSW
JC1394 / 11	GREEN WATER TREATMEN	600 W. CESAR CHAVEZ	TX VCP, TX GCC, TX IOP, TX TIER 2, TX IH...	110	0.021	ENE
IS1395 / 3	ANTOINE GROCERY	11209 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	110	0.021	ESE
CY1396 / 11	PAUL O. SIMMS CO	316 W 8TH ST	TX HIST UST	112	0.021	ESE
CY1397 / 11	JOE E. ROBINSON, JR.	316 W 8TH ST	TX HIST UST	112	0.021	ESE
DB1398 / 11	LINZ GUST B CLNR	809 CONGRESS AVE	EDR Hist Cleaner	112	0.021	WNW
Z1399 / 6	KWIK WASH COIN LAUND	7543 LAMAR BLVD N	EDR Hist Cleaner	112	0.021	ESE
DB1400 / 11	VIP CLEANERS	805 N CONGRESS	EDR Hist Cleaner	112	0.021	WNW
DI1401 / 11	AMERICAN CLEANERS	309 W 5TH	RCRA NonGen / NLR, FINDS, ECHO	112	0.021	ESE
DI1402 / 11	FORMER AMERICAN CLEA	309-311 WEST 5TH ST	TX PRIORITYCLEANERS, TX GCC	112	0.021	ESE
DI1403 / 11	UNITED STATES CLEANE	309 W 5TH ST	EDR Hist Cleaner	112	0.021	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DI1404 / 11	AMERICAN CLEANERS FA	309 W 5TH ST	TX VCP, TX Ind. Haz Waste	112	0.021	ESE
JD1405 / 15	ROUND2 INC.	1340 AIRPORT COMMERC	TX SWF/LF, TX SWRCY, TX ASBESTOS, TX COM...	113	0.021	South
JD1406 / 15	ROUND2, INC.	1340 AIRPORT COMMERC	RCRA-VSQG	113	0.021	South
IK1407 / 11	PEARL STEAM LAUNDRY	819 CONGRESS AVE	EDR Hist Cleaner	113	0.021	WNW
IK1408 / 11	TEXACO WINDPOWER CO	823 CONGRESS AVE 515	EDR Hist Auto	113	0.021	WNW
DF1409 / 11	RAPP BROS NEWS DLR A	617 CONGRESS AVE	EDR Hist Cleaner	113	0.021	WNW
DT1410 / 11	O. A. TIROFF	610 E 6TH ST	TX HIST UST	113	0.021	NE
DU1411 / 11	FINLEY	509 E 5TH ST	TX LPST, TX UST, TX HIST UST	114	0.022	SW
EW1412 / 14	E. C. STEWART	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1413 / 14	TRIBBLE ADV. COMPANY	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1414 / 14	A. A. ECK	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1415 / 14	MR. J. M. CAPERTON	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
DF1416 / 11	RAPP BROS NEWS DLRS	621 CONGRESS AVE	EDR Hist Cleaner	114	0.022	WNW
AQ1417 / 8	7-ELEVEN 24008	5101 N LAMAR BLVD	TX LPST, TX UST, TX ASBESTOS, TX Financi...	114	0.022	ESE
AQ1418 / 8	7-ELEVEN #24008	5101 N LAMAR	TX RDR	114	0.022	ESE
AQ1419 / 8	SEVEN ELEVEN #24008	5101 N LAMAR BLVD	TX HIST UST	114	0.022	ESE
AQ1420 / 8	W. L. BROWN	5101 N LAMAR BLVD	TX HIST UST	114	0.022	ESE
AQ1421 / 8	7 ELEVEN 24008	5101 N LAMAR	TX RDR	114	0.022	ESE
DF1422 / 11	PATTONS AUTO HOTEL	116 7TH E	EDR Hist Auto	115	0.022	WNW
DU1423 / 11	A.E. MASSENGALE	507 E 5TH ST	TX HIST UST	115	0.022	SW
FT1424 / 14	BEN H. POWELL	2304 S CONGRESS AVE	TX HIST UST	116	0.022	WNW
FT1425 / 14	GULF OIL COMPANY	2304 S CONGRESS AVE	TX HIST UST	116	0.022	WNW
JE1426 / 11	LYNDON B JOHNSON BUI	111 E 17TH ST	TX AST	117	0.022	ESE
JE1427 / 11	COMPTROLLER OF PUBLI	111 E 17TH ST	RCRA NonGen / NLR, FINDS, ECHO	117	0.022	ESE
JE1428 / 11	COMPTROLLER OF PUBLI	111 E 17TH ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	117	0.022	ESE
1429 / 11	STADIUM DRY CLEANERS	2107 SPEEDWAY	EDR Hist Cleaner	117	0.022	East
DY1430 / 11	WARDROBE CLNRS	213 CONGRESS AVE	EDR Hist Cleaner	118	0.022	SSW
DY1431 / 11	MOTORCYCLE SALES	213 CONGRESS AVE	EDR Hist Auto	118	0.022	SSW
JF1432 / 14	LOOMIS ARMORED AUSTI	78 EAST AVE	TX UST	118	0.022	ESE
IU1433 / 17	EVANS TEXACO	4712 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	118	0.022	WNW
IU1434 / 17	STEWART W T TEXACO	4712 CONGRESS AVE S	EDR Hist Auto	118	0.022	WNW
IU1435 / 17	MURPHY R L TEX	4712 CONGRESS AVE	EDR Hist Auto	118	0.022	WNW
IU1436 / 17	CLAWSONS TEXACO SERV	4712 CONGRESS AVE S	EDR Hist Auto	118	0.022	WNW
CV1437 / 11	MODEL STEAM LAUNDRY	112 10TH E	EDR Hist Cleaner	118	0.022	WNW
1438 / 14	JAMES DREW RENTAL	406 EAST AVE	TX LPST	119	0.023	ESE
DM1439 / 11	BEAR AUTOMOTIVE I EP	405 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1440 / 11	BEAR AUTOMOTIVE REPR	405 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1441 / 11	ELLIOTTS RADIATOR	406 7TH E	EDR Hist Auto	119	0.023	NNE
DM1442 / 11	ELLIOTTS RADIATOR SH	406 7TH ST E	EDR Hist Auto	119	0.023	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DM1443 / 11	ONE DAY CLNS	407 7TH E	EDR Hist Cleaner	119	0.023	NNE
DM1444 / 11	GAS MART GR	409 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1445 / 11	AUTO REPAIRS CO	408 7TH E	EDR Hist Auto	119	0.023	NNE
DM1446 / 11	JENSENS HARRY AUTO R	408 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1447 / 11	ALANIZ LOUIS AUTO RE	408 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1448 / 11	GAS A TERIA INC	409 7TH E	EDR Hist Auto	119	0.023	NNE
GQ1449 / 15	SPEEDYS	6301 E RIVERSIDE	TX RDR	119	0.023	SSW
GQ1450 / 15	CITGO GRO	6301 RIVERSIDE DR	EDR Hist Auto	119	0.023	SSW
GQ1451 / 15	SPEEDY'S	6301 EAST RIVERSIDE	TX RDR	119	0.023	SSW
GQ1452 / 15	SPEEDYS	6301 E RIVERSIDE DR	TX UST, TX HIST UST, TX SPILLS, TX ASBES...	119	0.023	SSW
JG1453 / 6	TEXAS FOOD MART	720 LAMAR PL	TX UST, TX HIST UST, TX Financial Assura...	120	0.023	ESE
1454 / 14	ABC MOBILE BRAKE	519 S 1ST ST	EDR Hist Auto	120	0.023	WNW
AL1455 / 8	CAPITOL LAUNDRY & DR	806 KOENIG LN W	EDR Hist Cleaner	120	0.023	WNW
DM1456 / 11	ELLIS & SALAZAR GARA	403 7TH ST E	EDR Hist Auto	120	0.023	NNE
DM1457 / 11	ELLIS BATTERY & AUTO	403 7TH E	EDR Hist Auto	120	0.023	NNE
JH1458 / 11	RAVENS GARAGE	605 RED RIVER CT	EDR Hist Auto	120	0.023	NE
FK1459 / 14	MS EXPRESS 901	2105 S CONGRESS AVE	TX LPST, TX UST, TX ASBESTOS, TX ENF, TX...	121	0.023	ESE
FK1460 / 14	E. M. BOHLS	2105 S CONGRESS AVE	TX HIST UST	121	0.023	ESE
FK1461 / 14	HOUSTON CONVENIENCE	2105 S CONGRESS AVE	TX RDR	121	0.023	ESE
FK1462 / 14	DIAMOND SHAMROCK	2105 S CONGRESS	EDR Hist Auto	121	0.023	ESE
FK1463 / 14	EVERYTIME FOOD MART	2105 S CONGRESS AVE	TX HIST UST	121	0.023	ESE
JI1464 / 11	CHESNUTT CLNRS	103 18TH W	EDR Hist Cleaner	121	0.023	ESE
AC1465 / 6	REED OIL CO GAS STA	7135 LAMAR BLVD N	EDR Hist Auto	121	0.023	ESE
AC1466 / 6	PIONEER SERVICE CO.	7135 N LAMAR BLVD	TX HIST UST	121	0.023	ESE
DJ1467 / 11	DRISKILL HOTEL ALLEY	604 BRAZOS ST	TX HIST UST, TX NON REGIST PST	121	0.023	SSW
DF1468 / 11	METZENTHIN BROS AUTO	102 7TH W	EDR Hist Auto	121	0.023	ESE
DF1469 / 11	RIOS FRANK TAILOR	103 7TH W	EDR Hist Cleaner	121	0.023	ESE
JJ1470 / 14	THE SHERWIN-WILLIAMS	500 E OLTORF ST	RCRA NonGen / NLR, FINDS, ECHO	122	0.023	NW
JJ1471 / 14	SHERWIN WILLIAMS	500 E OLTORF ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	122	0.023	NW
DU1472 / 11	SANDGARTENS SERVICE	510 RED RIVER CT	EDR Hist Auto	122	0.023	NE
JF1473 / 14	GILBERTS AUTO ELECTR	84 EAST AVE	EDR Hist Auto	122	0.023	ESE
JK1474 / 8	AUSTIN QUALITY CAR W	3120 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	123	0.023	WNW
JK1475 / 8	TEXACO STATION	3120 GUADALUPE ST	RCRA-VSQG, FINDS, ECHO	123	0.023	WNW
JK1476 / 8	CAR CARE CENTER	3120 GUADALUPE ST	EDR Hist Auto	123	0.023	WNW
JL1477 / 11	WILLIAM B TRAVIS	1701 CONGRESS AVE	TX UST, TX HIST UST	123	0.023	WNW
JL1478 / 11	WILLIAM TRAVIS STATE	1701 CONGRESS AVE	TX RDR	123	0.023	WNW
JL1479 / 11	RAILROAD COMMISSION	1701 CONGRESS AVE	EDR Hist Auto	123	0.023	WNW
FY1480 / 14	GUEROS ADDL SP	616 OLTORF ST E	EDR Hist Cleaner	123	0.023	SE
DG1481 / 11	SWEET CLEANERS	613 CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	123	0.023	West

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DG1482 / 11	SWEET CLEANERS	613 CONGRESS AVE	TX ASBESTOS, TX DRYCLEANERS, TX Ind. Haz...	123	0.023	West
DG1483 / 11	SWEET ONE HOUR	613 CONGRESS AVE	EDR Hist Cleaner	123	0.023	West
DN1484 / 11	JOE SING CHINESE LAU	104 E 6TH ST	EDR Hist Cleaner	124	0.023	NNE
FG1485 / 14	BUSH NET	105 E ANNIE	EDR Hist Auto	124	0.023	ESE
DB1486 / 11	ROSENTRITT H L GA	115 8TH E	EDR Hist Auto	124	0.023	WNW
DB1487 / 11	DAY R L GARAGE AUTO	114 8TH E	EDR Hist Auto	124	0.023	WNW
EH1488 / 11	401 S. 1ST ST PROJEC	401 S. 1ST ST.	TX HIST UST	124	0.023	NW
EH1489 / 11	N/A	401 S FIRST STREET	TX RDR	124	0.023	NW
AL1490 / 8	7-ELEVEN 12683	808 W KOENIG LN	TX LPST, TX UST, TX HIST UST, TX Financi...	124	0.023	WNW
DF1491 / 11	DAY R L AUTO REPR	114 7TH E	EDR Hist Auto	124	0.023	WNW
FB1492 / 14	WASHBURNS TOWN & COU	1423 S CONGRESS AVE	EDR Hist Cleaner	124	0.023	ESE
FB1493 / 14	WASHBURNS TOWN & COU	1423 S CONGRESS AVE	TX DRYCLEANERS	124	0.023	ESE
JM1494 / 6	CAPITAL FOOD STOP 2	8201 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	124	0.023	SE
JM1495 / 6	CIRCLE K STORES INC	8201 N LAMAR BLVD	EDR Hist Auto	124	0.023	SE
1496 / 14	LMN CORP	1603 S CONGRESS AVE	TX HIST UST	125	0.024	ESE
EK1497 / 14	W. T. CASWELL	501 S CONGRESS AVE	TX HIST UST	125	0.024	SW
DA1498 / 11	LOTT C G FILL STA	711 6TH W	EDR Hist Auto	125	0.024	WNW
AB1499 / 6	PATS LAWNMOWER SERVI	7205 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	126	0.024	ESE
AB1500 / 6	SCOGIN EXXON PRODUCT	7205 LAMAR BLVD N	EDR Hist Auto	126	0.024	ESE
JN1501 / 2	FORMER 7 ELEVEN 1781	12430 N LAMAR BLVD	TX RDR	126	0.024	West
JN1502 / 2	PRIME MART	12430 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	126	0.024	West
JN1503 / 2	7-ELEVEN INC	12430 N LAMAR BLVD	EDR Hist Auto	126	0.024	West
EH1504 / 14	DEEP EDDY RUG CLEANE	418 BARTON SPRINGS	EDR Hist Cleaner	127	0.024	SE
EH1505 / 14	A KISS CLEAN	418 BARTON SPRINGS	EDR Hist Cleaner	127	0.024	SE
CV1506 / 11	EXXON MOBIL CORP	1005 CONGRESS AVE ST	EDR Hist Auto	128	0.024	ESE
JO1507 / 11	TRAVIS COUNTY	705 E 14TH ST STE B1	RCRA NonGen / NLR, FINDS, ECHO	128	0.024	ESE
JO1508 / 11	TRAVIS COUNTY MEDICA	705 E 14TH ST STE B1	TX Ind. Haz Waste	128	0.024	ESE
JF1509 / 14	TEXACO SHOPPERS MART	90 EAST AVE	TX RDR	128	0.024	ESE
DY1510 / 11	R & R SERVICE STA FI	214 CONGRESS AVE	EDR Hist Auto	128	0.024	SSW
DC1511 / 11	S.B. RICKS	801 W 5TH ST	TX HIST UST	129	0.024	WNW
AT1512 / 8	MANFRED HOLOK	514 W 43RD ST	TX HIST UST	129	0.024	SW
GM1513 / 14	SOCO CENTER	3630 S CONGRESS AVE	TX LPST, TX UST, TX VCP, TX HIST UST, TX...	130	0.025	WNW
GM1514 / 14	DIAMOND SHAMROCK NO	3630 S CONGRESS ST	TX RDR	130	0.025	WNW
GM1515 / 14	SOUTH CONGRESS FOOD	3630 S CONGRESS AVE	TX RDR	130	0.025	WNW
DF1516 / 11	RIOS FRANK TAILOR	101 7TH W	EDR Hist Cleaner	130	0.025	ESE
DB1517 / 11	PAGE S F DCLO CLNR	802 CONGRESS AVE E	EDR Hist Cleaner	131	0.025	ESE
AM1518 / 8	LEGELTS FOREIGN SPOR	5412 LAMAR BLVD N	EDR Hist Auto	131	0.025	WNW
AM1519 / 8	N LAMAR U HAUL CTR	5412 N LAMAR BLVD	TX UST, TX HIST UST	131	0.025	WNW
DR1520 / 11	CURTIS GARAGE	602 NECHES ST	EDR Hist Auto	131	0.025	SW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
EL1521 / 14	AEGIS ASSOCIATES INC	44 EAST AVE STE 100	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	131	0.025	ESE
DF1522 / 11	ROYAL THE CLNRS	703 CONGRESS AVE	EDR Hist Cleaner	131	0.025	WNW
DA1523 / 11	ALFA OF AUSTIN	510 RIO GRANDE ST	EDR Hist Auto	131	0.025	WNW
FY1524 / 14	BROWNS TWIN OAKS 66	620 OLTORF ST E	EDR Hist Auto	132	0.025	SE
JB1525 / 11	WESLEY G M DCLO CLNR	913 CONGRESS AVE E	EDR Hist Cleaner	132	0.025	ESE
IJ1526 / 8	BUSKES GARAGE	3208 GUADALUPE	EDR Hist Auto	132	0.025	WNW
FU1527 / 14	SPEEDY ALIGNMENT WHE	111 OLTORF ST E	EDR Hist Auto	132	0.025	SE
CD1528 / 11	FORMER TEXAC0	1900 GUADALUPE	TX RDR	133	0.025	West
CD1529 / 11	TEXACO	1900 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	133	0.025	West
CD1530 / 11	TEXACO	1900 GUADALUPE ST	TX LPST, TX Ind. Haz Waste	133	0.025	West
CD1531 / 11	CAMPBELL A B SERVICE	1900 GUADALUPE	EDR Hist Auto	133	0.025	West
CD1532 / 11	TEXAS TAILOR SHOP	1900 GUADALUPE ST	EDR Hist Cleaner	133	0.025	West
CD1533 / 11	TEXACO STATION	1900 GUADALUPE	TX RDR	133	0.025	West
CD1534 / 11	STAR ENTERPRISES	1900 GUADALUPE ST	RCRA NonGen / NLR, FINDS, ECHO	133	0.025	West
DR1535 / 11	CASTROS CLEANERS	502 6TH ST E	EDR Hist Cleaner	133	0.025	NE
DR1536 / 11	SANCHEZ BROS DCLO CL	502 6TH E	EDR Hist Cleaner	133	0.025	NE
DR1537 / 11	HOOVER CLEANERS GR 8	502 6TH ST E	EDR Hist Cleaner	133	0.025	NE
GF1538 / 15	MOBIL OIL 00AIX	1919 S PLEASANT VALL	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	133	0.025	NE
GF1539 / 15	TETCO STORES INC	1919 S PLEASANT VALL	EDR Hist Auto	133	0.025	NE
GF1540 / 15	STAR STOP 73	1919 S PLEASANT VALL	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	133	0.025	NE
GF1541 / 15	MOBIL OIL CORPORATIO	1919 S PLEASANT VALL	RCRA NonGen / NLR, FINDS, ECHO	133	0.025	NE
DF1542 / 11	DAY R L AUTO REPR	112 7TH E	EDR Hist Auto	133	0.025	WNW
DF1543 / 11	DRISKILL STEAM LAUN	113 7TH E	EDR Hist Cleaner	133	0.025	WNW
DB1544 / 11	HONG LEE LAUNDRY	113 8TH E	EDR Hist Cleaner	133	0.025	WNW
EH1545 / 14	DEEP EDDY RUG CINS	414 BARTON SPRINGS	EDR Hist Cleaner	133	0.025	SE
DA1546 / 11	COTHRONS TEXACO SERV	701 W 6TH ST	TX LPST, TX UST, TX HIST UST	133	0.025	WNW
DA1547 / 11	KORNFUEHRER TEXACO S	701 W 6TH ST	EDR Hist Auto	133	0.025	WNW
EZ1548 / 14	CEN TEX NISSAN	1400 S CONGRESS AVE	TX UST, TX HIST UST	133	0.025	WNW
EZ1549 / 14	CEN-TEX NISSAN INC	1400 S CONGRESS	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	133	0.025	WNW
1550 / 11	UT AUSTIN MAIN CAMPU		PFAS RCRA MANIFEST	134	0.025	East
CV1551 / 11	DAVIS & CO TAILORS	1008 CONGRESS AVE	EDR Hist Cleaner	134	0.025	ESE
T1552 / 6	NORTH LAMAR PHILLIPS	8700 LAMAR BLVD N	EDR Hist Auto	134	0.025	NW
T1553 / 6	GIANT FOOD MART	8700 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	134	0.025	NW
DA1554 / 11	MASON IRA SERV STA	713 6TH W	EDR Hist Auto	134	0.025	WNW
JP1555 / 11	LITTLEFIELD PARKING	508 BRAZOS ST	TX VCP, TX GCC	134	0.025	SSW
JP1556 / 11	DELZELL & DEMENT AUT	508 BRAZOS ST	EDR Hist Auto	134	0.025	SSW
BW1557 / 11	DARES HUMBLE SERV	700 24TH W	EDR Hist Auto	135	0.026	West
JQ1558 / 11	GRAYBURG OIL CO STA	1601 CONGRESS AVE E	EDR Hist Auto	135	0.026	ESE
DY1559 / 11	AUSTIN AMERICAN STAT	305 CONGRESS AVE	TX Ind. Haz Waste	135	0.026	NNE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DQ1560 / 11	AUSTIN MOTOR SALES C	503 SAN JACINTO ST	EDR Hist Auto	135	0.026	SSW
EY1561 / 14	B. E. HOWELL	1316 S CONGRESS AVE	TX HIST UST	135	0.026	WNW
BW1562 / 11	HICKMAN HUMBLE SERVI	700 W 24TH ST	EDR Hist Auto	135	0.026	East
BB1563 / 8	SIGMOR SHAMROCK SERV	3706 GUADALUPE ST	EDR Hist Auto	135	0.026	WNW
BB1564 / 8	DIAMOND SHAMROCK 963	3706 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX Financi...	135	0.026	WNW
DG1565 / 11	LINZ NICK TAILOR	611 CONGRESS AVE	EDR Hist Cleaner	135	0.026	WSW
JR1566 / 3	EXPRESS FOOD MART	10500 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ED AQUI...	135	0.026	WNW
JR1567 / 3	EXPRESS MART 7	10500 N LAMAR BLVD	TX RDR	135	0.026	WNW
JR1568 / 3	SLAUSONS TEXACO	10500 LAMAR BLVD N	EDR Hist Auto	135	0.026	WNW
CK1569 / 11	GUTHTLRIE J C DCLO C	1712 CONGRESS AVE E	EDR Hist Cleaner	136	0.026	ESE
JS1570 / 3	7 ELEVEN 30467	10111 N LAMAR	TX RDR	136	0.026	ESE
JS1571 / 3	B PAC PITSTOP AUTO M	10111 LAMAR BLVD N	EDR Hist Auto	136	0.026	ESE
JS1572 / 3	7 ELEVEN STORE 30467	10111 N LAMAR BLVD	TX LPST, TX GCC	136	0.026	ESE
JS1573 / 3	7-ELEVEN 30467	10111 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	136	0.026	ESE
JS1574 / 3	7 ELEVEN STORE 30467	10111 N LAMAR ST	TX RDR	136	0.026	ESE
JS1575 / 3	7-11	10111 N LAMAR	TX RDR	136	0.026	ESE
DR1576 / 11	G F DURDEN C	504 6TH E	EDR Hist Cleaner	136	0.026	NE
BW1577 / 11	KWIK WASH COIN LAUND	704 24TH ST W	EDR Hist Cleaner	136	0.026	East
HS1578 / 15	HEB 628	2512 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX Financi...	137	0.026	NE
HS1579 / 15	EXXON TIGERMART RS 6	2512 E RIVERSIDE DR	TX Ind. Haz Waste	137	0.026	NE
HS1580 / 15	EXXON #6-01033	2512 EAST RIVERSIDE	TX RDR	137	0.026	NE
HS1581 / 15	EXXON MOBIL CORPORAT	2512 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	137	0.026	NE
HS1582 / 15	EXXON MOBIL CORPORAT	2512 E RIVERSIDE DR	EDR Hist Auto	137	0.026	NE
IX1583 / 11	MAGNOLIA PETROLEUM	220 CONGRESS AVE S	EDR Hist Auto	137	0.026	WNW
IX1584 / 11	WILLIAMS MOTOR INC	200 S CONGRESS AVE	TX HIST UST	137	0.026	NNE
IX1585 / 11	W.A. STEPHENS	200 S CONGRESS AVE	TX HIST UST	137	0.026	NNE
IR1586 / 8	HYDE PARK GARAGE AUT	513 43RD W	EDR Hist Auto	138	0.026	SW
IR1587 / 8	HYDE PARK GARAGE AUT	513 43RD ST W	EDR Hist Auto	138	0.026	SW
IR1588 / 8	HYDE PARK GARAGE	513 43RD ST W	EDR Hist Auto	138	0.026	SW
DR1589 / 11	DOYLE DARBY TAILOR	506 6TH E	EDR Hist Cleaner	138	0.026	NE
DQ1590 / 11	C. O. LANDAHL	300 E 6TH ST	TX HIST UST	139	0.026	NNE
R1591 / 6	7-ELEVEN 25445	8900 N LAMAR	TX RDR	139	0.026	WNW
R1592 / 6	GRIFFS TEXACO SERVIC	8900 LAMAR BLVD N	EDR Hist Auto	139	0.026	WNW
R1593 / 6	7-ELEVEN 25445	8900 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	139	0.026	WNW
R1594 / 6	7 ELEVEN 25445	8900 N LAMAR	TX RDR	139	0.026	WNW
1595 / 14	STOP N SAVE 3	1800 BURTON DR	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	139	0.026	ENE
DP1596 / 11	CUNNINGHAM & VOSS	218 E 6TH ST	TX HIST UST	139	0.026	NNE
1597 / 15	WASHTUB & PUB COIN O	1717 PLEASANT VALLE	EDR Hist Cleaner	139	0.026	NE
CX1598 / 11	ALL-PRO CLEANERS INC	602 W 7TH ST	EDR Hist Cleaner	139	0.026	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DF1599 / 11	AUSTIN STEPHEN F HOT	102 7TH E	EDR Hist Cleaner	140	0.027	ESE
BW1600 / 11	AUSTIN LAUNDRY & DRY	608 W 24TH ST	EDR Hist Cleaner	140	0.027	East
DN1601 / 11	DANNY LITTLE	106 E 6TH STREET	TX RDR	140	0.027	NNE
DN1602 / 11	LITTLEFIELD DRISKILL	106 E 6TH ST	TX LPST, TX VCP, TX ASBESTOS, TX GCC	140	0.027	NNE
DN1603 / 11	LITTLEFIELD BUILDING	106 E 6TH ST	TX HIST UST	140	0.027	NNE
DN1604 / 11	LITTLEFIELD BLDING I	106 E 6TH ST	TX HIST UST	140	0.027	NNE
FT1605 / 14	BROWN & ELLIOTT INC	2326 S CONGRESS	EDR Hist Cleaner	140	0.027	WNW
IR1606 / 8	COPELAND GARAGE	514 43RD ST W	EDR Hist Auto	140	0.027	SW
IR1607 / 8	MURRAYS GAR AUTO	514 43RD W	EDR Hist Auto	140	0.027	SW
IR1608 / 8	HYDE PARK GARAGE	514 43RD ST W	EDR Hist Auto	140	0.027	SW
IX1609 / 11	J.V. SIEGMUND	228 S CONGRESS AVE	TX HIST UST	140	0.027	WNW
IX1610 / 11	LACKIE CONSTRUCTION	228 S CONGRESS AVE	TX HIST UST	140	0.027	WNW
1611 / 14	METROLOGY LABORATORY	119 CUMBERLAND RD	TX Ind. Haz Waste	140	0.027	NE
EE1612 / 11	ACME CLEANERS	320 1ST E	EDR Hist Cleaner	141	0.027	WNW
DA1613 / 11	AUSTIN LACQUER COMPA	604 W 6TH ST	EDR Hist Auto	141	0.027	ESE
DA1614 / 11	C VAN R AUTOMOTIVE	604 W 6TH ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	141	0.027	ESE
JI1615 / 11	GULF REFG CO STA NO	1811 CONGRESS AVE E	EDR Hist Auto	141	0.027	ESE
1616 / 11		422 E 6TH ST	TX HIST UST	141	0.027	SSW
DB1617 / 11	OHENRY GAR	110 8TH E	EDR Hist Auto	142	0.027	WNW
FJ1618 / 14	SPICK SPAN LAUNDRY	1421 ARENA DR	EDR Hist Cleaner	142	0.027	ENE
DF1619 / 11	CASH AND CARRY	111 7TH E	EDR Hist Cleaner	142	0.027	WNW
1620 / 14	A. E. SULLIVAN	400 W MONROE ST	TX HIST UST	142	0.027	WNW
JG1621 / 6	KWIK WASH LAUNDRY	718 LAMAR PL	EDR Hist Cleaner	142	0.027	ESE
JT1622 / 11	YOUNG & PRATT	702 E 3RD ST	TX UST, TX ASBESTOS	142	0.027	WNW
JT1623 / 11	C. G. PURYEAR	702 E 3RD ST	TX HIST UST	142	0.027	WNW
JT1624 / 11	YOUNG & PRATT	702 E 3RD ST	TX HIST UST	142	0.027	WNW
CZ1625 / 11	PAGE SOUTHERLAND PAG	606 WEST AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	142	0.027	WNW
DR1626 / 11	STEVENSON J C C DCLO	510 6TH E	EDR Hist Cleaner	143	0.027	NE
DR1627 / 11	AXLE & WHEEL ALIGN	510 6TH E	EDR Hist Auto	143	0.027	NE
DR1628 / 11	VACANT 2 CASTROS CLE	511 6TH ST E	EDR Hist Cleaner	143	0.027	NE
DC1629 / 11	803 05 DEPENDABLE MT	803 5TH W	EDR Hist Auto	143	0.027	WNW
DC1630 / 11	DEPENDABLE MOTORS IN	803 5TH ST W	EDR Hist Auto	143	0.027	WNW
1631 / 11	BOZEMAN & HAGOOD SER	1811 CONGRESS AVE	EDR Hist Auto	144	0.027	WNW
CO1632 / 11	AUSTIN COMMUNITY COL	1212 RIO GRANDE ST	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	144	0.027	WNW
JU1633 / 6	GUTHRIE CLEANERS	9200 N LAMAR BLVD ST	TX DRYCLEANERS	144	0.027	WNW
JU1634 / 6	GUTHRIES CLEANERS	9200 LAMAR BLVD N	EDR Hist Cleaner	144	0.027	WNW
IV1635 / 11	THE UNIVERSITY OF TE	2617 SPEEDWAY STE 10	TX SPILLS, TX Ind. Haz Waste	144	0.027	East
IV1636 / 11	THE UNIVERSITY OF TE	2617 SPEEDWAY STE 10	RCRA-LQG, PADS, NY MANIFEST	144	0.027	East
IV1637 / 11	MAIN CAMPUS	2617 SPEEDWAY STE 10	TX IHW CORR ACTION	144	0.027	East

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
JV1638 / 11	CITY OF AUSTIN	654 W CESAR CHAVEZ S	TX HIST UST	145	0.027	ENE
JV1639 / 11	COA	654 W CESAR CHAVEZ S	TX HIST UST	145	0.027	ENE
EJ1640 / 14	RIVERSIDE CHEVRON	400 S CONGRESS AVE	TX LPST, TX UST, TX ASBESTOS, TX Financi...	145	0.027	WNW
EJ1641 / 14	RIVERSIDE CHEVRON	400 SOUTH CONGRESS A	TX RDR	145	0.027	WNW
EJ1642 / 14	RIVERSIDE SHELLSHAPE	400 S CONGRESS	EDR Hist Auto	145	0.027	WNW
EJ1643 / 14	RIVERSIDE CHEVRON	400 S CONGRESS AVE	TX HIST UST	145	0.027	WNW
EJ1644 / 14	R.E. LEIGH	400 S CONGRESS AVE	TX HIST UST	145	0.027	WNW
JI1645 / 11	1801 03 DYE SLS & SE	1801 CONGRESS AVE	EDR Hist Auto	145	0.027	WNW
DR1646 / 11	GALVAN IGNACIO CLDO	512 6TH E	EDR Hist Cleaner	145	0.027	NE
DR1647 / 11	SHARPS SERVICE STA	512 6TH E	EDR Hist Auto	145	0.027	NE
IL1648 / 11	D & S SERVICE STATIO	500 7TH ST E	EDR Hist Auto	146	0.028	NNE
IL1649 / 11	D&S SERV STA	500 7TH E	EDR Hist Auto	146	0.028	NNE
IL1650 / 11	D & S SERVICE STATIO	500 7TH ST E	EDR Hist Auto	146	0.028	NNE
1651 / 3	MONTGOMERY WARD 2276	10600 N LAMAR BLVD	TX Ind. Haz Waste	146	0.028	WNW
IP1652 / 11	LUDWIG ROBERT W TAIL	402 E 6TH ST	EDR Hist Cleaner	146	0.028	NNE
BV1653 / 11	FERDINANDTSEN G E N	2406 GUADALUPE ST	EDR Hist Cleaner	146	0.028	West
DL1654 / 11	M.H. CROCKETT	306 W WEST 29TH ST	TX HIST UST	146	0.028	WNW
CV1655 / 11	BIGGS & CO TAILORS	1007 CONGRESS AVE E	EDR Hist Cleaner	146	0.028	ESE
DC1656 / 11	C.B. SMITH MOTORS	805 W 5TH ST	TX HIST UST	147	0.028	WNW
DC1657 / 11	AUSTIN TOYOTA	1127 W 6TH STREET	TX LPST, TX UST, TX VCP, RCRA NonGen / N...	147	0.028	WNW
DC1658 / 11	AUSTIN TOYOTA INC	805 W 5TH ST	TX HIST UST	147	0.028	WNW
DR1659 / 11	ATTAL THOS SHOE REPR	515 6TH E	EDR Hist Cleaner	147	0.028	NE
DA1660 / 11	COTHRAN'S TEXACO	700 W 6TH ST	TX HIST UST	147	0.028	ESE
CV1661 / 11	BIGGS & CO TAILOR	1007 CONGRESS AVE	EDR Hist Cleaner	147	0.028	WNW
CV1662 / 11	BOBS GARAGE &	1007 CONGRESS AVE	EDR Hist Auto	147	0.028	WNW
DA1663 / 11	DEEP EDDY RUG & CARP	512 RIO GRANDE ST	EDR Hist Cleaner	148	0.028	WNW
DA1664 / 11	SPRINKLES BODY SHOP	512 RIO GRANDE	EDR Hist Auto	148	0.028	WNW
DA1665 / 11	BEE BOP PRINTING	512 RIO GRANDE ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	148	0.028	WNW
DL1666 / 11	COA SERVICE CENTER #	300 WEST AVE	TX HIST UST	148	0.028	WNW
DL1667 / 11	ELECTRIC UTILITY	300 WEST AVE	TX LPST, TX Ind. Haz Waste	148	0.028	WNW
DL1668 / 11	POLE YARD	300 WEST AVE	RCRA NonGen / NLR, FINDS, ECHO	148	0.028	WNW
DL1669 / 11	AUSTIN ENERGY POLE Y	300 WEST AVE	TX VCP	148	0.028	WNW
DL1670 / 11	CITY OF AUSTIN ELECT	300 WEST AVE	TX UST	148	0.028	WNW
FY1671 / 14	TWIN OAKS PHILLIPS 6	620 E OLTORF	EDR Hist Auto	148	0.028	SE
IL1672 / 11	CAPITAL CITY MOTOR	505 7TH ST E	EDR Hist Auto	149	0.028	NNE
CM1673 / 11	FIRST STATE BANK TOW	400 W 15TH ST STE 71	TX UST, TX HIST UST	149	0.028	WNW
FO1674 / 14	CLOSED CAR WASH	1510 TOWN CREEK DR.	TX HIST UST	149	0.028	NE
CV1675 / 11	PEELER JOHN F TAILO	1003 CONGRESS AVE	EDR Hist Cleaner	149	0.028	WNW
JW1676 / 19	SPEEDY STOP 405	7715 E BEN WHITE	TX RDR	150	0.028	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
JW1677 / 19	EXXON MOBIL CORPORAT	7715 E BEN WHITE BLV	EDR Hist Auto	150	0.028	WNW
JW1678 / 19	7-ELEVEN STORE 36642	7715 E BEN WHITE BLV	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	150	0.028	WNW
DR1679 / 11	2 RODRIGUEZ JOS CLDO	517 6TH E	EDR Hist Cleaner	150	0.028	NE
DF1680 / 11	MASTER VALET CLNS	109 7TH E	EDR Hist Cleaner	151	0.029	WNW
DF1681 / 11	MASTER VALET CLEANER	109 7TH ST E	EDR Hist Cleaner	151	0.029	WNW
FU1682 / 14	CONTINENTAL OIL COMP	2336 S CONGRESS AVE	TX HIST UST	152	0.029	NW
FU1683 / 14	SOUTH AUSTIN CONOCO	2336 CONGRESS AVE	EDR Hist Auto	152	0.029	NW
DM1684 / 11	NOWLIN R A AUTO REPR	602 TRINITY ST	EDR Hist Auto	152	0.029	SSW
GX1685 / 18	NUZ FRANK GARAGE	4237 CONGRESS AVE S	EDR Hist Auto	152	0.029	ESE
GX1686 / 18	SUNDBECK GAR	4241 CONGRESS AVE	EDR Hist Auto	152	0.029	ESE
GX1687 / 18	SUNDBECK GARAGE	4241 CONGRESS AVE S	EDR Hist Auto	152	0.029	ESE
GX1688 / 18	SUNBECK AUTOMOTIVE	4241 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	152	0.029	ESE
IA1689 / 11	L & M GARAGE AUTO RE	301 BARTON SPRINGS R	EDR Hist Auto	152	0.029	NE
L1690 / 3	HILL ELECTRIC	10100 N LAMAR BLVD	TX UST, TX HIST UST	152	0.029	WNW
DE1691 / 11	SHIRLEY CLEANERS & H	310 W 6TH ST	EDR Hist Cleaner	153	0.029	ESE
CN1692 / 11	ROBERT E JOHNSON BUI	1501 CONGRESS AVE	TX UST, TX HIST UST	153	0.029	WNW
DB1693 / 11	108 10 12 HENRV GARA	108 8TH E	EDR Hist Auto	153	0.029	WNW
EM1694 / 14	CENTRAL TEXAS EQUIPM	127 E RIVERSIDE DR	TX LPST, TX UST, TX VCP, TX HIST UST	153	0.029	SW
JX1695 / 14	OSF CONGRESS	2701 S CONGRESS AVE	TX TANKS, TX HIST UST, TX CENTRAL REGIST...	154	0.029	NNE
JX1696 / 14	OSF CONGRESS LP	2701 S CONGRESS	TX RDR	154	0.029	NNE
GK1697 / 14	DALES AUTO PARTS & M	3600 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	155	0.029	WNW
GK1698 / 14	SIGMOR NUMBER 232 IN	3600 S CONGRESS AVE	EDR Hist Auto	155	0.029	WNW
GK1699 / 14	DALES AUTO PARTS & M	3600 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	155	0.029	WNW
CV1700 / 11	BARKER B M AUTOMO	105 10TH E	EDR Hist Auto	155	0.029	WNW
CN1701 / 11	TEXAS EMPLOYMENT COM	101 E 15TH ST	TX UST, TX HIST UST, TX ASBESTOS	156	0.030	ESE
DR1702 / 11	CENTRAL SEWING MACH	522 6TH E	EDR Hist Auto	156	0.030	NE
JY1703 / 11	CNANO TECHNOLOGY USA	303 COLORADO ST	FINDS, ECHO, PFAS ECHO	157	0.030	NNE
JQ1704 / 11	GRAYBURG OIL CO STAT	1601 CONGRESS AVE	EDR Hist Auto	157	0.030	WNW
DJ1705 / 11	ZUAUTO PARTS LLC	701 BRAZOS ST STE 72	EDR Hist Auto	157	0.030	NNE
JZ1706 / 17	7-ELEVEN 20079	6702 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	159	0.030	WNW
JZ1707 / 17	FORMER 7 ELEVEN STOR	6702 S CONGRESS AVE	TX LPST, TX GCC	159	0.030	WNW
JZ1708 / 17	FORMER 7 ELEVEN 2007	6702 CONGRESS AVE	TX RDR	159	0.030	WNW
IL1709 / 11	MARSHALL BODY WORKS	515 7TH E	EDR Hist Auto	159	0.030	NNE
DG1710 / 11	MILLER BRESTE	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1711 / 11	GRAYBURG OIL CO.	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1712 / 11		112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1713 / 11	SCOTT & GREGG	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1714 / 11	MILLERS GARAGE	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DR1715 / 11	ELLIS SERVICE STATIO	524 6TH E	EDR Hist Auto	160	0.030	NE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
1716 / 19	JD MARKET 5	7310 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	160	0.030	NE
DF1717 / 11	AUSTIN STEPH F HOTEL	106 7TH E	EDR Hist Cleaner	160	0.030	ESE
KA1718 / 14	BEVERAGE BARN	2001 E RIVERSIDE BLV	TX RDR	162	0.031	SW
KA1719 / 14	BEVERAGE BARN	2001 EAST RIVERSIDE	TX RDR	162	0.031	SW
KA1720 / 14	BEVERAGE BARN	2001 E RIVERSIDE	TX RDR	162	0.031	SW
KA1721 / 14	BEVERAGE BARN	2001 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	162	0.031	SW
KB1722 / 3	AUSTIN TENNYSON 836	11409 N LAMAR	TX RDR	162	0.031	ESE
KB1723 / 3	TENNYSON 836	11409 N LAMAR BLVD	TX UST, TX AST, TX HIST UST, TX Financia...	162	0.031	ESE
KB1724 / 3	SAME	11409 N LAMAR	TX RDR	162	0.031	ESE
DP1725 / 11	GRANT JAMES C CLNR	505 BRAZOS ST	EDR Hist Cleaner	162	0.031	SSW
1726 / 14	GOLDIE CORPORATION	3822 S CONGRESS AVE	EDR Hist Auto	163	0.031	WNW
IL1727 / 11	HAGOOD SERV STA	519 7TH E	EDR Hist Auto	163	0.031	NE
IL1728 / 11	HAGOOD SERVICE STATI	519 7TH ST E	EDR Hist Auto	163	0.031	NE
DV1729 / 11	AUS TEX ENGINE	304 COLORADO ST	EDR Hist Auto	163	0.031	NNE
DY1730 / 11	PACKERY CHANNEL BAIT	308 CONGRESS AVE STE	EDR Hist Auto	164	0.031	NNE
KC1731 / 11	CENTEX AUTO REPAIR	202 SAN JACINTO ST	EDR Hist Auto	165	0.031	SSW
IS1732 / 3	7 ELEVEN 38289	701 W BRAKER LN	TX UST, TX HIST UST, TX Financial Assura...	165	0.031	ESE
DG1733 / 11	LINZ NICK TAILOR	607 CONGRESS AVE	EDR Hist Cleaner	166	0.031	WSW
DD1734 / 11	UNITED STATES CLEANE	601 W 5TH ST	EDR Hist Cleaner	166	0.031	ESE
1735 / 11	QUALITY CLEANERS GR	111 E 19TH ST	EDR Hist Cleaner	166	0.031	West
1736 / 14	B & M AUTOMOTIVE AUT	511 LIVE OAK ST W	EDR Hist Auto	167	0.032	WNW
BH1737 / 8	TWENTY NINTH STREET	604 W 29TH ST	EDR Hist Cleaner	167	0.032	WNW
KD1738 / 14	SHELL MINI MART 2	3906 S CONGRESS AVE	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	168	0.032	WNW
KD1739 / 14	SHELL	3906 S CONGRESS AVE	TX RDR	168	0.032	WNW
KD1740 / 14	BISHOP GARY	3906 S CONGRESS AVE	EDR Hist Auto	168	0.032	WNW
KD1741 / 14	TEXACO SERVICE STATI	3906 S CONGRESS	TX RDR	168	0.032	WNW
1742 / 14	A & M TRAILER REPAIR	2702 SHERWOOD LN	EDR Hist Auto	168	0.032	SSE
DP1743 / 11	SAVE WAY SERV	503 BRAZOS	EDR Hist Auto	168	0.032	SSW
KE1744 / 14	STEWART DON A INC	3909 S CONGRESS AVE	EDR Hist Auto	168	0.032	ESE
KE1745 / 14	SOUTH CONGRESS CHEVR	3909 S CONGRESS AVE	TX HIST UST	168	0.032	ESE
KE1746 / 14	CONGRESS CHEVRON	3909 S CONGRESS AVE	TX UST, TX ASBESTOS, TX ENF, TX Financia...	168	0.032	ESE
KE1747 / 14	AUSTIN ARMATURE WORK	3909 S CONGRESS AVE	TX HIST UST	168	0.032	ESE
KF1748 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	169	0.032	ESE
KF1749 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	RCRA NonGen / NLR, FTTS, HIST FTTS, FIND...	169	0.032	ESE
KF1750 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	TX ASBESTOS, TX LEAD, TX Ind. Haz Waste,...	169	0.032	ESE
1751 / 14	RED BALL TAXI CO.	301 W RIVERSIDE DR	TX HIST UST	170	0.032	SW
JA1752 / 11	MILLNER BROS SERVICE	813 12TH W	EDR Hist Auto	170	0.032	WNW
1753 / 6	GREASERS	8415 N LAMAR BLVD	TX UST, TX HIST UST	170	0.032	SE
JP1754 / 11	NUNEZ BROS TAILORS	506 BRAZOS	EDR Hist Cleaner	170	0.032	SSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
KG1755 / 11	CONSUMERS HOME ICE C	361 W 4TH ST	TX HIST UST	170	0.032	ESE
KH1756 / 11	AUSTIN MOTOR INN	207 CONGRESS AVE	EDR Hist Auto	171	0.032	SSW
KH1757 / 11		207 CONGRESS	TX HIST UST	171	0.032	SSW
KI1758 / 2	EXXON MOBIL CORPORAT	1100 W PARMER LN	EDR Hist Auto	173	0.033	West
KI1759 / 2	EXXON RAS NO 60117	1100 W PARMER	RCRA NonGen / NLR, FINDS, ECHO	173	0.033	West
KI1760 / 2	7-ELEVEN STORE 36588	1100 W PARMER LN	TX UST, TX HIST UST, TX ASBESTOS, TX ED ...	173	0.033	West
1761 / 11	JAMES DREW RENTAL IN	408 N I 35	TX HIST UST	173	0.033	East
Q1762 / 6	SAFETY RIDE CAR CARE	9307 LAMAR BLVD N	EDR Hist Auto	173	0.033	ESE
GO1763 / 14	DOCS SMALL ENGINE RE	104 KREBS LN	EDR Hist Auto	174	0.033	WNW
1764 / 11	ACC RIO GRANDE CAMPU	1218 WEST AVE.	TX HIST UST	174	0.033	WNW
DC1765 / 11	BELL JIM GARAGE AUTO	811 5TH ST W	EDR Hist Auto	174	0.033	WNW
1766 / 11	AUSTIN MUSIC HALL	208 NUECES ST	TX HIST UST, TX RDR	175	0.033	East
DF1767 / 11	MAJIK IRONERS INC	114 W 7TH ST	EDR Hist Cleaner	175	0.033	WNW
DP1768 / 11	VACANT PROPERTY BRAZ	501 BRAZOS ST	TX RDR	175	0.033	SSW
DP1769 / 11	BRADSHAW ED SERV	501 BRAZOS	EDR Hist Auto	175	0.033	SSW
DP1770 / 11	FORMER BANK DRIVE TH	501 BRAZOS	TX RDR	175	0.033	SSW
DP1771 / 11	5TH AND BRAZOS TOWER	501 BRAZOS ST	TX IHW CORR ACTION	175	0.033	SSW
DP1772 / 11	VACANT PROPERTY	501 BRAZOS ST	TX UST, TX HIST UST	175	0.033	SSW
KJ1773 / 11	CITY HALL ANNEX BLOC	UNKNOWN	US BROWNFIELDS, FINDS	176	0.033	ESE
DQ1774 / 11	AUSTIN BRAKE	506 TRINITY ST	EDR Hist Auto	176	0.033	SSW
DQ1775 / 11	DEAN MILLER	506 E TRINITY ST	TX HIST UST	176	0.033	SSW
JC1776 / 11	DIXIE OIL COMPANY	407 W CESAR CHAVEZ S	TX HIST UST	176	0.033	NE
1777 / 6	WILKERSON TRUCK LINE	6613 N LAMAR BLVD	TX HIST UST	176	0.033	ESE
KJ1778 / 11	COA - ANNEX	301 W 2ND ST	TX HIST UST	177	0.034	ESE
KJ1779 / 11	CITY OF AUSTIN EME|S	301 WEST 2ND STREET	TX HIST UST, TX ASBESTOS	177	0.034	ESE
1780 / 11	DUKES GAR REPRS	406 RED RIVER	EDR Hist Auto	177	0.034	WSW
CN1781 / 11	TEXAS HOUSE OF REPRE	105 W 15TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	177	0.034	WNW
KK1782 / 17	CIRCLE K STORES INC	4619 S CONGRESS AVE	EDR Hist Auto	178	0.034	ESE
KK1783 / 17	ALL STAR GROCERY 1	4619 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	178	0.034	ESE
KL1784 / 11	SOUTHWESTERN BELL TE	120 W 9TH ST	TX HIST UST	178	0.034	WNW
KL1785 / 11	SOUTHWESTERN BELL TE	120 W 9TH ST	TX HIST UST	178	0.034	WNW
DY1786 / 11	PARSLEY W L DCLO CLN	310 CONGRESS AVE	EDR Hist Cleaner	179	0.034	NNE
KM1787 / 6	NORTH LAMAR QUICK ST	8545 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	179	0.034	SE
KM1788 / 6	SIGMOR SHAMROCK SERV	8545 LAMAR BLVD N	EDR Hist Auto	179	0.034	SE
1789 / 14	TEXAS PEST CONTROL	3510 CONGRESS AVE	EDR Hist Cleaner	179	0.034	WNW
1790 / 11	ROBERT HATCHETT	1004 W WEST 24TH ST	TX HIST UST	180	0.034	WNW
DJ1791 / 11	704 6 BUSTIN MC CUTC	704 BRAZOS ST	EDR Hist Auto	180	0.034	NNE
1792 / 20	GPM STORE 4567	2001 BASTROP HWY E	TX LPST, TX UST, TX Financial Assurance,...	180	0.034	NNE
IL1793 / 11	EWINGS CONOCO SERVIC	519 E 7TH ST	EDR Hist Auto	181	0.034	NE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
IL1794 / 11	MERCHANTS TRANSFER S	519 E 7TH ST	TX HIST UST	181	0.034	NE
IL1795 / 11	TWIN LIQUORS	519 E 7TH ST	TX UST	181	0.034	NE
IL1796 / 11	TWIN LIQUORS	519 E 7TH ST	TX RDR, TX CENTRAL REGISTRY	181	0.034	NE
IL1797 / 11	F. W. STERNENBERG	519 E 7TH ST	TX HIST UST	181	0.034	NE
IL1798 / 11	TWIN LIQUORS	519 E 7TH ST	TX HIST UST	181	0.034	NE
DU1799 / 11	JOHNSON J W SERVICE	510 5TH ST E	EDR Hist Auto	181	0.034	SW
DU1800 / 11	CUNNINGHAM GEO L FIL	510 5TH E	EDR Hist Auto	181	0.034	SW
DU1801 / 11	CUNNINGHAM G L	510 5TH ST E	EDR Hist Auto	181	0.034	SW
KN1802 / 14	BEN HIBBETTS	1725 E RIVERSIDE DR	TX UST	183	0.035	WSW
1803 / 3	NORTH LAMAR SAFTI BR	701 PROVINES DR STE	TX Ind. Haz Waste	183	0.035	ESE
JR1804 / 3	AUSTIN KAWASKI	10426 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	184	0.035	WNW
JR1805 / 3	AUSTIN KAWASAKI	10426 LAMAR BLVD N	EDR Hist Auto	184	0.035	WNW
JR1806 / 3	UNDELIVERABLE	10426 N LAMAR BLVD	TX Ind. Haz Waste	184	0.035	WNW
BG1807 / 8	DRY CIN VILLAGE	604 29TH W	EDR Hist Cleaner	184	0.035	WNW
1808 / 11	AMERICAN TAXI CAB CO	408 W 11TH ST	TX HIST UST	184	0.035	WNW
BG1809 / 8	MASTER DICKENS CLEAN	604 29TH ST W	EDR Hist Cleaner	185	0.035	WNW
DU1810 / 11	HART BUBBA SERVICE S	509 5TH E	EDR Hist Auto	185	0.035	SW
DU1811 / 11	JOHNSONS SERVICE STA	508 5TH E	EDR Hist Auto	185	0.035	SW
KH1812 / 11	WALKER J M CLDO CLNR	208 CONGRESS AVE	EDR Hist Cleaner	187	0.035	SSW
AD1813 / 6	B & M DISCOUNT TRANS	808 JUSTIN LN	EDR Hist Auto	187	0.035	WNW
BK1814 / 11	A MASTER DICKENS CLE	2815 FRUTH ST	EDR Hist Cleaner	188	0.036	ENE
BK1815 / 11	ANN STUMPF	2815 FRUTH ST	TX UST, TX HIST UST	188	0.036	ENE
KO1816 / 9	J.E. RICKS	6215 N LAMAR BLVD	TX HIST UST	188	0.036	ESE
KO1817 / 9	T JS CYCLE SALES & S	6215 LAMAR BLVD N	EDR Hist Auto	188	0.036	ESE
KP1818 / 11	GULF REFG CO STA NO	507 5TH ST E	EDR Hist Auto	188	0.036	SW
KP1819 / 11	HALEY MALCOLM M FILL	507 5TH E	EDR Hist Auto	188	0.036	SW
KN1820 / 14	PARKER LN AND RIVERS	PARKER LN AND RIVERS	TX CLI	189	0.036	WSW
KN1821 / 14	PARKER LN & RIVERSID		TX CLI	189	0.036	WSW
KN1822 / 14	PARKER LN & RIVERSID		TX HIST LF	189	0.036	WSW
JX1823 / 14	BILL KASSON MOTORCYC	2603 S CONGRESS AVE	TX HIST UST, TX ASBESTOS	189	0.036	SE
KH1824 / 11	AUSTIN RADIATOR CO	205 CONGRESS AVE	EDR Hist Auto	189	0.036	SSW
JA1825 / 11	HUMBLE OIL & REFG	816 12TH W	EDR Hist Auto	190	0.036	WNW
1826 / 11	HOME STEAM LAUNDRY	601 E 14TH ST	EDR Hist Cleaner	191	0.036	ESE
DE1827 / 11	POLAR ICE CREAM	417 W 6TH ST	TX HIST UST	191	0.036	WNW
KQ1828 / 11	VACANT BUILDING	701 E 6TH ST	TX LPST	192	0.036	ENE
DI1829 / 11	B&N AXLE SERV	314 5TH W	EDR Hist Auto	193	0.037	ESE
CZ1830 / 11	ME MORRIS FORD INCOR	808 6TH ST W	EDR Hist Auto	193	0.037	WNW
CZ1831 / 11	MC MORRIS FORD INCOR	808 6TH ST W	EDR Hist Auto	193	0.037	WNW
1832 / 11	JENSENS HARRY AUTO R	408 E 7TH ST	EDR Hist Auto	194	0.037	NNE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
1833 / 8	FRANKS FIX IT	4214 AVENUE A	EDR Hist Auto	194	0.037	SW
IC1834 / 8	FRANK HUNT PROPERTY	605 W 37TH ST	TX RDR	195	0.037	WNW
IC1835 / 8	FURNITURE REJUVENATI	605 W 37TH ST	TX HIST UST	195	0.037	WNW
IC1836 / 8	FURNITURE REJUVENATO	605 W 37TH ST	TX LPST, TX TANKS, TX GCC	195	0.037	WNW
IC1837 / 8	ERNEST M. DURBIN	605 W 37TH ST	TX HIST UST	195	0.037	WNW
KR1838 / 11	GULF OIL CORPORATION	601 W 6TH ST	TX HIST UST	197	0.037	ESE
KS1839 / 11	PEARL LAUNDRY	401 1ST E	EDR Hist Cleaner	197	0.037	ESE
KS1840 / 11	REDDS HUMBLE SERV FI	401 1ST E	EDR Hist Auto	197	0.037	ESE
KT1841 / 11	AUSTIN MUNICIPAL BUI	124 W 8TH ST	TX UST, TX HIST UST	197	0.037	WNW
KU1842 / 11	OSCAR KUNTZ?	800 E CESAR CHAVEZ S	TX HIST UST	197	0.037	ESE
AM1843 / 8	GREAT HALL GAMES	5501 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	197	0.037	ESE
DI1844 / 11	MISSION CITY PONTIAC	312 5TH W	EDR Hist Auto	197	0.037	ESE
FU1845 / 14	FAMILY DOLLAR #3834	118 E. OLTORF ST	RCRA-VSQG	198	0.038	SE
KP1846 / 11	SMITH B C TIRE SHOP	500 5TH ST E	EDR Hist Auto	198	0.038	SW
KP1847 / 11	WALLACE GARAGE AUTO	500 5TH E	EDR Hist Auto	198	0.038	SW
IT1848 / 8	BALCARS HUMBLE	4501 GUADALUPE ST	EDR Hist Auto	199	0.038	ESE
GS1849 / 14	EXXON MOBIL CORPORAT	201 W BEN WHITE BLVD	EDR Hist Auto	199	0.038	WNW
GS1850 / 14	7-ELEVEN STORE 36591	201 W BEN WHITE BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	199	0.038	WNW
GS1851 / 14	7-ELEVEN STORE 36591	201 W BEN WHITE	RCRA NonGen / NLR, FINDS, ECHO	199	0.038	WNW
JA1852 / 11	ACC BOOK STORE	801 W 12TH ST	TX LPST, TX UST	199	0.038	WNW
JA1853 / 11	W.T. CASWELL	801 W 12TH ST	TX HIST UST	199	0.038	WNW
JA1854 / 11	LANE AUTO & ELECTRIC	801 12TH ST W	EDR Hist Auto	199	0.038	WNW
JA1855 / 11	BILL'S ACC BOOKSTORE	801 W 12TH ST	TX HIST UST	199	0.038	WNW
U1856 / 6	BUSKES GARAGE	8609 LAMAR BLVD	EDR Hist Auto	200	0.038	SE
KR1857 / 11	FICKELS SERV STA	617 6TH W	EDR Hist Auto	201	0.038	ESE
KV1858 / 3	IMPORT CAR REPAIR	10631 LAMAR BLVD N	EDR Hist Auto	202	0.038	ESE
KV1859 / 3	IMPORT CAR REPAIR	10631 N LAMAR	TX RDR	202	0.038	ESE
KV1860 / 3	IMPORT CAR REPAIR	10631 N LAMAR BLVD	TX UST, TX HIST UST, TX Ind. Haz Waste, ...	202	0.038	ESE
1861 / 14	GEORGES WAGON WORKS	1311 S 1ST ST	TX UST, TX HIST UST	202	0.038	WNW
KW1862 / 11	PERRY BROOKS BLDG	720 BRAZOS ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	203	0.038	ESE
BE1863 / 8	31ST ST GARAGE	609 W 31ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	204	0.039	WNW
BE1864 / 8	CARLSONS GARAGE	609 31ST ST W	EDR Hist Auto	204	0.039	WNW
KX1865 / 14	7 ELEVEN STORE 19097	1705 S LAKESHORE BLV	TX RDR, TX CENTRAL REGISTRY	204	0.039	ENE
KX1866 / 14	7-ELEVEN 19097	1705 S LAKESHORE BLV	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	204	0.039	ENE
KX1867 / 14	7 ELEVEN STORE NO 19	1705 S LAKESHORE BLV	TX RDR	204	0.039	ENE
1868 / 2	FIRST NATIONAL BANK	12800 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	204	0.039	West
KY1869 / 11	HAMS AUTO SERV	310 5TH W	EDR Hist Auto	204	0.039	ESE
KW1870 / 11	WILLIE FOO CHINESE L	113 E 8TH ST	EDR Hist Cleaner	205	0.039	ESE
JP1871 / 11	FOSTERS GARAGE	504 BRAZOS ST	EDR Hist Auto	205	0.039	SSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
KZ1872 / 14	WALTER JOHNSON	1207 S 1ST ST	TX HIST UST	206	0.039	WNW
KH1873 / 11	206-214 CONGRESS AVE	206 CONGRESS AVE	TX UST, TX HIST UST	206	0.039	SSW
KH1874 / 11	FORMER RTC PROPERTY	206 CONGRESS AVE	TX LPST	206	0.039	SSW
HA1875 / 17	A 1 AUTO ELECTRIC AU	4408 CONGRESS AVE S	EDR Hist Auto	206	0.039	WNW
LA1876 / 11	COMPTROLLER OF PUBLI	111 W 6TH ST	TX Ind. Haz Waste	207	0.039	West
LA1877 / 11	COMPTROLLER OF PUBLI	111 W 6TH ST	RCRA NonGen / NLR, FINDS, ECHO	207	0.039	West
LB1878 / 11	SUPERIOR DAIRIES	600 E 1ST ST	TX LPST, TX UST, TX HIST UST	207	0.039	WNW
LB1879 / 11	FAIRMONT HOTEL	600 E CESAR CHAVEZ S	TX HIST UST, TX RDR	207	0.039	WNW
KU1880 / 11	HOWARDS CLEANERS	804 1ST E	EDR Hist Cleaner	208	0.039	ESE
KR1881 / 11	MAGNOLIA PET CO STA	615 6TH W	EDR Hist Auto	208	0.039	ESE
LC1882 / 11	TEXAS STATE ASSO OF	1000 BRAZOS ST	TX UST, TX HIST UST	209	0.040	ESE
LD1883 / 14	DIAMOND SHAMROCK 207	628 E OLTROF	TX RDR	210	0.040	SE
LD1884 / 14	DIAMOND SHAMROCK 207	628 E OLTORF ST	TX LPST, TX ASBESTOS, TX ENF, TX Financi...	210	0.040	SE
LD1885 / 14	VALERO ENERGY STATIO	628 E OLTORF ST	EDR Hist Auto	210	0.040	SE
LD1886 / 14	QUAD FOOD MART	628 E OLTORF ST	TX UST, TX HIST UST, TX ASBESTOS	210	0.040	SE
JA1887 / 11	SMITH J B	821 12TH W	EDR Hist Cleaner	210	0.040	WNW
JG1888 / 6	AMMOCO TRANSMISSIONS	712 LAMAR PL	TX HIST UST	211	0.040	ESE
IB1889 / 8	DALES AUTO PARTS	602 W 34TH ST	TX Ind. Haz Waste	211	0.040	WNW
FM1890 / 14	AUSTIN NURSING & CON	110 E LIVE OAK	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	212	0.040	ESE
JY1891 / 11	AUS TEX AUTOMOTIVE S	308 COLORADO ST	EDR Hist Auto	213	0.040	NNE
AI1892 / 6	JIMS BODY SHOP	6324 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	213	0.040	WNW
AI1893 / 6	A CAR 4 YOU INC	6324 N LAMAR BLVD	EDR Hist Auto	213	0.040	WNW
AI1894 / 6	JIMS BODY SHOP	6324 N LAMAR BLVD	TX HIST UST, TX ASBESTOS, TX Ind. Haz Wa...	213	0.040	WNW
LE1895 / 11	TURK EQUIPMENT	400 NUECES ST	TX UST	213	0.040	ESE
LF1896 / 11	JACK BROWN CLEANERS	615 W MARTIN LUTHER	RCRA-SQG	214	0.041	East
LF1897 / 11	JACK BROWN CLEANERS	615 W MARTIN LUTHER	TX VCP, TX APAR, TX DRYCLEANERS, TX GCC,...	214	0.041	East
LF1898 / 11	BROWN JACK CLEANERS	615 W MLK BLVD	EDR Hist Cleaner	214	0.041	East
J1899 / 3	TRAN RICHMOND	10800 N LAMAR BLVD	EDR Hist Auto	214	0.041	WNW
1900 / 11	CHAMPION PROPERTIES	UNKNOWN	US BROWNFIELDS, FINDS	215	0.041	WNW
LG1901 / 11	CVS PHARMACY 7483	500 CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	216	0.041	SSW
LG1902 / 11	CVS PHARMACY 7483	500 500 CONGRESS AVE	RCRA NonGen / NLR	216	0.041	SSW
LH1903 / 11	FOUND ON SANBORN MAP	318 E 5TH ST	TX HIST UST	216	0.041	SSW
LI1904 / 11	MRS. ROBT. W. SHIPP	303 W MARTIN LUTHER	TX HIST UST	216	0.041	East
1905 / 14	ORTEGON AUTO BODY RE	111 E WOODWARD ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	217	0.041	ESE
1906 / 19	ALLMANS GROCERY & SE	7207 E RIVERSIDE	EDR Hist Auto	218	0.041	SW
KY1907 / 11	AUSTIN WELDIN E	304 5TH ST W	EDR Hist Auto	218	0.041	ESE
KY1908 / 11	CLYDES WIDG	304 5TH W	EDR Hist Auto	218	0.041	ESE
LJ1909 / 3	ZADAS AUTOMOTIVE & C	816 KRAMER LN	EDR Hist Auto	218	0.041	WNW
LA1910 / 11	H. C. FRISTOE	121 W 6TH ST	TX HIST UST	218	0.041	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
LK1911 / 11	AMERICAN TAXI CAB CO	305 W 6TH ST	TX HIST UST	221	0.042	ESE
JA1912 / 11	TYLER F A FILL STA	823 12TH W	EDR Hist Auto	222	0.042	WNW
KR1913 / 11	REYES CLNRS	611 6TH W	EDR Hist Cleaner	222	0.042	ESE
1914 / 14	LUCAS GULF STATION	1221 INTERREGIONAL H	EDR Hist Auto	223	0.042	NE
1915 / 8	CARLSONS GARAGE AUTO	609 31ST W	EDR Hist Auto	224	0.042	WNW
LL1916 / 17	7-ELEVEN STORE 38608	105 E STASSNEY LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	224	0.042	ESE
LL1917 / 17	QMART STASSNEY	105 E STASSNEY	TX RDR	224	0.042	ESE
KY1918 / 11	MARTIN DELL BRAKE	302 5TH W	EDR Hist Auto	225	0.043	ESE
BH1919 / 8	CONVENIENCE COIN LAU	606 29TH ST W	EDR Hist Cleaner	227	0.043	WNW
BH1920 / 8	CONVENIENCE COIN LAU	606 W 29TH ST	EDR Hist Cleaner	227	0.043	WNW
BH1921 / 8	GUADALUPE LAUNDROMAT	606 29TH W	EDR Hist Cleaner	228	0.043	WNW
IL1922 / 11	ALEX & IDA DOCHEN TR	500 E 7TH ST	TX UST	229	0.043	NNE
IL1923 / 11	D&S	500 E 7TH ST	TX HIST UST	229	0.043	NNE
IL1924 / 11	D & S SERVICE STATIO	500 E 7TH ST	EDR Hist Auto	229	0.043	NNE
IL1925 / 11	ALEX DOCHEN	500 E 7TH ST	TX HIST UST	229	0.043	NNE
IL1926 / 11	ALEX DOCHEN	500 E 7TH ST	TX HIST UST	229	0.043	NNE
KY1927 / 11	BADGER WALTER H JR F	300 5TH W	EDR Hist Auto	229	0.043	ESE
HY1928 / 11	RREEF HEMPHILL PARK	2810 HEMPHILL PARK	TX LPST, TX GCC	230	0.044	ENE
HY1929 / 11	2810 HEMPHILL	2810 HEMPHILL PK	TX RDR	230	0.044	ENE
KH1930 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX CLI	231	0.044	SSW
KH1931 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX HIST LF	231	0.044	SSW
KH1932 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX CLI	231	0.044	SSW
1933 / 14	ASTRO CLEANERS	1900 E RIVERSIDE DR	EDR Hist Cleaner	231	0.044	ENE
LM1934 / 8	HOMESTEAD 451 CENTRA	817 N LOOP	TX RDR	232	0.044	WNW
LH1935 / 11	CADILLAC SALES COMPA	304 E 5TH ST	TX HIST UST	232	0.044	SSW
LH1936 / 11	DEEN MILLER	324 E 5TH ST	TX HIST UST	232	0.044	SSW
JA1937 / 11	AUSTIN COMMUNITY COL	800 W 12TH STREET	TX HIST UST, TX ASBESTOS	233	0.044	WNW
JA1938 / 11	GRIFFIN A C HUMBLE	800 W 12TH ST	EDR Hist Auto	233	0.044	WNW
JA1939 / 11	HUMBLE OIL & REFININ	800 W 12TH ST	TX HIST UST	233	0.044	WNW
LN1940 / 6	LUCKY CLEANERS	7601 N LAMAR BLVD ST	EDR Hist Cleaner	234	0.044	ESE
LN1941 / 6	LUCKY CLEANERS	7601 N LAMAR BLVD ST	TX DRYCLEANERS	234	0.044	ESE
1942 / 11	CUNNINGHAM HENRY	403 16TH ST E	EDR Hist Auto	235	0.045	WNW
LO1943 / 8	TRANS TECH AUTOMOTIV	805 CAPITOL ST	EDR Hist Auto	235	0.045	WNW
LP1944 / 17	CONGRESS EXXON	6721 S CONGRESS AVE	EDR Hist Auto	236	0.045	ESE
LP1945 / 17	EXXON 6-9404	6721 S CONGRESS	TX RDR	236	0.045	ESE
LP1946 / 17	EXXON RS 69404	6721 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	236	0.045	ESE
LP1947 / 17	EXXON MOBIL CORPORAT	6721 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	236	0.045	ESE
LP1948 / 17	EXXON RSL 69404	6721 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	236	0.045	ESE
LI1949 / 11	RITTERS SERVICE STAT	301 W 19TH ST	EDR Hist Auto	236	0.045	East

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
JY1950 / 11	CAPITOL SPRING & BRA	310 COLORADO ST	EDR Hist Auto	237	0.045	NNE
1951 / 11	CPCG AUTO TX LP	408 W 17TH ST OFC 10	EDR Hist Auto	238	0.045	WNW
1952 / 15	ROAD RUNNERS COMMERC	1511 FARO DR	EDR Hist Cleaner	239	0.045	NNE
KX1953 / 14	MARIES TAILOR SHOP	1708 S LAKESHORE BLV	EDR Hist Cleaner	239	0.045	ENE
DD1954 / 11	KEESES ENCO PRODUCTS	600 W 5TH	EDR Hist Auto	240	0.045	ESE
DD1955 / 11	HORIZON BANK - 600 W	600 W 5TH ST	TX HIST UST, TX CENTRAL REGISTRY	240	0.045	ESE
LE1956 / 11	NW COR WEAVER MARGT	612 4TH W	EDR Hist Cleaner	240	0.045	ESE
1957 / 19	CAPITOL TRANSMISSION	7401 RIVERSIDE DR E	EDR Hist Auto	241	0.046	SW
1958 / 11	BELL JIM AUTOS INC	201 BRAZOS ST	EDR Hist Auto	241	0.046	SSW
LQ1959 / 14	M. H. CROCKETT	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1960 / 14	C.A. MAUFRAIS	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1961 / 14	METCALF L A SERVICE	300 S CONGRESS	EDR Hist Auto	241	0.046	NE
LQ1962 / 14	MAGNOLIA PETROLEUM C	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1963 / 14	A.E. SCHUTZE	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1964 / 14	J.H. STELFOX	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LM1965 / 8	AT&T SOC XU3382	819 N LOOP W	TX RDR	241	0.046	WNW
1966 / 6	WESTERN AUTO	9316 N LAMAR BLVD	TX LPST, TX UST	241	0.046	WNW
LR1967 / 6	F M PAULS CONCRETE C	6506 SHIRLEY AVE	TX UST, TX HIST UST	241	0.046	ESE
LS1968 / 11	COMMUNICATION SPECIA	603 DAVIS ST	TX Ind. Haz Waste	242	0.046	WNW
LS1969 / 11	COMMUNICATION SPECIA	603 DAVIS ST	RCRA NonGen / NLR, FINDS, ECHO	242	0.046	WNW
JA1970 / 11	MILLNERS SERVICE STA	827 12TH W	EDR Hist Auto	242	0.046	WNW
1971 / 6	CHAMBERLAIN S M GARA	7209 LAMAR BLVD N	EDR Hist Auto	242	0.046	ESE
JE1972 / 11	MC KEAN W L R	1610 BRAZOS ST	EDR Hist Auto	243	0.046	ESE
CZ1973 / 11	OLD HUTS HAMBURGERS	807 WEST 6TH STREET	TX HIST UST, TX ASBESTOS	244	0.046	WNW
KR1974 / 11	RIVER CITY Z SHOP AU	604 6TH ST W	EDR Hist Auto	244	0.046	ESE
KR1975 / 11	PIT SHOP THE AUTO RE	604 6TH ST W	EDR Hist Auto	244	0.046	ESE
LO1976 / 8	TEXAS GLASS	808 CAPITOL CT	EDR Hist Auto	244	0.046	WNW
KH1977 / 11	FRY JOHN L CLOTHES	202 CONGRESS AVE	EDR Hist Cleaner	245	0.046	SSW
IZ1978 / 6	AUSTEX INTERIORS	6910 SHIRLEY AVE	TX UST, TX HIST UST	245	0.046	ESE
KS1979 / 11	SIMPSON IRA AUTO	409 1ST E	EDR Hist Auto	245	0.046	ESE
LT1980 / 11	AUSTIN LAUNDRY & DRY	304 W 15TH ST	TX HIST UST	246	0.047	ESE
1981 / 6	BRODIE MARKET INC	812 THURMOND ST	EDR Hist Auto	246	0.047	NW
LS1982 / 11	TRAMMELL CROW DAVIS	602 DAVIS ST	TX IHW CORR ACTION	246	0.047	WNW
LU1983 / 8	TUXEDO JUNCTION CLEA	611 W 29TH ST	EDR Hist Cleaner	246	0.047	WNW
ED1984 / 11	U T SUPERIOR DAIRIES	213 RED RIVER ST	TX HIST UST	246	0.047	WNW
LV1985 / 8	SPEEDWAY SER STA	3706 SPEEDWAY	EDR Hist Auto	246	0.047	ESE
LV1986 / 8	FORMER STATION	3706 SPEEDWAY	TX RDR	246	0.047	ESE
LW1987 / 14	STOCKTON J F	1501 S 1ST ST	EDR Hist Auto	247	0.047	WNW
1988 / 19	UNIVERSITY WRECKER	2114 MAXWELL LN	EDR Hist Auto	247	0.047	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
KW1989 / 11	ARMY FUTURES COMMAND		DOD	247	0.047	NNE
1990 / 11	KXAN-TV	910 BRAZOS ST	TX HIST UST	249	0.047	ESE
KW1991 / 11	GULF STATES POWER LT	800 BRAZOS ST STE 40	EDR Hist Auto	249	0.047	ESE
1992 / 15	AMERICAN CLEANERS	1717 S PLEASANT VALL	TX DRYCLEANERS	250	0.047	SW
1993 / 6	NISHIO INTERNATIONAL	8610 N LAMAR STE 101	EDR Hist Cleaner	250	0.047	NW
LX1994 / 11	RUSHINGS SYLVAN W EN	800 W 6TH ST	EDR Hist Auto	251	0.048	WNW
LX1995 / 11	CHARLTON & CROCKET,	800 W 6TH ST	TX HIST UST	251	0.048	WNW
LX1996 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX HIST UST	251	0.048	WNW
LX1997 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX UST	251	0.048	WNW
LX1998 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX RDR, TX CENTRAL REGISTRY	251	0.048	WNW
LY1999 / 14	CRANE & LOCK SERV	344 CONGRESS AVE S	EDR Hist Auto	253	0.048	NE
LY2000 / 14	BESHEARS C A TEXACO	344 S CONGRESS	EDR Hist Auto	253	0.048	NE
LY2001 / 14	LOCK SERVICE STA FIL	344 CONGRESS AVE S	EDR Hist Auto	253	0.048	NE
LX2002 / 11	RUSHINGS SYLVAN W EX	800 6TH ST W	EDR Hist Auto	254	0.048	WNW
LX2003 / 11	RUSHINGS SYLVAN W EN	800 6TH ST W	EDR Hist Auto	254	0.048	WNW
LX2004 / 11	HUMBLE OIL & REF CO	800 6TH W	EDR Hist Auto	254	0.048	WNW
LR2005 / 6	PARAGON PRINTING & M	706 BRENTWOOD ST STE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	254	0.048	ESE
LZ2006 / 17	STOP N GO MARKET 210	111 W WILLIAM CANNON	TX LPST, TX UST, TX HIST UST	255	0.048	WNW
LZ2007 / 17	CLASSY CLEANERS SOUT	111 W WILLIAM CANNON	TX Ind. Haz Waste	255	0.048	WNW
LZ2008 / 17	CLASSY CLEANERS INC	111 W WILLIAM CANNON	RCRA NonGen / NLR, FINDS, ECHO	255	0.048	WNW
LZ2009 / 17	TQS	111 W WILLIAM CANNON	TX Ind. Haz Waste	255	0.048	WNW
LZ2010 / 17	BRAKE SPECIALIST INC	111 W WILLIAM CANNON	EDR Hist Auto	255	0.048	WNW
MA2011 / 11	200 24 AVENUE SERVIC	200 CONGRESS AVE E	EDR Hist Auto	255	0.048	SSW
2012 / 11	MEYER CREAMERY COMPA	311 W 7TH ST	TX HIST UST	256	0.048	ESE
MB2013 / 14	1601 S 1ST ST	1601 S 1ST ST	TX UST	257	0.049	WNW
MB2014 / 14	J. H. JOHNSON	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2015 / 14	AUTO-FROST	1601 S 1ST ST	EDR Hist Auto	257	0.049	WNW
MB2016 / 14	LEWIS SCHNELL	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2017 / 14	LEWIS SCHNELL	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2018 / 14	EAGLE BODY SHOP	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
KR2019 / 11	RUCKER CASS GULF SER	601 6TH W	EDR Hist Auto	258	0.049	ESE
IL2020 / 11	GULF OIL CORPORATION	504 E 7TH ST	TX HIST UST	259	0.049	NE
LO2021 / 8	FRENCH REVOLUTION AU	807 CAPITOL ST	EDR Hist Auto	260	0.049	WNW
MC2022 / 14	STRUTS CLEANERS	1106 S 1ST ST 1106-1	RCRA NonGen / NLR	261	0.049	WNW
MC2023 / 14	STRUTS CLEANERS	1106 S 1ST ST	TX Ind. Haz Waste	261	0.049	WNW
MD2024 / 8	KINSEYS AUTOMOTIVE	819 HOUSTON ST	EDR Hist Auto	262	0.050	WNW
MD2025 / 8	AUSTIN PAN AM CHEMIC	819 HOUSTON ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	262	0.050	WNW
JY2026 / 11	0 K GARAGE	312 COLORADO ST	EDR Hist Auto	262	0.050	NNE
ME2027 / 11	B&N AXLE SERV	219 W 4TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	263	0.050	NNE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
ME2028 / 11	B&N AXLE SERV INC	219 W 4TH ST	RCRA NonGen / NLR, FINDS, ECHO	263	0.050	NNE
MF2029 / 14	STOP N GO 2126	1516 TINNIN FORD RD	TX UST, TX HIST UST, TX Financial Assura...	263	0.050	NE
MF2030 / 14	DIAMOND SHAMROCK 212	1516 TINNIN FORD RD	TX LPST, TX ASBESTOS, TX GCC	263	0.050	NE
MF2031 / 14	DIAMOND SHAMROCK NO	1516 TINNIN FORD	TX RDR	263	0.050	NE
KY2032 / 11	TIRE SERVICE COMPANY	301 W 5TH ST	TX HIST UST	263	0.050	ESE
MG2033 / 14	THE GOODYEAR TIRE &	115 E OLTORF ST	RCRA NonGen / NLR, FINDS, ECHO	263	0.050	SE
MG2034 / 14	GOODYEAR AUTO SERVIC	115 E OLTORF ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	263	0.050	SE
MG2035 / 14	GOODYEAR TIRE & RUBB	115 E OLTORF ST	TX UST	263	0.050	SE
LV2036 / 8	SPEEDWAY SERVICE STA	3714 SPEEDWAY	EDR Hist Auto	264	0.050	ESE
JY2037 / 11	ROBINSON SAML	316 COLORADO	EDR Hist Auto	264	0.050	NNE
MH2038 / 17	CVS PHARMACY 0213	5526 5526 S CONGRESS	RCRA NonGen / NLR, FINDS, ECHO	264	0.050	WNW
MH2039 / 17	CVS PHARMACY	5526 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	264	0.050	WNW
MH2040 / 17	FAST STOP STORES INC	5526 S CONGRESS AVE	EDR Hist Auto	264	0.050	WNW
MH2041 / 17	FAST STOP 11	5526 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	264	0.050	WNW
MH2042 / 17	FAST STOP STORE 11	5526 S CONGRESS	TX RDR	264	0.050	WNW
MH2043 / 17	PROPOSED CVS PHARMAC	5526 S CONGRESS AVE	TX LPST, TX IHW CORR ACTION	264	0.050	WNW
MI2044 / 11	CAPITOL LAUNDRY 6 DR	301 W 8TH ST	EDR Hist Cleaner	265	0.050	ESE
LK2045 / 11	321 3 COVERT AUTO CO	321 6TH W	EDR Hist Auto	265	0.050	ESE
KH2046 / 11	ALAMO TRANSMISSION S	200 CONGRESS AVE	EDR Hist Auto	265	0.050	SSW
MJ2047 / 11	KEESES ENCO HUMBLE S	600 5TH ST W	EDR Hist Auto	265	0.050	ESE
MJ2048 / 11	WHEELERS ENCO HUMBLE	600 5TH ST W	EDR Hist Auto	265	0.050	ESE
MJ2049 / 11	ACME SERVICE STA	600 5TH W	EDR Hist Auto	265	0.050	ESE
LA2050 / 11	PRUDENCE BAILEY	122 W 5TH ST	TX HIST UST	267	0.051	SW
LQ2051 / 11	ROGERS & SALYER FILL	204 BARTON SPRINGS R	EDR Hist Auto	268	0.051	NE
KW2052 / 11	OCONNELL & WORLEY	201 8TH E	EDR Hist Cleaner	268	0.051	ESE
2053 / 11	NELSON CHESTER B	603 9TH W	EDR Hist Cleaner	268	0.051	ESE
2054 / 8	ROOHI JOOHI INC	7700 E MRTN LTHR KIN	EDR Hist Auto	269	0.051	West
2055 / 11	SAM HOUSTON BUILDING	201 E 14TH ST	TX AST	269	0.051	ESE
MJ2056 / 11	AUTOMOTIVE SPECIALIS	502 NUECES ST	EDR Hist Auto	269	0.051	ESE
MK2057 / 11	DEWEY PURYEAR	201 W CESAR CHAVEZ S	TX HIST UST	270	0.051	NNE
ML2058 / 15	JERRYS GARAGE	1902 MONTOPOLIS DR	EDR Hist Auto	271	0.051	NNE
2059 / 6	CAPITAL PREFABRICATO	6926 N LAMAR BLVD	TX HIST UST	272	0.052	WNW
MM2060 / 11	MIOTORAMP STGE	713 COLORADO	EDR Hist Auto	272	0.052	WNW
2061 / 8	GRAY CLEANERS	3912 SPEEDWAY	EDR Hist Cleaner	273	0.052	ESE
KS2062 / 11	FORMER GLO FACILITY	421 E CESAR CHAVEZ S	TX UST, TX HIST UST	273	0.052	ESE
MN2063 / 11	ORIENTAL OIL COMPANY	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2064 / 11	PIERCE PETROLEUM	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2065 / 11	DAVIS BROTHERS	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2066 / 11	ORIENTAL OIL COMPANY	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
MK2067 / 11	SILICON LABRITORIES		PFAS ECHO	273	0.052	NNE
JH2068 / 11	601 03 GAGE BROS	601 7TH E	EDR Hist Auto	273	0.052	NE
JH2069 / 11	REDS GARAGE AUTO REP	600 7TH E	EDR Hist Auto	273	0.052	NE
KT2070 / 11	AMERICAN CLEANERS	719A COLORADO ST	TX DRYCLEANERS	273	0.052	WNW
MB2071 / 14	SCHNELL BROS WHEEL	501 MONROE ST W	EDR Hist Auto	273	0.052	WNW
2072 / 8	LAY WALLACE DCLO CLN	3808 SPEEDWAY	EDR Hist Cleaner	274	0.052	ESE
KL2073 / 11	AUSTIN GREENWOOD CON	909 COLORADO ST	TX LPST, TX UST, TX HIST UST, TX Financi...	274	0.052	WNW
KL2074 / 11	AUSTIN GREENWOOD CON	909 COLORADO ST	TX AST	274	0.052	WNW
LF2075 / 11	BROWNS JACK CLEANERS	615 MARTIN LUTHER K	EDR Hist Cleaner	275	0.052	East
KU2076 / 11	CAMPOS MANUEL	801 1ST E	EDR Hist Auto	276	0.052	ESE
2077 / 14	SOUTH CENTRAL WATERF	NEC OF S FIRST ST AN	TX BROWNFIELDS	276	0.052	NE
ML2078 / 15	JERRYS GARAGE AUTO	1900 MONTOPOLIS DR	EDR Hist Auto	277	0.052	NNE
JP2079 / 11	TRAVIS COUNTY OIL	500 BRAZOS ST	EDR Hist Auto	277	0.052	SSW
2080 / 11	SCARBROUGH HOUSE TRA	2612 WHITIS AVE	TX VCP	277	0.052	East
MO2081 / 14	BROADDUS CHEVRON RIV	30 IH 35 N	TX UST, TX Financial Assurance	277	0.052	NE
LR2082 / 6	RAYS REPAIR	6516 SHIRLEY AVE	EDR Hist Auto	279	0.053	ESE
MO2083 / 14	BROADDUS ENTERPRISES	30 N I 35	EDR Hist Auto	279	0.053	NE
MO2084 / 14	RIVERSIDE GROCERY	30 N I 35	TX HIST UST	279	0.053	NE
LG2085 / 11	TEXAS CO THE FILLING	101 5TH ST W	EDR Hist Auto	279	0.053	SSW
JH2086 / 11	EMPIRE AUTOMOTIVE SE	604 7TH ST E	EDR Hist Auto	279	0.053	NE
JH2087 / 11	LOPEZ FRANK S	604 7TH E	EDR Hist Auto	279	0.053	NE
JH2088 / 11	EMPIRE AUTOMOTIVE SE	604 7TH ST E	EDR Hist Auto	279	0.053	NE
LG2089 / 11	THURMAN WAVERLY	120 5TH W	EDR Hist Cleaner	279	0.053	SSW
LG2090 / 11	PAGE SAM F DCLO CLNR	109 5TH ST W	EDR Hist Cleaner	279	0.053	SSW
LG2091 / 11	STROBURG & BLOMQUIST	103 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2092 / 11	GOSLIN J W T & CO	108 5TH ST E	EDR Hist Auto	280	0.053	SSW
LX2093 / 11	APPLE TRACT	811-814 W 6TH	TX UST	280	0.053	WNW
LX2094 / 11	APPLE TRACT	811 W 6TH ST	TX VCP	280	0.053	WNW
LG2095 / 11	NIEMAN ELECTRICAL	107 5TH W	EDR Hist Auto	280	0.053	SSW
LG2096 / 11	NIEMAN ELEC SER	107 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2097 / 11	ABADIE & ROLAND TAI	107 5TH ST W	EDR Hist Cleaner	280	0.053	SSW
LG2098 / 11	TAYLOR VIVIEN REPR S	123 5TH ST W	EDR Hist Auto	280	0.053	SSW
ME2099 / 11	B & N AXLE SERVICE	219 4TH ST W	EDR Hist Auto	280	0.053	NNE
ME2100 / 11	B & N AXLE SERVICE	219 4TH ST W	EDR Hist Auto	280	0.053	NNE
LG2101 / 11	DICKARD R AUTO REPR	104 5TH ST E	EDR Hist Auto	280	0.053	SSW
MP2102 / 11	BAKER LEONARD	1700 LAVACA ST	EDR Hist Cleaner	280	0.053	ESE
LG2103 / 11	111 13 BARGE ROBT AU	111 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2104 / 11	LUNCEFORD THOMAS J A	127 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2105 / 11	111 15 BENSON MOTOR	111 5TH ST E	EDR Hist Auto	280	0.053	SSW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
LG2106 / 11	EPPLER J LAYTON REPR	115 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2107 / 11	SE COR BLUE PENNANT	114 5TH ST W	EDR Hist Auto	280	0.053	SSW
MQ2108 / 8	TOSCO MARKETING COMP	3208 EAST AVE	EDR Hist Auto	280	0.053	ENE
MQ2109 / 8	7-ELEVEN #36560	3208 E SH 71	TX HIST UST	280	0.053	ENE
LG2110 / 11	CITIES SERVICE STA	120 5TH E	EDR Hist Auto	280	0.053	SSW
LG2111 / 11	BERGSTROM BROS	119 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2112 / 11	NE COR COX REALIZATI	117 5TH ST E	EDR Hist Auto	280	0.053	SSW
MR2113 / 11	JIMS CONOCO	1308 LAVACA ST	TX LPST, TX Ind. Haz Waste	280	0.053	ESE
MR2114 / 11	JIMS CONOCO	1308 LAVACA ST	TX UST, TX HIST UST	280	0.053	ESE
MR2115 / 11	OCONNERS JIM MOBIL G	1308 LAVACA ST	EDR Hist Auto	280	0.053	ESE
2116 / 6	CRUZ AUTOMOTIVE	8827 LAMAR BLVD N	EDR Hist Auto	281	0.053	SE
LH2117 / 11	ALEXANDER CLY D FILL	301 5TH E	EDR Hist Auto	281	0.053	SSW
LH2118 / 11	302 12 FROMME MOTOR	302 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2119 / 11	0 & M AUTO REPAIR GR	318 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2120 / 11	D & M AUTO REPAIR	318 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2121 / 11	ELLIOTT EUNICE E RAD	318 5TH E	EDR Hist Auto	281	0.053	SSW
JP2122 / 11	DARTER HOWARD T	217 5TH E	EDR Hist Auto	281	0.053	SSW
JP2123 / 11	DARTER H T AUTO	217 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2124 / 11	PILAND & ELLIOTT SER	311 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2125 / 11	TRAVIS MOTOR EXCHANG	311 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2126 / 11	PILAND & ELLIOTT	311 5TH E	EDR Hist Auto	281	0.053	SSW
LX2127 / 11	MCMORRIS FORD	808 W 6TH ST	TX UST	282	0.053	WNW
LX2128 / 11	MCMORRIS FORD	808 W 6TH ST	TX LPST, TX CENTRAL REGISTRY	282	0.053	WNW
LX2129 / 11	MCMORRIS FORD	808 W 6TH	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	282	0.053	WNW
LX2130 / 11	ME MORRIS FORD INC	808 W 6TH ST	EDR Hist Auto	282	0.053	WNW
LH2131 / 11	316 18 DELZELL & DEM	316 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2132 / 11	DELZELL & DEMENT AUT	316 5TH E	EDR Hist Auto	282	0.053	SSW
JP2133 / 11	CULLEN HUGH H GARAGE	206 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2134 / 11	RUMSEYS GARAGE	211 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2135 / 11	HOME STEAM LNDY	211 5TH ST E	EDR Hist Cleaner	282	0.053	SSW
LH2136 / 11	D&M AUTO REPR	305 5TH E	EDR Hist Auto	282	0.053	SSW
LH2137 / 11	REAR SMITH AUTO SERV	305 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2138 / 11	FROMME MOTOR CO	304 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2139 / 11	SAN JACINTO GARAGE	305 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2140 / 11	DARTER SLIM	213 5TH E	EDR Hist Auto	282	0.053	SSW
LH2141 / 11	LOCKE WILL MOTOR	306 5TH E	EDR Hist Auto	282	0.053	SSW
LH2142 / 11	RIEGERS GARAGE	307 5TH E	EDR Hist Auto	282	0.053	SSW
MP2143 / 11	CAMPBELL CLEANERS	1620 LAVACA	EDR Hist Cleaner	282	0.053	ESE
JP2144 / 11	WATT STUART SERVICE	200 5TH E	EDR Hist Auto	282	0.053	SSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
JP2145 / 11	FIFTH & BRAZOS SERVI	200 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2146 / 11	MILES DEAN DCLO CLNR	324 5TH ST E	EDR Hist Cleaner	282	0.053	SSW
JP2147 / 11	QUICK SERVICE GAR PI	204 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2148 / 11	205 7 AUSTIN RUBBER	205 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2149 / 11	CAPITOL CHEVROLET	218 5TH E	EDR Hist Auto	282	0.053	SSW
JP2150 / 11	BOWDIN M L SPRING	218 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2151 / 11	BEATY WELDING & RADI	219 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2152 / 11	CAPITOL CHEVROLET CO	220 5TH E	EDR Hist Auto	283	0.054	SSW
JP2153 / 11	ELECTRICAL SERVICE C	221 5TH ST E	EDR Hist Auto	283	0.054	SSW
JP2154 / 11	BURKHALTER E E AUTO	223 5TH ST E	EDR Hist Auto	283	0.054	SSW
LB2155 / 11	AUSTIN FRAME & WHEEL	526 1ST ST S	EDR Hist Auto	283	0.054	WNW
KQ2156 / 11	SMITH LANDRY C CLDO	706 6TH E	EDR Hist Cleaner	283	0.054	ENE
KY2157 / 11	LINDSAY AUTO ELEC	504 LAVACA	EDR Hist Auto	283	0.054	ESE
LB2158 / 11	AUSTIN FRAME & WHEEL	525 1ST ST S	EDR Hist Auto	284	0.054	WNW
MS2159 / 15	MASSEVS GARAGE AUTO	6507 RIVERSIDE DR E	EDR Hist Auto	284	0.054	SSW
MS2160 / 15	MASSEYS GARAGE	6507 RIVERSIDE DR E	EDR Hist Auto	284	0.054	SSW
KG2161 / 11	400 LAVACA ST AUSTIN	400 LAVACA ST	TX NON REGIST PST	285	0.054	ESE
KG2162 / 11	ABANDONED	400 LAVACA ST	TX RDR	285	0.054	ESE
KG2163 / 11	400 LAVACA ST AUSTIN	400 LAVACA ST	TX TANKS, TX CENTRAL REGISTRY	285	0.054	ESE
IY2164 / 11	KEALHOFER STARR TIRE	910 LAVACA ST	EDR Hist Auto	285	0.054	ESE
IY2165 / 11	COMMERICAL TITLE BUI	910 LAVACA ST	TX LPST	285	0.054	ESE
MT2166 / 14	EKSTROM G A	303 CROCKETT	EDR Hist Cleaner	285	0.054	ESE
2167 / 8	EURO SPORT CYCLES	616 W 34TH ST	TX Ind. Haz Waste	286	0.054	WNW
JE2168 / 11	AUTOMATIC BENDIX	207 17TH E	EDR Hist Cleaner	287	0.054	ESE
MU2169 / 11	327 27 HICKS RUBBER	325 CONGRESS AVE	EDR Hist Auto	287	0.054	NNE
2170 / 8	YOUNGS REPAIR SHOP	607 37TH W	EDR Hist Auto	287	0.054	WNW
LB2171 / 11	LINDSAY AUTO ELEC	515 1ST S	EDR Hist Auto	287	0.054	WNW
2172 / 6	B ALL AUTO SERVICE W	607 DEEN AVE	EDR Hist Auto	287	0.054	SE
MV2173 / 11	7-ELEVEN 12705	408 W 15TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	288	0.055	WNW
MV2174 / 11	7 ELEVEN 12705	408 W 15TH ST	TX RDR	288	0.055	WNW
LF2175 / 11	BURTONS LAUNDRY & CL	615 W 19TH ST	EDR Hist Cleaner	289	0.055	East
JH2176 / 11	TRAVIS MOTOR EX	611 7TH E	EDR Hist Auto	289	0.055	NE
JH2177 / 11	B & L CLUTCH & BRAKE	611 7TH ST E	EDR Hist Auto	289	0.055	NE
JH2178 / 11	B & L CLUTCH & BRAKE	611 7TH ST E	EDR Hist Auto	289	0.055	NE
MW2179 / 6	CINBAR ENGINEERING C	711 W ST. JOHNS AVE	TX HIST UST	290	0.055	ESE
KH2180 / 11	LAWSHA LEE C DCLO CL	215 CONGRESS AVE E	EDR Hist Cleaner	290	0.055	SSW
LO2181 / 8	AUSTIN RADIATOR WORK	810 CAPITOL CT	EDR Hist Auto	290	0.055	WNW
MN2182 / 11	GARDNERS SERVICE STA	99 CONGRESS AVE	EDR Hist Auto	291	0.055	NNE
MT2183 / 14	EKSTROM GUS AUTO REP	301 CROCKETT ST	EDR Hist Auto	291	0.055	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
JA2184 / 11	AUTOMOTIVE SPECIA	837 12TH W	EDR Hist Auto	292	0.055	WNW
JH2185 / 11	TRAVIS MTR EX	613 7TH E	EDR Hist Auto	292	0.055	NE
JH2186 / 11	TRAVIS MOTOR EXCHANG	613 7TH ST E	EDR Hist Auto	292	0.055	NE
MX2187 / 11	WELLS H P GARAGE	206 18TH E	EDR Hist Auto	292	0.055	ESE
LB2188 / 11	ACUNAS	511 E 1ST ST	TX UST	293	0.055	WNW
LB2189 / 11	TAYLORS SERIVCE	511 1ST E	EDR Hist Auto	293	0.055	WNW
LM2190 / 8	NEELLEY VENDING	813 W NORTH LOOP BLV	TX LPST, TX HIST UST	293	0.055	WNW
MK2191 / 11	BLOCK 4	100 COLORADO ST	TX VCP, TX GCC, TX IOP, TX CENTRAL REGIS...	293	0.055	NNE
MK2192 / 11	AUSTIN GAS LIGHT CO	100 COLORADO ST (COR	EDR MGP	293	0.055	NNE
KX2193 / 14	SOUTH LAKESHORE BOUL	1717 LAKESHORE BLVD	EDR Hist Cleaner	293	0.055	ENE
MN2194 / 11	LINCOLN PROPERTIES	FIRST AND CONGRESS	SEMS-ARCHIVE	294	0.056	NNE
JE2195 / 11	GRAY CLNRS	209 17TH E	EDR Hist Cleaner	294	0.056	ESE
MY2196 / 11	AUSTIN CONV. CTR. EX	3RD & RED RIVER	TX RDR	294	0.056	WNW
MZ2197 / 11	PARKING GARAGE E	1604 LAVACA ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	297	0.056	ESE
MZ2198 / 11	THRIFTY CLEANERS	1604 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
MR2199 / 11	LAVACA ST GARAGE	1404 LAVACA ST	EDR Hist Auto	297	0.056	ESE
MR2200 / 11	DAVIS H R DCLO CLNR	1404 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
MR2201 / 11	KALLGREN & HAMILTON	1402 LAVACA	EDR Hist Cleaner	297	0.056	ESE
MR2202 / 11	MAGNOLIA PET CO STI	1312 LAVACA ST	EDR Hist Auto	297	0.056	ESE
LT2203 / 11	BAKER LEONARD CLNR	1516 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
LK2204 / 11	LINDSAY AUTO ELEC	506 LAVACA ST	EDR Hist Auto	297	0.056	ESE
2205 / 17	BEN AUTO REPAIR	5409 WASSON RD	EDR Hist Auto	298	0.056	ESE
LT2206 / 11	FRIENDLY PRESSING SH	1504 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2207 / 11	11 AUSTIN LAUNDRY	1514 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2208 / 11	1504 AUSTIN LAUNDRY	1510 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2209 / 11	QUINN & SMITH CLNRS	1506 LAVACA ST	EDR Hist Cleaner	299	0.057	ESE
LK2210 / 11	SHIRLEYS HATTER	310 6TH W	EDR Hist Cleaner	299	0.057	ESE
LK2211 / 11	SHIRLEY CLEANERS & H	310 6TH ST W	EDR Hist Cleaner	299	0.057	ESE
2212 / 14	WESTERN AUTO	137 W OLTORF ST	TX LPST, TX UST	299	0.057	SE
NA2213 / 11	PEARSON WESLEY	301 CONGRESS AVE S	EDR Hist Auto	299	0.057	SSW
NA2214 / 11	GULF REFINING CO.	301 S CONGRESS AVE	TX HIST UST	299	0.057	SSW
NA2215 / 11	SMITTY AUTO SERVICE	301 CONGRESS AVE S	EDR Hist Auto	299	0.057	SSW
KY2216 / 11	CARLSONS T P SERV	500 LAVACA ST	EDR Hist Auto	300	0.057	ESE
JH2217 / 11	BETHKE BRAKE SERVICE	617 7TH ST E	EDR Hist Auto	300	0.057	NE
JH2218 / 11	BETHKE BRAKE SERVICE	617 7TH ST E	EDR Hist Auto	300	0.057	NE
NB2219 / 20	DIAMOND SHAMROCK REF	2001 BASTROP HWY E	EDR Hist Auto	300	0.057	NNE
NB2220 / 20	DIAMOND SHAMROCK REF	2001 BASTROP HWY	EDR Hist Auto	300	0.057	NNE
NB2221 / 20	DIAMOND SHAMROCK REF	2001 BASTHROP HWY	EDR Hist Auto	300	0.057	NNE
NB2222 / 20	SIGMORE DIAMOND SHAM	2001 BASTHROP HIGHWA	EDR Hist Auto	300	0.057	NNE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
NB2223 / 20	SIGMOR SHAMROCK SERV	2001 BASTROP HWY	EDR Hist Auto	300	0.057	NNE
KY2224 / 11	502 04 WHITING ROBT	502 LAVACA ST	EDR Hist Auto	300	0.057	ESE
NC2225 / 14	MARTIN J E SERVICE S	1710 1ST	EDR Hist Auto	301	0.057	WNW
NC2226 / 14	HAYNES R E FILL STA	1710 1ST	EDR Hist Auto	301	0.057	WNW
LA2227 / 11	AUSTIN GARAGE AUTOMO	511 COLORADO ST	EDR Hist Auto	301	0.057	West
MG2228 / 14	GOODYEAR TIRE & RUBB	117 E OLTORF ST	TX HIST UST	301	0.057	SE
MU2229 / 11	NIELSON GULF SERVICE	329 CONGRESS AVE	EDR Hist Auto	302	0.057	NNE
JP2230 / 11	M. C. PARRISH	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2231 / 11	YELLOW CAB	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2232 / 11	F. O. SWENSEN	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2233 / 11	NCNB TEXAS	201 E 5TH ST	TX LPST	302	0.057	SSW
JP2234 / 11	CLOSED SITE	201 E. 5TH ST	TX HIST UST	302	0.057	SSW
JP2235 / 11	CHRISTAL-FRAZIER MET	201 E 5TH ST	TX HIST UST	302	0.057	SSW
ND2236 / 11	BANK63	CORNER OF 3RD BRAZOS	TX UST	303	0.057	East
2237 / 8	BOWMAN RESIDENCE	212 W 33RD ST	TX TANKS, TX HIST UST, TX RDR, TX CENTRA...	303	0.057	WNW
LA2238 / 11	505 11 BARKER MOTOR	505 COLORADO ST	EDR Hist Auto	305	0.058	West
MU2239 / 11	MC GOWAN ED TEXACO	344 CONGRESS AVE	EDR Hist Auto	305	0.058	NNE
NE2240 / 14	MAJESTIC PRODUCTS	118 E ALPINE RD	TX HIST UST, TX Ind. Haz Waste, TX IHW C...	305	0.058	ESE
NE2241 / 14	BROYHILL FURNITURE I	118 E ALPINE RD	TX UST	305	0.058	ESE
NE2242 / 14	MAJESTIC PRODUCTS CO	118 E ALPINE RD	RCRA NonGen / NLR	305	0.058	ESE
NE2243 / 14	MAJESTIC PRODUCTS	118 E ALPINE RD	TX Ind. Haz Waste	305	0.058	ESE
NF2244 / 6	DIAMOND SHAMROCK	806 W RUNDBERG LN	EDR Hist Auto	307	0.058	WNW
NF2245 / 6	DIAMOND SHAMROCK 964	806 W RUNDBERG LN	TX LPST, TX UST, TX HIST UST	307	0.058	WNW
LV2246 / 8	CONVENIENCE COIN LAU	101 38TH ST E	EDR Hist Cleaner	307	0.058	ESE
LV2247 / 8	CONVENIENCE COIN LAU	101 38TH ST E	EDR Hist Cleaner	307	0.058	ESE
2248 / 11	STUDENT CO OPERATIVE	2412 SAN ANTONIO	EDR Hist Auto	307	0.058	West
LL2249 / 17	VALENTA SERVICE STAT	5607 CONGRESS AVE S	EDR Hist Auto	307	0.058	ESE
LL2250 / 17	VALENTA SERV STA	5607 CONGRESS AVE	EDR Hist Auto	307	0.058	ESE
LW2251 / 14	PRATHER F H FILL STA	1601 1ST	EDR Hist Auto	307	0.058	WNW
LW2252 / 14	MC CLAIN HORACE C CD	1600 1ST	EDR Hist Cleaner	307	0.058	WNW
MQ2253 / 8	CINDERELLA CLNS	3500 EAST AVE	EDR Hist Cleaner	307	0.058	ENE
MQ2254 / 8	NOACK BENJ FILL STA	3500 EAST AVE	EDR Hist Auto	307	0.058	ENE
LA2255 / 11	203 5 SMITH KELLY DC	203 6TH W	EDR Hist Cleaner	308	0.058	WNW
LA2256 / 11	STARR BLDG HISTORIC	501 COLORADO	TX RDR	308	0.058	West
LA2257 / 11	KEMP PROPERTIES	501 COLORADO ST	TX LPST, TX GCC	308	0.058	West
LA2258 / 11	WOFFORD S D FILLING	501 COLORADO	EDR Hist Auto	308	0.058	West
LO2259 / 8	Z TECH AUTO REPR	809 CAPITOL ST	EDR Hist Auto	310	0.059	WNW
KJ2260 / 11	SCHNEIDER ALBERT REP	310 2ND W	EDR Hist Auto	311	0.059	ESE
KY2261 / 11	SING FRANCES MRS LND	311 5TH ST W	EDR Hist Cleaner	313	0.059	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
MY2262 / 11	AUSTIN CONVENTION CE	300 RED RIVER ST	TX HIST UST	313	0.059	WNW
LX2263 / 11	GREGORY FENDER	815 6TH W	EDR Hist Auto	313	0.059	WNW
LV2264 / 8	M F ROUTE LAUNDRIES	103 38TH ST E	EDR Hist Cleaner	314	0.059	ESE
LV2265 / 8	CONVENIENCE COIN LAU	103 38TH ST E	EDR Hist Cleaner	314	0.059	ESE
2266 / 14	WALKERS LAUNDRY	1903 NEWTON ST	EDR Hist Cleaner	315	0.060	ESE
KL2267 / 11	BELL AIRDOME FILLING	900 COLORADO	EDR Hist Auto	316	0.060	WNW
2268 / 8	MEACHAM W W R	3104 KING ST	EDR Hist Cleaner	316	0.060	ESE
KS2269 / 11	FORMER GLO FAC	421 E 1ST	TX RDR	317	0.060	ESE
NG2270 / 11	THURMAN WAVERLY	620 COLORADO ST	EDR Hist Cleaner	318	0.060	WNW
LA2271 / 11	HOUGH ROY AUTO REPR	608 COLORADO ST	EDR Hist Auto	319	0.060	WNW
NH2272 / 11	WHITLEY CO	801 BRAZOS TO 805	TX UST, RCRA NonGen / NLR	319	0.060	ESE
NH2273 / 11	WHITLEY	801 BRAZOS TO 805	TX Ind. Haz Waste	319	0.060	ESE
NI2274 / 14	SOUTH FIRST CLEANERS	1905 S 1ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	319	0.060	WNW
NI2275 / 14	SOUTH FIRST CLEANERS	1905 S 1ST ST	EDR Hist Cleaner	319	0.060	WNW
KY2276 / 11	AMERICAN CLEANERS	309 5TH ST W	EDR Hist Cleaner	320	0.061	ESE
KY2277 / 11	FAULKNER RUSSELL C	309 5TH W	EDR Hist Auto	320	0.061	ESE
NJ2278 / 11	MC CUTCHEON U S AUTO	106 1ST E	EDR Hist Auto	320	0.061	NNE
NK2279 / 11	DOWNS R L & CO	309 10TH W	EDR Hist Cleaner	321	0.061	ESE
KH2280 / 11	WARDROBE CLNRS THE	207 CONGRESS AVE E	EDR Hist Cleaner	321	0.061	SSW
NA2281 / 11	FIRESTONE TIRE & SER	311 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	322	0.061	SSW
KT2282 / 11	209 11 BLUE BONNET O	209 8TH W	EDR Hist Cleaner	323	0.061	WNW
NA2283 / 11	GULF REFG CO STA NO	300 CONGRESS AVE S	EDR Hist Auto	323	0.061	SSW
NA2284 / 11	KINGSLEY AUTOMOTIVE	300 CONGRESS AVE S	EDR Hist Auto	323	0.061	SSW
LI2285 / 11	GREGG J EARLE CLNR	1808 LAVACA ST	EDR Hist Cleaner	324	0.061	East
MW2286 / 6	ALLEN RADIATORS	707 ST JOHNS AVE W	EDR Hist Auto	324	0.061	ESE
LY2287 / 14	HUMBLE PRODUCTS SERV	343 CONGRESS AVE S	EDR Hist Auto	326	0.062	NE
LY2288 / 14	RIVERSIDE SERVICE ST	343 CONGRESS AVE S	EDR Hist Auto	326	0.062	NE
LK2289 / 11	WEBB J E TIRES	608 LAVACA ST	EDR Hist Auto	328	0.062	ESE
2290 / 11	FIRE STATION 1	401 E 5TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	328	0.062	SSW
NJ2291 / 11	ALLMAN JESS	112 1ST E	EDR Hist Auto	328	0.062	NE
KY2292 / 11	AAMCO TRANSMISSIONS	307 5TH ST W	EDR Hist Auto	329	0.062	ESE
KY2293 / 11	307 9 KNIGHT WHIPPET	307 5TH ST W	EDR Hist Auto	329	0.062	ESE
KH2294 / 11	TEXAS OIL COMPANY	100 W 2ND ST	TX HIST UST	329	0.062	SSW
2295 / 11	WARD HAROLD	703 BARTON SPGS RD	EDR Hist Auto	329	0.062	WNW
KH2296 / 11	AVENUE GARAGE	205 CONGRESS AVE E	EDR Hist Auto	329	0.062	SSW
KZ2297 / 14	MARY DAWSON	1214 S 1ST ST	TX HIST UST	330	0.062	WNW
KZ2298 / 14	DIANA D ZUMWALT ETAL	1214 S 1ST ST	TX LPST, TX UST	330	0.062	WNW
KZ2299 / 14	OLD AUTO SHOP	1214 S 1ST ST	TX HIST UST	330	0.062	WNW
2300 / 8	K AND S INTERCONNECT	3709-B PROMONTORY PO	RCRA-VSQG	330	0.062	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
NG2301 / 11	SMITH KELLY CLEANERS	209 6TH W	EDR Hist Cleaner	330	0.062	WNW
NL2302 / 11	PHILLIPS BUILDING	103 E 5TH ST	TX VCP, TX GCC	330	0.062	SSW
NJ2303 / 11	112 14 ALLMANS JESS	114 1ST E	EDR Hist Auto	330	0.062	NE
2304 / 11	BOUCHARD E A GARAGE	207 14TH W	EDR Hist Auto	331	0.063	WNW
NM2305 / 8	MAGNOLIA PET CO STA	100 31ST E	EDR Hist Auto	332	0.063	ESE
KI2306 / 2	BROWN JACK CLEANERS	1109 W PARMER LN	EDR Hist Cleaner	332	0.063	West
NN2307 / 3	AUTOMATIC TRANSMISSI	811 PRAIRIE TRL	EDR Hist Auto	332	0.063	WNW
LC2308 / 11	EXXON 6 8082	2324 N ST MARYS	TX UST	333	0.063	ESE
NO2309 / 6	AUSTIN COMPLETE AUTO	821 BRENTWOOD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	334	0.063	WNW
NO2310 / 6	B & B BODY & PAINT R	821 BRANTWOOD ST	EDR Hist Auto	334	0.063	WNW
2311 / 3	MINGOS BODY SHOP	811 MCPAUL	RCRA NonGen / NLR, FINDS, ECHO	334	0.063	WNW
2312 / 11	LYNN SMITH	300 W DEAN KEETON ST	TX HIST UST	334	0.063	East
KY2313 / 11	ANDYS AUTO ELECTRIC	305 5TH ST W	EDR Hist Auto	336	0.064	ESE
KY2314 / 11	S & D AUTO ELECTRIC	305 5TH ST W	EDR Hist Auto	336	0.064	ESE
KY2315 / 11	ANDYS AUTO ELEC REPR	305 5TH W	EDR Hist Auto	336	0.064	ESE
NP2316 / 20	I DEAL TIRE	2415 BASTROP HWY E	TX SPILLS, TX Ind. Haz Waste, TX CENTRAL...	336	0.064	NE
NP2317 / 20	RAYMOND RAMSEY & JER	2415 BASTROP HWY E	TX UST	336	0.064	NE
NA2318 / 11	LINDHOLM GARAGE	219 BARTON SPRINGS R	EDR Hist Auto	337	0.064	SSW
NG2319 / 11	CAPITAL CITY AUTO CO	211 6TH W	EDR Hist Auto	337	0.064	WNW
LA2320 / 11	JOHNSON ARVEL G	510 COLORADO	EDR Hist Auto	338	0.064	West
NQ2321 / 8	WARREN CLNRS	3209 SPEEDWAY	EDR Hist Cleaner	338	0.064	ESE
NR2322 / 6	AUSTIN SHEET METAL S	715 W POWELL LN	TX HIST UST	338	0.064	SE
NQ2323 / 8	WARREN J A CLC CLNR	3207 SPEEDWAY	EDR Hist Cleaner	338	0.064	ESE
LJ2324 / 3	REBREU BODY & FRAME	822 KRAMER LN	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	338	0.064	WNW
KT2325 / 11	BARRS BLUE BONNET	213 8TH W	EDR Hist Cleaner	339	0.064	WNW
KP2326 / 11	SODIES AUTO REPAIR	405 NECHES ST	EDR Hist Auto	339	0.064	SW
KP2327 / 11	CAPITAL SPRING & BRA	403 NECHES ST	EDR Hist Auto	341	0.065	SW
NJ2328 / 11	NW COR SWEARINGEN AR	120 1ST W	EDR Hist Auto	341	0.065	NE
KC2329 / 11	BUMPER-TO-BUMPER CAR	201 SAN JACINTO BLVD	TX Ind. Haz Waste	341	0.065	WNW
KC2330 / 11	BUMPER-TO-BUMPER CAR	201 SAN JACINITO	RCRA NonGen / NLR, FINDS, ECHO	341	0.065	WNW
NS2331 / 11	PROPOSED CHICK FIL A	503 W MARTIN LUTHER	TX VCP	342	0.065	West
LU2332 / 8	7-ELEVEN STORE 36656	620 W 29TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	342	0.065	WNW
LU2333 / 8	DIAMOND SHAMROCK 206	620 W 29TH ST	TX RDR	342	0.065	WNW
LU2334 / 8	TP 2533	620 W 29TH ST	TX RDR	342	0.065	WNW
LU2335 / 8	FROMER 7 ELEVEN 3665	620 W 29TH ST	TX RDR	342	0.065	WNW
KP2336 / 11	LANDMARK ORGANIZATIO	401 NECHES ST	TX IHW CORR ACTION	342	0.065	SW
LA2337 / 11	TEXAS MOTORS	502 COLORADO ST	EDR Hist Auto	343	0.065	West
MA2338 / 11	FORDEX SERVICE AUTO	201 2ND W	EDR Hist Auto	343	0.065	SSW
KY2339 / 11	AUTOMATIC TRANSMISSI	303 5TH ST W	EDR Hist Auto	344	0.065	ESE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
NT2340 / 11	OLD SPAGHETTI WAREHO	117 W 4TH ST	TX HIST UST	344	0.065	NNE
NG2341 / 11	CAPITAL CITY REPAIR	213 6TH W	EDR Hist Auto	344	0.065	WNW
LA2342 / 11	LONE STAR GARAGE AUT	500 COLORADO ST	EDR Hist Auto	344	0.065	West
NU2343 / 15	ESCUELA MONTESSORI	2013 MONTOPOLIS DRIV	US BROWNFIELDS	344	0.065	SSW
NU2344 / 15	ESCUELA MONTESSORI	2013 MONTOPOLIS DR	TX HIST UST	344	0.065	SSW
NV2345 / 11	UNITED MTR EXCH	111 SAN JACINTO ST	EDR Hist Auto	344	0.065	WNW
MZ2346 / 11		W 16TH & LAVACA	TX HIST UST	346	0.066	ESE
MO2347 / 14	BROADDUS CHEVRON	30 N IH 35	TX LPST, TX Ind. Haz Waste	346	0.066	NE
2348 / 17	PRO CLEAN CARPET CLN	6411 STARSTREAK DR	EDR Hist Cleaner	346	0.066	WNW
LH2349 / 11	CAPITOL TIRE	301 E 5TH ST	TX HIST UST	347	0.066	SSW
LH2350 / 11	GENERAL TIRE STORE	301 E 5TH ST	TX HIST UST	347	0.066	SSW
LH2351 / 11	CAPITOL TIRE SERVICE	301 E 5TH ST	TX UST	347	0.066	SSW
2352 / 11	JONES JOHN H CLNR	212 17TH W	EDR Hist Cleaner	347	0.066	WNW
LH2353 / 11	ACTION SCREEN GRAPHI	305 E 5TH ST STE B	TX Ind. Haz Waste	347	0.066	SSW
2354 / 8	BRUNDRETT ARNOLD 0 A	404 32ND W	EDR Hist Auto	347	0.066	ESE
LH2355 / 11	CAPITOL AUTO & TRANS	311 E 5TH ST	EDR Hist Auto	347	0.066	SSW
LH2356 / 11	HERMINE WILDE ESTATE	311 E 5TH ST	TX UST, TX HIST UST	347	0.066	SSW
NW2357 / 11	G. L. ROWE	816 W 12TH ST	TX HIST UST	348	0.066	WNW
KH2358 / 11	ELLIOTTS RADIATOR SH	102 2ND ST W	EDR Hist Auto	348	0.066	SSW
KH2359 / 11	ELLIOTTS RADIATOR SH	102 2ND ST W	EDR Hist Auto	348	0.066	SSW
NX2360 / 11	SILBEY FIREPROOF WAR	309 E 4TH ST	TX HIST UST	348	0.066	NNE
NX2361 / 11	AUSTIN FIREPROOF WAR	309 E 4TH ST	TX HIST UST	348	0.066	NNE
NY2362 / 11	ALMQUIST SINCLAIR SE	700 RED RIVER	EDR Hist Auto	349	0.066	NE
NX2363 / 11	M&T RAILWAY COMPANY	301 E 4TH ST	TX HIST UST	349	0.066	NNE
NX2364 / 11	K&B STORAGE CO.	301 E 4TH ST	TX HIST UST	349	0.066	NNE
MQ2365 / 8	MC GINNIS & GRIMES	3810 E AVE	EDR Hist Cleaner	350	0.066	ENE
MQ2366 / 8	DYNA TUNE	3810 EAST AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	350	0.066	ENE
MI2367 / 11	CAPITOL LNDRY & CLN	301 8TH W	EDR Hist Cleaner	351	0.066	ESE
NG2368 / 11	NASH JOHN H MOTOR CO	215 6TH W	EDR Hist Auto	351	0.066	WNW
NZ2369 / 11	FOWLER ELECTRIC	621 E 7TH ST	TX UST, TX HIST UST	351	0.066	NE
LG2370 / 11	JACOBSON TYRE & REPA	101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2371 / 11		101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2372 / 11	TEXAS OIL COMPANY	101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2373 / 11		101 W 5TH ST	TX HIST UST	351	0.066	SSW
KY2374 / 11	SMITH C B MOTORS	301 5TH W	EDR Hist Auto	351	0.066	ESE
KY2375 / 11	CARREON MARCIEL CLN	301 5TH ST W	EDR Hist Cleaner	351	0.066	ESE
KY2376 / 11	301 3 TIRE SERVICE C	301 5TH ST W	EDR Hist Auto	351	0.066	ESE
KH2377 / 11	DEWEYS WELDING & RAD	110 2ND W	EDR Hist Auto	352	0.067	SSW
KH2378 / 11	108 10 0 0 K GARAGE	108 2ND W	EDR Hist Auto	352	0.067	SSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
2379 / 15	APPLE MART	2101 WICKERSHAM LN	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	353	0.067	NNE
2380 / 15	912 HWY 183	912 HWY 183	US BROWNFIELDS	353	0.067	ENE
2381 / 14	MURPHYS GARAGE AUTO	3801 WADFORD ST	EDR Hist Auto	355	0.067	WNW
MQ2382 / 8	EXXON STATION 67383	3807 EAST AVE	TX LPST	355	0.067	ENE
MQ2383 / 8	EXXON MOBIL CORPORAT	3807 EAST AVE	RCRA NonGen / NLR	355	0.067	ENE
MQ2384 / 8	SS 6 7383	3807 EAST AVE	TX UST	355	0.067	ENE
MQ2385 / 8	EXXON MOBIL NO 67383	3807 EAST AVE	TX Ind. Haz Waste	355	0.067	ENE
MQ2386 / 8	BALKOS HUMBLE	3807 EAST AVE	EDR Hist Auto	355	0.067	ENE
2387 / 14	MUD PPPIES SELF SERV	2015 E RIVERSIDE DR	EDR Hist Auto	355	0.067	SW
KR2388 / 11	MRS. PRUDENCE BAILEY	520 W 6TH ST	TX HIST UST	355	0.067	ESE
KR2389 / 11	WILLIAMS MOTORS	520 W 6TH ST	TX HIST UST	355	0.067	ESE
KR2390 / 11	520 W 6TH ST LLC	520 W 6TH	TX RDR	355	0.067	ESE
2391 / 3	RPS TRANSMISSION & A	700 W APPLEGATE DR	EDR Hist Auto	355	0.067	ESE
NR2392 / 6	COLD	704 W POWELL LN	TX LPST, TX UST, TX HIST UST	356	0.067	SE
MK2393 / 11	R. A. JOHN	200 W CESAR CHAVEZ S	TX HIST UST	356	0.067	NNE
MK2394 / 11	PAUL O. SIMMS	200 W CESAR CHAVEZ S	TX HIST UST	356	0.067	NNE
OA2395 / 4	CONCRETE CORING	820 W YAGER LN	TX Ind. Haz Waste	356	0.067	East
OA2396 / 4	CONCRETE CORING	820 W YAGER LN	TX Ind. Haz Waste	356	0.067	East
OA2397 / 4	COTTMAN TRANSMISSION	820 W YAGER LN	EDR Hist Auto	356	0.067	East
OB2398 / 14	CAPITOL CLEANERS	1408 S 1ST STREET	RCRA NonGen / NLR, FINDS, ECHO, TX DRYCL...	357	0.068	WNW
OB2399 / 14	CAPITOL CLEANERS	1408 S 1ST ST	TX Ind. Haz Waste	357	0.068	WNW
OB2400 / 14	TRIPLE L INC	1408 S FIRST ST	EDR Hist Cleaner	357	0.068	WNW
2401 / 14	JIM WIMBERLY	1720 S 1ST ST	TX HIST UST	357	0.068	WNW
OB2402 / 14	W. RAYMOND CANION	1406 S 1ST ST	TX HIST UST	357	0.068	WNW
OC2403 / 11	SERVICE CENTER 2	600 RIVER ST	TX UST, TX HIST UST	357	0.068	WNW
OC2404 / 11	CITY OF AUSTIN FLEET	600 RIVER ST	RCRA NonGen / NLR, FINDS, ECHO	357	0.068	WNW
OC2405 / 11	CITY OF AUSTIN SERVI	600 RIVER ST	TX Ind. Haz Waste	357	0.068	WNW
OC2406 / 11	SERVICE CENTER 2	600 RIVER ST	TX SWF/LF, TX LPST, TX Ind. Haz Waste	357	0.068	WNW
OC2407 / 11	EMMA BARRIENTOS MEXI	600 RIVER STREET	US BROWNFIELDS	357	0.068	WNW
LG2408 / 11	417 19 PATTON AUTO L	417 CONGRESS AVE	EDR Hist Auto	358	0.068	SSW
NG2409 / 11	ESTES & CO AUTO	216 6TH W	EDR Hist Auto	358	0.068	WNW
NG2410 / 11	FIEGELS GARAGE	217 6TH W	EDR Hist Auto	358	0.068	WNW
NZ2411 / 11	BETHKE BRAKE SERVICE	617 E 7TH ST	EDR Hist Auto	358	0.068	NE
LF2412 / 11	LONGHORN CLNRS	510 W MARTIN LUTHUR	RCRA-SQG, FINDS, ECHO	359	0.068	East
2413 / 8	MORGAN PRINTING	900 OLD KOENIG LANE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	360	0.068	WNW
NW2414 / 11	CONVENIENCE COIN LAU	817 12TH ST W	EDR Hist Cleaner	361	0.068	WNW
LV2415 / 8	CONVENIENCE COIN LAU	101 E 38TH ST	EDR Hist Cleaner	363	0.069	ESE
LK2416 / 11	RIEGERS GARAGE AUTO	513 LAVACA	EDR Hist Auto	364	0.069	ESE
LK2417 / 11	REIGER MOTOR SALES	505 LAVACA	EDR Hist Auto	364	0.069	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
OD2418 / 11	EARL E. SIMMS	119 E 5TH ST	TX HIST UST	364	0.069	SSW
JY2419 / 11	29WAT R907222	4TH & COLORADO	TX UST	364	0.069	NNE
NL2420 / 11	EAST 9TH STREET COMP	115 E 5TH ST STE 200	EDR Hist Auto	364	0.069	SSW
LK2421 / 11	MC CUTCHEON U S AUTO	503 LAVACA ST	EDR Hist Auto	364	0.069	ESE
LK2422 / 11	AUSTIN BTRY & ELEC	501 LAVACA	EDR Hist Auto	365	0.069	ESE
OE2423 / 8	CAPITOL LAUNDRY & DR	806 KOENIG LN W	EDR Hist Cleaner	365	0.069	WNW
2424 / 11	AUTOMATIC TRANSMISSI	211 4TH ST W	EDR Hist Auto	365	0.069	NNE
MQ2425 / 8	DELWOOD CLNS	3925 EAST AVE	EDR Hist Cleaner	367	0.070	ENE
NS2426 / 11	KELLY SMITH CLEANERS	511 MARTIN LUTHER K	EDR Hist Cleaner	368	0.070	West
OF2427 / 11	COVERT BUICK INC	500 5TH ST W	EDR Hist Auto	368	0.070	WNW
2428 / 17	BATH CREST OF AUSTIN	111 RAMBLE LN	EDR Hist Cleaner	369	0.070	WNW
NA2429 / 11	PEARSON WESLEY H	313 CONGRESS AVE S	EDR Hist Auto	369	0.070	SSW
NA2430 / 11	PEARSON WESLEY H FIL	313 CONGRESS AVE S	EDR Hist Auto	369	0.070	SSW
MP2431 / 11	CORLEY & BERRY SERVI	1701 LAVACA	EDR Hist Auto	370	0.070	ESE
MP2432 / 11	M D PHARMACY	1701 LAVACA ST	TX LPST, TX UST, TX HIST UST	370	0.070	ESE
2433 / 17	HOPF WOLBERT VAULT C	4515 S CONGRESS AVE	TX HIST UST	370	0.070	ESE
OF2434 / 11	AUSTIN FEDERAL COURT	501 W 5TH ST	TX UST, TX HIST UST	371	0.070	WNW
OF2435 / 11	AUSTIN FEDERAL COURT	501 W 5TH ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	371	0.070	WNW
OG2436 / 11	THE WALTER TIPS CO.	115 W 2ND ST	TX HIST UST	371	0.070	SSW
OH2437 / 11	CITY OF AUSTIN RIGHT	3RD & SAN ANTONIO	TX TANKS, TX CENTRAL REGISTRY	371	0.070	WNW
2438 / 14	EXXON MOBIL CORPORAT	619 N IH 35	RCRA NonGen / NLR, FINDS, ECHO	371	0.070	SSW
OI2439 / 11		W 6TH ST & SAN ANTON	TX HIST UST	371	0.070	WNW
OI2440 / 11	KUHLMAN HOW	501 6TH W	EDR Hist Auto	371	0.070	WNW
OF2441 / 11	LINDHOLM TORSTEN	502 5TH W	EDR Hist Auto	375	0.071	WNW
LF2442 / 11	LONGHOM CLEANERS	510 MARTIN LUTHER K	EDR Hist Cleaner	375	0.071	East
2443 / 3	NORTH AUSTIN FRAME &	825 KRAMER LN	EDR Hist Auto	376	0.071	WNW
2444 / 11	TRAVIS COUNTY JAIL	1000 SAN ANTONIO ST	TX UST, TX HIST UST	377	0.071	WNW
LB2445 / 11	J. G. MASON	511 E CESAR CHAVEZ S	TX HIST UST	377	0.071	WNW
LB2446 / 11	ACUNA'S	511 E CESAR CHAVEZ S	TX HIST UST	377	0.071	WNW
MQ2447 / 8	TAYLORS DELWOOO CONO	4021 EAST AVE	EDR Hist Auto	377	0.071	ENE
OJ2448 / 11	GULF OIL COMPANY	201 W 2ND ST	TX HIST UST	378	0.072	SSW
OI2449 / 11	ZIMMERMANH E E	503 6TH W	EDR Hist Cleaner	378	0.072	WNW
2450 / 11	MUELLER & BENSON	403 BRAZOS	EDR Hist Auto	379	0.072	NNE
2451 / 11	UNIVERSITY GARAGE AU	1806 SAN ANTONIO ST	EDR Hist Auto	380	0.072	WNW
MQ2452 / 8	SWEET ONE HOUR DRY C	4100 EAST AVE	EDR Hist Cleaner	380	0.072	ENE
2453 / 8	JAMES W L GARAGE	703 38TH W	EDR Hist Auto	381	0.072	ESE
MU2454 / 11	WESTBANK DRY CLEANIN	112 E 4TH ST	TX DRYCLEANERS	381	0.072	NNE
OF2455 / 11	LINDHOLM T F AUTO	500 SAN ANTONIO ST	EDR Hist Auto	381	0.072	WNW
OF2456 / 11	COVERT BUICK CO	505 5TH ST W	EDR Hist Auto	382	0.072	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
OF2457 / 11	COVERT BUICK CO	505 5TH ST W	EDR Hist Auto	382	0.072	WNW
2458 / 11	COR EZELLE JACK SERV	8 SAN JACINTO ST	EDR Hist Auto	382	0.072	WNW
NM2459 / 8	MASTER VALET CLEANER	3101 SPEEDWAY	TX DRYCLEANERS	386	0.073	ESE
NM2460 / 8	MASTER VALET CLEANER	3101 SPEEDWAY ST	EDR Hist Cleaner	386	0.073	ESE
NM2461 / 8	MITTAG WILLIAM O	3101 SPEEDWAY	EDR Hist Cleaner	386	0.073	ESE
OK2462 / 11	BADGER AUTO SUPPLY C	119 W 5TH ST	TX HIST UST	386	0.073	SW
OK2463 / 11	KENICHI RESTAURANT	121 W 5TH ST	TX HIST UST, TX RDR	386	0.073	SW
2464 / 11	AUSTIN LNDRY & DRY	608 24TH W	EDR Hist Cleaner	387	0.073	East
2465 / 20	FORMER SKEET & TRAP		UXO	387	0.073	SSW
2466 / 11	COVERT AUTOMO	420 SAN ANTONIO ST	EDR Hist Auto	387	0.073	WNW
OH2467 / 11	416 20 COVERT AUTO C	416 SAN ANTONIO ST	EDR Hist Auto	387	0.073	WNW
OI2468 / 11	LARSONS GARAGE AUTO	504 6TH ST W	EDR Hist Auto	387	0.073	WNW
OI2469 / 11	LARSONS GAR AUTO REP	504 6TH W	EDR Hist Auto	387	0.073	WNW
OL2470 / 6	HOWARD MCELROY	6607 SHIRLEY AVE	TX UST, TX HIST UST	388	0.073	ESE
OL2471 / 6	AUTOMOTIVE REFINISH	6615 SHIRLEY AVENUE	RCRA-SQG, FINDS, ECHO	388	0.073	ESE
LG2472 / 11	NATIONAL FINANCE CO	413 CONGRESS AVE	EDR Hist Auto	388	0.073	SSW
OM2473 / 14	REFUEL 329	31 N IH 35	TX UST, TX ASBESTOS, TX Financial Assura...	389	0.074	NNE
2474 / 20	AUSTIN BERGSTROM INT		PFAS ECHO	390	0.074	NW
OM2475 / 14	FAST N EASY SHELL	31 N HWY 35	EDR Hist Auto	392	0.074	NNE
OM2476 / 14	CITY STAR FOODS	31 N I 35	TX HIST UST, TX RDR	392	0.074	NNE
2477 / 11	GREENBERG GRANT & RI	80 RED RIVER ST	EDR Hist Auto	393	0.074	WNW
2478 / 3	CONANN DEVELOPMENT	11220 N LAMAR BLVD	TX UST, TX HIST UST	394	0.075	WNW
MZ2479 / 11	HASSE SERVICE STATIO	1511 LAVACA	EDR Hist Auto	395	0.075	ESE
ON2480 / 14	ST. EDWARDS UNIVERSI	3001 S CONGRESS	TX RDR	396	0.075	ESE
ON2481 / 14	ST EDWARDS UNIVERSIT	3001 S CONGRESS AVE	TX AST	396	0.075	ESE
ON2482 / 14	ST EDWARDS UNIVERSIT	3001 S CONGRESS AVE	TX UST, TX HIST UST, TX AIRS, TX ASBESTO...	396	0.075	ESE
2483 / 11	UNIVERSITY BODY	1409 LAVACA	EDR Hist Auto	396	0.075	ESE
OO2484 / 8	WR ROBBINS SECONDARY	3908 AVENUE B	TX Ind. Haz Waste	396	0.075	WNW
OO2485 / 8	AUSTIN ISD	3908 AVENUE B	RCRA NonGen / NLR, FINDS, ECHO	396	0.075	WNW
LT2486 / 11	LAVACA ST GARAGE	1417 LAVACA ST	EDR Hist Auto	396	0.075	ESE
MQ2487 / 8	EVANS DELWOOD CONOCO	4201 EAST AVE	EDR Hist Auto	396	0.075	ENE
OP2488 / 6	DOLLARS & SENSE DRY	6929 AIRPORT BLVD ST	TX ASBESTOS, TX DRYCLEANERS	396	0.075	ESE
OP2489 / 6	RAILYARD	6929 AIRPORT BLVD	EDR Hist Cleaner	396	0.075	ESE
MR2490 / 11	1311 13 YOUNG & SCHI	1311 LAVACA ST	EDR Hist Auto	396	0.075	ESE
MR2491 / 11	SPRINKLES BODY SHOP	1305 LAVACA	EDR Hist Auto	396	0.075	ESE
MZ2492 / 11	BATTERY SERVICE CO	1603 LAVACA ST	EDR Hist Auto	397	0.075	ESE
LT2493 / 11	KALLGREN & HAMILTON	1419 LAVACA ST	EDR Hist Cleaner	397	0.075	ESE
LT2494 / 11	KING I B STOVE	1419 LAVACA ST	EDR Hist Auto	397	0.075	ESE
MR2495 / 11	LUDER FRED AUTO REPR	1313 LAVACA ST	EDR Hist Auto	397	0.075	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
2496 / 3	FERRIS FRAME ALLGNME	830 SAGEBRUSH DR	EDR Hist Auto	397	0.075	WNW
2497 / 8	EXXON MOBIL CORPORAT	619 W NORTH LOOP 35	EDR Hist Auto	399	0.076	ESE
OQ2498 / 11	WALLACE ENGRAVING CO	407 LAVACA STREET	RCRA NonGen / NLR, FINDS, ECHO	400	0.076	ESE
OQ2499 / 11	WALLACE ENGRAVING	407 LAVACA ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	400	0.076	ESE
2500 / 6	CENTRAL ELECTRICAL A	6719 SHIRLEY AVE	TX HIST UST	401	0.076	ESE
MO2501 / 14	TOWN LAKE CHEVRON SE	30 INTERREGIONAL HWY	EDR Hist Auto	401	0.076	NE
NX2502 / 11	DARTER WELDING	408 SAN JACINTO ST	EDR Hist Auto	402	0.076	NNE
NX2503 / 11	SAN JACINTO CLEANERS	408 SAN JACINTO BLV	EDR Hist Cleaner	402	0.076	NNE
2504 / 21	WATTINGER CO., INC.	114 RALPH ABLANEDO D	TX HIST UST	402	0.076	WNW
LA2505 / 11	J. C. BRYANT CREAMER	200 W 5TH ST	TX HIST UST	403	0.076	WSW
NM2506 / 8	AUSTINS HOME LNDRY	104 31ST E	EDR Hist Cleaner	404	0.077	ESE
NM2507 / 8	MALMBERG H G AUTO	104 31ST E	EDR Hist Auto	404	0.077	ESE
NL2508 / 11	HONG LEE MRS CHINESE	411 CONGRESS AVE	EDR Hist Cleaner	404	0.077	SSW
2509 / 11	GULF INTRACOASTAL CA	221 E 9TH ST STE 206	EDR Hist Auto	404	0.077	ESE
OR2510 / 14	POWELL OFFSET SERVIC	2007 S 1ST ST	TX Ind. Haz Waste	405	0.077	WNW
NA2511 / 11	M. H. CROCKETT	319 S CONGRESS AVE	TX HIST UST	405	0.077	SSW
2512 / 14	REX CLEANERS DCLO CL	200 MARY W	EDR Hist Cleaner	405	0.077	WNW
OQ2513 / 11	TEXAS COMPANY	213 W 5TH ST	TX HIST UST	406	0.077	ESE
OQ2514 / 11	CATHERINE UMSTATTD	213 W 5TH ST	TX UST	406	0.077	ESE
OQ2515 / 11	VACANT COMMERCIAL BL	213 W 5TH ST	TX HIST UST	406	0.077	ESE
2516 / 14	KNIGHT WM Y	207 MILTON E	EDR Hist Auto	406	0.077	ESE
2517 / 8	J RS AUTO REPR	406 38 1/2 W	EDR Hist Auto	406	0.077	WNW
OS2518 / 17	5901 S CONGRESS	6001 S CONGRESS AVE	TX SWF/LF	408	0.077	ESE
OI2519 / 11	AUSTIN FOREIGN CAR C	510 6TH ST W	EDR Hist Auto	410	0.078	WNW
OI2520 / 11	EUROPEAN SPECIALIZED	510 6TH ST W	EDR Hist Auto	410	0.078	WNW
OI2521 / 11	510 12 AUSTIN AUTOMA	510 6TH W	EDR Hist Auto	410	0.078	WNW
LR2522 / 6	CERTIFIED BRAKES	6507 SHIRLEY AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	410	0.078	ESE
LR2523 / 6	OVERSEAS MOTORS AUTO	6507 SHIRLEY AVE	EDR Hist Auto	410	0.078	ESE
OF2524 / 11	COVERT BUICK	500 W 5TH ST	TX UST, TX HIST UST	410	0.078	WNW
OK2525 / 11	AUSTIN FOUNDRY	200 5TH ST W	EDR Hist Auto	411	0.078	WSW
OT2526 / 8	SIGMOR SHAMROCK SERV	3515 LAMAR BLVD N	EDR Hist Auto	411	0.078	WNW
OT2527 / 8	SNAX BASKET 3 TX0297	3515 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	411	0.078	WNW
MZ2528 / 11	CITIES SERVICE OIL C	1601 LAVACA ST	EDR Hist Auto	412	0.078	ESE
NI2529 / 14	GULF STATION	1900 S 1ST ST	TX HIST UST	413	0.078	WNW
NI2530 / 14	BARBARA LOVELESS HAR	1900 S 1ST ST	TX UST	413	0.078	WNW
NI2531 / 14	JOHN B. LOVELESS	1900 S 1ST ST	TX HIST UST	413	0.078	WNW
NI2532 / 14	JOHN LOVELESS	1900 S 1ST ST	TX HIST UST	413	0.078	WNW
2533 / 3	A PAYLESS AUTOMOTIVE	11116 LAMAR BLVD N	EDR Hist Auto	413	0.078	WNW
NS2534 / 11	KELLY SMITH CLEANERS	509-511 W 19TH	EDR Hist Cleaner	413	0.078	West

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2535 / 14	MORELL ARTH D	500 ACADEMY DR	EDR Hist Auto	414	0.078	SW
2536 / 3	MR SERVICE CENTERS	10200 N LAMAR BLVD	EDR Hist Auto	415	0.079	WNW
OU2537 / 6	PIERPOINT MOTORS	8140 LAMAR BLVD N	EDR Hist Auto	415	0.079	NW
OV2538 / 11	OLD FIRESTONE	901 LAVACA ST	TX HIST UST	415	0.079	ESE
OW2539 / 11	CAPITOL SERVICE STAT	1301 LAVACA	EDR Hist Auto	416	0.079	ESE
NZ2540 / 11	EMPIRE AUTOMOTIVE SE	604 E 7TH ST	EDR Hist Auto	420	0.080	NE
NY2541 / 11		705 RED RIVER	TX HIST UST	421	0.080	NE
OK2542 / 11	FISHER FRANK C AUTO	205 5TH ST W	EDR Hist Auto	421	0.080	WSW
OK2543 / 11	STEINERS SERVICE	205 5TH W	EDR Hist Auto	421	0.080	WSW
2544 / 6	AUBRY HILLS	8926 N LAMAR BLVD	TX IHW CORR ACTION	422	0.080	WNW
2545 / 15	PALM HARBOR HOMES, I	830 BASTROP HIGHWAY	TX Ind. Haz Waste, TX TIER 2	422	0.080	South
OE2546 / 8	KOENIG LANE SERVICE	901 W KOENIG LN	TX RDR	423	0.080	WNW
OE2547 / 8	KOENIG LANE SERVICE	901 W KOENIG LN	TX UST, TX HIST UST, TX Financial Assura...	423	0.080	WNW
OE2548 / 8	AUSTIN WATER WASTEWA	901 W KOENIG LN	TX LPST	423	0.080	WNW
OG2549 / 11	SMITH MOTOR CO AUTO	119 CONGRESS AVE	EDR Hist Auto	424	0.080	SSW
OI2550 / 11	MILLER BLUEPRINT	513 W 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	426	0.081	ESE
OI2551 / 11	MILLER BLUEPRINT COM	513 W 6TH STREET	RCRA NonGen / NLR, FINDS, ECHO	426	0.081	ESE
OK2552 / 11	VIOLET CROWN GARAGE	207 5TH ST W	EDR Hist Auto	426	0.081	WSW
OK2553 / 11	FREUND ROLAND R	207 5TH W	EDR Hist Auto	426	0.081	WSW
MQ2554 / 8	BURCH FOOD MART	4535 E SH 71	TX HIST UST	427	0.081	ENE
MY2555 / 11	AUSTIN CONVENTION CE	THIRD ST RED RIVER	TX UST	428	0.081	WNW
MU2556 / 11	417 21 PATTON TRANSF	417 CONGRESS AVE E	EDR Hist Auto	428	0.081	NNE
NT2557 / 11	RUDYS PHILLIPS	400 CONGRESS AVE	EDR Hist Auto	428	0.081	NNE
MN2558 / 11	AUSTIN GOODYEAR CO	101 CONGRESS AVE	EDR Hist Auto	429	0.081	NNE
OX2559 / 11	E-Z PAWN	99 N I 35	TX HIST UST	430	0.081	ESE
OX2560 / 11	E-Z PAWN SHOP	99 N INTERSTATE 35	TX UST	430	0.081	ESE
2561 / 20	ABIA FOOD & FUEL	2901 SPIRIT OF TEXAS	TX UST, TX HIST UST, TX Financial Assura...	430	0.081	WNW
NX2562 / 11	CABANISS-BROWN FURNI	216 E 4TH ST	TX HIST UST	430	0.081	NNE
NS2563 / 11	KELLV SMITH CLEANERS	511 W 19TH ST	EDR Hist Cleaner	433	0.082	West
OK2564 / 11	ROBINSON A A AUTO	209 5TH ST W	EDR Hist Auto	433	0.082	WSW
OK2565 / 11	LONE STAR SUPPLY CO	209 5TH ST W	EDR Hist Auto	433	0.082	WSW
OY2566 / 8	JIFFY LUBE #2925	3401 N LAMAR BLVD	TX LPST, TX TIER 2, TX CENTRAL REGISTRY	434	0.082	WNW
OY2567 / 8	QUICK LUBE	3401 N LAMAR BLVD	TX HIST UST	434	0.082	WNW
OY2568 / 8	QUICK LUBE AUTO LUBR	3401 LAMAR BLVD N	EDR Hist Auto	434	0.082	WNW
OY2569 / 8	MAGNOLIA PETROLEUM	3401 N LAMAR BLVD	TX HIST UST	434	0.082	WNW
MR2570 / 11	ADOLPH KOHN	217 W 14TH ST	TX HIST UST	434	0.082	ESE
MR2571 / 11	TOM BAKING COMPANY	217 W 14TH ST	TX HIST UST	434	0.082	ESE
OZ2572 / 8	TRAM STOP	3201 N LAMAR BLVD	TX UST, TX HIST UST	435	0.082	WNW
OZ2573 / 8	TRAM STOP	3201 N LAMAR BLVD	TX ASBESTOS, TX Financial Assurance, TX ...	435	0.082	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
OZ2574 / 8	THOMSON PREMIER SERV	3201 LAMAR BLVD N	EDR Hist Auto	435	0.082	WNW
OZ2575 / 8	CIRCLE K 3245	3201 N LAMAR BLVD	TX LPST, TX HIST UST	435	0.082	WNW
OZ2576 / 8	CIRCLE K 3245	3201 N LAMAR BLVD	TX UST	435	0.082	WNW
OY2577 / 8	REIDS LAUNDRY & DRY	3317 N LAMAR BLVD	RCRA NonGen / NLR	436	0.083	WNW
OY2578 / 8	REIDS CLEANERS 5	3317 N LAMAR BLVD	TX HIST UST, TX DRYCLEANERS, TX Ind. Haz...	436	0.083	WNW
OY2579 / 8	MARKLAND EXXON SERVI	3317 LAMAR BLVD N	EDR Hist Auto	436	0.083	WNW
OY2580 / 8	DON LLOYDS TEXACO	3317 N LAMAR BLVD	TX UST, TX HIST UST	436	0.083	WNW
OY2581 / 8	REIDS CLEANERS & LAU	3317 N LAMAR BLVD	EDR Hist Cleaner	436	0.083	WNW
OY2582 / 8	JOASH ENTERPRISES IN	3419 N LAMAR BLVD	EDR Hist Cleaner	436	0.083	WNW
LY2583 / 14	DEISON AUTO REPR	320 CONGRESS AVE S	EDR Hist Auto	436	0.083	NE
PA2584 / 11	DISCOUNT CLEANERS	510 19TH ST W	EDR Hist Cleaner	438	0.083	East
PB2585 / 11	JAS. LUCAS	503 E CESAR CHAVEZ S	TX HIST UST	438	0.083	ESE
OK2586 / 11	NE COR MAGNOLIA PET	211 5TH ST W	EDR Hist Auto	439	0.083	WSW
PC2587 / 18	THE CLOSET FACTORY	113 INDUSTRIAL BLVD	RCRA NonGen / NLR	440	0.083	ESE
OU2588 / 6	AUSTIN HWY TRK PARTS	8204 N LAMAR BLVD	TX Ind. Haz Waste	440	0.083	NW
OU2589 / 6	DISCOUNT DRIVE AXLE	8204 N LAMAR BLVD SU	RCRA NonGen / NLR, FINDS, ECHO	440	0.083	NW
OU2590 / 6	BEAVER & SON AUTO &	8204 LAMAR BLVD N	EDR Hist Auto	440	0.083	NW
OU2591 / 6	FLASHCARDS	8204 N LAMAR SUITE C	RCRA NonGen / NLR, FINDS, ECHO	440	0.083	NW
OU2592 / 6	FLASHCARDS	8204 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	440	0.083	NW
OU2593 / 6	DISCOUNT DRIVE AXLE	8204 N LAMAR BLVD ST	TX Ind. Haz Waste	440	0.083	NW
OK2594 / 11	AUTO SALVAGE CO	419 COLORADO ST	EDR Hist Auto	440	0.083	SW
2595 / 11	CAPITOL LAUNDRY & DR	501 W 24TH ST	EDR Hist Cleaner	441	0.084	West
PB2596 / 11	AUSTIN CONVENTION CE	500 E CESAR CHAVEZ S	RCRA NonGen / NLR	442	0.084	ESE
PB2597 / 11	AUSTIN CONVENTION CE	500 E CESAR CHAVEZ S	TX HIST UST, TX Ind. Haz Waste	442	0.084	ESE
PB2598 / 11	NEW CONVENTION CENTE	500 E 1ST ST	TX UST	442	0.084	ESE
PB2599 / 11	GENES MAGNOLIA SER	500 1ST E	EDR Hist Auto	442	0.084	ESE
LV2600 / 8	M F ROUTE LAUNDRIES	103 E 38TH ST	EDR Hist Cleaner	443	0.084	ESE
OK2601 / 11	TEXAS AMERICAN RESOU		PFAS ECHO	444	0.084	WSW
2602 / 11	CONOCOPHILLIPS COMPA	1122 COLORADO ST STE	EDR Hist Auto	444	0.084	WNW
OK2603 / 11	BEARD SPRING	213 5TH W	EDR Hist Auto	444	0.084	WSW
OK2604 / 11	BEARD SPRING C BRAKE	213 5TH ST W	EDR Hist Auto	444	0.084	WSW
OK2605 / 11	PURYEAR DEWEY	206 5TH W	EDR Hist Auto	444	0.084	WSW
OI2606 / 11	WILBURN SINCLAIR SER	520 6TH ST W	EDR Hist Auto	446	0.084	WNW
OI2607 / 11	BASS SERV STA	520 6TH W	EDR Hist Auto	446	0.084	WNW
2608 / 8	CENTRAL PROPERTIES I	6008 N LAMAR BLVD	TX HIST UST	449	0.085	WNW
OY2609 / 8	RICKS CLEANERS	3411 N LAMAR BLVD	TX DRYCLEANERS	450	0.085	WNW
PD2610 / 11	LEWIS PAUL C LAUNDRY	205 E 15TH ST	EDR Hist Cleaner	450	0.085	ESE
NL2611 / 11	KOCH CHARLES J DYE	405 CONGRESS ST	EDR Hist Cleaner	450	0.085	SSW
OH2612 / 11	AUSTIN CARBONICS	501 E 3RD ST	TX HIST UST	451	0.085	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
OH2613 / 11	FIELDON BERRY	501 W 3RD ST	TX UST	451	0.085	ESE
PE2614 / 11	STAR BRITE CLEANERS	501 W 15TH ST STE A	TX DRYCLEANERS, TX CENTRAL REGISTRY	451	0.085	WNW
PE2615 / 11	MARTINIZING 94177 15	501 W 15TH ST STE A	TX DRYCLEANERS	451	0.085	WNW
2616 / 6	ACCUGRAPHICS	7801 N LAMAR BLVD ST	TX Ind. Haz Waste	452	0.086	ESE
MX2617 / 11	REBECCA A. HEARN	200 E 18TH ST	TX HIST UST	452	0.086	ESE
MM2618 / 11	JOHNSON TIRE COMP.	210 W 7TH ST	TX HIST UST	452	0.086	WNW
OR2619 / 14	PECAN FOOD MART	2101 S 1ST ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	453	0.086	WNW
OR2620 / 14	CURTS OIL CO INC	2101 S FIRST	EDR Hist Auto	453	0.086	WNW
PF2621 / 17	7 ELEVEN STORE 35069	6607 CIRCLE S RD	TX RDR	454	0.086	ESE
PF2622 / 17	7-ELEVEN 39069	6607 CIRCLE S RD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	454	0.086	ESE
PF2623 / 17	RACETRAC PETROLEUM I	6607 CIRCLE S RD	EDR Hist Auto	454	0.086	ESE
PA2624 / 11	CHOTE'S SERVICE CO.	500 W MARTIN LUTHER	TX HIST UST	454	0.086	West
PA2625 / 11	FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	TX LPST	454	0.086	West
PA2626 / 11	FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	TX RDR	454	0.086	West
PA2627 / 11	CHOTES CHEVRON	500 W MARTIN LUTHER	TX UST, TX Ind. Haz Waste	454	0.086	West
PA2628 / 11	LASSBURG & SCHMEDES	500 W MARTIN LUTHER	TX HIST UST	454	0.086	West
PA2629 / 11	CHOTES CHEVRON	500 W MARTIN LUTHER	TX RDR	454	0.086	West
PA2630 / 11	CATHYS CLEANERS MLK	500 W MARTIN LUTHER	TX DRYCLEANERS, TX ENF	454	0.086	West
PA2631 / 11	CHOTES CHEVRON SERVI	500 MARTIN LUTHER KI	EDR Hist Auto	454	0.086	West
PG2632 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	TX UST, TX HIST UST	454	0.086	West
PG2633 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	TX VCP, TX HIST UST, TX GCC, TX Ind. Haz...	454	0.086	West
PG2634 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	RCRA-VSQG, FINDS, ECHO	454	0.086	West
PH2635 / 8	HEART HOSPITAL OF AU	3801 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	455	0.086	WNW
PH2636 / 8	HEART HOSPITAL OF AU	3801 N LAMAR BLVD	RCRA-SQG	455	0.086	WNW
OK2637 / 11	TRATEX AUTO STORAGE	208 5TH W	EDR Hist Auto	455	0.086	WSW
OD2638 / 11	SMITH & HUDLER BROS	406 BRAZOS ST	EDR Hist Auto	456	0.086	SSW
OI2639 / 11	AUSTIN FOREIGN CAR	510 W 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	457	0.087	ESE
2640 / 11	THE SALVATION ARMY C	501 E. 8TH	US BROWNFIELDS, FINDS	457	0.087	NNE
MN2641 / 11	SCHRAMM GULF SERV	107 CONGRESS AVE	EDR Hist Auto	458	0.087	NNE
PI2642 / 19	AUSTIN BEN WHITE FAC	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
PI2643 / 19	CYRUSONE	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
PI2644 / 19	GENERAL MOTORS - AUS	7401 E. BEN WHITE BL	RCRA-VSQG	458	0.087	SW
PI2645 / 19	AUSTIN DATA CENTER A	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
NY2646 / 11	A CRENSHAW GARAGE AU	711 RED RIVER CT	EDR Hist Auto	460	0.087	NE
OS2647 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX CLI	461	0.087	ESE
OS2648 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX HIST LF	461	0.087	ESE
OS2649 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX CLI	461	0.087	ESE
PJ2650 / 14	BRYANT AUTOMOTIVE	505 OLTORF ST W	EDR Hist Auto	463	0.088	West
NK2651 / 11	AUSTIN DAILY TRIBUNE	213 W 10TH ST	TX HIST UST	464	0.088	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
NL2652 / 11	SING LEE CHINESE LAU	403 CONGRESS AVE R	EDR Hist Cleaner	465	0.088	SSW
MQ2653 / 8	HERWICK DON PHILLIPS	4834 EAST AVE	EDR Hist Auto	465	0.088	ENE
PK2654 / 11	TEXAS GOVERNORS MANS	1010 COLORADO ST	TX RDR, TX CENTRAL REGISTRY	465	0.088	WNW
PK2655 / 11	TEXAS GOVERNORS MANS	1010 COLORADO ST	TX UST, TX HIST UST	465	0.088	WNW
NA2656 / 14	RAMIREZ GULF SERVICE	329 CONGRESS AVE S	EDR Hist Auto	466	0.088	NE
NA2657 / 14	BUTLERS GULF SERV	329 CONGRESS AVE S	EDR Hist Auto	466	0.088	NE
2658 / 15	HARVEY MASSEY	6505 E RIVERSIDE DR	TX HIST UST	467	0.088	NNE
2659 / 11	AUSTIN AMERICAN STAT	305 S CONGRESS AVE	TX LPST	469	0.089	SE
NG2660 / 11	CAPITAL CITY TIRE	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2661 / 11		221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2662 / 11	CHASE TOWER 14TH FLO	221 W. 6TH STREET	TX HIST UST, TX ASBESTOS	470	0.089	WNW
NG2663 / 11	GOODYEAR TIRE COMP.	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2664 / 11	GULF REFINING CO.	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2665 / 11	NONO SCHUTZ	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2666 / 11	NOT AVAILABLE	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2667 / 11	CHASE TOWER	221 W 6TH STREET	TX HIST UST, TX ASBESTOS	470	0.089	WNW
NN2668 / 3	AUSTIN SALES	825 PRAIRIE TRL	TX LPST, TX UST, TX HIST UST	471	0.089	WNW
OT2669 / 8	LABORATORY CORPORATI	3701 N LAMAR STE 200	RCRA NonGen / NLR, FINDS, ECHO	471	0.089	WNW
OT2670 / 8	LABCORP AUSTIN	3701 N LAMAR BLVD ST	TX Ind. Haz Waste	471	0.089	WNW
OJ2671 / 11	DEWEYS RADIATOR	112 COLORADO ST	EDR Hist Auto	472	0.089	SSW
2672 / 6	CITY CONSERVATION	625 BRENTWOOD ST	TX HIST UST	472	0.089	ESE
PL2673 / 14	TS CLEANERS AT TWIN	300 E OLTORF ST	TX DRYCLEANERS	473	0.090	NW
PL2674 / 14	GAHAU CLEANERS	300 OLTORF ST E	EDR Hist Cleaner	473	0.090	NW
PL2675 / 14	TWIN OAKS CLEANERS	300 E OLTORF	EDR Hist Cleaner	473	0.090	NW
MN2676 / 11	LINCOLN PROPERTY COM	100 CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	476	0.090	NNE
MN2677 / 11	GRAYBURG OIL CO NO	100 CONGRESS AVE E	EDR Hist Auto	476	0.090	NNE
2678 / 14	SUPER TRANSMISSION	2704 WILSON ST	EDR Hist Auto	476	0.090	WSW
PM2679 / 15	CVS PHARMACY 6945	4405 E RIVERSIDE DR	RCRA-VSQG, FINDS, ECHO	476	0.090	SW
PM2680 / 15	CVS PHARMACY	4405 E RIVERSIDE DR	TX ASBESTOS, TX Ind. Haz Waste	476	0.090	SW
PB2681 / 11	ACME CLEANERS	504 1ST E	EDR Hist Cleaner	476	0.090	WNW
OG2682 / 11	B & B GARAGE	117 CONGRESS AVE	EDR Hist Auto	477	0.090	SSW
OG2683 / 11	MC CULLOUGH D T	116 CONGRESS AVE	EDR Hist Auto	477	0.090	SSW
PN2684 / 11	HERMAN GARAGE	608 INTERREGIONAL HW	EDR Hist Auto	477	0.090	ENE
NW2685 / 11	AUSTIN COMMUNITY COL	824 W 12TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	477	0.090	WNW
NW2686 / 11	AUSTIN COMMUNITY COL	824 W 12TH	RCRA NonGen / NLR, FINDS, ECHO	477	0.090	WNW
MN2687 / 11	PINNERGY	111 CONGRESS AVE STE	TX Ind. Haz Waste	477	0.090	NNE
2688 / 8	ONE HOUR MARTINIZING	704 W 29TH ST	EDR Hist Cleaner	477	0.090	ESE
OK2689 / 11	413 15 POWELL GARAGE	413 COLORADO ST	EDR Hist Auto	478	0.091	SW
OV2690 / 11	E L STECK	217 W 9TH ST	TX HIST UST	478	0.091	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2691 / 8	GRAY P B DCLO CLNR	4413 AVENUE B	EDR Hist Cleaner	478	0.091	NE
OH2692 / 11	PARKING GARAGE N	300 SAN ANTONIO ST	TX UST, TX HIST UST	478	0.091	WNW
OW2693 / 11	LANG CLEANERS	208 13TH W	EDR Hist Cleaner	479	0.091	WNW
PH2694 / 8	KASPER CHAS E CLNS	3810 LAMAR BLVD N	EDR Hist Cleaner	479	0.091	WNW
OK2695 / 11	MAGNOLIA PET CO NO	212 5TH ST W	EDR Hist Auto	479	0.091	WSW
MQ2696 / 8	JAMES BOYCE	5021 E CSSAR CHAVEZ	TX HIST UST	479	0.091	ENE
PN2697 / 11	ADAMS QUADRACYCLE	610 INTERREGIONAL HW	EDR Hist Auto	481	0.091	ENE
PO2698 / 11	JOHNSONS GARAGE	504 7TH W	EDR Hist Auto	482	0.091	ESE
OI2699 / 11	D. A. GROVER	501 W 6TH ST	TX HIST UST	482	0.091	WNW
OI2700 / 11	D. A. GROVER	501 W 6TH ST	TX HIST UST	482	0.091	WNW
OK2701 / 11	EAST 9TH STREET COMP	201 W 5TH ST STE 220	EDR Hist Auto	482	0.091	WSW
OK2702 / 11		201 W 5TH ST	TX HIST UST	482	0.091	WSW
2703 / 14	WILSON OXYGEN & SUPP	150 E BEN WHITE BLVD	TX UST, TX HIST UST	484	0.092	ESE
PA2704 / 11	CHOTES SINCLAIR SERV	500 W 19TH ST	EDR Hist Auto	485	0.092	East
2705 / 6	FURROW BUILDING MATE	8319 N LAMAR	RCRA-VSQG, FINDS, ECHO	485	0.092	SE
NT2706 / 11	WESLEY GEORGE M TA	404 CONGRESS AVE	EDR Hist Cleaner	486	0.092	NNE
OG2707 / 11	DARRELL ROYAL WORK S	104 CONGRESS AVE	EDR Hist Auto	488	0.092	NNE
PP2708 / 19	HELIOVOLT	8201 E RIVERSIDE DR	RCRA NonGen / NLR	488	0.092	SE
PP2709 / 19	EBARA TECHNOLOGIES I	8201 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	488	0.092	SE
PP2710 / 19	PENTAGON TECHNOLOGIE	8201 E RIVERSIDE DR	RCRA-SQG, TX AIRS, TX Ind. Haz Waste, TX...	488	0.092	SE
PP2711 / 19	PRODUCT RESEARCH FAC	8201 E RIVERSIDE DR	TX AIRS, TX Ind. Haz Waste, TX IHW CORR ...	488	0.092	SE
PP2712 / 19	XBIOTECH USA	8201 E RIVERSIDE DR	RCRA NonGen / NLR	488	0.092	SE
PP2713 / 19	XBIOTECH USA	8201 E RIVERSIDE DR	TX Ind. Haz Waste	488	0.092	SE
PQ2714 / 14	AMERICAN CLEANERS	2201 S 1ST ST STE M	TX DRYCLEANERS	490	0.093	WNW
2715 / 14	AUSTIN ISD	201 E MARY	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	492	0.093	ESE
OG2716 / 11	113 15 GULF REFG CO	113 CONGRESS AVE E	EDR Hist Auto	492	0.093	NNE
OM2717 / 14	LAKESICE EXXON PRODU	31 INTERREGIONAL HWY	EDR Hist Auto	492	0.093	NNE
OR2718 / 14	P H BORING	2000 S 1ST ST	TX HIST UST	493	0.093	WNW
OG2719 / 11	DEWEY GARAGE	115 CONGRESS AVE	EDR Hist Auto	493	0.093	SSW
2720 / 14	TOM WALLACE MILLER	313 S CONGRESS AVE	TX HIST UST	494	0.094	NE
PH2721 / 8	DOLLARS & SENSE DRY	3816 N LAMAR BLVD	EDR Hist Cleaner	494	0.094	WNW
OK2722 / 11	POWELL AUTO BODY	409 COLORADO	EDR Hist Auto	495	0.094	SW
PO2723 / 11		504 W 7TH ST	TX HIST UST	496	0.094	ESE
PR2724 / 8	CHARLES T SIKES	1000 W 39TH ST	TX TANKS, TX ASBESTOS, TX CENTRAL REGIST...	496	0.094	WNW
PR2725 / 8	FORMER FUELING FACIL	1000 W 39TH ST	TX LPST	496	0.094	WNW
PR2726 / 8	FORMER FUELING FACIL	1000 WEST 39TH ST	TX RDR	496	0.094	WNW
2727 / 2	HID GLOBAL	611 CENTER RIDGE DR	TX AST	498	0.094	ESE
NG2728 / 11	PETMECKY COIS (COOF?	220 W 6TH ST	TX HIST UST	498	0.094	ESE
OD2729 / 11	MC FARLAND F H	404 BRAZOS ST	EDR Hist Auto	499	0.095	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
2730 / 14	RIVERSIDE FINA SERVI	1100 INTERREGIONAL H	EDR Hist Auto	500	0.095	NNE
ND2731 / 11	FOUR SEASONS HOTEL	98 SAN JACINTO BLVD	RCRA-VSQG, FINDS, ECHO	500	0.095	WNW
ND2732 / 11	THE SHORELINE BUILDI	98 SAN JACINTO BOULE	TX ASBESTOS, TX DRYCLEANERS	500	0.095	WNW
NY2733 / 11	PATTERSONS GARAGE C	716 RED RIVER CT	EDR Hist Auto	504	0.095	NE
PS2734 / 11	ONE HOUR MARTINIZING	907 24TH ST W	EDR Hist Cleaner	504	0.095	West
PS2735 / 11	JACK BROWN CLEANERS	907 W 24TH ST	TX Ind. Haz Waste	504	0.095	West
PS2736 / 11	JACK BROWN CLEANERS	907 W 24TH ST	RCRA NonGen / NLR, FINDS, ECHO	504	0.095	West
PC2737 / 18	CLEANING CO H	115 INDUSTRIAL BLVD	EDR Hist Cleaner	506	0.096	ESE
OT2738 / 8	LAMAR VILLAGE SHELL	3724 LAMAR BLVD N	EDR Hist Auto	507	0.096	WNW
OT2739 / 8	SUB WAY	3724 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	507	0.096	WNW
NY2740 / 11	HICKMAN R L C AUTO	718 RED RIVER CT	EDR Hist Auto	509	0.096	NE
PS2741 / 11	CONVENIENCE INC WASH	916 24TH ST W	EDR Hist Cleaner	511	0.097	West
2742 / 17	KEMAC CORPORATION	113 METEOR DR A	EDR Hist Auto	511	0.097	WNW
PQ2743 / 14	MOTORCYCLE RESSURECT	2209 S 1ST ST	EDR Hist Auto	514	0.097	WNW
OZ2744 / 8	THOMSON PREMIER SERV	3201 LAMAR BLVD N	EDR Hist Auto	515	0.098	WNW
2745 / 19	COASTAL STATES CRUDE	7901 E BEN WHITE BLV	TX Ind. Haz Waste	518	0.098	East
PT2746 / 11	GEST DUTCH CLEANERS	209 E 19TH	EDR Hist Cleaner	519	0.098	ESE
OX2747 / 11	INTERRIGIONAL CONOCO	901 1ST ST E	EDR Hist Auto	519	0.098	ESE
PG2748 / 11	TRANSMIX CONCRETE	812 W CESAR CHAVEZ S	TX HIST UST	520	0.098	West
PU2749 / 14	CUSTOM ENGINE RE	603 MARY W	EDR Hist Auto	520	0.098	WNW
PU2750 / 14	AUSTIN AUTOMOTIVE	603 MARY ST W	EDR Hist Auto	520	0.098	WNW
PV2751 / 6	RAILTON MANUFACTURIN	906 JUSTIN LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	522	0.099	WNW
PV2752 / 6	6909 RYAN DRIVE PROP	906 JUSTIN LN	TX VCP	522	0.099	WNW
OX2753 / 11	HILES JOHN L WASHING	900 1ST ST E	EDR Hist Auto	523	0.099	ESE
2754 / 8	FORMADORY TEXACO	5326 E SH 71	TX HIST UST	526	0.100	ENE
PW2755 / 3	RICHMOND AUTO	828 PRAIRIE TRL	EDR Hist Auto	527	0.100	WNW
PX2756 / 8	FRANKES SLS &	4126 LAMAR BLVD N	EDR Hist Auto	528	0.100	NW
PY2757 / 11	ROGERS BROS SERV STA	200 1ST E	EDR Hist Auto	528	0.100	ENE
PY2758 / 11	J. F. ROBINSON	200 E CESAR CHAVEZ S	TX HIST UST	528	0.100	ENE
2759 / 11	KXAN TV STUDIO	908 W MARTIN LUTHER	TX UST, TX HIST UST, TX Financial Assura...	529	0.100	West
PZ2760 / 17	GOODNIGHT SERV STA	4700 CONGRESS AVE S	EDR Hist Auto	530	0.100	WNW
PZ2761 / 17	ARCHIE FITZGERALD	4700 S CONGRESS AVE	TX HIST UST	530	0.100	WNW
NW2762 / 11	MAGNOLIA PETROLEUM C	837 W 12TH ST	TX HIST UST	532	0.101	WNW
2763 / 11	J J PICKLE FEDERAL O	300 E 8TH ST	TX UST, TX HIST UST, TX ASBESTOS	535	0.101	NNE
PJ2764 / 14	BRYANT AUTOMOTIVE	505 W OLTORF ST	TX UST, TX HIST UST	541	0.102	NW
PR2765 / 8	STA & GARAGE	3900 LAMAR BLVD N	EDR Hist Auto	542	0.103	WNW
2766 / 8	CHIEF CLEANERS	1001 W 34TH ST	EDR Hist Cleaner	546	0.103	WNW
OA2767 / 4	BOSS MANUFACTURING	818 W YAGER LN	TX DRYCLEANERS, TX Ind. Haz Waste, TX CE...	546	0.103	East
NV2768 / 11	BRADSHAW AND PURYEAR	206 E CESAR CHAVEZ S	TX HIST UST	546	0.103	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
QA2769 / 8	AT&T - HOMESTEAD 451	817 W NORTH LOOP BLV	TX HIST UST	547	0.104	WNW
QA2770 / 8	HOMESTEAD 451 CO XP3	817 W NORTH LOOP BLV	TX UST, TX Financial Assurance, TX TIER ...	547	0.104	WNW
QA2771 / 8	SOUTHWESTERN BELL TE	817 W NORTH LOOP BLV	TX HIST UST	547	0.104	WNW
QA2772 / 8	SBC HOMESTEAD 451 CE	817 W NO LOOP BLVD	TX Ind. Haz Waste	547	0.104	WNW
QA2773 / 8	SOUTHWESTERN BELL TE	817 W NORTH LOOP BLV	TX LPST	547	0.104	WNW
QA2774 / 8	SBC	817 N LOOP BLVD	RCRA NonGen / NLR	547	0.104	WNW
QA2775 / 8	NORTH LOOP SOC	819 W NO LOOP BLVD	TX LPST	548	0.104	WNW
QA2776 / 8	AUSTIN HOMESTEAD 451	819 W NO LOOP BLVD	TX LPST	548	0.104	WNW
QA2777 / 8	NORTH LOOP SOC PORT	819 W NO LOOP BLVD	TX UST, TX HIST UST, TX Financial Assura...	548	0.104	WNW
2778 / 14	TOWN LAKE GULF SERVI	901 CLERMONT AVE	EDR Hist Auto	549	0.104	NE
QB2779 / 17	COMMEMORATIVE BRANDS	7211 CIRCLE S RD	TX LPST, TX Ind. Haz Waste, TX IHW CORR ...	549	0.104	ESE
QB2780 / 17	CJC HOLDINGS	7211 CIRCLE S RD	TX UST, TX HIST UST	549	0.104	ESE
QB2781 / 17	COMMEMORATIVE BRANDS	7211 CIRCLE S RD	RCRA-VSQG, FINDS, ECHO	549	0.104	ESE
PS2782 / 11	AUSTIN LAUNDRY & DRY	911 W 24TH ST	EDR Hist Cleaner	552	0.105	West
2783 / 15	FOOD SPOT 2	2538 ELMONT DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	552	0.105	NE
QC2784 / 11	C.A. PETERS	719 E 7TH ST	TX HIST UST	553	0.105	ENE
QC2785 / 11	WALSH SERVICE STATIO	719 E 7TH ST	EDR Hist Auto	553	0.105	ENE
NZ2786 / 11	MOBIL STATION	E 7TH ST	TX LPST	555	0.105	ENE
OT2787 / 8	IMPORT MOTORS	3520 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste, TX CENTR...	556	0.105	WNW
2788 / 6	BANYON AUTOMOTIVE AU	916 BANYAN ST	EDR Hist Auto	556	0.105	WNW
PD2789 / 11	BERANS CONOCO SERV S	1500 SAN JACINTO	EDR Hist Auto	556	0.105	ESE
PD2790 / 11	TEXAS GENERAL SERVIC	1500 SAN JACINTO BLV	TX HIST UST, TX Ind. Haz Waste	556	0.105	ESE
2791 / 3	T&T TRANSMISSION	601 FERGUSON DR	EDR Hist Auto	557	0.105	ESE
QD2792 / 11	7 ELEVEN 16084	1700 SAN JACINTO BLV	TX UST, TX HIST UST	557	0.105	ESE
QD2793 / 11	BURNETTE SERVICE STA	1700 SAN JACINTO	EDR Hist Auto	557	0.105	ESE
OY2794 / 8	MAGNOLIA PETROLEUM C	1002 W 34TH ST	TX HIST UST	557	0.105	WNW
QE2795 / 8	FLOWER STATION	3100 N LAMAR BLVD	TX UST, TX DRYCLEANERS	559	0.106	WNW
QE2796 / 8	R E LEIGH	3100 N LAMAR BLVD	TX HIST UST	559	0.106	WNW
QE2797 / 8	THE FLOWER STATION	3100 N LAMAR BLVD	TX HIST UST	559	0.106	WNW
QE2798 / 8	CAR CARE BV ISSAC	3100 LAMAR BLVD N	EDR Hist Auto	559	0.106	WNW
PC2799 / 18	CHATLEFF CONTROLS	205 INDUSTRIAL BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	560	0.106	ESE
PC2800 / 18	CHATLEFF CONTROLS	205 INDUSTRIAL BLVD	RCRA NonGen / NLR, FINDS, ECHO	560	0.106	ESE
2801 / 6	SMS TRADING USA INC	9036 N LAMAR BLVD AP	EDR Hist Cleaner	562	0.106	WNW
2802 / 11	MESSER & HATCHER	205 W 5TH ST	TX HIST UST	564	0.107	WSW
QF2803 / 11	AUSTIN WATER LIGHT A	W. 5TH STREET	EDR MGP	565	0.107	WNW
QG2804 / 6	A&B RUG & CARPET	654 CANION	EDR Hist Cleaner	566	0.107	ESE
QH2805 / 11	HERBERT MEYER	828 W 6TH ST	TX HIST UST	568	0.108	WNW
QI2806 / 11	DOWNTOWN RAILYARD PR	800 E 4TH ST	TX AUL, TX VCP, TX BROWNFIELDS, TX GCC	568	0.108	East
QI2807 / 11	PLAZA SALTILLO	800 E 4TH ST	RCRA NonGen / NLR	568	0.108	East

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
QJ2808 / 8	UNIVERSITY SCHWINN C	2901 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	570	0.108	WNW
QK2809 / 11	GENERAL SERVICES COM	1518 SAN JACINTO BLV	RCRA-VSQG, FINDS, ECHO	573	0.109	ESE
QK2810 / 11	GENERAL SERVICES COM	1518 SAN JACINTO BLV	TX LPST, TX HIST UST, TX Ind. Haz Waste	573	0.109	ESE
PD2811 / 11	STATE SERVICE STATIO	1502 SAN JACINTO BLV	TX LPST, TX UST	573	0.109	ESE
QK2812 / 11	DOC & BUSTER SERV	1508 SAN JACINTO	EDR Hist Auto	573	0.109	ESE
PS2813 / 11	AUSTIN LAUNDRY & DRY	913 W 24TH ST	EDR Hist Cleaner	575	0.109	West
QL2814 / 20	TRANSPORTATION SECUR	3600 3600 PRESIDENTI	RCRA-SQG	578	0.109	South
QL2815 / 20	GAT AIRLINE GROUND S	3600 PRESIDENTIAL BL	FINDS, ECHO, PFAS ECHO	578	0.109	South
QL2816 / 20	UNITED AIRLINES	3600 PRESIDENTIAL BL	TX ASBESTOS, TX Ind. Haz Waste, TX TIER ...	578	0.109	South
QF2817 / 11	SMITH JAY BODY SHOP	832 5TH ST W	EDR Hist Auto	578	0.109	WNW
2818 / 21	DAVE TRANSPORTATION	8300 IH 35 S ACCESS	RCRA NonGen / NLR	584	0.111	ESE
2819 / 19	MONTOPOLIS CDC	2404 THRASHER	US BROWNFIELDS	587	0.111	SSW
QM2820 / 11	UNIVERSITY SIGN SHOP	2920 SAN JACINTO	TX RDR	587	0.111	East
QM2821 / 11	UNIVERSITY SIGN SHOP	2920 SAN JACINTO BLV	TX UST, TX HIST UST	587	0.111	East
QM2822 / 11	UT SIGN SHOP	2920 SAN JACINTO BLV	TX NON REGIST PST	587	0.111	East
QN2823 / 11	CAPITOL LAUNDRY	801 BARTON SPRINGS	EDR Hist Cleaner	590	0.112	WNW
QN2824 / 11	CAPITOL LAUNDRY & DR	801 BARTON SPRINGS	EDR Hist Cleaner	590	0.112	WNW
OT2825 / 8	BRAKE CHECK	3700 LAMAR BLVD N	EDR Hist Auto	590	0.112	WNW
QC2826 / 11	MOBIL MART	717 7TH ST E	EDR Hist Auto	595	0.113	ENE
QC2827 / 11	WALSH SERVICE CENTER	717 7TH ST E	EDR Hist Auto	595	0.113	ENE
QO2828 / 3	Z CAR SHOP	811 MCPHAUL	EDR Hist Auto	596	0.113	WNW
QO2829 / 3	MINGOS BODY SHOP	811 MCPHAUL ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	596	0.113	WNW
PS2830 / 11	CONVENIENCE COIN LAU	915 W 24TH ST	EDR Hist Cleaner	599	0.113	West
2831 / 11	BROWN BROS	1600 SAN JACINTO	EDR Hist Cleaner	599	0.113	ESE
PR2832 / 8	CARL M. TEMPLETON	3906 N LAMAR BLVD	TX HIST UST	600	0.114	WNW
QP2833 / 14	CAPITAL PRINTING CO	213 E ALPINE RD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	600	0.114	ESE
QP2834 / 14	CAPITAL PRINTING	213 E ALPINE RD	TX Ind. Haz Waste	600	0.114	ESE
PX2835 / 8	A-TEX AUSTIN INC	4106 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	603	0.114	NW
2836 / 6	BLACK & DECKER	911 W ANDERSON LN	TX Ind. Haz Waste, TX CENTRAL REGISTRY	606	0.115	WNW
PQ2837 / 14	LEE MANERS	601 W LIVE OAK ST	TX HIST UST	609	0.115	WNW
QQ2838 / 11	HUMBLE OIL REFG CO	1800 SAN JACINTO ST	EDR Hist Auto	609	0.115	ESE
QQ2839 / 11	KOCUREK WILLIE	1822 SAN JACINTO ST	EDR Hist Auto	610	0.116	ESE
QQ2840 / 11	WESLEY GEO DCLO CLNR	1818 SAN JACINTO	EDR Hist Cleaner	610	0.116	ESE
QQ2841 / 11	KOCUREKS SERVICE STA	1818 SAN JACINTO	EDR Hist Auto	610	0.116	ESE
QC2842 / 11	WALSH NORMAN SERVICE	719 7TH ST E	EDR Hist Auto	611	0.116	ENE
QC2843 / 11	BROWN & WALSH SERV S	719 7TH E	EDR Hist Auto	611	0.116	ENE
PW2844 / 3	PRONTO ENGINE & TRAN	830 PRAIRIE TRL	EDR Hist Auto	611	0.116	WNW
QR2845 / 6	A E D AUTO UPHOLSTER	615 POWELL LN W	EDR Hist Auto	612	0.116	SE
PX2846 / 8	LONE STAR CYCLE MOTI	4108 LAMAR BLVD N	EDR Hist Auto	618	0.117	NW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
PX2847 / 8	REED PHILLIPS OIL CO	4108 N LAMAR BLVD	TX HIST UST	618	0.117	NW
QS2848 / 6	COMET CLEANERS	9515 N LAMAR STE 108	RCRA NonGen / NLR, FINDS, ECHO	620	0.117	ESE
QS2849 / 6	COMET CLEANERS	9515 LAMAR BLVD N	EDR Hist Cleaner	620	0.117	ESE
QS2850 / 6	STAR BRITE CLEANERS	9515 N LAMAR BLVD ST	TX DRYCLEANERS, TX Ind. Haz Waste, TX CE...	620	0.117	ESE
QJ2851 / 8	MCBRIDES GUNS	2913 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	620	0.117	WNW
2852 / 11	CENTRAL FREIGHT LINE	901 E 4TH ST	TX HIST UST	620	0.117	East
QR2853 / 6	BRITISH MOTOR CAR SE	617 W POWELL LN # A	TX Ind. Haz Waste, TX CENTRAL REGISTRY	621	0.118	SE
PD2854 / 11	LES & MACS SERV	301 15TH E	EDR Hist Auto	623	0.118	ESE
QR2855 / 6	B CAMERON AUTOMOTIVE	611 POWELL LN W	EDR Hist Auto	623	0.118	SE
2856 / 6	STANFORD GUY REPR SH	508 JOAN OF ARC	EDR Hist Auto	628	0.119	ESE
2857 / 16	RUTLAND AUTO PARTS	1127 BASTROP HWY	EDR Hist Auto	633	0.120	ENE
PT2858 / 11	TXDOT RIGHT OF WAY	S MLK & E SAN JACINT	TX RDR	636	0.120	ESE
PT2859 / 11	TX DOT ROW	E MARTIN LUTHER KING	TX TANKS, TX CENTRAL REGISTRY	636	0.120	ESE
QT2860 / 14	H.A. GUERRERO CARPET	2313 S 1ST ST	TX HIST UST	640	0.121	West
QT2861 / 14	H A GUERRO CARPET CL	2313 S 1ST	TX RDR	640	0.121	West
2862 / 15	PRIME MOBILE LUBE	1405 MONTOPOLIS DRIV	RCRA NonGen / NLR, FINDS, ECHO	641	0.121	NNE
QD2863 / 11	DEATHE TEXACO SERV	1701 SAN JACINTO	EDR Hist Auto	642	0.122	ESE
QD2864 / 11	STATE PURCHASING AND	1711 SAN JACINTO BLV	TX ASBESTOS, TX Ind. Haz Waste	642	0.122	ESE
QD2865 / 11	STATE PURCHASING AND	1711 SAN JACINTO BLV	RCRA NonGen / NLR, FINDS, ECHO	642	0.122	ESE
QU2866 / 11	SMITH J E R	305 13TH E	EDR Hist Cleaner	643	0.122	ESE
QK2867 / 11	SAN JACINTO GARAGE	1511 SAN JACINTO ST	EDR Hist Auto	643	0.122	ESE
QC2868 / 11	TETCO #1167	717 E 7TH ST	TX RDR	644	0.122	ENE
QC2869 / 11	MOBIL OIL 00AFT	717 E 7TH ST	RCRA NonGen / NLR	644	0.122	ENE
QC2870 / 11	7-ELEVEN 36422	717 E 7TH ST	TX UST, TX HIST UST, TX ENF, TX Financia...	644	0.122	ENE
QC2871 / 11	MOBIL OIL 00AFT	717 E 7TH ST	TX LPST, TX ASBESTOS, TX Ind. Haz Waste	644	0.122	ENE
QC2872 / 11	WALSH SERVICE CENTER	717 E 7TH ST	EDR Hist Auto	644	0.122	ENE
QC2873 / 11	7-ELEVEN INC STORE N	717 E 7TH ST	TX RDR	644	0.122	ENE
QV2874 / 11	CULLEN SERVICE STA	1407 SAN JACINTO	EDR Hist Auto	644	0.122	ESE
QV2875 / 11	EMMETT SINCLAIR SERV	1409 SAN JACINTO ST	EDR Hist Auto	644	0.122	ESE
QG2876 / 6	BANNER SIGNS	650 CANION ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	646	0.122	ESE
QW2877 / 8	TEXAS ALLERGY & ASTH	4150 N LAMAR BLVD	TX UST	647	0.123	NW
QW2878 / 8	CONTINENTAL OIL COMP	4150 N LAMAR BLVD	TX HIST UST	647	0.123	NW
QW2879 / 8	TX ALLERGY ASTHMA CE	4150 N LAMAR BLVD	TX HIST UST	647	0.123	NW
QM2880 / 11	PAYLESS GAS NO 657	2805 SAN JACINTO BLV	EDR Hist Auto	647	0.123	East
QX2881 / 11	TRANSMISSION EVENTS	501 N INTERSTATE 35	EDR Hist Auto	648	0.123	East
QU2882 / 11	DAY R L GARAGE	1301 SAN JACINTO ST	EDR Hist Auto	648	0.123	ESE
QO2883 / 3	AMS INC	903 MC PHAUL ST	TX HIST UST	650	0.123	WNW
QY2884 / 14	FESTIVAL BEACH FOOD	35 WALLER ST	TX BROWNFIELDS	655	0.124	NNE
QY2885 / 14	FESTIVAL BEACH FOOD	35 WALLER STREET	US BROWNFIELDS	655	0.124	NNE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2886 / 11	SEAHOLM DISTRICT UPR	NO ADDRESS RAILROAD	TX BROWNFIELDS	657	0.124	West
2887 / 8	EXXON 6 2790	619 N IH 35	TX RDR	658	0.125	ESE
2888 / 8	SAM PAYNE	1010 W 38TH ST	TX HIST UST	659	0.125	WNW
QZ2889 / 3	HAIS AUTOMOTIVE	842 SAGEBRUSH DR	TX UST	660	0.125	WNW
RA2890 / 3	NETTLE WELDING WORKS	825 WAGON TRL	TX Ind. Haz Waste, TX CENTRAL REGISTRY	670	0.127	WNW
RA2891 / 3	NETTLE	825 WAGON TRL	TX Ind. Haz Waste	670	0.127	WNW
QT2892 / 14	I. E. STUBBS	2318 S 1ST ST	TX HIST UST	676	0.128	WNW
RB2893 / 11	US POSTAL SERVICE AU	300 E 9TH ST	RCRA-VSQG, FINDS, ECHO	680	0.129	ESE
RB2894 / 11	US POSTAL SERVICE AU	300 E 9TH ST	TX Ind. Haz Waste	680	0.129	ESE
2895 / 14	RBJ REDEVELOPMENT PR	21 WALLER ST	TX TANKS, TX HIST UST, TX RDR, TX CENTRA...	685	0.130	NE
2896 / 8	LAMAR VILLAGE SHOPPI	3800 N LAMAR BLVD	TX TANKS, TX CENTRAL REGISTRY	686	0.130	WNW
RC2897 / 17	RUDYS AUTOMOTIVE	4431 LUCKSINGER LN	TX COMP HIST, TX RDR, TX CENTRAL REGISTR...	696	0.132	ESE
RC2898 / 17	RUDYS AUTOMOTIVE	4431 LUCKSINGER LN	TX UST	696	0.132	ESE
RD2899 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	TX NON REGIST PST	699	0.132	SW
RD2900 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	699	0.132	SW
RD2901 / 21	PENSKE TRUCK RENTAL	8800 SOUTH CONGRESS	TX RDR	699	0.132	SW
RD2902 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	RCRA-VSQG	699	0.132	SW
RE2903 / 18	BUTLER PAPER	200 E SAINT ELMO RD	TX UST	706	0.134	ESE
RE2904 / 18	BUTLER PAPER CO	200 E ST ELMO RD	TX HIST UST	706	0.134	ESE
QF2905 / 11	LITTLE & GOSLIN	817 W 5TH ST	TX HIST UST	716	0.136	WNW
RF2906 / 11	FREEWHEELING	2404 SAN GABRIEL ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	717	0.136	West
2907 / 14	US DEPARTMENT OF JUS	55 N IH 35	RCRA NonGen / NLR	722	0.137	ESE
RG2908 / 11	CAPITOL CITY CHEVRON	601 N I 35	TX HIST UST	723	0.137	ENE
RE2909 / 18	DELSTAR TECHNOLOGIES		PFAS ECHO	744	0.141	ESE
2910 / 15	MABEL DAVIS PARK - C	INT. OF WOODWARD & B	SEMS-ARCHIVE	744	0.141	SSW
RE2911 / 18	VERITIV CORPORATION	210 E ST ELMO RD	RCRA-SQG	750	0.142	ESE
RE2912 / 18	VERITIV OPERATING	210 E SAINT ELMO RD	TX Ind. Haz Waste	750	0.142	ESE
RE2913 / 18	VERITIV OPERATING	210 210 E SAINT ELMO	RCRA-SQG	750	0.142	ESE
RG2914 / 11	EXXON #62790	619 N I 35	TX HIST UST	754	0.143	ENE
RH2915 / 11	AMERICAN CLEANERS	907 W 12TH ST	TX DRYCLEANERS	754	0.143	WNW
RH2916 / 11	AMERICAN CLEANERS	907 W 12TH STREET	RCRA-VSQG	754	0.143	WNW
QX2917 / 11	W.C. ROUNDTREE	900 E 5TH ST	TX HIST UST	770	0.146	East
QX2918 / 11	SOUTHERN PACIFIC TRA	900 E 5TH ST	TX HIST UST	770	0.146	East
2919 / 6	AUSTIN WASTE OIL SER	7300B MARCELL ST	TX Ind. Haz Waste	773	0.146	ESE
QH2920 / 11	RED MCCOMBS COLLISDI	841 W 6TH ST	TX Ind. Haz Waste	778	0.147	WNW
QH2921 / 11	RED MCCOMBS COLLISIO	841 W 6TH STREET	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	778	0.147	WNW
RF2922 / 11	EXXON CO. USA 64674	1004 W 24TH ST	TX HIST UST, TX Ind. Haz Waste	799	0.151	West
RF2923 / 11	EXXON MOBIL	1004 W 24TH ST	TX Ind. Haz Waste	799	0.151	West
RF2924 / 11	EXXON MOBIL CORPORAT	1004 W 24TH ST	RCRA NonGen / NLR, FINDS, ECHO	799	0.151	West

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2925 / 11	EMIL HAENEL, JR.	311 E 15TH ST	TX HIST UST	816	0.155	ESE
RI2926 / 20	THE HERTZ CORPORATIO	9401 RENTAL CAR LANE	TX HIST UST, TX TIER 2	825	0.156	WNW
RI2927 / 20	HERTZ RENT-A-CAR 163	9401 RENTAL CAR LN	TX AST	825	0.156	WNW
2928 / 2	CARMAX 7154	13300 N IH 35	TX UST, TX HIST UST, TX AIRS, TX Financi...	833	0.158	North
2929 / 15	ORACLE AMERICA WATER	2300 CLOUD WAY	TX AST	835	0.158	NE
QZ2930 / 3	GERMAN AUTOHAUS	902 SAGEBRUSH DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	839	0.159	WNW
RG2931 / 11	EXXON RS 62790	619 N IH 35	TX UST, TX Financial Assurance	839	0.159	ENE
RJ2932 / 11	TARGET STORE T3342	901 E 5TH ST STE 140	RCRA-SQG	842	0.159	East
RJ2933 / 11	TARGET STORE T3342	901 E 5TH ST STE 140	TX Ind. Haz Waste	842	0.159	East
2934 / 17	SALVATION ARMY SOUTH	4216 SOUTH CONGRESS	US BROWNFIELDS	848	0.161	WNW
RG2935 / 11	PRIME FOOD MART	601 N IH 35	TX UST, TX Financial Assurance	853	0.162	ENE
RK2936 / 8	WHITAKER FIELDS	4901 N GUADALUPE	TX UST	855	0.162	ESE
RK2937 / 8	WHITAKER FIELDS	4901 GUADALUPE ST	TX HIST UST	855	0.162	ESE
RL2938 / 11	SAFE WAY RENTAL TOWE	311 BOWIE ST	TX VCP, TX ASBESTOS, TX CENTRAL REGISTRY	857	0.162	WNW
RL2939 / 11	SAFEWAY RENTAL EQUIP	311 BOWIE ST	TX LPST, TX VCP	857	0.162	WNW
RL2940 / 11	SAFEWAY RENTAL TRACT	311 BOWIE ST	TX RDR	857	0.162	WNW
RL2941 / 11	SAFEWAY RENTAL EQUIP	311 BOWIE ST	TX UST	857	0.162	WNW
RM2942 / 11	CITY OF AUSTIN	715 E 8TH ST	RCRA NonGen / NLR, FINDS, ECHO	863	0.163	NE
RM2943 / 11	CITY OF AUSTIN POLIC	715 E 8TH ST	TX ASBESTOS, TX Ind. Haz Waste	863	0.163	NE
RM2944 / 11	POLICE DEPARTMENT HE	715 E 8TH ST	TX UST, TX HIST UST, TX Financial Assura...	863	0.163	NE
2945 / 11	UNION PACIFIC REALTY	900 W CESAR CHAVEZ S	TX HIST UST	863	0.163	West
2946 / 11	CLOSED GASOLINE STAT	2803 SAN JACINTO BLV	TX LPST, TX UST, TX HIST UST	864	0.164	East
2947 / 14	SUNRISE MINI MART 8	539 W OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	868	0.164	West
RA2948 / 3	MOLINA AUTOMOTIVE	903 WAGON TRL	TX UST, TX HIST UST	869	0.165	WNW
RA2949 / 3	MOLINA AUTOMOTIVE	903 WAGON TRAIL	TX RDR	869	0.165	WNW
RN2950 / 6	AMERICAN PRINTERS EX	630 CANION ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	877	0.166	ESE
RO2951 / 16	SB WINGFIELD LANDFIL	1111 OLD BASTROP HWY	TX Ind. Haz Waste	880	0.167	East
RO2952 / 16	AUSTIN VEE DUB	1111 OLD BASTROP HWY	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	880	0.167	East
RO2953 / 16	HARMON PROPERTIES LA	1111 OLD BASTROP HWY	TX SWF/LF	880	0.167	East
RO2954 / 16	SB WINGFIELD LANDFIL	1111 OLD BASTROP HWY	TX SWF/LF	880	0.167	East
RP2955 / 11	AUSTIN METAL & IRON	301 SAN MARCOS ST	TX UST, TX HIST UST	886	0.168	ESE
RP2956 / 11	AUSTIN METAL IRON	301 SAN MARCOS ST	TX LPST, TX VCP, TX GCC, TX COMP HIST, T...	886	0.168	ESE
RO2957 / 16	UNIVAC OF TEXAS	1115 OLD BASTROP HWY	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	886	0.168	East
RO2958 / 16	AA AUTO & EQUIPMENT	1115 OLD BASTROP HWY	TX UST	886	0.168	East
RH2959 / 11	RILEY SEVERN	919 W 12TH ST	TX HIST UST	896	0.170	WNW
RH2960 / 11	RILEY SEVERN	919 W 12TH ST	TX HIST UST	896	0.170	WNW
2961 / 8	MCCALLUM HIGH SCHOOL	5600 SUNSHINE DR	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	899	0.170	WNW
2962 / 14	THE LITHOPRINT CO	1825 S IH 35	RCRA NonGen / NLR	905	0.171	WSW
RQ2963 / 14	SOUTH AUSTIN SERVICE	3815 WOODBURY DR	TX LPST, TX UST, TX HIST UST	905	0.171	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
RR2964 / 11	GEORGE COFFEY LINCOL	900 W 6TH ST	TX HIST UST	907	0.172	WNW
RR2965 / 11	GEORGE COFFEY LINC-M	900 W 6TH	TX UST	907	0.172	WNW
RQ2966 / 14	PREFERRED PUMP	3805 WOODBURY DR	TX UST	917	0.174	ESE
RQ2967 / 14	PERFERRED PUMP	3805 WOODBURY	TX RDR	917	0.174	ESE
2968 / 11	SEAHOLM DISTRICT UPR	S 3RD STREET BETWEEN	US BROWNFIELDS, FINDS	917	0.174	WNW
RL2969 / 11	PROPOSED SPRING COND	302 BOWIE ST	TX IHW CORR ACTION	928	0.176	WNW
RS2970 / 11	7 ELEVEN STO4RE 3664	814 E 7TH ST	TX LPST, FINDS	929	0.176	ENE
RS2971 / 11	AUSTIN SHELL/STORE 4	814 E 7TH ST	TX RDR	929	0.176	ENE
RS2972 / 11	TP 2519	814 E 7TH ST	TX RDR	929	0.176	ENE
RT2973 / 11	COFFEY LINCOLN MERCU	900 6TH ST	RCRA NonGen / NLR, FINDS, ECHO	929	0.176	ENE
RT2974 / 11	COFFEY LINCOLN MERCU	900 E 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	929	0.176	ENE
RT2975 / 11	ARMADILLO AUTOMOTIVE	901 E 6TH ST	TX RDR	936	0.177	East
RT2976 / 11	VACANT BRICK BUILDIN	901 E. 6TH STREET	TX HIST UST, TX ASBESTOS	936	0.177	East
RT2977 / 11	ARMADILLO AUTO	901 E 6TH ST	TX HIST UST	936	0.177	East
RU2978 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX CLI	940	0.178	WNW
RU2979 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX CLI	940	0.178	WNW
RU2980 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX HIST LF	940	0.178	WNW
RL2981 / 11	BALCONES SPORTSWEAR	910 W 3RD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	940	0.178	WNW
RM2982 / 11	CITY OF AUSTIN FLEET	714 E 8TH ST	RCRA NonGen / NLR, FINDS, ECHO	945	0.179	NE
RM2983 / 11	VES SERVICE CENTER 5	714 E 8TH ST	TX UST, TX HIST UST, TX AIRS, TX Financi...	945	0.179	NE
RM2984 / 11	CITY OF AUSTIN VES S	714 E 8TH ST	TX ASBESTOS, TX Ind. Haz Waste	945	0.179	NE
RV2985 / 8	SHELL FOOD MART	4001 MEDICAL PKWY	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	947	0.179	WNW
2986 / 3	K & M SUPPLY	908 MC PHAUL ST	TX HIST UST	947	0.179	WNW
RW2987 / 8	TERMINIX COMPANY	4326 N LAMAR BLVD	TX HIST UST	949	0.180	NNW
RN2988 / 6	KO MACHINE	620 CANION ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	952	0.180	ESE
RX2989 / 11	SOUTHLAND REDDY ICE	901 RED RIVER ST	TX LPST	956	0.181	NE
RX2990 / 11	REDDY ICE	901 RED RIVER ST	TX UST, TX SPILLS	956	0.181	NE
RO2991 / 16	AUTOMOTIVE RECYCLING	1125 BASTROP HWY	TX HIST UST	975	0.185	ENE
RY2992 / 11	OLD TOWNSENDS TEXACO	2511 SAN JACINTO	TX LPST	976	0.185	East
RY2993 / 11	OLD TOWNSENDS TEXACO	2511 SAN JACINTO BLV	TX HIST UST	976	0.185	East
RX2994 / 11	OAK FARMS DAIRY	611 E 9TH ST	TX HIST UST	978	0.185	NE
RZ2995 / 2	RAVEN INDUSTRIES INC		PFAS ECHO	994	0.188	ESE
RW2996 / 8	CENTRAL TEX. REG. BL	4300 N LAMAR BLVD	TX HIST UST	1000	0.189	NNW
SA2997 / 18	TCI COATINGS INC	220 INDUSTRIAL BLVD	RCRA NonGen / NLR	1010	0.191	ESE
SA2998 / 18	TECHNICAL COATINGS	220 INDUSTRIAL BLVD	TX UST	1010	0.191	ESE
SA2999 / 18	TCI COATINGS	220 INDUSTRIAL BLVD	TX Ind. Haz Waste, TX RDR, TX CENTRAL RE...	1010	0.191	ESE
RS3000 / 11	JIM TENNISON ONE STO	701 N I 35	TX HIST UST	1015	0.192	ENE
RS3001 / 11	7-ELEVEN #36643	701 N I 35	TX HIST UST	1015	0.192	ENE
RZ3002 / 2	AUSTIN TECHNOLOGY CE	500 CENTER RIDGE DR	TX Ind. Haz Waste	1016	0.192	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
RZ3003 / 2	QUANTUM CLEAN	500 CENTER RIDGE DR	RCRA NonGen / NLR, FINDS, ECHO	1016	0.192	ESE
3004 / 18	BEN WHITE U HAUL	304 E BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST	1017	0.193	ESE
SB3005 / 11	KOLPACK PROPERTY	901-905 BARTON SPRIN	TX LPST	1021	0.193	WNW
RJ3006 / 11	SPTCO	SAN MARCOS & E 5TH	TX UST	1024	0.194	East
RS3007 / 11	7-ELEVEN STORE 36643	701 N IH 35	TX UST, TX Financial Assurance	1026	0.194	ENE
SC3008 / 14	JACK RITTER OIL CO.	2617 S 1ST ST	TX HIST UST	1032	0.195	West
SC3009 / 14	SOUTHSIDE BODY & FRA	2617 S. FIRST	TX RDR	1032	0.195	West
SC3010 / 14	SOUTHSIDE BODY & FRA	2617 S 1ST ST	TX HIST UST	1032	0.195	West
SC3011 / 14	SOUTH SIDE MOTOR	2617 S 1ST ST	TX UST	1032	0.195	West
RS3012 / 11	TEXACO FOOD MART	701 EAST AVE	TX LPST	1035	0.196	ENE
SD3013 / 11	FORMER UNLIMITED AUT	1023 W 24TH ST	TX UST	1035	0.196	West
SD3014 / 11	TEXACO INC	1023 W 24TH ST	TX HIST UST	1035	0.196	West
SD3015 / 11	FORMER UNLIMITED AUT	1023 W 24TH ST	TX RDR	1035	0.196	West
SD3016 / 11	UNLIMITED AUTO SERVI	1023 W 24TH ST	TX HIST UST	1035	0.196	West
RS3017 / 11	TEXACO	701 N IH 35	TX LPST	1035	0.196	ENE
RS3018 / 11	TEXACO	701 N IH 35	TX LPST	1037	0.196	ENE
RV3019 / 8	KWIK KOPY	4011 MEDICAL PKWY	TX Ind. Haz Waste	1038	0.197	WNW
SE3020 / 16	FORMER RITLER OIL	1250 BASTROP HWY	TX UST	1040	0.197	North
SE3021 / 16	LARRY'S AUTO SALES	1250 OLD BASTROP RD.	TX HIST UST	1040	0.197	North
SE3022 / 16	TXDOT RIGHT OF AWAY	1250 BASTROP HWY	TX RDR	1040	0.197	North
SF3023 / 11	MRS. WILLIE EAGLETON	1001 N LAMAR BLVD	TX HIST UST	1042	0.197	WNW
SG3024 / 16	B&B LAND CLEARING	1212 BASTROP HWY	TX HIST UST	1043	0.198	ESE
SG3025 / 16	B&B LAND CLEARING	1212 OLD BASTROP HWY	TX UST	1043	0.198	ESE
3026 / 11	RECREATIONAL EQUIPME	601 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	1043	0.198	WNW
SH3027 / 15	TXDOT SPECIAL CREWS	760 BASTROP HWY S	TX LPST, TX UST, TX HIST UST	1044	0.198	NNE
SH3028 / 15	TEXAS DEPARTMENT OF	760 LOCKHART HWY	RCRA NonGen / NLR, FINDS, ECHO	1044	0.198	NNE
SH3029 / 15	TEXAS DEPARTMENT OF	760 US HIGHWAY 183 S	RCRA NonGen / NLR, FINDS, ECHO	1044	0.198	NNE
SH3030 / 15	TEXAS DEPARTMENT OF	760 LOCKHART HWY	TX Ind. Haz Waste	1044	0.198	NNE
SH3031 / 15	TEXAS DEPT OF TRANSP	760 US HIGHWAY 183 S	TX Ind. Haz Waste	1044	0.198	NNE
SH3032 / 15	TXDOT OLD AUSTIN SPE	760 BASTROP HWY	TX RDR	1044	0.198	NNE
SF3033 / 11	7 ELEVEN 21884	917 N LAMAR BLVD	TX RDR	1053	0.199	WNW
SF3034 / 11	7 ELEVEN STORE 21884	917 N LAMAR BLVD	TX PST STAGE 2, TX CENTRAL REGISTRY	1053	0.199	WNW
SF3035 / 11	7-ELEVEN 21884	917 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1053	0.199	WNW
3036 / 11		1107 N LAMAR BLVD	TX HIST UST	1054	0.200	WNW
SI3037 / 2	MURPHY USA #6967	13000 N I 35	TX HIST UST	1055	0.200	ESE
RM3038 / 11	WALKER TIRE CO.	814 N I 35	TX HIST UST	1058	0.200	NE
3039 / 6	NATIONAL TIRE & BATT	8002 RESEARCH BLVD	RCRA-VSQG	1065	0.202	NW
SJ3040 / 11	AUSTIN GAS LIGHT COM	300 MEDINA STREET	SEMS-ARCHIVE	1067	0.202	ESE
SK3041 / 2	WAL-MART SUPERCENTER	12900 12900 N INTERS	RCRA-VSQG	1071	0.203	East

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
SK3042 / 2	WAL-MART SUPERCENTER	12900 N INTERSTATE 3	TX Ind. Haz Waste	1071	0.203	East
RX3043 / 11	SOUTHLAND ICE CO.	612 E 9TH ST	TX HIST UST	1073	0.203	NE
3044 / 20	AIRPORT FAST PARK	2300 SPIRIT OF TEXAS	TX AST	1080	0.205	NE
SL3045 / 18	NALTEX	220 E ST ELMO RD	TX HIST UST	1084	0.205	ESE
SL3046 / 18	DELSTAR TECHNOLOGIES	220 E SAINT ELMO RD	RCRA-SQG, FINDS, ECHO, TX Ind. Haz Waste	1084	0.205	ESE
SL3047 / 18	220 EAST ST ELMO ROA	220 E SAINT ELMO RD	TX IHW CORR ACTION, TX COMP HIST	1084	0.205	ESE
3048 / 6	CIRCLE K 3213	6812 AIRPORT BLVD	TX UST	1090	0.206	ESE
3049 / 8	AUSTIN NEURO DIAGNOS	1111 W 34TH STREET	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	1094	0.207	WNW
SM3050 / 8	ASCENSION SETON MEDI	1201 W 38TH STREET	RCRA-SQG, TX SWF/LF, TX LPST, TX UST, FI...	1098	0.208	WNW
SM3051 / 8	W. F. SMITH	1201 W 38TH ST	TX HIST UST	1098	0.208	WNW
SM3052 / 8	SETON MEDICAL CENTER	1201 W 38TH ST	TX HIST UST	1098	0.208	WNW
SJ3053 / 11	SALTILLO PLAZA-DOWNT	1000 E. 4TH STREET	US BROWNFIELDS	1098	0.208	East
SJ3054 / 11	SOUTHERN OIL	1000 E 4TH ST	TX HIST UST	1098	0.208	East
SN3055 / 2	GOODRICH AEROSPACE C	817 W HOWARD LN	TX UST, RCRA NonGen / NLR, FINDS, ECHO, ...	1102	0.209	NNE
SN3056 / 2	GOODRICH AEROSPACE C	817 W HOWARD LN	TX AST, TX Ind. Haz Waste, TX IHW CORR A...	1102	0.209	NNE
SN3057 / 2	CASTLEBERRY INSTRUMT	817 W HOWARD LN	TX LPST, TX ASBESTOS	1102	0.209	NNE
SL3058 / 18	BRYANT JANITORIAL SU	305 E SAINT ELMO RD	TX Ind. Haz Waste	1111	0.210	ESE
SI3059 / 2	LOWES OF NE AUSTIN T	13000 N IH 35	TX AST	1111	0.210	ESE
SI3060 / 2	MURPHY USA 6967	13000 S IH 35	TX UST, TX Financial Assurance	1111	0.210	ESE
SK3061 / 2	WAL-MART SUPERCENTER	12900 N IH 35	TX UST, TX ASBESTOS, TX Financial Assura...	1116	0.211	East
SA3062 / 18	TECHNICAL COATING	312 INDUSTRIAL BLVD	TX HIST UST, TX CENTRAL REGISTRY	1118	0.212	ESE
3063 / 20	ABIA CLEAN FUEL CENT	3100.5 SPIRIT OF TEX	TX HIST UST	1119	0.212	West
SO3064 / 11	WALKER TIRE	814 IH BLVD # 35	TX UST	1124	0.213	NE
SP3065 / 19	DON STEWART TEXACO	7110 E BEN WHITE	TX RDR	1131	0.214	SSW
SP3066 / 19	CHAMELEON 71	7110 E BEN WHITE BLV	TX UST, TX HIST UST, TX Financial Assura...	1131	0.214	SSW
SP3067 / 19	FORMER DON STEWART	7110 BEN WHITE BLVD	TX RDR	1131	0.214	SSW
3068 / 11	SERVICE BUILDING VEH	304 E 24TH ST	TX LPST, TX UST, TX ASBESTOS	1132	0.214	East
SQ3069 / 16	WHISENHUT	NE INTERSECTION OF D	TX CLI	1140	0.216	NNE
SQ3070 / 16	WHISENHUT		TX CLI	1140	0.216	NNE
SQ3071 / 16	WHISENHUT		TX HIST LF	1140	0.216	NNE
SF3072 / 11	STRAIT MUSIC	10TH & LAMAR	TX UST	1144	0.217	WNW
SR3073 / 11	ODAS JUNG	921 N LAMAR BLVD	TX HIST UST	1145	0.217	WNW
SR3074 / 11	W. L. STARK	921 N LAMAR BLVD	TX HIST UST	1145	0.217	WNW
SS3075 / 11	TEX-CON OIL COMPANY	1200 N LAMAR BLVD	TX HIST UST	1148	0.217	WNW
SS3076 / 11	KWIK MART 1	1200 N LAMAR BLVD	TX LPST, TX UST, TX ASBESTOS, TX ENF, TX...	1148	0.217	WNW
SS3077 / 11	KWIK MART #1	1200 N LAMAR BLVD	TX HIST UST	1148	0.217	WNW
ST3078 / 19	TOKYO ELECTRON TEXAS	2500 MONTOPOLIS DRIV	RCRA-VSQG, FINDS, ECHO	1149	0.218	SSW
ST3079 / 19	SYSTEM CONTROL CENTE	2500 MONTOPOLIS DRIV	TX Ind. Haz Waste, TX TIER 2, TX IHW COR...	1149	0.218	SSW
ST3080 / 19	AUSTIN ENERGY SYSTEM	2500 MONTOPOLIS DR	TX AST	1149	0.218	SSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
SU3081 / 14	DOUG SCALES BODY SHO	2707 S 1ST ST	TX HIST UST, TX AIRS	1150	0.218	West
SB3082 / 11	AUSTIN LYRIC OPERA C	905 BARTON SPRINGS R	TX HIST UST, TX RDR	1152	0.218	WNW
3083 / 6	SUPER K GRO	6700 GUADALUPE ST ST	TX UST, TX HIST UST, TX Financial Assura...	1157	0.219	ESE
3084 / 8	UNITED SHEET METAL W	1100 W KOENIG LN	TX HIST UST	1161	0.220	WNW
SU3085 / 14	DOUG SCALES BODY SHO	2717 S 1ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1163	0.220	West
SU3086 / 14	DOUG SCALES BODY SHO	2717 S 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	1163	0.220	West
3087 / 14	AUSTIN ISD	1601 HASKELL ST	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	1168	0.221	NNE
3088 / 11	REDDY ICE OAK FARMS	910 RED RIVER ST	TX LPST, TX UST, TX HIST UST	1168	0.221	NNE
3089 / 11	VACANT COMMERCIAL BL	905 E. 7TH ST.	TX HIST UST, TX ASBESTOS	1181	0.224	ENE
SV3090 / 3	J R BODY SHOP	1001 SAGEBRUSH	RCRA NonGen / NLR, FINDS, ECHO	1183	0.224	WNW
SV3091 / 3	J R BODY SHOP	1001 SAGEBRUSH DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1183	0.224	WNW
SE3092 / 16	E-CON-PLACER	1240 OLD BASTROP RD	TX HIST UST	1186	0.225	North
SE3093 / 16	RIGHT OF WAY PARCEL	1240 OLD BASTROP HWY	TX RDR	1186	0.225	North
3094 / 11	UNIV OF TEXAS DEPT G	CORNER OF 23RD AND S	RCRA NonGen / NLR	1189	0.225	East
SW3095 / 11	1001 E 6TH	1001 E 6TH ST	TX UST, TX HIST UST	1192	0.226	East
SW3096 / 11	PROPOSED CORAZON	1001 E 6TH ST	TX RDR	1192	0.226	East
SR3097 / 11	STRAIT MUSIC CO	908 N LAMAR BLVD	TX HIST UST	1199	0.227	WNW
SX3098 / 6	UNICOPY CORP	1011 W ANDERSON LN	RCRA NonGen / NLR, FINDS, ECHO	1205	0.228	WNW
SX3099 / 6	UNICOPY	1011 W ANDERSON LN	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1205	0.228	WNW
SS3100 / 11	TERMINIX OF AUSTIN	1206 PARKWAY	TX Ind. Haz Waste	1210	0.229	WNW
SS3101 / 11	TERMINIX INTERNAT'L	1206 PARKWAY	TX HIST UST	1210	0.229	WNW
SS3102 / 11	TERMINIX COMPANY OF	1206 PARKWAY	RCRA NonGen / NLR	1210	0.229	WNW
SS3103 / 11	TERMINIX INTERNATION	1206 PARKWAY	TX LPST, TX UST, TX CENTRAL REGISTRY	1210	0.229	WNW
3104 / 2	HID SHELL	601 CENTER RIDGE DR	TX HIST UST, TX CENTRAL REGISTRY	1213	0.230	ESE
3105 / 20	ABIA CONSOLIDATED RE	3819 PRESIDENTIAL BL	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	1213	0.230	East
SY3106 / 20	AVIS RENT A CAR SYST	9320 RENTAL CAR LN	TX AST	1218	0.231	WNW
SY3107 / 20	AVIS RENT A CAR SYST	9320 RENTAL CAR LN	TX HIST UST, TX TIER 2	1218	0.231	WNW
SZ3108 / 16	TEXAS ALTERNATOR	1230 BASTROP HWY	TX HIST UST	1235	0.234	ESE
SZ3109 / 16	TX ALTERNATOR STARTE	1230 BASTROP HWY	TX HIST UST	1235	0.234	ESE
3110 / 16	COLLIN'S GARAGE	1115 BASTROP HWY	TX HIST UST	1239	0.235	ENE
TA3111 / 11	SAFEWAY RENTAL EQUIP	405 N LAMAR BLVD	TX HIST UST	1239	0.235	WNW
TA3112 / 11	CAPITOL CHEVROLET MA	409 N LAMAR BLVD	TX UST, TX HIST UST	1239	0.235	WNW
TB3113 / 11	WHOLE FOODS MARKET	525 N LAMAR BLVD	TX TANKS	1241	0.235	WNW
TA3114 / 11	AMERICAN CLEANERS	407 N LAMAR BLVD	TX DRYCLEANERS	1249	0.237	WNW
TA3115 / 11	CAPITOL CHEVROLET CO	407 N LAMAR BLVD	TX HIST UST	1249	0.237	WNW
TA3116 / 11	C. B. SMITH MOTORS	407 N LAMAR BLVD	TX HIST UST	1249	0.237	WNW
TC3117 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	TX AST, TX Ind. Haz Waste	1255	0.238	ESE
TC3118 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	RCRA NonGen / NLR, ICIS, FINDS, ECHO	1255	0.238	ESE
TC3119 / 9	TEXAS DEPT PUBLIC SA	5710 GUADALUPE ST	TX RDR	1255	0.238	ESE

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
TC3120 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	TX UST, TX HIST UST	1255	0.238	ESE
TD3121 / 19	PPD DEVELOPMENT	7551 METRO CENTER DR	TX Ind. Haz Waste	1261	0.239	SSW
TD3122 / 19	PPD DEVELOPMENT	7551 7551 METRO CENT	RCRA-SQG, FINDS, ECHO	1261	0.239	SSW
TD3123 / 19	MET CENTER	7551 METRO CENTER DR	TX AST	1261	0.239	SSW
3124 / 11	ROY AND MATIAS VELAS	1020 E 5TH ST	US BROWNFIELDS	1266	0.240	East
3125 / 3	PTP OPERATING	916A PRAIRIE TRL	TX DRYCLEANERS	1268	0.240	WNW
SY3126 / 20	ALAMO RENT-A-CAR	9310 RENTAL CAR LN	TX AST	1269	0.240	WNW
SY3127 / 20	ALAMO CAR RENTAL	9310 RENTAL CAR LANE	TX HIST UST, TX TIER 2	1269	0.240	WNW
TE3128 / 11	TRAVIS COUNTY FLEET	1000 N LAMAR BLVD	TX LPST, TX HIST UST, TX TIER 2	1271	0.241	WNW
TE3129 / 11	FORMER TRAVIS CTY FL	1000 N LAMAR BLVD	TX RDR	1271	0.241	WNW
TE3130 / 11	SATELLITE 5 FLEET MA	1000 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	1271	0.241	WNW
TF3131 / 9	TEXAS DEPT OF PUBLIC	5900 GUADALUPE ST	TX UST, TX HIST UST	1272	0.241	ESE
TF3132 / 9	AUSTIN ISD	5900 GUADALUPE	RCRA NonGen / NLR, FINDS, ECHO	1272	0.241	ESE
TF3133 / 9	AUSTIN ISD	5900 GUADALUPE ST	TX Ind. Haz Waste	1272	0.241	ESE
TG3134 / 11	RECREATIONAL EQUIPME	1112 N LAMAR BLVD	TX UST, TX ASBESTOS	1277	0.242	WNW
TG3135 / 11	SIMMONS MOTOR CO.	1112 N LAMAR BLVD	TX HIST UST	1277	0.242	WNW
TG3136 / 11	REI LEASE PROPERTY	1112 N LAMAR BLVD	TX HIST UST	1277	0.242	WNW
TE3137 / 11	ONION CREEK VOLKSWAG	1014 N LAMAR BLVD	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	1278	0.242	WNW
TE3138 / 11	TIP TOP CLEANERS	1014 N LAMAR BLVD ST	TX DRYCLEANERS, TX CENTRAL REGISTRY	1278	0.242	WNW
TE3139 / 11	TIP TOP CLEANERS LAU	1014 N LAMAR BLVD ST	TX Ind. Haz Waste	1278	0.242	WNW
SW3140 / 11	A D BURRATTI	1007 E 6TH ST	TX HIST UST	1282	0.243	East
TH3141 / 18	TCI COATINGS INC		PFAS ECHO	1285	0.243	ESE
TH3142 / 18	STONE INDUSTRIAL SOL	301 INDUSTRIAL BLVD	RCRA NonGen / NLR, FINDS, ECHO	1286	0.244	ESE
TH3143 / 18	GULF CLEANING AND LA	301 INDUSTRIAL BLVD	TX AST	1286	0.244	ESE
TH3144 / 18	STONE INDUSTRIAL SOL	301 INDUSTRIAL BLVD	TX UST, TX VCP, TX HIST UST, TX Ind. Haz...	1286	0.244	ESE
3145 / 21	CIRCLE K STORE 27046	8801 S I 35	TX RDR	1294	0.245	SSE
TB3146 / 11	CAPITOL CHEVROLET	501 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	1297	0.246	WNW
TB3147 / 11	CAPITOL CHEVROLET	501 N LAMAR BLVD	TX UST, TX HIST UST, RCRA NonGen / NLR	1297	0.246	WNW
TI3148 / 4	AUSTIN CULLIGAN	505 W YAGER LANE	TX LPST, TX TIER 2	1297	0.246	East
TI3149 / 4	YAGER	505 W YAGER LN	TX UST	1297	0.246	East
SW3150 / 11	CITIES SERVICE OIL C	1000 E 6TH ST	TX HIST UST	1298	0.246	East
TH3151 / 18	403 - 301 INDUSTRIAL	403 INDUSTRIAL BLVD	TX VCP	1300	0.246	ESE
SZ3152 / 16	TEXAS ALTERNATOR STA	1230 E BEN WHITE BLV	TX UST	1305	0.247	North
3153 / 20	TEXACO RETAIL FAC	2453 HWY 71	TX RDR	1306	0.247	East
3154 / 14	MABRY ORDNANCE SHOP		FUDS	1311	0.248	South
SS3155 / 11	DONS PAINT AND BODY	1006 W 12TH ST	TX AIRS, TX Ind. Haz Waste, TX COMP HIST	1312	0.248	WNW
SS3156 / 11	DONS PAINT AND BODY	1006 W 12TH	RCRA NonGen / NLR, FINDS, ECHO	1312	0.248	WNW
SO3157 / 11	SIGNATURE #9	900 N I 35	TX HIST UST	1314	0.249	NE
TJ3158 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	RCRA-SQG, PADS	1314	0.249	WNW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
TJ3159 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	TX AST	1314	0.249	WNW
TJ3160 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	TX SPILLS, TX ASBESTOS, TX Ind. Haz Wast...	1314	0.249	WNW
SY3161 / 20	DOLLAR CAR RENTAL	9301 RENTAL CAR LN	TX HIST UST	1320	0.250	WNW
TK3162 / 15	MONTOPOLIS GROCERY	1211 MONTOPOLIS DR	TX RDR, TX CENTRAL REGISTRY	1331	0.252	NNE
3163 / 11	SIGNATURE 9	900 EAST AVE	TX LPST, TX UST, TX Financial Assurance,...	1352	0.256	NE
TF3164 / 9	AUSTIN ISD SNEED	5901 GUADALUPE ST	TX LPST, TX Ind. Haz Waste	1367	0.259	ESE
3165 / 11	LOPEZ PROPERTY	809 E.9TH STREET	US BROWNFIELDS	1416	0.268	ENE
3166 / 18	BUTCH WOOTEN INVESTM	315 E SAINT ELMO RD	TX LPST	1421	0.269	ESE
TK3167 / 15	MONTOPOLIS PARK	1200 MONTOPOLIS	US BROWNFIELDS, FINDS	1431	0.271	NNE
3168 / 15	AUSTIN LIQUID DISPOS	751 BASTROP HWY	TX SWF/LF, TX AIRS, TX COMP HIST, TX CEN...	1441	0.273	NNE
TL3169 / 8	HLD FOOD MART	1112 W KOENIG LN	TX LPST	1449	0.274	WNW
3170 / 2	AUSTIN EXECUTIVE AIR	811 W HOWARD LN	TX VCP	1450	0.275	NE
3171 / 15	PARKS & RECREATION M	2525 S LAKESHORE BLV	TX UST, TX HIST UST, TX Financial Assura...	1503	0.285	ENE
3172 / 8	WEED-CORLEY FUNERAL	1301 W 34TH ST	TX LPST, TX UST, TX HIST UST	1504	0.285	WNW
3173 / 14	KING FOOD MART	2907 S FIRST ST	TX RDR	1509	0.286	WSW
3174 / 11	SPAW GLASS CONSTRUCT	1020 RED RIVER ST	TX LPST	1515	0.287	NNE
3175 / 17	MULDOON INTERESTS	6210 CROW LN	TX VCP	1535	0.291	ESE
3176 / 6	FIRE STATION 16	7000 REESE LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1552	0.294	WNW
TM3177 / 20	SHOPPERS MART 6	2453 HIGHWAY 71 E	TX LPST	1561	0.296	East
TM3178 / 20	SHOPPERS MART 6	2453 HIGHWAY 71 E	TX LPST	1561	0.296	East
3179 / 3	MOFFITT MAINTENANCE	11502 TITAN DR	TX RDR	1581	0.299	WNW
TN3180 / 14	CIRCLE K STORE 27405	2222 E OLTORF	TX RDR	1582	0.300	SW
TN3181 / 14	CIRCLE K STORE #2740	2222 E OLTORF ST	TX RDR	1582	0.300	SW
TN3182 / 14	CIRCLE K 2740552	2222 E OLTORF ST	TX RDR	1582	0.300	SW
TN3183 / 14	CIRCLE K STORE 27405	2222 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1582	0.300	SW
3184 / 21	SIGNATURE 1	100 E SLAUGHTER LN	TX RDR	1601	0.303	SSE
3185 / 16		1111 OLD BASTROP HIG	TX CLI	1614	0.306	NNE
3186 / 11	GARDNER IRON AND MET	1201 E 4TH ST	TX VCP, TX HIST UST	1627	0.308	ESE
3187 / 21	TXDOT	7901 N I 35 FRONTAGE	TX RDR	1628	0.308	ESE
3188 / 9	GEORGE TORRES TEXACO	301 W KOENIG LN	TX LPST, TX HIST UST, TX ENF, TX COMP HI...	1635	0.310	ESE
TL3189 / 8	FORMER BROADDUS KOEN	1200 W KOENIG LN	TX LPST	1657	0.314	WNW
TL3190 / 8	FORMER KOENIG CHEVRO	1200 KOENIG LN	TX RDR	1657	0.314	WNW
TL3191 / 8	KOENIG LANE 66	1200 W KOENIG LN	TX LPST	1657	0.314	WNW
3192 / 17	TEXACO SERVICE STATI	616 WILLIAM CANNON	TX RDR	1660	0.314	ESE
3193 / 8	ELIZABET NEY MUSEUM	304 E. 44TH STREET	US BROWNFIELDS	1686	0.319	East
3194 / 17	ST ELMO	502 W SAINT ELMO RD	TX LPST	1732	0.328	WNW
3195 / 11	CAZARES PROPERTY	1112 E 6TH ST	TX HIST UST, TX IHW CORR ACTION, TX RDR,...	1764	0.334	East
3196 / 6	MERCEDES BENZ OF AUS	6757 AIRPORT BLVD	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	1788	0.339	ESE
TO3197 / 20	FORMER AIRPORT EXXON	2511 HWY 71 E	TX VCP	1788	0.339	East

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
TO3198 / 20	FORMER AIRPORT EXXON	2511 HIGHWAY 71 E	TX LPST	1788	0.339	East
TO3199 / 20	STATE HIGHWAY 71 E 2	2511 HIGHWAY 71 E	US BROWNFIELDS, FINDS	1788	0.339	East
3200 / 14	OLTORF FOOD MART	2225 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1799	0.341	SW
3201 / 15	SOUTHWESTERN BELL	650 BASTROP HWY	TX RDR	1805	0.342	North
3202 / 6	RED ARROW FREIGHT LI	8080 PURNELL DR	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	1819	0.345	SE
3203 / 6	MERCEDES BENZ OF AUS	412 PAMPA DR	TX TANKS, TX HIST UST, TX COMP HIST, TX ...	1841	0.349	ESE
3204 / 11	DOUGHERTY ARTS CENTE	1110 BARTON SPRINGS	TX SWF/LF, TX ASBESTOS	1842	0.349	WNW
3205 / 8	JULIOS CAFE	4220 DUVAL ST	TX HIST UST, TX RDR	1845	0.349	East
3206 / 11	G S TYPESETTERS	410 BAYLOR ST	TX LPST	1908	0.361	WNW
TP3207 / 21	FORMER 7-ELEVEN 3906	120 W SLAUGHTER LN	TX RDR	1911	0.362	SW
TP3208 / 21	WALGREENS	120 W SLAUGHTER LN	TX LPST, TX ASBESTOS, TX GCC	1911	0.362	SW
TQ3209 / 8	FIRST TEXAS HONDA	1301 W KOENIG LN	TX LPST, TX CENTRAL REGISTRY	1920	0.364	WNW
3210 / 15	VARGAS FOOD STORE	809 VARGAS RD	TX LPST, TX UST, TX HIST UST	1920	0.364	NW
TR3211 / 11	FORMER BRACKENRIDGE	601 E 15TH ST	TX RDR	1926	0.365	ESE
TR3212 / 11	FORMER BRACKENRIDGE	601 E 15TH ST	TX LPST, TX UST, TX HIST UST, TX AIRS, T...	1926	0.365	ESE
TR3213 / 11	CENTRAL HEALTH - BRA	601 E. 15TH STREET	US BROWNFIELDS	1926	0.365	ESE
TR3214 / 11	FORMER BRACKENRIDGE	601 EAST 15TH ST	TX RDR	1926	0.365	ESE
TQ3215 / 8	FORMER FIRST TEXAS H	1303 W. KOENIG	US BROWNFIELDS	1927	0.365	WNW
3216 / 17	CAPITOL CHEVROLET PA	700 N BLUFF DR	TX TANKS, TX CENTRAL REGISTRY	1956	0.370	ESE
3217 / 8	ROOSEVELT GARDENS	5606 ROOSEVELT AVENU	US BROWNFIELDS, FINDS, ECHO	1961	0.371	WNW
3218 / 13	SS6 1483	530 W BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST	1969	0.373	WNW
3219 / 17	BIG LOTS	801 E WILLIAM CANNON	TX VCP, TX HIST UST, TX ASBESTOS	1977	0.374	ESE
TS3220 / 6	SUNRISE MINI MART 7	102 W POWELL LN	TX LPST, TX UST, TX HIST UST, TX ENF, TX...	1981	0.375	SE
TS3221 / 6	DIAMOND SHAMROCK 215	102 W POWELL LN	TX RDR	1981	0.375	SE
3222 / 13	THE CORNER STORE	525 W BEN WHITE BLVD	TX LPST, TX UST, TX ASBESTOS, TX Financi...	2036	0.386	WNW
TT3223 / 13	SERVICE CENTER 11	3616 S 1ST ST	TX LPST, TX ASBESTOS	2048	0.388	WNW
TT3224 / 13	SOUTH 1ST STREET SER	3616A S 1ST ST	TX LPST	2049	0.388	WNW
3225 / 11	ATT AUSTIN FACILITY	705 E 12TH ST	TX LPST, TX ASBESTOS	2078	0.394	NE
3226 / 18	CAPITOL METAL FINISH	3909 WAREHOUSE ROW	SEMS-ARCHIVE, CORRACTS, RCRA NonGen / NL..	2083	0.395	ESE
3227 / 17	RICK HOFF	4333 S 1ST ST	TX LPST, TX UST	2085	0.395	WNW
3228 / 6	BEKINS MOVING STORAG	201 E ANDERSON LN	TX LPST	2095	0.397	ESE
3229 / 13	C STORE	4111 S 1ST	TX RDR	2117	0.401	WNW
TU3230 / 11	PLAZA SALTILLO BLK 5	1301 E 5TH ST	TX RDR	2153	0.408	East
TU3231 / 11	PLAZA SALTILLO	1301 E 5TH ST	TX TANKS, TX HIST UST, TX CENTRAL REGIST...	2153	0.408	East
3232 / 15	MR MCS GROCERY & MAR	2109 HOLLY ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	2170	0.411	NE
3233 / 9	OLD SEARS WAREHOUSE	108 DENSON DR	TX LPST, TX UST	2185	0.414	ESE
3234 / 13	FORMER QUIKIE PICKIE	600 W BEN WHITE	TX LPST, TX UST	2185	0.414	WNW
3235 / 14	LUBE PIT STOP	1951 E OLTORF	TX RDR	2217	0.420	SW
TV3236 / 11	FORMER HAROLD TIEDT	302 S LAMAR BLVD	TX RDR	2231	0.423	WSW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
TW3237 / 18	BEN WHITE LOTS 1,2,3	500 E BEN WHITE BLVD	TX VCP, TX GCC, TX IOP	2233	0.423	ESE
3238 / 2	7-ELEVEN 35805	13641 N IH 35	TX LPST, TX UST, TX Financial Assurance	2244	0.425	North
TW3239 / 18	FORMER TRUCK CITY DE	502 E BEN WHITE BLVD	TX LPST	2261	0.428	ESE
3240 / 8	HYDE PARK TEXACO	4500 DUVAL ST	TX LPST, TX UST, TX HIST UST	2276	0.431	East
TX3241 / 20	BERGSTROM 2	SITE AT N END OF BAS	TX HIST LF	2276	0.431	SE
TX3242 / 20	BERGSTROM 2	SITE AT N END OF BAS	TX CLI	2276	0.431	SE
TX3243 / 20	BERGSTROM 2	NORTH END OF FORMER	TX CLI	2276	0.431	SE
3244 / 15	PATHMARK 34	609 BASTROP HWY	TX RDR	2280	0.432	North
3245 / 11	EBENEZAR BAPTIST CHU	1011 SAN MARCOS ST	TX LPST, TX UST	2281	0.432	ENE
3246 / 11	PHOENIX MOTOR WORKS	1127 W 6TH ST	TX LPST, TX UST, TX HIST UST	2287	0.433	WNW
TY3247 / 17	TEXACO RETAIL FAC	800 E WILLIAM CANNON	TX RDR	2290	0.434	ESE
TY3248 / 17	TOWN FOOD MART	800 E WILLIAM CANNON	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2290	0.434	ESE
3249 / 14	USPS S AUSTIN STATIO	1806 S 5TH ST	TX LPST	2290	0.434	WNW
TZ3250 / 17	ANDYS FOOD MART	611 W STASSNEY LN	TX RDR, TX CENTRAL REGISTRY	2292	0.434	WNW
TZ3251 / 17	ANDYS FOOD MART	611 W STASSNEY LN	TX LPST, TX UST, TX HIST UST, TX Financi...	2292	0.434	WNW
UA3252 / 13	7 ELEVEN 26353	601 W BEN WHITE BLVD	TX RDR	2303	0.436	WNW
UA3253 / 13	7-ELEVEN 26353	601 W BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2303	0.436	WNW
UB3254 / 11	908 E. 11TH ST (11TH	908 E. 11TH ST	US BROWNFIELDS, FINDS	2312	0.438	NE
UB3255 / 11	912 E. 11TH STREET	912 E. 11TH STREET	US BROWNFIELDS	2345	0.444	NE
3256 / 18	WENCO DISTRIBUTORS O	600 INDUSTRIAL BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2354	0.446	ESE
UB3257 / 11	916 E. 11TH STREET	916 E. 11TH STREET	US BROWNFIELDS	2372	0.449	NE
UC3258 / 9	STOP N GO #2207	4429 DUVAL ST	TX RDR	2381	0.451	East
UC3259 / 9	SUNRISE SUPER STOP	4429 DUVAL ST	TX LPST, TX UST, TX HIST UST, TX Financi...	2381	0.451	East
UC3260 / 9	MINIS FOOD MART	4429 DUVAL ST	TX RDR	2381	0.451	East
3261 / 9	MR SAMS FOODMART	6515 AIRPORT BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2384	0.452	ESE
UD3262 / 8	CUTLER AUTOMOTIVE	4416 BURNET RD	TX RDR, TX CENTRAL REGISTRY	2390	0.453	NNW
UB3263 / 11	920 E. 11TH ST (11TH	920 E. 11TH ST	US BROWNFIELDS, FINDS	2393	0.453	ENE
UD3264 / 8	TETCO #1169	1309 W. 45TH ST	TX RDR	2398	0.454	NNW
3265 / 8	ABANDONED	1401 W KOENIG LN	TX RDR	2400	0.455	WNW
UB3266 / 11	903 JUNIPER ST (11TH	903 JUNIPER ST	US BROWNFIELDS, FINDS	2407	0.456	NE
3267 / 14	WHIP IN 2 100148	1950 S IH 35	TX LPST, TX UST, TX HIST UST	2408	0.456	WSW
3268 / 14	SUNRISE MINI MART 2	915 W OLTORF ST	TX LPST, TX UST, TX ASBESTOS, TX Financi...	2415	0.457	WNW
TV3269 / 11	300-302 S LAMAR	300 S LAMAR	TX RDR	2428	0.460	WSW
UB3270 / 11	905 JUNIPER ST (11TH	905 JUNIPER ST.	US BROWNFIELDS, FINDS	2432	0.461	NE
3271 / 11	HABITAT FOR HUMANITY	1407-1411 E. 4TH STR	US BROWNFIELDS, FINDS	2437	0.462	ESE
3272 / 3	E-Z STOP 2	1200 KRAMER LN STE 1	TX LPST, TX UST, TX HIST UST, TX ED AQUI...	2440	0.462	WNW
UE3273 / 15	B R CAPPS TEXACO	520 BASTROP HWY N	TX LPST, TX UST, TX HIST UST	2444	0.463	North
UE3274 / 15	FORMER CAPPS TEXACO	520 BASTROP HWY	TX RDR	2444	0.463	North
UF3275 / 20	BERGSTROM 1	NORTH END OF FORMER	TX CLI	2455	0.465	SW

MAPPED SITES SUMMARY

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
UF3276 / 20	BERGSTROM 1	SITE ON N END OF BAS	TX CLI	2455	0.465	SW
UF3277 / 20	BERGSTROM 1	SITE ON N END OF BAS	TX HIST LF	2455	0.465	SW
UB3278 / 11	907 JUNIPER ST (11TH	907 JUNIPER ST	US BROWNFIELDS, FINDS	2459	0.466	NE
3279 / 11	EXXON RS 67897	1104 EAST AVE	TX LPST, TX UST	2469	0.468	ESE
3280 / 17	TEXACO	5600 S 1ST ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2469	0.468	WNW
UB3281 / 11	909 JUNIPER ST (11TH	909 JUNIPER ST	US BROWNFIELDS, FINDS	2479	0.470	NE
UB3282 / 11	911 JUNIPER ST (11TH	911 JUNIPER ST	US BROWNFIELDS, FINDS	2493	0.472	NE
3283 / 8	FORMER MUFFIN MUFFLE	4818 BURNET RD	TX RDR	2520	0.477	WNW
3284 / 11	913 JUNIPER ST (11TH	913 JUNIPER ST	US BROWNFIELDS, FINDS	2527	0.479	ENE
3285 / 15	6301 CIRCULO DE AMIS	6301 CIRCULO DE AMIS	US BROWNFIELDS	2532	0.480	NNE
3286 / 8	STENGER TRACT	1406 N IH 35	TX VCP	2537	0.480	WNW
3287 / 9	PERRY ROSE TIRE HIGH	6401 AIRPORT BLVD	TX LPST, TX UST, TX HIST UST	2541	0.481	ESE
3288 / 20	INDOOR SMALL ARMS RA		UXO	2548	0.483	ESE
3289 / 8	LESTER BROWN PHILLIP	4500 BURNET RD	TX LPST, TX UST, TX HIST UST	2555	0.484	NNW
UG3290 / 14	EXXON MOBIL 67278	1320 E OLTORF ST	TX LPST, TX ASBESTOS, TX Ind. Haz Waste	2583	0.489	ESE
UG3291 / 14	7 ELEVEN STORE 36636	1320 E OLTORF ST	TX RDR	2583	0.489	ESE
UG3292 / 14	7-ELEVEN INC STORE N	1320 E OLTORF STREET	TX RDR	2583	0.489	ESE
UG3293 / 14	7-ELEVEN STORE 36636	1320 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2583	0.489	ESE
3294 / 11	DOUGHERTY ARTS CENTE	1500 TOOMEY RD	US BROWNFIELDS, FINDS	2596	0.492	WSW
3295 / 9	CONTINENTAL CARS	200 W HUNTLAND	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	2602	0.493	ESE
3296 / 17	SHELL	500 W WILLIAM CANNON	TX RDR	2605	0.493	WNW
UH3297 / 11	SIGNATURE 2	608 S LAMAR AVE	TX RDR	2621	0.496	WNW
UH3298 / 11	TEXACO RETAIL FAC	608 S LAMAR	TX RDR	2621	0.496	WNW
UH3299 / 11	SIGNATURE 2	608 S LAMAR BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	2621	0.496	WNW

Key Map - 7418065.7s


FALCON'S NEST HELIPORT
AUSTIN HELIPORT
OSSIPOR HELIPORT
BARTON CREEK RESORT HELIPORT
STARLIGHT FACILITY HELIPORT
BUDDY RYDEN AIRPORT
AUSTIN BERGSTROM INTL AIRPORT
DEL VALLE AIRPORT
KITCHING RANCH HELIPORT
SEIDEL RANCH AIRPORT
US-290 W
SH 130
FM-973
FM-969
FM-2222
Pearce Rd
Bluff Springs Rd
Dee Gabriel Collins Rd
Wyldwood Rd
Highway 290
Yager Ln
E Howard Ln
Bloor Rd
Blue Bluff Rd
Decker Lake Rd
Heatherwilde Blvd
Pearce Ln
Norwood Ln
Nez Perce
Hill Ln
Lindell Ln
Darlan Ln
Fallwell Ln
Platt Ln
Dalton Ave
Rosewood Ave
Emma Barrientos Dr
Colton Bluff Springs Rd
Nelms Rd
Roy Rd
Bass Rd
Fuchs
Cameron Rd
Killingsworth Ln
Bell Mountain Dr
Pecan Bluff Dr
Oak Shores Dr
Oak Park Rd
Glen Haven Dr
Travis Country Cir
Vega Ve
Lost Creek Blvd
Pate San Rd
Lisa Ln
Silver Ranch Rd
Bluff View Dr
River Place Blvd
Spicewood Springs Rd
Jester Blvd
Westlake Dr
Bee Caves Rd
Bluffstone Dr
Lake Austin Blvd
Loop 360
Mopac Expy
Capital of Texas Hwy
Ranch Rd 620
Bee Cave Rd
Hatfield Rd
Lake Austin Blvd
Bluffstone Dr
Bluff Springs Rd
Dalton Ave
Rosewood Ave
Emma Barrientos Dr
Fallwell Ln
Platt Ln
Heatherwilde Blvd
Pearce Ln
Norwood Ln
Nez Perce
Hill Ln
Lindell Ln
Darlan Ln
Bloor Rd
Blue Bluff Rd
Decker Lake Rd
Yager Ln
E Howard Ln
Cameron Rd
Killingsworth Ln
Fuchs
Bass Rd
Roy Rd
Nelms Rd
Colton Bluff Springs Rd
Dee Gabriel Collins Rd
Wyldwood Rd
Highway 290
Travis Country Cir
Vega Ve
Lost Creek Blvd
Pate San Rd
Lisa Ln
Silver Ranch Rd
Bluff View Dr
River Place Blvd
Spicewood Springs Rd
Jester Blvd
Westlake Dr
Bee Caves Rd
Bluffstone Dr
Lake Austin Blvd
Loop 360
Mopac Expy
Capital of Texas Hwy
Ranch Rd 620
Bee Cave Rd
Hatfield Rd
Bell Mountain Dr
Pecan Bluff Dr
Oak Shores Dr
Oak Park Rd
Glen Haven Dr
Pearce Rd
Bluff View Dr
Lisa Ln
Pate San Rd
Lost Creek Blvd
Travis Country Cir
Vega Ve
Silver Ranch Rd

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500	2	1	2	1	NR	NR	6
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000	1	0	0	1	0	NR	2
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500	1	0	0	0	NR	NR	1
Lists of Federal RCRA generators								
RCRA-LQG	0.250		2	0	NR	NR	NR	2
RCRA-SQG	0.250	7	9	7	NR	NR	NR	23
RCRA-VSQG	0.250	5	17	6	NR	NR	NR	28
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP	19	NR	NR	NR	NR	NR	19
Lists of state- and tribal (Superfund) equivalent sites								
TX SHWS	1.000		0	0	0	0	NR	0
Lists of state and tribal landfills and solid waste disposal facilities								
TX SWF/LF	0.500	1	3	3	2	NR	NR	9
TX DEBRIS	0.500		0	0	0	NR	NR	0
TX CLI	0.500	4	8	4	5	NR	NR	21
TX WASTE MGMT	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0
TX LPST	0.500	24	114	24	56	NR	NR	218
TX RDR	0.500	22	127	26	44	NR	NR	219
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
TX UST	0.250	45	208	55	NR	NR	NR	308
TX AST	0.250	4	10	12	NR	NR	NR	26
INDIAN UST	0.250		0	0	NR	NR	NR	0
TX TANKS	0.500	3	10	3	3	NR	NR	19
State and tribal institutional control / engineering control registries								
TX AUL	0.500		1	0	0	NR	NR	1
Lists of state and tribal voluntary cleanup sites								
TX VCP	0.500	7	21	5	7	NR	NR	40
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
TX BROWNFIELDS	0.500		5	0	0	NR	NR	5
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500	2	11	4	20	NR	NR	37
Local Lists of Landfill / Solid Waste Disposal Sites								
TX SWRCY	0.500		1	0	0	NR	NR	1
TX HIST LF	0.500	2	4	2	2	NR	NR	10
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
TX CDL	TP		NR	NR	NR	NR	NR	0
TX PRIORITYCLEANERS	0.500		1	0	0	NR	NR	1
TX DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
TX CENTRAL REGISTRY	TP	155	NR	NR	NR	NR	NR	155
Local Lists of Registered Storage Tanks								
TX NON REGIST PST	0.250	1	5	3	NR	NR	NR	9
Local Land Records								
TX HIST LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
TX LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP	1	NR	NR	NR	NR	NR	1
TX SPILLS	TP	20	NR	NR	NR	NR	NR	20
TX SPILLS 90	TP	6	NR	NR	NR	NR	NR	6
TX SPILLS 80	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	17	92	29	NR	NR	NR	138
FUDS	1.000		0	1	0	0	NR	1
DOD	1.000		1	0	0	0	NR	1
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP	4	NR	NR	NR	NR	NR	4
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP	1	NR	NR	NR	NR	NR	1
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP	3	NR	NR	NR	NR	NR	3
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP	6	NR	NR	NR	NR	NR	6
FTTS	TP	3	NR	NR	NR	NR	NR	3
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP	3	NR	NR	NR	NR	NR	3
DOT OPS	TP	2	NR	NR	NR	NR	NR	2
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	105	NR	NR	NR	NR	NR	105
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		1	0	1	0	NR	2
ECHO	TP	52	NR	NR	NR	NR	NR	52
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		1	0	NR	NR	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250	5	12	3	NR	NR	NR	20
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
TX PFAS	0.250		0	0	NR	NR	NR	0
TX AQUEOUS FOAM	0.250		0	0	NR	NR	NR	0
TX AIRS	TP	7	NR	NR	NR	NR	NR	7
TX APAR	TP		NR	NR	NR	NR	NR	0
TX ASBESTOS	TP	150	NR	NR	NR	NR	NR	150
TX COAL ASH	0.500		0	0	0	NR	NR	0
TX DRYCLEANERS	0.250	5	29	4	NR	NR	NR	38
TX ED AQUIF	TP		NR	NR	NR	NR	NR	0
TX ENF	TP	9	NR	NR	NR	NR	NR	9
TX Financial Assurance	TP	16	NR	NR	NR	NR	NR	16
TX GCC	TP	12	NR	NR	NR	NR	NR	12
TX IOP	TP	4	NR	NR	NR	NR	NR	4
TX LEAD	TP	2	NR	NR	NR	NR	NR	2
TX Ind. Haz Waste	0.250	32	148	49	NR	NR	NR	229
WI MANIFEST	0.250		0	1	NR	NR	NR	1
NY MANIFEST	0.250		1	0	NR	NR	NR	1
TX MSD	0.500		0	0	0	NR	NR	0
TX NPDES	TP		NR	NR	NR	NR	NR	0
TX RWS	TP		NR	NR	NR	NR	NR	0
TX TIER 2	TP	20	NR	NR	NR	NR	NR	20
TX UIC	TP	1	NR	NR	NR	NR	NR	1
TX IHW CORR ACTION	0.250	4	15	4	NR	NR	NR	23
TX PST STAGE 2	0.250		1	2	NR	NR	NR	3
TX COMP HIST	TP	17	NR	NR	NR	NR	NR	17
MINES MRDS	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		2	0	0	0	NR	2
EDR Hist Auto	0.125	186	666	NR	NR	NR	NR	852
EDR Hist Cleaner	0.125	96	290	NR	NR	NR	NR	386
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
TX RGA HWS	TP		NR	NR	NR	NR	NR	0
TX RGA LF	TP	3	NR	NR	NR	NR	NR	3
- Totals --		1098	1817	249	142	0	0	3306

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Focus Map - 1 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	0 1/4 1/2 Miles
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 1

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 2 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites
Target Property	Power Line	Indian Reservations BIA
Search Buffer	Pipe Line	
Focus Map - No Sites	National Priority List Sites	

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 2

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
1 / 2	LOWES OF NE AUSTIN	12805 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
A2 / 2	COXVILLE	12600 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	TP		
A3 / 2	COXVILLE	12600 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
B4 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	FINDS	TP		
B5 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
B6 / 2	NW CORNER OF IH-35 &	12501 N LAMAR BLVD	ECHO	TP		
7 / 2	7-ELEVEN INC	12434 N LAMAR BLVD	EDR Hist Auto	TP		
C8 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	TX COMP HIST, TX CENTRAL REGISTRY	TP		
C9 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	ECHO	TP		
C10 / 2	NYOS CHARTER SCHOOL	12333 N LAMAR BLVD	FINDS	TP		
HX1001 / 2	HOME DEPOT USA HD655	13309 N IH 35	RCRA-SQG	63	0.012	North
HX1002 / 2	HOME DEPOT USA HD655	13309 N IH 35	TX Ind. Haz Waste	63	0.012	North
JN1501 / 2	FORMER 7 ELEVEN 1781	12430 N LAMAR BLVD	TX RDR	126	0.024	West
JN1502 / 2	PRIME MART	12430 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	126	0.024	West
JN1503 / 2	7-ELEVEN INC	12430 N LAMAR BLVD	EDR Hist Auto	126	0.024	West
KI1758 / 2	EXXON MOBIL CORPORAT	1100 W PARMER LN	EDR Hist Auto	173	0.033	West
KI1759 / 2	EXXON RAS NO 60117	1100 W PARMER	RCRA NonGen / NLR, FINDS, ECHO	173	0.033	West
KI1760 / 2	7-ELEVEN STORE 36588	1100 W PARMER LN	TX UST, TX HIST UST, TX ASBESTOS, TX ED ...	173	0.033	West
1868 / 2	FIRST NATIONAL BANK	12800 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	204	0.039	West
KI2306 / 2	BROWN JACK CLEANERS	1109 W PARMER LN	EDR Hist Cleaner	332	0.063	West
2727 / 2	HID GLOBAL	611 CENTER RIDGE DR	TX AST	498	0.094	ESE
2928 / 2	CARMAX 7154	13300 N IH 35	TX UST, TX HIST UST, TX AIRS, TX Financi...	833	0.158	North
RZ2995 / 2	RAVEN INDUSTRIES INC		PFAS ECHO	994	0.188	ESE
RZ3002 / 2	AUSTIN TECHNOLOGY CE	500 CENTER RIDGE DR	TX Ind. Haz Waste	1016	0.192	ESE
RZ3003 / 2	QUANTUM CLEAN	500 CENTER RIDGE DR	RCRA NonGen / NLR, FINDS, ECHO	1016	0.192	ESE
SI3037 / 2	MURPHY USA #6967	13000 N I 35	TX HIST UST	1055	0.200	ESE
SK3041 / 2	WAL-MART SUPERCENTER	12900 12900 N INTERS	RCRA-VSQG	1071	0.203	East
SK3042 / 2	WAL-MART SUPERCENTER	12900 N INTERSTATE 3	TX Ind. Haz Waste	1071	0.203	East
SN3055 / 2	GOODRICH AEROSPACE C	817 W HOWARD LN	TX UST, RCRA NonGen / NLR, FINDS, ECHO, ...	1102	0.209	NNE
SN3056 / 2	GOODRICH AEROSPACE C	817 W HOWARD LN	TX AST, TX Ind. Haz Waste, TX IHW CORR A...	1102	0.209	NNE
SN3057 / 2	CASTLEBERRY INSTRUMT	817 W HOWARD LN	TX LPST, TX ASBESTOS	1102	0.209	NNE
SI3059 / 2	LOWES OF NE AUSTIN T	13000 N IH 35	TX AST	1111	0.210	ESE
SI3060 / 2	MURPHY USA 6967	13000 S IH 35	TX UST, TX Financial Assurance	1111	0.210	ESE
SK3061 / 2	WAL-MART SUPERCENTER	12900 N IH 35	TX UST, TX ASBESTOS, TX Financial Assura...	1116	0.211	East
3104 / 2	HID SHELL	601 CENTER RIDGE DR	TX HIST UST, TX CENTRAL REGISTRY	1213	0.230	ESE
3170 / 2	AUSTIN EXECUTIVE AIR	811 W HOWARD LN	TX VCP	1450	0.275	NE
3238 / 2	7-ELEVEN 35805	13641 N IH 35	TX LPST, TX UST, TX Financial Assurance	2244	0.425	North

Focus Map - 3 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME:	Austin Light Rail Project - Phase 1	CLIENT:	HDR
ADDRESS:	Austin Light Rail Project - Phase 1	CONTACT:	Kristine Lloyd
CITY/STATE:	Austin TX	INQUIRY #:	7418065.7s
ZIP:	78704	DATE:	08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 3

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
16 / 3	2 VACANT DUPLEXES	11708 N. LAMAR	TX ASBESTOS	TP		
E17 / 3	GAREY CONSTRUCTION C	11607 N LAMAR	RCRA NonGen / NLR	TP		
E18 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX AST	TP		
E19 / 3	GAREY CONSTRUCTION	11607 N LAMAR	FINDS, ECHO	TP		
E20 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX UST, TX HIST UST	TP		
E21 / 3	GAREY CONSTRUCTION	11607 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP		
F22 / 3	TRAILER COATING	11422 N LAMAR	TX CENTRAL REGISTRY	TP		
F23 / 3	OREILLY AUTO PARTS 5	11423 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
G24 / 3	KWIK STOP	11331 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
G25 / 3	KWIK STOP	11331 N LAMAR BLVD S	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP		
G26 / 3	KWIK STOP	11331 N LAMAR BLVD	TX ENF, TX COMP HIST	TP		
G27 / 3	POTOSINA MEAT MARKET	11331 N LAMAR BLVD	FINDS	TP		
H28 / 3	PROGRESSIVE MILL WOR	11118 N LAMAR BOULEV	FINDS	TP		
H29 / 3	HERITAGE BODY & FRAM	11108 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP		
H30 / 3	HERITAGE BODY & FRAM	11108 N LAMAR	TX CENTRAL REGISTRY	TP		
I31 / 3	AIRGAS SOUTHWEST, IN	11111 N. LAMAR	TX TIER 2	TP		
I32 / 3	AIRGAS USA, LLC - SO	11111 N. LAMAR	TX TIER 2	TP		
J33 / 3	FOSTER HI-TECH FINIS	10716 N LAMAR BLVD S	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP		
J34 / 3	FOSTER HI TECH FINIS	10716 N LAMAR BLVD S	RCRA NonGen / NLR, FINDS, ECHO	TP		
J35 / 3	AUSTIN PERFORMANCE S	10716 LAMAR BLVD N	EDR Hist Auto	TP		
J36 / 3	UNITED MOLDING	10714 N LAMAR	TX CENTRAL REGISTRY	TP		
J37 / 3	LANGHAM GROUP CULTUR	10712 N LAMAR BLVD S	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP		
J38 / 3	LANGFORD CABINETS	10710 NORTH LAMAR	TX CENTRAL REGISTRY	TP		
J39 / 3	NU-WAY UPHOLSTERY	10721 N LAMAR	EDR Hist Cleaner	TP		
K40 / 3	SUPER CARE CLEANERS	10206 LAMAR BLVD N	EDR Hist Cleaner	TP		
K41 / 3	SUPER CARE CLEANERS	10205 N LAMAR	EDR Hist Cleaner	TP		
L42 / 3	NAPA AUTO PARTS 22	10101 N LAMAR BLVD	FINDS	TP		
L43 / 3	AUSTEX AUTO PARTS	10101 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
M44 / 3	AUTOZONE	9905 N LAMAR BLVD	TX ASBESTOS	TP		
M45 / 3	AUTOZONE 1396	9905 N LAMAR BLVD	FINDS	TP		
M46 / 3	AUTOZONE 1396	9905 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
47 / 3	BRIDENT DENTAL	9813 N. LAMAR BLVD.	RCRA-VSQG, FINDS, ECHO	TP		
HV997 / 3	AUTOSYSTEMS WORKSHOP	10805 N LAMAR BLVD A	EDR Hist Auto	63	0.012	ESE
1020 / 3	SAMS CLUB PLUS NO 62	10601 N LAMAR BLVD	RCRA-VSQG, FINDS, ECHO	65	0.012	ESE
J1049 / 3	QUALITY BODY SHOP	10720 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	67	0.013	WNW
J1050 / 3	QUALITY BODY SHOP IN	10720 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO	67	0.013	WNW
1052 / 3	MONARCH TRANSMISSION	10409 LAMAR BLVD N	EDR Hist Auto	67	0.013	ESE
ID1070 / 3	CHUCKS CUSTOM AUTO	11000 N LAMAR BLVD	TX Ind. Haz Waste	68	0.013	WNW
ID1071 / 3	CHUCKS CUSTOM AUTO I	11000 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	68	0.013	WNW

MAPPED SITES SUMMARY - FOCUS MAP 3

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
ID1072 / 3	SCHARFE DENNIS F BUI	11000 N LAMAR BLVD	EDR Hist Auto	68	0.013	WNW
HV1080 / 3	SIGMOR SHAMROCK SERV	10810 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW
HV1081 / 3	LAMAR FOOD MARKET	10810 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	69	0.013	WNW
IF1091 / 3	METRO STAR GROCERY	10304 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	70	0.013	WNW
IF1092 / 3	METRO STAR GROCERY	10304 N LAMAR BLVD	TX RDR, TX CENTRAL REGISTRY	70	0.013	WNW
I1100 / 3	PHILLIPS 66 SS 26286	11100 N LAMAR BLVD	TX LPST, TX SPILLS	71	0.013	WNW
I1101 / 3	PHILLIPS SIXTY SIX S	11100 LAMAR BLVD N	EDR Hist Auto	71	0.013	WNW
I1102 / 3	NORTH LAMAR SERVICE	11100 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	71	0.013	WNW
I1103 / 3	NORTH LAMAR PHILLIPS	11100 NORTH LAMAR	TX RDR	71	0.013	WNW
H1133 / 3	A ME KANNIKS OTTO NE	11104 LAMAR BLVD N	EDR Hist Auto	73	0.014	WNW
K1134 / 3	QUICK LUBE CAR SERV	10300 LAMAR BLVD N	EDR Hist Auto	73	0.014	WNW
E1227 / 3	MOBILE HOME HAVEN	11606 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	81	0.015	WNW
F1260 / 3	BARGAIN BARN	11400 N LAMAR BLVD	TX HIST UST	87	0.016	WNW
F1261 / 3	ORACLE AUSTIN DATA C	11400 N LAMAR BLVD	TX HIST UST	87	0.016	WNW
F1262 / 3	ORACLE-AUSTIN DATA C	11400 N LAMAR BLVD	TX UST, TX Financial Assurance	87	0.016	WNW
F1263 / 3	JONES MACK SERVICE S	11400 N LAMAR	EDR Hist Auto	87	0.016	WNW
G1268 / 3	CVS PHARMACY 7442	11300 11300 N LAMAR	RCRA NonGen / NLR	88	0.017	WNW
G1269 / 3	CVS PHARMACY 7442	11300 N LAMAR BLVD	TX ASBESTOS, TX Ind. Haz Waste	88	0.017	WNW
IS1278 / 3	RESTORE RUNDBURG	SEC OF LAMAR AND BRA	TX BROWNFIELDS	90	0.017	ESE
IS1395 / 3	ANTOINE GROCERY	11209 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	110	0.021	ESE
JR1566 / 3	EXPRESS FOOD MART	10500 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ED AQUI...	135	0.026	WNW
JR1567 / 3	EXPRESS MART 7	10500 N LAMAR BLVD	TX RDR	135	0.026	WNW
JR1568 / 3	SLAUSONS TEXACO	10500 LAMAR BLVD N	EDR Hist Auto	135	0.026	WNW
JS1570 / 3	7 ELEVEN 30467	10111 N LAMAR	TX RDR	136	0.026	ESE
JS1571 / 3	B PAC PITSTOP AUTO M	10111 LAMAR BLVD N	EDR Hist Auto	136	0.026	ESE
JS1572 / 3	7 ELEVEN STORE 30467	10111 N LAMAR BLVD	TX LPST, TX GCC	136	0.026	ESE
JS1573 / 3	7-ELEVEN 30467	10111 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	136	0.026	ESE
JS1574 / 3	7 ELEVEN STORE 30467	10111 N LAMAR ST	TX RDR	136	0.026	ESE
JS1575 / 3	7-11	10111 N LAMAR	TX RDR	136	0.026	ESE
1651 / 3	MONTGOMERY WARD 2276	10600 N LAMAR BLVD	TX Ind. Haz Waste	146	0.028	WNW
L1690 / 3	HILL ELECTRIC	10100 N LAMAR BLVD	TX UST, TX HIST UST	152	0.029	WNW
KB1722 / 3	AUSTIN TENNYSON 836	11409 N LAMAR	TX RDR	162	0.031	ESE
KB1723 / 3	TENNYSON 836	11409 N LAMAR BLVD	TX UST, TX AST, TX HIST UST, TX Financia...	162	0.031	ESE
KB1724 / 3	SAME	11409 N LAMAR	TX RDR	162	0.031	ESE
IS1732 / 3	7 ELEVEN 38289	701 W BRAKER LN	TX UST, TX HIST UST, TX Financial Assura...	165	0.031	ESE
1803 / 3	NORTH LAMAR SAFTI BR	701 PROVINES DR STE	TX Ind. Haz Waste	183	0.035	ESE
JR1804 / 3	AUSTIN KAWASKI	10426 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	184	0.035	WNW
JR1805 / 3	AUSTIN KAWASAKI	10426 LAMAR BLVD N	EDR Hist Auto	184	0.035	WNW
JR1806 / 3	UNDELIVERABLE	10426 N LAMAR BLVD	TX Ind. Haz Waste	184	0.035	WNW

MAPPED SITES SUMMARY - FOCUS MAP 3

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
KV1858 / 3	IMPORT CAR REPAIR	10631 LAMAR BLVD N	EDR Hist Auto	202	0.038	ESE
KV1859 / 3	IMPORT CAR REPAIR	10631 N LAMAR	TX RDR	202	0.038	ESE
KV1860 / 3	IMPORT CAR REPAIR	10631 N LAMAR BLVD	TX UST, TX HIST UST, TX Ind. Haz Waste, ...	202	0.038	ESE
J1899 / 3	TRAN RICHMOND	10800 N LAMAR BLVD	EDR Hist Auto	214	0.041	WNW
LJ1909 / 3	ZADAS AUTOMOTIVE & C	816 KRAMER LN	EDR Hist Auto	218	0.041	WNW
NN2307 / 3	AUTOMATIC TRANSMISSI	811 PRAIRIE TRL	EDR Hist Auto	332	0.063	WNW
2311 / 3	MINGOS BODY SHOP	811 MCPAUL	RCRA NonGen / NLR, FINDS, ECHO	334	0.063	WNW
LJ2324 / 3	REBREU BODY & FRAME	822 KRAMER LN	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	338	0.064	WNW
2391 / 3	RPS TRANSMISSION & A	700 W APPLEGATE DR	EDR Hist Auto	355	0.067	ESE
2443 / 3	NORTH AUSTIN FRAME &	825 KRAMER LN	EDR Hist Auto	376	0.071	WNW
2478 / 3	CONANN DEVELOPMENT	11220 N LAMAR BLVD	TX UST, TX HIST UST	394	0.075	WNW
2496 / 3	FERRIS FRAME ALLGNME	830 SAGEBRUSH DR	EDR Hist Auto	397	0.075	WNW
2533 / 3	A PAYLESS AUTOMOTIVE	11116 LAMAR BLVD N	EDR Hist Auto	413	0.078	WNW
2536 / 3	MR SERVICE CENTERS	10200 N LAMAR BLVD	EDR Hist Auto	415	0.079	WNW
NN2668 / 3	AUSTIN SALES	825 PRAIRIE TRL	TX LPST, TX UST, TX HIST UST	471	0.089	WNW
PW2755 / 3	RICHMOND AUTO	828 PRAIRIE TRL	EDR Hist Auto	527	0.100	WNW
2791 / 3	T&T TRANSMISSION	601 FERGUSON DR	EDR Hist Auto	557	0.105	ESE
QO2828 / 3	Z CAR SHOP	811 MCPHAUL	EDR Hist Auto	596	0.113	WNW
QO2829 / 3	MINGOS BODY SHOP	811 MCPHAUL ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	596	0.113	WNW
PW2844 / 3	PRONTO ENGINE & TRAN	830 PRAIRIE TRL	EDR Hist Auto	611	0.116	WNW
QO2883 / 3	AMS INC	903 MC PHAUL ST	TX HIST UST	650	0.123	WNW
QZ2889 / 3	HAIS AUTOMOTIVE	842 SAGEBRUSH DR	TX UST	660	0.125	WNW
RA2890 / 3	NETTLE WELDING WORKS	825 WAGON TRL	TX Ind. Haz Waste, TX CENTRAL REGISTRY	670	0.127	WNW
RA2891 / 3	NETTLE	825 WAGON TRL	TX Ind. Haz Waste	670	0.127	WNW
QZ2930 / 3	GERMAN AUTOHAUS	902 SAGEBRUSH DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	839	0.159	WNW
RA2948 / 3	MOLINA AUTOMOTIVE	903 WAGON TRL	TX UST, TX HIST UST	869	0.165	WNW
RA2949 / 3	MOLINA AUTOMOTIVE	903 WAGON TRAIL	TX RDR	869	0.165	WNW
2986 / 3	K & M SUPPLY	908 MC PHAUL ST	TX HIST UST	947	0.179	WNW
SV3090 / 3	J R BODY SHOP	1001 SAGEBRUSH	RCRA NonGen / NLR, FINDS, ECHO	1183	0.224	WNW
SV3091 / 3	J R BODY SHOP	1001 SAGEBRUSH DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1183	0.224	WNW
3125 / 3	PTP OPERATING	916A PRAIRIE TRL	TX DRYCLEANERS	1268	0.240	WNW
3179 / 3	MOFFITT MAINTENANCE	11502 TITAN DR	TX RDR	1581	0.299	WNW
3272 / 3	E-Z STOP 2	1200 KRAMER LN STE 1	TX LPST, TX UST, TX HIST UST, TX ED AQUI...	2440	0.462	WNW

Focus Map - 4 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 4

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
11 / 4	NYOS CHARTER SCHOOL-	12301 N. LAMAR BLVD.	TX ASBESTOS	TP		
12 / 4	WALNUT CREEK PARK MA	12138 N. LAMAR BLVD.	TX ASBESTOS	TP		
D13 / 4	WALNUT PARK APARTMEN	12101 N LAMAR BLVD	FINDS, ECHO	TP		
D14 / 4	WALNUT PARK APARTMEN	12101 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
D15 / 4	AMIGOS AUTO SALES	12100 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
1121 / 4	VACANT PROPERTY	11902 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	72	0.014	WNW
OA2395 / 4	CONCRETE CORING	820 W YAGER LN	TX Ind. Haz Waste	356	0.067	East
OA2396 / 4	CONCRETE CORING	820 W YAGER LN	TX Ind. Haz Waste	356	0.067	East
OA2397 / 4	COTTMAN TRANSMISSION	820 W YAGER LN	EDR Hist Auto	356	0.067	East
OA2767 / 4	BOSS MANUFACTURING	818 W YAGER LN	TX DRYCLEANERS, TX Ind. Haz Waste, TX CE...	546	0.103	East
TI3148 / 4	AUSTIN CULLIGAN	505 W YAGER LANE	TX LPST, TX TIER 2	1297	0.246	East
TI3149 / 4	YAGER	505 W YAGER LN	TX UST	1297	0.246	East

Focus Map - 5 - 7418065.7s


KVUE-TV HELIPORT
N Mo Pac Expy
Executive Center Dr
Shoal Creek Blvd
Burnet Rd
Burnet Ln
Greenlawn Pkwy
Great Northern Blvd
RM-2222
Bull Creek Rd
Northland Dr
Balcones Dr
Hancock Dr
Wood Hollow Dr
Hart Ln
Far West Blvd
Lamplight Ln
Stonecliff Dr
Hidden Holw
Green Trl N
Green Trl S
Pebble Path
Sidehill Path
Rockpoint Dr
Edgerock Dr
Greystone Dr
Chimney Corners
Running Rope
Montana Norte
Spurlock Dr
Sangate Dr
Northledge
Rockledge Dr
Knollwood Dr
Thorncliffe Dr
Shadow Valley Dr
Shadow Mountain Dr
Laurel Ledge Ln
Highland Hills Dr
Highland View Dr
Hillbrook Dr
Mountaintimb Dr
Highlandale Dr
Highland Pass
Westside Dr
Valleyside Rd
E Hill Dr
N Hills Dr
Village Center Dr
Sumac Dr
Jorge Dominas Dr
Las Colinas Dr
Caprice Dr
Arrowhead Dr
Highland Crest Dr
Western Hills Dr
Lucas Ln
Ridge Oak Dr
Greenway Dr
Balcones Dr
Bay Bend Dr
Valley Oak Dr
Parkcrest Dr
Trail Overlook Dr
Trailridge Dr
Lakeridge Dr
Pinecrest Dr
Stoneway Dr
Dover Pl
Lexington Rd
Argentia Rd
Carlisle Dr
W Terrace Dr
Hunt Trl
Treadway Blvd
Bullard Dr
Jarey Dr
Rickey Dr
Caitlean Dr
Marilyn Dr
Louise Ln
Parkdale Dr
Pioneer Pl
Cascade Dr
Pinewood Ter
Albata Ave
Ellise Avenue
Dougherty St
Pegram Ave
Geraghty Ave
Joyce St
Addison Ave
Park View Dr
Twin Oaks Dr
Cavalier Ave
Wilbur Dr
Cary Dr
Nasco Dr
White Horse Trl
White Rock Dr
Nyrona Ave
Woodview Ave
Shoalwood Ave
Shoalmont Dr
Montvale St
Adams Ave
Clay Ave
Ulrich Ave
Laird Dr
Hallsl
Goodnight Ln
Hardy Dr
Yates Ave
Madison Ave
Piedmont Ave
W Saint Johns Ave
Cullen Ave
Justin Ln
Santa Clara St
Vallejo St
Redlands St
Burbank St
Karen Ave
Payne Ave
Sequeno St
Alegria Rd
Romeria Dr
Alguno Rd
Palo Duro Rd
Wildcrow Ave
Grover Ave
Arcadia Ave
Choquette Dr
Dwyce Dr
Aggie Ln
Richcreek Rd
Pasadena Dr
Barbara St
Princeton Ave
Dartmouth Ave
Duke
Mullen Dr
Rutgers Ave
Marcy Dr
Brockman St
Mahone Ave
Exmoor Dr
Teakwood Dr
Kenbridge Dr
Lanier Dr
Ashdale Dr
Logwood Dr
Parkdale Dr
Briarwood Ln
Rockwood Ln
Vineywood Ln
Stillwood Ln
Buell Ave
Perry Ln
Bowling Green Dr
Hathaway Dr
Doris Dr
Reeda Ln
Collfax Ave
Steck Ave
Foster Ln
Whitepine Dr
McElroy Dr
Whiteway Dr
Yellowpine Ter
Silverleaf Dr
Skylark Dr
Stardust Dr
Starline Dr
Chevy Dr
Bayswood Dr
Forest
Paint Rock Dr
Tablerock Dr
Shadyrock Dr
Stonewood Dr
Petra Path
Rustling Rd
Mirick Dr
Enclave Mesa Cir
Wood Hollow Dr
Stoneway Dr
Dover Pl
Pioneer Pl
Lexington Rd
Argentia Rd
Carlisle Dr
Treadway Blvd
Shoal Creek Dr W
Vine St
Burnet Rd
Burnet Ln

MAPPED SITES SUMMARY - FOCUS MAP 5

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 6 - 7418065.7s


W Longspur Blvd
E Longspur Blvd
E Pheasant Dr
Ploverhill Dr
Oriole Dr
Quail Park Dr
Quail Creek Dr
Little Elm Park
Quail Cir
Quail Field Dr
Norseman Ter
Trone Cir
Colonial Dr
Clarewood Dr
Redfield Ln
Parkfield Dr
Brookfield Dr
Dryfield Dr
Beech Dr
Clearfield Dr
Maine Dr
Fairfield Dr
Maryland Dr
Bridgeport Dr
Colony North Dr
Jamestown Dr
Alden Dr
Chesapeake Dr
Bradford Dr
Hampton Dr
Little Walnut Pkwy
Cooper Dr
N Creek Dr
Weyford Dr
Villanova Dr
Kramer St
Kamar Dr
Beckett St
Lacy Ln
Wooten Dr
Wooten Park Dr
Polar Dr
Applewood Dr
Burrell Dr
Dale Dr
W Anderson Ln
Duke Ave
Research Blvd
Bangor Bnd
Thurmond St
Meadow St
W Elliott St
Guadalupe St
Beaver St
Georgetown Dr
Florence Dr
Capitol Dr
East Dr
North Dr
Middle Ln
E Fawnridge Dr
Carpenter Ave
Stevenson Dr
Oak Plz
Walnut Dr
Park Dr
Oertli Ln
Bolles Dr
W Powell Ln
White Oak Dr
W Lola Dr
E Lola Dr
E Powell Ln
E Wonsley Dr
Purnell Dr
Gasser Dr
Northway Dr
Hermitage Dr
Park Plz
N Interstate 35
Fiskville Cemetery Rd
Durham Dr
Grayledge Dr
Shenandoah Dr
Loraine Dr
Wisteria
Danville Dr
Furness Dr
Bridgetown Dr
Brentwoods Ln
Norwood Park Blvd
Connor Ln
Park Center Dr
Rutherford Ln
Clock Tower Dr
E Anderson Ln
Jackson Ave
Calver Ave
Bethune Ave
Wheatley Ave
Meadow Ave
E Bennett Ave
E Saint Johns Ave
Wilks Ave
Gaston Ave
Ruth Ave
Brentwood St
Wild St
Madison Ave
Piedmont Ave
W Overline St
Easy Wind Dr
Stobaugh St
Watson St
Taulbee Ln
Morrow St
Gault St
Tisdale Dr
Anderson Sq
Dale Dr
Duke Ave
N Lamar Blvd
Shoreline Dr
Bissonnet St
Amesbury Ln
Creston Ln
Dalafield Ln
Meadowview Ln
Pine Dell
Northcrest Blvd
W Crestland Dr
W Croslin St
W Odell St
W Saint Johns Ave
Eastcrest Dr
Delmar Ave
Blackson Ave
E Croslin St
Duval St
E Lisa Dr
Swanee Dr
Kenniston Dr
Pampa St
Rutus Dr
Miranda Dr
Priscilla Dr
Deborah Dr
Twin Crest Dr
Brenda Dr
Esther Dr
Epplunland Dr
Roland Johnson Dr
Airport Blvd
W Hunthanna Dr
Irma Dr
Wilmes Dr
Hamp
Burnet St
Gaylor St
Wilson St
Merrell St
Morrow St
Sunset Ave
Stoddard Ave
Easy Wind Dr
Lamar Blvd
Research Blvd
Burnet Rd
Interstate 35
Austin Bergstrom Int'l Arpt
Austin Bergstrom Int'l Arpt
Austin Bergstrom Int'l Arpt

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
N48 / 6	FAMILY DOLLAR	9719 N LAMAR BLVD	TX ASBESTOS	TP
O49 / 6	LAUNDRY BASKET NO 1	9644 LAMAR BLVD N	EDR Hist Cleaner	TP
O50 / 6	DRY CLEAN CITY 125	9626 N LAMAR BLVD	EDR Hist Cleaner	TP
O51 / 6	DRY CLEAN CITY	9626 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	TP
O52 / 6	DRY CLEAN CITY	9626 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
O53 / 6	AUTO ZONE 1396	9620 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
O54 / 6	AUTO ZONE 1396	9620 N LAMAR BLVD	FINDS	TP
O55 / 6	ACME CLEANERS	9606 LAMAR BLVD N	EDR Hist Cleaner	TP
56 / 6	DOLLAR TREE	9514 N LAMAR BLVD	TX ASBESTOS	TP
P57 / 6	HEB 183	9411B N LAMAR BLVD	TX CENTRAL REGISTRY	TP
P58 / 6	ACEMART RESTAURANT S	9411 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	TP
P59 / 6	HEB 183	9411B N LAMAR BLVD	FINDS	TP
P60 / 6	HEB 183	9411B N LAMAR BLVD	TX UST, TX Financial Assurance	TP
Q61 / 6	A ACME CLEANERS & LA	9302 LAMAR BLVD N	EDR Hist Cleaner	TP
R62 / 6	CAPITAL FINA OIL SER	8909 LAMAR BLVD N	EDR Hist Auto	TP
R63 / 6		8833 NORTH LAMAR	ERNS	TP
R64 / 6	TARGA PORSCHE	8833 LAMAR BLVD N	EDR Hist Auto	TP
R65 / 6	TARGA PORSCHE	8833 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
S66 / 6	LACE	8829 N LAMAR BLVD	TX Ind. Haz Waste	TP
S67 / 6	LACE	8829 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
S68 / 6	AUSTIN DATSUN REPAIR	8825 LAMAR BLVD N	EDR Hist Auto	TP
S69 / 6	LACE ENGINEERING	8825 N LAMAR	TX CENTRAL REGISTRY	TP
S70 / 6	TRIPLE JS TIRE CENTE	8821 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
T71 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	TX CENTRAL REGISTRY	TP
T72 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	TX Ind. Haz Waste	TP
T73 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	RCRA NonGen / NLR	TP
T74 / 6	ALLSTAR BODY SHOP	8703A N LAMAR BLVD	FINDS, ECHO	TP
T75 / 6	CULP SERV STA	8703 LAMAR BLVD	EDR Hist Auto	TP
U76 / 6	DIP STICK	8601 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
U77 / 6	DIP STICK	8601 LAMAR BLVD N	EDR Hist Auto	TP
V78 / 6	FINELINE SPORTSWEAR	8451 N LAMAR BLVD	TX Ind. Haz Waste	TP
V79 / 6	FINELINE SPORTSWEAR	8451 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
V80 / 6	UNIVAR USA - PP&S AU	8402 N. LAMAR, SUITE	TX TIER 2	TP
V81 / 6	UNIVAR USA ES -AUSTI	8402 N LAMAR	FINDS	TP
W82 / 6	THIRD COAST AUTO GRO	8316 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
W83 / 6	RYDER TRUCK, IH-35 M	RYDER TRUCK, IH-35 M	TX SPILLS	TP
X84 / 6	RELIABLE AUTOM	8226 LAMAR BLVD N	EDR Hist Auto	TP
X85 / 6	SCHEIDERS SIN	8224 LAMAR BLVD N	EDR Hist Auto	TP
Y86 / 6	AUSTIN BRAKE & CLUTC	8151 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
Y87 / 6	AUSTIN BRAKE & CLUTC	8151 N LAMAR BLVD	TX UST	TP
Z88 / 6	ACME DRY CLEANERS &	7541 LAMAR BLVD N	EDR Hist Cleaner	TP
Z89 / 6	D & L MOTORCYCLES	7535 N LAMAR BLVD	TX ENF, TX COMP HIST	TP
Z90 / 6	D & L MOTORCYCLES	7535 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
Z91 / 6	D & L MOTORCYCLE INC	7535 LAMAR BLVD N	EDR Hist Auto	TP
AA92 / 6	NORTH LAMAR AUTO BOD	7313 NORTH LAMAR BLV	TX ENF, TX COMP HIST	TP
AA93 / 6	A & A USED TIRES	7313 N LAMAR BLVD	TX ENF, TX COMP HIST	TP
AA94 / 6	NORTH LAMAR AUTO BOD	7313 NORTH LAMAR BLV	TX CENTRAL REGISTRY	TP
AA95 / 6	K W AUTO REPAIR	7313 LAMAR BLVD N	EDR Hist Auto	TP
AA96 / 6	JC TIRE & WHEELS	7313 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AA97 / 6	NORTHSIDE GARAGE AUT	7277 LAMAR BLVD N	EDR Hist Auto	TP
AB98 / 6	A 1 TRANSMISSION	7227 LAMAR BLVD N	EDR Hist Auto	TP
AB99 / 6	PATS LAWN MOWER SVC	7201 N LAMAR BLVD	TX ENF, TX Ind. Haz Waste, TX CENTRAL RE...	TP
AB100 / 6	PATS LAWN MOWER SVC	7201 N LAMAR BLVD	TX COMP HIST	TP
AB101 / 6	7121 N LAMAR BLVD	7121 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AB102 / 6	AUTOMETRICS INC AUTO	7121 LAMAR BLVD N	EDR Hist Auto	TP
AB103 / 6	7121 N LAMAR BLVD	7121 N LAMAR BLVD	TX VCP, TX HIST UST, TX GCC	TP
AB104 / 6	OUTPLAN	7121 NORTH LAMAR	TX ASBESTOS	TP
AB105 / 6	JIMS GULF STATION GA	7107 LAMAR BLVD N	EDR Hist Auto	TP
AB106 / 6	AUSTIN RESEARCH LABO		PFAS ECHO	TP
AC107 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC108 / 6	AUSTIN LABORATORIES	7114 N LAMAR BLVD	TSCA, TX AIRS, TX Ind. Haz Waste, TX IHW...	TP
AC109 / 6	HUNTSMAN PETRO - AUS	7114 NORTH LAMAR BOU	TSCA	TP
AC110 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC111 / 6	TEXACO-AUSTIN LABORA	7114 N LAMAR BLVD	TSCA	TP
AC112 / 6	TEXACO CHEMICAL	7114 N. LAMAR	TX SPILLS 90	TP
AC113 / 6	HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	TSCA	TP
AC114 / 6	HUNTSMAN CORP	7114 N. LAMAR	TX SPILLS 90	TP
AC115 / 6	7114 N. LAMAR, AUSTI	7114 N. LAMAR, AUSTI	TX SPILLS	TP
AC116 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	TX GCC	TP
AC117 / 6	AUSTIN LABORATORIES	7114 N LAMAR BLVD	TX UST, TX HIST UST	TP
AC118 / 6		7114 N. LAMAR BL.	ERNS	TP
AC119 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC120 / 6	HUNTSMAN PETROCHEMIC	7114 NORTH LAMAR BOU	RMP	TP
AC121 / 6	7114 NORTH LAMAR (SO	7114 NORTH LAMAR (SO	TX SPILLS	TP
AC122 / 6	TEXACO CHEMICAL COMP	7114 N. LAMAR BOULEV	FTTS	TP
AC123 / 6	7114 N.LAMAR, AUSTIN	7114 N.LAMAR, AUSTIN	TX SPILLS	TP
AC124 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC125 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	FINDS	TP

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AC126 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC127 / 6	DOWTHERM VAPOR GENER	7114 N LAMAR BLVD	TX AIRS	TP
AC128 / 6		7114 N LAMAR ST	ERNS	TP
AC129 / 6	STEAM GENERATOR - JC	7114 N LAMAR BLVD	TX AIRS	TP
AC130 / 6		7114 N LAMAR BLVD	ERNS	TP
AC131 / 6	TEXACO CHEMICAL CO	7114 N.LAMAR	TX SPILLS 90	TP
AC132 / 6	TEXACO CHEMICAL	7114 NORTH LAMAR (SO	TX SPILLS 90	TP
AC133 / 6		7114 N LAMAR BLVD	ERNS	TP
AC134 / 6	HUNTSMAN PETROCHEMIC	7114 N LAMAR BLVD	SEMS-ARCHIVE, CORRACTS, RCRA-TSDF, RCRA I	TP
AC135 / 6	HUNTSMAN PETROCHEMIC	7114 N. LAMAR BLVD.	ICIS, FINDS, ECHO	TP
AC136 / 6	CRESTVIEW STATION	7114 N LAMAR BLVD	TX VCP, TX UIC, TX COMP HIST	TP
AC137 / 6	TEXACO CHEMICAL COMP	7114 N. LAMAR BOULEV	HIST FTTS	TP
AC138 / 6	7114 NORTH LAMAR, AU	7114 NORTH LAMAR, AU	TX SPILLS	TP
AC139 / 6	7114 N. LAMAR, AUSTI	7114 N. LAMAR, AUSTI	TX SPILLS	TP
AC140 / 6	7114 NORTH LAMAR BLV	7114 NORTH LAMAR BLV	TX SPILLS	TP
AC141 / 6		7114 NORTH LAMAR BLV	ERNS	TP
AC142 / 6		7114 N LAMAR BLVD	ERNS	TP
AC143 / 6	BLACKBURN TEXACO SER	7006 LAMAR BLVD N	EDR Hist Auto	TP
AC144 / 6	HUNTSMAN CORP. CHEMI	HUNTSMAN CORP. CHEMI	TX SPILLS	TP
AC145 / 6	TEXACO CHEMICAL PLAN	TEXACO CHEMICAL PLAN	TX SPILLS	TP
AC146 / 6	TEXACO CHEMICAL CO P	TEXACO CHEMICAL CO P	TX SPILLS	TP
AC147 / 6		7114 N. LAMAR	ERNS	TP
148 / 6	HEART-O-TEXAS FILM L	6929 N LAMAR BLVD	TX HIST UST	TP
AD149 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX LPST, TX UST	TP
AD150 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AD151 / 6	AUSTIN STANDARD TRAN	6916 LAMAR BLVD N	EDR Hist Auto	TP
AD152 / 6	JAMES EICHELBERGER J	6916 N LAMAR BLVD	TX HIST UST	TP
AD153 / 6	DING DONG AUTO CENTE	6916 N LAMAR BLVD	TX HIST UST	TP
AE154 / 6	SOUTHCREST PARK	6811 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AE155 / 6	AUSTIN KAWASAKI MOTO	6801 LAMAR BLVD N	EDR Hist Auto	TP
AE156 / 6	COLORPRESS INC	6801 N LAMAR BLVD	TX HIST UST	TP
AF157 / 6	K O MACHINE	6721 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AF158 / 6	K 0 MACHINE CO	6721 LAMAR BLVD N	EDR Hist Auto	TP
AF159 / 6	K O MACHINE INC	6721 N LAMAR BLVD ST	RCRA NonGen / NLR, FINDS, ECHO	TP
AF160 / 6	KO MACHINE SHOP	6721 N LAMAR	RCRA-SQG	TP
AF161 / 6	QUICKY	6719 N LAMAR BLVD	TX ASBESTOS	TP
AF162 / 6	NORTH LAMAR AND SHIR	6709 N LAMAR	TX ASBESTOS	TP
AF163 / 6	6705 N LAMAR BLVD, A	6705 N LAMAR BLVD,	US BROWNFIELDS, FINDS	TP
AF164 / 6	A-AABAT STORAGE	6705 N LAMAR BLVD	TX LPST, TX TANKS, TX GCC, TX RDR	TP

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AF165 / 6	A-AABAT SEF STORAGE	6705 N LAMAR BLVD	TX HIST UST	TP		
AF166 / 6	GLENN SERV STA	6705 LAMAR BLVD	EDR Hist Auto	TP		
AF167 / 6	EARNEST E PANNELL JR	6705 N LAMAR BLVD	TX HIST UST	TP		
AF168 / 6	A-AABAT STORAGE	6705 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
AG169 / 6	JEFFS CUSTOM BODY SH	6616 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP		
AG170 / 6	JEFFS CUSTOM BODY SH	6616 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	TP		
AG171 / 6	VEHICLE REPAIR & REF	6614 N. LAMAR	TX CENTRAL REGISTRY	TP		
AG172 / 6	RIVER CITY BULTACO M	6614 LAMAR BLVD N	EDR Hist Auto	TP		
AG173 / 6	SOUTHERN UNION GAS C	6615 NORTH LAMAR	DOT OPS	TP		
AH174 / 6	TASTE OF INK	6541 N LAMAR BLVD #B	TX ASBESTOS	TP		
AH175 / 6	RAYS GARAGE	6517 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
AH176 / 6	RAYS GARAGE	6517 LAMAR BLVD N	EDR Hist Auto	TP		
AH177 / 6	RAYS GARAGE	6517 N LAMAR BLVD	TX UST, TX HIST UST	TP		
AH178 / 6	WOODS HONDA	6509 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	TP		
AH179 / 6	WOODS HOND	6509 LAMAR BLVD N	EDR Hist Auto	TP		
AI180 / 6	JIFFV BRAKE SERVICE	6322 LAMAR BLVD N	EDR Hist Auto	TP		
R970 / 6	FRUZIA FINA SERVICE	8911 LAMAR BLVD N	EDR Hist Auto	61	0.012	ESE
R971 / 6	CAPITAL FOOD MART	8911 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	61	0.012	ESE
R972 / 6	TETCO 1144	8911 N LAMAR BLVD	TX LPST, TX GCC	61	0.012	ESE
AG983 / 6	ZIPPY FOOD STORE	6600 N LAMAR BLVD	TX HIST UST, TX CENTRAL REGISTRY	62	0.012	WNW
AG984 / 6	ZIPPY FOOD STORE	6600 N LAMAR BLVD	TX LPST	62	0.012	WNW
N986 / 6	FAMILY DOLLAR #6170	9717 N. LAMAR BLVD	RCRA-VSQG, FINDS	62	0.012	ESE
N987 / 6	WALGREEN CO	9717 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	62	0.012	ESE
AG989 / 6	PAYLESS GAS 866	6608 N LAMAR BLVD	TX UST	63	0.012	WNW
AG990 / 6	FUEL DISTRIBUTORS	6608 N LAMAR BLVD	TX UST	63	0.012	WNW
AG991 / 6	PAYLESS GAS	6608 LAMAR BLVD N	EDR Hist Auto	63	0.012	WNW
AI992 / 6	FAMOUS FOOD MART	6301 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	63	0.012	ESE
AI993 / 6	FOOD MART GAS & FOOD	6301 LAMAR BLVD N	EDR Hist Auto	63	0.012	ESE
AI994 / 6	SHELL FOOD MART	6301 N LAMAR BLVD	TX RDR	63	0.012	ESE
HZ1010 / 6	NORTH LAMAR AUTOMOTI	8807 A N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	64	0.012	NW
X1011 / 6	RELIABLE AUTOMOTIVE	8225 LAMAR BLVD N	EDR Hist Auto	65	0.012	SE
X1012 / 6	RELIABLE AUTOMOTIVE	8225 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	65	0.012	SE
Z1027 / 6	BOYEA ASSOCIATES INC	7530 N LAMAR	EDR Hist Auto	65	0.012	WNW
X1029 / 6	UNCLE BOB'S STORAGE	8227 N. LAMAR BLVD.	TX HIST UST, TX ASBESTOS	66	0.013	SE
O1056 / 6	MANAISH ENTERPRISES	9616 N LAMAR BLVD ST	EDR Hist Cleaner	68	0.013	WNW
O1057 / 6	AARONS	9616 N LAMAR BLVD	TX VCP, TX ASBESTOS	68	0.013	WNW
W1076 / 6	DONCO TRUCK & AUTOMO	8305 LAMAR BLVD N	EDR Hist Auto	69	0.013	SE
W1077 / 6	RYDER TRUCK RENTAL 0	8305 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	69	0.013	SE
AI1079 / 6	CENTRAL TEXAS HARLEY	6310 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
IE1084 / 6	A LONDON BRIDGE AUTO	6406 LAMAR BLVD N	EDR Hist Auto	69	0.013	WNW
V1095 / 6	FINELINE SPORTSWEAR	8407A N LAMAR BLVD	TX Ind. Haz Waste	70	0.013	SE
IE1097 / 6	THREADGILLS	6416 N LAMAR BLVD	TX UST, TX HIST UST	70	0.013	WNW
IE1098 / 6	THREADGILLS FILL STA	6416 LAMAR BLVD	EDR Hist Auto	70	0.013	WNW
U1114 / 6	LUU AUTO ELECTRIC	8603 N. LAMAR BLVD.	TX HIST UST, TX RDR	71	0.013	SE
U1115 / 6	COURTNEY SIXTY SIX	8603 LAMAR BLVD	EDR Hist Auto	71	0.013	SE
Z1116 / 6	LAMAR CORNER STORE	7545 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	71	0.013	ESE
S1137 / 6	QUALITY ENGINE EXCHA	8807 B N LAMAR BLVD	RCRA-VSQG, FINDS, ECHO, TX Ind. Haz Wast...	73	0.014	SE
S1138 / 6	AUSTIN QUALITY ENGIN	8807 LAMAR BLVD N	EDR Hist Auto	73	0.014	SE
S1139 / 6	OLMEDA TIRE & AUTO	8807 N LAMAR BLVD	TX RDR	73	0.014	SE
S1140 / 6	NORTH LAMAR AUTOMOTI	8807 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	73	0.014	SE
AH1148 / 6	B & B BODY & FRAME	6518 N LAMAR BLVD	TX AIRS, TX Ind. Haz Waste, TX COMP HIST...	74	0.014	WNW
AH1149 / 6	B & B BODY & FRAME I	6518 N LAMAR	RCRA NonGen / NLR	74	0.014	WNW
II1152 / 6	CALIBER COLLISION NO	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
II1153 / 6	CALIBER COLLISION CE	8735 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	74	0.014	SE
II1154 / 6	DUPLICATE OF 76136	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
II1155 / 6	MAACO	8735 N LAMAR BLVD	TX Ind. Haz Waste	74	0.014	SE
AG1156 / 6	B LAMAR CINS NO	812 BRANTWOOD ST	EDR Hist Cleaner	74	0.014	WNW
HZ1190 / 6	B JATCO TRANSMISSION	8745 LAMAR BLVD N	EDR Hist Auto	78	0.015	SE
AF1230 / 6	AUS TEX BODY SHOP	6706 LAMAR BLVD N	EDR Hist Auto	82	0.016	WNW
Y1247 / 6	ALAMO BOILER & MACHI	8134 N LAMAR BLVD	TX HIST UST	84	0.016	NW
AG1307 / 6	COIN 00 MATIC LAUNDR	6607 LAMAR BLVD N	EDR Hist Cleaner	95	0.018	ESE
AG1308 / 6	STONE COMPANY	6607 N LAMAR BLVD	TX HIST UST	95	0.018	ESE
Z1331 / 6	DALE'S AUTO	7544 N. LAMAR	TX RDR	101	0.019	WNW
Z1332 / 6	DOC HOLLIDAYS PAWN S	7544 N LAMAR BLVD	TX UST	101	0.019	WNW
AG1352 / 6	NORVELL MACHINERY CO	6535 LAMAR BLVD N	EDR Hist Cleaner	104	0.020	ESE
R1356 / 6	ACME DRY CLEANERS &	8901 LAMAR BLVD N	EDR Hist Cleaner	105	0.020	ESE
IZ1360 / 6	DURACLEAN ARTHOR CAR	6901 LAMAR BLVD N	EDR Hist Cleaner	106	0.020	ESE
IZ1361 / 6	SPIGHT AUTOMOTIVE	6901 N LAMAR BLVD	EDR Hist Auto	106	0.020	ESE
Z1399 / 6	KWIK WASH COIN LAUND	7543 LAMAR BLVD N	EDR Hist Cleaner	112	0.021	ESE
JG1453 / 6	TEXAS FOOD MART	720 LAMAR PL	TX UST, TX HIST UST, TX Financial Assura...	120	0.023	ESE
AC1465 / 6	REED OIL CO GAS STA	7135 LAMAR BLVD N	EDR Hist Auto	121	0.023	ESE
AC1466 / 6	PIONEER SERVICE CO.	7135 N LAMAR BLVD	TX HIST UST	121	0.023	ESE
JM1494 / 6	CAPITAL FOOD STOP 2	8201 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	124	0.023	SE
JM1495 / 6	CIRCLE K STORES INC	8201 N LAMAR BLVD	EDR Hist Auto	124	0.023	SE
AB1499 / 6	PATS LAWNMOWER SERVI	7205 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	126	0.024	ESE
AB1500 / 6	SCOGIN EXXON PRODUCT	7205 LAMAR BLVD N	EDR Hist Auto	126	0.024	ESE
T1552 / 6	NORTH LAMAR PHILLIPS	8700 LAMAR BLVD N	EDR Hist Auto	134	0.025	NW
T1553 / 6	GIANT FOOD MART	8700 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	134	0.025	NW

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
R1591 / 6	7-ELEVEN 25445	8900 N LAMAR	TX RDR	139	0.026	WNW
R1592 / 6	GRIFFS TEXACO SERVIC	8900 LAMAR BLVD N	EDR Hist Auto	139	0.026	WNW
R1593 / 6	7-ELEVEN 25445	8900 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	139	0.026	WNW
R1594 / 6	7 ELEVEN 25445	8900 N LAMAR	TX RDR	139	0.026	WNW
JG1621 / 6	KWIK WASH LAUNDRY	718 LAMAR PL	EDR Hist Cleaner	142	0.027	ESE
JU1633 / 6	GUTHRIE CLEANERS	9200 N LAMAR BLVD ST	TX DRYCLEANERS	144	0.027	WNW
JU1634 / 6	GUTHRIES CLEANERS	9200 LAMAR BLVD N	EDR Hist Cleaner	144	0.027	WNW
1753 / 6	GREASERS	8415 N LAMAR BLVD	TX UST, TX HIST UST	170	0.032	SE
Q1762 / 6	SAFETY RIDE CAR CARE	9307 LAMAR BLVD N	EDR Hist Auto	173	0.033	ESE
1777 / 6	WILKERSON TRUCK LINE	6613 N LAMAR BLVD	TX HIST UST	176	0.033	ESE
KM1787 / 6	NORTH LAMAR QUICK ST	8545 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Financi...	179	0.034	SE
KM1788 / 6	SIGMOR SHAMROCK SERV	8545 LAMAR BLVD N	EDR Hist Auto	179	0.034	SE
AD1813 / 6	B & M DISCOUNT TRANS	808 JUSTIN LN	EDR Hist Auto	187	0.035	WNW
U1856 / 6	BUSKES GARAGE	8609 LAMAR BLVD	EDR Hist Auto	200	0.038	SE
JG1888 / 6	AMMOCO TRANSMISSIONS	712 LAMAR PL	TX HIST UST	211	0.040	ESE
AI1892 / 6	JIMS BODY SHOP	6324 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	213	0.040	WNW
AI1893 / 6	A CAR 4 YOU INC	6324 N LAMAR BLVD	EDR Hist Auto	213	0.040	WNW
AI1894 / 6	JIMS BODY SHOP	6324 N LAMAR BLVD	TX HIST UST, TX ASBESTOS, TX Ind. Haz Wa...	213	0.040	WNW
LN1940 / 6	LUCKY CLEANERS	7601 N LAMAR BLVD ST	EDR Hist Cleaner	234	0.044	ESE
LN1941 / 6	LUCKY CLEANERS	7601 N LAMAR BLVD ST	TX DRYCLEANERS	234	0.044	ESE
1966 / 6	WESTERN AUTO	9316 N LAMAR BLVD	TX LPST, TX UST	241	0.046	WNW
LR1967 / 6	F M PAULS CONCRETE C	6506 SHIRLEY AVE	TX UST, TX HIST UST	241	0.046	ESE
1971 / 6	CHAMBERLAIN S M GARA	7209 LAMAR BLVD N	EDR Hist Auto	242	0.046	ESE
IZ1978 / 6	AUSTEX INTERIORS	6910 SHIRLEY AVE	TX UST, TX HIST UST	245	0.046	ESE
1981 / 6	BRODIE MARKET INC	812 THURMOND ST	EDR Hist Auto	246	0.047	NW
1993 / 6	NISHIO INTERNATIONAL	8610 N LAMAR STE 101	EDR Hist Cleaner	250	0.047	NW
LR2005 / 6	PARAGON PRINTING & M	706 BRENTWOOD ST STE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	254	0.048	ESE
2059 / 6	CAPITAL PREFABRICATO	6926 N LAMAR BLVD	TX HIST UST	272	0.052	WNW
LR2082 / 6	RAYS REPAIR	6516 SHIRLEY AVE	EDR Hist Auto	279	0.053	ESE
2116 / 6	CRUZ AUTOMOTIVE	8827 LAMAR BLVD N	EDR Hist Auto	281	0.053	SE
2172 / 6	B ALL AUTO SERVICE W	607 DEEN AVE	EDR Hist Auto	287	0.054	SE
MW2179 / 6	CINBAR ENGINEERING C	711 W ST. JOHNS AVE	TX HIST UST	290	0.055	ESE
NF2244 / 6	DIAMOND SHAMROCK	806 W RUNDBERG LN	EDR Hist Auto	307	0.058	WNW
NF2245 / 6	DIAMOND SHAMROCK 964	806 W RUNDBERG LN	TX LPST, TX UST, TX HIST UST	307	0.058	WNW
MW2286 / 6	ALLEN RADIATORS	707 ST JOHNS AVE W	EDR Hist Auto	324	0.061	ESE
NO2309 / 6	AUSTIN COMPLETE AUTO	821 BRENTWOOD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	334	0.063	WNW
NO2310 / 6	B & B BODY & PAINT R	821 BRANTWOOD ST	EDR Hist Auto	334	0.063	WNW
NR2322 / 6	AUSTIN SHEET METAL S	715 W POWELL LN	TX HIST UST	338	0.064	SE
NR2392 / 6	COLD	704 W POWELL LN	TX LPST, TX UST, TX HIST UST	356	0.067	SE

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
OL2470 / 6	HOWARD MCELROY	6607 SHIRLEY AVE	TX UST, TX HIST UST	388	0.073	ESE
OL2471 / 6	AUTOMOTIVE REFINISH	6615 SHIRLEY AVENUE	RCRA-SQG, FINDS, ECHO	388	0.073	ESE
OP2488 / 6	DOLLARS & SENSE DRY	6929 AIRPORT BLVD ST	TX ASBESTOS, TX DRYCLEANERS	396	0.075	ESE
OP2489 / 6	RAILYARD	6929 AIRPORT BLVD	EDR Hist Cleaner	396	0.075	ESE
2500 / 6	CENTRAL ELECTRICAL A	6719 SHIRLEY AVE	TX HIST UST	401	0.076	ESE
LR2522 / 6	CERTIFIED BRAKES	6507 SHIRLEY AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	410	0.078	ESE
LR2523 / 6	OVERSEAS MOTORS AUTO	6507 SHIRLEY AVE	EDR Hist Auto	410	0.078	ESE
OU2537 / 6	PIERPOINT MOTORS	8140 LAMAR BLVD N	EDR Hist Auto	415	0.079	NW
2544 / 6	AUBRY HILLS	8926 N LAMAR BLVD	TX IHW CORR ACTION	422	0.080	WNW
OU2588 / 6	AUSTIN HWY TRK PARTS	8204 N LAMAR BLVD	TX Ind. Haz Waste	440	0.083	NW
OU2589 / 6	DISCOUNT DRIVE AXLE	8204 N LAMAR BLVD SU	RCRA NonGen / NLR, FINDS, ECHO	440	0.083	NW
OU2590 / 6	BEAVER & SON AUTO &	8204 LAMAR BLVD N	EDR Hist Auto	440	0.083	NW
OU2591 / 6	FLASHCARDS	8204 N LAMAR SUITE C	RCRA NonGen / NLR, FINDS, ECHO	440	0.083	NW
OU2592 / 6	FLASHCARDS	8204 N LAMAR BLVD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	440	0.083	NW
OU2593 / 6	DISCOUNT DRIVE AXLE	8204 N LAMAR BLVD ST	TX Ind. Haz Waste	440	0.083	NW
2616 / 6	ACCUGRAPHICS	7801 N LAMAR BLVD ST	TX Ind. Haz Waste	452	0.086	ESE
2672 / 6	CITY CONSERVATION	625 BRENTWOOD ST	TX HIST UST	472	0.089	ESE
2705 / 6	FURROW BUILDING MATE	8319 N LAMAR	RCRA-VSQG, FINDS, ECHO	485	0.092	SE
PV2751 / 6	RAILTON MANUFACTURIN	906 JUSTIN LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	522	0.099	WNW
PV2752 / 6	6909 RYAN DRIVE PROP	906 JUSTIN LN	TX VCP	522	0.099	WNW
2788 / 6	BANYON AUTOMOTIVE AU	916 BANYAN ST	EDR Hist Auto	556	0.105	WNW
2801 / 6	SMS TRADING USA INC	9036 N LAMAR BLVD AP	EDR Hist Cleaner	562	0.106	WNW
QG2804 / 6	A&B RUG & CARPET	654 CANION	EDR Hist Cleaner	566	0.107	ESE
2836 / 6	BLACK & DECKER	911 W ANDERSON LN	TX Ind. Haz Waste, TX CENTRAL REGISTRY	606	0.115	WNW
QR2845 / 6	A E D AUTO UPHOLSTER	615 POWELL LN W	EDR Hist Auto	612	0.116	SE
QS2848 / 6	COMET CLEANERS	9515 N LAMAR STE 108	RCRA NonGen / NLR, FINDS, ECHO	620	0.117	ESE
QS2849 / 6	COMET CLEANERS	9515 LAMAR BLVD N	EDR Hist Cleaner	620	0.117	ESE
QS2850 / 6	STAR BRITE CLEANERS	9515 N LAMAR BLVD ST	TX DRYCLEANERS, TX Ind. Haz Waste, TX CE...	620	0.117	ESE
QR2853 / 6	BRITISH MOTOR CAR SE	617 W POWELL LN # A	TX Ind. Haz Waste, TX CENTRAL REGISTRY	621	0.118	SE
QR2855 / 6	B CAMERON AUTOMOTIVE	611 POWELL LN W	EDR Hist Auto	623	0.118	SE
2856 / 6	STANFORD GUY REPR SH	508 JOAN OF ARC	EDR Hist Auto	628	0.119	ESE
QG2876 / 6	BANNER SIGNS	650 CANION ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	646	0.122	ESE
2919 / 6	AUSTIN WASTE OIL SER	7300B MARCELL ST	TX Ind. Haz Waste	773	0.146	ESE
RN2950 / 6	AMERICAN PRINTERS EX	630 CANION ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	877	0.166	ESE
RU2978 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX CLI	940	0.178	WNW
RU2979 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX CLI	940	0.178	WNW
RU2980 / 6	TEXACO CHEMICALS	7114 N. LAMAR BLVD	TX HIST LF	940	0.178	WNW
RN2988 / 6	KO MACHINE	620 CANION ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	952	0.180	ESE
3039 / 6	NATIONAL TIRE & BATT	8002 RESEARCH BLVD	RCRA-VSQG	1065	0.202	NW

MAPPED SITES SUMMARY - FOCUS MAP 6

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
3048 / 6	CIRCLE K 3213	6812 AIRPORT BLVD	TX UST	1090	0.206	ESE
3083 / 6	SUPER K GRO	6700 GUADALUPE ST ST	TX UST, TX HIST UST, TX Financial Assura...	1157	0.219	ESE
SX3098 / 6	UNICOPY CORP	1011 W ANDERSON LN	RCRA NonGen / NLR, FINDS, ECHO	1205	0.228	WNW
SX3099 / 6	UNICOPY	1011 W ANDERSON LN	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1205	0.228	WNW
3176 / 6	FIRE STATION 16	7000 REESE LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1552	0.294	WNW
3196 / 6	MERCEDES BENZ OF AUS	6757 AIRPORT BLVD	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	1788	0.339	ESE
3202 / 6	RED ARROW FREIGHT LI	8080 PURNELL DR	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	1819	0.345	SE
3203 / 6	MERCEDES BENZ OF AUS	412 PAMPA DR	TX TANKS, TX HIST UST, TX COMP HIST, TX ...	1841	0.349	ESE
TS3220 / 6	SUNRISE MINI MART 7	102 W POWELL LN	TX LPST, TX UST, TX HIST UST, TX ENF, TX...	1981	0.375	SE
TS3221 / 6	DIAMOND SHAMROCK 215	102 W POWELL LN	TX RDR	1981	0.375	SE
3228 / 6	BEKINS MOVING STORAG	201 E ANDERSON LN	TX LPST	2095	0.397	ESE

Focus Map - 7 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites
Target Property	Power Line	Indian Reservations BIA
Search Buffer	Pipe Line	
Focus Map - No Sites	National Priority List Sites	

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 7

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 8 - 7418065.7s



Sites	Focus Map - Sites
Target Property	Power Line
Search Buffer	Pipe Line
Focus Map - No Sites	National Priority List Sites
Dept. Defense Sites	Indian Reservations BIA

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
Reg / 8	NG CAMP MABRY		DOD	5487 1.039 WNW
AK191 / 8	DEPARTMENT OF PUBLIC	5808 NORTH LAMAR BLV	TX ASBESTOS	TP
AK192 / 8	NORTH AUSTIN RESERVO	5802 N LAMAR BOULEVA	FINDS, ECHO	TP
AK193 / 8	NORTH AUSTIN RESERVO	5802 N LAMAR BOULEVA	TX COMP HIST, TX CENTRAL REGISTRY	TP
AK194 / 8	NORTH AUSTIN RESERVO	5802 N. LAMAR	TX ASBESTOS	TP
AK195 / 8	DEPARTMENT OF PUBLIC	DEPARTMENT OF PUBLIC	TX SPILLS	TP
AK196 / 8	TEXAS DEPARTMENT OF	5805 NORTH LAMAR	PRP	TP
AK197 / 8	TEXAS DEPARTMENT OF	5805 NORTH LAMAR BLV	PRP	TP
AK198 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR, AUSTIN	TX SPILLS, TX ASBESTOS, TX ENF	TP
AK199 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO	TP
AK200 / 8	TEXAS DEPARTMENT OF	5805 N. LAMAR BLVD.	TX TIER 2	TP
AK201 / 8	DPS HEADQUARTERS - D	5805 N LAMAR BLVD	ECHO	TP
AK202 / 8	DPS HEADQUARTERS - D	5805 N LAMAR BLVD	FINDS	TP
AK203 / 8	TEXAS DEPARTMENT OF	5805 N LAMAR BLVD	TX ASBESTOS, TX Ind. Haz Waste	TP
AK204 / 8	DEPARTMENT OF PUBLIC	5805 NORTH LAMAR	TX ASBESTOS	TP
AK205 / 8	TEXAS DEPARTMENT OF	5805 N. LAMAR	TX ASBESTOS	TP
AK206 / 8	DPS HEADQUARTERS	5805 N LAMAR BLDG R	TX ASBESTOS	TP
AK207 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR BLVD	TX AIRS, TX ASBESTOS, TX IHW CORR ACTION...	TP
AK208 / 8	TX. DEPT. OF PUBLIC	5805 N. LAMAR BLVD.	TX LPST, TX ASBESTOS	TP
AK209 / 8	TEXAS DEPARTMENT OF	5805 LAMAR BLVD	TX ASBESTOS	TP
AK210 / 8	TEXASDEPARTMENT OF P	5805 NORTH LAMAR	TX ASBESTOS	TP
AK211 / 8	TEXAS DEPT OF PUBLIC	5805 N LAMAR BLVD	TX UST	TP
AK212 / 8	DEPARTMENT OF PUBLIC	5801 NORTH LAMAR	TX ASBESTOS	TP
AK213 / 8	DEPARTMENT OF PUBLIC	5801 N. LAMAR	TX ASBESTOS	TP
AL214 / 8	CITY OF AUSTIN EMS S	5710 NORTH LAMAR BLV	TX ASBESTOS	TP
AL215 / 8	NORTH SERVICE CENTER	5708 NORTH LAMAR BLV	TX ASBESTOS	TP
AM216 / 8	TORN MACHINERY COMP.	5545 N LAMAR BLVD	TX HIST UST	TP
AN217 / 8	ATLAS AUTO AIR	5408 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
AN218 / 8	CAMDEN LAMAR HEIGHTS	5400 N. LAMAR BLVD.	TX ASBESTOS	TP
AN219 / 8	CENTRAL TEXAS REGION	5400 N LAMAR BLVD	TX UST	TP
AN220 / 8	CENTRAL TEXAS REGION	5400 N LAMAR BLVD	TX CENTRAL REGISTRY	TP
AO221 / 8	FORMER BUCKS FEED ST	5327 N. LAMAR	TX ASBESTOS	TP
AO222 / 8	J&J GARAGE	5312 LAMAR BLVD	EDR Hist Auto	TP
AO223 / 8	FASHION FLOOR INC	5304 LAMAR BLVD N	EDR Hist Cleaner	TP
AP224 / 8	VACANT BLDG. (FORMER	5242 NORTH LAMAR BLV	TX ASBESTOS	TP
225 / 8	ROY R. WARNER	5201 N LAMAR BLVD	TX HIST UST	TP
AQ226 / 8	CECILS (SINCLAIR)	5100 N LAMAR BLVD	TX HIST UST	TP
AQ227 / 8	MAXIM ENGINEERS INC	106011 N LAMAR BLVD	FINDS, ECHO	TP
AR228 / 8	STATE BUILDING	4900 NORTH LAMAR STR	TX ASBESTOS	TP

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AS229 / 8	MESA CLEANERS	4700 W GUADALUPE ST	FINDS	TP
AS230 / 8	MESA CLEANERS	4700 W GUADALUPE ST	TX DRYCLEANERS	TP
AS231 / 8	MESA CLEANERS	4700 W GUADALUPE ST	TX CENTRAL REGISTRY	TP
232 / 8	PROVISION DINING HOU	4600 W GUADALUPE STR	TX ASBESTOS	TP
233 / 8	RAMPART CONSTRUCTION	4510 W GUADALUPE ST	TX CENTRAL REGISTRY	TP
AT234 / 8	DODD-HURT TEXACO	4300 GUADALUPE	EDR Hist Auto	TP
235 / 8	AUSTIN STATE HOSPITA	4101GUADALUPE STREET	TX TIER 2	TP
AT236 / 8	BARTLETTS SERVICE ST	4231 GUADALUPE	EDR Hist Auto	TP
AT237 / 8	PERFORMANCE SHOP NOR	4225 GUADALUPE ST	EDR Hist Auto	TP
AT238 / 8	CLEAN & LEAN LAUNDRY	4225 GUADALUPE ST	EDR Hist Cleaner	TP
AU239 / 8	HYDE PARK GPVAGE	4215 GUADALUPE ST	EDR Hist Auto	TP
AU240 / 8	PERFECTION TATTOO	4205 GUADALUPE ST	TX ASBESTOS	TP
AU241 / 8	JAMES HERSHEL R	4203 GUADALUPE ST	EDR Hist Auto	TP
AV242 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	FINDS, ECHO	TP
AV243 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	FINDS	TP
AV244 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE	TX LPST, TX TIER 2	TP
AV245 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	RCRA-VSQG, TX AST, TX SPILLS, TX ASBESTO...	TP
AV246 / 8		4110 GUADALUPE	ERNS	TP
AV247 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	TX RGA LF	TP
AV248 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE STREE	TX ASBESTOS, TX TIER 2	TP
AV249 / 8	AUSTIN STATE HOSPITA	4110 GUADALUPE ST	TX UST, TX HIST UST	TP
AV250 / 8	GABLES RESIDENTIAL T	4110 GUADALUPE ST	TX SWF/LF	TP
AU251 / 8	NUNNELEE H W	4201 GUADALUPE ST	EDR Hist Auto	TP
AU252 / 8	GUADALUPE HUBSITE	4201 GUADALUPE ST	FINDS	TP
AU253 / 8	TX-13 TIME WARNER CA	4201 GUADALUPE ST	TX TIER 2	TP
AU254 / 8	TX-13 - TIME WARNER	4201 GUADALUPE ST.	TX TIER 2	TP
AW255 / 8	AUSTIN SPORTCYCLES M	4117 GUADALUPE ST	EDR Hist Auto	TP
AW256 / 8	STATE CLEANERS	4115 GUADALUPE	EDR Hist Cleaner	TP
AW257 / 8	PARAMOUNT CLEANERS	4109 GUADALUPE ST	EDR Hist Cleaner	TP
AW258 / 8	MILES EDGAR P BARB	4103 GUADALUPE ST	EDR Hist Cleaner	TP
AW259 / 8	AUSTIN MATTRESS	4101 GUADALUPE	EDR Hist Cleaner	TP
AX260 / 8	WALLIS CLEANERS	4023 GUADALUPE ST	EDR Hist Cleaner	TP
AX261 / 8	HYDE PARK SHOE SHOP	4011 GUADALUPE ST	EDR Hist Cleaner	TP
262 / 8	MIDAS MUFFLER SHOP	4001 GUADALUPE ST	EDR Hist Auto	TP
AY263 / 8	SIGMOR CORPOR	3915 GUADALUPE ST	EDR Hist Auto	TP
AY264 / 8	BAKER LEONARD CLNR	3911 GUADALUPE ST	EDR Hist Cleaner	TP
AY265 / 8	DIAMOND SHAMROCK 80	3909 GUADALUPE ST	FINDS	TP
AY266 / 8	CIRCLE K STORE 27400	3909 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
AY267 / 8	BALCAR HUMBLE SERV	3909 GUADALUPE	EDR Hist Auto	TP

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
AY268 / 8	DIAMOND SHAMROCK 80	3909 GUADALUPE ST	TX RDR	TP
AY269 / 8	CORNER STORE 0080	3909 GUADALUPE ST	TX CENTRAL REGISTRY	TP
AY270 / 8	NUNNELEE HARRY R	3907 GUADALUPE ST	EDR Hist Auto	TP
AY271 / 8	AUSTIN MATTRESS & CA	3907 GUADALUPE ST	EDR Hist Cleaner	TP
272 / 8	FORMER NATURAL GROCE	3901 GUADALUPE STREE	TX ASBESTOS	TP
273 / 8	UNIVERSITY CAR WASH	3825 GUADALUPE ST	EDR Hist Auto	TP
AZ274 / 8	C & H REPAIR SERVICE	3907 AVENUE C	EDR Hist Auto	TP
BA275 / 8	AVENEL AT HYDE PARK	3815 GUADALUPE ST. #	TX ASBESTOS	TP
AZ276 / 8	C&H REPR SERV	3907 AVENUE C	EDR Hist Auto	TP
BA277 / 8	HYDE PARK GULF	3801 GUADALUPE ST	EDR Hist Auto	TP
BB278 / 8	JAMES E P FILL STA	3710 GUADALUPE ST	EDR Hist Auto	TP
BB279 / 8	CIRCLE K CORPORATION	3713 GUADALUPE ST	EDR Hist Auto	TP
BB280 / 8	CIRCLE K 3208	3713 GUADALUPE ST	FINDS	TP
BB281 / 8	GOOD LUCK FOOD MART	3713 GUADALUPE ST	TX ASBESTOS	TP
BB282 / 8	CIRCLE K 3208	3713 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BB283 / 8	CIRCLE K 3208	3713 GUADALUPE ST	TX UST, TX HIST UST	TP
BB284 / 8	MAC'S PIZZA	3701 GUADALUPE	TX ASBESTOS	TP
BB285 / 8	VACANT LEASE SPACE	3701 GUADALUPE	TX ASBESTOS	TP
BB286 / 8	WILDSIDE SMOKE SHOP	3701 GUADALUPE ST	TX ASBESTOS	TP
287 / 8	AUSTIN DIAGNOSTIC CL	801 34TH ST W	EDR Hist Cleaner	TP
BC288 / 8	INTEGRATED BUILDERS	711 N 32ND ST	FINDS	TP
BC289 / 8	BUCKINGHAM INVESTMEN	711 W 32ND ST	TX CENTRAL REGISTRY	TP
BD290 / 8	KWIK WASH COIN LAUND	3105 GUADALUPE ST	EDR Hist Cleaner	TP
BE291 / 8	CAPITAL CITY PARTNER	3004- 3010 GUADALUPE	TX GCC, TX IOP	TP
BE292 / 8	TEXACO STATION	3016 GUADALUPE ST	RCRA-VSQG, FINDS, ECHO	TP
BE293 / 8	SAGE-OCONNER ASSOCIA	3016 GUADALUPE ST	FINDS	TP
BE294 / 8	ASHFORDS GARAGE	3016 GUADALUPE ST	EDR Hist Auto	TP
BE295 / 8	UNIVERSITY TEXACO	3016 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	TP
BE296 / 8	UNIVERSITY TEXACO	3016 GUADALUPE	TX RDR	TP
BE297 / 8	UNIVERSITY TEXACO	3016 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BE298 / 8	OCONNELL & WORLEY	3012 GUADALUPE ST	EDR Hist Cleaner	TP
BE299 / 8	NORTH AUSTIN GARAGE	3008 GUADALUPE ST	EDR Hist Auto	TP
BE300 / 8	RETAIL CENTER 3004-3	3004-3010 GUADALUPE	FINDS	TP
BE301 / 8	RETAIL CENTER 3004-3	3004-3010 GUADALUPE	TX CENTRAL REGISTRY	TP
BF302 / 8	MARY E KOSH	3009 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BF303 / 8	MARY E KOSH	3009 GUADALUPE ST	TX UST	TP
BF304 / 8	HOBBY TRACT	3000 GUADALUPE ST	FINDS	TP
BF305 / 8	MC GIRK J ARTH AUTO	3000 GUADALUPE	EDR Hist Auto	TP
BF306 / 8	HOBBY TRACT	3000 GUADALUPE ST	TX IOP, TX CENTRAL REGISTRY	TP

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BF307 / 8	VACANT LOT	3005 GUADALUPE ST	TX HIST UST	TP		
BF308 / 8	JESSE J. SMITH	602 W 30TH ST	TX HIST UST	TP		
BG309 / 8	DICKEN 6 BROS CLNRS	2930 GUADALUPE	EDR Hist Cleaner	TP		
BG310 / 8	FOUNTAIN TERRACE UNI	601 W. 30TH STREET	TX ASBESTOS	TP		
BG311 / 8	DICKENS CLEANERS & S	2918 GUADALUPE ST	EDR Hist Cleaner	TP		
BH312 / 8	RICKS CLEANERS INC	2908 GUADALUPE ST	EDR Hist Cleaner	TP		
BH313 / 8	COMMUNITY CLNRS	2904 GUADALUPE ST	EDR Hist Cleaner	TP		
314 / 8	FIRST ENGLISH LUTHER	3001 WHITIS AVENUE	TX ASBESTOS	TP		
BH315 / 8	MALLETT JACK SERVICE	2901 GUADALUPE	EDR Hist Auto	TP		
BI316 / 8	PARD-ANNEX BUILDING	2818 SAN GABRIEL	TX ASBESTOS	TP		
BI317 / 8	ANNEX BUILDING	2818 SAN GABRIEL ST.	TX ASBESTOS	TP		
BJ318 / 8	MONTGOMERYS HUMBLE	2825 GUADALUPE ST	EDR Hist Auto	TP		
BJ319 / 8	A C LINEN SUPPLY	2822 GUADALUPE	EDR Hist Cleaner	TP		
BG964 / 8	CVS PHARMACY 6892	2927 GUADALUPE ST	RCRA NonGen / NLR	61	0.012	ESE
BG965 / 8	CVS PHARMACY	2927 GUADALUPE ST	TX ASBESTOS, TX Ind. Haz Waste	61	0.012	ESE
AT966 / 8	GRAYBURG OIL CO STA	4301 GUADALUPE ST	EDR Hist Auto	61	0.012	ESE
AT968 / 8	DODD AUTOMOTIVE	4227 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	61	0.012	NNE
AT969 / 8	DODD & HURT TEXACO S	4227 GUADALUPE ST	EDR Hist Auto	61	0.012	NNE
HT973 / 8	THE NEON PLANT	4401 GUADALUPE ST	TX HIST UST, TX SPILLS	62	0.012	ESE
HT974 / 8	FARRIS LUTHER L FILL	4401 GUADALUPE	EDR Hist Auto	62	0.012	ESE
HT979 / 8	MARX W E MOTOR	4405 GUADALUPE ST	EDR Hist Auto	62	0.012	ESE
BD980 / 8	MY CLEANERS & ALTERA	3100 GUADALUPE ST	TX DRYCLEANERS	62	0.012	WNW
BD981 / 8	MY CLEANERS & ALTERA	3100 GUADALUPE ST	EDR Hist Cleaner	62	0.012	WNW
BD982 / 8	UNIVERSITY TEXACO	3100 GUADALUPE	EDR Hist Auto	62	0.012	WNW
HW998 / 8	GUADALUPE 4413	4413 GUADALUPE STREE	US BROWNFIELDS, FINDS	63	0.012	ESE
HW999 / 8	PEARSON WESLEY H FIL	4413 GUADALUPE	EDR Hist Auto	63	0.012	ESE
HW1000 / 8	A & R CORNER STORE	4413 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	63	0.012	ESE
AP1008 / 8	KRENEK E J AUTO	5200 LAMAR BLVD	EDR Hist Auto	64	0.012	WNW
IB1018 / 8	WATKINS PROPERTY	3400 GUADALUPE ST	TX UST, TX HIST UST	65	0.012	WNW
IB1019 / 8	POTTERS SERVICE STA	3400 GUADALUPE	EDR Hist Auto	65	0.012	WNW
AN1032 / 8	TUNE SMITHS	5405 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	66	0.013	ESE
AN1033 / 8	WAYNE BARBEE MUFFLER	5405 LAMAR BLVD N	EDR Hist Auto	66	0.013	ESE
1048 / 8	SCOTTVS AUTOMOTIVE S	5922 LAMAR BLVD N	EDR Hist Auto	67	0.013	WNW
IC1053 / 8	35TH AND GUADALUPE S	3508 GUADALUPE ST	EDR Hist Auto	67	0.013	WNW
IC1061 / 8	FLAMINGO AUTOMOTIVE	3512 GUADALUPE ST	EDR Hist Auto	68	0.013	WNW
IC1062 / 8	FLAMINGO AUTOMOTIVE	3512 GUADALUPE ST	TX UST, TX HIST UST	68	0.013	WNW
IC1063 / 8	JOE DAYWOOD	3512 GUADALUPE ST	TX LPST	68	0.013	WNW
BG1065 / 8	OXFORD CLEANERS	2928 GUADALUPE ST	EDR Hist Cleaner	68	0.013	WNW
1078 / 8	THE CAR BAZAR	5540 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	69	0.013	WNW

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
1159 / 8	U S P & F O FOR TX	35TH	TX UST	75	0.014	ESE
AL1163 / 8	KISHAN FOOD STOP 417	5630 N LAMAR BLVD	TX RDR	75	0.014	WNW
AL1164 / 8	7-ELEVEN #36653	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
AL1165 / 8	BRITTS AUTOMOTIVE	5630 N LAMAR	TX RDR	75	0.014	WNW
AL1166 / 8	7 ELEVEN STORE 36653	5630 N LAMAR BLVD	TX LPST, TX UST, TX Financial Assurance	75	0.014	WNW
AL1167 / 8	GRAPETTE BOTTLING CO	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
AL1168 / 8	7-ELEVEN INC STORE N	5630 N LAMAR BLVD	TX RDR	75	0.014	WNW
AL1169 / 8	HEBERT MOBIL STA	5630 LAMAR BLVD N	EDR Hist Auto	75	0.014	WNW
AL1170 / 8	7 ELEVEN STORE 36653	5630 N LAMAR BLVD	TX LPST, TX GCC, TX RDR	75	0.014	WNW
AL1171 / 8	SOCONY MOBIL OIL CO.	5630 N LAMAR BLVD	TX HIST UST	75	0.014	WNW
IJ1182 / 8	TIP TOP CLEANERS	3202 GUADALUPE ST	EDR Hist Cleaner	76	0.014	WNW
IJ1187 / 8	T & T CLEANERS LAUND	3206 GUADALUPE ST	EDR Hist Cleaner	77	0.015	WNW
AQ1191 / 8	MC CULLOUGHS SERV	5000 LAMAR BLVD	EDR Hist Auto	79	0.015	WNW
BD1201 / 8	HARTUNG PHILLIPS 66	3106 GUADALUPE ST	EDR Hist Auto	80	0.015	WNW
BB1202 / 8	SMITH ELMER L FILLIN	3711 GUADALUPE	EDR Hist Auto	81	0.015	ESE
IQ1231 / 8	TUNEUP MASTERS STORE	5624 N LAMAR BLVD	TX UST, TX HIST UST	83	0.016	WNW
IQ1232 / 8	TUNEUP MASTERS INC	5624 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	83	0.016	WNW
IQ1233 / 8	TUNEUP MASTERS 1004	5624 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste	83	0.016	WNW
IQ1234 / 8	GRIFFIN JACK SERV	5624 LAMAR BLVD N	EDR Hist Auto	83	0.016	WNW
IR1236 / 8	ROBBINS RUSSELL H AU	4311 AVENUE A	EDR Hist Auto	83	0.016	SW
IB1239 / 8	DALES UNIVERSITY AUT	3402 GUADALUPE ST	EDR Hist Auto	83	0.016	WNW
IB1240 / 8	PREVIOUS PAWN SHOP	3402 GUADALUPE STREE	TX HIST UST, TX ASBESTOS	83	0.016	WNW
IB1241 / 8	CASH AMERICAN PAWN S	3402 GUADALUPE	TX LPST	83	0.016	WNW
IC1243 / 8	SPIRES TIRE CO INC	3510 GUADALUPE	EDR Hist Auto	83	0.016	WNW
IC1244 / 8	SULLIVAN CARDINAL DC	3510 GUADALUPE ST	EDR Hist Cleaner	83	0.016	WNW
BB1248 / 8	CEARLEY E A FILL STA	3700 GUADALUPE ST	EDR Hist Auto	84	0.016	WNW
BA1249 / 8	JIFFY LUBE AUTO REPR	3809 GUADALUPE ST	EDR Hist Auto	85	0.016	ESE
BA1250 / 8	JIFFY LUBE STORE #82	3809 GUADALUPE	TX RDR	85	0.016	ESE
BA1251 / 8	JIFFY LUBE	3809 GUADALUPE	TX RDR	85	0.016	ESE
BA1252 / 8	HEARTLAND AUTOMOTIVE	3809 GUADALUPE	RCRA-SQG, FINDS, ECHO	85	0.016	ESE
BA1253 / 8	JIFFY LUBE	3809 GUADALUPE ST	TX UST, TX HIST UST	85	0.016	ESE
AR1255 / 8	CECILS AUTO TRIM	4926 N LAMAR BLVD	TX UST, TX HIST UST	85	0.016	WNW
AR1256 / 8	AUSTIN RADIATOR WORK	4926 LAMAR BLVD N	EDR Hist Auto	85	0.016	WNW
IT1280 / 8	PETRIFIED SERV STA	4505 GUADALUPE	EDR Hist Auto	90	0.017	ESE
IJ1283 / 8	GAS A TERIA INC	3200 GUADALUPE	EDR Hist Auto	91	0.017	WNW
AR1295 / 8	PEOPLES SINCLAIR	4926 LAMAR BLVD N	EDR Hist Auto	94	0.018	WNW
AR1296 / 8	M & M SINCLAIR	4926 LAMAR BLVD	EDR Hist Auto	94	0.018	WNW
BF1325 / 8	FOUR SON'S QUALITY C	3001 GUADALUPE	US AIRS, FINDS, ECHO, TX DRYCLEANERS	100	0.019	ESE
BF1326 / 8	CHING WONG CLEANERS	3001 GUADALUPE ST	EDR Hist Cleaner	100	0.019	ESE

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BF1327 / 8	MCWILLIAMS & FIEGEL	3001 GUADALUPE	EDR Hist Auto	100	0.019	ESE
AO1341 / 8	FLOYDS AUTO SALES &	5253 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	102	0.019	ESE
AO1342 / 8	GARDNERS GULL SERVIC	5253 LAMAR BLVD N	EDR Hist Auto	102	0.019	ESE
1351 / 8	BURNETTE L B O	118 31ST W	EDR Hist Auto	103	0.020	ESE
BJ1353 / 8	MIDAS MUFFLER SHOP	2828 GUADALUPE ST	EDR Hist Auto	104	0.020	WSW
AO1362 / 8	AUSTINS TINT CONNECT	5319 N LAMAR BLVD	TX UST	106	0.020	ESE
AO1363 / 8	AUSTIN TINT CONNECTI	5319 N LAMAR BLVD	TX HIST UST	106	0.020	ESE
AO1364 / 8	HUMBLE PRODUCTS SERV	5319 LAMAR BLVD N	EDR Hist Auto	106	0.020	ESE
AO1365 / 8	HUMBLE OIL & REFININ	5319 N LAMAR BLVD	TX HIST UST	106	0.020	ESE
AO1366 / 8	PHILLIPS PETROLEUM C	5301 N LAMAR BLVD	RCRA NonGen / NLR, FINDS, ECHO	106	0.020	ESE
AO1367 / 8	PHILLIPS PETROLEUM S	5301 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste	106	0.020	ESE
AO1368 / 8	PHILLIPS 66 #27288	5301 NORTH LAMAR	TX RDR	106	0.020	ESE
AO1369 / 8	PRET MANGER	5301 N LAMAR BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	106	0.020	ESE
AO1370 / 8	AMERICAN MUFFLER SHO	5301 LAMAR BLVD N	EDR Hist Auto	106	0.020	ESE
AQ1380 / 8	JOHN H WINTERS	701 W 51ST ST	TX UST, TX HIST UST	108	0.020	ESE
AQ1417 / 8	7-ELEVEN 24008	5101 N LAMAR BLVD	TX LPST, TX UST, TX ASBESTOS, TX Financi...	114	0.022	ESE
AQ1418 / 8	7-ELEVEN #24008	5101 N LAMAR	TX RDR	114	0.022	ESE
AQ1419 / 8	SEVEN ELEVEN #24008	5101 N LAMAR BLVD	TX HIST UST	114	0.022	ESE
AQ1420 / 8	W. L. BROWN	5101 N LAMAR BLVD	TX HIST UST	114	0.022	ESE
AQ1421 / 8	7 ELEVEN 24008	5101 N LAMAR	TX RDR	114	0.022	ESE
AL1455 / 8	CAPITOL LAUNDRY & DR	806 KOENIG LN W	EDR Hist Cleaner	120	0.023	WNW
JK1474 / 8	AUSTIN QUALITY CAR W	3120 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	123	0.023	WNW
JK1475 / 8	TEXACO STATION	3120 GUADALUPE ST	RCRA-VSQG, FINDS, ECHO	123	0.023	WNW
JK1476 / 8	CAR CARE CENTER	3120 GUADALUPE ST	EDR Hist Auto	123	0.023	WNW
AL1490 / 8	7-ELEVEN 12683	808 W KOENIG LN	TX LPST, TX UST, TX HIST UST, TX Financi...	124	0.023	WNW
AT1512 / 8	MANFRED HOLOK	514 W 43RD ST	TX HIST UST	129	0.024	SW
AM1518 / 8	LEGELTS FOREIGN SPOR	5412 LAMAR BLVD N	EDR Hist Auto	131	0.025	WNW
AM1519 / 8	N LAMAR U HAUL CTR	5412 N LAMAR BLVD	TX UST, TX HIST UST	131	0.025	WNW
IJ1526 / 8	BUSKES GARAGE	3208 GUADALUPE	EDR Hist Auto	132	0.025	WNW
BB1563 / 8	SIGMOR SHAMROCK SERV	3706 GUADALUPE ST	EDR Hist Auto	135	0.026	WNW
BB1564 / 8	DIAMOND SHAMROCK 963	3706 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX Financi...	135	0.026	WNW
IR1586 / 8	HYDE PARK GARAGE AUT	513 43RD W	EDR Hist Auto	138	0.026	SW
IR1587 / 8	HYDE PARK GARAGE AUT	513 43RD ST W	EDR Hist Auto	138	0.026	SW
IR1588 / 8	HYDE PARK GARAGE	513 43RD ST W	EDR Hist Auto	138	0.026	SW
IR1606 / 8	COPELAND GARAGE	514 43RD ST W	EDR Hist Auto	140	0.027	SW
IR1607 / 8	MURRAYS GAR AUTO	514 43RD W	EDR Hist Auto	140	0.027	SW
IR1608 / 8	HYDE PARK GARAGE	514 43RD ST W	EDR Hist Auto	140	0.027	SW
BH1737 / 8	TWENTY NINTH STREET	604 W 29TH ST	EDR Hist Cleaner	167	0.032	WNW
BG1807 / 8	DRY CIN VILLAGE	604 29TH W	EDR Hist Cleaner	184	0.035	WNW

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BG1809 / 8	MASTER DICKENS CLEAN	604 29TH ST W	EDR Hist Cleaner	185	0.035	WNW
1833 / 8	FRANKS FIX IT	4214 AVENUE A	EDR Hist Auto	194	0.037	SW
IC1834 / 8	FRANK HUNT PROPERTY	605 W 37TH ST	TX RDR	195	0.037	WNW
IC1835 / 8	FURNITURE REJUVENATI	605 W 37TH ST	TX HIST UST	195	0.037	WNW
IC1836 / 8	FURNITURE REJUVENATO	605 W 37TH ST	TX LPST, TX TANKS, TX GCC	195	0.037	WNW
IC1837 / 8	ERNEST M. DURBIN	605 W 37TH ST	TX HIST UST	195	0.037	WNW
AM1843 / 8	GREAT HALL GAMES	5501 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	197	0.037	ESE
IT1848 / 8	BALCARS HUMBLE	4501 GUADALUPE ST	EDR Hist Auto	199	0.038	ESE
BE1863 / 8	31ST ST GARAGE	609 W 31ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	204	0.039	WNW
BE1864 / 8	CARLSONS GARAGE	609 31ST ST W	EDR Hist Auto	204	0.039	WNW
IB1889 / 8	DALES AUTO PARTS	602 W 34TH ST	TX Ind. Haz Waste	211	0.040	WNW
1915 / 8	CARLSONS GARAGE AUTO	609 31ST W	EDR Hist Auto	224	0.042	WNW
BH1919 / 8	CONVENIENCE COIN LAU	606 29TH ST W	EDR Hist Cleaner	227	0.043	WNW
BH1920 / 8	CONVENIENCE COIN LAU	606 W 29TH ST	EDR Hist Cleaner	227	0.043	WNW
BH1921 / 8	GUADALUPE LAUNDROMAT	606 29TH W	EDR Hist Cleaner	228	0.043	WNW
LM1934 / 8	HOMESTEAD 451 CENTRA	817 N LOOP	TX RDR	232	0.044	WNW
LO1943 / 8	TRANS TECH AUTOMOTIV	805 CAPITOL ST	EDR Hist Auto	235	0.045	WNW
LM1965 / 8	AT&T SOC XU3382	819 N LOOP W	TX RDR	241	0.046	WNW
LO1976 / 8	TEXAS GLASS	808 CAPITOL CT	EDR Hist Auto	244	0.046	WNW
LU1983 / 8	TUXEDO JUNCTION CLEA	611 W 29TH ST	EDR Hist Cleaner	246	0.047	WNW
LV1985 / 8	SPEEDWAY SER STA	3706 SPEEDWAY	EDR Hist Auto	246	0.047	ESE
LV1986 / 8	FORMER STATION	3706 SPEEDWAY	TX RDR	246	0.047	ESE
LO2021 / 8	FRENCH REVOLUTION AU	807 CAPITOL ST	EDR Hist Auto	260	0.049	WNW
MD2024 / 8	KINSEYS AUTOMOTIVE	819 HOUSTON ST	EDR Hist Auto	262	0.050	WNW
MD2025 / 8	AUSTIN PAN AM CHEMIC	819 HOUSTON ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	262	0.050	WNW
LV2036 / 8	SPEEDWAY SERVICE STA	3714 SPEEDWAY	EDR Hist Auto	264	0.050	ESE
2054 / 8	ROOHI JOOHI INC	7700 E MRTN LTHR KIN	EDR Hist Auto	269	0.051	West
2061 / 8	GRAY CLEANERS	3912 SPEEDWAY	EDR Hist Cleaner	273	0.052	ESE
2072 / 8	LAY WALLACE DCLO CLN	3808 SPEEDWAY	EDR Hist Cleaner	274	0.052	ESE
MQ2108 / 8	TOSCO MARKETING COMP	3208 EAST AVE	EDR Hist Auto	280	0.053	ENE
MQ2109 / 8	7-ELEVEN #36560	3208 E SH 71	TX HIST UST	280	0.053	ENE
2167 / 8	EURO SPORT CYCLES	616 W 34TH ST	TX Ind. Haz Waste	286	0.054	WNW
2170 / 8	YOUNGS REPAIR SHOP	607 37TH W	EDR Hist Auto	287	0.054	WNW
LO2181 / 8	AUSTIN RADIATOR WORK	810 CAPITOL CT	EDR Hist Auto	290	0.055	WNW
LM2190 / 8	NEELLEY VENDING	813 W NORTH LOOP BLV	TX LPST, TX HIST UST	293	0.055	WNW
2237 / 8	BOWMAN RESIDENCE	212 W 33RD ST	TX TANKS, TX HIST UST, TX RDR, TX CENTRA...	303	0.057	WNW
LV2246 / 8	CONVENIENCE COIN LAU	101 38TH ST E	EDR Hist Cleaner	307	0.058	ESE
LV2247 / 8	CONVENIENCE COIN LAU	101 38TH ST E	EDR Hist Cleaner	307	0.058	ESE
MQ2253 / 8	CINDERELLA CLNS	3500 EAST AVE	EDR Hist Cleaner	307	0.058	ENE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
MQ2254 / 8	NOACK BENJ FILL STA	3500 EAST AVE	EDR Hist Auto	307	0.058	ENE
LO2259 / 8	Z TECH AUTO REPR	809 CAPITOL ST	EDR Hist Auto	310	0.059	WNW
LV2264 / 8	M F ROUTE LAUNDRIES	103 38TH ST E	EDR Hist Cleaner	314	0.059	ESE
LV2265 / 8	CONVENIENCE COIN LAU	103 38TH ST E	EDR Hist Cleaner	314	0.059	ESE
2268 / 8	MEACHAM W W R	3104 KING ST	EDR Hist Cleaner	316	0.060	ESE
2300 / 8	K AND S INTERCONNECT	3709-B PROMONTORY PO	RCRA-VSQG	330	0.062	WNW
NM2305 / 8	MAGNOLIA PET CO STA	100 31ST E	EDR Hist Auto	332	0.063	ESE
NQ2321 / 8	WARREN CLNRS	3209 SPEEDWAY	EDR Hist Cleaner	338	0.064	ESE
NQ2323 / 8	WARREN J A CLC CLNR	3207 SPEEDWAY	EDR Hist Cleaner	338	0.064	ESE
LU2332 / 8	7-ELEVEN STORE 36656	620 W 29TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	342	0.065	WNW
LU2333 / 8	DIAMOND SHAMROCK 206	620 W 29TH ST	TX RDR	342	0.065	WNW
LU2334 / 8	TP 2533	620 W 29TH ST	TX RDR	342	0.065	WNW
LU2335 / 8	FROMER 7 ELEVEN 3665	620 W 29TH ST	TX RDR	342	0.065	WNW
2354 / 8	BRUNDRETT ARNOLD 0 A	404 32ND W	EDR Hist Auto	347	0.066	ESE
MQ2365 / 8	MC GINNIS & GRIMES	3810 E AVE	EDR Hist Cleaner	350	0.066	ENE
MQ2366 / 8	DYNA TUNE	3810 EAST AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	350	0.066	ENE
MQ2382 / 8	EXXON STATION 67383	3807 EAST AVE	TX LPST	355	0.067	ENE
MQ2383 / 8	EXXON MOBIL CORPORAT	3807 EAST AVE	RCRA NonGen / NLR	355	0.067	ENE
MQ2384 / 8	SS 6 7383	3807 EAST AVE	TX UST	355	0.067	ENE
MQ2385 / 8	EXXON MOBIL NO 67383	3807 EAST AVE	TX Ind. Haz Waste	355	0.067	ENE
MQ2386 / 8	BALKOS HUMBLE	3807 EAST AVE	EDR Hist Auto	355	0.067	ENE
2413 / 8	MORGAN PRINTING	900 OLD KOENIG LANE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	360	0.068	WNW
LV2415 / 8	CONVENIENCE COIN LAU	101 E 38TH ST	EDR Hist Cleaner	363	0.069	ESE
OE2423 / 8	CAPITOL LAUNDRY & DR	806 KOENIG LN W	EDR Hist Cleaner	365	0.069	WNW
MQ2425 / 8	DELWOOD CLNS	3925 EAST AVE	EDR Hist Cleaner	367	0.070	ENE
MQ2447 / 8	TAYLORS DELWOOO CONO	4021 EAST AVE	EDR Hist Auto	377	0.071	ENE
MQ2452 / 8	SWEET ONE HOUR DRY C	4100 EAST AVE	EDR Hist Cleaner	380	0.072	ENE
2453 / 8	JAMES W L GARAGE	703 38TH W	EDR Hist Auto	381	0.072	ESE
NM2459 / 8	MASTER VALET CLEANER	3101 SPEEDWAY	TX DRYCLEANERS	386	0.073	ESE
NM2460 / 8	MASTER VALET CLEANER	3101 SPEEDWAY ST	EDR Hist Cleaner	386	0.073	ESE
NM2461 / 8	MITTAG WILLIAM O	3101 SPEEDWAY	EDR Hist Cleaner	386	0.073	ESE
OO2484 / 8	WR ROBBINS SECONDARY	3908 AVENUE B	TX Ind. Haz Waste	396	0.075	WNW
OO2485 / 8	AUSTIN ISD	3908 AVENUE B	RCRA NonGen / NLR, FINDS, ECHO	396	0.075	WNW
MQ2487 / 8	EVANS DELWOOD CONOCO	4201 EAST AVE	EDR Hist Auto	396	0.075	ENE
2497 / 8	EXXON MOBIL CORPORAT	619 W NORTH LOOP 35	EDR Hist Auto	399	0.076	ESE
NM2506 / 8	AUSTINS HOME LNDRY	104 31ST E	EDR Hist Cleaner	404	0.077	ESE
NM2507 / 8	MALMBERG H G AUTO	104 31ST E	EDR Hist Auto	404	0.077	ESE
2517 / 8	J RS AUTO REPR	406 38 1/2 W	EDR Hist Auto	406	0.077	WNW
OT2526 / 8	SIGMOR SHAMROCK SERV	3515 LAMAR BLVD N	EDR Hist Auto	411	0.078	WNW

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
OT2527 / 8	SNAX BASKET 3 TX0297	3515 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	411	0.078	WNW
OE2546 / 8	KOENIG LANE SERVICE	901 W KOENIG LN	TX RDR	423	0.080	WNW
OE2547 / 8	KOENIG LANE SERVICE	901 W KOENIG LN	TX UST, TX HIST UST, TX Financial Assura...	423	0.080	WNW
OE2548 / 8	AUSTIN WATER WASTEWA	901 W KOENIG LN	TX LPST	423	0.080	WNW
MQ2554 / 8	BURCH FOOD MART	4535 E SH 71	TX HIST UST	427	0.081	ENE
OY2566 / 8	JIFFY LUBE #2925	3401 N LAMAR BLVD	TX LPST, TX TIER 2, TX CENTRAL REGISTRY	434	0.082	WNW
OY2567 / 8	QUICK LUBE	3401 N LAMAR BLVD	TX HIST UST	434	0.082	WNW
OY2568 / 8	QUICK LUBE AUTO LUBR	3401 LAMAR BLVD N	EDR Hist Auto	434	0.082	WNW
OY2569 / 8	MAGNOLIA PETROLEUM	3401 N LAMAR BLVD	TX HIST UST	434	0.082	WNW
OZ2572 / 8	TRAM STOP	3201 N LAMAR BLVD	TX UST, TX HIST UST	435	0.082	WNW
OZ2573 / 8	TRAM STOP	3201 N LAMAR BLVD	TX ASBESTOS, TX Financial Assurance, TX ...	435	0.082	WNW
OZ2574 / 8	THOMSON PREMIER SERV	3201 LAMAR BLVD N	EDR Hist Auto	435	0.082	WNW
OZ2575 / 8	CIRCLE K 3245	3201 N LAMAR BLVD	TX LPST, TX HIST UST	435	0.082	WNW
OZ2576 / 8	CIRCLE K 3245	3201 N LAMAR BLVD	TX UST	435	0.082	WNW
OY2577 / 8	REIDS LAUNDRY & DRY	3317 N LAMAR BLVD	RCRA NonGen / NLR	436	0.083	WNW
OY2578 / 8	REIDS CLEANERS 5	3317 N LAMAR BLVD	TX HIST UST, TX DRYCLEANERS, TX Ind. Haz...	436	0.083	WNW
OY2579 / 8	MARKLAND EXXON SERVI	3317 LAMAR BLVD N	EDR Hist Auto	436	0.083	WNW
OY2580 / 8	DON LLOYDS TEXACO	3317 N LAMAR BLVD	TX UST, TX HIST UST	436	0.083	WNW
OY2581 / 8	REIDS CLEANERS & LAU	3317 N LAMAR BLVD	EDR Hist Cleaner	436	0.083	WNW
OY2582 / 8	JOASH ENTERPRISES IN	3419 N LAMAR BLVD	EDR Hist Cleaner	436	0.083	WNW
LV2600 / 8	M F ROUTE LAUNDRIES	103 E 38TH ST	EDR Hist Cleaner	443	0.084	ESE
2608 / 8	CENTRAL PROPERTIES I	6008 N LAMAR BLVD	TX HIST UST	449	0.085	WNW
OY2609 / 8	RICKS CLEANERS	3411 N LAMAR BLVD	TX DRYCLEANERS	450	0.085	WNW
PH2635 / 8	HEART HOSPITAL OF AU	3801 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	455	0.086	WNW
PH2636 / 8	HEART HOSPITAL OF AU	3801 N LAMAR BLVD	RCRA-SQG	455	0.086	WNW
MQ2653 / 8	HERWICK DON PHILLIPS	4834 EAST AVE	EDR Hist Auto	465	0.088	ENE
OT2669 / 8	LABORATORY CORPORATI	3701 N LAMAR STE 200	RCRA NonGen / NLR, FINDS, ECHO	471	0.089	WNW
OT2670 / 8	LABCORP AUSTIN	3701 N LAMAR BLVD ST	TX Ind. Haz Waste	471	0.089	WNW
2688 / 8	ONE HOUR MARTINIZING	704 W 29TH ST	EDR Hist Cleaner	477	0.090	ESE
2691 / 8	GRAY P B DCLO CLNR	4413 AVENUE B	EDR Hist Cleaner	478	0.091	NE
PH2694 / 8	KASPER CHAS E CLNS	3810 LAMAR BLVD N	EDR Hist Cleaner	479	0.091	WNW
MQ2696 / 8	JAMES BOYCE	5021 E CSSAR CHAVEZ	TX HIST UST	479	0.091	ENE
PH2721 / 8	DOLLARS & SENSE DRY	3816 N LAMAR BLVD	EDR Hist Cleaner	494	0.094	WNW
PR2724 / 8	CHARLES T SIKES	1000 W 39TH ST	TX TANKS, TX ASBESTOS, TX CENTRAL REGIST...	496	0.094	WNW
PR2725 / 8	FORMER FUELING FACIL	1000 W 39TH ST	TX LPST	496	0.094	WNW
PR2726 / 8	FORMER FUELING FACIL	1000 WEST 39TH ST	TX RDR	496	0.094	WNW
OT2738 / 8	LAMAR VILLAGE SHELL	3724 LAMAR BLVD N	EDR Hist Auto	507	0.096	WNW
OT2739 / 8	SUB WAY	3724 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST	507	0.096	WNW
OZ2744 / 8	THOMSON PREMIER SERV	3201 LAMAR BLVD N	EDR Hist Auto	515	0.098	WNW

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2754 / 8	FORMADORY TEXACO	5326 E SH 71	TX HIST UST	526	0.100	ENE
PX2756 / 8	FRANKES SLS &	4126 LAMAR BLVD N	EDR Hist Auto	528	0.100	NW
PR2765 / 8	STA & GARAGE	3900 LAMAR BLVD N	EDR Hist Auto	542	0.103	WNW
2766 / 8	CHIEF CLEANERS	1001 W 34TH ST	EDR Hist Cleaner	546	0.103	WNW
QA2769 / 8	AT&T - HOMESTEAD 451	817 W NORTH LOOP BLV	TX HIST UST	547	0.104	WNW
QA2770 / 8	HOMESTEAD 451 CO XP3	817 W NORTH LOOP BLV	TX UST, TX Financial Assurance, TX TIER ...	547	0.104	WNW
QA2771 / 8	SOUTHWESTERN BELL TE	817 W NORTH LOOP BLV	TX HIST UST	547	0.104	WNW
QA2772 / 8	SBC HOMESTEAD 451 CE	817 W NO LOOP BLVD	TX Ind. Haz Waste	547	0.104	WNW
QA2773 / 8	SOUTHWESTERN BELL TE	817 W NORTH LOOP BLV	TX LPST	547	0.104	WNW
QA2774 / 8	SBC	817 N LOOP BLVD	RCRA NonGen / NLR	547	0.104	WNW
QA2775 / 8	NORTH LOOP SOC	819 W NO LOOP BLVD	TX LPST	548	0.104	WNW
QA2776 / 8	AUSTIN HOMESTEAD 451	819 W NO LOOP BLVD	TX LPST	548	0.104	WNW
QA2777 / 8	NORTH LOOP SOC PORT	819 W NO LOOP BLVD	TX UST, TX HIST UST, TX Financial Assura...	548	0.104	WNW
OT2787 / 8	IMPORT MOTORS	3520 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste, TX CENTR...	556	0.105	WNW
OY2794 / 8	MAGNOLIA PETROLEUM C	1002 W 34TH ST	TX HIST UST	557	0.105	WNW
QE2795 / 8	FLOWER STATION	3100 N LAMAR BLVD	TX UST, TX DRYCLEANERS	559	0.106	WNW
QE2796 / 8	R E LEIGH	3100 N LAMAR BLVD	TX HIST UST	559	0.106	WNW
QE2797 / 8	THE FLOWER STATION	3100 N LAMAR BLVD	TX HIST UST	559	0.106	WNW
QE2798 / 8	CAR CARE BV ISSAC	3100 LAMAR BLVD N	EDR Hist Auto	559	0.106	WNW
QJ2808 / 8	UNIVERSITY SCHWINN C	2901 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	570	0.108	WNW
OT2825 / 8	BRAKE CHECK	3700 LAMAR BLVD N	EDR Hist Auto	590	0.112	WNW
PR2832 / 8	CARL M. TEMPLETON	3906 N LAMAR BLVD	TX HIST UST	600	0.114	WNW
PX2835 / 8	A-TEX AUSTIN INC	4106 N LAMAR	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	603	0.114	NW
PX2846 / 8	LONE STAR CYCLE MOTI	4108 LAMAR BLVD N	EDR Hist Auto	618	0.117	NW
PX2847 / 8	REED PHILLIPS OIL CO	4108 N LAMAR BLVD	TX HIST UST	618	0.117	NW
QJ2851 / 8	MCBRIDES GUNS	2913 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	620	0.117	WNW
QW2877 / 8	TEXAS ALLERGY & ASTH	4150 N LAMAR BLVD	TX UST	647	0.123	NW
QW2878 / 8	CONTINENTAL OIL COMP	4150 N LAMAR BLVD	TX HIST UST	647	0.123	NW
QW2879 / 8	TX ALLERGY ASTHMA CE	4150 N LAMAR BLVD	TX HIST UST	647	0.123	NW
2887 / 8	EXXON 6 2790	619 N IH 35	TX RDR	658	0.125	ESE
2888 / 8	SAM PAYNE	1010 W 38TH ST	TX HIST UST	659	0.125	WNW
2896 / 8	LAMAR VILLAGE SHOPPI	3800 N LAMAR BLVD	TX TANKS, TX CENTRAL REGISTRY	686	0.130	WNW
RK2936 / 8	WHITAKER FIELDS	4901 N GUADALUPE	TX UST	855	0.162	ESE
RK2937 / 8	WHITAKER FIELDS	4901 GUADALUPE ST	TX HIST UST	855	0.162	ESE
2961 / 8	MCCALLUM HIGH SCHOOL	5600 SUNSHINE DR	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	899	0.170	WNW
RV2985 / 8	SHELL FOOD MART	4001 MEDICAL PKWY	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	947	0.179	WNW
RW2987 / 8	TERMINIX COMPANY	4326 N LAMAR BLVD	TX HIST UST	949	0.180	NNW
RW2996 / 8	CENTRAL TEX. REG. BL	4300 N LAMAR BLVD	TX HIST UST	1000	0.189	NNW
RV3019 / 8	KWIK KOPY	4011 MEDICAL PKWY	TX Ind. Haz Waste	1038	0.197	WNW

MAPPED SITES SUMMARY - FOCUS MAP 8

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
3049 / 8	AUSTIN NEURO DIAGNOS	1111 W 34TH STREET	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	1094	0.207	WNW
SM3050 / 8	ASCENSION SETON MEDI	1201 W 38TH STREET	RCRA-SQG, TX SWF/LF, TX LPST, TX UST, FI...	1098	0.208	WNW
SM3051 / 8	W. F. SMITH	1201 W 38TH ST	TX HIST UST	1098	0.208	WNW
SM3052 / 8	SETON MEDICAL CENTER	1201 W 38TH ST	TX HIST UST	1098	0.208	WNW
3084 / 8	UNITED SHEET METAL W	1100 W KOENIG LN	TX HIST UST	1161	0.220	WNW
TJ3158 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	RCRA-SQG, PADS	1314	0.249	WNW
TJ3159 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	TX AST	1314	0.249	WNW
TJ3160 / 8	TEXAS DEPARTMENT OF	1100 W 49TH ST	TX SPILLS, TX ASBESTOS, TX Ind. Haz Wast...	1314	0.249	WNW
TL3169 / 8	HLD FOOD MART	1112 W KOENIG LN	TX LPST	1449	0.274	WNW
3172 / 8	WEED-CORLEY FUNERAL	1301 W 34TH ST	TX LPST, TX UST, TX HIST UST	1504	0.285	WNW
TL3189 / 8	FORMER BROADDUS KOEN	1200 W KOENIG LN	TX LPST	1657	0.314	WNW
TL3190 / 8	FORMER KOENIG CHEVRO	1200 KOENIG LN	TX RDR	1657	0.314	WNW
TL3191 / 8	KOENIG LANE 66	1200 W KOENIG LN	TX LPST	1657	0.314	WNW
3193 / 8	ELIZABET NEY MUSEUM	304 E. 44TH STREET	US BROWNFIELDS	1686	0.319	East
3205 / 8	JULIOS CAFE	4220 DUVAL ST	TX HIST UST, TX RDR	1845	0.349	East
TQ3209 / 8	FIRST TEXAS HONDA	1301 W KOENIG LN	TX LPST, TX CENTRAL REGISTRY	1920	0.364	WNW
TQ3215 / 8	FORMER FIRST TEXAS H	1303 W. KOENIG	US BROWNFIELDS	1927	0.365	WNW
3217 / 8	ROOSEVELT GARDENS	5606 ROOSEVELT AVENU	US BROWNFIELDS, FINDS, ECHO	1961	0.371	WNW
3240 / 8	HYDE PARK TEXACO	4500 DUVAL ST	TX LPST, TX UST, TX HIST UST	2276	0.431	East
UD3262 / 8	CUTLER AUTOMOTIVE	4416 BURNET RD	TX RDR, TX CENTRAL REGISTRY	2390	0.453	NNW
UD3264 / 8	TETCO #1169	1309 W. 45TH ST	TX RDR	2398	0.454	NNW
3265 / 8	ABANDONED	1401 W KOENIG LN	TX RDR	2400	0.455	WNW
3283 / 8	FORMER MUFFIN MUFFLE	4818 BURNET RD	TX RDR	2520	0.477	WNW
3286 / 8	STENGER TRACT	1406 N IH 35	TX VCP	2537	0.480	WNW
3289 / 8	LESTER BROWN PHILLIP	4500 BURNET RD	TX LPST, TX UST, TX HIST UST	2555	0.484	NNW

Focus Map - 9 - 7418065.7s


DELL CHILDREN'S MEDICAL CENTER HELIPO
E Highland Mall Blvd
W Huntland Dr
E Highway 290
US-290 W
N Interstate 35
Airport Blvd
Duval St
Cameron Rd
Berkman Dr
Manor Rd
Old Manor Rd
Lazy Brk
Sunny Brook Dr
Singing Brk
Greenbrook Pkwy
Running Brook Dr
Peacedale Ln
Robinsdale Ln
Brookdale Ln
Ravensdale Ln
Cloverdale Ln
Philomena St
Garcia St
Aldrich St
McBee St
Simond Ave
Camacho St
Zack Scott St
Philomena St
Robert Browning St
Mueller Blvd
Lancaster Dr
Norwood Rd
Bentwood Rd
Fairwood Rd
Rowood Rd
Crestwood Rd
Arderwood Rd
Wilshire Blvd
Kirkwood Rd
Ashwood Rd
Brookview Rd
Schieffer Ave
Bradwood Rd
Wright Wood Rd
Harmon Ave
E 41st St
E 40th St
E 39th St
E 38th St
E 37th St
E 51st St
E 52nd St
E 50th St
E 49th St
E 48th St
E 47th St
E 46th St
E 45th St
E 44th St
E 43rd St
E 56th St
E 55th St
E 54th St
E 53rd St
E 53rd 1/2 St
E 52nd St
E 49th 1/2 St
E 45th 1/2 St
W 56th St
W 56th 1/2 St
W 55th St
Franklin Blvd
Nelray Blvd
Rark Blvd
Keasbey St
Clarkson Ave
Red River St
Caswell Ave
Depew Ave
Bennett Ave
Elers Ave
Avenue H
Avenue F
Avenue D
Link Ave
Avenue G
Dillard Cir
E Skyview Rd
Tiradb St
E Koenig Ln
Reinli St
Middle Fiskville Rd
Sheridan Ave
Clayton Ln
Hillcrest Dr
Berkshire Dr
Yorkshire Dr
Braes Ridge Dr
Northridge Dr
Ridgehaven Dr
Larkwood Dr
Cloverdale Dr
Corona Dr
Suffolk Dr
Broadmoor Dr
Westmoor Dr
Nassau Dr
Briarcliff Blvd
Glenvalley Dr
Glenrest Dr
Brookside Dr
Ashberry Dr
Wheless Ln
Patton Ln
Hickman Ave
Linda Ln
Peggy St
Kenilworth Dr
Dorchester Dr
Brunswick Dr
Gaston Place Dr
Thames Dr
N Hampton Rd
Westminster Dr
Maplelaf Dr
Delwood Dr
Blanton Dr
Waterbrook Dr
Trafalgar Dr
Coventry Ln
Mira Loma Ln
Greekwood Rd
Bluebell Ln
Atkinson Rd
Grand Canyon Dr
Meadow Ave
Providence Ave
Bethune Ave
Cameron Ave
Wilks Ave
Biesling Ave
Fairbanks Dr
Radcliff Dr
Reagan Hill Dr
Coronado Hills Dr
Coronado Cir
Barcelona Dr
Sevilla Dr
Glenhill Rd
Athletic Dr
Esther D
Irma Dr
Wilmes Ave
Hammack Dr
Clenson Dr
Chesterfield Ave
Burton St
Chadwick Ave
Nelray Blvd
Franklin

MAPPED SITES SUMMARY - FOCUS MAP 9

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
AJ181 / 9	EARLS LAWN GARDEN EQ	6216 N LAMAR BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP		
AJ182 / 9	EARLS AIR COOLED ENG	6218 LAMAR BLVD N	EDR Hist Auto	TP		
AJ183 / 9	VIOLET CROWN CLNRS	6218 LAMAR BLVD	EDR Hist Cleaner	TP		
AJ184 / 9	LYLES CHEMICAL & SUP	6208 N LAMAR BLVD	TX HIST UST	TP		
AJ185 / 9	TJS CYCLE SALES & SE	6208 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
AJ186 / 9	RICKS SALES CO.	6205 N LAMAR BLVD	TX HIST UST	TP		
AJ187 / 9	SWANNS GARAGE & RADI	6203 N LAMAR BLVD	TX UST, TX HIST UST	TP		
AJ188 / 9	NORTH LAMAR AUTOMOTI	6203 LAMAR BLVD N	EDR Hist Auto	TP		
AJ189 / 9	SWANNS GARAGE RADIAT	6203 N LAMAR BLVD	TX LPST, TX Ind. Haz Waste	TP		
AJ190 / 9	SWANNS GARAGE & RADI	6203 N LAMAR BLVD	TX CENTRAL REGISTRY	TP		
AJ1321 / 9	KLINGEMANN CAR CARE	6200 N LAMAR BLVD	TX RDR	100	0.019	WNW
AJ1322 / 9	MORGAN AUTOMOTIVE	6200 N LAMAR BLVD	TX HIST UST, TX Ind. Haz Waste, TX CENTR...	100	0.019	WNW
AJ1323 / 9	NORTH LAMAR AUTOMOTI	6200 LAMAR BLVD N	EDR Hist Auto	100	0.019	WNW
KO1816 / 9	J.E. RICKS	6215 N LAMAR BLVD	TX HIST UST	188	0.036	ESE
KO1817 / 9	T JS CYCLE SALES & S	6215 LAMAR BLVD N	EDR Hist Auto	188	0.036	ESE
TC3117 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	TX AST, TX Ind. Haz Waste	1255	0.238	ESE
TC3118 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	RCRA NonGen / NLR, ICIS, FINDS, ECHO	1255	0.238	ESE
TC3119 / 9	TEXAS DEPT PUBLIC SA	5710 GUADALUPE ST	TX RDR	1255	0.238	ESE
TC3120 / 9	TEXAS DEPARTMENT OF	5710 GUADALUPE ST	TX UST, TX HIST UST	1255	0.238	ESE
TF3131 / 9	TEXAS DEPT OF PUBLIC	5900 GUADALUPE ST	TX UST, TX HIST UST	1272	0.241	ESE
TF3132 / 9	AUSTIN ISD	5900 GUADALUPE	RCRA NonGen / NLR, FINDS, ECHO	1272	0.241	ESE
TF3133 / 9	AUSTIN ISD	5900 GUADALUPE ST	TX Ind. Haz Waste	1272	0.241	ESE
TF3164 / 9	AUSTIN ISD SNEED	5901 GUADALUPE ST	TX LPST, TX Ind. Haz Waste	1367	0.259	ESE
3188 / 9	GEORGE TORRES TEXACO	301 W KOENIG LN	TX LPST, TX HIST UST, TX ENF, TX COMP HI...	1635	0.310	ESE
3233 / 9	OLD SEARS WAREHOUSE	108 DENSON DR	TX LPST, TX UST	2185	0.414	ESE
UC3258 / 9	STOP N GO #2207	4429 DUVAL ST	TX RDR	2381	0.451	East
UC3259 / 9	SUNRISE SUPER STOP	4429 DUVAL ST	TX LPST, TX UST, TX HIST UST, TX Financi...	2381	0.451	East
UC3260 / 9	MINIS FOOD MART	4429 DUVAL ST	TX RDR	2381	0.451	East
3261 / 9	MR SAMS FOODMART	6515 AIRPORT BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2384	0.452	ESE
3287 / 9	PERRY ROSE TIRE HIGH	6401 AIRPORT BLVD	TX LPST, TX UST, TX HIST UST	2541	0.481	ESE
3295 / 9	CONTINENTAL CARS	200 W HUNTLAND	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	2602	0.493	ESE

Focus Map - 10 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 10

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 11 - 7418065.7s


BRACKENRIDGE HOSPITAL HELIPORT
CAPITAL BANK BUILDING HELIPORT
E Riverside Dr
W Riverside Dr
Shoal Creek Blvd
Lamar Blvd
Guadalupe St
Red River St
E 7th St
E 8th St
E 10th St
E 11th St
E 12th St
E 15th St
E 16th St
E 17th St
E 18th St
E 19th St
E 20th St
E 21st St
E 22nd St
E 23rd St
E 24th St
E 30th St
E 31st St
E 32nd St
E 2nd St
E 3rd St
E 4th St
E 5th St
E 6th St
E 7th St
E 8th St
E 9th St
E 10th St
E 11th St
E 12th St
E 13th St
E 14

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
BJ320 / 11	CHEVRON SELF SERVICE	2819 GUADALUPE ST	EDR Hist Auto	TP
BJ321 / 11	CHEVRON FAC 107149	2819 GUADALUPE ST	FINDS	TP
BJ322 / 11	STAR STOP 74	2819 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BJ323 / 11	STAR STOP 74	2819 GUADALUPE ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
BJ324 / 11	TETCO 78	2819 GUADALUPE ST	TX RDR	TP
BK325 / 11	CHEVRON USA INC	2817 GUADALUPE ST	RCRA NonGen / NLR, FINDS, ECHO	TP
BK326 / 11	LICARI SAM GULF	2817 GUADALUPE ST	EDR Hist Auto	TP
BK327 / 11	CHEVRON FAC 107149	2817 GUADALUPE ST	TX Ind. Haz Waste	TP
BK328 / 11	CHEVRON STATION 1071	2817 GUADALUPE ST	TX LPST, TX ASBESTOS	TP
BK329 / 11	CHEVRON 107149	2817 GUADALUPE ST	TX CENTRAL REGISTRY	TP
BL330 / 11	AMERICAN CONSTRUCTOR	101 E 30TH ST	FINDS	TP
BL331 / 11	AMERICAN CONSTRUCTOR	101 E 30TH ST	TX CENTRAL REGISTRY	TP
BK332 / 11	MAGNOLIA PET CO STA	2810 GUADALUPE ST	EDR Hist Auto	TP
BM333 / 11	LAUNDERETTE WASHATER	2706 GUADALUPE	EDR Hist Cleaner	TP
BM334 / 11	PARAMOUNT CLNRS	2704 GUADALUPE ST	EDR Hist Cleaner	TP
BN335 / 11	MAC'S PIZZA	2701 GUADALUPE ST.	TX ASBESTOS	TP
BN336 / 11	DUNBAR LOUIE FILL ST	2701 GUADALUPE ST	EDR Hist Auto	TP
337 / 11	FORMER FRAT HOUSE BU	2614 RIO GRANDE ST	TX ASBESTOS	TP
BO338 / 11	FORTY ACRES CLNS	2605 GUADALUPE ST	EDR Hist Cleaner	TP
BP339 / 11	FRATERNITY HOUSE	800 W. 26TH ST.	TX ASBESTOS	TP
BP340 / 11	FRATERNITY HOUSE	800-804 WEST 26TH	TX ASBESTOS	TP
BP341 / 11	LYDA SWINERTON BUILD	711 W 26TH ST	TX CENTRAL REGISTRY	TP
BO342 / 11	LONGHORN GULF SERV	2601 GUADALUPE ST	EDR Hist Auto	TP
BQ343 / 11	SJL AD SPECIALTIES	2512 RIO GRANDE ST	TX Ind. Haz Waste	TP
BQ344 / 11	SJL AD SPECIALTIES	2512 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
BR345 / 11	BRIDGEWAY	2616 WICHITA	TX ASBESTOS	TP
BS346 / 11	LEES SUPER SERVICE F	2533 GUADALUPE	EDR Hist Auto	TP
BS347 / 11	UNIVERSITY CLEANERS	2520 GUADALUPE ST	EDR Hist Cleaner	TP
BS348 / 11	AUSTIN DRY CLEANERS	2516 GUADALUPE ST	EDR Hist Cleaner	TP
BT349 / 11	ALPHA EPSLION PHI SO	2500 RIO GRANDE ST.	TX ASBESTOS	TP
BT350 / 11	ALPHA EPSILON PHI SO	2500 RIO GRANDE ST.	TX ASBESTOS	TP
BT351 / 11	ALPHA EPSILON PHI HO	2500 RIO GRANDE	TX ASBESTOS	TP
BR352 / 11	STUDENT SERVICES BUI	100 W DEAN KEETON ST	TX ASBESTOS	TP
BU353 / 11	COWBOYS TAILOR	2505 GUADALUPE ST	EDR Hist Cleaner	TP
BU354 / 11	COUCH CLEANERS	2501 GUADALUPE	EDR Hist Cleaner	TP
BU355 / 11	2412 UNIVERSITY SERV	2436 GUADALUPE ST	EDR Hist Auto	TP
BU356 / 11	WALTER WEBB HALL	405 W. 25TH STREET	TX ASBESTOS	TP
BV357 / 11	UNIVERSITY UNITED ME	2409 GUADALUPE ST.	TX ASBESTOS	TP
BW358 / 11	FOODIES 2	2400 RIO GRANDE ST	TX SPILLS, TX ENF	TP

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
BW359 / 11	WAG-A-BAG 24	2400 RIO GRANDE ST	FINDS	TP
BW360 / 11	FOODIES 2	2400 RIO GRANDE ST	TX COMP HIST	TP
BW361 / 11	FOODIES NO. 2	2400 RIO GRANDE STRE	TX RDR	TP
BW362 / 11	FOODIES 2	2400 RIO GRANDE ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
BW363 / 11	FOODIES 2	2400 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
BW364 / 11	SCHIEFFERS BEN	701 24TH W	EDR Hist Auto	TP
BX365 / 11	B LONGHORN CLNS	705 24TH W	EDR Hist Cleaner	TP
BW366 / 11	LOONEY L P FILLING	2323 RIO GRANDE	EDR Hist Auto	TP
BY367 / 11	CORNERSTONE PLACE AP	2308 RIO GRANDE ST	FINDS	TP
BY368 / 11	GEDR AT UNION ON 24T	2308 RIO GRANDE ST	TX TANKS, TX VCP, TX ASBESTOS	TP
BY369 / 11	CORNERSTONE PLACE AP	2308 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
370 / 11	PARKING GARAGE	715 WEST 23RD STREET	TX ASBESTOS	TP
BZ371 / 11	WASH N FOLD INDRY	2202 RIO GRANDE ST	EDR Hist Cleaner	TP
CA372 / 11	AUSTIN MAIN POST OFF	2201 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CA373 / 11	AUSTIN MAIN POST OFF	2201 GUADALUPE ST	TX UST	TP
374 / 11	HODGES CLEANERS	107 21ST E	EDR Hist Cleaner	TP
CB375 / 11	THE SHOPS AT DOBIE C	2021 GUADALUPE SUITE	TX ASBESTOS	TP
CB376 / 11	TARGET STORE T3250	2021 2021 GUADALUPE	RCRA-SQG	TP
CB377 / 11	TARGET STORE T3250	2021 2021 GUADALUPE	FINDS, ECHO	TP
CB378 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST #	TX ASBESTOS, TX Ind. Haz Waste	TP
CB379 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST NO	RCRA NonGen / NLR, FINDS, ECHO	TP
CB380 / 11	GINNYS COPYING SERVI	2021 GUADALUPE ST #	TX CENTRAL REGISTRY	TP
CB381 / 11	TARGET STORE T3250	2021 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CC382 / 11	CITYVILLE AT PEARL	706 W MLK JR BLVD	FINDS	TP
CC383 / 11	CITYVILLE AT PEARL	706 W MLK JR BLVD	TX CENTRAL REGISTRY	TP
CB384 / 11	CUTLERS MOTOR CO	2015 GUADALUPE ST	EDR Hist Auto	TP
CD385 / 11	FORMER UT SHELL	1901 GUADALUPE ST	TX RDR	TP
CD386 / 11	EXXON SHOP 67450	1901 GUADALUPE	RCRA NonGen / NLR, FINDS, ECHO	TP
CD387 / 11	EXXON SHOP 67450	1901 GUADALUPE ST	TX Ind. Haz Waste	TP
CD388 / 11	U T SHELL	1901 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX Financi...	TP
CD389 / 11	EXXON SHOP GASOLINE	1901 GUADALUPE ST	EDR Hist Auto	TP
CD390 / 11		1901 GUDALPE ST	ERNS	TP
CD391 / 11	U T SHELL	1901 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CD392 / 11	TENNISON PROPERTIES	19TH & GUADALUPE	EDR Hist Auto	TP
CE393 / 11	TF AFFORDABLE HOUSIN	1717 WEST 67TH STREE	FINDS	TP
CE394 / 11	AUSTIN HIGH SCHOOL	1715 WEST AVE LOT ST	TX Ind. Haz Waste	TP
CF395 / 11	0 K TAILORING CO	1814 GUADALUPE ST	EDR Hist Cleaner	TP
CF396 / 11	7 ELEVEN STORE 23295	1814 GUADALUPE ST	FINDS	TP
CF397 / 11	GULF OIL CORP	1814 GUADALUPE ST	EDR Hist Auto	TP

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
CF398 / 11	7 ELEVEN STORE NO 23	1814 GUADALUPE ST	TX RDR	TP
CF399 / 11	7-ELEVEN 23295	1814 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
CF400 / 11	7-11 #23295	1814 GUADALUPE ST	TX RDR	TP
CF401 / 11	WHITING ROBT E	1809 GUADALUPE ST	EDR Hist Auto	TP
CF402 / 11	KNIGHT STEWART	1805 GUADALUPE	EDR Hist Auto	TP
CG403 / 11	UT BLANTON MUSEUM OF	200 E MARTIN LUTHER	ECHO	TP
CG404 / 11	UT BLANTON MUSEUM OF	200 E MARTIN LUTHER	FINDS	TP
CG405 / 11	BLANTON MUSEUM	200 E MARTIN LUTHER	TX HIST UST	TP
CG406 / 11	BLANTON MUSEUM LANDS	200 E MLK BLVD	TX RDR	TP
CG407 / 11	SKANSKA USA BUILDING	200 E MARTIN LUTHER	TX CENTRAL REGISTRY	TP
CH408 / 11	VACANT RESTAURANT BL	1715 GUADALUPE ST.	TX ASBESTOS	TP
CG409 / 11	MAGNOLIA PETROLEUM C	105 W MARTIN LUTHER	TX HIST UST	TP
CI410 / 11	DEAVERS CONSTRUCTION	1601 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
CI411 / 11	DEAVERS CONSTRUCTION	1601 RIO GRANDE ST	TX AST	TP
CH412 / 11	1705 GUADALUPE ST. B	1705 GUADALUPE ST.	TX ASBESTOS	TP
CH413 / 11	SPOTLESS CASH CLEAN	1703 GUADALUPE ST	EDR Hist Cleaner	TP
CJ414 / 11	WILLIAM GAMON INSURA	1615 GUADALUPE STREE	TX ASBESTOS	TP
CJ415 / 11	UT ADMINISTRATION BU	1616 GUADALUPE	TX ASBESTOS	TP
CJ416 / 11	GUADALUPE MOTOR POOL	1616 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CJ417 / 11	ABOUT TIME DRY CLEAN	1616 GUADALUPE ST	EDR Hist Cleaner	TP
CJ418 / 11	UT AUSTIN DAS	1616 GUADALUPE STREE	TX TIER 2	TP
CJ419 / 11	GUADALUPE MOTOR POOL	1616 GUADALUPE ST	TX UST, TX HIST UST	TP
CK420 / 11		LBJ BLDG 111 EAST 17	ERNS	TP
CL421 / 11	ENVIRONMENTAL CONTRA	1405 RIO GRANDE ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	TP
CL422 / 11	ENVIRONMENTAL CONTRA	1405 RIO GRANDE ST	FINDS	TP
CM423 / 11	PETTY LEASE-9 MILES	PETTY LEASE-9 MILES	TX SPILLS	TP
CN424 / 11	NOT AVAILABLE (ZONIN	101 W 15TH ST	TX HIST UST	TP
CO425 / 11	ACC RIO GRANDE ST	1215 RIO GRANDE ST	TX ASBESTOS	TP
CO426 / 11	ACC ATTACHE BUILDING	1209 RIO GRANDE	TX ASBESTOS	TP
CO427 / 11	ACC RIO GRANDE CAMPU	1209 RIO GRANDE STRE	TX ASBESTOS	TP
CP428 / 11	BURCH H H SERV STA	1228 CONGRESS AVE	EDR Hist Auto	TP
429 / 11	TEXAS WORKFORCE COMM	1215 GUADALUPE ST.	TX ASBESTOS	TP
CQ430 / 11	BUTLERS TERRACE	1123 CONGRESS AVE	EDR Hist Auto	TP
CQ431 / 11	VACANT BUILDING	1117 CONGRESS	TX ASBESTOS	TP
CQ432 / 11	NO DELAY CLN &	1117 CONGRESS AVE	EDR Hist Cleaner	TP
CQ433 / 11	MUSIC LANE SHOPPING	1109 CONGRESS	TX ASBESTOS	TP
CR434 / 11	CITY OF AUSTIN - WAT	901 WEST KOENING LAN	TX TIER 2	TP
CR435 / 11	WATER/WASTEWATER NOR	901 WEST KOENING LAN	TX TIER 2	TP
CR436 / 11	WEST 9TH STREET PART	704 W 9TH ST	EDR Hist Auto	TP

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
CS437 / 11	TRAVIS COUNTY COURTH	1000 GUADALUPE ST	TX CENTRAL REGISTRY	TP
CS438 / 11	HEMAN MARION SWEATT	1000 GUADALUPE STREE	TX ASBESTOS	TP
CS439 / 11	TRAVIS COUNTY COURTH	1000 GUADALUPE ST	TX UST	TP
CT440 / 11	TEXAS DEPT. OF TRANS	125 E. 11TH ST.	PRP	TP
CT441 / 11	TXDOT	125 E. 11TH STREET	ICIS, FINDS, ECHO	TP
CT442 / 11	TEXAS DEPT OF TRANSP	125 E 11TH ST	TX CENTRAL REGISTRY	TP
CT443 / 11	KENEDY COUNTY REST A	125 E. 11TH STREET	ICIS	TP
CU444 / 11	CARLSONS DAVE	915 GUADALUPE ST	EDR Hist Auto	TP
CU445 / 11	CARLSON DAVE GA	907 GUADALUPE ST	EDR Hist Auto	TP
CU446 / 11	COURT HOUSE SERV	905 GUADALUPE	EDR Hist Auto	TP
CV447 / 11	JOHNSON & LLOYD TAI	1001 CONGRESS ST	EDR Hist Cleaner	TP
CU448 / 11	VIAWEST, INC.	WEST 9TH STREET	ICIS, FINDS	TP
CW449 / 11	COMMERCIAL BUILDING	916 CONGRESS AVE	TX ASBESTOS	TP
CV450 / 11	VACANT BUILDING	107 E. 10TH STREET	TX ASBESTOS	TP
CV451 / 11	MODEL LAUNDRY	919 CONGRESS AVE	EDR Hist Cleaner	TP
CV452 / 11	MOBIL CORPORATION	919 CONGRESS AVE STE	EDR Hist Auto	TP
453 / 11	707 WEST AVE.	707 WEST AVE.	TX ASBESTOS	TP
CX454 / 11	701 RIO GRANDE	701 RIO GRANDE ST	TX ASBESTOS	TP
CY455 / 11	FAULK LIBRARY BUILDI	800 GUADALUPE STREET	TX ASBESTOS	TP
CY456 / 11	JOHN HENRY FAULK BRA	800 GUADALUPE	TX ASBESTOS	TP
CZ457 / 11	HUMBLE OIL & REFININ	719 W 6TH ST	TX HIST UST	TP
DA458 / 11	KATZ & ATLAS	618 W 6TH ST	TX CENTRAL REGISTRY	TP
DA459 / 11	KATZ & ATLAS	618 W 6TH ST	TX UST, TX HIST UST	TP
CZ460 / 11	507 WEST AVENUE	507 WEST AVENUE	TX GCC	TP
CZ461 / 11	507 WEST AVENUE	507 WEST AVE	TX IOP	TP
CZ462 / 11	507 WEST AVENUE	507 WEST AVE	TX GCC	TP
CZ463 / 11	507 WEST AVENUE	507 WEST AVE	TX CENTRAL REGISTRY	TP
DB464 / 11	TEXAS AMERICAN 220 G		PFAS ECHO	TP
DB465 / 11	BERGSTROM AIR FORCE		PFAS ECHO	TP
DA466 / 11	KELLY SMITH OWNER	617 W 6TH ST	TX HIST UST	TP
DA467 / 11	MAGNOLIA PETROLEUM C	617 W 6TH ST	TX HIST UST	TP
DA468 / 11	DICKERSON CINS	511 RIO GRANDE	EDR Hist Cleaner	TP
DA469 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	TX CENTRAL REGISTRY	TP
DA470 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	TX DRYCLEANERS	TP
DA471 / 11	AMERICAN CLEANERS	511 RIO GRANDE ST	FINDS	TP
DC472 / 11	DR PEPPER BOTTLING C	718 W 5TH ST	TX HIST UST	TP
DC473 / 11	DR PEPPER BOTTLING C	718 W 5TH ST	TX HIST UST	TP
DD474 / 11	AMERICAN TAXI CAB CO	610 W 5TH ST	TX HIST UST	TP
DD475 / 11	CAPITAL PETROLEUM PR	610 W 5TH ST	TX HIST UST	TP

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DE476 / 11	RTC	400 W 6TH ST	TX HIST UST	TP
DF477 / 11	FIX IT SHOP THE	123 7TH W	EDR Hist Auto	TP
DF478 / 11	120 22 NORWOOD MOTOR	120 7TH W	EDR Hist Auto	TP
DF479 / 11	MOTORAMP STORAGE	118 7TH W	EDR Hist Auto	TP
DF480 / 11	A CLEANERS & DYERS	119 7TH W	EDR Hist Cleaner	TP
DE481 / 11	SHIRLEY N A CLNRS	407 6TH W	EDR Hist Cleaner	TP
DE482 / 11	KOCH CLEANING & DYIN	405 6TH W	EDR Hist Cleaner	TP
DE483 / 11	ALAMO HOTEL GARAGE	402 6TH W	EDR Hist Auto	TP
DE484 / 11	PATSCHKE ALAMO	400 6TH W	EDR Hist Auto	TP
DE485 / 11	GRAYBURG OIL CO STA	401 6TH W	EDR Hist Auto	TP
DG486 / 11	MASTER VALET CLEANER	109 E 7TH ST	EDR Hist Cleaner	TP
DG487 / 11	DRISKILL HOTEL STEAM	113 E 7TH ST	EDR Hist Cleaner	TP
DG488 / 11	JLR CLEANERS	612 BRAZOS STREET	US AIRS, FINDS, ECHO	TP
DG489 / 11	DAVIS MAX DCLO CLNR	612 BRAZOS ST	EDR Hist Cleaner	TP
DG490 / 11	VACANT OFFICE BUILDI	612 BRAZOS	TX ASBESTOS	TP
DH491 / 11	DICKERSON DRY CLEANI	600 N CONGRESS AVE	TX HIST UST	TP
DI492 / 11	B & N AXEL SERV	503 GUADALUPE	EDR Hist Auto	TP
DJ493 / 11	LYM ARCHITECTURE BLD	610 BRAZOS	TX ASBESTOS	TP
DJ494 / 11	OFFICE BUILDING	610 BRAZOS	TX ASBESTOS	TP
DJ495 / 11	LYM ARCHITECTURE BUI	610 BRAZOS	TX ASBESTOS	TP
DH496 / 11	J HARPER STARR BLDG	106 W 6TH	TX RDR	TP
DK497 / 11	SOUTHWEST TOWERS	211 E 7TH	TX ASBESTOS	TP
DK498 / 11	MCI- AUSXTX (TXAUSXT	211 E 7TH ST FL 9	TX TIER 2	TP
DK499 / 11	GENERAL MUFFLER CORP	211 E 7TH	EDR Hist Auto	TP
DK500 / 11	MACONDA PARK	211 E 7TH ST STE 709	TX CENTRAL REGISTRY	TP
DK501 / 11	MCI AUSXTX	211 EAST 7TH STREET,	TX TIER 2	TP
DK502 / 11	REEF SERVICES LLC/D/	211 E. 7TH STREET, S	FINDS	TP
DK503 / 11	SOUTHWEST TOWERS	211 E 7TH STREET	TX HIST UST, TX ASBESTOS	TP
DJ504 / 11	DAVIS MAX DCLO CLNR	609 BRAZOS ST	EDR Hist Cleaner	TP
DH505 / 11	EXCELSIOR LAUNDRY	117 6TH W	EDR Hist Cleaner	TP
DH506 / 11	SCARBROUGH BUILDING	101 E. 6TH STREET	TX ASBESTOS	TP
DH507 / 11	SCARBROUGH BLDG.	101 E. 6TH STREET	TX ASBESTOS	TP
DH508 / 11	SCARBROUGH BUILDING	101 W 6TH ST	TX VCP, TX HIST UST	TP
DH509 / 11	SCARBROUGH BUILDING	101 W 6TH ST	FINDS	TP
DH510 / 11	SCARBROUGH BUILDING	101 W 6TH ST	TX CENTRAL REGISTRY	TP
DH511 / 11	CARRINGTON ASSOCIATE	101 W 6TH ST	FINDS	TP
DL512 / 11	AUSTIN CITY OF	301 W AVE	HIST FTTS	TP
DL513 / 11	AUSTIN CITY ELECT UT	301 W AVE	RCRA-SQG, FINDS, ECHO	TP
DL514 / 11	AUSTIN ENERGY - ENER	301 WEST AVENUE	TX GCC	TP

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DL515 / 11	AUSTIN ENERGY WEST A	301 WEST AVE	TX UST, TX Financial Assurance	TP
DL516 / 11	CITY OF AUSTIN	301 WEST AVE	FINDS	TP
DL517 / 11	AUSTIN ENERGY-ENERGY	301 WEST AVE	TX VCP	TP
DL518 / 11	AUSTIN ENERGY - ENER	301 WEST AVE	TX GCC	TP
DL519 / 11	AUSTIN ENERGY CONTRO	301 WEST AVE	TX HIST UST, TX ASBESTOS	TP
DL520 / 11	AUSTIN CITY OF	301 W AVE	FTTS	TP
DL521 / 11	AUSTIN ENERGY WEST A	301 WEST AVE	TX CENTRAL REGISTRY	TP
DL522 / 11	ENERGY CONTROL CENTE	301 WEST AVE.	TX TIER 2	TP
DM523 / 11	YOUNG 0 E AUTO REPR	613 TRINITY ST	EDR Hist Auto	TP
DN524 / 11	STAGES PORT E TAILOR	521 CONGRESS AVE	EDR Hist Cleaner	TP
DM525 / 11	CENTEX AUTO REPAIR	405 E 7TH ST	EDR Hist Auto	TP
DN526 / 11	515 CONGRESS OFFICE	515 CONGRESS AVE.	TX ASBESTOS	TP
DM527 / 11	GUSS GARAGE AUTO	609 TRINITY ST	EDR Hist Auto	TP
DM528 / 11	JOHNSON HARRY E	605 TRINITY	EDR Hist Auto	TP
DO529 / 11	SOUTHERN SERVICE STA	403 GUADALUPE	EDR Hist Auto	TP
DP530 / 11	13 MAG/ IN THE FLESH	211 E 6 STREET	TX ASBESTOS	TP
DP531 / 11	13 MAG/IN THE FLESH	211 E 6TH ST #B	TX ASBESTOS	TP
DP532 / 11	NCNB TEXAS	219 E 6TH ST	TX LPST	TP
DP533 / 11	NCNB TEXAS	219 E 6TH ST	TX CENTRAL REGISTRY	TP
DP534 / 11	MAJESTIC CLEANERS	219 E SIXTH	EDR Hist Cleaner	TP
DO535 / 11	THE REPUBLIC	401 W 4 STREET	FINDS	TP
DO536 / 11	THE REPUBLIC	401 W 4 STREET	ECHO	TP
DO537 / 11	THE REPUBLIC	401 W 4 STREET	TX CENTRAL REGISTRY	TP
DQ538 / 11	BLACK CAT TATTOO	315 E 6 STREET	TX ASBESTOS	TP
DQ539 / 11	LEVI JOSEPH MERCHAN	315 E 6TH ST	EDR Hist Cleaner	TP
DR540 / 11	TATTOOS FROM THE SOU	514 E 6TH ST	TX ASBESTOS	TP
DR541 / 11	TATTOOS FROM THE SOU	514 E 6TH STREET	TX ASBESTOS	TP
DR542 / 11	ALL SAINTS TATTOO	514 E 6TH ST	TX ASBESTOS	TP
DR543 / 11	ALL SAINTS TATTOOS	514 E 6TH STREET	TX ASBESTOS	TP
DR544 / 11	JUNIOR LEAGUE OF AUS	522 E 6TH ST	TX HIST UST	TP
DR545 / 11	JUNIOR LEAGUE OF AUS	524 E 6TH ST	TX CENTRAL REGISTRY	TP
DR546 / 11	JUNIOR LEAGUE OF AUS	524 E 6TH ST	TX LPST, TX UST	TP
DR547 / 11	GREGG AUTO REPAIRS	610 RED RIVER	EDR Hist Auto	TP
DR548 / 11	CAIN RHONIE AUTO	608 RED RIVER CT	EDR Hist Auto	TP
DR549 / 11	MARX J W AUTO REPR	606 RED RIVER CT	EDR Hist Auto	TP
DR550 / 11	HERRING WALTER B AUT	606 6TH E	EDR Hist Auto	TP
DR551 / 11	HERRINGS GARAGE AUTO	610 6TH ST E	EDR Hist Auto	TP
DR552 / 11	HERRINGS GARAGE AUTO	610 6TH ST E	EDR Hist Auto	TP
DR553 / 11	BIG SIX GARAGE AUTO	610 6TH E	EDR Hist Auto	TP

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
DS554 / 11	WALKER OIL COMP.	300-400 GUADALUPE	TX HIST UST	TP
DS555 / 11	GUGENHEIM-GOLDSMITH	410 E 3RD ST	TX HIST UST	TP
DS556 / 11	AUSTIN MUSEUM OF ART	400 W 3RD ST AUSTIN	TX HIST UST, TX CENTRAL REGISTRY	TP
DT557 / 11	MAGNOLIA PETROLEUM C	617 E 6TH ST	TX HIST UST	TP
DU558 / 11	504 5TH ST	504 EAST 5TH ST	TX ASBESTOS, TX CENTRAL REGISTRY	TP
DU559 / 11	STEARNS JACK AUTO	502 RED RIVER CT	EDR Hist Auto	TP
DV560 / 11	CATHYS DOWNTOWN CLEA	231 W 3RD ST	TX CENTRAL REGISTRY	TP
DV561 / 11	CATHYS DOWNTOWN CLEA	231 W 3RD ST	TX DRYCLEANERS	TP
DV562 / 11	CATHY CLEANER	231 W 3RD ST	EDR Hist Cleaner	TP
DU563 / 11	YELLOW CAB	555 E 5TH ST	TX HIST UST	TP
DW564 / 11	SUBSTATION; SEAHOLM	704 W CESAR CHAVEZ	TX TIER 2	TP
DW565 / 11	SEAHOLM SUBSTATION	704 WEST CESAR CHAVE	TX TIER 2	TP
DU566 / 11	FOUND ON SANBORN MAP	601 E 5TH ST	TX HIST UST	TP
DU567 / 11	G W CUNNINGHAM	601 E 5TH ST	TX HIST UST	TP
DX568 / 11	BLOCK 21	201 GUADALUPE ST	FINDS	TP
DX569 / 11	BLOCK 21 CITY OF AUS	201 GUADALUPE STREET	TX GCC, TX IOP	TP
DU570 / 11	BETHKE WALTER AUTO	408 RED RIVER	EDR Hist Auto	TP
DY571 / 11	PARSLEY W L DCLO CLN	310 CONGRESS AVE E	EDR Hist Cleaner	TP
DX572 / 11	COVERT BUICK BODY SH	402 2ND ST W	EDR Hist Auto	TP
DX573 / 11	COVERT BUICK BODY SH	402 2ND ST W	EDR Hist Auto	TP
574 / 11	GAS PIPE	701 E 5TH ST	TX ASBESTOS	TP
DZ575 / 11	SMITH BROS AUTO DLR	301 BRAZOS	EDR Hist Auto	TP
DZ576 / 11	THE WHITLEY	301 BRAZOS ST	TX CENTRAL REGISTRY	TP
DZ577 / 11	WHITLEY COMPANY#	301-05 BRAZOS	RCRA-SQG, FINDS, ECHO	TP
DZ578 / 11	MUELLERS GAR AUTO	212 3RD E	EDR Hist Auto	TP
DZ579 / 11	MUELLERS GARAGE GR	212 3RD ST E	EDR Hist Auto	TP
DZ580 / 11	THIRD AND BRAZOS	201 EAST 3RD	TX ASBESTOS	TP
DZ581 / 11	BNK 63	201 E 3RD ST	TX HIST UST	TP
EA582 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	TX CENTRAL REGISTRY	TP
EA583 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	FINDS	TP
EA584 / 11	THOMAS REPROGRAPHICS	304 E 3RD ST	ECHO	TP
EB585 / 11	SILICON LABORATORIES		PFAS ECHO	TP
EC586 / 11	CIRCLE SAW SHOP	201 TRINITY ST	TX HIST UST	TP
EC587 / 11	HOBART	404 E 2ND ST	TX CENTRAL REGISTRY	TP
EC588 / 11	HOBART	404 E 2ND ST	TX Ind. Haz Waste	TP
EC589 / 11	COVERT AUTOMOBILE CO	440 E 2ND ST	TX HIST UST	TP
EC590 / 11	M. SCHNEIDER ESTATE	440 E 2ND ST	TX HIST UST	TP
ED591 / 11	SETH ENGINE PARTS	617 E 3RD ST	TX UST, TX HIST UST	TP
ED592 / 11	FORMER SETH ENGINE P	617 E 3RD ST	TX LPST	TP

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
ED593 / 11	HOLIDAY CLEANERS	12300 INWOOD RD STE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	TP		
EE594 / 11	DEWEYS RADIATOR WORK	106 TRINITY ST	EDR Hist Auto	TP		
595 / 11	GLENN SERVICE STATIO	10 CONGRESS AVE	EDR Hist Auto	TP		
596 / 11	WCT WALLER BEACH SIT	74 TRINITY ST	TX ENF, TX COMP HIST	TP		
EF597 / 11	DAVIS SPRING BRANCH	151 S 1ST ST STE 200	TX CENTRAL REGISTRY	TP		
598 / 11	CFJ BARGE REFINING	210 BARTON SPRINGS #	RCRA NonGen / NLR, FINDS, ECHO	TP		
EG599 / 11	80 RAINEY STREET	78 80 82 AND 84 RAIN	TX CENTRAL REGISTRY	TP		
EG600 / 11	VACAN SHED	80 RAINEY STREET	TX ASBESTOS	TP		
EH601 / 11	HOOTER'S RESTAURANT	425 WEST RIVERSIDE D	TX ASBESTOS	TP		
EH602 / 11	FORMER GAS STATION P	425 W RIVERSIDE DR	TX TANKS, TX CENTRAL REGISTRY	TP		
HQ948 / 11	IVORY CLEANERS & ALT	1901 RIO GRANDE ST	EDR Hist Cleaner	60	0.011	East
HQ949 / 11	ADAMS SERVICE CO GAS	1901 RIO GRANDE ST	EDR Hist Auto	60	0.011	East
HQ950 / 11	7-ELEVEN 23630	1901 RIO GRANDE ST	TX UST, TX HIST UST	60	0.011	East
HQ951 / 11	IVORY CLEANERS & ALT	1901 RIO GRANDE ST	TX LPST, TX VCP, TX ASBESTOS, TX DRYCLEA...	60	0.011	East
HR957 / 11	WESLEY GEORGE CLEANE	606 GUADALUPE ST	EDR Hist Cleaner	60	0.011	WNW
HR958 / 11	FIEGEL GEO JR AUTO	606 GUADALUPE ST	EDR Hist Auto	60	0.011	WNW
DY960 / 11	OWL TAXI SERVICE	100 W 3RD ST	TX HIST UST	61	0.012	NNE
BX961 / 11	LONGHORN CLEANERS NO	705 W 24TH ST	EDR Hist Cleaner	61	0.012	East
BX962 / 11	CIRCLE K CORPORATION	705 W 24TH ST	EDR Hist Auto	61	0.012	East
DO963 / 11	GABLES RESIDENTIAL	401 GUADALUPE ST	TX HIST UST, TX GCC, TX IOP	61	0.012	ESE
967 / 11	PAGS CARBURETOR	403 RIO GRANDE	EDR Hist Auto	61	0.012	WNW
975 / 11	HYATT REGENCY HOTEL	208 BARTON SPRINGS R	TX VCP	62	0.012	South
DE976 / 11	ROTP 2 PROPERTY	401 W 6TH ST	TX UST	62	0.012	WNW
DE977 / 11	GRAYBURG OIL	401 W 6TH ST	TX HIST UST	62	0.012	WNW
DE978 / 11	US POST OFFICE	401 W 6TH ST	TX HIST UST	62	0.012	WNW
HU995 / 11	BURTONS LNDRY	411 23RD W	EDR Hist Cleaner	63	0.012	West
DG996 / 11	QUONG WAH CHINESE LA	115 E 7TH ST	EDR Hist Cleaner	63	0.012	NNE
DX1003 / 11	J.P. SCHNEIDER	401 W 2ND ST	TX HIST UST	63	0.012	WNW
DA1004 / 11	AUSTIN WATER METER	607 RIO GRANDE	EDR Hist Auto	63	0.012	WNW
DA1005 / 11	CUSTOM SERVICE CARPE	607 RIO GRANDE ST	EDR Hist Cleaner	63	0.012	WNW
HY1006 / 11	TACO BELL	2801 GUADALUPE ST	TX LPST, TX UST, TX ASBESTOS	63	0.012	ENE
HU1007 / 11	DOLLARS AND CENTS	2268 GUADALUPE	EDR Hist Cleaner	64	0.012	West
BZ1009 / 11	HARDIN RICHD G CO	2200 RIO GRANDE ST	EDR Hist Cleaner	64	0.012	West
HU1013 / 11	B CO OP PRESSING	2304 GUADALUPE ST	EDR Hist Cleaner	65	0.012	West
IA1014 / 11	REYES CLNRS	312 BARTON SPRINGS	EDR Hist Cleaner	65	0.012	NE
1025 / 11	TEXAS CLEANERS	2236 GUADALUPE	EDR Hist Cleaner	65	0.012	West
BM1030 / 11	TEXAS PACIFIC COAL O	2714 GUADALUPE	EDR Hist Auto	66	0.013	WSW
1034 / 11	LOOMIS ARMORED INC	78 N I 35	TX HIST UST	66	0.013	ESE
BN1035 / 11	LOCKHART LNDRY	2612 GUADALUPE ST	EDR Hist Cleaner	66	0.013	West

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
BM1036 / 11	BRANUM CLEANERS	2716 GUADALUPE	EDR Hist Cleaner	66	0.013	WSW
DM1037 / 11	PREMIUM PARKING PUBL	415 E 7TH ST	TX TANKS, TX COMP HIST, TX CENTRAL REGIS...	66	0.013	NNE
DM1038 / 11	HENRY KNEMPEL	415 E 7TH ST	TX HIST UST	66	0.013	NNE
DM1039 / 11	ALLRIGHT PARKING	415 E. 7TH ST.	TX HIST UST	66	0.013	NNE
DM1040 / 11	PREMIUM PARKING PUBL	415 E 7TH STREET	TX RDR	66	0.013	NNE
CA1042 / 11	CVS PHARMACY	2222 GUADALUPE ST	TX ASBESTOS, TX Ind. Haz Waste	66	0.013	West
1045 / 11	ADAMS HENRY J	1900 SPEEDWAY	EDR Hist Auto	67	0.013	ENE
CA1046 / 11	JONES JOHN H CLOTH	2214 GUADALUPE ST	EDR Hist Cleaner	67	0.013	West
BX1047 / 11	RIO GRANDE GAS	701 W 24TH	EDR Hist Auto	67	0.013	East
BM1054 / 11	RITTERS SERVICE STAT	2718 GUADALUPE ST	EDR Hist Auto	67	0.013	WSW
BM1055 / 11	GASKINS REAL ESTATE	2718 GUADALUPE ST	TX LPST, TX UST, TX HIST UST	67	0.013	WSW
1058 / 11	CAMPUS SHOP CLNRS	2332 GUADALUPE ST	EDR Hist Cleaner	68	0.013	West
DC1059 / 11	GHOST TANK	501 WEST AVE.	TX HIST UST	68	0.013	WNW
DC1060 / 11	5TH AND WEST	501 WEST AVE	TX TANKS, TX RDR, TX CENTRAL REGISTRY	68	0.013	WNW
CA1064 / 11	T CLEANING & PRESSIN	2206 GUADALUPE ST	EDR Hist Cleaner	68	0.013	West
HY1068 / 11	2800 02 SMITH J J GA	2800 GUADALUPE ST	EDR Hist Auto	68	0.013	WSW
HY1069 / 11	TACO BELL	2800 GUADALUPE ST	TX HIST UST	68	0.013	WSW
HY1082 / 11	DIRTY MARTINS PLACE	2808 GUADALUPE ST	TX UST	69	0.013	WSW
HY1083 / 11	DIRTY MARTINS PLACE	2808 GUADALUPE	TX RDR	69	0.013	WSW
DF1085 / 11	RIOS BROS TAILORS	115 7TH W	EDR Hist Cleaner	69	0.013	ESE
DS1089 / 11	AUSTIN AMERICAN STAT	308 GUADALUPE	RCRA NonGen / NLR, TX Ind. Haz Waste	69	0.013	WNW
BN1090 / 11	C BYRD ROY CLN NO 2	2610 GUADALUPE ST	EDR Hist Cleaner	70	0.013	West
BV1094 / 11	LONGHORN TAILOR SHOP	2424 GUADALUPE ST	EDR Hist Cleaner	70	0.013	West
IG1096 / 11	WILLIAMS WESS	2102 GUADALUPE	EDR Hist Cleaner	70	0.013	West
IH1099 / 11	MASON STEAM LNDRY	2006 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
DH1104 / 11	DICKERSON CLEANING	111 6TH W	EDR Hist Cleaner	71	0.013	NNE
IH1105 / 11	UNIVERSITY CLNS	2004 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
BV1107 / 11	UNIVERSITY SERVICE C	2412 GUADALUPE	EDR Hist Auto	71	0.013	West
DH1117 / 11	NEWSOME FRED C CLNR	106 6TH W	EDR Hist Cleaner	71	0.013	NNE
IH1118 / 11	WILLIAMS WESS	2014 SPEEDWAY	EDR Hist Cleaner	71	0.013	East
DH1120 / 11	PARIS CLEANING PARLO	102 6TH W	EDR Hist Cleaner	71	0.013	NNE
DH1122 / 11	SMITH KELLEY TAILOR	109 6TH W	EDR Hist Cleaner	72	0.014	NNE
DN1131 / 11	LATTIMORE CLEANERS	129 6TH E	EDR Hist Cleaner	73	0.014	NNE
BU1132 / 11	REYES CLNS	2504 GUADALUPE ST	EDR Hist Cleaner	73	0.014	West
DP1135 / 11	MAJESTIC CLNRS	219 6TH E	EDR Hist Cleaner	73	0.014	NNE
DP1136 / 11	MAJESTIC CLEANERS GR	219 6TH ST E	EDR Hist Cleaner	73	0.014	NNE
CV1145 / 11	HOME STEAM LAUNDRY	120 E 10TH ST	TX HIST UST	74	0.014	WNW
EF1147 / 11	BUD FOWLER	201 S 1ST ST	TX HIST UST	74	0.014	SSE
DP1158 / 11	KLUGE M C AUTO REPR	214 6TH E	EDR Hist Auto	75	0.014	NNE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
DF1161 / 11	RIOS ALPHONSO TAILO	706 CONGRESS AVE	EDR Hist Cleaner	75	0.014	ESE
1162 / 11	COLLEGE HOUSES	707 W. 21ST ST	US BROWNFIELDS, FINDS	75	0.014	East
DM1172 / 11	TOLSON OIL CO NO	409 E 7TH ST	EDR Hist Auto	76	0.014	NNE
EE1173 / 11	SCHWABE AUTOMOTIVE R	104 TRINITY ST	EDR Hist Auto	76	0.014	WNW
EE1174 / 11	GLENNS GARAGE	104 TRINITY ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	76	0.014	WNW
DU1175 / 11	REID GEO W AUTO	503 NECHES	EDR Hist Auto	76	0.014	SW
DX1176 / 11	CITY OF AUSTIN	411 W 2ND ST	RCRA NonGen / NLR, FINDS, ECHO	76	0.014	WNW
DX1177 / 11	DEPT OF PUBLIC WORKS	411 W 2ND ST	TX Ind. Haz Waste	76	0.014	WNW
DH1178 / 11	MARY LEE COMMUNITY	600 CONGRESS AVE	US BROWNFIELDS, FINDS	76	0.014	ESE
DH1179 / 11	BONILLA JOHN TAILOR	600 CONGRESS AVE	EDR Hist Cleaner	76	0.014	ESE
IK1183 / 11	GULF COAST COALITION	816 CONGRESS AVE	EDR Hist Auto	76	0.014	ESE
IK1184 / 11	HONG WAH CHINESE LAU	804 CONGRESS AVE	EDR Hist Cleaner	76	0.014	ESE
IL1189 / 11	AVS FOOD SERVICE INC	611 NECHES	EDR Hist Auto	77	0.015	NE
DU1192 / 11	JOHNSON J W SERVICE	510 E 5TH ST	EDR Hist Auto	79	0.015	SW
DU1193 / 11	TEXAS CO.	510 E 5TH ST	TX HIST UST	79	0.015	SW
IL1194 / 11	TIP TOP GARAGE AUTO	604 NECHES	EDR Hist Auto	79	0.015	SSW
1198 / 11	BOWLES GARAGE AUTO R	306 INTERREGIONAL HW	EDR Hist Auto	79	0.015	ESE
DQ1208 / 11	SCHEUMACK & HART TA	314 6TH E	EDR Hist Cleaner	81	0.015	NNE
DQ1209 / 11	SANCHEZ BROS CLO CLN	312 6TH E	EDR Hist Cleaner	81	0.015	NNE
HU1210 / 11	UNIVERSITY TOGGERY M	2310 GUADALUPE ST	EDR Hist Cleaner	81	0.015	West
DR1214 / 11	VACANT BUILDING	508 E. 6TH ST.	TX HIST UST	81	0.015	SW
DR1215 / 11	BOOTHE PROPERTY VACA	508 E 6TH ST	TX LPST	81	0.015	SW
DR1216 / 11	TERRY E BOOTH	508 E 6TH ST	TX UST	81	0.015	SW
DR1217 / 11	FORMER UST FACILITY	508 E. 6TH	TX HIST UST	81	0.015	SW
DR1218 / 11	A. W. HARRIS	508 E 6TH ST	TX HIST UST	81	0.015	SW
DR1219 / 11	S. FERRIS	508 E 6TH ST	TX HIST UST	81	0.015	SW
DQ1224 / 11	PASSON FRED W C TAI	407 6TH E	EDR Hist Cleaner	81	0.015	NNE
DQ1225 / 11	LUDWIG ROBERT TAILO	406 6TH E	EDR Hist Cleaner	81	0.015	NNE
IP1226 / 11	SMITH DEE 0 TAILOR	410 6TH E	EDR Hist Cleaner	81	0.015	NNE
DQ1228 / 11	SMITH A T DCLO PRESS	318 6TH E	EDR Hist Cleaner	82	0.016	NNE
IP1229 / 11	DATSON ISHMAEL C DCL	412 6TH E	EDR Hist Cleaner	82	0.016	NNE
DU1235 / 11	AUSTIN CAT & DOG HOS	506 E 5TH ST	TX LPST, TX UST, TX HIST UST, TX GCC	83	0.016	SW
IP1237 / 11	WING KEE	418 6TH E	EDR Hist Cleaner	83	0.016	NNE
DU1238 / 11	CHAS WOLF & O.G. WOL	535 E 5TH ST	TX HIST UST	83	0.016	WSW
DY1242 / 11	ELLIOTT CARL L	300 CONGRESS AVE	EDR Hist Auto	83	0.016	NNE
DE1245 / 11	THOMPSON BILL INC	417 6TH W	EDR Hist Auto	83	0.016	WNW
IP1246 / 11	FELTON B F C CLDO	422 6TH E	EDR Hist Cleaner	84	0.016	NNE
BO1257 / 11	SHAFER C D SERVICE S	2600 GUADALUPE	EDR Hist Auto	86	0.016	West
BO1258 / 11	7 ELEVEN 16996	2600 GUADALUPE	TX RDR	86	0.016	West

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
BO1259 / 11	7-ELEVEN 16996	2600 GUADALUPE ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	86	0.016	West
CP1264 / 11	AUTOMATIC TRANS	1300 CONGRESS AVE	EDR Hist Auto	87	0.016	WNW
IG1265 / 11	WILLIAMS WESS	2100 GUADALUPE ST	EDR Hist Cleaner	87	0.016	West
BV1270 / 11	COZY CLEANING AND	2402 GUADALUPE ST	EDR Hist Cleaner	88	0.017	West
1271 / 11	W HOTEL BLOCK 21	200 LAVACA ST	TX HIST UST, TX NPDES	88	0.017	SSW
BS1272 / 11	LONGHORN CLEANERS	2538 GUADALUPE	EDR Hist Cleaner	88	0.017	West
DA1275 / 11	KORNFUEHRER TEXACO S	701 6TH ST W	EDR Hist Auto	89	0.017	WNW
DA1276 / 11	KORNFUEHRER TEXACO S	701 6TH ST W	EDR Hist Auto	89	0.017	WNW
DA1277 / 11	AUSTIN GOODYEAR CO	701 6TH W	EDR Hist Auto	89	0.017	WNW
CB1279 / 11	BROWN JACK CLEANERS	2026 GUADALUPE ST	EDR Hist Cleaner	90	0.017	West
IH1284 / 11	VARSITY PRESSING SHO	2105 SPEEDWAY	EDR Hist Cleaner	91	0.017	East
CV1286 / 11	HOME STEAM	118 10TH E	EDR Hist Cleaner	91	0.017	WNW
EH1287 / 11	CHRISTIES CONOCO SER	400 BARTON SPRINGS R	EDR Hist Auto	92	0.017	SE
EH1288 / 11	CHTRISTIES CONOCO	400 BARTON SPRINGS R	EDR Hist Auto	92	0.017	SE
IH1289 / 11	UNIVERSITY CLEANING	2109 SPEEDWAY	EDR Hist Cleaner	92	0.017	East
CB1290 / 11	ST. AUSTIN CATHOLIC	2010 GUADALUPE ST.	TX HIST UST, TX ASBESTOS	93	0.018	West
IK1291 / 11	TROY BRANCH AUSTIN	806 CONGRESS AVE	EDR Hist Cleaner	93	0.018	ESE
CJ1292 / 11	AUSTIN MOTORCYCLE CO	1611 GUADALUPE ST	EDR Hist Auto	93	0.018	ESE
CJ1293 / 11	PETRICK FACILITY	1611 GUADALUPE ST	TX UST, TX HIST UST	93	0.018	ESE
DI1294 / 11	AMERICAN CLEANERS		PFAS ECHO	93	0.018	ESE
DE1297 / 11		405 W 6TH	TX HIST UST	94	0.018	WNW
EA1298 / 11	DEAN JOHNSTON	207 SAN JACINTO BLVD	TX UST	94	0.018	SSW
DD1305 / 11	PIT STOP INC THE AUT	700 5TH ST W	EDR Hist Auto	95	0.018	WNW
1306 / 11	TEXAS PUBLIC SERVICE	150 E. 6TH ST.	TX HIST UST	95	0.018	NNE
EB1309 / 11	N W COR GOAD MOTOR	104 GUADALUPE	EDR Hist Auto	95	0.018	ESE
CB1310 / 11	BYRD ROY CLEANERS	2002 GUADALUPE ST	EDR Hist Cleaner	95	0.018	West
DF1312 / 11	DRISKILL HOTEL	121 7TH E	EDR Hist Cleaner	97	0.018	WNW
1313 / 11	SERVICE STATION	2500 SPEEDWAY	EDR Hist Auto	97	0.018	East
IV1314 / 11	SPEEDWAY CLEANERS	2608 SPEEDWAY	EDR Hist Cleaner	98	0.019	East
IW1319 / 11	GULF REFG CO STA NO	26 GUADALUPE ST	EDR Hist Auto	99	0.019	NNE
DY1320 / 11	LAWSHA LEE DCLO CLNR	215 CONGRESS AVE	EDR Hist Cleaner	99	0.019	SSW
IX1324 / 11	RIVERSIDE SERVICE ST	207 CONGRESS AVE S	EDR Hist Auto	100	0.019	WNW
DW1328 / 11	CENTRAL LIBRARY	710 W. CESAR CHAVEZ	TX HIST UST	100	0.019	West
1329 / 11	CHAMBERS	1025 CONGRESS AVE	EDR Hist Cleaner	101	0.019	ESE
IY1330 / 11	TOM D. SMITH	307 W 10TH ST	TX HIST UST	101	0.019	ESE
DR1338 / 11	CASTRO CLEANERS	502 E 6TH ST	EDR Hist Cleaner	102	0.019	SW
DR1339 / 11	CASTRO'S CLEANERS	502 EAST 6TH STREET	RCRA NonGen / NLR, US AIRS, FINDS, ECHO	102	0.019	SW
DR1340 / 11	CASTROS CLEANERS	502 E 6TH ST	TX HIST UST, TX ASBESTOS, TX Ind. Haz Wa...	102	0.019	SW
CK1345 / 11	GUTHRIE J C	1712 CONGRESS AVE	EDR Hist Cleaner	103	0.020	ESE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DY1354 / 11	SCHRAMM SINCLAIR	301 CONGRESS AVE	EDR Hist Auto	104	0.020	NNE
DA1355 / 11	KORNFUEHRER SERV	704 6TH W	EDR Hist Auto	105	0.020	WNW
DF1357 / 11	DRISKILL LNDRY	119 7TH E	EDR Hist Cleaner	106	0.020	WNW
DF1358 / 11	MOTOR INN	118 7TH E	EDR Hist Auto	106	0.020	WNW
DB1359 / 11	HARRIS A L AUTO REPR	119 8TH E	EDR Hist Auto	106	0.020	WNW
IW1371 / 11	TENNISON PROPERTIES	19TH GUADALUPE	EDR Hist Auto	106	0.020	NNE
1378 / 11	FIRE STATION 3	201 W 30TH ST	TX UST	106	0.020	ENE
DI1379 / 11	JACK STABLEFORD PONT	311 W 5TH ST	TX HIST UST	107	0.020	ESE
DH1381 / 11	LINZ NICK TAILOR	611 CONGRESS AVE E	EDR Hist Cleaner	108	0.020	NNE
JA1382 / 11	HUMBLE OIL & REFG	800 12TH W	EDR Hist Auto	109	0.021	WNW
JA1383 / 11	BREWER SERVICE	801 12TH W	EDR Hist Auto	109	0.021	WNW
CW1384 / 11	WESLEY G M DCLO CLNR	913 CONGRESS AVE	EDR Hist Cleaner	109	0.021	WNW
CW1385 / 11		913 CONGRESS	TX HIST UST	109	0.021	WNW
JB1387 / 11	KOFAHL CHRIS BARBER	911 CONGRESS ST	EDR Hist Cleaner	109	0.021	WNW
1388 / 11	STATE OF TEXAS PRESE	TEXAS STATE CAPITOL	RCRA NonGen / NLR	110	0.021	ESE
JC1394 / 11	GREEN WATER TREATMEN	600 W. CESAR CHAVEZ	TX VCP, TX GCC, TX IOP, TX TIER 2, TX IH...	110	0.021	ENE
CY1396 / 11	PAUL O. SIMMS CO	316 W 8TH ST	TX HIST UST	112	0.021	ESE
CY1397 / 11	JOE E. ROBINSON, JR.	316 W 8TH ST	TX HIST UST	112	0.021	ESE
DB1398 / 11	LINZ GUST B CLNR	809 CONGRESS AVE	EDR Hist Cleaner	112	0.021	WNW
DB1400 / 11	VIP CLEANERS	805 N CONGRESS	EDR Hist Cleaner	112	0.021	WNW
DI1401 / 11	AMERICAN CLEANERS	309 W 5TH	RCRA NonGen / NLR, FINDS, ECHO	112	0.021	ESE
DI1402 / 11	FORMER AMERICAN CLEA	309-311 WEST 5TH ST	TX PRIORITYCLEANERS, TX GCC	112	0.021	ESE
DI1403 / 11	UNITED STATES CLEANE	309 W 5TH ST	EDR Hist Cleaner	112	0.021	ESE
DI1404 / 11	AMERICAN CLEANERS FA	309 W 5TH ST	TX VCP, TX Ind. Haz Waste	112	0.021	ESE
IK1407 / 11	PEARL STEAM LAUNDRY	819 CONGRESS AVE	EDR Hist Cleaner	113	0.021	WNW
IK1408 / 11	TEXACO WINDPOWER CO	823 CONGRESS AVE 515	EDR Hist Auto	113	0.021	WNW
DF1409 / 11	RAPP BROS NEWS DLR A	617 CONGRESS AVE	EDR Hist Cleaner	113	0.021	WNW
DT1410 / 11	O. A. TIROFF	610 E 6TH ST	TX HIST UST	113	0.021	NE
DU1411 / 11	FINLEY	509 E 5TH ST	TX LPST, TX UST, TX HIST UST	114	0.022	SW
DF1416 / 11	RAPP BROS NEWS DLRS	621 CONGRESS AVE	EDR Hist Cleaner	114	0.022	WNW
DF1422 / 11	PATTONS AUTO HOTEL	116 7TH E	EDR Hist Auto	115	0.022	WNW
DU1423 / 11	A.E. MASSENGALE	507 E 5TH ST	TX HIST UST	115	0.022	SW
JE1426 / 11	LYNDON B JOHNSON BUI	111 E 17TH ST	TX AST	117	0.022	ESE
JE1427 / 11	COMPTROLLER OF PUBLI	111 E 17TH ST	RCRA NonGen / NLR, FINDS, ECHO	117	0.022	ESE
JE1428 / 11	COMPTROLLER OF PUBLI	111 E 17TH ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	117	0.022	ESE
1429 / 11	STADIUM DRY CLEANERS	2107 SPEEDWAY	EDR Hist Cleaner	117	0.022	East
DY1430 / 11	WARDROBE CLNRS	213 CONGRESS AVE	EDR Hist Cleaner	118	0.022	SSW
DY1431 / 11	MOTORCYCLE SALES	213 CONGRESS AVE	EDR Hist Auto	118	0.022	SSW
CV1437 / 11	MODEL STEAM LAUNDRY	112 10TH E	EDR Hist Cleaner	118	0.022	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
DM1439 / 11	BEAR AUTOMOTIVE I EP	405 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1440 / 11	BEAR AUTOMOTIVE REPR	405 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1441 / 11	ELLIOTTS RADIATOR	406 7TH E	EDR Hist Auto	119	0.023	NNE
DM1442 / 11	ELLIOTTS RADIATOR SH	406 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1443 / 11	ONE DAY CLNS	407 7TH E	EDR Hist Cleaner	119	0.023	NNE
DM1444 / 11	GAS MART GR	409 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1445 / 11	AUTO REPAIRS CO	408 7TH E	EDR Hist Auto	119	0.023	NNE
DM1446 / 11	JENSENS HARRY AUTO R	408 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1447 / 11	ALANIZ LOUIS AUTO RE	408 7TH ST E	EDR Hist Auto	119	0.023	NNE
DM1448 / 11	GAS A TERIA INC	409 7TH E	EDR Hist Auto	119	0.023	NNE
DM1456 / 11	ELLIS & SALAZAR GARA	403 7TH ST E	EDR Hist Auto	120	0.023	NNE
DM1457 / 11	ELLIS BATTERY & AUTO	403 7TH E	EDR Hist Auto	120	0.023	NNE
JH1458 / 11	RAVENS GARAGE	605 RED RIVER CT	EDR Hist Auto	120	0.023	NE
JI1464 / 11	CHESNUTT CLNRS	103 18TH W	EDR Hist Cleaner	121	0.023	ESE
DJ1467 / 11	DRISKILL HOTEL ALLEY	604 BRAZOS ST	TX HIST UST, TX NON REGIST PST	121	0.023	SSW
DF1468 / 11	METZENTHIN BROS AUTO	102 7TH W	EDR Hist Auto	121	0.023	ESE
DF1469 / 11	RIOS FRANK TAILOR	103 7TH W	EDR Hist Cleaner	121	0.023	ESE
DU1472 / 11	SANDGARTENS SERVICE	510 RED RIVER CT	EDR Hist Auto	122	0.023	NE
JL1477 / 11	WILLIAM B TRAVIS	1701 CONGRESS AVE	TX UST, TX HIST UST	123	0.023	WNW
JL1478 / 11	WILLIAM TRAVIS STATE	1701 CONGRESS AVE	TX RDR	123	0.023	WNW
JL1479 / 11	RAILROAD COMMISSION	1701 CONGRESS AVE	EDR Hist Auto	123	0.023	WNW
DG1481 / 11	SWEET CLEANERS	613 CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	123	0.023	West
DG1482 / 11	SWEET CLEANERS	613 CONGRESS AVE	TX ASBESTOS, TX DRYCLEANERS, TX Ind. Haz...	123	0.023	West
DG1483 / 11	SWEET ONE HOUR	613 CONGRESS AVE	EDR Hist Cleaner	123	0.023	West
DN1484 / 11	JOE SING CHINESE LAU	104 E 6TH ST	EDR Hist Cleaner	124	0.023	NNE
DB1486 / 11	ROSENTRITT H L GA	115 8TH E	EDR Hist Auto	124	0.023	WNW
DB1487 / 11	DAY R L GARAGE AUTO	114 8TH E	EDR Hist Auto	124	0.023	WNW
EH1488 / 11	401 S. 1ST ST PROJEC	401 S. 1ST ST.	TX HIST UST	124	0.023	NW
EH1489 / 11	N/A	401 S FIRST STREET	TX RDR	124	0.023	NW
DF1491 / 11	DAY R L AUTO REPR	114 7TH E	EDR Hist Auto	124	0.023	WNW
DA1498 / 11	LOTT C G FILL STA	711 6TH W	EDR Hist Auto	125	0.024	WNW
CV1506 / 11	EXXON MOBIL CORP	1005 CONGRESS AVE ST	EDR Hist Auto	128	0.024	ESE
JO1507 / 11	TRAVIS COUNTY	705 E 14TH ST STE B1	RCRA NonGen / NLR, FINDS, ECHO	128	0.024	ESE
JO1508 / 11	TRAVIS COUNTY MEDICA	705 E 14TH ST STE B1	TX Ind. Haz Waste	128	0.024	ESE
DY1510 / 11	R & R SERVICE STA FI	214 CONGRESS AVE	EDR Hist Auto	128	0.024	SSW
DC1511 / 11	S.B. RICKS	801 W 5TH ST	TX HIST UST	129	0.024	WNW
DF1516 / 11	RIOS FRANK TAILOR	101 7TH W	EDR Hist Cleaner	130	0.025	ESE
DB1517 / 11	PAGE S F DCLO CLNR	802 CONGRESS AVE E	EDR Hist Cleaner	131	0.025	ESE
DR1520 / 11	CURTIS GARAGE	602 NECHES ST	EDR Hist Auto	131	0.025	SW

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
DF1522 / 11	ROYAL THE CLNRS	703 CONGRESS AVE	EDR Hist Cleaner	131	0.025	WNW
DA1523 / 11	ALFA OF AUSTIN	510 RIO GRANDE ST	EDR Hist Auto	131	0.025	WNW
JB1525 / 11	WESLEY G M DCLO CLNR	913 CONGRESS AVE E	EDR Hist Cleaner	132	0.025	ESE
CD1528 / 11	FORMER TEXAC0	1900 GUADALUPE	TX RDR	133	0.025	West
CD1529 / 11	TEXACO	1900 GUADALUPE ST	TX UST, TX HIST UST, TX Financial Assura...	133	0.025	West
CD1530 / 11	TEXACO	1900 GUADALUPE ST	TX LPST, TX Ind. Haz Waste	133	0.025	West
CD1531 / 11	CAMPBELL A B SERVICE	1900 GUADALUPE	EDR Hist Auto	133	0.025	West
CD1532 / 11	TEXAS TAILOR SHOP	1900 GUADALUPE ST	EDR Hist Cleaner	133	0.025	West
CD1533 / 11	TEXACO STATION	1900 GUADALUPE	TX RDR	133	0.025	West
CD1534 / 11	STAR ENTERPRISES	1900 GUADALUPE ST	RCRA NonGen / NLR, FINDS, ECHO	133	0.025	West
DR1535 / 11	CASTROS CLEANERS	502 6TH ST E	EDR Hist Cleaner	133	0.025	NE
DR1536 / 11	SANCHEZ BROS DCLO CL	502 6TH E	EDR Hist Cleaner	133	0.025	NE
DR1537 / 11	HOOVER CLEANERS GR 8	502 6TH ST E	EDR Hist Cleaner	133	0.025	NE
DF1542 / 11	DAY R L AUTO REPR	112 7TH E	EDR Hist Auto	133	0.025	WNW
DF1543 / 11	DRISKILL STEAM LAUN	113 7TH E	EDR Hist Cleaner	133	0.025	WNW
DB1544 / 11	HONG LEE LAUNDRY	113 8TH E	EDR Hist Cleaner	133	0.025	WNW
DA1546 / 11	COTHRONS TEXACO SERV	701 W 6TH ST	TX LPST, TX UST, TX HIST UST	133	0.025	WNW
DA1547 / 11	KORNFUEHRER TEXACO S	701 W 6TH ST	EDR Hist Auto	133	0.025	WNW
1550 / 11	UT AUSTIN MAIN CAMPU		PFAS RCRA MANIFEST	134	0.025	East
CV1551 / 11	DAVIS & CO TAILORS	1008 CONGRESS AVE	EDR Hist Cleaner	134	0.025	ESE
DA1554 / 11	MASON IRA SERV STA	713 6TH W	EDR Hist Auto	134	0.025	WNW
JP1555 / 11	LITTLEFIELD PARKING	508 BRAZOS ST	TX VCP, TX GCC	134	0.025	SSW
JP1556 / 11	DELZELL & DEMENT AUT	508 BRAZOS ST	EDR Hist Auto	134	0.025	SSW
BW1557 / 11	DARES HUMBLE SERV	700 24TH W	EDR Hist Auto	135	0.026	West
JQ1558 / 11	GRAYBURG OIL CO STA	1601 CONGRESS AVE E	EDR Hist Auto	135	0.026	ESE
DY1559 / 11	AUSTIN AMERICAN STAT	305 CONGRESS AVE	TX Ind. Haz Waste	135	0.026	NNE
DQ1560 / 11	AUSTIN MOTOR SALES C	503 SAN JACINTO ST	EDR Hist Auto	135	0.026	SSW
BW1562 / 11	HICKMAN HUMBLE SERVI	700 W 24TH ST	EDR Hist Auto	135	0.026	East
DG1565 / 11	LINZ NICK TAILOR	611 CONGRESS AVE	EDR Hist Cleaner	135	0.026	WSW
CK1569 / 11	GUTHTLRIE J C DCLO C	1712 CONGRESS AVE E	EDR Hist Cleaner	136	0.026	ESE
DR1576 / 11	G F DURDEN C	504 6TH E	EDR Hist Cleaner	136	0.026	NE
BW1577 / 11	KWIK WASH COIN LAUND	704 24TH ST W	EDR Hist Cleaner	136	0.026	East
IX1583 / 11	MAGNOLIA PETROLEUM	220 CONGRESS AVE S	EDR Hist Auto	137	0.026	WNW
IX1584 / 11	WILLIAMS MOTOR INC	200 S CONGRESS AVE	TX HIST UST	137	0.026	NNE
IX1585 / 11	W.A. STEPHENS	200 S CONGRESS AVE	TX HIST UST	137	0.026	NNE
DR1589 / 11	DOYLE DARBY TAILOR	506 6TH E	EDR Hist Cleaner	138	0.026	NE
DQ1590 / 11	C. O. LANDAHL	300 E 6TH ST	TX HIST UST	139	0.026	NNE
DP1596 / 11	CUNNINGHAM & VOSS	218 E 6TH ST	TX HIST UST	139	0.026	NNE
CX1598 / 11	ALL-PRO CLEANERS INC	602 W 7TH ST	EDR Hist Cleaner	139	0.026	ESE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DF1599 / 11	AUSTIN STEPHEN F HOT	102 7TH E	EDR Hist Cleaner	140	0.027	ESE
BW1600 / 11	AUSTIN LAUNDRY & DRY	608 W 24TH ST	EDR Hist Cleaner	140	0.027	East
DN1601 / 11	DANNY LITTLE	106 E 6TH STREET	TX RDR	140	0.027	NNE
DN1602 / 11	LITTLEFIELD DRISKILL	106 E 6TH ST	TX LPST, TX VCP, TX ASBESTOS, TX GCC	140	0.027	NNE
DN1603 / 11	LITTLEFIELD BUILDING	106 E 6TH ST	TX HIST UST	140	0.027	NNE
DN1604 / 11	LITTLEFIELD BLDING I	106 E 6TH ST	TX HIST UST	140	0.027	NNE
IX1609 / 11	J.V. SIEGMUND	228 S CONGRESS AVE	TX HIST UST	140	0.027	WNW
IX1610 / 11	LACKIE CONSTRUCTION	228 S CONGRESS AVE	TX HIST UST	140	0.027	WNW
EE1612 / 11	ACME CLEANERS	320 1ST E	EDR Hist Cleaner	141	0.027	WNW
DA1613 / 11	AUSTIN LACQUER COMPA	604 W 6TH ST	EDR Hist Auto	141	0.027	ESE
DA1614 / 11	C VAN R AUTOMOTIVE	604 W 6TH ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	141	0.027	ESE
JI1615 / 11	GULF REFG CO STA NO	1811 CONGRESS AVE E	EDR Hist Auto	141	0.027	ESE
1616 / 11		422 E 6TH ST	TX HIST UST	141	0.027	SSW
DB1617 / 11	OHENRY GAR	110 8TH E	EDR Hist Auto	142	0.027	WNW
DF1619 / 11	CASH AND CARRY	111 7TH E	EDR Hist Cleaner	142	0.027	WNW
JT1622 / 11	YOUNG & PRATT	702 E 3RD ST	TX UST, TX ASBESTOS	142	0.027	WNW
JT1623 / 11	C. G. PURYEAR	702 E 3RD ST	TX HIST UST	142	0.027	WNW
JT1624 / 11	YOUNG & PRATT	702 E 3RD ST	TX HIST UST	142	0.027	WNW
CZ1625 / 11	PAGE SOUTHERLAND PAG	606 WEST AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	142	0.027	WNW
DR1626 / 11	STEVENSON J C C DCLO	510 6TH E	EDR Hist Cleaner	143	0.027	NE
DR1627 / 11	AXLE & WHEEL ALIGN	510 6TH E	EDR Hist Auto	143	0.027	NE
DR1628 / 11	VACANT 2 CASTROS CLE	511 6TH ST E	EDR Hist Cleaner	143	0.027	NE
DC1629 / 11	803 05 DEPENDABLE MT	803 5TH W	EDR Hist Auto	143	0.027	WNW
DC1630 / 11	DEPENDABLE MOTORS IN	803 5TH ST W	EDR Hist Auto	143	0.027	WNW
1631 / 11	BOZEMAN & HAGOOD SER	1811 CONGRESS AVE	EDR Hist Auto	144	0.027	WNW
CO1632 / 11	AUSTIN COMMUNITY COL	1212 RIO GRANDE ST	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	144	0.027	WNW
IV1635 / 11	THE UNIVERSITY OF TE	2617 SPEEDWAY STE 10	TX SPILLS, TX Ind. Haz Waste	144	0.027	East
IV1636 / 11	THE UNIVERSITY OF TE	2617 SPEEDWAY STE 10	RCRA-LQG, PADS, NY MANIFEST	144	0.027	East
IV1637 / 11	MAIN CAMPUS	2617 SPEEDWAY STE 10	TX IHW CORR ACTION	144	0.027	East
JV1638 / 11	CITY OF AUSTIN	654 W CESAR CHAVEZ S	TX HIST UST	145	0.027	ENE
JV1639 / 11	COA	654 W CESAR CHAVEZ S	TX HIST UST	145	0.027	ENE
JI1645 / 11	1801 03 DYE SLS & SE	1801 CONGRESS AVE	EDR Hist Auto	145	0.027	WNW
DR1646 / 11	GALVAN IGNACIO CLDO	512 6TH E	EDR Hist Cleaner	145	0.027	NE
DR1647 / 11	SHARPS SERVICE STA	512 6TH E	EDR Hist Auto	145	0.027	NE
IL1648 / 11	D & S SERVICE STATIO	500 7TH ST E	EDR Hist Auto	146	0.028	NNE
IL1649 / 11	D&S SERV STA	500 7TH E	EDR Hist Auto	146	0.028	NNE
IL1650 / 11	D & S SERVICE STATIO	500 7TH ST E	EDR Hist Auto	146	0.028	NNE
IP1652 / 11	LUDWIG ROBERT W TAIL	402 E 6TH ST	EDR Hist Cleaner	146	0.028	NNE
BV1653 / 11	FERDINANDTSEN G E N	2406 GUADALUPE ST	EDR Hist Cleaner	146	0.028	West

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
DL1654 / 11	M.H. CROCKETT	306 W WEST 29TH ST	TX HIST UST	146	0.028	WNW
CV1655 / 11	BIGGS & CO TAILORS	1007 CONGRESS AVE E	EDR Hist Cleaner	146	0.028	ESE
DC1656 / 11	C.B. SMITH MOTORS	805 W 5TH ST	TX HIST UST	147	0.028	WNW
DC1657 / 11	AUSTIN TOYOTA	1127 W 6TH STREET	TX LPST, TX UST, TX VCP, RCRA NonGen / N...	147	0.028	WNW
DC1658 / 11	AUSTIN TOYOTA INC	805 W 5TH ST	TX HIST UST	147	0.028	WNW
DR1659 / 11	ATTAL THOS SHOE REPR	515 6TH E	EDR Hist Cleaner	147	0.028	NE
DA1660 / 11	COTHRAN'S TEXACO	700 W 6TH ST	TX HIST UST	147	0.028	ESE
CV1661 / 11	BIGGS & CO TAILOR	1007 CONGRESS AVE	EDR Hist Cleaner	147	0.028	WNW
CV1662 / 11	BOBS GARAGE &	1007 CONGRESS AVE	EDR Hist Auto	147	0.028	WNW
DA1663 / 11	DEEP EDDY RUG & CARP	512 RIO GRANDE ST	EDR Hist Cleaner	148	0.028	WNW
DA1664 / 11	SPRINKLES BODY SHOP	512 RIO GRANDE	EDR Hist Auto	148	0.028	WNW
DA1665 / 11	BEE BOP PRINTING	512 RIO GRANDE ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	148	0.028	WNW
DL1666 / 11	COA SERVICE CENTER #	300 WEST AVE	TX HIST UST	148	0.028	WNW
DL1667 / 11	ELECTRIC UTILITY	300 WEST AVE	TX LPST, TX Ind. Haz Waste	148	0.028	WNW
DL1668 / 11	POLE YARD	300 WEST AVE	RCRA NonGen / NLR, FINDS, ECHO	148	0.028	WNW
DL1669 / 11	AUSTIN ENERGY POLE Y	300 WEST AVE	TX VCP	148	0.028	WNW
DL1670 / 11	CITY OF AUSTIN ELECT	300 WEST AVE	TX UST	148	0.028	WNW
IL1672 / 11	CAPITAL CITY MOTOR	505 7TH ST E	EDR Hist Auto	149	0.028	NNE
CM1673 / 11	FIRST STATE BANK TOW	400 W 15TH ST STE 71	TX UST, TX HIST UST	149	0.028	WNW
CV1675 / 11	PEELER JOHN F TAILO	1003 CONGRESS AVE	EDR Hist Cleaner	149	0.028	WNW
DR1679 / 11	2 RODRIGUEZ JOS CLDO	517 6TH E	EDR Hist Cleaner	150	0.028	NE
DF1680 / 11	MASTER VALET CLNS	109 7TH E	EDR Hist Cleaner	151	0.029	WNW
DF1681 / 11	MASTER VALET CLEANER	109 7TH ST E	EDR Hist Cleaner	151	0.029	WNW
DM1684 / 11	NOWLIN R A AUTO REPR	602 TRINITY ST	EDR Hist Auto	152	0.029	SSW
IA1689 / 11	L & M GARAGE AUTO RE	301 BARTON SPRINGS R	EDR Hist Auto	152	0.029	NE
DE1691 / 11	SHIRLEY CLEANERS & H	310 W 6TH ST	EDR Hist Cleaner	153	0.029	ESE
CN1692 / 11	ROBERT E JOHNSON BUI	1501 CONGRESS AVE	TX UST, TX HIST UST	153	0.029	WNW
DB1693 / 11	108 10 12 HENRV GARA	108 8TH E	EDR Hist Auto	153	0.029	WNW
CV1700 / 11	BARKER B M AUTOMO	105 10TH E	EDR Hist Auto	155	0.029	WNW
CN1701 / 11	TEXAS EMPLOYMENT COM	101 E 15TH ST	TX UST, TX HIST UST, TX ASBESTOS	156	0.030	ESE
DR1702 / 11	CENTRAL SEWING MACH	522 6TH E	EDR Hist Auto	156	0.030	NE
JY1703 / 11	CNANO TECHNOLOGY USA	303 COLORADO ST	FINDS, ECHO, PFAS ECHO	157	0.030	NNE
JQ1704 / 11	GRAYBURG OIL CO STAT	1601 CONGRESS AVE	EDR Hist Auto	157	0.030	WNW
DJ1705 / 11	ZUAUTO PARTS LLC	701 BRAZOS ST STE 72	EDR Hist Auto	157	0.030	NNE
IL1709 / 11	MARSHALL BODY WORKS	515 7TH E	EDR Hist Auto	159	0.030	NNE
DG1710 / 11	MILLER BRESTE	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1711 / 11	GRAYBURG OIL CO.	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1712 / 11		112 E 7TH ST	TX HIST UST	159	0.030	NNE
DG1713 / 11	SCOTT & GREGG	112 E 7TH ST	TX HIST UST	159	0.030	NNE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
DG1714 / 11	MILLERS GARAGE	112 E 7TH ST	TX HIST UST	159	0.030	NNE
DR1715 / 11	ELLIS SERVICE STATIO	524 6TH E	EDR Hist Auto	160	0.030	NE
DF1717 / 11	AUSTIN STEPH F HOTEL	106 7TH E	EDR Hist Cleaner	160	0.030	ESE
DP1725 / 11	GRANT JAMES C CLNR	505 BRAZOS ST	EDR Hist Cleaner	162	0.031	SSW
IL1727 / 11	HAGOOD SERV STA	519 7TH E	EDR Hist Auto	163	0.031	NE
IL1728 / 11	HAGOOD SERVICE STATI	519 7TH ST E	EDR Hist Auto	163	0.031	NE
DV1729 / 11	AUS TEX ENGINE	304 COLORADO ST	EDR Hist Auto	163	0.031	NNE
DY1730 / 11	PACKERY CHANNEL BAIT	308 CONGRESS AVE STE	EDR Hist Auto	164	0.031	NNE
KC1731 / 11	CENTEX AUTO REPAIR	202 SAN JACINTO ST	EDR Hist Auto	165	0.031	SSW
DG1733 / 11	LINZ NICK TAILOR	607 CONGRESS AVE	EDR Hist Cleaner	166	0.031	WSW
DD1734 / 11	UNITED STATES CLEANE	601 W 5TH ST	EDR Hist Cleaner	166	0.031	ESE
1735 / 11	QUALITY CLEANERS GR	111 E 19TH ST	EDR Hist Cleaner	166	0.031	West
DP1743 / 11	SAVE WAY SERV	503 BRAZOS	EDR Hist Auto	168	0.032	SSW
JA1752 / 11	MILLNER BROS SERVICE	813 12TH W	EDR Hist Auto	170	0.032	WNW
JP1754 / 11	NUNEZ BROS TAILORS	506 BRAZOS	EDR Hist Cleaner	170	0.032	SSW
KG1755 / 11	CONSUMERS HOME ICE C	361 W 4TH ST	TX HIST UST	170	0.032	ESE
KH1756 / 11	AUSTIN MOTOR INN	207 CONGRESS AVE	EDR Hist Auto	171	0.032	SSW
KH1757 / 11		207 CONGRESS	TX HIST UST	171	0.032	SSW
1761 / 11	JAMES DREW RENTAL IN	408 N I 35	TX HIST UST	173	0.033	East
1764 / 11	ACC RIO GRANDE CAMPU	1218 WEST AVE.	TX HIST UST	174	0.033	WNW
DC1765 / 11	BELL JIM GARAGE AUTO	811 5TH ST W	EDR Hist Auto	174	0.033	WNW
1766 / 11	AUSTIN MUSIC HALL	208 NUECES ST	TX HIST UST, TX RDR	175	0.033	East
DF1767 / 11	MAJIK IRONERS INC	114 W 7TH ST	EDR Hist Cleaner	175	0.033	WNW
DP1768 / 11	VACANT PROPERTY BRAZ	501 BRAZOS ST	TX RDR	175	0.033	SSW
DP1769 / 11	BRADSHAW ED SERV	501 BRAZOS	EDR Hist Auto	175	0.033	SSW
DP1770 / 11	FORMER BANK DRIVE TH	501 BRAZOS	TX RDR	175	0.033	SSW
DP1771 / 11	5TH AND BRAZOS TOWER	501 BRAZOS ST	TX IHW CORR ACTION	175	0.033	SSW
DP1772 / 11	VACANT PROPERTY	501 BRAZOS ST	TX UST, TX HIST UST	175	0.033	SSW
KJ1773 / 11	CITY HALL ANNEX BLOC	UNKNOWN	US BROWNFIELDS, FINDS	176	0.033	ESE
DQ1774 / 11	AUSTIN BRAKE	506 TRINITY ST	EDR Hist Auto	176	0.033	SSW
DQ1775 / 11	DEAN MILLER	506 E TRINITY ST	TX HIST UST	176	0.033	SSW
JC1776 / 11	DIXIE OIL COMPANY	407 W CESAR CHAVEZ S	TX HIST UST	176	0.033	NE
KJ1778 / 11	COA - ANNEX	301 W 2ND ST	TX HIST UST	177	0.034	ESE
KJ1779 / 11	CITY OF AUSTIN EME|S	301 WEST 2ND STREET	TX HIST UST, TX ASBESTOS	177	0.034	ESE
1780 / 11	DUKES GAR REPRS	406 RED RIVER	EDR Hist Auto	177	0.034	WSW
CN1781 / 11	TEXAS HOUSE OF REPRE	105 W 15TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	177	0.034	WNW
KL1784 / 11	SOUTHWESTERN BELL TE	120 W 9TH ST	TX HIST UST	178	0.034	WNW
KL1785 / 11	SOUTHWESTERN BELL TE	120 W 9TH ST	TX HIST UST	178	0.034	WNW
DY1786 / 11	PARSLEY W L DCLO CLN	310 CONGRESS AVE	EDR Hist Cleaner	179	0.034	NNE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
1790 / 11	ROBERT HATCHETT	1004 W WEST 24TH ST	TX HIST UST	180	0.034	WNW
DJ1791 / 11	704 6 BUSTIN MC CUTC	704 BRAZOS ST	EDR Hist Auto	180	0.034	NNE
IL1793 / 11	EWINGS CONOCO SERVIC	519 E 7TH ST	EDR Hist Auto	181	0.034	NE
IL1794 / 11	MERCHANTS TRANSFER S	519 E 7TH ST	TX HIST UST	181	0.034	NE
IL1795 / 11	TWIN LIQUORS	519 E 7TH ST	TX UST	181	0.034	NE
IL1796 / 11	TWIN LIQUORS	519 E 7TH ST	TX RDR, TX CENTRAL REGISTRY	181	0.034	NE
IL1797 / 11	F. W. STERNENBERG	519 E 7TH ST	TX HIST UST	181	0.034	NE
IL1798 / 11	TWIN LIQUORS	519 E 7TH ST	TX HIST UST	181	0.034	NE
DU1799 / 11	JOHNSON J W SERVICE	510 5TH ST E	EDR Hist Auto	181	0.034	SW
DU1800 / 11	CUNNINGHAM GEO L FIL	510 5TH E	EDR Hist Auto	181	0.034	SW
DU1801 / 11	CUNNINGHAM G L	510 5TH ST E	EDR Hist Auto	181	0.034	SW
1808 / 11	AMERICAN TAXI CAB CO	408 W 11TH ST	TX HIST UST	184	0.035	WNW
DU1810 / 11	HART BUBBA SERVICE S	509 5TH E	EDR Hist Auto	185	0.035	SW
DU1811 / 11	JOHNSONS SERVICE STA	508 5TH E	EDR Hist Auto	185	0.035	SW
KH1812 / 11	WALKER J M CLDO CLNR	208 CONGRESS AVE	EDR Hist Cleaner	187	0.035	SSW
BK1814 / 11	A MASTER DICKENS CLE	2815 FRUTH ST	EDR Hist Cleaner	188	0.036	ENE
BK1815 / 11	ANN STUMPF	2815 FRUTH ST	TX UST, TX HIST UST	188	0.036	ENE
KP1818 / 11	GULF REFG CO STA NO	507 5TH ST E	EDR Hist Auto	188	0.036	SW
KP1819 / 11	HALEY MALCOLM M FILL	507 5TH E	EDR Hist Auto	188	0.036	SW
KH1824 / 11	AUSTIN RADIATOR CO	205 CONGRESS AVE	EDR Hist Auto	189	0.036	SSW
JA1825 / 11	HUMBLE OIL & REFG	816 12TH W	EDR Hist Auto	190	0.036	WNW
1826 / 11	HOME STEAM LAUNDRY	601 E 14TH ST	EDR Hist Cleaner	191	0.036	ESE
DE1827 / 11	POLAR ICE CREAM	417 W 6TH ST	TX HIST UST	191	0.036	WNW
KQ1828 / 11	VACANT BUILDING	701 E 6TH ST	TX LPST	192	0.036	ENE
DI1829 / 11	B&N AXLE SERV	314 5TH W	EDR Hist Auto	193	0.037	ESE
CZ1830 / 11	ME MORRIS FORD INCOR	808 6TH ST W	EDR Hist Auto	193	0.037	WNW
CZ1831 / 11	MC MORRIS FORD INCOR	808 6TH ST W	EDR Hist Auto	193	0.037	WNW
1832 / 11	JENSENS HARRY AUTO R	408 E 7TH ST	EDR Hist Auto	194	0.037	NNE
KR1838 / 11	GULF OIL CORPORATION	601 W 6TH ST	TX HIST UST	197	0.037	ESE
KS1839 / 11	PEARL LAUNDRY	401 1ST E	EDR Hist Cleaner	197	0.037	ESE
KS1840 / 11	REDDS HUMBLE SERV FI	401 1ST E	EDR Hist Auto	197	0.037	ESE
KT1841 / 11	AUSTIN MUNICIPAL BUI	124 W 8TH ST	TX UST, TX HIST UST	197	0.037	WNW
KU1842 / 11	OSCAR KUNTZ?	800 E CESAR CHAVEZ S	TX HIST UST	197	0.037	ESE
DI1844 / 11	MISSION CITY PONTIAC	312 5TH W	EDR Hist Auto	197	0.037	ESE
KP1846 / 11	SMITH B C TIRE SHOP	500 5TH ST E	EDR Hist Auto	198	0.038	SW
KP1847 / 11	WALLACE GARAGE AUTO	500 5TH E	EDR Hist Auto	198	0.038	SW
JA1852 / 11	ACC BOOK STORE	801 W 12TH ST	TX LPST, TX UST	199	0.038	WNW
JA1853 / 11	W.T. CASWELL	801 W 12TH ST	TX HIST UST	199	0.038	WNW
JA1854 / 11	LANE AUTO & ELECTRIC	801 12TH ST W	EDR Hist Auto	199	0.038	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
JA1855 / 11	BILL'S ACC BOOKSTORE	801 W 12TH ST	TX HIST UST	199	0.038	WNW
KR1857 / 11	FICKELS SERV STA	617 6TH W	EDR Hist Auto	201	0.038	ESE
KW1862 / 11	PERRY BROOKS BLDG	720 BRAZOS ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	203	0.038	ESE
KY1869 / 11	HAMS AUTO SERV	310 5TH W	EDR Hist Auto	204	0.039	ESE
KW1870 / 11	WILLIE FOO CHINESE L	113 E 8TH ST	EDR Hist Cleaner	205	0.039	ESE
JP1871 / 11	FOSTERS GARAGE	504 BRAZOS ST	EDR Hist Auto	205	0.039	SSW
KH1873 / 11	206-214 CONGRESS AVE	206 CONGRESS AVE	TX UST, TX HIST UST	206	0.039	SSW
KH1874 / 11	FORMER RTC PROPERTY	206 CONGRESS AVE	TX LPST	206	0.039	SSW
LA1876 / 11	COMPTROLLER OF PUBLI	111 W 6TH ST	TX Ind. Haz Waste	207	0.039	West
LA1877 / 11	COMPTROLLER OF PUBLI	111 W 6TH ST	RCRA NonGen / NLR, FINDS, ECHO	207	0.039	West
LB1878 / 11	SUPERIOR DAIRIES	600 E 1ST ST	TX LPST, TX UST, TX HIST UST	207	0.039	WNW
LB1879 / 11	FAIRMONT HOTEL	600 E CESAR CHAVEZ S	TX HIST UST, TX RDR	207	0.039	WNW
KU1880 / 11	HOWARDS CLEANERS	804 1ST E	EDR Hist Cleaner	208	0.039	ESE
KR1881 / 11	MAGNOLIA PET CO STA	615 6TH W	EDR Hist Auto	208	0.039	ESE
LC1882 / 11	TEXAS STATE ASSO OF	1000 BRAZOS ST	TX UST, TX HIST UST	209	0.040	ESE
JA1887 / 11	SMITH J B	821 12TH W	EDR Hist Cleaner	210	0.040	WNW
JY1891 / 11	AUS TEX AUTOMOTIVE S	308 COLORADO ST	EDR Hist Auto	213	0.040	NNE
LE1895 / 11	TURK EQUIPMENT	400 NUECES ST	TX UST	213	0.040	ESE
LF1896 / 11	JACK BROWN CLEANERS	615 W MARTIN LUTHER	RCRA-SQG	214	0.041	East
LF1897 / 11	JACK BROWN CLEANERS	615 W MARTIN LUTHER	TX VCP, TX APAR, TX DRYCLEANERS, TX GCC,...	214	0.041	East
LF1898 / 11	BROWN JACK CLEANERS	615 W MLK BLVD	EDR Hist Cleaner	214	0.041	East
1900 / 11	CHAMPION PROPERTIES	UNKNOWN	US BROWNFIELDS, FINDS	215	0.041	WNW
LG1901 / 11	CVS PHARMACY 7483	500 CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	216	0.041	SSW
LG1902 / 11	CVS PHARMACY 7483	500 500 CONGRESS AVE	RCRA NonGen / NLR	216	0.041	SSW
LH1903 / 11	FOUND ON SANBORN MAP	318 E 5TH ST	TX HIST UST	216	0.041	SSW
LI1904 / 11	MRS. ROBT. W. SHIPP	303 W MARTIN LUTHER	TX HIST UST	216	0.041	East
KY1907 / 11	AUSTIN WELDIN E	304 5TH ST W	EDR Hist Auto	218	0.041	ESE
KY1908 / 11	CLYDES WIDG	304 5TH W	EDR Hist Auto	218	0.041	ESE
LA1910 / 11	H. C. FRISTOE	121 W 6TH ST	TX HIST UST	218	0.041	WNW
LK1911 / 11	AMERICAN TAXI CAB CO	305 W 6TH ST	TX HIST UST	221	0.042	ESE
JA1912 / 11	TYLER F A FILL STA	823 12TH W	EDR Hist Auto	222	0.042	WNW
KR1913 / 11	REYES CLNRS	611 6TH W	EDR Hist Cleaner	222	0.042	ESE
KY1918 / 11	MARTIN DELL BRAKE	302 5TH W	EDR Hist Auto	225	0.043	ESE
IL1922 / 11	ALEX & IDA DOCHEN TR	500 E 7TH ST	TX UST	229	0.043	NNE
IL1923 / 11	D&S	500 E 7TH ST	TX HIST UST	229	0.043	NNE
IL1924 / 11	D & S SERVICE STATIO	500 E 7TH ST	EDR Hist Auto	229	0.043	NNE
IL1925 / 11	ALEX DOCHEN	500 E 7TH ST	TX HIST UST	229	0.043	NNE
IL1926 / 11	ALEX DOCHEN	500 E 7TH ST	TX HIST UST	229	0.043	NNE
KY1927 / 11	BADGER WALTER H JR F	300 5TH W	EDR Hist Auto	229	0.043	ESE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
HY1928 / 11	RREEF HEMPHILL PARK	2810 HEMPHILL PARK	TX LPST, TX GCC	230	0.044	ENE
HY1929 / 11	2810 HEMPHILL	2810 HEMPHILL PK	TX RDR	230	0.044	ENE
KH1930 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX CLI	231	0.044	SSW
KH1931 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX HIST LF	231	0.044	SSW
KH1932 / 11	PARKING LOT & BUILDI	206 CONGRESS AVE	TX CLI	231	0.044	SSW
LH1935 / 11	CADILLAC SALES COMPA	304 E 5TH ST	TX HIST UST	232	0.044	SSW
LH1936 / 11	DEEN MILLER	324 E 5TH ST	TX HIST UST	232	0.044	SSW
JA1937 / 11	AUSTIN COMMUNITY COL	800 W 12TH STREET	TX HIST UST, TX ASBESTOS	233	0.044	WNW
JA1938 / 11	GRIFFIN A C HUMBLE	800 W 12TH ST	EDR Hist Auto	233	0.044	WNW
JA1939 / 11	HUMBLE OIL & REFININ	800 W 12TH ST	TX HIST UST	233	0.044	WNW
1942 / 11	CUNNINGHAM HENRY	403 16TH ST E	EDR Hist Auto	235	0.045	WNW
LI1949 / 11	RITTERS SERVICE STAT	301 W 19TH ST	EDR Hist Auto	236	0.045	East
JY1950 / 11	CAPITOL SPRING & BRA	310 COLORADO ST	EDR Hist Auto	237	0.045	NNE
1951 / 11	CPCG AUTO TX LP	408 W 17TH ST OFC 10	EDR Hist Auto	238	0.045	WNW
DD1954 / 11	KEESES ENCO PRODUCTS	600 W 5TH	EDR Hist Auto	240	0.045	ESE
DD1955 / 11	HORIZON BANK - 600 W	600 W 5TH ST	TX HIST UST, TX CENTRAL REGISTRY	240	0.045	ESE
LE1956 / 11	NW COR WEAVER MARGT	612 4TH W	EDR Hist Cleaner	240	0.045	ESE
1958 / 11	BELL JIM AUTOS INC	201 BRAZOS ST	EDR Hist Auto	241	0.046	SSW
LS1968 / 11	COMMUNICATION SPECIA	603 DAVIS ST	TX Ind. Haz Waste	242	0.046	WNW
LS1969 / 11	COMMUNICATION SPECIA	603 DAVIS ST	RCRA NonGen / NLR, FINDS, ECHO	242	0.046	WNW
JA1970 / 11	MILLNERS SERVICE STA	827 12TH W	EDR Hist Auto	242	0.046	WNW
JE1972 / 11	MC KEAN W L R	1610 BRAZOS ST	EDR Hist Auto	243	0.046	ESE
CZ1973 / 11	OLD HUTS HAMBURGERS	807 WEST 6TH STREET	TX HIST UST, TX ASBESTOS	244	0.046	WNW
KR1974 / 11	RIVER CITY Z SHOP AU	604 6TH ST W	EDR Hist Auto	244	0.046	ESE
KR1975 / 11	PIT SHOP THE AUTO RE	604 6TH ST W	EDR Hist Auto	244	0.046	ESE
KH1977 / 11	FRY JOHN L CLOTHES	202 CONGRESS AVE	EDR Hist Cleaner	245	0.046	SSW
KS1979 / 11	SIMPSON IRA AUTO	409 1ST E	EDR Hist Auto	245	0.046	ESE
LT1980 / 11	AUSTIN LAUNDRY & DRY	304 W 15TH ST	TX HIST UST	246	0.047	ESE
LS1982 / 11	TRAMMELL CROW DAVIS	602 DAVIS ST	TX IHW CORR ACTION	246	0.047	WNW
ED1984 / 11	U T SUPERIOR DAIRIES	213 RED RIVER ST	TX HIST UST	246	0.047	WNW
KW1989 / 11	ARMY FUTURES COMMAND		DOD	247	0.047	NNE
1990 / 11	KXAN-TV	910 BRAZOS ST	TX HIST UST	249	0.047	ESE
KW1991 / 11	GULF STATES POWER LT	800 BRAZOS ST STE 40	EDR Hist Auto	249	0.047	ESE
LX1994 / 11	RUSHINGS SYLVAN W EN	800 W 6TH ST	EDR Hist Auto	251	0.048	WNW
LX1995 / 11	CHARLTON & CROCKET,	800 W 6TH ST	TX HIST UST	251	0.048	WNW
LX1996 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX HIST UST	251	0.048	WNW
LX1997 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX UST	251	0.048	WNW
LX1998 / 11	FORMER DOWNTOWN AUTO	800 W 6TH ST	TX RDR, TX CENTRAL REGISTRY	251	0.048	WNW
LX2002 / 11	RUSHINGS SYLVAN W EX	800 6TH ST W	EDR Hist Auto	254	0.048	WNW

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
LX2003 / 11	RUSHINGS SYLVAN W EN	800 6TH ST W	EDR Hist Auto	254	0.048	WNW
LX2004 / 11	HUMBLE OIL & REF CO	800 6TH W	EDR Hist Auto	254	0.048	WNW
MA2011 / 11	200 24 AVENUE SERVIC	200 CONGRESS AVE E	EDR Hist Auto	255	0.048	SSW
2012 / 11	MEYER CREAMERY COMPA	311 W 7TH ST	TX HIST UST	256	0.048	ESE
KR2019 / 11	RUCKER CASS GULF SER	601 6TH W	EDR Hist Auto	258	0.049	ESE
IL2020 / 11	GULF OIL CORPORATION	504 E 7TH ST	TX HIST UST	259	0.049	NE
JY2026 / 11	0 K GARAGE	312 COLORADO ST	EDR Hist Auto	262	0.050	NNE
ME2027 / 11	B&N AXLE SERV	219 W 4TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	263	0.050	NNE
ME2028 / 11	B&N AXLE SERV INC	219 W 4TH ST	RCRA NonGen / NLR, FINDS, ECHO	263	0.050	NNE
KY2032 / 11	TIRE SERVICE COMPANY	301 W 5TH ST	TX HIST UST	263	0.050	ESE
JY2037 / 11	ROBINSON SAML	316 COLORADO	EDR Hist Auto	264	0.050	NNE
MI2044 / 11	CAPITOL LAUNDRY 6 DR	301 W 8TH ST	EDR Hist Cleaner	265	0.050	ESE
LK2045 / 11	321 3 COVERT AUTO CO	321 6TH W	EDR Hist Auto	265	0.050	ESE
KH2046 / 11	ALAMO TRANSMISSION S	200 CONGRESS AVE	EDR Hist Auto	265	0.050	SSW
MJ2047 / 11	KEESES ENCO HUMBLE S	600 5TH ST W	EDR Hist Auto	265	0.050	ESE
MJ2048 / 11	WHEELERS ENCO HUMBLE	600 5TH ST W	EDR Hist Auto	265	0.050	ESE
MJ2049 / 11	ACME SERVICE STA	600 5TH W	EDR Hist Auto	265	0.050	ESE
LA2050 / 11	PRUDENCE BAILEY	122 W 5TH ST	TX HIST UST	267	0.051	SW
LQ2051 / 11	ROGERS & SALYER FILL	204 BARTON SPRINGS R	EDR Hist Auto	268	0.051	NE
KW2052 / 11	OCONNELL & WORLEY	201 8TH E	EDR Hist Cleaner	268	0.051	ESE
2053 / 11	NELSON CHESTER B	603 9TH W	EDR Hist Cleaner	268	0.051	ESE
2055 / 11	SAM HOUSTON BUILDING	201 E 14TH ST	TX AST	269	0.051	ESE
MJ2056 / 11	AUTOMOTIVE SPECIALIS	502 NUECES ST	EDR Hist Auto	269	0.051	ESE
MK2057 / 11	DEWEY PURYEAR	201 W CESAR CHAVEZ S	TX HIST UST	270	0.051	NNE
MM2060 / 11	MIOTORAMP STGE	713 COLORADO	EDR Hist Auto	272	0.052	WNW
KS2062 / 11	FORMER GLO FACILITY	421 E CESAR CHAVEZ S	TX UST, TX HIST UST	273	0.052	ESE
MN2063 / 11	ORIENTAL OIL COMPANY	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2064 / 11	PIERCE PETROLEUM	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2065 / 11	DAVIS BROTHERS	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MN2066 / 11	ORIENTAL OIL COMPANY	101 E CESAR CHAVEZ S	TX HIST UST	273	0.052	NNE
MK2067 / 11	SILICON LABRITORIES		PFAS ECHO	273	0.052	NNE
JH2068 / 11	601 03 GAGE BROS	601 7TH E	EDR Hist Auto	273	0.052	NE
JH2069 / 11	REDS GARAGE AUTO REP	600 7TH E	EDR Hist Auto	273	0.052	NE
KT2070 / 11	AMERICAN CLEANERS	719A COLORADO ST	TX DRYCLEANERS	273	0.052	WNW
KL2073 / 11	AUSTIN GREENWOOD CON	909 COLORADO ST	TX LPST, TX UST, TX HIST UST, TX Financi...	274	0.052	WNW
KL2074 / 11	AUSTIN GREENWOOD CON	909 COLORADO ST	TX AST	274	0.052	WNW
LF2075 / 11	BROWNS JACK CLEANERS	615 MARTIN LUTHER K	EDR Hist Cleaner	275	0.052	East
KU2076 / 11	CAMPOS MANUEL	801 1ST E	EDR Hist Auto	276	0.052	ESE
JP2079 / 11	TRAVIS COUNTY OIL	500 BRAZOS ST	EDR Hist Auto	277	0.052	SSW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2080 / 11	SCARBROUGH HOUSE TRA	2612 WHITIS AVE	TX VCP	277	0.052	East
LG2085 / 11	TEXAS CO THE FILLING	101 5TH ST W	EDR Hist Auto	279	0.053	SSW
JH2086 / 11	EMPIRE AUTOMOTIVE SE	604 7TH ST E	EDR Hist Auto	279	0.053	NE
JH2087 / 11	LOPEZ FRANK S	604 7TH E	EDR Hist Auto	279	0.053	NE
JH2088 / 11	EMPIRE AUTOMOTIVE SE	604 7TH ST E	EDR Hist Auto	279	0.053	NE
LG2089 / 11	THURMAN WAVERLY	120 5TH W	EDR Hist Cleaner	279	0.053	SSW
LG2090 / 11	PAGE SAM F DCLO CLNR	109 5TH ST W	EDR Hist Cleaner	279	0.053	SSW
LG2091 / 11	STROBURG & BLOMQUIST	103 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2092 / 11	GOSLIN J W T & CO	108 5TH ST E	EDR Hist Auto	280	0.053	SSW
LX2093 / 11	APPLE TRACT	811-814 W 6TH	TX UST	280	0.053	WNW
LX2094 / 11	APPLE TRACT	811 W 6TH ST	TX VCP	280	0.053	WNW
LG2095 / 11	NIEMAN ELECTRICAL	107 5TH W	EDR Hist Auto	280	0.053	SSW
LG2096 / 11	NIEMAN ELEC SER	107 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2097 / 11	ABADIE & ROLAND TAI	107 5TH ST W	EDR Hist Cleaner	280	0.053	SSW
LG2098 / 11	TAYLOR VIVIEN REPR S	123 5TH ST W	EDR Hist Auto	280	0.053	SSW
ME2099 / 11	B & N AXLE SERVICE	219 4TH ST W	EDR Hist Auto	280	0.053	NNE
ME2100 / 11	B & N AXLE SERVICE	219 4TH ST W	EDR Hist Auto	280	0.053	NNE
LG2101 / 11	DICKARD R AUTO REPR	104 5TH ST E	EDR Hist Auto	280	0.053	SSW
MP2102 / 11	BAKER LEONARD	1700 LAVACA ST	EDR Hist Cleaner	280	0.053	ESE
LG2103 / 11	111 13 BARGE ROBT AU	111 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2104 / 11	LUNCEFORD THOMAS J A	127 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2105 / 11	111 15 BENSON MOTOR	111 5TH ST E	EDR Hist Auto	280	0.053	SSW
LG2106 / 11	EPPLER J LAYTON REPR	115 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2107 / 11	SE COR BLUE PENNANT	114 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2110 / 11	CITIES SERVICE STA	120 5TH E	EDR Hist Auto	280	0.053	SSW
LG2111 / 11	BERGSTROM BROS	119 5TH ST W	EDR Hist Auto	280	0.053	SSW
LG2112 / 11	NE COR COX REALIZATI	117 5TH ST E	EDR Hist Auto	280	0.053	SSW
MR2113 / 11	JIMS CONOCO	1308 LAVACA ST	TX LPST, TX Ind. Haz Waste	280	0.053	ESE
MR2114 / 11	JIMS CONOCO	1308 LAVACA ST	TX UST, TX HIST UST	280	0.053	ESE
MR2115 / 11	OCONNERS JIM MOBIL G	1308 LAVACA ST	EDR Hist Auto	280	0.053	ESE
LH2117 / 11	ALEXANDER CLY D FILL	301 5TH E	EDR Hist Auto	281	0.053	SSW
LH2118 / 11	302 12 FROMME MOTOR	302 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2119 / 11	0 & M AUTO REPAIR GR	318 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2120 / 11	D & M AUTO REPAIR	318 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2121 / 11	ELLIOTT EUNICE E RAD	318 5TH E	EDR Hist Auto	281	0.053	SSW
JP2122 / 11	DARTER HOWARD T	217 5TH E	EDR Hist Auto	281	0.053	SSW
JP2123 / 11	DARTER H T AUTO	217 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2124 / 11	PILAND & ELLIOTT SER	311 5TH ST E	EDR Hist Auto	281	0.053	SSW
LH2125 / 11	TRAVIS MOTOR EXCHANG	311 5TH ST E	EDR Hist Auto	281	0.053	SSW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
LH2126 / 11	PILAND & ELLIOTT	311 5TH E	EDR Hist Auto	281	0.053	SSW
LX2127 / 11	MCMORRIS FORD	808 W 6TH ST	TX UST	282	0.053	WNW
LX2128 / 11	MCMORRIS FORD	808 W 6TH ST	TX LPST, TX CENTRAL REGISTRY	282	0.053	WNW
LX2129 / 11	MCMORRIS FORD	808 W 6TH	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	282	0.053	WNW
LX2130 / 11	ME MORRIS FORD INC	808 W 6TH ST	EDR Hist Auto	282	0.053	WNW
LH2131 / 11	316 18 DELZELL & DEM	316 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2132 / 11	DELZELL & DEMENT AUT	316 5TH E	EDR Hist Auto	282	0.053	SSW
JP2133 / 11	CULLEN HUGH H GARAGE	206 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2134 / 11	RUMSEYS GARAGE	211 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2135 / 11	HOME STEAM LNDY	211 5TH ST E	EDR Hist Cleaner	282	0.053	SSW
LH2136 / 11	D&M AUTO REPR	305 5TH E	EDR Hist Auto	282	0.053	SSW
LH2137 / 11	REAR SMITH AUTO SERV	305 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2138 / 11	FROMME MOTOR CO	304 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2139 / 11	SAN JACINTO GARAGE	305 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2140 / 11	DARTER SLIM	213 5TH E	EDR Hist Auto	282	0.053	SSW
LH2141 / 11	LOCKE WILL MOTOR	306 5TH E	EDR Hist Auto	282	0.053	SSW
LH2142 / 11	RIEGERS GARAGE	307 5TH E	EDR Hist Auto	282	0.053	SSW
MP2143 / 11	CAMPBELL CLEANERS	1620 LAVACA	EDR Hist Cleaner	282	0.053	ESE
JP2144 / 11	WATT STUART SERVICE	200 5TH E	EDR Hist Auto	282	0.053	SSW
JP2145 / 11	FIFTH & BRAZOS SERVI	200 5TH ST E	EDR Hist Auto	282	0.053	SSW
LH2146 / 11	MILES DEAN DCLO CLNR	324 5TH ST E	EDR Hist Cleaner	282	0.053	SSW
JP2147 / 11	QUICK SERVICE GAR PI	204 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2148 / 11	205 7 AUSTIN RUBBER	205 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2149 / 11	CAPITOL CHEVROLET	218 5TH E	EDR Hist Auto	282	0.053	SSW
JP2150 / 11	BOWDIN M L SPRING	218 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2151 / 11	BEATY WELDING & RADI	219 5TH ST E	EDR Hist Auto	282	0.053	SSW
JP2152 / 11	CAPITOL CHEVROLET CO	220 5TH E	EDR Hist Auto	283	0.054	SSW
JP2153 / 11	ELECTRICAL SERVICE C	221 5TH ST E	EDR Hist Auto	283	0.054	SSW
JP2154 / 11	BURKHALTER E E AUTO	223 5TH ST E	EDR Hist Auto	283	0.054	SSW
LB2155 / 11	AUSTIN FRAME & WHEEL	526 1ST ST S	EDR Hist Auto	283	0.054	WNW
KQ2156 / 11	SMITH LANDRY C CLDO	706 6TH E	EDR Hist Cleaner	283	0.054	ENE
KY2157 / 11	LINDSAY AUTO ELEC	504 LAVACA	EDR Hist Auto	283	0.054	ESE
LB2158 / 11	AUSTIN FRAME & WHEEL	525 1ST ST S	EDR Hist Auto	284	0.054	WNW
KG2161 / 11	400 LAVACA ST AUSTIN	400 LAVACA ST	TX NON REGIST PST	285	0.054	ESE
KG2162 / 11	ABANDONED	400 LAVACA ST	TX RDR	285	0.054	ESE
KG2163 / 11	400 LAVACA ST AUSTIN	400 LAVACA ST	TX TANKS, TX CENTRAL REGISTRY	285	0.054	ESE
IY2164 / 11	KEALHOFER STARR TIRE	910 LAVACA ST	EDR Hist Auto	285	0.054	ESE
IY2165 / 11	COMMERICAL TITLE BUI	910 LAVACA ST	TX LPST	285	0.054	ESE
JE2168 / 11	AUTOMATIC BENDIX	207 17TH E	EDR Hist Cleaner	287	0.054	ESE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
MU2169 / 11	327 27 HICKS RUBBER	325 CONGRESS AVE	EDR Hist Auto	287	0.054	NNE
LB2171 / 11	LINDSAY AUTO ELEC	515 1ST S	EDR Hist Auto	287	0.054	WNW
MV2173 / 11	7-ELEVEN 12705	408 W 15TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	288	0.055	WNW
MV2174 / 11	7 ELEVEN 12705	408 W 15TH ST	TX RDR	288	0.055	WNW
LF2175 / 11	BURTONS LAUNDRY & CL	615 W 19TH ST	EDR Hist Cleaner	289	0.055	East
JH2176 / 11	TRAVIS MOTOR EX	611 7TH E	EDR Hist Auto	289	0.055	NE
JH2177 / 11	B & L CLUTCH & BRAKE	611 7TH ST E	EDR Hist Auto	289	0.055	NE
JH2178 / 11	B & L CLUTCH & BRAKE	611 7TH ST E	EDR Hist Auto	289	0.055	NE
KH2180 / 11	LAWSHA LEE C DCLO CL	215 CONGRESS AVE E	EDR Hist Cleaner	290	0.055	SSW
MN2182 / 11	GARDNERS SERVICE STA	99 CONGRESS AVE	EDR Hist Auto	291	0.055	NNE
JA2184 / 11	AUTOMOTIVE SPECIA	837 12TH W	EDR Hist Auto	292	0.055	WNW
JH2185 / 11	TRAVIS MTR EX	613 7TH E	EDR Hist Auto	292	0.055	NE
JH2186 / 11	TRAVIS MOTOR EXCHANG	613 7TH ST E	EDR Hist Auto	292	0.055	NE
MX2187 / 11	WELLS H P GARAGE	206 18TH E	EDR Hist Auto	292	0.055	ESE
LB2188 / 11	ACUNAS	511 E 1ST ST	TX UST	293	0.055	WNW
LB2189 / 11	TAYLORS SERIVCE	511 1ST E	EDR Hist Auto	293	0.055	WNW
MK2191 / 11	BLOCK 4	100 COLORADO ST	TX VCP, TX GCC, TX IOP, TX CENTRAL REGIS...	293	0.055	NNE
MK2192 / 11	AUSTIN GAS LIGHT CO	100 COLORADO ST (COR	EDR MGP	293	0.055	NNE
MN2194 / 11	LINCOLN PROPERTIES	FIRST AND CONGRESS	SEMS-ARCHIVE	294	0.056	NNE
JE2195 / 11	GRAY CLNRS	209 17TH E	EDR Hist Cleaner	294	0.056	ESE
MY2196 / 11	AUSTIN CONV. CTR. EX	3RD & RED RIVER	TX RDR	294	0.056	WNW
MZ2197 / 11	PARKING GARAGE E	1604 LAVACA ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	297	0.056	ESE
MZ2198 / 11	THRIFTY CLEANERS	1604 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
MR2199 / 11	LAVACA ST GARAGE	1404 LAVACA ST	EDR Hist Auto	297	0.056	ESE
MR2200 / 11	DAVIS H R DCLO CLNR	1404 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
MR2201 / 11	KALLGREN & HAMILTON	1402 LAVACA	EDR Hist Cleaner	297	0.056	ESE
MR2202 / 11	MAGNOLIA PET CO STI	1312 LAVACA ST	EDR Hist Auto	297	0.056	ESE
LT2203 / 11	BAKER LEONARD CLNR	1516 LAVACA ST	EDR Hist Cleaner	297	0.056	ESE
LK2204 / 11	LINDSAY AUTO ELEC	506 LAVACA ST	EDR Hist Auto	297	0.056	ESE
LT2206 / 11	FRIENDLY PRESSING SH	1504 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2207 / 11	11 AUSTIN LAUNDRY	1514 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2208 / 11	1504 AUSTIN LAUNDRY	1510 LAVACA ST	EDR Hist Cleaner	298	0.056	ESE
LT2209 / 11	QUINN & SMITH CLNRS	1506 LAVACA ST	EDR Hist Cleaner	299	0.057	ESE
LK2210 / 11	SHIRLEYS HATTER	310 6TH W	EDR Hist Cleaner	299	0.057	ESE
LK2211 / 11	SHIRLEY CLEANERS & H	310 6TH ST W	EDR Hist Cleaner	299	0.057	ESE
NA2213 / 11	PEARSON WESLEY	301 CONGRESS AVE S	EDR Hist Auto	299	0.057	SSW
NA2214 / 11	GULF REFINING CO.	301 S CONGRESS AVE	TX HIST UST	299	0.057	SSW
NA2215 / 11	SMITTY AUTO SERVICE	301 CONGRESS AVE S	EDR Hist Auto	299	0.057	SSW
KY2216 / 11	CARLSONS T P SERV	500 LAVACA ST	EDR Hist Auto	300	0.057	ESE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
JH2217 / 11	BETHKE BRAKE SERVICE	617 7TH ST E	EDR Hist Auto	300	0.057	NE
JH2218 / 11	BETHKE BRAKE SERVICE	617 7TH ST E	EDR Hist Auto	300	0.057	NE
KY2224 / 11	502 04 WHITING ROBT	502 LAVACA ST	EDR Hist Auto	300	0.057	ESE
LA2227 / 11	AUSTIN GARAGE AUTOMO	511 COLORADO ST	EDR Hist Auto	301	0.057	West
MU2229 / 11	NIELSON GULF SERVICE	329 CONGRESS AVE	EDR Hist Auto	302	0.057	NNE
JP2230 / 11	M. C. PARRISH	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2231 / 11	YELLOW CAB	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2232 / 11	F. O. SWENSEN	219 E 5TH ST	TX HIST UST	302	0.057	SSW
JP2233 / 11	NCNB TEXAS	201 E 5TH ST	TX LPST	302	0.057	SSW
JP2234 / 11	CLOSED SITE	201 E. 5TH ST	TX HIST UST	302	0.057	SSW
JP2235 / 11	CHRISTAL-FRAZIER MET	201 E 5TH ST	TX HIST UST	302	0.057	SSW
ND2236 / 11	BANK63	CORNER OF 3RD BRAZOS	TX UST	303	0.057	East
LA2238 / 11	505 11 BARKER MOTOR	505 COLORADO ST	EDR Hist Auto	305	0.058	West
MU2239 / 11	MC GOWAN ED TEXACO	344 CONGRESS AVE	EDR Hist Auto	305	0.058	NNE
2248 / 11	STUDENT CO OPERATIVE	2412 SAN ANTONIO	EDR Hist Auto	307	0.058	West
LA2255 / 11	203 5 SMITH KELLY DC	203 6TH W	EDR Hist Cleaner	308	0.058	WNW
LA2256 / 11	STARR BLDG HISTORIC	501 COLORADO	TX RDR	308	0.058	West
LA2257 / 11	KEMP PROPERTIES	501 COLORADO ST	TX LPST, TX GCC	308	0.058	West
LA2258 / 11	WOFFORD S D FILLING	501 COLORADO	EDR Hist Auto	308	0.058	West
KJ2260 / 11	SCHNEIDER ALBERT REP	310 2ND W	EDR Hist Auto	311	0.059	ESE
KY2261 / 11	SING FRANCES MRS LND	311 5TH ST W	EDR Hist Cleaner	313	0.059	ESE
MY2262 / 11	AUSTIN CONVENTION CE	300 RED RIVER ST	TX HIST UST	313	0.059	WNW
LX2263 / 11	GREGORY FENDER	815 6TH W	EDR Hist Auto	313	0.059	WNW
KL2267 / 11	BELL AIRDOME FILLING	900 COLORADO	EDR Hist Auto	316	0.060	WNW
KS2269 / 11	FORMER GLO FAC	421 E 1ST	TX RDR	317	0.060	ESE
NG2270 / 11	THURMAN WAVERLY	620 COLORADO ST	EDR Hist Cleaner	318	0.060	WNW
LA2271 / 11	HOUGH ROY AUTO REPR	608 COLORADO ST	EDR Hist Auto	319	0.060	WNW
NH2272 / 11	WHITLEY CO	801 BRAZOS TO 805	TX UST, RCRA NonGen / NLR	319	0.060	ESE
NH2273 / 11	WHITLEY	801 BRAZOS TO 805	TX Ind. Haz Waste	319	0.060	ESE
KY2276 / 11	AMERICAN CLEANERS	309 5TH ST W	EDR Hist Cleaner	320	0.061	ESE
KY2277 / 11	FAULKNER RUSSELL C	309 5TH W	EDR Hist Auto	320	0.061	ESE
NJ2278 / 11	MC CUTCHEON U S AUTO	106 1ST E	EDR Hist Auto	320	0.061	NNE
NK2279 / 11	DOWNS R L & CO	309 10TH W	EDR Hist Cleaner	321	0.061	ESE
KH2280 / 11	WARDROBE CLNRS THE	207 CONGRESS AVE E	EDR Hist Cleaner	321	0.061	SSW
NA2281 / 11	FIRESTONE TIRE & SER	311 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	322	0.061	SSW
KT2282 / 11	209 11 BLUE BONNET O	209 8TH W	EDR Hist Cleaner	323	0.061	WNW
NA2283 / 11	GULF REFG CO STA NO	300 CONGRESS AVE S	EDR Hist Auto	323	0.061	SSW
NA2284 / 11	KINGSLEY AUTOMOTIVE	300 CONGRESS AVE S	EDR Hist Auto	323	0.061	SSW
LI2285 / 11	GREGG J EARLE CLNR	1808 LAVACA ST	EDR Hist Cleaner	324	0.061	East

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
LK2289 / 11	WEBB J E TIRES	608 LAVACA ST	EDR Hist Auto	328	0.062	ESE
2290 / 11	FIRE STATION 1	401 E 5TH ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	328	0.062	SSW
NJ2291 / 11	ALLMAN JESS	112 1ST E	EDR Hist Auto	328	0.062	NE
KY2292 / 11	AAMCO TRANSMISSIONS	307 5TH ST W	EDR Hist Auto	329	0.062	ESE
KY2293 / 11	307 9 KNIGHT WHIPPET	307 5TH ST W	EDR Hist Auto	329	0.062	ESE
KH2294 / 11	TEXAS OIL COMPANY	100 W 2ND ST	TX HIST UST	329	0.062	SSW
2295 / 11	WARD HAROLD	703 BARTON SPGS RD	EDR Hist Auto	329	0.062	WNW
KH2296 / 11	AVENUE GARAGE	205 CONGRESS AVE E	EDR Hist Auto	329	0.062	SSW
NG2301 / 11	SMITH KELLY CLEANERS	209 6TH W	EDR Hist Cleaner	330	0.062	WNW
NL2302 / 11	PHILLIPS BUILDING	103 E 5TH ST	TX VCP, TX GCC	330	0.062	SSW
NJ2303 / 11	112 14 ALLMANS JESS	114 1ST E	EDR Hist Auto	330	0.062	NE
2304 / 11	BOUCHARD E A GARAGE	207 14TH W	EDR Hist Auto	331	0.063	WNW
LC2308 / 11	EXXON 6 8082	2324 N ST MARYS	TX UST	333	0.063	ESE
2312 / 11	LYNN SMITH	300 W DEAN KEETON ST	TX HIST UST	334	0.063	East
KY2313 / 11	ANDYS AUTO ELECTRIC	305 5TH ST W	EDR Hist Auto	336	0.064	ESE
KY2314 / 11	S & D AUTO ELECTRIC	305 5TH ST W	EDR Hist Auto	336	0.064	ESE
KY2315 / 11	ANDYS AUTO ELEC REPR	305 5TH W	EDR Hist Auto	336	0.064	ESE
NA2318 / 11	LINDHOLM GARAGE	219 BARTON SPRINGS R	EDR Hist Auto	337	0.064	SSW
NG2319 / 11	CAPITAL CITY AUTO CO	211 6TH W	EDR Hist Auto	337	0.064	WNW
LA2320 / 11	JOHNSON ARVEL G	510 COLORADO	EDR Hist Auto	338	0.064	West
KT2325 / 11	BARRS BLUE BONNET	213 8TH W	EDR Hist Cleaner	339	0.064	WNW
KP2326 / 11	SODIES AUTO REPAIR	405 NECHES ST	EDR Hist Auto	339	0.064	SW
KP2327 / 11	CAPITAL SPRING & BRA	403 NECHES ST	EDR Hist Auto	341	0.065	SW
NJ2328 / 11	NW COR SWEARINGEN AR	120 1ST W	EDR Hist Auto	341	0.065	NE
KC2329 / 11	BUMPER-TO-BUMPER CAR	201 SAN JACINTO BLVD	TX Ind. Haz Waste	341	0.065	WNW
KC2330 / 11	BUMPER-TO-BUMPER CAR	201 SAN JACINITO	RCRA NonGen / NLR, FINDS, ECHO	341	0.065	WNW
NS2331 / 11	PROPOSED CHICK FIL A	503 W MARTIN LUTHER	TX VCP	342	0.065	West
KP2336 / 11	LANDMARK ORGANIZATIO	401 NECHES ST	TX IHW CORR ACTION	342	0.065	SW
LA2337 / 11	TEXAS MOTORS	502 COLORADO ST	EDR Hist Auto	343	0.065	West
MA2338 / 11	FORDEX SERVICE AUTO	201 2ND W	EDR Hist Auto	343	0.065	SSW
KY2339 / 11	AUTOMATIC TRANSMISSI	303 5TH ST W	EDR Hist Auto	344	0.065	ESE
NT2340 / 11	OLD SPAGHETTI WAREHO	117 W 4TH ST	TX HIST UST	344	0.065	NNE
NG2341 / 11	CAPITAL CITY REPAIR	213 6TH W	EDR Hist Auto	344	0.065	WNW
LA2342 / 11	LONE STAR GARAGE AUT	500 COLORADO ST	EDR Hist Auto	344	0.065	West
NV2345 / 11	UNITED MTR EXCH	111 SAN JACINTO ST	EDR Hist Auto	344	0.065	WNW
MZ2346 / 11		W 16TH & LAVACA	TX HIST UST	346	0.066	ESE
LH2349 / 11	CAPITOL TIRE	301 E 5TH ST	TX HIST UST	347	0.066	SSW
LH2350 / 11	GENERAL TIRE STORE	301 E 5TH ST	TX HIST UST	347	0.066	SSW
LH2351 / 11	CAPITOL TIRE SERVICE	301 E 5TH ST	TX UST	347	0.066	SSW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
2352 / 11	JONES JOHN H CLNR	212 17TH W	EDR Hist Cleaner	347	0.066	WNW
LH2353 / 11	ACTION SCREEN GRAPHI	305 E 5TH ST STE B	TX Ind. Haz Waste	347	0.066	SSW
LH2355 / 11	CAPITOL AUTO & TRANS	311 E 5TH ST	EDR Hist Auto	347	0.066	SSW
LH2356 / 11	HERMINE WILDE ESTATE	311 E 5TH ST	TX UST, TX HIST UST	347	0.066	SSW
NW2357 / 11	G. L. ROWE	816 W 12TH ST	TX HIST UST	348	0.066	WNW
KH2358 / 11	ELLIOTTS RADIATOR SH	102 2ND ST W	EDR Hist Auto	348	0.066	SSW
KH2359 / 11	ELLIOTTS RADIATOR SH	102 2ND ST W	EDR Hist Auto	348	0.066	SSW
NX2360 / 11	SILBEY FIREPROOF WAR	309 E 4TH ST	TX HIST UST	348	0.066	NNE
NX2361 / 11	AUSTIN FIREPROOF WAR	309 E 4TH ST	TX HIST UST	348	0.066	NNE
NY2362 / 11	ALMQUIST SINCLAIR SE	700 RED RIVER	EDR Hist Auto	349	0.066	NE
NX2363 / 11	M&T RAILWAY COMPANY	301 E 4TH ST	TX HIST UST	349	0.066	NNE
NX2364 / 11	K&B STORAGE CO.	301 E 4TH ST	TX HIST UST	349	0.066	NNE
MI2367 / 11	CAPITOL LNDRY & CLN	301 8TH W	EDR Hist Cleaner	351	0.066	ESE
NG2368 / 11	NASH JOHN H MOTOR CO	215 6TH W	EDR Hist Auto	351	0.066	WNW
NZ2369 / 11	FOWLER ELECTRIC	621 E 7TH ST	TX UST, TX HIST UST	351	0.066	NE
LG2370 / 11	JACOBSON TYRE & REPA	101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2371 / 11		101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2372 / 11	TEXAS OIL COMPANY	101 W 5TH ST	TX HIST UST	351	0.066	SSW
LG2373 / 11		101 W 5TH ST	TX HIST UST	351	0.066	SSW
KY2374 / 11	SMITH C B MOTORS	301 5TH W	EDR Hist Auto	351	0.066	ESE
KY2375 / 11	CARREON MARCIEL CLN	301 5TH ST W	EDR Hist Cleaner	351	0.066	ESE
KY2376 / 11	301 3 TIRE SERVICE C	301 5TH ST W	EDR Hist Auto	351	0.066	ESE
KH2377 / 11	DEWEYS WELDING & RAD	110 2ND W	EDR Hist Auto	352	0.067	SSW
KH2378 / 11	108 10 0 0 K GARAGE	108 2ND W	EDR Hist Auto	352	0.067	SSW
KR2388 / 11	MRS. PRUDENCE BAILEY	520 W 6TH ST	TX HIST UST	355	0.067	ESE
KR2389 / 11	WILLIAMS MOTORS	520 W 6TH ST	TX HIST UST	355	0.067	ESE
KR2390 / 11	520 W 6TH ST LLC	520 W 6TH	TX RDR	355	0.067	ESE
MK2393 / 11	R. A. JOHN	200 W CESAR CHAVEZ S	TX HIST UST	356	0.067	NNE
MK2394 / 11	PAUL O. SIMMS	200 W CESAR CHAVEZ S	TX HIST UST	356	0.067	NNE
OC2403 / 11	SERVICE CENTER 2	600 RIVER ST	TX UST, TX HIST UST	357	0.068	WNW
OC2404 / 11	CITY OF AUSTIN FLEET	600 RIVER ST	RCRA NonGen / NLR, FINDS, ECHO	357	0.068	WNW
OC2405 / 11	CITY OF AUSTIN SERVI	600 RIVER ST	TX Ind. Haz Waste	357	0.068	WNW
OC2406 / 11	SERVICE CENTER 2	600 RIVER ST	TX SWF/LF, TX LPST, TX Ind. Haz Waste	357	0.068	WNW
OC2407 / 11	EMMA BARRIENTOS MEXI	600 RIVER STREET	US BROWNFIELDS	357	0.068	WNW
LG2408 / 11	417 19 PATTON AUTO L	417 CONGRESS AVE	EDR Hist Auto	358	0.068	SSW
NG2409 / 11	ESTES & CO AUTO	216 6TH W	EDR Hist Auto	358	0.068	WNW
NG2410 / 11	FIEGELS GARAGE	217 6TH W	EDR Hist Auto	358	0.068	WNW
NZ2411 / 11	BETHKE BRAKE SERVICE	617 E 7TH ST	EDR Hist Auto	358	0.068	NE
LF2412 / 11	LONGHORN CLNRS	510 W MARTIN LUTHUR	RCRA-SQG, FINDS, ECHO	359	0.068	East

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
NW2414 / 11	CONVENIENCE COIN LAU	817 12TH ST W	EDR Hist Cleaner	361	0.068	WNW
LK2416 / 11	RIEGERS GARAGE AUTO	513 LAVACA	EDR Hist Auto	364	0.069	ESE
LK2417 / 11	REIGER MOTOR SALES	505 LAVACA	EDR Hist Auto	364	0.069	ESE
OD2418 / 11	EARL E. SIMMS	119 E 5TH ST	TX HIST UST	364	0.069	SSW
JY2419 / 11	29WAT R907222	4TH & COLORADO	TX UST	364	0.069	NNE
NL2420 / 11	EAST 9TH STREET COMP	115 E 5TH ST STE 200	EDR Hist Auto	364	0.069	SSW
LK2421 / 11	MC CUTCHEON U S AUTO	503 LAVACA ST	EDR Hist Auto	364	0.069	ESE
LK2422 / 11	AUSTIN BTRY & ELEC	501 LAVACA	EDR Hist Auto	365	0.069	ESE
2424 / 11	AUTOMATIC TRANSMISSI	211 4TH ST W	EDR Hist Auto	365	0.069	NNE
NS2426 / 11	KELLY SMITH CLEANERS	511 MARTIN LUTHER K	EDR Hist Cleaner	368	0.070	West
OF2427 / 11	COVERT BUICK INC	500 5TH ST W	EDR Hist Auto	368	0.070	WNW
NA2429 / 11	PEARSON WESLEY H	313 CONGRESS AVE S	EDR Hist Auto	369	0.070	SSW
NA2430 / 11	PEARSON WESLEY H FIL	313 CONGRESS AVE S	EDR Hist Auto	369	0.070	SSW
MP2431 / 11	CORLEY & BERRY SERVI	1701 LAVACA	EDR Hist Auto	370	0.070	ESE
MP2432 / 11	M D PHARMACY	1701 LAVACA ST	TX LPST, TX UST, TX HIST UST	370	0.070	ESE
OF2434 / 11	AUSTIN FEDERAL COURT	501 W 5TH ST	TX UST, TX HIST UST	371	0.070	WNW
OF2435 / 11	AUSTIN FEDERAL COURT	501 W 5TH ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	371	0.070	WNW
OG2436 / 11	THE WALTER TIPS CO.	115 W 2ND ST	TX HIST UST	371	0.070	SSW
OH2437 / 11	CITY OF AUSTIN RIGHT	3RD & SAN ANTONIO	TX TANKS, TX CENTRAL REGISTRY	371	0.070	WNW
OI2439 / 11		W 6TH ST & SAN ANTON	TX HIST UST	371	0.070	WNW
OI2440 / 11	KUHLMAN HOW	501 6TH W	EDR Hist Auto	371	0.070	WNW
OF2441 / 11	LINDHOLM TORSTEN	502 5TH W	EDR Hist Auto	375	0.071	WNW
LF2442 / 11	LONGHOM CLEANERS	510 MARTIN LUTHER K	EDR Hist Cleaner	375	0.071	East
2444 / 11	TRAVIS COUNTY JAIL	1000 SAN ANTONIO ST	TX UST, TX HIST UST	377	0.071	WNW
LB2445 / 11	J. G. MASON	511 E CESAR CHAVEZ S	TX HIST UST	377	0.071	WNW
LB2446 / 11	ACUNA'S	511 E CESAR CHAVEZ S	TX HIST UST	377	0.071	WNW
OJ2448 / 11	GULF OIL COMPANY	201 W 2ND ST	TX HIST UST	378	0.072	SSW
OI2449 / 11	ZIMMERMANH E E	503 6TH W	EDR Hist Cleaner	378	0.072	WNW
2450 / 11	MUELLER & BENSON	403 BRAZOS	EDR Hist Auto	379	0.072	NNE
2451 / 11	UNIVERSITY GARAGE AU	1806 SAN ANTONIO ST	EDR Hist Auto	380	0.072	WNW
MU2454 / 11	WESTBANK DRY CLEANIN	112 E 4TH ST	TX DRYCLEANERS	381	0.072	NNE
OF2455 / 11	LINDHOLM T F AUTO	500 SAN ANTONIO ST	EDR Hist Auto	381	0.072	WNW
OF2456 / 11	COVERT BUICK CO	505 5TH ST W	EDR Hist Auto	382	0.072	WNW
OF2457 / 11	COVERT BUICK CO	505 5TH ST W	EDR Hist Auto	382	0.072	WNW
2458 / 11	COR EZELLE JACK SERV	8 SAN JACINTO ST	EDR Hist Auto	382	0.072	WNW
OK2462 / 11	BADGER AUTO SUPPLY C	119 W 5TH ST	TX HIST UST	386	0.073	SW
OK2463 / 11	KENICHI RESTAURANT	121 W 5TH ST	TX HIST UST, TX RDR	386	0.073	SW
2464 / 11	AUSTIN LNDRY & DRY	608 24TH W	EDR Hist Cleaner	387	0.073	East
2466 / 11	COVERT AUTOMO	420 SAN ANTONIO ST	EDR Hist Auto	387	0.073	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
OH2467 / 11	416 20 COVERT AUTO C	416 SAN ANTONIO ST	EDR Hist Auto	387	0.073	WNW
OI2468 / 11	LARSONS GARAGE AUTO	504 6TH ST W	EDR Hist Auto	387	0.073	WNW
OI2469 / 11	LARSONS GAR AUTO REP	504 6TH W	EDR Hist Auto	387	0.073	WNW
LG2472 / 11	NATIONAL FINANCE CO	413 CONGRESS AVE	EDR Hist Auto	388	0.073	SSW
2477 / 11	GREENBERG GRANT & RI	80 RED RIVER ST	EDR Hist Auto	393	0.074	WNW
MZ2479 / 11	HASSE SERVICE STATIO	1511 LAVACA	EDR Hist Auto	395	0.075	ESE
2483 / 11	UNIVERSITY BODY	1409 LAVACA	EDR Hist Auto	396	0.075	ESE
LT2486 / 11	LAVACA ST GARAGE	1417 LAVACA ST	EDR Hist Auto	396	0.075	ESE
MR2490 / 11	1311 13 YOUNG & SCHI	1311 LAVACA ST	EDR Hist Auto	396	0.075	ESE
MR2491 / 11	SPRINKLES BODY SHOP	1305 LAVACA	EDR Hist Auto	396	0.075	ESE
MZ2492 / 11	BATTERY SERVICE CO	1603 LAVACA ST	EDR Hist Auto	397	0.075	ESE
LT2493 / 11	KALLGREN & HAMILTON	1419 LAVACA ST	EDR Hist Cleaner	397	0.075	ESE
LT2494 / 11	KING I B STOVE	1419 LAVACA ST	EDR Hist Auto	397	0.075	ESE
MR2495 / 11	LUDER FRED AUTO REPR	1313 LAVACA ST	EDR Hist Auto	397	0.075	ESE
OQ2498 / 11	WALLACE ENGRAVING CO	407 LAVACA STREET	RCRA NonGen / NLR, FINDS, ECHO	400	0.076	ESE
OQ2499 / 11	WALLACE ENGRAVING	407 LAVACA ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	400	0.076	ESE
NX2502 / 11	DARTER WELDING	408 SAN JACINTO ST	EDR Hist Auto	402	0.076	NNE
NX2503 / 11	SAN JACINTO CLEANERS	408 SAN JACINTO BLV	EDR Hist Cleaner	402	0.076	NNE
LA2505 / 11	J. C. BRYANT CREAMER	200 W 5TH ST	TX HIST UST	403	0.076	WSW
NL2508 / 11	HONG LEE MRS CHINESE	411 CONGRESS AVE	EDR Hist Cleaner	404	0.077	SSW
2509 / 11	GULF INTRACOASTAL CA	221 E 9TH ST STE 206	EDR Hist Auto	404	0.077	ESE
NA2511 / 11	M. H. CROCKETT	319 S CONGRESS AVE	TX HIST UST	405	0.077	SSW
OQ2513 / 11	TEXAS COMPANY	213 W 5TH ST	TX HIST UST	406	0.077	ESE
OQ2514 / 11	CATHERINE UMSTATTD	213 W 5TH ST	TX UST	406	0.077	ESE
OQ2515 / 11	VACANT COMMERCIAL BL	213 W 5TH ST	TX HIST UST	406	0.077	ESE
OI2519 / 11	AUSTIN FOREIGN CAR C	510 6TH ST W	EDR Hist Auto	410	0.078	WNW
OI2520 / 11	EUROPEAN SPECIALIZED	510 6TH ST W	EDR Hist Auto	410	0.078	WNW
OI2521 / 11	510 12 AUSTIN AUTOMA	510 6TH W	EDR Hist Auto	410	0.078	WNW
OF2524 / 11	COVERT BUICK	500 W 5TH ST	TX UST, TX HIST UST	410	0.078	WNW
OK2525 / 11	AUSTIN FOUNDRY	200 5TH ST W	EDR Hist Auto	411	0.078	WSW
MZ2528 / 11	CITIES SERVICE OIL C	1601 LAVACA ST	EDR Hist Auto	412	0.078	ESE
NS2534 / 11	KELLY SMITH CLEANERS	509-511 W 19TH	EDR Hist Cleaner	413	0.078	West
OV2538 / 11	OLD FIRESTONE	901 LAVACA ST	TX HIST UST	415	0.079	ESE
OW2539 / 11	CAPITOL SERVICE STAT	1301 LAVACA	EDR Hist Auto	416	0.079	ESE
NZ2540 / 11	EMPIRE AUTOMOTIVE SE	604 E 7TH ST	EDR Hist Auto	420	0.080	NE
NY2541 / 11		705 RED RIVER	TX HIST UST	421	0.080	NE
OK2542 / 11	FISHER FRANK C AUTO	205 5TH ST W	EDR Hist Auto	421	0.080	WSW
OK2543 / 11	STEINERS SERVICE	205 5TH W	EDR Hist Auto	421	0.080	WSW
OG2549 / 11	SMITH MOTOR CO AUTO	119 CONGRESS AVE	EDR Hist Auto	424	0.080	SSW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
OI2550 / 11	MILLER BLUEPRINT	513 W 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	426	0.081	ESE
OI2551 / 11	MILLER BLUEPRINT COM	513 W 6TH STREET	RCRA NonGen / NLR, FINDS, ECHO	426	0.081	ESE
OK2552 / 11	VIOLET CROWN GARAGE	207 5TH ST W	EDR Hist Auto	426	0.081	WSW
OK2553 / 11	FREUND ROLAND R	207 5TH W	EDR Hist Auto	426	0.081	WSW
MY2555 / 11	AUSTIN CONVENTION CE	THIRD ST RED RIVER	TX UST	428	0.081	WNW
MU2556 / 11	417 21 PATTON TRANSF	417 CONGRESS AVE E	EDR Hist Auto	428	0.081	NNE
NT2557 / 11	RUDYS PHILLIPS	400 CONGRESS AVE	EDR Hist Auto	428	0.081	NNE
MN2558 / 11	AUSTIN GOODYEAR CO	101 CONGRESS AVE	EDR Hist Auto	429	0.081	NNE
OX2559 / 11	E-Z PAWN	99 N I 35	TX HIST UST	430	0.081	ESE
OX2560 / 11	E-Z PAWN SHOP	99 N INTERSTATE 35	TX UST	430	0.081	ESE
NX2562 / 11	CABANISS-BROWN FURNI	216 E 4TH ST	TX HIST UST	430	0.081	NNE
NS2563 / 11	KELLV SMITH CLEANERS	511 W 19TH ST	EDR Hist Cleaner	433	0.082	West
OK2564 / 11	ROBINSON A A AUTO	209 5TH ST W	EDR Hist Auto	433	0.082	WSW
OK2565 / 11	LONE STAR SUPPLY CO	209 5TH ST W	EDR Hist Auto	433	0.082	WSW
MR2570 / 11	ADOLPH KOHN	217 W 14TH ST	TX HIST UST	434	0.082	ESE
MR2571 / 11	TOM BAKING COMPANY	217 W 14TH ST	TX HIST UST	434	0.082	ESE
PA2584 / 11	DISCOUNT CLEANERS	510 19TH ST W	EDR Hist Cleaner	438	0.083	East
PB2585 / 11	JAS. LUCAS	503 E CESAR CHAVEZ S	TX HIST UST	438	0.083	ESE
OK2586 / 11	NE COR MAGNOLIA PET	211 5TH ST W	EDR Hist Auto	439	0.083	WSW
OK2594 / 11	AUTO SALVAGE CO	419 COLORADO ST	EDR Hist Auto	440	0.083	SW
2595 / 11	CAPITOL LAUNDRY & DR	501 W 24TH ST	EDR Hist Cleaner	441	0.084	West
PB2596 / 11	AUSTIN CONVENTION CE	500 E CESAR CHAVEZ S	RCRA NonGen / NLR	442	0.084	ESE
PB2597 / 11	AUSTIN CONVENTION CE	500 E CESAR CHAVEZ S	TX HIST UST, TX Ind. Haz Waste	442	0.084	ESE
PB2598 / 11	NEW CONVENTION CENTE	500 E 1ST ST	TX UST	442	0.084	ESE
PB2599 / 11	GENES MAGNOLIA SER	500 1ST E	EDR Hist Auto	442	0.084	ESE
OK2601 / 11	TEXAS AMERICAN RESOU		PFAS ECHO	444	0.084	WSW
2602 / 11	CONOCOPHILLIPS COMPA	1122 COLORADO ST STE	EDR Hist Auto	444	0.084	WNW
OK2603 / 11	BEARD SPRING	213 5TH W	EDR Hist Auto	444	0.084	WSW
OK2604 / 11	BEARD SPRING C BRAKE	213 5TH ST W	EDR Hist Auto	444	0.084	WSW
OK2605 / 11	PURYEAR DEWEY	206 5TH W	EDR Hist Auto	444	0.084	WSW
OI2606 / 11	WILBURN SINCLAIR SER	520 6TH ST W	EDR Hist Auto	446	0.084	WNW
OI2607 / 11	BASS SERV STA	520 6TH W	EDR Hist Auto	446	0.084	WNW
PD2610 / 11	LEWIS PAUL C LAUNDRY	205 E 15TH ST	EDR Hist Cleaner	450	0.085	ESE
NL2611 / 11	KOCH CHARLES J DYE	405 CONGRESS ST	EDR Hist Cleaner	450	0.085	SSW
OH2612 / 11	AUSTIN CARBONICS	501 E 3RD ST	TX HIST UST	451	0.085	ESE
OH2613 / 11	FIELDON BERRY	501 W 3RD ST	TX UST	451	0.085	ESE
PE2614 / 11	STAR BRITE CLEANERS	501 W 15TH ST STE A	TX DRYCLEANERS, TX CENTRAL REGISTRY	451	0.085	WNW
PE2615 / 11	MARTINIZING 94177 15	501 W 15TH ST STE A	TX DRYCLEANERS	451	0.085	WNW
MX2617 / 11	REBECCA A. HEARN	200 E 18TH ST	TX HIST UST	452	0.086	ESE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
MM2618 / 11	JOHNSON TIRE COMP.	210 W 7TH ST	TX HIST UST	452	0.086	WNW
PA2624 / 11	CHOTE'S SERVICE CO.	500 W MARTIN LUTHER	TX HIST UST	454	0.086	West
PA2625 / 11	FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	TX LPST	454	0.086	West
PA2626 / 11	FORMER CHOTES CHEVRO	500 W MARTIN LUTHER	TX RDR	454	0.086	West
PA2627 / 11	CHOTES CHEVRON	500 W MARTIN LUTHER	TX UST, TX Ind. Haz Waste	454	0.086	West
PA2628 / 11	LASSBURG & SCHMEDES	500 W MARTIN LUTHER	TX HIST UST	454	0.086	West
PA2629 / 11	CHOTES CHEVRON	500 W MARTIN LUTHER	TX RDR	454	0.086	West
PA2630 / 11	CATHYS CLEANERS MLK	500 W MARTIN LUTHER	TX DRYCLEANERS, TX ENF	454	0.086	West
PA2631 / 11	CHOTES CHEVRON SERVI	500 MARTIN LUTHER KI	EDR Hist Auto	454	0.086	West
PG2632 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	TX UST, TX HIST UST	454	0.086	West
PG2633 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	TX VCP, TX HIST UST, TX GCC, TX Ind. Haz...	454	0.086	West
PG2634 / 11	SEAHOLM POWER PLANT	800 W CESAR CHAVEZ S	RCRA-VSQG, FINDS, ECHO	454	0.086	West
OK2637 / 11	TRATEX AUTO STORAGE	208 5TH W	EDR Hist Auto	455	0.086	WSW
OD2638 / 11	SMITH & HUDLER BROS	406 BRAZOS ST	EDR Hist Auto	456	0.086	SSW
OI2639 / 11	AUSTIN FOREIGN CAR	510 W 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	457	0.087	ESE
2640 / 11	THE SALVATION ARMY C	501 E. 8TH	US BROWNFIELDS, FINDS	457	0.087	NNE
MN2641 / 11	SCHRAMM GULF SERV	107 CONGRESS AVE	EDR Hist Auto	458	0.087	NNE
NY2646 / 11	A CRENSHAW GARAGE AU	711 RED RIVER CT	EDR Hist Auto	460	0.087	NE
NK2651 / 11	AUSTIN DAILY TRIBUNE	213 W 10TH ST	TX HIST UST	464	0.088	ESE
NL2652 / 11	SING LEE CHINESE LAU	403 CONGRESS AVE R	EDR Hist Cleaner	465	0.088	SSW
PK2654 / 11	TEXAS GOVERNORS MANS	1010 COLORADO ST	TX RDR, TX CENTRAL REGISTRY	465	0.088	WNW
PK2655 / 11	TEXAS GOVERNORS MANS	1010 COLORADO ST	TX UST, TX HIST UST	465	0.088	WNW
2659 / 11	AUSTIN AMERICAN STAT	305 S CONGRESS AVE	TX LPST	469	0.089	SE
NG2660 / 11	CAPITAL CITY TIRE	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2661 / 11		221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2662 / 11	CHASE TOWER 14TH FLO	221 W. 6TH STREET	TX HIST UST, TX ASBESTOS	470	0.089	WNW
NG2663 / 11	GOODYEAR TIRE COMP.	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2664 / 11	GULF REFINING CO.	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2665 / 11	NONO SCHUTZ	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2666 / 11	NOT AVAILABLE	221 W 6TH ST	TX HIST UST	470	0.089	WNW
NG2667 / 11	CHASE TOWER	221 W 6TH STREET	TX HIST UST, TX ASBESTOS	470	0.089	WNW
OJ2671 / 11	DEWEYS RADIATOR	112 COLORADO ST	EDR Hist Auto	472	0.089	SSW
MN2676 / 11	LINCOLN PROPERTY COM	100 CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	476	0.090	NNE
MN2677 / 11	GRAYBURG OIL CO NO	100 CONGRESS AVE E	EDR Hist Auto	476	0.090	NNE
PB2681 / 11	ACME CLEANERS	504 1ST E	EDR Hist Cleaner	476	0.090	WNW
OG2682 / 11	B & B GARAGE	117 CONGRESS AVE	EDR Hist Auto	477	0.090	SSW
OG2683 / 11	MC CULLOUGH D T	116 CONGRESS AVE	EDR Hist Auto	477	0.090	SSW
PN2684 / 11	HERMAN GARAGE	608 INTERREGIONAL HW	EDR Hist Auto	477	0.090	ENE
NW2685 / 11	AUSTIN COMMUNITY COL	824 W 12TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	477	0.090	WNW

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
NW2686 / 11	AUSTIN COMMUNITY COL	824 W 12TH	RCRA NonGen / NLR, FINDS, ECHO	477	0.090	WNW
MN2687 / 11	PINNERGY	111 CONGRESS AVE STE	TX Ind. Haz Waste	477	0.090	NNE
OK2689 / 11	413 15 POWELL GARAGE	413 COLORADO ST	EDR Hist Auto	478	0.091	SW
OV2690 / 11	E L STECK	217 W 9TH ST	TX HIST UST	478	0.091	ESE
OH2692 / 11	PARKING GARAGE N	300 SAN ANTONIO ST	TX UST, TX HIST UST	478	0.091	WNW
OW2693 / 11	LANG CLEANERS	208 13TH W	EDR Hist Cleaner	479	0.091	WNW
OK2695 / 11	MAGNOLIA PET CO NO	212 5TH ST W	EDR Hist Auto	479	0.091	WSW
PN2697 / 11	ADAMS QUADRACYCLE	610 INTERREGIONAL HW	EDR Hist Auto	481	0.091	ENE
PO2698 / 11	JOHNSONS GARAGE	504 7TH W	EDR Hist Auto	482	0.091	ESE
OI2699 / 11	D. A. GROVER	501 W 6TH ST	TX HIST UST	482	0.091	WNW
OI2700 / 11	D. A. GROVER	501 W 6TH ST	TX HIST UST	482	0.091	WNW
OK2701 / 11	EAST 9TH STREET COMP	201 W 5TH ST STE 220	EDR Hist Auto	482	0.091	WSW
OK2702 / 11		201 W 5TH ST	TX HIST UST	482	0.091	WSW
PA2704 / 11	CHOTES SINCLAIR SERV	500 W 19TH ST	EDR Hist Auto	485	0.092	East
NT2706 / 11	WESLEY GEORGE M TA	404 CONGRESS AVE	EDR Hist Cleaner	486	0.092	NNE
OG2707 / 11	DARRELL ROYAL WORK S	104 CONGRESS AVE	EDR Hist Auto	488	0.092	NNE
OG2716 / 11	113 15 GULF REFG CO	113 CONGRESS AVE E	EDR Hist Auto	492	0.093	NNE
OG2719 / 11	DEWEY GARAGE	115 CONGRESS AVE	EDR Hist Auto	493	0.093	SSW
OK2722 / 11	POWELL AUTO BODY	409 COLORADO	EDR Hist Auto	495	0.094	SW
PO2723 / 11		504 W 7TH ST	TX HIST UST	496	0.094	ESE
NG2728 / 11	PETMECKY COIS (COOF?	220 W 6TH ST	TX HIST UST	498	0.094	ESE
OD2729 / 11	MC FARLAND F H	404 BRAZOS ST	EDR Hist Auto	499	0.095	NNE
ND2731 / 11	FOUR SEASONS HOTEL	98 SAN JACINTO BLVD	RCRA-VSQG, FINDS, ECHO	500	0.095	WNW
ND2732 / 11	THE SHORELINE BUILDI	98 SAN JACINTO BOULE	TX ASBESTOS, TX DRYCLEANERS	500	0.095	WNW
NY2733 / 11	PATTERSONS GARAGE C	716 RED RIVER CT	EDR Hist Auto	504	0.095	NE
PS2734 / 11	ONE HOUR MARTINIZING	907 24TH ST W	EDR Hist Cleaner	504	0.095	West
PS2735 / 11	JACK BROWN CLEANERS	907 W 24TH ST	TX Ind. Haz Waste	504	0.095	West
PS2736 / 11	JACK BROWN CLEANERS	907 W 24TH ST	RCRA NonGen / NLR, FINDS, ECHO	504	0.095	West
NY2740 / 11	HICKMAN R L C AUTO	718 RED RIVER CT	EDR Hist Auto	509	0.096	NE
PS2741 / 11	CONVENIENCE INC WASH	916 24TH ST W	EDR Hist Cleaner	511	0.097	West
PT2746 / 11	GEST DUTCH CLEANERS	209 E 19TH	EDR Hist Cleaner	519	0.098	ESE
OX2747 / 11	INTERRIGIONAL CONOCO	901 1ST ST E	EDR Hist Auto	519	0.098	ESE
PG2748 / 11	TRANSMIX CONCRETE	812 W CESAR CHAVEZ S	TX HIST UST	520	0.098	West
OX2753 / 11	HILES JOHN L WASHING	900 1ST ST E	EDR Hist Auto	523	0.099	ESE
PY2757 / 11	ROGERS BROS SERV STA	200 1ST E	EDR Hist Auto	528	0.100	ENE
PY2758 / 11	J. F. ROBINSON	200 E CESAR CHAVEZ S	TX HIST UST	528	0.100	ENE
2759 / 11	KXAN TV STUDIO	908 W MARTIN LUTHER	TX UST, TX HIST UST, TX Financial Assura...	529	0.100	West
NW2762 / 11	MAGNOLIA PETROLEUM C	837 W 12TH ST	TX HIST UST	532	0.101	WNW
2763 / 11	J J PICKLE FEDERAL O	300 E 8TH ST	TX UST, TX HIST UST, TX ASBESTOS	535	0.101	NNE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
NV2768 / 11	BRADSHAW AND PURYEAR	206 E CESAR CHAVEZ S	TX HIST UST	546	0.103	WNW
PS2782 / 11	AUSTIN LAUNDRY & DRY	911 W 24TH ST	EDR Hist Cleaner	552	0.105	West
QC2784 / 11	C.A. PETERS	719 E 7TH ST	TX HIST UST	553	0.105	ENE
QC2785 / 11	WALSH SERVICE STATIO	719 E 7TH ST	EDR Hist Auto	553	0.105	ENE
NZ2786 / 11	MOBIL STATION	E 7TH ST	TX LPST	555	0.105	ENE
PD2789 / 11	BERANS CONOCO SERV S	1500 SAN JACINTO	EDR Hist Auto	556	0.105	ESE
PD2790 / 11	TEXAS GENERAL SERVIC	1500 SAN JACINTO BLV	TX HIST UST, TX Ind. Haz Waste	556	0.105	ESE
QD2792 / 11	7 ELEVEN 16084	1700 SAN JACINTO BLV	TX UST, TX HIST UST	557	0.105	ESE
QD2793 / 11	BURNETTE SERVICE STA	1700 SAN JACINTO	EDR Hist Auto	557	0.105	ESE
2802 / 11	MESSER & HATCHER	205 W 5TH ST	TX HIST UST	564	0.107	WSW
QF2803 / 11	AUSTIN WATER LIGHT A	W. 5TH STREET	EDR MGP	565	0.107	WNW
QH2805 / 11	HERBERT MEYER	828 W 6TH ST	TX HIST UST	568	0.108	WNW
QI2806 / 11	DOWNTOWN RAILYARD PR	800 E 4TH ST	TX AUL, TX VCP, TX BROWNFIELDS, TX GCC	568	0.108	East
QI2807 / 11	PLAZA SALTILLO	800 E 4TH ST	RCRA NonGen / NLR	568	0.108	East
QK2809 / 11	GENERAL SERVICES COM	1518 SAN JACINTO BLV	RCRA-VSQG, FINDS, ECHO	573	0.109	ESE
QK2810 / 11	GENERAL SERVICES COM	1518 SAN JACINTO BLV	TX LPST, TX HIST UST, TX Ind. Haz Waste	573	0.109	ESE
PD2811 / 11	STATE SERVICE STATIO	1502 SAN JACINTO BLV	TX LPST, TX UST	573	0.109	ESE
QK2812 / 11	DOC & BUSTER SERV	1508 SAN JACINTO	EDR Hist Auto	573	0.109	ESE
PS2813 / 11	AUSTIN LAUNDRY & DRY	913 W 24TH ST	EDR Hist Cleaner	575	0.109	West
QF2817 / 11	SMITH JAY BODY SHOP	832 5TH ST W	EDR Hist Auto	578	0.109	WNW
QM2820 / 11	UNIVERSITY SIGN SHOP	2920 SAN JACINTO	TX RDR	587	0.111	East
QM2821 / 11	UNIVERSITY SIGN SHOP	2920 SAN JACINTO BLV	TX UST, TX HIST UST	587	0.111	East
QM2822 / 11	UT SIGN SHOP	2920 SAN JACINTO BLV	TX NON REGIST PST	587	0.111	East
QN2823 / 11	CAPITOL LAUNDRY	801 BARTON SPRINGS	EDR Hist Cleaner	590	0.112	WNW
QN2824 / 11	CAPITOL LAUNDRY & DR	801 BARTON SPRINGS	EDR Hist Cleaner	590	0.112	WNW
QC2826 / 11	MOBIL MART	717 7TH ST E	EDR Hist Auto	595	0.113	ENE
QC2827 / 11	WALSH SERVICE CENTER	717 7TH ST E	EDR Hist Auto	595	0.113	ENE
PS2830 / 11	CONVENIENCE COIN LAU	915 W 24TH ST	EDR Hist Cleaner	599	0.113	West
2831 / 11	BROWN BROS	1600 SAN JACINTO	EDR Hist Cleaner	599	0.113	ESE
QQ2838 / 11	HUMBLE OIL REFG CO	1800 SAN JACINTO ST	EDR Hist Auto	609	0.115	ESE
QQ2839 / 11	KOCUREK WILLIE	1822 SAN JACINTO ST	EDR Hist Auto	610	0.116	ESE
QQ2840 / 11	WESLEY GEO DCLO CLNR	1818 SAN JACINTO	EDR Hist Cleaner	610	0.116	ESE
QQ2841 / 11	KOCUREKS SERVICE STA	1818 SAN JACINTO	EDR Hist Auto	610	0.116	ESE
QC2842 / 11	WALSH NORMAN SERVICE	719 7TH ST E	EDR Hist Auto	611	0.116	ENE
QC2843 / 11	BROWN & WALSH SERV S	719 7TH E	EDR Hist Auto	611	0.116	ENE
2852 / 11	CENTRAL FREIGHT LINE	901 E 4TH ST	TX HIST UST	620	0.117	East
PD2854 / 11	LES & MACS SERV	301 15TH E	EDR Hist Auto	623	0.118	ESE
PT2858 / 11	TXDOT RIGHT OF WAY	S MLK & E SAN JACINT	TX RDR	636	0.120	ESE
PT2859 / 11	TX DOT ROW	E MARTIN LUTHER KING	TX TANKS, TX CENTRAL REGISTRY	636	0.120	ESE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
QD2863 / 11	DEATHE TEXACO SERV	1701 SAN JACINTO	EDR Hist Auto	642	0.122	ESE
QD2864 / 11	STATE PURCHASING AND	1711 SAN JACINTO BLV	TX ASBESTOS, TX Ind. Haz Waste	642	0.122	ESE
QD2865 / 11	STATE PURCHASING AND	1711 SAN JACINTO BLV	RCRA NonGen / NLR, FINDS, ECHO	642	0.122	ESE
QU2866 / 11	SMITH J E R	305 13TH E	EDR Hist Cleaner	643	0.122	ESE
QK2867 / 11	SAN JACINTO GARAGE	1511 SAN JACINTO ST	EDR Hist Auto	643	0.122	ESE
QC2868 / 11	TETCO #1167	717 E 7TH ST	TX RDR	644	0.122	ENE
QC2869 / 11	MOBIL OIL 00AFT	717 E 7TH ST	RCRA NonGen / NLR	644	0.122	ENE
QC2870 / 11	7-ELEVEN 36422	717 E 7TH ST	TX UST, TX HIST UST, TX ENF, TX Financia...	644	0.122	ENE
QC2871 / 11	MOBIL OIL 00AFT	717 E 7TH ST	TX LPST, TX ASBESTOS, TX Ind. Haz Waste	644	0.122	ENE
QC2872 / 11	WALSH SERVICE CENTER	717 E 7TH ST	EDR Hist Auto	644	0.122	ENE
QC2873 / 11	7-ELEVEN INC STORE N	717 E 7TH ST	TX RDR	644	0.122	ENE
QV2874 / 11	CULLEN SERVICE STA	1407 SAN JACINTO	EDR Hist Auto	644	0.122	ESE
QV2875 / 11	EMMETT SINCLAIR SERV	1409 SAN JACINTO ST	EDR Hist Auto	644	0.122	ESE
QM2880 / 11	PAYLESS GAS NO 657	2805 SAN JACINTO BLV	EDR Hist Auto	647	0.123	East
QX2881 / 11	TRANSMISSION EVENTS	501 N INTERSTATE 35	EDR Hist Auto	648	0.123	East
QU2882 / 11	DAY R L GARAGE	1301 SAN JACINTO ST	EDR Hist Auto	648	0.123	ESE
2886 / 11	SEAHOLM DISTRICT UPR	NO ADDRESS RAILROAD	TX BROWNFIELDS	657	0.124	West
RB2893 / 11	US POSTAL SERVICE AU	300 E 9TH ST	RCRA-VSQG, FINDS, ECHO	680	0.129	ESE
RB2894 / 11	US POSTAL SERVICE AU	300 E 9TH ST	TX Ind. Haz Waste	680	0.129	ESE
QF2905 / 11	LITTLE & GOSLIN	817 W 5TH ST	TX HIST UST	716	0.136	WNW
RF2906 / 11	FREEWHEELING	2404 SAN GABRIEL ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	717	0.136	West
RG2908 / 11	CAPITOL CITY CHEVRON	601 N I 35	TX HIST UST	723	0.137	ENE
RG2914 / 11	EXXON #62790	619 N I 35	TX HIST UST	754	0.143	ENE
RH2915 / 11	AMERICAN CLEANERS	907 W 12TH ST	TX DRYCLEANERS	754	0.143	WNW
RH2916 / 11	AMERICAN CLEANERS	907 W 12TH STREET	RCRA-VSQG	754	0.143	WNW
QX2917 / 11	W.C. ROUNDTREE	900 E 5TH ST	TX HIST UST	770	0.146	East
QX2918 / 11	SOUTHERN PACIFIC TRA	900 E 5TH ST	TX HIST UST	770	0.146	East
QH2920 / 11	RED MCCOMBS COLLISDI	841 W 6TH ST	TX Ind. Haz Waste	778	0.147	WNW
QH2921 / 11	RED MCCOMBS COLLISIO	841 W 6TH STREET	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	778	0.147	WNW
RF2922 / 11	EXXON CO. USA 64674	1004 W 24TH ST	TX HIST UST, TX Ind. Haz Waste	799	0.151	West
RF2923 / 11	EXXON MOBIL	1004 W 24TH ST	TX Ind. Haz Waste	799	0.151	West
RF2924 / 11	EXXON MOBIL CORPORAT	1004 W 24TH ST	RCRA NonGen / NLR, FINDS, ECHO	799	0.151	West
2925 / 11	EMIL HAENEL, JR.	311 E 15TH ST	TX HIST UST	816	0.155	ESE
RG2931 / 11	EXXON RS 62790	619 N IH 35	TX UST, TX Financial Assurance	839	0.159	ENE
RJ2932 / 11	TARGET STORE T3342	901 E 5TH ST STE 140	RCRA-SQG	842	0.159	East
RJ2933 / 11	TARGET STORE T3342	901 E 5TH ST STE 140	TX Ind. Haz Waste	842	0.159	East
RG2935 / 11	PRIME FOOD MART	601 N IH 35	TX UST, TX Financial Assurance	853	0.162	ENE
RL2938 / 11	SAFE WAY RENTAL TOWE	311 BOWIE ST	TX VCP, TX ASBESTOS, TX CENTRAL REGISTRY	857	0.162	WNW
RL2939 / 11	SAFEWAY RENTAL EQUIP	311 BOWIE ST	TX LPST, TX VCP	857	0.162	WNW

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
RL2940 / 11	SAFEWAY RENTAL TRACT	311 BOWIE ST	TX RDR	857	0.162	WNW
RL2941 / 11	SAFEWAY RENTAL EQUIP	311 BOWIE ST	TX UST	857	0.162	WNW
RM2942 / 11	CITY OF AUSTIN	715 E 8TH ST	RCRA NonGen / NLR, FINDS, ECHO	863	0.163	NE
RM2943 / 11	CITY OF AUSTIN POLIC	715 E 8TH ST	TX ASBESTOS, TX Ind. Haz Waste	863	0.163	NE
RM2944 / 11	POLICE DEPARTMENT HE	715 E 8TH ST	TX UST, TX HIST UST, TX Financial Assura...	863	0.163	NE
2945 / 11	UNION PACIFIC REALTY	900 W CESAR CHAVEZ S	TX HIST UST	863	0.163	West
2946 / 11	CLOSED GASOLINE STAT	2803 SAN JACINTO BLV	TX LPST, TX UST, TX HIST UST	864	0.164	East
RP2955 / 11	AUSTIN METAL & IRON	301 SAN MARCOS ST	TX UST, TX HIST UST	886	0.168	ESE
RP2956 / 11	AUSTIN METAL IRON	301 SAN MARCOS ST	TX LPST, TX VCP, TX GCC, TX COMP HIST, T...	886	0.168	ESE
RH2959 / 11	RILEY SEVERN	919 W 12TH ST	TX HIST UST	896	0.170	WNW
RH2960 / 11	RILEY SEVERN	919 W 12TH ST	TX HIST UST	896	0.170	WNW
RR2964 / 11	GEORGE COFFEY LINCOL	900 W 6TH ST	TX HIST UST	907	0.172	WNW
RR2965 / 11	GEORGE COFFEY LINC-M	900 W 6TH	TX UST	907	0.172	WNW
2968 / 11	SEAHOLM DISTRICT UPR	S 3RD STREET BETWEEN	US BROWNFIELDS, FINDS	917	0.174	WNW
RL2969 / 11	PROPOSED SPRING COND	302 BOWIE ST	TX IHW CORR ACTION	928	0.176	WNW
RS2970 / 11	7 ELEVEN STO4RE 3664	814 E 7TH ST	TX LPST, FINDS	929	0.176	ENE
RS2971 / 11	AUSTIN SHELL/STORE 4	814 E 7TH ST	TX RDR	929	0.176	ENE
RS2972 / 11	TP 2519	814 E 7TH ST	TX RDR	929	0.176	ENE
RT2973 / 11	COFFEY LINCOLN MERCU	900 6TH ST	RCRA NonGen / NLR, FINDS, ECHO	929	0.176	ENE
RT2974 / 11	COFFEY LINCOLN MERCU	900 E 6TH ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	929	0.176	ENE
RT2975 / 11	ARMADILLO AUTOMOTIVE	901 E 6TH ST	TX RDR	936	0.177	East
RT2976 / 11	VACANT BRICK BUILDIN	901 E. 6TH STREET	TX HIST UST, TX ASBESTOS	936	0.177	East
RT2977 / 11	ARMADILLO AUTO	901 E 6TH ST	TX HIST UST	936	0.177	East
RL2981 / 11	BALCONES SPORTSWEAR	910 W 3RD ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	940	0.178	WNW
RM2982 / 11	CITY OF AUSTIN FLEET	714 E 8TH ST	RCRA NonGen / NLR, FINDS, ECHO	945	0.179	NE
RM2983 / 11	VES SERVICE CENTER 5	714 E 8TH ST	TX UST, TX HIST UST, TX AIRS, TX Financi...	945	0.179	NE
RM2984 / 11	CITY OF AUSTIN VES S	714 E 8TH ST	TX ASBESTOS, TX Ind. Haz Waste	945	0.179	NE
RX2989 / 11	SOUTHLAND REDDY ICE	901 RED RIVER ST	TX LPST	956	0.181	NE
RX2990 / 11	REDDY ICE	901 RED RIVER ST	TX UST, TX SPILLS	956	0.181	NE
RY2992 / 11	OLD TOWNSENDS TEXACO	2511 SAN JACINTO	TX LPST	976	0.185	East
RY2993 / 11	OLD TOWNSENDS TEXACO	2511 SAN JACINTO BLV	TX HIST UST	976	0.185	East
RX2994 / 11	OAK FARMS DAIRY	611 E 9TH ST	TX HIST UST	978	0.185	NE
RS3000 / 11	JIM TENNISON ONE STO	701 N I 35	TX HIST UST	1015	0.192	ENE
RS3001 / 11	7-ELEVEN #36643	701 N I 35	TX HIST UST	1015	0.192	ENE
SB3005 / 11	KOLPACK PROPERTY	901-905 BARTON SPRIN	TX LPST	1021	0.193	WNW
RJ3006 / 11	SPTCO	SAN MARCOS & E 5TH	TX UST	1024	0.194	East
RS3007 / 11	7-ELEVEN STORE 36643	701 N IH 35	TX UST, TX Financial Assurance	1026	0.194	ENE
RS3012 / 11	TEXACO FOOD MART	701 EAST AVE	TX LPST	1035	0.196	ENE
SD3013 / 11	FORMER UNLIMITED AUT	1023 W 24TH ST	TX UST	1035	0.196	West

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
SD3014 / 11	TEXACO INC	1023 W 24TH ST	TX HIST UST	1035	0.196	West
SD3015 / 11	FORMER UNLIMITED AUT	1023 W 24TH ST	TX RDR	1035	0.196	West
SD3016 / 11	UNLIMITED AUTO SERVI	1023 W 24TH ST	TX HIST UST	1035	0.196	West
RS3017 / 11	TEXACO	701 N IH 35	TX LPST	1035	0.196	ENE
RS3018 / 11	TEXACO	701 N IH 35	TX LPST	1037	0.196	ENE
SF3023 / 11	MRS. WILLIE EAGLETON	1001 N LAMAR BLVD	TX HIST UST	1042	0.197	WNW
3026 / 11	RECREATIONAL EQUIPME	601 N LAMAR BLVD	TX HIST UST, TX ASBESTOS	1043	0.198	WNW
SF3033 / 11	7 ELEVEN 21884	917 N LAMAR BLVD	TX RDR	1053	0.199	WNW
SF3034 / 11	7 ELEVEN STORE 21884	917 N LAMAR BLVD	TX PST STAGE 2, TX CENTRAL REGISTRY	1053	0.199	WNW
SF3035 / 11	7-ELEVEN 21884	917 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1053	0.199	WNW
3036 / 11		1107 N LAMAR BLVD	TX HIST UST	1054	0.200	WNW
RM3038 / 11	WALKER TIRE CO.	814 N I 35	TX HIST UST	1058	0.200	NE
SJ3040 / 11	AUSTIN GAS LIGHT COM	300 MEDINA STREET	SEMS-ARCHIVE	1067	0.202	ESE
RX3043 / 11	SOUTHLAND ICE CO.	612 E 9TH ST	TX HIST UST	1073	0.203	NE
SJ3053 / 11	SALTILLO PLAZA-DOWNT	1000 E. 4TH STREET	US BROWNFIELDS	1098	0.208	East
SJ3054 / 11	SOUTHERN OIL	1000 E 4TH ST	TX HIST UST	1098	0.208	East
SO3064 / 11	WALKER TIRE	814 IH BLVD # 35	TX UST	1124	0.213	NE
3068 / 11	SERVICE BUILDING VEH	304 E 24TH ST	TX LPST, TX UST, TX ASBESTOS	1132	0.214	East
SF3072 / 11	STRAIT MUSIC	10TH & LAMAR	TX UST	1144	0.217	WNW
SR3073 / 11	ODAS JUNG	921 N LAMAR BLVD	TX HIST UST	1145	0.217	WNW
SR3074 / 11	W. L. STARK	921 N LAMAR BLVD	TX HIST UST	1145	0.217	WNW
SS3075 / 11	TEX-CON OIL COMPANY	1200 N LAMAR BLVD	TX HIST UST	1148	0.217	WNW
SS3076 / 11	KWIK MART 1	1200 N LAMAR BLVD	TX LPST, TX UST, TX ASBESTOS, TX ENF, TX...	1148	0.217	WNW
SS3077 / 11	KWIK MART #1	1200 N LAMAR BLVD	TX HIST UST	1148	0.217	WNW
SB3082 / 11	AUSTIN LYRIC OPERA C	905 BARTON SPRINGS R	TX HIST UST, TX RDR	1152	0.218	WNW
3088 / 11	REDDY ICE OAK FARMS	910 RED RIVER ST	TX LPST, TX UST, TX HIST UST	1168	0.221	NNE
3089 / 11	VACANT COMMERCIAL BL	905 E. 7TH ST.	TX HIST UST, TX ASBESTOS	1181	0.224	ENE
3094 / 11	UNIV OF TEXAS DEPT G	CORNER OF 23RD AND S	RCRA NonGen / NLR	1189	0.225	East
SW3095 / 11	1001 E 6TH	1001 E 6TH ST	TX UST, TX HIST UST	1192	0.226	East
SW3096 / 11	PROPOSED CORAZON	1001 E 6TH ST	TX RDR	1192	0.226	East
SR3097 / 11	STRAIT MUSIC CO	908 N LAMAR BLVD	TX HIST UST	1199	0.227	WNW
SS3100 / 11	TERMINIX OF AUSTIN	1206 PARKWAY	TX Ind. Haz Waste	1210	0.229	WNW
SS3101 / 11	TERMINIX INTERNAT'L	1206 PARKWAY	TX HIST UST	1210	0.229	WNW
SS3102 / 11	TERMINIX COMPANY OF	1206 PARKWAY	RCRA NonGen / NLR	1210	0.229	WNW
SS3103 / 11	TERMINIX INTERNATION	1206 PARKWAY	TX LPST, TX UST, TX CENTRAL REGISTRY	1210	0.229	WNW
TA3111 / 11	SAFEWAY RENTAL EQUIP	405 N LAMAR BLVD	TX HIST UST	1239	0.235	WNW
TA3112 / 11	CAPITOL CHEVROLET MA	409 N LAMAR BLVD	TX UST, TX HIST UST	1239	0.235	WNW
TB3113 / 11	WHOLE FOODS MARKET	525 N LAMAR BLVD	TX TANKS	1241	0.235	WNW
TA3114 / 11	AMERICAN CLEANERS	407 N LAMAR BLVD	TX DRYCLEANERS	1249	0.237	WNW

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
TA3115 / 11	CAPITOL CHEVROLET CO	407 N LAMAR BLVD	TX HIST UST	1249	0.237	WNW
TA3116 / 11	C. B. SMITH MOTORS	407 N LAMAR BLVD	TX HIST UST	1249	0.237	WNW
3124 / 11	ROY AND MATIAS VELAS	1020 E 5TH ST	US BROWNFIELDS	1266	0.240	East
TE3128 / 11	TRAVIS COUNTY FLEET	1000 N LAMAR BLVD	TX LPST, TX HIST UST, TX TIER 2	1271	0.241	WNW
TE3129 / 11	FORMER TRAVIS CTY FL	1000 N LAMAR BLVD	TX RDR	1271	0.241	WNW
TE3130 / 11	SATELLITE 5 FLEET MA	1000 N LAMAR BLVD	TX UST, TX HIST UST, TX Financial Assura...	1271	0.241	WNW
TG3134 / 11	RECREATIONAL EQUIPME	1112 N LAMAR BLVD	TX UST, TX ASBESTOS	1277	0.242	WNW
TG3135 / 11	SIMMONS MOTOR CO.	1112 N LAMAR BLVD	TX HIST UST	1277	0.242	WNW
TG3136 / 11	REI LEASE PROPERTY	1112 N LAMAR BLVD	TX HIST UST	1277	0.242	WNW
TE3137 / 11	ONION CREEK VOLKSWAG	1014 N LAMAR BLVD	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	1278	0.242	WNW
TE3138 / 11	TIP TOP CLEANERS	1014 N LAMAR BLVD ST	TX DRYCLEANERS, TX CENTRAL REGISTRY	1278	0.242	WNW
TE3139 / 11	TIP TOP CLEANERS LAU	1014 N LAMAR BLVD ST	TX Ind. Haz Waste	1278	0.242	WNW
SW3140 / 11	A D BURRATTI	1007 E 6TH ST	TX HIST UST	1282	0.243	East
TB3146 / 11	CAPITOL CHEVROLET	501 N LAMAR BLVD	TX LPST, TX UST, TX HIST UST, TX Ind. Ha...	1297	0.246	WNW
TB3147 / 11	CAPITOL CHEVROLET	501 N LAMAR BLVD	TX UST, TX HIST UST, RCRA NonGen / NLR	1297	0.246	WNW
SW3150 / 11	CITIES SERVICE OIL C	1000 E 6TH ST	TX HIST UST	1298	0.246	East
SS3155 / 11	DONS PAINT AND BODY	1006 W 12TH ST	TX AIRS, TX Ind. Haz Waste, TX COMP HIST	1312	0.248	WNW
SS3156 / 11	DONS PAINT AND BODY	1006 W 12TH	RCRA NonGen / NLR, FINDS, ECHO	1312	0.248	WNW
SO3157 / 11	SIGNATURE #9	900 N I 35	TX HIST UST	1314	0.249	NE
3163 / 11	SIGNATURE 9	900 EAST AVE	TX LPST, TX UST, TX Financial Assurance,...	1352	0.256	NE
3165 / 11	LOPEZ PROPERTY	809 E.9TH STREET	US BROWNFIELDS	1416	0.268	ENE
3174 / 11	SPAW GLASS CONSTRUCT	1020 RED RIVER ST	TX LPST	1515	0.287	NNE
3186 / 11	GARDNER IRON AND MET	1201 E 4TH ST	TX VCP, TX HIST UST	1627	0.308	ESE
3195 / 11	CAZARES PROPERTY	1112 E 6TH ST	TX HIST UST, TX IHW CORR ACTION, TX RDR,...	1764	0.334	East
3204 / 11	DOUGHERTY ARTS CENTE	1110 BARTON SPRINGS	TX SWF/LF, TX ASBESTOS	1842	0.349	WNW
3206 / 11	G S TYPESETTERS	410 BAYLOR ST	TX LPST	1908	0.361	WNW
TR3211 / 11	FORMER BRACKENRIDGE	601 E 15TH ST	TX RDR	1926	0.365	ESE
TR3212 / 11	FORMER BRACKENRIDGE	601 E 15TH ST	TX LPST, TX UST, TX HIST UST, TX AIRS, T...	1926	0.365	ESE
TR3213 / 11	CENTRAL HEALTH - BRA	601 E. 15TH STREET	US BROWNFIELDS	1926	0.365	ESE
TR3214 / 11	FORMER BRACKENRIDGE	601 EAST 15TH ST	TX RDR	1926	0.365	ESE
3225 / 11	ATT AUSTIN FACILITY	705 E 12TH ST	TX LPST, TX ASBESTOS	2078	0.394	NE
TU3230 / 11	PLAZA SALTILLO BLK 5	1301 E 5TH ST	TX RDR	2153	0.408	East
TU3231 / 11	PLAZA SALTILLO	1301 E 5TH ST	TX TANKS, TX HIST UST, TX CENTRAL REGIST...	2153	0.408	East
TV3236 / 11	FORMER HAROLD TIEDT	302 S LAMAR BLVD	TX RDR	2231	0.423	WSW
3245 / 11	EBENEZAR BAPTIST CHU	1011 SAN MARCOS ST	TX LPST, TX UST	2281	0.432	ENE
3246 / 11	PHOENIX MOTOR WORKS	1127 W 6TH ST	TX LPST, TX UST, TX HIST UST	2287	0.433	WNW
UB3254 / 11	908 E. 11TH ST (11TH	908 E. 11TH ST	US BROWNFIELDS, FINDS	2312	0.438	NE
UB3255 / 11	912 E. 11TH STREET	912 E. 11TH STREET	US BROWNFIELDS	2345	0.444	NE
UB3257 / 11	916 E. 11TH STREET	916 E. 11TH STREET	US BROWNFIELDS	2372	0.449	NE

MAPPED SITES SUMMARY - FOCUS MAP 11

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
UB3263 / 11	920 E. 11TH ST (11TH	920 E. 11TH ST	US BROWNFIELDS, FINDS	2393	0.453	ENE
UB3266 / 11	903 JUNIPER ST (11TH	903 JUNIPER ST	US BROWNFIELDS, FINDS	2407	0.456	NE
TV3269 / 11	300-302 S LAMAR	300 S LAMAR	TX RDR	2428	0.460	WSW
UB3270 / 11	905 JUNIPER ST (11TH	905 JUNIPER ST.	US BROWNFIELDS, FINDS	2432	0.461	NE
3271 / 11	HABITAT FOR HUMANITY	1407-1411 E. 4TH STR	US BROWNFIELDS, FINDS	2437	0.462	ESE
UB3278 / 11	907 JUNIPER ST (11TH	907 JUNIPER ST	US BROWNFIELDS, FINDS	2459	0.466	NE
3279 / 11	EXXON RS 67897	1104 EAST AVE	TX LPST, TX UST	2469	0.468	ESE
UB3281 / 11	909 JUNIPER ST (11TH	909 JUNIPER ST	US BROWNFIELDS, FINDS	2479	0.470	NE
UB3282 / 11	911 JUNIPER ST (11TH	911 JUNIPER ST	US BROWNFIELDS, FINDS	2493	0.472	NE
3284 / 11	913 JUNIPER ST (11TH	913 JUNIPER ST	US BROWNFIELDS, FINDS	2527	0.479	ENE
3294 / 11	DOUGHERTY ARTS CENTE	1500 TOOMEY RD	US BROWNFIELDS, FINDS	2596	0.492	WSW
UH3297 / 11	SIGNATURE 2	608 S LAMAR AVE	TX RDR	2621	0.496	WNW
UH3298 / 11	TEXACO RETAIL FAC	608 S LAMAR	TX RDR	2621	0.496	WNW
UH3299 / 11	SIGNATURE 2	608 S LAMAR BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	2621	0.496	WNW

Focus Map - 12 - 7418065.7s


E 38th 1/2 St
E 38th St
E 39th St
E 37th St
E 31st St
E 32nd St
E 30th St
E 29th St
E 28th St
E 22nd St
E Martin Luther King Jr Blvd
E 18th St
E 17th St
E 16th St
E 14th St
E 13th St
E 12th St
E 8th St
E 7th St
E 6th St
E 5th St
E 4th St
Anchor Ln
Airport Blvd
Denver Ave
Greenwood Ave
E M Franklin Ave
Alexander Ave
Chicon St
Chicon Ave
Pedernales St
Navarro St
Comal St
Springdale Rd
Pennsylvania Ave
Sol Wilson Ave
Oak Springs Dr
New York Dr
New York Ave
Rosewood Ave
Chestnut Ave
Maple Ave
Cedar Ave
Walnut Ave
Hargrave St
Ridgeway Dr
Crest Ave
Bedford St
Thompson St
Neal St
Govalle Ave
Webberville Rd
Tillery St
Gunter St
Munson St
Prock Ln
Alf Ave
Don Ann St
Saucedo St
Brookswood Ave
Garland Ave
Ebert Ave
Berger St
Mercer Dr
Tannery St
Mendoza Dr
Reyes St
Santa Anna St
Lyons Rd
Zaragosta St
Francisco St
Castro St
Prado St
Gonzales St
Hidalgo St
Diaz St
Chicon St
Comal St
Navarro St
Pedernales St
Shady Ln
Bolm Rd
Milburn Ln
Choate Ave
Guillett St
Walton Ln
Seven Creek Way
Emmitt Run
Perry Rd
Lux St
Stuart Cir
Malkan Dr
Ledesma Rd
Estes Ave
Prock Ln
Chico St
Santa Rosa St
Santa Maria St
Leadbetter Valley Rd
Hollon St
Northwestern Ave
Harvard St
Prospect Ave
San Saba St
Webberville Rd
Lindburg St
Chicon St
Gregg St
Salina St
Hamilton Ave
Tillotson Ave
Bryan St
Poquito St
Coleto St
Alamo St
Chestnut Ave
Alexander Ave
Miriam Ave
Clifford Ave
Sanchez St
Harley St
Wickham Ave
Tillery St
Loreto Dr
Greenwood Ave
Delonay St
Peter St
Seabrook Dr
Adriane Dr
Victoria Dr
Aster Pl
Elmira Rd
Leslie Ave
Glomar Ave
Comalia St
Luna St
Reed St
Moss St
Higgins St
Beckett St
Enclno Cir
Thill Dr
Banton Rd
Grayson Ln
Basford Rd
Giles St
Larry Ln
Merrie Lynn Ave
Walnut Ave
Hemlock Ave
Cherrywood Rd
Lafayette Ave
Kern
Rambler St
Clarkson Ave
Werner Ave
Hollywood Ave
Concordia Ave
Robinson Ave
Harmon
Luther Ln
Kirkwood Rd
Ashwood Rd
Schiefer Ave
Zach Scott St
McCoskey St
Emma Long St
Antone St
Berkman Dr
Goodman St
Thelma St
Harriet St
Martin St
Frank Miller St
Lovell St
Kwood Rd
Rimrock Trl
Marlo Dr
Kitty Ave
Ribbecke Ave
Lott Ave
Santa Anna St
Mason Ave
Garland Ave
Chicon St
Comal St
Navarro St
Pedernales St
Interstate 35
Alpalina St
Gregg St
Salina St
Chicon St
Chalmers Ave
Lindburg St
Harvard St
Prospect Ave
San Saba St
Webberville Rd
Hidalgo St
Diaz St
Chicon St
Comal St
Navarro St
Pedernales St
Leadbetter Valley Rd
Santa Rosa St
Santa Maria St
Hollon St
Northwestern Ave
Tillotson Ave
Hamilton

MAPPED SITES SUMMARY - FOCUS MAP 12

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

Focus Map - 13 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	0 1/4 1/2 Miles
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

SITE NAME:	Austin Light Rail Project - Phase 1	CLIENT:	HDR
ADDRESS:	Austin Light Rail Project - Phase 1	CONTACT:	Kristine Lloyd
CITY/STATE:	Austin TX	INQUIRY #:	7418065.7s
ZIP:	78704	DATE:	08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 13

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
3218 / 13	SS6 1483	530 W BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST	1969	0.373	WNW
3222 / 13	THE CORNER STORE	525 W BEN WHITE BLVD	TX LPST, TX UST, TX ASBESTOS, TX Financi...	2036	0.386	WNW
TT3223 / 13	SERVICE CENTER 11	3616 S 1ST ST	TX LPST, TX ASBESTOS	2048	0.388	WNW
TT3224 / 13	SOUTH 1ST STREET SER	3616A S 1ST ST	TX LPST	2049	0.388	WNW
3229 / 13	C STORE	4111 S 1ST	TX RDR	2117	0.401	WNW
3234 / 13	FORMER QUIKIE PICKIE	600 W BEN WHITE	TX LPST, TX UST	2185	0.414	WNW
UA3252 / 13	7 ELEVEN 26353	601 W BEN WHITE BLVD	TX RDR	2303	0.436	WNW
UA3253 / 13	7-ELEVEN 26353	601 W BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2303	0.436	WNW

Focus Map - 14 - 7418065.7s



SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
EI603 / 14	EDS AUTOMOTIVE	208 RIVERSIDE DR W	EDR Hist Auto	TP
EI604 / 14	MIDAS MUFFLER	207 RIVERSIDE DR W	EDR Hist Auto	TP
EI605 / 14	R&S GARAGE REPRS	205 RIVERSIDE DR W	EDR Hist Auto	TP
EI606 / 14	HAWKINS GARAGE AUTO	205 RIVERSIDE DR W	EDR Hist Auto	TP
EJ607 / 14	C.A. ARMACOST	118 W RIVERSIDE DR	TX HIST UST	TP
EJ608 / 14	REEDYS AUTO WAY	103 RIVERSIDE DR W	EDR Hist Auto	TP
EJ609 / 14	EDDIE SLACKS RIVERSI	400 CONGRESS AVE S	EDR Hist Auto	TP
EJ610 / 14	CHRISTIES CITIES	400 CONGRESS AVE S	EDR Hist Auto	TP
EJ611 / 14	CHESNUTT DON N	401 S CONGRESS	EDR Hist Cleaner	TP
EJ612 / 14	TEXAS CLEANERS	401 CONGRESS AVE S	EDR Hist Cleaner	TP
EJ613 / 14	TEXAS CLEANERS	401 CONGRESS AVE S	EDR Hist Cleaner	TP
EJ614 / 14	BOHLS SERVICE STATIO	401 CONGRESS AVE S	EDR Hist Auto	TP
EJ615 / 14	TEXAS PACIFIC COAL	401 CONGRESS AVE S	EDR Hist Auto	TP
616 / 14	COVERT AUTOMOBILE CO	507 S 1ST ST	TX HIST UST	TP
EK617 / 14	STOP N GO 2066	160 E RIVERSIDE DR	TX UST, TX HIST UST, TX Financial Assura...	TP
EK618 / 14	DIAMOND SHAMROCK 206	160 E RIVERSIDE DR	TX LPST	TP
EK619 / 14	DIAMOND SHAMROCK 206	160 E RIVERSIDE	TX RDR	TP
EK620 / 14	STOP N GO 2066	160 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
621 / 14	TURNER CREST VILLAGE	3.77 MI NE OF INTERX	FINDS, ECHO	TP
EK622 / 14	AUSTIN AMERICAN STAT	305 CONGRESS AVE	RCRA-VSQG, TX UST, TX HIST UST, FINDS, E...	TP
EK623 / 14	AUSTIN AMERICAN STAT	166 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
EL624 / 14	GILBERTS AUTO ELEC	48 EAST AVE	EDR Hist Auto	TP
EL625 / 14	OFFICE BUILDING	48 EAST AVENUE	TX ASBESTOS	TP
EM626 / 14	CAR WELL INC AUTO RE	205 RIVERSIDE DR E	EDR Hist Auto	TP
EM627 / 14	ELLIS & SALAZAR GARA	211 RIVERSIDE DR E	EDR Hist Auto	TP
EN628 / 14	TRIPLE S PETROLEUM C	900 EAST AVE	EDR Hist Auto	TP
EN629 / 14	SIGNATURE 9	900 E AVE	TX RDR	TP
EN630 / 14	SIGNATURE 9	900 EAST AVE	TX CENTRAL REGISTRY	TP
EN631 / 14	SHOPPERS MART 9	900 EAST AVE	FINDS	TP
EO632 / 14	JS MARKET-PLANT - 37	611 S CONGRESS AVE S	FINDS	TP
633 / 14		802 SOUTH 1ST STREET	ERNS	TP
EP634 / 14	CAPITAL CITY TRADE &	205 E RIVERSIDE DR	TX Ind. Haz Waste	TP
EP635 / 14	205 EAST RIVERSIDE,	205 EAST RIVERSIDE,	TX SPILLS	TP
EP636 / 14	CAPITAL CITY TRADE &	205 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	TP
EP637 / 14	UNKNOWN	205 EAST RIVERSIDE	TX SPILLS 90	TP
EP638 / 14	CAPITOL CITY TRADE &	205 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
EQ639 / 14	VACANT BUILDING	901 S. CONGRESS AVE.	TX ASBESTOS	TP
EQ640 / 14	MUSE APARTMENTS	901 S CONGRESS	TX ASBESTOS	TP
ER641 / 14	MUSIC LANE MIXED USE	1100 SOUTH CONGRESS	FINDS, ECHO	TP

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
ER642 / 14	MUSE APARTMENTS	1007 S. CONGRESS AVE	TX ASBESTOS	TP
ER643 / 14	CAMDEN SOUTH CONGRES	1007 S CONGRESS AVE	FINDS	TP
ES644 / 14	BOBS GARAGE	1007 CONGRESS AVE S	EDR Hist Auto	TP
ES645 / 14	KOCUREKS MAGNOLIA	1007 CONGRESS AVE S	EDR Hist Auto	TP
ES646 / 14	CAPITAL SPRING & BRA	1009 CONGRESS AVE S	EDR Hist Auto	TP
ES647 / 14	HANCOCK SERVICE STAT	1101 CONGRESS AVE S	EDR Hist Auto	TP
ET648 / 14	RUBIOLA BROTHERS	1113 S CONGRESS AVE	TX HIST UST	TP
ET649 / 14	NO DELAY CLEANERS	1117 CONGRESS AVE S	EDR Hist Cleaner	TP
ET650 / 14	NO DELAY CLEANERS CL	1117 CONGRESS AVE S	EDR Hist Cleaner	TP
ET651 / 14	MC COWN & LINDER	1123 CONGRESS AVE S	EDR Hist Auto	TP
ET652 / 14	BUTLERS TERRACE GULF	1123 CONGRESS AVE S	EDR Hist Auto	TP
653 / 14	CRAWFORD RESIDENCE	500 EAST RIVERSIDE #	TX ASBESTOS	TP
EU654 / 14	AUSTIN MOTEL	1202 SOUTH CONGRESS	TX ASBESTOS	TP
EU655 / 14	AUSTIN MOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU656 / 14	AUSTIN HOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU657 / 14	AUSTIN HOTEL	1204 SOUTH CONGRESS	TX ASBESTOS	TP
EU658 / 14	1206 S CONGRESS	1206 S. CONGRESS AVE	TX ASBESTOS	TP
EV659 / 14	DONALDSON SAND GRAVE	.75 MILE NE OF FM 43	TX RGA LF	TP
EV660 / 14		6MI E INTRSC FM973/S	TX RGA LF	TP
EU661 / 14	SOUTH AUSTIN CLEAN	1210 CONGRESS AVE S	EDR Hist Cleaner	TP
EU662 / 14	E. C. STEWART	1224 S CONGRESS AVE	TX HIST UST	TP
EU663 / 14	B. E. HOWELL	1224 S CONGRESS AVE	TX HIST UST	TP
EU664 / 14	AUSTIN MOTEL	1224 S CONGRESS	TX ASBESTOS	TP
EU665 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	FINDS	TP
EU666 / 14	INNOVATIVE MEDICAL G	1221 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	TP
EU667 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	RCRA-SQG	TP
EU668 / 14	INNOVATIVE MEDICAL G	1221 1221 S CONGRESS	ECHO	TP
EU669 / 14	STATE HOUSE ON CONGR	1221 SOUTH CONGRESS	TX ASBESTOS	TP
EU670 / 14	LEONS CLEANERS INC	1221 S CONGRESS AVE	EDR Hist Cleaner	TP
EU671 / 14	SHELL IRVING FILLING	1228 CONGRESS AVE S	EDR Hist Auto	TP
EU672 / 14	BURCH H H CONOCO SER	1228 S CONGRESS	EDR Hist Auto	TP
EU673 / 14	BURCH H H SERV STA	1228 CONGRESS AVE S	EDR Hist Auto	TP
EW674 / 14	109 JAMES STREET, SI	109 JAMES STREET, SI	TX SPILLS	TP
EW675 / 14	K T GARAGE & SER	1300 CONGRESS AVE S	EDR Hist Auto	TP
EW676 / 14	CITY WRECKER SERVICE	1300 CONGRESS AVE S	EDR Hist Auto	TP
EW677 / 14	BLUE FRONT FILLING S	1301 CONGRESS AVE S	EDR Hist Auto	TP
EW678 / 14	CARLSON C A FILLING	1301 CONGRESS AVE S	EDR Hist Auto	TP
EX679 / 14	HOLLY SHORES FOOD FO	COMAL STREET AND NAS	US BROWNFIELDS	TP
EX680 / 14	HOLLY SHORES FOOD FO	COMAL STREET AND NAS	FINDS	TP

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
EW681 / 14	PALACE CLEANERS	1313 CONGRESS AVE S	EDR Hist Cleaner	TP
EY682 / 14	HANSON HARRY A CLNR	1315 CONGRESS AVE S	EDR Hist Cleaner	TP
EY683 / 14	SAINT VINCENT	1333 S CONGRESS AVE	FINDS, ECHO	TP
EY684 / 14	SAINT VINCENT	1333 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
EZ685 / 14	SOUTH AUSTIN BAR	1400 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ686 / 14	MEARS DOC CLNRS	1415 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ687 / 14	CAMPION COLOR	1423 CONGRESS AVE S	EDR Hist Cleaner	TP
EZ688 / 14	TOWN 6 COUNTRY CLEAN	1423 CONGRESS AVE S	EDR Hist Cleaner	TP
FA689 / 14	AUSTIN COTTON	409 W MONROE ST	TX CENTRAL REGISTRY	TP
FA690 / 14	AUSTIN COTTON	409 W MONROE ST	TX Ind. Haz Waste	TP
FB691 / 14	A CLEANERS SUB STA	1507 CONGRESS AVE S	EDR Hist Cleaner	TP
FB692 / 14	GRIFFITH W G INDRY	1512 CONGRESS AVE S	EDR Hist Cleaner	TP
FB693 / 14	SOUTH MAIN CLEANERS	1518 CONGRESS AVE S	EDR Hist Cleaner	TP
FB694 / 14	SOUTH AUSTIN LAUN	1518 CONGRESS AVE S	EDR Hist Cleaner	TP
FC695 / 14	DOHERTY L W CLDO	1602 CONGRESS AVE S	EDR Hist Cleaner	TP
FC696 / 14	DOHERTY L W DCLO CLN	1602 CONGRESS AVE S	EDR Hist Cleaner	TP
FC697 / 14	WELLS SAML W AUTO	1606 CONGRESS AVE S	EDR Hist Auto	TP
FC698 / 14	BOBS GARAGE	1606 CONGRESS AVE S	EDR Hist Auto	TP
FC699 / 14	SOUTH AUSTIN CLNRS	1608 CONGRESS AVE S	EDR Hist Cleaner	TP
FC700 / 14	SOUTH AUSTIN CLEANER	1608 CONGRESS AVE S	EDR Hist Cleaner	TP
FC701 / 14	A. F. HARACH	1610 S CONGRESS AVE	TX HIST UST	TP
FD702 / 14	STAR RIVERSIDE	1300 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FD703 / 14	RIVERVIEW APARTMENTS	1300 E. RIVERSIDE DR	TX ASBESTOS	TP
FE704 / 14	BOBS GARAGE REPRS	103 MILTON W	EDR Hist Auto	TP
FE705 / 14	CALDWELL & MILLER	1700 S CONGRESS AVE	TX HIST UST	TP
FE706 / 14	CALDWELL & MILLER	1700 S CONGRESS AVE	TX HIST UST	TP
FE707 / 14	T. J. CALDWELL	1700 S CONGRESS AVE	TX HIST UST	TP
FF708 / 14	RUTLANDS PHILLIPS 66	1610 RIVERSIDE DR E	EDR Hist Auto	TP
FG709 / 14	DYE A D FILL STA	1801 CONGRESS AVE S	EDR Hist Auto	TP
FG710 / 14	DYE SALES & SERVICE	1801 CONGRESS AVE S	EDR Hist Auto	TP
FF711 / 14	SHOPPERS MART 22	1609 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FF712 / 14		1609 EAST RIVERSIDE	ERNS	TP
FF713 / 14	RUTLAND PHILLIPS 66	1609 E RIVERSIDE	EDR Hist Auto	TP
FF714 / 14	SHOPPERS MART 22	1609 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST	TP
FF715 / 14	SIGMOR SHAMROCK SERV	1620 RIVERSIDE DR	EDR Hist Auto	TP
716 / 14	CITY OF AUSTIN BOARD	1820 S LAKESHORE BLV	TX CENTRAL REGISTRY	TP
717 / 14	SOUTHSHORE TOWNHOMES	1201 TOWN CREEK DR	TX CENTRAL REGISTRY	TP
FH718 / 14	TEXAS AUTOMOTIVE SER	2006 CONGRESS AVE S	EDR Hist Auto	TP
FH719 / 14	HUGHES LAUNDERETTE	2006 CONGRESS AVE S	EDR Hist Cleaner	TP

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
FI720 / 14	ACME CLEANERS	1800 RIVERSIDE DR E	EDR Hist Cleaner	TP
FI721 / 14	KWIK WASH COIN LAUND	1723 RIVERSIDE DR E	EDR Hist Cleaner	TP
FI722 / 14	KWIK WASH COIN LAUND	1723 RIVERSIDE DR	EDR Hist Cleaner	TP
FI723 / 14	KAVECKI TEXACO SE	1725 RIVERSIDE DR E	EDR Hist Auto	TP
FI724 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP
FI725 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX ENF, TX COMP HIST	TP
FI726 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FI727 / 14	RIVERSIDE GROCERY	1727 E RIVERSIDE DR	FINDS, ECHO	TP
FI728 / 14	7-ELEVEN 23076	1729 E RIVERSIDE DR	TX UST, TX HIST UST	TP
FI729 / 14	7 ELEVEN 23076	1729 E RIVERSIDE DR	FINDS	TP
FI730 / 14	7 ELEVEN 23076	1729 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FH731 / 14	QUALITY WHOL LNDRY	2006 CONGRESS AVE	EDR Hist Cleaner	TP
FJ732 / 14	TOWN LAKE PLAZA ASTR	1900 RIVERSIDE DR E	EDR Hist Cleaner	TP
FJ733 / 14	JIMS RIVERSIDE GULF	1801 RIVERSIDE DR E	EDR Hist Auto	TP
FK734 / 14	7-ELEVEN INC 22245	2103 S CONGRESS AVE	TX RDR	TP
FK735 / 14	7 ELEVEN STORE 22245	2103 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
FK736 / 14	7 11 STORE 22245	2103 S CONGRESS AVE	TX RDR	TP
FK737 / 14	7 ELEVEN STORE 22245	2103 S CONGRESS AVE	FINDS	TP
FK738 / 14	7-ELEVEN 22245	2103 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP
FK739 / 14	SIGMOR SHAMROCK SERV	2105 CONGRESS AVE S	EDR Hist Auto	TP
FK740 / 14	TUCKER & RILEY GARAG	2100 CONGRESS AVE S	EDR Hist Auto	TP
FK741 / 14	BOHLS SERVICE STATIO	2109 CONGRESS AVE S	EDR Hist Auto	TP
742 / 14	MAJESTIC CLEANERS	2114 CONGRESS AVE S	EDR Hist Cleaner	TP
FL743 / 14	TOWN LAKE PLAZA SHOP	1918 E RIVERSIDE DR	TX VCP, TX GCC	TP
FL744 / 14	TOWN LAKE PLAZA SHOP	1918 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FL745 / 14	TOWN LAKE PLAZA SHOP	1918 EAST RIVERSIDE	TX GCC	TP
FL746 / 14	SOUTHSHORE RETAIL	1920 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FM747 / 14	RILEYS LIVE OAK	2121 CONGRESS AVE S	EDR Hist Auto	TP
FM748 / 14	JOHNSON T J FILL STA	2201 CONGRESS AVE S	EDR Hist Auto	TP
FN749 / 14	HIGGINS AUTOMOTIVE	2202 CONGRESS AVE S	EDR Hist Auto	TP
FO750 / 14	RIVERSIDE TEXACO	2000 RIVERSIDE DR E	EDR Hist Auto	TP
FN754 / 14	KWIK WASH COIN LAUND	2209 CONGRESS AVE S	EDR Hist Cleaner	TP
FO755 / 14	WALGREEN 2915	2020 E RIVERSIDE DR	RCRA-SQG, FINDS, ECHO	TP
FO756 / 14	WALGREENS	2020 E RIVERSIDE DR	TX ASBESTOS, TX Ind. Haz Waste	TP
FO757 / 14	WALGREENS 2915	2020 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
FQ758 / 14	BOHOT ENCO PRODUCTS	2300 CONGRESS AVE S	EDR Hist Auto	TP
FQ759 / 14	MASON BROS SERV	2300 CONGRESS AVE S	EDR Hist Auto	TP
FQ760 / 14	JOHNSON HUGO C	2215 CONGRESS AVE S	EDR Hist Auto	TP
FQ761 / 14	JOHNSON HUGO SERV	2215 CONGRESS AVE S	EDR Hist Auto	TP

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
FQ762 / 14	BROWN JACK CLEANERS	2215 CONGRESS AVE S	EDR Hist Cleaner	TP
FR763 / 14	KENNETH A ROBERTSON	RIVERSIDE & BURTON	TX UST	TP
FR764 / 14	KENNETH A ROBERTSON	RIVERSIDE & BURTON	FINDS	TP
FS765 / 14	EAST BOULDIN-EUCLID-	2400-2600 EUCLID, 24	TX CENTRAL REGISTRY	TP
FS766 / 14	TEJAS WATER HAULERS	2405 FOREST AVE	TX CENTRAL REGISTRY	TP
FT767 / 14	ONE HOUR MARTINIZING	2326 CONGRESS AVE S	EDR Hist Cleaner	TP
FT768 / 14	TWIN OAKS SERV STA	2315 CONGRESS AVE S	EDR Hist Auto	TP
FT769 / 14	TWIN OAKS GULF SERVI	2315 CONGRESS AVE S	EDR Hist Auto	TP
FT770 / 14	SOUTH AUSTIN CONOCO	2332 S CONGRESS	EDR Hist Auto	TP
FT771 / 14	ES 3S MC ANGUS MILFO	2323 CONGRESS AVE S	EDR Hist Auto	TP
FT772 / 14	SOUTH AUSTIN CONOCO	2336 CONGRESS AVE S	EDR Hist Auto	TP
FT773 / 14	S AUSTIN CONOCO	2336 CONGRESS AVE S	EDR Hist Auto	TP
FT774 / 14	INSPIRED MOVEMENT	2311 S CONGRESS AVE	TX ASBESTOS	TP
FT775 / 14	FORMER SUBWAY	2315 S CONGRESS AVE	TX ASBESTOS	TP
FT776 / 14	TWIN OAKS SERV	2315 CONGRESS AVE	EDR Hist Auto	TP
FU777 / 14	TWIN OAKS MOBIL GAS	2401 CONGRESS AVE S	EDR Hist Auto	TP
FU778 / 14	ODAS JUNG	104 E OLTORF ST	TX HIST UST	TP
FU782 / 14	ACE MART RESTAURANT	2415 S CONGRESS AVE	TX ASBESTOS	TP
FW783 / 14	THE JEWEL APARTMENTS	1616 ROYAL CREST	TX ASBESTOS	TP
FW784 / 14	JEWEL APARTMENTS	1616 ROYAL CREST DRI	TX ASBESTOS	TP
785 / 14		2515 WILSON ST	DOT OPS	TP
786 / 14	2501 SOUTH CONGRESS	2501 SOUTH CONGRESS	TX ASBESTOS	TP
FX787 / 14		2610 EUCLID AVE	TX LEAD	TP
FY788 / 14	SEMATECH CONSTRUCTIO	550 OLTORF ST E	ICIS, FINDS, ECHO	TP
789 / 14	OAKS APARTMENTS, AUS	OAKS APARTMENTS, AUS	TX SPILLS	TP
FX790 / 14		2612 EUCLID AVE	TX LEAD	TP
FZ791 / 14	GARDNER BETTS JUVENI	2515 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
FZ792 / 14	GARDNER BETTS JUVENI	2515 SOUTH CONGRESS	TX ASBESTOS	TP
FZ793 / 14	GARDNER BETTS JUVENI	2515 S CONGRESS AVE	TX UST, TX HIST UST	TP
GA794 / 14	DRY CLEAN USA	2410 E RIVERSIDE	EDR Hist Cleaner	TP
GA795 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	FINDS	TP
GA796 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP
GA797 / 14	RIVERSIDE PLACE SHOP	2410 E RIVERSIDE DR	TX VCP, TX ASBESTOS	TP
FZ798 / 14	KASSON BILL YAMAHA M	2603 CONGRESS AVE S	EDR Hist Auto	TP
GB799 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX UST, TX HIST UST, TX Financial Assura...	TP
GB800 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX TIER 2	TP
GB801 / 14	SOUTHWESTERN BELL TE	201 CUMBERLAND RD	TX LPST	TP
GB802 / 14	HICKORY 442 XP2995	201 CUMBERLAND RD	TX CENTRAL REGISTRY	TP
GB803 / 14	AUSTIN HICKORY 442 C	201 CUMBERLAND RD	TX AST	TP

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
GC804 / 14	SHOP N SAVE	2204 WOODLAND AVE	TX CENTRAL REGISTRY	TP		
GC805 / 14	SHOP N SAVE	2204 WOODLAND AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	TP		
GC806 / 14	T M T INC	2204 WOODLAND DR	EDR Hist Auto	TP		
GC807 / 14	HNQ INC DBA SHOP N S	2204 WOODLAND AVE	FINDS	TP		
GD808 / 14	HENDRICKS TOM AUTO B	2701 CONGRESS AVE S	EDR Hist Auto	TP		
GD809 / 14	TWIN OAKS SHELL SERV	2704 CONGRESS AVE S	EDR Hist Auto	TP		
GD810 / 14	WHITTS SERV STA	2704 CONGRESS AVE S	EDR Hist Auto	TP		
GD811 / 14	SOULE MARK AUTOMOTIV	2716 CONGRESS AVE S	EDR Hist Auto	TP		
GE812 / 14	MCSPADDEN AUTOMOTIVE	2716 S CONGRESS AVE	FINDS	TP		
GE813 / 14	MCSPADDEN AUTOMOTIVE	2716 SOUTH CONGRESS,	TX SPILLS	TP		
GG815 / 14	KWIK WASH COIN LAUND	3004 CONGRESS AVE S	EDR Hist Cleaner	TP		
GG816 / 14	ATX FOOD MART	3002 S CONGRESS AVE	TX ASBESTOS	TP		
GG817 / 14	STN ENTERPRISES INC	3002 S CONGRESS AVE	EDR Hist Auto	TP		
GG818 / 14	ST. JOSEPH HALL	3001 CONGRESS AVE.	TX ASBESTOS	TP		
819 / 14	A ONE RADIATOR SERVI	3405 CONGRESS AVE S	EDR Hist Auto	TP		
GK827 / 14	SOUTH CONGRESS FOOD	3602 S CONGRESS AVE	TX ASBESTOS	TP		
GM832 / 14	SIGMOR SHAMROCK SERV	3630 CONGRESS AVE S	EDR Hist Auto	TP		
GM833 / 14	MACHEN LEE SPECIAL A	3634 CONGRESS AVE S	EDR Hist Auto	TP		
GM834 / 14	DYE BILL AUTOMOTIVE	3716 CONGRESS AVE S	EDR Hist Auto	TP		
GN835 / 14	GREYSTAR DEVELOPMENT	3801 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
GN836 / 14	SOCO CLEANERS & ALTE	3801 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
GN837 / 14	GREYSTAR DEVELOPMENT	3801 S CONGRESS AVE	FINDS	TP		
GN838 / 14	SOCO CLEANERS & ALTE	3801 S CONGRESS AVE	TX DRYCLEANERS	TP		
GN839 / 14	SOCO CLEANER & ALTER	3801 S CONGRESS AVE	EDR Hist Cleaner	TP		
GN840 / 14	YOUNG TROY H GULF SE	3800 CONGRESS AVE S	EDR Hist Auto	TP		
GO841 / 14	TWO-STORY OFFICE / R	3804 S. CONGRESS AVE	TX ASBESTOS	TP		
GO845 / 14	A A LOTUS AUTO CENTE	3822 CONGRESS AVE S	EDR Hist Auto	TP		
GR854 / 14	YOUNG TROY GULF	3900 CONGRESS AVE S	EDR Hist Auto	TP		
GR855 / 14	KAYO SERVICE STATION	3903 CONGRESS AVE S	EDR Hist Auto	TP		
GR856 / 14	FINANCIAL RESOURCE M	3905 S CONGRESS AVE	TX HIST UST	TP		
GD947 / 14	TEXAN MKT 5	2700 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	60	0.011	WNW
FG952 / 14	HI TECH AUTOMOTIVE	1801 S CONGRESS AVE	TX RDR	60	0.011	ESE
FG953 / 14	HI TECH AUTOMOTIVE	1801 S CONGRESS AVE	TX UST, TX ENF, TX NON REGIST PST	60	0.011	ESE
FG954 / 14	A. D. DYE	1801 S CONGRESS AVE	TX HIST UST	60	0.011	ESE
FG955 / 14	DYE CHARLES	1801 S CONGRESS	EDR Hist Auto	60	0.011	ESE
FG956 / 14	DYE AUTOMOTIVE	1801 S CONGRESS AVE	TX HIST UST	60	0.011	ESE
EW985 / 14	TOM E. SHORT	1301 S CONGRESS AVE	TX HIST UST	62	0.012	ESE
FO1015 / 14	WALGREENS	2000 E RIVERSIDE DR	TX RDR	65	0.012	NE
FO1016 / 14	UMPHRIES BILL TEXACO	2000 E RIVERSIDE	EDR Hist Auto	65	0.012	NE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
FO1017 / 14	TEXACO	2000 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX GCC	65	0.012	NE
FT1023 / 14	CVS PHARMACY 6844	2301 2301 S CONGRESS	RCRA NonGen / NLR, FINDS, ECHO	65	0.012	ESE
FT1024 / 14	CVS PHARMACY	2301 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	65	0.012	ESE
FR1026 / 14	TOWNLAKE CLEANERS	2017 RIVERSIDE DR E	EDR Hist Cleaner	65	0.012	SW
FL1028 / 14	RIVER HILLS SHOPPING	1901 RIVERSIDE DR	EDR Hist Cleaner	66	0.013	WSW
EO1031 / 14	TOWNE PARK LTD	611 S CONGRESS AVE	EDR Hist Cleaner	66	0.013	ESE
FO1066 / 14	HUDSON OIL CO NO 91	2001 RIVERSIDE DR E	EDR Hist Auto	68	0.013	SW
FO1067 / 14	BEVERAGE BARN	2001 RIVERSIDE	TX RDR	68	0.013	SW
ET1073 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX HIST LF	68	0.013	WNW
ET1074 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX CLI	68	0.013	WNW
ET1075 / 14	CONGRESS AVE	1200 BLK CONGRESS AV	TX CLI	68	0.013	WNW
EQ1086 / 14	SOUTH CONGRESS OFFIC	907 S CONGRESS AVE	TX HIST UST	69	0.013	ESE
EQ1087 / 14	PACIFIC SOUTHWEST BA	907 S CONGRESS AVE	TX LPST, TX UST	69	0.013	ESE
EQ1088 / 14	LON MARTIN	907 S CONGRESS AVE	TX HIST UST	69	0.013	ESE
FE1093 / 14	MONKEY SEE MONKEY DO	1712 S CONGRESS AVE	EDR Hist Cleaner	70	0.013	WNW
FE1106 / 14	D. F. WRIGHT	1710 S CONGRESS AVE	TX HIST UST	71	0.013	WNW
ES1108 / 14	C A SCHUTZE AGENCY	1101 S CONGRESS AVE	TX RDR	71	0.013	ESE
ER1109 / 14	TWOMEY AUTO WORKS	1009 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	71	0.013	ESE
ER1110 / 14	FORMER TWOMEYS AUTO	1009 S CONGRESS AVE	TX RDR	71	0.013	ESE
ER1111 / 14	TWOMEY AUTO WORKS AU	1009 S CONGRESS AVE	TX TANKS, TX ASBESTOS, TX Ind. Haz Waste...	71	0.013	ESE
ER1112 / 14	TWOMEY AUTO	1009 S. CONGRESS AVE	TX HIST UST	71	0.013	ESE
ER1113 / 14	MAGNOLIA PETROLEUM C	1009 S CONGRESS AVE	TX HIST UST	71	0.013	ESE
1123 / 14	L. L. EARNEST	1822 S CONGRESS AVE	TX HIST UST	72	0.014	WNW
FQ1124 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	TX HIST UST	72	0.014	East
FQ1125 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	72	0.014	East
FQ1126 / 14	BROWN JACK CLEANERS	2215 S CONGRESS AVE	EDR Hist Cleaner	72	0.014	East
FQ1127 / 14	W. L. MOORE	2215 S CONGRESS AVE	TX HIST UST	72	0.014	East
FQ1128 / 14	WALLACE TEXACO	2215 CONGRESS AVE	EDR Hist Auto	72	0.014	East
FQ1129 / 14	JACK BROWN CLEANERS	2215 S CONGRESS AVE	TX LPST, TX UST, TX DRYCLEANERS, TX Ind....	72	0.014	East
FQ1130 / 14	RAMIREZ TEXACO STATI	2215 S CONGRESS	EDR Hist Auto	72	0.014	East
GR1144 / 14	YOUNG TROY H GULF	3900 CONGRESS AVE	EDR Hist Auto	74	0.014	WNW
1151 / 14	FORMER AUTO SALES FA	118 E RIVERSIDE DR	TX RDR	74	0.014	NE
GO1160 / 14	ENVIRONMENTAL IMPACT	3800 S CONGRESS AVE	TX LPST	75	0.014	WNW
1188 / 14	DRAKE CONDOMINIUMS	68 RAINEY ST	TX VCP	77	0.015	ESE
GE1199 / 14	WITTS SERV STA	2704 CONGRESS AVE	EDR Hist Auto	79	0.015	WNW
1211 / 14	WHITES GARAGE FILLIN	304 JOHANNA W	EDR Hist Auto	81	0.015	ESE
FF1266 / 14	DIAMOND SHAMROCK 236	1620 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX Financi...	88	0.017	NE
FF1267 / 14	DIAMOND SHAMROCK INC	1620 E RIVERSIDE	EDR Hist Auto	88	0.017	NE
FL1281 / 14	BROWN JACK CLEANERS	1901 E RIVERSIDE DR	EDR Hist Cleaner	91	0.017	WSW

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
FL1282 / 14	JACK BROWN CLEANERS	1901 E RIVERSIDE DR	TX DRYCLEANERS	91	0.017	WSW
FQ1301 / 14	STONE BOB	2300 S CONGRESS AVE	EDR Hist Auto	94	0.018	West
FQ1302 / 14	STONES TEXACO	2300 S CONGRESS AVE	TX LPST, TX UST	94	0.018	West
FQ1303 / 14	STONE'S TEXACO	2300 S CONGRESS AVE	TX HIST UST	94	0.018	West
FQ1304 / 14	MRS. J. TADLOCK/ HUM	2300 S CONGRESS AVE	TX HIST UST	94	0.018	West
FL1311 / 14	FAMILY DOLLAR #1700	1917 E. RIVERSIDE DR	RCRA-VSQG	96	0.018	WSW
FI1318 / 14	THE OIL EXCHANGE	1806 E RIVERSIDE DR	TX UST, TX HIST UST	98	0.019	ENE
EJ1333 / 14	SHERRILL'S EXXON	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1334 / 14	M. H. CROCKETT	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1335 / 14	M. H. CROCKETT	343 S CONGRESS AVE	TX HIST UST	102	0.019	NE
EJ1336 / 14	PAUL SHERRILLS EXXON	343 S CONGRESS AVE	EDR Hist Auto	102	0.019	NE
EJ1337 / 14	EXXON SS6 0015	343 S CONGRESS AVE	TX LPST, TX UST	102	0.019	NE
ET1343 / 14	ACE CLEANERS & ALTER	1117 S CONGRESS AVE	TX DRYCLEANERS	103	0.020	ESE
ET1344 / 14	NO DELAY CLEANERS	1117 S CONGRESS	EDR Hist Cleaner	103	0.020	ESE
ET1346 / 14	BUTLER WILLIAM A	1123 S CONGRESS	EDR Hist Auto	103	0.020	ESE
ET1347 / 14	DOCS AUTO WORKS	1123 S CONGRESS AVE	TX RDR	103	0.020	ESE
ET1348 / 14	MUSIC LANE OWNER, LL	1123 S. CONGRESS AVE	TX HIST UST	103	0.020	ESE
ET1349 / 14	W. W. ROGERS	1123 S CONGRESS AVE	TX HIST UST	103	0.020	ESE
ET1350 / 14	DOCS BACK YARD	1123 SOUTH CONGRESS	TX LPST, TX ASBESTOS, TX GCC, TX RDR	103	0.020	ESE
FU1372 / 14	MRS. JAS. R. HAMILTO	2401 S CONGRESS AVE	TX HIST UST	106	0.020	SE
FU1373 / 14	HARLESS MOBIL	2401 S CONGRESS AVE	TX HIST UST	106	0.020	SE
FU1374 / 14	MOBIL SS 12 D93	2401 S CONGRESS AVE	TX LPST, TX UST	106	0.020	SE
FU1375 / 14	CHARLES DIRK TALBOT	2401 S CONGRESS AVE	EDR Hist Auto	106	0.020	SE
FU1376 / 14	MOBIL OIL CORPORATIO	2401 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	106	0.020	SE
FU1377 / 14	MOBIL OIL	2401 S CONGRESS AVE	TX Ind. Haz Waste	106	0.020	SE
EW1412 / 14	E. C. STEWART	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1413 / 14	TRIBBLE ADV. COMPANY	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1414 / 14	A. A. ECK	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
EW1415 / 14	MR. J. M. CAPERTON	1300 S CONGRESS AVE	TX HIST UST	114	0.022	WNW
FT1424 / 14	BEN H. POWELL	2304 S CONGRESS AVE	TX HIST UST	116	0.022	WNW
FT1425 / 14	GULF OIL COMPANY	2304 S CONGRESS AVE	TX HIST UST	116	0.022	WNW
JF1432 / 14	LOOMIS ARMORED AUSTI	78 EAST AVE	TX UST	118	0.022	ESE
1438 / 14	JAMES DREW RENTAL	406 EAST AVE	TX LPST	119	0.023	ESE
1454 / 14	ABC MOBILE BRAKE	519 S 1ST ST	EDR Hist Auto	120	0.023	WNW
FK1459 / 14	MS EXPRESS 901	2105 S CONGRESS AVE	TX LPST, TX UST, TX ASBESTOS, TX ENF, TX...	121	0.023	ESE
FK1460 / 14	E. M. BOHLS	2105 S CONGRESS AVE	TX HIST UST	121	0.023	ESE
FK1461 / 14	HOUSTON CONVENIENCE	2105 S CONGRESS AVE	TX RDR	121	0.023	ESE
FK1462 / 14	DIAMOND SHAMROCK	2105 S CONGRESS	EDR Hist Auto	121	0.023	ESE
FK1463 / 14	EVERYTIME FOOD MART	2105 S CONGRESS AVE	TX HIST UST	121	0.023	ESE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
JJ1470 / 14	THE SHERWIN-WILLIAMS	500 E OLTORF ST	RCRA NonGen / NLR, FINDS, ECHO	122	0.023	NW
JJ1471 / 14	SHERWIN WILLIAMS	500 E OLTORF ST	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	122	0.023	NW
JF1473 / 14	GILBERTS AUTO ELECTR	84 EAST AVE	EDR Hist Auto	122	0.023	ESE
FY1480 / 14	GUEROS ADDL SP	616 OLTORF ST E	EDR Hist Cleaner	123	0.023	SE
FG1485 / 14	BUSH NET	105 E ANNIE	EDR Hist Auto	124	0.023	ESE
FB1492 / 14	WASHBURNS TOWN & COU	1423 S CONGRESS AVE	EDR Hist Cleaner	124	0.023	ESE
FB1493 / 14	WASHBURNS TOWN & COU	1423 S CONGRESS AVE	TX DRYCLEANERS	124	0.023	ESE
1496 / 14	LMN CORP	1603 S CONGRESS AVE	TX HIST UST	125	0.024	ESE
EK1497 / 14	W. T. CASWELL	501 S CONGRESS AVE	TX HIST UST	125	0.024	SW
EH1504 / 14	DEEP EDDY RUG CLEANE	418 BARTON SPRINGS	EDR Hist Cleaner	127	0.024	SE
EH1505 / 14	A KISS CLEAN	418 BARTON SPRINGS	EDR Hist Cleaner	127	0.024	SE
JF1509 / 14	TEXACO SHOPPERS MART	90 EAST AVE	TX RDR	128	0.024	ESE
GM1513 / 14	SOCO CENTER	3630 S CONGRESS AVE	TX LPST, TX UST, TX VCP, TX HIST UST, TX...	130	0.025	WNW
GM1514 / 14	DIAMOND SHAMROCK NO	3630 S CONGRESS ST	TX RDR	130	0.025	WNW
GM1515 / 14	SOUTH CONGRESS FOOD	3630 S CONGRESS AVE	TX RDR	130	0.025	WNW
EL1521 / 14	AEGIS ASSOCIATES INC	44 EAST AVE STE 100	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	131	0.025	ESE
FY1524 / 14	BROWNS TWIN OAKS 66	620 OLTORF ST E	EDR Hist Auto	132	0.025	SE
FU1527 / 14	SPEEDY ALIGNMENT WHE	111 OLTORF ST E	EDR Hist Auto	132	0.025	SE
EH1545 / 14	DEEP EDDY RUG CINS	414 BARTON SPRINGS	EDR Hist Cleaner	133	0.025	SE
EZ1548 / 14	CEN TEX NISSAN	1400 S CONGRESS AVE	TX UST, TX HIST UST	133	0.025	WNW
EZ1549 / 14	CEN-TEX NISSAN INC	1400 S CONGRESS	TX LPST, RCRA NonGen / NLR, FINDS, ECHO,...	133	0.025	WNW
EY1561 / 14	B. E. HOWELL	1316 S CONGRESS AVE	TX HIST UST	135	0.026	WNW
1595 / 14	STOP N SAVE 3	1800 BURTON DR	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	139	0.026	ENE
FT1605 / 14	BROWN & ELLIOTT INC	2326 S CONGRESS	EDR Hist Cleaner	140	0.027	WNW
1611 / 14	METROLOGY LABORATORY	119 CUMBERLAND RD	TX Ind. Haz Waste	140	0.027	NE
FJ1618 / 14	SPICK SPAN LAUNDRY	1421 ARENA DR	EDR Hist Cleaner	142	0.027	ENE
1620 / 14	A. E. SULLIVAN	400 W MONROE ST	TX HIST UST	142	0.027	WNW
EJ1640 / 14	RIVERSIDE CHEVRON	400 S CONGRESS AVE	TX LPST, TX UST, TX ASBESTOS, TX Financi...	145	0.027	WNW
EJ1641 / 14	RIVERSIDE CHEVRON	400 SOUTH CONGRESS A	TX RDR	145	0.027	WNW
EJ1642 / 14	RIVERSIDE SHELLSHAPE	400 S CONGRESS	EDR Hist Auto	145	0.027	WNW
EJ1643 / 14	RIVERSIDE CHEVRON	400 S CONGRESS AVE	TX HIST UST	145	0.027	WNW
EJ1644 / 14	R.E. LEIGH	400 S CONGRESS AVE	TX HIST UST	145	0.027	WNW
FY1671 / 14	TWIN OAKS PHILLIPS 6	620 E OLTORF	EDR Hist Auto	148	0.028	SE
FO1674 / 14	CLOSED CAR WASH	1510 TOWN CREEK DR.	TX HIST UST	149	0.028	NE
FU1682 / 14	CONTINENTAL OIL COMP	2336 S CONGRESS AVE	TX HIST UST	152	0.029	NW
FU1683 / 14	SOUTH AUSTIN CONOCO	2336 CONGRESS AVE	EDR Hist Auto	152	0.029	NW
EM1694 / 14	CENTRAL TEXAS EQUIPM	127 E RIVERSIDE DR	TX LPST, TX UST, TX VCP, TX HIST UST	153	0.029	SW
JX1695 / 14	OSF CONGRESS	2701 S CONGRESS AVE	TX TANKS, TX HIST UST, TX CENTRAL REGIST...	154	0.029	NNE
JX1696 / 14	OSF CONGRESS LP	2701 S CONGRESS	TX RDR	154	0.029	NNE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
GK1697 / 14	DALES AUTO PARTS & M	3600 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	155	0.029	WNW
GK1698 / 14	SIGMOR NUMBER 232 IN	3600 S CONGRESS AVE	EDR Hist Auto	155	0.029	WNW
GK1699 / 14	DALES AUTO PARTS & M	3600 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	155	0.029	WNW
KA1718 / 14	BEVERAGE BARN	2001 E RIVERSIDE BLV	TX RDR	162	0.031	SW
KA1719 / 14	BEVERAGE BARN	2001 EAST RIVERSIDE	TX RDR	162	0.031	SW
KA1720 / 14	BEVERAGE BARN	2001 E RIVERSIDE	TX RDR	162	0.031	SW
KA1721 / 14	BEVERAGE BARN	2001 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	162	0.031	SW
1726 / 14	GOLDIE CORPORATION	3822 S CONGRESS AVE	EDR Hist Auto	163	0.031	WNW
1736 / 14	B & M AUTOMOTIVE AUT	511 LIVE OAK ST W	EDR Hist Auto	167	0.032	WNW
KD1738 / 14	SHELL MINI MART 2	3906 S CONGRESS AVE	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	168	0.032	WNW
KD1739 / 14	SHELL	3906 S CONGRESS AVE	TX RDR	168	0.032	WNW
KD1740 / 14	BISHOP GARY	3906 S CONGRESS AVE	EDR Hist Auto	168	0.032	WNW
KD1741 / 14	TEXACO SERVICE STATI	3906 S CONGRESS	TX RDR	168	0.032	WNW
1742 / 14	A & M TRAILER REPAIR	2702 SHERWOOD LN	EDR Hist Auto	168	0.032	SSE
KE1744 / 14	STEWART DON A INC	3909 S CONGRESS AVE	EDR Hist Auto	168	0.032	ESE
KE1745 / 14	SOUTH CONGRESS CHEVR	3909 S CONGRESS AVE	TX HIST UST	168	0.032	ESE
KE1746 / 14	CONGRESS CHEVRON	3909 S CONGRESS AVE	TX UST, TX ASBESTOS, TX ENF, TX Financia...	168	0.032	ESE
KE1747 / 14	AUSTIN ARMATURE WORK	3909 S CONGRESS AVE	TX HIST UST	168	0.032	ESE
KF1748 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	169	0.032	ESE
KF1749 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	RCRA NonGen / NLR, FTTS, HIST FTTS, FIND...	169	0.032	ESE
KF1750 / 14	TEXAS SCHOOL FOR THE	1102 S CONGRESS AVE	TX ASBESTOS, TX LEAD, TX Ind. Haz Waste,...	169	0.032	ESE
1751 / 14	RED BALL TAXI CO.	301 W RIVERSIDE DR	TX HIST UST	170	0.032	SW
GO1763 / 14	DOCS SMALL ENGINE RE	104 KREBS LN	EDR Hist Auto	174	0.033	WNW
1789 / 14	TEXAS PEST CONTROL	3510 CONGRESS AVE	EDR Hist Cleaner	179	0.034	WNW
KN1802 / 14	BEN HIBBETTS	1725 E RIVERSIDE DR	TX UST	183	0.035	WSW
KN1820 / 14	PARKER LN AND RIVERS	PARKER LN AND RIVERS	TX CLI	189	0.036	WSW
KN1821 / 14	PARKER LN & RIVERSID		TX CLI	189	0.036	WSW
KN1822 / 14	PARKER LN & RIVERSID		TX HIST LF	189	0.036	WSW
JX1823 / 14	BILL KASSON MOTORCYC	2603 S CONGRESS AVE	TX HIST UST, TX ASBESTOS	189	0.036	SE
FU1845 / 14	FAMILY DOLLAR #3834	118 E. OLTORF ST	RCRA-VSQG	198	0.038	SE
GS1849 / 14	EXXON MOBIL CORPORAT	201 W BEN WHITE BLVD	EDR Hist Auto	199	0.038	WNW
GS1850 / 14	7-ELEVEN STORE 36591	201 W BEN WHITE BLVD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	199	0.038	WNW
GS1851 / 14	7-ELEVEN STORE 36591	201 W BEN WHITE	RCRA NonGen / NLR, FINDS, ECHO	199	0.038	WNW
1861 / 14	GEORGES WAGON WORKS	1311 S 1ST ST	TX UST, TX HIST UST	202	0.038	WNW
KX1865 / 14	7 ELEVEN STORE 19097	1705 S LAKESHORE BLV	TX RDR, TX CENTRAL REGISTRY	204	0.039	ENE
KX1866 / 14	7-ELEVEN 19097	1705 S LAKESHORE BLV	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	204	0.039	ENE
KX1867 / 14	7 ELEVEN STORE NO 19	1705 S LAKESHORE BLV	TX RDR	204	0.039	ENE
KZ1872 / 14	WALTER JOHNSON	1207 S 1ST ST	TX HIST UST	206	0.039	WNW
LD1883 / 14	DIAMOND SHAMROCK 207	628 E OLTROF	TX RDR	210	0.040	SE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
LD1884 / 14	DIAMOND SHAMROCK 207	628 E OLTORF ST	TX LPST, TX ASBESTOS, TX ENF, TX Financi...	210	0.040	SE
LD1885 / 14	VALERO ENERGY STATIO	628 E OLTORF ST	EDR Hist Auto	210	0.040	SE
LD1886 / 14	QUAD FOOD MART	628 E OLTORF ST	TX UST, TX HIST UST, TX ASBESTOS	210	0.040	SE
FM1890 / 14	AUSTIN NURSING & CON	110 E LIVE OAK	TX HIST UST, RCRA NonGen / NLR, FINDS, E...	212	0.040	ESE
1905 / 14	ORTEGON AUTO BODY RE	111 E WOODWARD ST	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	217	0.041	ESE
1914 / 14	LUCAS GULF STATION	1221 INTERREGIONAL H	EDR Hist Auto	223	0.042	NE
1933 / 14	ASTRO CLEANERS	1900 E RIVERSIDE DR	EDR Hist Cleaner	231	0.044	ENE
KX1953 / 14	MARIES TAILOR SHOP	1708 S LAKESHORE BLV	EDR Hist Cleaner	239	0.045	ENE
LQ1959 / 14	M. H. CROCKETT	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1960 / 14	C.A. MAUFRAIS	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1961 / 14	METCALF L A SERVICE	300 S CONGRESS	EDR Hist Auto	241	0.046	NE
LQ1962 / 14	MAGNOLIA PETROLEUM C	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1963 / 14	A.E. SCHUTZE	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LQ1964 / 14	J.H. STELFOX	300 S CONGRESS AVE	TX HIST UST	241	0.046	NE
LW1987 / 14	STOCKTON J F	1501 S 1ST ST	EDR Hist Auto	247	0.047	WNW
LY1999 / 14	CRANE & LOCK SERV	344 CONGRESS AVE S	EDR Hist Auto	253	0.048	NE
LY2000 / 14	BESHEARS C A TEXACO	344 S CONGRESS	EDR Hist Auto	253	0.048	NE
LY2001 / 14	LOCK SERVICE STA FIL	344 CONGRESS AVE S	EDR Hist Auto	253	0.048	NE
MB2013 / 14	1601 S 1ST ST	1601 S 1ST ST	TX UST	257	0.049	WNW
MB2014 / 14	J. H. JOHNSON	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2015 / 14	AUTO-FROST	1601 S 1ST ST	EDR Hist Auto	257	0.049	WNW
MB2016 / 14	LEWIS SCHNELL	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2017 / 14	LEWIS SCHNELL	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MB2018 / 14	EAGLE BODY SHOP	1601 S 1ST ST	TX HIST UST	257	0.049	WNW
MC2022 / 14	STRUTS CLEANERS	1106 S 1ST ST 1106-1	RCRA NonGen / NLR	261	0.049	WNW
MC2023 / 14	STRUTS CLEANERS	1106 S 1ST ST	TX Ind. Haz Waste	261	0.049	WNW
MF2029 / 14	STOP N GO 2126	1516 TINNIN FORD RD	TX UST, TX HIST UST, TX Financial Assura...	263	0.050	NE
MF2030 / 14	DIAMOND SHAMROCK 212	1516 TINNIN FORD RD	TX LPST, TX ASBESTOS, TX GCC	263	0.050	NE
MF2031 / 14	DIAMOND SHAMROCK NO	1516 TINNIN FORD	TX RDR	263	0.050	NE
MG2033 / 14	THE GOODYEAR TIRE &	115 E OLTORF ST	RCRA NonGen / NLR, FINDS, ECHO	263	0.050	SE
MG2034 / 14	GOODYEAR AUTO SERVIC	115 E OLTORF ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	263	0.050	SE
MG2035 / 14	GOODYEAR TIRE & RUBB	115 E OLTORF ST	TX UST	263	0.050	SE
MB2071 / 14	SCHNELL BROS WHEEL	501 MONROE ST W	EDR Hist Auto	273	0.052	WNW
2077 / 14	SOUTH CENTRAL WATERF	NEC OF S FIRST ST AN	TX BROWNFIELDS	276	0.052	NE
MO2081 / 14	BROADDUS CHEVRON RIV	30 IH 35 N	TX UST, TX Financial Assurance	277	0.052	NE
MO2083 / 14	BROADDUS ENTERPRISES	30 N I 35	EDR Hist Auto	279	0.053	NE
MO2084 / 14	RIVERSIDE GROCERY	30 N I 35	TX HIST UST	279	0.053	NE
MT2166 / 14	EKSTROM G A	303 CROCKETT	EDR Hist Cleaner	285	0.054	ESE
MT2183 / 14	EKSTROM GUS AUTO REP	301 CROCKETT ST	EDR Hist Auto	291	0.055	ESE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
KX2193 / 14	SOUTH LAKESHORE BOUL	1717 LAKESHORE BLVD	EDR Hist Cleaner	293	0.055	ENE
2212 / 14	WESTERN AUTO	137 W OLTORF ST	TX LPST, TX UST	299	0.057	SE
NC2225 / 14	MARTIN J E SERVICE S	1710 1ST	EDR Hist Auto	301	0.057	WNW
NC2226 / 14	HAYNES R E FILL STA	1710 1ST	EDR Hist Auto	301	0.057	WNW
MG2228 / 14	GOODYEAR TIRE & RUBB	117 E OLTORF ST	TX HIST UST	301	0.057	SE
NE2240 / 14	MAJESTIC PRODUCTS	118 E ALPINE RD	TX HIST UST, TX Ind. Haz Waste, TX IHW C...	305	0.058	ESE
NE2241 / 14	BROYHILL FURNITURE I	118 E ALPINE RD	TX UST	305	0.058	ESE
NE2242 / 14	MAJESTIC PRODUCTS CO	118 E ALPINE RD	RCRA NonGen / NLR	305	0.058	ESE
NE2243 / 14	MAJESTIC PRODUCTS	118 E ALPINE RD	TX Ind. Haz Waste	305	0.058	ESE
LW2251 / 14	PRATHER F H FILL STA	1601 1ST	EDR Hist Auto	307	0.058	WNW
LW2252 / 14	MC CLAIN HORACE C CD	1600 1ST	EDR Hist Cleaner	307	0.058	WNW
2266 / 14	WALKERS LAUNDRY	1903 NEWTON ST	EDR Hist Cleaner	315	0.060	ESE
NI2274 / 14	SOUTH FIRST CLEANERS	1905 S 1ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	319	0.060	WNW
NI2275 / 14	SOUTH FIRST CLEANERS	1905 S 1ST ST	EDR Hist Cleaner	319	0.060	WNW
LY2287 / 14	HUMBLE PRODUCTS SERV	343 CONGRESS AVE S	EDR Hist Auto	326	0.062	NE
LY2288 / 14	RIVERSIDE SERVICE ST	343 CONGRESS AVE S	EDR Hist Auto	326	0.062	NE
KZ2297 / 14	MARY DAWSON	1214 S 1ST ST	TX HIST UST	330	0.062	WNW
KZ2298 / 14	DIANA D ZUMWALT ETAL	1214 S 1ST ST	TX LPST, TX UST	330	0.062	WNW
KZ2299 / 14	OLD AUTO SHOP	1214 S 1ST ST	TX HIST UST	330	0.062	WNW
MO2347 / 14	BROADDUS CHEVRON	30 N IH 35	TX LPST, TX Ind. Haz Waste	346	0.066	NE
2381 / 14	MURPHYS GARAGE AUTO	3801 WADFORD ST	EDR Hist Auto	355	0.067	WNW
2387 / 14	MUD PPPIES SELF SERV	2015 E RIVERSIDE DR	EDR Hist Auto	355	0.067	SW
OB2398 / 14	CAPITOL CLEANERS	1408 S 1ST STREET	RCRA NonGen / NLR, FINDS, ECHO, TX DRYCL...	357	0.068	WNW
OB2399 / 14	CAPITOL CLEANERS	1408 S 1ST ST	TX Ind. Haz Waste	357	0.068	WNW
OB2400 / 14	TRIPLE L INC	1408 S FIRST ST	EDR Hist Cleaner	357	0.068	WNW
2401 / 14	JIM WIMBERLY	1720 S 1ST ST	TX HIST UST	357	0.068	WNW
OB2402 / 14	W. RAYMOND CANION	1406 S 1ST ST	TX HIST UST	357	0.068	WNW
2438 / 14	EXXON MOBIL CORPORAT	619 N IH 35	RCRA NonGen / NLR, FINDS, ECHO	371	0.070	SSW
OM2473 / 14	REFUEL 329	31 N IH 35	TX UST, TX ASBESTOS, TX Financial Assura...	389	0.074	NNE
OM2475 / 14	FAST N EASY SHELL	31 N HWY 35	EDR Hist Auto	392	0.074	NNE
OM2476 / 14	CITY STAR FOODS	31 N I 35	TX HIST UST, TX RDR	392	0.074	NNE
ON2480 / 14	ST. EDWARDS UNIVERSI	3001 S CONGRESS	TX RDR	396	0.075	ESE
ON2481 / 14	ST EDWARDS UNIVERSIT	3001 S CONGRESS AVE	TX AST	396	0.075	ESE
ON2482 / 14	ST EDWARDS UNIVERSIT	3001 S CONGRESS AVE	TX UST, TX HIST UST, TX AIRS, TX ASBESTO...	396	0.075	ESE
MO2501 / 14	TOWN LAKE CHEVRON SE	30 INTERREGIONAL HWY	EDR Hist Auto	401	0.076	NE
OR2510 / 14	POWELL OFFSET SERVIC	2007 S 1ST ST	TX Ind. Haz Waste	405	0.077	WNW
2512 / 14	REX CLEANERS DCLO CL	200 MARY W	EDR Hist Cleaner	405	0.077	WNW
2516 / 14	KNIGHT WM Y	207 MILTON E	EDR Hist Auto	406	0.077	ESE
NI2529 / 14	GULF STATION	1900 S 1ST ST	TX HIST UST	413	0.078	WNW

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
NI2530 / 14	BARBARA LOVELESS HAR	1900 S 1ST ST	TX UST	413	0.078	WNW
NI2531 / 14	JOHN B. LOVELESS	1900 S 1ST ST	TX HIST UST	413	0.078	WNW
NI2532 / 14	JOHN LOVELESS	1900 S 1ST ST	TX HIST UST	413	0.078	WNW
2535 / 14	MORELL ARTH D	500 ACADEMY DR	EDR Hist Auto	414	0.078	SW
LY2583 / 14	DEISON AUTO REPR	320 CONGRESS AVE S	EDR Hist Auto	436	0.083	NE
OR2619 / 14	PECAN FOOD MART	2101 S 1ST ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	453	0.086	WNW
OR2620 / 14	CURTS OIL CO INC	2101 S FIRST	EDR Hist Auto	453	0.086	WNW
PJ2650 / 14	BRYANT AUTOMOTIVE	505 OLTORF ST W	EDR Hist Auto	463	0.088	West
NA2656 / 14	RAMIREZ GULF SERVICE	329 CONGRESS AVE S	EDR Hist Auto	466	0.088	NE
NA2657 / 14	BUTLERS GULF SERV	329 CONGRESS AVE S	EDR Hist Auto	466	0.088	NE
PL2673 / 14	TS CLEANERS AT TWIN	300 E OLTORF ST	TX DRYCLEANERS	473	0.090	NW
PL2674 / 14	GAHAU CLEANERS	300 OLTORF ST E	EDR Hist Cleaner	473	0.090	NW
PL2675 / 14	TWIN OAKS CLEANERS	300 E OLTORF	EDR Hist Cleaner	473	0.090	NW
2678 / 14	SUPER TRANSMISSION	2704 WILSON ST	EDR Hist Auto	476	0.090	WSW
2703 / 14	WILSON OXYGEN & SUPP	150 E BEN WHITE BLVD	TX UST, TX HIST UST	484	0.092	ESE
PQ2714 / 14	AMERICAN CLEANERS	2201 S 1ST ST STE M	TX DRYCLEANERS	490	0.093	WNW
2715 / 14	AUSTIN ISD	201 E MARY	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	492	0.093	ESE
OM2717 / 14	LAKESICE EXXON PRODU	31 INTERREGIONAL HWY	EDR Hist Auto	492	0.093	NNE
OR2718 / 14	P H BORING	2000 S 1ST ST	TX HIST UST	493	0.093	WNW
2720 / 14	TOM WALLACE MILLER	313 S CONGRESS AVE	TX HIST UST	494	0.094	NE
2730 / 14	RIVERSIDE FINA SERVI	1100 INTERREGIONAL H	EDR Hist Auto	500	0.095	NNE
PQ2743 / 14	MOTORCYCLE RESSURECT	2209 S 1ST ST	EDR Hist Auto	514	0.097	WNW
PU2749 / 14	CUSTOM ENGINE RE	603 MARY W	EDR Hist Auto	520	0.098	WNW
PU2750 / 14	AUSTIN AUTOMOTIVE	603 MARY ST W	EDR Hist Auto	520	0.098	WNW
PJ2764 / 14	BRYANT AUTOMOTIVE	505 W OLTORF ST	TX UST, TX HIST UST	541	0.102	NW
2778 / 14	TOWN LAKE GULF SERVI	901 CLERMONT AVE	EDR Hist Auto	549	0.104	NE
QP2833 / 14	CAPITAL PRINTING CO	213 E ALPINE RD	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	600	0.114	ESE
QP2834 / 14	CAPITAL PRINTING	213 E ALPINE RD	TX Ind. Haz Waste	600	0.114	ESE
PQ2837 / 14	LEE MANERS	601 W LIVE OAK ST	TX HIST UST	609	0.115	WNW
QT2860 / 14	H.A. GUERRERO CARPET	2313 S 1ST ST	TX HIST UST	640	0.121	West
QT2861 / 14	H A GUERRO CARPET CL	2313 S 1ST	TX RDR	640	0.121	West
QY2884 / 14	FESTIVAL BEACH FOOD	35 WALLER ST	TX BROWNFIELDS	655	0.124	NNE
QY2885 / 14	FESTIVAL BEACH FOOD	35 WALLER STREET	US BROWNFIELDS	655	0.124	NNE
QT2892 / 14	I. E. STUBBS	2318 S 1ST ST	TX HIST UST	676	0.128	WNW
2895 / 14	RBJ REDEVELOPMENT PR	21 WALLER ST	TX TANKS, TX HIST UST, TX RDR, TX CENTRA...	685	0.130	NE
2907 / 14	US DEPARTMENT OF JUS	55 N IH 35	RCRA NonGen / NLR	722	0.137	ESE
2947 / 14	SUNRISE MINI MART 8	539 W OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	868	0.164	West
2962 / 14	THE LITHOPRINT CO	1825 S IH 35	RCRA NonGen / NLR	905	0.171	WSW
RQ2963 / 14	SOUTH AUSTIN SERVICE	3815 WOODBURY DR	TX LPST, TX UST, TX HIST UST	905	0.171	ESE

MAPPED SITES SUMMARY - FOCUS MAP 14

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
RQ2966 / 14	PREFERRED PUMP	3805 WOODBURY DR	TX UST	917	0.174	ESE
RQ2967 / 14	PERFERRED PUMP	3805 WOODBURY	TX RDR	917	0.174	ESE
SC3008 / 14	JACK RITTER OIL CO.	2617 S 1ST ST	TX HIST UST	1032	0.195	West
SC3009 / 14	SOUTHSIDE BODY & FRA	2617 S. FIRST	TX RDR	1032	0.195	West
SC3010 / 14	SOUTHSIDE BODY & FRA	2617 S 1ST ST	TX HIST UST	1032	0.195	West
SC3011 / 14	SOUTH SIDE MOTOR	2617 S 1ST ST	TX UST	1032	0.195	West
SU3081 / 14	DOUG SCALES BODY SHO	2707 S 1ST ST	TX HIST UST, TX AIRS	1150	0.218	West
SU3085 / 14	DOUG SCALES BODY SHO	2717 S 1ST ST	TX Ind. Haz Waste, TX CENTRAL REGISTRY	1163	0.220	West
SU3086 / 14	DOUG SCALES BODY SHO	2717 S 1ST ST	RCRA NonGen / NLR, FINDS, ECHO	1163	0.220	West
3087 / 14	AUSTIN ISD	1601 HASKELL ST	RCRA NonGen / NLR, FINDS, ECHO, TX ASBES...	1168	0.221	NNE
3154 / 14	MABRY ORDNANCE SHOP		FUDS	1311	0.248	South
3173 / 14	KING FOOD MART	2907 S FIRST ST	TX RDR	1509	0.286	WSW
TN3180 / 14	CIRCLE K STORE 27405	2222 E OLTORF	TX RDR	1582	0.300	SW
TN3181 / 14	CIRCLE K STORE #2740	2222 E OLTORF ST	TX RDR	1582	0.300	SW
TN3182 / 14	CIRCLE K 2740552	2222 E OLTORF ST	TX RDR	1582	0.300	SW
TN3183 / 14	CIRCLE K STORE 27405	2222 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1582	0.300	SW
3200 / 14	OLTORF FOOD MART	2225 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	1799	0.341	SW
3235 / 14	LUBE PIT STOP	1951 E OLTORF	TX RDR	2217	0.420	SW
3249 / 14	USPS S AUSTIN STATIO	1806 S 5TH ST	TX LPST	2290	0.434	WNW
3267 / 14	WHIP IN 2 100148	1950 S IH 35	TX LPST, TX UST, TX HIST UST	2408	0.456	WSW
3268 / 14	SUNRISE MINI MART 2	915 W OLTORF ST	TX LPST, TX UST, TX ASBESTOS, TX Financi...	2415	0.457	WNW
UG3290 / 14	EXXON MOBIL 67278	1320 E OLTORF ST	TX LPST, TX ASBESTOS, TX Ind. Haz Waste	2583	0.489	ESE
UG3291 / 14	7 ELEVEN STORE 36636	1320 E OLTORF ST	TX RDR	2583	0.489	ESE
UG3292 / 14	7-ELEVEN INC STORE N	1320 E OLTORF STREET	TX RDR	2583	0.489	ESE
UG3293 / 14	7-ELEVEN STORE 36636	1320 E OLTORF ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2583	0.489	ESE

Focus Map - 15 - 7418065.7s



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 15

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
FP751 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX CLI	TP		
FP752 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX CLI	TP		
FP753 / 15	PLEASANT VALLEY & R	SW CORNER OF PLEASAN	TX HIST LF	TP		
FV779 / 15	METROPOLITAN APTS #	2423 TOWN LAKE CIRCL	TX ASBESTOS	TP		
FV780 / 15	METROPOLITAN APARTME	2423 TOWN LAKE CENTE	TX ASBESTOS	TP		
FV781 / 15	METROPOLITAN APARTME	2423 TOWN LAKE CIRCL	TX ASBESTOS	TP		
GF814 / 15	OXFORD FINE CLEANERS	4410 E RIVERSIDE DR	EDR Hist Cleaner	TP		
GH820 / 15	FAIRWAY VILLAGE APTS	FAIRWAY VILLAGE APTS	TX SPILLS	TP		
GH821 / 15	FAIRWAY VILLAGE APTS		TX SPILLS 90	TP		
822 / 15	FAIRWAY VILLAGE APAR	6118 FAIRWAY STREET	TX ASBESTOS	TP		
GI823 / 15	VERDE APARTMENTS	2310 WICKERSHAM DRIV	TX ASBESTOS	TP		
GI824 / 15	VERDE APARTMENTS	2310 WICKERSHAM LANE	TX ASBESTOS	TP		
GJ825 / 15	FAMILY DOLLAR #8248	1508 MONTOPOLIS DR.	RCRA-VSQG, FINDS, ECHO	TP		
GJ826 / 15	FAMILY DOLLAR	1590 MONTOPOLIS DR	TX ASBESTOS	TP		
GL828 / 15	RIVERSIDE EAST TOWNH	5701 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP		
GL829 / 15	RIVERSIDE EAST CONDO	5701 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP		
GL830 / 15	RIVERSIDE EAST	5701 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP		
831 / 15	FAIRWAY COIN LAUNDRY	1612 MONTOPOLIS DR	EDR Hist Cleaner	TP		
GP842 / 15	CONOCO FOOD MART	6220 EAST RIVERSIDE	TX ASBESTOS	TP		
GP843 / 15	AURA RIVERSIDE	6107 EAST RIVERSIDE	TX CENTRAL REGISTRY	TP		
GP844 / 15	AURA RIVERSIDE	6107 EAST RIVERSIDE	FINDS, ECHO	TP		
GQ846 / 15	CIRCLE K 2741300	6306 E RIVERSIDE	TX RDR	TP		
GQ847 / 15	CIRCLE K 2741300	6306 RIVERSIDE DR	TX RDR	TP		
GQ848 / 15	CIRCLE K STORE 27413	6306 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP		
GQ849 / 15	6306 EAST RIVERSIDE	6306 EAST RIVERSIDE	HMIRS	TP		
GQ850 / 15	CIRCLE K STORE #2741	6306 RIVERSIDE DR	TX RDR	TP		
GQ851 / 15	VALERO CORNER STORE	6306 E RIVERSIDE DR	FINDS	TP		
GQ852 / 15	DIAMOND SHAMROCK REF	6306 E RIVERSIDE DR	EDR Hist Auto	TP		
GQ853 / 15	CIRCLE K STORE 27413	6306 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	TP		
857 / 15	IDEA PUBLIC SCHOOLS	1909 VARGAS ROAD	TX CENTRAL REGISTRY	TP		
HS959 / 15	HEB GROCERY	2508 RIVERSIDE DR	TX RDR	61	0.012	NE
1041 / 15	AUSTIN COMMUNITY COL	5712 E RIVERSIDE DR	TX UST	66	0.013	NNE
1119 / 15	FIRE STATION 22	5307 E RIVERSIDE DR	TX UST, TX HIST UST	71	0.013	SSW
GQ1141 / 15	CONOCO FOOD MART	6214 E RIVERSIDE DR	EDR Hist Auto	74	0.014	NNE
GQ1142 / 15	CONOCO FOOD MART	6214 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	74	0.014	NNE
GQ1143 / 15	CONOCO FOOD MART	6214 EAST RIVERSIDE	TX RDR	74	0.014	NNE
IN1205 / 15	ATLAS CLEANERS NO	6110 RIVERSIDE DR E	EDR Hist Cleaner	81	0.015	NNE
IN1206 / 15	ATLAS CLEANERS 2	6110 E RIVERSIDE DR	TX DRYCLEANERS	81	0.015	NNE
IN1220 / 15	J&S BROTHERS TIRE SH	6108 E RIVERSIDE DR	TX HIST UST, TX ENF, TX COMP HIST	81	0.015	NNE

MAPPED SITES SUMMARY - FOCUS MAP 15

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
IN1221 / 15	ACE AUTO REPAIR	6108 RIVERSIDE DR	EDR Hist Auto	81	0.015	NNE
IN1222 / 15	AUTO SALVAGE YARD	6108 E. RIVERSIDE DR	TX RDR	81	0.015	NNE
IN1223 / 15	AUTO SALVAGE YARD	6108 E. RIVERSIDE	TX RDR	81	0.015	NNE
1386 / 15	DIAMOND SHAMROCK INC	6307 E RIVERSIDE DR	EDR Hist Auto	109	0.021	SSW
JD1405 / 15	ROUND2 INC.	1340 AIRPORT COMMERC	TX SWF/LF, TX SWRCY, TX ASBESTOS, TX COM...	113	0.021	South
JD1406 / 15	ROUND2, INC.	1340 AIRPORT COMMERC	RCRA-VSQG	113	0.021	South
GQ1449 / 15	SPEEDYS	6301 E RIVERSIDE	TX RDR	119	0.023	SSW
GQ1450 / 15	CITGO GRO	6301 RIVERSIDE DR	EDR Hist Auto	119	0.023	SSW
GQ1451 / 15	SPEEDY'S	6301 EAST RIVERSIDE	TX RDR	119	0.023	SSW
GQ1452 / 15	SPEEDYS	6301 E RIVERSIDE DR	TX UST, TX HIST UST, TX SPILLS, TX ASBES...	119	0.023	SSW
GF1538 / 15	MOBIL OIL 00AIX	1919 S PLEASANT VALL	TX ASBESTOS, TX Ind. Haz Waste, TX CENTR...	133	0.025	NE
GF1539 / 15	TETCO STORES INC	1919 S PLEASANT VALL	EDR Hist Auto	133	0.025	NE
GF1540 / 15	STAR STOP 73	1919 S PLEASANT VALL	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	133	0.025	NE
GF1541 / 15	MOBIL OIL CORPORATIO	1919 S PLEASANT VALL	RCRA NonGen / NLR, FINDS, ECHO	133	0.025	NE
HS1578 / 15	HEB 628	2512 E RIVERSIDE DR	TX LPST, TX UST, TX HIST UST, TX Financi...	137	0.026	NE
HS1579 / 15	EXXON TIGERMART RS 6	2512 E RIVERSIDE DR	TX Ind. Haz Waste	137	0.026	NE
HS1580 / 15	EXXON #6-01033	2512 EAST RIVERSIDE	TX RDR	137	0.026	NE
HS1581 / 15	EXXON MOBIL CORPORAT	2512 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	137	0.026	NE
HS1582 / 15	EXXON MOBIL CORPORAT	2512 E RIVERSIDE DR	EDR Hist Auto	137	0.026	NE
1597 / 15	WASHTUB & PUB COIN O	1717 PLEASANT VALLE	EDR Hist Cleaner	139	0.026	NE
1952 / 15	ROAD RUNNERS COMMERC	1511 FARO DR	EDR Hist Cleaner	239	0.045	NNE
1992 / 15	AMERICAN CLEANERS	1717 S PLEASANT VALL	TX DRYCLEANERS	250	0.047	SW
ML2058 / 15	JERRYS GARAGE	1902 MONTOPOLIS DR	EDR Hist Auto	271	0.051	NNE
ML2078 / 15	JERRYS GARAGE AUTO	1900 MONTOPOLIS DR	EDR Hist Auto	277	0.052	NNE
MS2159 / 15	MASSEVS GARAGE AUTO	6507 RIVERSIDE DR E	EDR Hist Auto	284	0.054	SSW
MS2160 / 15	MASSEYS GARAGE	6507 RIVERSIDE DR E	EDR Hist Auto	284	0.054	SSW
NU2343 / 15	ESCUELA MONTESSORI	2013 MONTOPOLIS DRIV	US BROWNFIELDS	344	0.065	SSW
NU2344 / 15	ESCUELA MONTESSORI	2013 MONTOPOLIS DR	TX HIST UST	344	0.065	SSW
2379 / 15	APPLE MART	2101 WICKERSHAM LN	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	353	0.067	NNE
2380 / 15	912 HWY 183	912 HWY 183	US BROWNFIELDS	353	0.067	ENE
2545 / 15	PALM HARBOR HOMES, I	830 BASTROP HIGHWAY	TX Ind. Haz Waste, TX TIER 2	422	0.080	South
2658 / 15	HARVEY MASSEY	6505 E RIVERSIDE DR	TX HIST UST	467	0.088	NNE
PM2679 / 15	CVS PHARMACY 6945	4405 E RIVERSIDE DR	RCRA-VSQG, FINDS, ECHO	476	0.090	SW
PM2680 / 15	CVS PHARMACY	4405 E RIVERSIDE DR	TX ASBESTOS, TX Ind. Haz Waste	476	0.090	SW
2783 / 15	FOOD SPOT 2	2538 ELMONT DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	552	0.105	NE
2862 / 15	PRIME MOBILE LUBE	1405 MONTOPOLIS DRIV	RCRA NonGen / NLR, FINDS, ECHO	641	0.121	NNE
2910 / 15	MABEL DAVIS PARK - C	INT. OF WOODWARD & B	SEMS-ARCHIVE	744	0.141	SSW
2929 / 15	ORACLE AMERICA WATER	2300 CLOUD WAY	TX AST	835	0.158	NE
SH3027 / 15	TXDOT SPECIAL CREWS	760 BASTROP HWY S	TX LPST, TX UST, TX HIST UST	1044	0.198	NNE

MAPPED SITES SUMMARY - FOCUS MAP 15

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
SH3028 / 15	TEXAS DEPARTMENT OF	760 LOCKHART HWY	RCRA NonGen / NLR, FINDS, ECHO	1044	0.198	NNE
SH3029 / 15	TEXAS DEPARTMENT OF	760 US HIGHWAY 183 S	RCRA NonGen / NLR, FINDS, ECHO	1044	0.198	NNE
SH3030 / 15	TEXAS DEPARTMENT OF	760 LOCKHART HWY	TX Ind. Haz Waste	1044	0.198	NNE
SH3031 / 15	TEXAS DEPT OF TRANSP	760 US HIGHWAY 183 S	TX Ind. Haz Waste	1044	0.198	NNE
SH3032 / 15	TXDOT OLD AUSTIN SPE	760 BASTROP HWY	TX RDR	1044	0.198	NNE
TK3162 / 15	MONTOPOLIS GROCERY	1211 MONTOPOLIS DR	TX RDR, TX CENTRAL REGISTRY	1331	0.252	NNE
TK3167 / 15	MONTOPOLIS PARK	1200 MONTOPOLIS	US BROWNFIELDS, FINDS	1431	0.271	NNE
3168 / 15	AUSTIN LIQUID DISPOS	751 BASTROP HWY	TX SWF/LF, TX AIRS, TX COMP HIST, TX CEN...	1441	0.273	NNE
3171 / 15	PARKS & RECREATION M	2525 S LAKESHORE BLV	TX UST, TX HIST UST, TX Financial Assura...	1503	0.285	ENE
3201 / 15	SOUTHWESTERN BELL	650 BASTROP HWY	TX RDR	1805	0.342	North
3210 / 15	VARGAS FOOD STORE	809 VARGAS RD	TX LPST, TX UST, TX HIST UST	1920	0.364	NW
3232 / 15	MR MCS GROCERY & MAR	2109 HOLLY ST	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	2170	0.411	NE
3244 / 15	PATHMARK 34	609 BASTROP HWY	TX RDR	2280	0.432	North
UE3273 / 15	B R CAPPS TEXACO	520 BASTROP HWY N	TX LPST, TX UST, TX HIST UST	2444	0.463	North
UE3274 / 15	FORMER CAPPS TEXACO	520 BASTROP HWY	TX RDR	2444	0.463	North
3285 / 15	6301 CIRCULO DE AMIS	6301 CIRCULO DE AMIS	US BROWNFIELDS	2532	0.480	NNE

Focus Map - 16 - 7418065.7s



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 16

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
2857 / 16	RUTLAND AUTO PARTS	1127 BASTROP HWY	EDR Hist Auto	633	0.120	ENE
RO2951 / 16	SB WINGFIELD LANDFIL	1111 OLD BASTROP HWY	TX Ind. Haz Waste	880	0.167	East
RO2952 / 16	AUSTIN VEE DUB	1111 OLD BASTROP HWY	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	880	0.167	East
RO2953 / 16	HARMON PROPERTIES LA	1111 OLD BASTROP HWY	TX SWF/LF	880	0.167	East
RO2954 / 16	SB WINGFIELD LANDFIL	1111 OLD BASTROP HWY	TX SWF/LF	880	0.167	East
RO2957 / 16	UNIVAC OF TEXAS	1115 OLD BASTROP HWY	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	886	0.168	East
RO2958 / 16	AA AUTO & EQUIPMENT	1115 OLD BASTROP HWY	TX UST	886	0.168	East
RO2991 / 16	AUTOMOTIVE RECYCLING	1125 BASTROP HWY	TX HIST UST	975	0.185	ENE
SE3020 / 16	FORMER RITLER OIL	1250 BASTROP HWY	TX UST	1040	0.197	North
SE3021 / 16	LARRY'S AUTO SALES	1250 OLD BASTROP RD.	TX HIST UST	1040	0.197	North
SE3022 / 16	TXDOT RIGHT OF AWAY	1250 BASTROP HWY	TX RDR	1040	0.197	North
SG3024 / 16	B&B LAND CLEARING	1212 BASTROP HWY	TX HIST UST	1043	0.198	ESE
SG3025 / 16	B&B LAND CLEARING	1212 OLD BASTROP HWY	TX UST	1043	0.198	ESE
SQ3069 / 16	WHISENHUT	NE INTERSECTION OF D	TX CLI	1140	0.216	NNE
SQ3070 / 16	WHISENHUT		TX CLI	1140	0.216	NNE
SQ3071 / 16	WHISENHUT		TX HIST LF	1140	0.216	NNE
SE3092 / 16	E-CON-PLACER	1240 OLD BASTROP RD	TX HIST UST	1186	0.225	North
SE3093 / 16	RIGHT OF WAY PARCEL	1240 OLD BASTROP HWY	TX RDR	1186	0.225	North
SZ3108 / 16	TEXAS ALTERNATOR	1230 BASTROP HWY	TX HIST UST	1235	0.234	ESE
SZ3109 / 16	TX ALTERNATOR STARTE	1230 BASTROP HWY	TX HIST UST	1235	0.234	ESE
3110 / 16	COLLIN'S GARAGE	1115 BASTROP HWY	TX HIST UST	1239	0.235	ENE
SZ3152 / 16	TEXAS ALTERNATOR STA	1230 E BEN WHITE BLV	TX UST	1305	0.247	North
3185 / 16		1111 OLD BASTROP HIG	TX CLI	1614	0.306	NNE

Focus Map - 17 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	0 1/4 1/2 Miles
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

SITE NAME:	Austin Light Rail Project - Phase 1	CLIENT:	HDR
ADDRESS:	Austin Light Rail Project - Phase 1	CONTACT:	Kristine Lloyd
CITY/STATE:	Austin TX	INQUIRY #:	7418065.7s
ZIP:	78704	DATE:	08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION
GW874 / 17	SUNDBECK GARAGE	4220 CONGRESS AVE S	EDR Hist Auto	TP
GX875 / 17	SUNBECK AUTOMOTIVE	4239 S CONGRESS AVE	TX HIST UST	TP
GY876 / 17	AMERICAN TREE	4311 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
GY877 / 17	ABM MACHINERY	4311 S. CONGRESS AVE	SEMS-ARCHIVE	TP
GY878 / 17	AMERICAN TREE	4311 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	TP
GY879 / 17	THE CONGRESS LOFTS	4315 S CONGRESS AVE	FINDS, ECHO	TP
GY882 / 17	THE TIRE WHAREHOUSE	4323 S CONGRESS AVE	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP
GY883 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	FINDS	TP
GY884 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	ECHO	TP
GY885 / 17	THE TIRE WHAREHOUSE	4323 S CONGRESS AVE	FINDS	TP
GY886 / 17	ST ELMO RESIDENTIAL	4323 SOUTH CONGRESS	TX COMP HIST, TX CENTRAL REGISTRY	TP
887 / 17	MULTIPLE STORAGE BUI	4341 CONGRESS AVE.	TX ASBESTOS	TP
888 / 17	TENNISON PROPERTIES	4360 S CONGRESS AVE	EDR Hist Auto	TP
HA889 / 17	CAPITAL BUMPER EXCHA	4422 CONGRESS AVE S	EDR Hist Auto	TP
HD892 / 17	ELL IS & SALAZAR GAR	4501 CONGRESS AVE S	EDR Hist Auto	TP
HD893 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	TX AIRS, TX COMP HIST, TX CENTRAL REGIST...	TP
HD894 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	TP
HD895 / 17	ELLIS AND SALAZAR	4501 S CONGRESS AVE	TX Ind. Haz Waste	TP
HF898 / 17		4703 SOUTH CONGRESS	ERNS	TP
HF899 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HF900 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	FINDS	TP
HF901 / 17	INMAN F M SERV	4703 CONGRESS AVE S	EDR Hist Auto	TP
HF902 / 17	JACKS NEW CONCEPT AU	4703 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	TP
HF903 / 17	MC NEES HUMBLE	4703 CONGRESS AVE	EDR Hist Auto	TP
HF904 / 17	PHILLIPS SIXTY SIX G	4703 CONGRESS AVE S	EDR Hist Auto	TP
HG905 / 17	SOUTHSIDE RECYCLING	4917 S CONGRESS AVE	FINDS	TP
HG906 / 17	SOUTHSIDE RECYCLING	4917 S CONGRESS AVE	FTTS, HIST FTTS	TP
907 / 17	TITOS IMPORTS AUTO R	5310 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HH908 / 17	KOVAR ROY TEXACO	100 RED BIRD TRAIL	EDR Hist Auto	TP
HH909 / 17	ROOSTERS PAINT & D C	5501 S CONGRESS AVE	TX ASBESTOS	TP
HI910 / 17	RITTERS OF SOUTH	5503 CONGRESS AVE S	EDR Hist Auto	TP
HI911 / 17	5503 S CONGRESS AVE	5503 S CONGRESS AVE	TX UST, TX HIST UST	TP
HI912 / 17	VACANT	5503 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
HI913 / 17	RITTERS GASOLINE STA	5505 CONGRESS AVE S	EDR Hist Auto	TP
914 / 17	SOUTHSIDE AUTO SALES	5609 1/2 S CONGRESS	TX CENTRAL REGISTRY	TP
HJ915 / 17	A PLUS AUTO & TRUCKS	5711 S CONGRESS AVE	TX CENTRAL REGISTRY	TP
916 / 17	SOCO II APARTMENTS	6001 SOUTH CONGRESS	FINDS, ECHO	TP
HK917 / 17	H & R FOOD MART	6400 S CONGRESS AVE	FINDS	TP
HK918 / 17	H & R FOOD MART	6400 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	TP

MAPPED SITES SUMMARY - FOCUS MAP 17

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
HK919 / 17	H & R FOOD MART	6400 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
920 / 17	KWIK WASH COIN LAUND	6500 CONGRESS AVE S	EDR Hist Cleaner	TP		
HL921 / 17	ACME CLEANERS	6630 CONGRESS AVE S	EDR Hist Cleaner	TP		
HL922 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HL923 / 17	BROWN JACK CLEANERS	6650 S CONGRESS AVE	EDR Hist Cleaner	TP		
HL924 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	TX DRYCLEANERS	TP		
HL925 / 17	JACK BROWN CLEANERS	6650 S CONGRESS AVE	FINDS	TP		
926 / 17	PUBLIC STORAGE 20149	7112 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HM927 / 17	AUSTIN ENGINE WORKS	7305 CONGRESS AVE S	EDR Hist Auto	TP		
HM928 / 17	VACANT LOT	7307 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HM929 / 17	VACANT LOT	7307 S CONGRESS AVE	TX UST, TX HIST UST	TP		
HL988 / 17	KWIK WASH COIN LAUND	6606 CONGRESS AVE S	EDR Hist Cleaner	62	0.012	WNW
HL1021 / 17	RAINBO BAKING	6534 S CONGRESS AVE	TX UST, TX HIST UST	65	0.012	WNW
HL1022 / 17	GENOA TRANSMISSIONS	6534 S CONGRESS AVE	EDR Hist Auto	65	0.012	WNW
HJ1146 / 17	FAIRLVIEW GARAGE	5804 CONGRESS AVE S	EDR Hist Auto	74	0.014	WNW
HA1150 / 17	CECILS WRECKER SERV	4404 CONGRESS AVE S	EDR Hist Auto	74	0.014	WNW
HJ1157 / 17	LUCKY FOOD STORE	5800 S CONGRESS AVE	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	74	0.014	WNW
HD1180 / 17	CAPITOL CARPET CLEAN	4506 CONGRESS AVE S	EDR Hist Cleaner	76	0.014	WNW
HD1181 / 17	WRECKER SERVICE	4506 S CONGRESS AVE	TX UST, TX HIST UST	76	0.014	WNW
GY1185 / 17	LAIDLAW TRANSIT	4300 S CONGRESS	RCRA-SQG, TX LPST, TX UST, TX HIST UST, ...	77	0.015	WNW
1186 / 17	SHEEHAN DENNIS W. T	5014 CONGRESS AVE	EDR Hist Cleaner	77	0.015	WNW
IO1207 / 17	CALL'S SALES & SERVI	4900 S CONGRESS AVE	TX HIST UST	81	0.015	WNW
GW1212 / 17	ENTERPRISE RENT A CA	4210 S CONGRESS AVE	TX AST	81	0.015	WNW
GW1213 / 17	FURROW BUILDING MATE	4210 S CONGRESS	RCRA-VSQG, FINDS, ECHO	81	0.015	WNW
HA1285 / 17	QUIKTRIP 4125	4402 S CONGRESS AVE	TX UST	91	0.017	WNW
IU1299 / 17	THURMAN WAREHOUSE	4714 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	94	0.018	WNW
IU1300 / 17	PDQ FOOD MART	4714 S CONGRESS	EDR Hist Auto	94	0.018	WNW
IO1315 / 17	RISING SUN JAPANESE	4930 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	98	0.019	WNW
IO1316 / 17	JET ENVIRONMENTAL SE	4930 S. CONGRESS AVE	RCRA NonGen / NLR	98	0.019	WNW
IO1317 / 17	RISING SUN JAPANESE	4930 S CONGRESS AVE	TX Ind. Haz Waste, TX CENTRAL REGISTRY	98	0.019	WNW
IU1433 / 17	EVANS TEXACO	4712 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST	118	0.022	WNW
IU1434 / 17	STEWART W T TEXACO	4712 CONGRESS AVE S	EDR Hist Auto	118	0.022	WNW
IU1435 / 17	MURPHY R L TEX	4712 CONGRESS AVE	EDR Hist Auto	118	0.022	WNW
IU1436 / 17	CLAWSONS TEXACO SERV	4712 CONGRESS AVE S	EDR Hist Auto	118	0.022	WNW
JZ1706 / 17	7-ELEVEN 20079	6702 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	159	0.030	WNW
JZ1707 / 17	FORMER 7 ELEVEN STOR	6702 S CONGRESS AVE	TX LPST, TX GCC	159	0.030	WNW
JZ1708 / 17	FORMER 7 ELEVEN 2007	6702 CONGRESS AVE	TX RDR	159	0.030	WNW
KK1782 / 17	CIRCLE K STORES INC	4619 S CONGRESS AVE	EDR Hist Auto	178	0.034	ESE
KK1783 / 17	ALL STAR GROCERY 1	4619 S CONGRESS AVE	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	178	0.034	ESE

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.)		DIRECTION
HA1875 / 17	A 1 AUTO ELECTRIC AU	4408 CONGRESS AVE S	EDR Hist Auto	206	0.039	WNW
LL1916 / 17	7-ELEVEN STORE 38608	105 E STASSNEY LN	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	224	0.042	ESE
LL1917 / 17	QMART STASSNEY	105 E STASSNEY	TX RDR	224	0.042	ESE
LP1944 / 17	CONGRESS EXXON	6721 S CONGRESS AVE	EDR Hist Auto	236	0.045	ESE
LP1945 / 17	EXXON 6-9404	6721 S CONGRESS	TX RDR	236	0.045	ESE
LP1946 / 17	EXXON RS 69404	6721 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	236	0.045	ESE
LP1947 / 17	EXXON MOBIL CORPORAT	6721 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO	236	0.045	ESE
LP1948 / 17	EXXON RSL 69404	6721 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	236	0.045	ESE
LZ2006 / 17	STOP N GO MARKET 210	111 W WILLIAM CANNON	TX LPST, TX UST, TX HIST UST	255	0.048	WNW
LZ2007 / 17	CLASSY CLEANERS SOUT	111 W WILLIAM CANNON	TX Ind. Haz Waste	255	0.048	WNW
LZ2008 / 17	CLASSY CLEANERS INC	111 W WILLIAM CANNON	RCRA NonGen / NLR, FINDS, ECHO	255	0.048	WNW
LZ2009 / 17	TQS	111 W WILLIAM CANNON	TX Ind. Haz Waste	255	0.048	WNW
LZ2010 / 17	BRAKE SPECIALIST INC	111 W WILLIAM CANNON	EDR Hist Auto	255	0.048	WNW
MH2038 / 17	CVS PHARMACY 0213	5526 5526 S CONGRESS	RCRA NonGen / NLR, FINDS, ECHO	264	0.050	WNW
MH2039 / 17	CVS PHARMACY	5526 S CONGRESS AVE	TX ASBESTOS, TX Ind. Haz Waste	264	0.050	WNW
MH2040 / 17	FAST STOP STORES INC	5526 S CONGRESS AVE	EDR Hist Auto	264	0.050	WNW
MH2041 / 17	FAST STOP 11	5526 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	264	0.050	WNW
MH2042 / 17	FAST STOP STORE 11	5526 S CONGRESS	TX RDR	264	0.050	WNW
MH2043 / 17	PROPOSED CVS PHARMAC	5526 S CONGRESS AVE	TX LPST, TX IHW CORR ACTION	264	0.050	WNW
2205 / 17	BEN AUTO REPAIR	5409 WASSON RD	EDR Hist Auto	298	0.056	ESE
LL2249 / 17	VALENTA SERVICE STAT	5607 CONGRESS AVE S	EDR Hist Auto	307	0.058	ESE
LL2250 / 17	VALENTA SERV STA	5607 CONGRESS AVE	EDR Hist Auto	307	0.058	ESE
2348 / 17	PRO CLEAN CARPET CLN	6411 STARSTREAK DR	EDR Hist Cleaner	346	0.066	WNW
2428 / 17	BATH CREST OF AUSTIN	111 RAMBLE LN	EDR Hist Cleaner	369	0.070	WNW
2433 / 17	HOPF WOLBERT VAULT C	4515 S CONGRESS AVE	TX HIST UST	370	0.070	ESE
OS2518 / 17	5901 S CONGRESS	6001 S CONGRESS AVE	TX SWF/LF	408	0.077	ESE
PF2621 / 17	7 ELEVEN STORE 35069	6607 CIRCLE S RD	TX RDR	454	0.086	ESE
PF2622 / 17	7-ELEVEN 39069	6607 CIRCLE S RD	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	454	0.086	ESE
PF2623 / 17	RACETRAC PETROLEUM I	6607 CIRCLE S RD	EDR Hist Auto	454	0.086	ESE
OS2647 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX CLI	461	0.087	ESE
OS2648 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX HIST LF	461	0.087	ESE
OS2649 / 17	BRADSHERE-FLOURNOY	EAST OF 6000 BLOCK O	TX CLI	461	0.087	ESE
2742 / 17	KEMAC CORPORATION	113 METEOR DR A	EDR Hist Auto	511	0.097	WNW
PZ2760 / 17	GOODNIGHT SERV STA	4700 CONGRESS AVE S	EDR Hist Auto	530	0.100	WNW
PZ2761 / 17	ARCHIE FITZGERALD	4700 S CONGRESS AVE	TX HIST UST	530	0.100	WNW
QB2779 / 17	COMMEMORATIVE BRANDS	7211 CIRCLE S RD	TX LPST, TX Ind. Haz Waste, TX IHW CORR ...	549	0.104	ESE
QB2780 / 17	CJC HOLDINGS	7211 CIRCLE S RD	TX UST, TX HIST UST	549	0.104	ESE
QB2781 / 17	COMMEMORATIVE BRANDS	7211 CIRCLE S RD	RCRA-VSQG, FINDS, ECHO	549	0.104	ESE
RC2897 / 17	RUDYS AUTOMOTIVE	4431 LUCKSINGER LN	TX COMP HIST, TX RDR, TX CENTRAL REGISTR...	696	0.132	ESE

MAPPED SITES SUMMARY - FOCUS MAP 17

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
RC2898 / 17	RUDYS AUTOMOTIVE	4431 LUCKSINGER LN	TX UST	696	0.132	ESE
2934 / 17	SALVATION ARMY SOUTH	4216 SOUTH CONGRESS	US BROWNFIELDS	848	0.161	WNW
3175 / 17	MULDOON INTERESTS	6210 CROW LN	TX VCP	1535	0.291	ESE
3192 / 17	TEXACO SERVICE STATI	616 WILLIAM CANNON	TX RDR	1660	0.314	ESE
3194 / 17	ST ELMO	502 W SAINT ELMO RD	TX LPST	1732	0.328	WNW
3216 / 17	CAPITOL CHEVROLET PA	700 N BLUFF DR	TX TANKS, TX CENTRAL REGISTRY	1956	0.370	ESE
3219 / 17	BIG LOTS	801 E WILLIAM CANNON	TX VCP, TX HIST UST, TX ASBESTOS	1977	0.374	ESE
3227 / 17	RICK HOFF	4333 S 1ST ST	TX LPST, TX UST	2085	0.395	WNW
TY3247 / 17	TEXACO RETAIL FAC	800 E WILLIAM CANNON	TX RDR	2290	0.434	ESE
TY3248 / 17	TOWN FOOD MART	800 E WILLIAM CANNON	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2290	0.434	ESE
TZ3250 / 17	ANDYS FOOD MART	611 W STASSNEY LN	TX RDR, TX CENTRAL REGISTRY	2292	0.434	WNW
TZ3251 / 17	ANDYS FOOD MART	611 W STASSNEY LN	TX LPST, TX UST, TX HIST UST, TX Financi...	2292	0.434	WNW
3280 / 17	TEXACO	5600 S 1ST ST	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2469	0.468	WNW
3296 / 17	SHELL	500 W WILLIAM CANNON	TX RDR	2605	0.493	WNW

Focus Map - 18 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 18

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
GS858 / 18	REAR JOES GARAGE AUT	4014 CONGRESS AVE S	EDR Hist Auto	TP		
GS862 / 18	RUDYS CAFE	4105 CONGRESS AVE S	EDR Hist Auto	TP		
GU863 / 18	SUNBECK AUTOMOTIVE	4139 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
GU864 / 18	SUNBECK AUTOMOTIVE	4139 S CONGRESS AVE	TX LPST, TX UST	TP		
GW868 / 18	PIXELS & POWERTOOLS	4201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
GW869 / 18	PIXELS & POWERTOOLS	4201 S CONGRESS AVE	FINDS, ECHO	TP		
GW870 / 18	M C RIVER CITY AUTO	4201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
GW871 / 18	JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	TX ASBESTOS	TP		
GW872 / 18	4201 S CONGRESS	4201 S CONGRESS	TX CENTRAL REGISTRY	TP		
GW873 / 18	JOHNSTON SUPPLY WARE	4201 S. CONGRESS AVE	TX ASBESTOS	TP		
GS1254 / 18	MCCOY'S LAWN EQUIPME	4140 S CONGRESS AVE	TX HIST UST, TX ASBESTOS	85	0.016	WNW
GX1685 / 18	NUZ FRANK GARAGE	4237 CONGRESS AVE S	EDR Hist Auto	152	0.029	ESE
GX1686 / 18	SUNDBECK GAR	4241 CONGRESS AVE	EDR Hist Auto	152	0.029	ESE
GX1687 / 18	SUNDBECK GARAGE	4241 CONGRESS AVE S	EDR Hist Auto	152	0.029	ESE
GX1688 / 18	SUNBECK AUTOMOTIVE	4241 S CONGRESS AVE	RCRA NonGen / NLR, FINDS, ECHO, TX Ind. ...	152	0.029	ESE
PC2587 / 18	THE CLOSET FACTORY	113 INDUSTRIAL BLVD	RCRA NonGen / NLR	440	0.083	ESE
PC2737 / 18	CLEANING CO H	115 INDUSTRIAL BLVD	EDR Hist Cleaner	506	0.096	ESE
PC2799 / 18	CHATLEFF CONTROLS	205 INDUSTRIAL BLVD	TX Ind. Haz Waste, TX CENTRAL REGISTRY	560	0.106	ESE
PC2800 / 18	CHATLEFF CONTROLS	205 INDUSTRIAL BLVD	RCRA NonGen / NLR, FINDS, ECHO	560	0.106	ESE
RE2903 / 18	BUTLER PAPER	200 E SAINT ELMO RD	TX UST	706	0.134	ESE
RE2904 / 18	BUTLER PAPER CO	200 E ST ELMO RD	TX HIST UST	706	0.134	ESE
RE2909 / 18	DELSTAR TECHNOLOGIES		PFAS ECHO	744	0.141	ESE
RE2911 / 18	VERITIV CORPORATION	210 E ST ELMO RD	RCRA-SQG	750	0.142	ESE
RE2912 / 18	VERITIV OPERATING	210 E SAINT ELMO RD	TX Ind. Haz Waste	750	0.142	ESE
RE2913 / 18	VERITIV OPERATING	210 210 E SAINT ELMO	RCRA-SQG	750	0.142	ESE
SA2997 / 18	TCI COATINGS INC	220 INDUSTRIAL BLVD	RCRA NonGen / NLR	1010	0.191	ESE
SA2998 / 18	TECHNICAL COATINGS	220 INDUSTRIAL BLVD	TX UST	1010	0.191	ESE
SA2999 / 18	TCI COATINGS	220 INDUSTRIAL BLVD	TX Ind. Haz Waste, TX RDR, TX CENTRAL RE...	1010	0.191	ESE
3004 / 18	BEN WHITE U HAUL	304 E BEN WHITE BLVD	TX LPST, TX UST, TX HIST UST	1017	0.193	ESE
SL3045 / 18	NALTEX	220 E ST ELMO RD	TX HIST UST	1084	0.205	ESE
SL3046 / 18	DELSTAR TECHNOLOGIES	220 E SAINT ELMO RD	RCRA-SQG, FINDS, ECHO, TX Ind. Haz Waste	1084	0.205	ESE
SL3047 / 18	220 EAST ST ELMO ROA	220 E SAINT ELMO RD	TX IHW CORR ACTION, TX COMP HIST	1084	0.205	ESE
SL3058 / 18	BRYANT JANITORIAL SU	305 E SAINT ELMO RD	TX Ind. Haz Waste	1111	0.210	ESE
SA3062 / 18	TECHNICAL COATING	312 INDUSTRIAL BLVD	TX HIST UST, TX CENTRAL REGISTRY	1118	0.212	ESE
TH3141 / 18	TCI COATINGS INC		PFAS ECHO	1285	0.243	ESE
TH3142 / 18	STONE INDUSTRIAL SOL	301 INDUSTRIAL BLVD	RCRA NonGen / NLR, FINDS, ECHO	1286	0.244	ESE
TH3143 / 18	GULF CLEANING AND LA	301 INDUSTRIAL BLVD	TX AST	1286	0.244	ESE
TH3144 / 18	STONE INDUSTRIAL SOL	301 INDUSTRIAL BLVD	TX UST, TX VCP, TX HIST UST, TX Ind. Haz...	1286	0.244	ESE
TH3151 / 18	403 - 301 INDUSTRIAL	403 INDUSTRIAL BLVD	TX VCP	1300	0.246	ESE

MAPPED SITES SUMMARY - FOCUS MAP 18

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
3166 / 18	BUTCH WOOTEN INVESTM	315 E SAINT ELMO RD	TX LPST	1421	0.269	ESE
3226 / 18	CAPITOL METAL FINISH	3909 WAREHOUSE ROW	SEMS-ARCHIVE, CORRACTS, RCRA NonGen / NL..	2083	0.395	ESE
TW3237 / 18	BEN WHITE LOTS 1,2,3	500 E BEN WHITE BLVD	TX VCP, TX GCC, TX IOP	2233	0.423	ESE
TW3239 / 18	FORMER TRUCK CITY DE	502 E BEN WHITE BLVD	TX LPST	2261	0.428	ESE
3256 / 18	WENCO DISTRIBUTORS O	600 INDUSTRIAL BLVD	TX LPST, TX UST, TX HIST UST, TX ASBESTO...	2354	0.446	ESE

Focus Map - 19 - 7418065.7s



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 19

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
HB890 / 19	HAWTHORN SUITES LTD	(MET CENTER)	FINDS, ECHO	TP		
HC891 / 19	HAWTHORNE SUITES	7800 E RIVERSIDE DR	ICIS, FINDS, ECHO	TP		
HC896 / 19	7901 E RIVERSIDE DR		PFAS ECHO	TP		
HE897 / 19	OES EQUIPMENT	7900 E RIVERSIDE DR	TX CENTRAL REGISTRY	TP		
HE1203 / 19	ELECTRONINKS	7901 E RIVERSIDE DR	RCRA-LQG	81	0.015	SSW
HE1204 / 19	ELECTRONINKS	7901 E RIVERSIDE DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	81	0.015	SSW
HB1273 / 19	HERAEUS AMERSIL	7715 E RIVERSIDE DR	TX Ind. Haz Waste, TX CENTRAL REGISTRY	88	0.017	WSW
HB1274 / 19	HERAEUS AMERSIL INC	7715 RIVERSIDE DRIVE	RCRA NonGen / NLR, FINDS, ECHO	88	0.017	WSW
JW1676 / 19	SPEEDY STOP 405	7715 E BEN WHITE	TX RDR	150	0.028	WNW
JW1677 / 19	EXXON MOBIL CORPORAT	7715 E BEN WHITE BLV	EDR Hist Auto	150	0.028	WNW
JW1678 / 19	7-ELEVEN STORE 36642	7715 E BEN WHITE BLV	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	150	0.028	WNW
1716 / 19	JD MARKET 5	7310 E RIVERSIDE DR	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	160	0.030	NE
1906 / 19	ALLMANS GROCERY & SE	7207 E RIVERSIDE	EDR Hist Auto	218	0.041	SW
1957 / 19	CAPITOL TRANSMISSION	7401 RIVERSIDE DR E	EDR Hist Auto	241	0.046	SW
1988 / 19	UNIVERSITY WRECKER	2114 MAXWELL LN	EDR Hist Auto	247	0.047	NNE
PI2642 / 19	AUSTIN BEN WHITE FAC	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
PI2643 / 19	CYRUSONE	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
PI2644 / 19	GENERAL MOTORS - AUS	7401 E. BEN WHITE BL	RCRA-VSQG	458	0.087	SW
PI2645 / 19	AUSTIN DATA CENTER A	7401 E BEN WHITE BLV	TX AST	458	0.087	SW
PP2708 / 19	HELIOVOLT	8201 E RIVERSIDE DR	RCRA NonGen / NLR	488	0.092	SE
PP2709 / 19	EBARA TECHNOLOGIES I	8201 E RIVERSIDE DR	RCRA NonGen / NLR, FINDS, ECHO	488	0.092	SE
PP2710 / 19	PENTAGON TECHNOLOGIE	8201 E RIVERSIDE DR	RCRA-SQG, TX AIRS, TX Ind. Haz Waste, TX...	488	0.092	SE
PP2711 / 19	PRODUCT RESEARCH FAC	8201 E RIVERSIDE DR	TX AIRS, TX Ind. Haz Waste, TX IHW CORR ...	488	0.092	SE
PP2712 / 19	XBIOTECH USA	8201 E RIVERSIDE DR	RCRA NonGen / NLR	488	0.092	SE
PP2713 / 19	XBIOTECH USA	8201 E RIVERSIDE DR	TX Ind. Haz Waste	488	0.092	SE
2745 / 19	COASTAL STATES CRUDE	7901 E BEN WHITE BLV	TX Ind. Haz Waste	518	0.098	East
2819 / 19	MONTOPOLIS CDC	2404 THRASHER	US BROWNFIELDS	587	0.111	SSW
SP3065 / 19	DON STEWART TEXACO	7110 E BEN WHITE	TX RDR	1131	0.214	SSW
SP3066 / 19	CHAMELEON 71	7110 E BEN WHITE BLV	TX UST, TX HIST UST, TX Financial Assura...	1131	0.214	SSW
SP3067 / 19	FORMER DON STEWART	7110 BEN WHITE BLVD	TX RDR	1131	0.214	SSW
ST3078 / 19	TOKYO ELECTRON TEXAS	2500 MONTOPOLIS DRIV	RCRA-VSQG, FINDS, ECHO	1149	0.218	SSW
ST3079 / 19	SYSTEM CONTROL CENTE	2500 MONTOPOLIS DRIV	TX Ind. Haz Waste, TX TIER 2, TX IHW COR...	1149	0.218	SSW
ST3080 / 19	AUSTIN ENERGY SYSTEM	2500 MONTOPOLIS DR	TX AST	1149	0.218	SSW
TD3121 / 19	PPD DEVELOPMENT	7551 METRO CENTER DR	TX Ind. Haz Waste	1261	0.239	SSW
TD3122 / 19	PPD DEVELOPMENT	7551 7551 METRO CENT	RCRA-SQG, FINDS, ECHO	1261	0.239	SSW
TD3123 / 19	MET CENTER	7551 METRO CENTER DR	TX AST	1261	0.239	SSW

Focus Map - 20 - 7418065.7s



Sites
Target Property
Search Buffer
Focus Map - No Sites
Focus Map - Sites
Power Line
Pipe Line
National Priority List Sites
Dept. Defense Sites
Indian Reservations BIA

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 20

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
GT859 / 20	BERGSTROM AIRFORCE B	N AREA OF BASE CLOSE	TX CLI	TP		
GT860 / 20	BERGSTROM AIRFORCE B	N AREA OF BASE CLOSE	TX HIST LF	TP		
GT861 / 20	BERGSTROM AIRFORCE B	NORTH AREA OF FORMER	TX CLI	TP		
GV865 / 20	GONZALEZ & LINDSEY P	1600 E HIGHWAY 71	FINDS	TP		
GV866 / 20	PARKING SPOT PARKING	1600 E HIGHWAY 71	FINDS	TP		
GV867 / 20	GONZALEZ & LINDSEY P	1600 E HIGHWAY 71	TX CENTRAL REGISTRY	TP		
GZ880 / 20	BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	TX TIER 2	TP		
GZ881 / 20	BERGSTROM SUBSTATION	1800 BASTROP HIGHWAY	TX TIER 2	TP		
IM1195 / 20	ABIA AUS431		PFAS ECHO	79	0.015	SSW
IM1196 / 20	GROUND SERVICES INTE		PFAS ECHO	79	0.015	SSW
IM1197 / 20	GLOBAL AVIATION SERV		PFAS ECHO	79	0.015	SSW
1200 / 20	AUS STSLM		ECHO, PFAS ECHO	80	0.015	SSW
IM1389 / 20	MENZIES AVIATION ITP	9401 CARGO AVE STE 2	FINDS, ECHO, PFAS ECHO	110	0.021	SSW
IM1390 / 20	PRIMEFLIGHT AT AUS		ECHO, PFAS ECHO	110	0.021	SSW
IM1391 / 20	AUSTIN GATEWAY	9401 CARGO AVENUE BA	RCRA-VSQG, FINDS, ECHO	110	0.021	SSW
IM1392 / 20	GROUND SERVICES INTE	9401 CARGO AVE STE 4	RCRA NonGen / NLR, FINDS, ECHO	110	0.021	SSW
IM1393 / 20	PINNACLE AIRLINES	9401 CARGO AVE STE 4	TX Ind. Haz Waste, TX IHW CORR ACTION	110	0.021	SSW
1792 / 20	GPM STORE 4567	2001 BASTROP HWY E	TX LPST, TX UST, TX Financial Assurance,...	180	0.034	NNE
NB2219 / 20	DIAMOND SHAMROCK REF	2001 BASTROP HWY E	EDR Hist Auto	300	0.057	NNE
NB2220 / 20	DIAMOND SHAMROCK REF	2001 BASTROP HWY	EDR Hist Auto	300	0.057	NNE
NB2221 / 20	DIAMOND SHAMROCK REF	2001 BASTHROP HWY	EDR Hist Auto	300	0.057	NNE
NB2222 / 20	SIGMORE DIAMOND SHAM	2001 BASTHROP HIGHWA	EDR Hist Auto	300	0.057	NNE
NB2223 / 20	SIGMOR SHAMROCK SERV	2001 BASTROP HWY	EDR Hist Auto	300	0.057	NNE
NP2316 / 20	I DEAL TIRE	2415 BASTROP HWY E	TX SPILLS, TX Ind. Haz Waste, TX CENTRAL...	336	0.064	NE
NP2317 / 20	RAYMOND RAMSEY & JER	2415 BASTROP HWY E	TX UST	336	0.064	NE
2465 / 20	FORMER SKEET & TRAP		UXO	387	0.073	SSW
2474 / 20	AUSTIN BERGSTROM INT		PFAS ECHO	390	0.074	NW
2561 / 20	ABIA FOOD & FUEL	2901 SPIRIT OF TEXAS	TX UST, TX HIST UST, TX Financial Assura...	430	0.081	WNW
QL2814 / 20	TRANSPORTATION SECUR	3600 3600 PRESIDENTI	RCRA-SQG	578	0.109	South
QL2815 / 20	GAT AIRLINE GROUND S	3600 PRESIDENTIAL BL	FINDS, ECHO, PFAS ECHO	578	0.109	South
QL2816 / 20	UNITED AIRLINES	3600 PRESIDENTIAL BL	TX ASBESTOS, TX Ind. Haz Waste, TX TIER ...	578	0.109	South
RI2926 / 20	THE HERTZ CORPORATIO	9401 RENTAL CAR LANE	TX HIST UST, TX TIER 2	825	0.156	WNW
RI2927 / 20	HERTZ RENT-A-CAR 163	9401 RENTAL CAR LN	TX AST	825	0.156	WNW
3044 / 20	AIRPORT FAST PARK	2300 SPIRIT OF TEXAS	TX AST	1080	0.205	NE
3063 / 20	ABIA CLEAN FUEL CENT	3100.5 SPIRIT OF TEX	TX HIST UST	1119	0.212	West
3105 / 20	ABIA CONSOLIDATED RE	3819 PRESIDENTIAL BL	TX UST, TX HIST UST, TX ASBESTOS, TX Fin...	1213	0.230	East
SY3106 / 20	AVIS RENT A CAR SYST	9320 RENTAL CAR LN	TX AST	1218	0.231	WNW
SY3107 / 20	AVIS RENT A CAR SYST	9320 RENTAL CAR LN	TX HIST UST, TX TIER 2	1218	0.231	WNW
SY3126 / 20	ALAMO RENT-A-CAR	9310 RENTAL CAR LN	TX AST	1269	0.240	WNW

MAPPED SITES SUMMARY - FOCUS MAP 20

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
SY3127 / 20	ALAMO CAR RENTAL	9310 RENTAL CAR LANE	TX HIST UST, TX TIER 2	1269	0.240	WNW
3153 / 20	TEXACO RETAIL FAC	2453 HWY 71	TX RDR	1306	0.247	East
SY3161 / 20	DOLLAR CAR RENTAL	9301 RENTAL CAR LN	TX HIST UST	1320	0.250	WNW
TM3177 / 20	SHOPPERS MART 6	2453 HIGHWAY 71 E	TX LPST	1561	0.296	East
TM3178 / 20	SHOPPERS MART 6	2453 HIGHWAY 71 E	TX LPST	1561	0.296	East
TO3197 / 20	FORMER AIRPORT EXXON	2511 HWY 71 E	TX VCP	1788	0.339	East
TO3198 / 20	FORMER AIRPORT EXXON	2511 HIGHWAY 71 E	TX LPST	1788	0.339	East
TO3199 / 20	STATE HIGHWAY 71 E 2	2511 HIGHWAY 71 E	US BROWNFIELDS, FINDS	1788	0.339	East
TX3241 / 20	BERGSTROM 2	SITE AT N END OF BAS	TX HIST LF	2276	0.431	SE
TX3242 / 20	BERGSTROM 2	SITE AT N END OF BAS	TX CLI	2276	0.431	SE
TX3243 / 20	BERGSTROM 2	NORTH END OF FORMER	TX CLI	2276	0.431	SE
UF3275 / 20	BERGSTROM 1	NORTH END OF FORMER	TX CLI	2455	0.465	SW
UF3276 / 20	BERGSTROM 1	SITE ON N END OF BAS	TX CLI	2455	0.465	SW
UF3277 / 20	BERGSTROM 1	SITE ON N END OF BAS	TX HIST LF	2455	0.465	SW
3288 / 20	INDOOR SMALL ARMS RA		UXO	2548	0.483	ESE

Focus Map - 21 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 21

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION		
930 / 21	HIGHMARK	7440 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
931 / 21	SOCO II	8100 S. CONGRESS AVE	TX ASBESTOS	TP		
HN932 / 21	SOCO SOUTH	8103 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HN933 / 21	SOCO SOUTH	8103 SOUTH CONGRESS	FINDS, ECHO	TP		
934 / 21	CAPITAL AREA FOOD BA	8201 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HO935 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	TX CENTRAL REGISTRY	TP		
HO936 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	FINDS	TP		
HO937 / 21	AARONS AUTO PARTS	8409 S CONGRESS AVE	TX ASBESTOS, TX IHW CORR ACTION	TP		
HO938 / 21	HUMPHRYS HANSEN	8411 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HO939 / 21	ANTIQUE ST LAMPS S C	8412 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HO940 / 21	ANTIQUE STREET LAMPS	8412 S CONGRESS AVEW	RCRA-SQG, FINDS, ECHO	TP		
HO941 / 21	B AND L AUTO PART	8413 SOUTH CONGRESS	TX CENTRAL REGISTRY	TP		
HP942 / 21	SHOP N CARRY FOOD ST	8514 S CONGRESS AVE	TX LPST	TP		
HP943 / 21	SHOP N CARRY	8514 S CONGRESS AVE	TX ASBESTOS	TP		
HP944 / 21	TOSCO MARKETING COMP	8514 S CONGRESS AVE	EDR Hist Auto	TP		
HP945 / 21	SHOP N CARRY FOOD ST	8514 S CONGRESS AVE	TX LPST	TP		
HP946 / 21	OAKS AT SLAUGHTER BL	NORTHEAST CORNER OF	TX CENTRAL REGISTRY	TP		
HO1043 / 21	SHOP N CARRY FOODS	8422 S CONGRESS AVE	TX LPST, TX RDR	67	0.013	WNW
HO1044 / 21	SHOP N CARRY FOODS	8422 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	67	0.013	WNW
1051 / 21	PIRRUNG MOBILE SERV	7400 CONGRESS AVE S	EDR Hist Auto	67	0.013	WNW
2504 / 21	WATTINGER CO., INC.	114 RALPH ABLANEDO D	TX HIST UST	402	0.076	WNW
2818 / 21	DAVE TRANSPORTATION	8300 IH 35 S ACCESS	RCRA NonGen / NLR	584	0.111	ESE
RD2899 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	TX NON REGIST PST	699	0.132	SW
RD2900 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	TX UST, TX HIST UST, TX Financial Assura...	699	0.132	SW
RD2901 / 21	PENSKE TRUCK RENTAL	8800 SOUTH CONGRESS	TX RDR	699	0.132	SW
RD2902 / 21	PENSKE TRUCK LEASING	8800 S CONGRESS AVE	RCRA-VSQG	699	0.132	SW
3145 / 21	CIRCLE K STORE 27046	8801 S I 35	TX RDR	1294	0.245	SSE
3184 / 21	SIGNATURE 1	100 E SLAUGHTER LN	TX RDR	1601	0.303	SSE
3187 / 21	TXDOT	7901 N I 35 FRONTAGE	TX RDR	1628	0.308	ESE
TP3207 / 21	FORMER 7-ELEVEN 3906	120 W SLAUGHTER LN	TX RDR	1911	0.362	SW
TP3208 / 21	WALGREENS	120 W SLAUGHTER LN	TX LPST, TX ASBESTOS, TX GCC	1911	0.362	SW

Focus Map - 22 - 7418065.7s



Sites	Focus Map - Sites	Dept. Defense Sites	
Target Property	Power Line	Indian Reservations BIA	
Search Buffer	Pipe Line		
Focus Map - No Sites	National Priority List Sites		

0 1/4 1/2 Miles

SITE NAME: Austin Light Rail Project - Phase 1	CLIENT: HDR
ADDRESS: Austin Light Rail Project - Phase 1	CONTACT: Kristine Lloyd
CITY/STATE: Austin TX	INQUIRY #: 7418065.7s
ZIP: 78704	DATE: 08/16/23

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAPPED SITES SUMMARY - FOCUS MAP 22

Target Property:
AUSTIN LIGHT RAIL PROJECT - PHASE 1
AUSTIN, TX 78704

MAP ID / FOCUS MAP	SITE NAME	ADDRESS	DATABASE ACRONYMS	DIST (ft. & mi.) DIRECTION

NO MAPPED SITES FOUND

DOD **NG CAMP MABRY** **DOD** **CUSA401792**
Region **N/A**
WNW **, TX**
> 1
5487 ft.

Focus Map:
8

DOD:

Site Name:	NG CAMP MABRY
DOD Component:	Army Guard
Joint Base:	N/A
Operating Status:	ACT (Active): Site has an on-going operational/support mission (s).

---

1 **LOWES OF NE AUSTIN** **TX CENTRAL REGISTRY** **S126667852**
Target **12805 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Actual:
729 ft.

Focus Map:
2

CENTRAL REGISTRY:

Regulated Entity Number:	RN103782405
Name:	LOWES OF NE AUSTIN
Address:	12805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1101
Status:	ACTIVE
Status Date:	2003-08-11
Customer Number:	CN600545537
Customer Name:	EMJ CORPORATION
Customer Legal Name:	EMJ Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2003-04-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	444190
Primary NAICS Industry Type Description:	Other Building Material Dealers
Physical Location Description:	IH 35 AND 13000 N LAMAR BLVD

Regulated Entity Number:	RN103782405
Name:	LOWES OF NE AUSTIN
Address:	12805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1101
Status:	ACTIVE
Status Date:	2003-08-11
Customer Number:	CN600545537
Customer Name:	EMJ CORPORATION
Customer Legal Name:	EMJ Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2003-04-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	444190
Primary NAICS Industry Type Description:	Other Building Material Dealers
Physical Location Description:	IH 35 AND 13000 N LAMAR BLVD

A2 Target Property | **COXVILLE**
12600 N LAMAR BLVD
AUSTIN, TX 78753 | **TX LPST** | **U001292676**
TX UST | **N/A**
TX HIST UST

Site 1 of 2 in cluster A

Actual: 721 ft.

Focus Map: 2

LPST:

Name:	COXVILLE
Address:	12600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78758
Facility ID:	0063631
LPST Id:	107165
Facility Location:	12600 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/04/1993
Entered Date:	10/14/1993
Reported Date:	08/04/1993
Closure Date:	02/07/1994
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	ALVIN COX
Responsible Party Address:	501 E TAYLOR ST
Responsible Party City,St,Zip:	ROUND ROCK, TX 78664
Responsible Party Telephone:	512/244-7656
Reported Date:	08/04/1993
Case Start Date:	02/07/1994
Reference Number:	RN101698058
Project Manager:	HWELCH

UST:

Name:	COXVILLE
Address:	12600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787537600
AI Number:	63631
Facility Type:	RETAIL
Facility Begin Date:	11/06/1992
Facility Status:	INACTIVE
Additional ID:	962439412002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	ALVIN COX,OWNER
Contact Organization Name:	COXVILLE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

COXVILLE (Continued) **U001292676**

Contact Telephone:	5122447656
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/21/1992
Signature Name/Title On Earliest Reg Form:	ALVIN COX,OWNER
Application Received Date On Earliest Reg Form:	09/22/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600917397
Owner Last Name:	COX ALVIN W
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	952439402002075
Additional ID:	962439412002075
AI Number:	63631
Owner Effective Begin Date:	11/06/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/22/1992
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146776
Facility ID:	94598
Ai Number:	63631
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/21/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

COXVILLE (Continued) **U001292676**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	152633
UST ID:	146776
AI Number:	63631
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

COXVILLE (Continued) **U001292676**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24717
Cert ID:	112792
UST Comprt ID:	323812
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112791
UST Comprt ID:	323813
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112794
UST Comprt ID:	323810
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112795

COXVILLE (Continued) **U001292676**

UST Comprt ID:	323809
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112796
UST Comprt ID:	323808
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112797
UST Comprt ID:	323807
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	235727
UST Comprt ID:	676692
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	251227
UST Comprt ID:	722228
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	267897
UST Comprt ID:	771692
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	284576
UST Comprt ID:	821226
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	303041
UST Comprt ID:	876326

COXVILLE (Continued) **U001292676**

UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	319209
UST Comprt ID:	924565
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	337277
UST Comprt ID:	978648
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	345892
UST Comprt ID:	1004883
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	361503
UST Comprt ID:	1052063
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	378696
UST Comprt ID:	1104088
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112785
UST Comprt ID:	323817
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112786
UST Comprt ID:	323818
UST ID:	96793

COXVILLE (Continued) **U001292676**

AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112787
UST Comprt ID:	323819
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112788
UST Comprt ID:	323816
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112789
UST Comprt ID:	323815
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112790
UST Comprt ID:	323814
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112793
UST Comprt ID:	323811
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/22/1992
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146777
Facility ID:	94598
Ai Number:	63631
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND

COXVILLE (Continued) **U001292676**

Tank Status Date:	07/21/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	152634
UST ID:	146777
AI Number:	63631
Compartment ID:	A

COXVILLE (Continued) **U001292676**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24717
Cert ID:	112792
UST Comprt ID:	323812
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112791
UST Comprt ID:	323813
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112794
UST Comprt ID:	323810
UST ID:	96793

COXVILLE (Continued) **U001292676**

AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112795
UST Comprt ID:	323809
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112796
UST Comprt ID:	323808
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112797
UST Comprt ID:	323807
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	235727
UST Comprt ID:	676692
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	251227
UST Comprt ID:	722228
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	267897
UST Comprt ID:	771692
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	284576
UST Comprt ID:	821226
UST ID:	96793
AI Number:	63631

COXVILLE (Continued) **U001292676**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	303041
UST Comprt ID:	876326
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	319209
UST Comprt ID:	924565
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	337277
UST Comprt ID:	978648
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	345892
UST Comprt ID:	1004883
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	361503
UST Comprt ID:	1052063
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	378696
UST Comprt ID:	1104088
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112785
UST Comprt ID:	323817
UST ID:	96793
AI Number:	63631
Tank ID:	1

COXVILLE (Continued) **U001292676**

Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112786
UST Comprt ID:	323818
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112787
UST Comprt ID:	323819
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112788
UST Comprt ID:	323816
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112789
UST Comprt ID:	323815
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112790
UST Comprt ID:	323814
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112793
UST Comprt ID:	323811
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/22/1992
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N

COXVILLE (Continued) **U001292676**

Pipe Type:	Not reported
UST ID:	146778
Facility ID:	94598
Ai Number:	63631
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/21/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

COXVILLE (Continued) **U001292676**

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	152635
UST ID:	146778
AI Number:	63631
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24717
Cert ID:	112792
UST Comprt ID:	323812
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24717
Cert ID:	112791
UST Comprt ID:	323813
UST ID:	96793

COXVILLE (Continued) **U001292676**

AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112794
UST Comprt ID:	323810
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112795
UST Comprt ID:	323809
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112796
UST Comprt ID:	323808
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112797
UST Comprt ID:	323807
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	235727
UST Comprt ID:	676692
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	251227
UST Comprt ID:	722228
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	267897
UST Comprt ID:	771692
UST ID:	96793
AI Number:	63631

COXVILLE (Continued) **U001292676**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	284576
UST Comprt ID:	821226
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	303041
UST Comprt ID:	876326
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	319209
UST Comprt ID:	924565
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	337277
UST Comprt ID:	978648
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	345892
UST Comprt ID:	1004883
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	361503
UST Comprt ID:	1052063
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	378696
UST Comprt ID:	1104088
UST ID:	96793
AI Number:	63631
Tank ID:	1

COXVILLE (Continued) **U001292676**

Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112785
UST Comprt ID:	323817
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112786
UST Comprt ID:	323818
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112787
UST Comprt ID:	323819
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112788
UST Comprt ID:	323816
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112789
UST Comprt ID:	323815
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112790
UST Comprt ID:	323814
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24717
Cert ID:	112793
UST Comprt ID:	323811
UST ID:	96793
AI Number:	63631
Tank ID:	1
Compartment ID:	A

COXVILLE (Continued) **U001292676**

Facility Billing Contacts:

Contact Organization Name:	COX ALVIN W
Contact Mailing Address (Delivery):	518 E TAYLOR AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ROUND ROCK, TX 78664 3047
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94598
Additional ID:	962439412002075
Princ ID:	952439402002075
AI Number:	63631
Facility Name:	COXVILLE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ALVIN W COX/

HIST UST AUSTIN:

Name:	COXVILLE
Address:	12600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0626
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

A3 **COXVILLE** **TX CENTRAL REGISTRY** **S126537384**
Target **12600 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 2 of 2 in cluster A

Actual: 721 ft.

Focus Map: 2

CENTRAL REGISTRY:

Regulated Entity Number:	RN101698058
Name:	COXVILLE
Address:	12600 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-7600
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN600917397
Customer Name:	COX ALVIN W
Customer Legal Name:	Alvin W. Cox
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/6/1992
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	--- 12600 N LAMAR, AUSTIN, TX, 78758 ---

Regulated Entity Number:	RN101698058
Name:	COXVILLE

COXVILLE (Continued) **S126537384**

Address:	12600 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-7600
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN604442566
Customer Name:	COX ANNE
Customer Legal Name:	Cox Anne
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	--- 12600 N LAMAR, AUSTIN, TX, 78758 ---

Regulated Entity Number:	RN101698058
Name:	COXVILLE
Address:	12600 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-7600
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN600917397
Customer Name:	COX ALVIN W
Customer Legal Name:	Alvin W. Cox
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/6/1992
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	--- 12600 N LAMAR, AUSTIN, TX, 78758 ---

Regulated Entity Number:	RN101698058
Name:	COXVILLE
Address:	12600 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-7600
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN604442566
Customer Name:	COX ANNE
Customer Legal Name:	Cox Anne
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	--- 12600 N LAMAR, AUSTIN, TX, 78758 ---

B4 Target Property | **NW CORNER OF IH-35 & PARMER LANE** | **FINDS** | **1025821629**
12501 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 1 of 3 in cluster B

Actual: 715 ft.
Focus Map: 2

FINDS:
Registry ID: 110070566719

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

B5 Target Property | **NW CORNER OF IH-35 & PARMER LANE** | **TX CENTRAL REGISTRY** | **S126957484**
12501 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 2 of 3 in cluster B

Actual: 715 ft.
Focus Map: 2

CENTRAL REGISTRY:

Regulated Entity Number:	RN110810033
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1107
Status:	ACTIVE
Status Date:	2019-07-10
Customer Number:	CN602841728
Customer Name:	JAMES CONSTRUCTION GROUP LLC
Customer Legal Name:	James Construction Group, L.L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-07-10
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110810033
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1107
Status:	ACTIVE
Status Date:	2019-07-10
Customer Number:	CN602841728
Customer Name:	JAMES CONSTRUCTION GROUP LLC
Customer Legal Name:	James Construction Group, L.L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-07-10

NW CORNER OF IH-35 & PARMER LANE (Continued) **S126957484**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110810033
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1107
Status:	ACTIVE
Status Date:	2019-07-10
Customer Number:	CN602841728
Customer Name:	JAMES CONSTRUCTION GROUP LLC
Customer Legal Name:	James Construction Group, L.L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-07-10
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110810033
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1107
Status:	ACTIVE
Status Date:	2019-07-10
Customer Number:	CN602841728
Customer Name:	JAMES CONSTRUCTION GROUP LLC
Customer Legal Name:	James Construction Group, L.L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-07-10
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110810033
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1107
Status:	ACTIVE
Status Date:	2019-07-10
Customer Number:	CN602841728
Customer Name:	JAMES CONSTRUCTION GROUP LLC
Customer Legal Name:	James Construction Group, L.L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-07-10
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

NW CORNER OF IH-35 & PARMER LANE (Continued) **S126957484**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

B6 Target Property **NW CORNER OF IH-35 & PARMER LANE**
12501 N LAMAR BLVD
AUSTIN, TX 78753

ECHO **1025900661**
N/A

Site 3 of 3 in cluster B

Actual: 715 ft.
Focus Map: 2

ECHO:

Envid:	1025900661
Registry ID:	110070566719
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070566719
Name:	NW CORNER OF IH-35 & PARMER LANE
Address:	12501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

---

7 Target Property **7-ELEVEN INC**
12434 N LAMAR BLVD
AUSTIN, TX 78753

EDR Hist Auto **1020289381**
N/A

EDR Hist Auto

Actual: 712 ft.
Focus Map: 2

Year:	Name:	Type:
1994	SOUTHLAND CORPORATION	Convenience Stores
1995	SOUTHLAND CORPORATION	Convenience Stores
1996	SOUTHLAND CORPORATION	Convenience Stores
1999	7-ELEVEN INC	Convenience Stores
2000	7-ELEVEN INC	Convenience Stores
2001	7-ELEVEN INC	Convenience Stores
2002	7-ELEVEN INC	Convenience Stores

C8 Target Property **NYOS CHARTER SCHOOL**
12333 N LAMAR BLVD
AUSTIN, TX 78753

TX COMP HIST **S126970262**
TX CENTRAL REGISTRY **N/A**

Site 1 of 3 in cluster C

Actual: 704 ft.
Focus Map: 2

COMP HIST:

RN Number:	RN111047866
Name:	NYOS CHARTER SCHOOL
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605783075
CN Name:	KENCON CONSTRUCTORS CONSTRUCTION MANAGERS LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	444120

NYOS CHARTER SCHOOL (Continued) **S126970262**

SIC Code: 1542
Related Number: TXR1507CH,TXR1507CH

CENTRAL REGISTRY:
Regulated Entity Number: RN111047866
Name: NYOS CHARTER SCHOOL
Address: 12333 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1320
Status: ACTIVE
Status Date: 2020-05-29
Customer Number: CN605783075
Customer Name: KENCON CONSTRUCTORS CONSTRUCTION MANAGERS LLC
Customer Legal Name: Kencon Constructors/Construction Managers, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2020-05-29
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

C9 Target Property | **NYOS CHARTER SCHOOL** | **ECHO** | **1026208571**
12333 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 2 of 3 in cluster C

Actual: 704 ft.
Focus Map: 2

ECHO:
Envid: 1026208571
Registry ID: 110070791504
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110070791504
Name: NYOS CHARTER SCHOOL
Address: 12333 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753

C10 Target Property | **NYOS CHARTER SCHOOL** | **FINDS** | **1026435945**
12333 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 3 of 3 in cluster C

Actual: 704 ft.
Focus Map: 2

FINDS:
Registry ID: 110070791504

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

NYOS CHARTER SCHOOL (Continued) **1026435945**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

11
Target
Property

NYOS CHARTER SCHOOL-BLDG. D
12301 N. LAMAR BLVD.
AUSTIN, TX 78758

TX ASBESTOS **S119152258**
N/A

Actual:
702 ft.

Focus Map:
4

ASBESTOS:

Name:	NYOS CHARTER SCHOOL-BLDG. D
Address:	12301 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78758
Date of inspection:	11/09/2012
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2012008186
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/27/2012
Date Routed by Supervisor:	11/29/2012
Date Routed to PSQA:	12/04/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported

NYOS CHARTER SCHOOL-BLDG. D (Continued) **S119152258**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

---

12 **WALNUT CREEK PARK MAINTENANCE BUILDING** **TX ASBESTOS** **S128135439**
Target **12138 N. LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78753**

Actual:
663 ft.

Focus Map:
4

ASBESTOS:

Name:	WALNUT CREEK PARK MAINTENANCE BUILDING
Address:	12138 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	Not reported
Reason for Inspection:	Ahmad Nasser
Violation:	Not reported
Complaint Date:	10/13/2021
Notification Number:	2021006399
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1

WALNUT CREEK PARK MAINTENANCE BUILDING (Continued) **S128135439**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/11/2021
Certification Statement Phone:	512-974-9187
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/11/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALNUT CREEK PARK MAINTENANCE BUILDING
Address:	12138 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	Not reported
Reason for Inspection:	Ahmad Nasser
Violation:	Not reported
Complaint Date:	10/12/2021
Notification Number:	2021006399
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

WALNUT CREEK PARK MAINTENANCE BUILDING (Continued) **S128135439**

Date Report Received:	09/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/22/2021
Certification Statement Phone:	512-974-9187
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/11/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

D13 Target Property | **WALNUT PARK APARTMENTS**
12101 N LAMAR BLVD
AUSTIN, TX 78753 | **FINDS ECHO** | **1024442299 N/A**

Site 1 of 3 in cluster D

Actual: 607 ft.
Focus Map: 4

FINDS:
Registry ID: 110070366169

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024442299
Registry ID:	110070366169
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070366169
Name:	WALNUT PARK APARTMENTS
Address:	12101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

D14 Target Property | **WALNUT PARK APARTMENTS**
12101 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S126899292 N/A**

Site 2 of 3 in cluster D

Actual: 607 ft.
Focus Map: 4

CENTRAL REGISTRY:

Regulated Entity Number:	RN109083493
Name:	WALNUT PARK APARTMENTS
Address:	12101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1727
Status:	ACTIVE
Status Date:	2016-02-19
Customer Number:	CN605092469
Customer Name:	WALNUT PARK LTD
Customer Legal Name:	WALNUT PARK, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2016-02-24
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109083493
Name:	WALNUT PARK APARTMENTS
Address:	12101 N LAMAR BLVD
Address 2:	Not reported

WALNUT PARK APARTMENTS (Continued) **S126899292**

City,State,Zip:	AUSTIN, TX 78753-1727
Status:	ACTIVE
Status Date:	2016-02-19
Customer Number:	CN605092469
Customer Name:	WALNUT PARK LTD
Customer Legal Name:	WALNUT PARK, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2016-02-24
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109083493
Name:	WALNUT PARK APARTMENTS
Address:	12101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1727
Status:	ACTIVE
Status Date:	2016-02-19
Customer Number:	CN601162472
Customer Name:	LARRY PEEL & CO INC
Customer Legal Name:	Larry Peel & Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2016-02-19
Affiliation End Date:	2016-02-23
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109083493
Name:	WALNUT PARK APARTMENTS
Address:	12101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1727
Status:	ACTIVE
Status Date:	2016-02-19
Customer Number:	CN601162472
Customer Name:	LARRY PEEL & CO INC
Customer Legal Name:	Larry Peel & Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2016-02-19
Affiliation End Date:	2016-02-23
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

D15 Target Property | **AMIGOS AUTO SALES**
12100 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S126626374**
N/A

Site 3 of 3 in cluster D

Actual: 622 ft.

Focus Map: 4

CENTRAL REGISTRY:

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN601869829
Customer Name:	AAMIGOS AUTO SALES
Customer Legal Name:	Aamigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN601869829
Customer Name:	AAMIGOS AUTO SALES
Customer Legal Name:	Aamigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN601869829
Customer Name:	AAMIGOS AUTO SALES
Customer Legal Name:	Aamigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

AMIGOS AUTO SALES (Continued) **S126626374**

Physical Location Description: Not reported

Regulated Entity Number: RN103349247
Name: AMIGOS AUTO SALES
Address: 12100 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1701
Status: ACTIVE
Status Date: 7/2/2003
Customer Number: CN601869829
Customer Name: AAMIGOS AUTO SALES
Customer Legal Name: Aamigos Auto Sales
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN103349247
Name: AMIGOS AUTO SALES
Address: 12100 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1701
Status: ACTIVE
Status Date: 7/2/2003
Customer Number: CN601869829
Customer Name: AAMIGOS AUTO SALES
Customer Legal Name: Aamigos Auto Sales
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN103349247
Name: AMIGOS AUTO SALES
Address: 12100 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1701
Status: ACTIVE
Status Date: 7/2/2003
Customer Number: CN600466429
Customer Name: AMIGOS AUTO SALES
Customer Legal Name: Amigos Auto Sales
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN103349247

AMIGOS AUTO SALES (Continued) **S126626374**

Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN600466429
Customer Name:	AMIGOS AUTO SALES
Customer Legal Name:	Amigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN600466429
Customer Name:	AMIGOS AUTO SALES
Customer Legal Name:	Amigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN600466429
Customer Name:	AMIGOS AUTO SALES
Customer Legal Name:	Amigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported

AMIGOS AUTO SALES (Continued) **S126626374**

City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN600466429
Customer Name:	AMIGOS AUTO SALES
Customer Legal Name:	Amigos Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103349247
Name:	AMIGOS AUTO SALES
Address:	12100 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1701
Status:	ACTIVE
Status Date:	7/2/2003
Customer Number:	CN604975177
Customer Name:	AIMEE USED TIRES
Customer Legal Name:	Aimee Used Tires
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
15 additional TX CENTRAL REG: record(s) in the EDR Site Report.

---

16 **2 VACANT DUPLEXES** **TX ASBESTOS** **S128132908**
Target **11708 N. LAMAR** **N/A**
Property **AUSTIN, TX 78753**

Actual:
732 ft.

Focus Map:
3

ASBESTOS:

Name:	2 VACANT DUPLEXES
Address:	11708 N. LAMAR
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	Not reported
Reason for Inspection:	Pat Fleener
Violation:	Not reported
Complaint Date:	06/25/2021
Notification Number:	2021003856
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

2 VACANT DUPLEXES (Continued) **S128132908**

Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	06/07/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/07/2021
Certification Statement Phone:	512-336-7665
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/21/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

E17 Target Property | **GAREY CONSTRUCTION CO INC**
11607 N LAMAR
AUSTIN, TX 78753 | **RCRA NonGen / NLR** | **1004784295**
TXD087309746

Site 1 of 6 in cluster E

Actual: 745 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Garey Construction Co Inc
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD087309746
Contact Name:	HAROLD WOLFF
Contact Address:	N LAMAR
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-837-5916
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Garey Construction Co Inc
Owner Type:	Private
Operator Name:	Garey Construction Co Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

GARAEY CONSTRUCTION CO INC (Continued) **1004784295**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: GAREY CONSTRUCTION CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	11607 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-5916
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GAREY CONSTRUCTION CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	11607 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-5916
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK GAREY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

GAREY CONSTRUCTION CO INC (Continued) **1004784295**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date:	19870228
Handler Name:	GAREY CONST CO
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name:	GAREY CONSTRUCTION CO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E18 Target Property | **GAREY CONSTRUCTION** | **TX AST** | **1000226011**
11607 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 2 of 6 in cluster E

Actual: 745 ft.
Focus Map: 3

AST:

Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532658
Facility ID:	58161
Additional ID:	473855222002153
AI Number:	21450
Facility Type:	UNKNOWN
Facility Begin Date:	09/15/1986
Facility Status:	INACTIVE
Facility Exempt Status:	N

GAREY CONSTRUCTION (Continued) **1000226011**

Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	0
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	HAROLD WOLF/EQUIPMENT MANAGER
Contact Organization Name:	GAREY CONSTRUCTION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5128375916
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	04/01/1986
Signature First Name on Earliest Reg Form:	L
Application Received Date on Earliest Reg Form:	05/08/1986
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	SHANK
Signature Title on Earliest Reg Form:	SEC/TREAS
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	58161
Tank ID:	1
AST ID:	152449
AI Number:	21450
Install Date:	08/31/1989
Tank Registration Date:	05/08/1986
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	08/31/1989
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10000
Substance:	EMPTY
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

E19 Target Property | **GAREY CONSTRUCTION**
11607 N LAMAR
AUSTIN, TX 78753 | **FINDS** | **1016099871**
ECHO | **N/A**

Site 3 of 6 in cluster E

Actual: 745 ft.
Focus Map: 3

FINDS:
Registry ID: 110005065589

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016099871
Registry ID:	110005065589
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005065589
Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR
City,State,Zip:	AUSTIN, TX 78753

E20 Target Property | **GAREY CONSTRUCTION**
11607 N LAMAR BLVD
AUSTIN, TX 78753 | **TX UST** | **U003841451**
TX HIST UST | **N/A**

Site 4 of 6 in cluster E

Actual: 745 ft.
Focus Map: 3

UST:

Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532658
AI Number:	21450
Facility Type:	UNKNOWN
Facility Begin Date:	09/15/1986
Facility Status:	INACTIVE
Additional ID:	473855222002153
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753

GAREY CONSTRUCTION (Continued) **U003841451**

Contact Name/Title:	HAROLD WOLF,EQUIPMENT MANAGER
Contact Organization Name:	GAREY CONSTRUCTION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128375916
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/01/1986
Signature Name/Title On Earliest Reg Form:	L SHANK,SEC/TREAS
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600333165
Owner Last Name:	GAREY CONSTRUCTION LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	652538932001297
Additional ID:	473855222002153
AI Number:	21450
Owner Effective Begin Date:	09/15/1986
State Tax ID:	17421134051
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	55119
Facility ID:	58161
Ai Number:	21450
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/18/1998

GAREY CONSTRUCTION (Continued) **U003841451**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	64532
UST ID:	55119
AI Number:	21450
Compartment ID:	A
Substance Stored1:	GASOLINE

GAREY CONSTRUCTION (Continued) **U003841451**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	55118
Facility ID:	58161
Ai Number:	21450
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/18/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

GAREY CONSTRUCTION (Continued) **U003841451**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	64531
UST ID:	55118
AI Number:	21450
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

GAREY CONSTRUCTION (Continued) **U003841451**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	GAREY CONSTRUCTION LTD
Contact Mailing Address (Delivery):	11607 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 2658
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	58161
Additional ID:	473855222002153
Princ ID:	652538932001297
AI Number:	21450
Facility Name:	GAREY CONSTRUCTION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HAROLD WOLF/

HIST UST AUSTIN:

Name:	GAREY CONSTRUCTION CO INC
Address:	11607 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1276
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

E21 Target Property | **GAREY CONSTRUCTION**
11607 N LAMAR BLVD
AUSTIN, TX 78753 | **TX Ind. Haz Waste**
TX CENTRAL REGISTRY | **S102748143**
N/A

Site 5 of 6 in cluster E

Actual: 745 ft.

Focus Map: 3

Ind. Haz Waste:

Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61207
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD087309746
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	PRIVATE
Description of Facility Site Location:	11607 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	GAREY CONSTRUCTION LTD
Contact Name:	HAROLD WOLFF
Contact Telephone Number:	512-8375916
Mailing Address:	11607 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787532658
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19566
Site Owner Tax ID:	742113405
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

GAREY CONSTRUCTION (Continued) **S102748143**

Ind. Haz Waste:

Operator Name:	GAREY CONSTRUCTION LTD
Operator Address:	11607 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8375916
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17421134051
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	GAREY CONSTRUCTION LTD
Owner Mailing Address:	11607 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8375916
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17421134051
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	11607 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375916
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	11607 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375916
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	HAROLD WOLFF
Contact Title:	ENVIRONEMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	11607 NLAMAR BLVD
Contact Address 2:	Not reported

GAREY CONSTRUCTION (Continued) **S102748143**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375916
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	11601 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000303496
Principal Name:	GAREY CONSTRUCTION LTD
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	11601 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000303496
Principal Name:	GAREY CONSTRUCTION LTD
Attention Name:	Not reported
Attention Suffix:	HWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100624352
Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2658
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600333165
Customer Name:	GAREY CONSTRUCTION LTD
Customer Legal Name:	Garey Construction Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	11607 N Lamar, Austin, TX

Regulated Entity Number:	RN100624352
Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2658
Status:	ACTIVE
Status Date:	##########

GAREY CONSTRUCTION (Continued) **S102748143**

Customer Number:	CN600333165
Customer Name:	GAREY CONSTRUCTION LTD
Customer Legal Name:	Garey Construction Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	11607 N Lamar, Austin, TX

Regulated Entity Number:	RN100624352
Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2658
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600333165
Customer Name:	GAREY CONSTRUCTION LTD
Customer Legal Name:	Garey Construction Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	11607 N Lamar, Austin, TX

Regulated Entity Number:	RN100624352
Name:	GAREY CONSTRUCTION
Address:	11607 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2658
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600333165
Customer Name:	GAREY CONSTRUCTION LTD
Customer Legal Name:	Garey Construction Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	11607 N Lamar, Austin, TX

F22 **TRAILER COATING** **TX CENTRAL REGISTRY** **S123848227**
Target **11422 N LAMAR** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 6 in cluster F

Actual:
752 ft.

Focus Map:
3

CENTRAL REGISTRY:

Regulated Entity Number:	RN100719871
Name:	TRAILER COATING
Address:	11422 N LAMAR
Address 2:	Not reported

TRAILER COATING (Continued) **S123848227**

City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600407837
Customer Name:	ELLIOTT TRAILER SALES
Customer Legal Name:	Elliott Trailer Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/7/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332312
Primary NAICS Industry Type Description:	Fabricated Structural Metal Manufacturing
Physical Location Description:	11422 N LAMAR

Regulated Entity Number:	RN100719871
Name:	TRAILER COATING
Address:	11422 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600407837
Customer Name:	ELLIOTT TRAILER SALES
Customer Legal Name:	Elliott Trailer Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/7/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332312
Primary NAICS Industry Type Description:	Fabricated Structural Metal Manufacturing
Physical Location Description:	11422 N LAMAR

F23 **OREILLY AUTO PARTS 5871** **TX CENTRAL REGISTRY** **S126950700**
Target **11423 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 2 of 6 in cluster F

Actual: 752 ft.
Focus Map: 3

CENTRAL REGISTRY:

Regulated Entity Number:	RN110655339
Name:	OREILLY AUTO PARTS 5871
Address:	11423 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2688
Status:	ACTIVE
Status Date:	1/29/2019
Customer Number:	CN604511071
Customer Name:	OREILLY AUTO ENTERPRISES LLC
Customer Legal Name:	O'Reilly Auto Enterprises, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/25/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441310
Primary NAICS Industry Type Description:	Automotive Parts and Accessories Stores
Physical Location Description:	Not reported

G24 Target Property | **KWIK STOP**
11331 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S126813340**
N/A

Site 1 of 6 in cluster G

Actual: 771 ft.

Focus Map: 3

CENTRAL REGISTRY:

Regulated Entity Number:	RN105916639
Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2664
Status:	ACTIVE
Status Date:	4/26/2010
Customer Number:	CN603662792
Customer Name:	OVA-TOR INC
Customer Legal Name:	OVA-TOR INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/19/2010
Affiliation End Date:	8/11/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	NE CORNER OF LAMAR AND BRAKER

Regulated Entity Number:	RN105916639
Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2664
Status:	ACTIVE
Status Date:	4/26/2010
Customer Number:	CN604651372
Customer Name:	KWIK TEXACO LLC
Customer Legal Name:	KWIK TEXACO LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/1/2014
Affiliation End Date:	3/26/2020
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	NE CORNER OF LAMAR AND BRAKER

Regulated Entity Number:	RN105916639
Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2664
Status:	ACTIVE
Status Date:	4/26/2010
Customer Number:	CN605773209
Customer Name:	11331 ENTERPRISE LLC
Customer Legal Name:	11331 Enterprise LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/27/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations

KWIK STOP (Continued) **S126813340**

Physical Location Description: NE CORNER OF LAMAR AND BRAKER

G25 Target Property | **KWIK STOP** | **TX UST** | **U004159666**
11331 N LAMAR BLVD STE A | **TX HIST UST** | **N/A**
AUSTIN, TX 78753 | **TX ASBESTOS**
TX Financial Assurance
Site 2 of 6 in cluster G | **TX NON REGIST PST**

Actual: 771 ft.

Focus Map: 3

UST:

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 787532664
AI Number:	83668
Facility Type:	RETAIL
Facility Begin Date:	04/19/2010
Facility Status:	ACTIVE
Additional ID:	880438782010117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	ASIFBHAI MAREDIYA,OPERATOR
Contact Organization Name:	KWIK STOP
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123633297
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/15/2022
Signature Name/Title On Earliest Reg Form:	ASIFBHAJ MAREDIYA,OPERATOR
Application Received Date On Earliest Reg Form:	09/15/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	434484732020108
Additional ID:	880438782010117
Ai Number:	83668
Operator CN:	CN605773209
Operator Name:	11331 ENTERPRISE LLC
Operator Effective Begin Date:	03/27/2020
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	ASIFHAI MAREDIYA/
Contact Organization Name:	11331 ENTERPRISE LLC
Contact Mailing Address (Delivery):	11331 N LAMAR BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-2664
Contact Phone Country Code:	0

KWIK STOP (Continued) **U004159666**

Contact Phone Area Code:	512
Contact Phone Number:	3633297
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605773209
Owner Last Name:	11331 ENTERPRISE LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	11331 N LAMAR BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	2664
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	434484732020108
Additional ID:	880438782010117
AI Number:	83668
Owner Effective Begin Date:	03/27/2020
State Tax ID:	32073369814
Contact Role:	OWNCON
Contact Name/Title:	ANISH PRALA/
Contact Organization Name:	11331 ENTERPRISE LLC

Self Certification:

Self Cert ID:	128050
Cert ID:	376407
AI Number:	83668
Self Certification Date:	09/15/2022
Signature Name/Title:	ASIFBHAJ MAREDIYA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK STOP (Continued) **U004159666**

Self Cert ID:	128050
Cert ID:	360073
AI Number:	83668
Self Certification Date:	09/16/2021
Signature Name/Title:	ASIFRHAI MAREDIYA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	343169
AI Number:	83668
Self Certification Date:	08/25/2020
Signature Name/Title:	ASIFBHAI MAREDIYA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	335805
AI Number:	83668
Self Certification Date:	03/31/2020
Signature Name/Title:	ASIFBHAI MAREDIYA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK STOP (Continued) **U004159666**

Self Cert ID:	128050
Cert ID:	329822
AI Number:	83668
Self Certification Date:	12/24/2019
Signature Name/Title:	MOHAMMAD OVAIS OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	312860
AI Number:	83668
Self Certification Date:	12/20/2018
Signature Name/Title:	MOHAMMAD OVAIS OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	298320
AI Number:	83668
Self Certification Date:	12/27/2017
Signature Name/Title:	MOHAMMAD OVAIS OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK STOP (Continued) **U004159666**

Self Cert ID:	128050
Cert ID:	280672
AI Number:	83668
Self Certification Date:	12/27/2016
Signature Name/Title:	MOHAMMAD OVAIS OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	261657
AI Number:	83668
Self Certification Date:	11/28/2015
Signature Name/Title:	M OVAIS OFFICER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	255989
AI Number:	83668
Self Certification Date:	08/03/2015
Signature Name/Title:	M OVAIS OFFICER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK STOP (Continued) **U004159666**

Self Cert ID:	128050
Cert ID:	240357
AI Number:	83668
Self Certification Date:	08/11/2014
Signature Name/Title:	MOHAMMAD OVAIS OFFICER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	223265
AI Number:	83668
Self Certification Date:	07/25/2013
Signature Name/Title:	BASSAM QUSSAD OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	128050
Cert ID:	218360
AI Number:	83668
Self Certification Date:	06/22/2012
Signature Name/Title:	BASSAM QUSSAD OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

KWIK STOP (Continued) **U004159666**

Self Cert ID:	128050
Cert ID:	218359
AI Number:	83668
Self Certification Date:	07/20/2011
Signature Name/Title:	BASSAM QUSSAD OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	128050
Cert ID:	218358
AI Number:	83668
Self Certification Date:	08/27/2010
Signature Name/Title:	BASSAM QUSSAD OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/19/2010
Tank Registration Date:	09/02/2010
Number of Compartments:	2
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	213865
Facility ID:	128050
Ai Number:	83668
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/19/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

KWIK STOP (Continued) **U004159666**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	05/17/2010

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	178898
UST ID:	213865
AI Number:	83668
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

KWIK STOP (Continued) **U004159666**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/19/2010
Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	178899
UST ID:	213865
AI Number:	83668
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N

KWIK STOP (Continued) **U004159666**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/19/2010

Install Date:	04/19/2010
Tank Registration Date:	09/02/2010
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	213864
Facility ID:	128050
Ai Number:	83668
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/19/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

KWIK STOP (Continued) **U004159666**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	05/17/2010

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	178897
UST ID:	213864
AI Number:	83668
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

KWIK STOP (Continued) **U004159666**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/19/2010

Construction Notification:

NOC ID:	34244
Facility ID:	128050
AI Number:	83668
Application Received Date:	02/25/2019
Scheduled Construction Date:	02/25/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	02/25/2019
Signature Date On Form:	02/23/2019
Signature Name On Form:	KEVIN PRITCHARD
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	KWIK TEXACO LLC
Owner CN At Time Of Construction:	CN604651372
Owner AR At Time Of Construction:	76781
General Desc Of Prop Construct:	REPAIR/REPLACE SPILL BUCKET - TEST DISPENSER SUMPS.

NOC ID:	22795
Facility ID:	128050
AI Number:	83668
Application Received Date:	03/11/2010
Scheduled Construction Date:	04/01/2010
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	02/25/2019

KWIK STOP (Continued) **U004159666**

Signature Date On Form:	02/23/2019
Signature Name On Form:	KEVIN PRITCHARD
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	70778
General Desc Of Prop Construct:	INSTALLATION OF (2) GLASS STEEL TANKS, DOUBLE WALL FRP PIPING TO 5 MPD'S.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	40554
UST ID:	213865
NOC ID:	Not reported
AI Number:	83668
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	FUEL TEX
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	40553
UST ID:	213864
NOC ID:	Not reported
AI Number:	83668
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	FUEL TEX
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

KWIK STOP (Continued) **U004159666**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	23921
UST ID:	Not reported
NOC ID:	22795
AI Number:	83668
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	FUEL TEX
Representative Name:	RANDY HOLYBEE
Mailing Address (Delivery):	1210 E 4TH ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TAYLOR
Mailing State:	TX
Mailing Zip:	76574
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3526460
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	81184
UST ID:	Not reported
NOC ID:	34244
AI Number:	83668
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000121
Company Name:	A-1 PUMP INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 4289
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BRYAN
Mailing State:	TX
Mailing Zip:	77805
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	979
Phone Number:	7782418
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	979
Fax Number:	7784309
Email Address:	Not reported
Cont/Cons/Installer ID:	81183
UST ID:	Not reported
NOC ID:	34244
AI Number:	83668
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001864

KWIK STOP (Continued) **U004159666**

Company Name:	Not reported
Representative Name:	KEVIN PRITCHARD
Mailing Address (Delivery):	PO BOX 4289
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BRYAN
Mailing State:	TX
Mailing Zip:	77805
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	979
Phone Number:	7782418
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	979
Fax Number:	7784309
Email Address:	Not reported
Cont/Cons/Installer ID:	23922
UST ID:	Not reported
NOC ID:	22795
AI Number:	83668
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000029
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	55694
UST ID:	213864
NOC ID:	Not reported
AI Number:	83668
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	LARRY HOLYBEE
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

KWIK STOP (Continued) **U004159666**

Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	55695
UST ID:	213865
NOC ID:	Not reported
AI Number:	83668
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	LARRY HOLYBEE
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	11331 ENTERPRISE LLC
Contact Mailing Address (Delivery):	11331 N LAMAR BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 2664
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	128050
Additional ID:	880438782010117
Princ ID:	434484732020108
AI Number:	83668
Facility Name:	KWIK STOP
AR Number:	81639
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ANISH PRALA/

HIST UST AUSTIN:

Name:	KWIK TEXACO
Address:	11331 N LAMAR BLVD

KWIK STOP (Continued) **U004159666**

City,State,Zip:	AUSTIN, TX
Id UST:	3337
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	10/21/2015
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	4.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	11/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	11/06/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	11/05/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

KWIK STOP (Continued) **U004159666**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	274206
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2022
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 877 4748808
Policy Number:	PP3641544 2
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	257116
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y

KWIK STOP (Continued) **U004159666**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2021
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP36415441
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	230628
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2020
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 804 3271700
Policy Number:	PP3641544
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	237561
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2020
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641544
Coverage Amount:	1,000,000

KWIK STOP (Continued) **U004159666**

Coverage Expiration Date:	03/27/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	225451
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/29/2019
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391-05
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	206341
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/29/2018
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391-04
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050

KWIK STOP (Continued) **U004159666**

Finass ID:	191760
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/29/2017
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391-03
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	174028
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/29/2016
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391-02
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	147006
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

KWIK STOP (Continued) **U004159666**

Financial Assurance Begin Date:	04/29/2015
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	131718
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/29/2014
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641391
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/29/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	112399
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2013
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP3641145-03
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/23/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

KWIK STOP (Continued) **U004159666**

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	15825
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2012
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641145-02
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/23/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	128050
Finass ID:	104512
AI:	83668
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2011
Date Financial Assurance Form Rec:	09/15/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641145-01
Coverage Amount:	1000000
Coverage Expiration Date:	04/23/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

NON REGIST PST:

RN Number:	RN105916639
Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753 2664
Physical Location:	NE CORNER OF LAMAR AND BRAKER
CN Number:	CN605773209
Customer Name:	11331 ENTERPRISE LLC
Customer Role:	OWNER OPERATOR

KWIK STOP (Continued) **U004159666**

Primary Business:	RETAIL
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=748519842010116

G26 **KWIK STOP** **TX ENF** **S121202677**
Target **11331 N LAMAR BLVD** **TX COMP HIST** **N/A**
Property **AUSTIN, TX 78753**

Site 3 of 6 in cluster G

Actual:
771 ft.

Focus Map:
3

ENFORCEMENT:

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001421732
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	453,376,342,017,235.00
Role Code:	Not reported
Date Notice Of Violation Issued:	08/25/2017
Description 1:	Failure to ensure that the underground storage tank (UST) system is operated, maintained, and managed in a manner that will prevent releases of regulated substances from the UST system.
Description 2:	On or about June 30, 2017, the investigator received documentation indicating there was a leak at the hose swivel so the hose swivel was replaced. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.42(a)
Status Of The NOV:	DAPPROVED
Investigation:	1421732
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported

KWIK STOP (Continued) **S121202677**

Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001421732
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	453,376,342,017,235.00
Role Code:	Not reported
Date Notice Of Violation Issued:	08/25/2017
Description 1:	Failure to ensure that the underground storage tank (UST) system is operated, maintained, and managed in a manner that will prevent releases of regulated substances from the UST system.
Description 2:	On or about June 30, 2017, the investigator received documentation indicating there was a leak at the hose swivel so the hose swivel was replaced. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.48(a)
Status Of The NOV:	DAPPROVED
Investigation:	1421732
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported

KWIK STOP (Continued) **S121202677**

Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001538951
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	379,554,282,019,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/19/2019
Description 1:	Failure to ensure that all release detection equipment installed is maintained in good operating condition.
Description 2:	On February 12, 2019, an invoice and a liquid status report dated February 8, 2019 was received by email. The records indicated that the sensor (L3) was replaced with a functioning sensor. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.48(e)
Status Of The NOV:	DAPPROVED
Investigation:	1538951
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001538951
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	379,554,282,019,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/19/2019
Description 1:	Failure to test the containment sumps for tightness once every three years.
Description 2:	The regulated entity submitted documentation to resolve this violation

KWIK STOP (Continued) **S121202677**

	on 3/29/19.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.45(d)(1)(E)(iv)
Status Of The NOV:	DAPPROVED
Investigation:	1538951
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001538951
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	379,554,282,019,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/19/2019
Description 1:	Failure to visually inspect the containment sumps for tightness annually.
Description 2:	The regulated entity submitted documentation to resolve this violation on 3/29/19.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.45(d)(1)(E)(iv)
Status Of The NOV:	DAPPROVED
Investigation:	1538951
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported

KWIK STOP (Continued) **S121202677**

Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Unique TCEQ Ref Number Of Customer:	CN604651372
Unique TCEQ Ref Number Of Reg. Entity:	RN105916639
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	KWIK TEXACO LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	NE CORNER OF LAMAR AND BRAKER
Near City:	AUSTIN
Investigation Number:	000000001538951
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	379,554,282,019,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/19/2019
Description 1:	Failure to ensure that all spill and overfill prevention devices are maintained in good operating condition.
Description 2:	The regulated entity submitted documentation to resolve this violation on 5/6/2019.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.51(a)(6)
Status Of The NOV:	DAPPROVED
Investigation:	1538951
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

COMP HIST:

RN Number:	RN105916639
Name:	KWIK STOP
Address:	11331 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753-2664
Region:	REGION 11 - AUSTIN
CN Number:	CN605773209
CN Name:	11331 ENTERPRISE LLC
CN Rating:	0
Classification:	HIGH

KWIK STOP (Continued) **S121202677**

Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447190
SIC Code:	1522
Related Number:	83668,83668

G27 **POTOSINA MEAT MARKET** **FINDS** **1014841588**
Target **11331 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 4 of 6 in cluster G

Actual:
771 ft.

FINDS:
Registry ID: 110041725176

Focus Map:
3

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H28 **PROGRESSIVE MILL WORKS** **FINDS** **1024381255**
Target **11118 N LAMAR BOULEVARDSUITE A** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 4 in cluster H

Actual:
775 ft.

FINDS:
Registry ID: 110070285393

Focus Map:
3

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
OSHA ESTABLISHMENT

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H29 Target Property | **HERITAGE BODY & FRAME**
11108 N LAMAR BLVD
AUSTIN, TX 78753

RCRA NonGen / NLR
FINDS
ECHO
TX Ind. Haz Waste

1000154096
TXD066438946

Site 2 of 4 in cluster H

Actual: 776 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Heritage Body And Frame
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD066438946
Contact Name:	GLENN BORKLAND
Contact Address:	E BRAKER LANE
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-835-9795
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E BRAKER LANE
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Heritage Body And Frame
Owner Type:	Private
Operator Name:	Heritage Body And Frame
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

HERITAGE BODY & FRAME (Continued) **1000154096**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene,

HERITAGE BODY & FRAME (Continued) **1000154096**

2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: HERITAGE BODY AND FRAME	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	611 E BRAKER LANE
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-835-9795
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN COMMUNITY PROPERTIES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 33251
Owner/Operator City,State,Zip:	AUSTIN, TX 78764-0251
Owner/Operator Telephone:	512-835-9795
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HERITAGE BODY AND FRAME	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	611 E BRAKER LANE
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-835-9795
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19851022
Handler Name: HERITAGE BODY & FRAME	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

HERITAGE BODY & FRAME (Continued) **1000154096**

Receive Date: 20010823
Handler Name: HERITAGE BODY AND FRAME
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005058515

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000154096
Registry ID: 110005058515
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005058515
Name: HERITAGE BODY & FRAME
Address: 11108 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753

Ind. Haz Waste:
Name: HERITAGE BODY AND FRAME

HERITAGE BODY & FRAME (Continued) **1000154096**

Address:	11108 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	67299
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD066438946
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	PRIVATE
Description of Facility Site Location:	11108 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	HERITAGE BODY AND FRAME INC
Contact Name:	GLENN BORKLAND
Contact Telephone Number:	512-8359795
Mailing Address:	611 E BRAKER LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787532752
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22430
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	HERITAGE BODY AND FRAME INC
Operator Address:	611 E BRAKER LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA

HERITAGE BODY & FRAME (Continued) **1000154096**

Operator Telephone:	1-512-8359795
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17424484909
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	HERITAGE BODY AND FRAME INC
Owner Mailing Address:	611 E BRAKER LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8359795
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17424484909
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	611 E BRAKER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8359795
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	611 E BRAKER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8359795
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	GLENN BORKLAND
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	611 E BRAKER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8359795
Contact Fax:	Not reported
Contact Email:	Not reported

HERITAGE BODY & FRAME (Continued) **1000154096**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	109 E BRAKER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000309866
Principal Name:	HERITAGE BODY AND FRAME INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	109 E BRAKER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000309866
Principal Name:	HERITAGE BODY AND FRAME INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	109 E BRAKER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000309866
Principal Name:	HERITAGE BODY AND FRAME INC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	109 E BRAKER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000309866
Principal Name:	HERITAGE BODY AND FRAME INC
Attention Name:	Not reported
Attention Suffix:	HWF

H30 **HERITAGE BODY & FRAME** **TX CENTRAL REGISTRY** **S123846453**
Target **11108 N LAMAR** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 4 in cluster H

Actual:
776 ft.

Focus Map:
3

CENTRAL REGISTRY:

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported

HERITAGE BODY & FRAME (Continued) **S123846453**

City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600347538
Customer Name:	HERITAGE BODY AND FRAME INC
Customer Legal Name:	Heritage Body And Frame, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/7/1995
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600347538
Customer Name:	HERITAGE BODY AND FRAME INC
Customer Legal Name:	Heritage Body And Frame, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/7/1995
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600347538
Customer Name:	HERITAGE BODY AND FRAME INC
Customer Legal Name:	Heritage Body And Frame, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/7/1995
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########

HERITAGE BODY & FRAME (Continued) **S123846453**

Customer Number:	CN603878729
Customer Name:	LAMAR BODY SHOP
Customer Legal Name:	LAMAR BODY SHOP
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/7/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603878729
Customer Name:	LAMAR BODY SHOP
Customer Legal Name:	LAMAR BODY SHOP
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/7/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603878729
Customer Name:	LAMAR BODY SHOP
Customer Legal Name:	LAMAR BODY SHOP
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/7/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600347538
Customer Name:	HERITAGE BODY AND FRAME INC
Customer Legal Name:	Heritage Body And Frame, Inc.

HERITAGE BODY & FRAME (Continued) **S123846453**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/7/1995
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600347538
Customer Name:	HERITAGE BODY AND FRAME INC
Customer Legal Name:	Heritage Body And Frame, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/7/1995
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603878729
Customer Name:	LAMAR BODY SHOP
Customer Legal Name:	LAMAR BODY SHOP
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/7/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	11108 N LAMAR

Regulated Entity Number:	RN100636943
Name:	HERITAGE BODY & FRAME
Address:	11108 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603878729
Customer Name:	LAMAR BODY SHOP
Customer Legal Name:	LAMAR BODY SHOP
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/7/1989
Affiliation End Date:	12/31/3000

HERITAGE BODY & FRAME (Continued) **S123846453**

Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811121
Primary NAICS Industry Type Description: Paint and Interior Repair and Maintenance
Physical Location Description: 11108 N LAMAR

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

I31 **AIRGAS SOUTHWEST, INC.- AUSTIN #9** **TX TIER 2** **S108449688**
Target **11111 N. LAMAR** **N/A**
Property **AUSTIN, TX 78469**

Site 1 of 6 in cluster I

Actual:
780 ft.

Focus Map:
3

TIER 2:

Facility Id:	FATR201126L4QV03PBP4
Facility Name:	AIRGAS SOUTHWEST, INC.- AUSTIN #9
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	2/27/2012
Mailing Address:	P.O. Box 9096
Mailing City/State/Country:	Corpus Christi, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	22
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Cindy Grant, Risk Manager
Latitude:	30.380277
Longitude:	-97.68687
Lat/Long Location Desc:	Not reported
Lat/Long Method:	A5 - Address Matching (Primary Name)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR201026L4QV03PBP4
Facility Name:	AIRGAS SOUTHWEST, INC.- AUSTIN #9
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	2/28/2011
Mailing Address:	P.O. Box 9096
Mailing City/State/Country:	Corpus Christi, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	22

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Cindy Grant, Risk Manager
Latitude:	30.380277
Longitude:	-97.68687
Lat/Long Location Desc:	Not reported
Lat/Long Method:	A5 - Address Matching (Primary Name)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR200926L4QV03PBP4
Facility Name:	AIRGAS SOUTHWEST, INC. AUSTIN #9
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/27/2010
Mailing Address:	P.O. Box 9096
Mailing City/State/Country:	Corpus Christi, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	22
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	CINDY GRANT
Latitude:	30.380277
Longitude:	-97.68687
Lat/Long Location Desc:	Not reported
Lat/Long Method:	A5 - Address Matching (Primary Name)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR200826L4QV03PBP4
Facility Name:	AIRGAS SOUTHWEST, INC.- AUSTIN #9
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	2/27/2009
Mailing Address:	P.O Box 9086
Mailing City/State/Country:	Corpus Christi, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	22
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Curtis Henson - Safety Director
Latitude:	30.380277
Longitude:	-97.68687
Lat/Long Location Desc:	Not reported
Lat/Long Method:	A5 - Address Matching (Primary Name)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200726L4QV03PBP4/AIRGAS-SOUTHWEST, INC.
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	2/29/2008
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Cindy Grant, Risk manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200626L4QV03PBP4/AIRGAS-SOUTHWEST INC.
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2/22/2007
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Brandon Jones Authorized Representative
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200526L4QV03PBP4/"AIRGAS-SOUTHWEST, INC."
Reporting Year:	2005
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	2/28/2006
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Cindy Grant/ auth rep
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	5169
Id Type:	SIC
Description:	CHEMICALS AND ALLIED PRODUCTS
Last Modified:	2/27/2003
Id:	027183839
Id Type:	Dun & Bradstreet

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Description:	Not reported
Last Modified:	2/27/2003
Id:	424690
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/15/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	P.O. Box 9096
Contact City/State/Zip:	Corpus Christi, TX 78469
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Airgas Southwest, Inc.
Title:	Owner/Operator
Modification Date:	3/13/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	P O Box 9096
Contact City/State/Zip:	Corpus Christi, TX 78469
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Emergency Contact
Contact Name:	Cindy Grant
Title:	Risk Manager
Modification Date:	3/13/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	11111 N. Lamar
Contact City/State/Zip:	Austin, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Gary Underwood
Title:	Not reported
Modification Date:	3/13/2010

Chemical Inventory:

Facility Id:	FATR200926L4QV03PBP4
Chemical Name:	Carbon Dioxide
Chemical Inv Record Id:	CVTR20096BJHLP03D1RG
CAS Number:	124-38-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	26000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	366
Fire Hazard:	Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20096BJHMB03ELGT
Chemical Inventory Record Id:	CVTR20096BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHMF03FQDD
Chemical Inventory Record Id:	CVTR20096BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Liquid Storage Area
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHMJ03GT79
Chemical Inventory Record Id:	CVTR20096BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Cylinder Storage Area
Last Modified:	3/13/2010

Facility Id:	FATR200926L4QV03PBP4
Chemical Name:	Nitrogen
Chemical Inv Record Id:	CVTR20096BJHQG03HB8A
CAS Number:	7727-37-9
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	20400
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	366
Fire Hazard:	Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20096BJHTE03KW10
Chemical Inventory Record Id:	CVTR20096BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Liquid Filling Area
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHTJ03LZCC
Chemical Inventory Record Id:	CVTR20096BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Liquid Filling Area
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHTB03JT9E
Chemical Inventory Record Id:	CVTR20096BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Behind the Main Building
Last Modified:	3/13/2010

Facility Id:	FATR200926L4QV03PBP4
Chemical Name:	Oxygen
Chemical Inv Record Id:	CVTR20096BJHV103M99C
CAS Number:	7782-44-7
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	57000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	366
Fire Hazard:	T

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20096BJHW003N3SV
Chemical Inventory Record Id:	CVTR20096BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHW803QANE
Chemical Inventory Record Id:	CVTR20096BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock
Last Modified:	3/13/2010

Record Key:	CLTR20096BJHW303P6XS
Chemical Inventory Record Id:	CVTR20096BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Dock
Last Modified:	3/13/2010

Facility Id:	FATR200926L4QV03PBP4
Chemical Name:	ARGON
Chemical Inv Record Id:	CVTR200971WGT5015M0W
CAS Number:	7440-37-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	707
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971WGZG0162QN
Chemical Inventory Record Id:	CVTR200971WGT5015M0W
Amt Of Sub Stored Or Transported:	10848
Amount Units:	pounds
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CYL STORAGE AREA - WEST SIDE YARD
Last Modified:	3/13/2010

Record Key:	CLTR200971WH1Y0177HZ
Chemical Inventory Record Id:	CVTR200971WGT5015M0W
Amt Of Sub Stored Or Transported:	7536
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	DEWARS - CYLINDER STORAGE AREA
Last Modified:	3/13/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

Facility Info:

Id:	027183839
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/27/2003
Id:	5169
Id Type:	SIC
Description:	CHEMICALS AND ALLIED PRODUCTS
Last Modified:	2/27/2003
Id:	424690

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Id Type:	NAICS
Description:	Not reported
Last Modified:	2/15/2009

Contact:

Contact Email:	CINDY.GRANT@AIRGAS.COM
Contact Mail Address:	P O Box 9096
Contact City/State/Zip:	Corpus Christi, TX 78469
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Emergency Contact
Contact Type 3:	Owner / Operator
Contact Name:	Cindy Grant
Title:	Risk Manager
Modification Date:	5/18/2011

Contact:

Contact Email:	cindy.grant@airgas.com
Contact Mail Address:	P.O. Box 9096
Contact City/State/Zip:	Corpus Christi, TX 78469
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Airgas Southwest, Inc.
Title:	Owner/Operator
Modification Date:	4/1/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	11111 N. Lamar
Contact City/State/Zip:	Austin, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Gary Underwood
Title:	Not reported
Modification Date:	4/1/2011

Chemical Inventory:

Facility Id:	FATR201026L4QV03PBP4
Chemical Name:	Carbon Dioxide
Chemical Inv Record Id:	CVTR20106BJHLP03D1RG
CAS Number:	124-38-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	26000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/1/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20106BJHMJ03GT79
Chemical Inventory Record Id:	CVTR20106BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Cylinder Storage Area
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHMF03FQDD
Chemical Inventory Record Id:	CVTR20106BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Liquid Storage Area
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHMB03ELGT
Chemical Inventory Record Id:	CVTR20106BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	4/1/2011

Facility Id:	FATR201026L4QV03PBP4
Chemical Name:	Nitrogen
Chemical Inv Record Id:	CVTR20106BJHQG03HB8A
CAS Number:	7727-37-9
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	20400
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	4/1/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20106BJHTB03JT9E
Chemical Inventory Record Id:	CVTR20106BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Behind the Main Building
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHTE03KW10
Chemical Inventory Record Id:	CVTR20106BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Liquid Filling Area
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHTJ03LZCC
Chemical Inventory Record Id:	CVTR20106BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Liquid Filling Area
Last Modified:	4/1/2011

Facility Id:	FATR201026L4QV03PBP4
Chemical Name:	Oxygen
Chemical Inv Record Id:	CVTR20106BJHV103M99C
CAS Number:	7782-44-7
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	57000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/1/2011
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20106BJHW003N3SV
Chemical Inventory Record Id:	CVTR20106BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHW303P6XS
Chemical Inventory Record Id:	CVTR20106BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Dock
Last Modified:	4/1/2011

Record Key:	CLTR20106BJHW803QANE
Chemical Inventory Record Id:	CVTR20106BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock
Last Modified:	4/1/2011

Facility Id:	FATR201026L4QV03PBP4
Chemical Name:	ARGON
Chemical Inv Record Id:	CVTR201071WGT5015M0W
CAS Number:	7440-37-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	707
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	4/1/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Mixture Form: T
Sudden Release Of Pressure Haz: T
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2010
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201071WH1Y0177HZ
Chemical Inventory Record Id: CVTR201071WGT5015M0W
Amt Of Sub Stored Or Transported: 7536
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 6
Desc of Loc(Or Transported) Subs: DEWARS - CYLINDER STORAGE AREA
Last Modified: 4/1/2011

Record Key: CLTR201071WGZG0162QN
Chemical Inventory Record Id: CVTR201071WGT5015M0W
Amt Of Sub Stored Or Transported: 10848
Amount Units: pounds
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: CYL STORAGE AREA - WEST SIDE YARD
Last Modified: 4/1/2011

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:
Id: 424690
Id Type: NAICS
Description: Not reported
Last Modified: 2/15/2009
Id: 5169
Id Type: SIC
Description: CHEMICALS AND ALLIED PRODUCTS
Last Modified: 2/27/2003
Id: 027183839
Id Type: Dun & Bradstreet
Description: Not reported

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Last Modified: 2/27/2003

Contact:
Contact Email: cindy.grant@airgas.com
Contact Mail Address: P.O. Box 9096
Contact City/State/Zip: Corpus Christi, TX 78469
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: Airgas Southwest, Inc.
Title: Owner/Operator
Modification Date: 3/7/2012

Contact Email: cindy.grant@airgas.com
Contact Mail Address: P.O. Box 9096
Contact City/State/Zip: Corpus Christi, TX 78469
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: Airgas Southwest, Inc.
Title: Owner/Operator
Modification Date: 3/7/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 11111 N. Lamar
Contact City/State/Zip: Austin, TX 78753
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: Gary Underwood
Title: Not reported
Modification Date: 3/7/2012

Contact:
Contact Email: CINDY.GRANT@AIRGAS.COM
Contact Mail Address: P O Box 9096
Contact City/State/Zip: Corpus Christi, TX 78469
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Type 2: Emergency Contact
Contact Type 3: Owner / Operator
Contact Name: Cindy Grant
Title: Risk Manager
Modification Date: 3/7/2012

Contact Email: CINDY.GRANT@AIRGAS.COM
Contact Mail Address: P O Box 9096
Contact City/State/Zip: Corpus Christi, TX 78469
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Type 2: Emergency Contact
Contact Type 3: Owner / Operator
Contact Name: Cindy Grant
Title: Risk Manager
Modification Date: 3/7/2012

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Chemical Inventory:

Facility Id:	FATR201126L4QV03PBP4
Chemical Name:	Carbon Dioxide
Chemical Inv Record Id:	CVTR20116BJHLP03D1RG
CAS Number:	124-38-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	26000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/7/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20116BJHMB03ELGT
Chemical Inventory Record Id:	CVTR20116BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHMF03FQDD
Chemical Inventory Record Id:	CVTR20116BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Liquid Storage Area
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHMJ03GT79
Chemical Inventory Record Id:	CVTR20116BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Cylinder Storage Area

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Last Modified:	3/7/2012

Facility Id:	FATR201126L4QV03PBP4
Chemical Name:	Nitrogen
Chemical Inv Record Id:	CVTR20116BJHQG03HB8A
CAS Number:	7727-37-9
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	20400
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/7/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20116BJHTB03JT9E
Chemical Inventory Record Id:	CVTR20116BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Behind the Main Building
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHTE03KW10
Chemical Inventory Record Id:	CVTR20116BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Liquid Filling Area
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHTJ03LZCC
Chemical Inventory Record Id:	CVTR20116BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Liquid Filling Area

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Last Modified:	3/7/2012

Facility Id:	FATR201126L4QV03PBP4
Chemical Name:	Oxygen
Chemical Inv Record Id:	CVTR20116BJHV103M99C
CAS Number:	7782-44-7
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	57000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/7/2012
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20116BJHW003N3SV
Chemical Inventory Record Id:	CVTR20116BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Bulk Liquid Storage Area
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHW303P6XS
Chemical Inventory Record Id:	CVTR20116BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Dock
Last Modified:	3/7/2012

Record Key:	CLTR20116BJHW803QANE
Chemical Inventory Record Id:	CVTR20116BJHV103M99C
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock

AIRGAS SOUTHWEST, INC.- AUSTIN #9 (Continued) **S108449688**

Last Modified:	3/7/2012

Facility Id:	FATR201126L4QV03PBP4
Chemical Name:	ARGON
Chemical Inv Record Id:	CVTR201171WGT5015M0W
CAS Number:	7440-37-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	628
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/7/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201171WGZG0162QN
Chemical Inventory Record Id:	CVTR201171WGT5015M0W
Amt Of Sub Stored Or Transported:	10848
Amount Units:	pounds
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CYL STORAGE AREA - WEST SIDE YARD
Last Modified:	3/7/2012

Record Key:	CLTR201171WH1Y0177HZ
Chemical Inventory Record Id:	CVTR201171WGT5015M0W
Amt Of Sub Stored Or Transported:	7536
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	DEWARS - CYLINDER STORAGE AREA
Last Modified:	3/7/2012

Notes:	Not reported
Validation:	Not reported

I32 Target Property | **AIRGAS USA, LLC - SOUTHWEST - AUSTIN**
11111 N. LAMAR
AUSTIN, TX 78753 | **TX TIER 2** | **S113677907**
N/A

Site 2 of 6 in cluster I

Actual: 780 ft.

Focus Map: 3

TIER 2:

Facility Id:	FATR201226L4QV03PBP4
Facility Name:	AIRGAS USA, LLC - SOUTHWEST - AUSTIN
Reporting Year:	2012
Facility Country:	USA
Facility Department:	C116
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/27/2012
Mailing Address:	31 N. Peoria Ave.
Mailing City/State/Country:	Tulsa, OK USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Brandon Ketcher Regulatory Compliance Manager
Latitude:	30.380277
Longitude:	-97.68687
Lat/Long Location Desc:	Not reported
Lat/Long Method:	A5 - Address Matching (Primary Name)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	5169
Id Type:	SIC
Description:	Not reported
Last Modified:	1/15/2013
Id:	927105247
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/15/2013
Id:	424690
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/15/2009

Contact:

Contact Email:	brandon.ketcher@airgas.com
Contact Mail Address:	259 Radnor-Chester Road
Contact City/State/Zip:	Radnor, PA 19087-5283
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	LLC Airgas USA

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Title:	Owner/Operator
Modification Date:	4/26/2013
Contact Email:	brandon.ketcher@airgas.com
Contact Mail Address:	259 Radnor-Chester Road
Contact City/State/Zip:	Radnor, PA 19087-5283
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	LLC Airgas USA
Title:	Owner/Operator
Modification Date:	4/26/2013

Contact:

Contact Email:	stephen.schultz@airgas.com
Contact Mail Address:	11111 N. Lamar
Contact City/State/Zip:	Austin, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Stephen Schultz
Title:	Branch Manager
Modification Date:	3/7/2013

Contact:

Contact Email:	cindy.grant@airgas.com
Contact Mail Address:	4817 Agnes Street
Contact City/State/Zip:	Corpus Christi, TX 78405
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Emergency Contact
Contact Name:	Cindy Grant
Title:	Risk Manager
Modification Date:	4/26/2013
Contact Email:	cindy.grant@airgas.com
Contact Mail Address:	4817 Agnes Street
Contact City/State/Zip:	Corpus Christi, TX 78405
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Emergency Contact
Contact Name:	Cindy Grant
Title:	Risk Manager
Modification Date:	4/26/2013

Contact:

Contact Email:	brandon.ketcher@airgas.com
Contact Mail Address:	31 North Peoria Avenue
Contact City/State/Zip:	Tulsa, OK 74120
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Brandon Ketcher
Title:	Regulatory Compliance Manager
Modification Date:	1/16/2013

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Contact Email:	brandon.ketcher@airgas.com
Contact Mail Address:	31 North Peoria Avenue
Contact City/State/Zip:	Tulsa, OK 74120
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Brandon Ketcher
Title:	Regulatory Compliance Manager
Modification Date:	1/16/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Airgas Emergency Services
Title:	Emergency Services
Modification Date:	4/26/2013

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Airgas Emergency Services
Title:	Emergency Services
Modification Date:	4/26/2013

Chemical Inventory:

Facility Id:	FATR201226L4QV03PBP4
Chemical Name:	Carbon Dioxide
Chemical Inv Record Id:	CVTR20126BJHLP03D1RG
CAS Number:	124-38-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	26000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Chemical Inventory Location:

Record Key:	CLTR20126BJHMB03ELGT
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	SE Corner of Building
Last Modified:	3/7/2013

Record Key:	CLTR20126BJHMF03FQDD
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	SE Corner of Building - Bulk Tank Area
Last Modified:	3/7/2013

Record Key:	CLTR20126BJHMJ03GT79
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	6
Desc of Loc(Or Transported) Subs:	Inside Building - South End
Last Modified:	3/7/2013

Record Key:	CLTR201293THW201SJA1
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Yard - East Portion of Property
Last Modified:	3/7/2013

Record Key:	CLTR201293THW901TQKR
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside Building - South End
Last Modified:	3/7/2013

Record Key:	CLTR201293THWD01UTVV
Chemical Inventory Record Id:	CVTR20126BJHLP03D1RG
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock - West Side of Building
Last Modified:	3/7/2013

Facility Id:	FATR201226L4QV03PBP4
Chemical Name:	Nitrogen
Chemical Inv Record Id:	CVTR20126BJHQG03HB8A
CAS Number:	7727-37-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	20400
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20126BJHTB03JT9E
Chemical Inventory Record Id:	CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	SW Corner of Building
Last Modified:	3/7/2013

Record Key:	CLTR20126BJHTE03KW10
Chemical Inventory Record Id:	CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	SW Corner of Building - Bulk Tank Area
Last Modified:	3/7/2013

Record Key:	CLTR20126BJHTJ03LZCC
Chemical Inventory Record Id:	CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Number Code/Storage Temperature: 7
Desc of Loc(Or Transported) Subs: Inside Building - South End
Last Modified: 3/7/2013

Record Key: CLTR201293TJ2B01WYD8
Chemical Inventory Record Id: CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Yard - East Portion of Property
Last Modified: 3/7/2013

Record Key: CLTR201293TJ2F01X29L
Chemical Inventory Record Id: CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside Building - South End
Last Modified: 3/7/2013

Record Key: CLTR201293TJ2L01Y643
Chemical Inventory Record Id: CVTR20126BJHQG03HB8A
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Dock - West Side of Building
Last Modified: 3/7/2013

Facility Id: FATR201226L4QV03PBP4
Chemical Name: Oxygen
Chemical Inv Record Id: CVTR20126BJHV103M99C
CAS Number: 7782-44-7
Chemical Same As Last Year: Not reported
Acute Health Risks: Not reported
Average Daily Amount: 10,000 - 99,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: 57000
Chronic Health Risks: T
EHS Substance: Not reported
Last Modified: 3/7/2013
Days On Site: 365
Fire Hazard: T
Gas: T
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: T
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Label Code: TX2012
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20126BJHW003N3SV
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 7
Desc of Loc(Or Transported) Subs: SW Corner of Building
Last Modified: 3/7/2013

Record Key: CLTR20126BJHW303P6XS
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 7
Desc of Loc(Or Transported) Subs: SW Corner of Building - Bulk Tank Area
Last Modified: 3/7/2013

Record Key: CLTR20126BJHW803QANE
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 7
Desc of Loc(Or Transported) Subs: Inside Building - South End
Last Modified: 3/7/2013

Record Key: CLTR201293TJ7U01ZQ7Z
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Yard - East Portion of Property
Last Modified: 3/7/2013

Record Key: CLTR201293TJ7Y020TEF
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside Building - South End
Last Modified: 3/7/2013

Record Key: CLTR201293TJ82021XAT
Chemical Inventory Record Id: CVTR20126BJHV103M99C
Amt Of Sub Stored Or Transported: Not reported

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock - West Side of Building
Last Modified:	3/7/2013

Facility Id:	FATR201226L4QV03PBP4
Chemical Name:	Argon
Chemical Inv Record Id:	CVTR201271WGT5015M0W
CAS Number:	7440-37-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201271WGZG0162QN
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Yard - South Side of Property
Last Modified:	3/7/2013

Record Key:	CLTR201271WH1Y0177HZ
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	Inside Building - South End
Last Modified:	3/7/2013

Record Key:	CLTR201293THGG01PSLE
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	7
Desc of Loc(Or Transported) Subs:	SE Corner of Building - Bulk Tank Area
Last Modified:	3/7/2013

Record Key:	CLTR201293THGM01QWQ4
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Yard - East Portion of Property
Last Modified:	3/7/2013

Record Key:	CLTR201293THP401RJCP
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside Building - South End
Last Modified:	3/7/2013

Record Key:	CLTR201294QC4L05RZJG
Chemical Inventory Record Id:	CVTR201271WGT5015M0W
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Cylinder
Number Code/Storage Pressure:	2
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Dock - West Side of Building
Last Modified:	3/7/2013

Facility Id:	FATR201226L4QV03PBP4
Chemical Name:	Propane
Chemical Inv Record Id:	CVTR201293T4BA01KXHG
CAS Number:	74-98-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	5080
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	T
Pure Form:	T
Reactive Hazard:	Not reported

AIRGAS USA, LLC - SOUTHWEST - AUSTIN (Continued) **S113677907**

Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2012
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201293T4FT01LUCG
Chemical Inventory Record Id: CVTR201293T4BA01KXHG
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Yard (Back of Facility) - North Side
Last Modified: 3/7/2013

Record Key: CLTR201293T4G001M070
Chemical Inventory Record Id: CVTR201293T4BA01KXHG
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: North Side of yard - Next to Bulk Tank
Last Modified: 3/7/2013

Record Key: CLTR201293T4ZR01NBHQ
Chemical Inventory Record Id: CVTR201293T4BA01KXHG
Amt Of Sub Stored Or Transported: Not reported
Amount Units: Not reported
Type Of Storage: Cylinder
Number Code/Storage Pressure: 2
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Concrete Bunkers - East End of Property
Last Modified: 3/7/2013

Notes: Not reported
Validation: Not reported

J33 Target Property | **FOSTER HI-TECH FINISHES**
10716 N LAMAR BLVD STE B
AUSTIN, TX 78753 | **TX Ind. Haz Waste** **S103602014**
TX CENTRAL REGISTRY **N/A**

Site 1 of 10 in cluster J

Actual: 751 ft.
Focus Map: 3

Ind. Haz Waste:
Name: FOSTER HI-TECH FINISHES
Address: 10716 N LAMAR BLVD STE B
City,State,Zip: AUSTIN, TX 78753
Permit Number: Not reported
Registration Number: 34984
Registration Initial Notification Date: 12/13/1985
Registration Last Amendment Date: 02/06/2007
EPA Identification: TXD981146269

FOSTER HI-TECH FINISHES (Continued) **S103602014**

Primary NAICS Code:	Not reported
Status Change Date:	19851213
Land Type:	PRIVATE
Description of Facility Site Location:	10716 N Lamar Blvd, Ste B, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	FOSTER HI-TECH FINISHES
Contact Name:	BILL FOSTER
Contact Telephone Number:	512-8355559
Mailing Address:	10716 N LAMAR BLVD STE B
Mailing Address2:	STE B
Mailing City,State,Zip:	AUSTIN, TX 787533162
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	12398
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20070206
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	FOSTER HI-TECH FINISHES
Operator Address:	10716 NLAMAR BLVD STE B
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8355559
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown

FOSTER HI-TECH FINISHES (Continued) **S103602014**

Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FOSTER HI-TECH FINISHES
Owner Mailing Address:	10716 NLAMAR BLVD STE B
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8355559
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	DRUMS Cap: 3000 LBS.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	10716 NLAMAR BLVD STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8355559
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported

FOSTER HI-TECH FINISHES (Continued) **S103602014**

Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	10716 NLAMAR BLVD STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8355559
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BILL FOSTER
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	10716 NLAMAR BLVD STE B
Contact Address 2:	STE B
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8355559
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100580539
Name:	FOSTER HI-TECH FINISHES
Address:	10716 N LAMAR BLVD STE B
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3162
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600290837
Customer Name:	FOSTER HI-TECH FINISHES
Customer Legal Name:	Foster Hi-Tech Finishes
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10716 N Lamar Blvd, Ste B, Austin, TX

Regulated Entity Number:	RN100580539
Name:	FOSTER HI-TECH FINISHES
Address:	10716 N LAMAR BLVD STE B
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3162
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600290837
Customer Name:	FOSTER HI-TECH FINISHES
Customer Legal Name:	Foster Hi-Tech Finishes
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

FOSTER HI-TECH FINISHES (Continued) **S103602014**

Physical Location Description: 10716 N Lamar Blvd, Ste B, Austin, TX

J34 Target Property | **FOSTER HI TECH FINISHES** | **RCRA NonGen / NLR** | **1000401374**
10716 N LAMAR BLVD STE B | **FINDS** | **TXD981146269**
AUSTIN, TX 78753 | **ECHO**

Site 2 of 10 in cluster J

Actual: 751 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	20070206
Handler Name:	Foster Hi Tech Finishes
Handler Address:	N LAMAR BLVD STE B
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD981146269
Contact Name:	BILL FOSTER
Contact Address:	N LAMAR BLVD STE B
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-835-5559
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD STE B
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Foster Hi Tech Finishes
Owner Type:	Private
Operator Name:	Foster Hi Tech Finishes
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

FOSTER HI TECH FINISHES (Continued) **1000401374**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20070220
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F019
Waste Description:	Wastewater Treatment Sludges From The Chemical Conversion Coating Of Aluminum, Except From Zirconium Phosphating In Aluminum Can Washing When Such Phosphating Is An Exclusive Conversion Coating Process.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WO FOSTER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: FOSTER HI TECH FINISHES	
Legal Status:	Private
Date Became Current:	20070206
Date Ended Current:	Not reported
Owner/Operator Address:	10716 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-835-5559
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: FOSTER HI TECH FINISHES	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported

FOSTER HI TECH FINISHES (Continued) **1000401374**

Owner/Operator Address: 10716 N LAMAR BLVD STE B
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-835-5559
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FOSTER HI TECH FINISHES
Legal Status: Private
Date Became Current: 20070206
Date Ended Current: Not reported
Owner/Operator Address: 10716 N LAMAR BLVD STE B
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-835-5559
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FOSTER HI TECH FINISHES
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 10716 N LAMAR BLVD STE B
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-835-5559
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19851017
Handler Name: FOSTER HI TECH FINISHES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: FOSTER HI TECH FINISHES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

FOSTER HI TECH FINISHES (Continued) **1000401374**

Receive Date:	20070206
Handler Name:	FOSTER HI TECH FINISHES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005086076

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000401374
Registry ID:	110005086076
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005086076
Name:	FOSTER HI TECH FINISHES
Address:	10716 N LAMAR BLVD STE B
City,State,Zip:	AUSTIN, TX 78753

J35 Target Property | **AUSTIN PERFORMANCE SPECIALTY & EQUIP INC SPEC AUTO** | **EDR Hist Auto** | **1013753129**
10716 LAMAR BLVD N | **N/A**
TRAVIS (County), TX 78753

Site 3 of 10 in cluster J

Actual: 751 ft.

EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1990	AUSTIN PERFORMANCE SPECIALTY &	AUTOMOBILE REPAIRING
2013	PERFORMANCE PLUS MACHINE	Automotive Repair Shops, NEC, NEC
2014	PERFORMANCE PLUS MACHINE	Automotive Repair Shops, NEC, NEC

J36 Target Property | **UNITED MOLDING** | **TX CENTRAL REGISTRY** | **S123848254**
10714 N LAMAR | **N/A**
AUSTIN, TX 78753

Site 4 of 10 in cluster J

Actual: 751 ft.

Focus Map: 3

CENTRAL REGISTRY:

Regulated Entity Number:	RN100720200
Name:	UNITED MOLDING
Address:	10714 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600408140
Customer Name:	UNITED MOLDING
Customer Legal Name:	United Molding, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/7/1983
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	10714 N LAMAR

Regulated Entity Number:	RN100720200
Name:	UNITED MOLDING
Address:	10714 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600408140
Customer Name:	UNITED MOLDING
Customer Legal Name:	United Molding, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/7/1983
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	10714 N LAMAR

J37 Target Property | **LANGHAM GROUP CULTURED MARBLE FACILITY**
10712 N LAMAR BLVD STE A
AUSTIN, TX 78753

TX AIRS **S118718392**
TX COMP HIST **N/A**
TX CENTRAL REGISTRY

Site 5 of 10 in cluster J

Actual: 751 ft.

Focus Map: 3

AIRS:

Name:	LANGHAM GROUP CULTURED MARBLE FACILITY
Address:	10712 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX
Permit Num:	141136
Regulated Id:	RN109241331
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	07/26/2016
Expiration Date:	12/31/3000
Customer Id:	CN605166214
Company Name:	LANGHAM GROUP, LLC
Physical Location Desc:	Not reported
Rep Official(RO):	OWNER
RO Name:	MR KENNETH LANGHAM JR
RO Delivery Address:	10712 N LAMAR BLVD STE C
RO City/State/Zip:	AUSTIN, T 78753-306
RO Phone:	806-783-9944
RO Ext Num:	0
RO EMail Address:	KEN@LANGHAMGROUPTX.COM
Lat Dec Coord Num:	30.377219
Long Dec Coord Num:	-97.691775

COMP HIST:

RN Number:	RN109241331
Name:	LANGHAM GROUP CULTURED MARBLE FACILITY
Address:	10712 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605166214
CN Name:	LANGHAM GROUP LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	321999
SIC Code:	3089
Related Number:	141136,141136

CENTRAL REGISTRY:

Regulated Entity Number:	RN109241331
Name:	LANGHAM GROUP CULTURED MARBLE FACILITY
Address:	10712 N LAMAR BLVD STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3066
Status:	ACTIVE
Status Date:	6/8/2016
Customer Number:	CN605166214

LANGHAM GROUP CULTURED MARBLE FACILITY (Continued) **S118718392**

Customer Name:	LANGHAM GROUP LLC
Customer Legal Name:	Langham Group, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/6/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109241331
Name:	LANGHAM GROUP CULTURED MARBLE FACILITY
Address:	10712 N LAMAR BLVD STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3066
Status:	ACTIVE
Status Date:	6/8/2016
Customer Number:	CN605166214
Customer Name:	LANGHAM GROUP LLC
Customer Legal Name:	Langham Group, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/6/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

J38 **LANGFORD CABINETS** **TX CENTRAL REGISTRY** **S123848720**
Target **10710 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78701**

Site 6 of 10 in cluster J

Actual:
750 ft.

Focus Map:
3

CENTRAL REGISTRY:

Regulated Entity Number:	RN100725670
Name:	LANGFORD CABINETS
Address:	10710 NORTH LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600413207
Customer Name:	LANGFORD CABINETS INC
Customer Legal Name:	Langford Cabinet, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/10/1985
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	10710 NORTH LAMAR

Regulated Entity Number:	RN100725670
Name:	LANGFORD CABINETS
Address:	10710 NORTH LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701

LANGFORD CABINETS (Continued) **S123848720**

Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600413207
Customer Name:	LANGFORD CABINETS INC
Customer Legal Name:	Langford Cabinet, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/10/1985
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	10710 NORTH LAMAR

J39 **NU-WAY UPHOLSTERY** **EDR Hist Cleaner** **1018555819**
Target **10721 N LAMAR** **N/A**
Property **AUSTIN, TX 78753**

Site 7 of 10 in cluster J

Actual:
749 ft.

EDR Hist Cleaner

Focus Map:
3

Year:	Name:	Type:
1983	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning
1985	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning
1986	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning
1987	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning
1988	BUDGET CLEANERS	Drycleaning Plants, Except Rugs
1988	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning
1989	BUDGET CLEANERS	Drycleaning Plants, Except Rugs
1989	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning On Customer Premises
1990	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning On Customer Premises
1990	BUDGET CLEANERS	Drycleaning Plants, Except Rugs
1991	NU-WAY UPHOLSTERY	Carpet And Upholstery Cleaning On Customer Premises

---

K40 **SUPER CARE CLEANERS DRY CDNA** **EDR Hist Cleaner** **1013784978**
Target **10206 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78753**

Site 1 of 3 in cluster K

Actual:
719 ft.

EDR Hist Cleaner

Focus Map:
3

Year:	Name:	Type:
1990	SUPER CARE CLEANERS DRY CDNA	CLEANERS AND DYERS

K41 Target Property | **SUPER CARE CLEANERS 2**
10205 N LAMAR
AUSTIN, TX 78753 | **EDR Hist Cleaner** | **1018778970**
N/A

Site 2 of 3 in cluster K

Actual: 720 ft.

Focus Map: 3

EDR Hist Cleaner

Year:	Name:	Type:
1988	SUPER CARE CLEANERS 2	Garment Pressing And Cleaners' Agents
1989	SUPER CARE CLEANERS 2	Garment Pressing And Cleaners' Agents
1990	SUPER CARE CLEANERS 2	Garment Pressing And Cleaners' Agents
1994	SUPER CARE CLEANERS	Drycleaning Plants, Except Rugs

L42 Target Property | **NAPA AUTO PARTS 22**
10101 N LAMAR BLVD
AUSTIN, TX 78753 | **FINDS** | **1011354722**
N/A

Site 1 of 3 in cluster L

Actual: 712 ft.

Focus Map: 3

FINDS:
Registry ID: 110034776650

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

L43 Target Property | **AUSTEX AUTO PARTS**
10101 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S126524417**
N/A

Site 2 of 3 in cluster L

Actual: 712 ft.

Focus Map: 3

CENTRAL REGISTRY:

Regulated Entity Number:	RN101502979
Name:	AUSTEX AUTO PARTS
Address:	10101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3601
Status:	ACTIVE
Status Date:	2/25/2002
Customer Number:	CN600242879
Customer Name:	NAPA AUTO PARTS
Customer Legal Name:	Napa Auto Parts
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

AUSTEX AUTO PARTS (Continued) **S126524417**

Physical Location Description:	10101 NORTH LAMAR

Regulated Entity Number:	RN101502979
Name:	AUSTEX AUTO PARTS
Address:	10101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3601
Status:	ACTIVE
Status Date:	2/25/2002
Customer Number:	CN600242879
Customer Name:	NAPA AUTO PARTS
Customer Legal Name:	Napa Auto Parts
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10101 NORTH LAMAR

Regulated Entity Number:	RN101502979
Name:	AUSTEX AUTO PARTS
Address:	10101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3601
Status:	ACTIVE
Status Date:	2/25/2002
Customer Number:	CN600915797
Customer Name:	AUSTEX AUTO PARTS INCORPORATED
Customer Legal Name:	Austex Auto Parts Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10101 NORTH LAMAR

Regulated Entity Number:	RN101502979
Name:	AUSTEX AUTO PARTS
Address:	10101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3601
Status:	ACTIVE
Status Date:	2/25/2002
Customer Number:	CN600915797
Customer Name:	AUSTEX AUTO PARTS INCORPORATED
Customer Legal Name:	Austex Auto Parts Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10101 NORTH LAMAR

M44 Target Property | **AUTOZONE**
9905 N LAMAR BLVD
AUSTIN, TX 78753 | **TX ASBESTOS** | **S119138964**
N/A

Site 1 of 3 in cluster M

Actual: 700 ft.

Focus Map: 3

ASBESTOS:

Name:	AUTOZONE
Address:	9905 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

AUTOZONE (Continued) **S119138964**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

M45 Target Property **AUTOZONE 1396**
9905 N LAMAR BLVD
AUSTIN, TX 78753

FINDS **1010694624**
N/A

Site 2 of 3 in cluster M

Actual: 700 ft.

Focus Map: 3

FINDS:
Registry ID: 110033228736

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M46 Target Property **AUTOZONE 1396**
9905 N LAMAR BLVD
AUSTIN, TX 78753

TX CENTRAL REGISTRY **S126601219**
N/A

Site 3 of 3 in cluster M

Actual: 700 ft.

Focus Map: 3

CENTRAL REGISTRY:

Regulated Entity Number:	RN102992153
Name:	AUTOZONE 1396
Address:	9905 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133136
Customer Name:	AUTOZONE INC
Customer Legal Name:	Autozone, Inc.

AUTOZONE 1396 (Continued) **S126601219**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	9/24/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	9905 N LAMAR BLVD

Regulated Entity Number:	RN102992153
Name:	AUTOZONE 1396
Address:	9905 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133136
Customer Name:	AUTOZONE INC
Customer Legal Name:	Autozone, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	9/24/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	9905 N LAMAR BLVD

Regulated Entity Number:	RN102992153
Name:	AUTOZONE 1396
Address:	9905 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604679654
Customer Name:	AUTOZONE PARTS INC
Customer Legal Name:	Autozone Parts, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/25/2014
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	9905 N LAMAR BLVD

Regulated Entity Number:	RN102992153
Name:	AUTOZONE 1396
Address:	9905 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604679654
Customer Name:	AUTOZONE PARTS INC
Customer Legal Name:	Autozone Parts, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/25/2014
Affiliation End Date:	12/31/3000

AUTOZONE 1396 (Continued) **S126601219**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	9905 N LAMAR BLVD

---

47 Target Property | **BRIDENT DENTAL**
9813 N. LAMAR BLVD.
AUSTIN, TX 78753 | **RCRA-VSQG FINDS ECHO** | **1016452460 TXR000081608**

Actual: 696 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	20131104
Handler Name:	Brident Dental
Handler Address:	N. LAMAR BLVD.
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXR000081608
Contact Name:	EDWARD SALDANA
Contact Address:	S. MAIN ST.
Contact City,State,Zip:	ORANGE, CA 92868
Contact Telephone:	714-571-3502
Contact Fax:	714-571-3599
Contact Email:	ESALDANA@WESTERNDENTAL.COM
Contact Title:	FACILITIES MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	12
Mailing Address:	S. MAIN ST.
Mailing City,State,Zip:	ORANGE, CA 92868
Owner Name:	Brident Dental Services, Llc
Owner Type:	Private
Operator Name:	Brident Dental
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	Yes
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

BRIDENT DENTAL (Continued) **1016452460**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20131104
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D011
Waste Description:	Silver

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: BRIDENT DENTAL	
Legal Status:	Private
Date Became Current:	20140123
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BRIDENT DENTAL SERVICES, LLC	
Legal Status:	Private
Date Became Current:	20140123
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20131104
Handler Name:	BRIDENT DENTAL

BRIDENT DENTAL (Continued) **1016452460**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	339114
NAICS Description:	DENTAL EQUIPMENT AND SUPPLIES MANUFACTURING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110056335862

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016452460
Registry ID:	110056335862
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056335862
Name:	BRIDENT DENTAL
Address:	9813 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78753

N48 **FAMILY DOLBAR** **TX ASBESTOS** **S119145071**
Target **9719 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 3 in cluster N

Actual:
691 ft.

Focus Map:
6

ASBESTOS:

Name:	FAMILY DOLLAR
Address:	9719 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	04/15/2013

FAMILY DOLLAR (Continued) **S119145071**

Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/24/2013
Date Routed by Supervisor:	04/24/2013
Date Routed to PSQA:	04/29/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

FAMILY DOLLAR (Continued) **S119145071**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

O49 Target Property **LAUNDRY BASKET NO 1 THE**
9644 LAMAR BLVD N
TRAVIS (County), TX 78753

EDR Hist Cleaner **1013784800**
N/A

Site 1 of 9 in cluster O

Actual: 688 ft.

EDR Hist Cleaner

Focus Map: 6

Year:	Name:	Type:
1984	A LAUNDRY BASKET NO	LAUNDRIES-SELF SERVE
1990	LAUNDRY BASKET NO 1 THE	LAUNDRIES-SELF SERVE
1991	LAUNDRY BASKET NUMBER 1	Coin-Operated Laundries And Cleaning, NEC
1992	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1993	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1994	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1995	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC

O50 Target Property **DRY CLEAN CITY 125**
9626 N LAMAR BLVD
AUSTIN, TX 78753

EDR Hist Cleaner **1019975931**
N/A

Site 2 of 9 in cluster O

Actual: 688 ft.

EDR Hist Cleaner

Focus Map: 6

Year:	Name:	Type:
1993	DRY CLEAN CITY 125	Drycleaning Plants, Except Rugs, NEC

O51 Target Property **DRY CLEAN CITY**
9626 N LAMAR BLVD
AUSTIN, TX 78753

RCRA NonGen / NLR **1000836137**
FINDS **TXD988071395**
ECHO

Site 3 of 9 in cluster O

Actual: 688 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20060613
Handler Name:	Dry Clean City
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD988071395
Contact Name:	WINN MCCOREA
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-834-0812
Contact Fax:	Not reported
Contact Email:	Not reported

DRY CLEAN CITY (Continued) **1000836137**

Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Dry Clean City
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

DRY CLEAN CITY (Continued) **1000836137**

Hazardous Waste Summary:

Waste Code:	D007
Waste Description:	Chromium
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MCCREA CLEANING CRP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6926 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-834-0812
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: DRY CLEAN CITY	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	9626 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-834-0812
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: DRY CLEAN CITY	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	9626 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-834-0812
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: DRY CLEAN CITY	
Legal Status:	Private
Date Became Current:	20010127

DRY CLEAN CITY (Continued) **1000836137**

Date Ended Current:	Not reported
Owner/Operator Address:	9626 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-834-0812
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920507
Handler Name: DRYCLEAN CITY	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010127
Handler Name: DRY CLEAN CITY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060613
Handler Name: DRY CLEAN CITY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	81232
NAICS Description:	DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

DRY CLEAN CITY (Continued) **1000836137**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005150415

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836137
Registry ID:	110005150415
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005150415
Name:	DRY CLEAN CITY
Address:	9626 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

O52 Target Property | **DRY CLEAN CITY**
9626 N LAMAR BLVD
AUSTIN, TX 78753 | **TX Ind. Haz Waste** **S102758173**
TX CENTRAL REGISTRY **N/A**

Site 4 of 9 in cluster O

Actual: 688 ft.

Focus Map: 6

Ind. Haz Waste:

Name:	DRY CLEAN CITY
Address:	9626 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	77632
Registration Initial Notification Date:	07/27/1992
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD988071395
Primary NAICS Code:	812320
Status Change Date:	19920727
Land Type:	PRIVATE
Description of Facility Site Location:	9626 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

DRY CLEAN CITY (Continued) **S102758173**

Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	DRY CLEAN CITY
Contact Name:	WINN MCCOREA
Contact Telephone Number:	512-8340812
Mailing Address:	9626 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787534110
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31858
Site Owner Tax ID:	562296110
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060613
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	DRY CLEAN CITY
Operator Address:	9626 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8340812
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	32000351554
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DRY CLEAN CITY
Owner Mailing Address:	9626 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8340812
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	32000351554

DRY CLEAN CITY (Continued) **S102758173**

Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	9626 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8340812
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	9626 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8340812
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WINN MCCOREA
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	9626 N LAMAR BLVD
Contact Address 2:	Not reported

DRY CLEAN CITY (Continued) **S102758173**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8340812
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	140494
Texas Waste Code:	Not reported
Texas Waste Code 2:	0506609H
Waste Code Status:	INACTIVE
Waste Form:	609
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	PERC SLUDGE
Standard Industrial Code:	72160
Primary Source:	G24
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169512082
Primary NAICS Code:	812320
EPA Waste Form Code:	W609
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9626 N LAMAR BLVD STE 110
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310896
Principal Name:	DRY CLEAN CITY
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9626 N LAMAR BLVD STE 110
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310896
Principal Name:	DRY CLEAN CITY
Attention Name:	Not reported
Attention Suffix:	NWF

DRY CLEAN CITY (Continued) **S102758173**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9626 N LAMAR BLVD STE 110
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310896
Principal Name:	DRY CLEAN CITY
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9626 N LAMAR BLVD STE 110
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310896
Principal Name:	DRY CLEAN CITY
Attention Name:	Not reported
Attention Suffix:	HWF

CENTRAL REGISTRY:

Regulated Entity Number:	RN100635481
Name:	DRY CLEAN CITY
Address:	9626 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4110
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346126
Customer Name:	DRY CLEAN CITY
Customer Legal Name:	Chris LE, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	9626 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100635481
Name:	DRY CLEAN CITY
Address:	9626 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4110
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346126
Customer Name:	DRY CLEAN CITY
Customer Legal Name:	Chris LE, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320

DRY CLEAN CITY (Continued) **S102758173**

Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 9626 N Lamar Blvd, Austin, TX

Regulated Entity Number: RN100635481
Name: DRY CLEAN CITY
Address: 9626 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-4110
Status: ACTIVE
Status Date: ##########
Customer Number: CN600346126
Customer Name: DRY CLEAN CITY
Customer Legal Name: Chris LE, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 9626 N Lamar Blvd, Austin, TX

Regulated Entity Number: RN100635481
Name: DRY CLEAN CITY
Address: 9626 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-4110
Status: ACTIVE
Status Date: ##########
Customer Number: CN600346126
Customer Name: DRY CLEAN CITY
Customer Legal Name: Chris LE, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 9626 N Lamar Blvd, Austin, TX

Regulated Entity Number: RN100635481
Name: DRY CLEAN CITY
Address: 9626 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-4110
Status: ACTIVE
Status Date: ##########
Customer Number: CN600346126
Customer Name: DRY CLEAN CITY
Customer Legal Name: Chris LE, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 9626 N Lamar Blvd, Austin, TX

DRY CLEAN CITY (Continued) **S102758173**

Regulated Entity Number:	RN100635481
Name:	DRY CLEAN CITY
Address:	9626 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4110
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346126
Customer Name:	DRY CLEAN CITY
Customer Legal Name:	Chris LE, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	9626 N Lamar Blvd, Austin, TX

O53 **AUTO ZONE 1396** **TX CENTRAL REGISTRY** **S126555693**
Target **9620 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 5 of 9 in cluster O

Actual:
688 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN102002805
Name:	AUTO ZONE 1396
Address:	9620 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4110
Status:	ACTIVE
Status Date:	4/22/2002
Customer Number:	CN600133136
Customer Name:	AUTOZONE INC
Customer Legal Name:	Autozone, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	9620 N LAMAR BLVD

Regulated Entity Number:	RN102002805
Name:	AUTO ZONE 1396
Address:	9620 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4110
Status:	ACTIVE
Status Date:	4/22/2002
Customer Number:	CN600133136
Customer Name:	AUTOZONE INC
Customer Legal Name:	Autozone, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

AUTO ZONE 1396 (Continued) **S126555693**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: 9620 N LAMAR BLVD

O54 Target Property **AUTO ZONE 1396**
9620 N LAMAR BLVD
AUTO ZONE 1396 **FINDS** **1010739385**
N/A

Site 6 of 9 in cluster O

Actual: 688 ft.
Focus Map: 6

FINDS:
Registry ID: 110033457293

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

O55 Target Property **ACME CLEANERS**
9606 LAMAR BLVD N
AUTO ZONE 1396 **EDR Hist Cleaner** **1013785230**
N/A

Site 7 of 9 in cluster O

Actual: 686 ft.
Focus Map: 6

EDR Hist Cleaner

Year:	Name:	Type:
1984	ACME CLEANERS	CLEANERS AND DYERS

---

56 Target Property **DOLLAR TREE**
9514 N LAMAR BLVD
AUTO ZONE 1396 **TX ASBESTOS** **S119143829**
N/A

Actual: 682 ft.
Focus Map: 6

ASBESTOS:

Name:	DOLLAR TREE
Address:	9514 N LAMAR BLVD
City,State,Zip:	AUTO ZONE 1396 AUSTIN, TX 78753
Date of inspection:	04/15/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1

DOLLAR TREE (Continued) **S119143829**

Mileage:	0
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/24/2013
Date Routed by Supervisor:	04/24/2013
Date Routed to PSQA:	04/29/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

P57 HEB 183 **TX CENTRAL REGISTRY** **S126602473**
Target 9411B N LAMAR BLVD **N/A**
Property AUSTIN, TX 78753

Site 1 of 4 in cluster P

Actual: 682 ft.
Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN103025433
Name:	HEB 183
Address:	9411B N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4105
Status:	ACTIVE
Status Date:	3/13/2003
Customer Number:	CN601297963
Customer Name:	H-E-B LP
Customer Legal Name:	H-E-B, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

P58 ACEMART RESTAURANT SUPPLY **TX HIST UST** **S119137504**
Target 9411 N LAMAR BLVD **TX ASBESTOS** **N/A**
Property AUSTIN, TX 78753

Site 2 of 4 in cluster P

Actual: 682 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	HEB #183 - AUSTIN #15
Address:	9411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3276
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	ACEMART RESTAURANT SUPPLY
Address:	9411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	04/15/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	2.5
Reg:	07
Init:	EJ

ACEMART RESTAURANT SUPPLY (Continued) **S119137504**

Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/24/2013
Date Routed by Supervisor:	04/24/2013
Date Routed to PSQA:	04/29/2013
Date Reviewed by PSQA:	Received from Mich
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

P59 Target Property | **HEB 183**
9411B N LAMAR BLVD
AUSTIN, TX 78753 | **FINDS** | **1010758310**
N/A

Site 3 of 4 in cluster P

Actual: 682 ft.
Focus Map: 6

FINDS:
Registry ID: 110033900241

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P60 Target Property | **HEB 183**
9411B N LAMAR BLVD
AUSTIN, TX 78753 | **TX UST**
TX Financial Assurance | **U003876513**
N/A

Site 4 of 4 in cluster P

Actual: 682 ft.
Focus Map: 6

UST:

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787534105
AI Number:	75357
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	514742632003072
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/11/2002
Signature Name/Title On Earliest Reg Form:	TERRY PARR,OPS MGR
Application Received Date On Earliest Reg Form:	09/11/2002
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported

HEB 183 (Continued) **U003876513**

Enforcement Action: No
Facility Not Inspectable: No

Operator:
Princ ID: 691789092002161
Additional ID: 514742632003072
Ai Number: 75357
Operator CN: CN601297963
Operator Name: H-E-B LP
Operator Effective Begin Date: 09/11/2002
Operator Type: PA
Operator Role: OWNOPRCON
Contact Name: TERRY PARR/
Contact Organization Name: H-E-B LP
Contact Mailing Address (Delivery): PO BOX 839968
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: SAN ANTONIO TX 78283-3968
Contact Phone Country Code: 0
Contact Phone Area Code: 210
Contact Phone Number: 9384040
Contact Phone Extension: 0
Contact Fax Country Code: Not reported
Contact Fax Area Code: Not reported
Contact Fax Number: Not reported
Contact Fax Extension: Not reported
Contact Email Address: PARR.TERRY@HEB.COM
Contact Address Deliverable: Not reported

Owner:
Owner CN: CN601297963
Owner Last Name: H-E-B LP
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: PA
Contact Mailing Address (Delivery): PO BOX 839968
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: SAN ANTONIO
Contact Mailing State: TX
Contact Mailing Zip: 78283
Contact Mailing Zip5: 3968
Contact Phone Number/Ext: 0 210 9384040/0
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: PARR.TERRY@HEB.COM
Contact Address Deliverable: Not reported
Princ ID: 691789092002161
Additional ID: 514742632003072
AI Number: 75357
Owner Effective Begin Date: 09/11/2002
State Tax ID: 17430106579
Contact Role: OWNOPRCON
Contact Name/Title: TERRY PARR/
Contact Organization Name: H-E-B LP

Self Certification:
Self Cert ID: 115397
Cert ID: 373558

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/29/2022
Signature Name/Title:	REGINA LOPEZ PETROLEUM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	356914
AI Number:	75357
Self Certification Date:	07/29/2021
Signature Name/Title:	Regina Lopez Petroleum Operations
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	339781
AI Number:	75357
Self Certification Date:	07/21/2020
Signature Name/Title:	Regina Lopez Operations Trainer
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	323741

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/26/2019
Signature Name/Title:	Jude A Fournier Petroleum Ops Traing
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	307133
AI Number:	75357
Self Certification Date:	07/30/2018
Signature Name/Title:	Jude A Fournier Petroleum Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	290019
AI Number:	75357
Self Certification Date:	08/07/2017
Signature Name/Title:	Jude A Fournier Petroleum Manager
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	273876

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	08/19/2016
Signature Name/Title:	Rosie Espinoza petroluem advisor
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	256333
AI Number:	75357
Self Certification Date:	08/06/2015
Signature Name/Title:	Rosie Espinoza petrol
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	239030
AI Number:	75357
Self Certification Date:	07/21/2014
Signature Name/Title:	Rosie Espinoza petroleum advisor
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	221832

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/11/2013
Signature Name/Title:	Rosie Espinoza Administrative
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	115397
Cert ID:	207388
AI Number:	75357
Self Certification Date:	07/12/2012
Signature Name/Title:	ROSIE ESPINOZA PETROLEUM ADVISOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207387
AI Number:	75357
Self Certification Date:	07/20/2011
Signature Name/Title:	ROSIE GOMEZ ADMINISTRATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207386

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/30/2010
Signature Name/Title:	ROSIE GOMEZ PETROLEUM ADVISOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207385
AI Number:	75357
Self Certification Date:	07/21/2009
Signature Name/Title:	ROSIE GOMEZ PETROLEUM ADVISOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207384
AI Number:	75357
Self Certification Date:	08/27/2008
Signature Name/Title:	ROSIE GOMEZ ADMIN
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207383

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/18/2007
Signature Name/Title:	ROSIE GOMEZ TECHNICAL SUPPORT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207382
AI Number:	75357
Self Certification Date:	07/06/2006
Signature Name/Title:	TERRY PARR OPERATIONS MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207381
AI Number:	75357
Self Certification Date:	07/20/2005
Signature Name/Title:	ROSIE GOMEZ ADMINISTRATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207380

HEB 183 (Continued) **U003876513**

AI Number:	75357
Self Certification Date:	07/08/2004
Signature Name/Title:	ROSIE GOMEZ ADMINISTRATION
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207379
AI Number:	75357
Self Certification Date:	07/09/2003
Signature Name/Title:	ROSIE GOMEZ HEB FACILITY ADMIN
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	115397
Cert ID:	207378
AI Number:	75357
Self Certification Date:	09/11/2002
Signature Name/Title:	TERRY PARR OPS MGR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/14/2002

HEB 183 (Continued) **U003876513**

Tank Registration Date:	09/11/2002
Number of Compartments:	2
Tank Capacity:	23000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	200469
Facility ID:	115397
Ai Number:	75357
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/14/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

HEB 183 (Continued) **U003876513**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/11/2002

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	171828
UST ID:	200469
AI Number:	75357
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	171829
UST ID:	200469
AI Number:	75357
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

HEB 183 (Continued) **U003876513**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	28682
Cert ID:	72227
UST Comprt ID:	218988
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72234
UST Comprt ID:	218984
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72231
UST Comprt ID:	218992
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A

HEB 183 (Continued) **U003876513**

Self Cert ID:	28682
Cert ID:	72233
UST Comprt ID:	218985
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72236
UST Comprt ID:	218982
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72232
UST Comprt ID:	218986
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72235
UST Comprt ID:	218983
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72226
UST Comprt ID:	218987
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72229
UST Comprt ID:	218990
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682
Cert ID:	72228
UST Comprt ID:	218989
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28682

HEB 183 (Continued) **U003876513**

Cert ID:	72230
UST Comprt ID:	218991
UST ID:	75418
AI Number:	75357
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	18986
Facility ID:	115397
AI Number:	75357
Application Received Date:	07/29/2002
Scheduled Construction Date:	08/28/2002
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M20729013
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	Not reported

NOC ID:	18985
Facility ID:	115397
AI Number:	75357
Application Received Date:	11/18/2004
Scheduled Construction Date:	09/04/2004
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M41118003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported

HEB 183 (Continued) **U003876513**

Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	1777
General Desc Of Prop Construct:	Not reported

NOC ID:	18984
Facility ID:	115397
AI Number:	75357
Application Received Date:	03/18/2005
Scheduled Construction Date:	04/17/2005
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50318044
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	58478
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	36517
UST ID:	200469
NOC ID:	Not reported
AI Number:	75357
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001224
Company Name:	Service Station Concrete
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

HEB 183 (Continued) **U003876513**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	20303
UST ID:	Not reported
NOC ID:	18985
AI Number:	75357
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000103
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	51681
UST ID:	200469
NOC ID:	Not reported
AI Number:	75357
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000460
Company Name:	Not reported
Representative Name:	EDDIE DAMINSKI
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	H-E-B LP

HEB 183 (Continued) **U003876513**

Contact Mailing Address (Delivery):	PO BOX 839968
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78283 3968
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	115397
Additional ID:	514742632003072
Princ ID:	691789092002161
AI Number:	75357
Facility Name:	HEB 183
AR Number:	58478
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	TERRY PARR/

TX Financial Assurance 2:

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	271405
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 6888254
Policy Number:	ISPILLSCFI7W001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	253867
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

HEB 183 (Continued) **U003876513**

Financial Assurance Begin Date:	12/29/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	233967
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	217078
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

HEB 183 (Continued) **U003876513**

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	200279
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	182237
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	165907
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

HEB 183 (Continued) **U003876513**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	147140
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	AIG INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	129961
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	OTHER
Issuer Phone:	Not reported

HEB 183 (Continued) **U003876513**

Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	110491
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	CHARTIS SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	112598
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	CHARTIS SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

HEB 183 (Continued) **U003876513**

Region:	2
Facility ID:	115397
Finass ID:	14637
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/05/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9384934
Policy Number:	0
Coverage Amount:	1000000
Coverage Expiration Date:	01/05/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	99382
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9387042
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	07/27/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	99383
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

HEB 183 (Continued) **U003876513**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/12/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9387042
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	01/12/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	99384
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/18/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9387042
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	08/18/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 183
Address:	9411B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	115397
Finass ID:	99385
AI:	75357
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901

HEB 183 (Continued) **U003876513**

Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: No

Q61 **A ACME CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1013779843**
Target **9302 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 2 in cluster Q

Actual: EDR Hist Cleaner
684 ft.

Focus Map:
6

Year:	Name:	Type:
1975	A ACME CLEANERS & LAUNDRY	CLEANERS AND DYERS
1980	A ACME CLEANERS & LAUNDRY	CLEANERS AND DYERS

R62 **CAPITAL FINA OIL SERV STATION** **EDR Hist Auto** **1013774945**
Target **8909 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78753**

Site 1 of 12 in cluster R

Actual: EDR Hist Auto
662 ft.

Focus Map:
6

Year:	Name:	Type:
1975	CAPITAL FINA OIL SERV STATION	GASOLINE STATIONS

R63 **ERNS** **2005776537**
Target **8833 NORTH LAMAR** **N/A**
Property **AUSTIN, TX**

Site 2 of 12 in cluster R

Actual:
659 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Focus Map:
6

R64 **TARGA PORSCHE** **EDR Hist Auto** **1013761561**
Target **8833 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78753**

Site 3 of 12 in cluster R

Actual: EDR Hist Auto
659 ft.

Focus Map:
6

Year:	Name:	Type:
1974	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1975	TARGA PORSCHE	REPAIR SHOPS
1975	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1976	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1977	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops

TARGA PORSCHE (Continued) **1013761561**

1978	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1979	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1980	TARGA PORSCH WORKSHOP	REPAIR SHOPS
1980	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1982	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1983	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1984	TARGA PORSCHE WORKSHOP INC AUTO	REPAIR SHOPS
1985	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1986	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1987	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1988	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1989	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1990	TARGA PORSCHE WORKSHOP INC AUTO	REPAIR SHOPS
1990	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1991	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1992	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1993	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1994	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1995	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1996	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1997	TARGA PORSCHE WORKSHOP INC	General Automotive Repair Shops
1998	TPWF INC	General Automotive Repair Shops
1999	TPWF INC	General Automotive Repair Shops
2000	TPWF INC	General Automotive Repair Shops
2001	TPWF INC	General Automotive Repair Shops
2002	TPWF INC	General Automotive Repair Shops
2003	TPWF INC	General Automotive Repair Shops
2004	TPWF INC	General Automotive Repair Shops
2005	TPWF INC	General Automotive Repair Shops
2006	TPWF INC	General Automotive Repair Shops
2007	TPWF INC	General Automotive Repair Shops
2008	TPWF INC	General Automotive Repair Shops
2009	TPWF INC	General Automotive Repair Shops
2010	TPWF INC	General Automotive Repair Shops
2011	TPWF INC	General Automotive Repair Shops
2012	TPWF INC	General Automotive Repair Shops
2013	TPWF INC	General Automotive Repair Shops
2014	TPWF INC	General Automotive Repair Shops

R65 **TARGA PORSCHE** **TX Ind. Haz Waste** **S103605627**
Target **8833 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78753**

Site 4 of 12 in cluster R

Actual:
659 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	TARGA PORSCHE
Address:	8833 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61294
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	8833 N Lamar Blvd, Austin, TX

TARGA PORSCHE (Continued) **S103605627**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TPWS INC
Contact Name:	CAROL KOEHN
Contact Telephone Number:	Not reported
Mailing Address:	8833 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535425
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19649
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TPWS INC
Operator Address:	8833 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17417014622
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TPWS INC
Owner Mailing Address:	8833 N LAMAR BLVD

TARGA PORSCHE (Continued) **S103605627**

Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17417014622
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8833 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8833 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	CAROL KOEHN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8833 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100613173
Name:	TARGA PORSCHE
Address:	8833 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600322408
Customer Name:	TPWS INC

TARGA PORSCHE (Continued) **S103605627**

Customer Legal Name:	TPWS, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8833 N Lamar Blvd, Austin, TX

S66 **LACE** **TX Ind. Haz Waste** **S103599310**
Target **8829 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 9 in cluster S

Actual:
651 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	LACE
Address:	8829 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	30456
Registration Initial Notification Date:	04/15/1976
Registration Last Amendment Date:	11/06/1998
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19760415
Land Type:	Not reported
Description of Facility Site Location:	8829 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	LACE INC
Contact Name:	DON BRESIE
Contact Telephone Number:	512-8362380
Mailing Address:	PO BOX 9757
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787669757
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	8021
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040220
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

LACE (Continued) **S103599310**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	LACE INCORPORATED
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	LACE INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	LACE INCORPORATED
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	LACE INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported

LACE (Continued) **S103599310**

Owner Telephone: Not reported
Owner Fax: Not reported
Owner Email Address: Not reported
Owner Business Type: Corporation
Owner Tax ID: Not reported
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: DON BRESIE
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: PO BOX 9757
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78766
Contact Phone: 1-512-8362380
Contact Fax: Not reported
Contact Email: Not reported

S67 **LACE** **TX CENTRAL REGISTRY** **S126592572**
Target **8829 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 2 of 9 in cluster S

Actual:
651 ft.

Focus Map:
6

CENTRAL REGISTRY:
Regulated Entity Number: RN102786514
Name: LACE
Address: 8829 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-5425
Status: ACTIVE
Status Date: 7/24/2002
Customer Number: CN600409809
Customer Name: LACE INC
Customer Legal Name: LACE, INC.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 8829 N Lamar Blvd, Austin, TX

Regulated Entity Number: RN102786514
Name: LACE
Address: 8829 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-5425
Status: ACTIVE
Status Date: 7/24/2002
Customer Number: CN603896366
Customer Name: LACE INCORPORATED
Customer Legal Name: LACE INCORPORATED
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 11/6/1998

LACE (Continued) **S126592572**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8829 N Lamar Blvd, Austin, TX

S68 Target Property **AUSTIN DATSUN REPAIR AUTO REPR** **EDR Hist Auto** **1013756144**
8825 LAMAR BLVD N **N/A**
TRAVIS (County), TX 78753

Site 3 of 9 in cluster S

Actual: 655 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1984	AUSTIN DATSUN REPAIR	AUTOMOBILE REPAIRING
1989	PRO MOTION AUTO MACH	General Automotive Repair Shops
1990	AUSTIN DATSUN REPAIR AUTO REPR	AUTOMOBILE REPAIRING
1990	PRO MOTION AUTO MACH	General Automotive Repair Shops
1992	PRO MOTION AUTO MACH	General Automotive Repair Shops
1993	PRO MOTION AUTO MACH	General Automotive Repair Shops

S69 Target Property **LACE ENGINEERING** **TX CENTRAL REGISTRY** **S123848402**
8825 N LAMAR **N/A**
AUSTIN, TX 78753

Site 4 of 9 in cluster S

Actual: 655 ft.

Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN100721950
Name:	LACE ENGINEERING
Address:	8825 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600409809
Customer Name:	LACE INC
Customer Legal Name:	LACE, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/17/1983
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541710
Primary NAICS Industry Type Description:	Research and Development in the Physical, Engineering, and Life Sciences
Physical Location Description:	8825 N LAMAR

Regulated Entity Number:	RN100721950
Name:	LACE ENGINEERING
Address:	8825 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600409809

LACE ENGINEERING (Continued) **S123848402**

Customer Name:	LACE INC
Customer Legal Name:	LACE, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/17/1983
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541710
Primary NAICS Industry Type Description:	Research and Development in the Physical, Engineering, and Life Sciences
Physical Location Description:	8825 N LAMAR

S70 Target Property | **TRIPLE JS TIRE CENTER** | **TX CENTRAL REGISTRY** | **S126896791**
8821 N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 5 of 9 in cluster S

Actual: 656 ft.
Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN108921909
Name:	TRIPLE JS TIRE CENTER
Address:	8821 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5425
Status:	ACTIVE
Status Date:	12/16/2015
Customer Number:	CN605041037
Customer Name:	TRIPLE JS TIRE CENTER
Customer Legal Name:	Triple Js Tire Center
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

T71 Target Property | **ALLSTAR BODY SHOP** | **TX CENTRAL REGISTRY** | **S126525598**
8703A N LAMAR BLVD | **N/A**
AUSTIN, TX 78753

Site 1 of 7 in cluster T

Actual: 676 ft.
Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN101518090
Name:	ALLSTAR BODY SHOP
Address:	8703A N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5423
Status:	ACTIVE
Status Date:	2/28/2002
Customer Number:	CN600415988
Customer Name:	ALLSTAR BODY SHOP
Customer Legal Name:	All Star Body Shop, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000

ALLSTAR BODY SHOP (Continued) **S126525598**

Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	8703A N LAMAR & ELLIOT AUSTIN TX

Regulated Entity Number:	RN101518090
Name:	ALLSTAR BODY SHOP
Address:	8703A N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5423
Status:	ACTIVE
Status Date:	2/28/2002
Customer Number:	CN600415988
Customer Name:	ALLSTAR BODY SHOP
Customer Legal Name:	All Star Body Shop, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	8703A N LAMAR & ELLIOT AUSTIN TX

Regulated Entity Number:	RN101518090
Name:	ALLSTAR BODY SHOP
Address:	8703A N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5423
Status:	ACTIVE
Status Date:	2/28/2002
Customer Number:	CN600415988
Customer Name:	ALLSTAR BODY SHOP
Customer Legal Name:	All Star Body Shop, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	8703A N LAMAR & ELLIOT AUSTIN TX

T72 Target Property **ALLSTAR BODY SHOP**
8703A N LAMAR BLVD
AUSTIN, TX 78753

TX Ind. Haz Waste **S121199858**
N/A

Site 2 of 7 in cluster T

Actual: 676 ft.

Focus Map: 6

Ind. Haz Waste:

Name:	ALLSTAR BODY SHOP
Address:	8703A N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	76797
Registration Initial Notification Date:	06/17/1992
Registration Last Amendment Date:	09/20/2017
EPA Identification:	TXD988059713
Primary NAICS Code:	811121
Status Change Date:	19920617

ALLSTAR BODY SHOP (Continued) **S121199858**

Land Type:	PRIVATE
Description of Facility Site Location:	8703A N LAMAR & ELLIOT AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	ALLSTAR BODY SHOP
Contact Name:	XAU VAN PHAN
Contact Telephone Number:	512-3398055
Mailing Address:	8703A N LAMAR BLVD
Mailing Address2:	& ELLIOT
Mailing City,State,Zip:	AUSTIN, TX 787535423
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31104
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20171013
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	ALLSTAR BODY SHOP
Operator Address:	8703A NLAMAR ELLIOT
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-3398055
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17426195693
Operator Bankruptcy Code:	Not reported

ALLSTAR BODY SHOP (Continued) **S121199858**

Ind. Haz Waste:

Owner Name:	ALLSTAR BODY SHOP
Owner Mailing Address:	8703A NLAMAR ELLIOT
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-3398055
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17426195693
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8703A NLAMAR ELLIOT
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3398055
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8703A NLAMAR ELLIOT

ALLSTAR BODY SHOP (Continued) **S121199858**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3398055
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	XAU PHAN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8703A NLAMAR BLVD
Contact Address 2:	& ELLIOT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3398055
Contact Fax:	Not reported
Contact Email:	Not reported

T73 Target Property **ALLSTAR BODY SHOP**
8703A N LAMAR BLVD
AUSTIN, TX 78753

RCRA NonGen / NLR **1004786059**
TXD988059713

Site 3 of 7 in cluster T

Actual: 676 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20170920
Handler Name:	Allstar Body Shop
Handler Address:	8703A N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753-5423
EPA ID:	TXD988059713
Contact Name:	XAU PHAN
Contact Address:	8703A N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753-5423
Contact Telephone:	512-339-8055
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	8703A N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753-5423
Owner Name:	Allstar Body Shop
Owner Type:	Private
Operator Name:	Allstar Body Shop
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

ALLSTAR BODY SHOP (Continued) **1004786059**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171017
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends

ALLSTAR BODY SHOP (Continued) **1004786059**

Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: XAU VAN PHAN	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	8703 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-339-8055
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ALLSTAR BODY SHOP	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8703A N LAMAR & ELLIOT
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-339-8055
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ALLSTAR BODY SHOP	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8703A N LAMAR & ELLIOT
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-339-8055
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ALLSTAR BODY SHOP	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8703A N LAMAR ELLIOT
Owner/Operator City,State,Zip:	AUSTIN, TX 78753-9999
Owner/Operator Telephone:	512-339-8055
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ALLSTAR BODY SHOP	
Legal Status:	Private

ALLSTAR BODY SHOP (Continued) **1004786059**

Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8703A N LAMAR ELLIOT
Owner/Operator City,State,Zip:	AUSTIN, TX 78753-9999
Owner/Operator Telephone:	512-339-8055
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920107
Handler Name: ALL STAR BODY SHOP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: ALLSTAR BODY SHOP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170920
Handler Name: ALLSTAR BODY SHOP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811121
NAICS Description:	AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:

Violations:	No Violations Found

ALLSTAR BODY SHOP (Continued) **1004786059**

Evaluation Action Summary:
Evaluations: No Evaluations Found

T74 Target Property **ALLSTAR BODY SHOP**
8703A N LAMAR BLVD
AUSTIN, TX 78753

FINDS **1016204705**
ECHO **N/A**

Site 4 of 7 in cluster T

Actual: 676 ft.

Focus Map: 6

FINDS:
Registry ID: 110005145477

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016204705
Registry ID:	110005145477
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005145477
Name:	ALLSTAR BODY SHOP
Address:	8703A N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

T75 Target Property **CULP SERV STA**
8703 LAMAR BLVD
AUSTIN, TX

EDR Hist Auto **1013753824**
N/A

Site 5 of 7 in cluster T

Actual: 676 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	CULP SERV STA	GASOLINE STATIONS
1958	CULP SERV STA	GASOLINE STATIONS
1962	MC DONALD SERV	GASOLINE STATIONS
1990	B I CAPE AUTO REPAIR	AUTOMOBILE REPAIRING

U76 Target Property | **DIP STICK**
8601 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S123844048**
N/A

Site 1 of 5 in cluster U

Actual: 692 ft.

Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN100532456
Name:	DIP STICK
Address:	8601 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5544
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600250054
Customer Name:	DIP STICK
Customer Legal Name:	Dipstick, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8601 N LAMAR

Regulated Entity Number:	RN100532456
Name:	DIP STICK
Address:	8601 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5544
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600250054
Customer Name:	DIP STICK
Customer Legal Name:	Dipstick, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8601 N LAMAR

U77 Target Property | **DIP STICK**
8601 LAMAR BLVD N
TRAVIS (County), TX 78753 | **EDR Hist Auto** | **1013775033**
N/A

Site 2 of 5 in cluster U

Actual: 692 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1982	ROCHAS LUBE SERVICE	Gasoline Service Stations
1983	ROCHAS LUBE SERVICE	Gasoline Service Stations
1985	ROCHAS LUBE SERVICE	Gasoline Service Stations
1986	ROCHAS LUBE SERVICE	Gasoline Service Stations
1986	DIP STICK	General Automotive Repair Shops
1987	DIP STICK	General Automotive Repair Shops
1987	ROCHAS LUBE SERVICE	Gasoline Service Stations
1988	ROCHAS LUBE SERVICE	Gasoline Service Stations

DIP STICK (Continued) **1013775033**

1988	DIP STICK	General Automotive Repair Shops
1989	ROCHAS LUBE SERVICE	Gasoline Service Stations
1990	DIP STICK	AUTOMOBILE REPAIRING
1990	ROCHAS LUBE SERVICE	Gasoline Service Stations
1991	DIP STICK	Gasoline Service Stations
1992	DIP STICK	Gasoline Service Stations
1993	DIP STICK	Gasoline Service Stations
1994	DIP STICK	Gasoline Service Stations
1995	DIP STICK	Gasoline Service Stations
1996	DIP STICK	Gasoline Service Stations
1997	DIP STICK	Gasoline Service Stations
1998	DIP STICK	Gasoline Service Stations
2006	DIP STICK	Gasoline Service Stations
2007	DIP STICK	Gasoline Service Stations
2008	DIP STICK	Gasoline Service Stations
2009	DIP STICK	Gasoline Service Stations
2010	DIP STICK	Gasoline Service Stations
2011	DIP STICK	Gasoline Service Stations
2012	DIP STICK	Gasoline Service Stations
2013	DIP STICK	Gasoline Service Stations
2014	DIP STICK	Gasoline Service Stations

V78 **FINELINE SPORTSWEAR** **TX Ind. Haz Waste** **S102755330**
Target **8451 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 1 of 5 in cluster V

Actual:
716 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	FINELINE SPORTSWEAR
Address:	8451 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	73876
Registration Initial Notification Date:	10/23/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19891023
Land Type:	Not reported
Description of Facility Site Location:	8451 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	FINELINE SPORTSWEAR INC
Contact Name:	DAN DAWE
Contact Telephone Number:	512-8321441
Mailing Address:	8451 N LAMAR BLVD

FINELINE SPORTSWEAR (Continued) **S102755330**

Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535922
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28285
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	FINELINE SPORTSWEAR INC
Operator Address:	8451 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8321441
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17423695109
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FINELINE SPORTSWEAR INC
Owner Mailing Address:	8451 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8321441
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17423695109
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8451 N LAMAR BLVD
Contact Address 2:	Not reported

FINELINE SPORTSWEAR (Continued) **S102755330**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8451 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DAN DAWE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8451 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

V79 **FINELINE SPORTSWEAR** **TX CENTRAL REGISTRY** **S126554889**
Target **8451 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 2 of 5 in cluster V

Actual:
716 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN101954915
Name:	FINELINE SPORTSWEAR
Address:	8451 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5922
Status:	ACTIVE
Status Date:	4/6/2002
Customer Number:	CN600360655
Customer Name:	FINELINE SPORTSWEAR INC
Customer Legal Name:	Fineline Sportswear, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8451 N Lamar, Austin, TX

V80 Target Property | **UNIVAR USA - PP&S AUSTIN (AS)**
8402 N. LAMAR, SUITE A-6
AUSTIN, TX 78753 | **TX TIER 2** | **S112001831**
N/A

Site 3 of 5 in cluster V

Actual: 720 ft.

Focus Map: 6

TIER 2:

Facility Id/Name:	FATR20128EAUGC01WFT8/UNIVAR USA - PP&S AUSTIN (AS)
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2-12-2013
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	T
Fire District:	Austin Fire Dept
Submitted By:	R. Christopher Potts
Latitude:	30.352755
Longitude:	-97.706465
Lat/Long Location Desc:	PG - Plant Entrance (General)
Lat/Long Method:	A3 - Address Matching (Street Centerline)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20118EAUGC01WFT8/UNIVAR USA - PP&S AUSTIN (AS)
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	2-23-2012
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	T
Fire District:	Austin Fire Dept
Submitted By:	R. Christopher Potts
Latitude:	30.352755
Longitude:	-97.706465
Lat/Long Location Desc:	PG - Plant Entrance (General)
Lat/Long Method:	A3 - Address Matching (Street Centerline)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	5169
Id Type:	SIC
Description:	CHEMICALS AND ALLIED PRODUCTS
Last Modified:	2/15/2012
Id:	42269
Id Type:	NAICS
Description:	Other Chemical and Allied Products Wholesalers
Last Modified:	2/15/2012
Id:	7943319
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/15/2012

Contact:

Contact Email:	chris.potts@univarusa.com
Contact Mail Address:	7425 East 30th Street
Contact City/State/Zip:	Indianapolis, IN 46219
Contact Mail Country:	USA
Contact Type 1:	Submitter
Contact Type 2:	Emergency Contact
Contact Name:	Chris Potts
Title:	Regional Operations Manager
Modification Date:	2/24/2013

Contact Email:	chris.potts@univarusa.com
Contact Mail Address:	7425 East 30th Street
Contact City/State/Zip:	Indianapolis, IN 46219
Contact Mail Country:	USA
Contact Type 1:	Submitter
Contact Type 2:	Emergency Contact
Contact Name:	Chris Potts
Title:	Regional Operations Manager
Modification Date:	2/24/2013

Contact:

Contact Email:	charles.everett@univarusa.com
Contact Mail Address:	8402 N. Lamar, Suite A-6
Contact City/State/Zip:	Austin, TX 48753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Charles Everett
Title:	Customer Service Rep.
Modification Date:	2/24/2013

Contact:

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Austin, TX
Contact Mail Country:	USA
Contact Type 1:	Fire Department
Contact Name:	Fire Deptartment
Title:	Not reported
Modification Date:	2/15/2012

Contact:

Contact Email:	douglas.windsor@univarusa.com
Contact Mail Address:	11076 Grader St
Contact City/State/Zip:	Dallas, TX 75238-2401
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Douglas Windsor
Title:	Branch Operations Mgr
Modification Date:	2/24/2013

Contact Email:	douglas.windsor@univarusa.com
Contact Mail Address:	11076 Grader St
Contact City/State/Zip:	Dallas, TX 75238-2401
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Douglas Windsor
Title:	Branch Operations Mgr
Modification Date:	2/24/2013

Chemical Inventory:

Facility Id:	FATR20128EAUGC01WFT8
Chemical Name:	AMERICAN BRAND PERMETHRIN GRANULES
Chemical Inv Record Id:	CVTR20128EAUR1024ZFB
CAS Number:	52645-53-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	25
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/24/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Chemical Inventory Location:

Record Key:	CLTR20128EAUX40257XT
Chemical Inventory Record Id:	CVTR20128EAUR1024ZFB
Amt Of Sub Stored Or Transported:	20000
Amount Units:	pounds
Type Of Storage:	Bag
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	DFT
Last Modified:	2/24/2013

Mixture:

Record Key:	CMTR20128EAUXR026SAC
Chemical Inv Record Id:	CVTR20128EAUR1024ZFB
Mix Chemical:	AMERICAN BRAND PERMETHRIN GRANULES
Percentage:	.25
Facility Id:	FATR20128EAUGC01WFT8
Mixture Cas:	52645-53-1
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	2/24/2013

Facility Id:	FATR20128EAUGC01WFT8
Chemical Name:	BIFENTHRIN L/P INSECTICIDE GRANULES
Chemical Inv Record Id:	CVTR20128EAUYL027HPV
CAS Number:	82657-04-3
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	25
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/24/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20128EAV1C028X11
Chemical Inventory Record Id:	CVTR20128EAUYL027HPV
Amt Of Sub Stored Or Transported:	30000
Amount Units:	pounds
Type Of Storage:	Bag
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Desc of Loc(Or Transported) Subs: W10
Last Modified: 2/24/2013

Mixture:
Record Key: CMTR20128EAV20029FCN
Chemical Inv Record Id: CVTR20128EAUYL027HPV
Mix Chemical: BIFENTHRIN
Percentage: .20
Facility Id: FATR20128EAUGC01WFT8
Mixture Cas: 82657-04-3
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 2/24/2013

Facility Id: FATR20128EAUGC01WFT8
Chemical Name: BROMADIOLONE
Chemical Inv Record Id: CVTR201293SXLK00AXSV
CAS Number: 028772-56-7
Chemical Same As Last Year: Not reported
Acute Health Risks: Not reported
Average Daily Amount: 100 - 999 pounds
Max Daily Amount: 100 - 999 pounds
Max Amount In Largest Container: 16
Chronic Health Risks: T
EHS Substance: T
Last Modified: 2/24/2013
Days On Site: 155
Fire Hazard: Not reported
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2012
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201293SXP700B6XJ
Chemical Inventory Record Id: CVTR201293SXLK00AXSV
Amt Of Sub Stored Or Transported: 750
Amount Units: pounds
Type Of Storage: Plastic or non-metallic drum
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: W10
Last Modified: 2/24/2013

Mixture:
Record Key: CMTR201293SXPN00CLGY
Chemical Inv Record Id: CVTR201293SXLK00AXSV
Mix Chemical: BROMADIOLONE
Percentage: 100

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Facility Id: FATR20128EAUGC01WFT8
Mixture Cas: 028772-56-7
Weight/Volume: Wt
Mixture Ehs: T
Mixture Last Modified: 2/24/2013

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 5169
Id Type: SIC
Description: CHEMICALS AND ALLIED PRODUCTS
Last Modified: 2/15/2012
Id: 42269
Id Type: NAICS
Description: Other Chemical and Allied Products Wholesalers
Last Modified: 2/15/2012
Id: 7943319
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 2/15/2012

Contact:
Contact Email: chris.potts@univarusa.com
Contact Mail Address: 7425 East 30th Street
Contact City/State/Zip: Indianapolis, IN 46219
Contact Mail Country: USA
Contact Type 1: Submitter
Contact Type 2: Emergency Contact
Contact Name: Chris Potts
Title: Regional Operations Manager
Modification Date: 2/24/2012

Contact Email: chris.potts@univarusa.com
Contact Mail Address: 7425 East 30th Street
Contact City/State/Zip: Indianapolis, IN 46219
Contact Mail Country: USA
Contact Type 1: Submitter
Contact Type 2: Emergency Contact
Contact Name: Chris Potts
Title: Regional Operations Manager
Modification Date: 2/24/2012

Contact:
Contact Email: chris.shores@univarusa.com
Contact Mail Address: 9430 Research Blvd #4 suite 350
Contact City/State/Zip: Austin, TX 78759
Contact Mail Country: USA
Contact Type 1: Other
Contact Name: Chris Shores
Title: Director of Operations
Modification Date: 2/8/2012

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Contact Email:	chris.shores@univarusa.com
Contact Mail Address:	9430 Research Blvd #4 suite 350
Contact City/State/Zip:	Austin, TX 78759
Contact Mail Country:	USA
Contact Type 1:	Other
Contact Name:	Chris Shores
Title:	Director of Operations
Modification Date:	2/8/2012

Contact:

Contact Email:	rusty.thompson@univarusa.com
Contact Mail Address:	191 Jacintoport Blvd
Contact City/State/Zip:	Houston, TX 77015
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Rusty Thompson
Title:	Branch Operations Manager
Modification Date:	2/24/2012

Contact Email:	rusty.thompson@univarusa.com
Contact Mail Address:	191 Jacintoport Blvd
Contact City/State/Zip:	Houston, TX 77015
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Rusty Thompson
Title:	Branch Operations Manager
Modification Date:	2/24/2012

Contact:

Contact Email:	charles.everett@univarusa.com
Contact Mail Address:	8402 N. Lamar, Suite A-6
Contact City/State/Zip:	Austin, TX 48753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Charles Everett
Title:	Customer Service Rep.
Modification Date:	2/24/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Austin, TX
Contact Mail Country:	USA
Contact Type 1:	Fire Department
Contact Name:	Fire Deptartment
Title:	Not reported
Modification Date:	2/15/2012

Chemical Inventory:

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Facility Id:	FATR20118EAUGC01WFT8
Chemical Name:	AMERICAN BRAND PERMETHRIN GRANULES
Chemical Inv Record Id:	CVTR20118EAUR1024ZFB
CAS Number:	52645-53-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	25
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/24/2012
Days On Site:	364
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAUX40257XT
Chemical Inventory Record Id:	CVTR20118EAUR1024ZFB
Amt Of Sub Stored Or Transported:	20000
Amount Units:	pounds
Type Of Storage:	Bag
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	DFT
Last Modified:	2/24/2012

Mixture:

Record Key:	CMTR20118EAUXR026SAC
Chemical Inv Record Id:	CVTR20118EAUR1024ZFB
Mix Chemical:	AMERICAN BRAND PERMETHRIN GRANULES
Percentage:	.25
Facility Id:	FATR20118EAUGC01WFT8
Mixture Cas:	52645-53-1
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	2/24/2012

Facility Id:	FATR20118EAUGC01WFT8
Chemical Name:	BIFENTHRIN L/P INSECTICIDE GRANULES
Chemical Inv Record Id:	CVTR20118EAUYL027HPV
CAS Number:	82657-04-3
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Max Amount In Largest Container:	25
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/24/2012
Days On Site:	364
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAV1C028X11
Chemical Inventory Record Id:	CVTR20118EAUYL027HPV
Amt Of Sub Stored Or Transported:	30000
Amount Units:	pounds
Type Of Storage:	Bag
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	W10
Last Modified:	2/24/2012

Mixture:

Record Key:	CMTR20118EAV20029FCN
Chemical Inv Record Id:	CVTR20118EAUYL027HPV
Mix Chemical:	BIFENTHRIN
Percentage:	.20
Facility Id:	FATR20118EAUGC01WFT8
Mixture Cas:	82657-04-3
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	2/24/2012

Facility Id:	FATR20118EAUGC01WFT8
Chemical Name:	TOPCHOICE INSECTICIDE - RUP
Chemical Inv Record Id:	CVTR20118EAV2Z02AAJU
CAS Number:	120068-37-3
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	50
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/24/2012
Days On Site:	358
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported

UNIVAR USA - PP&S AUSTIN (AS) (Continued) **S112001831**

Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported
Reactive Hazard: Not reported
Solid: T
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2011
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20118EAV7502BWZ2
Chemical Inventory Record Id: CVTR20118EAV2Z02AAJU
Amt Of Sub Stored Or Transported: 20000
Amount Units: pounds
Type Of Storage: Bag
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: DFT
Last Modified: 2/24/2012

Mixture:
Record Key: CMTR20118EAV8702CUKH
Chemical Inv Record Id: CVTR20118EAV2Z02AAJU
Mix Chemical: TRADE SEC - NOT REGULATED
Percentage: 99.9
Facility Id: FATR20118EAUGC01WFT8
Mixture Cas: Not reported
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 2/24/2012

Record Key: CMTR20118EAVCK02DLMU
Chemical Inv Record Id: CVTR20118EAV2Z02AAJU
Mix Chemical: FIPRONIL
Percentage: .01
Facility Id: FATR20118EAUGC01WFT8
Mixture Cas: 120068-37-3
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 2/24/2012

Notes: Not reported
Validation: Not reported

V81 Target Property | **UNIVAR USA ES -AUSTIN**
8402 N LAMAR
AUSTIN, TX 78753 | **FINDS** | **1024211206**
N/A

Site 4 of 5 in cluster V

Actual: 720 ft.
Focus Map: 6

FINDS:
Registry ID: 110070198917

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

W82 Target Property | **THIRD COAST AUTO GROUP**
8316 N LAMAR BLVD
AUSTIN, TX 78753 | **TX CENTRAL REGISTRY** | **S126892393**
N/A

Site 1 of 4 in cluster W

Actual: 728 ft.
Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN108827593
Name:	THIRD COAST AUTO GROUP
Address:	8316 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5921
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604966275
Customer Name:	THIRD COAST AUTO GROUP INC
Customer Legal Name:	Third Coast Auto Group Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

W83 Target Property | **RYDER TRUCK, IH-35 MI.MARKER 220 NO. BOUND, NEAR B**
RYDER TRUCK, IH-35 MI.MARKER 220 NO. BOUND, NEAR BUDA
, TX | **TX SPILLS** | **S107002571**
N/A

Site 2 of 4 in cluster W

Actual: 728 ft.
Focus Map: 6

SPILLS:

Name:	RYDER TRUCK, IH-35 MI.MARKER 220 NO. BOUND, NEAR BUDA
Address:	RYDER TRUCK, IH-35 MI.MARKER 220 NO. BOUND, NEAR BUDA
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported

RYDER TRUCK, IH-35 MI.MARKER 220 NO. BOUND, NEAR BUDA (Continued) **S107002571**

Date of Spill:	08/07/1992
Seq Num:	Not reported
Responsible Party Name:	RYDER TRUCK
Responsible Party Address:	8305 N. LAMAR BLVD.
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	Not reported
Responsible Party Telephone:	5128367286
Substance:	DIESEL FUEL
Material Code:	1040
Media Affected:	Not reported
Permit Number:	0
District:	08
Origin:	005
Cause:	002
Basin Code:	0
Notify Date:	Not reported
Adequate Clean:	003
Classification:	003
Basin Name:	Not reported
Water Affected:	UNK
Amnt Spilled:	100 GAL
Amnt in Water:	0 GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	M. STINE
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

X84 Target Property | **RELIABLE AUTOM**
8226 LAMAR BLVD N
AUSTIN, TX 78763 | **EDR Hist Auto** | **1013773584**
N/A

Site 1 of 5 in cluster X

Actual: 734 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1984	RELIABLE AUTOM	AUTOMOBILE REPAIRING

X85 Target Property | **SCHEIDERS SIN**
8224 LAMAR BLVD N
AUSTIN, TX | **EDR Hist Auto** | **1013769626**
N/A

Site 2 of 5 in cluster X

Actual: 734 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	HOLLANDS TRUCK	GASOLINE STATIONS
1962	SCHEIDERS SIN	GASOLINE STATIONS

Y86 Target Property | **AUSTIN BRAKE & CLUTCH SUPPLY**
8151 N LAMAR BLVD
AUSTIN, TX 78753 | **RCRA NonGen / NLR**
FINDS
ECHO
TX Ind. Haz Waste
TX CENTRAL REGISTRY | **1000412165**
TXD026009696

Site 1 of 3 in cluster Y

Actual: 742 ft.
Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20011108
Handler Name:	Austin Brake & Clutch Supply
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD026009696
Contact Name:	GILBERT DEMENT
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-836-0482
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Austin Brake & Clutch Supply
Owner Type:	Not reported
Operator Name:	Austin Brake & Clutch Supply
Operator Type:	Not reported
Short-Term Generator Activity:	No

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN BRAKE & CLUTCH SUPPLY
Legal Status: Not reported
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: 8151 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-836-0482
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN BRAKE & CLUTCH SUP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN BRAKE & CLUTCH SUPPLY
Legal Status: Not reported
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: 8151 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-836-0482
Owner/Operator Telephone Ext: Not reported

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19861120
Handler Name: AUSTIN BRAKE & CLUTCH SUPPLY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011108
Handler Name: AUSTIN BRAKE & CLUTCH SUPPLY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005041392

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412165
Registry ID:	110005041392
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005041392
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

Ind. Haz Waste:

Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	69307
Registration Initial Notification Date:	03/07/1986
Registration Last Amendment Date:	11/08/2001
EPA Identification:	TXD026009696
Primary NAICS Code:	811111
Status Change Date:	19860307
Land Type:	Not reported
Description of Facility Site Location:	8151 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	ABCS CLOSING ENTITY INC
Contact Name:	GILBERT DEMENT
Contact Telephone Number:	512-8360482
Mailing Address:	8151 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787536232
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24186
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	ABCS CLOSING ENTITY INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17419015007
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	ABCS CLOSING ENTITY INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17419015007
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	GILBERT DEMENT
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8151 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8360482
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	139168
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013456
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139169
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	IMMERSION CLEANER
Standard Industrial Code:	Not reported

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013456
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139170
Texas Waste Code:	Not reported
Texas Waste Code 2:	14763101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	USED FILTERS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013456
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8151 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000306972
Principal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Attention Name:	Not reported

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8151 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000306972
Principal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Attention Name:	Not reported
Attention Suffix:	HWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521561
Customer Name:	ABCS CLOSING ENTITY INC
Customer Legal Name:	Abcs Closing Entity, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521561
Customer Name:	ABCS CLOSING ENTITY INC
Customer Legal Name:	Abcs Closing Entity, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Status Date:	##########
Customer Number:	CN600521561
Customer Name:	ABCS CLOSING ENTITY INC
Customer Legal Name:	Abcs Closing Entity, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603913948
Customer Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Legal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/8/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603913948
Customer Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Legal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/8/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603913948
Customer Name:	AUSTIN BRAKE & CLUTCH SUPPLY

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **1000412165**

Customer Legal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/8/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521561
Customer Name:	ABCS CLOSING ENTITY INC
Customer Legal Name:	Abcs Closing Entity, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100843457
Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-6232
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603913948
Customer Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Legal Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/8/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8151 N Lamar Blvd, Austin, TX

Y87 **AUSTIN BRAKE & CLUTCH SUPPLY** **TX UST** **U001240681**
Target **8151 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 2 of 3 in cluster Y

Actual:
742 ft.

Focus Map:
6

UST:

Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Address:	8151 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787536232
AI Number:	3877
Facility Type:	UNKNOWN
Facility Begin Date:	06/18/1986

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **U001240681**

Facility Status:	INACTIVE
Additional ID:	691280042003072
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	L GILBERT DEMENT,PRESIDENT
Contact Organization Name:	AUSTIN BRAKE & CLUTCH SUPPLY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128360482
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/21/1986
Signature Name/Title On Earliest Reg Form:	L G DEMENT,PRESIDENT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600521561
Owner Last Name:	ABCS CLOSING ENTITY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	71283472001338
Additional ID:	691280042003072
AI Number:	3877
Owner Effective Begin Date:	06/18/1986
State Tax ID:	17419015007
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **U001240681**

Number of Compartments:	1
Tank Capacity:	2500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	9470
Facility ID:	42505
Ai Number:	3877
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/04/1998
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **U001240681**

Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	2500
UST Comprt ID:	13147
UST ID:	9470
AI Number:	3877
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUSTIN BRAKE & CLUTCH SUPPLY INC
Contact Mailing Address (Delivery):	8151 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 6232
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y

AUSTIN BRAKE & CLUTCH SUPPLY (Continued) **U001240681**

Facility ID:	42505
Additional ID:	691280042003072
Princ ID:	71283472001338
AI Number:	3877
Facility Name:	AUSTIN BRAKE & CLUTCH SUPPLY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	L GILBERT DEMENT/

Z88 **ACME DRY CLEANERS & LAUNDRY NO** **EDR Hist Cleaner** **1013785234**
Target **7541 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78752**

Site 1 of 9 in cluster Z

Actual:
751 ft.

EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1970	ACME DRY CLEANERS & LAUNDRY NO	CLEANERS AND DYERS

Z89 **D & L MOTORCYCLES** **TX ENF** **S118665610**
Target **7535 N LAMAR BLVD** **TX COMP HIST** **N/A**
Property **AUSTIN, TX 78752**

Site 2 of 9 in cluster Z

Actual:
751 ft.

Focus Map:
6

ENFORCEMENT:

Name:	D & L MOTORCYCLES
Address:	7535 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-1345
Unique TCEQ Ref Number Of Customer:	CN605109297
Unique TCEQ Ref Number Of Reg. Entity:	RN108815648
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	FOWOWE, GBENGA A
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001313130
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	359,599,782,016,088.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/31/2016
Description 1:	Failure to register as a scrap tire facility prior to processing scrap tires.
Description 2:	On June 27, 2016, Mr. Fowowe submitted a letter to the TCEQ Austin Regional Office which stated that Access USA Automotive had contracted a third-party company that specializes in the disposal of scrap tires, however Mr. Fowowe did not include the name of the company. On August 1, 2016, Mr. Grunnet contacted the Mr. Fowowe to get more information. Mr. Fowowe stated that he had contracted Liberty Tire Recycling to

D & L MOTORCYCLES (Continued) **S118665610**

	pick up scrap tires, however he had not generated any loads yet because he had been out of the country. Mr. Grunnet determined that this information was adequate to resolve the violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.63(c)
Status Of The NOV:	DAPPROVED
Investigation:	1313130
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

COMP HIST:

RN Number:	RN108815648
Name:	D & L MOTORCYCLES
Address:	7535 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-1345
Region:	REGION 11 - AUSTIN
CN Number:	CN604954339
CN Name:	D & L MOTORCYCLES
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	332618
SIC Code:	1521
Related Number:	5681,R11108815648,R11108815648

RN Number:	RN108815648
Name:	D & L MOTORCYCLES
Address:	7535 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-1345
Region:	REGION 11 - AUSTIN
CN Number:	CN605109297
CN Name:	FOWOWE, GBENGA A
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022

D & L MOTORCYCLES (Continued) **S118665610**

NAICS Code: 236115
SIC Code: 1521
Related Number: 5681,R11108815648,R11108815648

Z90 Target Property **D & L MOTORCYCLES**
7535 N LAMAR BLVD
AUSTIN, TX 78752

TX CENTRAL REGISTRY **S126891217**
N/A

Site 3 of 9 in cluster Z

Actual: 751 ft.

Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN108815648
Name:	D & L MOTORCYCLES
Address:	7535 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-1345
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN605109297
Customer Name:	FOWOWE, GBENGA A
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	3/11/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108815648
Name:	D & L MOTORCYCLES
Address:	7535 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-1345
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604954339
Customer Name:	D & L MOTORCYCLES
Customer Legal Name:	D & L Motorcycles
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Z91 Target Property | **D & L MOTORCYCLE INC SIS & SERV**
7535 LAMAR BLVD N
TRAVIS (County), TX 78752 | **EDR Hist Auto** | **1013753887**
N/A

Site 4 of 9 in cluster Z

Actual: 751 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1975	D & L MOTORCYCLE INC SIS & SERV	MOTORCYCLE DEALERS AND REPAIRERS
1980	D & L MOTORCYCLE INC SIS & SERV	MOTORCYCLE DEALERS AND REPAIRERS
1984	D & L MOTORCYCLES INC SLS & SER	MOTORCYCLE DEALERS AND REPAIRERS
1990	D & L MOTORCYCLES INC SAS & SER	MOTORCYCLE DEALERS AND REPAIRERS

AA92 Target Property | **NORTH LAMAR AUTO BODY**
7313 NORTH LAMAR BLVD
AUSTIN, TX | **TX ENF**
TX COMP HIST | **S107634179**
N/A

Site 1 of 6 in cluster AA

Actual: 736 ft.

Focus Map: 6

ENFORCEMENT:

Name:	NORTH LAMAR AUTO BODY
Address:	7313 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN100723436
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	AUTO BODY SHOP
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	10/04/2001
Description 1:	OPERATING W/O PI-7
Description 2:	Not reported
Category of the NOV:	Minor
Method Of Notice Issuance:	VERBAL
TCEQ Prog Area Monitoring Violation:	AIR
TCEQ Rule Number Cited For The Violation:	116.110(a)(4)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

NORTH LAMAR AUTO BODY (Continued) **S107634179**

COMP HIST:

RN Number:	RN100723436
Name:	NORTH LAMAR AUTO BODY
Address:	7313 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600411144
CN Name:	NORTH LAMAR AUTO BODY SHOP INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811121
SIC Code:	1521
Related Number:	49398,49398

AA93 **A & A USED TIRES** **TX ENF** **S118665415**
Target **7313 N LAMAR BLVD** **TX COMP HIST** **N/A**
Property **AUSTIN, TX 78752**

Site 2 of 6 in cluster AA

Actual: 736 ft.

Focus Map: 6

ENFORCEMENT:

Name:	A & A USED TIRES
Address:	7313 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2341
Unique TCEQ Ref Number Of Customer:	CN605069533
Unique TCEQ Ref Number Of Reg. Entity:	RN105004477
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	A & A USED TIRES LLC
Regulated Entity Associated With An NOV:	AUTO REPAIR
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001307060
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	798,545,222,016,053.00
Role Code:	Not reported
Date Notice Of Violation Issued:	02/23/2016
Description 1:	Failure to maintain manifests for the removal of scrap tires from the property.
Description 2:	Mr. Arreguin was able to demonstrate that he has been maintaining records to document scrap tire removal from the facility. No further action is required at this time.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.56(c)
Status Of The NOV:	DAPPROVED
Investigation:	1307060

A & A USED TIRES (Continued) **S118665415**

Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	A & A USED TIRES
Address:	7313 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2341
Unique TCEQ Ref Number Of Customer:	CN605069533
Unique TCEQ Ref Number Of Reg. Entity:	RN105004477
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	A & A USED TIRES LLC
Regulated Entity Associated With An NOV:	AUTO REPAIR
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001307060
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	798,545,222,016,053.00
Role Code:	Not reported
Date Notice Of Violation Issued:	02/23/2016
Description 1:	Failure to ensure tires are transported to an authorized facility.
Description 2:	Mr. Arreguin was able to demonstrate that scrap tires are transported to an authorized facility. No further action is required at this time.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.56(b)
Status Of The NOV:	DAPPROVED
Investigation:	1307060
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	A & A USED TIRES
Address:	7313 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2341

A & A USED TIRES (Continued) **S118665415**

Unique TCEQ Ref Number Of Customer:	CN605069533
Unique TCEQ Ref Number Of Reg. Entity:	RN105004477
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	A & A USED TIRES LLC
Regulated Entity Associated With An NOV:	AUTO REPAIR
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001393768
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	429,646,682,017,046.00
Role Code:	Not reported
Date Notice Of Violation Issued:	02/16/2017
Description 1:	Failure to register as a scrap tire facility prior to processing (cutting) scrap tires.
Description 2:	Based on the documentation reviewed and the information received on August 30, 2017, the violation has been resolved. No further action is required at this time.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.63(c)
Status Of The NOV:	DAPPROVED
Investigation:	1393768
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

COMP HIST:

RN Number:	RN105004477
Name:	A & A USED TIRES
Address:	7313 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2341
Region:	REGION 11 - AUSTIN
CN Number:	CN605069533
CN Name:	A & A USED TIRES LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210

A & A USED TIRES (Continued) **S118665415**

SIC Code: 5541
Related Number: R111050044771,R111050044771

AA94 **NORTH LAMAR AUTO BODY** **TX CENTRAL REGISTRY** **S123848529**
Target **7313 NORTH LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 6 in cluster AA

Actual:
736 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN100723436
Name:	NORTH LAMAR AUTO BODY
Address:	7313 NORTH LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600411144
Customer Name:	NORTH LAMAR AUTO BODY SHOP INC
Customer Legal Name:	North Lamar Auto Body Shop, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/3/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	7313 NORTH LAMAR BLVD

Regulated Entity Number:	RN100723436
Name:	NORTH LAMAR AUTO BODY
Address:	7313 NORTH LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600411144
Customer Name:	NORTH LAMAR AUTO BODY SHOP INC
Customer Legal Name:	North Lamar Auto Body Shop, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/3/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	7313 NORTH LAMAR BLVD

AA95 **K W AUTO REPAIR** **EDR Hist Auto** **1013755949**
Target **7313 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX**

Site 4 of 6 in cluster AA

Actual:
736 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1965	K W AUTO REPAIR	AUTOMOBILE REPAIRING

K W AUTO REPAIR (Continued) **1013755949**

1979	AUTO-TRONICS	Automotive Repair Shops, NEC
1980	AUTO-TRONICS	Automotive Repair Shops, NEC
1982	AUTO-TRONICS	Automotive Repair Shops, NEC
1983	AUTO-TRONICS	Automotive Repair Shops, NEC
1985	AUTO-TRONICS	Automotive Repair Shops, NEC
1988	BEST AUTO SERVICE & BODY WORK	General Automotive Repair Shops
1989	BEST AUTO SERVICE & BODY WORK	General Automotive Repair Shops
1990	A CUSTOM AUTO TREATMENTS	AUTOMOBILE REPAIRING
1994	EXCALIBUR AUTOMOTIVE REPAIR	General Automotive Repair Shops
1995	EXCALIBUR AUTOMOTIVE REPAIR	General Automotive Repair Shops
1996	ABA AUTO SERVICE INC	General Automotive Repair Shops
1996	EXCALIBUR AUTOMOTIVE REPAIR	General Automotive Repair Shops
1997	ABA AUTO SERVICE INC	General Automotive Repair Shops
1998	ABA AUTO SERVICE INC	General Automotive Repair Shops
1999	ABA AUTO SERVICE INC	General Automotive Repair Shops
2000	ABA AUTO SERVICE INC	General Automotive Repair Shops
2000	ADA HIGH TECH INC	General Automotive Repair Shops
2001	ADA HIGH TECH INC	General Automotive Repair Shops
2001	ABA AUTO SERVICE INC	General Automotive Repair Shops
2002	ABA AUTO SERVICE INC	General Automotive Repair Shops
2002	ADA HIGH TECH INC	General Automotive Repair Shops
2003	ADA HIGH TECH INC	General Automotive Repair Shops
2003	ABA AUTO SERVICE INC	General Automotive Repair Shops
2004	ABA AUTO SERVICE INC	General Automotive Repair Shops
2004	DISCOUNT AUTO CARE	General Automotive Repair Shops
2004	ADA HIGH TECH INC	General Automotive Repair Shops
2005	ADA HIGH TECH INC	General Automotive Repair Shops
2005	ABA HIGH TECK INC	General Automotive Repair Shops
2005	DISCOUNT AUTO CARE	General Automotive Repair Shops
2006	DISCOUNT AUTO CARE	General Automotive Repair Shops
2006	ADA HIGH TECH INC	General Automotive Repair Shops
2006	ABA HIGH TECK INC	General Automotive Repair Shops
2007	ADA HIGH TECH INC	General Automotive Repair Shops
2007	DISCOUNT AUTO CARE	General Automotive Repair Shops
2007	ABA HIGH TECK INC	General Automotive Repair Shops
2008	ABA HIGH TECK INC	General Automotive Repair Shops
2008	DISCOUNT AUTO CARE	General Automotive Repair Shops
2008	ADA HIGH TECH INC	General Automotive Repair Shops
2009	ABA HIGH TECK INC	General Automotive Repair Shops
2009	DISCOUNT AUTO CARE	General Automotive Repair Shops
2010	ABA HIGH TECK INC	General Automotive Repair Shops
2011	ABA HIGH TECK INC	General Automotive Repair Shops
2012	ABA HIGH TECK INC	General Automotive Repair Shops
2013	ABA HIGH TECK INC	General Automotive Repair Shops
2014	ABA HIGH TECK INC	General Automotive Repair Shops

AA96 **JC TIRE & WHEELS** **TX CENTRAL REGISTRY** **S126937159**
Target **7313 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 5 of 6 in cluster AA

Actual:
736 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN110367992
Name:	JC TIRE & WHEELS
Address:	7313 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2341

JC TIRE & WHEELS (Continued) **S126937159**

Status:	ACTIVE
Status Date:	4/13/2018
Customer Number:	CN605493444
Customer Name:	OHIAGU, JOE
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AA97 **NORTHSIDE GARAGE AUTO** **EDR Hist Auto** **1013755044**
Target **7277 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX**

Site 6 of 6 in cluster AA

Actual:
733 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1965	NORTHSIDE GARAGE AUTO	AUTOMOBILE REPAIRING

AB98 **A 1 TRANSMISSION** **EDR Hist Auto** **1013755934**
Target **7227 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX**

Site 1 of 11 in cluster AB

Actual:
730 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1962	A 1 TRANSMISSION	AUTOMOBILE REPAIRING
1970	NORTHSIDE GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	NORTHSIDE GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1980	CARTER BROTHERS AUTOMATIC TRANS	AUTOMOBILE REPAIRING
1984	CARTER BROTHERS AUTOMATIC TRAMI	AUTOMOBILE REPAIRING
1986	CARTER BROS TRANSM & AT SVS	Automotive Repair Shops, NEC
1987	CARTER BROS TRANSM & AUTO SVCS	Automotive Repair Shops, NEC
1988	CARTER BROS TRANSM & AUTO SVCS	Automotive Repair Shops, NEC
1989	CARTERS TRANSMISSION & RADS	Automotive Repair Shops, NEC, NEC
1990	CARTER BROTHERS AUTOMATIC TRANS	AUTOMOBILE REPAIRING
1990	CARTERS TRANSMISSION & RADS	Automotive Repair Shops, NEC, NEC
1991	CARTERS TRANSMISSION & RADS	Automotive Repair Shops, NEC, NEC
1992	CARTERS TRANSMISSION & RADS	Automotive Transmission Repair Shops
1993	CARTERS TRANSMISSION & RADS	Automotive Transmission Repair Shops
1994	CARTERS TRANSMISSION & RADS	Automotive Transmission Repair Shops
1995	CARTERS TRANSMISSION & RADS	Automotive Transmission Repair Shops
1996	CARTERS TRANSMISSION & RADS	Automotive Transmission Repair Shops
1997	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
1998	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
1999	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2000	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2001	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2002	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops

A 1 TRANSMISSION (Continued) **1013755934**

2003	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2004	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2010	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2011	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2012	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2013	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops
2014	ADVANCED AUTO TECH INC	Automotive Transmission Repair Shops

---

AB99 **PATS LAWN MOWER SVC** **TX ENF** **S102748188**
Target **7201 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
Property **AUSTIN, TX 78752** **TX CENTRAL REGISTRY**

Site 2 of 11 in cluster AB

Actual:
728 ft.

Focus Map:
6

ENFORCEMENT:

Name:	PATS LAWN MOWER SVC
Address:	7201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2311
Unique TCEQ Ref Number Of Customer:	CN605076389
Unique TCEQ Ref Number Of Reg. Entity:	RN100693332
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	OLMEDA, JUAN
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	7201 N Lamar, Austin, TX
Near City:	Not reported
Investigation Number:	000000001265915
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	107,354,382,016,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/17/2016
Description 1:	Failure to obtain scrap tire manifests from the transporter collecting tires from the generator's place of business and maintain a record of each individual load of used or scrap tires or tire pieces hauled off from their business location.
Description 2:	On May 10, 2016, Mr. Mark Olmeda submitted a scrap tire manifest. The document was the generator copy of a carbon copy tire manifest. The generator and transporter portions were filled out and signed by Mr. Juan Olmeda showing that 68 scrap tires had been transported to Reliable Tire Disposal, a registered tire processor. It was noted that Mr. Olmeda now appeared to be using scrap tire manifests as required. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.58(a)
Status Of The NOV:	DAPPROVED
Investigation:	1265915
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported

PATS LAWN MOWER SVC (Continued) **S102748188**

Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	PATS LAWN MOWER SVC
Address:	7201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752-2311
Unique TCEQ Ref Number Of Customer:	CN605076389
Unique TCEQ Ref Number Of Reg. Entity:	RN100693332
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	OLMEDA, JUAN
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	7201 N Lamar, Austin, TX
Near City:	Not reported
Investigation Number:	000000001265915
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	107,354,382,016,074.00
Role Code:	Not reported
Date Notice Of Violation Issued:	03/17/2016
Description 1:	Failure to register as a scrap tire facility prior to processing scrap tires.
Description 2:	On May 10, 2016, Mr. Mark Olmeda submitted a scrap tire manifest. The document was the generator copy of a carbon copy tire manifest. The generator and transporter portions were filled out and signed by Mr. Juan Olmeda showing that 68 scrap tires had been transported to Reliable Tire Disposal, a registered tire processor. It was noted that Mr. Olmeda had ceased processing his own scrap tires without authorization. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.63(c)
Status Of The NOV:	DAPPROVED
Investigation:	1265915
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Ind. Haz Waste:

Name:	PATS LAWN MOWER SVC
Address:	7201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752

PATS LAWN MOWER SVC (Continued) **S102748188**

Permit Number:	Not reported
Registration Number:	61261
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	7201 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	PATS LAWN MOWER SVC
Contact Name:	SANDRA CHISM
Contact Telephone Number:	Not reported
Mailing Address:	7201 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787522311
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19619
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	PATS LAWN MOWER SVC
Operator Address:	7201 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported

PATS LAWN MOWER SVC (Continued) **S102748188**

Operator Email: Not reported
Operator Business Type: Other/Misc
Operator Tax ID: Not reported
Operator Bankruptcy Code: Not reported

Ind. Haz Waste:
Owner Name: PATS LAWN MOWER SVC
Owner Mailing Address: 7201 N LAMAR BLVD
Owner Mailing Address 2: Not reported
Owner Mailing Address 3: Not reported
Owner Mailing City,State,Zip: AUSTIN, TX 78752
Owner Country: UNITED STA
Owner Telephone: Not reported
Owner Fax: Not reported
Owner Email Address: Not reported
Owner Business Type: Other/Misc
Owner Tax ID: Not reported
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OPRCON
Contact Address: 7201 N LAMAR BLVD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78752
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 7201 N LAMAR BLVD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78752
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: SANDRA CHISM
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 7201 N LAMAR BLVD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78752
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

CENTRAL REGISTRY:
Regulated Entity Number: RN100693332

PATS LAWN MOWER SVC (Continued) **S102748188**

Name:	PATS LAWN MOWER SVC
Address:	7201 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2311
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600399687
Customer Name:	PATS LAWN MOWER SVC
Customer Legal Name:	Pats Lawn Mower SVC
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	7201 N Lamar, Austin, TX

AB100 **PATS LAWN MOWER SVC** **TX COMP HIST** **S118665950**
Target **7201 N LAMAR BLVD** **N/A**
Property **TRAVIS (County), TX 78752**

Site 3 of 11 in cluster AB

Actual:
728 ft.

Focus Map:
6

COMP HIST:

RN Number:	RN100693332
Name:	PATS LAWN MOWER SVC
Address:	7201 N LAMAR BLVD
City,State,Zip:	TX 78752-2311
Region:	REGION 11 - AUSTIN
CN Number:	CN600399687
CN Name:	PATS LAWN MOWER SVC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	238220
SIC Code:	1521
Related Number:	R11100693332,R11100693332

AB101 **7121 N LAMAR BLVD** **TX CENTRAL REGISTRY** **S126836838**
Target **7121 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 4 of 11 in cluster AB

Actual:
728 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN106360175
Name:	7121 N LAMAR BLVD
Address:	7121 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2309
Status:	ACTIVE

7121 N LAMAR BLVD (Continued) **S126836838**

Status Date:	1/1/2001
Customer Number:	CN604052100
Customer Name:	SL NORTH LAMAR LP
Customer Legal Name:	Sl North Lamar, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2/15/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	442110
Primary NAICS Industry Type Description:	Furniture Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN106360175
Name:	7121 N LAMAR BLVD
Address:	7121 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2309
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604052100
Customer Name:	SL NORTH LAMAR LP
Customer Legal Name:	Sl North Lamar, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2/15/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	442110
Primary NAICS Industry Type Description:	Furniture Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN106360175
Name:	7121 N LAMAR BLVD
Address:	7121 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2309
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604052100
Customer Name:	SL NORTH LAMAR LP
Customer Legal Name:	Sl North Lamar, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2/15/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	442110
Primary NAICS Industry Type Description:	Furniture Stores
Physical Location Description:	Not reported

AB102 Target Property | **AUTOMETRICS INC AUTOMOBILE REPR**
7121 LAMAR BLVD N
TRAVIS (County), TX 78752 | **EDR Hist Auto** | **1013753158**
N/A

Site 5 of 11 in cluster AB

Actual: 728 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1969	BEE AUTOMATIC TRANSMISSIONS	Automotive Repair Shops, NEC
1970	BEE AUTOMATIC TRANSMISSIONS	Automotive Repair Shops, NEC
1975	AUTOMETRICS INC AUTOMOBILE REPR	AUTOMOBILE REPAIRING

AB103 Target Property | **7121 N LAMAR BLVD**
7121 N LAMAR BLVD
AUSTIN, TX 78752 | **TX VCP**
TX HIST UST
TX GCC | **S111678585**
N/A

Site 6 of 11 in cluster AB

Actual: 728 ft.
Focus Map: 6

VCP TCEQ:

Name:	7121 N LAMAR BLVD
Address:	7121 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	REGION 11 - AUSTIN
Facility ID:	2481
VCP Record Date:	Not reported
Facility Type:	RETAIL
PCA Number:	34674
Project Manager:	JMANNING
Phase:	COMPLETED
Acres at Site:	0.90
REM Program:	VCP
RN Number:	RN106360175
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	Not reported
Administrative Status:	INACTIVE
Region Notified of Application:	02/15/2012
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	06/19/2013
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	02/15/2012
GW Target COC Class:	CHLORINATED SOLVENTS; VOCS; METALS; SVOCS; TPH
Sediment Target COC Class:	Not reported

7121 N LAMAR BLVD (Continued) **S111678585**

Application Accepted?: Not reported
Application Accepted Date: 2012-03-26 00:00:00
Soil Target COC Class: CHLORINATED SOLVENTS; VOCS; METALS; SVOCS; TPH
Surface Water Target COC Class: Not reported
Alternate VCP ID: 2481
Leaking Petroleum Storage Registration Tank: Not reported
Project Number: 346740
Off Site?: Not reported
Media: PAPER
IOP Number: Not reported
File Location: D/200-25
Latitude: 0.00
Longitude: 0.00

HIST UST AUSTIN:
Name: C.B. SMITH
Address: 7121 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: H0420
HID UST: 420
Inspection: Not reported
Due: 06/01/2012

GCC:
Name: 7121 N LAMAR BLVD
Address: 7121 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: *
File Number: 2481
Contamination Description: HEAVY METALS
Date Of Earliest Known Contamination Confirmation: 3/26/2012
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 7121 N LAMAR BLVD
Address: 7121 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 2481
Contamination Description: METALS
Date Of Earliest Known Contamination Confirmation: 3/26/2012
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E

7121 N LAMAR BLVD (Continued) **S111678585**

Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

AB104 **OUTPLAN** **TX ASBESTOS** **S121362006**
Target **7121 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 7 of 11 in cluster AB

Actual:
728 ft.

Focus Map:
6

ASBESTOS:

Name:	OUTPLAN
Address:	7121 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	04/28/2017
Notification Number:	2017002855
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/21/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/21/2017
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0

OUTPLAN (Continued) **S121362006**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	04/28/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	OUTPLAN
Address:	7121 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	04/25/2017
Notification Number:	2017002855
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/11/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

OUTPLAN (Continued) **S121362006**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/11/2017
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	04/25/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AB105 **JIMS GULF STATION GAS** **EDR Hist Auto** **1013758655**
Target **7107 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX**

Site 8 of 11 in cluster AB

Actual:
728 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1953	TODDS GULF SERV	GASOLINE STATIONS
1958	TODDS GULF SERV	GASOLINE STATIONS
1962	TAFFS GULF SERV	GASOLINE STATIONS
1965	JIMS GULF STATION GAS	GASOLINE STATIONS

AB106 Target Property | **AUSTIN RESEARCH LABORATOR** | **PFAS ECHO** | **1027328043** **N/A**

AUSTIN, TX

Site 9 of 11 in cluster AB

Actual: 727 ft.

Focus Map: 6

PFAS ECHO:

Name:	AUSTIN RESEARCH LABORATOR
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.33919
Longitude:	-97.71798
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Petroleum
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110000465513
Facility Percent Minority:	57.281
Facility Derived Tribes:	-
Facility Population:	5243.13
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	10
Facility Derived CB2010:	484530015041011
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	5/15/2003
Facility Days Last Inspection:	7,254
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	12/6/2000
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	12/6/2000
Facility Last Penalty AMT:	1,000
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-

AUSTIN RESEARCH LABORATOR (Continued) **1027328043**

CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TXD041470980
RCRA Permit Types:	Other
RCRA NAICS:	325199
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	78752TXCCH7114N
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.71798,%22y%22:30.33919,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
Name:	AUSTIN RESEARCH LABORATOR
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.33919
Longitude:	-97.71798
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Chemical Mfg
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110000465513
Facility Percent Minority:	57.281
Facility Derived Tribes:	-
Facility Population:	5243.13
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	10
Facility Derived CB2010:	484530015041011
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	5/15/2003
Facility Days Last Inspection:	7,254
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	12/6/2000
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	12/6/2000

AUSTIN RESEARCH LABORATOR (Continued) **1027328043**

Facility Last Penalty AMT:	1,000
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TXD041470980
RCRA Permit Types:	Other
RCRA NAICS:	325199
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	78752TXCCH7114N
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.71798,%22y%22:30.33919,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

AC107 **ERNS** **2000548571**
Target Property **7114 NORTH LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 1 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC108 Target Property | **AUSTIN LABORATORIES**
7114 N LAMAR BLVD
AUSTIN, TX 78752

Site 2 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

TSCA | **1005926273**
TX AIRS | **N/A**
TX Ind. Haz Waste
TX IHW CORR ACTION
TX COMP HIST
TX CENTRAL REGISTRY

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

AIRS:

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	12995
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	01/20/2006
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	ENVIRONMENTAL ENGINEER
RO Name:	MR RAVINDER JOSEPH
RO Delivery Address:	8600 GOSLING RD
RO City/State/Zip:	THE WOODLANDS, T 77381-484
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	29885
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	07/26/1995
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	47338

AUSTIN LABORATORIES (Continued) **1005926273**

Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR - CHEMICALS R D
RO Name:	MR DAVID W HESTER
RO Delivery Address:	7114 N LAMAR BLVD
RO City/State/Zip:	AUSTIN, T 78752-231
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	47502
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR CHEMICALS RD
RO Name:	MR DAVID HESTER
RO Delivery Address:	PO BOX 15730
RO City/State/Zip:	AUSTIN, T 78761-573
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	47509
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR CHEMICALS RD
RO Name:	MR DAVID HESTER
RO Delivery Address:	PO BOX 15730
RO City/State/Zip:	AUSTIN, T 78761-573
RO Phone:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

RO Ext Num: 0
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 47660
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 01/01/1900
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): DIRECTOR CHEMICALS RD
RO Name: MR DAVID HESTER
RO Delivery Address: PO BOX 15730
RO City/State/Zip: AUSTIN, T 78761-573
RO Phone: Not reported
RO Ext Num: 0
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 48422
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 08/28/2001
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): DIRECTOR - CHEMICALS R D
RO Name: MR DAVID W HESTER
RO Delivery Address: 7114 N LAMAR BLVD
RO City/State/Zip: AUSTIN, T 78752-231
RO Phone: Not reported
RO Ext Num: 0
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 25371
Regulated Id: RN100726215
Permit Type: EXEMPT
Permit Status: CANCELLED
Permit Issued Date: 07/22/1994

AUSTIN LABORATORIES (Continued) **1005926273**

Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	27093
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	12/16/1994
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	28140
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	02/24/1995
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

AUSTIN LABORATORIES (Continued) **1005926273**

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	44059
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR - CHEMICALS R D
RO Name:	MR DAVID W HESTER
RO Delivery Address:	PO BOX 15730
RO City/State/Zip:	AUSTIN, T 78761-573
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	44060
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	04/25/2000
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR - CHEMICALS R D
RO Name:	MR DAVID W HESTER
RO Delivery Address:	PO BOX 15730
RO City/State/Zip:	AUSTIN, T 78761-573
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	10872
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	EFFECTIVE
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

RO Name: Not reported
RO Delivery Address: Not reported
RO City/State/Zip: Not reported
RO Phone: Not reported
RO Ext Num: Not reported
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 70496
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 12/19/2003
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): MANAGER - EHS
RO Name: MR RICHARD BENNETT
RO Delivery Address: 7114 N LAMAR BLVD
RO City/State/Zip: AUSTIN, T 78752-231
RO Phone: Not reported
RO Ext Num: 0
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 16231
Regulated Id: RN100726215
Permit Type: EXEMPT
Permit Status: CANCELLED
Permit Issued Date: 03/10/1989
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): Not reported
RO Name: Not reported
RO Delivery Address: Not reported
RO City/State/Zip: Not reported
RO Phone: Not reported
RO Ext Num: Not reported
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 39227

AUSTIN LABORATORIES (Continued) **1005926273**

Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	09/11/1998
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	55173
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	05/29/2003
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	MANAGER - EHS
RO Name:	MR RICHARD BENNETT
RO Delivery Address:	PO BOX 15730
RO City/State/Zip:	AUSTIN, T 78761-573
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	32736
Regulated Id:	RN100726215
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

RO Ext Num: Not reported
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 33034
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 01/01/1900
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): Not reported
RO Name: Not reported
RO Delivery Address: Not reported
RO City/State/Zip: Not reported
RO Phone: Not reported
RO Ext Num: Not reported
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 33571
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 01/01/1900
Expiration Date: 12/31/3000
Customer Id: CN600632848
Company Name: HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc: 7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO): Not reported
RO Name: Not reported
RO Delivery Address: Not reported
RO City/State/Zip: Not reported
RO Phone: Not reported
RO Ext Num: Not reported
RO EMail Address: Not reported
Lat Dec Coord Num: 30.342700
Long Dec Coord Num: -97.7166

Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Permit Num: 34409
Regulated Id: RN100726215
Permit Type: PBR
Permit Status: CANCELLED
Permit Issued Date: 01/01/1900

AUSTIN LABORATORIES (Continued) **1005926273**

Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	35175
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	04/30/1997
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	35914
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	09/09/1997
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

AUSTIN LABORATORIES (Continued) **1005926273**

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	50885
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	05/23/2002
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	DIRECTOR CHEMICALS RD
RO Name:	MR DAVID HESTER
RO Delivery Address:	7114 N LAMAR BLVD
RO City/State/Zip:	AUSTIN, T 78752-231
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	53562
Regulated Id:	RN100726215
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	12/16/2002
Expiration Date:	12/31/3000
Customer Id:	CN600632848
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Physical Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
Rep Official(RO):	MANAGER - EHS
RO Name:	MR RICHARD BENNETT
RO Delivery Address:	7114 N LAMAR BLVD
RO City/State/Zip:	AUSTIN, T 78752-231
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

Ind. Haz Waste:

Name:	HUNTSMAN PETROCHEMICAL
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	30688
Registration Initial Notification Date:	09/23/1976
Registration Last Amendment Date:	09/09/2019
EPA Identification:	TXD041470980
Primary NAICS Code:	325199
Status Change Date:	20120409
Land Type:	PRIVATE
Description of Facility Site Location:	7114 N Lamar Blvd, Austin, TX

AUSTIN LABORATORIES (Continued) **1005926273**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Contact Name:	RAVINDER JOSEPH
Contact Telephone Number:	512-4830178
Mailing Address:	8600 GOSLING RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	THE WOODLANDS, TX 773814845
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	8252
Site Owner Tax ID:	621539359
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Operator Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Operator Address:	7114 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4830934
Operator Fax Number:	1-512-4830989
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	15815945181
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Owner Mailing Address:	7114 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4830934
Owner Fax:	1-512-4830989
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	15815945181
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960718
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14

AUSTIN LABORATORIES (Continued) **1005926273**

Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940712
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	6500
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19951220
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	12000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19951128
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	10000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020313
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	20000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19951020
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	007
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	2000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19921117
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	008
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	2000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19921117
Deed Record Needed:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Deed Recording Date:	Not reported
Unit Number:	009
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	50000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020313
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	010
Unit Type Code:	18
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	50000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19930609
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	011
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	OTHER
UIC Permit Number:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Capacity:	21500
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960718
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	012
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	16000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960718
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	013
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	16000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960613
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	014
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19950927
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	015
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	40000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Stores PWW & SCWOU blend

AUSTIN LABORATORIES (Continued) **1005926273**

Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	016
Unit Type Code:	18
Unit Status:	CLOSED
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	40000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970123
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	017
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Stores PWW and SCWOU blend.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	018

AUSTIN LABORATORIES (Continued) **1005926273**

Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	T-WI-47 Organic Waste Hazardous. Haz amines/polyols w/MeOH
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	019
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	T-WI-48 Organic Waste Non-Haz. Non-haz polyols/amines.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	020
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	T-T1-211 Auxilliary Fuel-MeOH rinsate from polyol/amine production
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	021
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Hazardous container storage area. Corner of Ave B & Third.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	022
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	T-T1-203
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	023
Unit Type Code:	22
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Class 1 compactor
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	024
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Non-hazardous container storage area N of Bldg 35.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219

AUSTIN LABORATORIES (Continued) **1005926273**

Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	025
Unit Type Code:	22
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Class 2 office trash dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	026
Unit Type Code:	22
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	class 2 office trash dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	027
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	08

AUSTIN LABORATORIES (Continued) **1005926273**

UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	129
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	T-T1-212. Stores PWW or SCWOU Blend
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	028
Unit Type Code:	17
Unit Status:	CLOSED
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	070
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Super Critical Water Oxidation Unit.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	029
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	135
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Wastewater equalization tank. contents monitored for TOC prior to POTW Disc har
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	030
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Wastewater intermediate tank IT-1.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	031
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Permit Sequence Number:	Not reported
Unit Description:	Wastewater intermediate tank, IT-2.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	032
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Wastewater intermediate tank IT-3
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	033
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Wastewater intermediate tank IT-4
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20061219
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Unit Number:	034
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	no longer used - K-13
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	035
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	20000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Nonhazardous waste storage tank, T-T1-243
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040108
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	7114 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4830934
Contact Fax:	1-512-4830989
Contact Email:	Not reported
Contact Name:	RAVINDER JOSEPH
Contact Title:	SEN ENVIRONMENTAL ENGINEE
Contact Role:	PRICONT
Contact Address:	8600 GOSLING RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	THE WOODLANDS, TX 77381
Contact Phone:	1-512-4830178
Contact Fax:	1-512-4830955
Contact Email:	ravi_joseph@huntsman.com

Ind. Haz Waste:

Waste ID:	12624
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001201H
Waste Code Status:	INACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Methanol/water from cleaning the plant and equipment. The rinsate is methanol a
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MEOH TT206 (T-T1-206)
Primary NAICS Code:	325199
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12615
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Polyol/Amine/methanol waste. Off-spec amine & polyol product, blended withmetha
Standard Industrial Code:	28690
Primary Source:	G13

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Amine TT-47 (T-W1-47)
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12616
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Polyol/methanol waste mixture. Disposal of off-spec polyol, blended with methan
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Polyol-TT-48 (T-W1-48)
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12626
Texas Waste Code:	Not reported
Texas Waste Code 2:	00042071
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Washwater from cleaning plant unit, and processing equipment. Date of initial g
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Washwater TT-212, TT213, (T-T1-212), (T-T1-213)
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	12628
Texas Waste Code:	Not reported
Texas Waste Code 2:	00053021
Waste Code Status:	INACTIVE
Waste Form:	302
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Dowtherm, contaminatd soil and absorbent. Cleanup operation of Dowtherm J produ
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Dowtherm solid
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	12622
Texas Waste Code:	Not reported
Texas Waste Code 2:	00069011
Waste Code Status:	INACTIVE
Waste Form:	901
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Trash contaminated plant production refuse material. Papers, cardboard, cans, e
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Compacted trash Class 1
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	12631
Texas Waste Code:	Not reported
Texas Waste Code 2:	00073191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Reacted isocyanate from poyurea from research. The mixing of isocyanate with am
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Reacted isocyanate
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	12635
Texas Waste Code:	Not reported
Texas Waste Code 2:	00083881
Waste Code Status:	INACTIVE
Waste Form:	388
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glass (crushed). Glass containers that are RCRA empty. Containers are crusheda
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Broken glass
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	12630
Texas Waste Code:	Not reported
Texas Waste Code 2:	00094032
Waste Code Status:	INACTIVE
Waste Form:	403

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Polyol/polyol solids. Polyol/polyol filter cake waste from the manufactureof po
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Polyol/Polyol filter cake
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	73632
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solvent non-halogenated. Spent oils from hydraulic reservoirs and engine oil ch
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Solvent waste
Primary NAICS Code:	325199
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73633
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	Halogenated solvents. Composite of various halogenated solvents from cleaning,
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Halogenated solvents
Primary NAICS Code:	325199
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12613
Texas Waste Code:	Not reported
Texas Waste Code 2:	00123191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amine/amine solids. Off-spec amine and amine solids from production of amine pro
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Amine filter cake
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	12609
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent acids of di-chromate acid mixed with sulfuric acid and chlorinated waste.
Standard Industrial Code:	28690
Primary Source:	G02
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Di-chronic acid waste
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73630
Texas Waste Code:	Not reported
Texas Waste Code 2:	00143012
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amine/silicate filtering waste. Waste is generated from emptying a silicate fil
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Amine/silicate filtering media
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	12623
Texas Waste Code:	Not reported
Texas Waste Code 2:	00153111
Waste Code Status:	INACTIVE
Waste Form:	311
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos insulation removal from mediation projects. Date of initial generation
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Audit Performed:	0
Company Waste ID:	Asbestos
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	12602
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Isocyanate (aliphatic) liquid waste. Generating process is from mixing a Part A
Standard Industrial Code:	28690
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Aliphatic isocyanate
Primary NAICS Code:	325199
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73629
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Isocyanate (aromatic) liquid waste. Generating process is from mixing a Part A
Standard Industrial Code:	28690
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Aromatic isocyanate
Primary NAICS Code:	325199
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12639
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab packs. Disposal of discarded, out of date, or off-spec chemicals appearingi
Standard Industrial Code:	28690
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Lab packs (hazardous)
Primary NAICS Code:	325199
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73625
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amine filters/cloth. Production of amine product. These filters are a part of

AUSTIN LABORATORIES (Continued) **1005926273**

Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Amine filter hazardous
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85924
Texas Waste Code:	Not reported
Texas Waste Code 2:	0020109H
Waste Code Status:	INACTIVE
Waste Form:	109
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent sodium hydroxide material used for cleaning equipment Waste inactivated d
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73624
Texas Waste Code:	Not reported
Texas Waste Code 2:	00213011
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	TPH soil contaminated. Soil or absorbant contaminated with a TPH content greate
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TPH contaminated soil
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	73631
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acute hazard lab packs process for this waste stream is the lab packing of disca
Standard Industrial Code:	28690
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Acute hazard lab pack
Primary NAICS Code:	325199
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	12619
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Residue, paint. Discarding of old paint containing RCRA metals and solvents. D
Standard Industrial Code:	28690
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Residue, paint
Primary NAICS Code:	325199

AUSTIN LABORATORIES (Continued) **1005926273**

EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	148925
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024117H
Waste Code Status:	INACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Rinsate from the cleaning of broken guages and thermometers glassware.
Standard Industrial Code:	28690
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73626
Texas Waste Code:	Not reported
Texas Waste Code 2:	00253011
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sump residue. Generating process is the removal of soil from area grale drains.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Sump residue
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	73627
Texas Waste Code:	Not reported
Texas Waste Code 2:	00264041
Waste Code Status:	INACTIVE
Waste Form:	404
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Activated carbon, spent carbon from filtering process manufacturing amine and po
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Activated carbon
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	12621
Texas Waste Code:	Not reported
Texas Waste Code 2:	00279032
Waste Code Status:	INACTIVE
Waste Form:	903
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant office refuse. Generating process is general office trash as defined in 3
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Office refuse
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	73628
Texas Waste Code:	Not reported
Texas Waste Code 2:	00289012
Waste Code Status:	INACTIVE
Waste Form:	901
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production refuse. Generating process is plant production trash as define
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	148926
Texas Waste Code:	Not reported
Texas Waste Code 2:	0029409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Discarded pure chemicals from research and development laboratory Waste inactiv
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Naphthalene
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85925
Texas Waste Code:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code 2:	0030204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent acetone, methanol, polyol & amine liquid waste generated from discarding r
Standard Industrial Code:	28690
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	95209
Texas Waste Code:	Not reported
Texas Waste Code 2:	0031117H
Waste Code Status:	INACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury from broken thermometers and electrical switches containing liquid mercu
Standard Industrial Code:	28690
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Mercury waste
Primary NAICS Code:	325199
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	95034
Texas Waste Code:	Not reported
Texas Waste Code 2:	00324092
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	A brownish/black solid with partial crystalization. Production of amine (methyl
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	95032
Texas Waste Code:	Not reported
Texas Waste Code 2:	00336091
Waste Code Status:	INACTIVE
Waste Form:	609
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater tank/sump sludge from cleanout.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	118311
Texas Waste Code:	Not reported
Texas Waste Code 2:	00342192

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Methylmorpholinone lights. Aqueous waste material from 4M2M process containing
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Methylmorpholinone Lights
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Waste ID:	122157
Texas Waste Code:	Not reported
Texas Waste Code 2:	0035409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Phenol waste. Cleanup material (e.g. absorbents, gloves, respirators, phenols)
Standard Industrial Code:	28690
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Phenol solids waste
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	122109
Texas Waste Code:	Not reported
Texas Waste Code 2:	00362072
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Polyol (aqueous) waste. Poly(alkoxylate) alcohol generation by-product

AUSTIN LABORATORIES (Continued) **1005926273**

	materia
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	123149
Texas Waste Code:	Not reported
Texas Waste Code 2:	00372061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oils from motor combustion engines, vacuum pumps and/or hydrogen pumps which exh
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	123143
Texas Waste Code:	Not reported
Texas Waste Code 2:	00382061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Vacuum pump oils (recycle). Oils drained from vacuum pumps which exhibit no haz
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	123142
Texas Waste Code:	Not reported
Texas Waste Code 2:	00392061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hydrogen pump oils (recycle). Oils drained from hydrogen pumps which exhibit no
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	123139
Texas Waste Code:	Not reported
Texas Waste Code 2:	00403101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used spent oil filters (recycle). Used oil filters which exhibit no hazardous c
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	124641

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00412191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amines (non-hazardous). By-product from the manufacture of various amine and am
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	125417
Texas Waste Code:	Not reported
Texas Waste Code 2:	00423101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SCWO Unit Filters. Pre-filters from a Clean Water Act pre-treatment unit flowin
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	125425
Texas Waste Code:	Not reported
Texas Waste Code 2:	0043103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nitric acid. Acid used for de-scaling a Clean Water Act pre-treatment

AUSTIN LABORATORIES (Continued) **1005926273**

	unit.
Standard Industrial Code:	28690
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	128665
Texas Waste Code:	Not reported
Texas Waste Code 2:	00444091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Miscellaneous wood pieces, contaminated floor sweep and general warehouse debris
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	128666
Texas Waste Code:	Not reported
Texas Waste Code 2:	00452071
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	80-90% water and 10-20% organic blend/ The blending of several waste streams wit
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	128667
Texas Waste Code:	Not reported
Texas Waste Code 2:	00462071
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	95 +% water with trace organics/ off-specification Super Critical Water Oxidatio
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	130927
Texas Waste Code:	Not reported
Texas Waste Code 2:	00472192
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	50-80% Polyol, 20-50% Amine, 20-60% Water, with residual solvents/ Mixtureof noW
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	133849
Texas Waste Code:	Not reported
Texas Waste Code 2:	00483931
Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent metal catalysts/production of amines and polyols; 5/92
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Spent metal catalyst (nonhazardous)
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	141087
Texas Waste Code:	Not reported
Texas Waste Code 2:	0049393H
Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent copper chromite catalysts / Production of amines / May 1995
Standard Industrial Code:	28690
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	111
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	141088
Texas Waste Code:	Not reported
Texas Waste Code 2:	00504091
Waste Code Status:	INACTIVE

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Chemically contaminated Plant Production Refuse material. Paper, cardboard, crus
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	147584
Texas Waste Code:	Not reported
Texas Waste Code 2:	0051219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Old Aniline. This material was purchased and never used due to theWaste
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Aniline
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	146138
Texas Waste Code:	Not reported
Texas Waste Code 2:	0052409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Unused Phenol generated due to cacellation of a research project.Waste
Standard Industrial Code:	28690

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Phenol
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	146139
Texas Waste Code:	Not reported
Texas Waste Code 2:	00532191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Class 1 polyols and amines from researchand developed processes. Flashpoint140-
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Polyols & Amines
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	146140
Texas Waste Code:	Not reported
Texas Waste Code 2:	0054212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Isocyanate-polyol polymer with free residual isocyanate from R&D activities.
Standard Industrial Code:	28690
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Company Waste ID:	Isocyanate-Polyol
Primary NAICS Code:	325199
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	149273
Texas Waste Code:	Not reported
Texas Waste Code 2:	00550031
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Class 1 lab pack items. Small quantitiesof R&D chemicals no longer needed.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Lab Pack (Nonhaz.)
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	149274
Texas Waste Code:	Not reported
Texas Waste Code 2:	0056393H
Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Silver catalyst.
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Silver catalyst
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	151096
Texas Waste Code:	Not reported
Texas Waste Code 2:	00572021
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Halogenated Hydrocarbon removed during routine maintenance of refrigeration Wa
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Freon/Refrigerant
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	154965
Texas Waste Code:	Not reported
Texas Waste Code 2:	0058105H
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Unused ferric sulfate solution. Initial generation October 1996. Waste
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Ferric Sulfate Soln.
Primary NAICS Code:	325199
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	157706
Texas Waste Code:	Not reported
Texas Waste Code 2:	0059393H

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Vanadium Phosphate Dried Powder Catalyst waste containing alcohol.2/97
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Van-PO4 Dried Powder
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	157707
Texas Waste Code:	Not reported
Texas Waste Code 2:	0060207H
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Concentrated water solution of TBA/TBHP generated when making PO. Initial gen-e
Standard Industrial Code:	28690
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TBA/TBHP
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	158404
Texas Waste Code:	Not reported
Texas Waste Code 2:	0061701H
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Hazardous gases. Unused or spent gases destined for disposal.
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Hazardous gases
Primary NAICS Code:	325199
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	158900
Texas Waste Code:	Not reported
Texas Waste Code 2:	00621011
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Process Wash Water with low solvent and organic content. Wash water fromcle
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Process Wash Water
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	158901
Texas Waste Code:	Not reported
Texas Waste Code 2:	00631011
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	80-90% water and 10-20% organic blend. The blending of waste streams to produce
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SCWOU Feed Blend
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	158902
Texas Waste Code:	Not reported
Texas Waste Code 2:	00641011
Waste Code Status:	INACTIVE
Waste Form:	101

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	95+% water with trace organics. Off- spec SCWOU effluent (high TOC). Waste i
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SCWOU Effluent
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	161265
Texas Waste Code:	Not reported
Texas Waste Code 2:	00654091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solid caustic material such as KOH and NaOH used to neutralize chemicals.Waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Caustic, solid
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	165578
Texas Waste Code:	Not reported
Texas Waste Code 2:	0066104H
Waste Code Status:	INACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Phosphoric acid which is out dated.
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1

AUSTIN LABORATORIES (Continued) **1005926273**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Phosphoric acid
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	168017
Texas Waste Code:	Not reported
Texas Waste Code 2:	0067203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste Cyclohexane from Kettle Cleanup
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste Cyclohexane
Primary NAICS Code:	325199
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	168018
Texas Waste Code:	Not reported
Texas Waste Code 2:	0068493H
Waste Code Status:	INACTIVE
Waste Form:	493
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent Catalyst from Methanol and Amine Service
Standard Industrial Code:	28690
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	169114
Texas Waste Code:	Not reported
Texas Waste Code 2:	0069801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hazardous Gases - organic. Unused or spent gases destined for disposal.
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Hazardous Gases-Org.
Primary NAICS Code:	325199
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	169522
Texas Waste Code:	Not reported
Texas Waste Code 2:	00703071
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Boiler Scale - iron scale generated during clean out of boiler.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Boiler Scale
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 172173
Texas Waste Code: Not reported
Texas Waste Code 2: 00712191
Waste Code Status: INACTIVE
Waste Form: 219
Waste Classification: 1
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Organic Waste, Nonhazardous T-W1-248. Off-spec non-haz polyol/amines
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Organic Waste Nonhaz
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 174973
Texas Waste Code: Not reported
Texas Waste Code 2: 0072105H
Waste Code Status: INACTIVE
Waste Form: 105
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Formic Acid - unused, outdated product drum quantity for research and develop-m
Standard Industrial Code: 28690
Primary Source: G02
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Formic Acid
Primary NAICS Code: 325199
EPA Waste Form Code: W105
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 174974

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0073219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Benzene - unused, outdated product. Drum quantity for research and develop-m
Standard Industrial Code:	28690
Primary Source:	G24
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Benzene
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175225
Texas Waste Code:	Not reported
Texas Waste Code 2:	0074409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amine Solids. Hazardous solid amine fromoff-spec or outdated product.
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Amine Solid-Haz
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175226

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0075409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Polyol Solids - Hazardous. Haz solid polyol from off-spec product or out-date
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Polyol Solid - Haz
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	177835
Texas Waste Code:	Not reported
Texas Waste Code 2:	00767011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Unused Or Spent Non-Hazardous inorganic gases destined for disposal.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Inorg. Gas Cylinders
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	181250
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H

AUSTIN LABORATORIES (Continued) **1005926273**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Amine Liquids-Hazardous. Discarding of off-spec or out-dated product.
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183444
Texas Waste Code:	Not reported
Texas Waste Code 2:	0078409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	benzene containing solids
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	benzene solids
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183445
Texas Waste Code:	Not reported
Texas Waste Code 2:	0079211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Jeffstrip paint stripper

AUSTIN LABORATORIES (Continued) **1005926273**

Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Jeffstrip
Primary NAICS Code:	325199
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183682
Texas Waste Code:	Not reported
Texas Waste Code 2:	00803931
Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	vanadium pyrophosphate catalyst - Class 1, low pH.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	184998
Texas Waste Code:	Not reported
Texas Waste Code 2:	00814091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Isocyanate- polyol waste, mostly reacted.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	isocyanate-polyol

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	186153
Texas Waste Code:	Not reported
Texas Waste Code 2:	0082105H
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	sulfuric acid and water, acetic acid and water
Standard Industrial Code:	28690
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	acids
Primary NAICS Code:	325199
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186248
Texas Waste Code:	Not reported
Texas Waste Code 2:	0083109H
Waste Code Status:	INACTIVE
Waste Form:	109
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	caustic soda, potassium hydroxide and water
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	potassium hydroxide
Primary NAICS Code:	325199
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	186154
Texas Waste Code:	Not reported
Texas Waste Code 2:	0084219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	aniline clean up waste
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	analine waste
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186249
Texas Waste Code:	Not reported
Texas Waste Code 2:	0085319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	High pressure sodium and metal halide light bulbs. One time shipment, wasteinact
Standard Industrial Code:	28690
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	electric light bulbs
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	188256

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0086219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	sodium methylate solution
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	sodium methylate sol
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	188780
Texas Waste Code:	Not reported
Texas Waste Code 2:	0087409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	solids with aniline and nitrobenzene
Standard Industrial Code:	28690
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	solids with aniline
Primary NAICS Code:	325199
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	190282
Texas Waste Code:	Not reported
Texas Waste Code 2:	0088319H
Waste Code Status:	INACTIVE

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	computer monitors
Standard Industrial Code:	28690
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	computer monitors
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	190283
Texas Waste Code:	Not reported
Texas Waste Code 2:	0089609H
Waste Code Status:	INACTIVE
Waste Form:	609
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater tank sludge and sump sludge
Standard Industrial Code:	28690
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	tank and sump sludge
Primary NAICS Code:	325199
EPA Waste Form Code:	W609
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	195777
Texas Waste Code:	Not reported
Texas Waste Code 2:	0090319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	contaminated equipment from tank and equipment closures

AUSTIN LABORATORIES (Continued) **1005926273**

Standard Industrial Code:	28690
Primary Source:	G41
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	cont. equipment
Primary NAICS Code:	325199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	205240
Texas Waste Code:	Not reported
Texas Waste Code 2:	00914092
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	off-spec and waste fatty alcohols
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	LINEAR FATTY ALCOHOL
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	203318
Texas Waste Code:	Not reported
Texas Waste Code 2:	0092110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic soda and caustic potash waste
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ALKALI WASTES

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	325199
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	205241
Texas Waste Code:	Not reported
Texas Waste Code 2:	00932961
Waste Code Status:	INACTIVE
Waste Form:	296
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste ethylene glycol and water mixtures
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ETHYLENE GLYCOL WATE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	213770
Texas Waste Code:	Not reported
Texas Waste Code 2:	00942192
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste linear fatty acids
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	WASTE FATTY ACID
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	205242

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00952191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	unused & off-spec isopropylated triphenyl phosphate
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ISOPROPYLATED TPP
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	208060
Texas Waste Code:	Not reported
Texas Waste Code 2:	0097203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	n-butanol and n-butanol wastes
Standard Industrial Code:	Not reported
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	N-BUTANOL
Primary NAICS Code:	325199
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	208061
Texas Waste Code:	Not reported
Texas Waste Code 2:	0099219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	phosphate ester
Standard Industrial Code:	Not reported
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOSPHATE ESTERS
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	208062
Texas Waste Code:	Not reported
Texas Waste Code 2:	01000031
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixed non-haz labpack
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MIXED NON-HAZ LABPAC
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	208107
Texas Waste Code:	Not reported
Texas Waste Code 2:	01017011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	BF3 gas
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Company Waste ID:	BF3 INORGANIC GAS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	208063
Texas Waste Code:	Not reported
Texas Waste Code 2:	0102003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixed non-acutely hazardous labpack
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MIXED HAZ LABPACK
Primary NAICS Code:	325199
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	213665
Texas Waste Code:	Not reported
Texas Waste Code 2:	01032121
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	polymeric isocyanate waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	POLYMERIC ISOCYANATE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	210399
Texas Waste Code:	Not reported
Texas Waste Code 2:	0104315H
Waste Code Status:	INACTIVE
Waste Form:	315
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	phosphoric anhydride waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOSPHORIC ANHYDRIDE
Primary NAICS Code:	325199
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	211817
Texas Waste Code:	Not reported
Texas Waste Code 2:	01052081
Waste Code Status:	INACTIVE

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Form:	208
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	nonyl phenol and other alkyl phenols
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ALKYL PHENOLS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	211818
Texas Waste Code:	Not reported
Texas Waste Code 2:	0106104H
Waste Code Status:	INACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste nitric acid
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NITRIC ACID WASTE
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	211819
Texas Waste Code:	Not reported
Texas Waste Code 2:	0107104H
Waste Code Status:	INACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste sulfuric acid
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE SULFURIC ACID
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	211893
Texas Waste Code:	Not reported
Texas Waste Code 2:	0108219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	methyl pyridine waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	METHYL PYRIDINE WAST
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	213666
Texas Waste Code:	Not reported
Texas Waste Code 2:	01091191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	molybdenum in weak ammonium hydroxide
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MOLY IN AMMONIUM HYD

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	211820
Texas Waste Code:	Not reported
Texas Waste Code 2:	0111211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	petroleum distillate waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PETROLEUM DISTILLATE
Primary NAICS Code:	325199
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	211894
Texas Waste Code:	Not reported
Texas Waste Code 2:	0112219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MTBE waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MTBE WASTE
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Waste ID:	211821
Texas Waste Code:	Not reported
Texas Waste Code 2:	0113219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	flammable glycol ethers
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	GLYCOL ETHERS
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	211895
Texas Waste Code:	Not reported
Texas Waste Code 2:	01153162
Waste Code Status:	INACTIVE
Waste Form:	316
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	non-hazardous sodium salts
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ SODIUM SALTS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	213667
Texas Waste Code:	Not reported
Texas Waste Code 2:	0117212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	waste styrene
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE STYRENE
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	212963
Texas Waste Code:	Not reported
Texas Waste Code 2:	01182191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	flame retardants
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAME RETARDANT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	212964
Texas Waste Code:	Not reported
Texas Waste Code 2:	0120219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste toluene mixtures
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Company Waste ID:	WASTE TOLUENE
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	212965
Texas Waste Code:	Not reported
Texas Waste Code 2:	01212191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	solution of tolytriazole in water
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE TOLYTRIAZOL
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	212966
Texas Waste Code:	Not reported
Texas Waste Code 2:	01222192
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste polyglycols
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE POLYGLYCOLS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Waste ID:	212967
Texas Waste Code:	Not reported
Texas Waste Code 2:	0123219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste organic acids
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE ORGANIC ACIDS
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	212968
Texas Waste Code:	Not reported
Texas Waste Code 2:	0124203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	flammable non-halogenated and not listed solvents
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE SOLVENTS
Primary NAICS Code:	325199
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	212969
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125203H
Waste Code Status:	INACTIVE
Waste Form:	203

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste acetone
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE ACETONE
Primary NAICS Code:	325199
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	212970
Texas Waste Code:	Not reported
Texas Waste Code 2:	0126212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste toluene diisocyanate
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOLUENE DIISOCYANATE
Primary NAICS Code:	325199
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	213668
Texas Waste Code:	Not reported
Texas Waste Code 2:	01294091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	waste methylene dianiline
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	METHYLENE DIANILINE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	213669
Texas Waste Code:	Not reported
Texas Waste Code 2:	0130211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	paint thinners and coatings
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PAINT THINNERS
Primary NAICS Code:	325199
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	213670
Texas Waste Code:	Not reported
Texas Waste Code 2:	0132202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	methylene chloride waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	METHYLENE CHLORIDE W
Primary NAICS Code:	325199
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	213671
Texas Waste Code:	Not reported
Texas Waste Code 2:	01333161
Waste Code Status:	INACTIVE
Waste Form:	316
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste phosphorous compounds
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOSPHOROUS COMPOUND
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	213672
Texas Waste Code:	Not reported
Texas Waste Code 2:	01342051
Waste Code Status:	INACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste lube oil water emulsion
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OIL WATER EMULSION
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Waste ID:	213771
Texas Waste Code:	Not reported
Texas Waste Code 2:	0135004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab Pack containing acute haz wastes
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	LAB PACK
Primary NAICS Code:	325199
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	213772
Texas Waste Code:	Not reported
Texas Waste Code 2:	0136104H
Waste Code Status:	INACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste hydrochloric acid
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WASTE HYDROCHLORIC
Primary NAICS Code:	325199
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	214076
Texas Waste Code:	Not reported
Texas Waste Code 2:	0137212H
Waste Code Status:	INACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	toxic and flammable isocyanate mixtures
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC ISOCYANATE MIX
Primary NAICS Code:	325199
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	129331
Texas Waste Code:	Not reported
Texas Waste Code 2:	50009022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Supplemental plant production refuse/Class 2 waste from production, manufacturin
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Waste ID:	129333
Texas Waste Code:	Not reported
Texas Waste Code 2:	50013072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Metal scrap/metal scale, filings or scrap generated form work associated with th
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	129335
Texas Waste Code:	Not reported
Texas Waste Code 2:	50024882
Waste Code Status:	INACTIVE
Waste Form:	488
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wood scrap/generated from projects associated with production or manufacturing o
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	129336
Texas Waste Code:	Not reported
Texas Waste Code 2:	50033902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	Construction debris/generated from projects associated with production or manufa
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	129337
Texas Waste Code:	Not reported
Texas Waste Code 2:	50043192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Insulation (non-asbestos)/generated from projects associated with production orm
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	133847
Texas Waste Code:	Not reported
Texas Waste Code 2:	50053962
Waste Code Status:	INACTIVE
Waste Form:	396
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-PCB dry-type transformers and capacitors as well as ballasts from office lig
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Audit Performed:	1
Company Waste ID:	Electrical equipment
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	CLASS AUDIT

Ind. Haz Waste:

Waste ID:	133848
Texas Waste Code:	Not reported
Texas Waste Code 2:	50064032
Waste Code Status:	INACTIVE
Waste Form:	403
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	60-80% epoxy resins, 20-40% drysorb, trace of glass/research and development ofe
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Epoxy/Epoxy resins
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	141089
Texas Waste Code:	Not reported
Texas Waste Code 2:	50079992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Office trash - cardboard, paper, staples, etc. Generating process is general of
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN LABORATORIES (Continued) **1005926273**

Waste ID:	141090
Texas Waste Code:	Not reported
Texas Waste Code 2:	50089992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production trash. Generating process is plant production activities. Dat
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	144278
Texas Waste Code:	Not reported
Texas Waste Code 2:	50093012
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil generated from facility maintenanceoperations containing dirt, rock, andcem
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Soil
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	146141
Texas Waste Code:	Not reported
Texas Waste Code 2:	50102022
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Generators Waste Description:	Rigid foam B-component formulation containing CFC141B as a blowing agent. I
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Rigid foam B-Comp.
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	157708
Texas Waste Code:	Not reported
Texas Waste Code 2:	50113192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Electrical parts:Non-PCB dry-type transformers,capacitors and ballasts fromoffic
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Electrical equipment
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	157709
Texas Waste Code:	Not reported
Texas Waste Code 2:	50121192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater treated under the CWA. Low strength TOC water from facilityoper
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Audit Performed:	1
Company Waste ID:	Wastewater
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	157710
Texas Waste Code:	Not reported
Texas Waste Code 2:	50133932
Waste Code Status:	INACTIVE
Waste Form:	393
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Vanadium pyrophosphate catalyst waste. Laboratory samples no longer needed.2/97
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Vanadium PyroPO4
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	261322
Texas Waste Code:	Not reported
Texas Waste Code 2:	C3N62071
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262382

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	C4XL3081
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262383
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4XM3191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	264516
Texas Waste Code:	Not reported
Texas Waste Code 2:	C7HB4091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	276604
Texas Waste Code:	Not reported
Texas Waste Code 2:	CQ594072
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	276605
Texas Waste Code:	Not reported
Texas Waste Code 2:	CQ5B2192
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	281171
Texas Waste Code:	Not reported
Texas Waste Code 2:	CWM53161
Waste Code Status:	INACTIVE
Waste Form:	316
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	281172
Texas Waste Code:	Not reported
Texas Waste Code 2:	CWM63071
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	311921
Texas Waste Code:	Not reported
Texas Waste Code 2:	DLNH403H
Waste Code Status:	INACTIVE
Waste Form:	403
Waste Classification:	H
Waste is Radioactive:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	311922
Texas Waste Code:	Not reported
Texas Waste Code 2:	DLNJ403H
Waste Code Status:	INACTIVE
Waste Form:	403
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	311318
Texas Waste Code:	Not reported
Texas Waste Code 2:	DMVX2191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	297913
Texas Waste Code:	Not reported
Texas Waste Code 2:	DN854031
Waste Code Status:	INACTIVE
Waste Form:	403
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	298743
Texas Waste Code:	Not reported
Texas Waste Code 2:	DNFB201H
Waste Code Status:	INACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	300009
Texas Waste Code:	Not reported
Texas Waste Code 2:	DRMJ202H
Waste Code Status:	INACTIVE

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	300010
Texas Waste Code:	Not reported
Texas Waste Code 2:	DRMK203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	305504
Texas Waste Code:	Not reported
Texas Waste Code 2:	DTVZ1191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	306531
Texas Waste Code:	Not reported
Texas Waste Code 2:	DVB2208H
Waste Code Status:	INACTIVE
Waste Form:	208
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	302141
Texas Waste Code:	Not reported
Texas Waste Code 2:	DWMC2191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	302142

AUSTIN LABORATORIES (Continued) **1005926273**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DWMD2191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	302143
Texas Waste Code:	Not reported
Texas Waste Code 2:	DWMF2191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	304836
Texas Waste Code:	Not reported
Texas Waste Code 2:	DXDM202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	304863
Texas Waste Code:	Not reported
Texas Waste Code 2:	DXFN219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	307554
Texas Waste Code:	Not reported
Texas Waste Code 2:	DY6Y203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Ind. Haz Waste:

Waste ID:	307555
Texas Waste Code:	Not reported
Texas Waste Code 2:	DY6Z219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	307556
Texas Waste Code:	Not reported
Texas Waste Code 2:	DY72219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	307557
Texas Waste Code:	Not reported
Texas Waste Code 2:	DY73219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0

AUSTIN LABORATORIES (Continued) **1005926273**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	307585
Texas Waste Code:	Not reported
Texas Waste Code 2:	DY82219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	307650
Texas Waste Code:	Not reported
Texas Waste Code 2:	DYBG302H
Waste Code Status:	INACTIVE
Waste Form:	302
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	300731
Texas Waste Code:	Not reported
Texas Waste Code 2:	F3PM409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	301628
Texas Waste Code:	Not reported
Texas Waste Code 2:	F3ZB219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

AUSTIN LABORATORIES (Continued) **1005926273**

Contact Telephone:	Not reported
Mailing Address:	8600 GOSLING RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	THE WOODLANDS, TX 77381
AR Number:	0000300344
Principal Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8600 GOSLING RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	THE WOODLANDS, TX 77381
AR Number:	0000300344
Principal Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	HUNTSMAN PETROCHEMICAL AUSTIN
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Program Id:	30688
Location Desc:	7114 N LAMAR BLVD, AUSTIN, TX
RN NUM:	RN100726215
Status:	INACTIVE
Status Date:	07/05/2005
EDR Link ID:	30688
Project Phase:	TRANSFERRED
Phase Status Date:	07/05/2005
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

COMP HIST:

RN Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600632848
CN Name:	HUNTSMAN PETROCHEMICAL CORPORATION
CN Rating:	5.89
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	325199
SIC Code:	1611

AUSTIN LABORATORIES (Continued) **1005926273**

Related Number: TH0052P,TXD041470980,10872,TH0052P,4845300036,4845300036

CENTRAL REGISTRY:

Regulated Entity Number: RN100726215
Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-2310
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600632848
Customer Name: HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name: Huntsman Petrochemical Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 6/14/1985
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 325199
Primary NAICS Industry Type Description: All Other Basic Organic Chemical Manufacturing
Physical Location Description: 7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number: RN100726215
Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-2310
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN604173187
Customer Name: TEXACO CHEMICAL COMPANY
Customer Legal Name: TEXACO CHEMICAL COMPANY
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/10/1986
Affiliation End Date: 8/20/2006
Customer Status: UNVALD
Primary NAICS Industry Type Code: 325199
Primary NAICS Industry Type Description: All Other Basic Organic Chemical Manufacturing
Physical Location Description: 7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number: RN100726215
Name: AUSTIN LABORATORIES
Address: 7114 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-2310
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600632848
Customer Name: HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name: Huntsman Petrochemical Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 6/14/1985
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 325199
Primary NAICS Industry Type Description: All Other Basic Organic Chemical Manufacturing
Physical Location Description: 7114 N LAMAR BLVD, AUSTIN, TX

AUSTIN LABORATORIES (Continued) **1005926273**

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD

AUSTIN LABORATORIES (Continued) **1005926273**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE

AUSTIN LABORATORIES (Continued) **1005926273**

Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Regulated Entity Number:	RN100726215
Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-2310
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600632848
Customer Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Customer Legal Name:	Huntsman Petrochemical Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/14/1985
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325199
Primary NAICS Industry Type Description:	All Other Basic Organic Chemical Manufacturing
Physical Location Description:	7114 N LAMAR BLVD, AUSTIN, TX

Click this hyperlink while viewing on your computer to access
72 additional TX CENTRAL REG: record(s) in the EDR Site Report.

AC109 **HUNTSMAN PETRO - AUSTIN LABORATORIES** **TSCA** **1001958812**
Target **7114 NORTH LAMAR BOULEVARD** **N/A**
Property **AUSTIN, TX 78752**

Site 3 of 43 in cluster AC

Actual:
727 ft.

Click this hyperlink while viewing on your computer to access
additional TSCA detail in the EDR Site Report.

Focus Map:
6

AC110 **ERNS** **97405497**
Target Property **7114 NORTH LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 4 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC111 **TEXACO-AUSTIN LABORATORIES** **TSCA** **1005932738**
Target Property **7114 N LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 5 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

AC112 **TEXACO CHEMICAL** **TX SPILLS 90** **S112323525**
Target Property **7114 N. LAMAR** **N/A**
AUSTIN, TX

Site 6 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Spills:

Status:	Not reported
Contact Name:	TEXACO CHEMICAL
Contact Phone:	5124830147
Site ID:	TXSP1220199114
Secondary ID:	Not reported
Cross Street:	7114 N. LAMAR, AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

AC113 **HUNTSMAN PETROCHEMICAL CORP. - AUSTIN LABORATORIES** **TSCA** **1007089087**
Target Property **7114 NORTH LAMAR BOULEVARD** **N/A**
AUSTIN, TX 78752

Site 7 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

AC114 Target Property | **HUNTSMAN CORP**
7114 N. LAMAR
AUSTIN, TX | **TX SPILLS 90** | **S112321108**
N/A

Site 8 of 43 in cluster AC

Actual: 727 ft.
Focus Map: 6

Spills:

Status:	Not reported
Contact Name:	HUNTSMAN CORP
Contact Phone:	5124830178
Site ID:	TXSP110719945
Secondary ID:	Not reported
Cross Street:	7114 N. LAMAR, AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

AC115 Target Property | **7114 N. LAMAR, AUSTIN**
7114 N. LAMAR, AUSTIN
AUSTIN, TX | **TX SPILLS** | **S107012468**
N/A

Site 9 of 43 in cluster AC

Actual: 727 ft.
Focus Map: 6

SPILLS:

Name:	7114 N. LAMAR, AUSTIN
Address:	7114 N. LAMAR, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	11/07/1994
Seq Num:	5
Responsible Party Name:	HUNTSMAN CORP
Responsible Party Address:	7114 N. LAMAR BLVD.
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78752
Responsible Party Telephone:	5124830178
Substance:	METHY, MORPHLENE MON
Material Code:	9000
Media Affected:	Not reported
Permit Number:	NONE
District:	11
Origin:	001
Cause:	005
Basin Code:	0000
Notify Date:	Not reported
Adequate Clean:	007
Classification:	006
Basin Name:	COLORADO
Water Affected:	AIR RELEASE
Amnt Spilled:	UNK LBS
Amnt in Water:	NONE LBS
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	P. WINSBOROUGH

7114 N. LAMAR, AUSTIN (Continued) **S107012468**

Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC116 **HUNTSMAN PETROCHEMICAL CORP** **TX GCC** **S107525809**
Target **7114 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 10 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

GCC:

Name:	HUNTSMAN PETROCHEMICAL CORP
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Division:	REM
New Cases:	Not reported
File Number:	30688
Contamination Description:	VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation:	Not reported
Enforcement Status - Level Of Agency Response:	2B -
Enforcement Status - Site Activity Status:	6C -
Data Quality 1:	Not reported
Section 5236:	Not reported
Type:	INACTIVE GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2018
Agency:	TCEQ
Section:	CA
Year Deleted:	2002
Location:	Not reported
Data Quality 2:	Not reported

Name:	HUNTSMAN PETROCHEMICAL CORP
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Division:	RMD
New Cases:	Not reported

HUNTSMAN PETROCHEMICAL CORP (Continued) **S107525809**

File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2008
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2012
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752

HUNTSMAN PETROCHEMICAL CORP (Continued) **S107525809**

Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2011
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2015
Agency: TCEQ
Section: Not reported
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP

HUNTSMAN PETROCHEMICAL CORP (Continued) **S107525809**

Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2013
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2016
Agency: TCEQ
Section: Not reported
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: RMD
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2007
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported

HUNTSMAN PETROCHEMICAL CORP (Continued) **S107525809**

Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: RMD
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: RMD
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: CA
Year Deleted: 2002
Location: Not reported
Data Quality 2: Not reported

Name: HUNTSMAN PETROCHEMICAL CORP
Address: 7114 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Division: REM
New Cases: Not reported
File Number: 30688
Contamination Description: VOLATILE ORGANICS, METALS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 2B -
Enforcement Status - Site Activity Status: -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2014
Agency: TCEQ

HUNTSMAN PETROCHEMICAL CORP (Continued) **S107525809**

Section:	CA
Year Deleted:	2002
Location:	Not reported
Data Quality 2:	Not reported

AC117 **AUSTIN LABORATORIES** **TX UST** **U001254873**
Target **7114 N LAMAR BLVD** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78752**

Site 11 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

UST:

Name:	AUSTIN LABORATORIES
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787522310
AI Number:	20048
Facility Type:	UNKNOWN
Facility Begin Date:	09/10/1986
Facility Status:	INACTIVE
Additional ID:	495447012002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	GUY CRAWFORD,
Contact Organization Name:	AUSTIN LABORATORIES
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124830074
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	W H BRADER,GEN MGR RESEARCH
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600632848
Owner Last Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported

AUSTIN LABORATORIES (Continued) **U001254873**

Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	570026052002006
Additional ID:	495447012002075
AI Number:	20048
Owner Effective Begin Date:	08/21/2006
State Tax ID:	15815945181
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	51659
Facility ID:	57152
Ai Number:	20048
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/21/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

AUSTIN LABORATORIES (Continued) **U001254873**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/06/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	67011
UST ID:	51659
AI Number:	20048
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

AUSTIN LABORATORIES (Continued) **U001254873**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	51662
Facility ID:	57152
Ai Number:	20048
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

AUSTIN LABORATORIES (Continued) **U001254873**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/06/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	67014
UST ID:	51662
AI Number:	20048
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951

AUSTIN LABORATORIES (Continued) **U001254873**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	51661
Facility ID:	57152
Ai Number:	20048
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	12/31/1966
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

AUSTIN LABORATORIES (Continued) **U001254873**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/06/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	67013
UST ID:	51661
AI Number:	20048
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	51660
Facility ID:	57152

AUSTIN LABORATORIES (Continued) **U001254873**

Ai Number:	20048
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	12/31/1966
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/06/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	67012

AUSTIN LABORATORIES (Continued) **U001254873**

UST ID:	51660
AI Number:	20048
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Contact Mailing Address (Delivery):	PO BOX 847
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PORT NECHES, TX 77651 0847
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	57152
Additional ID:	495447012002075
Princ ID:	570026052002006
AI Number:	20048
Facility Name:	AUSTIN LABORATORIES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported

AUSTIN LABORATORIES (Continued) **U001254873**

Contact Name/Title: STEVEN M BARRE/

HIST UST AUSTIN:

Name:	TEXACO CHEMICAL CO
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0251
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AC118 **ERNS** **96324887**
Target Property **7114 N. LAMAR BL.** **N/A**
AUSTIN, TX 78752

Site 12 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC119 **ERNS** **9039904**
Target Property **7114 NORTH LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 13 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC120 **HUNTSMAN PETROCHEMICAL CORPORATION** **RMP** **1011827907**
Target Property **7114 NORTH LAMAR BOULEVARD** **N/A**
AUSTIN, TX 78752

Site 14 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

RMP:

Facility ID:	9699
Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Address:	7114 NORTH LAMAR BOULEVARD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752
LEPC city:	Travis County LEPC
Facility decimal latitude:	30.342778

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

Facility decimal longitude:	-97.716667
Is facility in county box:	T
LatLong method:	I1
LatLong description:	CE
Home page web address:	http:\\\\www.huntsman.com
Facility telephone:	Not reported
Facility email:	richard_bennett@huntsman.com
Facility DUNS #:	39423611
Parents name:	Huntsman Corporation
Partners name:	Not reported
Parents DUNS #:	834697377
Partners DUNS #:	0
Operators name:	Huntsman Petrochemical Corporation
Operators telephone:	5124830981
Operators address:	7114 North Lamar Boulevard
Operators City,St,Zip:	Austin, TX 78752
RMP implementation contact:	David W. Hester
RMP contact title:	Director - Chemicals R & D
Emergency contact:	Richard H. Bennett
Emergency contact title:	Manager - EH&S
Emergency contact telephone:	5124830934
24 hour emergency telephone:	5124596543
Emergency contact ext/pin #:	Not reported
Number of full time employees:	253
EPA ID:	TXD041470980
Facility ID provided by CEPPO:	100000120157
Is facility covered by OSHA PSM:	T
Is facility covered by EPCRA 302:	F
Is fac. covered by CAA Title V 112(2):	F
Clean air op. permit/State ID:	Not reported
Last safety insp. dat:	1997-12-17 00:00:00
Inspected by:	Fire Department
Is it OSHA approved with star/merit ranking:	True
Will RMP involve predictive filing:	False
Submission type:	First Time
RMP description:	Not reported
Facility has no accident hist. recs:	False
Foreign owner's address:	Not reported
Foreign owner's zip:	Not reported
Foreign owner's country:	Not reported
Claim # of employees as CBI:	False
Date RMP accepted by EPA:	1999-07-13 00:00:00
Date of error Report:	Not reported
Date RMP received:	1999-06-22 00:00:00
Does RMP contain graphics files:	False
Does RMP contain attachments:	False
Was certification letter received:	True
RMP submission method:	RMP*Submit
Does RMP contain CBI substantiation:	False
Does RMP contain electronic waiver:	False
Date RMP postmarked:	1999-06-18 00:00:00
Is RMP complete:	True
Date of de-registration:	2003-04-22 00:00:00
Date de-registration is effective:	2002-10-25 00:00:00
Aniversary date:	2004-06-18 00:00:00
Does RMP contain CBI data:	False
Does RMP contain unsanitized CBI version:	False

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

RMP version #:	1.1.7
FRS latitude:	30.34273
FRS longitude:	-97.719220000000007
FRS Description:	FACILITY CENTROID
FRS Method:	INTERPOLATION-MAP

Accident History:

Accident History ID:	1015
facid:	9699
Accident Date:	1998-10-28 00:00:00
Accident Time:	1120
NAICS code:	32511
Accident release duration:	00001
Release Event:	Spill
Release Source:	Pump
Wind speed:	3.5
Wind speed units:	b
Wind direction:	SE
Temperature:	77
Stability class:	D
Precipitation was present:	False
Weather was unknown:	False
Num. of on-site workers killed:	0
Num. of responders killed:	0
Num. of public deaths:	0
Num. of on-site workers injured:	1
Num. of responders injured:	0
Num. of public injured:	0
Property damage in dollars:	0
Num. of on-site deaths:	0
Num. of hospitalizations:	0
Num. of other medical treatments:	0
Num. of evacuated:	0
Num. of sheltered in place:	0
Off-site property damage in dollars:	0
Environmental damage:	Not reported
Initiating event:	b
Contributing factor:	Improper procedure, Unsuitable equipment
Were offsite responders notified:	No, not notified
Changes Made:	Improved equipment, Revised operating procedure
Record contains CBI data:	False

Accident Chemicals:

Chemical released:	Ammonia (anhydrous)
Quantity of chemical released in pounds:	6
Percent weight of chemical released:	Not reported

Emergency Responses:

ER plan most recent review date:	1998-08-01 00:00:00
ER plan most recent employee training date:	1999-04-14 00:00:00
Local agency coordinating ER plan:	Austin Fire Department
Telephone of the coordinating local agency:	5124488331
Federal regulation:	True
OSHA 1910 120:	True
SPCC:	True
RCRA:	True
OPA 90:	False

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

EPCRA:	True
Other Regulations:	Not reported

Processes:

Process ID:	12043
Optional facility description:	PDU/Tank Farm & PDA areas
Program level:	3
Record contains CBI data:	False

Process NAICS:

NAICS code description:	Petrochemical Manufacturing

Prevention Program 3:

Safety review date:	1999-04-27 00:00:00
Most recent PHA date:	1999-04-27 00:00:00
Process Hazard Analysis:	HAZOP
Expected PHA changes completion date:	2000-12-31 00:00:00
Major Hazard:	Toxic Release, Explosion, Run away reaction, Polymerization, Overpressurization, Overfilling, Contamination, Equipment failure, Cooling loss
Process Control:	Vents, Relief valves, Check valves, Scrubbers, Flares, Manual shutoffs, Automatic shutoffs, Interlocks, Alarms, Emergency air supply, Emergency power, Backup pump, Grounding equipment, Rupture disks, Excess flow device, Purge system
Mitigation Systems:	Dikes, Deluge system
Monitoring/Detection:	Process area detector, Perimeter monitors
Changes since the last process hazard analysis:	No changes since last PHA
Most recent review of op. procedures:	1999-03-15 00:00:00
Most recent training progs review/update:	1998-05-15 00:00:00
Training:	Classroom, computer-based training
Competency testing:	Written test, Demonstration
Most recent maintenance review date:	1998-07-09 00:00:00
Most recent equipment inspection date:	1998-07-09 00:00:00
Equipment tested:	storage tank
Most recent changes by mgmt:	1999-03-25 00:00:00
Date of most recent review/update:	1998-12-29 00:00:00
Date of pre-start review:	1998-08-28 00:00:00
Most recent compliance audit date:	1998-02-16 00:00:00
Expected date of audit completion:	2000-12-31 00:00:00
Most recent incident investigation:	1998-10-30 00:00:00
Expected date of investigation changes:	1999-12-01 00:00:00
Date of participation plan review:	1998-07-07 00:00:00
Date of hot work permit review:	1999-04-09 00:00:00
Date of contractor safety review:	1997-03-21 00:00:00
Date of contractor safety eval. review:	1998-06-01 00:00:00
Record has CBI data:	False

Safety review date:	1996-11-09 00:00:00
Most recent PHA date:	1996-09-23 00:00:00
Process Hazard Analysis:	HAZOP
Expected PHA changes completion date:	1999-12-31 00:00:00
Major Hazard:	Toxic Release, Fire, Explosion, Run away reaction, Polymerization, Overpressurization, Overfilling, Contamination, Equipment failure, Cooling loss
Process Control:	Vents, Relief valves, Check valves, Scrubbers, Flares, Manual shutoffs, Automatic shutoffs, Interlocks, Alarms, Emergency air supply, Grounding equipment, Rupture disks, Excess flow device, Purge

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

	system
Mitigation Systems:	Deluge system, fire monitors, gas detectors
Monitoring/Detection:	Process area detector, Perimeter monitors
Changes since the last process hazard analysis:	Procedure revisions
Most recent review of op. procedures:	1998-08-26 00:00:00
Most recent training progs review/update:	1998-05-15 00:00:00
Training:	Classroom, computer-based training
Competency testing:	Written test, Demonstration, computer-based training
Most recent maintenance review date:	1998-07-09 00:00:00
Most recent equipment inspection date:	1998-07-09 00:00:00
Equipment tested:	storage tank
Most recent changes by mgmt:	1996-10-04 00:00:00
Date of most recent review/update:	1998-12-29 00:00:00
Date of pre-start review:	Not reported
Most recent compliance audit date:	1998-02-16 00:00:00
Expected date of audit completion:	2000-12-31 00:00:00
Most recent incident investigation:	1998-09-07 00:00:00
Expected date of investigation changes:	1999-12-31 00:00:00
Date of participation plan review:	1998-07-07 00:00:00
Date of hot work permit review:	1999-04-09 00:00:00
Date of contractor safety review:	1997-03-21 00:00:00
Date of contractor safety eval. review:	1998-06-01 00:00:00
Record has CBI data:	False

Process Chemicals:

Chemical name:	Acrylonitrile [2-Propenenitrile]
Process chemical qty in 100s lbs:	100000
Chemical name:	Ammonia (anhydrous)
Process chemical qty in 100s lbs:	110000
Chemical name:	Ethylene oxide [Oxirane]
Process chemical qty in 100s lbs:	370000
Chemical name:	Formaldehyde (solution)
Process chemical qty in 100s lbs:	42000
Chemical name:	Propylene oxide [Oxirane, methyl-]
Process chemical qty in 100s lbs:	120000
Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

Toxics Alt Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's OCA Guidance Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Deluge systems, fire monitors, leak detectors

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

Toxics Alt Releases:

Percent weight of chemical:	Not reported
Physical state:	a
Analytical basic:	EPA's RMP Guidance for Ammonia Refrigeration Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Deluge systems, Excess flow valve, fire monitors, leak detectors

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

Toxics Alt Releases:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's OCA Guidance Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Deluge systems, fire monitors, leak detectors

Toxics Worst Case:

Percent weight of chemical:	Not reported
Physical state:	c
Analytical basic:	EPA's OCA Guidance Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	10
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	1.5

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1011827907**

Stability class:	F
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

Toxics Alt Releases:

Percent weight of chemical:	55
Physical state:	b
Analytical basic:	EPA's OCA Guidance Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	fire monitors

Chemical name:	Public OCA Chemical
Process chemical qty in 100s lbs:	0

Toxics Alt Releases:

Percent weight of chemical:	Not reported
Physical state:	b
Analytical basic:	EPA's OCA Guidance Reference Tables or Equations
Scenario:	Not reported
Quantity released in pounds:	Not reported
Release duration in minutes:	Not reported
Release rate in pounds per second:	Not reported
Wind speed in meters/second:	3
Stability class:	D
Topography:	a
Distance to endpoint in miles:	Not reported
Residential population:	Not reported
Public receptors:	Not reported
Environmental receptors:	Not reported
Passive mitigation:	Not reported
Active mitigation:	Deluge systems, fire monitors, leak detectors

AC121 Target Property | **7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN**
7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN
AUSTIN, TX | **TX SPILLS** | **S106997173**
N/A

Site 15 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

SPILLS:

Name:	7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN
Address:	7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	03/19/1991
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL
Responsible Party Address:	PO OBX 15730
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78761
Responsible Party Telephone:	5124596543
Substance:	USED OIL
Material Code:	1080
Media Affected:	YES
Permit Number:	30688
District:	14
Origin:	005
Cause:	003
Basin Code:	1430
Notify Date:	Not reported
Adequate Clean:	007
Classification:	003
Basin Name:	COLORADO
Water Affected:	GROUNDWATER CONTAMINATION
Amnt Spilled:	50 GAL
Amnt in Water:	50 GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	TWC
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	S. JONES
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported

7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN (Continued) **S106997173**

Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC122 **TEXACO CHEMICAL COMPANY** **FTTS** **1010010576**
Target **7114 N. LAMAR BOULEVARD** **N/A**
Property **AUSTIN, TX 78752**

Site 16 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

FTTS INSP:

Inspection Number:	19870324NEIC 1
Region:	11
Inspection Date:	03/24/87
Inspector:	NEIC
Violation occurred:	No
Investigation Type:	Section 5 Failure to Notify
Investigation Reason:	Neutral Scheme, Headquarters
Legislation Code:	TSCA
Facility Function:	Manufacturer

AC123 **7114 N.LAMAR, AUSTIN** **TX SPILLS** **S106994154**
Target **7114 N.LAMAR, AUSTIN** **N/A**
Property **AUSTIN, TX**

Site 17 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

SPILLS:

Name:	7114 N.LAMAR, AUSTIN
Address:	7114 N.LAMAR, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	05/08/1990
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL CO
Responsible Party Address:	PO BOX 15730
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78761
Responsible Party Telephone:	5124596543
Substance:	PROPYLENE OXIDE
Material Code:	2085
Media Affected:	NO
Permit Number:	30688
District:	14
Origin:	001
Cause:	002
Basin Code:	1428
Notify Date:	Not reported

7114 N.LAMAR, AUSTIN (Continued) **S106994154**

Adequate Clean:	001
Classification:	005
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	5 GAL
Amnt in Water:	NONE
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	C. FINCH
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC124 **ERNS** **2000538678**
Target Property **7114 NORTH LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 18 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC125 **HUNTSMAN PETROCHEMICAL** **FINDS** **1011318972**
Target **7114 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 19 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

FINDS:
Registry ID: 110070752608

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110034407979

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AC126 **ERNS** **97382526**
Target **7114 NORTH LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 20 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC127 **DOWTHERM VAPOR GENERATOR - JCCO NO HK-K** **TX AIRS** **S121946831**
Target **7114 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 21 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

AIRS:

Name:	DOWTHERM VAPOR GENERATOR - JCCO NO HK-K
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	2839
Regulated Id:	RN100726215
Permit Type:	CONSTRUCT
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN604173187
Company Name:	TEXACO CHEMICAL COMPANY

DOWTHERM VAPOR GENERATOR - JCCO NO HK-K (Continued) **S121946831**

Physical Location Desc:	7114 N LAMAR BLVD AUSTIN TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

AC128 **ERNS** **8851852**
Target Property **7114 N LAMAR ST**
AUSTIN, TX **N/A**

Site 22 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC129 **STEAM GENERATOR - JCCO NO HK-6** **TX AIRS** **S121946832**
Target Property **7114 N LAMAR BLVD**
AUSTIN, TX **N/A**

Site 23 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

AIRS:

Name:	STEAM GENERATOR - JCCO NO HK-6
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	2838
Regulated Id:	RN100726215
Permit Type:	CONSTRUCT
Permit Status:	CANCELLED
Permit Issued Date:	01/01/1900
Expiration Date:	12/31/3000
Customer Id:	CN604173187
Company Name:	TEXACO CHEMICAL COMPANY
Physical Location Desc:	7114 N LAMAR BLVD AUSTIN TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.342700
Long Dec Coord Num:	-97.7166

AC130 **ERNS** **95295771**
Target Property **7114 N LAMAR BLVD** **N/A**
AUSTIN, TX

Site 24 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC131 **TEXACO CHEMICAL CO** **TX SPILLS 90** **S112308621**
Target Property **7114 N.LAMAR** **N/A**
AUSTIN, TX

Site 25 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Spills:

Status:	Not reported
Contact Name:	TEXACO CHEMICAL CO
Contact Phone:	5124596543
Site ID:	TXSP050819908
Secondary ID:	Not reported
Cross Street:	7114 N.LAMAR, AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

AC132 **TEXACO CHEMICAL** **TX SPILLS 90** **S112305129**
Target Property **7114 NORTH LAMAR (SOUTH EDGE OF LOT)** **N/A**
AUSTIN, TX

Site 26 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Spills:

Status:	Not reported
Contact Name:	TEXACO CHEMICAL
Contact Phone:	5124596543
Site ID:	TXSP031919917
Secondary ID:	Not reported
Cross Street:	7114 NORTH LAMAR (SOUTH EDGE OF LOT), AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

AC133 **ERNS** **94257490**
Target Property **7114 N LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 27 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AC134 **HUNTSMAN PETROCHEMICAL** **SEMS-ARCHIVE** **1000144736**
Target Property **7114 N LAMAR BLVD** **CORRACTS** **TXD041470980**
AUSTIN, TX 78752 **RCRA-TSDF**
RCRA NonGen / NLR

Site 28 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

SEMS Archive:

Site ID:	0601908
EPA ID:	TXD041470980
Name:	TEXACO CHEMICAL CO AUSTIN LABS
Address:	7114 N LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752
Cong District:	10
FIPS Code:	48453
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	06
Site ID:	0601908
EPA ID:	TXD041470980
Site Name:	TEXACO CHEMICAL CO AUSTIN LABS
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1995-09-07 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	06
Site ID:	0601908
EPA ID:	TXD041470980
Site Name:	TEXACO CHEMICAL CO AUSTIN LABS
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1983-07-01 04:00:00
Finish Date:	1983-07-01 04:00:00

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0601908
EPA ID:	TXD041470980
Site Name:	TEXACO CHEMICAL CO AUSTIN LABS
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1984-01-01 05:00:00
Finish Date:	1984-01-01 05:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0601908
EPA ID:	TXD041470980
Site Name:	TEXACO CHEMICAL CO AUSTIN LABS
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1984-01-01 05:00:00
Finish Date:	1984-01-01 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

CORRACTS:

Name:	HUNTSMAN PETROCHEMICAL
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
EPA ID:	TXD041470980
Area Name:	ENTIRE FACILITY
Corrective Action:	CA PRIORITIZATION-LOW CA PRIORITY
Actual Date:	19920805
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

Name:	HUNTSMAN PETROCHEMICAL
Address:	7114 N LAMAR BLVD
Address 2:	Not reported
EPA ID:	TXD041470980
Area Name:	ENTIRE FACILITY
Corrective Action:	CA PRIORITIZATION-LOW CA PRIORITY
Actual Date:	19980911
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Surface Water Release Indicator: Not reported

RCRA TSDF:

Treatment Storage and Disposal Type:	Storage
Full Enforcement Universe:	Not reported
Corrective Action Workload Universe:	No
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Storage
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
Operating TSDF Universe:	Not reported
Commercial TSD Indicator:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	Yes

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

RCRA Listings:

Date Form Received by Agency:	20190909
Handler Name:	Huntsman Petrochemical
Handler Address:	7114 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78752-2310
EPA ID:	TXD041470980
Contact Name:	RAVINDER JOSEPH
Contact Address:	8600 GOSLING RD
Contact City,State,Zip:	THE WOODLANDS, TX 77381-4845
Contact Telephone:	512-483-0178
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	8600 GOSLING RD
Mailing City,State,Zip:	THE WOODLANDS, TX 77381-4845
Owner Name:	Huntsman Petrochemical Corporation
Owner Type:	Private

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Operator Name:	Huntsman Petrochemical Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	Low
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190925
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D013
Waste Description:	Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)
Waste Code:	D015
Waste Description:	Toxaphene (C10 H10 Cl8, Technical Chlorinated Camphene, 67-69 Percent Chlorine)
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D019
Waste Description:	Carbon Tetrachloride
Waste Code:	D020
Waste Description:	Chlordane
Waste Code:	D022
Waste Description:	Chloroform
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: D038
Waste Description: Pyridine

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D041
Waste Description: 2,4,5-Trichlorophenol

Waste Code: D042
Waste Description: 2,4,6-Trichlorophenol

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P003
Waste Description: 2-Propenal (Or) Acrolein

Waste Code: P005
Waste Description: 2-Propen-1-Ol (Or) Allyl Alcohol

Waste Code: P010
Waste Description: Arsenic Acid H3aso4

Waste Code: P011
Waste Description: Arsenic Oxide As2o5 (Or) Arsenic Pentoxide

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P028
Waste Description: Benzene, (Chloromethyl)- (Or) Benzyl Chloride

Waste Code: P029
Waste Description: Copper Cyanide (Or) Copper Cyanide Cu(Cn)

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P048
Waste Description: 2,4-Dinitrophenol (Or) Phenol, 2,4-Dinitro-

Waste Code: P068
Waste Description: Hydrazine, Methyl- (Or) Methyl Hydrazine

Waste Code: P082
Waste Description: Methanimine, N-Methyl-N-Nitroso- (Or) N-Nitrosodimethylamine

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P105
Waste Description: Sodium Azide

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: P121
Waste Description: Zinc Cyanide (Or) Zinc Cyanide Zn(Cn)2

Waste Code: U001
Waste Description: Acetaldehyde (I) (Or) Ethanal (I)

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U003
Waste Description: Acetonitrile (I,T)

Waste Code: U004
Waste Description: Acetophenone (Or) Ethanone, 1-Phenyl-

Waste Code: U005
Waste Description: 2-Acetylaminofluorene (Or) Acetamide, N-9h-Fluoren-2-Yl

Waste Code: U006
Waste Description: Acetyl Chloride (C,R,T)

Waste Code: U007
Waste Description: 2-Propenamide (Or) Acrylamide

Waste Code: U008
Waste Description: 2-Propenoic Acid (I) (Or) Acrylic Acid (I)

Waste Code: U009
Waste Description: 2-Propenenitrile (Or) Acrylonitrile

Waste Code: U010
Waste Description: Azirino [2',3':3,4]Pyrrolo[1,2-A]Indole-4,7-Dione, 6-Amino-8-[[(Aminocarbonyl)Oxy]Methyl]-1,1a,2,8,8a,8b-Hexahydro-8a-Methoxy-5-Methyl-, [1as-(1aalpha, 8beta, 8aalpha, 8balpha)]- (Or) Mitomycin C

Waste Code: U011
Waste Description: 1h-1,2,4-Triazol-3-Amine (Or) Amitrole

Waste Code: U012
Waste Description: Aniline (I,T) (Or) Benzenamine (I,T)

Waste Code: U014
Waste Description: Auramine (Or) Benzenamine, 4,4'-Carbonimidoylbis[N,N-Dimethyl-

Waste Code: U015
Waste Description: Azaserine (Or) L-Serine, Diazoacetate (Ester)

Waste Code: U016
Waste Description: Benz[C]Acridine

Waste Code: U017
Waste Description: Benzal Chloride (Or) Benzene, (Dichloromethyl)-

Waste Code: U018
Waste Description: Benz[A]Anthracene

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U020
Waste Description: Benzenesulfonic Acid Chloride (C,R) (Or) Benzenesulfonyl Chloride (C,R)

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U021
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine (Or) Benzidine

Waste Code: U022
Waste Description: Benzo[A]Pyrene

Waste Code: U023
Waste Description: Benzene, (Trichloromethyl)- (Or) Benzotrichloride (C,R,T)

Waste Code: U024
Waste Description: Dichloromethoxy Ethane (Or) Ethane,
1,1'-[Methylenebis(Oxy)]Bis[2-Chloro-

Waste Code: U025
Waste Description: Dichloroethyl Ether (Or) Ethane, 1,1'-Oxybis[2-Chloro-

Waste Code: U026
Waste Description: Chlornaphazin (Or) Naphthalenamine, N,N'-Bis(2-Chloroethyl)-

Waste Code: U027
Waste Description: Dichloroisopropyl Ether (Or) Propane, 2,2'-Oxybis[2-Chloro-

Waste Code: U028
Waste Description: 1,2-Benzenedicarboxylic Acid, Bis(2-Ethylhexyl) Ester (Or)
Diethylhexyl Phthalate

Waste Code: U029
Waste Description: Methane, Bromo- (Or) Methyl Bromide

Waste Code: U030
Waste Description: 4-Bromophenyl Phenyl Ether (Or) Benzene, 1-Bromo-4-Phenoxy-

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U032
Waste Description: Calcium Chromate (Or) Chromic Acid H2cro4, Calcium Salt

Waste Code: U033
Waste Description: Carbon Oxyfluoride (R,T) (Or) Carbonic Difluoride

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U036
Waste Description: 4,7-Methano-1h-Indene,
1,2,4,5,6,7,8,8-Octachloro-2,3,3a,4,7,7a-Hexahydro- (Or) Chlordane,
Alpha & Gamma Isomers

Waste Code: U037
Waste Description: Benzene, Chloro- (Or) Chlorobenzene

Waste Code: U038
Waste Description: Benzeneacetic Acid, 4-Chloro-Alpha-(4-Chlorophenyl)-Alpha-Hydroxy-,

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Ethyl Ester (Or) Chlorobenzilate

Waste Code: U039
Waste Description: P-Chloro-M-Cresol (Or) Phenol, 4-Chloro-3-Methyl-

Waste Code: U041
Waste Description: Epichlorohydrin (Or) Oxirane, (Chloromethyl)-

Waste Code: U042
Waste Description: 2-Chloroethyl Vinyl Ether (Or) Ethene, (2-Chloroethoxy)-

Waste Code: U043
Waste Description: Ethene, Chloro- (Or) Vinyl Chloride

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U045
Waste Description: Methane, Chloro- (I,T) (Or) Methyl Chloride (I,T)

Waste Code: U046
Waste Description: Chloromethyl Methyl Ether (Or) Methane, Chloromethoxy-

Waste Code: U047
Waste Description: Beta-Chloronaphthalene (Or) Naphthalene, 2-Chloro-

Waste Code: U048
Waste Description: O-Chlorophenol (Or) Phenol, 2-Chloro-

Waste Code: U049
Waste Description: 4-Chloro-O-Toluidine, Hydrochloride (Or) Benzenamine, 4-Chloro-2-Methyl-, Hydrochloride

Waste Code: U050
Waste Description: Chrysene

Waste Code: U051
Waste Description: Creosote

Waste Code: U052
Waste Description: Cresol (Cresylic Acid) (Or) Phenol, Methyl-

Waste Code: U053
Waste Description: 2-Butenal (Or) Crotonaldehyde

Waste Code: U055
Waste Description: Benzene, (1-Methylethyl)- (I) (Or) Cumene (I)

Waste Code: U056
Waste Description: Benzene, Hexahydro- (I) (Or) Cyclohexane (I)

Waste Code: U057
Waste Description: Cyclohexanone (I)

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U059
Waste Description: 5,12-Naphthacenedione, 8-Acetyl-10-[(3-Amino-2,3,6-Trideoxy)-Alpha-L-Lyxo-Hexopyranosyl)Oxy]-7,8,9,10-Tetrahydro-6,8,11-Trihydroxy-1-Methoxy-, (8s-Cis)- (Or) Daunomycin

Waste Code: U060
Waste Description: Benzene, 1,1'-(2,2-Dichloroethylidene)Bis[4-Chloro- (Or) Ddd

Waste Code: U061
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Chloro- (Or) Ddt

Waste Code: U062
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3-Dichloro-2-Propenyl) Ester (Or) Diallate

Waste Code: U063
Waste Description: Dibenz[A,H]Anthracene

Waste Code: U064
Waste Description: Benzo[Rst]Pentaphene (Or) Dibenzo[A,I]Pyrene

Waste Code: U066
Waste Description: 1,2-Dibromo-3-Chloropropane (Or) Propane, 1,2-Dibromo-3-Chloro-

Waste Code: U067
Waste Description: Ethane, 1,2-Dibromo- (Or) Ethylene Dibromide

Waste Code: U068
Waste Description: Methane, Dibromo- (Or) Methylene Bromide

Waste Code: U069
Waste Description: 1,2-Benzenedicarboxylic Acid, Dibutyl Ester (Or) Dibutyl Phthalate

Waste Code: U070
Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

Waste Code: U071
Waste Description: Benzene, 1,3-Dichloro- (Or) M-Dichlorobenzene

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U073
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dichloro- (Or) 3,3'-Dichlorobenzidine

Waste Code: U074
Waste Description: 1,4-Dichloro-2-Butene (I,T) (Or) 2-Butene, 1,4-Dichloro- (I,T)

Waste Code: U075
Waste Description: Dichlorodifluoromethane (Or) Methane, Dichlorodifluoro-

Waste Code: U076
Waste Description: Ethane, 1,1-Dichloro- (Or) Ethylidene Dichloride

Waste Code: U077

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Description: Ethane, 1,2-Dichloro- (Or) Ethylene Dichloride

Waste Code: U078
Waste Description: 1,1-Dichloroethylene (Or) Ethene, 1,1-Dichloro-

Waste Code: U079
Waste Description: 1,2-Dichloroethylene (Or) Ethene, 1,2-Dichloro-,(E)-

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U081
Waste Description: 2,4-Dichlorophenol (Or) Phenol, 2,4-Dichloro-

Waste Code: U082
Waste Description: 2,6-Dichlorophenol (Or) Phenol, 2,6-Dichloro-

Waste Code: U083
Waste Description: Propane, 1,2-Dichloro- (Or) Propylene Dichloride

Waste Code: U084
Waste Description: 1,3-Dichloropropene (Or) 1-Propene, 1,3-Dichloro-

Waste Code: U085
Waste Description: 1,2:3,4-Diepoxybutane (I,T) (Or) 2,2'-Bioxirane

Waste Code: U086
Waste Description: Hydrazine, 1,2-Diethyl- (Or) N,N'-Diethylhydrazine

Waste Code: U087
Waste Description: O,O-Diethyl S-Methyl Dithiophosphate (Or) Phosphorodithioic Acid, O,O-Diethyl S-Methyl Ester

Waste Code: U088
Waste Description: 1,2-Benzenedicarboxylic Acid, Diethyl Ester (Or) Diethyl Phthalate

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4'-(1,2-Diethyl-1,2-Ethenediyl)Bis, (E)-

Waste Code: U090
Waste Description: 1,3-Benzodioxole, 5-Propyl- (Or) Dihydrosafrole

Waste Code: U091
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethoxy- (Or) 3,3'-Dimethoxybenzidine

Waste Code: U092
Waste Description: Dimethylamine (I) (Or) Methanamine, N-Methyl- (I)

Waste Code: U093
Waste Description: Benzenamine, N,N-Dimethyl-4-(Phenylazo)- (Or) P-Dimethylaminoazobenzene

Waste Code: U094
Waste Description: 7,12-Dimethylbenz[A]Anthracene (Or) Benz[A]Anthracene, 7,12-Dimethyl-

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U095
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethyl- (Or) 3,3'-Dimethylbenzidine

Waste Code: U096
Waste Description: Alpha,Alpha-Dimethylbenzylhydroperoxide (R) (Or) Hydroperoxide, 1-Methyl-1-Phenylethyl- (R)

Waste Code: U097
Waste Description: Carbamic Chloride, Dimethyl- (Or) Dimethylcarbamoyl Chloride

Waste Code: U098
Waste Description: 1,1-Dimethylhydrazine (Or) Hydrazine, 1,1-Dimethyl-

Waste Code: U099
Waste Description: 1,2-Dimethylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U101
Waste Description: 2,4-Dimethylphenol (Or) Phenol, 2,4-Dimethyl-

Waste Code: U102
Waste Description: 1,2-Benzenedicarboxylic Acid, Dimethyl Ester (Or) Dimethyl Phthalate

Waste Code: U103
Waste Description: Dimethyl Sulfate (Or) Sulfuric Acid, Dimethyl Ester

Waste Code: U105
Waste Description: 2,4-Dinitrotoluene (Or) Benzene, 1-Methyl-2,4-Dinitro-

Waste Code: U106
Waste Description: 2,6-Dinitrotoluene (Or) Benzene, 2-Methyl-1,3-Dinitro-

Waste Code: U107
Waste Description: 1,2-Benzenedicarboxylic Acid, Dioctyl Ester (Or) Di-N-Octyl Phthalate

Waste Code: U108
Waste Description: 1,4-Diethyleneoxide (Or) 1,4-Dioxane

Waste Code: U109
Waste Description: 1,2-Diphenylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U110
Waste Description: 1-Propanimine, N-Propyl-(I) (Or) Dipropylamine (I)

Waste Code: U111
Waste Description: 1-Propanamine, N-Nitroso-N-Propyl- (Or) Di-N-Propylnitrosamine

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U113
Waste Description: 2-Propenoic Acid, Ethyl Ester (I) (Or) Ethyl Acrylate (I)

Waste Code: U114
Waste Description: Carbamodithioic Acid, 1,2-Ethanediylbis-, Salts & Esters (Or) Ethylenebisdithiocarbamic Acid, Salts & Esters

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U115
Waste Description: Ethylene Oxide (I,T) (Or) Oxirane (I,T)

Waste Code: U116
Waste Description: 2-Imidazolidinethione (Or) Ethylenethiourea

Waste Code: U117
Waste Description: Ethane, 1,1'-Oxybis-(I) (Or) Ethyl Ether (I)

Waste Code: U118
Waste Description: 2-Propenoic Acid, 2-Methyl-, Ethyl Ester (Or) Ethyl Methacrylate

Waste Code: U119
Waste Description: Ethyl Methanesulfonate (Or) Methanesulfonic Acid, Ethyl Ester

Waste Code: U120
Waste Description: Fluoranthene

Waste Code: U121
Waste Description: Methane, Trichlorofluoro- (Or) Trichloromonofluoromethane

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U123
Waste Description: Formic Acid (C,T)

Waste Code: U124
Waste Description: Furan (I) (Or) Furfuran (I)

Waste Code: U125
Waste Description: 2-Furancarboxaldehyde (I) (Or) Furfural (I)

Waste Code: U126
Waste Description: Glycidylaldehyde (Or) Oxiranecarboxyaldehyde

Waste Code: U127
Waste Description: Benzene, Hexachloro- (Or) Hexachlorobenzene

Waste Code: U128
Waste Description: 1,3-Butadiene, 1,1,2,3,4,4-Hexachloro- (Or) Hexachlorobutadiene

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U130
Waste Description: 1,3-Cyclopentadiene, 1,2,3,4,5,5-Hexachloro- (Or) Hexachlorocyclopentadiene

Waste Code: U131
Waste Description: Ethane, Hexachloro- (Or) Hexachloroethane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2'-Methylenebis[3,4,6-Trichloro-

Waste Code: U133

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Description: Hydrazine (R,T)

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Waste Code: U135
Waste Description: Hydrogen Sulfide (Or) Hydrogen Sulfide H2s

Waste Code: U136
Waste Description: Arsinic Acid, Dimethyl- (Or) Cacodylic Acid

Waste Code: U137
Waste Description: Indeno[1,2,3-Cd]Pyrene

Waste Code: U138
Waste Description: Methane, Iodo- (Or) Methyl Iodide

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U141
Waste Description: 1,3-Benzodioxole, 5-(1-Propenyl)- (Or) Isosafrole

Waste Code: U142
Waste Description: 1,3,4-Metheno-2h-Cyclobuta[Cd]Pentalen-2-One,
1,1a,3,3a,4,5,5,5a,5b,6-Decachlorooctahydro- (Or) Kepone

Waste Code: U143
Waste Description: 2-Butenoic Acid, 2-Methyl-,
7-[[2,3-Dihydroxy-2-(1-Methoxyethyl)-3-Methyl-1-Oxobutoxy]Methyl]-2,3,
5,7a-Tetrahydro-1h-Pyrrolizin-1-Yl Ester, [1s-[1alpha(Z), 7(2s*,3r*),
7aalpha]]- (Or) Lasiocarpine

Waste Code: U144
Waste Description: Acetic Acid, Lead(2+) Salt (Or) Lead Acetate

Waste Code: U145
Waste Description: Lead Phosphate (Or) Phosphoric Acid, Lead(2+) Salt (2:3)

Waste Code: U146
Waste Description: Lead Subacetate (Or) Lead, Bis(Acetato-O)Tetrahydroxytri-

Waste Code: U147
Waste Description: 2,5-Furandione (Or) Maleic Anhydride

Waste Code: U148
Waste Description: 3,6-Pyridazinedione, 1,2-Dihydro- (Or) Maleic Hydrazide

Waste Code: U149
Waste Description: Malononitrile (Or) Propanedinitrile

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U151
Waste Description: Mercury

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U152
Waste Description: 2-Propenenitrile, 2-Methyl- (I,T) (Or) Methacrylonitrile (I,T)

Waste Code: U153
Waste Description: Methanethiol (I,T) (Or) Thiomethanol (I,T)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U155
Waste Description: 1,2-Ethanediamine, N,N-Dimethyl-N'-2-Pyridinyl-N'-(2-Thienylmethyl)- (Or) Methapyrilene

Waste Code: U156
Waste Description: Carbonochloridic Acid, Methyl Ester, (I,T) (Or) Methyl Chlorocarbonate (I,T)

Waste Code: U157
Waste Description: 3-Methylcholanthrene (Or) Benz[J]Aceanthrylene, 1,2-Dihydro-3-Methyl-

Waste Code: U158
Waste Description: 4,4'-Methylenebis(2-Chloroaniline) (Or) Benzenamine, 4,4'-Methylenebis[2-Chloro-

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U162
Waste Description: 2-Propenoic Acid, 2-Methyl-, Methyl Ester (I,T) (Or) Methyl Methacrylate (I,T)

Waste Code: U163
Waste Description: Guanidine, N-Methyl-N'-Nitro-N-Nitroso- (Or) Mnng

Waste Code: U164
Waste Description: 4(1h)-Pyrimidinone, 2,3-Dihydro-6-Methyl-2-Thioxo- (Or) Methylthiouracil

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U166
Waste Description: 1,4-Naphthalenedione (Or) 1,4-Naphthoquinone

Waste Code: U167
Waste Description: 1-Napthalenamine (Or) Alpha-Naphthylamine

Waste Code: U168
Waste Description: 2-Napthalenamine (Or) Beta-Naphthylamine

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U169
Waste Description: Benzene, Nitro- (Or) Nitrobenzene (I,T)

Waste Code: U170
Waste Description: P-Nitrophenol (I,T) (Or) Phenol, 4-Nitro-

Waste Code: U171
Waste Description: 2-Nitropropane (I,T) (Or) Propane, 2-Nitro- (I,T)

Waste Code: U172
Waste Description: 1-Butanamine, N-Butyl-N-Nitroso- (Or) N-Nitrosodi-N-Butylamine

Waste Code: U173
Waste Description: Ethanol, 2,2'-(Nitrosoimino)Bis- (Or) N-Nitrosodiethanolamine

Waste Code: U174
Waste Description: Ethanamine, N-Ethyl-N-Nitroso- (Or) N-Nitrosodiethylamine

Waste Code: U176
Waste Description: N-Nitroso-N-Ethylurea (Or) Urea, N-Ethyl-N-Nitroso-

Waste Code: U177
Waste Description: N-Nitroso-N-Methylurea (Or) Urea, N-Methyl-N-Nitroso-

Waste Code: U178
Waste Description: Carbamic Acid, Methylnitroso-, Ethyl Ester (Or) N-Nitroso-N-Methylurethane

Waste Code: U179
Waste Description: N-Nitrosopiperidine (Or) Piperidine, 1-Nitroso-

Waste Code: U180
Waste Description: N-Nitrosopyrrolidine (Or) Pyrrolidine, 1-Nitroso-

Waste Code: U181
Waste Description: 5-Nitro-O-Toluidine (Or) Benzenamine, 2-Methyl-5-Nitro

Waste Code: U182
Waste Description: 1,3,5-Trioxane, 2,4,6-Trimethyl- (Or) Paraldehyde

Waste Code: U183
Waste Description: Benzene, Pentachloro- (Or) Pentachlorobenzene

Waste Code: U184
Waste Description: Ethane, Pentachloro- (Or) Pentachloroethane

Waste Code: U185
Waste Description: Benzene, Pentachloronitro- (Or) Pentachloronitrobenzene (Pcnb)

Waste Code: U186
Waste Description: 1,3-Pentadiene (I) (Or) 1-Methylbutadiene (I)

Waste Code: U187
Waste Description: Acetamide, N-(4-Ethoxyphenyl)- (Or) Phenacetin

Waste Code: U188
Waste Description: Phenol

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U189
Waste Description: Phosphorus Sulfide (R) (Or) Sulfur Phosphide (R)

Waste Code: U190
Waste Description: 1,3-Isobenzofurandione (Or) Phthalic Anhydride

Waste Code: U191
Waste Description: 2-Picoline (Or) Pyridine, 2-Methyl-

Waste Code: U192
Waste Description: Benzamide, 3,5-Dichloro-N-(1,1-Dimethyl-2-Propynyl)- (Or) Pronamide

Waste Code: U193
Waste Description: 1,2-Oxathiolane, 2,2-Dioxide (Or) 1,3-Propane Sultone

Waste Code: U194
Waste Description: 1-Propanamine (I,T) (Or) N-Propylamine (I,T)

Waste Code: U196
Waste Description: Pyridine

Waste Code: U197
Waste Description: 2,5-Cyclohexadiene-1,4-Dione (Or) P-Benzoquinone

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U202
Waste Description: 1,2-Benzisothiazol-3(2h)-One, 1,1-Dioxide, & Salts (Or) Saccharin, & Salts

Waste Code: U203
Waste Description: 1,3-Benzodioxole, 5-(2-Propenyl)- (Or) Safrole

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U206
Waste Description: D-Glucose, 2-Deoxy-2-[[(Methylnitrosoamino)-Carbonyl]Amino]- (Or) Glucopyranose, 2-Deoxy-2-(3-Methyl-3-Nitrosoureido)-,D- (Or) Streptozotocin

Waste Code: U207
Waste Description: 1,2,4,5-Tetrachlorobenzene (Or) Benzene, 1,2,4,5-Tetrachloro-

Waste Code: U208
Waste Description: 1,1,1,2-Tetrachloroethane (Or) Ethane, 1,1,1,2-Tetrachloro-

Waste Code: U209

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Description: 1,1,2,2-Tetrachloroethane (Or) Ethane, 1,1,2,2-Tetrachloro-

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U213
Waste Description: Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)

Waste Code: U214
Waste Description: Acetic Acid, Thallium(1+) Salt (Or) Thallium(I) Acetate

Waste Code: U215
Waste Description: Carbonic Acid, Dithallium(1+) Salt (Or) Thallium(I) Carbonate

Waste Code: U216
Waste Description: Thallium Chloride Tlcl (Or) Thallium(I) Chloride

Waste Code: U217
Waste Description: Nitric Acid, Thallium(1+) Salt (Or) Thallium(I) Nitrate

Waste Code: U218
Waste Description: Ethanethioamide (Or) Thioacetamide

Waste Code: U219
Waste Description: Thiourea

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U221
Waste Description: Benzenediamine, Ar-Methyl- (Or) Toluenediamine

Waste Code: U222
Waste Description: Benzenamine, 2-Methyl-, Hydrochloride (Or) O-Toluidine Hydrochloride

Waste Code: U223
Waste Description: Benzene, 1,3-Diisocyanatomethyl- (R,T) (Or) Toluene Diisocyanate (R,T)

Waste Code: U225
Waste Description: Bromoform (Or) Methane, Tribromo-

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U227
Waste Description: 1,1,2-Trichloroethane (Or) Ethane, 1,1,2-Trichloro-

Waste Code: U228
Waste Description: Ethene, Trichloro- (Or) Trichloroethylene

Waste Code: U234
Waste Description: 1,3,5-Trinitrobenzene (R,T) (Or) Benzene, 1,3,5-Trinitro-

Waste Code: U235

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Description: 1-Propanol, 2,3-Dibromo-, Phosphate (3:1) (Or) Tris(2,3,-Dibromopropyl) Phosphate

Waste Code: U236
Waste Description: 2,7-Naphthalenedisulfonic Acid,3,3'-[(3,3'-Dimethyl[1,1'-Biphenyl]-4,4'-Diyl)Bis(Azo)Bis[5-Amino -4-Hydroxy]-, Tetrasodium Salt (Or) Trypan Blue

Waste Code: U237
Waste Description: 2,4-(1h,3h)-Pyrimidinedione, 5-[Bis(2-Chloroethyl)Amino]- (Or) Uracil Mustard

Waste Code: U238
Waste Description: Carbamic Acid, Ethyl Ester (Or) Ethyl Carbamate (Urethane)

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U243
Waste Description: 1-Propene, 1,1,2,3,3,3-Hexachloro- (Or) Hexachloropropene

Waste Code: U244
Waste Description: Thioperoxydicarbonic Diamide [(H2n)C(S)]2s2, Tetramethyl- (Or) Thiram

Waste Code: U246
Waste Description: Cyanogen Bromide (Cn)Br

Waste Code: U247
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Methoxy- (Or) Methoxychlor

Waste Code: U248
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenyl-Butyl)-, & Salts, When Present At Concentrations Of 0.3% Or Less (Or) Warfarin, & Salts, When Present At Concentrations Of 0.3% Or Less

Waste Code: U249
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Of 10% Or Less

Waste Code: U271
Waste Description: Benomyl (Or) Carbamic Acid, [1-[(Butylamino)Carbonyl]-1h-Benzimidazol-2-Yl]-, Methyl Ester

Waste Code: U277
Waste Description: Sulfallate (Or) Carbamodithioic Acid, Diethyl-, 2-Chloro-2-Propenyl Ester

Waste Code: U278
Waste Description: Bendiocarb (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-, Methyl Carbamate

Waste Code: U279
Waste Description: U279

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U280
Waste Description: Barban (Or) Carbamic Acid, (3-Chlorophenyl)-, 4-Chloro-2-Butynyl Ester

Waste Code: U328
Waste Description: Benzenamine, 2-Methyl- (Or) O-Toluidine

Waste Code: U353
Waste Description: Benzenamine, 4-Methyl- (Or) P-Toluidine

Waste Code: U359
Waste Description: Ethanol, 2-Ethoxy- (Or) Ethylene Glycol Monoethyl Ether

Waste Code: U364
Waste Description: Bendiocarb Phenol (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-

Waste Code: U365
Waste Description: H-Azepine-1-Carbothioic Acid, Hexahydro-, S-Ethyl Ester (Or) Molinate

Waste Code: U366
Waste Description: Dazomet (Or) 2h-1,3,5-Thiadiazine- 2-Thione, Tetrahydro-3,5-Dimethyl-

Waste Code: U367
Waste Description: 7-Benzofuranol, 2,3-Dihydro-2,2-Dimethyl- (Or) Carbofuran Phenol

Waste Code: U372
Waste Description: Carbamic Acid, 1h-Benzimidazol-2-Yl, Methyl Ester (Or) Carbendazim

Waste Code: U373
Waste Description: Carbamic Acid, Phenyl-, 1-Methylethyl Ester (Or) Propham

Waste Code: U375
Waste Description: Carbamic Acid, Butyl-, 3-Iodo-2-Propynyl Ester (Or) 3-Iodo-2-Propynyl N-Butylcarbamate

Waste Code: U376
Waste Description: Carbamodithioic Acid, Dimethyl-, Tetraanhydrosulfide With Orthothiosetenious Acid (Or) Selenium, Tetrakis (Dimethyldithiocarbamate)

Waste Code: U377
Waste Description: Carbamodithioic Acid, Methyl-, Monopotassium Salt (Or) Potassium N-Methyldithiocarbamate

Waste Code: U378
Waste Description: Carbamodithioic Acid, (Hydroxymethyl) Methyl-, Monopotassium Salt (Or) Potassium N-Hydroxymethyl- N-Methyldi-Thiocarbamate

Waste Code: U379
Waste Description: Sodium Dibutyldithiocarbamate (Or) Carbamodithioic Acid, Dibutyl, Sodium Salt

Waste Code: U381
Waste Description: Carbamodithioic Acid, Diethyl-, Sodium Salt (Or) Sodium Diethyldithiocarbamate

Waste Code: U382
Waste Description: Carbamodithioic Acid, Dimethyl-, Sodium Salt (Or) Sodium

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Dimethyldithiocarbamate

Waste Code: U383
Waste Description: Carbamodithioic Acid, Dimethyl, Potassium Salt (Or) Potassium Dimethyldithiocarbamate

Waste Code: U384
Waste Description: Carbamodithioic Acid, Methyl-, Monosodium Salt (Or) Metam Sodium

Waste Code: U385
Waste Description: Carbamothioic Acid, Dipropyl-, S-Propyl Ester

Waste Code: U386
Waste Description: Carbamothioic Acid, Cyclohexylethyl-, S-Ethyl Ester (Or) Cycloate

Waste Code: U387
Waste Description: Carbamothioic Acid, Dipropyl-, S-(Phenylmethyl) Ester (Or) Prosulfocarb

Waste Code: U389
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3,3-Trichloro-2-Propenyl) Ester (Or) Triallate

Waste Code: U390
Waste Description: Carbamothioic Acid, Dipropyl-, S-Ethyl Ester (Or) Eptc

Waste Code: U391
Waste Description: Carbamothioic Acid, Butylethyl-, S-Propyl Ester (Or) Pebulate

Waste Code: U392
Waste Description: Butylate (Or) Carbamothioic Acid, Bis(2-Methylpropyl)-, S-Ethyl Ester

Waste Code: U393
Waste Description: Copper, Bis(Dimethylcarbamodithioato-S,S')- (Or) Copper Dimethyldithiocarbamate

Waste Code: U394
Waste Description: A2213 (Or) Ethanimidothioic Acid, 2-(Dimethylamino)-N-Hydroxy-2-Oxo-, Methyl Ester

Waste Code: U395
Waste Description: Diethylene Glycol, Dicarbamate (Or) Ethanol, 2,2'-Oxybis-, Dicarbamate

Waste Code: U396
Waste Description: Ferbam (Or) Iron, Tris(Dimethylcarbamodithioato-S,S')-,

Waste Code: U400
Waste Description: Bis(Pentamethylene)Thiuram Tetrasulfide (Or) Piperidine, 1,1'-(Tetrathiodicarbonothioyl)-Bis-

Waste Code: U401
Waste Description: Bis(Dimethylthiocarbamoyl) Sulfide (Or) Tetramethylthiuram Monosulfide

Waste Code: U402
Waste Description: Tetrabutylthiuram Disulfide (Or) Thioperoxydicarbonic Diamide, Tetrabutyl

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Waste Code: U403
Waste Description: Disulfiram (Or) Thioperoxydicarbonic Diamide, Tetraethyl

Waste Code: U404
Waste Description: U404

Waste Code: U407
Waste Description: Ethyl Ziram

Waste Code: U408
Waste Description: U408

Waste Code: U409
Waste Description: Carbamic Acid, [1,2-Phenylenebis (Iminocarbonothioyl)]Bis-, Dimethyl Ester (Or) Thiophanate-Methyl

Waste Code: U410
Waste Description: Ethanimidothioic Acid, N,N'-[Thiobis[(Methylimino)Carbonyloxy]]Bis-, Dimethyl Ester (Or) Thiodicarb

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TEXACO INC
Legal Status: Private
Date Became Current: 19940622
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 15730
Owner/Operator City,State,Zip: AUSTIN, TX 78761
Owner/Operator Telephone: 512-459-6543
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 500 HUNTSMAN WAY
Owner/Operator City,State,Zip: SALT LAKE CITY, UT 84108
Owner/Operator Telephone: 801-584-5700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040604
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060130
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-9999
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXACO CHEMICAL CO DIV OF TEXACO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 15730

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 512-459-6543
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050712
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20061219
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-9999
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Date Became Current: 20040108
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050712
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20051128
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20120409
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040108
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20120409
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040604
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040126
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20051128
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060130
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20061219
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION,
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040604
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050118
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050711
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Date Became Current: 20040126
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050118
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20060213
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION,
Legal Status: Private
Date Became Current: 20030224
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20040604
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HUNTSMAN PETROCHEMICAL CORPORATION
Legal Status: Private
Date Became Current: 20050711
Date Ended Current: Not reported
Owner/Operator Address: 7114 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-483-0934
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990310
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20001207
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040126
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040108
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040604
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050118
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Receive Date: 20050711
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050712
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051020
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051128
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060130
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060213
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060725
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060824
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070109
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110415
Handler Name: HUNTSMAN PETROCHEMICAL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120409
Handler Name: HUNTSMAN PETROCHEMICAL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190909
Handler Name: HUNTSMAN PETROCHEMICAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: TEXACO CHEMICAL CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920122
Handler Name: TEXACO CHEMICAL COMPANY

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940125
Handler Name: TEXACO CHEMICAL COMPANY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960301
Handler Name: HUNTSMAN CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980125
Handler Name: AUSTIN LABORATORIES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000125
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301
Handler Name: HUNTSMAN CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040301
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060301
Handler Name: HUNTSMAN PETROCHEMICAL CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32511
NAICS Description: PETROCHEMICAL MANUFACTURING

NAICS Code: 325188
NAICS Description: ALL OTHER BASIC INORGANIC CHEMICAL MANUFACTURING

NAICS Code: 325199
NAICS Description: ALL OTHER BASIC ORGANIC CHEMICAL MANUFACTURING

Has the Facility Received Notices of Violations:

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

HUNTSMAN PETROCHEMICAL (Continued) **1000144736**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20030515
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19881207
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: R6DAC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

AC135 Target Property | **HUNTSMAN PETROCHEMICAL CORPORATION**
7114 N. LAMAR BLVD.
AUSTIN, TX 78752 | **ICIS FINDS ECHO** | **1016462383 N/A**

Site 29 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

ICIS:

Enforcement Action ID:	06-2000-1247
FRS ID:	110000465513
Action Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Facility Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Facility Address:	7114 N. LAMAR BLVD. AUSTIN, TX 78752
Enforcement Action Type:	CERCLA 109A AO For Class I Penalties
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	109A
Facility SIC Code:	2869
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.342731
Longitude in Decimal Degrees:	-97.719215
Permit Type Desc:	Not reported
Program System Acronym:	26977
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	06-1986-0084
FRS ID:	110000465513
Action Name:	TEXACO CHEMICAL CO.
Facility Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Facility Address:	7114 N. LAMAR BLVD. AUSTIN, TX 78752
Enforcement Action Type:	TSCA 16 Action For Penalty
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	16
Facility SIC Code:	2869
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.342731
Longitude in Decimal Degrees:	-97.719215
Permit Type Desc:	Not reported
Program System Acronym:	26977
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Address:	7114 N. LAMAR BLVD.
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	2869

Facility Name:	HUNTSMAN PETROCHEMICAL CORPORATION
Address:	7114 N. LAMAR BLVD.
Tribal Indicator:	N
Fed Facility:	No

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1016462383**

NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1016462383**

SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1016462383**

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

Facility Name: HUNTSMAN PETROCHEMICAL CORPORATION
Address: 7114 N. LAMAR BLVD.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 2869

FINDS:
Registry ID: 110000465513

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
TSCA SUBMITTER
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are

HUNTSMAN PETROCHEMICAL CORPORATION (Continued) **1016462383**

transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS AIR POLLUTANT MAJOR
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.
US EPA Risk Management Plan (RMP) database stores the risk management plans reported by companies that handle, manufacture, use, or store certain flammable or toxic substances, as required under section 112(r) of the Clean Air Act (CAA).

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016462383
Registry ID:	110000465513
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000465513
Name:	AUSTIN RESEARCH LABORATOR
Address:	7114 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752

AC136 **CRESTVIEW STATION** **TX VCP** **S110510505**
Target **7114 N LAMAR BLVD** **TX UIC** **N/A**
Property **AUSTIN, TX 78752** **TX COMP HIST**

Site 30 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

VCP TCEQ:

Name:	CRESTVIEW STATION
Address:	7114 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	REGION 11 - AUSTIN
Facility ID:	1830
VCP Record Date:	06/15/2005

CRESTVIEW STATION (Continued) **S110510505**

Facility Type:	WAREHOUSE/STORAGE
PCA Number:	34029
Project Manager:	MRIGGLE
Phase:	COMPLETED
Acres at Site:	73
REM Program:	VCP
RN Number:	RN104686134
Former Facility Type:	Not reported
Site Address Description:	TRIANGULAR PIECE OF LAND BOUNDED BY NORTH LAMAR TO THE EAST, RAILROAD TRACKS TO THE WEST AND MORROW ROAD TO THE NORTH
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	06/15/2005
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	3
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	07/18/2007; 09/28/2007
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	06/13/2005
GW Target COC Class:	VOCS; SVOCS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2005-07-05 00:00:00
Soil Target COC Class:	Not reported
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1830
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	340290
Off Site?:	Not reported
Media:	MICROFILM; PAPER
IOP Number:	Not reported
File Location:	D/211; D/212; 299N, RACK 2, SIDE B, BOX 74; CR
Latitude:	30.20
Longitude:	-97.44

UIC:

Name:	CRESTVIEW STATION
Address:	Not reported
City,State,Zip:	TX
Near City:	AUSTIN
Authorization Number:	5X2600439
Authorization Date:	9/28/06
Physical Location:	Not reported

CRESTVIEW STATION (Continued) **S110510505**

Primary Business:	No primary business description on file.
Status:	CANCELLED
Date Received:	8/31/06
Affluent Program Contact:	Not reported
WWC Tracking:	12013865
Facility / Owner:	Trammel Crow Company
Injection Rate:	Gravity
Ownership Type:	Not reported
Injection Fluid:	Hydrogen Peroxide
Company Consult Contact:	Jeff Henke
Latitude:	30.342222
Longitude:	-97.718333
Company Consult:	Weston Solutions, Inc.
Prior Authorization Number:	Not reported
Company Consult Phone:	512/651-7125
High Priority:	Not reported
Project Manager:	M. Ryan
Affiliated Program:	VCP 1830
Comments:	Mike Frew
Date Closure:	Not reported
Status Report:	Future Rounds
Last Reports:	Not reported
File in Central Records:	Not reported
Well Type:	Aquifer Remediation
Number of Wells:	5-10 IT
Well Site:	Not reported
Wells in SWA:	Not reported
Well Name:	Not reported
Status Date:	Not reported
P AND A:	Not reported
Total Depth:	Not reported
Injection Zone Top:	15
Injection Zone Bottom:	18
AOR Well:	Not reported
IZ Name:	Austin Chalk
IZ Lithology:	Not reported
IZ Permeability:	Not reported
IZ Porosity:	Not reported
USDW Depth:	Not reported
OFF Inj:	Not reported
PAA Number:	Not reported
Company:	Not reported
Issued Date:	Not reported
Expired Date:	Not reported
Renewed Date:	Not reported
Revoked Date:	Not reported
Mined:	Not reported
Amend MOD Activity:	Not reported
Region:	Not reported
Operator Status:	Not reported
Operator Status Date:	Not reported
Well Number:	Not reported
AQUI Exempt:	Not reported
Program:	UNDERGROUND INJECTION CONTROL
Permit Type:	PERMIT

Customer:

RN Number:	RN104686134

CRESTVIEW STATION (Continued) **S110510505**

Customer Number:	CN600612014
Customer Name:	WESTON SOLUTIONS INC
Customer Role:	APPLICANT, OWNER OPERATOR

Name:	CRESTVIEW STATION
Address:	Not reported
City,State,Zip:	TX
Near City:	AUSTIN
Authorization Number:	5X2600439
Authorization Date:	Not reported
Physical Location:	Not reported
Primary Business:	No primary business description on file.
Status:	CANCELLED
Date Received:	11/15/06
Affluent Program Contact:	Not reported
WWC Tracking:	12021312
Facility / Owner:	Trammel Crow Company
Injection Rate:	100 psi & 50 gpm
Ownership Type:	Not reported
Injection Fluid:	Tadco racer F Green AX 2573-37 dye
Company Consult Contact:	Jeff Henke
Latitude:	30.342222
Longitude:	-97.718333
Company Consult:	Weston Solutions, Inc.
Prior Authorization Number:	5X2600439
Company Consult Phone:	512/651-7125
High Priority:	Not reported
Project Manager:	Bryan Smith
Affiliated Program:	VCP 1830
Comments:	No Auth Lttr on file
Date Closure:	Not reported
Status Report:	Not reported
Last Reports:	Not reported
File in Central Records:	Not reported
Well Type:	Pilot Test
Number of Wells:	3 IG & 1 MW
Well Site:	Not reported
Wells in SWA:	Not reported
Well Name:	Not reported
Status Date:	Not reported
P AND A:	Not reported
Total Depth:	Not reported
Injection Zone Top:	15
Injection Zone Bottom:	18
AOR Well:	Not reported
IZ Name:	Upper Shallow
IZ Lithology:	Not reported
IZ Permeability:	Not reported
IZ Porosity:	Not reported
USDW Depth:	Not reported
OFF Inj:	Not reported
PAA Number:	Not reported
Company:	Not reported
Issued Date:	Not reported
Expired Date:	Not reported
Renewed Date:	Not reported

CRESTVIEW STATION (Continued) **S110510505**

Revoked Date:	Not reported
Mined:	Not reported
Amend MOD Activity:	Not reported
Region:	Not reported
Operator Status:	Not reported
Operator Status Date:	Not reported
Well Number:	Not reported
AQUI Exempt:	Not reported
Program:	UNDERGROUND INJECTION CONTROL
Permit Type:	PERMIT

Customer:

RN Number:	RN104686134
Customer Number:	CN600612014
Customer Name:	WESTON SOLUTIONS INC
Customer Role:	APPLICANT, OWNER OPERATOR

COMP HIST:

RN Number:	RN104686134
Name:	CRESTVIEW STATION
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600612014
CN Name:	WESTON SOLUTIONS INC
CN Rating:	1.71
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236115
SIC Code:	7999
Related Number:	11-02120201

AC137 **TEXACO CHEMICAL COMPANY** **HIST FTTS** **1008190729**
Target **7114 N. LAMAR BOULEVARD** **N/A**
Property **AUSTIN, TX 78752**

Site 31 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

HIST FTTS INSP:

Inspection Number:	19870324NEIC 1
Region:	11
Inspection Date:	Not reported
Inspector:	NEIC
Violation occurred:	No
Investigation Type:	Section 5 Failure to Notify
Investigation Reason:	Neutral Scheme, Headquarters
Legislation Code:	TSCA
Facility Function:	Manufacturer

AC138 **7114 NORTH LAMAR, AUSTIN** **TX SPILLS** **S101721382**
Target **7114 NORTH LAMAR, AUSTIN** **N/A**
Property **AUSTIN, TX**

Site 32 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

SPILLS:

Name:	7114 NORTH LAMAR, AUSTIN
Address:	7114 NORTH LAMAR, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	05/20/1989
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL COMPANY
Responsible Party Address:	7114 NORTH LAMAR
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78752
Responsible Party Telephone:	5124830147
Substance:	ANTIFREEZE
Material Code:	9000
Media Affected:	NO
Permit Number:	30688
District:	14
Origin:	001
Cause:	002
Basin Code:	1427
Notify Date:	Not reported
Adequate Clean:	NONE
Classification:	006
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	~1000 GAL
Amnt in Water:	NONE
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	S. ADAMS
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported

7114 NORTH LAMAR, AUSTIN (Continued) **S101721382**

Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC139 **7114 N. LAMAR, AUSTIN** **TX SPILLS** **S107000138**
Target Property **7114 N. LAMAR, AUSTIN** **N/A**
AUSTIN, TX

Site 33 of 43 in cluster AC

Actual: 727 ft.

Focus Map: 6

SPILLS:

Name:	7114 N. LAMAR, AUSTIN
Address:	7114 N. LAMAR, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	12/20/1991
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL
Responsible Party Address:	7114 N. LAMAR
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	Not reported
Responsible Party Telephone:	5124830147
Substance:	WASTEWATER
Material Code:	9000
Media Affected:	Not reported
Permit Number:	0
District:	14
Origin:	001
Cause:	006
Basin Code:	1428
Notify Date:	Not reported
Adequate Clean:	003
Classification:	006
Basin Name:	COLORADO
Water Affected:	WALNUT CREEK
Amnt Spilled:	UNK GAL
Amnt in Water:	UNK GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	X. X
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported

7114 N. LAMAR, AUSTIN (Continued) **S107000138**

Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC140 **7114 NORTH LAMAR BLVD., AUSTIN,TX 78761** **TX SPILLS** **S107003820**
Target **7114 NORTH LAMAR BLVD., AUSTIN,TX 78761** **N/A**
Property **AUSTIN, TX**

Site 34 of 43 in cluster AC

Actual:
727 ft.

Focus Map:
6

SPILLS:

Name:	7114 NORTH LAMAR BLVD., AUSTIN,TX 78761
Address:	7114 NORTH LAMAR BLVD., AUSTIN,TX 78761
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	12/07/1992
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL
Responsible Party Address:	PO BOX 15730
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78761
Responsible Party Telephone:	5124830934
Substance:	ETHYLENE GLYCOL
Material Code:	2053
Media Affected:	A
Permit Number:	30688
District:	14
Origin:	001
Cause:	003
Basin Code:	0
Notify Date:	Not reported
Adequate Clean:	001
Classification:	006
Basin Name:	Not reported
Water Affected:	NONE
Amnt Spilled:	80 LBS
Amnt in Water:	0 LBS
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported

7114 NORTH LAMAR BLVD., AUSTIN,TX 78761 (Continued) **S107003820**

Enforce:	Not reported
Information Final:	X
Coordinator:	C. SMITH
Time Reported:	11:40
Spill Time:	08:00
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC141 **ERNS** **91100538**
Target Property **7114 NORTH LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 35 of 43 in cluster AC

Actual:
727 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Focus Map:
6

AC142 **ERNS** **92147966**
Target Property **7114 N LAMAR BLVD** **N/A**
AUSTIN, TX 78752

Site 36 of 43 in cluster AC

Actual:
727 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Focus Map:
6

AC143 Target Property | **BLACKBURN TEXACO SERVICE STATION**
7006 LAMAR BLVD N
TRAVIS (County), TX 78752 | **EDR Hist Auto** | **1013756818**
N/A

Site 37 of 43 in cluster AC

Actual: 725 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	KAVECKI CHAS TEX	GASOLINE STATIONS
1958	DOWDYS TEXACO	GASOLINE STATIONS
1965	GIBSON TEXACO STATION	GASOLINE STATIONS
1970	BLACKBURN TEXACO SERVICE STATIO	GASOLINE STATIONS

AC144 Target Property | **HUNTSMAN CORP. CHEMICAL LAB**
HUNTSMAN CORP. CHEMICAL LAB
HUNT, TX | **TX SPILLS** | **S107011715**
N/A

Site 38 of 43 in cluster AC

Actual: 725 ft.

Focus Map: 6

SPILLS:

Name:	HUNTSMAN CORP. CHEMICAL LAB
Address:	HUNTSMAN CORP. CHEMICAL LAB
City,State,Zip:	HUNT, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	08/26/1994
Seq Num:	5
Responsible Party Name:	HUNTSMAN CORPORATION
Responsible Party Address:	7114 N. LAMAR BLVD.
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78752
Responsible Party Telephone:	5124830178
Substance:	T BUTYL PHENOL
Material Code:	2080
Media Affected:	Not reported
Permit Number:	NONE
District:	11
Origin:	001
Cause:	003
Basin Code:	1429
Notify Date:	Not reported
Adequate Clean:	001
Classification:	005
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	15 LBS
Amnt in Water:	NONE LBS
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	C. SMITH
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported

HUNTSMAN CORP. CHEMICAL LAB (Continued) **S107011715**

Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC145 **TEXACO CHEMICAL PLANT SITE @ FACILITY AT ABOVE LOC** **TX SPILLS** **S106991259**
Target Property **TEXACO CHEMICAL PLANT SITE @ FACILITY AT ABOVE LOCATION , TX** **N/A**

Site 39 of 43 in cluster AC

Actual: 724 ft.

Focus Map: 6

SPILLS:

Name:	TEXACO CHEMICAL PLANT SITE @ FACILITY AT ABOVE LOCATION
Address:	TEXACO CHEMICAL PLANT SITE @ FACILITY AT ABOVE LOCATION
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	01/21/1989
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL COMPANY
Responsible Party Address:	7114 NO. LAMAR
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78754
Responsible Party Telephone:	5124596543
Substance:	GLYCERIN ETHOXYLATE
Material Code:	9000
Media Affected:	NO
Permit Number:	30688
District:	14
Origin:	001
Cause:	003
Basin Code:	1403
Notify Date:	Not reported
Adequate Clean:	NONE
Classification:	006
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	5000 GAL
Amnt in Water:	NONE
Latitude:	Not reported

TEXACO CHEMICAL PLANT SITE @ FACILITY AT ABOVE LOCATION (Continued) **S106991259**

Longitude:	Not reported
Inspected By:	TWC
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	J. YOUNG
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC146 **TEXACO CHEMICAL CO PLANT, 7114 N.LAMAR, AUSTIN** **TX SPILLS** **S106996049**
Target Property **TEXACO CHEMICAL CO PLANT, 7114 N.LAMAR, AUSTIN** **N/A**
AUSTIN, TX

Site 40 of 43 in cluster AC

Actual: 724 ft.

Focus Map: 6

SPILLS:

Name:	TEXACO CHEMICAL CO PLANT, 7114 N.LAMAR, AUSTIN
Address:	TEXACO CHEMICAL CO PLANT, 7114 N.LAMAR, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	12/07/1990
Seq Num:	Not reported
Responsible Party Name:	TEXACO CHEMICAL
Responsible Party Address:	7114 N. LAMAR
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78761
Responsible Party Telephone:	5124830147
Substance:	TRIENHAND AMINE
Material Code:	9000
Media Affected:	NO
Permit Number:	30688
District:	14
Origin:	001

TEXACO CHEMICAL CO PLANT, 7114 N.LAMAR, AUSTIN (Continued) **S106996049**

Cause:	003
Basin Code:	1428
Notify Date:	Not reported
Adequate Clean:	001
Classification:	006
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	20 GAL
Amnt in Water:	NONE
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	J. YOUNG
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AC147 **ERNS** **877756**
Target Property **7114 N. LAMAR** **N/A**
TRAVIS (County), TX

Site 41 of 43 in cluster AC

Actual:
724 ft.

Focus Map:
6

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

148 Target Property | **HEART-O-TEXAS FILM LINES**
6929 N LAMAR BLVD
AUSTIN, TX | **TX HIST UST** | **S111678672**
N/A

Actual: 722 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	HEART-O-TEXAS FILM LINES
Address:	6929 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0600
HID UST:	600
Inspection:	Not reported
Due:	06/01/2012

AD149 Target Property | **DING DONG AUTO CENTER**
6916 N LAMAR BLVD
AUSTIN, TX 78752 | **TX LPST**
TX UST | **U001542847**
N/A

Site 1 of 6 in cluster AD

Actual: 718 ft.
Focus Map: 6

LPST:

Name:	DING DONG AUTO CENTER
Address:	6916 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0065041
LPST Id:	107367
Facility Location:	6916 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/05/1993
Entered Date:	12/06/1993
Reported Date:	10/05/1993
Closure Date:	11/10/1993
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	ED DAUGHERTY
Responsible Party Address:	3988 FAR W BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78731
Responsible Party Telephone:	512/345-4639
Reported Date:	10/05/1993
Case Start Date:	11/10/1993
Reference Number:	RN103772646
Project Manager:	HWELCH

UST:

Name:	DING DONG AUTO CENTER
Address:	6916 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787523508
AI Number:	65041
Facility Type:	RETAIL
Facility Begin Date:	10/06/1993
Facility Status:	INACTIVE
Additional ID:	865652152003210

DING DONG AUTO CENTER (Continued) **U001542847**

Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/30/1993
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRESIDENT
Application Received Date On Earliest Reg Form:	10/01/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602291742
Owner Last Name:	DAUGHERTY ED
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	874652142003210
Additional ID:	865652152003210
AI Number:	65041
Owner Effective Begin Date:	10/06/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	3000

DING DONG AUTO CENTER (Continued) **U001542847**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149036
Facility ID:	96747
Ai Number:	65041
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

DING DONG AUTO CENTER (Continued) **U001542847**

Installation Signature Date:	09/20/1993
Compartment Records:	
Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	162454
UST ID:	149036
AI Number:	65041
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582

DING DONG AUTO CENTER (Continued) **U001542847**

UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644
UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149037
Facility ID:	96747
Ai Number:	65041
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

DING DONG AUTO CENTER (Continued) **U001542847**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	09/20/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	162455
UST ID:	149037
AI Number:	65041
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

DING DONG AUTO CENTER (Continued) **U001542847**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644
UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149038
Facility ID:	96747
Ai Number:	65041

DING DONG AUTO CENTER (Continued) **U001542847**

Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	09/20/1993

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	162456
UST ID:	149038

DING DONG AUTO CENTER (Continued) **U001542847**

AI Number:	65041
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644

DING DONG AUTO CENTER (Continued) **U001542847**

UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149039
Facility ID:	96747
Ai Number:	65041
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

DING DONG AUTO CENTER (Continued) **U001542847**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	09/20/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	162457
UST ID:	149039
AI Number:	65041
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

DING DONG AUTO CENTER (Continued) **U001542847**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644
UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149040
Facility ID:	96747
Ai Number:	65041
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

DING DONG AUTO CENTER (Continued) **U001542847**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	09/20/1993

Compartment Records:

Tank ID:	6
Tank Capacity:	0
UST Comprt ID:	162458
UST ID:	149040
AI Number:	65041
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

DING DONG AUTO CENTER (Continued) **U001542847**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644
UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309

DING DONG AUTO CENTER (Continued) **U001542847**

Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	10/01/1993
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149041
Facility ID:	96747
Ai Number:	65041
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

DING DONG AUTO CENTER (Continued) **U001542847**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	09/20/1993

Compartment Records:

Tank ID:	5
Tank Capacity:	0
UST Comprt ID:	162459
UST ID:	149041
AI Number:	65041
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

DING DONG AUTO CENTER (Continued) **U001542847**

More Self Certification:

Self Cert ID:	25309
Cert ID:	68646
UST Comprt ID:	214579
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68645
UST Comprt ID:	214582
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68644
UST Comprt ID:	214581
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25309
Cert ID:	68643
UST Comprt ID:	214580
UST ID:	79305
AI Number:	65041
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	DAUGHERTY ED
Contact Mailing Address (Delivery):	3988 FAR WEST BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78731 2901
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96747
Additional ID:	865652152003210
Princ ID:	874652142003210
AI Number:	65041
Facility Name:	DING DONG AUTO CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ED DAUGHERTY/

AD150 Target Property | **DING DONG AUTO CENTER**
6916 N LAMAR BLVD
AUSTIN, TX 78752 | **TX CENTRAL REGISTRY** | **S126667297**
N/A

Site 2 of 6 in cluster AD

Actual: 718 ft.

Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN103772646
Name:	DING DONG AUTO CENTER
Address:	6916 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3508
Status:	ACTIVE
Status Date:	7/29/2003
Customer Number:	CN602291742
Customer Name:	DAUGHERTY ED
Customer Legal Name:	Daugherty Ed
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/6/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103772646
Name:	DING DONG AUTO CENTER
Address:	6916 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3508
Status:	ACTIVE
Status Date:	7/29/2003
Customer Number:	CN602291742
Customer Name:	DAUGHERTY ED
Customer Legal Name:	Daugherty Ed
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/6/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AD151 Target Property | **AUSTIN STANDARD TRANSMISSION & CLUTCH**
6916 LAMAR BLVD N
AUSTIN, TX 78752 | **EDR Hist Auto** | **1013759183**
N/A

Site 3 of 6 in cluster AD

Actual: 718 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	WOFFORD SERV STA	GASOLINE STATIONS
1958	WOFFORD SERV STA	GASOLINE STATIONS
1962	WOFFORDS HUMBLE	GASOLINE STATIONS
1965	CHAPMANS HUMBLE SERVICE GAS STG	GASOLINE STATIONS
1970	CHAPMANS HUMBLE SERVICE	GASOLINE STATIONS
1975	CHAPMANS EXXON	GASOLINE STATIONS
1980	MOTORSPORTS INTERNAT	GASOLINE STATIONS
1984	AUSTIN STANDARD TRANSMISSION &	AUTOMOBILE REPAIRING

AUSTIN STANDARD TRANSMISSION & CLUTCH (Continued) **1013759183**

1990	AUSTIN CARBURETOR CLINIC AUTO R	AUTOMOBILE REPAIRING
2004	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2005	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2006	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2007	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2008	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2009	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2010	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC
2011	J&J AUSTIN MOTORS INC	Automotive Dealers, NEC, NEC

AD152 **JAMES EICHELBERGER JR.** **TX HIST UST** **S128729290**
Target **6916 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 4 of 6 in cluster AD

Actual:
718 ft.

Focus Map:
6

HIST UST AUSTIN:

Name:	JAMES EICHELBERGER JR.
Address:	6916 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0484
HID UST:	484
Inspection:	04/21/2009
Due:	04/21/2012

AD153 **DING DONG AUTO CENTER** **TX HIST UST** **S128729027**
Target **6916 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 5 of 6 in cluster AD

Actual:
718 ft.

Focus Map:
6

HIST UST AUSTIN:

Name:	DING DONG AUTO CENTER
Address:	6916 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0418
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AE154 **SOUTHCREST PARK** **TX CENTRAL REGISTRY** **S126572855**
Target **6811 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 3 in cluster AE

Actual:
716 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN102329943
Name:	SOUTHCREST PARK
Address:	6811 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3505
Status:	ACTIVE

SOUTHCREST PARK (Continued) **S126572855**

Status Date:	2002-05-23
Customer Number:	CN601229842
Customer Name:	EICHELBERGER, JAMES K
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102329943
Name:	SOUTHCREST PARK
Address:	6811 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3505
Status:	ACTIVE
Status Date:	2002-05-23
Customer Number:	CN601229842
Customer Name:	EICHELBERGER, JAMES K
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102329943
Name:	SOUTHCREST PARK
Address:	6811 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3505
Status:	ACTIVE
Status Date:	2002-05-23
Customer Number:	CN601229842
Customer Name:	EICHELBERGER, JAMES K
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

AE155 Target Property | **AUSTIN KAWASAKI MOTORCYCLE ALA & AERV**
6801 LAMAR BLVD N
AUSTIN, TX 78752 | **EDR Hist Auto** | **1013757563**
N/A

Site 2 of 3 in cluster AE

Actual: 716 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1975	KAWASAKI MOTOSPORTS MOTORCYCLE	MOTORCYCLE DEALERS AND REPAIRERS
1980	AUSTIN KAWASAKI MOTORCYCLE SLS	MOTORCYCLE DEALERS AND REPAIRERS
1984	AUSTIN KAWASAKI MOTORCYCLE ALA	MOTORCYCLE DEALERS AND REPAIRERS

AE156 Target Property | **COLORPRESS INC**
6801 N LAMAR BLVD
AUSTIN, TX | **TX HIST UST** | **S111678610**
N/A

Site 3 of 3 in cluster AE

Actual: 716 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	COLORPRESS INC
Address:	6801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0831
HID UST:	831
Inspection:	04/08/2009
Due:	04/08/2012

AF157 Target Property | **K O MACHINE**
6721 N LAMAR BLVD STE 705
AUSTIN, TX 78752 | **TX Ind. Haz Waste**
TX CENTRAL REGISTRY | **S103609601**
N/A

Site 1 of 13 in cluster AF

Actual: 715 ft.
Focus Map: 6

Ind. Haz Waste:

Name:	K O MACHINE
Address:	6721 N LAMAR BLVD STE 705
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	76696
Registration Initial Notification Date:	03/06/1992
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD988032884
Primary NAICS Code:	Not reported
Status Change Date:	19920306
Land Type:	PRIVATE
Description of Facility Site Location:	6721 N Lamar Blvd, Ste 705, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0

K O MACHINE (Continued) **S103609601**

Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	K O MACHINE INC
Contact Name:	CARL KOWALCZYK
Contact Telephone Number:	512-4545602
Mailing Address:	6721 N LAMAR BLVD STE 705
Mailing Address2:	STE 705
Mailing City,State,Zip:	AUSTIN, TX 787523500
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31007
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	K O MACHINE INC
Operator Address:	6721 N LAMAR BLVD STE 705
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4545602
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	30113138967
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	K O MACHINE INC
Owner Mailing Address:	6721 N LAMAR BLVD STE 705
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4545602
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	30113138967
Owner Bankruptcy Code:	Not reported

K O MACHINE (Continued) **S103609601**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6721 N LAMAR BLVD STE 705
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4545602
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6721 N LAMAR BLVD STE 705
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4545602
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	CARL KOWALCZYK
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6721 N LAMAR BLVD STE 705
Contact Address 2:	STE 705
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4545602
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100642081
Name:	K O MACHINE
Address:	6721 N LAMAR BLVD STE 705
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3500
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600352462
Customer Name:	K O MACHINE INC
Customer Legal Name:	K.O. Machine, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6721 N Lamar Blvd, Ste 705, Austin, TX

Regulated Entity Number:	RN100642081
Name:	K O MACHINE

K O MACHINE (Continued) **S103609601**

Address:	6721 N LAMAR BLVD STE 705
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3500
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600352462
Customer Name:	K O MACHINE INC
Customer Legal Name:	K.O. Machine, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6721 N Lamar Blvd, Ste 705, Austin, TX

AF158 **K 0 MACHINE CO** **EDR Hist Auto** **1013763827**
Target **6721 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78752**

Site 2 of 13 in cluster AF

Actual:
715 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1988	T JS SALES & SERVICE	General Automotive Repair Shops
1989	T JS SALES & SERVICE	General Automotive Repair Shops
1990	K 0 MACHINE CO	AUTOMOBILE REPAIRING
1992	K O MACHINE INC	Engine Repair
1993	K O MACHINE INC	Engine Repair

AF159 **K O MACHINE INC** **RCRA NonGen / NLR** **1000708620**
Target **6721 N LAMAR BLVD STE 705** **FINDS** **TXD988032884**
Property **AUSTIN, TX 78752** **ECHO**

Site 3 of 13 in cluster AF

Actual:
715 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	K O Machine Inc
Handler Address:	N LAMAR BLVD STE 705
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD988032884
Contact Name:	CARL KOWALCZYK
Contact Address:	N LAMAR BLVD STE 705
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-454-5602
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

K O MACHINE INC (Continued) **1000708620**

Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD STE 705
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	K O Machine Inc
Owner Type:	Private
Operator Name:	K O Machine Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium

K O MACHINE INC (Continued) **1000708620**

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: K O MACHINE INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	6721 N LAMAR BLVD STE 705
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-5602
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: DIMENSION PROPERTIES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	609 WOOD ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78703
Owner/Operator Telephone:	512-476-1072
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

K O MACHINE INC (Continued) **1000708620**

Owner/Operator Indicator: Owner
Owner/Operator Name: K O MACHINE INC
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 6721 N LAMAR BLVD STE 705
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-454-5602
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910401
Handler Name: KO MACHINE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: K O MACHINE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005133033

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

K O MACHINE INC (Continued) **1000708620**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000708620
Registry ID:	110005133033
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005133033
Name:	K O MACHINE INC
Address:	6721 N LAMAR BLVD STE 705
City,State,Zip:	AUSTIN, TX 78752

AF160 **KO MACHINE SHOP** **RCRA-SQG** **1010415820**
Target **6721 N LAMAR** **TXD988023867**
Property **AUSTIN, TX 78752**

Site 4 of 13 in cluster AF

Actual:
715 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	19910107
Handler Name:	Ko Machine Shop
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD988023867
Contact Name:	CARL KOWALCZYK
Contact Address:	6721 N LAMAR
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-454-5602
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Ko Machine Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

KO MACHINE SHOP (Continued) **1010415820**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: KO MACHINE INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6721 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-5602
Owner/Operator Telephone Ext:	Not reported

KO MACHINE SHOP (Continued) **1010415820**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910107
Handler Name: KO MACHINE SHOP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AF161 **QUICKY** **TX ASBESTOS** **S119154535**
Target **6719 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78753**

Site 5 of 13 in cluster AF

Actual:
714 ft.

Focus Map:
6

ASBESTOS:
Name: QUICKY
Address: 6719 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752
Date of inspection: 12/07/2012
Reason for Inspection: Routine
Violation: Yes
Complaint Date: Not reported
Notification Number: Not reported
ASB Priority: Not reported
PIF State: Not reported
Detained: No
Product Name: Not reported
Time Spent: 2
Travel Time: 1.5
Mileage: 7.6
Reg: 07
Init: MAO
Seq: 03
Facility Type: Tattooing and Body Piercing
Inspector Name: Margaret Olsovsky
Date Report Received: 12/10/2012
Date Routed by Supervisor: 12/11/2012

QUICKY (Continued) **S119154535**

Date Routed to PSQA:	11/11/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	QUICKY
Address:	6719 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	03/31/2016
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported

QUICKY (Continued) **S119154535**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.7
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Tattooing
Inspector Name:	Eddie Jackson
Date Report Received:	04/04/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	04/06/2016
Date Reviewed by PSQA:	2016-04-06 00:00:00
Date Routed by Supervisor1:	04/05/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

QUICKY (Continued) **S119154535**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AF162 **NORTH LAMAR AND SHIRLEY TRACT** **TX ASBESTOS** **S127319980**
Target **6709 N LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 6 of 13 in cluster AF

Actual:
714 ft.

Focus Map:
6

ASBESTOS:

Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	01/29/2021
Notification Number:	2020007680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/08/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/08/2021
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/14/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	03/05/2021
Notification Number:	2020007680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/08/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/08/2021
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	01/29/2021
Notification Number:	2020007680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2021

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/05/2021
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/11/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	03/05/2021
Notification Number:	2020007680

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/05/2021
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	01/29/2021
Notification Number:	2020007680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2020
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/11/2021
Client Code:	Not reported
Client Name:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/02/2021
Reason for Inspection:	John Nelson
Violation:	Not reported
Complaint Date:	03/05/2021
Notification Number:	2020007680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	12/11/2020
Certification Statement Phone:	512-243-2913
Is The Facility a School or K-12?:	N

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/02/02
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	02/02/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020007680
File Number:	57095
License Status Description:	Paid
Expiration Date:	03/05/2021
Original Date:	12/11/2020
Rank Effective Date:	12/11/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25738
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/01/20
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/20/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020007680
File Number:	57095
License Status Description:	Paid
Expiration Date:	03/05/2021
Original Date:	12/11/2020
Rank Effective Date:	12/11/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25527
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/01/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/15/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020007680
File Number:	57095
License Status Description:	Paid
Expiration Date:	03/05/2021
Original Date:	12/11/2020

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Rank Effective Date:	12/11/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	25385
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	NORTH LAMAR AND SHIRLEY TRACT
Address:	6709 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/01/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported

NORTH LAMAR AND SHIRLEY TRACT (Continued) **S127319980**

Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/15/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020007680
File Number:	57095
License Status Description:	Paid
Expiration Date:	03/05/2021
Original Date:	12/11/2020
Rank Effective Date:	12/11/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25524
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

AF163 **6705 N LAMAR BLVD, AUSTIN** **US BROWNFIELDS** **1016356270**
Target **6705 N LAMAR BLVD,** **FINDS** **N/A**
Property **AUSTIN, TX 78752**

Site 7 of 13 in cluster AF

Actual:
714 ft.

Focus Map:
6

US BROWNFIELDS:

Name:	6705 N LAMAR BLVD, AUSTIN
Address:	6705 N LAMAR BLVD,
Recipient name:	R6 TBA - Texas (ARRA)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.334972
Longitude:	-97.720258
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Former Use: TBA request from the City of Austin on behalf of the property owner. No hydrocarbons were found but UST removal is recommended if property is redeveloped.
Datum:	World Geodetic System of 1984
Acres Property ID:	120301
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	76800

6705 N LAMAR BLVD, AUSTIN (Continued) **1016356270**

Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - TBA Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	n/a
Start Date:	12/9/2010
Ownership Entity:	Private
Completion Date:	3/31/2011
Current Owner:	Randall Daugherty
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	TBA request from the City of Austin on behalf of the property owner. No hydrocarbons were found but UST removal is recommended if property is redeveloped.
Below Poverty Number:	853
Below Poverty Percent:	19.13
Meidan Income:	8534
Meidan Income Number:	1656
Meidan Income Percent:	37.15
Vacant Housing Number:	189
Vacant Housing Percent:	7.89
Unemployed Number:	243
Unemployed Percent:	5.45

6705 N LAMAR BLVD, AUSTIN (Continued) **1016356270**

Name:	6705 N LAMAR BLVD, AUSTIN
Address:	6705 N LAMAR BLVD,
Recipient name:	R6 TBA - Texas (ARRA)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.334972
Longitude:	-97.720258
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Former Use: TBA request from the City of Austin on behalf of the property owner. No hydrocarbons were found but UST removal is recommended if property is redeveloped.
Datum:	World Geodetic System of 1984
Acres Property ID:	120301
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6500
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - TBA Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	8/18/2010
Ownership Entity:	Private
Completion Date:	12/9/2010
Current Owner:	Randall Daugherty
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Not reported

6705 N LAMAR BLVD, AUSTIN (Continued) **1016356270**

Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	TBA request from the City of Austin on behalf of the property owner. No hydrocarbons were found but UST removal is recommended if property is redeveloped.
Below Poverty Number:	853
Below Poverty Percent:	19.13
Meidan Income:	8534
Meidan Income Number:	1656
Meidan Income Percent:	37.15
Vacant Housing Number:	189
Vacant Housing Percent:	7.89
Unemployed Number:	243
Unemployed Percent:	5.45

FINDS:
Registry ID: 110042111112

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AF164 **A-AABAT STORAGE** **TX LPST** **S111678636**
Target **6705 N LAMAR BLVD** **TX TANKS** **N/A**
Property **AUSTIN, TX 78752** **TX GCC**
TX RDR

Site 8 of 13 in cluster AF

Actual: 714 ft.
Focus Map: 6

LPST:

Name:	A-AABAT STORAGE FACILITY
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	0085162
LPST Id:	118958
Facility Location:	6705 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/17/2012
Entered Date:	10/25/2012
Reported Date:	09/17/2012
Closure Date:	10/26/2012
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED

A-AABAT STORAGE (Continued) **S111678636**

Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	KJF
Responsible Party Name:	Not reported
Responsible Party Contact:	RANDY DAUGHERTY
Responsible Party Address:	6720 B SHIRLEY AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/459-6569
Reported Date:	09/17/2012
Case Start Date:	10/26/2012
Reference Number:	RN106494073
Project Manager:	KFROSS

TANKS:

Facility ID:	130333
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787523503
Total UST:	0
Additional ID:	222063332012231
AI Number:	85162
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

GCC:

A-AABAT STORAGE (Continued) **S111678636**

Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	118958
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	10/25/2012
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

RDR:

RDR ID:	20793
Facility ID:	85162
RN:	Not reported
CN:	Not reported
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/4/2012
Due Date:	12/3/2012
Tank Owner:	A-AABAT STORAGE
Contact Person:	RANDY DAUGHTERLY
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/25/2012
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	118958
Pre-Existing LPST Number:	Not reported
Comments:	TECH RESP 10/4/12
Review Coordinator:	KJF
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AF165 Target Property | **A-AABAT SEF STORAGE**
6705 N LAMAR BLVD
AUSTIN, TX | **TX HIST UST** | **S128729561**
N/A

Site 9 of 13 in cluster AF

Actual: 714 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	A-AABAT SEF STORAGE
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0174
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AF166 Target Property | **GLENN SERV STA**
6705 LAMAR BLVD
AUSTIN, TX | **EDR Hist Auto** | **1013755329**
N/A

Site 10 of 13 in cluster AF

Actual: 714 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	GLENN SERV STA	GASOLINE STATIONS
1965	RITTERS SERVICE STATION	GASOLINE STATIONS
1970	RITTERS GASOLINE STATION	GASOLINE STATIONS

AF167 Target Property | **EARNEST E PANNELL JR.**
6705 N LAMAR BLVD
AUSTIN, TX | **TX HIST UST** | **S128729262**
N/A

Site 11 of 13 in cluster AF

Actual: 714 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	EARNEST E PANNELL JR.
Address:	6705 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0392
HID UST:	392
Inspection:	Not reported
Due:	06/01/2012

AF168 Target Property | **A-AABAT STORAGE**
6705 N LAMAR BLVD
AUSTIN, TX 78752 | **TX CENTRAL REGISTRY** | **S126843392**
N/A

Site 12 of 13 in cluster AF

Actual: 714 ft.
Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN106494073
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3503

A-AABAT STORAGE (Continued) **S126843392**

Status:	ACTIVE
Status Date:	8/18/2012
Customer Number:	CN604127837
Customer Name:	DAUGHTERY
Customer Legal Name:	Daughtery
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106494073
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3503
Status:	ACTIVE
Status Date:	8/18/2012
Customer Number:	CN604235846
Customer Name:	DAUGHTERY, RANDY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106494073
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3503
Status:	ACTIVE
Status Date:	8/18/2012
Customer Number:	CN604127837
Customer Name:	DAUGHTERY
Customer Legal Name:	Daughtery
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106494073
Name:	A-AABAT STORAGE
Address:	6705 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3503
Status:	ACTIVE
Status Date:	8/18/2012
Customer Number:	CN604235846

A-AABAT STORAGE (Continued) **S126843392**

Customer Name:	DAUGHTERY, RANDY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AG169 **JEFFS CUSTOM BODY SHOP** **TX Ind. Haz Waste** **S102749880**
Target **6616 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 14 in cluster AG

Actual:
713 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	JEFFS CUSTOM BODY SHOP
Address:	6616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	66410
Registration Initial Notification Date:	08/21/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD102738960
Primary NAICS Code:	Not reported
Status Change Date:	19850821
Land Type:	PRIVATE
Description of Facility Site Location:	6616 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	NON INDUS
Company Name:	JEFFS CUSTOM BODY SHOP
Contact Name:	JEFF SESSLER
Contact Telephone Number:	512-4523373
Mailing Address:	6616 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787523502
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21686
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1

JEFFS CUSTOM BODY SHOP (Continued) **S102749880**

MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JEFFS CUSTOM BODY SHOP
Operator Address:	6616 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4523373
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JEFFS CUSTOM BODY SHOP
Owner Mailing Address:	6616 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4523373
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6616 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4523373
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6616 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported

JEFFS CUSTOM BODY SHOP (Continued) **S102749880**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4523373
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JEFF SESSLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6616 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4523373
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100646314
Name:	JEFFS CUSTOM BODY SHOP
Address:	6616 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3502
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600356398
Customer Name:	JEFFS CUSTOM BODY SHOP
Customer Legal Name:	Jeffs Custom Body Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6616 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100646314
Name:	JEFFS CUSTOM BODY SHOP
Address:	6616 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3502
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600356398
Customer Name:	JEFFS CUSTOM BODY SHOP
Customer Legal Name:	Jeffs Custom Body Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6616 N Lamar Blvd, Austin, TX

AG170 Target Property | **JEFFS CUSTOM BODY SHOP**
6616 N LAMAR BLVD
AUSTIN, TX 78752 | **RCRA NonGen / NLR**
FINDS
ECHO | **1000230637**
TXD102738960

Site 2 of 14 in cluster AG

Actual: 713 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Jeffs Custom Body Shop
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD102738960
Contact Name:	JEFF SESSLER
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-452-3373
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Jeffs Custom Body Shop
Owner Type:	Private
Operator Name:	Jeffs Custom Body Shop
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

JEFFS CUSTOM BODY SHOP (Continued) **1000230637**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JEFFS CUSTOM BODY SHOP	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	6616 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-452-3373
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JEFF SESSLER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JEFFS CUSTOM BODY SHOP	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	6616 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-452-3373
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19850927

JEFFS CUSTOM BODY SHOP (Continued) **1000230637**

Handler Name: JEFFS CUSTOM BODY SHOP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: JEFFS CUSTOM BODY SHOP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005070314

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000230637
Registry ID: 110005070314
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005070314
Name: JEFFS CUSTOM BODY SHOP

JEFFS CUSTOM BODY SHOP (Continued) **1000230637**

Address: 6616 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752

AG171 **VEHICLE REPAIR & REFINISH** **TX CENTRAL REGISTRY** **S123849006**
Target **6614 N. LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 3 of 14 in cluster AG

Actual:
713 ft.

Focus Map:
6

CENTRAL REGISTRY:

Regulated Entity Number:	RN100729193
Name:	VEHICLE REPAIR & REFINISH
Address:	6614 N. LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600416317
Customer Name:	JEFFS AUTO BODY REPAIR INC
Customer Legal Name:	Jeff's Auto Body Repair, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/19/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	6614 N. LAMAR

Regulated Entity Number:	RN100729193
Name:	VEHICLE REPAIR & REFINISH
Address:	6614 N. LAMAR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600416317
Customer Name:	JEFFS AUTO BODY REPAIR INC
Customer Legal Name:	Jeff's Auto Body Repair, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/19/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	6614 N. LAMAR

AG172 **RIVER CITY BULTACO MOTORCYCLE SIS & SERV** **EDR Hist Auto** **1013776544**
Target **6614 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78752**

Site 4 of 14 in cluster AG

Actual:
713 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1975	RIVER CITY BULTACO MOTORCYCLE S	MOTORCYCLE DEALERS AND REPAIRERS

RIVER CITY BULTACO MOTORCYCLE SIS & SERV (Continued) **1013776544**

1994	JEFFS AUTO BODY REPAIR INC	General Automotive Repair Shops
1995	JEFFS AUTO BODY REPAIR INC	General Automotive Repair Shops
1996	JEFFS AUTO BODY REPAIR INC	General Automotive Repair Shops

---

AG173 **SOUTHERN UNION GAS CO** **DOT OPS** **1009630634**
Target **6615 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78751**

Site 5 of 14 in cluster AG

Actual:
713 ft.

Focus Map:
6

DOT OPS:

Name:	SOUTHERN UNION GAS CO
Address:	6615 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78751

Natural Gas Distribution 1984 - 2004:

Operator ID:	18532
Date of Incident:	19910713

Click this hyperlink while viewing on your computer to access additional DOT OPS: detail in the EDR Site Report.

AH174 **TASTE OF INK** **TX ASBESTOS** **S119158202**
Target **6541 N LAMAR BLVD #B** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 8 in cluster AH

Actual:
714 ft.

Focus Map:
6

ASBESTOS:

Name:	TASTE OF INK
Address:	6541 N LAMAR BLVD #B
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	03/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	1.75
Mileage:	7.7
Reg:	07
Init:	MAO
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Margaret Olsovsky
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

TASTE OF INK (Continued) **S119158202**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TASTE OF INK
Address:	6541 N LAMAR BLVD #B
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/12/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	2
Travel Time:	1.5

TASTE OF INK (Continued) **S119158202**

Mileage:	5.3
Reg:	07
Init:	MAO
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Margaret Olsovsky
Date Report Received:	04/15/2013
Date Routed by Supervisor:	04/15/2013
Date Routed to PSQA:	04/16/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AH175 RAYS GARAGE **TX CENTRAL REGISTRY** **S126525048**
Target 6517 N LAMAR BLVD **N/A**
Property AUSTIN, TX 78752

Site 2 of 8 in cluster AH

Actual: 714 ft.

Focus Map: 6

CENTRAL REGISTRY:

Regulated Entity Number:	RN101510089
Name:	RAYS GARAGE
Address:	6517 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	2/26/2002
Customer Number:	CN600787253
Customer Name:	PILLACK, RAY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/4/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AH176 RAYS GARAGE **EDR Hist Auto** **1013767346**
Target 6517 LAMAR BLVD N **N/A**
Property AUSTIN, TX 78752

Site 3 of 8 in cluster AH

Actual: 714 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1970	RAYS GARAGE	AUTOMOBILE GARAGES
1971	RAYS GARAGE	General Automotive Repair Shops
1972	RAYS GARAGE	General Automotive Repair Shops
1973	RAYS GARAGE	General Automotive Repair Shops
1974	RAYS GARAGE	General Automotive Repair Shops
1975	RAYS GARAGE	AUTOMOBILE REPAIRING
1975	RAYS GARAGE	General Automotive Repair Shops
1976	RAYS GARAGE	General Automotive Repair Shops
1977	RAYS GARAGE	General Automotive Repair Shops
1978	RAYS GARAGE INC	General Automotive Repair Shops
1979	RAYS GARAGE INC	General Automotive Repair Shops
1980	RAVS GARAGE	AUTOMOBILE REPAIRING
1980	RAYS GARAGE INC	General Automotive Repair Shops
1982	RAYS GARAGE	General Automotive Repair Shops
1983	RAYS GARAGE	General Automotive Repair Shops
1984	RAYS GARAGE	AUTOMOBILE REPAIRING
1985	RAYS GARAGE	General Automotive Repair Shops
1986	RAYS GARAGE	General Automotive Repair Shops
1987	RAYS GARAGE	General Automotive Repair Shops
1988	RAYS GARAGE	General Automotive Repair Shops
1989	RAYS GARAGE	General Automotive Repair Shops
1990	RAYS GARAGE	General Automotive Repair Shops
1991	RAYS GARAGE	General Automotive Repair Shops
1992	RAYS GARAGE	General Automotive Repair Shops
1993	RAYS GARAGE	General Automotive Repair Shops
1994	RAYS GARAGE	General Automotive Repair Shops

RAYS GARAGE (Continued) **1013767346**

1995	RAYS GARAGE	General Automotive Repair Shops
1996	RAYS GARAGE	General Automotive Repair Shops
1997	RAYS GARAGE	General Automotive Repair Shops
1998	RAYS GARAGE	General Automotive Repair Shops
1999	RAYS GARAGE	General Automotive Repair Shops
2000	RAYS GARAGE	General Automotive Repair Shops
2001	RAYS GARAGE	General Automotive Repair Shops
2002	RAYS GARAGE	General Automotive Repair Shops
2003	RAYS GARAGE	General Automotive Repair Shops
2004	RAYS GARAGE	General Automotive Repair Shops
2005	RAYS GARAGE	General Automotive Repair Shops
2006	RAYS GARAGE	General Automotive Repair Shops
2007	RAYS GARAGE	General Automotive Repair Shops
2008	RAYS GARAGE	General Automotive Repair Shops
2009	RAYS GARAGE	General Automotive Repair Shops
2010	RAYS GARAGE	General Automotive Repair Shops
2011	YOST AUTOMOTIVE II	Automotive Repair Shops, NEC
2012	YOST AUTOMOTIVE II LLC	Automotive Repair Shops, NEC
2013	YOST AUTOMOTIVE II LLC	Automotive Repair Shops, NEC
2013	YOST AUTOMOTIVE LLC	General Automotive Repair Shops
2014	YOST AUTOMOTIVE LLC	General Automotive Repair Shops
2014	YOST AUTOMOTIVE II LLC	Automotive Repair Shops, NEC

AH177 **RAYS GARAGE** **TX UST** **U001279863**
Target **6517 N LAMAR BLVD** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78752**

Site 4 of 8 in cluster AH

Actual:
714 ft.

Focus Map:
6

UST:

Name:	RAYS GARAGE
Address:	6517 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524009
AI Number:	48798
Facility Type:	RETAIL
Facility Begin Date:	08/04/1989
Facility Status:	INACTIVE
Additional ID:	849686242002057
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	RAY PILLACK,OWNER
Contact Organization Name:	RAYS GARAGE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124512236
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/26/1989
Signature Name/Title On Earliest Reg Form:	RAY PILLACK,OWNER

RAYS GARAGE (Continued) **U001279863**

Application Received Date On Earliest Reg Form:	07/31/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600787253
Owner Last Name:	PILLACK
Owner First Name:	RAY
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	839686212002057
Additional ID:	849686242002057
AI Number:	48798
Owner Effective Begin Date:	08/04/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	07/31/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	126867
Facility ID:	80539
Ai Number:	48798
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/14/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

RAYS GARAGE (Continued) **U001279863**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/01/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	132233
UST ID:	126867
AI Number:	48798
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

RAYS GARAGE (Continued) **U001279863**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PILLACK RAY
Contact Mailing Address (Delivery):	1800 REDLANDS ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78757 2826
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80539
Additional ID:	849686242002057
Princ ID:	839686212002057
AI Number:	48798
Facility Name:	RAYS GARAGE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	RAY'S GARAGE
Address:	6517 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0056
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AH178 Target Property

WOODS HONDA
6509 N LAMAR BLVD
AUSTIN, TX 78752

Site 5 of 8 in cluster AH

TX LPST **U001241002**
TX UST **N/A**
TX HIST UST
TX Ind. Haz Waste
TX CENTRAL REGISTRY

Actual: 714 ft.

Focus Map: 6

LPST:

Name:	WOODS HONDA FUN CENTER
Address:	6509 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0004263
LPST Id:	104753
Facility Location:	6509 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/23/1992
Entered Date:	01/23/1995
Reported Date:	09/25/1992
Closure Date:	12/04/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	MARK WOODS
Responsible Party Address:	6509 N LAMAR
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/459-3311
Reported Date:	09/25/1992
Case Start Date:	12/04/1992
Reference Number:	RN100562412
Project Manager:	HWELCH

UST:

Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524009
AI Number:	4263
Facility Type:	UNKNOWN
Facility Begin Date:	06/19/1986
Facility Status:	INACTIVE
Additional ID:	955090002002069
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	WOODS HONDA
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

WOODS HONDA (Continued) **U001241002**

Contact Telephone:	5124593311
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1986
Signature Name/Title On Earliest Reg Form:	MARK WOODS,PRESIDENT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600273171
Owner Last Name:	WOODS HONDA
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	700320162001297
Additional ID:	955090002002069
AI Number:	4263
Owner Effective Begin Date:	06/19/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	10385
Facility ID:	42953
Ai Number:	4263
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

WOODS HONDA (Continued) **U001241002**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	14075
UST ID:	10385
AI Number:	4263
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

WOODS HONDA (Continued) **U001241002**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	10386
Facility ID:	42953
Ai Number:	4263
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

WOODS HONDA (Continued) **U001241002**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	14076
UST ID:	10386
AI Number:	4263
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

WOODS HONDA (Continued) **U001241002**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WOODS HONDA
Contact Mailing Address (Delivery):	6509 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 4009
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	42953
Additional ID:	955090002002069
Princ ID:	700320162001297
AI Number:	4263
Facility Name:	WOODS HONDA
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	WOODS FUN CENTER
Address:	6509 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0350
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD

WOODS HONDA (Continued) **U001241002**

City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61325
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6509 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	WOODS HONDA
Contact Name:	TOM JOHNSON
Contact Telephone Number:	Not reported
Mailing Address:	6509 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524009
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19679
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	WOODS HONDA
Owner Mailing Address:	6509 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	Not reported

WOODS HONDA (Continued) **U001241002**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6509 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	TOM JOHNSON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6509 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600273171
Customer Name:	WOODS HONDA
Customer Legal Name:	Woods Honda
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	6/19/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########

WOODS HONDA (Continued) **U001241002**

Customer Number:	CN605021948
Customer Name:	WOODS HONDA KAWASAKI YAMAHA SEADOO
Customer Legal Name:	Woods Honda Kawasaki Yamaha Seadoo
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604440305
Customer Name:	WOODS HONDA FUN CENTER
Customer Legal Name:	Woods Honda Fun Center
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600273171
Customer Name:	WOODS HONDA
Customer Legal Name:	Woods Honda
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	6/19/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605021948
Customer Name:	WOODS HONDA KAWASAKI YAMAHA SEADOO
Customer Legal Name:	Woods Honda Kawasaki Yamaha Seadoo

WOODS HONDA (Continued) **U001241002**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604440305
Customer Name:	WOODS HONDA FUN CENTER
Customer Legal Name:	Woods Honda Fun Center
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600273171
Customer Name:	WOODS HONDA
Customer Legal Name:	Woods Honda
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	6/19/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6509 N Lamar, Austin, TX

Regulated Entity Number:	RN100562412
Name:	WOODS HONDA
Address:	6509 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4009
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605021948
Customer Name:	WOODS HONDA KAWASAKI YAMAHA SEADOO
Customer Legal Name:	Woods Honda Kawasaki Yamaha Seadoo
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000

WOODS HONDA (Continued) **U001241002**

Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 6509 N Lamar, Austin, TX

Regulated Entity Number: RN100562412
Name: WOODS HONDA
Address: 6509 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4009
Status: ACTIVE
Status Date: ##########
Customer Number: CN604440305
Customer Name: WOODS HONDA FUN CENTER
Customer Legal Name: Woods Honda Fun Center
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 6509 N Lamar, Austin, TX

Regulated Entity Number: RN100562412
Name: WOODS HONDA
Address: 6509 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4009
Status: ACTIVE
Status Date: ##########
Customer Number: CN600273171
Customer Name: WOODS HONDA
Customer Legal Name: Woods Honda
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 6/19/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 6509 N Lamar, Austin, TX

Regulated Entity Number: RN100562412
Name: WOODS HONDA
Address: 6509 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4009
Status: ACTIVE
Status Date: ##########
Customer Number: CN600273171
Customer Name: WOODS HONDA
Customer Legal Name: Woods Honda
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 6/19/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported

WOODS HONDA (Continued) **U001241002**

Physical Location Description: 6509 N Lamar, Austin, TX

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

AH179 **WOODS HOND** **EDR Hist Auto** **1013755745**
Target **6509 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78752**

Site 6 of 8 in cluster AH

Actual:
714 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1975	WOODS HOND	MOTORCYCLE DEALERS AND REPAIRERS
1980	WOODS HOND	MOTORCYCLE DEALERS AND REPAIRERS
1984	WOODS HONDA MTR CYCLE	MOTORCYCLE DEALERS AND REPAIRERS
1990	WOODS HONDA MTR CYCLE	MOTORCYCLE DEALERS AND REPAIRERS

AI180 **JIFFV BRAKE SERVICE AUTO REPR** **EDR Hist Auto** **1013769641**
Target **6322 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 8 in cluster AI

Actual:
712 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1962	JIFFY BRAKE SERV	AUTOMOBILE REPAIRING
1965	JIFFY BRAKE SERVICE AUTO	AUTOMOBILE REPAIRING
1970	JIFFY BRAKE SERVICE AUTO REPR	AUTOMOBILE REPAIRING
1975	JIFLY BRAKE SERVICE AUTO REPR	AUTOMOBILE REPAIRING
1980	JIFFV BRAKE SERVICE AUTO REPR	AUTOMOBILE REPAIRING
1984	JIFFY BRAKE SERVICE	AUTOMOBILE REPAIRING

AJ181 **EARLS LAWN GARDEN EQUIPMENT** **TX Ind. Haz Waste** **S102748126**
Target **6216 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 13 in cluster AJ

Actual:
709 ft.

Ind. Haz Waste:

Focus Map:
9

Name:	EARLS LAWN GARDEN EQUIPMENT
Address:	6216 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61187
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	05/01/1987
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6216 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported

EARLS LAWN GARDEN EQUIPMENT (Continued) **S102748126**

Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	EARLS LAWN GARDEN EQUIPMENT
Contact Name:	LAURIE DAVIS
Contact Telephone Number:	Not reported
Mailing Address:	6216 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524004
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19548
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030408
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	EARLS LAWN GARDEN EQUIPMENT
Operator Address:	6216 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EARLS LAWN GARDEN EQUIPMENT
Owner Mailing Address:	6216 N LAMAR BLVD
Owner Mailing Address 2:	Not reported

EARLS LAWN GARDEN EQUIPMENT (Continued) **S102748126**

Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6216 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6216 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LAURIE DAVIS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6216 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100638022
Name:	EARLS LAWN GARDEN EQUIPMENT
Address:	6216 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600348577
Customer Name:	EARLS LAWN GARDEN EQUIPMENT
Customer Legal Name:	Earls Lawn Garden Equipment

EARLS LAWN GARDEN EQUIPMENT (Continued) **S102748126**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/1/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6216 N Lamar, Austin, TX

AJ182 **EARLS AIR COOLED ENGINE SERVICE** **EDR Hist Auto** **1013756964**
Target **6218 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX 78752**

Site 2 of 13 in cluster AJ

Actual: EDR Hist Auto
709 ft.

Focus Map:
9

Year:	Name:	Type:
1975	EARLS AIR COOLED ENGINE SERVICE	AUTOMOBILE REPAIRING
1980	EARLS AIR COOLED ENGINE SERVICE	AUTOMOBILE REPAIRING

AJ183 **VIOLET CROWN CLNRS** **EDR Hist Cleaner** **1013778425**
Target **6218 LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 3 of 13 in cluster AJ

Actual: EDR Hist Cleaner
709 ft.

Focus Map:
9

Year:	Name:	Type:
1953	VIOLET CROWN CLNRS	CLEANERS AND DYERS

AJ184 **LYLES CHEMICAL & SUPPLY CO.** **TX HIST UST** **S111678726**
Target **6208 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 4 of 13 in cluster AJ

Actual: HIST UST AUSTIN:
709 ft.

Focus Map:
9

Name:	LYLES CHEMICAL & SUPPLY CO.
Address:	6208 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0436
HID UST:	436
Inspection:	Not reported
Due:	06/01/2012

AJ185 Target Property | **TJS CYCLE SALES & SERVICE**
6208 N LAMAR BLVD
AUSTIN, TX 78752 | **TX CENTRAL REGISTRY** | **S126891953**
N/A

Site 5 of 13 in cluster AJ

Actual: 709 ft.

Focus Map: 9

CENTRAL REGISTRY:

Regulated Entity Number:	RN108823147
Name:	TJS CYCLE SALES & SERVICE
Address:	6208 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604961771
Customer Name:	TJS CYCLE SALES & SERVICE
Customer Legal Name:	Tjs Cycle Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108823147
Name:	TJS CYCLE SALES & SERVICE
Address:	6208 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604961771
Customer Name:	TJS CYCLE SALES & SERVICE
Customer Legal Name:	Tjs Cycle Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108823147
Name:	TJS CYCLE SALES & SERVICE
Address:	6208 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN605031038
Customer Name:	PERFORMANCE TIRE
Customer Legal Name:	Performance Tire
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

TJS CYCLE SALES & SERVICE (Continued) **S126891953**

Physical Location Description:	Not reported
Regulated Entity Number:	RN108823147
Name:	TJS CYCLE SALES & SERVICE
Address:	6208 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN605031038
Customer Name:	PERFORMANCE TIRE
Customer Legal Name:	Performance Tire
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AJ186 **RICKS SALES CO.** **TX HIST UST** **S111678792**
Target **6205 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 6 of 13 in cluster AJ

Actual: 709 ft.
Focus Map: 9

HIST UST AUSTIN:

Name:	RICKS SALES CO.
Address:	6205 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0437
HID UST:	437
Inspection:	Not reported
Due:	06/01/2012

AJ187 **SWANNS GARAGE & RADIATOR** **TX UST** **U001293072**
Target **6203 N LAMAR BLVD** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78752**

Site 7 of 13 in cluster AJ

Actual: 707 ft.
Focus Map: 9

UST:

Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524003
AI Number:	64126
Facility Type:	RETAIL
Facility Begin Date:	01/21/1993
Facility Status:	INACTIVE
Additional ID:	273741662002154
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	SWANNS GARAGE & RADIATOR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128340487
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/12/1993
Signature Name/Title On Earliest Reg Form:	JEFF BOYKO,PROJ MANAGER
Application Received Date On Earliest Reg Form:	01/20/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601261761
Owner Last Name:	HIGDON
Owner First Name:	BETTY
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	282741652002154
Additional ID:	273741662002154
AI Number:	64126
Owner Effective Begin Date:	01/21/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147569
Facility ID:	95078

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Ai Number:	64126
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	157021

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	147569
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023
UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026
UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147570
Facility ID:	95078
Ai Number:	64126
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	5
Tank Capacity:	1000
UST Comprt ID:	157022
UST ID:	147570
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017
UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026
UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147571
Facility ID:	95078
Ai Number:	64126
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	6
Tank Capacity:	500
UST Comprt ID:	157023
UST ID:	147571
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023
UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017
UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026
UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147572
Facility ID:	95078
Ai Number:	64126
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	157024
UST ID:	147572
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023
UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017
UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026
UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147573
Facility ID:	95078
Ai Number:	64126
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	157025
UST ID:	147573
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023
UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017
UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/20/1993
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	147574
Facility ID:	95078
Ai Number:	64126
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/15/1989

Compartment Records:

Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	157026
UST ID:	147574
AI Number:	64126
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24896
Cert ID:	140024
UST Comprt ID:	411321
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140023
UST Comprt ID:	411322
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	303134
UST Comprt ID:	876625
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	319902
UST Comprt ID:	926640
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	336444
UST Comprt ID:	976130
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	353443
UST Comprt ID:	1027601

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	370760
UST Comprt ID:	1079948
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140015
UST Comprt ID:	411328
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140016
UST Comprt ID:	411329
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140017
UST Comprt ID:	411330
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140018
UST Comprt ID:	411327
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140019
UST Comprt ID:	411326
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140020
UST Comprt ID:	411325
UST ID:	146372

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140026
UST Comprt ID:	411319
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	224958
UST Comprt ID:	645336
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	241772
UST Comprt ID:	694602
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	246477
UST Comprt ID:	708629
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	253166
UST Comprt ID:	727993
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	269845
UST Comprt ID:	777407
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	292972
UST Comprt ID:	846139
UST ID:	146372
AI Number:	64126

SWANNS GARAGE & RADIATOR (Continued) **U001293072**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140021
UST Comprt ID:	411324
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140022
UST Comprt ID:	411323
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24896
Cert ID:	140025
UST Comprt ID:	411320
UST ID:	146372
AI Number:	64126
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	HIGDON BETTY
Contact Mailing Address (Delivery):	11508 OAKWOOD DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 2729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95078
Additional ID:	273741662002154
Princ ID:	282741652002154
AI Number:	64126
Facility Name:	SWANNS GARAGE & RADIATOR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BETTY HIGDON/

HIST UST AUSTIN:

Name:	SWAN'S GARAGE
Address:	6203 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0509
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AJ188 **NORTH LAMAR AUTOMOTIVE** **EDR Hist Auto** **1013764393**
Target **6203 LAMAR BLVD N** **N/A**
Property **TRAVIS (County), TX 78752**

Site 8 of 13 in cluster AJ

Actual:
707 ft.

EDR Hist Auto

Focus Map:
9

Year:	Name:	Type:
1953	RICKS SALES CO	GASOLINE STATIONS
1958	RICKS SLS CO FILLING	GASOLINE STATIONS
1962	RICKS SLS CO GAS	GASOLINE STATIONS
1965	NORTH LAMAR AUTOMOTIVE	AUTOMOBILE REPAIRING
1965	NORTH LAMAR MOBIL SERVICE	GASOLINE STATIONS
1970	NORTH LAMAR AUTOMOTIVE	AUTOMOBILE REPAIRING
1970	NORTH LAMAR MOBIL SERVICE STATI	GASOLINE STATIONS
1971	NORTH LAMAR AUTOMTV SV STN GAR	Gasoline Service Stations
1973	SWANN J HUGH	General Automotive Repair Shops
1980	SWANNS GARAGE&RADIATOR	AUTOMOBILE REPAIRING
1980	SWANN J HUGH	General Automotive Repair Shops
1982	SWANN J HUGH	General Automotive Repair Shops
1983	SWANN J HUGH	General Automotive Repair Shops
1984	SWANNS RADIATOR & GARAGE INC	AUTOMOBILE REPAIRING
1985	SWANN J HUGH	General Automotive Repair Shops
1986	SWANN J HUGH	General Automotive Repair Shops
1987	SWANN J HUGH	General Automotive Repair Shops
1988	SWANN J HUGH	General Automotive Repair Shops
1989	SWANNS GARAGE AND RADIATOR INC	General Automotive Repair Shops
1990	SWANNS GARAGE & RADIATOR SHOP I	AUTOMOBILE REPAIRING
1990	SWANNS GARAGE AND RADIATOR INC	General Automotive Repair Shops
1991	SWANNS GARAGE AND RADIATOR	General Automotive Repair Shops
1992	SWANNS GARAGE AND RADIATOR	General Automotive Repair Shops

---

AJ189 **SWANNS GARAGE RADIATOR** **TX LPST** **S102748212**
Target **6203 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
Property **AUSTIN, TX 78753**

Site 9 of 13 in cluster AJ

Actual:
707 ft.

LPST:

Focus Map:
9

Name:	SWANNS GARAGE RADIATOR
Address:	6203 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0064126
LPST Id:	104480
Facility Location:	6203 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	01/07/1992
Entered Date:	10/02/1992
Reported Date:	09/03/1992
Closure Date:	04/16/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	SMO
Responsible Party Name:	Not reported

SWANNS GARAGE RADIATOR (Continued) **S102748212**

Responsible Party Contact:	BETTY HIGDON
Responsible Party Address:	712 DENSON
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	/-
Reported Date:	09/03/1992
Case Start Date:	04/16/1993
Reference Number:	RN100621788
Project Manager:	SMO

Ind. Haz Waste:

Name:	SWANNS GARAGE
Address:	6203 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61288
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/15/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6203 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Contact Name:	DIANA WALLMAN
Contact Telephone Number:	Not reported
Mailing Address:	6203 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524003
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19644
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020115
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported

SWANNS GARAGE RADIATOR (Continued) **S102748212**

Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Operator Address:	6203 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17421861869
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Owner Mailing Address:	6203 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17421861869
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6203 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6203 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DIANA WALLMAN

SWANNS GARAGE RADIATOR (Continued) **S102748212**

Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6203 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

AJ190 **SWANNS GARAGE & RADIATOR** **TX CENTRAL REGISTRY** **S123846013**
Target **6203 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 10 of 13 in cluster AJ

Actual:
707 ft.

Focus Map:
9

CENTRAL REGISTRY:

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600330682
Customer Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Customer Legal Name:	SWANN'S GARAGE AND RADIATOR SHOP, INC.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601261761
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/21/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported

SWANNS GARAGE & RADIATOR (Continued) **S123846013**

City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604439133
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600330682
Customer Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Customer Legal Name:	SWANN'S GARAGE AND RADIATOR SHOP, INC.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601261761
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/21/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########

SWANNS GARAGE & RADIATOR (Continued) **S123846013**

Customer Number:	CN604439133
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600330682
Customer Name:	SWANNS GARAGE AND RADIATOR SHOP INC
Customer Legal Name:	SWANN'S GARAGE AND RADIATOR SHOP, INC.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601261761
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/21/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

Regulated Entity Number:	RN100621788
Name:	SWANNS GARAGE & RADIATOR
Address:	6203 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4003
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604439133
Customer Name:	HIGDON, BETTY
Customer Legal Name:	Not reported

SWANNS GARAGE & RADIATOR (Continued) **S123846013**

Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6203 N Lamar, Austin, TX

AK191 **DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS** **TX ASBESTOS** **S121062714**
Target **5808 NORTH LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 23 in cluster AK

Actual:
704 ft.

Focus Map:
8

ASBESTOS:

Name:	DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/05/2016
Notification Number:	2016004218
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/04/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/04/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/19/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017002541
File Number:	18920
License Status Description:	Current
Expiration Date:	05/13/2017
Original Date:	03/30/2017
Rank Effective Date:	03/30/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	5931
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/07/2016
Notification Number:	2016003415
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/06/2016
Certification Statement Phone:	512-260-7170
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/09/2016
Notification Number:	2016003415
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/25/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/25/2016
Certification Statement Phone:	512-260-7170
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/19/2017
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/13/2017
Notification Number:	2017002541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/30/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/30/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Analytical Method:	PLM
Start Date:	04/13/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY - HQ BLDG A
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/03/2017
Notification Number:	2017006044
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/11/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Work Type Flag:	A
Certification Statement Date:	08/11/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/26/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY - HQ BLDG A
Address:	5808 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/24/2017
Notification Number:	2017006486
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/05/2017
Date Routed by Supervisor:	Not reported

DEPARTMENT OF PUBLIC SAFETY NORTH LAMAR CAMPUS (Continued) **S121062714**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/05/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/23/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK192 Target Property | **NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN**
5802 N LAMAR BOULEVARD
AUSTIN, TX 78752 | **FINDS** **ECHO** | **1026456563** **N/A**

Site 2 of 23 in cluster AK

Actual: 703 ft.
Focus Map: 8

FINDS:
Registry ID: 110070816468

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1026456563
Registry ID:	110070816468
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070816468
Name:	NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN
Address:	5802 N LAMAR BOULEVARD
City,State,Zip:	AUSTIN, TX 78752

AK193 Target Property | **NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN**
5802 N LAMAR BOULEVARD
AUSTIN, TX 78752 | **TX COMP HIST** **TX CENTRAL REGISTRY** | **S126971496** **N/A**

Site 3 of 23 in cluster AK

Actual: 703 ft.
Focus Map: 8

COMP HIST:

RN Number:	RN111061289
Name:	NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603989880
CN Name:	MGC CONTRACTORS INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	1611
Related Number:	TXR1512CN,TXR1512CN

CENTRAL REGISTRY:

Regulated Entity Number:	RN111061289

NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN (Continued) **S126971496**

Name:	NORTH AUSTIN RESERVOIR AND PUMP STATION IMPROVEMEN
Address:	5802 N LAMAR BOULEVARD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-
Status:	ACTIVE
Status Date:	2020-06-26
Customer Number:	CN603989880
Customer Name:	MGC CONTRACTORS INC
Customer Legal Name:	MGC CONTRACTORS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2020-06-26
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AK194 **NORTH AUSTIN RESERVOIR & PUMP STATION** **TX ASBESTOS** **S127037177**
Target **5802 N. LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 4 of 23 in cluster AK

Actual:
703 ft.

Focus Map:
8

ASBESTOS:

Name:	NORTH AUSTIN RESERVOIR & PUMP STATION
Address:	5802 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	10/30/2020
Notification Number:	2020006157
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement

NORTH AUSTIN RESERVOIR & PUMP STATION (Continued) **S127037177**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/12/2020
Certification Statement Phone:	512-751-4007
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/26/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NORTH AUSTIN RESERVOIR & PUMP STATION
Address:	5802 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	10/30/2020
Notification Number:	2020006157
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/07/2020

NORTH AUSTIN RESERVOIR & PUMP STATION (Continued) **S127037177**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/07/2020
Certification Statement Phone:	512-751-4007
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/28/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK195 Target Property | **DEPARTMENT OF PUBLIC SAFETY COMPLEX 5805 N. LAMAR DEPARTMENT OF PUBLIC SAFETY COMPLEX 5805 N. LAMAR BLVD., AUS , TX** | **TX SPILLS** | **S107010732 N/A**

Site 5 of 23 in cluster AK

Actual: 703 ft.

Focus Map: 8

SPILLS:

Name:	DEPARTMENT OF PUBLIC SAFETY COMPLEX 5805 N. LAMAR BLVD., AUST
Address:	DEPARTMENT OF PUBLIC SAFETY COMPLEX 5805 N. LAMAR BLVD., AUST
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	06/10/1994
Seq Num:	17
Responsible Party Name:	TX. DEPT. OF PUBLIC SAFETY
Responsible Party Address:	5805 N. LAMAR
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78752
Responsible Party Telephone:	5124652167
Substance:	DIESEL
Material Code:	1040
Media Affected:	Not reported
Permit Number:	NONE
District:	11
Origin:	001
Cause:	003
Basin Code:	1429
Notify Date:	Not reported
Adequate Clean:	003
Classification:	003
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	712 GAL
Amnt in Water:	NONE GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	H. JANUS
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported

DEPARTMENT OF PUBLIC SAFETY COMPLEX 5805 N. LAMAR BLVD., AUS (Continued) **S107010732**

Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

AK196 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **PRP** **1026643600**
Target **5805 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 6 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

PRP:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Superfund EPAID:	TXD980864789
Superfund Name:	MALONE SERVICE CO - SWAN LAKE PLANT
Superfund Address:	LOOP 197 S
Superfund City,State,Zip:	TEXAS CITY, TX 77590
NPL Status:	Currently on the Final NPL
NPL Status Short Name:	Not reported
Data Type:	Not reported
Action Date:	Not reported
Settlement Code:	Not reported
Settlement:	Not reported
Latitude:	29.333056
Longitude:	-94.902778

AK197 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **PRP** **1026643599**
Target **5805 NORTH LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78752**

Site 7 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

PRP:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Superfund EPAID:	TXD980864789
Superfund Name:	MALONE SERVICE CO - SWAN LAKE PLANT
Superfund Address:	LOOP 197 S
Superfund City,State,Zip:	TEXAS CITY, TX 77590
NPL Status:	Currently on the Final NPL
NPL Status Short Name:	Not reported
Data Type:	SETTLEMENT DATE
Action Date:	6/26/2012
Settlement Code:	AC-7
Settlement:	ADM ORDR
Latitude:	29.333056
Longitude:	-94.902778

AK198 Target Property | **TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS**
5805 N LAMAR, AUSTIN, TX
AUSTIN, TX 78752

TX SPILLS
TX ASBESTOS
TX ENF

S107641089
N/A

Site 8 of 23 in cluster AK

Actual: 702 ft.

Focus Map: 8

SPILLS:

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR, AUSTIN, TX
City,State,Zip:	AUSTIN, TX 78752
Incident Number:	1323
Facility Id:	RN101721728
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	Not reported
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11 - AUSTIN
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	unknown
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	Not reported
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	No Incident Type
Near City Name:	AUSTIN
Importance Level:	6
Received Date:	01/24/2002
Start Date:	01/23/2002
Status Date:	06/05/2002
Media Name:	AIR
Customer:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Effect:	GENERAL
Num Complaining:	1
Frequency:	PAST
Nature:	OTHER
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Closed

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S107641089**

Disputed Status:	Not reported
Disputed Date:	01/01/1900
Comments:	This complaint was received on 01/24/2002 at 8:51 a.m.
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

ASBESTOS:

Name:	TEXAS DEPT. OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	05/30/2014
Reason for Inspection:	Notified
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	2014003513
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	07/16/2014
Date Routed by Supervisor:	08/04/2014
Date Routed to PSQA:	08/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S107641089**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600610976
Unique TCEQ Ref Number Of Reg. Entity:	RN101721728
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	05/31/2002
Description 1:	Partial failure to maintain data required to document compliance with incinerator design requirements
Description 2:	Not reported
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	AIR
TCEQ Rule Number Cited For The Violation:	106.491(1)(A)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S107641089**

Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600610976
Unique TCEQ Ref Number Of Reg. Entity:	RN101721728
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	05/31/2002
Description 1:	Failure to maintain complete records of the materials incinerated at the facility.
Description 2:	Not reported
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	AIR
TCEQ Rule Number Cited For The Violation:	106.491(2)(C)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600610976
Unique TCEQ Ref Number Of Reg. Entity:	RN101721728
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Regulated Entity Associated With An NOV:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S107641089**

Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	05/31/2002
Description 1:	Complete failure to maintain required document.
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	AIR
TCEQ Rule Number Cited For The Violation:	106.491(2)(D)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

AK199 **TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS** **RCRA NonGen / NLR** **1000156888**
Target **5805 N LAMAR** **FINDS** **TXD981901770**
Property **AUSTIN, TX 78752** **ECHO**

Site 9 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20020115
Handler Name:	Texas Department Of Public Safety
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD981901770
Contact Name:	D PAT JOHNSON
Contact Address:	PO BOX 4143
Contact City,State,Zip:	AUSTIN, TX 78765
Contact Telephone:	512-465-2105
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **1000156888**

State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 4143
Mailing City,State,Zip:	AUSTIN, TX 78765
Owner Name:	Texas Department Of Public Safety
Owner Type:	Municipal
Operator Name:	Texas Department Of Public Safety
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **1000156888**

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U117
Waste Description: Ethane, 1,1'-Oxybis-(I) (Or) Ethyl Ether (I)

Waste Code: U123
Waste Description: Formic Acid (C,T)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Legal Status: Municipal
Date Became Current: 20020115
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4143
Owner/Operator City,State,Zip: AUSTIN, TX 78765
Owner/Operator Telephone: 512-465-2105
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Legal Status: Municipal
Date Became Current: 20020115
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4143
Owner/Operator City,State,Zip: AUSTIN, TX 78765
Owner/Operator Telephone: 512-465-2105
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19971211
Handler Name: TEXAS DEPT OF PUBLIC SAFETY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **1000156888**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020115
Handler Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005097625

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000156888
Registry ID: 110005097625

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **1000156888**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005097625
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX 78752

AK200 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **TX TIER 2** **S108441521**
Target **5805 N. LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78752**

Site 10 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

TIER 2:

Facility Id:	FATR20124Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/20/2013
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Philip Johnson
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20114Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	1/5/2012
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Philip B. Johnson

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20094Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	3/1/2010
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Andy Mokry
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20084Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	3/9/2009
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Andrew Mokry
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20074Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	2/28/2008
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Andrew Mokry
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20064Z3ZHU01FQYJ
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2-28-2007
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Andrew Mokry
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR200549ERLD0185T1
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Reporting Year:	2005
Facility Country:	USA
Facility Department:	Texas Department of Public Safety
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	Not reported
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Andrew Mokry
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Notes: Not reported
Validation: Not reported

Facility Info:
Id: Not reported
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 2/28/2007
Id: 92114
Id Type: NAICS
Description: Not reported
Last Modified: 3/9/2009
Id: 9131
Id Type: SIC
Description: EXEC & LEGIS OFFICES COMBINED
Last Modified: 2/28/2007

Contact:
Contact Email: philip.johnson@txdps.state.tx.us
Contact Mail Address: PO Box 4087
Contact City/State/Zip: Austin, TX 78773
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Name: Philip Johnson
Title: Environmental Coordinator
Modification Date: 3/9/2009

Contact Email: philip.johnson@txdps.state.tx.us
Contact Mail Address: PO Box 4087
Contact City/State/Zip: Austin, TX 78773
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Name: Philip Johnson
Title: Environmental Coordinator
Modification Date: 3/9/2009

Contact:
Contact Email: Not reported
Contact Mail Address: 5805 N. Lamar Blvd.
Contact City/State/Zip: Austin, TX 78752
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Owner / Operator
Contact Name: Tommy Wright
Title: Not reported
Modification Date: 2/24/2013

Chemical Inventory:
Facility Id: FATR20124Z3ZHU01FQYJ
Chemical Name: Diesel Fuel
Chemical Inv Record Id: CVTR20124Z3ZM301QJJ2
CAS Number: 68476-34-6
Chemical Same As Last Year: Not reported
Acute Health Risks: T

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	43482
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/24/2013
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20124Z3ZNB01RLYL
Chemical Inventory Record Id:	CVTR20124Z3ZM301QJJ2
Amt Of Sub Stored Or Transported:	6000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Rear of main building, west of courtyard.
Last Modified:	2/24/2013

Notes:	Not reported
Validation:	Not reported

Facility Info:

Id:	9131
Id Type:	SIC
Description:	EXEC & LEGIS OFFICES COMBINED
Last Modified:	2/28/2007
Id:	92114
Id Type:	NAICS
Description:	Not reported
Last Modified:	3/9/2009
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/28/2007

Contact:

Contact Email:	philip.johnson@txdps.state.tx.us
Contact Mail Address:	PO Box 4087
Contact City/State/Zip:	Austin, TX 78773
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Philip Johnson

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Title:	Environmental Coordinator
Modification Date:	3/9/2009
Contact Email:	philip.johnson@txdps.state.tx.us
Contact Mail Address:	PO Box 4087
Contact City/State/Zip:	Austin, TX 78773
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Philip Johnson
Title:	Environmental Coordinator
Modification Date:	3/9/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	5805 N. Lamar Blvd.
Contact City/State/Zip:	Austin, TX 78752
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Tommy Wright
Title:	Not reported
Modification Date:	2/6/2012

Chemical Inventory:

Facility Id:	FATR20114Z3ZHU01FQYJ
Chemical Name:	Diesel Fuel
Chemical Inv Record Id:	CVTR20114Z3ZM301QJJ2
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	43482
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/6/2012
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20114Z3ZNB01RLYL
Chemical Inventory Record Id:	CVTR20114Z3ZM301QJJ2
Amt Of Sub Stored Or Transported:	6000
Amount Units:	gallons

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Rear of main building, west of courtyard.
Last Modified: 2/6/2012

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 92114
Id Type: NAICS
Description: Not reported
Last Modified: 3/9/2009
Id: Not reported
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 2/28/2007
Id: 9131
Id Type: SIC
Description: EXEC & LEGIS OFFICES COMBINED
Last Modified: 2/28/2007

Contact:
Contact Email: Not reported
Contact Mail Address: 5805 N. Lamar Blvd.
Contact City/State/Zip: Austin, TX 78752
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Owner / Operator
Contact Name: Tommy Wright
Title: Not reported
Modification Date: 3/3/2010

Contact:
Contact Email: Not reported
Contact Mail Address: PO Box 4087
Contact City/State/Zip: Austin, TX 78773
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Name: Philip Johnson
Title: Environmental Coordinator
Modification Date: 3/9/2009

Chemical Inventory:
Facility Id: FATR20094Z3ZHU01FQYJ
Chemical Name: Diesel Fuil
Chemical Inv Record Id: CVTR20094Z3ZM301QJJ2
CAS Number: 68476-34-6
Chemical Same As Last Year: Not reported
Acute Health Risks: T
Average Daily Amount: 10,000 - 99,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S108441521**

Max Amount In Largest Container:	43482
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/3/2010
Days On Site:	365
Fire Hazard:	T
Gas:	T
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20094Z3ZNB01RLYL
Chemical Inventory Record Id:	CVTR20094Z3ZM301QJJ2
Amt Of Sub Stored Or Transported:	6000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Rear of main building, west of courtyard.
Last Modified:	3/3/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported

Validation: This facility passed all validation checks.

AK201 **DPS HEADQUARTERS - DUAL FEED ELECTRICAL SERVICES** **ECHO** **1026133127**
Target **5805 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78752**

Site 11 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ECHO:

Envid:	1026133127
Registry ID:	110070704357
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070704357
Name:	DPS HEADQUARTERS - DUAL FEED ELECTRICAL SERVICES
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752

AK202 Target Property | **DPS HEADQUARTERS - DUAL FEED ELECTRICAL SERVICES** | **FINDS** | **1026398058**
5805 N LAMAR BLVD | **N/A**
AUSTIN, TX 78752

Site 12 of 23 in cluster AK

Actual: 702 ft.
Focus Map: 8

FINDS:
Registry ID: 110070704357

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AK203 Target Property | **TEXAS DEPARTMENT OF PUBLIC SAFETY** | **TX ASBESTOS** | **S103607552**
5805 N LAMAR BLVD | **TX Ind. Haz Waste** | **N/A**
AUSTIN, TX 78752

Site 13 of 23 in cluster AK

Actual: 702 ft.
Focus Map: 8

ASBESTOS:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/24/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/13/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	203
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/26/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/25/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/25/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	195
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/02/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/02/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	195
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/10/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/02/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/09/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	195
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Analytical Method:	PLM
Start Date:	03/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/02/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/17/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Work Type Flag:	A
Certification Statement Date:	03/17/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	203
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/10/2020
Notification Number:	2020001426
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/25/2020
Date Routed by Supervisor:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/25/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	203
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/14/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/26/2020
Notification Number:	2020001426
ASB Priority:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/12/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	195
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/26/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/04/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/14/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020001426

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

File Number:	50299
License Status Description:	Paid
Expiration Date:	04/24/2020
Original Date:	02/12/2020
Rank Effective Date:	02/12/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	21120
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY BUILDING B
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/11/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020008045
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/17/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	12/31/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	70244
Registration Initial Notification Date:	12/16/1986
Registration Last Amendment Date:	01/15/2002
EPA Identification:	TXD981901770
Primary NAICS Code:	Not reported
Status Change Date:	19861216
Land Type:	Not reported
Description of Facility Site Location:	5805 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Contact Name:	D PAT JOHNSON
Contact Telephone Number:	512-4652105
Mailing Address:	PO BOX 4143
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787654143
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25075
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040423
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Operator Address:	PO BOX 4143
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78765
Operator Country:	UNITED STA
Operator Telephone:	1-512-4652105
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Owner Mailing Address:	PO BOX 4143
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78765
Owner Country:	UNITED STA
Owner Telephone:	1-512-4652105
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Contact Role:	OPRCON
Contact Address:	PO BOX 4143
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78765
Contact Phone:	1-512-4652105
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 4143
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78765
Contact Phone:	1-512-4652105
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	D JOHNSON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 4143
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78765
Contact Phone:	1-512-4652105
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	262193
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4PZ004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262194

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	C4Q2004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262195
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4Q30091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	269380
Texas Waste Code:	Not reported
Texas Waste Code 2:	CC6F004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	269381
Texas Waste Code:	Not reported
Texas Waste Code 2:	CC6G004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	269382
Texas Waste Code:	Not reported
Texas Waste Code 2:	CC6H0091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	269383
Texas Waste Code:	Not reported
Texas Waste Code 2:	CC6J701H
Waste Code Status:	Not reported
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	276302
Texas Waste Code:	Not reported
Texas Waste Code 2:	CMFV004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	276303
Texas Waste Code:	Not reported
Texas Waste Code 2:	CMFW0091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	275314
Texas Waste Code:	Not reported
Texas Waste Code 2:	CNKG004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	275315
Texas Waste Code:	Not reported
Texas Waste Code 2:	CNKH0091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289161
Texas Waste Code:	Not reported
Texas Waste Code 2:	D74Z004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289162
Texas Waste Code:	Not reported
Texas Waste Code 2:	D752004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289163
Texas Waste Code:	Not reported
Texas Waste Code 2:	D7530021
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	002
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289164
Texas Waste Code:	Not reported
Texas Waste Code 2:	D754004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	288463
Texas Waste Code:	Not reported
Texas Waste Code 2:	D9WM701H
Waste Code Status:	Not reported
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	288464
Texas Waste Code:	Not reported
Texas Waste Code 2:	D9WN004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290260
Texas Waste Code:	Not reported
Texas Waste Code 2:	DBFG701H
Waste Code Status:	Not reported
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290261

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DBFH801H
Waste Code Status:	Not reported
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289719
Texas Waste Code:	Not reported
Texas Waste Code 2:	DFCY319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289720
Texas Waste Code:	Not reported
Texas Waste Code 2:	DFCZ4091
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289721
Texas Waste Code:	Not reported
Texas Waste Code 2:	DFD2207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289722
Texas Waste Code:	Not reported
Texas Waste Code 2:	DFD3207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	289723
Texas Waste Code:	Not reported
Texas Waste Code 2:	DFD4207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287101
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGC701H
Waste Code Status:	Not reported
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287102
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGD4091
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287103
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGF110H
Waste Code Status:	Not reported
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287104
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGG207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287105
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGH207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287106
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGJ207H
Waste Code Status:	Not reported
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287107
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGK105H
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287108
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGL319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287109
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGM110H
Waste Code Status:	Not reported
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287110
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGN203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287111
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGP219H
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287112

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGQ105H
Waste Code Status:	Not reported
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287113
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGR319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287114
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGS203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287115
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGT0011
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287116
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHGV004H
Waste Code Status:	Not reported
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	292584
Texas Waste Code:	Not reported
Texas Waste Code 2:	DHYV3971
Waste Code Status:	Not reported
Waste Form:	397
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314170
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC8V0091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314171
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC8W001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314172
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC8X001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314173
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC8Y001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314174
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC8Z409H
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314175
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC92001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314176
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC93409H
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314177
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC94319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314178
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC95409H
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314179
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC96001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314180
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC97001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314181

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	FC98319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314182
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC99319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314183
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC9B319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314184
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC9C319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314185
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC9D001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	314186
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC9F203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314187
Texas Waste Code:	Not reported
Texas Waste Code 2:	FC9G203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314531
Texas Waste Code:	Not reported
Texas Waste Code 2:	FCPD319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314532
Texas Waste Code:	Not reported
Texas Waste Code 2:	FCPF319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314533
Texas Waste Code:	Not reported
Texas Waste Code 2:	FCPG105H
Waste Code Status:	Not reported
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314534
Texas Waste Code:	Not reported
Texas Waste Code 2:	FCPH119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314535
Texas Waste Code:	Not reported
Texas Waste Code 2:	FCPJ219H
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314815
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD26105H
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314816
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD27319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314817
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD28319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314818
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD29319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314819
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD2B309H
Waste Code Status:	Not reported
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314820

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	FD2C119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314821
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD2D319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	314822
Texas Waste Code:	Not reported
Texas Waste Code 2:	FD2F319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317430
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF27001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317431
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF28001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	317432
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF29001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317433
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2B001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317434
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2C001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317435
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2D001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317436
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2F001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317437
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2G001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317438
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2H001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317439
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF2J001H
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317458
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF36319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	317459
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF37219H
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	318072
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF79119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	318073
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF7B219H
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	318074

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	FF7C319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	318075
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF7D409H
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	318076
Texas Waste Code:	Not reported
Texas Waste Code 2:	FF7F319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319507
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQR119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319508
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQS319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	319509
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQT319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319510
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQV319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319511
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQW119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319512
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQX319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319513
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQY119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319514
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFQZ119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319644
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFWH319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319645
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFWJ319H
Waste Code Status:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	319646
Texas Waste Code:	Not reported
Texas Waste Code 2:	FFWK119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322478
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWR409H
Waste Code Status:	Not reported
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322479
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWS319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322480
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWT105H
Waste Code Status:	Not reported
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322481

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWV119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322482
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWW319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322483
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWX319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322484
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWY110H
Waste Code Status:	Not reported
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322485
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGWZ319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	322486
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGX2119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322487
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGX3119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322488
Texas Waste Code:	Not reported
Texas Waste Code 2:	FGX4701H
Waste Code Status:	Not reported
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	322654
Texas Waste Code:	Not reported
Texas Waste Code 2:	FKH7319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G25
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	132
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	325174
Texas Waste Code:	Not reported
Texas Waste Code 2:	FQDD3191
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	325175
Texas Waste Code:	Not reported
Texas Waste Code 2:	FQDF801H
Waste Code Status:	Not reported
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	325176
Texas Waste Code:	Not reported
Texas Waste Code 2:	FQDG001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Ind. Haz Waste:

Waste ID:	325177
Texas Waste Code:	Not reported
Texas Waste Code 2:	FQDH0011
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	325178
Texas Waste Code:	Not reported
Texas Waste Code 2:	FQDJ3091
Waste Code Status:	Not reported
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5805 N LAMAR BLVD
Mailing Address 2:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S103607552**

Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000305920
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5805 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000305920
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5805 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000305920
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5805 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000305920
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	HWG

AK204 **DEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S125391015**
Target **5805 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 14 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	01/06/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/19/2019
Notification Number:	2019003153
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S125391015**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/15/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/15/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	34
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S125391015**

Inspection Number Grade:	Not reported
Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	01/06/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/26/2019
Notification Number:	2019003153
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/18/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	34
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S125391015**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK205 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S121064160**
Target **5805 N. LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 15 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/28/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/15/2020
Notification Number:	2020007179
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Certification Statement Date:	12/15/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	42
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/28/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/17/2020
Notification Number:	2020007179
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/02/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	57
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/28/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/17/2020
Notification Number:	2020007179
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/02/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	57
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/28/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/17/2020
Notification Number:	2020007179
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/10/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	02/28/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/17/2020
Notification Number:	2020007179
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/27/2020
Certification Statement Phone:	512-563-4660
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/19/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/20/2020
Notification Number:	2020007282
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/15/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/16/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/19/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/20/2020
Notification Number:	2020007282
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/02/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	46
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/16/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	06/12/2016
Notification Number:	2016004199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	06/03/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/03/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	06/11/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	06/05/2016
Notification Number:	2016004199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	05/20/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	06/04/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2017005016
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/06/2017
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	07/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/21/2020
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	01/25/2020
Notification Number:	2020000339
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Date Report Received:	01/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/10/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	01/25/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/21/2020
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	01/25/2020

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Notification Number:	2020000339
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/24/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/24/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	01/25/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	04/08/2022
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020000495
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	01/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/15/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	02/01/2020
Client Code:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	11/20/2016
Notification Number:	2016009060
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/03/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/03/2016
Certification Statement Phone:	512-424-5277

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	11/19/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	OLIVIA ESPINOZA
Violation:	Not reported
Complaint Date:	09/19/2015
Notification Number:	2015005741
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/09/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/03/2015
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	09/19/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	05/24/2021
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	05/31/2020
Notification Number:	2020003541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/30/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/30/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	33
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	05/29/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	05/24/2021
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	05/30/2020
Notification Number:	2020003541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/15/2020
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	33
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	05/29/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	PHILIP B JOHNSON
Violation:	Not reported
Complaint Date:	12/31/2015
Notification Number:	2016000875
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/02/2015
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	02/14/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	08/14/2016
Notification Number:	2016006362
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/27/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/27/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	08/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	08/21/2016
Notification Number:	2016006771
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	08/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/18/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	08/20/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Violation:	Not reported
Complaint Date:	08/21/2016
Notification Number:	2016006771
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	08/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/05/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	08/19/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	09/22/2016
Notification Number:	2016007266
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/09/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Start Date:	09/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	09/26/2016
Notification Number:	2016007266
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	08/26/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Certification Statement Date:	08/26/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	09/10/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2011/04/09
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/09/2011
Client Code:	1400
Client Name:	Environmental Facilities/Notification
License Number:	2011001662
File Number:	74784
License Status Description:	Paid
Expiration Date:	04/10/2011
Original Date:	03/15/2011
Rank Effective Date:	03/15/2011
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	26805
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	A
Inspection Secondary Class Code Description:	Asbestos
Results:	Pass
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	07/24/2016
Notification Number:	2016005699
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/08/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/08/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	07/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S121064160**

Results:	Not reported
Inspection Number Grade:	Not reported

AK206 Target Property **DPS HEADQUARTERS**
5805 N LAMAR BLDG R
AUSTIN, TX 78752

TX ASBESTOS **S128133620**
N/A

Site 16 of 23 in cluster AK

Actual: 702 ft.

Focus Map: 8

ASBESTOS:

Name:	DPS HEADQUARTERS
Address:	5805 N LAMAR BLDG R
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	08/15/2022
Reason for Inspection:	Brenda J Troth
Violation:	Not reported
Complaint Date:	06/11/2021
Notification Number:	2021003572
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/09/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/09/2021
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment

DPS HEADQUARTERS (Continued) **S128133620**

Analytical Method:	PLM
Start Date:	06/11/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DPS HEADQUARTERS
Address:	5805 N LAMAR BLDG R
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	08/15/2022
Reason for Inspection:	Brenda J Troth
Violation:	Not reported
Complaint Date:	06/11/2021
Notification Number:	2021003572
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/27/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original

DPS HEADQUARTERS (Continued) **S128133620**

Work Type Flag:	A
Certification Statement Date:	05/27/2021
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/11/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK207 **TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS** **TX AIRS** **S121950950**
Target **5805 N LAMAR BLVD** **TX ASBESTOS** **N/A**
Property **AUSTIN, TX 78752** **TX IHW CORR ACTION**
TX COMP HIST
Site 17 of 23 in cluster AK **TX CENTRAL REGISTRY**

Actual:
702 ft.

Focus Map:
8

AIRS:

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Permit Num:	3141
Regulated Id:	RN101721728
Permit Type:	CONSTRUCT
Permit Status:	CANCELLED
Permit Issued Date:	03/12/1991
Expiration Date:	11/10/1990
Customer Id:	CN600610976
Company Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Physical Location Desc:	5805 N Lamar, Austin, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.326500
Long Dec Coord Num:	-97.725993

ASBESTOS:

Name:	TDPS HEADQUARTERS - SMALL ARMS FIRING RANGE
Address:	5805 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	08/27/2021
Notification Number:	2021003369
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/15/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2021

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDPS HEADQUARTERS - SMALL ARMS FIRING RANGE
Address:	5805 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	08/27/2021
Notification Number:	2021003369
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/02/2021

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/15/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDPS HEADQUARTERS - SMALL ARMS FIRING RANGE
Address:	5805 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	08/27/2021
Notification Number:	2021003369
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/14/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/14/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDPS HEADQUARTERS - SMALL ARMS FIRING RANGE
Address:	5805 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	08/27/2021
Notification Number:	2021003369
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	05/20/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/07/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Inspection Number Grade: Not reported

IHW CORR ACTION:

Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Program Id:	70244
Location Desc:	5805 N LAMAR AUSTIN TX
RN NUM:	RN101721728
Status:	INACTIVE
Status Date:	06/17/2022
EDR Link ID:	70244
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	06/17/2022
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

COMP HIST:

RN Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603796467
CN Name:	JT VAUGHN CONSTRUCTION LLC
CN Rating:	.53
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	922190
SIC Code:	1542
Related Number:	47223,TH0086V,TXR1534BR,2751,2751

RN Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600610976
CN Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	922190
SIC Code:	1542

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Related Number: 47223,TH0086V,TXR1534BR,2751,2751

CENTRAL REGISTRY:

Regulated Entity Number: RN101721728
Name: TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address: 5805 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4431
Status: ACTIVE
Status Date: 2002-03-26
Customer Number: CN600610976
Customer Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name: Texas Department of Public Safety
Customer Ownership Type: STATE GOVERNMENT
Affiliation Begin Date: 1986-05-08
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 922190
Primary NAICS Industry Type Description: Other Justice, Public Order, and Safety Activities
Physical Location Description: 5805 N Lamar, Austin, TX

Regulated Entity Number: RN101721728
Name: TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address: 5805 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4431
Status: ACTIVE
Status Date: 2002-03-26
Customer Number: CN603796467
Customer Name: JT VAUGHN CONSTRUCTION LLC
Customer Legal Name: J.T. Vaughn Construction, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2020-03-11
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 922190
Primary NAICS Industry Type Description: Other Justice, Public Order, and Safety Activities
Physical Location Description: 5805 N Lamar, Austin, TX

Regulated Entity Number: RN101721728
Name: TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address: 5805 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-4431
Status: ACTIVE
Status Date: 3/26/2002
Customer Number: CN600610976
Customer Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name: Texas Department of Public Safety
Customer Ownership Type: STATE GOVERNMENT
Affiliation Begin Date: 5/8/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 922190
Primary NAICS Industry Type Description: Other Justice, Public Order, and Safety Activities
Physical Location Description: 5805 N Lamar, Austin, TX

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/11/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN600610976
Customer Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name:	Texas Department of Public Safety
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN600610976
Customer Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name:	Texas Department of Public Safety
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/11/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/11/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN600610976
Customer Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name:	Texas Department of Public Safety
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE

TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS (Continued) **S121950950**

Status Date:	3/26/2002
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/11/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Regulated Entity Number:	RN101721728
Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Address:	5805 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4431
Status:	ACTIVE
Status Date:	3/26/2002
Customer Number:	CN600610976
Customer Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Customer Legal Name:	Texas Department of Public Safety
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	922190
Primary NAICS Industry Type Description:	Other Justice, Public Order, and Safety Activities
Physical Location Description:	5805 N Lamar, Austin, TX

Click this hyperlink while viewing on your computer to access
6 additional TX CENTRAL REG: record(s) in the EDR Site Report.

AK208 **TX. DEPT. OF PUBLIC SAFETY** **TX LPST** **S116702628**
Target **5805 N. LAMAR BLVD.** **TX ASBESTOS** **N/A**
Property **AUSTIN, TX 78752**

Site 18 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

LPST:

Name:	TEXAS DEPT OF PUBLIC SAFETY
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78773
Facility ID:	0002751
LPST Id:	094079
Facility Location:	5710 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/07/1989
Entered Date:	12/11/1989
Reported Date:	11/07/1989
Closure Date:	01/03/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	HERMAN WOLF
Responsible Party Address:	5710 GUADALUPE
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/465-2043
Reported Date:	11/07/1989
Case Start Date:	01/03/1990
Reference Number:	RN101721728
Project Manager:	HWELCH

ASBESTOS:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	07/24/2017
Notification Number:	2017005018
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/06/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005186
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/17/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/17/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005186
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Inspector Name:	Not reported
Date Report Received:	08/04/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/04/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug.Grieco
Violation:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Complaint Date:	08/21/2017
Notification Number:	2017005186
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/08/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/08/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005186
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/15/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/15/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005186
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/12/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/12/2017

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/15/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/15/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/14/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/21/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/21/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/11/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/25/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/25/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/04/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/04/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/07/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/07/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/19/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017005188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/12/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/12/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78773

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	04/02/2018
Notification Number:	2017008882
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/01/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/01/2017
Certification Statement Phone:	512-527-4178
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	19
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	03/30/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPT. OF PUBLIC SAFETY
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	07/13/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013004879
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	07/25/2013
Date Routed by Supervisor:	07/31/2013
Date Routed to PSQA:	08/06/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TX. DEPT. OF PUBLIC SAFETY
Address:	5805 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	08/10/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013005801
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	08/30/2013
Date Routed by Supervisor:	09/05/2013
Date Routed to PSQA:	09/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002537
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	05/20/2016

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/20/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002537

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/28/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/28/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002537
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/18/2016
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/02/2016
Client Code:	Not reported
Client Name:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	01/15/2018
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/01/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/01/2017
Certification Statement Phone:	512-527-4178
Is The Facility a School or K-12?:	N

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Region:	07
Priority:	HIGH
ARU:	19
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	01/12/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	12/25/2017
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/13/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/13/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	58
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	11/10/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	01/08/2018
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/23/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/23/2017
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	58
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	11/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	01/15/2018
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/09/2017
Certification Statement Phone:	512-527-4178
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	58
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	12/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	04/02/2018
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/17/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/17/2017
Certification Statement Phone:	512-527-4178
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	58
Is this a phased abatement project?:	Y
Ordered:	N

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	01/12/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	12/11/2017
Notification Number:	2017007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TX. DEPT. OF PUBLIC SAFETY (Continued) **S116702628**

Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/29/2017
Certification Statement Phone:	512-527-4178
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	58
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	10/27/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK209 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S122367290**
Target **5805 LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78773**

Site 19 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5805 LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78773
Date of inspection:	Not reported
Reason for Inspection:	Doug Grieco
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018001056
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S122367290**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	02/09/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/09/2018
Certification Statement Phone:	512-424-2507
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	03/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK210 **TEXASDEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S125923136**
Target **5805 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 20 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	TEXASDEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/08/2020
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/21/2019
Notification Number:	2019008748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/21/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/21/2019
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/14/2019
Client Code:	Not reported
Client Name:	Not reported

TEXASDEPARTMENT OF PUBLIC SAFETY (Continued) **S125923136**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXASDEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/08/2020
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/22/2019
Notification Number:	2019008748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/12/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/12/2019
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N

TEXASDEPARTMENT OF PUBLIC SAFETY (Continued) **S125923136**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/14/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXASDEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/08/2020
Reason for Inspection:	Philip Johnson
Violation:	Not reported
Complaint Date:	12/15/2019
Notification Number:	2019008748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

TEXASDEPARTMENT OF PUBLIC SAFETY (Continued) **S125923136**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/27/2019
Certification Statement Phone:	512-424-5277
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	12/14/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXASDEPARTMENT OF PUBLIC SAFETY
Address:	5805 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/12/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

TEXASDEPARTMENT OF PUBLIC SAFETY (Continued) **S125923136**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	12/14/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019008748
File Number:	47313
License Status Description:	Current
Expiration Date:	12/21/2019
Original Date:	11/27/2019
Rank Effective Date:	11/27/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20047
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

AK211 Target Property | **TEXAS DEPT OF PUBLIC SAFETY**
5805 N LAMAR BLVD
AUSTIN, TX 78752 | **TX UST** | **U001239709**
N/A

Site 21 of 23 in cluster AK

Actual: 702 ft.

Focus Map: 8

UST:

Name:	TEXAS DEPT OF PUBLIC SAFETY
Address:	5805 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524431
AI Number:	2751
Facility Type:	FLEET REFUELING
Facility Begin Date:	06/11/1986
Facility Status:	ACTIVE
Additional ID:	696782462002205
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	MARK BLOMQUIST,
Contact Organization Name:	TEXAS DEPT OF PUBLIC SAFETY HEADQUARTERS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124245253
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/21/2021
Signature Name/Title On Earliest Reg Form:	MARK BLOMQUIST,ENV. MANAGER
Application Received Date On Earliest Reg Form:	08/03/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	189570062001351
Additional ID:	696782462002205
Ai Number:	2751
Operator CN:	CN600610976
Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Operator Effective Begin Date:	04/27/2001
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	JERSEY VILLAGE TX 77065-4523
Contact Phone Country Code:	1
Contact Phone Area Code:	281
Contact Phone Number:	5171509
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600610976
Owner Last Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	JERSEY VILLAGE
Contact Mailing State:	TX
Contact Mailing Zip:	77065
Contact Mailing Zip5:	4523
Contact Phone Number/Ext:	1 281 5171509/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	189570062001351
Additional ID:	696782462002205
AI Number:	2751
Owner Effective Begin Date:	04/27/2001
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY

Self Certification:

Self Cert ID:	41292
Cert ID:	374739
AI Number:	2751
Self Certification Date:	07/21/2022
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	358139
AI Number:	2751
Self Certification Date:	07/21/2021

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	MARK BLOMQUIST ENV. MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	41292
Cert ID:	341493
AI Number:	2751
Self Certification Date:	07/31/2020
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	41292
Cert ID:	324514
AI Number:	2751
Self Certification Date:	07/19/2019
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	41292
Cert ID:	301378
AI Number:	2751
Self Certification Date:	02/28/2018

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	MARK BLOMQUIST ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	284418
AI Number:	2751
Self Certification Date:	02/28/2017
Signature Name/Title:	MARK BLOMQUIST ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	268155
AI Number:	2751
Self Certification Date:	04/12/2016
Signature Name/Title:	PHILIP JOHNSON ASST MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	251113
AI Number:	2751
Self Certification Date:	03/24/2015

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	PHILIP JOHNSON ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	234755
AI Number:	2751
Self Certification Date:	04/01/2014
Signature Name/Title:	PHILIP JOHNSON ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	41292
Cert ID:	218948
AI Number:	2751
Self Certification Date:	04/29/2013
Signature Name/Title:	PHILIP JOHNSON ENV COORD
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	41292
Cert ID:	13449
AI Number:	2751
Self Certification Date:	03/12/2012

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	PHILIP JOHNSON ENV COORD
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13448
AI Number:	2751
Self Certification Date:	04/04/2011
Signature Name/Title:	PHILIP JOHNSON ENV COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13447
AI Number:	2751
Self Certification Date:	04/05/2010
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13446
AI Number:	2751
Self Certification Date:	06/25/2009

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13445
AI Number:	2751
Self Certification Date:	04/14/2008
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13444
AI Number:	2751
Self Certification Date:	04/12/2007
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13443
AI Number:	2751
Self Certification Date:	04/19/2006

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	CYNTHIA R LEFTWICH PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	41292
Cert ID:	13442
AI Number:	2751
Self Certification Date:	06/01/2005
Signature Name/Title:	GERARDO R DE LA PENA ENV GROUP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	41292
Cert ID:	13441
AI Number:	2751
Self Certification Date:	04/16/2004
Signature Name/Title:	CYNTHIA LEFTWICH PRES LIBERTY EQUIP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	41292
Cert ID:	13440
AI Number:	2751
Self Certification Date:	04/01/2003

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Signature Name/Title:	TERRY SAULS VP OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13439
AI Number:	2751
Self Certification Date:	04/16/2002
Signature Name/Title:	H D LARK PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	41292
Cert ID:	13438
AI Number:	2751
Self Certification Date:	04/20/2001
Signature Name/Title:	WILLIAM SCHRAMM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6844
Facility ID:	41292
Ai Number:	2751
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	6000
UST Comprt ID:	9791
UST ID:	6844
AI Number:	2751
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6845
Facility ID:	41292
Ai Number:	2751
Tank Id:	5

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	9792
UST ID:	6845
AI Number:	2751

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6846
Facility ID:	41292
Ai Number:	2751
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	9793
UST ID:	6846
AI Number:	2751
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1955
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6847
Facility ID:	41292
Ai Number:	2751
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	9794
UST ID:	6847
AI Number:	2751
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6848
Facility ID:	41292
Ai Number:	2751
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/22/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	6500
UST Comprt ID:	9795
UST ID:	6848
AI Number:	2751
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1992
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	6849
Facility ID:	41292
Ai Number:	2751
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/12/1990

Compartment Records:

Tank ID:	6
Tank Capacity:	6000
UST Comprt ID:	9796
UST ID:	6849
AI Number:	2751
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1994
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	174394
Facility ID:	41292
Ai Number:	2751
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1994
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	9797
UST ID:	174394
AI Number:	2751
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/01/1992

Facility Billing Contacts:

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U001239709**

Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	PO BOX 4087 MSC0225
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78773 0001
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	41292
Additional ID:	696782462002205
Princ ID:	189570062001351
AI Number:	2751
Facility Name:	TEXAS DEPT OF PUBLIC SAFETY
AR Number:	79599
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	MARK BLOMQUIST/

AK212 **DEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S128133598**
Target **5801 NORTH LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 22 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	09/15/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	06/28/2021
Notification Number:	2021003926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/22/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/26/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	09/15/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	06/28/2021
Notification Number:	2021003926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Inspector Name:	Not reported
Date Report Received:	06/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/22/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/25/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	09/15/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Complaint Date:	06/25/2021
Notification Number:	2021003926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/09/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/09/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/23/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	07/01/2022
Notification Number:	2022003960
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/23/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/23/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/30/2022

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 NORTH LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022003960
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/13/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/13/2022

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133598**

Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/27/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AK213 **DEPARTMENT OF PUBLIC SAFETY** **TX ASBESTOS** **S128133597**
Target **5801 N. LAMAR** **N/A**
Property **AUSTIN, TX 78752**

Site 23 of 23 in cluster AK

Actual:
702 ft.

Focus Map:
8

ASBESTOS:

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	09/09/2021
Notification Number:	2021005158
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/24/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/24/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/23/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Franklin W Wiget

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Violation:	Not reported
Complaint Date:	09/03/2021
Notification Number:	2021005158
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/06/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/06/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	09/03/2021
Notification Number:	2021005158
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/13/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/13/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Start Date:	08/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	09/09/2021
Notification Number:	2021005158
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/17/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Certification Statement Date:	08/17/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/23/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DEPARTMENT OF PUBLIC SAFETY
Address:	5801 N. LAMAR
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	11/18/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	08/31/2021
Notification Number:	2021005158
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/26/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

DEPARTMENT OF PUBLIC SAFETY (Continued) **S128133597**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/26/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	26
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/09/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AL214 **CITY OF AUSTIN EMS STATION # 5** **TX ASBESTOS** **S128929070**
Target **5710 NORTH LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78752**

Site 1 of 13 in cluster AL

Actual:
697 ft.

Focus Map:
8

ASBESTOS:

Name:	CITY OF AUSTIN EMS STATION # 5
Address:	5710 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported

CITY OF AUSTIN EMS STATION # 5 (Continued) **S128929070**

Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/31/2022
Notification Number:	2022005143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/25/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/25/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/25/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

CITY OF AUSTIN EMS STATION # 5 (Continued) **S128929070**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN EMS STATION # 5
Address:	5710 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/26/2022
Notification Number:	2022005143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/16/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/16/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported

CITY OF AUSTIN EMS STATION # 5 (Continued) **S128929070**

Analytical Method:	PLM
Start Date:	08/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN EMS STATION # 5
Address:	5710 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/26/2022
Notification Number:	2022005143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment

CITY OF AUSTIN EMS STATION # 5 (Continued) **S128929070**

Work Type Flag:	A
Certification Statement Date:	08/18/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/25/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN EMS STATION # 5
Address:	5710 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2022005143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/02/2022
Date Routed by Supervisor:	Not reported

CITY OF AUSTIN EMS STATION # 5 (Continued) **S128929070**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/02/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/16/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AL215 Target Property | **NORTH SERVICE CENTER ANNEX**
5708 NORTH LAMAR BLVD
AUSTIN, TX 78752 | **TX ASBESTOS** | **S121361782**
N/A

Site 2 of 13 in cluster AL

Actual: 697 ft.

Focus Map: 8

ASBESTOS:

Name:	NORTH SERVICE CENTER ANNEX
Address:	5708 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/26/2017
Notification Number:	2017006535
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/05/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/23/2017
Client Code:	Not reported
Client Name:	Not reported

NORTH SERVICE CENTER ANNEX (Continued) **S121361782**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	NORTH SERVICE CENTER ANNEX
Address:	5708 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/06/2017
Notification Number:	2017006535
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/19/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/19/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N

NORTH SERVICE CENTER ANNEX (Continued) **S121361782**

Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NORTH SERVICE CENTER ANNEX
Address:	5708 NORTH LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/19/2017
Notification Number:	2017006535
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

NORTH SERVICE CENTER ANNEX (Continued) **S121361782**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/27/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/16/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AM216 **TORN MACHINERY COMP.** **TX HIST UST** **S111678838**
Target **5545 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 1 of 4 in cluster AM

Actual:
683 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	TORN MACHINERY COMP.
Address:	5545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0548
HID UST:	548
Inspection:	Not reported
Due:	06/01/2012

AN217 Target Property | **ATLAS AUTO AIR**
5408 N LAMAR BLVD
AUSTIN, TX 78751 | **TX Ind. Haz Waste**
TX CENTRAL REGISTRY | **S102754065**
N/A

Site 1 of 6 in cluster AN

Actual: 681 ft.

Focus Map: 8

Ind. Haz Waste:

Name:	ATLAS AUTO AIR
Address:	5408 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	72268
Registration Initial Notification Date:	11/14/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19861114
Land Type:	Not reported
Description of Facility Site Location:	5408 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	ATLAS AUTO AIR
Contact Name:	JOSEPH MEYERS
Contact Telephone Number:	512-4536684
Mailing Address:	5408 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787511825
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26710
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031031
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

ATLAS AUTO AIR (Continued) **S102754065**

Ind. Haz Waste:

Operator Name:	ATLAS AUTO AIR
Operator Address:	5408 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78751
Operator Country:	UNITED STA
Operator Telephone:	1-512-4536684
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17424137168
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ATLAS AUTO AIR
Owner Mailing Address:	5408 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Country:	UNITED STA
Owner Telephone:	1-512-4536684
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17424137168
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	5408 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4536684
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	5408 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4536684
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JOSEPH MEYERS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	5408 N LAMAR BLVD
Contact Address 2:	Not reported

ATLAS AUTO AIR (Continued) **S102754065**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4536684
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100557917
Name:	ATLAS AUTO AIR
Address:	5408 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1825
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600268742
Customer Name:	ATLAS AUTO AIR
Customer Legal Name:	Atlas Auto Air Conditioning, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5408 N Lamar, Austin, TX

AN218 **CAMDEN LAMAR HEIGHTS** **TX ASBESTOS** **S119140535**
Target **5400 N. LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78756**

Site 2 of 6 in cluster AN

Actual: 679 ft.

Focus Map: 8

ASBESTOS:

Name:	CAMDEN LAMAR HEIGHTS
Address:	5400 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	01/29/2014
Reason for Inspection:	Discretionary
Violation:	No
Complaint Date:	Not reported
Notification Number:	N/A
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	05
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	02/28/2014
Date Routed by Supervisor:	04/17/2014
Date Routed to PSQA:	04/23/2014
Date Reviewed by PSQA:	Not reported

CAMDEN LAMAR HEIGHTS (Continued) **S119140535**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AN219 **CENTRAL TEXAS REGIONAL BLOOD CENTER** **TX UST** **U001273459**
Target **5400 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78751**

Site 3 of 6 in cluster AN

Actual:
679 ft.

Focus Map:
8

UST:

Name:	CENTRAL TEXAS REGIONAL BLOOD CENTER
Address:	5400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787515400
AI Number:	41027
Facility Type:	UNKNOWN

CENTRAL TEXAS REGIONAL BLOOD CENTER (Continued) **U001273459**

Facility Begin Date:	01/21/1987
Facility Status:	INACTIVE
Additional ID:	461370672002069
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	E JACKSON,INVENTORY SECTION
Contact Organization Name:	CENTRAL TEXAS REGIONAL BLOOD CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124581121
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/18/1986
Signature Name/Title On Earliest Reg Form:	TRUDELL S GREEN,ADMIN.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600889000
Owner Last Name:	WE ARE BLOOD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	451370662002069
Additional ID:	461370672002069
AI Number:	41027
Owner Effective Begin Date:	01/21/1987
State Tax ID:	17413662929
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976

CENTRAL TEXAS REGIONAL BLOOD CENTER (Continued) **U001273459**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108718
Facility ID:	70653
Ai Number:	41027
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/18/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

CENTRAL TEXAS REGIONAL BLOOD CENTER (Continued) **U001273459**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	83443
UST ID:	108718
AI Number:	41027
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CENTRAL TEXAS REGIONAL BLOOD CENTER
Contact Mailing Address (Delivery):	4300 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78756 3421
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

CENTRAL TEXAS REGIONAL BLOOD CENTER (Continued) **U001273459**

Contact Address Deliverable:	Y
Facility ID:	70653
Additional ID:	461370672002069
Princ ID:	451370662002069
AI Number:	41027
Facility Name:	CENTRAL TEXAS REGIONAL BLOOD CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

AN220 **CENTRAL TEXAS REGIONAL BLOOD CNT** **TX CENTRAL REGISTRY** **S126533769**
Target **5400 N LAMAR BLVD** **N/A**
Property **AUSTIN, TX 78751**

Site 4 of 6 in cluster AN

Actual:
679 ft.

Focus Map:
8

CENTRAL REGISTRY:

Regulated Entity Number:	RN101650877
Name:	CENTRAL TEXAS REGIONAL BLOOD CNT
Address:	5400 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-5400
Status:	ACTIVE
Status Date:	3/10/2002
Customer Number:	CN600889000
Customer Name:	WE ARE BLOOD
Customer Legal Name:	We Are Blood
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/21/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AO221 **FORMER BUCKS FEED STORE** **TX ASBESTOS** **S122366205**
Target **5327 N. LAMAR** **N/A**
Property **AUSTIN, TX 78703**

Site 1 of 14 in cluster AO

Actual:
677 ft.

Focus Map:
8

ASBESTOS:

Name:	FORMER BUCKS FEED STORE
Address:	5327 N. LAMAR
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/05/01
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

FORMER BUCKS FEED STORE (Continued) **S122366205**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/01/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018003162
File Number:	30215
License Status Description:	Paid
Expiration Date:	05/03/2018
Original Date:	04/17/2018
Rank Effective Date:	04/17/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	10265
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

FORMER BUCKS FEED STORE (Continued) **S122366205**

Name:	FORMER BUCKS FEED STORE
Address:	5327 N. LAMAR
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	05/01/2018
Reason for Inspection:	Brent Plant
Violation:	Not reported
Complaint Date:	05/03/2018
Notification Number:	2018003162
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/17/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/17/2018
Certification Statement Phone:	979-492-5104
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	18
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

FORMER BUCKS FEED STORE (Continued) **S122366205**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AO222 **J&J GARAGE** **EDR Hist Auto** **1013763380**
Target **5312 LAMAR BLVD** **N/A**
Property **AUSTIN, TX**

Site 2 of 14 in cluster AO

Actual:
678 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	J & J GARAGE	AUTOMOBILE REPAIRING
1958	J&J GARAGE	AUTOMOBILE REPAIRING
1962	J&J GARAGE AUTO	AUTOMOBILE REPAIRING
1965	REAR A ONE AUTO CLINIC	AUTOMOBILE REPAIRING

AO223 **FASHION FLOOR INC** **EDR Hist Cleaner** **1013781609**
Target **5304 LAMAR BLVD N** **N/A**
Property **AUSTIN, TX 78751**

Site 3 of 14 in cluster AO

Actual:
678 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1980	FASHION FLOORS INC CARPET RUG D	CARPET AND RUG CLEANERS
1984	FASHION FLOOR INC	ORIENTAL RUG CLEANING
1984	FASHION FLOOR INC	RUG CLEANING AND RENOVATING
1990	FASHION FLOORS INC	RUG CLEANING AND RENOVATING
1990	FASHION FLOORS INC	ORIENTAL RUG CLEANING

AP224 **VACANT BLDG. (FORMER AUSTIN VACUUM)** **TX ASBESTOS** **S119159884**
Target **5242 NORTH LAMAR BLVD.** **N/A**
Property **AUSTIN, TX 78751**

Site 1 of 2 in cluster AP

Actual:
674 ft.

ASBESTOS:

Focus Map:
8

Name:	VACANT BLDG. (FORMER AUSTIN VACUUM)
Address:	5242 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	07/09/2013
Reason for Inspection:	Notified
Violation:	No

VACANT BLDG. (FORMER AUSTIN VACUUM) (Continued) **S119159884**

Complaint Date:	Not reported
Notification Number:	2013004977
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	07/25/2013
Date Routed by Supervisor:	07/31/2013
Date Routed to PSQA:	08/06/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

VACANT BLDG. (FORMER AUSTIN VACUUM) (Continued) **S119159884**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

225
Target Property
ROY R. WARNER
5201 N LAMAR BLVD
AUSTIN, TX

TX HIST UST **S111678797**
N/A

Actual: 670 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	ROY R. WARNER
Address:	5201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0942
HID UST:	942
Inspection:	06/15/2011
Due:	06/15/2014

AQ226
Target Property
CECILS (SINCLAIR)
5100 N LAMAR BLVD
AUSTIN, TX

TX HIST UST **S128729551**
N/A

Site 1 of 9 in cluster AQ

Actual: 667 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	CECILS (SINCLAIR)
Address:	5100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0150
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AQ227
Target Property
MAXIM ENGINEERS INC
106011 N LAMAR BLVD
AUSTIN, TX 78753

FINDS **1004604504**
ECHO **N/A**

Site 2 of 9 in cluster AQ

Actual: 665 ft.
Focus Map: 8

FINDS:
Registry ID: 110010774288

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
ICIS (Integrated Compliance Information System) is the Integrated

MAXIM ENGINEERS INC (Continued) **1004604504**

Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004604504
Registry ID:	110010774288
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110010774288
Name:	MAXIM ENGINEERS INC
Address:	106011 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

AR228 **STATE BUILDING** **TX ASBESTOS** **S128134975**
Target **4900 NORTH LAMAR STREET** **N/A**
Property **AUSTIN, TX 78751**

Site 1 of 5 in cluster AR

Actual:
663 ft.

Focus Map:
8

ASBESTOS:

Name:	STATE BUILDING
Address:	4900 NORTH LAMAR STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	07/23/2021
Notification Number:	2021003711
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

STATE BUILDING (Continued) **S128134975**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/16/2021
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	STATE BUILDING
Address:	4900 NORTH LAMAR STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	07/02/2021
Notification Number:	2021003711
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

STATE BUILDING (Continued) **S128134975**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/25/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/25/2021
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

STATE BUILDING (Continued) **S128134975**

Name:	STATE BUILDING
Address:	4900 NORTH LAMAR STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	07/09/2021
Notification Number:	2021003711
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/02/2021
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

STATE BUILDING (Continued) **S128134975**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	STATE BUILDING
Address:	4900 NORTH LAMAR STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	07/16/2021
Notification Number:	2021003711
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/08/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/08/2021
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

STATE BUILDING (Continued) **S128134975**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	STATE BUILDING
Address:	4900 NORTH LAMAR STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	06/25/2021
Notification Number:	2021003711
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

STATE BUILDING (Continued) **S128134975**

Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/02/2021
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AS229 **MESA CLEANERS** **FINDS** **1011354047**
Target **4700 W GUADALUPE ST STE 2** **N/A**
Property **AUSTIN, TX 78751**

Site 1 of 3 in cluster AS

Actual:
651 ft.

Focus Map:
8

FINDS:
Registry ID: 110034710481

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

MESA CLEANERS (Continued) **1011354047**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AS230 Target Property **MESA CLEANERS**
4700 W GUADALUPE ST STE 2
AUSTIN, TX 78751

TX DRYCLEANERS **S108419485**
N/A

Site 2 of 3 in cluster AS

Actual: 651 ft.

Focus Map: 8

DRYCLEANERS:

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	REGION 11 - AUSTIN
CN Number:	CN604490060
DCR Number:	DCR14661
AR Number:	24006970
Principal Name:	IMAM786 INC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@GMAIL.COM
Phone Number:	512 3427111
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	REGION 11 - AUSTIN
CN Number:	CN604490060
DCR Number:	DCR14661
AR Number:	24006970
Principal Name:	IMAM786 INC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@GMAIL.COM
Phone Number:	512 3427111
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2

MESA CLEANERS (Continued) **S108419485**

City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	REGION 11 - AUSTIN
CN Number:	CN604490060
DCR Number:	DCR14661
AR Number:	24006970
Principal Name:	IMAM786 INC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	AKBARALI_MOMIN@SBCGLOBAL.NET
Phone Number:	512 3427111
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN602459521
DCR Number:	Not reported
AR Number:	24000146
Principal Name:	MESA CLEANERS INC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN602459521
DCR Number:	Not reported
AR Number:	24000146
Principal Name:	MESA CLEANERS INC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM

MESA CLEANERS (Continued) **S108419485**

Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS

MESA CLEANERS (Continued) **S108419485**

Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700

MESA CLEANERS (Continued) **S108419485**

EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
City,State,Zip:	AUSTIN, TX 78751
RN Number:	RN104994827
Region:	11
CN Number:	CN603277187
DCR Number:	Not reported
AR Number:	24005314
Principal Name:	SKN INVESTMENTS LLC
Bill Addr1:	8127 MESA DR STE C299
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78759 8700
EMail:	MESACLEANERS@AUSTIN.RR.COM
Phone Number:	512 3427111
Site Name:	MESA CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	IN PROGRESS
Fiscal Year:	FY2014
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

AS231 Target Property | **MESA CLEANERS**
4700 W GUADALUPE ST STE 2
AUSTIN, TX 78751 | **TX CENTRAL REGISTRY** | **S126747737**
N/A

Site 3 of 3 in cluster AS

Actual: 651 ft.

Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602459521
Customer Name:	MESA CLEANERS INC
Customer Legal Name:	Mesa Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/17/2007
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602459521
Customer Name:	MESA CLEANERS INC
Customer Legal Name:	Mesa Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/17/2007
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602459521
Customer Name:	MESA CLEANERS INC
Customer Legal Name:	Mesa Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/17/2007
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)

MESA CLEANERS (Continued) **S126747737**

Physical Location Description: Not reported

Regulated Entity Number: RN104994827
Name: MESA CLEANERS
Address: 4700 W GUADALUPE ST STE 2
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-3778
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN602459521
Customer Name: MESA CLEANERS INC
Customer Legal Name: Mesa Cleaners, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/17/2007
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: Not reported

Regulated Entity Number: RN104994827
Name: MESA CLEANERS
Address: 4700 W GUADALUPE ST STE 2
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-3778
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN602459521
Customer Name: MESA CLEANERS INC
Customer Legal Name: Mesa Cleaners, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/17/2007
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: Not reported

Regulated Entity Number: RN104994827
Name: MESA CLEANERS
Address: 4700 W GUADALUPE ST STE 2
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-3778
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN603277187
Customer Name: SKN INVESTMENTS LLC
Customer Legal Name: SKN INVESTMENTS LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/2007
Affiliation End Date: 11/26/2013
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: Not reported

Regulated Entity Number: RN104994827

MESA CLEANERS (Continued) **S126747737**

Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603277187
Customer Name:	SKN INVESTMENTS LLC
Customer Legal Name:	SKN INVESTMENTS LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2007
Affiliation End Date:	11/26/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603277187
Customer Name:	SKN INVESTMENTS LLC
Customer Legal Name:	SKN INVESTMENTS LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2007
Affiliation End Date:	11/26/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603277187
Customer Name:	SKN INVESTMENTS LLC
Customer Legal Name:	SKN INVESTMENTS LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2007
Affiliation End Date:	11/26/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported

MESA CLEANERS (Continued) **S126747737**

City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603277187
Customer Name:	SKN INVESTMENTS LLC
Customer Legal Name:	SKN INVESTMENTS LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2007
Affiliation End Date:	11/26/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104994827
Name:	MESA CLEANERS
Address:	4700 W GUADALUPE ST STE 2
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-3778
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604490060
Customer Name:	IMAM786 INC
Customer Legal Name:	IMAM786 INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/27/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

---

232 **PROVISION DINING HOUSE** **TX ASBESTOS** **S128931012**
Target **4600 W GUADALUPE STREET STE B-5** **N/A**
Property **AUSTIN, TX 78751**

Actual:
642 ft.

Focus Map:
8

ASBESTOS:

Name:	PROVISION DINING HOUSE
Address:	4600 W GUADALUPE STREET STE B-5
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/03/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

PROVISION DINING HOUSE (Continued) **S128931012**

Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/28/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	70445
License Status Description:	Current
Expiration Date:	03/31/2027
Original Date:	04/01/2022
Rank Effective Date:	04/01/2022
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	31969
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Fail
Inspection Number Grade:	Not reported

233 Target Property | **RAMPART CONSTRUCTION THE TRIANGLE BUILDING C** | **TX CENTRAL REGISTRY** | **S126739500**
4510 W GUADALUPE ST | **N/A**
AUSTIN, TX 78751

Actual: 637 ft.
Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN104881735
Name:	RAMPART CONSTRUCTION THE TRIANGLE BUILDING C
Address:	4510 W GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2973
Status:	ACTIVE
Status Date:	2006-02-10
Customer Number:	CN602981623
Customer Name:	RAMPART CONSTRUCTION COMPANY LP
Customer Legal Name:	Rampart Construction Company, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236115
Primary NAICS Industry Type Description:	New Single-Family Housing Construction (except Operative Builders)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104881735
Name:	RAMPART CONSTRUCTION THE TRIANGLE BUILDING C
Address:	4510 W GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2973
Status:	ACTIVE
Status Date:	2006-02-10
Customer Number:	CN602981623
Customer Name:	RAMPART CONSTRUCTION COMPANY LP
Customer Legal Name:	Rampart Construction Company, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236115
Primary NAICS Industry Type Description:	New Single-Family Housing Construction (except Operative Builders)
Physical Location Description:	Not reported

AT234 Target Property | **DODD-HURT TEXACO** | **EDR Hist Auto** | **1020280624**
4300 GUADALUPE | **N/A**
AUSTIN, TX 78751

Site 1 of 8 in cluster AT

Actual: 627 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1972	DODD-HURT TEXACO	Gasoline Service Stations
1973	DODD-HURT TEXACO	Gasoline Service Stations
1974	DODD-HURT TEXACO	Gasoline Service Stations
1975	DODD-HURT TEXACO	Gasoline Service Stations
1976	DODD-HURT TEXACO	Gasoline Service Stations
1977	DODD-HURT TEXACO	Gasoline Service Stations

235 Target Property | **AUSTIN STATE HOSPITAL**
4101GUADALUPE STREET
AUSTIN, TX 78751 | **TX TIER 2** | **S109702802**
N/A

Actual: 636 ft.

Focus Map: 8

TIER 2:

Facility Id/Name:	FATR20086CRR5F002F3W/AUSTIN STATE HOSPITAL
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Safety and Risk Management
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	Not reported
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Not reported
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	MOTOR POOL
Lat/Long Method:	A0 - Address Matching (Other)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes: Not reported

Validation: Signature is required for submission. Date Signed is required for submission. A NAICS code must be reported. State field (TXT2 Number:) required for submission. State field (TXT2 Number:) is required to be a 5-digit number. An Owner/Operator contactrecord is required. An Emergency Contact record is required. None were found. This Facility does not have any Chemical In Inventory records.

AT236 Target Property | **BARTLETTS SERVICE STA & GARAGE**
4231 GUADALUPE
AUSTIN, TX | **EDR Hist Auto** | **1013768389**
N/A

Site 2 of 8 in cluster AT

Actual: 623 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1940	BARTLETTS SERVICE STA & GARAGE	GASOLINE AND OIL SERVICE STATIONS
1940	BARTLETTS SERVICE STA & GARAGE	AUTOMOBILE REPAIRING

AT237 Target Property — **PERFORMANCE SHOP NORTH THE**, **4225 GUADALUPE ST**, **AUSTIN, TX 78751** — **EDR Hist Auto** — **1013773234** / **N/A**

Site 3 of 8 in cluster AT

Actual: 622 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1980	PERFORMANCE SHOP NORTH THE	AUTOMOBILE REPAIRING
1985	L & M VOLKSWERKS INC	Automotive Repair Shops, NEC
1986	L & M VOLKSWERKS INC	Automotive Repair Shops, NEC
1987	L & M VOLKSWERKS INC	Automotive Repair Shops, NEC

AT238 Target Property — **CLEAN & LEAN LAUNDRY & FITNESS**, **4225 GUADALUPE ST**, **TRAVIS (County), TX 78751** — **EDR Hist Cleaner** — **1013781400** / **N/A**

Site 4 of 8 in cluster AT

Actual: 622 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1990	CLEAN & LEAN LAUNDRY & FITNESS	LAUNDRIES AND DRY CLEANERS

AU239 Target Property — **HYDE PARK GPVAGE**, **4215 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013757394** / **N/A**

Site 1 of 7 in cluster AU

Actual: 623 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1929	HYDE PARK GARAGE & FILLING STAT	AUTOMOBILE GARAGES
1929	HYDE PARK GARAGE & FILLING STAT	GASOLINE AND OIL SERVICE STATIONS
1935	HYDE PARK GPVAGE	GASOLINE AND OIL SERVICE STATIONS

AU240 Target Property — **PERFECTION TATTOO**, **4205 GUADALUPE ST**, **AUSTIN, TX 78751** — **TX ASBESTOS** — **S119153762** / **N/A**

Site 2 of 7 in cluster AU

Actual: 622 ft.

Focus Map: 8

ASBESTOS:

Name:	PERFECTION TATTOO
Address:	4205 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	03/19/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

PERFECTION TATTOO (Continued) **S119153762**

Time Spent:	2
Travel Time:	0.16
Mileage:	1.5
Reg:	07
Init:	RC
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	03/24/2014
Date Routed by Supervisor:	03/25/2014
Date Routed to PSQA:	03/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AU241 Target Property | **JAMES HERSHEL R**
4203 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013754640**
N/A

Site 3 of 7 in cluster AU

Actual: 622 ft.

EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1953	JAMES HERSHEL AUTO	AUTOMOBILE REPAIRING
1958	JAMES HERSHEL R	AUTOMOBILE REPAIRING

AV242 Target Property | **AUSTIN STATE HOSPITAL**
4110 GUADALUPE ST
AUSTIN, TX 78751 | **FINDS ECHO** | **1010022958**
N/A

Site 1 of 9 in cluster AV

Actual: 625 ft.

FINDS:
Registry ID: 110028045005

Focus Map: 8

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010022958
Registry ID:	110028045005
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110028045005
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751

AV243 Target Property | **GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER C**
4110 GUADALUPE ST
AUSTIN, TX 78751 | **FINDS** | **1010761410**
N/A

Site 2 of 9 in cluster AV

Actual: 625 ft.
Focus Map: 8

FINDS:
Registry ID: 110033766734

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AV244 Target Property | **AUSTIN STATE HOSPITAL**
4110 GUADALUPE
AUSTIN, TX 78751 | **TX LPST**
TX TIER 2 | **S108443327**
N/A

Site 3 of 9 in cluster AV

Actual: 625 ft.
Focus Map: 8

LPST:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0005228
LPST Id:	109725
Facility Location:	4110 GUADALUPE ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/17/1995
Entered Date:	08/14/1995
Reported Date:	07/17/1995
Closure Date:	05/27/1997
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	ROBERT W KNAPP
Responsible Party Address:	4110 GUADALUPE ST
Responsible Party City,St,Zip:	AUSTIN, TX 78751
Responsible Party Telephone:	512/206-5880
Reported Date:	07/17/1995
Case Start Date:	05/27/1997
Reference Number:	RN100553759
Project Manager:	HWELCH

AUSTIN STATE HOSPITAL (Continued) **S108443327**

TIER 2:

Facility Id/Name:	FATR201049PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2010
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	1/6/2011
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Logan Hopkins
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200949PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2009
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	02/10/2010
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Logan Hopkins
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200849PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2008
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	02-28-2008
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	John Kinniell
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200549PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2005
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	3/7/2006
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Robert A. Woodruff
Latitude:	30.308610
Longitude:	97.735830
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Fire District: Not reported
Additional Mail Addr: Not reported

Facility Info:
Id: Not reported
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 3/3/2006
Id: 8063
Id Type: SIC
Description: PSYCHIATRIC HOSPITAL
Last Modified: 3/3/2006
Id: 0501235
Id Type: Document #
Description: Not reported
Last Modified: 3/17/2006
Id: 622210
Id Type: NAICS
Description: Not reported
Last Modified: 2/27/2009

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Not reported
Contact Name: Cathy Notttebart
Title: Asst. Super
Modification Date: 3/6/2009

Contact:
Contact Email: Not reported
Contact Mail Address: 4110 Guadalupe
Contact City/State/Zip: Austin, TX 78751
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: Logan Hopkins
Title: Safety & Risk Managment Coordinator
Modification Date: 3/13/2010

Contact:
Contact Email: Not reported
Contact Mail Address: 4110 Guadalupe
Contact City/State/Zip: Austin, TX 78751
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Other
Contact Type 3: Owner / Operator
Contact Name: Austin State Hospital
Title: Department of State Health Services
Modification Date: 3/13/2010

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Chemical Inventory:

Facility Id:	FATR200949PVFJ002111
Chemical Name:	unleaded gasoline
Chemical Inv Record Id:	CVTR200949PW1P005EY1
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	24236
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200949YH8T0025SN
Chemical Inventory Record Id:	CVTR200949PW1P005EY1
Amt Of Sub Stored Or Transported:	4000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	west side of campus, 4110 N. Lamar
Last Modified:	3/13/2010

Facility Id:	FATR200949PVFJ002111
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR200949YHM4004U79
CAS Number:	68476-30-2
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	13280
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200949YRCT005WZY
Chemical Inventory Record Id:	CVTR200949YHM4004U79
Amt Of Sub Stored Or Transported:	2000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	West side of campus, 4110 N. Lamar
Last Modified:	3/13/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:

Id:	0501235
Id Type:	Document #
Description:	Not reported
Last Modified:	3/17/2006
Id:	622210
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/27/2009
Id:	8063
Id Type:	SIC
Description:	PSYCHIATRIC HOSPITAL
Last Modified:	3/3/2006
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	3/3/2006

Contact:

Contact Email:	logan.hopkins@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Other
Contact Type 3:	Owner / Operator
Contact Name:	Austin State Hospital
Title:	Department of State Health Services
Modification Date:	4/2/2011

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Contact:

Contact Email:	logan.hopkins@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Logan Hopkins
Title:	Safety & Risk Managment Coordinator
Modification Date:	4/2/2011

Contact:

Contact Email:	catherine.nottebart@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Not reported
Contact Name:	Cathy Notttebart
Title:	Asst. Super
Modification Date:	1/6/2011

Chemical Inventory:

Facility Id:	FATR201049PVFJ002111
Chemical Name:	unleaded gasoline
Chemical Inv Record Id:	CVTR201049PW1P005EY1
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	24236
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201049YH8T0025SN
Chemical Inventory Record Id:	CVTR201049PW1P005EY1
Amt Of Sub Stored Or Transported:	4000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1

AUSTIN STATE HOSPITAL (Continued) **S108443327**

Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: west side of campus, 4110 N. Lamar
Last Modified: 4/2/2011

Facility Id: FATR201049PVFJ002111
Chemical Name: DIESEL FUEL
Chemical Inv Record Id: CVTR201049YHM4004U79
CAS Number: 68476-30-2
Chemical Same As Last Year: T
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: 13280
Chronic Health Risks: T
EHS Substance: Not reported
Last Modified: 4/2/2011
Days On Site: 365
Fire Hazard: T
Gas: Not reported
Liquid: T
Mixture Form: Not reported
Sudden Release Of Pressure Haz: Not reported
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: tx2010
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201049YRCT005WZY
Chemical Inventory Record Id: CVTR201049YHM4004U79
Amt Of Sub Stored Or Transported: 2000
Amount Units: gallons
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: West side of campus, 4110 N. Lamar
Last Modified: 4/2/2011

Notes: Not reported
Validation: Not reported

Notes: Not reported

Validation: An Owner/Operator contact record is required. ---------- Validation Errors for Chemical: Chemical Name is required for submission. One of the check boxes, pure or mixture, must be checked. One of the check boxes, solid, liquid or gas, must be checked. Maximum Amount Code is required for submission. Average Amount Code is required for submission. Storage Location information is required for submission. ---------- Validation Errors for Chemical: Chemical Name is

AUSTIN STATE HOSPITAL (Continued) **S108443327**

required for submission. One ofthe check boxes, pure or mixture, must be checked. One of the check boxes, solid, liquid or gas, must be checked. Maximum Amount Code is required for submission. Average Amount Code is required for submission. Storage Location information is required for submission.

Notes: Not reported
Validation: Not reported

AV245 **AUSTIN STATE HOSPITAL** **RCRA-VSQG** **1000412177**
Target **4110 GUADALUPE ST** **TX AST** **TXD120593165**
Property **AUSTIN, TX 78751** **TX SPILLS**
TX ASBESTOS
Site 4 of 9 in cluster AV **TX Ind. Haz Waste**
TX IHW CORR ACTION
Actual: **TX RDR**
625 ft. **TX CENTRAL REGISTRY**

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20220216
Handler Name:	Austin State Hospital
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78751
EPA ID:	TXD120593165
Contact Name:	LISA M MICAN
Contact Address:	GUADALUPE ST
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Telephone:	512-419-2757
Contact Fax:	Not reported
Contact Email:	LISA.MICAN@HHS.TEXAS.GOV
Contact Title:	DIRECTOR OF PHARMACY
EPA Region:	06
Land Type:	State
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE ST
Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Name:	Austin State Hospital
Owner Type:	Other
Operator Name:	Austin State Hospital
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221012
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	H

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	F003

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U188
Waste Description: Phenol

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN STATE HOSPITAL	
Legal Status:	Other
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	4110 GUADALUPE ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78751
Owner/Operator Telephone:	512-452-0381
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: STACEY THOMPSON	
Legal Status:	State
Date Became Current:	20190206
Date Ended Current:	Not reported
Owner/Operator Address:	4110 GUADALUPE ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78751
Owner/Operator Telephone:	512-419-2970
Owner/Operator Telephone Ext:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Owner/Operator Fax: Not reported
Owner/Operator Email: STACEY.THOMPSON@HHS.TEXAS.GOV

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN STATE HOSPITAL
Legal Status: Other
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 4110 GUADALUPE ST
Owner/Operator City,State,Zip: AUSTIN, TX 78751
Owner/Operator Telephone: 512-452-0381
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN STATE HOSPITAL
Legal Status: Other
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 4110 GUADALUPE ST
Owner/Operator City,State,Zip: AUSTIN, TX 78751
Owner/Operator Telephone: 512-452-0381
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN STATE HOSPITAL
Legal Status: Other
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 4110 GUADALUPE ST
Owner/Operator City,State,Zip: AUSTIN, TX 78751
Owner/Operator Telephone: 512-452-0381
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS - TEXAS HEALTH AND HUMAN SERVICES
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4601 GUADALUPE ST

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Owner/Operator City,State,Zip: AUSTIN, TX 78751
Owner/Operator Telephone: 512-424-6500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19851125
Handler Name: AUSTIN STATE HOSP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: AUSTIN STATE HOSPITAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220216
Handler Name: AUSTIN STATE HOSPITAL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 622210
NAICS Description: PSYCHIATRIC AND SUBSTANCE ABUSE HOSPITALS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AUSTIN STATE HOSPITAL (Continued) **1000412177**

AST:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787514223
Facility ID:	136752
Additional ID:	438304252021007
AI Number:	91655
Facility Type:	FLEET REFUELING
Facility Begin Date:	02/19/1996
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	2
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78751
Contact Name/Title:	BRAD GONZALES/
Contact Organization Name:	AUSTIN STATE HOSPITAL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124192336
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	Not reported
Signature First Name on Earliest Reg Form:	Not reported
Application Received Date on Earliest Reg Form:	Not reported
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	Not reported
Signature Title on Earliest Reg Form:	Not reported
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	136752
Tank ID:	1
AST ID:	226081
AI Number:	91655
Install Date:	11/19/2020
Tank Registration Date:	12/16/2020
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	11/19/2020
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	Not reported
Other Substance B:	Not reported
Other Substance C:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

Facility ID:	136752
Tank ID:	2
AST ID:	226082
AI Number:	91655
Install Date:	11/19/2020
Tank Registration Date:	12/16/2020
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	11/19/2020
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	4000
Substance:	Not reported
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

Facility ID:	136752
Tank ID:	1A
AST ID:	226191
AI Number:	91655
Install Date:	02/19/1996
Tank Registration Date:	06/28/1996
Mult Comp:	Y
Tank Status:	OUT OF USE
Tank Status Date:	02/01/2021
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	DIESEL
Other Substance B:	GASOLINE
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

SPILLS:

Name:	FACILITY AT ABOVE LOCATION
Address:	FACILITY AT ABOVE LOCATION
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	11/17/1989
Seq Num:	Not reported
Responsible Party Name:	AUSTIN STATE HOSPITAL
Responsible Party Address:	4110 GUADALUPE
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	787514296
Responsible Party Telephone:	5124520381
Substance:	FUEL OIL
Material Code:	1022
Media Affected:	NO
Permit Number:	NONE
District:	14
Origin:	001
Cause:	007
Basin Code:	1429
Notify Date:	Not reported
Adequate Clean:	NO
Classification:	003
Basin Name:	COLORADO
Water Affected:	NONE
Amnt Spilled:	UNKNOWN
Amnt in Water:	NONE
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	TWC
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	C. CARSON
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

ASBESTOS:

Name:	AUSTIN STATE HOSPITAL BUILDING 796
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	04/14/2016
Notification Number:	2016002797
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/13/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	04/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL BUILDING 796
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	04/13/2016
Notification Number:	2016002797
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/12/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	04/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL BUILDING 796
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	04/13/2016
Notification Number:	2016002797
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/30/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/30/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	04/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL ADMIN BUILDING
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	07/16/2016
Notification Number:	2016005370
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/29/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	07/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL ADMIN BUILDING
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	08/08/2016
Notification Number:	2016005370
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/24/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/24/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Analytical Method:	Assumed Asbestos
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	61330
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD120593165
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	OTHER
Description of Facility Site Location:	4110 Guadalupe St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN STATE HOSPITAL
Contact Name:	HARVEY DAVIS
Contact Telephone Number:	512-4520381
Mailing Address:	4110 GUADALUPE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787514223
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19684

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021106
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN STATE HOSPITAL
Operator Address:	4110 GUADALUPE ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78751
Operator Country:	UNITED STA
Operator Telephone:	1-512-4520381
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN STATE HOSPITAL
Owner Mailing Address:	4110 GUADALUPE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Country:	UNITED STA
Owner Telephone:	1-512-4520381
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4110 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4520381
Contact Fax:	Not reported
Contact Email:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4110 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4520381
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	HARVEY DAVIS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4110 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4520381
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	262871
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5JN119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262872
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5JP297H
Waste Code Status:	Not reported
Waste Form:	297
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262873
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5JQ209H
Waste Code Status:	Not reported
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262874
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5JS2061
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Ind. Haz Waste:

Waste ID:	265189
Texas Waste Code:	Not reported
Texas Waste Code 2:	C89W119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	265190
Texas Waste Code:	Not reported
Texas Waste Code 2:	C89X003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	265191
Texas Waste Code:	Not reported
Texas Waste Code 2:	C89Y117H
Waste Code Status:	Not reported
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266548
Texas Waste Code:	Not reported
Texas Waste Code 2:	C9XP2061
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266549
Texas Waste Code:	Not reported
Texas Waste Code 2:	C9XQ119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266550
Texas Waste Code:	Not reported
Texas Waste Code 2:	C9XR003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266551
Texas Waste Code:	Not reported
Texas Waste Code 2:	C9XS003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266872
Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC24091
Waste Code Status:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266873
Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC32061
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266874
Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC4119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

AUSTIN STATE HOSPITAL (Continued) **1000412177**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266875
Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC5003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266876
Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC6003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266877

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Texas Waste Code:	Not reported
Texas Waste Code 2:	CBC7003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	278968
Texas Waste Code:	Not reported
Texas Waste Code 2:	CSYH211H
Waste Code Status:	Not reported
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4110 GUADALUPE ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78751
AR Number:	0000310688
Principal Name:	AUSTIN STATE HOSPITAL
Attention Name:	Not reported
Attention Suffix:	NWF

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4110 GUADALUPE ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78751
AR Number:	0000310688
Principal Name:	AUSTIN STATE HOSPITAL
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4110 GUADALUPE ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78751
AR Number:	0000310688
Principal Name:	AUSTIN STATE HOSPITAL
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4110 GUADALUPE ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78751
AR Number:	0000310688
Principal Name:	AUSTIN STATE HOSPITAL
Attention Name:	Not reported
Attention Suffix:	HWF

IHW CORR ACTION:

Name:	TEXAS DEPT OF MENTAL HEALTH AND MENTAL RETARDATION AUSTIN ST
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Program Id:	61330
Location Desc:	4110 Guadalupe ST, AUSTIN, TX
RN NUM:	RN100553759
Status:	INACTIVE
Status Date:	07/14/2004
EDR Link ID:	61330
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	07/14/2004
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

RDR:

RDR ID:	29932
Facility ID:	5228
RN:	100553759
CN:	600264683

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/14/2021
Due Date:	6/13/2021
Tank Owner:	AUSTIN STATE HOSPITAL
Contact Person:	RUBEN MENDOZA
Report:	Tank Closure
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/28/2021
Project Manager:	Frank Clayworth
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600264683
Customer Name:	AUSTIN STATE HOSPITAL
Customer Legal Name:	Austin State Hospital
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600264683
Customer Name:	AUSTIN STATE HOSPITAL
Customer Legal Name:	Austin State Hospital
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number: RN100553759
Name: AUSTIN STATE HOSPITAL
Address: 4110 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4223
Status: ACTIVE
Status Date: ##########
Customer Number: CN600264683
Customer Name: AUSTIN STATE HOSPITAL
Customer Legal Name: Austin State Hospital
Customer Ownership Type: OTHER GOVERNMENT
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number: RN100553759
Name: AUSTIN STATE HOSPITAL
Address: 4110 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4223
Status: ACTIVE
Status Date: ##########
Customer Number: CN601229313
Customer Name: GABLES RESIDENTIAL TRUST
Customer Legal Name: Gables Residential Trust
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number: RN100553759
Name: AUSTIN STATE HOSPITAL
Address: 4110 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4223
Status: ACTIVE
Status Date: ##########
Customer Number: CN601229313
Customer Name: GABLES RESIDENTIAL TRUST
Customer Legal Name: Gables Residential Trust
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 4110 Guadalupe ST, AUSTIN, TX

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601098403
Customer Name:	TEXAS DEPARTMENT OF MENTAL HEALTH AND MENTAL RETARDATION
Customer Legal Name:	Texas Department of Mental Health and Mental Retardation
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601098403
Customer Name:	TEXAS DEPARTMENT OF MENTAL HEALTH AND MENTAL RETARDATION
Customer Legal Name:	Texas Department of Mental Health and Mental Retardation
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604452326
Customer Name:	TEXAS STATE HOSPITAL
Customer Legal Name:	Texas State Hospital
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST

AUSTIN STATE HOSPITAL (Continued) **1000412177**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604452326
Customer Name:	TEXAS STATE HOSPITAL
Customer Legal Name:	Texas State Hospital
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605437276
Customer Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Customer Legal Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	3/27/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Regulated Entity Number:	RN100553759
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4223
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605437276
Customer Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Customer Legal Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	3/27/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4110 Guadalupe ST, AUSTIN, TX

Click this hyperlink while viewing on your computer to access
62 additional TX CENTRAL REG: record(s) in the EDR Site Report.

AV246 **ERNS** **89119009**
Target Property **4110 GUADALUPE** **N/A**
AUSTIN, TX -

Site 5 of 9 in cluster AV

Actual: 625 ft.

Focus Map: 8

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

AV247 **GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER C** **TX RGA LF** **S115125585**
Target Property **4110 GUADALUPE ST** **N/A**
AUSTIN, TX

Site 6 of 9 in cluster AV

Actual: 625 ft.

Focus Map: 8

RGA LF:

2012 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2011 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2010 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2009 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2008 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2007 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST
2004 GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL 4110 GUADALUPE ST

AV248 **AUSTIN STATE HOSPITAL** **TX ASBESTOS** **S111992538**
Target Property **4110 GUADALUPE STREET** **TX TIER 2** **N/A**
AUSTIN, TX 78751

Site 7 of 9 in cluster AV

Actual: 625 ft.

Focus Map: 8

ASBESTOS:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	12/04/2020
Notification Number:	2020006872
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/03/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	12/03/2020
Notification Number:	2020006872
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/03/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	12/04/2020
Notification Number:	2020006872
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/13/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/13/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Analytical Method:	PLM
Start Date:	11/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	12/04/2020
Notification Number:	2020006872
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/13/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Work Type Flag:	D
Certification Statement Date:	11/13/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	09/18/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/02/2020
Date Routed by Supervisor:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/02/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/14/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	10/16/2020
Notification Number:	2020005439
ASB Priority:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/02/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	09/18/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/14/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	10/07/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/28/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	09/18/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/18/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/18/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/14/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	10/23/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/18/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/18/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/05/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	09/18/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/27/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	09/15/2020
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	09/30/2020
Notification Number:	2020005439
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/27/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/21/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/09/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	09/15/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020005439
File Number:	54589
License Status Description:	Paid
Expiration Date:	10/16/2020
Original Date:	08/27/2020
Rank Effective Date:	08/27/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	23398
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/02/02
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	02/02/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021000313
File Number:	58217
License Status Description:	Paid
Expiration Date:	03/19/2021
Original Date:	01/18/2021
Rank Effective Date:	01/18/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25739
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Complaint Date:	2019/12/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	12/19/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019008012
File Number:	46504
License Status Description:	Paid
Expiration Date:	04/08/2020
Original Date:	10/28/2019
Rank Effective Date:	10/28/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20049
Inspection Status:	Closed

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/06/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/24/2020

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020004010
File Number:	53054
License Status Description:	Paid
Expiration Date:	07/17/2020
Original Date:	06/08/2020
Rank Effective Date:	06/08/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	22370
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/06/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/24/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020004010
File Number:	53054
License Status Description:	Paid
Expiration Date:	07/17/2020
Original Date:	06/08/2020
Rank Effective Date:	06/08/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	22369
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/02/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	06/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/08/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/17/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	06/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/08/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/02/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/09/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/17/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/09/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/02/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/17/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/02/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/22/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/24/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	07/17/2020
Notification Number:	2020004010
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/22/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/22/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland Delagarza
Violation:	Not reported
Complaint Date:	08/27/2016
Notification Number:	2016006837
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	08/25/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/25/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/26/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	08/27/2016
Notification Number:	2016006837
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	08/10/2016

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/10/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/26/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Roland DeLaGarza
Violation:	Not reported
Complaint Date:	08/24/2016
Notification Number:	2016006837

AUSTIN STATE HOSPITAL (Continued) **S111992538**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	08/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/09/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/10/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/08/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/18/2019
Client Code:	Not reported
Client Name:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/17/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/15/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/24/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/25/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/25/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/02/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/24/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/02/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/24/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/17/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/24/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/18/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill :Post
Violation:	Not reported
Complaint Date:	01/24/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/27/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/03/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/28/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	134
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Violation:	Not reported
Complaint Date:	02/19/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	17
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/08/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	04/08/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	17
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/08/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/28/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Certification Statement Date:	01/06/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill :Post
Violation:	Not reported
Complaint Date:	02/28/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill :Post
Violation:	Not reported
Complaint Date:	10/30/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/10/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/27/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/28/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/16/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	10/30/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/16/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

AUSTIN STATE HOSPITAL (Continued) **S111992538**

ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/27/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/28/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/27/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	11/06/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/27/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET

AUSTIN STATE HOSPITAL (Continued) **S111992538**

City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/28/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/13/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/13/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	11/06/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/13/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/13/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/19/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/20/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	11/06/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Report Received:	02/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/20/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/19/2020

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/03/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/01/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/03/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/19/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/06/2020
Certification Statement Phone:	512-778-6800

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/08/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/06/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	02/19/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	16
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/16/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	04/12/2021
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/15/2020
Notification Number:	2019008012
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	16
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/16/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	163
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	02/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/22/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	03/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/22/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	02/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/22/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Violation:	Not reported
Complaint Date:	03/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/22/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	02/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/18/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/18/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	02/02/2021
Reason for Inspection:	MATTHEW T KUBASTA
Violation:	Not reported
Complaint Date:	03/19/2021
Notification Number:	2021000313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/18/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Certification Statement Date:	01/18/2021
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Matt Kubasta
Violation:	Not reported
Complaint Date:	12/23/2022
Notification Number:	2022007188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/20/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/03/2022
Notification Number:	2022007188
ASB Priority:	Not reported
PIF State:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/27/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/30/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/09/2022
Notification Number:	2022007188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/30/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/30/2022
Certification Statement Phone:	5127786800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/06/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/23/2022
Notification Number:	2022007188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/06/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

AUSTIN STATE HOSPITAL (Continued) **S111992538**

ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/01/2022
Notification Number:	2022007188
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/14/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TIER 2:

Facility Id/Name:	FATR201249PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2012
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/19/2013
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Submitted By:	Gabriel Moreno
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR201149PVFJ002111/AUSTIN STATE HOSPITAL
Reporting Year:	2011
Facility Country:	USA
Facility Department:	DSHS
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	2/27/2012
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	814
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Gabriel Moreno
Latitude:	30.30861
Longitude:	97.73583
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G1 - GPS (Static)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	3/3/2006
Id:	0501235
Id Type:	Document #
Description:	Not reported
Last Modified:	3/17/2006
Id:	8063
Id Type:	SIC
Description:	PSYCHIATRIC HOSPITAL
Last Modified:	3/3/2006

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Id:	622210
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/27/2009

Contact:

Contact Email:	Gabriel.Moreno@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Other
Contact Type 3:	Owner / Operator
Contact Name:	ASH Austin State Hospital
Title:	Department of State Health Services
Modification Date:	2/22/2013

Contact:

Contact Email:	catherine.nottebart@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Not reported
Contact Name:	Cathy Nottebart
Title:	Asst. Super
Modification Date:	2/27/2012

Contact:

Contact Email:	Gabriel.Moreno@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe Street
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Gabriel Moreno
Title:	Safety/Risk Management Coordinator
Modification Date:	2/27/2012

Contact:

Contact Email:	Richard.Reneau@dshs.state.tx.us
Contact Mail Address:	4110 Guadalupe St.
Contact City/State/Zip:	Austin, TX 78751
Contact Mail Country:	USA
Contact Type 1:	Other
Contact Name:	Richard Reneau
Title:	Director of Maintenance
Modification Date:	2/19/2013

Chemical Inventory:

Facility Id:	FATR201249PVFJ002111
Chemical Name:	unleaded gasoline
Chemical Inv Record Id:	CVTR201249PW1P005EY1
CAS Number:	8006-61-9

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	24236
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/22/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201249YH8T0025SN
Chemical Inventory Record Id:	CVTR201249PW1P005EY1
Amt Of Sub Stored Or Transported:	4000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	west side of campus, 4110 N. Lamar
Last Modified:	2/22/2013

Facility Id:	FATR201249PVFJ002111
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR201249YHM4004U79
CAS Number:	68476-30-2
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	13280
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/22/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2012

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201249YRCT005WZY
Chemical Inventory Record Id: CVTR201249YHM4004U79
Amt Of Sub Stored Or Transported: 2000
Amount Units: gallons
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: West side of campus, 4110 N. Lamar
Last Modified: 2/22/2013

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 0501235
Id Type: Document #
Description: Not reported
Last Modified: 3/17/2006
Id: 8063
Id Type: SIC
Description: PSYCHIATRIC HOSPITAL
Last Modified: 3/3/2006
Id: Not reported
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 3/3/2006
Id: 622210
Id Type: NAICS
Description: Not reported
Last Modified: 2/27/2009

Contact:
Contact Email: Gabriel.Moreno@dshs.state.tx.us
Contact Mail Address: 4110 Guadalupe
Contact City/State/Zip: Austin, TX 78751
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Other
Contact Type 3: Owner / Operator
Contact Name: ASH Austin State Hospital
Title: Department of State Health Services
Modification Date: 3/9/2012

Contact:
Contact Email: catherine.nottebart@dshs.state.tx.us
Contact Mail Address: 4110 Guadalupe
Contact City/State/Zip: Austin, TX 78751
Contact Mail Country: USA
Contact Type 1: Not reported
Contact Name: Cathy Nottebart

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Title: Asst. Super
Modification Date: 2/27/2012

Contact:
Contact Email: Gabriel.Moreno@dshs.state.tx.us
Contact Mail Address: 4110 Guadalupe Street
Contact City/State/Zip: Austin, TX 78751
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Name: Gabriel Moreno
Title: Safety/Risk Management Coordinator
Modification Date: 2/27/2012

Chemical Inventory:
Facility Id: FATR201149PVFJ002111
Chemical Name: unleaded gasoline
Chemical Inv Record Id: CVTR201149PW1P005EY1
CAS Number: 8006-61-9
Chemical Same As Last Year: T
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: 24236
Chronic Health Risks: T
EHS Substance: Not reported
Last Modified: 3/9/2012
Days On Site: 365
Fire Hazard: T
Gas: Not reported
Liquid: T
Mixture Form: Not reported
Sudden Release Of Pressure Haz: Not reported
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: tx2011
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201149YH8T0025SN
Chemical Inventory Record Id: CVTR201149PW1P005EY1
Amt Of Sub Stored Or Transported: 4000
Amount Units: gallons
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: west side of campus, 4110 N. Lamar
Last Modified: 3/9/2012

Facility Id: FATR201149PVFJ002111
Chemical Name: DIESEL FUEL
Chemical Inv Record Id: CVTR201149YHM4004U79
CAS Number: 68476-30-2

AUSTIN STATE HOSPITAL (Continued) **S111992538**

Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	13280
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/9/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	tx2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201149YRCT005WZY
Chemical Inventory Record Id:	CVTR201149YHM4004U79
Amt Of Sub Stored Or Transported:	2000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	West side of campus, 4110 N. Lamar
Last Modified:	3/9/2012

Notes: Not reported
Validation: Not reported

AV249 **AUSTIN STATE HOSPITAL** **TX UST** **U003841440**
Target **4110 GUADALUPE ST** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78751**

Site 8 of 9 in cluster AV

Actual:
625 ft.

Focus Map:
8

UST:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787514223
AI Number:	91655
Facility Type:	FLEET REFUELING
Facility Begin Date:	02/19/1996
Facility Status:	ACTIVE
Additional ID:	438304252021007
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	BRAD GONZALES,
Contact Organization Name:	AUSTIN STATE HOSPITAL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124192336
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Application Received Date On Earliest Reg Form:	Not reported
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	592385872017317
Additional ID:	438304252021007
Ai Number:	91655
Operator CN:	CN605437276
Operator Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Operator Effective Begin Date:	11/19/2020
Operator Type:	SG
Operator Role:	OPRCON
Contact Name:	TIMOTHY E BRAY/ASSOCIATE COMMISSIONER
Contact Organization Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Contact Mailing Address (Delivery):	6711 S NEW BRAUNFELS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78223-3005
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	2065336
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	TIM.BRAY@HHSC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605437276
Owner Last Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 38
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	CARLSBAD
Contact Mailing State:	TX

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Contact Mailing Zip:	76934
Contact Mailing Zip5:	0038
Contact Phone Number/Ext:	1 325 4654391/0
Contact Fax Country Code:	1
Contact Fax Number/Ext:	325 4652801/0
Contact Email Address:	NATALIE.MONTALVO@HHSC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	592385872017317
Additional ID:	438304252021007
AI Number:	91655
Owner Effective Begin Date:	11/19/2020
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	NATALIE MONTALVO/DIRECTOR
Contact Organization Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	225121
Facility ID:	136752
Ai Number:	91655
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/31/1978
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

AUSTIN STATE HOSPITAL (Continued) **U003841440**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/23/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	196402
UST ID:	225121
AI Number:	91655
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	225113
Facility ID:	136752
Ai Number:	91655
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/27/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

AUSTIN STATE HOSPITAL (Continued) **U003841440**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/23/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	196394
UST ID:	225113
AI Number:	91655
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	225114
Facility ID:	136752
Ai Number:	91655
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/27/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/23/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	196395
UST ID:	225114
AI Number:	91655
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	225115

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Facility ID:	136752
Ai Number:	91655
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/27/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/23/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000

AUSTIN STATE HOSPITAL (Continued) **U003841440**

UST Comprt ID:	196396
UST ID:	225115
AI Number:	91655
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	225122
Facility ID:	136752
Ai Number:	91655
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/27/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/23/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	196403
UST ID:	225122
AI Number:	91655
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

AUSTIN STATE HOSPITAL (Continued) **U003841440**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	37826
Facility ID:	136752
AI Number:	91655
Application Received Date:	03/08/2021
Scheduled Construction Date:	03/05/2021
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	03/08/2021
Signature Date On Form:	03/05/2021
Signature Name On Form:	RYAN METZ
Signature Company On Form:	Not reported
Signature Title On Form:	MARKET SPEC

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Owner CN At Time Of Construction:	CN605437276
Owner AR At Time Of Construction:	82325
General Desc Of Prop Construct:	REMOVAL OF UNREGISTERED "GHOST" UST DISCOVERED DURING CONSTRUCTION ACTIVITIES

NOC ID:	37675
Facility ID:	136752
AI Number:	91655
Application Received Date:	01/04/2021
Scheduled Construction Date:	01/04/2021
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	Y
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	03/08/2021
Signature Date On Form:	03/05/2021
Signature Name On Form:	RYAN METZ
Signature Company On Form:	Not reported
Signature Title On Form:	MARKET SPEC
Signature Role:	Not reported
Owner Name At Time Of Construction:	AUSTIN STATE HOSPITAL;AUSTIN STATE HOSPITAL
Owner CN At Time Of Construction:	CN600264683,CN600264683
Owner AR At Time Of Construction:	3311A,3311U
General Desc Of Prop Construct:	INSTALLATION OF NEW AST SYSTEM FOR BACK UP GENERATORS

NOC ID:	37674
Facility ID:	136752
AI Number:	91655
Application Received Date:	01/04/2021
Scheduled Construction Date:	01/04/2021
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	Y
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	03/08/2021
Signature Date On Form:	03/05/2021
Signature Name On Form:	RYAN METZ

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Signature Company On Form:	Not reported
Signature Title On Form:	MARKET SPEC
Signature Role:	Not reported
Owner Name At Time Of Construction:	AUSTIN STATE HOSPITAL;AUSTIN STATE HOSPITAL
Owner CN At Time Of Construction:	CN600264683,CN600264683
Owner AR At Time Of Construction:	3311A,3311U
General Desc Of Prop Construct:	INSTALLATION OF NEW AST SYSTEM FOR BACK UP GENERATORS

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	89996
UST ID:	Not reported
NOC ID:	37826
AI Number:	91655
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON
Representative Name:	CODY W PFUND PULLIAM
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS BLVD STE 160
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	89997
UST ID:	Not reported
NOC ID:	37826
AI Number:	91655
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	GREUNE ENVIRONMENTAL CONSTRUCTION LP
Representative Name:	RYAN METZ
Mailing Address (Delivery):	1659 W STATE HIGHWAY 46 STE 115
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Cont/Cons/Installer ID:	89509
UST ID:	Not reported
NOC ID:	37674
AI Number:	91655
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	UST FUEL SOLUTIONS
Representative Name:	SERGIO PEREZ
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	89510
UST ID:	Not reported
NOC ID:	37675
AI Number:	91655
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	UST FUEL SOLUTIONS
Representative Name:	SERGIO PEREZ
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS HEALTH AND HUMAN SERVICES COMMISSION
Contact Mailing Address (Delivery):	4110 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 4223
Phone Number/Ext:	512 4192371/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y

AUSTIN STATE HOSPITAL (Continued) **U003841440**

Facility ID:	136752
Additional ID:	438304252021007
Princ ID:	592385872017317
AI Number:	91655
Facility Name:	AUSTIN STATE HOSPITAL
AR Number:	82325
AR UST Number Suffix:	A
AR AST Number Suffix:	Not reported
Contact Name/Title:	BRAD GONZALES/

HIST UST AUSTIN:

Name:	AUSTIN STATE HOSPITAL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0573
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AV250 **GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER C** **TX SWF/LF** **S116753811**
Target **4110 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78751**

Site 9 of 9 in cluster AV

Actual:
625 ft.

Focus Map:
8

SWF/LF:

Name:	GABLES RESIDENTIAL TRUST ENCLOSED STRUCTURE OVER CLOSED LANDFILL
Address:	4110 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751-4223
Region:	11
Permit Number:	65003
Facility Status:	CLOSED
Facility Type:	CR
Permit Status:	ISSUED
Status Date:	04/24/2001
Mailing Address:	Not reported
Client Name:	CN601229313, Gables Residential Trust
Client Address:	2925 BRIARPARK DR HOUSTON, TX 77042-3720
Client Telephone:	N/A
Business Type:	INDIVIDUAL
Area Served:	Not reported
Estimated Closure Date:	Not reported
Permit Acreage:	Not reported
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	30.30701 / -97.73553

AU251 Target Property | **NUNNELEE H W**
4201 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013760091**
N/A

Site 4 of 7 in cluster AU

Actual: 622 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1935	NUNNELEE H W	AUTOMOBILE REPAIRERS
1935	NUNNELEE H W	GASOLINE AND OIL SERVICE STATIONS
1940	GEORGE ROY GULF	GASOLINE AND OIL SERVICE STATIONS
1947	COTTONS GULF SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1953	KUEHNER GULF SERV	GASOLINE STATIONS
1958	KUEHNER GULF SERV	GASOLINE STATIONS
1965	CARTER AUTOMATIC	AUTOMOBILE REPAIRING
1975	BATLA AUTO SERVICE	AUTOMOBILE REPAIRING
1979	BILLS AUTO CENTER	General Automotive Repair Shops
1980	BILLS AUTO CENTER	General Automotive Repair Shops
1982	BILLS AUTO CENTER	General Automotive Repair Shops

AU252 Target Property | **GUADALUPE HUBSITE**
4201 GUADALUPE ST
AUSTIN, TX 78751 | **FINDS** | **1024210445**
N/A

Site 5 of 7 in cluster AU

Actual: 622 ft.
Focus Map: 8

FINDS:
Registry ID: 110070198109

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AU253 Target Property | **TX-13 TIME WARNER CABLE - GUADALUPE HUBSITE**
4201 GUADALUPE ST
AUSTIN, TX 78757 | **TX TIER 2** | **S112000454**
N/A

Site 6 of 7 in cluster AU

Actual: 622 ft.
Focus Map: 8

TIER 2:

Facility Id:	FATR20118DEE610161AE
Facility Name:	TX-13 TIME WARNER CABLE - GUADALUPE HUBSITE
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	2/24/2012
Mailing Address:	7800 Crescent Executive Drive
Mailing City/State/Country:	Charlotte, NC USA

TX-13 TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S112000454**

Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	400
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Donna Pallister/Senior Environmental Engineer
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4841
Id Type:	SIC
Description:	CABLE & OTHER PAY TV SERVICES
Last Modified:	2/1/2012
Id:	51322
Id Type:	NAICS
Description:	Cable and Other Program Distribution
Last Modified:	2/1/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	7800 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Time Warner Cable
Title:	Not reported
Modification Date:	2/27/2012

Contact Email:	Not reported
Contact Mail Address:	7800 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Time Warner Cable
Title:	Not reported
Modification Date:	2/27/2012

Contact:

Contact Email:	bruce.buchanan@twcable.com
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA

TX-13 TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S112000454**

Contact Type 1:	Emergency Contact
Contact Name:	Bruce Buchanan
Title:	Not reported
Modification Date:	2/27/2012
Contact Email:	bruce.buchanan@twcable.com
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Bruce Buchanan
Title:	Not reported
Modification Date:	2/27/2012

Contact:

Contact Email:	marty.cheshire@twcable.com
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Other
Contact Name:	Marty Cheshier
Title:	Engineering Hub Site USTs - Primary Contact
Modification Date:	2/1/2012

Contact:

Contact Email:	steve.reisner@twcable.com
Contact Mail Address:	7820 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Steve Reisner
Title:	Director of Risk Management
Modification Date:	2/21/2012
Contact Email:	steve.reisner@twcable.com
Contact Mail Address:	7820 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Steve Reisner
Title:	Director of Risk Management
Modification Date:	2/21/2012

Chemical Inventory:

Facility Id:	FATR20118DEE610161AE
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	CVTR20118DEENY00ANTJ
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	12.52
Chronic Health Risks:	Not reported

TX-13 TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S112000454**

EHS Substance:	T
Last Modified:	2/27/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118DEESW00B25K
Chemical Inventory Record Id:	CVTR20118DEENY00ANTJ
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Located in hub (40 CSB Batteries)
Last Modified:	2/27/2012

Notes: Not reported
Validation: Not reported

AU254 **TX-13 - TIME WARNER CABLE - GUADALUPE HUBSITE** **TX TIER 2** **S113683382**
Target **4201 GUADALUPE ST.** **N/A**
Property **AUSTIN, TX 78705**

Site 7 of 7 in cluster AU

Actual: 622 ft.

Focus Map: 8

TIER 2:

Facility Id:	FATR20128DEE610161AE
Facility Name:	TX-13 - TIME WARNER CABLE - GUADALUPE HUBSITE
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/28/2013
Mailing Address:	7800 Crescent Executive Drive
Mailing City/State/Country:	Charlotte, NC USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	400
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Donna Pallister, Senior Environmental Scientist
Latitude:	Not reported
Longitude:	Not reported

TX-13 - TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S113683382**

Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4841
Id Type:	SIC
Description:	CABLE & OTHER PAY TV SERVICES
Last Modified:	2/1/2012
Id:	51322
Id Type:	NAICS
Description:	Cable and Other Program Distribution
Last Modified:	2/1/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	7800 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Time Warner Cable
Title:	Not reported
Modification Date:	3/8/2013

Contact Email:	Not reported
Contact Mail Address:	7800 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Time Warner Cable
Title:	Not reported
Modification Date:	3/8/2013

Contact:

Contact Email:	bruce.buchanan@twcable.com
Contact Mail Address:	11921 North Mopac Expressway
Contact City/State/Zip:	Austin, TX 78759
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Bruce Buchanan
Title:	Regional Fulfillment Manager, Critical Infrastructures
Modification Date:	3/8/2013

Contact Email:	bruce.buchanan@twcable.com
Contact Mail Address:	11921 North Mopac Expressway
Contact City/State/Zip:	Austin, TX 78759
Contact Mail Country:	USA

TX-13 - TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S113683382**

Contact Type 1:	Emergency Contact
Contact Name:	Bruce Buchanan
Title:	Regional Fulfillment Manager, Critical Infrastructures
Modification Date:	3/8/2013

Contact:

Contact Email:	marty.cheshire@twcable.com
Contact Mail Address:	12012 North Mopac Expressway
Contact City/State/Zip:	Austin, TX 78758
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Marty Cheshier
Title:	Engineering Hub Site USTs - Primary Contact
Modification Date:	3/8/2013

Contact:

Contact Email:	steve.reisner@twcable.com
Contact Mail Address:	7820 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Steve Reisner
Title:	Director of Risk Management
Modification Date:	2/12/2013

Contact Email:	steve.reisner@twcable.com
Contact Mail Address:	7820 Crescent Executive Drive
Contact City/State/Zip:	Charlotte, NC 28217
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Steve Reisner
Title:	Director of Risk Management
Modification Date:	2/12/2013

Chemical Inventory:

Facility Id:	FATR20128DEE610161AE
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	CVTR20128DEENY00ANTJ
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	12.52
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/8/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T

TX-13 - TIME WARNER CABLE - GUADALUPE HUBSITE (Continued) **S113683382**

Reactive Hazard: T
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2012
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20128DEESW00B25K
Chemical Inventory Record Id: CVTR20128DEENY00ANTJ
Amt Of Sub Stored Or Transported: Not reported
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Located in hub (40 CSB Batteries)
Last Modified: 3/8/2013

Notes: Not reported
Validation: Not reported

AW255 **AUSTIN SPORTCYCLES MOTORCYCLES** **EDR Hist Auto** **1013765320**
Target **4117 GUADALUPE ST** **N/A**
Property **TRAVIS (County), TX 78751**

Site 1 of 5 in cluster AW

Actual: EDR Hist Auto
621 ft.

Focus Map: Year: Name: Type:
8 1975 AUSTIN SPORTCYCLES MOTORCYCLES MOTORCYCLE DEALERS AND REPAIRERS

AW256 **STATE CLEANERS** **EDR Hist Cleaner** **1013778402**
Target **4115 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 2 of 5 in cluster AW

Actual: EDR Hist Cleaner
621 ft.

Focus Map: Year: Name: Type:
8 1953 STATE CLEANERS CLEANERS AND DYERS

AW257 Target Property — **PARAMOUNT CLEANERS**, **4109 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780549** / **N/A**

Site 3 of 5 in cluster AW

Actual: 620 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1935	PARAMOUNT CLEANERS	CLOTHES PRESSERS AND CLEANERS

AW258 Target Property — **MILES EDGAR P BARBER**, **4103 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783242** / **N/A**

Site 4 of 5 in cluster AW

Actual: 620 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1911	MILES EDGAR P BARBER	CLOTHES PRESSERS AND CLEANERS

AW259 Target Property — **AUSTIN MATTRESS**, **4101 GUADALUPE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013786620** / **N/A**

Site 5 of 5 in cluster AW

Actual: 619 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1940	AUSTIN MATTRESS	CARPET AND RUG CLEANERS

AX260 Target Property — **WALLIS CLEANERS**, **4023 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780812** / **N/A**

Site 1 of 2 in cluster AX

Actual: 618 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1953	EDWARDS CLNRS	CLEANERS AND DYERS
1958	EDWARDS CLEANERS	CLEANERS AND DYERS
1962	EDWARDS CLNS	CLEANERS AND DYERS
1965	WALLIS CLEANERS	CLEANERS AND DYERS
1970	IMPERIAL CLEANERS	CLEANERS AND DYERS
1980	A ONE CARPET CLEANER	CARPET AND RUG CLEANERS

AX261 Target Property — **HYDE PARK SHOE SHOP**, **4011 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013785609** / **N/A**

Site 2 of 2 in cluster AX

Actual: 616 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1929	HYDE PARK SHOE SHOP	CLOTHES CLEANERS AND PRESSERS
1935	HYDE PARK CLEANERS	CLOTHES PRESSERS AND CLEANERS
1940	HYDE PARK CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	EDWARDS CLEANERS	CLOTHES PRESSERS AND CLEANERS

---

262 Target Property — **MIDAS MUFFLER SHOP**, **4001 GUADALUPE ST**, **TRAVIS (County), TX 78751** — **EDR Hist Auto** — **1013769913** / **N/A**

EDR Hist Auto

Actual: 614 ft.

Focus Map: 8

Year:	Name:	Type:
1970	MIDAS MUFFLER SHOP	AUTOMOBILE GARAGES
1972	NORTH AUSTIN MUFFLERS INC	Automotive Repair Shops, NEC
1973	NORTH AUSTIN MUFFLERS INC	Automotive Repair Shops, NEC
1974	NORTH AUSTIN MUFFLERS INC	Automotive Repair Shops, NEC
1975	SOUTHWEST MUFFLER SHOPS INC	Automotive Repair Shops, NEC
1976	SOUTHWEST MUFFLER SHOPS INC	Automotive Repair Shops, NEC
1977	SOUTHWEST MUFFLER SHOPS INC	Automotive Repair Shops, NEC
1978	SOUTHWEST MUFFLER SHOPS INC	Automotive Repair Shops, NEC
1979	DAV-CAM INC	Automotive Repair Shops, NEC
1980	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1982	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1983	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1985	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1986	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1987	DAV-CAM CORPORATION	Automotive Repair Shops, NEC
1988	DAV-CAM CORPORATION	Automotive Repair Shops, NEC

AY263 Target Property — **SIGMOR CORPOR**, **3915 GUADALUPE ST**, **AUSTIN, TX 78751** — **EDR Hist Auto** — **1013776615** / **N/A**

Site 1 of 9 in cluster AY

Actual: 610 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1984	SIGMOR CORPOR	GASOLINE STATIONS
1986	DIAMOND SHAMROCK CORP	Gasoline Service Stations
1987	DIAMOND SHAMROCK REF MKTG *	Gasoline Service Stations
1988	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1989	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1990	SIGMOR REFINING GAS ST	GASOLINE STATIONS
1990	DIAMOND SHMRCK RFNG	Gasoline Service Stations, NEC
1991	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1992	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1993	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1994	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC

SIGMOR CORPOR (Continued) **1013776615**

1995	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1996	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1997	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC
1998	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations, NEC

AY264 **BAKER LEONARD CLNR** **EDR Hist Cleaner** **1013777234**
Target **3911 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 9 in cluster AY

Actual:
610 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1916	BAKER LEONARD CLNR	CLOTHES CLEANERS AND PRESSERS

AY265 **DIAMOND SHAMROCK 80** **FINDS** **1011343273**
Target **3909 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78751**

Site 3 of 9 in cluster AY

Actual:
610 ft.

FINDS:
Registry ID: 110034693794

Focus Map:
8

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AY266 **CIRCLE K STORE 2740080** **TX LPST** **U003566325**
Target **3909 GUADALUPE ST** **TX UST** **N/A**
Property **AUSTIN, TX 78751** **TX HIST UST**
TX ASBESTOS
Site 4 of 9 in cluster AY **TX Financial Assurance**

Actual:
610 ft.

LPST:

Focus Map:
8

Name:	DIAMOND SHAMROCK STATION 80
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0045186
LPST Id:	091720
Facility Location:	3909 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/23/1988
Entered Date:	02/23/1988

CIRCLE K STORE 2740080 (Continued) **U003566325**

Reported Date:	02/23/1988
Closure Date:	03/10/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/1P/1
Coordinators RPR:	KKC
Responsible Party Name:	Not reported
Responsible Party Contact:	MACK BRICE
Responsible Party Address:	PO 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/592-4663
Reported Date:	02/23/1988
Case Start Date:	03/10/1999
Reference Number:	RN102375953
Project Manager:	KKC

UST:

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787514522
AI Number:	45186
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	506847942002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/24/2017
Signature Name/Title On Earliest Reg Form:	JENNIFER RESNIK,COMP COORD
Application Received Date On Earliest Reg Form:	08/25/2017
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	658325792001221
Additional ID:	506847942002149

CIRCLE K STORE 2740080 (Continued) **U003566325**

Ai Number:	45186
Operator CN:	CN600134456
Operator Name:	CIRCLE K STORES INC
Operator Effective Begin Date:	08/16/2021
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PHOENIX AZ 85072-2085
Contact Phone Country Code:	0
Contact Phone Area Code:	602
Contact Phone Number:	7288000
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600134456
Owner Last Name:	CIRCLE K STORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	PHOENIX
Contact Mailing State:	AZ
Contact Mailing Zip:	85072
Contact Mailing Zip5:	2085
Contact Phone Number/Ext:	0 602 7288000/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	658325792001221
Additional ID:	506847942002149
AI Number:	45186
Owner Effective Begin Date:	08/16/2021
State Tax ID:	17411495405
Contact Role:	OWNOPRCON
Contact Name/Title:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC

Self Certification:

Self Cert ID:	74573
Cert ID:	379545
AI Number:	45186
Self Certification Date:	09/29/2022
Signature Name/Title:	KELLIE BODDIE ENVIRONMENTAL SPECIA
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	360468
AI Number:	45186
Self Certification Date:	09/21/2021
Signature Name/Title:	KELLIE BODDIE ENVIRONMENTAL SPECIALIST
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	342779
AI Number:	45186
Self Certification Date:	09/02/2020
Signature Name/Title:	Veronica Rivera OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	332730
AI Number:	45186
Self Certification Date:	02/03/2020
Signature Name/Title:	VERONICA RIVERA ENV SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	326892
AI Number:	45186
Self Certification Date:	09/19/2019
Signature Name/Title:	Annette S Toale Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	311345
AI Number:	45186
Self Certification Date:	10/01/2018
Signature Name/Title:	Annette S Toale MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	292381
AI Number:	45186
Self Certification Date:	08/24/2017
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	274930
AI Number:	45186
Self Certification Date:	08/22/2016
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	258401
AI Number:	45186
Self Certification Date:	08/26/2015
Signature Name/Title:	JENNIFER RESNIK COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	242320
AI Number:	45186
Self Certification Date:	08/29/2014
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	226090
AI Number:	45186
Self Certification Date:	08/22/2013
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74573
Cert ID:	104471
AI Number:	45186
Self Certification Date:	08/22/2012
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104470
AI Number:	45186
Self Certification Date:	08/24/2011
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104469
AI Number:	45186
Self Certification Date:	08/24/2010
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104468
AI Number:	45186
Self Certification Date:	07/28/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104467
AI Number:	45186
Self Certification Date:	07/27/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104466
AI Number:	45186
Self Certification Date:	08/29/2008
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104465
AI Number:	45186
Self Certification Date:	03/11/2008
Signature Name/Title:	TERRY HANKINS O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104464
AI Number:	45186
Self Certification Date:	08/28/2007
Signature Name/Title:	KENT HANEL COMPLIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104463
AI Number:	45186
Self Certification Date:	08/01/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104462
AI Number:	45186
Self Certification Date:	07/26/2005
Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104461
AI Number:	45186
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104460
AI Number:	45186
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104459
AI Number:	45186
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104458
AI Number:	45186
Self Certification Date:	02/15/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT

CIRCLE K STORE 2740080 (Continued) **U003566325**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74573
Cert ID:	104457
AI Number:	45186
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIST TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6064
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118286
Facility ID:	74573
Ai Number:	45186
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6064
UST Comprt ID:	103596
UST ID:	118286
AI Number:	45186
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

CIRCLE K STORE 2740080 (Continued) **U003566325**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634

CIRCLE K STORE 2740080 (Continued) **U003566325**

Cert ID:	121799
UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST Comprt ID:	352165
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802
UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

Install Date:	01/01/1971
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6064
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118287
Facility ID:	74573
Ai Number:	45186
Tank Id:	1

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6064
UST Comprt ID:	103597
UST ID:	118287
AI Number:	45186

CIRCLE K STORE 2740080 (Continued) **U003566325**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121799
UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769

CIRCLE K STORE 2740080 (Continued) **U003566325**

AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797
UST Comprt ID:	352165
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802
UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1

CIRCLE K STORE 2740080 (Continued) **U003566325**

Compartment ID:	A
Install Date:	01/01/1974
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118288
Facility ID:	74573
Ai Number:	45186
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	10088
UST Comprt ID:	103598
UST ID:	118288
AI Number:	45186
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769

CIRCLE K STORE 2740080 (Continued) **U003566325**

AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121799
UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797
UST Comprt ID:	352165
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1

CIRCLE K STORE 2740080 (Continued) **U003566325**

Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802
UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

CIRCLE K STORE 2740080 (Continued) **U003566325**

Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1971
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6064
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118289
Facility ID:	74573
Ai Number:	45186
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

CIRCLE K STORE 2740080 (Continued) **U003566325**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6064
UST Comprt ID:	103599
UST ID:	118289
AI Number:	45186
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

CIRCLE K STORE 2740080 (Continued) **U003566325**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121799
UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

CIRCLE K STORE 2740080 (Continued) **U003566325**

Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797
UST Comprt ID:	352165
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634

CIRCLE K STORE 2740080 (Continued) **U003566325**

Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Install Date:	11/27/2001
Tank Registration Date:	01/28/2002
Number of Compartments:	1
Tank Capacity:	15126
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199273
Facility ID:	74573
Ai Number:	45186
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/16/2002

Compartment Records:

Tank ID:	5
Tank Capacity:	15126
UST Comprt ID:	103600
UST ID:	199273
AI Number:	45186
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

CIRCLE K STORE 2740080 (Continued) **U003566325**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/27/2001

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121799

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797
UST Comprt ID:	352165

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341
UST ID:	116769

CIRCLE K STORE 2740080 (Continued) **U003566325**

AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802
UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Install Date:	11/27/2001
Tank Registration Date:	01/28/2002
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199274
Facility ID:	74573
Ai Number:	45186
Tank Id:	6
Tank Status (Current):	IN USE

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank Status Date:	11/27/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/16/2002

Compartment Records:

Tank ID:	6
Tank Capacity:	12098
UST Comprt ID:	103601
UST ID:	199274
AI Number:	45186
Compartment ID:	A

CIRCLE K STORE 2740080 (Continued) **U003566325**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/27/2001

More Self Certification:

Self Cert ID:	17634
Cert ID:	121800
UST Comprt ID:	352162
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17634
Cert ID:	357264
UST Comprt ID:	1039153
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17634
Cert ID:	121792
UST Comprt ID:	352170
UST ID:	116769

CIRCLE K STORE 2740080 (Continued) **U003566325**

AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	322008
UST Comprt ID:	932972
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121799
UST Comprt ID:	352163
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	305943
UST Comprt ID:	885213
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121789
UST Comprt ID:	352171
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121798
UST Comprt ID:	352164
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	287889
UST Comprt ID:	830930
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	272244
UST Comprt ID:	784693
UST ID:	116769
AI Number:	45186

CIRCLE K STORE 2740080 (Continued) **U003566325**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121796
UST Comprt ID:	352166
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121797
UST Comprt ID:	352165
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121791
UST Comprt ID:	352173
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121795
UST Comprt ID:	352167
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	255732
UST Comprt ID:	735699
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	373025
UST Comprt ID:	1086968
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121794
UST Comprt ID:	352168
UST ID:	116769
AI Number:	45186
Tank ID:	1

CIRCLE K STORE 2740080 (Continued) **U003566325**

Compartment ID:	A
Self Cert ID:	17634
Cert ID:	238765
UST Comprt ID:	685773
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	230037
UST Comprt ID:	660341
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121790
UST Comprt ID:	352172
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121802
UST Comprt ID:	352160
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121793
UST Comprt ID:	352169
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	121801
UST Comprt ID:	352161
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17634
Cert ID:	339572
UST Comprt ID:	986041
UST ID:	116769
AI Number:	45186
Tank ID:	1
Compartment ID:	A

CIRCLE K STORE 2740080 (Continued) **U003566325**

Construction Notification:

NOC ID:	11017
Facility ID:	74573
AI Number:	45186
Application Received Date:	09/26/2001
Scheduled Construction Date:	10/22/2001
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00926011
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	29838
UST ID:	199274
NOC ID:	Not reported
AI Number:	45186
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	29837

CIRCLE K STORE 2740080 (Continued) **U003566325**

UST ID:	199273
NOC ID:	Not reported
AI Number:	45186
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11836
UST ID:	Not reported
NOC ID:	11017
AI Number:	45186
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	45002
UST ID:	199274
NOC ID:	Not reported
AI Number:	45186
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	Not reported
Representative Name:	TONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

CIRCLE K STORE 2740080 (Continued) **U003566325**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	45001
UST ID:	199273
NOC ID:	Not reported
AI Number:	45186
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	Not reported
Representative Name:	TONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	3802 CORPOREX PARK DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TAMPA, FL 33619 1125
Phone Number/Ext:	984 3891316/0
Contact Fax Number/Ext:	/
Contact Email Address:	kboddie@circlek.com
Contact Address Deliverable:	Y
Facility ID:	74573
Additional ID:	506847942002149
Princ ID:	658325792001221
AI Number:	45186
Facility Name:	CIRCLE K STORE 2740080
AR Number:	82920
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	KELLIE BODDIE/ENVIRONMENTAL SPECIALIST

CIRCLE K STORE 2740080 (Continued) **U003566325**

HIST UST AUSTIN:

Name:	CORNER STORE NO. 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	376
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	VALERO
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	05/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/28/2013
Date Routed by Supervisor:	05/28/2013
Date Routed to PSQA:	06/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported

CIRCLE K STORE 2740080 (Continued) **U003566325**

Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	275358
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/11/2022
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 984 3891316
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/11/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	257469
AI:	45186

CIRCLE K STORE 2740080 (Continued) **U003566325**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/23/2020
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/27/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	220794
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/27/2019
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	1 602 7288000
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	227686
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/27/2019
Date Financial Assurance Form Rec:	08/25/2017

CIRCLE K STORE 2740080 (Continued) **U003566325**

Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/27/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	204446
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	NAVIGATORS INS CO
Issuer Phone:	Not reported
Policy Number:	CH18ESP0BDKN0NC
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	185470
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2017
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080

CIRCLE K STORE 2740080 (Continued) **U003566325**

Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	167277
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/15/2016
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	149019
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2015
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/09/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	133433
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

CIRCLE K STORE 2740080 (Continued) **U003566325**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/2014
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	115847
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2013
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 692275
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	7926
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2012
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3454670
Policy Number:	None

CIRCLE K STORE 2740080 (Continued) **U003566325**

Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	57653
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/25/2008
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	57654
AI:	45186
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/06/2007
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	09/06/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2

CIRCLE K STORE 2740080 (Continued) **U003566325**

Facility ID:	74573
Finass ID:	57655
AI:	45186
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	N
3rd Party MET Flag:	N
Financial Assurance Begin Date:	09/06/2007
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	09/06/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740080
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	74573
Finass ID:	57656
AI:	45186
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

AY267 **BALCAR HUMBLE SERV** **EDR Hist Auto** **1013765404**
Target **3909 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 5 of 9 in cluster AY

Actual: EDR Hist Auto
610 ft.

Focus Map:
8

Year:	Name:	Type:
1935	CAMP TEXAS FILLING	GASOLINE AND OIL SERVICE STATIONS
1940	CAMP TEXAS FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	CAMP TEXAS SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1953	BALCAR HUMBLE SERV	GASOLINE STATIONS
1962	REFINERY OUTLET NO	GASOLINE STATIONS

BALCAR HUMBLE SERV (Continued) **1013765404**

1965	SIGMOR SERV INC GL	GASOLINE STATIONS
1970	SIGMOR SERVICE INC NO 80 GAS ST	GASOLINE STATIONS
1975	SIGMOR SERVICE INC NO 80 GAS ST	GASOLINE STATIONS
1980	SIGMOR SHAMROCK SERVICE INC NO	GASOLINE STATIONS
1990	DIAMOND SHAMROCK NO 80 GAS STA	GASOLINE STATIONS
1994	DIAMOND SHAMROCK INC	Convenience Stores
2001	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2002	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2003	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2004	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2005	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2012	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2013	SIGMOR NUMBER 80 INC	Gasoline Service Stations
2014	SIGMOR NUMBER 80 INC	Gasoline Service Stations

AY268 **DIAMOND SHAMROCK 80** **TX RDR** **S127533589**
Target **3909 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 6 of 9 in cluster AY

Actual:
610 ft.

Focus Map:
8

RDR:

RDR ID:	6425
Facility ID:	45186
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 80
Address:	3909 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/21/2003
Due Date:	5/20/2003
Tank Owner:	DIAMOND SHAMROCK REF & MK
Contact Person:	MACK BRICE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/25/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	91720
Comments:	6A, RDR ORIG RECD 3/8/02
Review Coordinator:	PPC/SRJ
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/25/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AY269 Target Property | **CORNER STORE 0080**
3909 GUADALUPE ST
AUSTIN, TX 78751 | **TX CENTRAL REGISTRY** | **S126576504**
N/A

Site 7 of 9 in cluster AY

Actual: 610 ft.

Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN603485079
Customer Name:	SIGMOR NUMBER 80 INC
Customer Legal Name:	Sigmor Number 80, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/31/2008
Affiliation End Date:	11/10/2019
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1987
Affiliation End Date:	3/9/2008 1
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601426042
Customer Name:	SIGMOR COMPANY LLC
Customer Legal Name:	Sigmor Company, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/10/2008
Affiliation End Date:	7/31/2009
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

CORNER STORE 0080 (Continued) **S126576504**

Physical Location Description: Not reported

Regulated Entity Number: RN102375953
Name: CORNER STORE 0080
Address: 3909 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4522
Status: ACTIVE
Status Date: 5/29/2002
Customer Number: CN602400699
Customer Name: DIAMOND SHAMROCK REFINING CORPORATION
Customer Legal Name: Diamond Shamrock Refining Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN102375953
Name: CORNER STORE 0080
Address: 3909 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4522
Status: ACTIVE
Status Date: 5/29/2002
Customer Number: CN603503665
Customer Name: SIGMOR BEVERAGE INC
Customer Legal Name: Sigmor Beverage, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 11/11/2019
Affiliation End Date: 8/15/2021
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN102375953
Name: CORNER STORE 0080
Address: 3909 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78751-4522
Status: ACTIVE
Status Date: 5/29/2002
Customer Number: CN600134456
Customer Name: CIRCLE K STORES INC
Customer Legal Name: Circle K Stores Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/16/2021
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN102375953

CORNER STORE 0080 (Continued) **S126576504**

Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN603485079
Customer Name:	SIGMOR NUMBER 80 INC
Customer Legal Name:	Sigmor Number 80, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/31/2008
Affiliation End Date:	11/10/2019
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1987
Affiliation End Date:	3/9/2008 1
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601426042
Customer Name:	SIGMOR COMPANY LLC
Customer Legal Name:	Sigmor Company, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/10/2008
Affiliation End Date:	7/31/2009
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported

CORNER STORE 0080 (Continued) **S126576504**

City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602400699
Customer Name:	DIAMOND SHAMROCK REFINING CORPORATION
Customer Legal Name:	Diamond Shamrock Refining Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102375953
Name:	CORNER STORE 0080
Address:	3909 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-4522
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN603503665
Customer Name:	SIGMOR BEVERAGE INC
Customer Legal Name:	Sigmor Beverage, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/11/2019
Affiliation End Date:	8/15/2021
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

AY270 **NUNNELEE HARRY R** **EDR Hist Auto** **1013761191**
Target **3907 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 8 of 9 in cluster AY

Actual:
609 ft. EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1922	NUNNELEE HARRY R	AUTOMOBILE GARAGES

AY271 **AUSTIN MATTRESS & CARPET** **EDR Hist Cleaner** **1013783970**
Target **3907 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 9 of 9 in cluster AY

Actual:
609 ft. EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1929	AUSTIN MATTRESS & CARPET	RUG CLEANERS

AUSTIN MATTRESS & CARPET (Continued) **1013783970**

1929 AUSTIN MATTRESS & CARPET CARPET CLEANERS

---

272 Target Property | **FORMER NATURAL GROCERS**
3901 GUADALUPE STREET
AUSTIN, TX 78751

TX ASBESTOS **S126247509**
N/A

Actual: 607 ft.

Focus Map: 8

ASBESTOS:

Name:	FORMER NATURAL GROCERS
Address:	3901 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/03
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/03/2020
Client Code:	1500

FORMER NATURAL GROCERS (Continued) **S126247509**

Client Name:	Environmental Notification
License Number:	Not reported
File Number:	49344
License Status Description:	Current
Expiration Date:	01/14/2025
Original Date:	01/15/2020
Rank Effective Date:	01/15/2020
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20052
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported

---

273 **UNIVERSITY CAR WASH** **EDR Hist Auto** **1020373555**
Target **3825 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78751**

EDR Hist Auto

Actual:
600 ft.

Year:	Name:	Type:
2014	TEXACO EXPRESS LUBE	Gasoline Service Stations, NEC

Focus Map:
8

AZ274 **C & H REPAIR SERVICE** **EDR Hist Auto** **1013774854**
Target **3907 AVENUE C** **N/A**
Property **AUSTIN, TX 78751**

Site 1 of 2 in cluster AZ

Actual:
614 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1965	C & H REPAIR SERVICE	REPAIR SHOPS
1970	C & H REPAIR SERVICE	REPAIR SHOPS
1975	C & H REPAIR SERVICE	REPAIR SHOPS
1980	C & H REPAIR SERVICE	REPAIR SHOPS

BA275 Target Property | **AVENEL AT HYDE PARK CONDOMINUIMS**
3815 GUADALUPE ST. #202
AUSTIN, TX 78751 | **TX ASBESTOS** | **S129327902**
N/A

Site 1 of 7 in cluster BA

Actual: 599 ft.

Focus Map: 8

ASBESTOS:

Name:	AVENEL AT HYDE PARK CONDOMINUIMS
Address:	3815 GUADALUPE ST. #202
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	08/22/2016
Notification Number:	2016006789
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/22/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/22/2016
Client Code:	Not reported
Client Name:	Not reported

AVENEL AT HYDE PARK CONDOMINUIMS (Continued) **S129327902**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AVENEL AT HYDE PARK CONDOMINUIMS
Address:	3815 GUADALUPE ST. #202
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	08/23/2016
Notification Number:	2016006789
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/08/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/08/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N

AVENEL AT HYDE PARK CONDOMINUIMS (Continued) **S129327902**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/22/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AZ276 **C&H REPR SERV** **EDR Hist Auto** **1013768789**
Target **3907 AVENUE C** **N/A**
Property **HYDE PARK, TX**

Site 2 of 2 in cluster AZ

Actual: **613 ft.** EDR Hist Auto

Focus Map: **8**

Year:	Name:	Type:
1962	C&H REPR SERV	REPAIR SHOPS

BA277 **HYDE PARK GULF** **EDR Hist Auto** **1013754380**
Target **3801 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 7 in cluster BA

Actual: **600 ft.** EDR Hist Auto

Focus Map: **8**

Year:	Name:	Type:
1958	HYDE PARK GULF	GASOLINE STATIONS
1962	HYDE PARK GULF	GASOLINE STATIONS
1965	SLAUSON GULF SERVICE	GASOLINE STATIONS
1969	SLAUSONS GULF SERVICE	Gasoline Service Stations
1970	TEXS GULF SERVICE STATION	GASOLINE STATIONS

HYDE PARK GULF (Continued) **1013754380**

1970	SLAUSONS GULF SERVICE	Gasoline Service Stations
1975	JUNGS GULF SERVICE STATION	GASOLINE STATIONS

BB278 **JAMES E P FILL STA** **EDR Hist Auto** **1013769753**
Target **3710 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 13 in cluster BB

Actual: EDR Hist Auto
599 ft.

Focus Map:
8

Year:	Name:	Type:
1929	JAMES E P FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	JAMES E P FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	JAMES EDW P FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1947	HELGE PAUL E SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

BB279 **CIRCLE K CORPORATION** **EDR Hist Auto** **1020968889**
Target **3713 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 2 of 13 in cluster BB

Actual: EDR Hist Auto
600 ft.

Focus Map:
8

Year:	Name:	Type:
1993	CIRCLE K CORPORATION	Convenience Stores
1994	CIRCLE K CORPORATION	Convenience Stores
1995	CIRCLE K CORPORATION	Convenience Stores

BB280 **CIRCLE K 3208** **FINDS** **1024182614**
Target **3713 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 13 in cluster BB

Actual: FINDS:
600 ft. Registry ID: 110070167224

Focus Map:
8 Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BB281 Target Property | **GOOD LUCK FOOD MART**
3713 GUADALUPE ST
AUSTIN, TX 78705 | **TX ASBESTOS** | **S119146979**
N/A

Site 4 of 13 in cluster BB

Actual: 600 ft.

Focus Map: 8

ASBESTOS:

Name:	GOOD LUCK FOOD MART
Address:	3713 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/03/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

GOOD LUCK FOOD MART (Continued) **S119146979**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	GOOD LUCK FOOD MART
Address:	3713 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	06/03/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	07
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

GOOD LUCK FOOD MART (Continued) **S119146979**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BB282 **CIRCLE K 3208** **TX CENTRAL REGISTRY** **S126558187**
Target **3713 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 5 of 13 in cluster BB

Actual:
600 ft.

Focus Map:
8

CENTRAL REGISTRY:

Regulated Entity Number:	RN102035326
Name:	CIRCLE K 3208
Address:	3713 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1325
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600134456
Customer Name:	CIRCLE K STORES INC
Customer Legal Name:	Circle K Stores Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/22/1986
Affiliation End Date:	10/9/1996
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

BB283 Target Property | **CIRCLE K 3208**
3713 GUADALUPE ST
AUSTIN, TX 78705 | **TX UST** | **U001269404**
TX HIST UST | **N/A**

Site 6 of 13 in cluster BB

Actual: 600 ft.

Focus Map: 8

UST:

Name:	CIRCLE K 3208
Address:	3713 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787051325
AI Number:	36537
Facility Type:	RETAIL
Facility Begin Date:	12/22/1986
Facility Status:	INACTIVE
Additional ID:	619600972002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	KEN YOUNGER,
Contact Organization Name:	CIRCLE K 3208
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123398836
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	D ESPERSON,GAS. FACIL MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600134456
Owner Last Name:	CIRCLE K STORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	658325792001221
Additional ID:	619600972002117

CIRCLE K 3208 (Continued) **U001269404**

AI Number:	36537
Owner Effective Begin Date:	05/08/1986
State Tax ID:	17411495405
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	04/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96616
Facility ID:	44043
Ai Number:	36537
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/17/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

CIRCLE K 3208 (Continued) **U001269404**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	17991
UST ID:	96616
AI Number:	36537
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

CIRCLE K 3208 (Continued) **U001269404**

Install Date:	04/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96617
Facility ID:	44043
Ai Number:	36537
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/17/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CIRCLE K 3208 (Continued) **U001269404**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	17992
UST ID:	96617
AI Number:	36537
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PHOENIX, AZ 85072 2085
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

CIRCLE K 3208 (Continued) **U001269404**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	44043
Additional ID:	619600972002117
Princ ID:	658325792001221
AI Number:	36537
Facility Name:	CIRCLE K 3208
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BERLIN ANDERSON/

HIST UST AUSTIN:

Name:	CIRCLE K #3208
Address:	3713 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0599
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

BB284 **MAC'S PIZZA** **TX ASBESTOS** **S129332280**
Target **3701 GUADALUPE** **N/A**
Property **AUSTIN, TX 78705**

Site 7 of 13 in cluster BB

Actual:
596 ft.

Focus Map:
8

ASBESTOS:

Name:	MAC'S PIZZA
Address:	3701 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/05/2016
Reason for Inspection:	Rudy J Orta
Violation:	Not reported
Complaint Date:	02/07/2016
Notification Number:	2016000835
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

MAC'S PIZZA (Continued) **S129332280**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/06/2016
Certification Statement Phone:	409-527-0462
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	02/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MAC'S PIZZA
Address:	3701 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/05/2016
Reason for Inspection:	Rudy J Orta
Violation:	Not reported
Complaint Date:	02/06/2016
Notification Number:	2016000835
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

MAC'S PIZZA (Continued) **S129332280**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/21/2016
Certification Statement Phone:	409-962-1647
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	02/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BB285 Target Property | **VACANT LEASE SPACE**
3701 GUADALUPE
AUSTIN, TX 78705 | **TX ASBESTOS** | **S122367524**
N/A

Site 8 of 13 in cluster BB

Actual: 596 ft.

Focus Map: 8

ASBESTOS:

Name:	VACANT LEASE SPACE
Address:	3701 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/10/2018
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	05/10/2018
Notification Number:	2018003425
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/26/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/26/2018
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/10/2018
Client Code:	Not reported
Client Name:	Not reported

VACANT LEASE SPACE (Continued) **S122367524**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT LEASE SPACE
Address:	3701 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/05/10
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

VACANT LEASE SPACE (Continued) **S122367524**

Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/10/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018003425
File Number:	30513
License Status Description:	Paid
Expiration Date:	05/10/2018
Original Date:	04/26/2018
Rank Effective Date:	04/26/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	10453
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

BB286 **WILDSIDE SMOKE SHOP** **TX ASBESTOS** **S119161546**
Target **3701 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 9 of 13 in cluster BB

Actual:
596 ft.

Focus Map:
8

ASBESTOS:

Name:	WILDSIDE SMOKE SHOP
Address:	3701 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/11/2015
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson

WILDSIDE SMOKE SHOP (Continued) **S119161546**

Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

287 Target Property | **AUSTIN DIAGNOSTIC CLINIC THE**
801 34TH ST W
TRAVIS (County), TX 78705 | **EDR Hist Cleaner** | **1013781267**
N/A

EDR Hist Cleaner

Actual: 611 ft.
Focus Map: 8

Year:	Name:	Type:
1990	AUSTIN DIAGNOSTIC CLINIC THE	CLEANERS-CARPET

BC288 Target Property | **INTEGRATED BUILDERS BUCKINGHAM SQUARE APARTMENTS**
711 N 32ND ST
AUSTIN, TX 78705 | **FINDS** | **1010755532**
N/A

Site 1 of 2 in cluster BC

Actual: 606 ft.
Focus Map: 8

FINDS:
Registry ID: 110033933064

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BC289 Target Property | **BUCKINGHAM INVESTMENTS BUCKINGHAM SQUARE APARTMENT**
711 W 32ND ST
AUSTIN, TX 78705 | **TX CENTRAL REGISTRY** | **S126758863**
N/A

Site 2 of 2 in cluster BC

Actual: 606 ft.
Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN105149678
Name:	BUCKINGHAM INVESTMENTS BUCKINGHAM SQUARE APARTMENTS
Address:	711 W 32ND ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2201
Status:	ACTIVE
Status Date:	2007-01-25
Customer Number:	CN603143603
Customer Name:	BUCKINGHAM INVESTMENTS LIMITED
Customer Legal Name:	Buckingham Investments Limited
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2006-08-14
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction

BUCKINGHAM INVESTMENTS BUCKINGHAM SQUARE APARTMENTS (Continued) **S126758863**

Physical Location Description: Not reported

Regulated Entity Number: RN105149678
Name: BUCKINGHAM INVESTMENTS BUCKINGHAM SQUARE APARTMENTS
Address: 711 W 32ND ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-2201
Status: ACTIVE
Status Date: 2007-01-25
Customer Number: CN603143603
Customer Name: BUCKINGHAM INVESTMENTS LIMITED
Customer Legal Name: Buckingham Investments Limited
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2006-08-14
Affiliation End Date: 3000-12-31
Customer Status: UNVALD
Primary NAICS Industry Type Code: 236220
Primary NAICS Industry Type Description: Commercial and Institutional Building Construction
Physical Location Description: Not reported

BD290 **KWIK WASH COIN LAUNDRIES NO** **EDR Hist Cleaner** **1013779408**
Target **3105 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 5 in cluster BD

Actual: 592 ft.
Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1975	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1984	KWIK WAAB COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

BE291 **CAPITAL CITY PARTNERS PROPERTY** **TX GCC** **S106871022**
Target **3004- 3010 GUADALUPE STREET** **TX IOP** **N/A**
Property **AUSTIN, TX**

Site 1 of 13 in cluster BE

Actual: 588 ft.
Focus Map: 8

GCC:
Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported

CAPITAL CITY PARTNERS PROPERTY (Continued) **S106871022**

Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 2B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 0 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION

CAPITAL CITY PARTNERS PROPERTY (Continued) **S106871022**

ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 2B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1B -

CAPITAL CITY PARTNERS PROPERTY (Continued) **S106871022**

Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CAPITAL CITY PARTNERS PROPERTY
Address: 3004- 3010 GUADALUPE STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 481
Contamination Description: VOCS
Date Of Earliest Known Contamination Confirmation: 3/3/2005
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

IOP:
Name: CAPITAL CITY PARTNERS PROPERTY
Address: Not reported
City,State,Zip: AUSTIN, TX
Program ID: 481
Date IOP Received: Not reported
Region: REGION 11 - AUSTIN
Phase: WITHDRAWN

CAPITAL CITY PARTNERS PROPERTY (Continued) **S106871022**

Interest In Site:	Not reported
PCA Number:	32481
Property Use:	PROPERTY VACANT
Project Manager:	HPODLIPN
Project Number:	324810
Latitude:	30.30
Longitude:	-97.74
Acres:	1
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	Not reported
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN104558903
Consultant/Attorney Phone:	Not reported
Site Address Description:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	03/03/2005
Application Received Date:	03/03/2005
Application Acceptance Date:	Not reported
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	D/200-37; D/200-44

Customer:

REM Program:	IOP
Program ID:	481
RN Number:	RN104558903
CN Number:	CN604860924
CN Name:	SAGE-3006 GUADALUPE LTD
Role CD:	APPLCONT
Contact Name:	MOORE, GRAHAM
Contact Title:	ASSISTANT PROPERTY MANAGER
Organization Name:	Not reported
Mailing Address:	1717 W 6TH ST STE 380

CAPITAL CITY PARTNERS PROPERTY (Continued) **S106871022**

Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78703
Contact Phone:	(512) 472-1585
Contact Ext:	0

BE292 **TEXACO STATION** **RCRA-VSQG** **1004783944**
Target **3016 GUADALUPE ST** **FINDS** **TX0000994756**
Property **AUSTIN, TX 78705** **ECHO**

Site 2 of 13 in cluster BE

Actual:
589 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	19941227
Handler Name:	Texaco Station
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TX0000994756
Contact Name:	DARVIN E MAYO
Contact Address:	333 RESEARCH COURT
Contact City,State,Zip:	NORCROSS, GA 30092
Contact Telephone:	404-453-5442
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	RESEARCH COURT
Mailing City,State,Zip:	NORCROSS, GA 30092
Owner Name:	Star Enterprise
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

TEXACO STATION (Continued) **1004783944**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STAR ENTERPRISE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	333 RESEARCH COURT
Owner/Operator City,State,Zip:	NORCROSS, GA 30092
Owner/Operator Telephone:	404-453-5400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19941227
Handler Name: TEXACO STATION	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

TEXACO STATION (Continued) **1004783944**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005023465

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004783944
Registry ID: 110005023465
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005023465
Name: TEXACO STATION
Address: 3016 GUADALUPE ST
City,State,Zip: AUSTIN, TX 78705

BE293 **SAGE-OCONNER ASSOCIATES GUADALUPE TRACT** **FINDS** **1011400197**
Target **3016 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 13 in cluster BE

Actual:
589 ft.

Focus Map:
8

FINDS:
Registry ID: 110035368447

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

SAGE-OCONNER ASSOCIATES GUADALUPE TRACT (Continued) **1011400197**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BE294 **ASHFORDS GARAGE** **EDR Hist Auto** **1013763786**
Target **3016 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 13 in cluster BE

Actual: EDR Hist Auto
589 ft.

Focus Map:
8

Year:	Name:	Type:
1929	ASHFORDS GARAGE	AUTOMOBILE GARAGES
1935	ASHFORDS GARAGE	AUTOMOBILE REPAIRERS
1940	WALBERG SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1947	JONES FRED	AUTOMOBILE REPAIRING
1953	ZIMMERMANN CHARLIE FILLING STA	GASOLINE STATIONS
1958	ZIMMERMAN	GASOLINE STATIONS
1962	ZIMMERMANN CHARLIE	GASOLINE STATIONS
1965	ZIMMERMANN CHARLIE	GASOLINE STATIONS
1969	ZIMMERMAN CHARLIE F	Gasoline Service Stations
1970	ZIMMERMANN C RLIE SERVICE STATI	GASOLINE STATIONS
1970	ZIMMERMAN CHARLIE F	Gasoline Service Stations
1971	ZIMMERMAN CHARLIE F	Gasoline Service Stations
1972	ZIMMERMAN CHARLIE F	Gasoline Service Stations
1973	ZIMMERMAN CHARLES F	Gasoline Service Stations
1974	ZIMMERMAN CHARLES F	Gasoline Service Stations
1975	ZIMMERMANN CHARLIE TEXACO SERVI	GASOLINE STATIONS
1975	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1976	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1977	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1978	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1979	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1980	ZIMMERMANN CHARLIE TEXACO SERVI	GASOLINE STATIONS
1980	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1982	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1983	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1984	ZIMMERMANN CHARLIE TEXACO SERVI	GASOLINE STATIONS
1985	ZIMMERMAN C F TEXACO	Gasoline Service Stations
1990	UNIVERSITY AUTOMOTIVE TEXACO CN	GASOLINE STATIONS
1991	UNIVERSITY AUTOMTV TEXACO CTR	Gasoline Service Stations
1992	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1993	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1994	UNIVERSITY TEXACO	Gasoline Service Stations, NEC
1994	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1995	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1996	UNIVERSITY TEXACO	Gasoline Service Stations, NEC
1996	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1997	UNIVERSITY AUTO TEXACO CTR	Gasoline Service Stations
1997	UNIVERSITY TEXACO	Gasoline Service Stations, NEC
1998	UNIVERSITY AUTOMOTIVE SVCS CTR	Gasoline Service Stations
1999	UNIVERSITY AUTOMOTIVE SVCS CTR	Gasoline Service Stations
2000	UNIVERSITY AUTOMOTIVE SVCS CTR	General Automotive Repair Shops
2001	UNIVERSITY AUTOMOTIVE SVCS CTR	General Automotive Repair Shops
2001	UNIVERSITY TEXACO	Gasoline Service Stations, NEC
2002	UNIVERSITY TEXACO	Gasoline Service Stations, NEC
2002	UNIVERSITY AUTOMOTIVE SVCS CTR	General Automotive Repair Shops
2003	ATC TRADING CO	Gasoline Service Stations, NEC

ASHFORDS GARAGE (Continued) **1013763786**

2003	UNIVERSITY AUTOMOTIVE SVCS CTR	General Automotive Repair Shops
2004	UNIVERSITY AUTOMOTIVE SVCS CTR	General Automotive Repair Shops
2004	ATC TRADING CO	Gasoline Service Stations, NEC
2005	ATC TRADING CO	Gasoline Service Stations, NEC

BE295 **UNIVERSITY TEXACO** **TX LPST** **U001240379**
Target **3016 GUADALUPE ST** **TX UST** **N/A**
Property **AUSTIN, TX 78705** **TX HIST UST**

Site 5 of 13 in cluster BE

Actual: 589 ft.

Focus Map: 8

LPST:

Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0003517
LPST Id:	116474
Facility Location:	3016 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/19/1995
Entered Date:	05/10/2005
Reported Date:	05/19/1995
Closure Date:	06/29/2005
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	DB2
Responsible Party Name:	Not reported
Responsible Party Contact:	THELMA YEATES
Responsible Party Address:	3304 GREENLEE DR
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/346-0908
Reported Date:	05/19/1995
Case Start Date:	06/29/2005
Reference Number:	RN102430089
Project Manager:	DBRATBER

UST:

Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787052862
AI Number:	3517
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	518694212002152
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS

UNIVERSITY TEXACO (Continued) **U001240379**

Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	ED VERA,PRES
Contact Organization Name:	UNIVERSITY TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124525516
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/07/1986
Signature Name/Title On Earliest Reg Form:	ED VERA,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601255334
Owner Last Name:	UNIVERSITY TEXACO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	509694202002152
Additional ID:	518694212002152
AI Number:	3517
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1950
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	8674
Facility ID:	95508
Ai Number:	3517
Tank Id:	1

UNIVERSITY TEXACO (Continued) **U001240379**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/16/1995
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	161435
UST ID:	8674
AI Number:	3517

UNIVERSITY TEXACO (Continued) **U001240379**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	1398
Cert ID:	132597
UST Comprt ID:	366085
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132596
UST Comprt ID:	366084
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132595
UST Comprt ID:	366083

UNIVERSITY TEXACO (Continued) **U001240379**

UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1950
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	8675
Facility ID:	95508
Ai Number:	3517
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/16/1995
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

UNIVERSITY TEXACO (Continued) **U001240379**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	161436
UST ID:	8675
AI Number:	3517
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	1398

UNIVERSITY TEXACO (Continued) **U001240379**

Cert ID:	132597
UST Comprt ID:	366085
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132596
UST Comprt ID:	366084
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132595
UST Comprt ID:	366083
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1950
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	8676
Facility ID:	95508
Ai Number:	3517
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/16/1995
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

UNIVERSITY TEXACO (Continued) **U001240379**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	161437
UST ID:	8676
AI Number:	3517
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

UNIVERSITY TEXACO (Continued) **U001240379**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	1398
Cert ID:	132597
UST Comprt ID:	366085
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132596
UST Comprt ID:	366084
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132595
UST Comprt ID:	366083
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	8677
Facility ID:	95508
Ai Number:	3517
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/16/1995
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported

UNIVERSITY TEXACO (Continued) **U001240379**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	161438
UST ID:	8677
AI Number:	3517
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

UNIVERSITY TEXACO (Continued) **U001240379**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	1398
Cert ID:	132597
UST Comprt ID:	366085
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132596
UST Comprt ID:	366084
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A
Self Cert ID:	1398
Cert ID:	132595
UST Comprt ID:	366083
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A

UNIVERSITY TEXACO (Continued) **U001240379**

Install Date:	08/31/1987
Tank Registration Date:	08/19/1995
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	176262
Facility ID:	95508
Ai Number:	3517
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/15/1995
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

UNIVERSITY TEXACO (Continued) **U001240379**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	0
UST Comprt ID:	161439
UST ID:	176262
AI Number:	3517
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	1398
Cert ID:	132597
UST Comprt ID:	366085
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A

UNIVERSITY TEXACO (Continued) **U001240379**

Self Cert ID:	1398
Cert ID:	132596
UST Comprt ID:	366084
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A

Self Cert ID:	1398
Cert ID:	132595
UST Comprt ID:	366083
UST ID:	124454
AI Number:	3517
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	UNIVERSITY TEXACO
Contact Mailing Address (Delivery):	3016 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78705 2862
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95508
Additional ID:	518694212002152
Princ ID:	509694202002152
AI Number:	3517
Facility Name:	UNIVERSITY TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0571
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

BE296 Target Property | **UNIVERSITY TEXACO**
3016 GUADALUPE
AUSTIN, TX | **TX RDR** | **S127531004**
N/A

Site 6 of 13 in cluster BE

Actual: 589 ft.
Focus Map: 8

RDR:

RDR ID:	14287
Facility ID:	3517
RN:	Not reported
CN:	Not reported
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/3/2005
Due Date:	5/2/2005
Tank Owner:	THELMA YEATES
Contact Person:	THELMA YEATES
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	5/10/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	116474
Pre-Existing LPST Number:	Not reported
Comments:	PLUS RBA & PROPOSAL; DOES THIS NEED A LPST#?;LAD SENT 5/20/05
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

BE297 Target Property | **UNIVERSITY TEXACO**
3016 GUADALUPE ST
AUSTIN, TX 78705 | **TX CENTRAL REGISTRY** | **S126580147**
N/A

Site 7 of 13 in cluster BE

Actual: 589 ft.
Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN602918245
Customer Name:	SAGE-OCONNOR ASSOCIATES LTD
Customer Legal Name:	SAGE - O'CONNOR ASSOCIATES, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2005-05-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

UNIVERSITY TEXACO (Continued) **S126580147**

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN602918245
Customer Name:	SAGE-OCONNOR ASSOCIATES LTD
Customer Legal Name:	SAGE - O'CONNOR ASSOCIATES, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2005-05-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN601255334
Customer Name:	UNIVERSITY TEXACO
Customer Legal Name:	University Texaco
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1988-09-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN601255334
Customer Name:	UNIVERSITY TEXACO
Customer Legal Name:	University Texaco
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1988-09-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST

UNIVERSITY TEXACO (Continued) **S126580147**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN604467373
Customer Name:	YEATES, THELMA
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	2002-06-01
Customer Number:	CN604467373
Customer Name:	YEATES, THELMA
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN602918245
Customer Name:	SAGE-OCONNOR ASSOCIATES LTD
Customer Legal Name:	SAGE - O'CONNOR ASSOCIATES, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	5/17/2005
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE

UNIVERSITY TEXACO (Continued) **S126580147**

Status Date:	6/1/2002
Customer Number:	CN601255334
Customer Name:	UNIVERSITY TEXACO
Customer Legal Name:	University Texaco
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN604467373
Customer Name:	YEATES, THELMA
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN602918245
Customer Name:	SAGE-OCONNOR ASSOCIATES LTD
Customer Legal Name:	SAGE - O'CONNOR ASSOCIATES, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	5/17/2005
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102430089
Name:	UNIVERSITY TEXACO
Address:	3016 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2862
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN601255334
Customer Name:	UNIVERSITY TEXACO

UNIVERSITY TEXACO (Continued) **S126580147**

Customer Legal Name:	University Texaco
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

BE298 **OCONNELL & WORLEY** **EDR Hist Cleaner** **1013787207**
Target **3012 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 8 of 13 in cluster BE

Actual:
589 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1958	OCONNELL & WORLEY	CARPET AND RUG CLEANERS

BE299 **NORTH AUSTIN GARAGE** **EDR Hist Auto** **1013761107**
Target **3008 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 9 of 13 in cluster BE

Actual:
590 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1929	NORTH AUSTIN GARAGE	AUTOMOBILE GARAGES

BE300 **RETAIL CENTER 3004-3010 GUADALUPE STREET** **FINDS** **1011314829**
Target **3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849** **N/A**
Property **AUSTIN, TX 78701**

Site 10 of 13 in cluster BE

Actual:
590 ft.
FINDS:
Registry ID: 110034452116

Focus Map:
8
Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

RETAIL CENTER 3004-3010 GUADALUPE STREET (Continued) **1011314829**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BE301 Target Property **RETAIL CENTER 3004-3010 GUADALUPE STREET**
3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
AUSTIN, TX 78701

TX CENTRAL REGISTRY **S126717560**
N/A

Site 11 of 13 in cluster BE

Actual: 590 ft.

Focus Map: 8

CENTRAL REGISTRY:

Regulated Entity Number:	RN104558903
Name:	RETAIL CENTER 3004-3010 GUADALUPE STREET
Address:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	3/16/2005
Customer Number:	CN602805061
Customer Name:	CAPITAL CITY PARTNERS INC
Customer Legal Name:	Capital City Partners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/8/2005
Affiliation End Date:	5/31/2015
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849

Regulated Entity Number:	RN104558903
Name:	RETAIL CENTER 3004-3010 GUADALUPE STREET
Address:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	3/16/2005
Customer Number:	CN602805061
Customer Name:	CAPITAL CITY PARTNERS INC
Customer Legal Name:	Capital City Partners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/8/2005
Affiliation End Date:	5/31/2015
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849

Regulated Entity Number:	RN104558903
Name:	RETAIL CENTER 3004-3010 GUADALUPE STREET
Address:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	3/16/2005
Customer Number:	CN604860924
Customer Name:	SAGE-3006 GUADALUPE LTD
Customer Legal Name:	Sage-3006 Guadalupe, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	6/1/2015

RETAIL CENTER 3004-3010 GUADALUPE STREET (Continued) **S126717560**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849

Regulated Entity Number:	RN104558903
Name:	RETAIL CENTER 3004-3010 GUADALUPE STREET
Address:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	3/16/2005
Customer Number:	CN604860924
Customer Name:	SAGE-3006 GUADALUPE LTD
Customer Legal Name:	Sage-3006 Guadalupe, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	6/1/2015
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3004-3010 GUADALUPE STREET AUSTIN, TX 78705-2849

BF302 **MARY E KOSH** **TX CENTRAL REGISTRY** **S126666990**
Target **3009 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 10 in cluster BF

Actual:
590 ft.

Focus Map:
8

CENTRAL REGISTRY:

Regulated Entity Number:	RN103768123
Name:	MARY E KOSH
Address:	3009 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2817
Status:	ACTIVE
Status Date:	7/23/2003
Customer Number:	CN602286452
Customer Name:	KOSH, MARY E
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	10/25/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

BF303 Target Property | **MARY E KOSH**
3009 GUADALUPE ST
AUSTIN, TX 78705 | **TX UST** | **U003566371**
N/A

Site 2 of 10 in cluster BF

Actual: 590 ft.

Focus Map: 8

UST:

Name:	MARY E KOSH
Address:	3009 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787052817
AI Number:	56470
Facility Type:	Not reported
Facility Begin Date:	10/25/1990
Facility Status:	INACTIVE
Additional ID:	485754352003204
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	JULIAN M KOSH,MANAGER
Contact Organization Name:	MARY E KOSH
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122514241
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/19/1990
Signature Name/Title On Earliest Reg Form:	MARY E KOSH,MANAGER
Application Received Date On Earliest Reg Form:	10/23/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602286452
Owner Last Name:	KOSH
Owner First Name:	MARY
Owner Middle Name:	E
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	463754342003204
Additional ID:	485754352003204

MARY E KOSH (Continued) **U003566371**

AI Number:	56470
Owner Effective Begin Date:	10/25/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/23/1990
Number of Compartments:	1
Tank Capacity:	880
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	136409
Facility ID:	86332
Ai Number:	56470
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

MARY E KOSH (Continued) **U003566371**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/19/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	880
UST Comprt ID:	136588
UST ID:	136409
AI Number:	56470
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

MARY E KOSH (Continued) **U003566371**

Facility Billing Contacts:

Contact Organization Name:	KOSH MARY E
Contact Mailing Address (Delivery):	2201 ROWE LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PFLUGERVILLE, TX 78660 7602
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	86332
Additional ID:	485754352003204
Princ ID:	463754342003204
AI Number:	56470
Facility Name:	MARY E KOSH
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JULIAN M KOSH/

BF304 **HOBBY TRACT** **FINDS** **1010776307**
Target **3000 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 10 in cluster BF

Actual:
592 ft.

Focus Map:
8

FINDS:
Registry ID: 110033884376

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BF305 **MC GIRK J ARTH AUTO** **EDR Hist Auto** **1013757401**
Target **3000 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 4 of 10 in cluster BF

Actual:
592 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1916	MAIN GARAGE AND MA	AUTOMOBILE GARAGES
1916	MAIN GARAGE AND MA	AUTOMOBILE REPAIRERS
1929	HILDINGERS FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1929	LOWERY B A AUTO REPR	AUTOMOBILE REPAIRERS
1935	HILDINGER J J FILL STA	GASOLINE AND OIL SERVICE STATIONS

MC GIRK J ARTH AUTO (Continued) **1013757401**

1940	HILDINGER JACOB J FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1940	MC GIRK J ARTH AUTO	AUTOMOBILE REPAIRING
1947	MCGIRK AUTO REPAIR	AUTOMOBILE REPAIRING
1947	HILDINGER FILLING STA	GASOLINE AND OIL SERVICE STATIONS

BF306 **HOBBY TRACT** **TX IOP** **S104918399**
Target **3000 GUADALUPE ST** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78705**

Site 5 of 10 in cluster BF

Actual:
592 ft.

Focus Map:
8

IOP:

Name:	HOBBY TRACT
Address:	3000 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Program ID:	183
Date IOP Received:	Not reported
Region:	REGION 11 - AUSTIN
Phase:	COMPLETED
Interest In Site:	Not reported
PCA Number:	32183
Property Use:	PRINTING
Project Manager:	MPALMIE
Project Number:	321830
Latitude:	29.00
Longitude:	-95.00
Acres:	CITY BLOCK
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	05/14/2001; 02/21/2001; 03/23/2001
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN100520097
Consultant/Attorney Phone:	Not reported
Site Address Description:	400 BLOCK OF W 3RD ST
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	07/28/2000
Application Received Date:	08/02/2000
Application Acceptance Date:	09/18/2000
IOP Application Accepted:	Y

HOBBY TRACT (Continued) **S104918399**

SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	200-37N/D

Customer:

REM Program:	IOP
Program ID:	183
RN Number:	RN100520097
CN Number:	CN600240618
CN Name:	GENERAL SERVICES COMMISSION
Role CD:	APPLCONT
Contact Name:	DAVENPORT, JOHN
Contact Title:	DIRECTOR FACILITIES
Organization Name:	GENERAL SERVICES COMMISSION
Mailing Address:	PO BOX 13047
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78711
Contact Phone:	(512) 463-3583
Contact Ext:	0

REM Program:	IOP
Program ID:	183
RN Number:	RN100520097
CN Number:	CN600240618
CN Name:	GENERAL SERVICES COMMISSION
Role CD:	BILLCONT
Contact Name:	DAVENPORT, JOHN
Contact Title:	Not reported
Organization Name:	GENERAL SERVICES COMMISSION
Mailing Address:	PO BOX 13047
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78711
Contact Phone:	(512) 463-3583
Contact Ext:	0

CENTRAL REGISTRY:

Regulated Entity Number:	RN100520097
Name:	HOBBY TRACT
Address:	3000 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600240618
Customer Name:	GENERAL SERVICES COMMISSION
Customer Legal Name:	General Services Commission
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

HOBBY TRACT (Continued) **S104918399**

Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 400 BLOCK OF W 3RD ST

Regulated Entity Number: RN100520097
Name: HOBBY TRACT
Address: 3000 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-2845
Status: ACTIVE
Status Date: ##########
Customer Number: CN600240618
Customer Name: GENERAL SERVICES COMMISSION
Customer Legal Name: General Services Commission
Customer Ownership Type: CITY GOVERNMENT
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 400 BLOCK OF W 3RD ST

BF307 **VACANT LOT** **TX HIST UST** **S128728943**
Target **3005 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 6 of 10 in cluster BF

Actual:
590 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: VACANT LOT
Address: 3005 GUADALUPE ST
City,State,Zip: AUSTIN, TX
Id UST: C0176
HID UST: Not reported
Inspection: Not reported
Due: Not reported

BF308 **JESSE J. SMITH** **TX HIST UST** **S111678704**
Target **602 W 30TH ST** **N/A**
Property **AUSTIN, TX**

Site 7 of 10 in cluster BF

Actual:
593 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: JESSE J. SMITH
Address: 602 W 30TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0029
HID UST: 29
Inspection: Not reported
Due: 06/01/2012

BG309 Target Property | **DICKEN 6 BROS CLNRS**
2930 GUADALUPE
AUSTIN, TX | **EDR Hist Cleaner** | **1013777466**
N/A

Site 1 of 8 in cluster BG

Actual: 597 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1953	DICKEN 6 BROS CLNRS	CLEANERS AND DYERS
1958	DICKENS CLNS	CLEANERS
1958	DICKENS CLNS	CLEANERS AND DYERS

BG310 Target Property | **FOUNTAIN TERRACE UNIT 117**
601 W. 30TH STREET
AUSTIN, TX 78705 | **TX ASBESTOS** | **S126247569**
N/A

Site 2 of 8 in cluster BG

Actual: 594 ft.

Focus Map: 8

ASBESTOS:

Name:	FOUNTAIN TERRACE UNIT 117
Address:	601 W. 30TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Javier Velazquez
Violation:	Not reported
Complaint Date:	01/29/2020
Notification Number:	2020000537
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/15/2020
Certification Statement Phone:	512-470-7173
Is The Facility a School or K-12?:	N
Region:	07

FOUNTAIN TERRACE UNIT 117 (Continued) **S126247569**

Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/29/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BG311 **DICKENS CLEANERS & SHIRT** **EDR Hist Cleaner** **1013780209**
Target **2918 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 8 in cluster BG

Actual:
597 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1962	2918 20 DICKENS CLNS &	CLEANERS
1962	2918 20 DICKENS CLNS &	CLEANERS AND DYERS
1965	DICKENS CLEANERS & SHIRT	CLEANERS
1965	DICKENS CLEANERS & SHIRT	CLEANERS AND DYERS
1969	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs
1970	DICKENS CLEANERS & SHIRT LAUNDR	CLEANERS AND DYERS
1970	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs
1971	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs
1972	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs
1974	DICKENS CLEANERS & SHIRT LAUND	Drycleaning Plants, Except Rugs
1975	DICKENS CLEANERS & SHIRT LAUNDR	CLEANERS AND DYERS
1975	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs

BH312 **RICKS CLEANERS INC** **EDR Hist Cleaner** **1020074566**
Target **2908 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 7 in cluster BH

Actual:
596 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1994	RICKS CLEANERS INC	Drycleaning Plants, Except Rugs
1995	RICKS CLEANERS INC	Drycleaning Plants, Except Rugs
1996	RICKS CLEANERS INC	Drycleaning Plants, Except Rugs
1997	RICKS CLEANERS INC	Drycleaning Plants, Except Rugs

BH313 **COMMUNITY CLNRS** **EDR Hist Cleaner** **1013777404**
Target **2904 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 7 in cluster BH

Actual:
596 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1935	COMMUNITY CLNRS	CLOTHES PRESSERS AND CLEANERS
1940	COMMUNITY CLEAN	CLOTHES PRESSERS AND CLEANERS

---

314 **FIRST ENGLISH LUTHERAN CHURCH** **TX ASBESTOS** **S129330060**
Target **3001 WHITIS AVENUE** **N/A**
Property **AUSTIN, TX 78705**

Actual:
564 ft.

Focus Map:
8

ASBESTOS:

Name:	FIRST ENGLISH LUTHERAN CHURCH
Address:	3001 WHITIS AVENUE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	12/23/2016
Notification Number:	2016009809
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

FIRST ENGLISH LUTHERAN CHURCH (Continued) **S129330060**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/07/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/22/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BH315 **MALLETT JACK SERVICE** **EDR Hist Auto** **1013757711**
Target **2901 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 3 of 7 in cluster BH

Actual:
595 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	MALLETT JACK SERVICE	GASOLINE AND OIL SERVICE STATIONS
1947	KING SAM SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	KING SAM SERV STA	GASOLINE STATIONS
1958	KING SAM SERV STA	GASOLINE STATIONS
1962	KING SAM SERV STA	GASOLINE STATIONS
1965	HERRIN TEXACO SERVICE	GASOLINE STATIONS

BI316 Target Property | **PARD-ANNEX BUILDING B**
2818 SAN GABRIEL
AUSTIN, TX 78705 | **TX ASBESTOS** | **S126248162**
N/A

Site 1 of 2 in cluster BI

Actual: 546 ft.

Focus Map: 8

ASBESTOS:

Name:	PARD-ANNEX BUILDING B
Address:	2818 SAN GABRIEL
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	02/29/2020
Notification Number:	2020001366
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/11/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/26/2020
Client Code:	Not reported
Client Name:	Not reported

PARD-ANNEX BUILDING B (Continued) **S126248162**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARD-ANNEX BUILDING B
Address:	2818 SAN GABRIEL
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	05/17/2020
Notification Number:	2020003016
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/01/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/01/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N

PARD-ANNEX BUILDING B (Continued) **S126248162**

Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/16/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARD-ANNEX BUILDING B
Address:	2818 SAN GABRIEL
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	05/12/2020
Notification Number:	2020003016
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/23/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

PARD-ANNEX BUILDING B (Continued) **S126248162**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/23/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BI317 **ANNEX BUILDING** **TX ASBESTOS** **S119138284**
Target **2818 SAN GABRIEL ST.** **N/A**
Property **AUSTIN, TX 78705**

Site 2 of 2 in cluster BI

Actual:
546 ft.

Focus Map:
8

ASBESTOS:

Name:	ANNEX BUILDING
Address:	2818 SAN GABRIEL ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/29/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported

ANNEX BUILDING (Continued) **S119138284**

Notification Number:	2014002329
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	05/28/2014
Date Routed by Supervisor:	06/19/2014
Date Routed to PSQA:	06/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

ANNEX BUILDING (Continued) **S119138284**

Inspection Class Descriptio: Not reported
Inspection Secondary Class Code: Not reported
Inspection Secondary Class Code Description: Not reported
Results: Not reported
Inspection Number Grade: Not reported

BJ318 **MONTGOMERYS HUMBLE** **EDR Hist Auto** **1013766465**
Target **2825 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 8 in cluster BJ

Actual: EDR Hist Auto
594 ft.

Focus Map:
8

Year:	Name:	Type:
1929	HUMBLE OIL CO STA	GASOLINE AND OIL SERVICE STATIONS
1935	HUMBLE OIL & REFG	GASOLINE AND OIL SERVICE STATIONS
1953	NELLE SERV STA FILLING	GASOLINE STATIONS
1958	NELLE SERV STA	GASOLINE STATIONS
1962	SIMPSON HUMBLE	GASOLINE STATIONS
1965	MONTGOMERYS HUMBLE	GASOLINE STATIONS

BJ319 **A C LINEN SUPPLY** **EDR Hist Cleaner** **1013781159**
Target **2822 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 2 of 8 in cluster BJ

Actual: EDR Hist Cleaner
595 ft.

Focus Map:
8

Year:	Name:	Type:
1947	A C LINEN SUPPLY	LAUNDRIES
1947	WHITE LAUNDRY & DRY CLEANING CO	LAUNDRIES

BJ320 **CHEVRON SELF SERVICE STATION** **EDR Hist Auto** **1013768615**
Target **2819 GUADALUPE ST** **N/A**
Property **TRAVIS (County), TX 78705**

Site 3 of 8 in cluster BJ

Actual: EDR Hist Auto
593 ft.

Focus Map:
11

Year:	Name:	Type:
1989	BINGAMAN BEVERAGE COMPAN	Gasoline Service Stations
1990	CHEVRON SELF SERVICE STATION	GASOLINE STATIONS
1991	BINGAMAN BEVERAGE COMPANY	Gasoline Service Stations
1992	BINGAMAN BEVERAGE COMPANY	Gasoline Service Stations
1993	BINGAMAN BEVERAGE COMPANY	Gasoline Service Stations
1993	CHEVRON STATIONS INC	Gasoline Service Stations
1994	CHEVRON STATIONS INC	Gasoline Service Stations
1995	CHEVRON STATIONS INC	Gasoline Service Stations
1996	CHEVRON STATIONS INC	Gasoline Service Stations
1997	CHEVRON STATIONS INC	Gasoline Service Stations
1998	CHEVRON STATIONS INC	Gasoline Service Stations
1999	CHEVRON STATIONS INC	Gasoline Service Stations

CHEVRON SELF SERVICE STATION (Continued) **1013768615**

2000	CHEVRON STATIONS INC	Gasoline Service Stations
2001	CHEVRON STATIONS INC	Gasoline Service Stations
2002	CHEVRON STATIONS INC	Gasoline Service Stations
2003	CHEVRON STATIONS INC	Gasoline Service Stations
2004	CHEVRON STATIONS INC	Gasoline Service Stations
2005	CHEVRON STATIONS INC	Gasoline Service Stations, NEC
2006	CHEVRON STATIONS INC	Gasoline Service Stations, NEC
2007	CHEVRON STATIONS INC	Gasoline Service Stations, NEC

BJ321 **CHEVRON FAC 107149** **FINDS** **1011358827**
Target **2819 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 4 of 8 in cluster BJ

Actual:
593 ft.

Focus Map:
11

FINDS:
Registry ID: 110034674350

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BJ322 **STAR STOP 74** **TX CENTRAL REGISTRY** **S128211339**
Target **2819 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 5 of 8 in cluster BJ

Actual:
593 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number: RN102789633

STAR STOP 74 (Continued) **S128211339**

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/24/1986
Affiliation End Date:	10/14/2003
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600745145
Customer Name:	TETCO INC
Customer Legal Name:	Tetco, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602596686
Customer Name:	CAPITAL CONVENIENCE STORES LP
Customer Legal Name:	Capital Convenience Stores, L.P.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/15/2003
Affiliation End Date:	10/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported

STAR STOP 74 (Continued) **S128211339**

City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2012
Affiliation End Date:	9/30/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604013359
Customer Name:	PANJWANI ENERGY LLC
Customer Legal Name:	Panjwani Energy, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/1/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001

STAR STOP 74 (Continued) **S128211339**

Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/24/1986
Affiliation End Date:	10/14/2003
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600745145
Customer Name:	TETCO INC
Customer Legal Name:	Tetco, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602596686
Customer Name:	CAPITAL CONVENIENCE STORES LP
Customer Legal Name:	Capital Convenience Stores, L.P.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/15/2003
Affiliation End Date:	10/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102789633
Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.

STAR STOP 74 (Continued) **S128211339**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2012
Affiliation End Date:	9/30/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
20 additional TX CENTRAL REG: record(s) in the EDR Site Report.

BJ323 **STAR STOP 74** **TX UST** **U001262277**
Target **2819 GUADALUPE ST** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78705** **TX ASBESTOS**
TX Financial Assurance

Site 6 of 8 in cluster BJ

Actual: 593 ft.

Focus Map: 11

UST:

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787053723
AI Number:	28643
Facility Type:	RETAIL
Facility Begin Date:	01/01/1974
Facility Status:	ACTIVE
Additional ID:	574685622002205
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	SUNNY PANJWANI,SUPV
Contact Organization Name:	STAR STOP 74
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8328149789
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/20/2021
Signature Name/Title On Earliest Reg Form:	KARIM PANJWANI,
Application Received Date On Earliest Reg Form:	06/02/2021
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	323464072011354
Additional ID:	574685622002205
Ai Number:	28643
Operator CN:	CN604013359
Operator Name:	PANJWANI ENERGY LLC

STAR STOP 74 (Continued) **U001262277**

Operator Effective Begin Date:	10/01/2013
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	FEROZ PANJWANI/PRES
Contact Organization Name:	PANJWANI ENERGY LLC
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON TX 77036-3360
Contact Phone Country Code:	1
Contact Phone Area Code:	713
Contact Phone Number:	7814610
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	MIKE@PANJWANIENT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604013359
Owner Last Name:	PANJWANI ENERGY LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	HOUSTON
Contact Mailing State:	TX
Contact Mailing Zip:	77036
Contact Mailing Zip5:	3360
Contact Phone Number/Ext:	1 713 7814610/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MIKE@PANJWANIENT.COM
Contact Address Deliverable:	Not reported
Princ ID:	323464072011354
Additional ID:	574685622002205
AI Number:	28643
Owner Effective Begin Date:	10/01/2013
State Tax ID:	32044634874
Contact Role:	OWNOPRCON
Contact Name/Title:	FEROZ PANJWANI/PRES
Contact Organization Name:	PANJWANI ENERGY LLC

Self Certification:

Self Cert ID:	63566
Cert ID:	377003
AI Number:	28643
Self Certification Date:	09/27/2022
Signature Name/Title:	AMIN PANJWANI OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	359563
AI Number:	28643
Self Certification Date:	09/09/2021
Signature Name/Title:	NAZNEEN MERCHANT MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	344030
AI Number:	28643
Self Certification Date:	09/03/2020
Signature Name/Title:	FEROZ PANJWANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	325913
AI Number:	28643
Self Certification Date:	08/15/2019
Signature Name/Title:	SHASUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	309218
AI Number:	28643
Self Certification Date:	08/24/2018
Signature Name/Title:	SHAMSUDDIN PANJWANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	293045
AI Number:	28643
Self Certification Date:	09/08/2017
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	276166
AI Number:	28643
Self Certification Date:	09/09/2016
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	259822
AI Number:	28643
Self Certification Date:	09/23/2015
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	243760
AI Number:	28643
Self Certification Date:	09/30/2014
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	243759
AI Number:	28643
Self Certification Date:	10/01/2013
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	63566
Cert ID:	76524
AI Number:	28643
Self Certification Date:	11/06/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	63566
Cert ID:	76523
AI Number:	28643
Self Certification Date:	11/05/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	63566
Cert ID:	76522
AI Number:	28643
Self Certification Date:	01/06/2012
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76521
AI Number:	28643
Self Certification Date:	12/27/2010
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76520
AI Number:	28643
Self Certification Date:	12/04/2009
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76519
AI Number:	28643
Self Certification Date:	01/01/2009
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76518
AI Number:	28643
Self Certification Date:	12/19/2007
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76517
AI Number:	28643
Self Certification Date:	12/28/2006
Signature Name/Title:	RAYMOND MCNIECE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76281
AI Number:	28643
Self Certification Date:	12/30/2005
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76280
AI Number:	28643
Self Certification Date:	12/30/2004
Signature Name/Title:	RAYMOND MCNIECE ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76279
AI Number:	28643
Self Certification Date:	01/02/2004
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76278
AI Number:	28643
Self Certification Date:	10/21/2003
Signature Name/Title:	RAYMOND MCNIECE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76277
AI Number:	28643
Self Certification Date:	10/13/2003
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76276
AI Number:	28643
Self Certification Date:	03/28/2003
Signature Name/Title:	DAVID POOL RESH SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76275
AI Number:	28643
Self Certification Date:	04/19/2002
Signature Name/Title:	DAVID POOL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

STAR STOP 74 (Continued) **U001262277**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	63566
Cert ID:	76274
AI Number:	28643
Self Certification Date:	01/08/2001
Signature Name/Title:	LODNEY DAVIS RESH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9842
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75199
Facility ID:	63566
Ai Number:	28643
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1974
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

STAR STOP 74 (Continued) **U001262277**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9842
UST Comprt ID:	70952
UST ID:	75199
AI Number:	28643
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

STAR STOP 74 (Continued) **U001262277**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/1986

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9842
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75202
Facility ID:	63566
Ai Number:	28643
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

STAR STOP 74 (Continued) **U001262277**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	9842
UST Comprt ID:	70955
UST ID:	75202
AI Number:	28643
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y

STAR STOP 74 (Continued) **U001262277**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/1986

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9842
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75201
Facility ID:	63566
Ai Number:	28643
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y

STAR STOP 74 (Continued) **U001262277**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	9842
UST Comprt ID:	70954
UST ID:	75201
AI Number:	28643
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

STAR STOP 74 (Continued) **U001262277**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/1986

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5766
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	75200
Facility ID:	63566
Ai Number:	28643
Tank Id:	4
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	05/03/2021
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

STAR STOP 74 (Continued) **U001262277**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	5766
UST Comprt ID:	70953
UST ID:	75200
AI Number:	28643
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/1986

Construction Notification:

NOC ID:	6389

STAR STOP 74 (Continued) **U001262277**

Facility ID:	63566
AI Number:	28643
Application Received Date:	05/21/2004
Scheduled Construction Date:	05/21/2004
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M40521006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	62121
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	6865
UST ID:	Not reported
NOC ID:	6389
AI Number:	28643
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PANJWANI ENERGY LLC
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111

STAR STOP 74 (Continued) **U001262277**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77036 3360
Phone Number/Ext:	713 7814610/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	63566
Additional ID:	574685622002205
Princ ID:	323464072011354
AI Number:	28643
Facility Name:	STAR STOP 74
AR Number:	72839
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	FEROZ PANJWANI/PRES

HIST UST AUSTIN:

Name:	STAR STOP #74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	994
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	STAR STOP
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	06/03/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.3
Mileage:	7.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

STAR STOP 74 (Continued) **U001262277**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	STAR STOP
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/11/2015
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1

STAR STOP 74 (Continued) **U001262277**

Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	STAR STOP 74

STAR STOP 74 (Continued) **U001262277**

Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	274806
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2022
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 7224994
Policy Number:	04-TOP-000031332
Coverage Amount:	2,000,000
Coverage Expiration Date:	08/15/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	256447
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2021
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	0 918 5619338
Policy Number:	04-TOP-000021625
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	238808
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

STAR STOP 74 (Continued) **U001262277**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2020
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000012413
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	219541
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2019
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-to-005001600
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	202607
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2017
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534

STAR STOP 74 (Continued) **U001262277**

Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	168631
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2015
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	186217
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2016
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2

STAR STOP 74 (Continued) **U001262277**

Facility ID:	63566
Finass ID:	150970
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2014
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	135498
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2014
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	134811
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

STAR STOP 74 (Continued) **U001262277**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2013
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	116685
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2012
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	5352
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No

STAR STOP 74 (Continued) **U001262277**

Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47613
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2011
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	001215401
Coverage Amount:	1000000
Coverage Expiration Date:	12/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47612
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2012
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235400
Coverage Amount:	1000000
Coverage Expiration Date:	12/18/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47614
AI:	28643

STAR STOP 74 (Continued) **U001262277**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2009
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	000026400
Coverage Amount:	1000000
Coverage Expiration Date:	12/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47615
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2009
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	000026400
Coverage Amount:	1000000
Coverage Expiration Date:	12/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47616
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	06/02/2021

STAR STOP 74 (Continued) **U001262277**

Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST 8058109
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47617
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST 8057698
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 74
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	63566
Finass ID:	47618
AI:	28643
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	06/02/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

BJ324 Target Property | **TETCO 78**
2819 GUADALUPE ST
AUSTIN, TX | **TX RDR** | **S127529182**
N/A

Site 7 of 8 in cluster BJ

Actual: 593 ft.
Focus Map: 11

RDR:

RDR ID:	21079
Facility ID:	28643
RN:	Not reported
CN:	Not reported
Name:	TETCO 78
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/25/2013
Due Date:	9/23/2013
Tank Owner:	CAPITAL CONVENIENCE STORE
Contact Person:	JOHN FARRELL
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/5/2013
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	93212
Comments:	RDR 2/4/13; DEF LTR 4/4/13; TECH RESP 7/25/13
Review Coordinator:	EAE
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

BK325 Target Property | **CHEVRON USA INC**
2817 GUADALUPE ST
AUSTIN, TX 78705 | **RCRA NonGen / NLR**
FINDS
ECHO | **1000653751**
TXD988035218

Site 1 of 8 in cluster BK

Actual: 595 ft.
Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20070417
Handler Name:	Chevron Usa Inc
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TXD988035218
Contact Name:	KATHRYN MINTER
Contact Address:	PO BOX 5004
Contact City,State,Zip:	SAN RAMON, CA 94583
Contact Telephone:	713-754-3500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CHEVRON USA INC (Continued) **1000653751**

Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 5004
Mailing City,State,Zip:	SAN RAMON, CA 94583
Owner Name:	Chevron Usa Inc
Owner Type:	Private
Operator Name:	Chevron Usa Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20070426
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste

CHEVRON USA INC (Continued) **1000653751**

Waste Code: D018
Waste Description: Benzene

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CHEVRON USA INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5004
Owner/Operator City,State,Zip: SAN RAMON, CA 94583
Owner/Operator Telephone: 713-754-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHEVRON USA INC
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5004
Owner/Operator City,State,Zip: SAN RAMON, CA 94583
Owner/Operator Telephone: 713-754-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHEVRON USA INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5004
Owner/Operator City,State,Zip: SAN RAMON, CA 94583
Owner/Operator Telephone: 713-754-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CHEVRON USA INC
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5004
Owner/Operator City,State,Zip: SAN RAMON, CA 94583
Owner/Operator Telephone: 713-754-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHEVRON USA INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported

CHEVRON USA INC (Continued) **1000653751**

Owner/Operator Address:	PO BOX 4256
Owner/Operator City,State,Zip:	HOUSTON, TX 77210
Owner/Operator Telephone:	713-754-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CHEVRON USA INC	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5004
Owner/Operator City,State,Zip:	SAN RAMON, CA 94583
Owner/Operator Telephone:	713-754-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CHEVRON USA INC	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5004
Owner/Operator City,State,Zip:	SAN RAMON, CA 94583
Owner/Operator Telephone:	713-754-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19910501
Handler Name: CHEVRON USA INC #107149	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010823
Handler Name: CHEVRON USA INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CHEVRON USA INC (Continued) **1000653751**

Receive Date:	20051129
Handler Name: CHEVRON USA INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070417
Handler Name: CHEVRON USA INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070165910

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.
Registry ID: 110005134684

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CHEVRON USA INC (Continued) **1000653751**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000653751
Registry ID:	110005134684
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005134684
Name:	CHEVRON USA INC
Address:	2817 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705

BK326 **LICARI SAM GULF** **EDR Hist Auto** **1013757412**
Target **2817 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 8 in cluster BK

Actual: **595 ft.**

Focus Map: **11**

EDR Hist Auto

Year:	Name:	Type:
1962	LICARI SAM GULF	GASOLINE STATIONS
1965	MORGAN GULF SERVICE & R	GASOLINE STATIONS
1970	MORGAN AUTOMOTIVE AUTO REPR	AUTOMOBILE REPAIRING
1970	MORGAN GULF SERVICE	GASOLINE STATIONS
1972	MORGAN ROBERT V	Gasoline Service Stations
1973	MORGAN ROBERT V	Gasoline Service Stations
1974	MORGAN ROBERT V	Gasoline Service Stations
1975	MORGAN ROBERT V	Gasoline Service Stations
1980	GULF SELF SERVICE ST	GASOLINE STATIONS
1984	GULF SELF SERVICE STATION	GASOLINE STATIONS
1992	CHEVRON STATIONS	Gasoline Service Stations

BK327 **CHEVRON FAC 107149** **TX Ind. Haz Waste** **S102758868**
Target **2817 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 8 in cluster BK

Actual: **595 ft.**

Focus Map: **11**

Ind. Haz Waste:

Name:	CHEVRON FAC 107149
Address:	2817 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	79170
Registration Initial Notification Date:	10/26/1992
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988035218
Primary NAICS Code:	Not reported
Status Change Date:	19921026
Land Type:	PRIVATE
Description of Facility Site Location:	2817 Guadalupe St, Austin, TX
Site Primary Standard Industrial Code:	Not reported

CHEVRON FAC 107149 (Continued) **S102758868**

Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CHEVRON USA INC
Contact Name:	KATHRYN MINTER
Contact Telephone Number:	713-7543500
Mailing Address:	PO BOX 5004
Mailing Address2:	Not reported
Mailing City,State,Zip:	SAN RAMON, CA 945830804
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	32724
Site Owner Tax ID:	250527925
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CHEVRON USA INC
Operator Address:	PO BOX 5004
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	SAN RAMON, CA 94583
Operator Country:	UNITED STA
Operator Telephone:	1-713-7543500
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	12505279252
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CHEVRON USA INC

CHEVRON FAC 107149 (Continued) **S102758868**

Owner Mailing Address:	PO BOX 5004
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	SAN RAMON, CA 94583
Owner Country:	UNITED STA
Owner Telephone:	1-713-7543500
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	12505279252
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	19
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 5004
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN RAMON, CA 94583
Contact Phone:	1-713-7543500
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 5004
Contact Address 2:	Not reported
Contact Address 3:	Not reported

CHEVRON FAC 107149 (Continued) **S102758868**

Contact City,State,Zip:	SAN RAMON, CA 94583
Contact Phone:	1-713-7543500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	KATHRYN MINTER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 5004
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN RAMON, CA 94583
Contact Phone:	1-713-7543500
Contact Fax:	Not reported
Contact Email:	Not reported

BK328 **CHEVRON STATION 107149** **TX LPST** **S116702337**
Target **2817 GUADALUPE ST** **TX ASBESTOS** **N/A**
Property **AUSTIN, TX 78705**

Site 4 of 8 in cluster BK

Actual: 595 ft.

Focus Map: 11

LPST:

Name:	CHEVRON STATION 107149
Address:	2817 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0028643
LPST Id:	093212
Facility Location:	2817 GUADALUPE ST @ 29TH ST & FRUIT ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/30/1989
Entered Date:	07/06/1989
Reported Date:	07/05/1989
Closure Date:	02/06/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1
Coordinators RPR:	KSR
Responsible Party Name:	Not reported
Responsible Party Contact:	JEFFREY DOWNING
Responsible Party Address:	PO BOX 4256
Responsible Party City,St,Zip:	HOUSTON, TX 77210
Responsible Party Telephone:	713/219-5210
Reported Date:	07/05/1989
Case Start Date:	02/06/2001
Reference Number:	RN102789633
Project Manager:	KSR

ASBESTOS:

Name:	7-ELEVEN
Address:	2819 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705

CHEVRON STATION 107149 (Continued) **S116702337**

Date of inspection:	05/03/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

CHEVRON STATION 107149 (Continued) **S116702337**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BK329 **CHEVRON 107149** **TX CENTRAL REGISTRY** **S126531060**
Target **2817 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 5 of 8 in cluster BK

Actual:
595 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101616381
Name:	CHEVRON 107149
Address:	2817 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	3/8/2002
Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2817 Guadalupe St, Austin, TX

Regulated Entity Number:	RN101616381
Name:	CHEVRON 107149
Address:	2817 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3723
Status:	ACTIVE
Status Date:	3/8/2002
Customer Number:	CN600132484
Customer Name:	CHEVRON USA INC
Customer Legal Name:	Chevron U.S.A. Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2817 Guadalupe St, Austin, TX

BL330 Target Property | **AMERICAN CONSTRUCTORS PHASE 1-AUSTIN PRESBYTERIAN**
101 E 30TH ST
AUSTIN, TX 78705 | **FINDS** | **1010719366**
N/A

Site 1 of 2 in cluster BL

Actual: 572 ft.
Focus Map: 11

FINDS:
Registry ID: 110033449631

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BL331 Target Property | **AMERICAN CONSTRUCTORS PHASE 1-AUSTIN PRESBYTERIAN**
101 E 30TH ST
AUSTIN, TX 78705 | **TX CENTRAL REGISTRY** | **S126776470**
N/A

Site 2 of 2 in cluster BL

Actual: 572 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN105399497
Name:	AMERICAN CONSTRUCTORS PHASE 1-AUSTIN PRESBYTERIAN THEOLOGICAL SEMINARY-ANDERSON
Address:	101 E 30TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3844
Status:	ACTIVE
Status Date:	2008-01-17
Customer Number:	CN602642001
Customer Name:	AMERICAN CONSTRUCTORS LP
Customer Legal Name:	American Constructors, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2007-12-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105399497
Name:	AMERICAN CONSTRUCTORS PHASE 1-AUSTIN PRESBYTERIAN THEOLOGICAL SEMINARY-ANDERSON
Address:	101 E 30TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-3844
Status:	ACTIVE
Status Date:	2008-01-17
Customer Number:	CN602642001
Customer Name:	AMERICAN CONSTRUCTORS LP
Customer Legal Name:	American Constructors, L.P.
Customer Ownership Type:	PARTNERSHIP

AMERICAN CONSTRUCTORS PHASE 1-AUSTIN PRESBYTERIAN THEOLOGICA (Continued) **S126776470**

Affiliation Begin Date:	2007-12-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

BK332 **MAGNOLIA PET CO STA** **EDR Hist Auto** **1013776017**
Target Property **2810 GUADALUPE ST** **N/A**
AUSTIN, TX

Site 6 of 8 in cluster BK

Actual: 597 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	MAGNOLIA PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	WOFFORD JOHN W FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1947	WOFFORD J W SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	TOLAR & TURNER SERV	GASOLINE STATIONS

BM333 **LAUNDERETTE WASHATERIA** **EDR Hist Cleaner** **1013780799**
Target Property **2706 GUADALUPE** **N/A**
AUSTIN, TX

Site 1 of 6 in cluster BM

Actual: 603 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1947	LAUNDERETTE WASHATERIA	LAUNDRIES
1958	MOORES	LAUNDRIES

BM334 **PARAMOUNT CLNRS** **EDR Hist Cleaner** **1013779394**
Target Property **2704 GUADALUPE ST** **N/A**
AUSTIN, TX

Site 2 of 6 in cluster BM

Actual: 603 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	PARAMOUNT CLNRS	CLOTHES PRESSERS AND CLEANERS
1940	PARAMOUNT CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	GUTHRIE DELUXE CLNRS	CLOTHES PRESSERS AND CLEANERS
1953	GUTHRIE DELUXE	CLEANERS AND DYERS
1958	GUTHRIE CLEANERS	CLEANERS AND PRESSERS
1958	GUTHRIE CLEANERS	CLEANERS AND DYERS
1962	2704 06 GUTHRIE BROS	CLEANERS AND DYERS
1970	MASTER VALET DRY CLEANING	CLEANERS AND DYERS

BN335 Target Property | **MAC'S PIZZA**
2701 GUADALUPE ST.
AUSTIN, TX 78705 | **TX ASBESTOS** | **S119150596**
N/A

Site 1 of 4 in cluster BN

Actual: 609 ft.

Focus Map: 11

ASBESTOS:

Name:	MAC'S PIZZA
Address:	2701 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/05/2016
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2016000835
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	04
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	03/23/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	05/16/2016
Date Reviewed by PSQA:	2016-05-16 00:00:00
Date Routed by Supervisor1:	05/09/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

MAC'S PIZZA (Continued) **S119150596**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BN336 **DUNBAR LOUIE FILL STA** **EDR Hist Auto** **1013753891**
Target **2701 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 4 in cluster BN

Actual:
609 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	DUNBAR LOUIE FILL STA	GASOLINE AND OIL SERVICE STATIONS

---

337 **FORMER FRAT HOUSE BUILDINGS** **TX ASBESTOS** **S125922074**
Target **2614 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Actual:
603 ft.

Focus Map:
11

ASBESTOS:

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/05/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/30/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/02/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/30/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/02/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	10/08/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/23/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/15/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/23/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	10/22/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/03/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/30/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/30/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/03/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/30/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/05/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/15/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/29/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/15/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/29/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/08/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/28/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/04/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Inspector Name:	Not reported
Date Report Received:	11/04/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/28/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/04/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Complaint Date:	11/14/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/02/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/02/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/11/2019

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/22/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/08/2019

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/08/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/22/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/19/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/19/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/22/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/20/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/21/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/20/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/24/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/21/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/22/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/21/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/29/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/22/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/22/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/29/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/25/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/25/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/05/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/27/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/02/2019
Client Code:	Not reported
Client Name:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/27/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	10/02/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/11/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER FRAT HOUSE BUILDINGS
Address:	2614 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/15/2019
Notification Number:	2019007035
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

FORMER FRAT HOUSE BUILDINGS (Continued) **S125922074**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	09/11/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BO338 Target Property | **FORTY ACRES CLNS**
2605 GUADALUPE ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013782959**
N/A

Site 1 of 5 in cluster BO

Actual: 610 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1962	FORTY ACRES CLNS	CLEANERS AND DYERS

BP339 Target Property | **FRATERNITY HOUSE**
800 W. 26TH ST.
AUSTIN, TX 78705 | **TX ASBESTOS** | **S119146329**
N/A

Site 1 of 3 in cluster BP

Actual: 604 ft.

Focus Map: 11

ASBESTOS:

Name:	FRATERNITY HOUSE
Address:	800 W. 26TH ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/29/2012
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2012007508
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/27/2012
Date Routed by Supervisor:	11/29/2012
Date Routed to PSQA:	12/04/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported

FRATERNITY HOUSE (Continued) **S119146329**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BP340 **FRATERNITY HOUSE** **TX ASBESTOS** **S129330932**
Target **800-804 WEST 26TH** **N/A**
Property **AUSTIN, TX 78705**

Site 2 of 3 in cluster BP

Actual:
604 ft.

Focus Map:
11

ASBESTOS:

Name:	FRATERNITY HOUSE
Address:	800-804 WEST 26TH
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2012/10/29
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

FRATERNITY HOUSE (Continued) **S129330932**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	10/29/2012
Client Code:	1400
Client Name:	Environmental Facilities/Notification
License Number:	2012007508
File Number:	94642
License Status Description:	Paid
Expiration Date:	11/29/2012
Original Date:	10/10/2012
Rank Effective Date:	10/10/2012
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	31271
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	A
Inspection Secondary Class Code Description:	Asbestos
Results:	Pass
Inspection Number Grade:	0

BP341 **LYDA SWINERTON BUILDERS PIAZZA NAVONA** **TX CENTRAL REGISTRY** **S126705055**
Target **711 W 26TH ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 3 in cluster BP

Actual:
603 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN104346432
Name:	LYDA SWINERTON BUILDERS PIAZZA NAVONA
Address:	711 W 26TH ST
Address 2:	Not reported

LYDA SWINERTON BUILDERS PIAZZA NAVONA (Continued) **S126705055**

City,State,Zip:	AUSTIN, TX 78705-4468
Status:	ACTIVE
Status Date:	2004-07-27
Customer Number:	CN602500241
Customer Name:	LYDA SWINERTON BUILDERS INC
Customer Legal Name:	Lyda Swinerton Builders, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-05-03
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236115
Primary NAICS Industry Type Description:	New Single-Family Housing Construction (except Operative Builders)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104346432
Name:	LYDA SWINERTON BUILDERS PIAZZA NAVONA
Address:	711 W 26TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4468
Status:	ACTIVE
Status Date:	2004-07-27
Customer Number:	CN602500241
Customer Name:	LYDA SWINERTON BUILDERS INC
Customer Legal Name:	Lyda Swinerton Builders, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-05-03
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236115
Primary NAICS Industry Type Description:	New Single-Family Housing Construction (except Operative Builders)
Physical Location Description:	Not reported

BO342 **LONGHORN GULF SERV** **EDR Hist Auto** **1013770010**
Target **2601 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 5 in cluster BO

Actual:
609 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	CROCKETT HARRY FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1947	NASH & SASSMAN SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	LONGHORN GULF SERV	GASOLINE STATIONS
1958	LONGHORN GULF SERV	GASOLINE STATIONS
1962	LONGHORN SERV STA	GASOLINE STATIONS
1965	NELSONS PHILLIPS	GASOLINE STATIONS
1969	LONGHORN PHILLIPS 66 SVC STN	Gasoline Service Stations

BQ343 Target Property | **SJL AD SPECIALTIES**
2512 RIO GRANDE ST
AUSTIN, TX 78705 | **TX Ind. Haz Waste** | **S103612367**
N/A

Site 1 of 2 in cluster BQ

Actual: 602 ft.

Focus Map: 11

Ind. Haz Waste:

Name:	SJL AD SPECIALTIES
Address:	2512 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	82668
Registration Initial Notification Date:	03/03/1994
Registration Last Amendment Date:	02/14/2001
EPA Identification:	Not reported
Primary NAICS Code:	313320
Status Change Date:	19940303
Land Type:	Not reported
Description of Facility Site Location:	2512 Rio Grande St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	LENDIN, LEE
Contact Name:	DAVID B HURLBUT
Contact Telephone Number:	512-3200077
Mailing Address:	2512 RIO GRANDE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787054529
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	98771
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040205
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

SJL AD SPECIALTIES (Continued) **S103612367**

Ind. Haz Waste:

Operator Name:	LEE LENDIN
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	LEE LENDIN
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	LEE LENDIN
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	LEE LENDIN
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	DAVID HURLBUT

SJL AD SPECIALTIES (Continued) **S103612367**

Contact Title:	PRODUCTION MANAGER
Contact Role:	PRICONT
Contact Address:	2512 RIO GRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	1-512-3200077
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	94618
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Petroleumnaphtha from circulating parts washer
Standard Industrial Code:	22950
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	313320
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

BQ344 **SJL AD SPECIALTIES** **TX CENTRAL REGISTRY** **S126522181**
Target **2512 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 2 of 2 in cluster BQ

Actual:
602 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101465946
Name:	SJL AD SPECIALTIES
Address:	2512 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4529
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600759419
Customer Name:	LENDIN, LEE
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########

SJL AD SPECIALTIES (Continued) **S126522181**

Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320
Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

Regulated Entity Number: RN101465946
Name: SJL AD SPECIALTIES
Address: 2512 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-4529
Status: ACTIVE
Status Date: ##########
Customer Number: CN600759419
Customer Name: LENDIN, LEE
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320
Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

Regulated Entity Number: RN101465946
Name: SJL AD SPECIALTIES
Address: 2512 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-4529
Status: ACTIVE
Status Date: ##########
Customer Number: CN603903279
Customer Name: LENDIN, LEE
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 2/14/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320
Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

Regulated Entity Number: RN101465946
Name: SJL AD SPECIALTIES
Address: 2512 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-4529
Status: ACTIVE
Status Date: ##########
Customer Number: CN603903279
Customer Name: LENDIN, LEE
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 2/14/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320

SJL AD SPECIALTIES (Continued) **S126522181**

Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

Regulated Entity Number: RN101465946
Name: SJL AD SPECIALTIES
Address: 2512 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-4529
Status: ACTIVE
Status Date: ##########
Customer Number: CN603885955
Customer Name: LENDIN, LEE
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 10/19/1994
Affiliation End Date: 2/13/2001
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320
Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

Regulated Entity Number: RN101465946
Name: SJL AD SPECIALTIES
Address: 2512 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-4529
Status: ACTIVE
Status Date: ##########
Customer Number: CN603885955
Customer Name: LENDIN, LEE
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 10/19/1994
Affiliation End Date: 2/13/2001
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 313320
Primary NAICS Industry Type Description: Fabric Coating Mills
Physical Location Description: 2512 Rio Grande St, Austin, TX

BR345 **BRIDGEWAY** **TX ASBESTOS** **S119140062**
Target **2616 WICHITA** **N/A**
Property **AUSTIN, TX 78712**

Site 1 of 2 in cluster BR

Actual:
589 ft.

Focus Map:
11

ASBESTOS:
Name: BRIDGEWAY
Address: 2616 WICHITA
City,State,Zip: AUSTIN, TX 78712
Date of inspection: Not reported
Reason for Inspection: Tonya L Bosher
Violation: Not reported
Complaint Date: 11/27/2017
Notification Number: 2017008379
ASB Priority: Not reported
PIF State: Not reported
Detained: Not reported
Product Name: Not reported

BRIDGEWAY (Continued) **S119140062**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/13/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/13/2017
Certification Statement Phone:	512-922-2429
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	11/27/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BRIDGEWAY (Continued) **S119140062**

Name:	BRIDGEWAY BUILDING
Address:	2616 WICHITA ST.
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	02/06/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2014000440
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	05
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	03/03/2014
Date Routed by Supervisor:	04/18/2014
Date Routed to PSQA:	04/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

BRIDGEWAY (Continued) **S119140062**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BS346 **LEES SUPER SERVICE FILLING STA** **EDR Hist Auto** **1013760831**
Target **2533 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 1 of 4 in cluster BS

Actual:
602 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	ROBINSON RUTLAND	GASOLINE AND OIL SERVICE STATIONS
1940	LEES SUPER SERVICE FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1947	JACKSON NORMAN M SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	JACKSON NORMAN M	GASOLINE STATIONS
1962	JACKSONS TEXACO	GASOLINE STATIONS
1965	JACKSONS TEXACO SERVICE STATION	GASOLINE STATIONS

BS347 **UNIVERSITY CLEANERS** **EDR Hist Cleaner** **1013785033**
Target **2520 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 4 in cluster BS

Actual:
601 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	UNIVERSITY CLEANERS	CLOTHES CLEANERS AND PRESSERS

BS348 **AUSTIN DRY CLEANERS** **EDR Hist Cleaner** **1013783968**
Target **2516 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 4 in cluster BS

Actual:
600 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	AUSTIN DRY CLEANERS	CLOTHES CLEANERS AND PRESSERS

BT349 Target Property | **ALPHA EPSLION PHI SORORITY HOUSE**
2500 RIO GRANDE ST.
AUSTIN, TX 78705 | **TX ASBESTOS** | **S119138010**
N/A

Site 1 of 3 in cluster BT

Actual: 600 ft.

Focus Map: 11

ASBESTOS:

Name:	ALPHA EPSLION PHI SORORITY HOUSE
Address:	2500 RIO GRANDE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/25/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2014005682
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/13/2014
Date Routed by Supervisor:	10/31/2014
Date Routed to PSQA:	11/03/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

ALPHA EPSLION PHI SORORITY HOUSE (Continued) **S119138010**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BT350 Target Property **ALPHA EPSILON PHI SORORITY HOUSE** **TX ASBESTOS** **S119138009**
2500 RIO GRANDE ST. **N/A**
AUSTIN, TX 78705

Site 2 of 3 in cluster BT

Actual: 600 ft.

Focus Map: 11

ASBESTOS:

Name:	ALPHA EPSILON PHI SORORITY HOUSE
Address:	2500 RIO GRANDE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/17/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013003336
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	06/18/2013
Date Routed by Supervisor:	07/02/2013
Date Routed to PSQA:	07/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported

ALPHA EPSILON PHI SORORITY HOUSE (Continued) **S119138009**

Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BT351 **ALPHA EPSILON PHI HOUSE** **TX ASBESTOS** **S121062192**
Target **2500 RIO GRANDE** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 3 in cluster BT

Actual:
600 ft.

Focus Map:
11

ASBESTOS:

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	07/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/29/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/17/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/17/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/03/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/24/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/24/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	07/01/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/27/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/27/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Inspector Name:	Not reported
Date Report Received:	06/01/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/01/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Complaint Date:	06/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/15/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/07/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/17/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/16/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/27/2016

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	07/14/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/24/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/24/2016

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	05/30/2016
Notification Number:	2016004039
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/16/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/24/2017
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/02/2017
Notification Number:	2017003543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/23/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/23/2017
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	54
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Inspection Number Grade:	Not reported
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/24/2017
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	05/31/2017
Notification Number:	2017003543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/18/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/18/2017
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	49
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/24/2017
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	06/02/2017
Notification Number:	2017003543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/09/2017
Certification Statement Phone:	512-448-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	131

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/23/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/05/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/24/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017003543
File Number:	19998
License Status Description:	Paid
Expiration Date:	06/02/2017
Original Date:	05/09/2017
Rank Effective Date:	05/09/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	6526
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	ALPHA EPSILON PHI HOUSE
Address:	2500 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/30/2019
Notification Number:	2019003872
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

ALPHA EPSILON PHI HOUSE (Continued) **S121062192**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/14/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/14/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BR352 Target Property | **STUDENT SERVICES BUILDING**
100 W DEAN KEETON ST
AUSTIN, TX 78712 | **TX ASBESTOS** | **S125923088**
N/A

Site 2 of 2 in cluster BR

Actual: 594 ft.

Focus Map: 11

ASBESTOS:

Name:	STUDENT SERVICES BUILDING
Address:	100 W DEAN KEETON ST
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported
Reason for Inspection:	Kevin Alexander
Violation:	Not reported
Complaint Date:	10/03/2019
Notification Number:	2019007008
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/18/2019
Certification Statement Phone:	512-471-8780
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	10/03/2019
Client Code:	Not reported
Client Name:	Not reported

STUDENT SERVICES BUILDING (Continued) **S125923088**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BU353 Target Property **COWBOYS TAILOR** **EDR Hist Cleaner** **1013784169**
2505 GUADALUPE ST **N/A**
AUSTIN, TX

Site 1 of 5 in cluster BU

Actual: 599 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	COWBOYS TAILOR	CLOTHES PRESSERS AND CLEANERS

BU354 Target Property **COUCH CLEANERS** **EDR Hist Cleaner** **1013777455**
2501 GUADALUPE **N/A**
AUSTIN, TX

Site 2 of 5 in cluster BU

Actual: 599 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1940	COUCH CLEANERS	CLOTHES PRESSERS AND CLEANERS

BU355 Target Property **2412 UNIVERSITY SERVICE** **EDR Hist Auto** **1013773913**
2436 GUADALUPE ST **N/A**
AUSTIN, TX

Site 3 of 5 in cluster BU

Actual: 596 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	2412 UNIVERSITY SERVICE	AUTOMOBILE GARAGES
1929	MITCHELL E W AUTO REPR	AUTOMOBILE REPAIRERS
1929	2412 UNIVERSITY SERVICE	GASOLINE AND OIL SERVICE STATIONS
1935	MITCHELL E W AUTO	AUTOMOBILE REPAIRERS
1935	SERVICE CO	GASOLINE AND OIL SERVICE STATIONS
1947	UNIVERSITY SERVICE CO FILLING S	GASOLINE AND OIL SERVICE STATIONS

2412 UNIVERSITY SERVICE (Continued) **1013773913**

1953 UNIV ERSITY SERV CO GASOLINE STATIONS

BU356 Target Property **WALTER WEBB HALL**
405 W. 25TH STREET
AUSTIN, TX 78705

TX ASBESTOS **S126248840**
N/A

Site 4 of 5 in cluster BU

Actual: 597 ft.

Focus Map: 11

ASBESTOS:

Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/10/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/25/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/17/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

WALTER WEBB HALL (Continued) **S126248840**

Start Date:	03/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/13/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/18/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

WALTER WEBB HALL (Continued) **S126248840**

Certification Statement Date:	02/18/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/03/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/20/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/02/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/10/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/20/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/09/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/03/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/12/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/24/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/26/2020
Notification Number:	2020001423
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/12/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

WALTER WEBB HALL (Continued) **S126248840**

ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/26/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/22/2021
Notification Number:	2021000763
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/17/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/17/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/18/2021
Notification Number:	2021000763
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/04/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET

WALTER WEBB HALL (Continued) **S126248840**

City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/06/2021
Notification Number:	2020007687
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/31/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/31/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/28/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020007687
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

WALTER WEBB HALL (Continued) **S126248840**

High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/28/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL (CP775804)
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/03/2021
Notification Number:	2021000354
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/20/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0

WALTER WEBB HALL (Continued) **S126248840**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/20/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/03/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALTER WEBB HALL
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/29/2021
Notification Number:	2021004920
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Date Report Received:	07/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/16/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALTER WEBB HALL
Address:	405 W. 25TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/30/2021

WALTER WEBB HALL (Continued) **S126248840**

Notification Number:	2021004920
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/15/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

WALTER WEBB HALL (Continued) **S126248840**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BV357 **UNIVERSITY UNITED METHODIST CHURCH** **TX ASBESTOS** **S119159732**
Target **2409 GUADALUPE ST.** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 5 in cluster BV

Actual:
596 ft.

Focus Map:
11

ASBESTOS:

Name:	UNIVERSITY UNITED METHODIST CHURCH
Address:	2409 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/08/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013007185
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/30/2013
Date Routed by Supervisor:	11/08/2013
Date Routed to PSQA:	11/13/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported

UNIVERSITY UNITED METHODIST CHURCH (Continued) **S119159732**

Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BW358 **FOODIES 2** **TX SPILLS** **S111325805**
Target **2400 RIO GRANDE ST** **TX ENF** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 12 in cluster BW

Actual: 596 ft.

Focus Map: 11

SPILLS:

Name:	WAG-A-BAG 24
Address:	Not reported
City,State,Zip:	AUSTIN, TX 78705
Incident Number:	158254
Facility Id:	RN102866217
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	GASOLINE, AUTOMOTIVE OR AVIATION
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	005 - Hazardous Material Minor
Basin Name:	Not reported
Water Affected:	Not reported

FOODIES 2 (Continued) **S111325805**

Amnt Spilled:	0
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Emergency Response
Near City Name:	AUSTIN
Importance Level:	3
Received Date:	08/18/2011
Start Date:	Not reported
Status Date:	10/20/2011
Media Name:	WASTE
Customer:	HAYS CITY CORPORATION
Effect:	GENERAL
Num Complaining:	0
Frequency:	CURRENT
Nature:	OTHER
Watertext:	Not reported
Air Text:	UST
Incident Status:	Closed
Disputed Status:	Not reported
Disputed Date:	08/22/2011
Comments:	No liquid fuel was found so the hold was covered with plastic. On August 19, 2011, Excell Fueling Systems tightness tested the USTs and piping. The USTs and piping passed the tightness tests. Wag-A-Bag 24 was allowed to return the UST system to service. On August 23, 2011, Ms. Stella Ortegon of the TCEQ Austin Regional Office, conducted an investigation of Wag-A-Bag 24 to determine compliance with Title 30 Texas Administrative Code (TAC) Chapter 334 Underground and Aboveground Storage Tanks regulations for the Petroleum Storage Tank (PST) Program.Three violations were cited. The owner/operator failed to file notice of any change or additional information with the agency within 30 days from the date of the occurrence of the change or addition, or within 30 days from the date on which the owner or operator first became aware of the change or addition, as applicable. Specifically, according to TCEQ records, all USTs store gasoline; however, during the investigation, the investigator observed that one of the USTs stores diesel. The owner/operator failed to ensure that a legible tag, label, or marking is permanently applied upon or affixed to either the top of the fill tube or to a nonremovable point in the immediate area of the fill tube for each regulated UST at the facility. The owner/operator failed to install flexible connectors at both ends of each pressurized product or delivery line to provide flexibility and to allow for vertical and horizontal movement in the piping.A Notice of Violation (NOV) letter has been issued as a result of the investigation.
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

FOODIES 2 (Continued) **S111325805**

Name:	WAG-A-BAG 24
Address:	Not reported
City,State,Zip:	AUSTIN, TX 78705
Incident Number:	158254
Facility Id:	RN102866217
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	GASOLINE, AUTOMOTIVE OR AVIATION
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	Not reported
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	005 - Hazardous Material Minor
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	0.00
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Emergency Response
Near City Name:	AUSTIN
Importance Level:	3
Received Date:	08/18/2011
Start Date:	Not reported
Status Date:	10/20/2011
Media Name:	WASTE
Customer:	HAYS CITY CORPORATION
Effect:	GENERAL
Num Complaining:	0
Frequency:	CURRENT
Nature:	OTHER
Watertext:	Not reported
Air Text:	UST
Incident Status:	Closed
Disputed Status:	Not reported
Disputed Date:	08/22/2011
Comments:	No liquid fuel was found so the hold was covered with plastic. On August 19, 2011, Excell Fueling Systems tightness tested the USTs and piping. The USTs and piping passed the tightness tests. Wag-A-Bag 24

FOODIES 2 (Continued) **S111325805**

was allowed to return the UST system to service. On August 23, 2011, Ms. Stella Ortegon of the TCEQ Austin Regional Office, conducted an investigation of Wag-A-Bag 24 to determine compliance with Title 30 Texas Administrative Code (TAC) Chapter 334 Underground and Aboveground Storage Tanks regulations for the Petroleum Storage Tank (PST) Program.

Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

ENFORCEMENT:

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to ensure that a legible tag, label, or marking is permanently applied upon or affixed to either the top of the fill tube or to a nonremovable point in the immediate area of the fill tube for each regulated UST at the facility.
Description 2:	On October 31, 2011, Ms. Ortegon received photos of labeled tanks.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.8(c)(5)(C)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	FOODIES 2

FOODIES 2 (Continued) **S111325805**

Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	REGMAIL
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to ensure that a legible tag, label, or marking is permanently applied upon or affixed to either the top of the fill tube or to a nonremovable point in the immediate area of the fill tube for each regulated UST at the facility.
Description 2:	On October 31, 2011, Ms. Ortegon received photos of labeled tanks.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.8(c)(5)(C)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported

FOODIES 2 (Continued) **S111325805**

Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	REGMAIL
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to file or provide notice of any change or additional information to the agency within 30 days from the date of the occurrence of the change or addition, or within 30 days from the date on which the owner or operator first became aware of the change or addition, as applicable.
Description 2:	On October 31, 2011, Ms. Ortegon received an updated registration form. On November 7, 2011, Ms. Ortegon verified that the facility's registration information was updated.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.7(d)(3)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to file or provide notice of any change or additional information to the agency within 30 days from the date of the occurrence of the change or addition, or within 30 days from the date on which the owner or operator first became aware of the change or addition, as applicable.
Description 2:	On October 31, 2011, Ms. Ortegon received an updated registration form. On November 7, 2011, Ms. Ortegon verified that the facility's

FOODIES 2 (Continued) **S111325805**

	registration information was updated.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.7(d)(3)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	REGMAIL
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to install UL-listed (or agency accepted equivalent listing by Underwriter's Laboratories of Canada (ULC), or Factory Mutual Research Corporation (FMRC)) flexible connectors at both ends of each pressurized product or delivery line to provide flexibility and to allow for vertical and horizontal movement in the piping.
Description 2:	On December 21, 2011, Ms. Ortegon received a copy of the invoice demonstrating that the crimped flex connector and swing joint had been replaced.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.45(c)(3)(B)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported

FOODIES 2 (Continued) **S111325805**

Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102866217
Contact Person For The Reg. Entity:	CLAYTON JOHNSON
Owner/operator Of A Regulated Entity:	HAYS CITY CORPORATION
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	PRESIDENT
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000000950606
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	289,517,462,011,291.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	10/21/2011
Description 1:	Failure to install UL-listed (or agency accepted equivalent listing by Underwriter's Laboratories of Canada (ULC), or Factory Mutual Research Corporation (FMRC)) flexible connectors at both ends of each pressurized product or delivery line to provide flexibility and to allow for vertical and horizontal movement in the piping.
Description 2:	On December 21, 2011, Ms. Ortegon received a copy of the invoice demonstrating that the crimped flex connector and swing joint had been replaced.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.45(c)(3)(B)
Status Of The NOV:	DAPPROVED
Investigation:	950606
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

BW359 **WAG-A-BAG 24** **FINDS** **1011321627**
Target **2400 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 2 of 12 in cluster BW

Actual:
596 ft.

Focus Map:
11

FINDS:
Registry ID: 110034348622

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BW360 **FOODIES 2** **TX COMP HIST** **S123214550**
Target **2400 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 12 in cluster BW

Actual:
596 ft.

Focus Map:
11

COMP HIST:

RN Number:	RN102866217
Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Region:	REGION 11 - AUSTIN
CN Number:	CN605542000
CN Name:	NAAZ 24 BIZ INC
CN Rating:	33.75
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	33.75
Classification 2:	SATISFACTORY
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447190
SIC Code:	1522
Related Number:	38367,38367

RN Number:	RN102866217
Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705-4813
Region:	REGION 11 - AUSTIN
CN Number:	CN602402174
CN Name:	HAYS CITY CORPORATION
CN Rating:	1.45
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	19.29

FOODIES 2 (Continued) **S123214550**

Classification 2:	SATISFACTORY
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	423930
SIC Code:	1521
Related Number:	38367,38367

BW361 **FOODIES NO. 2** **TX RDR** **S127531735**
Target **2400 RIO GRANDE STREET** **N/A**
Property **AUSTIN, TX**

Site 4 of 12 in cluster BW

Actual:
596 ft.

Focus Map:
11

RDR:

RDR ID:	27111
Facility ID:	38367
RN:	Not reported
CN:	Not reported
Name:	FOODIES NO. 2
Address:	2400 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/18/2019
Due Date:	8/17/2019
Tank Owner:	HAYS CITY CORPORATION
Contact Person:	KEVIN LITTLE
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	7/9/2019
Project Manager:	Robin Shaver
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

BW362 **FOODIES 2** **TX UST** **U001271010**
Target **2400 RIO GRANDE ST** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78705** **TX ASBESTOS**
TX Financial Assurance

Site 5 of 12 in cluster BW

Actual:
596 ft.

Focus Map:
11

UST:

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 787054813
AI Number:	38367
Facility Type:	RETAIL
Facility Begin Date:	01/08/1987
Facility Status:	ACTIVE

FOODIES 2 (Continued) **U001271010**

Additional ID:	187378282002256
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	ZAHIR PRASLA,MGR
Contact Organization Name:	FOODIES 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5125760786
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/15/2021
Signature Name/Title On Earliest Reg Form:	DAN KOHL,SAFTEY MGR
Application Received Date On Earliest Reg Form:	05/14/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	757423652018176
Additional ID:	187378282002256
Ai Number:	38367
Operator CN:	CN605542000
Operator Name:	NAAZ 24 BIZ INC
Operator Effective Begin Date:	07/01/2017
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602402174
Owner Last Name:	HAYS CITY CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported

FOODIES 2 (Continued) **U001271010**

Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	327575342003232
Additional ID:	187378282002256
AI Number:	38367
Owner Effective Begin Date:	10/31/2009
State Tax ID:	17418292623
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	69439
Cert ID:	372054
AI Number:	38367
Self Certification Date:	05/15/2022
Signature Name/Title:	DAN KOHL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69439
Cert ID:	355458
AI Number:	38367
Self Certification Date:	05/15/2021
Signature Name/Title:	DAN KOHL SAFTEY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	338320
AI Number:	38367
Self Certification Date:	05/24/2020
Signature Name/Title:	DAN KOHL SAFETY & COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	321219
AI Number:	38367
Self Certification Date:	05/24/2019
Signature Name/Title:	DAN KOHL SAFETY AND COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	305816
AI Number:	38367
Self Certification Date:	06/07/2018
Signature Name/Title:	KEVIN LITTLE OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	286708
AI Number:	38367
Self Certification Date:	04/26/2017
Signature Name/Title:	KEVIN LITTLE OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	269706
AI Number:	38367
Self Certification Date:	05/02/2016
Signature Name/Title:	KEVIN LITTLE SAFETY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	69439
Cert ID:	253229
AI Number:	38367
Self Certification Date:	04/28/2015
Signature Name/Title:	BOB STEHLING OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69439
Cert ID:	237079
AI Number:	38367
Self Certification Date:	04/28/2014
Signature Name/Title:	BOB STEHLING OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69439
Cert ID:	219646
AI Number:	38367
Self Certification Date:	05/08/2013
Signature Name/Title:	CLAYTON P JOHNSON PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	69439
Cert ID:	92785
AI Number:	38367
Self Certification Date:	06/08/2012
Signature Name/Title:	CLAYTON B JOHSON PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92784
AI Number:	38367
Self Certification Date:	05/17/2011
Signature Name/Title:	CLAYTON B JOHNSON PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92783
AI Number:	38367
Self Certification Date:	06/14/2010
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92782
AI Number:	38367
Self Certification Date:	04/23/2009
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92781
AI Number:	38367
Self Certification Date:	04/22/2008
Signature Name/Title:	CLAY JOHNSON PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92780
AI Number:	38367
Self Certification Date:	05/01/2007
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92779
AI Number:	38367
Self Certification Date:	05/29/2006
Signature Name/Title:	TIM RAMSEY V P
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92778
AI Number:	38367
Self Certification Date:	05/29/2005
Signature Name/Title:	TIM RAMSEY VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92777
AI Number:	38367
Self Certification Date:	05/29/2004
Signature Name/Title:	TIM RAMSEY V PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92533
AI Number:	38367
Self Certification Date:	05/29/2003
Signature Name/Title:	TIM RAMSEY VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

FOODIES 2 (Continued) **U001271010**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92532
AI Number:	38367
Self Certification Date:	06/18/2002
Signature Name/Title:	TIM RAMSEY PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	69439
Cert ID:	92531
AI Number:	38367
Self Certification Date:	01/17/2001
Signature Name/Title:	TIM RAMSEY PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101119
Facility ID:	69439
Ai Number:	38367
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

FOODIES 2 (Continued) **U001271010**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	84023
UST ID:	101119
AI Number:	38367
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

FOODIES 2 (Continued) **U001271010**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	10/26/2005

More Self Certification:

Self Cert ID:	14935
Cert ID:	15785
UST Comprt ID:	45814
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15786
UST Comprt ID:	45813
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15787
UST Comprt ID:	45812
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A

FOODIES 2 (Continued) **U001271010**

Self Cert ID:	14935
Cert ID:	15788
UST Comprt ID:	45811
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	246675
UST Comprt ID:	709186
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	264093
UST Comprt ID:	760659
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	280449
UST Comprt ID:	808913
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	297267
UST Comprt ID:	858506
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	313847
UST Comprt ID:	908393
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	331598
UST Comprt ID:	961434
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935

FOODIES 2 (Continued) **U001271010**

Cert ID:	347066
UST Comprt ID:	1008404
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	363616
UST Comprt ID:	1058392
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	381143
UST Comprt ID:	1112075
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15789
UST Comprt ID:	45810
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15790
UST Comprt ID:	45809
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15791
UST Comprt ID:	45808
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15792
UST Comprt ID:	45807
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15793

FOODIES 2 (Continued) **U001271010**

UST Comprt ID:	45806
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	231083
UST Comprt ID:	663412
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15781
UST Comprt ID:	45816
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15782
UST Comprt ID:	45817
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15783
UST Comprt ID:	45818
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15784
UST Comprt ID:	45815
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101120
Facility ID:	69439
Ai Number:	38367

FOODIES 2 (Continued) **U001271010**

Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	84024
UST ID:	101120

FOODIES 2 (Continued) **U001271010**

AI Number:	38367
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	10/26/2005

More Self Certification:

Self Cert ID:	14935
Cert ID:	15785
UST Comprt ID:	45814
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15786
UST Comprt ID:	45813
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15787

FOODIES 2 (Continued) **U001271010**

UST Comprt ID:	45812
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15788
UST Comprt ID:	45811
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	246675
UST Comprt ID:	709186
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	264093
UST Comprt ID:	760659
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	280449
UST Comprt ID:	808913
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	297267
UST Comprt ID:	858506
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	313847
UST Comprt ID:	908393
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	331598
UST Comprt ID:	961434

FOODIES 2 (Continued) **U001271010**

UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	347066
UST Comprt ID:	1008404
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	363616
UST Comprt ID:	1058392
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	381143
UST Comprt ID:	1112075
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15789
UST Comprt ID:	45810
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15790
UST Comprt ID:	45809
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15791
UST Comprt ID:	45808
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15792
UST Comprt ID:	45807
UST ID:	16234

FOODIES 2 (Continued) **U001271010**

AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15793
UST Comprt ID:	45806
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	231083
UST Comprt ID:	663412
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15781
UST Comprt ID:	45816
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15782
UST Comprt ID:	45817
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15783
UST Comprt ID:	45818
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15784
UST Comprt ID:	45815
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000

FOODIES 2 (Continued) **U001271010**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101121
Facility ID:	69439
Ai Number:	38367
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

FOODIES 2 (Continued) **U001271010**

Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	84025
UST ID:	101121
AI Number:	38367
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	10/26/2005
More Self Certification:	
Self Cert ID:	14935
Cert ID:	15785
UST Comprt ID:	45814
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15786
UST Comprt ID:	45813

FOODIES 2 (Continued) **U001271010**

UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15787
UST Comprt ID:	45812
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15788
UST Comprt ID:	45811
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	246675
UST Comprt ID:	709186
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	264093
UST Comprt ID:	760659
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	280449
UST Comprt ID:	808913
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	297267
UST Comprt ID:	858506
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	313847
UST Comprt ID:	908393
UST ID:	16234

FOODIES 2 (Continued) **U001271010**

AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	331598
UST Comprt ID:	961434
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	347066
UST Comprt ID:	1008404
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	363616
UST Comprt ID:	1058392
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	381143
UST Comprt ID:	1112075
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15789
UST Comprt ID:	45810
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15790
UST Comprt ID:	45809
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15791
UST Comprt ID:	45808
UST ID:	16234
AI Number:	38367

FOODIES 2 (Continued) **U001271010**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15792
UST Comprt ID:	45807
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15793
UST Comprt ID:	45806
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	231083
UST Comprt ID:	663412
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15781
UST Comprt ID:	45816
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15782
UST Comprt ID:	45817
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15783
UST Comprt ID:	45818
UST ID:	16234
AI Number:	38367
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14935
Cert ID:	15784
UST Comprt ID:	45815
UST ID:	16234
AI Number:	38367
Tank ID:	2

FOODIES 2 (Continued) **U001271010**

Compartment ID: A

Construction Notification:

NOC ID:	8136
Facility ID:	69439
AI Number:	38367
Application Received Date:	10/10/2005
Scheduled Construction Date:	10/19/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M51010019
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	17806

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	8647
UST ID:	Not reported
NOC ID:	8136
AI Number:	38367
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

FOODIES 2 (Continued) **U001271010**

Email Address: Not reported

Facility Billing Contacts:

Contact Organization Name:	HAYS CITY CORPORATION
Contact Mailing Address (Delivery):	PO BOX 18463
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78760 8463
Phone Number/Ext:	512 6177777/0
Contact Fax Number/Ext:	/
Contact Email Address:	DKOHL@TEXCONOIL.COM
Contact Address Deliverable:	Y
Facility ID:	69439
Additional ID:	187378282002256
Princ ID:	327575342003232
AI Number:	38367
Facility Name:	FOODIES 2
AR Number:	17806
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	DAN KOHL/

HIST UST AUSTIN:

Name:	WAG A BAG #24
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX
Id UST:	623
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	WAG A BAG
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/02/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013

FOODIES 2 (Continued) **U001271010**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WAG A BAG
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/09/2015
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported

FOODIES 2 (Continued) **U001271010**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

FOODIES 2 (Continued) **U001271010**

Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	269875
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2021
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000022654
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	252191
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2020
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000011650
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439

FOODIES 2 (Continued) **U001271010**

Finass ID:	232473
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2019
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top005001070
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	214807
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2018
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	199117
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

FOODIES 2 (Continued) **U001271010**

Financial Assurance Begin Date:	07/12/2017
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	179679
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2016
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	162071
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2015
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	1436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

FOODIES 2 (Continued) **U001271010**

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	144277
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2014
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	128586
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2013
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	108288
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

FOODIES 2 (Continued) **U001271010**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2012
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	6433
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2011
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	51197
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2009
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336

FOODIES 2 (Continued) **U001271010**

Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	51198
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2008
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	69439
Finass ID:	51199
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2007
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705

FOODIES 2 (Continued) **U001271010**

Region:	2
Facility ID:	69439
Finass ID:	51200
AI:	38367
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/1991
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

BW363 **FOODIES 2** **TX CENTRAL REGISTRY** **S126596472**
Target **2400 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 6 of 12 in cluster BW

Actual:
596 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN102866217
Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4813
Status:	ACTIVE
Status Date:	9/13/2002
Customer Number:	CN602402174
Customer Name:	HAYS CITY CORPORATION
Customer Legal Name:	Hays City Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/8/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102866217
Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4813
Status:	ACTIVE
Status Date:	9/13/2002
Customer Number:	CN600887228
Customer Name:	WAG-A-BAG INC
Customer Legal Name:	Wag-A-Bag, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2009

FOODIES 2 (Continued) **S126596472**

Affiliation End Date:	6/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102866217
Name:	FOODIES 2
Address:	2400 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4813
Status:	ACTIVE
Status Date:	9/13/2002
Customer Number:	CN605542000
Customer Name:	NAAZ 24 BIZ INC
Customer Legal Name:	Naaz 24 Biz Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/1/2017
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

BW364 **SCHIEFFERS BEN** **EDR Hist Auto** **1013755037**
Target **701 24TH W** **N/A**
Property **AUSTIN, TX**

Site 7 of 12 in cluster BW

Actual:
593 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	SCHIEFFERS BEN	GASOLINE STATIONS
1962	PETERSONS FRANK	GASOLINE STATIONS

BX365 **B LONGHORN CLNS** **EDR Hist Cleaner** **1013781250**
Target **705 24TH W** **N/A**
Property **AUSTIN, TX**

Site 1 of 4 in cluster BX

Actual:
596 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1962	B LONGHORN CLNS	CLEANERS AND DYERS

BW366 Target Property | **LOONEY L P FILLING**
2323 RIO GRANDE
AUSTIN, TX | **EDR Hist Auto** | **1013773113**
N/A

Site 8 of 12 in cluster BW

Actual: 592 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	LOONEY L P FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	NELLE E H SERV STA	GASOLINE AND OIL SERVICE STATIONS

BY367 Target Property | **CORNERSTONE PLACE APARTMENTS**
2308 RIO GRANDE ST
AUSTIN, TX 78705 | **FINDS** | **1011325499**
N/A

Site 1 of 3 in cluster BY

Actual: 591 ft.
Focus Map: 11

FINDS:
Registry ID: 110034372612

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BY368 Target Property | **GEDR AT UNION ON 24TH**
2308 RIO GRANDE ST
AUSTIN, TX 78705 | **TX TANKS**
TX VCP
TX ASBESTOS | **S123820169**
N/A

Site 2 of 3 in cluster BY

Actual: 591 ft.
Focus Map: 11

TANKS:

Facility ID:	137402
Name:	GEDR AT UNION ON 24TH
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 787055139
Total UST:	Not reported
Additional ID:	577537942021356
AI Number:	92315
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	Not reported
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705

GEDR AT UNION ON 24TH (Continued) **S123820169**

Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	Not reported
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

VCP TCEQ:

Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	REGION 11 - AUSTIN
Facility ID:	371
VCP Record Date:	10/10/1996
Facility Type:	PROPERTY COMMERCIAL
PCA Number:	38281
Project Manager:	MFREW
Phase:	COMPLETED
Acres at Site:	0.83
REM Program:	VCP
RN Number:	RN101055473
Former Facility Type:	Not reported
Site Address Description:	2308 RIO GRANDE
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	10/09/1996
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	11/04/1996
Standards:	PLAN A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	NOT REQUIRED

GEDR AT UNION ON 24TH (Continued) **S123820169**

Air Target COC Class:	Not reported
Date Cashier Check Received:	10/09/1996
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1996-11-04 00:00:00
Soil Target COC Class:	TPH; PETROLEUM (BTEX)
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	371
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	312810
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.32
Longitude:	-97.77

Contact:

REM Program:	VCP
Program ID:	371
RN Number:	RN101055473
CN Number:	CN601634322
CN Name:	GARZA, SA
Role Code:	BILLCONT
Contact Name:	GARZA, RUDY
Contact Title:	Not reported
Organization Name:	S A GARZA AND VIOLA GARZA
Mailing Address:	3302 SOUTHILL CIR
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78703
Contact Telephone:	(512) 476-5901
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	371
RN Number:	RN101055473
CN Number:	CN601634330
CN Name:	GARZA, VIOLA G
Role Code:	BILLCONT
Contact Name:	GARZA, RUDY
Contact Title:	Not reported
Organization Name:	S A GARZA AND VIOLA GARZA
Mailing Address:	3302 SOUTHILL CIR
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78703
Contact Telephone:	(512) 476-5901
Contact Telephone Ext:	0

ASBESTOS:

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/10/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	10/19/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021006543
File Number:	65221
License Status Description:	Paid
Expiration Date:	12/31/2021
Original Date:	09/29/2021
Rank Effective Date:	09/29/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado

GEDR AT UNION ON 24TH (Continued) **S123820169**

Inspection Number:	31799
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/22/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI

GEDR AT UNION ON 24TH (Continued) **S123820169**

Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment

GEDR AT UNION ON 24TH (Continued) **S123820169**

Work Type Flag:	D
Certification Statement Date:	12/22/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/12/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/18/2021
Date Routed by Supervisor:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/18/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/03/2021
Notification Number:	2021006543
ASB Priority:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/18/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/18/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh R Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/21/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh R Hook
Violation:	Not reported
Complaint Date:	12/03/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/21/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07

GEDR AT UNION ON 24TH (Continued) **S123820169**

Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/23/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/22/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/22/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS

GEDR AT UNION ON 24TH (Continued) **S123820169**

Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/29/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/29/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

GEDR AT UNION ON 24TH (Continued) **S123820169**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/03/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

GEDR AT UNION ON 24TH (Continued) **S123820169**

Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/02/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

GEDR AT UNION ON 24TH (Continued) **S123820169**

Inspector Name:	Not reported
Date Report Received:	11/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/02/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/05/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/04/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/12/2021

GEDR AT UNION ON 24TH (Continued) **S123820169**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/29/2021

GEDR AT UNION ON 24TH (Continued) **S123820169**

Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/03/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/29/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	10/22/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/29/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Inspection Number Grade:	Not reported
Name:	CORNERSTON CONDOMINIUMS
Address:	2308 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/19/2021
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	12/03/2021
Notification Number:	2021006543
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	09/29/2021
Certification Statement Phone:	316-305-0593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

GEDR AT UNION ON 24TH (Continued) **S123820169**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BY369 **CORNERSTONE PLACE APARTMENTS** **TX CENTRAL REGISTRY** **S123866638**
Target **2308 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78705**

Site 3 of 3 in cluster BY

Actual:
591 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600614481
Customer Name:	SA GARZA & VIOLA GARZA
Customer Legal Name:	Sa Garza & Viola Garza
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	4/14/2003
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601660285
Customer Name:	CORNERSTONE PLACE
Customer Legal Name:	Cornerstone Place
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

CORNERSTONE PLACE APARTMENTS (Continued) **S123866638**

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601634322
Customer Name:	GARZA, SA
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601634330
Customer Name:	GARZA, VIOLA G
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602883399
Customer Name:	ABASOLO LLC
Customer Legal Name:	Abasolo, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	6/26/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST

CORNERSTONE PLACE APARTMENTS (Continued) **S123866638**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605182286
Customer Name:	ABA SOLO LLC A TEXAS LTD LIABILITY CO
Customer Legal Name:	Aba Solo LLC A Texas Ltd Liability Co
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	6/27/2016
Affiliation End Date:	11/20/2018
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605595735
Customer Name:	ABA SOLO LLL A TEXAS LTD LIABILITY CO
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	11/21/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605967173
Customer Name:	GEDR AT UNION ON 24TH LLC
Customer Legal Name:	GEdR at Union on 24th, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE

CORNERSTONE PLACE APARTMENTS (Continued) **S123866638**

Status Date:	##########
Customer Number:	CN600614481
Customer Name:	SA GARZA & VIOLA GARZA
Customer Legal Name:	Sa Garza & Viola Garza
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	4/14/2003
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600614481
Customer Name:	SA GARZA & VIOLA GARZA
Customer Legal Name:	Sa Garza & Viola Garza
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	4/14/2003
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Regulated Entity Number:	RN101055473
Name:	CORNERSTONE PLACE APARTMENTS
Address:	2308 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5139
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601660285
Customer Name:	CORNERSTONE PLACE
Customer Legal Name:	Cornerstone Place
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2308 RIO GRANDE

Click this hyperlink while viewing on your computer to access
14 additional TX CENTRAL REG: record(s) in the EDR Site Report.

370 Target Property | **PARKING GARAGE**
715 WEST 23RD STREET
AUSTIN, TX 78705 | **TX ASBESTOS** | **S122569722**
N/A

Actual: 593 ft.

Focus Map: 11

ASBESTOS:

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/31/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/03/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

PARKING GARAGE (Continued) **S122569722**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	12/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/03/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

PARKING GARAGE (Continued) **S122569722**

ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/23/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/06/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/18/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

PARKING GARAGE (Continued) **S122569722**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/16/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/23/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	11/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

PARKING GARAGE (Continued) **S122569722**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/18/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/16/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET

PARKING GARAGE (Continued) **S122569722**

City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/10/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/25/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/20/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/30/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

PARKING GARAGE (Continued) **S122569722**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	11/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/25/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/20/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

PARKING GARAGE (Continued) **S122569722**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/30/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3

PARKING GARAGE (Continued) **S122569722**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/25/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	12/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

PARKING GARAGE (Continued) **S122569722**

Date Report Received:	07/30/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/25/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/23/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/31/2018

PARKING GARAGE (Continued) **S122569722**

Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/10/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

PARKING GARAGE (Continued) **S122569722**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	12/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/10/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/23/2018
Client Code:	Not reported

PARKING GARAGE (Continued) **S122569722**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/03/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/27/2018
Certification Statement Phone:	512-260-6202

PARKING GARAGE (Continued) **S122569722**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/18/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/24/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	11/30/2018
Notification Number:	2018005541
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

PARKING GARAGE (Continued) **S122569722**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/27/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	52
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PARKING GARAGE
Address:	715 WEST 23RD STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/08/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

PARKING GARAGE (Continued) **S122569722**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/24/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018005541
File Number:	32778
License Status Description:	Paid
Expiration Date:	12/30/2018
Original Date:	07/06/2018
Rank Effective Date:	07/06/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	11709
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

BZ371 Target Property — **WASH N FOLD INDRY**, **2202 RIO GRANDE ST**, **TRAVIS (County), TX 78705** — **EDR Hist Cleaner** — **1013782306** / **N/A**

Site 1 of 2 in cluster BZ

Actual: 582 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1965	WASH N FOLD LNDRY	LAUNDRIES
1970	WASH N FOLD INDRV	LAUNDRIES
1975	WASH N FOLD INDRY	LAUNDRIES AND DRY CLEANERS

CA372 Target Property — **AUSTIN MAIN POST OFFICE**, **2201 GUADALUPE ST**, **AUSTIN, TX 78712** — **TX CENTRAL REGISTRY** — **S126537297** / **N/A**

Site 1 of 5 in cluster CA

Actual: 577 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101696490
Name:	AUSTIN MAIN POST OFFICE
Address:	2201 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78712-0548
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601245400
Customer Name:	UNITED STATES POSTAL SERVICE
Customer Legal Name:	United States Postal Service
Customer Ownership Type:	FEDERAL GOVERNMENT
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

CA373 Target Property — **AUSTIN MAIN POST OFFICE**, **2201 GUADALUPE ST**, **AUSTIN, TX 78712** — **TX UST** — **U001962590** / **N/A**

Site 2 of 5 in cluster CA

Actual: 577 ft.
Focus Map: 11

UST:

Name:	AUSTIN MAIN POST OFFICE
Address:	2201 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787120548
AI Number:	65994
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	706374152002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	5TH & 6TH & GUADALUPE & SAN ANTONIO

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	RUSSEL STROUD,
Contact Organization Name:	AUSTIN MAIN POST OFFICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2106578483
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/15/1994
Signature Name/Title On Earliest Reg Form:	TIM HERBERT,PROJECT GEOLOGIST
Application Received Date On Earliest Reg Form:	09/20/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601245400
Owner Last Name:	UNITED STATES POSTAL SERVICE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	207672192002150
Additional ID:	706374152002075
AI Number:	65994
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/20/1994
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172085
Facility ID:	98513

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Ai Number:	65994
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/18/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	164386

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST ID:	172085
AI Number:	65994
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330391
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330386
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Cert ID:	118236
UST Comprt ID:	330388
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330393
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683036
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632769
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330389
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118241
UST Comprt ID:	330383
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118232
UST Comprt ID:	330394
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118240

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST Comprt ID:	330384
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330390
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330385
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118230
UST Comprt ID:	330392
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330387
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777698
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	252918
UST Comprt ID:	727221
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777697

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	252918
UST Comprt ID:	727220
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683037
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632768
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118240
UST Comprt ID:	330395
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330396
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330397
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118236
UST Comprt ID:	330399
UST ID:	122677

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330400
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330401
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330402
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118232
UST Comprt ID:	330404
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330403
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330398
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Install Date:	08/31/1987
Tank Registration Date:	09/20/1994
Number of Compartments:	1
Tank Capacity:	500

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172086
Facility ID:	98513
Ai Number:	65994
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/18/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	2
Tank Capacity:	500
UST Comprt ID:	164387
UST ID:	172086
AI Number:	65994
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330391
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330386

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118236
UST Comprt ID:	330388
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330393
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683036
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632769
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330389
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118241
UST Comprt ID:	330383
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118232
UST Comprt ID:	330394
UST ID:	122676

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118240
UST Comprt ID:	330384
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330390
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330385
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118230
UST Comprt ID:	330392
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330387
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777698
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	252918
UST Comprt ID:	727221
UST ID:	122676
AI Number:	65994

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777697
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	252918
UST Comprt ID:	727220
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683037
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632768
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118240
UST Comprt ID:	330395
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330396
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330397
UST ID:	122677
AI Number:	65994
Tank ID:	1

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118236
UST Comprt ID:	330399
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330400
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330401
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330402
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118232
UST Comprt ID:	330404
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330403
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330398
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Install Date:	08/31/1987
Tank Registration Date:	09/20/1994
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172087
Facility ID:	98513
Ai Number:	65994
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	164388
UST ID:	172087
AI Number:	65994
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330391
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330386
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	118236
UST Comprt ID:	330388
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330393
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683036
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632769
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330389
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707
Cert ID:	118241
UST Comprt ID:	330383
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25707

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

Cert ID:	118232
UST Comprt ID:	330394
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118240
UST Comprt ID:	330384
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330390
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330385
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118230
UST Comprt ID:	330392
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330387
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777698
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	252918

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST Comprt ID:	727221
UST ID:	122676
AI Number:	65994
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25707
Cert ID:	269936
UST Comprt ID:	777697
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	252918
UST Comprt ID:	727220
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	237847
UST Comprt ID:	683037
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	220660
UST Comprt ID:	632768
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118240
UST Comprt ID:	330395
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118239
UST Comprt ID:	330396
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118238
UST Comprt ID:	330397

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118236
UST Comprt ID:	330399
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118235
UST Comprt ID:	330400
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118234
UST Comprt ID:	330401
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118233
UST Comprt ID:	330402
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118232
UST Comprt ID:	330404
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118231
UST Comprt ID:	330403
UST ID:	122677
AI Number:	65994
Tank ID:	1
Compartment ID:	B
Self Cert ID:	25707
Cert ID:	118237
UST Comprt ID:	330398
UST ID:	122677

AUSTIN MAIN POST OFFICE (Continued) **U001962590**

AI Number:	65994
Tank ID:	1
Compartment ID:	B

Facility Billing Contacts:

Contact Organization Name:	US POSTAL SERVICE
Contact Mailing Address (Delivery):	1 POST OFFICE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78284 8401
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	98513
Additional ID:	706374152002075
Princ ID:	207672192002150
AI Number:	65994
Facility Name:	AUSTIN MAIN POST OFFICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

---

374 **HODGES CLEANERS** **EDR Hist Cleaner** **1013787283**
Target **107 21ST E** **N/A**
Property **AUSTIN, TX**

EDR Hist Cleaner

Actual:
557 ft.

Year:	Name:	Type:
1935	HODGES CLEANERS	CLOTHES PRESSERS AND CLEANERS

Focus Map:
11

CB375 **THE SHOPS AT DOBIE CENTER** **TX ASBESTOS** **S119158771**
Target **2021 GUADALUPE SUITE. 268** **N/A**
Property **AUSTIN, TX 78705**

Site 1 of 11 in cluster CB

Actual:
568 ft.

Focus Map:
11

ASBESTOS:

Name:	THE SHOPS AT DOBIE CENTER
Address:	2021 GUADALUPE SUITE. 268
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/08/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2014004785
ASB Priority:	Low
PIF State:	Not reported

THE SHOPS AT DOBIE CENTER (Continued) **S119158771**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/10/2014
Date Routed by Supervisor:	10/30/2014
Date Routed to PSQA:	10/31/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

THE SHOPS AT DOBIE CENTER (Continued) **S119158771**

Results: Not reported
Inspection Number Grade: Not reported

CB376 Target Property | **TARGET STORE T3250**
2021 2021 GUADALUPE ST
AUSTIN, TX 78705 | **RCRA-SQG** | **1023969152**
TXR000084233

Site 2 of 11 in cluster CB

Actual: 568 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20220531
Handler Name:	Target Store T3250
Handler Address:	2021 GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705-5654
EPA ID:	TXR000084233
Contact Name:	STEVE MUSSER
Contact Address:	PO BOX 111
Contact City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Contact Telephone:	800-587-2228
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 111
Mailing City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner Name:	Target Corporation
Owner Type:	Private
Operator Name:	Target Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

TARGET STORE T3250 (Continued) **1023969152**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220607
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene

TARGET STORE T3250 (Continued) **1023969152**

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20170817
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20170817
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20170817
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20170817

TARGET STORE T3250 (Continued) **1023969152**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20170817
Handler Name: TARGET STORE T3250	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20220531
Handler Name: TARGET STORE T3250	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	45221
NAICS Description:	DEPARTMENT STORES
NAICS Code:	452210
NAICS Description:	DEPARTMENT STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CB377 Target Property | **TARGET STORE T3250**
2021 2021 GUADALUPE ST
AUSTIN, TX 78705 | **FINDS** | **1024037399**
ECHO | **N/A**

Site 3 of 11 in cluster CB

Actual: 568 ft.
Focus Map: 11

FINDS:
Registry ID: 110070158146

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024037399
Registry ID:	110070158146
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070158146
Name:	TARGET STORE T3250
Address:	2021 2021 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705

CB378 Target Property | **GINNYS COPYING SERVICE**
2021 GUADALUPE ST # 414
AUSTIN, TX 78705 | **TX ASBESTOS**
TX Ind. Haz Waste | **S102749727**
N/A

Site 4 of 11 in cluster CB

Actual: 568 ft.
Focus Map: 11

ASBESTOS:

Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	12/08/2020
Notification Number:	2020007041
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/07/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/08/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	12/07/2020
Notification Number:	2020007041
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/20/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/07/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/03/29
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/29/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022001679
File Number:	69845
License Status Description:	Current

GINNYS COPYING SERVICE (Continued) **S102749727**

Expiration Date:	03/29/2022
Original Date:	03/09/2022
Rank Effective Date:	03/09/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	31950
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	09/09/2020
Notification Number:	2020005334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/09/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4

GINNYS COPYING SERVICE (Continued) **S102749727**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	09/11/2020
Notification Number:	2020005334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/28/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/28/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	09/11/2020
Notification Number:	2020005334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/21/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/21/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705

GINNYS COPYING SERVICE (Continued) **S102749727**

Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/30/2022
Notification Number:	2022004748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/05/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	575
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/15/2022
Notification Number:	2022004748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/29/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	31
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

GINNYS COPYING SERVICE (Continued) **S102749727**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2022
Notification Number:	2022004748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement

GINNYS COPYING SERVICE (Continued) **S102749727**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/12/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	575
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2022
Notification Number:	2022004748
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/15/2022

GINNYS COPYING SERVICE (Continued) **S102749727**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/15/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	575
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/03/2022
Notification Number:	2022004748

GINNYS COPYING SERVICE (Continued) **S102749727**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/15/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	06/19/2022
Notification Number:	2022003733
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/03/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/03/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	06/18/2022
Client Code:	Not reported
Client Name:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/10/2023
Notification Number:	2022008671
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/20/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/20/2023
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N

GINNYS COPYING SERVICE (Continued) **S102749727**

Region:	07
Priority:	HIGH
ARU:	48
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/30/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/20/2023
Notification Number:	2022008671
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/28/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	48
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/09/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/27/2023
Notification Number:	2022008671
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/06/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/06/2023
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	48
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/16/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/03/2023
Notification Number:	2022008671
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/13/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/13/2023
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	48
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/23/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/13/2023
Notification Number:	2022008671
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/19/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/19/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	48
Is this a phased abatement project?:	N
Ordered:	N

GINNYS COPYING SERVICE (Continued) **S102749727**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/02/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020007604
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/10/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/24/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AIRCO DOBIE PROJECT
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020007604
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/18/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/18/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/19/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jimmy Stafford

GINNYS COPYING SERVICE (Continued) **S102749727**

Violation:	Not reported
Complaint Date:	03/29/2022
Notification Number:	2022001679
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/29/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/30/2022
Notification Number:	2022001679
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/22/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/22/2022
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos

GINNYS COPYING SERVICE (Continued) **S102749727**

Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOBIE TWENTY21
Address:	2021 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/23/2022
Notification Number:	2022001679
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A

GINNYS COPYING SERVICE (Continued) **S102749727**

Certification Statement Date:	03/09/2022
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	GINNYS COPYING SERVICE
Address:	2021 GUADALUPE ST # 414
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	66204
Registration Initial Notification Date:	07/27/2001
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD063078984
Primary NAICS Code:	Not reported
Status Change Date:	20010727
Land Type:	PRIVATE
Description of Facility Site Location:	2021 Guadalupe St, No 414, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0

GINNYS COPYING SERVICE (Continued) **S102749727**

Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	ONETOUCHPOINT SOUTHWEST CORP
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	2201 GUADALUPE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787120548
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21498
Site Owner Tax ID:	741765538
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	ONETOUCHPOINT SOUTHWEST CORP
Operator Address:	2201 GUADALUPE ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78712
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17417655382
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ONETOUCHPOINT SOUTHWEST CORP
Owner Mailing Address:	2201 GUADALUPE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78712
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17417655382
Owner Bankruptcy Code:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2201 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78712
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2201 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78712
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	2201 GUADALUPE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78712
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Name:	TARGET STORE T3250
Address:	2021 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	96801
Registration Initial Notification Date:	08/17/2017
Registration Last Amendment Date:	05/31/2022
EPA Identification:	TXR000084233
Primary NAICS Code:	452210
Status Change Date:	20170817
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0

GINNYS COPYING SERVICE (Continued) **S102749727**

Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TARGET CORPORATION
Contact Name:	STEVE MUSSER
Contact Telephone Number:	800-5872228
Mailing Address:	PO BOX 111
Mailing Address2:	Not reported
Mailing City,State,Zip:	MINNEAPOLIS, MN 554400111
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	132140
Site Owner Tax ID:	410215170
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220531
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TARGET CORPORATION
Operator Address:	PO BOX 111
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	MINNEAPOLIS, MN 55440
Operator Country:	UNITED STA
Operator Telephone:	1-800-5872228
Operator Fax Number:	Not reported
Operator Email:	POC@TARGET.COM
Operator Business Type:	Corporation
Operator Tax ID:	14102151702
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TARGET CORPORATION
Owner Mailing Address:	PO BOX 111
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	MINNEAPOLIS, MN 55440
Owner Country:	UNITED STA
Owner Telephone:	1-800-5872228
Owner Fax:	Not reported
Owner Email Address:	POC@TARGET.COM
Owner Business Type:	Corporation

GINNYS COPYING SERVICE (Continued) **S102749727**

Owner Tax ID:	14102151702
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	200
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	WASTE STORAGE AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20170817
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	PO BOX 111
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	MINNEAPOLIS, MN 55440
Contact Phone:	1-800-5872228
Contact Fax:	Not reported
Contact Email:	POC@TARGET.COM

Contact Name:	STEVE MUSSER
Contact Title:	COMPLIANCE DIRECTOR
Contact Role:	PRICONT
Contact Address:	PO BOX 111
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	MINNEAPOLIS, MN 55440
Contact Phone:	1-800-5872228
Contact Fax:	Not reported
Contact Email:	POC@TARGET.COM

Ind. Haz Waste:

Waste ID:	394280
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001801H

GINNYS COPYING SERVICE (Continued) **S102749727**

Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	AEROSOLS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452210
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395714
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

GINNYS COPYING SERVICE (Continued) **S102749727**

Waste ID:	395716
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE SOLIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395718
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acid (Corrosive) Liquid
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACID CORROSIVE LIQ
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

GINNYS COPYING SERVICE (Continued) **S102749727**

Waste ID:	395723
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acid (Corrosive) Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACID CORROSIVE SOL
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395725
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Basic (Corrosive) Liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC CORROSIVE LI
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395726
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007319H
Waste Code Status:	ACTIVE
Waste Form:	319

GINNYS COPYING SERVICE (Continued) **S102749727**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Basic (Corrosive) Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC CORROSIVE SO
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395727
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizer Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZER SOLIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395728
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizer Liquids
Standard Industrial Code:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZER LIQUIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395730
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395731
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Liquids

GINNYS COPYING SERVICE (Continued) **S102749727**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC LIQUIDS
Primary NAICS Code:	452112
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395732
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Propane and Lighters
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PROPANE AND LIGHTERS
Primary NAICS Code:	452112
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395733
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

GINNYS COPYING SERVICE (Continued) **S102749727**

Generators Waste Description:	P-List Pharmaceuticals
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	P-LIST PHARMACEUTICA
Primary NAICS Code:	452112
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395734
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury Containing Waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HG CONTAINING WASTE
Primary NAICS Code:	452112
EPA Waste Form Code:	W320
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395735
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Batteries Lead Acid
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1

GINNYS COPYING SERVICE (Continued) **S102749727**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BATTERIES LEAD ACID
Primary NAICS Code:	452112
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	395736
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023209H
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint and/or paint related materials
Standard Industrial Code:	Not reported
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PAINT
Primary NAICS Code:	452112
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

GINNYS COPYING SERVICE (Continued) **S102749727**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-800-5872228 x0
Mailing Address:	PO BOX 111
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MINNEAPOLIS, MN 55440
AR Number:	0000315309
Principal Name:	TARGET CORPORATION
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-800-5872228 x0
Mailing Address:	PO BOX 111
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MINNEAPOLIS, MN 55440
AR Number:	0000315309
Principal Name:	TARGET CORPORATION
Attention Name:	Not reported
Attention Suffix:	NWG

CB379 Target Property | **GINNYS COPYING SERVICE**
2021 GUADALUPE ST NO 414
AUSTIN, TX 78712 | **RCRA NonGen / NLR**
FINDS
ECHO | **1000323815**
TXD063078984

Site 5 of 11 in cluster CB

Actual: 568 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Ginnys Copying Service
Handler Address:	GUADALUPE ST NO 414
Handler City,State,Zip:	AUSTIN, TX 78712
EPA ID:	TXD063078984
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	GUADALUPE ST
Contact City,State,Zip:	AUSTIN, TX 78712
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE ST
Mailing City,State,Zip:	AUSTIN, TX 78712
Owner Name:	Ginnys Copying Service
Owner Type:	Private
Operator Name:	Ginnys Copying Service

GINNYS COPYING SERVICE (Continued) **1000323815**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: VIRGINIA GEERY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

GINNYS COPYING SERVICE (Continued) **1000323815**

Owner/Operator Name: GINNYS COPYING SERVICE
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 2201 GUADALUPE ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GINNYS COPYING SERVICE
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 2201 GUADALUPE ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800702
Handler Name: GINNYS COPYING SVC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: GINNYS COPYING SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32311
NAICS Description: PRINTING

NAICS Code: 561439
NAICS Description: OTHER BUSINESS SERVICE CENTERS (INCLUDING COPY SHOPS)

GINNYS COPYING SERVICE (Continued) **1000323815**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005056946

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000323815
Registry ID:	110005056946
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005056946
Name:	GINNYS COPYING SERVICE
Address:	2021 GUADALUPE ST NO 414
City,State,Zip:	AUSTIN, TX 78712

CB380 Target Property **GINNYS COPYING SERVICE**
2021 GUADALUPE ST # 414
AUSTIN, TX 78705

TX CENTRAL REGISTRY **S126522147**
N/A

Site 6 of 11 in cluster CB

Actual: 568 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101465151
Name:	GINNYS COPYING SERVICE
Address:	2021 GUADALUPE ST # 414
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5654
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600758908
Customer Name:	ONETOUCHPOINT SOUTHWEST CORP
Customer Legal Name:	Onetouchpoint Southwest Corp.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2021 GUADALUPE ST, NO 414, AUSTIN, TX

Regulated Entity Number: RN101465151

GINNYS COPYING SERVICE (Continued) **S126522147**

Name:	GINNYS COPYING SERVICE
Address:	2021 GUADALUPE ST # 414
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5654
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600758908
Customer Name:	ONETOUCHPOINT SOUTHWEST CORP
Customer Legal Name:	Onetouchpoint Southwest Corp.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2021 GUADALUPE ST, NO 414, AUSTIN, TX

CB381 Target Property | **TARGET STORE T3250**
2021 GUADALUPE ST
AUSTIN, TX 78705 | **TX CENTRAL REGISTRY** | **S126923227**
N/A

Site 7 of 11 in cluster CB

Actual: 568 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN109918276
Name:	TARGET STORE T3250
Address:	2021 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5654
Status:	ACTIVE
Status Date:	2017-08-23
Customer Number:	CN601672397
Customer Name:	TARGET CORPORATION
Customer Legal Name:	Target Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2017-08-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	452112
Primary NAICS Industry Type Description:	Discount Department Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN109918276
Name:	TARGET STORE T3250
Address:	2021 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5654
Status:	ACTIVE
Status Date:	8/23/2017
Customer Number:	CN601672397
Customer Name:	TARGET CORPORATION
Customer Legal Name:	Target Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/17/2017
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	452112
Primary NAICS Industry Type Description:	Discount Department Stores

TARGET STORE T3250 (Continued) **S126923227**

Physical Location Description: Not reported

Regulated Entity Number: RN109918276
Name: TARGET STORE T3250
Address: 2021 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-5654
Status: ACTIVE
Status Date: 8/23/2017
Customer Number: CN601672397
Customer Name: TARGET CORPORATION
Customer Legal Name: Target Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/17/2017
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 452112
Primary NAICS Industry Type Description: Discount Department Stores
Physical Location Description: Not reported

Regulated Entity Number: RN109918276
Name: TARGET STORE T3250
Address: 2021 GUADALUPE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-5654
Status: ACTIVE
Status Date: 8/23/2017
Customer Number: CN601672397
Customer Name: TARGET CORPORATION
Customer Legal Name: Target Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/17/2017
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 452112
Primary NAICS Industry Type Description: Discount Department Stores
Physical Location Description: Not reported

CC382 **CITYVILLE AT PEARL** **FINDS** **1011346174**
Target **706 W MLK JR BLVD** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 2 in cluster CC

Actual:
589 ft.

Focus Map:
11

FINDS:
Registry ID: 110034670737

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

CITYVILLE AT PEARL (Continued) **1011346174**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CC383 Target Property | **CITYVILLE AT PEARL**
706 W MLK JR BLVD
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S126752057**
N/A

Site 2 of 2 in cluster CC

Actual: 589 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN105055438
Name:	CITYVILLE AT PEARL
Address:	706 W MLK JR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1109
Status:	ACTIVE
Status Date:	2006-09-15
Customer Number:	CN603093089
Customer Name:	CITYVILLE AT PEARL LP
Customer Legal Name:	Cityville at Pearl, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2006-07-20
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105055438
Name:	CITYVILLE AT PEARL
Address:	706 W MLK JR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1109
Status:	ACTIVE
Status Date:	2006-09-15
Customer Number:	CN603093089
Customer Name:	CITYVILLE AT PEARL LP
Customer Legal Name:	Cityville at Pearl, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2006-07-20
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105055438
Name:	CITYVILLE AT PEARL
Address:	706 W MLK JR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1109
Status:	ACTIVE
Status Date:	2006-09-15
Customer Number:	CN603093089
Customer Name:	CITYVILLE AT PEARL LP
Customer Legal Name:	Cityville at Pearl, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2006-07-20

CITYVILLE AT PEARL (Continued) **S126752057**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

CB384 Target Property **CUTLERS MOTOR CO** **EDR Hist Auto** **1013759987**
2015 GUADALUPE ST **N/A**
AUSTIN, TX

Site 8 of 11 in cluster CB

Actual: 568 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1958	CUTLERS MOTOR CO	AUTOMOBILE REPAIRING
1962	CUTLERS MOTOR CO	AUTOMOBILE REPAIRING

CD385 Target Property **FORMER UT SHELL** **TX RDR** **S127528357**
1901 GUADALUPE ST **N/A**
AUSTIN, TX

Site 1 of 15 in cluster CD

Actual: 566 ft. RDR:

Focus Map: 11

RDR ID:	22804
Facility ID:	26119
RN:	Not reported
CN:	Not reported
Name:	FORMER UT SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/24/2015
Due Date:	6/23/2015
Tank Owner:	THE UNIVERSITY OF TX AUSTIN
Contact Person:	IREZAMA ANDERSON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/18/2015
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CD386	**EXXON SHOP 67450**	**RCRA NonGen / NLR**	**1004785568**
Target	**1901 GUADALUPE**	**FINDS**	**TXD988031902**
Property	**AUSTIN, TX 78705**	**ECHO**	

Site 2 of 15 in cluster CD

Actual: 566 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	GUADALUPE
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TXD988031902
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 2180
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Telephone:	713-656-7709
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2180
Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

EXXON SHOP 67450 (Continued) **1004785568**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON CO USA	
Legal Status:	Private
Date Became Current:	Not reported

EXXON SHOP 67450 (Continued) **1004785568**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4415
Owner/Operator City,State,Zip:	HOUSTON, TX 77210
Owner/Operator Telephone:	713-656-7761
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19910401
Handler Name: EXXON CO USA #67450	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name: EXXON MOBIL CORPORATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

EXXON SHOP 67450 (Continued) **1004785568**

Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920922
Handler Name: EXXON CO. USA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005132356

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations,

EXXON SHOP 67450 (Continued) **1004785568**

authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004785568
Registry ID:	110005132356
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005132356
Name:	EXXON SHOP 67450
Address:	1901 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705

CD387 Target Property **EXXON SHOP 67450**
1901 GUADALUPE ST
AUSTIN, TX 78705

TX Ind. Haz Waste **S102757841**
N/A

Site 3 of 15 in cluster CD

Actual: 566 ft.

Focus Map: 11

Ind. Haz Waste:

Name:	EXXON SHOP 67450
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	77156
Registration Initial Notification Date:	06/28/1991
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988031902
Primary NAICS Code:	Not reported
Status Change Date:	19910628
Land Type:	PRIVATE
Description of Facility Site Location:	1901 Guadalupe, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6567709
Mailing Address:	PO BOX 2180
Mailing Address2:	ROOM 2753X
Mailing City,State,Zip:	HOUSTON, TX 772522180
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31464
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101

EXXON SHOP 67450 (Continued) **S102757841**

Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 2180
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77252
Operator Country:	UNITED STA
Operator Telephone:	1-713-6567709
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 2180
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Country:	UNITED STA
Owner Telephone:	1-713-6567709
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported

EXXON SHOP 67450 (Continued) **S102757841**

Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	WASTE ADMINISTRATOR
Contact Role:	PRICONT
Contact Address:	PO BOX 2180
Contact Address 2:	ROOM 2753X
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4415
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HOUSTON, TX 77210
AR Number:	0000309102

EXXON SHOP 67450 (Continued) **S102757841**

Principal Name:	EXXON MOBIL CORPORATION
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4415
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HOUSTON, TX 77210
AR Number:	0000309102
Principal Name:	EXXON MOBIL CORPORATION
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4415
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HOUSTON, TX 77210
AR Number:	0000309102
Principal Name:	EXXON MOBIL CORPORATION
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4415
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HOUSTON, TX 77210
AR Number:	0000309102
Principal Name:	EXXON MOBIL CORPORATION
Attention Name:	Not reported
Attention Suffix:	NWG

CD388 **U T SHELL** **TX LPST** **U001260123**
Target **1901 GUADALUPE ST** **TX UST** **N/A**
Property **AUSTIN, TX 78705** **TX HIST UST**
TX Financial Assurance
Site 4 of 15 in cluster CD **TX RDR**

Actual:
566 ft.

Focus Map:
11

LPST:

Name:	EXXON 67450
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0026119
LPST Id:	111047
Facility Location:	1901 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/20/1996
Entered Date:	05/22/1996
Reported Date:	05/20/1996
Closure Date:	07/27/2005
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS

U T SHELL (Continued) **U001260123**

Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/1P/1
Coordinators RPR:	ML2
Responsible Party Name:	Not reported
Responsible Party Contact:	DEBBIE HUNTER
Responsible Party Address:	800 BELL ST STE 2789M
Responsible Party City,St,Zip:	HOUSTON, TX 77002 7426
Responsible Party Telephone:	713/656-2312
Reported Date:	05/20/1996
Case Start Date:	07/27/2005
Reference Number:	RN101474179
Project Manager:	ML2

UST:

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787055606
AI Number:	26119
Facility Type:	RETAIL
Facility Begin Date:	05/08/1986
Facility Status:	INACTIVE
Additional ID:	618606822002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	MANSOOR HASSAN,PARTNER
Contact Organization Name:	U T SHELL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124225834
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,E SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	456486862005105
Additional ID:	618606822002175
Ai Number:	26119
Operator CN:	CN602822983
Operator Name:	NORTH DALLAS PETROLEUM LP

U T SHELL (Continued) **U001260123**

Operator Effective Begin Date:	12/17/2004
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	FAZIL MALIK/
Contact Organization Name:	NORTH DALLAS PETROLEUM LP
Contact Mailing Address (Delivery):	17171 PARK ROW STE 295
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON TX 77084-5640
Contact Phone Country Code:	1
Contact Phone Area Code:	281
Contact Phone Number:	4929555
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602822983
Owner Last Name:	NORTH DALLAS PETROLEUM LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	17171 PARK ROW STE 295
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	HOUSTON
Contact Mailing State:	TX
Contact Mailing Zip:	77084
Contact Mailing Zip5:	5640
Contact Phone Number/Ext:	1 281 4929555/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	456486862005105
Additional ID:	618606822002175
AI Number:	26119
Owner Effective Begin Date:	12/17/2004
State Tax ID:	17524549445
Contact Role:	OWNCON
Contact Name/Title:	FAZIL MALIK/
Contact Organization Name:	NORTH DALLAS PETROLEUM LP

Self Certification:

Self Cert ID:	47986
Cert ID:	34885
AI Number:	26119
Self Certification Date:	03/21/2011
Signature Name/Title:	FAZIL MALIK PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

U T SHELL (Continued) **U001260123**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34884
AI Number:	26119
Self Certification Date:	01/18/2010
Signature Name/Title:	FAZIL MALIK PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34883
AI Number:	26119
Self Certification Date:	01/23/2009
Signature Name/Title:	MEAGAN BUFKIN OFFICE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34882
AI Number:	26119
Self Certification Date:	01/03/2008
Signature Name/Title:	FAZIL MALIK PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

U T SHELL (Continued) **U001260123**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34881
AI Number:	26119
Self Certification Date:	01/29/2007
Signature Name/Title:	MANSOON MASSON PARTNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34880
AI Number:	26119
Self Certification Date:	01/23/2006
Signature Name/Title:	MANSOOR HASSAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34879
AI Number:	26119
Self Certification Date:	03/10/2005
Signature Name/Title:	FRANK MALIK PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

U T SHELL (Continued) **U001260123**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34878
AI Number:	26119
Self Certification Date:	03/12/2004
Signature Name/Title:	ERIC M. MCPHEE CMS PERMITTING MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34630
AI Number:	26119
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34629
AI Number:	26119
Self Certification Date:	03/12/2002
Signature Name/Title:	WENDY SALAS PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

U T SHELL (Continued) **U001260123**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47986
Cert ID:	34628
AI Number:	26119
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67334
Facility ID:	47986
Ai Number:	26119
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/16/2011
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

U T SHELL (Continued) **U001260123**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	36618
UST ID:	67334
AI Number:	26119
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

U T SHELL (Continued) **U001260123**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/12/1988

Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67335
Facility ID:	47986
Ai Number:	26119
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/16/2011
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

U T SHELL (Continued) **U001260123**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3A
Tank Capacity:	10000
UST Comprt ID:	36619
UST ID:	67335
AI Number:	26119
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N

U T SHELL (Continued) **U001260123**

SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/12/1988

Install Date:	01/01/1962
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67329
Facility ID:	47986
Ai Number:	26119
Tank Id:	1B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

U T SHELL (Continued) **U001260123**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1B
Tank Capacity:	8000
UST Comprt ID:	36613
UST ID:	67329
AI Number:	26119
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

U T SHELL (Continued) **U001260123**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67333
Facility ID:	47986
Ai Number:	26119
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/16/2011
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

U T SHELL (Continued) **U001260123**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	12000
UST Comprt ID:	36617
UST ID:	67333
AI Number:	26119
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/12/1988

Install Date:	01/01/1962
Tank Registration Date:	05/08/1986
Number of Compartments:	1

U T SHELL (Continued) **U001260123**

Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67331
Facility ID:	47986
Ai Number:	26119
Tank Id:	3B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

U T SHELL (Continued) **U001260123**

Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3B
Tank Capacity:	6000
UST Comprt ID:	36615
UST ID:	67331
AI Number:	26119
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67332
Facility ID:	47986
Ai Number:	26119
Tank Id:	2B

U T SHELL (Continued) **U001260123**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2B
Tank Capacity:	8000
UST Comprt ID:	36616
UST ID:	67332
AI Number:	26119

U T SHELL (Continued) **U001260123**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67330
Facility ID:	47986
Ai Number:	26119
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

U T SHELL (Continued) **U001260123**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	36614
UST ID:	67330
AI Number:	26119
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

U T SHELL (Continued) **U001260123**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	3619
Facility ID:	47986
AI Number:	26119
Application Received Date:	12/15/2011
Scheduled Construction Date:	12/27/2011
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported

U T SHELL (Continued) **U001260123**

Owner AR At Time Of Construction: 62691
General Desc Of Prop Construct: REMOVAL OF UST SYSTEM DUE TO PROPERTY SALE. *REQUEST WAIVER OF 30 DAY NOTICE*

Facility Billing Contacts:

Contact Organization Name:	NORTH DALLAS PETROLEUM LP
Contact Mailing Address (Delivery):	17171 PARK ROW STE 295
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77084 5640
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47986
Additional ID:	618606822002175
Princ ID:	456486862005105
AI Number:	26119
Facility Name:	U T SHELL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KAREN MENDEZ/

HIST UST AUSTIN:

Name:	UT SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	85
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	2176
AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 281 7528000
Policy Number:	04-TO-00076239
Coverage Amount:	1000000
Coverage Expiration Date:	03/15/2012

U T SHELL (Continued) **U001260123**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	31556
AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 281 7528000
Policy Number:	04-TO-00069844
Coverage Amount:	1000000
Coverage Expiration Date:	03/15/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	31557
AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 281 7528000
Policy Number:	04TO00067395
Coverage Amount:	1000000
Coverage Expiration Date:	03/15/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	31558

U T SHELL (Continued) **U001260123**

AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 281 7528000
Policy Number:	04TO00065318
Coverage Amount:	1000000
Coverage Expiration Date:	03/15/2008
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	31559
AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	47986
Finass ID:	31560
AI:	26119
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992

U T SHELL (Continued) **U001260123**

Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	20238
Facility ID:	26119
RN:	Not reported
CN:	Not reported
Name:	U T SHELL
Address:	1901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/23/2012
Due Date:	3/23/2012
Tank Owner:	NORTH DALLAS PETROLEUM LP
Contact Person:	FAZIL MALIK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/16/2012
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	111047
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/16/2012
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CD389 **EXXON SHOP GASOLINE ST** **EDR Hist Auto** **1013763370**
Target **1901 GUADALUPE ST** **N/A**
Property **TRAVIS (County), TX 78705**

Site 5 of 15 in cluster CD

Actual: EDR Hist Auto
566 ft.

Focus Map:
11

Year:	Name:	Type:
1935	HUMBLE OIL & REFG	GASOLINE AND OIL SERVICE STATIONS
1958	BELLOTTE HUMBLE	GASOLINE STATIONS
1965	KING HUMBLE SERVICE GAS	GASOLINE STATIONS
1969	KING BOB ENCO PRODUCTS	Gasoline Service Stations
1970	KING HUMBLE SERVICE	GASOLINE STATIONS
1970	KING BOB ENCO PRODUCTS	Gasoline Service Stations
1971	KING BOB ENCO PRODUCTS	Gasoline Service Stations
1972	KING BOB ENCO PRODUCTS	Gasoline Service Stations
1973	KING BOB EXXON PRODUCTS	Gasoline Service Stations
1974	KING BOB EXXON PRODUCTS	Gasoline Service Stations

EXXON SHOP GASOLINE ST (Continued) **1013763370**

1975	KING BOB EXXON SERVICE	GASOLINE STATIONS
1975	KING BOB EXXON PRODUCTS	Gasoline Service Stations
1976	KING BOB EXXON PRODUCTS	Gasoline Service Stations
1977	KING BOB SERVICE STATION	Gasoline Service Stations
1977	KING BOB EXXON PRODUCTS	Gasoline Service Stations
1978	KING BOB SERVICE STATION	Gasoline Service Stations
1979	KING BOB SERVICE STATION	Gasoline Service Stations
1980	KING BOB EXXON SERVICE	GASOLINE STATIONS
1980	KING BOB SERVICE STATION	Gasoline Service Stations
1982	KING BOB SERVICE STATION	Gasoline Service Stations
1983	KING BOB SERVICE STATION	Gasoline Service Stations
1984	KING BOB EXXON SERVICE	GASOLINE STATIONS
1985	KING BOB SERVICE STATION	Gasoline Service Stations
1986	KING BOB SERVICE STATION	Gasoline Service Stations
1987	KING BOB SERVICE STATION	Gasoline Service Stations
1988	KING BOB SERVICE STATION	Gasoline Service Stations
1988	MIKE WALKER EXXON	Gasoline Service Stations
1989	MIKE WALKER EXXON	Gasoline Service Stations
1990	EXXON SHOP GASOLINE ST	GASOLINE STATIONS
1990	MIKE WALKER EXXON	Gasoline Service Stations
1991	KAHN NAEEM	Gasoline Service Stations, NEC
1992	MIKE WALKER EXXON	Gasoline Service Stations
1992	KAHN NAEEM	Gasoline Service Stations, NEC
1993	MIKE WALKER EXXON	Gasoline Service Stations
1993	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1994	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1995	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1996	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1997	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1998	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
1999	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
2000	WADIWALLA MOHAMED	Gasoline Service Stations, NEC
2004	UT EXXON STATION 67450	Gasoline Service Stations
2005	UT EXXON STATION 67450	Gasoline Service Stations
2005	UT SHELL	Gasoline Service Stations
2006	UT SHELL	Gasoline Service Stations
2006	UT EXXON STATION 67450	Gasoline Service Stations
2007	UT SHELL	Gasoline Service Stations
2007	UT EXXON STATION 67450	Gasoline Service Stations
2008	UT EXXON STATION 67450	Gasoline Service Stations
2008	UT SHELL	Gasoline Service Stations
2009	UT SHELL	Gasoline Service Stations
2010	UT SHELL	Gasoline Service Stations
2011	UT SHELL	Gasoline Service Stations

CD390 **ERNS** **2000548349**
Target Property **1901 GUDALPE ST** **N/A**
AUSTIN, TX

Site 6 of 15 in cluster CD

Actual:
566 ft.

Focus Map:
11

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

CD391 Target Property | **U T SHELL**
1901 GUADALUPE ST
AUSTIN, TX 78705 | **TX CENTRAL REGISTRY** | **S126522692**
N/A

Site 7 of 15 in cluster CD

Actual: 566 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602822983
Customer Name:	NORTH DALLAS PETROLEUM LP
Customer Legal Name:	North Dallas Petroleum LP
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/17/2004
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

U T SHELL (Continued) **S126522692**

Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602822983
Customer Name:	NORTH DALLAS PETROLEUM LP
Customer Legal Name:	North Dallas Petroleum LP
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/17/2004
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179

U T SHELL (Continued) **S126522692**

Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602822983
Customer Name:	NORTH DALLAS PETROLEUM LP
Customer Legal Name:	North Dallas Petroleum LP
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/17/2004
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported

U T SHELL (Continued) **S126522692**

City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Regulated Entity Number:	RN101474179
Name:	U T SHELL
Address:	1901 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5606
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1901 Guadalupe, Austin, Texas 78705

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

CD392 **TENNISON PROPERTIES INC** **EDR Hist Auto** **1022141136**
Target **19TH & GUADALUPE** **N/A**
Property **AUSTIN, TX 78705**

Site 8 of 15 in cluster CD

Actual:
564 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1998	TENNISON PROPERTIES INC	Convenience Stores
1999	TENNISON PROPERTIES INC	Convenience Stores

CE393 Target Property | **TF AFFORDABLE HOUSING LP**
1717 WEST 67TH STREET, SUITE 315
AUSTIN, TX 78703 | **FINDS** | **1009323468**
N/A

Site 1 of 2 in cluster CE

Actual: 600 ft.
Focus Map: 11

FINDS:
Registry ID: 110024279831

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CE394 Target Property | **AUSTIN HIGH SCHOOL**
1715 WEST AVE LOT ST
AUSTIN, TX 78701 | **TX Ind. Haz Waste** | **S105532119**
N/A

Site 2 of 2 in cluster CE

Actual: 601 ft.
Focus Map: 11

Ind. Haz Waste:

Name:	AUSTIN HIGH SCHOOL
Address:	1715 WEST AVE LOT ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	69662
Registration Initial Notification Date:	08/30/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD138034731
Primary NAICS Code:	Not reported
Status Change Date:	19860830
Land Type:	Not reported
Description of Facility Site Location:	1715 W Lot St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG

AUSTIN HIGH SCHOOL (Continued) **S105532119**

Type of Generator:	NON INDUS
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	WAYNE SCHADE
Contact Telephone Number:	512-4518411
Mailing Address:	6100 GUADALUPE ST RM 210
Mailing Address2:	RM 210
Mailing City,State,Zip:	AUSTIN, TX 787524420
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24534
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021112
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	6100 GUADALUPE ST RM 210
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4518411
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	6100 GUADALUPE ST RM 210
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4518411
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

AUSTIN HIGH SCHOOL (Continued) **S105532119**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	WAYNE SCHADE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	RM 210
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752

AUSTIN HIGH SCHOOL (Continued) **S105532119**

Contact Phone: 1-512-4518411
Contact Fax: Not reported
Contact Email: Not reported

CF395 **0 K TAILORING CO** **EDR Hist Cleaner** **1013781145**
Target **1814 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 8 in cluster CF

Actual:
559 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	0 K TAILORING CO	CLOTHES CLEANERS AND PRESSERS

CF396 **7 ELEVEN STORE 23295** **FINDS** **1010714945**
Target **1814 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 8 in cluster CF

Actual:
559 ft.
FINDS:
Registry ID: 110033427414

Focus Map:
11
Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CF397 **GULF OIL CORP** **EDR Hist Auto** **1013754386**
Target **1814 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 8 in cluster CF

Actual:
559 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	GULF OIL CORP	GASOLINE STATIONS
1962	UNIVERSITY GULF	GASOLINE STATIONS
1965	UNIVERSITY GULF SERVICE	GASOLINE STATIONS
1969	UNIVERSITY GULF	Gasoline Service Stations
1969	UNIVERSITY GULF SERVICE	Gasoline Service Stations
1970	UNIVERSITY GULF SERVICE STATION	GASOLINE STATIONS
1970	UNIVERSITY GULF SERVICE	Gasoline Service Stations
1971	UNIVERSITY GULF SERVICE	Gasoline Service Stations

GULF OIL CORP (Continued) **1013754386**

1972	UNIVERSITY GULF SERVICE	Gasoline Service Stations
1973	UNIVERSITY GULF SERVICE	Gasoline Service Stations
1975	MORGAN R V GULF SERVICE	GASOLINE STATIONS
1976	MORGANS GULF	Gasoline Service Stations
1977	MORGANS GULF	Gasoline Service Stations
1978	MORGANS GULF	Gasoline Service Stations
1979	MORGANS GULF	Gasoline Service Stations
1980	MORGAN R V GULF SERVICE	GASOLINE STATIONS
1980	MORGANS GULF	Gasoline Service Stations

CF398 **7 ELEVEN STORE NO 23295** **TX RDR** **S127538742**
Target **1814 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 8 in cluster CF

Actual:
559 ft.

Focus Map:
11

RDR:

RDR ID:	15384
Facility ID:	7173
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE NO 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/5/2007
Due Date:	6/4/2007
Tank Owner:	7 ELEVEN INC
Contact Person:	RON FULENCHEK
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	6/29/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORIG REC 6/13/2000; DOES THIS NEED A LPST#?; REC TECH RESP 9/18/2006; REC TECH RESP 4/05/07
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	6/29/2007
Region:	Not reported
DKC RDR (misfiled):	Not reported

CF399 **7-ELEVEN 23295** **TX LPST** **U001243596**
Target **1814 GUADALUPE ST** **TX UST** **N/A**
Property **AUSTIN, TX 78701** **TX HIST UST**
TX ASBESTOS
TX Financial Assurance
TX GCC
TX RDR
TX CENTRAL REGISTRY

Site 5 of 8 in cluster CF

Actual:
559 ft.

Focus Map:
11

LPST:

7-ELEVEN 23295 (Continued) **U001243596**

Name:	7 ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0007173
LPST Id:	115013
Facility Location:	1814 GUADALUPE ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	05/10/2000
Entered Date:	07/31/2000
Reported Date:	05/10/2000
Closure Date:	07/09/2002
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SRJ
Responsible Party Name:	Not reported
Responsible Party Contact:	JANE LOMAS
Responsible Party Address:	1201 BELT LINE RD
Responsible Party City,St,Zip:	COPPELL, TX 75019
Responsible Party Telephone:	972/341-8300
Reported Date:	05/10/2000
Case Start Date:	07/09/2002
Reference Number:	RN102018819
Project Manager:	SRJ

Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	119942
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	12/15/2015
Entered Date:	06/16/2016
Reported Date:	12/15/2015
Closure Date:	02/16/2018
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	12/15/2015
Case Start Date:	02/16/2018
Reference Number:	RN102018819
Project Manager:	RKRAFT

7-ELEVEN 23295 (Continued) **U001243596**

UST:

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787011217
AI Number:	7173
Facility Type:	RETAIL
Facility Begin Date:	01/04/1982
Facility Status:	ACTIVE
Additional ID:	746137812002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 23295
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/01/2019
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,REGION COMPLIANCE MANAGER
Application Received Date On Earliest Reg Form:	10/03/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	746137812002117
Ai Number:	7173
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	746137812002117
AI Number:	7173
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46175
Cert ID:	381578
AI Number:	7173
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	364254
AI Number:	7173
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	348014
AI Number:	7173
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	331053
AI Number:	7173
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	328927
AI Number:	7173
Self Certification Date:	10/22/2019
Signature Name/Title:	RAYMOND MCNIESE REG COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	314623
AI Number:	7173
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	296115
AI Number:	7173
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	281116
AI Number:	7173
Self Certification Date:	01/20/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	267015
AI Number:	7173
Self Certification Date:	02/18/2016
Signature Name/Title:	RAYMOND MCNIECE REG COMP MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	263353
AI Number:	7173
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	246903
AI Number:	7173
Self Certification Date:	01/15/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	229606
AI Number:	7173
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46175
Cert ID:	28089
AI Number:	7173
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28088
AI Number:	7173
Self Certification Date:	12/15/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28087
AI Number:	7173
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28086
AI Number:	7173
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28085
AI Number:	7173
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28084
AI Number:	7173
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28083
AI Number:	7173
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28082
AI Number:	7173
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28081
AI Number:	7173
Self Certification Date:	12/14/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28080
AI Number:	7173
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28079
AI Number:	7173
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 23295 (Continued) **U001243596**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28078
AI Number:	7173
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46175
Cert ID:	28077
AI Number:	7173
Self Certification Date:	01/17/2001
Signature Name/Title:	WILLO A SMITH ENVIR DIR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/04/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N

7-ELEVEN 23295 (Continued) **U001243596**

Pipe Type:	P
UST ID:	18610
Facility ID:	46175
Ai Number:	7173
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/2015
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

7-ELEVEN 23295 (Continued) **U001243596**

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26090
UST ID:	18610
AI Number:	7173
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/04/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18612
Facility ID:	46175
Ai Number:	7173
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/2015

7-ELEVEN 23295 (Continued) **U001243596**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26092
UST ID:	18612
AI Number:	7173
Compartment ID:	A
Substance Stored1:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/04/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18611
Facility ID:	46175
Ai Number:	7173
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/2015
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 23295 (Continued) **U001243596**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26091
UST ID:	18611
AI Number:	7173
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

7-ELEVEN 23295 (Continued) **U001243596**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	02/18/2016
Tank Registration Date:	03/04/2016
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	221144
Facility ID:	46175
Ai Number:	7173
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	10/22/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

7-ELEVEN 23295 (Continued) **U001243596**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	01/18/2016

Compartment Records:

Tank ID:	4
Tank Capacity:	12000
UST Comprt ID:	189848
UST ID:	221144
AI Number:	7173
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

7-ELEVEN 23295 (Continued) **U001243596**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	02/18/2016

Tank ID:	4
Tank Capacity:	8000
UST Comprt ID:	189849
UST ID:	221144
AI Number:	7173
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

7-ELEVEN 23295 (Continued) **U001243596**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	02/18/2016

Construction Notification:

NOC ID:	27930
Facility ID:	46175
AI Number:	7173
Application Received Date:	07/20/2015
Scheduled Construction Date:	08/17/2015
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	07/20/2015
Signature Date On Form:	07/17/2015
Signature Name On Form:	LUKE UERECHT
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL OF EXISTING USTS PIPING AND DISPENSERS. INSTALL NEW TANKS, FIBERGLASS PIPING AND 400 GALLON SINGLE WALL OIL AND WATER SEPARATOR WHICH TIES INTO CITY DRAIN

NOC ID:	2517
Facility ID:	46175
AI Number:	7173
Application Received Date:	04/25/2006
Scheduled Construction Date:	05/10/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60425008
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	07/20/2015
Signature Date On Form:	07/17/2015

7-ELEVEN 23295 (Continued) **U001243596**

Signature Name On Form:	LUKE UERECHT
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	65629
UST ID:	Not reported
NOC ID:	27930
AI Number:	7173
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CB&I
Representative Name:	JOHN RUFF
Mailing Address (Delivery):	12005 FORD RD STE 6000
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	68859
UST ID:	221144
NOC ID:	Not reported
AI Number:	7173
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Cont/Cons/Installer ID:	2780
UST ID:	Not reported
NOC ID:	2517
AI Number:	7173
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	65628
UST ID:	Not reported
NOC ID:	27930
AI Number:	7173
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	68858
UST ID:	221144
NOC ID:	Not reported
AI Number:	7173
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	NATHANIEL LAWSON
Mailing Address (Delivery):	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	65630
UST ID:	Not reported
NOC ID:	27930
AI Number:	7173
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	STOVALL BOBBY GEORGE
Representative Name:	Not reported
Mailing Address (Delivery):	902 BOWER DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75061
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	BSTOVALL@MCCONBUILDING.COM

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46175
Additional ID:	746137812002117
Princ ID:	959578622001257
AI Number:	7173
Facility Name:	7-ELEVEN 23295
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

7-ELEVEN 23295 (Continued) **U001243596**

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	803
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	7-ELEVEN
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/08/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/11/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	278703
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411

7-ELEVEN 23295 (Continued) **U001243596**

Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	261552
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	242259
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701

7-ELEVEN 23295 (Continued) **U001243596**

Region:	2
Facility ID:	46175
Finass ID:	223522
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	224122
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	207931
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN 23295 (Continued) **U001243596**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	189239
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	172744
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017

7-ELEVEN 23295 (Continued) **U001243596**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	154087
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	158756
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	138248

7-ELEVEN 23295 (Continued) **U001243596**

AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	118517
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	120905
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013

7-ELEVEN 23295 (Continued) **U001243596**

Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	1542
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28798
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 23295 (Continued) **U001243596**

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28799
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28800
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28801
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 23295 (Continued) **U001243596**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28802
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46175
Finass ID:	28803
AI:	7173
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	10/03/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported

7-ELEVEN 23295 (Continued) **U001243596**

Policy Number: Unknown
Coverage Amount: 0
Coverage Expiration Date: 01/01/1901
Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: No

GCC:
Name: 7 ELEVEN STORE 23295
Address: 1814 GUADALUPE ST
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: *
File Number: 119942
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/15/2015
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 2/L2 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

RDR:
RDR ID: 23636
Facility ID: 7173
RN: Not reported
CN: Not reported
Name: 7 ELEVEN STORE 23295
Address: 1814 GUADALUPE ST
City,State,Zip: AUSTIN, TX
Date Report Received: 4/27/2016
Due Date: 6/26/2016
Tank Owner: 7 ELEVEN INC
Contact Person: JOSE RIOS
Report: RDR
Latest TCEQ Letter: New LPST
Date of Latest TCEQ Letter: 6/16/2016
Project Manager: Ryan Kraft
Team: #N/A
New LPST Number: 119942
Pre-Existing LPST Number: Not reported
Comments: Not reported
Review Coordinator: Not reported
Date Release Reported: Not reported
Suspected: Not reported
Confirmed: Not reported
NOLPST Letter Date: Not reported
Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

7-ELEVEN 23295 (Continued) **U001243596**

CENTRAL REGISTRY:

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295

7-ELEVEN 23295 (Continued) **U001243596**

Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-04
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217

7-ELEVEN 23295 (Continued) **U001243596**

Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/4/1982
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/4/1982
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102018819
Name:	7 ELEVEN STORE 23295
Address:	1814 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1217
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/4/1982
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

CF400 Target Property | **7-11 #23295**
1814 GUADALUPE ST
AUSTIN, TX | **TX RDR** | **S127538743**
N/A

Site 6 of 8 in cluster CF

Actual: 559 ft.
Focus Map: 11

RDR:

RDR ID:	9692
Facility ID:	7173
RN:	Not reported
CN:	Not reported
Name:	7-11 #23295
Address:	1814 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/13/2000
Due Date:	8/12/2000
Tank Owner:	7 ELEVEN INC
Contact Person:	WILLO SMITH
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	7/31/2000
Project Manager:	Joyce Sirota
Team:	Team A
New LPST Number:	115013
Pre-Existing LPST Number:	Not reported
Comments:	115013 JES
Review Coordinator:	JES
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CF401 Target Property | **WHITING ROBT E**
1809 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013761906**
N/A

Site 7 of 8 in cluster CF

Actual: 558 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1958	WHITING ROBT E	AUTOMOBILE REPAIRING

CF402 Target Property | **KNIGHT STEWART**
1805 GUADALUPE
AUSTIN, TX | **EDR Hist Auto** | **1013775957**
N/A

Site 8 of 8 in cluster CF

Actual: 558 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	KNIGHT STEWART	AUTOMOBILE BRAKE SERVICE

CG403 Target Property | **UT BLANTON MUSEUM OF ART**
200 E MARTIN LUTHER KING JR BLVD
AUSTIN, TX 78712 | **ECHO** | **1026896334**
N/A

Site 1 of 6 in cluster CG

Actual: 525 ft.
Focus Map: 11

ECHO:

Envid:	1026896334
Registry ID:	110071076671
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071076671
Name:	UT BLANTON MUSEUM OF ART
Address:	200 E MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78712

CG404 Target Property | **UT BLANTON MUSEUM OF ART**
200 E MARTIN LUTHER KING JR BLVD
AUSTIN, TX 78712 | **FINDS** | **1011409548**
N/A

Site 2 of 6 in cluster CG

Actual: 525 ft.
Focus Map: 11

FINDS:

Registry ID: 110071076671

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Registry ID: 110035174851

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CG405 Target Property | **BLANTON MUSEUM**
200 E MARTIN LUTHER KING JR BLVD
AUSTIN, TX | **TX HIST UST** | **S128728745**
N/A

Site 3 of 6 in cluster CG

Actual: 525 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	BLANTON MUSEUM
Address:	200 E MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX

BLANTON MUSEUM (Continued) **S128728745**

Id UST:	3363
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CG406 Target Property **BLANTON MUSEUM LANDSCAPING PROJECT** **TX RDR** **S127541847**
200 E MLK BLVD **N/A**
AUSTIN, TX

Site 4 of 6 in cluster CG

Actual: 525 ft.
Focus Map: 11

RDR:

RDR ID:	14962
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	BLANTON MUSEUM LANDSCAPING PROJECT
Address:	200 E MLK BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/9/2005
Due Date:	2/7/2006
Tank Owner:	UNIVERSITY OF TEXAS SYSTE
Contact Person:	JIM CROOK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/7/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/7/2006
Date Report Returned:	5/24/2006
Region:	Not reported
DKC RDR (misfiled):	Not reported

CG407 Target Property **SKANSKA USA BUILDING SKANSKA USA BUILDING** **TX CENTRAL REGISTRY** **S126737473**
200 E MARTIN LUTHER KING JR **N/A**
AUSTIN, TX 78701

Site 5 of 6 in cluster CG

Actual: 525 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN104853650
Name:	SKANSKA USA BUILDING SKANSKA USA BUILDING
Address:	200 E MARTIN LUTHER KING JR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-
Status:	ACTIVE
Status Date:	2006-01-23
Customer Number:	CN602544421

SKANSKA USA BUILDING SKANSKA USA BUILDING (Continued) **S126737473**

Customer Name:	SKANSKA USA BUILDING INC
Customer Legal Name:	Skanska USA Building Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2005-07-22
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported
Regulated Entity Number:	RN104853650
Name:	SKANSKA USA BUILDING SKANSKA USA BUILDING
Address:	200 E MARTIN LUTHER KING JR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-
Status:	ACTIVE
Status Date:	2006-01-23
Customer Number:	CN602544421
Customer Name:	SKANSKA USA BUILDING INC
Customer Legal Name:	Skanska USA Building Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2005-07-22
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

CH408 **VACANT RESTAURANT BLDG.** **TX ASBESTOS** **S119160380**
Target **1715 GUADALUPE ST.** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 3 in cluster CH

Actual:
559 ft.

Focus Map:
11

ASBESTOS:

Name:	VACANT RESTAURANT BLDG.
Address:	1715 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/05/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013001646
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	05
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/05/2013
Date Routed by Supervisor:	04/19/2013
Date Routed to PSQA:	04/30/2013

VACANT RESTAURANT BLDG. (Continued) **S119160380**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CG409 **MAGNOLIA PETROLEUM COMP.** **TX HIST UST** **S111678740**
Target **105 W MARTIN LUTHER KING JR BLVD** **N/A**
Property **AUSTIN, TX**

Site 6 of 6 in cluster CG

Actual:
527 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM COMP.
Address:	105 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0195

MAGNOLIA PETROLEUM COMP. (Continued) **S111678740**

HID UST:	195
Inspection:	06/11/2009
Due:	06/11/2012

CI410 **DEAVERS CONSTRUCTION** **TX CENTRAL REGISTRY** **S126523936**
Target **1601 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 2 in cluster CI

Actual:
558 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101494425
Name:	DEAVERS CONSTRUCTION
Address:	1601 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1137
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600782395
Customer Name:	DEAVERS CONSTRUCTION LP
Customer Legal Name:	Deavers Construction, L.P.
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	11/30/2000
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101494425
Name:	DEAVERS CONSTRUCTION
Address:	1601 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1137
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN602299430
Customer Name:	JONES CONTRACTORS
Customer Legal Name:	Jones Contractors
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

CI411 Target Property | **DEAVERS CONSTRUCTION**
1601 RIO GRANDE ST
AUSTIN, TX 78701 | **TX AST** | **A100173946**
N/A

Site 2 of 2 in cluster CI

Actual: 558 ft.

Focus Map: 11

AST:

Name:	DEAVERS CONSTRUCTION
Address:	1601 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 787011137
Facility ID:	112322
Additional ID:	914654692002053
AI Number:	73702
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	0
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78701
Contact Name/Title:	LARRY GARLAND/VICE PRESIDENT
Contact Organization Name:	DEAVERS CONSTRUCTION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124781200
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	10/03/2000
Signature First Name on Earliest Reg Form:	LARRY W
Application Received Date on Earliest Reg Form:	11/30/2000
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	GARLAND
Signature Title on Earliest Reg Form:	VICE PRESIDENT
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	112322
Tank ID:	64
AST ID:	195494
AI Number:	73702
Install Date:	08/31/1989
Tank Registration Date:	11/30/2000
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	12/31/2005
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000

DEAVERS CONSTRUCTION (Continued) **A100173946**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

CH412 **1705 GUADALUPE ST. BLDG.** **TX ASBESTOS** **S119136628**
Target **1705 GUADALUPE ST.** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 3 in cluster CH

Actual:
556 ft.

Focus Map:
11

ASBESTOS:

Name:	1705 GUADALUPE ST. BLDG.
Address:	1705 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/02/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2014002076
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	05/05/2014
Date Routed by Supervisor:	05/22/2014
Date Routed to PSQA:	05/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

1705 GUADALUPE ST. BLDG. (Continued) **S119136628**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CH413 **SPOTLESS CASH CLEAN** **EDR Hist Cleaner** **1013783665**
Target **1703 GUADALUPE ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 3 in cluster CH

Actual:
553 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	SPOTLESS CASH CLEAN	CLOTHES PRESSERS AND CLEANERS

CJ414 **WILLIAM GAMON INSURANCE BUILDING** **TX ASBESTOS** **S125923532**
Target **1615 GUADALUPE STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 8 in cluster CJ

Actual:
551 ft.

ASBESTOS:

Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701

Focus Map:
11

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Date of inspection:	Not reported
Reason for Inspection:	Brenda J Troth
Violation:	Not reported
Complaint Date:	06/22/2021
Notification Number:	2021003699
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/02/2021
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	11/26/2021
Notification Number:	2021003751
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/11/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/11/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	09/24/2021
Notification Number:	2021003751
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/28/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/28/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/13/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	09/24/2021
Notification Number:	2021003751
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/12/2021

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/12/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/27/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	11/26/2021
Notification Number:	2021003751

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/26/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/26/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/03/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	11/26/2021
Notification Number:	2021003751
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/02/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/02/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/12/2021
Client Code:	Not reported
Client Name:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WILLIAM GAMON INSURANCE BUILDING
Address:	1615 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erika Martin
Violation:	Not reported
Complaint Date:	09/24/2021
Notification Number:	2021003751
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/03/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/03/2021
Certification Statement Phone:	972-721-0898
Is The Facility a School or K-12?:	N

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/29/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WILLIAM GAMMON INSURANCE BUILDING
Address:	1615 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/14/2020
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	12/27/2019
Notification Number:	2019008815
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/27/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	20
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WILLIAM GAMMON INSURANCE BUILDING
Address:	1615 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/14/2020
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	01/06/2020
Notification Number:	2019008815
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/03/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/03/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	20
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Name:	WILLIAM GAMMON INSURANCE BUILDING
Address:	1615 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/14/2020
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	01/06/2020
Notification Number:	2019008815
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/03/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/03/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	20
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

WILLIAM GAMON INSURANCE BUILDING (Continued) **S125923532**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CJ415 **UT ADMINISTRATION BUILDING - SUITE 3.304** **TX ASBESTOS** **S121363288**
Target **1616 GUADALUPE** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 8 in cluster CJ

Actual:
547 ft.

Focus Map:
11

ASBESTOS:

Name:	UT ADMINISTRATION BUILDING - SUITE 3.304
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/01/07
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/07/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018009579
File Number:	37170
License Status Description:	Paid
Expiration Date:	01/10/2019
Original Date:	12/17/2018
Rank Effective Date:	12/17/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	13718
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	UT ADMINISTRATION BUILDING (UTA)
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tonya L Bosher
Violation:	Not reported
Complaint Date:	11/30/2017
Notification Number:	2017008181
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/13/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/13/2017
Certification Statement Phone:	512-922-2429
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/29/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	UT ADMINISTRATION BUILDING (UTA)
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tonya L Bosher
Violation:	Not reported
Complaint Date:	11/23/2017
Notification Number:	2017008181
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/03/2017
Certification Statement Phone:	512-922-2429
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Name:	UT ADMINISTRATION BUILDING
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/29/2018
Notification Number:	2018007915
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/24/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/24/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	UT ADMINISTRATION BUILDING
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/29/2018
Notification Number:	2018008138
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/02/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	UT ADMINISTRATION BUILDING - SUITE 3.304
Address:	1616 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	01/07/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/10/2019
Notification Number:	2018009579
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

UT ADMINISTRATION BUILDING - SUITE 3.304 (Continued) **S121363288**

Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/17/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/07/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CJ416 **GUADALUPE MOTOR POOL** **TX CENTRAL REGISTRY** **S126576995**
Target **1616 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 8 in cluster CJ

Actual:
547 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN102381746
Name:	GUADALUPE MOTOR POOL
Address:	1616 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1204
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600261663
Customer Name:	SOUTHWESTERN BELL TELEPHONE LP
Customer Legal Name:	Southwestern Bell Telephone, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988

GUADALUPE MOTOR POOL (Continued) **S126576995**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102381746
Name:	GUADALUPE MOTOR POOL
Address:	1616 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1204
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN602814709
Customer Name:	NEW CINGULAR WIRELESS PCS LLC
Customer Legal Name:	New Cingular Wireless PCS, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/25/2017
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

CJ417 **ABOUT TIME DRY CLEANING** **EDR Hist Cleaner** **1018561370**
Target **1616 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 8 in cluster CJ

Actual:
547 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
2008	ABOUT TIME DRY CLEANING	Laundry And Drycleaner Agents
2009	ABOUT TIME DRY CLEANING	Laundry And Drycleaner Agents
2010	ABOUT TIME DRY CLEANING	Laundry And Drycleaner Agents

CJ418 **UT AUSTIN DAS** **TX TIER 2** **S113681955**
Target **1616 GUADALUPE STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 8 in cluster CJ

Actual:
547 ft.

TIER 2:

Focus Map:
11

Facility Id/Name:	FATR201271PUVN002LK1/UT AUSTIN DAS
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	1/18/2013
Mailing Address:	P.O. Box 97061
Mailing City/State/Country:	Redmond, WA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	7
Number Of Employess On Site:	N/A

UT AUSTIN DAS (Continued) **S113681955**

Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Caroline Lammers, EH&S Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	UN
Lat/Long Method:	UN
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	102026754
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/24/2010
Id:	517210
Id Type:	NAICS
Description:	Cellular and Other Wireless Telecommunications
Last Modified:	2/24/2010
Id:	4812
Id Type:	SIC
Description:	RADIOTELEPHONE COMMUNICATIONS
Last Modified:	2/24/2010

Contact:

Contact Email:	ehs.compliance@att.com
Contact Mail Address:	P.O. Box 97061
Contact City/State/Zip:	Redmond, WA 98073
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Owner / Operator
Contact Name:	AT&T Mobility, LLC
Title:	EH&S Compliance
Modification Date:	4/4/2011

Contact Email:	Not reported
Contact Mail Address:	P.O. Box 97061
Contact City/State/Zip:	Redmond, WA 98073
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Owner / Operator
Contact Name:	AT&T Mobility, LLC
Title:	EH&S Compliance
Modification Date:	3/14/2010

Contact Email:	ehs.compliance@att.com
Contact Mail Address:	P.O. Box 97061
Contact City/State/Zip:	Redmond, WA 98073
Contact Mail Country:	USA

UT AUSTIN DAS (Continued) **S113681955**

Contact Type 1:	Owner / Operator
Contact Type 2:	Owner / Operator
Contact Name:	New Cingular Wireless PCS, LLC
Title:	EH&S Compliance
Modification Date:	2/24/2013
Contact Email:	ehs.compliance@att.com
Contact Mail Address:	P.O. Box 97061
Contact City/State/Zip:	Redmond, WA 98073
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Owner / Operator
Contact Name:	New Cingular Wireless PCS, LLC
Title:	EH&S Compliance
Modification Date:	2/24/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	EHS Hotline
Title:	Hotline Operator
Modification Date:	4/4/2011
Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	EHS Hotline
Title:	Hotline Operator
Modification Date:	3/14/2010
Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	EHS Hotline
Title:	Hotline Operator
Modification Date:	2/24/2013
Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	EHS Hotline
Title:	Hotline Operator
Modification Date:	2/24/2013

UT AUSTIN DAS (Continued) **S113681955**

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Type 3:	Emergency Contact
Contact Name:	Peters Scott
Title:	Manager Operations
Modification Date:	2/24/2013

Chemical Inventory:

Facility Id:	FATR201271PUVN002LK1
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	CVTR201271PUVN009LN8
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	526
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/24/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201271PUVN00ALNQ
Chemical Inventory Record Id:	CVTR201271PUVN009LN8
Amt Of Sub Stored Or Transported:	526
Amount Units:	Pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	batteries at cell site
Last Modified:	2/24/2013

Notes: Not reported
Validation: Not reported

CJ419 Target Property | **GUADALUPE MOTOR POOL**
1616 GUADALUPE ST
AUSTIN, TX 78701 | **TX UST** | **U001255578**
TX HIST UST | **N/A**

Site 6 of 8 in cluster CJ

Actual: 547 ft.

Focus Map: 11

UST:

Name:	GUADALUPE MOTOR POOL
Address:	1616 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787011204
AI Number:	20854
Facility Type:	Not reported
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	125612332002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	J RANKIN,SUPV
Contact Organization Name:	GUADALUPE MOTOR POOL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128702985
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/19/1986
Signature Name/Title On Earliest Reg Form:	G BEAN,ASST SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600261663
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	35290742001297
Additional ID:	125612332002150

GUADALUPE MOTOR POOL (Continued) **U001255578**

AI Number:	20854
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	12/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	53567
Facility ID:	76710
Ai Number:	20854
Tank Id:	XX1918
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/12/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

GUADALUPE MOTOR POOL (Continued) **U001255578**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	XX1918
Tank Capacity:	4000
UST Comprt ID:	114856
UST ID:	53567
AI Number:	20854
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

GUADALUPE MOTOR POOL (Continued) **U001255578**

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76710
Additional ID:	125612332002150
Princ ID:	35290742001297
AI Number:	20854
Facility Name:	GUADALUPE MOTOR POOL
AR Number:	22573
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	SW BELL AUSTIN DIV
Address:	1616 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0618
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CK420 **ERNS** **89100954**
Target Property **LBJ BLDG 111 EAST 17TH STREET** **N/A**
AUSTIN, TX

Site 1 of 3 in cluster CK

Actual: 543 ft.

Focus Map: 11

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

CL421 **ENVIRONMENTAL CONTRACTORS** **TX Ind. Haz Waste** **S102747077**
Target Property **1405 RIO GRANDE ST** **TX CENTRAL REGISTRY** **N/A**
AUSTIN, TX 78701

Site 1 of 2 in cluster CL

Actual: 527 ft.

Focus Map: 11

Ind. Haz Waste:

Name:	ENVIRONMENTAL CONTRACTORS
Address:	1405 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	41860

ENVIRONMENTAL CONTRACTORS (Continued) **S102747077**

Registration Initial Notification Date:	11/12/1991
Registration Last Amendment Date:	02/13/2001
EPA Identification:	Not reported
Primary NAICS Code:	484110
Status Change Date:	19911112
Land Type:	Not reported
Description of Facility Site Location:	1405 Rio Grande Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	ENVIRONMENTAL CONTRACTORS INC
Contact Name:	TAMMY T BAILEY
Contact Telephone Number:	512-4748501
Mailing Address:	1405 RIO GRANDE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787011505
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	18244
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030930
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	1

Ind. Haz Waste:

Owner Name:	ENVIRONMENTAL CONTRACTORS INC
Owner Mailing Address:	1405 RIO GRANDE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4748501
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown

ENVIRONMENTAL CONTRACTORS (Continued) **S102747077**

Owner Tax ID: 17426099283
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 1405 RIO GRANDE ST
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78701
Contact Phone: 1-512-4748501
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: TAMMY BAILEY
Contact Title: PRESIDENT
Contact Role: PRICONT
Contact Address: 1405 RIO GRANDE ST
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78701
Contact Phone: 1-512-4748501
Contact Fax: Not reported
Contact Email: Not reported

CENTRAL REGISTRY:
Regulated Entity Number: RN100619444
Name: ENVIRONMENTAL CONTRACTORS
Address: 1405 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1505
Status: ACTIVE
Status Date: ##########
Customer Number: CN600328413
Customer Name: ENVIRONMENTAL CONTRACTORS INC
Customer Legal Name: Environmental Contractors, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 2/13/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 484110
Primary NAICS Industry Type Description: General Freight Trucking, Local
Physical Location Description: 1405 Rio Grande Street, Austin, TX

Regulated Entity Number: RN100619444
Name: ENVIRONMENTAL CONTRACTORS
Address: 1405 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1505
Status: ACTIVE
Status Date: ##########
Customer Number: CN600328413
Customer Name: ENVIRONMENTAL CONTRACTORS INC
Customer Legal Name: Environmental Contractors, Inc.

ENVIRONMENTAL CONTRACTORS (Continued) **S102747077**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/13/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	484110
Primary NAICS Industry Type Description:	General Freight Trucking, Local
Physical Location Description:	1405 Rio Grande Street, Austin, TX

CL422 **ENVIRONMENTAL CONTRACTORS** **FINDS** **1011323687**
Target **1405 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 2 in cluster CL

Actual:
527 ft.

Focus Map:
11

FINDS:
Registry ID: 110034231098

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CM423 **PETTY LEASE-9 MILES NORTH OF BIG WELLS, TX** **TX SPILLS** **S107006180**
Target **PETTY LEASE-9 MILES NORTH OF BIG WELLS, TX** **N/A**
Property **, TX**

Site 1 of 2 in cluster CM

Actual:
539 ft.

Focus Map:
11

SPILLS:

Name:	PETTY LEASE-9 MILES NORTH OF BIG WELLS, TX
Address:	PETTY LEASE-9 MILES NORTH OF BIG WELLS, TX
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	06/12/1993
Seq Num:	Not reported
Responsible Party Name:	GLC ENERGY
Responsible Party Address:	400 W. 15TH STE 1400
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78701
Responsible Party Telephone:	9999999999
Substance:	OIL
Material Code:	1099
Media Affected:	Not reported
Permit Number:	NONE
District:	08
Origin:	003
Cause:	007

PETTY LEASE-9 MILES NORTH OF BIG WELLS, TX (Continued) **S107006180**

Basin Code:	2117
Notify Date:	Not reported
Adequate Clean:	003
Classification:	003
Basin Name:	NUECES
Water Affected:	NONE
Amnt Spilled:	25 BBL
Amnt in Water:	UNK BBL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	M. STINE
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

CN424 **NOT AVAILABLE (ZONING ONLY)** **TX HIST UST** **S111678758**
Target **101 W 15TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 4 in cluster CN

Actual:
551 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	NOT AVAILABLE (ZONING ONLY)
Address:	101 W 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0958
HID UST:	958
Inspection:	Not reported
Due:	06/01/2012

CO425 Target Property | **ACC RIO GRANDE ST**
1215 RIO GRANDE ST
AUSTIN, TX 78701 | **TX ASBESTOS** | **S128928621**
N/A

Site 1 of 4 in cluster CO

Actual: 515 ft.

Focus Map: 11

ASBESTOS:

Name:	ACC RIO GRANDE ST
Address:	1215 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	01/13/2022
Notification Number:	2021008189
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/08/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/08/2021
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/10/2022
Client Code:	Not reported
Client Name:	Not reported

ACC RIO GRANDE ST (Continued) **S128928621**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ACC RIO GRANDE ST
Address:	1215 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tammie Garza
Violation:	Not reported
Complaint Date:	02/09/2022
Notification Number:	2021008288
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/08/2022
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N

ACC RIO GRANDE ST (Continued) **S128928621**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACC RIO GRANDE ST
Address:	1215 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tammie Garza
Violation:	Not reported
Complaint Date:	02/18/2022
Notification Number:	2021008288
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/13/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

ACC RIO GRANDE ST (Continued) **S128928621**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/13/2022
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACC RIO GRANDE ST
Address:	1215 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tammie Garza
Violation:	Not reported
Complaint Date:	02/18/2022
Notification Number:	2021008288
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

ACC RIO GRANDE ST (Continued) **S128928621**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/18/2022
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ACC RIO GRANDE ST (Continued) **S128928621**

Name:	ACC RIO GRANDE ST
Address:	1215 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Tammie Gomez
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2021008288
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	12/10/2021
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

ACC RIO GRANDE ST (Continued) **S128928621**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CO426 **ACC ATTACHE BUILDING** **TX ASBESTOS** **S126246845**
Target **1209 RIO GRANDE** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 4 in cluster CO

Actual:
515 ft.

Focus Map:
11

ASBESTOS:

Name:	ACC ATTACHE BUILDING
Address:	1209 RIO GRANDE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	03/27/2020
Notification Number:	2020001741
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/25/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/25/2020
Certification Statement Phone:	512-260-6202

ACC ATTACHE BUILDING (Continued) **S126246845**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	81
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/16/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CO427 **ACC RIO GRANDE CAMPUS- ATTACHE BUILDING** **TX ASBESTOS** **S127036423**
Target **1209 RIO GRANDE STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 4 in cluster CO

Actual:
515 ft.

Focus Map:
11

ASBESTOS:

Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	10/09/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Inspector Name:	Not reported
Date Report Received:	09/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/15/2020
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/28/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Complaint Date:	09/04/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/14/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/14/2020
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/31/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	09/18/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/28/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/28/2020
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/07/2020

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	09/25/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/04/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/04/2020

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/14/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	10/09/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/10/2020
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/21/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACC RIO GRANDE CAMPUS- ATTACHE BUILDING
Address:	1209 RIO GRANDE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	08/21/2020
Notification Number:	2020005007
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/03/2020
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

ACC RIO GRANDE CAMPUS- ATTACHE BUILDING (Continued) **S127036423**

Inspection Number Grade: Not reported

CP428 Target Property **BURCH H H SERV STA**
1228 CONGRESS AVE
SOUTH AUSTIN, TX

EDR Hist Auto **1013771656**
N/A

Site 1 of 2 in cluster CP

Actual: 547 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1962	BURCH H H SERV STA	GASOLINE STATIONS

---

429 Target Property **TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG.**
1215 GUADALUPE ST.
AUSTIN, TX 78778

TX ASBESTOS **S119158499**
N/A

Actual: 552 ft.

Focus Map: 11

ASBESTOS:

Name:	TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG.
Address:	1215 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/27/2016
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2016000066
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	04
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	05/16/2016
Date Reviewed by PSQA:	2016-05-16 00:00:00
Date Routed by Supervisor1:	05/09/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG. (Continued) **S119158499**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG
Address:	1215 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/27/2016
Reason for Inspection:	Kamal Hussein
Violation:	Not reported
Complaint Date:	01/29/2016
Notification Number:	2016000066
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG. (Continued) **S119158499**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/12/2016
Certification Statement Phone:	713-856-5354
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG
Address:	1215 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/27/2016
Reason for Inspection:	Kamal Hussein
Violation:	Not reported
Complaint Date:	01/25/2016
Notification Number:	2016000066
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TEXAS WORKFORCE COMMISSION / GUADALUPE BLDG. (Continued) **S119158499**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/05/2016
Certification Statement Phone:	713-856-5354
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	38
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/19/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CQ430 Target Property | **BUTLERS TERRACE**
1123 CONGRESS AVE
SOUTH AUSTIN, TX | **EDR Hist Auto** | **1013759684**
N/A

Site 1 of 4 in cluster CQ

Actual: 542 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1962	BUTLERS TERRACE	GASOLINE STATIONS

CQ431 Target Property | **VACANT BUILDING**
1117 CONGRESS
AUSTIN, TX 78767 | **TX ASBESTOS** | **S121363331**
N/A

Site 2 of 4 in cluster CQ

Actual: 539 ft.
Focus Map: 11

ASBESTOS:

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	03/31/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/10/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10

VACANT BUILDING (Continued) **S121363331**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/28/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	06/11/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

VACANT BUILDING (Continued) **S121363331**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/10/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/03/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	02/08/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

VACANT BUILDING (Continued) **S121363331**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/22/2016
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767

VACANT BUILDING (Continued) **S121363331**

Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	02/03/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/04/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/04/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

VACANT BUILDING (Continued) **S121363331**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	02/17/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/27/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

VACANT BUILDING (Continued) **S121363331**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/15/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	03/03/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/14/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement

VACANT BUILDING (Continued) **S121363331**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/14/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	03/03/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2017

VACANT BUILDING (Continued) **S121363331**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/22/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	05/31/2017
Notification Number:	2016010407

VACANT BUILDING (Continued) **S121363331**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/22/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/14/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

VACANT BUILDING (Continued) **S121363331**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	03/23/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/28/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/21/2017
Client Code:	Not reported
Client Name:	Not reported

VACANT BUILDING (Continued) **S121363331**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	06/11/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/28/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N

VACANT BUILDING (Continued) **S121363331**

Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/03/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	03/23/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

VACANT BUILDING (Continued) **S121363331**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/28/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	06/11/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

VACANT BUILDING (Continued) **S121363331**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/28/2017
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/03/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

VACANT BUILDING (Continued) **S121363331**

Name:	VACANT BUILDING
Address:	1117 CONGRESS
City,State,Zip:	AUSTIN, TX 78767
Date of inspection:	Not reported
Reason for Inspection:	Jim Metcalf
Violation:	Not reported
Complaint Date:	01/27/2017
Notification Number:	2016010407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/22/2016
Certification Statement Phone:	972-271-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/25/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

VACANT BUILDING (Continued) **S121363331**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CQ432 **NO DELAY CLN &** **EDR Hist Cleaner** **1013780511**
Target **1117 CONGRESS AVE** **N/A**
Property **SOUTH AUSTIN, TX**

Site 3 of 4 in cluster CQ

Actual:
539 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1962	NO DELAY CLN &	CLEANERS AND DYERS

CQ433 **MUSIC LANE SHOPPING CENTER** **TX ASBESTOS** **S121361724**
Target **1109 CONGRESS** **N/A**
Property **AUSTIN, TX 78704**

Site 4 of 4 in cluster CQ

Actual:
532 ft.

Focus Map:
11

ASBESTOS:

Name:	MUSIC LANE SHOPPING CENTER
Address:	1109 CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/05/2017
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/06/2016
Notification Number:	2016005068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/06/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSIC LANE SHOPPING CENTER
Address:	1109 CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/05/2017
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	01/25/2017
Notification Number:	2016005068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/06/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Name:	MUSIC LANE SHOPPING CENTER
Address:	1109 CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/05/2017
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016005068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/15/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/15/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSIC LANE SHOPPING CENTER
Address:	1109 CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/05/2017
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	01/25/2017
Notification Number:	2016005068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/15/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/15/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSIC LANE SHOPPING CENTER
Address:	1109 CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/12/06
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

MUSIC LANE SHOPPING CENTER (Continued) **S121361724**

Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	12/06/2016
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2016005068
File Number:	10100
License Status Description:	Paid
Expiration Date:	01/05/2017
Original Date:	06/15/2016
Rank Effective Date:	06/15/2016
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	4499
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Fail
Inspection Number Grade:	0

CR434 **CITY OF AUSTIN - WATER/WASTEWATER NORTH** **TX TIER 2** **S111037814**
Target **901 WEST KOENING LANE** **N/A**
Property **AUSTIN, TX 78757**

Site 1 of 3 in cluster CR

Actual: 496 ft.

Focus Map: 11

TIER 2:

Facility Id:	FATR20124ZXX6N015KJG
Facility Name:	CITY OF AUSTIN - WATER/WASTEWATER NORTH
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Fuel Operations
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/26/2013
Mailing Address:	1190 Hargrave Street
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Will O'Connor
Latitude:	30.3208
Longitude:	-97.7092
Lat/Long Location Desc:	CE
Lat/Long Method:	G0 - GPS (Other)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20114ZXX6N015KJG
Facility Name:	CITY OF AUSTIN - WATER/WASTEWATER NORTH
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Fuel Operations
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	1/3/2012
Mailing Address:	1190 Hargrave Street
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	WILL OCONNOR
Latitude:	30.3208
Longitude:	-97.7092
Lat/Long Location Desc:	CE
Lat/Long Method:	G0 - GPS (Other)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20104ZXX6N015KJG
Facility Name:	CITY OF AUSTIN - WATER/WASTEWATER NORTH
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Fuel Operations
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	2/28/2011
Mailing Address:	1190 Hargrave Street
Mailing City/State/Country:	Austin, TX USA

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Will O'Connor
Latitude:	30.3208
Longitude:	-97.7092
Lat/Long Location Desc:	CE
Lat/Long Method:	G0 - GPS (Other)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	9199
Id Type:	SIC
Description:	GENERAL GOVERNMENT, NEC Municipal Govt'
Last Modified:	3/27/2007
Id:	066432683
Id Type:	Dun & Bradstreet
Description:	CITY OF AUSTIN TX
Last Modified:	2/12/2010
Id:	811111
Id Type:	NAICS
Description:	General Automotive Repair
Last Modified:	2/12/2010

Contact:

Contact Email:	jimmy.tubbs@ci.austin.tx.us
Contact Mail Address:	6400 BOLM RD
Contact City/State/Zip:	AUSTIN, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	JIMMY TUBBS
Title:	FUEL PGM COORD
Modification Date:	4/3/2011

Contact:

Contact Email:	will.oconnor@ci.austin.tx.us
Contact Mail Address:	1190 Hargave Street
Contact City/State/Zip:	Austin, TX 78702
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Type 3:	Owner / Operator
Contact Name:	Will OCONNOR
Title:	Fuel Operations Coordiantor

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Modification Date: 4/3/2011

Chemical Inventory:

Facility Id:	FATR20104ZXX6N015KJG
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR201050J7LQ02YLPA
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/3/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201050UJNJ02ZN30
Chemical Inventory Record Id:	CVTR201050J7LQ02YLPA
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	4/3/2011

Facility Id:	FATR20104ZXX6N015KJG
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR201050UJQ70303JZ
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/3/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201050UJRP031CLP
Chemical Inventory Record Id:	CVTR201050UJQ70303JZ
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	4/3/2011

Notes:	Not reported
Validation:	Not reported

Facility Info:

Id:	9199
Id Type:	SIC
Description:	GENERAL GOVERNMENT, NEC Municipal Govt'
Last Modified:	3/27/2007
Id:	066432683
Id Type:	Dun & Bradstreet
Description:	CITY OF AUSTIN TX
Last Modified:	2/12/2010
Id:	811111
Id Type:	NAICS
Description:	General Automotive Repair
Last Modified:	2/12/2010

Contact:

Contact Email:	will.oconnor@austintexas.gov
Contact Mail Address:	6400 Bolm Rd
Contact City/State/Zip:	Austin, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Type 3:	Owner / Operator
Contact Name:	Will OCONNOR
Title:	Fuel Operations Coordiantor
Modification Date:	3/7/2013

Contact:

Contact Email:	jimmy.tubbs@austintexas.gov
Contact Mail Address:	6400 BOLM RD

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Contact City/State/Zip:	AUSTIN, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	JIMMY TUBBS
Title:	FUEL PGM COORD
Modification Date:	3/7/2013

Chemical Inventory:

Facility Id:	FATR20124ZXX6N015KJG
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR201250J7LQ02YLPA
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201250UJNJ02ZN30
Chemical Inventory Record Id:	CVTR201250J7LQ02YLPA
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	3/7/2013

Facility Id:	FATR20124ZXX6N015KJG
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR201250UJQ70303JZ
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Last Modified:	3/7/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201250UJRP031CLP
Chemical Inventory Record Id:	CVTR201250UJQ70303JZ
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	3/7/2013

Notes:	Not reported
Validation:	Not reported

Facility Info:

Id:	066432683
Id Type:	Dun & Bradstreet
Description:	CITY OF AUSTIN TX
Last Modified:	2/12/2010
Id:	811111
Id Type:	NAICS
Description:	General Automotive Repair
Last Modified:	2/12/2010
Id:	9199
Id Type:	SIC
Description:	GENERAL GOVERNMENT, NEC Municipal Govt'
Last Modified:	3/27/2007

Contact:

Contact Email:	will.oconnor@austintexas.gov
Contact Mail Address:	6400 Bolm Rd
Contact City/State/Zip:	Austin, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Type 3:	Owner / Operator
Contact Name:	Will OCONNOR
Title:	Fuel Operations Coordiantor
Modification Date:	2/6/2012

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Contact:

Contact Email:	jimmy.tubbs@austintexas.gov
Contact Mail Address:	6400 BOLM RD
Contact City/State/Zip:	AUSTIN, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	JIMMY TUBBS
Title:	FUEL PGM COORD
Modification Date:	2/6/2012

Chemical Inventory:

Facility Id:	FATR20114ZXX6N015KJG
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR201150J7LQ02YLPA
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/6/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201150UJNJ02ZN30
Chemical Inventory Record Id:	CVTR201150J7LQ02YLPA
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	2/6/2012

Facility Id:	FATR20114ZXX6N015KJG
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR201150UJQ70303JZ
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds

CITY OF AUSTIN - WATER/WASTEWATER NORTH (Continued) **S111037814**

Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/6/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201150UJRP031CLP
Chemical Inventory Record Id:	CVTR201150UJQ70303JZ
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	CONFIDENTIAL
Last Modified:	2/6/2012

Notes: Not reported
Validation: Not reported

CR435 Target Property **WATER/WASTEWATER NORTH**
901 WEST KOENING LANE
AUSTIN, TX 78757

TX TIER 2 **S108888627**
N/A

Site 2 of 3 in cluster CR

Actual: 496 ft.

Focus Map: 11

TIER 2:

Facility Id:	FATR20094ZXX6N015KJG
Facility Name:	CITY OF AUSTIN WATER/WASTEWATER NORTH
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Fuel Operations
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	02/12/2010
Mailing Address:	1190 Hargrave Street
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	WILL OCONNOR

WATER/WASTEWATER NORTH (Continued) **S108888627**

Latitude:	30.3208
Longitude:	-97.7092
Lat/Long Location Desc:	CE
Lat/Long Method:	G0 - GPS (Other)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20064ZXX6N015KJG/WATER/WASTEWATER NORTH
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Fuel Operations
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	03/13/2007
Mailing Address:	1190 Hargrave Street
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Paul Gross
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	066432683
Id Type:	Dun & Bradstreet
Description:	CITY OF AUSTIN TX
Last Modified:	2/12/2010
Id:	811111
Id Type:	NAICS
Description:	General Automotive Repair
Last Modified:	2/12/2010
Id:	9199
Id Type:	SIC
Description:	GENERAL GOVERNMENT, NEC Municipal Govt'
Last Modified:	3/27/2007

WATER/WASTEWATER NORTH (Continued) **S108888627**

Contact:

Contact Email:	Not reported
Contact Mail Address:	1190 Hargave Street
Contact City/State/Zip:	Austin, TX 78702
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Type 3:	Owner / Operator
Contact Name:	Will OCONNOR
Title:	Fuel Operations Coordiantor
Modification Date:	2/16/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	6400 BOLM RD
Contact City/State/Zip:	AUSTIN, TX 78721
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	STACEY MONROE
Title:	FUEL PGM COORD
Modification Date:	2/16/2010

Chemical Inventory:

Facility Id:	FATR20094ZXX6N015KJG
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR200950J7LQ02YLPA
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/16/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200950UJNJ02ZN30
Chemical Inventory Record Id:	CVTR200950J7LQ02YLPA
Amt Of Sub Stored Or Transported:	9000
Amount Units:	gallons

WATER/WASTEWATER NORTH (Continued) **S108888627**

Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: CONFIDENTIAL
Last Modified: 2/16/2010

Facility Id: FATR20094ZXX6N015KJG
Chemical Name: FUELS, GASOLINE
Chemical Inv Record Id: CVTR200950UJQ70303JZ
CAS Number: 8006-61-9
Chemical Same As Last Year: T
Acute Health Risks: T
Average Daily Amount: 10,000 - 99,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: Not reported
Chronic Health Risks: T
EHS Substance: Not reported
Last Modified: 2/16/2010
Days On Site: 365
Fire Hazard: T
Gas: Not reported
Liquid: T
Mixture Form: Not reported
Sudden Release Of Pressure Haz: Not reported
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2009
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR200950UJRP031CLP
Chemical Inventory Record Id: CVTR200950UJQ70303JZ
Amt Of Sub Stored Or Transported: 9000
Amount Units: gallons
Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: CONFIDENTIAL
Last Modified: 2/16/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported
Validation: Not reported

CR436 Target Property | **WEST 9TH STREET PARTNERS**
704 W 9TH ST
AUSTIN, TX 78701 | **EDR Hist Auto** | **1021677307**
N/A

Site 3 of 3 in cluster CR

Actual: 500 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
2014	WEST 9TH STREET PARTNERS	Gasoline Service Stations

CS437 Target Property | **TRAVIS COUNTY COURTHOUSE**
1000 GUADALUPE ST
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S126666619**
N/A

Site 1 of 3 in cluster CS

Actual: 541 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN103762092
Name:	TRAVIS COUNTY COURTHOUSE
Address:	1000 GUADALUPE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2328
Status:	ACTIVE
Status Date:	7/21/2003
Customer Number:	CN600338388
Customer Name:	TRAVIS COUNTY
Customer Legal Name:	Travis County
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	9/25/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

CS438 Target Property | **HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE**
1000 GUADALUPE STREET
AUSTIN, TX 78701 | **TX ASBESTOS** | **S123212974**
N/A

Site 2 of 3 in cluster CS

Actual: 541 ft.

Focus Map: 11

ASBESTOS:

Name:	HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE
Address:	1000 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	11/28/2018
Notification Number:	2018008280
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE (Continued) **S123212974**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/23/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/23/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE
Address:	1000 GUADALUPE STREET

HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE (Continued) **S123212974**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	11/26/2018
Notification Number:	2018008280
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/09/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/09/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/25/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

HEMAN MARION SWEATT TRAVIS COUNTY COURTHOUSE (Continued) **S123212974**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CS439 **TRAVIS COUNTY COURTHOUSE** **TX UST** **U001289500**
Target **1000 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 3 in cluster CS

Actual:
541 ft.

Focus Map:
11

UST:

Name:	TRAVIS COUNTY COURTHOUSE
Address:	1000 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787012328
AI Number:	60042
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/09/1991
Facility Status:	INACTIVE
Additional ID:	835600912003202
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	JOHN SUTTON,
Contact Organization Name:	TRAVIS COUNTY COURTHOUSE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124739500
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/27/1991
Signature Name/Title On Earliest Reg Form:	JOHN M SUTTON,DIR GEN SRVCS
Application Received Date On Earliest Reg Form:	09/09/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600338388
Owner Last Name:	TRAVIS COUNTY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OG

TRAVIS COUNTY COURTHOUSE (Continued) **U001289500**

Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	178448372001300
Additional ID:	835600912003202
AI Number:	60042
Owner Effective Begin Date:	09/25/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/09/1991
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	141403
Facility ID:	72700
Ai Number:	60042
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/20/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

TRAVIS COUNTY COURTHOUSE (Continued) **U001289500**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	104900
UST ID:	141403
AI Number:	60042
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

TRAVIS COUNTY COURTHOUSE (Continued) **U001289500**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRAVIS COUNTY
Contact Mailing Address (Delivery):	PO BOX 1748
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1748
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72700
Additional ID:	835600912003202
Princ ID:	178448372001300
AI Number:	60042
Facility Name:	TRAVIS COUNTY COURTHOUSE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KEITH COBURN/

CT440 **TEXAS DEPT. OF TRANSPORTATION** **PRP** **1026643607**
Target **125 E. 11TH ST.** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 4 in cluster CT

Actual:
519 ft.

Focus Map:
11

PRP:

Name:	TEXAS DEPT. OF TRANSPORTATION
Address:	125 E. 11TH ST.
City,State,Zip:	AUSTIN, TX 78701
Superfund EPAID:	TXD980864789
Superfund Name:	MALONE SERVICE CO - SWAN LAKE PLANT
Superfund Address:	LOOP 197 S
Superfund City,State,Zip:	TEXAS CITY, TX 77590
NPL Status:	Currently on the Final NPL
NPL Status Short Name:	Not reported
Data Type:	SETTLEMENT DATE
Action Date:	6/26/2012
Settlement Code:	AC-7
Settlement:	ADM ORDR
Latitude:	29.333056
Longitude:	-94.902778

CT441 Target Property | **TXDOT**
125 E. 11TH STREET
AUSTIN, TX 78701 | **ICIS** **FINDS** **ECHO** | **1007121753** **N/A**

Site 2 of 4 in cluster CT

Actual: 519 ft.

Focus Map: 11

ICIS:

Enforcement Action ID:	06-2003-2726
FRS ID:	110015748020
Action Name:	TXDOT
Facility Name:	TXDOT
Facility Address:	125 E. 11TH STREET AUSTIN, TX 78701
Enforcement Action Type:	CWA 309G2B AO For Class II Penalties
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	309G2B
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.27257
Longitude in Decimal Degrees:	-97.740556
Permit Type Desc:	Not reported
Program System Acronym:	5415092
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	TXDOT
Address:	125 E. 11TH STREET
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	Not reported

FINDS:

Registry ID: 110070171136

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Registry ID: 110015748020

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the

TXDOT (Continued) **1007121753**

discharge does not adversely affect water quality.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1007121753
Registry ID:	110015748020
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110015748020
Name:	TXDOT
Address:	125 E. 11TH STREET
City,State,Zip:	AUSTIN, TX 78701

CT442 **TEXAS DEPT OF TRANSPORTATION** **TX CENTRAL REGISTRY** **S126663646**
Target **125 E 11TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 4 in cluster CT

Actual: 519 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN103726634
Name:	TEXAS DEPT OF TRANSPORTATION
Address:	125 E 11TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2409
Status:	ACTIVE
Status Date:	7/11/2003
Customer Number:	CN600803456
Customer Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Customer Legal Name:	Texas Department of Transportation
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103726634
Name:	TEXAS DEPT OF TRANSPORTATION
Address:	125 E 11TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2409
Status:	ACTIVE

TEXAS DEPT OF TRANSPORTATION (Continued) **S126663646**

Status Date:	7/11/2003
Customer Number:	CN600803456
Customer Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Customer Legal Name:	Texas Department of Transportation
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

CT443 **KENEDY COUNTY REST AREA WWTP** **ICIS** **1018307949**
Target **125 E. 11TH STREET** **N/A**
Property **KENEDY COUNTY, TX 78701**

Site 4 of 4 in cluster CT

Actual:
519 ft.

Focus Map:
11

ICIS:

Enforcement Action ID:	TX-200123378
FRS ID:	110033719073
Action Name:	Email - 6/12/15
Facility Name:	KENEDY COUNTY REST AREA WWTP
Facility Address:	125 E. 11TH STREET KENEDY COUNTY, TX 78701
Enforcement Action Type:	Phone Call/ EMAIL
Facility County:	KENEDY
Program System Acronym:	NPDES
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	PHEMAIL
Facility SIC Code:	7033
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	27.133055
Longitude in Decimal Degrees:	-97.793611
Permit Type Desc:	NPDES Individual Permit
Program System Acronym:	TX0128678
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	TX-200063183
FRS ID:	110033719073
Action Name:	EMAIL - 2/28/12
Facility Name:	KENEDY COUNTY REST AREA WWTP
Facility Address:	125 E. 11TH STREET KENEDY COUNTY, TX 78701
Enforcement Action Type:	Phone Call/ EMAIL
Facility County:	KENEDY
Program System Acronym:	NPDES
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	PHEMAIL
Facility SIC Code:	7033
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	27.133055
Longitude in Decimal Degrees:	-97.793611
Permit Type Desc:	NPDES Individual Permit
Program System Acronym:	TX0128678
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

CU444 Target Property | **CARLSONS DAVE**
915 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013756519**
N/A

Site 1 of 4 in cluster CU

Actual: 535 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	COURT HOUSE SERV	GASOLINE STATIONS
1958	CARLSONS DAVE	GASOLINE STATIONS
1962	COURT HSE HUMBLE	GASOLINE STATIONS

CU445 Target Property | **CARLSON DAVE GA**
907 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013756517**
N/A

Site 2 of 4 in cluster CU

Actual: 535 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	COURT HOUSE SERVICE	GASOLINE AND OIL SERVICE STATIONS
1947	CARLSON DAVE GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1953	CARLSON DAVE GAR	AUTOMOBILE REPAIRING
1958	CARLSON DAVE GA	AUTOMOBILE REPAIRING

CU446 Target Property | **COURT HOUSE SERV**
905 GUADALUPE
AUSTIN, TX | **EDR Hist Auto** | **1013753990**
N/A

Site 3 of 4 in cluster CU

Actual: 534 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	COURT HOUSE SERV	GASOLINE AND OIL SERVICE STATIONS

CV447 Target Property | **JOHNSON & LLOYD TAILORS**
1001 CONGRESS ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013782013**
N/A

Site 1 of 14 in cluster CV

Actual: 516 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	JOHNSON & LLOYD TAILORS	CLOTHES PRESSERS AND CLEANERS

CU448 Target Property | **VIAWEST, INC.**
WEST 9TH STREET
AUSTIN, TX 78701 | **ICIS FINDS** | **1014842326**
N/A

Site 4 of 4 in cluster CU

Actual: 533 ft.

Focus Map: 11

ICIS:

Enforcement Action ID:	HQ-2011-8000
FRS ID:	110043473737
Action Name:	ViaWest, Inc.
Facility Name:	VIAWEST, INC.
Facility Address:	WEST 9TH STREET AUSTIN, TX 78701
Enforcement Action Type:	EPCRA 325 Action For Penalty
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	325
Facility SIC Code:	4813
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.27181
Longitude in Decimal Degrees:	-97.74526
Permit Type Desc:	Not reported
Program System Acronym:	1800054835
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	HQ-2011-8000
FRS ID:	110043473737
Action Name:	ViaWest, Inc.
Facility Name:	VIAWEST, INC.
Facility Address:	WEST 9TH STREET AUSTIN, TX 78701
Enforcement Action Type:	CAA 113D1 Action For Penalty
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	113D1
Facility SIC Code:	4813
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.27181
Longitude in Decimal Degrees:	-97.74526
Permit Type Desc:	Not reported
Program System Acronym:	1800054835
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

FINDS:

Registry ID: 110043473737

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with

VIAWEST, INC. (Continued) **1014842326**

a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CW449 **COMMERCIAL BUILDING** **TX ASBESTOS** **S121062603**
Target **916 CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 3 in cluster CW

Actual:
518 ft.

Focus Map:
11

ASBESTOS:

Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	01/31/2017
Notification Number:	2017000395
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/31/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/31/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N

COMMERCIAL BUILDING (Continued) **S121062603**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	01/30/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	03/01/2016
Notification Number:	2017000395
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/31/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/31/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	02/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	01/31/2017
Notification Number:	2017000395
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/13/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/13/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	01/30/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	11/20/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	01/19/2018
Notification Number:	2017008461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/05/2018
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/07/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	11/20/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	01/07/2018
Notification Number:	2017008461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/01/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/01/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

COMMERCIAL BUILDING (Continued) **S121062603**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	11/20/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	01/08/2018
Notification Number:	2017008461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/05/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/07/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	11/20/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	01/05/2018
Notification Number:	2017008461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/15/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/04/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell

COMMERCIAL BUILDING (Continued) **S121062603**

Violation:	Not reported
Complaint Date:	06/30/2017
Notification Number:	2017002555
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/02/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	06/02/2017
Notification Number:	2017002555
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/31/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/31/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

COMMERCIAL BUILDING (Continued) **S121062603**

Start Date:	05/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/30/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D

COMMERCIAL BUILDING (Continued) **S121062603**

Certification Statement Date:	10/26/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/13/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/26/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/30/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/30/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/25/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/03/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/11/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/11/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/10/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/29/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/09/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/10/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/16/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/12/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

COMMERCIAL BUILDING (Continued) **S121062603**

ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/09/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	COMMERCIAL BUILDING
Address:	916 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/25/2018
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/06/2017
Notification Number:	2017006238
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/22/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

COMMERCIAL BUILDING (Continued) **S121062603**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/22/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/05/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CV450 **VACANT BUILDING** **TX ASBESTOS** **S128931827**
Target **107 E. 10TH STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 14 in cluster CV

Actual:
518 ft.

Focus Map:
11

ASBESTOS:

Name:	VACANT BUILDING
Address:	107 E. 10TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/21/2022
Notification Number:	2022004314
ASB Priority:	Not reported

VACANT BUILDING (Continued) **S128931827**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/18/2022
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	23
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

VACANT BUILDING (Continued) **S128931827**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BUILDING
Address:	107 E. 10TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/21/2022
Notification Number:	2022004314
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/18/2022
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	23
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

VACANT BUILDING (Continued) **S128931827**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CV451 **MODEL LAUNDRY** **EDR Hist Cleaner** **1013782989**
Target Property **919 CONGRESS AVE** **N/A**
AUSTIN, TX

Site 3 of 14 in cluster CV

Actual: 514 ft.
EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1901	PICKETT MARTIN L. PROPR AUSTIN	LAUNDRIES
1906	MODEL LAUNDRY	LAUNDRIES

CV452 **MOBIL CORPORATION** **EDR Hist Auto** **1022226638**
Target Property **919 CONGRESS AVE STE 820** **N/A**
AUSTIN, TX 78701

Site 4 of 14 in cluster CV

Actual: 514 ft.
EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1998	MOBIL CORPORATION	Gasoline Service Stations
1999	MOBIL CORPORATION	Gasoline Service Stations
2001	MOBIL CORPORATION	Gasoline Service Stations
2002	MOBIL CORPORATION	Gasoline Service Stations

---

453 **707 WEST AVE.** **TX ASBESTOS** **S129327259**
Target Property **707 WEST AVE.** **N/A**
AUSTIN, TX 78701

Actual: 472 ft.

Focus Map: 11

ASBESTOS:

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/07/14

707 WEST AVE. (Continued) **S129327259**

Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	07/14/2016
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2016005454
File Number:	10518
License Status Description:	Paid
Expiration Date:	01/10/2017
Original Date:	06/29/2016
Rank Effective Date:	06/29/2016
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	1941
Inspection Status:	Open
Disposition:	I090 - Completed Inspection

707 WEST AVE. (Continued) **S129327259**

Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/14/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported

707 WEST AVE. (Continued) **S129327259**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	01/10/2017
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/14/2016
Certification Statement Phone:	512-778-6069

707 WEST AVE. (Continued) **S129327259**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/20/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

707 WEST AVE. (Continued) **S129327259**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/21/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	08/26/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

707 WEST AVE. (Continued) **S129327259**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/21/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

707 WEST AVE. (Continued) **S129327259**

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/05/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

707 WEST AVE. (Continued) **S129327259**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	09/02/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/05/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N

707 WEST AVE. (Continued) **S129327259**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

707 WEST AVE. (Continued) **S129327259**

Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/12/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	09/16/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

707 WEST AVE. (Continued) **S129327259**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/12/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/29/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell

707 WEST AVE. (Continued) **S129327259**

Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/26/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/26/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

707 WEST AVE. (Continued) **S129327259**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	09/30/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/26/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/26/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

707 WEST AVE. (Continued) **S129327259**

Start Date:	09/12/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A

707 WEST AVE. (Continued) **S129327259**

Certification Statement Date:	09/09/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/14/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

707 WEST AVE. (Continued) **S129327259**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/09/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/26/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported

707 WEST AVE. (Continued) **S129327259**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/22/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

707 WEST AVE. (Continued) **S129327259**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/28/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/22/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/10/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

707 WEST AVE. (Continued) **S129327259**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/06/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

707 WEST AVE. (Continued) **S129327259**

ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	11/04/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

707 WEST AVE. (Continued) **S129327259**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/06/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/24/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

707 WEST AVE. (Continued) **S129327259**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/21/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.

707 WEST AVE. (Continued) **S129327259**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/25/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/21/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

707 WEST AVE. (Continued) **S129327259**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

707 WEST AVE. (Continued) **S129327259**

High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	12/09/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9

707 WEST AVE. (Continued) **S129327259**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/04/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/21/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

707 WEST AVE. (Continued) **S129327259**

Date Report Received:	11/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/18/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	12/23/2016

707 WEST AVE. (Continued) **S129327259**

Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/18/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

707 WEST AVE. (Continued) **S129327259**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/01/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/01/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported

707 WEST AVE. (Continued) **S129327259**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	12/30/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/01/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/01/2016
Certification Statement Phone:	512-778-6069

707 WEST AVE. (Continued) **S129327259**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/12/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

707 WEST AVE. (Continued) **S129327259**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	01/04/2017
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

707 WEST AVE. (Continued) **S129327259**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/14/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

707 WEST AVE. (Continued) **S129327259**

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/12/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

707 WEST AVE. (Continued) **S129327259**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	01/05/2017
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/12/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N

707 WEST AVE. (Continued) **S129327259**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

707 WEST AVE. (Continued) **S129327259**

Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/13/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	01/06/2017
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

707 WEST AVE. (Continued) **S129327259**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/13/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/16/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell

707 WEST AVE. (Continued) **S129327259**

Violation:	Not reported
Complaint Date:	07/22/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/29/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

707 WEST AVE. (Continued) **S129327259**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	707 WEST AVE.
Address:	707 WEST AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	07/14/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	07/29/2016
Notification Number:	2016005454
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/29/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	97
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

707 WEST AVE. (Continued) **S129327259**

Start Date:	07/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CX454 **701 RIO GRANDE** **TX ASBESTOS** **S125921394**
Target **701 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 2 in cluster CX

Actual:
488 ft.

Focus Map:
11

ASBESTOS:

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	11/14/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/29/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/29/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/30/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/06/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/13/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/13/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019

701 RIO GRANDE (Continued) **S125921394**

Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/06/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/13/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/13/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/09/04
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Analytical Method:	Not reported
Start Date:	09/04/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019006199
File Number:	44373
License Status Description:	Paid
Expiration Date:	11/15/2019
Original Date:	08/13/2019
Rank Effective Date:	08/13/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	18985
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment

701 RIO GRANDE (Continued) **S125921394**

Work Type Flag:	A
Certification Statement Date:	11/04/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	11/15/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2019
Date Routed by Supervisor:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/04/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/30/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/06/2019
Notification Number:	2019006199
ASB Priority:	Not reported

701 RIO GRANDE (Continued) **S125921394**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/13/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/13/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/06/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/13/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/13/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

701 RIO GRANDE (Continued) **S125921394**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/13/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/19/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07

701 RIO GRANDE (Continued) **S125921394**

Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/13/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/19/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/09/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/19/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE

701 RIO GRANDE (Continued) **S125921394**

Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/13/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/19/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/10/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/10/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

701 RIO GRANDE (Continued) **S125921394**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/25/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

701 RIO GRANDE (Continued) **S125921394**

Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/10/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

701 RIO GRANDE (Continued) **S125921394**

Inspector Name:	Not reported
Date Report Received:	09/16/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/16/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Complaint Date:	09/27/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/16/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/16/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/23/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/23/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019

701 RIO GRANDE (Continued) **S125921394**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	10/02/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/23/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/23/2019

701 RIO GRANDE (Continued) **S125921394**

Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/24/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/24/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	10/08/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/24/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/24/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/30/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/30/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	10/14/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/30/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/30/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13

701 RIO GRANDE (Continued) **S125921394**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/07/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/07/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/07/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	10/21/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/07/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/07/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/14/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701

701 RIO GRANDE (Continued) **S125921394**

Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/11/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	10/25/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/11/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

701 RIO GRANDE (Continued) **S125921394**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)

701 RIO GRANDE (Continued) **S125921394**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/17/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	11/11/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/17/2019

701 RIO GRANDE (Continued) **S125921394**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/17/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199

701 RIO GRANDE (Continued) **S125921394**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/25/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/25/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	11/11/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/25/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/25/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/29/2019
Client Code:	Not reported
Client Name:	Not reported

701 RIO GRANDE (Continued) **S125921394**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/28/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N

701 RIO GRANDE (Continued) **S125921394**

Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	11/14/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/28/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/31/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	701 RIO GRANDE
Address:	701 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/04/2019
Reason for Inspection:	Kevin Nichols
Violation:	Not reported
Complaint Date:	09/18/2019
Notification Number:	2019006199
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

701 RIO GRANDE (Continued) **S125921394**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/29/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/29/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	13
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CY455 Target Property | **FAULK LIBRARY BUILDING**
800 GUADALUPE STREET
AUSTIN, TX 78701 | **TX ASBESTOS** | **S129159870**
N/A

Site 1 of 4 in cluster CY

Actual: 534 ft.

Focus Map: 11

ASBESTOS:

Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erin M Oppermann
Violation:	Not reported
Complaint Date:	12/30/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/21/2022
Certification Statement Phone:	817-266-3774
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	197
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported

FAULK LIBRARY BUILDING (Continued) **S129159870**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Kelsey Stone
Violation:	Not reported
Complaint Date:	12/30/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/23/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/23/2022
Certification Statement Phone:	512-705-2130
Is The Facility a School or K-12?:	N

FAULK LIBRARY BUILDING (Continued) **S129159870**

Region:	07
Priority:	HIGH
ARU:	165
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erin M Oppermann
Violation:	Not reported
Complaint Date:	11/30/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/25/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

FAULK LIBRARY BUILDING (Continued) **S129159870**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/25/2022
Certification Statement Phone:	817-266-3774
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	165
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erin M Oppermann
Violation:	Not reported
Complaint Date:	11/30/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

FAULK LIBRARY BUILDING (Continued) **S129159870**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/09/2022
Certification Statement Phone:	817-266-3774
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	165
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FAULK LIBRARY BUILDING (Continued) **S129159870**

Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Pedro Meza
Violation:	Not reported
Complaint Date:	12/16/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/29/2022
Certification Statement Phone:	512-596-8485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	165
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

FAULK LIBRARY BUILDING (Continued) **S129159870**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FAULK LIBRARY BUILDING
Address:	800 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Kelsey Stone
Violation:	Not reported
Complaint Date:	12/23/2022
Notification Number:	2022006781
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/14/2022
Certification Statement Phone:	512-705-2130
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	165
Is this a phased abatement project?:	Y
Ordered:	N

FAULK LIBRARY BUILDING (Continued) **S129159870**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CY456 **JOHN HENRY FAULK BRANCH LIBRARY** **TX ASBESTOS** **S122569437**
Target **800 GUADALUPE** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 4 in cluster CY

Actual:
534 ft.

Focus Map:
11

ASBESTOS:

Name:	JOHN HENRY FAULK BRANCH LIBRARY
Address:	800 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Arthur Daniel Potts
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018005079
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/18/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

JOHN HENRY FAULK BRANCH LIBRARY (Continued) **S122569437**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/18/2018
Certification Statement Phone:	512-972-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CZ457 **HUMBLE OIL & REFINING CO.** **TX HIST UST** **S111678685**
Target **719 W 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 9 in cluster CZ

Actual:
465 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	HUMBLE OIL & REFINING CO.
Address:	719 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0240
HID UST:	240
Inspection:	03/26/2010

HUMBLE OIL & REFINING CO. (Continued) **S111678685**

Due: 03/26/2013

DA458 Target Property **KATZ & ATLAS**
618 W 6TH ST
AUSTIN, TX 78701

TX CENTRAL REGISTRY **S126523700**
N/A

Site 1 of 25 in cluster DA

Actual: 477 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101491736
Name:	KATZ & ATLAS
Address:	618 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2706
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600780324
Customer Name:	M & M KATZ INC
Customer Legal Name:	M & M Katz, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/4/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

DA459 Target Property **KATZ & ATLAS**
618 W 6TH ST
AUSTIN, TX 78701

TX UST **U001279854**
TX HIST UST **N/A**

Site 2 of 25 in cluster DA

Actual: 477 ft.
Focus Map: 11

UST:

Name:	KATZ & ATLAS
Address:	618 W 6TH ST
City,State,Zip:	AUSTIN, TX 787012706
AI Number:	48781
Facility Type:	UNKNOWN
Facility Begin Date:	08/04/1989
Facility Status:	INACTIVE
Additional ID:	974594802002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DON HEIMBECRON,CONSULTANT
Contact Organization Name:	KATZ & ATLAS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

KATZ & ATLAS (Continued) **U001279854**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124722037
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/19/1989
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	07/26/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780324
Owner Last Name:	M & M KATZ INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	965594792002053
Additional ID:	974594802002053
AI Number:	48781
Owner Effective Begin Date:	08/04/1989
State Tax ID:	17420679643
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1939
Tank Registration Date:	07/26/1989
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	126849
Facility ID:	80508
Ai Number:	48781
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	07/27/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

KATZ & ATLAS (Continued) **U001279854**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	Y
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/01/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	131480
UST ID:	126849
AI Number:	48781
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

KATZ & ATLAS (Continued) **U001279854**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	KATZ & ATLAS INC
Contact Mailing Address (Delivery):	618 W 6TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2706
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80508
Additional ID:	974594802002053
Princ ID:	965594792002053
AI Number:	48781
Facility Name:	KATZ & ATLAS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	KATZ"S DELI
Address:	618 W 6TH ST
City,State,Zip:	AUSTIN, TX

KATZ & ATLAS (Continued) **U001279854**

Id UST: 3364
HID UST: Not reported
Inspection: Not reported
Due: Not reported

CZ460 **507 WEST AVENUE** **TX GCC** **S128127743**
Target **507 WEST AVENUE** **N/A**
Property **AUSTIN, TX**

Site 2 of 9 in cluster CZ

Actual:
465 ft.

Focus Map:
11

GCC:
Name: 507 WEST AVENUE
Address: 507 WEST AVENUE
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 942
Contamination Description: VOCS, HEAVY METALS
Date Of Earliest Known Contamination Confirmation: 12/8/2014
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 507 WEST AVENUE
Address: 507 WEST AVENUE
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: *
File Number: 942
Contamination Description: VOCS, HEAVY METALS
Date Of Earliest Known Contamination Confirmation: 10/20/2014
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

CZ461 **507 WEST AVENUE** **TX IOP** **S123569372**
Target **507 WEST AVE** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 9 in cluster CZ

Actual:
465 ft.

Focus Map:
11

IOP:

Name:	507 WEST AVENUE
Address:	507 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Program ID:	942
Date IOP Received:	Not reported
Region:	REGION 11 - AUSTIN
Phase:	COMPLETED
Interest In Site:	Not reported
PCA Number:	32942
Property Use:	PARKING/TRANSIT CENTER
Project Manager:	EJIMENEZ
Project Number:	329420
Latitude:	30.27
Longitude:	-97.75
Acres:	0.097
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	03/31/2015
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN107853137
Consultant/Attorney Phone:	Not reported
Site Address Description:	Not reported
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	10/20/2014
Application Received Date:	10/20/2014
Application Acceptance Date:	12/08/2014
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	BUTYLBENZENE, TERT-; XYLENES; MTBE
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER

507 WEST AVENUE (Continued) **S123569372**

File Location:	D2/200-22
Customer:	
REM Program:	IOP
Program ID:	942
RN Number:	RN107853137
CN Number:	CN604707687
CN Name:	507 WEST AVENUE LP
Role CD:	APPLCONT
Contact Name:	SMITHEAL, JEREMY
Contact Title:	MANAGER
Organization Name:	Not reported
Mailing Address:	100 CONGRESS AVE STE 780
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78701
Contact Phone:	(512) 476-7806
Contact Ext:	0

Name:	507 WEST AVENUE
Address:	507 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Program ID:	1120
Date IOP Received:	Not reported
Region:	REGION 11 - AUSTIN
Phase:	COMPLETED
Interest In Site:	Not reported
PCA Number:	61120
Property Use:	PROPERTY
Project Manager:	AWEINRIC
Project Number:	611200
Latitude:	30.27
Longitude:	-97.75
Acres:	0.0999
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	01/10/2020
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN107853137

507 WEST AVENUE (Continued) **S123569372**

Consultant/Attorney Phone:	Not reported
Site Address Description:	Not reported
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	03/15/2019
Application Received Date:	03/15/2019
Application Acceptance Date:	04/26/2019
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	MTBE (METHYL TERT-BUTYL ETHER)
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	ELECTRONIC AND PAPER
File Location:	D-290

Customer:

REM Program:	IOP
Program ID:	1120
RN Number:	RN107853137
CN Number:	CN605641042
CN Name:	506 WEST AVENUE LP
Role CD:	APPLCONT
Contact Name:	LECKTEIG, JOSH
Contact Title:	Not reported
Organization Name:	MANIFOLD REAL ESTATE
Mailing Address:	PO BOX 200463
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78720
Contact Phone:	(512) 422-6036
Contact Ext:	0

CZ462 **507 WEST AVENUE** **TX GCC** **S128127742**
Target **507 WEST AVE** **N/A**
Property **AUSTIN, TX**

Site 4 of 9 in cluster CZ

Actual:
465 ft.

Focus Map:
11

GCC:

Name:	507 WEST AVENUE
Address:	507 WEST AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/VCIOP
New Cases:	*
File Number:	1120
Contamination Description:	MTBE
Date Of Earliest Known Contamination Confirmation:	10/9/2014
Enforcement Status - Level Of Agency Response:	-
Enforcement Status - Site Activity Status:	6C -
Data Quality 1:	Not reported
Section 5236:	Not reported
Type:	2019 GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported

507 WEST AVENUE (Continued) **S128127742**

Location: Not reported
Data Quality 2: Not reported

Name: 507 WEST AVENUE
Address: 507 WEST AVE
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 1120
Contamination Description: MTBE
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2019
Location: Not reported
Data Quality 2: Not reported

Name: 507 WEST AVENUE
Address: 507 WEST AVE
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 1120
Contamination Description: MTBE
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2019
Location: Not reported
Data Quality 2: Not reported

CZ463 **507 WEST AVENUE** **TX CENTRAL REGISTRY** **S126876677**
Target **507 WEST AVE** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 9 in cluster CZ

Actual:
465 ft.

Focus Map:
11

CENTRAL REGISTRY:
Regulated Entity Number: RN107853137
Name: 507 WEST AVENUE
Address: 507 WEST AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-2734
Status: ACTIVE
Status Date: 11/21/2014
Customer Number: CN604707687
Customer Name: 507 WEST AVENUE LP
Customer Legal Name: 507 West Avenue, LP

507 WEST AVENUE (Continued) **S126876677**

Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	10/20/2014
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107853137
Name:	507 WEST AVENUE
Address:	507 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2734
Status:	ACTIVE
Status Date:	11/21/2014
Customer Number:	CN604707687
Customer Name:	507 WEST AVENUE LP
Customer Legal Name:	507 West Avenue, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	10/20/2014
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107853137
Name:	507 WEST AVENUE
Address:	507 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2734
Status:	ACTIVE
Status Date:	11/21/2014
Customer Number:	CN605641042
Customer Name:	506 WEST AVENUE LP
Customer Legal Name:	506 West Avenue, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	3/15/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107853137
Name:	507 WEST AVENUE
Address:	507 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2734
Status:	ACTIVE
Status Date:	11/21/2014
Customer Number:	CN605641042
Customer Name:	506 WEST AVENUE LP
Customer Legal Name:	506 West Avenue, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	3/15/2019
Affiliation End Date:	12/31/3000

507 WEST AVENUE (Continued) **S126876677**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

DB464 **TEXAS AMERICAN 220 GULF COAST BASIN** **PFAS ECHO** **1027427800**
Target Property **AUSTIN, TX** **N/A**

Site 1 of 11 in cluster DB

Actual: 503 ft.

Focus Map: 11

PFAS ECHO:

Name:	TEXAS AMERICAN 220 GULF COAST BASIN
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.269773
Longitude:	-97.741786
Count:	1
County:	Not reported
Status:	Unknown
Region:	06
Industry:	Oil and Gas
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071162100
Facility Percent Minority:	-
Facility Derived Tribes:	-
Facility Population:	-
EPA Programs:	-
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	Zip Code Centroid
Facility Derived HUC:	-
Facility Derived WBD:	-
Facility Derived CD113:	-
Facility Derived CB2010:	-
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	-
Facility Programs With SNC:	0
Facility Compliance Status:	-
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N

TEXAS AMERICAN 220 GULF COAST BASIN (Continued) **1027427800**

GHG Flag:	Y
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	-
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.741786,%22y%22:30.269773,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

DB465 **BERGSTROM AIR FORCE BASE** **PFAS ECHO** **1027331663**
Target Property **N/A**
AUSTIN, TX

Site 2 of 11 in cluster DB

Actual: 503 ft.

Focus Map: 11

PFAS ECHO:

Name:	BERGSTROM AIR FORCE BASE
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.269773
Longitude:	-97.741786
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110064117218
Facility Percent Minority:	-
Facility Derived Tribes:	-
Facility Population:	-
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	Zip Code Centroid
Facility Derived HUC:	-
Facility Derived WBD:	-
Facility Derived CD113:	-

BERGSTROM AIR FORCE BASE (Continued) **1027331663**

Facility Derived CB2010:	-
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TX0000381657
RCRA Permit Types:	Other
RCRA NAICS:	488119
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	-
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.741786,%22y%22:30.269773,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

DA466 **KELLY SMITH OWNER** **TX HIST UST** **S111678712**
Target **617 W 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 25 in cluster DA

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	KELLY SMITH OWNER
Address:	617 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0124
HID UST:	124
Inspection:	10/22/2010
Due:	10/22/2013

DA467 **MAGNOLIA PETROLEUM COMP.** **TX HIST UST** **S111678743**
Target **617 W 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 25 in cluster DA

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM COMP.
Address:	617 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0198
HID UST:	198
Inspection:	04/24/2009
Due:	04/24/2012

DA468 **DICKERSON CINS** **EDR Hist Cleaner** **1013778869**
Target **511 RIO GRANDE** **N/A**
Property **AUSTIN, TX**

Site 5 of 25 in cluster DA

Actual:
474 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1947	DICKERSON CLEANERS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1953	DICKERSON CINS	CLEANERS AND DYERS
1958	DICKERSON CLEANERS	CLEANERS AND DYERS

DA469 **AMERICAN CLEANERS** **TX CENTRAL REGISTRY** **S126744732**
Target **511 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 6 of 25 in cluster DA

Actual:
474 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN104955513
Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2715

AMERICAN CLEANERS (Continued) **S126744732**

Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600404552
Customer Name:	JOASH ENTERPRISES INC
Customer Legal Name:	Joash Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104955513
Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2715
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600404552
Customer Name:	JOASH ENTERPRISES INC
Customer Legal Name:	Joash Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104955513
Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2715
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600404552
Customer Name:	JOASH ENTERPRISES INC
Customer Legal Name:	Joash Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104955513
Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2715
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600404552

AMERICAN CLEANERS (Continued) **S126744732**

Customer Name:	JOASH ENTERPRISES INC
Customer Legal Name:	Joash Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN104955513
Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2715
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600404552
Customer Name:	JOASH ENTERPRISES INC
Customer Legal Name:	Joash Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

DA470 **AMERICAN CLEANERS** **TX DRYCLEANERS** **S108995455**
Target **511 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 7 of 25 in cluster DA

Actual:
474 ft.

Focus Map:
11

DRYCLEANERS:

Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104955513
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

AMERICAN CLEANERS (Continued) **S108995455**

Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104955513
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104955513
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	511 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104955513
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported

AMERICAN CLEANERS (Continued) **S108995455**

Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

DA471 **AMERICAN CLEANERS** **FINDS** **1010743479**
Target **511 RIO GRANDE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 8 of 25 in cluster DA

Actual:
474 ft.

Focus Map:
11

FINDS:
Registry ID: 110033464542

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DC472 **DR PEPPER BOTTLING CO.** **TX HIST UST** **S128729437**
Target **718 W 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 11 in cluster DC

Actual:
464 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DR PEPPER BOTTLING CO.
Address:	718 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0833
HID UST:	833
Inspection:	Not reported
Due:	06/01/2012

DC473 **DR PEPPER BOTTLING CO.** **TX HIST UST** **S128729272**
Target **718 W 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 11 in cluster DC

Actual:
464 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DR PEPPER BOTTLING CO.
Address:	718 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0414
HID UST:	414
Inspection:	Not reported
Due:	06/01/2012

DD474 **AMERICAN TAXI CAB CO.** **TX HIST UST** **S111678555**
Target **610 W 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 6 in cluster DD

Actual:
469 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	AMERICAN TAXI CAB CO.
Address:	610 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0458
HID UST:	458
Inspection:	Not reported
Due:	06/01/2012

DD475 **CAPITAL PETROLEUM PRODUCTS** **TX HIST UST** **S111678595**
Target **610 W 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 6 in cluster DD

Actual:
469 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CAPITAL PETROLEUM PRODUCTS
Address:	610 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0113
HID UST:	113
Inspection:	Not reported
Due:	06/01/2012

DE476 **RTC** **TX HIST UST** **S128729026**
Target **400 W 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 13 in cluster DE

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	RTC
Address:	400 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0417
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DF477 **FIX IT SHOP THE** **EDR Hist Auto** **1013757207**
Target **123 7TH W** **N/A**
Property **AUSTIN, TX**

Site 1 of 25 in cluster DF

Actual:
499 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1916	FIX IT SHOP THE	AUTOMOBILE REPAIRERS

DF478 **120 22 NORWOOD MOTORAMP INC** **EDR Hist Auto** **1013764951**
Target **120 7TH W** **N/A**
Property **AUSTIN, TX**

Site 2 of 25 in cluster DF

Actual:
499 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	120 22 NORWOOD MOTORAMP INC	AUTOMOBILE REPAIRERS
1929	120 22 NORWOOD MOTORAMP INC	AUTOMOBILE GARAGES

DF479 **MOTORAMP STORAGE** **EDR Hist Auto** **1013755817**
Target **118 7TH W** **N/A**
Property **AUSTIN, TX**

Site 3 of 25 in cluster DF

Actual:
499 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	118 20 MOTORAMP GARAGE	AUTOMOBILE GARAGES
1940	MOTORAMP STORAGE	AUTOMOBILE GARAGES

DF480 Target Property — **A CLEANERS & DYERS**, **119 7TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013781161** / **N/A**

Site 4 of 25 in cluster DF

Actual: 499 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	A CLEANERS & DYERS	CLOTHES CLEANERS AND PRESSERS

DE481 Target Property — **SHIRLEY N A CLNRS**, **407 6TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783335** / **N/A**

Site 2 of 13 in cluster DE

Actual: 494 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	KOCH C A DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1940	KOCH C A CLDO	CLOTHES PRESSERS AND CLEANERS
1947	SHIRLEY N A CLNRS	CLOTHES PRESSERS AND CLEANERS

DE482 Target Property — **KOCH CLEANING & DYING**, **405 6TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783308** / **N/A**

Site 3 of 13 in cluster DE

Actual: 495 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	KOCH CLEANING & DYING	CLOTHES CLEANERS AND PRESSERS
1940	LEWIS GARNETT CLO CLNR	CLOTHES PRESSERS AND CLEANERS

DE483 Target Property — **ALAMO HOTEL GARAGE**, **402 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774263** / **N/A**

Site 4 of 13 in cluster DE

Actual: 495 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	ALAMO HOTEL GARAGE	AUTOMOBILE GARAGES
1935	ALAMO HOTEL GARAGE	AUTOMOBILE GARAGES

DE484 Target Property — **PATSCHKE ALAMO**, **400 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013757627**, **N/A**

Site 5 of 13 in cluster DE

Actual: 495 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	JOHNSON A G	AUTOMOBILE REPAIRING
1958	PATSCHKE ALAMO	AUTOMOBILE REPAIRING
1962	PATSCHKES ALAMO	AUTOMOBILE REPAIRING

DE485 Target Property — **GRAYBURG OIL CO STA NO**, **401 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013772220**, **N/A**

Site 6 of 13 in cluster DE

Actual: 495 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	GRAYBURG OIL CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1935	ROGERS OIL CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	RAYS SERVICE STA FILLING ST	GASOLINE AND OIL SERVICE STATIONS

DG486 Target Property — **MASTER VALET CLEANERS**, **109 E 7TH ST**, **TRAVIS (County), TX 78701** — **EDR Hist Cleaner** — **1013779391**, **N/A**

Site 1 of 16 in cluster DG

Actual: 497 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1970	MASTER VALET CLEANERS	CLEANERS AND DYERS

DG487 Target Property — **DRISKILL HOTEL STEAM LAUNDRY**, **113 E 7TH ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013778925**, **N/A**

Site 2 of 16 in cluster DG

Actual: 498 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1901	DRISKILL HOTEL STEAM LAUNDRY	LAUNDRIES

DG488 Target Property | **JLR CLEANERS**
612 BRAZOS STREET
AUSTIN, TX 78701 | **US AIRS**
FINDS
ECHO | **1004601120**
N/A

Site 3 of 16 in cluster DG

Actual: 500 ft.

Focus Map: 11

US AIRS MINOR:

Envid:	1004601120
Region Code:	06
Programmatic ID:	AIR 06000000484536E022
Facility Registry ID:	110001875061
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	06
Programmatic ID:	AIR 06000000484536E022
Facility Registry ID:	110001875061
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	1997-06-11 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:

Registry ID: 110001875061

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004601120
Registry ID:	110001875061
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001875061
Name:	JLR CLEANERS

JLR CLEANERS (Continued) **1004601120**

Address: 612 BRAZOS STREET
City,State,Zip: AUSTIN, TX 78701

DG489 **DAVIS MAX DCLO CLNR** **EDR Hist Cleaner** **1013779733**
Target **612 BRAZOS ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 16 in cluster DG

Actual:
500 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	DAVIS MAX DCLO CLNR	CLOTHES CLEANERS AND PRESSERS
1989	T M CLEANERS & PHOTO SER	Drycleaning Plants, Except Rugs
1990	T M CLEANERS & PHOTO SERVICES C	CLEANERS AND DYERS
1991	T M CLEANERS & PHOTO SER	Drycleaning Plants, Except Rugs
1992	T M CLEANERS & PHOTO SERVICE	Drycleaning Plants, Except Rugs

---

DG490 **VACANT OFFICE BUILDING** **TX ASBESTOS** **S129336431**
Target **612 BRAZOS** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 16 in cluster DG

Actual:
500 ft.

ASBESTOS:

Focus Map:
11

Name:	VACANT OFFICE BUILDING
Address:	612 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	GREG BROOKS
Violation:	Not reported
Complaint Date:	11/08/2016
Notification Number:	2016008746
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/08/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

VACANT OFFICE BUILDING (Continued) **S129336431**

Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT OFFICE BUILDING
Address:	612 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	GREG BROOKS
Violation:	Not reported
Complaint Date:	11/08/2016
Notification Number:	2016008746
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

VACANT OFFICE BUILDING (Continued) **S129336431**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/20/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DH491 Target Property | **DICKERSON DRY CLEANING**
600 N CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678627**
N/A

Site 1 of 16 in cluster DH

Actual: 496 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	DICKERSON DRY CLEANING
Address:	600 N CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0181
HID UST:	181
Inspection:	04/16/2009
Due:	04/16/2012

DI492 Target Property | **B & N AXEL SERV**
503 GUADALUPE
AUSTIN, TX | **EDR Hist Auto** | **1013765365**
N/A

Site 1 of 9 in cluster DI

Actual: 491 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1953	B & N AXEL SERV	AUTOMOBILE REPAIRING

DJ493 Target Property | **LYM ARCHITECTURE BLDG**
610 BRAZOS
AUSTIN, TX 78704 | **TX ASBESTOS** | **S125922481**
N/A

Site 1 of 7 in cluster DJ

Actual: 499 ft.
Focus Map: 11

ASBESTOS:

Name:	LYM ARCHITECTURE BLDG
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	01/17/2020
Notification Number:	2020000345
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

LYM ARCHITECTURE BLDG (Continued) **S125922481**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/17/2020
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LYM ARCHITECTURE BLDG
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	01/19/2020
Notification Number:	2020000345
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

LYM ARCHITECTURE BLDG (Continued) **S125922481**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/02/2020
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

LYM ARCHITECTURE BLDG (Continued) **S125922481**

Inspection Number Grade:	Not reported
Name:	LYM ARCHITECTURE BLDG
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	06/10/2020
Reason for Inspection:	ROBERT ABBOTT
Violation:	Not reported
Complaint Date:	11/09/2019
Notification Number:	2019008102
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/25/2019
Certification Statement Phone:	512-515-0705
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/08/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

LYM ARCHITECTURE BLDG (Continued) **S125922481**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DJ494 **OFFICE BUILDING** **TX ASBESTOS** **S123438551**
Target **610 BRAZOS** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 7 in cluster DJ

Actual:
499 ft.

Focus Map:
11

ASBESTOS:

Name:	OFFICE BUILDING
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/12/17
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

OFFICE BUILDING (Continued) **S123438551**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	12/17/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018008682
File Number:	36241
License Status Description:	Paid
Expiration Date:	01/04/2019
Original Date:	11/29/2018
Rank Effective Date:	11/29/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	13617
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

Name:	OFFICE BUILDING
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	12/17/2018
Reason for Inspection:	Paul B Dehlinger
Violation:	Not reported
Complaint Date:	01/04/2019
Notification Number:	2018008682
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

OFFICE BUILDING (Continued) **S123438551**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/11/2018
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	60
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	OFFICE BUILDING
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	12/17/2018
Reason for Inspection:	PAUL BYRON DEHLINGER
Violation:	Not reported
Complaint Date:	12/28/2018
Notification Number:	2018008682
ASB Priority:	Not reported
PIF State:	Not reported

OFFICE BUILDING (Continued) **S123438551**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/29/2018
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	60
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/13/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

OFFICE BUILDING (Continued) **S123438551**

Results:	Not reported
Inspection Number Grade:	Not reported

DJ495 Target Property **LYM ARCHITECTURE BUILDING**
610 BRAZOS
AUSTIN, TX 78701

TX ASBESTOS **S125392456**
N/A

Site 3 of 7 in cluster DJ

Actual: 499 ft.

Focus Map: 11

ASBESTOS:

Name:	LYM ARCHITECTURE BUILDING
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Paul B Dehlinger
Violation:	Not reported
Complaint Date:	03/21/2019
Notification Number:	2019001430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/12/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/12/2019
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	62
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment

LYM ARCHITECTURE BUILDING (Continued) **S125392456**

Analytical Method:	PLM
Start Date:	02/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LYM ARCHITECTURE BUILDING
Address:	610 BRAZOS
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Paul Dehlinger
Violation:	Not reported
Complaint Date:	03/15/2019
Notification Number:	2019001430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/21/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment

LYM ARCHITECTURE BUILDING (Continued) **S125392456**

Work Type Flag:	A
Certification Statement Date:	02/21/2019
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	53
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DH496 **J HARPER STARR BLDG PARKING LOT** **TX RDR** **S127542872**
Target **106 W 6TH** **N/A**
Property **AUSTIN, TX**

Site 2 of 16 in cluster DH

Actual:
495 ft.

Focus Map:
11

RDR:

RDR ID:	13366
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	J HARPER STARR BLDG PARKING LOT
Address:	106 W 6TH
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/8/2004
Due Date:	6/7/2004
Tank Owner:	TEXAS BLDG & PROCUREMENT
Contact Person:	Not reported
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Bob Patton
Team:	#N/A

J HARPER STARR BLDG PARKING LOT (Continued) **S127542872**

New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	REP
Date Release Reported:	Not reported
Suspected:	I
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DK497 **SOUTHWEST TOWERS** **TX ASBESTOS** **S121064045**
Target **211 E 7TH** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 7 in cluster DK

Actual:
513 ft.

Focus Map:
11

ASBESTOS:

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/25/2017
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	05/25/2017
Notification Number:	2017003520
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/05/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N

SOUTHWEST TOWERS (Continued) **S121064045**

Region:	07
Priority:	HIGH
ARU:	56
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/17/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/05/18
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

SOUTHWEST TOWERS (Continued) **S121064045**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/18/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017003520
File Number:	19975
License Status Description:	Paid
Expiration Date:	05/25/2017
Original Date:	05/09/2017
Rank Effective Date:	05/09/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	6219
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

DK498 **MCI- AUSXTX (TXAUSXTX)** **TX TIER 2** **S112009491**
Target **211 E 7TH ST FL 9** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 7 in cluster DK

Actual:
513 ft.

Focus Map:
11

TIER 2:

Facility Id/Name:	FATR2012TXAUSXTX/MCI- AUSXTX (TXAUSXTX)
Reporting Year:	2012
Facility Country:	US
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	1/3/2013
Mailing Address:	2400 North Glenville

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Mailing City/State/Country:	Richardson, TX US
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	No
State Fees Total:	Not reported
Number Of Employess On Site:	0
Site Map:	Not reported
Fire District:	Austin Fire Department ID: 3275
Submitted By:	Jason Weller - Manager, Global EH&S Compliance
Latitude:	30.268908
Longitude:	-97.740448
Lat/Long Location Desc:	CE - Center of Facility
Lat/Long Method:	A1 - Address Matching (House Number)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR2011TXAUSXTX/MCI- AUSXTX (TXAUSXTX)
Reporting Year:	2011
Facility Country:	US
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	1/3/2012
Mailing Address:	2400 North Glenville
Mailing City/State/Country:	Richardson, TX US
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	No
State Fees Total:	Not reported
Number Of Employess On Site:	0
Site Map:	Not reported
Fire District:	Austin Fire Department ID: 3275
Submitted By:	Jason Weller
Latitude:	30.268908
Longitude:	-97.740448
Lat/Long Location Desc:	CE - Center of Facility
Lat/Long Method:	A1 - Address Matching (House Number)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	517110
Id Type:	NAICS
Description:	Not reported
Last Modified:	1/3/2013
Id:	4813

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Id Type:	SIC
Description:	TELEPHONE COM, EXCEPT RADIO
Last Modified:	1/3/2013
Id:	132745892
Id Type:	EIN #
Description:	Not reported
Last Modified:	1/3/2013
Id:	020289070
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/3/2013

Contact:

Contact Email:	bruce.ward@verizon.com
Contact Mail Address:	1515 Aldine-Meadows Rd
Contact City/State/Zip:	Houston, TX
Contact Mail Country:	US
Contact Type 1:	Emergency Contact
Contact Name:	Carl Ward
Title:	Property Manager
Modification Date:	2/23/2013

Contact Email:	bruce.ward@verizon.com
Contact Mail Address:	1515 Aldine-Meadows Rd
Contact City/State/Zip:	Houston, TX
Contact Mail Country:	US
Contact Type 1:	Emergency Contact
Contact Name:	Carl Ward
Title:	Property Manager
Modification Date:	2/23/2013

Contact:

Contact Email:	jason.weller@verizon.com
Contact Mail Address:	2400 North Glenville
Contact City/State/Zip:	Richardson, TX 75082
Contact Mail Country:	US
Contact Type 1:	Owner / Operator
Contact Name:	Jason Weller
Title:	- Manager, Global EH&S Compliance
Modification Date:	2/24/2013

Contact Email:	jason.weller@verizon.com
Contact Mail Address:	2400 North Glenville
Contact City/State/Zip:	Richardson, TX 75082
Contact Mail Country:	US
Contact Type 1:	Owner / Operator
Contact Name:	Jason Weller
Title:	- Manager, Global EH&S Compliance
Modification Date:	2/24/2013

Contact:

Contact Email:	jason.weller@verizon.com
Contact Mail Address:	2400 North Glenville
Contact City/State/Zip:	Richardson, TX 75082

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Contact Mail Country:	US
Contact Type 1:	Emergency Contact
Contact Name:	Jason Weller
Title:	Manager
Modification Date:	2/24/2013
Contact Email:	jason.weller@verizon.com
Contact Mail Address:	2400 North Glenville
Contact City/State/Zip:	Richardson, TX 75082
Contact Mail Country:	US
Contact Type 1:	Emergency Contact
Contact Name:	Jason Weller
Title:	Manager
Modification Date:	2/24/2013

Chemical Inventory:

Facility Id:	FATR2012TXAUSXTX
Chemical Name:	LEAD ACID BATTERIES
Chemical Inv Record Id:	TXAUSXTX91443
CAS Number:	7664-93-9
Chemical Same As Last Year:	N
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	424
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/23/2013
Days On Site:	365
Fire Hazard:	T
Gas:	F
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	F
Pure Form:	F
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	TXAUSXTX91443386070
Chemical Inventory Record Id:	TXAUSXTX91443
Amt Of Sub Stored Or Transported:	10176
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside-Main Bldg - Basement
Last Modified:	2/23/2013
Record Key:	TXAUSXTX91443386489
Chemical Inventory Record Id:	TXAUSXTX91443
Amt Of Sub Stored Or Transported:	24000

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside-Main Bldg - 900
Last Modified: 2/23/2013

Record Key: TXAUSXTX91443387367
Chemical Inventory Record Id: TXAUSXTX91443
Amt Of Sub Stored Or Transported: 12.4
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside-Main Bldg - Fire Panel
Last Modified: 2/23/2013

Record Key: TXAUSXTX91443387369
Chemical Inventory Record Id: TXAUSXTX91443
Amt Of Sub Stored Or Transported: 59.5
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside-Main Bldg - Gen start bat
Last Modified: 2/23/2013

Mixture:
Record Key: TXAUSXTX9144377860
Chemical Inv Record Id: TXAUSXTX91443
Mix Chemical: SULFURIC ACID
Percentage: 6.35
Facility Id: FATR2012TXAUSXTX
Mixture Cas: 7664-93-9
Weight/Volume: Wt
Mixture Ehs: T
Mixture Last Modified: 2/23/2013

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 020289070
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 1/3/2012
Id: 132745892
Id Type: EIN #
Description: Not reported
Last Modified: 1/3/2012
Id: 517110
Id Type: NAICS
Description: Not reported
Last Modified: 1/3/2012
Id: 4813

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Id Type: SIC
Description: TELEPHONE COM, EXCEPT RADIO
Last Modified: 1/3/2012

Contact:
Contact Email: wimburne.phinney@one.verizon.com
Contact Mail Address: 1515 Irene Drive
Contact City/State/Zip: Irving, TX
Contact Mail Country: US
Contact Type 1: Emergency Contact
Contact Name: Wimburne Phinney
Title: Property Manager
Modification Date: 3/30/2012

Contact Email: wimburne.phinney@one.verizon.com
Contact Mail Address: 1515 Irene Drive
Contact City/State/Zip: Irving, TX
Contact Mail Country: US
Contact Type 1: Emergency Contact
Contact Name: Wimburne Phinney
Title: Property Manager
Modification Date: 3/30/2012

Contact:
Contact Email: jason.weller@verizon.com
Contact Mail Address: 2400 North Glenville
Contact City/State/Zip: Richardson, TX 75082
Contact Mail Country: US
Contact Type 1: Owner / Operator
Contact Name: Jason Weller
Title: - Manager, Global EH&S Compliance
Modification Date: 3/30/2012

Contact Email: jason.weller@verizon.com
Contact Mail Address: 2400 North Glenville
Contact City/State/Zip: Richardson, TX 75082
Contact Mail Country: US
Contact Type 1: Owner / Operator
Contact Name: Jason Weller
Title: - Manager, Global EH&S Compliance
Modification Date: 3/30/2012

Contact:
Contact Email: jason.weller@verizon.com
Contact Mail Address: 2400 North Glenville
Contact City/State/Zip: Richardson, TX 75082
Contact Mail Country: US
Contact Type 1: Emergency Contact
Contact Name: Jason Weller
Title: Manager
Modification Date: 3/30/2012

Contact Email: jason.weller@verizon.com
Contact Mail Address: 2400 North Glenville

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Contact City/State/Zip:	Richardson, TX 75082
Contact Mail Country:	US
Contact Type 1:	Emergency Contact
Contact Name:	Jason Weller
Title:	Manager
Modification Date:	3/30/2012

Chemical Inventory:

Facility Id:	FATR2011TXAUSXTX
Chemical Name:	LEAD ACID BATTERIES
Chemical Inv Record Id:	TXAUSXTX91443
CAS Number:	7664-93-9
Chemical Same As Last Year:	N
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	424
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/30/2012
Days On Site:	365
Fire Hazard:	T
Gas:	F
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	F
Pure Form:	F
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	TXAUSXTX91443386070
Chemical Inventory Record Id:	TXAUSXTX91443
Amt Of Sub Stored Or Transported:	10176
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside-Main Bldg - Basement
Last Modified:	3/30/2012

Record Key:	TXAUSXTX91443386489
Chemical Inventory Record Id:	TXAUSXTX91443
Amt Of Sub Stored Or Transported:	24000
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside-Main Bldg - 900
Last Modified:	3/30/2012

Record Key:	TXAUSXTX91443387367

MCI- AUSXTX (TXAUSXTX) (Continued) **S112009491**

Chemical Inventory Record Id: TXAUSXTX91443
Amt Of Sub Stored Or Transported: 12.4
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside-Main Bldg - Fire Panel
Last Modified: 3/30/2012

Record Key: TXAUSXTX91443387369
Chemical Inventory Record Id: TXAUSXTX91443
Amt Of Sub Stored Or Transported: 59.5
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Inside-Main Bldg - Gen start bat
Last Modified: 3/30/2012

Mixture:
Record Key: TXAUSXTX9144377860
Chemical Inv Record Id: TXAUSXTX91443
Mix Chemical: SULFURIC ACID
Percentage: 6.35
Facility Id: FATR2011TXAUSXTX
Mixture Cas: 7664-93-9
Weight/Volume: Wt
Mixture Ehs: T
Mixture Last Modified: 3/30/2012

Notes: Not reported
Validation: Not reported

DK499 **GENERAL MUFFLER CORPORATION** **EDR Hist Auto** **1021422223**
Target **211 E 7TH** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 7 in cluster DK

Actual:
513 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1978	GENERAL MUFFLER CORPORATION	Automotive Repair Shops, NEC
1979	GENERAL MUFFLER CORPORATION	Automotive Repair Shops, NEC
1980	GENERAL MUFFLER CORPORATION	Automotive Repair Shops, NEC
2010	501 AUTOMOTIVE LLC	General Automotive Repair Shops
2011	501 AUTOMOTIVE LLC	General Automotive Repair Shops
2011	GULF COAST CARRIERS LLC	Gasoline Service Stations, NEC
2011	KING OAKS AT COLLEGE STN LLC	Gasoline Service Stations
2012	501 AUTOMOTIVE LLC	General Automotive Repair Shops
2013	501 AUTOMOTIVE LLC	General Automotive Repair Shops
2014	501 AUTOMOTIVE LLC	General Automotive Repair Shops

DK500 Target Property | **MACONDA PARK**
211 E 7TH ST STE 709
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S126561033**
N/A

Site 4 of 7 in cluster DK

Actual: 513 ft.

Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN102075991
Name:	MACONDA PARK
Address:	211 E 7TH ST STE 709
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3218
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121064
Customer Name:	HIGHLAND RESOURCES INC
Customer Legal Name:	Highland Resources Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102075991
Name:	MACONDA PARK
Address:	211 E 7TH ST STE 709
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3218
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121064
Customer Name:	HIGHLAND RESOURCES INC
Customer Legal Name:	Highland Resources Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102075991
Name:	MACONDA PARK
Address:	211 E 7TH ST STE 709
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3218
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121064
Customer Name:	HIGHLAND RESOURCES INC
Customer Legal Name:	Highland Resources Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities

MACONDA PARK (Continued) **S126561033**

Physical Location Description: Not reported

DK501 Target Property | **MCI AUSXTX**
211 EAST 7TH STREET, SUITE 900
AUSTIN, TX 78701 | **TX TIER 2** | **S108877580**
N/A

Site 5 of 7 in cluster DK

Actual: 513 ft.

Focus Map: 11

TIER 2:

Facility Id/Name:	FATR201023GHW50HESL9/MCI - AUSXTX
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	01-11-2011
Mailing Address:	2400 N. Glenville Drive
Mailing City/State/Country:	Richardson, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Jason Weller / Environmental Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200923GHW50HESL9/MCI AUSXTX
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	02-04-2010
Mailing Address:	2400 N. Glenville Drive
Mailing City/State/Country:	Richardson, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Jason Weller / Environmental Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported

MCI AUSXTX (Continued) **S108877580**

Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200823GHW50HESL9/MCI - AUSXTX, AUAHTX
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	2/2/2009
Mailing Address:	2400 N. Glenville Drive
Mailing City/State/Country:	Richardson, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Karen Mehta/Environmental Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200723GHW50HESL9/MCI - AUSXTX, AUAHTX
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	1/23/2008
Mailing Address:	2400 N. Glenville Drive
Mailing City/State/Country:	Richardson, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Karen Mehta/Environmental Rep.
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported

MCI AUSXTX (Continued) **S108877580**

Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200623GHW50HESL9/MCI - AUSXTX
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	1/16/2007
Mailing Address:	2400 N. Glenville Drive
Mailing City/State/Country:	Richardson, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Karen Mehta/Environmental Rep.
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	517110
Id Type:	NAICS
Description:	Wired Telecommunications Carriers
Last Modified:	2/2/2009
Id:	4813
Id Type:	SIC
Description:	TELEPHONE COM, EXCEPT RADIO
Last Modified:	1/10/2003
Id:	020289070
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/10/2003

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported

MCI AUSXTX (Continued) **S108877580**

Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Name:	Network Management
Title:	Not reported
Modification Date:	2/17/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	1950 Stemmons Freeway
Contact City/State/Zip:	Dallas, TX 75207
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Win Phinney
Title:	Manager
Modification Date:	2/17/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	2400 N. Glenville Drive
Contact City/State/Zip:	Richardson, TX 75082
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Jason Weller
Title:	Environmental Manager
Modification Date:	1/21/2010

Chemical Inventory:

Facility Id:	FATR200923GHW50HESL9
Chemical Name:	Lead Acid Batteries
Chemical Inv Record Id:	CVTR200923GHW50HLSP7
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/12/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009

MCI AUSXTX (Continued) **S108877580**

Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR200923GHW50HMSQ3
Chemical Inventory Record Id: CVTR200923GHW50HLSP7
Amt Of Sub Stored Or Transported: 34248
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Battery Room
Last Modified: 2/12/2010

Mixture:
Record Key: CMTR20092T0M760091P5
Chemical Inv Record Id: CVTR200923GHW50HLSP7
Mix Chemical: Sulfuric Acid
Percentage: 40
Facility Id: FATR200923GHW50HESL9
Mixture Cas: 7664-93-9
Weight/Volume: Vol
Mixture Ehs: T
Mixture Last Modified: 2/12/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:
Id: 517110
Id Type: NAICS
Description: Wired Telecommunications Carriers
Last Modified: 2/2/2009
Id: 4813
Id Type: SIC
Description: TELEPHONE COM, EXCEPT RADIO
Last Modified: 1/10/2003
Id: 020289070
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 1/10/2003

Contact:
Contact Email: jason.weller@verizonbusiness.com
Contact Mail Address: 2400 N. Glenville Drive
Contact City/State/Zip: Richardson, TX 75082
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Type 2: Submitter
Contact Name: Jason Weller
Title: Environmental Manager
Modification Date: 1/21/2010

MCI AUSXTX (Continued) **S108877580**

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	Not reported
Contact Type 1:	Emergency Contact
Contact Name:	Network Management
Title:	Not reported
Modification Date:	2/16/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	1950 Stemmons Freeway
Contact City/State/Zip:	Dallas, TX 75207
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Win Phinney
Title:	Manager
Modification Date:	2/16/2011

Chemical Inventory:

Facility Id:	FATR201023GHW50HESL9
Chemical Name:	Lead Acid Batteries
Chemical Inv Record Id:	CVTR201023GHW50HLSP7
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/16/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	T
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201023GHW50HMSQ3
Chemical Inventory Record Id:	CVTR201023GHW50HLSP7
Amt Of Sub Stored Or Transported:	34248
Amount Units:	pounds
Type Of Storage:	Other

MCI AUSXTX (Continued) **S108877580**

Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Battery Room
Last Modified: 2/16/2011

Mixture:
Record Key: CMTR20102T0M760091P5
Chemical Inv Record Id: CVTR201023GHW50HLSP7
Mix Chemical: Sulfuric Acid
Percentage: 40
Facility Id: FATR201023GHW50HESL9
Mixture Cas: 7664-93-9
Weight/Volume: Vol
Mixture Ehs: T
Mixture Last Modified: 2/16/2011

Notes: Not reported
Validation: Not reported

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

DK502 Target Property **REEF SERVICES LLC/D/B/A ROCKWATER ENERGY SOLUTIONS** **FINDS** **1024048682**
211 E. 7TH STREET, STE. 620 **N/A**
AUSTIN, TX 78701

Site 6 of 7 in cluster DK

Actual: 513 ft.

Focus Map: 11

FINDS:
Registry ID: 110070132330

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
TSCA SUBMITTER
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also

REEF SERVICES LLC/D/B/A ROCKWATER ENERGY SOLUTIONS (Continued) **1024048682**

has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DK503 Target Property **SOUTHWEST TOWERS**
211 E 7TH STREET
AUSTIN, TX 78701

TX HIST UST **S111678558**
TX ASBESTOS **N/A**

Site 7 of 7 in cluster DK

Actual: 513 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	AUSTIN ALLRIGHT PARKING COMPANY
Address:	211 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0955
HID UST:	955
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	SOUTHWEST TOWER
Address:	211 E. 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	JESSIE RAY
Violation:	Not reported
Complaint Date:	04/27/2016
Notification Number:	2016003096
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement

SOUTHWEST TOWERS (Continued) **S111678558**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/07/2016
Certification Statement Phone:	512-474-6491
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/21/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	09/23/2016
Notification Number:	2016006492
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/07/2016

SOUTHWEST TOWERS (Continued) **S111678558**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/02/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	51
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/16/2016
Notification Number:	2016006492

SOUTHWEST TOWERS (Continued) **S111678558**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/25/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/25/2016
Notification Number:	2016006492
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/10/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/05/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/16/2016
Client Code:	Not reported
Client Name:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/29/2016
Notification Number:	2016006492
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/12/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N

SOUTHWEST TOWERS (Continued) **S111678558**

Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	09/13/2016
Notification Number:	2016006492
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/24/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/22/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	08/16/2016
Notification Number:	2016006492
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/25/2016
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	03/21/2017
Notification Number:	2017001801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/20/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/15/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	03/16/2017
Notification Number:	2017001801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/01/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N

SOUTHWEST TOWERS (Continued) **S111678558**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/15/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	02/17/2017
Notification Number:	2017000619
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/07/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/02/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/15/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	02/11/2017
Notification Number:	2017000619
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/24/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/19/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	23
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SOUTHWEST TOWERS
Address:	211 E 7TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL

SOUTHWEST TOWERS (Continued) **S111678558**

Violation:	Not reported
Complaint Date:	04/22/2019
Notification Number:	2019002779
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/22/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	131
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/08/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

SOUTHWEST TOWERS (Continued) **S111678558**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DJ504 **DAVIS MAX DCLO CLNR** **EDR Hist Cleaner** **1013778886**
Target **609 BRAZOS ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 7 in cluster DJ

Actual: EDR Hist Cleaner
498 ft.

Focus Map:
11

Year:	Name:	Type:
1929	DAVIS MAX DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

DH505 **EXCELSIOR LAUNDRY** **EDR Hist Cleaner** **1013777592**
Target **117 6TH W** **N/A**
Property **AUSTIN, TX**

Site 3 of 16 in cluster DH

Actual: EDR Hist Cleaner
494 ft.

Focus Map:
11

Year:	Name:	Type:
1906	EXCELSIOR LAUNDRY	LAUNDRIES
1911	EXCELSIOR LAUNDRY	LAUNDRIES

DH506 **SCARBROUGH BUILDING** **TX ASBESTOS** **S125393670**
Target **101 E. 6TH STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 16 in cluster DH

Actual: ASBESTOS:
493 ft.

Focus Map:
11

Name:	SCARBROUGH BUILDING
Address:	101 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Paul B Dehlinger
Violation:	Not reported
Complaint Date:	12/20/2016
Notification Number:	2016009497
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

SCARBROUGH BUILDING (Continued) **S125393670**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/06/2016
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	27
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SCARBROUGH BUILDING
Address:	101 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported

SCARBROUGH BUILDING (Continued) **S125393670**

Reason for Inspection:	Paul B Dehlinger
Violation:	Not reported
Complaint Date:	12/16/2016
Notification Number:	2016009497
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/23/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/23/2016
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	27
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

SCARBROUGH BUILDING (Continued) **S125393670**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SCARBROUGH BUILDING
Address:	101 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/15/2019
Notification Number:	2019001067
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/31/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment

SCARBROUGH BUILDING (Continued) **S125393670**

Analytical Method:	PLM
Start Date:	02/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SCARBROUGH BUILDING
Address:	101 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/15/2019
Notification Number:	2019001067
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/30/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original

SCARBROUGH BUILDING (Continued) **S125393670**

Work Type Flag:	A
Certification Statement Date:	01/30/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DH507 **SCARBROUGH BLDG.** **TX ASBESTOS** **S121362573**
Target **101 E. 6TH STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 16 in cluster DH

Actual:
493 ft.

Focus Map:
11

ASBESTOS:

Name:	SCARBROUGH BLDG.
Address:	101 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	04/20/2017
Notification Number:	2017002626
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

SCARBROUGH BLDG. (Continued) **S121362573**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/03/2017
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SCARBROUGH BLDG 4TH FLOOR
Address:	101 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701

SCARBROUGH BLDG. (Continued) **S121362573**

Date of inspection:	Not reported
Reason for Inspection:	PAUL DEHLINGER
Violation:	Not reported
Complaint Date:	02/23/2018
Notification Number:	2018001447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/15/2018
Certification Statement Phone:	512-587-8036
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/14/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

SCARBROUGH BLDG. (Continued) **S121362573**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SCARBROUGH BLDG 4TH FLOOR
Address:	101 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	PAUL DEHLINGER
Violation:	Not reported
Complaint Date:	02/23/2018
Notification Number:	2018001447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/21/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/30/2018
Certification Statement Phone:	512-587-8036
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

SCARBROUGH BLDG. (Continued) **S121362573**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/12/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SCARBROUGH BLDG 4TH FLOOR
Address:	101 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	PAUL DEHLINGER
Violation:	Not reported
Complaint Date:	02/14/2018
Notification Number:	2018001447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/21/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement

SCARBROUGH BLDG. (Continued) **S121362573**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/21/2018
Certification Statement Phone:	512-587-8036
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/31/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DH508 **SCARBROUGH BUILDING** **TX VCP** **S103865171**
Target **101 W 6TH ST** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78701**

Site 6 of 16 in cluster DH

Actual:
493 ft.

Focus Map:
11

VCP TCEQ:

Name:	SCARBROUGH BUILDING
Address:	101 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	638
VCP Record Date:	10/21/1997
Facility Type:	RETAIL STORE/SHOPPING CENTER
PCA Number:	31548
Project Manager:	MFREW
Phase:	COMPLETED
Acres at Site:	1
REM Program:	VCP
RN Number:	RN101053650
Former Facility Type:	Not reported
Site Address Description:	101 WEST 6TH STREET

SCARBROUGH BUILDING (Continued) **S103865171**

Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	10/20/1997
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	12/03/1997
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	NOT REQUIRED
Air Target COC Class:	Not reported
Date Cashier Check Received:	10/20/1997
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1997-11-20 00:00:00
Soil Target COC Class:	TPH; CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	638
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	315480
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.27
Longitude:	-97.74

Contact:

REM Program:	VCP
Program ID:	638
RN Number:	RN101053650
CN Number:	CN600613053
CN Name:	SCARBROUGH BUILDING PARTNERSHIP
Role Code:	BILLCONT
Contact Name:	GREEN, ALLEN
Contact Title:	Not reported
Organization Name:	SCARBROUGH BLDG PARTNERSHIP
Mailing Address:	PO BOX 908
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Telephone:	(512) 397-2925
Contact Telephone Ext:	0

SCARBROUGH BUILDING (Continued) **S103865171**

HIST UST AUSTIN:

Name:	SCARBROUGH BUILDING
Address:	101 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	3328
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DH509 **SCARBROUGH BUILDING** **FINDS** **1011403384**
Target **101 W 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 7 of 16 in cluster DH

Actual:
493 ft.

Focus Map:
11

FINDS:
Registry ID: 110035339746

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DH510 **SCARBROUGH BUILDING** **TX CENTRAL REGISTRY** **S123866561**
Target **101 W 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 8 of 16 in cluster DH

Actual:
493 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101053650
Name:	SCARBROUGH BUILDING
Address:	101 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2942
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600613053
Customer Name:	SCARBROUGH BUILDING PARTNERSHIP
Customer Legal Name:	Scarbrough Building Partnership
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	101 WEST 6TH STREET

SCARBROUGH BUILDING (Continued) **S123866561**

Regulated Entity Number:	RN101053650
Name:	SCARBROUGH BUILDING
Address:	101 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2942
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600613053
Customer Name:	SCARBROUGH BUILDING PARTNERSHIP
Customer Legal Name:	Scarbrough Building Partnership
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	101 WEST 6TH STREET

DH511 **CARRINGTON ASSOCIATES INC** **FINDS** **1011265853**
Target **101 W 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 9 of 16 in cluster DH

Actual:
493 ft.

Focus Map:
11

FINDS:
Registry ID: 110034193682

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DL512 **AUSTIN CITY OF** **HIST FTTS** **1008175156**
Target **301 W AVE** **N/A**
Property **AUSTIN, TX 0**

Site 1 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

HIST FTTS:

Case Number:	Not reported
Docket Number:	VI-306C-T
Complaint Issue Date:	04/15/1987
Abatement Amount:	0.0000
Proposed Penalty:	42000.0000
Final Assessment:	5000.0000
Final Order Date:	12/29/1987
Close Date:	/ /
Violations(s):	PCB, Inspect PCB, Use

AUSTIN CITY OF (Continued) **1008175156**

PCB, Storage

DL513 **AUSTIN CITY ELECT UTILITY** **RCRA-SQG** **1000412220**
Target **301 W AVE** **FINDS** **TXT490014578**
Property **AUSTIN, TX 78701** **ECHO**

Site 2 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	19810430
Handler Name:	Austin City Elect Utility
Handler Address:	W AVE
Handler City,State,Zip:	AUSTIN, TX 78767
EPA ID:	TXT490014578
Contact Name:	TODD SHAW
Contact Address:	PO BOX 1088
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-322-6267
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1088
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	City Of Austin
Owner Type:	Municipal
Operator Name:	City Of Austin Texas
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

AUSTIN CITY ELECT UTILITY (Continued) **1000412220**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	301 W AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF AUSTIN TEXAS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19810430
Handler Name: AUSTIN CITY ELECT UTILITY	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

AUSTIN CITY ELECT UTILITY (Continued) **1000412220**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005193557

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412220
Registry ID:	110005193557
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005193557
Name:	AUSTIN CITY ELECT UTILITY
Address:	301 W AVE
City,State,Zip:	AUSTIN, TX 78701

DL514 **AUSTIN ENERGY - ENERGY CONTROL CENTER** **TX GCC** **S122570489**
Target **301 WEST AVENUE** **N/A**
Property **AUSTIN, TX**

Site 3 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

GCC:

Name:	AUSTIN ENERGY - ENERGY CONTROL CENTER
Address:	301 WEST AVENUE
City,State,Zip:	AUSTIN, TX
Division:	REM/DCRP
New Cases:	Not reported
File Number:	2485
Contamination Description:	VOCS. SVOCS, METALS, CHLORINATED SOLVENTS, TPH
Date Of Earliest Known Contamination Confirmation:	4/30/2012
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

DL515 **AUSTIN ENERGY WEST AVENUE** **TX UST** **U003566431**
Target **301 WEST AVE** **TX Financial Assurance** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

UST:

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 787014757
AI Number:	65201
Facility Type:	Not reported
Facility Begin Date:	11/30/1993
Facility Status:	INACTIVE
Additional ID:	249025772002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MARC CHILDERS,
Contact Organization Name:	AUSTIN ENERGY WEST AVENUE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129742834
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Signature Date On Earliest Reg Form:	12/20/1993
Signature Name/Title On Earliest Reg Form:	GREG B MCINTOSH,VP
Application Received Date On Earliest Reg Form:	12/22/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	840354562001227
Additional ID:	249025772002150
Ai Number:	65201
Operator CN:	CN600135198
Operator Name:	CITY OF AUSTIN
Operator Effective Begin Date:	03/01/1994
Operator Type:	CI
Operator Role:	OPRCON
Contact Name:	SANDRA CREIGHTON/
Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	505 BARTON SPRINGS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-1216
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78721
Contact Mailing Zip5:	3639
Contact Phone Number/Ext:	1 512 9782649/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	249025772002150
AI Number:	65201
Owner Effective Begin Date:	03/01/1994
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JIMMY TUBBS/FUEL OPS COORD

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Contact Organization Name:	CITY OF AUSTIN
Self Certification:	
Self Cert ID:	96600
Cert ID:	218931
AI Number:	65201
Self Certification Date:	04/18/2013
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N
Self Cert ID:	96600
Cert ID:	161048
AI Number:	65201
Self Certification Date:	05/08/2012
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161047
AI Number:	65201
Self Certification Date:	04/08/2011
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SENIOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161046
AI Number:	65201
Self Certification Date:	05/10/2010
Signature Name/Title:	WILL O'CONNOR FLEET PROGRAM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161045
AI Number:	65201
Self Certification Date:	11/13/2009
Signature Name/Title:	STACEY MONROE FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161044
AI Number:	65201
Self Certification Date:	08/27/2004
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161043
AI Number:	65201
Self Certification Date:	09/11/2003
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	96600
Cert ID:	161042
AI Number:	65201
Self Certification Date:	12/16/2002
Signature Name/Title:	MARC CHILDERS FUEL OPERATION MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/22/1993
Tank Registration Date:	12/22/1993
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	149262
Facility ID:	96600
Ai Number:	65201
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/29/2014
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	160705
UST ID:	149262
AI Number:	65201
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	25109
Facility ID:	96600
AI Number:	65201
Application Received Date:	01/10/2014
Scheduled Construction Date:	01/27/2014
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	01/10/2014
Signature Date On Form:	01/08/2014
Signature Name On Form:	JULIE SPEER
Signature Company On Form:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN;CITY OF AUSTIN
Owner CN At Time Of Construction:	CN600135198,CN600135198
Owner AR At Time Of Construction:	5A,5U
General Desc Of Prop Construct:	PERMANENTLY REMOVE 2,000 GALLON DIESEL UST SYSTEM FROM SERVICE BY REMOVAL FROM GROUND.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	58917
UST ID:	Not reported
NOC ID:	25109
AI Number:	65201
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TRC ENVIRONMENTAL CORP
Representative Name:	JULIE SPEER
Mailing Address (Delivery):	505 E HUNTLAND DR STE 250
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78752
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3296080
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3298750
Email Address:	Not reported

Cont/Cons/Installer ID:	58916
UST ID:	Not reported
NOC ID:	25109
AI Number:	65201
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	HILL COUNTRY ENVIRONMENTAL INC
Representative Name:	KEVIN MURPHY
Mailing Address (Delivery):	1613 S CAPITAL OF TEXAS HWY STE 201
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3272725
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3272750
Email Address:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	4411 MEINARDUS DR STE D
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 1170
Phone Number/Ext:	512 9782649/0
Contact Fax Number/Ext:	512 9121524/0
Contact Email Address:	WILLIAM.OCONNOR@AUSTINTEXAS.GOV
Contact Address Deliverable:	Y
Facility ID:	96600
Additional ID:	249025772002150
Princ ID:	840354562001227
AI Number:	65201
Facility Name:	AUSTIN ENERGY WEST AVENUE
AR Number:	5
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	WILLIAM OCONNOR/

TX Financial Assurance 2:

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	107480
AI:	65201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	9966
AI:	65201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	82788
AI:	65201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	82789
AI:	65201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/04/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	1000000

AUSTIN ENERGY WEST AVENUE (Continued) **U003566431**

Coverage Expiration Date:	02/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	82790
AI:	65201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/23/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 9742600
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	11/23/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	96600
Finass ID:	82791
AI:	65201
Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

DL516 Target Property | **CITY OF AUSTIN**
301 WEST AVE
AUSTIN, TX 78701 | **FINDS** | **1011307328**
N/A

Site 5 of 17 in cluster DL

Actual: 467 ft.
Focus Map: 11

FINDS:
Registry ID: 110034288919

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DL517 Target Property | **AUSTIN ENERGY-ENERGY CONTROL CENTER**
301 WEST AVE
AUSTIN, TX 78701 | **TX VCP** | **S123819963**
N/A

Site 6 of 17 in cluster DL

Actual: 467 ft.
Focus Map: 11

VCP TCEQ:

Name:	AUSTIN ENERGY-ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2485
VCP Record Date:	03/12/2012
Facility Type:	PROPERTY COMMERCIAL
PCA Number:	34678
Project Manager:	JSTEFEK
Phase:	COMPLETED
Acres at Site:	1.737
REM Program:	VCP
RN Number:	RN106321532
Former Facility Type:	PROPERTY COMMERCIAL
Site Address Description:	Not reported
Near City Name:	Not reported
Administrative Status:	INACTIVE
Region Notified of Application:	03/07/2012
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported

AUSTIN ENERGY-ENERGY CONTROL CENTER (Continued) **S123819963**

Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	09/16/2014
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	03/07/2012
GW Target COC Class:	METALS; SVOCS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2012-04-30 00:00:00
Soil Target COC Class:	Not reported
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2485
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	346780
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	0.00
Longitude:	0.00

DL518 **AUSTIN ENERGY - ENERGY CONTROL CENTER** **TX GCC** **S122570488**
Target **301 WEST AVE** **N/A**
Property **AUSTIN, TX**

Site 7 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

GCC:

Name:	AUSTIN ENERGY - ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/VC
New Cases:	*
File Number:	2485
Contamination Description:	VOCS.SVOCS,HEAVY METALS,CHL SLVT, TPH
Date Of Earliest Known Contamination Confirmation:	4/30/2012
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	2A -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	AUSTIN ENERGY - ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/VC
New Cases:	Not reported
File Number:	2485
Contamination Description:	VOCS.SVOCS,METALS,CHL SLVT, TPH
Date Of Earliest Known Contamination Confirmation:	4/30/2012

AUSTIN ENERGY - ENERGY CONTROL CENTER (Continued) **S122570488**

Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

DL519 **AUSTIN ENERGY CONTROL CENTER** **TX HIST UST** **S128728655**
Target **301 WEST AVE** **TX ASBESTOS** **N/A**
Property **AUSTIN, TX 78701**

Site 8 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

HIST UST AUSTIN:
Name: AUSTIN ENERGY CONTROL CENTER
Address: 301 WEST AVE
City,State,Zip: AUSTIN, TX
Id UST: 3128
HID UST: Not reported
Inspection: Not reported
Due: Not reported

ASBESTOS:
Name: AUSTIN ENERGY CONTROL CENTER
Address: 301 WEST AVE
City,State,Zip: AUSTIN, TX 78701
Date of inspection: 08/15/2016
Reason for Inspection: JIMMY STAFFORD
Violation: Not reported
Complaint Date: 12/04/2015
Notification Number: 2015006284
ASB Priority: Not reported
PIF State: Not reported
Detained: Not reported
Product Name: Not reported
Time Spent: Not reported
Travel Time: Not reported
Mileage: Not reported
Reg: Not reported
Init: Not reported
Seq: Not reported
Facility Type: NESHAP
Inspector Name: Not reported
Date Report Received: 10/01/2015
Date Routed by Supervisor: Not reported
Date Routed to PSQA: Not reported
Date Reviewed by PSQA: Not reported
Date Routed by Supervisor1: Not reported
Date Rtnd to Inspector Corrections: Not reported
Date Rcvd Back: Not reported
Date Rtnd to Inspector Corrections2: Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/28/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/16/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	11/06/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/28/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/06/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/20/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/30/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/28/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/06/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	11/26/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/28/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/13/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/05/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	01/15/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/28/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/13/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	11/26/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Report Received:	11/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/28/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/05/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	01/15/2016

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/28/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/04/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/11/2015
Client Code:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	01/15/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/04/2015
Certification Statement Phone:	512-260-7171

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/11/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/24/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/10/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/18/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	01/23/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/24/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/10/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/14/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	10/13/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/01/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/09/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/23/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/22/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/15/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/04/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21
Is this a phased abatement project?:	N
Ordered:	N

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/15/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Notification Status:	Current
Amendo:	15
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/04/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/11/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/16/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/18/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/23/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Violation:	Not reported
Complaint Date:	01/29/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/18/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/23/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/20/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Start Date:	12/01/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Certification Statement Date:	11/20/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/23/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/30/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/02/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/30/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/23/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/01/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/07/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/01/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/23/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/04/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/09/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/04/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/31/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/08/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/14/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/08/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/31/2015
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/11/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/11/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	161
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	12/22/2015

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/16/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/15/2016
Reason for Inspection:	JIMMY STAFFORD
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2015006284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/16/2015
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/04/2016
Client Code:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN ENERGY CONTROL CENTER
Address:	301 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/08/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	NOTIFICATION, PROGRAM
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

AUSTIN ENERGY CONTROL CENTER (Continued) **S128728655**

Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/15/2016
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2015006284
File Number:	973
License Status Description:	Paid
Expiration Date:	02/05/2016
Original Date:	10/01/2015
Rank Effective Date:	10/01/2015
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	notifictn
Inspection Number:	2763
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	N/A
Inspection Number Grade:	0

DL520 **AUSTIN CITY OF** **FTTS** **1010001006**
Target **301 W AVE** **N/A**
Property **AUSTIN, TX 0**

Site 9 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

FTTS:

Case Number:	Not reported
Docket Number:	VI-306C-T
Complaint Issue Date:	04/15/87
Abatement Amount:	0.0000
Proposed Penalty:	42000.0000
Final Assessment:	5000.0000
Final Order Date:	12/29/87
Close Date:	/ /
Violations(s):	PCB, Inspect PCB, Use PCB, Storage

DL521 **AUSTIN ENERGY WEST AVENUE** **TX CENTRAL REGISTRY** **S126834754**
Target **301 WEST AVE** **N/A**
Property **AUSTIN, TX 78701**

Site 10 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/1/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/7/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604226035
Customer Name:	TECOM UST SYSTEMS INC
Customer Legal Name:	TECOM U.S.T. SYSTEMS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/30/1993
Affiliation End Date:	8/31/1996
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation

AUSTIN ENERGY WEST AVENUE (Continued) **S126834754**

Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/1/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/1/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/1/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532

AUSTIN ENERGY WEST AVENUE (Continued) **S126834754**

Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/1/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/7/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/7/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported

AUSTIN ENERGY WEST AVENUE (Continued) **S126834754**

City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/7/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Regulated Entity Number:	RN106321532
Name:	AUSTIN ENERGY WEST AVENUE
Address:	301 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4757
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	3/7/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221119
Primary NAICS Industry Type Description:	Other Electric Power Generation
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

DL522 **ENERGY CONTROL CENTER** **TX TIER 2** **S108454660**
Target **301 WEST AVE.** **N/A**
Property **AUSTIN, TX 78701**

Site 11 of 17 in cluster DL

Actual:
467 ft.

Focus Map:
11

TIER 2:

Facility Id/Name:	FASAFTEC433856317420/ENERGY CONTROL CENTER
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	02/27/2013
Mailing Address:	811 Barton Springs Rd. Environmental Services
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Not reported
Latitude:	Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20111FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	03/09/2012
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	fred blood
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20101FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	2/25/2011
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Carol Bowman

ENERGY CONTROL CENTER (Continued) **S108454660**

Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20091FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/22/2010
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	550.00
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	David Wood
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20081FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	2/25/2009
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Submitted By:	David Wood
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20071FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	2/29/2008
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Arthur Flores
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20061FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2/23/2007
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	120
Site Map:	Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Fire District:	Not reported
Submitted By:	Doug Granell
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20051FZXQ800HW26/ENERGY CONTROL CENTER
Reporting Year:	2005
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	3/1/2006
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Doug Granell
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Contact:

Contact Email:	Not reported
Contact Mail Address:	811 Barton Springs Rd. Environmental Services
Contact City/State/Zip:	Austin, TX 78704-1194
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	City of Austin dba Austin Energy
Title:	Facility Service Coordinator
Modification Date:	3/7/2013

ENERGY CONTROL CENTER (Continued) **S108454660**

Contact:

Contact Email:	Not reported
Contact Mail Address:	301 West Ave.
Contact City/State/Zip:	Austin, Tx 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Gerard Rumsey
Title:	Facility Service Coordinator
Modification Date:	3/7/2013

Chemical Inventory:

Facility Id:	FASAFTEC433856317420
Chemical Name:	Citgo No. 2 Diesel Fuel, Low Sulfur, All Grades
Chemical Inv Record Id:	CVSAFTEC424961601207
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/7/2013
Days On Site:	366
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	Tx2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLSAFTEC572162754338
Chemical Inventory Record Id:	CVSAFTEC424961601207
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Emergency Diesel Generator Fuel Tank
Last Modified:	3/7/2013

Mixture:

Record Key:	CMSAFTEC196728951838
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Trimethylbenzenes, All Isomers
Percentage:	0.38
Facility Id:	FASAFTEC433856317420
Mixture Cas:	25551-13-7

ENERGY CONTROL CENTER (Continued) **S108454660**

Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC985390287695
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Cumene
Percentage: 0.19
Facility Id: FASAFTEC433856317420
Mixture Cas: 98-82-8
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC632689467016
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Diesel Fuel, No. 2
Percentage: 19.1
Facility Id: FASAFTEC433856317420
Mixture Cas: 68476-34-6
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC396207830280
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Biphenyl (Diphenyl)
Percentage: 0.38
Facility Id: FASAFTEC433856317420
Mixture Cas: 92-52-4
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC974764059671
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Hydrodesulfurized Middle Distillate (Petroleum)
Percentage: 19.1
Facility Id: FASAFTEC433856317420
Mixture Cas: 64742-80-9
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC285631515116
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Hydrodesulfurized Kerosine (Petroleum)
Percentage: 19.1
Facility Id: FASAFTEC433856317420
Mixture Cas: 64742-81-0
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC585950142212
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Nonane, All Isomers

ENERGY CONTROL CENTER (Continued) **S108454660**

Percentage:	1.91
Facility Id:	FASAFTEC433856317420
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

Record Key:	CMSAFTEC924797213393
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Ethyl Benzene
Percentage:	0.19
Facility Id:	FASAFTEC433856317420
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

Record Key:	CMSAFTEC595016769168
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Xylene
Percentage:	0.17
Facility Id:	FASAFTEC433856317420
Mixture Cas:	1330-20-7
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

Record Key:	CMSAFTEC134286415999
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Naphthalene
Percentage:	0.38
Facility Id:	FASAFTEC433856317420
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

Record Key:	CMSAFTEC964684198895
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Ethylbenzene
Percentage:	0.19
Facility Id:	FASAFTEC433856317420
Mixture Cas:	100-41-4
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

Record Key:	CMSAFTEC913531830449
Chemical Inv Record Id:	CVSAFTEC424961601207
Mix Chemical:	Toluene
Percentage:	0.01
Facility Id:	FASAFTEC433856317420
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/7/2013

ENERGY CONTROL CENTER (Continued) **S108454660**

Record Key: CMSAFTEC388309378305
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Naphthalen
Percentage: 0.38
Facility Id: FASAFTEC433856317420
Mixture Cas: 91-20-3
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC592436055710
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Hydrodesulfurized Light Catalytic Cracked Distillate (Petroleum)
Percentage: 19.1
Facility Id: FASAFTEC433856317420
Mixture Cas: 68333-25-5
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC156805785011
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Benzene
Percentage: 0.01
Facility Id: FASAFTEC433856317420
Mixture Cas: Not reported
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC718361870615
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Benzene
Percentage: 0.01
Facility Id: FASAFTEC433856317420
Mixture Cas: 71-43-2
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Record Key: CMSAFTEC562014689176
Chemical Inv Record Id: CVSAFTEC424961601207
Mix Chemical: Kerosene
Percentage: 19.1
Facility Id: FASAFTEC433856317420
Mixture Cas: 8008-20-6
Weight/Volume: Wt
Mixture Ehs: Not reported
Mixture Last Modified: 3/7/2013

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Facility Info:

Id:	221112
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/12/2002
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/12/2002
Id:	4911
Id Type:	SIC
Description:	Not reported
Last Modified:	2/12/2002

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Austin Energy City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	3/13/2012

Contact:

Contact Email:	fred.blood@austinenergy.com
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/15/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	310 WEST AVE.
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Energy Control Center
Title:	Emergency
Modification Date:	3/13/2012

Contact:

Contact Email:	jerry.Hernandez@austinenergy.com
Contact Mail Address:	301 West Ave.
Contact City/State/Zip:	Austin, TX 78703
Contact Mail Country:	USA

ENERGY CONTROL CENTER (Continued) **S108454660**

Contact Type 1:	Owner / Operator
Contact Name:	Jerry Hernandez
Title:	Not reported
Modification Date:	3/13/2012

Contact:

Contact Email:	Basheer.Mohamed@austinenergy.com
Contact Mail Address:	721 Barton Creek
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Basheer Mohamed
Title:	Not reported
Modification Date:	3/13/2012

Contact:

Contact Email:	carol.bowman@austinenergy.com
Contact Mail Address:	ECC, 310 West Avenue
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Carol Bowman
Title:	Acting Director, System Operations and Reliability
Modification Date:	3/13/2012

Chemical Inventory:

Facility Id:	FATR20111FZXQ800HW26
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR20111FZZVJ02X9TV
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Chemical Inventory Location:

Record Key:	CLTR20111G005K02YZ4G
Chemical Inventory Record Id:	CVTR20111FZZVJ02X9TV
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Driveway just inside front gate
Last Modified:	3/13/2012

Facility Id:	FATR20111FZXQ800HW26
Chemical Name:	Sulfuric acid (in batteries)
Chemical Inv Record Id:	CVTR201171MXJR01CTXH
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	24
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/13/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201171MY0101D25E
Chemical Inventory Record Id:	CVTR201171MXJR01CTXH
Amt Of Sub Stored Or Transported:	98
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	in battery bank
Last Modified:	3/13/2012

Notes: Not reported
Validation: Not reported

Notes: Not reported

Validation: This facility passed all validation checks.

ENERGY CONTROL CENTER (Continued) **S108454660**

Notes: Not reported
Validation: Not reported

Facility Info:
Id: Not reported
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 2/12/2002
Id: 4911
Id Type: SIC
Description: Not reported
Last Modified: 2/12/2002
Id: 221112
Id Type: NAICS
Description: Not reported
Last Modified: 2/12/2002

Contact:
Contact Email: Not reported
Contact Mail Address: 721 Barton Springs Rd
Contact City/State/Zip: Austin, TX 78704
Contact Mail Country: USA
Contact Type 1: Regulatory Point of Contact
Contact Type 2: Submitter
Contact Name: Jim Eldred
Title: Env Prog Coord'r
Modification Date: 2/22/2010

Contact:
Contact Email: Not reported
Contact Mail Address: 301 West Ave
Contact City/State/Zip: Austin, TX 78703
Contact Mail Country: USA
Contact Type 1: Manager
Contact Name: David Wood
Title: Director
Modification Date: 1/23/2009

Contact:
Contact Email: Not reported
Contact Mail Address: 721 Barton Springs Road
Contact City/State/Zip: Austin, TX 78704
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: City of Austin Electric Dep (dba Austin Energy)
Title: Owner
Modification Date: 3/14/2010

Contact:
Contact Email: Not reported
Contact Mail Address: 721 Barton Springs Rd
Contact City/State/Zip: Austin, TX 78704

ENERGY CONTROL CENTER (Continued) **S108454660**

Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/22/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	301 West Ave
Contact City/State/Zip:	Austin, TX 78703
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Geddy Rumsey
Title:	Facility Maintenance
Modification Date:	3/3/2010

Chemical Inventory:

Facility Id:	FATR20091FZXQ800HW26
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR20091FZZVJ02X9TV
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/3/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20091G005K02YZ4G
Chemical Inventory Record Id:	CVTR20091FZZVJ02X9TV
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Driveway just inside front gate
Last Modified:	3/3/2010
Facility Id:	FATR20091FZXQ800HW26

ENERGY CONTROL CENTER (Continued) **S108454660**

Chemical Name:	Sulfuric acid (in batteries)
Chemical Inv Record Id:	CVTR200971MXJR01CTXH
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	24
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/3/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971MY0101D25E
Chemical Inventory Record Id:	CVTR200971MXJR01CTXH
Amt Of Sub Stored Or Transported:	98
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	in battery bank
Last Modified:	3/3/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:

Id:	4911
Id Type:	SIC
Description:	Not reported
Last Modified:	2/12/2002
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/12/2002
Id:	221112
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/12/2002

ENERGY CONTROL CENTER (Continued) **S108454660**

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Austin Energy City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	4/4/2011

Contact:

Contact Email:	fred.blood@austinenergy.com
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/15/2011

Contact:

Contact Email:	carol.bowman@austinenergy.com
Contact Mail Address:	ECC, 310 West Avenue
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Carol Bowman
Title:	Acting Director, System Operations and Reliability
Modification Date:	3/11/2011

Contact:

Contact Email:	jerry.Hernandez@austinenergy.com
Contact Mail Address:	301 West Ave.
Contact City/State/Zip:	Austin, TX 78703
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Jerry Hernandez
Title:	Not reported
Modification Date:	3/11/2011

Contact:

Contact Email:	Basheer.Mohamed@austinenergy.com
Contact Mail Address:	721 Barton Creek
Contact City/State/Zip:	Austin, TX
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Basheer Mohamed
Title:	Not reported

ENERGY CONTROL CENTER (Continued) **S108454660**

Modification Date: 3/11/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	310 WEST AVE.
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Energy Control Center
Title:	Emergency
Modification Date:	4/4/2011

Chemical Inventory:

Facility Id:	FATR20101FZXQ800HW26
Chemical Name:	DIESEL FUEL
Chemical Inv Record Id:	CVTR20101FZZVJ02X9TV
CAS Number:	68476-34-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/11/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20101G005K02YZ4G
Chemical Inventory Record Id:	CVTR20101FZZVJ02X9TV
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Driveway just inside front gate
Last Modified:	3/11/2011

Facility Id:	FATR20101FZXQ800HW26
Chemical Name:	Sulfuric acid (in batteries)
Chemical Inv Record Id:	CVTR201071MXJR01CTXH
CAS Number:	7664-93-9

ENERGY CONTROL CENTER (Continued) **S108454660**

Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	24
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/11/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201071MY0101D25E
Chemical Inventory Record Id:	CVTR201071MXJR01CTXH
Amt Of Sub Stored Or Transported:	98
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	in battery bank
Last Modified:	3/11/2011

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

DM523 **YOUNG 0 E AUTO REPR** **EDR Hist Auto** **1013756192**
Target **613 TRINITY ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 22 in cluster DM

Actual:
496 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	YOUNG 0 E AUTO REPR	AUTOMOBILE REPAIRERS
1969	B & L CLUTCH SERVICE	Automotive Repair Shops, NEC
1970	B & I CLUTCH SERVICE	AUTOMOBILE REPAIRING
1970	B & L CLUTCH SERVICE	Automotive Repair Shops, NEC
1971	B & L CLUTCH SERVICE	Automotive Repair Shops, NEC

DN524 Target Property **STAGES PORT E TAILOR**
521 CONGRESS AVE
AUSTIN, TX

EDR Hist Cleaner **1013781032**
N/A

Site 1 of 8 in cluster DN

Actual: 492 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1935	STAGES PORT E TAILOR	CLEANERS, PRESSERS AND DYERS
1935	STAGES PORT E TAILOR	CLOTHES PRESSERS AND CLEANERS

DM525 Target Property **CENTEX AUTO REPAIR**
405 E 7TH ST
TRAVIS (County), TX 78701

EDR Hist Auto **1013759715**
N/A

Site 2 of 22 in cluster DM

Actual: 493 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1969	CEN-TEX BODY SHOP	General Automotive Repair Shops
1970	CENTEX AUTO REPAIR	AUTOMOBILE REPAIRING
1970	CEN-TEX BODY SHOP	General Automotive Repair Shops
1971	CEN-TEX BODY SHOP	General Automotive Repair Shops
1972	CEN-TEX BODY SHOP	General Automotive Repair Shops
1985	ALLMAN JESS GARAGE INC	General Automotive Repair Shops
1986	ALLMAN JESS GARAGE INC	General Automotive Repair Shops
1987	ALLMAN JESS GARAGE INC	General Automotive Repair Shops

DN526 Target Property **515 CONGRESS OFFICE BLDG.**
515 CONGRESS AVE.
AUSTIN, TX 78701

TX ASBESTOS **S119136773**
N/A

Site 2 of 8 in cluster DN

Actual: 492 ft.
Focus Map: 11

ASBESTOS:

Name:	515 CONGRESS OFFICE BLDG.
Address:	515 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	02/11/2014
Reason for Inspection:	Notified
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	2014000818
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	05
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	03/25/2014

515 CONGRESS OFFICE BLDG. (Continued) **S119136773**

Date Routed by Supervisor:	03/28/2014
Date Routed to PSQA:	03/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DM527 **GUSS GARAGE AUTO** **EDR Hist Auto** **1013761177**
Target **609 TRINITY ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 22 in cluster DM

Actual: EDR Hist Auto
495 ft.

Focus Map:
11

Year:	Name:	Type:
1929	NOWLIN R A AUTO REPR	AUTOMOBILE REPAIRERS
1935	NOWLIN R A AUTO REPR	AUTOMOBILE REPAIRERS
1940	NOWLIN ROBT A AUTO	AUTOMOBILE REPAIRING
1947	NELSON HUGH GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1953	NELSON HUGH C AUTO	AUTOMOBILE REPAIRING
1958	NELSON HUGH C GA	AUTOMOBILE REPAIRING
1962	GUSS GARAGE AUTO	AUTOMOBILE REPAIRING
1965	WALKERS AUTOMOTIVE AUTO	AUTOMOBILE REPAIRING
1970	WALKERS AUTOMOTIVE	AUTOMOBILE REPAIRING
1975	HAGOODS AUTOMOTIVE	AUTOMOBILE REPAIRING
1975	WALKER AUTOMOTIVE	General Automotive Repair Shops
1976	WALKER AUTOMOTIVE	General Automotive Repair Shops
1977	WALKER AUTOMOTIVE	General Automotive Repair Shops
1978	WALKER AUTOMOTIVE	General Automotive Repair Shops
1979	WALKER AUTOMOTIVE	General Automotive Repair Shops
1979	WALKER AUTOMOTIVE	General Automotive Repair Shops

DM528 **JOHNSON HARRY E** **EDR Hist Auto** **1013766387**
Target **605 TRINITY** **N/A**
Property **AUSTIN, TX**

Site 4 of 22 in cluster DM

Actual: EDR Hist Auto
493 ft.

Focus Map:
11

Year:	Name:	Type:
1929	FORD SPECIALISTS GARAGE	AUTOMOBILE REPAIRERS
1935	JOHNSON SCHIEFFER	AUTOMOBILE REPAIRERS
1940	JOHNSON HARRY E	AUTOMOBILE REPAIRING
1947	JOHNSON HARRY E AUTO REPR	AUTOMOBILE REPAIRING
1953	JOHNSON HARRY E	AUTOMOBILE REPAIRING
1958	JOHNSON HARRY E	AUTOMOBILE REPAIRING
1962	JOHNSON HARRY F	AUTOMOBILE REPAIRING
1965	JOHNSON HARRY E GARAGE	AUTOMOBILE REPAIRING
1969	JOHNSON HARRY E	General Automotive Repair Shops
1970	JOHNSON HARRY E	General Automotive Repair Shops

DO529 **SOUTHERN SERVICE STA** **EDR Hist Auto** **1013758281**
Target **403 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 1 of 5 in cluster DO

Actual: EDR Hist Auto
480 ft.

Focus Map:
11

Year:	Name:	Type:
1935	ROWE T E FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	SOUTHERN SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	REDMOND ROY REPR SHOP	REPAIR SHOPS

SOUTHERN SERVICE STA (Continued) **1013758281**

1953 CALHOUN SERY STA GASOLINE STATIONS

DP530 **13 MAG/ IN THE FLESH** **TX ASBESTOS** **S119136599**
Target **211 E 6 STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 16 in cluster DP

Actual:
488 ft.

Focus Map:
11

ASBESTOS:

Name:	13 MAG/ IN THE FLESH
Address:	211 E 6 STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/25/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	2
Travel Time:	0.01
Mileage:	0.2
Reg:	07
Init:	RC
Seq:	03
Facility Type:	Tattooing and Body Piercing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/01/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

13 MAG/ IN THE FLESH (Continued) **S119136599**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DP531 **13 MAG/IN THE FLESH** **TX ASBESTOS** **S119136600**
Target **211 E 6TH ST #B** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 16 in cluster DP

Actual:
488 ft.

Focus Map:
11

ASBESTOS:

Name:	13 MAG/IN THE FLESH
Address:	211 E 6TH ST #B
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/09/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	1.75
Mileage:	8.9
Reg:	07
Init:	MAO
Seq:	02
Facility Type:	Tattooing and Body Piercing
Inspector Name:	Margaret Olsovsky
Date Report Received:	05/13/2013
Date Routed by Supervisor:	05/13/2013
Date Routed to PSQA:	06/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

13 MAG/IN THE FLESH (Continued) **S119136600**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DP532 **NCNB TEXAS** **TX LPST** **S105050033**
Target **219 E 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 16 in cluster DP

Actual:
488 ft.

Focus Map:
11

LPST:

Name:	NCNB TEXAS
Address:	219 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	099342
Facility Location:	E 6TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/29/1991
Entered Date:	06/25/1991
Reported Date:	05/29/1991

NCNB TEXAS (Continued) **S105050033**

Closure Date:	07/07/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	CHRIS CHANDLER
Responsible Party Name:	Not reported
Responsible Party Contact:	WOODY OGLESBY
Responsible Party Address:	1201 MAIN ST INSP DEPT
Responsible Party City,St,Zip:	DALLAS, TX 75283
Responsible Party Telephone:	214/508-4748
Reported Date:	05/29/1991
Case Start Date:	07/07/1993
Reference Number:	RN106997257
Project Manager:	CWC

DP533 **NCNB TEXAS** **TX CENTRAL REGISTRY** **S126862120**
Target **219 E 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 16 in cluster DP

Actual:
488 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN106997257
Name:	NCNB TEXAS
Address:	219 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3625
Status:	ACTIVE
Status Date:	11/20/2013
Customer Number:	CN604478123
Customer Name:	FDIC AMRESCO MGMT INC
Customer Legal Name:	Not reported
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	E 6TH ST

DP534 **MAJESTIC CLEANERS** **EDR Hist Cleaner** **1020033409**
Target **219 E SIXTH** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 16 in cluster DP

Actual:
488 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1969	MAJESTIC CLEANERS	Drycleaning Plants, Except Rugs

DO535 Target Property | **THE REPUBLIC**
401 W 4 STREET
AUSTIN, TX 78701 | **FINDS** | **1027272256**
N/A

Site 2 of 5 in cluster DO

Actual: 478 ft.
Focus Map: 11

FINDS:
Registry ID: 110071251726

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DO536 Target Property | **THE REPUBLIC**
401 W 4 STREET
AUSTIN, TX 78701 | **ECHO** | **1027230844**
N/A

Site 3 of 5 in cluster DO

Actual: 478 ft.
Focus Map: 11

ECHO:

Envid:	1027230844
Registry ID:	110071251726
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071251726
Name:	THE REPUBLIC
Address:	401 W 4 STREET
City,State,Zip:	AUSTIN, TX 78701

DO537 Target Property | **THE REPUBLIC**
401 W 4 STREET
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S128993705**
N/A

Site 4 of 5 in cluster DO

Actual: 478 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN111474656
Name:	THE REPUBLIC
Address:	401 W 4 STREET
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-
Status:	ACTIVE
Status Date:	2022-04-08
Customer Number:	CN603693771
Customer Name:	HARVEY-CLEARY BUILDERS
Customer Legal Name:	Harvey-Cleary Builders
Customer Ownership Type:	OTHER
Affiliation Begin Date:	2022-04-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

THE REPUBLIC (Continued) **S128993705**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

DQ538 **BLACK CAT TATTOO** **TX ASBESTOS** **S119139672**
Target **315 E 6 STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 11 in cluster DQ

Actual:
487 ft.

Focus Map:
11

ASBESTOS:

Name:	BLACK CAT TATTOO
Address:	315 E 6 STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	0.25
Travel Time:	0.01
Mileage:	0.01
Reg:	07
Init:	RC
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/01/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

BLACK CAT TATTOO (Continued) **S119139672**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DQ539 **LEVI JOSEPH MERCHANT TAILOR DVER RPR** **EDR Hist Cleaner** **1013777988**
Target Property **315 E 6TH ST** **N/A**
AUSTIN, TX

Site 2 of 11 in cluster DQ

Actual: 487 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1901	LEVI JOSEPH MERCHANT TAILOR D	DYERS AND SCOURERS

DR540 **TATTOOS FROM THE SOUL INC** **TX ASBESTOS** **S119158238**
Target Property **514 E 6TH ST** **N/A**
AUSTIN, TX 78701

Site 1 of 38 in cluster DR

Actual: 483 ft.
Focus Map: 11

ASBESTOS:

Name:	TATTOOS FROM THE SOUL INC
Address:	514 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	1.5
Mileage:	8.1
Reg:	07

TATTOOS FROM THE SOUL INC (Continued) **S119158238**

Init:	MAO
Seq:	01
Facility Type:	Tattooing
Inspector Name:	Margaret Olsovsky
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DR541 Target Property | **TATTOOS FROM THE SOUL INC**
514 E 6TH STREET
AUSTIN, TX 78701 | **TX ASBESTOS** | **S119158239**
N/A

Site 2 of 38 in cluster DR

Actual: 483 ft.

Focus Map: 11

ASBESTOS:

Name:	TATTOOS FROM THE SOUL INC
Address:	514 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/20/2014
Reason for Inspection:	Routine
Violation:	Not reported
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.1
Travel Time:	0.5
Mileage:	8.1
Reg:	07
Init:	RC
Seq:	01
Facility Type:	Tattooing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	06/23/2014
Date Routed by Supervisor:	06/25/2014
Date Routed to PSQA:	06/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

TATTOOS FROM THE SOUL INC (Continued) **S119158239**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DR542 **ALL SAINTS TATTOO** **TX ASBESTOS** **S119137930**
Target **514 E 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 38 in cluster DR

Actual:
483 ft.

Focus Map:
11

ASBESTOS:

Name:	ALL SAINTS TATTOO
Address:	514 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/21/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	2
Travel Time:	1.5
Mileage:	8.2
Reg:	07
Init:	MAO
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Margaret Olsovsky
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported

ALL SAINTS TATTOO (Continued) **S119137930**

Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DR543 **ALL SAINTS TATTOOS** **TX ASBESTOS** **S119137931**
Target **514 E 6TH STREET** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 38 in cluster DR

Actual:
483 ft.

Focus Map:
11

ASBESTOS:

Name:	ALL SAINTS TATTOOS
Address:	514 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/20/2014
Reason for Inspection:	Routine
Violation:	Not reported
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	2
Travel Time:	0.01

ALL SAINTS TATTOOS (Continued) **S119137931**

Mileage:	0
Reg:	07
Init:	RC
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	06/23/2014
Date Routed by Supervisor:	06/25/2014
Date Routed to PSQA:	06/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DR544 **JUNIOR LEAGUE OF AUSTIN** **TX HIST UST** **S128728993**
Target **522 E 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 5 of 38 in cluster DR

Actual:
480 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JUNIOR LEAGUE OF AUSTIN
Address:	522 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0306
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DR545 **JUNIOR LEAGUE OF AUSTIN PKG LOT** **TX CENTRAL REGISTRY** **S126524125**
Target **524 E 6TH ST** **N/A**
Property **AUSTIN, TX 78701**

Site 6 of 38 in cluster DR

Actual:
480 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101496685
Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600784227
Customer Name:	JUNIOR LEAGUE OF AUSTIN INC
Customer Legal Name:	The Junior League of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/29/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101496685
Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN604433003
Customer Name:	THE JUNIOR LEAGUE OF AUSTIN
Customer Legal Name:	The Junior League Of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101496685

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **S126524125**

Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600784227
Customer Name:	JUNIOR LEAGUE OF AUSTIN INC
Customer Legal Name:	The Junior League of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/29/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101496685
Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN604433003
Customer Name:	THE JUNIOR LEAGUE OF AUSTIN
Customer Legal Name:	The Junior League Of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

DR546 **JUNIOR LEAGUE OF AUSTIN PKG LOT** **TX LPST** **U001290311**
Target **524 E 6TH ST** **TX UST** **N/A**
Property **AUSTIN, TX 78701**

Site 7 of 38 in cluster DR

Actual:
480 ft.

Focus Map:
11

LPST:

Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0061143
LPST Id:	102489
Facility Location:	522 EAST 6TH STREET
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/16/1992
Entered Date:	04/21/1992
Reported Date:	03/16/1992
Closure Date:	05/12/1992
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	ELIZABETH ATHERTON
Responsible Party Address:	5416 PARKCREST 100
Responsible Party City,St,Zip:	AUSTIN, TX 78731
Responsible Party Telephone:	512/467-8982
Reported Date:	03/16/1992
Case Start Date:	05/12/1992
Reference Number:	RN101496685
Project Manager:	HWELCH

UST:

Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
Address:	524 E 6TH ST
City,State,Zip:	AUSTIN, TX 787013742
AI Number:	61143
Facility Type:	UNKNOWN
Facility Begin Date:	10/29/1991
Facility Status:	INACTIVE
Additional ID:	447715092002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/25/1991
Signature Name/Title On Earliest Reg Form:	ELIZABETH W ATHERTON,PRES
Application Received Date On Earliest Reg Form:	10/25/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784227
Owner Last Name:	JUNIOR LEAGUE OF AUSTIN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	439715082002053
Additional ID:	447715092002053
AI Number:	61143
Owner Effective Begin Date:	10/29/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/25/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143418
Facility ID:	91359
Ai Number:	61143
Tank Id:	B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/17/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	B
Tank Capacity:	0
UST Comprt ID:	143062
UST ID:	143418
AI Number:	61143
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/25/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143417
Facility ID:	91359
Ai Number:	61143
Tank Id:	C
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/17/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	C
Tank Capacity:	0
UST Comprt ID:	143061
UST ID:	143417
AI Number:	61143
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Install Date:	08/31/1987
Tank Registration Date:	10/25/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143419
Facility ID:	91359
Ai Number:	61143
Tank Id:	A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/17/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	A
Tank Capacity:	0
UST Comprt ID:	143063
UST ID:	143419
AI Number:	61143
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	JUNIOR LEAGUE OF AUSTIN INC
Contact Mailing Address (Delivery):	5416 PARKCREST DR STE 100
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78731 4935
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

JUNIOR LEAGUE OF AUSTIN PKG LOT (Continued) **U001290311**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91359
Additional ID:	447715092002053
Princ ID:	439715082002053
AI Number:	61143
Facility Name:	JUNIOR LEAGUE OF AUSTIN PKG LOT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ELIZABETH ATHERTON/

DR547 **GREGG AUTO REPAIRS** **EDR Hist Auto** **1013757074**
Target Property **610 RED RIVER** **N/A**
AUSTIN, TX

Site 8 of 38 in cluster DR

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	GREGG AUTO REPAIRS	AUTOMOBILE REPAIRING

DR548 **CAIN RHONIE AUTO** **EDR Hist Auto** **1013768807**
Target Property **608 RED RIVER CT** **N/A**
AUSTIN, TX

Site 9 of 38 in cluster DR

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	CAIN & WILSON C AUTO	AUTOMOBILE REPAIRERS
1935	CAIN RHONIE AUTO	AUTOMOBILE REPAIRERS

DR549 **MARX J W AUTO REPR** **EDR Hist Auto** **1013766542**
Target Property **606 RED RIVER CT** **N/A**
AUSTIN, TX

Site 10 of 38 in cluster DR

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	HAYDEN & ENNIS C	AUTOMOBILE REPAIRERS
1929	MARX J W AUTO REPR	AUTOMOBILE REPAIRERS

DR550 Target Property — **HERRING WALTER B AUTO REPR**, **606 6TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013754512** / **N/A**

Site 11 of 38 in cluster DR

Actual: 478 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	HERRING WALTER B	AUTOMOBILE REPAIRING
1947	HERRING WALTER B AUTO REPR	AUTOMOBILE REPAIRING

DR551 Target Property — **HERRINGS GARAGE AUTO REPR**, **610 6TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013763614** / **N/A**

Site 12 of 38 in cluster DR

Actual: 477 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	HERRINGS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

DR552 Target Property — **HERRINGS GARAGE AUTO REPR**, **610 6TH ST E**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013766645** / **N/A**

Site 13 of 38 in cluster DR

Actual: 477 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1970	HERRINGS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	HERRINGS GARAGE	AUTOMOBILE REPAIRING

DR553 Target Property — **BIG SIX GARAGE AUTO REPRS**, **610 6TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768460** / **N/A**

Site 14 of 38 in cluster DR

Actual: 477 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	BIG SIX GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1953	HERRINGS GARAGE	AUTOMOBILE REPAIRING
1958	HERRINGS GARAGE	AUTOMOBILE REPAIRING
1962	HERRINGS GARAGE	AUTOMOBILE REPAIRING

DS554 **WALKER OIL COMP.** **TX HIST UST** **S128729170**
Target **300-400 GUADALUPE** **N/A**
Property **AUSTIN, TX**

Site 1 of 4 in cluster DS

Actual:
475 ft.
Focus Map:
11

HIST UST AUSTIN:

Name:	WALKER OIL COMP.
Address:	300-400 GUADALUPE
City,State,Zip:	AUSTIN, TX
Id UST:	H0056
HID UST:	Not reported
Inspection:	07/12/1917
Due:	Not reported

DS555 **GUGENHEIM-GOLDSMITH COMPANY** **TX HIST UST** **S111678652**
Target **410 E 3RD ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 4 in cluster DS

Actual:
475 ft.
Focus Map:
11

HIST UST AUSTIN:

Name:	GUGENHEIM-GOLDSMITH COMPANY
Address:	410 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0998
HID UST:	998
Inspection:	Not reported
Due:	06/01/2012

DS556 **AUSTIN MUSEUM OF ART** **TX HIST UST** **S126522022**
Target **400 W 3RD ST AUSTIN TX 78701** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 4 in cluster DS

Actual:
475 ft.
Focus Map:
11

HIST UST AUSTIN:

Name:	MISSOURI PACIFIC RAILROAD
Address:	400 W 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0403
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101461853
Name:	AUSTIN MUSEUM OF ART
Address:	400 W 3RD ST AUSTIN TX 78701
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600757082
Customer Name:	THE CONTEMPORARY AUSTIN MUSEUM INC

AUSTIN MUSEUM OF ART (Continued) **S126522022**

Customer Legal Name:	The Contemporary Austin Museum, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	400 W 3RD ST AUSTIN TX 78701

Regulated Entity Number:	RN101461853
Name:	AUSTIN MUSEUM OF ART
Address:	400 W 3RD ST AUSTIN TX 78701
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600757082
Customer Name:	THE CONTEMPORARY AUSTIN MUSEUM INC
Customer Legal Name:	The Contemporary Austin Museum, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	400 W 3RD ST AUSTIN TX 78701

DT557 **MAGNOLIA PETROLEUM COMP.** **TX HIST UST** **S111678742**
Target **617 E 6TH ST** **N/A**
Property **AUSTIN, TX**

Site 1 of 2 in cluster DT

Actual:
473 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM COMP.
Address:	617 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0197
HID UST:	197
Inspection:	10/22/2010
Due:	10/22/2013

DU558 **504 5TH ST** **TX ASBESTOS** **S126537787**
Target **504 EAST 5TH ST** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 19 in cluster DU

Actual:
477 ft.

Focus Map:
11

ASBESTOS:

Name:	504 5TH ST
Address:	504 EAST 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported

504 5TH ST (Continued) **S126537787**

Complaint Date:	02/22/2023
Notification Number:	2023000224
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/16/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/16/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	01/23/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

504 5TH ST (Continued) **S126537787**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	504 5TH ST
Address:	504 EAST 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/17/2023
Notification Number:	2023000224
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/06/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	01/23/2023

504 5TH ST (Continued) **S126537787**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	504 5TH ST
Address:	504 EAST 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/07/2023
Notification Number:	2023000224
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	01/10/2023

504 5TH ST (Continued) **S126537787**

Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	01/23/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101718575
Name:	SANY MOUNTAIN WTP
Address:	504 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3726
Status:	ACTIVE
Status Date:	2002-03-20
Customer Number:	CN600922116
Customer Name:	SANDY MOUNTAIN DEVELOPMENT CO
Customer Legal Name:	Sandy Mountain Development Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221310
Primary NAICS Industry Type Description:	Water Supply and Irrigation Systems
Physical Location Description:	Not reported

Regulated Entity Number:	RN101718575
Name:	SANY MOUNTAIN WTP
Address:	504 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3726

504 5TH ST (Continued) **S126537787**

Status:	ACTIVE
Status Date:	2002-03-20
Customer Number:	CN600922116
Customer Name:	SANDY MOUNTAIN DEVELOPMENT CO
Customer Legal Name:	Sandy Mountain Development Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221310
Primary NAICS Industry Type Description:	Water Supply and Irrigation Systems
Physical Location Description:	Not reported

Regulated Entity Number:	RN101718575
Name:	SANY MOUNTAIN WTP
Address:	504 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3726
Status:	ACTIVE
Status Date:	2002-03-20
Customer Number:	CN600922116
Customer Name:	SANDY MOUNTAIN DEVELOPMENT CO
Customer Legal Name:	Sandy Mountain Development Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	221310
Primary NAICS Industry Type Description:	Water Supply and Irrigation Systems
Physical Location Description:	Not reported

DU559 **STEARNS JACK AUTO** **EDR Hist Auto** **1013767526**
Target Property **502 RED RIVER CT** **N/A**
AUSTIN, TX

Site 2 of 19 in cluster DU

Actual: 473 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1935	STEARNS JACK AUTO	AUTOMOBILE REPAIRERS
1940	STEARNS JOHN E AUTO	AUTOMOBILE REPAIRING
1947	LEWIS SIMON D AUTO REPR	AUTOMOBILE REPAIRING

DV560 **CATHYS DOWNTOWN CLEANERS** **TX CENTRAL REGISTRY** **S126835819**
Target Property **231 W 3RD ST** **N/A**
AUSTIN, TX 78701

Site 1 of 4 in cluster DV

Actual: 477 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN106343353
Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3879

CATHYS DOWNTOWN CLEANERS (Continued) **S126835819**

Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604038679
Customer Name:	CATHYS CLEANERS DOWNTOWN INC
Customer Legal Name:	Cathy's Cleaners Downtown, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/1/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106343353
Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3879
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604038679
Customer Name:	CATHYS CLEANERS DOWNTOWN INC
Customer Legal Name:	Cathy's Cleaners Downtown, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/1/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106343353
Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3879
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604038679
Customer Name:	CATHYS CLEANERS DOWNTOWN INC
Customer Legal Name:	Cathy's Cleaners Downtown, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/1/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106343353
Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3879
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604038679

CATHYS DOWNTOWN CLEANERS (Continued) **S126835819**

Customer Name:	CATHYS CLEANERS DOWNTOWN INC
Customer Legal Name:	Cathy's Cleaners Downtown, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/1/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106343353
Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3879
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604038679
Customer Name:	CATHYS CLEANERS DOWNTOWN INC
Customer Legal Name:	Cathy's Cleaners Downtown, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/1/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

DV561 **CATHYS DOWNTOWN CLEANERS** **TX DRYCLEANERS** **S111990228**
Target **231 W 3RD ST** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 4 in cluster DV

Actual:
477 ft.

Focus Map:
11

DRYCLEANERS:

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289193
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289193
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHY S CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289701
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289193
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289193
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289701
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	11
CN Number:	CN604038679
DCR Number:	Not reported
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	THYCA77@YAHOO.COM
Phone Number:	512 2289197
Site Name:	CATHYS DOWNTOWN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289701
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289193
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

CATHYS DOWNTOWN CLEANERS (Continued) **S111990228**

Name:	CATHYS DOWNTOWN CLEANERS
Address:	231 W 3RD ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN106343353
Region:	REGION 11 - AUSTIN
CN Number:	CN604038679
DCR Number:	DCR15515
AR Number:	24006560
Principal Name:	CATHYS CLEANERS DOWNTOWN INC
Bill Addr1:	231 W 3RD ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 3879
EMail:	HANG.NGUYEN@CATHYSCLEANERS.NET
Phone Number:	512 2289701
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

DV562 **CATHY CLEANER** **EDR Hist Cleaner** **1018784417**
Target **231 W 3RD ST** **N/A**
Property **AUSTIN, TX 78701**

Site 3 of 4 in cluster DV

Actual:
477 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
2007	CATHY CLEANER	Laundry And Drycleaner Agents
2008	CATHY CLEANER	Laundry And Drycleaner Agents
2009	CATHY CLEANER	Laundry And Drycleaner Agents
2010	CATHY CLEANER	Laundry And Drycleaner Agents
2011	CATHY CLEANER	Laundry And Drycleaner Agents
2012	CATHY CLEANER	Laundry And Drycleaner Agents
2013	CATHY CLEANER	Laundry And Drycleaner Agents
2014	CATHY CLEANER	Laundry And Drycleaner Agents

DU563 **YELLOW CAB** **TX HIST UST** **S111678863**
Target **555 E 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 3 of 19 in cluster DU

Actual:
473 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	YELLOW CAB
Address:	555 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0670
HID UST:	670
Inspection:	Not reported
Due:	06/01/2012

DW564 **SUBSTATION; SEAHOLM** **TX TIER 2** **S113677653**
Target **704 W CESAR CHAVEZ** **N/A**
Property **AUSTIN, TX**

Site 1 of 3 in cluster DW

Actual:
454 ft.

Focus Map:
11

TIER 2:

Facility Id/Name:	FASAFTEC505880228410/SUBSTATION; SEAHOLM
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	02/27/2013
Mailing Address:	811 Barton Springs Rd. Environmental Services
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4911
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	02/27/2013
Id:	2211
Id Type:	SIC
Description:	Not reported
Last Modified:	02/27/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	811 Barton Springs Rd. Environmental Services
Contact City/State/Zip:	Austin, TX 78704-1194
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	City of Austin dba Austin Energy
Title:	Not reported
Modification Date:	3/8/2013

SUBSTATION; SEAHOLM (Continued) **S113677653**

Contact:

Contact Email:	Not reported
Contact Mail Address:	704 W CESAR CHAVEZ
Contact City/State/Zip:	Austin, TX
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Operator
Title:	Emergency Control Center
Modification Date:	3/8/2013

Chemical Inventory:

Facility Id:	FASAFTEC505880228410
Chemical Name:	Lead-Acid Battery Electrolyte
Chemical Inv Record Id:	CVSAFTEC606928815120
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/8/2013
Days On Site:	366
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLSAFTEC369933214737
Chemical Inventory Record Id:	CVSAFTEC606928815120
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Not reported
Last Modified:	3/8/2013

Mixture:

Record Key:	CMSAFTEC327395906164
Chemical Inv Record Id:	CVSAFTEC606928815120
Mix Chemical:	Sulfuric Acid
Percentage:	75.7
Facility Id:	FASAFTEC505880228410
Mixture Cas:	7664-93-9

SUBSTATION; SEAHOLM (Continued) **S113677653**

Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/8/2013

Record Key:	CMSAFTEC357395050239
Chemical Inv Record Id:	CVSAFTEC606928815120
Mix Chemical:	Sulfuric Acid
Percentage:	24.2
Facility Id:	FASAFTEC505880228410
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/8/2013

Facility Id:	FASAFTEC505880228410
Chemical Name:	ASTM D-3487 Type II Transformer Oil
Chemical Inv Record Id:	CVSAFTEC737442342476
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/8/2013
Days On Site:	366
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLSAFTEC256266435630
Chemical Inventory Record Id:	CVSAFTEC737442342476
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	Not reported
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Not reported
Last Modified:	3/8/2013

Mixture:

Record Key:	CMSAFTEC871797592460
Chemical Inv Record Id:	CVSAFTEC737442342476
Mix Chemical:	Highly Refined Petroleum Oils
Percentage:	50.0

SUBSTATION; SEAHOLM (Continued) **S113677653**

Facility Id:	FASAFTEC505880228410
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/8/2013

Record Key:	CMSAFTEC270117836518
Chemical Inv Record Id:	CVSAFTEC737442342476
Mix Chemical:	Dielectric Oil
Percentage:	50.0
Facility Id:	FASAFTEC505880228410
Mixture Cas:	Not reported
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	3/8/2013

Notes:	Not reported
Validation:	Not reported

DW565 Target Property **SEAHOLM SUBSTATION**
704 WEST CESAR CHAVEZ
AUSTIN, TX 78703

TX TIER 2 **S111995697**
N/A

Site 2 of 3 in cluster DW

Actual: 454 ft.

Focus Map: 11

TIER 2:

Facility Id/Name:	FATR201171MMKM010FR9/SEAHOLM SUBSTATION
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	03/09/2012
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	0
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	fred blood
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

SEAHOLM SUBSTATION (Continued) **S111995697**

Facility Info:

Id:	221122
Id Type:	NAICS
Description:	Electric Power Distribution
Last Modified:	2/23/2010
Id:	4911
Id Type:	SIC
Description:	ELECTRICAL SERVICES
Last Modified:	2/23/2010
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/23/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Austin Energy City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	3/13/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	2412 Kramer Ln.
Contact City/State/Zip:	Austin, TX 78758
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Todd Henson
Title:	Substation Supt.
Modification Date:	3/13/2012

Contact:

Contact Email:	fred.blood@austinenergy.com
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/15/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	310 WEST AVE.
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact

SEAHOLM SUBSTATION (Continued) **S111995697**

Contact Type 2: Owner / Operator
Contact Name: Energy Control Center
Title: Emergency
Modification Date: 3/13/2012

Chemical Inventory:
Facility Id: FATR201171MMKM010FR9
Chemical Name: Sulfuric Acid (in batteries)
Chemical Inv Record Id: CVTR201171MMKM019FUG
CAS Number: 7664-93-9
Chemical Same As Last Year: Not reported
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 1,000 - 9,999 pounds
Max Amount In Largest Container: 24
Chronic Health Risks: T
EHS Substance: T
Last Modified: 3/13/2012
Days On Site: 365
Fire Hazard: T
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2011
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR201171MMKM01AFWB
Chemical Inventory Record Id: CVTR201171MMKM019FUG
Amt Of Sub Stored Or Transported: 98
Amount Units: gallons
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: in batteries in substation maint building
Last Modified: 3/13/2012

Notes: Not reported
Validation: Not reported

DU566 **FOUND ON SANBORN MAPS** **TX HIST UST** **S111678643**
Target **601 E 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 4 of 19 in cluster DU

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	FOUND ON SANBORN MAPS
Address:	601 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H1005
HID UST:	1005
Inspection:	Not reported
Due:	06/01/2012

DU567 **G W CUNNINGHAM** **TX HIST UST** **S111678645**
Target **601 E 5TH ST** **N/A**
Property **AUSTIN, TX**

Site 5 of 19 in cluster DU

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	G W CUNNINGHAM
Address:	601 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0133
HID UST:	133
Inspection:	02/06/2009
Due:	02/06/2012

DX568 **BLOCK 21** **FINDS** **1010710420**
Target **201 GUADALUPE ST** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 7 in cluster DX

Actual:
473 ft.

Focus Map:
11

FINDS:
Registry ID: 110033409103

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DX569 Target Property | **BLOCK 21 CITY OF AUSTIN**
201 GUADALUPE STREET
AUSTIN, TX | **TX GCC** | **S108652512**
TX IOP | **N/A**

Site 2 of 7 in cluster DX

Actual: 473 ft.

Focus Map: 11

GCC:

Name:	BLOCK 21 CITY OF AUSTIN
Address:	201 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX
Division:	RMD/VCIO
New Cases:	Not reported
File Number:	619
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	5/11/2007
Enforcement Status - Level Of Agency Response:	6 -
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

IOP:

Name:	BLOCK 21 CITY OF AUSTIN
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Program ID:	619
Date IOP Received:	Not reported
Region:	REGION 11 - AUSTIN
Phase:	COMPLETED
Interest In Site:	Not reported
PCA Number:	32619
Property Use:	PARKING/TRANSIT CENTER
Project Manager:	SDUNAHOO
Project Number:	326190
Latitude:	30.27
Longitude:	-97.75
Acres:	1.80
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	09/10/2008
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported

BLOCK 21 CITY OF AUSTIN (Continued) **S108652512**

Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN105233845
Consultant/Attorney Phone:	Not reported
Site Address Description:	BOUNDED BY W 3RD ST TO THE NORTH, WEST 2ND ST TO THE SOUTH, GUADALUPE ST TO THE WEST AND LAVACA ST TO THE EAST
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	05/11/2007
Application Received Date:	05/11/2007
Application Acceptance Date:	Not reported
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	Not reported

Customer:

REM Program:	IOP
Program ID:	619
RN Number:	RN105233845
CN Number:	CN603195819
CN Name:	STRATUS BLOCK 21 INVESTMENTS LP
Role CD:	BILLCONT
Contact Name:	JONES, KENNETH
Contact Title:	Not reported
Organization Name:	STRATUS BLOCK 21 INVESTMENTS
Mailing Address:	98 SAN JACINTO BLVD STE 220
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78701
Contact Phone:	(512) 435-2302
Contact Ext:	0

REM Program:	IOP
Program ID:	619
RN Number:	RN105233845
CN Number:	CN603195819
CN Name:	STRATUS BLOCK 21 INVESTMENTS LP
Role CD:	APPLCONT
Contact Name:	JONES, KENNETH
Contact Title:	AUTHORIZED AGENT
Organization Name:	STRATUS BLOCK 21 INVESTMENTS LP
Mailing Address:	98 SAN JACINTO BLVD STE 220
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78701
Contact Phone:	(512) 435-2302
Contact Ext:	0

DU570 Target Property — **BETHKE WALTER AUTO**, **408 RED RIVER**, **AUSTIN, TX** — **EDR Hist Auto** — **1013753290** / **N/A**

Site 6 of 19 in cluster DU

Actual: 470 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	BETHKE WALTER AUTO	AUTOMOBILE REPAIRING

DY571 Target Property — **PARSLEY W L DCLO CLNR**, **310 CONGRESS AVE E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780574** / **N/A**

Site 1 of 11 in cluster DY

Actual: 478 ft. — EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	PARSLEY W L DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

DX572 Target Property — **COVERT BUICK BODY SHOP**, **402 2ND ST W**, **AUSTIN, TX 78701** — **EDR Hist Auto** — **1013756991** / **N/A**

Site 3 of 7 in cluster DX

Actual: 472 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1980	COVERT BUICK BODY SHOP	AUTOMOBILE REPAIRING

DX573 Target Property — **COVERT BUICK BODY SHOP**, **402 2ND ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013763112** / **N/A**

Site 4 of 7 in cluster DX

Actual: 472 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	COVERT BUICK BODY SHOP	AUTOMOBILE REPAIRING

---

574 Target Property — **GAS PIPE**, **701 E 5TH ST**, **AUSTIN, TX 78701** — **TX ASBESTOS** — **S119146692** / **N/A**

Actual: 462 ft.

Focus Map: 11

ASBESTOS:

Name:	GAS PIPE
Address:	701 E 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/24/2013
Reason for Inspection:	Routine
Violation:	No

GAS PIPE (Continued) **S119146692**

Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

GAS PIPE (Continued) **S119146692**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WATERLOO CENTRAL
Address:	701 EAST 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	03/08/2021
Notification Number:	2021000512
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/16/2021
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/22/2021

GAS PIPE (Continued) **S119146692**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WATERLOO CENTRAL
Address:	701 EAST 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	03/08/2021
Notification Number:	2021000512
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/04/2021

GAS PIPE (Continued) **S119146692**

Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/15/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WATERLOO CENTRAL
Address:	701 EAST 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	03/08/2021
Notification Number:	2021000512
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/12/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

GAS PIPE (Continued) **S119146692**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/12/2021
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WATERLOO CENTRAL
Address:	701 EAST 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	03/08/2021
Notification Number:	2021000512
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

GAS PIPE (Continued) **S119146692**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/16/2021
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/17/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

GAS PIPE (Continued) **S119146692**

Inspection Number Grade:	Not reported
Name:	WATERLOO CENTRAL
Address:	701 EAST 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Adam Robles
Violation:	Not reported
Complaint Date:	02/12/2021
Notification Number:	2021000512
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/25/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	01/25/2021
Certification Statement Phone:	575-915-2893
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/08/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

GAS PIPE (Continued) **S119146692**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DZ575 **SMITH BROS AUTO DLR** **EDR Hist Auto** **1013758538**
Target **301 BRAZOS** **N/A**
Property **AUSTIN, TX**

Site 1 of 7 in cluster DZ

Actual:
478 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	SMITH BROS AUTO DLR	AUTOMOBILE REPAIRING
1953	SMITH BROTHERS AUTOS	AUTOMOBILE REPAIRING

DZ576 **THE WHITLEY** **TX CENTRAL REGISTRY** **S126612761**
Target **301 BRAZOS ST** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 7 in cluster DZ

Actual:
478 ft.

CENTRAL REGISTRY:

Focus Map:
11

Regulated Entity Number:	RN103209573
Name:	THE WHITLEY
Address:	301 BRAZOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4330
Status:	ACTIVE
Status Date:	2003-06-30
Customer Number:	CN600325203
Customer Name:	THE WHITLEY COMPANY LP
Customer Legal Name:	The Whitley Company, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2002-07-09
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323110
Primary NAICS Industry Type Description:	Commercial Lithographic Printing
Physical Location Description:	Not reported

Regulated Entity Number:	RN103209573
Name:	THE WHITLEY
Address:	301 BRAZOS ST
Address 2:	Not reported

THE WHITLEY (Continued) **S126612761**

City,State,Zip:	AUSTIN, TX 78701-4330
Status:	ACTIVE
Status Date:	2003-06-30
Customer Number:	CN600325203
Customer Name:	THE WHITLEY COMPANY LP
Customer Legal Name:	The Whitley Company, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2002-07-09
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323110
Primary NAICS Industry Type Description:	Commercial Lithographic Printing
Physical Location Description:	Not reported

Regulated Entity Number:	RN103209573
Name:	THE WHITLEY
Address:	301 BRAZOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4330
Status:	ACTIVE
Status Date:	2003-06-30
Customer Number:	CN602496192
Customer Name:	RIVERSIDE RESOURCES MANAGEMENT LLC
Customer Legal Name:	Riverside Resources Management, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-10-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323110
Primary NAICS Industry Type Description:	Commercial Lithographic Printing
Physical Location Description:	Not reported

Regulated Entity Number:	RN103209573
Name:	THE WHITLEY
Address:	301 BRAZOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4330
Status:	ACTIVE
Status Date:	2003-06-30
Customer Number:	CN602496192
Customer Name:	RIVERSIDE RESOURCES MANAGEMENT LLC
Customer Legal Name:	Riverside Resources Management, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-10-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323110
Primary NAICS Industry Type Description:	Commercial Lithographic Printing
Physical Location Description:	Not reported

DZ577	**WHITLEY COMPANY#**	**RCRA-SQG**	**1000414748**
Target	**301-05 BRAZOS**	**FINDS**	**TXD008116857**
Property	**AUSTIN, TX 78767**	**ECHO**	

Site 3 of 7 in cluster DZ

Actual:
478 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	19800728
Handler Name:	Whitley Company#
Handler Address:	BRAZOS
Handler City,State,Zip:	AUSTIN, TX 78767
EPA ID:	TXD008116857
Contact Name:	JOHN-G JONES
Contact Address:	PO BOX 1564
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-476-7101
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1564
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	John G Jones President Corporation
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

WHITLEY COMPANY# (Continued) **1000414748**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JOHN G JONES PRESIDENT CORPORATION
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19800728
Handler Name:	WHITLEY COMPANY#
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	32311
NAICS Description:	PRINTING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

WHITLEY COMPANY# (Continued) **1000414748**

FINDS:
Registry ID: 110005038324

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000414748
Registry ID:	110005038324
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005038324
Name:	WHITLEY COMPANY#
Address:	301-05 BRAZOS
City,State,Zip:	AUSTIN, TX 78767

DZ578 **MUELLERS GAR AUTO** **EDR Hist Auto** **1013766906**
Target Property **212 3RD E** **N/A**
AUSTIN, TX

Site 4 of 7 in cluster DZ

Actual: 478 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	MUELLERS GAR AUTO	AUTOMOBILE REPAIRING

DZ579 **MUELLERS GARAGE GR** **EDR Hist Auto** **1013769917**
Target Property **212 3RD ST E** **N/A**
AUSTIN, TX

Site 5 of 7 in cluster DZ

Actual: 478 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	MUELLERS GARAGE GR	AUTOMOBILE REPAIRING

DZ580 THIRD AND BRAZOS **TX ASBESTOS** **S127320270**
Target 201 EAST 3RD **N/A**
Property AUSTIN, TX 78701

Site 6 of 7 in cluster DZ

Actual: 477 ft.

Focus Map: 11

ASBESTOS:

Name:	THIRD AND BRAZOS
Address:	201 EAST 3RD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/21/2022
Reason for Inspection:	Tammie S Garza
Violation:	Not reported
Complaint Date:	04/09/2021
Notification Number:	2021000580
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/09/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/09/2021
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/08/2021
Client Code:	Not reported
Client Name:	Not reported

THIRD AND BRAZOS (Continued) **S127320270**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	THIRD AND BRAZOS
Address:	201 EAST 3RD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/21/2022
Reason for Inspection:	Tammie S Garza
Violation:	Not reported
Complaint Date:	04/02/2021
Notification Number:	2021000580
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/19/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/19/2021
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N

THIRD AND BRAZOS (Continued) **S127320270**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	THIRD AND BRAZOS
Address:	201 EAST 3RD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/21/2022
Reason for Inspection:	Tammie S Garza
Violation:	Not reported
Complaint Date:	04/16/2021
Notification Number:	2021000580
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/24/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

THIRD AND BRAZOS (Continued) **S127320270**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/24/2021
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/08/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	THIRD AND BRAZOS
Address:	201 EAST 3RD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/21/2022
Reason for Inspection:	Tammie S Garza
Violation:	Not reported
Complaint Date:	04/02/2021
Notification Number:	2021000580
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

THIRD AND BRAZOS (Continued) **S127320270**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	01/27/2021
Certification Statement Phone:	713-670-0135
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DZ581 Target Property | **BNK 63**
201 E 3RD ST
AUSTIN, TX | **TX HIST UST** | **S128728982**
N/A

Site 7 of 7 in cluster DZ

Actual: 477 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	BNK 63
Address:	201 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0281
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EA582 Target Property | **THOMAS REPROGRAPHICS**
304 E 3RD ST
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S128251767**
N/A

Site 1 of 4 in cluster EA

Actual: 477 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN111321204
Name:	THOMAS REPROGRAPHICS
Address:	304 E 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4036
Status:	ACTIVE
Status Date:	2021-08-23
Customer Number:	CN600379812
Customer Name:	THOMAS REPROGRAPHICS INC
Customer Legal Name:	Thomas Reprographics, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2021-08-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN111321204
Name:	THOMAS REPROGRAPHICS
Address:	304 E 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4036
Status:	ACTIVE
Status Date:	2021-08-23
Customer Number:	CN600379812
Customer Name:	THOMAS REPROGRAPHICS INC
Customer Legal Name:	Thomas Reprographics, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2021-08-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

EA583 Target Property | **THOMAS REPROGRAPHICS**
304 E 3RD ST
AUSTIN, TX 78701 | **FINDS** | **1027122854**
N/A

Site 2 of 4 in cluster EA

Actual: 477 ft.
Focus Map: 11

FINDS:
Registry ID: 110071158292

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EA584 Target Property | **THOMAS REPROGRAPHICS**
304 E 3RD ST
AUSTIN, TX 78701 | **ECHO** | **1026941612**
N/A

Site 3 of 4 in cluster EA

Actual: 477 ft.
Focus Map: 11

ECHO:

Envid:	1026941612
Registry ID:	110071158292
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071158292
Name:	THOMAS REPROGRAPHICS
Address:	304 E 3RD ST
City,State,Zip:	AUSTIN, TX 78701

EB585 Target Property | **SILICON LABORATORIES**
AUSTIN, TX | **PFAS ECHO** | **1027419708**
N/A

Site 1 of 2 in cluster EB

Actual: 462 ft.
Focus Map: 11

PFAS ECHO:

Name:	SILICON LABORATORIES
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.26434
Longitude:	-97.74804
Count:	1
County:	TRAVIS
Status:	Active
Region:	06
Industry:	Electronics Industry
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110061391701
Facility Percent Minority:	45.586
Facility Derived Tribes:	-
Facility Population:	5638.18
EPA Programs:	CWA

SILICON LABORATORIES (Continued) **1027419708**

Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	21
Facility Derived CB2010:	484530011001142
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXRNEY881
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	3674
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	Y
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.74804,%22y%22:30.26434,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

EC586 Target Property | **CIRCLE SAW SHOP**
201 TRINITY ST
AUSTIN, TX | **TX HIST UST** | **S128728939**
N/A

Site 1 of 5 in cluster EC

Actual: 472 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CIRCLE SAW SHOP
Address:	201 TRINITY ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0166
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EC587 Target Property | **HOBART**
404 E 2ND ST
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S126554894**
N/A

Site 2 of 5 in cluster EC

Actual: 472 ft.
Focus Map: 11

CENTRAL REGISTRY:

Regulated Entity Number:	RN101955284
Name:	HOBART
Address:	404 E 2ND ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-
Status:	ACTIVE
Status Date:	4/6/2002
Customer Number:	CN600379135
Customer Name:	HOBART CORPORATION
Customer Legal Name:	Hobart Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/26/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	404 E 2nd St, Austin, TX

EC588 Target Property | **HOBART**
404 E 2ND ST
AUSTIN, TX 78701 | **TX Ind. Haz Waste** | **S102755331**
N/A

Site 3 of 5 in cluster EC

Actual: 472 ft.
Focus Map: 11

Ind. Haz Waste:

Name:	HOBART
Address:	404 E 2ND ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	73877
Registration Initial Notification Date:	10/23/1989
Registration Last Amendment Date:	02/26/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19891023

HOBART (Continued) **S102755331**

Land Type:	Not reported
Description of Facility Site Location:	404 E 2nd St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	HOBART CORPORATION
Contact Name:	DEBBIE HOLINGSWORTH
Contact Telephone Number:	Not reported
Mailing Address:	404 E 2ND ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 78701
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28286
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	HOBART CORPORATION
Operator Address:	404 E 2NDST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13636453352
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

HOBART (Continued) **S102755331**

Owner Name:	HOBART CORPORATION
Owner Mailing Address:	404 E 2NDST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13636453352
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	404 E 2NDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	404 E 2NDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DEBBIE HOLINGSWORTH
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	404 E 2NDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

EC589 Target Property — **COVERT AUTOMOBILE CO.**, **440 E 2ND ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678615** / **N/A**

Site 4 of 5 in cluster EC

Actual: 472 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	COVERT AUTOMOBILE CO.
Address:	440 E 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0596
HID UST:	596
Inspection:	04/22/2009
Due:	04/22/2012

EC590 Target Property — **M. SCHNEIDER ESTATE**, **440 E 2ND ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678732** / **N/A**

Site 5 of 5 in cluster EC

Actual: 472 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	M. SCHNEIDER ESTATE
Address:	440 E 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0312
HID UST:	312
Inspection:	04/22/2009
Due:	04/22/2012

ED591 Target Property — **SETH ENGINE PARTS**, **617 E 3RD ST**, **AUSTIN, TX 78701** — **TX UST**, **TX HIST UST** — **U004022062** / **N/A**

Site 1 of 4 in cluster ED

Actual: 461 ft.
Focus Map: 11

UST:

Name:	SETH ENGINE PARTS
Address:	617 E 3RD ST
City,State,Zip:	AUSTIN, TX 78701
AI Number:	49597
Facility Type:	UNKNOWN
Facility Begin Date:	01/18/1990
Facility Status:	INACTIVE
Additional ID:	231595552002152
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported

SETH ENGINE PARTS (Continued) **U004022062**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/30/1989
Signature Name/Title On Earliest Reg Form:	BOB HENDRICKSON,ENGINEER
Application Received Date On Earliest Reg Form:	10/30/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	231595552002152
AI Number:	49597
Owner Effective Begin Date:	01/18/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/30/1989
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	128686
Facility ID:	37585
Ai Number:	49597
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/22/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

SETH ENGINE PARTS (Continued) **U004022062**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	329
UST ID:	128686
AI Number:	49597
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported

SETH ENGINE PARTS (Continued) **U004022062**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37585
Additional ID:	231595552002152
Princ ID:	840354562001227
AI Number:	49597
Facility Name:	SETH ENGINE PARTS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	SETH ENGINE PARTS

SETH ENGINE PARTS (Continued) **U004022062**

Address:	617 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0277
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ED592 **FORMER SETH ENGINE PARTS FACILITY** **TX LPST** **S116702849**
Target **617 E 3RD ST** **N/A**
Property **AUSTIN, TX 78701**

Site 2 of 4 in cluster ED

Actual:
461 ft.

Focus Map:
11

LPST:

Name:	FORMER SETH ENGINE PARTS FACILITY
Address:	617 E 3RD ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0049597
LPST Id:	094728
Facility Location:	617 E 3RD ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/22/1990
Entered Date:	02/28/1990
Reported Date:	01/22/1990
Closure Date:	12/09/1992
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	DEH
Responsible Party Name:	Not reported
Responsible Party Contact:	NATHAN SCHNEIDER
Responsible Party Address:	505 BARTON SPRINGS RD
Responsible Party City,St,Zip:	AUSTIN, TX 78704
Responsible Party Telephone:	512/499-7218
Reported Date:	01/22/1990
Case Start Date:	12/09/1992
Reference Number:	RN102067188
Project Manager:	DEH

ED593 **HOLIDAY CLEANERS** **RCRA NonGen / NLR** **1000238076**
Target **12300 INWOOD RD STE 101** **FINDS** **TXD080255581**
Property **DALLAS, TX 75244** **ECHO**
TX Ind. Haz Waste

Site 3 of 4 in cluster ED

Actual:
461 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Holiday Cleaners
Handler Address:	INWOOD RD STE 101
Handler City,State,Zip:	DALLAS, TX 75244
EPA ID:	TXD080255581

HOLIDAY CLEANERS (Continued) **1000238076**

Contact Name:	VERN TRAWICK
Contact Address:	INWOOD RD STE 101
Contact City,State,Zip:	DALLAS, TX 75244
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	04
Mailing Address:	INWOOD RD STE 101
Mailing City,State,Zip:	DALLAS, TX 75244
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

HOLIDAY CLEANERS (Continued) **1000238076**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CARL G SETH	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19870408
Handler Name: SETH ENGINE PARTS DIST CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: HOLIDAY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

HOLIDAY CLEANERS (Continued) **1000238076**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005063723

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000238076
Registry ID:	110005063723
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005063723
Name:	HOLIDAY CLEANERS
Address:	12300 INWOOD RD STE 101
City,State,Zip:	DALLAS, TX 75244

Ind. Haz Waste:

Name:	SETH ENGINE PARTS
Address:	617 S 3RD ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	61869
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/14/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	617 S 3rd St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG

HOLIDAY CLEANERS (Continued) **1000238076**

Type of Generator:	NON INDUS
Company Name:	SETH ENGINE PARTS
Contact Name:	CARL SETH
Contact Telephone Number:	Not reported
Mailing Address:	617 S 3RD ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787041601
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20208
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030305
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	SETH ENGINE PARTS
Operator Address:	617 S 3RDST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17419884592
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	SETH ENGINE PARTS
Owner Mailing Address:	617 S 3RDST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17419884592
Owner Bankruptcy Code:	Not reported

HOLIDAY CLEANERS (Continued) **1000238076**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	617 S 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	617 S 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	CARL SETH
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	617 S 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

EE594 **DEWEYS RADIATOR WORKS** **EDR Hist Auto** **1013759843**
Target **106 TRINITY ST** **N/A**
Property **TRAVIS (County), TX 78701**

Site 1 of 4 in cluster EE

Actual:
470 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	DEWEYS RAIDIATOR WEORKS R CPRS	AUTOMOBILE RADIATOR REPAIRERS
1971	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1972	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1973	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1974	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1975	DEWEYS RADIATOR WORKS REPRS	AUTOMOBILE RADIATOR REPAIRERS
1975	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1976	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1977	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1978	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1979	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1980	DEWEYS RADIATOR WORKS REPRS	AUTOMOBILE RADIATOR REPAIRERS
1980	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC

DEWEYS RADIATOR WORKS (Continued) **1013759843**

1982	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1983	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1984	DEWEYS RADIATOR WORKS	AUTOMOBILE RADIATOR REPAIRERS
1985	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1986	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1986	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1987	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1987	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1988	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1989	DEWEYS RADIATOR WORKS	Powertrain Components Repair Services
1990	DEWEYS RADIATOR WORKS	AUTOMOBILE RADIATOR REPAIRERS
1990	DEWEYS RADIATOR WORKS	Powertrain Components Repair Services
1991	DEWEYS RADIATOR WORKS	Powertrain Components Repair Services

---

595 **GLENN SERVICE STATION FILLING STA** **EDR Hist Auto** **1013769316**
Target **10 CONGRESS AVE** **N/A**
Property **AUSTIN, TX**

EDR Hist Auto

Actual:
435 ft.

Focus Map:
11

Year:	Name:	Type:
1940	GLENN SERVICE STATION FILLING S	GASOLINE AND OIL SERVICE STATIONS

---

596 **WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY** **TX ENF** **S113871149**
Target **74 TRINITY ST** **TX COMP HIST** **N/A**
Property **AUSTIN, TX**

Actual:
463 ft.

Focus Map:
11

ENFORCEMENT:

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	ALEXA LOCKLEAR
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	CAPITAL IMPROVEMENT CONSTRUCTION & INSPECTION SUPERVISOR
Physical Location:	74 TRINITY ST
Near City:	AUSTIN
Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.

WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY (Continued) **S113871149**

Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	STEPHEN HAWKINS
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	ENVIRONMENTAL INSPECTION SENIOR
Physical Location:	74 TRINITY ST
Near City:	AUSTIN
Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	PARTICIPAT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported

WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY (Continued) **S113871149**

Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	STEPHEN HAWKINS
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	ENVIRONMENTAL INSPECTION SENIOR
Physical Location:	74 TRINITY ST
Near City:	AUSTIN
Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	JASON DEVANEY
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	PROJECT MANAGER
Physical Location:	74 TRINITY ST
Near City:	AUSTIN

WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY (Continued) **S113871149**

Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	JASON DEVANEY
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	PROJECT MANAGER
Physical Location:	74 TRINITY ST
Near City:	AUSTIN
Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	PARTICIPAT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported

WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY (Continued) **S113871149**

TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN600135198
Unique TCEQ Ref Number Of Reg. Entity:	RN106664659
Contact Person For The Reg. Entity:	ALEXA LOCKLEAR
Owner/operator Of A Regulated Entity:	CITY OF AUSTIN
Regulated Entity Associated With An NOV:	CONSTRUCTION
Org Title Of The Contact Person:	CAPITAL IMPROVEMENT CONSTRUCTION & INSPECTION SUPERVISOR
Physical Location:	74 TRINITY ST
Near City:	AUSTIN
Investigation Number:	000000001088976
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,504,062,013,134.00
Role Code:	PARTICIPAT
Date Notice Of Violation Issued:	05/20/2013
Description 1:	Failure to sign and post a completed construction site notice for a secondary operator.
Description 2:	The COA provided a photograph of a CSN posted at the WCTOF thus resolving the alleged violation.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1088976
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY (Continued) **S113871149**

COMP HIST:

RN Number:	RN106664659
Name:	WCT WALLER BEACH SITE IMPROVEMENTS OUTLET FACILITY
Address:	74 TRINITY ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603327818
CN Name:	ZACHRY CONSTRUCTION CORPORATION
CN Rating:	1.36
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	423930
SIC Code:	1623
Related Number:	R11106664659,R11106664659

EF597 **DAVIS SPRING BRANCH** **TX CENTRAL REGISTRY** **S126561072**
Target **151 S 1ST ST STE 200** **N/A**
Property **AUSTIN, TX 78704**

Site 1 of 2 in cluster EF

Actual:
448 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121221
Customer Name:	EMILE JAMAIL PROPERTIES INC
Customer Legal Name:	Emile Jamail Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121221
Customer Name:	EMILE JAMAIL PROPERTIES INC
Customer Legal Name:	Emile Jamail Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01

DAVIS SPRING BRANCH (Continued) **S126561072**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121221
Customer Name:	EMILE JAMAIL PROPERTIES INC
Customer Legal Name:	Emile Jamail Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121221
Customer Name:	EMILE JAMAIL PROPERTIES INC
Customer Legal Name:	Emile Jamail Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN601121221
Customer Name:	EMILE JAMAIL PROPERTIES INC
Customer Legal Name:	Emile Jamail Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320

DAVIS SPRING BRANCH (Continued) **S126561072**

Primary NAICS Industry Type Description: Sewage Treatment Facilities
Physical Location Description: Not reported

Regulated Entity Number: RN102076544
Name: DAVIS SPRING BRANCH
Address: 151 S 1ST ST STE 200
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1243
Status: ACTIVE
Status Date: 2002-05-03
Customer Number: CN602932220
Customer Name: JAMAIL TIM AND JAMAIL SCOTT
Customer Legal Name: Jamail Tim and Jamail Scott
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 221320
Primary NAICS Industry Type Description: Sewage Treatment Facilities
Physical Location Description: Not reported

Regulated Entity Number: RN102076544
Name: DAVIS SPRING BRANCH
Address: 151 S 1ST ST STE 200
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1243
Status: ACTIVE
Status Date: 2002-05-03
Customer Number: CN602932220
Customer Name: JAMAIL TIM AND JAMAIL SCOTT
Customer Legal Name: Jamail Tim and Jamail Scott
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 221320
Primary NAICS Industry Type Description: Sewage Treatment Facilities
Physical Location Description: Not reported

Regulated Entity Number: RN102076544
Name: DAVIS SPRING BRANCH
Address: 151 S 1ST ST STE 200
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1243
Status: ACTIVE
Status Date: 2002-05-03
Customer Number: CN602932220
Customer Name: JAMAIL TIM AND JAMAIL SCOTT
Customer Legal Name: Jamail Tim and Jamail Scott
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 221320
Primary NAICS Industry Type Description: Sewage Treatment Facilities
Physical Location Description: Not reported

DAVIS SPRING BRANCH (Continued) **S126561072**

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN602932220
Customer Name:	JAMAIL TIM AND JAMAIL SCOTT
Customer Legal Name:	Jamail Tim and Jamail Scott
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Regulated Entity Number:	RN102076544
Name:	DAVIS SPRING BRANCH
Address:	151 S 1ST ST STE 200
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1243
Status:	ACTIVE
Status Date:	2002-05-03
Customer Number:	CN602932220
Customer Name:	JAMAIL TIM AND JAMAIL SCOTT
Customer Legal Name:	Jamail Tim and Jamail Scott
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	221320
Primary NAICS Industry Type Description:	Sewage Treatment Facilities
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

---

598 **CFJ BARGE REFINING** **RCRA NonGen / NLR** **1000103967**
Target **210 BARTON SPRINGS #319** **FINDS** **TXD980865067**
Property **AUSTIN, TX 78704** **ECHO**

Actual: 450 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	19830822
Handler Name:	Cfj Barge Refining
Handler Address:	BARTON SPRINGS #319
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD980865067
Contact Name:	KIM COX
Contact Address:	210 BARTON SPRINGS #319
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-884-6321
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported

CFJ BARGE REFINING (Continued) **1000103967**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	BARTON SPRINGS #319
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Barge Refng Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D001

CFJ BARGE REFINING (Continued) **1000103967**

Waste Description: Ignitable Waste

Waste Code: K048
Waste Description: Dissolved Air Flotation (Daf) Float From The Petroleum Refining Industry.

Waste Code: K049
Waste Description: Slop Oil Emulsion Solids From The Petroleum Refining Industry.

Waste Code: K050
Waste Description: Heat Exchanger Bundle Cleaning Sludge From The Petroleum Refining Industry.

Waste Code: K051
Waste Description: Api Separator Sludge From The Petroleum Refining Industry.

Waste Code: K052
Waste Description: Tank Bottoms (Leaded) From The Petroleum Refining Industry.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: BARGE REFNG INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19830822
Handler Name: CFJ BARGE REFINING	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CFJ BARGE REFINING (Continued) **1000103967**

FINDS:
Registry ID: 110005080250

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000103967
Registry ID:	110005080250
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005080250
Name:	CFJ BARGE REFINING
Address:	210 BARTON SPRINGS #319
City,State,Zip:	AUSTIN, TX 78704

EG599 **80 RAINEY STREET** **TX CENTRAL REGISTRY** **S128250027**
Target **78 80 82 AND 84 RAINEY ST** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 2 in cluster EG

Actual:
462 ft.

Focus Map:
11

CENTRAL REGISTRY:

Regulated Entity Number:	RN111300505
Name:	80 RAINEY STREET
Address:	78 80 82 AND 84 RAINEY ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	7/21/2021
Customer Number:	CN605914316
Customer Name:	80 RAINEY STREET OWNER LLC
Customer Legal Name:	80 Rainey Street Owner, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/14/2021
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	78 80 82 AND 84 RAINEY ST

EG600 Target Property | **VACAN SHED**
80 RAINEY STREET
AUSTIN, TX 78701 | **TX ASBESTOS** | **S129335881**
N/A

Site 2 of 2 in cluster EG

Actual: 461 ft.

Focus Map: 11

ASBESTOS:

Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/08/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/28/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/28/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported

VACAN SHED (Continued) **S129335881**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/09/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/28/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/28/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N

VACAN SHED (Continued) **S129335881**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/01/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

VACAN SHED (Continued) **S129335881**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/22/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/02/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

VACAN SHED (Continued) **S129335881**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/22/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

VACAN SHED (Continued) **S129335881**

Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/25/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/11/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

VACAN SHED (Continued) **S129335881**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACAN SHED
Address:	80 RAINEY STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/26/2016
Notification Number:	2016005745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	07/11/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

VACAN SHED (Continued) **S129335881**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EH601 **HOOTER'S RESTAURANT** **TX ASBESTOS** **S125392020**
Target **425 WEST RIVERSIDE DRIVE** **N/A**
Property **AUSTIN, TX 78704**

Site 1 of 9 in cluster EH

Actual:
455 ft.

Focus Map:
11

ASBESTOS:

Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/11/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/08/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	02/22/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/28/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/01/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/06/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/08/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/15/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/15/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

HOOTER'S RESTAURANT (Continued) **S125392020**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/09/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/22/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/26/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/11/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/25/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/25/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	02/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer

HOOTER'S RESTAURANT (Continued) **S125392020**

Violation:	Not reported
Complaint Date:	03/18/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/28/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material
Start Date:	03/07/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

HOOTER'S RESTAURANT (Continued) **S125392020**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	03/11/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/28/2019
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	No Suspect Material

HOOTER'S RESTAURANT (Continued) **S125392020**

Start Date:	02/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	HOOTER'S RESTAURANT
Address:	425 WEST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Judy Pfeffer
Violation:	Not reported
Complaint Date:	02/22/2019
Notification Number:	2019000925
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D

HOOTER'S RESTAURANT (Continued) **S125392020**

Certification Statement Date:	01/28/2019
Certification Statement Phone:	972-434-3283
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EH602 **FORMER GAS STATION PROPERTY** **TX TANKS** **S126900612**
Target **425 W RIVERSIDE DR** **TX CENTRAL REGISTRY** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 9 in cluster EH

Actual:
455 ft.

Focus Map:
11

TANKS:

Facility ID:	133376
Name:	FORMER GAS STATION PROPERTY
Address:	425 W RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787041228
Total UST:	Not reported
Additional ID:	278449732016081
AI Number:	88261
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

FORMER GAS STATION PROPERTY (Continued) **S126900612**

Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN109140871
Name:	FORMER GAS STATION PROPERTY
Address:	425 W RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1228
Status:	ACTIVE
Status Date:	3/21/2016
Customer Number:	CN605114644
Customer Name:	MOLLY BELLE PROPERTIES LP
Customer Legal Name:	MOLLY BELLE PROPERTIES LP
Customer Ownership Type:	GENERAL PARTNERSHIP
Affiliation Begin Date:	3/17/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

EI603 **EDS AUTOMOTIVE** **EDR Hist Auto** **1013768912**
Target **208 RIVERSIDE DR W** **N/A**
Property **SOUTH AUSTIN, TX**

Site 1 of 4 in cluster EI

Actual: EDR Hist Auto
454 ft.

Focus Map:
14

Year:	Name:	Type:
1958	EDS AUTOMOTIVE	AUTOMOBILE REPAIRING

EI604 Target Property — **MIDAS MUFFLER**, **207 RIVERSIDE DR W**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013769910** / **N/A**

Site 2 of 4 in cluster EI

Actual: 454 ft. — **Focus Map: 14**

EDR Hist Auto

Year:	Name:	Type:
1958	MIDAS MUFFLER	AUTOMOBILE REPAIRING

EI605 Target Property — **R&S GARAGE REPRS**, **205 RIVERSIDE DR W**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013755371** / **N/A**

Site 3 of 4 in cluster EI

Actual: 454 ft. — **Focus Map: 14**

EDR Hist Auto

Year:	Name:	Type:
1953	R & S GARAGE REPRS	AUTOMOBILE REPAIRING
1958	R&S GARAGE REPRS	AUTOMOBILE REPAIRING

EI606 Target Property — **HAWKINS GARAGE AUTO REPR**, **205 RIVERSIDE DR W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013757414** / **N/A**

Site 4 of 4 in cluster EI

Actual: 454 ft. — **Focus Map: 14**

EDR Hist Auto

Year:	Name:	Type:
1965	HAWKINS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

EJ607 Target Property — **C.A. ARMACOST**, **118 W RIVERSIDE DR**, **AUSTIN, TX** — **TX HIST UST** — **S111678582** / **N/A**

Site 1 of 19 in cluster EJ

Actual: 450 ft. — **Focus Map: 14**

HIST UST AUSTIN:

Name:	C.A. ARMACOST
Address:	118 W RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	H0342
HID UST:	342
Inspection:	04/24/2009
Due:	04/24/2012

EJ608 Target Property — **REEDYS AUTO WAY**, **103 RIVERSIDE DR W**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013761487**, **N/A**

Site 2 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1953	REEDYS AUTO WAY	AUTOMOBILE REPAIRING

EJ609 Target Property — **EDDIE SLACKS RIVERSIDE SHELL**, **400 CONGRESS AVE S**, **TRAVIS (County), TX 78704** — **EDR Hist Auto** — **1013760834**, **N/A**

Site 3 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1940	LEIGH SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1965	SOUTH CONGRESS PHILLIPS	GASOLINE STATIONS
1970	SOUTH CONGRESS SHELL SERVICE ST	GASOLINE STATIONS
1975	EDDIE SLACKS RIVERSIDE SHELL	GASOLINE STATIONS
1980	S 0 S AUTO REPR	AUTOMOBILE REPAIRING
1980	SLACKS EDDIE RIVERSIDE SHELL	GASOLINE STATIONS
1984	SLACKS EDDIE RIVERSIDE SHELL	GASOLINE STATIONS
1990	SLACKS EDDIE RIVERSIDE SHELL GA	GASOLINE STATIONS

EJ610 Target Property — **CHRISTIES CITIES**, **400 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013753520**, **N/A**

Site 4 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1935	WHITE SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	LEIGH SERVICE STATION NO 1 FILL	GASOLINE AND OIL SERVICE STATIONS
1953	WILBURNS HUMBLE	GASOLINE STATIONS
1958	CHRISTIES CITIES	GASOLINE STATIONS

EJ611 Target Property — **CHESNUTT DON N**, **401 S CONGRESS**, **AUSTIN, TX 78704** — **EDR Hist Cleaner** — **1019953290**, **N/A**

Site 5 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1969	CHESNUTT DON N	Drycleaning Plants, Except Rugs
1970	CHESNUTT DON N	Drycleaning Plants, Except Rugs
1971	CHESNUTT DON N	Drycleaning Plants, Except Rugs
1972	CHESNUTT DON N	Drycleaning Plants, Except Rugs
1973	CHESNUTT DON N	Drycleaning Plants, Except Rugs

EJ612 Target Property **TEXAS CLEANERS**
401 CONGRESS AVE S
SOUTH AUSTIN, TX

EDR Hist Cleaner **1013782312**
N/A

Site 6 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1953	TEXAS CLEANERS	CLEANERS AND DYERS
1958	TEX CLNS DCLO CLNS	CLEANERS AND DYERS

EJ613 Target Property **TEXAS CLEANERS**
401 CONGRESS AVE S
TRAVIS (County), TX 78704

EDR Hist Cleaner **1013781040**
N/A

Site 7 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1965	TEXAS CLEANERS H	CLEANERS AND DYERS
1970	TEXAS CLEANERS	CLEANERS AND DYERS

EJ614 Target Property **BOHLS SERVICE STATION**
401 CONGRESS AVE S
AUSTIN, TX

EDR Hist Auto **1013768541**
N/A

Site 8 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1940	BOHLS SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
2008	SOUTH COAST AUTO	General Automotive Repair Shops
2009	SOUTH COAST AUTO	General Automotive Repair Shops
2010	SOUTH COAST AUTO	General Automotive Repair Shops
2011	SOUTH COAST AUTO	General Automotive Repair Shops
2012	SOUTH COAST AUTO	General Automotive Repair Shops
2012	AUTO-TROL TECH EUROPE LTD	General Automotive Repair Shops
2013	SOUTH COAST AUTO	General Automotive Repair Shops
2014	SOUTH COAST AUTO	General Automotive Repair Shops
2014	GARAGE DOCTORS LLC	General Automotive Repair Shops

EJ615 Target Property **TEXAS PACIFIC COAL**
401 CONGRESS AVE S
SOUTH AUSTIN, TX

EDR Hist Auto **1013776971**
N/A

Site 9 of 19 in cluster EJ

Actual: 450 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1935	TEXAS PACIFIC COAL	GASOLINE AND OIL SERVICE STATIONS

616 Target Property | **COVERT AUTOMOBILE CO.**
507 S 1ST ST
AUSTIN, TX | **TX HIST UST** | **S111678616**
N/A

Actual: 450 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	COVERT AUTOMOBILE CO.
Address:	507 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0707
HID UST:	707
Inspection:	Not reported
Due:	06/01/2012

EK617 Target Property | **STOP N GO 2066**
160 E RIVERSIDE DR
AUSTIN, TX 78704 | **TX UST**
TX HIST UST
TX Financial Assurance | **U003040314**
N/A

Site 1 of 7 in cluster EK

Actual: 450 ft.
Focus Map: 14

UST:

Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787041202
AI Number:	39559
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	INACTIVE
Additional ID:	69753832002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	CHRIS TRINKLE,O&E
Contact Organization Name:	STOP N GO 2066
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2105924666
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/25/1986
Signature Name/Title On Earliest Reg Form:	WILLIAM CALVERT,GAS MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	765580132003199
Additional ID:	69753832002149
Ai Number:	39559
Operator CN:	CN602277386

STOP N GO 2066 (Continued) **U003040314**

Operator Name:	CST SERVICES LLC
Operator Effective Begin Date:	10/10/2000
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	KENT HAMEL/COORD
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78269-6000
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	3454670
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	SAN ANTONIO
Contact Mailing State:	TX
Contact Mailing Zip:	78269
Contact Mailing Zip5:	6000
Contact Phone Number/Ext:	1 210 3454670/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	69753832002149
AI Number:	39559
Owner Effective Begin Date:	10/10/2000
State Tax ID:	17425053794
Contact Role:	OWNCON
Contact Name/Title:	KENT HAMEL/COORDINATOR
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY

Self Certification:

Self Cert ID:	61079
Cert ID:	63087
AI Number:	39559
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

STOP N GO 2066 (Continued) **U003040314**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61079
Cert ID:	63086
AI Number:	39559
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	10/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104590
Facility ID:	61079
Ai Number:	39559
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/21/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

STOP N GO 2066 (Continued) **U003040314**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10088
UST Comprt ID:	54693
UST ID:	104590
AI Number:	39559
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

STOP N GO 2066 (Continued) **U003040314**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	10/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104591
Facility ID:	61079
Ai Number:	39559
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/21/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

STOP N GO 2066 (Continued) **U003040314**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10088
UST Comprt ID:	54694
UST ID:	104591
AI Number:	39559
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

STOP N GO 2066 (Continued) **U003040314**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	7039
Facility ID:	61079
AI Number:	39559
Application Received Date:	03/06/2003
Scheduled Construction Date:	03/18/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30306004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	7587
UST ID:	Not reported
NOC ID:	7039
AI Number:	39559
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported

STOP N GO 2066 (Continued) **U003040314**

Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61079
Additional ID:	69753832002149
Princ ID:	765580132003199
AI Number:	39559
Facility Name:	STOP N GO 2066
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	DIAMOND SHAMROCK #2066
Address:	160 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	1189
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61079
Finass ID:	43449
AI:	39559
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

STOP N GO 2066 (Continued) **U003040314**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

EK618 **DIAMOND SHAMROCK 2066** **TX LPST** **S106031876**
Target **160 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 7 in cluster EK

Actual:
450 ft.

Focus Map:
14

LPST:

Name:	DIAMOND SHAMROCK 2066
Address:	160 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0039559
LPST Id:	115780
Facility Location:	160 E RIVERSIDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	12/31/3000
Entered Date:	08/19/2003
Reported Date:	12/31/3000
Closure Date:	07/13/2005
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT 500F
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater or storm water runoff is affected and discharges within 500 feet of the known extent of contamination to a surface water body used for human drinking water, contact recreation, habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	CJH
Responsible Party Name:	Not reported
Responsible Party Contact:	C SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269
Responsible Party Telephone:	210/592-4663
Reported Date:	12/31/3000
Case Start Date:	07/13/2005
Reference Number:	RN102370186
Project Manager:	CHAY

EK619 Target Property | **DIAMOND SHAMROCK 2066**
160 E RIVERSIDE
AUSTIN, TX | **TX RDR** | **S127532145**
N/A

Site 3 of 7 in cluster EK

Actual: 450 ft.
Focus Map: 14

RDR:

RDR ID:	12472
Facility ID:	39559
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 2066
Address:	160 E RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/16/2003
Due Date:	8/15/2003
Tank Owner:	NATIONAL CONVENIENCE STOR
Contact Person:	C SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	8/19/2003
Project Manager:	Stacey Jagge
Team:	#N/A
New LPST Number:	115780
Pre-Existing LPST Number:	Not reported
Comments:	LPST # 115780 SRJ
Review Coordinator:	SRJ
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

EK620 Target Property | **STOP N GO 2066**
160 E RIVERSIDE DR
AUSTIN, TX 78704 | **TX CENTRAL REGISTRY** | **S126575996**
N/A

Site 4 of 7 in cluster EK

Actual: 450 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN600135370
Customer Name:	DIAMOND SHAMROCK
Customer Legal Name:	Diamond Shamrock
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

STOP N GO 2066 (Continued) **S126575996**

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601536014
Customer Name:	NATIONAL CONVENIENCE STORES INCORPORATED
Customer Legal Name:	National Convenience Stores Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/14/1987
Affiliation End Date:	12/12/1995
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/13/1995
Affiliation End Date:	6/25/1997
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/10/2000
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR

STOP N GO 2066 (Continued) **S126575996**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601091176
Customer Name:	STOP N GO MARKETS OF TEXAS INC
Customer Legal Name:	Stop 'N Go Markets of Texas, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/26/1997
Affiliation End Date:	10/9/2000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN604401554
Customer Name:	NATIONAL CONVENIENCE STORES
Customer Legal Name:	National Convenience Stores
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN600135370
Customer Name:	DIAMOND SHAMROCK
Customer Legal Name:	Diamond Shamrock
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE

STOP N GO 2066 (Continued) **S126575996**

Status Date:	5/29/2002
Customer Number:	CN601536014
Customer Name:	NATIONAL CONVENIENCE STORES INCORPORATED
Customer Legal Name:	National Convenience Stores Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/14/1987
Affiliation End Date:	12/12/1995
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/13/1995
Affiliation End Date:	6/25/1997
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/10/2000
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102370186
Name:	STOP N GO 2066
Address:	160 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601091176
Customer Name:	STOP N GO MARKETS OF TEXAS INC

STOP N GO 2066 (Continued) **S126575996**

Customer Legal Name:	Stop 'N Go Markets of Texas, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/26/1997
Affiliation End Date:	10/9/2000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

---

621 Target Property **TURNER CREST VILLAGE WWTP** **FINDS** **1010345986**
3.77 MI NE OF INTERX OF HWY 80 AND HWY 142 **ECHO** **N/A**
CALDWELL COUNTY, TX 78704

Actual: 458 ft.

Focus Map: 14

FINDS:
Registry ID: 110030771010

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010345986
Registry ID:	110030771010
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110030771010
Name:	TURNER CREST VILLAGE WWTP
Address:	3.77 MI NE OF INTERX OF HWY 80 AND HWY 142
City,State,Zip:	CALDWELL COUNTY, TX 78704

EK622 Target Property **AUSTIN AMERICAN STATESMAN** **RCRA-VSQG** **1000412211**
305 CONGRESS AVE **TX UST** **TXD982291569**
AUSTIN, TX 78701 **TX HIST UST**
FINDS
Site 5 of 7 in cluster EK **ECHO**

Actual: 449 ft.

Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20130326
Handler Name:	Austin American Statesman
Handler Address:	305 CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78701-4023
EPA ID:	TXD982291569
Contact Name:	RUDY ESTRADA
Contact Address:	PO BOX 670
Contact City,State,Zip:	AUSTIN, TX 78767-0670

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Contact Telephone:	512-445-3705
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 670
Mailing City,State,Zip:	AUSTIN, TX 78767-0670
Owner Name:	Austin American Statesman
Owner Type:	Private
Operator Name:	Austin American Statesman
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D008
Waste Description: Lead

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090224
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Date Became Current: 20100120
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20041021
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20080304
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20060320
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090224
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090825
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767-0670
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090414
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20041021
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090414
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767-0670
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COX ENTERPRISES INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1400 LAKE HEARN DR NE
Owner/Operator City,State,Zip: ATLANTA, GA 30319-0000
Owner/Operator Telephone: 404-843-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20050824
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20050824
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20060320
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20090825
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20080304
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN AMERICAN STATESMAN
Legal Status: Private
Date Became Current: 20100120
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 670
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-445-3705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19970613
Handler Name: AUSTIN AMERICAN STATESMAN

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011108
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20041021
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050824
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060320
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080304
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090224
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090414
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090825
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Receive Date: 20100120
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130326
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 51111
NAICS Description: NEWSPAPER PUBLISHERS

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20090123
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20031125
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

UST:

Name:	AUSTIN AMERICAN STATESMAN
Address:	166 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787041202
AI Number:	19681
Facility Type:	OTHER
Facility Begin Date:	09/08/1986
Facility Status:	INACTIVE
Additional ID:	480521542002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	F P MACK,MAINT MGR
Contact Organization Name:	AUSTIN AMERICAN STATESMAN
Contact Mailing Address1:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124453500
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/25/1986
Signature Name/Title On Earliest Reg Form:	F P MACK,MAINT MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778112
Owner Last Name:	DBA-COX TEXAS PUBLICATIONS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	471521532002053
Additional ID:	480521542002053
AI Number:	19681
Owner Effective Begin Date:	09/08/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50634
Facility ID:	56730
Ai Number:	19681
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	62612
UST ID:	50634
AI Number:	19681
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50635
Facility ID:	56730
Ai Number:	19681
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	62613
UST ID:	50635
AI Number:	19681
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50638
Facility ID:	56730
Ai Number:	19681
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	560
UST Comprt ID:	62616
UST ID:	50638
AI Number:	19681
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50637
Facility ID:	56730
Ai Number:	19681
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	62615
UST ID:	50637
AI Number:	19681
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50636
Facility ID:	56730
Ai Number:	19681
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	12000
UST Comprt ID:	62614
UST ID:	50636
AI Number:	19681
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

Facility Billing Contacts:

Contact Organization Name:	DBA-COX TEXAS PUBLICATIONS INC
Contact Mailing Address (Delivery):	166 E RIVERSIDE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 1202
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	56730
Additional ID:	480521542002053
Princ ID:	471521532002053
AI Number:	19681
Facility Name:	AUSTIN AMERICAN STATESMAN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	F P MACK/

HIST UST AUSTIN:

Name:	AUSTIN AMERICAN STATESMAN
Address:	166 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0336
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FINDS:

Registry ID: 110005104083

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

HAZARDOUS AIR POLLUTANT MAJOR
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412211
Registry ID:	110005104083

AUSTIN AMERICAN STATESMAN (Continued) **1000412211**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005104083
Name: AUSTIN AMERICAN STATESMAN
Address: 305 CONGRESS AVE
City,State,Zip: AUSTIN, TX 78701

EK623 Target Property | **AUSTIN AMERICAN STATESMAN**
166 E RIVERSIDE DR
AUSTIN, TX 78704 | **TX CENTRAL REGISTRY** | **S126523468**
N/A

Site 6 of 7 in cluster EK

Actual: 449 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number: RN101489169
Name: AUSTIN AMERICAN STATESMAN
Address: 166 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1202
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN600778112
Customer Name: DBA-COX TEXAS PUBLICATIONS INC
Customer Legal Name: Dba-Cox Texas Publications, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/8/1986
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN101489169
Name: AUSTIN AMERICAN STATESMAN
Address: 166 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1202
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN601073166
Customer Name: COX TEXAS NEWSPAPERS LP
Customer Legal Name: Cox Texas Newspapers, L.P.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN101489169
Name: AUSTIN AMERICAN STATESMAN
Address: 166 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1202
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN600778112
Customer Name: DBA-COX TEXAS PUBLICATIONS INC
Customer Legal Name: Dba-Cox Texas Publications, Inc.

AUSTIN AMERICAN STATESMAN (Continued) **S126523468**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101489169
Name:	AUSTIN AMERICAN STATESMAN
Address:	166 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1202
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN601073166
Customer Name:	COX TEXAS NEWSPAPERS LP
Customer Legal Name:	Cox Texas Newspapers, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

EL624 **GILBERTS AUTO ELEC** **EDR Hist Auto** **1013754137**
Target Property **48 EAST AVE** **N/A**
AUSTIN, TX

Site 1 of 3 in cluster EL

Actual: 456 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1962	GILBERTS AUTO ELEC	AUTOMOBILE REPAIRING

EL625 **OFFICE BUILDING** **TX ASBESTOS** **S123213135**
Target Property **48 EAST AVENUE** **N/A**
AUSTIN, TX 78701

Site 2 of 3 in cluster EL

Actual: 456 ft.
Focus Map: 14

ASBESTOS:

Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins
Violation:	Not reported
Complaint Date:	12/17/2018
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/27/2019
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins
Violation:	Not reported
Complaint Date:	03/01/2019
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/27/2019
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/31/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins
Violation:	Not reported
Complaint Date:	12/17/2018
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/14/2018
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N

OFFICE BUILDING (Continued) **S123213135**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins
Violation:	Not reported
Complaint Date:	02/20/2019
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/14/2018
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins
Violation:	Not reported
Complaint Date:	12/15/2018
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/05/2018
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	09/09/2019
Reason for Inspection:	Matthew Collins

OFFICE BUILDING (Continued) **S123213135**

Violation:	Not reported
Complaint Date:	01/18/2019
Notification Number:	2018008169
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/05/2018
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	300
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	OFFICE BUILDING
Address:	48 EAST AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/11/27
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

OFFICE BUILDING (Continued) **S123213135**

Start Date:	11/27/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018008169
File Number:	35693
License Status Description:	Current
Expiration Date:	03/01/2019
Original Date:	11/05/2018
Rank Effective Date:	11/05/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	13111
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

EM626 **CAR WELL INC AUTO REPR** **EDR Hist Auto** **1013768612**
Target Property **205 RIVERSIDE DR E** **N/A**
TRAVIS (County), TX 78704

Site 1 of 3 in cluster EM

Actual: 448 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1975	CAR WELL INC AUTO REPR	AUTOMOBILE REPAIRING

EM627 **ELLIS & SALAZAR GARAGE & BODY SHOP** **EDR Hist Auto** **1013757373**
Target Property **211 RIVERSIDE DR E** **N/A**
AUSTIN, TX 78704

Site 2 of 3 in cluster EM

Actual: 447 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1970	ELLIS & SALAZAR GARAGE AUTO REP	AUTOMOBILE REPAIRING
1975	ELLIS & SALAZAR GARAGE AUTO REP	AUTOMOBILE REPAIRING
1980	ELLIS & SALAZAR GARAGE AUTO REP	AUTOMOBILE REPAIRING
1984	ELLIS & SALAZAR GARAGE & BODY S	AUTOMOBILE REPAIRING

EN628 Target Property | **TRIPLE S PETROLEUM COMPANY**
900 EAST AVE
AUSTIN, TX 78701 | **EDR Hist Auto** | **1021178780**
N/A

Site 1 of 4 in cluster EN

Actual: 453 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1995	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1996	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1997	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1998	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1999	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2000	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2001	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2002	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2003	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2004	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2005	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2006	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2007	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2008	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2009	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2010	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2011	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2012	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2013	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations

EN629 Target Property | **SIGNATURE 9**
900 E AVE
AUSTIN, TX | **TX RDR** | **S127530907**
N/A

Site 2 of 4 in cluster EN

Actual: 453 ft.

Focus Map: 14

RDR:

RDR ID:	28376
Facility ID:	34918
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 9
Address:	900 E AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/12/2020
Due Date:	5/11/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	SUSPECTED RELEASE
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	4/17/2020
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported

SIGNATURE 9 (Continued) **S127530907**

Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

EN630 Target Property | **SIGNATURE 9**
900 EAST AVE
AUSTIN, TX 78701 | **TX CENTRAL REGISTRY** | **S126693440**
N/A

Site 3 of 4 in cluster EN

Actual: 453 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number: RN104162466
Name: SIGNATURE 9
Address: 900 EAST AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-2601
Status: ACTIVE
Status Date: 2/23/2004
Customer Number: CN601163454
Customer Name: TRIPLE S PETROLEUM COMPANY
Customer Legal Name: Triple S Petroleum Company
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/1988
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN104162466
Name: SIGNATURE 9
Address: 900 EAST AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-2601
Status: ACTIVE
Status Date: 2/23/2004
Customer Number: CN600918452
Customer Name: TEXAS ENTERPRISES INC
Customer Legal Name: Texas Enterprises, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 5/14/2012
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN104162466
Name: SIGNATURE 9
Address: 900 EAST AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-2601
Status: ACTIVE
Status Date: 2/23/2004
Customer Number: CN601163454
Customer Name: TRIPLE S PETROLEUM COMPANY
Customer Legal Name: Triple S Petroleum Company
Customer Ownership Type: CORPORATION

SIGNATURE 9 (Continued) **S126693440**

Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN104162466
Name:	SIGNATURE 9
Address:	900 EAST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2601
Status:	ACTIVE
Status Date:	2/23/2004
Customer Number:	CN600918452
Customer Name:	TEXAS ENTERPRISES INC
Customer Legal Name:	Texas Enterprises, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/14/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

EN631 **SHOPPERS MART 9** **FINDS** **1011378952**
Target **900 EAST AVE** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 4 in cluster EN

Actual:
453 ft.

Focus Map:
14

FINDS:
Registry ID: 110035060359

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EO632 Target Property | **JS MARKET-PLANT - 3749 HWY 183**
611 S CONGRESS AVE STE 450
AUSTIN, TX 78704 | **FINDS** | **1026963769**
N/A

Site 1 of 2 in cluster EO

Actual: 473 ft.
Focus Map: 14

FINDS:
Registry ID: 110049609688

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
WATER TREATMENT PLANT
TRANSIENT NON-COMMUNITY WATER SYSTEM

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

633 Target Property | **802 SOUTH 1ST STREET**
AUSTIN, TX | **ERNS** | **2018216746**
N/A

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

Actual: 503 ft.
Focus Map: 14

EP634 Target Property | **CAPITAL CITY TRADE & TECH SCHOOL**
205 E RIVERSIDE DR
AUSTIN, TX 78704 | **TX Ind. Haz Waste** | **S101718223**
N/A

Site 1 of 5 in cluster EP

Actual: 445 ft.
Focus Map: 14

Ind. Haz Waste:

Name:	CAPITAL CITY TRADE & TECH SCHOOL
Address:	205 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	69372
Registration Initial Notification Date:	03/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD982560716
Primary NAICS Code:	Not reported
Status Change Date:	19860307
Land Type:	PRIVATE
Description of Facility Site Location:	205 E Riverside Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **S101718223**

Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CAPITAL CITY TRADE & TECH SCHOOL
Contact Name:	BRIAN ALLEN GOAD
Contact Telephone Number:	512-4443257
Mailing Address:	205 E RIVERSIDE DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787041203
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24250
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040423
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CAPITAL CITY TRADE & TECH SCHOOL
Operator Address:	205 E RIVERSIDE DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4443257
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITAL CITY TRADE & TECH SCHOOL
Owner Mailing Address:	205 E RIVERSIDE DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4443257
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **S101718223**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	205 E RIVERSIDE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443257
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	205 E RIVERSIDE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443257
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BRIAN GOAD
Contact Title:	LEAD INSTRUCTOR
Contact Role:	PRICONT
Contact Address:	205 E RIVERSIDE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443257
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	205 E RIVERSIDE DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306159
Principal Name:	CAPITAL CITY TRADE & TECH SCHOOL
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	205 E RIVERSIDE DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306159
Principal Name:	CAPITAL CITY TRADE & TECH SCHOOL
Attention Name:	Not reported
Attention Suffix:	HWG

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **S101718223**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	205 E RIVERSIDE DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306159
Principal Name:	CAPITAL CITY TRADE & TECH SCHOOL
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	205 E RIVERSIDE DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306159
Principal Name:	CAPITAL CITY TRADE & TECH SCHOOL
Attention Name:	Not reported
Attention Suffix:	NWG

EP635 **205 EAST RIVERSIDE, AUSTIN** **TX SPILLS** **S106994481**
Target Property **205 EAST RIVERSIDE, AUSTIN** **N/A**
AUSTIN, TX

Site 2 of 5 in cluster EP

Actual: 445 ft.

Focus Map: 14

SPILLS:

Name:	205 EAST RIVERSIDE, AUSTIN
Address:	205 EAST RIVERSIDE, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	06/13/1990
Seq Num:	Not reported
Responsible Party Name:	UNKNOWN
Responsible Party Address:	UNKNOWN
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	SEWAGE
Material Code:	8000
Media Affected:	YES
Permit Number:	NONE
District:	14
Origin:	001
Cause:	003
Basin Code:	1402
Notify Date:	Not reported
Adequate Clean:	003
Classification:	006
Basin Name:	COLORADO
Water Affected:	UNKNOWN CREEK
Amnt Spilled:	UNKNOWN
Amnt in Water:	UNKNOWN

205 EAST RIVERSIDE, AUSTIN (Continued) **S106994481**

Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	X
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	D. FAWN
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

EP636 **CAPITAL CITY TRADE & TECH SCHOOL** **RCRA NonGen / NLR** **1000264758**
Target **205 E RIVERSIDE DR** **FINDS** **TXD982560716**
Property **AUSTIN, TX 78704** **ECHO**

Site 3 of 5 in cluster EP

Actual:
445 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Capital City Trade & Tech School
Handler Address:	E RIVERSIDE DR
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD982560716
Contact Name:	BRIAN ALLEN GOAD
Contact Address:	E RIVERSIDE DR
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-444-3257
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **1000264758**

Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E RIVERSIDE DR
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Capital City Trade & Tech School
Owner Type:	Private
Operator Name:	Capital City Trade & Tech School
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **1000264758**

Waste Code: D018
Waste Description: Benzene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CAPITAL CITY TRADE & TECH SCHOOL
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 205 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-444-3257
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERT C HOLT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CAPITAL CITY TRADE & TECH SCHOOL
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 205 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-444-3257
Owner/Operator Telephone Ext: Not reported

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **1000264758**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960408
Handler Name: CAPITOL CITY TRADE AND TECHNICAL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: CAPITAL CITY TRADE & TECH SCHOOL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005110030

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CAPITAL CITY TRADE & TECH SCHOOL (Continued) **1000264758**

ECHO:

Envid:	1000264758
Registry ID:	110005110030
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005110030
Name:	CAPITAL CITY TRADE & TECH SCHOOL
Address:	205 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704

EP637 **UNKNOWN** **TX SPILLS 90** **S112311366**
Target Property **205 EAST RIVERSIDE** **N/A**
AUSTIN, TX

Site 4 of 5 in cluster EP

Actual: 445 ft.
Focus Map: 14

Spills:

Status:	Not reported
Contact Name:	UNKNOWN
Contact Phone:	Not reported
Site ID:	TXSP0613199014
Secondary ID:	Not reported
Cross Street:	205 EAST RIVERSIDE, AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

EP638 **CAPITOL CITY TRADE & TECH SCHOOL** **TX CENTRAL REGISTRY** **S123847475**
Target Property **205 E RIVERSIDE DR** **N/A**
AUSTIN, TX 78704

Site 5 of 5 in cluster EP

Actual: 445 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN100693167
Name:	CAPITOL CITY TRADE & TECH SCHOOL
Address:	205 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1203
Status:	ACTIVE
Status Date:	###########
Customer Number:	CN600399547
Customer Name:	CAPITAL CITY TRADE & TECH SCHOOL
Customer Legal Name:	Capital City Trade & Tech School
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	205 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN100693167
Name:	CAPITOL CITY TRADE & TECH SCHOOL
Address:	205 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1203

CAPITOL CITY TRADE & TECH SCHOOL (Continued) **S123847475**

Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600399547
Customer Name:	CAPITAL CITY TRADE & TECH SCHOOL
Customer Legal Name:	Capital City Trade & Tech School
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	205 E Riverside Dr, Austin, TX

EQ639 **VACANT BUILDING** **TX ASBESTOS** **S119160036**
Target **901 S. CONGRESS AVE.** **N/A**
Property **AUSTIN, TX 78701**

Site 1 of 5 in cluster EQ

Actual:
486 ft.

Focus Map:
14

ASBESTOS:

Name:	VACANT BUILDING
Address:	901 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/30/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013002968
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	05/30/2013
Date Routed by Supervisor:	06/05/2013
Date Routed to PSQA:	06/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

VACANT BUILDING (Continued) **S119160036**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EQ640 **MUSE APARTMENTS** **TX ASBESTOS** **S129160260**
Target **901 S CONGRESS** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 5 in cluster EQ

Actual:
486 ft.

Focus Map:
14

ASBESTOS:

Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	01/05/2023
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

MUSE APARTMENTS (Continued) **S129160260**

Inspector Name:	Not reported
Date Report Received:	11/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/18/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Complaint Date:	10/21/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/09/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	10/28/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/15/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/26/2022

MUSE APARTMENTS (Continued) **S129160260**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	11/11/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/20/2022

MUSE APARTMENTS (Continued) **S129160260**

Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	11/18/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/03/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/03/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	12/18/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/13/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/13/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	12/23/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/10/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	01/05/2023
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/15/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0

MUSE APARTMENTS (Continued) **S129160260**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	901 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/11/30
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

MUSE APARTMENTS (Continued) **S129160260**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	11/30/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022005683
File Number:	74318
License Status Description:	Current
Expiration Date:	01/05/2023
Original Date:	08/29/2022
Rank Effective Date:	08/29/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	36903
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

ER641 **MUSIC LANE MIXED USE DEVELOPMENT** **FINDS** **1023666312**
Target **1100 SOUTH CONGRESS AVE** **ECHO** **N/A**
Property **AUSTIN, TX 78704**

Site 1 of 8 in cluster ER

Actual:
500 ft.

Focus Map:
14

FINDS:
Registry ID: 110070080495

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain

MUSIC LANE MIXED USE DEVELOPMENT (Continued) **1023666312**

limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1023666312
Registry ID:	110070080495
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070080495
Name:	MUSIC LANE MIXED USE DEVELOPMENT
Address:	1100 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

ER642 **MUSE APARTMENTS** **TX ASBESTOS** **S122365891**
Target **1007 S. CONGRESS AVE.** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 8 in cluster ER

Actual:
497 ft.

Focus Map:
14

ASBESTOS:

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	09/20/2022
Reason for Inspection:	Jacob Grace
Violation:	Not reported
Complaint Date:	12/01/2022
Notification Number:	2022005383
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D

MUSE APARTMENTS (Continued) **S122365891**

Certification Statement Date:	09/20/2022
Certification Statement Phone:	785-640-2476
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/20/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	09/20/2022
Reason for Inspection:	Jacob Grace
Violation:	Not reported
Complaint Date:	12/01/2022
Notification Number:	2022005383
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/15/2022
Certification Statement Phone:	785-640-2476
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/20/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/30/2022
Reason for Inspection:	Grayson Knavel
Violation:	Not reported
Complaint Date:	10/12/2022
Notification Number:	2022005683
ASB Priority:	Not reported
PIF State:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/29/2022
Certification Statement Phone:	469-805-8127
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/12/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY VIEW APARTMENT DEMOLITION
Address:	1007 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Sandra Gamez
Violation:	Not reported
Complaint Date:	05/28/2018
Notification Number:	2018001950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/10/2018
Certification Statement Phone:	972-225-1200
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY VIEW APARTMENT DEMOLITION
Address:	1007 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Sandra Gamez
Violation:	Not reported
Complaint Date:	05/21/2018
Notification Number:	2018001950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/20/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/20/2018
Certification Statement Phone:	972-225-1200
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

MUSE APARTMENTS (Continued) **S122365891**

ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY VIEW APARTMENT DEMOLITION
Address:	1007 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Sandra Gamez
Violation:	Not reported
Complaint Date:	05/21/2018
Notification Number:	2018001950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/30/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/30/2018
Certification Statement Phone:	972-225-1200
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/09/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY VIEW APARTMENT DEMOLITION
Address:	1007 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Sandra Gamez
Violation:	Not reported
Complaint Date:	05/21/2018
Notification Number:	2018001950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/06/2018
Certification Statement Phone:	972-225-1200
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/11/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY VIEW APARTMENT DEMOLITION
Address:	1007 SOUTH CONGRESS AVENUE

MUSE APARTMENTS (Continued) **S122365891**

City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Sandra Gamez
Violation:	Not reported
Complaint Date:	05/21/2018
Notification Number:	2018001950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/07/2018
Certification Statement Phone:	972-225-1200
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	19
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/12/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

MUSE APARTMENTS (Continued) **S122365891**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/13/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	09/17/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/13/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1

MUSE APARTMENTS (Continued) **S122365891**

Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/13/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/03/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	10/01/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Report Received:	07/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/29/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/17/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	10/15/2021

MUSE APARTMENTS (Continued) **S122365891**

Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/17/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/17/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/31/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	11/02/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/30/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/30/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/21/2021
Client Code:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	12/10/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/20/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/20/2021
Certification Statement Phone:	469-879-9463

MUSE APARTMENTS (Continued) **S122365891**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/12/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	12/24/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/11/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/27/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	01/14/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/25/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/25/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	01/28/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/15/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/30/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	02/11/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/29/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

MUSE APARTMENTS (Continued) **S122365891**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/14/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	03/04/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/08/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/08/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/28/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	03/18/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/20/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/20/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel

MUSE APARTMENTS (Continued) **S122365891**

Violation:	Not reported
Complaint Date:	04/08/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/11/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/01/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/20/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

MUSE APARTMENTS (Continued) **S122365891**

Start Date:	02/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	05/15/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D

MUSE APARTMENTS (Continued) **S122365891**

Certification Statement Date:	02/11/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	06/09/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/02/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	15
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/02/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/29/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	06/24/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	16
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/28/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/12/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Chester Grace
Violation:	Not reported
Complaint Date:	07/22/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/13/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	17
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/13/2022
Certification Statement Phone:	903-809-1555
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	18
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	05/11/2022
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

MUSE APARTMENTS (Continued) **S122365891**

ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/13/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/11/2022
Reason for Inspection:	Colin McDaniel
Violation:	Not reported
Complaint Date:	09/03/2021
Notification Number:	2021004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/01/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	07/01/2021
Certification Statement Phone:	469-879-9463
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/20/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/05/11
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/11/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021004603
File Number:	63024
License Status Description:	Paid
Expiration Date:	06/12/2022
Original Date:	07/01/2021
Rank Effective Date:	07/01/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	33044
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Fail
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.

MUSE APARTMENTS (Continued) **S122365891**

City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/04/13
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/13/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021004603
File Number:	63024
License Status Description:	Paid
Expiration Date:	06/12/2022
Original Date:	07/01/2021
Rank Effective Date:	07/01/2021
Mod Code:	ANOT

MUSE APARTMENTS (Continued) **S122365891**

Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	32595
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Fail
Inspection Number Grade:	Not reported
Name:	MUSE APARTMENTS
Address:	1007 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/09/20
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported

MUSE APARTMENTS (Continued) **S122365891**

High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	09/20/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022005383
File Number:	73980
License Status Description:	Canceled
Expiration Date:	09/20/2022
Original Date:	08/15/2022
Rank Effective Date:	08/15/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	35444
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

ER643 **CAMDEN SOUTH CONGRESS APARTMENTS** **FINDS** **1012289934**
Target **1007 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 3 of 8 in cluster ER

Actual:
497 ft.

Focus Map:
14

FINDS:
Registry ID: 110040157530

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ES644 **BOBS GARAGE** **EDR Hist Auto** **1013771531**
Target **1007 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 1 of 5 in cluster ES

Actual:
504 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1947	WELLS H P SERVICE STA FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	TARTER STEVE SERV	GASOLINE STATIONS

BOBS GARAGE (Continued) **1013771531**

1958 BOBS GARAGE GASOLINE STATIONS

ES645 **KOCUREKS MAGNOLIA** **EDR Hist Auto** **1013763630**
Target **1007 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 2 of 5 in cluster ES

Actual: EDR Hist Auto
504 ft.

Focus Map:
14

Year:	Name:	Type:
1940	KOCUREKS MAGNOLIA	GASOLINE AND OIL SERVICE STATIONS

ES646 **CAPITAL SPRING & BRAKE AUTO REPR SPRINGS BRAKES** **EDR Hist Auto** **1013771888**
Target **1009 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 3 of 5 in cluster ES

Actual: EDR Hist Auto
503 ft.

Focus Map:
14

Year:	Name:	Type:
1990	CAPITAL SPRING & BRAKE AUTO REP	BRAKE SERVICE
1990	CAPITAL SPRING & BRAKE AUTO REP	AUTOMOBILE REPAIRING

ES647 **HANCOCK SERVICE STATION** **EDR Hist Auto** **1013754489**
Target **1101 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 4 of 5 in cluster ES

Actual: EDR Hist Auto
503 ft.

Focus Map:
14

Year:	Name:	Type:
1965	HANCOCK SERVICE STATION	GASOLINE STATIONS

ET648 **RUBIOLA BROTHERS** **TX HIST UST** **S111678798**
Target **1113 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX**

Site 1 of 15 in cluster ET

Actual: HIST UST AUSTIN:
502 ft.

Focus Map:
14

Name:	RUBIOLA BROTHERS
Address:	1113 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0546
HID UST:	546
Inspection:	Not reported
Due:	06/01/2012

ET649 NO DELAY CLEANERS **EDR Hist Cleaner** **1013777178**
Target 1117 CONGRESS AVE S **N/A**
Property AUSTIN, TX

Site 2 of 15 in cluster ET

Actual: EDR Hist Cleaner
502 ft.

Focus Map:
14

Year:	Name:	Type:
1965	NO DELAY CLEANERS	CLEANERS AND DYERS
1970	NO DELAY CLEANERS & LAUNDRY	CLEANERS AND DYERS
1975	ACE ALTERATIONS CLEANERS	CLEANERS AND DYERS
1980	ACE ALTERATIONS CLEANERS	CLEANERS AND DYERS
1984	ACE ALTERATIONS CLEANERS	CLEANERS AND DYERS
1990	ACE CLEANERS & ALTERATIONS	CLEANERS AND DYERS

ET650 NO DELAY CLEANERS CLO CLNRS **EDR Hist Cleaner** **1013777816**
Target 1117 CONGRESS AVE S **N/A**
Property SOUTH AUSTIN, TX

Site 3 of 15 in cluster ET

Actual: EDR Hist Cleaner
502 ft.

Focus Map:
14

Year:	Name:	Type:
1947	NO DELAY CLEANERS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1953	NO DELAY CLNRS	CLEANERS AND DYERS
1958	NO DELAY CLNS	CLEANERS AND DYERS

ET651 MC COWN & LINDER **EDR Hist Auto** **1013756512**
Target 1123 CONGRESS AVE S **N/A**
Property SOUTH AUSTIN, TX

Site 4 of 15 in cluster ET

Actual: EDR Hist Auto
502 ft.

Focus Map:
14

Year:	Name:	Type:
1947	BURCH SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	MC COWN & LINDER	GASOLINE STATIONS
1958	TERRACE SUPER	GASOLINE STATIONS

ET652 BUTLERS TERRACE GULF **EDR Hist Auto** **1013756582**
Target 1123 CONGRESS AVE S **N/A**
Property AUSTIN, TX

Site 5 of 15 in cluster ET

Actual: EDR Hist Auto
502 ft.

Focus Map:
14

Year:	Name:	Type:
1940	ELLISON GENE FILLING	GASOLINE AND OIL SERVICE STATIONS
1965	BUTLERS TERRACE GULF	GASOLINE STATIONS
1970	BUTLERS TERRACE GULF SERVICE	GASOLINE STATIONS
1990	D & M TIRE COMPANY AUTO REPR	AUTOMOBILE REPAIRING

653 Target Property | **CRAWFORD RESIDENCE**
500 EAST RIVERSIDE #137
AUSTIN, TX 78704 | **TX ASBESTOS** | **S122366015**
N/A

Actual: 446 ft.

Focus Map: 14

ASBESTOS:

Name:	CRAWFORD RESIDENCE
Address:	500 EAST RIVERSIDE #137
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Javier Velazquez
Violation:	Not reported
Complaint Date:	02/23/2018
Notification Number:	2018000932
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/07/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/07/2018
Certification Statement Phone:	512-470-7173
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	02/22/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

CRAWFORD RESIDENCE (Continued) **S122366015**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU654 **AUSTIN MOTEL** **TX ASBESTOS** **S125390124**
Target **1202 SOUTH CONGRESS AVE.** **N/A**
Property **AUSTIN, TX 78704**

Site 1 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

ASBESTOS:

Name:	AUSTIN MOTEL
Address:	1202 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	07/22/2019
Notification Number:	2019005209
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/01/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment

AUSTIN MOTEL (Continued) **S125390124**

Work Type Flag:	A
Certification Statement Date:	07/01/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN MOTEL
Address:	1202 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	07/22/2019
Notification Number:	2019005209
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/01/2019
Date Routed by Supervisor:	Not reported

AUSTIN MOTEL (Continued) **S125390124**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/01/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU655 Target Property | **AUSTIN MOTEL**
1204 SOUTH CONGRESS AVE
AUSTIN, TX 78704 | **TX ASBESTOS** | **S125390125**
N/A

Site 2 of 18 in cluster EU

Actual: 501 ft.

Focus Map: 14

ASBESTOS:

Name:	AUSTIN MOTEL
Address:	1204 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	07/22/2019
Notification Number:	2019005210
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/15/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/15/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/16/2019
Client Code:	Not reported
Client Name:	Not reported

AUSTIN MOTEL (Continued) **S125390125**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN MOTEL
Address:	1204 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	07/22/2019
Notification Number:	2019005210
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/01/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/01/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N

AUSTIN MOTEL (Continued) **S125390125**

Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/17/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU656 **AUSTIN HOTEL** **TX ASBESTOS** **S125390118**
Target **1204 SOUTH CONGRESS AVE STE 201** **N/A**
Property **AUSTIN, TX 78704**

Site 3 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

ASBESTOS:

Name:	AUSTIN HOTEL
Address:	1204 SOUTH CONGRESS AVE STE 201
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	07/08/2019
Notification Number:	2019003609
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

AUSTIN HOTEL (Continued) **S125390118**

Date Report Received:	06/14/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/14/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	67
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU657 Target Property | **AUSTIN HOTEL**
1204 SOUTH CONGRESS AVE
AUSTIN, TX 78704 | **TX ASBESTOS** | **S125390119**
N/A

Site 4 of 18 in cluster EU

Actual: 501 ft.

Focus Map: 14

ASBESTOS:

Name:	AUSTIN HOTEL
Address:	1204 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	05/29/2019
Notification Number:	2019003609
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/06/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/20/2019
Client Code:	Not reported
Client Name:	Not reported

AUSTIN HOTEL (Continued) **S125390119**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU658 **1206 S CONGRESS** **TX ASBESTOS** **S127319227**
Target **1206 S. CONGRESS AVE.** **N/A**
Property **AUSTIN, TX 78704**

Site 5 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

ASBESTOS:

Name:	1206 S CONGRESS
Address:	1206 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/06/2021
Notification Number:	2020007704
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0

1206 S CONGRESS (Continued) **S127319227**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/04/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EV659 **DONALDSON SAND GRAVEL LANDFILL** **TX RGA LF** **S115125153**
Target **.75 MILE NE OF FM 434 .75 MILE S OF STATE HIGHWAY 6 EAST** **N/A**
Property **N/A, TX**

Site 1 of 2 in cluster EV

Actual:
438 ft.

Focus Map:
14

RGA LF:

2007 DONALDSON SAND GRAVEL LANDFILL .75 MILE NE OF FM 434 .75 MILE S OF STATE HIGHWAY 6 EAST

EV660 **TX RGA LF** **S115122371**
Target Property **6MI E INTRSC FM973/SH71,ADJ NE SIDE SH71** **N/A**
AUSTIN, TX

Site 2 of 2 in cluster EV

Actual: 438 ft.
Focus Map: 14

RGA LF:

1993	6MI E INTRSC FM973/SH71,ADJ NE SIDE SH71
1992	6MI E INTRSC FM973/SH71,ADJ NE SIDE SH71

EU661 **SOUTH AUSTIN CLEAN** **EDR Hist Cleaner** **1013786270**
Target Property **1210 CONGRESS AVE S** **N/A**
SOUTH AUSTIN, TX

Site 6 of 18 in cluster EU

Actual: 501 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1935	SOUTH AUSTIN CLEAN	CLOTHES PRESSERS AND CLEANERS

EU662 **E. C. STEWART** **TX HIST UST** **S111678631**
Target Property **1224 S CONGRESS AVE** **N/A**
AUSTIN, TX

Site 7 of 18 in cluster EU

Actual: 501 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	E. C. STEWART
Address:	1224 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0904
HID UST:	904
Inspection:	Not reported
Due:	06/01/2012

EU663 **B. E. HOWELL** **TX HIST UST** **S111678568**
Target Property **1224 S CONGRESS AVE** **N/A**
AUSTIN, TX

Site 8 of 18 in cluster EU

Actual: 501 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	B. E. HOWELL
Address:	1224 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0328
HID UST:	328
Inspection:	Not reported
Due:	06/01/2012

EU664 AUSTIN MOTEL **TX ASBESTOS** **S121359492**
Target 1224 S CONGRESS **N/A**
Property AUSTIN, TX 78704

Site 9 of 18 in cluster EU

Actual: 501 ft.

Focus Map: 14

ASBESTOS:

Name:	AUSTIN MOTEL
Address:	1224 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	12/07/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	02/23/2018
Notification Number:	2018001191
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/22/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/20/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/22/2018
Client Code:	Not reported
Client Name:	Not reported

AUSTIN MOTEL (Continued) **S121359492**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN MOTEL
Address:	1224 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	12/07/2018
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	02/22/2018
Notification Number:	2018001191
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/14/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/07/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N

AUSTIN MOTEL (Continued) **S121359492**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN MOTEL
Address:	1224 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/02/22
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

AUSTIN MOTEL (Continued) **S121359492**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	02/22/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018001191
File Number:	28085
License Status Description:	Paid
Expiration Date:	02/23/2018
Original Date:	02/14/2018
Rank Effective Date:	02/14/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	9352
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	AUSTIN MOTEL
Address:	1224 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	10/04/2017
Notification Number:	2017007411
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

AUSTIN MOTEL (Continued) **S121359492**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/25/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/03/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AUSTIN MOTEL (Continued) **S121359492**

Name:	AUSTIN MOTEL
Address:	1224 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	10/03/2017
Notification Number:	2017007411
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/19/2017
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

AUSTIN MOTEL (Continued) **S121359492**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU665 **INNOVATIVE MEDICAL GROUP** **FINDS** **1027285019**
Target **1221 1221 S CONGRESS AVE STE 1-110** **N/A**
Property **AUSTIN, TX 78704**

Site 10 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

FINDS:
Registry ID: 110071268893

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EU666 **INNOVATIVE MEDICAL GROUP** **TX ASBESTOS** **S125393878**
Target **1221 S CONGRESS AVE STE 1-110** **TX Ind. Haz Waste** **N/A**
Property **AUSTIN, TX 78704** **TX CENTRAL REGISTRY**

Site 11 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

ASBESTOS:

Name:	STATE HOUSE ON CONGRESS
Address:	1221 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	JOHN R NELSON
Violation:	Not reported
Complaint Date:	05/24/2019
Notification Number:	2019002436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/22/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/05/2019
Certification Statement Phone:	512-680-6673
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	INNOVATIVE MEDICAL GROUP
Address:	1221 S CONGRESS AVE STE 1-110

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	98228
Registration Initial Notification Date:	03/30/2022
Registration Last Amendment Date:	05/06/2022
EPA Identification:	TXR000085887
Primary NAICS Code:	621111
Status Change Date:	20220330
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	INNOVATIVE MEDICAL GROUP FL PLLC
Contact Name:	ADRIAN AOUN
Contact Telephone Number:	415-3490850
Mailing Address:	660 4TH ST # 202
Mailing Address2:	Not reported
Mailing City,State,Zip:	SAN FRANCISCO, CA 941071618
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	133565
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220508
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	INNOVATIVE MEDICAL GROUP FL PLLC
Operator Address:	660 4THST # 202
Operator Address 2:	Not reported
Operator Address 3:	Not reported

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

Operator City,State,Zip:	SAN FRANCISCO, CA 94107
Operator Country:	UNITED STA
Operator Telephone:	1-415-3490850
Operator Fax Number:	Not reported
Operator Email:	INFO@GOFORWARD.COM
Operator Business Type:	Corporation
Operator Tax ID:	32082063788
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	INNOVATIVE MEDICAL GROUP FL PLLC
Owner Mailing Address:	660 4THST # 202
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	SAN FRANCISCO, CA 94107
Owner Country:	UNITED STA
Owner Telephone:	1-415-3490850
Owner Fax:	Not reported
Owner Email Address:	INFO@GOFORWARD.COM
Owner Business Type:	Corporation
Owner Tax ID:	32082063788
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	MEDICAL CLINIC AUS1
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20220506
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	660 4THST # 202
Contact Address 2:	Not reported
Contact Address 3:	Not reported

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

Contact City,State,Zip:	SAN FRANCISCO, CA 94107
Contact Phone:	1-415-3490850
Contact Fax:	Not reported
Contact Email:	INFO@GOFORWARD.COM
Contact Name:	ADRIAN AOUN
Contact Title:	AUTHORIZED SIGNATORY
Contact Role:	PRICONT
Contact Address:	660 4THST # 202
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN FRANCISCO, CA 94107
Contact Phone:	1-415-3490850
Contact Fax:	Not reported
Contact Email:	INFO@GOFORWARD.COM

Ind. Haz Waste:

Waste ID:	432322
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	VARIOUS MEDICAL WASTE
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	621111
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	ADRIAN AOUN
Contact Title:	AUTHORIZED SIGNATORY
Contact Telephone:	0-415-3490850 x0
Mailing Address:	660 4TH ST # 202
Mailing Address 2:	Not reported

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

Mailing City,St,Zip: SAN FRANCISCO, CA 94107
AR Number: Not reported
Principal Name: INNOVATIVE MEDICAL GROUP FL PLLC
Attention Name: AOUN ,ADRIAN
Attention Suffix: Not reported

CENTRAL REGISTRY:

Regulated Entity Number: RN111496154
Name: INNOVATIVE MEDICAL GROUP
Address: 1221 S CONGRESS AVE STE 1-110
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-0157
Status: ACTIVE
Status Date: 5/6/2022
Customer Number: CN606016046
Customer Name: INNOVATIVE MEDICAL GROUP FL PLLC
Customer Legal Name: Innovative Medical Group FL, PLLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/30/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 621111
Primary NAICS Industry Type Description: Offices of Physicians (except Mental Health Specialists)
Physical Location Description: Not reported

Regulated Entity Number: RN111496154
Name: INNOVATIVE MEDICAL GROUP
Address: 1221 S CONGRESS AVE STE 1-110
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-0157
Status: ACTIVE
Status Date: 5/6/2022
Customer Number: CN606016046
Customer Name: INNOVATIVE MEDICAL GROUP FL PLLC
Customer Legal Name: Innovative Medical Group FL, PLLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/30/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 621111
Primary NAICS Industry Type Description: Offices of Physicians (except Mental Health Specialists)
Physical Location Description: Not reported

Regulated Entity Number: RN111496154
Name: INNOVATIVE MEDICAL GROUP
Address: 1221 S CONGRESS AVE STE 1-110
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-0157
Status: ACTIVE
Status Date: 5/6/2022
Customer Number: CN606016046
Customer Name: INNOVATIVE MEDICAL GROUP FL PLLC
Customer Legal Name: Innovative Medical Group FL, PLLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/30/2022
Affiliation End Date: 12/31/3000

INNOVATIVE MEDICAL GROUP (Continued) **S125393878**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	621111
Primary NAICS Industry Type Description:	Offices of Physicians (except Mental Health Specialists)
Physical Location Description:	Not reported

EU667 **INNOVATIVE MEDICAL GROUP** **RCRA-SQG** **1027223220**
Target **1221 1221 S CONGRESS AVE STE 1-110** **TXR000085887**
Property **AUSTIN, TX 78704**

Site 12 of 18 in cluster EU

Actual:
501 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20220506
Handler Name:	Innovative Medical Group
Handler Address:	1221 S CONGRESS AVE STE 1-110
Handler City,State,Zip:	AUSTIN, TX 78704-0157
EPA ID:	TXR000085887
Contact Name:	ADRIAN AOUN
Contact Address:	660 4TH ST # 202
Contact City,State,Zip:	SAN FRANCISCO, CA 94107-1618
Contact Telephone:	415-349-0850
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	660 4TH ST # 202
Mailing City,State,Zip:	SAN FRANCISCO, CA 94107-1618
Owner Name:	Innovative Medical Group Fl Pllc
Owner Type:	Private
Operator Name:	Innovative Medical Group Fl Pllc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

INNOVATIVE MEDICAL GROUP (Continued) **1027223220**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220523
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D011
Waste Description:	Silver
Waste Code:	P001
Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P042
Waste Description:	1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine
Waste Code:	P075
Waste Description:	Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts
Waste Code:	P105
Waste Description:	Sodium Azide
Waste Code:	U359
Waste Description:	Ethanol, 2-Ethoxy- (Or) Ethylene Glycol Monoethyl Ether

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	INNOVATIVE MEDICAL GROUP FL PLLC
Legal Status:	Private

INNOVATIVE MEDICAL GROUP (Continued) **1027223220**

Date Became Current:	20220330
Date Ended Current:	Not reported
Owner/Operator Address:	660 4TH ST # 202
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94107-1618
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	INNOVATIVE MEDICAL GROUP FL PLLC
Legal Status:	Private
Date Became Current:	20220330
Date Ended Current:	Not reported
Owner/Operator Address:	660 4TH ST # 202
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94107-1618
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20220506
Handler Name:	INNOVATIVE MEDICAL GROUP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	621111
NAICS Description:	OFFICES OF PHYSICIANS (EXCEPT MENTAL HEALTH SPECIALISTS)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

EU668 Target Property | **INNOVATIVE MEDICAL GROUP**
1221 1221 S CONGRESS AVE STE 1-110
AUSTIN, TX 78704 | **ECHO** | **1027245033**
N/A

Site 13 of 18 in cluster EU

Actual: 501 ft.
Focus Map: 14

ECHO:

Envid:	1027245033
Registry ID:	110071268893
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071268893
Name:	INNOVATIVE MEDICAL GROUP
Address:	1221 1221 S CONGRESS AVE STE 1-110
City,State,Zip:	AUSTIN, TX 78704

EU669 Target Property | **STATE HOUSE ON CONGRESS**
1221 SOUTH CONGRESS AVENUE
AUSTIN, TX 78704 | **TX ASBESTOS** | **S125393879**
N/A

Site 14 of 18 in cluster EU

Actual: 501 ft.
Focus Map: 14

ASBESTOS:

Name:	STATE HOUSE ON CONGRESS
Address:	1221 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew D. Romer
Violation:	Not reported
Complaint Date:	05/24/2019
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	02/27/2019
Certification Statement Phone:	214-789-8974
Is The Facility a School or K-12?:	N

STATE HOUSE ON CONGRESS (Continued) **S125393879**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	STATE HOUSE ON CONGRESS
Address:	1221 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew D. Romer
Violation:	Not reported
Complaint Date:	05/24/2019
Notification Number:	2019001883
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

STATE HOUSE ON CONGRESS (Continued) **S125393879**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	02/27/2019
Certification Statement Phone:	214-789-8974
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

EU670 **LEONS CLEANERS INC** **EDR Hist Cleaner** **1020027109**
Target **1221 S CONGRESS AVE APT 9** **N/A**
Property **AUSTIN, TX 78704**

Site 15 of 18 in cluster EU

Actual: EDR Hist Cleaner
501 ft.

Focus Map:
14

Year:	Name:	Type:
2007	LEONS CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2008	LEONS CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

EU671 **SHELL IRVING FILLING** **EDR Hist Auto** **1013768628**
Target **1228 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 16 of 18 in cluster EU

Actual: EDR Hist Auto
501 ft.

Focus Map:
14

Year:	Name:	Type:
1940	SHELL IRVING FILLING	GASOLINE AND OIL SERVICE STATIONS
1965	BURCH H H SERVICE STATION	GASOLINE STATIONS

EU672 **BURCH H H CONOCO SERVICE STN** **EDR Hist Auto** **1021493997**
Target **1228 S CONGRESS** **N/A**
Property **AUSTIN, TX 78704**

Site 17 of 18 in cluster EU

Actual: EDR Hist Auto
501 ft.

Focus Map:
14

Year:	Name:	Type:
1969	BURCH H H CONOCO SERVICE STN	Gasoline Service Stations
1970	BURCH H H CONOCO SERVICE STN	Gasoline Service Stations

EU673 **BURCH H H SERV STA** **EDR Hist Auto** **1013762616**
Target **1228 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 18 of 18 in cluster EU

Actual: EDR Hist Auto
501 ft.

Focus Map:
14

Year:	Name:	Type:
1947	FLEMISTER SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	BURCH H H SERV STA	GASOLINE STATIONS
1958	BURCH H H SERV STA	GASOLINE STATIONS

EW674 **109 JAMES STREET, SINTON** **TX SPILLS** **S107015081**
Target **109 JAMES STREET, SINTON** **N/A**
Property **, TX**

Site 1 of 11 in cluster EW

Actual: SPILLS:
508 ft.

Focus Map:
14

Name:	109 JAMES STREET, SINTON
Address:	109 JAMES STREET, SINTON
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	09/16/1995
Seq Num:	Not reported
Responsible Party Name:	CENTRAL POWER AND LIGHT CO
Responsible Party Address:	P.O BOX 2121
Responsible Party City:	CORPUS CHRISTI
Responsible Party State:	TX
Responsible Party Zip:	787032121
Responsible Party Telephone:	5128815516

109 JAMES STREET, SINTON (Continued) **S107015081**

Substance:	TRANSFORMER/MINERAL OIL
Material Code:	1097
Media Affected:	L
Permit Number:	Not reported
District:	14
Origin:	001
Cause:	002
Basin Code:	20
Notify Date:	Not reported
Adequate Clean:	001
Classification:	003
Basin Name:	SAN ANTONIO-NUECES COASTAL
Water Affected:	NONE
Amnt Spilled:	2 GAL
Amnt in Water:	NONE
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	DENNIS KING SR.
Time Reported:	09:05
Spill Time:	15:30
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

EW675 **K T GARAGE & SER** **EDR Hist Auto** **1013769648**
Target **1300 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 11 in cluster EW

Actual: EDR Hist Auto
507 ft.

Focus Map:
14

Year:	Name:	Type:
1929	K T GARAGE & SERVICE	AUTOMOBILE GARAGES
1929	K T GARAGE & SERVICE	GASOLINE AND OIL SERVICE STATIONS
1935	K T GARAGE & SER	AUTOMOBILE REPAIRERS
1935	K T GARAGE & SER	GASOLINE AND OIL SERVICE STATIONS

EW676 **CITY WRECKER SERVICE** **EDR Hist Auto** **1013762673**
Target **1300 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 3 of 11 in cluster EW

Actual: EDR Hist Auto
507 ft.

Focus Map:
14

Year:	Name:	Type:
1922	K T GARAGE	AUTOMOBILE GARAGES
1965	AUTOMATIC TRANSMISSION CO	AUTOMOBILE REPAIRING
1970	CITY WRECKER SERVICE	AUTOMOBILE REPAIRING
1970	CARTER AUTOMATIC TRANSMISSION C	AUTOMOBILE REPAIRING
1975	CARTER AUTOMATIC TRANSMISSION C	AUTOMOBILE REPAIRING

EW677 **BLUE FRONT FILLING STATION** **EDR Hist Auto** **1013768482**
Target **1301 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 4 of 11 in cluster EW

Actual: EDR Hist Auto
507 ft.

Focus Map:
14

Year:	Name:	Type:
1929	BLUE FRONT FILLING STATION	GASOLINE AND OIL SERVICE STATIONS

EW678 **CARLSON C A FILLING** **EDR Hist Auto** **1013768650**
Target **1301 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 5 of 11 in cluster EW

Actual: EDR Hist Auto
507 ft.

Focus Map:
14

Year:	Name:	Type:
1940	CARLSON C A FILLING	GASOLINE AND OIL SERVICE STATIONS

EX679 Target Property | **HOLLY SHORES FOOD FOREST**
COMAL STREET AND NASH HERNANDEZ SENIOR ROAD
AUSTIN, TX 78702 | **US BROWNFIELDS** | **1018119586**
N/A

Site 1 of 2 in cluster EX

Actual: 455 ft.

Focus Map: 14

US BROWNFIELDS:

Name:	HOLLY SHORES FOOD FOREST
Address:	COMAL STREET AND NASH HERNANDEZ SENIOR ROAD
Recipient name:	R6 TBA - Texas (STAG Funded)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	5.25
Latitude:	30.25105
Longitude:	-97.7320924
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Thie site is located near the city center of Austin within the district consisting of public recreational and residential property. Thie site is adjacent to the north shore of the Colorado River and US Interstate 35. The total area is approximately 5.25 acres confined within an oval shaped tract. The City of Austin has developed the property into a food garden for the community.
Datum:	North American Datum of 1983
Acres Property ID:	194661
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	n/a
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	N
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

HOLLY SHORES FOOD FOREST (Continued) **1018119586**

IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	5.25
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	701
Below Poverty Percent:	24.83
Meidan Income:	4633
Meidan Income Number:	1158
Meidan Income Percent:	41.02
Vacant Housing Number:	241
Vacant Housing Percent:	14.61
Unemployed Number:	136
Unemployed Percent:	4.82

Name:	HOLLY SHORES FOOD FOREST
Address:	COMAL STREET AND NASH HERNANDEZ SENIOR ROAD
Recipient name:	R6 TBA - Texas (STAG Funded)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	5.25
Latitude:	30.25105
Longitude:	-97.7320924
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Thie site is located near the city center of Austin within the district consisting of public recreational and residential property. Thie site is adjacent to the north shore of the Colorado River and US Interstate 35. The total area is approximately 5.25 acres confined within an oval shaped tract. The City of Austin has developed the property into a food garden for the community.
Datum:	North American Datum of 1983
Acres Property ID:	194661
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported

HOLLY SHORES FOOD FOREST (Continued) **1018119586**

Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	64998
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - TBA Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	9/23/2014
Ownership Entity:	Not reported
Completion Date:	12/2/2014
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	N
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	5.25
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	701
Below Poverty Percent:	24.83
Meidan Income:	4633
Meidan Income Number:	1158
Meidan Income Percent:	41.02
Vacant Housing Number:	241
Vacant Housing Percent:	14.61
Unemployed Number:	136

HOLLY SHORES FOOD FOREST (Continued) **1018119586**

Unemployed Percent: 4.82

EX680 Target Property **HOLLY SHORES FOOD FOREST**
COMAL STREET AND NASH HERNANDEZ SENIOR ROAD
AUSTIN, TX 78702

FINDS **1023198572**
N/A

Site 2 of 2 in cluster EX

Actual: 455 ft.
Focus Map: 14

FINDS:
Registry ID: 110064564939

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EW681 Target Property **PALACE CLEANERS**
1313 CONGRESS AVE S
AUSTIN, TX

EDR Hist Cleaner **1013785864**
N/A

Site 6 of 11 in cluster EW

Actual: 512 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1940	PALACE CLEANERS	CLOTHES PRESSERS AND CLEANERS

EY682 Target Property **HANSON HARRY A CLNR**
1315 CONGRESS AVE S
SOUTH AUSTIN, TX

EDR Hist Cleaner **1013785979**
N/A

Site 1 of 4 in cluster EY

Actual: 513 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1916	HANSON HARRY A CLNR	CLOTHES CLEANERS AND PRESSERS

EY683 Target Property **SAINT VINCENT**
1333 S CONGRESS AVE
AUSTIN, TX 78704

FINDS **1024439695**
ECHO **N/A**

Site 2 of 4 in cluster EY

Actual: 524 ft.
Focus Map: 14

FINDS:
Registry ID: 110070362880

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

SAINT VINCENT (Continued) **1024439695**

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024439695
Registry ID:	110070362880
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070362880
Name:	SAINT VINCENT
Address:	1333 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

EY684 **SAINT VINCENT** **TX CENTRAL REGISTRY** **S126937599**
Target Property **1333 S CONGRESS AVE** **N/A**
AUSTIN, TX 78704

Site 3 of 4 in cluster EY

Actual: 524 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN110375888
Name:	SAINT VINCENT
Address:	1333 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2570
Status:	ACTIVE
Status Date:	2018-04-25
Customer Number:	CN604068155
Customer Name:	SABRE COMMERCIAL INC
Customer Legal Name:	Sabre Commercial, Inc.
Customer Ownership Type:	GENERAL PARTNERSHIP
Affiliation Begin Date:	2018-04-25
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

EZ685 **SOUTH AUSTIN BAR** **EDR Hist Cleaner** **1013787533**
Target Property **1400 CONGRESS AVE S** **N/A**
SOUTH AUSTIN, TX

Site 1 of 6 in cluster EZ

Actual: 525 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1958	SOUTH AUSTIN BAR	CLEANERS AND DYERS

EZ686 Target Property — **MEARS DOC CLNRS**, **1415 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Cleaner** — **1013777922** / **N/A**

Site 2 of 6 in cluster EZ

Actual: 527 ft. **Focus Map: 14**

EDR Hist Cleaner

Year:	Name:	Type:
1953	MEARS DOC CLNRS	CLEANERS AND DYERS

EZ687 Target Property — **CAMPION COLOR**, **1423 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Cleaner** — **1013778761** / **N/A**

Site 3 of 6 in cluster EZ

Actual: 529 ft. **Focus Map: 14**

EDR Hist Cleaner

Year:	Name:	Type:
1953	CAMPION CLNRS	CLEANERS AND DYERS
1958	CAMPION COLOR	CLEANERS AND DYERS

EZ688 Target Property — **TOWN 6 COUNTRY CLEANERS**, **1423 CONGRESS AVE S**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013787544** / **N/A**

Site 4 of 6 in cluster EZ

Actual: 529 ft. **Focus Map: 14**

EDR Hist Cleaner

Year:	Name:	Type:
1965	TOWN 6 COUNTRY CLEANERS	CLEANERS AND DYERS
1970	TOWN & COUNTRY CLEANERS & LAUND	CLEANERS AND DYERS
1975	TOWN & COUNTRY CLEANERS & LAUND	CLEANERS AND DYERS
1980	WASHBURNS TOWN & COUNTRY CLEANE	CLEANERS AND DYERS
1984	WASHBURNS TOWN & COUNTRY CLEANE	CLEANERS AND DYERS
1990	WASHBURNS TOWN & COUNTRY CLEANE	CLEANERS AND DYERS

FA689 Target Property — **AUSTIN COTTON**, **409 W MONROE ST**, **AUSTIN, TX 78704** — **TX CENTRAL REGISTRY** — **S126602750** / **N/A**

Site 1 of 2 in cluster FA

Actual: 502 ft. **Focus Map: 14**

CENTRAL REGISTRY:

Regulated Entity Number:	RN103029807
Name:	AUSTIN COTTON
Address:	409 W MONROE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3025
Status:	ACTIVE
Status Date:	3/17/2003
Customer Number:	CN601559479
Customer Name:	BALCONES SPORTSWARE
Customer Legal Name:	Balcones Sportsware
Customer Ownership Type:	CORPORATION

AUSTIN COTTON (Continued) **S126602750**

Affiliation Begin Date:	2/3/1994
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	313320
Primary NAICS Industry Type Description:	Fabric Coating Mills
Physical Location Description:	Not reported

Regulated Entity Number:	RN103029807
Name:	AUSTIN COTTON
Address:	409 W MONROE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3025
Status:	ACTIVE
Status Date:	3/17/2003
Customer Number:	CN601559479
Customer Name:	BALCONES SPORTSWARE
Customer Legal Name:	Balcones Sportsware
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/3/1994
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	313320
Primary NAICS Industry Type Description:	Fabric Coating Mills
Physical Location Description:	Not reported

FA690 **AUSTIN COTTON** **TX Ind. Haz Waste** **S103611530**
Target **409 W MONROE ST** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 2 in cluster FA

Actual:
502 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	AUSTIN COTTON
Address:	409 W MONROE ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	81595
Registration Initial Notification Date:	09/08/1993
Registration Last Amendment Date:	01/05/2006
EPA Identification:	Not reported
Primary NAICS Code:	313320
Status Change Date:	19930908
Land Type:	Not reported
Description of Facility Site Location:	409 W Monroe, Austin, TX 78704
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	BALCONES SPORTSWARE

AUSTIN COTTON (Continued) **S103611530**

Contact Name:	JEFF A WITTIG
Contact Telephone Number:	512-4424922
Mailing Address:	409 W MONROE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787043025
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	36615
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060105
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BALCONES SPORTSWARE
Operator Address:	409 W MONROE ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BALCONES SPORTSWARE
Owner Mailing Address:	409 W MONROE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

AUSTIN COTTON (Continued) **S103611530**

Contact Role:	OPRCON
Contact Address:	409 W MONROE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	409 W MONROE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JEFF WITTIG
Contact Title:	PRODUCTION MANAGER
Contact Role:	PRICONT
Contact Address:	409 W MONROE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4424922
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	75389
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvent clean silk screens, 11-92
Standard Industrial Code:	22950
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	313320
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

AUSTIN COTTON (Continued) **S103611530**

Ind. Haz Waste:

FB691 **A CLEANERS SUB STA** **EDR Hist Cleaner** **1013782420**
Target **1507 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 1 of 6 in cluster FB

Actual: EDR Hist Cleaner
542 ft.

Focus Map:
14

Year:	Name:	Type:
1953	A CLEANERS SUB STA	CLEANERS AND DYERS

FB692 **GRIFFITH W G INDRY** **EDR Hist Cleaner** **1013780614**
Target **1512 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 6 in cluster FB

Actual: EDR Hist Cleaner
542 ft.

Focus Map:
14

Year:	Name:	Type:
1929	GRIFFITH W G INDRY	LAUNDRIES

FB693 **SOUTH MAIN CLEANERS** **EDR Hist Cleaner** **1013783602**
Target **1518 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 3 of 6 in cluster FB

Actual: EDR Hist Cleaner
543 ft.

Focus Map:
14

Year:	Name:	Type:
1940	SOUTH AUSTIN LAUN	LAUNDRIES
1970	SOUTH MAIN CLEANERS	CLEANERS AND DYERS

FB694 **SOUTH AUSTIN LAUN** **EDR Hist Cleaner** **1013778276**
Target **1518 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 4 of 6 in cluster FB

Actual: EDR Hist Cleaner
543 ft.

Focus Map:
14

Year:	Name:	Type:
1935	SOUTH AUSTIN LAUN	LAUNDRIES

FC695 **DOHERTY L W CLDO** **EDR Hist Cleaner** **1013778879**
Target **1602 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 1 of 7 in cluster FC

Actual: EDR Hist Cleaner
549 ft.

Focus Map: Year: Name: Type:
14 1940 DOHERTY L W CLDO CLOTHES PRESSERS AND CLEANERS

FC696 **DOHERTY L W DCLO CLNR** **EDR Hist Cleaner** **1013778880**
Target **1602 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 7 in cluster FC

Actual: EDR Hist Cleaner
549 ft.

Focus Map: Year: Name: Type:
14 1935 DOHERTY L W DCLO CLNR CLOTHES PRESSERS AND CLEANERS
1947 MCCOY CLEANERS CLOTHES PRESSERS AND CLEANERS

FC697 **WELLS SAML W AUTO** **EDR Hist Auto** **1013758606**
Target **1606 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 3 of 7 in cluster FC

Actual: EDR Hist Auto
550 ft.

Focus Map: Year: Name: Type:
14 1940 WELLS SAML W AUTO AUTOMOBILE REPAIRING

FC698 **BOBS GARAGE** **EDR Hist Auto** **1013753337**
Target **1606 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 4 of 7 in cluster FC

Actual: EDR Hist Auto
550 ft.

Focus Map: Year: Name: Type:
14 1947 BOBS GARAGE AUTOMOBILE REPAIRING

FC699 **SOUTH AUSTIN CLNRS** **EDR Hist Cleaner** **1013786273**
Target **1608 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 5 of 7 in cluster FC

Actual: EDR Hist Cleaner
550 ft.

Focus Map: Year: Name: Type:
14 1935 TAYLORS TAILOR SHOP CLOTHES PRESSERS AND CLEANERS

SOUTH AUSTIN CLNRS (Continued) **1013786273**

1947	SOUTH AUSTIN CLEANERS	CLOTHES PRESSERS AND CLEANERS
1953	SOUTH AUSTIN CLNRS	CLEANERS AND DYERS

FC700 Target Property **SOUTH AUSTIN CLEANERS** **EDR Hist Cleaner** **1013784934**
1608 CONGRESS AVE S **N/A**
AUSTIN, TX

Site 6 of 7 in cluster FC

Actual: 550 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1940	SOUTH AUSTIN CLEAN	CLOTHES PRESSERS AND CLEANERS
1965	SOUTH AUSTIN CLEANERS	CLEANERS AND DYERS

FC701 Target Property **A. F. HARACH** **TX HIST UST** **S111678537**
1610 S CONGRESS AVE **N/A**
AUSTIN, TX

Site 7 of 7 in cluster FC

Actual: 550 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	A. F. HARACH
Address:	1610 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0948
HID UST:	948
Inspection:	Not reported
Due:	06/01/2012

FD702 Target Property **STAR RIVERSIDE** **TX CENTRAL REGISTRY** **S126794087**
1300 E RIVERSIDE DR **N/A**
AUSTIN, TX 78741

Site 1 of 2 in cluster FD

Actual: 481 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN105634091
Name:	STAR RIVERSIDE
Address:	1300 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1108
Status:	ACTIVE
Status Date:	2008-10-10
Customer Number:	CN603941840
Customer Name:	SOUTHERN CROSS GROUP USA LLC
Customer Legal Name:	Southern Cross Group Usa LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2011-07-12
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

STAR RIVERSIDE (Continued) **S126794087**

Regulated Entity Number:	RN105634091
Name:	STAR RIVERSIDE
Address:	1300 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1108
Status:	ACTIVE
Status Date:	2008-10-10
Customer Number:	CN603941840
Customer Name:	SOUTHERN CROSS GROUP USA LLC
Customer Legal Name:	Southern Cross Group Usa LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2011-07-12
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105634091
Name:	STAR RIVERSIDE
Address:	1300 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1108
Status:	ACTIVE
Status Date:	2008-10-10
Customer Number:	CN603414392
Customer Name:	CONSTELLATION PROPERTY GROUP STAR LP
Customer Legal Name:	Constellation Property Group (Star) LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2008-09-11
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105634091
Name:	STAR RIVERSIDE
Address:	1300 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1108
Status:	ACTIVE
Status Date:	2008-10-10
Customer Number:	CN603414392
Customer Name:	CONSTELLATION PROPERTY GROUP STAR LP
Customer Legal Name:	Constellation Property Group (Star) LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2008-09-11
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

FD703 Target Property | **RIVERVIEW APARTMENTS**
1300 E. RIVERSIDE DR.
AUSTIN, TX 78741 | **TX ASBESTOS** | **S119155627**
N/A

Site 2 of 2 in cluster FD

Actual: 481 ft.

Focus Map: 14

ASBESTOS:

Name:	RIVERVIEW APARTMENTS
Address:	1300 E. RIVERSIDE DR.
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/29/2012
Reason for Inspection:	Discretionary
Violation:	No
Complaint Date:	Not reported
Notification Number:	N/A
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	12/17/2012
Date Routed by Supervisor:	12/27/2012
Date Routed to PSQA:	01/14/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

RIVERVIEW APARTMENTS (Continued) **S119155627**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FE704 **BOBS GARAGE REPRS** **EDR Hist Auto** **1013768507**
Target Property **103 MILTON W** **N/A**
S AUSTIN, TX

Site 1 of 6 in cluster FE

Actual: 559 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1953	BOBS GARAGE REPRS	AUTOMOBILE REPAIRING

FE705 **CALDWELL & MILLER** **TX HIST UST** **S128729164**
Target Property **1700 S CONGRESS AVE** **N/A**
AUSTIN, TX

Site 2 of 6 in cluster FE

Actual: 560 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	CALDWELL & MILLER
Address:	1700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0028
HID UST:	28
Inspection:	03/06/2009
Due:	03/06/2012

FE706 Target Property | **CALDWELL & MILLER**
1700 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S128729179**
N/A

Site 3 of 6 in cluster FE

Actual: 560 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	CALDWELL & MILLER
Address:	1700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0085
HID UST:	85
Inspection:	Not reported
Due:	06/01/2012

FE707 Target Property | **T. J. CALDWELL**
1700 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678815**
N/A

Site 4 of 6 in cluster FE

Actual: 560 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	T. J. CALDWELL
Address:	1700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0314
HID UST:	314
Inspection:	Not reported
Due:	06/01/2012

FF708 Target Property | **RUTLANDS PHILLIPS 66 SERVICE STATION**
1610 RIVERSIDE DR E
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013758268**
N/A

Site 1 of 8 in cluster FF

Actual: 471 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1970	RUTLANDS PHILLIPS 66 SERVICE ST	GASOLINE STATIONS

FG709 Target Property | **DYE A D FILL STA**
1801 CONGRESS AVE S
SOUTH AUSTIN, TX | **EDR Hist Auto** | **1013760052**
N/A

Site 1 of 8 in cluster FG

Actual: 566 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1929	DYES GROCERY & FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	DYE A D FILL STA	GASOLINE AND OIL SERVICE STATIONS
1947	DYES SERVICE STATION FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	DYES SERVICE STA	GASOLINE STATIONS
1958	DYE C A SERV STA	GASOLINE STATIONS

FG710 Target Property | **DYE SALES & SERVICE GAS ST**
1801 CONGRESS AVE S
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013763054**
N/A

Site 2 of 8 in cluster FG

Actual: 566 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1940	DYES SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1965	DYE SALES & SERVICE GAS STA H	GASOLINE STATIONS
1970	DYE SALES & SERVICE GAS ST	GASOLINE STATIONS
1975	ARCO DYE SALES & SERVICE GAS ST	GASOLINE STATIONS
1980	DYE SALES & SERVICE GAS ST	GASOLINE STATIONS
1984	DYE SALES & SERVICE GAS ST	GASOLINE STATIONS
1990	HI TECH AUTOMOTIVE REPR	AUTOMOBILE REPAIRING

FF711 Target Property | **SHOPPERS MART 22**
1609 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX CENTRAL REGISTRY** | **S126594076**
N/A

Site 2 of 8 in cluster FF

Actual: 477 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN102821915
Name:	SHOPPERS MART 22
Address:	1609 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1005
Status:	ACTIVE
Status Date:	8/13/2002
Customer Number:	CN601163454
Customer Name:	TRIPLE S PETROLEUM COMPANY
Customer Legal Name:	Triple S Petroleum Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102821915
Name:	SHOPPERS MART 22
Address:	1609 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1005
Status:	ACTIVE
Status Date:	8/13/2002
Customer Number:	CN601163454
Customer Name:	TRIPLE S PETROLEUM COMPANY
Customer Legal Name:	Triple S Petroleum Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FF712 **ERNS** **9169426**
Target Property **1609 EAST RIVERSIDE DRIVE** **N/A**
AUSTIN, TX 78762

Site 3 of 8 in cluster FF

Actual: 477 ft.

Focus Map: 14

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

FF713 **RUTLAND PHILLIPS 66** **EDR Hist Auto** **1020596442**
Target Property **1609 E RIVERSIDE** **N/A**
AUSTIN, TX 78741

Site 4 of 8 in cluster FF

Actual: 477 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1969	RUTLAND PHILLIPS 66	Gasoline Service Stations
1970	RUTLAND PHILLIPS 66	Gasoline Service Stations
1971	RUTLAND PHILLIPS 66	Gasoline Service Stations
1972	RUTLAND PHILLIPS 66	Gasoline Service Stations
1994	TEXACO ONE STOP	Gasoline Service Stations
1995	TEXACO ONE STOP	Gasoline Service Stations
1996	TEXACO ONE STOP	Gasoline Service Stations

FF714 **SHOPPERS MART 22** **TX LPST** **U001267923**
Target Property **1609 E RIVERSIDE DR** **TX UST** **N/A**
AUSTIN, TX 78741 **TX HIST UST**

Site 5 of 8 in cluster FF

Actual: 477 ft.

Focus Map: 14

LPST:

Name:	SHOPPERS MART 22
Address:	1609 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0034930
LPST Id:	104746
Facility Location:	1609 EAST RIVERSIDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/17/1992
Entered Date:	10/22/1992
Reported Date:	09/18/1992
Closure Date:	04/06/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	FORD SMITH

SHOPPERS MART 22 (Continued) **U001267923**

Responsible Party Address:	PO BOX 6156
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	512/385-2020
Reported Date:	09/18/1992
Case Start Date:	04/06/1993
Reference Number:	RN102821915
Project Manager:	HWELCH

UST:

Name:	SHOPPERS MART 22
Address:	1609 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411005
AI Number:	34930
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	820664942002225
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	SHOPPERS MART 22
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123852020
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	FORD SMITH,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601163454
Owner Last Name:	TRIPLE S PETROLEUM COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported

SHOPPERS MART 22 (Continued) **U001267923**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	832335922002134
Additional ID:	820664942002225
AI Number:	34930
Owner Effective Begin Date:	09/01/1988
State Tax ID:	17424887101
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92345
Facility ID:	77359
Ai Number:	34930
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/20/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

SHOPPERS MART 22 (Continued) **U001267923**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	120140
UST ID:	92345
AI Number:	34930
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

SHOPPERS MART 22 (Continued) **U001267923**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92346
Facility ID:	77359
Ai Number:	34930
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/20/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

SHOPPERS MART 22 (Continued) **U001267923**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	120141
UST ID:	92346
AI Number:	34930
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1

SHOPPERS MART 22 (Continued) **U001267923**

Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92347
Facility ID:	77359
Ai Number:	34930
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/20/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

SHOPPERS MART 22 (Continued) **U001267923**

Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	120142
UST ID:	92347
AI Number:	34930
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92348
Facility ID:	77359
Ai Number:	34930
Tank Id:	1

SHOPPERS MART 22 (Continued) **U001267923**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/20/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	120143
UST ID:	92348
AI Number:	34930

SHOPPERS MART 22 (Continued) **U001267923**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRIPLE S PETROLEUM COMPANY
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77359
Additional ID:	820664942002225
Princ ID:	832335922002134
AI Number:	34930
Facility Name:	SHOPPERS MART 22
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	FORD SMITH/

SHOPPERS MART 22 (Continued) **U001267923**

HIST UST AUSTIN:

Name:	SHOPPERS MART
Address:	1609 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0467
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FF715 **SIGMOR SHAMROCK SERVICE STATION NO** **EDR Hist Auto** **1013758533**
Target **1620 RIVERSIDE DR** **N/A**
Property **TRAVIS (County), TX 78741**

Site 6 of 8 in cluster FF

Actual: 472 ft.

EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1970	SHAMROCK SERVICE STATION NO	GASOLINE STATIONS
1975	SHAMROCK SERVICE STATION NO	GASOLINE STATIONS
1980	SIGMOR SERVICE STATION	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1990	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS

---

716 **CITY OF AUSTIN BOARDWALK TRAIL AT LADY BIRD LAKE** **TX CENTRAL REGISTRY** **S126843857**
Target **1820 S LAKESHORE BLVD** **N/A**
Property **AUSTIN, TX 78741**

Actual: 434 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN106500705
Name:	CITY OF AUSTIN BOARDWALK TRAIL AT LADY BIRD LAKE
Address:	1820 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1251
Status:	ACTIVE
Status Date:	2012-08-27
Customer Number:	CN602464067
Customer Name:	JAY-REESE CONTRACTORS INC
Customer Legal Name:	Jay-Reese Contractors, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-08-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	237990
Primary NAICS Industry Type Description:	Other Heavy and Civil Engineering Construction
Physical Location Description:	Not reported

717 Target Property | **SOUTHSHORE TOWNHOMES**
1201 TOWN CREEK DR
AUSTIN, TX 78741 | **TX CENTRAL REGISTRY** | **S126909200**
N/A

Actual: 447 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN109436048
Name:	SOUTHSHORE TOWNHOMES
Address:	1201 TOWN CREEK DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1536
Status:	ACTIVE
Status Date:	2016-09-30
Customer Number:	CN605240720
Customer Name:	SAGE SOUTH SHORE LLC
Customer Legal Name:	Sage South Shore, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2016-09-30
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FH718 Target Property | **TEXAS AUTOMOTIVE SERVICE AUTO REPRS**
2006 CONGRESS AVE S
SOUTH AUSTIN, TX | **EDR Hist Auto** | **1013767864**
N/A

Site 1 of 3 in cluster FH

Actual: 576 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1947	TEXAS AUTOMOTIVE SERVICE AUTO R	AUTOMOBILE REPAIRING

FH719 Target Property | **HUGHES LAUNDERETTE**
2006 CONGRESS AVE S
SOUTH AUSTIN, TX | **EDR Hist Cleaner** | **1013779462**
N/A

Site 2 of 3 in cluster FH

Actual: 576 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1953	HUGHES LAUNDERETTE	LAUNDRIES-SELF SERVE

FI720 Target Property | **ACME CLEANERS**
1800 RIVERSIDE DR E
TRAVIS (County), TX 78741 | **EDR Hist Cleaner** | **1013782492**
N/A

Site 1 of 12 in cluster FI

Actual: 452 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1975	ACME CLEANERS	CLEANERS AND DYERS

FI721 Target Property | **KWIK WASH COIN LAUNDRIES NO**
1723 RIVERSIDE DR E
AUSTIN, TX 78741 | **EDR Hist Cleaner** | **1013780709**
N/A

Site 2 of 12 in cluster FI

Actual: 461 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1975	KWIK WASH COIN OPERATED	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1984	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

FI722 Target Property | **KWIK WASH COIN LAUNDRIES NO**
1723 RIVERSIDE DR
TRAVIS (County), TX 78741 | **EDR Hist Cleaner** | **1013780708**
N/A

Site 3 of 12 in cluster FI

Actual: 461 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1990	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

FI723 Target Property | **KAVECKI TEXACO SE**
1725 RIVERSIDE DR E
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013754564**
N/A

Site 4 of 12 in cluster FI

Actual: 460 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1965	KAVECKI TEXACO SERVICE GAS STA	GASOLINE STATIONS
1970	KAVECKI TEXACO SE	GASOLINE STATIONS
1975	KAVECKI TEXACO SERVICE	GASOLINE STATIONS

FI724 Target Property | **RIVERSIDE GROCERY**
1727 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX UST**
TX HIST UST
TX ASBESTOS
TX Financial Assurance | **U004240520**
N/A

Site 5 of 12 in cluster FI

Actual: 459 ft.
Focus Map: 14

UST:

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411319
AI Number:	86602
Facility Type:	RETAIL
Facility Begin Date:	12/12/2013
Facility Status:	ACTIVE
Additional ID:	924407402014041
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported

RIVERSIDE GROCERY (Continued) **U004240520**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/01/2018
Signature Name/Title On Earliest Reg Form:	GUY OLIVER,
Application Received Date On Earliest Reg Form:	10/04/2018
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	264324162020029
Additional ID:	924407402014041
Ai Number:	86602
Operator CN:	CN605745975
Operator Name:	GOZIG HOLDINGS LLC
Operator Effective Begin Date:	01/01/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601413677
Owner Last Name:	720 LAMAR PLACE LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

RIVERSIDE GROCERY (Continued) **U004240520**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	335739642002204
Additional ID:	924407402014041
AI Number:	86602
Owner Effective Begin Date:	12/12/2013
State Tax ID:	30118952057
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	131728
Cert ID:	373765
AI Number:	86602
Self Certification Date:	08/02/2022
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	361267
AI Number:	86602
Self Certification Date:	09/29/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	341778
AI Number:	86602

RIVERSIDE GROCERY (Continued) **U004240520**

Self Certification Date:	08/31/2020
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	131728
Cert ID:	332215
AI Number:	86602
Self Certification Date:	01/15/2020
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	131728
Cert ID:	323879
AI Number:	86602
Self Certification Date:	07/31/2019
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	131728
Cert ID:	306303
AI Number:	86602

RIVERSIDE GROCERY (Continued) **U004240520**

Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	290414
AI Number:	86602
Self Certification Date:	08/15/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	273445
AI Number:	86602
Self Certification Date:	08/11/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	257072
AI Number:	86602

RIVERSIDE GROCERY (Continued) **U004240520**

Self Certification Date:	08/21/2015
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	239307
AI Number:	86602
Self Certification Date:	07/24/2014
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131728
Cert ID:	231751
AI Number:	86602
Self Certification Date:	01/15/2014
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	12/12/2013
Tank Registration Date:	02/07/2014

RIVERSIDE GROCERY (Continued) **U004240520**

Number of Compartments:	2
Tank Capacity:	20172
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	219160
Facility ID:	131728
Ai Number:	86602
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/12/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y

RIVERSIDE GROCERY (Continued) **U004240520**

Technical Compliance Flag:	Y
Tank Tested Flag:	Not reported
Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	1
Tank Capacity:	16059
UST Comprt ID:	186789
UST ID:	219160
AI Number:	86602
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported
Tank ID:	1
Tank Capacity:	4113
UST Comprt ID:	186790
UST ID:	219160
AI Number:	86602
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

RIVERSIDE GROCERY (Continued) **U004240520**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	32927
Cert ID:	106831
UST Comprt ID:	299541
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927
Cert ID:	106830
UST Comprt ID:	299544
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927
Cert ID:	106833
UST Comprt ID:	299539
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927

RIVERSIDE GROCERY (Continued) **U004240520**

Cert ID:	106832
UST Comprt ID:	299540
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927
Cert ID:	106834
UST Comprt ID:	299538
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927
Cert ID:	106828
UST Comprt ID:	299542
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A
Self Cert ID:	32927
Cert ID:	106829
UST Comprt ID:	299543
UST ID:	99173
AI Number:	86602
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	512 6372010/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	131728
Additional ID:	924407402014041
Princ ID:	335739642002204
AI Number:	86602
Facility Name:	RIVERSIDE GROCERY
AR Number:	50118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX

RIVERSIDE GROCERY (Continued) **U004240520**

Id UST:	3374
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported

RIVERSIDE GROCERY (Continued) **U004240520**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/17/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported

RIVERSIDE GROCERY (Continued) **U004240520**

Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	271614
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

RIVERSIDE GROCERY (Continued) **U004240520**

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	255487
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	227178
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	236743
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

RIVERSIDE GROCERY (Continued) **U004240520**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	216570
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	199578
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported

RIVERSIDE GROCERY (Continued) **U004240520**

Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	182958
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	165386
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

RIVERSIDE GROCERY (Continued) **U004240520**

Region:	2
Facility ID:	131728
Finass ID:	148061
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224499
Policy Number:	04-TO-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	122473
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	131728
Finass ID:	130224
AI:	86602
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

RIVERSIDE GROCERY (Continued) **U004240520**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

FI725 **RIVERSIDE GROCERY** **TX ENF** **S115812926**
Target **1727 E RIVERSIDE DR** **TX COMP HIST** **N/A**
Property **AUSTIN, TX 78741**

Site 6 of 12 in cluster FI

Actual:
459 ft.

Focus Map:
14

ENFORCEMENT:

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN603661398
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	MTG MANAGEMENT INC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	RECONT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported

RIVERSIDE GROCERY (Continued) **S115812926**

Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN603661398
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	MTG MANAGEMENT INC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN603661398
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	MTG MANAGEMENT INC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported

RIVERSIDE GROCERY (Continued) **S115812926**

Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	PARTICIPAT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN603661398
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	MTG MANAGEMENT INC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	REGMAIL
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.

RIVERSIDE GROCERY (Continued) **S115812926**

Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN601413677
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	720 LAMAR PLACE LC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	RECONT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported

RIVERSIDE GROCERY (Continued) **S115812926**

Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN601413677
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	720 LAMAR PLACE LC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	PARTICIPAT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN601413677
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	720 LAMAR PLACE LC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported

RIVERSIDE GROCERY (Continued) **S115812926**

Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	NOV CONT
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Unique TCEQ Ref Number Of Customer:	CN601413677
Unique TCEQ Ref Number Of Reg. Entity:	RN107020703
Contact Person For The Reg. Entity:	GUY OLIVER
Owner/operator Of A Regulated Entity:	720 LAMAR PLACE LC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001138157
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	462,575,032,014,029.00
Role Code:	REGMAIL
Date Notice Of Violation Issued:	01/31/2014
Description 1:	Failed to meet pH limit of 9.0
Description 2:	The pH of the effluent was reduced as the wastewater flowed through the wastewater treatment carbon. In the future, the pH will be monitored when the the treatment process is started and the effluent

RIVERSIDE GROCERY (Continued) **S115812926**

	will not be discharged until the effluent meets the pH requirement.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	305.125(1)
Status Of The NOV:	DAPPROVED
Investigation:	1138157
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	C

COMP HIST:

RN Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Region:	REGION 11 - AUSTIN
CN Number:	CN605745975
CN Name:	GOZIG HOLDINGS LLC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	325182
SIC Code:	1542
Related Number:	86602,14518,14518

RN Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Region:	REGION 11 - AUSTIN
CN Number:	CN603661398
CN Name:	MTG MANAGEMENT INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	813110
SIC Code:	5541

RIVERSIDE GROCERY (Continued) **S115812926**

Related Number:	86602,14518,14518

RN Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Region:	REGION 11 - AUSTIN
CN Number:	CN601704208
CN Name:	A ONE DISCOUNT TIRE
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	423140
SIC Code:	0115
Related Number:	86602,14518,14518

RN Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-1319
Region:	REGION 11 - AUSTIN
CN Number:	CN601413677
CN Name:	720 LAMAR PLACE LC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	8351
Related Number:	86602,14518,14518

FI726 **RIVERSIDE GROCERY** **TX CENTRAL REGISTRY** **S126862835**
Target **1727 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 7 of 12 in cluster FI

Actual:
459 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	2013-12-03
Customer Number:	CN601413677
Customer Name:	720 LAMAR PLACE LC
Customer Legal Name:	720 Lamar Place, L.C.
Customer Ownership Type:	CORPORATION

RIVERSIDE GROCERY (Continued) **S126862835**

Affiliation Begin Date:	2013-11-25
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	2013-12-03
Customer Number:	CN601704208
Customer Name:	A ONE DISCOUNT TIRE
Customer Legal Name:	A-One Discount Tires, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	2013-12-03
Customer Number:	CN603661398
Customer Name:	MTG MANAGEMENT INC
Customer Legal Name:	MTG MANAGEMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-11-25
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	2013-12-03
Customer Number:	CN605745975
Customer Name:	GOZIG HOLDINGS LLC
Customer Legal Name:	Gozig Holdings, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2020-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE

RIVERSIDE GROCERY (Continued) **S126862835**

Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN601413677
Customer Name:	720 LAMAR PLACE LC
Customer Legal Name:	720 Lamar Place, L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/25/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN601704208
Customer Name:	A ONE DISCOUNT TIRE
Customer Legal Name:	A-One Discount Tires, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN603661398
Customer Name:	MTG MANAGEMENT INC
Customer Legal Name:	MTG MANAGEMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/25/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

RIVERSIDE GROCERY (Continued) **S126862835**

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN605745975
Customer Name:	GOZIG HOLDINGS LLC
Customer Legal Name:	Gozig Holdings, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/1/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN601413677
Customer Name:	720 LAMAR PLACE LC
Customer Legal Name:	720 Lamar Place, L.C.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/25/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN601704208
Customer Name:	A ONE DISCOUNT TIRE
Customer Legal Name:	A-One Discount Tires, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN107020703
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR

RIVERSIDE GROCERY (Continued) **S126862835**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	12/3/2013
Customer Number:	CN603661398
Customer Name:	MTG MANAGEMENT INC
Customer Legal Name:	MTG MANAGEMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/25/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

FI727 **RIVERSIDE GROCERY** **FINDS** **1016701562**
Target **1727 E RIVERSIDE DR** **ECHO** **N/A**
Property **AUSTIN, TX 78741**

Site 8 of 12 in cluster FI

Actual:
459 ft.

Focus Map:
14

FINDS:
Registry ID: 110056410325

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016701562
Registry ID:	110056410325
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056410325
Name:	RIVERSIDE GROCERY
Address:	1727 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

FI728 Target Property | **7-ELEVEN 23076**
1729 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX UST** / **TX HIST UST** | **U001243550** / **N/A**

Site 9 of 12 in cluster FI

Actual: 458 ft.

Focus Map: 14

UST:

Name:	7-ELEVEN 23076
Address:	1729 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411319
AI Number:	7127
Facility Type:	RETAIL
Facility Begin Date:	07/03/1986
Facility Status:	INACTIVE
Additional ID:	985133342002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	7-ELEVEN 23076
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123462260
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	985133342002118

7-ELEVEN 23076 (Continued) **U001243550**

AI Number:	7127
Owner Effective Begin Date:	07/03/1986
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18460
Facility ID:	46134
Ai Number:	7127
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/20/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7-ELEVEN 23076 (Continued) **U001243550**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	25928
UST ID:	18460
AI Number:	7127
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

7-ELEVEN 23076 (Continued) **U001243550**

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18461
Facility ID:	46134
Ai Number:	7127
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/20/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

7-ELEVEN 23076 (Continued) **U001243550**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	25929
UST ID:	18461
AI Number:	7127
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/

7-ELEVEN 23076 (Continued) **U001243550**

Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46134
Additional ID:	985133342002118
Princ ID:	959578622001257
AI Number:	7127
Facility Name:	7-ELEVEN 23076
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #23076
Address:	1729 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0078
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FI729 **7 ELEVEN 23076** **FINDS** **1024182763**
Target **1729 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 10 of 12 in cluster FI

Actual:
458 ft.

Focus Map:
14

FINDS:
Registry ID: 110070167390

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FI730 **7 ELEVEN 23076** **TX CENTRAL REGISTRY** **S126559204**
Target **1729 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 11 of 12 in cluster FI

Actual:
458 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN102048337
Name:	7 ELEVEN 23076
Address:	1729 E RIVERSIDE DR
Address 2:	Not reported

7 ELEVEN 23076 (Continued) **S126559204**

City,State,Zip:	AUSTIN, TX 78741-1319
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/3/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FH731 **QUALITY WHOL LNDRY** **EDR Hist Cleaner** **1013783211**
Target Property **2006 CONGRESS AVE** **N/A**
SOUTH AUSTIN, TX

Site 3 of 3 in cluster FH

Actual: 576 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1962	QUALITY WHOL LNDRY	LAUNDRIES

FJ732 **TOWN LAKE PLAZA ASTRO CLEANERS** **EDR Hist Cleaner** **1013780960**
Target Property **1900 RIVERSIDE DR E** **N/A**
AUSTIN, TX 78741

Site 1 of 3 in cluster FJ

Actual: 466 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1970	TOWN LAKE PLAZA LA CASA CLEANER	CLEANERS AND DYERS
1975	TOWN LAKE PLAZA LA CASA CLEANER	CLEANERS AND DYERS
1980	TOWN LAKE PLAZA LA CASA CLEANER	CLEANERS AND DYERS
1984	TOWN LAKE PLAZA ASTRO CLEANERS	CLEANERS AND DYERS

FJ733 **JIMS RIVERSIDE GULF SERVICE** **EDR Hist Auto** **1013758362**
Target Property **1801 RIVERSIDE DR E** **N/A**
TRAVIS (County), TX 78704

Site 2 of 3 in cluster FJ

Actual: 467 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1970	JIMS RIVERSIDE GULF SERVICE	GASOLINE STATIONS
1975	RIVERSIDE GULF SERVICE	GASOLINE STATIONS
1980	RIVERSIDE GULF SERVICE	GASOLINE STATIONS

FK734 Target Property | **7-ELEVEN INC 22245**
2103 S CONGRESS AVE
AUSTIN, TX | **TX RDR** | **S127538658**
N/A

Site 1 of 13 in cluster FK

Actual: 580 ft.
Focus Map: 14

RDR:

RDR ID:	15750
Facility ID:	7144
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN INC 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/22/2006
Due Date:	2/20/2007
Tank Owner:	7-ELEVEN INC
Contact Person:	SHANE PARTRIDGE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/1/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	104821
Comments:	DOES THIS NEED A NEW LPST # OR REOPENED?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/1/2007
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FK735 Target Property | **7 ELEVEN STORE 22245**
2103 S CONGRESS AVE
AUSTIN, TX 78704 | **TX CENTRAL REGISTRY** | **S126054790**
N/A

Site 2 of 13 in cluster FK

Actual: 580 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

7 ELEVEN STORE 22245 (Continued) **S126054790**

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP
Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP
Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE

7 ELEVEN STORE 22245 (Continued) **S126054790**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE

7 ELEVEN STORE 22245 (Continued) **S126054790**

Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP
Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057890
Name:	7 ELEVEN STORE 22245
Address:	2103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4316
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP

7 ELEVEN STORE 22245 (Continued) **S126054790**

Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
12 additional TX CENTRAL REG: record(s) in the EDR Site Report.

FK736 **7 11 STORE 22245** **TX RDR** **S127538657**
Target **2103 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX**

Site 3 of 13 in cluster FK

Actual:
580 ft.

Focus Map:
14

RDR:

RDR ID:	12614
Facility ID:	7144
RN:	Not reported
CN:	Not reported
Name:	7 11 STORE 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/1/2003
Due Date:	9/30/2003
Tank Owner:	7 ELEVEN INC
Contact Person:	WILLO SMITH
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/27/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	104821
Comments:	Not reported
Review Coordinator:	PPC/SRJ
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/27/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FK737 **7 ELEVEN STORE 22245** **FINDS** **1010746993**
Target **2103 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 4 of 13 in cluster FK

Actual:
580 ft.

Focus Map:
14

FINDS:
Registry ID: 110033437868

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
TSCA SUBMITTER
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FK738 **7-ELEVEN 22245** **TX LPST** **U001243567**
Target **2103 S CONGRESS AVE** **TX UST** **N/A**
Property **AUSTIN, TX 78704** **TX HIST UST**
TX ASBESTOS
Site 5 of 13 in cluster FK **TX Financial Assurance**

Actual:
580 ft.

Focus Map:
14

LPST:

Name:	7 ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0007144
LPST Id:	104821
Facility Location:	2103 SOUTH CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/16/1992
Entered Date:	10/05/1992
Reported Date:	07/20/1992
Closure Date:	06/17/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/2
Coordinators RPR:	VYF
Responsible Party Name:	Not reported
Responsible Party Contact:	PATRICIA LAMBERT
Responsible Party Address:	PO BOX 711
Responsible Party City,St,Zip:	DALLAS, TX 75221 0711
Responsible Party Telephone:	972/341-8300
Reported Date:	07/20/1992
Case Start Date:	06/17/1997
Reference Number:	RN102057890
Project Manager:	VYF

7-ELEVEN 22245 (Continued) **U001243567**

UST:

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787044316
AI Number:	7144
Facility Type:	RETAIL
Facility Begin Date:	07/08/1986
Facility Status:	ACTIVE
Additional ID:	442439262002118
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PEGGIE BETZ,ENV COMP SPEC
Contact Organization Name:	7-ELEVEN 22245
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	442439262002118
Ai Number:	7144
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	442439262002118
AI Number:	7144
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46148
Cert ID:	381572
AI Number:	7144
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	364247
AI Number:	7144
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	348303
AI Number:	7144
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	331169
AI Number:	7144
Self Certification Date:	01/10/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	314253
AI Number:	7144
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	295930
AI Number:	7144
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	280576
AI Number:	7144
Self Certification Date:	01/18/2017
Signature Name/Title:	Raymond Mcniece Enironmental Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	263352
AI Number:	7144
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	246902
AI Number:	7144
Self Certification Date:	01/15/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	229603
AI Number:	7144
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46148
Cert ID:	27188
AI Number:	7144
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27187
AI Number:	7144
Self Certification Date:	12/15/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27186
AI Number:	7144
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27185
AI Number:	7144
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27184
AI Number:	7144
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27183
AI Number:	7144
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27182
AI Number:	7144
Self Certification Date:	12/19/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27181
AI Number:	7144
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27180
AI Number:	7144
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK GAS & ENV COMPL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27179
AI Number:	7144
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27178
AI Number:	7144
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27177
AI Number:	7144
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46148
Cert ID:	27176
AI Number:	7144
Self Certification Date:	01/17/2001
Signature Name/Title:	WILLOW A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

7-ELEVEN 22245 (Continued) **U001243567**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/04/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18517
Facility ID:	46148
Ai Number:	7144
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/04/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

7-ELEVEN 22245 (Continued) **U001243567**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	25981
UST ID:	18517
AI Number:	7144
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

7-ELEVEN 22245 (Continued) **U001243567**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/04/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18518
Facility ID:	46148
Ai Number:	7144
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/04/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

7-ELEVEN 22245 (Continued) **U001243567**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	25982
UST ID:	18518
AI Number:	7144
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/04/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1

7-ELEVEN 22245 (Continued) **U001243567**

Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18519
Facility ID:	46148
Ai Number:	7144
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/04/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

7-ELEVEN 22245 (Continued) **U001243567**

Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	25983
UST ID:	18519
AI Number:	7144
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	27050
Facility ID:	46148
AI Number:	7144
Application Received Date:	01/28/2015
Scheduled Construction Date:	03/02/2015
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N

7-ELEVEN 22245 (Continued) **U001243567**

UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL AND DISPOSAL OF THREE (3) 12,000 GALLON STEEL USTS; PIPING, VENTS AND DISPENSERS.

NOC ID:	2492
Facility ID:	46148
AI Number:	7144
Application Received Date:	04/04/2006
Scheduled Construction Date:	05/04/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60404012
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2491
Facility ID:	46148
AI Number:	7144
Application Received Date:	04/16/2003
Scheduled Construction Date:	05/12/2003
UST Improvement:	N
UST Installation:	Y

7-ELEVEN 22245 (Continued) **U001243567**

UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30416003
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2490
Facility ID:	46148
AI Number:	7144
Application Received Date:	12/01/2003
Scheduled Construction Date:	12/04/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M31201013
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2489
Facility ID:	46148
AI Number:	7144
Application Received Date:	12/29/2008
Scheduled Construction Date:	01/28/2009
UST Improvement:	Y

7-ELEVEN 22245 (Continued) **U001243567**

UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M81229012
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2488
Facility ID:	46148
AI Number:	7144
Application Received Date:	06/22/2000
Scheduled Construction Date:	07/10/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00622011
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	01/28/2015
Signature Date On Form:	01/22/2015
Signature Name On Form:	HOLLY M FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	63320
UST ID:	Not reported
NOC ID:	27050
AI Number:	7144

7-ELEVEN 22245 (Continued) **U001243567**

Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CB&I ENVIRONMENTAL & INFRASTRUCTURE INC
Representative Name:	HOLLY M FLAHERTY
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738413
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	7738400
Email Address:	Not reported

Cont/Cons/Installer ID:	2748
UST ID:	Not reported
NOC ID:	2490
AI Number:	7144
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001075
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2750
UST ID:	Not reported
NOC ID:	2492
AI Number:	7144
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	2747
UST ID:	Not reported
NOC ID:	2488
AI Number:	7144
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001306
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	2749
UST ID:	Not reported
NOC ID:	2491
AI Number:	7144
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Email Address: Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46148
Additional ID:	442439262002118
Princ ID:	959578622001257
AI Number:	7144
Facility Name:	7-ELEVEN 22245
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	798
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/13/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/18/2013
Date Routed by Supervisor:	03/18/2013
Date Routed to PSQA:	03/18/2013

7-ELEVEN 22245 (Continued) **U001243567**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	7-ELEVEN
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/28/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	278697
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	261545
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148

7-ELEVEN 22245 (Continued) **U001243567**

Finass ID:	242252
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	223515
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	224115
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN 22245 (Continued) **U001243567**

Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	207919
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	189228
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 22245 (Continued) **U001243567**

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	172738
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	154051
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	138240
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 22245 (Continued) **U001243567**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	120376
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	118164
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported

7-ELEVEN 22245 (Continued) **U001243567**

Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	1523
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	28478
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

7-ELEVEN 22245 (Continued) **U001243567**

Region:	2
Facility ID:	46148
Finass ID:	28479
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	28480
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	28481
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN 22245 (Continued) **U001243567**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	28482
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 22245
Address:	2103 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46148
Finass ID:	28483
AI:	7144
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901

7-ELEVEN 22245 (Continued) **U001243567**

Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: No

FK739 **SIGMOR SHAMROCK SERVICE STATION NO** **EDR Hist Auto** **1013761529**
Target **2105 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 6 of 13 in cluster FK

Actual: EDR Hist Auto
579 ft.

Focus Map:
14

Year:	Name:	Type:
1970	SIGMOR SERVICE INC NO 111 GAS	GASOLINE STATIONS
1975	SIGMOR SERVICE INC NO 111 GAS	GASOLINE STATIONS
1980	SIGMOR SHAMROCK SERVICE INC NO	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1990	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS

FK740 **TUCKER & RILEY GARAGE AUTO REPR** **EDR Hist Auto** **1013761841**
Target **2100 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 7 of 13 in cluster FK

Actual: EDR Hist Auto
579 ft.

Focus Map:
14

Year:	Name:	Type:
1947	TUCKER & RILEY GARAGE AUTO REPR	AUTOMOBILE REPAIRING

FK741 **BOHLS SERVICE STATION FILLING ST** **EDR Hist Auto** **1013753356**
Target **2109 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 8 of 13 in cluster FK

Actual: EDR Hist Auto
580 ft.

Focus Map:
14

Year:	Name:	Type:
1940	BOHLS SERVICE STATION FILLING S	GASOLINE AND OIL SERVICE STATIONS

---

742 **MAJESTIC CLEANERS** **EDR Hist Cleaner** **1013786156**
Target **2114 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

EDR Hist Cleaner

Actual:
582 ft.

Year:	Name:	Type:
1953	MAJESTIC CLEANERS	CLEANERS AND DYERS

Focus Map:
14

FL743 Target Property | **TOWN LAKE PLAZA SHOPPING CENTER**
1918 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX VCP** | **S111381297**
TX GCC | **N/A**

Site 1 of 8 in cluster FL

Actual: 472 ft.

Focus Map: 14

VCP TCEQ:

Name:	TOWN LAKE PLAZA SHOPPING CENTER
Address:	1918 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	REGION 11 - AUSTIN
Facility ID:	2113
VCP Record Date:	11/13/2007
Facility Type:	DRY CLEANER
PCA Number:	34308
Project Manager:	JBECKAGE
Phase:	COMPLETED
Acres at Site:	4.823
REM Program:	VCP
RN Number:	RN105377006
Former Facility Type:	Not reported
Site Address Description:	1900 BLOCK OF E RIVERSIDE BETWEEN ARENA DR AND TOWN CREEK DR
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	11/13/2007
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	08/17/2011
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	11/09/2007
GW Target COC Class:	CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2007-12-28 00:00:00
Soil Target COC Class:	Not reported
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2113
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	343080
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12; D/200-43N
Latitude:	30.24

TOWN LAKE PLAZA SHOPPING CENTER (Continued) **S111381297**

Longitude: -97.73

Contact:
REM Program: VCP
Program ID: 2113
RN Number: RN105377006
CN Number: CN603269689
CN Name: GRAYCO TOWN LAKE INVESTMENT 2007 LP
Role Code: APPLCONT
Contact Name: GRAY, JEFF
Contact Title: Not reported
Organization Name: GRAYCO TOWN LAKE INVESTMENT 2007 LP
Mailing Address: 55 WAUGH DR STE 500
Mailing City: HOUSTON
Mailing State: TX
Mailing Zip: 77007
Contact Telephone: (713) 426-2004
Contact Telephone Ext: 0

GCC:
Name: TOWN LAKE PLAZA SHOPPING CENTER
Address: 1918 E RIVERSIDE DR
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 2113
Contamination Description: CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/13/2007
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 2B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TOWN LAKE PLAZA SHOPPING CENTER
Address: 1918 E RIVERSIDE DR
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 2113
Contamination Description: CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/13/2007
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 2B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported

TOWN LAKE PLAZA SHOPPING CENTER (Continued) **S111381297**

Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

FL744 **TOWN LAKE PLAZA SHOPPING CENTER** **TX CENTRAL REGISTRY** **S126774824**
Target **1918 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 8 in cluster FL

Actual:
472 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN105377006
Name:	TOWN LAKE PLAZA SHOPPING CENTER
Address:	1918 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1323
Status:	ACTIVE
Status Date:	11/29/2007
Customer Number:	CN603269689
Customer Name:	GRAYCO TOWN LAKE INVESTMENT 2007 LP
Customer Legal Name:	Grayco Town Lake Investment 2007, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1900 BLOCK OF E RIVERSIDE BETWEEN ARENA DR AND TOWN CREEK DR

FL745 **TOWN LAKE PLAZA SHOPPING CENTER** **TX GCC** **S108962540**
Target **1918 EAST RIVERSIDE DRIVE** **N/A**
Property **AUSTIN, TX**

Site 3 of 8 in cluster FL

Actual:
472 ft.

Focus Map:
14

GCC:

Name:	TOWN LAKE PLAZA SHOPPING CENTER
Address:	1918 EAST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	2113
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/13/2007
Enforcement Status - Level Of Agency Response:	2B -
Enforcement Status - Site Activity Status:	2B -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

TOWN LAKE PLAZA SHOPPING CENTER (Continued) **S108962540**

Name:	TOWN LAKE PLAZA SHOPPING CENTER
Address:	1918 EAST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	2113
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/13/2007
Enforcement Status - Level Of Agency Response:	2B -
Enforcement Status - Site Activity Status:	2B -
Data Quality 1:	E
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

FL746 **SOUTHSHORE RETAIL** **TX CENTRAL REGISTRY** **S126863671**
Target **1920 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 4 of 8 in cluster FL

Actual:
473 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN107060923
Name:	SOUTHSHORE RETAIL
Address:	1920 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1342
Status:	ACTIVE
Status Date:	2014-01-03
Customer Number:	CN602575417
Customer Name:	ZAPALAC REED CONSTRUCTION CO LP
Customer Legal Name:	Zapalac/Reed Construction Co., L.P.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	2014-01-03
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FM747 **RILEYS LIVE OAK** **EDR Hist Auto** **1013769009**
Target **2121 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 1 of 3 in cluster FM

Actual:
587 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1929	WS 1 S LONE OAK FILLING STATION	GASOLINE AND OIL SERVICE STATIONS
1929	ES 3 S BECKER FILLING STATION	GASOLINE AND OIL SERVICE STATIONS
1929	ES 1 S SOUTH AUSTIN FILLING STA	GASOLINE AND OIL SERVICE STATIONS

RILEYS LIVE OAK (Continued) **1013769009**

1929	DUDLEY R D FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	RILEYS LIVE OAK	GASOLINE AND OIL SERVICE STATIONS

FM748 **JOHNSON T J FILL STA** **EDR Hist Auto** **1013775871**
Target **2201 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 3 in cluster FM

Actual: EDR Hist Auto
590 ft.

Focus Map:
14

Year:	Name:	Type:
1935	JOHNSON T J FILL STA	GASOLINE AND OIL SERVICE STATIONS

FN749 **HIGGINS AUTOMOTIVE** **EDR Hist Auto** **1013754255**
Target **2202 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 1 of 2 in cluster FN

Actual: EDR Hist Auto
591 ft.

Focus Map:
14

Year:	Name:	Type:
1953	HIGGINS AUTOMOTIVE	AUTOMOBILE REPAIRING

FO750 **RIVERSIDE TEXACO** **EDR Hist Auto** **1013773530**
Target **2000 RIVERSIDE DR E** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 10 in cluster FO

Actual: EDR Hist Auto
473 ft.

Focus Map:
14

Year:	Name:	Type:
1980	RIVERSIDE TEXACO	GASOLINE STATIONS
1984	RIVERTOWNE MALL RIVERSIDE TEXAC	GASOLINE STATIONS

FP751 **PLEASANT VALLEY & R** **TX CLI** **S103258975**
Target **SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.** **N/A**
Property **, TX**

Site 1 of 3 in cluster FP

Actual: CLI:
464 ft.

Focus Map:
15

Name:	PLEASANT VALLEY & R
Address:	SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported

PLEASANT VALLEY & R (Continued) **S103258975**

Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	2
Source Code:	Not reported
Date Opened:	**********
Date Closed:	**********
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	14.47
Long Deg:	97
Long Min:	43.36
Lat/Long (deg):	30.241167 / -97.722667
Owner:	Not reported
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	**********
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported

PLEASANT VALLEY & R (Continued) **S103258975**

Inspc Comments:	INIT INSP REVEALED EXCAVATN WORK IN PROCESS,2ND INSP WORK COMPL W VEGETATION
Comments:	???
Update:	0
Reviewer:	Not reported
Flag:	Not reported

FP752 **PLEASANT VALLEY & R** **TX CLI** **S118454928**
Target Property **SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.** **N/A**
TRAVIS (County), TX

Site 2 of 3 in cluster FP

Actual: 464 ft.
Focus Map: 15

CAPCOG LI:

Name:	PLEASANT VALLEY & R
Address:	SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	0
Date Close:	0
Unum:	1612
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	14.470000000000001
Longitude Deg:	97
Longitude Min:	43.359999999999999
Lat Dd:	30.241167000000001
Long Dd:	-97.722667000000001
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	2
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Michio Yamaguchi et al./ O'Reilley Auto Parts
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported

PLEASANT VALLEY & R (Continued) **S118454928**

A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	NO SUPPORTING DOCUMENTATION
Cog1:	12
Twc Dist:	0
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Inspection:	INIT INSP REVEALED EXCAVATN WORK IN PROCESS,2ND INSP WORK COMPL W VEGETATION
Comment:	???
Latitude:	30.24116667
Longitude:	-97.72266667
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=205

FP753 **PLEASANT VALLEY & R** **TX HIST LF** **S129373070**
Target **SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.** **N/A**
Property **TRAVIS (County), TX**

Site 3 of 3 in cluster FP

Actual:
464 ft.

Focus Map:
15

HIST LF:

Name:	PLEASANT VALLEY & R
Name 2:	Not reported
Address:	SW CORNER OF PLEASANT VALLEY RD. & RIVERSIDE DR.
City,State,Zip:	TX
Latitude:	30.241167
Longitude:	-97.722667
Lat Deg:	30
Lat MM:	14.47
Lon DD:	97
Lon MM:	43.36
UNUM:	1612
Comments:	???
Inspection:	INIT INSP REVEALED EXCAVATN WORK IN PROCESS,2ND INSP WORK COMPL W VEGETATION
COG Number:	12

PLEASANT VALLEY & R (Continued) **S129373070**

COOR CD:	Not reported
TWC District:	Not reported
Owner Name:	Not reported
Owner Code:	Not reported
Open Date:	0
Close Date:	0
Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	2

FN754 **KWIK WASH COIN LAUNDRIES NO** **EDR Hist Cleaner** **1013779407**
Target **2209 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 2 of 2 in cluster FN

Actual: 592 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1975	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1984	KWIK WASH COIN IAUNDRIES NO	LAUNDRIES-SELF SERVE
1990	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

FO755 **WALGREEN 2915** **RCRA-SQG** **1001128499**
Target **2020 E RIVERSIDE DR** **FINDS** **TXR000020263**
Property **AUSTIN, TX 78741** **ECHO**

Site 2 of 10 in cluster FO

Actual: 473 ft. RCRA Listings:

Focus Map: 14

Date Form Received by Agency:	20220301
Handler Name:	Walgreen 2915
Handler Address:	E RIVERSIDE DR

WALGREEN 2915 (Continued) **1001128499**

Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXR000020263
Contact Name:	ARIEL DAVILA
Contact Address:	E RIVERSIDE DR BLDG B
Contact City,State,Zip:	AUSTIN, TX 78741-1347
Contact Telephone:	512-326-5225
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2021
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	E RIVERSIDE DR BLDG B
Mailing City,State,Zip:	AUSTIN, TX 78741-1347
Owner Name:	Walgreen Co
Owner Type:	Private
Operator Name:	Walgreen Co
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230515

WALGREEN 2915 (Continued) **1001128499**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	P001
Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P075
Waste Description:	Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts
Waste Code:	U001
Waste Description:	Acetaldehyde (I) (Or) Ethanal (I)
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: QUALEX	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2408 REICHARD ST
Owner/Operator City,State,Zip:	DURHAM, NC 27705
Owner/Operator Telephone:	919-382-6592
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

WALGREEN 2915 (Continued) **1001128499**

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALGREEN CO	
Legal Status:	Not reported
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-326-5225
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20050105
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-326-5225
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741-1325
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20050105
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-326-5225
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741-1325
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

WALGREEN 2915 (Continued) **1001128499**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 20010726
Date Ended Current: Not reported
Owner/Operator Address: 2020 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78741-1325
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 20081215
Date Ended Current: Not reported
Owner/Operator Address: 2020 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-326-5225
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Not reported
Date Became Current: 20010726
Date Ended Current: Not reported
Owner/Operator Address: 2020 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-326-5225
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 20010726
Date Ended Current: Not reported
Owner/Operator Address: 2020 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78741-1325
Owner/Operator Telephone: 512-326-5225
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 20010726
Date Ended Current: Not reported
Owner/Operator Address: 2020 E RIVERSIDE DR

WALGREEN 2915 (Continued) **1001128499**

Owner/Operator City,State,Zip:	AUSTIN, TX 78741-1325
Owner/Operator Telephone:	512-326-5225
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741-1325
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20081215
Date Ended Current:	Not reported
Owner/Operator Address:	2020 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-326-5225
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20220301
Handler Name: WALGREEN 2915	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	19970311
Handler Name: WALGREENS NO 2915	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

WALGREEN 2915 (Continued) **1001128499**

Receive Date:	20010726
Handler Name: WALGREEN CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20050105
Handler Name: WALGREEN CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20081215
Handler Name: WALGREEN CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20220128
Handler Name: WALGREEN 2915	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220128
Handler Name: WALGREEN 2915	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

WALGREEN 2915 (Continued) **1001128499**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	456110
NAICS Description:	PHARMACIES AND DRUG RETAILERS

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

FINDS:

Registry ID: 110005176781

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001128499
Registry ID:	110005176781
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005176781
Name:	WALGREEN 2915
Address:	2020 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

FO756 Target Property | **WALGREENS**
2020 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX ASBESTOS**
TX Ind. Haz Waste | **S102763297**
N/A

Site 3 of 10 in cluster FO

Actual: 473 ft.

Focus Map: 14

ASBESTOS:

Name:	WALGREENS
Address:	2020 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/22/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

WALGREENS (Continued) **S102763297**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALGREENS
Address:	2020 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/16/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

WALGREENS (Continued) **S102763297**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	WALGREEN 2915
Address:	2020 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	85070
Registration Initial Notification Date:	01/24/1997
Registration Last Amendment Date:	01/28/2022
EPA Identification:	TXR000020263
Primary NAICS Code:	456110
Status Change Date:	19970124
Land Type:	PRIVATE
Description of Facility Site Location:	2020 E RIVERSIDE DR AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS

WALGREENS (Continued) **S102763297**

Company Name:	WALGREEN CO
Contact Name:	ARIEL DAVILA
Contact Telephone Number:	512-3265225
Mailing Address:	1920 E RIVERSIDE DR BLDG B
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787411347
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	105453
Site Owner Tax ID:	361924025
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220706
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	WALGREEN CO
Operator Address:	2020 E RIVERSIDE DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78741
Operator Country:	UNITED STA
Operator Telephone:	1-512-3265225
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13619240255
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	WALGREEN CO
Owner Mailing Address:	2020 E RIVERSIDE DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Country:	UNITED STA
Owner Telephone:	1-512-3265225
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13619240255
Owner Bankruptcy Code:	Not reported

WALGREENS (Continued) **S102763297**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	30
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Closed-head drums for haul-away service/disposal
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970124
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2020 E RIVERSIDE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3265225
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2020 E RIVERSIDE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3265225
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	ARIEL DAVILA
Contact Title:	STORE MANAGER
Contact Role:	PRICONT
Contact Address:	1920 E RIVERSIDE DR BLDG B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741

WALGREENS (Continued) **S102763297**

Contact Phone:	1-512-3265225
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	158868
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Photochemical waste (developer & fixer) from photo process
Standard Industrial Code:	73840
Primary Source:	G25
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812921
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	430316
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE AEROSOLS A
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430317

WALGREENS (Continued) **S102763297**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430318
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430319
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H

WALGREENS (Continued) **S102763297**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W005
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430321
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	208043
Texas Waste Code:	Not reported
Texas Waste Code 2:	0630319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spill debris. Waste generated from photo spill. Date of generation 1-3-2005.
Standard Industrial Code:	73840
Primary Source:	G08
Primary Measurement Point:	Not reported

WALGREENS (Continued) **S102763297**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812921
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	430322
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-3226522 x0
Mailing Address:	1920 E RIVERSIDE DR BLDG B
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000314032
Principal Name:	WALGREEN CO
Attention Name:	Not reported
Attention Suffix:	HWG

WALGREENS (Continued) **S102763297**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-3226522 x0
Mailing Address:	1920 E RIVERSIDE DR BLDG B
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000314032
Principal Name:	WALGREEN CO
Attention Name:	Not reported
Attention Suffix:	NWG

FO757 **WALGREENS 2915** **TX CENTRAL REGISTRY** **S126531619**
Target **2020 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 4 of 10 in cluster FO

Actual:
473 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	3/9/2002
Customer Number:	CN600306849
Customer Name:	QUALEX INC
Customer Legal Name:	Qualex Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	Not reported
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	3/9/2002
Customer Number:	CN600306849
Customer Name:	QUALEX INC
Customer Legal Name:	Qualex Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	Not reported
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR

WALGREENS 2915 (Continued) **S126531619**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	3/9/2002
Customer Number:	CN601476641
Customer Name:	WALGREEN CO
Customer Legal Name:	Walgreen Co.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/26/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	3/9/2002
Customer Number:	CN601476641
Customer Name:	WALGREEN CO
Customer Legal Name:	Walgreen Co.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/26/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	2002-03-09
Customer Number:	CN600306849
Customer Name:	QUALEX INC
Customer Legal Name:	Qualex Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	1800-01-01
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE

WALGREENS 2915 (Continued) **S126531619**

Status Date:	2002-03-09
Customer Number:	CN600306849
Customer Name:	QUALEX INC
Customer Legal Name:	Qualex Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	1800-01-01
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	2002-03-09
Customer Number:	CN600306849
Customer Name:	QUALEX INC
Customer Legal Name:	Qualex Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	1800-01-01
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	2002-03-09
Customer Number:	CN601476641
Customer Name:	WALGREEN CO
Customer Legal Name:	Walgreen Co.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2001-07-26
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	2002-03-09
Customer Number:	CN601476641
Customer Name:	WALGREEN CO

WALGREENS 2915 (Continued) **S126531619**

Customer Legal Name:	Walgreen Co.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2001-07-26
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Regulated Entity Number:	RN101623213
Name:	WALGREENS 2915
Address:	2020 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1325
Status:	ACTIVE
Status Date:	2002-03-09
Customer Number:	CN601476641
Customer Name:	WALGREEN CO
Customer Legal Name:	Walgreen Co.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2001-07-26
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	446110
Primary NAICS Industry Type Description:	Pharmacies and Drug Stores
Physical Location Description:	2020 E Riverside Dr, Austin, TX

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

FQ758 **BOHOT ENCO PRODUCTS GAS** **EDR Hist Auto** **1013761579**
Target **2300 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 1 of 16 in cluster FQ

Actual: **594 ft.** EDR Hist Auto

Focus Map: **14**

Year:	Name:	Type:
1965	BOHOT ENCO PRODUCTS GAS	GASOLINE STATIONS
1970	STONE BOB L ENCO PRODUCTS SERVI	GASOLINE STATIONS
1975	STONE BOB L EXXON PRODUCTS SERV	GASOLINE STATIONS
1980	STONE BOB L EXXON PRODUCTS SERV	GASOLINE STATIONS
1984	STONE BOB L EXXON PRODUCTS SERV	GASOLINE STATIONS
1990	STONE BOB TEXACO SERVICE STATIO	GASOLINE STATIONS

FQ759 **MASON BROS SERV** **EDR Hist Auto** **1013773135**
Target **2300 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 16 in cluster FQ

Actual: **594 ft.** EDR Hist Auto

Focus Map: **14**

Year:	Name:	Type:
1953	MASON BROS SERV	GASOLINE STATIONS

FQ760 **JOHNSON HUGO C** **EDR Hist Auto** **1013775855**
Target **2215 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 3 of 16 in cluster FQ

Actual: EDR Hist Auto
594 ft.

Focus Map:
14

Year:	Name:	Type:
1947	JOHNSON HUGO C FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	JOHNSON HUGO C	GASOLINE STATIONS
1958	LOWERYS TEXACO	GASOLINE STATIONS

FQ761 **JOHNSON HUGO SERV** **EDR Hist Auto** **1013755227**
Target **2215 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 4 of 16 in cluster FQ

Actual: EDR Hist Auto
594 ft.

Focus Map:
14

Year:	Name:	Type:
1940	JOHNSON HUGO SERV	GASOLINE AND OIL SERVICE STATIONS
1965	REGIENES TEXACO SERVICE	GASOLINE STATIONS
1970	RAMIREZ TEXACO & AUTOMOTIVE GAS	GASOLINE STATIONS
1975	RAMIREZ TEXACO & AUTOMOTIVE GAS	GASOLINE STATIONS

FQ762 **BROWN JACK CLEANERS** **EDR Hist Cleaner** **1013785349**
Target **2215 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 5 of 16 in cluster FQ

Actual: EDR Hist Cleaner
594 ft.

Focus Map:
14

Year:	Name:	Type:
1990	BROWN JACK CLEANERS	CLEANERS AND DYERS

FR763 **KENNETH A ROBERTSON JR** **TX UST** **U001266408**
Target **RIVERSIDE & BURTON** **N/A**
Property **AUSTIN, TX**

Site 1 of 3 in cluster FR

Actual: UST:
478 ft.

Focus Map:
14

Name:	KENNETH A ROBERTSON JR
Address:	RIVERSIDE & BURTON
City,State,Zip:	AUSTIN, TX
AI Number:	33252
Facility Type:	UNKNOWN
Facility Begin Date:	12/01/1986
Facility Status:	INACTIVE
Additional ID:	710058192002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

KENNETH A ROBERTSON JR (Continued) **U001266408**

Site Location Description:	RIVERSIDE & BURTON
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	KENNETH A ROBERTSON JR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7136210330
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	B T BATY,DIST. MGR.
Application Received Date On Earliest Reg Form:	05/05/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600124051
Owner Last Name:	MOTIVA ENTERPRISES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	504380502001134
Additional ID:	710058192002139
AI Number:	33252
Owner Effective Begin Date:	10/01/1998
State Tax ID:	17602624904
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/05/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87837

KENNETH A ROBERTSON JR (Continued) **U001266408**

Facility ID:	45210
Ai Number:	33252
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	06/30/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported

KENNETH A ROBERTSON JR (Continued) **U001266408**

UST Comprt ID:	22011
UST ID:	87837
AI Number:	33252
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/05/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87838
Facility ID:	45210
Ai Number:	33252
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	06/30/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

KENNETH A ROBERTSON JR (Continued) **U001266408**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	22012
UST ID:	87838
AI Number:	33252
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

KENNETH A ROBERTSON JR (Continued) **U001266408**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/05/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87839
Facility ID:	45210
Ai Number:	33252
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	06/30/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

KENNETH A ROBERTSON JR (Continued) **U001266408**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	22013
UST ID:	87839
AI Number:	33252
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

KENNETH A ROBERTSON JR (Continued) **U001266408**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MOTIVA ENTERPRISES LLC
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	45210
Additional ID:	710058192002139
Princ ID:	504380502001134
AI Number:	33252
Facility Name:	KENNETH A ROBERTSON JR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

FR764 **KENNETH A ROBERTSON JR** **FINDS** **1024183501**
Target **RIVERSIDE & BURTON** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 3 in cluster FR

Actual:
479 ft.

FINDS:
Registry ID: 110070168285

Focus Map:
14

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry

KENNETH A ROBERTSON JR (Continued) **1024183501**

(TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FS765 **EAST BOULDIN-EUCLID-WILSON STORM DRAIN IMPROVEMENT** **TX CENTRAL REGISTRY** **S126839291**
Target Property **2400-2600 EUCLID, 2404-2606 WILSON, 121-501 OLTORF ST, 2523-** **N/A**
AUSTIN, TX 78704

Site 1 of 2 in cluster FS

Actual: 588 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN106409998
Name:	EAST BOULDIN-EUCLID-WILSON STORM DRAIN IMPROVEMENTS
Address:	2400-2600 EUCLID, 2404-2606 WILSON, 121-501 OLTORF ST, 2523-2407 DURWOOD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704
Status:	ACTIVE
Status Date:	2012-05-16
Customer Number:	CN603953951
Customer Name:	MCLEAN PLUMBING HEATING AND AIR CONDITIONING COMPANY INC
Customer Legal Name:	MCLEAN PLUMBING, HEATING AND AIR CONDITIONING COMPANY, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-02-20
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	237110
Primary NAICS Industry Type Description:	Water and Sewer Line and Related Structures Construction
Physical Location Description:	2400-2600 EUCLID, 2404-2606 WILSON, 121-501 OLTORF ST, 2523-2407 DURWOOD

FS766 **TEJAS WATER HAULERS** **TX CENTRAL REGISTRY** **S126843224**
Target Property **2405 FOREST AVE** **N/A**
AUSTIN, TX 78704

Site 2 of 2 in cluster FS

Actual: 580 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN106489800
Name:	TEJAS WATER HAULERS
Address:	2405 FOREST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5521
Status:	ACTIVE
Status Date:	2012-08-14
Customer Number:	CN604125310
Customer Name:	LANTANA WATER LLC
Customer Legal Name:	Lantana Water LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-07-20
Affiliation End Date:	2018-01-23

TEJAS WATER HAULERS (Continued) **S126843224**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106489800
Name:	TEJAS WATER HAULERS
Address:	2405 FOREST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5521
Status:	ACTIVE
Status Date:	2012-08-14
Customer Number:	CN605461904
Customer Name:	H2ECO BULK LLC
Customer Legal Name:	H2Eco Bulk LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-01-24
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FT767 **ONE HOUR MARTINIZING NO** **EDR Hist Cleaner** **1013779105**
Target **2326 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 1 of 15 in cluster FT

Actual: EDR Hist Cleaner
597 ft.

Focus Map:
14

Year:	Name:	Type:
1970	ONE HOUR MARTINIZING	CLEANERS AND DYERS
1975	ONE HOUR MARTINIZING NO	CLEANERS AND DYERS
1980	ONE HOUR MARTINIZING NO	CLEANERS AND DYERS
1984	BROWN JACK CLEANERS	CLEANERS AND DYERS

FT768 **TWIN OAKS SERV STA** **EDR Hist Auto** **1013776891**
Target **2315 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 2 of 15 in cluster FT

Actual: EDR Hist Auto
596 ft.

Focus Map:
14

Year:	Name:	Type:
1958	TWIN OAKS SERV STA	GASOLINE STATIONS

FT769 Target Property — **TWIN OAKS GULF SERVICE GAS STA H**
2315 CONGRESS AVE S
AUSTIN, TX

EDR Hist Auto — **1013770810**
N/A

Site 3 of 15 in cluster FT

Actual: 596 ft. — EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1965	TWIN OAKS GULF SERVICE GAS STA	GASOLINE STATIONS

FT770 Target Property — **SOUTH AUSTIN CONOCO**
2332 S CONGRESS
AUSTIN, TX 78704

EDR Hist Auto — **1020859847**
N/A

Site 4 of 15 in cluster FT

Actual: 597 ft. — EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1969	SOUTH AUSTIN CONOCO	Gasoline Service Stations
1970	SOUTH AUSTIN CONOCO	Gasoline Service Stations
1971	SOUTH AUSTIN CONOCO	Gasoline Service Stations
1972	SOUTH AUSTIN CONOCO	Gasoline Service Stations

FT771 Target Property — **ES 3S MC ANGUS MILFORD**
2323 CONGRESS AVE S
SOUTH AUSTIN, TX

EDR Hist Auto — **1013769319**
N/A

Site 5 of 15 in cluster FT

Actual: 597 ft. — EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1935	ES 3S MC ANGUS MILFORD	GASOLINE AND OIL SERVICE STATIONS
1935	WS 8S MEADOWS J E FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	WS 12S MIDDLETON JOHN FILL	GASOLINE AND OIL SERVICE STATIONS
1935	WS IS LONE OAK FILLING STA	GASOLINE AND OIL SERVICE STATIONS

FT772 Target Property — **SOUTH AUSTIN CONOCO SERVICE STATION**
2336 CONGRESS AVE S
TRAVIS (County), TX 78704

EDR Hist Auto — **1013755389**
N/A

Site 6 of 15 in cluster FT

Actual: 597 ft. — EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1965	SOUTH AUSTIN CONOCO	GASOLINE STATIONS
1970	SOUTH AUSTIN CONOCO SERVICE STA	GASOLINE STATIONS

FT773 **S AUSTIN CONOCO** **EDR Hist Auto** **1013755270**
Target **2336 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 7 of 15 in cluster FT

Actual: EDR Hist Auto
597 ft.

Focus Map:
14

Year:	Name:	Type:
1958	S AUSTIN CONOCO	GASOLINE STATIONS

FT774 **INSPIRED MOVEMENT** **TX ASBESTOS** **S126247763**
Target **2311 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 8 of 15 in cluster FT

Actual: ASBESTOS:
596 ft.

Focus Map:
14

Name:	INSPIRED MOVEMENT
Address:	2311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported

INSPIRED MOVEMENT (Continued) **S126247763**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/28/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	51149
License Status Description:	Current
Expiration Date:	03/11/2025
Original Date:	03/12/2020
Rank Effective Date:	03/12/2020
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20824
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Fail
Inspection Number Grade:	Not reported

FT775 **FORMER SUBWAY** **TX ASBESTOS** **S126247545**
Target **2315 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 9 of 15 in cluster FT

Actual: 596 ft.

Focus Map: 14

ASBESTOS:

Name:	FORMER SUBWAY
Address:	2315 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

FORMER SUBWAY (Continued) **S126247545**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/28/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	51147
License Status Description:	Current
Expiration Date:	03/11/2025
Original Date:	03/12/2020
Rank Effective Date:	03/12/2020
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20822
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Fail
Inspection Number Grade:	Not reported

FT776 **TWIN OAKS SERV** **EDR Hist Auto** **1013773870**
Target **2315 CONGRESS AVE** **N/A**
Property **SOUTH AUSTIN, TX**

Site 10 of 15 in cluster FT

Actual: EDR Hist Auto
596 ft.

Focus Map: Year: Name: Type:
14 1962 TWIN OAKS SERV GASOLINE STATIONS

FU777 **TWIN OAKS MOBIL GAS STA** **EDR Hist Auto** **1013755639**
Target **2401 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX**

Site 1 of 13 in cluster FU

Actual:
602 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1965	TWIN OAKS MOBIL GAS STA	GASOLINE STATIONS
1970	TWIN OAKS MOBIL SERVICE STATION	GASOLINE STATIONS
1975	RINEYS SERVICE CENTER	AUTOMOBILE REPAIRING
1980	TWIN OAKS MOBIL GAS STATION	GASOLINE STATIONS
1984	TWIN OAKS MOBIL STATION	GASOLINE STATIONS

FU778 **ODAS JUNG** **TX HIST UST** **S111678764**
Target **104 E OLTORF ST** **N/A**
Property **AUSTIN, TX**

Site 2 of 13 in cluster FU

Actual:
602 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	ODAS JUNG
Address:	104 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0573
HID UST:	573
Inspection:	Not reported
Due:	06/01/2012

FV779 **METROPOLITAN APTS # 112** **TX ASBESTOS** **S122366645**
Target **2423 TOWN LAKE CIRCLE** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 3 in cluster FV

Actual:
469 ft.

Focus Map:
15

ASBESTOS:

Name:	METROPOLITAN APARTMENS
Address:	2423 TOWN LAKE CENTER
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	05/31/2019
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018000909
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

METROPOLITAN APTS # 112 (Continued) **S122366645**

Date Report Received:	02/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/06/2018
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	METROPOLITAN APTS # 112
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	DANA MITCHELL
Violation:	Not reported
Complaint Date:	10/03/2016

METROPOLITAN APTS # 112 (Continued) **S122366645**

Notification Number:	2016008335
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/04/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/03/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

METROPOLITAN APTS # 112 (Continued) **S122366645**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	METROPOLITAN APTS #209
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	09/07/2016
Notification Number:	2016007145
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/23/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/23/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/06/2016
Client Code:	Not reported

METROPOLITAN APTS # 112 (Continued) **S122366645**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FV780 **METROPOLITAN APARTMENTS** **TX ASBESTOS** **S121361638**
Target **2423 TOWN LAKE CENTER** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 3 in cluster FV

Actual:
469 ft.

Focus Map:
15

ASBESTOS:

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CENTER
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/16/2018
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009810
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

METROPOLITAN APARTMENTS (Continued) **S121361638**

Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/07/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CENTER
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/16/2018
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009810
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

METROPOLITAN APARTMENTS (Continued) **S121361638**

Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CENTER
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	09/05/2019
Reason for Inspection:	Gary Morgan
Violation:	Not reported

METROPOLITAN APARTMENTS (Continued) **S121361638**

Complaint Date:	12/28/2016
Notification Number:	2016010018
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/23/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/23/2016
Certification Statement Phone:	210-677-5549
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/27/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

METROPOLITAN APARTMENTS (Continued) **S121361638**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CENTER
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	09/05/2019
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	12/27/2016
Notification Number:	2016010018
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/13/2016
Certification Statement Phone:	210-677-5549
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/27/2016

METROPOLITAN APARTMENTS (Continued) **S121361638**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FV781 **METROPOLITAN APARTMENTS** **TX ASBESTOS** **S125392609**
Target **2423 TOWN LAKE CIRCLE** **N/A**
Property **AUSTIN, TX 78741**

Site 3 of 3 in cluster FV

Actual:
469 ft.

Focus Map:
15

ASBESTOS:

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/11/2022
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020003624
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

METROPOLITAN APARTMENTS (Continued) **S125392609**

Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2020
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/15/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021000410
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

METROPOLITAN APARTMENTS (Continued) **S125392609**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/21/2021
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Robert Bowman

METROPOLITAN APARTMENTS (Continued) **S125392609**

Violation:	Not reported
Complaint Date:	12/31/2023
Notification Number:	2022008994
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/27/2022
Certification Statement Phone:	5122561002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/10/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

METROPOLITAN APARTMENTS (Continued) **S125392609**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Cameron Cadenhead
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2022001680
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/09/2022
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

METROPOLITAN APARTMENTS (Continued) **S125392609**

Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	METROPOLITAN APARTMENTS
Address:	2423 TOWN LAKE CIRCLE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	10/01/2020
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019001370
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A

METROPOLITAN APARTMENTS (Continued) **S125392609**

Certification Statement Date:	02/08/2019
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FU782 **ACE MART RESTAURANT SUPPLY** **TX ASBESTOS** **S119137497**
Target **2415 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 3 of 13 in cluster FU

Actual:
604 ft.

Focus Map:
14

ASBESTOS:

Name:	ACE MART RESTAURANT SUPPLY
Address:	2415 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ

ACE MART RESTAURANT SUPPLY (Continued) **S119137497**

Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ACE MART RESTAURANT SUPPLY
Address:	2415 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/27/2014

ACE MART RESTAURANT SUPPLY (Continued) **S119137497**

Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

ACE MART RESTAURANT SUPPLY (Continued) **S119137497**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FW783 **THE JEWEL APARTMENTS** **TX ASBESTOS** **S121363017**
Target **1616 ROYAL CREST** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 2 in cluster FW

Actual:
527 ft.

Focus Map:
14

ASBESTOS:

Name:	THE JEWEL APARTMENTS
Address:	1616 ROYAL CREST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/16/2018
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009805
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/07/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1

THE JEWEL APARTMENTS (Continued) **S121363017**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	THE JEWEL APARTMENTS
Address:	1616 ROYAL CREST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/16/2018
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009805
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

THE JEWEL APARTMENTS (Continued) **S121363017**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	THE JEWEL APARTMENTS
Address:	1616 ROYAL CREST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	02/05/2018
Notification Number:	2018000484
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

THE JEWEL APARTMENTS (Continued) **S121363017**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/19/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/19/2018
Certification Statement Phone:	210-677-5549
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	THE JEWEL APARTMENTS
Address:	1616 ROYAL CREST
City,State,Zip:	AUSTIN, TX 78741

THE JEWEL APARTMENTS (Continued) **S121363017**

Date of inspection:	06/05/2019
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018000912
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/06/2018
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

THE JEWEL APARTMENTS (Continued) **S121363017**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FW784 **JEWEL APARTMENTS** **TX ASBESTOS** **S125392197**
Target **1616 ROYAL CREST DRIVE** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 2 in cluster FW

Actual:
527 ft.

Focus Map:
14

ASBESTOS:

Name:	JEWELL APARTMENTS
Address:	1616 ROYAL CREST DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John O Cannon
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2022000843
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/01/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/01/2022
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

JEWEL APARTMENTS (Continued) **S125392197**

ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/16/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	COBALT APARTMENTS
Address:	1616 ROYAL CREST DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002847
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/01/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

JEWEL APARTMENTS (Continued) **S125392197**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/01/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/16/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JEWEL APARTMENTS
Address:	1616 ROYAL CREST DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020003619
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

JEWEL APARTMENTS (Continued) **S125392197**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2020
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/05/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JEWELL APARTMENTS
Address:	1616 ROYAL CREST DRIVE

JEWEL APARTMENTS (Continued) **S125392197**

City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Robert Bowman
Violation:	Not reported
Complaint Date:	12/31/2023
Notification Number:	2022008995
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/27/2022
Certification Statement Phone:	5122561002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/10/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

JEWEL APARTMENTS (Continued) **S125392197**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	JEWEL APARTMENTS
Address:	1616 ROYAL CREST DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021000401
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/21/2021
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

JEWEL APARTMENTS (Continued) **S125392197**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	JEWEL APARTMENTS
Address:	1616 ROYAL CREST DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	10/08/2020
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019001375
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0

JEWEL APARTMENTS (Continued) **S125392197**

Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/08/2019
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

---

785 **DOT OPS** **1009635850**
Target Property **2515 WILSON ST** **N/A**
AUSTIN, TX 78701

Actual: 573 ft.

Focus Map: 14

DOT OPS:

Name:	Not reported
Address:	2515 WILSON ST
City,State,Zip:	AUSTIN, TX 78701

Natural Gas Distribution 1970 - 1984:

Operator ID:	18532
Operator Name:	SOUTHERN UNION GAS COMPANY

Click this hyperlink while viewing on your computer to access additional DOT OPS: detail in the EDR Site Report.

786 Target Property | **2501 SOUTH CONGRESS AVE.**
2501 SOUTH CONGRESS AVE.
AUSTIN, TX 78704 | **TX ASBESTOS** | **S119139112**
N/A

Actual: 614 ft.

Focus Map: 14

ASBESTOS:

Name:	2501 SOUTH CONGRESS AVE.
Address:	2501 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	01/06/2020
Notification Number:	2019009786
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/20/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/20/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

2501 SOUTH CONGRESS AVE. (Continued) **S119139112**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BANK/COUNTY OFFICE BLDG.
Address:	2501 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	12/17/2015
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2015008337
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	01/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	02/04/2016
Date Reviewed by PSQA:	2016-02-04 00:00:00
Date Routed by Supervisor1:	02/04/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported

2501 SOUTH CONGRESS AVE. (Continued) **S119139112**

ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FX787 **TX LEAD** **S128694134**
Target Property **2610 EUCLID AVE** **N/A**
AUSTIN, TX 78704

Site 1 of 2 in cluster FX

Actual: 581 ft.
Focus Map: 14

LEAD:

License Number:	200702248
Address:	2610 EUCLID AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	Region 7
Owner Name:	LOUIS LIMON JR RESIDENCE
Client Code:	1400
Client Name:	Environmental Facilities/Notification
Primary Name:	Not reported
DBA Name:	Not reported
Address Type:	Not reported
Mail Name:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State:	Not reported
Mail Zip:	Not reported
File Number:	31910
Expiration Date:	11/06/2007
Origination Date:	10/29/2007
Rank Effective Date:	02/22/2008
License Status Description:	Paid
Modifier Code:	LNOT
Area:	Area 09

(Continued) **S128694134**

Inspector:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	3538
Inspection End Date:	12/13/2007
Inspection Status:	Closed
Inspection Type Description:	Notified
Disposition:	0050 - Completed Complaint Open
Inspection Visit ID:	Not reported
Inspection Visit End Date:	Not reported
Visit Disposition:	Not reported
Inspection Discipline ID:	Not reported
Inspection Discipline Description:	Not reported
Inspection Class Description:	Environmental
Inspection Secondary Code:	L
Inspection Secondary Code Description:	Lead
Results:	UNKNOWN
Inspection Number Grade:	Not reported
Inspection Start Date:	Not reported
Board Name:	Not reported
License Type Code:	Not reported
Status Date:	Not reported
Rank Description:	Not reported
Entity Number ID:	Not reported

FY788 **SEMATECH CONSTRUCTION SITE** **ICIS** **1004600368**
Target **550 OLTORF ST E** **FINDS** **N/A**
Property **AUSTIN, TX 78701** **ECHO**

Site 1 of 4 in cluster FY

Actual:
577 ft.

Focus Map:
14

ICIS:

Enforcement Action ID:	06-1997-0161
FRS ID:	110010653550
Action Name:	A. G. BUILDING LTD. (TXR10X007)
Facility Name:	SEMATECH CONSTRUCTION SITE
Facility Address:	550 OLTORF ST E AUSTIN, TX 78701
Enforcement Action Type:	CWA 309 AO For Compliance (Old)
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	309
Facility SIC Code:	1542
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.237003
Longitude in Decimal Degrees:	-97.750374
Permit Type Desc:	Not reported
Program System Acronym:	23757
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	SEMATECH CONSTRUCTION SITE
Address:	550 OLTORF ST E
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	1542

SEMATECH CONSTRUCTION SITE (Continued) **1004600368**

FINDS:
Registry ID: 110010653550

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004600368
Registry ID:	110010653550
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110010653550
Name:	SEMATECH CONSTRUCTION SITE
Address:	550 OLTORF ST E
City,State,Zip:	AUSTIN, TX 78701

---

789 **OAKS APARTMENTS, AUSTIN** **TX SPILLS** **S107002623**
Target **OAKS APARTMENTS, AUSTIN** **N/A**
Property **AUSTIN, TX**

Actual: 593 ft.

Focus Map: 14

SPILLS:

Name:	OAKS APARTMENTS, AUSTIN
Address:	OAKS APARTMENTS, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	08/10/1992
Seq Num:	Not reported
Responsible Party Name:	OAKS APARTMENTS
Responsible Party Address:	Not reported
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	Not reported
Responsible Party Telephone:	5124417074
Substance:	PCB OIL - 5.4 PPM
Material Code:	2173
Media Affected:	Not reported
Permit Number:	0
District:	14
Origin:	001
Cause:	001
Basin Code:	0

OAKS APARTMENTS, AUSTIN (Continued) **S107002623**

Notify Date:	Not reported
Adequate Clean:	001
Classification:	006
Basin Name:	Not reported
Water Affected:	NONE
Amnt Spilled:	1 GAL
Amnt in Water:	0 GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	M. QUEREJAZU
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

FX790 **TX LEAD** **S128694136**
Target Property **2612 EUCLID AVE**
AUSTIN, TX 78704 **N/A**

Site 2 of 2 in cluster FX

Actual: 581 ft.

Focus Map: 14

LEAD:

License Number:	200702250
Address:	2612 EUCLID AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	Region 7
Owner Name:	LOUIS LIMON SR RESIDENCE
Client Code:	1400
Client Name:	Environmental Facilities/Notification
Primary Name:	Not reported
DBA Name:	Not reported
Address Type:	Not reported
Mail Name:	Not reported

(Continued) **S128694136**

Mail Address:	Not reported
Mail City:	Not reported
Mail State:	Not reported
Mail Zip:	Not reported
File Number:	31994
Expiration Date:	11/09/2007
Origination Date:	10/30/2007
Rank Effective Date:	01/07/2009
License Status Description:	Paid
Modifier Code:	LNOT
Area:	Area 09
Inspector:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	10106
Inspection End Date:	10/27/2008
Inspection Status:	Closed
Inspection Type Description:	Notified
Disposition:	0050 - Completed Complaint Open
Inspection Visit ID:	Not reported
Inspection Visit End Date:	Not reported
Visit Disposition:	Not reported
Inspection Discipline ID:	Not reported
Inspection Discipline Description:	Not reported
Inspection Class Description:	Environmental
Inspection Secondary Code:	L
Inspection Secondary Code Description:	Lead
Results:	UNKNOWN
Inspection Number Grade:	Not reported
Inspection Start Date:	Not reported
Board Name:	Not reported
License Type Code:	Not reported
Status Date:	Not reported
Rank Description:	Not reported
Entity Number ID:	Not reported

FZ791 **GARDNER BETTS JUVENILE JUSTICE CENTER** **TX CENTRAL REGISTRY** **S126603738**
Target **2515 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 1 of 4 in cluster FZ

Actual:
614 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN103059374
Name:	GARDNER BETTS JUVENILE JUSTICE CENTER
Address:	2515 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5513
Status:	ACTIVE
Status Date:	4/7/2003
Customer Number:	CN600338388
Customer Name:	TRAVIS COUNTY
Customer Legal Name:	Travis County
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	2/22/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

GARDNER BETTS JUVENILE JUSTICE CENTER (Continued) **S126603738**

Physical Location Description: Not reported

FZ792 Target Property | **GARDNER BETTS JUVENILLE JUSTICE CTR.**
2515 SOUTH CONGRESS AVENUE
AUSTIN, TX 78704 | **TX ASBESTOS** | **S119146669**
N/A

Site 2 of 4 in cluster FZ

Actual: 614 ft.

Focus Map: 14

ASBESTOS:

Name:	GARDNER BETTS JUVENILLE JUSTICE CTR.
Address:	2515 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	06/25/2014
Reason for Inspection:	Notified
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	201400337
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	EE
Seq:	01
Facility Type:	Mold
Inspector Name:	Emmanuel Enemkpali
Date Report Received:	07/14/2014
Date Routed by Supervisor:	07/16/2014
Date Routed to PSQA:	07/16/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

GARDNER BETTS JUVENILLE JUSTICE CTR. (Continued) **S119146669**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FZ793 **GARDNER BETTS JUVENILE JUSTICE CENTER** **TX UST** **U003566351**
Target **2515 S CONGRESS AVE** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78704**

Site 3 of 4 in cluster FZ

Actual:
614 ft.

Focus Map:
14

UST:

Name:	GARDNER BETTS JUVENILE JUSTICE CENTER
Address:	2515 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787045513
AI Number:	47174
Facility Type:	UNKNOWN
Facility Begin Date:	02/01/1989
Facility Status:	INACTIVE
Additional ID:	592535412003097
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	BILL BALES,
Contact Organization Name:	GARDNER BETTS JUVENILE JUSTICE CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124487000
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/10/1988
Signature Name/Title On Earliest Reg Form:	SAME,
Application Received Date On Earliest Reg Form:	02/01/1989
Signature Role On Earliest Reg Form:	Not reported

GARDNER BETTS JUVENILE JUSTICE CENTER (Continued) **U003566351**

Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600338388
Owner Last Name:	TRAVIS COUNTY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	178448372001300
Additional ID:	592535412003097
AI Number:	47174
Owner Effective Begin Date:	02/22/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	02/01/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	123192
Facility ID:	72699
Ai Number:	47174
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/09/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

GARDNER BETTS JUVENILE JUSTICE CENTER (Continued) **U003566351**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/23/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	104899
UST ID:	123192
AI Number:	47174
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

GARDNER BETTS JUVENILE JUSTICE CENTER (Continued) **U003566351**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRAVIS COUNTY
Contact Mailing Address (Delivery):	PO BOX 1748
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1748
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72699
Additional ID:	592535412003097
Princ ID:	178448372001300
AI Number:	47174
Facility Name:	GARDNER BETTS JUVENILE JUSTICE CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DAVE FOWLER/

HIST UST AUSTIN:

Name:	TRAVIS CNTY JUVENILE CNTR
Address:	2515 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3172
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GA794 **DRY CLEAN USA** **EDR Hist Cleaner** **1018876648**
Target **2410 E RIVERSIDE** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 4 in cluster GA

Actual:
489 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1987	DRY CLEAN USA	Drycleaning Plants, Except Rugs
1988	DRY CLEAN USA	Laundry And Garment Services, NEC
1989	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1990	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1991	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
1991	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1992	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
1992	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1993	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1993	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
1994	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
1994	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
1995	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
2003	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
2004	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC
2005	DRY CLEAN USA	Laundry And Garment Services, NEC, NEC

GA795 **RIVERSIDE PLACE SHOPPING CENTER** **FINDS** **1011931036**
Target **2410 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 4 in cluster GA

Actual:
489 ft.

Focus Map:
14

FINDS:
Registry ID: 110037527183

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GA796 **RIVERSIDE PLACE SHOPPING CENTER** **TX CENTRAL REGISTRY** **S126522775**
Target **2410 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 3 of 4 in cluster GA

Actual:
489 ft.

Focus Map:
14

CENTRAL REGISTRY:

Regulated Entity Number:	RN101475390
Name:	RIVERSIDE PLACE SHOPPING CENTER
Address:	2410 E RIVERSIDE DR
Address 2:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S126522775**

City,State,Zip:	AUSTIN, TX 78741-3083
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600767107
Customer Name:	DURHAM AND BASSETT REALTY GROUP INC
Customer Legal Name:	Durham and Bassett Realty Group Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2410 EAST RIVERSIDE DRIVE

Regulated Entity Number:	RN101475390
Name:	RIVERSIDE PLACE SHOPPING CENTER
Address:	2410 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3083
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600767107
Customer Name:	DURHAM AND BASSETT REALTY GROUP INC
Customer Legal Name:	Durham and Bassett Realty Group Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2410 EAST RIVERSIDE DRIVE

Regulated Entity Number:	RN101475390
Name:	RIVERSIDE PLACE SHOPPING CENTER
Address:	2410 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3083
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603035023
Customer Name:	DURHAM AND BASSETT REALTY GRP
Customer Legal Name:	Durham and Bassett Realty Grp
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2410 EAST RIVERSIDE DRIVE

Regulated Entity Number:	RN101475390
Name:	RIVERSIDE PLACE SHOPPING CENTER
Address:	2410 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3083
Status:	ACTIVE
Status Date:	##########

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S126522775**

Customer Number:	CN603035023
Customer Name:	DURHAM AND BASSETT REALTY GRP
Customer Legal Name:	Durham and Bassett Realty Grp
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2410 EAST RIVERSIDE DRIVE

GA797 **RIVERSIDE PLACE SHOPPING CENTER** **TX VCP** **S103864973**
Target **2410 E RIVERSIDE DR** **TX ASBESTOS** **N/A**
Property **AUSTIN, TX 78741**

Site 4 of 4 in cluster GA

Actual:
489 ft.

Focus Map:
14

VCP TCEQ:

Name:	RIVERSIDE PLACE SHOPPING CENTER
Address:	2410 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	REGION 11 - AUSTIN
Facility ID:	157
VCP Record Date:	12/29/1995
Facility Type:	DRY CLEANER
PCA Number:	38067
Project Manager:	DCOKER
Phase:	COMPLETED
Acres at Site:	13.6
REM Program:	VCP
RN Number:	RN101475390
Former Facility Type:	Not reported
Site Address Description:	2410 EAST RIVERSIDE DRIVE
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	01/09/1996
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	09/24/1996
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	EXCAVATION, REMOVAL TO OFF-SITE LANDFILL
Air Target COC Class:	Not reported
Date Cashier Check Received:	Not reported
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

Application Accepted?:	Y
Application Accepted Date:	1996-02-16 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	157
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	310670
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.24
Longitude:	-97.73

Contact:

REM Program:	VCP
Program ID:	157
RN Number:	RN101475390
CN Number:	CN600767107
CN Name:	DURHAM AND BASSETT REALTY GROUP INC
Role Code:	BILLCONT
Contact Name:	DURHAM, STEVE
Contact Title:	PRESIDENT
Organization Name:	DURHAM AND BASSETT REALTY GRP
Mailing Address:	PO BOX 684601
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78768
Contact Telephone:	(512) 833-6444
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	157
RN Number:	RN101475390
CN Number:	CN603035023
CN Name:	DURHAM AND BASSETT REALTY GRP
Role Code:	BILLCONT
Contact Name:	DURHAM, STEVE
Contact Title:	PRESIDENT
Organization Name:	DURHAM AND BASSETT REALTY GRP
Mailing Address:	PO BOX 684601
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78768
Contact Telephone:	(512) 833-6444
Contact Telephone Ext:	0

ASBESTOS:

Name:	NAILS AT LAST
Address:	2410 E RIVERSIDE DR #F2
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	11/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	No
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	1.5
Mileage:	10.7
Reg:	07
Init:	MAO
Seq:	01
Facility Type:	Tattooing
Inspector Name:	Margaret Olsovsky
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RENT A CENTER
Address:	2410 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/22/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.6
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RENT A CENTER
Address:	2410 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/16/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	NAILS AT LAST
Address:	2410 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	07/24/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Eddie Jackson
Date Report Received:	07/28/2014
Date Routed by Supervisor:	07/30/2014
Date Routed to PSQA:	07/31/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

RIVERSIDE PLACE SHOPPING CENTER (Continued) **S103864973**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FZ798 **KASSON BILL YAMAHA MOTORCYCLES SAS & SERV** **EDR Hist Auto** **1013766685**
Target **2603 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 4 of 4 in cluster FZ

Actual: EDR Hist Auto
611 ft.

Focus Map:
14

Year:	Name:	Type:
1990	KASSON BILL YAMAHA MOTORCYCLES	MOTORCYCLE DEALERS AND REPAIRERS

GB799 Target Property | **AUSTIN HICKORY 442 CO XP2995**
201 CUMBERLAND RD
AUSTIN, TX 78704 | **TX UST** | **U003841450**
TX HIST UST | **N/A**
TX Financial Assurance

Site 1 of 5 in cluster GB

Actual: 590 ft.

Focus Map: 14

UST:

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 787045413
AI Number:	19361
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	327651632002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	JULIANNA BROCK,
Contact Organization Name:	AUSTIN HICKORY 442 CO XP2995
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2547577700
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/09/2021
Signature Name/Title On Earliest Reg Form:	CLAY WYATT,OWNER
Application Received Date On Earliest Reg Form:	04/09/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	576368792017305
Additional ID:	327651632002150
Ai Number:	19361
Operator CN:	CN605433374
Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Operator Effective Begin Date:	09/24/2018
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	DERONICA LAMB/MANAGER EH&S ENVIRONMENTAL SERVICES
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75202-5315
Contact Phone Country Code:	1
Contact Phone Area Code:	214
Contact Phone Number:	7410464
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	DR1429@ATT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605433374
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75202
Contact Mailing Zip5:	5315
Contact Phone Number/Ext:	1 214 7410630/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MP0873@ATT.COM
Contact Address Deliverable:	Not reported
Princ ID:	576368792017305
Additional ID:	327651632002150
AI Number:	19361
Owner Effective Begin Date:	09/24/2018
State Tax ID:	14305297104
Contact Role:	OWNOPRCON
Contact Name/Title:	MICHAEL PERRY/AREA MANAGER, EH&S ENVIRONMENTAL SERVICE
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY

Self Certification:

Self Cert ID:	76478
Cert ID:	381325
AI Number:	19361
Self Certification Date:	01/10/2023
Signature Name/Title:	CAMERON SPARKS TANK PROGRAM MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76478
Cert ID:	362249
AI Number:	19361
Self Certification Date:	10/26/2021

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	Vyrl L Naumann EH&S Tank Manager
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76478
Cert ID:	345836
AI Number:	19361
Self Certification Date:	11/10/2020
Signature Name/Title:	Vyrl L Naumann Tank Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76478
Cert ID:	328672
AI Number:	19361
Self Certification Date:	10/24/2019
Signature Name/Title:	Vyrl L Naumann EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76478
Cert ID:	310215
AI Number:	19361
Self Certification Date:	09/20/2018

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	Rayshell T Wamsley Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	292804
AI Number:	19361
Self Certification Date:	09/13/2017
Signature Name/Title:	Jurandir Felipe-Ortega EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	277784
AI Number:	19361
Self Certification Date:	10/06/2016
Signature Name/Title:	Jurandir Felipe-Ortega EHS Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	266414
AI Number:	19361
Self Certification Date:	01/22/2016

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	JURANDIR FELIPE-ORTEGA EHS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	248699
AI Number:	19361
Self Certification Date:	02/12/2015
Signature Name/Title:	Lisa Espinosa EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	233844
AI Number:	19361
Self Certification Date:	03/19/2014
Signature Name/Title:	Lisa Espinosa Manager EH&S
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76478
Cert ID:	116385
AI Number:	19361
Self Certification Date:	03/28/2013

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	TAMEKA JACKSON EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116384
AI Number:	19361
Self Certification Date:	03/30/2012
Signature Name/Title:	ROBERT D PICKENS EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116383
AI Number:	19361
Self Certification Date:	03/23/2011
Signature Name/Title:	ROBERT D PICKENS SR ADMIN ENVIR HEALT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116382
AI Number:	19361
Self Certification Date:	03/30/2010

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	TAMEKA JACKSON MGR-EH&S
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116381
AI Number:	19361
Self Certification Date:	03/09/2009
Signature Name/Title:	MARK E DINUBILA ENVIRONMENTAL MANAGE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116380
AI Number:	19361
Self Certification Date:	03/05/2008
Signature Name/Title:	ROBERT D TAYLOR SOUTHWEST REGIONAL M
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116379
AI Number:	19361
Self Certification Date:	03/22/2007

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	ROBERT D TAYLOR ENVIRONMENTAL MANAGE
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116378
AI Number:	19361
Self Certification Date:	02/24/2006
Signature Name/Title:	CHERYL ALLEN ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116377
AI Number:	19361
Self Certification Date:	02/07/2005
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76478
Cert ID:	116376
AI Number:	19361
Self Certification Date:	01/21/2004

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76478
Cert ID:	116375
AI Number:	19361
Self Certification Date:	02/19/2003
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76478
Cert ID:	116374
AI Number:	19361
Self Certification Date:	06/03/2002
Signature Name/Title:	HARRY C HIXSON MGR ENV MGMT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	05/23/2002
Tank Registration Date:	06/10/2002
Number of Compartments:	1

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	200021
Facility ID:	76478
Ai Number:	19361
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	05/23/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Tank Tested Flag:	Y
Installation Signature Date:	05/29/2002

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	113884
UST ID:	200021
AI Number:	19361
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50084
Facility ID:	76478
Ai Number:	19361
Tank Id:	1A

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/18/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	1000
UST Comprt ID:	113883
UST ID:	50084
AI Number:	19361

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	38014
Facility ID:	76478
AI Number:	19361
Application Received Date:	04/09/2021
Scheduled Construction Date:	04/23/2021
UST Improvement:	Y
UST Installation:	N
UST Removal:	Y
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	SOUTHWESTERN BELL TELEPHONE COMPANY;SOUTHWESTERN BE
Owner CN At Time Of Construction:	CN602245615,CN602245615
Owner AR At Time Of Construction:	73410A,73410U
General Desc Of Prop Construct:	REQUESTING 30 DAY WAIVER - REPLACING SPILL BUCKET AND OVERFLOW PREVENTION VALVE

NOC ID:	11970
Facility ID:	76478
AI Number:	19361
Application Received Date:	08/30/2001
Scheduled Construction Date:	09/25/2001
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10830004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	90437
UST ID:	Not reported
NOC ID:	38014
AI Number:	19361
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TAIT ENVIRONMENTAL SERVICES
Representative Name:	BILLY BOB BATES
Mailing Address (Delivery):	1819 FIRMAN DR STE 115
Mailing Address (Internal Delivery):	Not reported
Mailing City:	RICHARDSON
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	30150
UST ID:	200021
NOC ID:	Not reported
AI Number:	19361
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001141
Company Name:	ERS Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	90438
UST ID:	Not reported
NOC ID:	38014
AI Number:	19361
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000189
Company Name:	CARBON ENVIRONMENTAL LLC
Representative Name:	Not reported
Mailing Address (Delivery):	661 E MAIN ST 200-254
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MIDLOTHIAN
Mailing State:	TX
Mailing Zip:	76065
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	6822440
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Cont/Cons/Installer ID:	12758
UST ID:	Not reported
NOC ID:	11970
AI Number:	19361
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001141
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	45314
UST ID:	200021
NOC ID:	Not reported
AI Number:	19361
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001048
Company Name:	Not reported
Representative Name:	TRUMAN COPE
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	90439
UST ID:	Not reported
NOC ID:	38014
AI Number:	19361
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	CLAY WYATT
Mailing Address (Delivery):	661 E MAIN ST 200-254

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	MIDLOTHIAN
Mailing State:	TX
Mailing Zip:	76065
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	6822440
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76478
Additional ID:	327651632002150
Princ ID:	576368792017305
AI Number:	19361
Facility Name:	AUSTIN HICKORY 442 CO XP2995
AR Number:	83091
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	VYRL NAUMANN/

HIST UST AUSTIN:

Name:	S W BELL - AUSTIN HICKORY "442" CENTRAL *
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX
Id UST:	3253
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	278452
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2022
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	0 800 7475256
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2024
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	251357
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2021
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	240527
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2019
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	203602
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2018
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	166477
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Facility ID:	76478
Finass ID:	185950
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	158154
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2015
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	9414
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	123487
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2013
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ50593
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60146
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60148
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60147
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2010
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60149
AI:	19361

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50514
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60150
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2008
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	9723041
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60151
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	04/09/2021

AUSTIN HICKORY 442 CO XP2995 (Continued) **U003841450**

Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 0 0
Policy Number:	1595289
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60152
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	Not reported
Policy Number:	1595289
Coverage Amount:	1000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	76478
Finass ID:	60153
AI:	19361
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	04/09/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GB800 Target Property | **AUSTIN HICKORY 442 CO - XP2995**
201 CUMBERLAND RD
AUSTIN, TX 78704 | **TX TIER 2** | **S108456169**
N/A

Site 2 of 5 in cluster GB

Actual: 590 ft.

Focus Map: 14

TIER 2:

Facility Id:	FA201145149ZXXXXXXXX
Facility Name:	AUSTIN HICKORY 442 CO - XP2995
Reporting Year:	2011
Facility Country:	USA
Facility Department:	AUSTIN HICKORY 442 CO - XP2995
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	02/06/2012
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	3
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0.000000
Longitude:	0.000000
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FA201045149ZXXXXXXXX
Facility Name:	AUSTIN HICKORY 442 CO - XP2995
Reporting Year:	2010
Facility Country:	USA
Facility Department:	AUSTIN HICKORY 442 CO - XP2995
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	01/05/2011
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	4
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0.000000
Longitude:	0.000000
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FA200945149ZXXXXXXXX/AUSTIN HICKORY 442 CO XP2995
Reporting Year:	2009
Facility Country:	USA
Facility Department:	AUSTIN HICKORY 442 CO - XP2995
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	01/06/2010
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	3
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0.000000
Longitude:	0.000000
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FA200845149ZXXXXXXXX
Facility Name:	AUSTIN HICKORY 442 CO - XP2995
Reporting Year:	2008
Facility Country:	USA
Facility Department:	AUSTIN HICKORY 442 CO - XP2995
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	02/20/2009
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	7
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0
Longitude:	0
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20063SBCIDXP2995/AT&T TELEPHONE FACILITY
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2/1/2007
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id:	FATR20053SBCIDXP2995
Facility Name:	SOUTHWESTERN BELL TELEPHONE FACILITY
Reporting Year:	2005
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	2/1/2006
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Jim Stehr
Latitude:	Not reported
Longitude:	Not reported

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes:	Not reported
Validation:	Not reported

Facility Info:

Id:	108024050
Id Type:	Dun & Bradstreet
Description:	other
Last Modified:	01/05/2011
Id:	4813
Id Type:	SIC
Description:	Unknown
Last Modified:	01/05/2011
Id:	517110
Id Type:	NAICS
Description:	Unknown
Last Modified:	01/05/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Alternate Contact
Contact Name:	EH&S Hotline
Title:	Alternative Contact (IMS/EPCRA)
Modification Date:	01/05/2011

Contact:

Contact Email:	rr4284@semail.att.com
Contact Mail Address:	4544 S LAMAR BLVD
Contact City/State/Zip:	AUSTIN, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	ROBERT ROHLF
Title:	Property Manager
Modification Date:	4/3/2011

Contact:

Contact Email:	lrragsdale@att.com
Contact Mail Address:	898 Marie Lane

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Contact City/State/Zip:	Conyers, GA 30094
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Lynn Ragsdale
Title:	EH&S Manager
Modification Date:	4/4/2011

Chemical Inventory:

Facility Id:	FA201045149ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA201045149Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045149Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA201045149Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	4/2/2011

Facility Id:	FA201045149ZXXXXXXXX
Chemical Name:	LEAD
Chemical Inv Record Id:	FA201045149Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045149Z31Z1ZZXX
Chemical Inventory Record Id:	FA201045149Z31ZXXXXX
Amt Of Sub Stored Or Transported:	156016
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	4/2/2011

Facility Id:	FA201045149ZXXXXXXXX
Chemical Name:	DIESEL FUEL #2 LOW SULFUR
Chemical Inv Record Id:	FA201045149Z70ZXXXXX
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	69858
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045149Z70Z63ZXX
Chemical Inventory Record Id:	FA201045149Z70ZXXXXX
Amt Of Sub Stored Or Transported:	714

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Amount Units: pounds
Type Of Storage: Tank inside building
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Engine Room - 1 st
Last Modified: 4/2/2011

Record Key: FA201045149Z70Z0ZZXX
Chemical Inventory Record Id: FA201045149Z70ZXXXXX
Amt Of Sub Stored Or Transported: 69144
Amount Units: pounds
Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 4/2/2011

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 108024050
Id Type: Dun & Bradstreet
Description: other
Last Modified: 01/06/2010
Id: 517110
Id Type: NAICS
Description: Unknown
Last Modified: 01/06/2010
Id: 4813
Id Type: SIC
Description: Unknown
Last Modified: 01/06/2010

Contact:
Contact Email: Not reported
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: Lynn Ragsdale
Title: EH&S Manager
Modification Date: 3/14/2010

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)
Modification Date: 1/6/2010

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Contact:

Contact Email:	Not reported
Contact Mail Address:	4544 S LAMAR BLVD
Contact City/State/Zip:	AUSTIN, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	ROBERT ROHLF
Title:	Property Manager
Modification Date:	3/14/2010

Chemical Inventory:

Facility Id:	FA200945149ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA200945149Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA200945149Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA200945149Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	3/13/2010

Facility Id:	FA200945149ZXXXXXXXX
Chemical Name:	LEAD
Chemical Inv Record Id:	FA200945149Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA200945149Z31Z1ZZXX
Chemical Inventory Record Id:	FA200945149Z31ZXXXXX
Amt Of Sub Stored Or Transported:	156016
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	3/13/2010

Facility Id:	FA200945149ZXXXXXXXX
Chemical Name:	DIESEL FUEL #2 LOW SULFUR
Chemical Inv Record Id:	FA200945149Z70ZXXXXX
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	69858
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/13/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Record Key: FA200945149Z70Z0ZZXX
Chemical Inventory Record Id: FA200945149Z70ZXXXXX
Amt Of Sub Stored Or Transported: 714
Amount Units: pounds
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 3/13/2010

Record Key: FA200945149Z70Z0ZZXX
Chemical Inventory Record Id: FA200945149Z70ZXXXXX
Amt Of Sub Stored Or Transported: 69144
Amount Units: pounds
Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 3/13/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:
Id: 108024050
Id Type: Dun & Bradstreet
Description: other
Last Modified: 02/06/2012
Id: 517110
Id Type: NAICS
Description: Unknown
Last Modified: 02/06/2012
Id: 4813
Id Type: SIC
Description: Unknown
Last Modified: 02/06/2012

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)
Modification Date: 02/06/2012

Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Modification Date: 02/06/2012

Contact:
Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Certifier
Contact Name: Lynn Ragsdale
Title: EH&S Manager
Modification Date: 02/06/2012

Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Certifier
Contact Name: Lynn Ragsdale
Title: EH&S Manager
Modification Date: 02/06/2012

Contact:
Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Certifier
Contact Name: Lynn Ragsdale
Title: EH&S Manager
Modification Date: 02/06/2012

Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Certifier
Contact Name: Lynn Ragsdale
Title: EH&S Manager
Modification Date: 02/06/2012

Contact:
Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: SWBT Texas, LLC
Title: Not reported
Modification Date: 2/14/2012

Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	SWBT Texas, LLC
Title:	Not reported
Modification Date:	2/14/2012

Contact:

Contact Email:	rr4284@us.att.com
Contact Mail Address:	4544 S LAMAR BLVD
Contact City/State/Zip:	AUSTIN, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	ROBERT ROHLF
Title:	Property Manager
Modification Date:	2/14/2012

Chemical Inventory:

Facility Id:	FA201145149ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA201145149Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/14/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201145149Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA201145149Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	2/14/2012

Facility Id:	FA201145149ZXXXXXXXX

AUSTIN HICKORY 442 CO - XP2995 (Continued) **S108456169**

Chemical Name:	LEAD
Chemical Inv Record Id:	FA201145149Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/14/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201145149Z31Z1ZZXX
Chemical Inventory Record Id:	FA201145149Z31ZXXXXX
Amt Of Sub Stored Or Transported:	156016
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	2/14/2012

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

Notes: Added from Chris Mach spreadsheet.

Validation: This facility passed all validation checks.

GB801 Target Property | **SOUTHWESTERN BELL TELEPHONE HICKORY**
201 CUMBERLAND RD
AUSTIN, TX | **TX LPST** | **S104958103**
N/A

Site 3 of 5 in cluster GB

Actual: 590 ft.
Focus Map: 14

LPST:

Name:	SOUTHWESTERN BELL TELEPHONE HICKORY
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX
Facility ID:	0019361
LPST Id:	105778
Facility Location:	201 CUMBERLAND DRIVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/30/1992
Entered Date:	01/29/1993
Reported Date:	09/30/1992
Closure Date:	07/13/1995
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	HARRY HIXSON
Responsible Party Address:	308 S AKARD ROOM 900
Responsible Party City,St,Zip:	DALLAS, TX 75202 5399
Responsible Party Telephone:	214/464-1805
Reported Date:	09/30/1992
Case Start Date:	07/13/1995
Reference Number:	RN102387115
Project Manager:	HWELCH

GB802 Target Property | **HICKORY 442 XP2995**
201 CUMBERLAND RD
AUSTIN, TX 78704 | **TX CENTRAL REGISTRY** | **S126577444**
N/A

Site 4 of 5 in cluster GB

Actual: 590 ft.
Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600261663
Customer Name:	SOUTHWESTERN BELL TELEPHONE LP
Customer Legal Name:	Southwestern Bell Telephone, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	11/30/2015
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

HICKORY 442 XP2995 (Continued) **S126577444**

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN602921132
Customer Name:	SOUTHWESTERN BELL TELEPHONE CO
Customer Legal Name:	Southwestern Bell Telephone, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN602245615
Customer Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Customer Legal Name:	Southwestern Bell Telephone Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/1/2015
Affiliation End Date:	9/23/2018
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN605433374
Customer Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Customer Legal Name:	Southwestern Bell Telephone Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/24/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD

HICKORY 442 XP2995 (Continued) **S126577444**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600261663
Customer Name:	SOUTHWESTERN BELL TELEPHONE LP
Customer Legal Name:	Southwestern Bell Telephone, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	11/30/2015
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN602921132
Customer Name:	SOUTHWESTERN BELL TELEPHONE CO
Customer Legal Name:	Southwestern Bell Telephone, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN602245615
Customer Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Customer Legal Name:	Southwestern Bell Telephone Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/1/2015
Affiliation End Date:	9/23/2018
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102387115
Name:	HICKORY 442 XP2995
Address:	201 CUMBERLAND RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5413
Status:	ACTIVE

HICKORY 442 XP2995 (Continued) **S126577444**

Status Date:	5/30/2002
Customer Number:	CN605433374
Customer Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Customer Legal Name:	Southwestern Bell Telephone Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/24/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

GB803 **AUSTIN HICKORY 442 CO XP2995** **TX AST** **A100276223**
Target **201 CUMBERLAND RD** **N/A**
Property **AUSTIN, TX 78704**

Site 5 of 5 in cluster GB

Actual:
590 ft.

Focus Map:
14

AST:

Name:	AUSTIN HICKORY 442 CO XP2995
Address:	201 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 787045413
Facility ID:	76478
Additional ID:	327651632002150
AI Number:	19361
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	Y
UST Financial Assurance Required:	N
Number of Active ASTs:	0
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78704
Contact Name/Title:	JULIANNA BROCK/
Contact Organization Name:	AUSTIN HICKORY 442 CO XP2995
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	2547577700
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	04/09/2021
Signature First Name on Earliest Reg Form:	CLAY
Application Received Date on Earliest Reg Form:	04/09/2021
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	WYATT
Signature Title on Earliest Reg Form:	OWNER
Signature Role on Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

AUSTIN HICKORY 442 CO XP2995 (Continued) **A100276223**

Enforcement Action Date: Not reported

Facility:

Facility ID:	76478
Tank ID:	1
AST ID:	176056
AI Number:	19361
Install Date:	09/01/1994
Tank Registration Date:	10/17/1995
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	08/09/2001
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

GC804 **SHOP N SAVE** **TX CENTRAL REGISTRY** **S126524321**
Target **2204 WOODLAND AVE** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 4 in cluster GC

Actual: 520 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN600784193
Customer Name:	QUSSAD, BASSAM
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE

SHOP N SAVE (Continued) **S126524321**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN601676885
Customer Name:	HNQ INC
Customer Legal Name:	HNQ, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	3/31/1999
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN601676885
Customer Name:	HNQ INC
Customer Legal Name:	HNQ, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/15/1994
Affiliation End Date:	5/31/2011
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN604064576
Customer Name:	WOODLAND GROCERS INC
Customer Legal Name:	Woodland Grocers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/1/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE

SHOP N SAVE (Continued) **S126524321**

Status Date:	2/23/2002
Customer Number:	CN600464648
Customer Name:	TMT INC
Customer Legal Name:	TMT, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN600784193
Customer Name:	QUSSAD, BASSAM
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN601676885
Customer Name:	HNQ INC
Customer Legal Name:	HNQ, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	3/31/1999
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN601676885
Customer Name:	HNQ INC

SHOP N SAVE (Continued) **S126524321**

Customer Legal Name:	HNQ, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/15/1994
Affiliation End Date:	5/31/2011
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN604064576
Customer Name:	WOODLAND GROCERS INC
Customer Legal Name:	Woodland Grocers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/1/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101499309
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-2965
Status:	ACTIVE
Status Date:	2/23/2002
Customer Number:	CN600464648
Customer Name:	TMT INC
Customer Legal Name:	TMT, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

GC805 Target Property

SHOP N SAVE
2204 WOODLAND AVE
AUSTIN, TX 78741

Site 2 of 4 in cluster GC

Actual: 520 ft.

Focus Map: 14

TX LPST **U001269006**
TX UST **N/A**
TX HIST UST
TX ASBESTOS
TX Financial Assurance
TX RDR

LPST:

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120177
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	04/14/2016
Entered Date:	03/15/2017
Reported Date:	04/14/2016
Closure Date:	03/16/2017
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	04/14/2016
Case Start Date:	03/16/2017
Reference Number:	RN101499309
Project Manager:	JROBINSO

UST:

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 787412965
AI Number:	36105
Facility Type:	RETAIL
Facility Begin Date:	01/01/1976
Facility Status:	INACTIVE
Additional ID:	4490462002054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	JAFFAR UMER,OFFICER
Contact Organization Name:	SHOP N SAVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

SHOP N SAVE (Continued) **U001269006**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124475052
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/26/2015
Signature Name/Title On Earliest Reg Form:	JAFFAR UMER,
Application Received Date On Earliest Reg Form:	03/27/2015
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	729350832012102
Additional ID:	4490462002054
Ai Number:	36105
Operator CN:	CN604064576
Operator Name:	WOODLAND GROCERS INC
Operator Effective Begin Date:	06/01/2011
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	JAFFAR UMER/PRES
Contact Organization Name:	WOODLAND GROCERS INC
Contact Mailing Address (Delivery):	2204 WOODLAND AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78741-2965
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4475052
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604064576
Owner Last Name:	WOODLAND GROCERS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	2204 WOODLAND AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78741
Contact Mailing Zip5:	2965
Contact Phone Number/Ext:	1 512 4475052/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	729350832012102
Additional ID:	4490462002054

SHOP N SAVE (Continued) **U001269006**

AI Number:	36105
Owner Effective Begin Date:	06/01/2011
State Tax ID:	32041699672
Contact Role:	OWNCON
Contact Name/Title:	JAFFAR UMER/PRES
Contact Organization Name:	WOODLAND GROCERS INC

Self Certification:

Self Cert ID:	89538
Cert ID:	251520
AI Number:	36105
Self Certification Date:	03/26/2015
Signature Name/Title:	JAFFAIR UMER OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	89538
Cert ID:	234784
AI Number:	36105
Self Certification Date:	03/31/2014
Signature Name/Title:	JAFFAIR UMER OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	89538
Cert ID:	218473
AI Number:	36105
Self Certification Date:	04/08/2013
Signature Name/Title:	JAFFAR UMER OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	89538
Cert ID:	143634
AI Number:	36105
Self Certification Date:	04/02/2012
Signature Name/Title:	JAFFAR UMER OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143633
AI Number:	36105
Self Certification Date:	03/31/2012
Signature Name/Title:	JAFFAR UMER OFFICER
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143632
AI Number:	36105
Self Certification Date:	03/15/2010
Signature Name/Title:	BASSAM QUSSAD PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143631
AI Number:	36105
Self Certification Date:	02/13/2009
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143630
AI Number:	36105
Self Certification Date:	02/07/2008
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143629
AI Number:	36105
Self Certification Date:	02/17/2007
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143628
AI Number:	36105
Self Certification Date:	01/30/2006
Signature Name/Title:	BASSAM QUASSAD PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143627
AI Number:	36105
Self Certification Date:	03/29/2005
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	OPERATOR
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143626
AI Number:	36105
Self Certification Date:	03/28/2005
Signature Name/Title:	BASSAM GUSSAD PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	89538
Cert ID:	143625
AI Number:	36105
Self Certification Date:	03/05/2004
Signature Name/Title:	BASSAM QUSSAN PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	89538
Cert ID:	143624
AI Number:	36105
Self Certification Date:	02/28/2003
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	89538
Cert ID:	143623
AI Number:	36105
Self Certification Date:	02/02/2002
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	89538
Cert ID:	143622
AI Number:	36105
Self Certification Date:	12/11/2000
Signature Name/Title:	BASSAM QUSSAD PRESIDENT
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	95512
Facility ID:	89538
Ai Number:	36105
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/2016
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

SHOP N SAVE (Continued) **U001269006**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	150848
UST ID:	95512
AI Number:	36105
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y

SHOP N SAVE (Continued) **U001269006**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	95513
Facility ID:	89538
Ai Number:	36105
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/2016
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

SHOP N SAVE (Continued) **U001269006**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	150849
UST ID:	95513
AI Number:	36105
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y

SHOP N SAVE (Continued) **U001269006**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	14410
Facility ID:	89538
AI Number:	36105
Application Received Date:	10/12/2012
Scheduled Construction Date:	11/12/2012
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	73174
General Desc Of Prop Construct:	INSTALL GRAPHITE ANODES AND RECERTIFY SYSTEM.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	15450
UST ID:	Not reported
NOC ID:	14410
AI Number:	36105
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113 REGAL ROW
Mailing Address (Internal Delivery):	STE A
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748

SHOP N SAVE (Continued) **U001269006**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	15451
UST ID:	Not reported
NOC ID:	14410
AI Number:	36105
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WOODLAND GROCERS INC
Contact Mailing Address (Delivery):	2204 WOODLAND AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 2965
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89538
Additional ID:	4490462002054
Princ ID:	729350832012102
AI Number:	36105
Facility Name:	SHOP N SAVE
AR Number:	73174
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	JAFFAR UMER/

HIST UST AUSTIN:

SHOP N SAVE (Continued) **U001269006**

Name:	SHOP-N-SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX
Id UST:	1871
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/20/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

SHOP N SAVE (Continued) **U001269006**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	2.4
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported

SHOP N SAVE (Continued) **U001269006**

Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	142591
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2015
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00091960
Coverage Amount:	1,000,000

SHOP N SAVE (Continued) **U001269006**

Coverage Expiration Date:	03/10/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	125962
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2014
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00087870
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/10/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	106899
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2013
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04-to-00083806
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/10/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538

SHOP N SAVE (Continued) **U001269006**

Finass ID:	9267
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2012
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00079952
Coverage Amount:	1000000
Coverage Expiration Date:	03/10/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	74995
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2010
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00073685
Coverage Amount:	1000000
Coverage Expiration Date:	03/10/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	74996
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SHOP N SAVE (Continued) **U001269006**

Financial Assurance Begin Date:	09/24/2007
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 9873373
Policy Number:	USC851083608
Coverage Amount:	1000000
Coverage Expiration Date:	09/24/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	89538
Finass ID:	74997
AI:	36105
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/27/2015
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	24253
Facility ID:	36105
RN:	Not reported
CN:	Not reported
Name:	SHOP N SAVE
Address:	2204 WOODLAND AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/6/2017
Due Date:	5/5/2017
Tank Owner:	WOODLAND GROCERS INC
Contact Person:	ALVIN MOMIN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	3/15/2017
Project Manager:	Jennifer Robinson
Team:	Team A
New LPST Number:	120177
Pre-Existing LPST Number:	Not reported
Comments:	RDR REC 12/12/16; DEF LTR SENT 2/3/17; TECH RESP REC 3/6/17;
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported

SHOP N SAVE (Continued) **U001269006**

Confirmed: Not reported
NOLPST Letter Date: Not reported
Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

GC806 **T M T INC** **EDR Hist Auto** **1020828917**
Target **2204 WOODLAND DR** **N/A**
Property **AUSTIN, TX 78741**

Site 3 of 4 in cluster GC

Actual:
520 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1985	T M T INC	Grocery Stores
1986	T M T INC	Grocery Stores
1987	T M T INC	Grocery Stores
1988	T M T INC	Grocery Stores
1989	T M T INC	Convenience Stores

GC807 **HNQ INC DBA SHOP N SAVE** **FINDS** **1010767070**
Target **2204 WOODLAND AVE** **N/A**
Property **AUSTIN, TX 78741**

Site 4 of 4 in cluster GC

Actual:
520 ft.

FINDS:
Registry ID: 110034034373

Focus Map:
14

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GD808 **HENDRICKS TOM AUTO BEAUTY SALON** **EDR Hist Auto** **1013757474**
Target **2701 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 1 of 5 in cluster GD

Actual:
623 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1975	HENDRICKS TOM AUTO BEAUTY SALON	AUTOMOBILE REPAIRING
1980	HENDRICKS TOM AUTO BEAUTY SALON	AUTOMOBILE REPAIRING

GD809 Target Property — **TWIN OAKS SHELL SERVICE**, **2704 CONGRESS AVE S**, **AUSTIN, TX** — **EDR Hist Auto** — **1013758697** / **N/A**

Site 2 of 5 in cluster GD

Actual: 622 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1965	TWIN OAKS SHELL SERVICE	GASOLINE STATIONS
1970	TWIN OAKS FINA SERVICE STATION	GASOLINE STATIONS

GD810 Target Property — **WHITTS SERV STA**, **2704 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013761876** / **N/A**

Site 3 of 5 in cluster GD

Actual: 622 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1953	WHITTS SERV STA	GASOLINE STATIONS
1958	WITTS SERV STA	GASOLINE STATIONS

GD811 Target Property — **SOULE MARK AUTOMOTIVE REPR**, **2716 CONGRESS AVE S**, **AUSTIN, TX 78704** — **EDR Hist Auto** — **1013758495** / **N/A**

Site 4 of 5 in cluster GD

Actual: 623 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1984	SOULE MARK AUTOMOTIVE REPR	AUTOMOBILE REPAIRING
1990	SPEEDWAY AUTO SUPVR	AUTOMOBILE REPAIRING

GE812 Target Property — **MCSPADDEN AUTOMOTIVE**, **2716 S CONGRESS AVE**, **AUSTIN, TX 78704** — **FINDS** — **1011329387** / **N/A**

Site 1 of 3 in cluster GE

Actual: 621 ft.
Focus Map: 14

FINDS:
Registry ID: 110034376084

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

MCSPADDEN AUTOMOTIVE (Continued) **1011329387**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GE813 **MCSPADDEN AUTOMOTIVE** **TX SPILLS** **S113437792**
Target **2716 SOUTH CONGRESS, AUSTIN, TX 78704** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 3 in cluster GE

Actual:
621 ft.

Focus Map:
14

SPILLS:

Name:	MCSPADDEN AUTOMOTIVE
Address:	2716 SOUTH CONGRESS, AUSTIN, TX 78704
City,State,Zip:	AUSTIN, TX 78704
Incident Number:	35694
Facility Id:	RN104146980
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	Not reported
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11 - AUSTIN
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	unknown
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	Not reported
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	No Incident Type
Near City Name:	AUSTIN
Importance Level:	1
Received Date:	03/02/2004
Start Date:	12/30/1899
Status Date:	04/05/2004
Media Name:	WASTE
Customer:	MCSPADDEN, RAYMOND
Effect:	ENVIRONMEN
Num Complaining:	1
Frequency:	CURRENT

MCSPADDEN AUTOMOTIVE (Continued) **S113437792**

Nature:	WATER
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Closed
Disputed Status:	Not reported
Disputed Date:	03/06/2004
Comments:	Employees at McSpadden Automotive are power-washing antifreeze onto the ground.
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

GF814 **OXFORD FINE CLEANERS** **EDR Hist Cleaner** **1020056623**
Target **4410 E RIVERSIDE DR 220** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 5 in cluster GF

Actual:
480 ft.

EDR Hist Cleaner

Focus Map:
15

Year:	Name:	Type:
1988	OXFORD FINE CLEANERS	Drycleaning Plants, Except Rugs

GG815 **KWIK WASH COIN LAUNDRIES** **EDR Hist Cleaner** **1013783361**
Target **3004 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78704**

Site 1 of 4 in cluster GG

Actual:
623 ft.

EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1975	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1984	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1990	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE

GG816 **ATX FOOD MART** **TX ASBESTOS** **S119138616**
Target **3002 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78704**

Site 2 of 4 in cluster GG

Actual:
621 ft.

Focus Map:
14

ASBESTOS:

Name:	ATX FOOD MART
Address:	3002 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported

ATX FOOD MART (Continued) **S119138616**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.6
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

ATX FOOD MART (Continued) **S119138616**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GG817 Target Property **STN ENTERPRISES INC**
3002 S CONGRESS AVE
AUSTIN, TX 78704

EDR Hist Auto **1021283671**
N/A

Site 3 of 4 in cluster GG

Actual: 621 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
2001	STN ENTERPRISES INC	Gasoline Service Stations
2002	STN ENTERPRISES INC	Gasoline Service Stations
2003	STN ENTERPRISES INC	Gasoline Service Stations
2004	STN ENTERPRISES INC	Gasoline Service Stations

GG818 Target Property **ST. JOSEPH HALL**
3001 CONGRESS AVE.
AUSTIN, TX 78704

TX ASBESTOS **S125923054**
N/A

Site 4 of 4 in cluster GG

Actual: 621 ft.

Focus Map: 14

ASBESTOS:

Name:	ST. JOSEPH HALL
Address:	3001 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/28/2020
Reason for Inspection:	Michael Medina
Violation:	Not reported
Complaint Date:	01/28/2020
Notification Number:	2019008801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

ST. JOSEPH HALL (Continued) **S125923054**

Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/27/2020
Certification Statement Phone:	915-422-0631
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	199
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. JOSEPH HALL
Address:	3001 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/28/2020
Reason for Inspection:	Michael Medina
Violation:	Not reported
Complaint Date:	01/31/2020
Notification Number:	2019008801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

ST. JOSEPH HALL (Continued) **S125923054**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/09/2020
Certification Statement Phone:	915-422-0631
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	199
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. JOSEPH HALL
Address:	3001 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/28/2020
Reason for Inspection:	Michael Medina

ST. JOSEPH HALL (Continued) **S125923054**

Violation:	Not reported
Complaint Date:	01/10/2020
Notification Number:	2019008801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/02/2019
Certification Statement Phone:	915-422-0631
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	199
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

ST. JOSEPH HALL (Continued) **S125923054**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. JOSEPH HALL
Address:	3001 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

ST. JOSEPH HALL (Continued) **S125923054**

Start Date:	01/28/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019008801
File Number:	47371
License Status Description:	Paid
Expiration Date:	01/28/2020
Original Date:	12/02/2019
Rank Effective Date:	12/02/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20705
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

---

819 Target Property **A ONE RADIATOR SERVICE**
3405 CONGRESS AVE S
AUSTIN, TX 78704
EDR Hist Auto **1013762036**
N/A

EDR Hist Auto

Actual: 625 ft.
Focus Map: 14

Year:	Name:	Type:
1984	A ONE RADIATOR SERVICE	AUTOMOBILE RADIATOR REPAIRERS
1990	A ONE RADIATOR SERVICE	AUTOMOBILE RADIATOR REPAIRERS

GH820 Target Property **FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN**
FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN
AUSTIN, TX
TX SPILLS **S106997486**
N/A

Site 1 of 2 in cluster GH

Actual: 496 ft.
Focus Map: 15

SPILLS:

Name:	FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN
Address:	FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	04/15/1991
Seq Num:	Not reported
Responsible Party Name:	FAIRWAY VILLAGE APTS
Responsible Party Address:	6118 FAIRWAY
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78741
Responsible Party Telephone:	5123852405

FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN (Continued) **S106997486**

Substance:	ORGANIC ACID
Material Code:	9000
Media Affected:	Not reported
Permit Number:	0
District:	14
Origin:	007
Cause:	003
Basin Code:	1428
Notify Date:	Not reported
Adequate Clean:	001
Classification:	005
Basin Name:	COLORADO RIVER
Water Affected:	NONE
Amnt Spilled:	15 GAL
Amnt in Water:	0 GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	S. JONES
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

GH821 Target Property | **FAIRWAY VILLAGE APTS** | **TX SPILLS 90** | **S112306947** **N/A**

AUSTIN, TX

Site 2 of 2 in cluster GH

Actual: 496 ft.

Focus Map: 15

Spills:

Status:	Not reported
Contact Name:	FAIRWAY VILLAGE APTS
Contact Phone:	5123852405
Site ID:	TXSP0415199116
Secondary ID:	Not reported
Cross Street:	FAIRWAY VILLAGE APTS., 6118 FAIRWAY, AUSTIN
County:	Not reported
Longitude:	0
Latitude:	0
Elevation:	Not reported

---

822 Target Property | **FAIRWAY VILLAGE APARTMENTS** | **TX ASBESTOS** | **S125391242** **N/A**

6118 FAIRWAY STREET
AUSTIN, TX 78741

Actual: 496 ft.

Focus Map: 15

ASBESTOS:

Name:	FAIRWAY VILLAGE APARTMENTS
Address:	6118 FAIRWAY STREET
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	JB Shilts on behalf of the Owner
Violation:	Not reported
Complaint Date:	06/20/2019
Notification Number:	2019004279
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/11/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/28/2019

FAIRWAY VILLAGE APARTMENTS (Continued) **S125391242**

Certification Statement Phone:	210-349-7242
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	06/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GI823 **VERDE APARTMENTS** **TX ASBESTOS** **S121363636**
Target **2310 WICKERSHAM DRIVE** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 2 in cluster GI

Actual:
505 ft.

Focus Map:
15

ASBESTOS:

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009802
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

VERDE APARTMENTS (Continued) **S121363636**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/07/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John Cannon

VERDE APARTMENTS (Continued) **S121363636**

Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009802
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-363-2815
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

VERDE APARTMENTS (Continued) **S121363636**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/05/2019
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018000911
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/06/2018
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

VERDE APARTMENTS (Continued) **S121363636**

Start Date:	02/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002845
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A

VERDE APARTMENTS (Continued) **S121363636**

Certification Statement Date:	09/06/2016
Certification Statement Phone:	817-595-0790
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002845
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

VERDE APARTMENTS (Continued) **S121363636**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/29/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM DRIVE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016002845
ASB Priority:	Not reported
PIF State:	Not reported

VERDE APARTMENTS (Continued) **S121363636**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/01/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/01/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

VERDE APARTMENTS (Continued) **S121363636**

Results:	Not reported
Inspection Number Grade:	Not reported

GI824 Target Property **VERDE APARTMENTS**
2310 WICKERSHAM LANE
AUSTIN, TX 78741

TX ASBESTOS **S125394824**
N/A

Site 2 of 2 in cluster GI

Actual: 505 ft.

Focus Map: 15

ASBESTOS:

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM LANE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/21/2022
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020003629
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2020
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported

VERDE APARTMENTS (Continued) **S125394824**

Analytical Method:	PLM
Start Date:	06/05/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM LANE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021000416
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original

VERDE APARTMENTS (Continued) **S125394824**

Work Type Flag:	A
Certification Statement Date:	01/21/2021
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM LANE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Cameron Cadenhead
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2022001682
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2022
Date Routed by Supervisor:	Not reported

VERDE APARTMENTS (Continued) **S125394824**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/09/2022
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VERDE APARTMENTS
Address:	2310 WICKERSHAM LANE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Paul Monin
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019001376
ASB Priority:	Not reported

VERDE APARTMENTS (Continued) **S125394824**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/08/2019
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/25/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

VERDE APARTMENTS (Continued) **S125394824**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GJ825 Target Property | **FAMILY DOLLAR #8248**
1508 MONTOPOLIS DR.
AUSTIN, TX 78701 | **RCRA-VSQG FINDS ECHO** | **1017789260 TXR000083077**

Site 1 of 2 in cluster GJ

Actual: 496 ft.

Focus Map: 15

RCRA Listings:

Date Form Received by Agency:	20150420
Handler Name:	Family Dollar #8248
Handler Address:	MONTOPOLIS DR.
Handler City,State,Zip:	AUSTIN, TX 78701-5268
EPA ID:	TXR000083077
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported
Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PROGRAM MGR., ENV. COMPLIANCE
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1017
Mailing City,State,Zip:	CHARLOTTE, NC 28201
Owner Name:	Thanh Do And Nga Nguyen
Owner Type:	Private
Operator Name:	Family Dollar Stores
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

FAMILY DOLLAR #8248 (Continued) **1017789260**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150424
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	U002

FAMILY DOLLAR #8248 (Continued) **1017789260**

Waste Description: 2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: THANH DO AND NGA NGUYEN
Legal Status: Private
Date Became Current: 20110511
Date Ended Current: Not reported
Owner/Operator Address: 12020 BLACK ANGUS DR.
Owner/Operator City,State,Zip: AUSTIN, TX 78727
Owner/Operator Telephone: 512-791-6573
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: FAMILY DOLLAR STORES
Legal Status: Private
Date Became Current: 20110310
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20150420
Handler Name: FAMILY DOLLAR #8248
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110064387015

FAMILY DOLLAR #8248 (Continued) **1017789260**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1017789260
Registry ID:	110064387015
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110064387015
Name:	FAMILY DOLLAR #8248
Address:	1508 MONTOPOLIS DR.
City,State,Zip:	AUSTIN, TX 78701

GJ826 **FAMILY DOLLAR** **TX ASBESTOS** **S119144999**
Target **1590 MONTOPOLIS DR** **N/A**
Property **AUSTIN, TX 78741**

Site 2 of 2 in cluster GJ

Actual: 497 ft.

Focus Map: 15

ASBESTOS:

Name:	FAMILY DOLLAR
Address:	1590 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/02/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/09/2013
Date Routed by Supervisor:	04/09/2013
Date Routed to PSQA:	04/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

FAMILY DOLLAR (Continued) **S119144999**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FAMILY DOLLAR
Address:	1590 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/24/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.1
Reg:	07
Init:	EJ

FAMILY DOLLAR (Continued) **S119144999**

Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GK827 Target Property | **SOUTH CONGRESS FOOD MART**
3602 S CONGRESS AVE
AUSTIN, TX 78704 | **TX ASBESTOS** | **S119157033**
N/A

Site 1 of 4 in cluster GK

Actual: 630 ft.

Focus Map: 14

ASBESTOS:

Name:	SOUTH CONGRESS FOOD MART
Address:	3602 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

SOUTH CONGRESS FOOD MART (Continued) **S119157033**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SOUTH CONGRESS FOOD MART
Address:	3602 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/20/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/24/2014
Date Routed by Supervisor:	03/24/2014
Date Routed to PSQA:	03/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

SOUTH CONGRESS FOOD MART (Continued) **S119157033**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GL828 **RIVERSIDE EAST TOWNHOMES** **TX CENTRAL REGISTRY** **S126782639**
Target **5701 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 3 in cluster GL

Actual:
508 ft.

Focus Map:
15

CENTRAL REGISTRY:

Regulated Entity Number:	RN105475172
Name:	RIVERSIDE EAST TOWNHOMES
Address:	5701 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-4801
Status:	ACTIVE
Status Date:	2008-03-11
Customer Number:	CN603331497
Customer Name:	PORTRAIT HOMES-RIVERSIDE TOWNHOMES LLC
Customer Legal Name:	Portrait Homes-Riverside Townhomes LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2008-03-02
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

GL829 Target Property | **RIVERSIDE EAST CONDOMINIUMS**
5701 EAST RIVERSIDE DRIVE AUSTIN TX 78741
AUSTIN, TX 78741 | **TX CENTRAL REGISTRY** | **S126844562**
N/A

Site 2 of 3 in cluster GL

Actual: 508 ft.
Focus Map: 15

CENTRAL REGISTRY:

Regulated Entity Number:	RN106512395
Name:	RIVERSIDE EAST CONDOMINIUMS
Address:	5701 EAST RIVERSIDE DRIVE AUSTIN TX 78741
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741
Status:	ACTIVE
Status Date:	2012-09-18
Customer Number:	CN604065508
Customer Name:	HANSEN CONTRACTING LLC
Customer Legal Name:	HANSEN CONTRACTING, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-08-20
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5701 EAST RIVERSIDE DRIVE AUSTIN TX 78741

GL830 Target Property | **RIVERSIDE EAST**
5701 EAST RIVERSIDE DRIVE
AUSTIN, TX 78741 | **TX CENTRAL REGISTRY** | **S126845556**
N/A

Site 3 of 3 in cluster GL

Actual: 508 ft.
Focus Map: 15

CENTRAL REGISTRY:

Regulated Entity Number:	RN106528912
Name:	RIVERSIDE EAST
Address:	5701 EAST RIVERSIDE DRIVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741
Status:	ACTIVE
Status Date:	2012-10-12
Customer Number:	CN603636176
Customer Name:	MILESTONE COMMUNITY BUILDERS LLC
Customer Legal Name:	Milestone Community Builders, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-09-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236115
Primary NAICS Industry Type Description:	New Single-Family Housing Construction (except Operative Builders)
Physical Location Description:	5701 EAST RIVERSIDE DRIVE

831 Target Property | **FAIRWAY COIN LAUNDRY**
1612 MONTOPOLIS DR
TRAVIS (County), TX 78741 | **EDR Hist Cleaner** | **1013784267**
N/A

EDR Hist Cleaner

Actual: 499 ft.
Focus Map: 15

Year:	Name:	Type:
1975	FAIRWAY COIN LAUNDRY	LAUNDRIES-SELF SERVE
1980	FAIRWAY COIN LAUNDRY	LAUNDRIES-SELF SERVE
1984	FAIRWAY COIN LAUNDRY	LAUNDRIES-SELF SERVE

GM832 Target Property | **SIGMOR SHAMROCK SERVICE STATION**
3630 CONGRESS AVE S
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013761515**
N/A

Site 1 of 6 in cluster GM

Actual: 632 ft.

EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1970	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1975	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1980	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1986	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1987	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1988	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1989	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1990	SIGINOR SHAMROCK SERVICE STATIO	GASOLINE STATIONS
1990	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1991	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1992	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1993	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1994	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1995	DIAMOND SHAMROCK INC	Gasoline Service Stations, NEC
1995	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1996	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Gasoline Service Stations, NEC
1997	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations, NEC
1997	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1998	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations, NEC
1998	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1999	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1999	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations, NEC
2000	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations, NEC
2000	NATIONAL CNVENIENCE STORES INC	Gasoline Service Stations
2001	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations, NEC
2001	NATIONAL CNVENIENCE STORES INC	Gasoline Service Stations
2002	NATIONAL CNVENIENCE STORES INC	Gasoline Service Stations
2002	VALERO ENERGY CORPORATION	Gasoline Service Stations, NEC
2003	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2004	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2005	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2006	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2007	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2008	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations, NEC
2011	VALERO ENERGY STATION	Gasoline Service Stations

GM833 Target Property | **MACHEN LEE SPECIAL AUTOMOTIVE**
3634 CONGRESS AVE S
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013754764**
N/A

Site 2 of 6 in cluster GM

Actual: 632 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1975	MACHEN LEE SPECIAL AUTOMOTIVE	AUTOMOBILE REPAIRING

GM834 Target Property | **DYE BILL AUTOMOTIVE AUTO REPR**
3716 CONGRESS AVE S
TRAVIS (County), TX 78704 | **EDR Hist Auto** | **1013759667**
N/A

Site 3 of 6 in cluster GM

Actual: 632 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1980	BURTS AUTOMOTIVE	AUTOMOBILE REPAIRING
1984	DYE BILL AUTOMOTIVE AUTO REPR	AUTOMOBILE REPAIRING
1990	DYE BILL AUTOMOTIVE AUTO REPR	AUTOMOBILE REPAIRING

GN835 Target Property | **GREYSTAR DEVELOPMENT SOCO LOFTS AND BELLA AT SOUTH**
3801 S CONGRESS AVE
AUSTIN, TX 78704 | **TX CENTRAL REGISTRY** | **S126752313**
N/A

Site 1 of 6 in cluster GN

Actual: 641 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN105058176
Name:	GREYSTAR DEVELOPMENT SOCO LOFTS AND BELLA AT SOUTH CONGRESS APARTM
Address:	3801 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8042
Status:	ACTIVE
Status Date:	2006-09-15
Customer Number:	CN603094111
Customer Name:	GREYSTAR DEVELOPMENT GROUP LP
Customer Legal Name:	Greystar Development Group, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2006-07-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105058176
Name:	GREYSTAR DEVELOPMENT SOCO LOFTS AND BELLA AT SOUTH CONGRESS APARTM
Address:	3801 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8042
Status:	ACTIVE
Status Date:	2006-09-15
Customer Number:	CN603094111
Customer Name:	GREYSTAR DEVELOPMENT GROUP LP

GREYSTAR DEVELOPMENT SOCO LOFTS AND BELLA AT SOUTH CONGRESS (Continued) **S126752313**

Customer Legal Name:	Greystar Development Group, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2006-07-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

GN836
Target Property

SOCO CLEANERS & ALTERATIONS
3801 S CONGRESS AVE STE 103
AUSTIN, TX 78704

TX CENTRAL REGISTRY **S126833003**
N/A

Site 2 of 6 in cluster GN

Actual: 641 ft.

Focus Map: 14

CENTRAL REGISTRY:

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN603981283
Customer Name:	NGA THU LAM
Customer Legal Name:	NGA THU LAM
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	4/15/2009
Affiliation End Date:	8/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN603981283
Customer Name:	NGA THU LAM
Customer Legal Name:	NGA THU LAM
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	4/15/2009
Affiliation End Date:	8/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE

SOCO CLEANERS & ALTERATIONS (Continued) **S126833003**

Status Date:	11/8/2011
Customer Number:	CN603981283
Customer Name:	NGA THU LAM
Customer Legal Name:	NGA THU LAM
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	4/15/2009
Affiliation End Date:	8/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN603981283
Customer Name:	NGA THU LAM
Customer Legal Name:	NGA THU LAM
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	4/15/2009
Affiliation End Date:	8/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN603981283
Customer Name:	NGA THU LAM
Customer Legal Name:	NGA THU LAM
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	4/15/2009
Affiliation End Date:	8/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN604578534
Customer Name:	SOCO CLEANERS ALTERATION LLC

SOCO CLEANERS & ALTERATIONS (Continued) **S126833003**

Customer Legal Name:	SOCO CLEANERS ALTERATION LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/13/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN604578534
Customer Name:	SOCO CLEANERS ALTERATION LLC
Customer Legal Name:	SOCO CLEANERS ALTERATION LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/13/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN604578534
Customer Name:	SOCO CLEANERS ALTERATION LLC
Customer Legal Name:	SOCO CLEANERS ALTERATION LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/13/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN604578534
Customer Name:	SOCO CLEANERS ALTERATION LLC
Customer Legal Name:	SOCO CLEANERS ALTERATION LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/13/2013

SOCO CLEANERS & ALTERATIONS (Continued) **S126833003**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN106265333
Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-8043
Status:	ACTIVE
Status Date:	11/8/2011
Customer Number:	CN604578534
Customer Name:	SOCO CLEANERS ALTERATION LLC
Customer Legal Name:	SOCO CLEANERS ALTERATION LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/13/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

GN837 **GREYSTAR DEVELOPMENT SOCO LOFTS AND BELLA AT SOUTH** **FINDS** **1010779279**
Target Property **3801 S CONGRESS AVE** **N/A**
AUSTIN, TX 78704

Site 3 of 6 in cluster GN

Actual: 641 ft.
Focus Map: 14

FINDS:
Registry ID: 110033847817

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GN838 Target Property | **SOCO CLEANERS & ALTERATIONS**
3801 S CONGRESS AVE STE 103
AUSTIN, TX 78704 | **TX DRYCLEANERS** | **S111990117**
N/A

Site 4 of 6 in cluster GN

Actual: 641 ft.

Focus Map: 14

DRYCLEANERS:

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	Not reported
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534

SOCO CLEANERS & ALTERATIONS (Continued) **S111990117**

DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	Not reported
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE

SOCO CLEANERS & ALTERATIONS (Continued) **S111990117**

Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	11

SOCO CLEANERS & ALTERATIONS (Continued) **S111990117**

CN Number:	CN603981283
DCR Number:	Not reported
AR Number:	24006412
Principal Name:	NGA THU LAM
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	SOCOCLEANERSALTERATIONS@GMAIL.COM
Phone Number:	512 9620048
Site Name:	SOCO CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	11
CN Number:	CN603981283
DCR Number:	Not reported
AR Number:	24006412
Principal Name:	NGA THU LAM
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	SOCOCLEANERSALTERATIONS@GMAIL.COM
Phone Number:	512 9620048
Site Name:	SOCO CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	11
CN Number:	CN603981283
DCR Number:	Not reported
AR Number:	24006412
Principal Name:	NGA THU LAM
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	SOCOCLEANERSALTERATIONS@GMAIL.COM
Phone Number:	512 9620048
Site Name:	SOCO CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION

SOCO CLEANERS & ALTERATIONS (Continued) **S111990117**

Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	11
CN Number:	CN603981283
DCR Number:	Not reported
AR Number:	24006412
Principal Name:	NGA THU LAM
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	SOCOCLEANERSALTERATIONS@GMAIL.COM
Phone Number:	512 9620048
Site Name:	SOCO CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333
Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SOCO CLEANERS & ALTERATIONS
Address:	3801 S CONGRESS AVE STE 103
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN106265333

SOCO CLEANERS & ALTERATIONS (Continued) **S111990117**

Region:	REGION 11 - AUSTIN
CN Number:	CN604578534
DCR Number:	DCR15402
AR Number:	24007063
Principal Name:	SOCO CLEANERS ALTERATION LLC
Bill Addr1:	3801 S CONGRESS AVE STE 103
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 8043
EMail:	TOM_HUU@YAHOO.COM
Phone Number:	512 4620048
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

GN839 **SOCO CLEANER & ALTER** **EDR Hist Cleaner** **1020090126**
Target Property **3801 S CONGRESS AVE** **N/A**
AUSTIN, TX 78704

Site 5 of 6 in cluster GN

Actual: 641 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
2009	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs
2010	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs
2011	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs
2012	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs
2013	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs
2014	SOCO CLEANER & ALTER	Drycleaning Plants, Except Rugs

GN840 **YOUNG TROY H GULF SERVICE** **EDR Hist Auto** **1013755762**
Target Property **3800 CONGRESS AVE S** **N/A**
AUSTIN, TX

Site 6 of 6 in cluster GN

Actual: 632 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1965	YOUNG TROY H GULF SERVICE	GASOLINE STATIONS

GO841 Target Property | **TWO-STORY OFFICE / RETAIL BLDG.**
3804 S. CONGRESS AVE.
AUSTIN, TX 78704 | **TX ASBESTOS** | **S119159481**
N/A

Site 1 of 4 in cluster GO

Actual: 633 ft.

Focus Map: 14

ASBESTOS:

Name:	TWO-STORY OFFICE / RETAIL BLDG.
Address:	3804 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/28/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013002083
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	03
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/29/2013
Date Routed by Supervisor:	05/14/2013
Date Routed to PSQA:	05/23/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

TWO-STORY OFFICE / RETAIL BLDG. (Continued) **S119159481**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GP842 **CONOCO FOOD MART** **TX ASBESTOS** **S126247255**
Target **6220 EAST RIVERSIDE** **N/A**
Property **AUSTIN, TX 78741**

Site 1 of 3 in cluster GP

Actual:
513 ft.

Focus Map:
15

ASBESTOS:

Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/06/10
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/10/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020003064
File Number:	52069
License Status Description:	Paid
Expiration Date:	06/20/2020
Original Date:	04/24/2020
Rank Effective Date:	04/24/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	22125
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	06/10/2020
Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Date Report Received:	05/29/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/29/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/08/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	06/20/2020

CONOCO FOOD MART (Continued) **S126247255**

Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/29/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	05/29/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/15/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	06/10/2020
Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/15/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/08/2020
Client Code:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	06/20/2020
Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	05/15/2020
Certification Statement Phone:	512-778-6800

CONOCO FOOD MART (Continued) **S126247255**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/15/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/20/2020
Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/24/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/24/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CONOCO FOOD MART
Address:	6220 EAST RIVERSIDE
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	06/10/2020
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	05/28/2020
Notification Number:	2020003064
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

CONOCO FOOD MART (Continued) **S126247255**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/24/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	04/24/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/21/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GP843 Target Property | **AURA RIVERSIDE**
6107 EAST RIVERSIDE DRIVER
AUSTIN, TX 78741 | **TX CENTRAL REGISTRY** | **S126926894**
N/A

Site 2 of 3 in cluster GP

Actual: 513 ft.
Focus Map: 15

CENTRAL REGISTRY:

Regulated Entity Number:	RN110035839
Name:	AURA RIVERSIDE
Address:	6107 EAST RIVERSIDE DRIVER
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-
Status:	ACTIVE
Status Date:	2017-11-16
Customer Number:	CN604133561
Customer Name:	TRINSIC RESIDENTIAL BUILDERS LLC
Customer Legal Name:	TRINSIC RESIDENTIAL BUILDERS LLC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2017-10-31
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

GP844 Target Property | **AURA RIVERSIDE**
6107 EAST RIVERSIDE DRIVER
AUSTIN, TX 78741 | **FINDS** | **1024450756**
ECHO | **N/A**

Site 3 of 3 in cluster GP

Actual: 513 ft.
Focus Map: 15

FINDS:

Registry ID: 110070377437

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024450756
Registry ID:	110070377437
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070377437
Name:	AURA RIVERSIDE
Address:	6107 EAST RIVERSIDE DRIVER
City,State,Zip:	AUSTIN, TX 78741

GO845 Target Property — **A A LOTUS AUTO CENTER ACCESS & PARTS RET**, **3822 CONGRESS AVE S**, **TRAVIS (County), TX 78704** — **EDR Hist Auto** — **1013765077**, **N/A**

Site 2 of 4 in cluster GO

Actual: 639 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1990	A A LOTUS AUTO CENTER ACCESS &	AUTOMOBILE REPAIRING

GQ846 Target Property — **CIRCLE K 2741300**, **6306 E RIVERSIDE**, **AUSTIN, TX** — **TX RDR** — **S127534600**, **N/A**

Site 1 of 15 in cluster GQ

Actual: 513 ft.
Focus Map: 15

RDR:

RDR ID:	29215
Facility ID:	48561
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K 2741300
Address:	6306 E RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/11/2021
Due Date:	4/12/2021
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	2/12/2021
Project Manager:	Frank Clayworth
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORG RDR RECD 12/7/20; Deficiency 1/14/2021
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GQ847 Target Property — **CIRCLE K 2741300**, **6306 RIVERSIDE DR**, **AUSTIN, TX** — **TX RDR** — **S127534601**, **N/A**

Site 2 of 15 in cluster GQ

Actual: 513 ft.
Focus Map: 15

RDR:

RDR ID:	28907
Facility ID:	48561
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K 2741300

CIRCLE K 2741300 (Continued) **S127534601**

Address:	6306 RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/26/2020
Due Date:	10/25/2020
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	10/22/2020
Project Manager:	Reagan Stephens
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GQ848 **CIRCLE K STORE 2741300** **TX CENTRAL REGISTRY** **S126576176**
Target **6306 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 3 of 15 in cluster GQ

Actual:
513 ft.

Focus Map:
15

CENTRAL REGISTRY:

Regulated Entity Number:	RN102372133
Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6614
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN602277386
Customer Name:	CST SERVICES LLC
Customer Legal Name:	CST Services LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/1/1990
Affiliation End Date:	3/17/2008
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102372133
Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6614
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN600557847
Customer Name:	CST SHAMROCK STATIONS INC
Customer Legal Name:	Cst Shamrock Stations, Inc.

CIRCLE K STORE 2741300 (Continued) **S126576176**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/18/2008
Affiliation End Date:	12/9/2010
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102372133
Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6614
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN601363500
Customer Name:	BIG DIAMOND INC
Customer Legal Name:	Big Diamond, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/18/2008
Affiliation End Date:	4/28/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102372133
Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6614
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN604312421
Customer Name:	BIG DIAMOND LLC
Customer Legal Name:	Big Diamond, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/29/2013
Affiliation End Date:	8/15/2021
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102372133
Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6614
Status:	ACTIVE
Status Date:	5/29/2002
Customer Number:	CN600134456
Customer Name:	CIRCLE K STORES INC
Customer Legal Name:	Circle K Stores Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/16/2021
Affiliation End Date:	12/31/3000

CIRCLE K STORE 2741300 (Continued) **S126576176**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

GQ849 **6306 EAST RIVERSIDE DRIVE** **HMIRS** **2005712962**
Target **6306 EAST RIVERSIDE DRIVE** **N/A**
Property **AUSTIN, TX**

Site 4 of 15 in cluster GQ

Actual:
513 ft.

Focus Map:
15

Click this hyperlink while viewing on your computer to access additional HMIRS detail in the EDR Site Report.

GQ850 **CIRCLE K STORE #2741300** **TX RDR** **S127534602**
Target **6306 RIVERSIDE DR** **N/A**
Property **AUSTIN, TX**

Site 5 of 15 in cluster GQ

Actual:
513 ft.

Focus Map:
15

RDR:

RDR ID:	29950
Facility ID:	48561
RN:	RN102372133
CN:	CN604312421
Name:	CIRCLE K STORE #2741300
Address:	6306 RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/16/2021
Due Date:	6/15/2021
Tank Owner:	CIRCLE K STORES INC
Contact Person:	KEVIN PAGSOLINGAN
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	6/15/2021
Project Manager:	Victor Lombeida
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GQ851 **VALERO CORNER STORE 1300** **FINDS** **1011386892**
Target **6306 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 6 of 15 in cluster GQ

Actual:
513 ft.

Focus Map:
15

FINDS:
Registry ID: 110035114275

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GQ852 **DIAMOND SHAMROCK REF & MKTG CO** **EDR Hist Auto** **1013753729**
Target **6306 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78741**

Site 7 of 15 in cluster GQ

Actual:
513 ft.

Focus Map:
15

EDR Hist Auto

Year:	Name:	Type:
1990	DIAMOND SHAMROCK	GASOLINE STATIONS
1991	STATION 1300	Gasoline Service Stations
1992	STATION 1300	Gasoline Service Stations
1993	STATION 1300	Gasoline Service Stations
1995	DIAMOND SHAMROCK INC	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Convenience Stores
1997	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
1998	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
1998	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
1999	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
1999	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
2000	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
2000	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
2001	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
2002	VALERO ENERGY CORPORATION	Convenience Stores
2003	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2004	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2005	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2006	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2007	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2008	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2009	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2010	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2011	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2011	VALERO ENERGY STATION	Gasoline Service Stations
2012	VALERO ENERGY STATION	Gasoline Service Stations
2012	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores
2013	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores

DIAMOND SHAMROCK REF & MKTG CO (Continued) **1013753729**

2013	VALERO ENERGY STATION	Gasoline Service Stations
2014	VALERO ENERGY STATION	Gasoline Service Stations
2014	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores

GQ853 **CIRCLE K STORE 2741300** **TX UST** **U003566356**
Target **6306 E RIVERSIDE DR** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78741** **TX ASBESTOS**
TX Financial Assurance

Site 8 of 15 in cluster GQ

Actual: 513 ft.

Focus Map: 15

UST:

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787416614
AI Number:	48561
Facility Type:	RETAIL
Facility Begin Date:	06/01/1989
Facility Status:	ACTIVE
Additional ID:	901785062002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/12/2019
Signature Name/Title On Earliest Reg Form:	VERONICA RIVERA,ENV SPC
Application Received Date On Earliest Reg Form:	08/13/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	658325792001221
Additional ID:	901785062002149
Ai Number:	48561
Operator CN:	CN600134456
Operator Name:	CIRCLE K STORES INC
Operator Effective Begin Date:	08/16/2021
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Contact Mailing City/State/Zip:	PHOENIX AZ 85072-2085
Contact Phone Country Code:	0
Contact Phone Area Code:	602
Contact Phone Number:	7288000
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600134456
Owner Last Name:	CIRCLE K STORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	PHOENIX
Contact Mailing State:	AZ
Contact Mailing Zip:	85072
Contact Mailing Zip5:	2085
Contact Phone Number/Ext:	0 602 7288000/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	658325792001221
Additional ID:	901785062002149
AI Number:	48561
Owner Effective Begin Date:	08/16/2021
State Tax ID:	17411495405
Contact Role:	OWNOPRCON
Contact Name/Title:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC

Self Certification:

Self Cert ID:	74704
Cert ID:	379051
AI Number:	48561
Self Certification Date:	09/29/2022
Signature Name/Title:	KELLIE BODDIE ENV. SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	360516
AI Number:	48561
Self Certification Date:	09/21/2021
Signature Name/Title:	KELLIE BODDIE ENVIRONMENTAL SPECIALIST
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	342490
AI Number:	48561
Self Certification Date:	09/02/2020
Signature Name/Title:	Veronica Rivera OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	327497
AI Number:	48561
Self Certification Date:	09/25/2019
Signature Name/Title:	Annette S Toale Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	310977
AI Number:	48561
Self Certification Date:	10/01/2018
Signature Name/Title:	Annette S Toale WC Enviro Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	292481
AI Number:	48561
Self Certification Date:	08/24/2017
Signature Name/Title:	JENNIFER RESNIK COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	276048
AI Number:	48561
Self Certification Date:	08/22/2016
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	257779
AI Number:	48561
Self Certification Date:	08/26/2015
Signature Name/Title:	JENNIFER RESNIK COMPLIANCE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	242827
AI Number:	48561
Self Certification Date:	08/29/2014
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	226328
AI Number:	48561
Self Certification Date:	09/04/2013
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74704
Cert ID:	105471
AI Number:	48561
Self Certification Date:	08/24/2012
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105470
AI Number:	48561
Self Certification Date:	08/24/2011
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105469
AI Number:	48561
Self Certification Date:	12/15/2010
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105468
AI Number:	48561
Self Certification Date:	08/24/2010
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105467
AI Number:	48561
Self Certification Date:	08/28/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105466
AI Number:	48561
Self Certification Date:	08/29/2008
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105223
AI Number:	48561
Self Certification Date:	03/20/2008
Signature Name/Title:	TERRY HANKINS O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105222
AI Number:	48561
Self Certification Date:	08/28/2007
Signature Name/Title:	KENT HAMEL COMPLIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105221
AI Number:	48561
Self Certification Date:	08/02/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105220
AI Number:	48561
Self Certification Date:	07/27/2005
Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105219
AI Number:	48561
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105218
AI Number:	48561
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105217
AI Number:	48561
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74704
Cert ID:	105216
AI Number:	48561
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/08/1989
Tank Registration Date:	06/05/1990
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	126292
Facility ID:	74704
Ai Number:	48561
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	06/08/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10088
UST Comprt ID:	106113
UST ID:	126292
AI Number:	48561
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/08/1989
Tank Registration Date:	06/05/1990
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	126293
Facility ID:	74704
Ai Number:	48561
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/08/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10088
UST Comprt ID:	106114
UST ID:	126293
AI Number:	48561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/08/1989
Tank Registration Date:	06/05/1990
Number of Compartments:	1
Tank Capacity:	10088
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	126291
Facility ID:	74704
Ai Number:	48561
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/08/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

CIRCLE K STORE 2741300 (Continued) **U003566356**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10088
UST Comprt ID:	106112
UST ID:	126291
AI Number:	48561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	11415
Facility ID:	74704
AI Number:	48561
Application Received Date:	01/28/2013
Scheduled Construction Date:	02/25/2013
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	68299
General Desc Of Prop Construct:	INSTALL NEW DOUBLE WALL SPILL BUCKETS AND UPGRADE SITE TO NESHAP COMPLIANCE.

NOC ID:	11414
Facility ID:	74704
AI Number:	48561
Application Received Date:	02/13/2013
Scheduled Construction Date:	03/16/2013
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	68299
General Desc Of Prop Construct:	REPLACE OLD DISPENSERS WITH NEW BLENDING DISPENSERS AND CONVERTING THE PLUS TANK INTO DIESEL.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	12230
UST ID:	Not reported
NOC ID:	11414
AI Number:	48561
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CST
Representative Name:	CHRIS TRINKLE
Mailing Address (Delivery):	ONE VALERO WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78269
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6454666
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	12232
UST ID:	Not reported
NOC ID:	11415
AI Number:	48561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113A REGAL ROW
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN

CIRCLE K STORE 2741300 (Continued) **U003566356**

Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	12229
UST ID:	Not reported
NOC ID:	11414
AI Number:	48561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PSI
Representative Name:	BOB BISSEN
Mailing Address (Delivery):	14833 BULVERDE RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78247
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6612489
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	12231
UST ID:	Not reported
NOC ID:	11414
AI Number:	48561
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	12233
UST ID:	Not reported
NOC ID:	11415
AI Number:	48561
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	3802 CORPOREX PARK DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TAMPA, FL 33619 1125
Phone Number/Ext:	984 3891316/0
Contact Fax Number/Ext:	/
Contact Email Address:	kboddie@circlek.com
Contact Address Deliverable:	Y
Facility ID:	74704
Additional ID:	901785062002149
Princ ID:	658325792001221
AI Number:	48561
Facility Name:	CIRCLE K STORE 2741300
AR Number:	82920
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	KELLIE BODDIE/ENVIRONMENTAL SPECIALIST

HIST UST AUSTIN:

Name:	CORNER STORE #1300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	3120
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

ASBESTOS:

Name:	VALERO
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CORNER STORE
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/23/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.6
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported

CIRCLE K STORE 2741300 (Continued) **U003566356**

Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	275426
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/11/2022
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 984 3891316
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/11/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704

CIRCLE K STORE 2741300 (Continued) **U003566356**

Finass ID:	257508
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/23/2020
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/27/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	220965
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/27/2019
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	204827
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

CIRCLE K STORE 2741300 (Continued) **U003566356**

Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	NAVIGATORS INS CO
Issuer Phone:	Not reported
Policy Number:	CH18ESP0BDKNONC
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	185549
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2017
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	168301
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/15/2016
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

CIRCLE K STORE 2741300 (Continued) **U003566356**

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	148892
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2015
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/09/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	133943
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/2014
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	116027
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

CIRCLE K STORE 2741300 (Continued) **U003566356**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2013
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	8026
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2012
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	59936
AI:	48561
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/16/2010
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000

CIRCLE K STORE 2741300 (Continued) **U003566356**

Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	12/16/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	59934
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	59937
AI:	48561
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

CIRCLE K STORE 2741300 (Continued) **U003566356**

Region:	2
Facility ID:	74704
Finass ID:	59935
AI:	48561
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	04/23/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	59938
AI:	48561
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2007
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	09/12/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2741300
Address:	6306 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74704
Finass ID:	59939
AI:	48561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

CIRCLE K STORE 2741300 (Continued) **U003566356**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	08/13/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GR854 **YOUNG TROY GULF** **EDR Hist Auto** **1013758834**
Target Property **3900 CONGRESS AVE S** **N/A**
SOUTH AUSTIN, TX

Site 1 of 4 in cluster GR

Actual: 657 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1958	YOUNG TROY GULF	GASOLINE STATIONS

GR855 **KAYO SERVICE STATION** **EDR Hist Auto** **1013763674**
Target Property **3903 CONGRESS AVE S** **N/A**
TRAVIS (County), TX 78704

Site 2 of 4 in cluster GR

Actual: 657 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1965	KAYO SERVICE STATION	GASOLINE STATIONS
1970	KAYO SERVICE STATION	GASOLINE STATIONS
1975	WALCO SERVICE STATION	GASOLINE STATIONS

GR856 **FINANCIAL RESOURCE MANAGEMENT** **TX HIST UST** **S128728984**
Target Property **3905 S CONGRESS AVE** **N/A**
AUSTIN, TX

Site 3 of 4 in cluster GR

Actual: 657 ft. HIST UST AUSTIN:

Focus Map: 14

Name:	FINANCIAL RESOURCE MANAGEMENT
Address:	3905 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0283
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

857 Target Property | **IDEA PUBLIC SCHOOLS VARGAS STREET PREP SCHOOL** | **TX CENTRAL REGISTRY** | **S126865723** | **N/A**
1909 VARGAS ROAD
AUSTIN, TX 78741

Actual: 508 ft.
Focus Map: 15

CENTRAL REGISTRY:

Regulated Entity Number:	RN107134686
Name:	IDEA PUBLIC SCHOOLS VARGAS STREET PREP SCHOOL
Address:	1909 VARGAS ROAD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-
Status:	ACTIVE
Status Date:	2014-02-27
Customer Number:	CN600530786
Customer Name:	JOERIS GENERAL CONTRACTORS LTD
Customer Legal Name:	Joeris General Contractors, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2014-02-27
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

GS858 Target Property | **REAR JOES GARAGE AUTO** | **EDR Hist Auto** | **1013759468** | **N/A**
4014 CONGRESS AVE S
SOUTH AUSTIN, TX

Site 1 of 6 in cluster GS

Actual: 665 ft.
Focus Map: 18

EDR Hist Auto

Year:	Name:	Type:
1958	REAR JOES GARAGE AUTO	AUTOMOBILE REPAIRING
1958	BOBS PHILLIPS	GASOLINE STATIONS

GT859 Target Property | **BERGSTROM AIRFORCE B** | **TX CLI** | **S103258977** | **N/A**
N AREA OF BASE CLOSE TO INTRX OF HWY 71 & HWY 183
, TX

Site 1 of 3 in cluster GT

Actual: 483 ft.
Focus Map: 20

CLI:

Name:	BERGSTROM AIRFORCE B
Address:	N AREA OF BASE CLOSE TO INTRX OF HWY 71 & HWY 183
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported

BERGSTROM AIRFORCE B (Continued) **S103258977**

Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	2
Source Code:	Not reported
Date Opened:	**********
Date Closed:	**********
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	13.31
Long Deg:	97
Long Min:	40.69
Lat/Long (deg):	30.221833 / -97.678167
Owner:	Not reported
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	**********
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported
Inspc Comments:	NO PI
Comments:	???
Update:	0
Reviewer:	Not reported
Flag:	Not reported

GT860 Target Property | **BERGSTROM AIRFORCE B**
N AREA OF BASE CLOSE TO INTRX OF HWY 71 & HWY 183
TRAVIS (County), TX | **TX HIST LF** | **S129373072**
N/A

Site 2 of 3 in cluster GT

Actual: 483 ft.

Focus Map: 20

HIST LF:

Name:	BERGSTROM AIRFORCE B
Name 2:	Not reported
Address:	N AREA OF BASE CLOSE TO INTRX OF HWY 71 & HWY 183
City,State,Zip:	TX
Latitude:	30.221833
Longitude:	-97.678167
Lat Deg:	30
Lat MM:	13.31
Lon DD:	97
Lon MM:	40.69
UNUM:	1614
Comments:	???
Inspection:	NO PI
COG Number:	12
COOR CD:	Not reported
TWC District:	Not reported
Owner Name:	Not reported
Owner Code:	Not reported
Open Date:	0
Close Date:	0
Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	2

GT861 Target Property | **BERGSTROM AIRFORCE B**
NORTH AREA OF FORMER BERGSTROM AFB, CLOSE TO INTERSECTION OF TRAVIS (County), TX | **TX CLI** | **S119135268** **N/A**

Site 3 of 3 in cluster GT

Actual: 483 ft.

Focus Map: 20

CAPCOG LI:

Name:	BERGSTROM AIRFORCE B
Address:	NORTH AREA OF FORMER BERGSTROM AFB, CLOSE TO INTERSECTION OF HWY 71 AND HWY 18
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	0
Date Close:	0
Unum:	1614
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	13.31
Longitude Deg:	97
Longitude Min:	40.689999999999998
Lat Dd:	30.221833
Long Dd:	-97.678167000000002
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	2
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Airport 71 Land Ltd
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	0
Size Acres:	0

BERGSTROM AIRFORCE B (Continued) **S119135268**

Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Inspection:	NO PI
Comment:	???
Latitude:	30.22183333
Longitude:	-97.67816667
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=237

GS862 **RUDYS CAFE** **EDR Hist Auto** **1013764335**
Target Property **4105 CONGRESS AVE S** **N/A**
SOUTH AUSTIN, TX

Site 2 of 6 in cluster GS

Actual: 666 ft. EDR Hist Auto

Focus Map: 18

Year:	Name:	Type:
1953	RUDYS CAFE	GASOLINE STATIONS

GU863 **SUNBECK AUTOMOTIVE** **TX CENTRAL REGISTRY** **S126559091**
Target Property **4139 S CONGRESS AVE** **N/A**
AUSTIN, TX 78745

Site 1 of 2 in cluster GU

Actual: 666 ft. CENTRAL REGISTRY:

Focus Map: 18

Regulated Entity Number:	RN102046869
Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1101
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN601110646
Customer Name:	SUNDBECK W C
Customer Legal Name:	W. C. Sundbeck
Customer Ownership Type:	ORGANIZATION

SUNBECK AUTOMOTIVE (Continued) **S126559091**

Affiliation Begin Date:	1/20/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102046869
Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1101
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN604444406
Customer Name:	SUNBECK W C
Customer Legal Name:	Sunbeck W C
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102046869
Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1101
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN601110646
Customer Name:	SUNDBECK W C
Customer Legal Name:	W. C. Sundbeck
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/20/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102046869
Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1101
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN604444406
Customer Name:	SUNBECK W C
Customer Legal Name:	Sunbeck W C
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

SUNBECK AUTOMOTIVE (Continued) **S126559091**

Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

GU864 Target Property | **SUNBECK AUTOMOTIVE**
4139 S CONGRESS AVE
AUSTIN, TX 78745 | **TX LPST** **U001294336**
TX UST **N/A**

Site 2 of 2 in cluster GU

Actual: 666 ft.

Focus Map: 18

LPST:

Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0063596
LPST Id:	105496
Facility Location:	4239 SOUTH CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/03/1992
Entered Date:	01/07/1993
Reported Date:	12/08/1992
Closure Date:	08/22/1996
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	HLN
Responsible Party Name:	Not reported
Responsible Party Contact:	AL HAYES
Responsible Party Address:	4608 RAMSEY
Responsible Party City,St,Zip:	AUSTIN, TX 78756
Responsible Party Telephone:	512/459-9713
Reported Date:	12/08/1992
Case Start Date:	08/22/1996
Reference Number:	RN102046869
Project Manager:	HLN

UST:

Name:	SUNBECK AUTOMOTIVE
Address:	4139 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451101
AI Number:	63596
Facility Type:	UNKNOWN
Facility Begin Date:	01/20/1993
Facility Status:	INACTIVE
Additional ID:	592083672002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

SUNBECK AUTOMOTIVE (Continued) **U001294336**

Site Location (Location Zip):	78756
Contact Name/Title:	W C SUNDRECK,
Contact Organization Name:	SUNBECK AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122424817
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/13/1992
Signature Name/Title On Earliest Reg Form:	W C SUNDRECK,
Application Received Date On Earliest Reg Form:	09/15/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601110646
Owner Last Name:	SUNDBECK W C
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	582083672002118
Additional ID:	592083672002118
AI Number:	63596
Owner Effective Begin Date:	01/20/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/15/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146701
Facility ID:	94510
Ai Number:	63596
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND

SUNBECK AUTOMOTIVE (Continued) **U001294336**

Tank Status Date:	11/25/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	151714
UST ID:	146701
AI Number:	63596
Compartment ID:	A

SUNBECK AUTOMOTIVE (Continued) **U001294336**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/15/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146702
Facility ID:	94510
Ai Number:	63596
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/25/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

SUNBECK AUTOMOTIVE (Continued) **U001294336**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	151715
UST ID:	146702
AI Number:	63596
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

SUNBECK AUTOMOTIVE (Continued) **U001294336**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SUNDBECK W C
Contact Mailing Address (Delivery):	4608 RAMSEY AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78756 3004
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94510
Additional ID:	592083672002118
Princ ID:	582083672002118
AI Number:	63596
Facility Name:	SUNBECK AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	W C SUNDBECK/

GV865 **GONZALEZ & LINDSEY PARKING EXPRESS** **FINDS** **1010764037**
Target Property **1600 E HIGHWAY 71** **N/A**
AUSTIN, TX 78742

Site 1 of 3 in cluster GV

Actual: 486 ft.
Focus Map: 20

FINDS:
Registry ID: 110034024428

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GV866 **PARKING SPOT PARKING IMPROVEMENTS** **FINDS** **1012099116**
Target Property **1600 E HIGHWAY 71** **N/A**
AUSTIN, TX 78742

Site 2 of 3 in cluster GV

Actual: 486 ft.
Focus Map: 20

FINDS:
Registry ID: 110038487367

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GV867 **GONZALEZ & LINDSEY PARKING EXPRESS** **TX CENTRAL REGISTRY** **S126758429**
Target Property **1600 E HIGHWAY 71** **N/A**
AUSTIN, TX 78742

Site 3 of 3 in cluster GV

Actual: 486 ft.
Focus Map: 20

CENTRAL REGISTRY:

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602499865

GONZALEZ & LINDSEY PARKING EXPRESS (Continued) **S126758429**

Customer Name:	GONZALEZ & LINDSEY LLC
Customer Legal Name:	Gonzalez & Lindsey LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2006-10-12
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602499865
Customer Name:	GONZALEZ & LINDSEY LLC
Customer Legal Name:	Gonzalez & Lindsey LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2006-10-12
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602499865
Customer Name:	GONZALEZ & LINDSEY LLC
Customer Legal Name:	Gonzalez & Lindsey LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2006-10-12
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602465874
Customer Name:	JOE BLAND CONSTRUCTION LP
Customer Legal Name:	Joe Bland Construction, L.P.
Customer Ownership Type:	PARTNERSHIP

GONZALEZ & LINDSEY PARKING EXPRESS (Continued) **S126758429**

Affiliation Begin Date:	2008-05-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602465874
Customer Name:	JOE BLAND CONSTRUCTION LP
Customer Legal Name:	Joe Bland Construction, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2008-05-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

Regulated Entity Number:	RN105142756
Name:	GONZALEZ & LINDSEY PARKING EXPRESS
Address:	1600 E HIGHWAY 71
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78742-2824
Status:	ACTIVE
Status Date:	2007-01-22
Customer Number:	CN602465874
Customer Name:	JOE BLAND CONSTRUCTION LP
Customer Legal Name:	Joe Bland Construction, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2008-05-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

GW868 **PIXELS & POWERTOOLS DBA DSN MFG** **TX CENTRAL REGISTRY** **S126942179**
Target **4201 S CONGRESS AVE STE 317** **N/A**
Property **AUSTIN, TX 78745**

Site 1 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

CENTRAL REGISTRY:

Regulated Entity Number:	RN110471497
Name:	PIXELS & POWERTOOLS DBA DSN MFG
Address:	4201 S CONGRESS AVE STE 317
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1171
Status:	ACTIVE
Status Date:	2018-08-09
Customer Number:	CN605557743

PIXELS & POWERTOOLS DBA DSN MFG (Continued) **S126942179**

Customer Name:	PIXELS & POWERTOOLS LLC
Customer Legal Name:	Pixels & Powertools LLC
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-09
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110471497
Name:	PIXELS & POWERTOOLS DBA DSN MFG
Address:	4201 S CONGRESS AVE STE 317
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1171
Status:	ACTIVE
Status Date:	2018-08-09
Customer Number:	CN605557743
Customer Name:	PIXELS & POWERTOOLS LLC
Customer Legal Name:	Pixels & Powertools LLC
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-09
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

GW869 Target Property **PIXELS & POWERTOOLS**
4201 S CONGRESS AVE STE 317
AUSTIN, TX 78745

FINDS **1011338811**
ECHO **N/A**

Site 2 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

FINDS:

Registry ID: 110070358633

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Registry ID: 110034494205

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations,

PIXELS & POWERTOOLS (Continued) **1011338811**

authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1011338811
Registry ID:	110070358633
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070358633
Name:	PIXELS & POWERTOOLS
Address:	4201 S CONGRESS AVE STE 317
City,State,Zip:	AUSTIN, TX 78745

GW870 **M C RIVER CITY AUTO** **TX CENTRAL REGISTRY** **S123843587**
Target **4201 S CONGRESS AVE STE 314** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

CENTRAL REGISTRY:

Regulated Entity Number:	RN100523067
Name:	M C RIVER CITY AUTO
Address:	4201 S CONGRESS AVE STE 314
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1171
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600243034
Customer Name:	M C RIVER CITY AUTO INC
Customer Legal Name:	M.C. River City Auto Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4201 S CONGRESS AVE 314

Regulated Entity Number:	RN100523067
Name:	M C RIVER CITY AUTO
Address:	4201 S CONGRESS AVE STE 314
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1171
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600243034
Customer Name:	M C RIVER CITY AUTO INC
Customer Legal Name:	M.C. River City Auto Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4201 S CONGRESS AVE 314

GW871 Target Property | **JOHNSTON SUPPLY WAREHOUSE**
4201 S. CONGRESS AVE., STE.# 323
AUSTIN, TX 78745 | **TX ASBESTOS** | **S119149008**
N/A

Site 4 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

ASBESTOS:

Name:	JOHNSTON SUPPLY WAREHOUSE
Address:	4201 S. CONGRESS AVE., STE.# 323
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	12/18/2012
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2012008985
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	01/22/2013
Date Routed by Supervisor:	01/28/2013
Date Routed to PSQA:	02/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

JOHNSTON SUPPLY WAREHOUSE (Continued) **S119149008**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GW872 **4201 S CONGRESS** **TX CENTRAL REGISTRY** **S123943301**
Target Property **4201 S CONGRESS** **N/A**
AUSTIN, TX 78701

Site 5 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

CENTRAL REGISTRY:

Regulated Entity Number:	RN102573276
Name:	4201 S CONGRESS
Address:	4201 S CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	6/12/2002
Customer Number:	CN600275408
Customer Name:	SOUTHSIDE COLLISION & PAINT
Customer Legal Name:	Southside Collision & Paint
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	4/2/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	4201 S CONGRESS

Regulated Entity Number:	RN102573276
Name:	4201 S CONGRESS
Address:	4201 S CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	6/12/2002
Customer Number:	CN600275408
Customer Name:	SOUTHSIDE COLLISION & PAINT
Customer Legal Name:	Southside Collision & Paint
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	4/2/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121

4201 S CONGRESS (Continued) **S123943301**

Primary NAICS Industry Type Description: Paint and Interior Repair and Maintenance
Physical Location Description: 4201 S CONGRESS

GW873 Target Property | **JOHNSTON SUPPLY WAREHOUSE**
4201 S. CONGRESS AVE., #323
AUSTIN, TX 78745 | **TX ASBESTOS** | **S119149007**
N/A

Site 6 of 9 in cluster GW

Actual: 667 ft.

Focus Map: 18

ASBESTOS:

Name:	JOHNSTON SUPPLY WAREHOUSE
Address:	4201 S. CONGRESS AVE., #323
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	01/14/2013
Reason for Inspection:	Complaint
Violation:	No
Complaint Date:	1/14/2013
Notification Number:	2012008985
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	02/13/2013
Date Routed by Supervisor:	02/22/2013
Date Routed to PSQA:	03/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

JOHNSTON SUPPLY WAREHOUSE (Continued) **S119149007**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GW874 **SUNDBECK GARAGE** **EDR Hist Auto** **1013761643**
Target **4220 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 7 of 9 in cluster GW

Actual:
667 ft.

Focus Map:
17

EDR Hist Auto

Year:	Name:	Type:
1953	SUNDBECK GARAGE	AUTOMOBILE REPAIRING
1958	SUNDBECK GARAGE	AUTOMOBILE REPAIRING

GX875 **SUNBECK AUTOMOTIVE** **TX HIST UST** **S128729011**
Target **4239 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX**

Site 1 of 5 in cluster GX

Actual:
666 ft.

Focus Map:
17

HIST UST AUSTIN:

Name:	SUNBECK AUTOMOTIVE
Address:	4239 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0365
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GY876 Target Property | **AMERICAN TREE**
4311 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126709362**
N/A

Site 1 of 10 in cluster GY

Actual: 662 ft.

Focus Map: 17

CENTRAL REGISTRY:

Regulated Entity Number:	RN104424833
Name:	AMERICAN TREE
Address:	4311 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1105
Status:	ACTIVE
Status Date:	10/19/2004
Customer Number:	CN602722167
Customer Name:	PAPERCRAFT CORP
Customer Legal Name:	Papercraft Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/23/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN104424833
Name:	AMERICAN TREE
Address:	4311 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1105
Status:	ACTIVE
Status Date:	10/19/2004
Customer Number:	CN602722167
Customer Name:	PAPERCRAFT CORP
Customer Legal Name:	Papercraft Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/23/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN104424833
Name:	AMERICAN TREE
Address:	4311 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1105
Status:	ACTIVE
Status Date:	10/19/2004
Customer Number:	CN602722167
Customer Name:	PAPERCRAFT CORP
Customer Legal Name:	Papercraft Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	5/23/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

AMERICAN TREE (Continued) **S126709362**

Physical Location Description: Not reported

GY877 Target Property **ABM MACHINERY**
4311 S. CONGRESS AVE.
AUSTIN, TX 78745

SEMS-ARCHIVE **1003875590**
TXD987989340

Site 2 of 10 in cluster GY

Actual: 662 ft.

Focus Map: 17

SEMS Archive:

Site ID:	0604118
EPA ID:	TXD987989340
Name:	ABM MACHINERY
Address:	4311 S. CONGRESS AVE.
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745
Cong District:	02
FIPS Code:	48453
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	06
Site ID:	0604118
EPA ID:	TXD987989340
Site Name:	ABM MACHINERY
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1998-01-09 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	06
Site ID:	0604118
EPA ID:	TXD987989340
Site Name:	ABM MACHINERY
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1991-10-18 04:00:00
Finish Date:	1991-10-18 04:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0604118
EPA ID:	TXD987989340
Site Name:	ABM MACHINERY
NPL:	N
FF:	N

ABM MACHINERY (Continued) **1003875590**

OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1997-08-15 04:00:00
Finish Date:	1998-01-06 05:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	06
Site ID:	0604118
EPA ID:	TXD987989340
Site Name:	ABM MACHINERY
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1990-04-01 05:00:00
Finish Date:	1990-04-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

GY878 Target Property — **AMERICAN TREE**, **4311 S CONGRESS AVE**, **AUSTIN, TX 78745**

TX LPST **U001284244**
TX UST **N/A**
TX HIST UST

Site 3 of 10 in cluster GY

Actual: 662 ft.

Focus Map: 17

LPST:

Name:	AMERICAN TREE
Address:	4311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0053804
LPST Id:	096195
Facility Location:	4311 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/05/1990
Entered Date:	07/19/1990
Reported Date:	06/05/1990
Closure Date:	09/24/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	JAMES KASHIN
Responsible Party Address:	PAPERCRAFT PARK
Responsible Party City,St,Zip:	PITTSBURGH, PA 15238
Responsible Party Telephone:	412/362-8000
Reported Date:	06/05/1990
Case Start Date:	09/24/1991

AMERICAN TREE (Continued) **U001284244**

Reference Number: RN104424833
Project Manager: HWELCH

UST:

Name:	AMERICAN TREE
Address:	4311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451105
AI Number:	53804
Facility Type:	UNKNOWN
Facility Begin Date:	05/23/1990
Facility Status:	INACTIVE
Additional ID:	900591822004293
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	AMERICAN TREE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	4123628000
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/27/1990
Signature Name/Title On Earliest Reg Form:	IRVING SPECTOR,VP
Application Received Date On Earliest Reg Form:	05/01/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602722167
Owner Last Name:	PAPERCRAFT CORP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	888591802004293
Additional ID:	900591822004293

AMERICAN TREE (Continued) **U001284244**

AI Number:	53804
Owner Effective Begin Date:	05/23/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/01/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	132305
Facility ID:	83615
Ai Number:	53804
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

AMERICAN TREE (Continued) **U001284244**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/02/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	127438
UST ID:	132305
AI Number:	53804
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AMERICAN TREE (Continued) **U001284244**

Facility Billing Contacts:

Contact Organization Name:	PAPERCRAFT CORP
Contact Mailing Address (Delivery):	PAPERCRAFT PARK
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PITTSBURGH, PA 15238
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	83615
Additional ID:	900591822004293
Princ ID:	888591802004293
AI Number:	53804
Facility Name:	AMERICAN TREE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	IRVING SPECTOR/

HIST UST AUSTIN:

Name:	AMERICAN TREE CO
Address:	4311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0135
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GY879 **THE CONGRESS LOFTS** **FINDS** **1027572793**
Target **4315 S CONGRESS AVE** **ECHO** **N/A**
Property **AUSTIN, TX 78745**

Site 4 of 10 in cluster GY

Actual:
661 ft.

Focus Map:
17

FINDS:
Registry ID: 110071347519

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1027572793
Registry ID:	110071347519
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071347519

THE CONGRESS LOFTS (Continued) **1027572793**

Name:	THE CONGRESS LOFTS
Address:	4315 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745

GZ880 Target Property | **BERGSTROM SUBSTATION**
1800 BASTROP HIGHWAY (SH 71)
AUSTIN, TX 78617 | **TX TIER 2** | **S110383611**
N/A

Site 1 of 2 in cluster GZ

Actual: 500 ft.

Focus Map: 20

TIER 2:

Facility Id/Name:	FATR200971DJEA027HXF/BERGSTROM SUBSTATION
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/22/2010
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	550
Number Of Employess On Site:	0
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Dan Smith
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4911
Id Type:	SIC
Description:	ELECTRICAL SERVICES
Last Modified:	2/19/2010
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/19/2010
Id:	221122
Id Type:	NAICS
Description:	Electric Power Distribution
Last Modified:	2/19/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	2412 Kramer Ln.

BERGSTROM SUBSTATION (Continued) **S110383611**

Contact City/State/Zip:	Austin, TX 78758
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Todd Henson
Title:	Substation Supt.
Modification Date:	3/14/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/22/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	2412 Kramer Ln
Contact City/State/Zip:	Austin, TX 78758
Contact Mail Country:	USA
Contact Type 1:	Manager
Contact Name:	Dan Smith
Title:	Facilities Coordinator
Modification Date:	1/26/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Jim Eldred
Title:	Env Prog Coord'r
Modification Date:	2/22/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	3/14/2010

Chemical Inventory:

Facility Id:	FATR200971DJEA027HXF
Chemical Name:	Sulfuric Acid (in batteries)

BERGSTROM SUBSTATION (Continued) **S110383611**

Chemical Inv Record Id:	CVTR200971DJEA02GHZ9
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	14
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/14/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971DJEA02HHZR
Chemical Inventory Record Id:	CVTR200971DJEA02GHZ9
Amt Of Sub Stored Or Transported:	54
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	in batteries in substation maint building
Last Modified:	3/14/2010

Notes: Not reported

Validation: This facility passed all validation checks.

GZ881 **BERGSTROM SUBSTATION** **TX TIER 2** **S111046779**
Target **1800 BASTROP HIGHWAY (SH 71)** **N/A**
Property **AUSTIN, TX 78617**

Site 2 of 2 in cluster GZ

Actual: 500 ft.
Focus Map: 20

TIER 2:

Facility Id/Name:	FATR201071DJEA027HXF/BERGSTROM SUBSTATION
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	02/25/2011
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported

BERGSTROM SUBSTATION (Continued) **S111046779**

All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	0
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Todd Henson
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4911
Id Type:	SIC
Description:	ELECTRICAL SERVICES
Last Modified:	2/19/2010
Id:	221122
Id Type:	NAICS
Description:	Electric Power Distribution
Last Modified:	2/19/2010
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/19/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Type 2:	Emergency Contact
Contact Name:	Austin Energy City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	4/4/2011

Contact:

Contact Email:	fred.blood@austinenergy.com
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/15/2011

BERGSTROM SUBSTATION (Continued) **S111046779**

Contact:

Contact Email:	Not reported
Contact Mail Address:	310 WEST AVE.
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Energy Control Center
Title:	Emergency
Modification Date:	4/4/2011

Contact:

Contact Email:	Not reported
Contact Mail Address:	2412 Kramer Ln.
Contact City/State/Zip:	Austin, TX 78758
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Todd Henson
Title:	Substation Supt.
Modification Date:	4/4/2011

Chemical Inventory:

Facility Id:	FATR201071DJEA027HXF
Chemical Name:	Sulfuric Acid (in batteries)
Chemical Inv Record Id:	CVTR201071DJEA02GHZ9
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	14
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201071DJEA02HHZR
Chemical Inventory Record Id:	CVTR201071DJEA02GHZ9
Amt Of Sub Stored Or Transported:	54
Amount Units:	gallons
Type Of Storage:	Other

BERGSTROM SUBSTATION (Continued) **S111046779**

Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: in batteries in substation maint building
Last Modified: 4/2/2011

Notes: Not reported
Validation: Not reported

GY882 Target Property | **THE TIRE WHAREHOUSE**
4323 S CONGRESS AVE
AUSTIN, TX 78745

TX AIRS **S121946058**
TX COMP HIST **N/A**
TX CENTRAL REGISTRY

Site 5 of 10 in cluster GY

Actual: 660 ft.

Focus Map: 17

AIRS:

Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Permit Num:	37685
Regulated Id:	RN100525443
Permit Type:	PBR
Permit Status:	CANCELLED
Permit Issued Date:	03/09/1998
Expiration Date:	12/31/3000
Customer Id:	CN600416010
Company Name:	GRINLAND INC
Physical Location Desc:	4323 S CONGRESS AVE
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

COMP HIST:

RN Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600244891
CN Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811111
SIC Code:	4813

THE TIRE WHAREHOUSE (Continued) **S121946058**

Related Number:	TH0708G,TH0708G

RN Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN602295586
CN Name:	THE TIRE WHAREHOUSE
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811111
SIC Code:	6552
Related Number:	TH0708G,TH0708G

CENTRAL REGISTRY:

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600244891
Customer Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
Customer Legal Name:	Grimland, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602295586
Customer Name:	THE TIRE WHAREHOUSE
Customer Legal Name:	The Tire Wharehouse
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

THE TIRE WHAREHOUSE (Continued) **S121946058**

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600416010
Customer Name:	GRINLAND IN C
Customer Legal Name:	Grinland In C
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	3/9/1998
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600244891
Customer Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
Customer Legal Name:	Grimland, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600244891
Customer Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
Customer Legal Name:	Grimland, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE

THE TIRE WHAREHOUSE (Continued) **S121946058**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602295586
Customer Name:	THE TIRE WHAREHOUSE
Customer Legal Name:	The Tire Wharehouse
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602295586
Customer Name:	THE TIRE WHAREHOUSE
Customer Legal Name:	The Tire Wharehouse
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600416010
Customer Name:	GRINLAND IN C
Customer Legal Name:	Grinland In C
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	3/9/1998
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE

THE TIRE WHAREHOUSE (Continued) **S121946058**

Status Date:	##########
Customer Number:	CN600416010
Customer Name:	GRINLAND IN C
Customer Legal Name:	Grinland In C
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	3/9/1998
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600244891
Customer Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
Customer Legal Name:	Grimland, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Regulated Entity Number:	RN100525443
Name:	THE TIRE WHAREHOUSE
Address:	4323 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600244891
Customer Name:	SOUTHWESTERN MOTOR & TRANSMISSION REBUILDERS
Customer Legal Name:	Grimland, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	4323 S CONGRESS AVE

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

GY883 Target Property | **ST ELMO RESIDENTIAL**
4323 SOUTH CONGRESS AVENUE
AUSTIN, TX 78745 | **FINDS** | **1026457589**
N/A

Site 6 of 10 in cluster GY

Actual: 660 ft.
Focus Map: 17

FINDS:
Registry ID: 110070817606

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GY884 Target Property | **ST ELMO RESIDENTIAL**
4323 SOUTH CONGRESS AVENUE
AUSTIN, TX 78745 | **ECHO** | **1026225643**
N/A

Site 7 of 10 in cluster GY

Actual: 660 ft.
Focus Map: 17

ECHO:

Envid:	1026225643
Registry ID:	110070817606
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070817606
Name:	ST ELMO RESIDENTIAL
Address:	4323 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745

GY885 Target Property | **THE TIRE WHAREHOUSE**
4323 S CONGRESS AVE
AUSTIN, TX 78702 | **FINDS** | **1011385394**
N/A

Site 8 of 10 in cluster GY

Actual: 660 ft.
Focus Map: 17

FINDS:
Registry ID: 110035088357

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

GY886 Target Property | **ST ELMO RESIDENTIAL**
4323 SOUTH CONGRESS AVENUE
AUSTIN, TX 78745 | **TX COMP HIST** | **S126971036**
TX CENTRAL REGISTRY | **N/A**

Site 9 of 10 in cluster GY

Actual: 660 ft.
Focus Map: 17

COMP HIST:

RN Number:	RN111056453
Name:	ST ELMO RESIDENTIAL
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605206986
CN Name:	MAKER BROS LLC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	3827
Related Number:	TXR1511CL,TXR1511CL

CENTRAL REGISTRY:

Regulated Entity Number:	RN111056453
Name:	ST ELMO RESIDENTIAL
Address:	4323 SOUTH CONGRESS AVENUE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745
Status:	ACTIVE
Status Date:	2020-06-17
Customer Number:	CN605206986
Customer Name:	MAKER BROS LLC
Customer Legal Name:	Maker Bros, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2020-06-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4323 SOUTH CONGRESS AVENUE

---

887 Target Property | **MULTIPLE STORAGE BUILDINGS**
4341 CONGRESS AVE.
AUSTIN, TX 78745 | **TX ASBESTOS** | **S128930635**
N/A

Actual: 658 ft.
Focus Map: 17

ASBESTOS:

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/21/2022
Notification Number:	2022002000
ASB Priority:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/12/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/13/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/12/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/14/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/29/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/29/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/21/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/11/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/11/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/21/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/14/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/14/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/21/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Inspector Name:	Not reported
Date Report Received:	04/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/15/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Complaint Date:	07/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/15/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/01/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/21/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/27/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/18/2022

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	07/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/27/2022

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/22/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/24/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/24/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	05/04/2022
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/01/2022
Notification Number:	2022002000
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/24/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/24/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	69
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/19/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/11/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/15/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/11/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange L Collins
Violation:	Not reported
Complaint Date:	04/14/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/06/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/06/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange L Collins
Violation:	Not reported
Complaint Date:	06/15/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/06/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/06/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/19/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/08/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/15/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/08/2022
Certification Statement Phone:	5122479485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	04/14/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/29/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	06/01/2022
Notification Number:	2022002148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/29/2022

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/29/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/05/04
Notification Number:	Not reported

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/04/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022002000
File Number:	70205
License Status Description:	Current
Expiration Date:	06/13/2022
Original Date:	03/24/2022
Rank Effective Date:	03/24/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	32720
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	MULTIPLE STORAGE BUILDINGS
Address:	4341 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/04/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/19/2022
Client Code:	1500
Client Name:	Environmental Notification

MULTIPLE STORAGE BUILDINGS (Continued) **S128930635**

License Number:	2022002000
File Number:	70205
License Status Description:	Current
Expiration Date:	06/13/2022
Original Date:	03/24/2022
Rank Effective Date:	03/24/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	32558
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

---

888 **TENNISON PROPERTIES INC** **EDR Hist Auto** **1013776785**
Target **4360 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

EDR Hist Auto

Actual:
652 ft.

Focus Map:
17

Year:	Name:	Type:
1990	SNAPPY CAR RENTAL	AUTOMOBILE REPAIRING
1991	TENNISON PROPERTIES INC	Convenience Stores
1992	TENNISON PROPERTIES INC	Convenience Stores
1993	TENNISON PROPERTIES INC	Convenience Stores
1994	TENNISON PROPERTIES INC	Convenience Stores
1995	TENNISON PROPERTIES INC	Convenience Stores

HA889 **CAPITAL BUMPER EXCHANGE** **EDR Hist Auto** **1013774944**
Target **4422 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78745**

Site 1 of 4 in cluster HA

Actual:
648 ft.

Focus Map:
17

EDR Hist Auto

Year:	Name:	Type:
1970	CAPITAL BUMPER EXCHANGE	AUTOMOBILE REPAIRING
1975	CAPITAL BUMPER EXCHANGE	AUTOMOBILE REPAIRING

HB890 **HAWTHORN SUITES LTD** **FINDS** **1006379971**
Target **(MET CENTER)** **ECHO** **N/A**
Property **AUSTIN, TX 78744**

Site 1 of 3 in cluster HB

Actual:
550 ft.

Focus Map:
19

FINDS:
Registry ID: 110013314289

Click Here for FRS Facility Detail Report:

HAWTHORN SUITES LTD (Continued) **1006379971**

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1006379971
Registry ID:	110013314289
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110013314289
Name:	HAWTHORN SUITES LTD
Address:	(MET CENTER)
City,State,Zip:	AUSTIN, TX 78744

HC891 **HAWTHORNE SUITES** **ICIS** **1006801292**
Target **7800 E RIVERSIDE DR** **FINDS** **N/A**
Property **AUSTIN, TX 78744** **ECHO**

Site 1 of 2 in cluster HC

Actual: 541 ft.

Focus Map: 19

ICIS:

Enforcement Action ID:	06-2002-1814
FRS ID:	110013724256
Action Name:	CHASCO CONTRACTING AND FELIX ENTERPRISE NI. 1, LTD.
Facility Name:	HAWTHORNE SUITES
Facility Address:	7800 E RIVERSIDE DR AUSTIN, TX 78744
Enforcement Action Type:	CWA 309A AO For Compliance
Facility County:	TRAVIS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	309A
Facility SIC Code:	1542
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.216894
Longitude in Decimal Degrees:	-97.689936
Permit Type Desc:	Not reported
Program System Acronym:	27957
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	HAWTHORNE SUITES
Address:	7800 E RIVERSIDE DR
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	1542

FINDS:

HAWTHORNE SUITES (Continued) **1006801292**

Registry ID: 110013724256

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1006801292
Registry ID:	110013724256
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110013724256
Name:	HAWTHORNE SUITES
Address:	7800 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78744

HD892 **ELL IS & SALAZAR GARAGE & BODY SHOP** **EDR Hist Auto** **1013757370**
Target **4501 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78745**

Site 1 of 6 in cluster HD

Actual: EDR Hist Auto
643 ft.

Focus Map:
17

Year:	Name:	Type:
1985	SALAZAR & SON INC	General Automotive Repair Shops
1986	SALAZAR & SON INC	General Automotive Repair Shops
1987	SALAZAR & SON INC	Not reported
1988	SALAZAR & SON INC	Not reported
1989	SALAZAR & SON INC	Exterior Repair Services
1990	ELL IS & SALAZAR GARAGE & BODY	AUTOMOBILE REPAIRING
1992	3J AUTOMOTIVE INC	Exterior Repair Services
1993	3J AUTOMOTIVE INC	Exterior Repair Services
1994	3J AUTOMOTIVE INC	Exterior Repair Services
1995	3J AUTOMOTIVE INC	Exterior Repair Services
1996	3J AUTOMOTIVE INC	Exterior Repair Services
1997	3J AUTOMOTIVE INC	Exterior Repair Services
1998	3J AUTOMOTIVE INC	Exterior Repair Services
1999	3J AUTOMOTIVE INC	Exterior Repair Services
2000	3J AUTOMOTIVE INC	Exterior Repair Services
2001	3J AUTOMOTIVE INC	Exterior Repair Services
2002	3J AUTOMOTIVE INC	Exterior Repair Services
2003	3J AUTOMOTIVE INC	Exterior Repair Services
2004	3J AUTOMOTIVE INC	Exterior Repair Services

ELL IS & SALAZAR GARAGE & BODY SHOP (Continued) **1013757370**

2005	3J AUTOMOTIVE INC	Exterior Repair Services
2006	3J AUTOMOTIVE INC	Exterior Repair Services
2007	3J AUTOMOTIVE INC	Exterior Repair Services
2008	3J AUTOMOTIVE INC	Exterior Repair Services
2009	3J AUTOMOTIVE INC	Exterior Repair Services
2010	3J AUTOMOTIVE INC	Exterior Repair Services
2010	JWJ AUTOMOTIVE INC	General Automotive Repair Shops
2011	3J AUTOMOTIVE INC	Exterior Repair Services
2012	3J AUTOMOTIVE INC	Exterior Repair Services
2013	3J AUTOMOTIVE INC	Exterior Repair Services
2014	3J AUTOMOTIVE INC	Exterior Repair Services

HD893 **ELLIS AND SALAZAR** **TX AIRS** **S118071802**
Target **4501 S CONGRESS AVE** **TX COMP HIST** **N/A**
Property **AUSTIN, TX 78745** **TX CENTRAL REGISTRY**

Site 2 of 6 in cluster HD

Actual:
643 ft.

Focus Map:
17

AIRS:

Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Permit Num:	25489
Regulated Id:	RN100561968
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	08/26/1994
Expiration Date:	12/31/3000
Customer Id:	CN600272736
Company Name:	3 J AUTOMOTIVE
Physical Location Desc:	4501 S. CONGRESS
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

COMP HIST:

RN Number:	RN100561968
Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600272736
CN Name:	3J AUTOMOTIVE INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022

ELLIS AND SALAZAR (Continued) **S118071802**

NAICS Code:	811121
SIC Code:	6552
Related Number:	25489,TH0496V,TH0496V

CENTRAL REGISTRY:

Regulated Entity Number:	RN100561968
Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1907
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600272736
Customer Name:	3J AUTOMOTIVE INC
Customer Legal Name:	3J Automotive, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	4501 S. CONGRESS

Regulated Entity Number:	RN100561968
Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1907
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600272736
Customer Name:	3J AUTOMOTIVE INC
Customer Legal Name:	3J Automotive, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	4501 S. CONGRESS

Regulated Entity Number:	RN100561968
Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1907
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600272736
Customer Name:	3J AUTOMOTIVE INC
Customer Legal Name:	3J Automotive, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance

ELLIS AND SALAZAR (Continued) **S118071802**

Physical Location Description: 4501 S. CONGRESS

Regulated Entity Number: RN100561968
Name: ELLIS AND SALAZAR
Address: 4501 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-1907
Status: ACTIVE
Status Date: ##########
Customer Number: CN600272736
Customer Name: 3J AUTOMOTIVE INC
Customer Legal Name: 3J Automotive, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/30/1994
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811121
Primary NAICS Industry Type Description: Paint and Interior Repair and Maintenance
Physical Location Description: 4501 S. CONGRESS

Regulated Entity Number: RN100561968
Name: ELLIS AND SALAZAR
Address: 4501 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-1907
Status: ACTIVE
Status Date: ##########
Customer Number: CN600272736
Customer Name: 3J AUTOMOTIVE INC
Customer Legal Name: 3J Automotive, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/30/1994
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811121
Primary NAICS Industry Type Description: Paint and Interior Repair and Maintenance
Physical Location Description: 4501 S. CONGRESS

HD894 **ELLIS AND SALAZAR** **RCRA NonGen / NLR** **1000261815**
Target **4501 S CONGRESS AVE** **FINDS** **TXD981058274**
Property **AUSTIN, TX 78745** **ECHO**

Site 3 of 6 in cluster HD

Actual:
643 ft.

Focus Map:
17

RCRA Listings:
Date Form Received by Agency: 20011127
Handler Name: 3j Automotive
Handler Address: S CONGRESS AVE
Handler City,State,Zip: AUSTIN, TX 78745
EPA ID: TXD981058274
Contact Name: WAYNE BURKLUND
Contact Address: S CONGRESS AVE
Contact City,State,Zip: AUSTIN, TX 78745
Contact Telephone: 512-444-5555
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 06

ELLIS AND SALAZAR (Continued) **1000261815**

Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	3j Automotive
Owner Type:	Not reported
Operator Name:	3j Automotive
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

ELLIS AND SALAZAR (Continued) **1000261815**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SALAZAR & SON INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: 3J AUTOMOTIVE	
Legal Status:	Not reported
Date Became Current:	20011127
Date Ended Current:	Not reported
Owner/Operator Address:	4501 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-444-5555
Owner/Operator Telephone Ext:	Not reported

ELLIS AND SALAZAR (Continued) **1000261815**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 3J AUTOMOTIVE
Legal Status: Not reported
Date Became Current: 20011127
Date Ended Current: Not reported
Owner/Operator Address: 4501 S CONGRESS AVE
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-444-5555
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19850720
Handler Name: ELLIS & SALAZAR BO SH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011127
Handler Name: 3J AUTOMOTIVE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005084407

ELLIS AND SALAZAR (Continued) **1000261815**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000261815
Registry ID:	110005084407
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005084407
Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
City,State,Zip:	AUTIN, TX 78745

HD895 **ELLIS AND SALAZAR** **TX Ind. Haz Waste** **S103606419**
Target **4501 S CONGRESS AVE** **N/A**
Property **AUTIN, TX 78745**

Site 4 of 6 in cluster HD

Actual: 643 ft.

Focus Map: 17

Ind. Haz Waste:

Name:	ELLIS AND SALAZAR
Address:	4501 S CONGRESS AVE
City,State,Zip:	AUTIN, TX 78745
Permit Number:	Not reported
Registration Number:	66346
Registration Initial Notification Date:	07/03/1985
Registration Last Amendment Date:	11/27/2001
EPA Identification:	TXD981058274
Primary NAICS Code:	811121
Status Change Date:	19850703
Land Type:	Not reported
Description of Facility Site Location:	4501 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

ELLIS AND SALAZAR (Continued) **S103606419**

Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	3J AUTOMOTIVE INC
Contact Name:	WAYNE BURKLUND
Contact Telephone Number:	512-4445555
Mailing Address:	4501 S CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787451907
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21625
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030102
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	3J AUTOMOTIVE INC
Operator Address:	4501 S CONGRESS AVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4445555
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17425530445
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	3J AUTOMOTIVE INC
Owner Mailing Address:	4501 S CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4445555
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown

ELLIS AND SALAZAR (Continued) **S103606419**

Owner Tax ID:	17425530445
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	5
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	129
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Inside paint mixing building East of property by detail shop.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970514
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	061
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drums between paint booths iin East end of property
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970430
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported

ELLIS AND SALAZAR (Continued) **S103606419**

Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4501 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4445555
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4501 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4445555
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WAYNE BURKLUND
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4501 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4445555
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	118862
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint & thinner/painting autos
Standard Industrial Code:	75320
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

ELLIS AND SALAZAR (Continued) **S103606419**

Ind. Haz Waste:

Waste ID:	118863
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste solvents/parts cleaner machine
Standard Industrial Code:	75320
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	118864
Texas Waste Code:	Not reported
Texas Waste Code 2:	00032061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste oil/oil changes
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	118865
Texas Waste Code:	Not reported
Texas Waste Code 2:	00043101

ELLIS AND SALAZAR (Continued) **S103606419**

Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Absorbents containing oil/clean-up
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	165068
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Automotive Parts Cleaner Washer . Inclosed metal container - Waste are minerals
Standard Industrial Code:	75320
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4501 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745

ELLIS AND SALAZAR (Continued) **S103606419**

AR Number:	0000309851
Principal Name:	3J AUTOMOTIVE INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4501 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000309851
Principal Name:	3J AUTOMOTIVE INC
Attention Name:	Not reported
Attention Suffix:	NWG

HC896 **7901 E RIVERSIDE DR BLDG 2 STE 150** **PFAS ECHO** **1027320367**
Target Property **AUSTIN, TX** **N/A**

Site 2 of 2 in cluster HC

Actual: 531 ft.
Focus Map: 19

PFAS ECHO:

Name:	7901 E RIVERSIDE DR BLDG 2 STE 150
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21596
Longitude:	-97.68884
Count:	1
County:	Not reported
Status:	Inactive
Region:	06
Industry:	Electronics Industry
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070358737
Facility Percent Minority:	80.25
Facility Derived Tribes:	-
Facility Population:	1832.1
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484530024312018
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0

7901 E RIVERSIDE DR BLDG 2 STE 150 (Continued) **1027320367**

Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXRNEAU15
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	3674
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.68884,%22y%22:30.21596,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

HE897 **OES EQUIPMENT** **TX CENTRAL REGISTRY** **S128263734**
Target **7900 E RIVERSIDE DR** **N/A**
Property **AUSTIN, TX 78744**

Site 1 of 3 in cluster HE

Actual:
527 ft.

Focus Map:
19

CENTRAL REGISTRY:

Regulated Entity Number:	RN111467841
Name:	OES EQUIPMENT
Address:	7900 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1643
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN606001386
Customer Name:	OES EQUIPMENT LLC
Customer Legal Name:	O.E.S. Equipment, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/28/2022

OES EQUIPMENT (Continued) **S128263734**

Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 532490
Primary NAICS Industry Type Description: Other Commercial and Industrial Machinery and Equipment Rental and Leasing
Physical Location Description: Not reported

HF898 **ERNS** **2000538677**
Target Property **4703 SOUTH CONGRESS AVE.** **N/A**
TRAVIS (County), TX

Site 1 of 7 in cluster HF

Actual: 643 ft.

Focus Map: 17

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

HF899 **JACKS NEW CONCEPT AUTO REPAIR** **TX CENTRAL REGISTRY** **S126537494**
Target Property **4703 S CONGRESS AVE** **N/A**
AUSTIN, TX 78745

Site 2 of 7 in cluster HF

Actual: 642 ft.

Focus Map: 17

CENTRAL REGISTRY:

Regulated Entity Number: RN101700862
Name: JACKS NEW CONCEPT AUTO REPAIR
Address: 4703 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-2302
Status: ACTIVE
Status Date: 3/16/2002
Customer Number: CN600918585
Customer Name: VITAS, JACOB
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 5/29/1987
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN101700862
Name: JACKS NEW CONCEPT AUTO REPAIR
Address: 4703 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-2302
Status: ACTIVE
Status Date: 3/16/2002
Customer Number: CN604211284
Customer Name: VITAS, JACOB
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE

JACKS NEW CONCEPT AUTO REPAIR (Continued) **S126537494**

Affiliation Begin Date:	9/1/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101700862
Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-2302
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN604249201
Customer Name:	SEVERN DAN
Customer Legal Name:	SEVERN DAN
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

HF900 **JACKS NEW CONCEPT AUTO REPAIR** **FINDS** **1010761288**
Target **4703 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 7 in cluster HF

Actual:
642 ft.

Focus Map:
17

FINDS:
Registry ID: 110033867457

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

HF901 **INMAN F M SERV** **EDR Hist Auto** **1013771651**
Target **4703 CONGRESS AVE S** **N/A**
Property **SOUTH AUSTIN, TX**

Site 4 of 7 in cluster HF

Actual:
642 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1953	COLLINS SERV STA	GASOLINE STATIONS
1958	INMAN F M SERV	GASOLINE STATIONS

HF902 **JACKS NEW CONCEPT AUTO REPAIR** **TX UST** **U001276573**
Target **4703 S CONGRESS AVE** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78745** **TX Financial Assurance**
TX RDR

Site 5 of 7 in cluster HF

Actual:
642 ft.

Focus Map:
17

UST:

Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787452302
AI Number:	44890
Facility Type:	RETAIL
Facility Begin Date:	11/01/1984
Facility Status:	ACTIVE
Additional ID:	773532182002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	JACOB VITAS,OWNER
Contact Organization Name:	JACKS NEW CONCEPT AUTO REPAIR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124418889
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/27/1987
Signature Name/Title On Earliest Reg Form:	DAN SEVERN,OWNER
Application Received Date On Earliest Reg Form:	05/29/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	Not reported

Operator:

Princ ID:	763532182002075
Additional ID:	773532182002075
Ai Number:	44890
Operator CN:	CN600918585
Operator Name:	JACOB VITAS
Operator Effective Begin Date:	09/01/1989

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Operator Type:	IN
Operator Role:	OPRCON
Contact Name:	JACOB VITAS/OWNER
Contact Organization Name:	VITAS JACOB
Contact Mailing Address (Delivery):	4703 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78745-2302
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4418889
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600918585
Owner Last Name:	VITAS
Owner First Name:	JACOB
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	4703 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78745
Contact Mailing Zip5:	2302
Contact Phone Number/Ext:	1 512 4418889/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	763532182002075
Additional ID:	773532182002075
AI Number:	44890
Owner Effective Begin Date:	09/01/1989
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JACOB VITAS/OWNER
Contact Organization Name:	VITAS JACOB

Self Certification:

Self Cert ID:	95291
Cert ID:	155310
AI Number:	44890
Self Certification Date:	02/01/2010
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155309
AI Number:	44890
Self Certification Date:	03/11/2009
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155308
AI Number:	44890
Self Certification Date:	03/10/2008
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155307
AI Number:	44890
Self Certification Date:	03/14/2007
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155306
AI Number:	44890
Self Certification Date:	01/30/2006
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155305
AI Number:	44890
Self Certification Date:	02/25/2005
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155304
AI Number:	44890
Self Certification Date:	03/24/2004
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155303
AI Number:	44890
Self Certification Date:	03/18/2003
Signature Name/Title:	JACOB VITAS
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155302
AI Number:	44890
Self Certification Date:	03/07/2002
Signature Name/Title:	JACOB VITAS
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95291
Cert ID:	155301
AI Number:	44890
Self Certification Date:	09/15/2000
Signature Name/Title:	JACOB VITAS OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	11/01/1984
Tank Registration Date:	05/29/1987
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117556
Facility ID:	95291
Ai Number:	44890
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/08/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	159587
UST ID:	117556
AI Number:	44890
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1993

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

More Self Certification:

Self Cert ID:	17573
Cert ID:	22464
UST Comprt ID:	58874
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22463
UST Comprt ID:	58875
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22452
UST Comprt ID:	58884
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22457
UST Comprt ID:	58881
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22462
UST Comprt ID:	58876
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22453
UST Comprt ID:	58885
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22459
UST Comprt ID:	58879
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Self Cert ID:	17573
Cert ID:	22461
UST Comprt ID:	58877
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	22456
UST Comprt ID:	58882
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	22458
UST Comprt ID:	58880
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	22460
UST Comprt ID:	58878
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	22454
UST Comprt ID:	59750
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	219372
UST Comprt ID:	628756
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17573
Cert ID:	22455
UST Comprt ID:	58883
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Install Date:	11/01/1984
Tank Registration Date:	05/29/1987
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117557
Facility ID:	95291
Ai Number:	44890
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/08/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	159588
UST ID:	117557
AI Number:	44890
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1993

More Self Certification:

Self Cert ID:	17573
Cert ID:	22464
UST Comprt ID:	58874
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Self Cert ID:	17573
Cert ID:	22463
UST Comprt ID:	58875
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22452
UST Comprt ID:	58884
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22457
UST Comprt ID:	58881
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22462
UST Comprt ID:	58876
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22453
UST Comprt ID:	58885
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22459
UST Comprt ID:	58879
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22461
UST Comprt ID:	58877
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Cert ID:	22456
UST Comprt ID:	58882
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22458
UST Comprt ID:	58880
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22460
UST Comprt ID:	58878
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22454
UST Comprt ID:	59750
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	219372
UST Comprt ID:	628756
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22455
UST Comprt ID:	58883
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Install Date:	11/01/1984
Tank Registration Date:	05/29/1987
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117558
Facility ID:	95291

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Ai Number:	44890
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/08/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	159589

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

UST ID:	117558
AI Number:	44890
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1993

More Self Certification:

Self Cert ID:	17573
Cert ID:	22464
UST Comprt ID:	58874
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22463
UST Comprt ID:	58875
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Cert ID:	22452
UST Comprt ID:	58884
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22457
UST Comprt ID:	58881
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22462
UST Comprt ID:	58876
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22453
UST Comprt ID:	58885
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22459
UST Comprt ID:	58879
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22461
UST Comprt ID:	58877
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22456
UST Comprt ID:	58882
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22458

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

UST Comprt ID:	58880
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22460
UST Comprt ID:	58878
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22454
UST Comprt ID:	59750
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	219372
UST Comprt ID:	628756
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22455
UST Comprt ID:	58883
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/29/1987
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	117559
Facility ID:	95291
Ai Number:	44890
Tank Id:	4
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	01/01/1999
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	159590
UST ID:	117559
AI Number:	44890
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17573
Cert ID:	22464
UST Comprt ID:	58874
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22463
UST Comprt ID:	58875
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22452
UST Comprt ID:	58884
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22457

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

UST Comprt ID:	58881
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22462
UST Comprt ID:	58876
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22453
UST Comprt ID:	58885
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22459
UST Comprt ID:	58879
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22461
UST Comprt ID:	58877
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22456
UST Comprt ID:	58882
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22458
UST Comprt ID:	58880
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22460
UST Comprt ID:	58878

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22454
UST Comprt ID:	59750
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	219372
UST Comprt ID:	628756
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17573
Cert ID:	22455
UST Comprt ID:	58883
UST ID:	20482
AI Number:	44890
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	15399
Facility ID:	95291
AI Number:	44890
Application Received Date:	07/06/2010
Scheduled Construction Date:	07/08/2010
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Owner AR At Time Of Construction: 40063
General Desc Of Prop Construct: PERMANENT REMOVAL AND DISPOSAL OF (3) UNDERGROUND STORAGE TANKS; SAMPLING AND RE PORTING. REQUEST WAIVER OF 30-DAY NOTIFICATION REQUIREMENT.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16534
UST ID:	Not reported
NOC ID:	15399
AI Number:	44890
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113 REGAL ROW
Mailing Address (Internal Delivery):	STE A
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	16535
UST ID:	Not reported
NOC ID:	15399
AI Number:	44890
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	VITAS JACOB

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Contact Mailing Address (Delivery):	4703 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 2302
Phone Number/Ext:	512 4418889/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95291
Additional ID:	773532182002075
Princ ID:	763532182002075
AI Number:	44890
Facility Name:	JACKS NEW CONCEPT AUTO REPAIR
AR Number:	40063
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	JACOB VITAS/OWNER

HIST UST AUSTIN:

Name:	JACK'S NEW CNCPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	1110
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	95291
Finass ID:	8487
AI:	44890
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/08/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361339
Policy Number:	13654
Coverage Amount:	1000000
Coverage Expiration Date:	10/08/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Region:	2
Facility ID:	95291
Finass ID:	82973
AI:	44890
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/08/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361339
Policy Number:	13654
Coverage Amount:	1000000
Coverage Expiration Date:	10/08/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	95291
Finass ID:	82974
AI:	44890
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/08/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	13654
Coverage Amount:	1000000
Coverage Expiration Date:	10/08/2008
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	95291
Finass ID:	82975
AI:	44890
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

JACKS NEW CONCEPT AUTO REPAIR (Continued) **U001276573**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	19410
Facility ID:	44890
RN:	Not reported
CN:	Not reported
Name:	JACKS NEW CONCEPT AUTO REPAIR
Address:	4703 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/20/2010
Due Date:	2/18/2011
Tank Owner:	WOLFE VITAS PARTNERSHIP
Contact Person:	JACOB VITAS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/11/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/11/2011
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

HF903 **MC NEES HUMBLE** **EDR Hist Auto** **1013776082**
Target **4703 CONGRESS AVE** **N/A**
Property **SOUTH AUSTIN, TX**

Site 6 of 7 in cluster HF

Actual:
642 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1962	MC NEES HUMBLE	GASOLINE STATIONS

HF904 **PHILLIPS SIXTY SIX GAS ST** **EDR Hist Auto** **1013757647**
Target **4703 CONGRESS AVE S** **N/A**
Property **TRAVIS (County), TX 78745**

Site 7 of 7 in cluster HF

Actual:
642 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1965	JOHNSON ENCO PRODUCTS GAS	GASOLINE STATIONS
1969	JOHNSON SERVICE STATION	Gasoline Service Stations
1970	JOHNSON ENCO PRODUCTS	GASOLINE STATIONS
1970	JOHNSON SERVICE STATION	Gasoline Service Stations
1975	SOUTH CONGRESS EXXON	GASOLINE STATIONS
1977	SOUTH CONGRESS EXXON	Gasoline Service Stations
1978	SOUTH CONGRESS EXXON	Gasoline Service Stations
1980	SOUTH CONGRESS EXXON	GASOLINE STATIONS
1984	TERRYS SOUTH CONGRESS EXXON GAS	GASOLINE STATIONS
1990	PHILLIPS SIXTY SIX GAS ST	GASOLINE STATIONS
1991	WRIGHT PHILLIPS 66	Gasoline Service Stations
1992	WRIGHT PHILLIPS 66	Gasoline Service Stations
1993	WRIGHT PHILLIPS 66	Gasoline Service Stations
1994	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations
1995	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
1996	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
1997	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
1998	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
1999	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2000	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2001	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2002	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2003	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2004	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2005	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2006	JACKS NEW CONCEPT AUTO REPAIR	Gasoline Service Stations, NEC
2007	JACKS NEW CONCEPT AUTO REPAIR	General Automotive Repair Shops
2008	JACKS NEW CONCEPT AUTO REPAIR	General Automotive Repair Shops
2009	JACKS NEW CONCEPT AUTO REPAIR	General Automotive Repair Shops
2010	JACKS NEW CONCEPT AUTO REPAIR	General Automotive Repair Shops
2010	CHESHIRE AUTO REPAIR	General Automotive Repair Shops
2011	CHESHIRE AUTO REPAIR	General Automotive Repair Shops
2011	JACKS NEW CONCEPT AUTO REPAIR	General Automotive Repair Shops
2013	KREMKO AUTOMOTIVE	Automotive Repair Shops, NEC
2014	KREMKO AUTOMOTIVE	Automotive Repair Shops, NEC

HG905 **SOUTHSIDE RECYCLING CO** **FINDS** **1016286387**
Target **4917 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 1 of 2 in cluster HG

Actual:
600 ft.

FINDS:
Registry ID: 110011418466

Focus Map:
17

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in

SOUTHSIDE RECYCLING CO (Continued) **1016286387**

regions and states with cooperative agreements, enforcement actions, and settlements.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

HG906 **SOUTHSIDE RECYCLING CO** **FTTS** **1004603591**
Target **4917 S CONGRESS AVE** **HIST FTTS** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 2 in cluster HG

Actual:
600 ft.

Focus Map:
17

FTTS INSP:

Inspection Number:	19890130TX004 1
Region:	06
Inspection Date:	01/30/89
Inspector:	KELLY
Violation occurred:	No
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

HIST FTTS INSP:

Inspection Number:	19890130TX004 1
Region:	06
Inspection Date:	Not reported
Inspector:	KELLY
Violation occurred:	No
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

---

907 **TITOS IMPORTS AUTO REPAIR** **TX CENTRAL REGISTRY** **S126893004**
Target **5310 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Actual:
603 ft.

Focus Map:
17

CENTRAL REGISTRY:

Regulated Entity Number:	RN108833765
Name:	TITOS IMPORTS AUTO REPAIR
Address:	5310 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3102
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604972513
Customer Name:	TITOS IMPORTS AUTO REPAIR
Customer Legal Name:	Titos Imports Auto Repair
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

TITOS IMPORTS AUTO REPAIR (Continued) **S126893004**

Physical Location Description: Not reported

HH908 **KOVAR ROY TEXACO** **EDR Hist Auto** **1021170164**
Target **100 RED BIRD TRAIL** **N/A**
Property **AUSTIN, TX 78746**

Site 1 of 2 in cluster HH

Actual:
621 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1983	KOVAR ROY TEXACO	Gasoline Service Stations

HH909 **ROOSTERS PAINT & D COR** **TX ASBESTOS** **S119155740**
Target **5501 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 2 in cluster HH

Actual:
625 ft.

Focus Map:
17

ASBESTOS:

Name:	ROOSTERS PAINT & D COR
Address:	5501 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.9
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2014
Date Routed by Supervisor:	03/04/2014
Date Routed to PSQA:	03/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

ROOSTERS PAINT & D COR (Continued) **S119155740**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HI910 **RITTERS OF SOUTH** **EDR Hist Auto** **1013755330**
Target Property **5503 CONGRESS AVE S** **N/A**
AUSTIN, TX

Site 1 of 4 in cluster HI

Actual: 628 ft. EDR Hist Auto

Focus Map: 17

Year:	Name:	Type:
1965	RITTERS OF SOUTH	GASOLINE STATIONS

HI911 **5503 S CONGRESS AVE** **TX UST** **U003566444**
Target Property **5503 S CONGRESS AVE** **TX HIST UST** **N/A**
AUSTIN, TX 78745

Site 2 of 4 in cluster HI

Actual: 628 ft. UST:

Focus Map: 17

Name:	5503 S CONGRESS AVE
Address:	5503 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787453105
AI Number:	68959

5503 S CONGRESS AVE (Continued) **U003566444**

Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	711464802002175
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	MICHAEL MENEM,OWNER
Contact Organization Name:	5503 S CONGRESS AVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124413232
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/03/1996
Signature Name/Title On Earliest Reg Form:	MICHAEL MENEM,OWNER
Application Received Date On Earliest Reg Form:	10/08/1996
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN604228700
Owner Last Name:	AUTO SHOW PLACE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	799646752012346
Additional ID:	711464802002175
AI Number:	68959
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

5503 S CONGRESS AVE (Continued) **U003566444**

Install Date:	08/31/1987
Tank Registration Date:	10/08/1996
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181512
Facility ID:	104457
Ai Number:	68959
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/21/1996
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

5503 S CONGRESS AVE (Continued) **U003566444**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	170440
UST ID:	181512
AI Number:	68959
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/08/1996
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181513

5503 S CONGRESS AVE (Continued) **U003566444**

Facility ID:	104457
Ai Number:	68959
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/21/1996
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000

5503 S CONGRESS AVE (Continued) **U003566444**

UST Comprt ID:	170441
UST ID:	181513
AI Number:	68959
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUTO SHOW PLACE
Contact Mailing Address (Delivery):	5701 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 4130
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	104457
Additional ID:	711464802002175
Princ ID:	799646752012346
AI Number:	68959
Facility Name:	5503 S CONGRESS AVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported

5503 S CONGRESS AVE (Continued) **U003566444**

AR AST Number Suffix: Not reported
Contact Name/Title: MICHAEL MENEM/

HIST UST AUSTIN:
Name: AUTO SHOW PLACE
Address: 5503 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: C0631
HID UST: Not reported
Inspection: Not reported
Due: Not reported

HI912 **VACANT** **TX CENTRAL REGISTRY** **S126586313**
Target Property **5503 S CONGRESS AVE** **N/A**
AUSTIN, TX 78745

Site 3 of 4 in cluster HI

Actual: 628 ft.
Focus Map: 17

CENTRAL REGISTRY:
Regulated Entity Number: RN102651700
Name: VACANT
Address: 5503 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-3105
Status: ACTIVE
Status Date: 6/24/2002
Customer Number: CN601349343
Customer Name: AUTO SHOWPLACE INC
Customer Legal Name: Auto Showplace, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 10/8/1996
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN102651700
Name: VACANT
Address: 5503 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-3105
Status: ACTIVE
Status Date: 6/24/2002
Customer Number: CN604228700
Customer Name: AUTO SHOW PLACE
Customer Legal Name: AUTO SHOW PLACE
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/31/1987
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

HI913 Target Property | **RITTERS GASOLINE STATION**
5505 CONGRESS AVE S
TRAVIS (County), TX 78745 | **EDR Hist Auto** | **1013770460**
N/A

Site 4 of 4 in cluster HI

Actual: 628 ft.
Focus Map: 17

EDR Hist Auto

Year:	Name:	Type:
1970	RITTERS GASOLINE STATION	GASOLINE STATIONS

---

914 Target Property | **SOUTHSIDE AUTO SALES**
5609 1/2 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126891899**
N/A

Actual: 639 ft.
Focus Map: 17

CENTRAL REGISTRY:

Regulated Entity Number:	RN108822586
Name:	SOUTHSIDE AUTO SALES
Address:	5609 1/2 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3152
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604961243
Customer Name:	SOUTHSIDE AUTO SALES
Customer Legal Name:	Southside Auto Sales
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

HJ915 Target Property | **A PLUS AUTO & TRUCKS**
5711 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126893115**
N/A

Site 1 of 3 in cluster HJ

Actual: 624 ft.
Focus Map: 17

CENTRAL REGISTRY:

Regulated Entity Number:	RN108834888
Name:	A PLUS AUTO & TRUCKS
Address:	5711 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4130
Status:	ACTIVE
Status Date:	10/26/2015
Customer Number:	CN604973677
Customer Name:	A PLUS AUTO & TRUCKS
Customer Legal Name:	A Plus Auto & Trucks
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

916 Target Property | **SOCO II APARTMENTS**
6001 SOUTH CONGRESS AVENUE
AUSTIN, TX 78745 | **FINDS ECHO** | **1024435082 N/A**

Actual: 640 ft.

Focus Map: 17

FINDS:
Registry ID: 110070356931

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024435082
Registry ID:	110070356931
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070356931
Name:	SOCO II APARTMENTS
Address:	6001 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745

HK917 Target Property | **H & R FOOD MART**
6400 S CONGRESS AVE
AUSTIN, TX 78745 | **FINDS** | **1010773820 N/A**

Site 1 of 3 in cluster HK

Actual: 668 ft.

Focus Map: 17

FINDS:
Registry ID: 110033919160

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

HK918 Target Property | **H & R FOOD MART**
6400 S CONGRESS AVE
AUSTIN, TX 78745 | **TX UST** | **U001249726**
TX HIST UST | **N/A**
TX Financial Assurance

Site 2 of 3 in cluster HK

Actual: 668 ft.

Focus Map: 17

UST:

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787454502
AI Number:	14277
Facility Type:	RETAIL
Facility Begin Date:	06/01/1983
Facility Status:	ACTIVE
Additional ID:	522385872002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	PATRICK OLIVER,PRESIDENT
Contact Organization Name:	H & R FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	PBOVENTURES@GMAIL.COM
Signature Date On Earliest Reg Form:	09/30/2022
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,VP
Application Received Date On Earliest Reg Form:	10/06/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	522385872002117
Ai Number:	14277
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

H & R FOOD MART (Continued) **U001249726**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601101579
Owner Last Name:	OFLP-1 LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	290809782002116
Additional ID:	522385872002117
AI Number:	14277
Owner Effective Begin Date:	08/07/2012
State Tax ID:	32036480542
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	97214
Cert ID:	378568
AI Number:	14277
Self Certification Date:	09/30/2022
Signature Name/Title:	PATRICK OLIVER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	362005
AI Number:	14277
Self Certification Date:	09/24/2021

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	345439
AI Number:	14277
Self Certification Date:	09/14/2020
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	326220
AI Number:	14277
Self Certification Date:	08/28/2019
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	309928
AI Number:	14277
Self Certification Date:	09/17/2018

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	293327
AI Number:	14277
Self Certification Date:	09/19/2017
Signature Name/Title:	Guy Oliver Authorized Legal Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	277662
AI Number:	14277
Self Certification Date:	10/04/2016
Signature Name/Title:	Guy Oliver Authorized Legal Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	259506
AI Number:	14277
Self Certification Date:	09/22/2015

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	241790
AI Number:	14277
Self Certification Date:	09/11/2014
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	227283
AI Number:	14277
Self Certification Date:	10/04/2013
Signature Name/Title:	Guy Oliver Authroized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	97214
Cert ID:	165094
AI Number:	14277
Self Certification Date:	09/28/2012

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165093
AI Number:	14277
Self Certification Date:	09/16/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165092
AI Number:	14277
Self Certification Date:	09/10/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165091
AI Number:	14277
Self Certification Date:	09/01/2009

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165090
AI Number:	14277
Self Certification Date:	09/10/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165089
AI Number:	14277
Self Certification Date:	09/11/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	97214
Cert ID:	165088
AI Number:	14277
Self Certification Date:	09/05/2006

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	97214
Cert ID:	165087
AI Number:	14277
Self Certification Date:	09/02/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	97214
Cert ID:	165086
AI Number:	14277
Self Certification Date:	09/01/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	97214
Cert ID:	165085
AI Number:	14277
Self Certification Date:	09/18/2003

H & R FOOD MART (Continued) **U001249726**

Signature Name/Title:	GUY N OLIVER PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	97214
Cert ID:	165084
AI Number:	14277
Self Certification Date:	10/01/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	97214
Cert ID:	165083
AI Number:	14277
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1

H & R FOOD MART (Continued) **U001249726**

Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36764
Facility ID:	97214
Ai Number:	14277
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	06/01/1983
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

H & R FOOD MART (Continued) **U001249726**

Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	153103
UST ID:	36764
AI Number:	14277
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	5647
Cert ID:	72377
UST Comprt ID:	206188
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A
Self Cert ID:	5647
Cert ID:	72378

H & R FOOD MART (Continued) **U001249726**

UST Comprt ID:	206189
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A
Install Date:	06/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36766
Facility ID:	97214
Ai Number:	14277
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/01/1983
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

H & R FOOD MART (Continued) **U001249726**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	153105
UST ID:	36766
AI Number:	14277
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

H & R FOOD MART (Continued) **U001249726**

Self Cert ID:	5647
Cert ID:	72377
UST Comprt ID:	206188
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A
Self Cert ID:	5647
Cert ID:	72378
UST Comprt ID:	206189
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A
Install Date:	06/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36765
Facility ID:	97214
Ai Number:	14277
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/01/1983
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y

H & R FOOD MART (Continued) **U001249726**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	153104
UST ID:	36765
AI Number:	14277
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

H & R FOOD MART (Continued) **U001249726**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	5647
Cert ID:	72377
UST Comprt ID:	206188
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A
Self Cert ID:	5647
Cert ID:	72378
UST Comprt ID:	206189
UST ID:	68215
AI Number:	14277
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	OFLP-1 LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	97214
Additional ID:	522385872002117
Princ ID:	290809782002116
AI Number:	14277
Facility Name:	H & R FOOD MART
AR Number:	44900
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK OLIVER/PRESIDENT

HIST UST AUSTIN:

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	459
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

H & R FOOD MART (Continued) **U001249726**

TX Financial Assurance 2:

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	276304
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	259014
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	240164
AI:	14277
Mechanism Type Other:	Not reported

H & R FOOD MART (Continued) **U001249726**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	212874
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	220358
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO

H & R FOOD MART (Continued) **U001249726**

Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	202525
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/27/2017
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	186087
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE

H & R FOOD MART (Continued) **U001249726**

City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	168888
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	149975
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	132159
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

H & R FOOD MART (Continued) **U001249726**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	116338
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	10798
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000

H & R FOOD MART (Continued) **U001249726**

Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81354
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81355
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214

H & R FOOD MART (Continued) **U001249726**

Finass ID:	81356
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81357
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81358
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

H & R FOOD MART (Continued) **U001249726**

Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81359
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81360
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2006
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO64843
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2007
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

H & R FOOD MART (Continued) **U001249726**

Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	97214
Finass ID:	81361
AI:	14277
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1989
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

HK919 **H & R FOOD MART** **TX CENTRAL REGISTRY** **S126557613**
Target **6400 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 3 in cluster HK

Actual:
668 ft.

Focus Map:
17

CENTRAL REGISTRY:

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN601101579
Customer Name:	OFLP-1 LTD
Customer Legal Name:	OFLP-1, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	7/19/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600733729
Customer Name:	OLIVER, GUY

H & R FOOD MART (Continued) **S126557613**

Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	2/1/2001
Affiliation End Date:	9/30/2002
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN603661398
Customer Name:	MTG MANAGEMENT INC
Customer Legal Name:	MTG MANAGEMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/8/2012
Affiliation End Date:	3/31/2019
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN604184739
Customer Name:	ATHYRIO INC
Customer Legal Name:	ATHYRIO INC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	7/18/1994
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN601275076
Customer Name:	E-Z SERVE PETROLEUM MARKETING COMPANY
Customer Legal Name:	E-Z Serve Petroleum Marketing Company
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1989

H & R FOOD MART (Continued) **S126557613**

Affiliation End Date:	8/31/1989
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102028248
Name:	H & R FOOD MART
Address:	6400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4502
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN605646710
Customer Name:	V&S ENTERPRISES LC
Customer Legal Name:	V&S Enterprises, LC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/1/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

---

920 **KWIK WASH COIN LAUNDRIES NO** **EDR Hist Cleaner** **1013783374**
Target **6500 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX 78745**

EDR Hist Cleaner

Actual:
660 ft.

Year:	Name:	Type:
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

Focus Map:
17

HL921 **ACME CLEANERS** **EDR Hist Cleaner** **1013778701**
Target **6630 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX 78745**

Site 1 of 8 in cluster HL

Actual:
655 ft.

EDR Hist Cleaner

Focus Map:
17

Year:	Name:	Type:
1980	ACME CLEANERS	CLEANERS AND DYERS
1984	BROWN JACK CLEANERS NO	CLEANERS AND DYERS
1990	BROWN JACK CLEANERS NO	CLEANERS AND DYERS
1998	BROWN JACK CLEANERS INC	Garment Pressing And Cleaners' Agents
1999	BROWN JACK CLEANERS INC	Garment Pressing And Cleaners' Agents
2000	BROWN JACK CLEANERS INC	Garment Pressing And Cleaners' Agents

HL922 **JACK BROWN CLEANERS 16** **TX CENTRAL REGISTRY** **S126683409**
Target **6650 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 8 in cluster HL

Actual:
655 ft.

Focus Map:
17

CENTRAL REGISTRY:

Regulated Entity Number:	RN103980835
Name:	JACK BROWN CLEANERS 16
Address:	6650 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4498
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600264543
Customer Name:	JACK BROWN CLEANERS INC
Customer Legal Name:	Jack Brown Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN103980835
Name:	JACK BROWN CLEANERS 16
Address:	6650 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4498
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600264543
Customer Name:	JACK BROWN CLEANERS INC
Customer Legal Name:	Jack Brown Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

HL923 **BROWN JACK CLEANERS INC** **EDR Hist Cleaner** **1018634522**
Target **6650 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 8 in cluster HL

Actual:
655 ft.

Focus Map:
17

EDR Hist Cleaner

Year:	Name:	Type:
1991	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1992	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1993	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1994	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1995	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1996	JACK BROWN CLEANERS 16	Garment Pressing And Cleaners' Agents
1997	BROWN JACK CLEANERS INC	Garment Pressing And Cleaners' Agents
2001	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

BROWN JACK CLEANERS INC (Continued) **1018634522**

2002	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2003	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2004	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2005	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2006	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2007	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2008	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

HL924 **JACK BROWN CLEANERS 16** **TX DRYCLEANERS** **S109360991**
Target **6650 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 4 of 8 in cluster HL

Actual:
655 ft.

Focus Map:
17

DRYCLEANERS:

Name:	JACK BROWN CLEANERS 16
Address:	6650 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
RN Number:	RN103980835
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	Not reported
Phone Number:	Not reported
Site Name:	JACK BROWN CLEANERS 16
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	JACK BROWN CLEANERS 16
Address:	6650 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
RN Number:	RN103980835
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	Not reported
Phone Number:	Not reported
Site Name:	JACK BROWN CLEANERS 16
Site Type:	DROP STATION REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported

JACK BROWN CLEANERS 16 (Continued) **S109360991**

Part Stat: YES
Gross Receipts: Not reported

HL925
Target Property

JACK BROWN CLEANERS 16
6650 S CONGRESS AVE
AUSTIN, TX 78745

FINDS **1010750839**
N/A

Site 5 of 8 in cluster HL

Actual: 655 ft.
Focus Map: 17

FINDS:
Registry ID: 110033875625

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

926
Target Property

PUBLIC STORAGE 20149
7112 S CONGRESS AVE
AUSTIN, TX 78745

TX CENTRAL REGISTRY **S126730664**
N/A

Actual: 656 ft.
Focus Map: 17

CENTRAL REGISTRY:

Regulated Entity Number:	RN104758263
Name:	PUBLIC STORAGE 20149
Address:	7112 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-5753
Status:	ACTIVE
Status Date:	2005-09-19
Customer Number:	CN602909517
Customer Name:	PS GPT PROPERTIES INC
Customer Legal Name:	Ps GPT Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-01-14
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	493110
Primary NAICS Industry Type Description:	General Warehousing and Storage
Physical Location Description:	Not reported

Regulated Entity Number:	RN104758263
Name:	PUBLIC STORAGE 20149
Address:	7112 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-5753
Status:	ACTIVE
Status Date:	2005-09-19
Customer Number:	CN602909517
Customer Name:	PS GPT PROPERTIES INC

PUBLIC STORAGE 20149 (Continued) **S126730664**

Customer Legal Name:	Ps GPT Properties, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-01-14
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	493110
Primary NAICS Industry Type Description:	General Warehousing and Storage
Physical Location Description:	Not reported

Regulated Entity Number:	RN104758263
Name:	PUBLIC STORAGE 20149
Address:	7112 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-5753
Status:	ACTIVE
Status Date:	2005-09-19
Customer Number:	CN602899767
Customer Name:	PS TEXAS HOLDINGS LTD
Customer Legal Name:	PS Texas Holdings, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2004-01-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	493110
Primary NAICS Industry Type Description:	General Warehousing and Storage
Physical Location Description:	Not reported

Regulated Entity Number:	RN104758263
Name:	PUBLIC STORAGE 20149
Address:	7112 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-5753
Status:	ACTIVE
Status Date:	2005-09-19
Customer Number:	CN602899767
Customer Name:	PS TEXAS HOLDINGS LTD
Customer Legal Name:	PS Texas Holdings, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2004-01-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	493110
Primary NAICS Industry Type Description:	General Warehousing and Storage
Physical Location Description:	Not reported

HM927 **AUSTIN ENGINE WORKS** **EDR Hist Auto** **1013753106**
Target **7305 CONGRESS AVE S** **N/A**
Property **AUSTIN, TX 78745**

Site 1 of 3 in cluster HM

Actual:
649 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1970	JAMES GULF STATION & GROCERY	GASOLINE STATIONS
1971	BUDDYS FEED & SERVICE STATION	Gasoline Service Stations
1972	BUDDYS FEED & SERVICE STATION	Gasoline Service Stations
1980	AUSTIN ENGINE WORKS	AUTOMOBILE REPAIRING

AUSTIN ENGINE WORKS (Continued) **1013753106**

1984 T N M TRAILER SALES AUTOMOBILE REPAIRING

HM928 **VACANT LOT** **TX CENTRAL REGISTRY** **S126537378**
Target **7307 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 3 in cluster HM

Actual:
649 ft.

Focus Map:
17

CENTRAL REGISTRY:

Regulated Entity Number:	RN101697977
Name:	VACANT LOT
Address:	7307 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6628
Status:	ACTIVE
Status Date:	3/16/2002
Customer Number:	CN600917355
Customer Name:	LEWIS LAWRENCE ET AL
Customer Legal Name:	Lewis Lawrence ET AL
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	7307 S Congress Ave., Austin

HM929 **VACANT LOT** **TX UST** **U003566434**
Target **7307 S CONGRESS AVE** **TX HIST UST** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 3 in cluster HM

Actual:
649 ft.

Focus Map:
17

UST:

Name:	VACANT LOT
Address:	7307 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
AI Number:	66264
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	683433552002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	FRED EARL LEWIS,FAMILY REP
Contact Organization Name:	VACANT LOT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

VACANT LOT (Continued) **U003566434**

Contact Telephone:	7135813285
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/05/1994
Signature Name/Title On Earliest Reg Form:	FRED EARL LEWIS,FAMILY REP
Application Received Date On Earliest Reg Form:	12/13/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600917355
Owner Last Name:	LEWIS LAWRENCE ET AL
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	673433552002075
Additional ID:	683433552002075
AI Number:	66264
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/13/1994
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172953
Facility ID:	99328
Ai Number:	66264
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/20/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

VACANT LOT (Continued) **U003566434**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	165407
UST ID:	172953
AI Number:	66264
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

VACANT LOT (Continued) **U003566434**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	LEWIS LAWRENCE ET AL
Contact Mailing Address (Delivery):	605 BELLAIRE CIR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ALVIN, TX 77511 3619
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	99328
Additional ID:	683433552002075
Princ ID:	673433552002075
AI Number:	66264
Facility Name:	VACANT LOT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	FRED LEWIS/

HIST UST AUSTIN:

Name:	VACANT LOT
Address:	7307 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0532

VACANT LOT (Continued) **U003566434**

HID UST: Not reported
Inspection: Not reported
Due: Not reported

---

930 **HIGHMARK** **TX CENTRAL REGISTRY** **S126887687**
Target **7440 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Actual:
633 ft.

Focus Map:
21

CENTRAL REGISTRY:

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603298068
Customer Name:	MERITAGE HOMES OF TEXAS LLC
Customer Legal Name:	Meritage Homes of Texas, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2015-08-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603298068
Customer Name:	MERITAGE HOMES OF TEXAS LLC
Customer Legal Name:	Meritage Homes of Texas, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2015-08-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603298068
Customer Name:	MERITAGE HOMES OF TEXAS LLC
Customer Legal Name:	Meritage Homes of Texas, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2015-08-18

HIGHMARK (Continued) **S126887687**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603298068
Customer Name:	MERITAGE HOMES OF TEXAS LLC
Customer Legal Name:	Meritage Homes of Texas, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2015-08-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN602641078
Customer Name:	CC CARLTON INDUSTRIES LTD
Customer Legal Name:	C.C. Carlton Industries, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2015-09-30
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN108725219
Name:	HIGHMARK
Address:	7440 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-6673
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN602641078
Customer Name:	CC CARLTON INDUSTRIES LTD
Customer Legal Name:	C.C. Carlton Industries, LTD.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2015-09-30
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

HIGHMARK (Continued) **S126887687**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN108725219
Name: HIGHMARK
Address: 7440 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-6673
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN602641078
Customer Name: CC CARLTON INDUSTRIES LTD
Customer Legal Name: C.C. Carlton Industries, LTD.
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 2015-09-30
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN108725219
Name: HIGHMARK
Address: 7440 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-6673
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN602641078
Customer Name: CC CARLTON INDUSTRIES LTD
Customer Legal Name: C.C. Carlton Industries, LTD.
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 2015-09-30
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

---

931 **SOCO II** **TX ASBESTOS** **S125923024**
Target **8100 S. CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Actual:
658 ft.

Focus Map:
21

ASBESTOS:
Name: SOCO II
Address: 8100 S. CONGRESS AVE
City,State,Zip: AUSTIN, TX 78745
Date of inspection: Not reported
Reason for Inspection: Reginald Powell
Violation: Not reported
Complaint Date: 09/06/2019
Notification Number: 2019006338
ASB Priority: Not reported
PIF State: Not reported
Detained: Not reported
Product Name: Not reported
Time Spent: Not reported
Travel Time: Not reported

SOCO II (Continued) **S125923024**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/20/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/20/2019
Certification Statement Phone:	210-408-8131
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	09/03/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HN932 Target Property | **SOCO SOUTH**
8103 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126954340**
N/A

Site 1 of 2 in cluster HN

Actual: 660 ft.
Focus Map: 21

CENTRAL REGISTRY:

Regulated Entity Number:	RN110757622
Name:	SOCO SOUTH
Address:	8103 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4390
Status:	ACTIVE
Status Date:	2019-04-18
Customer Number:	CN602792640
Customer Name:	NRP CONTRACTORS LLC
Customer Legal Name:	NRP Contractors LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2019-04-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

HN933 Target Property | **SOCO SOUTH**
8103 SOUTH CONGRESS AVE
AUSTIN, TX 78745 | **FINDS ECHO** | **1025471853**
N/A

Site 2 of 2 in cluster HN

Actual: 660 ft.
Focus Map: 21

FINDS:

Registry ID: 110070547522

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1025471853
Registry ID:	110070547522
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070547522
Name:	SOCO SOUTH
Address:	8103 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745

934 Target Property | **CAPITAL AREA FOOD BANK OF TEXAS**
8201 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126901175**
N/A

Actual: 674 ft.
Focus Map: 21

CENTRAL REGISTRY:

Regulated Entity Number:	RN109156810
Name:	CAPITAL AREA FOOD BANK OF TEXAS
Address:	8201 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7390
Status:	ACTIVE
Status Date:	4/5/2016
Customer Number:	CN605122480
Customer Name:	CENTRAL TEXAS FOOD BANK INC
Customer Legal Name:	Central Texas Food Bank, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/30/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	624210
Primary NAICS Industry Type Description:	Community Food Services
Physical Location Description:	Not reported

Regulated Entity Number:	RN109156810
Name:	CAPITAL AREA FOOD BANK OF TEXAS
Address:	8201 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7390
Status:	ACTIVE
Status Date:	4/5/2016
Customer Number:	CN605122480
Customer Name:	CENTRAL TEXAS FOOD BANK INC
Customer Legal Name:	Central Texas Food Bank, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/30/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	624210
Primary NAICS Industry Type Description:	Community Food Services
Physical Location Description:	Not reported

HO935 Target Property | **AARONS AUTO PARTS**
8409 S CONGRESS AVE
AUSTIN, TX 78745 | **TX CENTRAL REGISTRY** | **S126606661**
N/A

Site 1 of 9 in cluster HO

Actual: 687 ft.
Focus Map: 21

CENTRAL REGISTRY:

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN605353630
Customer Name:	BILL AARONS DISMANTLER INC
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2017-04-18

AARONS AUTO PARTS (Continued) **S126606661**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN605353630
Customer Name:	BILL AARONS DISMANTLER INC
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2017-04-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN605353630
Customer Name:	BILL AARONS DISMANTLER INC
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2017-04-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN605353630
Customer Name:	BILL AARONS DISMANTLER INC
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2017-04-18
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140

AARONS AUTO PARTS (Continued) **S126606661**

Primary NAICS Industry Type Description: Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description: Not reported

Regulated Entity Number: RN103099990
Name: AARONS AUTO PARTS
Address: 8409 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-7309
Status: ACTIVE
Status Date: 2003-04-15
Customer Number: CN600616262
Customer Name: AARONS AUTO PARTS
Customer Legal Name: Aaron's Auto Parts
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423140
Primary NAICS Industry Type Description: Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description: Not reported

Regulated Entity Number: RN103099990
Name: AARONS AUTO PARTS
Address: 8409 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-7309
Status: ACTIVE
Status Date: 2003-04-15
Customer Number: CN600616262
Customer Name: AARONS AUTO PARTS
Customer Legal Name: Aaron's Auto Parts
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423140
Primary NAICS Industry Type Description: Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description: Not reported

Regulated Entity Number: RN103099990
Name: AARONS AUTO PARTS
Address: 8409 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-7309
Status: ACTIVE
Status Date: 2003-04-15
Customer Number: CN600616262
Customer Name: AARONS AUTO PARTS
Customer Legal Name: Aaron's Auto Parts
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423140
Primary NAICS Industry Type Description: Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description: Not reported

AARONS AUTO PARTS (Continued) **S126606661**

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN600616262
Customer Name:	AARONS AUTO PARTS
Customer Legal Name:	Aaron's Auto Parts
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN602388076
Customer Name:	PRATHER, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	2001-10-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN602388076
Customer Name:	PRATHER, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	2001-10-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Regulated Entity Number:	RN103099990
Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE

AARONS AUTO PARTS (Continued) **S126606661**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-7309
Status:	ACTIVE
Status Date:	2003-04-15
Customer Number:	CN602388076
Customer Name:	PRATHER, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	2001-10-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423140
Primary NAICS Industry Type Description:	Motor Vehicle Parts (Used) Merchant Wholesalers
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
25 additional TX CENTRAL REG: record(s) in the EDR Site Report.

HO936 **AARONS AUTO PARTS** **FINDS** **1010714245**
Target **8409 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 9 in cluster HO

Actual:
687 ft.

Focus Map:
21

FINDS:
Registry ID: 110033395813

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

HO937 **AARONS AUTO PARTS** **TX ASBESTOS** **S113416807**
Target **8409 S CONGRESS AVE** **TX IHW CORR ACTION** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 9 in cluster HO

Actual:
687 ft.

Focus Map:
21

ASBESTOS:

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/04/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/02/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	02/14/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/02/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	02/12/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/03/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

AARONS AUTO PARTS (Continued) **S113416807**

ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/05/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/03/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/03/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/02/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE

AARONS AUTO PARTS (Continued) **S113416807**

City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/17/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/02/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/15/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/04/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/03/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/03/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

AARONS AUTO PARTS (Continued) **S113416807**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/17/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/03/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3

AARONS AUTO PARTS (Continued) **S113416807**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/03/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/15/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/04/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Date Report Received:	01/12/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/12/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	02/07/2018

AARONS AUTO PARTS (Continued) **S113416807**

Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/12/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/12/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	02/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/02/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/02/2018
Client Code:	Not reported

AARONS AUTO PARTS (Continued) **S113416807**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPILLMAN TRACTS
Address:	8409 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	11/21/2018
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	01/05/2018
Notification Number:	2017008783
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-442-1122

AARONS AUTO PARTS (Continued) **S113416807**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/03/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

IHW CORR ACTION:

Name:	AARONS AUTO PARTS
Address:	8409 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Program Id:	T1674
Location Desc:	Not reported
RN NUM:	RN103099990
Status:	INACTIVE
Status Date:	12/14/2005
EDR Link ID:	T1674
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	12/19/2005
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

HO938 **HUMPHRYS HANSEN** **TX CENTRAL REGISTRY** **S123848727**
Target **8411 SOUTH CONGRESS** **N/A**
Property **AUSTIN, TX 78701**

Site 4 of 9 in cluster HO

Actual:
687 ft.

Focus Map:
21

CENTRAL REGISTRY:

Regulated Entity Number:	RN100725746
Name:	HUMPHRYS HANSEN
Address:	8411 SOUTH CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600413272
Customer Name:	HUMPHRYS HANSEN INC
Customer Legal Name:	Humphrys Hansen Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	562998
Primary NAICS Industry Type Description:	All Other Miscellaneous Waste Management Services
Physical Location Description:	8411 SOUTH CONGRESS

HO939 **ANTIQUE ST LAMPS S CONGRS** **TX CENTRAL REGISTRY** **S123919997**
Target **8412 SOUTH CONGRESS** **N/A**
Property **AUSTIN, TX 78701**

Site 5 of 9 in cluster HO

Actual:
689 ft.

Focus Map:
21

CENTRAL REGISTRY:

Regulated Entity Number:	RN102183704
Name:	ANTIQUE ST LAMPS S CONGRS
Address:	8412 SOUTH CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	5/16/2002
Customer Number:	CN600267876
Customer Name:	ANTIQUE STREET LAMPS INC
Customer Legal Name:	Antique Street Lamps, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/7/1990
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	332323
Primary NAICS Industry Type Description:	Ornamental and Architectural Metal Work Manufacturing
Physical Location Description:	8412 SOUTH CONGRESS

HO940	**ANTIQUE STREET LAMPS INC**	**RCRA-SQG**	**1000656033**
Target	**8412 S CONGRESS AVEW**	**FINDS**	**TXD988059879**
Property	**AUSTIN, TX 78745**	**ECHO**	

Site 6 of 9 in cluster HO

Actual:
689 ft.

Focus Map:
21

RCRA Listings:

Date Form Received by Agency:	19911218
Handler Name:	Antique Street Lamps Inc
Handler Address:	S CONGRESS AVEW
Handler City,State,Zip:	AUSTIN, TX 78745-5675
EPA ID:	TXD988059879
Contact Name:	ROBERT PEERY
Contact Address:	8412 S CONGRESS AVEW
Contact City,State,Zip:	AUSTIN, TX 78745-5675
Contact Telephone:	512-282-9780
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS AVEW
Mailing City,State,Zip:	AUSTIN, TX 78745-5675
Owner Name:	Sc Properties
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ANTIQUE STREET LAMPS INC (Continued) **1000656033**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner

ANTIQUE STREET LAMPS INC (Continued) **1000656033**

Owner/Operator Name: SC PROPERTIES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3355 BEE CAVES RD #502
Owner/Operator City,State,Zip: AUSTIN, TX 78746
Owner/Operator Telephone: 512-327-5826
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19911218
Handler Name: ANTIQUE STREET LAMPS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005145565

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000656033
Registry ID: 110005145565
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005145565
Name: ANTIQUE STREET LAMPS INC

ANTIQUE STREET LAMPS INC (Continued) **1000656033**

Address: 8412 S CONGRESS AVEW
City,State,Zip: AUSTIN, TX 78745

HO941 **B AND L AUTO PART** **TX CENTRAL REGISTRY** **S123848706**
Target **8413 SOUTH CONGRESS** **N/A**
Property **AUSTIN, TX 78701**

Site 7 of 9 in cluster HO

Actual:
687 ft.

Focus Map:
21

CENTRAL REGISTRY:

Regulated Entity Number:	RN100725506
Name:	B AND L AUTO PART
Address:	8413 SOUTH CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600413058
Customer Name:	B AND L AUTO PART CO
Customer Legal Name:	B and L Auto Part Co
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	562998
Primary NAICS Industry Type Description:	All Other Miscellaneous Waste Management Services
Physical Location Description:	8413 SOUTH CONGRESS

HP942 **SHOP N CARRY FOOD STORE** **TX LPST** **S125401038**
Target **8514 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 1 of 5 in cluster HP

Actual:
690 ft.

Focus Map:
21

LPST:

Name:	SHOP N CARRY FOOD STORE
Address:	8514 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010996
LPST Id:	092335
Facility Location:	8514 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/22/1988
Entered Date:	12/08/1988
Reported Date:	10/28/1988
Closure Date:	10/28/1991
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	DELONDA ALEXANDER
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported

SHOP N CARRY FOOD STORE (Continued) **S125401038**

Responsible Party Address:	8514 S CONGRESS
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/280-2539
Reported Date:	10/28/1988
Case Start Date:	10/28/1991
Reference Number:	RN101493062
Project Manager:	DSA

HP943 **SHOP N CARRY** **TX ASBESTOS** **S119156662**
Target **8514 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 2 of 5 in cluster HP

Actual:
690 ft.

Focus Map:
21

ASBESTOS:

Name:	SHOP N CARRY
Address:	8514 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/07/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.7
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/11/2013
Date Routed by Supervisor:	02/11/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported

SHOP N CARRY (Continued) **S119156662**

Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HP944 **TOSCO MARKETING COMPANY** **EDR Hist Auto** **1020371376**
Target **8514 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 3 of 5 in cluster HP

Actual: EDR Hist Auto
690 ft.

Focus Map:
21

Year:	Name:	Type:
1993	CIRCLE K CORPORATION	Convenience Stores
1994	CIRCLE K CORPORATION	Convenience Stores
1995	CIRCLE K STORES INC	Convenience Stores
1996	CIRCLE K STORES INC	Convenience Stores
1997	TOSCO MARKETING COMPANY	Convenience Stores
1998	TOSCO MARKETING COMPANY	Convenience Stores
1999	TOSCO MARKETING COMPANY INC	Convenience Stores

HP945 **SHOP N CARRY FOOD STORE** **TX LPST** **S125401013**
Target **8514 S CONGRESS AVE** **N/A**
Property **AUSTIN, TX 78745**

Site 4 of 5 in cluster HP

Actual: LPST:
690 ft.

Focus Map:
21

Name:	SHOP N CARRY FOOD STORE
Address:	8514 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010996
LPST Id:	111287

SHOP N CARRY FOOD STORE (Continued) **S125401013**

Facility Location:	8514 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/20/1996
Entered Date:	07/10/1996
Reported Date:	06/20/1996
Closure Date:	03/31/1997
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1
Coordinators RPR:	MMW
Responsible Party Name:	Not reported
Responsible Party Contact:	RAMZAN JIWAMI
Responsible Party Address:	8514 S CONGRESS AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/280-2539
Reported Date:	06/20/1996
Case Start Date:	03/31/1997
Reference Number:	RN101493062
Project Manager:	MMW

HP946 **OAKS AT SLAUGHTER BLOCK B LOT** **TX CENTRAL REGISTRY** **S128242870**
Target **NORTHEAST CORNER OF S CONGRESS AVE AND RALPH ABLANEDO DRIVE** **N/A**
Property **AUSTIN, TX 78745**

Site 5 of 5 in cluster HP

Actual:
688 ft.

Focus Map:
21

CENTRAL REGISTRY:

Regulated Entity Number:	RN111215471
Name:	OAKS AT SLAUGHTER BLOCK B LOT
Address:	NORTHEAST CORNER OF S CONGRESS AVE AND RALPH ABLANEDO DRIVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745
Status:	ACTIVE
Status Date:	3/10/2021
Customer Number:	CN605866474
Customer Name:	SOCO 35 RETAIL LTD
Customer Legal Name:	SOCO 35 RETAIL, LTD.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/3/2021
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	NORTHEAST CORNER OF S CONGRESS AVE AND RALPH ABLANEDO DRIVE

GD947 WNW < 1/8 0.011 mi. 60 ft. | **TEXAN MKT 5**
2700 S CONGRESS AVE
AUSTIN, TX 78704
Site 5 of 5 in cluster GD | **TX LPST, TX UST, TX HIST UST, TX ASBESTOS** | **U001254477, N/A**

Actual: 620 ft.

Focus Map: 14

LPST:

Name:	TEXAN MARKET 5
Address:	2700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0019603
LPST Id:	091135
Facility Location:	2700 S CONGRESS @ CUMBERLAND
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/07/1986
Entered Date:	09/17/1986
Reported Date:	09/17/1986
Closure Date:	06/18/1998
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/4/1/4
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	STACY OLIVER
Responsible Party Address:	201 W STASSNEY LN STE 512
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/448-0585
Reported Date:	09/17/1986
Case Start Date:	06/18/1998
Reference Number:	RN102429867
Project Manager:	HWELCH

UST:

Name:	TEXAN MKT 5
Address:	2700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787046422
AI Number:	19603
Facility Type:	RETAIL
Facility Begin Date:	09/05/1986
Facility Status:	INACTIVE
Additional ID:	747690712002152
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

TEXAN MKT 5 (Continued) **U001254477**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	T ROSS,GEN MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601253164
Owner Last Name:	STARTEX FIRST EQUIPMENT LIMITED PARTNERSHIP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	192614792002152
Additional ID:	747690712002152
AI Number:	19603
Owner Effective Begin Date:	09/08/1994
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50405
Facility ID:	75962
Ai Number:	19603
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/22/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

TEXAN MKT 5 (Continued) **U001254477**

Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	121628
UST ID:	50405
AI Number:	19603
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

TEXAN MKT 5 (Continued) **U001254477**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50407
Facility ID:	75962
Ai Number:	19603
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/22/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

TEXAN MKT 5 (Continued) **U001254477**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	121630
UST ID:	50407
AI Number:	19603
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

TEXAN MKT 5 (Continued) **U001254477**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50406
Facility ID:	75962
Ai Number:	19603
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/22/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

TEXAN MKT 5 (Continued) **U001254477**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	121629
UST ID:	50406
AI Number:	19603
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

TEXAN MKT 5 (Continued) **U001254477**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	STARTEX FIRST EQUIPMENT LTD
Contact Mailing Address (Delivery):	PO BOX 6110
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6110
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	75962
Additional ID:	747690712002152
Princ ID:	192614792002152
AI Number:	19603
Facility Name:	TEXAN MKT 5
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	TEXAN MARKET #5
Address:	2700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	848
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	SMART MART
Address:	2700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported

TEXAN MKT 5 (Continued) **U001254477**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

TEXAN MKT 5 (Continued) **U001254477**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SMART MART
Address:	2700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/28/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

TEXAN MKT 5 (Continued) **U001254477**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HQ948 **IVORY CLEANERS & ALTERATIONS** **EDR Hist Cleaner** **1020010354**
East **1901 RIO GRANDE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.011 mi.
60 ft. **Site 1 of 4 in cluster HQ**

Actual:
571 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1999	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2000	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2001	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2002	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2003	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2004	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2005	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2006	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2007	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2008	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2009	IVORY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs

---

HQ949 **ADAMS SERVICE CO GAS ST** **EDR Hist Auto** **1013753816**
East **1901 RIO GRANDE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.011 mi.
60 ft. **Site 2 of 4 in cluster HQ**

Actual:
571 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	HOWELLS CHAS SERVICE	GASOLINE AND OIL SERVICE STATIONS
1947	BRANYON SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	ROGERS GULF SERV STA	GASOLINE STATIONS
1958	UNIVERSITY GULF	GASOLINE STATIONS
1962	ADAMS SERV CO GAS	GASOLINE STATIONS
1965	ADAMS HENRY GARAGE AUTO	AUTOMOBILE REPAIRING
1965	ADAMS SERVICE CO GAS STA	GASOLINE STATIONS
1969	ADAMS SERVICE CENTER	Gasoline Service Stations
1969	ADAMS SERVICE CO	Gasoline Service Stations

ADAMS SERVICE CO GAS ST (Continued) **1013753816**

1970	ADAMS SERVICE CO GAS ST	GASOLINE STATIONS
1970	ADAMS HENRY GAI AGE AUTO REPR	AUTOMOBILE REPAIRING
1970	ADAMS SERVICE CO	Gasoline Service Stations
1970	ADAMS SERVICE CENTER	Gasoline Service Stations
1971	ADAMS SERVICE CENTER	Gasoline Service Stations
1971	ADAMS SERVICE CO	Gasoline Service Stations
1972	ADAMS SERVICE CO	Gasoline Service Stations
1972	ADAMS SERVICE CENTER	Gasoline Service Stations
1973	ADAMS SERVICE CENTER	Gasoline Service Stations
1973	ADAMS SERVICE CO	Gasoline Service Stations
1974	ADAMS SERVICE CO	Gasoline Service Stations
1974	ADAMS SERVICE CENTER	Gasoline Service Stations
1975	ADAMS HENRY GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	ADAMS SERVICE CO GAS ST	GASOLINE STATIONS
1975	ADAMS SERVICE CO	Gasoline Service Stations
1976	ADAMS SERVICE CENTER	Gasoline Service Stations
1977	ADAMS SERVICE CENTER	Gasoline Service Stations
1979	ADAMS HENRY SERVICE	Gasoline Service Stations
1980	ADAMS SERVICE CO GAS ST	GASOLINE STATIONS
1980	ADAMS HENRY GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1980	ADAMS HENRY SERVICE	Gasoline Service Stations
1982	ADAMS HENRY SERVICE	Gasoline Service Stations
1983	ADAMS HENRY SERVICE	Gasoline Service Stations

HQ950 **7-ELEVEN 23630** **TX UST** **U001243595**
East **1901 RIO GRANDE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.011 mi.
60 ft. **Site 3 of 4 in cluster HQ**

Actual:
571 ft.

Focus Map:
11

UST:

Name:	7-ELEVEN 23630
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 787055515
AI Number:	7172
Facility Type:	RETAIL
Facility Begin Date:	07/08/1986
Facility Status:	INACTIVE
Additional ID:	732115942002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	7-ELEVEN 23630
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2149070711
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986

7-ELEVEN 23630 (Continued) **U001243595**

Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	732115942002117
AI Number:	7172
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18609
Facility ID:	46174
Ai Number:	7172
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/07/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

7-ELEVEN 23630 (Continued) **U001243595**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26089
UST ID:	18609
AI Number:	7172
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

7-ELEVEN 23630 (Continued) **U001243595**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18607
Facility ID:	46174
Ai Number:	7172
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/07/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

7-ELEVEN 23630 (Continued) **U001243595**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26087
UST ID:	18607
AI Number:	7172
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

7-ELEVEN 23630 (Continued) **U001243595**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18608
Facility ID:	46174
Ai Number:	7172
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/07/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

7-ELEVEN 23630 (Continued) **U001243595**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26088
UST ID:	18608
AI Number:	7172
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

7-ELEVEN 23630 (Continued) **U001243595**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	24767
Facility ID:	46174
AI Number:	7172
Application Received Date:	10/01/2013
Scheduled Construction Date:	09/30/2013
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	10/01/2013
Signature Date On Form:	09/27/2013
Signature Name On Form:	KEVIN DENSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	REMOVAL OF A GHOST WASTE OIL TANK DISCOVERED AT AN ACTIVE CONSTRUCTION SITE. MASS EXCAVATION IS ONGOING.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	58028
UST ID:	Not reported
NOC ID:	24767
AI Number:	7172
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON CONSULTANTS INC
Representative Name:	KEVIN DENSON
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported

7-ELEVEN 23630 (Continued) **U001243595**

Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	4421181
Email Address:	Not reported

Cont/Cons/Installer ID:	58029
UST ID:	Not reported
NOC ID:	24767
AI Number:	7172
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	GRUENE ENVIRONMENTAL COMPANIES
Representative Name:	RYAN LAMBERT
Mailing Address (Delivery):	11 NAFTA CIRCLE
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	830
Fax Number:	6267576
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46174
Additional ID:	732115942002117
Princ ID:	959578622001257
AI Number:	7172
Facility Name:	7-ELEVEN 23630
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name: SEVEN ELEVEN #23630

7-ELEVEN 23630 (Continued) **U001243595**

Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0325
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

HQ951 **IVORY CLEANERS & ALTERATIONS** **TX LPST** **S108527034**
East **1901 RIO GRANDE ST** **TX VCP** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX ASBESTOS**
0.011 mi. **TX DRYCLEANERS**
60 ft. **Site 4 of 4 in cluster HQ** **TX GCC**
TX COMP HIST

Actual:
571 ft.

Focus Map:
11

LPST:

Name:	MLKRIO GRANDE SITE
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0007172
LPST Id:	119160
Facility Location:	1901 RIO GRANDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/08/2013
Entered Date:	07/02/2013
Reported Date:	04/01/2013
Closure Date:	02/10/2014
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	11 - VCP
CA Status:	6P - FINAL PENDING WELL PLUG
Priority Description:	4.0
Status:	**PREASSESSMENT/RELEASE DETERMINATION**
Coordinators Primary:	11/1
Coordinators RPR:	VKM
Responsible Party Name:	Not reported
Responsible Party Contact:	STEPHEN HAUG
Responsible Party Address:	4801 SPICEWOOD SPRINGS RD STE 100
Responsible Party City,St,Zip:	AUSTIN, TX 78759
Responsible Party Telephone:	512/343-4555
Reported Date:	04/01/2013
Case Start Date:	02/10/2014
Reference Number:	RN102018033
Project Manager:	VMODAK

VCP TCEQ:

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	REGION 11 - AUSTIN
Facility ID:	2578
VCP Record Date:	Not reported
Facility Type:	PROPERTY VACANT
PCA Number:	34771
Project Manager:	JSTEFEK
Phase:	COMPLETED
Acres at Site:	0.80

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

REM Program:	VCP
RN Number:	RN102018033
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	Not reported
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	02/10/2014
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	04/05/2013
GW Target COC Class:	CHLORINATED SOLVENTS; VOCS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2013-06-04 00:00:00
Soil Target COC Class:	VOCS; CHLORINATED SOLVENTS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2578
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	347710
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/ROOM 200-39; D2/211
Latitude:	30.28
Longitude:	-97.75

ASBESTOS:

Name:	ASPEN WEST CAMPUS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	Not reported
Reason for Inspection:	JOHN R NELSON
Violation:	Not reported
Complaint Date:	09/29/2016
Notification Number:	2016007460
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/02/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/26/2016
Certification Statement Phone:	512-369-3030
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/09/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

DRYCLEANERS:

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102018033
Region:	11
CN Number:	CN602511107
DCR Number:	Not reported
AR Number:	24001637
Principal Name:	IVORY CLEANERS II INC
Bill Addr1:	3800 ALAZAN CIR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78734 1607
EMail:	Not reported
Phone Number:	Not reported
Site Name:	IVORY CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102018033
Region:	11
CN Number:	CN602511107
DCR Number:	Not reported
AR Number:	24001637
Principal Name:	IVORY CLEANERS II INC
Bill Addr1:	3800 ALAZAN CIR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78734 1607
EMail:	Not reported
Phone Number:	Not reported
Site Name:	IVORY CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102018033
Region:	11
CN Number:	CN602511107
DCR Number:	Not reported
AR Number:	24001637
Principal Name:	IVORY CLEANERS II INC
Bill Addr1:	3800 ALAZAN CIR

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78734 1607
EMail:	Not reported
Phone Number:	Not reported
Site Name:	IVORY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102018033
Region:	11
CN Number:	CN602511107
DCR Number:	Not reported
AR Number:	24001637
Principal Name:	IVORY CLEANERS II INC
Bill Addr1:	3800 ALAZAN CIR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78734 1607
EMail:	Not reported
Phone Number:	Not reported
Site Name:	IVORY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PERC
Gallons:	50
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102018033
Region:	11
CN Number:	CN602511107
DCR Number:	Not reported
AR Number:	24001637
Principal Name:	IVORY CLEANERS II INC
Bill Addr1:	3800 ALAZAN CIR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78734 1607
EMail:	Not reported
Phone Number:	Not reported
Site Name:	IVORY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

Gross Receipts: $150,000 OR LESS

Name: IVORY CLEANERS & ALTERATIONS
Address: 1901 RIO GRANDE ST
City,State,Zip: AUSTIN, TX 78705
RN Number: RN102018033
Region: 11
CN Number: CN602511107
DCR Number: Not reported
AR Number: 24001637
Principal Name: IVORY CLEANERS II INC
Bill Addr1: 3800 ALAZAN CIR
Bill Addr2: Not reported
Bill City/State/Zip: AUSTIN, TX 78734 1607
EMail: Not reported
Phone Number: Not reported
Site Name: IVORY CLEANERS & ALTERATIONS
Site Type: DROP STATION REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2009
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: $150,000 OR LESS

GCC:
Name: MLK/RIO GRANDE SITE
Address: 1901 RIO GRANDE ST
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: *
File Number: 2578
Contamination Description: VOCS, CHLORINATED SOLVENTS, TPH
Date Of Earliest Known Contamination Confirmation: 4/5/2013
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: MLK/RIO GRANDE SITE
Address: 1901 RIO GRANDE STREET
City,State,Zip: AUSTIN, TX
Division: REM/DCRP
New Cases: Not reported
File Number: 2578
Contamination Description: VOCS, CHLORINATED SOLVENTS, TPH
Date Of Earliest Known Contamination Confirmation: 4/5/2013
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

COMP HIST:

RN Number:	RN102018033
Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	TX 78705
Region:	REGION 11 - AUSTIN
CN Number:	CN604321331
CN Name:	ROLLING CASH TEXAS VENTURE LP
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	812320
SIC Code:	1542
Related Number:	R11109296038

RN Number:	RN102018033
Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	TX 78705
Region:	REGION 11 - AUSTIN
CN Number:	CN602511107
CN Name:	IVORY CLEANERS II INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	812320
SIC Code:	1522
Related Number:	19629

RN Number:	RN102018033
Name:	IVORY CLEANERS & ALTERATIONS
Address:	1901 RIO GRANDE ST
City,State,Zip:	TX 78705
Region:	REGION 11 - AUSTIN
CN Number:	CN600240329
CN Name:	7-ELEVEN INC
CN Rating:	.34
Classification:	SATISFACTORY

IVORY CLEANERS & ALTERATIONS (Continued) **S108527034**

Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	812320
SIC Code:	5541
Related Number:	36529

FG952 **HI TECH AUTOMOTIVE** **TX RDR** **S127542822**
ESE **1801 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.011 mi.
60 ft. **Site 3 of 8 in cluster FG**

Actual:
569 ft.

Focus Map:
14

RDR:

RDR ID:	15395
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	HI TECH AUTOMOTIVE
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/10/2006
Due Date:	9/8/2006
Tank Owner:	WILLIAM DYE
Contact Person:	BILL DYE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/30/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/30/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FG953 **HI TECH AUTOMOTIVE** **TX UST** **U004053511**
ESE **1801 S CONGRESS AVE** **TX ENF** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX NON REGIST PST**
0.011 mi.
60 ft. **Site 4 of 8 in cluster FG**

Actual:
569 ft.

Focus Map:
14

UST:

Name:	HI TECH AUTOMOTIVE
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787043501
AI Number:	78051

HI TECH AUTOMOTIVE (Continued) **U004053511**

Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	922276122006257
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	WILLIAM DYE,
Contact Organization Name:	HI TECH AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5126362475
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/28/2006
Signature Name/Title On Earliest Reg Form:	WILLIAM A DYE,OWNER
Application Received Date On Earliest Reg Form:	06/28/2006
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN603041427
Owner Last Name:	DYE
Owner First Name:	WILLIAM
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	896327342006151
Additional ID:	922276122006257
AI Number:	78051
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

HI TECH AUTOMOTIVE (Continued) **U004053511**

Install Date:	08/31/1987
Tank Registration Date:	06/28/2006
Number of Compartments:	1
Tank Capacity:	750
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	206864
Facility ID:	120292
Ai Number:	78051
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/30/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

HI TECH AUTOMOTIVE (Continued) **U004053511**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	750
UST Comprt ID:	180793
UST ID:	206864
AI Number:	78051
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	21369
Facility ID:	120292
AI Number:	78051
Application Received Date:	05/15/2006
Scheduled Construction Date:	05/30/2006
UST Improvement:	N

HI TECH AUTOMOTIVE (Continued) **U004053511**

UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60515009
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	66014
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	22418
UST ID:	Not reported
NOC ID:	21369
AI Number:	78051
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000068
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DYE WILLIAM
Contact Mailing Address (Delivery):	3716 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 7216
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

HI TECH AUTOMOTIVE (Continued) **U004053511**

Contact Address Deliverable:	Y
Facility ID:	120292
Additional ID:	922276122006257
Princ ID:	896327342006151
AI Number:	78051
Facility Name:	HI TECH AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	WILLIAM DYE/

ENFORCEMENT:

Name:	4C18 - 1801 CONGRESS
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704-3501
Unique TCEQ Ref Number Of Customer:	CN604082230
Unique TCEQ Ref Number Of Reg. Entity:	RN104960117
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	FLINTCO LLC
Regulated Entity Associated With An NOV:	FLEET REFUELING
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001644105
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	241,405,862,020,122.00
Role Code:	Not reported
Date Notice Of Violation Issued:	05/08/2020
Description 1:	Failure to post a construction site notice where it is safely and readily available for viewing by the general public, local, state, and federal authorities.
Description 2:	Photographic documentation was provided that demonstrated the construction site notice had been properly located in accordance with the permit.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	281.25(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1644105
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

HI TECH AUTOMOTIVE (Continued) **U004053511**

Name:	HI-TECH AUTOMOTIVE
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN603041427
Unique TCEQ Ref Number Of Reg. Entity:	RN104960117
Contact Person For The Reg. Entity:	WILLIAM DYE
Owner/operator Of A Regulated Entity:	DYE, WILLIAM
Regulated Entity Associated With An NOV:	FLEET REFUELING
Org Title Of The Contact Person:	OWNER
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	06/12/2006
Description 1:	Failure to register with the TCEQ, on authorized TCEQ forms, an underground storage tank (UST) in existence on or after September 1, 1987.
Description 2:	Compliance documentation was received on June 28, 2006 resolving the alleged outstanding violation.
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	334.7
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

NON REGIST PST:

RN Number:	RN104960117
Name:	4C18 - 1801 CONGRESS
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704 3501
Physical Location:	No physical location description ON file.
CN Number:	CN603041427
Customer Name:	DYE, WILLIAM
Customer Role:	OWNER
Primary Business:	FLEET REFUELING
Code:	1542
Classification:	SIC
Industry Name:	General Contractors-Nonresidential Buildings
Program:	PETROLEUM STORAGE TANK NON REGISTERED

HI TECH AUTOMOTIVE (Continued) **U004053511**

ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=228331312006151

RN Number:	RN104960117
Name:	4C18 - 1801 CONGRESS
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704 3501
Physical Location:	No physical location description ON file.
CN Number:	CN604082230
Customer Name:	FLINTCO LLC
Customer Role:	OPERATOR
Primary Business:	FLEET REFUELING
Code:	1795
Classification:	SIC
Industry Name:	Wrecking and Demolition Work
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=228331312006151

RN Number:	RN104960117
Name:	4C18 - 1801 CONGRESS
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704 3501
Physical Location:	No physical location description ON file.
CN Number:	CN604999292
Customer Name:	HI TECH AUTOMOTIVE
Customer Role:	OWNER
Primary Business:	FLEET REFUELING
Code:	1795
Classification:	SIC
Industry Name:	Wrecking and Demolition Work
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=228331312006151

FG954 **A. D. DYE** **TX HIST UST** **S128729214**
ESE **1801 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.011 mi.
60 ft. **Site 5 of 8 in cluster FG**

Actual:
569 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	A. D. DYE
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0212
HID UST:	212
Inspection:	Not reported
Due:	06/01/2012

FG955 **DYE CHARLES** **EDR Hist Auto** **1020571718**
ESE **1801 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.011 mi.
60 ft. **Site 6 of 8 in cluster FG**

Actual:
569 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1969	DYE CHARLES A	Gasoline Service Stations
1970	DYE CHARLES A	Gasoline Service Stations
1971	DYE CHARLES A	Gasoline Service Stations
1972	DYE CHARLES A	Gasoline Service Stations
1973	DYE CHARLES A	Gasoline Service Stations
1974	DYE CHARLES A	Gasoline Service Stations
1975	DYE CHARLES A	Gasoline Service Stations
1976	DYE CHARLES	Gasoline Service Stations
1977	DYE CHARLES	Gasoline Service Stations
1978	DYE CHARLES	Gasoline Service Stations
1979	DYE CHARLES	Gasoline Service Stations
1980	DYE CHARLES	Gasoline Service Stations
1982	DYE CHARLIE	Gasoline Service Stations
1983	DYE CHARLIE	Gasoline Service Stations
1985	DYE CHARLIE	Gasoline Service Stations
1986	BUSH NET	Gasoline Service Stations
1988	JUSTIN S AUTOMOTIVE	General Automotive Repair Shops
1988	HI TECH AUTOMOTIVE	General Automotive Repair Shops
1989	HI TECH AUTOMOTIVE	General Automotive Repair Shops
1990	HI TECH AUTOMOTIVE	General Automotive Repair Shops
1992	T H F C CORPORATION	General Automotive Repair Shops
1993	T H F C CORPORATION	General Automotive Repair Shops
1994	T H F C CORPORATION	General Automotive Repair Shops
1995	T H F C CORPORATION	General Automotive Repair Shops
1996	T H F C CORPORATION	General Automotive Repair Shops
1997	T H F C CORPORATION	General Automotive Repair Shops
1998	T H F C CORPORATION	General Automotive Repair Shops
1999	T H F C CORPORATION	General Automotive Repair Shops
2000	T H F C CORPORATION	General Automotive Repair Shops
2001	T H F C CORPORATION	General Automotive Repair Shops
2002	T H F C CORPORATION	General Automotive Repair Shops
2003	T H F C CORPORATION	General Automotive Repair Shops
2004	T H F C CORPORATION	General Automotive Repair Shops
2005	T H F C CORPORATION	General Automotive Repair Shops
2006	T H F C CORPORATION	General Automotive Repair Shops
2007	THFC CORPORATION	General Automotive Repair Shops
2008	THFC CORPORATION	General Automotive Repair Shops
2009	THFC CORPORATION	General Automotive Repair Shops
2010	THFC CORPORATION	General Automotive Repair Shops
2011	THFC CORPORATION	General Automotive Repair Shops
2012	THFC CORPORATION	General Automotive Repair Shops
2013	THFC CORPORATION	General Automotive Repair Shops
2014	THFC CORPORATION	General Automotive Repair Shops

FG956 ESE < 1/8 0.011 mi. 60 ft. | **DYE AUTOMOTIVE**
1801 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S128728872**
N/A

Site 7 of 8 in cluster FG

Actual: 569 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	DYE AUTOMOTIVE
Address:	1801 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0039
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

HR957 WNW < 1/8 0.011 mi. 60 ft. | **WESLEY GEORGE CLEANERS**
606 GUADALUPE ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013781047**
N/A

Site 1 of 2 in cluster HR

Actual: 502 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1940	WESLEY GEO CLDO	CLEANERS, PRESSERS AND DYERS
1940	WESLEY GEO CLDO	DYERS AND CLEANERS
1940	WESLEY GEO CLDO	DRY CLEANERS
1940	WESLEY GEO CLDO	CLOTHES PRESSERS AND CLEANERS
1940	WESLEY GEO CLDO	RUG CLEANERS
1947	WESLEY GEO CLEANERS	DYERS AND CLEANERS
1947	WESLEY GEO CLEANERS	CLOTHES PRESSERS AND CLEANERS
1947	WESLEY GEO CLEANERS	HAT CLEANERS AND BLOCKERS
1953	WESLEY GEO CLDO	HAT CLEANERS AND BLOCKERS
1953	WESLEY GEO CLDO	CLEANERS AND DYERS
1958	WESLEY GEO CLNS	HAT CLEANERS AND BLOCKERS
1958	WESLEY GEO CLNS	CLEANERS AND DYERS
1962	606 08 WESLEY GEO CLN	CLEANERS AND DYERS
1965	WESLEY GEORGE CLEANERS	CLEANERS AND DYERS
1969	WESLEY GEORGE CLEANERS	Drycleaning Plants, Except Rugs
1970	WESLEY GEO CLEANER S	CLEANERS AND DYERS

HR958 WNW < 1/8 0.011 mi. 60 ft. | **FIEGEL GEO JR AUTO**
606 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013754103**
N/A

Site 2 of 2 in cluster HR

Actual: 502 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1922	FIEGEL GEO JR AUTO	AUTOMOBILE REPAIRERS

HS959 **HEB GROCERY** **TX RDR** **S127535795**
NE **2508 RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
61 ft. **Site 1 of 6 in cluster HS**

Actual:
486 ft.

Focus Map:
15

RDR:

RDR ID:	20693
Facility ID:	55951
RN:	Not reported
CN:	Not reported
Name:	HEB GROCERY
Address:	2508 RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/14/2012
Due Date:	10/13/2012
Tank Owner:	HEB GROCERY CO
Contact Person:	TERRY PARR
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/17/2012
Project Manager:	Jennifer Robinson
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	JLR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/17/2012
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DY960 **OWL TAXI SERVICE** **TX HIST UST** **S111678769**
NNE **100 W 3RD ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
61 ft. **Site 2 of 11 in cluster DY**

Actual:
478 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	OWL TAXI SERVICE
Address:	100 W 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0680
HID UST:	680
Inspection:	Not reported
Due:	06/01/2012

BX961 **LONGHORN CLEANERS NO** **EDR Hist Cleaner** **1013780756**
East **705 W 24TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
61 ft. **Site 2 of 4 in cluster BX**

Actual:
596 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	LONGHORN CLEANERS NO	CLEANERS AND DYERS

BX962 **CIRCLE K CORPORATION** **EDR Hist Auto** **1021234190**
East **705 W 24TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
61 ft. **Site 3 of 4 in cluster BX**

Actual:
596 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1993	CIRCLE K CORPORATION	Convenience Stores
1994	CIRCLE K CORPORATION	Convenience Stores
1995	CIRCLE K CORPORATION	Convenience Stores

DO963 **GABLES RESIDENTIAL** **TX HIST UST** **S108837198**
ESE **401 GUADALUPE ST** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX IOP**
0.012 mi.
61 ft. **Site 5 of 5 in cluster DO**

Actual:
480 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	401 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX
Id UST:	C0706
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GCC:

Name:	GABLES RESIDENTIAL
Address:	401 GUADALUPE
City,State,Zip:	AUSTIN, TX
Division:	RMD/VCIO
New Cases:	Not reported
File Number:	629
Contamination Description:	VOCS, METALS
Date Of Earliest Known Contamination Confirmation:	7/3/2007
Enforcement Status - Level Of Agency Response:	6 -
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported

GABLES RESIDENTIAL (Continued) **S108837198**

Data Quality 2: Not reported

IOP:

Name:	GABLES RESIDENTIAL
Address:	401 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78701
Program ID:	629
Date IOP Received:	Not reported
Region:	REGION 11 - AUSTIN
Phase:	COMPLETED
Interest In Site:	Not reported
PCA Number:	32629
Property Use:	PROPERTY VACANT
Project Manager:	RKYGAR
Project Number:	326290
Latitude:	30.27
Longitude:	-97.75
Acres:	0.4
Media Affected:	Not reported
LPST Number:	Not reported
VCP ID:	Not reported
Cert Issued:	04/16/2008
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN105271951
Consultant/Attorney Phone:	Not reported
Site Address Description:	NEC OF THE INTERSECTION OF GUADALUPE AND 4TH STS
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	07/03/2007
Application Received Date:	07/03/2007
Application Acceptance Date:	Not reported
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	Not reported

GABLES RESIDENTIAL (Continued) **S108837198**

Customer:

REM Program:	IOP
Program ID:	629
RN Number:	RN105271951
CN Number:	CN603011586
CN Name:	GABLES RESIDENTIAL
Role CD:	BILLCONT
Contact Name:	WITHERS, WILL
Contact Title:	Not reported
Organization Name:	GABLES RESIDENTIAL
Mailing Address:	6850 AUSTIN CENTER BLVD STE 200
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78731
Contact Phone:	(512) 502-6014
Contact Ext:	0

REM Program:	IOP
Program ID:	629
RN Number:	RN105271951
CN Number:	CN603011586
CN Name:	GABLES RESIDENTIAL
Role CD:	APPLCONT
Contact Name:	WITHERS, WILL
Contact Title:	DEVELOPMENT ASSOCIATE
Organization Name:	LG GUADALUPE LP
Mailing Address:	6850 AUSTIN CENTER BLVD STE 200
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78731
Contact Phone:	(512) 502-6014
Contact Ext:	0

BG964 **CVS PHARMACY 6892** **RCRA NonGen / NLR** **1014961741**
ESE **2927 GUADALUPE ST** **TXR000080904**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
61 ft. **Site 4 of 8 in cluster BG**

Actual:
594 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20221230
Handler Name:	Cvs Pharmacy 6892
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705-3721
EPA ID:	TXR000080904
Contact Name:	WENDY BRANT
Contact Address:	CVS DR
Contact City,State,Zip:	WOONSOCKET, RI 02895-6146
Contact Telephone:	401-765-1500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CVS PHARMACY 6892 (Continued) **1014961741**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	CVS DR
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cvs Pharmacy Inc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230109
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:
Year: 2017

CVS PHARMACY 6892 (Continued) **1014961741**

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

CVS PHARMACY 6892 (Continued) **1014961741**

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U010
Waste Description: Azirino [2',3':3,4]Pyrrolo[1,2-A]Indole-4,7-Dione, 6-Amino-8-[[(Aminocarbonyl)Oxy]Methyl]-1,1a,2,8,8a,8b-Hexahydro-8a-Methoxy-5-Methyl-, [1as-(1aalpha, 8beta, 8aalpha, 8balpha)]- (Or) Mitomycin C

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U059
Waste Description: 5,12-Naphthacenedione, 8-Acetyl-10-[(3-Amino-2,3,6-Trideoxy)-Alpha-L-Lyxo-Hexopyranosyl)Oxy]-7,8,9,10-Tetrahydro-6,8,11-Trihydroxy-1-Methoxy-, (8s-Cis)- (Or) Daunomycin

Waste Code: U070
Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

CVS PHARMACY 6892 (Continued) **1014961741**

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4'-(1,2-Diethyl-1,2-Ethenediyl)Bis, (E)-

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2'-Methylenebis[3,4,6-Trichloro-

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U151
Waste Description: Mercury

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U188
Waste Description: Phenol

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U206
Waste Description: D-Glucose, 2-Deoxy-2-[[(Methylnitrosoamino)-Carbonyl]Amino]- (Or) Glucopyranose, 2-Deoxy-2-(3-Methyl-3-Nitrosoureido)-,D- (Or) Streptozotocin

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U279
Waste Description: U279

CVS PHARMACY 6892 (Continued) **1014961741**

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported

CVS PHARMACY 6892 (Continued) **1014961741**

Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	

CVS PHARMACY 6892 (Continued) **1014961741**

Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	CORPORATEENVIRONMENTALTEAM@CVSHEALTH.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY 6892 (Continued) **1014961741**

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported

CVS PHARMACY 6892 (Continued) **1014961741**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR

CVS PHARMACY 6892 (Continued) **1014961741**

Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: MAHONEY PARTNERSHIP	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	1311 HILLCREST DR
Owner/Operator City,State,Zip:	SAN JOSE, CA 95120
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private

CVS PHARMACY 6892 (Continued) **1014961741**

Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: VARSITY CORNER, LLC	
Legal Status:	Private
Date Became Current:	20141101
Date Ended Current:	Not reported
Owner/Operator Address:	5959 S.W. 1ST CT.
Owner/Operator City,State,Zip:	CORAL GABLES, FL 33114
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140301
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160301
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CVS PHARMACY 6892 (Continued) **1014961741**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180301
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220301
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20120725
Handler Name: CVS PHARMACY #6892	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130501
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140408
Handler Name: CVS PHARMACY 6892	

CVS PHARMACY 6892 (Continued) **1014961741**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180412
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190211
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20191214
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20210914
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CVS PHARMACY 6892 (Continued) **1014961741**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20210909
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220328
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220328
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20221230
Handler Name: CVS PHARMACY 6892	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

CVS PHARMACY 6892 (Continued) **1014961741**

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	456110
NAICS Description:	PHARMACIES AND DRUG RETAILERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BG965 **CVS PHARMACY** **TX ASBESTOS** **S116387847**
ESE **2927 GUADALUPE ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
61 ft. **Site 5 of 8 in cluster BG**

Actual:
594 ft.

Focus Map:
8

ASBESTOS:

Name:	CVS PHARMACY
Address:	2927 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/03/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported

CVS PHARMACY (Continued) **S116387847**

Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	2927 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	06/03/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals

CVS PHARMACY (Continued) **S116387847**

Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	2927 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/11/2015
Reason for Inspection:	Routine
Violation:	No

CVS PHARMACY (Continued) **S116387847**

Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

CVS PHARMACY (Continued) **S116387847**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 6892
Address:	2927 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	95632
Registration Initial Notification Date:	05/01/2013
Registration Last Amendment Date:	12/30/2022
EPA Identification:	TXR000080904
Primary NAICS Code:	456110
Status Change Date:	20210913
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130977
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20221230
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported

CVS PHARMACY (Continued) **S116387847**

Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA
Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500
Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 GALLON CONTAINERS ARE STORED IN THE BACK STORAGE AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported

CVS PHARMACY (Continued) **S116387847**

Last Changed Date:	20130501
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	13
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20160203
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM
Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	379916
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H

CVS PHARMACY (Continued) **S116387847**

Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE AEROSOLS A
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362217
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Aerosols, [flammable, (each not exceeding 1 L capacity)]
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362218
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0

CVS PHARMACY (Continued) **S116387847**

Waste Treated Off Site:	1
Generators Waste Description:	Corrosive liquids, Basic, n.o.s.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQ BASIC
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	361141
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	379921
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,

CVS PHARMACY (Continued) **S116387847**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362215
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	379924
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported

CVS PHARMACY (Continued) **S116387847**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	379912
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Telephone:	0-401-7651500 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	BRANT ,WENDY
Attention Suffix:	HWG
Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Telephone:	0-401-7651500 x0

CVS PHARMACY (Continued) **S116387847**

Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	BRANT ,WENDY
Attention Suffix:	NWG

AT966 **GRAYBURG OIL CO STA** **EDR Hist Auto** **1013762143**
ESE **4301 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
61 ft. **Site 5 of 8 in cluster AT**

Actual:
623 ft. EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1929	GRAYBURG OIL CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	ALLENS FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1947	METCALF & FLEMING SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	WILEYS SERV STA	GASOLINE STATIONS
1958	HYDE PARK MOBIL	GASOLINE STATIONS
1962	HYDE PARK MOBIL	GASOLINE STATIONS
1965	TUNNIGATE MOBIL SERVICE	GASOLINE STATIONS
1975	HYDE PARK GARAGE	AUTOMOBILE REPAIRING
1980	HYDE PARK GARAGE	AUTOMOBILE REPAIRING
1985	HYDE PARK GARAGE	General Automotive Repair Shops
1986	HYDE PARK GARAGE	General Automotive Repair Shops
1987	HYDE PARK GARAGE	General Automotive Repair Shops
1988	HYDE PARK GARAGE	General Automotive Repair Shops

---

967 **PAGS CARBURETOR** **EDR Hist Auto** **1013761147**
WNW **403 RIO GRANDE** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
61 ft.

Actual:
465 ft. EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	PAGS CARBURETOR	AUTOMOBILE REPAIRING
1958	PAGS CARBURETOR	AUTOMOBILE REPAIRING
1962	PAGS CARBURETOR	AUTOMOBILE REPAIRING
1965	PAGS CARBURETOR	AUTOMOBILE REPAIRING
1969	PAGS CARBURETOR & ELECTRIC	Automotive Repair Shops, NEC
1970	PAGS CARBURETOR & ELECTRIC	Automotive Repair Shops, NEC

AT968 NNE < 1/8 0.012 mi. 61 ft. | **DODD AUTOMOTIVE 4227 GUADALUPE ST AUSTIN, TX 78751** | **TX LPST TX UST TX HIST UST** | **U001238946 N/A**

Site 6 of 8 in cluster AT

Actual: 622 ft.

Focus Map: 8

LPST:

Name:	DODD AUTOMOTIVE
Address:	4227 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78765
Facility ID:	0001832
LPST Id:	104780
Facility Location:	4227 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/22/1992
Entered Date:	10/20/1992
Reported Date:	09/22/1992
Closure Date:	01/22/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	WELLS HURT
Responsible Party Address:	2515 E 45TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78756
Responsible Party Telephone:	512/453-1710
Reported Date:	09/22/1992
Case Start Date:	01/22/1993
Reference Number:	RN101493195
Project Manager:	HWELCH

UST:

Name:	DODD AUTOMOTIVE
Address:	4227 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787514224
AI Number:	1832
Facility Type:	UNKNOWN
Facility Begin Date:	06/05/1986
Facility Status:	INACTIVE
Additional ID:	177625622002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78765
Contact Name/Title:	WELLS HURT,
Contact Organization Name:	DODD AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

DODD AUTOMOTIVE (Continued) **U001238946**

Contact Telephone:	5124531710
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	WELLS HURT,
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600781462
Owner Last Name:	HURT
Owner First Name:	WELLS
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	167625622002053
Additional ID:	177625622002053
AI Number:	1832
Owner Effective Begin Date:	06/05/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4504
Facility ID:	39965
Ai Number:	1832
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

DODD AUTOMOTIVE (Continued) **U001238946**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	7674
UST ID:	4504
AI Number:	1832
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

DODD AUTOMOTIVE (Continued) **U001238946**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4505
Facility ID:	39965
Ai Number:	1832
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

DODD AUTOMOTIVE (Continued) **U001238946**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	7675
UST ID:	4505
AI Number:	1832
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

DODD AUTOMOTIVE (Continued) **U001238946**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4506
Facility ID:	39965
Ai Number:	1832
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

DODD AUTOMOTIVE (Continued) **U001238946**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	7676
UST ID:	4506
AI Number:	1832
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

DODD AUTOMOTIVE (Continued) **U001238946**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4507
Facility ID:	39965
Ai Number:	1832
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

DODD AUTOMOTIVE (Continued) **U001238946**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	7677
UST ID:	4507
AI Number:	1832
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

DODD AUTOMOTIVE (Continued) **U001238946**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HURT WELLS
Contact Mailing Address (Delivery):	2515 W 45TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78756 2901
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	39965
Additional ID:	177625622002053
Princ ID:	167625622002053
AI Number:	1832
Facility Name:	DODD AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	DODD'S TEXACO
Address:	4227 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0351
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AT969 **DODD & HURT TEXACO SERVICE STATION** **EDR Hist Auto** **1013755879**
NNE **4227 GUADALUPE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.012 mi.
61 ft. **Site 7 of 8 in cluster AT**

Actual:
622 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1947	GEORGE ROY TEXACO SERVICE STATI	GASOLINE AND OIL SERVICE STATIONS
1953	GEORGE ROY SERV	GASOLINE STATIONS
1958	GEORGE ROY SERV	GASOLINE STATIONS
1962	4227 31 GEORGE ROY SERV STA	GASOLINE STATIONS
1965	GEORGE ROY SERVICE	GASOLINE STATIONS
1970	GEORGE ROY TEXACO SERVICE STATI	GASOLINE STATIONS
1971	GEORGE ROY SERVICE STATION	Gasoline Service Stations
1972	GEORGE ROY SERVICE STATION	Gasoline Service Stations
1973	GEORGE ROY SERVICE STATION	Gasoline Service Stations
1974	GEORGE ROY SERVICE STATION	Gasoline Service Stations
1975	DODD & HURT TEXACO SERVICE STAT	GASOLINE STATIONS

DODD & HURT TEXACO SERVICE STATION (Continued) **1013755879**

1976	GEORGE ROY SERVICE STATION	Gasoline Service Stations
1980	BRIDGES AUTO SERVICE GAS ST	GASOLINE STATIONS
1980	BRIDGES AUTO SERVICE	General Automotive Repair Shops
1982	BRIDGES AUTO SERVICE	General Automotive Repair Shops
1983	BRIDGES AUTO SERVICE	General Automotive Repair Shops
1984	BRIDGES AUTO SERVICE GAS ST	GASOLINE STATIONS
1988	DODDS TEXACO & GARAGE	Gasoline Service Stations
1989	DODDS TEXACO & GARAGE	Gasoline Service Stations
1990	DODDS TEXACO & GARAGE GAS STA	GASOLINE STATIONS
1990	DODDS TEXACO & GARAGE	Gasoline Service Stations
1993	DODDS TEXACO & GARAGE	Gasoline Service Stations
1994	DODDS TEXACO & GARAGE	Gasoline Service Stations
1995	DODDS TEXACO & GARAGE	Gasoline Service Stations
1996	DODDS SERVICE CENTER	Gasoline Service Stations
1997	DODDS SERVICE CENTER	Gasoline Service Stations
1998	D ODDS SERVICE CENTER	Gasoline Service Stations
1999	D ODDS SERVICE CENTER	Gasoline Service Stations
2000	D ODDS SERVICE CENTER	Gasoline Service Stations
2001	D ODDS SERVICE CENTER	Gasoline Service Stations
2002	D ODDS SERVICE CENTER	Gasoline Service Stations
2003	D ODDS SERVICE CENTER	Gasoline Service Stations
2004	DODDS SERVICE CENTER	Automotive Dealers, NEC
2005	DODDS SERVICE CENTER	Automotive Dealers, NEC
2006	DODDS SERVICE CENTER	Automotive Dealers, NEC
2007	DODDS SERVICE CENTER	General Automotive Repair Shops
2008	DODDS SERVICE CENTER	General Automotive Repair Shops
2011	EACO AUTO GROUP LLC	General Automotive Repair Shops

R970 **FRUZIA FINA SERVICE STATION** **EDR Hist Auto** **1013760272**
ESE **8911 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.012 mi.
61 ft. **Site 5 of 12 in cluster R**

Actual:
663 ft. EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1970	FRUZIA FINA SERVICE STATION	GASOLINE STATIONS
1972	PERRYS TIRE SERVICE & FINA	Gasoline Service Stations
1973	PERRYS TIRE SERVICE & FINA	Gasoline Service Stations
1974	PERRYS TIRE SERVICE & FINA	Gasoline Service Stations
1975	LARRYS FINA GAS STA	GASOLINE STATIONS
1975	PERRYS TIRE SERVICE & FINA	Gasoline Service Stations
1976	LARRYS FINA	Gasoline Service Stations
1977	LARRYS FINA	Gasoline Service Stations
1978	LARRYS FINA	Gasoline Service Stations
1979	LARRYS FINA	Gasoline Service Stations
1980	NEAL INCORPORATED GAS ST	GASOLINE STATIONS
1980	LARRYS FINA	Gasoline Service Stations
1982	LARRYS FINA	Gasoline Service Stations
1983	LARRYS FINA	Gasoline Service Stations
1991	MACS FOOD SHORE	Grocery Stores
1993	CENTRAL TEXAS GROCERIES INC	Convenience Stores
1994	CENTRAL TEXAS GROCERIES INC	Convenience Stores
1995	CENTRAL TEXAS GROCERIES INC	Convenience Stores
1996	CENTRAL TEXAS GROCERIES INC	Convenience Stores
1997	SHAHEEN RETAIL CO INC	Convenience Stores
1998	SHAHEEN RETAIL CO INC	Convenience Stores

FRUZIA FINA SERVICE STATION (Continued) **1013760272**

1999	SHAHEEN RETAIL CO INC	Convenience Stores
2000	SHAHEEN RETAIL CO INC	Convenience Stores
2001	SHAHEEN RETAIL CO INC	Convenience Stores
2002	TETCO INC	Gasoline Service Stations, NEC
2002	SHAHEEN RETAIL CO INC	Convenience Stores
2003	SHAHEEN RETAIL CO INC	Convenience Stores
2003	TETCO STORES INC	Gasoline Service Stations, NEC
2004	SHAHEEN RETAIL CO INC	Convenience Stores
2004	TETCO STORES INC	Gasoline Service Stations, NEC
2005	SHAHEEN RETAIL CO INC	Convenience Stores
2005	TETCO STORES INC	Gasoline Service Stations, NEC
2006	SHAHEEN RETAIL CO INC	Convenience Stores
2006	TETCO STORES INC	Gasoline Service Stations, NEC
2007	TETCO STORES INC	Gasoline Service Stations, NEC
2007	SHAHEEN RETAIL CO INC	Convenience Stores
2008	SHAHEEN RETAIL CO INC	Convenience Stores
2009	SHAHEEN RETAIL CO INC	Convenience Stores
2010	SHAHEEN RETAIL CO INC	Convenience Stores
2011	SHAHEEN RETAIL CO INC	Convenience Stores
2012	SHAHEEN RETAIL CO INC	Convenience Stores
2013	SHAHEEN RETAIL CO INC	Convenience Stores
2014	SHAHEEN RETAIL CO INC	Convenience Stores

R971 **CAPITAL FOOD MART** **TX UST** **U001249783**
ESE **8911 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.012 mi.
61 ft. **Site 6 of 12 in cluster R**

Actual:
663 ft.

Focus Map:
6

UST:

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535011
AI Number:	14336
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	345145832002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	MENDI J MOMIN,PRES
Contact Organization Name:	CAPITAL FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123392964
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/09/2022
Signature Name/Title On Earliest Reg Form:	MENDI MOMIN,PRES

CAPITAL FOOD MART (Continued) **U001249783**

Application Received Date On Earliest Reg Form:	05/17/2022
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	968489162002054
Additional ID:	345145832002139
Ai Number:	14336
Operator CN:	CN600785976
Operator Name:	SHAHEEN RETAIL COMPANY INC
Operator Effective Begin Date:	01/12/2010
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	MENDI MOMIN/PRES
Contact Organization Name:	SHAHEEN RETAIL COMPANY INC
Contact Mailing Address (Delivery):	8911 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-5011
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3392964
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600785976
Owner Last Name:	SHAHEEN RETAIL COMPANY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	8911 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	5011
Contact Phone Number/Ext:	1 512 3392964/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	968489162002054
Additional ID:	345145832002139
AI Number:	14336
Owner Effective Begin Date:	01/12/2010
State Tax ID:	17427935055
Contact Role:	OWNCON
Contact Name/Title:	MENDI J MOMIN/PRES
Contact Organization Name:	SHAHEEN RETAIL COMPANY INC

CAPITAL FOOD MART (Continued) **U001249783**

Self Certification:

Self Cert ID:	92474
Cert ID:	371308
AI Number:	14336
Self Certification Date:	05/09/2022
Signature Name/Title:	MENDI MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	354755
AI Number:	14336
Self Certification Date:	05/17/2021
Signature Name/Title:	MENDI MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	337436
AI Number:	14336
Self Certification Date:	04/30/2020
Signature Name/Title:	MENDI MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	320923
AI Number:	14336
Self Certification Date:	05/07/2019
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	305305
AI Number:	14336
Self Certification Date:	05/17/2018
Signature Name/Title:	MENDI MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	286654
AI Number:	14336
Self Certification Date:	05/09/2017
Signature Name/Title:	MENDI MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	270766
AI Number:	14336
Self Certification Date:	05/21/2016
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	253667
AI Number:	14336
Self Certification Date:	05/08/2015
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	92474
Cert ID:	236646
AI Number:	14336
Self Certification Date:	05/01/2014
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	219419
AI Number:	14336
Self Certification Date:	04/28/2013
Signature Name/Title:	MENDI J MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	92474
Cert ID:	147287
AI Number:	14336
Self Certification Date:	04/23/2012
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147286
AI Number:	14336
Self Certification Date:	04/28/2011
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	147285
AI Number:	14336
Self Certification Date:	04/21/2010
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147284
AI Number:	14336
Self Certification Date:	12/16/2009
Signature Name/Title:	MENDI J MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147283
AI Number:	14336
Self Certification Date:	09/18/2008
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	147282
AI Number:	14336
Self Certification Date:	09/27/2007
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147281
AI Number:	14336
Self Certification Date:	09/18/2006
Signature Name/Title:	RAYMOND MCNIECE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147280
AI Number:	14336
Self Certification Date:	09/28/2005
Signature Name/Title:	RAYMOND MCNIECE ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	147279
AI Number:	14336
Self Certification Date:	09/30/2004
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147278
AI Number:	14336
Self Certification Date:	02/27/2004
Signature Name/Title:	RAYMOND MCNIECE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147277
AI Number:	14336
Self Certification Date:	07/07/2003
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CAPITAL FOOD MART (Continued) **U001249783**

Self Cert ID:	92474
Cert ID:	147276
AI Number:	14336
Self Certification Date:	04/17/2002
Signature Name/Title:	MICHAEL K GARROTT SR ENC COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	92474
Cert ID:	147275
AI Number:	14336
Self Certification Date:	01/18/2001
Signature Name/Title:	MICHAEL K GARROTT, SR ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36926
Facility ID:	92474
Ai Number:	14336
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

CAPITAL FOOD MART (Continued) **U001249783**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	144933
UST ID:	36926
AI Number:	14336
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

CAPITAL FOOD MART (Continued) **U001249783**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1976

More Self Certification:

Self Cert ID:	5662
Cert ID:	72697
UST Comprt ID:	207333
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A
Self Cert ID:	5662
Cert ID:	72696
UST Comprt ID:	207332
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A
Install Date:	11/13/2009
Tank Registration Date:	01/06/2010
Number of Compartments:	3
Tank Capacity:	24000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	213019
Facility ID:	92474

CAPITAL FOOD MART (Continued) **U001249783**

Ai Number:	14336
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	11/13/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	14000
UST Comprt ID:	144936

CAPITAL FOOD MART (Continued) **U001249783**

UST ID:	213019
AI Number:	14336
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/13/2009

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	144937
UST ID:	213019
AI Number:	14336
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

CAPITAL FOOD MART (Continued) **U001249783**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/13/2009
Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	144938
UST ID:	213019
AI Number:	14336
Compartment ID:	C
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

CAPITAL FOOD MART (Continued) **U001249783**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/13/2009

More Self Certification:

Self Cert ID:	5662
Cert ID:	72697
UST Comprt ID:	207333
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A

Self Cert ID:	5662
Cert ID:	72696
UST Comprt ID:	207332
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36928
Facility ID:	92474
Ai Number:	14336
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

CAPITAL FOOD MART (Continued) **U001249783**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	144935
UST ID:	36928
AI Number:	14336
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

CAPITAL FOOD MART (Continued) **U001249783**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1976

More Self Certification:

Self Cert ID:	5662
Cert ID:	72697
UST Comprt ID:	207333
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A

Self Cert ID:	5662
Cert ID:	72696
UST Comprt ID:	207332
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36927
Facility ID:	92474
Ai Number:	14336
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

CAPITAL FOOD MART (Continued) **U001249783**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	144934
UST ID:	36927
AI Number:	14336
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

CAPITAL FOOD MART (Continued) **U001249783**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1976

More Self Certification:

Self Cert ID:	5662
Cert ID:	72697
UST Comprt ID:	207333
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A
Self Cert ID:	5662
Cert ID:	72696
UST Comprt ID:	207332
UST ID:	68279
AI Number:	14336
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	15559
Facility ID:	92474
AI Number:	14336
Application Received Date:	08/31/2009
Scheduled Construction Date:	09/30/2009
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N

CAPITAL FOOD MART (Continued) **U001249783**

UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90831012
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

NOC ID:	15558
Facility ID:	92474
AI Number:	14336
Application Received Date:	08/31/2009
Scheduled Construction Date:	09/30/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90831012
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16691
UST ID:	Not reported
NOC ID:	15559
AI Number:	14336
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	Not reported
Representative Name:	Not reported

CAPITAL FOOD MART (Continued) **U001249783**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	16690
UST ID:	Not reported
NOC ID:	15558
AI Number:	14336
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SHAHEEN RETAIL COMPANY INC
Contact Mailing Address (Delivery):	8911 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 5011
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	92474
Additional ID:	345145832002139
Princ ID:	968489162002054
AI Number:	14336
Facility Name:	CAPITAL FOOD MART
AR Number:	49286
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U

CAPITAL FOOD MART (Continued) **U001249783**

Contact Name/Title: MENDI J MOMIN/

HIST UST AUSTIN:

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	464
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	269117
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2021
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005004788
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	251603
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2020
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000

CAPITAL FOOD MART (Continued) **U001249783**

Policy Number:	G24690696011
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	232397
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2019
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 214 6401000
Policy Number:	G24690696010
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	214524
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2018
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24690696009
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

CAPITAL FOOD MART (Continued) **U001249783**

Region:	2
Facility ID:	92474
Finass ID:	198788
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2017
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24690696008
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	179623
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2016
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24690696 007
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	163177
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

CAPITAL FOOD MART (Continued) **U001249783**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2015
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24690696006
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	144719
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2014
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24690696005
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	128250
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2013
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 9514119
Policy Number:	G24690696004
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2014

CAPITAL FOOD MART (Continued) **U001249783**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	107998
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2012
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 3524462
Policy Number:	G24690696-003
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/14/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	10413
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2011
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 3524462
Policy Number:	G24690696002
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76282

CAPITAL FOOD MART (Continued) **U001249783**

AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2010
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 3524462
Policy Number:	G24690696001
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76283
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2009
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00072746
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76286
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2009

CAPITAL FOOD MART (Continued) **U001249783**

Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00072746
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76285
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2009
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-0007246
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76284
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/14/2009
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-0007246
Coverage Amount:	1000000
Coverage Expiration Date:	11/14/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

CAPITAL FOOD MART (Continued) **U001249783**

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76287
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8058109
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76288
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8057698
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76289
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

CAPITAL FOOD MART (Continued) **U001249783**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2006
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9220603 00
Coverage Amount:	5000000
Coverage Expiration Date:	12/22/2007
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD MART
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	92474
Finass ID:	76290
AI:	14336
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/17/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

R972 **TETCO 1144** **TX LPST** **S110377036**
ESE **8911 N LAMAR BLVD** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.012 mi.
61 ft. **Site 7 of 12 in cluster R**

Actual:
663 ft.

Focus Map:
6

LPST:

Name:	TETCO 1144
Address:	8911 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0014336
LPST Id:	118246
Facility Location:	8911 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/03/2009
Entered Date:	03/10/2010
Reported Date:	11/03/2009
Closure Date:	07/14/2010

TETCO 1144 (Continued) **S110377036**

Priority: 4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 1P - PRIVATIZATION CONTRACTOR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1P
Coordinators RPR: MWB
Responsible Party Name: Not reported
Responsible Party Contact: RAYMOND MCNIECE
Responsible Party Address: PO BOX 171720
Responsible Party City,St,Zip: SAN ANTONIO, TX 78217
Responsible Party Telephone: 210/821-5900
Reported Date: 11/03/2009
Case Start Date: 07/14/2010
Reference Number: RN102269362
Project Manager: MBRATBER

GCC:
Name: TETCO STORES LP
Address: 8911 N LAMAR
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 118246
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 3/10/2010
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TETCO STORES LP
Address: 8911 N LAMAR
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 118246
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 3/10/2010
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported

TETCO 1144 (Continued) **S110377036**

Data Quality 2: Not reported

HT973 **THE NEON PLANT** **TX HIST UST** **S113432445**
ESE **4401 GUADALUPE ST** **TX SPILLS** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.012 mi.
62 ft. **Site 1 of 3 in cluster HT**

Actual:
629 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	GHOST TANKS
Address:	4401 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3396
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SPILLS:

Name:	THE NEON PLANT
Address:	4401 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Incident Number:	5332
Facility Id:	RN102817228
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	Not reported
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11 - AUSTIN
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	unknown
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	Not reported
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	No Incident Type

THE NEON PLANT (Continued) **S113432445**

Near City Name:	AUSTIN
Importance Level:	5
Received Date:	08/07/2002
Start Date:	12/30/1899
Status Date:	09/30/2002
Media Name:	WASTE
Customer:	THE NEON PLANT
Effect:	ENVIRONMEN
Num Complaining:	1
Frequency:	CURRENT
Nature:	INDUSTRIAL
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Closed
Disputed Status:	Not reported
Disputed Date:	01/01/1900
Comments:	This complaint was received on 08/08/2002 at 1:37 p.m.
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

HT974 **FARRIS LUTHER L FILLING STA** **EDR Hist Auto** **1013754044**
ESE **4401 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
62 ft. **Site 2 of 3 in cluster HT**

Actual:
629 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1935	STILES E L FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	STILES E L FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	FARRIS LUTHER L FILLING STA	GASOLINE AND OIL SERVICE STATIONS

---

975 **HYATT REGENCY HOTEL** **TX VCP** **S107406750**
South **208 BARTON SPRINGS RD** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.012 mi.
62 ft.

Actual:
444 ft.
VCP TCEQ:

Focus Map:
11

Name:	HYATT REGENCY HOTEL
Address:	208 BARTON SPRINGS RD
City,State,Zip:	AUSTIN, TX 78704
Region:	REGION 11 - AUSTIN
Facility ID:	1872
VCP Record Date:	09/29/2005
Facility Type:	PARKING/TRANSIT CENTER
PCA Number:	34071
Project Manager:	MARTHUR
Phase:	COMPLETED
Acres at Site:	2.75
REM Program:	VCP
RN Number:	RN104778188

HYATT REGENCY HOTEL (Continued) **S107406750**

Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	09/29/2005
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	05/22/2009
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	09/29/2005
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2005-10-18 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1872
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	340710
Off Site?:	Not reported
Media:	PAPER; MICROFILM
IOP Number:	Not reported
File Location:	D/211; D/104; CR
Latitude:	30.26
Longitude:	-97.75

Contact:

REM Program:	VCP
Program ID:	1872
RN Number:	RN104778188
CN Number:	CN602924649
CN Name:	FAIRFIELD TOWN LAKE ZILKER LP
Role Code:	BILLCONT
Contact Name:	SHAIKH, TERRY
Contact Title:	Not reported
Organization Name:	TANTALLON AUSTIN LLC
Mailing Address:	1500 SAN LAKE RD
Mailing City:	ORLANDO
Mailing State:	FL
Mailing Zip:	32809
Contact Telephone:	(407) 816-5184
Contact Telephone Ext:	0

DE976 **ROTP 2 PROPERTY** **TX UST** **U001291258**
WNW **401 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.012 mi.
62 ft. **Site 7 of 13 in cluster DE**

Actual:
493 ft.

Focus Map:
11

UST:

Name:	ROTP 2 PROPERTY
Address:	401 W 6TH ST
City,State,Zip:	AUSTIN, TX 787013163
AI Number:	62049
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	300473512002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	ROTP 2 PROPERTY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2145085361
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/10/1991
Signature Name/Title On Earliest Reg Form:	STEVEN T WAREING,ENVIRO SPECIALIST
Application Received Date On Earliest Reg Form:	12/17/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601245400
Owner Last Name:	UNITED STATES POSTAL SERVICE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	207672192002150
Additional ID:	300473512002075

ROTP 2 PROPERTY (Continued) **U001291258**

AI Number:	62049
Owner Effective Begin Date:	08/31/1996
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/17/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	144257
Facility ID:	97328
Ai Number:	62049
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/30/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

ROTP 2 PROPERTY (Continued) **U001291258**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	154700
UST ID:	144257
AI Number:	62049
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

ROTP 2 PROPERTY (Continued) **U001291258**

Install Date:	08/31/1987
Tank Registration Date:	12/17/1991
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144255
Facility ID:	97328
Ai Number:	62049
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

ROTP 2 PROPERTY (Continued) **U001291258**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	154698
UST ID:	144255
AI Number:	62049
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/17/1991
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144256

ROTP 2 PROPERTY (Continued) **U001291258**

Facility ID:	97328
Ai Number:	62049
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	560

ROTP 2 PROPERTY (Continued) **U001291258**

UST Comprt ID:	154699
UST ID:	144256
AI Number:	62049
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	UNITED STATES POSTAL SERVICE
Contact Mailing Address (Delivery):	1 POST OFFICE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78284 8401
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	97328
Additional ID:	300473512002075
Princ ID:	207672192002150
AI Number:	62049
Facility Name:	ROTP 2 PROPERTY
AR Number:	Not reported
AR UST Number Suffix:	Not reported

ROTP 2 PROPERTY (Continued) **U001291258**

AR AST Number Suffix: Not reported
Contact Name/Title: /

DE977 **GRAYBURG OIL** **TX HIST UST** **S128729189**
WNW **401 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
62 ft. **Site 8 of 13 in cluster DE**

Actual:
493 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	GRAYBURG OIL
Address:	401 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0119
HID UST:	119
Inspection:	03/19/2009
Due:	03/19/2012

DE978 **US POST OFFICE** **TX HIST UST** **S128729052**
WNW **401 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
62 ft. **Site 9 of 13 in cluster DE**

Actual:
493 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	US POST OFFICE
Address:	401 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0487
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

HT979 **MARX W E MOTOR** **EDR Hist Auto** **1013764028**
ESE **4405 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
62 ft. **Site 3 of 3 in cluster HT**

Actual:
629 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1935	MARX W E MOTOR	MOTORCYCLE DEALERS AND REPAIRERS

BD980 **MY CLEANERS & ALTERATIONS** **TX DRYCLEANERS** **S108892903**
WNW **3100 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
62 ft. **Site 2 of 5 in cluster BD**

Actual:
592 ft.

Focus Map:
8

DRYCLEANERS:

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	REGION 11 - AUSTIN
CN Number:	CN603002288
DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	7513 LOBELIA DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78729 7909
EMail:	BEBOP1245@AUSTIN.RR.COM
Phone Number:	512 9406608
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	REGION 11 - AUSTIN
CN Number:	CN603002288
DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	7513 LOBELIA DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78729 7909
EMail:	BEBOP1245@AUSTIN.RR.COM
Phone Number:	512 9406608
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	REGION 11 - AUSTIN
CN Number:	CN603002288

MY CLEANERS & ALTERATIONS (Continued) **S108892903**

DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE

MY CLEANERS & ALTERATIONS (Continued) **S108892903**

Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11

MY CLEANERS & ALTERATIONS (Continued) **S108892903**

CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION

MY CLEANERS & ALTERATIONS (Continued) **S108892903**

Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	11
CN Number:	CN603002288
DCR Number:	Not reported
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	MY CLEANERS & ALTERATIONS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	REGION 11 - AUSTIN
CN Number:	CN603002288
DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	605 S BELL BLVD STE 100
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 3835
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667

MY CLEANERS & ALTERATIONS (Continued) **S108892903**

Region:	REGION 11 - AUSTIN
CN Number:	CN603002288
DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	7513 LOBELIA DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78729 7909
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MY CLEANERS & ALTERATIONS
Address:	3100 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN105297667
Region:	REGION 11 - AUSTIN
CN Number:	CN603002288
DCR Number:	DCR14938
AR Number:	24003737
Principal Name:	FOUSE INC
Bill Addr1:	7513 LOBELIA DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78729 7909
EMail:	Not reported
Phone Number:	512 2197901
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

BD981 **MY CLEANERS & ALTERATIONS** **EDR Hist Cleaner** **1013785417**
WNW **3100 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
62 ft. **Site 3 of 5 in cluster BD**

Actual:
592 ft. EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1965	CAPITOL LAUNDRY & DRY	LAUNDRIES
2007	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2008	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2009	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2010	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2011	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2012	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC

MY CLEANERS & ALTERATIONS (Continued) **1013785417**

2013	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC
2014	MY CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs, NEC

BD982 **UNIVERSITY TEXACO** **EDR Hist Auto** **1020744284**
WNW **3100 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
62 ft. **Site 4 of 5 in cluster BD**

Actual:
592 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1986	UNIVERSITY TEXACO	Gasoline Service Stations
1987	UNIVERSITY TEXACO	Gasoline Service Stations

AG983 **ZIPPY FOOD STORE** **TX HIST UST** **S126860450**
WNW **6600 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.012 mi.
62 ft. **Site 6 of 14 in cluster AG**

Actual:
713 ft.

Focus Map:
6

HIST UST AUSTIN:

Name:	ZIPPY FOOD STORE
Address:	6600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0057
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN106972763
Name:	ZIPPY FOOD STORE
Address:	6600 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3502
Status:	ACTIVE
Status Date:	11/14/2013
Customer Number:	CN604402339
Customer Name:	FUEL DISTRIBUTORS
Customer Legal Name:	Fuel Distributors
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AG984 WNW < 1/8 0.012 mi. 62 ft. | **ZIPPY FOOD STORE 6600 N LAMAR BLVD AUSTIN, TX 78752** | **TX LPST** | **S105121614 N/A**

Site 7 of 14 in cluster AG

Actual: 713 ft.

Focus Map: 6

LPST:

Name:	ZIPPY FOOD STORE
Address:	6600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	Not reported
LPST Id:	091169
Facility Location:	6600 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/02/1986
Entered Date:	12/02/1986
Reported Date:	12/02/1986
Closure Date:	03/13/1987
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	JACK LOWDEN
Responsible Party Address:	PO BOX 6374
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	/-
Reported Date:	12/02/1986
Case Start Date:	03/13/1987
Reference Number:	RN106972763
Project Manager:	REGION

EW985 ESE < 1/8 0.012 mi. 62 ft. | **TOM E. SHORT 1301 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S111678836 N/A**

Site 7 of 11 in cluster EW

Actual: 508 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	TOM E. SHORT
Address:	1301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0278
HID UST:	278
Inspection:	Not reported
Due:	06/01/2012

N986 ESE < 1/8 0.012 mi. 62 ft. | **FAMILY DOLLAR #6170**
9717 N. LAMAR BLVD
AUSTIN, TX 78753
Site 2 of 3 in cluster N | **RCRA-VSQG FINDS** | **1017789159 TXR000082963**

Actual: 691 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20150304
Handler Name:	Family Dollar #6170
Handler Address:	N. LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXR000082963
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported
Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PROGRAM MGR., ENV. COMPLIANCE
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1017
Mailing City,State,Zip:	CHARLOTTE, NC 28201
Owner Name:	2m And 3d, Ltd.
Owner Type:	Private
Operator Name:	Family Dollar Stores
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

FAMILY DOLLAR #6170 (Continued) **1017789159**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150310
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator

FAMILY DOLLAR #6170 (Continued) **1017789159**

Owner/Operator Name: FAMILY DOLLAR STORES
Legal Status: Private
Date Became Current: 20040318
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 2M AND 3D, LTD.
Legal Status: Private
Date Became Current: 20140101
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 91973
Owner/Operator City,State,Zip: AUSTIN, TX 78709
Owner/Operator Telephone: 512-619-4114
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20150304
Handler Name: FAMILY DOLLAR #6170
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110064013473

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

FAMILY DOLLAR #6170 (Continued) **1017789159**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

N987 **WALGREEN CO** **RCRA NonGen / NLR** **1001225768**
ESE **9717 N LAMAR BLVD** **FINDS** **TXR000026096**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.012 mi. **TX ASBESTOS**
62 ft. **Site 3 of 3 in cluster N** **TX Ind. Haz Waste**

Actual:
691 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20081217
Handler Name:	Walgreen Co
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXR000026096
Contact Name:	RUSS ROELLER
Contact Address:	STIRRUP CREEK DR STE 211
Contact City,State,Zip:	DURHAM, NC 27703
Contact Telephone:	919-484-3631
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	STIRRUP CREEK DR STE 211
Mailing City,State,Zip:	DURHAM, NC 27703
Owner Name:	Walgreen Co
Owner Type:	Private
Operator Name:	Walgreen Co
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

WALGREEN CO (Continued) **1001225768**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20090311
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D011
Waste Description:	Silver

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALGREEN CO	
Legal Status:	Private
Date Became Current:	20081217
Date Ended Current:	Not reported
Owner/Operator Address:	200 WILMOT RD
Owner/Operator City,State,Zip:	DEERFIELD, IL 60015
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: QUALEX	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2408 REICHARD ST
Owner/Operator City,State,Zip:	DURHAM, NC 27705
Owner/Operator Telephone:	919-382-6592
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

WALGREEN CO (Continued) **1001225768**

Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 19980128
Date Ended Current: Not reported
Owner/Operator Address: 200 WILMOT RD
Owner/Operator City,State,Zip: DEERFIELD, IL 60015
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 19980128
Date Ended Current: Not reported
Owner/Operator Address: 200 WILMOT RD
Owner/Operator City,State,Zip: DEERFIELD, IL 60015
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 20081217
Date Ended Current: Not reported
Owner/Operator Address: 200 WILMOT RD
Owner/Operator City,State,Zip: DEERFIELD, IL 60015
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19980303
Handler Name: WALGREENS NO 1542
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980128
Handler Name: WALGREEN CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

WALGREEN CO (Continued) **1001225768**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081217
Handler Name: WALGREEN CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005180927

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001225768
Registry ID: 110005180927
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005180927
Name: WALGREEN CO
Address: 9717 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753

ASBESTOS:
Name: FAMILY DOLLAR
Address: 9717 N LAMAR BLVD

WALGREEN CO (Continued) **1001225768**

City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	Not reported
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

WALGREEN CO (Continued) **1001225768**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RENT A CENTER
Address:	9717 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported

WALGREEN CO (Continued) **1001225768**

High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	WALGREENS 1542
Address:	9717 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	85529
Registration Initial Notification Date:	01/28/1998
Registration Last Amendment Date:	12/17/2008
EPA Identification:	TXR000026096
Primary NAICS Code:	446110
Status Change Date:	19980128
Land Type:	PRIVATE
Description of Facility Site Location:	9717 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	WALGREEN CO
Contact Name:	RUSS ROELLER
Contact Telephone Number:	919-4843631
Mailing Address:	4020 STIRRUP CREEK DR STE 211
Mailing Address2:	STE 211
Mailing City,State,Zip:	DURHAM, NC 277039410
Mailing County:	UNITED STATES

WALGREEN CO (Continued) **1001225768**

Facility Country:	UNITED STATES
TNRCC Facility ID:	107148
Site Owner Tax ID:	361924025
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20081217
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	WALGREEN CO
Operator Address:	200 WILMOT RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	DEERFIELD, IL 60015
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13619240255
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	WALGREEN CO
Owner Mailing Address:	200 WILMOT RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	DEERFIELD, IL 60015
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13619240255
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported

WALGREEN CO (Continued) **1001225768**

Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	010
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Waste drum storage
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19980128
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	200 WILMOT RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	DEERFIELD, IL 60015
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	200 WILMOT RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	DEERFIELD, IL 60015
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RUSS ROELLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4020 STIRRUP CREEK DR STE 211
Contact Address 2:	STE 211
Contact Address 3:	Not reported
Contact City,State,Zip:	DURHAM, NC 27703
Contact Phone:	1-919-4843631
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	167653

WALGREEN CO (Continued) **1001225768**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0629119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Photo fixer silver solution from photo processing. Waste was sent to Safety Klee
Standard Industrial Code:	59120
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	446110
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

HL988 **KWIK WASH COIN LAUNDRIES NO** **EDR Hist Cleaner** **1013783375**
WNW **6606 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.012 mi.
62 ft. **Site 6 of 8 in cluster HL**

Actual:
655 ft.

EDR Hist Cleaner

Focus Map:
17

Year:	Name:	Type:
1984	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1990	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

AG989 **PAYLESS GAS 866** **TX UST** **U004318521**
WNW **6608 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.012 mi.
63 ft. **Site 8 of 14 in cluster AG**

Actual:
714 ft.

UST:

Focus Map:
6

Name:	PAYLESS GAS 866
Address:	6608 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787523502
AI Number:	18930
Facility Type:	RETAIL
Facility Begin Date:	09/04/1986
Facility Status:	INACTIVE
Additional ID:	185672102002150
Facility Exempt Status:	N
Records Off-Site:	No

PAYLESS GAS 866 (Continued) **U004318521**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	PAYLESS GAS 866
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8177783547
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	B HARTWELL,OPERATIONS MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600134746
Owner Last Name:	STRASBURGER ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	624329392001221
Additional ID:	185672102002150
AI Number:	18930
Owner Effective Begin Date:	09/04/1986
State Tax ID:	17418017533
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N

PAYLESS GAS 866 (Continued) **U004318521**

Pipe Type:	Not reported
UST ID:	49302
Facility ID:	52591
Ai Number:	18930
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/26/1990

PAYLESS GAS 866 (Continued) **U004318521**

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	49147
UST ID:	49302
AI Number:	18930
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7281
Cert ID:	157559
UST Comprt ID:	458992
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157561
UST Comprt ID:	458990
UST ID:	155377

PAYLESS GAS 866 (Continued) **U004318521**

AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	345208
UST Comprt ID:	1002953
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	243470
UST Comprt ID:	699614
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	227229
UST Comprt ID:	652065
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	294333
UST Comprt ID:	849954
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157558
UST Comprt ID:	458993
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157566
UST Comprt ID:	458985
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157555
UST Comprt ID:	458994
UST ID:	155377
AI Number:	18930

PAYLESS GAS 866 (Continued) **U004318521**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157565
UST Comprt ID:	458986
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	309916
UST Comprt ID:	896910
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157564
UST Comprt ID:	458987
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157557
UST Comprt ID:	458996
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157563
UST Comprt ID:	458988
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	378538
UST Comprt ID:	1103641
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157562
UST Comprt ID:	458989
UST ID:	155377
AI Number:	18930
Tank ID:	1

PAYLESS GAS 866 (Continued) **U004318521**

Compartment ID:	A
Self Cert ID:	7281
Cert ID:	327223
UST Comprt ID:	948544
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	277371
UST Comprt ID:	799689
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	361578
UST Comprt ID:	1052271
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157560
UST Comprt ID:	458991
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157556
UST Comprt ID:	458995
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	259948
UST Comprt ID:	748207
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N

PAYLESS GAS 866 (Continued) **U004318521**

Pipe Type:	Not reported
UST ID:	49301
Facility ID:	52591
Ai Number:	18930
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/26/1990

PAYLESS GAS 866 (Continued) **U004318521**

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	49146
UST ID:	49301
AI Number:	18930
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7281
Cert ID:	157559
UST Comprt ID:	458992
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A

Self Cert ID:	7281
Cert ID:	157561
UST Comprt ID:	458990
UST ID:	155377

PAYLESS GAS 866 (Continued) **U004318521**

AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	345208
UST Comprt ID:	1002953
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	243470
UST Comprt ID:	699614
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	227229
UST Comprt ID:	652065
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	294333
UST Comprt ID:	849954
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157558
UST Comprt ID:	458993
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157566
UST Comprt ID:	458985
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157555
UST Comprt ID:	458994
UST ID:	155377
AI Number:	18930

PAYLESS GAS 866 (Continued) **U004318521**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157565
UST Comprt ID:	458986
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	309916
UST Comprt ID:	896910
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157564
UST Comprt ID:	458987
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157557
UST Comprt ID:	458996
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157563
UST Comprt ID:	458988
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	378538
UST Comprt ID:	1103641
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157562
UST Comprt ID:	458989
UST ID:	155377
AI Number:	18930
Tank ID:	1

PAYLESS GAS 866 (Continued) **U004318521**

Compartment ID:	A
Self Cert ID:	7281
Cert ID:	327223
UST Comprt ID:	948544
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	277371
UST Comprt ID:	799689
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	361578
UST Comprt ID:	1052271
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157560
UST Comprt ID:	458991
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157556
UST Comprt ID:	458995
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	259948
UST Comprt ID:	748207
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N

PAYLESS GAS 866 (Continued) **U004318521**

Pipe Type:	Not reported
UST ID:	49300
Facility ID:	52591
Ai Number:	18930
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1980
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/26/1990

PAYLESS GAS 866 (Continued) **U004318521**

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	49145
UST ID:	49300
AI Number:	18930
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7281
Cert ID:	157559
UST Comprt ID:	458992
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157561
UST Comprt ID:	458990
UST ID:	155377

PAYLESS GAS 866 (Continued) **U004318521**

AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	345208
UST Comprt ID:	1002953
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	243470
UST Comprt ID:	699614
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	227229
UST Comprt ID:	652065
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	294333
UST Comprt ID:	849954
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157558
UST Comprt ID:	458993
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157566
UST Comprt ID:	458985
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157555
UST Comprt ID:	458994
UST ID:	155377
AI Number:	18930

PAYLESS GAS 866 (Continued) **U004318521**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157565
UST Comprt ID:	458986
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	309916
UST Comprt ID:	896910
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157564
UST Comprt ID:	458987
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157557
UST Comprt ID:	458996
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157563
UST Comprt ID:	458988
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	378538
UST Comprt ID:	1103641
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157562
UST Comprt ID:	458989
UST ID:	155377
AI Number:	18930
Tank ID:	1

PAYLESS GAS 866 (Continued) **U004318521**

Compartment ID:	A
Self Cert ID:	7281
Cert ID:	327223
UST Comprt ID:	948544
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	277371
UST Comprt ID:	799689
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	361578
UST Comprt ID:	1052271
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157560
UST Comprt ID:	458991
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	157556
UST Comprt ID:	458995
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7281
Cert ID:	259948
UST Comprt ID:	748207
UST ID:	155377
AI Number:	18930
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	STRASBURGER ENTERPRISES INC
Contact Mailing Address (Delivery):	PO BOX 6117
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEMPLE, TX 76503 6117
Phone Number/Ext:	/

PAYLESS GAS 866 (Continued) **U004318521**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	52591
Additional ID:	185672102002150
Princ ID:	624329392001221
AI Number:	18930
Facility Name:	PAYLESS GAS 866
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KEVIN GANDY/

AG990 **FUEL DISTRIBUTORS** **TX UST** **U004318522**
WNW **6608 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.012 mi.
63 ft. **Site 9 of 14 in cluster AG**

Actual:
714 ft.

Focus Map:
6

UST:

Name:	FUEL DISTRIBUTORS
Address:	6608 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787523502
AI Number:	44619
Facility Type:	UNKNOWN
Facility Begin Date:	03/18/1987
Facility Status:	INACTIVE
Additional ID:	577632612002241
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	FUEL DISTRIBUTORS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8177783547
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/26/1987
Signature Name/Title On Earliest Reg Form:	BILL HARTWELL,OPER. MGR.
Application Received Date On Earliest Reg Form:	03/05/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600134746
Owner Last Name:	STRASBURGER ENTERPRISES INC

FUEL DISTRIBUTORS (Continued) **U004318522**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	624329392001221
Additional ID:	577632612002241
AI Number:	44619
Owner Effective Begin Date:	03/18/1987
State Tax ID:	17418017533
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	03/05/1987
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	116913
Facility ID:	52614
Ai Number:	44619
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

FUEL DISTRIBUTORS (Continued) **U004318522**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/19/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	49891
UST ID:	116913
AI Number:	44619
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

FUEL DISTRIBUTORS (Continued) **U004318522**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17520
Cert ID:	120146
UST Comprt ID:	345198
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120145
UST Comprt ID:	345199
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120144
UST Comprt ID:	345201
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120143
UST Comprt ID:	345200
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120148
UST Comprt ID:	345196
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520

FUEL DISTRIBUTORS (Continued) **U004318522**

Cert ID:	120147
UST Comprt ID:	345197
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Install Date:	01/01/1970
Tank Registration Date:	03/05/1987
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	116914
Facility ID:	52614
Ai Number:	44619
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

FUEL DISTRIBUTORS (Continued) **U004318522**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/19/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	49892
UST ID:	116914
AI Number:	44619
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

FUEL DISTRIBUTORS (Continued) **U004318522**

More Self Certification:

Self Cert ID:	17520
Cert ID:	120146
UST Comprt ID:	345198
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120145
UST Comprt ID:	345199
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120144
UST Comprt ID:	345201
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120143
UST Comprt ID:	345200
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120148
UST Comprt ID:	345196
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	17520
Cert ID:	120147
UST Comprt ID:	345197
UST ID:	115121
AI Number:	44619
Tank ID:	3A
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	STRASBURGER ENTERPRISES INC
Contact Mailing Address (Delivery):	PO BOX 6117
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TEMPLE, TX 76503 6117
Phone Number/Ext:	/

FUEL DISTRIBUTORS (Continued) **U004318522**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	52614
Additional ID:	577632612002241
Princ ID:	624329392001221
AI Number:	44619
Facility Name:	FUEL DISTRIBUTORS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KEVIN GANDY/

AG991 **PAYLESS GAS** **EDR Hist Auto** **1013770283**
WNW **6608 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.012 mi.
63 ft. **Site 10 of 14 in cluster AG**

Actual:
714 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1980	PAYLESS GAS	GASOLINE STATIONS

AI992 **FAMOUS FOOD MART** **TX LPST** **U001253971**
ESE **6301 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX HIST UST**
0.012 mi. **TX Financial Assurance**
63 ft. **Site 2 of 8 in cluster AI** **TX RDR**

Actual:
713 ft.

Focus Map:
6

LPST:

Name:	S FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0019074
LPST Id:	112387
Facility Location:	6301 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	06/17/1997
Reported Date:	12/31/3000
Closure Date:	07/11/2007
Priority:	3.1 - GW IMPACT PUB/DOM WATER SUPPLY WELL W/IN .25 - .5mi
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located between 0.25 and 0.5 miles from the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1
Coordinators RPR:	MDS
Responsible Party Name:	Not reported
Responsible Party Contact:	TIMOTHY CRAFT OLIVER
Responsible Party Address:	PO BOX 6110 LN

FAMOUS FOOD MART (Continued) **U001253971**

Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	512/457-1977
Reported Date:	12/31/3000
Case Start Date:	07/11/2007
Reference Number:	RN102393139
Project Manager:	MSEFCIK

UST:

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524005
AI Number:	19074
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	781702572002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	PATRICK OLIVER,
Contact Organization Name:	FAMOUS FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/01/2021
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,PRE
Application Received Date On Earliest Reg Form:	04/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	781702572002150
Ai Number:	19074
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600750186
Owner Last Name:	OFLP-2 LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	18479812002030
Additional ID:	781702572002150
AI Number:	19074
Owner Effective Begin Date:	09/08/1994
State Tax ID:	32036480534
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	75960
Cert ID:	369432
AI Number:	19074
Self Certification Date:	04/08/2022
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	352801
AI Number:	19074
Self Certification Date:	04/01/2021
Signature Name/Title:	PATRICK OLIVER PRE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	335441
AI Number:	19074
Self Certification Date:	03/10/2020
Signature Name/Title:	PATRICK OLIVER VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	319642
AI Number:	19074
Self Certification Date:	04/04/2019
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	300779
AI Number:	19074
Self Certification Date:	03/12/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	284853
AI Number:	19074
Self Certification Date:	04/05/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	267445
AI Number:	19074
Self Certification Date:	03/31/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	250214
AI Number:	19074
Self Certification Date:	03/10/2015
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	234095
AI Number:	19074
Self Certification Date:	03/25/2014
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75960
Cert ID:	111073
AI Number:	19074
Self Certification Date:	03/13/2013
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	111072
AI Number:	19074
Self Certification Date:	03/09/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111071
AI Number:	19074
Self Certification Date:	03/16/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111070
AI Number:	19074
Self Certification Date:	03/19/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	111069
AI Number:	19074
Self Certification Date:	03/30/2009
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111068
AI Number:	19074
Self Certification Date:	03/25/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111067
AI Number:	19074
Self Certification Date:	03/01/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	111066
AI Number:	19074
Self Certification Date:	03/01/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111065
AI Number:	19074
Self Certification Date:	03/02/2005
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111064
AI Number:	19074
Self Certification Date:	03/01/2004
Signature Name/Title:	GUY N OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Self Cert ID:	75960
Cert ID:	111063
AI Number:	19074
Self Certification Date:	03/31/2003
Signature Name/Title:	GUY NEWELL OLIVER AUTHORIZED REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111062
AI Number:	19074
Self Certification Date:	03/22/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75960
Cert ID:	111061
AI Number:	19074
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	49690
Facility ID:	75960
Ai Number:	19074
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1971
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	121622
UST ID:	49690
AI Number:	19074
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/23/2005

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P

FAMOUS FOOD MART (Continued) **U001253971**

UST ID:	49692
Facility ID:	75960
Ai Number:	19074
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1971
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3

FAMOUS FOOD MART (Continued) **U001253971**

Tank Capacity:	10000
UST Comprt ID:	121624
UST ID:	49692
AI Number:	19074
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/23/2005

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	49691
Facility ID:	75960
Ai Number:	19074
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1971
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

FAMOUS FOOD MART (Continued) **U001253971**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	121623
UST ID:	49691
AI Number:	19074
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/23/2005

Construction Notification:

NOC ID:	11048
Facility ID:	75960
AI Number:	19074
Application Received Date:	08/15/2005
Scheduled Construction Date:	08/22/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50815012
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	34584
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	11860
UST ID:	Not reported
NOC ID:	11048
AI Number:	19074
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	OFLP2 LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	75960
Additional ID:	781702572002150
Princ ID:	18479812002030
AI Number:	19074
Facility Name:	FAMOUS FOOD MART
AR Number:	34584
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK OLIVER/

HIST UST AUSTIN:

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX

FAMOUS FOOD MART (Continued) **U001253971**

Id UST:	704
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	267071
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	249066
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD

FAMOUS FOOD MART (Continued) **U001253971**

City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	230277
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	213194
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	211797
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	193632
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	177684
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000099530
Coverage Amount:	1,000,000

FAMOUS FOOD MART (Continued) **U001253971**

Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	159163
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	141135
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960

FAMOUS FOOD MART (Continued) **U001253971**

Finass ID:	124721
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	7728
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60659
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

FAMOUS FOOD MART (Continued) **U001253971**

Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00079114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60660
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO9114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60661
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

FAMOUS FOOD MART (Continued) **U001253971**

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60662
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60663
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60664
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

FAMOUS FOOD MART (Continued) **U001253971**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75960
Finass ID:	60665
AI:	19074
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	04/05/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	32457
Facility ID:	19074
RN:	102393139
CN:	600750186
Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/3/2023
Due Date:	3/4/2023
Tank Owner:	OFLP-2 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	1/20/2023
Project Manager:	Ross Eide
Team:	Team 2
New LPST Number:	Not reported

FAMOUS FOOD MART (Continued) **U001253971**

Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	23294
Facility ID:	19074
RN:	Not reported
CN:	Not reported
Name:	FAMOUS FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/23/2015
Due Date:	1/22/2016
Tank Owner:	OFLP 2 LTD
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	1/22/2016
Project Manager:	Morgan Suhm
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AI993 **FOOD MART GAS & FOOD STORE** **EDR Hist Auto** **1013764580**
ESE **6301 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.012 mi.
63 ft. **Site 3 of 8 in cluster AI**

Actual:
713 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1975	SITE OIL CO GAS ST	GASOLINE STATIONS
1980	SITE OIL CO GAS ST	GASOLINE STATIONS
1984	SITE OIL CO GAS ST	GASOLINE STATIONS
1990	FOOD MART GAS & FOOD STORE	GASOLINE STATIONS

AI994 ESE < 1/8 0.012 mi. 63 ft. | **SHELL FOOD MART 6301 N LAMAR BLVD AUSTIN, TX** | **TX RDR** | **S127526181 N/A**

Site 4 of 8 in cluster AI

Actual: 713 ft.

Focus Map: 6

RDR:

RDR ID:	19827
Facility ID:	19074
RN:	Not reported
CN:	Not reported
Name:	SHELL FOOD MART
Address:	6301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/6/2011
Due Date:	9/4/2011
Tank Owner:	OFLP-2 LTD
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	9/20/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SIR LTR/NO FURTHER SITE CHECK REQUIRED
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	9/20/2011
Region:	Not reported
DKC RDR (misfiled):	Not reported

HU995 West < 1/8 0.012 mi. 63 ft. | **BURTONS LNDRY 411 23RD W AUSTIN, TX** | **EDR Hist Cleaner** | **1013777343 N/A**

Site 1 of 4 in cluster HU

Actual: 585 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1958	BURTONS LNDRY	LAUNDRIES

DG996 NNE < 1/8 0.012 mi. 63 ft. | **QUONG WAH CHINESE LAUNDRY 115 E 7TH ST AUSTIN, TX** | **EDR Hist Cleaner** | **1013785730 N/A**

Site 6 of 16 in cluster DG

Actual: 499 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1896	QUONG WAH CHINESE LAUNDRY	LAUNDRIES

HV997 **AUTOSYSTEMS WORKSHOP INC** **EDR Hist Auto** **1020227770**
ESE **10805 N LAMAR BLVD A** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.012 mi.
63 ft. **Site 1 of 3 in cluster HV**

Actual:
756 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1987	AUSTIN AUTO AIR INC	Auto And Home Supply Stores
1992	AUTOSYSTEMS WORKSHOP	General Automotive Repair Shops
1993	AUTOSYSTEMS WORKSHOP	General Automotive Repair Shops
1993	LONGS GUARANTEE TRANSM SVC	Automotive Transmission Repair Shops
1993	LEE DAVID	General Automotive Repair Shops
1994	LONGS GUARANTEE TRANSM SVC	Automotive Transmission Repair Shops
1994	AUTOSYSTEMS WORKSHOP	General Automotive Repair Shops
1994	LEE AUTO REPAIR	General Automotive Repair Shops
1995	LEE AUTO REPAIR	General Automotive Repair Shops
1995	LONGS GUARANTEE TRANSM SVC	Automotive Transmission Repair Shops
1996	A AUTO ELECTRONICS	General Automotive Repair Shops
1996	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
1996	T&T TRANSMISSION	Automotive Transmission Repair Shops
1997	A AUTO ELECTRONICS	General Automotive Repair Shops
1997	THANET AUTO SERVICE	General Automotive Repair Shops
1997	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
1997	T&T TRANSMISSION	Automotive Transmission Repair Shops
1998	A AUTO ELECTRONICS	General Automotive Repair Shops
1998	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
1998	THANET AUTO SERVICE	General Automotive Repair Shops
1998	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
1998	T&T TRANSMISSION	Automotive Transmission Repair Shops
1999	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
1999	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
1999	T&T TRANSMISSION	Automotive Transmission Repair Shops
1999	THANET AUTO SERVICE	General Automotive Repair Shops
2000	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2000	T&T TRANSMISSION	Automotive Transmission Repair Shops
2000	THANET AUTO SERVICE	General Automotive Repair Shops
2000	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2001	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2001	T&T TRANSMISSION	Automotive Transmission Repair Shops
2001	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2001	THANET AUTO SERVICE	General Automotive Repair Shops
2002	THANET AUTO SERVICE	General Automotive Repair Shops
2002	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2002	T&T TRANSMISSION	Automotive Transmission Repair Shops
2002	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2003	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2003	THANET AUTO SERVICE	General Automotive Repair Shops
2003	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2004	THANET AUTO SERVICE	General Automotive Repair Shops
2004	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2004	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2005	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2005	THANET AUTO SERVICE	General Automotive Repair Shops
2005	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2006	THANET AUTO SERVICE	General Automotive Repair Shops
2006	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2006	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops

AUTOSYSTEMS WORKSHOP INC (Continued) **1020227770**

2007	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2007	THANET AUTO SERVICE	General Automotive Repair Shops
2007	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2008	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2008	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2008	THANET AUTO SERVICE	General Automotive Repair Shops
2009	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2009	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2009	THANET AUTO SERVICE	General Automotive Repair Shops
2010	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2010	THANET AUTO SERVICE	General Automotive Repair Shops
2010	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2011	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2011	AUTOSYSTEMS WORKSHOP INC	General Automotive Repair Shops
2011	THANET AUTO SERVICE	General Automotive Repair Shops
2012	THANET AUTO SERVICE	General Automotive Repair Shops
2012	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2013	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2013	THANET AUTO SERVICE	General Automotive Repair Shops
2014	THANET AUTO SERVICE	General Automotive Repair Shops
2014	H&H TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops

---

HW998 **GUADALUPE 4413** **US BROWNFIELDS** **1011995550**
ESE **4413 GUADALUPE STREET** **FINDS** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.012 mi.
63 ft. **Site 1 of 3 in cluster HW**

Actual:
631 ft.

Focus Map:
8

US BROWNFIELDS:

Name:	GUADALUPE 4413
Address:	4413 GUADALUPE STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	217936
Parcel size:	0.22
Latitude:	30.310669
Longitude:	-97.73286
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	A & R Corner Store is a thriving convenience store located at one of most highly visiable and traveled intersections Guadalupe and 45th Streets. The service station portion of the site is currently out of service . All tanks, piping and other related service equipment were removed in 2010. Commerical convenience store. Former Use: In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Datum:	North American Datum of 1983
Acres Property ID:	67842
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported

GUADALUPE 4413 (Continued) **1011995550**

Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cindy Lee/ Tang Tran
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	5/1/1986
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	8/1/2010
Contaminant Found:	Petroleum Products
Contaminant Cleanup:	Petroleum Products
Media Affected:	Soil
Media Cleanup:	Soil
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.22
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Below Poverty Number:	1093
Below Poverty Percent:	24.54
Meidan Income:	6423
Meidan Income Number:	1830
Meidan Income Percent:	41.09

GUADALUPE 4413 (Continued) **1011995550**

Vacant Housing Number:	133
Vacant Housing Percent:	4.95
Unemployed Number:	198
Unemployed Percent:	4.45
Name:	GUADALUPE 4413
Address:	4413 GUADALUPE STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	217936
Parcel size:	0.22
Latitude:	30.310669
Longitude:	-97.73286
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	A & R Corner Store is a thriving convenience store located at one of most highly visiable and traveled intersections Guadalupe and 45th Streets. The service station portion of the site is currently out of service . All tanks, piping and other related service equipment were removed in 2010. Commerical convenience store. Former Use: In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Datum:	North American Datum of 1983
Acres Property ID:	67842
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	1/1/2010
Redev Completition Date:	Not reported
Completed Date:	4/1/2010
Acres Cleaned Up:	0.22
Cleanup Funding:	25000
Cleanup Funding Source:	Mr. Tang Tran
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Private/Other Funding
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cindy Lee/ Tang Tran
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y

GUADALUPE 4413 (Continued) **1011995550**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	5/1/1986
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	8/1/2010
Contaminant Found:	Petroleum Products
Contaminant Cleanup:	Petroleum Products
Media Affected:	Soil
Media Cleanup:	Soil
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.22
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Below Poverty Number:	1093
Below Poverty Percent:	24.54
Meidan Income:	6423
Meidan Income Number:	1830
Meidan Income Percent:	41.09
Vacant Housing Number:	133
Vacant Housing Percent:	4.95
Unemployed Number:	198
Unemployed Percent:	4.45

Name:	GUADALUPE 4413
Address:	4413 GUADALUPE STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	217936
Parcel size:	0.22
Latitude:	30.310669
Longitude:	-97.73286
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	A & R Corner Store is a thriving convenience store located at one of most highly visiable and traveled intersections Guadalupe and 45th Streets. The service station portion of the site is currently out of service . All tanks, piping and other related service equipment were removed in 2010. Commerical convenience store. Former Use: In the 1940's the property was developed and operated as an auto service

GUADALUPE 4413 (Continued) **1011995550**

	station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Datum:	North American Datum of 1983
Acres Property ID:	67842
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1095.67
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	96600601
Start Date:	12/11/2007
Ownership Entity:	Private
Completion Date:	3/7/2008
Current Owner:	Cindy Lee/ Tang Tran
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	5/1/1986
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	8/1/2010
Contaminant Found:	Petroleum Products
Contaminant Cleanup:	Petroleum Products
Media Affected:	Soil
Media Cleanup:	Soil
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.22
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported

GUADALUPE 4413 (Continued) **1011995550**

Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Below Poverty Number:	1093
Below Poverty Percent:	24.54
Meidan Income:	6423
Meidan Income Number:	1830
Meidan Income Percent:	41.09
Vacant Housing Number:	133
Vacant Housing Percent:	4.95
Unemployed Number:	198
Unemployed Percent:	4.45
Name:	GUADALUPE 4413
Address:	4413 GUADALUPE STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	217936
Parcel size:	0.22
Latitude:	30.310669
Longitude:	-97.73286
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	A & R Corner Store is a thriving convenience store located at one of most highly visiable and traveled intersections Guadalupe and 45th Streets. The service station portion of the site is currently out of service . All tanks, piping and other related service equipment were removed in 2010. Commerical convenience store. Former Use: In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Datum:	North American Datum of 1983
Acres Property ID:	67842
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4801.13
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment

GUADALUPE 4413 (Continued) **1011995550**

Accomplishment Count:	Y
Cooperative Agreement Number:	96600601
Start Date:	12/11/2007
Ownership Entity:	Private
Completion Date:	3/7/2008
Current Owner:	Cindy Lee/ Tang Tran
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	5/1/1986
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	8/1/2010
Contaminant Found:	Petroleum Products
Contaminant Cleanup:	Petroleum Products
Media Affected:	Soil
Media Cleanup:	Soil
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.22
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Below Poverty Number:	1093
Below Poverty Percent:	24.54
Meidan Income:	6423
Meidan Income Number:	1830
Meidan Income Percent:	41.09
Vacant Housing Number:	133
Vacant Housing Percent:	4.95
Unemployed Number:	198
Unemployed Percent:	4.45

Name:	GUADALUPE 4413
Address:	4413 GUADALUPE STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	217936
Parcel size:	0.22

GUADALUPE 4413 (Continued) **1011995550**

Latitude:	30.310669
Longitude:	-97.73286
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	A & R Corner Store is a thriving convenience store located at one of most highly visiable and traveled intersections Guadalupe and 45th Streets. The service station portion of the site is currently out of service . All tanks, piping and other related service equipment were removed in 2010. Commerical convenience store. Former Use: In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Datum:	North American Datum of 1983
Acres Property ID:	67842
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cindy Lee/ Tang Tran
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	5/1/1986
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	8/1/2010
Contaminant Found:	Petroleum Products
Contaminant Cleanup:	Petroleum Products
Media Affected:	Soil

GUADALUPE 4413 (Continued) **1011995550**

Media Cleanup:	Soil
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.22
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	In the 1940's the property was developed and operated as an auto service station then a used auto sales dealership till 1970. In 1975 it operated as a retail fueling station and convenience store. Today it operates as a convenient store.
Below Poverty Number:	1093
Below Poverty Percent:	24.54
Meidan Income:	6423
Meidan Income Number:	1830
Meidan Income Percent:	41.09
Vacant Housing Number:	133
Vacant Housing Percent:	4.95
Unemployed Number:	198
Unemployed Percent:	4.45

FINDS:
Registry ID: 110038718867

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

HW999 **PEARSON WESLEY H FILLING STATION NO 2** **EDR Hist Auto** **1013773251**
ESE **4413 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
63 ft. **Site 2 of 3 in cluster HW**

Actual:
631 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	PEARSON WESLEY X	GASOLINE AND OIL SERVICE STATIONS
1947	PEARSON WESLEY H FILLING STATIO	GASOLINE AND OIL SERVICE STATIONS
1953	PETERSON & COOK	GASOLINE STATIONS
1958	PILLOW SERV STA	GASOLINE STATIONS
1997	A&R CORNER STORE	Convenience Stores
1998	A&R CORNER STORE	Convenience Stores
1999	A&R CORNER STORE	Convenience Stores
2000	A&R CORNER STORE	Convenience Stores
2001	A&R CORNER STORE	Convenience Stores
2002	A&R CORNER STORE	Convenience Stores

PEARSON WESLEY H FILLING STATION NO 2 (Continued) **1013773251**

2003	A&R CORNER STORE	Convenience Stores
2004	A&R CORNER STORE	Convenience Stores
2005	A&R CORNER STORE	Convenience Stores
2006	A&R CORNER STORE	Convenience Stores
2007	A&R CORNER STORE	Convenience Stores
2008	A&R CORNER STORE	Convenience Stores
2009	A&R CORNER STORE	Convenience Stores
2010	A&R CORNER STORE	Convenience Stores
2011	A&R CORNER STORE	Convenience Stores
2012	A&R CORNER STORE	Convenience Stores
2013	A&R CORNER STORE	Convenience Stores
2014	A&R CORNER STORE	Convenience Stores

HW1000 **A & R CORNER STORE** **TX UST** **U003566309**
ESE **4413 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78751** **TX Financial Assurance**
0.012 mi.
63 ft. **Site 3 of 3 in cluster HW**

Actual:
631 ft.

Focus Map:
8

UST:

Name:	A & R CORNER STORE
Address:	4413 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787513616
AI Number:	36621
Facility Type:	RETAIL
Facility Begin Date:	08/31/1990
Facility Status:	INACTIVE
Additional ID:	675373862002152
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	TANG TRAN,OWNER
Contact Organization Name:	A & R CORNER STORE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128730173
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	DON ESPERSON,FAC MANAGER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	318600832002028
Additional ID:	675373862002152
Ai Number:	36621

A & R CORNER STORE (Continued) **U003566309**

Operator CN:	CN600743546
Operator Name:	TANG TRAN
Operator Effective Begin Date:	01/01/1996
Operator Type:	IN
Operator Role:	OPRCON
Contact Name:	TANG TRAN/OWNER
Contact Organization Name:	TRAN TANG
Contact Mailing Address (Delivery):	4413 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78751-3616
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4597055
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600743546
Owner Last Name:	TRAN
Owner First Name:	TANG
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	318600832002028
Additional ID:	675373862002152
AI Number:	36621
Owner Effective Begin Date:	01/01/1996
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	87030
Cert ID:	135152
AI Number:	36621
Self Certification Date:	07/14/2006
Signature Name/Title:	TANG TRAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

A & R CORNER STORE (Continued) **U003566309**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87030
Cert ID:	135151
AI Number:	36621
Self Certification Date:	08/11/2005
Signature Name/Title:	TANG TRAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87030
Cert ID:	135150
AI Number:	36621
Self Certification Date:	10/25/2004
Signature Name/Title:	TANG TRAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87030
Cert ID:	135149
AI Number:	36621
Self Certification Date:	06/14/2003
Signature Name/Title:	TANG TRAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

A & R CORNER STORE (Continued) **U003566309**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87030
Cert ID:	135148
AI Number:	36621
Self Certification Date:	05/15/2001
Signature Name/Title:	TANG TRAN OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	96883
Facility ID:	87030
Ai Number:	36621
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/08/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

A & R CORNER STORE (Continued) **U003566309**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	129715
UST ID:	96883
AI Number:	36621
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

A & R CORNER STORE (Continued) **U003566309**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14220
Cert ID:	48580
UST Comprt ID:	127506
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48578
UST Comprt ID:	127508
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48581
UST Comprt ID:	127505
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48577
UST Comprt ID:	127507
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48579

A & R CORNER STORE (Continued) **U003566309**

UST Comprt ID:	127509
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	96884
Facility ID:	87030
Ai Number:	36621
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/08/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

A & R CORNER STORE (Continued) **U003566309**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	127701
UST ID:	96884
AI Number:	36621
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

A & R CORNER STORE (Continued) **U003566309**

Self Cert ID:	14220
Cert ID:	48580
UST Comprt ID:	127506
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48578
UST Comprt ID:	127508
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48581
UST Comprt ID:	127505
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48577
UST Comprt ID:	127507
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48579
UST Comprt ID:	127509
UST ID:	53547
AI Number:	36621
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	13775
Facility ID:	87030
AI Number:	36621
Application Received Date:	12/14/2009
Scheduled Construction Date:	12/16/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N

A & R CORNER STORE (Continued) **U003566309**

Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	58147
General Desc Of Prop Construct:	PERMANENT REMOVAL AND DISPOSAL OF TWO (2) TANKS, SAMPLING AND REPORTING. REQUES T 30 DAY WAIVER.

Facility Billing Contacts:

Contact Organization Name:	TRAN TANG
Contact Mailing Address (Delivery):	4413 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 3616
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87030
Additional ID:	675373862002152
Princ ID:	318600832002028
AI Number:	36621
Facility Name:	A & R CORNER STORE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	TANG TRAN/

HIST UST AUSTIN:

Name:	A & R CORNER STORE
Address:	4413 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	658
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	A & R CORNER STORE
Address:	4413 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	87030
Finass ID:	69391
AI:	36621
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

A & R CORNER STORE (Continued) **U003566309**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

HX1001 **HOME DEPOT USA HD6553** **RCRA-SQG** **1007881382**
North **13309 N IH 35** **TXR000060608**
< 1/8 **AUSTIN, TX 78753**
0.012 mi.
63 ft. **Site 1 of 2 in cluster HX**

Actual:
762 ft.

Focus Map:
2

RCRA Listings:

Date Form Received by Agency:	20230419
Handler Name:	Home Depot Usa Hd6553
Handler Address:	N IH 35
Handler City,State,Zip:	AUSTIN, TX 78753-1023
EPA ID:	TXR000060608
Contact Name:	MICHELLE OBRIEN
Contact Address:	PACES FERRY RD SE # D-4
Contact City,State,Zip:	ATLANTA, GA 30339-6444
Contact Telephone:	770-433-8211
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PACES FERRY RD SE # D-4
Mailing City,State,Zip:	ATLANTA, GA 30339-6444
Owner Name:	Home Depot Usa Inc
Owner Type:	Private
Operator Name:	Home Depot Usa Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

HOME DEPOT USA HD6553 (Continued) **1007881382**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230523
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead

HOME DEPOT USA HD6553 (Continued) **1007881382**

Waste Code: D009
Waste Description: Mercury

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D028
Waste Description: 1,2-Dichloroethane

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P122
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Greater Than 10% (R,T)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

HOME DEPOT USA HD6553 (Continued) **1007881382**

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U151
Waste Description: Mercury

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U228
Waste Description: Ethene, Trichloro- (Or) Trichloroethylene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Waste Code: U249
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Of 10% Or Less

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20060828
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Telephone:	512-989-6650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20060828
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	512-989-6650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20071012
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091201
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091215
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211

HOME DEPOT USA HD6553 (Continued) **1007881382**

Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-1834
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20041003
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	512-989-6650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20090818
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091201
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20120702
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008-7393
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip: ATLANTA, GA 30339-6444
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008-7393
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20041003
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008
Owner/Operator Telephone: 760-602-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20060621
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008
Owner/Operator Telephone: 760-602-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20060828
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100202
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100803
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-6444

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091029
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091215
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100202
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100629

HOME DEPOT USA HD6553 (Continued) **1007881382**

Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC,	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20120702
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-1834
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20050218
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008
Owner/Operator Telephone: 512-989-6650
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20060828
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008
Owner/Operator Telephone: 760-602-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip: ATLANTA, GA 30339-1834
Owner/Operator Telephone: 770-384-3540
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip: ATLANTA, GA 30339-6444
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20050618
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008
Owner/Operator Telephone: 512-989-6650
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20090818
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	512-989-6650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100629
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20100803
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC,	
Legal Status:	Private
Date Became Current:	20090817
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-1834
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-1834

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-1834
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20071012
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	512-989-6650
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC,	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211

HOME DEPOT USA HD6553 (Continued) **1007881382**

Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008-7393
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091211
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE # C19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339-6444
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20050218
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20050618
Date Ended Current:	Not reported
Owner/Operator Address:	1905 ASTON AVE STE 100
Owner/Operator City,State,Zip:	CARLSBAD, CA 92008
Owner/Operator Telephone:	760-602-8700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOME DEPOT USA INC	
Legal Status:	Private
Date Became Current:	20091029
Date Ended Current:	Not reported
Owner/Operator Address:	2455 PACES FERRY AVE C 19
Owner/Operator City,State,Zip:	ATLANTA, GA 30339
Owner/Operator Telephone:	770-384-3540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

HOME DEPOT USA HD6553 (Continued) **1007881382**

Owner/Operator Name: HOME DEPOT USA INC,
Legal Status: Private
Date Became Current: 20090817
Date Ended Current: Not reported
Owner/Operator Address: 2455 PACES FERRY AVE
Owner/Operator City,State,Zip: ATLANTA, GA 30339-1834
Owner/Operator Telephone: 770-384-3540
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008-7393
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOME DEPOT USA INC
Legal Status: Private
Date Became Current: 20091211
Date Ended Current: Not reported
Owner/Operator Address: 1905 ASTON AVE STE 100
Owner/Operator City,State,Zip: CARLSBAD, CA 92008-7393
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20041003
Handler Name: HOME DEPOT USA INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050218
Handler Name: HOME DEPOT USA INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

HOME DEPOT USA HD6553 (Continued) **1007881382**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20050618
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060627
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060829
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060925
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

HOME DEPOT USA HD6553 (Continued) **1007881382**

Receive Date:	20071012
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090818
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20091029
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20091201
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20091215
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

HOME DEPOT USA HD6553 (Continued) **1007881382**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20100202
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20100629
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20100803
Handler Name: HOME DEPOT USA INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110503
Handler Name: HOME DEPOT USA HD6553	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

HOME DEPOT USA HD6553 (Continued) **1007881382**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110621
Handler Name: HOME DEPOT USA HD6553
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120702
Handler Name: HOME DEPOT USA INC - HD6553
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20121219
Handler Name: HOME DEPOT USA HD6553
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130227
Handler Name: HOME DEPOT USA HD6553
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141104
Handler Name: HOME DEPOT USA HD6553

HOME DEPOT USA HD6553 (Continued) **1007881382**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150623
Handler Name: HOME DEPOT USA HD6553	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150706
Handler Name: HOME DEPOT USA HD6553	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180507
Handler Name: HOME DEPOT USA HD6553	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20211020
Handler Name: HOME DEPOT USA HD6553	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

HOME DEPOT USA HD6553 (Continued) **1007881382**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20230419
Handler Name:	HOME DEPOT USA HD6553
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20230419
Handler Name:	HOME DEPOT USA HD6553
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44411
NAICS Description:	HOME CENTERS

NAICS Code:	444110
NAICS Description:	HOME CENTERS

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Federal or State Statute
Date Violation was Determined:	20220121
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported

HOME DEPOT USA HD6553 (Continued) **1007881382**

Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20220121
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	TT
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

HX1002 **HOME DEPOT USA HD6553** **TX Ind. Haz Waste** **S106872814**
North **13309 N IH 35** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.012 mi.
63 ft. **Site 2 of 2 in cluster HX**

Actual:
762 ft.

Focus Map:
2

Ind. Haz Waste:

Name:	HOME DEPOT USA HD6553
Address:	13309 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	87565
Registration Initial Notification Date:	10/03/2004
Registration Last Amendment Date:	10/20/2021
EPA Identification:	TXR000060608
Primary NAICS Code:	444110
Status Change Date:	20041003
Land Type:	PRIVATE
Description of Facility Site Location:	13309 N IH 35 AUSTIN TX
Site Primary Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	HOME DEPOT USA INC
Contact Name:	ASHLEY CAMPBELL
Contact Telephone Number:	281-8420809
Mailing Address:	9950 CHEMICAL RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	PASADENA, TX 775071606
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	118210
Site Owner Tax ID:	581853319
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20211221
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	HOME DEPOT USA INC
Operator Address:	2455 PACES FERRY AVE # C19
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	ATLANTA, GA 30339
Operator Country:	UNITED STA
Operator Telephone:	1-770-3843540
Operator Fax Number:	Not reported
Operator Email:	mkoske@3ecompany.com
Operator Business Type:	Corporation
Operator Tax ID:	15818533190
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	HOME DEPOT USA INC

HOME DEPOT USA HD6553 (Continued) **S106872814**

Owner Mailing Address:	1905 ASTON AVE STE 100
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	CARLSBAD, CA 92008
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	1-760-9184025
Owner Email Address:	mkoske@3ecompany.com
Owner Business Type:	Corporation
Owner Tax ID:	15818533190
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	200
Capacity Measurement:	P
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Off spec and damaged material.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20060828
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2455 PACES FERRY AVE # C19
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	ATLANTA, GA 30339
Contact Phone:	1-770-3843540
Contact Fax:	Not reported
Contact Email:	mkoske@3ecompany.com

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1905 ASTON AVE STE 100
Contact Address 2:	Not reported
Contact Address 3:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Contact City,State,Zip:	CARLSBAD, CA 92008
Contact Phone:	Not reported
Contact Fax:	1-760-9184025
Contact Email:	mkoske@3ecompany.com
Contact Name:	ASHLEY CAMPBELL
Contact Title:	COMPLIANCE & REGULATORY A
Contact Role:	PRICONT
Contact Address:	9950 CHEMICAL RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	PASADENA, TX 77507
Contact Phone:	1-281-8420809
Contact Fax:	Not reported
Contact Email:	ACAMPBELL@HARSCO.COM

Ind. Haz Waste:

Waste ID:	209593
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Liquids nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS NO
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209594
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acidic Organic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS AC
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209595
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Basic Organic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS BA
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209596
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Basic Inorganic nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

HOME DEPOT USA HD6553 (Continued) **S106872814**

Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS BA
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209597
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Liquids Organic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC LIQUIDS ORGANI
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209598
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Solid Organic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLID ORGANIC
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209599
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aerosols; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209600
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acidic Inorganic; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS AC
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	209601
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Gasoline; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	GASOLINE
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209602
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury Lamps; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MERCURY LAMPS
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209603

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0011003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Charcoal; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CHARCOAL
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209604
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Solid Acidic Inorganic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE SOLID ACID
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209605
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013003H
Waste Code Status:	INACTIVE
Waste Form:	003

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Solids Basic Inorganic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE SOLIDS BAS
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209606
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Liquids Toxic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS TO
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209607
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Fuses; Inactivated for Unknown Reason.

HOME DEPOT USA HD6553 (Continued) **S106872814**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FUSEE
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209608
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hazardous Waste Solid Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HAZARDOUS WASTE SOLI
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209609
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic Peroxide Type D Liquid; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ORGANIC PEROXIDE TYP
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209610
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizer Liquid Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZER LIQUID NOS
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209611
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizer Solid Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

HOME DEPOT USA HD6553 (Continued) **S106872814**

Audit Performed:	0
Company Waste ID:	OXIDIZER SOLID NOS
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209612
Texas Waste Code:	Not reported
Texas Waste Code 2:	0020003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxygen Compressed; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXYGEN COMPRESSED
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209613
Texas Waste Code:	Not reported
Texas Waste Code 2:	0021003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Pesticide Liquid Toxic Nos; Inactivated for Unknown Reason.; Inactivated for Unk
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PESTICIDE LIQUID TOX
Primary NAICS Code:	444110
EPA Waste Form Code:	W001

HOME DEPOT USA HD6553 (Continued) **S106872814**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209614
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Pesticide Solid Toxic Nos; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PESTICIDE SOLID TOXI
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209615
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sodium Hydrosulfite; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SODIUM HYDROSULFITE
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	216177
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint Related Material; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PAINT RELATED MATERI
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	216178
Texas Waste Code:	Not reported
Texas Waste Code 2:	0025003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Propane; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PROPANE
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	216179
Texas Waste Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code 2:	0026003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hypochlorite Solutions; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HYPOCHLORITE SOLUTIO
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	216180
Texas Waste Code:	Not reported
Texas Waste Code 2:	0027003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic Peroxide Solids; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ORGANIC PEROXIDE SOL
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236417
Texas Waste Code:	Not reported
Texas Waste Code 2:	0100210H
Waste Code Status:	INACTIVE
Waste Form:	210
Waste Classification:	H

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ORGANIC PEROXIDE; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME5 2
Primary NAICS Code:	444110
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236418
Texas Waste Code:	Not reported
Texas Waste Code 2:	0101001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	WASTE CORROSIVE FLAMMABLE; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMECORFLAM
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236419
Texas Waste Code:	Not reported
Texas Waste Code 2:	0103409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	DEBRIS CONTAINING GASOLINE

HOME DEPOT USA HD6553 (Continued) **S106872814**

Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMESPILLGAS
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236420
Texas Waste Code:	Not reported
Texas Waste Code 2:	0104113H
Waste Code Status:	ACTIVE
Waste Form:	113
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OZZY JUICE - PARTS WASHER SOLUTION
Standard Industrial Code:	Not reported
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEOZZY
Primary NAICS Code:	444110
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236421
Texas Waste Code:	Not reported
Texas Waste Code 2:	0105409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FLAMMABLE SOLID LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME4 1
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236422
Texas Waste Code:	Not reported
Texas Waste Code 2:	0106211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FLAMMABLE LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME3
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236423
Texas Waste Code:	Not reported
Texas Waste Code 2:	0107001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ALKALINE/CORROSIVE LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME8B
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236424
Texas Waste Code:	Not reported
Texas Waste Code 2:	0108119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ACIDIC/CORROSIVE LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME8A
Primary NAICS Code:	444110
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236425
Texas Waste Code:	Not reported
Texas Waste Code 2:	0109409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	TOXIC (SOLIDS ONLY) LOOSEPACK - NO FERTILIZERS
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME6 1S
Primary NAICS Code:	444110
EPA Waste Form Code:	W409

HOME DEPOT USA HD6553 (Continued) **S106872814**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236426
Texas Waste Code:	Not reported
Texas Waste Code 2:	0110219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	TOXIC (LIQUIDS ONLY) LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME6 1L
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236427
Texas Waste Code:	Not reported
Texas Waste Code 2:	0111801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	AEROSOLS - ACCUMULATION DRUM
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME2 1
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	236428
Texas Waste Code:	Not reported
Texas Waste Code 2:	0112319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZER SOLID LOOSEPACK; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME5 1
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236429
Texas Waste Code:	Not reported
Texas Waste Code 2:	0113209H
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OIL BASED PAINTS AND STAINS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEBPAINT
Primary NAICS Code:	444110
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236430
Texas Waste Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code 2:	0114409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FERTILIZERS WITH PESTICIDES (BROKEN BAGS ONLY)
Standard Industrial Code:	Not reported
Primary Source:	G33
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEPESTINC
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236431
Texas Waste Code:	Not reported
Texas Waste Code 2:	0115001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	BLEACH SOLUTIONS (NO SOLIDS) LOOSEPACK; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEBLEACH
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236432
Texas Waste Code:	Not reported
Texas Waste Code 2:	0116307H
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	H

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CRUSHED FLUORESCENT LIGHT TUBES; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMETUBEC
Primary NAICS Code:	444110
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236433
Texas Waste Code:	Not reported
Texas Waste Code 2:	0117409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FERTILIZER SWEEPINGS ONLY (NO BAGS)
Standard Industrial Code:	Not reported
Primary Source:	G33
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEPESTLF
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236434
Texas Waste Code:	Not reported
Texas Waste Code 2:	0118211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	BULK GASOLINE
Standard Industrial Code:	Not reported
Primary Source:	G33

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEGAS
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236435
Texas Waste Code:	Not reported
Texas Waste Code 2:	0119801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	COMPRESSED GAS CYLINDERS (All Sizes); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMECYSML
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236436
Texas Waste Code:	Not reported
Texas Waste Code 2:	0120801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXYGEN COMPRESSED GAS CYLINDERS (SMALL)
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1

HOME DEPOT USA HD6553 (Continued) **S106872814**

Audit Performed:	0
Company Waste ID:	HOMECYSO
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236437
Texas Waste Code:	Not reported
Texas Waste Code 2:	0121117H
Waste Code Status:	ACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	APPARATUSES CONTAINING MERCURY AND DEBRIS
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEHG
Primary NAICS Code:	444110
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236438
Texas Waste Code:	Not reported
Texas Waste Code 2:	0122319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZER LIQUID LOOSE PACK; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEOXLIQ
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236439
Texas Waste Code:	Not reported
Texas Waste Code 2:	0123219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OFF SPEC CATCH BASIN WATER
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEFLASH
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236440
Texas Waste Code:	Not reported
Texas Waste Code 2:	0124801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	LIGHTERS FOR DISPOSAL
Standard Industrial Code:	Not reported
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMELIGHT
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	236441
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	COMPRESSED GAS CYLINDERS (MAPP Gas); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEMAPPGAS
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	241251
Texas Waste Code:	Not reported
Texas Waste Code 2:	0126219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ORGANIC PEROXIDE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME5 2
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	241252
Texas Waste Code:	Not reported
Texas Waste Code 2:	0127119H
Waste Code Status:	ACTIVE

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	BLEACH SOLUTIONS (NO SOLIDS) LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEBLEACH
Primary NAICS Code:	444110
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	241253
Texas Waste Code:	Not reported
Texas Waste Code 2:	0128319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CRUSHED FLUORESCENT LIGHT TUBES
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMETUBEC
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	241254
Texas Waste Code:	Not reported
Texas Waste Code 2:	0129219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZER LIQUID LOOSE PACK; Inactivated for Unknown Reason.

HOME DEPOT USA HD6553 (Continued) **S106872814**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEOXLIQ
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	246211
Texas Waste Code:	Not reported
Texas Waste Code 2:	0130211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FLAMMABLE/TOXIC LOOSE PACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME36 1-01
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	246212
Texas Waste Code:	Not reported
Texas Waste Code 2:	0131002H
Waste Code Status:	ACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	LEAD CONTAMINATED DEBRIS
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMELEADDEB-00
Primary NAICS Code:	444110
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	246213
Texas Waste Code:	Not reported
Texas Waste Code 2:	0133002H
Waste Code Status:	ACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PARTS WASHER MACHINE
Standard Industrial Code:	Not reported
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEPARTSWM-00
Primary NAICS Code:	444110
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	246214
Texas Waste Code:	Not reported
Texas Waste Code 2:	0134309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	REGULATED LEAD ACID BATTERIES FOR RECYCLING (AUTOMOTIVE)
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMERGPBBATT-00
Primary NAICS Code:	444110

HOME DEPOT USA HD6553 (Continued) **S106872814**

EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	247647
Texas Waste Code:	Not reported
Texas Waste Code 2:	0135119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZER LIQUID LOOSE PACK; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEOXLIQ
Primary NAICS Code:	444110
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	247648
Texas Waste Code:	Not reported
Texas Waste Code 2:	0136309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	REGULATED SMALL SEALED LEAD ACID BATTERIES
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMERGSSLA-00
Primary NAICS Code:	444110
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	254351
Texas Waste Code:	Not reported
Texas Waste Code 2:	0137105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ACIDS CONTAINING HYDROFLUORIC ACID
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEHFACID
Primary NAICS Code:	444110
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254352
Texas Waste Code:	Not reported
Texas Waste Code 2:	0138409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ZINC PHOSPHIDE RODENTICIDE; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME4 3ZNPH
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254353

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0139409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	POOL TABLETS; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEPOOLTAB
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254354
Texas Waste Code:	Not reported
Texas Waste Code 2:	0140002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	EMPTY GAS CADDY; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEEMGASCAD
Primary NAICS Code:	444110
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254355
Texas Waste Code:	Not reported
Texas Waste Code 2:	0141210H
Waste Code Status:	INACTIVE
Waste Form:	210
Waste Classification:	H

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ISOCYANATES CYLINDER; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEISOCYL
Primary NAICS Code:	444110
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254356
Texas Waste Code:	Not reported
Texas Waste Code 2:	0142319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OIL BASED PAINT CONTAMINATED DEBRIS
Standard Industrial Code:	Not reported
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMERGPNTDBR
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254357
Texas Waste Code:	Not reported
Texas Waste Code 2:	0143319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SAFETY BOOSTERS; Inactivated for Unknown Reason.

HOME DEPOT USA HD6553 (Continued) **S106872814**

Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMESAFBOOST
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254358
Texas Waste Code:	Not reported
Texas Waste Code 2:	0144219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	METHANOL/ETHANOL AND WATER; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	355816
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254359
Texas Waste Code:	Not reported
Texas Waste Code 2:	0145409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MOTH BALLS
Standard Industrial Code:	Not reported
Primary Source:	G11

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEMOTHBLS
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254360
Texas Waste Code:	Not reported
Texas Waste Code 2:	0146519H
Waste Code Status:	ACTIVE
Waste Form:	519
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ACIDIC/CORROSIVE /ORGANIC LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOME8AO
Primary NAICS Code:	444110
EPA Waste Form Code:	W519
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254361
Texas Waste Code:	Not reported
Texas Waste Code 2:	0147801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ACETYLENE CYLINDER; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEACETYLCY
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	254362
Texas Waste Code:	Not reported
Texas Waste Code 2:	0148001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	AMINES LIQUID CORROSIVE FLAMMABLE; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEAMINES
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335088
Texas Waste Code:	Not reported
Texas Waste Code 2:	20008011
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	MDI RESIN CYLINDER
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335089
Texas Waste Code:	Not reported
Texas Waste Code 2:	2001402H
Waste Code Status:	ACTIVE
Waste Form:	402
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ZINC PHOSPHIDE RODENTICIDE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W401
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335091
Texas Waste Code:	Not reported
Texas Waste Code 2:	2002211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	TOXIC/FLAMMABLE LIQUIDS LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	335092
Texas Waste Code:	Not reported
Texas Waste Code 2:	20033051
Waste Code Status:	ACTIVE
Waste Form:	305
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	CORROSIVE SOLIDS,INORGANIC
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335093
Texas Waste Code:	Not reported
Texas Waste Code 2:	2004801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ACETYLENE CYLINDERS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335094
Texas Waste Code:	Not reported
Texas Waste Code 2:	20053111
Waste Code Status:	ACTIVE

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Form:	311
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ASBESTOS,FRIABLE AND NON-FRIABLE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335095
Texas Waste Code:	Not reported
Texas Waste Code 2:	20062961
Waste Code Status:	ACTIVE
Waste Form:	296
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ANTIFREEZE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335097
Texas Waste Code:	Not reported
Texas Waste Code 2:	20077011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	CARBON DIOXIDE(CO2)CYLINDERS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335098
Texas Waste Code:	Not reported
Texas Waste Code 2:	20087011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDERS,LARGE (INORGANIC); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	335101
Texas Waste Code:	Not reported
Texas Waste Code 2:	20097011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDERS,MEDIUM (INORGANIC); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	335103
Texas Waste Code:	Not reported
Texas Waste Code 2:	20107011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDER,SMALL (INORGANIC); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	335108
Texas Waste Code:	Not reported
Texas Waste Code 2:	2011002H
Waste Code Status:	ACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	EMPTY GAS CADDY
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335109
Texas Waste Code:	Not reported
Texas Waste Code 2:	20123081
Waste Code Status:	ACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Treated Off Site:	1
Generators Waste Description:	EMPTY DRUM
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335110
Texas Waste Code:	Not reported
Texas Waste Code 2:	20137011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	HELIUM CYLINDERS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335111
Texas Waste Code:	Not reported
Texas Waste Code 2:	2014117H
Waste Code Status:	ACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ELEMENTAL MERCURY
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary NAICS Code:	444110
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335112
Texas Waste Code:	Not reported
Texas Waste Code 2:	20152101
Waste Code Status:	ACTIVE
Waste Form:	210
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	POLYMERIC MDI LIQUID
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335113
Texas Waste Code:	Not reported
Texas Waste Code 2:	20167011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	MOSQUITO MAGNET CO2 CARTRIDGES
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	335114
Texas Waste Code:	Not reported
Texas Waste Code 2:	20173191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	NON-PCB LIGHT BALLASTS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335115
Texas Waste Code:	Not reported
Texas Waste Code 2:	20183191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	NON-RCRA FERTILIZERS,SOLID
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335116
Texas Waste Code:	Not reported
Texas Waste Code 2:	20194891
Waste Code Status:	ACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	OILY DEBRIS
Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335117
Texas Waste Code:	Not reported
Texas Waste Code 2:	20202101
Waste Code Status:	ACTIVE
Waste Form:	210
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	POLYOL RESIN
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335118
Texas Waste Code:	Not reported
Texas Waste Code 2:	2021319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	POOL TABLETS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335119
Texas Waste Code:	Not reported
Texas Waste Code 2:	20222191
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	OIL-FILLED RADIATOR HEATER
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335120
Texas Waste Code:	Not reported
Texas Waste Code 2:	20238011
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	REFRIGERANT GAS CYLINDERS,SMALL
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	335121
Texas Waste Code:	Not reported
Texas Waste Code 2:	2024409H
Waste Code Status:	ACTIVE

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	FLAMMABLE DEBRIS
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335122
Texas Waste Code:	Not reported
Texas Waste Code 2:	2025405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SAFETY BOOSTERS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335123
Texas Waste Code:	Not reported
Texas Waste Code 2:	2026102H
Waste Code Status:	ACTIVE
Waste Form:	102

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	INSECTICIDE LIQUIDS WITH CARBARYL
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335124
Texas Waste Code:	Not reported
Texas Waste Code 2:	2027316H
Waste Code Status:	ACTIVE
Waste Form:	316
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	WELDING RODS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	335100
Texas Waste Code:	Not reported
Texas Waste Code 2:	20288011
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDER,LARGE (ORGANIC); Inactivated for Unknown Reason.

HOME DEPOT USA HD6553 (Continued) **S106872814**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	335102
Texas Waste Code:	Not reported
Texas Waste Code 2:	20298011
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDERS,MEDIUM (ORGANIC); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	335105
Texas Waste Code:	Not reported
Texas Waste Code 2:	20308011
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NON-FLAMMABLE GAS CYLINDER,SMALL (ORGANIC); Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	336227
Texas Waste Code:	Not reported
Texas Waste Code 2:	2031202H
Waste Code Status:	ACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	TOXIC LIQUIDS,HALOGENATED ORGANICS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336230
Texas Waste Code:	Not reported
Texas Waste Code 2:	2032211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	DIESEL FUEL,BULK
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336231
Texas Waste Code:	Not reported
Texas Waste Code 2:	20333101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OIL FILTERS; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	336232
Texas Waste Code:	Not reported
Texas Waste Code 2:	2034603H
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OZZY JUICE/MATS/SLUDGE; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336233
Texas Waste Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code 2:	20354961
Waste Code Status:	ACTIVE
Waste Form:	496
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	PCB LIGHT BALLASTS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	351068
Texas Waste Code:	Not reported
Texas Waste Code 2:	2037114H
Waste Code Status:	ACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZER LIQUIDS LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336218
Texas Waste Code:	Not reported
Texas Waste Code 2:	2038110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ZAP ENFORCER
Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336219
Texas Waste Code:	Not reported
Texas Waste Code 2:	20391031
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OILY WATER; Inactivated for Unknown Reason.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	336220
Texas Waste Code:	Not reported
Texas Waste Code 2:	20407011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	FIRE EXTINGUISHER,SMALL
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	336221
Texas Waste Code:	Not reported
Texas Waste Code 2:	2041319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	OXIDIZER SOLIDS LOOSEPACK
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	336222
Texas Waste Code:	Not reported
Texas Waste Code 2:	2042801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	MAPP GAS CYLINDERS
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	336223
Texas Waste Code:	Not reported
Texas Waste Code 2:	20434091
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	LATEX PAINT CONTAMINATED DEBRIS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	336224
Texas Waste Code:	Not reported
Texas Waste Code 2:	20442191
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	NON-REGULATED WASTE PRODUCTS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	336225
Texas Waste Code:	Not reported
Texas Waste Code 2:	20452061
Waste Code Status:	ACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	USED OIL,BULK
Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	336226
Texas Waste Code:	Not reported
Texas Waste Code 2:	20462051
Waste Code Status:	ACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SUMP WATER FROM CATCH BASINS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	346782
Texas Waste Code:	Not reported
Texas Waste Code 2:	2047219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	FLAMMABLE/CORROSIVE LIQUIDS, ACIDIC
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346784
Texas Waste Code:	Not reported
Texas Waste Code 2:	2048203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	FLAMMABLE/CORROSIVE LIQUIDS, ALKALINE
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346786
Texas Waste Code:	Not reported
Texas Waste Code 2:	2049203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	FLAMMABLE LIQUIDS, U-LISTED
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	346787
Texas Waste Code:	Not reported
Texas Waste Code 2:	2050110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	ALKALINE LIQUIDS, ORGANIC
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346788
Texas Waste Code:	Not reported
Texas Waste Code 2:	2051316H
Waste Code Status:	ACTIVE
Waste Form:	316
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	METAL BEARING CAULKS/SEALANTS (RCRA)
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W316
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste ID:	346789
Texas Waste Code:	Not reported
Texas Waste Code 2:	2052219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	CLASS 9 LIQUIDS, ORGANIC (RCRA)
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346790
Texas Waste Code:	Not reported
Texas Waste Code 2:	20532101
Waste Code Status:	ACTIVE
Waste Form:	210
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	BENZOYL PEROXIDE HARDENERS, <10% BPO
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	346791
Texas Waste Code:	Not reported
Texas Waste Code 2:	2054211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	JET FUEL
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346792
Texas Waste Code:	Not reported
Texas Waste Code 2:	2055307H
Waste Code Status:	ACTIVE
Waste Form:	307
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SOLDER MATERIALS
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	346793
Texas Waste Code:	Not reported
Texas Waste Code 2:	20568011
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	POLYOL CYLINDER
Standard Industrial Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	346794
Texas Waste Code:	Not reported
Texas Waste Code 2:	20572191
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	AMINES, CORROSIVE/NON-FLAMMABLE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	367055
Texas Waste Code:	Not reported
Texas Waste Code 2:	2068307H
Waste Code Status:	ACTIVE
Waste Form:	307
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	KEY SHAVINGS
Standard Industrial Code:	Not reported
Primary Source:	G05
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	367056
Texas Waste Code:	Not reported
Texas Waste Code 2:	2070409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ROAD FLARES
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	367057
Texas Waste Code:	Not reported
Texas Waste Code 2:	2071001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	INORGANIC OXIDIZER SOLID
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Waste ID:	367058
Texas Waste Code:	Not reported
Texas Waste Code 2:	2073801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	POWER TOOL FUEL CELLS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	367059
Texas Waste Code:	Not reported
Texas Waste Code 2:	2074409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CHARCOAL
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	367060
Texas Waste Code:	Not reported

HOME DEPOT USA HD6553 (Continued) **S106872814**

Texas Waste Code 2:	2076319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MATCHES
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	367061
Texas Waste Code:	Not reported
Texas Waste Code 2:	2077801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ISOCYANATES CYLINDERS
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	373713
Texas Waste Code:	Not reported
Texas Waste Code 2:	2079801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0

HOME DEPOT USA HD6553 (Continued) **S106872814**

Waste Treated Off Site:	Not reported
Generators Waste Description:	NITROUS OXIDE CARTRIDGES
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMENITROUS-01
Primary NAICS Code:	444110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	373714
Texas Waste Code:	Not reported
Texas Waste Code 2:	2082219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUMP WASTE, IGNITABLE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HOMEFLASHK03-00
Primary NAICS Code:	444110
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

HOME DEPOT USA HD6553 (Continued) **S106872814**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-281-8420809 x0
Mailing Address:	9950 CHEMICAL RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	PASADENA, TX 77507
AR Number:	0000314146
Principal Name:	HOME DEPOT USA INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-281-8420809 x0
Mailing Address:	9950 CHEMICAL RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	PASADENA, TX 77507
AR Number:	0000314146
Principal Name:	HOME DEPOT USA INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-281-8420809 x0
Mailing Address:	9950 CHEMICAL RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	PASADENA, TX 77507
AR Number:	0000314437
Principal Name:	HOME DEPOT USA INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-281-8420809 x0
Mailing Address:	9950 CHEMICAL RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	PASADENA, TX 77507
AR Number:	0000314437
Principal Name:	HOME DEPOT USA INC
Attention Name:	Not reported
Attention Suffix:	NWG

DX1003 **J.P. SCHNEIDER** **TX HIST UST** **S111678696**
WNW **401 W 2ND ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
63 ft. **Site 5 of 7 in cluster DX**

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	J.P. SCHNEIDER
Address:	401 W 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0333

J.P. SCHNEIDER (Continued) **S111678696**

HID UST: 333
Inspection: 04/22/2009
Due: 04/22/2012

DA1004 **AUSTIN WATER METER** **EDR Hist Auto** **1013774415**
WNW **607 RIO GRANDE** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
63 ft. **Site 9 of 25 in cluster DA**

Actual:
475 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	AUSTIN WATER METER	REPAIR SHOPS

DA1005 **CUSTOM SERVICE CARPET & DRAPERY CLEANERS** **EDR Hist Cleaner** **1013780182**
WNW **607 RIO GRANDE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.012 mi.
63 ft. **Site 10 of 25 in cluster DA**

Actual:
475 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1970	CUSTOM SERVICE CARPET & DRAPERY	CARPET AND RUG CLEANERS

HY1006 **TACO BELL** **TX LPST** **U003566358**
ENE **2801 GUADALUPE ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX ASBESTOS**
0.012 mi.
63 ft. **Site 1 of 7 in cluster HY**

Actual:
599 ft.

Focus Map:
11

LPST:

Name:	TACO BELL
Address:	2801 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0048720
LPST Id:	093370
Facility Location:	2800 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/13/1989
Entered Date:	08/03/1989
Reported Date:	07/13/1989
Closure Date:	04/23/1997
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/6/1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	DIRK DOZIER

TACO BELL (Continued) **U003566358**

Responsible Party Address:	500 CAPITOL OF TEXAS HWY
Responsible Party City,St,Zip:	AUSTIN, TX 78746
Responsible Party Telephone:	512/327-4654
Reported Date:	07/13/1989
Case Start Date:	04/23/1997
Reference Number:	RN102465234
Project Manager:	HWELCH

UST:

Name:	TACO BELL
Address:	2801 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787053764
AI Number:	48720
Facility Type:	UNKNOWN
Facility Begin Date:	08/04/1989
Facility Status:	INACTIVE
Additional ID:	480150662002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	DIRK DOZIER,VICE PRESIDENT
Contact Organization Name:	TACO BELL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123274654
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/13/1989
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	07/17/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601271059
Owner Last Name:	FLINT SMITH HEATH TROLL
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported

TACO BELL (Continued) **U003566358**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	472150662002156
Additional ID:	480150662002156
AI Number:	48720
Owner Effective Begin Date:	08/04/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1964
Tank Registration Date:	07/17/1989
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	126680
Facility ID:	83898
Ai Number:	48720
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/27/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

TACO BELL (Continued) **U003566358**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	550
UST Comprt ID:	130086
UST ID:	126680
AI Number:	48720
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

TACO BELL (Continued) **U003566358**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1964
Tank Registration Date:	07/17/1989
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	126681
Facility ID:	83898
Ai Number:	48720
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/27/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

TACO BELL (Continued) **U003566358**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	130087
UST ID:	126681
AI Number:	48720
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FLINT SMITH HEATH TROLL

TACO BELL (Continued) **U003566358**

Contact Mailing Address (Delivery):	515 CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 3504
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83898
Additional ID:	480150662002156
Princ ID:	472150662002156
AI Number:	48720
Facility Name:	TACO BELL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	WESLEY RITCHIE/

ASBESTOS:

Name:	IGLOW SMOKE SHOP
Address:	2801 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/02/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

TACO BELL (Continued) **U003566358**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

HU1007 **DOLLARS AND CENTS** **EDR Hist Cleaner** **1019974283**
West **2268 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX 78759**
0.012 mi.
64 ft. **Site 2 of 4 in cluster HU**

Actual:
583 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1988	DOLLARS AND CENTS	Drycleaning Plants, Except Rugs

AP1008 **KRENEK E J AUTO** **EDR Hist Auto** **1013756777**
WNW **5200 LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
64 ft. **Site 2 of 2 in cluster AP**

Actual:
671 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	KRENEK E J AUTO	AUTOMOBILE REPAIRING
1958	CRIDERS GARAGE	AUTOMOBILE REPAIRING

BZ1009 West < 1/8 0.012 mi. 64 ft. | **HARDIN RICHD G CO**
2200 RIO GRANDE ST
AUSTIN, TX 78705 | **EDR Hist Cleaner** | **1013787451**
N/A

Site 2 of 2 in cluster BZ

Actual: 581 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1980	HARDIN RICHD G CO	LAUNDRIES-SELF SERVE

HZ1010 NW < 1/8 0.012 mi. 64 ft. | **NORTH LAMAR AUTOMOTIVE INC**
8807 A N LAMAR BLVD
AUSTIN, TX 78753 | **RCRA NonGen / NLR**
FINDS
ECHO | **1000406186**
TXD051157949

Site 1 of 2 in cluster HZ

Actual: 663 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	North Lamar Automotive Inc
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD051157949
Contact Name:	BENJAMIN BENNETT
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-837-5300
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	North Lamar Automotive Inc
Owner Type:	Private
Operator Name:	North Lamar Automotive Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

NORTH LAMAR AUTOMOTIVE INC (Continued) **1000406186**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

NORTH LAMAR AUTOMOTIVE INC (Continued) **1000406186**

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NORTH LAMAR AUTOMOTIVE INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 8807 A N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-837-5300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DAVID STUART
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NORTH LAMAR AUTOMOTIVE INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 8807 A N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-837-5300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19890315
Handler Name: NORTH LAMAR AUTOMOTIVE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

NORTH LAMAR AUTOMOTIVE INC (Continued) **1000406186**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: NORTH LAMAR AUTOMOTIVE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005051228

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000406186
Registry ID: 110005051228
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005051228
Name: NORTH LAMAR AUTOMOTIVE INC
Address: 8807 A N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753

X1011 **RELIABLE AUTOMOTIVE** **EDR Hist Auto** **1013764490**
SE **8225 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.012 mi.
65 ft. **Site 3 of 5 in cluster X**

Actual:
734 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1990	RELIABLE AUTOMOTIVE	AUTOMOBILE REPAIRING
1991	RELIABLE AUTOMOTIVE	General Automotive Repair Shops
1994	DYER TRANSMISSION & AUTOMOTIVE	General Automotive Repair Shops
1995	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
1996	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
1997	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
1998	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
1999	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2000	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2001	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2001	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2002	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2002	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2003	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2004	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2005	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2006	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2007	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2007	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2008	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2008	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2009	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2009	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2010	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2010	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2011	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2011	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2012	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2012	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2013	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2013	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2014	DYER AUTO & TRANSMISSIONS	Automotive Repair Shops, NEC
2014	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC

X1012 **RELIABLE AUTOMOTIVE** **TX Ind. Haz Waste** **S102748308**
SE **8225 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.012 mi.
65 ft. **Site 4 of 5 in cluster X**

Actual:
734 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	RELIABLE AUTOMOTIVE
Address:	8225 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61401
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/01/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930

RELIABLE AUTOMOTIVE (Continued) **S102748308**

Land Type:	Not reported
Description of Facility Site Location:	8225 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	RELIABLE AUTOMOTIVE
Contact Name:	HOWARD MOSEBAR
Contact Telephone Number:	Not reported
Mailing Address:	8225 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535918
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19755
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030124
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	RELIABLE AUTOMOTIVE
Operator Address:	8225 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

RELIABLE AUTOMOTIVE (Continued) **S102748308**

Owner Name:	RELIABLE AUTOMOTIVE
Owner Mailing Address:	8225 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8225 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8225 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	HOWARD MOSEBAR
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8225 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100557883
Name:	RELIABLE AUTOMOTIVE
Address:	8225 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5918
Status:	ACTIVE
Status Date:	##########

RELIABLE AUTOMOTIVE (Continued) **S102748308**

Customer Number:	CN600268718
Customer Name:	RELIABLE AUTOMOTIVE
Customer Legal Name:	Reliable Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/1/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8225 N Lamar, Austin, TX

HU1013 **B CO OP PRESSING** **EDR Hist Cleaner** **1013783941**
West **2304 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
65 ft. **Site 3 of 4 in cluster HU**

Actual:
586 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	B CO OP PRESSING	CLOTHES CLEANERS AND PRESSERS

IA1014 **REYES CLNRS** **EDR Hist Cleaner** **1013779272**
NE **312 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.012 mi.
65 ft. **Site 1 of 2 in cluster IA**

Actual:
454 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1953	REYES CLNRS	CLEANERS AND DYERS

FO1015 **WALGREENS** **TX RDR** **S127527627**
NE **2000 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
65 ft. **Site 5 of 10 in cluster FO**

Actual:
472 ft.

Focus Map:
14

RDR:

RDR ID:	21420
Facility ID:	23200
RN:	Not reported
CN:	Not reported
Name:	WALGREENS
Address:	2000 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/14/2014
Due Date:	7/13/2014
Tank Owner:	2020 JOINT VENTURE
Contact Person:	MEL LEVENSON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/11/2014
Project Manager:	Jake Halfhill

WALGREENS (Continued) **S127527627**

Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	101251
Comments:	7/26/13 REL DET; 9/25/13 FAR; DEF LTR 11/4/13; 4/14/14 FAR; ISSUED CLOSURE LTR 7/11/2014
Review Coordinator:	JHH
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FO1016 **UMPHRIES BILL TEXACO** **EDR Hist Auto** **1021540075**
NE **2000 E RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.012 mi.
65 ft. **Site 6 of 10 in cluster FO**

Actual:
472 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1973	UMPHRES BILL TEXACO	Gasoline Service Stations
1974	UMPHRIES BILL TEXACO	Gasoline Service Stations

FO1017 **TEXACO** **TX LPST** **U003566279**
NE **2000 E RIVERSIDE DR** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX HIST UST**
0.012 mi. **TX GCC**
65 ft. **Site 7 of 10 in cluster FO**

Actual:
472 ft.
LPST:

Focus Map:
14

Name:	TEXACO
Address:	2000 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0023200
LPST Id:	101251
Facility Location:	2000 E RIVERSIDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/21/1989
Entered Date:	01/10/1992
Reported Date:	07/21/1989
Closure Date:	07/11/2014
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6P - FINAL PENDING WELL PLUG
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JOAN BECKNER
Responsible Party Address:	4500 FULLER DR STE 400
Responsible Party City,St,Zip:	IRVING, TX 75038

TEXACO (Continued) **U003566279**

Responsible Party Telephone:	214/650-0200
Reported Date:	07/21/1989
Case Start Date:	07/11/2014
Reference Number:	RN102793338
Project Manager:	JHALFHIL

UST:

Name:	TEXACO
Address:	2000 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411325
AI Number:	23200
Facility Type:	RETAIL
Facility Begin Date:	09/24/1986
Facility Status:	INACTIVE
Additional ID:	101654032002207
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	GEORGE TORRES,RETAILER
Contact Organization Name:	TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124415240
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	ROGER EBERT,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600124051
Owner Last Name:	MOTIVA ENTERPRISES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

TEXACO (Continued) **U003566279**

Contact Address Deliverable:	Not reported
Princ ID:	504380502001134
Additional ID:	101654032002207
AI Number:	23200
Owner Effective Begin Date:	09/24/1986
State Tax ID:	17602624904
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59707
Facility ID:	79651
Ai Number:	23200
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

TEXACO (Continued) **U003566279**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	123117
UST ID:	59707
AI Number:	23200
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

TEXACO (Continued) **U003566279**

Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID:	8789
Cert ID:	62875
UST Comprt ID:	177716
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62874
UST Comprt ID:	177717
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62873
UST Comprt ID:	177718
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62872
UST Comprt ID:	177721
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62871
UST Comprt ID:	177720
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62870
UST Comprt ID:	177719
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62876
UST Comprt ID:	177715
UST ID:	61506
AI Number:	23200
Tank ID:	3

TEXACO (Continued) **U003566279**

Compartment ID:	A
Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59708
Facility ID:	79651
Ai Number:	23200
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

TEXACO (Continued) **U003566279**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	123118
UST ID:	59708
AI Number:	23200
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8789
Cert ID:	62875
UST Comprt ID:	177716
UST ID:	61506

TEXACO (Continued) **U003566279**

AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62874
UST Comprt ID:	177717
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62873
UST Comprt ID:	177718
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62872
UST Comprt ID:	177721
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62871
UST Comprt ID:	177720
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62870
UST Comprt ID:	177719
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62876
UST Comprt ID:	177715
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000

TEXACO (Continued) **U003566279**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59709
Facility ID:	79651
Ai Number:	23200
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

TEXACO (Continued) **U003566279**

Installation Signature Date:	06/12/1991
Compartment Records:	
Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	123119
UST ID:	59709
AI Number:	23200
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	8789
Cert ID:	62875
UST Comprt ID:	177716
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62874
UST Comprt ID:	177717

TEXACO (Continued) **U003566279**

UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62873
UST Comprt ID:	177718
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62872
UST Comprt ID:	177721
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62871
UST Comprt ID:	177720
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62870
UST Comprt ID:	177719
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62876
UST Comprt ID:	177715
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59710
Facility ID:	79651
Ai Number:	23200
Tank Id:	2

TEXACO (Continued) **U003566279**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	123120
UST ID:	59710
AI Number:	23200

TEXACO (Continued) **U003566279**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8789
Cert ID:	62875
UST Comprt ID:	177716
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62874
UST Comprt ID:	177717
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62873
UST Comprt ID:	177718

TEXACO (Continued) **U003566279**

UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62872
UST Comprt ID:	177721
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62871
UST Comprt ID:	177720
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62870
UST Comprt ID:	177719
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A
Self Cert ID:	8789
Cert ID:	62876
UST Comprt ID:	177715
UST ID:	61506
AI Number:	23200
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	MOTIVA ENTERPRISES LLC
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79651
Additional ID:	101654032002207
Princ ID:	504380502001134
AI Number:	23200
Facility Name:	TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

TEXACO (Continued) **U003566279**

HIST UST AUSTIN:

Name:	GEORGES TORRES TEXACO #228
Address:	2000 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0090
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GCC:

Name:	TEXACO
Address:	2000 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	101251
Contamination Description:	WASTE OIL
Date Of Earliest Known Contamination Confirmation:	1/10/1992
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

IB1018 **WATKINS PROPERTY** **TX UST** **U001289986**
WNW **3400 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.012 mi.
65 ft. **Site 1 of 6 in cluster IB**

Actual:
596 ft.

Focus Map:
8

UST:

Name:	WATKINS PROPERTY
Address:	3400 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787051322
AI Number:	60728
Facility Type:	RETAIL
Facility Begin Date:	10/21/1991
Facility Status:	INACTIVE
Additional ID:	238518232002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	RUSSELL MOORE,
Contact Organization Name:	WATKINS PROPERTY

WATKINS PROPERTY (Continued) **U001289986**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124761771
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/15/1991
Signature Name/Title On Earliest Reg Form:	DOUG ROMING,ENVIR SPECIALIST
Application Received Date On Earliest Reg Form:	10/15/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777957
Owner Last Name:	WATKINS RAY & SMITH LLOYD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	228518222002053
Additional ID:	238518232002053
AI Number:	60728
Owner Effective Begin Date:	10/21/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142618
Facility ID:	91006
Ai Number:	60728
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED

WATKINS PROPERTY (Continued) **U001289986**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	140307
UST ID:	142618
AI Number:	60728
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

WATKINS PROPERTY (Continued) **U001289986**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142619
Facility ID:	91006
Ai Number:	60728
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

WATKINS PROPERTY (Continued) **U001289986**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	140308
UST ID:	142619
AI Number:	60728
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

WATKINS PROPERTY (Continued) **U001289986**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142620
Facility ID:	91006
Ai Number:	60728
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y

WATKINS PROPERTY (Continued) **U001289986**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	140309
UST ID:	142620
AI Number:	60728
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

WATKINS PROPERTY (Continued) **U001289986**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142621
Facility ID:	91006
Ai Number:	60728
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

WATKINS PROPERTY (Continued) **U001289986**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	140310
UST ID:	142621
AI Number:	60728
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

WATKINS PROPERTY (Continued) **U001289986**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	250
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142622
Facility ID:	91006
Ai Number:	60728
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

WATKINS PROPERTY (Continued) **U001289986**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	250
UST Comprt ID:	140311
UST ID:	142622
AI Number:	60728
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

WATKINS PROPERTY (Continued) **U001289986**

Facility Billing Contacts:

Contact Organization Name:	WATKINS RAY & SMITH LLOYD
Contact Mailing Address (Delivery):	3302 BROADWAY ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77017 2214
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91006
Additional ID:	238518232002053
Princ ID:	228518222002053
AI Number:	60728
Facility Name:	WATKINS PROPERTY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RAY WATKINS/

HIST UST AUSTIN:

Name:	COOPER TIRE STORE
Address:	3400 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0113
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IB1019 **POTTERS SERVICE STA** **EDR Hist Auto** **1013761848**
WNW **3400 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.012 mi.
65 ft. **Site 2 of 6 in cluster IB**

Actual:
596 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	POTTERS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	TAYLORS FRANK SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	WEEDON DON SERV STA	GASOLINE STATIONS
1958	WEEDEN DON SERV	GASOLINE STATIONS
1962	WEEDON DON SERV STA	GASOLINE STATIONS
1965	WEEDONS DON SERVICE	GASOLINE STATIONS
1969	WEEDONS DON INC	Auto And Home Supply Stores
1970	WEEDON DON SER VICE STATION	GASOLINE STATIONS
1970	WEEDONS DON INC	Auto And Home Supply Stores
1971	WEEDONS DON INC	Auto And Home Supply Stores
1972	WEEDONS DON INC	Auto And Home Supply Stores
1973	WEEDONS DON INC	Auto And Home Supply Stores
1974	WEEDONS DON INC	Auto And Home Supply Stores
1975	WEEDON DON SERVICE STATION	GASOLINE STATIONS
1975	WEEDONS DON INC	Auto And Home Supply Stores
1976	WEEDONS DON INC	Auto And Home Supply Stores
1977	WEEDONS DON INC	Household Appliance Stores
1978	WEEDONS DON INC	Household Appliance Stores

POTTERS SERVICE STA (Continued) **1013761848**

1979	WEEDONS DON INC	Household Appliance Stores
1980	WEEDON DON SERVICE STATION	GASOLINE STATIONS
1980	WEEDONS DON INC	Household Appliance Stores
1982	WEEDONS DON INC	Household Appliance Stores

1020 ESE < 1/8 0.012 mi. 65 ft. | **SAMS CLUB PLUS NO 6287**
10601 N LAMAR BLVD
AUSTIN, TX 78753 | **RCRA-VSQG FINDS ECHO** | **1004787753 TXR000020867**

Actual: 732 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	19970402
Handler Name:	Sams Club Plus No 6287
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXR000020867
Contact Name:	JOSEPH SIKES
Contact Address:	DEPT 8013
Contact City,State,Zip:	BENTONVILLE, AR 72716-8013
Contact Telephone:	512-719-3833
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	DEPT 8013
Mailing City,State,Zip:	BENTONVILLE, AR 72716-8013
Owner Name:	Sams East Ins
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

SAMS CLUB PLUS NO 6287 (Continued) **1004787753**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SAMS EAST INS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	DEPT 8013
Owner/Operator City,State,Zip:	BENTONVILLE, AR 72716-8013
Owner/Operator Telephone:	479-273-8715
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19970402
Handler Name: SAMS CLUB PLUS NO 6287	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

SAMS CLUB PLUS NO 6287 (Continued) **1004787753**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005177227

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004787753
Registry ID: 110005177227
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005177227
Name: SAMS CLUB PLUS NO 6287
Address: 10601 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753

HL1021 **RAINBO BAKING** **TX UST** **U001239085**
WNW **6534 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.012 mi.
65 ft. **Site 7 of 8 in cluster HL**

Actual:
657 ft.

Focus Map:
17

UST:
Name: RAINBO BAKING
Address: 6534 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 787454462
AI Number: 1994
Facility Type: UNKNOWN
Facility Begin Date: 06/06/1986
Facility Status: INACTIVE
Additional ID: 34362792002075
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0

RAINBO BAKING (Continued) **U001239085**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	RAINBO BAKING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124443359
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/24/1986
Signature Name/Title On Earliest Reg Form:	RICHARD JONES,FLEET SUPT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602493033
Owner Last Name:	SARA LEE BAKERY GROUP INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	769427712003309
Additional ID:	34362792002075
AI Number:	1994
Owner Effective Begin Date:	06/06/1986
State Tax ID:	13632010453
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	4896

RAINBO BAKING (Continued) **U001239085**

Facility ID:	74830
Ai Number:	1994
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/03/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000

RAINBO BAKING (Continued) **U001239085**

UST Comprt ID:	107796
UST ID:	4896
AI Number:	1994
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE EARTHGRAINS COMPANY
Contact Mailing Address (Delivery):	6534 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 4462
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74830
Additional ID:	34362792002075
Princ ID:	769427712003309
AI Number:	1994
Facility Name:	RAINBO BAKING
AR Number:	Not reported
AR UST Number Suffix:	Not reported

RAINBO BAKING (Continued) **U001239085**

AR AST Number Suffix: Not reported
Contact Name/Title: /

HIST UST AUSTIN:
Name: RAINBO BAKING
Address: 6534 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: C0205
HID UST: Not reported
Inspection: Not reported
Due: Not reported

HL1022 **GENOA TRANSMISSIONS INC** **EDR Hist Auto** **1021993444**
WNW **6534 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.012 mi.
65 ft. **Site 8 of 8 in cluster HL**

Actual:
657 ft.

Focus Map:
17

EDR Hist Auto

Year:	Name:	Type:
2006	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2007	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2008	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2009	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2010	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2011	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2012	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2013	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2014	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops

---

FT1023 **CVS PHARMACY 6844** **RCRA NonGen / NLR** **1015751237**
ESE **2301 2301 S CONGRESS AVE** **FINDS** **TXR000080991**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.012 mi.
65 ft. **Site 11 of 15 in cluster FT**

Actual:
596 ft.

Focus Map:
14

RCRA Listings:
Date Form Received by Agency: 20220328
Handler Name: Cvs Pharmacy 6844
Handler Address: 2301 S CONGRESS AVE
Handler City,State,Zip: AUSTIN, TX 78704-5253
EPA ID: TXR000080991
Contact Name: WENDY BRANT
Contact Address: 1 CVS DR
Contact City,State,Zip: WOONSOCKET, RI 02895-6146
Contact Telephone: 401-765-1500
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 06
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported

CVS PHARMACY 6844 (Continued) **1015751237**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1 CVS DR
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cvs Pharmacy Inc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220603
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

CVS PHARMACY 6844 (Continued) **1015751237**

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	P001
Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P012
Waste Description:	Arsenic Oxide As2o3 (Or) Arsenic Trioxide
Waste Code:	P075
Waste Description:	Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts
Waste Code:	P081
Waste Description:	1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported

CVS PHARMACY 6844 (Continued) **1015751237**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR

CVS PHARMACY 6844 (Continued) **1015751237**

Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private

CVS PHARMACY 6844 (Continued) **1015751237**

Date Became Current:	20120716
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY 6844 (Continued) **1015751237**

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported

CVS PHARMACY 6844 (Continued) **1015751237**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120716
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160301
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20180301
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported

CVS PHARMACY 6844 (Continued) **1015751237**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20120716
Handler Name:	CVS PHARMACY INC - STORE 6844
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130226
Handler Name:	CVS PHARMACY 6844
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130513
Handler Name:	CVS PHARMACY 6844
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150223
Handler Name:	CVS PHARMACY 6844
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CVS PHARMACY 6844 (Continued) **1015751237**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150223
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170206
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180223
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190211
Handler Name: CVS PHARMACY 6844	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190319

CVS PHARMACY 6844 (Continued) **1015751237**

Handler Name: CVS PHARMACY 6844
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220328
Handler Name: CVS PHARMACY 6844
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 812922
NAICS Description: ONE-HOUR PHOTOFINISHING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070738337

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110054865810

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CVS PHARMACY 6844 (Continued) **1015751237**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1015751237
Registry ID:	110054865810
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110054865810
Name:	CVS PHARMACY 6844
Address:	2301 2301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

FT1024 **CVS PHARMACY** **TX ASBESTOS** **S112202590**
ESE **2301 S CONGRESS AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.012 mi.
65 ft. **Site 12 of 15 in cluster FT**

Actual:
596 ft.

Focus Map:
14

ASBESTOS:

Name:	HEB SHOPPING CENTER
Address:	2301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

CVS PHARMACY (Continued) **S112202590**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/28/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	51148
License Status Description:	Current
Expiration Date:	03/11/2025
Original Date:	03/12/2020
Rank Effective Date:	03/12/2020
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20823
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	CVS PHARMACY
Address:	2301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013

CVS PHARMACY (Continued) **S112202590**

Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	2301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported

CVS PHARMACY (Continued) **S112202590**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

CVS PHARMACY (Continued) **S112202590**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 6844
Address:	2301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	91365
Registration Initial Notification Date:	04/20/2012
Registration Last Amendment Date:	03/28/2022
EPA Identification:	TXR000080991
Primary NAICS Code:	446110
Status Change Date:	20130726
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130332
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220525
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

CVS PHARMACY (Continued) **S112202590**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	ATTN WENDY BRANT
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA
Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	ATTN WENDY BRANT
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500
Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the back storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150223
Deed Record Needed:	Not reported

CVS PHARMACY (Continued) **S112202590**

Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150223
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	ATTN WENDY BRANT
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM
Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	350733
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008101H
Waste Code Status:	INACTIVE
Waste Form:	101

CVS PHARMACY (Continued) **S112202590**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (SILVER, AMMONIUM THIOSULFATE) 9 PGIII
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOTO FIXER DEVELOPE
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350728
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE GAS
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350724
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

CVS PHARMACY (Continued) **S112202590**

Generators Waste Description:	UN1950 Aerosols, [flammable, (each not exceeding 1 L capacity)] 2.1, PG , ERG-1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350725
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1760 Corrosive liquids, n.o.s. (Sodium Hydroxide, Potassium Carbonate) 8, PG
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC LIQUID CORROS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350727
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported

CVS PHARMACY (Continued) **S112202590**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350731
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3139 Oxidizing liquid, n.o.s. (Hydrogen Peroxide) 5.1, PG II, ERG-140
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUID
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	337444
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077114H
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT PHOTO PROCESSING SOLUTIONS CONTAINING SILVER FROM PHOTO LAB PROCESSING
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported

CVS PHARMACY (Continued) **S112202590**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350732
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350723
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

CVS PHARMACY (Continued) **S112202590**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350726
Texas Waste Code:	Not reported
Texas Waste Code 2:	0211009H
Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3077 Environmentally hazardous substances, solid, n.o.s. (Mercury, Silver) 9,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN LAMPS PHOTO
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	369874
Texas Waste Code:	Not reported
Texas Waste Code 2:	0217001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic, liquids, organic, n.o.s.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

CVS PHARMACY (Continued) **S112202590**

Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389212
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	379849
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001

CVS PHARMACY (Continued) **S112202590**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316673
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316673
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316673
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316673
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWG

1025 West < 1/8 0.012 mi. 65 ft. | **TEXAS CLEANERS 2236 GUADALUPE AUSTIN, TX** | **EDR Hist Cleaner** | **1013783700 N/A**

Actual: 581 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	T PRESSING SHOP	CLOTHES CLEANERS AND PRESSERS
1935	TEXAS CLEANERS	CLOTHES PRESSERS AND CLEANERS
1940	TEXAS CLEANERS	CLOTHES PRESSERS AND CLEANERS

FR1026 SW < 1/8 0.012 mi. 65 ft. | **TOWNLAKE CLEANERS 2017 RIVERSIDE DR E TRAVIS (County), TX 78741** | **EDR Hist Cleaner** | **1013786839 N/A**

Site 3 of 3 in cluster FR

Actual: 479 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1975	TOWNLAKE CLEANERS	CLEANERS AND DYERS
1984	DISCOUNT CLEANERS	CLEANERS AND DYERS

Z1027 WNW < 1/8 0.012 mi. 65 ft. | **BOYEA ASSOCIATES INC 7530 N LAMAR AUSTIN, TX 78752** | **EDR Hist Auto** | **1020318686 N/A**

Site 5 of 9 in cluster Z

Actual: 751 ft. EDR Hist Auto

Focus Map: 6

Year:	Name:	Type:
1969	BOYEA ASSOCIATES INC	Gasoline Service Stations
1970	BOYEA ASSOCIATES INC	Gasoline Service Stations

FL1028 WSW < 1/8 0.013 mi. 66 ft. | **RIVER HILLS SHOPPING CENTER BROWN JACK CLEANERS 1901 RIVERSIDE DR TRAVIS (County), TX 78741** | **EDR Hist Cleaner** | **1013784486 N/A**

Site 5 of 8 in cluster FL

Actual: 479 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1980	RIVER HILLS SHOPPING CENTER ACM	CLEANERS AND DYERS
1984	RIVER HILLS SHOPPING CENTER BRO	CLEANERS AND DYERS
1990	RIVER HILLS SHOPPING CENTER BRO	CLEANERS AND DYERS

X1029 SE < 1/8 0.013 mi. 66 ft. | **UNCLE BOB'S STORAGE 8227 N. LAMAR BLVD. AUSTIN, TX 78753** | **TX HIST UST TX ASBESTOS** | **S111678811 N/A**

Site 5 of 5 in cluster X

Actual: 732 ft.

Focus Map: 6

HIST UST AUSTIN:

Name:	STARK ROOFING CO
Address:	8227 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0682
HID UST:	682
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	UNCLE BOB'S STORAGE
Address:	8227 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	12/17/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013009109
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	01/08/2014
Date Routed by Supervisor:	01/27/2014
Date Routed to PSQA:	01/30/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported

UNCLE BOB'S STORAGE (Continued) **S111678811**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BM1030 **TEXAS PACIFIC COAL OIL CO FILLING** **EDR Hist Auto** **1013764832**
WSW **2714 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft. **Site 3 of 6 in cluster BM**

Actual:
601 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	TEXAS PACIFIC COAL OIL CO FILLI	GASOLINE AND OIL SERVICE STATIONS

EO1031 **TOWNE PARK LTD** **EDR Hist Cleaner** **1018542666**
ESE **611 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.013 mi.
66 ft. **Site 2 of 2 in cluster EO**

Actual:
461 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
2011	TOWNE PARK LTD	Garment Pressing And Cleaners' Agents

AN1032 **TUNE SMITHS** **TX Ind. Haz Waste** **S102748664**
ESE **5405 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.013 mi.
66 ft. **Site 5 of 6 in cluster AN**

Actual:
680 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	TUNE SMITHS
Address:	5405 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	61814
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	5405 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TUNE SMITHS
Contact Name:	H SAMUEL
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 33322
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787640322
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20154
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

TUNE SMITHS (Continued) **S102748664**

Ind. Haz Waste:

Operator Name:	TUNE SMITHS
Operator Address:	PO BOX 33322
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78764
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17418419713
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TUNE SMITHS
Owner Mailing Address:	PO BOX 33322
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78764
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17418419713
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 33322
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 33322
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	H SAMUEL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 33322
Contact Address 2:	Not reported

TUNE SMITHS (Continued) **S102748664**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100648724
Name:	TUNE SMITHS
Address:	5405 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1824
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600358600
Customer Name:	TUNE SMITHS
Customer Legal Name:	Tune Smiths, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5405 N LAMAR BLVD, AUSTIN, TX

AN1033 **WAYNE BARBEE MUFFLERS** **EDR Hist Auto** **1013764864**
ESE **5405 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.013 mi.
66 ft. **Site 6 of 6 in cluster AN**

Actual:
680 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1976	TUNE SMITHS INC	General Automotive Repair Shops
1977	TUNE SMITHS INC	General Automotive Repair Shops
1978	TUNE SMITHS INC	General Automotive Repair Shops
1980	TUNE SMITHS INC AUTO REPR	AUTOMOBILE REPAIRING
1980	TUNE SMITHS INC	General Automotive Repair Shops
1982	TUNE SMITHS INC	General Automotive Repair Shops
1983	TUNE SMITHS INC	General Automotive Repair Shops
1984	TUNE SMITHS INC AUTO REPR	AUTOMOBILE REPAIRING
1988	AUTO & MUFFLER SERVICING	Automotive Repair Shops, NEC
1988	AMERICAN MUFFLER	Automotive Repair Shops, NEC
1989	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
1989	AUTO & MUFFLER SERVICING	Automotive Repair Shops, NEC
1990	WAYNE BARBEE MUFFLERS	AUTOMOBILE REPAIRING
1990	AUTO & MUFFLER SERVICING	Automotive Repair Shops, NEC
1993	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
1994	AUTO & MUFFLER SERVICING	Automotive Repair Shops, NEC
1994	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
1995	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
1996	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
1997	WAYNE BARBEE MUFFLERS AN	General Automotive Repair Shops
2007	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2008	GROOVY AUTOMOTIVE	General Automotive Repair Shops

WAYNE BARBEE MUFFLERS (Continued) **1013764864**

2009	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2010	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2011	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2011	AFFORDABLE TRANSMISSIONS	Automotive Transmission Repair Shops
2012	AFFORDABLE TRANSMISSIONS	Automotive Transmission Repair Shops
2012	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2013	AFFORDABLE TRANSMISSIONS	Automotive Transmission Repair Shops
2013	GROOVY AUTOMOTIVE	General Automotive Repair Shops
2014	AFFORDABLE TRANSMISSIONS	Automotive Transmission Repair Shops
2014	GROOVY AUTOMOTIVE	General Automotive Repair Shops

1034 **LOOMIS ARMORED INC** **TX HIST UST** **S128728959**
ESE **78 N I 35** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft.

Actual:
465 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	LOOMIS ARMORED INC
Address:	78 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0223
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

BN1035 **LOCKHART LNDRY** **EDR Hist Cleaner** **1013778075**
West **2612 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft. **Site 3 of 4 in cluster BN**

Actual:
608 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1953	LOCKHART LNDRY	LAUNDRIES
1958	LOCKHART LNDRY	LAUNDRIES

BM1036 **BRANUM CLEANERS** **EDR Hist Cleaner** **1013779717**
WSW **2716 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft. **Site 4 of 6 in cluster BM**

Actual:
601 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1916	SPILLAR BLISS R CLNR	CLOTHES CLEANERS AND PRESSERS
1953	BRANUM CLEANERS	CLEANERS AND DYERS

DM1037 **PREMIUM PARKING PUBLIC LOT** **TX TANKS** **S126967615**
NNE **415 E 7TH ST** **TX COMP HIST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX CENTRAL REGISTRY**
0.013 mi.
66 ft. **Site 5 of 22 in cluster DM**

Actual:
491 ft.

Focus Map:
11

TANKS:

Facility ID:	136260
Name:	PREMIUM PARKING PUBLIC LOT
Address:	415 E 7TH ST
City,State,Zip:	AUSTIN, TX 787013316
Total UST:	Not reported
Additional ID:	269530182020077
AI Number:	91155
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

COMP HIST:

RN Number:	RN111011607
Name:	PREMIUM PARKING PUBLIC LOT
Address:	Not reported
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605765759
CN Name:	JP AUSTIN II LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED

PREMIUM PARKING PUBLIC LOT (Continued) **S126967615**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236220
SIC Code:	1522
Related Number:	91155,91155

CENTRAL REGISTRY:

Regulated Entity Number:	RN111011607
Name:	PREMIUM PARKING PUBLIC LOT
Address:	415 E 7TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3316
Status:	ACTIVE
Status Date:	3/17/2020
Customer Number:	CN605765759
Customer Name:	JP AUSTIN II LLC
Customer Legal Name:	JP Austin II, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/11/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

DM1038 **HENRY KNEMPEL** **TX HIST UST** **S128729297**
NNE **415 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft. **Site 6 of 22 in cluster DM**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	HENRY KNEMPEL
Address:	415 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0499
HID UST:	499
Inspection:	Not reported
Due:	06/01/2012

DM1039 **ALLRIGHT PARKING** **TX HIST UST** **S128729559**
NNE **415 E. 7TH ST.** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
66 ft. **Site 7 of 22 in cluster DM**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ALLRIGHT PARKING
Address:	415 E. 7TH ST.
City,State,Zip:	AUSTIN, TX
Id UST:	N0168
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DM1040 NNE < 1/8 0.013 mi. 66 ft. | **PREMIUM PARKING PUBLIC LOT**
415 E 7TH STREET
AUSTIN, TX
Site 8 of 22 in cluster DM | **TX RDR** | **S127541328**
N/A

Actual: 491 ft.
Focus Map: 11

RDR:

RDR ID:	28610
Facility ID:	91155
RN:	Not reported
CN:	Not reported
Name:	PREMIUM PARKING PUBLIC LOT
Address:	415 E 7TH STREET
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/15/2020
Due Date:	7/14/2020
Tank Owner:	JP AUSTIN II LLC
Contact Person:	DANIEL WEISSMAN
Report:	TANK REMOVAL
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/17/2020
Project Manager:	Olusola Ayilara
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

1041 NNE < 1/8 0.013 mi. 66 ft. | **AUSTIN COMMUNITY COLLEGE**
5712 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX UST** | **U001240873**
N/A

Actual: 513 ft.
Focus Map: 15

UST:

Name:	AUSTIN COMMUNITY COLLEGE
Address:	5712 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787414801
AI Number:	4105
Facility Type:	Not reported
Facility Begin Date:	06/18/1986
Facility Status:	INACTIVE
Additional ID:	99496822002054
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	J ADAMS,ASST DIRECTOR

AUSTIN COMMUNITY COLLEGE (Continued) **U001240873**

Contact Organization Name:	AUSTIN COMMUNITY COLLEGE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124957520
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/17/1986
Signature Name/Title On Earliest Reg Form:	J BRODIR,VP
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600269211
Owner Last Name:	AUSTIN COMMUNITY COLLEGE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	7309722001297
Additional ID:	99496822002054
AI Number:	4105
Owner Effective Begin Date:	06/18/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	9990
Facility ID:	42803
Ai Number:	4105
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/26/1989
Empty:	N

AUSTIN COMMUNITY COLLEGE (Continued) **U001240873**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	13722
UST ID:	9990
AI Number:	4105
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **U001240873**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUSTIN COMMUNITY COLLEGE
Contact Mailing Address (Delivery):	5930 MIDDLE FISKVILLE RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 4341
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	42803
Additional ID:	99496822002054
Princ ID:	7309722001297
AI Number:	4105
Facility Name:	AUSTIN COMMUNITY COLLEGE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ROBERT N PERRY/

CA1042 **CVS PHARMACY** **TX ASBESTOS** **S112202436**
West **2222 GUADALUPE ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.013 mi.
66 ft. **Site 3 of 5 in cluster CA**

Actual:
580 ft.

Focus Map:
11

ASBESTOS:

Name:	CVS PHARMACY
Address:	2222 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/30/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/06/2013
Date Routed by Supervisor:	05/06/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

CVS PHARMACY (Continued) **S112202436**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	2222 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/15/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/18/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

CVS PHARMACY (Continued) **S112202436**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	2222 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/10/2015
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported

CVS PHARMACY (Continued) **S112202436**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 7606
Address:	2222 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	91211
Registration Initial Notification Date:	04/20/2012
Registration Last Amendment Date:	03/22/2022
EPA Identification:	TXR000080776
Primary NAICS Code:	812922
Status Change Date:	20130724
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported

CVS PHARMACY (Continued) **S112202436**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130178
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220718
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	ATTN WENDY BRANT
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA
Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

CVS PHARMACY (Continued) **S112202436**

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	ATTN WENDY BRANT
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500
Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the back storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20170213
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

CVS PHARMACY (Continued) **S112202436**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20170213
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	ATTN WENDY BRANT
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	360475
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (SILVER, AMMONIUM THIOSULFATE) 9 PGIII
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOTO FIXER DEVELOPE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

CVS PHARMACY (Continued) **S112202436**

Ind. Haz Waste:

Waste ID:	360476
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1760 WASTE CORROSIVE LIQUIDS, N.O.S. (SULFURIC ACID, POTASSIUM HYDROXIDE) 8 PG
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOTO CHEMICAL KITS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389520
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE AEROSOLS A
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

CVS PHARMACY (Continued) **S112202436**

Waste ID:	351720
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1950 Aerosols, [flammable, (each not exceeding 1 L capacity)] 2.1, PG , ERG-1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	360474
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive liquids, Basic, n.o.s.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC LIQUID
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	351722
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE

CVS PHARMACY (Continued) **S112202436**

Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	337040
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077114H
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT PHOTO PROCESSING SOLUTIONS CONTAINING SILVER FROM PHOTO LAB PROCESSING
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	351723
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H

CVS PHARMACY (Continued) **S112202436**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2811 Toxic solids, organic, n.o.s. (Pyrethoids, Selenium) 6.1, PG II, ERG-154
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	360472
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	351721
Texas Waste Code:	Not reported
Texas Waste Code 2:	0211009H
Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

CVS PHARMACY (Continued) **S112202436**

Generators Waste Description:	UN3077 Environmentally hazardous substances, solid, n.o.s. (Mercury, Silver) 9,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN LAMPS PHOTO
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389525
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389521
Texas Waste Code:	Not reported
Texas Waste Code 2:	0224002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Environmentally hazardous substances, solid, n.o.s., Mercury
Standard Industrial Code:	Not reported

CVS PHARMACY (Continued) **S112202436**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN FLUORESCENT L
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389524
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316519
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0

CVS PHARMACY (Continued) **S112202436**

Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316519
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316519
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316519
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWG

HO1043 **SHOP N CARRY FOODS** **TX LPST** **S125401024**
WNW **8422 S CONGRESS AVE** **TX RDR** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
67 ft. **Site 8 of 9 in cluster HO**

Actual:
690 ft.

Focus Map:
21

LPST:

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120751
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	04/26/2019
Entered Date:	07/11/2019
Reported Date:	04/27/2019
Closure Date:	12/31/3000
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	2 - SITE ASSESSMENT
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported

SHOP N CARRY FOODS (Continued) **S125401024**

Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	04/27/2019
Case Start Date:	12/31/3000
Reference Number:	RN101493062
Project Manager:	THAMMITT

RDR:

RDR ID:	26976
Facility ID:	10996
RN:	Not reported
CN:	Not reported
Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/15/2019
Due Date:	7/14/2019
Tank Owner:	USMAN TRADING INC
Contact Person:	MUHAMMED NAVEED USMAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	7/12/2019
Project Manager:	Riley Monk
Team:	#N/A
New LPST Number:	120751
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

HO1044 **SHOP N CARRY FOODS** **TX UST** **U001246990**
WNW **8422 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX Financial Assurance**
0.013 mi. **TX GCC**
67 ft. **Site 9 of 9 in cluster HO**

Actual:
690 ft.

Focus Map:
21

UST:

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787457310
AI Number:	10996
Facility Type:	RETAIL
Facility Begin Date:	07/25/1986
Facility Status:	INACTIVE
Additional ID:	16623652002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

SHOP N CARRY FOODS (Continued) **U001246990**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	NAVEED USMAN,MGR
Contact Organization Name:	SHOP N CARRY FOODS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122802539
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/2019
Signature Name/Title On Earliest Reg Form:	MOHAMMAD USMAN,PRES
Application Received Date On Earliest Reg Form:	05/13/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	857522802003309
Additional ID:	16623652002053
Ai Number:	10996
Operator CN:	CN602493322
Operator Name:	USMAN TRADING INC
Operator Effective Begin Date:	01/01/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	NAVEED M USMAN/PRESIDENT
Contact Organization Name:	USMAN TRADING INC
Contact Mailing Address (Delivery):	4509 E MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78721-1356
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	2802539
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602493322
Owner Last Name:	USMAN TRADING INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	4509 E MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX

SHOP N CARRY FOODS (Continued) **U001246990**

Contact Mailing Zip:	78721
Contact Mailing Zip5:	1356
Contact Phone Number/Ext:	1 512 2802539/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	857522802003309
Additional ID:	16623652002053
AI Number:	10996
Owner Effective Begin Date:	01/01/2012
State Tax ID:	17429847761
Contact Role:	OWNOPRCON
Contact Name/Title:	NAVEED M USMAN/PRESIDENT
Contact Organization Name:	USMAN TRADING INC

Self Certification:

Self Cert ID:	43997
Cert ID:	272708
AI Number:	10996
Self Certification Date:	07/20/2016
Signature Name/Title:	NAVEED USMAN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43997
Cert ID:	253912
AI Number:	10996
Self Certification Date:	05/29/2015
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43997
Cert ID:	240802

SHOP N CARRY FOODS (Continued) **U001246990**

AI Number:	10996
Self Certification Date:	08/29/2014
Signature Name/Title:	NAVEED USMAN PRE
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43997
Cert ID:	221659
AI Number:	10996
Self Certification Date:	06/24/2013
Signature Name/Title:	NAUEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43997
Cert ID:	19008
AI Number:	10996
Self Certification Date:	05/27/2012
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19007

SHOP N CARRY FOODS (Continued) **U001246990**

AI Number:	10996
Self Certification Date:	07/07/2011
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19006
AI Number:	10996
Self Certification Date:	06/29/2010
Signature Name/Title:	MUHAMMAD N USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19005
AI Number:	10996
Self Certification Date:	06/10/2009
Signature Name/Title:	MUHAMMAD NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19004

SHOP N CARRY FOODS (Continued) **U001246990**

AI Number:	10996
Self Certification Date:	07/01/2008
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19003
AI Number:	10996
Self Certification Date:	06/12/2007
Signature Name/Title:	MUHAMMAD NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19002
AI Number:	10996
Self Certification Date:	06/25/2006
Signature Name/Title:	NAVEED USMAN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19001

SHOP N CARRY FOODS (Continued) **U001246990**

AI Number:	10996
Self Certification Date:	05/19/2005
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	19000
AI Number:	10996
Self Certification Date:	06/18/2004
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	18999
AI Number:	10996
Self Certification Date:	09/23/2003
Signature Name/Title:	NAVEED USMAN PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	18998

SHOP N CARRY FOODS (Continued) **U001246990**

AI Number:	10996
Self Certification Date:	07/15/2003
Signature Name/Title:	KARIM M ALI PRES/SEC
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	18997
AI Number:	10996
Self Certification Date:	07/10/2002
Signature Name/Title:	KARIM M ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43997
Cert ID:	18996
AI Number:	10996
Self Certification Date:	01/10/2001
Signature Name/Title:	KARIM M ALI PRES/SEC
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1976

SHOP N CARRY FOODS (Continued) **U001246990**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28919
Facility ID:	43997
Ai Number:	10996
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/07/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

SHOP N CARRY FOODS (Continued) **U001246990**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	8000
UST Comprt ID:	17403
UST ID:	28919
AI Number:	10996
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/07/1996
Tank Registration Date:	02/11/1997
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	182640
Facility ID:	43997

SHOP N CARRY FOODS (Continued) **U001246990**

Ai Number:	10996
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/11/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	01/09/1997

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	17405

SHOP N CARRY FOODS (Continued) **U001246990**

UST ID:	182640
AI Number:	10996
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1999

Install Date:	12/07/1996
Tank Registration Date:	03/17/1997
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	183590
Facility ID:	43997
Ai Number:	10996
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/11/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

SHOP N CARRY FOODS (Continued) **U001246990**

Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	03/17/1997

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	17406
UST ID:	183590
AI Number:	10996
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y

SHOP N CARRY FOODS (Continued) **U001246990**

CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1999

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28920
Facility ID:	43997
Ai Number:	10996
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/07/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

SHOP N CARRY FOODS (Continued) **U001246990**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	8000
UST Comprt ID:	17404
UST ID:	28920
AI Number:	10996
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

SHOP N CARRY FOODS (Continued) **U001246990**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	34347
Facility ID:	43997
AI Number:	10996
Application Received Date:	03/13/2019
Scheduled Construction Date:	04/15/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	USMAN TRADING INC
Owner CN At Time Of Construction:	CN602493322
Owner AR At Time Of Construction:	61667
General Desc Of Prop Construct:	REMOVAL OF 2-8K DW FRP UST'S, DISPENSERS, AND LINES.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	81459

SHOP N CARRY FOODS (Continued) **U001246990**

UST ID:	Not reported
NOC ID:	34347
AI Number:	10996
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	RANGER ENVIRONMENTAL SERVICES INC
Representative Name:	DAN AIREY
Mailing Address (Delivery):	PO BOX 201179
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78720
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3350527
Email Address:	Not reported

Cont/Cons/Installer ID:	26175
UST ID:	182640
NOC ID:	Not reported
AI Number:	10996
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000139
Company Name:	UNITED PUMP SUPPLY INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	81461
UST ID:	Not reported
NOC ID:	34347
AI Number:	10996
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK AND PUMP SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 170398
Mailing Address (Internal Delivery):	Not reported

SHOP N CARRY FOODS (Continued) **U001246990**

Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3105611
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3105610
Email Address:	Not reported
Cont/Cons/Installer ID:	26176
UST ID:	183590
NOC ID:	Not reported
AI Number:	10996
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000139
Company Name:	UNITED PUMP SUPPLY INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	81460
UST ID:	Not reported
NOC ID:	34347
AI Number:	10996
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3105611
Phone Number Extension:	0

SHOP N CARRY FOODS (Continued) **U001246990**

Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3105610
Email Address:	Not reported

Cont/Cons/Installer ID:	41341
UST ID:	182640
NOC ID:	Not reported
AI Number:	10996
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001896
Company Name:	Not reported
Representative Name:	RITCHIE ROGERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	41342
UST ID:	183590
NOC ID:	Not reported
AI Number:	10996
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001896
Company Name:	Not reported
Representative Name:	RITCHIE ROGERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	USMAN TRADING INC
Contact Mailing Address (Delivery):	4509 E MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported

SHOP N CARRY FOODS (Continued) **U001246990**

Contact Mailing City/State/Zip:	AUSTIN, TX 78721 1356
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	43997
Additional ID:	16623652002053
Princ ID:	857522802003309
AI Number:	10996
Facility Name:	SHOP N CARRY FOODS
AR Number:	61667
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	NAVEED M USMAN/

HIST UST AUSTIN:

Name:	SHOP N CARRY FOOD #1
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	639
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	165165
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/16/2015
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-106389
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/16/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997

SHOP N CARRY FOODS (Continued) **U001246990**

Finass ID:	144976
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/16/2015
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 503 9773333
Policy Number:	STP-106389
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/16/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	132149
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/16/2013
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	1 503 9773333
Policy Number:	179E05828-13-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/16/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	110739
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SHOP N CARRY FOODS (Continued) **U001246990**

Financial Assurance Begin Date:	02/16/2013
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	503 977 3333
Policy Number:	179E05828-13-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/16/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	1066
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/16/2012
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP364120001
Coverage Amount:	1000000
Coverage Expiration Date:	02/16/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	24380
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/16/2011
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641200
Coverage Amount:	1000000
Coverage Expiration Date:	02/16/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

SHOP N CARRY FOODS (Continued) **U001246990**

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	24381
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/28/2010
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 917910300
Coverage Amount:	1000000
Coverage Expiration Date:	01/28/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	24382
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/13/2008
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 281 7528000
Policy Number:	USC 5337976 05
Coverage Amount:	1000000
Coverage Expiration Date:	11/13/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	24383
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SHOP N CARRY FOODS (Continued) **U001246990**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/13/2007
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 281 7528000
Policy Number:	USC 5337976 04
Coverage Amount:	1000000
Coverage Expiration Date:	11/13/2008
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43997
Finass ID:	24384
AI:	10996
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/13/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	SHOP N CARRY FOODS
Address:	8422 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	120751
Contamination Description:	OTHER
Date Of Earliest Known Contamination Confirmation:	4/27/2019
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	2A - Investigation
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	Not reported
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported

SHOP N CARRY FOODS (Continued) **U001246990**

Data Quality 2: Not reported

Name: SHOP N CARRY FOODS
Address: 8422 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 120751
Contamination Description: OTHER
Date Of Earliest Known Contamination Confirmation: 4/27/2019
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A - Investigation
Data Quality 1: E,Q
Section 5236: Not reported
Type: Not reported
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

1045 ENE < 1/8 0.013 mi. 67 ft. | **ADAMS HENRY J 1900 SPEEDWAY AUSTIN, TX** | **EDR Hist Auto** | **1013774242 N/A**

Actual: 534 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	MAGNOLIA PET CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1935	MAE PET CC STA NO	GASOLINE AND OIL SERVICE STATIONS
1940	WELLS SHERMAN T FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1947	WELLS S T SERV STATION	GASOLINE AND OIL SERVICE STATIONS
1953	WELLS S T SERV FILL	GASOLINE STATIONS
1958	ADAMS HENRY J	GASOLINE STATIONS
1965	JOHNSON LAMBERT MOBIL	GASOLINE STATIONS

CA1046 West < 1/8 0.013 mi. 67 ft. | **JONES JOHN H CLOTHES 2214 GUADALUPE ST AUSTIN, TX** | **EDR Hist Cleaner** | **1013787346 N/A**

Site 4 of 5 in cluster CA

Actual: 579 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	JONES JOHN H CLOTHES	CLOTHES PRESSERS AND CLEANERS
1916	SMITH RUFUS H CLNR	CLOTHES CLEANERS AND PRESSERS

BX1047
East
< 1/8
0.013 mi.
67 ft.

RIO GRANDE GAS
701 W 24TH
AUSTIN, TX 78705

Site 4 of 4 in cluster BX

EDR Hist Auto **1013761804**
N/A

Actual:
596 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	UNIVERSITY CONOCO SERVICE	GASOLINE STATIONS
1974	RIO GRANDE GAS	Gasoline Service Stations
1975	RIO GRANDE GAS	Gasoline Service Stations
1976	RIO GRANDE GAS	Gasoline Service Stations
1977	RIO GRANDE GAS	Gasoline Service Stations
1978	RIO GRANDE GAS	Gasoline Service Stations
1979	RIO GRANDE GAS	Gasoline Service Stations
1980	RIO GRANDE GAS	Gasoline Service Stations
1982	RIO GRANDE GAS	Gasoline Service Stations
1983	RIO GRANDE GAS	Gasoline Service Stations
1985	RIO GRANDE GAS	Gasoline Service Stations
1986	RIO GRANDE GAS	Gasoline Service Stations
1987	RIO GRANDE GAS	Gasoline Service Stations

1048
WNW
< 1/8
0.013 mi.
67 ft.

SCOTTVS AUTOMOTIVE SERVICE REPR
5922 LAMAR BLVD N
TRAVIS (County), TX 78752

EDR Hist Auto **1013773428**
N/A

Actual:
707 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1970	SCOTTVS AUTOMOTIVE SERVICE REPR	AUTOMOBILE REPAIRING
1971	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1972	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1973	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1974	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1975	SCOTTYS AUTOMOTIVE SERVICE REPR	AUTOMOBILE REPAIRING
1976	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1977	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1978	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1979	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1980	SCOTTYS AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1980	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1982	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1983	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1984	SCOTTYS AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1985	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1986	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1987	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1988	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1989	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1990	SCOTTYS AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1990	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1991	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1992	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1993	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1994	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1995	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1996	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops

SCOTTVS AUTOMOTIVE SERVICE REPR (Continued) **1013773428**

1997	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1998	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1999	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2000	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2001	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2002	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2003	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2004	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2005	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2006	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2007	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2008	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2009	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2010	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2011	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2012	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2013	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2014	SCOTTYS AUTOMOTIVE SERVICE	General Automotive Repair Shops

---

J1049 **QUALITY BODY SHOP** **TX Ind. Haz Waste** **S102749829**
WNW **10720 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
67 ft. **Site 8 of 10 in cluster J**

Actual:
751 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	QUALITY BODY SHOP
Address:	10720 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66345
Registration Initial Notification Date:	07/03/1985
Registration Last Amendment Date:	01/11/2002
EPA Identification:	TXD030916472
Primary NAICS Code:	Not reported
Status Change Date:	19850703
Land Type:	PRIVATE
Description of Facility Site Location:	10720 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	QUALITY BODY SHOP INC
Contact Name:	BILL THOMISON
Contact Telephone Number:	512-8373568
Mailing Address:	10720 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787533070
Mailing County:	UNITED STATES

QUALITY BODY SHOP (Continued) **S102749829**

Facility Country:	UNITED STATES
TNRCC Facility ID:	21624
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	QUALITY BODY SHOP INC
Operator Address:	10720 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8373568
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17516625435
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	QUALITY BODY SHOP INC
Owner Mailing Address:	10720 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8373568
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17516625435
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	10720 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373568

QUALITY BODY SHOP (Continued) **S102749829**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	10720 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373568
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	BILL THOMISON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	10720 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373568
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100559830
Name:	QUALITY BODY SHOP
Address:	10720 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3070
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600270649
Customer Name:	QUALITY BODY SHOP INC
Customer Legal Name:	Quality Body Shop, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/11/2002
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10720 N Lamar, Austin, TX
Regulated Entity Number:	RN100559830
Name:	QUALITY BODY SHOP
Address:	10720 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3070
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600270649
Customer Name:	QUALITY BODY SHOP INC
Customer Legal Name:	Quality Body Shop, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/11/2002

QUALITY BODY SHOP (Continued) **S102749829**

Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10720 N Lamar, Austin, TX

J1050 **QUALITY BODY SHOP INC** **RCRA NonGen / NLR** **1000287309**
WNW **10720 N LAMAR** **FINDS** **TXD030916472**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.013 mi.
67 ft. **Site 9 of 10 in cluster J**

Actual:
751 ft.

Focus Map:
3

RCRA Listings:

Date Form Received by Agency:	20020111
Handler Name:	Quality Body Shop Inc
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD030916472
Contact Name:	BILL THOMISON
Contact Address:	N LAMAR
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-837-3568
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Quality Body Shop Inc
Owner Type:	Private
Operator Name:	Quality Body Shop Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

QUALITY BODY SHOP INC (Continued) **1000287309**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: QUALITY BODY SHOP INC	
Legal Status:	Private
Date Became Current:	20020111
Date Ended Current:	Not reported
Owner/Operator Address:	10720 N LAMAR

QUALITY BODY SHOP INC (Continued) **1000287309**

Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-3568
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: QUALITY BODY SHOP INC	
Legal Status:	Private
Date Became Current:	20020111
Date Ended Current:	Not reported
Owner/Operator Address:	10720 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-3568
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: BILL THOMISON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19850725
Handler Name: QUALITY BODY SHOP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20020111
Handler Name: QUALITY BODY SHOP INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

QUALITY BODY SHOP INC (Continued) **1000287309**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005046057

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000287309
Registry ID:	110005046057
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005046057
Name:	QUALITY BODY SHOP INC
Address:	10720 N LAMAR
City,State,Zip:	AUSTIN, TX 78753

1051 WNW < 1/8 0.013 mi. 67 ft. **PIRRUNG MOBILE SERV ST** **EDR Hist Auto** **1013761260**
7400 CONGRESS AVE S **N/A**
AUSTIN, TX 78745

Actual: 640 ft. EDR Hist Auto

Focus Map: 21

Year:	Name:	Type:
1972	PIRRUNG FRANK E	Gasoline Service Stations
1973	PIRRUNG FRANK E	Gasoline Service Stations
1974	PIRRUNG FRANK E	Gasoline Service Stations
1975	PIRRUNG SERVICE STATION	GASOLINE STATIONS
1975	PIRRUNG FRANK E	Gasoline Service Stations
1976	PIRRUNG FRANK E	Gasoline Service Stations
1977	PIRRUNG FRANK E	Gasoline Service Stations
1980	PIRRUNG MOBILE SERV ST	GASOLINE STATIONS

1052 ESE < 1/8 0.013 mi. 67 ft. | **MONARCH TRANSMISSION SERVICE**
10409 LAMAR BLVD N
AUSTIN, TX 78753 | **EDR Hist Auto** | **1013754893**
N/A

Actual: 722 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1976	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1977	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1978	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1979	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1980	MONARCH TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1980	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1982	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1983	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1984	MONARCH TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1985	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1986	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1987	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1988	MONARCH TRANSMISSION CO	Automotive Repair Shops, NEC
1989	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1990	MONARCH TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1990	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1991	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1992	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1993	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1994	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1995	MONARCH TRANSMISSION CO	Automotive Transmission Repair Shops
1996	AUSTIN COLLISION & GL CLINIC	General Automotive Repair Shops
1997	AUSTIN COLLISION & GL CLINIC	General Automotive Repair Shops
1998	FAMILY AUTO REPAIRS	General Automotive Repair Shops
1998	AUSTIN COLLISION & GL CLINIC	General Automotive Repair Shops
1999	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2000	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2001	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2002	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2003	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2004	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2005	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2006	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2007	FAMILY AUTO REPAIRS	General Automotive Repair Shops
2008	FAMILY AUTO REPAIRS	General Automotive Repair Shops

IC1053 WNW < 1/8 0.013 mi. 67 ft. | **35TH AND GUADALUPE SERVICE STATION**
3508 GUADALUPE ST
AUSTIN, TX | **EDR Hist Auto** | **1013755833**
N/A

Site 1 of 10 in cluster IC

Actual: 595 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1929	35TH AND GUADALUPE SERVICE STAT	GASOLINE AND OIL SERVICE STATIONS

BM1054 **RITTERS SERVICE STATION** **EDR Hist Auto** **1013767429**
WSW **2718 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
67 ft. **Site 5 of 6 in cluster BM**

Actual:
600 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	TROXELL BROS FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	TROXELLS SERV STA	GASOLINE STATIONS
1958	TROXELL SERV STA	GASOLINE STATIONS
1962	TROXELL SERV STA	GASOLINE STATIONS
1965	RITTERS SERVICE STATION	GASOLINE STATIONS
1970	RITTERS GASOLINE STATION	GASOLINE STATIONS
1975	RITTERS GASOLINE STATION	GASOLINE STATIONS

BM1055 **GASKINS REAL ESTATE BROKERAGE** **TX LPST** **U001281028**
WSW **2718 GUADALUPE ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.013 mi.
67 ft. **Site 6 of 6 in cluster BM**

Actual:
600 ft.

Focus Map:
11

LPST:

Name:	GASKINS REAL ESTATE BROKERAGE
Address:	2718 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0050186
LPST Id:	094905
Facility Location:	2718 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/09/1990
Entered Date:	03/16/1990
Reported Date:	02/09/1990
Closure Date:	04/10/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	MATT GASKINS
Responsible Party Address:	PO BOX 49701 327 CON
Responsible Party City,St,Zip:	AUSTIN, TX 78765
Responsible Party Telephone:	512/480-8083
Reported Date:	02/09/1990
Case Start Date:	04/10/1990
Reference Number:	RN101490258
Project Manager:	HWELCH

UST:

Name:	GASKINS REAL ESTATE BROKERAGE
Address:	2718 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787053702
AI Number:	50186
Facility Type:	UNKNOWN

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Facility Begin Date:	02/08/1990
Facility Status:	INACTIVE
Additional ID:	669559422002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/05/1990
Signature Name/Title On Earliest Reg Form:	W M GASKINS,PRESIDENT
Application Received Date On Earliest Reg Form:	02/06/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600779102
Owner Last Name:	GASKINS REAL ESTATE BROKERAGE INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	661559412002053
Additional ID:	669559422002053
AI Number:	50186
Owner Effective Begin Date:	02/08/1990
State Tax ID:	17425634320
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130072
Facility ID:	81816
Ai Number:	50186
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	6
Tank Capacity:	500
UST Comprt ID:	131623
UST ID:	130072
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432
Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	117993
UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998
UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	266667

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130073
Facility ID:	81816
Ai Number:	50186
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	131624
UST ID:	130073
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117993

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998
UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	266667
UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130074
Facility ID:	81816
Ai Number:	50186
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	131625
UST ID:	130074
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432
Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117993
UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998
UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	266667
UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1973
Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130075
Facility ID:	81816
Ai Number:	50186
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	131626
UST ID:	130075
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432
Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117993
UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998
UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	266667
UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Self Cert ID:	19432

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1973
Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130076
Facility ID:	81816
Ai Number:	50186
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	131627
UST ID:	130076
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432
Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117993
UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	266667
UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1973
Tank Registration Date:	02/06/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	130077
Facility ID:	81816
Ai Number:	50186
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	131628
UST ID:	130077
AI Number:	50186
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19432
Cert ID:	117986
UST Comprt ID:	335493
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	381345
UST Comprt ID:	1112580
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117988
UST Comprt ID:	335495
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117989
UST Comprt ID:	335492
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117990
UST Comprt ID:	335491

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117991
UST Comprt ID:	335490
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117992
UST Comprt ID:	335489
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117993
UST Comprt ID:	335488
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117994
UST Comprt ID:	335487
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117995
UST Comprt ID:	335486
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117996
UST Comprt ID:	335485
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117997
UST Comprt ID:	335484
UST ID:	113979

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117998
UST Comprt ID:	335483
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	233853
UST Comprt ID:	671310
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	248715
UST Comprt ID:	715115
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	266667
UST Comprt ID:	768148
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	277789
UST Comprt ID:	800903
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	294243
UST Comprt ID:	849786
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	310229
UST Comprt ID:	897708
UST ID:	113979
AI Number:	50186

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	328897
UST Comprt ID:	953330
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	345851
UST Comprt ID:	1004781
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	362269
UST Comprt ID:	1054252
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A
Self Cert ID:	19432
Cert ID:	117987
UST Comprt ID:	335494
UST ID:	113979
AI Number:	50186
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	GASKINS REAL ESTATE BROKERAGE
Contact Mailing Address (Delivery):	PO BOX 49701
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78765 9701
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	81816
Additional ID:	669559422002053
Princ ID:	661559412002053
AI Number:	50186
Facility Name:	GASKINS REAL ESTATE BROKERAGE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

GASKINS REAL ESTATE BROKERAGE (Continued) **U001281028**

HIST UST AUSTIN:

Name:	BUY & FLY
Address:	2718 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0046
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

O1056 **MANAISH ENTERPRISES INC** **EDR Hist Cleaner** **1018593164**
WNW **9616 N LAMAR BLVD STE A** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
68 ft. **Site 8 of 9 in cluster O**

Actual:
688 ft.

EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1994	DRY CLEAN CITY 159	Drycleaning Plants, Except Rugs, NEC
1995	DRY CLEAN CITY 159	Drycleaning Plants, Except Rugs, NEC
1996	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1996	MC CREA CLEANING CORP	Drycleaning Plants, Except Rugs, NEC
1997	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1998	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
1999	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
2000	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
2001	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
2008	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
2009	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC
2010	MANAISH ENTERPRISES INC	Coin-Operated Laundries And Cleaning, NEC

O1057 **AARONS** **TX VCP** **S103865075**
WNW **9616 N LAMAR BLVD** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
68 ft. **Site 9 of 9 in cluster O**

Actual:
688 ft.

VCP TCEQ:

Focus Map:
6

Name:	NORTH PARK SHOPPING CENTER
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	REGION 11 - AUSTIN
Facility ID:	406
VCP Record Date:	11/27/1996
Facility Type:	RETAIL STORE/SHOPPING CENTER
PCA Number:	38316
Project Manager:	RCONCIEN
Phase:	COMPLETED
Acres at Site:	10.003
REM Program:	VCP
RN Number:	RN102743630
Former Facility Type:	Not reported
Site Address Description:	9616 NORTH LAMAR BOULEVARD
Near City Name:	AUSTIN
Administrative Status:	INACTIVE

AARONS (Continued) **S103865075**

Region Notified of Application:	11/22/1996
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	02/11/1997
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	NOT REQUIRED
Air Target COC Class:	Not reported
Date Cashier Check Received:	11/22/1996
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1996-12-01 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	406
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	313160
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.37
Longitude:	-97.70

Contact:

REM Program:	VCP
Program ID:	406
RN Number:	RN102743630
CN Number:	CN603010695
CN Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Role Code:	BILLCONT
Contact Name:	ARCHER, KEVIN
Contact Title:	Not reported
Organization Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Mailing Address:	3267 BEE CAVES RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Contact Telephone:	(512) 328-2020
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	406
RN Number:	RN102743630
CN Number:	CN600411128

AARONS (Continued) **S103865075**

CN Name:	KEYSTONE-AUSTIN PROPERTY HOLDING CORP
Role Code:	BILLCONT
Contact Name:	ARCHER, KEVIN
Contact Title:	Not reported
Organization Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Mailing Address:	3267 BEE CAVES RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Contact Telephone:	(512) 328-2020
Contact Telephone Ext:	0

ASBESTOS:

Name:	AARONS
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported

AARONS (Continued) **S103865075**

Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AARONS SALES & LEASE
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	07/02/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	07/08/2013
Date Routed by Supervisor:	07/08/2013
Date Routed to PSQA:	08/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

AARONS (Continued) **S103865075**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOLLAR GENERAL
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ

AARONS (Continued) **S103865075**

Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOLLAR GENERAL
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	07/02/2013

AARONS (Continued) **S103865075**

Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	2.6
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/08/2013
Date Routed by Supervisor:	07/08/2013
Date Routed to PSQA:	08/07/2013
Date Reviewed by PSQA:	Email from Mic
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

AARONS (Continued) **S103865075**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CLOUD 9 ATX
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/17/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2014
Date Routed by Supervisor:	07/02/2014
Date Routed to PSQA:	07/02/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

AARONS (Continued) **S103865075**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CLOUD 9 ATX
Address:	9616 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	07/02/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/08/2013
Date Routed by Supervisor:	07/08/2013
Date Routed to PSQA:	08/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

AARONS (Continued) **S103865075**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

1058
West
< 1/8
0.013 mi.
68 ft.

CAMPUS SHOP CLNRS **EDR Hist Cleaner** **1013778762**
2332 GUADALUPE ST **N/A**
AUSTIN, TX

Actual:
588 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	CAMPUS SHOP CLNRS	CLOTHES CLEANERS AND PRESSERS

DC1059
WNW
< 1/8
0.013 mi.
68 ft.

GHOST TANK **TX HIST UST** **S128728754**
501 WEST AVE. **N/A**
AUSTIN, TX

Site 3 of 11 in cluster DC

Actual:
464 ft.

HIST UST AUSTIN:

Name:	GHOST TANK
Address:	501 WEST AVE.
City,State,Zip:	AUSTIN, TX

Focus Map:
11

GHOST TANK (Continued) **S128728754**

Id UST:	3391
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DC1060 **5TH AND WEST** **TX TANKS** **S126886578**
WNW **501 WEST AVE** **TX RDR** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX CENTRAL REGISTRY**
0.013 mi.
68 ft. **Site 4 of 11 in cluster DC**

Actual:
464 ft.

Focus Map:
11

TANKS:

Facility ID:	132926
Name:	5TH AND WEST
Address:	501 WEST AVE
City,State,Zip:	AUSTIN, TX 787012893
Total UST:	Not reported
Additional ID:	124352952015202
AI Number:	87800
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

RDR:

RDR ID:	23082
Facility ID:	87800
RN:	Not reported
CN:	Not reported
Name:	5TH AND WEST

5TH AND WEST (Continued) **S126886578**

Address:	501 WEST AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/21/2015
Due Date:	10/20/2015
Tank Owner:	5TH & WEST OWNER LP
Contact Person:	JOHN NEEDHAM
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/31/2015
Project Manager:	Morgan Suhm
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN108671553
Name:	5TH AND WEST
Address:	501 WEST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2893
Status:	ACTIVE
Status Date:	7/21/2015
Customer Number:	CN604896217
Customer Name:	5TH AND WEST OWNER LP
Customer Legal Name:	5TH AND WEST OWNER, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/16/2015
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

IC1061 **FLAMINGO AUTOMOTIVE** **EDR Hist Auto** **1013763304**
WNW **3512 GUADALUPE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.013 mi.
68 ft. **Site 2 of 10 in cluster IC**

Actual:
594 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1962	STAR AUTO SERV	AUTOMOBILE REPAIRING
1984	SHIMEK RON GARAGE	AUTOMOBILE REPAIRING
1986	RON SHIMEKS GARAGE	General Automotive Repair Shops
1990	FLAMINGO AUTOMOTIVE	AUTOMOBILE REPAIRING
1991	LAMPING JOSEPH P	General Automotive Repair Shops
1992	LAMPING JOSEPH P	Automotive Repair Shops, NEC

FLAMINGO AUTOMOTIVE (Continued) **1013763304**

1993	LAMPING JOSEPH P	Automotive Repair Shops, NEC
1994	LAMPING JOSEPH P	Automotive Repair Shops, NEC
1995	LAMPING JOSEPH P	Automotive Repair Shops, NEC
1996	LAMPING JOSEPH P	Automotive Repair Shops, NEC
1997	LAMPING JOSEPH P	Automotive Repair Shops, NEC
1998	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
1999	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2000	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2001	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2002	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2003	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2004	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2005	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2006	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2007	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2008	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2009	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2010	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2011	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2012	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2013	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC
2014	FLAMINGO AUTOMOTIVE	Automotive Repair Shops, NEC

IC1062 **FLAMINGO AUTOMOTIVE** **TX UST** **U001290527**
WNW **3512 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.013 mi.
68 ft. **Site 3 of 10 in cluster IC**

Actual:
594 ft.

Focus Map:
8

UST:

Name:	FLAMINGO AUTOMOTIVE
Address:	3512 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787051336
AI Number:	61457
Facility Type:	RETAIL
Facility Begin Date:	11/04/1991
Facility Status:	INACTIVE
Additional ID:	299697752002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	JOE DAYWOOD,
Contact Organization Name:	FLAMINGO AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124784118
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/31/1991
Signature Name/Title On Earliest Reg Form:	TODD MCCANN,MGR

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

Application Received Date On Earliest Reg Form:	10/31/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600783559
Owner Last Name:	DAYWOOD JOE H
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	123693972002053
Additional ID:	299697752002053
AI Number:	61457
Owner Effective Begin Date:	11/04/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/31/1991
Number of Compartments:	1
Tank Capacity:	20
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	143535
Facility ID:	91570
Ai Number:	61457
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	20
UST Comprt ID:	143836
UST ID:	143535
AI Number:	61457
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/31/1991
Number of Compartments:	1
Tank Capacity:	573
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	143536
Facility ID:	91570
Ai Number:	61457
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	573
UST Comprt ID:	143837
UST ID:	143536
AI Number:	61457
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/31/1991
Number of Compartments:	1
Tank Capacity:	579
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	143537
Facility ID:	91570
Ai Number:	61457
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	579
UST Comprt ID:	143838
UST ID:	143537
AI Number:	61457
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/31/1991
Number of Compartments:	1
Tank Capacity:	1043
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	143534
Facility ID:	91570
Ai Number:	61457
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/21/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	1043
UST Comprt ID:	143835
UST ID:	143534
AI Number:	61457
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

FLAMINGO AUTOMOTIVE (Continued) **U001290527**

Facility Billing Contacts:

Contact Organization Name:	DAYWOOD JOE H
Contact Mailing Address (Delivery):	1602 E 6TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78702 3308
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91570
Additional ID:	299697752002053
Princ ID:	123693972002053
AI Number:	61457
Facility Name:	FLAMINGO AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOE DAYWOOD/

HIST UST AUSTIN:

Name:	FLAMINGO AUTO
Address:	3512 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0309
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IC1063 **JOE DAYWOOD** **TX LPST** **S116695858**
WNW **3512 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.013 mi.
68 ft. **Site 4 of 10 in cluster IC**

Actual:
594 ft.

Focus Map:
8

LPST:

Name:	JOE DAYWOOD
Address:	3512 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0061457
LPST Id:	102227
Facility Location:	3512 N GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/27/1992
Entered Date:	04/13/1992
Reported Date:	03/14/1992
Closure Date:	03/11/1996
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported

JOE DAYWOOD (Continued) **S116695858**

Responsible Party Contact: DAVID LAMPING
Responsible Party Address: 3512 N GUADALUPE
Responsible Party City,St,Zip: AUSTIN, TX 78711
Responsible Party Telephone: 512/459-9917
Reported Date: 03/14/1992
Case Start Date: 03/11/1996
Reference Number: RN101495919
Project Manager: HWELCH

CA1064 **T CLEANING & PRESSING SHOP R** **EDR Hist Cleaner** **1013783683**
West **2206 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
68 ft. **Site 5 of 5 in cluster CA**

Actual:
578 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	T CLEANING & PRESSING SHOP R	CLOTHES CLEANERS AND PRESSERS

BG1065 **OXFORD CLEANERS** **EDR Hist Cleaner** **1013784479**
WNW **2928 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.013 mi.
68 ft. **Site 6 of 8 in cluster BG**

Actual:
597 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1990	OXFORD CLEANERS	CLEANERS AND DYERS
1992	OXFORD CLEANERS	Drycleaning Plants, Except Rugs
1993	OXFORD CLEANERS	Drycleaning Plants, Except Rugs
1994	OXFORD CLEANERS	Drycleaning Plants, Except Rugs

FO1066 **HUDSON OIL CO NO 91 GAS ATA** **EDR Hist Auto** **1013769435**
SW **2001 RIVERSIDE DR E** **N/A**
< 1/8 **TRAVIS (County), TX 78741**
0.013 mi.
68 ft. **Site 8 of 10 in cluster FO**

Actual:
479 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1975	HUDSON OIL CO NO 91 GAS ATA	GASOLINE STATIONS

FO1067 SW < 1/8 0.013 mi. 68 ft. | **BEVERAGE BARN 2001 RIVERSIDE AUSTIN, TX** | **TX RDR** | **S127526664 N/A**

Site 9 of 10 in cluster FO

Actual: 479 ft.

Focus Map: 14

RDR:

RDR ID:	23361
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN
Address:	2001 RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/21/2016
Due Date:	5/20/2016
Tank Owner:	MTG MANAGEMENT INC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/8/2016
Project Manager:	Morgan Suhm
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR REC 12/28/16; DEF LTR SENT 2/18/16; REC TECH RESP 3/21/16; REC FSC 7/26/16;
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

HY1068 WSW < 1/8 0.013 mi. 68 ft. | **2800 02 SMITH J J GARAGE 2800 GUADALUPE ST AUSTIN, TX** | **EDR Hist Auto** | **1013755526 N/A**

Site 2 of 7 in cluster HY

Actual: 598 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1922	SMITHS GARAGE 28TH	AUTOMOBILE GARAGES
1929	2800 02 SMITH J J GARAGE	AUTOMOBILE FILLING STATIONS
1929	2800 02 SMITH J J GARAGE	AUTOMOBILE GARAGES
1929	2800 02 SMITH J J GARAGE	AUTOMOBILE REPAIRERS
1935	SMITH JESSE J	AUTOMOBILE REPAIRERS
1935	SMITH JESSE J	AUTOMOBILE GARAGES
1935	SMITH JESSE J	AUTOMOBILE FILLING STATIONS
1935	SMITH JESSE J	AUTOMOBILE BRAKE SERVICE
1940	SMITH JESSE J	GASOLINE AND OIL SERVICE STATIONS
1940	SMITH JESSE J	AUTOMOBILE REPAIRING
1947	SMITH JESSE JAMES GARAGE AUTO R	AUTOMOBILE REPAIRING
1947	SMITH JESSE JAMES GARAGE AUTO R	GASOLINE AND OIL SERVICE STATIONS
1953	SMITH JESSE JAS	AUTOMOBILE REPAIRING
1958	SMITH JESSE JAS	AUTOMOBILE REPAIRING
1962	SMITH JESSE JAS	AUTOMOBILE REPAIRING

2800 02 SMITH J J GARAGE (Continued) **1013755526**

1969	SMITH JESSE JAMES GARAGE	General Automotive Repair Shops
1970	SMITH JESSE JAMES GARAGE	General Automotive Repair Shops

---

HY1069
WSW
< 1/8
0.013 mi.
68 ft.

TACO BELL
2800 GUADALUPE ST
AUSTIN, TX

Site 3 of 7 in cluster HY

TX HIST UST **S128728924**
N/A

Actual:
598 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TACO BELL
Address:	2800 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0136
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ID1070
WNW
< 1/8
0.013 mi.
68 ft.

CHUCKS CUSTOM AUTO
11000 N LAMAR BLVD
AUSTIN, TX 78753

Site 1 of 3 in cluster ID

TX Ind. Haz Waste **S102749824**
N/A

Actual:
770 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	CHUCKS CUSTOM AUTO
Address:	11000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66336
Registration Initial Notification Date:	06/24/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD051351187
Primary NAICS Code:	Not reported
Status Change Date:	19850624
Land Type:	PRIVATE
Description of Facility Site Location:	11000 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CHUCKS CUSTOM AUTO INC
Contact Name:	CHUCK LAMME
Contact Telephone Number:	512-8373395
Mailing Address:	11000 N LAMAR BLVD
Mailing Address2:	Not reported

CHUCKS CUSTOM AUTO (Continued) **S102749824**

Mailing City,State,Zip:	AUSTIN, TX 787533049
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21615
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031104
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CHUCKS CUSTOM AUTO INC
Operator Address:	11000 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8373395
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17425039744
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CHUCKS CUSTOM AUTO INC
Owner Mailing Address:	11000 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8373395
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17425039744
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	11000 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported

CHUCKS CUSTOM AUTO (Continued) **S102749824**

Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373395
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	11000 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373395
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	CHUCK LAMME
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	11000 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8373395
Contact Fax:	Not reported
Contact Email:	Not reported

ID1071 **CHUCKS CUSTOM AUTO INC** **RCRA NonGen / NLR** **1000173540**
WNW **11000 N LAMAR BLVD** **FINDS** **TXD051351187**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.013 mi.
68 ft. **Site 2 of 3 in cluster ID**

Actual:
770 ft.

Focus Map:
3

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Chucks Custom Auto Inc
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD051351187
Contact Name:	CHUCK LAMME
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-837-3395
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753

CHUCKS CUSTOM AUTO INC (Continued) **1000173540**

Owner Name:	Chucks Custom Auto Inc
Owner Type:	Private
Operator Name:	Chucks Custom Auto Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed

CHUCKS CUSTOM AUTO INC (Continued) **1000173540**

In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CHUCKS CUSTOM AUTO INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	11000 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-3395
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CHUCKS CUSTOM AUTO INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	11000 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-837-3395
Owner/Operator Telephone Ext:	Not reported

CHUCKS CUSTOM AUTO INC (Continued) **1000173540**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHUCK LAMME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 11000 N LAMAR
Owner/Operator City,State,Zip: AUSTIN, TX 78753-0000
Owner/Operator Telephone: 512-837-3395
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19850710
Handler Name: CHUCKS CUSTOM AUTO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: CHUCKS CUSTOM AUTO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005051344

CHUCKS CUSTOM AUTO INC (Continued) **1000173540**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000173540
Registry ID:	110005051344
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005051344
Name:	CHUCKS CUSTOM AUTO INC
Address:	11000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

ID1072 **SCHARFE DENNIS F BUILDER INC** **EDR Hist Auto** **1020968870**
WNW **11000 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
68 ft. **Site 3 of 3 in cluster ID**

Actual:
770 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1975	PERRYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1976	PERRYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1977	PERRYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1978	PERRYS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1999	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2000	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2001	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2002	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2003	AUSTIN CRC INC	Exterior Repair Services
2003	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2004	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2004	AUSTIN CRC INC	Exterior Repair Services
2005	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2005	AUSTIN CRC INC	Exterior Repair Services
2006	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2006	AUSTIN CRC INC	Exterior Repair Services
2007	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2007	AUSTIN CRC INC	Exterior Repair Services
2008	AUSTIN CRC INC	Exterior Repair Services
2008	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2009	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2009	AUSTIN CRC INC	Exterior Repair Services
2010	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2010	AUSTIN CRC INC	Exterior Repair Services
2011	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2011	AUSTIN CRC INC	Exterior Repair Services
2012	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2012	AUSTIN CRC INC	Exterior Repair Services

SCHARFE DENNIS F BUILDER INC (Continued) **1020968870**

2013	AUSTIN CRC INC	Exterior Repair Services
2013	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2014	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2014	AUSTIN CRC INC	Exterior Repair Services

ET1073 **CONGRESS AVE** **TX HIST LF** **S129375040**
WNW **1200 BLK CONGRESS AVE** **N/A**
< 1/8 **TRAVIS (County), TX**
0.013 mi.
68 ft. **Site 6 of 15 in cluster ET**

Actual:
503 ft.

Focus Map:
14

HIST LF:

Name:	CONGRESS AVE
Name 2:	Not reported
Address:	1200 BLK CONGRESS AVE
City,State,Zip:	TX
Latitude:	30.252500
Longitude:	-97.748833
Lat Deg:	30
Lat MM:	15.15
Lon DD:	97
Lon MM:	44.93
UNUM:	885
Comments:	Identified in list of Travis County sites;
Inspection:	???
COG Number:	12
COOR CD:	Not reported
TWC District:	14
Owner Name:	Not reported
Owner Code:	Not reported
Open Date:	1925
Close Date:	1930
Acres:	0
Yards:	0
Parties:	Austin
Household:	Y
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Y
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	Not reported

ET1074 **CONGRESS AVE** **TX CLI** **S103259059**
WNW **1200 BLK CONGRESS AVE** **N/A**
< 1/8 **, TX**
0.013 mi.
68 ft. **Site 7 of 15 in cluster ET**

Actual:
503 ft.

Focus Map:
14

CLI:

Name:	CONGRESS AVE
Address:	1200 BLK CONGRESS AVE
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	*********
Source Code:	Not reported
Date Opened:	1925
Date Closed:	1930
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	15.15
Long Deg:	97
Long Min:	44.93
Lat/Long (deg):	30.252500 / -97.748833
Owner:	Not reported
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	14
Code for Landfill:	1
Parties:	Austin
Accepts House Hold:	Yes
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported

CONGRESS AVE (Continued) **S103259059**

Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Yes
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Uk
Inspc Comments:	???
Comments:	Identified in list of Travis County sites;
Update:	0
Reviewer:	Not reported
Flag:	Not reported

ET1075 **CONGRESS AVE** **TX CLI** **S113416475**
WNW **1200 BLK CONGRESS AVE** **N/A**
< 1/8 **TRAVIS (County), TX**
0.013 mi.
68 ft. **Site 8 of 15 in cluster ET**

Actual:
503 ft.

Focus Map:
14

CAPCOG LI:

Name:	CONGRESS AVE
Address:	1200 BLK CONGRESS AVE
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	1925
Date Close:	1930
Unum:	885
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	15.15
Longitude Deg:	97
Longitude Min:	44.93
Lat Dd:	30.252500000000001
Long Dd:	-97.748833000000005
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	0
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported

CONGRESS AVE (Continued) **S113416475**

Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	John Thompson and Dottye Dean
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	14
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Austin
Household:	Y
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Y
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Inspection:	???
Comment:	Identified in list of Travis County sites;
Latitude:	30.2525
Longitude:	-97.74883333
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part1.pdf#page=179

W1076 SE < 1/8 0.013 mi. 69 ft. | **DONCO TRUCK & AUTOMOTIVE AUTO REPR** | **EDR Hist Auto** | **1013768909**
8305 LAMAR BLVD N | **N/A**
TRAVIS (County), TX 78753

Site 3 of 4 in cluster W

Actual: 728 ft. EDR Hist Auto

Focus Map: 6

Year:	Name:	Type:
1972	DONCO TRUCK & AUTOMOTIVE	General Automotive Repair Shops
1973	DONCO TRUCK & AUTOMOTIVE	General Automotive Repair Shops
1974	DONCO TRUCK & AUTOMOTIVE	General Automotive Repair Shops
1975	DONCO TRUCK & AUTOMOTIVE AUTO R	AUTOMOBILE REPAIRING
1975	DONCO TRUCK & AUTO REPAIR	General Automotive Repair Shops
1976	DONCO TRUCK & AUTO REPAIR	General Automotive Repair Shops
1978	WHITTLESEY BROS AT & TRCK CTR*	General Automotive Repair Shops

---

W1077 SE < 1/8 0.013 mi. 69 ft. | **RYDER TRUCK RENTAL 0789A** | **TX LPST** | **U001239626**
8305 N LAMAR BLVD | **TX UST** | **N/A**
AUSTIN, TX 78753 | **TX HIST UST**
TX Financial Assurance

Site 4 of 4 in cluster W

Actual: 728 ft.

Focus Map: 6

LPST:

Name:	RYDER TRUCK RENTAL FAC
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0002651
LPST Id:	094088
Facility Location:	8305 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/04/1989
Entered Date:	12/05/1989
Reported Date:	12/05/1989
Closure Date:	02/05/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	IVAN J GONZALEZ
Responsible Party Address:	3411 CEDAR KNOLLS DR
Responsible Party City,St,Zip:	KINGWOOD, TX 77339
Responsible Party Telephone:	713/358-8086
Reported Date:	12/05/1989
Case Start Date:	02/05/1990
Reference Number:	RN102238698
Project Manager:	HWELCH

UST:

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535920
AI Number:	2651
Facility Type:	FLEET REFUELING

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	941807592002138
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	RYDER TRUCK RENTAL 0789A
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128367286
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	3056294290
Contact Email Address:	COMPLIANCERFS@RYDER.COM
Signature Date On Earliest Reg Form:	05/20/2022
Signature Name/Title On Earliest Reg Form:	EBONY COLEMAN,CO COOR
Application Received Date On Earliest Reg Form:	05/23/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	619280312001297
Additional ID:	941807592002138
Ai Number:	2651
Operator CN:	CN600257299
Operator Name:	RYDER TRUCK RENTAL INC
Operator Effective Begin Date:	05/08/1986
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	RYDER TRUCK RENTAL INC
Contact Mailing Address (Delivery):	3500 BELT LINE RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75234-2422
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Princ ID:	619280312001297
Additional ID:	941807592002138
Ai Number:	2651
Operator CN:	CN600257299

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Operator Name:	RYDER TRUCK RENTAL INC
Operator Effective Begin Date:	06/30/1998
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600257299
Owner Last Name:	RYDER TRUCK RENTAL INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 70737
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	HOUSTON
Contact Mailing State:	TX
Contact Mailing Zip:	77270
Contact Mailing Zip5:	0737
Contact Phone Number/Ext:	1 713 4264800/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	619280312001297
Additional ID:	941807592002138
AI Number:	2651
Owner Effective Begin Date:	05/08/1986
State Tax ID:	15907470353
Contact Role:	OWNCON
Contact Name/Title:	/
Contact Organization Name:	RYDER TRUCK RENTAL INC

Self Certification:

Self Cert ID:	75233
Cert ID:	371526
AI Number:	2651
Self Certification Date:	05/20/2022
Signature Name/Title:	EBONY COLEMAN CO COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	355745
AI Number:	2651
Self Certification Date:	06/24/2021
Signature Name/Title:	ELENA MACIAS RFS COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	338483
AI Number:	2651
Self Certification Date:	06/11/2020
Signature Name/Title:	HEATHER MELTON FUEL SREV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	321992
AI Number:	2651
Self Certification Date:	06/12/2019
Signature Name/Title:	HEATHER MELTON COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	304569
AI Number:	2651
Self Certification Date:	06/01/2018
Signature Name/Title:	HEATHER MELTON COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	287552
AI Number:	2651
Self Certification Date:	05/25/2017
Signature Name/Title:	HEATHER MELTON COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	270146
AI Number:	2651
Self Certification Date:	05/13/2016
Signature Name/Title:	AMY WHITE SR COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75233
Cert ID:	254054
AI Number:	2651
Self Certification Date:	05/29/2015
Signature Name/Title:	AMY WHITE COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75233
Cert ID:	237884
AI Number:	2651
Self Certification Date:	06/04/2014
Signature Name/Title:	AMY WHITE SR COMPL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75233
Cert ID:	220420
AI Number:	2651
Self Certification Date:	05/21/2013
Signature Name/Title:	AMY WHITE SR COMPL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75233
Cert ID:	108777
AI Number:	2651
Self Certification Date:	05/24/2012
Signature Name/Title:	AMY WHITE SR COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75233
Cert ID:	108776
AI Number:	2651
Self Certification Date:	05/24/2011
Signature Name/Title:	AMY WHITE COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75233
Cert ID:	108775
AI Number:	2651
Self Certification Date:	06/01/2010
Signature Name/Title:	COREY MCMILLAN COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108774
AI Number:	2651
Self Certification Date:	07/07/2009
Signature Name/Title:	AMY WHITE OPERATIONS OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108773
AI Number:	2651
Self Certification Date:	07/11/2008
Signature Name/Title:	AMY WHITE RYDER FS COO
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108772
AI Number:	2651
Self Certification Date:	05/02/2007
Signature Name/Title:	AMY WHITE COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108771
AI Number:	2651
Self Certification Date:	05/03/2006
Signature Name/Title:	AMY WHITE OWNER'S AUTH. REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108770
AI Number:	2651
Self Certification Date:	04/30/2005
Signature Name/Title:	AMY WHITE COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108769
AI Number:	2651
Self Certification Date:	04/30/2004
Signature Name/Title:	AMY WHITE COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108768
AI Number:	2651
Self Certification Date:	05/15/2003
Signature Name/Title:	AMY WHITE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108767
AI Number:	2651
Self Certification Date:	04/15/2002
Signature Name/Title:	AMY WHITE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75233
Cert ID:	108766
AI Number:	2651
Self Certification Date:	02/02/2001
Signature Name/Title:	STEPHEN R LEWIS SR MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6544
Facility ID:	75233
Ai Number:	2651
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	98465
UST ID:	6544
AI Number:	2651
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6545
Facility ID:	75233
Ai Number:	2651
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	98466
UST ID:	6545
AI Number:	2651
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	6546
Facility ID:	75233
Ai Number:	2651
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Compartment Records:

Tank ID:	3A
Tank Capacity:	12000
UST Comprt ID:	98467
UST ID:	6546
AI Number:	2651
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1990
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	6547
Facility ID:	75233
Ai Number:	2651
Tank Id:	3
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	06/09/2022

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	98468
UST ID:	6547
AI Number:	2651
Compartment ID:	A
Substance Stored1:	EMPTY

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1990
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	6548
Facility ID:	75233
Ai Number:	2651
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	98469
UST ID:	6548
AI Number:	2651
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1990
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	6549
Facility ID:	75233
Ai Number:	2651
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/24/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	98470
UST ID:	6549
AI Number:	2651
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RYDER TRUCK RENTAL INC
Contact Mailing Address (Delivery):	757 N ELDRIDGE PKWY STE 760
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77079 4548
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	COMPLIANCE@RYDERFS.COM
Contact Address Deliverable:	Y
Facility ID:	75233
Additional ID:	941807592002138
Princ ID:	619280312001297
AI Number:	2651
Facility Name:	RYDER TRUCK RENTAL 0789A
AR Number:	51976
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	ERIC HARVEY/

HIST UST AUSTIN:

Name:	RYDER TRANSPORTATION SERVICES #0789
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1920
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Finass ID:	269332
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G71744255 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	252482
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2020
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	ust g71744255 002
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	233161
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Financial Assurance Begin Date:	10/01/2019
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G71744255001
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	215781
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2018
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZY3572540
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	187642
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2017
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z3572539
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	197927
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2017
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z 35725 39
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	180429
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2016
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 724 8345000
Policy Number:	Z-35725-38
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	162417
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2015
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z-35725-37
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	145092
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2014
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z-35725-36
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	129317
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2013
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Policy Number:	Z-35725-35
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	116629
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2013
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z-35725-35
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	8156
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725 34
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Region:	2
Facility ID:	75233
Finass ID:	109172
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	Z-35725-34
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62702
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2011
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725 33
Coverage Amount:	1000000
Coverage Expiration Date:	10/01/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62703
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2010
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725 32
Coverage Amount:	2000000
Coverage Expiration Date:	10/01/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62704
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2010
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725 32
Coverage Amount:	2000000
Coverage Expiration Date:	10/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62705
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2009
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725 31
Coverage Amount:	2000000
Coverage Expiration Date:	10/01/2010

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62706
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2008
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725
Coverage Amount:	2000000
Coverage Expiration Date:	10/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62707
AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2007
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 888 7937865
Policy Number:	Z-35725
Coverage Amount:	2000000
Coverage Expiration Date:	10/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RYDER TRUCK RENTAL 0789A
Address:	8305 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	75233
Finass ID:	62708

RYDER TRUCK RENTAL 0789A (Continued) **U001239626**

AI:	2651
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1989
Date Financial Assurance Form Rec:	05/23/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

1078 **THE CAR BAZAR** **TX Ind. Haz Waste** **S103605798**
WNW **5540 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.013 mi.
69 ft.

Actual:
690 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	THE CAR BAZAR
Address:	5540 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	61759
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	5540 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	THE CAR BAZAR
Contact Name:	PATRICK STEBBINS
Contact Telephone Number:	Not reported
Mailing Address:	5540 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787511016
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

THE CAR BAZAR (Continued) **S103605798**

TNRCC Facility ID:	20100
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	THE CAR BAZAR
Operator Address:	5540 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78751
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE CAR BAZAR
Owner Mailing Address:	5540 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	5540 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported

THE CAR BAZAR (Continued) **S103605798**

Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	5540 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	PATRICK STEBBINS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	5540 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100607019
Name:	THE CAR BAZAR
Address:	5540 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1016
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600316483
Customer Name:	THE CAR BAZAR
Customer Legal Name:	The Car Bazar
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5540 N Lamar Blvd, Austin, TX

AI1079 **CENTRAL TEXAS HARLEY DAVIDSON** **EDR Hist Auto** **1013774880**
WNW **6310 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.013 mi.
69 ft. **Site 5 of 8 in cluster AI**

Actual:
711 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1990	CENTRAL TEXAS HARLEY DAVIDSON	MOTORCYCLE DEALERS AND REPAIRERS

HV1080 **SIGMOR SHAMROCK SERVICE STATION** **EDR Hist Auto** **1013767516**
WNW **10810 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
69 ft. **Site 2 of 3 in cluster HV**

Actual:
754 ft.

Focus Map:
3

EDR Hist Auto

Year:	Name:	Type:
1980	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1990	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1991	SIGMORE CORP	Gasoline Service Stations
1992	SIGMORE CORP	Gasoline Service Stations
1993	SIGMORE CORP	Gasoline Service Stations
1994	SIGMORE CORP	Gasoline Service Stations
1995	SIGMORE CORP	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Gasoline Service Stations

HV1081 **LAMAR FOOD MARKET** **TX UST** **U003566345**
WNW **10810 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.013 mi.
69 ft. **Site 3 of 3 in cluster HV**

Actual:
754 ft.

Focus Map:
3

UST:

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533046
AI Number:	45723
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	714575392002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	NAVROZ KARIMALI,
Contact Organization Name:	LAMAR FOOD MARKET
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123392295
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/29/2020
Signature Name/Title On Earliest Reg Form:	NAVROZ KARIMALI,OWNER
Application Received Date On Earliest Reg Form:	08/25/2020
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

LAMAR FOOD MARKET (Continued) **U003566345**

Operator:

Princ ID:	164364672012103
Additional ID:	714575392002053
Ai Number:	45723
Operator CN:	CN604065185
Operator Name:	NKA INC
Operator Effective Begin Date:	04/01/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	NAVROZ KARIMALI/
Contact Organization Name:	NKA INC
Contact Mailing Address (Delivery):	10810 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-3046
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3392295
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604065185
Owner Last Name:	NKA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	10810 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	3046
Contact Phone Number/Ext:	1 512 3392295/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	164364672012103
Additional ID:	714575392002053
AI Number:	45723
Owner Effective Begin Date:	04/01/2012
State Tax ID:	32045624163
Contact Role:	OWNOPRCON
Contact Name/Title:	NAVROZ KARIMALI/
Contact Organization Name:	NKA INC

Self Certification:

Self Cert ID:	74633
Cert ID:	373734
AI Number:	45723
Self Certification Date:	08/01/2022

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	357941
AI Number:	45723
Self Certification Date:	08/16/2021
Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	357944
AI Number:	45723
Self Certification Date:	08/16/2021
Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	341554
AI Number:	45723
Self Certification Date:	06/29/2020

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	324822
AI Number:	45723
Self Certification Date:	08/20/2019
Signature Name/Title:	NAVROZ KARIMALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	307373
AI Number:	45723
Self Certification Date:	07/19/2018
Signature Name/Title:	NAVROZ KARIMALI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	289904
AI Number:	45723
Self Certification Date:	07/25/2017

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	NAVROZ KARIMALI MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74633
Cert ID:	272872
AI Number:	45723
Self Certification Date:	07/07/2016
Signature Name/Title:	NAVROZ KARIMALI MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74633
Cert ID:	256666
AI Number:	45723
Self Certification Date:	06/22/2015
Signature Name/Title:	NAVROZ KARIM ALI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74633
Cert ID:	239800
AI Number:	45723
Self Certification Date:	07/18/2014

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	NAVROZ KARIM ALI MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	222566
AI Number:	45723
Self Certification Date:	06/20/2013
Signature Name/Title:	NAVROZ KARIMALI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74633
Cert ID:	106357
AI Number:	45723
Self Certification Date:	04/11/2012
Signature Name/Title:	NAVROZ KARIMALI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106356
AI Number:	45723
Self Certification Date:	04/10/2012

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	NAVROZ KARIMALI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106355
AI Number:	45723
Self Certification Date:	03/15/2011
Signature Name/Title:	BADARUDDIN ARAIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106354
AI Number:	45723
Self Certification Date:	02/24/2010
Signature Name/Title:	BADARUDDIN ARAIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106353
AI Number:	45723
Self Certification Date:	02/23/2009

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	BADARUDDIN ARAIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106352
AI Number:	45723
Self Certification Date:	02/27/2008
Signature Name/Title:	BADARUDDIN ARAIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106351
AI Number:	45723
Self Certification Date:	06/28/2007
Signature Name/Title:	BADARUDDIN ARAIN PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106350
AI Number:	45723
Self Certification Date:	09/14/2006

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	TARIQ MAJEED PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74633
Cert ID:	106349
AI Number:	45723
Self Certification Date:	09/11/2005
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74633
Cert ID:	106348
AI Number:	45723
Self Certification Date:	08/31/2004
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74633
Cert ID:	106347
AI Number:	45723
Self Certification Date:	09/01/2003

LAMAR FOOD MARKET (Continued) **U003566345**

Signature Name/Title:	KHUSHI MOHAMMAD MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106346
AI Number:	45723
Self Certification Date:	08/12/2002
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74633
Cert ID:	106345
AI Number:	45723
Self Certification Date:	04/20/2001
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/06/1986
Number of Compartments:	1

LAMAR FOOD MARKET (Continued) **U003566345**

Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119664
Facility ID:	74633
Ai Number:	45723
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/08/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

LAMAR FOOD MARKET (Continued) **U003566345**

Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1A
Tank Capacity:	8000
UST Comprt ID:	105193
UST ID:	119664
AI Number:	45723
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/06/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119665
Facility ID:	74633
Ai Number:	45723
Tank Id:	3

LAMAR FOOD MARKET (Continued) **U003566345**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/08/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	105194
UST ID:	119665
AI Number:	45723

LAMAR FOOD MARKET (Continued) **U003566345**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/06/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119666
Facility ID:	74633
Ai Number:	45723
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/08/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

LAMAR FOOD MARKET (Continued) **U003566345**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	105195
UST ID:	119666
AI Number:	45723
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y

LAMAR FOOD MARKET (Continued) **U003566345**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/06/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119667
Facility ID:	74633
Ai Number:	45723
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

LAMAR FOOD MARKET (Continued) **U003566345**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	105196
UST ID:	119667
AI Number:	45723
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

LAMAR FOOD MARKET (Continued) **U003566345**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	05/07/1999
Tank Registration Date:	05/17/1999
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191140
Facility ID:	74633
Ai Number:	45723
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	05/07/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

LAMAR FOOD MARKET (Continued) **U003566345**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/07/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	105197
UST ID:	191140
AI Number:	45723
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

LAMAR FOOD MARKET (Continued) **U003566345**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	05/07/1999
Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	105198
UST ID:	191140
AI Number:	45723
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	05/07/1999

LAMAR FOOD MARKET (Continued) **U003566345**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	30318
UST ID:	191140
NOC ID:	Not reported
AI Number:	45723
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	45479
UST ID:	191140
NOC ID:	Not reported
AI Number:	45723
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	Not reported
Representative Name:	TONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	NKA INC
Contact Mailing Address (Delivery):	10810 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3046
Phone Number/Ext:	512 3392295/0
Contact Fax Number/Ext:	/

LAMAR FOOD MARKET (Continued) **U003566345**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74633
Additional ID:	714575392002053
Princ ID:	164364672012103
AI Number:	45723
Facility Name:	LAMAR FOOD MARKET
AR Number:	73178
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	NAVROZ KARIMALI/

HIST UST AUSTIN:

Name:	LAMAR FOOD MART
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	393
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	271583
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2022
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000027715
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	254674
AI:	45723
Mechanism Type Other:	Not reported

LAMAR FOOD MARKET (Continued) **U003566345**

Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2021
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 80 722499
Policy Number:	04-TOP-000018186
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	254677
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2021
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 80 722499
Policy Number:	04-TOP-000018186
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	236189
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2020
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO

LAMAR FOOD MARKET (Continued) **U003566345**

Issuer Phone:	1 800 7224994
Policy Number:	04TOP000012214
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	218986
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2019
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000001460
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	200694
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2018
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000105530
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD

LAMAR FOOD MARKET (Continued) **U003566345**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	183107
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2017
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000100772
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	165318
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2016
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00096430
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	147663
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y

LAMAR FOOD MARKET (Continued) **U003566345**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2015
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04-TO-00092249
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	131537
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2014
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00088140
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/04/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	111472
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2013
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00084116
Coverage Amount:	1,000,000

LAMAR FOOD MARKET (Continued) **U003566345**

Coverage Expiration Date:	04/04/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	7962
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/04/2012
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00081427
Coverage Amount:	1000000
Coverage Expiration Date:	04/04/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	58519
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2010
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 688971-03
Coverage Amount:	1000000
Coverage Expiration Date:	06/06/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633

LAMAR FOOD MARKET (Continued) **U003566345**

Finass ID:	58520
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2009
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 688971-02
Coverage Amount:	1000000
Coverage Expiration Date:	06/06/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	58521
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2008
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 3430280
Policy Number:	PP 688971-01
Coverage Amount:	1000000
Coverage Expiration Date:	06/06/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	58522
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

LAMAR FOOD MARKET (Continued) **U003566345**

Financial Assurance Begin Date:	06/06/2007
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 3430352
Policy Number:	PP 688971
Coverage Amount:	1000000
Coverage Expiration Date:	06/06/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	LAMAR FOOD MARKET
Address:	10810 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74633
Finass ID:	58523
AI:	45723
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	08/25/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

HY1082 **DIRTY MARTINS PLACE** **TX UST** **U004159605**
WSW **2808 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.013 mi.
69 ft. **Site 4 of 7 in cluster HY**

Actual:
597 ft.

Focus Map:
11

UST:

Name:	DIRTY MARTINS PLACE
Address:	2808 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787053704
AI Number:	77600
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	125343862011158
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705

DIRTY MARTINS PLACE (Continued) **U004159605**

Contact Name/Title:	MARK NEMIR,
Contact Organization Name:	DIRTY MARTINS PLACE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122471297
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/06/2005
Signature Name/Title On Earliest Reg Form:	MARK NEMIR,OWNER
Application Received Date On Earliest Reg Form:	07/21/2005
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602798423
Owner Last Name:	NEMIR PROPERTIES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	482394462005067
Additional ID:	125343862011158
AI Number:	77600
Owner Effective Begin Date:	08/31/1987
State Tax ID:	12007788461
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/21/2005
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	205650
Facility ID:	119395
Ai Number:	77600
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/03/2005

DIRTY MARTINS PLACE (Continued) **U004159605**

Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	179651
UST ID:	205650
AI Number:	77600
Compartment ID:	A
Substance Stored1:	Not reported

DIRTY MARTINS PLACE (Continued) **U004159605**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/2005
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	205651
Facility ID:	119395
Ai Number:	77600
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/03/2005
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

DIRTY MARTINS PLACE (Continued) **U004159605**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	179652
UST ID:	205651
AI Number:	77600
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

DIRTY MARTINS PLACE (Continued) **U004159605**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/2005
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	205652
Facility ID:	119395
Ai Number:	77600
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/03/2005
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

DIRTY MARTINS PLACE (Continued) **U004159605**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	179653
UST ID:	205652
AI Number:	77600
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

DIRTY MARTINS PLACE (Continued) **U004159605**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/2005
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	205653
Facility ID:	119395
Ai Number:	77600
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/03/2005
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

DIRTY MARTINS PLACE (Continued) **U004159605**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	2000
UST Comprt ID:	179654
UST ID:	205653
AI Number:	77600
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

DIRTY MARTINS PLACE (Continued) **U004159605**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/2005
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	205654
Facility ID:	119395
Ai Number:	77600
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/03/2005
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

DIRTY MARTINS PLACE (Continued) **U004159605**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	179655
UST ID:	205654
AI Number:	77600
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

DIRTY MARTINS PLACE (Continued) **U004159605**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Construction Notification:
NOC ID: 20660
Facility ID: 119395
AI Number: 77600
Application Received Date: 10/07/2004
Scheduled Construction Date: 11/04/2004
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M41007025
Waiver Flag: N
Late Filing Flag: N
Form Received Date: Not reported
Signature Date On Form: Not reported
Signature Name On Form: Not reported
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 64749
General Desc Of Prop Construct: Not reported

NOC ID: 20659
Facility ID: 119395
AI Number: 77600
Application Received Date: 03/04/2005
Scheduled Construction Date: 04/03/2005
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M50304005
Waiver Flag: N
Late Filing Flag: N
Form Received Date: Not reported
Signature Date On Form: Not reported
Signature Name On Form: Not reported
Signature Company On Form: Not reported
Signature Title On Form: Not reported

DIRTY MARTINS PLACE (Continued) **U004159605**

Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 64749
General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 21836
UST ID: Not reported
NOC ID: 20660
AI Number: 77600
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000068
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 21835
UST ID: Not reported
NOC ID: 20659
AI Number: 77600
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000068
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Facility Billing Contacts:

DIRTY MARTINS PLACE (Continued) **U004159605**

Contact Organization Name:	NEMIR PROPERTIES INC
Contact Mailing Address (Delivery):	PO BOX 49369
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78765 9369
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	119395
Additional ID:	125343862011158
Princ ID:	482394462005067
AI Number:	77600
Facility Name:	DIRTY MARTINS PLACE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MARK NEMIR/

HY1083 **DIRTY MARTINS PLACE** **TX RDR** **S127542188**
WSW **2808 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
69 ft. **Site 5 of 7 in cluster HY**

Actual:
597 ft.

Focus Map:
11

RDR:

RDR ID:	14649
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	DIRTY MARTINS PLACE
Address:	2808 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/21/2005
Due Date:	9/19/2005
Tank Owner:	NEMIR PROPERTIES INC
Contact Person:	MARK NEMIR
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/2/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/2/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

IE1084 **A LONDON BRIDGE AUTO REPR** **EDR Hist Auto** **1013768114**
WNW **6406 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.013 mi.
69 ft. **Site 1 of 3 in cluster IE**

Actual:
714 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1976	SMOKEYS R V REPAIR	General Automotive Repair Shops
1977	SMOKEYS R V REPAIR	General Automotive Repair Shops
1978	SMOKEYS R V REPAIR	General Automotive Repair Shops
1979	SMOKEYS R V REPAIR	General Automotive Repair Shops
1980	SMOKEYS R V REPAIR	General Automotive Repair Shops
1982	SMOKEYS R V REPAIR	General Automotive Repair Shops
1983	SMOKEYS R V REPAIR	General Automotive Repair Shops
1990	A LONDON BRIDGE AUTO REPR	AUTOMOBILE REPAIRING
1991	LONDON BRIDGE	General Automotive Repair Shops

DF1085 **RIOS BROS TAILORS** **EDR Hist Cleaner** **1013780453**
ESE **115 7TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
69 ft. **Site 5 of 25 in cluster DF**

Actual:
499 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	RIOS BROS TAILORS	CLOTHES PRESSERS AND CLEANERS

EQ1086 **SOUTH CONGRESS OFFICE BLDG** **TX HIST UST** **S128728994**
ESE **907 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
69 ft. **Site 3 of 5 in cluster EQ**

Actual:
487 ft.

HIST UST AUSTIN:

Focus Map:
14

Name:	SOUTH CONGRESS OFFICE BLDG
Address:	907 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0312
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EQ1087 **PACIFIC SOUTHWEST BANK FSB** **TX LPST** **U003566386**
ESE **907 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.013 mi.
69 ft. **Site 4 of 5 in cluster EQ**

Actual:
487 ft.

LPST:

Focus Map:
14

Name:	PACIFIC SOUTHWEST BANK PROPERTY
Address:	907 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0062968

PACIFIC SOUTHWEST BANK FSB (Continued) **U003566386**

LPST Id:	102685
Facility Location:	907 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/13/1992
Entered Date:	05/05/1992
Reported Date:	04/13/1992
Closure Date:	05/27/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	ANN LIGGITT
Responsible Party Address:	5206 FM 1960 STE 105
Responsible Party City,St,Zip:	HOUSTON, TX 77069
Responsible Party Telephone:	713/580-1247
Reported Date:	04/13/1992
Case Start Date:	05/27/1992
Reference Number:	RN102400306
Project Manager:	HWELCH

UST:

Name:	PACIFIC SOUTHWEST BANK FSB
Address:	907 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041777
AI Number:	62968
Facility Type:	OTHER
Facility Begin Date:	05/13/1992
Facility Status:	INACTIVE
Additional ID:	141766552002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	PACIFIC SOUTHWEST BANK FSB
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7135801247
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/05/1992
Signature Name/Title On Earliest Reg Form:	ANNE S LIGGETT,ASSET MANAGER
Application Received Date On Earliest Reg Form:	05/11/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported

PACIFIC SOUTHWEST BANK FSB (Continued) **U003566386**

Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601247703
Owner Last Name:	PACIFIC SOUTHWEST BANK FSB
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	150766552002150
Additional ID:	141766552002150
AI Number:	62968
Owner Effective Begin Date:	05/13/1992
State Tax ID:	17425203894
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/11/1992
Number of Compartments:	1
Tank Capacity:	300
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145663
Facility ID:	91605
Ai Number:	62968
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/06/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

PACIFIC SOUTHWEST BANK FSB (Continued) **U003566386**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/03/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	300
UST Comprt ID:	143883
UST ID:	145663
AI Number:	62968
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

PACIFIC SOUTHWEST BANK FSB (Continued) **U003566386**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PACIFIC SOUTHWEST BANK FSB
Contact Mailing Address (Delivery):	5206 FM 1960 RD W
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77069 4420
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91605
Additional ID:	141766552002150
Princ ID:	150766552002150
AI Number:	62968
Facility Name:	PACIFIC SOUTHWEST BANK FSB
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DON BAUMANN/

EQ1088 **LON MARTIN** **TX HIST UST** **S128729205**
ESE **907 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
69 ft. **Site 5 of 5 in cluster EQ**

Actual:
487 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	LON MARTIN
Address:	907 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0174
HID UST:	174
Inspection:	02/19/2009
Due:	02/19/2012

DS1089 **AUSTIN AMERICAN STATESMAN** **RCRA NonGen / NLR** **1000412160**
WNW **308 GUADALUPE** **TX Ind. Haz Waste** **TXD008116089**
< 1/8 **AUSTIN, TX 78767**
0.013 mi.
69 ft. **Site 4 of 4 in cluster DS**

Actual:
476 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin American Statesman
Handler Address:	GUADALUPE
Handler City,State,Zip:	AUSTIN, TX 78767
EPA ID:	TXD008116089
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	CONGRESS AVE
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-445-3500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Austin American Statesman
Owner Type:	Private
Operator Name:	Austin American Statesman
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

AUSTIN AMERICAN STATESMAN (Continued) **1000412160**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	AUSTIN AMERICAN STATESMAN
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	305 CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-445-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COX ENTERPRISES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AUSTIN AMERICAN STATESMAN
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	305 CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-445-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412160**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date:	19800818
Handler Name:	AUSTIN AMERICAN-STATESMAN
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name:	AUSTIN AMERICAN STATESMAN
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	51111
NAICS Description:	NEWSPAPER PUBLISHERS

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

Ind. Haz Waste:

Name:	AUSTIN AMERICAN STATESMAN
Address:	308 GUADALUPE
City,State,Zip:	AUSTIN, TX 78767
Permit Number:	Not reported
Registration Number:	66041
Registration Initial Notification Date:	08/23/2001
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD008116089
Primary NAICS Code:	Not reported
Status Change Date:	20010823
Land Type:	PRIVATE
Description of Facility Site Location:	308 Guadalupe, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1

AUSTIN AMERICAN STATESMAN (Continued) **1000412160**

TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	COX TEXAS NEWSPAPERS LP
Contact Name:	ENVIRONMENTAL MANAGER
Contact Telephone Number:	512-4453500
Mailing Address:	305 CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787014023
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21344
Site Owner Tax ID:	582275222
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030519
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	COX TEXAS NEWSPAPERS LP
Operator Address:	305 CONGRESS AVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4453500
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	15822752224
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COX TEXAS NEWSPAPERS LP
Owner Mailing Address:	305 CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **1000412160**

Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4453500
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	15822752224
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	305 CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4453500
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	305 CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4453500
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ENVIRONMENTAL MANAGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	305 CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4453500
Contact Fax:	Not reported
Contact Email:	Not reported

BN1090 **C BYRD ROY CLN NO 2** **EDR Hist Cleaner** **1013780070**
West **2610 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
70 ft. **Site 4 of 4 in cluster BN**

Actual:
608 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1962	C BYRD ROY CLN NO 2	CLEANERS AND DYERS
1965	C BYRD ROY CLEANERS NO	CLEANERS AND DYERS

IF1091 **METRO STAR GROCERY** **TX UST** **U003040301**
WNW **10304 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.013 mi.
70 ft. **Site 1 of 2 in cluster IF**

Actual:
720 ft.

Focus Map:
3

UST:

Name:	METRO STAR GROCERY
Address:	10304 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533606
AI Number:	11312
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	621618552002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	WASIM PURI,OWNER
Contact Organization Name:	METRO STAR GROCERY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128358832
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/23/1999
Signature Name/Title On Earliest Reg Form:	WASIM PURI,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	816323882002247
Additional ID:	621618552002053
Ai Number:	11312
Operator CN:	CN601445257
Operator Name:	WASIM PURI
Operator Effective Begin Date:	09/04/2002
Operator Type:	IN
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

METRO STAR GROCERY (Continued) **U003040301**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601445257
Owner Last Name:	PURI
Owner First Name:	WASIM
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	10304 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	3606
Contact Phone Number/Ext:	1 512 8358832/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	816323882002247
Additional ID:	621618552002053
AI Number:	11312
Owner Effective Begin Date:	09/04/2002
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	WASIM PURI/
Contact Organization Name:	PURI WASIM

Tank:

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29715
Facility ID:	87016
Ai Number:	11312
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/29/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

METRO STAR GROCERY (Continued) **U003040301**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	129667
UST ID:	29715
AI Number:	11312
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y

METRO STAR GROCERY (Continued) **U003040301**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29717
Facility ID:	87016
Ai Number:	11312
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/29/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y

METRO STAR GROCERY (Continued) **U003040301**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	129669
UST ID:	29717
AI Number:	11312
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

METRO STAR GROCERY (Continued) **U003040301**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29716
Facility ID:	87016
Ai Number:	11312
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/29/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y

METRO STAR GROCERY (Continued) **U003040301**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	129668
UST ID:	29716
AI Number:	11312
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

METRO STAR GROCERY (Continued) **U003040301**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	13766
Facility ID:	87016
AI Number:	11312
Application Received Date:	07/03/2003
Scheduled Construction Date:	07/22/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30703004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	53765
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	14751
UST ID:	Not reported
NOC ID:	13766
AI Number:	11312
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000068
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

METRO STAR GROCERY (Continued) **U003040301**

Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PURI WASIM
Contact Mailing Address (Delivery):	10304 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3606
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87016
Additional ID:	621618552002053
Princ ID:	816323882002247
AI Number:	11312
Facility Name:	METRO STAR GROCERY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	WASIM PURI/

HIST UST AUSTIN:

Name:	METRO STARS
Address:	10304 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1171
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	METRO STAR GROCERY
Address:	10304 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	87016
Finass ID:	69346
AI:	11312
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/09/1991
Date Financial Assurance Form Rec:	Not reported

METRO STAR GROCERY (Continued) **U003040301**

Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	METRO STAR GROCERY
Address:	10304 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	87016
Finass ID:	69347
AI:	11312
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/09/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

IF1092 **METRO STAR GROCERY** **TX RDR** **S126523794**
WNW **10304 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
70 ft. **Site 2 of 2 in cluster IF**

Actual:
720 ft.

Focus Map:
3

RDR:

RDR ID:	12960
Facility ID:	11312
RN:	Not reported
CN:	Not reported
Name:	METRO STAR GROCERY
Address:	10304 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/23/2004
Due Date:	9/21/2004
Tank Owner:	WASIM PURI
Contact Person:	WASIM PRUI
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	5/27/2004
Project Manager:	Brandy Brooks
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RETURN LETTER SENT; NO MTBE ANALYSIS ON SOIL SAMPLES.REC LTR 7/23/04

METRO STAR GROCERY (Continued) **S126523794**

Review Coordinator: BLB
Date Release Reported: Not reported
Suspected: Not reported
Confirmed: Not reported
NOLPST Letter Date: Not reported
Date Report Returned: 5/27/2004
Region: Not reported
DKC RDR (misfiled): Not reported

CENTRAL REGISTRY:
Regulated Entity Number: RN101492791
Name: METRO STAR GROCERY
Address: 10304 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-3606
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN601445257
Customer Name: PURI, WASIM
Customer Legal Name: Not reported
Customer Ownership Type: INDIVIDUAL OWNER TYPE
Affiliation Begin Date: 9/4/2002
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN101492791
Name: METRO STAR GROCERY
Address: 10304 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-3606
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN603487331
Customer Name: METRO MARTS INCORPORATED
Customer Legal Name: Metro Marts, Incorporated
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/1988
Affiliation End Date: 12/31/1994
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN101492791
Name: METRO STAR GROCERY
Address: 10304 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-3606
Status: ACTIVE
Status Date: 2/22/2002
Customer Number: CN600775878
Customer Name: METRO SUPPLIERS INCORPORATED
Customer Legal Name: Metro Suppliers, Incorporated
Customer Ownership Type: CORPORATION

METRO STAR GROCERY (Continued) **S126523794**

Affiliation Begin Date:	1/1/1995
Affiliation End Date:	2/25/1999
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101492791
Name:	METRO STAR GROCERY
Address:	10304 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3606
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600976021
Customer Name:	TOLSON OIL CO
Customer Legal Name:	Tolson Oil Company
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1988
Affiliation End Date:	8/31/1988
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FE1093 **MONKEY SEE MONKEY DO** **EDR Hist Cleaner** **1018809467**
WNW **1712 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.013 mi.
70 ft. **Site 5 of 6 in cluster FE**

Actual:
562 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
2005	MONKEY SEE MONKEY DO	Laundry And Drycleaner Agents

BV1094 **LONGHORN TAILOR SHOP** **EDR Hist Cleaner** **1013780803**
West **2424 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
70 ft. **Site 2 of 5 in cluster BV**

Actual:
593 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	LONGHORN TAILOR SHOP	CLOTHES CLEANERS AND PRESSERS
1935	LONGHORN CLNRS	CLOTHES PRESSERS AND CLEANERS

V1095 **FINELINE SPORTSWEAR** **TX Ind. Haz Waste** **S102757014**
SE **8407A N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.013 mi.
70 ft. **Site 5 of 5 in cluster V**

Actual:
716 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	FINELINE SPORTSWEAR
Address:	8407A N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	76118
Registration Initial Notification Date:	03/23/1990
Registration Last Amendment Date:	11/05/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19900323
Land Type:	Not reported
Description of Facility Site Location:	8407A N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	FINELINE SPORTSWEAR INC
Contact Name:	DAN DAWE
Contact Telephone Number:	512-8321441
Mailing Address:	PO BOX 180087
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787180087
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30448
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030304
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

FINELINE SPORTSWEAR (Continued) **S102757014**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	FINELINE SPORTSWEAR INC
Operator Address:	PO BOX 180087
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78718
Operator Country:	UNITED STA
Operator Telephone:	1-512-8321441
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17423695109
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FINELINE SPORTSWEAR INC
Owner Mailing Address:	PO BOX 180087
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78718
Owner Country:	UNITED STA
Owner Telephone:	1-512-8321441
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17423695109
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

FINELINE SPORTSWEAR (Continued) **S102757014**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 180087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 180087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DAN DAWE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 180087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	1-512-8321441
Contact Fax:	Not reported
Contact Email:	Not reported

IG1096 **WILLIAMS WESS** **EDR Hist Cleaner** **1013784862**
West **2102 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
70 ft. **Site 1 of 2 in cluster IG**

Actual:
569 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1940	WILLIAMS WESS	CLOTHES PRESSERS AND CLEANERS
1947	WILLIAMS WESLEY W CLO CLNR	CLOTHES PRESSERS AND CLEANERS

IE1097 **THREADGILLS** **TX UST** **U002021239**
WNW **6416 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.013 mi.
70 ft. **Site 2 of 3 in cluster IE**

Actual:
714 ft.

Focus Map:
6

UST:

Name:	THREADGILLS
Address:	6416 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787524008
AI Number:	66132
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	314713362002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	MIKE MAYS,
Contact Organization Name:	THREADGILLS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124515440
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/03/1994
Signature Name/Title On Earliest Reg Form:	THOMAS M MAYS,AGENT
Application Received Date On Earliest Reg Form:	11/07/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784151
Owner Last Name:	THREADGILLS SERVICE STATION INCORPORATED
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	305713352002053
Additional ID:	314713362002053

THREADGILLS (Continued) **U002021239**

AI Number:	66132
Owner Effective Begin Date:	08/31/1987
State Tax ID:	17420427555
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	11/07/1994
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172587
Facility ID:	99022
Ai Number:	66132
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/17/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

THREADGILLS (Continued) **U002021239**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	165272
UST ID:	172587
AI Number:	66132
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

THREADGILLS (Continued) **U002021239**

Install Date:	08/31/1987
Tank Registration Date:	11/07/1994
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172588
Facility ID:	99022
Ai Number:	66132
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/17/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

THREADGILLS (Continued) **U002021239**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	165273
UST ID:	172588
AI Number:	66132
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THREADGILLS SERVICE STATION INC
Contact Mailing Address (Delivery):	6416 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 4008
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

THREADGILLS (Continued) **U002021239**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	99022
Additional ID:	314713362002053
Princ ID:	305713352002053
AI Number:	66132
Facility Name:	THREADGILLS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MIKE MAYS/

HIST UST AUSTIN:

Name:	THREADGILLS
Address:	6416 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0533
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IE1098 **THREADGILLS FILL STA** **EDR Hist Auto** **1013767710**
WNW **6416 LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
70 ft. **Site 3 of 3 in cluster IE**

Actual:
714 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1953	THREADGILLS FILL STA	GASOLINE STATIONS

IH1099 **MASON STEAM LNDRY** **EDR Hist Cleaner** **1013787428**
East **2006 SPEEDWAY** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 1 of 5 in cluster IH**

Actual:
538 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1947	MASON STEAM LNDRY	LAUNDRIES

I1100 WNW < 1/8 0.013 mi. 71 ft. | **PHILLIPS 66 SS 26286**
11100 N LAMAR BLVD
AUSTIN, TX 78753
Site 3 of 6 in cluster I

TX LPST **S107638206**
TX SPILLS **N/A**

Actual: 775 ft.

Focus Map: 3

LPST:

Name:	PHILLIPS 66 SS 26286
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0010901
LPST Id:	099432
Facility Location:	N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/28/1991
Entered Date:	07/09/1991
Reported Date:	06/28/1991
Closure Date:	02/18/1992
Priority:	4B - MINOR SURFACE WATER IMPACT
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SURFACE WATER IMPACT
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2/1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	THOMAS KOSEL
Responsible Party Address:	6 E 13TH ST ADAMS BLDG
Responsible Party City,St,Zip:	LDGBARTLESVILLE, OK 74004
Responsible Party Telephone:	918/661-7439
Reported Date:	06/28/1991
Case Start Date:	02/18/1992
Reference Number:	RN101431609
Project Manager:	HWELCH

SPILLS:

Name:	N LAMAR SERVICE STATION - JN
Address:	11100 N LAMAR
City,State,Zip:	AUSTIN, TX 78753
Incident Number:	2958
Facility Id:	RN101431609
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	Not reported
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11 - AUSTIN
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported

PHILLIPS 66 SS 26286 (Continued) **S107638206**

Adequate Clean:	Not reported
Classification:	unknown
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	Not reported
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	No Incident Type
Near City Name:	AUSTIN
Importance Level:	5
Received Date:	06/14/2002
Start Date:	12/30/1899
Status Date:	07/01/2002
Media Name:	Not reported
Customer:	SCHARFE, DENNIS F
Effect:	GENERAL
Num Complaining:	1
Frequency:	CURRENT
Nature:	OTHER
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Closed
Disputed Status:	Not reported
Disputed Date:	01/01/1900
Comments:	This complaint was received on 06/14/2002 at 9:45 a.m.
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

I1101 **PHILLIPS SIXTY SIX STATION GAS STA** **EDR Hist Auto** **1013761835**
WNW **11100 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.013 mi.
71 ft. **Site 4 of 6 in cluster I**

Actual:
775 ft.
EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1971	KRAMER LANE 66	Gasoline Service Stations
1972	KRAMER LANE 66	Gasoline Service Stations
1973	KRAMER LANE 66	Gasoline Service Stations
1974	KRAMER LANE 66	Gasoline Service Stations
1975	KRAMER LANE 66	Gasoline Service Stations
1976	KRAMER LANE 66	Gasoline Service Stations
1977	KRAMER LANE 66	Gasoline Service Stations
1978	KRAMER LANE 66	Gasoline Service Stations
1979	KRAMER LANE 66	Gasoline Service Stations
1980	WAY LO GAS ST	GASOLINE STATIONS

PHILLIPS SIXTY SIX STATION GAS STA (Continued) **1013761835**

1986	NORTH LAMAR 66	Gasoline Service Stations
1987	NORTH LAMAR 66	Gasoline Service Stations
1988	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
1989	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations, NEC
1990	PHILLIPS SIXTY SIX STATION GAS	GASOLINE STATIONS
1990	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations, NEC
1991	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations, NEC
1992	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1993	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1994	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1995	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1996	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1997	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1998	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
1999	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2000	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2001	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2002	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2003	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2004	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2005	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2006	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2008	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2009	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2010	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2011	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2012	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2013	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC
2014	SCHARFE DENNIS F BUILDER INC	Gasoline Service Stations, NEC

I1102 **NORTH LAMAR SERVICE STATION JN** **TX UST** **U001246897**
WNW **11100 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.013 mi.
71 ft. **Site 5 of 6 in cluster I**

Actual:
775 ft.

Focus Map:
3

UST:

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533047
AI Number:	10901
Facility Type:	RETAIL
Facility Begin Date:	12/01/1971
Facility Status:	ACTIVE
Additional ID:	86402942002154
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	JUNG NAM HAN,OWNER
Contact Organization Name:	NORTH LAMAR SERVICE STATION JN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128372701
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/25/2022
Signature Name/Title On Earliest Reg Form:	ALI KARIM,REPRESENTATIVE
Application Received Date On Earliest Reg Form:	02/25/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	939282722005348
Additional ID:	86402942002154
Ai Number:	10901
Operator CN:	CN602952509
Operator Name:	WON YOUNG AMERICA INC
Operator Effective Begin Date:	10/17/2005
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	JUNG N HAN/
Contact Organization Name:	WON YOUNG AMERICA INC
Contact Mailing Address (Delivery):	11100 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	8372701
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	NLAMARSERVICE@GMAIL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602952509
Owner Last Name:	WON YOUNG AMERICA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	11100 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 8372701/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	NLAMARSERVICE@GMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	939282722005348
Additional ID:	86402942002154

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

AI Number:	10901
Owner Effective Begin Date:	10/17/2005
State Tax ID:	17706383332
Contact Role:	OWNOPRCON
Contact Name/Title:	JUNG N HAN/
Contact Organization Name:	WON YOUNG AMERICA INC

Self Certification:

Self Cert ID:	91891
Cert ID:	384746
AI Number:	10901
Self Certification Date:	02/22/2023
Signature Name/Title:	MURAD SAMNANI REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91891
Cert ID:	367703
AI Number:	10901
Self Certification Date:	02/25/2022
Signature Name/Title:	ALI KARIM REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91891
Cert ID:	351641
AI Number:	10901
Self Certification Date:	03/05/2021
Signature Name/Title:	JUNG N HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	334126
AI Number:	10901
Self Certification Date:	02/20/2020
Signature Name/Title:	JUNG HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	317986
AI Number:	10901
Self Certification Date:	02/10/2019
Signature Name/Title:	JUNG HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	300615
AI Number:	10901
Self Certification Date:	02/22/2018
Signature Name/Title:	JUNG HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/28/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	281980
AI Number:	10901
Self Certification Date:	01/11/2017
Signature Name/Title:	JUNG HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	266237
AI Number:	10901
Self Certification Date:	02/10/2016
Signature Name/Title:	JUNG NAN HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	250864
AI Number:	10901
Self Certification Date:	02/20/2015
Signature Name/Title:	JUNG N HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/29/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	234963
AI Number:	10901
Self Certification Date:	02/24/2014
Signature Name/Title:	JUNG N HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	91891
Cert ID:	149331
AI Number:	10901
Self Certification Date:	12/21/2012
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149330
AI Number:	10901
Self Certification Date:	02/02/2012
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/28/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149329
AI Number:	10901
Self Certification Date:	02/10/2011
Signature Name/Title:	MY HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149328
AI Number:	10901
Self Certification Date:	01/20/2010
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149040
AI Number:	10901
Self Certification Date:	01/20/2009
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/28/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149039
AI Number:	10901
Self Certification Date:	01/04/2008
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149038
AI Number:	10901
Self Certification Date:	12/28/2006
Signature Name/Title:	JUNG NAM HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149037
AI Number:	10901
Self Certification Date:	10/18/2005
Signature Name/Title:	JUNG NAM HAN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	02/28/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149036
AI Number:	10901
Self Certification Date:	10/17/2005
Signature Name/Title:	JUNG N HAN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149035
AI Number:	10901
Self Certification Date:	09/12/2005
Signature Name/Title:	ROBERT SCHARFE MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149034
AI Number:	10901
Self Certification Date:	09/22/2004
Signature Name/Title:	ROBERT SCHARFE MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149033
AI Number:	10901
Self Certification Date:	09/02/2003
Signature Name/Title:	ROBERT SCHARFE MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149032
AI Number:	10901
Self Certification Date:	08/27/2002
Signature Name/Title:	ROBERT SCHARFE OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91891
Cert ID:	149031
AI Number:	10901
Self Certification Date:	12/28/2000
Signature Name/Title:	DENNIS F SCHARFE PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	28630
Facility ID:	91891
Ai Number:	10901
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1971
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	140455
UST ID:	28630
AI Number:	10901
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Install Date:	12/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	28633
Facility ID:	91891
Ai Number:	10901
Tank Id:	4
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	06/20/2017
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	140458
UST ID:	28633
AI Number:	10901
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	12/01/1971

Install Date:	12/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	28632

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Facility ID:	91891
Ai Number:	10901
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1974
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	8000

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

UST Comprt ID:	140457
UST ID:	28632
AI Number:	10901
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	28631
Facility ID:	91891
Ai Number:	10901
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1971
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	140456
UST ID:	28631
AI Number:	10901
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	12/01/1986

Facility Billing Contacts:

Contact Organization Name:	WON YOUNG AMERICA INC
Contact Mailing Address (Delivery):	11100 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3047
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91891
Additional ID:	86402942002154
Princ ID:	939282722005348
AI Number:	10901
Facility Name:	NORTH LAMAR SERVICE STATION JN
AR Number:	64892
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	JUNG NAM HAN/

HIST UST AUSTIN:

Name:	NORTH LAMAR SERVICE STATION
Address:	11100 N LAMAR BLVD

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

City,State,Zip:	AUSTIN, TX
Id UST:	580
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	281890
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/09/2023
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 7224994
Policy Number:	04-TOP-005006757
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/09/2024
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	265307
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2021
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000024491
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	247613
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2020
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000015076
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	228993
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2019
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000006159
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	211652
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2018
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000109282
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	191804
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2017
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7724994
Policy Number:	04TO000103867
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	175099
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2016
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00099327

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	157953
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2015
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00095027
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	141851
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/10/2014
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091793
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/10/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Facility ID:	91891
Finass ID:	126126
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2013
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18455
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	10127
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2012
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18455
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/09/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	75048
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2011
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18455
Coverage Amount:	1000000
Coverage Expiration Date:	10/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	75049
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2009
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18455
Coverage Amount:	1000000
Coverage Expiration Date:	10/19/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	75050
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2008
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18455
Coverage Amount:	1000000
Coverage Expiration Date:	10/19/2009
Ins Premium Pre-Paid For Entire Yr:	No

NORTH LAMAR SERVICE STATION JN (Continued) **U001246897**

Proof of Financial Assurance:	No

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	75051
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2007
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 512 8372701
Policy Number:	18455
Coverage Amount:	1000000
Coverage Expiration Date:	10/19/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	NORTH LAMAR SERVICE STATION JN
Address:	11100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	91891
Finass ID:	75052
AI:	10901
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1989
Date Financial Assurance Form Rec:	02/25/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

I1103 WNW < 1/8 0.013 mi. 71 ft. | **NORTH LAMAR PHILLIPS 66**
11100 NORTH LAMAR
AUSTIN, TX
Site 6 of 6 in cluster I | **TX RDR** | **S127524152**
N/A

Actual: 775 ft.
Focus Map: 3

RDR:

RDR ID:	220
Facility ID:	10901
RN:	Not reported
CN:	Not reported
Name:	NORTH LAMAR PHILLIPS 66
Address:	11100 NORTH LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	DENNIS SCHARFE
Contact Person:	ROBERT SCHARFE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	11/6/1998
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 9
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	11/6/1998
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DH1104 NNE < 1/8 0.013 mi. 71 ft. | **DICKERSON CLEANING**
111 6TH W
AUSTIN, TX
Site 10 of 16 in cluster DH | **EDR Hist Cleaner** | **1013782825**
N/A

Actual: 494 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1935	DICKERSON CLEANING	CLOTHES PRESSERS AND CLEANERS
1940	DICKERSON CLEANING	CLOTHES PRESSERS AND CLEANERS

IH1105 East < 1/8 0.013 mi. 71 ft. | **UNIVERSITY CLNS**
2004 SPEEDWAY
AUSTIN, TX
Site 2 of 5 in cluster IH | **EDR Hist Cleaner** | **1013781035**
N/A

Actual: 538 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1940	UNIVERSITY CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	UNIVERSITY CLEANERS	CLOTHES PRESSERS AND CLEANERS

UNIVERSITY CLNS (Continued) **1013781035**

1953	UNIVERSITY CLNS	CLEANERS AND DYERS
1958	UNIVERSITY CLN	CLEANERS AND DYERS
1962	UNIVERSITY CLNS	CLEANERS AND DYERS
1965	UNIVERSITY CLEANERS	CLEANERS AND DYERS

FE1106 **D. F. WRIGHT** **TX HIST UST** **S111678619**
WNW **1710 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 6 of 6 in cluster FE**

Actual:
561 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	D. F. WRIGHT
Address:	1710 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0091
HID UST:	91
Inspection:	Not reported
Due:	06/01/2012

BV1107 **UNIVERSITY SERVICE CO FILLING STA** **EDR Hist Auto** **1013767845**
West **2412 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 3 of 5 in cluster BV**

Actual:
592 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	UNIVERSITY SERVICE CO FILLING S	GASOLINE AND OIL SERVICE STATIONS

ES1108 **C A SCHUTZE AGENCY** **TX RDR** **S127541921**
ESE **1101 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 5 of 5 in cluster ES**

Actual:
496 ft.

Focus Map:
14

RDR:

RDR ID:	10629
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	C A SCHUTZE AGENCY
Address:	1101 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/3/2000
Due Date:	10/2/2000
Tank Owner:	C A SCHUTZE AGENCY
Contact Person:	STEVE SCHUTZE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	11/29/2000
Project Manager:	Julia Goree
Team:	#N/A

C A SCHUTZE AGENCY (Continued) **S127541921**

New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NO LEAKER PENDING 09/14/2000
Review Coordinator:	JMG
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	11/29/2000
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

ER1109 **TWOMEY AUTO WORKS** **RCRA NonGen / NLR** **1004783473**
ESE **1009 S CONGRESS AVE** **FINDS** **TX0000241430**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.013 mi.
71 ft. **Site 4 of 8 in cluster ER**

Actual:
497 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Twomey Auto Works
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TX0000241430
Contact Name:	RICH LOSIEWICZ
Contact Address:	S CONGRESS AVE
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-444-0606
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Twomey Auto Works
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

TWOMEY AUTO WORKS (Continued) **1004783473**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

TWOMEY AUTO WORKS (Continued) **1004783473**

Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SID SAMPSON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1011 S CONGRESS
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-448-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TWOMEY AUTO WORKS	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	1009 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19940421
Handler Name: TWOMEY AUTO WORKS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

TWOMEY AUTO WORKS (Continued) **1004783473**

Electronic Manifest Broker: Not reported

Receive Date: 20010129
Handler Name: TWOMEY AUTO WORKS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: TWOMEY AUTO WORKS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005015321

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

TWOMEY AUTO WORKS (Continued) **1004783473**

Envid:	1004783473
Registry ID:	110005015321
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005015321
Name:	TWOMEY AUTO WORKS
Address:	1009 S CONGRESS AVE
City,State,Zip:	AUTIN, TX 78704

ER1110 **FORMER TWOMEYS AUTO** **TX RDR** **S127541226**
ESE **1009 S CONGRESS AVE** **N/A**
< 1/8 **AUTIN, TX**
0.013 mi.
71 ft. **Site 5 of 8 in cluster ER**

Actual:
497 ft.

Focus Map:
14

RDR:

RDR ID:	26510
Facility ID:	90188
RN:	Not reported
CN:	Not reported
Name:	FORMER TWOMEYS AUTO
Address:	1009 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/27/2018
Due Date:	2/25/2019
Tank Owner:	ALLISON SAMPSON MILLER PARTNER
Contact Person:	KEVIN TISEO
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/22/2019
Project Manager:	Ronnie Eason
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

ER1111 **TWOMEY AUTO WORKS AUSTIN TX** **TX TANKS** **S104855354**
ESE **1009 S CONGRESS AVE** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX Ind. Haz Waste**
0.013 mi. **TX CENTRAL REGISTRY**
71 ft. **Site 6 of 8 in cluster ER**

Actual:
497 ft.

Focus Map:
14

TANKS:

Facility ID:	135294
Name:	FORMER TWOMEY AUTO GARAGE
Address:	1009 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041787
Total UST:	Not reported
Additional ID:	783491012018276
AI Number:	90188

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	1009 S CONGRESS AVE AUSTIN TX
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

ASBESTOS:

Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/09/06
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	09/06/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018006546
File Number:	33874
License Status Description:	Paid
Expiration Date:	09/14/2018
Original Date:	08/20/2018
Rank Effective Date:	08/20/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	11840
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms
Violation:	Not reported
Complaint Date:	09/07/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/11/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/11/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms
Violation:	Not reported
Complaint Date:	09/14/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/11/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/11/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms
Violation:	Not reported
Complaint Date:	09/07/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/04/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/04/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/06/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms
Violation:	Not reported
Complaint Date:	09/14/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/04/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/04/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms
Violation:	Not reported
Complaint Date:	09/06/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/20/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/20/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/04/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER TOWMEY AUTOMOTIVE
Address:	1009 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/20/2019
Reason for Inspection:	Randy Timms

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Violation:	Not reported
Complaint Date:	09/14/2018
Notification Number:	2018006546
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/20/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/20/2018
Certification Statement Phone:	817-305-6591
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	10
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/07/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	TWOMEY AUTO WORKS AUSTIN TX
Address:	1009 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	81908
Registration Initial Notification Date:	04/19/1994
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TX0000241430
Primary NAICS Code:	811121
Status Change Date:	19940419
Land Type:	Not reported
Description of Facility Site Location:	1009 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TWOMEY AUTO WORKS
Contact Name:	RICH LOSIEWICZ
Contact Telephone Number:	512-4440606
Mailing Address:	1009 S CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787041787
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	37001
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040426
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	TWOMEY AUTO WORKS
Owner Mailing Address:	1009 S CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	30007688697
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1009 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RICH LOSIEWICZ
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	1009 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4440606
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	79450
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	MEK, Toluene, Xylene & Waste Paint Material
Standard Industrial Code:	75320
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269906
Customer Name:	TWOMEY AUTO WORKS
Customer Legal Name:	Twomey Auto Works, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269906
Customer Name:	TWOMEY AUTO WORKS
Customer Legal Name:	Twomey Auto Works, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269906
Customer Name:	TWOMEY AUTO WORKS
Customer Legal Name:	Twomey Auto Works, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605577386
Customer Name:	MILLER, ALLISON SAMPSON
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	10/8/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605577386
Customer Name:	MILLER, ALLISON SAMPSON
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	10/8/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########

TWOMEY AUTO WORKS AUSTIN TX (Continued) **S104855354**

Customer Number:	CN605577386
Customer Name:	MILLER, ALLISON SAMPSON
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	10/8/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269906
Customer Name:	TWOMEY AUTO WORKS
Customer Legal Name:	Twomey Auto Works, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100559103
Name:	TWOMEY AUTO WORKS - AUSTIN TX
Address:	1009 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1787
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605577386
Customer Name:	MILLER, ALLISON SAMPSON
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	10/8/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	1009 S Congress Ave, Austin, TX

ER1112 **TWOMEY AUTO** **TX HIST UST** **S128728775**
ESE **1009 S. CONGRESS AVE.** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 7 of 8 in cluster ER**

Actual:
497 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	TWOMEY AUTO
Address:	1009 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX
Id UST:	3423

TWOMEY AUTO (Continued) **S128728775**

HID UST: Not reported
Inspection: Not reported
Due: Not reported

ER1113 **MAGNOLIA PETROLEUM CO.** **TX HIST UST** **S128729466**
ESE **1009 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 8 of 8 in cluster ER**

Actual:
497 ft.

Focus Map:
14

HIST UST AUSTIN:
Name: MAGNOLIA PETROLEUM CO.
Address: 1009 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: H0905
HID UST: 905
Inspection: Not reported
Due: 06/01/2012

U1114 **LUU AUTO ELECTRIC** **TX HIST UST** **S127543006**
SE **8603 N. LAMAR BLVD.** **TX RDR** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 3 of 5 in cluster U**

Actual:
691 ft.

Focus Map:
6

HIST UST AUSTIN:
Name: THE DIP STICK
Address: 8603 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: C0686
HID UST: Not reported
Inspection: Not reported
Due: Not reported

RDR:
RDR ID: 11785
Facility ID: 0
RN: Not reported
CN: Not reported
Name: LUU AUTO ELECTRIC
Address: 8603 N. LAMAR BLVD.
City,State,Zip: AUSTIN, TX
Date Report Received: 12/10/1999
Due Date: 2/8/2000
Tank Owner: MRS. PHUONG LUU
Contact Person: MRS. PHUONG LUU
Report: RDR
Latest TCEQ Letter: No Leaker
Date of Latest TCEQ Letter: 3/9/2000
Project Manager: Michelle Sefcik
Team: #N/A
New LPST Number: Not reported
Pre-Existing LPST Number: Not reported

LUU AUTO ELECTRIC (Continued) **S127543006**

Comments:	NO LEAKER
Review Coordinator:	MDS
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/9/2000
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

U1115 **COURTNEY SIXTY SIX** **EDR Hist Auto** **1013753991**
SE **8603 LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 4 of 5 in cluster U**

Actual:
691 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1953	PRUETTS SERVICE	GASOLINE STATIONS
1958	COURTNEY SIXTY SIX	GASOLINE STATIONS
1969	AUTOMOTIVE ELECTRIC	Motor Vehicle Supplies And New Parts
1970	AUTOMOTIVE ELECTRIC OF AUSTIN A	AUTOMOBILE REPAIRING
1970	AUTOMOTIVE ELECTRIC	Motor Vehicle Supplies And New Parts
2000	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2001	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2002	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2003	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2004	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2005	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2006	LUU AUTO & ELECTRIC	Automotive Repair Shops, NEC
2013	SAN FERNANDO AUTO SVC	General Automotive Repair Shops
2014	SAN FERNANDO AUTO SVC	General Automotive Repair Shops

Z1116 **LAMAR CORNER STORE** **TX LPST** **U001247253**
ESE **7545 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX HIST UST**
0.013 mi. **TX Financial Assurance**
71 ft. **Site 6 of 9 in cluster Z** **TX RDR**

Actual:
754 ft.

Focus Map:
6

LPST:

Name:	BALLARDS DRIVE IN GROCERY 5
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78700
Facility ID:	0011311
LPST Id:	091422
Facility Location:	7545 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/13/1987
Entered Date:	08/13/1987
Reported Date:	08/13/1987
Closure Date:	01/14/1988
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED

LAMAR CORNER STORE (Continued) **U001247253**

Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JERRY BALLARD
Responsible Party Address:	1220 S LAMAR
Responsible Party City,St,Zip:	AUSTIN, TX 78704
Responsible Party Telephone:	512/442-4790
Reported Date:	08/13/1987
Case Start Date:	01/14/1988
Reference Number:	RN101375996
Project Manager:	HWELCH

UST:

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787521345
AI Number:	11311
Facility Type:	RETAIL
Facility Begin Date:	08/01/1987
Facility Status:	ACTIVE
Additional ID:	874694062002068
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	SULTAN MAREDIA,MGR
Contact Organization Name:	LAMAR CORNER STORE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124535702
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/07/2020
Signature Name/Title On Earliest Reg Form:	SULTAN MAREDIA,MGR
Application Received Date On Earliest Reg Form:	05/22/2020
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	683514492012256
Additional ID:	874694062002068
Ai Number:	11311
Operator CN:	CN604139105
Operator Name:	SULTANALI T MOMIN
Operator Effective Begin Date:	05/20/2007
Operator Type:	IN

LAMAR CORNER STORE (Continued) **U001247253**

Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602511537
Owner Last Name:	SUPER LAMAR INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	557354312003339
Additional ID:	874694062002068
AI Number:	11311
Owner Effective Begin Date:	05/19/2007
State Tax ID:	18205771019
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	42486
Cert ID:	337061
AI Number:	11311
Self Certification Date:	04/07/2020
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2021

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	322260
AI Number:	11311
Self Certification Date:	06/24/2019
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	305563
AI Number:	11311
Self Certification Date:	06/05/2018
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	286498
AI Number:	11311
Self Certification Date:	04/20/2017
Signature Name/Title:	SULTAN MAREDIA MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	278857
AI Number:	11311
Self Certification Date:	10/25/2016
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	270296
AI Number:	11311
Self Certification Date:	04/07/2016
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	252750
AI Number:	11311
Self Certification Date:	04/28/2015
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	236885
AI Number:	11311
Self Certification Date:	05/08/2014
Signature Name/Title:	SULTAN MOMIN MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42486
Cert ID:	218706
AI Number:	11311
Self Certification Date:	04/08/2013
Signature Name/Title:	SULTAN ALI MOMIN MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	42486
Cert ID:	17060
AI Number:	11311
Self Certification Date:	04/10/2012
Signature Name/Title:	SULTAN ALI MOMIN MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17059
AI Number:	11311
Self Certification Date:	04/25/2011
Signature Name/Title:	SULTANALI MOMIN MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17058
AI Number:	11311
Self Certification Date:	04/09/2010
Signature Name/Title:	SULTAN MAREDIA MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17057
AI Number:	11311
Self Certification Date:	03/19/2009
Signature Name/Title:	MOIZ ALI MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17056
AI Number:	11311
Self Certification Date:	05/06/2008
Signature Name/Title:	MOIZ ALI MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17055
AI Number:	11311
Self Certification Date:	04/12/2007
Signature Name/Title:	SULTAN MAREDIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17054
AI Number:	11311
Self Certification Date:	06/05/2006
Signature Name/Title:	SULTAN S MAREDIA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17053
AI Number:	11311
Self Certification Date:	03/21/2005
Signature Name/Title:	SULTANALI T MOMIN PRESIDENT
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17052
AI Number:	11311
Self Certification Date:	04/14/2004
Signature Name/Title:	SULTAN S MAREDIA MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17051
AI Number:	11311
Self Certification Date:	07/10/2003
Signature Name/Title:	SULTAN S MAREDIA
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004

LAMAR CORNER STORE (Continued) **U001247253**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17050
AI Number:	11311
Self Certification Date:	06/02/2002
Signature Name/Title:	RAFIQ MOHAMMAD DHUKA
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42486
Cert ID:	17049
AI Number:	11311
Self Certification Date:	01/22/2001
Signature Name/Title:	RAFIQ MOHAMMAD N DHUKA OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29709
Facility ID:	42486
Ai Number:	11311
Tank Id:	1A

LAMAR CORNER STORE (Continued) **U001247253**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1A
Tank Capacity:	4000
UST Comprt ID:	13088
UST ID:	29709
AI Number:	11311

LAMAR CORNER STORE (Continued) **U001247253**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29710
Facility ID:	42486
Ai Number:	11311
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

LAMAR CORNER STORE (Continued) **U001247253**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2A
Tank Capacity:	4000
UST Comprt ID:	13089
UST ID:	29710
AI Number:	11311
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

LAMAR CORNER STORE (Continued) **U001247253**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	29714
Facility ID:	42486
Ai Number:	11311
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

LAMAR CORNER STORE (Continued) **U001247253**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	13093
UST ID:	29714
AI Number:	11311
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

LAMAR CORNER STORE (Continued) **U001247253**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	08/01/1987

Install Date:	08/01/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	29712
Facility ID:	42486
Ai Number:	11311
Tank Id:	2
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	10/25/2016
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

LAMAR CORNER STORE (Continued) **U001247253**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	13091
UST ID:	29712
AI Number:	11311
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

LAMAR CORNER STORE (Continued) **U001247253**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	08/01/1987

Install Date:	08/01/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	29713
Facility ID:	42486
Ai Number:	11311
Tank Id:	3
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	10/25/2016
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

LAMAR CORNER STORE (Continued) **U001247253**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	13092
UST ID:	29713
AI Number:	11311
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

LAMAR CORNER STORE (Continued) **U001247253**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	08/01/1987

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29711
Facility ID:	42486
Ai Number:	11311
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

LAMAR CORNER STORE (Continued) **U001247253**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3A
Tank Capacity:	3000
UST Comprt ID:	13090
UST ID:	29711
AI Number:	11311
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

LAMAR CORNER STORE (Continued) **U001247253**

Contact Organization Name:	SUPER LAMAR INC
Contact Mailing Address (Delivery):	7545 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 1345
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	42486
Additional ID:	874694062002068
Princ ID:	557354312003339
AI Number:	11311
Facility Name:	LAMAR CORNER STORE
AR Number:	61345
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1173
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	231904
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2019
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000004111
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD

LAMAR CORNER STORE (Continued) **U001247253**

City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	215885
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2018
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000107665
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	198854
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2017
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000102647
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	171176
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y

LAMAR CORNER STORE (Continued) **U001247253**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2016
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00098067
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	179473
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2016
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00098067
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	162654
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2015
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00093821
Coverage Amount:	1,000,000

LAMAR CORNER STORE (Continued) **U001247253**

Coverage Expiration Date:	08/23/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	143894
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2014
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00089688
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	128407
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2013
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00085637
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486

LAMAR CORNER STORE (Continued) **U001247253**

Finass ID:	107178
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2012
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00081703
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	1384
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2011
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04-TO-00077931
Coverage Amount:	1000000
Coverage Expiration Date:	08/23/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23745
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

LAMAR CORNER STORE (Continued) **U001247253**

Financial Assurance Begin Date:	08/23/2010
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04TO00074168
Coverage Amount:	1000000
Coverage Expiration Date:	08/23/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23746
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2009
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04TO00070975
Coverage Amount:	1000000
Coverage Expiration Date:	08/23/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23747
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2008
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04TO00068969
Coverage Amount:	1000000
Coverage Expiration Date:	08/23/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

LAMAR CORNER STORE (Continued) **U001247253**

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23748
AI:	11311
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2007
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04TO00066177
Coverage Amount:	1000000
Coverage Expiration Date:	08/15/2008
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23749
AI:	11311
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	42486
Finass ID:	23750
AI:	11311
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y

LAMAR CORNER STORE (Continued) **U001247253**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/22/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	24159
Facility ID:	11311
RN:	Not reported
CN:	Not reported
Name:	LAMAR CORNER STORE
Address:	7545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/3/2017
Due Date:	6/2/2017
Tank Owner:	SUPER LAMAR INC
Contact Person:	SULTAN MAREDIA
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/26/2017
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR REC 11/3/16; MORE INFO SENT 4/3/17
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DH1117 **NEWSOME FRED C CLNR** **EDR Hist Cleaner** **1013780509**
NNE **106 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.013 mi.
71 ft. **Site 11 of 16 in cluster DH**

Actual:
494 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	NEWSOME FRED C CLNR	CLOTHES CLEANERS AND PRESSERS

IH1118 East < 1/8 0.013 mi. 71 ft. | **WILLIAMS WESS 2014 SPEEDWAY AUSTIN, TX** | **EDR Hist Cleaner** | **1013787479 N/A**

Site 3 of 5 in cluster IH

Actual: 538 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1958	WILLIAMS WESS	LAUNDRIES
1962	WILLIAMS WESS	LAUNDRIES
1965	WILLIAMS WESS LAUNDRY	LAUNDRIES

1119 SSW < 1/8 0.013 mi. 71 ft. | **FIRE STATION 22 5307 E RIVERSIDE DR AUSTIN, TX 78741** | **TX UST TX HIST UST** | **U001542541 N/A**

Actual: 507 ft.

Focus Map: 15

UST:

Name:	FIRE STATION 22
Address:	5307 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787414808
AI Number:	18167
Facility Type:	UNKNOWN
Facility Begin Date:	09/02/1986
Facility Status:	INACTIVE
Additional ID:	782758622002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	C E MCCAMANT,TECH
Contact Organization Name:	FIRE STATION 22
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129281492
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	J A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI

FIRE STATION 22 (Continued) **U001542541**

Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	782758622002138
AI Number:	18167
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1300
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46981
Facility ID:	37571
Ai Number:	18167
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/16/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

FIRE STATION 22 (Continued) **U001542541**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1300
UST Comprt ID:	310
UST ID:	46981
AI Number:	18167
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y

FIRE STATION 22 (Continued) **U001542541**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7029
Cert ID:	317459
UST Comprt ID:	919329
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	361631
UST Comprt ID:	1052399
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	227178
UST Comprt ID:	651951
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	310081
UST Comprt ID:	897332
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160548
UST Comprt ID:	472569
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160553
UST Comprt ID:	472562
UST ID:	154572

FIRE STATION 22 (Continued) **U001542541**

AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	294285
UST Comprt ID:	849847
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160549
UST Comprt ID:	472566
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160557
UST Comprt ID:	472558
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	276838
UST Comprt ID:	798101
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160550
UST Comprt ID:	472565
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160554
UST Comprt ID:	472561
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	260009
UST Comprt ID:	748396
UST ID:	154572
AI Number:	18167

FIRE STATION 22 (Continued) **U001542541**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160551
UST Comprt ID:	472564
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160556
UST Comprt ID:	472559
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	243500
UST Comprt ID:	699690
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160552
UST Comprt ID:	472563
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160546
UST Comprt ID:	472567
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	327144
UST Comprt ID:	948351
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160555
UST Comprt ID:	472560
UST ID:	154572
AI Number:	18167
Tank ID:	3

FIRE STATION 22 (Continued) **U001542541**

Compartment ID:	A
Self Cert ID:	7029
Cert ID:	378191
UST Comprt ID:	1102704
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	345164
UST Comprt ID:	1002855
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7029
Cert ID:	160547
UST Comprt ID:	472568
UST ID:	154572
AI Number:	18167
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37571
Additional ID:	782758622002138
Princ ID:	840354562001227
AI Number:	18167
Facility Name:	FIRE STATION 22
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COA AFD FIRE STATION #22
Address:	5307 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	184
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DH1120 NNE < 1/8 0.013 mi. 71 ft. | **PARIS CLEANING PARLOR**
102 6TH W
AUSTIN, TX
Site 12 of 16 in cluster DH | **EDR Hist Cleaner** | **1013781499**
N/A

Actual: 494 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1922	PARIS CLEANING PARLOR	CLOTHES CLEANERS AND PRESSERS
1929	DICKERSON CLEANING CO	CLOTHES CLEANERS AND PRESSERS

1121 WNW < 1/8 0.014 mi. 72 ft. | **VACANT PROPERTY**
11902 N LAMAR BLVD
AUSTIN, TX 78753 | **TX LPST**
TX UST
TX HIST UST | **U003566389**
N/A

Actual: 706 ft.

Focus Map: 4

LPST:

Name:	VACANT PROPERTY
Address:	11902 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0063416
LPST Id:	104576
Facility Location:	11902 NORTH LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/10/1992
Entered Date:	10/13/1992
Reported Date:	09/10/1992
Closure Date:	11/10/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	LARRY BLACK
Responsible Party Address:	100 W HOUSTON
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78205
Responsible Party Telephone:	512/220-5300
Reported Date:	09/10/1992
Case Start Date:	11/10/1992
Reference Number:	RN101696896
Project Manager:	HWELCH

UST:

Name:	VACANT PROPERTY
Address:	11902 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532143
AI Number:	63416
Facility Type:	Not reported
Facility Begin Date:	08/03/1992
Facility Status:	INACTIVE
Additional ID:	351393622002075
Facility Exempt Status:	N
Records Off-Site:	No

VACANT PROPERTY (Continued) **U003566389**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	DALE CURRY,
Contact Organization Name:	VACANT PROPERTY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123148300
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/29/1992
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,REGIONAL MANAGER
Application Received Date On Earliest Reg Form:	07/31/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600916803
Owner Last Name:	THE FROST NATIONAL BANK OF S A
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	341393612002075
Additional ID:	351393622002075
AI Number:	63416
Owner Effective Begin Date:	08/03/1992
State Tax ID:	17463010664
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/31/1992
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N

VACANT PROPERTY (Continued) **U003566389**

Pipe Type:	Not reported
UST ID:	146395
Facility ID:	94336
Ai Number:	63416
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/02/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

VACANT PROPERTY (Continued) **U003566389**

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	163844
UST ID:	146395
AI Number:	63416
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE FROST NATIONAL BANK OF S A
Contact Mailing Address (Delivery):	100 W HOUSTON ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78205 1414
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94336
Additional ID:	351393622002075
Princ ID:	341393612002075

VACANT PROPERTY (Continued) **U003566389**

AI Number: 63416
Facility Name: VACANT PROPERTY
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: WAYDE ANDERSON/

HIST UST AUSTIN:
Name: ABANDONED SITE
Address: 11902 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: C0346
HID UST: Not reported
Inspection: Not reported
Due: Not reported

DH1122 **SMITH KELLEY TAILOR** **EDR Hist Cleaner** **1013778263**
NNE **109 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
72 ft. **Site 13 of 16 in cluster DH**

Actual:
494 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	SMITH KELLEY TAILOR	CLOTHES CLEANERS AND PRESSERS

1123 **L. L. EARNEST** **TX HIST UST** **S111678715**
WNW **1822 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
72 ft.

Actual:
571 ft.

Focus Map:
14

HIST UST AUSTIN:
Name: L. L. EARNEST
Address: 1822 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: H0907
HID UST: 907
Inspection: Not reported
Due: 06/01/2012

FQ1124 **JACK BROWN CLEANERS** **TX HIST UST** **S128729005**
East **2215 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
72 ft. **Site 6 of 16 in cluster FQ**

Actual:
594 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	JACK BROWN CLEANERS
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0340
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FQ1125 **JACK BROWN CLEANERS NO 6** **RCRA NonGen / NLR** **1000265996**
East **2215 S CONGRESS AVE** **FINDS** **TXD981590706**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.014 mi.
72 ft. **Site 7 of 16 in cluster FQ**

Actual:
594 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20141219
Handler Name:	Jack Brown Cleaners No 6
Handler Address:	2215 S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78704-4318
EPA ID:	TXD981590706
Contact Name:	PAUL BROWN
Contact Address:	PO BOX 28159
Contact City,State,Zip:	AUSTIN, TX 78755-8159
Contact Telephone:	512-451-1333
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 28159
Mailing City,State,Zip:	AUSTIN, TX 78755-8159
Owner Name:	Jack Brown Cleaners Inc
Owner Type:	Private
Operator Name:	Jack Brown Cleaners Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150220
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JACK T BROWN CLEANERS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: 1
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20091006
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20091006
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Legal Status:	Private
Date Became Current:	20020128
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	1
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20090831
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20090831
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20020128
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20020128
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755-8159
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860902
Handler Name: JACK BROWN CLNRS NO 6
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010129
Handler Name: JACK BROWN CLNRS NO 6
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020228
Handler Name: JACK BROWN CLNRS NO 6
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020128
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070124
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090831
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Receive Date: 20091006
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141215
Handler Name: JACK BROWN CLEANERS NO 6
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141219
Handler Name: JACK BROWN CLEANERS NO 6
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: JACK BROWN CLNRS #6
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20141205
Actual Return to Compliance Date: 20150122
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20141205
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20141205
Actual Return to Compliance Date: 20150122
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20141205
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20141205
Actual Return to Compliance Date: 20150122
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20141205
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20141205
Actual Return to Compliance Date:	20150122
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20141205
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20141204
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: 20150122
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20141204
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20141204
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: 20150122
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20181017
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20141204
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20150122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110005091435

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

JACK BROWN CLEANERS NO 6 (Continued) **1000265996**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000265996
Registry ID:	110005091435
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005091435
Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

FQ1126 **BROWN JACK CLEANERS INC** **EDR Hist Cleaner** **1019944322**
East **2215 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.014 mi.
72 ft. **Site 8 of 16 in cluster FQ**

Actual:
594 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1994	JACK BROWN CLEANERS	Drycleaning Plants, Except Rugs
1995	JACK BROWN CLEANERS	Drycleaning Plants, Except Rugs
1996	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1997	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1998	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1999	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2000	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2001	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2002	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2003	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2004	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2011	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2012	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2013	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2014	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

FQ1127 **W. L. MOORE** **TX HIST UST** **S128729475**
East **2215 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
72 ft. **Site 9 of 16 in cluster FQ**

Actual:
594 ft.
Focus Map:
14

HIST UST AUSTIN:

Name:	W. L. MOORE
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0937
HID UST:	937
Inspection:	Not reported
Due:	06/01/2012

FQ1128 **WALLACE TEXACO** **EDR Hist Auto** **1013761765**
East **2215 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.014 mi.
72 ft. **Site 10 of 16 in cluster FQ**

Actual:
594 ft.
Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1962	WALLACE TEXACO	GASOLINE STATIONS

FQ1129 **JACK BROWN CLEANERS** **TX LPST** **U003566285**
East **2215 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX DRYCLEANERS**
0.014 mi. **TX Ind. Haz Waste**
72 ft. **Site 11 of 16 in cluster FQ** **TX COMP HIST**

Actual:
594 ft.
Focus Map:
14

LPST:

Name:	JACK BROWN CLEANERS
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0023302
LPST Id:	104533
Facility Location:	2215 SOUTH CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/08/1992
Entered Date:	10/01/1992
Reported Date:	09/08/1992
Closure Date:	11/10/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	SWEDE CARLSON
Responsible Party Address:	1316 W 5TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/473-8382

JACK BROWN CLEANERS (Continued) **U003566285**

Reported Date:	09/08/1992
Case Start Date:	11/10/1992
Reference Number:	RN101445021
Project Manager:	HWELCH

UST:

Name:	JACK BROWN CLEANERS
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787044318
AI Number:	23302
Facility Type:	RETAIL
Facility Begin Date:	09/25/1986
Facility Status:	INACTIVE
Additional ID:	387713422002207
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	R L EBERT,DIV. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601419310
Owner Last Name:	BROWN JACK
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

JACK BROWN CLEANERS (Continued) **U003566285**

Princ ID:	395713412002207
Additional ID:	387713422002207
AI Number:	23302
Owner Effective Begin Date:	09/25/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	60033
Facility ID:	59332
Ai Number:	23302
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

JACK BROWN CLEANERS (Continued) **U003566285**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	54388
UST ID:	60033
AI Number:	23302
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

JACK BROWN CLEANERS (Continued) **U003566285**

More Self Certification:

Self Cert ID:	8832
Cert ID:	39672
UST Comprt ID:	120872
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39670
UST Comprt ID:	120874
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39669
UST Comprt ID:	120878
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39668
UST Comprt ID:	120877
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39667
UST Comprt ID:	120876
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39666
UST Comprt ID:	120875
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	385090
UST Comprt ID:	1123791
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A

JACK BROWN CLEANERS (Continued) **U003566285**

Self Cert ID:	8832
Cert ID:	366984
UST Comprt ID:	1068527
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	350300
UST Comprt ID:	1018319
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	332887
UST Comprt ID:	965313
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	313788
UST Comprt ID:	908210
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	299315
UST Comprt ID:	864935
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	282570
UST Comprt ID:	815088
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	265570
UST Comprt ID:	764989
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832

JACK BROWN CLEANERS (Continued) **U003566285**

Cert ID:	248843
UST Comprt ID:	715276
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	232370
UST Comprt ID:	667175
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	227643
UST Comprt ID:	653246
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39679
UST Comprt ID:	120865
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39678
UST Comprt ID:	120866
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39677
UST Comprt ID:	120867
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39676
UST Comprt ID:	120868
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39675

JACK BROWN CLEANERS (Continued) **U003566285**

UST Comprt ID:	120869
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39674
UST Comprt ID:	120870
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39673
UST Comprt ID:	120871
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39671
UST Comprt ID:	120873
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	60034
Facility ID:	59332
Ai Number:	23302
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

JACK BROWN CLEANERS (Continued) **U003566285**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	54389
UST ID:	60034
AI Number:	23302
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

JACK BROWN CLEANERS (Continued) **U003566285**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8832
Cert ID:	39672
UST Comprt ID:	120872
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39670
UST Comprt ID:	120874
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39669
UST Comprt ID:	120878
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39668
UST Comprt ID:	120877
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39667

JACK BROWN CLEANERS (Continued) **U003566285**

UST Comprt ID:	120876
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39666
UST Comprt ID:	120875
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	385090
UST Comprt ID:	1123791
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	366984
UST Comprt ID:	1068527
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	350300
UST Comprt ID:	1018319
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	332887
UST Comprt ID:	965313
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	313788
UST Comprt ID:	908210
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	299315
UST Comprt ID:	864935

JACK BROWN CLEANERS (Continued) **U003566285**

UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	282570
UST Comprt ID:	815088
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	265570
UST Comprt ID:	764989
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	248843
UST Comprt ID:	715276
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	232370
UST Comprt ID:	667175
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	227643
UST Comprt ID:	653246
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39679
UST Comprt ID:	120865
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39678
UST Comprt ID:	120866
UST ID:	28033

JACK BROWN CLEANERS (Continued) **U003566285**

AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39677
UST Comprt ID:	120867
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39676
UST Comprt ID:	120868
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39675
UST Comprt ID:	120869
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39674
UST Comprt ID:	120870
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39673
UST Comprt ID:	120871
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39671
UST Comprt ID:	120873
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000

JACK BROWN CLEANERS (Continued) **U003566285**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	60037
Facility ID:	59332
Ai Number:	23302
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

JACK BROWN CLEANERS (Continued) **U003566285**

Installation Signature Date:	06/12/1991
Compartment Records:	
Tank ID:	5
Tank Capacity:	4000
UST Comprt ID:	54392
UST ID:	60037
AI Number:	23302
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	8832
Cert ID:	39672
UST Comprt ID:	120872
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39670
UST Comprt ID:	120874

JACK BROWN CLEANERS (Continued) **U003566285**

UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39669
UST Comprt ID:	120878
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39668
UST Comprt ID:	120877
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39667
UST Comprt ID:	120876
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39666
UST Comprt ID:	120875
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	385090
UST Comprt ID:	1123791
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	366984
UST Comprt ID:	1068527
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	350300
UST Comprt ID:	1018319
UST ID:	28033

JACK BROWN CLEANERS (Continued) **U003566285**

AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	332887
UST Comprt ID:	965313
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	313788
UST Comprt ID:	908210
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	299315
UST Comprt ID:	864935
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	282570
UST Comprt ID:	815088
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	265570
UST Comprt ID:	764989
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	248843
UST Comprt ID:	715276
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	232370
UST Comprt ID:	667175
UST ID:	28033
AI Number:	23302

JACK BROWN CLEANERS (Continued) **U003566285**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	227643
UST Comprt ID:	653246
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39679
UST Comprt ID:	120865
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39678
UST Comprt ID:	120866
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39677
UST Comprt ID:	120867
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39676
UST Comprt ID:	120868
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39675
UST Comprt ID:	120869
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39674
UST Comprt ID:	120870
UST ID:	28033
AI Number:	23302
Tank ID:	1

JACK BROWN CLEANERS (Continued) **U003566285**

Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39673
UST Comprt ID:	120871
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39671
UST Comprt ID:	120873
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	60036
Facility ID:	59332
Ai Number:	23302
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

JACK BROWN CLEANERS (Continued) **U003566285**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	54391
UST ID:	60036
AI Number:	23302
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

JACK BROWN CLEANERS (Continued) **U003566285**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8832
Cert ID:	39672
UST Comprt ID:	120872
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39670
UST Comprt ID:	120874
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39669
UST Comprt ID:	120878
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39668
UST Comprt ID:	120877
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39667
UST Comprt ID:	120876
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39666
UST Comprt ID:	120875
UST ID:	28033
AI Number:	23302
Tank ID:	1

JACK BROWN CLEANERS (Continued) **U003566285**

Compartment ID:	A
Self Cert ID:	8832
Cert ID:	385090
UST Comprt ID:	1123791
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	366984
UST Comprt ID:	1068527
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	350300
UST Comprt ID:	1018319
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	332887
UST Comprt ID:	965313
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	313788
UST Comprt ID:	908210
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	299315
UST Comprt ID:	864935
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	282570
UST Comprt ID:	815088
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A

JACK BROWN CLEANERS (Continued) **U003566285**

Self Cert ID:	8832
Cert ID:	265570
UST Comprt ID:	764989
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	248843
UST Comprt ID:	715276
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	232370
UST Comprt ID:	667175
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	227643
UST Comprt ID:	653246
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39679
UST Comprt ID:	120865
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39678
UST Comprt ID:	120866
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39677
UST Comprt ID:	120867
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832

JACK BROWN CLEANERS (Continued) **U003566285**

Cert ID:	39676
UST Comprt ID:	120868
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39675
UST Comprt ID:	120869
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39674
UST Comprt ID:	120870
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39673
UST Comprt ID:	120871
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39671
UST Comprt ID:	120873
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	60035
Facility ID:	59332
Ai Number:	23302
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/28/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

JACK BROWN CLEANERS (Continued) **U003566285**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	54390
UST ID:	60035
AI Number:	23302
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

JACK BROWN CLEANERS (Continued) **U003566285**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8832
Cert ID:	39672
UST Comprt ID:	120872
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39670
UST Comprt ID:	120874
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39669
UST Comprt ID:	120878
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832

JACK BROWN CLEANERS (Continued) **U003566285**

Cert ID:	39668
UST Comprt ID:	120877
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39667
UST Comprt ID:	120876
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39666
UST Comprt ID:	120875
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	385090
UST Comprt ID:	1123791
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	366984
UST Comprt ID:	1068527
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	350300
UST Comprt ID:	1018319
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	332887
UST Comprt ID:	965313
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	313788

JACK BROWN CLEANERS (Continued) **U003566285**

UST Comprt ID:	908210
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	299315
UST Comprt ID:	864935
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	282570
UST Comprt ID:	815088
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	265570
UST Comprt ID:	764989
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	248843
UST Comprt ID:	715276
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	232370
UST Comprt ID:	667175
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	227643
UST Comprt ID:	653246
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39679
UST Comprt ID:	120865

JACK BROWN CLEANERS (Continued) **U003566285**

UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39678
UST Comprt ID:	120866
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39677
UST Comprt ID:	120867
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39676
UST Comprt ID:	120868
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39675
UST Comprt ID:	120869
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39674
UST Comprt ID:	120870
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39673
UST Comprt ID:	120871
UST ID:	28033
AI Number:	23302
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8832
Cert ID:	39671
UST Comprt ID:	120873
UST ID:	28033

JACK BROWN CLEANERS (Continued) **U003566285**

AI Number:	23302
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	BROWN JACK
Contact Mailing Address (Delivery):	1316 W 5TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 5207
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	59332
Additional ID:	387713422002207
Princ ID:	395713412002207
AI Number:	23302
Facility Name:	JACK BROWN CLEANERS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JACK T BROWN/

DRYCLEANERS:

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported

JACK BROWN CLEANERS (Continued) **U003566285**

AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	400
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006

JACK BROWN CLEANERS (Continued) **U003566285**

Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	480
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	480
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543

JACK BROWN CLEANERS (Continued) **U003566285**

DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	700
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	700
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

JACK BROWN CLEANERS (Continued) **U003566285**

Fiscal Year:	FY2011
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	900
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	250
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	11

JACK BROWN CLEANERS (Continued) **U003566285**

CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	190
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	65
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	FACILITY REGISTRATION

JACK BROWN CLEANERS (Continued) **U003566285**

Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	190
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	90
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021

JACK BROWN CLEANERS (Continued) **U003566285**

Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	145
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6

JACK BROWN CLEANERS (Continued) **U003566285**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	PETROLEUM
Gallons:	165
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN101445021
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR10775
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS NO 6
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Ind. Haz Waste:

Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66313
Registration Initial Notification Date:	04/15/1985
Registration Last Amendment Date:	12/19/2014
EPA Identification:	TXD981590706
Primary NAICS Code:	812320
Status Change Date:	20141216
Land Type:	PRIVATE
Description of Facility Site Location:	2215 S CONGRESS AVE AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS

JACK BROWN CLEANERS (Continued) **U003566285**

Company Name:	JACK BROWN CLEANERS INC
Contact Name:	PAUL BROWN
Contact Telephone Number:	512-4511333
Mailing Address:	PO BOX 28159
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787558159
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21592
Site Owner Tax ID:	741395502
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20150204
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	JACK BROWN CLEANERS INC
Operator Address:	PO BOX 28159
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78755
Operator Country:	UNITED STA
Operator Telephone:	1-512-4511333
Operator Fax Number:	1-512-4511303
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17413955026
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JACK BROWN CLEANERS INC
Owner Mailing Address:	PO BOX 28159
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78755
Owner Country:	UNITED STA
Owner Telephone:	1-512-4511333
Owner Fax:	1-512-4511303
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17413955026
Owner Bankruptcy Code:	Not reported

JACK BROWN CLEANERS (Continued) **U003566285**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	UN rated drum to store waste liquid tetrachloroethylene until pick up.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	N
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	UN rated drum to store tetrachloroethylene sludge to be hauled off in for recycl
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON

JACK BROWN CLEANERS (Continued) **U003566285**

Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4511333
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4511333
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Contact Name:	PAUL BROWN
Contact Title:	PRESIDENT
Contact Role:	PRICONT
Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4511333
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	70349
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	236804
Texas Waste Code:	Not reported

JACK BROWN CLEANERS (Continued) **U003566285**

Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	non hazardous waste
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	70350
Texas Waste Code:	Not reported
Texas Waste Code 2:	3605601H
Waste Code Status:	INACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301765
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWG

JACK BROWN CLEANERS (Continued) **U003566285**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301765
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWG

COMP HIST:

RN Number:	RN101445021
Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	TX 78704
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
CN Name:	JACK BROWN CLEANERS INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	812320
SIC Code:	1521
Related Number:	TXD981590706,DCR10775,DCR10775

RN Number:	RN101445021
Name:	JACK BROWN CLEANERS NO 6
Address:	2215 S CONGRESS AVE
City,State,Zip:	TX 78704
Region:	REGION 11 - AUSTIN
CN Number:	CN601419310
CN Name:	BROWN JACK
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	812320
SIC Code:	1521
Related Number:	TXD981590706,DCR10775,DCR10775

FQ1130 **RAMIREZ TEXACO STATION** **EDR Hist Auto** **1020230459**
East **2215 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.014 mi.
72 ft. **Site 12 of 16 in cluster FQ**

Actual:
594 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1971	RAMIREZ TEXACO STATION	Gasoline Service Stations
1972	RAMIREZ TEXACO STATION	Gasoline Service Stations
1973	RAMIREZ TEXACO STATION	Gasoline Service Stations
1974	RAMIREZ TEXACO STATION	Gasoline Service Stations
1976	RAMIREZ TEXACO STATION	Gasoline Service Stations
1977	RAMIREZ TEXACO STATION	Gasoline Service Stations
1978	RAMIREZ TEXACO STATION	Gasoline Service Stations
1979	RAMIREZ TEXACO STATION	Gasoline Service Stations
1980	RAMIREZ TEXACO STATION	Gasoline Service Stations
1982	RAMIREZ TEXACO STATION	Gasoline Service Stations
1983	RAMIREZ TEXACO STATION	Gasoline Service Stations

DN1131 **LATTIMORE CLEANERS** **EDR Hist Cleaner** **1013784762**
NNE **129 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
73 ft. **Site 3 of 8 in cluster DN**

Actual:
493 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	LATTIMORE CLEANERS	CLOTHES PRESSERS AND CLEANERS

BU1132 **REYES CLNS** **EDR Hist Cleaner** **1013781378**
West **2504 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
73 ft. **Site 5 of 5 in cluster BU**

Actual:
598 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	CACTUS PRESSING SHOP	CLOTHES CLEANERS AND PRESSERS
1935	CACTUS PRESSING SHOP	CLOTHES PRESSERS AND CLEANERS
1958	REYES CLNS	CLEANERS AND DYERS

H1133 **A ME KANNIKS OTTO NEIGHBORHOOD GARAGE** **EDR Hist Auto** **1013752920**
WNW **11104 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.014 mi.
73 ft. **Site 4 of 4 in cluster H**

Actual:
775 ft.
EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1988	AUTOFIX SYSTEMS INC	Motor Vehicle Supplies And New Parts
1989	AUTOFIX SYSTEMS INC	Automotive Supplies And Parts
1990	A ME KANNIKS OTTO NEIGHBORHOOD	AUTOMOBILE REPAIRING

K1134 **QUICK LUBE CAR SERV** **EDR Hist Auto** **1013776559**
WNW **10300 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.014 mi.
73 ft. **Site 3 of 3 in cluster K**

Actual:
719 ft.
EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1990	QUICK LUBE CAR SERV	AUTOMOBILE OIL AND LUBRICATING SERVICE
1990	QUICK LUBE CAR SERV	AUTOMOBILE REPAIRING
1991	QUICK LUBE	Automotive Repair Shops, NEC
1992	QUICK LUBE	Automotive Repair Shops, NEC
1993	QUICK LUBE	Automotive Repair Shops, NEC
1994	QUICK LUBE	Automotive Repair Shops, NEC
1995	QUICK LUBE	Automotive Repair Shops, NEC
1996	QUICK LUBE	Automotive Repair Shops, NEC
1997	QUICK LUBE	Automotive Repair Shops, NEC
1998	QUICK LUBE INC	Automotive Repair Shops, NEC
1999	QUICK LUBE INC	Automotive Repair Shops, NEC
2000	QUICK LUBE INC	Automotive Repair Shops, NEC
2001	QUICK LUBE INC	Automotive Repair Shops, NEC
2006	HEARTLAND AUTOMOTIVE SERVICES	General Automotive Repair Shops

---

DP1135 **MAJESTIC CLNRS** **EDR Hist Cleaner** **1013783469**
NNE **219 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
73 ft. **Site 6 of 16 in cluster DP**

Actual:
489 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1953	MAJESTIC CLEANERS	CLEANERS AND DYERS
1958	MAJESTIC CLNRS	CLEANERS AND DYERS
1962	MAJESTIC CLNS	CLEANERS AND DYERS

DP1136 **MAJESTIC CLEANERS GR** **EDR Hist Cleaner** **1013778143**
NNE **219 6TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
73 ft. **Site 7 of 16 in cluster DP**

Actual:
489 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	MAJESTIC CLEANERS GR	CLEANERS AND DYERS

S1137	**QUALITY ENGINE EXCHANGE**	**RCRA-VSQG**	**1000287315**
SE	**8807 B N LAMAR BLVD**	**FINDS**	**TXD160827978**
< 1/8	**AUSTIN, TX 78753**	**ECHO**	
0.014 mi.		**TX Ind. Haz Waste**	
73 ft.	**Site 6 of 9 in cluster S**	**TX CENTRAL REGISTRY**	

Actual:
659 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20110217
Handler Name:	Quality Engine Exchange
Handler Address:	8807 B N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD160827978
Contact Name:	PAM HARMON
Contact Address:	8807-B N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-836-9222
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	8807-B N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Quality Engine Exchange,
Owner Type:	Private
Operator Name:	Quality Engine Exchange,
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110308
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D021
Waste Description:	Chlorobenzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DAVID STUART	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: QUALITY ENGINE EXCHANGE,	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	8807-B N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-836-9222
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: QUALITY ENGINE EXCHANGE,	
Legal Status:	Private
Date Became Current:	20110124
Date Ended Current:	Not reported
Owner/Operator Address:	8807-B N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-836-9222
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: QUALITY ENGINE EXCHANGE	
Legal Status:	Not reported
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	8807-B N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-836-9222
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19890315
Handler Name: QUALITY ENGINE EXCHANGE	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010127
Handler Name:	QUALITY ENGINE EXCHANGE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110217
Handler Name:	QUALITY ENGINE EXCHANGE
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811118
NAICS Description:	OTHER AUTOMOTIVE MECHANICAL AND ELECTRICAL REPAIR AND MAINTENANCE

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20100517
Actual Return to Compliance Date:	20100923
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100624
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20100517
Actual Return to Compliance Date: 20100923
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100624
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20100517
Actual Return to Compliance Date:	20100923
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100624
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20100517
Actual Return to Compliance Date: 20100923
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100624
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20100517
Actual Return to Compliance Date:	20100923
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100624
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20100517
Actual Return to Compliance Date:	20100923
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100624
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20100517
Actual Return to Compliance Date: 20100923
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100624
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20100517
Actual Return to Compliance Date: 20100923
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100624
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20100517
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: 20100923
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20100517
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier: Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20101007
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100517
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100923
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110043556434

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000287315
Registry ID:	110043556434
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110043556434
Name:	QUALITY ENGINE EXCHANGE
Address:	8807 B N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

Ind. Haz Waste:

Name:	QUALITY ENGINE EXCHANGE
Address:	8807 N LAMAR BLVD STE B
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	73608
Registration Initial Notification Date:	03/10/1989
Registration Last Amendment Date:	01/24/2011
EPA Identification:	TXD160827978
Primary NAICS Code:	811118
Status Change Date:	19890310
Land Type:	PRIVATE
Description of Facility Site Location:	8807 B N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	QUALITY ENGINE EXCHANGE
Contact Name:	PAM HARMON
Contact Telephone Number:	512-8369222
Mailing Address:	8807 N LAMAR BLVD STE B
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535409
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28020
Site Owner Tax ID:	742466939
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110217
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	QUALITY ENGINE EXCHANGE
Operator Address:	8807 N LAMAR BLVD STE B
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8369222
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	QUALITY ENGINE EXCHANGE
Owner Mailing Address:	8807 N LAMAR BLVD STE B
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8369222
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8807 N LAMAR BLVD STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8369222
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8807 N LAMAR BLVD STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8369222
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	PAM HARMON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8807 N LAMAR BLVD STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8369222
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	139762
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	75390
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169014866
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139763
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	IMMERSION CLEANER
Standard Industrial Code:	75390
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169014866
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139764
Texas Waste Code:	Not reported
Texas Waste Code 2:	14763101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	USED FILTERS

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169014866
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307307
Principal Name:	QUALITY ENGINE EXCHANGE
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307307
Principal Name:	QUALITY ENGINE EXCHANGE
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307307
Principal Name:	QUALITY ENGINE EXCHANGE
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307307
Principal Name:	QUALITY ENGINE EXCHANGE

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Attention Name: Not reported
Attention Suffix: HWF

CENTRAL REGISTRY:

Regulated Entity Number: RN100563634
Name: QUALITY ENGINE EXCHANGE
Address: 8807 N LAMAR BLVD STE B
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-5409
Status: ACTIVE
Status Date: ##########
Customer Number: CN600274377
Customer Name: QUALITY ENGINE EXCHANGE
Customer Legal Name: Quality Engine Exchange
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811118
Primary NAICS Industry Type Description: Other Automotive Mechanical and Electrical Repair and Maintenance
Physical Location Description: 8807 B N Lamar Blvd, Austin, TX

Regulated Entity Number: RN100563634
Name: QUALITY ENGINE EXCHANGE
Address: 8807 N LAMAR BLVD STE B
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-5409
Status: ACTIVE
Status Date: ##########
Customer Number: CN600274377
Customer Name: QUALITY ENGINE EXCHANGE
Customer Legal Name: Quality Engine Exchange
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811118
Primary NAICS Industry Type Description: Other Automotive Mechanical and Electrical Repair and Maintenance
Physical Location Description: 8807 B N Lamar Blvd, Austin, TX

Regulated Entity Number: RN100563634
Name: QUALITY ENGINE EXCHANGE
Address: 8807 N LAMAR BLVD STE B
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-5409
Status: ACTIVE
Status Date: ##########
Customer Number: CN600274377
Customer Name: QUALITY ENGINE EXCHANGE
Customer Legal Name: Quality Engine Exchange
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1/27/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811118
Primary NAICS Industry Type Description: Other Automotive Mechanical and Electrical Repair and Maintenance

QUALITY ENGINE EXCHANGE (Continued) **1000287315**

Physical Location Description: 8807 B N Lamar Blvd, Austin, TX

S1138 **AUSTIN QUALITY ENGINE ENG REPR** **EDR Hist Auto** **1013765318**
SE **8807 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.014 mi.
73 ft. **Site 7 of 9 in cluster S**

Actual:
659 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1979	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1980	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1982	NORTH LAMAR ATMTV SRS INC	General Automotive Repair Shops
1983	NORTH LAMAR ATMTV SRS INC	General Automotive Repair Shops
1985	REEP MACHINERY INC	Automotive Repair Shops, NEC
1986	REEP MACHINERY INC	Automotive Repair Shops, NEC
1987	QUALITY ENGINES	Industrial Machinery, NEC
1987	REEP MACHINERY INC	Automotive Repair Shops, NEC
1988	REEP MACHINERY INC	Automotive Repair Shops, NEC
1989	REEP MACHINERY INC	Automotive Repair Shops, NEC
1990	AUSTIN QUALITY ENGINE ENG REPR	AUTOMOBILE REPAIRING
1990	REEP MACHINERY INC	Automotive Repair Shops, NEC
1991	REEP MACHINERY INC	Automotive Repair Shops, NEC
1992	NORTH LAMAR AUTOMOTIVE	Engine Repair
1993	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1994	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1995	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1996	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1997	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1998	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
1999	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
2000	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
2001	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
2001	QUALITY ENGINE EXCHANGE INC	Engine Repair
2002	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops
2002	QUALITY ENGINE EXCHANGE INC	Engine Repair
2003	QUALITY ENGINE EXCHANGE INC	Engine Repair
2003	NORTH LAMAR AUTOMOTIVE INC	General Automotive Repair Shops

---

S1139 **OLMEDA TIRE & AUTO** **TX RDR** **S128622892**
SE **8807 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
73 ft. **Site 8 of 9 in cluster S**

Actual:
659 ft.

RDR:

RDR ID:	31653
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	OLMEDA TIRE & AUTO
Address:	8807 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/1/2022
Due Date:	5/31/2022

Focus Map:
6

OLMEDA TIRE & AUTO (Continued) **S128622892**

Tank Owner:	OLMEDA TIRE & AUTO
Contact Person:	ZACHARY ARMSTRONG
Report:	Tank Closure
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/5/2022
Project Manager:	Rodney Bryant
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

S1140 **NORTH LAMAR AUTOMOTIVE** **TX Ind. Haz Waste** **S103608602**
SE **8807 N LAMAR BLVD STE A** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.014 mi.
73 ft. **Site 9 of 9 in cluster S**

Actual:
659 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	NORTH LAMAR AUTOMOTIVE
Address:	8807 N LAMAR BLVD STE A
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	73603
Registration Initial Notification Date:	03/10/1989
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXD051157949
Primary NAICS Code:	811111
Status Change Date:	19890310
Land Type:	PRIVATE
Description of Facility Site Location:	8807 A N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	NORTH LAMAR AUTOMOTIVE INC
Contact Name:	BENJAMIN BENNETT
Contact Telephone Number:	512-8375300
Mailing Address:	8807 N LAMAR BLVD STE A
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535409
Mailing County:	UNITED STATES

NORTH LAMAR AUTOMOTIVE (Continued) **S103608602**

Facility Country:	UNITED STATES
TNRCC Facility ID:	28015
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	NORTH LAMAR AUTOMOTIVE INC
Operator Address:	8807 N LAMAR BLVD STE A
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8375300
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17426141259
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	NORTH LAMAR AUTOMOTIVE INC
Owner Mailing Address:	8807 N LAMAR BLVD STE A
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8375300
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17426141259
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	11
UIC Permit Number:	Not reported

NORTH LAMAR AUTOMOTIVE (Continued) **S103608602**

Capacity:	5
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Finish Thompson Inc. solvent recover unit little still Serial #02056B93
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19950125
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8807 N LAMAR BLVD STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375300
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8807 N LAMAR BLVD STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375300
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BENJAMIN BENNETT
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8807 N LAMAR BLVD STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8375300
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

NORTH LAMAR AUTOMOTIVE (Continued) **S103608602**

Waste ID:	151157
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001201H
Waste Code Status:	INACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solvent from degreasing operation in cleaning automobile engine parts, Ign
Standard Industrial Code:	75380
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811111
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307306
Principal Name:	NORTH LAMAR AUTOMOTIVE INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8807 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000307306
Principal Name:	NORTH LAMAR AUTOMOTIVE INC
Attention Name:	Not reported
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100551332
Name:	NORTH LAMAR AUTOMOTIVE
Address:	8807 N LAMAR BLVD STE A
Address 2:	Not reported

NORTH LAMAR AUTOMOTIVE (Continued) **S103608602**

City,State,Zip:	AUSTIN, TX 78753-5409
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600262299
Customer Name:	NORTH LAMAR AUTOMOTIVE INC
Customer Legal Name:	North Lamar Automotive, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8807 A N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100551332
Name:	NORTH LAMAR AUTOMOTIVE
Address:	8807 N LAMAR BLVD STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5409
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600262299
Customer Name:	NORTH LAMAR AUTOMOTIVE INC
Customer Legal Name:	North Lamar Automotive, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8807 A N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100551332
Name:	NORTH LAMAR AUTOMOTIVE
Address:	8807 N LAMAR BLVD STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5409
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600262299
Customer Name:	NORTH LAMAR AUTOMOTIVE INC
Customer Legal Name:	North Lamar Automotive, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	8807 A N Lamar Blvd, Austin, TX

GQ1141 **CONOCO FOOD MART** **EDR Hist Auto** **1021016937**
NNE **6214 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.014 mi.
74 ft. **Site 9 of 15 in cluster GQ**

Actual:
512 ft.
EDR Hist Auto

Focus Map:
15

Year:	Name:	Type:
2000	CONOCO FOOD MART	Convenience Stores
2001	CONOCO FOOD MART	Convenience Stores
2002	CONOCO FOOD MART	Convenience Stores
2003	CONOCO FOOD MART	Convenience Stores
2004	CONOCO FOOD MART	Convenience Stores
2005	CONOCO FOOD MART	Convenience Stores
2006	CONOCO FOOD MART	Convenience Stores
2007	CONOCO FOOD MART	Convenience Stores
2008	CONOCO FOOD MART	Convenience Stores
2009	CONOCO FOOD MART	Convenience Stores
2010	CONOCO FOOD MART	Convenience Stores
2011	CONOCO FOOD MART	Convenience Stores
2012	CONOCO FOOD MART	Convenience Stores
2013	CONOCO FOOD MART	Convenience Stores
2014	CONOCO FOOD MART	Convenience Stores

GQ1142 **CONOCO FOOD MART** **TX UST** **U001246994**
NNE **6214 E RIVERSIDE DR** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX ASBESTOS**
0.014 mi. **TX Financial Assurance**
74 ft. **Site 10 of 15 in cluster GQ**

Actual:
512 ft.
UST:

Focus Map:
15

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787416516
AI Number:	11000
Facility Type:	RETAIL
Facility Begin Date:	01/01/1973
Facility Status:	INACTIVE
Additional ID:	15491982002054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	ADAM ABU HAMDAN,MGR
Contact Organization Name:	CONOCO FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123893914
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/24/2019
Signature Name/Title On Earliest Reg Form:	ADAM AHMAD,PRES

CONOCO FOOD MART (Continued) **U001246994**

Application Received Date On Earliest Reg Form:	09/24/2019
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	621521472004118
Additional ID:	15491982002054
Ai Number:	11000
Operator CN:	CN602618324
Operator Name:	A M PETROLEUM INC
Operator Effective Begin Date:	01/01/2006
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	ADAM AHMAD/PRES
Contact Organization Name:	A M PETROLEUM INC
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78752-1979
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3396008
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	AMPETROLEUM@AOL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602618324
Owner Last Name:	A M PETROLEUM INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78752
Contact Mailing Zip5:	1979
Contact Phone Number/Ext:	1 512 3396008/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	AMPETROLEUM@AOL.COM
Contact Address Deliverable:	Not reported
Princ ID:	621521472004118
Additional ID:	15491982002054
AI Number:	11000
Owner Effective Begin Date:	01/01/2006
State Tax ID:	17429784329
Contact Role:	OWNOPRCON
Contact Name/Title:	ADAM AHMAD/PRES
Contact Organization Name:	A M PETROLEUM INC

CONOCO FOOD MART (Continued) **U001246994**

Self Certification:

Self Cert ID:	80208
Cert ID:	322827
AI Number:	11000
Self Certification Date:	07/03/2019
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80208
Cert ID:	305225
AI Number:	11000
Self Certification Date:	06/07/2018
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80208
Cert ID:	288649
AI Number:	11000
Self Certification Date:	06/26/2017
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	272348
AI Number:	11000
Self Certification Date:	07/11/2016
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80208
Cert ID:	254954
AI Number:	11000
Self Certification Date:	06/13/2015
Signature Name/Title:	ADAM K AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80208
Cert ID:	238258
AI Number:	11000
Self Certification Date:	06/10/2014
Signature Name/Title:	ADAM K AHMAD OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	221786
AI Number:	11000
Self Certification Date:	07/02/2013
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80208
Cert ID:	124397
AI Number:	11000
Self Certification Date:	05/18/2012
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124396
AI Number:	11000
Self Certification Date:	06/14/2011
Signature Name/Title:	ADAM K AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	124395
AI Number:	11000
Self Certification Date:	06/23/2010
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124159
AI Number:	11000
Self Certification Date:	05/25/2009
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124158
AI Number:	11000
Self Certification Date:	06/15/2008
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	124157
AI Number:	11000
Self Certification Date:	06/28/2007
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124156
AI Number:	11000
Self Certification Date:	06/06/2006
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124155
AI Number:	11000
Self Certification Date:	12/28/2005
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	124154
AI Number:	11000
Self Certification Date:	01/13/2005
Signature Name/Title:	ADAM AHMAD
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124153
AI Number:	11000
Self Certification Date:	02/02/2004
Signature Name/Title:	ADAM AHMAD
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80208
Cert ID:	124152
AI Number:	11000
Self Certification Date:	12/30/2002
Signature Name/Title:	ADAM AHMAD OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Self Cert ID:	80208
Cert ID:	124151
AI Number:	11000
Self Certification Date:	08/22/2002
Signature Name/Title:	ADAM AHMAD OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	28927
Facility ID:	80208
Ai Number:	11000
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/29/2020
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

CONOCO FOOD MART (Continued) **U001246994**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	113766
UST ID:	28927
AI Number:	11000
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y

CONOCO FOOD MART (Continued) **U001246994**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	28928
Facility ID:	80208
Ai Number:	11000
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/29/2020
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

CONOCO FOOD MART (Continued) **U001246994**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	113767
UST ID:	28928
AI Number:	11000
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

CONOCO FOOD MART (Continued) **U001246994**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	06/01/1995
Tank Registration Date:	04/09/1999
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	190897
Facility ID:	80208
Ai Number:	11000
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/29/2020
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

CONOCO FOOD MART (Continued) **U001246994**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	113768
UST ID:	190897
AI Number:	11000
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	08/30/2001

Construction Notification:

NOC ID:	36852
Facility ID:	80208

CONOCO FOOD MART (Continued) **U001246994**

AI Number:	11000
Application Received Date:	08/10/2020
Scheduled Construction Date:	09/10/2020
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	08/10/2020
Signature Date On Form:	08/10/2020
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	A M PETROLEUM INC
Owner CN At Time Of Construction:	CN602618324
Owner AR At Time Of Construction:	59197
General Desc Of Prop Construct:	INSTALL NEW UST SYSTEM

NOC ID:	36818
Facility ID:	80208
AI Number:	11000
Application Received Date:	08/04/2020
Scheduled Construction Date:	08/04/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	08/10/2020
Signature Date On Form:	08/10/2020
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	A M PETROLEUM INC
Owner CN At Time Of Construction:	CN602618324
Owner AR At Time Of Construction:	59197
General Desc Of Prop Construct:	REMOVE TWO 10,000 GAL UST AND ONE 6,000 GAL REQUEST 30 DAY WAIVER

NOC ID:	36707

CONOCO FOOD MART (Continued) **U001246994**

Facility ID:	80208
AI Number:	11000
Application Received Date:	07/09/2020
Scheduled Construction Date:	07/25/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	08/10/2020
Signature Date On Form:	08/10/2020
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	A M PETROLEUM INC
Owner CN At Time Of Construction:	CN602618324
Owner AR At Time Of Construction:	59197
General Desc Of Prop Construct:	REMOVAL OF 3 USTS AND ASSOC PIPING. REQUEST 30 DAY WAIVER

NOC ID:	12743
Facility ID:	80208
AI Number:	11000
Application Received Date:	11/14/2008
Scheduled Construction Date:	11/17/2008
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M81114006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	08/10/2020
Signature Date On Form:	08/10/2020
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	59197
General Desc Of Prop Construct:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	87480
UST ID:	Not reported
NOC ID:	36818
AI Number:	11000
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000189
Company Name:	CARBON ENV LLC
Representative Name:	CLAY WYATT
Mailing Address (Delivery):	661 E MAIN STE 200-254
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MIDLOTHIAN
Mailing State:	Not reported
Mailing Zip:	76065
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	87550
UST ID:	Not reported
NOC ID:	36852
AI Number:	11000
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	JF PETROLEUM GROUP
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	13668
UST ID:	Not reported
NOC ID:	12743
AI Number:	11000
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	87195
UST ID:	Not reported
NOC ID:	36707
AI Number:	11000
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	JF PETROLEUM GROUP
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	87479
UST ID:	Not reported
NOC ID:	36818
AI Number:	11000
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001273
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	87196
UST ID:	Not reported
NOC ID:	36707
AI Number:	11000
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	PEFFER BRENT ALLYN
Representative Name:	Not reported
Mailing Address (Delivery):	58 HEARTHSHIRE CIR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MAGNOLIA
Mailing State:	TX
Mailing Zip:	77354
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	A M PETROLEUM INC
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 1979
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80208
Additional ID:	15491982002054
Princ ID:	621521472004118
AI Number:	11000
Facility Name:	CONOCO FOOD MART
AR Number:	59197
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ADAM AHMAD/

HIST UST AUSTIN:

Name:	JD'S MARKET #9
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	649

CONOCO FOOD MART (Continued) **U001246994**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/23/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	216373
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2018
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-000107704
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

CONOCO FOOD MART (Continued) **U001246994**

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	198715
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2017
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-000102627
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	181814
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2016
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00098123
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	164809
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

CONOCO FOOD MART (Continued) **U001246994**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2015
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-93855
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	152207
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2015
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-93855
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	145916
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2014
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported

CONOCO FOOD MART (Continued) **U001246994**

Policy Number:	04-TO-00089711
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	129690
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2013
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00081735
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	110871
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2012
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00081735
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

CONOCO FOOD MART (Continued) **U001246994**

Region:	2
Facility ID:	80208
Finass ID:	9217
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2011
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000078901
Coverage Amount:	1000000
Coverage Expiration Date:	08/25/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67434
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2011
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000078901
Coverage Amount:	1000000
Coverage Expiration Date:	08/25/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67435
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

CONOCO FOOD MART (Continued) **U001246994**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2010
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18581
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67436
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2010
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18581
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67437
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2009
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18581
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2010

CONOCO FOOD MART (Continued) **U001246994**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67438
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2008
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18581
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67439
AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2007
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18581
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	CONOCO FOOD MART
Address:	6214 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	80208
Finass ID:	67440

CONOCO FOOD MART (Continued) **U001246994**

AI:	11000
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	09/24/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GQ1143 **CONOCO FOOD MART** **TX RDR** **S127524190**
NNE **6214 EAST RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
74 ft. **Site 11 of 15 in cluster GQ**

Actual:
512 ft.

Focus Map:
15

RDR:

RDR ID:	28872
Facility ID:	11000
RN:	Not reported
CN:	Not reported
Name:	CONOCO FOOD MART
Address:	6214 EAST RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/24/2020
Due Date:	10/23/2020
Tank Owner:	A M PETROLEUM INC
Contact Person:	ADAM AHMAD
Report:	Tank Removal
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/23/2020
Project Manager:	Meagan Kunze-Nevarez
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GR1144 **YOUNG TROY H GULF** **EDR Hist Auto** **1013767908**
WNW **3900 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.014 mi.
74 ft. **Site 4 of 4 in cluster GR**

Actual:
659 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1962	YOUNG TROY H GULF	GASOLINE STATIONS

CV1145 **HOME STEAM LAUNDRY** **TX HIST UST** **S111678678**
WNW **120 E 10TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
74 ft. **Site 5 of 14 in cluster CV**

Actual:
514 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	HOME STEAM LAUNDRY
Address:	120 E 10TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0337
HID UST:	337
Inspection:	Not reported
Due:	06/01/2012

HJ1146 **FAIRLVIEW GARAGE** **EDR Hist Auto** **1013766121**
WNW **5804 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.014 mi.
74 ft. **Site 2 of 3 in cluster HJ**

Actual:
629 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1965	TOWNSLEY GARAGE	AUTOMOBILE REPAIRING
1970	FAIRLVIEW GARAGE	AUTOMOBILE REPAIRING
1975	FAIRVIEW GARAGE	AUTOMOBILE REPAIRING
1980	DAN ROBERT AUTOMOTIVE	AUTOMOBILE REPAIRING
1982	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1983	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1984	DAN ROBERTS AUTOMOTIVE	AUTOMOBILE REPAIRING
1985	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1986	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1987	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1988	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1988	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC
1988	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC
1989	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC
1989	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC
1989	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1989	ALVINS AUTOMOTIVE	General Automotive Repair Shops
1990	DAN AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC
1990	ALVINS AUTOMOTIVE	General Automotive Repair Shops
1990	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1990	JAEGER AUTOMOTIVE INC	Automotive Repair Shops, NEC

FAIRLVIEW GARAGE (Continued) **1013766121**

1991	ALVINS AUTOMOTIVE	General Automotive Repair Shops
1991	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1992	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1992	ALVINS AUTOMOTIVE	General Automotive Repair Shops
1993	ALVINS AUTOMOTIVE	General Automotive Repair Shops
1993	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1994	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1995	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1996	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1997	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1998	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
1999	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2000	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2001	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2002	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2003	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2004	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2005	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2006	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2007	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2008	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2009	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2010	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2011	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2012	ROBERTS AUTOMOTIVE	General Automotive Repair Shops
2013	ROBERTS AUTOMOTIVE	General Automotive Repair Shops

EF1147 **BUD FOWLER** **TX HIST UST** **S111678578**
SSE **201 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
74 ft. **Site 2 of 2 in cluster EF**

Actual:
448 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	BUD FOWLER
Address:	201 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0771
HID UST:	771
Inspection:	Not reported
Due:	06/01/2012

AH1148 **B & B BODY & FRAME** **TX AIRS** **S102749761**
WNW **6518 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX COMP HIST**
0.014 mi. **TX CENTRAL REGISTRY**
74 ft. **Site 7 of 8 in cluster AH**

Actual:
714 ft.

Focus Map:
6

AIRS:

Name:	B AND B BODY AND FRAME INC
Address:	6518 N LAMAR BLVD
City,State,Zip:	TX
Permit Num:	27824
Regulated Id:	RN102862802
Permit Type:	PBR

B & B BODY & FRAME (Continued) **S102749761**

Permit Status:	EFFECTIVE
Permit Issued Date:	12/07/2011
Expiration Date:	12/31/3000
Customer Id:	CN605105246
Company Name:	SERVICE KING PAINT & BODY LLC
Physical Location Desc:	6518 N LAMAR, AUSTIN, TX 78752
Rep Official(RO):	PROJECT SPECIALIST
RO Name:	MR JOHN HALBROOK
RO Delivery Address:	808 S CENTRAL EXPY
RO City/State/Zip:	RICHARDSON, T 75080-741
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	JOHN.HALBROOK@SERVICEKING.COM
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

Ind. Haz Waste:

Name:	B & B BODY & FRAME
Address:	6518 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	66255
Registration Initial Notification Date:	08/18/1984
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD026010579
Primary NAICS Code:	Not reported
Status Change Date:	19840818
Land Type:	PRIVATE
Description of Facility Site Location:	6518 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	B & B BODY & FRAME INC
Contact Name:	REX WOMBLE
Contact Telephone Number:	512-4540461
Mailing Address:	6518 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524010
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21540
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060316
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported

B & B BODY & FRAME (Continued) **S102749761**

Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	B & B BODY & FRAME INC
Operator Address:	6518 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4540461
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17415301633
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	B & B BODY & FRAME INC
Owner Mailing Address:	6518 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4540461
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17415301633
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6518 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4540461
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6518 N LAMAR BLVD
Contact Address 2:	Not reported

B & B BODY & FRAME (Continued) **S102749761**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4540461
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	REX WOMBLE
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	6518 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4540461
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	138878
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	PAINT WASTE
Standard Industrial Code:	Not reported
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169415183
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

COMP HIST:

RN Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN

B & B BODY & FRAME (Continued) **S102749761**

CN Number:	CN605105246
CN Name:	SERVICE KING PAINT & BODY LLC
CN Rating:	1.88
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	237310
SIC Code:	1521
Related Number:	27824,TH0536L,TH0536L

RN Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600407399
CN Name:	B & B BODY & FRAME INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811121
SIC Code:	7999
Related Number:	27824,TH0536L,TH0536L

CENTRAL REGISTRY:

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600407399
Customer Name:	B & B BODY & FRAME INC
Customer Legal Name:	B & B Body & Frame, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010

B & B BODY & FRAME (Continued) **S102749761**

Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600407399
Customer Name:	B & B BODY & FRAME INC
Customer Legal Name:	B & B Body & Frame, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605105246
Customer Name:	SERVICE KING PAINT & BODY LLC
Customer Legal Name:	Service King Paint & Body, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/31/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605105246
Customer Name:	SERVICE KING PAINT & BODY LLC
Customer Legal Name:	Service King Paint & Body, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/31/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600407399

B & B BODY & FRAME (Continued) **S102749761**

Customer Name:	B & B BODY & FRAME INC
Customer Legal Name:	B & B Body & Frame, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600407399
Customer Name:	B & B BODY & FRAME INC
Customer Legal Name:	B & B Body & Frame, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605105246
Customer Name:	SERVICE KING PAINT & BODY LLC
Customer Legal Name:	Service King Paint & Body, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/31/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

Regulated Entity Number:	RN102862802
Name:	B AND B BODY AND FRAME
Address:	6518 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4010
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605105246
Customer Name:	SERVICE KING PAINT & BODY LLC
Customer Legal Name:	Service King Paint & Body, LLC
Customer Ownership Type:	CORPORATION

B & B BODY & FRAME (Continued) **S102749761**

Affiliation Begin Date:	10/31/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6518 N LAMAR, AUSTIN, TX 78752

AH1149 **B & B BODY & FRAME INC** **RCRA NonGen / NLR** **1000104989**
WNW **6518 N LAMAR** **TXD026010579**
< 1/8 **AUSTIN, TX 78752**
0.014 mi.
74 ft. **Site 8 of 8 in cluster AH**

Actual:
714 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20010127
Handler Name:	B & B Body & Frame Inc
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD026010579
Contact Name:	REX WOMBLE
Contact Address:	N LAMAR
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-454-0461
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	B & B Body & Frame Inc
Owner Type:	Private
Operator Name:	B & B Body & Frame Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

B & B BODY & FRAME INC (Continued) **1000104989**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060411
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D022
Waste Description:	Chloroform
Waste Code:	D028
Waste Description:	1,2-Dichloroethane
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent

B & B BODY & FRAME INC (Continued) **1000104989**

Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: B & B BODY & FRAME INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	6518 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-0461
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: B & B BODY & FRAME INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	6518 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-0461
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: COLLISION TEAM OF AMERICA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	500 E OHIO ST
Owner/Operator City,State,Zip:	INDIANAPOLIS, IN 46204
Owner/Operator Telephone:	317-630-5030
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19980813
Handler Name: B & B BODY AND PAINT MAIN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

B & B BODY & FRAME INC (Continued) **1000104989**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010127
Handler Name: B & B BODY & FRAME INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

HA1150 **CECILS WRECKER SERV** **EDR Hist Auto** **1013756609**
WNW **4404 CONGRESS AVE S** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.014 mi.
74 ft. **Site 2 of 4 in cluster HA**

Actual:
649 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1980	CECILS WRECKER SERV	AUTOMOBILE REPAIRING
1984	CECILS WRECKER SERVICE INC	AUTOMOBILE REPAIRING

1151 **FORMER AUTO SALES FAC** **TX RDR** **S127542346**
NE **118 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
74 ft.

Actual:
449 ft.

RDR:

Focus Map:
14

RDR ID:	14298
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FORMER AUTO SALES FAC
Address:	118 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX

FORMER AUTO SALES FAC (Continued) **S127542346**

Date Report Received:	3/7/2005
Due Date:	5/6/2005
Tank Owner:	TXDOT
Contact Person:	DOUG MACK
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	5/4/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	116468
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?;LAD NOAPAR SENT 5/9/05
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

II1152 **CALIBER COLLISION NORTH LAMAR** **TX Ind. Haz Waste** **S110294260**
SE **8735 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.014 mi.
74 ft. **Site 1 of 4 in cluster II**

Actual:
666 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	CALIBER COLLISION NORTH LAMAR
Address:	8735 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	76136
Registration Initial Notification Date:	03/30/1990
Registration Last Amendment Date:	01/28/2002
EPA Identification:	TXD102730967
Primary NAICS Code:	Not reported
Status Change Date:	19900330
Land Type:	PRIVATE
Description of Facility Site Location:	8735 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	BODY-TEK
Contact Name:	CLEON NETTLES
Contact Telephone Number:	512-8360163
Mailing Address:	8735 N LAMAR BLVD
Mailing Address2:	Not reported

CALIBER COLLISION NORTH LAMAR (Continued) **S110294260**

Mailing City,State,Zip:	AUSTIN, TX 787535423
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30464
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110421
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BODY-TEK
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	CALIBER BODYWORKS OF TEXAS INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17527278083
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BODY-TEK
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported

CALIBER COLLISION NORTH LAMAR (Continued) **S110294260**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported
Owner Name:	CALIBER BODYWORKS OF TEXAS INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17527278083
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	CLEON NETTLES
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8735 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8360163
Contact Fax:	Not reported
Contact Email:	Not reported

II1153 **CALIBER COLLISION CENTERS** **RCRA NonGen / NLR** **1004784336**
SE **8735 N LAMAR BLVD** **FINDS** **TXD102730967**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.014 mi.
74 ft. **Site 2 of 4 in cluster II**

Actual:
666 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20020128
Handler Name:	Caliber Collision Centers
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD102730967
Contact Name:	CLEON NETTLES
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-836-0163
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CALIBER COLLISION CENTERS (Continued) **1004784336**

Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Caliber Bodyworks Of Texas Inc
Owner Type:	Private
Operator Name:	Caliber Bodyworks Of Texas Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste

CALIBER COLLISION CENTERS (Continued) **1004784336**

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CALIBER BODYWORKS OF TEXAS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: 8735 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-836-0163
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: VPH INC

CALIBER COLLISION CENTERS (Continued) **1004784336**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	8735 NO LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753-0000
Owner/Operator Telephone:	512-836-0163
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CALIBER BODYWORKS OF TEXAS INC
Legal Status:	Private
Date Became Current:	20020128
Date Ended Current:	Not reported
Owner/Operator Address:	8735 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78753
Owner/Operator Telephone:	512-836-0163
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19910430
Handler Name:	CAILBER BODYWORKS OF TEXAS INC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020128
Handler Name:	CALIBER COLLISION CENTERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CALIBER COLLISION CENTERS (Continued) **1004784336**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005070270

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004784336
Registry ID:	110005070270
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005070270
Name:	CALIBER COLLISION CENTERS
Address:	8735 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

II1154 **DUPLICATE OF 76136** **TX Ind. Haz Waste** **S103609431**
SE **8735 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.014 mi.
74 ft. **Site 3 of 4 in cluster II**

Actual:
666 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	DUPLICATE OF 76136
Address:	8735 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66257
Registration Initial Notification Date:	08/16/1984
Registration Last Amendment Date:	01/07/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19840816
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

DUPLICATE OF 76136 (Continued) **S103609431**

Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	JUDD AUTOBODY INC
Contact Name:	PAUL PAYNE
Contact Telephone Number:	512-8366077
Mailing Address:	8735 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535423
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21542
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JUDD AUTOBODY INC
Operator Address:	8735 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8366077
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17526863539
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JUDD AUTOBODY INC
Owner Mailing Address:	8735 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8366077
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17526863539
Owner Bankruptcy Code:	Not reported

DUPLICATE OF 76136 (Continued) **S103609431**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8735 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8366077
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8735 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8366077
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	PAUL PAYNE
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	8735 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8366077
Contact Fax:	Not reported
Contact Email:	Not reported

II1155 **MAACO** **TX Ind. Haz Waste** **S110293975**
SE **8735 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.014 mi.
74 ft. **Site 4 of 4 in cluster II**

Actual:
666 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	MAACO
Address:	8735 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66188
Registration Initial Notification Date:	09/18/1984
Registration Last Amendment Date:	06/04/2010
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19840918
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported

MAACO (Continued) **S110293975**

Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MAACO
Contact Name:	PAUL PAYNE
Contact Telephone Number:	512-8366077
Mailing Address:	8735 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787535423
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21484
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	MAACO
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	PAUL PAYNE
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	8735 N LAMAR BLVD
Contact Address 2:	Not reported

MAACO (Continued) **S110293975**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8366077
Contact Fax:	Not reported
Contact Email:	Not reported

AG1156 **B LAMAR CINS NO** **EDR Hist Cleaner** **1013778619**
WNW **812 BRANTWOOD ST** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
74 ft. **Site 11 of 14 in cluster AG**

Actual:
713 ft.

Focus Map:
6

EDR Hist Cleaner

Year:	Name:	Type:
1953	TURNER CLEANERS	CLEANERS AND DYERS
1958	B LAMAR CINS NO	CLEANERS AND DYERS
1962	B PERFECTO CLN NO 3	CLEANERS AND DYERS
1965	PERFECTO CLEANERS NO	CLEANERS AND DYERS

HJ1157 **LUCKY FOOD STORE** **TX UST** **U001246995**
WNW **5800 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX ASBESTOS**
0.014 mi. **TX Financial Assurance**
74 ft. **Site 3 of 3 in cluster HJ**

Actual:
633 ft.

Focus Map:
17

UST:

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787454131
AI Number:	11001
Facility Type:	RETAIL
Facility Begin Date:	08/31/1990
Facility Status:	ACTIVE
Additional ID:	890794852002068
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/15/2022
Signature Name/Title On Earliest Reg Form:	ASHRAF SURANI,

LUCKY FOOD STORE (Continued) **U001246995**

Application Received Date On Earliest Reg Form:	02/24/2022
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	145357082009181
Additional ID:	890794852002068
Ai Number:	11001
Operator CN:	CN603502196
Operator Name:	LUCKY ASSOCIATES INC
Operator Effective Begin Date:	04/01/1995
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605872241
Owner Last Name:	SURANI
Owner First Name:	ASHRAF
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	869406582021085
Additional ID:	890794852002068
AI Number:	11001
Owner Effective Begin Date:	03/01/2021
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Self Certification:

Self Cert ID:	67437
Cert ID:	368014
AI Number:	11001
Self Certification Date:	02/15/2022
Signature Name/Title:	ASHRAF SURANI
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	352117
AI Number:	11001
Self Certification Date:	03/15/2021
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	335476
AI Number:	11001
Self Certification Date:	03/25/2020
Signature Name/Title:	ASHRAF HIRANI PRESIDENT
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	318892
AI Number:	11001
Self Certification Date:	03/23/2019
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	302054
AI Number:	11001
Self Certification Date:	03/25/2018
Signature Name/Title:	ASHRAF SURANI REP
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	284819
AI Number:	11001
Self Certification Date:	03/25/2017
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	267858
AI Number:	11001
Self Certification Date:	03/18/2016
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	251523
AI Number:	11001
Self Certification Date:	03/23/2015
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	67437
Cert ID:	234325
AI Number:	11001
Self Certification Date:	03/18/2014
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	218625
AI Number:	11001
Self Certification Date:	03/25/2013
Signature Name/Title:	ASHRAF SURANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	67437
Cert ID:	84002
AI Number:	11001
Self Certification Date:	04/01/2012
Signature Name/Title:	ASHRAF SURANI VP
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	84001
AI Number:	11001
Self Certification Date:	03/22/2011
Signature Name/Title:	ASHRAF SURANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	84000
AI Number:	11001
Self Certification Date:	04/01/2010
Signature Name/Title:	ASGRAF SURAN VP
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83999
AI Number:	11001
Self Certification Date:	03/01/2009
Signature Name/Title:	NAUSHAD HIRANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83998
AI Number:	11001
Self Certification Date:	04/30/2008
Signature Name/Title:	NAUSHAD HIRANI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	83997
AI Number:	11001
Self Certification Date:	03/01/2007
Signature Name/Title:	NAUSHAD HIRANI PRESIDENT
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83996
AI Number:	11001
Self Certification Date:	03/01/2006
Signature Name/Title:	ASHRAF URANI
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83995
AI Number:	11001
Self Certification Date:	04/04/2005
Signature Name/Title:	NAUSHAD HIRANI MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Self Cert ID:	67437
Cert ID:	83994
AI Number:	11001
Self Certification Date:	04/25/2004
Signature Name/Title:	NAUSHAD HIRANI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83993
AI Number:	11001
Self Certification Date:	06/09/2003
Signature Name/Title:	ASHRAF SURANI
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67437
Cert ID:	83992
AI Number:	11001
Self Certification Date:	04/30/2001
Signature Name/Title:	NAVISHAD HIRANI MANAGER
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Tank:

Install Date:	04/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28929
Facility ID:	67437
Ai Number:	11001
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/23/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

LUCKY FOOD STORE (Continued) **U001246995**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	90720
UST ID:	28929
AI Number:	11001
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	03/23/1999
Tank Registration Date:	03/26/1999
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S

LUCKY FOOD STORE (Continued) **U001246995**

UST ID:	190564
Facility ID:	67437
Ai Number:	11001
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	03/23/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/23/1999

Compartment Records:

Tank ID:	1

LUCKY FOOD STORE (Continued) **U001246995**

Tank Capacity:	8000
UST Comprt ID:	90722
UST ID:	190564
AI Number:	11001
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	90723
UST ID:	190564
AI Number:	11001
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

LUCKY FOOD STORE (Continued) **U001246995**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28930
Facility ID:	67437
Ai Number:	11001
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/23/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

LUCKY FOOD STORE (Continued) **U001246995**

Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	6000
UST Comprt ID:	90721
UST ID:	28930
AI Number:	11001
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N

LUCKY FOOD STORE (Continued) **U001246995**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	9142
Facility ID:	67437
AI Number:	11001
Application Received Date:	11/01/2001
Scheduled Construction Date:	11/12/2001
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M01101004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	57714
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	28937
UST ID:	28930
NOC ID:	Not reported
AI Number:	11001
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	28938
UST ID:	190564
NOC ID:	Not reported
AI Number:	11001
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Excell Enviromental
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	9805
UST ID:	Not reported
NOC ID:	9142
AI Number:	11001
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	44110
UST ID:	190564
NOC ID:	Not reported
AI Number:	11001
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	Not reported
Representative Name:	RICHARD ROLLINS S
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	44109
UST ID:	28930
NOC ID:	Not reported
AI Number:	11001
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Facility Billing Contacts:

Contact Organization Name:	ASHRAF SURANI
Contact Mailing Address (Delivery):	5800 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 4131
Phone Number/Ext:	512 6333873/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	67437
Additional ID:	890794852002068
Princ ID:	869406582021085
AI Number:	11001
Facility Name:	LUCKY FOOD STORE
AR Number:	82543
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ASHRAF SURANI/OWNER

HIST UST AUSTIN:

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	647
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/06/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/11/2013
Date Routed by Supervisor:	02/11/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2014
Date Routed by Supervisor:	03/04/2014
Date Routed to PSQA:	03/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

TX Financial Assurance 2:

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	265624
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2021
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24765751 009
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	248035
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2020
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24765751008
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	230313
AI:	11001
Mechanism Type Other:	Not reported

LUCKY FOOD STORE (Continued) **U001246995**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2019
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24765751 007
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	212414
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2018
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24765751 006
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	195255
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2017
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO

LUCKY FOOD STORE (Continued) **U001246995**

Issuer Phone:	1 215 6401000
Policy Number:	G24765751 005
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	177658
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2016
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24765751 004
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	159572
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2015
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24765751003
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE

LUCKY FOOD STORE (Continued) **U001246995**

City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	142594
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2014
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24765751002
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	125429
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2013
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 9514119
Policy Number:	G24765751001
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	107082
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y

LUCKY FOOD STORE (Continued) **U001246995**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2012
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9424259-04
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	6509
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2011
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9424259 04
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/21/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	52846
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2010
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9424259 03
Coverage Amount:	1000000

LUCKY FOOD STORE (Continued) **U001246995**

Coverage Expiration Date:	09/21/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	52847
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2010
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9424259 02
Coverage Amount:	1000000
Coverage Expiration Date:	09/21/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	52848
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2009
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9424259 01
Coverage Amount:	1000000
Coverage Expiration Date:	09/21/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437

LUCKY FOOD STORE (Continued) **U001246995**

Finass ID:	52849
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/21/2008
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 9873371
Policy Number:	USC 9424259 00
Coverage Amount:	1000000
Coverage Expiration Date:	09/21/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	LUCKY FOOD STORE
Address:	5800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	67437
Finass ID:	52850
AI:	11001
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	02/24/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

DP1158 **KLUGE M C AUTO REPR** **EDR Hist Auto** **1013754720**
NNE **214 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 8 of 16 in cluster DP**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	KLUGE M C AUTO REPR	AUTOMOBILE REPAIRERS

1159 ESE < 1/8 0.014 mi. 75 ft. | **U S P & F O FOR TX 35TH AUSTIN, TX** | **TX UST** | **U001267971 N/A**

Actual: 612 ft.

Focus Map: 8

UST:

Name:	U S P & F O FOR TX
Address:	35TH
City,State,Zip:	AUSTIN, TX
AI Number:	34980
Facility Type:	UNKNOWN
Facility Begin Date:	12/10/1986
Facility Status:	INACTIVE
Additional ID:	958609872002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	35TH
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	U S P & F O FOR TX
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7137543709
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1986
Signature Name/Title On Earliest Reg Form:	H J ODONNELL,ENG
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600132484
Owner Last Name:	CHEVRON USA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	329482572001157
Additional ID:	958609872002156

U S P & F O FOR TX (Continued) **U001267971**

AI Number:	34980
Owner Effective Begin Date:	12/10/1986
State Tax ID:	12505279252
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92462
Facility ID:	63753
Ai Number:	34980
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

U S P & F O FOR TX (Continued) **U001267971**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	74510
UST ID:	92462
AI Number:	34980
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

U S P & F O FOR TX (Continued) **U001267971**

More Self Certification:

Self Cert ID:	13523
Cert ID:	126430
UST Comprt ID:	367168
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	249130
UST Comprt ID:	716164
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126429
UST Comprt ID:	367167
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126433
UST Comprt ID:	367163
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126428
UST Comprt ID:	367166
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126439
UST Comprt ID:	367157
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	367235
UST Comprt ID:	1069277
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A

U S P & F O FOR TX (Continued) **U001267971**

Self Cert ID:	13523
Cert ID:	126432
UST Comprt ID:	367164
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	352395
UST Comprt ID:	1024608
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126435
UST Comprt ID:	367161
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	346676
UST Comprt ID:	1007304
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126431
UST Comprt ID:	367165
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126440
UST Comprt ID:	367156
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	334628
UST Comprt ID:	970553
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523

U S P & F O FOR TX (Continued) **U001267971**

Cert ID:	317103
UST Comprt ID:	918238
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126437
UST Comprt ID:	367159
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126434
UST Comprt ID:	367162
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	300840
UST Comprt ID:	869909
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	283282
UST Comprt ID:	817292
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126436
UST Comprt ID:	367160
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126438
UST Comprt ID:	367158
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	264998

U S P & F O FOR TX (Continued) **U001267971**

UST Comprt ID:	763307
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	232577
UST Comprt ID:	667844
UST ID:	118685
AI Number:	34980
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CHEVRON USA INC
Contact Mailing Address (Delivery):	PO BOX 6004
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN RAMON, CA 94583 0904
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	63753
Additional ID:	958609872002156
Princ ID:	329482572001157
AI Number:	34980
Facility Name:	U S P & F O FOR TX
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PERMIT DESK/

GO1160 **ENVIRONMENTAL IMPACT** **TX LPST** **S105121946**
WNW **3800 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.014 mi.
75 ft. **Site 3 of 4 in cluster GO**

Actual:
631 ft.

Focus Map:
14

LPST:

Name:	ENVIRONMENTAL IMPACT
Address:	3800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	Not reported
LPST Id:	114811
Facility Location:	3800 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	12/31/3000
Entered Date:	01/27/2000
Reported Date:	12/31/3000
Closure Date:	06/27/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED

ENVIRONMENTAL IMPACT (Continued) **S105121946**

Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3
Coordinators RPR:	SLR
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	CORRECTIVE ACTION
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	/-
Reported Date:	12/31/3000
Case Start Date:	06/27/2001
Reference Number:	RN106987282
Project Manager:	SLR

DF1161 **RIOS ALPHONSO TAILOR** **EDR Hist Cleaner** **1013777757**
ESE **706 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 6 of 25 in cluster DF**

Actual:
500 ft. EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	RIOS ALPHONSO TAILOR	CLOTHES PRESSERS AND CLEANERS

1162 **COLLEGE HOUSES** **US BROWNFIELDS FINDS** **1026004482**
East **707 W. 21ST ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.014 mi.
75 ft.

Actual:
583 ft. US BROWNFIELDS:

Focus Map:
11

Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM

COLLEGE HOUSES (Continued) **1026004482**

standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.

Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	500000
Redev. Funding Source:	City of Austin Neighborhood Housing
Redev. Funding Entity Name:	Local Funding
Redevelopment Start Date:	6/1/2019
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	86
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

COLLEGE HOUSES (Continued) **1026004482**

Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57
Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.

COLLEGE HOUSES (Continued) **1026004482**

Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student

COLLEGE HOUSES (Continued) **1026004482**

housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.

Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57

Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

COLLEGE HOUSES (Continued) **1026004482**

Assessment Funding:	4059
Assessment Funding Source:	City of Austin Brownfields
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	6/14/2019
Ownership Entity:	Private
Completion Date:	9/30/2019
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194

COLLEGE HOUSES (Continued) **1026004482**

Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57
Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4059
Assessment Funding Source:	City of Austin Brownfields
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous

COLLEGE HOUSES (Continued) **1026004482**

Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	6/14/2019
Ownership Entity:	Private
Completion Date:	9/30/2019
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57
Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of

COLLEGE HOUSES (Continued) **1026004482**

Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	890000
Redev. Funding Source:	College Houses
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	6/1/2019
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N

COLLEGE HOUSES (Continued) **1026004482**

Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	86
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57

Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported

COLLEGE HOUSES (Continued) **1026004482**

Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6914
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	2/21/2019
Ownership Entity:	Private
Completion Date:	9/12/2019
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

COLLEGE HOUSES (Continued) **1026004482**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57
Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A

COLLEGE HOUSES (Continued) **1026004482**

vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.

Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6914
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	2/21/2019
Ownership Entity:	Private
Completion Date:	9/12/2019
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25

COLLEGE HOUSES (Continued) **1026004482**

Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57

Name:	COLLEGE HOUSES
Address:	707 W. 21ST ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.284028
Longitude:	-97.745713
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	College Houses provides affordable housing for college students near the University of Texas at Austin. They are looking to expand and renovate their 21st Street cooperative. To complete the renovations, they have applied for HUD funding through the City of Austin Neighborhood Housing and Community Development (NHCD), which requires a Phase I ESA as part of the due diligence in the application process. The Phase I ESA was completed in April 2019. The Phase I ESA identified historical dry cleaners in the vicinity of the property, and subsequent concerns about potential subsurface vapor issues. A vapor encroachment survey was recommended to determine if the property was affected by volatile organic compounds from dry cleaners. Samples were collected and analyzed following the ASTM standard (E2600) using City of Austin funds. None of the samples analyzed had exceedances, and no further action is anticipated at this time. Former Use: The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with

COLLEGE HOUSES (Continued) **1026004482**

wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.

Datum:	Not reported
Acres Property ID:	240348
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	College Houses
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.25
Past use residential acreage:	1.75
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.25
Future use residential acreage:	1.75
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported

COLLEGE HOUSES (Continued) **1026004482**

Past Use: Multistory	Not reported
Property Description:	The 21st Street Coop was built in 1974 as the first structure in Austin designed and constructed specifically for use as a student housing coop. This multi-family structure features a "treehouse" inspired design, with five separate buildings joined with wooden walkways surrounding a central courtyard of green space. This creative architecture lends 21st Street Coop a true feeling of community, making it much more than affordable student housing.
Below Poverty Number:	6263
Below Poverty Percent:	53.08
Meidan Income:	3930
Meidan Income Number:	7194
Meidan Income Percent:	60.97
Vacant Housing Number:	586
Vacant Housing Percent:	14.04
Unemployed Number:	775
Unemployed Percent:	6.57

FINDS:
Registry ID: 110070629145

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AL1163 **KISHAN FOOD STOP 417** **TX RDR** **S127525239**
WNW **5630 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 3 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

RDR:

RDR ID:	16810
Facility ID:	15562
RN:	Not reported
CN:	Not reported
Name:	KISHAN FOOD STOP 417
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/3/2007
Due Date:	2/1/2008
Tank Owner:	METRO SUPPLIERS INC
Contact Person:	CLIFF SNYDER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/27/2008
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported

KISHAN FOOD STOP 417 (Continued) **S127525239**

Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/27/2008
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AL1164 **7-ELEVEN #36653** **TX HIST UST** **S128728613**
WNW **5630 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 4 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	7-ELEVEN #36653
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1465
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AL1165 **BRITTS AUTOMOTIVE** **TX RDR** **S127525238**
WNW **5630 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 5 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

RDR:

RDR ID:	939
Facility ID:	15562
RN:	Not reported
CN:	Not reported
Name:	BRITTS AUTOMOTIVE
Address:	5630 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/15/2000
Due Date:	8/14/2000
Tank Owner:	METRO SUPPLIERS INC
Contact Person:	DOUG SCHRAM
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Paula Gonzalez
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	91290
Comments:	6A; DOES THIS NEED A NEW LPST # OR REOPEN OLD
Review Coordinator:	PHG
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported

BRITTS AUTOMOTIVE (Continued) **S127525238**

DKC RDR (misfiled): Not reported

AL1166 **7 ELEVEN STORE 36653 TP 2524** **TX LPST** **U003103741**
WNW **5630 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78751** **TX Financial Assurance**
0.014 mi.
75 ft. **Site 6 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

LPST:

Name:	3 STAR TEXACO
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0015562
LPST Id:	091290
Facility Location:	5630 N LAMAR BLVD @ OLD KOENIG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/15/1985
Entered Date:	08/11/1986
Reported Date:	08/11/1986
Closure Date:	06/25/2003
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3/2
Coordinators RPR:	RWS
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	1100 GATTIS SCHOOL STE 300B
Responsible Party City,St,Zip:	ROUNDROCK, TX 78664
Responsible Party Telephone:	/-
Reported Date:	08/11/1986
Case Start Date:	06/25/2003
Reference Number:	RN101488583
Project Manager:	RSHAVER

UST:

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511018
AI Number:	15562
Facility Type:	RETAIL
Facility Begin Date:	08/18/1986
Facility Status:	ACTIVE
Additional ID:	486505372002053
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	PEGGIE BETZ,

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Contact Organization Name:	7-ELEVEN 15562
Contact Mailing Address1:	5630 N LAMAR BLVD
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787511018
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/12/2014
Signature Name/Title On Earliest Reg Form:	RAYMON MCNIECE,
Application Received Date On Earliest Reg Form:	05/15/2014
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	961346052007212
Additional ID:	486505372002053
Ai Number:	15562
Operator CN:	CN603223793
Operator Name:	THOMAS PETROLEUM LLC
Operator Effective Begin Date:	12/28/2012
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	486505372002053
AI Number:	15562
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	54258
Cert ID:	381690
AI Number:	15562
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	54258
Cert ID:	364367
AI Number:	15562
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	54258
Cert ID:	348219
AI Number:	15562
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	329987
AI Number:	15562
Self Certification Date:	01/03/2020
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	314466
AI Number:	15562
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	296033
AI Number:	15562
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	280990
AI Number:	15562
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	263849
AI Number:	15562
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	246786
AI Number:	15562
Self Certification Date:	01/15/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	230755
AI Number:	15562
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	54258
Cert ID:	46257
AI Number:	15562
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46256
AI Number:	15562
Self Certification Date:	02/20/2012
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46255
AI Number:	15562
Self Certification Date:	02/28/2011
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46254
AI Number:	15562
Self Certification Date:	02/15/2010
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46253
AI Number:	15562
Self Certification Date:	11/05/2008
Signature Name/Title:	JEFF JOHANSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	54258
Cert ID:	46073
AI Number:	15562
Self Certification Date:	11/04/2008
Signature Name/Title:	JEFF JOHANSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	54258
Cert ID:	46072
AI Number:	15562
Self Certification Date:	07/18/2007
Signature Name/Title:	CLIFF SNYDER CFO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	54258
Cert ID:	46071
AI Number:	15562
Self Certification Date:	04/03/2006
Signature Name/Title:	DOUGLAS SCHRAM OPERATIONS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46070
AI Number:	15562
Self Certification Date:	04/12/2005
Signature Name/Title:	DOUGLAS G SCHRAM OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46069
AI Number:	15562
Self Certification Date:	03/01/2004
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46068
AI Number:	15562
Self Certification Date:	03/04/2003
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46067
AI Number:	15562
Self Certification Date:	02/13/2002
Signature Name/Title:	DOUGLAS G SCHRAM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	54258
Cert ID:	46066
AI Number:	15562
Self Certification Date:	10/03/2000
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

UST ID:	39867
Facility ID:	54258
Ai Number:	15562
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	2

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Tank Capacity:	4000
UST Comprt ID:	52814
UST ID:	39867
AI Number:	15562
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	174697
Facility ID:	54258
Ai Number:	15562
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/07/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	52817
UST ID:	174697
AI Number:	15562
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	39869
Facility ID:	54258
Ai Number:	15562
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	52816
UST ID:	39869
AI Number:	15562
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	39868
Facility ID:	54258
Ai Number:	15562
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	52815
UST ID:	39868
AI Number:	15562
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	37304
Facility ID:	54258
AI Number:	15562
Application Received Date:	11/18/2020
Scheduled Construction Date:	11/23/2020
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	4547
Facility ID:	54258
AI Number:	15562
Application Received Date:	07/22/2005
Scheduled Construction Date:	08/20/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50722006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	47654
General Desc Of Prop Construct:	Not reported

NOC ID:	4546
Facility ID:	54258
AI Number:	15562
Application Received Date:	03/03/2000
Scheduled Construction Date:	03/02/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00303007
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	47654
General Desc Of Prop Construct:	Not reported

NOC ID:	4545
Facility ID:	54258
AI Number:	15562
Application Received Date:	02/09/2009
Scheduled Construction Date:	02/11/2009
UST Improvement:	Y
UST Installation:	N
UST Removal:	N

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90209005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	7636
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	88556
UST ID:	Not reported
NOC ID:	37304
AI Number:	15562
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	KIM TAPIA
Mailing Address (Delivery):	12005 FORD RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738400
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	0
Fax Number:	0
Email Address:	KTAPIA@APTIM.COM

Cont/Cons/Installer ID:	4917
UST ID:	Not reported
NOC ID:	4545
AI Number:	15562
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	4918
UST ID:	Not reported
NOC ID:	4546
AI Number:	15562
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	4919
UST ID:	Not reported
NOC ID:	4547
AI Number:	15562
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	88555
UST ID:	Not reported
NOC ID:	37304
AI Number:	15562
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	NLAWSON@MCCONBUILDING.COM

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	54258
Additional ID:	486505372002053
Princ ID:	959578622001257
AI Number:	15562
Facility Name:	7 ELEVEN STORE 36653 TP 2524
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

TX Financial Assurance 2:

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	278815
AI:	15562

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	261665
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	241683
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	05/15/2014

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	223628
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	224228
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	207388
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	188926
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	172687
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	154586
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	137925
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	120933
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	3801
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Facility ID:	54258
Finass ID:	38616
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2011
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	38617
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2010
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	38618
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2009
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	38619
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2008
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 0 0
Policy Number:	17722
Coverage Amount:	2000000
Coverage Expiration Date:	12/31/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN STORE 36653 TP 2524
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	54258
Finass ID:	38620
AI:	15562
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/15/2014
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No

7 ELEVEN STORE 36653 TP 2524 (Continued) **U003103741**

Proof of Financial Assurance: No

AL1167 **GRAPETTE BOTTLING COMPANY** **TX HIST UST** **S128729298**
WNW **5630 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 7 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	GRAPETTE BOTTLING COMPANY
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0500
HID UST:	500
Inspection:	05/25/2011
Due:	05/25/2014

AL1168 **7-ELEVEN INC STORE NO 36653** **TX RDR** **S127525237**
WNW **5630 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 8 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

RDR:

RDR ID:	30077
Facility ID:	15562
RN:	101488583
CN:	600240329
Name:	7-ELEVEN INC STORE NO 36653
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/28/2022
Due Date:	4/29/2022
Tank Owner:	7-ELEVEN INC
Contact Person:	SHELLENA HUSSEIN
Report:	Suspected Release
Latest TCEQ Letter:	No Leaker - 6A
Date of Latest TCEQ Letter:	4/13/2022
Project Manager:	Corbin Reyes
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORIG REC 05/03/2021; NOD 06/23/2021
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AL1169 **HEBERT MOBIL STA** **EDR Hist Auto** **1013753185**
WNW **5630 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.014 mi.
75 ft. **Site 9 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1962	BACHS MOBIL SERV	GASOLINE STATIONS
1965	TOM & JERRYS MOBIL	GASOLINE STATIONS
1970	HEBERT MOBIL STA	GASOLINE STATIONS
1975	DON HARRIS MOBILE SERVICE	GASOLINE STATIONS
1980	HARRIS DON MOBIL SERV	GASOLINE STATIONS
1980	HARRIS DON MOBIL SERVICE STN	Gasoline Service Stations
1982	HARRIS DON MBL SVC STA	Gasoline Service Stations
1983	HARRIS DON MBL SVC STA	Gasoline Service Stations
1984	HARRIS DON MOBIL SERVICE	GASOLINE STATIONS
1985	DARRELLS AUTO REPAIR	General Automotive Repair Shops
1985	HARRIS DON MBL SVC STA	Gasoline Service Stations
1986	DARRELLS AUTO REPAIR	General Automotive Repair Shops
1987	DARRELLS AUTO REPAIR	General Automotive Repair Shops
1988	DARRELLS AUTO REPAIR	General Automotive Repair Shops
1988	JAMES B DARRELL	General Automotive Repair Shops
1990	SAPP TEXACO SERVICE STATION	GASOLINE STATIONS
1991	FRANKLIN SERVICE STATIONS INC	Gasoline Service Stations
1992	FRANKLIN SERVICE STATIONS INC	Gasoline Service Stations
1993	FRANKLIN SERVICE STATIONS INC	Gasoline Service Stations
1994	FRANKLIN SERVICE STATIONS INC	Gasoline Service Stations
1995	FRANKLIN SERVICE STATIONS INC	Gasoline Service Stations
1996	SHEPPARD CHRIS	Gasoline Service Stations
1997	SHEPPARD CHRIS	Gasoline Service Stations
2000	KINSEY BRITT	General Automotive Repair Shops
2001	KINSEY BRITT	General Automotive Repair Shops
2002	KINSEY BRITT	General Automotive Repair Shops
2003	KINSEY BRITT	General Automotive Repair Shops
2004	KINSEY BRITT	General Automotive Repair Shops

AL1170 **7 ELEVEN STORE 36653** **TX LPST** **S118903914**
WNW **5630 N LAMAR BLVD** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX** **TX RDR**
0.014 mi.
75 ft. **Site 10 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

LPST:

Name:	7 ELEVEN STORE 36653
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120052
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	07/15/2016
Entered Date:	10/14/2016
Reported Date:	07/18/2016
Closure Date:	10/22/2019
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED

7 ELEVEN STORE 36653 (Continued) **S118903914**

Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 07/18/2016
Case Start Date: 10/22/2019
Reference Number: RN101488583
Project Manager: RKRAFT

GCC:
Name: 7 ELEVEN STORE 36653
Address: 5630 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: *
File Number: 120052
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 7/18/2016
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 7 ELEVEN STORE 36653
Address: 5630 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 120052
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 7/18/2016
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 2/L2 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

RDR:

7 ELEVEN STORE 36653 (Continued) **S118903914**

RDR ID:	23930
Facility ID:	15562
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 36653
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/15/2016
Due Date:	10/14/2016
Tank Owner:	7 ELEVEN INC
Contact Person:	JOSE RIOS
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/14/2016
Project Manager:	Ryan Kraft
Team:	#N/A
New LPST Number:	120052
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AL1171 **SOCONY MOBIL OIL CO.** **TX HIST UST** **S128729415**
WNW **5630 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
75 ft. **Site 11 of 13 in cluster AL**

Actual:
697 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	SOCONY MOBIL OIL CO.
Address:	5630 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0781
HID UST:	781
Inspection:	05/25/2011
Due:	05/25/2014

DM1172 **TOLSON OIL CO NO** **EDR Hist Auto** **1013773838**
NNE **409 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.014 mi.
76 ft. **Site 9 of 22 in cluster DM**

Actual:
492 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1970	TOLSON OIL CO NO	GASOLINE STATIONS

EE1173 **SCHWABE AUTOMOTIVE REPRS** **EDR Hist Auto** **1013770342**
WNW **104 TRINITY ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.014 mi.
76 ft. **Site 2 of 4 in cluster EE**

Actual:
470 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1970	SCHWABE AUTOMOTIVE R IEPR	AUTOMOBILE REPAIRING
1975	SCHWABE AUTOMOTIVE REPRS	AUTOMOBILE REPAIRING
1980	SCHWABE AUTOMOTIVE REPRS	AUTOMOBILE REPAIRING
1983	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1984	SCHWABE AUTOMOTIVE REPRS	AUTOMOBILE REPAIRING
1985	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1986	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1987	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1988	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1989	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1990	SCHWABE AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1991	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC

EE1174 **GLENNS GARAGE** **TX Ind. Haz Waste** **S102748139**
WNW **104 TRINITY ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.014 mi.
76 ft. **Site 3 of 4 in cluster EE**

Actual:
470 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	GLENNS GARAGE
Address:	104 TRINITY ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	61203
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	104 Trinity, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	GLENNS GARAGE
Contact Name:	GLENN SCHWABE
Contact Telephone Number:	Not reported
Mailing Address:	104 TRINITY ST
Mailing Address2:	Not reported

GLENNS GARAGE (Continued) **S102748139**

Mailing City,State,Zip:	AUSTIN, TX 787014113
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19562
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	GLENNS GARAGE
Operator Address:	104 TRINITY ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	GLENNS GARAGE
Owner Mailing Address:	104 TRINITY ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	104 TRINITY ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported

GLENNS GARAGE (Continued) **S102748139**

Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	104 TRINITY ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	GLENN SCHWABE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	104 TRINITY ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100652767
Name:	GLENNS GARAGE
Address:	104 TRINITY ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4113
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600362305
Customer Name:	GLENNS GARAGE
Customer Legal Name:	Glenn's Garage
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	104 Trinity, Austin, TX

DU1175 **REID GEO W AUTO** **EDR Hist Auto** **1013764475**
SW **503 NECHES** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
76 ft. **Site 7 of 19 in cluster DU**

Actual:
480 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	REID GEO W AUTO	AUTOMOBILE REPAIRING

DX1176 **CITY OF AUSTIN** **RCRA NonGen / NLR** **1000412194**
WNW **411 W 2ND ST** **FINDS** **TXD981901481**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.014 mi.
76 ft. **Site 6 of 7 in cluster DX**

Actual:
471 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	City Of Austin
Handler Address:	W 2ND ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981901481
Contact Name:	JIM ELMAN
Contact Address:	PO BOX 1088
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-499-8331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1088
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	City Of Austin
Owner Type:	Municipal
Operator Name:	City Of Austin
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CITY OF AUSTIN (Continued) **1000412194**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1088
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-499-8331
Owner/Operator Telephone Ext:	Not reported

CITY OF AUSTIN (Continued) **1000412194**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1088
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-499-8331
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960606
Handler Name: AUSTIN CITY BLDG MAINT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: CITY OF AUSTIN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005097402

CITY OF AUSTIN (Continued) **1000412194**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412194
Registry ID:	110005097402
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005097402
Name:	CITY OF AUSTIN
Address:	411 W 2ND ST
City,State,Zip:	AUSTIN, TX 78701

DX1177 **DEPT OF PUBLIC WORKS & TRANSPORATION** **TX Ind. Haz Waste** **S104854518**
WNW **411 W 2ND ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.014 mi.
76 ft. **Site 7 of 7 in cluster DX**

Actual:
471 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	DEPT OF PUBLIC WORKS & TRANSPORATION
Address:	411 W 2ND ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72382
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981901481
Primary NAICS Code:	Not reported
Status Change Date:	19870501
Land Type:	Not reported
Description of Facility Site Location:	411 W 2nd St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	CITY OF AUSTIN
Contact Name:	JIM ELMAN
Contact Telephone Number:	512-4998331
Mailing Address:	PO BOX 1088
Mailing Address2:	PUBLIC WORKS & TRANSPORATION

DEPT OF PUBLIC WORKS & TRANSPORATION (Continued) **S104854518**

Mailing City,State,Zip:	AUSTIN, TX 787671088
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26823
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031104
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	PO BOX 1088
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	1-512-4998331
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	PO BOX 1088
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	1-512-4998331
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 1088
Contact Address 2:	Not reported
Contact Address 3:	Not reported

DEPT OF PUBLIC WORKS & TRANSPORATION (Continued) **S104854518**

Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4998331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 1088
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4998331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JIM ELMAN
Contact Title:	ENVIRONMENTAL CONTACT
Contact Role:	PRICONT
Contact Address:	PO BOX 1088
Contact Address 2:	PUBLIC WORKS & TRANSPORATION
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4998331
Contact Fax:	Not reported
Contact Email:	Not reported

DH1178 **MARY LEE COMMUNITY** **US BROWNFIELDS FINDS** **1012101364**
ESE **600 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.014 mi.
76 ft. **Site 14 of 16 in cluster DH**

Actual:
496 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	MARY LEE COMMUNITY
Address:	600 CONGRESS AVE
Recipient name:	R6 TBA - Texas (Pre-law Superfund TBA)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	Not reported
Latitude:	30.2682277
Longitude:	-97.74303
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	10899
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1

MARY LEE COMMUNITY (Continued) **1012101364**

Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - TBA Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	8/15/2002
Ownership Entity:	Not reported
Completion Date:	8/15/2002
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	423
Below Poverty Percent:	13.87
Meidan Income:	15056
Meidan Income Number:	548
Meidan Income Percent:	17.97
Vacant Housing Number:	521
Vacant Housing Percent:	22.99
Unemployed Number:	199
Unemployed Percent:	6.53

MARY LEE COMMUNITY (Continued) **1012101364**

FINDS:
Registry ID: 110038743820

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.
Registry ID: 110070788678

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
SSTS (Section Seven Tracking System) evolved from the FIFRA and TSCA Enforcement System (FATES). SSTS tracks the registration of all pesticide-producing establishments and tracks annually the types and amounts of pesticides, active ingredients, and related devices that are produced, sold, or distributed each year.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DH1179 **BONILLA JOHN TAILOR** **EDR Hist Cleaner** **1013777307**
ESE **600 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.014 mi.
76 ft. **Site 15 of 16 in cluster DH**

Actual:
496 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	BONILLA JOHN TAILOR	CLOTHES CLEANERS AND PRESSERS
1988	HOUSTON VALET PARKING SERVICE	Garment Pressing And Cleaners' Agents
1989	PERFECT TOUCH CLEANERS	Power Laundries, Family And Commercial
1989	HOUSTON VALET PARKING SERVICE	Garment Pressing And Cleaners' Agents
1990	HOUSTON VALET PARKING SERVICE	Garment Pressing And Cleaners' Agents
1990	PERFECT TOUCH CLEANERS	Power Laundries, Family And Commercial
1991	PERFECT TOUCH CLEANERS	Power Laundries, Family And Commercial
1992	PERFECT TOUCH CLEANERS	Power Laundries, Family And Commercial

---

HD1180 **CAPITOL CARPET CLEANING** **EDR Hist Cleaner** **1013780082**
WNW **4506 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.014 mi.
76 ft. **Site 5 of 6 in cluster HD**

Actual:
645 ft.

EDR Hist Cleaner

Focus Map:
17

Year:	Name:	Type:
1990	CAPITOL CARPET CLEANING	CARPET AND RUG CLEANERS
1990	CAPITOL CARPET CLEANING INC	Carpet And Upholstery Cleaning On Customer Premises
1992	CAPITOL CARPET CLEANING INC	Carpet And Upholstery Cleaning On Customer Premises
1993	CAPITOL CARPET CLEANING INC	Carpet And Upholstery Cleaning On Customer Premises
1994	CAPITOL CARPET CLEANING INC	Carpet And Upholstery Cleaning On Customer Premises
1995	CAPITOL CARPET CLEANING INC	Carpet And Upholstery Cleaning On Customer Premises

HD1181 **WRECKER SERVICE** **TX UST** **U001292456**
WNW **4506 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.014 mi.
76 ft. **Site 6 of 6 in cluster HD**

Actual:
645 ft.

Focus Map:
17

UST:

Name:	WRECKER SERVICE
Address:	4506 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451979
AI Number:	63402
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/18/1996
Facility Status:	INACTIVE
Additional ID:	116737792002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	DEAN GOODNIGHT,
Contact Organization Name:	WRECKER SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124421471
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/24/1992
Signature Name/Title On Earliest Reg Form:	CHARLES GOODNIGHT,OWNER
Application Received Date On Earliest Reg Form:	07/30/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784979
Owner Last Name:	GOODNIGHT CHARLES
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	106737782002053
Additional ID:	116737792002053

WRECKER SERVICE (Continued) **U001292456**

AI Number:	63402
Owner Effective Begin Date:	01/18/1996
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/30/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146372
Facility ID:	94317
Ai Number:	63402
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

WRECKER SERVICE (Continued) **U001292456**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	163812
UST ID:	146372
AI Number:	63402
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

WRECKER SERVICE (Continued) **U001292456**

Facility Billing Contacts:

Contact Organization Name:	GOODNIGHT CHARLES
Contact Mailing Address (Delivery):	4700 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 2303
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94317
Additional ID:	116737792002053
Princ ID:	106737782002053
AI Number:	63402
Facility Name:	WRECKER SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DEAN GOODNIGHT/

HIST UST AUSTIN:

Name:	WRECKER SERVICE
Address:	4506 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0660
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IJ1182 **TIP TOP CLEANERS** **EDR Hist Cleaner** **1013782684**
WNW **3202 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.014 mi.
76 ft. **Site 1 of 4 in cluster IJ**

Actual:
594 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1990	C TIP TOP CLEANERS & LAUNDERERS	CLEANERS AND DYERS
1992	TIP TOP CLEANERS	Drycleaning Plants, Except Rugs
1993	TIP TOP CLEANERS	Drycleaning Plants, Except Rugs
1994	TIP TOP CLEANERS	Drycleaning Plants, Except Rugs
1995	T & T CLEANERS	Drycleaning Plants, Except Rugs
1996	T & T CLEANERS	Drycleaning Plants, Except Rugs
1997	T & T CLEANERS	Drycleaning Plants, Except Rugs

IK1183 ESE < 1/8 0.014 mi. 76 ft. | **GULF COAST COALITION CITIES**
816 CONGRESS AVE
AUSTIN, TX 78701
Site 1 of 5 in cluster IK | **EDR Hist Auto** | **1020596829**
N/A

Actual: 509 ft.
EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
2008	VALDEZ JERRY GOVTL AFFAIRS	General Automotive Repair Shops, NEC
2011	CU AUTO BIDS LLC	General Automotive Repair Shops
2012	CU AUTO BIDS LLC	General Automotive Repair Shops
2013	GULF COAST COALITION CITIES	Gasoline Service Stations, NEC
2014	GULF COAST COALITION CITIES	Gasoline Service Stations, NEC

IK1184 ESE < 1/8 0.014 mi. 76 ft. | **HONG WAH CHINESE LAUNDRY**
804 CONGRESS AVE
AUSTIN, TX
Site 2 of 5 in cluster IK | **EDR Hist Cleaner** | **1013786070**
N/A

Actual: 509 ft.
EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1896	HONG WAH CHINESE LAUNDRY	LAUNDRIES

GY1185 WNW < 1/8 0.015 mi. 77 ft. | **LAIDLAW TRANSIT**
4300 S CONGRESS
AUSTIN, TX 78745
Site 10 of 10 in cluster GY | **RCRA-SQG**
TX LPST
TX UST
TX HIST UST
FINDS
ECHO | **1000656202**
TXD988061685

Actual: 661 ft.
RCRA Listings:

Focus Map: 17

Date Form Received by Agency:	19920208
Handler Name:	Laidlaw Transit
Handler Address:	S CONGRESS
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD988061685
Contact Name:	PAT HARNEN
Contact Address:	4300 S CONGRESS
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-441-3544
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Laidlaw Transit

LAIDLAW TRANSIT (Continued) **1000656202**

Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LAIDLAW TRANSIT	
Legal Status:	Private

LAIDLAW TRANSIT (Continued) **1000656202**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4300 S CONGRESS
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-441-3544
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920208
Handler Name: LAIDLAW TRANSIT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

LPST:

Name:	LAIDLAW TRANSIT
Address:	4300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010025
LPST Id:	095787
Facility Location:	4300 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/17/1990
Entered Date:	06/13/1990
Reported Date:	04/17/1990
Closure Date:	10/19/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	PAT HARMON

LAIDLAW TRANSIT (Continued) **1000656202**

Responsible Party Address:	4300 S CONGRESS
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/441-3544
Reported Date:	04/17/1990
Case Start Date:	10/19/1990
Reference Number:	RN102024221
Project Manager:	HWELCH

Name:	LAIDLAW TRANSIT
Address:	4300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010025
LPST Id:	098480
Facility Location:	S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/01/1991
Entered Date:	04/04/1991
Reported Date:	04/01/1991
Closure Date:	11/20/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	PAT HARMON
Responsible Party Address:	4300 S CONGRESS
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/448-2294
Reported Date:	04/01/1991
Case Start Date:	11/20/1991
Reference Number:	RN102024221
Project Manager:	HWELCH

UST:

Name:	LAIDLAW TRANSIT
Address:	4300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451106
AI Number:	10025
Facility Type:	FLEET REFUELING
Facility Begin Date:	07/18/1986
Facility Status:	INACTIVE
Additional ID:	449270902002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	EUGENE CHIANG,CONTROLLER
Contact Organization Name:	LAIDLAW TRANSIT

LAIDLAW TRANSIT (Continued) **1000656202**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7135235694
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/20/1992
Signature Name/Title On Earliest Reg Form:	EUGENE CHIANG,CONTROLLER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601104433
Owner Last Name:	JUNG
Owner First Name:	ODAS
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	440270892002117
Additional ID:	449270902002117
AI Number:	10025
Owner Effective Begin Date:	07/18/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	26510
Facility ID:	67435
Ai Number:	10025
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/29/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

LAIDLAW TRANSIT (Continued) **1000656202**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	90716
UST ID:	26510
AI Number:	10025
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported

LAIDLAW TRANSIT (Continued) **1000656202**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	7500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	26509
Facility ID:	67435
Ai Number:	10025
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/29/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

LAIDLAW TRANSIT (Continued) **1000656202**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	7500
UST Comprt ID:	90715
UST ID:	26509
AI Number:	10025
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

LAIDLAW TRANSIT (Continued) **1000656202**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	7500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	26508
Facility ID:	67435
Ai Number:	10025
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/29/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

LAIDLAW TRANSIT (Continued) **1000656202**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	7500
UST Comprt ID:	90714
UST ID:	26508
AI Number:	10025
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

LAIDLAW TRANSIT (Continued) **1000656202**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	JUNG ODAS
Contact Mailing Address (Delivery):	PO BOX 41149
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 0020
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	67435
Additional ID:	449270902002117
Princ ID:	440270892002117
AI Number:	10025
Facility Name:	LAIDLAW TRANSIT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	LAIDLAW TRANSIT
Address:	4300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0587
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FINDS:

Registry ID: 110005146662

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

LAIDLAW TRANSIT (Continued) **1000656202**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000656202
Registry ID:	110005146662
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005146662
Name:	LAIDLAW TRANSIT
Address:	4300 S CONGRESS
City,State,Zip:	AUSTIN, TX 78745

1186 WNW < 1/8 0.015 mi. 77 ft. **SHEEHAN DENNIS W. TAILOR DYER SCOURER** **EDR Hist Cleaner** **1013778464**
5014 CONGRESS AVE **N/A**
AUSTIN, TX

Actual: 596 ft. EDR Hist Cleaner

Focus Map: 17

Year:	Name:	Type:
1901	SHEEHAN DENNIS W. TAILOR DYER	DYERS AND SCOURERS

IJ1187 WNW < 1/8 0.015 mi. 77 ft. **T & T CLEANERS LAUNDERERS** **EDR Hist Cleaner** **1018831316**
3206 GUADALUPE ST **N/A**
AUSTIN, TX 78705

Site 2 of 4 in cluster IJ

Actual: 595 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1998	T & T CLEANERS	Drycleaning Plants, Except Rugs
1999	T & T CLEANERS LAUNDERERS	Drycleaning Plants, Except Rugs
2000	T & T CLEANERS LAUNDERERS	Laundry And Drycleaner Agents

1188 ESE < 1/8 0.015 mi. 77 ft. **DRAKE CONDOMINIUMS** **TX VCP** **S123819853**
68 RAINEY ST **N/A**
AUSTIN, TX 78701

Actual: 460 ft. VCP TCEQ:

Focus Map: 14

Name:	DRAKE CONDOMINIUMS
Address:	68 RAINEY ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2036
VCP Record Date:	03/07/2007
Facility Type:	PROPERTY RESIDENTIAL
PCA Number:	34232

DRAKE CONDOMINIUMS (Continued) **S123819853**

Project Manager:	SDUNAHOO
Phase:	COMPLETED
Acres at Site:	0.78
REM Program:	VCP
RN Number:	RN105195408
Former Facility Type:	Not reported
Site Address Description:	68 - 76 (EVENS) RAINEY ST
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	03/07/2007
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	05/16/2008
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	03/07/2007
GW Target COC Class:	METALS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2007-04-13 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2036
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	342320
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	30.26
Longitude:	-97.74

Contact:

REM Program:	VCP
Program ID:	2036
RN Number:	RN105195408
CN Number:	CN603171737
CN Name:	DRAKE CONDOMINIUMS LLC
Role Code:	APPLCONT
Contact Name:	MAIDA, STEVE
Contact Title:	PRESIDENT
Organization Name:	DRAKE CONDOMINIUMS LLC
Mailing Address:	108 E 45TH ST
Mailing City:	AUSTIN

DRAKE CONDOMINIUMS (Continued) **S123819853**

Mailing State:	TX
Mailing Zip:	78751
Contact Telephone:	(512) 467-9852
Contact Telephone Ext:	0
REM Program:	VCP
Program ID:	2036
RN Number:	RN105195408
CN Number:	CN603171737
CN Name:	DRAKE CONDOMINIUMS LLC
Role Code:	BILLCONT
Contact Name:	MAIDA, STEVE
Contact Title:	Not reported
Organization Name:	DRAKE CONDOMINIUMS LLC
Mailing Address:	108 E 46TH ST
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78751
Contact Telephone:	(512) 467-9852
Contact Telephone Ext:	0

IL1189 **AVS FOOD SERVICE INC** **EDR Hist Auto** **1021892197**
NE **611 NECHES** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.015 mi.
77 ft. **Site 1 of 21 in cluster IL**

Actual:
489 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1982	AVS FOOD SERVICE INC	Merchandising Machine Operators
1983	AVS FOOD SERVICE INC	Merchandising Machine Operators
1985	AVS FOOD SERVICE INC	Merchandising Machine Operators
1986	AVS FOOD SERVICES INC	Merchandising Machine Operators
1987	AVS FOOD SERVICES INC	Merchandising Machine Operators
1988	AVS FOOD SERVICES INC	Merchandising Machine Operators

HZ1190 **B JATCO TRANSMISSIONS AUTO REPR** **EDR Hist Auto** **1013774458**
SE **8745 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78763**
0.015 mi.
78 ft. **Site 2 of 2 in cluster HZ**

Actual:
663 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1975	B T RS CHOP SHOP	MOTORCYCLE DEALERS AND REPAIRERS
1980	B AUTOMATIC TRANSMISSION REBUIL	AUTOMOBILE REPAIRING
1984	B JATCO TRANSMISSIONS AUTO REPR	AUTOMOBILE REPAIRING

AQ1191 **MC CULLOUGHS SERV** **EDR Hist Auto** **1013760855**
WNW **5000 LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 3 of 9 in cluster AQ**

Actual:
666 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	MC CULLOUGHS SERV	GASOLINE STATIONS
1958	MC CULLOUGHS SERV	GASOLINE STATIONS
1962	MC CULLOUGHS SERV	GASOLINE STATIONS
1965	MC CULLOUGHS SERVICE	GASOLINE STATIONS
1969	PAPPAS WILLIAM T	Gasoline Service Stations
1969	PAPPAS WILLIAM T	Gasoline Service Stations
1970	UNIVERSITY SINCLAIR SER V ST	GASOLINE STATIONS
1970	PAPPAS WILLIAM T	Gasoline Service Stations
1972	PAPPAS WILLIAM T	Gasoline Service Stations

DU1192 **JOHNSON J W SERVICE STATION** **EDR Hist Auto** **1020453027**
SW **510 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.015 mi.
79 ft. **Site 8 of 19 in cluster DU**

Actual:
476 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1969	JOHNSON J W SERVICE STATION	Gasoline Service Stations
1970	JOHNSON J W SERVICE STATION	Gasoline Service Stations
1971	JOHNSON J W SERVICE STATION	Gasoline Service Stations
1972	JOHNSON J W SERVICE STATION	Gasoline Service Stations
1973	JOHNSON J W SERVICE STATION	Gasoline Service Stations
1974	JOHNSON J W SERVICE STATION	Gasoline Service Stations

DU1193 **TEXAS CO.** **TX HIST UST** **S111678819**
SW **510 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 9 of 19 in cluster DU**

Actual:
476 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	TEXAS CO.
Address:	510 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0227
HID UST:	227
Inspection:	02/06/2009
Due:	02/06/2012

IL1194 **TIP TOP GARAGE AUTO** **EDR Hist Auto** **1013759748**
SSW **604 NECHES** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 2 of 21 in cluster IL**

Actual:
487 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	TIP TOP GARAGE AUTO	AUTOMOBILE REPAIRING
1947	BROWN & WILLIAMS GARAGE & PNT S	AUTOMOBILE REPAIRING

IM1195 **ABIA AUS431** **PFAS ECHO** **1027320848**
SSW **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 1 of 8 in cluster IM**

Actual:
499 ft.

Focus Map:
20

PFAS ECHO:

Name:	ABIA AUS431
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21781
Longitude:	-97.66907
Count:	1
County:	Not reported
Status:	Inactive
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070375682
Facility Percent Minority:	82.042
Facility Derived Tribes:	-
Facility Population:	918.83
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N

ABIA AUS431 (Continued) **1027320848**

AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05DA03
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66907,%22y%22:30.21781,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

IM1196 **GROUND SERVICES INTERNATIONAL** **PFAS ECHO** **1027365728**
SSW **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 2 of 8 in cluster IM**

Actual:
499 ft.

Focus Map:
20

PFAS ECHO:

Name:	GROUND SERVICES INTERNATIONAL
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21781
Longitude:	-97.66907
Count:	1
County:	Not reported
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070355489
Facility Percent Minority:	82.042
Facility Derived Tribes:	-
Facility Population:	918.83
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N

GROUND SERVICES INTERNATIONAL (Continued) **1027365728**

Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05CN30 TXR05FO30
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66907,%22y%22:30.21781,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

IM1197 **GLOBAL AVIATION SERVICE** **PFAS ECHO** **1027364067**
SSW **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
79 ft. **Site 3 of 8 in cluster IM**

Actual:
499 ft.

Focus Map:
20

PFAS ECHO:

Name:	GLOBAL AVIATION SERVICE
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21781
Longitude:	-97.66907
Count:	1
County:	Not reported
Status:	Inactive
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070687570
Facility Percent Minority:	82.042
Facility Derived Tribes:	-
Facility Population:	918.83
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05EN60

GLOBAL AVIATION SERVICE (Continued) **1027364067**

CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66907,%22y%22:30.21781,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

1198 ESE < 1/8 0.015 mi. 79 ft. **BOWLES GARAGE AUTO REPR** **EDR Hist Auto** **1013774674**
306 INTERREGIONAL HWY N **N/A**
TRAVIS (County), TX 78701

Actual: 468 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1970	BOWLES GARAGE AUTO REPR	AUTOMOBILE REPAIRING

GE1199 WNW < 1/8 0.015 mi. 79 ft. **WITTS SERV STA** **EDR Hist Auto** **1013755741**
2704 CONGRESS AVE **N/A**
SOUTH AUSTIN, TX

Site 3 of 3 in cluster GE

Actual: 620 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1962	WITTS SERV STA	GASOLINE STATIONS

1200 SSW < 1/8 0.015 mi. 80 ft. **AUS STSLM** **ECHO** **1026892218**
PFAS ECHO **N/A**
AUSTIN, TX

Actual: 505 ft. ECHO:

Focus Map: 20

Envid:	1026892218
Registry ID:	110071069629
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071069629
Name:	AUS STSLM
Address:	9501 CARGO AVE STE 400

AUS STSLM (Continued) **1026892218**

City,State,Zip: AUSTIN, TX 78719

PFAS ECHO:

Name:	AUS STSLM
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.215686
Longitude:	-97.664764
Count:	1
County:	TRAVIS COUNTY
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071069629
Facility Percent Minority:	83.169
Facility Derived Tribes:	-
Facility Population:	777.36
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	-
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05EW58 TXR05FH95
CWA Permit Types:	Minor
CWA NAICS:	-

AUS STSLM (Continued) **1026892218**

CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.664764,%22y%22:30.215686,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

BD1201 **HARTUNG PHILLIPS 66** **EDR Hist Auto** **1013762694**
WNW **3106 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
80 ft. **Site 5 of 5 in cluster BD**

Actual:
592 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	LEIGH SERVICE STA NO	GASOLINE AND OIL SERVICE STATIONS
1947	LEIGH SERVICE STATION NO 3 FILL	GASOLINE AND OIL SERVICE STATIONS
1953	CITY SERVICE STATION	GASOLINE STATIONS
1958	CITIES SERV STA BR	GASOLINE STATIONS
1962	HARTUNG PHILLIPS 66	GASOLINE STATIONS
1965	HARTUNG PHILLIPS SIXTY	GASOLINE STATIONS
1969	HARTUNG PHILLIPS 66 SVC STN	Gasoline Service Stations
1970	HARTUNG PHILLIPS 66 SVC STN	Gasoline Service Stations

BB1202 **SMITH ELMER L FILLING STA** **EDR Hist Auto** **1013776742**
ESE **3711 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 10 of 13 in cluster BB**

Actual:
600 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	SMITH ELMER L FILLING STA	GASOLINE AND OIL SERVICE STATIONS

HE1203 **ELECTRONINKS** **RCRA-LQG** **1027100659**
SSW **7901 E RIVERSIDE DR** **TXR000085707**
< 1/8 **AUSTIN, TX 78744**
0.015 mi.
81 ft. **Site 2 of 3 in cluster HE**

Actual:
527 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20230406
Handler Name:	Electroninks
Handler Address:	E RIVERSIDE DR
Handler City,State,Zip:	AUSTIN, TX 78744-1661
EPA ID:	TXR000085707
Contact Name:	JACOB MAHER
Contact Address:	E RIVERSIDE DR
Contact City,State,Zip:	AUSTIN, TX 78744-1661
Contact Telephone:	815-299-5558
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	E RIVERSIDE DR
Mailing City,State,Zip:	AUSTIN, TX 78744-1661
Owner Name:	Electroninks Incorporated
Owner Type:	Private
Operator Name:	Electroninks Incorporated
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ELECTRONINKS (Continued) **1027100659**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	F003

ELECTRONINKS (Continued) **1027100659**

Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ELECTRONINKS INCORPORATED
Legal Status:	Private
Date Became Current:	20210831
Date Ended Current:	Not reported
Owner/Operator Address:	7901 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1661
Owner/Operator Telephone:	737-300-1366
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	FACILITIES@ELECTRONINKS.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ELECTRONINKS INCORPORATED
Legal Status:	Private
Date Became Current:	20210831
Date Ended Current:	Not reported
Owner/Operator Address:	7901 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1661
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ELECTRONINKS INCORPORATED
Legal Status:	Private
Date Became Current:	20210831
Date Ended Current:	Not reported
Owner/Operator Address:	7901 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1661
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ELECTRONINKS INCORPORATED
Legal Status:	Private
Date Became Current:	20210831
Date Ended Current:	Not reported
Owner/Operator Address:	7901 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1661
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

ELECTRONINKS (Continued) **1027100659**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR

ELECTRONINKS (Continued) **1027100659**

Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: 737-300-1366
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: FACILITIES@ELECTRONINKS.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private
Date Became Current: 20210831
Date Ended Current: Not reported
Owner/Operator Address: 7901 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1661
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELECTRONINKS INCORPORATED
Legal Status: Private

ELECTRONINKS (Continued) **1027100659**

Date Became Current:	20210831
Date Ended Current:	Not reported
Owner/Operator Address:	7901 E RIVERSIDE DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1661
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20220301
Handler Name: ELECTRONINKS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20210916
Handler Name: ELECTRONINKS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220311
Handler Name: ELECTRONINKS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220823
Handler Name: ELECTRONINKS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

ELECTRONINKS (Continued) **1027100659**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220920
Handler Name: ELECTRONINKS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221028
Handler Name: ELECTRONINKS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20230406
Handler Name: ELECTRONINKS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 325910
NAICS Description: PRINTING INK MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

HE1204 **ELECTRONINKS** **TX Ind. Haz Waste** **S126921611**
SSW **7901 E RIVERSIDE DR** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78744**
0.015 mi.
81 ft. **Site 3 of 3 in cluster HE**

Actual:
527 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	ELECTRONINKS
Address:	7901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	98071
Registration Initial Notification Date:	08/31/2021
Registration Last Amendment Date:	10/28/2022
EPA Identification:	TXR000085707
Primary NAICS Code:	325910
Status Change Date:	20210831
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	ELECTRONINKS INCORPORATED
Contact Name:	JACOB MAHER
Contact Telephone Number:	815-2995558
Mailing Address:	7901 E RIVERSIDE DR
Mailing Address2:	BLDG 1 STE 150
Mailing City,State,Zip:	AUSTIN, TX 787441661
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	133408
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20221028
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

ELECTRONINKS (Continued) **S126921611**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	ELECTRONINKS INCORPORATED
Operator Address:	7901 E RIVERSIDE DR
Operator Address 2:	BLDG 1 STE 150
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78744
Operator Country:	UNITED STA
Operator Telephone:	1-737-3001366
Operator Fax Number:	Not reported
Operator Email:	FACILITIES@ELECTRONINKS.COM
Operator Business Type:	Corporation
Operator Tax ID:	32055992351
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ELECTRONINKS INCORPORATED
Owner Mailing Address:	7901 E RIVERSIDE DR
Owner Mailing Address 2:	BLDG 1 STE 150
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78744
Owner Country:	UNITED STA
Owner Telephone:	1-737-3001366
Owner Fax:	Not reported
Owner Email Address:	FACILITIES@ELECTRONINKS.COM
Owner Business Type:	Corporation
Owner Tax ID:	32055992351
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	HAZARDOUS WASTE ROOM NEAR CONSUMABLE HALLWAY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20210831
Deed Record Needed:	Not reported

ELECTRONINKS (Continued) **S126921611**

Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Fume hood accumulation waste area. Fume hood number 23.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20210916
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	7901 E RIVERSIDE DR
Contact Address 2:	BLDG 1 STE 150
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-737-3001366
Contact Fax:	Not reported
Contact Email:	FACILITIES@ELECTRONINKS.COM
Contact Name:	JACOB MAHER
Contact Title:	LAB MANAGER
Contact Role:	PRICONT
Contact Address:	7901 E RIVERSIDE DR
Contact Address 2:	BLDG 1 STE 150
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-815-2995558
Contact Fax:	Not reported
Contact Email:	JACOB@ELECTRONINKS.COM

Ind. Haz Waste:

Waste ID:	427493
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001319H
Waste Code Status:	ACTIVE
Waste Form:	319

ELECTRONINKS (Continued) **S126921611**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ENVIRONMENTALLY HAZARDOUS SUBSTANCES, SOLID, N.O.S. (SILVER, PPE). CONTAMINATED
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	325910
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427663
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	RINSING OF LAB GLASSWARE USED IN LAB PROCESS WHICH INVOLVES SILVER
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HYDROGEN PEROXIDE AG
Primary NAICS Code:	325910
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427664
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0

ELECTRONINKS (Continued) **S126921611**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Inorganic acid with metals. Discarding Acids used in various lab activities.; Du
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	INORGANIC ACID METAL
Primary NAICS Code:	325910
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427665
Texas Waste Code:	Not reported
Texas Waste Code 2:	00040011
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Discarding off-spec or outdated chemicals. Non-Reg Liquids Pack.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-REG LIQUIDS PACK
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	427667
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Silver Acetate Waste. DISCARDING OLD MATERIAL USED IN PRINTED CIRCUIT BOARDS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported

ELECTRONINKS (Continued) **S126921611**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SILVER ACETATE WASTE
Primary NAICS Code:	325910
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427668
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CLEANING OF ELECTRONICS PARTS CONTAMINATED WITH SILVER
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SILVER CONT SOLIDS
Primary NAICS Code:	325910
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427669
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Haz lab pack- 12L of: Aqua Regia. 15 gal of: methanol with traces of silver. 4L
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

ELECTRONINKS (Continued) **S126921611**

Company Waste ID:	HAZ LAB PACK
Primary NAICS Code:	325910
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	427670
Texas Waste Code:	Not reported
Texas Waste Code 2:	00080011
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-haz lab pack
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON HAZ LAB PACK
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	427671
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Methanol with traces of silver
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

ELECTRONINKS (Continued) **S126921611**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	METHANOL WITH SILVER
Primary NAICS Code:	325910
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	430862
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Neutralized inorganic acid with metals. Discarded acids used in various lab acti
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NEUTRALIZED ACID
Primary NAICS Code:	325910
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430867
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ENVIRONMENTALLY HAZARDOUS SUBSTANCES, SOLID, N.O.S. (NICKEL, PPE). CONTAMINATED
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SOLID NICKEL WASTE
Primary NAICS Code:	325910

ELECTRONINKS (Continued) **S126921611**

EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430868
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Discarded liquids during an ink making process
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	LIQUID NICKEL WASTE
Primary NAICS Code:	325910
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	431469
Texas Waste Code:	Not reported
Texas Waste Code 2:	00133191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nickel contaminated PPE and pipettes
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SOLID NICKEL WASTE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	433955
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0

ELECTRONINKS (Continued) **S126921611**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Production and R&D solvent waste with various metals
Standard Industrial Code:	Not reported
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PROD-RD SOLV W M
Primary NAICS Code:	325910
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	433956
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Unneutralized acid with metals. Discarding Acids used in various lab activities.
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	UNNEUTRALIZED ACID M
Primary NAICS Code:	325910
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	434336
Texas Waste Code:	Not reported
Texas Waste Code 2:	00163881
Waste Code Status:	ACTIVE
Waste Form:	388
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glassware that has been triple rinsed with water
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported

ELECTRONINKS (Continued) **S126921611**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	EMPTY GLASSWARE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	434968
Texas Waste Code:	Not reported
Texas Waste Code 2:	00173091
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Alkaline Batteries
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ALKALINE BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	434969
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Trimethylamine Cylinder
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CYLINDER
Primary NAICS Code:	325910
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

ELECTRONINKS (Continued) **S126921611**

Ind. Haz Waste:

Contact Name:	SPENCER VIOLETTE
Contact Title:	DIRECTOR OF FINANCE
Contact Telephone:	0-737-3001366 x0
Mailing Address:	7901 E RIVERSIDE DR STE 150
Mailing Address 2:	BLDG 1 STE 150
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000319478
Principal Name:	ELECTRONINKS INCORPORATED
Attention Name:	VIOLETTE ,SPENCER
Attention Suffix:	HWG

Contact Name:	SPENCER VIOLETTE
Contact Title:	DIRECTOR OF FINANCE
Contact Telephone:	0-737-3001366 x0
Mailing Address:	7901 E RIVERSIDE DR STE 150
Mailing Address 2:	BLDG 1 STE 150
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000319478
Principal Name:	ELECTRONINKS INCORPORATED
Attention Name:	VIOLETTE ,SPENCER
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN109862037
Name:	7901 E RIVERSIDE DR BLDG 2 STE 150
Address:	7901 E RIVERSIDE DR STE 150
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1661
Status:	ACTIVE
Status Date:	2017-07-20
Customer Number:	CN605098524
Customer Name:	TEKMOS INC
Customer Legal Name:	TEKMOS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2016-11-03
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

IN1205 **ATLAS CLEANERS NO** **EDR Hist Cleaner** **1013782566**
NNE **6110 RIVERSIDE DR E** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.015 mi.
81 ft. **Site 1 of 6 in cluster IN**

Actual:
510 ft.

Focus Map:
15

EDR Hist Cleaner

Year:	Name:	Type:
1980	ATLAS CLEANERS NO	CLEANERS
1980	ATLAS CLEANERS NO	CLEANERS AND DYERS
1984	ATLAS CLEANERS NO	CLEANERS AND DYERS
1986	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1987	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents

ATLAS CLEANERS NO (Continued) **1013782566**

1988	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1989	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1990	ATLAS CLEANERS NO	CLEANERS AND DYERS
1990	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1991	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1992	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1993	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1994	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1995	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1996	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1997	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1998	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
1999	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2000	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2001	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2002	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2003	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2004	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2005	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2006	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2007	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents
2008	ATLAS CLEANERS	Garment Pressing And Cleaners' Agents

IN1206 **ATLAS CLEANERS 2** **TX DRYCLEANERS** **S109360357**
NNE **6110 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.015 mi.
81 ft. **Site 2 of 6 in cluster IN**

Actual:
510 ft.

Focus Map:
15

DRYCLEANERS:

Name:	ATLAS CLEANERS 2
Address:	6110 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104059803
Region:	11
CN Number:	CN602463812
DCR Number:	Not reported
AR Number:	24000992
Principal Name:	CASTRO, JESSE
Bill Addr1:	6110 E RIVERSIDE DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78741 6514
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ATLAS CLEANERS 2
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	ATLAS CLEANERS 2
Address:	6110 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104059803
Region:	11

ATLAS CLEANERS 2 (Continued) **S109360357**

CN Number:	CN602463812
DCR Number:	Not reported
AR Number:	24000992
Principal Name:	CASTRO, JESSE
Bill Addr1:	6110 E RIVERSIDE DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78741 6514
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ATLAS CLEANERS 2
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	ATLAS CLEANERS 2
Address:	6110 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104059803
Region:	11
CN Number:	CN602463812
DCR Number:	Not reported
AR Number:	24000992
Principal Name:	CASTRO, JESSE
Bill Addr1:	6110 E RIVERSIDE DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78741 6514
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ATLAS CLEANERS 2
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	ATLAS CLEANERS 2
Address:	6110 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104059803
Region:	11
CN Number:	CN602463812
DCR Number:	Not reported
AR Number:	24000992
Principal Name:	CASTRO, JESSE
Bill Addr1:	6110 E RIVERSIDE DR
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78741 6514
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ATLAS CLEANERS 2
Site Type:	DROP STATION REGISTRATION

ATLAS CLEANERS 2 (Continued) **S109360357**

Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

IO1207 **CALL'S SALES & SERVICE** **TX HIST UST** **S111678592**
WNW **4900 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 1 of 4 in cluster IO**

Actual:
614 ft.

Focus Map:
17

HIST UST AUSTIN:

Name:	CALL'S SALES & SERVICE
Address:	4900 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0821
HID UST:	821
Inspection:	05/09/2012
Due:	05/09/2015

DQ1208 **SCHEUMACK & HART TAIL** **EDR Hist Cleaner** **1013787716**
NNE **314 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 3 of 11 in cluster DQ**

Actual:
489 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1911	SCHEUMACK & HART TAIL	CLOTHES PRESSERS AND CLEANERS

DQ1209 **SANCHEZ BROS CLO CLNRS** **EDR Hist Cleaner** **1013779623**
NNE **312 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 4 of 11 in cluster DQ**

Actual:
489 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1947	SANCHEZ BROS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS

HU1210 West < 1/8 0.015 mi. 81 ft. | **UNIVERSITY TOGGERY MENS**
2310 GUADALUPE ST
AUSTIN, TX
Site 4 of 4 in cluster HU | **EDR Hist Cleaner** | **1013779739**
N/A

Actual: 586 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	UNIVERSITY TOGGERY MENS	CLOTHES CLEANERS AND PRESSERS

1211 ESE < 1/8 0.015 mi. 81 ft. | **WHITES GARAGE FILLING STA**
304 JOHANNA W
SOUTH AUSTIN, TX | **EDR Hist Auto** | **1013770943**
N/A

Actual: 555 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1947	WHITES GARAGE FILLING STA	AUTOMOBILE REPAIRING

GW1212 WNW < 1/8 0.015 mi. 81 ft. | **ENTERPRISE RENT A CAR**
4210 S CONGRESS AVE
AUSTIN, TX 78745
Site 8 of 9 in cluster GW | **TX AST** | **A100298035**
N/A

Actual: 667 ft. AST:

Focus Map: 17

Name:	ENTERPRISE RENT A CAR
Address:	4210 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451104
Facility ID:	120195
Additional ID:	968569112006167
AI Number:	77996
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78745
Contact Name/Title:	PHILLIP RUSSELL/OPER MGR
Contact Organization Name:	ENTERPRISE RENT A CAR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5129215354
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	05/25/2006
Signature First Name on Earliest Reg Form:	DONALD

ENTERPRISE RENT A CAR (Continued) **A100298035**

Application Received Date on Earliest Reg Form:	05/30/2006
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	SCHWENT
Signature Title on Earliest Reg Form:	CONTROLLER
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	120195
Tank ID:	1
AST ID:	206746
AI Number:	77996
Install Date:	05/22/2006
Tank Registration Date:	05/30/2006
Mult Comp:	Y
Tank Status:	IN USE
Tank Status Date:	05/22/2006
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	GASOLINE
Other Substance B:	DIESEL
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

GW1213 **FURROW BUILDING MATERIALS** **RCRA-VSQG** **1004786571**
WNW **4210 S CONGRESS** **FINDS** **TXD988078598**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.015 mi.
81 ft. **Site 9 of 9 in cluster GW**

Actual:
667 ft.

Focus Map:
17

RCRA Listings:

Date Form Received by Agency:	19920921
Handler Name:	Furrow Building Materials
Handler Address:	S CONGRESS
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD988078598
Contact Name:	DAVE MCKEE
Contact Address:	PO BOX 419466
Contact City,State,Zip:	KANSAS CITY, MO 64141-0466
Contact Telephone:	816-234-6000
Contact Fax:	Not reported
Contact Email:	Not reported

FURROW BUILDING MATERIALS (Continued) **1004786571**

Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 419466
Mailing City,State,Zip:	KANSAS CITY, MO 64141-0466
Owner Name:	Payless Cashways Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

FURROW BUILDING MATERIALS (Continued) **1004786571**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: PAYLESS CASHWAYS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 419466
Owner/Operator City,State,Zip: KANSAS CITY, MO 64141-0466
Owner/Operator Telephone: 816-234-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19920921
Handler Name: FURROW BUILDING MATERIALS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005154073

FURROW BUILDING MATERIALS (Continued) **1004786571**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004786571
Registry ID:	110005154073
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005154073
Name:	FURROW BUILDING MATERIALS
Address:	4210 S CONGRESS
City,State,Zip:	AUSTIN, TX 78745

DR1214 **VACANT BUILDING** **TX HIST UST** **S128728769**
SW **508 E. 6TH ST.** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 15 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	VACANT BUILDING
Address:	508 E. 6TH ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3413
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DR1215 **BOOTHE PROPERTY VACANT** **TX LPST** **S116697608**
SW **508 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.015 mi.
81 ft. **Site 16 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

LPST:

Name:	BOOTHE PROPERTY VACANT
Address:	508 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0064808
LPST Id:	107192
Facility Location:	508-510 E 6TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/12/1993
Entered Date:	10/22/1993
Reported Date:	08/12/1993
Closure Date:	09/03/1993

BOOTHE PROPERTY VACANT (Continued) **S116697608**

Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	TERRY BOOTH
Responsible Party Address:	503B E 6TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/478-7110
Reported Date:	08/12/1993
Case Start Date:	09/03/1993
Reference Number:	RN101490456
Project Manager:	HWELCH

DR1216 **TERRY E BOOTH** **TX UST** **U001542622**
SW **508 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.015 mi.
81 ft. **Site 17 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

UST:

Name:	TERRY E BOOTH
Address:	508 E 6TH ST
City,State,Zip:	AUSTIN, TX 787013742
AI Number:	64808
Facility Type:	RETAIL
Facility Begin Date:	07/22/1993
Facility Status:	INACTIVE
Additional ID:	998564422002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	TERRY BOOTH,OWNER
Contact Organization Name:	TERRY E BOOTH
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124787110
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/01/1993
Signature Name/Title On Earliest Reg Form:	TERRY BOOTH,OWNER
Application Received Date On Earliest Reg Form:	07/16/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

TERRY E BOOTH (Continued) **U001542622**

Owner:

Owner CN:	CN600779276
Owner Last Name:	BOOTH TERRY E
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	988564422002053
Additional ID:	998564422002053
AI Number:	64808
Owner Effective Begin Date:	07/22/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/16/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148664
Facility ID:	96369
Ai Number:	64808
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/23/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

TERRY E BOOTH (Continued) **U001542622**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/30/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	158074
UST ID:	148664
AI Number:	64808
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

TERRY E BOOTH (Continued) **U001542622**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25197
Cert ID:	100066
UST Comprt ID:	297717
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100061
UST Comprt ID:	297722
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100060
UST Comprt ID:	297723
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	259394
UST Comprt ID:	746657
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100059
UST Comprt ID:	297724
UST ID:	107616
AI Number:	64808

TERRY E BOOTH (Continued) **U001542622**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100058
UST Comprt ID:	297727
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100067
UST Comprt ID:	297716
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100057
UST Comprt ID:	297726
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	241405
UST Comprt ID:	693539
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100056
UST Comprt ID:	297725
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100062
UST Comprt ID:	297721
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	276979
UST Comprt ID:	798499
UST ID:	107616
AI Number:	64808
Tank ID:	1

TERRY E BOOTH (Continued) **U001542622**

Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100063
UST Comprt ID:	297720
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100064
UST Comprt ID:	297719
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100065
UST Comprt ID:	297718
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	226435
UST Comprt ID:	649851
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	07/16/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148665
Facility ID:	96369
Ai Number:	64808
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/23/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

TERRY E BOOTH (Continued) **U001542622**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/30/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	500
UST Comprt ID:	158075
UST ID:	148665
AI Number:	64808
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

TERRY E BOOTH (Continued) **U001542622**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25197
Cert ID:	100066
UST Comprt ID:	297717
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100061
UST Comprt ID:	297722
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100060
UST Comprt ID:	297723
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	259394
UST Comprt ID:	746657
UST ID:	107616
AI Number:	64808
Tank ID:	1

TERRY E BOOTH (Continued) **U001542622**

Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100059
UST Comprt ID:	297724
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100058
UST Comprt ID:	297727
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100067
UST Comprt ID:	297716
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100057
UST Comprt ID:	297726
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	241405
UST Comprt ID:	693539
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100056
UST Comprt ID:	297725
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100062
UST Comprt ID:	297721
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

TERRY E BOOTH (Continued) **U001542622**

Self Cert ID:	25197
Cert ID:	276979
UST Comprt ID:	798499
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100063
UST Comprt ID:	297720
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100064
UST Comprt ID:	297719
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100065
UST Comprt ID:	297718
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	226435
UST Comprt ID:	649851
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	07/16/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148666
Facility ID:	96369
Ai Number:	64808
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/23/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

TERRY E BOOTH (Continued) **U001542622**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/30/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	158076
UST ID:	148666
AI Number:	64808
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

TERRY E BOOTH (Continued) **U001542622**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25197
Cert ID:	100066
UST Comprt ID:	297717
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100061
UST Comprt ID:	297722
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25197
Cert ID:	100060
UST Comprt ID:	297723
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

TERRY E BOOTH (Continued) **U001542622**

Self Cert ID:	25197
Cert ID:	259394
UST Comprt ID:	746657
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100059
UST Comprt ID:	297724
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100058
UST Comprt ID:	297727
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100067
UST Comprt ID:	297716
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100057
UST Comprt ID:	297726
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	241405
UST Comprt ID:	693539
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197
Cert ID:	100056
UST Comprt ID:	297725
UST ID:	107616
AI Number:	64808
Tank ID:	1
Compartment ID:	A

Self Cert ID:	25197

TERRY E BOOTH (Continued) **U001542622**

Cert ID: 100062
UST Comprt ID: 297721
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Self Cert ID: 25197
Cert ID: 276979
UST Comprt ID: 798499
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Self Cert ID: 25197
Cert ID: 100063
UST Comprt ID: 297720
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Self Cert ID: 25197
Cert ID: 100064
UST Comprt ID: 297719
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Self Cert ID: 25197
Cert ID: 100065
UST Comprt ID: 297718
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Self Cert ID: 25197
Cert ID: 226435
UST Comprt ID: 649851
UST ID: 107616
AI Number: 64808
Tank ID: 1
Compartment ID: A

Facility Billing Contacts:
Contact Organization Name: BOOTH TERRY E
Contact Mailing Address (Delivery): 503 E 6TH ST STE B
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: AUSTIN, TX 78701 3733
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y

TERRY E BOOTH (Continued) **U001542622**

Facility ID:	96369
Additional ID:	998564422002053
Princ ID:	988564422002053
AI Number:	64808
Facility Name:	TERRY E BOOTH
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	TERRY BOOTH/

DR1217 **FORMER UST FACILITY** **TX HIST UST** **S128729131**
SW **508 E. 6TH** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 18 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	FORMER UST FACILITY
Address:	508 E. 6TH
City,State,Zip:	AUSTIN, TX
Id UST:	C0711
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DR1218 **A. W. HARRIS** **TX HIST UST** **S128729459**
SW **508 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 19 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	A. W. HARRIS
Address:	508 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0884
HID UST:	884
Inspection:	Not reported
Due:	06/01/2012

DR1219 **S. FERRIS** **TX HIST UST** **S128729460**
SW **508 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 20 of 38 in cluster DR**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	S. FERRIS
Address:	508 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0886
HID UST:	886

S. FERRIS (Continued) **S128729460**

Inspection: Not reported
Due: 06/01/2012

IN1220 **J&S BROTHERS TIRE SHOP** **TX HIST UST** **S118855039**
NNE **6108 E RIVERSIDE DR** **TX ENF** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX COMP HIST**
0.015 mi.
81 ft. **Site 3 of 6 in cluster IN**

Actual:
508 ft.

Focus Map:
15

HIST UST AUSTIN:

Name:	JAIMES AUTO REPAIR
Address:	6108 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	N0153
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ENFORCEMENT:

Name:	J&S BROTHERS TIRE SHOP
Address:	6108 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-6514
Unique TCEQ Ref Number Of Customer:	CN605139088
Unique TCEQ Ref Number Of Reg. Entity:	RN109194795
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	CAMACHO ROJAS, AURORA V
Regulated Entity Associated With An NOV:	USED TIRE SALES AND REPAIR
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001329903
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	416,537,802,016,154.00
Role Code:	Not reported
Date Notice Of Violation Issued:	06/06/2016
Description 1:	Failure to document the removal and management of all scrap tires generated on-site.
Description 2:	Based on the information gathered, the violations have been administratively resolved. No further action is required at this time. A Final Letter will be sent to Mr. Camacho.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.56(c)
Status Of The NOV:	DAPPROVED
Investigation:	1329903
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported

J&S BROTHERS TIRE SHOP (Continued) **S118855039**

Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	J&S BROTHERS TIRE SHOP
Address:	6108 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-6514
Unique TCEQ Ref Number Of Customer:	CN605139088
Unique TCEQ Ref Number Of Reg. Entity:	RN109194795
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	CAMACHO ROJAS, AURORA V
Regulated Entity Associated With An NOV:	USED TIRE SALES AND REPAIR
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001329903
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	416,537,802,016,154.00
Role Code:	Not reported
Date Notice Of Violation Issued:	06/06/2016
Description 1:	Failure to register as a scrap tire facility prior to processing (cutting) scrap tires.
Description 2:	Based on the information gathered, the violations have been administratively resolved. No further action is required at this time. A Final Letter will be sent to Mr. Camacho.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	328.63(c)
Status Of The NOV:	DAPPROVED
Investigation:	1329903
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

COMP HIST:

RN Number:	RN109194795
Name:	J&S BROTHERS TIRE SHOP
Address:	6108 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741-6514
Region:	REGION 11 - AUSTIN
CN Number:	CN605139088

J&S BROTHERS TIRE SHOP (Continued) **S118855039**

CN Name:	CAMACHO ROJAS, AURORA V
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811198
SIC Code:	7521
Related Number:	R11109194795,R11109194795

IN1221 **ACE AUTO REPAIR** **EDR Hist Auto** **1013765119**
NNE **6108 RIVERSIDE DR** **N/A**
< 1/8 **TRAVIS (County), TX 78741**
0.015 mi.
81 ft. **Site 4 of 6 in cluster IN**

Actual:
508 ft.

Focus Map:
15

EDR Hist Auto

Year:	Name:	Type:
1990	ACE AUTO REPAIR	AUTOMOBILE REPAIRING
1992	JAIMES REPAIR	General Automotive Repair Shops
1993	JAIMES REPAIR	General Automotive Repair Shops
1994	JAIMES REPAIR	General Automotive Repair Shops
1995	JAIMES REPAIR INC	General Automotive Repair Shops
1996	JAIMES REPAIR INC	General Automotive Repair Shops
1997	JAIMES REPAIR INC	General Automotive Repair Shops
1998	JAIMES REPAIR INC	General Automotive Repair Shops
1999	JAIMES REPAIR INC	General Automotive Repair Shops
2000	JAIMES REPAIR INC	General Automotive Repair Shops
2001	JAIMES REPAIR INC	General Automotive Repair Shops
2002	JAIMES REPAIR INC	General Automotive Repair Shops
2003	JAIMES REPAIR INC	General Automotive Repair Shops
2004	JAIMES REPAIR INC	General Automotive Repair Shops
2005	JAIMES REPAIR INC	General Automotive Repair Shops
2006	JAIMES REPAIR INC	General Automotive Repair Shops
2007	JAIMES REPAIR INC	General Automotive Repair Shops
2008	JAIMES REPAIR INC	General Automotive Repair Shops

IN1222 **AUTO SALVAGE YARD** **TX RDR** **S127541787**
NNE **6108 E. RIVERSIDE DR.** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 5 of 6 in cluster IN**

Actual:
508 ft.

Focus Map:
15

RDR:

RDR ID:	11794
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	AUTO SALVAGE YARD
Address:	6108 E. RIVERSIDE DR.
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/29/1999

AUTO SALVAGE YARD (Continued) **S127541787**

Due Date:	2/27/2000
Tank Owner:	W. E. KASPAREK
Contact Person:	W.E. KASPAREK
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Michelle Sefcik
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NO LEAKER
Review Coordinator:	MDS
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

IN1223 **AUTO SALVAGE YARD** **TX RDR** **S127541788**
NNE **6108 E. RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 6 of 6 in cluster IN**

Actual:
508 ft.

Focus Map:
15

RDR:

RDR ID:	11793
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	AUTO SALVAGE YARD
Address:	6108 E. RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/29/1999
Due Date:	2/27/2000
Tank Owner:	Not reported
Contact Person:	W.E. KASPAREK
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Michelle Sefcik
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NO LEAKER -PENDING
Review Coordinator:	MDS
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DQ1224 **PASSON FRED W C TAILOR** **EDR Hist Cleaner** **1013787196**
NNE **407 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 5 of 11 in cluster DQ**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	PASSON FRED W C TAILOR	CLOTHES PRESSERS AND CLEANERS

DQ1225 **LUDWIG ROBERT TAILOR** **EDR Hist Cleaner** **1013780859**
NNE **406 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 6 of 11 in cluster DQ**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	LUDWIG ROBERT TAILOR	DYERS AND SCOURERS
1911	LUDWIG ROBERT TAILOR	CLOTHES PRESSERS AND CLEANERS

IP1226 **SMITH DEE 0 TAILOR** **EDR Hist Cleaner** **1013779644**
NNE **410 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.015 mi.
81 ft. **Site 1 of 5 in cluster IP**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	SMITH DEE 0 TAILOR	CLOTHES PRESSERS AND CLEANERS

E1227 **MOBILE HOME HAVEN** **TX Ind. Haz Waste** **S102751339**
WNW **11606 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.015 mi.
81 ft. **Site 6 of 6 in cluster E**

Actual:
744 ft.
Ind. Haz Waste:

Focus Map:
3

Name:	MOBILE HOME HAVEN
Address:	11606 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	68435
Registration Initial Notification Date:	03/31/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19860331
Land Type:	Not reported
Description of Facility Site Location:	11606 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1

MOBILE HOME HAVEN (Continued) **S102751339**

Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MOBILE HOME HAVEN
Contact Name:	GENE A GUALT
Contact Telephone Number:	Not reported
Mailing Address:	11606 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787532624
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	23383
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MOBILE HOME HAVEN
Operator Address:	11606 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MOBILE HOME HAVEN
Owner Mailing Address:	11606 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA

MOBILE HOME HAVEN (Continued) **S102751339**

Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	11606 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	11606 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	GENE GUALT
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	11606 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100617653
Name:	MOBILE HOME HAVEN
Address:	11606 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-2624
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600326722
Customer Name:	MOBILE HOME HAVEN
Customer Legal Name:	Mobile Home Haven
Customer Ownership Type:	OTHER
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000

MOBILE HOME HAVEN (Continued) **S102751339**

Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 11606 N Lamar, Austin, TX

DQ1228 **SMITH A T DCLO PRESSER** **EDR Hist Cleaner** **1013780945**
NNE **318 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
82 ft. **Site 7 of 11 in cluster DQ**

Actual:
489 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	SMITH A T DCLO PRESSER	CLOTHES CLEANERS AND PRESSERS

IP1229 **DATSON ISHMAEL C DCLO CLNR** **EDR Hist Cleaner** **1013785508**
NNE **412 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
82 ft. **Site 2 of 5 in cluster IP**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	DATSON ISHMAEL C DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

AF1230 **AUS TEX BODY SHOP** **EDR Hist Auto** **1013774382**
WNW **6706 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.016 mi.
82 ft. **Site 13 of 13 in cluster AF**

Actual:
715 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1970	AUS TEX BODY SHOP	AUTOMOBILE REPAIRING
1990	CHUCKS TRANSMISSION & AUTO REPA	AUTOMOBILE REPAIRING
1991	CHUCKS TRANSMISSION WAREHOUSE	General Automotive Repair Shops
1992	CHUCKS TRANSMISSION WAREHOUSE	General Automotive Repair Shops
1993	CHUCKS TRANSMISSION WAREHOUSE	General Automotive Repair Shops
1994	CHUCKS TRANSMISSION WAREHOUSE	General Automotive Repair Shops
1995	CHUCKS TRANSMISSION WAREHOUSE	General Automotive Repair Shops
1996	CHUCKS AUTOMOTIVE REPAIR INC	General Automotive Repair Shops
1997	CHUCKS AUTOMOTIVE REPAIR INC	General Automotive Repair Shops
1998	UNDERGROUND VW	General Automotive Repair Shops
1999	UNDERGROUND VW	General Automotive Repair Shops
2000	UNDERGROUND VW	General Automotive Repair Shops
2001	UNDERGROUND VW	General Automotive Repair Shops
2002	UNDERGROUND VW	General Automotive Repair Shops
2003	VOLKES WAGON	General Automotive Repair Shops
2004	VOLKES WAGON	General Automotive Repair Shops
2005	VOLKES WAGON	General Automotive Repair Shops
2006	VOLKES WAGON	General Automotive Repair Shops
2007	VOLKES WAGON	General Automotive Repair Shops

AUS TEX BODY SHOP (Continued) **1013774382**

2008	VOLKES WAGON	General Automotive Repair Shops
2009	VOLKES WAGON	General Automotive Repair Shops
2010	VOLKES WAGON	General Automotive Repair Shops
2011	VOLKES WAGON	General Automotive Repair Shops
2012	VOLKES WAGON	General Automotive Repair Shops
2013	VOLKES WAGON	General Automotive Repair Shops
2014	VOLKES WAGON	General Automotive Repair Shops

IQ1231 **TUNEUP MASTERS STORE 1004** **TX UST** **U001258335**
WNW **5624 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.016 mi.
83 ft. **Site 1 of 4 in cluster IQ**

Actual:
695 ft.

Focus Map:
8

UST:

Name:	TUNEUP MASTERS STORE 1004
Address:	5624 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511058
AI Number:	24078
Facility Type:	UNKNOWN
Facility Begin Date:	09/30/1986
Facility Status:	INACTIVE
Additional ID:	138669272002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	GEORGE MAYER,OPER MGR
Contact Organization Name:	TUNEUP MASTERS STORE 1004
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8053751100
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/02/1986
Signature Name/Title On Earliest Reg Form:	GEORGE MAYER,OPER MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600317598
Owner Last Name:	TUNEUP MASTERS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	349471302001297
Additional ID:	138669272002138
AI Number:	24078
Owner Effective Begin Date:	09/30/1986
State Tax ID:	19527450100
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	61914
Facility ID:	39536
Ai Number:	24078
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/25/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	5338
UST ID:	61914
AI Number:	24078
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9123
Cert ID:	28999
UST Comprt ID:	82568
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28998
UST Comprt ID:	82569
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29001
UST Comprt ID:	82566
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29002
UST Comprt ID:	82565
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29003
UST Comprt ID:	82564
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29004
UST Comprt ID:	82563
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Self Cert ID:	9123
Cert ID:	28775
UST Comprt ID:	82573
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28776
UST Comprt ID:	82574
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28777
UST Comprt ID:	82575
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28778
UST Comprt ID:	82572
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28779
UST Comprt ID:	82571
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	230077
UST Comprt ID:	660454
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	247009
UST Comprt ID:	710178
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Cert ID:	263284
UST Comprt ID:	758240
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	280698
UST Comprt ID:	809635
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	295938
UST Comprt ID:	854681
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	314460
UST Comprt ID:	910167
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	330710
UST Comprt ID:	958691
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29000
UST Comprt ID:	82567
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28997
UST Comprt ID:	82570
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	61917
Facility ID:	39536
Ai Number:	24078
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	9999
UST Comprt ID:	5341
UST ID:	61917
AI Number:	24078
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9123
Cert ID:	28999
UST Comprt ID:	82568
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Self Cert ID:	9123
Cert ID:	28998
UST Comprt ID:	82569
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29001
UST Comprt ID:	82566
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29002
UST Comprt ID:	82565
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29003
UST Comprt ID:	82564
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29004
UST Comprt ID:	82563
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28775
UST Comprt ID:	82573
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28776
UST Comprt ID:	82574
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Cert ID:	28777
UST Comprt ID:	82575
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28778
UST Comprt ID:	82572
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28779
UST Comprt ID:	82571
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	230077
UST Comprt ID:	660454
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	247009
UST Comprt ID:	710178
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	263284
UST Comprt ID:	758240
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	280698
UST Comprt ID:	809635
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	295938

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

UST Comprt ID:	854681
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	314460
UST Comprt ID:	910167
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	330710
UST Comprt ID:	958691
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29000
UST Comprt ID:	82567
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28997
UST Comprt ID:	82570
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	61916
Facility ID:	39536
Ai Number:	24078
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	9999
UST Comprt ID:	5340
UST ID:	61916
AI Number:	24078
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9123
Cert ID:	28999
UST Comprt ID:	82568
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28998
UST Comprt ID:	82569
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29001
UST Comprt ID:	82566
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29002

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

UST Comprt ID:	82565
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29003
UST Comprt ID:	82564
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29004
UST Comprt ID:	82563
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28775
UST Comprt ID:	82573
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28776
UST Comprt ID:	82574
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28777
UST Comprt ID:	82575
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28778
UST Comprt ID:	82572
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28779
UST Comprt ID:	82571

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	230077
UST Comprt ID:	660454
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	247009
UST Comprt ID:	710178
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	263284
UST Comprt ID:	758240
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	280698
UST Comprt ID:	809635
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	295938
UST Comprt ID:	854681
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	314460
UST Comprt ID:	910167
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	330710
UST Comprt ID:	958691
UST ID:	25482

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29000
UST Comprt ID:	82567
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28997
UST Comprt ID:	82570
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	61915
Facility ID:	39536
Ai Number:	24078
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	9999
UST Comprt ID:	5339
UST ID:	61915
AI Number:	24078
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9123
Cert ID:	28999
UST Comprt ID:	82568
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28998
UST Comprt ID:	82569
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29001
UST Comprt ID:	82566
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29002
UST Comprt ID:	82565
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29003
UST Comprt ID:	82564
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29004
UST Comprt ID:	82563
UST ID:	25482

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28775
UST Comprt ID:	82573
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28776
UST Comprt ID:	82574
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28777
UST Comprt ID:	82575
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28778
UST Comprt ID:	82572
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28779
UST Comprt ID:	82571
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	230077
UST Comprt ID:	660454
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	247009
UST Comprt ID:	710178
UST ID:	25482
AI Number:	24078

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	263284
UST Comprt ID:	758240
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	280698
UST Comprt ID:	809635
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	295938
UST Comprt ID:	854681
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	314460
UST Comprt ID:	910167
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	330710
UST Comprt ID:	958691
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	29000
UST Comprt ID:	82567
UST ID:	25482
AI Number:	24078
Tank ID:	3
Compartment ID:	A
Self Cert ID:	9123
Cert ID:	28997
UST Comprt ID:	82570
UST ID:	25482
AI Number:	24078
Tank ID:	3

TUNEUP MASTERS STORE 1004 (Continued) **U001258335**

Compartment ID: A

Facility Billing Contacts:

Contact Organization Name:	TUNEUP MASTERS INC
Contact Mailing Address (Delivery):	750 W 5TH ST STE 300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	FORT WORTH, TX 76102 3621
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	39536
Additional ID:	138669272002138
Princ ID:	349471302001297
AI Number:	24078
Facility Name:	TUNEUP MASTERS STORE 1004
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GEORGE MAYER/

HIST UST AUSTIN:

Name:	TUNE UP MASTERS #1004
Address:	5624 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0335
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IQ1232 **TUNEUP MASTERS INC** **RCRA NonGen / NLR** **1000224560**
WNW **5624 N LAMAR BLVD** **FINDS** **TXD982286288**
< 1/8 **AUSTIN, TX 78751** **ECHO**
0.016 mi.
83 ft. **Site 2 of 4 in cluster IQ**

Actual:
695 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Tuneup Masters Inc
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78751
EPA ID:	TXD982286288
Contact Name:	GEORGE MAYER
Contact Address:	CORPORATE CENTER DR
Contact City,State,Zip:	NEWBURY PARK, CA 91320
Contact Telephone:	805-375-1100
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

TUNEUP MASTERS INC (Continued) **1000224560**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	CORPORATE CENTER DR
Mailing City,State,Zip:	NEWBURY PARK, CA 91320
Owner Name:	Tuneup Masters Inc
Owner Type:	Private
Operator Name:	Tuneup Masters Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002

TUNEUP MASTERS INC (Continued) **1000224560**

Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: TUNEUP MASTERS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TUNEUP MASTERS INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	2001 CORPORATE CENTER DR
Owner/Operator City,State,Zip:	NEWBURY PARK, CA 91320
Owner/Operator Telephone:	805-375-1100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TUNEUP MASTERS INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	2001 CORPORATE CENTER DR
Owner/Operator City,State,Zip:	NEWBURY PARK, CA 91320
Owner/Operator Telephone:	805-375-1100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19871127
Handler Name: TUNEUP MASTERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

TUNEUP MASTERS INC (Continued) **1000224560**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name: TUNEUP MASTERS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005102334

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000224560
Registry ID:	110005102334
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005102334
Name:	TUNEUP MASTERS INC
Address:	5624 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751

IQ1233 **TUNEUP MASTERS 1004** **TX HIST UST** **S102755725**
WNW **5624 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.016 mi.
83 ft. **Site 3 of 4 in cluster IQ**

Actual:
695 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	JACK GRIFFIN
Address:	5624 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0422
HID UST:	422
Inspection:	05/25/2011
Due:	05/25/2014

Ind. Haz Waste:

Name:	TUNEUP MASTERS 1004
Address:	5624 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	74404
Registration Initial Notification Date:	11/13/1987
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD982286288
Primary NAICS Code:	Not reported
Status Change Date:	19871113
Land Type:	PRIVATE
Description of Facility Site Location:	5624 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TUNEUP MASTERS INC
Contact Name:	GEORGE MAYER
Contact Telephone Number:	805-3751100
Mailing Address:	2001 CORPORATE CENTER DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	NEWBURY PARK, CA 913201428
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28783
Site Owner Tax ID:	952745010
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030903
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

TUNEUP MASTERS 1004 (Continued) **S102755725**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TUNEUP MASTERS INC
Operator Address:	2001 CORPORATE CENTER DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	NEWBURY PARK, CA 91320
Operator Country:	UNITED STA
Operator Telephone:	1-805-3751100
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	19527450100
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TUNEUP MASTERS INC
Owner Mailing Address:	2001 CORPORATE CENTER DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	NEWBURY PARK, CA 91320
Owner Country:	UNITED STA
Owner Telephone:	1-805-3751100
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	19527450100
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2001 CORPORATE CENTER DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	NEWBURY PARK, CA 91320
Contact Phone:	1-805-3751100
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2001 CORPORATE CENTER DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	NEWBURY PARK, CA 91320

TUNEUP MASTERS 1004 (Continued) **S102755725**

Contact Phone:	1-805-3751100
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	GEORGE MAYER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	2001 CORPORATE CENTER DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	NEWBURY PARK, CA 91320
Contact Phone:	1-805-3751100
Contact Fax:	Not reported
Contact Email:	Not reported

IQ1234 **GRIFFIN JACK SERV** **EDR Hist Auto** **1013757093**
WNW **5624 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 4 of 4 in cluster IQ**

Actual:
695 ft. EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	GRIFFIN JACK SERV	GASOLINE STATIONS
1958	GRIFFIN JACK SERV	GASOLINE STATIONS
1962	GRIFFIN JACK SERV	GASOLINE STATIONS
1965	GRIFFIN JACK SERVICE	GASOLINE STATIONS
1969	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1970	GRIFFIN JACK SERVICE STATION	GASOLINE STATIONS
1970	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1971	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1972	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1973	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1974	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1975	GRIFFIN JACK SERVICE STATION	GASOLINE STATIONS
1975	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1976	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1977	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1978	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1978	TUNE-UP INC	General Automotive Repair Shops
1979	TUNE-UP INC	General Automotive Repair Shops
1979	GRIFFIN SUPER SERVICE STATION	Gasoline Service Stations
1980	TUNER UP INC	AUTOMOBILE REPAIRING
1984	TUNE UP MASTERS	AUTOMOBILE REPAIRING
1990	TUNE UP MASTERS	AUTOMOBILE REPAIRING
2000	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2001	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2002	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2003	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2004	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2005	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2006	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2007	TUNEUP MASTERS INC	Automotive Repair Shops, NEC
2013	SALEMS AUTO CENTER	General Automotive Repair Shops
2014	SALEMS AUTO CENTER	General Automotive Repair Shops

DU1235 **AUSTIN CAT & DOG HOSPITAL** **TX LPST** **U001291289**
SW **506 E 5TH ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX HIST UST**
0.016 mi. **TX GCC**
83 ft. **Site 10 of 19 in cluster DU**

Actual:
476 ft.

Focus Map:
11

LPST:

Name:	AUSTIN DOG CAT HOSPITAL
Address:	506 E 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0062072
LPST Id:	102270
Facility Location:	506 E 5TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	03/23/1992
Reported Date:	03/23/1992
Closure Date:	01/31/2017
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	CARMELO MAURO
Responsible Party Address:	504 E 5TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 77079
Responsible Party Telephone:	512/477-7497
Reported Date:	03/23/1992
Case Start Date:	01/31/2017
Reference Number:	RN101489912
Project Manager:	HWELCH

UST:

Name:	AUSTIN CAT & DOG HOSPITAL
Address:	506 E 5TH ST
City,State,Zip:	AUSTIN, TX 787013726
AI Number:	62072
Facility Type:	RETAIL
Facility Begin Date:	01/02/1992
Facility Status:	INACTIVE
Additional ID:	129549932002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	AUSTIN CAT & DOG HOSPITAL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Contact Telephone:	5124763535
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/12/1991
Signature Name/Title On Earliest Reg Form:	RON STRIED,OWNER
Application Received Date On Earliest Reg Form:	12/19/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778807
Owner Last Name:	STRIED RON
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	119549932002053
Additional ID:	129549932002053
AI Number:	62072
Owner Effective Begin Date:	01/02/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144287
Facility ID:	92277
Ai Number:	62072
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/07/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	143189
UST ID:	144287
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144286
Facility ID:	92277
Ai Number:	62072
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	143188
UST ID:	144286
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	250
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144285
Facility ID:	92277
Ai Number:	62072
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/07/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	6
Tank Capacity:	250
UST Comprt ID:	143187
UST ID:	144285
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144283
Facility ID:	92277
Ai Number:	62072
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	143185
UST ID:	144283
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144284
Facility ID:	92277
Ai Number:	62072
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	143186
UST ID:	144284
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Tank Registration Date:	12/19/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	144282
Facility ID:	92277
Ai Number:	62072
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/07/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	143184
UST ID:	144282
AI Number:	62072
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	STRIED RON
Contact Mailing Address (Delivery):	11400 SILMARILLION TRL
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78739 5624
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

AUSTIN CAT & DOG HOSPITAL (Continued) **U001291289**

Contact Address Deliverable:	Y
Facility ID:	92277
Additional ID:	129549932002053
Princ ID:	119549932002053
AI Number:	62072
Facility Name:	AUSTIN CAT & DOG HOSPITAL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RON STRIED/

HIST UST AUSTIN:

Name:	AUSTIN CAT AND DOG HOSPITAL
Address:	506 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0196
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GCC:

Name:	AUSTIN DOG CAT HOSPITAL
Address:	506 E 5TH ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	102270
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	3/23/1992
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

IR1236 **ROBBINS RUSSELL H AUTO REPR** **EDR Hist Auto** **1013770486**
SW **4311 AVENUE A** **N/A**
< 1/8 **HYDE PARK, TX**
0.016 mi.
83 ft. **Site 1 of 7 in cluster IR**

Actual:
623 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1947	ROBBINS RUSSELL H AUTO REPR	AUTOMOBILE REPAIRING

IP1237 **WING KEE** **EDR Hist Cleaner** **1013783548**
NNE **418 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 3 of 5 in cluster IP**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1906	WING KEE	LAUNDRIES

DU1238 **CHAS WOLF & O.G. WOLF** **TX HIST UST** **S111678603**
WSW **535 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 11 of 19 in cluster DU**

Actual:
474 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	CHAS WOLF & O.G. WOLF
Address:	535 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0239
HID UST:	239
Inspection:	02/06/2009
Due:	02/06/2012

IB1239 **DALES UNIVERSITY AUTO REPAIR CENTER** **EDR Hist Auto** **1013760074**
WNW **3402 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.016 mi.
83 ft. **Site 3 of 6 in cluster IB**

Actual:
597 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1965	WEEDON DON AUTOMOTIVE	AUTOMOBILE REPAIRING
1970	WEEDON DON AUTOMOTIVE SERVICE R	AUTOMOBILE REPAIRING
1975	WEEDON DON AUTOMOTIVE SERVICE R	AUTOMOBILE REPAIRING
1980	WEEDON DON AUTOMOTIVE SERVICE R	AUTOMOBILE REPAIRING
1984	DALES UNIVERSITY AUTO REPAIR CE	AUTOMOBILE REPAIRING

IB1240 **PREVIOUS PAWN SHOP** **TX HIST UST** **S123213509**
WNW **3402 GUADALUPE STREET** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.016 mi.
83 ft. **Site 4 of 6 in cluster IB**

Actual:
597 ft.
HIST UST AUSTIN:

Focus Map:
8

Name:	R & K INVESTMENTS
Address:	3402 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0341
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PREVIOUS PAWN SHOP (Continued) **S123213509**

ASBESTOS:

Name:	PREVIOUS PAWN SHOP
Address:	3402 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Charles Staffeld
Violation:	Not reported
Complaint Date:	08/17/2020
Notification Number:	2020004919
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/28/2020
Certification Statement Phone:	800-231-2988
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported

PREVIOUS PAWN SHOP (Continued) **S123213509**

Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT RETAIL
Address:	3402 GUADALUPE STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Pat Fleener
Violation:	Not reported
Complaint Date:	11/23/2018
Notification Number:	2018008235
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/08/2018
Certification Statement Phone:	512-336-7665
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	6
Is this a phased abatement project?:	N

PREVIOUS PAWN SHOP (Continued) **S123213509**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/23/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

IB1241 **CASH AMERICAN PAWN SHOP** **TX LPST** **S105050211**
WNW **3402 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.016 mi.
83 ft. **Site 5 of 6 in cluster IB**

Actual:
597 ft.

Focus Map:
8

LPST:

Name:	CASH AMERICAN PAWN SHOP
Address:	3402 GUADALUPE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	104444
Facility Location:	3402 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/31/1992
Entered Date:	10/01/1992
Reported Date:	08/31/1992
Closure Date:	01/10/1994
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	KRIS HAWKINS
Responsible Party Address:	5716 W HWY 290
Responsible Party City,St,Zip:	AUSTIN, TX 78735
Responsible Party Telephone:	512/892-6000

CASH AMERICAN PAWN SHOP (Continued) **S105050211**

Reported Date: 08/31/1992
Case Start Date: 01/10/1994
Reference Number: RN106980204
Project Manager: HWELCH

DY1242 **ELLIOTT CARL L** **EDR Hist Auto** **1013772576**
NNE **300 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.016 mi.
83 ft. **Site 3 of 11 in cluster DY**

Actual:
478 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	ELLIOTT CARL L	GASOLINE STATIONS

IC1243 **SPIRES TIRE CO INC** **EDR Hist Auto** **1013766776**
WNW **3510 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 5 of 10 in cluster IC**

Actual:
595 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1947	JAMES HERSHEL SERVICE STATION F	GASOLINE AND OIL SERVICE STATIONS
1953	SPIRES TIRE CO INC	GASOLINE STATIONS

IC1244 **SULLIVAN CARDINAL DCLO CLNR** **EDR Hist Cleaner** **1013783624**
WNW **3510 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 6 of 10 in cluster IC**

Actual:
595 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1929	SULLIVAN CARDINAL DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

DE1245 **THOMPSON BILL INC** **EDR Hist Auto** **1013770914**
WNW **417 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
83 ft. **Site 10 of 13 in cluster DE**

Actual:
493 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	THOMPSON BILL INC	AUTOMOBILE REPAIRERS

IP1246 **FELTON B F C CLDO** **EDR Hist Cleaner** **1013785638**
NNE **422 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
84 ft. **Site 4 of 5 in cluster IP**

Actual:
487 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	FELTON B F C CLDO	CLOTHES CLEANERS AND PRESSERS
1929	PIERCE R 0 C DCLO CLNR	CLOTHES CLEANERS AND PRESSERS
1940	HOPKINS CLEANERS	CLOTHES PRESSERS AND CLEANERS

Y1247 **ALAMO BOILER & MACHINE WORKS** **TX HIST UST** **S111678549**
NW **8134 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
84 ft. **Site 3 of 3 in cluster Y**

Actual:
740 ft.

HIST UST AUSTIN:

Focus Map:
6

Name:	ALAMO BOILER & MACHINE WORKS
Address:	8134 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0597
HID UST:	597
Inspection:	Not reported
Due:	06/01/2012

BB1248 **CEARLEY E A FILL STA** **EDR Hist Auto** **1013753232**
WNW **3700 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
84 ft. **Site 11 of 13 in cluster BB**

Actual:
595 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1929	CEARLEY E A FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	ROSS PAUL FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	BASEY 0 C FILLING	GASOLINE AND OIL SERVICE STATIONS

BA1249 **JIFFY LUBE AUTO REPR** **EDR Hist Auto** **1013754746**
ESE **3809 GUADALUPE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.016 mi.
85 ft. **Site 3 of 7 in cluster BA**

Actual:
600 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1988	3B + 3B INC	General Automotive Repair Shops
1990	JIFFY LUBE AUTO REPR	AUTOMOBILE REPAIRING
2013	HEARTLAND AUTOMOTIVE SVCS INC	Automotive Maintenance Services
2014	HEARTLAND AUTOMOTIVE SVCS INC	Automotive Maintenance Services

BA1250 ESE < 1/8 0.016 mi. 85 ft. | **JIFFY LUBE STORE #829 3809 GUADALUPE AUSTIN, TX** | **TX RDR** | **S127533766 N/A**

Site 4 of 7 in cluster BA

Actual: 600 ft.

Focus Map: 8

RDR:

RDR ID:	6516
Facility ID:	45667
RN:	Not reported
CN:	Not reported
Name:	JIFFY LUBE STORE #829
Address:	3809 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	HEARTLAND AUTOMOTIVE SERV
Contact Person:	PHILLIP MEYERS
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	5/27/1998
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	5/27/1998
Region:	Not reported
DKC RDR (misfiled):	Not reported

BA1251 ESE < 1/8 0.016 mi. 85 ft. | **JIFFY LUBE 3809 GUADALUPE AUSTIN, TX** | **TX RDR** | **S127542900 N/A**

Site 5 of 7 in cluster BA

Actual: 600 ft.

Focus Map: 8

RDR:

RDR ID:	11233
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	JIFFY LUBE
Address:	3809 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	HEARTLAND AUTOMOTIVE
Contact Person:	PHILLIP MEYERS
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	9/17/1998
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported

JIFFY LUBE (Continued) **S127542900**

Comments:	RDR 1ST RTND 3/17/1998
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	9/17/1998
Region:	Not reported
DKC RDR (misfiled):	Not reported

BA1252 **HEARTLAND AUTOMOTIVE SERVICES JIFFY LUBE** **RCRA-SQG** **1000469966**
ESE **3809 GUADALUPE** **FINDS** **TXD988018420**
< 1/8 **AUSTIN, TX 78751** **ECHO**
0.016 mi.
85 ft. **Site 6 of 7 in cluster BA**

Actual:
600 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	19950628
Handler Name:	Jiffy Lube
Handler Address:	GUADALUPE
Handler City,State,Zip:	AUSTIN, TX 78751
EPA ID:	TXD988018420
Contact Name:	JERRY RODDICK
Contact Address:	3809 GUADALUPE
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Telephone:	512-453-0210
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE
Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Name:	J-Lube Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

HEARTLAND AUTOMOTIVE SERVICES JIFFY LUBE (Continued) **1000469966**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: J-LUBE INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950628
Handler Name: JIFFY LUBE	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

HEARTLAND AUTOMOTIVE SERVICES JIFFY LUBE (Continued) **1000469966**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005123455

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000469966
Registry ID: 110005123455
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005123455
Name: HEARTLAND AUTOMOTIVE SERVICES JIFFY LUBE
Address: 3809 GUADALUPE
City,State,Zip: AUSTIN, TX 78751

BA1253 **JIFFY LUBE** **TX UST** **U001277225**
ESE **3809 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.016 mi.
85 ft. **Site 7 of 7 in cluster BA**

Actual:
600 ft.

Focus Map:
8

UST:
Name: JIFFY LUBE
Address: 3809 GUADALUPE ST
City,State,Zip: AUSTIN, TX 787514907
AI Number: 45667
Facility Type: RETAIL
Facility Begin Date: 12/29/1987

JIFFY LUBE (Continued) **U001277225**

Facility Status:	INACTIVE
Additional ID:	683025632002149
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	,
Contact Organization Name:	JIFFY LUBE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123285757
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/14/1987
Signature Name/Title On Earliest Reg Form:	JERRY RODDICK,OWNER
Application Received Date On Earliest Reg Form:	12/28/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601589260
Owner Last Name:	JIFFY LUBE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	4341212003093
Additional ID:	683025632002149
AI Number:	45667
Owner Effective Begin Date:	12/29/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	12/28/1987

JIFFY LUBE (Continued) **U001277225**

Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119547
Facility ID:	77183
Ai Number:	45667
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

JIFFY LUBE (Continued) **U001277225**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	118344
UST ID:	119547
AI Number:	45667
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	12/28/1987
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119548
Facility ID:	77183
Ai Number:	45667

JIFFY LUBE (Continued) **U001277225**

Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	118345
UST ID:	119548

JIFFY LUBE (Continued) **U001277225**

AI Number:	45667
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	12/28/1987
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119549
Facility ID:	77183
Ai Number:	45667
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

JIFFY LUBE (Continued) **U001277225**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	118346
UST ID:	119549
AI Number:	45667
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

JIFFY LUBE (Continued) **U001277225**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	12/28/1987
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119550
Facility ID:	77183
Ai Number:	45667
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

JIFFY LUBE (Continued) **U001277225**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	118347
UST ID:	119550
AI Number:	45667
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

JIFFY LUBE (Continued) **U001277225**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	JIFFY LUBE
Contact Mailing Address (Delivery):	3809 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 4907
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77183
Additional ID:	683025632002149
Princ ID:	4341212003093
AI Number:	45667
Facility Name:	JIFFY LUBE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JERRY RODICK/

HIST UST AUSTIN:

Name:	JIFFY LUBE
Address:	3809 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0047
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GS1254 **MCCOY'S LAWN EQUIPMENT** **TX HIST UST** **S111678820**
WNW **4140 S CONGRESS AVE** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.016 mi.
85 ft. **Site 3 of 6 in cluster GS**

Actual:
667 ft.

Focus Map:
18

HIST UST AUSTIN:

Name:	TEXAS COMPANY-GOODNIGHT PROP.
Address:	4140 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0578
HID UST:	578
Inspection:	07/14/2011
Due:	07/14/2014

ASBESTOS:

Name:	FORMER MCCOY S LAWN EQUIPMENT
Address:	4140 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	06/03/2022
Notification Number:	2022003414
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/03/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/03/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	8

MCCOY'S LAWN EQUIPMENT (Continued) **S111678820**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/02/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER MCCOY S LAWN EQUIPMENT
Address:	4140 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	06/06/2022
Notification Number:	2022003414
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

MCCOY'S LAWN EQUIPMENT (Continued) **S111678820**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/20/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/02/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCOY'S LAWN EQUIPMENT
Address:	4140 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/12/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07

MCCOY'S LAWN EQUIPMENT (Continued) **S111678820**

Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/19/2013
Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCOY'S LAWN EQUIPMENT
Address:	4140 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745

MCCOY'S LAWN EQUIPMENT (Continued) **S111678820**

Date of inspection:	03/12/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/17/2014
Date Routed by Supervisor:	03/18/2014
Date Routed to PSQA:	03/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

MCCOY'S LAWN EQUIPMENT (Continued) **S111678820**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AR1255 **CECILS AUTO TRIM** **TX UST** **U001277169**
WNW **4926 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.016 mi.
85 ft. **Site 2 of 5 in cluster AR**

Actual:
664 ft.

Focus Map:
8

UST:

Name:	CECILS AUTO TRIM
Address:	4926 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787512316
AI Number:	45597
Facility Type:	RETAIL
Facility Begin Date:	02/16/1988
Facility Status:	INACTIVE
Additional ID:	473715352002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	CECIL IRBY,GEOLOGIST
Contact Organization Name:	CECILS AUTO TRIM
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123279501
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/20/1987
Signature Name/Title On Earliest Reg Form:	CECIL IRBY,GEOLOGIST
Application Received Date On Earliest Reg Form:	01/21/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784243
Owner Last Name:	CECILS AUTO TRIM INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported

CECILS AUTO TRIM (Continued) **U001277169**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	464715342002053
Additional ID:	473715352002053
AI Number:	45597
Owner Effective Begin Date:	02/16/1988
State Tax ID:	17415322647
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1962
Tank Registration Date:	01/21/1987
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119381
Facility ID:	77158
Ai Number:	45597
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	12/01/1969
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

CECILS AUTO TRIM (Continued) **U001277169**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	118259
UST ID:	119381
AI Number:	45597
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

CECILS AUTO TRIM (Continued) **U001277169**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/21/1987
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119382
Facility ID:	77158
Ai Number:	45597
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	12/01/1969
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

CECILS AUTO TRIM (Continued) **U001277169**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	118260
UST ID:	119382
AI Number:	45597
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

CECILS AUTO TRIM (Continued) **U001277169**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1962
Tank Registration Date:	01/21/1987
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119383
Facility ID:	77158
Ai Number:	45597
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	12/01/1969
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

CECILS AUTO TRIM (Continued) **U001277169**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	118261
UST ID:	119383
AI Number:	45597
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CECILS AUTO TRIM INC
Contact Mailing Address (Delivery):	4926 N LAMAR BLVD

CECILS AUTO TRIM (Continued) **U001277169**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 2316
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77158
Additional ID:	473715352002053
Princ ID:	464715342002053
AI Number:	45597
Facility Name:	CECILS AUTO TRIM
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	CECIL'S AUTO TRIM
Address:	4926 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0055
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AR1256 **AUSTIN RADIATOR WORKS NO** **EDR Hist Auto** **1013771321**
WNW **4926 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.016 mi.
85 ft. **Site 3 of 5 in cluster AR**

Actual:
664 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1969	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1970	AUSTIN RADIATOR WORKS NO	AUTOMOBILE RADIATOR REPAIRERS
1970	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1971	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1972	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1973	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1974	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1975	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1976	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1977	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC

BO1257 **SHAFER C D SERVICE STATION** **EDR Hist Auto** **1013753394**
West **2600 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
86 ft. **Site 3 of 5 in cluster BO**

Actual:
602 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	MAGNOLIA PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	SHAFER CHAS D FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	SHAFER C D SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1953	NASH & SASSMAN	GASOLINE STATIONS
1958	NASH & SASSMAN	GASOLINE STATIONS
1962	CLYDES CONOCO SERV	GASOLINE STATIONS
1965	LONGHORN CONOCO SERVICE	GASOLINE STATIONS
1970	RAVES TRAVIS CONOCO NO	GASOLINE STATIONS
1970	SLACK EDDIE SERVICE CENTER	Gasoline Service Stations
1972	JACKS CONOCO	Gasoline Service Stations
1973	JACKS CONOCO	Gasoline Service Stations
1974	JACKS CONOCO	Gasoline Service Stations
1975	JACKS CONOCO	Gasoline Service Stations

BO1258 **7 ELEVEN 16996** **TX RDR** **S127538747**
West **2600 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
86 ft. **Site 4 of 5 in cluster BO**

Actual:
602 ft.

Focus Map:
11

RDR:

RDR ID:	15734
Facility ID:	7175
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 16996
Address:	2600 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/29/2006
Due Date:	1/28/2007
Tank Owner:	7 ELEVEN INC
Contact Person:	SHANE PARTRIDGE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/2/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	102858
Comments:	DOES THIS NEED A LPST #?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/2/2007
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

BO1259 **7-ELEVEN 16996** **TX LPST** **U001243598**
West **2600 GUADALUPE ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.016 mi. **TX ASBESTOS**
86 ft. **Site 5 of 5 in cluster BO** **TX Financial Assurance**
TX RDR

Actual:
602 ft.

Focus Map:
11

LPST:

Name:	7 ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0007175
LPST Id:	102858
Facility Location:	2600 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/24/1992
Entered Date:	05/18/1992
Reported Date:	04/27/1992
Closure Date:	03/08/1995
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	JES
Responsible Party Name:	Not reported
Responsible Party Contact:	ROD TOWNS
Responsible Party Address:	PO BOX 711
Responsible Party City,St,Zip:	DALLAS, TX 75221
Responsible Party Telephone:	214/907-0711
Reported Date:	04/27/1992
Case Start Date:	03/08/1995
Reference Number:	RN102020625
Project Manager:	JSIROTA

UST:

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787054009
AI Number:	7175
Facility Type:	RETAIL
Facility Begin Date:	04/01/1974
Facility Status:	ACTIVE
Additional ID:	730180392002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN 16996
Contact Mailing Address1:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	730180392002117
Ai Number:	7175
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257

7-ELEVEN 16996 (Continued) **U001243598**

Additional ID:	730180392002117
AI Number:	7175
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46177
Cert ID:	381580
AI Number:	7175
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	364256
AI Number:	7175
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	348449
AI Number:	7175
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	330706
AI Number:	7175
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	314624
AI Number:	7175
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	296190
AI Number:	7175
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	280851
AI Number:	7175
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	263477
AI Number:	7175
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	247179
AI Number:	7175
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	229555
AI Number:	7175
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46177
Cert ID:	28117
AI Number:	7175
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46177
Cert ID:	28116
AI Number:	7175
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28115
AI Number:	7175
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28114
AI Number:	7175
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28113
AI Number:	7175
Self Certification Date:	07/17/2009
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28112
AI Number:	7175
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28111
AI Number:	7175
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28110
AI Number:	7175
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28109
AI Number:	7175
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28108
AI Number:	7175
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28107
AI Number:	7175
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28106
AI Number:	7175
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28105
AI Number:	7175
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46177
Cert ID:	28104
AI Number:	7175
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18616
Facility ID:	46177
Ai Number:	7175
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y

7-ELEVEN 16996 (Continued) **U001243598**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26098
UST ID:	18616
AI Number:	7175
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Install Date:	04/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18617
Facility ID:	46177
Ai Number:	7175
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

7-ELEVEN 16996 (Continued) **U001243598**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26099
UST ID:	18617
AI Number:	7175
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18618

7-ELEVEN 16996 (Continued) **U001243598**

Facility ID:	46177
Ai Number:	7175
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000

7-ELEVEN 16996 (Continued) **U001243598**

UST Comprt ID:	26100
UST ID:	18618
AI Number:	7175
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	06/17/2009
Tank Registration Date:	07/22/2009
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	212471
Facility ID:	46177
Ai Number:	7175
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	06/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	07/15/2009

Compartment Records:

Tank ID:	4
Tank Capacity:	15000
UST Comprt ID:	26101
UST ID:	212471
AI Number:	7175
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

7-ELEVEN 16996 (Continued) **U001243598**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/17/2009

Install Date:	06/17/2009
Tank Registration Date:	07/22/2009
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	212472
Facility ID:	46177
Ai Number:	7175
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	06/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 16996 (Continued) **U001243598**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	07/15/2009

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	26102
UST ID:	212472
AI Number:	7175
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

7-ELEVEN 16996 (Continued) **U001243598**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/17/2009

Construction Notification:

NOC ID:	2521
Facility ID:	46177
AI Number:	7175
Application Received Date:	05/05/2000
Scheduled Construction Date:	05/09/2000
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00505005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2520
Facility ID:	46177

7-ELEVEN 16996 (Continued) **U001243598**

AI Number:	7175
Application Received Date:	06/06/2006
Scheduled Construction Date:	06/10/2006
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60606002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	2788
UST ID:	Not reported
NOC ID:	2521
AI Number:	7175
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001306
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2787
UST ID:	Not reported
NOC ID:	2520
AI Number:	7175
Type Of Contact:	CONTRACTOR

7-ELEVEN 16996 (Continued) **U001243598**

Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	26897
UST ID:	212471
NOC ID:	Not reported
AI Number:	7175
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	26898
UST ID:	212472
NOC ID:	Not reported
AI Number:	7175
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42061
UST ID:	212471
NOC ID:	Not reported
AI Number:	7175
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42062
UST ID:	212472
NOC ID:	Not reported
AI Number:	7175
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46177
Additional ID:	730180392002117
Princ ID:	959578622001257
AI Number:	7175
Facility Name:	7-ELEVEN 16996
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN STORE #16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	802
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/02/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	7-ELEVEN
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	08/14/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/18/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Name:	7-ELEVEN
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/10/2015
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.7
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	278705
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	261554
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001

7-ELEVEN 16996 (Continued) **U001243598**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	242261
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	223524
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2

7-ELEVEN 16996 (Continued) **U001243598**

Facility ID:	46177
Finass ID:	224124
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	207933
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	189241
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7-ELEVEN 16996 (Continued) **U001243598**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	172710
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	173786
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No

7-ELEVEN 16996 (Continued) **U001243598**

Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	154054
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	138250
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	118595
AI:	7175

7-ELEVEN 16996 (Continued) **U001243598**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 972 8287805
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	120383
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	2248
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28809
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28810
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996

7-ELEVEN 16996 (Continued) **U001243598**

Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28812
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28811
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28813
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

7-ELEVEN 16996 (Continued) **U001243598**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28814
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	46177
Finass ID:	28815
AI:	7175
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown

7-ELEVEN 16996 (Continued) **U001243598**

Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	18471
Facility ID:	7175
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN 16996
Address:	2600 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/1/2009
Due Date:	11/30/2009
Tank Owner:	7-ELEVEN
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	11/4/2009
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	102858
Comments:	FSC 1/6/2010.
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	11/4/2009
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

F1260 **BARGAIN BARN** **TX HIST UST** **S128729099**
WNW **11400 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
87 ft. **Site 3 of 6 in cluster F**

Actual:
754 ft.

Focus Map:
3

HIST UST AUSTIN:

Name:	BARGAIN BARN
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0646
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

F1261 **ORACLE AUSTIN DATA CENTER** **TX HIST UST** **S128728705**
WNW **11400 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.016 mi.
87 ft. **Site 4 of 6 in cluster F**

Actual:
754 ft.

Focus Map:
3

HIST UST AUSTIN:

Name:	ORACLE AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3268
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

F1262 **ORACLE-AUSTIN DATA CENTER** **TX UST** **U001289584**
WNW **11400 N LAMAR BLVD** **TX Financial Assurance** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.016 mi.
87 ft. **Site 5 of 6 in cluster F**

Actual:
754 ft.

Focus Map:
3

UST:

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532663
AI Number:	60088
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	10/02/1991
Facility Status:	ACTIVE
Additional ID:	58532632003161
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	TOM WAYLAND,ENGINEER
Contact Organization Name:	ORACLE-AUSTIN DATA CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128731136
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	TOM.WAYLAND@ORACLE.COM
Signature Date On Earliest Reg Form:	05/24/2022
Signature Name/Title On Earliest Reg Form:	TOM WAYLAND,ENG
Application Received Date On Earliest Reg Form:	07/01/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	911489222004083
Additional ID:	58532632003161

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Ai Number:	60088
Operator CN:	CN602594046
Operator Name:	ORACLE CORPORATION
Operator Effective Begin Date:	07/09/2003
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	MITCH MARTIN/
Contact Organization Name:	ORACLE CORPORATION
Contact Mailing Address (Delivery):	11400 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-2663
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	8731136
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	TOM.WAYLAND@ORACLE.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602594046
Owner Last Name:	ORACLE CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	11400 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	2663
Contact Phone Number/Ext:	1 512 8731136/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	TOM.WAYLAND@ORACLE.COM
Contact Address Deliverable:	Not reported
Princ ID:	911489222004083
Additional ID:	58532632003161
AI Number:	60088
Owner Effective Begin Date:	07/09/2003
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	MITCH MARTIN/
Contact Organization Name:	ORACLE CORPORATION

Self Certification:

Self Cert ID:	90583
Cert ID:	373134
AI Number:	60088
Self Certification Date:	05/24/2022
Signature Name/Title:	TOM WAYLAND ENG
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	355275
AI Number:	60088
Self Certification Date:	05/07/2021
Signature Name/Title:	TOM WAYLAND ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	338631
AI Number:	60088
Self Certification Date:	06/02/2020
Signature Name/Title:	TOM WAYLAND ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	321034
AI Number:	60088
Self Certification Date:	05/17/2019
Signature Name/Title:	MITCH MARTIN MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	303803
AI Number:	60088
Self Certification Date:	05/09/2018
Signature Name/Title:	MITCH MARTIN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	286471
AI Number:	60088
Self Certification Date:	04/24/2017
Signature Name/Title:	MITCH MARTIN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	270043
AI Number:	60088
Self Certification Date:	05/10/2016
Signature Name/Title:	STEPHEN METCALF MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	252890
AI Number:	60088
Self Certification Date:	04/23/2015
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	237131
AI Number:	60088
Self Certification Date:	05/05/2014
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90583
Cert ID:	220555
AI Number:	60088
Self Certification Date:	04/26/2013
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	90583
Cert ID:	143023
AI Number:	60088
Self Certification Date:	04/25/2012
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143022
AI Number:	60088
Self Certification Date:	04/26/2011
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143021
AI Number:	60088
Self Certification Date:	04/23/2010
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143020
AI Number:	60088
Self Certification Date:	06/26/2009
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143019
AI Number:	60088
Self Certification Date:	04/23/2008
Signature Name/Title:	STEPHEN METCALF SR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143018
AI Number:	60088
Self Certification Date:	04/20/2007
Signature Name/Title:	STEPHEN METCALF DATA CENTER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143017
AI Number:	60088
Self Certification Date:	04/24/2006
Signature Name/Title:	STEVE METCALF DATA CENTER MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143016
AI Number:	60088
Self Certification Date:	04/20/2005
Signature Name/Title:	STEPHEN METCALF SR MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143015
AI Number:	60088
Self Certification Date:	04/21/2004
Signature Name/Title:	STEPHEN METCALF SR MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143014
AI Number:	60088
Self Certification Date:	11/07/2003
Signature Name/Title:	STEVE METCALF SR MGR-FACILITIES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143013
AI Number:	60088
Self Certification Date:	03/13/2003
Signature Name/Title:	CECILIA SCOPEL MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90583
Cert ID:	143012
AI Number:	60088
Self Certification Date:	02/27/2002
Signature Name/Title:	CECILIA SCOPEL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1946
Tank Registration Date:	09/27/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	141446
Facility ID:	90583
Ai Number:	60088
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2A
Tank Capacity:	1000
UST Comprt ID:	137737
UST ID:	141446
AI Number:	60088
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1946
Tank Registration Date:	09/27/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	141447
Facility ID:	90583
Ai Number:	60088
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/18/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1A
Tank Capacity:	1000
UST Comprt ID:	137738
UST ID:	141447
AI Number:	60088
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	05/29/2001
Tank Registration Date:	03/06/2002
Number of Compartments:	1

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199491
Facility ID:	90583
Ai Number:	60088
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	05/29/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Tank Tested Flag:	Y
Installation Signature Date:	02/26/2002

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	137739
UST ID:	199491
AI Number:	60088
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	05/29/2001
Tank Registration Date:	03/06/2002
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199492
Facility ID:	90583
Ai Number:	60088
Tank Id:	2

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Tank Status (Current):	IN USE
Tank Status Date:	05/29/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/26/2002

Compartment Records:

Tank ID:	2
Tank Capacity:	20000
UST Comprt ID:	137740
UST ID:	199492
AI Number:	60088

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	05/29/2001
Tank Registration Date:	03/06/2002
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199493
Facility ID:	90583
Ai Number:	60088
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	05/29/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/26/2002

Compartment Records:

Tank ID:	3
Tank Capacity:	20000
UST Comprt ID:	137741
UST ID:	199493
AI Number:	60088
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	05/29/2001
Tank Registration Date:	03/06/2002
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	199494
Facility ID:	90583
Ai Number:	60088
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	05/29/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/26/2002

Compartment Records:

Tank ID:	4
Tank Capacity:	20000
UST Comprt ID:	137742
UST ID:	199494
AI Number:	60088
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	30062
Facility ID:	90583
AI Number:	60088
Application Received Date:	08/10/2016
Scheduled Construction Date:	08/08/2016
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	08/10/2016
Signature Date On Form:	08/10/2016
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	ORACLE CORPORATION
Owner CN At Time Of Construction:	CN602594046
Owner AR At Time Of Construction:	61916
General Desc Of Prop Construct:	INSTALL ALL NEW DOUBLE WALL SUMPS & REMOVE SINGLE WALL PIPING. INSTALL SMITH FIBERGLASS PIPING.

NOC ID:	15247
Facility ID:	90583
AI Number:	60088
Application Received Date:	03/09/2001

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Scheduled Construction Date:	04/15/2001
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10309003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	08/10/2016
Signature Date On Form:	08/10/2016
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	8634
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	71042
UST ID:	Not reported
NOC ID:	30062
AI Number:	60088
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	31415
UST ID:	199492
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	31417
UST ID:	199494
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	31416
UST ID:	199493
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	31414
UST ID:	199491
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	46582
UST ID:	199492
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	46584

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

UST ID:	199494
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	46581
UST ID:	199491
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	46583
UST ID:	199493
NOC ID:	Not reported
AI Number:	60088
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	71043
UST ID:	Not reported
NOC ID:	30062
AI Number:	60088
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Facility Billing Contacts:

Contact Organization Name:	ORACLE CORPORATION
Contact Mailing Address (Delivery):	11400 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 2663
Phone Number/Ext:	512 8731136/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	90583
Additional ID:	58532632003161
Princ ID:	911489222004083
AI Number:	60088
Facility Name:	ORACLE-AUSTIN DATA CENTER
AR Number:	61916
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	MITCH MARTIN/

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

TX Financial Assurance 2:

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	270974
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/01/2021
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 513 3695000
Policy Number:	STP-E601112 01
Coverage Amount:	2,000,000
Coverage Expiration Date:	08/01/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	252021
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/01/2020
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	OTHER
Issuer Phone:	1 513 3695000
Policy Number:	STP E601112 00
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	233353
AI:	60088
Mechanism Type Other:	Not reported

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2019
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	USTG27303493 007
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	214663
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2018
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G27303493 006
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	197154
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2017
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Issuer Phone:	1 215 6401000
Policy Number:	G27303493005
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	179447
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2016
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G27303493 004
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	162314
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2015
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 713 4033217
Policy Number:	UST G27303493 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	144040
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2014
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USTG27303493002
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	128647
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2013
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 9514119
Policy Number:	USTG27303493001
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/03/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	109280
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2012
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USC 9426793 03
Coverage Amount:	2,000,000
Coverage Expiration Date:	10/03/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	9593
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2011
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9426793 02
Coverage Amount:	2000000
Coverage Expiration Date:	10/03/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	77106
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2010
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9426793 01
Coverage Amount:	2000000

ORACLE-AUSTIN DATA CENTER (Continued) **U001289584**

Coverage Expiration Date:	10/03/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	77107
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/2009
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9426793 00
Coverage Amount:	2000000
Coverage Expiration Date:	10/03/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ORACLE-AUSTIN DATA CENTER
Address:	11400 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	90583
Finass ID:	77108
AI:	60088
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	07/01/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

F1263 WNW < 1/8 0.016 mi. 87 ft. — **JONES MACK SERVICE STATION**, **11400 N LAMAR**, **AUSTIN, TX 78753** — **EDR Hist Auto** — **1021595106** / **N/A**

Site 6 of 6 in cluster F

Actual: 754 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1972	JONES MACK SERVICE STATION	Gasoline Service Stations
1973	JONES MACK SERVICE STATION	Gasoline Service Stations
1974	JONES MACK SERVICE STATION	Gasoline Service Stations
1976	JONES MACK SERVICE STATION	Gasoline Service Stations
1977	JONES MACK SERVICE STATION	Gasoline Service Stations
1978	JONES MACK SERVICE STATION	Gasoline Service Stations
1979	JONES MACK SERVICE STATION	Gasoline Service Stations
1980	JONES MACK SERVICE STATION	Gasoline Service Stations
1982	JONES MACK SERVICE STATION	Gasoline Service Stations
1983	JONES MACK SERVICE STATION	Gasoline Service Stations

CP1264 WNW < 1/8 0.016 mi. 87 ft. — **AUTOMATIC TRANS**, **1300 CONGRESS AVE**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013756185** / **N/A**

Site 2 of 2 in cluster CP

Actual: 546 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	AUTOMATIC TRANS	AUTOMOBILE REPAIRING

IG1265 West < 1/8 0.016 mi. 87 ft. — **WILLIAMS WESS**, **2100 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013779595** / **N/A**

Site 2 of 2 in cluster IG

Actual: 568 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	WILLIAMS WESS	LAUNDRIES
1958	WILLIAMS WESS	LAUNDRIES
1962	WILLIAMS WESS	LAUNDRIES
1965	WILLIAMS WESS LAUNDRY	LAUNDRIES

FF1266 NE < 1/8 0.017 mi. 88 ft. — **DIAMOND SHAMROCK 236**, **1620 E RIVERSIDE DR**, **AUSTIN, TX 78741** — **TX LPST**, **TX UST**, **TX HIST UST**, **TX Financial Assurance**, **TX RDR** — **U003566336** / **N/A**

Site 7 of 8 in cluster FF

Actual: 470 ft. LPST:

Focus Map: 14

Name:	DIAMOND SHAMROCK 236
Address:	1620 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0045204
LPST Id:	116305

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Facility Location:	1620 E RIVERSIDE DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/29/2002
Entered Date:	12/16/2004
Reported Date:	11/08/2002
Closure Date:	12/22/2004
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P
Coordinators RPR:	MICHAEL BAME
Responsible Party Name:	Not reported
Responsible Party Contact:	C SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/592-4669
Reported Date:	11/08/2002
Case Start Date:	12/22/2004
Reference Number:	RN102379898
Project Manager:	MBAME

UST:

Name:	DIAMOND SHAMROCK 236
Address:	1620 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411008
AI Number:	45204
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	763051542002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	CHRIS TRINKLE,
Contact Organization Name:	DIAMOND SHAMROCK 236
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2105924666
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	JAMES MANNING,DIV MGR
Application Received Date On Earliest Reg Form:	10/08/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Facility Not Inspectable:	No

Operator:

Princ ID:	765580132003199
Additional ID:	763051542002150
Ai Number:	45204
Operator CN:	CN602277386
Operator Name:	CST SERVICES LLC
Operator Effective Begin Date:	09/01/1987
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	KENT HAMEL/COORD
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78269-6000
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	3454670
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	SAN ANTONIO
Contact Mailing State:	TX
Contact Mailing Zip:	78269
Contact Mailing Zip5:	6000
Contact Phone Number/Ext:	1 210 3454670/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	763051542002150
AI Number:	45204
Owner Effective Begin Date:	09/01/1987
State Tax ID:	17425053794
Contact Role:	OWNCON
Contact Name/Title:	KENT HAMEL/COORDINATOR
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY

Self Certification:

Self Cert ID:	74590
Cert ID:	105073
AI Number:	45204

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118357
Facility ID:	74590
Ai Number:	45204
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/02/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

DIAMOND SHAMROCK 236 (Continued) **U003566336**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9994
UST Comprt ID:	104344
UST ID:	118357
AI Number:	45204
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118358
Facility ID:	74590
Ai Number:	45204
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/22/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

DIAMOND SHAMROCK 236 (Continued) **U003566336**

PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	9994
UST Comprt ID:	104345
UST ID:	118358
AI Number:	45204
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	7895
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118359
Facility ID:	74590
Ai Number:	45204
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/22/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	7895
UST Comprt ID:	104346
UST ID:	118359
AI Number:	45204
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	11160
Facility ID:	74590
AI Number:	45204
Application Received Date:	06/28/2002
Scheduled Construction Date:	08/19/2002
UST Improvement:	N

DIAMOND SHAMROCK 236 (Continued) **U003566336**

UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M20628008
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	11159
Facility ID:	74590
AI Number:	45204
Application Received Date:	09/12/2001
Scheduled Construction Date:	09/20/2001
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00912009
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	11994
UST ID:	Not reported
NOC ID:	11159
AI Number:	45204

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11995
UST ID:	Not reported
NOC ID:	11160
AI Number:	45204
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74590
Additional ID:	763051542002150
Princ ID:	765580132003199
AI Number:	45204

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Facility Name:	DIAMOND SHAMROCK 236
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	DIAMOND SHAMROCK #0236
Address:	1620 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	387
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	DIAMOND SHAMROCK 236
Address:	1620 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74590
Finass ID:	57949
AI:	45204
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	6434
Facility ID:	45204
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 236
Address:	1620 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/7/2003
Due Date:	5/6/2003
Tank Owner:	SIGMOR CORPORATION
Contact Person:	MACK BRICE
Report:	RDR
Latest TCEQ Letter:	Not reported

DIAMOND SHAMROCK 236 (Continued) **U003566336**

Date of Latest TCEQ Letter:	Not reported
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	LPST# 116305 PPC; RTN; NEED VERTICAL DELINEATION, MISSING INFO FROM SECTION C.
Review Coordinator:	PPC/SRJ/SNW
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FF1267 **DIAMOND SHAMROCK INCORP** **EDR Hist Auto** **1020904884**
NE **1620 E RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.017 mi.
88 ft. **Site 8 of 8 in cluster FF**

Actual:
470 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1986	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1987	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1988	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1989	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1990	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1991	DIAMOND SHAMROCK INCORP	Gasoline Service Stations
1992	DIAMOND SHAMROCK INCORPORATED	Gasoline Service Stations
1993	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1994	DIAMOND SHAMROCK INC	Gasoline Service Stations
1995	DIAMOND SHAMROCK INC	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Gasoline Service Stations

G1268 **CVS PHARMACY 7442** **RCRA NonGen / NLR** **1014961822**
WNW **11300 11300 N LAMAR BLVD** **TXR000081087**
< 1/8 **AUSTIN, TX 78753**
0.017 mi.
88 ft. **Site 5 of 6 in cluster G**

Actual:
770 ft.

RCRA Listings:

Focus Map:
3

Date Form Received by Agency:	20220322
Handler Name:	Cvs Pharmacy 7442
Handler Address:	11300 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78753-2665
EPA ID:	TXR000081087
Contact Name:	WENDY BRANT
Contact Address:	1 CVS DR
Contact City,State,Zip:	WOONSOCKET, RI 02895-6146
Contact Telephone:	401-765-1500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

CVS PHARMACY 7442 (Continued) **1014961822**

EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1 CVS DR
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cvs Pharmacy Inc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220725
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CVS PHARMACY 7442 (Continued) **1014961822**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D007
Waste Description: Chromium

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146

CVS PHARMACY 7442 (Continued) **1014961822**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501

CVS PHARMACY 7442 (Continued) **1014961822**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

CVS PHARMACY 7442 (Continued) **1014961822**

Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BONIUK INTERESTS, LTD
Legal Status: Private
Date Became Current: 20040801
Date Ended Current: Not reported
Owner/Operator Address: 3720 SAN JACINTO
Owner/Operator City,State,Zip: HOUSTON, TX 77004
Owner/Operator Telephone: 713-984-8300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

CVS PHARMACY 7442 (Continued) **1014961822**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146

CVS PHARMACY 7442 (Continued) **1014961822**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501

CVS PHARMACY 7442 (Continued) **1014961822**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20130501
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

CVS PHARMACY 7442 (Continued) **1014961822**

Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20130501
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140301
Handler Name: CVS PHARMACY 7442
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160301
Handler Name: CVS PHARMACY 7442
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

CVS PHARMACY 7442 (Continued) **1014961822**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20120725
Handler Name: CVS PHARMACY #7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130501
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140407
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20141023
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CVS PHARMACY 7442 (Continued) **1014961822**

Receive Date:	20150222
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150222
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170206
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20171222
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20171222
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

CVS PHARMACY 7442 (Continued) **1014961822**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180821
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180821
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190212
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20191024
Handler Name: CVS PHARMACY 7442	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CVS PHARMACY 7442 (Continued) **1014961822**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220322
Handler Name: CVS PHARMACY 7442
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G1269 **CVS PHARMACY 7442** **TX ASBESTOS** **S116387837**
WNW **11300 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.017 mi.
88 ft. **Site 6 of 6 in cluster G**

Actual:
770 ft.

Focus Map:
3

ASBESTOS:
Name: CVS PHARMACY
Address: 11300 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78753
Date of inspection: 10/21/2015
Reason for Inspection: Routine
Violation: No
Complaint Date: Not reported
Notification Number: Not reported
ASB Priority: Not reported
PIF State: Not reported
Detained: Not reported
Product Name: Not reported
Time Spent: 0.5
Travel Time: 0.1
Mileage: 0.1
Reg: 07
Init: EJ
Seq: 02
Facility Type: Abusible Volitile Chemicals

CVS PHARMACY 7442 (Continued) **S116387837**

Inspector Name:	Eddie Jackson
Date Report Received:	11/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	11/06/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	11/05/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 7442
Address:	11300 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	95621

CVS PHARMACY 7442 (Continued) **S116387837**

Registration Initial Notification Date:	05/01/2013
Registration Last Amendment Date:	03/22/2022
EPA Identification:	TXR000081087
Primary NAICS Code:	446110
Status Change Date:	20220718
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130966
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220718
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA

CVS PHARMACY 7442 (Continued) **S116387837**

Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500
Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the back storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20130501
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

CVS PHARMACY 7442 (Continued) **S116387837**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150222
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM
Contact Name:	WENDY BRANT
Contact Title:	CVS CORPORATE ENVIRONMENT
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	380417
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

CVS PHARMACY 7442 (Continued) **S116387837**

Audit Performed:	0
Company Waste ID:	FLAM AEROSOL AND GAS
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362101
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aerosols, [flammable, (each not exceeding 1 L capacity)]; A new hazardous waste
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362102
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive liquids, Basic, n.o.s.; A new hazardous waste determination has been p
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQ BASIC
Primary NAICS Code:	446110

CVS PHARMACY 7442 (Continued) **S116387837**

EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	361052
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362103
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Oxidizing liquid, n.o.s.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

CVS PHARMACY 7442 (Continued) **S116387837**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362104
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS ORGANIC
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362100
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

CVS PHARMACY 7442 (Continued) **S116387837**

Ind. Haz Waste:

Waste ID:	380426
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389173
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

CVS PHARMACY 7442 (Continued) **S116387837**

Ind. Haz Waste:

Contact Name:	WENDY BRANT
Contact Title:	CVS CORPORATE ENVIRONMENT
Contact Telephone:	0-401-7651500 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	BRANT ,WENDY
Attention Suffix:	NWG

Contact Name:	WENDY BRANT
Contact Title:	CVS CORPORATE ENVIRONMENT
Contact Telephone:	0-401-7651500 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	BRANT ,WENDY
Attention Suffix:	HWG

BV1270 **COZY CLEANING AND** **EDR Hist Cleaner** **1013778862**
West **2402 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
88 ft. **Site 4 of 5 in cluster BV**

Actual:
590 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	COZY CLEANING AND	CLOTHES CLEANERS AND PRESSERS

1271 **W HOTEL BLOCK 21** **TX HIST UST** **S117273842**
SSW **200 LAVACA ST** **TX NPDES** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.017 mi.
88 ft.

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	THE W HOTEL
Address:	200 LAVACA ST
City,State,Zip:	AUSTIN, TX
Id UST:	3340
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NPDES:

Name:	W HOTEL BLOCK 21
Address:	200 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701

W HOTEL BLOCK 21 (Continued) **S117273842**

AI:	WQ0004854000
Facility Id:	15404
Facility Operational Status:	ACTIVE
Facility Disposal Method:	DISCHARGE
EPA Id:	TX0131547
EPA Fac Class:	MINOR
Auth Type:	IND WW
Approval Date:	10/21/2019
Original Approval Date:	11/06/2008
Expiration Date:	10/21/2024
Auth Status:	ACTIVE
Tpdes State:	TPDES
Permittee Name:	RHP Block 21, LLC
Permittee Address:	1 GAYLORD DR NASHVILLE, TN 37214-1207
Region:	REGION 11 - AUSTIN
Secondary Region/County:	Not reported
Site Location:	200 LAVACA ST, AUSTIN, TX, 78701
Permit Authority:	STATE
Compliance Authority:	STATE
Pretreatment Facility Design:	Not reported
Facility Toxic Rating:	2
Facility Average Design Flow:	Not reported
Loc In Coast Zone:	N
Instit Of High Learn:	N
Bio Energy Facility:	N
Primary Sic Code:	6513
Secondary Sic Code:	Not reported
Primary Naics Code:	Not reported
Secondary Naics Code:	Not reported
Segment:	1429
Basin:	14
Animal Type/Count:	Not reported
Latitude:	30.265555
Longitude:	-97.746944

Detail:

NPDES Number:	0131547
Permit Number:	04854-000
Letter:	Not reported
Status:	Current Permit
DTYPE:	W
Initials:	KJC
Latitude:	30.263848209999999
Longitude:	-97.74817917
Segment:	1429
Basin:	14
Region:	11
Horizontal Method:	DRG
Horizontal Accuracy:	12
Horizontal Reference:	other
Horizontal Date:	20190604
Horizontal Organization:	TCEQ
Horizontal Datum:	NAD83
Horizontal Description:	End of pipe as indicated on paper map
UTM Zone:	14

BS1272 **LONGHORN CLEANERS** **EDR Hist Cleaner** **1013778077**
West **2538 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
88 ft. **Site 4 of 4 in cluster BS**

Actual:
600 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	AUSTIN DRY CLNRS	CLOTHES PRESSERS AND CLEANERS
1940	LONGHORN CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	LONGHORN CLEANERS	CLOTHES PRESSERS AND CLEANERS
1953	LONGHORN CLNS	CLEANERS AND DYERS
1958	LONGHORN CLNS NO	CLEANERS AND DYERS
1962	LONGHORN CLNS NO 1	CLEANERS AND DYERS
1965	LONGHORN CLEANERS NO	CLEANERS AND DYERS
1969	LONGHORN CLEANERS INC	Drycleaning Plants, Except Rugs
1970	LONGHORN CLEANERS	CLEANERS AND DYERS
1970	LONGHORN CLEANERS INC	Drycleaning Plants, Except Rugs
1971	LONGHORN CLEANERS	Drycleaning Plants, Except Rugs

HB1273 **HERAEUS AMERSIL** **TX Ind. Haz Waste** **S102749681**
WSW **7715 E RIVERSIDE DR** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78744**
0.017 mi.
88 ft. **Site 2 of 3 in cluster HB**

Actual:
551 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	HERAEUS AMERSIL
Address:	7715 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	66140
Registration Initial Notification Date:	07/25/1983
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD988071411
Primary NAICS Code:	Not reported
Status Change Date:	19830725
Land Type:	Not reported
Description of Facility Site Location:	7715 Riverside Drive, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	HERAEUS AMERSIL INC
Contact Name:	ROGER LARSON
Contact Telephone Number:	512-2515530
Mailing Address:	2219 GRAND AVENUE PKWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787283812
Mailing County:	UNITED STATES

HERAEUS AMERSIL (Continued) **S102749681**

Facility Country:	UNITED STATES
TNRCC Facility ID:	21440
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	HERAEUS AMERSIL INC
Owner Mailing Address:	2219 GRAND AVENUE PKWY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78728
Owner Country:	UNITED STA
Owner Telephone:	1-512-2515530
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	12218136526
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2219 GRAND AVENUE PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78728
Contact Phone:	1-512-2515530
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ROGER LARSON
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	2219 GRAND AVENUE PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78728
Contact Phone:	1-512-2515530
Contact Fax:	Not reported
Contact Email:	Not reported

HERAEUS AMERSIL (Continued) **S102749681**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	E 7715A RIVERSIDE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000306917
Principal Name:	HERAEUS AMERSIL INC
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	E 7715A RIVERSIDE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000306917
Principal Name:	HERAEUS AMERSIL INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	E 7715A RIVERSIDE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000306917
Principal Name:	HERAEUS AMERSIL INC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	E 7715A RIVERSIDE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000306917
Principal Name:	HERAEUS AMERSIL INC
Attention Name:	Not reported
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100611342
Name:	HERAEUS AMERSIL
Address:	7715 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1644
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600320659
Customer Name:	HERAEUS AMERSIL INC

HERAEUS AMERSIL (Continued) **S102749681**

Customer Legal Name: Heraeus Tenevo Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 7715 Riverside Drive, Austin, TX

Regulated Entity Number: RN100611342
Name: HERAEUS AMERSIL
Address: 7715 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1644
Status: ACTIVE
Status Date: ##########
Customer Number: CN600320659
Customer Name: HERAEUS AMERSIL INC
Customer Legal Name: Heraeus Tenevo Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 7715 Riverside Drive, Austin, TX

Regulated Entity Number: RN100611342
Name: HERAEUS AMERSIL
Address: 7715 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1644
Status: ACTIVE
Status Date: ##########
Customer Number: CN604060699
Customer Name: HERAEUS QUARTZ AMERICA LLC
Customer Legal Name: Heraeus Quartz America LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 12/1/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 7715 Riverside Drive, Austin, TX

Regulated Entity Number: RN100611342
Name: HERAEUS AMERSIL
Address: 7715 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1644
Status: ACTIVE
Status Date: ##########
Customer Number: CN604060699
Customer Name: HERAEUS QUARTZ AMERICA LLC
Customer Legal Name: Heraeus Quartz America LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 12/1/2001

HERAEUS AMERSIL (Continued) **S102749681**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	7715 Riverside Drive, Austin, TX

HB1274 **HERAEUS AMERSIL INC** **RCRA NonGen / NLR** **1000836139**
WSW **7715 RIVERSIDE DRIVE** **FINDS** **TXD988071411**
< 1/8 **AUSTIN, TX 78744** **ECHO**
0.017 mi.
88 ft. **Site 3 of 3 in cluster HB**

Actual:
551 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Heraeus Amersil Inc
Handler Address:	RIVERSIDE DRIVE
Handler City,State,Zip:	AUSTIN, TX 78744
EPA ID:	TXD988071411
Contact Name:	ROGER LARSON
Contact Address:	GRAND AVENUE PARKWAY
Contact City,State,Zip:	AUSTIN, TX 78728
Contact Telephone:	512-251-5530
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GRAND AVENUE PARKWAY
Mailing City,State,Zip:	AUSTIN, TX 78728
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

HERAEUS AMERSIL INC (Continued) **1000836139**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	0000000000
Owner/Operator City,State,Zip:	0000000000, TX 00000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920507
Handler Name: HEREAUS AMERSIL INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

HERAEUS AMERSIL INC (Continued) **1000836139**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: HERAEUS AMERSIL INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005150424

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836139
Registry ID:	110005150424
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005150424
Name:	HERAEUS AMERSIL INC
Address:	7715 RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX 78744

DA1275 **KORNFUEHRER TEXACO SERVICE** **EDR Hist Auto** **1013766128**
WNW **701 6TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
89 ft. **Site 11 of 25 in cluster DA**

Actual:
474 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	KORNFUEHRER TEXACO SERVICE	GASOLINE STATIONS
1980	KORNFUEHRER TEXACO SERVICE STAT	GASOLINE STATIONS
1984	COTHRONS TEXACO SERVICE STATION	GASOLINE STATIONS

DA1276 **KORNFUEHRER TEXACO SERVICE STATION** **EDR Hist Auto** **1013760088**
WNW **701 6TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.017 mi.
89 ft. **Site 12 of 25 in cluster DA**

Actual:
474 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1975	KORNFUEHRER TEXACO SERVICE STAT	GASOLINE STATIONS
1990	COTHRONS TEXACO SERVICE STATION	GASOLINE STATIONS

DA1277 **AUSTIN GOODYEAR CO** **EDR Hist Auto** **1013765296**
WNW **701 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
89 ft. **Site 13 of 25 in cluster DA**

Actual:
474 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	AUSTIN GOODYEAR CO	GASOLINE AND OIL SERVICE STATIONS
1947	KILLIONS J E TEXACO SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	KORNFUEHRER SER	GASOLINE STATIONS
1962	KORNFUEHRER SERV STA	GASOLINE STATIONS

IS1278 **RESTORE RUNDBURG** **TX BROWNFIELDS** **S116385815**
ESE **SEC OF LAMAR AND BRAKER** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.017 mi.
90 ft. **Site 1 of 3 in cluster IS**

Actual:
776 ft.

Focus Map:
3

BROWNFIELDS:

Name:	RESTORE RUNDBURG
Address:	SEC OF LAMAR AND BRAKER
City,State,Zip:	AUSTIN, TX 78753
BF Site Assessment Received:	03/03/2014
PCA number:	99690
BF Grant Number:	G158
Facility Type:	Commercial/Residential
Lead Type:	City
Project manager:	PALLEN
Phase:	COMPLETED
Lat/Long:	30.381574 / -97.686206999999996

RESTORE RUNDBURG (Continued) **S116385815**

Lat/Long (deg):	30.381574 / -97.686206999999996
Acres:	5.74
TCEQ Region:	11
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Austin (Austin Resource Recovery
Applicant Title:	Brownfields Program Manager
Applicant Address:	PO Box 1088
Applicant City,St,Zip:	Austin, TX 78767
Applicant Phone:	512-974-6085
Applicant Fax:	Not reported
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported
Status Date:	10/14/2014

CB1279 **BROWN JACK CLEANERS CLNS** **EDR Hist Cleaner** **1013784019**
West **2026 GUADALUPE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.017 mi.
90 ft. **Site 9 of 11 in cluster CB**

Actual:
563 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1990	BROWN JACK CLEANERS CLNS	CLEANERS AND DYERS

IT1280 **PETRIFIED SERV STA** **EDR Hist Auto** **1013764170**
ESE **4505 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
90 ft. **Site 1 of 2 in cluster IT**

Actual:
632 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	PETRIFIED SERV STA	GASOLINE AND OIL SERVICE STATIONS

FL1281 **BROWN JACK CLEANERS INC** **EDR Hist Cleaner** **1019944313**
WSW **1901 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.017 mi.
91 ft. **Site 6 of 8 in cluster FL**

Actual:
472 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1992	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1993	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1994	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1995	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1996	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1997	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1998	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1999	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2000	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2001	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2002	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2003	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

FL1282 **JACK BROWN CLEANERS 15** **TX DRYCLEANERS** **S106454346**
WSW **1901 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.017 mi.
91 ft. **Site 7 of 8 in cluster FL**

Actual:
472 ft.
DRYCLEANERS:

Focus Map:
14

Name:	RICKS CLEANERS
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104416490
Region:	11
CN Number:	CN601536972
DCR Number:	Not reported
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	Not reported
Site Name:	RICKS CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	RICKS CLEANERS
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104416490
Region:	11
CN Number:	CN601536972
DCR Number:	Not reported
AR Number:	24000713

JACK BROWN CLEANERS 15 (Continued) **S106454346**

Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	Not reported
Site Name:	RICKS CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	RICKS CLEANERS
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104416490
Region:	11
CN Number:	CN601536972
DCR Number:	Not reported
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	Not reported
Site Name:	RICKS CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	RICKS CLEANERS
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104416490
Region:	11
CN Number:	CN601536972
DCR Number:	Not reported
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	Not reported
Site Name:	RICKS CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported

JACK BROWN CLEANERS 15 (Continued) **S106454346**

Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	RICKS CLEANERS
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104416490
Region:	11
CN Number:	CN601536972
DCR Number:	Not reported
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	Not reported
Site Name:	RICKS CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	JACK BROWN CLEANERS 15
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN103982518
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	Not reported
Phone Number:	Not reported
Site Name:	JACK BROWN CLEANERS 15
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	JACK BROWN CLEANERS 15
Address:	1901 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN103982518
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported

JACK BROWN CLEANERS 15 (Continued) **S106454346**

AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	Not reported
Phone Number:	Not reported
Site Name:	JACK BROWN CLEANERS 15
Site Type:	DROP STATION REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

IJ1283 **GAS A TERIA INC** **EDR Hist Auto** **1013754490**
WNW **3200 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
91 ft. **Site 3 of 4 in cluster IJ**

Actual:
594 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	GAS A TERIA INC	GASOLINE STATIONS
1965	HANCOCK SERVICE STATION	GASOLINE STATIONS

IH1284 **VARSITY PRESSING SHOP R** **EDR Hist Cleaner** **1013787676**
East **2105 SPEEDWAY** **N/A**
< 1/8 **HYDE PARK, TX**
0.017 mi.
91 ft. **Site 4 of 5 in cluster IH**

Actual:
539 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	VARSITY PRESSING SHOP R	CLOTHES CLEANERS AND PRESSERS

HA1285 **QUIKTRIP 4125** **TX UST** **U004363180**
WNW **4402 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.017 mi.
91 ft. **Site 3 of 4 in cluster HA**

Actual:
649 ft.

UST:

Focus Map:
17

Name:	QUIKTRIP 4125
Address:	4402 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787451945
AI Number:	92268
Facility Type:	RETAIL
Facility Begin Date:	11/23/2021
Facility Status:	ACTIVE
Additional ID:	916473552021313
Facility Exempt Status:	N

QUIKTRIP 4125 (Continued) **U004363180**

Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	5
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	REX POPE,
Contact Organization Name:	QUIKTRIP 4125
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5126715017
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/05/2022
Signature Name/Title On Earliest Reg Form:	VICTORIA HENSLEY,ECS
Application Received Date On Earliest Reg Form:	12/08/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	290523072020162
Additional ID:	916473552021313
Ai Number:	92268
Operator CN:	CN605786011
Operator Name:	QT SOUTH LLC
Operator Effective Begin Date:	11/25/2022
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	CODY THIEMS/ENV COMP MGR
Contact Organization Name:	QT SOUTH LLC
Contact Mailing Address (Delivery):	4705 S 129TH EAST AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TULSA OK 74134-7005
Contact Phone Country Code:	1
Contact Phone Area Code:	918
Contact Phone Number:	6157304
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	qtenviro@quiktrip.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605786011
Owner Last Name:	QT SOUTH LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	4705 S 129TH EAST AVE

QUIKTRIP 4125 (Continued) **U004363180**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	TULSA
Contact Mailing State:	OK
Contact Mailing Zip:	74134
Contact Mailing Zip5:	7005
Contact Phone Number/Ext:	1 918 6157304/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	qtenviro@quiktrip.com
Contact Address Deliverable:	Not reported
Princ ID:	290523072020162
Additional ID:	916473552021313
AI Number:	92268
Owner Effective Begin Date:	11/25/2022
State Tax ID:	32073167036
Contact Role:	OWNOPRCON
Contact Name/Title:	CODY THIEMS/ENV COMP MGR
Contact Organization Name:	QT SOUTH LLC

Self Certification:

Self Cert ID:	137355
Cert ID:	380617
AI Number:	92268
Self Certification Date:	12/05/2022
Signature Name/Title:	VICTORIA HENSLEY ECS
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	137355
Cert ID:	380618
AI Number:	92268
Self Certification Date:	12/05/2022
Signature Name/Title:	VICTORIA HENSLEY ECS
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

QUIKTRIP 4125 (Continued) **U004363180**

Self Cert ID:	137355
Cert ID:	373348
AI Number:	92268
Self Certification Date:	07/15/2022
Signature Name/Title:	VICTORIA HENSLEY ECS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	11/23/2021
Tank Registration Date:	07/15/2022
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	226354
Facility ID:	137355
Ai Number:	92268
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	11/23/2021
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

QUIKTRIP 4125 (Continued) **U004363180**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/30/2022

Compartment Records:

Tank ID:	4
Tank Capacity:	15000
UST Comprt ID:	198366
UST ID:	226354
AI Number:	92268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N

QUIKTRIP 4125 (Continued) **U004363180**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/31/2021

Install Date:	11/23/2021
Tank Registration Date:	07/15/2022
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	226353
Facility ID:	137355
Ai Number:	92268
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	11/23/2021
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

QUIKTRIP 4125 (Continued) **U004363180**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/30/2022

Compartment Records:

Tank ID:	3
Tank Capacity:	15000
UST Comprt ID:	198365
UST ID:	226353
AI Number:	92268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

QUIKTRIP 4125 (Continued) **U004363180**

Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/31/2021
Install Date:	11/23/2021
Tank Registration Date:	07/15/2022
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	226355
Facility ID:	137355
Ai Number:	92268
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	11/23/2021
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y

QUIKTRIP 4125 (Continued) **U004363180**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/30/2022

Compartment Records:

Tank ID:	5
Tank Capacity:	15000
UST Comprt ID:	198367
UST ID:	226355
AI Number:	92268
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/31/2021

Install Date:	11/23/2021
Tank Registration Date:	07/15/2022
Number of Compartments:	1
Tank Capacity:	15000

QUIKTRIP 4125 (Continued) **U004363180**

Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	226352
Facility ID:	137355
Ai Number:	92268
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	11/23/2021
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y

QUIKTRIP 4125 (Continued) **U004363180**

Installation Signature Date:	06/30/2022
Compartment Records:	
Tank ID:	2
Tank Capacity:	15000
UST Comprt ID:	198364
UST ID:	226352
AI Number:	92268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/31/2021
Install Date:	11/23/2021
Tank Registration Date:	07/15/2022
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	226351
Facility ID:	137355
Ai Number:	92268
Tank Id:	1
Tank Status (Current):	IN USE

QUIKTRIP 4125 (Continued) **U004363180**

Tank Status Date:	11/23/2021
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/30/2022

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	198363
UST ID:	226351
AI Number:	92268
Compartment ID:	A

QUIKTRIP 4125 (Continued) **U004363180**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/31/2021

Construction Notification:

NOC ID:	39104
Facility ID:	137355
AI Number:	92268
Application Received Date:	11/03/2021
Scheduled Construction Date:	12/02/2021
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	11/03/2021

QUIKTRIP 4125 (Continued) **U004363180**

Signature Date On Form:	11/02/2021
Signature Name On Form:	JOEY LANGLEY
Signature Company On Form:	Not reported
Signature Title On Form:	ADMIN
Signature Role:	Not reported
Owner Name At Time Of Construction:	QUIKTRIP CORPORATION
Owner CN At Time Of Construction:	CN600241673
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	NEW STORE INSTALLING USTS

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	93161
UST ID:	Not reported
NOC ID:	39104
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD
Representative Name:	EPIFANIO MARTINEZ
Mailing Address (Delivery):	PO BOX 2393
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BOERNE
Mailing State:	TX
Mailing Zip:	78006
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	8162225
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	830
Fax Number:	2495551
Email Address:	Not reported

Cont/Cons/Installer ID:	96217
UST ID:	226352
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

QUIKTRIP 4125 (Continued) **U004363180**

Email Address:	Not reported
Cont/Cons/Installer ID:	96216
UST ID:	226351
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96219
UST ID:	226353
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96222
UST ID:	226354
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD

QUIKTRIP 4125 (Continued) **U004363180**

Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96213
UST ID:	226355
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	MSCS LTD
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96220
UST ID:	226353
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO P MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported

QUIKTRIP 4125 (Continued) **U004363180**

Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	93162
UST ID:	Not reported
NOC ID:	39104
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96215
UST ID:	226351
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO P MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96214

QUIKTRIP 4125 (Continued) **U004363180**

UST ID:	226355
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO P MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	96218
UST ID:	226352
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO P MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	96221
UST ID:	226354
NOC ID:	Not reported
AI Number:	92268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001454
Company Name:	Not reported
Representative Name:	EPIFANIO P MARTINEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

QUIKTRIP 4125 (Continued) **U004363180**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	QT SOUTH LLC
Contact Mailing Address (Delivery):	4705 S 129TH EAST AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TULSA, OK 74134 7005
Phone Number/Ext:	918 6157304/0
Contact Fax Number/Ext:	/
Contact Email Address:	QTENVIRO@QUIKTRIP.COM
Contact Address Deliverable:	Y
Facility ID:	137355
Additional ID:	916473552021313
Princ ID:	290523072020162
AI Number:	92268
Facility Name:	QUIKTRIP 4125
AR Number:	81781
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	CODY THIEMS/

CV1286 **HOME STEAM** **EDR Hist Cleaner** **1013777105**
WNW **118 10TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
91 ft. **Site 6 of 14 in cluster CV**

Actual:
513 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	118 20 HOME STEAM LAUN BRAZOS	LAUNDRIES
1940	HOME STEAM	LAUNDRIES
1947	HOME STEAM LAUNDRY	STEAM LAUNDRIES
1947	HOME STEAM LAUNDRY	LAUNDRIES
1947	HOME STEAM LAUNDRY	WET WASH LAUNDRIES

EH1287 **CHRISTIES CONOCO SERVICE** **EDR Hist Auto** **1013756537**
SE **400 BARTON SPRINGS RD** **N/A**
< 1/8 **AUSTIN, TX**
0.017 mi.
92 ft. **Site 3 of 9 in cluster EH**

Actual:
455 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	CHRISTIES CONOCO SERVICE	GASOLINE STATIONS
1969	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1970	CHRISTIES CONOCO SERVICE STATIO	GASOLINE STATIONS
1970	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1971	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1972	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1973	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1974	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1975	FAS GAS GAS ST	GASOLINE STATIONS
1975	CHRISTIS CONOCO SERVICE STN	Gasoline Service Stations
1980	FAS GAS NO	GASOLINE STATIONS

EH1288 **CHTRISTIES CONOCO** **EDR Hist Auto** **1013759642**
SE **400 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.017 mi.
92 ft. **Site 4 of 9 in cluster EH**

Actual:
455 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	CHTRISTIES CONOCO	GASOLINE STATIONS

IH1289 **UNIVERSITY CLEANING & PRESSING CO R** **EDR Hist Cleaner** **1013787633**
East **2109 SPEEDWAY** **N/A**
< 1/8 **HYDE PARK, TX**
0.017 mi.
92 ft. **Site 5 of 5 in cluster IH**

Actual:
539 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	UNIVERSITY CLEANING & PRESSING	CLOTHES CLEANERS AND PRESSERS

CB1290 **ST. AUSTIN CATHOLIC PARISH RECTORY** **TX HIST UST** **S128134963**
West **2010 GUADALUPE ST.** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.018 mi.
93 ft. **Site 10 of 11 in cluster CB**

Actual:
561 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	ST AUSTIN'S CATHOLIC CHURCH
Address:	2010 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0212
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

ASBESTOS:

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/21/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/21/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/21/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	14
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/21/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/03/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/15/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/30/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/17/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/15/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/08/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/10/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/30/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/30/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/08/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/23/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/30/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/30/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Analytical Method:	PLM
Start Date:	12/15/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III - Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/17/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Work Type Flag:	A
Certification Statement Date:	12/09/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/15/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III - Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2021
Date Routed by Supervisor:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/09/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/20/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III - Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/29/2021
Notification Number:	2021007304
ASB Priority:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/15/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/22/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III - Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/14/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/15/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/14/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/22/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	02/28/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/22/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/14/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/29/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	02/28/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/29/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/10/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	02/28/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/10/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Inspector Name:	Not reported
Date Report Received:	01/24/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/24/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Complaint Date:	02/28/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/24/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/24/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/07/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	02/28/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/07/2022

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/09/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	03/31/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/09/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/28/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	03/31/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	02/28/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/07/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/07/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-D
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/14/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-D
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/14/2022
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	11/24/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/04/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/29/2022
Reason for Inspection:	Jesse Robles III-Delegated Agent for Owner
Violation:	Not reported
Complaint Date:	12/10/2021
Notification Number:	2021007304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2021

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/04/2021
Certification Statement Phone:	915-858-0376
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/30/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. AUSTIN CATHOLIC PARISH RECTORY
Address:	2010 GUADALUPE ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/03/29
Notification Number:	Not reported

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/29/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021007304
File Number:	66101
License Status Description:	Paid
Expiration Date:	04/15/2022
Original Date:	11/04/2021
Rank Effective Date:	11/04/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	31951
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental

ST. AUSTIN CATHOLIC PARISH RECTORY (Continued) **S128134963**

Inspection Secondary Class Code: AB
Inspection Secondary Class Code Description: Asbestos Both
Results: Pass
Inspection Number Grade: Not reported

IK1291 **TROY BRANCH AUSTIN** **EDR Hist Cleaner** **1013781260**
ESE **806 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
93 ft. **Site 3 of 5 in cluster IK**

Actual:
508 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1896	SCHMITT JOHN TAILOR DYER SCOURE	DYERS AND SCOURERS
1896	BOSLEY W CLEMENT MCHT TAILOR DY	DYERS AND SCOURERS
1901	BOSCHE PHILIP PROPR BOSCHES TR	LAUNDRIES
1901	HONG WAH CHINESE LAUNDRY	LAUNDRIES
1906	BOSCHES TROY LAUNDRY	LAUNDRIES
1916	BOSCHES TROY LAUNDRY	DRY CLEANING
1916	BOSCHES TROY LAUNDRY	LAUNDRIES
1922	TROY BRANCH AUSTIN	LAUNDRIES
1922	BANNER CLEANING	CLOTHES CLEANERS AND PRESSERS

CJ1292 **AUSTIN MOTORCYCLE CO INC** **EDR Hist Auto** **1013759189**
ESE **1611 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.018 mi.
93 ft. **Site 7 of 8 in cluster CJ**

Actual:
552 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	AUSTIN MOTORCYCLE CO	MOTORCYCLE DEALERS AND REPAIRERS
1975	AUSTIN MOTORCYCLE CO INC	MOTORCYCLE DEALERS AND REPAIRERS
1980	AUSTIN MOTORCYCLE CO INC	MOTORCYCLE DEALERS AND REPAIRERS
1984	AUSTIN MOTORCYCLE CO INC	MOTORCYCLE DEALERS AND REPAIRERS

CJ1293 **PETRICK FACILITY** **TX UST** **U001293463**
ESE **1611 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.018 mi.
93 ft. **Site 8 of 8 in cluster CJ**

Actual:
552 ft.
UST:

Focus Map:
11

Name:	PETRICK FACILITY
Address:	1611 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787011212
AI Number:	50071
Facility Type:	UNKNOWN
Facility Begin Date:	01/31/1990
Facility Status:	INACTIVE
Additional ID:	35705402002205
Facility Exempt Status:	N
Records Off-Site:	No

PETRICK FACILITY (Continued) **U001293463**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	STEVE HOLLAND,MANAGER
Contact Organization Name:	PETRICK FACILITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124795400
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/24/1990
Signature Name/Title On Earliest Reg Form:	STEVE HOLLAND,MANAGER
Application Received Date On Earliest Reg Form:	01/26/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601417447
Owner Last Name:	BONNET RESOURCES CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	701701862002205
Additional ID:	35705402002205
AI Number:	50071
Owner Effective Begin Date:	01/31/1990
State Tax ID:	17522957657
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1960
Tank Registration Date:	01/26/1990
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N

PETRICK FACILITY (Continued) **U001293463**

Pipe Type:	Not reported
UST ID:	129803
Facility ID:	83531
Ai Number:	50071
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/20/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/21/1989

PETRICK FACILITY (Continued) **U001293463**

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	126573
UST ID:	129803
AI Number:	50071
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	19352
Cert ID:	116096
UST Comprt ID:	333245
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	381322
UST Comprt ID:	1112553
UST ID:	113869

PETRICK FACILITY (Continued) **U001293463**

AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116095
UST Comprt ID:	333246
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	266412
UST Comprt ID:	767552
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116094
UST Comprt ID:	333247
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	292803
UST Comprt ID:	845732
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116093
UST Comprt ID:	333248
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	328669
UST Comprt ID:	952873
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116092
UST Comprt ID:	333249
UST ID:	113869
AI Number:	50071

PETRICK FACILITY (Continued) **U001293463**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	233843
UST Comprt ID:	671296
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	275742
UST Comprt ID:	794884
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116090
UST Comprt ID:	333250
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116098
UST Comprt ID:	333243
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116089
UST Comprt ID:	333251
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	345835
UST Comprt ID:	1004761
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116088
UST Comprt ID:	333254
UST ID:	113869
AI Number:	50071
Tank ID:	2

PETRICK FACILITY (Continued) **U001293463**

Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116097
UST Comprt ID:	333244
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116087
UST Comprt ID:	333253
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	248811
UST Comprt ID:	715223
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	116086
UST Comprt ID:	333252
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	362248
UST Comprt ID:	1054228
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A
Self Cert ID:	19352
Cert ID:	310214
UST Comprt ID:	897689
UST ID:	113869
AI Number:	50071
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	BONNET RESOURCES CORPORATION
Contact Mailing Address (Delivery):	PO BOX 2629
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77252 2629
Phone Number/Ext:	/

PETRICK FACILITY (Continued) **U001293463**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83531
Additional ID:	35705402002205
Princ ID:	701701862002205
AI Number:	50071
Facility Name:	PETRICK FACILITY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	V CARL TRAGESSER/

HIST UST AUSTIN:

Name:	PETRICK FACILITY
Address:	1611 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0258
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DI1294 **AMERICAN CLEANERS** **PFAS ECHO** **1027324510**
ESE **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
93 ft. **Site 2 of 9 in cluster DI**

Actual:
489 ft.

Focus Map:
11

PFAS ECHO:

Name:	AMERICAN CLEANERS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.26802
Longitude:	-97.74633
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Printing
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110005098036
Facility Percent Minority:	44.131
Facility Derived Tribes:	-
Facility Population:	5538.27
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	21
Facility Derived CB2010:	484530011001085
Facility Major Flag:	-
Facility Active Flag:	-

AMERICAN CLEANERS (Continued) **1027324510**

Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TXD981904972
RCRA Permit Types:	Other
RCRA NAICS:	323120
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.74633,%22y%22:30.26802,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

AR1295 **PEOPLES SINCLAIR** **EDR Hist Auto** **1013764106**
WNW **4926 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
94 ft. **Site 4 of 5 in cluster AR**

Actual:
664 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1962	PEOPLES SINCLAIR	GASOLINE STATIONS
1965	NORTH LAMAR SINCLAIR	GASOLINE STATIONS

AR1296 **M & M SINCLAIR** **EDR Hist Auto** **1013776193**
WNW **4926 LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
94 ft. **Site 5 of 5 in cluster AR**

Actual:
664 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1953	M & M SINCLAIR	GASOLINE STATIONS
1958	M&M SINCLAIR STA	GASOLINE STATIONS

DE1297 **TX HIST UST** **S128729207**
WNW **405 W 6TH** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
94 ft. **Site 11 of 13 in cluster DE**

Actual:
492 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	405 W 6TH
City,State,Zip:	AUSTIN, TX
Id UST:	H0182
HID UST:	Not reported
Inspection:	10/27/1927
Due:	Not reported

EA1298 **DEAN JOHNSTON** **TX UST** **U001288958**
SSW **207 SAN JACINTO BLVD** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.018 mi.
94 ft. **Site 4 of 4 in cluster EA**

Actual:
475 ft.

Focus Map:
11

UST:

Name:	DEAN JOHNSTON
Address:	207 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 787014002
AI Number:	59396
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	08/19/1991
Facility Status:	INACTIVE
Additional ID:	893242782002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DEAN JOHNSTON,PRES
Contact Organization Name:	DEAN JOHNSTON
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124773747

DEAN JOHNSTON (Continued) **U001288958**

Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/08/1991
Signature Name/Title On Earliest Reg Form:	DEAN JOHNSTON,PRES
Application Received Date On Earliest Reg Form:	08/14/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778393
Owner Last Name:	DEAN JOHNSTON INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	268533862002053
Additional ID:	893242782002139
AI Number:	59396
Owner Effective Begin Date:	08/19/1991
State Tax ID:	17413327358
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/14/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	140407
Facility ID:	89819
Ai Number:	59396
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

DEAN JOHNSTON (Continued) **U001288958**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/06/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	145631
UST ID:	140407
AI Number:	59396
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

DEAN JOHNSTON (Continued) **U001288958**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	23136
Cert ID:	237060
UST Comprt ID:	680620
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	220310
UST Comprt ID:	631553
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125889
UST Comprt ID:	366191
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125890
UST Comprt ID:	366190

DEAN JOHNSTON (Continued) **U001288958**

UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125891
UST Comprt ID:	366189
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	271382
UST Comprt ID:	781990
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	287217
UST Comprt ID:	828993
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	304471
UST Comprt ID:	880679
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	320881
UST Comprt ID:	929517
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	337101
UST Comprt ID:	978114
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	354124
UST Comprt ID:	1029600
UST ID:	121471

DEAN JOHNSTON (Continued) **U001288958**

AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	357773
UST Comprt ID:	1040681
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	376972
UST Comprt ID:	1098873
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125884
UST Comprt ID:	366194
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125885
UST Comprt ID:	366195
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125886
UST Comprt ID:	366196
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125887
UST Comprt ID:	366193
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125888
UST Comprt ID:	366192
UST ID:	121471
AI Number:	59396

DEAN JOHNSTON (Continued) **U001288958**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125892
UST Comprt ID:	366188
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125893
UST Comprt ID:	366187
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	125894
UST Comprt ID:	366186
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	126144
UST Comprt ID:	366185
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	126145
UST Comprt ID:	366184
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A
Self Cert ID:	23136
Cert ID:	253797
UST Comprt ID:	729819
UST ID:	121471
AI Number:	59396
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	JOHNSTON DEAN
Contact Mailing Address (Delivery):	PO BOX 2153
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78768 2153

DEAN JOHNSTON (Continued) **U001288958**

Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89819
Additional ID:	893242782002139
Princ ID:	268533862002053
AI Number:	59396
Facility Name:	DEAN JOHNSTON
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DEAN JOHNSTON/

IU1299 **THURMAN WAREHOUSE** **TX LPST** **U001247261**
WNW **4714 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX HIST UST**
0.018 mi.
94 ft. **Site 1 of 6 in cluster IU**

Actual:
639 ft.

Focus Map:
17

LPST:

Name:	THURMAN WAREHOUSE
Address:	4714 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0011319
LPST Id:	099861
Facility Location:	S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/13/1991
Entered Date:	09/18/1991
Reported Date:	08/13/1991
Closure Date:	01/27/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	BARBARA SMITH
Responsible Party Address:	4500 BISSONNET STE 200
Responsible Party City,St,Zip:	BELLAIRE, TX 77401
Responsible Party Telephone:	/-
Reported Date:	08/13/1991
Case Start Date:	01/27/1992
Reference Number:	RN101488369
Project Manager:	HWELCH

UST:

Name:	THURMAN WAREHOUSE
Address:	4714 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787452303
AI Number:	11319
Facility Type:	RETAIL

THURMAN WAREHOUSE (Continued) **U001247261**

Facility Begin Date:	08/31/1989
Facility Status:	INACTIVE
Additional ID:	998500812002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	THURMAN WAREHOUSE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124473303
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	S D HOWLE,
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777379
Owner Last Name:	DJX INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	988500802002053
Additional ID:	998500812002053
AI Number:	11319
Owner Effective Begin Date:	07/14/1998
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1983

THURMAN WAREHOUSE (Continued) **U001247261**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29736
Facility ID:	89964
Ai Number:	11319
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

THURMAN WAREHOUSE (Continued) **U001247261**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	146578
UST ID:	29736
AI Number:	11319
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29735
Facility ID:	89964

THURMAN WAREHOUSE (Continued) **U001247261**

Ai Number:	11319
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	146577

THURMAN WAREHOUSE (Continued) **U001247261**

UST ID:	29735
AI Number:	11319
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DJX INC
Contact Mailing Address (Delivery):	4714 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 2303
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89964
Additional ID:	998500812002053
Princ ID:	988500802002053
AI Number:	11319
Facility Name:	THURMAN WAREHOUSE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported

THURMAN WAREHOUSE (Continued) **U001247261**

Contact Name/Title: /

HIST UST AUSTIN:

Name:	PDQ DRIVE IN
Address:	4714 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0267
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IU1300 **PDQ FOOD MART** **EDR Hist Auto** **1022047712**
WNW **4714 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.018 mi.
94 ft. **Site 2 of 6 in cluster IU**

Actual:
639 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1985	PDQ FOOD MART	Grocery Stores
1986	PDQ FOOD MART	Grocery Stores
1987	PDQ FOOD MART	Grocery Stores
1988	PDQ FOOD MART	Grocery Stores

FQ1301 **STONE BOB** **EDR Hist Auto** **1020625952**
West **2300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.018 mi.
94 ft. **Site 13 of 16 in cluster FQ**

Actual:
596 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1969	STONE BOBBY LUNN	Gasoline Service Stations
1969	STONE BOBBY LUNN	Gasoline Service Stations
1970	STONE BOBBY LYNN	Gasoline Service Stations
1971	STONE BOBBY LYNN	Gasoline Service Stations
1972	STONE BOBBY LYNN	Gasoline Service Stations
1973	STONE BOBBY LYNN	Gasoline Service Stations
1974	STONE BOBBY LYNN	Gasoline Service Stations
1975	STONE BOBBY LYNN	Gasoline Service Stations
1988	BOB STONES TEXACO	Gasoline Service Stations
1989	BOB STONES TEXACO	Gasoline Service Stations, NEC
1990	BOB STONES TEXACO	Gasoline Service Stations, NEC
1991	STONE BOB	Gasoline Service Stations, NEC
1992	STONE BOB	Gasoline Service Stations, NEC
1993	STONE BOB	Gasoline Service Stations, NEC
1994	STONE BOB	Gasoline Service Stations, NEC
1995	STONE BOB	Gasoline Service Stations, NEC
1996	STONE BOB	Gasoline Service Stations, NEC
1997	STONE BOB	Gasoline Service Stations, NEC
1998	STONE BOB	Gasoline Service Stations, NEC
1999	STONE BOB	Gasoline Service Stations, NEC

STONE BOB (Continued) **1020625952**

2000	STONE BOB	Gasoline Service Stations, NEC
2001	STONES BOB AUTOMOTIVE	Gasoline Service Stations, NEC
2008	SOCO AUTOMOTIVE	General Automotive Repair Shops
2009	SOCO AUTOMOTIVE	General Automotive Repair Shops
2010	SOCO AUTOMOTIVE	General Automotive Repair Shops

FQ1302 **STONES TEXACO** **TX LPST** **U003040346**
West **2300 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.018 mi.
94 ft. **Site 14 of 16 in cluster FQ**

Actual:
596 ft.

Focus Map:
14

LPST:

Name:	STONES TEXACO
Address:	2300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0022264
LPST Id:	110045
Facility Location:	2300 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	11/06/1995
Entered Date:	12/04/1995
Reported Date:	11/08/1995
Closure Date:	01/14/2008
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1
Coordinators RPR:	MDS
Responsible Party Name:	Not reported
Responsible Party Contact:	BOB L STONE
Responsible Party Address:	4805 BROKEN BOW PASS
Responsible Party City,St,Zip:	AUSTIN, TX 78745 2833
Responsible Party Telephone:	512/444-1654
Reported Date:	11/08/1995
Case Start Date:	01/14/2008
Reference Number:	RN101496990
Project Manager:	MSEFCIK

UST:

Name:	STONES TEXACO
Address:	2300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787045208
AI Number:	22264
Facility Type:	RETAIL
Facility Begin Date:	09/18/1986
Facility Status:	INACTIVE
Additional ID:	886720552002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported

STONES TEXACO (Continued) **U003040346**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	BOB STONE,OWNER
Contact Organization Name:	STONES TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124424434
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/24/1986
Signature Name/Title On Earliest Reg Form:	BOB L STONE,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784466
Owner Last Name:	STONE BOB L
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	877720542002053
Additional ID:	886720552002053
AI Number:	22264
Owner Effective Begin Date:	09/18/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57036
Facility ID:	58888
Ai Number:	22264

STONES TEXACO (Continued) **U003040346**

Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	64692
UST ID:	57036

STONES TEXACO (Continued) **U003040346**

AI Number:	22264
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57039
Facility ID:	58888
Ai Number:	22264
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

STONES TEXACO (Continued) **U003040346**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	64695
UST ID:	57039
AI Number:	22264
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

STONES TEXACO (Continued) **U003040346**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57038
Facility ID:	58888
Ai Number:	22264
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

STONES TEXACO (Continued) **U003040346**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	64694
UST ID:	57038
AI Number:	22264
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

STONES TEXACO (Continued) **U003040346**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57037
Facility ID:	58888
Ai Number:	22264
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

STONES TEXACO (Continued) **U003040346**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	64693
UST ID:	57037
AI Number:	22264
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

STONES TEXACO (Continued) **U003040346**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	STONE BOB L
Contact Mailing Address (Delivery):	2300 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5208
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	58888
Additional ID:	886720552002053
Princ ID:	877720542002053
AI Number:	22264
Facility Name:	STONES TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BOB STONE/

FQ1303 **STONE'S TEXACO** **TX HIST UST** **S128729080**
West **2300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
94 ft. **Site 15 of 16 in cluster FQ**

Actual:
596 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	STONE'S TEXACO
Address:	2300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0592
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FQ1304 **MRS. J. TADLOCK/ HUMBLE OIL** **TX HIST UST** **S128729304**
West **2300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
94 ft. **Site 16 of 16 in cluster FQ**

Actual:
596 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	MRS. J. TADLOCK/ HUMBLE OIL
Address:	2300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0510
HID UST:	510
Inspection:	03/04/2009
Due:	03/04/2012

DD1305 **PIT STOP INC THE AUTO REPR & SALES** **EDR Hist Auto** **1013761273**
WNW **700 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.018 mi.
95 ft. **Site 3 of 6 in cluster DD**

Actual:
467 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1970	PIT STOP INC THE AUTO REPR & SA	AUTOMOBILE REPAIRING

1306 **TEXAS PUBLIC SERVICE** **TX HIST UST** **S128729563**
NNE **150 E. 6TH ST.** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
95 ft.

Actual:
490 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TEXAS PUBLIC SERVICE
Address:	150 E. 6TH ST.
City,State,Zip:	AUSTIN, TX
Id UST:	N0176
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AG1307 **COIN 00 MATIC LAUNDRY** **EDR Hist Cleaner** **1013780158**
ESE **6607 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
95 ft. **Site 12 of 14 in cluster AG**

Actual:
713 ft.

Focus Map:
6

EDR Hist Cleaner

Year:	Name:	Type:
1965	COIN 00 MATIC LAUNDRY	LAUNDRIES-SELF SERVE
2008	SPRUCE UPHOLSTERY	Carpet And Upholstery Cleaning
2009	SPRUCE UPHOLSTERY	Carpet And Upholstery Cleaning
2010	SPRUCE UPHOLSTERY	Carpet And Upholstery Cleaning

AG1308 ESE < 1/8 0.018 mi. 95 ft. — **STONE COMPANY, 6607 N LAMAR BLVD, AUSTIN, TX** — **TX HIST UST** — **S111678814, N/A**

Site 13 of 14 in cluster AG

Actual: 713 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	STONE COMPANY
Address:	6607 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0544
HID UST:	544
Inspection:	Not reported
Due:	06/01/2012

EB1309 ESE < 1/8 0.018 mi. 95 ft. — **N W COR GOAD MOTOR, 104 GUADALUPE, AUSTIN, TX** — **EDR Hist Auto** — **1013770408, N/A**

Site 2 of 2 in cluster EB

Actual: 462 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	N W COR GOAD MOTOR	AUTOMOBILE REPAIRING

CB1310 West < 1/8 0.018 mi. 95 ft. — **BYRD ROY CLEANERS, 2002 GUADALUPE ST, AUSTIN, TX** — **EDR Hist Cleaner** — **1013781371, N/A**

Site 11 of 11 in cluster CB

Actual: 560 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1958	BYRD ROY CLNS	CLEANERS AND DYERS
1962	BYRD ROY CLN	CLEANERS AND DYERS
1965	BYRD ROY CLEANERS	CLEANERS AND DYERS

FL1311 WSW < 1/8 0.018 mi. 96 ft. — **FAMILY DOLLAR #1700, 1917 E. RIVERSIDE DR., AUSTIN, TX 78741** — **RCRA-VSQG** — **1017780670, TXR000082290**

Site 8 of 8 in cluster FL

Actual: 482 ft.
Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20141229
Handler Name:	Family Dollar #1700
Handler Address:	E. RIVERSIDE DR.
Handler City,State,Zip:	AUSTIN, TX 78741-1332
EPA ID:	TXR000082290
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported

FAMILY DOLLAR #1700 (Continued) **1017780670**

Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PRG MGR, ENVR COMPLIANCE
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1017
Mailing City,State,Zip:	CHARLOTTE, NC 28201
Owner Name:	Rshc, Llc
Owner Type:	Private
Operator Name:	Family Dollar Stores
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150112
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

FAMILY DOLLAR #1700 (Continued) **1017780670**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: FAMILY DOLLAR STORES	
Legal Status:	Private
Date Became Current:	19910313
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RSHC, LLC	
Legal Status:	Private
Date Became Current:	20110101
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 29837

FAMILY DOLLAR #1700 (Continued) **1017780670**

Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-441-6262
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20141229
Handler Name: FAMILY DOLLAR #1700
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

DF1312 **DRISKILL HOTEL** **EDR Hist Cleaner** **1013777521**
WNW **121 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.018 mi.
97 ft. **Site 7 of 25 in cluster DF**

Actual:
497 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	DRISKILL HOTEL LNDRY	LAUNDRIES
1940	DRISKILL HOTEL	LAUNDRIES
1947	DRISKILL HOTEL LNDRY	LAUNDRIES

1313 **SERVICE STATION** **EDR Hist Auto** **1020959898**
East **2500 SPEEDWAY** **N/A**
< 1/8 **AUSTIN, TX 78712**
0.018 mi.
97 ft.

Actual:
559 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2012	SERVICE STATION	Gasoline Service Stations

SERVICE STATION (Continued) **1020959898**

2013 SERVICE STATION Gasoline Service Stations

IV1314 **SPEEDWAY CLEANERS** **EDR Hist Cleaner** **1013787597**
East **2608 SPEEDWAY** **N/A**
< 1/8 **AUSTIN, TX**
0.019 mi.
98 ft. **Site 1 of 4 in cluster IV**

Actual:
558 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	SPEEDWAY CLEANERS	CLOTHES CLEANERS AND PRESSERS

IO1315 **RISING SUN JAPANESE AUTOMOTIVE** **RCRA NonGen / NLR** **1000257003**
WNW **4930 S CONGRESS AVE BLDG D** **FINDS** **TXD982548430**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.019 mi.
98 ft. **Site 2 of 4 in cluster IO**

Actual:
613 ft.
RCRA Listings:

Focus Map:
17

Date Form Received by Agency:	20010823
Handler Name:	Rising Sun Japanese Automotive
Handler Address:	S CONGRESS AVE BLDG D
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD982548430
Contact Name:	ALLAN WALKER
Contact Address:	S CONGRESS AVE BLDG D
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-443-4122
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS AVE BLDG D
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Rising Sun Japanese Automotive
Owner Type:	Private
Operator Name:	Rising Sun Japanese Automotive
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

RISING SUN JAPANESE AUTOMOTIVE (Continued) **1000257003**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends

RISING SUN JAPANESE AUTOMOTIVE (Continued) **1000257003**

Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ALLAN WALKER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RISING SUN JAPANESE AUTOMOTIVE	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	4930 S CONGRESS AVE BLDG D
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-443-4122
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RISING SUN JAPANESE AUTOMOTIVE	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	4930 S CONGRESS AVE BLDG D
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-443-4122
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19880222
Handler Name: RISING SUN INC	
Federal Waste Generator Description:	Small Quantity Generator

RISING SUN JAPANESE AUTOMOTIVE (Continued) **1000257003**

State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name:	RISING SUN JAPANESE AUTOMOTIVE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005106152

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000257003
Registry ID:	110005106152
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005106152
Name:	RISING SUN JAPANESE AUTOMOTIVE
Address:	4930 S CONGRESS AVE BLDG D
City,State,Zip:	AUSTIN, TX 78745

IO1316 **JET ENVIRONMENTAL SERVICES, INC.** **RCRA NonGen / NLR** **1019326700**
WNW **4930 S. CONGRESS AVE.** **TXR000083881**
< 1/8 **AUSTIN, TX 78745**
0.019 mi.
98 ft. **Site 3 of 4 in cluster IO**

Actual:
613 ft.

Focus Map:
17

RCRA Listings:

Date Form Received by Agency:	20210524
Handler Name:	Jet Environmental Services, Inc.
Handler Address:	S. CONGRESS AVE.
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXR000083881
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

JET ENVIRONMENTAL SERVICES, INC. (Continued) **1019326700**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210805
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JET ENVIRONMENTAL SERVICES, INC.
Legal Status:	Private
Date Became Current:	20151201
Date Ended Current:	Not reported
Owner/Operator Address:	4930 SOUTH CONGRESS AVENUE
Owner/Operator City,State,Zip:	AUSTIN 98745
Owner/Operator Telephone:	909-483-3300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	JET ENVIRONMENTAL SERVICES, INC.
Legal Status:	Private
Date Became Current:	20151201
Date Ended Current:	Not reported
Owner/Operator Address:	4930 SOUTH CONGRESS AVENUE
Owner/Operator City,State,Zip:	AUSTIN 98745
Owner/Operator Telephone:	909-483-3300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20210524
Handler Name:	JET ENVIRONMENTAL SERVICES, INC.
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

JET ENVIRONMENTAL SERVICES, INC. (Continued) **1019326700**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20160809
Handler Name:	JET ENVIRONMENTAL SERVICES, INC.
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	541620
NAICS Description:	ENVIRONMENTAL CONSULTING SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

IO1317 **RISING SUN JAPANESE AUTOMOTIVE** **TX Ind. Haz Waste** **S103608823**
WNW **4930 S CONGRESS AVE BLDG D** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.019 mi.
98 ft. **Site 4 of 4 in cluster IO**

Actual:
613 ft.

Focus Map:
17

Ind. Haz Waste:

Name:	RISING SUN JAPANESE AUTOMOTIVE
Address:	4930 S CONGRESS AVE BLDG D
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	74316
Registration Initial Notification Date:	08/31/1987
Registration Last Amendment Date:	08/04/2021
EPA Identification:	TXD982548430
Primary NAICS Code:	Not reported
Status Change Date:	19870831
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1

RISING SUN JAPANESE AUTOMOTIVE (Continued) **S103608823**

Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	RISING SUN JAPANESE AUTOMOTIVE
Contact Name:	ALLAN WALKER
Contact Telephone Number:	512-4434122
Mailing Address:	4930 S CONGRESS AVE BLDG D
Mailing Address2:	BLDG D
Mailing City,State,Zip:	AUSTIN, TX 787452374
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28696
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20211207
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	RISING SUN JAPANESE AUTOMOTIVE
Operator Address:	4930 S CONGRESS AVE BLDG D
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4434122
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	RISING SUN JAPANESE AUTOMOTIVE
Owner Mailing Address:	4930 S CONGRESS AVE BLDG D
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4434122
Owner Fax:	Not reported

RISING SUN JAPANESE AUTOMOTIVE (Continued) **S103608823**

Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4930 S CONGRESS AVE BLDG D
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4434122
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4930 S CONGRESS AVE BLDG D
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4434122
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALLAN WALKER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4930 S CONGRESS AVE BLDG D
Contact Address 2:	BLDG D
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4434122
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4930 S CONGRESS AVE BLDG D
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000304086
Principal Name:	RISING SUN JAPANESE AUTOMOTIVE
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4930 S CONGRESS AVE BLDG D
Mailing Address 2:	Not reported

RISING SUN JAPANESE AUTOMOTIVE (Continued) **S103608823**

Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000304086
Principal Name:	RISING SUN JAPANESE AUTOMOTIVE
Attention Name:	Not reported
Attention Suffix:	HWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100635754
Name:	RISING SUN JAPANESE AUTOMOTIVE
Address:	4930 S CONGRESS AVE BLDG D
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-2374
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346381
Customer Name:	RISING SUN JAPANESE AUTOMOTIVE
Customer Legal Name:	Rising Sun Japanese Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100635754
Name:	RISING SUN JAPANESE AUTOMOTIVE
Address:	4930 S CONGRESS AVE BLDG D
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-2374
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346381
Customer Name:	RISING SUN JAPANESE AUTOMOTIVE
Customer Legal Name:	Rising Sun Japanese Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

FI1318 **THE OIL EXCHANGE** **TX UST** **U001256425**
ENE **1806 E RIVERSIDE DR** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.019 mi.
98 ft. **Site 12 of 12 in cluster FI**

Actual:
460 ft.

Focus Map:
14

UST:

Name:	THE OIL EXCHANGE
Address:	1806 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411322
AI Number:	21834
Facility Type:	RETAIL
Facility Begin Date:	09/16/1986

THE OIL EXCHANGE (Continued) **U001256425**

Facility Status:	INACTIVE
Additional ID:	343251102003095
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	KYLE NICHOLS,
Contact Organization Name:	THE OIL EXCHANGE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124400001
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	G R LUCA,V.P OPERATIONS
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601592116
Owner Last Name:	RIVERSIDE OW LIMITED PARTNERSHIP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OT
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	351251092003095
Additional ID:	343251102003095
AI Number:	21834
Owner Effective Begin Date:	09/16/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986

THE OIL EXCHANGE (Continued) **U001256425**

Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	56076
Facility ID:	88501
Ai Number:	21834
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/13/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

THE OIL EXCHANGE (Continued) **U001256425**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/15/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	143542
UST ID:	56076
AI Number:	21834
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RIVERSIDE OW LIMITED PARTNERSHIP
Contact Mailing Address (Delivery):	1806 E RIVERSIDE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 1322
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y

THE OIL EXCHANGE (Continued) **U001256425**

Facility ID:	88501
Additional ID:	343251102003095
Princ ID:	351251092003095
AI Number:	21834
Facility Name:	THE OIL EXCHANGE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KYLE NICHOLS/

HIST UST AUSTIN:

Name:	ROAD RUNNER LUBE
Address:	1806 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	EX061
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IW1319 **GULF REFG CO STA NO** **EDR Hist Auto** **1013766523**
NNE **26 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.019 mi.
99 ft. **Site 1 of 2 in cluster IW**

Actual:
448 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS

DY1320 **LAWSHA LEE DCLO CLNR** **EDR Hist Cleaner** **1013779547**
SSW **215 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.019 mi.
99 ft. **Site 4 of 11 in cluster DY**

Actual:
477 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	LAWSHA LEE DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1940	LAWSHA LEE DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

AJ1321 **KLINGEMANN CAR CARE CENTER** **TX RDR** **S127542951**
WNW **6200 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.019 mi.
100 ft. **Site 11 of 13 in cluster AJ**

Actual:
706 ft.
RDR:

Focus Map:
9

RDR ID:	15274
Facility ID:	0
RN:	Not reported

KLINGEMANN CAR CARE CENTER (Continued) **S127542951**

CN:	Not reported
Name:	KLINGEMANN CAR CARE CENTER
Address:	6200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/15/2006
Due Date:	7/14/2006
Tank Owner:	JACKSON FAMILY LIMITED
Contact Person:	LAVADA STEED JACKSON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/10/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	7/10/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AJ1322 **MORGAN AUTOMOTIVE** **TX HIST UST** **S102748179**
WNW **6200 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX CENTRAL REGISTRY**
0.019 mi. **TX NON REGIST PST**
100 ft. **Site 12 of 13 in cluster AJ**

Actual:
706 ft.

Focus Map:
9

HIST UST AUSTIN:

Name:	KLINGMAN CAR CARE
Address:	6200 N. LAMAR BLVD.
City,State,Zip:	AUSTIN, TX
Id UST:	C0720
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	MORGAN AUTOMOTIVE
Address:	6200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61249
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6200 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11

MORGAN AUTOMOTIVE (Continued) **S102748179**

Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MORGAN AUTOMOTIVE
Contact Name:	ROBERT MORGAN
Contact Telephone Number:	Not reported
Mailing Address:	6200 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524004
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19608
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030303
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MORGAN AUTOMOTIVE
Operator Address:	6200 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MORGAN AUTOMOTIVE
Owner Mailing Address:	6200 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752

MORGAN AUTOMOTIVE (Continued) **S102748179**

Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6200 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6200 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ROBERT MORGAN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6200 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100547371
Name:	KLINGEMANN CAR CARE CENTERS
Address:	6200 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600258438
Customer Name:	MORGAN AUTOMOTIVE
Customer Legal Name:	Morgan Automotive
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001

MORGAN AUTOMOTIVE (Continued) **S102748179**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6200 N Lamar, Austin, TX

Regulated Entity Number:	RN100547371
Name:	KLINGEMANN CAR CARE CENTERS
Address:	6200 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4004
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602955627
Customer Name:	JACKSON FAMILY LIMITED PARTNERSHIP
Customer Legal Name:	Jackson Family, Limited Partnership
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	12/21/2005
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6200 N Lamar, Austin, TX

NON REGIST PST:

RN Number:	RN100547371
Name:	KLINGEMANN CAR CARE CENTERS
Address:	6200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752 4004
Physical Location:	6200 N Lamar, Austin, TX
CN Number:	CN600258438
Customer Name:	MORGAN AUTOMOTIVE
Customer Role:	OWNER OPERATOR
Primary Business:	No primary business description on file.
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=297283022001297

RN Number:	RN100547371
Name:	KLINGEMANN CAR CARE CENTERS
Address:	6200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752 4004
Physical Location:	6200 N Lamar, Austin, TX
CN Number:	CN602955627
Customer Name:	JACKSON FAMILY LIMITED PARTNERSHIP
Customer Role:	N/A
Primary Business:	No primary business description on file.
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED

MORGAN AUTOMOTIVE (Continued) **S102748179**

ID Number: Not reported
ID Type: Not reported
ID Status: Not reported
URL: https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=297283022001297

AJ1323 **NORTH LAMAR AUTOMOTIVE** **EDR Hist Auto** **1013761054**
WNW **6200 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.019 mi.
100 ft. **Site 13 of 13 in cluster AJ**

Actual:
706 ft.

EDR Hist Auto

Focus Map:
9

Year:	Name:	Type:
1972	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1973	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1974	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1975	NORTH LAMAR AUTOMOTIVE	AUTOMOBILE REPAIRING
1976	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1977	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1978	NORTH LAMAR AUTOMOTIVE SERVICE	General Automotive Repair Shops
1980	RANSOM AUTOMOTIVE CNTR REPR	AUTOMOBILE REPAIRING
1982	MORGAN AUTOMOTIVE	Gasoline Service Stations
1983	MORGAN AUTOMOTIVE	Gasoline Service Stations
1984	MORGAN AUTOMOTIVE REPR	AUTOMOBILE REPAIRING
1985	MORGAN AUTOMOTIVE	Gasoline Service Stations
1986	MORGAN AUTOMOTIVE	Gasoline Service Stations
1987	MORGAN AUTOMOTIVE	Gasoline Service Stations
1988	MORGAN AUTOMOTIVE	Gasoline Service Stations
1989	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1990	FOREIGN & DOMESTIC AUTOMOTIVE A	AUTOMOBILE REPAIRING
1991	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1992	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1993	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1994	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1995	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1996	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1997	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1998	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
1999	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
2000	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
2001	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
2002	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
2003	FOREIGN & DOMESTIC AUTOMOTIVE	General Automotive Repair Shops
2008	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2009	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2010	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2011	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2012	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops
2013	A TO Z AUTOMOTIVE INCORPORATED	General Automotive Repair Shops

IX1324 **RIVERSIDE SERVICE STATION** **EDR Hist Auto** **1013761444**
WNW **207 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.019 mi.
100 ft. **Site 1 of 6 in cluster IX**

Actual:
438 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	RIVERSIDE SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS

BF1325 **FOUR SON'S QUALITY CLEANERS** **US AIRS** **1004601127**
ESE **3001 GUADALUPE** **FINDS** **N/A**
< 1/8 **AUSTIN, TX 78705** **ECHO**
0.019 mi. **TX DRYCLEANERS**
100 ft. **Site 8 of 10 in cluster BF**

Actual:
591 ft.

Focus Map:
8

US AIRS MINOR:

Envid:	1004601127
Region Code:	06
Programmatic ID:	AIR 06000000484536E017
Facility Registry ID:	110001875016
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	06
Programmatic ID:	AIR 06000000484536E017
Facility Registry ID:	110001875016
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	1997-06-13 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:

Registry ID: 110001875016

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

of the Clean Air Act.
AIR MINOR
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004601127
Registry ID:	110001875016
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001875016
Name:	FOUR SON'S QUALITY CLEANERS
Address:	3001 GUADALUPE
City,State,Zip:	AUSTIN, TX 78705

DRYCLEANERS:

Name:	FOUR SONS QUALITY CLEANERS 26
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR12155
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	Not reported
Bill Addr2:	Not reported
Bill City/State/Zip:	Not reported
EMail:	Not reported
Phone Number:	0 0
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	6000
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	4500
Part Stat:	YES
Gross Receipts:	> $150,000

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	HYDROCARON, RECLAIMED
Gallons:	600
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	1200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	1200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PETROLEUM
Gallons:	2200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PETROLEUM
Gallons:	4500
Part Stat:	YES
Gross Receipts:	> $150,000

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	11
CN Number:	CN602465189
DCR Number:	Not reported
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	3001 GUADALUPE ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78705 2817
EMail:	KNEWBERRY49@ATT.NET
Phone Number:	512 4772969
Site Name:	FOUR SONS QUALITY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS 26
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR12155
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	FOUR SONS QUALITY CLEANERS 26
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

FOUR SON'S QUALITY CLEANERS (Continued) **1004601127**

Name:	FOUR SONS QUALITY CLEANERS 26
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	REGION 11 - AUSTIN
CN Number:	CN602465189
DCR Number:	DCR12155
AR Number:	24000432
Principal Name:	NLN CORPORATION
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	FOUR SONS QUALITY CLEANERS 26
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FOUR SONS QUALITY CLEANERS 26
Address:	3001 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103967675
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR12155
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	FOUR SONS QUALITY CLEANERS 26
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	2500
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

BF1326 **CHING WONG CLEANERS** **EDR Hist Cleaner** **1013781372**
ESE **3001 GUADALUPE ST** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.019 mi.
100 ft. **Site 9 of 10 in cluster BF**

Actual:
591 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1969	CHING WONG INC	Drycleaning Plants, Except Rugs
1970	CHING WONG CLEANERS	CLEANERS AND DYERS
1970	CHING WONG INC	Drycleaning Plants, Except Rugs

CHING WONG CLEANERS (Continued) **1013781372**

1971	CHING WONG INC	Drycleaning Plants, Except Rugs
1972	CHING WONG INC	Drycleaning Plants, Except Rugs
1973	CHING WONG INC	Drycleaning Plants, Except Rugs
1974	CHING WONG INC	Drycleaning Plants, Except Rugs
1975	C & W CLEANERS	CLEANERS AND DYERS
1975	CHING WONG INC	Drycleaning Plants, Except Rugs
1976	CHING WONG INC	Drycleaning Plants, Except Rugs
1977	CHING WONG INC	Drycleaning Plants, Except Rugs
1978	CHING WONG INC	Drycleaning Plants, Except Rugs
1979	CHING WONG INC	Drycleaning Plants, Except Rugs
1980	CLOTHES CARE CENTER	CLEANERS AND DYERS
1980	CLOTHES CARE CENTER	Power Laundries, Family And Commercial
1980	CHING WONG INC	Drycleaning Plants, Except Rugs
1982	CHING WONG INC	Drycleaning Plants, Except Rugs
1982	FOUR SONS CLOTHES CARE CENTER*	Drycleaning Plants, Except Rugs
1983	CHING WONG INC	Drycleaning Plants, Except Rugs
1983	FOUR SONS CLTHS CR CTR INC	Drycleaning Plants, Except Rugs
1984	CLOTHES CARE CENTER CLN	CLEANERS AND DYERS
1985	FOUR SONS CLTHS CR CTR INC	Drycleaning Plants, Except Rugs
1986	FOUR SONS CLOTHES CARE CENTER*	Drycleaning Plants, Except Rugs
1987	FOUR SONS CLOTHES CARE CENTER*	Drycleaning Plants, Except Rugs
1988	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1989	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1990	FOUR SONS CLOTHES CARE CENTER C	CLEANERS AND DYERS
1990	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1991	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1992	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1993	FOUR SONS CLOTHES CARE CENTER	Drycleaning Plants, Except Rugs
1994	NLN CORPORATION	Drycleaning Plants, Except Rugs
1995	NLN CORPORATION	Drycleaning Plants, Except Rugs
1996	NLN CORPORATION	Drycleaning Plants, Except Rugs
1997	NLN CORPORATION	Drycleaning Plants, Except Rugs
1998	NLN CORPORATION	Drycleaning Plants, Except Rugs
1999	NLN CORPORATION	Drycleaning Plants, Except Rugs
2000	NLN CORPORATION	Drycleaning Plants, Except Rugs
2001	NLN CORPORATION	Drycleaning Plants, Except Rugs
2002	NLN CORPORATION	Drycleaning Plants, Except Rugs
2003	NLN CORPORATION	Drycleaning Plants, Except Rugs
2004	NLN CORPORATION	Drycleaning Plants, Except Rugs
2005	NLN CORPORATION	Drycleaning Plants, Except Rugs
2006	NLN CORPORATION	Drycleaning Plants, Except Rugs
2007	NLN CORPORATION	Drycleaning Plants, Except Rugs
2010	NLN CORPORATION	Drycleaning Plants, Except Rugs
2011	NLN CORPORATION	Drycleaning Plants, Except Rugs
2012	NLN CORPORATION	Drycleaning Plants, Except Rugs
2013	NLN CORPORATION	Drycleaning Plants, Except Rugs
2014	NLN CORPORATION	Drycleaning Plants, Except Rugs

BF1327 ESE < 1/8 0.019 mi. 100 ft. — **MCWILLIAMS & FIEGEL FILLING STA**, **3001 GUADALUPE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013770020** / **N/A**

Site 10 of 10 in cluster BF

Actual: 591 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1935	SUTHERLAND W F FILL	GASOLINE AND OIL SERVICE STATIONS
1947	MCWILLIAMS & FIEGEL FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1958	SLOANS SERV STA	GASOLINE STATIONS
1962	PICNIC MOBIL SERV	GASOLINE STATIONS

DW1328 West < 1/8 0.019 mi. 100 ft. — **CENTRAL LIBRARY**, **710 W. CESAR CHAVEZ ST.**, **AUSTIN, TX** — **TX HIST UST** — **S128728753** / **N/A**

Site 3 of 3 in cluster DW

Actual: 458 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	CENTRAL LIBRARY
Address:	710 W. CESAR CHAVEZ ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3389
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

1329 ESE < 1/8 0.019 mi. 101 ft. — **CHAMBERS**, **1025 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780105** / **N/A**

Actual: 520 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1962	CHAMBERS	CLEANERS AND DYERS

IY1330 ESE < 1/8 0.019 mi. 101 ft. — **TOM D. SMITH**, **307 W 10TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678835** / **N/A**

Site 1 of 3 in cluster IY

Actual: 541 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	TOM D. SMITH
Address:	307 W 10TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0322
HID UST:	322
Inspection:	Not reported
Due:	06/01/2012

Z1331 WNW < 1/8 0.019 mi. 101 ft. **DALE'S AUTO 7544 N. LAMAR AUSTIN, TX** **TX RDR** **S127537102 N/A**

Site 7 of 9 in cluster Z

Actual: 755 ft.

Focus Map: 6

RDR:

RDR ID:	8626
Facility ID:	64039
RN:	Not reported
CN:	Not reported
Name:	DALE'S AUTO
Address:	7544 N. LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/16/1999
Due Date:	5/15/1999
Tank Owner:	R & K INVESTMENTS
Contact Person:	RUSSELL MOORE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/14/1999
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	REPORT RECD MARCH 16, 1999
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/14/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

Z1332 WNW < 1/8 0.019 mi. 101 ft. **DOC HOLLIDAYS PAWN SHOP 7544 N LAMAR BLVD AUSTIN, TX 78752** **TX UST** **U003566392 N/A**

Site 8 of 9 in cluster Z

Actual: 755 ft.

Focus Map: 6

UST:

Name:	DOC HOLLIDAYS PAWN SHOP
Address:	7544 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787521346
AI Number:	64039
Facility Type:	RETAIL
Facility Begin Date:	12/28/1992
Facility Status:	INACTIVE
Additional ID:	412586332002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,

DOC HOLLIDAYS PAWN SHOP (Continued) **U003566392**

Contact Organization Name:	DOC HOLLIDAYS PAWN SHOP
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124515712
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/05/1992
Signature Name/Title On Earliest Reg Form:	L D SMITH,PARTNER
Application Received Date On Earliest Reg Form:	12/18/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780035
Owner Last Name:	R & K INVESTMENTS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	403586322002053
Additional ID:	412586332002053
AI Number:	64039
Owner Effective Begin Date:	02/23/1994
State Tax ID:	17516670886
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/18/1992
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147451
Facility ID:	94975
Ai Number:	64039
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/03/1999
Empty:	N

DOC HOLLIDAYS PAWN SHOP (Continued) **U003566392**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	12/10/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	156105
UST ID:	147451
AI Number:	64039
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported

DOC HOLLIDAYS PAWN SHOP (Continued) **U003566392**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	R & K INVESTMENTS
Contact Mailing Address (Delivery):	5716 W HIGHWAY 290 STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78735 8721
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94975
Additional ID:	412586332002053
Princ ID:	403586322002053
AI Number:	64039
Facility Name:	DOC HOLLIDAYS PAWN SHOP
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RUSSELL MOORE/

EJ1333 NE < 1/8 0.019 mi. 102 ft. | **SHERRILL'S EXXON 343 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S128728871 N/A**

Site 10 of 19 in cluster EJ

Actual: 449 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	SHERRILL'S EXXON
Address:	343 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0038
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EJ1334 NE < 1/8 0.019 mi. 102 ft. | **M. H. CROCKETT 343 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S128729478 N/A**

Site 11 of 19 in cluster EJ

Actual: 449 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	M. H. CROCKETT
Address:	343 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0944
HID UST:	944
Inspection:	Not reported
Due:	06/01/2012

EJ1335 NE < 1/8 0.019 mi. 102 ft. | **M. H. CROCKETT 343 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S128729203 N/A**

Site 12 of 19 in cluster EJ

Actual: 449 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	M. H. CROCKETT
Address:	343 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0167
HID UST:	167
Inspection:	Not reported
Due:	06/01/2012

EJ1336 **PAUL SHERRILLS EXXON** **EDR Hist Auto** **1020820565**
NE **343 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.019 mi.
102 ft. **Site 13 of 19 in cluster EJ**

Actual:
449 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1986	PAUL SHERRILLS EXXON	Gasoline Service Stations
1987	PAUL SHERRILLS EXXON	Gasoline Service Stations
1988	PAUL SHERRILLS EXXON	Gasoline Service Stations
1989	PAUL SHERRILLS EXXON	Gasoline Service Stations
1990	PAUL SHERRILLS EXXON	Gasoline Service Stations
1991	PAUL SHERRILLS EXXON	Gasoline Service Stations
1992	PAUL SHERRILLS EXXON	Gasoline Service Stations
1993	PAUL SHERRILLS EXXON	Gasoline Service Stations
1994	PAUL SHERRILLS EXXON	Gasoline Service Stations

EJ1337 **EXXON SS6 0015** **TX LPST** **U001260012**
NE **343 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.019 mi.
102 ft. **Site 14 of 19 in cluster EJ**

Actual:
449 ft.

Focus Map:
14

LPST:

Name:	EXXON 60015
Address:	343 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0026003
LPST Id:	091595
Facility Location:	343 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/01/1986
Entered Date:	01/06/1988
Reported Date:	12/23/1987
Closure Date:	10/03/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	JES
Responsible Party Name:	Not reported
Responsible Party Contact:	DEBBIE H HUNTER
Responsible Party Address:	PO BOX 2180
Responsible Party City,St,Zip:	HOUSTON, TX 77252 2180
Responsible Party Telephone:	713/656-2312
Reported Date:	12/23/1987
Case Start Date:	10/03/1997
Reference Number:	RN102655388
Project Manager:	JSIROTA

UST:

Name:	EXXON SS6 0015
Address:	343 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041218

EXXON SS6 0015 (Continued) **U001260012**

AI Number:	26003
Facility Type:	RETAIL
Facility Begin Date:	10/13/1986
Facility Status:	INACTIVE
Additional ID:	87570382002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	JOSEPH SYKORA,OWNER
Contact Organization Name:	EXXON SS6 0015
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2547729895
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,ENG SUPERVISOR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600123939
Owner Last Name:	EXXON MOBIL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	679380312001134
Additional ID:	87570382002175
AI Number:	26003
Owner Effective Begin Date:	10/13/1986
State Tax ID:	11354090059
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

EXXON SS6 0015 (Continued) **U001260012**

Tank:

Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66786
Facility ID:	47901
Ai Number:	26003
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

EXXON SS6 0015 (Continued) **U001260012**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	34819
UST ID:	66786
AI Number:	26003
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2

EXXON SS6 0015 (Continued) **U001260012**

Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66787
Facility ID:	47901
Ai Number:	26003
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

EXXON SS6 0015 (Continued) **U001260012**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	34820
UST ID:	66787
AI Number:	26003
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

EXXON SS6 0015 (Continued) **U001260012**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66791
Facility ID:	47901
Ai Number:	26003
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

EXXON SS6 0015 (Continued) **U001260012**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	34824
UST ID:	66791
AI Number:	26003
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

EXXON SS6 0015 (Continued) **U001260012**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66789

EXXON SS6 0015 (Continued) **U001260012**

Facility ID:	47901
Ai Number:	26003
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported

EXXON SS6 0015 (Continued) **U001260012**

UST Comprt ID:	34822
UST ID:	66789
AI Number:	26003
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809

EXXON SS6 0015 (Continued) **U001260012**

Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66790
Facility ID:	47901
Ai Number:	26003
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

EXXON SS6 0015 (Continued) **U001260012**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	34823
UST ID:	66790
AI Number:	26003
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

EXXON SS6 0015 (Continued) **U001260012**

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1946
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66788
Facility ID:	47901
Ai Number:	26003
Tank Id:	6
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

EXXON SS6 0015 (Continued) **U001260012**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	6
Tank Capacity:	Not reported
UST Comprt ID:	34821
UST ID:	66788
AI Number:	26003
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

EXXON SS6 0015 (Continued) **U001260012**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9809
Cert ID:	128665
UST Comprt ID:	355759
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128666
UST Comprt ID:	355760
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128670
UST Comprt ID:	355754
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128669
UST Comprt ID:	355755
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A
Self Cert ID:	9809
Cert ID:	128668
UST Comprt ID:	355756
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

EXXON SS6 0015 (Continued) **U001260012**

Self Cert ID:	9809
Cert ID:	128667
UST Comprt ID:	355757
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128673
UST Comprt ID:	355751
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128672
UST Comprt ID:	355752
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128671
UST Comprt ID:	355753
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Self Cert ID:	9809
Cert ID:	128664
UST Comprt ID:	355758
UST ID:	116936
AI Number:	26003
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	EXXON MOBIL CORPORATION
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47901
Additional ID:	87570382002175
Princ ID:	679380312001134
AI Number:	26003
Facility Name:	EXXON SS6 0015
AR Number:	Not reported
AR UST Number Suffix:	Not reported

EXXON SS6 0015 (Continued) **U001260012**

AR AST Number Suffix: Not reported
Contact Name/Title: HEATHER GILMORE/

DR1338 **CASTRO CLEANERS** **EDR Hist Cleaner** **1018882357**
SW **502 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.019 mi.
102 ft. **Site 21 of 38 in cluster DR**

Actual:
484 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1969	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1970	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1971	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1972	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1973	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1974	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1976	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1980	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1982	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1983	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1985	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1986	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1987	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1988	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1989	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1990	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1991	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1992	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1993	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1994	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1995	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1996	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1997	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1998	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
1999	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
2000	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
2001	CASTRO CLEANERS	Drycleaning Plants, Except Rugs
2002	CASTRO CLEANERS	Drycleaning Plants, Except Rugs

DR1339 **CASTRO'S CLEANERS** **RCRA NonGen / NLR** **1000420360**
SW **502 EAST 6TH STREET** **US AIRS** **TXD981610827**
< 1/8 **AUSTIN, TX 78701** **FINDS**
0.019 mi. **ECHO**
102 ft. **Site 22 of 38 in cluster DR**

Actual:
484 ft.

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Castros Cleaners
Handler Address:	E 6TH
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981610827
Contact Name:	LUCIANO CASTRO
Contact Address:	E 6TH

Focus Map:
11

CASTRO'S CLEANERS (Continued) **1000420360**

Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-478-1458
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E 6TH
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Castros Cleaners
Owner Type:	Private
Operator Name:	Castros Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CASTRO'S CLEANERS (Continued) **1000420360**

Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LUCIANO CASTRO JR	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CASTROS CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	502 E 6TH
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-478-1458
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CASTROS CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	502 E 6TH
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-478-1458
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CASTRO'S CLEANERS (Continued) **1000420360**

Historic Generators:

Receive Date:	19861006
Handler Name: CASTROS CLNRS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: CASTROS CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

US AIRS MINOR:

Envid:	1000420360
Region Code:	06
Programmatic ID:	AIR 06000000484536E021
Facility Registry ID:	110001875052
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	06
Programmatic ID:	AIR 06000000484536E021
Facility Registry ID:	110001875052
Air Operating Status Code:	OPR

CASTRO'S CLEANERS (Continued) **1000420360**

Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1997-06-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001875052

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000420360
Registry ID: 110001875052
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001875052
Name: CASTRO'S CLEANERS
Address: 502 EAST 6TH STREET
City,State,Zip: AUSTIN, TX 78701

DR1340 **CASTROS CLEANERS** **TX HIST UST** **S102752373**
SW **502 E 6TH ST** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX Ind. Haz Waste**
0.019 mi. **TX CENTRAL REGISTRY**
102 ft. **Site 23 of 38 in cluster DR**

Actual:
484 ft.

Focus Map:
11

HIST UST AUSTIN:
Name: OTTA TIROFF
Address: 502 E 6TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0128
HID UST: 128
Inspection: Not reported

CASTROS CLEANERS (Continued) **S102752373**

Due: 06/01/2012

ASBESTOS:

Name:	MIR TRADING
Address:	502 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	6.2
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

CASTROS CLEANERS (Continued) **S102752373**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CASTROS CLEANERS
Address:	502 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	69773
Registration Initial Notification Date:	10/10/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981610827
Primary NAICS Code:	Not reported
Status Change Date:	19861010
Land Type:	PRIVATE
Description of Facility Site Location:	502 E 6th, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CASTROS CLEANERS
Contact Name:	LUCIANO CASTRO
Contact Telephone Number:	512-4781458
Mailing Address:	502 E 6TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787013742
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24644
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported

CASTROS CLEANERS (Continued) **S102752373**

Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CASTROS CLEANERS
Operator Address:	502 E 6THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4781458
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CASTROS CLEANERS
Owner Mailing Address:	502 E 6THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4781458
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	502 E 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4781458
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	502 E 6THST

CASTROS CLEANERS (Continued) **S102752373**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4781458
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LUCIANO CASTRO
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	502 E 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4781458
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100568179
Name:	CASTROS CLEANERS
Address:	502 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600278816
Customer Name:	CASTROS CLEANERS
Customer Legal Name:	Castro's Cleaners
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	502 E 6th, Austin, TX

Regulated Entity Number:	RN100568179
Name:	CASTROS CLEANERS
Address:	502 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3742
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600278816
Customer Name:	CASTROS CLEANERS
Customer Legal Name:	Castro's Cleaners
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	502 E 6th, Austin, TX

AO1341	**FLOYDS AUTO SALES & SERVICE**	**TX LPST**	**U001250910**
ESE	**5253 N LAMAR BLVD**	**TX UST**	**N/A**
< 1/8	**AUSTIN, TX 78751**	**TX HIST UST**	
0.019 mi.		**TX Ind. Haz Waste**	
102 ft.	**Site 4 of 14 in cluster AO**	**TX CENTRAL REGISTRY**	

Actual:
674 ft.

Focus Map:
8

LPST:

Name:	FLOYDS AUTO SALES SERVICE
Address:	5253 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0015637
LPST Id:	100889
Facility Location:	5253 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/11/1991
Entered Date:	12/03/1991
Reported Date:	11/11/1991
Closure Date:	04/02/1993
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	ANTONIO PENA
Responsible Party Name:	Not reported
Responsible Party Contact:	FLOYD SCHKADE
Responsible Party Address:	5353 N LAMAR
Responsible Party City,St,Zip:	AUSTIN, TX 78751
Responsible Party Telephone:	512/454-0664
Reported Date:	11/11/1991
Case Start Date:	04/02/1993
Reference Number:	RN100555283
Project Manager:	ARP

UST:

Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511820
AI Number:	15637
Facility Type:	RETAIL
Facility Begin Date:	08/15/1986
Facility Status:	INACTIVE
Additional ID:	562048392002149
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	,
Contact Organization Name:	FLOYDS AUTO SALES & SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Contact Telephone:	5124540664
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/24/1986
Signature Name/Title On Earliest Reg Form:	FLOYD W SCHKADE,OWNER
Application Received Date On Earliest Reg Form:	07/29/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600266183
Owner Last Name:	FLOYDS AUTO SALES & SERVICE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	639302122001297
Additional ID:	562048392002149
AI Number:	15637
Owner Effective Begin Date:	08/15/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1956
Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	40163
Facility ID:	54280
Ai Number:	15637
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	52881
UST ID:	40163
AI Number:	15637
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	40164
Facility ID:	54280
Ai Number:	15637
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	52882
UST ID:	40164
AI Number:	15637
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	175098
Facility ID:	54280
Ai Number:	15637
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	1000
UST Comprt ID:	52886
UST ID:	175098
AI Number:	15637
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	40166
Facility ID:	54280
Ai Number:	15637
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	52884
UST ID:	40166
AI Number:	15637
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	40167
Facility ID:	54280
Ai Number:	15637
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/12/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	52885
UST ID:	40167
AI Number:	15637
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Tank Registration Date:	07/29/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	40165
Facility ID:	54280
Ai Number:	15637
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	52883
UST ID:	40165
AI Number:	15637
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FLOYDS AUTO SALES & SERVICE
Contact Mailing Address (Delivery):	5253 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 1820
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Contact Address Deliverable:	Y
Facility ID:	54280
Additional ID:	562048392002149
Princ ID:	639302122001297
AI Number:	15637
Facility Name:	FLOYDS AUTO SALES & SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	FLOYD SCHKADE/

HIST UST AUSTIN:

Name:	FLOYD'S AUTO SALES AND SERVICE
Address:	5253 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0058
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	73161
Registration Initial Notification Date:	01/09/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19870109
Land Type:	Not reported
Description of Facility Site Location:	5253 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	FLOYDS AUTO SALES & SERVICE
Contact Name:	FLOYD SCHKADE
Contact Telephone Number:	512-4540664
Mailing Address:	5253 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787511820
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

TNRCC Facility ID:	27592
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030221
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	FLOYDS AUTO SALES & SERVICE
Operator Address:	5253 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78751
Operator Country:	UNITED STA
Operator Telephone:	1-512-4540664
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FLOYDS AUTO SALES & SERVICE
Owner Mailing Address:	5253 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Country:	UNITED STA
Owner Telephone:	1-512-4540664
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	5253 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4540664
Contact Fax:	Not reported

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	5253 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4540664
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	FLOYD SCHKADE
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	5253 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	1-512-4540664
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600266183
Customer Name:	FLOYDS AUTO SALES & SERVICE
Customer Legal Name:	Floyd's Auto Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX
Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427948
Customer Name:	SCHKADE, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600266183
Customer Name:	FLOYDS AUTO SALES & SERVICE
Customer Legal Name:	Floyd's Auto Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427948
Customer Name:	SCHKADE, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600266183
Customer Name:	FLOYDS AUTO SALES & SERVICE
Customer Legal Name:	Floyd's Auto Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

FLOYDS AUTO SALES & SERVICE (Continued) **U001250910**

Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427948
Customer Name:	SCHKADE, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600266183
Customer Name:	FLOYDS AUTO SALES & SERVICE
Customer Legal Name:	Floyd's Auto Sales & Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

Regulated Entity Number:	RN100555283
Name:	FLOYDS AUTO SALES & SERVICE
Address:	5253 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-1820
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427948
Customer Name:	SCHKADE, FLOYD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	5253 N Lamar, Austin, TX

AO1342 **GARDNERS GULL SERVICE** **EDR Hist Auto** **1013766282**
ESE **5253 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.019 mi.
102 ft. **Site 5 of 14 in cluster AO**

Actual:
674 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1958	FRETWELLS GULF	GASOLINE STATIONS
1962	D&L GULF SERV GAS	GASOLINE STATIONS
1965	GRABENS GULF SERVICE GAS	GASOLINE STATIONS
1970	GARDNERS GULL SERVICE	GASOLINE STATIONS
1975	PEREZ GULF SERVICE	GASOLINE STATIONS
1982	FLOYDS AUTO SALES	General Automotive Repair Shops
1983	FLOYDS AUTO SALES	General Automotive Repair Shops
1985	FLOYDS AUTO SALES	General Automotive Repair Shops
1986	FLOYDS AUTO SALES	General Automotive Repair Shops
1987	FLOYDS AUTO SALES	General Automotive Repair Shops
1988	FLOYDS AUTO SALES	General Automotive Repair Shops
1989	FLOYDS AUTO SALES	General Automotive Repair Shops
1990	FLOYDS AUTO SALES	General Automotive Repair Shops
1991	FLOYDS AUTO SALES	General Automotive Repair Shops
1992	FLOYDS AUTO SALES	General Automotive Repair Shops
1993	FLOYDS AUTO SALES	General Automotive Repair Shops
1994	FLOYDS AUTO SALES	General Automotive Repair Shops
1995	FLOYDS AUTO SALES	General Automotive Repair Shops
1996	FLOYDS AUTO SALES	General Automotive Repair Shops
1997	FLOYDS AUTO SALES	General Automotive Repair Shops
1998	FLOYDS AUTO SALES	General Automotive Repair Shops
1999	FLOYDS AUTO SALES	General Automotive Repair Shops
2000	FLOYDS AUTO SALES	General Automotive Repair Shops
2001	FLOYDS AUTO SALES	General Automotive Repair Shops
2002	FLOYDS AUTO SALES	General Automotive Repair Shops
2003	FLOYDS AUTO SALES	General Automotive Repair Shops
2004	FLOYDS AUTO SALES	General Automotive Repair Shops
2005	FLOYDS AUTO SALES	General Automotive Repair Shops
2006	FLOYDS AUTO SALES	General Automotive Repair Shops
2007	FLOYDS AUTO SALES	General Automotive Repair Shops
2008	FLOYDS AUTO SALES	General Automotive Repair Shops
2009	FLOYDS AUTO SALES	General Automotive Repair Shops
2010	FLOYDS AUTO SALES	General Automotive Repair Shops
2011	FLOYDS AUTO SALES	General Automotive Repair Shops
2012	FLOYDS AUTO SALES	General Automotive Repair Shops
2013	FLOYDS AUTO SALES	General Automotive Repair Shops
2014	FLOYDS AUTO SALES	General Automotive Repair Shops

ET1343 **ACE CLEANERS & ALTERATIONS** **TX DRYCLEANERS** **S109362059**
ESE **1117 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
103 ft. **Site 9 of 15 in cluster ET**

Actual:
499 ft.

DRYCLEANERS:

Name:	ACE CLEANERS & ALTERATIONS
Address:	1117 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103995502
Region:	11
CN Number:	CN602482275

Focus Map:
14

ACE CLEANERS & ALTERATIONS (Continued) **S109362059**

DCR Number:	Not reported
AR Number:	24001229
Principal Name:	WONG, MEI LIN
Bill Addr1:	1790 VIA PETIRROJO APT G
Bill Addr2:	Not reported
Bill City/State/Zip:	NEWBURY PARK, CA 91320 5961
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ACE CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	ACE CLEANERS & ALTERATIONS
Address:	1117 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103995502
Region:	11
CN Number:	CN602482275
DCR Number:	Not reported
AR Number:	24001229
Principal Name:	WONG, MEI LIN
Bill Addr1:	1790 VIA PETIRROJO APT G
Bill Addr2:	Not reported
Bill City/State/Zip:	NEWBURY PARK, CA 91320 5961
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ACE CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	250
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	ACE CLEANERS & ALTERATIONS
Address:	1117 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103995502
Region:	11
CN Number:	CN602482275
DCR Number:	Not reported
AR Number:	24001229
Principal Name:	WONG, MEI LIN
Bill Addr1:	1790 VIA PETIRROJO APT G
Bill Addr2:	Not reported
Bill City/State/Zip:	NEWBURY PARK, CA 91320 5961
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ACE CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

ACE CLEANERS & ALTERATIONS (Continued) **S109362059**

Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	ACE CLEANERS & ALTERATIONS
Address:	1117 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103995502
Region:	11
CN Number:	CN602482275
DCR Number:	Not reported
AR Number:	24001229
Principal Name:	WONG, MEI LIN
Bill Addr1:	1790 VIA PETIRROJO APT G
Bill Addr2:	Not reported
Bill City/State/Zip:	NEWBURY PARK, CA 91320 5961
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ACE CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	ACE CLEANERS & ALTERATIONS
Address:	1117 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103995502
Region:	11
CN Number:	CN602482275
DCR Number:	Not reported
AR Number:	24001229
Principal Name:	WONG, MEI LIN
Bill Addr1:	1790 VIA PETIRROJO APT G
Bill Addr2:	Not reported
Bill City/State/Zip:	NEWBURY PARK, CA 91320 5961
EMail:	Not reported
Phone Number:	Not reported
Site Name:	ACE CLEANERS & ALTERATIONS
Site Type:	FACILITY REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

ET1344 **NO DELAY CLEANERS** **EDR Hist Cleaner** **1019920592**
ESE **1117 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
103 ft. **Site 10 of 15 in cluster ET**

Actual:
499 ft.

EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1969	NO DELAY CLEANERS	Drycleaning Plants, Except Rugs
1971	NO DELAY CLEANERS	Drycleaning Plants, Except Rugs
1972	NO DELAY CLEANERS	Drycleaning Plants, Except Rugs
1991	ACE CUSTOM TAILORS	Drycleaning Plants, Except Rugs
1993	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1994	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1995	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1996	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1997	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1998	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
1999	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2000	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2001	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2002	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2003	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2004	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2005	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2006	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2007	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2008	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2009	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs
2010	ACE CLEANERS & ALTERATIONS	Drycleaning Plants, Except Rugs

---

CK1345 **GUTHRIE J C** **EDR Hist Cleaner** **1013785445**
ESE **1712 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
103 ft. **Site 2 of 3 in cluster CK**

Actual:
538 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	GUTHRIE J C	CLOTHES PRESSERS AND CLEANERS
1940	GUTHRIE CLEANERS	CLOTHES PRESSERS AND CLEANERS
1947	CHESNUTT BROS CLEANERS	CLOTHES PRESSERS AND CLEANERS

ET1346 **BUTLER WILLIAM A** **EDR Hist Auto** **1020165266**
ESE **1123 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
103 ft. **Site 11 of 15 in cluster ET**

Actual:
500 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1969	BUTLER WILLIAM A	Gasoline Service Stations
1970	BUTLER WILLIAM A	Gasoline Service Stations
1971	BUTLER WILLIAM A	Gasoline Service Stations
1972	TERRACE GULF SERVICE STATION	Gasoline Service Stations

BUTLER WILLIAM A (Continued) **1020165266**

1987	D & M TIRE CO	Auto And Home Supply Stores
1988	D & M TIRE CO	Auto And Home Supply Stores
1992	D & M TIRE CO	Auto And Home Supply Stores, NEC
1993	D & M TIRE CO	Auto And Home Supply Stores, NEC
1994	D & M TIRE CO	Auto And Home Supply Stores, NEC
1995	D & M TIRE CO	Auto And Home Supply Stores, NEC
1996	D & M TIRE CO	Auto And Home Supply Stores, NEC
1997	D & M TIRE CO	Auto And Home Supply Stores, NEC
1998	D & M TIRE CO	Auto And Home Supply Stores, NEC
2000	DOCS MOTORWORKS INC	General Automotive Repair Shops
2001	DOCS MOTORWORKS INC	General Automotive Repair Shops
2002	DOCS MOTORWORKS INC	General Automotive Repair Shops
2003	DOCS MOTORWORKS INC	General Automotive Repair Shops
2007	D & M TIRE CO	Tire Retreading And Repair Shops, NEC
2008	D & M TIRE CO	Tire Retreading And Repair Shops, NEC

ET1347 **DOCS AUTO WORKS** **TX RDR** **S127542192**
ESE **1123 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
103 ft. **Site 12 of 15 in cluster ET**

Actual:
500 ft.

Focus Map:
14

RDR:

RDR ID:	11033
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	DOCS AUTO WORKS
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/25/2002
Due Date:	12/24/2002
Tank Owner:	STACY MOLITOR SMITH TRUST
Contact Person:	SAM CALLIHAM
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/17/2003
Project Manager:	Tim Rupert
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	TSR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/17/2003
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

ET1348 **MUSIC LANE OWNER, LLC** **TX HIST UST** **S128728773**
ESE **1123 S. CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
103 ft. **Site 13 of 15 in cluster ET**

Actual:
500 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	MUSIC LANE OWNER, LLC
Address:	1123 S. CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3418
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ET1349 **W. W. ROGERS** **TX HIST UST** **S128729247**
ESE **1123 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
103 ft. **Site 14 of 15 in cluster ET**

Actual:
500 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	W. W. ROGERS
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0346
HID UST:	346
Inspection:	Not reported
Due:	06/01/2012

ET1350 **DOCS BACK YARD** **TX LPST** **S111678850**
ESE **1123 SOUTH CONGRESS AVE** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX GCC**
0.020 mi. **TX RDR**
103 ft. **Site 15 of 15 in cluster ET**

Actual:
500 ft.

Focus Map:
14

LPST:

Name:	FORMER DOCS RESTAURANT
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120860
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	01/01/2016
Entered Date:	12/19/2019
Reported Date:	01/04/2016
Closure Date:	12/19/2019
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported

DOCS BACK YARD (Continued) **S111678850**

Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	01/04/2016
Case Start Date:	12/19/2019
Reference Number:	RN100535624
Project Manager:	KFROSS

ASBESTOS:

Name:	DOCS BACK YARD
Address:	1123 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	01/06/2017
Notification Number:	2016005074
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/15/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

DOCS BACK YARD (Continued) **S111678850**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	01/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOCS BACK YARD
Address:	1123 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	John Cannon
Violation:	Not reported
Complaint Date:	01/21/2017
Notification Number:	2016005074
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0

DOCS BACK YARD (Continued) **S111678850**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/15/2016
Certification Statement Phone:	512-256-1002
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	01/10/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GCC:

Name:	FORMER DOCS RESTAURANT
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	120860
Contamination Description:	WASTE OIL
Date Of Earliest Known Contamination Confirmation:	1/4/2016
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	Not reported
Section 5236:	Not reported
Type:	2019 GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

DOCS BACK YARD (Continued) **S111678850**

RDR:

RDR ID:	25173
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FORMER DOCS RESTAURANT
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/20/2019
Due Date:	10/19/2019
Tank Owner:	MUSIC OWNERS LLC
Contact Person:	ANDREW JOBLON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/16/2019
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORG RDR REC 12/1/17; NOD SENT 1/26/18; TECH RESP RECV'D VIA EMAIL 8/20/19;
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	27924
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FORMER DOCS RESTAURANT
Address:	1123 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/2019
Due Date:	2/8/2020
Tank Owner:	MUSIC OWNERS LLC
Contact Person:	ANDREW JOBLON
Report:	Suspected Release
Latest TCEQ Letter:	Other
Date of Latest TCEQ Letter:	12/19/2019
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	120860
Pre-Existing LPST Number:	Not reported
Comments:	LAD/FINAL COMBO LETTER SENT 12/19/2019;
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

1351 ESE < 1/8 0.020 mi. 103 ft. — **BURNETTE L B O**, **118 31ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013759629** / **N/A**

Actual: 601 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1922	BURNETTE L B O	AUTOMOBILE GARAGES
1929	BURNETTE GEORGE BATTERY	AUTOMOBILE GARAGES

AG1352 ESE < 1/8 0.020 mi. 104 ft. — **NORVELL MACHINERY CO INDRY EQUIP**, **6535 LAMAR BLVD N**, **TRAVIS (County), TX 78752** — **EDR Hist Cleaner** — **1013777865** / **N/A**

Site 14 of 14 in cluster AG

Actual: 713 ft. EDR Hist Cleaner

Focus Map: 6

Year:	Name:	Type:
1965	NORVELL MACHINERY CO	LAUNDRY SUPPLIES AND EQUIPMENT DEALERS
1970	NORVELL MACHINERY CO INDRY EQUI	LAUNDRY SUPPLIES AND EQUIPMENT DEALERS

BJ1353 WSW < 1/8 0.020 mi. 104 ft. — **MIDAS MUFFLER SHOP**, **2828 GUADALUPE ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013766921** / **N/A**

Site 8 of 8 in cluster BJ

Actual: 596 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1962	MIDAS MUFFLER SHOP	AUTOMOBILE REPAIRING
1965	MIDAS MUFFLER SHOP	AUTOMOBILE REPAIRING
1970	GUARDIAN TRANSMISSIONS	AUTOMOBILE REPAIRING
1970	NORTH AUSTIN MUFFLERS INC	Automotive Repair Shops, NEC

DY1354 NNE < 1/8 0.020 mi. 104 ft. — **SCHRAMM SINCLAIR**, **301 CONGRESS AVE**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013770340** / **N/A**

Site 5 of 11 in cluster DY

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	SCHRAMM SINCLAIR	GASOLINE STATIONS

DA1355 WNW < 1/8 0.020 mi. 105 ft. — **KORNFUEHRER SERV**, **704 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775768** / **N/A**

Site 14 of 25 in cluster DA

Actual: 473 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1958	KORNFUEHRER SERV	GASOLINE STATIONS

R1356 ESE < 1/8 0.020 mi. 105 ft. — **ACME DRY CLEANERS & LAUNDIRY NO**, **8901 LAMAR BLVD N**, **TRAVIS (County), TX 78753** — **EDR Hist Cleaner** — **1013782016** / **N/A**

Site 8 of 12 in cluster R

Actual: 661 ft. EDR Hist Cleaner

Focus Map: 6

Year:	Name:	Type:
1970	ACME DRY CLEANERS & LAUNDIRY NO	CLEANERS AND DYERS
1975	KWIK WASH LAUNDRY COIN OPERATED	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO 15	LAUNDRIES-SELF SERVE
1984	KWIK WASH COIN LAUNDRIES NO 15	LAUNDRIES-SELF SERVE
1990	KW 15 WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

DF1357 WNW < 1/8 0.020 mi. 106 ft. — **DRISKILL LNDRY**, **119 7TH E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013786888** / **N/A**

Site 8 of 25 in cluster DF

Actual: 497 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	DRISKILL LNDRY	LAUNDRIES
1958	DRISKILL LNDRY BR	LAUNDRIES

DF1358 WNW < 1/8 0.020 mi. 106 ft. — **MOTOR INN**, **118 7TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013763857** / **N/A**

Site 9 of 25 in cluster DF

Actual: 497 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	MOTOR INN	AUTOMOBILE GARAGES

DB1359 **HARRIS A L AUTO REPR** **EDR Hist Auto** **1013775569**
WNW **119 8TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 3 of 11 in cluster DB**

Actual:
502 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	HARRIS A L AUTO REPR	AUTOMOBILE REPAIRERS

IZ1360 **DURACLEAN ARTHOR CARPET** **EDR Hist Cleaner** **1013785579**
ESE **6901 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.020 mi.
106 ft. **Site 1 of 3 in cluster IZ**

Actual:
716 ft.
EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1975	DURACLEAN ARTHOR CARPET	CARPET AND RUG CLEANERS
1992	ALL REGIONAL CARPET CLEANING	Carpet And Upholstery Cleaning On Customer Premises
1993	ALL REGIONAL CARPET CLEANING	Carpet And Upholstery Cleaning On Customer Premises
2007	MASTER TOUCH CARPET CARE	Carpet And Upholstery Cleaning
2008	MASTER TOUCH CARPET CARE	Carpet And Upholstery Cleaning

IZ1361 **SPIGHT AUTOMOTIVE** **EDR Hist Auto** **1021673725**
ESE **6901 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.020 mi.
106 ft. **Site 2 of 3 in cluster IZ**

Actual:
716 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1998	BALLARD & SONS INC	Grocery Stores, NEC
1999	BALLARD & SONS INC	Grocery Stores, NEC
2000	BALLARD & SONS INC	Grocery Stores, NEC
2013	SPIGHT AUTOMOTIVE	Automotive Repair Shops, NEC

AO1362 **AUSTINS TINT CONNECTION** **TX UST** **U003040366**
ESE **5319 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.020 mi.
106 ft. **Site 6 of 14 in cluster AO**

Actual:
676 ft.
UST:

Focus Map:
8

Name:	AUSTINS TINT CONNECTION
Address:	5319 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511822
AI Number:	67897
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	624330482002118
Facility Exempt Status:	N
Records Off-Site:	No

AUSTINS TINT CONNECTION (Continued) **U003040366**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	L J BURKS,
Contact Organization Name:	AUSTINS TINT CONNECTION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124795051
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/29/1995
Signature Name/Title On Earliest Reg Form:	L J BURKS,OWNER
Application Received Date On Earliest Reg Form:	12/29/1995
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601112980
Owner Last Name:	BURKS
Owner First Name:	LJ
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	634330472002118
Additional ID:	624330482002118
AI Number:	67897
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1960
Tank Registration Date:	12/29/1995
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

Pipe Type:	Not reported
UST ID:	177823
Facility ID:	102620
Ai Number:	67897
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/01/1975
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

AUSTINS TINT CONNECTION (Continued) **U003040366**

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	176206
UST ID:	177823
AI Number:	67897
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26243
Cert ID:	33083
UST Comprt ID:	103315
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33082
UST Comprt ID:	103316
UST ID:	39212

AUSTINS TINT CONNECTION (Continued) **U003040366**

AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33081
UST Comprt ID:	103319
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33080
UST Comprt ID:	103318
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33079
UST Comprt ID:	103317
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	370227
UST Comprt ID:	1078085
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	299158
UST Comprt ID:	864501
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	283008
UST Comprt ID:	816452
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	350068
UST Comprt ID:	1017605
UST ID:	39212
AI Number:	67897

AUSTINS TINT CONNECTION (Continued) **U003040366**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	333212
UST Comprt ID:	966232
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	315459
UST Comprt ID:	913334
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	265066
UST Comprt ID:	763531
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	231971
UST Comprt ID:	666005
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33093
UST Comprt ID:	103305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33092
UST Comprt ID:	103306
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33091
UST Comprt ID:	103307
UST ID:	39212
AI Number:	67897
Tank ID:	3

AUSTINS TINT CONNECTION (Continued) **U003040366**

Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33090
UST Comprt ID:	103308
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33089
UST Comprt ID:	103309
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33088
UST Comprt ID:	103310
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33087
UST Comprt ID:	103311
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33086
UST Comprt ID:	103312
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33085
UST Comprt ID:	103313
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33084
UST Comprt ID:	103314
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A

AUSTINS TINT CONNECTION (Continued) **U003040366**

Self Cert ID:	26243
Cert ID:	248852
UST Comprt ID:	715305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A

Install Date:	01/01/1960
Tank Registration Date:	12/29/1995
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	177824
Facility ID:	102620
Ai Number:	67897
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/01/1975
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	176207
UST ID:	177824
AI Number:	67897
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AUSTINS TINT CONNECTION (Continued) **U003040366**

More Self Certification:

Self Cert ID:	26243
Cert ID:	33083
UST Comprt ID:	103315
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33082
UST Comprt ID:	103316
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33081
UST Comprt ID:	103319
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33080
UST Comprt ID:	103318
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33079
UST Comprt ID:	103317
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	370227
UST Comprt ID:	1078085
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	299158
UST Comprt ID:	864501
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A

AUSTINS TINT CONNECTION (Continued) **U003040366**

Self Cert ID:	26243
Cert ID:	283008
UST Comprt ID:	816452
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	350068
UST Comprt ID:	1017605
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	333212
UST Comprt ID:	966232
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	315459
UST Comprt ID:	913334
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	265066
UST Comprt ID:	763531
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	231971
UST Comprt ID:	666005
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33093
UST Comprt ID:	103305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243

AUSTINS TINT CONNECTION (Continued) **U003040366**

Cert ID:	33092
UST Comprt ID:	103306
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33091
UST Comprt ID:	103307
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33090
UST Comprt ID:	103308
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33089
UST Comprt ID:	103309
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33088
UST Comprt ID:	103310
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33087
UST Comprt ID:	103311
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33086
UST Comprt ID:	103312
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33085

AUSTINS TINT CONNECTION (Continued) **U003040366**

UST Comprt ID:	103313
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33084
UST Comprt ID:	103314
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	248852
UST Comprt ID:	715305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1960
Tank Registration Date:	12/29/1995
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	177825
Facility ID:	102620
Ai Number:	67897
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/01/1975
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	176208
UST ID:	177825
AI Number:	67897
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26243
Cert ID:	33083
UST Comprt ID:	103315
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33082
UST Comprt ID:	103316
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33081
UST Comprt ID:	103319
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33080
UST Comprt ID:	103318
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33079
UST Comprt ID:	103317
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	370227

AUSTINS TINT CONNECTION (Continued) **U003040366**

UST Comprt ID:	1078085
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	299158
UST Comprt ID:	864501
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	283008
UST Comprt ID:	816452
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	350068
UST Comprt ID:	1017605
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	333212
UST Comprt ID:	966232
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	315459
UST Comprt ID:	913334
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	265066
UST Comprt ID:	763531
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	231971
UST Comprt ID:	666005

AUSTINS TINT CONNECTION (Continued) **U003040366**

UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33093
UST Comprt ID:	103305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33092
UST Comprt ID:	103306
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33091
UST Comprt ID:	103307
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33090
UST Comprt ID:	103308
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33089
UST Comprt ID:	103309
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33088
UST Comprt ID:	103310
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33087
UST Comprt ID:	103311
UST ID:	39212

AUSTINS TINT CONNECTION (Continued) **U003040366**

AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33086
UST Comprt ID:	103312
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33085
UST Comprt ID:	103313
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33084
UST Comprt ID:	103314
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	248852
UST Comprt ID:	715305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1960
Tank Registration Date:	12/29/1995
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	177826
Facility ID:	102620
Ai Number:	67897
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/16/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	176209
UST ID:	177826
AI Number:	67897
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26243
Cert ID:	33083
UST Comprt ID:	103315
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33082
UST Comprt ID:	103316
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33081
UST Comprt ID:	103319
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33080
UST Comprt ID:	103318
UST ID:	39212

AUSTINS TINT CONNECTION (Continued) **U003040366**

AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33079
UST Comprt ID:	103317
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	370227
UST Comprt ID:	1078085
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	299158
UST Comprt ID:	864501
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	283008
UST Comprt ID:	816452
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	350068
UST Comprt ID:	1017605
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	333212
UST Comprt ID:	966232
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	315459
UST Comprt ID:	913334
UST ID:	39212
AI Number:	67897

AUSTINS TINT CONNECTION (Continued) **U003040366**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	265066
UST Comprt ID:	763531
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	231971
UST Comprt ID:	666005
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33093
UST Comprt ID:	103305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33092
UST Comprt ID:	103306
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33091
UST Comprt ID:	103307
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33090
UST Comprt ID:	103308
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33089
UST Comprt ID:	103309
UST ID:	39212
AI Number:	67897
Tank ID:	3

AUSTINS TINT CONNECTION (Continued) **U003040366**

Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33088
UST Comprt ID:	103310
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33087
UST Comprt ID:	103311
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33086
UST Comprt ID:	103312
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33085
UST Comprt ID:	103313
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33084
UST Comprt ID:	103314
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	248852
UST Comprt ID:	715305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1960
Tank Registration Date:	12/29/1995
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N

AUSTINS TINT CONNECTION (Continued) **U003040366**

Pipe Type:	Not reported
UST ID:	177827
Facility ID:	102620
Ai Number:	67897
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/16/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

AUSTINS TINT CONNECTION (Continued) **U003040366**

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	176210
UST ID:	177827
AI Number:	67897
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26243
Cert ID:	33083
UST Comprt ID:	103315
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33082
UST Comprt ID:	103316
UST ID:	39212

AUSTINS TINT CONNECTION (Continued) **U003040366**

AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33081
UST Comprt ID:	103319
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33080
UST Comprt ID:	103318
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33079
UST Comprt ID:	103317
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	370227
UST Comprt ID:	1078085
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	299158
UST Comprt ID:	864501
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	283008
UST Comprt ID:	816452
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	350068
UST Comprt ID:	1017605
UST ID:	39212
AI Number:	67897

AUSTINS TINT CONNECTION (Continued) **U003040366**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	333212
UST Comprt ID:	966232
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	315459
UST Comprt ID:	913334
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	265066
UST Comprt ID:	763531
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	231971
UST Comprt ID:	666005
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33093
UST Comprt ID:	103305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33092
UST Comprt ID:	103306
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33091
UST Comprt ID:	103307
UST ID:	39212
AI Number:	67897
Tank ID:	3

AUSTINS TINT CONNECTION (Continued) **U003040366**

Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33090
UST Comprt ID:	103308
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33089
UST Comprt ID:	103309
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33088
UST Comprt ID:	103310
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33087
UST Comprt ID:	103311
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33086
UST Comprt ID:	103312
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33085
UST Comprt ID:	103313
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26243
Cert ID:	33084
UST Comprt ID:	103314
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A

AUSTINS TINT CONNECTION (Continued) **U003040366**

Self Cert ID:	26243
Cert ID:	248852
UST Comprt ID:	715305
UST ID:	39212
AI Number:	67897
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	BURKS L J
Contact Mailing Address (Delivery):	3909 MYRICK DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78731 1458
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	102620
Additional ID:	624330482002118
Princ ID:	634330472002118
AI Number:	67897
Facility Name:	AUSTINS TINT CONNECTION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	LJ BURKS/

AO1363 **AUSTIN TINT CONNECTION** **TX HIST UST** **S128729102**
ESE **5319 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 7 of 14 in cluster AO**

Actual:
676 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	AUSTIN TINT CONNECTION
Address:	5319 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0654
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AO1364 **HUMBLE PRODUCTS SERVICE** **EDR Hist Auto** **1013753615**
ESE **5319 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 8 of 14 in cluster AO**

Actual:
676 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1965	HUMBLE PRODUCTS SERVICE	GASOLINE STATIONS
1970	TAYLORS DOC ENCO SERV ST	GASOLINE STATIONS

HUMBLE PRODUCTS SERVICE (Continued) **1013753615**

1984	CERTIFIED AUTOMOTIVE	AUTOMOBILE REPAIRING
1986	CERTIFIED AUTOMOTIVE	General Automotive Repair Shops
1997	KHOURYS AUTOMOTIVE REPAIR	General Automotive Repair Shops
1998	KHOURYS AUTOMOTIVE REPAIR	General Automotive Repair Shops
1999	KHOURYS AUTOMOTIVE REPAIR	General Automotive Repair Shops
2002	KHOURYS AUTOMOTIVE REPAIR	General Automotive Repair Shops

---

AO1365 **HUMBLE OIL & REFINING CO.** **TX HIST UST** **S128729382**
ESE **5319 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 9 of 14 in cluster AO**

Actual:
676 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	HUMBLE OIL & REFINING CO.
Address:	5319 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0701
HID UST:	701
Inspection:	02/26/2009
Due:	02/26/2012

AO1366 **PHILLIPS PETROLEUM COMPANY** **RCRA NonGen / NLR** **1000836427**
ESE **5301 N LAMAR BLVD** **FINDS** **TXD988075834**
< 1/8 **AUSTIN, TX 78751** **ECHO**
0.020 mi.
106 ft. **Site 10 of 14 in cluster AO**

Actual:
675 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20191017
Handler Name:	Phillips Petroleum Station 2728
Handler Address:	5301 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78751-1822
EPA ID:	TXD988075834
Contact Name:	THOMAS KOSEL
Contact Address:	PO BOX 2400
Contact City,State,Zip:	BARTLESVILLE, OK 74005-2400
Contact Telephone:	918-661-7439
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 2400
Mailing City,State,Zip:	BARTLESVILLE, OK 74005-2400
Owner Name:	Phillips Petroleum Company
Owner Type:	Private
Operator Name:	Phillips Petroleum Company

PHILLIPS PETROLEUM COMPANY (Continued) **1000836427**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20191030
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PHILLIPS PETROLEUM COMPANY

PHILLIPS PETROLEUM COMPANY (Continued) **1000836427**

Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2400
Owner/Operator City,State,Zip: BARTLESVILLE, OK 74005
Owner/Operator Telephone: 918-661-7439
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PHILLIPS PETROLEUM COMPANY
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2400
Owner/Operator City,State,Zip: BARTLESVILLE, OK 74005-2400
Owner/Operator Telephone: 918-661-7439
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PHILLIPS PETROLEUM CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2400
Owner/Operator City,State,Zip: BARTLESVILLE, OK 74005
Owner/Operator Telephone: 918-661-7439
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PHILLIPS PETROLEUM COMPANY
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2400
Owner/Operator City,State,Zip: BARTLESVILLE, OK 74005-2400
Owner/Operator Telephone: 918-661-7439
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PHILLIPS PETROLEUM COMPANY
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2400
Owner/Operator City,State,Zip: BARTLESVILLE, OK 74005
Owner/Operator Telephone: 918-661-7439
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

PHILLIPS PETROLEUM COMPANY (Continued) **1000836427**

Historic Generators:

Receive Date:	19920901
Handler Name:	PHILLIPS PETROLEUM CO SS#27288
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010214
Handler Name:	PHILLIPS PETROLEUM COMPANY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20191017
Handler Name:	PHILLIPS PETROLEUM STATION 2728
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	445299
NAICS Description:	ALL OTHER SPECIALTY FOOD STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110005152556

PHILLIPS PETROLEUM COMPANY (Continued) **1000836427**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836427
Registry ID:	110005152556
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005152556
Name:	PHILLIPS PETROLEUM COMPANY
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751

AO1367 **PHILLIPS PETROLEUM STATION 2728** **TX HIST UST** **S105168987**
ESE **5301 N LAMAR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.020 mi.
106 ft. **Site 11 of 14 in cluster AO**

Actual:
675 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	TEXAS OIL COMPANY
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0475
HID UST:	475
Inspection:	Not reported
Due:	06/01/2012

Ind. Haz Waste:

Name:	PHILLIPS PETROLEUM STATION 2728
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	80689
Registration Initial Notification Date:	07/15/1992
Registration Last Amendment Date:	10/17/2019
EPA Identification:	TXD988075834
Primary NAICS Code:	445299
Status Change Date:	19920715
Land Type:	PRIVATE
Description of Facility Site Location:	5301 N Lamar Blvd, Austin, TX

PHILLIPS PETROLEUM STATION 2728 (Continued) **S105168987**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CONOCOPHILLIPS COMPANY
Contact Name:	THOMAS H KOSEL
Contact Telephone Number:	918-6617439
Mailing Address:	PO BOX 2400
Mailing Address2:	Not reported
Mailing City,State,Zip:	BARTLESVILLE, OK 740052400
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	35489
Site Owner Tax ID:	730400345
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CONOCOPHILLIPS COMPANY
Operator Address:	PO BOX 2400
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	BARTLESVILLE, OK 74005
Operator Country:	UNITED STA
Operator Telephone:	1-918-6617439
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17304003456
Operator Bankruptcy Code:	Not reported

PHILLIPS PETROLEUM STATION 2728 (Continued) **S105168987**

Ind. Haz Waste:

Owner Name:	CONOCOPHILLIPS COMPANY
Owner Mailing Address:	PO BOX 2400
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	BARTLESVILLE, OK 74005
Owner Country:	UNITED STA
Owner Telephone:	1-918-6617439
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17304003456
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	miscellaneous storage containers
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19920715
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2400
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BARTLESVILLE, OK 74005
Contact Phone:	1-918-6617439
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2400

PHILLIPS PETROLEUM STATION 2728 (Continued) **S105168987**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BARTLESVILLE, OK 74005
Contact Phone:	1-918-6617439
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	THOMAS KOSEL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2400
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BARTLESVILLE, OK 74005
Contact Phone:	1-918-6617439
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	108628
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Removal of water from underground storage tanks containing gasoline or diesel.
Standard Industrial Code:	55410
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	447110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

AO1368 **PHILLIPS 66 #27288** **TX RDR** **S127533719**
ESE **5301 NORTH LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 12 of 14 in cluster AO**

Actual:
675 ft.

Focus Map:
8

RDR:

RDR ID:	6488
Facility ID:	45524
RN:	Not reported
CN:	Not reported
Name:	PHILLIPS 66 #27288
Address:	5301 NORTH LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	PHILLIPS 66
Contact Person:	Not reported
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/11/1996
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 6
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/11/1996
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AO1369 **PRET MANGER** **TX UST** **U003421933**
ESE **5301 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78751** **TX ASBESTOS**
0.020 mi. **TX Financial Assurance**
106 ft. **Site 13 of 14 in cluster AO** **TX RDR**

Actual:
675 ft.

Focus Map:
8

UST:

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511822
AI Number:	45524
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	548661292002205
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	JOSEPH RAJA,

PRET MANGER (Continued) **U003421933**

Contact Organization Name:	PRET MANGER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124548600
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/18/2021
Signature Name/Title On Earliest Reg Form:	SAM ORTEGA,MANAGER
Application Received Date On Earliest Reg Form:	10/18/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	786528372011242
Additional ID:	548661292002205
Ai Number:	45524
Operator CN:	CN603952755
Operator Name:	TEXXON PETROCHEMICALS LLC
Operator Effective Begin Date:	06/01/2011
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	JOSEPH RAJA/
Contact Organization Name:	TEXXON PETROCHEMICALS LLC
Contact Mailing Address (Delivery):	5301 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78751-1822
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4548600
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603952755
Owner Last Name:	TEXXON PETROCHEMICALS LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	5301 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78751
Contact Mailing Zip5:	1822
Contact Phone Number/Ext:	1 512 4548600/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

PRET MANGER (Continued) **U003421933**

Contact Address Deliverable:	Not reported
Princ ID:	786528372011242
Additional ID:	548661292002205
AI Number:	45524
Owner Effective Begin Date:	06/01/2011
State Tax ID:	32043832784
Contact Role:	OWNOPRCON
Contact Name/Title:	JOSEPH RAJA/
Contact Organization Name:	TEXXON PETROCHEMICALS LLC

Self Certification:

Self Cert ID:	40958
Cert ID:	379711
AI Number:	45524
Self Certification Date:	10/27/2022
Signature Name/Title:	CARLOS ORTEGA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	362093
AI Number:	45524
Self Certification Date:	10/18/2021
Signature Name/Title:	SAM ORTEGA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	344893
AI Number:	45524
Self Certification Date:	09/16/2020
Signature Name/Title:	SAM ORTEGA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	326544
AI Number:	45524
Self Certification Date:	09/17/2019
Signature Name/Title:	SAM ORTEGA MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	310457
AI Number:	45524
Self Certification Date:	08/10/2018
Signature Name/Title:	SAM ORTEGA MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	293856
AI Number:	45524
Self Certification Date:	09/14/2017
Signature Name/Title:	SAM ORTEED MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	278342
AI Number:	45524
Self Certification Date:	10/07/2016
Signature Name/Title:	SAM ORTEGA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	260870
AI Number:	45524
Self Certification Date:	10/09/2015
Signature Name/Title:	SAM ORTEGA MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	244614
AI Number:	45524
Self Certification Date:	11/03/2014
Signature Name/Title:	SAM ORTEGA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	227103
AI Number:	45524
Self Certification Date:	09/06/2013
Signature Name/Title:	SARAVANA RAGHAVAN CEO
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	40958
Cert ID:	9191
AI Number:	45524
Self Certification Date:	07/20/2012
Signature Name/Title:	JOSEPH RAJA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9190
AI Number:	45524
Self Certification Date:	07/19/2012
Signature Name/Title:	JOSEH RAJA OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9189
AI Number:	45524
Self Certification Date:	08/22/2011
Signature Name/Title:	JOSEPH RAJA OPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9188
AI Number:	45524
Self Certification Date:	06/16/2010
Signature Name/Title:	IRAJ NOURI PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9187
AI Number:	45524
Self Certification Date:	06/16/2009
Signature Name/Title:	IRAJ NOURI PRES
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9186
AI Number:	45524
Self Certification Date:	06/04/2008
Signature Name/Title:	RICHARD CATALAN ASSET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9185
AI Number:	45524
Self Certification Date:	06/03/2008
Signature Name/Title:	RICHARD CATALAN ASSET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9184
AI Number:	45524
Self Certification Date:	06/01/2006
Signature Name/Title:	MANOHAR S JADHAV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9183
AI Number:	45524
Self Certification Date:	10/13/2005
Signature Name/Title:	JOHN FARREN SVP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9182
AI Number:	45524
Self Certification Date:	08/27/2004
Signature Name/Title:	NANCY WINFIELD ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	40958
Cert ID:	9870
AI Number:	45524
Self Certification Date:	10/07/2003
Signature Name/Title:	JENNIFER SIEGRIST FOR JEFF DEGROT VP OPS
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9869
AI Number:	45524
Self Certification Date:	05/11/2002
Signature Name/Title:	JEFF DEGROOT VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9868
AI Number:	45524
Self Certification Date:	05/10/2002
Signature Name/Title:	JEFF DEGROOT VP
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	40958
Cert ID:	9867
AI Number:	45524
Self Certification Date:	09/26/2000
Signature Name/Title:	BRENT MARSHALL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y

PRET MANGER (Continued) **U003421933**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	02/09/1988
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119224
Facility ID:	40958
Ai Number:	45524
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

PRET MANGER (Continued) **U003421933**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	8752
UST ID:	119224
AI Number:	45524
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

PRET MANGER (Continued) **U003421933**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 17707
Cert ID: 122866
UST Comprt ID: 356633
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122865
UST Comprt ID: 356636
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122864
UST Comprt ID: 356635
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122863
UST Comprt ID: 356634
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122872
UST Comprt ID: 356627
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122871
UST Comprt ID: 356628
UST ID: 111678
AI Number: 45524
Tank ID: 2A
Compartment ID: A

Self Cert ID: 17707
Cert ID: 122870
UST Comprt ID: 356629
UST ID: 111678
AI Number: 45524

PRET MANGER (Continued) **U003421933**

Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122869
UST Comprt ID:	356630
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122868
UST Comprt ID:	356631
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122867
UST Comprt ID:	356632
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Install Date:	01/01/1988
Tank Registration Date:	02/09/1988
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119225
Facility ID:	40958
Ai Number:	45524
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

PRET MANGER (Continued) **U003421933**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	8753
UST ID:	119225
AI Number:	45524
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y

PRET MANGER (Continued) **U003421933**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17707
Cert ID:	122866
UST Comprt ID:	356633
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122865
UST Comprt ID:	356636
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122864
UST Comprt ID:	356635
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122863
UST Comprt ID:	356634
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122872
UST Comprt ID:	356627
UST ID:	111678
AI Number:	45524

PRET MANGER (Continued) **U003421933**

Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122871
UST Comprt ID:	356628
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122870
UST Comprt ID:	356629
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122869
UST Comprt ID:	356630
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122868
UST Comprt ID:	356631
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122867
UST Comprt ID:	356632
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Install Date:	01/01/1988
Tank Registration Date:	02/09/1988
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119226
Facility ID:	40958
Ai Number:	45524
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1988

PRET MANGER (Continued) **U003421933**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	8754
UST ID:	119226
AI Number:	45524
Compartment ID:	A
Substance Stored1:	GASOLINE

PRET MANGER (Continued) **U003421933**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17707
Cert ID:	122866
UST Comprt ID:	356633
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122865
UST Comprt ID:	356636
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122864
UST Comprt ID:	356635
UST ID:	111678
AI Number:	45524

PRET MANGER (Continued) **U003421933**

Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122863
UST Comprt ID:	356634
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122872
UST Comprt ID:	356627
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122871
UST Comprt ID:	356628
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122870
UST Comprt ID:	356629
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122869
UST Comprt ID:	356630
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122868
UST Comprt ID:	356631
UST ID:	111678
AI Number:	45524
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17707
Cert ID:	122867
UST Comprt ID:	356632
UST ID:	111678
AI Number:	45524
Tank ID:	2A

PRET MANGER (Continued) **U003421933**

Compartment ID: A

Construction Notification:

NOC ID:	1020
Facility ID:	40958
AI Number:	45524
Application Received Date:	10/04/2005
Scheduled Construction Date:	11/03/2005
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M51007001
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	1594
General Desc Of Prop Construct:	Not reported

NOC ID:	1019
Facility ID:	40958
AI Number:	45524
Application Received Date:	05/12/2006
Scheduled Construction Date:	06/11/2006
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60512004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported

PRET MANGER (Continued) **U003421933**

Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 1594
General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 1127
UST ID: Not reported
NOC ID: 1020
AI Number: 45524
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000257
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 1126
UST ID: Not reported
NOC ID: 1019
AI Number: 45524
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000257
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Facility Billing Contacts:
Contact Organization Name: TEXXON PETROCHEMICALS LLC

PRET MANGER (Continued) **U003421933**

Contact Mailing Address (Delivery):	5301 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78751 1822
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	40958
Additional ID:	548661292002205
Princ ID:	786528372011242
AI Number:	45524
Facility Name:	PRET MANGER
AR Number:	73640
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	JOSEPH RAJA/

HIST UST AUSTIN:

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3016
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	05/30/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/03/2013
Date Routed by Supervisor:	06/03/2013
Date Routed to PSQA:	06/06/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

PRET MANGER (Continued) **U003421933**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	08/07/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1

PRET MANGER (Continued) **U003421933**

Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/11/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

PRET MANGER (Continued) **U003421933**

TX Financial Assurance 2:

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	276897
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2022
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	Not reported
Policy Number:	STP419474
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	259231
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2021
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-415401
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	239590
AI:	45524
Mechanism Type Other:	Not reported

PRET MANGER (Continued) **U003421933**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2020
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-410127
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	221421
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2019
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-128618
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	203880
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2018
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS

PRET MANGER (Continued) **U003421933**

Issuer Phone:	1 973 4906600
Policy Number:	STP-123778
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	186975
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2017
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-118988
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/12/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	170615
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2016
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-113898
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD

PRET MANGER (Continued) **U003421933**

City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	152430
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2015
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP109012
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	135830
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2014
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 800 0
Policy Number:	STP-104948
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	116744
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

PRET MANGER (Continued) **U003421933**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2013
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	1 281 5759900
Policy Number:	179E067211301
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/12/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	873
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/27/2012
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	1 0 0
Policy Number:	179E04916-12-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/27/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	21544
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/27/2011
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	COMMERCE & INDUSTRY INS CO
Issuer Phone:	1 212 7707000
Policy Number:	017778703
Coverage Amount:	1000000

PRET MANGER (Continued) **U003421933**

Coverage Expiration Date:	06/27/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	21545
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/24/2008
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 401 8280675
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	06/24/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	40958
Finass ID:	21546
AI:	45524
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	10/18/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	24139
Facility ID:	45224
RN:	Not reported
CN:	Not reported

PRET MANGER (Continued) **U003421933**

Name:	PRET MANGER
Address:	5301 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/28/2016
Due Date:	12/27/2016
Tank Owner:	TEXXON PETROCHEMICALS
Contact Person:	SARAVANA RAGHAVAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/21/2016
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AO1370 **AMERICAN MUFFLER SHOP** **EDR Hist Auto** **1013753033**
ESE **5301 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.020 mi.
106 ft. **Site 14 of 14 in cluster AO**

Actual:
675 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1953	TEXACO SERV STA	GASOLINE STATIONS
1958	BECKETT TEXACO	GASOLINE STATIONS
1962	SALINAS J E TEXACO	GASOLINE STATIONS
1965	GRELLE E TEXACO STATION	GASOLINE STATIONS
1969	GRELLE EDGAR E	Gasoline Service Stations
1970	PURYERRR TEXACO	GASOLINE STATIONS
1970	GRELLE EDGAR E	Gasoline Service Stations
1972	ANDERSON CARL J JR	Gasoline Service Stations
1973	ANDERSON CARL J JR	Gasoline Service Stations
1977	AMERICAN MUFFLER SHOP	Automotive Repair Shops, NEC
1978	AMERICAN MUFFLER SHOP	Automotive Repair Shops, NEC
1979	AMERICAN MUFFLER SHOP	Auto And Home Supply Stores
1980	AMERICAN MUFFLER SHOP	AUTOMOBILE REPAIRING
1980	AMERICAN MUFFLER SHOP	Auto And Home Supply Stores
1985	AMERICAN MUFFLER & BRAKE SHOP	Automotive Repair Shops, NEC
1986	AMERICAN MUFFLER & BRAKE SHOP	Automotive Repair Shops, NEC
1987	AMERICAN MUFFLER	Automotive Repair Shops, NEC
1990	PHLLLIPS SIXTY SIX NO 27288 GAS	GASOLINE STATIONS
1994	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
1995	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
1996	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
1997	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
1998	PHILLIPS PETROLEUM COMPANY	Gasoline Service Stations
2001	OMKAR FOOD PLAZA	Grocery Stores
2002	OMKAR FOOD PLAZA	Grocery Stores

AMERICAN MUFFLER SHOP (Continued) **1013753033**

2003	OMKAR FOOD PLAZA	Grocery Stores
2004	RUSHI INC	Grocery Stores
2005	RUSHI INC	Grocery Stores
2006	RUSHI INC	Grocery Stores
2007	OMKAR FOOD PLAZA	Grocery Stores
2008	OMKAR FOOD PLAZA	Grocery Stores
2010	OMKAR FOOD PLAZA	Grocery Stores

IW1371 **TENNISON PROPERTIES INC** **EDR Hist Auto** **1021658638**
NNE **19TH GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.020 mi.
106 ft. **Site 2 of 2 in cluster IW**

Actual:
452 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1997	TENNISON PROPERTIES INC	Convenience Stores

FU1372 **MRS. JAS. R. HAMILTON** **TX HIST UST** **S128729465**
SE **2401 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 4 of 13 in cluster FU**

Actual:
604 ft.

HIST UST AUSTIN:

Focus Map:
14

Name:	MRS. JAS. R. HAMILTON
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0898
HID UST:	898
Inspection:	Not reported
Due:	06/01/2012

FU1373 **HARLESS MOBIL** **TX HIST UST** **S128728873**
SE **2401 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
106 ft. **Site 5 of 13 in cluster FU**

Actual:
604 ft.

HIST UST AUSTIN:

Focus Map:
14

Name:	HARLESS MOBIL
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0040
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FU1374 **MOBIL SS 12 D93** **TX LPST** **U001252746**
SE **2401 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
106 ft. **Site 6 of 13 in cluster FU**

Actual:
604 ft.

Focus Map:
14

LPST:

Name:	FORMER SS 12 D93
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 75240
Facility ID:	0017726
LPST Id:	096497
Facility Location:	2401 S CONGRESS AVE & OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/30/1990
Entered Date:	08/20/1990
Reported Date:	05/30/1990
Closure Date:	05/14/1996
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	EAE
Responsible Party Name:	Not reported
Responsible Party Contact:	F BRUCE MORLOCK
Responsible Party Address:	4200 SINGLETON BLVD
Responsible Party City,St,Zip:	DALLAS, TX 75212 3433
Responsible Party Telephone:	214/905-0506
Reported Date:	05/30/1990
Case Start Date:	05/14/1996
Reference Number:	RN101494698
Project Manager:	EEKPO

Name:	MOBIL SS 12D93
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 75240
Facility ID:	0017726
LPST Id:	091811
Facility Location:	2401 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/18/1988
Entered Date:	04/18/1988
Reported Date:	04/18/1988
Closure Date:	07/01/1988
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	C L PEARSON
Responsible Party Address:	3225 GALLOWS RD
Responsible Party City,St,Zip:	FAIRFAX, VA 22037

MOBIL SS 12 D93 (Continued) **U001252746**

Responsible Party Telephone:	703/849-4620
Reported Date:	04/18/1988
Case Start Date:	07/01/1988
Reference Number:	RN101494698
Project Manager:	HWELCH

UST:

Name:	MOBIL SS 12 D93
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787045511
AI Number:	17726
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	308662722002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	75240
Contact Name/Title:	R W HARLESS,DEALER
Contact Organization Name:	MOBIL SS 12 D93
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124442694
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/21/1986
Signature Name/Title On Earliest Reg Form:	T B NEWMAN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600920748
Owner Last Name:	EXXONMOBIL OIL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

MOBIL SS 12 D93 (Continued) **U001252746**

Contact Address Deliverable:	Not reported
Princ ID:	949579912002079
Additional ID:	308662722002053
AI Number:	17726
Owner Effective Begin Date:	09/01/1988
State Tax ID:	11354015700
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	06/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	45647
Facility ID:	78961
Ai Number:	17726
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/21/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

MOBIL SS 12 D93 (Continued) **U001252746**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	111751
UST ID:	45647
AI Number:	17726
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

MOBIL SS 12 D93 (Continued) **U001252746**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	45650
Facility ID:	78961
Ai Number:	17726
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/21/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

MOBIL SS 12 D93 (Continued) **U001252746**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	111754
UST ID:	45650
AI Number:	17726
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y

MOBIL SS 12 D93 (Continued) **U001252746**

Tank Doublewall:	N
Pipe Type:	P
UST ID:	45649
Facility ID:	78961
Ai Number:	17726
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/21/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

MOBIL SS 12 D93 (Continued) **U001252746**

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	111753
UST ID:	45649
AI Number:	17726
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	45648
Facility ID:	78961
Ai Number:	17726
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/21/1989

MOBIL SS 12 D93 (Continued) **U001252746**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	111752
UST ID:	45648
AI Number:	17726
Compartment ID:	A
Substance Stored1:	GASOLINE

MOBIL SS 12 D93 (Continued) **U001252746**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MOBIL OIL CORPORATION
Contact Mailing Address (Delivery):	7300 W FRIENDLY AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27410 6232
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	78961
Additional ID:	308662722002053
Princ ID:	949579912002079
AI Number:	17726
Facility Name:	MOBIL SS 12 D93
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GILBARCO VEEDER-ROOT/

FU1375 **CHARLES DIRK TALBOT** **EDR Hist Auto** **1020597095**
SE **2401 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
106 ft. **Site 7 of 13 in cluster FU**

Actual:
604 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1969	TWIN OAKS MOBIL	Gasoline Service Stations
1971	TWIN OAK MOBIL	Gasoline Service Stations
1971	TWIN OAKS MOBILE SERVICE	Gasoline Service Stations
1972	TWIN OAK MOBIL	Gasoline Service Stations
1972	TWIN OAKS MOBILE SERVICE	Gasoline Service Stations
1973	RINEYS SERVICE CENTER	Gasoline Service Stations
1973	TWIN OAK MOBIL	Gasoline Service Stations
1974	TWIN OAK MOBIL	Gasoline Service Stations
1974	RINEYS SERVICE CENTER	Gasoline Service Stations
1975	RINEYS SERVICE STATION	Gasoline Service Stations
1976	RINEYS SERVICE STATION	Gasoline Service Stations
1977	RINEYS SERVICE STATION	Gasoline Service Stations
1978	RINEYS SERVICE STATION	Gasoline Service Stations
1978	STARR KEALHOFER TIRE & SUP CO*	Auto And Home Supply Stores
1979	RINEYS SERVICE STATION	Gasoline Service Stations
1979	STARR KEALHOFER TIRE & SUP CO*	Auto And Home Supply Stores
1980	STARR KEALHOFER TIRE & SUP CO*	Gasoline Service Stations
1982	STARR KEALHOFER TIRE & SUP CO*	Gasoline Service Stations
1983	STARR KEALHOFER TIRE & SUP CO*	Gasoline Service Stations
1987	ULTRA PRIDE PRODUCTS INC	Gas And Other Services Combined
1989	CHARLES DIRK TALBOT	Gasoline Service Stations, NEC
1992	CHARLES DIRK TALBOT	Gasoline Service Stations, NEC
1993	CHARLES DIRK TALBOT	Gasoline Service Stations, NEC

FU1376 **MOBIL OIL CORPORATION** **RCRA NonGen / NLR** **1000653998**
SE **2401 S CONGRESS AVE** **FINDS** **TXD988038428**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.020 mi.
106 ft. **Site 8 of 13 in cluster FU**

Actual:
604 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Mobil Oil Corporation
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD988038428
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	GALLOWS RD
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Telephone:	703-846-3000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx

MOBIL OIL CORPORATION (Continued) **1000653998**

State District:	11
Mailing Address:	GALLOWS RD
Mailing City,State,Zip:	FAIRFAX, VA 22037
Owner Name:	Mobil Oil Corporation
Owner Type:	Private
Operator Name:	Mobil Oil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008

MOBIL OIL CORPORATION (Continued) **1000653998**

Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-846-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-846-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORP MKTG ENVIRON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-846-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD

MOBIL OIL CORPORATION (Continued) **1000653998**

Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: 703-846-3000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19910501
Handler Name: MOBIL OIL CORP SS# D93
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: MOBIL OIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: MOBIL OIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940301
Handler Name: MOBIL OIL CORP.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

MOBIL OIL CORPORATION (Continued) **1000653998**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005136227

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Registry ID: 110070165436

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000653998
Registry ID: 110005136227
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005136227
Name: MOBIL OIL CORPORATION
Address: 2401 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78704

FU1377 **MOBIL OIL** **TX Ind. Haz Waste** **S103610801**
SE **2401 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.020 mi.
106 ft. **Site 9 of 13 in cluster FU**

Actual:
604 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	MOBIL OIL
Address:	2401 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	80648
Registration Initial Notification Date:	07/28/1992
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988038428
Primary NAICS Code:	Not reported
Status Change Date:	19920728
Land Type:	PRIVATE
Description of Facility Site Location:	2401 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXONMOBIL OIL CORPORATION
Contact Name:	ENVIRONMENTAL MANAGER
Contact Telephone Number:	703-8463000
Mailing Address:	3225 GALLOWS RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	FAIRFAX, VA 220370002
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	35439
Site Owner Tax ID:	135401570
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

MOBIL OIL (Continued) **S103610801**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXONMOBIL OIL CORPORATION
Operator Address:	3225 GALLOWS RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	FAIRFAX, VA 22037
Operator Country:	UNITED STA
Operator Telephone:	1-703-8463000
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354015700
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXONMOBIL OIL CORPORATION
Owner Mailing Address:	3225 GALLOWS RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	FAIRFAX, VA 22037
Owner Country:	UNITED STA
Owner Telephone:	1-703-8463000
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354015700
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19920728
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

MOBIL OIL (Continued) **S103610801**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8463000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8463000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ENVIRONMENTAL MANAGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8463000
Contact Fax:	Not reported
Contact Email:	Not reported

1378 **FIRE STATION 3** **TX UST** **U003566257**
ENE **201 W 30TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.020 mi.
106 ft.

Actual:
556 ft.

Focus Map:
11

UST:

Name:	FIRE STATION 3
Address:	201 W 30TH ST
City,State,Zip:	AUSTIN, TX 787052905
AI Number:	18163
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	INACTIVE
Additional ID:	246804042002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS

FIRE STATION 3 (Continued) **U003566257**

Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	C E MCCAMANT,TECH.
Contact Organization Name:	FIRE STATION 3
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129281492
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	J A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	246804042002138
AI Number:	18163
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46975
Facility ID:	37567
Ai Number:	18163
Tank Id:	1

FIRE STATION 3 (Continued) **U003566257**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	304
UST ID:	46975
AI Number:	18163

FIRE STATION 3 (Continued) **U003566257**

Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7028
Cert ID:	160540
UST Comprt ID:	472530
UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160541
UST Comprt ID:	472531
UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160543
UST Comprt ID:	472529

FIRE STATION 3 (Continued) **U003566257**

UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160542
UST Comprt ID:	472532
UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160545
UST Comprt ID:	472527
UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160544
UST Comprt ID:	472528
UST ID:	154568
AI Number:	18163
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37567
Additional ID:	246804042002138
Princ ID:	840354562001227
AI Number:	18163
Facility Name:	FIRE STATION 3
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

DI1379 ESE < 1/8 0.020 mi. 107 ft. — **JACK STABLEFORD PONTIAC CO.** — **TX HIST UST** — **S111678699** / **N/A**

311 W 5TH ST
AUSTIN, TX

Site 3 of 9 in cluster DI

Actual: 488 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	JACK STABLEFORD PONTIAC CO.
Address:	311 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0418
HID UST:	418
Inspection:	03/20/2009
Due:	03/20/2012

AQ1380 ESE < 1/8 0.020 mi. 108 ft. — **JOHN H WINTERS** — **TX UST** — **U003921132** / **TX HIST UST** — **N/A**

701 W 51ST ST
AUSTIN, TX 78751

Site 4 of 9 in cluster AQ

Actual: 665 ft.
Focus Map: 8

UST:

Name:	JOHN H WINTERS
Address:	701 W 51ST ST
City,State,Zip:	AUSTIN, TX 787512312
AI Number:	76046
Facility Type:	FLEET REFUELING
Facility Begin Date:	06/01/1983
Facility Status:	ACTIVE
Additional ID:	518333592003344
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	TERRY SOUTHALL,
Contact Organization Name:	JOHN H WINTERS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124633600
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/11/2003
Signature Name/Title On Earliest Reg Form:	MEL BULLOCK,CONTROLS/OPS MGR
Application Received Date On Earliest Reg Form:	09/15/2003
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	167546612009246
Additional ID:	518333592003344

JOHN H WINTERS (Continued) **U003921132**

Ai Number:	76046
Operator CN:	CN603527441
Operator Name:	TEXAS FACILITIES COMMISSION
Operator Effective Begin Date:	09/11/2003
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78711-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9000333
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603527441
Owner Last Name:	TEXAS FACILITIES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78711
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 9000333/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	167546612009246
Additional ID:	518333592003344
AI Number:	76046
Owner Effective Begin Date:	09/11/2003
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION

Self Certification:

Self Cert ID:	116668
Cert ID:	208180
AI Number:	76046
Self Certification Date:	09/11/2003
Signature Name/Title:	MEL BULLOCK
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

JOHN H WINTERS (Continued) **U003921132**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/01/1983
Tank Registration Date:	09/15/2003
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	202084
Facility ID:	116668
Ai Number:	76046
Tank Id:	1
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	09/17/2009
Empty:	Y
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

JOHN H WINTERS (Continued) **U003921132**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	183127
UST ID:	202084
AI Number:	76046
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

JOHN H WINTERS (Continued) **U003921132**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	20413
Facility ID:	116668
AI Number:	76046
Application Received Date:	11/04/2004
Scheduled Construction Date:	11/04/2004
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M41104006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	55232
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	21641
UST ID:	Not reported
NOC ID:	20413
AI Number:	76046
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported

JOHN H WINTERS (Continued) **U003921132**

Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78711 3047
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	116668
Additional ID:	518333592003344
Princ ID:	167546612009246
AI Number:	76046
Facility Name:	JOHN H WINTERS
AR Number:	55232
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	JONATHAN HICKMAN/

HIST UST AUSTIN:

Name:	TX BLDG & PROCUREMENT COMMISSION
Address:	701 W. 51ST ST.
City,State,Zip:	AUSTIN, TX
Id UST:	EX088
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DH1381 **LINZ NICK TAILOR** **EDR Hist Cleaner** **1013779372**
NNE **611 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.020 mi.
108 ft. **Site 16 of 16 in cluster DH**

Actual:
494 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	LINZ NICK TAILOR	CLEANERS PRESSERS AND DYERS
1929	LINZ NICK TAILOR	CLOTHES CLEANERS AND PRESSERS

JA1382 **HUMBLE OIL & REFG** **EDR Hist Auto** **1013772263**
WNW **800 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
109 ft. **Site 1 of 15 in cluster JA**

Actual:
507 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	HUMBLE OIL & REFG	GASOLINE STATIONS
1962	GRIFFIN A C HUMBLE	GASOLINE STATIONS

JA1383 **BREWER SERVICE** **EDR Hist Auto** **1013765699**
WNW **801 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
109 ft. **Site 2 of 15 in cluster JA**

Actual:
507 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	BREWER SERVICE	GASOLINE AND OIL SERVICE STATIONS
1947	HAMMER & WEBB GULF SERVICE FILL	GASOLINE AND OIL SERVICE STATIONS
1953	KANEWSKE ROBT GULF	GASOLINE STATIONS
1958	KANEWSKE GULF SERV	GASOLINE STATIONS
1962	KANEWSKE GULF SERV	GASOLINE STATIONS

CW1384 **WESLEY G M DCLO CLNR** **EDR Hist Cleaner** **1013778382**
WNW **913 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
109 ft. **Site 2 of 3 in cluster CW**

Actual:
510 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	WESLEY G M DCLO CLNR	CLOTHES CLEANERS AND PRESSERS
1935	WESLEY GEO CLEANERS	DRY CLEANERS
1935	WESLEY GEO CLEANERS	CLEANERS, PRESSERS AND DYERS
1935	WESLEY GEO CLEANERS	CLOTHES PRESSERS AND CLEANERS
1935	WESLEY GEO CLEANERS	DYERS AND CLEANERS

CW1385 **TX HIST UST** **S128729198**
WNW **913 CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
109 ft. **Site 3 of 3 in cluster CW**

Actual:
510 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	Not reported
Address:	913 CONGRESS
City,State,Zip:	AUSTIN, TX
Id UST:	H0154
HID UST:	Not reported
Inspection:	04/22/1926
Due:	Not reported

1386 SSW < 1/8 0.021 mi. 109 ft. | **DIAMOND SHAMROCK INC**
6307 E RIVERSIDE DR
AUSTIN, TX 78741 | **EDR Hist Auto** | **1020767691**
N/A

Actual: 514 ft. EDR Hist Auto

Focus Map: 15

Year:	Name:	Type:
1994	DIAMOND SHAMROCK INC	Convenience Stores
1995	DIAMOND SHAMROCK INC	Convenience Stores

JB1387 WNW < 1/8 0.021 mi. 109 ft. | **KOFAHL CHRIS BARBER**
911 CONGRESS ST
AUSTIN, TX
Site 1 of 2 in cluster JB | **EDR Hist Cleaner** | **1013780690**
N/A

Actual: 510 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	KOFAHL CHRIS BARBER	CLOTHES PRESSERS AND CLEANERS

1388 ESE < 1/8 0.021 mi. 110 ft. | **STATE OF TEXAS PRESERVATION BOARD**
TEXAS STATE CAPITOL 12
AUSTIN, TX 78711 | **RCRA NonGen / NLR** | **1000654124**
TXD988039681

Actual: 542 ft. RCRA Listings:

Focus Map: 11

Date Form Received by Agency:	20081022
Handler Name:	State Of Texas Preservation Board
Handler Address:	TEXAS STATE CAPITOL 12
Handler City,State,Zip:	AUSTIN, TX 78711
EPA ID:	TXD988039681
Contact Name:	LLOYD ROSENBAUM
Contact Address:	W 14TH ST RM 503
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-475-4974
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W 14TH ST RM 503
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	State Of Texas Preservation Board
Owner Type:	Private
Operator Name:	State Of Texas Preservation Board
Operator Type:	Private
Short-Term Generator Activity:	No

STATE OF TEXAS PRESERVATION BOARD (Continued) **1000654124**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20081114
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	STATE OF TEXAS PRESERVATION BOARD
Legal Status:	Private
Date Became Current:	20081022
Date Ended Current:	Not reported
Owner/Operator Address:	201 W 14TH ST RM 503
Owner/Operator City,State,Zip:	AUSTIN, TX 78701

STATE OF TEXAS PRESERVATION BOARD (Continued) **1000654124**

Owner/Operator Telephone: 512-475-4974
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 12TH & CONGRESS
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-463-5390
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS PRESERVATION BOARD
Legal Status: Private
Date Became Current: 20081022
Date Ended Current: Not reported
Owner/Operator Address: 201 W 14TH ST RM 503
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-475-4974
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE PRESERVATION BOARD
Legal Status: Not reported
Date Became Current: 19941122
Date Ended Current: Not reported
Owner/Operator Address: 201 W 14TH ST RM 503
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-475-4974
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: STATE PRESERVATION BOARD
Legal Status: Not reported
Date Became Current: 19941122
Date Ended Current: Not reported
Owner/Operator Address: 201 W 14TH ST RM 503
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-475-4974
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910513
Handler Name: TEXAS STATE CAPITOL
Federal Waste Generator Description: Large Quantity Generator

STATE OF TEXAS PRESERVATION BOARD (Continued) **1000654124**

State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941122
Handler Name: STATE PRESERVATION BOARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081022
Handler Name: STATE OF TEXAS PRESERVATION BOARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940124
Handler Name: STATE PRESERVATION BOARD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23332
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

NAICS Code: 23622
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

STATE OF TEXAS PRESERVATION BOARD (Continued) **1000654124**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

IM1389 **MENZIES AVIATION ITP AUS** **FINDS** **1024449361**
SSW **9401 CARGO AVE STE 200** **ECHO** **N/A**
< 1/8 **AUSTIN, TX 78719** **PFAS ECHO**
0.021 mi.
110 ft. **Site 4 of 8 in cluster IM**

Actual:
501 ft.

Focus Map:
20

FINDS:
Registry ID: 110071158892

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Registry ID: 110070375682

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1024449361
Registry ID: 110070375682
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110070375682
Name: ABIA AUS431
Address: 9401 CARGO AVE STE 200
City,State,Zip: AUSTIN, TX 78719

PFAS ECHO:
Name: MENZIES AVIATION ITP AUS
Address: Not reported
City,State,Zip: AUSTIN, TX
Latitude: 30.21781
Longitude: -97.66907

MENZIES AVIATION ITP AUS (Continued) **1024449361**

Count:	1
County:	TRAVIS COUNTY
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071158892
Facility Percent Minority:	82.042
Facility Derived Tribes:	-
Facility Population:	918.83
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05FD91
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N

MENZIES AVIATION ITP AUS (Continued) **1024449361**

TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66907,%22y%22:30.21781,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

IM1390 **PRIMEFLIGHT AT AUS** **ECHO** **1026940559**
SSW **PFAS ECHO** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
110 ft. **Site 5 of 8 in cluster IM**

Actual:
501 ft.

Focus Map:
20

ECHO:

Envid:	1026940559
Registry ID:	110071157233
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071157233
Name:	PRIMEFLIGHT AT AUS
Address:	9401 CARGO AVE STE 300
City,State,Zip:	AUSTIN, TX 78719

PFAS ECHO:

Name:	PRIMEFLIGHT AT AUS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21781
Longitude:	-97.66907
Count:	1
County:	TRAVIS COUNTY
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071157233
Facility Percent Minority:	82.042
Facility Derived Tribes:	-
Facility Population:	918.83
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001006
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-

PRIMEFLIGHT AT AUS (Continued) **1026940559**

Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05FJ45
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66907,%22y%22:30.21781,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

IM1391 **AUSTIN GATEWAY** **RCRA-VSQG** **1004787919**
SSW **9401 CARGO AVENUE BAY F** **FINDS** **TXR000034207**
< 1/8 **AUSTIN, TX 78719** **ECHO**
0.021 mi.
110 ft. **Site 6 of 8 in cluster IM**

Actual:
501 ft.

Focus Map:
20

RCRA Listings:

Date Form Received by Agency:	20221110
Handler Name:	United Parcel Service Inc
Handler Address:	CARGO AVENUE BAY F
Handler City,State,Zip:	AUSTIN, TX 78719
EPA ID:	TXR000034207
Contact Name:	ANDERSON BRADFORD
Contact Address:	SWEETWATER LN
Contact City,State,Zip:	HOUSTON, TX 77037
Contact Telephone:	832-472-3695

AUSTIN GATEWAY (Continued) **1004787919**

Contact Fax:	Not reported
Contact Email:	ABRADFORD@UPS.COM
Contact Title:	CORP ENVR COORDINATOR
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	SWEETWATER LN
Mailing City,State,Zip:	HOUSTON, TX 77037
Owner Name:	El Paso Airport
Owner Type:	Other
Operator Name:	United Parcel Service Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221110
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

AUSTIN GATEWAY (Continued) **1004787919**

Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D019
Waste Description: Carbon Tetrachloride

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D022
Waste Description: Chloroform

Waste Code: D023
Waste Description: O-Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D028
Waste Description: 1,2-Dichloroethane

AUSTIN GATEWAY (Continued) **1004787919**

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D038
Waste Description: Pyridine

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

AUSTIN GATEWAY (Continued) **1004787919**

Waste Code: P105
Waste Description: Sodium Azide

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U003
Waste Description: Acetonitrile (I,T)

Waste Code: U012
Waste Description: Aniline (I,T) (Or) Benzenamine (I,T)

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U037
Waste Description: Benzene, Chloro- (Or) Chlorobenzene

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U055
Waste Description: Benzene, (1-Methylethyl)- (I) (Or) Cumene (I)

Waste Code: U056
Waste Description: Benzene, Hexahydro- (I) (Or) Cyclohexane (I)

Waste Code: U057
Waste Description: Cyclohexanone (I)

Waste Code: U069
Waste Description: 1,2-Benzenedicarboxylic Acid, Dibutyl Ester (Or) Dibutyl Phthalate

Waste Code: U070
Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

Waste Code: U079
Waste Description: 1,2-Dichloroethylene (Or) Ethene, 1,2-Dichloro-,(E)-

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U107
Waste Description: 1,2-Benzenedicarboxylic Acid, Dioctyl Ester (Or) Di-N-Octyl Phthalate

Waste Code: U108
Waste Description: 1,4-Diethyleneoxide (Or) 1,4-Dioxane

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U113
Waste Description: 2-Propenoic Acid, Ethyl Ester (I) (Or) Ethyl Acrylate (I)

AUSTIN GATEWAY (Continued) **1004787919**

Waste Code: U117
Waste Description: Ethane, 1,1'-Oxybis-(I) (Or) Ethyl Ether (I)

Waste Code: U118
Waste Description: 2-Propenoic Acid, 2-Methyl-, Ethyl Ester (Or) Ethyl Methacrylate

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U123
Waste Description: Formic Acid (C,T)

Waste Code: U124
Waste Description: Furan (I) (Or) Furfuran (I)

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U147
Waste Description: 2,5-Furandione (Or) Maleic Anhydride

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U162
Waste Description: 2-Propenoic Acid, 2-Methyl-, Methyl Ester (I,T) (Or) Methyl Methacrylate (I,T)

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U188
Waste Description: Phenol

Waste Code: U190
Waste Description: 1,3-Isobenzofurandione (Or) Phthalic Anhydride

Waste Code: U196
Waste Description: Pyridine

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U210

AUSTIN GATEWAY (Continued) **1004787919**

Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U213
Waste Description: Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)

Waste Code: U219
Waste Description: Thiourea

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U228
Waste Description: Ethene, Trichloro- (Or) Trichloroethylene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U279
Waste Description: U279

Waste Code: U404
Waste Description: U404

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: UNITED PARCEL SERVICE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6400 SEVEN STATES
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78244
Owner/Operator Telephone: 210-661-1786
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EL PASO AIRPORT
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6701 CONVAIR RD
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78244
Owner/Operator Telephone: 915-212-7315
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

AUSTIN GATEWAY (Continued) **1004787919**

Owner/Operator Indicator: Operator
Owner/Operator Name: UNITED PARCEL SERVICE INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 55 GLENLAKE PKWY NE
Owner/Operator City,State,Zip: ATLANTA, GA 30328
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000120
Handler Name: AUSTIN GATEWAY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20221110
Handler Name: UNITED PARCEL SERVICE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 49211
NAICS Description: COURIERS AND EXPRESS DELIVERY SERVICES

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20210608
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20210608
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported

AUSTIN GATEWAY (Continued) **1004787919**

Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	65
Consent/Final Order Respondent Name:	United Parcel Service Rcra Docket 06-2021-0906
Consent/Final Order Lead Agency:	0
Enforcement Type:	MULTI SITE CA/FO
Enforcement Responsible Person:	FD
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3800000
Paid Amount:	Not reported
Final Count:	1
Final Amount:	3800000

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20210608
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20210608
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	65
Consent/Final Order Respondent Name:	United Parcel Service Rcra Docket 06-2021-0906
Consent/Final Order Lead Agency:	0
Enforcement Type:	MULTI SITE CA/FO
Enforcement Responsible Person:	FD
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

AUSTIN GATEWAY (Continued) **1004787919**

SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3800000
Paid Amount:	Not reported
Final Count:	1
Final Amount:	3800000
Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Listing - General
Date Violation was Determined:	20210608
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20210608
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	65
Consent/Final Order Respondent Name:	United Parcel Service Rcra Docket 06-2021-0906
Consent/Final Order Lead Agency:	0
Enforcement Type:	MULTI SITE CA/FO
Enforcement Responsible Person:	FD
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3800000
Paid Amount:	Not reported
Final Count:	1
Final Amount:	3800000
Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20210608
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20210608
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported

AUSTIN GATEWAY (Continued) **1004787919**

Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	65
Consent/Final Order Respondent Name:	United Parcel Service Rcra Docket 06-2021-0906
Consent/Final Order Lead Agency:	0
Enforcement Type:	MULTI SITE CA/FO
Enforcement Responsible Person:	FD
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3800000
Paid Amount:	Not reported
Final Count:	1
Final Amount:	3800000

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	LDR - General
Date Violation was Determined:	20210608
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20210608
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	65
Consent/Final Order Respondent Name:	United Parcel Service Rcra Docket 06-2021-0906
Consent/Final Order Lead Agency:	0
Enforcement Type:	MULTI SITE CA/FO
Enforcement Responsible Person:	FD
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

AUSTIN GATEWAY (Continued) **1004787919**

SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3800000
Paid Amount:	Not reported
Final Count:	1
Final Amount:	3800000

Evaluation Action Summary:

Evaluation Date:	20210608
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	FD
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20210608
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	FD
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20210608
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	FD
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20210608
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	FD
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

AUSTIN GATEWAY (Continued) **1004787919**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20210608
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	FD
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110005186869

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004787919
Registry ID:	110005186869
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005186869
Name:	AUSTIN GATEWAY
Address:	9401 CARGO AVENUE BAY F
City,State,Zip:	AUSTIN, TX 78719

IM1392 **GROUND SERVICES INTERNATIONAL** **RCRA NonGen / NLR** **1011863849**
SSW **9401 CARGO AVE STE 400** **FINDS** **TXR000079335**
< 1/8 **AUSTIN, TX 78719** **ECHO**
0.021 mi.
110 ft. **Site 7 of 8 in cluster IM**

Actual:
501 ft.

Focus Map:
20

RCRA Listings:

Date Form Received by Agency:	20181010
Handler Name:	Pinnacle Airlines
Handler Address:	9401 CARGO AVE STE 400

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Handler City,State,Zip:	AUSTIN, TX 78719-2352
EPA ID:	TXR000079335
Contact Name:	RHONDA QUINT
Contact Address:	7500 AIRLINE DR
Contact City,State,Zip:	MINNEAPOLIS, MN 55450-1101
Contact Telephone:	612-794-9412
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	7500 AIRLINE DR
Mailing City,State,Zip:	MINNEAPOLIS, MN 55450-1101
Owner Name:	Pinnacle Airlines Inc
Owner Type:	Private
Operator Name:	Pinnacle Airlines Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181025

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MESABA AIRLINES INC	
Legal Status:	Private
Date Became Current:	20081030
Date Ended Current:	Not reported
Owner/Operator Address:	1000 BLUE GENTIAN RD STE 200
Owner/Operator City,State,Zip:	EAGAN, MN 55121
Owner/Operator Telephone:	651-367-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12
Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MESABA AIRLINES INC	
Legal Status:	Private
Date Became Current:	20080926
Date Ended Current:	Not reported
Owner/Operator Address:	1000 BLUE GENTIAN RD STE 200
Owner/Operator City,State,Zip:	EAGAN, MN 55121
Owner/Operator Telephone:	651-367-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MESABA AVIATION INC	
Legal Status:	Private
Date Became Current:	20081030
Date Ended Current:	Not reported
Owner/Operator Address:	1000 BLUE GENTIAN RD STE 200
Owner/Operator City,State,Zip:	EAGAN, MN 55121
Owner/Operator Telephone:	651-367-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12
Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12
Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MESABA AIRLINES INC	
Legal Status:	Private

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Date Became Current:	20080926
Date Ended Current:	Not reported
Owner/Operator Address:	1000 BLUE GENTIAN RD STE 200
Owner/Operator City,State,Zip:	EAGAN, MN 55121
Owner/Operator Telephone:	651-367-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12
Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PINNACLE AIRLINES INC	
Legal Status:	Private
Date Became Current:	20120712
Date Ended Current:	Not reported
Owner/Operator Address:	40 S MAIN ST FL 12
Owner/Operator City,State,Zip:	MEMPHIS, TN 38103-2514
Owner/Operator Telephone:	901-922-0660
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20080926
Handler Name: MESABA AIRLINES INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20081030
Handler Name: MESABA AVIATION INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130925
Handler Name: PINNACLE AIRLINES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140529
Handler Name: PINNACLE AIRLINES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20181010
Handler Name: PINNACLE AIRLINES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 481111
NAICS Description: SCHEDULED PASSENGER AIR TRANSPORTATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070359288

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Registry ID: 110070355489

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Registry ID: 110070372583

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Registry ID: 110037445707

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1011863849
Registry ID:	110070359288
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070359288
Name:	DHL EXPRESS USA
Address:	9401 CARGO AVE
City,State,Zip:	AUSTIN, TX 78719

GROUND SERVICES INTERNATIONAL (Continued) **1011863849**

Envid:	1011863849
Registry ID:	110070372583
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070372583
Name:	UPS AUSTIN GATEWAY
Address:	9401 CARGO AVE
City,State,Zip:	AUSTIN, TX 78719

Envid:	1011863849
Registry ID:	110037445707
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110037445707
Name:	PINNACLE AIRLINES
Address:	9401 CARGO AVE STE 400
City,State,Zip:	AUSTIN, TX 78719

Envid:	1011863849
Registry ID:	110070355489
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070355489
Name:	GROUND SERVICES INTERNATIONAL
Address:	9401 CARGO AVE STE 400
City,State,Zip:	AUSTIN, TX 78719

IM1393 **PINNACLE AIRLINES** **TX Ind. Haz Waste** **S112202231**
SSW **9401 CARGO AVE STE 400** **TX IHW CORR ACTION** **N/A**
< 1/8 **AUSTIN, TX 78719**
0.021 mi.
110 ft. **Site 8 of 8 in cluster IM**

Actual:
501 ft.

Focus Map:
20

Ind. Haz Waste:

Name:	PINNACLE AIRLINES
Address:	9401 CARGO AVE STE 400
City,State,Zip:	AUSTIN, TX 78719
Permit Number:	Not reported
Registration Number:	88605
Registration Initial Notification Date:	09/09/2008
Registration Last Amendment Date:	10/10/2018
EPA Identification:	TXR000079335
Primary NAICS Code:	481111
Status Change Date:	20181018
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	ENDEAVOR AIR INC
Contact Name:	RHONDA QUINT
Contact Telephone Number:	612-7949412
Mailing Address:	7500 AIRLINE DR
Mailing Address2:	DEPT 625

PINNACLE AIRLINES (Continued) **S112202231**

Mailing City,State,Zip:	MINNEAPOLIS, MN 554501101
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	123140
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20181018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	ENDEAVOR AIR INC
Operator Address:	40 S MAINST FL 12
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	MEMPHIS, TN 38103
Operator Country:	UNITED STA
Operator Telephone:	1-901-9220660
Operator Fax Number:	Not reported
Operator Email:	RQUINT@PNCL.COM
Operator Business Type:	Corporation
Operator Tax ID:	15816053787
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ENDEAVOR AIR INC
Owner Mailing Address:	40 S MAINST FL 12
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	MEMPHIS, TN 38103
Owner Country:	UNITED STA
Owner Telephone:	1-901-9220660
Owner Fax:	Not reported
Owner Email Address:	RQUINT@PNCL.COM
Owner Business Type:	Corporation
Owner Tax ID:	15816053787
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14

PINNACLE AIRLINES (Continued) **S112202231**

Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	55
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	061
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Closed head 55-gal drums in container storage area inside building
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20181010
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	061
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Open head 55 gal drums in storage area inside of building
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20181010
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	40 S MAINST FL 12
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	MEMPHIS, TN 38103
Contact Phone:	1-901-9220660

PINNACLE AIRLINES (Continued) **S112202231**

Contact Fax:	Not reported
Contact Email:	RQUINT@PNCL.COM
Contact Name:	RHONDA QUINT
Contact Title:	BASE MANAGER
Contact Role:	PRICONT
Contact Address:	7500 AIRLINE DR
Contact Address 2:	DEPT 625
Contact Address 3:	Not reported
Contact City,State,Zip:	MINNEAPOLIS, MN 55450
Contact Phone:	1-612-7949412
Contact Fax:	Not reported
Contact Email:	PHILSUNDBERG@MESABA.COM

Ind. Haz Waste:

Waste ID:	228665
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solv/fuel rags, paper towels - wiping of airplane parts. Date of G
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	481111
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228666
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oil and jet fuel - oil and fuel from parts cleaningDate of Generation: 8/1/08
Standard Industrial Code:	Not reported
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1

PINNACLE AIRLINES (Continued) **S112202231**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	481111
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228667
Texas Waste Code:	Not reported
Texas Waste Code 2:	00034891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Pigs and mats with oil - spill cleanupDate of Generation: 8/1/08
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	228668
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Discarding obsolete materials - Aerosol cans. Not paint related.Date of Gener a
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	481111
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

PINNACLE AIRLINES (Continued) **S112202231**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	356617
Texas Waste Code:	Not reported
Texas Waste Code 2:	1119119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	JP8 FUEL WITH WATER GENERATED FROM AIRCRAFT MAINTENANCE.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	481111
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	356615
Texas Waste Code:	Not reported
Texas Waste Code 2:	5219219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PAINT RELATED MATERIAL USED IN AIRCRAFT MAINTENANCE SUCH AS PRIMER, THINNER, ADH
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	481111
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

PINNACLE AIRLINES (Continued) **S112202231**

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-901-9220660 x0
Mailing Address:	40 S MAIN ST FL 12
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MEMPHIS, TN 38103
AR Number:	0000315135
Principal Name:	ENDEAVOR AIR INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-901-9220660 x0
Mailing Address:	40 S MAIN ST FL 12
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MEMPHIS, TN 38103
AR Number:	0000317078
Principal Name:	ENDEAVOR AIR INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-901-9220660 x0
Mailing Address:	40 S MAIN ST FL 12
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MEMPHIS, TN 38103
AR Number:	0000317078
Principal Name:	ENDEAVOR AIR INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-901-9220660 x0
Mailing Address:	40 S MAIN ST FL 12
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MEMPHIS, TN 38103
AR Number:	0000315135
Principal Name:	ENDEAVOR AIR INC
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	MESABA AVIATION
Address:	9401 CARGO AVE STE 400

PINNACLE AIRLINES (Continued) **S112202231**

City,State,Zip:	AUSTIN, TX 78719
Program Id:	88605
Location Desc:	Not reported
RN NUM:	RN105586655
Status:	INACTIVE
Status Date:	10/10/2018
EDR Link ID:	88605
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	10/10/2018
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

JC1394 **GREEN WATER TREATMENT PLANT** **TX VCP** **S108440406**
ENE **600 W. CESAR CHAVEZ** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX IOP**
0.021 mi. **TX TIER 2**
110 ft. **Site 1 of 2 in cluster JC** **TX IHW CORR ACTION**

Actual:
453 ft.

Focus Map:
11

VCP TCEQ:

Name:	WATER TRTMT PLANT - CITY OF AUSTIN PUB WORKS
Address:	600 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2199
VCP Record Date:	07/09/2008
Facility Type:	WATER/WASTEWATER TREATMENT
PCA Number:	78285
Project Manager:	RBRYANT
Phase:	COMPLETED
Acres at Site:	6.075
REM Program:	VCP
RN Number:	RN105377568
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	07/09/2008
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	03/12/2013
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Date Cashier Check Received: 07/03/2008
GW Target COC Class: Not reported
Sediment Target COC Class: Not reported
Application Accepted?: Not reported
Application Accepted Date: 2008-08-11 00:00:00
Soil Target COC Class: METALS; SVOCS
Surface Water Target COC Class: Not reported
Alternate VCP ID: 2199
Leaking Petroleum Storage Registration Tank: Not reported
Project Number: 782850
Off Site?: Not reported
Media: PAPER
IOP Number: 952; 805
File Location: D/298
Latitude: 0.00
Longitude: 0.00

GCC:
Name: BLOCK 23 OF FORMER GREEN WATER TREATMENT PLANT
Address: 600 W CESAR CHAVEZ ST
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: *
File Number: 952
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 4/6/2015
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: THOMAS C. GREEN WATER TREATMENT PLANT
Address: 600 W CESAR CHAVEZ STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 805
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 12/9/2011
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Name: THOMAS C. GREEN WATER TREATMENT PLANT
Address: 600 W CESAR CHAVEZ STREET
City,State,Zip: AUSTIN, TX
Division: REM/VCIO
New Cases: Not reported
File Number: 805
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 12/9/2011
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

IOP:
Name: THOMAS C GREEN WATER TREATMENT PLANT
Address: 600 W CESAR CHAVEZ ST
City,State,Zip: AUSTIN, TX 78701
Program ID: 805
Date IOP Received: Not reported
Region: REGION 11 - AUSTIN
Phase: COMPLETED
Interest In Site: Not reported
PCA Number: 32805
Property Use: WATER/WASTEWATER TREATMENT
Project Manager: RBRYANT
Project Number: 328050
Latitude: 0.00
Longitude: 0.00
Acres: 6.08
Media Affected: Not reported
LPST Number: Not reported
VCP ID: Not reported
Cert Issued: 04/12/2013
Solid Waste Regn Number: Not reported
EPA TX ID/Cerclis regn Number: Not reported
Contaminant Categories: Not reported
Applicant Information: Not reported
Applicant First Name: Not reported
Applicant Last Name: Not reported
Applicant Title: Not reported
Applicant Address: Not reported
Applicant City,State,Zip: Not reported
Applicant Phone: Not reported
Applicant Fax: Not reported
Consultant/Attorney: Not reported
Consultant/Attorney First Name: Not reported
Consultant/Attorney Last Name: Not reported
Consultant/Attorney Title: Not reported
Consultant/Attorney Address: Not reported
Consultant/Attorney City,State,Zip: Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

REM Program:	IOP
RN Number:	RN105377568
Consultant/Attorney Phone:	Not reported
Site Address Description:	Not reported
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	10/26/2011
Application Received Date:	10/26/2011
Application Acceptance Date:	Not reported
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	212/D2

TIER 2:

Facility Id/Name:	FATR200971UJR80024TH/GREEN WATER TREATMENT PLANT
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Austin Water Utility
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	3/16/2010
Mailing Address:	P.O.Box 1088
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Jane Burazer
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200825GD6S00213X/GREEN WATER TREATMENT PLANT
Reporting Year:	2008
Facility Country:	USA
Facility Department:	City of Austin - Austin Water Utility
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	1/12/2008
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

All Chemicals Same As Last Year:	True
State Fees Total:	150
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Austin Fire Department
Submitted By:	Jane Burazer
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200625GD6S00213X/GREEN WATER TREATMENT PLANT
Reporting Year:	2006
Facility Country:	USA
Facility Department:	City of Austin - Austin Water Utility
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	3/20/2007
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Austin Fire Department
Submitted By:	David C. Gaines
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR200525GD6S00213X/GREEN WATER TREATMENT PLANT
Reporting Year:	2005
Facility Country:	USA
Facility Department:	City of Austin - Austin Water Utility
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	Not reported
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Austin Fire Department
Submitted By:	"Steve Carricom, Superintendent Green Water Treatment Plant"
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes: This facility was decomissioned in September 23rd, 2008. These hazardous materials and extremely hazardous substances will no longer be present at this facility.

Validation: This facility passed all validation checks.

Facility Info:

Id:	22132
Id Type:	NAICS
Description:	Sewage Treatment Facilities
Last Modified:	2/26/2010
Id:	4952
Id Type:	SIC
Description:	SEWERAGE SYSTEMS
Last Modified:	2/26/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	P.O.Box 1088
Contact City/State/Zip:	Austin, TX 78701-8859
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Gregg Meszaros
Title:	COA Director of Water and Wastewater
Modification Date:	3/17/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	625 East 10th St
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Assistant Director for W/WW Treatment

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Contact Name:	Jane Burazer
Title:	Assistant Director for Treatment
Modification Date:	2/24/2004

Contact:

Contact Email:	Not reported
Contact Mail Address:	3907 S. Industrial Dr
Contact City/State/Zip:	Austin, TX 78744-1070
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	David Gaines
Title:	OHS Coordinator
Modification Date:	2/27/2008

Contact:

Contact Email:	Not reported
Contact Mail Address:	600 W. Cesar Chavez
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Steve Carrico
Title:	Division Manager WTP
Modification Date:	3/17/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	625 E. 10th St., P.O. Box 1088
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Austin Water Utility City of Austin
Title:	Not reported
Modification Date:	3/17/2010

Chemical Inventory:

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Sodium Hydroxide
Chemical Inv Record Id:	CVTR200971UK1300FNWK
CAS Number:	1310-73-2
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	7000
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UK9X00K9TE
Chemical Inventory Record Id:	CVTR200971UK1300FNWK
Amt Of Sub Stored Or Transported:	7000
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Scrubber south of facility
Last Modified:	3/17/2010

Record Key:	CLTR200971UK9T00J63H
Chemical Inventory Record Id:	CVTR200971UK1300FNWK
Amt Of Sub Stored Or Transported:	110
Amount Units:	gallons
Type Of Storage:	Plastic or non-metallic drum
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Warehouse
Last Modified:	3/17/2010

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Calcium Hydroxide
Chemical Inv Record Id:	CVTR200971UK4800GCWS
CAS Number:	1305-78-8
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	3000
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Chemical Inventory Location:

Record Key:	CLTR200971UK8H00H25H
Chemical Inventory Record Id:	CVTR200971UK4800GCWS
Amt Of Sub Stored Or Transported:	3000
Amount Units:	pounds
Type Of Storage:	Tank inside building
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Roof of chemical building
Last Modified:	3/17/2010

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Hydrofluorosilicic Acid
Chemical Inv Record Id:	CVTR200971UKBS00LWGT
CAS Number:	16961-83-4
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	7000
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UKEB00M36A
Chemical Inventory Record Id:	CVTR200971UKBS00LWGT
Amt Of Sub Stored Or Transported:	7000
Amount Units:	pounds
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	East of Backwash Tower
Last Modified:	3/17/2010

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Ferric Sulfate
Chemical Inv Record Id:	CVTR200971UKFD00N0UL
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Max Amount In Largest Container:	7000
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UKH200QFQC
Chemical Inventory Record Id:	CVTR200971UKFD00N0UL
Amt Of Sub Stored Or Transported:	1000
Amount Units:	pounds
Type Of Storage:	Tank inside building
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Second Floor of Chemical Building
Last Modified:	3/17/2010

Record Key:	CLTR200971UKGY00PCCD
Chemical Inventory Record Id:	CVTR200971UKFD00N0UL
Amt Of Sub Stored Or Transported:	7000
Amount Units:	pounds
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	West side of chemical Building
Last Modified:	3/17/2010

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Sodium Hexametaphosphate
Chemical Inv Record Id:	CVTR200971UKK300R6X8
CAS Number:	68915-31-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	7000
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Pure Form:	Not reported
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UKME00S7BH
Chemical Inventory Record Id:	CVTR200971UKK300R6X8
Amt Of Sub Stored Or Transported:	8000
Amount Units:	pounds
Type Of Storage:	Bag
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Second Floor Chemical Bldg
Last Modified:	3/17/2010

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Activated Carbon
Chemical Inv Record Id:	CVTR200971UKND00T2FV
CAS Number:	7440-44-0
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	7000
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UKQQ00U1ZC
Chemical Inventory Record Id:	CVTR200971UKND00T2FV
Amt Of Sub Stored Or Transported:	7000
Amount Units:	pounds
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	North of Carbon Building
Last Modified:	3/17/2010

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Facility Id:	FATR200971UJR80024TH
Chemical Name:	Diesel Fuel
Chemical Inv Record Id:	CVTR200971UKS400V9J1
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	600
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/17/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971UKU800W449
Chemical Inventory Record Id:	CVTR200971UKS400V9J1
Amt Of Sub Stored Or Transported:	100
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	North of Ammonia Scrubber
Last Modified:	3/17/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

IHW CORR ACTION:

Name:	GREEN WATER TREATMENT PLANT
Address:	600 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	T2229

GREEN WATER TREATMENT PLANT (Continued) **S108440406**

Location Desc:	Not reported
RN NUM:	RN105377568
Status:	INACTIVE
Status Date:	01/21/2009
EDR Link ID:	T2229
Project Phase:	TRANSFERRED
Phase Status Date:	01/21/2009
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

IS1395 **ANTOINE GROCERY** **TX UST** **U001962404**
ESE **11209 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.021 mi. **TX RDR**
110 ft. **Site 2 of 3 in cluster IS**

Actual:
777 ft.

Focus Map:
3

UST:

Name:	ANTOINE GROCERY
Address:	11209 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533077
AI Number:	65829
Facility Type:	RETAIL
Facility Begin Date:	01/01/1988
Facility Status:	INACTIVE
Additional ID:	404520522002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	THANH PHAM,
Contact Organization Name:	ANTOINE GROCERY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128349142
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/20/1994
Signature Name/Title On Earliest Reg Form:	ALI ABDUL,LEASING OWNER
Application Received Date On Earliest Reg Form:	07/14/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	397520522002053
Additional ID:	404520522002053
Ai Number:	65829
Operator CN:	CN600778062

ANTOINE GROCERY (Continued) **U001962404**

Operator Name:	THANH VAN PHAM
Operator Effective Begin Date:	09/01/2000
Operator Type:	IN
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600778054
Owner Last Name:	MARLEY
Owner First Name:	DANA
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	391520502002053
Additional ID:	404520522002053
AI Number:	65829
Owner Effective Begin Date:	09/01/2000
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	98004
Cert ID:	163453
AI Number:	65829
Self Certification Date:	07/05/2005
Signature Name/Title:	THANH VAN PHAM OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

ANTOINE GROCERY (Continued) **U001962404**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	98004
Cert ID:	163452
AI Number:	65829
Self Certification Date:	07/05/2004
Signature Name/Title:	THANH VAN PHAM OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	98004
Cert ID:	162864
AI Number:	65829
Self Certification Date:	07/10/2003
Signature Name/Title:	THANH VAN PHAM OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	98004
Cert ID:	162863
AI Number:	65829
Self Certification Date:	11/15/2002
Signature Name/Title:	THANH VAN PHAM OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

ANTOINE GROCERY (Continued) **U001962404**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	98004
Cert ID:	162862
AI Number:	65829
Self Certification Date:	06/20/2001
Signature Name/Title:	JOE JUNG PROP MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	07/14/1994
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171448
Facility ID:	98004
Ai Number:	65829
Tank Id:	1B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/13/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

ANTOINE GROCERY (Continued) **U001962404**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1B
Tank Capacity:	6000
UST Comprt ID:	162781
UST ID:	171448
AI Number:	65829
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

ANTOINE GROCERY (Continued) **U001962404**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	04/13/1999
Tank Registration Date:	05/05/1999
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	190979
Facility ID:	98004
Ai Number:	65829
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/07/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

ANTOINE GROCERY (Continued) **U001962404**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/04/1999

Compartment Records:

Tank ID:	1A
Tank Capacity:	8000
UST Comprt ID:	162783
UST ID:	190979
AI Number:	65829
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

ANTOINE GROCERY (Continued) **U001962404**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Tank ID:	1A
Tank Capacity:	4000
UST Comprt ID:	162784
UST ID:	190979
AI Number:	65829
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1988

ANTOINE GROCERY (Continued) **U001962404**

Tank Registration Date:	07/14/1994
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171449
Facility ID:	98004
Ai Number:	65829
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/13/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

ANTOINE GROCERY (Continued) **U001962404**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	162782
UST ID:	171449
AI Number:	65829
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	16641
Facility ID:	98004
AI Number:	65829
Application Received Date:	02/08/2006
Scheduled Construction Date:	01/24/2006
UST Improvement:	N
UST Installation:	N

ANTOINE GROCERY (Continued) **U001962404**

UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60208007
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	58148
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	17954
UST ID:	Not reported
NOC ID:	16641
AI Number:	65829
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	32672
UST ID:	190979
NOC ID:	Not reported
AI Number:	65829
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Excell Enviromental
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

ANTOINE GROCERY (Continued) **U001962404**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	47838
UST ID:	190979
NOC ID:	Not reported
AI Number:	65829
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	Not reported
Representative Name:	RICHARD ROLLINS S
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MARLEY DANA
Contact Mailing Address (Delivery):	PO BOX 41149
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 0020
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	98004
Additional ID:	404520522002053
Princ ID:	391520502002053
AI Number:	65829
Facility Name:	ANTOINE GROCERY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOE JUNG/

ANTOINE GROCERY (Continued) **U001962404**

HIST UST AUSTIN:

Name:	ANTOINE'S GROCERY
Address:	11209 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	645
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	ANTOINE GROCERY
Address:	11209 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	98004
Finass ID:	79940
AI:	65829
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	15186
Facility ID:	65829
RN:	Not reported
CN:	Not reported
Name:	ANTOINE GROCERY
Address:	11209 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/27/2006
Due Date:	5/26/2006
Tank Owner:	TWIN OAKS ASSOCIATES
Contact Person:	SCOTT JUNG
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/1/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC

ANTOINE GROCERY (Continued) **U001962404**

Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/1/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CY1396 **PAUL O. SIMMS CO** **TX HIST UST** **S111678774**
ESE **316 W 8TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
112 ft. **Site 3 of 4 in cluster CY**

Actual:
540 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	PAUL O. SIMMS CO
Address:	316 W 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0268
HID UST:	268
Inspection:	Not reported
Due:	06/01/2012

CY1397 **JOE E. ROBINSON, JR.** **TX HIST UST** **S111678707**
ESE **316 W 8TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
112 ft. **Site 4 of 4 in cluster CY**

Actual:
540 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JOE E. ROBINSON, JR.
Address:	316 W 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0009
HID UST:	9
Inspection:	02/16/2010
Due:	02/16/2013

DB1398 **LINZ GUST B CLNR** **EDR Hist Cleaner** **1013787297**
WNW **809 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
112 ft. **Site 4 of 11 in cluster DB**

Actual:
505 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1916	LINZ GUST B CLNR	CLOTHES CLEANERS AND PRESSERS

Z1399 ESE < 1/8 0.021 mi. 112 ft. | **KWIK WASH COIN LAUNDRIES**
7543 LAMAR BLVD N
TRAVIS (County), TX 78752
Site 9 of 9 in cluster Z | **EDR Hist Cleaner** | **1013779386**
N/A

Actual: 752 ft. EDR Hist Cleaner

Focus Map: 6

Year:	Name:	Type:
1975	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1984	KWF' WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1990	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

DB1400 WNW < 1/8 0.021 mi. 112 ft. | **VIP CLEANERS**
805 N CONGRESS
AUSTIN, TX 78701
Site 5 of 11 in cluster DB | **EDR Hist Cleaner** | **1018558191**
N/A

Actual: 504 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1988	VIP CLEANERS	Drycleaning Plants, Except Rugs
1989	VIP CLEANERS	Drycleaning Plants, Except Rugs
1990	VIP CLEANERS	Drycleaning Plants, Except Rugs

DI1401 ESE < 1/8 0.021 mi. 112 ft. | **AMERICAN CLEANERS**
309 W 5TH
AUSTIN, TX 78701
Site 4 of 9 in cluster DI | **RCRA NonGen / NLR**
FINDS
ECHO | **1000360515**
TXD981904972

Actual: 488 ft. RCRA Listings:

Focus Map: 11

Date Form Received by Agency:	20210717
Handler Name:	American Cleaners
Handler Address:	309 W 5TH ST
Handler City,State,Zip:	AUSTIN, TX 78701-2911
EPA ID:	TXD981904972
Contact Name:	NELDA DAVIS
Contact Address:	PO BOX 161868
Contact City,State,Zip:	AUSTIN, TX 78716-1868
Contact Telephone:	512-327-9688
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 161868
Mailing City,State,Zip:	AUSTIN, TX 78716-1868
Owner Name:	American Cleaners

AMERICAN CLEANERS (Continued) **1000360515**

Owner Type:	Private
Operator Name:	American Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211229
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And

AMERICAN CLEANERS (Continued) **1000360515**

F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: AMERICAN CLEANERS	
Legal Status:	Private
Date Became Current:	20120625
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 161868
Owner/Operator City,State,Zip:	AUSTIN, TX 78716
Owner/Operator Telephone:	512-327-9688
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: AMERICAN CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 161868
Owner/Operator City,State,Zip:	AUSTIN, TX 78716-1868
Owner/Operator Telephone:	512-327-9688
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: AMERICAN CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 161868
Owner/Operator City,State,Zip:	AUSTIN, TX 78716-1868
Owner/Operator Telephone:	512-327-9688
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: AMERICAN CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 161868
Owner/Operator City,State,Zip:	AUSTIN, TX 78716-1868
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: AMERICAN DRYCLEAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

AMERICAN CLEANERS (Continued) **1000360515**

Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AMERICAN CLEANERS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 161868
Owner/Operator City,State,Zip: AUSTIN, TX 78716
Owner/Operator Telephone: 512-327-9688
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AMERICAN CLEANERS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 161868
Owner/Operator City,State,Zip: AUSTIN, TX 78716-1868
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AMERICAN CLEANERS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 161868
Owner/Operator City,State,Zip: AUSTIN, TX 78716
Owner/Operator Telephone: 512-327-9688
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AMERICAN CLEANERS
Legal Status: Private
Date Became Current: 20120625
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 161868
Owner/Operator City,State,Zip: AUSTIN, TX 78716
Owner/Operator Telephone: 512-327-9688
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19970825

AMERICAN CLEANERS (Continued) **1000360515**

Handler Name: AMERICAN CLNRS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: AMERICAN CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120625
Handler Name: AMERICAN CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130114
Handler Name: AMERICAN CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210717
Handler Name: AMERICAN CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

AMERICAN CLEANERS (Continued) **1000360515**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 32312
NAICS Description: SUPPORT ACTIVITIES FOR PRINTING

NAICS Code: 323120
NAICS Description: SUPPORT ACTIVITIES FOR PRINTING

NAICS Code: 323121
NAICS Description: TRADEBINDING AND RELATED WORK

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005098036

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000360515
Registry ID: 110005098036
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005098036
Name: AMERICAN CLEANERS
Address: 309 W 5TH
City,State,Zip: AUSTIN, TX 78701

DI1402 FORMER AMERICAN CLEANERS TX PRIORITYCLEANERS S109028921
ESE 309-311 WEST 5TH ST TX GCC N/A
< 1/8 AUSTIN, TX
0.021 mi.
112 ft. Site 5 of 9 in cluster DI

Actual:
488 ft.

Focus Map:
11

PRIORITY CLEANERS:

Name:	FORMER AMERICAN CLEANERS
Address:	309-311 WEST 5TH ST
City,State,Zip:	AUSTIN, TX
Priority Status:	Closed
DCRP App Number:	DC0097
RN Number:	100698174
Corrective Action Status:	TRRP Remedy Standard A - Residential
Rank Score:	Not reported
Priority:	Not reported
Project Manager:	Not reported

GCC:

Name:	AMERICAN CLEANERS FACILITY
Address:	309-311 WEST 5TH ST
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	188
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	2/28/1996
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	3 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	AMERICAN CLEANERS FACILITY
Address:	309-311 WEST 5TH ST
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	188
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	2/28/1996
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	3 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

DI1403 **UNITED STATES CLEANERS INC** **EDR Hist Cleaner** **1020111142**
ESE **309 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.021 mi.
112 ft. **Site 6 of 9 in cluster DI**

Actual:
488 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1994	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
1995	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
1996	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs

---

DI1404 **AMERICAN CLEANERS FACILITY** **TX VCP** **S102754146**
ESE **309 W 5TH ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.021 mi.
112 ft. **Site 7 of 9 in cluster DI**

Actual:
488 ft.
VCP TCEQ:

Focus Map:
11

Name:	AMERICAN CLEANERS FACILITY
Address:	309 W 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	188
VCP Record Date:	02/28/1996
Facility Type:	DRY CLEANER
PCA Number:	38098
Project Manager:	MARTHUR
Phase:	TRANSFERRED TO DCRP
Acres at Site:	0.27
REM Program:	VCP
RN Number:	RN100698174
Former Facility Type:	Not reported
Site Address Description:	309 W 5TH AUSTIN TX
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	02/23/1996
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	02/23/1996
GW Target COC Class:	CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported

AMERICAN CLEANERS FACILITY (Continued) **S102754146**

Application Accepted?:	Y
Application Accepted Date:	2006-12-22 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	188
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	310980
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	200-43/D
Latitude:	30.27
Longitude:	-97.75

Ind. Haz Waste:

Name:	AMERICAN CLEANERS
Address:	309 W 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72367
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	07/17/2021
EPA Identification:	TXD981904972
Primary NAICS Code:	323120
Status Change Date:	20130807
Land Type:	PRIVATE
Description of Facility Site Location:	309 W 5TH AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	JOASH ENTERPRISES INC
Contact Name:	NELDA DAVIS
Contact Telephone Number:	512-3279688
Mailing Address:	PO BOX 161868
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787161868
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26808
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20210719
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

AMERICAN CLEANERS FACILITY (Continued) **S102754146**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JOASH ENTERPRISES INC
Operator Address:	PO BOX 161868
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78716
Operator Country:	UNITED STA
Operator Telephone:	1-512-3279688
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17427236132
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JOASH ENTERPRISES INC
Owner Mailing Address:	PO BOX 161868
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78716
Owner Country:	UNITED STA
Owner Telephone:	1-512-3279688
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17427236132
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 161868
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78716
Contact Phone:	1-512-3279688
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 161868
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78716

AMERICAN CLEANERS FACILITY (Continued) **S102754146**

Contact Phone:	1-512-3279688
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	NELDA DAVIS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 161868
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78716
Contact Phone:	1-512-3279688
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	67393
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	DRY CLEANING RESIDUE
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323121
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	67395
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PROCESS FILTRATIONLARGE CARTRIDGE FILTERS CONTAINING PAPER AND/OR CARBON CONTAMI
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

AMERICAN CLEANERS FACILITY (Continued) **S102754146**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323121
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	294007
Texas Waste Code:	Not reported
Texas Waste Code 2:	DCMR301H
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294008
Texas Waste Code:	Not reported
Texas Waste Code 2:	DCMS101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AMERICAN CLEANERS FACILITY (Continued) **S102754146**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 161868
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78716
AR Number:	0000303219
Principal Name:	JOASH ENTERPRISES INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 161868
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78716
AR Number:	0000303219
Principal Name:	JOASH ENTERPRISES INC
Attention Name:	Not reported
Attention Suffix:	HWG

JD1405 **ROUND2 INC.** **TX SWF/LF** **S111326163**
South **1340 AIRPORT COMMERCE DR STE 3300** **TX SWRCY** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX ASBESTOS**
0.021 mi. **TX COMP HIST**
113 ft. **Site 1 of 2 in cluster JD**

Actual:
484 ft.

Focus Map:
15

SWF/LF:

Name:	ROUND2 INC.
Address:	1340 AIRPORT COMMERCE DR STE 3300
City,State,Zip:	AUSTIN, TX 78741-6831
Region:	11
Permit Number:	100312
Facility Status:	ACTIVE
Facility Type:	5RR
Permit Status:	ACKNOWLEDGED
Status Date:	08/30/2011
Mailing Address:	1340 AIRPORT COMMERCE DR STE 3300 AUSTIN, TX 78741-6831
Client Name:	Not reported
Client Address:	Not reported
Client Telephone:	N/A
Business Type:	BUSINESS
Area Served:	TRAVIS COUNTY
Estimated Closure Date:	Not reported
Permit Acreage:	NA
Permit Start:	05/19/2011
Permit End:	08/30/2011
Polution Served:	Not reported
Tons per Day:	NA
Yards per Day:	NA
Application:	NEW APPLICATION
Lat/Long:	30.22350 / -97.68807

ROUND2 INC. (Continued) **S111326163**

SWRCY:

Name:	ROUND2 INC.
Address:	1340 AIRPORT COMMERCE DR STE 3300
City,State,Zip:	AUSTIN, TX 787416831
Facility Type:	Recycling and Recovery Facility
Program:	MSW-NOI
Additional Id:	100312
Legal Status:	ACKNOWLEDGED
Physical Site Status:	ACTIVE
RN:	RN106141989
Region:	REGION 11 - AUSTIN
Near Physical Loc Address:	Not reported
Near Physical Loc City/State/Zip:	AUSTIN, TX 78741
Legal Status Date:	08/30/2011
Latitude:	30.22350
Longitude:	-97.68807

ASBESTOS:

Name:	NATIONAL HME
Address:	1340 AIRPORT COMMERCE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	10/17/2012
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.7
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	10/23/2012
Date Routed by Supervisor:	10/29/2012
Date Routed to PSQA:	10/30/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

ROUND2 INC. (Continued) **S111326163**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NATIONAL HME
Address:	1340 AIRPORT COMMERCE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	10/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.8
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

ROUND2 INC. (Continued) **S111326163**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

COMP HIST:

RN Number:	RN106141989
Name:	ROUND 2
Address:	1340 AIRPORT COMMERCE DR STE 3300
City,State,Zip:	AUSTIN, TX 787416831
Region:	REGION 11 - AUSTIN
CN Number:	CN603510413
CN Name:	ROUND2 INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022

ROUND2 INC. (Continued) **S111326163**

Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	423930
SIC Code:	5541
Related Number:	100312,100312

JD1406 **ROUND2, INC.** **RCRA-VSQG** **1014473467**
South **1340 AIRPORT COMMERCE DR., BLDG. 3** **TXR000080327**
< 1/8 **AUSTIN, TX 78741**
0.021 mi.
113 ft. **Site 2 of 2 in cluster JD**

Actual:
484 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20110606
Handler Name:	Round2, Inc.
Handler Address:	AIRPORT COMMERCE DR., BLDG. 3
Handler City,State,Zip:	AUSTIN, TX 78741-6836
EPA ID:	TXR000080327
Contact Name:	PATRICK ARNOLD
Contact Address:	AIRPORT COMMERCE DR., BLDG. 3
Contact City,State,Zip:	AUSTIN, TX 78741-6836
Contact Telephone:	512-342-8855
Contact Fax:	Not reported
Contact Email:	PATRICK.ARNOLD@ROUND2.NET
Contact Title:	PLANT MGR
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	AIRPORT COMMERCE DR., BLDG. 3
Mailing City,State,Zip:	AUSTIN, TX 78741-6836
Owner Name:	Sfsv Hill Airport Commerce Lp
Owner Type:	Private
Operator Name:	Round2 Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

ROUND2, INC. (Continued) **1014473467**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20110606
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: ROUND2 INC	
Legal Status:	Private
Date Became Current:	20110519
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: SFSV HILL AIRPORT COMMERCE LP	
Legal Status:	Private
Date Became Current:	20110519
Date Ended Current:	Not reported
Owner/Operator Address:	1111 W 11TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ROUND2, INC. (Continued) **1014473467**

Historic Generators:

Receive Date:	20110606
Handler Name: ROUND2, INC.	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	42343
NAICS Description:	COMPUTER AND COMPUTER PERIPHERAL EQUIPMENT AND SOFTWARE MERCHANT WHOLESALERS
NAICS Code:	42393
NAICS Description:	RECYCLABLE MATERIAL MERCHANT WHOLESALERS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

IK1407 **PEARL STEAM LAUNDRY ROBERT STOCKER PROPI M. M. B** **EDR Hist Cleaner** **1013787213**
WNW **819 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.021 mi.
113 ft. **Site 4 of 5 in cluster IK**

Actual:
507 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1896	PEARL STEAM LAUNDRY ROBERT STO	LAUNDRIES

IK1408 **TEXACO WINDPOWER CO** **EDR Hist Auto** **1021416469**
WNW **823 CONGRESS AVE 515** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.021 mi.
113 ft. **Site 5 of 5 in cluster IK**

Actual:
507 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2002	TEXACO WINDPOWER CO	Gasoline Service Stations
2011	STEVES GARAGE LLC	General Automotive Repair Shops

DF1409 WNW < 1/8 0.021 mi. 113 ft. — **RAPP BROS NEWS DLR AND CLO CLNRS**, **617 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013784389** / **N/A**

Site 10 of 25 in cluster DF

Actual: 496 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1940	RAPP BROS NEWS DLRS	CLOTHES PRESSERS AND CLEANERS
1947	RAPP BROS NEWS DLR AND CLO CLNR	CLOTHES PRESSERS AND CLEANERS

DT1410 NE < 1/8 0.021 mi. 113 ft. — **O. A. TIROFF**, **610 E 6TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678761** / **N/A**

Site 2 of 2 in cluster DT

Actual: 475 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	O. A. TIROFF
Address:	610 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0076
HID UST:	76
Inspection:	Not reported
Due:	06/01/2012

DU1411 SW < 1/8 0.022 mi. 114 ft. — **FINLEY**, **509 E 5TH ST**, **AUSTIN, TX 78701** — **TX LPST**, **TX UST**, **TX HIST UST** — **U001283932** / **N/A**

Site 12 of 19 in cluster DU

Actual: 475 ft.
Focus Map: 11

LPST:

Name:	THE TUNNEL CLUB
Address:	509 E 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0053521
LPST Id:	096081
Facility Location:	509 E 5TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/01/1990
Entered Date:	07/09/1990
Reported Date:	06/01/1990
Closure Date:	10/01/1991
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	MICHAEL BAME
Responsible Party Name:	Not reported
Responsible Party Contact:	TIM FINLEY
Responsible Party Address:	PO BOX 2086
Responsible Party City,St,Zip:	AUSTIN, TX 78768

FINLEY (Continued) **U001283932**

Responsible Party Telephone:	512/478-0885
Reported Date:	06/01/1990
Case Start Date:	10/01/1991
Reference Number:	RN101497956
Project Manager:	MBAME

UST:

Name:	FINLEY
Address:	509 E 5TH ST
City,State,Zip:	AUSTIN, TX 787013725
AI Number:	53521
Facility Type:	RETAIL
Facility Begin Date:	05/04/1990
Facility Status:	INACTIVE
Additional ID:	599745282002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	FINLEY COMPANY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124780885
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/26/1990
Signature Name/Title On Earliest Reg Form:	CARL A TEINERT,V PRES
Application Received Date On Earliest Reg Form:	04/25/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600785182
Owner Last Name:	FINLEY COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

FINLEY (Continued) **U001283932**

Contact Address Deliverable:	Not reported
Princ ID:	589745272002053
Additional ID:	599745282002053
AI Number:	53521
Owner Effective Begin Date:	05/04/1990
State Tax ID:	15102975099
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/25/1990
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	131800
Facility ID:	83382
Ai Number:	53521
Tank Id:	3NORTH
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

FINLEY (Continued) **U001283932**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	3NORTH
Tank Capacity:	2000
UST Comprt ID:	125563
UST ID:	131800
AI Number:	53521
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

FINLEY (Continued) **U001283932**

Stage 1 Installation Date:	Not reported
Install Date:	08/31/1987
Tank Registration Date:	04/25/1990
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	131799
Facility ID:	83382
Ai Number:	53521
Tank Id:	2MIDDLE
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

FINLEY (Continued) **U001283932**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	2MIDDLE
Tank Capacity:	2000
UST Comprt ID:	125562
UST ID:	131799
AI Number:	53521
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	04/25/1990
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	Y

FINLEY (Continued) **U001283932**

Tank Doublewall:	N
Pipe Type:	S
UST ID:	131798
Facility ID:	83382
Ai Number:	53521
Tank Id:	1SOUTH
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

FINLEY (Continued) **U001283932**

Compartment Records:

Tank ID:	1SOUTH
Tank Capacity:	5000
UST Comprt ID:	125561
UST ID:	131798
AI Number:	53521
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FINLEY COMPANY
Contact Mailing Address (Delivery):	PO BOX 2086
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78768 2086
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83382
Additional ID:	599745282002053
Princ ID:	589745272002053

FINLEY (Continued) **U001283932**

AI Number: 53521
Facility Name: FINLEY
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: TIM FINLEY/

HIST UST AUSTIN:
Name: FINLEY CO
Address: 509 E 5TH ST
City,State,Zip: AUSTIN, TX
Id UST: C0155
HID UST: Not reported
Inspection: Not reported
Due: Not reported

EW1412 **E. C. STEWART** **TX HIST UST** **S111678632**
WNW **1300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 8 of 11 in cluster EW**

Actual:
512 ft.

Focus Map:
14

HIST UST AUSTIN:
Name: E. C. STEWART
Address: 1300 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: H0111
HID UST: 111
Inspection: Not reported
Due: 06/01/2012

EW1413 **TRIBBLE ADV. COMPANY** **TX HIST UST** **S111678840**
WNW **1300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 9 of 11 in cluster EW**

Actual:
512 ft.

Focus Map:
14

HIST UST AUSTIN:
Name: TRIBBLE ADV. COMPANY
Address: 1300 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: H0558
HID UST: 558
Inspection: Not reported
Due: 06/01/2012

EW1414 WNW < 1/8 0.022 mi. 114 ft. — **A. A. ECK, 1300 S CONGRESS AVE, AUSTIN, TX** — **TX HIST UST** — **S111678535 / N/A**

Site 10 of 11 in cluster EW

Actual: 512 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	A. A. ECK
Address:	1300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0151
HID UST:	151
Inspection:	Not reported
Due:	06/01/2012

EW1415 WNW < 1/8 0.022 mi. 114 ft. — **MR. J. M. CAPERTON, 1300 S CONGRESS AVE, AUSTIN, TX** — **TX HIST UST** — **S111678752 / N/A**

Site 11 of 11 in cluster EW

Actual: 512 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	MR. J. M. CAPERTON
Address:	1300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0044
HID UST:	44
Inspection:	Not reported
Due:	06/01/2012

DF1416 WNW < 1/8 0.022 mi. 114 ft. — **RAPP BROS NEWS DLRS, 621 CONGRESS AVE, AUSTIN, TX** — **EDR Hist Cleaner** — **1013784390 / N/A**

Site 11 of 25 in cluster DF

Actual: 497 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1935	RAPP BROS NEWS DLRS	CLOTHES PRESSERS AND CLEANERS

AQ1417 ESE < 1/8 0.022 mi. 114 ft. — **7-ELEVEN 24008, 5101 N LAMAR BLVD, AUSTIN, TX 78751** — **TX LPST, TX UST, TX ASBESTOS, TX Financial Assurance, TX GCC, TX RDR, TX CENTRAL REGISTRY** — **U001243592 / N/A**

Site 5 of 9 in cluster AQ

Actual: 666 ft.
Focus Map: 8

LPST:

Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120589

7-ELEVEN 24008 (Continued) **U001243592**

Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	02/05/2018
Entered Date:	10/11/2018
Reported Date:	02/06/2018
Closure Date:	09/17/2021
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	02/06/2018
Case Start Date:	09/17/2021
Reference Number:	RN102015401
Project Manager:	RKRAFT

UST:

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787512319
AI Number:	7169
Facility Type:	RETAIL
Facility Begin Date:	01/01/1982
Facility Status:	ACTIVE
Additional ID:	751041712002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/21/2018
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,REGION COMPLIANCE MANAGER
Application Received Date On Earliest Reg Form:	06/25/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No

7-ELEVEN 24008 (Continued) **U001243592**

Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	751041712002117
Ai Number:	7169
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	751041712002117
AI Number:	7169
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46171
Cert ID:	381577
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	364253
AI Number:	7169
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	347239
AI Number:	7169
Self Certification Date:	01/12/2021
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	330873
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	314559
AI Number:	7169
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	306099
AI Number:	7169
Self Certification Date:	06/21/2018
Signature Name/Title:	RAYMOND MCNIECE REGION COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	296367
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	12/28/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	280579
AI Number:	7169
Self Certification Date:	01/18/2017
Signature Name/Title:	Raymond Mcniece Enironmental Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	263382
AI Number:	7169
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	246734
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	01/15/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	230068
AI Number:	7169
Self Certification Date:	01/13/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46171
Cert ID:	28072
AI Number:	7169
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28071
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	12/15/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28070
AI Number:	7169
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28069
AI Number:	7169
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28068
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28067
AI Number:	7169
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28066
AI Number:	7169
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28065
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	28064
AI Number:	7169
Self Certification Date:	12/14/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	27849
AI Number:	7169
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	27848
AI Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	27847
AI Number:	7169
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46171
Cert ID:	27846
AI Number:	7169
Self Certification Date:	01/17/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986

7-ELEVEN 24008 (Continued) **U001243592**

Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18597
Facility ID:	46171
Ai Number:	7169
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/05/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y

7-ELEVEN 24008 (Continued) **U001243592**

Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26074
UST ID:	18597
AI Number:	7169
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18598
Facility ID:	46171
Ai Number:	7169

7-ELEVEN 24008 (Continued) **U001243592**

Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/05/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26075
UST ID:	18598

7-ELEVEN 24008 (Continued) **U001243592**

AI Number:	7169
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18599
Facility ID:	46171
Ai Number:	7169
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/05/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

7-ELEVEN 24008 (Continued) **U001243592**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26076
UST ID:	18599
AI Number:	7169
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

7-ELEVEN 24008 (Continued) **U001243592**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	06/14/2018
Tank Registration Date:	06/21/2018
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	223175
Facility ID:	46171
Ai Number:	7169
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	06/14/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

7-ELEVEN 24008 (Continued) **U001243592**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/15/2018

Compartment Records:

Tank ID:	4
Tank Capacity:	15000
UST Comprt ID:	193217
UST ID:	223175
AI Number:	7169
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

7-ELEVEN 24008 (Continued) **U001243592**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	06/14/2018
Tank Registration Date:	06/21/2018
Number of Compartments:	2
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	223176
Facility ID:	46171
Ai Number:	7169
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	06/14/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

7-ELEVEN 24008 (Continued) **U001243592**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/15/2018

Compartment Records:

Tank ID:	5
Tank Capacity:	7000
UST Comprt ID:	193218
UST ID:	223176
AI Number:	7169
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

7-ELEVEN 24008 (Continued) **U001243592**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Tank ID:	5
Tank Capacity:	8000
UST Comprt ID:	193219
UST ID:	223176
AI Number:	7169
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

7-ELEVEN 24008 (Continued) **U001243592**

Construction Notification:

NOC ID:	32327
Facility ID:	46171
AI Number:	7169
Application Received Date:	12/15/2017
Scheduled Construction Date:	01/13/2018
UST Improvement:	N
UST Installation:	Y
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	12/15/2017
Signature Date On Form:	12/14/2017
Signature Name On Form:	ANTHONY LEWIS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL OF EXISTING FUEL SYSTEM AND INSTALLATION OF 1-20K (12K & 8K SPLIT), USTS, DISPENSERS, AND PIPING

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	76463
UST ID:	Not reported
NOC ID:	32327
AI Number:	7169
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	APTIM
Representative Name:	MONIKA KAUFMAN
Mailing Address (Delivery):	1250 CAPITAL OF TX HWY S BLDG 3
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN 24008 (Continued) **U001243592**

Cont/Cons/Installer ID:	76462
UST ID:	Not reported
NOC ID:	32327
AI Number:	7169
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK & PUMP SERVICES INC
Representative Name:	ANTHONY LEWIS
Mailing Address (Delivery):	PO BOX 170398
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	78676
UST ID:	223176
NOC ID:	Not reported
AI Number:	7169
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK AND PUMP SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	78675
UST ID:	223175
NOC ID:	Not reported
AI Number:	7169
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK & PUMP SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported

7-ELEVEN 24008 (Continued) **U001243592**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	76464
UST ID:	Not reported
NOC ID:	32327
AI Number:	7169
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	78669
UST ID:	223175
NOC ID:	Not reported
AI Number:	7169
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645

7-ELEVEN 24008 (Continued) **U001243592**

Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	78670
UST ID:	223176
NOC ID:	Not reported
AI Number:	7169
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46171
Additional ID:	751041712002117
Princ ID:	959578622001257
AI Number:	7169
Facility Name:	7-ELEVEN 24008
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

ASBESTOS:

Name:	7-ELEVEN
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	05/30/2013
Reason for Inspection:	Routine

7-ELEVEN 24008 (Continued) **U001243592**

Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/03/2013
Date Routed by Supervisor:	06/03/2013
Date Routed to PSQA:	06/06/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

7-ELEVEN 24008 (Continued) **U001243592**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	7-ELEVEN
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	08/07/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/11/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

7-ELEVEN 24008 (Continued) **U001243592**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	278702
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	261551
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN 24008 (Continued) **U001243592**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	242258
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	223521
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000

7-ELEVEN 24008 (Continued) **U001243592**

Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	224121
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	207930
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171

7-ELEVEN 24008 (Continued) **U001243592**

Finass ID:	189238
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	172743
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	154086
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN 24008 (Continued) **U001243592**

Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	138247
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	120381
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 24008 (Continued) **U001243592**

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	1540
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28789
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28790
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 24008 (Continued) **U001243592**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28791
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28792
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277

7-ELEVEN 24008 (Continued) **U001243592**

Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28793
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	46171
Finass ID:	28794
AI:	7169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	06/25/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD

7-ELEVEN 24008 (Continued) **U001243592**

City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: *
File Number: 120589
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 2/6/2018
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: Not reported
Section 5236: Not reported
Type: 2019 GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 7 ELEVEN STORE 24008
Address: 5101 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 120589
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 2/6/2018
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A - Investigation
Data Quality 1: E,Q
Section 5236: Not reported
Type: Not reported
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 7 ELEVEN STORE 24008
Address: 5101 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 120589
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 2/6/2018
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 - Action Completed
Data Quality 1: E,Q
Section 5236: Not reported
Type: Not reported
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

7-ELEVEN 24008 (Continued) **U001243592**

RDR:

RDR ID:	25954
Facility ID:	7169
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/1/2018
Due Date:	9/30/2018
Tank Owner:	7 ELEVEN INC
Contact Person:	JOSE RIOS
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/11/2018
Project Manager:	Ryan Kraft
Team:	#N/A
New LPST Number:	120589
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329

7-ELEVEN 24008 (Continued) **U001243592**

Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION

7-ELEVEN 24008 (Continued) **U001243592**

Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1982-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/1/1982
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102015401
Name:	7 ELEVEN STORE 24008
Address:	5101 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-2319
Status:	ACTIVE
Status Date:	4/27/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/1/1982
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

7-ELEVEN 24008 (Continued) **U001243592**

Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: Not reported

AQ1418 **7-ELEVEN #24008** **TX RDR** **S127538730**
ESE **5101 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 6 of 9 in cluster AQ**

Actual:
666 ft.

Focus Map:
8

RDR:

RDR ID:	9684
Facility ID:	7169
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN #24008
Address:	5101 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	SOUTHLAND
Contact Person:	K. JANE LOMAS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/30/1996
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 19
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/30/1996
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AQ1419 **SEVEN ELEVEN #24008** **TX HIST UST** **S128728831**
ESE **5101 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 7 of 9 in cluster AQ**

Actual:
666 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #24008
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	807
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AQ1420 **W. L. BROWN** **TX HIST UST** **S128729328**
ESE **5101 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 8 of 9 in cluster AQ**

Actual:
666 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	W. L. BROWN
Address:	5101 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0575
HID UST:	575
Inspection:	06/15/2011
Due:	06/15/2014

AQ1421 **7 ELEVEN 24008** **TX RDR** **S127538729**
ESE **5101 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
114 ft. **Site 9 of 9 in cluster AQ**

Actual:
666 ft.

Focus Map:
8

RDR:

RDR ID:	19029
Facility ID:	7169
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 24008
Address:	5101 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/14/2010
Due Date:	9/12/2010
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	9/9/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	9/9/2010
Region:	Not reported
DKC RDR (misfiled):	Not reported

DF1422 **PATTONS AUTO HOTEL** **EDR Hist Auto** **1013758137**
WNW **116 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
115 ft. **Site 12 of 25 in cluster DF**

Actual:
497 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	PATTONS AUTO HOTEL	AUTOMOBILE SERVICE STATIONS

DU1423 **A.E. MASSENGALE** **TX HIST UST** **S111678539**
SW **507 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
115 ft. **Site 13 of 19 in cluster DU**

Actual:
475 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	A.E. MASSENGALE
Address:	507 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0433
HID UST:	433
Inspection:	Not reported
Due:	06/01/2012

FT1424 **BEN H. POWELL** **TX HIST UST** **S111678573**
WNW **2304 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
116 ft. **Site 13 of 15 in cluster FT**

Actual:
597 ft.
HIST UST AUSTIN:

Focus Map:
14

Name:	BEN H. POWELL
Address:	2304 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0382
HID UST:	382
Inspection:	04/24/2009
Due:	04/24/2012

FT1425 **GULF OIL COMPANY** **TX HIST UST** **S111678657**
WNW **2304 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
116 ft. **Site 14 of 15 in cluster FT**

Actual:
597 ft.
HIST UST AUSTIN:

Focus Map:
14

Name:	GULF OIL COMPANY
Address:	2304 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0380
HID UST:	380
Inspection:	03/04/2009
Due:	03/04/2012

JE1426 **LYNDON B JOHNSON BUILDING** **TX AST** **A100327266**
ESE **111 E 17TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.022 mi.
117 ft. **Site 1 of 6 in cluster JE**

Actual:
530 ft.

Focus Map:
11

AST:

Name:	LYNDON B JOHNSON BUILDING
Address:	111 E 17TH ST
City,State,Zip:	AUSTIN, TX 787011403
Facility ID:	123780
Additional ID:	616479882010130
AI Number:	79795
Facility Type:	Not reported
Facility Begin Date:	12/19/2008
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78701
Contact Name/Title:	KOY LIVINGSTON/BLDG MGR
Contact Organization Name:	LYNDON B JOHNSON BUILDING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124633237
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	02/20/2009
Signature First Name on Earliest Reg Form:	MEL
Application Received Date on Earliest Reg Form:	03/13/2009
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	BULLOCK
Signature Title on Earliest Reg Form:	PHYS PLT MGR
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	123780
Tank ID:	1
AST ID:	211994
AI Number:	79795
Install Date:	12/19/2008
Tank Registration Date:	03/13/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	12/19/2008
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000

LYNDON B JOHNSON BUILDING (Continued) **A100327266**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

JE1427 **COMPTROLLER OF PUBLIC ACCOUNTS** **RCRA NonGen / NLR** **1000884648**
ESE **111 E 17TH ST** **FINDS** **TXD981914955**
< 1/8 **AUSTIN, TX 78774** **ECHO**
0.022 mi.
117 ft. **Site 2 of 6 in cluster JE**

Actual:
530 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Comptroller Of Public Accounts
Handler Address:	E 17TH ST
Handler City,State,Zip:	AUSTIN, TX 78774
EPA ID:	TXD981914955
Contact Name:	GILLMORE KRUEGER
Contact Address:	E 17TH ST
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Telephone:	512-463-4112
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E 17TH ST
Mailing City,State,Zip:	AUSTIN, TX 78774
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000884648**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE OF TEXAS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19870515

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000884648**

Handler Name: TEXAS COMPTROLLER PROCESSING DEP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: COMPTROLLER OF PUBLIC ACCOUNTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005100381

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000884648**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000884648
Registry ID:	110005100381
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005100381
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
City,State,Zip:	AUSTIN, TX 78774

JE1428 **COMPTROLLER OF PUBLIC ACCOUNTS** **TX ASBESTOS** **S105479936**
ESE **111 E 17TH ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78774** **TX CENTRAL REGISTRY**
0.022 mi.
117 ft. **Site 3 of 6 in cluster JE**

Actual:
530 ft.

Focus Map:
11

ASBESTOS:

Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Lance Anderson
Violation:	Not reported
Complaint Date:	03/25/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/23/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/23/2022
Certification Statement Phone:	8322587602
Is The Facility a School or K-12?:	N

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Lance T Anderson
Violation:	Not reported
Complaint Date:	03/25/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/21/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/21/2022
Certification Statement Phone:	832-258-7602
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Lance Anderson
Violation:	Not reported
Complaint Date:	03/25/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/22/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/22/2022
Certification Statement Phone:	8322587602
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	09/16/2018
Notification Number:	2018006682
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/06/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	09/16/2018
Notification Number:	2018006682
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/24/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/24/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	Y
Ordered:	N

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	06/11/2021
Notification Number:	2021002745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/23/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/23/2021
Certification Statement Phone:	210-872-6781
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	206
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/26/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	06/04/2021
Notification Number:	2021002745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/09/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/09/2021
Certification Statement Phone:	210-872-6781
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	206
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Violation:	Not reported
Complaint Date:	06/11/2021
Notification Number:	2021002745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/17/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/17/2021
Certification Statement Phone:	210-872-6781
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	206
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/24/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	05/28/2021
Notification Number:	2021002745
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/26/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/26/2021
Certification Statement Phone:	210-872-6781
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	206
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Start Date:	05/10/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	06/17/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Certification Statement Date:	06/15/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	94
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	02/02/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/06/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/06/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	188
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	02/02/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/18/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	188
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	05/02/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/01/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/01/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	188
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	06/10/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/29/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

ARU:	94
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	06/15/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/23/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/23/2022
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	94
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/28/2022
Notification Number:	2021008453
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/16/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	188
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH ST

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	07/29/2022
Notification Number:	2022004068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/27/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/05/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	07/27/2022
Notification Number:	2022004068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/22/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/22/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/05/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LYNDON BAINES JOHNSON STATE OFFICE BUILDING 12 -STORY HIGH RISE
Address:	111 E 17TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	07/22/2022
Notification Number:	2022004068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	06/19/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/19/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/05/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/08/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Report Received:	11/30/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/30/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	10/31/2020

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/15/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	10/31/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/05/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/05/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	10/31/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/23/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/23/2020
Certification Statement Phone:	512-576-2019

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/02/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/16/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/02/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/09/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/18/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	10/31/2020
Notification Number:	2020003222
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/01/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/01/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/17/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 E.17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/15/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019008058
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/30/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/30/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	313
Is this a phased abatement project?:	Y
Ordered:	N

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/15/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 E.17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/15/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2019008058
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/06/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	316
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/16/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/16/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/26/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/17/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/17/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/25/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/23/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/23/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Start Date:	08/25/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/25/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Certification Statement Date:	08/25/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/26/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/13/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/13/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/26/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LBJ STATE OFFICE BLDG
Address:	111 EAST 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Franklin W Wiget
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2021005430
ASB Priority:	Not reported
PIF State:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/04/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	282
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	LBJ STATE OFFICE BUILDING
Address:	111 E. 17TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/02/2019
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	01/20/2019
Notification Number:	2019000001
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/02/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/02/2019
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
City,State,Zip:	AUSTIN, TX 78774
Permit Number:	Not reported
Registration Number:	72462
Registration Initial Notification Date:	05/08/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981914955
Primary NAICS Code:	Not reported
Status Change Date:	19870508
Land Type:	Not reported
Description of Facility Site Location:	111 E 17th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Contact Name:	GILLMORE KRUEGER
Contact Telephone Number:	512-4634112
Mailing Address:	111 E 17TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787741440
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26902
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Owner Mailing Address:	111 E 17TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78774
Owner Country:	UNITED STA
Owner Telephone:	1-512-4634112
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	111 E 17TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Phone:	1-512-4634112
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	GILLMORE KRUEGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	111 E 17TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Phone:	1-512-4634112
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	111 E 17TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78774
AR Number:	0000303997

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Principal Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	111 E 17TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78774
AR Number:	0000303997
Principal Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	111 E 17TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78774
AR Number:	0000303997
Principal Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	111 E 17TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78774
AR Number:	0000303997
Principal Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Attention Name:	Not reported
Attention Suffix:	HWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521629
Customer Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Customer Legal Name:	Comptroller of Public Accounts
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521629
Customer Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Customer Legal Name:	Comptroller of Public Accounts
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603527441
Customer Name:	TEXAS FACILITIES COMMISSION
Customer Legal Name:	Texas Facilities Commission
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	12/19/2008
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603527441
Customer Name:	TEXAS FACILITIES COMMISSION
Customer Legal Name:	Texas Facilities Commission
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	12/19/2008
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521629
Customer Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Customer Legal Name:	Comptroller of Public Accounts
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479936**

Status Date:	##########
Customer Number:	CN603527441
Customer Name:	TEXAS FACILITIES COMMISSION
Customer Legal Name:	Texas Facilities Commission
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	12/19/2008
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

Regulated Entity Number:	RN100843515
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 E 17TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78774-1440
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E 17th St, Austin, TX

1429 East < 1/8 0.022 mi. 117 ft. **STADIUM DRY CLEANERS** **EDR Hist Cleaner** **1013779732**
2107 SPEEDWAY **N/A**
AUSTIN, TX

Actual: 540 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	STADIUM DRY CLEANERS	CLOTHES CLEANERS AND PRESSERS

DY1430 SSW < 1/8 0.022 mi. 118 ft. **WARDROBE CLNRS** **EDR Hist Cleaner** **1013782110**
213 CONGRESS AVE **N/A**
AUSTIN, TX
Site 6 of 11 in cluster DY

Actual: 477 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1922	LAWSHA LEE C CLDO	CLOTHES CLEANERS AND PRESSERS
1935	WARDROBE CLNRS	CLOTHES PRESSERS AND CLEANERS

DY1431 SSW < 1/8 0.022 mi. 118 ft. | **MOTORCYCLE SALES**
213 CONGRESS AVE
AUSTIN, TX
Site 7 of 11 in cluster DY | **EDR Hist Auto** | **1013757799**
N/A

Actual: 477 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	MOTORCYCLE SALES	MOTORCYCLE DEALERS AND REPAIRERS

JF1432 ESE < 1/8 0.022 mi. 118 ft. | **LOOMIS ARMORED AUSTIN**
78 EAST AVE
AUSTIN, TX 78701
Site 1 of 3 in cluster JF | **TX UST** | **U001269523**
N/A

Actual: 459 ft.

Focus Map: 14

UST:

Name:	LOOMIS ARMORED AUSTIN
Address:	78 EAST AVE
City,State,Zip:	AUSTIN, TX 787014315
AI Number:	36668
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/01/1989
Facility Status:	INACTIVE
Additional ID:	707116112002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	LOOMIS ARMORED AUSTIN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124767592
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/17/1986
Signature Name/Title On Earliest Reg Form:	TOMMY HARDEN,STAFF VP
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600277073
Owner Last Name:	LOOMIS ARMORED US INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

LOOMIS ARMORED AUSTIN (Continued) **U001269523**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	10330612001297
Additional ID:	707116112002117
AI Number:	36668
Owner Effective Begin Date:	09/01/1989
State Tax ID:	17501172005
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	97025
Facility ID:	51389
Ai Number:	36668
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/23/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

LOOMIS ARMORED AUSTIN (Continued) **U001269523**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	49849
UST ID:	97025
AI Number:	36668
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

LOOMIS ARMORED AUSTIN (Continued) **U001269523**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14244
Cert ID:	48643
UST Comprt ID:	128309
UST ID:	53622
AI Number:	36668
Tank ID:	4
Compartment ID:	A

Self Cert ID:	14244
Cert ID:	48645
UST Comprt ID:	128310
UST ID:	53622
AI Number:	36668
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	LOOMIS FARGO & CO
Contact Mailing Address (Delivery):	10202 MILLER RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75238 1217
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	51389
Additional ID:	707116112002117
Princ ID:	10330612001297
AI Number:	36668
Facility Name:	LOOMIS ARMORED AUSTIN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	TOMMY HARDEN/

IU1433 **EVANS TEXACO** **TX LPST** **U001253682**
WNW **4712 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX HIST UST**
0.022 mi.
118 ft. **Site 3 of 6 in cluster IU**

Actual:
642 ft.

Focus Map:
17

LPST:

Name:	FORMER EVANS TEXACO
Address:	4712 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0018769
LPST Id:	095403
Facility Location:	S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/18/1990
Entered Date:	05/07/1990
Reported Date:	04/19/1990
Closure Date:	08/31/2004
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3/4/1/3/1
Coordinators RPR:	RWS
Responsible Party Name:	Not reported
Responsible Party Contact:	KAY THURMAN
Responsible Party Address:	4602 COPANO CT
Responsible Party City,St,Zip:	AUSTIN, TX 78749
Responsible Party Telephone:	512/280-1517
Reported Date:	04/19/1990
Case Start Date:	08/31/2004
Reference Number:	RN101494490
Project Manager:	RSHAVER

UST:

Name:	EVANS TEXACO
Address:	4712 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787452303
AI Number:	18769
Facility Type:	RETAIL
Facility Begin Date:	09/04/1986
Facility Status:	INACTIVE
Additional ID:	13656422002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	J L EVANS,LESSEE
Contact Organization Name:	EVANS TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

EVANS TEXACO (Continued) **U001253682**

Contact Telephone:	5124416333
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/03/1986
Signature Name/Title On Earliest Reg Form:	J L EVANS,LESSEE
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600782445
Owner Last Name:	HAZEL GOODNIGHT TRUST
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	3656412002053
Additional ID:	13656422002053
AI Number:	18769
Owner Effective Begin Date:	09/04/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	48776
Facility ID:	56596
Ai Number:	18769
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

EVANS TEXACO (Continued) **U001253682**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	45388
UST ID:	48776
AI Number:	18769
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EVANS TEXACO (Continued) **U001253682**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7225
Cert ID:	28670
UST Comprt ID:	87895
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28667
UST Comprt ID:	87896
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28668
UST Comprt ID:	87897
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28669

EVANS TEXACO (Continued) **U001253682**

UST Comprt ID:	87898
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28672
UST Comprt ID:	87893
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28673
UST Comprt ID:	87892
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28674
UST Comprt ID:	87891
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28671
UST Comprt ID:	87894
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	48777
Facility ID:	56596
Ai Number:	18769
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

EVANS TEXACO (Continued) **U001253682**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	45389
UST ID:	48777
AI Number:	18769
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EVANS TEXACO (Continued) **U001253682**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7225
Cert ID:	28670
UST Comprt ID:	87895
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28667
UST Comprt ID:	87896
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28668
UST Comprt ID:	87897
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28669

EVANS TEXACO (Continued) **U001253682**

UST Comprt ID:	87898
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28672
UST Comprt ID:	87893
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28673
UST Comprt ID:	87892
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28674
UST Comprt ID:	87891
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28671
UST Comprt ID:	87894
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	48775
Facility ID:	56596
Ai Number:	18769
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

EVANS TEXACO (Continued) **U001253682**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	45387
UST ID:	48775
AI Number:	18769
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EVANS TEXACO (Continued) **U001253682**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7225
Cert ID:	28670
UST Comprt ID:	87895
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28667
UST Comprt ID:	87896
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28668
UST Comprt ID:	87897
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28669

EVANS TEXACO (Continued) **U001253682**

UST Comprt ID:	87898
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28672
UST Comprt ID:	87893
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28673
UST Comprt ID:	87892
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28674
UST Comprt ID:	87891
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28671
UST Comprt ID:	87894
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	48779
Facility ID:	56596
Ai Number:	18769
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

EVANS TEXACO (Continued) **U001253682**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	500
UST Comprt ID:	45391
UST ID:	48779
AI Number:	18769
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EVANS TEXACO (Continued) **U001253682**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7225
Cert ID:	28670
UST Comprt ID:	87895
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28667
UST Comprt ID:	87896
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28668
UST Comprt ID:	87897
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28669

EVANS TEXACO (Continued) **U001253682**

UST Comprt ID:	87898
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28672
UST Comprt ID:	87893
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28673
UST Comprt ID:	87892
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28674
UST Comprt ID:	87891
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28671
UST Comprt ID:	87894
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	48778
Facility ID:	56596
Ai Number:	18769
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

EVANS TEXACO (Continued) **U001253682**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	45390
UST ID:	48778
AI Number:	18769
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EVANS TEXACO (Continued) **U001253682**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7225
Cert ID:	28670
UST Comprt ID:	87895
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28667
UST Comprt ID:	87896
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28668
UST Comprt ID:	87897
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28669

EVANS TEXACO (Continued) **U001253682**

UST Comprt ID:	87898
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28672
UST Comprt ID:	87893
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28673
UST Comprt ID:	87892
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28674
UST Comprt ID:	87891
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7225
Cert ID:	28671
UST Comprt ID:	87894
UST ID:	26192
AI Number:	18769
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	HAZEL GOODNIGHT TRUST
Contact Mailing Address (Delivery):	9608 DERECHO DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78737 1001
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	56596
Additional ID:	13656422002053
Princ ID:	3656412002053
AI Number:	18769
Facility Name:	EVANS TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PAUL H WENDLER/

EVANS TEXACO (Continued) **U001253682**

HIST UST AUSTIN:

Name:	EVAN'S TEXACO
Address:	4712 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	1736
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IU1434 **STEWART W T TEXACO** **EDR Hist Auto** **1013770600**
WNW **4712 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.022 mi.
118 ft. **Site 4 of 6 in cluster IU**

Actual:
642 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1958	STEWART W T TEXACO	GASOLINE STATIONS

IU1435 **MURPHY R L TEX** **EDR Hist Auto** **1013763918**
WNW **4712 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.022 mi.
118 ft. **Site 5 of 6 in cluster IU**

Actual:
642 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1962	MURPHY R L TEX	GASOLINE STATIONS

IU1436 **CLAWSONS TEXACO SERVICE STATION** **EDR Hist Auto** **1013754218**
WNW **4712 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.022 mi.
118 ft. **Site 6 of 6 in cluster IU**

Actual:
642 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1965	MURPHYS TEXACO SERVICE	GASOLINE STATIONS
1970	MURPHYS TEXACO SERVICE STATION	GASOLINE STATIONS
1971	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1972	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1973	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1974	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1975	CLAWSONS TEXACO SERVICE STATION	GASOLINE STATIONS
1975	CLAWSONS TEXACO SERVICE	Gasoline Service Stations
1975	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1976	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1977	MURPHY TEXACO SERVICE STATION	Gasoline Service Stations
1980	EVANS TEXACO SERVICE STATION	GASOLINE STATIONS
1984	EVANS TEXACO	GASOLINE STATIONS

CLAWSONS TEXACO SERVICE STATION (Continued) **1013754218**

1988	EVANS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1989	EVANS AUTOMOTIVE SERVICE	General Automotive Repair Shops
1990	EVANS TEXACO	GASOLINE STATIONS
1990	EVANS AUTOMOTIVE SERVICE	General Automotive Repair Shops

---

CV1437 **MODEL STEAM LAUNDRY** **EDR Hist Cleaner** **1013782993**
WNW **112 10TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.022 mi.
118 ft. **Site 7 of 14 in cluster CV**

Actual:
513 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	MODEL STEAM LAUNDRY	LAUNDRIES

1438 **JAMES DREW RENTAL** **TX LPST** **S111748379**
ESE **406 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.023 mi.
119 ft.

Actual:
582 ft.

Focus Map:
14

LPST:

Name:	JAMES DREW RENTAL
Address:	406 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0014512
LPST Id:	118788
Facility Location:	406 EAST AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	04/17/2012
Reported Date:	04/17/2012
Closure Date:	09/25/2012
Priority:	3.2 - IMPACTED GW W/IN 500FT-0.25MI TO SW USED BY HUMANENDGR SPEC
Program:	11 - VCP
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**PREASSESSMENT/RELEASE DETERMINATION**
Coordinators Primary:	11
Coordinators RPR:	VKM
Responsible Party Name:	Not reported
Responsible Party Contact:	LAURAINE RIZER
Responsible Party Address:	505 BARTON SPRINGS RD
Responsible Party City,St,Zip:	AUSTIN 78704
Responsible Party Telephone:	512/974-7078
Reported Date:	04/17/2012
Case Start Date:	09/25/2012
Reference Number:	RN101491827
Project Manager:	VMODAK

DM1439 **BEAR AUTOMOTIVE I EPR** **EDR Hist Auto** **1013768201**
NNE **405 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.023 mi.
119 ft. **Site 10 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1980	BEAR AUTOMOTIVE I EPR	AUTOMOBILE REPAIRING
1984	ALLMAN BODY SHOP AUTO REPR	AUTOMOBILE REPAIRING

DM1440 **BEAR AUTOMOTIVE REPR** **EDR Hist Auto** **1013771467**
NNE **405 7TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.023 mi.
119 ft. **Site 11 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1975	BEAR AUTOMOTIVE REPR	AUTOMOBILE REPAIRING

DM1441 **ELLIOTTS RADIATOR** **EDR Hist Auto** **1013775589**
NNE **406 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 12 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1935	LOPEZ GARAGE	AUTOMOBILE REPAIRERS
1947	THOMSON FENDER SHOP	AUTOMOBILE REPAIRING
1953	ELLIOTTS RADIATOR	AUTOMOBILE RADIATOR REPAIRING
1953	ELLIOTTS RADIATOR	RADIATOR REPAIRERS-AUTOMOBILE
1958	ELLIOTTS RADIATOR	AUTOMOBILE RADIATOR REPAIRERS
1962	ELLIOTTS RADIATOR	AUTOMOBILE RADIATOR REPAIRERS

DM1442 **ELLIOTTS RADIATOR SHOP** **EDR Hist Auto** **1013775590**
NNE **406 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 13 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1965	ELLIOTTS RADIATOR SHOP	AUTOMOBILE RADIATOR REPAIRERS

DM1443 **ONE DAY CLNS** **EDR Hist Cleaner** **1013785766**
NNE **407 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 14 of 22 in cluster DM**

Actual: EDR Hist Cleaner
498 ft.

Focus Map:
11

Year:	Name:	Type:
1958	ONE DAY CLNS	CLEANERS AND DYERS

DM1444 **GAS MART GR** **EDR Hist Auto** **1013772207**
NNE **409 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 15 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1965	GAS MART GR	GASOLINE STATIONS

DM1445 **AUTO REPAIRS CO** **EDR Hist Auto** **1013768316**
NNE **408 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 16 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1947	KNIGHT R L AUTO REPR	AUTOMOBILE REPAIRING
1953	AUTO REPAIRS CO	AUTOMOBILE REPAIRING
1958	AUTO REPAIRS CO	AUTOMOBILE REPAIRING
1962	JENSENS HARRY	AUTOMOBILE REPAIRING

DM1446 **JENSENS HARRY AUTO REPAIRS** **EDR Hist Auto** **1013760776**
NNE **408 7TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.023 mi.
119 ft. **Site 17 of 22 in cluster DM**

Actual: EDR Hist Auto
498 ft.

Focus Map:
11

Year:	Name:	Type:
1975	JENSENS HARRY AUTO REPAIRS	AUTOMOBILE REPAIRING

DM1447 NNE < 1/8 0.023 mi. 119 ft. | **ALANIZ LOUIS AUTO REPAIRS**
408 7TH ST E
AUSTIN, TX 78701
Site 18 of 22 in cluster DM | **EDR Hist Auto** | **1013762139**
N/A

Actual: 498 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1965	JENSENS HARRY AUTO	AUTOMOBILE REPAIRING
1980	JENSENS HAIRYV AUTO REPAIRS	AUTOMOBILE REPAIRING
1984	ALANIZ LOUIS AUTO REPAIRS	AUTOMOBILE REPAIRING

DM1448 NNE < 1/8 0.023 mi. 119 ft. | **GAS A TERIA INC**
409 7TH E
AUSTIN, TX
Site 19 of 22 in cluster DM | **EDR Hist Auto** | **1013757016**
N/A

Actual: 498 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1953	GAS A TERIA INC	GASOLINE STATIONS

GQ1449 SSW < 1/8 0.023 mi. 119 ft. | **SPEEDYS**
6301 E RIVERSIDE
AUSTIN, TX
Site 12 of 15 in cluster GQ | **TX RDR** | **S127529366**
N/A

Actual: 515 ft.
Focus Map: 15

RDR:

RDR ID:	27392
Facility ID:	29155
RN:	Not reported
CN:	Not reported
Name:	SPEEDYS
Address:	6301 E RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/21/2019
Due Date:	10/20/2019
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	10/21/2019
Project Manager:	Yongrui Tan
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GQ1450 **CITGO GRO** **EDR Hist Auto** **1013753555**
SSW **6301 RIVERSIDE DR** **N/A**
< 1/8 **TRAVIS (County), TX 78741**
0.023 mi.
119 ft. **Site 13 of 15 in cluster GQ**

Actual:
515 ft.

Focus Map:
15

EDR Hist Auto

Year:	Name:	Type:
1980	U PUMP UM NO 2 GAS ST	GASOLINE STATIONS
1984	U PUMP UM NO 2 GAS ST	GASOLINE STATIONS
1986	U PUMPUM INC	Gasoline Service Stations
1987	U PUMPUM INC	Gasoline Service Stations
1988	U PUMPUM INC	Gasoline Service Stations
1989	U PUMPUM INC	Gasoline Service Stations
1990	CITGO GRO	GASOLINE STATIONS
1990	U PUMPUM INC	Gasoline Service Stations
1991	U PUMPUM INC	Gasoline Service Stations
1992	U PUMPUM INC	Gasoline Service Stations
1993	U PUMPUM INC	Gasoline Service Stations

GQ1451 **SPEEDY'S** **TX RDR** **S127529365**
SSW **6301 EAST RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
119 ft. **Site 14 of 15 in cluster GQ**

Actual:
515 ft.

Focus Map:
15

RDR:

RDR ID:	30085
Facility ID:	29155
RN:	101510170
CN:	600787097
Name:	SPEEDY'S
Address:	6301 EAST RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/5/2021
Due Date:	7/4/2021
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	5/24/2021
Project Manager:	Ross Eide
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GQ1452	**SPEEDYS**	**TX UST**	**U001262735**
SSW	**6301 E RIVERSIDE DR**	**TX HIST UST**	**N/A**
< 1/8	**AUSTIN, TX 78741**	**TX SPILLS**	
0.023 mi.		**TX ASBESTOS**	
119 ft.	**Site 15 of 15 in cluster GQ**	**TX Financial Assurance**	
		TX RDR	

Actual:
515 ft.

Focus Map:
15

UST:

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787416613
AI Number:	29155
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	968713862002057
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	PATRICK OLIVER,
Contact Organization Name:	SPEEDYS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/21/2022
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,PRESIDENT
Application Received Date On Earliest Reg Form:	04/26/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	968713862002057
Ai Number:	29155
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported

SPEEDYS (Continued) **U001262735**

Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600787097
Owner Last Name:	OFLP-3 LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	525611132002057
Additional ID:	968713862002057
AI Number:	29155
Owner Effective Begin Date:	08/08/2012
State Tax ID:	17426221150
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	75966
Cert ID:	370545
AI Number:	29155
Self Certification Date:	04/21/2022
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	353979
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/29/2021
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	337141
AI Number:	29155
Self Certification Date:	04/29/2020
Signature Name/Title:	PATRICK OLIVER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	319666
AI Number:	29155
Self Certification Date:	04/04/2019
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	302091
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/06/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	286078
AI Number:	29155
Self Certification Date:	05/03/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	268094
AI Number:	29155
Self Certification Date:	04/14/2016
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	252494
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	05/05/2015
Signature Name/Title:	Guy Oliver Authorized Legal Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	234945
AI Number:	29155
Self Certification Date:	04/11/2014
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75966
Cert ID:	219093
AI Number:	29155
Self Certification Date:	04/23/2013
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	75966
Cert ID:	111351
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/16/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111350
AI Number:	29155
Self Certification Date:	05/02/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111349
AI Number:	29155
Self Certification Date:	05/19/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111348
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/01/2009
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111347
AI Number:	29155
Self Certification Date:	04/01/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111346
AI Number:	29155
Self Certification Date:	04/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111345
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/03/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75966
Cert ID:	111344
AI Number:	29155
Self Certification Date:	04/01/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75966
Cert ID:	111343
AI Number:	29155
Self Certification Date:	04/01/2004
Signature Name/Title:	GUY N OLIVER PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	75966
Cert ID:	111342
AI Number:	29155

SPEEDYS (Continued) **U001262735**

Self Certification Date:	04/01/2003
Signature Name/Title:	GUY NEWELL OLIVER LEGAL REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111341
AI Number:	29155
Self Certification Date:	04/29/2002
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75966
Cert ID:	111340
AI Number:	29155
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986

SPEEDYS (Continued) **U001262735**

Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	76787
Facility ID:	75966
Ai Number:	29155
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1978
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

SPEEDYS (Continued) **U001262735**

Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	5000
UST Comprt ID:	121642
UST ID:	76787
AI Number:	29155
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/11/2005

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	76788
Facility ID:	75966
Ai Number:	29155

SPEEDYS (Continued) **U001262735**

Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	121643
UST ID:	76788

SPEEDYS (Continued) **U001262735**

AI Number:	29155
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/11/2005

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	76789
Facility ID:	75966
Ai Number:	29155
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

SPEEDYS (Continued) **U001262735**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	121644
UST ID:	76789
AI Number:	29155
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

SPEEDYS (Continued) **U001262735**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/11/2005

Construction Notification:

NOC ID:	35481
Facility ID:	75966
AI Number:	29155
Application Received Date:	10/11/2019
Scheduled Construction Date:	10/11/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	10/11/2019
Signature Date On Form:	10/11/2019
Signature Name On Form:	LARRY HOLYBEE
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	OFLP-3 LTD

SPEEDYS (Continued) **U001262735**

Owner CN At Time Of Construction:	CN600787097
Owner AR At Time Of Construction:	45395
General Desc Of Prop Construct:	LOCATION FAILED A LINE TEST AND PRODUCT IN SUMP DRAINING FROM DOUBLE WALL EMPTY LINES TODAY AND START MONDAY ON LOCATION LEAK AND REPAIRING
NOC ID:	11052
Facility ID:	75966
AI Number:	29155
Application Received Date:	07/07/2005
Scheduled Construction Date:	07/11/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50707005
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	10/11/2019
Signature Date On Form:	10/11/2019
Signature Name On Form:	LARRY HOLYBEE
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	45395
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	84060
UST ID:	Not reported
NOC ID:	35481
AI Number:	29155
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PETROLEUM SOLUTIONS
Representative Name:	LARYY HOLYBEE
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

SPEEDYS (Continued) **U001262735**

Email Address:	Not reported
Cont/Cons/Installer ID:	11864
UST ID:	Not reported
NOC ID:	11052
AI Number:	29155
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	OFLP3 LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	75966
Additional ID:	968713862002057
Princ ID:	525611132002057
AI Number:	29155
Facility Name:	SPEEDYS
AR Number:	45395
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK OLIVER/

HIST UST AUSTIN:

Name:	SPEEDY'S
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	117
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SPEEDYS (Continued) **U001262735**

SPILLS:

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	TX 78741
Incident Number:	361079
Facility Id:	RN101510170
Date of Spill:	Not reported
Seq Num:	Not reported
Responsible Party Name:	Not reported
Responsible Party Address:	Not reported
Responsible Party City:	Not reported
Responsible Party State:	Not reported
Responsible Party Zip:	Not reported
Responsible Party Telephone:	Not reported
Substance:	WASTEWATER SLUDGE
Material Code:	Not reported
Media Affected:	Not reported
Permit Number:	Not reported
District:	REGION 11 - AUSTIN
Origin:	Not reported
Cause:	Not reported
Basin Code:	Not reported
Notify Date:	Not reported
Adequate Clean:	Not reported
Classification:	006_OTHER
Basin Name:	Not reported
Water Affected:	Not reported
Amnt Spilled:	0
Amnt in Water:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	Not reported
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	Not reported
Coordinator:	Not reported
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	06/24/2021
Start Date:	06/21/2021
Status Date:	06/29/2021
Media Name:	WATER
Customer:	V&S ENTERPRISES LC
Effect:	GENERAL, HEALTH
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	WASTEWATER
Watertext:	Not reported
Air Text:	bathroom
Incident Status:	CLOSED
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	This incident does not meet the necessary criteria for conducting an on-site emergency response investigation. The incident didn't meet the

SPEEDYS (Continued) **U001262735**

criteria for an investigation.

Incident Action:	This incident has been referred to Rowdy Salazar with the City of Austin Code Department. The contact number is (512) 974-2633.
Incident Description:	Report of unsanitary conditions in the restroom at a gas station.
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	CN605646710

ASBESTOS:

Name:	SPEED DS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	4.9
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

SPEEDYS (Continued) **U001262735**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MOMS 6
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/23/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.2
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

SPEEDYS (Continued) **U001262735**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	268345
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023

SPEEDYS (Continued) **U001262735**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	268346
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	250554
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	231987

SPEEDYS (Continued) **U001262735**

AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	213171
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	211809
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018

SPEEDYS (Continued) **U001262735**

Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00019456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	194732
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	178869
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SPEEDYS (Continued) **U001262735**

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	159497
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	143498
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	125606
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SPEEDYS (Continued) **U001262735**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	7731
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	107601
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported

SPEEDYS (Continued) **U001262735**

Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60904
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00079114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60905
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

SPEEDYS (Continued) **U001262735**

Region:	2
Facility ID:	75966
Finass ID:	60906
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60907
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60908
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

SPEEDYS (Continued) **U001262735**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60909
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 817 2329000
Policy Number:	04TO66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75966
Finass ID:	60910
AI:	29155
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	04/26/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901

SPEEDYS (Continued) **U001262735**

Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: No

RDR:

RDR ID:	32196
Facility ID:	29155
RN:	101510170
CN:	600787097
Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/5/2022
Due Date:	12/4/2022
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	11/15/2022
Project Manager:	Hannah Anderson
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	31373
Facility ID:	29155
RN:	101510170
CN:	605646710
Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/7/2022
Due Date:	3/8/2022
Tank Owner:	OFLP 3 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/7/2022
Project Manager:	Kristine Elliott
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported

SPEEDYS (Continued) **U001262735**

Region:	Not reported
DKC RDR (misfiled):	Not reported
RDR ID:	27727
Facility ID:	29155
RN:	Not reported
CN:	Not reported
Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/12/2019
Due Date:	1/11/2020
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/13/2020
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported
RDR ID:	27817
Facility ID:	29155
RN:	Not reported
CN:	Not reported
Name:	SPEEDYS
Address:	6301 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/2019
Due Date:	2/8/2020
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	1/27/2020
Project Manager:	Olusola Ayilara
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported

SPEEDYS (Continued) **U001262735**

DKC RDR (misfiled): Not reported

JG1453 **TEXAS FOOD MART** **TX UST** **U001254478**
ESE **720 LAMAR PL** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX Financial Assurance**
0.023 mi.
120 ft. **Site 1 of 3 in cluster JG**

Actual:
713 ft.

Focus Map:
6

UST:

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 787524023
AI Number:	19604
Facility Type:	RETAIL
Facility Begin Date:	09/05/1986
Facility Status:	ACTIVE
Additional ID:	632026612002208
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	T ROSS,GEN. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	264324162020029
Additional ID:	632026612002208
Ai Number:	19604
Operator CN:	CN605745975
Operator Name:	GOZIG HOLDINGS LLC
Operator Effective Begin Date:	01/01/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported

TEXAS FOOD MART (Continued) **U001254478**

Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601413677
Owner Last Name:	720 LAMAR PLACE LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	335739642002204
Additional ID:	632026612002208
AI Number:	19604
Owner Effective Begin Date:	01/01/2020
State Tax ID:	30118952057
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	75963
Cert ID:	373760
AI Number:	19604
Self Certification Date:	08/02/2022
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	361290
AI Number:	19604
Self Certification Date:	09/29/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	341773
AI Number:	19604
Self Certification Date:	08/31/2020
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	332210
AI Number:	19604
Self Certification Date:	01/15/2020
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	323874
AI Number:	19604
Self Certification Date:	07/31/2019
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	306297
AI Number:	19604
Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	290409
AI Number:	19604
Self Certification Date:	08/15/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	273439
AI Number:	19604
Self Certification Date:	08/11/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	255688
AI Number:	19604
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	238877
AI Number:	19604
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	223215
AI Number:	19604
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75963
Cert ID:	111327
AI Number:	19604
Self Certification Date:	07/13/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111326
AI Number:	19604
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	111325
AI Number:	19604
Self Certification Date:	07/20/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111324
AI Number:	19604
Self Certification Date:	05/28/2009
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111081
AI Number:	19604
Self Certification Date:	07/02/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	111080
AI Number:	19604
Self Certification Date:	07/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111079
AI Number:	19604
Self Certification Date:	07/05/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111078
AI Number:	19604
Self Certification Date:	07/11/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	111077
AI Number:	19604
Self Certification Date:	07/06/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111076
AI Number:	19604
Self Certification Date:	07/02/2003
Signature Name/Title:	GUY NEWELL OLIVER LEGAL AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75963
Cert ID:	111075
AI Number:	19604
Self Certification Date:	08/16/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TEXAS FOOD MART (Continued) **U001254478**

Self Cert ID:	75963
Cert ID:	111074
AI Number:	19604
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50408
Facility ID:	75963
Ai Number:	19604
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

TEXAS FOOD MART (Continued) **U001254478**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	12000
UST Comprt ID:	121631
UST ID:	50408
AI Number:	19604
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N

TEXAS FOOD MART (Continued) **U001254478**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50411
Facility ID:	75963
Ai Number:	19604
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

TEXAS FOOD MART (Continued) **U001254478**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	121634
UST ID:	50411
AI Number:	19604
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

TEXAS FOOD MART (Continued) **U001254478**

Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50410
Facility ID:	75963
Ai Number:	19604
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

TEXAS FOOD MART (Continued) **U001254478**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	121633
UST ID:	50410
AI Number:	19604
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000

TEXAS FOOD MART (Continued) **U001254478**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50409
Facility ID:	75963
Ai Number:	19604
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y

TEXAS FOOD MART (Continued) **U001254478**

Installation Signature Date:	02/22/1991
Compartment Records:	
Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	121632
UST ID:	50409
AI Number:	19604
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:	
Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	512 6372010/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	75963
Additional ID:	632026612002208

TEXAS FOOD MART (Continued) **U001254478**

Princ ID:	335739642002204
AI Number:	19604
Facility Name:	TEXAS FOOD MART
AR Number:	50118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	TEXAS MARKET
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX
Id UST:	845
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	271609
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	255482
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

TEXAS FOOD MART (Continued) **U001254478**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	227173
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	236738
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020

TEXAS FOOD MART (Continued) **U001254478**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	216565
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	199572
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	182952

TEXAS FOOD MART (Continued) **U001254478**

AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	165380
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	146478
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014

TEXAS FOOD MART (Continued) **U001254478**

Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	130217
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	112298
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

TEXAS FOOD MART (Continued) **U001254478**

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	112248
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	7729
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	60666
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

TEXAS FOOD MART (Continued) **U001254478**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	60667
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	60668
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

TEXAS FOOD MART (Continued) **U001254478**

Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	60669
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	75963
Finass ID:	60670
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TEXAS FOOD MART
Address:	720 LAMAR PL
City,State,Zip:	AUSTIN, TX 78752

TEXAS FOOD MART (Continued) **U001254478**

Region:	2
Facility ID:	75963
Finass ID:	60671
AI:	19604
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

1454 **ABC MOBILE BRAKE** **EDR Hist Auto** **1020913456**
WNW **519 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.023 mi.
120 ft.

Actual:
450 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1978	ABC MOBILE BRAKE	Motor Vehicle Supplies And New Parts
1980	DONS AUTOMOTIVE REPAIR	General Automotive Repair Shops
1982	DONS AUTOMOTIVE REPAIR	General Automotive Repair Shops
1983	DONS AUTOMOTIVE REPAIR	General Automotive Repair Shops

AL1455 **CAPITOL LAUNDRY & DRY CLEANING CO STATION NO** **EDR Hist Cleaner** **1013784073**
WNW **806 KOENIG LN W** **N/A**
< 1/8 **TRAVIS (County), TX 78756**
0.023 mi.
120 ft. **Site 12 of 13 in cluster AL**

Actual:
700 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1970	CAPITOL LAUNDRY & DRY CLEANING	LAUNDRIES

DM1456 NNE < 1/8 0.023 mi. 120 ft. — **ELLIS & SALAZAR GARAGE**, **403 7TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775591** / **N/A**

Site 20 of 22 in cluster DM

Actual: 498 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	ELLIS & SALAZAR GARAGE	AUTOMOBILE REPAIRING

DM1457 NNE < 1/8 0.023 mi. 120 ft. — **ELLIS BATTERY & AUTO REPRS**, **403 7TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013754369** / **N/A**

Site 21 of 22 in cluster DM

Actual: 498 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	ELLIS BATTERY & AUTO REPRS	AUTOMOBILE REPAIRING
1953	ELLIS & SALAZAR	AUTOMOBILE REPAIRING
1958	ELLIS & SALAZAR	AUTOMOBILE REPAIRING
1962	ELLIS & SALAZAR	AUTOMOBILE REPAIRING

JH1458 NE < 1/8 0.023 mi. 120 ft. — **RAVENS GARAGE**, **605 RED RIVER CT**, **AUSTIN, TX** — **EDR Hist Auto** — **1013755259** / **N/A**

Site 1 of 13 in cluster JH

Actual: 481 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	RAVEN & GIESE AUTO	AUTOMOBILE REPAIRERS
1929	RAVENS GARAGE	AUTOMOBILE REPAIRERS
1935	RAVENS GARAGE	AUTOMOBILE REPAIRERS
1940	RAVENS GARAGE AUTO	AUTOMOBILE REPAIRING
1947	RAVENS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1953	RAVEN JESSE L AUTO	AUTOMOBILE REPAIRING
1953	RAVENS GAR REPRS	AUTOMOBILE REPAIRING
1958	RAVENS GARAGE	AUTOMOBILE REPAIRING
1962	RAVENS LOUIE GAR	AUTOMOBILE REPAIRING
1965	RAVENS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1969	RAVEN JESSE L	General Automotive Repair Shops
1970	RAVENS GARAGE	AUTOMOBILE REPAIRING
1970	RAVEN JESSE L	General Automotive Repair Shops
1971	RAVEN JESSE L	General Automotive Repair Shops
1972	RAVEN JESSE L	General Automotive Repair Shops
1973	RAVEN JESSE L	General Automotive Repair Shops
1974	RAVEN JESSE L	General Automotive Repair Shops
1975	RAVENS GARAGE	AUTOMOBILE REPAIRING
1975	RAVEN JESSE L	General Automotive Repair Shops

FK1459	**MS EXPRESS 901**	**TX LPST**	**U003566328**
ESE	**2105 S CONGRESS AVE**	**TX UST**	**N/A**
< 1/8	**AUSTIN, TX 78704**	**TX ASBESTOS**	
0.023 mi.		**TX ENF**	
121 ft.	**Site 9 of 13 in cluster FK**	**TX Financial Assurance**	
		TX RDR	

Actual:
583 ft.

Focus Map:
14

LPST:

Name:	HOUSTON CONVENIENCE STORE 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0045192
LPST Id:	115195
Facility Location:	2105 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	05/29/2001
Entered Date:	06/28/2001
Reported Date:	05/29/2001
Closure Date:	09/09/2003
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SAW
Responsible Party Name:	Not reported
Responsible Party Contact:	PETER OTTO
Responsible Party Address:	945 MCKINNEY ST BOX 375
Responsible Party City,St,Zip:	HOUSTON, TX 77002 6308
Responsible Party Telephone:	203/359-5710
Reported Date:	05/29/2001
Case Start Date:	09/09/2003
Reference Number:	RN101698793
Project Manager:	SWAUGH

UST:

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787044316
AI Number:	45192
Facility Type:	RETAIL
Facility Begin Date:	01/01/1972
Facility Status:	INACTIVE
Additional ID:	784466262002075
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	BOB KAMINSKI,
Contact Organization Name:	MS EXPRESS 901
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

MS EXPRESS 901 (Continued) **U003566328**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2819831922
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	JAMES MANNING,DIV MGR
Application Received Date On Earliest Reg Form:	10/08/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	335739642002204
Additional ID:	784466262002075
Ai Number:	45192
Operator CN:	CN601413677
Operator Name:	720 LAMAR PLACE LC
Operator Effective Begin Date:	08/25/2002
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	GUY OLIVER/
Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78746-6771
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9276100
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601413677
Owner Last Name:	720 LAMAR PLACE LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6110
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6110
Contact Phone Number/Ext:	1 512 9276100/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	335739642002204
Additional ID:	784466262002075

MS EXPRESS 901 (Continued) **U003566328**

AI Number:	45192
Owner Effective Begin Date:	08/25/2002
State Tax ID:	30118952057
Contact Role:	OWNCON
Contact Name/Title:	GUY OLIVER/AUTH REP
Contact Organization Name:	720 LAMAR PLACE L C

Self Certification:

Self Cert ID:	74578
Cert ID:	306301
AI Number:	45192
Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	290412
AI Number:	45192
Self Certification Date:	08/15/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	273443
AI Number:	45192
Self Certification Date:	08/11/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	255692
AI Number:	45192
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	238881
AI Number:	45192
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	223219
AI Number:	45192
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74578
Cert ID:	104512
AI Number:	45192
Self Certification Date:	07/13/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74578
Cert ID:	104511
AI Number:	45192
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74578
Cert ID:	104510
AI Number:	45192
Self Certification Date:	07/20/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104509
AI Number:	45192
Self Certification Date:	07/06/2009
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104508
AI Number:	45192
Self Certification Date:	07/02/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104507
AI Number:	45192
Self Certification Date:	07/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104506
AI Number:	45192
Self Certification Date:	07/05/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104505
AI Number:	45192
Self Certification Date:	07/11/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74578
Cert ID:	104504
AI Number:	45192
Self Certification Date:	07/06/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74578
Cert ID:	104503
AI Number:	45192
Self Certification Date:	07/02/2003
Signature Name/Title:	GUY NEWELL OLIVER LEGAL AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74578
Cert ID:	104502
AI Number:	45192
Self Certification Date:	08/25/2002
Signature Name/Title:	GUY OLIVER MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74578
Cert ID:	104501
AI Number:	45192
Self Certification Date:	01/18/2001
Signature Name/Title:	PETER OTTO PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

MS EXPRESS 901 (Continued) **U003566328**

Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118309
Facility ID:	74578
Ai Number:	45192
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/22/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

MS EXPRESS 901 (Continued) **U003566328**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	104294
UST ID:	118309
AI Number:	45192
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

MS EXPRESS 901 (Continued) **U003566328**

More Self Certification:

Self Cert ID:	17636
Cert ID:	22776
UST Comprt ID:	59901
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22774
UST Comprt ID:	59903
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22775
UST Comprt ID:	59904
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22773
UST Comprt ID:	59902
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118311
Facility ID:	74578
Ai Number:	45192
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/22/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

MS EXPRESS 901 (Continued) **U003566328**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	104296
UST ID:	118311
AI Number:	45192
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y

MS EXPRESS 901 (Continued) **U003566328**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17636
Cert ID:	22776
UST Comprt ID:	59901
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22774
UST Comprt ID:	59903
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22775
UST Comprt ID:	59904
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22773
UST Comprt ID:	59902
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A

MS EXPRESS 901 (Continued) **U003566328**

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118312
Facility ID:	74578
Ai Number:	45192
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/24/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

MS EXPRESS 901 (Continued) **U003566328**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	104297
UST ID:	118312
AI Number:	45192
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17636
Cert ID:	22776
UST Comprt ID:	59901
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A

MS EXPRESS 901 (Continued) **U003566328**

Self Cert ID:	17636
Cert ID:	22774
UST Comprt ID:	59903
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22775
UST Comprt ID:	59904
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22773
UST Comprt ID:	59902
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118310
Facility ID:	74578
Ai Number:	45192
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/22/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

MS EXPRESS 901 (Continued) **U003566328**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	104295
UST ID:	118310
AI Number:	45192
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y

MS EXPRESS 901 (Continued) **U003566328**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17636
Cert ID:	22776
UST Comprt ID:	59901
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22774
UST Comprt ID:	59903
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22775
UST Comprt ID:	59904
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17636
Cert ID:	22773
UST Comprt ID:	59902
UST ID:	20499
AI Number:	45192
Tank ID:	4
Compartment ID:	A

Construction Notification:

NOC ID:	11022
Facility ID:	74578
AI Number:	45192
Application Received Date:	10/05/2009
Scheduled Construction Date:	10/07/2009

MS EXPRESS 901 (Continued) **U003566328**

UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91005009
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	50118
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	11839
UST ID:	Not reported
NOC ID:	11022
AI Number:	45192
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	512 6372010/0
Contact Fax Number/Ext:	/

MS EXPRESS 901 (Continued) **U003566328**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74578
Additional ID:	784466262002075
Princ ID:	335739642002204
AI Number:	45192
Facility Name:	MS EXPRESS 901
AR Number:	50118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

ASBESTOS:

Name:	EVERYTIME STOP
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/13/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/18/2013
Date Routed by Supervisor:	03/18/2013
Date Routed to PSQA:	03/18/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported

MS EXPRESS 901 (Continued) **U003566328**

Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	EVERYTIME STOP
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/28/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	4.8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

MS EXPRESS 901 (Continued) **U003566328**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Unique TCEQ Ref Number Of Customer:	CN601413677
Unique TCEQ Ref Number Of Reg. Entity:	RN101698793
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	30 TAC Chapter 334, SubChapter C
Regulated Entity Associated With An NOV:	720 LAMAR PLACE LC
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	878209
Status Code:	RESOLVED
Status Date:	01/03/2011
Violation Tracking Number:	310,341,312,010,322.00
Violation Category:	A

MS EXPRESS 901 (Continued) **U003566328**

Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	Not reported
Description 1:	30 TAC 334.49(a)(1) - (a) General requirements. (1) Owners and operators of underground storage tank (UST) systems (or underground metal UST system components) which are required to be protected from corrosion shall comply with the requirements in this section to ensure that releases due to corrosion are prevented.
Description 2:	The Executive Director recognizes that the Respondent repaired and successfully tested the UST system's rectifier on August 24, 2010.
Category of the NOV:	Not reported
Method Of Notice Issuance:	Not reported
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	Not reported
Status Of The NOV:	DAPPROVED
Investigation:	Not reported
Investigation ID:	190331042010322
Regulated Entity ID:	776466252002075
Date of Notice Enforcement:	12/24/2010
Violation Date:	2012-07-18 00:00:00
Rejected:	NO
Type Code:	ADMINORDER
Date Resolved:	04/01/2012
Assessed Amount:	3750
Deferred Amount:	0
Payable Amount:	3750
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

TX Financial Assurance 2:

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	199576
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

MS EXPRESS 901 (Continued) **U003566328**

Region:	2
Facility ID:	74578
Finass ID:	182956
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	165384
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	146482
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

MS EXPRESS 901 (Continued) **U003566328**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	130221
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	112302
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013

MS EXPRESS 901 (Continued) **U003566328**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	112252
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	7929
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57901

MS EXPRESS 901 (Continued) **U003566328**

AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57902
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57903
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009

MS EXPRESS 901 (Continued) **U003566328**

Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57904
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57905
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

MS EXPRESS 901 (Continued) **U003566328**

Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74578
Finass ID:	57906
AI:	45192
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	26714
Facility ID:	45192
RN:	Not reported
CN:	Not reported
Name:	MS EXPRESS 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/5/2019
Due Date:	5/4/2019
Tank Owner:	720 LAMAR PLACE LC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/30/2019
Project Manager:	Kristine Elliott
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FK1460 ESE < 1/8 0.023 mi. 121 ft. | **E. M. BOHLS 2105 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S128729463 N/A**

Site 10 of 13 in cluster FK

Actual: 583 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	E. M. BOHLS
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0894
HID UST:	894
Inspection:	05/31/2011
Due:	05/31/2014

FK1461 ESE < 1/8 0.023 mi. 121 ft. | **HOUSTON CONVENIENCE 901 2105 S CONGRESS AVE AUSTIN, TX** | **TX RDR** | **S127533591 N/A**

Site 11 of 13 in cluster FK

Actual: 583 ft.
Focus Map: 14

RDR:

RDR ID:	6427
Facility ID:	45192
RN:	Not reported
CN:	Not reported
Name:	HOUSTON CONVENIENCE 901
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/20/2001
Due Date:	8/19/2001
Tank Owner:	HOUSTON CONVENIENCE
Contact Person:	BOB KAMINSKI
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Stefan Dorman
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	115195
Comments:	115195 SKD
Review Coordinator:	SKD/MAO
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

FK1462 ESE < 1/8 0.023 mi. 121 ft. — **DIAMOND SHAMROCK, 2105 S CONGRESS, AUSTIN, TX 78704** — **EDR Hist Auto** — **1020290235, N/A**

Site 12 of 13 in cluster FK

Actual: 583 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1986	DIAMOND SHAMROCK	Gasoline Service Stations
1987	DIAMOND SHAMROCK	Gasoline Service Stations
1988	DIAMOND SHAMROCK	Gasoline Service Stations
1992	DIAMOND SHAMROCK REF MKTG CO	Convenience Stores
1993	DIAMOND SHAMROCK REF MKTG CO	Convenience Stores
1994	DIAMOND SHAMROCK INC	Convenience Stores
1995	DIAMOND SHAMROCK INC	Convenience Stores
1996	DIAMOND SHAMROCK INC	Convenience Stores
2001	SIGMOR NUMBER 111 INC	Gasoline Service Stations
2002	SIGMOR NUMBER 111 INC	Gasoline Service Stations
2003	SIGMOR NUMBER 111 INC	Gasoline Service Stations
2004	SIGMOR NUMBER 111 INC	Gasoline Service Stations

FK1463 ESE < 1/8 0.023 mi. 121 ft. — **EVERYTIME FOOD MART, 2105 S CONGRESS AVE, AUSTIN, TX** — **TX HIST UST** — **S128728798, N/A**

Site 13 of 13 in cluster FK

Actual: 583 ft. HIST UST AUSTIN:

Focus Map: 14

Name:	EVERYTIME FOOD MART
Address:	2105 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	378
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

JI1464 ESE < 1/8 0.023 mi. 121 ft. — **CHESNUTT CLNRS, 103 18TH W, AUSTIN, TX** — **EDR Hist Cleaner** — **1013786756, N/A**

Site 1 of 3 in cluster JI

Actual: 536 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	CHESNUTT CLNRS	CLEANERS AND DYERS

AC1465 ESE < 1/8 0.023 mi. 121 ft. | **REED OIL CO GAS STA**
7135 LAMAR BLVD N
AUSTIN, TX
Site 42 of 43 in cluster AC | **EDR Hist Auto** | **1013758421**
N/A

Actual: 728 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1962	REED OIL CO GAS STA	GASOLINE STATIONS
1965	THOMSON SERVICE STATION	GASOLINE STATIONS
1969	THOMPSON CLIFFORD R OIL CO	Gasoline Service Stations
1970	THOMSON SERVICE STATION GAS	GASOLINE STATIONS
1970	THOMPSON CLIFFORD R OIL CO	Gasoline Service Stations
1971	THOMPSON CLIFFORD R OIL CO	Gasoline Service Stations
1971	STARTEX MAJOR QUALITY GAS	Gasoline Service Stations
1972	STARTEX MAJOR QUALITY GAS	Gasoline Service Stations
1973	STARTEX MAJOR QUALITY GAS	Gasoline Service Stations
1974	STARTEX MAJOR QUALITY GAS	Gasoline Service Stations
1975	STARWAY GAS GAS ST	GASOLINE STATIONS

AC1466 ESE < 1/8 0.023 mi. 121 ft. | **PIONEER SERVICE CO.**
7135 N LAMAR BLVD
AUSTIN, TX
Site 43 of 43 in cluster AC | **TX HIST UST** | **S111678778**
N/A

Actual: 728 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	PIONEER SERVICE CO.
Address:	7135 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0599
HID UST:	599
Inspection:	02/26/2009
Due:	02/26/2012

DJ1467 SSW < 1/8 0.023 mi. 121 ft. | **DRISKILL HOTEL ALLEY TANK**
604 BRAZOS ST
AUSTIN, TX 78701
Site 5 of 7 in cluster DJ | **TX HIST UST**
TX NON REGIST PST | **S122568378**
N/A

Actual: 493 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	DRISKILL HOTEL
Address:	604 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Id UST:	3327
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NON REGIST PST:

RN Number:	RN105481477
Name:	DRISKILL HOTEL ALLEY TANK
Address:	604 BRAZOS ST
City,State,Zip:	AUSTIN, TX 78701 3212

DRISKILL HOTEL ALLEY TANK (Continued) **S122568378**

Physical Location:	No physical location description ON file.
CN Number:	CN603335340
Customer Name:	LH BRAZOS HOLDING LP
Customer Role:	N/A
Primary Business:	Hotel
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=253405962008080

DF1468 **METZENTHIN BROS AUTO** **EDR Hist Auto** **1013775989**
ESE **102 7TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
121 ft. **Site 13 of 25 in cluster DF**

Actual:
498 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	METZENTHIN BROS AUTO	AUTOMOBILE SERVICE

DF1469 **RIOS FRANK TAILOR** **EDR Hist Cleaner** **1013783091**
ESE **103 7TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
121 ft. **Site 14 of 25 in cluster DF**

Actual:
498 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	RIOS FRANK TAILOR	CLOTHES CLEANERS AND PRESSERS

JJ1470 **THE SHERWIN-WILLIAMS COMPANY** **RCRA NonGen / NLR** **1000371696**
NW **500 E OLTORF ST** **FINDS** **TXD000812503**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.023 mi.
122 ft. **Site 1 of 2 in cluster JJ**

Actual:
611 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20020114
Handler Name:	The Sherwin-Williams Company
Handler Address:	E OLTORF ST
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD000812503
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	E OLTORF ST
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

THE SHERWIN-WILLIAMS COMPANY (Continued) **1000371696**

Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E OLTORF ST
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	The Sherwin-Williams Company
Owner Type:	Private
Operator Name:	The Sherwin-Williams Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

THE SHERWIN-WILLIAMS COMPANY (Continued) **1000371696**

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F017
Waste Description: Not Defined

Waste Code: F018
Waste Description: Not Defined

Waste Code: P090
Waste Description: Not Defined

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

THE SHERWIN-WILLIAMS COMPANY (Continued) **1000371696**

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: THE SHERWIN-WILLIAMS COMPANY
Legal Status: Private
Date Became Current: 20020114
Date Ended Current: Not reported
Owner/Operator Address: 500 E OLTORF ST
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SHERWIN WILLIAMS CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE SHERWIN-WILLIAMS COMPANY
Legal Status: Private
Date Became Current: 20020114
Date Ended Current: Not reported
Owner/Operator Address: 500 E OLTORF ST
Owner/Operator City,State,Zip: AUSTIN, TX 78704

THE SHERWIN-WILLIAMS COMPANY (Continued) **1000371696**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800818
Handler Name: SHERWIN WILLIAMS CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020114
Handler Name: THE SHERWIN-WILLIAMS COMPANY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005030215

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

THE SHERWIN-WILLIAMS COMPANY (Continued) **1000371696**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000371696
Registry ID:	110005030215
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005030215
Name:	THE SHERWIN-WILLIAMS COMPANY
Address:	500 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704

JJ1471 **SHERWIN WILLIAMS** **TX ASBESTOS** **S102749593**
NW **500 E OLTORF ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX CENTRAL REGISTRY**
0.023 mi.
122 ft. **Site 2 of 2 in cluster JJ**

Actual:
611 ft.

Focus Map:
14

ASBESTOS:

Name:	SHERWIN WILLIAMS
Address:	500 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

SHERWIN WILLIAMS (Continued) **S102749593**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SHERWIN WILLIAMS
Address:	500 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

SHERWIN WILLIAMS (Continued) **S102749593**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	SHERWIN WILLIAMS
Address:	500 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66023
Registration Initial Notification Date:	01/14/2002
Registration Last Amendment Date:	01/14/2002
EPA Identification:	TXD000812503
Primary NAICS Code:	Not reported
Status Change Date:	20020114
Land Type:	PRIVATE
Description of Facility Site Location:	500 E Oltorf St, Austin, TX

SHERWIN WILLIAMS (Continued) **S102749593**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CLASS1
Type of Generator:	NON INDUS
Company Name:	THE SHERWIN-WILLIAMS COMPANY
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	500 E OLTORF ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787045639
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21329
Site Owner Tax ID:	340526850
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030314
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	THE SHERWIN-WILLIAMS COMPANY
Operator Address:	500 E OLTORF ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13405268502
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE SHERWIN-WILLIAMS COMPANY
Owner Mailing Address:	500 E OLTORF ST

SHERWIN WILLIAMS (Continued) **S102749593**

Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13405268502
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	500 E OLTORF ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	500 E OLTORF ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	500 E OLTORF ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	305754
Texas Waste Code:	Not reported
Texas Waste Code 2:	DXNV211H
Waste Code Status:	Not reported
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported

SHERWIN WILLIAMS (Continued) **S102749593**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	305755
Texas Waste Code:	Not reported
Texas Waste Code 2:	DXNW1191
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100712421
Name:	SHERWIN WILLIAMS
Address:	500 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5639
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600278600
Customer Name:	THE SHERWIN-WILLIAMS COMPANY
Customer Legal Name:	The Sherwin-Williams Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/14/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	500 E Oltorf St, Austin, TX

SHERWIN WILLIAMS (Continued) **S102749593**

Regulated Entity Number:	RN100712421
Name:	SHERWIN WILLIAMS
Address:	500 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5639
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600278600
Customer Name:	THE SHERWIN-WILLIAMS COMPANY
Customer Legal Name:	The Sherwin-Williams Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/14/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	500 E Oltorf St, Austin, TX

DU1472 **SANDGARTENS SERVICE** **EDR Hist Auto** **1013773525**
NE **510 RED RIVER CT** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
122 ft. **Site 14 of 19 in cluster DU**

Actual:
475 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	SANDGARTENS SERVICE	GASOLINE AND OIL SERVICE STATIONS

JF1473 **GILBERTS AUTO ELECTRIC AND** **EDR Hist Auto** **1013757141**
ESE **84 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
122 ft. **Site 2 of 3 in cluster JF**

Actual:
459 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1965	GILBERTS AUTO ELECTRIC AND	AUTOMOBILE REPAIRING
1987	AUSTIN FOREIGN CAR CENTER	General Automotive Repair Shops
1988	AUSTIN FOREIGN CAR CENTER	General Automotive Repair Shops
1989	AUSTIN FOREIGN CAR CENTER	Engine Repair
1990	AUSTIN FOREIGN CAR CENTER AUTO	AUTOMOBILE REPAIRING
1990	AUSTIN FOREIGN CAR CENTER	Engine Repair
1991	AUSTIN FOREIGN CAR CENTER	Engine Repair
1992	AUSTIN FOREIGN CAR CENTER	Engine Repair
1993	AUSTIN FOREIGN CAR CENTER	Engine Repair
1994	AUSTIN FOREIGN CAR CENTER	Engine Repair
1995	AUSTIN FOREIGN CAR CENTER	Engine Repair
1996	AUSTIN FOREIGN CAR CENTER	Engine Repair
1997	AUSTIN FOREIGN CAR CENTER	Engine Repair
1998	AUSTIN FOREIGN CAR CENTER	Engine Repair
1999	AUSTIN FOREIGN CAR CENTER	Engine Repair
2000	AUSTIN FOREIGN CAR CENTER	Engine Repair
2001	AUSTIN FOREIGN CAR CENTER	Engine Repair
2002	AUSTIN FOREIGN CAR CENTER	Engine Repair

GILBERTS AUTO ELECTRIC AND (Continued) **1013757141**

2003	AUSTIN FOREIGN CAR CENTER	Engine Repair
2004	AUSTIN FOREIGN CAR CENTER	Engine Repair
2005	AUSTIN FOREIGN CAR CENTER	Engine Repair
2006	AUSTIN FOREIGN CAR CENTER	Engine Repair
2007	AUSTIN FOREIGN CAR CENTER	Engine Repair
2008	AUSTIN FOREIGN CAR CENTER	Engine Repair
2009	AUSTIN FOREIGN CAR CENTER	Engine Repair
2010	AUSTIN FOREIGN CAR CENTER	Engine Repair

JK1474 **AUSTIN QUALITY CAR WASH** **TX UST** **U001237555**
WNW **3120 GUADALUPE ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX Financial Assurance**
0.023 mi.
123 ft. **Site 1 of 3 in cluster JK**

Actual:
594 ft.

Focus Map:
8

UST:

Name:	AUSTIN QUALITY CAR WASH
Address:	3120 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787052821
AI Number:	149
Facility Type:	UNKNOWN
Facility Begin Date:	05/27/1986
Facility Status:	INACTIVE
Additional ID:	391536442002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	ROBERT E MARTIN,PRESIDENT
Contact Organization Name:	AUSTIN QUALITY CAR WASH
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123274945
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/04/1986
Signature Name/Title On Earliest Reg Form:	JOEL PICKENS,MANAGER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778427
Owner Last Name:	PICKENS AND PICKENS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	382536432002053
Additional ID:	391536442002053
AI Number:	149
Owner Effective Begin Date:	01/10/1992
State Tax ID:	17426206540
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	347
Facility ID:	38071
Ai Number:	149
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/23/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	1375
UST ID:	347
AI Number:	149
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	348
Facility ID:	38071
Ai Number:	149
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/23/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	1376
UST ID:	348
AI Number:	149
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	349
Facility ID:	38071
Ai Number:	149
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/23/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	1377
UST ID:	349
AI Number:	149
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/16/1997
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	185444
Facility ID:	38071
Ai Number:	149
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/23/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	1378
UST ID:	185444
AI Number:	149
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PICKENS & PICKENS
Contact Mailing Address (Delivery):	3120 GUADALUPE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78705 2821
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	38071
Additional ID:	391536442002053
Princ ID:	382536432002053

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

AI Number:	149
Facility Name:	AUSTIN QUALITY CAR WASH
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	AUSTIN QUALITY CAR WASH
Address:	3120 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	1551
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	AUSTIN QUALITY CAR WASH
Address:	3120 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	38071
Finass ID:	17588
AI:	149
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	AUSTIN QUALITY CAR WASH
Address:	3120 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	38071
Finass ID:	17587
AI:	149
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y

AUSTIN QUALITY CAR WASH (Continued) **U001237555**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

JK1475 **TEXACO STATION** **RCRA-VSQG** **1000982678**
WNW **3120 GUADALUPE ST** **FINDS** **TX0000994889**
< 1/8 **AUSTIN, TX 78705** **ECHO**
0.023 mi.
123 ft. **Site 2 of 3 in cluster JK**

Actual:
594 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	19941227
Handler Name:	Texaco Station
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TX0000994889
Contact Name:	DARVIN MAYO
Contact Address:	333 RESEARCH CRT
Contact City,State,Zip:	NORCROSS, GA 30092
Contact Telephone:	404-453-5442
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	RESEARCH CRT
Mailing City,State,Zip:	NORCROSS, GA 30092
Owner Name:	Star Enterprise
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

TEXACO STATION (Continued) **1000982678**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STAR ENTERPRISE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	333 RESEARCH CRT
Owner/Operator City,State,Zip:	NORCROSS, GA 30092
Owner/Operator Telephone:	404-453-5400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19941227
Handler Name: TEXACO STATION	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

TEXACO STATION (Continued) **1000982678**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005023526

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000982678
Registry ID:	110005023526
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005023526
Name:	TEXACO STATION
Address:	3120 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705

JK1476 **CAR CARE CENTER** **EDR Hist Auto** **1013756460**
WNW **3120 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.023 mi.
123 ft. **Site 3 of 3 in cluster JK**

Actual:
594 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1972	CAMPBELL & FLETCHER SERVICE	Gasoline Service Stations
1973	CAMPBELL & FLETCHER SERVICE	Gasoline Service Stations
1978	AUSTIN QUALITY CAR WASH	Carwashes
1979	LEES AUTOMOTIVE	General Automotive Repair Shops
1979	AUSTIN QUALITY CAR WASH	Carwashes
1980	AUSTIN QUALITY CAR WASH	Carwashes
1980	LEES AUTOMOTIVE	General Automotive Repair Shops

CAR CARE CENTER (Continued) **1013756460**

1982	AUSTIN QUALITY CAR WASH	Carwashes
1982	LEES AUTOMOTIVE	General Automotive Repair Shops
1983	AUSTIN QUALITY CAR WASH INC	Carwashes
1983	LEES AUTOMOTIVE	General Automotive Repair Shops
1984	CAR CARE CENTER	GASOLINE STATIONS
1985	AUSTIN QUALITY CAR WASH INC	Carwashes
1985	LEES AUTOMOTIVE	General Automotive Repair Shops
1986	LEES AUTOMOTIVE	General Automotive Repair Shops
1986	AUSTIN QUALITY CAR WASH INC	Carwashes
1987	AUSTIN QUALITY CAR WASH INC	Carwashes
1987	LEES AUTOMOTIVE	General Automotive Repair Shops
1988	AUSTIN QUALITY CAR WASH INC	Carwashes
1988	LEES AUTOMOTIVE	General Automotive Repair Shops
1989	LEES AUTOMOTIVE	General Automotive Repair Shops
1989	AUSTIN QUALITY CAR WASH INC	Carwashes
1990	AUSTIN QUALITY CAR WASH INC	Carwashes
1990	LEES AUTOMOTIVE	General Automotive Repair Shops
1991	LEES AUTOMOTIVE	General Automotive Repair Shops
1991	AUSTIN QUALITY CAR WASH INC	Carwashes
1992	LEES AUTOMOTIVE	General Automotive Repair Shops
1992	AUSTIN QUALITY CAR WASH INC	Carwashes
1993	AUSTIN QUALITY CAR WASH INC	Carwashes
1994	AUSTIN QUALITY CAR WASH INC	Carwashes
1995	AUSTIN QUALITY CAR WASH INC	Carwashes
1996	AUSTIN QUALITY CAR WASH INC	Carwashes
1997	PICKENS AND PICKENS INC	Carwashes
1998	PICKENS AND PICKENS INC	Carwashes
1999	PICKENS AND PICKENS INC	Carwashes
2000	PICKENS AND PICKENS INC	Carwashes
2001	PICKENS AND PICKENS INC	Carwashes
2002	PICKENS AND PICKENS INC	Carwashes
2003	PICKENS AND PICKENS INC	Carwashes
2004	PICKENS AND PICKENS INC	Carwashes
2005	PICKENS AND PICKENS INC	Carwashes
2006	PICKENS AND PICKENS INC	Carwashes
2007	PICKENS AND PICKENS INC	Carwashes
2008	PICKENS AND PICKENS INC	Carwashes
2009	PICKENS AND PICKENS INC	Carwashes
2010	PICKENS AND PICKENS INC	Carwashes
2011	PICKENS AND PICKENS INC	Carwashes
2012	PICKENS AND PICKENS INC	Carwashes
2013	PICKENS AND PICKENS INC	Carwashes
2014	ARBOR CAR WASH INC	Carwashes

JL1477 **WILLIAM B TRAVIS** **TX UST** **U003921133**
WNW **1701 CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.023 mi.
123 ft. **Site 1 of 3 in cluster JL**

Actual:
535 ft.

Focus Map:
11

UST:

Name:	WILLIAM B TRAVIS
Address:	1701 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787011402
AI Number:	76047
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE

WILLIAM B TRAVIS (Continued) **U003921133**

Additional ID:	597333752003344
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	LOUIS OJEDA,
Contact Organization Name:	WILLIAM B TRAVIS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124633600
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/16/2014
Signature Name/Title On Earliest Reg Form:	KEN HULIN,
Application Received Date On Earliest Reg Form:	01/17/2014
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	167546612009246
Additional ID:	597333752003344
Ai Number:	76047
Operator CN:	CN603527441
Operator Name:	TEXAS FACILITIES COMMISSION
Operator Effective Begin Date:	09/11/2003
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78711-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9000333
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603527441
Owner Last Name:	TEXAS FACILITIES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78711
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 9000333/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	167546612009246
Additional ID:	597333752003344
AI Number:	76047
Owner Effective Begin Date:	09/11/2003
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION

Self Certification:

Self Cert ID:	116669
Cert ID:	230645
AI Number:	76047
Self Certification Date:	01/16/2014
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116669
Cert ID:	208186
AI Number:	76047
Self Certification Date:	02/12/2013
Signature Name/Title:	KEN HULIN ELEC SUPVR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	116669
Cert ID:	208185
AI Number:	76047
Self Certification Date:	01/31/2012
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	116669
Cert ID:	208184
AI Number:	76047
Self Certification Date:	02/11/2011
Signature Name/Title:	KEN HULIN ELECTRICAL SPVR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	116669
Cert ID:	208183
AI Number:	76047
Self Certification Date:	10/28/2009
Signature Name/Title:	JONATHAN HICKMAN ELEC SUPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	116669
Cert ID:	208182
AI Number:	76047
Self Certification Date:	10/23/2009
Signature Name/Title:	JONATHAN HICKMAN ELEC SUPVR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	116669
Cert ID:	208181
AI Number:	76047
Self Certification Date:	09/11/2003
Signature Name/Title:	MEL BULLOCK
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/15/2003
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	202085
Facility ID:	116669
Ai Number:	76047
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2014
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR

WILLIAM B TRAVIS (Continued) **U003921133**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	183128
UST ID:	202085
AI Number:	76047
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	25813
Facility ID:	116669
AI Number:	76047
Application Received Date:	05/19/2014
Scheduled Construction Date:	06/03/2014
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	05/19/2014
Signature Date On Form:	05/14/2014
Signature Name On Form:	HENRY WISE
Signature Company On Form:	Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: TEXAS FACILITIES COMMISSION;TEXAS FACILITIES COMMISSION
Owner CN At Time Of Construction: CN603527441,CN603527441
Owner AR At Time Of Construction: 55232A,55232U
General Desc Of Prop Construct: REMOVAL OF (1) 500 GAL UST. REQUEST 30 DAY WAIVER.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID: 60359
UST ID: Not reported
NOC ID: 25813
AI Number: 76047
Type Of Contact: CONSULTANT
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: SWS ENVIRONMENTAL SERVICES
Representative Name: HENRY WISE
Mailing Address (Delivery): 1700 N E ST
Mailing Address (Internal Delivery): Not reported
Mailing City: LA PORTE
Mailing State: TX
Mailing Zip: 77571
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 281
Phone Number: 8679131
Phone Number Extension: Not reported
Fax Number Country Code: 1
Fax Number Area Code: 281
Fax Number: 8679150
Email Address: Not reported

Cont/Cons/Installer ID: 60360
UST ID: Not reported
NOC ID: 25813
AI Number: 76047
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: SWS ENVIRONMENTAL SERVICES
Representative Name: HENRY M WISE
Mailing Address (Delivery): 1700 N E ST
Mailing Address (Internal Delivery): Not reported
Mailing City: LA PORTE
Mailing State: TX
Mailing Zip: 77571
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 281
Phone Number: 8679131
Phone Number Extension: Not reported
Fax Number Country Code: 1
Fax Number Area Code: 281
Fax Number: 8679150
Email Address: Not reported

WILLIAM B TRAVIS (Continued) **U003921133**

Facility Billing Contacts:

Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78711 3047
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	116669
Additional ID:	597333752003344
Princ ID:	167546612009246
AI Number:	76047
Facility Name:	WILLIAM B TRAVIS
AR Number:	55232
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	JONATHAN HICKMAN/

HIST UST AUSTIN:

Name:	WB TRAVIS BUILDING
Address:	1701 CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3338
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

JL1478 **WILLIAM TRAVIS STATE OFF BLDG** **TX RDR** **S127539877**
WNW **1701 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
123 ft. **Site 2 of 3 in cluster JL**

Actual:
535 ft.

Focus Map:
11

RDR:

RDR ID:	22252
Facility ID:	76047
RN:	Not reported
CN:	Not reported
Name:	WILLIAM TRAVIS STATE OFF BLDG
Address:	1701 CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/25/2014
Due Date:	10/24/2014
Tank Owner:	TEXAS FACILITIES COMMISSION
Contact Person:	KENNETH HULIN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/12/2014
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported

WILLIAM TRAVIS STATE OFF BLDG (Continued) **S127539877**

Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JL1479 **RAILROAD COMMISSION OF TEXAS** **EDR Hist Auto** **1021405788**
WNW **1701 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.023 mi.
123 ft. **Site 3 of 3 in cluster JL**

Actual:
535 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2005	RAILROAD COMMISSION OF TEXAS	Gasoline Service Stations
2006	RAILROAD COMMISSION OF TEXAS	Gasoline Service Stations

FY1480 **GUEROS ADDL SP** **EDR Hist Cleaner** **1013777952**
SE **616 OLTORF ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78704**
0.023 mi.
123 ft. **Site 2 of 4 in cluster FY**

Actual:
562 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1990	GUEROS ADDL SP	CLEANERS AND DYERS

DG1481 **SWEET CLEANERS** **RCRA NonGen / NLR** **1000223221**
West **613 CONGRESS AVE** **FINDS** **TXD981586811**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.023 mi.
123 ft. **Site 7 of 16 in cluster DG**

Actual:
496 ft.
RCRA Listings:

Focus Map:
11

Date Form Received by Agency:	19930222
Handler Name:	Sweet Cleaners Inc
Handler Address:	CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981586811
Contact Name:	MARK SCHECHTER
Contact Address:	CONGRESS AVE
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-477-4083
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

SWEET CLEANERS (Continued) **1000223221**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Sweet Cleaners Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20041123
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane,

SWEET CLEANERS (Continued) **1000223221**

Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SWEET CLEANERS INC	
Legal Status:	Private
Date Became Current:	19930222
Date Ended Current:	Not reported
Owner/Operator Address:	613 CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-477-4083
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: SWEET 1 HR DRY CLNRS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19860731
Handler Name: SWEET 1 HR DRY CLNRS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930222
Handler Name: SWEET CLEANERS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

SWEET CLEANERS (Continued) **1000223221**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005090944

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000223221
Registry ID: 110005090944
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005090944
Name: SWEET CLEANERS
Address: 613 CONGRESS AVE
City,State,Zip: AUSTIN, TX 78701

DG1482 **SWEET CLEANERS** **TX ASBESTOS** **S102750264**
West **613 CONGRESS AVE** **TX DRYCLEANERS** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX Ind. Haz Waste**
0.023 mi. **TX CENTRAL REGISTRY**
123 ft. **Site 8 of 16 in cluster DG**

Actual:
496 ft.

Focus Map:
11

ASBESTOS:
Name: 7-ELEVEN
Address: 613 CONGRESS AVE
City,State,Zip: AUSTIN, TX 78701
Date of inspection: 04/25/2013
Reason for Inspection: Routine
Violation: No

SWEET CLEANERS (Continued) **S102750264**

Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FORMER SWEET CLEANERS
Address:	613 CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/30/2012
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2012007780
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/27/2012
Date Routed by Supervisor:	11/29/2012
Date Routed to PSQA:	12/04/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FORMER SWEET CLEANERS
Address:	613 CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2012/10/30
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	10/30/2012
Client Code:	1400
Client Name:	Environmental Facilities/Notification
License Number:	2012007780
File Number:	94985
License Status Description:	Paid
Expiration Date:	10/30/2012
Original Date:	10/18/2012
Rank Effective Date:	10/18/2012
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	31401
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	A
Inspection Secondary Class Code Description:	Asbestos
Results:	Pass
Inspection Number Grade:	0

DRYCLEANERS:

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602461147
DCR Number:	Not reported
AR Number:	24000549
Principal Name:	SWEET ONE HOUR CLEANERS INC
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

SWEET CLEANERS (Continued) **S102750264**

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602461147
DCR Number:	Not reported
AR Number:	24000549
Principal Name:	SWEET ONE HOUR CLEANERS INC
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

SWEET CLEANERS (Continued) **S102750264**

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN100593409
Region:	11
CN Number:	CN602463184
DCR Number:	Not reported
AR Number:	24000688
Principal Name:	SWEET ONE HOUR CLEANERS INC NO 2
Bill Addr1:	1401 W BEN WHITE BLVD
Bill Addr2:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Bill City/State/Zip:	AUSTIN, TX 78704 7603
EMail:	Not reported
Phone Number:	512 2881966
Site Name:	SWEET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Ind. Haz Waste:

Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	66873
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	02/22/1993
EPA Identification:	TXD981586811
Primary NAICS Code:	812320
Status Change Date:	19850930
Land Type:	PRIVATE
Description of Facility Site Location:	613 Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	SWEET CLEANERS INC
Contact Name:	MARK SCHECHTER
Contact Telephone Number:	512-4774083
Mailing Address:	613 CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787013214
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22124
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20041115
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	SWEET CLEANERS INC
Owner Mailing Address:	613 CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4774083
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	613 CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4774083
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MARK SCHECHTER
Contact Title:	Not reported
Contact Role:	PRICONT
Contact Address:	613 CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4774083
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	70445
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

SWEET CLEANERS (Continued) **S102750264**

Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	70446
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	70447
Texas Waste Code:	Not reported
Texas Waste Code 2:	3605601H
Waste Code Status:	INACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	UNKNOWN

SWEET CLEANERS (Continued) **S102750264**

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	613 CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000303525
Principal Name:	SWEET CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	613 CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000303525
Principal Name:	SWEET CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	613 CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000303525
Principal Name:	SWEET CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	613 CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000303525
Principal Name:	SWEET CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWF

CENTRAL REGISTRY:

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE

SWEET CLEANERS (Continued) **S102750264**

Status Date:	##########
Customer Number:	CN600303325
Customer Name:	SWEET CLEANERS INC
Customer Legal Name:	SWEET CLEANERS, INC. NO. 3
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/22/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600303325
Customer Name:	SWEET CLEANERS INC
Customer Legal Name:	SWEET CLEANERS, INC. NO. 3
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/22/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600303325
Customer Name:	SWEET CLEANERS INC
Customer Legal Name:	SWEET CLEANERS, INC. NO. 3
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/22/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600303325
Customer Name:	SWEET CLEANERS INC

SWEET CLEANERS (Continued) **S102750264**

Customer Legal Name:	SWEET CLEANERS, INC. NO. 3
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/22/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600303325
Customer Name:	SWEET CLEANERS INC
Customer Legal Name:	SWEET CLEANERS, INC. NO. 3
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/22/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602461147
Customer Name:	SWEET ONE HOUR CLEANERS INC
Customer Legal Name:	Sweet One Hour Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	613 Congress Ave, Austin, TX

Regulated Entity Number:	RN100593409
Name:	SWEET CLEANERS
Address:	613 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602461147
Customer Name:	SWEET ONE HOUR CLEANERS INC
Customer Legal Name:	Sweet One Hour Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########

SWEET CLEANERS (Continued) **S102750264**

Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 613 Congress Ave, Austin, TX

Regulated Entity Number: RN100593409
Name: SWEET CLEANERS
Address: 613 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-3214
Status: ACTIVE
Status Date: ##########
Customer Number: CN602461147
Customer Name: SWEET ONE HOUR CLEANERS INC
Customer Legal Name: Sweet One Hour Cleaners, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 613 Congress Ave, Austin, TX

Regulated Entity Number: RN100593409
Name: SWEET CLEANERS
Address: 613 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-3214
Status: ACTIVE
Status Date: ##########
Customer Number: CN602461147
Customer Name: SWEET ONE HOUR CLEANERS INC
Customer Legal Name: Sweet One Hour Cleaners, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 613 Congress Ave, Austin, TX

Regulated Entity Number: RN100593409
Name: SWEET CLEANERS
Address: 613 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-3214
Status: ACTIVE
Status Date: ##########
Customer Number: CN602461147
Customer Name: SWEET ONE HOUR CLEANERS INC
Customer Legal Name: Sweet One Hour Cleaners, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320

SWEET CLEANERS (Continued) **S102750264**

Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 613 Congress Ave, Austin, TX

Regulated Entity Number: RN100593409
Name: SWEET CLEANERS
Address: 613 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-3214
Status: ACTIVE
Status Date: ##########
Customer Number: CN602972846
Customer Name: SWEET CLEANERS INC NO 3
Customer Legal Name: Sweet Cleaners, Inc. No.3
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 7/1/2005
Affiliation End Date: 6/2/2006
Customer Status: UNVALD
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 613 Congress Ave, Austin, TX

Click this hyperlink while viewing on your computer to access
34 additional TX CENTRAL REG: record(s) in the EDR Site Report.

DG1483 **SWEET ONE HOUR** **EDR Hist Cleaner** **1013778351**
West **613 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
123 ft. **Site 9 of 16 in cluster DG**

Actual: EDR Hist Cleaner
496 ft.

Focus Map:
11

Year:	Name:	Type:
1958	SWIFT 11 HOUR CLNS	CLEANERS AND DYERS
1962	SWEET ONE HOUR	CLEANERS AND DYERS
1965	SWEET ONE HOUR DRY	CLEANERS AND DYERS
1969	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1970	SWEET ONE HOUR DRY CLEANERS NO	CLEANERS AND DYERS
1970	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1971	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1972	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1973	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1974	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1975	SWEET ONE HOUR DRY CLEANERS NO	CLEANERS AND DYERS
1975	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1976	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1977	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1978	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1979	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1980	SWEET ONE HOUR DRY CLEANERS NO	CLEANERS AND DYERS
1980	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1982	SWEETS ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1983	SWEETS 1 HOUR CLNRS	Drycleaning Plants, Except Rugs
1985	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1986	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1987	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1988	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1989	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

SWEET ONE HOUR (Continued) **1013778351**

1990	SWEET ONE HOUR DRY CLEANERS	CLEANERS AND DYERS
1990	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1991	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1992	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1993	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1994	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1995	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1996	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1997	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1998	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
1999	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2000	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2001	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2002	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2003	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2004	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2005	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2005	M S & P INC	Garment Pressing And Cleaners' Agents
2006	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2006	M S & P INC	Garment Pressing And Cleaners' Agents
2007	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2007	SWEET CLEANERS	Garment Pressing And Cleaners' Agents
2008	SWEET CLEANERS	Garment Pressing And Cleaners' Agents
2008	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2009	SWEET CLEANERS	Garment Pressing And Cleaners' Agents
2009	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2010	SWEET CLEANERS	Garment Pressing And Cleaners' Agents
2010	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs
2011	SWEET DRY CLEANERS	Garment Pressing And Cleaners' Agents
2011	SWEETS ONE HOUR CLEANERS INC	Drycleaning Plants, Except Rugs

---

DN1484 **JOE SING CHINESE LAUNDRY** **EDR Hist Cleaner** **1013787318**
NNE **104 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 4 of 8 in cluster DN**

Actual:
494 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1901	JOE SING CHINESE LAUNDRY	LAUNDRIES

FG1485 **BUSH NET** **EDR Hist Auto** **1021704433**
ESE **105 E ANNIE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.023 mi.
124 ft. **Site 8 of 8 in cluster FG**

Actual:
568 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1987	BUSH NET	Gasoline Service Stations

DB1486 **ROSENTRITT H L GA** **EDR Hist Auto** **1013765483**
WNW **115 8TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 6 of 11 in cluster DB**

Actual:
502 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	BLAND JOHN C GARAGE	AUTOMOBILE GARAGES
1935	ROSENTRITT H L GA	AUTOMOBILE REPAIRERS

DB1487 **DAY R L GARAGE AUTO REPRS** **EDR Hist Auto** **1013762994**
WNW **114 8TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 7 of 11 in cluster DB**

Actual:
502 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	WESSENBERG AXEL AUTO	AUTOMOBILE REPAIRERS
1940	DAY RALPH L AUTO	AUTOMOBILE REPAIRING
1947	DAY R L GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1947	SODERBERG GARAGE AUTO REPR	AUTOMOBILE REPAIRING

EH1488 **401 S. 1ST ST PROJECT** **TX HIST UST** **S128728779**
NW **401 S. 1ST ST.** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 5 of 9 in cluster EH**

Actual:
453 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	401 S. 1ST ST PROJECT
Address:	401 S. 1ST ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3429
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EH1489 **N/A** **TX RDR** **S127543113**
NW **401 S FIRST STREET** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 6 of 9 in cluster EH**

Actual:
453 ft.

RDR:

Focus Map:
11

RDR ID:	27328
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	N/A
Address:	401 S FIRST STREET
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/26/2019

N/A (Continued) **S127543113**

Due Date:	9/24/2019
Tank Owner:	STREAM REALTY AUSTIN LP
Contact Person:	ERIC HERRON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/23/2019
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

AL1490 **7-ELEVEN 12683** **TX LPST** **U001243593**
WNW **808 W KOENIG LN** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX HIST UST**
0.023 mi. **TX Financial Assurance**
124 ft. **Site 13 of 13 in cluster AL**

Actual:
700 ft.

Focus Map:
8

LPST:

Name:	7 ELEVEN 12683
Address:	808 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0007170
LPST Id:	099954
Facility Location:	KOENIG
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/22/1991
Entered Date:	09/25/1991
Reported Date:	08/22/1991
Closure Date:	06/25/2003
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3/1P
Coordinators RPR:	RWS
Responsible Party Name:	Not reported
Responsible Party Contact:	JANE LOMAS
Responsible Party Address:	1201 BELTLINE RD
Responsible Party City,St,Zip:	COPPELL, TX 75019
Responsible Party Telephone:	817/341-8314
Reported Date:	08/22/1991
Case Start Date:	06/25/2003
Reference Number:	RN102065653
Project Manager:	RSHAVER

UST:

7-ELEVEN 12683 (Continued) **U001243593**

Name:	7-ELEVEN 12683
Address:	808 W KOENIG LN
City,State,Zip:	AUSTIN, TX 787521502
AI Number:	7170
Facility Type:	RETAIL
Facility Begin Date:	04/01/1979
Facility Status:	INACTIVE
Additional ID:	430339092002120
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	WILLO SMITH,ENVIR MGR
Contact Organization Name:	7-ELEVEN 12683
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	4075322039
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	430339092002120
Ai Number:	7170
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

7-ELEVEN 12683 (Continued) **U001243593**

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	430339092002120
AI Number:	7170
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46172
Cert ID:	28074
AI Number:	7170
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46172
Cert ID:	28073
AI Number:	7170
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN 12683 (Continued) **U001243593**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18600
Facility ID:	46172
Ai Number:	7170
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/15/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

7-ELEVEN 12683 (Continued) **U001243593**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26077
UST ID:	18600
AI Number:	7170
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

7-ELEVEN 12683 (Continued) **U001243593**

More Self Certification:

Self Cert ID:	2923
Cert ID:	149269
UST Comprt ID:	444813
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149274
UST Comprt ID:	444807
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149277
UST Comprt ID:	444804
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149268
UST Comprt ID:	444812
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149270
UST Comprt ID:	444811
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	251565
UST Comprt ID:	723254
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149275
UST Comprt ID:	444806
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

7-ELEVEN 12683 (Continued) **U001243593**

Self Cert ID:	2923
Cert ID:	235927
UST Comprt ID:	677295
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	149276
UST Comprt ID:	444805
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	149273
UST Comprt ID:	444808
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	149271
UST Comprt ID:	444810
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	149278
UST Comprt ID:	444803
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	220237
UST Comprt ID:	631335
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Self Cert ID:	2923
Cert ID:	149272
UST Comprt ID:	444809
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

7-ELEVEN 12683 (Continued) **U001243593**

Install Date:	04/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18601
Facility ID:	46172
Ai Number:	7170
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/15/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

7-ELEVEN 12683 (Continued) **U001243593**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	26078
UST ID:	18601
AI Number:	7170
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	2923
Cert ID:	149269
UST Comprt ID:	444813
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

7-ELEVEN 12683 (Continued) **U001243593**

Self Cert ID:	2923
Cert ID:	149274
UST Comprt ID:	444807
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149277
UST Comprt ID:	444804
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149268
UST Comprt ID:	444812
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149270
UST Comprt ID:	444811
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	251565
UST Comprt ID:	723254
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149275
UST Comprt ID:	444806
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	235927
UST Comprt ID:	677295
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923

7-ELEVEN 12683 (Continued) **U001243593**

Cert ID:	149276
UST Comprt ID:	444805
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149273
UST Comprt ID:	444808
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149271
UST Comprt ID:	444810
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149278
UST Comprt ID:	444803
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	220237
UST Comprt ID:	631335
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149272
UST Comprt ID:	444809
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Install Date:	04/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18602
Facility ID:	46172

7-ELEVEN 12683 (Continued) **U001243593**

Ai Number:	7170
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/15/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	26079

7-ELEVEN 12683 (Continued) **U001243593**

UST ID:	18602
AI Number:	7170
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	2923
Cert ID:	149269
UST Comprt ID:	444813
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149274
UST Comprt ID:	444807
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923

7-ELEVEN 12683 (Continued) **U001243593**

Cert ID:	149277
UST Comprt ID:	444804
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149268
UST Comprt ID:	444812
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149270
UST Comprt ID:	444811
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	251565
UST Comprt ID:	723254
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149275
UST Comprt ID:	444806
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	235927
UST Comprt ID:	677295
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149276
UST Comprt ID:	444805
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149273

7-ELEVEN 12683 (Continued) **U001243593**

UST Comprt ID:	444808
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149271
UST Comprt ID:	444810
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149278
UST Comprt ID:	444803
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	220237
UST Comprt ID:	631335
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149272
UST Comprt ID:	444809
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Install Date:	04/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18603
Facility ID:	46172
Ai Number:	7170
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/15/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

7-ELEVEN 12683 (Continued) **U001243593**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26080
UST ID:	18603
AI Number:	7170
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

7-ELEVEN 12683 (Continued) **U001243593**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	2923
Cert ID:	149269
UST Comprt ID:	444813
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149274
UST Comprt ID:	444807
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149277
UST Comprt ID:	444804
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149268

7-ELEVEN 12683 (Continued) **U001243593**

UST Comprt ID:	444812
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149270
UST Comprt ID:	444811
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	251565
UST Comprt ID:	723254
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149275
UST Comprt ID:	444806
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	235927
UST Comprt ID:	677295
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149276
UST Comprt ID:	444805
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149273
UST Comprt ID:	444808
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149271
UST Comprt ID:	444810

7-ELEVEN 12683 (Continued) **U001243593**

UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149278
UST Comprt ID:	444803
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	220237
UST Comprt ID:	631335
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A
Self Cert ID:	2923
Cert ID:	149272
UST Comprt ID:	444809
UST ID:	143323
AI Number:	7170
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	2515
Facility ID:	46172
AI Number:	7170
Application Received Date:	02/15/2002
Scheduled Construction Date:	03/01/2002
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M20215023
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported

7-ELEVEN 12683 (Continued) **U001243593**

Owner AR At Time Of Construction: 3971
General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	2777
UST ID:	Not reported
NOC ID:	2515
AI Number:	7170
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001410
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46172
Additional ID:	430339092002120
Princ ID:	959578622001257
AI Number:	7170
Facility Name:	7-ELEVEN 12683
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #12683
Address:	808 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Id UST:	806
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

7-ELEVEN 12683 (Continued) **U001243593**

TX Financial Assurance 2:

Name:	7-ELEVEN 12683
Address:	808 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	46172
Finass ID:	28795
AI:	7170
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

DF1491 **DAY R L AUTO REPR** **EDR Hist Auto** **1013759992**
WNW **114 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.023 mi.
124 ft. **Site 15 of 25 in cluster DF**

Actual:
497 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	DAY R L AUTO REPR	AUTOMOBILE REPAIRERS

FB1492 **WASHBURNS TOWN & COUNTRY CLRS** **EDR Hist Cleaner** **1018877921**
ESE **1423 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.023 mi.
124 ft. **Site 5 of 6 in cluster FB**

Actual:
540 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1982	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1983	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1985	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1986	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1987	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1988	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1989	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1990	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1991	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1992	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1993	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs

WASHBURNS TOWN & COUNTRY CLRS (Continued) **1018877921**

1994	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1995	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1996	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1997	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1998	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
1999	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2000	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2001	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2002	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2003	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2004	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2005	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2006	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs
2007	WASHBURNS TOWN & COUNTRY CLRS	Drycleaning Plants, Except Rugs

---

FB1493 **WASHBURNS TOWN & COUNTRY** **TX DRYCLEANERS** **S106207311**
ESE **1423 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.023 mi.
124 ft. **Site 6 of 6 in cluster FB**

Actual:
540 ft.

Focus Map:
14

DRYCLEANERS:

Name:	WASHBURNS TOWN & COUNTRY
Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24001686
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	1423 S CONGRESS AVE
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 2434
EMail:	Not reported
Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	WASHBURNS TOWN & COUNTRY
Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24001686
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	1423 S CONGRESS AVE
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 2434
EMail:	Not reported

WASHBURNS TOWN & COUNTRY (Continued) **S106207311**

Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	5200
Part Stat:	NO
Gross Receipts:	> $200,000

Name:	WASHBURNS TOWN & COUNTRY
Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24002648
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	Not reported
Bill Addr2:	Not reported
Bill City/State/Zip:	Not reported
EMail:	Not reported
Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	5200
Part Stat:	NO
Gross Receipts:	> $200,000

Name:	WASHBURNS TOWN & COUNTRY
Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24001686
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	1423 S CONGRESS AVE
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 2434
EMail:	Not reported
Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	5200
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WASHBURNS TOWN & COUNTRY

WASHBURNS TOWN & COUNTRY (Continued) **S106207311**

Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24001686
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	1423 S CONGRESS AVE
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 2434
EMail:	Not reported
Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	5200
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WASHBURNS TOWN & COUNTRY
Address:	1423 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN104068432
Region:	11
CN Number:	CN602513665
DCR Number:	Not reported
AR Number:	24001686
Principal Name:	DOUGLAS L WASHBURN & KENNETH W WASHBURN
Bill Addr1:	1423 S CONGRESS AVE
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 2434
EMail:	Not reported
Phone Number:	Not reported
Site Name:	WASHBURNS TOWN & COUNTRY
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	5200
Part Stat:	NO
Gross Receipts:	> $150,000

JM1494 **CAPITAL FOOD STOP 2** **TX UST** **U001269484**
SE **8201 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.023 mi.
124 ft. **Site 1 of 2 in cluster JM**

Actual:
737 ft.

Focus Map:
6

UST:

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535918
AI Number:	36623
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Facility Status:	ACTIVE
Additional ID:	455541512002054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	AZIZ MAKNOJIYA,OPERATOR
Contact Organization Name:	CAPITAL FOOD STOP 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129730668
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/21/2021
Signature Name/Title On Earliest Reg Form:	BIKASH JOSHI,CASHIER
Application Received Date On Earliest Reg Form:	07/19/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	865345452010342
Additional ID:	455541512002054
Ai Number:	36623
Operator CN:	CN603785494
Operator Name:	RUBY BROTHERS LP
Operator Effective Begin Date:	07/30/2006
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	AZIZ MAKNOJIYA/REP
Contact Organization Name:	RUBY BROTHERS LP
Contact Mailing Address (Delivery):	8201 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-5918
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9730668
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603785494
Owner Last Name:	RUBY BROTHERS LP
Owner First Name:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	8201 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	5918
Contact Phone Number/Ext:	1 512 9730668/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	865345452010342
Additional ID:	455541512002054
AI Number:	36623
Owner Effective Begin Date:	07/30/2006
State Tax ID:	12042144639
Contact Role:	OWNOPRCON
Contact Name/Title:	AZIZ MAKNOJIYA/REP
Contact Organization Name:	RUBY BROTHERS LP

Self Certification:

Self Cert ID:	74020
Cert ID:	373730
AI Number:	36623
Self Certification Date:	08/01/2022
Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	356597
AI Number:	36623
Self Certification Date:	06/21/2021
Signature Name/Title:	BIKASH JOSHI CASHIER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	340662
AI Number:	36623
Self Certification Date:	07/21/2020
Signature Name/Title:	BIKASH JOSHI CLERK
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	323089
AI Number:	36623
Self Certification Date:	06/19/2019
Signature Name/Title:	AZIZ MAKNOJIA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	307795
AI Number:	36623
Self Certification Date:	06/28/2018
Signature Name/Title:	BIKASH JOSHI CASHIER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74020
Cert ID:	290590
AI Number:	36623
Self Certification Date:	07/19/2017
Signature Name/Title:	AZIZ MAKNOJIYA OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74020
Cert ID:	274065
AI Number:	36623
Self Certification Date:	06/20/2016
Signature Name/Title:	BIKASH JOSHI CASHIER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74020
Cert ID:	256916
AI Number:	36623
Self Certification Date:	06/15/2015
Signature Name/Title:	BIKASH JOSHI CASHIER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	240159
AI Number:	36623
Self Certification Date:	07/28/2014
Signature Name/Title:	RIY ALI REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	223363
AI Number:	36623
Self Certification Date:	07/06/2013
Signature Name/Title:	MEHMOOD BATANIA OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74020
Cert ID:	100380
AI Number:	36623
Self Certification Date:	07/05/2012
Signature Name/Title:	AZIZ MAKNOJIYA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100379
AI Number:	36623
Self Certification Date:	06/23/2011
Signature Name/Title:	RAHIM KHAWAPE REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100378
AI Number:	36623
Self Certification Date:	07/09/2010
Signature Name/Title:	RAHIM KHAWAPE REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100377
AI Number:	36623
Self Certification Date:	08/10/2009
Signature Name/Title:	AZIZ MAKNOJIYA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74020
Cert ID:	100376
AI Number:	36623
Self Certification Date:	07/04/2008
Signature Name/Title:	AZIZ MAKNOJIYA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74020
Cert ID:	100375
AI Number:	36623
Self Certification Date:	08/29/2007
Signature Name/Title:	AZIZ MAKNOJIYA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74020
Cert ID:	100374
AI Number:	36623
Self Certification Date:	10/18/2006
Signature Name/Title:	AZIZ MAKNOJIYA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100373
AI Number:	36623
Self Certification Date:	09/08/2005
Signature Name/Title:	KHUSIH MOHAMMAD OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100372
AI Number:	36623
Self Certification Date:	08/31/2004
Signature Name/Title:	GHULAM QADIR KHAN OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100371
AI Number:	36623
Self Certification Date:	12/29/2003
Signature Name/Title:	GHULAM QADIR KHAN
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100370
AI Number:	36623
Self Certification Date:	12/27/2002
Signature Name/Title:	CARLTON LABEFF AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100369
AI Number:	36623
Self Certification Date:	06/18/2002
Signature Name/Title:	CARLTON LABEFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100368
AI Number:	36623
Self Certification Date:	05/01/2002
Signature Name/Title:	ROBERT J BYRNES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74020
Cert ID:	100367
AI Number:	36623
Self Certification Date:	12/20/2000
Signature Name/Title:	RHONDA PAXTON ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10152
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	96887
Facility ID:	74020
Ai Number:	36623
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10152
UST Comprt ID:	107643
UST ID:	96887
AI Number:	36623
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14220
Cert ID:	48581
UST Comprt ID:	127515
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48579
UST Comprt ID:	127519
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48580
UST Comprt ID:	127516
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48577
UST Comprt ID:	127517
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48578
UST Comprt ID:	127518
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Install Date:	04/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10152
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	96888
Facility ID:	74020
Ai Number:	36623
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10152
UST Comprt ID:	107644
UST ID:	96888
AI Number:	36623
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14220
Cert ID:	48581
UST Comprt ID:	127515
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Self Cert ID:	14220
Cert ID:	48579
UST Comprt ID:	127519
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48580
UST Comprt ID:	127516
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48577
UST Comprt ID:	127517
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48578
UST Comprt ID:	127518
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Install Date:	04/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10152
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	96889
Facility ID:	74020
Ai Number:	36623
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10152
UST Comprt ID:	107645
UST ID:	96889
AI Number:	36623
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

CAPITAL FOOD STOP 2 (Continued) **U001269484**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14220
Cert ID:	48581
UST Comprt ID:	127515
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48579
UST Comprt ID:	127519
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48580
UST Comprt ID:	127516
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A
Self Cert ID:	14220
Cert ID:	48577
UST Comprt ID:	127517
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Self Cert ID:	14220
Cert ID:	48578
UST Comprt ID:	127518
UST ID:	53549
AI Number:	36623
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	9994
Facility ID:	74020
AI Number:	36623
Application Received Date:	10/18/2010
Scheduled Construction Date:	11/19/2010
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	66488
General Desc Of Prop Construct:	DEMO CONCRETE AND REMOVE SUPER SPILL BUCKET THEN PREP AREA AND INSTALL NEW CONCR ETE AND NEW SPILL BUCKET.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	10914
UST ID:	Not reported
NOC ID:	9994
AI Number:	36623
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	BAXTER ENVIRONMENTAL INC
Representative Name:	S B BAXTER
Mailing Address (Delivery):	15156 FOREST LN
Mailing Address (Internal Delivery):	Not reported
Mailing City:	CONROE
Mailing State:	TX
Mailing Zip:	77306
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Phone Number Country Code:	1
Phone Number Area Code:	281
Phone Number:	3998206
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	10913
UST ID:	Not reported
NOC ID:	9994
AI Number:	36623
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001400
Company Name:	ALPINE ENVIRONMENTAL TECHNOLOGIES INC
Representative Name:	KEVIN LEASURE
Mailing Address (Delivery):	PO BOX 691061
Mailing Address (Internal Delivery):	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77269
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	713
Phone Number:	4605777
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	10915
UST ID:	Not reported
NOC ID:	9994
AI Number:	36623
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001400
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Facility Billing Contacts:

Contact Organization Name:	RUBY BROTHERS LP
Contact Mailing Address (Delivery):	8201 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 5918
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74020
Additional ID:	455541512002054
Princ ID:	865345452010342
AI Number:	36623
Facility Name:	CAPITAL FOOD STOP 2
AR Number:	66488
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	AZIZ MAKNOJIYA/

HIST UST AUSTIN:

Name:	CAPITAL FOOD STOP #2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	632
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	271579
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2022
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000030825
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	253506
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2020
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000011970
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	235494
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2020
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000011970
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	201096
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2018
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000108520
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	216703
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2018
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000108520
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	183551
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2017
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000102319

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	166644
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2016
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00097778
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	147896
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2015
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00093514
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Facility ID:	74020
Finass ID:	131625
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2014
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00089370
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	112714
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2013
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00085830
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/28/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	7241
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

CAPITAL FOOD STOP 2 (Continued) **U001269484**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2011
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00077818
Coverage Amount:	1000000
Coverage Expiration Date:	07/28/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	55401
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2010
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00073906
Coverage Amount:	1000000
Coverage Expiration Date:	07/28/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	55402
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/28/2009
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00070794
Coverage Amount:	1000000
Coverage Expiration Date:	07/28/2010
Ins Premium Pre-Paid For Entire Yr:	Yes

CAPITAL FOOD STOP 2 (Continued) **U001269484**

Proof of Financial Assurance:	No

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	55403
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/29/2008
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 214 2391609
Policy Number:	04-TO-00068057
Coverage Amount:	1000000
Coverage Expiration Date:	03/29/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CAPITAL FOOD STOP 2
Address:	8201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74020
Finass ID:	55404
AI:	36623
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	07/19/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

JM1495 SE < 1/8 0.023 mi. 124 ft. | **CIRCLE K STORES INC**
8201 N LAMAR BLVD
AUSTIN, TX 78753
Site 2 of 2 in cluster JM | **EDR Hist Auto** | **1020957195**
N/A

Actual: 737 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1993	CIRCLE K CORPORATION	Convenience Stores
1994	CIRCLE K CORPORATION	Convenience Stores
1995	CIRCLE K STORES INC	Convenience Stores
1996	CIRCLE K STORES INC	Convenience Stores
1997	TOSCO MARKETING COMPANY	Convenience Stores
1998	TOSCO MARKETING COMPANY INC	Convenience Stores
1999	TOSCO MARKETING COMPANY	Convenience Stores
2000	TOSCO MARKETING COMPANY	Convenience Stores
2001	TOSCO MARKETING COMPANY	Convenience Stores
2002	CIRCLE K STORES INC	Convenience Stores
2003	CIRCLE K STORES INC	Convenience Stores
2004	CIRCLE K STORES INC	Convenience Stores
2005	CIRCLE K STORES INC	Convenience Stores
2006	CIRCLE K STORES INC	Convenience Stores
2007	CIRCLE K STORES INC	Convenience Stores
2008	CIRCLE K STORES INC	Convenience Stores

1496 ESE < 1/8 0.024 mi. 125 ft. | **LMN CORP**
1603 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678723**
N/A

Actual: 556 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	LMN CORP
Address:	1603 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0671
HID UST:	671
Inspection:	Not reported
Due:	06/01/2012

EK1497 SW < 1/8 0.024 mi. 125 ft. | **W. T. CASWELL**
501 S CONGRESS AVE
AUSTIN, TX
Site 7 of 7 in cluster EK | **TX HIST UST** | **S111678849**
N/A

Actual: 454 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	W. T. CASWELL
Address:	501 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0296
HID UST:	296
Inspection:	Not reported
Due:	06/01/2012

DA1498 **LOTT C G FILL STA** **EDR Hist Auto** **1013764008**
WNW **711 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.024 mi.
125 ft. **Site 15 of 25 in cluster DA**

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	LOTT C G FILL STA	GASOLINE AND OIL SERVICE STATIONS

AB1499 **PATS LAWNMOWER SERVICE** **TX LPST** **U001268714**
ESE **7205 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX HIST UST**
0.024 mi.
126 ft. **Site 10 of 11 in cluster AB**

Actual:
730 ft.

Focus Map:
6

LPST:

Name:	PATS LAWNMOWER SERVICE
Address:	7205 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0035789
LPST Id:	107259
Facility Location:	7205 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/21/1993
Entered Date:	05/31/1994
Reported Date:	09/21/1993
Closure Date:	12/08/1994
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	ERN
Responsible Party Name:	Not reported
Responsible Party Contact:	J L PASCHALL
Responsible Party Address:	1705 MORROW
Responsible Party City,St,Zip:	AUSTIN, TX 78757
Responsible Party Telephone:	512/459-8632
Reported Date:	09/21/1993
Case Start Date:	12/08/1994
Reference Number:	RN101492130
Project Manager:	ERN

UST:

Name:	PATS LAWNMOWER SERVICE
Address:	7205 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787522311
AI Number:	35789
Facility Type:	RETAIL
Facility Begin Date:	12/16/1986
Facility Status:	INACTIVE
Additional ID:	583605162002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No

PATS LAWNMOWER SERVICE (Continued) **U001268714**

Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	CHUCK MCCOY,BUSINESS OWNER
Contact Organization Name:	PATS LAWNMOWER SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124535846
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	D A STEWART,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780662
Owner Last Name:	PASCHALL J L
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	573605152002053
Additional ID:	583605162002053
AI Number:	35789
Owner Effective Begin Date:	12/16/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported

PATS LAWNMOWER SERVICE (Continued) **U001268714**

UST ID:	94702
Facility ID:	91913
Ai Number:	35789
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1

PATS LAWNMOWER SERVICE (Continued) **U001268714**

Tank Capacity:	3000
UST Comprt ID:	140490
UST ID:	94702
AI Number:	35789
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	94703
Facility ID:	91913
Ai Number:	35789
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

PATS LAWNMOWER SERVICE (Continued) **U001268714**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	140491
UST ID:	94703
AI Number:	35789
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

PATS LAWNMOWER SERVICE (Continued) **U001268714**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	94704
Facility ID:	91913
Ai Number:	35789
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

PATS LAWNMOWER SERVICE (Continued) **U001268714**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	140492
UST ID:	94704
AI Number:	35789
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

PATS LAWNMOWER SERVICE (Continued) **U001268714**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PASCHALL J L
Contact Mailing Address (Delivery):	1705 MORROW ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78757 1806
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91913
Additional ID:	583605162002053
Princ ID:	573605152002053
AI Number:	35789
Facility Name:	PATS LAWNMOWER SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	PATS OF AUSTIN
Address:	7205 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0409
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AB1500 ESE < 1/8 0.024 mi. 126 ft. | **SCOGIN EXXON PRODUCTS SERVICE STATION**
7205 LAMAR BLVD N
TRAVIS (County), TX 78752
Site 11 of 11 in cluster AB | **EDR Hist Auto** | **1013773419**
N/A

Actual: 730 ft.

Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1953	SCOGINS SERVICE	GASOLINE STATIONS
1958	SCOGIN SERV STA	GASOLINE STATIONS
1962	SCOGIN HUMBLE	GASOLINE STATIONS
1965	SCOGIN HUMBLE PRODUCTS	GASOLINE STATIONS
1970	SCOGIN HUMBLE PRODUCTS SERVICE	GASOLINE STATIONS
1970	SCOGIN HUMBLE SERVICE STATION	Gasoline Service Stations
1971	SCOGINS GAYLORD SERVICE STN	Gasoline Service Stations
1972	SCOGINS GAYLORD SERVICE STN	Gasoline Service Stations
1973	SCOGINS GAYLORD SERVICE STN	Gasoline Service Stations
1974	SCOGINS GAYLORD SERVICE STN	Gasoline Service Stations
1975	SCOGIN EXXON PRODUCTS SERVICE S	GASOLINE STATIONS
1975	SCOGINS GAYLORD SERVICE STN	Gasoline Service Stations
1976	SCOGGIN EXXON SERVICE STATION	Gasoline Service Stations
1977	SCOGGIN EXXON SERVICE STATION	Gasoline Service Stations
1978	SCOGGIN EXXON SERVICE STATION	Gasoline Service Stations
1979	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1980	SCOGIN EXXON PRODUCTS SERVICE S	GASOLINE STATIONS
1980	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1982	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1983	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1985	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1986	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations
1987	SCOGIN EXXON SERVICE STATION	Gasoline Service Stations

JN1501 West < 1/8 0.024 mi. 126 ft. | **FORMER 7 ELEVEN 17810**
12430 N LAMAR BLVD
AUSTIN, TX
Site 1 of 3 in cluster JN | **TX RDR** | **S127538717**
N/A

Actual: 707 ft.

Focus Map: 2

RDR:

RDR ID:	14444
Facility ID:	7164
RN:	Not reported
CN:	Not reported
Name:	FORMER 7 ELEVEN 17810
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/29/2005
Due Date:	6/28/2005
Tank Owner:	7 ELEVEN INC
Contact Person:	RON FULENCHEK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/13/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC

FORMER 7 ELEVEN 17810 (Continued) **S127538717**

Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/13/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JN1502 **PRIME MART** **TX UST** **U001243587**
West **12430 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.024 mi.
126 ft. **Site 2 of 3 in cluster JN**

Actual:
707 ft.

Focus Map:
2

UST:

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787531319
AI Number:	7164
Facility Type:	RETAIL
Facility Begin Date:	04/01/1976
Facility Status:	ACTIVE
Additional ID:	695703732002116
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	ARIF ALI,
Contact Organization Name:	PRIME MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124134619
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	ALIARIFEER@YAHOO.COM
Signature Date On Earliest Reg Form:	10/07/2022
Signature Name/Title On Earliest Reg Form:	ARIF ALI,OPERATOR
Application Received Date On Earliest Reg Form:	10/17/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	400431422006115
Additional ID:	695703732002116
Ai Number:	7164
Operator CN:	CN603024134
Operator Name:	PRIME MART INC
Operator Effective Begin Date:	09/14/2007
Operator Type:	CO
Operator Role:	OWNOPRCON

PRIME MART (Continued) **U001243587**

Contact Name:	ARIF ALI/
Contact Organization Name:	PRIME MART INC
Contact Mailing Address (Delivery):	12430 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-1319
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4134619
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	ALIARIFEER@YAHOO.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603024134
Owner Last Name:	PRIME MART INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	12430 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	1319
Contact Phone Number/Ext:	1 512 4134619/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	ALIARIFEER@YAHOO.COM
Contact Address Deliverable:	Not reported
Princ ID:	400431422006115
Additional ID:	695703732002116
AI Number:	7164
Owner Effective Begin Date:	09/14/2007
State Tax ID:	12028986136
Contact Role:	OWNOPRCON
Contact Name/Title:	ARIF ALI/
Contact Organization Name:	PRIME MART INC

Self Certification:

Self Cert ID:	46166
Cert ID:	378880
AI Number:	7164
Self Certification Date:	10/07/2022
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	362437
AI Number:	7164
Self Certification Date:	10/10/2021
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	345445
AI Number:	7164
Self Certification Date:	10/10/2020
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	328106
AI Number:	7164
Self Certification Date:	09/30/2019
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	309872
AI Number:	7164
Self Certification Date:	09/12/2018
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	294905
AI Number:	7164
Self Certification Date:	09/30/2017
Signature Name/Title:	ARIF ALI OP/OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	277706
AI Number:	7164
Self Certification Date:	09/30/2016
Signature Name/Title:	ARIF ALI OPER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	P

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	260444
AI Number:	7164
Self Certification Date:	09/01/2015
Signature Name/Title:	ARIF ALI VP
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	243911
AI Number:	7164
Self Certification Date:	08/22/2014
Signature Name/Title:	ARIF ALI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	227458
AI Number:	7164
Self Certification Date:	09/30/2013
Signature Name/Title:	DILAWAR ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	P

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	46166
Cert ID:	27789
AI Number:	7164
Self Certification Date:	10/01/2012
Signature Name/Title:	DILAWAR ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46166
Cert ID:	27788
AI Number:	7164
Self Certification Date:	10/02/2011
Signature Name/Title:	DILAWAR N ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46166
Cert ID:	27787
AI Number:	7164
Self Certification Date:	08/20/2010
Signature Name/Title:	DILAWAR N ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46166
Cert ID:	27786
AI Number:	7164
Self Certification Date:	11/12/2009
Signature Name/Title:	DILAWAR ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46166
Cert ID:	27785
AI Number:	7164
Self Certification Date:	08/27/2008
Signature Name/Title:	DILAWAR ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46166
Cert ID:	27784
AI Number:	7164
Self Certification Date:	12/15/2006
Signature Name/Title:	DILAWAR N ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27783
AI Number:	7164
Self Certification Date:	12/14/2006
Signature Name/Title:	DILAWAR N ALI PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27782
AI Number:	7164
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MANANGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27781
AI Number:	7164
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27780
AI Number:	7164
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27779
AI Number:	7164
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46166
Cert ID:	27778
AI Number:	7164
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported

PRIME MART (Continued) **U001243587**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18582
Facility ID:	46166
Ai Number:	7164
Tank Id:	1B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/30/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

PRIME MART (Continued) **U001243587**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1B
Tank Capacity:	10000
UST Comprt ID:	26045
UST ID:	18582
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976

PRIME MART (Continued) **U001243587**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18583
Facility ID:	46166
Ai Number:	7164
Tank Id:	2B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/30/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

PRIME MART (Continued) **U001243587**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2B
Tank Capacity:	8000
UST Comprt ID:	26046
UST ID:	18583
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18584
Facility ID:	46166

PRIME MART (Continued) **U001243587**

Ai Number:	7164
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/30/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	26047

PRIME MART (Continued) **U001243587**

UST ID:	18584
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	11/06/1996
Tank Registration Date:	01/23/1997
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	182503
Facility ID:	46166
Ai Number:	7164
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/09/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

PRIME MART (Continued) **U001243587**

Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/14/1997

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	26048
UST ID:	182503
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

PRIME MART (Continued) **U001243587**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	11/06/1996
Tank Registration Date:	01/23/1997
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	182504
Facility ID:	46166
Ai Number:	7164
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/09/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N

PRIME MART (Continued) **U001243587**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/14/1997

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	26049
UST ID:	182504
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

PRIME MART (Continued) **U001243587**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	10/02/2006
Tank Registration Date:	09/14/2007
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	208835
Facility ID:	46166
Ai Number:	7164
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	10/02/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

PRIME MART (Continued) **U001243587**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	12000
UST Comprt ID:	26050
UST ID:	208835
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

PRIME MART (Continued) **U001243587**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	10/02/2006
Tank Registration Date:	09/14/2007
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	208836
Facility ID:	46166
Ai Number:	7164
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	10/02/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

PRIME MART (Continued) **U001243587**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	6000
UST Comprt ID:	26051
UST ID:	208836
AI Number:	7164
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

PRIME MART (Continued) **U001243587**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Tank ID:	5
Tank Capacity:	6000
UST Comprt ID:	26052
UST ID:	208836
AI Number:	7164
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	2509
Facility ID:	46166
AI Number:	7164
Application Received Date:	09/12/2006
Scheduled Construction Date:	09/25/2006
UST Improvement:	N

PRIME MART (Continued) **U001243587**

UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60912004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	67780
General Desc Of Prop Construct:	Not reported

NOC ID:	2508
Facility ID:	46166
AI Number:	7164
Application Received Date:	12/09/2004
Scheduled Construction Date:	01/08/2005
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M41209001
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	67780
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	2771
UST ID:	Not reported
NOC ID:	2508
AI Number:	7164

PRIME MART (Continued) **U001243587**

Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000337
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2772
UST ID:	Not reported
NOC ID:	2509
AI Number:	7164
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000020
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	27154
UST ID:	182503
NOC ID:	Not reported
AI Number:	7164
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported

PRIME MART (Continued) **U001243587**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	27155
UST ID:	182504
NOC ID:	Not reported
AI Number:	7164
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42322
UST ID:	182503
NOC ID:	Not reported
AI Number:	7164
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001565
Company Name:	Not reported
Representative Name:	EDWARD MANN
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

PRIME MART (Continued) **U001243587**

Email Address:	Not reported
Cont/Cons/Installer ID:	42323
UST ID:	182504
NOC ID:	Not reported
AI Number:	7164
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001565
Company Name:	Not reported
Representative Name:	EDWARD MANN
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PRIME MART INC
Contact Mailing Address (Delivery):	12430 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 1319
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	46166
Additional ID:	695703732002116
Princ ID:	400431422006115
AI Number:	7164
Facility Name:	PRIME MART
AR Number:	67780
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ARIF ALI/

HIST UST AUSTIN:

Name:	PRIME MART INC
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	809
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PRIME MART (Continued) **U001243587**

TX Financial Assurance 2:

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	276533
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2022
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801 007
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	259447
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2021
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801 006
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	240169
AI:	7164
Mechanism Type Other:	Not reported

PRIME MART (Continued) **U001243587**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2020
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801005
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	222145
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2019
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801 004
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	203250
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2018
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO

PRIME MART (Continued) **U001243587**

Issuer Phone:	1 215 6401000
Policy Number:	G24839801 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	187988
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2017
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801 002
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	170042
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2016
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24839801 001
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD

PRIME MART (Continued) **U001243587**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	151971
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2015
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24802632001
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	135034
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2014
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 9514119
Policy Number:	G24779671001
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	117115
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

PRIME MART (Continued) **U001243587**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2013
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USC9425153-04
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/23/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	1535
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2012
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9425153 03
Coverage Amount:	1000000
Coverage Expiration Date:	01/23/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	28539
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2011
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC942515302
Coverage Amount:	1000000

PRIME MART (Continued) **U001243587**

Coverage Expiration Date:	01/23/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	28540
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2010
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 3361338
Policy Number:	USC942515301
Coverage Amount:	1000000
Coverage Expiration Date:	01/23/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	28541
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2009
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18649
Coverage Amount:	1000000
Coverage Expiration Date:	01/23/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166

PRIME MART (Continued) **U001243587**

Finass ID:	28542
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/23/2008
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18649
Coverage Amount:	1000000
Coverage Expiration Date:	01/23/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	PRIME MART
Address:	12430 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46166
Finass ID:	28543
AI:	7164
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	10/17/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

JN1503 **7-ELEVEN INC** **EDR Hist Auto** **1020402488**
West **12430 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.024 mi.
126 ft. **Site 3 of 3 in cluster JN**

Actual:
707 ft.

EDR Hist Auto

Focus Map:
2

Year:	Name:	Type:
1993	SOUTHLAND CORPORATION	Convenience Stores
2003	7-ELEVEN INC	Convenience Stores
2004	7-ELEVEN INC	Convenience Stores
2005	7-ELEVEN INC	Convenience Stores
2006	7-ELEVEN INC	Convenience Stores
2007	7-ELEVEN INC	Convenience Stores

7-ELEVEN INC (Continued) **1020402488**

2008	7-ELEVEN INC	Convenience Stores
2009	7-ELEVEN INC	Convenience Stores
2010	7-ELEVEN INC	Convenience Stores
2011	7-ELEVEN INC	Convenience Stores
2012	7-ELEVEN INC	Convenience Stores
2013	7-ELEVEN INC	Convenience Stores
2014	7-ELEVEN INC	Convenience Stores
2014	PRIME MART INC	Automotive Repair Shops, NEC

EH1504 **DEEP EDDY RUG CLEANERS** **EDR Hist Cleaner** **1013780237**
SE **418 BARTON SPRINGS RD** **N/A**
< 1/8 **AUSTIN, TX**
0.024 mi.
127 ft. **Site 7 of 9 in cluster EH**

Actual:
455 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1965	DEEP EDDY RUG CLEANERS	CARPET AND RUG CLEANERS

EH1505 **A KISS CLEAN** **EDR Hist Cleaner** **1013782425**
SE **418 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.024 mi.
127 ft. **Site 8 of 9 in cluster EH**

Actual:
455 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1962	A KISS CLEAN	CARPET AND RUG CLEANERS
1962	A KISS CLEAN	CARPET CLEANERS

CV1506 **EXXON MOBIL CORP** **EDR Hist Auto** **1020748190**
ESE **1005 CONGRESS AVE STE 900** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.024 mi.
128 ft. **Site 8 of 14 in cluster CV**

Actual:
527 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2005	CHEVRON TEXACO PUBLIC GOVT	Gasoline Service Stations
2005	TEXACO INC	Gasoline Service Stations, NEC
2006	TEXACO INC	Gasoline Service Stations, NEC
2006	CHEVRON USA INC	Gasoline Service Stations
2007	CHEVRON USA INC	Gasoline Service Stations, NEC
2007	TEXACO INC	Gasoline Service Stations, NEC
2008	CHEVRON USA INC	Gasoline Service Stations, NEC
2009	CHEVRON USA INC	Gasoline Service Stations, NEC
2010	CHEVRON USA INC	Gasoline Service Stations, NEC
2011	CHEVRON USA INC	Gasoline Service Stations, NEC
2011	EXXON MOBIL CORP	Gasoline Service Stations
2012	CHEVRON USA INC	Gasoline Service Stations, NEC
2013	CHEVRON USA INC	Gasoline Service Stations, NEC
2014	CHEVRON USA INC	Gasoline Service Stations, NEC

EXXON MOBIL CORP (Continued) **1020748190**

2014 EXXON MOBIL CORPORATION Gasoline Service Stations, NEC

JO1507 **TRAVIS COUNTY** **RCRA NonGen / NLR** **1000433328**
ESE **705 E 14TH ST STE B13** **FINDS** **TXD982563264**
< 1/8 **AUSTIN, TX 78702** **ECHO**
0.024 mi.
128 ft. **Site 1 of 2 in cluster JO**

Actual:
524 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20080806
Handler Name:	Travis County
Handler Address:	E 14TH ST STE B13
Handler City,State,Zip:	AUSTIN, TX 78702
EPA ID:	TXD982563264
Contact Name:	C H TRIPP
Contact Address:	PO BOX 1748
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-480-1366
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1748
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	Travis County
Owner Type:	Private
Operator Name:	Travis County
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

TRAVIS COUNTY (Continued) **1000433328**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20080818
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	U003
Waste Description:	Acetonitrile (I,T)
Waste Code:	U122
Waste Description:	Formaldehyde

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: TRAVIS COUNTY	
Legal Status:	Private
Date Became Current:	20080806
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1748
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-480-1366
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: TRAVIS COUNTY MEDICAL EXAMINERS OFFICE	
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1748
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-480-1366
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

TRAVIS COUNTY (Continued) **1000433328**

Owner/Operator Name: TRAVIS COUNTY MEDICAL EXAMINERS OFFICE
Legal Status: Not reported
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1748
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-480-1366
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRAVIS COUNTY
Legal Status: Private
Date Became Current: 20080806
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1748
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-480-1366
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRAVIS CTY
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080806
Handler Name: TRAVIS COUNTY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890221
Handler Name: TRAVIS COUNTY MEDICAL EXAMINER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

TRAVIS COUNTY (Continued) **1000433328**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: TRAVIS COUNTY MEDICAL EXAMINERS OFFICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005111262

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000433328
Registry ID: 110005111262
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005111262
Name: TRAVIS COUNTY
Address: 705 E 14TH ST STE B13
City,State,Zip: AUSTIN, TX 78702

JO1508 **TRAVIS COUNTY MEDICAL EXAMINERS OFFICE** **TX Ind. Haz Waste** **S103608963**
ESE **705 E 14TH ST STE B13** **N/A**
< 1/8 **AUSTIN, TX 78702**
0.024 mi.
128 ft. **Site 2 of 2 in cluster JO**

Actual:
524 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	TRAVIS COUNTY MEDICAL EXAMINERS OFFICE
Address:	705 E 14TH ST STE B13
City,State,Zip:	AUSTIN, TX 78702
Permit Number:	Not reported
Registration Number:	74706
Registration Initial Notification Date:	02/10/1989
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD982563264
Primary NAICS Code:	Not reported
Status Change Date:	19890210
Land Type:	Not reported
Description of Facility Site Location:	705 E 14th St, Ste B13, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TRAVIS COUNTY
Contact Name:	C H TRIPP
Contact Telephone Number:	512-4801366
Mailing Address:	PO BOX 1748
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671748
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29075
Site Owner Tax ID:	746000192
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20080806
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

TRAVIS COUNTY MEDICAL EXAMINERS OFFICE (Continued) **S103608963**

Ind. Haz Waste:

Operator Name:	TRAVIS COUNTY
Operator Address:	PO BOX 1748
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	1-512-4801366
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TRAVIS COUNTY
Owner Mailing Address:	PO BOX 1748
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	1-512-4801366
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 1748
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4801366
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 1748
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4801366
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	C TRIPP
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1748
Contact Address 2:	Not reported

TRAVIS COUNTY MEDICAL EXAMINERS OFFICE (Continued) **S103608963**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4801366
Contact Fax:	Not reported
Contact Email:	Not reported

JF1509 **TEXACO SHOPPERS MART** **TX RDR** **S127530908**
ESE **90 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.024 mi.
128 ft. **Site 3 of 3 in cluster JF**

Actual:
460 ft.

Focus Map:
14

RDR:

RDR ID:	4745
Facility ID:	34918
RN:	Not reported
CN:	Not reported
Name:	TEXACO SHOPPERS MART
Address:	90 EAST AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/6/2003
Due Date:	4/7/2003
Tank Owner:	TRIPLE S PETROLEUM INC
Contact Person:	ALLEN SMITH
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/10/2003
Project Manager:	Diana Kalich
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	96329
Comments:	RDR 1ST RECD 3/22/2002,RTN: QAQC MISSING, REG. FORM, WATER IN TANKHOLD??
Review Coordinator:	DRK
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	4/10/2003
Date Report Returned:	11/20/2002
Region:	Not reported
DKC RDR (misfiled):	Not reported

DY1510 **R & R SERVICE STA FILLING STA** **EDR Hist Auto** **1013773492**
SSW **214 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.024 mi.
128 ft. **Site 8 of 11 in cluster DY**

Actual:
476 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	PUBLIX OILS INC	GASOLINE AND OIL SERVICE STATIONS
1940	R & R SERVICE STA FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1953	REED SALES CO TIRES	GASOLINE STATIONS
1958	REED SLS CO GAS	GASOLINE STATIONS

DC1511 WNW < 1/8 0.024 mi. 129 ft. — **S.B. RICKS, 801 W 5TH ST, AUSTIN, TX** — **TX HIST UST** — **S111678799** / **N/A**

Site 5 of 11 in cluster DC

Actual: 463 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	S.B. RICKS
Address:	801 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0376
HID UST:	376
Inspection:	04/29/2009
Due:	04/29/2012

AT1512 SW < 1/8 0.024 mi. 129 ft. — **MANFRED HOLOK, 514 W 43RD ST, AUSTIN, TX** — **TX HIST UST** — **S111678744** / **N/A**

Site 8 of 8 in cluster AT

Actual: 621 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	MANFRED HOLOK
Address:	514 W 43RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0906
HID UST:	906
Inspection:	Not reported
Due:	06/01/2012

GM1513 WNW < 1/8 0.025 mi. 130 ft. — **SOCO CENTER, 3630 S CONGRESS AVE, AUSTIN, TX 78704** — **TX LPST, TX UST, TX VCP, TX HIST UST, TX Financial Assurance, TX RDR** — **U003566333** / **N/A**

Site 4 of 6 in cluster GM

Actual: 624 ft.
Focus Map: 14

LPST:

Name:	DIAMOND SHAMROCK CORNER STORE 2
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0045201
LPST Id:	109867
Facility Location:	3630 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/22/1993
Entered Date:	10/04/1995
Reported Date:	03/04/1994
Closure Date:	07/14/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/1P/1

SOCO CENTER (Continued) **U003566333**

Coordinators RPR:	VYF
Responsible Party Name:	Not reported
Responsible Party Contact:	SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/530-8403
Reported Date:	03/04/1994
Case Start Date:	07/14/1997
Reference Number:	RN102870243
Project Manager:	VYF

UST:

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787047238
AI Number:	45201
Facility Type:	RETAIL
Facility Begin Date:	01/01/1970
Facility Status:	ACTIVE
Additional ID:	231571092002259
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PATRICK OLIVER,PRESIDENT
Contact Organization Name:	SOCO CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	PBOVENTURES@GMAIL.COM
Signature Date On Earliest Reg Form:	09/30/2022
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,VP
Application Received Date On Earliest Reg Form:	10/06/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	231571092002259
Ai Number:	45201
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported

SOCO CENTER (Continued) **U003566333**

Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601101579
Owner Last Name:	OFLP-1 LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	290809782002116
Additional ID:	231571092002259
AI Number:	45201
Owner Effective Begin Date:	08/07/2012
State Tax ID:	32036480542
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	74587
Cert ID:	378612
AI Number:	45201
Self Certification Date:	09/30/2022
Signature Name/Title:	PATRICK OLIVER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	361696
AI Number:	45201
Self Certification Date:	09/24/2021
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	345393
AI Number:	45201
Self Certification Date:	09/14/2020
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	326125
AI Number:	45201
Self Certification Date:	08/28/2019
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	309933
AI Number:	45201
Self Certification Date:	09/17/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	293332
AI Number:	45201
Self Certification Date:	09/19/2017
Signature Name/Title:	Guy Oliver Authorized Legal Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	277667
AI Number:	45201
Self Certification Date:	10/04/2016
Signature Name/Title:	Guy Oliver Authorized Legal Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	259511
AI Number:	45201
Self Certification Date:	09/22/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	241795
AI Number:	45201
Self Certification Date:	09/11/2014
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	227288
AI Number:	45201
Self Certification Date:	10/04/2013
Signature Name/Title:	Guy Oliver Authroized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74587
Cert ID:	104828
AI Number:	45201
Self Certification Date:	09/28/2012
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104827
AI Number:	45201
Self Certification Date:	09/16/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104826
AI Number:	45201
Self Certification Date:	12/14/2010
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104825
AI Number:	45201
Self Certification Date:	08/02/2009
Signature Name/Title:	MICHAEL LOBEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104824
AI Number:	45201
Self Certification Date:	10/03/2008
Signature Name/Title:	MIKE LEBEL VP
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104823
AI Number:	45201
Self Certification Date:	09/10/2007
Signature Name/Title:	SATNAM K GREWAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104822
AI Number:	45201
Self Certification Date:	07/26/2005
Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104821
AI Number:	45201
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74587
Cert ID:	104820
AI Number:	45201
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

SOCO CENTER (Continued) **U003566333**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74587
Cert ID:	104819
AI Number:	45201
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74587
Cert ID:	104818
AI Number:	45201
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1970
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118345
Facility ID:	74587
Ai Number:	45201
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/21/2006
Empty:	N

SOCO CENTER (Continued) **U003566333**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9994
UST Comprt ID:	104330
UST ID:	118345
AI Number:	45201
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported

SOCO CENTER (Continued) **U003566333**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17638
Cert ID:	22792
UST Comprt ID:	59983
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22793
UST Comprt ID:	59982
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22794
UST Comprt ID:	59981
UST ID:	20505
AI Number:	45201
Tank ID:	3

SOCO CENTER (Continued) **U003566333**

Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22795
UST Comprt ID:	59980
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22796
UST Comprt ID:	59979
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22797
UST Comprt ID:	59978
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	232515
UST Comprt ID:	667635
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	266750
UST Comprt ID:	768351
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	249692
UST Comprt ID:	717782
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	283346
UST Comprt ID:	817492
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

SOCO CENTER (Continued) **U003566333**

Self Cert ID:	17638
Cert ID:	300120
UST Comprt ID:	867372
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	315767
UST Comprt ID:	914257
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	333973
UST Comprt ID:	968601
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	350773
UST Comprt ID:	1019739
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	366491
UST Comprt ID:	1067052
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	22798
UST Comprt ID:	59977
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638
Cert ID:	22799
UST Comprt ID:	59976
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Self Cert ID:	17638

SOCO CENTER (Continued) **U003566333**

Cert ID:	22800
UST Comprt ID:	59975
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22787
UST Comprt ID:	59986
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22788
UST Comprt ID:	59987
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22789
UST Comprt ID:	59988
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22790
UST Comprt ID:	59985
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22791
UST Comprt ID:	59984
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1970
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118346
Facility ID:	74587

SOCO CENTER (Continued) **U003566333**

Ai Number:	45201
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/21/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	9994
UST Comprt ID:	104331

SOCO CENTER (Continued) **U003566333**

UST ID:	118346
AI Number:	45201
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17638
Cert ID:	22792
UST Comprt ID:	59983
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22793
UST Comprt ID:	59982
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638

SOCO CENTER (Continued) **U003566333**

Cert ID:	22794
UST Comprt ID:	59981
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22795
UST Comprt ID:	59980
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22796
UST Comprt ID:	59979
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22797
UST Comprt ID:	59978
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	232515
UST Comprt ID:	667635
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	266750
UST Comprt ID:	768351
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	249692
UST Comprt ID:	717782
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	283346

SOCO CENTER (Continued) **U003566333**

UST Comprt ID:	817492
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	300120
UST Comprt ID:	867372
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	315767
UST Comprt ID:	914257
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	333973
UST Comprt ID:	968601
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	350773
UST Comprt ID:	1019739
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	366491
UST Comprt ID:	1067052
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22798
UST Comprt ID:	59977
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22799
UST Comprt ID:	59976

SOCO CENTER (Continued) **U003566333**

UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22800
UST Comprt ID:	59975
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22787
UST Comprt ID:	59986
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22788
UST Comprt ID:	59987
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22789
UST Comprt ID:	59988
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22790
UST Comprt ID:	59985
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22791
UST Comprt ID:	59984
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1

SOCO CENTER (Continued) **U003566333**

Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118347
Facility ID:	74587
Ai Number:	45201
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/21/2006
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

SOCO CENTER (Continued) **U003566333**

Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	9994
UST Comprt ID:	104332
UST ID:	118347
AI Number:	45201
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17638
Cert ID:	22792
UST Comprt ID:	59983
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22793

SOCO CENTER (Continued) **U003566333**

UST Comprt ID:	59982
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22794
UST Comprt ID:	59981
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22795
UST Comprt ID:	59980
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22796
UST Comprt ID:	59979
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22797
UST Comprt ID:	59978
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	232515
UST Comprt ID:	667635
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	266750
UST Comprt ID:	768351
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	249692
UST Comprt ID:	717782

SOCO CENTER (Continued) **U003566333**

UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	283346
UST Comprt ID:	817492
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	300120
UST Comprt ID:	867372
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	315767
UST Comprt ID:	914257
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	333973
UST Comprt ID:	968601
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	350773
UST Comprt ID:	1019739
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	366491
UST Comprt ID:	1067052
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22798
UST Comprt ID:	59977
UST ID:	20505

SOCO CENTER (Continued) **U003566333**

AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22799
UST Comprt ID:	59976
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22800
UST Comprt ID:	59975
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22787
UST Comprt ID:	59986
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22788
UST Comprt ID:	59987
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22789
UST Comprt ID:	59988
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22790
UST Comprt ID:	59985
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22791
UST Comprt ID:	59984
UST ID:	20505
AI Number:	45201

SOCO CENTER (Continued) **U003566333**

Tank ID:	3
Compartment ID:	A
Install Date:	10/30/2006
Tank Registration Date:	09/13/2007
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	208833
Facility ID:	74587
Ai Number:	45201
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	06/11/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N

SOCO CENTER (Continued) **U003566333**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	12/11/2006

Compartment Records:

Tank ID:	4
Tank Capacity:	14000
UST Comprt ID:	104333
UST ID:	208833
AI Number:	45201
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	10/30/2006

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	104334
UST ID:	208833
AI Number:	45201

SOCO CENTER (Continued) **U003566333**

Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	10/30/2006

More Self Certification:

Self Cert ID:	17638
Cert ID:	22792
UST Comprt ID:	59983
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22793
UST Comprt ID:	59982
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22794
UST Comprt ID:	59981

SOCO CENTER (Continued) **U003566333**

UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22795
UST Comprt ID:	59980
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22796
UST Comprt ID:	59979
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22797
UST Comprt ID:	59978
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	232515
UST Comprt ID:	667635
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	266750
UST Comprt ID:	768351
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	249692
UST Comprt ID:	717782
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	283346
UST Comprt ID:	817492
UST ID:	20505

SOCO CENTER (Continued) **U003566333**

AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	300120
UST Comprt ID:	867372
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	315767
UST Comprt ID:	914257
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	333973
UST Comprt ID:	968601
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	350773
UST Comprt ID:	1019739
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	366491
UST Comprt ID:	1067052
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22798
UST Comprt ID:	59977
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22799
UST Comprt ID:	59976
UST ID:	20505
AI Number:	45201

SOCO CENTER (Continued) **U003566333**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22800
UST Comprt ID:	59975
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22787
UST Comprt ID:	59986
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22788
UST Comprt ID:	59987
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22789
UST Comprt ID:	59988
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22790
UST Comprt ID:	59985
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17638
Cert ID:	22791
UST Comprt ID:	59984
UST ID:	20505
AI Number:	45201
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	29183
Facility ID:	74587
AI Number:	45201
Application Received Date:	01/20/2016

SOCO CENTER (Continued) **U003566333**

Scheduled Construction Date:	01/20/2016
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	01/20/2016
Signature Date On Form:	01/18/2016
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	OWNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	OFLP-1 LTD
Owner CN At Time Of Construction:	CN601101579
Owner AR At Time Of Construction:	44900
General Desc Of Prop Construct:	REPAIR VENT LINES THAT WERE DAMAGED BY VEHICLE.

NOC ID:	11157
Facility ID:	74587
AI Number:	45201
Application Received Date:	04/05/2006
Scheduled Construction Date:	06/12/2006
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60405003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	01/20/2016
Signature Date On Form:	01/18/2016
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	OWNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	11156
Facility ID:	74587
AI Number:	45201

SOCO CENTER (Continued) **U003566333**

Application Received Date:	06/15/2006
Scheduled Construction Date:	06/28/2006
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60615010
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	01/20/2016
Signature Date On Form:	01/18/2016
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	OWNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	29582
UST ID:	208833
NOC ID:	Not reported
AI Number:	45201
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11992
UST ID:	Not reported
NOC ID:	11156
AI Number:	45201
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000022

SOCO CENTER (Continued) **U003566333**

Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	44748
UST ID:	208833
NOC ID:	Not reported
AI Number:	45201
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001579
Company Name:	Not reported
Representative Name:	MARK SPENRATH
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	68838
UST ID:	Not reported
NOC ID:	29183
AI Number:	45201
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

SOCO CENTER (Continued) **U003566333**

Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	OFLP-1 LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	74587
Additional ID:	231571092002259
Princ ID:	290809782002116
AI Number:	45201
Facility Name:	SOCO CENTER
AR Number:	44900
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK OLIVER/PRESIDENT

VCP TCEQ:

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	REGION 11 - AUSTIN
Facility ID:	2337
VCP Record Date:	07/30/2010
Facility Type:	GAS STATION
PCA Number:	34528
Project Manager:	JSTEFEK
Phase:	WITHDRAWN
Acres at Site:	0.38
REM Program:	VCP
RN Number:	RN102870243
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	Not reported
Administrative Status:	INACTIVE
Region Notified of Application:	07/30/2010
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported

SOCO CENTER (Continued) **U003566333**

Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	07/30/2010
GW Target COC Class:	TPH; VOCS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2010-09-13 00:00:00
Soil Target COC Class:	TPH; VOCS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2337
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	345280
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D-200/12
Latitude:	0.00
Longitude:	0.00

HIST UST AUSTIN:

Name:	CONGRESS EXPRESS
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	384
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	276308
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO

SOCO CENTER (Continued) **U003566333**

Issuer Phone:	Not reported
Policy Number:	04TOP000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	258692
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	240124
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE

SOCO CENTER (Continued) **U003566333**

City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	220243
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	212879
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	202530
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

SOCO CENTER (Continued) **U003566333**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/27/2017
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	186092
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	168893
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000

SOCO CENTER (Continued) **U003566333**

Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	149980
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	132164
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587

SOCO CENTER (Continued) **U003566333**

Finass ID:	129073
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	116343
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57933
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SOCO CENTER (Continued) **U003566333**

Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	7935
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57934
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SOCO CENTER (Continued) **U003566333**

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57935
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57937
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/11/2008
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 512 3021887
Policy Number:	USC9424066
Coverage Amount:	1000000
Coverage Expiration Date:	09/11/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57936
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SOCO CENTER (Continued) **U003566333**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/11/2008
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC942406600
Coverage Amount:	1000000
Coverage Expiration Date:	09/11/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57938
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/13/2006
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 0 0
Policy Number:	USC5090134-00
Coverage Amount:	1000000
Coverage Expiration Date:	12/13/2007
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	74587
Finass ID:	57939
AI:	45201
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported

SOCO CENTER (Continued) **U003566333**

Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	27682
Facility ID:	45201
RN:	Not reported
CN:	Not reported
Name:	SOCO CENTER
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/4/2019
Due Date:	1/3/2020
Tank Owner:	OFLP-1 LTD
Contact Person:	PATRICK OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	12/27/2019
Project Manager:	Saul Garza
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GM1514 **DIAMOND SHAMROCK NO 232** **TX RDR** **S127533599**
WNW **3630 S CONGRESS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
130 ft. **Site 5 of 6 in cluster GM**

Actual:
624 ft.

Focus Map:
14

RDR:

RDR ID:	15502
Facility ID:	45201
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK NO 232
Address:	3630 S CONGRESS ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/24/2006
Due Date:	10/23/2006
Tank Owner:	SIGMOR CORP
Contact Person:	KENT HAMEL
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/27/2006
Project Manager:	PST Privitization Contract

DIAMOND SHAMROCK NO 232 (Continued) **S127533599**

Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	109867
Comments:	6P REOPEN OR NEW LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	10/27/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GM1515 **SOUTH CONGRESS FOOD MART** **TX RDR** **S127533600**
WNW **3630 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
130 ft. **Site 6 of 6 in cluster GM**

Actual:
624 ft.

Focus Map:
14

RDR:

RDR ID:	20066
Facility ID:	45201
RN:	Not reported
CN:	Not reported
Name:	SOUTH CONGRESS FOOD MART
Address:	3630 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/2/2013
Due Date:	3/3/2013
Tank Owner:	OFLP-1 LTD
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/20/2013
Project Manager:	Michelle Ogee
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SIR LTR SENT 1/6/12 NO FURTHER SITE CHECK REQUIRED; IR 11/12/12; 10/24/11 RDR, DEF LTR 1/6/12 PPC; IR 12/11/12; REC TECH RESP 1/2/2013 (RDR)
Review Coordinator:	MAO
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	1/6/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

DF1516 ESE < 1/8 0.025 mi. 130 ft. — **RIOS FRANK TAILOR**, **101 7TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780454** / **N/A**

Site 16 of 25 in cluster DF

Actual: 498 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1916	RIOS FRANK TAILOR	CLOTHES CLEANERS AND PRESSERS

DB1517 ESE < 1/8 0.025 mi. 131 ft. — **PAGE S F DCLO CLNR**, **802 CONGRESS AVE E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780514** / **N/A**

Site 8 of 11 in cluster DB

Actual: 503 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	PAGE S F DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

AM1518 WNW < 1/8 0.025 mi. 131 ft. — **LEGELTS FOREIGN SPORT CAR REPAIR**, **5412 LAMAR BLVD N**, **TRAVIS (County), TX 78751** — **EDR Hist Auto** — **1013763837** / **N/A**

Site 2 of 4 in cluster AM

Actual: 689 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1970	LEGELTS FOREIGN SPORT CAR REPAI	AUTOMOBILE REPAIRING

AM1519 WNW < 1/8 0.025 mi. 131 ft. — **N LAMAR U HAUL CTR**, **5412 N LAMAR BLVD**, **AUSTIN, TX 78751** — **TX UST**, **TX HIST UST** — **U001269284** / **N/A**

Site 3 of 4 in cluster AM

Actual: 689 ft. UST:

Focus Map: 8

Name:	N LAMAR U HAUL CTR
Address:	5412 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787511825
AI Number:	36409
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	966374862002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751

N LAMAR U HAUL CTR (Continued) **U001269284**

Contact Name/Title:	BILL GREEN,
Contact Organization Name:	N LAMAR U HAUL CTR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2107312810
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/17/1986
Signature Name/Title On Earliest Reg Form:	VERA M CLEMINGS,OFF MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600349617
Owner Last Name:	U-HAUL CO OF SAN ANTONIO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	545292462001309
Additional ID:	966374862002075
AI Number:	36409
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96300
Facility ID:	43089
Ai Number:	36409
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1995

N LAMAR U HAUL CTR (Continued) **U001269284**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	14898
UST ID:	96300
AI Number:	36409
Compartment ID:	A
Substance Stored1:	GASOLINE

N LAMAR U HAUL CTR (Continued) **U001269284**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	U-HAUL CO OF SAN ANTONIO
Contact Mailing Address (Delivery):	5810 SAN PEDRO AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78212 1250
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	43089
Additional ID:	966374862002075
Princ ID:	545292462001309
AI Number:	36409
Facility Name:	N LAMAR U HAUL CTR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HORACE ROYAL/

N LAMAR U HAUL CTR (Continued) **U001269284**

HIST UST AUSTIN:

Name:	U-HAUL
Address:	5412 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0589
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DR1520 **CURTIS GARAGE** **EDR Hist Auto** **1013765997**
SW **602 NECHES ST** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
131 ft. **Site 24 of 38 in cluster DR**

Actual:
486 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	EVANS VINCENT C AUTO REP	AUTOMOBILE REPAIRERS
1929	HAYDEN R J C AUTO REPR	AUTOMOBILE REPAIRERS
1935	CURTIS GARAGE	AUTOMOBILE REPAIRERS
1947	WASHINGTONS GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1953	WASHINGTONS GEO	AUTOMOBILE REPAIRING

EL1521 **AEGIS ASSOCIATES INC** **RCRA NonGen / NLR** **1000261878**
ESE **44 EAST AVE STE 100** **FINDS** **TXD982557167**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.025 mi. **TX Ind. Haz Waste**
131 ft. **Site 3 of 3 in cluster EL** **TX CENTRAL REGISTRY**

Actual:
454 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Aegis Associates Inc
Handler Address:	EAST AVE STE 100
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD982557167
Contact Name:	ROBERT MILLER
Contact Address:	EAST AVE STE 100
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-474-8789
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	EAST AVE STE 100
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Aegis Associates Inc

AEGIS ASSOCIATES INC (Continued) **1000261878**

Owner Type:	Private
Operator Name:	Aegis Associates Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:

AEGIS ASSOCIATES INC (Continued) **1000261878**

Owner/Operator Indicator:	Owner
Owner/Operator Name: AEGIS ASSOCIATES INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	44 EAST AVE STE 100
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-474-8789
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AEGIS ASSOCIATES INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	44 EAST AVE STE 100
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-474-8789
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CLAUDIA MILLER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19881003
Handler Name: AEGIS ASSOCIATES	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: AEGIS ASSOCIATES INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

AEGIS ASSOCIATES INC (Continued) **1000261878**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005108971

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000261878
Registry ID: 110005108971
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005108971
Name: AEGIS ASSOCIATES INC
Address: 44 EAST AVE STE 100
City,State,Zip: AUSTIN, TX 78701

Ind. Haz Waste:
Name: AEGIS ASSOCIATES
Address: 44 EAST AVE UNIT 100
City,State,Zip: AUSTIN, TX 78701
Permit Number: Not reported
Registration Number: 72867
Registration Initial Notification Date: 09/02/1988
Registration Last Amendment Date: 08/23/2001
EPA Identification: TXD982557167
Primary NAICS Code: Not reported
Status Change Date: 19880902
Land Type: PRIVATE
Description of Facility Site Location: 44 East Ave, Ste 100, Austin, TX
Site Primary Standard Industrial Code: Not reported
Registration is Generator of Waste: 1
TNRCC Region Number: 11

AEGIS ASSOCIATES INC (Continued) **1000261878**

Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AEGIS ASSOCIATES INC
Contact Name:	ROBERT MILLER
Contact Telephone Number:	512-4748789
Mailing Address:	44 EAST AVE UNIT 100
Mailing Address2:	STE 100
Mailing City,State,Zip:	AUSTIN, TX 787011182
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27305
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031030
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AEGIS ASSOCIATES INC
Operator Address:	44 EASTAVE UNIT 100
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4748789
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17424255564
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AEGIS ASSOCIATES INC

AEGIS ASSOCIATES INC (Continued) **1000261878**

Owner Mailing Address:	44 EASTAVE UNIT 100
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4748789
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17424255564
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	OFFICE/LABORATORY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19860601
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	OFFICE/LABORATORY

AEGIS ASSOCIATES INC (Continued) **1000261878**

Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19860601
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	OFFICE/LABORATORY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19880101
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	44 EASTAVE UNIT 100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748789
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	44 EASTAVE UNIT 100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748789
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ROBERT MILLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT

AEGIS ASSOCIATES INC (Continued) **1000261878**

Contact Address:	44 EASTAVE UNIT 100
Contact Address 2:	STE 100
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748789
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100569524
Name:	AEGIS ASSOCIATES
Address:	44 EAST AVE UNIT 100
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1182
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600280127
Customer Name:	AEGIS ASSOCIATES INC
Customer Legal Name:	AEGIS ASSOCIATES, INCORPORATED
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	44 East Ave, Ste 100, Austin, TX

Regulated Entity Number:	RN100569524
Name:	AEGIS ASSOCIATES
Address:	44 EAST AVE UNIT 100
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1182
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600280127
Customer Name:	AEGIS ASSOCIATES INC
Customer Legal Name:	AEGIS ASSOCIATES, INCORPORATED
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	44 East Ave, Ste 100, Austin, TX

DF1522 **ROYAL THE CLNRS** **EDR Hist Cleaner** **1013787082**
WNW **703 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
131 ft. **Site 17 of 25 in cluster DF**

Actual:
498 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	ROYAL THE CLNRS	CLOTHES CLEANERS AND PRESSERS
1922	MAJESTIC DRY CLNR	CLOTHES CLEANERS AND PRESSERS

DA1523 **ALFA OF AUSTIN** **EDR Hist Auto** **1013761910**
WNW **510 RIO GRANDE ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.025 mi.
131 ft. **Site 16 of 25 in cluster DA**

Actual:
471 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	ZAP FOREIGN CAR REPAIR	AUTOMOBILE REPAIRING
1975	ZAP MOTORS	General Automotive Repair Shops
1976	ZAP MOTORS	General Automotive Repair Shops
1977	ZAP MOTORS	General Automotive Repair Shops
1978	ZAP MOTORS	General Automotive Repair Shops
1979	ZAP MOTORS	General Automotive Repair Shops
1980	ZAP AUTO	AUTOMOBILE REPAIRING
1980	ZAP MOTORS	General Automotive Repair Shops
1982	ZAP MOTORS	General Automotive Repair Shops
1983	ZAP MOTORS	General Automotive Repair Shops
1983	ALFA OF AUSTIN	General Automotive Repair Shops
1984	ALFA OF AUSTIN	AUTOMOBILE REPAIRING
1985	ZAP MOTORS	General Automotive Repair Shops
1985	ALFA OF AUSTIN	General Automotive Repair Shops
1986	ZAP MOTORS	General Automotive Repair Shops
1986	ALFA OF AUSTIN	General Automotive Repair Shops
1987	ZAP MOTORS	General Automotive Repair Shops

FY1524 **BROWNS TWIN OAKS 66 SERVICE GAS STA** **EDR Hist Auto** **1013768841**
SE **620 OLTORF ST E** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.025 mi.
132 ft. **Site 3 of 4 in cluster FY**

Actual:
561 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1975	BROWNS TWIN OAKS 66 SERVICE GAS	GASOLINE STATIONS
1980	BROWNS TWIN OAKS 66 SERVICE GAS	GASOLINE STATIONS

JB1525 **WESLEY G M DCLO CLNR** **EDR Hist Cleaner** **1013778383**
ESE **913 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
132 ft. **Site 2 of 2 in cluster JB**

Actual:
508 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	WESLEY G M DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

IJ1526 WNW < 1/8 0.025 mi. 132 ft. | **BUSKES GARAGE 3208 GUADALUPE AUSTIN, TX** | **EDR Hist Auto** | **1013761108 N/A**

Site 4 of 4 in cluster IJ

Actual: 596 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1929	NORTH AUSTIN SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1935	NORTH AUSTIN SERVICE	GASOLINE AND OIL SERVICE STATIONS
1940	BUSKES GARAGE	AUTOMOBILE REPAIRING

FU1527 SE < 1/8 0.025 mi. 132 ft. | **SPEEDY ALIGNMENT WHEEL 111 OLTORF ST E TRAVIS (County), TX 78704** | **EDR Hist Auto** | **1013764596 N/A**

Site 10 of 13 in cluster FU

Actual: 602 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1990	SPEEDY ALIGNMENT WHEEL	AUTOMOBILE REPAIRING

CD1528 West < 1/8 0.025 mi. 133 ft. | **FORMER TEXAC0 1900 GUADALUPE AUSTIN, TX** | **TX RDR** | **S127527617 N/A**

Site 9 of 15 in cluster CD

Actual: 553 ft. RDR:

Focus Map: 11

RDR ID:	14308
Facility ID:	23190
RN:	Not reported
CN:	Not reported
Name:	FORMER TEXAC0
Address:	1900 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/8/2005
Due Date:	5/7/2005
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	JOYCE DAVIS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/17/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	97075
Comments:	6P REOPEN OR NEW LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/17/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CD1529 West < 1/8 0.025 mi. 133 ft. | **TEXACO**
1900 GUADALUPE ST
AUSTIN, TX 78705
Site 10 of 15 in cluster CD | **TX UST** | **U003566275**
TX HIST UST | **N/A**
TX Financial Assurance

Actual: 553 ft.

Focus Map: 11

UST:

Name:	TEXACO
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787055607
AI Number:	23190
Facility Type:	RETAIL
Facility Begin Date:	09/24/1986
Facility Status:	INACTIVE
Additional ID:	610852742002138
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	SCOTT HAGGERTON,
Contact Organization Name:	TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2146317213
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	ROGER EBERT,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	504380502001134
Additional ID:	610852742002138
Ai Number:	23190
Operator CN:	CN600124051
Operator Name:	MOTIVA ENTERPRISES LLC
Operator Effective Begin Date:	01/20/1999
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	GREG P LUCCHESI/GENERAL MANAGER
Contact Organization Name:	MOTIVA ENTERPRISES LLC
Contact Mailing Address (Delivery):	PO BOX 712
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PORT ARTHUR TX 77641-0712
Contact Phone Country Code:	1
Contact Phone Area Code:	409
Contact Phone Number:	9897001
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

TEXACO (Continued) **U003566275**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	GREG.LUCCHESI@MOTIVA.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600124051
Owner Last Name:	MOTIVA ENTERPRISES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 712
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	PORT ARTHUR
Contact Mailing State:	TX
Contact Mailing Zip:	77641
Contact Mailing Zip5:	0712
Contact Phone Number/Ext:	1 409 9897001/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	GREG.LUCCHESI@MOTIVA.COM
Contact Address Deliverable:	Not reported
Princ ID:	504380502001134
Additional ID:	610852742002138
AI Number:	23190
Owner Effective Begin Date:	01/20/1999
State Tax ID:	17602624904
Contact Role:	OWNOPRCON
Contact Name/Title:	GREG P LUCCHESI/GENERAL MANAGER
Contact Organization Name:	MOTIVA ENTERPRISES LLC

Self Certification:

Self Cert ID:	79642
Cert ID:	128118
AI Number:	23190
Self Certification Date:	01/16/2004
Signature Name/Title:	SCOTT HAGGERTON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79642
Cert ID:	128117
AI Number:	23190
Self Certification Date:	02/25/2003

TEXACO (Continued) **U003566275**

Signature Name/Title:	SCOTT HAGGERTON HSE COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79642
Cert ID:	127858
AI Number:	23190
Self Certification Date:	03/01/2002
Signature Name/Title:	GEORGE CARTWRIGHT SHE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79642
Cert ID:	127857
AI Number:	23190
Self Certification Date:	11/27/2000
Signature Name/Title:	R I RENEAU SH & E COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1

TEXACO (Continued) **U003566275**

Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59664
Facility ID:	79642
Ai Number:	23190
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

TEXACO (Continued) **U003566275**

Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	3000
UST Comprt ID:	123073
UST ID:	59664
AI Number:	23190
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59655
Facility ID:	79642
Ai Number:	23190
Tank Id:	2B

TEXACO (Continued) **U003566275**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2B
Tank Capacity:	8000
UST Comprt ID:	123064
UST ID:	59655
AI Number:	23190

TEXACO (Continued) **U003566275**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59656
Facility ID:	79642
Ai Number:	23190
Tank Id:	1B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

TEXACO (Continued) **U003566275**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1B
Tank Capacity:	8000
UST Comprt ID:	123065
UST ID:	59656
AI Number:	23190
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

TEXACO (Continued) **U003566275**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59657
Facility ID:	79642
Ai Number:	23190
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/22/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

TEXACO (Continued) **U003566275**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	123066
UST ID:	59657
AI Number:	23190
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

TEXACO (Continued) **U003566275**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1991
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	59663
Facility ID:	79642
Ai Number:	23190
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

TEXACO (Continued) **U003566275**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	123072
UST ID:	59663
AI Number:	23190
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

TEXACO (Continued) **U003566275**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1991
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	59659
Facility ID:	79642
Ai Number:	23190
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

TEXACO (Continued) **U003566275**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	3A
Tank Capacity:	10000
UST Comprt ID:	123068
UST ID:	59659
AI Number:	23190
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

TEXACO (Continued) **U003566275**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1991
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	59660
Facility ID:	79642
Ai Number:	23190
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/04/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

TEXACO (Continued) **U003566275**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	123069
UST ID:	59660
AI Number:	23190
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986

TEXACO (Continued) **U003566275**

Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59661
Facility ID:	79642
Ai Number:	23190
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

TEXACO (Continued) **U003566275**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	7
Tank Capacity:	3000
UST Comprt ID:	123070
UST ID:	59661
AI Number:	23190
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59662
Facility ID:	79642
Ai Number:	23190

TEXACO (Continued) **U003566275**

Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	6
Tank Capacity:	3000
UST Comprt ID:	123071
UST ID:	59662

TEXACO (Continued) **U003566275**

AI Number:	23190
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59658
Facility ID:	79642
Ai Number:	23190
Tank Id:	3B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

TEXACO (Continued) **U003566275**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	3B
Tank Capacity:	8000
UST Comprt ID:	123067
UST ID:	59658
AI Number:	23190
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

TEXACO (Continued) **U003566275**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	12231
Facility ID:	79642
AI Number:	23190
Application Received Date:	05/13/2004
Scheduled Construction Date:	05/19/2004
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M40513005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported

TEXACO (Continued) **U003566275**

Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 52374
General Desc Of Prop Construct: Not reported

Facility Billing Contacts:

Contact Organization Name:	MOTIVA ENTERPRISES LLC
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79642
Additional ID:	610852742002138
Princ ID:	504380502001134
AI Number:	23190
Facility Name:	TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	SHELL SERVICE STATION
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	778
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	TEXACO
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	79642
Finass ID:	64958
AI:	23190
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1994
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901

TEXACO (Continued) **U003566275**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	TEXACO
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	79642
Finass ID:	64957
AI:	23190
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1994
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

CD1530 **TEXACO** **TX LPST** **S105491636**
West **1900 GUADALUPE ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.025 mi.
133 ft. **Site 11 of 15 in cluster CD**

Actual:
553 ft.

Focus Map:
11

LPST:

Name:	TEXACO
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0023190
LPST Id:	097075
Facility Location:	1900 GUADALUPE ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/25/1990
Entered Date:	10/26/1990
Reported Date:	07/25/1990
Closure Date:	05/01/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SEL
Responsible Party Name:	Not reported
Responsible Party Contact:	DAVID J GUMBLEY
Responsible Party Address:	4500 FULLER DR STE 400
Responsible Party City,St,Zip:	IRVING, TX 75038
Responsible Party Telephone:	214/650-0200

TEXACO (Continued) **S105491636**

Reported Date:	07/25/1990
Case Start Date:	05/01/1999
Reference Number:	RN102246113
Project Manager:	SLAWLESS

Ind. Haz Waste:

Name:	STAR ENTERPRISES
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	75890
Registration Initial Notification Date:	12/18/1991
Registration Last Amendment Date:	08/17/2020
EPA Identification:	TX0000994863
Primary NAICS Code:	424710
Status Change Date:	19911218
Land Type:	PRIVATE
Description of Facility Site Location:	1900 Guadalupe, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	STAR ENTERPRISE GENERAL PARTNERSHIP
Contact Name:	DAVID GUMBLEY
Contact Telephone Number:	214-6500200
Mailing Address:	PO BOX 2099
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 772522099
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30226
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200817
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

TEXACO (Continued) **S105491636**

Ind. Haz Waste:

Operator Name:	STAR ENTERPRISES INC
Operator Address:	PO BOX 2099
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77252
Operator Country:	UNITED STA
Operator Telephone:	1-214-6500200
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	STAR ENTERPRISE GENERAL PARTNERSHIP
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	STAR ENTERPRISES INC
Owner Mailing Address:	PO BOX 2099
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Country:	UNITED STA
Owner Telephone:	1-214-6500200
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	STAR ENTERPRISE GENERAL PARTNERSHIP
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported

TEXACO (Continued) **S105491636**

Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2099
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-214-6500200
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2099
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-214-6500200
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DAVID GUMBLEY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2099
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-214-6500200
Contact Fax:	Not reported
Contact Email:	Not reported

CD1531 **CAMPBELL A B SERVICE STA** **EDR Hist Auto** **1013756670**
West **1900 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 12 of 15 in cluster CD**

Actual:
553 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	TEXAS CO THE STA	AUTOMOBILE FILLING STATIONS
1929	TEXAS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1935	CAMPBELL SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1940	CAMPBELL A B SERVICE STA FILLIN	GASOLINE AND OIL SERVICE STATIONS
1947	CAMPBELL A B SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	CAMPBELL & FLETCHER	GASOLINE STATIONS
1958	CAMPBELL	GASOLINE STATIONS
1962	CAMPBELL& FLETCHER	GASOLINE STATIONS
1965	CAMPBELL & FLETCHER	GASOLINE STATIONS
1969	CAMPBELL & FLETCHER SVC STN	Gasoline Service Stations
1970	CAMPBELL & FLETCHER TEXACO SERV	GASOLINE STATIONS
1970	CAMPBELL & FLETCHER SVC STN	Gasoline Service Stations
1971	CAMPBELL & FLETCHER SVC STN	Gasoline Service Stations
1972	HOLDER TEXACO	Gasoline Service Stations
1973	HOLDER TEXACO	Gasoline Service Stations
1974	HOLDER TEXACO	Gasoline Service Stations

CAMPBELL A B SERVICE STA (Continued) **1013756670**

1975	HOLDER FRANK TEXACO SERVICE	GASOLINE STATIONS
1975	HOLDER TEXACO	Gasoline Service Stations
1976	HOLDER TEXACO	Gasoline Service Stations
1977	HOLDER TEXACO	Gasoline Service Stations
1978	HOLDER TEXACO	Gasoline Service Stations
1979	HOLDER TEXACO	Gasoline Service Stations
1980	TEXACO FULL SERVICE	GASOLINE STATIONS
1980	HOLDER TEXACO	Gasoline Service Stations
1982	HOLDER TEXACO	Gasoline Service Stations
1983	HOLDER TEXACO	Gasoline Service Stations
1984	TEXACO ONE STOP	GASOLINE STATIONS
1990	TEXACO ONE STOP	GASOLINE STATIONS
1991	TEXACO 1 SHOP	Grocery Stores
1992	TEXACO 1 SHOP	Grocery Stores
1996	TEXACO 1 STOP	Gasoline Service Stations
1997	TEXACO 1 STOP	Gasoline Service Stations
1998	TENNISON J D	Gasoline Service Stations
1999	TENNISON J D	Gasoline Service Stations
2000	TENNISON J D	Gasoline Service Stations
2000	TENNISON PROPERTIES INC	Convenience Stores
2001	TENNISON J D	Gasoline Service Stations
2001	TENNISON PROPERTIES INC	Convenience Stores
2002	TENNISON J D	Gasoline Service Stations
2002	TENNISON PROPERTIES INC	Convenience Stores

CD1532 **TEXAS TAILOR SHOP** **EDR Hist Cleaner** **1013783701**
West **1900 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 13 of 15 in cluster CD**

Actual:
553 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	TEXAS TAILOR SHOP	CLOTHES CLEANERS AND PRESSERS

CD1533 **TEXACO STATION** **TX RDR** **S127527618**
West **1900 GUADALUPE** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 14 of 15 in cluster CD**

Actual:
553 ft.
RDR:

Focus Map:
11

RDR ID:	13530
Facility ID:	23190
RN:	Not reported
CN:	Not reported
Name:	TEXACO STATION
Address:	1900 GUADALUPE
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/1/2004
Due Date:	7/31/2004
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	JOYCE DAVIS
Report:	RDR
Latest TCEQ Letter:	No Leaker

TEXACO STATION (Continued) **S127527618**

Date of Latest TCEQ Letter:	9/27/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	97075
Comments:	6A REOPEN OR NEW LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/27/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CD1534 **STAR ENTERPRISES** **RCRA NonGen / NLR** **1000982677**
West **1900 GUADALUPE ST** **FINDS** **TX0000994863**
< 1/8 **AUSTIN, TX 78705** **ECHO**
0.025 mi.
133 ft. **Site 15 of 15 in cluster CD**

Actual:
553 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20200817
Handler Name:	Star Enterprises
Handler Address:	1900 GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78705-5607
EPA ID:	TX0000994863
Contact Name:	DAVID GUMBLEY
Contact Address:	PO BOX 2099
Contact City,State,Zip:	HOUSTON, TX 77252-2099
Contact Telephone:	214-650-0200
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 2099
Mailing City,State,Zip:	HOUSTON, TX 77252-2099
Owner Name:	Star Enterprises Inc
Owner Type:	Private
Operator Name:	Star Enterprises Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

STAR ENTERPRISES (Continued) **1000982677**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200828
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOTIVA ENTERPRISES LLC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4540
Owner/Operator City,State,Zip:	HOUSTON, TX 77210-4540
Owner/Operator Telephone:	713-241-0236
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Private

STAR ENTERPRISES (Continued) **1000982677**

Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252-2099
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Private
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252-2099
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Private
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252-2099
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Private
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252-2099
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Not reported
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

STAR ENTERPRISES (Continued) **1000982677**

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOTIVA ENTERPRISES LLC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4540
Owner/Operator City,State,Zip:	HOUSTON, TX 77210-4540
Owner/Operator Telephone:	713-241-0236
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STAR ENTERPRISES INC	
Legal Status:	Not reported
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2099
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	214-650-0200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20030421
Handler Name: STAR ENTERPRISE	
Federal Waste Generator Description:	Not reported
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19941229
Handler Name: STAR ENTERPRISE	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020114
Handler Name: STAR ENTERPRISES INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

STAR ENTERPRISES (Continued) **1000982677**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200817
Handler Name: STAR ENTERPRISES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200817
Handler Name: STAR ENTERPRISES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	42471
NAICS Description:	PETROLEUM BULK STATIONS AND TERMINALS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110070168199

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations,

STAR ENTERPRISES (Continued) **1000982677**

authorizations, etc) and their status.

Registry ID: 110005023517

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000982677
Registry ID:	110005023517
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005023517
Name:	STAR ENTERPRISES
Address:	1900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705

DR1535 **CASTROS CLEANERS** **EDR Hist Cleaner** **1013780060**
NE **502 6TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.025 mi.
133 ft. **Site 25 of 38 in cluster DR**

Actual:
484 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1970	CASTROS CLEANERS	CLEANERS AND DYERS
1975	CASTROS CLEANERS	CLEANERS AND DYERS
1990	CASTROS CLEANERS	CLEANERS AND DYERS

DR1536 **SANCHEZ BROS DCLO CLNRS** **EDR Hist Cleaner** **1013779424**
NE **502 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 26 of 38 in cluster DR**

Actual:
484 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	SANCHEZ BROS DCLO CLNRS	CLOTHES CLEANERS AND PRESSERS
1947	WILLIAMS & HOOVER CLNRS & HATTE	HAT CLEANERS AND BLOCKERS
1953	WILLIAMS LOUIS	CLEANERS AND DYERS
1958	WILLIAMS LOUIS	CLEANERS AND DYERS
1962	HOOVER CLN CLO	CLEANERS AND DYERS

DR1537 **HOOVER CLEANERS GR 8 145 B** **EDR Hist Cleaner** **1013778739**
NE **502 6TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 27 of 38 in cluster DR**

Actual:
484 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	HOOVER CLEANERS GR 8 145 B	CLEANERS AND DYERS
1984	CASTROS CLEANERS	CLEANERS AND DYERS

GF1538 **MOBIL OIL 00AIX** **TX ASBESTOS** **S103610704**
NE **1919 S PLEASANT VALLEY RD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX CENTRAL REGISTRY**
0.025 mi.
133 ft. **Site 2 of 5 in cluster GF**

Actual:
479 ft.

Focus Map:
15

ASBESTOS:

Name:	7-ELEVEN
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported

MOBIL OIL 00AIX (Continued) **S103610704**

ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	MOBIL OIL 00AIX
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	80513
Registration Initial Notification Date:	07/28/1992
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988038451
Primary NAICS Code:	Not reported
Status Change Date:	19920728
Land Type:	PRIVATE
Description of Facility Site Location:	1919 S Pleasant Valley Rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXONMOBIL OIL CORPORATION
Contact Name:	ROBIN A BUNN

MOBIL OIL 00AIX (Continued) **S103610704**

Contact Telephone Number:	703-8493330
Mailing Address:	3225 GALLOWS RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	FAIRFAX, VA 220370002
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	35271
Site Owner Tax ID:	135401570
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXONMOBIL OIL CORPORATION
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354015700
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXONMOBIL OIL CORPORATION
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354015700
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

MOBIL OIL 00AIX (Continued) **S103610704**

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19920728
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	ROBIN BUNN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8493330
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600745145
Customer Name:	TETCO INC
Customer Legal Name:	Tetco, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/17/1992
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

MOBIL OIL 00AIX (Continued) **S103610704**

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600745145
Customer Name:	TETCO INC
Customer Legal Name:	Tetco, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/17/1992
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600920748
Customer Name:	EXXONMOBIL OIL CORPORATION
Customer Legal Name:	ExxonMobil Oil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1987
Affiliation End Date:	8/31/1987
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600920748
Customer Name:	EXXONMOBIL OIL CORPORATION
Customer Legal Name:	ExxonMobil Oil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1987
Affiliation End Date:	8/31/1987
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD

MOBIL OIL 00AIX (Continued) **S103610704**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602928814
Customer Name:	TETCO STORES LP
Customer Legal Name:	Tetco Stores LP
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/1/1998
Affiliation End Date:	10/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602928814
Customer Name:	TETCO STORES LP
Customer Legal Name:	Tetco Stores LP
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/1/1998
Affiliation End Date:	10/31/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600920748
Customer Name:	EXXONMOBIL OIL CORPORATION
Customer Legal Name:	ExxonMobil Oil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE

MOBIL OIL 00AIX (Continued) **S103610704**

Status Date:	1/1/2001
Customer Number:	CN600920748
Customer Name:	EXXONMOBIL OIL CORPORATION
Customer Legal Name:	ExxonMobil Oil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2012
Affiliation End Date:	11/14/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2012
Affiliation End Date:	11/14/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Regulated Entity Number:	RN100561869
Name:	TETCO 54
Address:	1919 S PLEASANT VALLEY RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3108
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601556145
Customer Name:	JBM LAND II CORPORATION

MOBIL OIL 00AIX (Continued) **S103610704**

Customer Legal Name:	JBM LAND II CORPORATION
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1987
Affiliation End Date:	9/30/1998
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1919 S PLEASANT VALLEY RD AUSTIN TX

Click this hyperlink while viewing on your computer to access
32 additional TX CENTRAL REG: record(s) in the EDR Site Report.

GF1539 **TETCO STORES INC** **EDR Hist Auto** **1013763985**
NE **1919 S PLEASANT VALLEY RD** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.025 mi.
133 ft. **Site 3 of 5 in cluster GF**

Actual:
479 ft.

Focus Map:
15

EDR Hist Auto

Year:	Name:	Type:
1990	MOBIL MART SERVICE STATION	GASOLINE STATIONS
2000	TETCO STORES INC	Grocery Stores
2001	TETCO STORES INC	Grocery Stores
2002	TETCO STORES INC	Grocery Stores
2003	TETCO STORES INC	Grocery Stores
2004	TETCO STORES INC	Grocery Stores
2005	TETCO STORES INC	Grocery Stores
2006	TETCO 265	Grocery Stores
2007	TETCO STORES INC	Grocery Stores
2008	TETCO STORES INC	Grocery Stores
2009	TETCO STORES INC	Grocery Stores
2010	TETCO STORES INC	Grocery Stores
2011	TETCO STORES INC	Grocery Stores
2012	TETCO STORES INC	Grocery Stores
2013	TETCO STORES INC	Grocery Stores
2014	TETCO STORES INC	Grocery Stores

GF1540 **STAR STOP 73** **TX UST** **U001291453**
NE **1919 S PLEASANT VALLEY RD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX ASBESTOS**
0.025 mi. **TX Financial Assurance**
133 ft. **Site 4 of 5 in cluster GF**

Actual:
479 ft.

Focus Map:
15

UST:

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 787413108
AI Number:	62266
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	991250192002156
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No

STAR STOP 73 (Continued) **U001291453**

Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	SUNNY PANJWANI,SUPERVISOR
Contact Organization Name:	STAR STOP 73
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8328149789
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/03/2020
Signature Name/Title On Earliest Reg Form:	FEROZ PANJWANI,PRESIDENT
Application Received Date On Earliest Reg Form:	09/14/2020
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	323464072011354
Additional ID:	991250192002156
Ai Number:	62266
Operator CN:	CN604013359
Operator Name:	PANJWANI ENERGY LLC
Operator Effective Begin Date:	11/15/2013
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	FEROZ PANJWANI/PRES
Contact Organization Name:	PANJWANI ENERGY LLC
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON TX 77036-3360
Contact Phone Country Code:	1
Contact Phone Area Code:	713
Contact Phone Number:	7814610
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	MIKE@PANJWANIENT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604013359
Owner Last Name:	PANJWANI ENERGY LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	HOUSTON

STAR STOP 73 (Continued) **U001291453**

Contact Mailing State:	TX
Contact Mailing Zip:	77036
Contact Mailing Zip5:	3360
Contact Phone Number/Ext:	1 713 7814610/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MIKE@PANJWANIENT.COM
Contact Address Deliverable:	Not reported
Princ ID:	323464072011354
Additional ID:	991250192002156
AI Number:	62266
Owner Effective Begin Date:	11/15/2013
State Tax ID:	32044634874
Contact Role:	OWNOPRCON
Contact Name/Title:	FEROZ PANJWANI/PRES
Contact Organization Name:	PANJWANI ENERGY LLC

Self Certification:

Self Cert ID:	95659
Cert ID:	377031
AI Number:	62266
Self Certification Date:	09/27/2022
Signature Name/Title:	AMIN PANJWANI OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	359518
AI Number:	62266
Self Certification Date:	09/09/2021
Signature Name/Title:	NAZNEEN MERCHANT MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	344029
AI Number:	62266
Self Certification Date:	09/03/2020
Signature Name/Title:	FEROZ PANJWANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	326007
AI Number:	62266
Self Certification Date:	08/15/2019
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	309227
AI Number:	62266
Self Certification Date:	08/24/2018
Signature Name/Title:	SHAMSUDDIN PANJWANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	293062
AI Number:	62266
Self Certification Date:	09/08/2017
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	276162
AI Number:	62266
Self Certification Date:	09/08/2016
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	259851
AI Number:	62266
Self Certification Date:	09/23/2015
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	243708
AI Number:	62266
Self Certification Date:	09/30/2014
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	228221
AI Number:	62266
Self Certification Date:	11/25/2013
Signature Name/Title:	SHAMSUDDIN PANJWANI VP
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95659
Cert ID:	153903
AI Number:	62266
Self Certification Date:	11/06/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	153902
AI Number:	62266
Self Certification Date:	11/05/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153901
AI Number:	62266
Self Certification Date:	09/30/2012
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153900
AI Number:	62266
Self Certification Date:	10/03/2011
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	153899
AI Number:	62266
Self Certification Date:	09/30/2010
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153898
AI Number:	62266
Self Certification Date:	10/01/2009
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153897
AI Number:	62266
Self Certification Date:	09/18/2008
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	153896
AI Number:	62266
Self Certification Date:	09/27/2007
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153895
AI Number:	62266
Self Certification Date:	09/21/2006
Signature Name/Title:	RAYMOND MCNIECE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153894
AI Number:	62266
Self Certification Date:	09/28/2005
Signature Name/Title:	RAYMOND MCNIECE ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	153893
AI Number:	62266
Self Certification Date:	09/30/2004
Signature Name/Title:	RAYMOND MCNEICE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153892
AI Number:	62266
Self Certification Date:	09/23/2003
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659
Cert ID:	153891
AI Number:	62266
Self Certification Date:	08/28/2002
Signature Name/Title:	SHAWN BROOKE ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	95659

STAR STOP 73 (Continued) **U001291453**

Cert ID:	153890
AI Number:	62266
Self Certification Date:	12/15/2000
Signature Name/Title:	MICHAEL K GARROTT SR ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1987
Tank Registration Date:	01/17/1992
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	144585
Facility ID:	95659
Ai Number:	62266
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

STAR STOP 73 (Continued) **U001291453**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/14/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	163966
UST ID:	144585
AI Number:	62266
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y

STAR STOP 73 (Continued) **U001291453**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1987

Install Date:	04/01/1987
Tank Registration Date:	01/17/1992
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	144586
Facility ID:	95659
Ai Number:	62266
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

STAR STOP 73 (Continued) **U001291453**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/14/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	163967
UST ID:	144586
AI Number:	62266
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM

STAR STOP 73 (Continued) **U001291453**

Stage 1 Installation Date:	12/01/1987
Install Date:	04/01/1987
Tank Registration Date:	01/17/1992
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	144587
Facility ID:	95659
Ai Number:	62266
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

STAR STOP 73 (Continued) **U001291453**

Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/14/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	163968
UST ID:	144587
AI Number:	62266
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1987

Install Date:	04/01/1987
Tank Registration Date:	01/17/1992
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N

STAR STOP 73 (Continued) **U001291453**

Tank Doublewall:	Y
Pipe Type:	P
UST ID:	144588
Facility ID:	95659
Ai Number:	62266
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	01/14/1992

STAR STOP 73 (Continued) **U001291453**

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	163969
UST ID:	144588
AI Number:	62266
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1987

Construction Notification:

NOC ID:	15660
Facility ID:	95659
AI Number:	62266
Application Received Date:	05/14/2002
Scheduled Construction Date:	06/10/2002
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N

STAR STOP 73 (Continued) **U001291453**

UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M20514002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

NOC ID:	15659
Facility ID:	95659
AI Number:	62266
Application Received Date:	11/04/2003
Scheduled Construction Date:	11/13/2003
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M31104006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

NOC ID:	15658
Facility ID:	95659
AI Number:	62266
Application Received Date:	10/10/2001
Scheduled Construction Date:	10/29/2001
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N

STAR STOP 73 (Continued) **U001291453**

UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M01011005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

NOC ID:	15657
Facility ID:	95659
AI Number:	62266
Application Received Date:	11/03/2006
Scheduled Construction Date:	11/06/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M61103002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	52410
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16795
UST ID:	Not reported
NOC ID:	15659
AI Number:	62266
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported

STAR STOP 73 (Continued) **U001291453**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	16794
UST ID:	Not reported
NOC ID:	15658
AI Number:	62266
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001318
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	16793
UST ID:	Not reported
NOC ID:	15657
AI Number:	62266
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001443
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported

STAR STOP 73 (Continued) **U001291453**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	16796
UST ID:	Not reported
NOC ID:	15660
AI Number:	62266
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001318
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PANJWANI ENERGY LLC
Contact Mailing Address (Delivery):	6161 SAVOY DR STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77036 3360
Phone Number/Ext:	713 7814610/0
Contact Fax Number/Ext:	/
Contact Email Address:	MIKE@PANJWANIENT.COM
Contact Address Deliverable:	Y
Facility ID:	95659
Additional ID:	991250192002156
Princ ID:	323464072011354
AI Number:	62266
Facility Name:	STAR STOP 73
AR Number:	72839
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	FEROZ PANJWANI/PRESIDENT

HIST UST AUSTIN:

Name:	STARSTOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX
Id UST:	2031

STAR STOP 73 (Continued) **U001291453**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	STAR STOP
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/16/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported

STAR STOP 73 (Continued) **U001291453**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	274834
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2022
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 7224994
Policy Number:	04-TOP-000031332
Coverage Amount:	2,000,000
Coverage Expiration Date:	08/15/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	256460
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

STAR STOP 73 (Continued) **U001291453**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2021
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	0 918 5619338
Policy Number:	04-TOP-000021625
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	238834
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2020
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000012413
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	219564
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/15/2019
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-to-005001600
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2020
Ins Premium Pre-Paid For Entire Yr:	No

STAR STOP 73 (Continued) **U001291453**

Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	202615
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2017
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	186233
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2016
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	168657
AI:	62266

STAR STOP 73 (Continued) **U001291453**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2015
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	135524
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2014
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	150997
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2014
Date Financial Assurance Form Rec:	09/14/2020

STAR STOP 73 (Continued) **U001291453**

Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	117850
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2013
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	134837
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2013
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9986534
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73

STAR STOP 73 (Continued) **U001291453**

Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	8785
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80006
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2011
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	001215401
Coverage Amount:	2000000
Coverage Expiration Date:	12/01/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80005
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

STAR STOP 73 (Continued) **U001291453**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2012
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235400
Coverage Amount:	1000000
Coverage Expiration Date:	12/18/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80007
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2009
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	000026400
Coverage Amount:	1000000
Coverage Expiration Date:	12/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80008
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8058109

STAR STOP 73 (Continued) **U001291453**

Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80009
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8057698
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	95659
Finass ID:	80010
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2006
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 9220603 00
Coverage Amount:	5000000
Coverage Expiration Date:	12/22/2007
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STAR STOP 73
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2

STAR STOP 73 (Continued) **U001291453**

Facility ID:	95659
Finass ID:	80011
AI:	62266
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	09/14/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GF1541 **MOBIL OIL CORPORATION** **RCRA NonGen / NLR** **1000654001**
NE **1919 S PLEASANT VALLEY RD** **FINDS** **TXD988038451**
< 1/8 **AUSTIN, TX 78741** **ECHO**
0.025 mi.
133 ft. **Site 5 of 5 in cluster GF**

Actual:
479 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Mobil Oil Corporation
Handler Address:	S PLEASANT VALLEY RD
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXD988038451
Contact Name:	ROBIN A BUNN
Contact Address:	GALLOWS RD
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Telephone:	703-849-3330
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GALLOWS RD
Mailing City,State,Zip:	FAIRFAX, VA 22037
Owner Name:	Mobil Oil Corporation
Owner Type:	Private
Operator Name:	Mobil Oil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

MOBIL OIL CORPORATION (Continued) **1000654001**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037

MOBIL OIL CORPORATION (Continued) **1000654001**

Owner/Operator Telephone: 703-849-3330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MOBIL OIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 3225 GALLOWS RD
Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: 703-849-3330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MOBIL OIL CORP MKTG ENVIRON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3225 GALLOWS RD
Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: 703-849-3330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MOBIL OIL CORPORATION
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 3225 GALLOWS RD
Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: 703-849-3330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MOBIL OIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 3225 GALLOWS RD
Owner/Operator City,State,Zip: FAIRFAX, VA 22037
Owner/Operator Telephone: 703-849-3330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910501
Handler Name: MOBIL OIL CORP SS# AIY
Federal Waste Generator Description: Small Quantity Generator

MOBIL OIL CORPORATION (Continued) **1000654001**

State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name: MOBIL OIL CORPORATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20051129
Handler Name: MOBIL OIL CORPORATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005136245

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

MOBIL OIL CORPORATION (Continued) **1000654001**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000654001
Registry ID:	110005136245
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005136245
Name:	MOBIL OIL CORPORATION
Address:	1919 S PLEASANT VALLEY RD
City,State,Zip:	AUSTIN, TX 78741

DF1542 **DAY R L AUTO REPR** **EDR Hist Auto** **1013752796**
WNW **112 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 18 of 25 in cluster DF**

Actual:
497 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	MILLERS GARAGE	AUTOMOBILE GARAGES
1929	112 14 MILLERS GARAGE	AUTOMOBILE GARAGES
1935	DAY R L AUTO REPR	AUTOMOBILE REPAIRERS
1935	MILLERS GARAGE	AUTOMOBILE GARAGES
1940	MILLERS STORAGE	AUTOMOBILE GARAGES
1947	MILLERS STORAGE GARAGE	AUTOMOBILE GARAGES
1953	MILLERS GARAGE	AUTOMOBILE GARAGES

DF1543 **DRISKILL STEAM LAUN** **EDR Hist Cleaner** **1013786467**
WNW **113 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 19 of 25 in cluster DF**

Actual:
497 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1906	DRISKILL STEAM LAUN	LAUNDRIES
1911	DRISKILL STEAM LAUNDRY	LAUNDRIES
1916	DRISKILL HOTEL LAUN	LAUNDRIES
1916	DRISKILL HOTEL LAUN	CLEANERS AND DYERS
1916	DRISKILL HOTEL LAUN	CLOTHES CLEANERS AND PRESSERS
1929	113 19 DRISKILL HOTEL LAUNDRY	LAUNDRIES

DB1544 **HONG LEE LAUNDRY** **EDR Hist Cleaner** **1013782008**
WNW **113 8TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
133 ft. **Site 9 of 11 in cluster DB**

Actual:
502 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	HONG LEE CHINESE LAUN	LAUNDRIES
1916	HONG LEE LAUNDRY	LAUNDRIES
1922	HONG LEE LNDRY	LAUNDRIES

EH1545 **DEEP EDDY RUG CINS** **EDR Hist Cleaner** **1013780236**
SE **414 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.025 mi.
133 ft. **Site 9 of 9 in cluster EH**

Actual:
455 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1958	DEEP EDDY RUG CINS	CARPET AND RUG CLEANERS
1958	DEEP EDDY RUG CINS	RUG CLEANERS

DA1546 **COTHRONS TEXACO SERVICE** **TX LPST** **U001259380**
WNW **701 W 6TH ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX HIST UST**
0.025 mi.
133 ft. **Site 17 of 25 in cluster DA**

Actual:
472 ft.
LPST:

Focus Map:
11

Name:	COTHRONS TEXACO SERVICE
Address:	701 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0025280
LPST Id:	098124
Facility Location:	CORNER OF W 6TH AND RIO GRANDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/04/1991
Entered Date:	03/05/1991
Reported Date:	03/04/1991
Closure Date:	04/17/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	DOUG DANFORTH
Responsible Party Address:	1400 WEST AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/473-4343
Reported Date:	03/04/1991
Case Start Date:	04/17/1991

COTHRONS TEXACO SERVICE (Continued) **U001259380**

Reference Number: RN101488872
Project Manager: HWELCH

UST:

Name:	COTHRONS TEXACO SERVICE
Address:	701 W 6TH ST
City,State,Zip:	AUSTIN, TX 787012707
AI Number:	25280
Facility Type:	RETAIL
Facility Begin Date:	10/08/1986
Facility Status:	INACTIVE
Additional ID:	40514062002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	R LOPEZ,MGR
Contact Organization Name:	COTHRONS TEXACO SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124776891
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	O COTHRON,STATION OPER.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777858
Owner Last Name:	DANFORTH INVESTMENTS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	30514052002053
Additional ID:	40514062002053

COTHRONS TEXACO SERVICE (Continued) **U001259380**

AI Number:	25280
Owner Effective Begin Date:	10/08/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64977
Facility ID:	61941
Ai Number:	25280
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

COTHRONS TEXACO SERVICE (Continued) **U001259380**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	79237
UST ID:	64977
AI Number:	25280
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

COTHRONS TEXACO SERVICE (Continued) **U001259380**

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64979
Facility ID:	61941
Ai Number:	25280
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

COTHRONS TEXACO SERVICE (Continued) **U001259380**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	79239
UST ID:	64979
AI Number:	25280
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64978

COTHRONS TEXACO SERVICE (Continued) **U001259380**

Facility ID:	61941
Ai Number:	25280
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	0

COTHRONS TEXACO SERVICE (Continued) **U001259380**

UST Comprt ID:	79238
UST ID:	64978
AI Number:	25280
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DANFORTH INVESTMENTS
Contact Mailing Address (Delivery):	1400 WEST AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1528
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61941
Additional ID:	40514062002053
Princ ID:	30514052002053
AI Number:	25280
Facility Name:	COTHRONS TEXACO SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported

COTHRONS TEXACO SERVICE (Continued) **U001259380**

AR AST Number Suffix: Not reported
Contact Name/Title: /

HIST UST AUSTIN:

Name:	R. G. MUELLER
Address:	701 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0932
HID UST:	932
Inspection:	Not reported
Due:	06/01/2012

DA1547 **KORNFUEHRER TEXACO SERVICE STATION** **EDR Hist Auto** **1013775769**
WNW **701 W 6TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.025 mi.
133 ft. **Site 18 of 25 in cluster DA**

Actual:
472 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1969	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1970	KORNFUEHRER TEXACO SERVICE STAT	GASOLINE STATIONS
1970	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1971	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1972	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1973	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1974	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1975	KORNFUEHRER SERVICE STATION	Gasoline Service Stations
1988	COTHRAN SERVICE STATION	Gasoline Service Stations
1989	COTHRAN SERVICE STATION	Gasoline Service Stations
1990	COTHRAN SERVICE STATION	Gasoline Service Stations

EZ1548 **CEN TEX NISSAN** **TX UST** **U001273334**
WNW **1400 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.025 mi.
133 ft. **Site 5 of 6 in cluster EZ**

Actual:
530 ft.

Focus Map:
14

UST:

Name:	CEN TEX NISSAN
Address:	1400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787042487
AI Number:	40885
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1989
Facility Status:	INACTIVE
Additional ID:	963236982002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported

CEN TEX NISSAN (Continued) **U001273334**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PEARCE JOHNSON,
Contact Organization Name:	CEN TEX NISSAN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124408898
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1986
Signature Name/Title On Earliest Reg Form:	JILL JOHNSON DAMORE,VP
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601272909
Owner Last Name:	ESTATE OF SARA JOHNSON
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	954236972002156
Additional ID:	963236982002156
AI Number:	40885
Owner Effective Begin Date:	09/01/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108331
Facility ID:	93163
Ai Number:	40885

CEN TEX NISSAN (Continued) **U001273334**

Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/15/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	138040
UST ID:	108331

CEN TEX NISSAN (Continued) **U001273334**

AI Number:	40885
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108332
Facility ID:	93163
Ai Number:	40885
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/15/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

CEN TEX NISSAN (Continued) **U001273334**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	138041
UST ID:	108332
AI Number:	40885
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

CEN TEX NISSAN (Continued) **U001273334**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108333
Facility ID:	93163
Ai Number:	40885
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/15/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

CEN TEX NISSAN (Continued) **U001273334**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	138042
UST ID:	108333
AI Number:	40885
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

CEN TEX NISSAN (Continued) **U001273334**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ESTATE OF SARA JOHNSON
Contact Mailing Address (Delivery):	512 RIVER RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78734 5829
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93163
Additional ID:	963236982002156
Princ ID:	954236972002156
AI Number:	40885
Facility Name:	CEN TEX NISSAN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PEARCE JOHNSON/

HIST UST AUSTIN:

Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0522
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EZ1549 **CEN-TEX NISSAN INC** **TX LPST** **1000404121**
WNW **1400 S CONGRESS** **RCRA NonGen / NLR** **TXD982562829**
< 1/8 **AUSTIN, TX 78704** **FINDS**
0.025 mi. **ECHO**
133 ft. **Site 6 of 6 in cluster EZ** **TX Ind. Haz Waste**
TX CENTRAL REGISTRY

Actual:
530 ft.

Focus Map:
14

LPST:

Name:	CEN TEX NISSAN
Address:	1400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0040885
LPST Id:	108915
Facility Location:	1400 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/07/1994
Entered Date:	12/21/1994
Reported Date:	11/07/1994
Closure Date:	03/22/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	PEARCE JOHNSON
Responsible Party Address:	412 E RIVERSIDE
Responsible Party City,St,Zip:	AUSTIN, TX 78704
Responsible Party Telephone:	512/440-8898
Reported Date:	11/07/1994
Case Start Date:	03/22/1995
Reference Number:	RN100598390
Project Manager:	HWELCH

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Cen-Tex Nissan Inc
Handler Address:	S CONGRESS
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD982562829
Contact Name:	JIMMY A WEBB
Contact Address:	S IH 35
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-444-1400
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx

CEN-TEX NISSAN INC (Continued) **1000404121**

State District:	11
Mailing Address:	S IH 35
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Cen-Tex Nissan Inc
Owner Type:	Not reported
Operator Name:	Cen-Tex Nissan Inc
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007

CEN-TEX NISSAN INC (Continued) **1000404121**

Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CEN-TEX NISSAN INC	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	4914 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-444-1400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PEARCE JOHNSON	
Legal Status:	Private
Date Became Current:	Not reported

CEN-TEX NISSAN INC (Continued) **1000404121**

Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CEN-TEX NISSAN INC	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	4914 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-444-1400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19890209
Handler Name: CENTEX NISSAN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010214
Handler Name: CEN-TEX NISSAN INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44111
NAICS Description:	NEW CAR DEALERS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CEN-TEX NISSAN INC (Continued) **1000404121**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005111011

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000404121
Registry ID:	110005111011
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005111011
Name:	CEN-TEX NISSAN INC
Address:	1400 S CONGRESS
City,State,Zip:	AUSTIN, TX 78704

Ind. Haz Waste:

Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	75002
Registration Initial Notification Date:	01/27/1989
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXD982562829
Primary NAICS Code:	441110
Status Change Date:	19890127
Land Type:	Not reported
Description of Facility Site Location:	1400 S Congress, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	CEN-TEX NISSAN INC
Contact Name:	JIMMY A WEBB
Contact Telephone Number:	512-4441400
Mailing Address:	4914 S IH 35

CEN-TEX NISSAN INC (Continued) **1000404121**

Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787452441
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29360
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CEN-TEX NISSAN INC
Operator Address:	4914 S IH35
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4441400
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17418766303
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CEN-TEX NISSAN INC
Owner Mailing Address:	4914 S IH35
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4441400
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17418766303
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4914 S IH35
Contact Address 2:	Not reported

CEN-TEX NISSAN INC (Continued) **1000404121**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4441400
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4914 S IH35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4441400
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JIMMY WEBB
Contact Title:	SERVICE MANAGER
Contact Role:	PRICONT
Contact Address:	4914 S IH35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4441400
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	140072
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	55110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012267
Primary NAICS Code:	441110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CEN-TEX NISSAN INC (Continued) **1000404121**

Waste ID:	140073
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	IMMERSION CLEANER
Standard Industrial Code:	55110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012267
Primary NAICS Code:	441110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1400 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306667
Principal Name:	CEN-TEX NISSAN INC
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1400 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306667
Principal Name:	CEN-TEX NISSAN INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported

CEN-TEX NISSAN INC (Continued) **1000404121**

Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1400 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306667
Principal Name:	CEN-TEX NISSAN INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1400 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306667
Principal Name:	CEN-TEX NISSAN INC
Attention Name:	Not reported
Attention Suffix:	NWF

CENTRAL REGISTRY:

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers

CEN-TEX NISSAN INC (Continued) **1000404121**

Physical Location Description:	1400 S Congress, Austin, TX
Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX
Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601272909
Customer Name:	ESTATE OF SARA JOHNSON
Customer Legal Name:	Estate of Sara Johnson
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX
Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601272909
Customer Name:	ESTATE OF SARA JOHNSON
Customer Legal Name:	Estate of Sara Johnson
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX
Regulated Entity Number:	RN100598390

CEN-TEX NISSAN INC (Continued) **1000404121**

Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601272909
Customer Name:	ESTATE OF SARA JOHNSON
Customer Legal Name:	Estate of Sara Johnson
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported

CEN-TEX NISSAN INC (Continued) **1000404121**

City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600308175
Customer Name:	CEN-TEX NISSAN INC
Customer Legal Name:	Jim P., Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/30/1989
Affiliation End Date:	8/31/1989
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604453472
Customer Name:	JOHNSON SASA ESTATE
Customer Legal Name:	Johnson Sasa Estate
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Regulated Entity Number:	RN100598390
Name:	CENTEX NISSAN
Address:	1400 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-2487
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604453472
Customer Name:	JOHNSON SASA ESTATE
Customer Legal Name:	Johnson Sasa Estate
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	441110
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1400 S Congress, Austin, TX

Click this hyperlink while viewing on your computer to access
20 additional TX CENTRAL REG: record(s) in the EDR Site Report.

1550 East < 1/8 0.025 mi. 134 ft. | **UT AUSTIN MAIN CAMPUS**
AUSTIN, TX | **PFAS RCRA MANIFEST** | **1027318584**
N/A

Actual: 563 ft.

Focus Map: 11

PFAS RCRA MANIFEST:

EPA ID:	TXD980869184
Name:	UT AUSTIN MAIN CAMPUS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.2908
Longitude:	-97.73665
Date Received:	2020-10-12 00:00:00
Management Method Description:	INCINERATION
EJSCREEN report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.73665,%22y%22:30.2908,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
DES Facility ID:	TXD000838896
DES Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS
DES Facility City:	PORT ARTHUR
DES Facility State:	TX
DES Latitude:	29.853056
DES Longitude:	-94.095278
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:0,%22y%22:29.853056,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
Manifest ID:	19263714
Waste Line ID:	35693517
Waste Line Number:	23
COI Only:	N
DOT Hazardous:	Y
DOT ID Number Description:	UN2920
DOT Printed Information:	UN2920, WASTE CORROSIVE LIQUIDS, FLAMMABLE, n.o.s., (BROMOACETYL CHLORIDE, TRICHLORO(1H,1H,2H,2H-PERFLUOROOCTYL)SILANE), 8 (3), II
Non Hazardous Waste Description:	-
Waste Line Handling:	W:408925 A:VGCPTAVES203
Waste Residue Comments:	-
Manifest Handling:	-
State Waste Codes:	0026004H
Quantity KG:	0.45351501999999999
Date Shipped:	2020-10-02 00:00:00
Date Certified:	2020-10-15 00:00:00

EPA ID:	TXD980869184
Name:	UT AUSTIN MAIN CAMPUS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.2908
Longitude:	-97.73665
Date Received:	2022-07-27 12:00:00
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
EJSCREEN report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.73665,%22y%22:30.2908,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
DES Facility ID:	TXD000838896
DES Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS,
DES Facility City:	BEAUMONT
DES Facility State:	TX

UT AUSTIN MAIN CAMPUS (Continued) **1027318584**

DES Latitude:	29.853056
DES Longitude:	-94.095278
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:0,%22y%22:29.853056,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
Manifest ID:	27910027
Waste Line ID:	54649816
Waste Line Number:	27
COI Only:	N
DOT Hazardous:	N
DOT ID Number Description:	-
DOT Printed Information:	-
Non Hazardous Waste Description:	NON RCRA AND DOT NON REGULATED LIQUID, (LITHIUM CHLORIDE, PERFLUOROPOLYETHER)
Waste Line Handling:	W:934209 A:UTPTAVES038
Waste Residue Comments:	-
Manifest Handling:	-
State Waste Codes:	NONIND06
Quantity KG:	23.58278
Date Shipped:	2022-07-15 12:00:00
Date Certified:	2022-08-09 12:37:31
EPA ID:	TXD980869184
Name:	UT AUSTIN MAIN CAMPUS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.2908
Longitude:	-97.73665
Date Received:	2022-09-22 12:00:00
Management Method Description:	INCINERATION
EJSCREEN report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.73665,%22y%22:30.2908,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
DES Facility ID:	TXD000838896
DES Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS,
DES Facility City:	BEAUMONT
DES Facility State:	TX
DES Latitude:	29.853056
DES Longitude:	-94.095278
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:0,%22y%22:29.853056,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
Manifest ID:	28445208
Waste Line ID:	55829431
Waste Line Number:	52
COI Only:	N
DOT Hazardous:	Y
DOT ID Number Description:	UN3082
DOT Printed Information:	UN3082, ENVIRONMENTALLY HAZARDOUS SUBSTANCE, LIQUID, n.o.s., (1H,1H,2H,2H-PERFLUORODECANETHIOL), 9, III
Non Hazardous Waste Description:	-
Waste Line Handling:	W:934209 A:UTPTAVES038
Waste Residue Comments:	-
Manifest Handling:	-
State Waste Codes:	NONIND06
Quantity KG:	2.7210899999999998
Date Shipped:	2022-09-09 12:00:00

UT AUSTIN MAIN CAMPUS (Continued) **1027318584**

Date Certified: 2022-09-30 10:44:45

CV1551 **DAVIS & CO TAILORS** **EDR Hist Cleaner** **1013777483**
ESE **1008 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
134 ft. **Site 9 of 14 in cluster CV**

Actual:
515 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	DAVIS & CO TAILORS	CLOTHES PRESSERS AND CLEANERS

T1552 **NORTH LAMAR PHILLIPS 66 SERVICE STATION** **EDR Hist Auto** **1013760138**
NW **8700 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.025 mi.
134 ft. **Site 6 of 7 in cluster T**

Actual:
673 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1970	NORTH LAMAR PHILLIPS 66 SERVICE	GASOLINE STATIONS
1970	NORTH LAMAR PHILLIPS 66	Gasoline Service Stations
1971	NORTH LAMAR PHILLIPS 66	Gasoline Service Stations
1972	NORTH LAMAR PHILLIPS 66	Gasoline Service Stations
1975	FAIRFIELDS PHILLIPS	GASOLINE STATIONS
1994	GIANT FOOD MART	Grocery Stores
1995	GIANT FOOD MART	Grocery Stores
1996	GIANT FOOD MART	Grocery Stores
1997	GIANT FOOD MART	Grocery Stores
1998	GIANT FOOD MART	Grocery Stores
1999	GIANT FOOD MART	Grocery Stores
2000	GIANT FOOD MART	Grocery Stores
2001	GIANT FOOD MART	Grocery Stores
2002	GIANT FOOD MART	Grocery Stores
2003	GIANT FOOD MART	Grocery Stores
2004	GIANT FOOD MART	Grocery Stores
2005	GIANT FOOD MART	Gasoline Service Stations, NEC
2006	GIANT FOOD MART	Gasoline Service Stations, NEC
2007	GIANT FOOD MART	Gasoline Service Stations, NEC
2008	GIANT FOOD MART	Gasoline Service Stations, NEC
2010	GIANT FOOD MART	Gasoline Service Stations, NEC

T1553 **GIANT FOOD MART** **TX LPST** **U001249384**
NW **8700 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX HIST UST**
0.025 mi. **TX Financial Assurance**
134 ft. **Site 7 of 7 in cluster T** **TX RDR**

Actual:
673 ft.

LPST:

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0013885

Focus Map:
6

GIANT FOOD MART (Continued) **U001249384**

LPST Id:	091369
Facility Location:	8700 N LAMAR BLVD @ PEYTON GIN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/30/1987
Entered Date:	07/02/1987
Reported Date:	06/30/1987
Closure Date:	08/21/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING**
Coordinators Primary:	1/4
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	STACY OLIVER
Responsible Party Address:	201 W STASSNEY LN STE 512
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/448-0585
Reported Date:	06/30/1987
Case Start Date:	08/21/1997
Reference Number:	RN102454790
Project Manager:	OAYILARA

UST:

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535424
AI Number:	13885
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	403738012002155
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	PATRICK OLIVER,
Contact Organization Name:	GIANT FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/11/2022
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,VICE PRESIDENT
Application Received Date On Earliest Reg Form:	07/22/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported

GIANT FOOD MART (Continued) **U001249384**

Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	403738012002155
Ai Number:	13885
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601265929
Owner Last Name:	8700 N LAMAR LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	226664472002155
Additional ID:	403738012002155
AI Number:	13885
Owner Effective Begin Date:	09/01/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	93401
Cert ID:	374114

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/11/2022
Signature Name/Title:	PATRICK OLIVER VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	357377
AI Number:	13885
Self Certification Date:	07/12/2021
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	340329
AI Number:	13885
Self Certification Date:	07/10/2020
Signature Name/Title:	PATRICK OLIVER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	324184

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/17/2019
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	306284
AI Number:	13885
Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	290654
AI Number:	13885
Self Certification Date:	08/25/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	272812

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/28/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	255695
AI Number:	13885
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	238866
AI Number:	13885
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	223237

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93401
Cert ID:	148888
AI Number:	13885
Self Certification Date:	07/11/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148887
AI Number:	13885
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148886

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/20/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148885
AI Number:	13885
Self Certification Date:	07/06/2009
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148884
AI Number:	13885
Self Certification Date:	07/02/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148883

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148882
AI Number:	13885
Self Certification Date:	07/05/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148881
AI Number:	13885
Self Certification Date:	07/11/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148880

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	07/06/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148879
AI Number:	13885
Self Certification Date:	07/02/2003
Signature Name/Title:	GUY NEWELL OLIVER LEGAL AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148878
AI Number:	13885
Self Certification Date:	08/16/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93401
Cert ID:	148877

GIANT FOOD MART (Continued) **U001249384**

AI Number:	13885
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	35850
Facility ID:	93401
Ai Number:	13885
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1974
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y

GIANT FOOD MART (Continued) **U001249384**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	140762
UST ID:	35850
AI Number:	13885
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

GIANT FOOD MART (Continued) **U001249384**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	172941
Facility ID:	93401
Ai Number:	13885
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

GIANT FOOD MART (Continued) **U001249384**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	9999
UST Comprt ID:	140765
UST ID:	172941
AI Number:	13885
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

GIANT FOOD MART (Continued) **U001249384**

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	172940
Facility ID:	93401
Ai Number:	13885
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

GIANT FOOD MART (Continued) **U001249384**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	140764
UST ID:	172940
AI Number:	13885
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	172939

GIANT FOOD MART (Continued) **U001249384**

Facility ID:	93401
Ai Number:	13885
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000

GIANT FOOD MART (Continued) **U001249384**

UST Comprt ID:	140763
UST ID:	172939
AI Number:	13885
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	14999
Facility ID:	93401
AI Number:	13885
Application Received Date:	10/25/2006
Scheduled Construction Date:	11/06/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N

GIANT FOOD MART (Continued) **U001249384**

Historical Tracking Number:	M61025006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	38158
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16084
UST ID:	Not reported
NOC ID:	14999
AI Number:	13885
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	8700 N LAMAR LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	93401
Additional ID:	403738012002155
Princ ID:	226664472002155
AI Number:	13885
Facility Name:	GIANT FOOD MART
AR Number:	38158
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U

GIANT FOOD MART (Continued) **U001249384**

Contact Name/Title: PATRICK OLIVER/

HIST UST AUSTIN:

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	832
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	271961
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	254269
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

GIANT FOOD MART (Continued) **U001249384**

Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	235169
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	217862
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

GIANT FOOD MART (Continued) **U001249384**

Region:	2
Facility ID:	93401
Finass ID:	213188
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	199551
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	183384
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

GIANT FOOD MART (Continued) **U001249384**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	165137
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	146485
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-to-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015

GIANT FOOD MART (Continued) **U001249384**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	130231
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	112287
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	112236

GIANT FOOD MART (Continued) **U001249384**

AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	11264
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76324
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010

GIANT FOOD MART (Continued) **U001249384**

Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76325
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76326
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

GIANT FOOD MART (Continued) **U001249384**

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76327
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76328
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	93401
Finass ID:	76329
AI:	13885
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

GIANT FOOD MART (Continued) **U001249384**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	28106
Facility ID:	13885
RN:	Not reported
CN:	Not reported
Name:	GIANT FOOD MART
Address:	8700 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/22/2020
Due Date:	3/22/2020
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	3/18/2020
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DA1554 **MASON IRA SERV STA** **EDR Hist Auto** **1013757625**
WNW **713 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.025 mi.
134 ft. **Site 19 of 25 in cluster DA**

Actual:
472 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	JOHNSON & BISHOP	GASOLINE AND OIL SERVICE STATIONS
1947	MASON IRA SERV STA	GASOLINE AND OIL SERVICE STATIONS

JP1555 **LITTLEFIELD PARKING GARAGE** **TX VCP** **S103169130**
SSW **508 BRAZOS ST** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.025 mi.
134 ft. **Site 1 of 27 in cluster JP**

Actual:
488 ft.

Focus Map:
11

VCP TCEQ:

Name:	LITTLEFIELD PARKING GARAGE
Address:	508 BRAZOS ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	673
VCP Record Date:	12/23/1997
Facility Type:	DRY CLEANER
PCA Number:	31583
Project Manager:	MLEBRON
Phase:	COMPLETED
Acres at Site:	Not reported
REM Program:	VCP
RN Number:	RN102617198
Former Facility Type:	Not reported
Site Address Description:	508 BRAZOS STREET
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	12/23/1997
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	06/28/1999
Standards:	1
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	NOT REQUIRED
Air Target COC Class:	Not reported
Date Cashier Check Received:	12/23/1997
GW Target COC Class:	TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1998-01-30 00:00:00
Soil Target COC Class:	TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	673
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	315830
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.27

LITTLEFIELD PARKING GARAGE (Continued) **S103169130**

Longitude: -97.74

Contact:
REM Program: VCP
Program ID: 673
RN Number: RN102617198
CN Number: CN601324932
CN Name: KFP LITTLEFIELD INC LP
Role Code: BILLCONT
Contact Name: KHIMJI, MAHMOOD
Contact Title: Not reported
Organization Name: KFP LITTLEFIELD INC LP
Mailing Address: 545 E JOHN CARPENTER FWY STE 1400
Mailing City: IRVING
Mailing State: TX
Mailing Zip: 75062
Contact Telephone: (972) 444-9700
Contact Telephone Ext: 0

GCC:
Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: INACTIVE GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2018
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2012
Agency: TCEQ
Section: VC

LITTLEFIELD PARKING GARAGE (Continued) **S103169130**

Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2015
Agency: TCEQ
Section: VC/VC
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009

LITTLEFIELD PARKING GARAGE (Continued) **S103169130**

Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2011
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported

LITTLEFIELD PARKING GARAGE (Continued) **S103169130**

Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2013
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported

Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2008
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported

Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2007
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -

LITTLEFIELD PARKING GARAGE (Continued) **S103169130**

Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS ST
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2016
Agency: TCEQ
Section: Not reported
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD PARKING GARAGE
Address: 508 BRAZOS STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 673
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2014
Agency: TCEQ
Section: VC/VCP
Year Deleted: 2000
Location: Not reported
Data Quality 2: Not reported

JP1556 SSW < 1/8 0.025 mi. 134 ft. | **DELZELL & DEMENT AUTO**
508 BRAZOS ST
AUSTIN, TX | **EDR Hist Auto** | **1013769114**
N/A

Site 2 of 27 in cluster JP

Actual: 488 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	DELZELL & DEMENT AUTO	AUTOMOBILE REPAIRERS

BW1557 West < 1/8 0.026 mi. 135 ft. | **DARES HUMBLE SERV**
700 24TH W
AUSTIN, TX | **EDR Hist Auto** | **1013775236**
N/A

Site 9 of 12 in cluster BW

Actual: 597 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	DARES HUMBLE SERV	GASOLINE STATIONS

JQ1558 ESE < 1/8 0.026 mi. 135 ft. | **GRAYBURG OIL CO STA NO**
1601 CONGRESS AVE E
AUSTIN, TX | **EDR Hist Auto** | **1013766175**
N/A

Site 1 of 2 in cluster JQ

Actual: 548 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	GRAYBURG OIL CO STA NO	GASOLINE AND OIL SERVICE STATIONS

DY1559 NNE < 1/8 0.026 mi. 135 ft. | **AUSTIN AMERICAN STATESMAN**
305 CONGRESS AVE
AUSTIN, TX 78701 | **TX Ind. Haz Waste** | **S103599487**
N/A

Site 9 of 11 in cluster DY

Actual: 479 ft. Ind. Haz Waste:

Focus Map: 11

Name:	AUSTIN AMERICAN STATESMAN
Address:	305 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	30724
Registration Initial Notification Date:	12/06/1976
Registration Last Amendment Date:	03/26/2013
EPA Identification:	TXD982291569
Primary NAICS Code:	511110
Status Change Date:	19761206
Land Type:	PRIVATE
Description of Facility Site Location:	305 Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	COX TEXAS NEWSPAPERS LP
Contact Name:	RUDY ESTRADA
Contact Telephone Number:	512-4453705
Mailing Address:	PO BOX 670
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787670670
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	8287
Site Owner Tax ID:	582275222
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20130326
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	COX TEXAS NEWSPAPERS LP
Operator Address:	PO BOX 670
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	1-512-4453705
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	15822752224
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COX TEXAS NEWSPAPERS LP
Owner Mailing Address:	PO BOX 670
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	1-512-4453705
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	15822752224
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970626
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Container storage area, 55-gallon drums. Located in the Southeast corner of the
Unit Description 2:	Not reported
Unit Description 3:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 670
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4453705
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 670
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4453705
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RUDY ESTRADA
Contact Title:	SAFETY MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 670
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4453705
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	160620
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solvent. Generated from cleaning parts and press equipment. Date of init
Standard Industrial Code:	27110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	99611
Texas Waste Code:	Not reported
Texas Waste Code 2:	00042961
Waste Code Status:	INACTIVE
Waste Form:	296
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Color Replinisher/Newspaper Production
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TSAMX-39647
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	99612
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste Paint/Out-dated Product
Standard Industrial Code:	27110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Ind. Haz Waste:

Waste ID:	77900
Texas Waste Code:	Not reported
Texas Waste Code 2:	0100110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Aqueous alkaline detergent/unused product/10-1-93.
Standard Industrial Code:	27110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	77901
Texas Waste Code:	Not reported
Texas Waste Code 2:	01011091
Waste Code Status:	INACTIVE
Waste Form:	109
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Sadium molybdate mixture/unused product/10-1-93.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77902
Texas Waste Code:	Not reported
Texas Waste Code 2:	01021011
Waste Code Status:	INACTIVE

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Butyl water/unused product/10-1-93.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77903
Texas Waste Code:	Not reported
Texas Waste Code 2:	01030031
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nonhazardous lab pack/Discarded chemicals/10-1-93.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	77904
Texas Waste Code:	Not reported
Texas Waste Code 2:	0104003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Hazardous lab pack/Discarded chemicals/10-1-93.
Standard Industrial Code:	27110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	231824
Texas Waste Code:	Not reported
Texas Waste Code 2:	03093101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent oil filters
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	OIL FILTERS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	161035
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvents from parts degreasing/ cleaning. Date of initial generation prio
Standard Industrial Code:	27110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	225677
Texas Waste Code:	Not reported
Texas Waste Code 2:	05052091
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non hazardous waste liquid - Ink
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	INK - NON HAZARDOUS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	172926
Texas Waste Code:	Not reported
Texas Waste Code 2:	0507206H
Waste Code Status:	ACTIVE
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oil generated from a chiller unit with chloronated solvents. First generated 6-
Standard Industrial Code:	27110
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W206
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Waste ID:	177412
Texas Waste Code:	Not reported
Texas Waste Code 2:	0509310H
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sorbants with solvents, oil, water mix; absorbing fluids.Gen: 07/01/99
Standard Industrial Code:	27110
Primary Source:	G33
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511110
EPA Waste Form Code:	W310
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	225678
Texas Waste Code:	Not reported
Texas Waste Code 2:	05103101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-DOT regulated Material, Sorbents and PPE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ADSORBENTS AND PPE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	212504
Texas Waste Code:	Not reported
Texas Waste Code 2:	05112011
Waste Code Status:	ACTIVE
Waste Form:	201
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Generators Waste Description:	Solvent waste (synthetic hydrocarbons). Press and parts cleaner. 8/10/2005
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	212505
Texas Waste Code:	Not reported
Texas Waste Code 2:	05122061
Waste Code Status:	ACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil. Printing press oil. 8/10/2005
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	215072
Texas Waste Code:	Not reported
Texas Waste Code 2:	05131141
Waste Code Status:	ACTIVE
Waste Form:	114
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Fountain solution-spent plate cleaner. 3/1/2006
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	231338
Texas Waste Code:	Not reported
Texas Waste Code 2:	08011141
Waste Code Status:	ACTIVE
Waste Form:	114
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste aqueous solution from chillerONE TIME SHIPMENTDate of Generation: 7/18/ 0
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	231825
Texas Waste Code:	Not reported
Texas Waste Code 2:	0901319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Absorbet mats with sulfuric acid from battery spill
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ABSORBENT ACID SPILL
Primary NAICS Code:	511110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Waste ID:	231826
Texas Waste Code:	Not reported
Texas Waste Code 2:	09023191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Absorbent mats with developer solution
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ABSORBENT DEVELOPER
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	233044
Texas Waste Code:	Not reported
Texas Waste Code 2:	09043101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent ink filters from recycling process.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT INK FILTERS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	236536
Texas Waste Code:	Not reported
Texas Waste Code 2:	09052051
Waste Code Status:	ACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Water-Oil mixture spill clean-up ONE TIME SHIPMENT Date of Generation: 08/02/09

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WATER-OIL MIXTURE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	266153
Texas Waste Code:	Not reported
Texas Waste Code 2:	C9GM001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	280717
Texas Waste Code:	Not reported
Texas Waste Code 2:	CW331011
Waste Code Status:	Not reported
Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 286143
Texas Waste Code: Not reported
Texas Waste Code 2: DH4W1011
Waste Code Status: Not reported
Waste Form: 101
Waste Classification: 1
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Not reported
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 311709
Texas Waste Code: Not reported
Texas Waste Code 2: DQ2L003H
Waste Code Status: Not reported
Waste Form: 003
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Not reported
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 311710
Texas Waste Code: Not reported
Texas Waste Code 2: DQ2M0031
Waste Code Status: Not reported
Waste Form: 003
Waste Classification: 1

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	309336
Texas Waste Code:	Not reported
Texas Waste Code 2:	DW7P319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	306103
Texas Waste Code:	Not reported
Texas Waste Code 2:	F2H4003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	306104
Texas Waste Code:	Not reported
Texas Waste Code 2:	F2H5003H
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	306105
Texas Waste Code:	Not reported
Texas Waste Code 2:	F2H60031
Waste Code Status:	Not reported
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN AMERICAN STATESMAN (Continued) **S103599487**

Ind. Haz Waste:

Contact Name:	LENELL DUGGAN
Contact Title:	Not reported
Contact Telephone:	1-512-4453712 x0
Mailing Address:	305 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000301978
Principal Name:	COX TEXAS NEWSPAPERS LP
Attention Name:	DUGGAN ,LENELL
Attention Suffix:	NWG

Contact Name:	LENELL DUGGAN
Contact Title:	Not reported
Contact Telephone:	1-512-4453712 x0
Mailing Address:	305 S CONGRESS AVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000301978
Principal Name:	COX TEXAS NEWSPAPERS LP
Attention Name:	DUGGAN ,LENELL
Attention Suffix:	HWG

DQ1560 **AUSTIN MOTOR SALES CO** **EDR Hist Auto** **1013774393**
SSW **503 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
135 ft. **Site 8 of 11 in cluster DQ**

Actual:
486 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1916	AUSTIN MOTOR SALES CO	AUTOMOBILE GARAGES

EY1561 **B. E. HOWELL** **TX HIST UST** **S111678569**
WNW **1316 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
135 ft. **Site 4 of 4 in cluster EY**

Actual:
518 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	B. E. HOWELL
Address:	1316 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0327
HID UST:	327
Inspection:	Not reported
Due:	06/01/2012

BW1562 **HICKMAN HUMBLE SERVICE GAS** **EDR Hist Auto** **1013763969**
East **700 W 24TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
135 ft. **Site 10 of 12 in cluster BW**

Actual:
597 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	HICKMAN HUMBLE SERVICE GAS	GASOLINE STATIONS
1969	HICKMAN WARNER	Gasoline Service Stations
1970	MITCHELLS ENCO SERVICE STATION	GASOLINE STATIONS
1970	HICKMAN WARNER	Gasoline Service Stations
1975	MITCHELLS EXXON SERVICE STATION	GASOLINE STATIONS
1980	MITCHELLS EXXON SERVICE STATION	GASOLINE STATIONS
2001	COASTAL MART INC	Gasoline Service Stations, NEC
2002	COASTAL MART INC	Gasoline Service Stations, NEC

BB1563 **SIGMOR SHAMROCK SERVICE STATION GAS STA** **EDR Hist Auto** **1013761531**
WNW **3706 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.026 mi.
135 ft. **Site 12 of 13 in cluster BB**

Actual:
598 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1940	SMITH JAMES RESTR	AUTOMOBILE GARAGES
1975	FILL EM FAST GAS STA	GASOLINE STATIONS
1980	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1990	DIAMOND SHAMROCK SERV STATION N	GASOLINE STATIONS
1991	STATION 0963	Gasoline Service Stations
1992	STATION 0963	Gasoline Service Stations
1993	STATION 0963	Gasoline Service Stations
1994	DIAMOND SHAMROCK INC	Convenience Stores
1995	DIAMOND SHAMROCK INC	Convenience Stores
1996	DIAMOND SHAMROCK INC	Convenience Stores
1997	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
1998	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
1999	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
2000	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
2001	ULTRAMAR DIAMOND SHAMROCK CORP	Convenience Stores
2002	VALERO ENERGY CORPORATION	Convenience Stores
2003	DIAMOND SHAMROCK REF & MKTG CO	Convenience Stores

BB1564 **DIAMOND SHAMROCK 963** **TX LPST** **U003566342**
WNW **3706 GUADALUPE ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.026 mi. **TX Financial Assurance**
135 ft. **Site 13 of 13 in cluster BB** **TX RDR**

Actual:
598 ft.
LPST:

Focus Map:
8

Name:	DIAMOND SHAMROCK 963
Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0045250
LPST Id:	115608

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Facility Location:	3706 GUADLUPE ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	03/28/2002
Entered Date:	01/02/2003
Reported Date:	03/28/2002
Closure Date:	04/30/2003
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SNW
Responsible Party Name:	Not reported
Responsible Party Contact:	TIM GEORGE
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/592-4658
Reported Date:	03/28/2002
Case Start Date:	04/30/2003
Reference Number:	RN102370129
Project Manager:	SNW

Name:	DIAMOND SHAMROCK CORNER STORE 9
Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0045250
LPST Id:	091646
Facility Location:	3706 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/22/1988
Entered Date:	01/25/1988
Reported Date:	01/25/1988
Closure Date:	08/31/1993
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	IKE IKEMBA
Responsible Party Name:	Not reported
Responsible Party Contact:	C SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/641-8869
Reported Date:	01/25/1988
Case Start Date:	08/31/1993
Reference Number:	RN102370129
Project Manager:	UIKEMBA

UST:

Name:	DIAMOND SHAMROCK 963

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787051485
AI Number:	45250
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	504752212002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	CHRIS TRINKLE,
Contact Organization Name:	DIAMOND SHAMROCK 963
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2105924666
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1987
Signature Name/Title On Earliest Reg Form:	JAMES MANNING,DIV MGR
Application Received Date On Earliest Reg Form:	10/08/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	765580132003199
Additional ID:	504752212002149
Ai Number:	45250
Operator CN:	CN602277386
Operator Name:	CST SERVICES LLC
Operator Effective Begin Date:	09/01/1987
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	KENT HAMEL/COORD
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78269-6000
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	3454670
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	SAN ANTONIO
Contact Mailing State:	TX
Contact Mailing Zip:	78269
Contact Mailing Zip5:	6000
Contact Phone Number/Ext:	1 210 3454670/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	504752212002149
AI Number:	45250
Owner Effective Begin Date:	09/01/1987
State Tax ID:	17425053794
Contact Role:	OWNCON
Contact Name/Title:	KENT HAMEL/COORDINATOR
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY

Self Certification:

Self Cert ID:	74625
Cert ID:	106047
AI Number:	45250
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118526
Facility ID:	74625

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Ai Number:	45250
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/28/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9994
UST Comprt ID:	104485

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST ID:	118526
AI Number:	45250
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	60995
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61004
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Cert ID:	23104
UST Comprt ID:	61005
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	60994
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901797
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650673
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699916
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61000
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	60997
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST Comprt ID:	745481
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836774
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61001
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61002
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61003
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	60996
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	60999
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	60998

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118527
Facility ID:	74625
Ai Number:	45250
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/28/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

DIAMOND SHAMROCK 963 (Continued) **U003566342**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	9994
UST Comprt ID:	104486
UST ID:	118527
AI Number:	45250
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Cert ID:	23112
UST Comprt ID:	60995
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61004
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23104
UST Comprt ID:	61005
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	60994
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901797
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650673
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699916
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST Comprt ID:	61000
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	60997
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745481
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836774
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61001
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61002
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61003
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	60996

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	60999
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	60998
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118528
Facility ID:	74625
Ai Number:	45250
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/28/2002
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

DIAMOND SHAMROCK 963 (Continued) **U003566342**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	9994
UST Comprt ID:	104487
UST ID:	118528
AI Number:	45250
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

DIAMOND SHAMROCK 963 (Continued) **U003566342**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	60995
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61004
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23104
UST Comprt ID:	61005
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	60994
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901797
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650673

DIAMOND SHAMROCK 963 (Continued) **U003566342**

UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699916
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61000
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	60997
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745481
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836774
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61001
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61002
UST ID:	20552

DIAMOND SHAMROCK 963 (Continued) **U003566342**

AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61003
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	60996
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	60999
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	60998
UST ID:	20552
AI Number:	45250
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	11183
Facility ID:	74625
AI Number:	45250
Application Received Date:	01/28/2002
Scheduled Construction Date:	03/04/2002
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M20128003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	12016
UST ID:	Not reported
NOC ID:	11183
AI Number:	45250
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74625
Additional ID:	504752212002149
Princ ID:	765580132003199
AI Number:	45250
Facility Name:	DIAMOND SHAMROCK 963
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

DIAMOND SHAMROCK 963 (Continued) **U003566342**

HIST UST AUSTIN:

Name:	DIAMOND SHAMROCK #0963
Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	397
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	DIAMOND SHAMROCK 963
Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74625
Finass ID:	58271
AI:	45250
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	6444
Facility ID:	45250
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 963
Address:	3706 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/14/2002
Due Date:	7/13/2002
Tank Owner:	DIAMOND SHAMROCK REF & MK
Contact Person:	MACK BRICE
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	1/2/2003
Project Manager:	Tim Rupert
Team:	#N/A
New LPST Number:	115608
Pre-Existing LPST Number:	91646
Comments:	6A 115608 TSR
Review Coordinator:	TSR

DIAMOND SHAMROCK 963 (Continued) **U003566342**

Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DG1565 **LINZ NICK TAILOR** **EDR Hist Cleaner** **1013787298**
WSW **611 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
135 ft. **Site 10 of 16 in cluster DG**

Actual:
495 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1922	LINZ NICK TAILOR	CLOTHES CLEANERS AND PRESSERS
1922	LINZ NICK TAILOR	DYERS AND CLEANERS
1922	LINZ NICK TAILOR	CLEANERS, PRESSERS AND DYERS
1935	LINZ NICK TAILORS	CLOTHES PRESSERS AND CLEANERS
1940	LINZ NICK DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

JR1566 **EXPRESS FOOD MART** **TX LPST** **U003421927**
WNW **10500 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX HIST UST**
0.026 mi. **TX ED AQUIF**
135 ft. **Site 1 of 6 in cluster JR** **TX Financial Assurance**
TX COMP HIST

Actual:
729 ft.

Focus Map:
3

LPST:

Name:	SHOPPERS MART 24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0034932
LPST Id:	104147
Facility Location:	10500 NORTH LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/10/1992
Entered Date:	08/24/1992
Reported Date:	08/10/1992
Closure Date:	09/29/1995
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	FORD SMITH
Responsible Party Address:	PO BOX 6165
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	512/385-2020
Reported Date:	08/10/1992

EXPRESS FOOD MART (Continued) **U003421927**

Case Start Date:	09/29/1995
Reference Number:	RN102759008
Project Manager:	HWELCH

UST:

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533464
AI Number:	34932
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	991316872002255
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	PAUL PEMBERTON,PRES
Contact Organization Name:	EXPRESS FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123852020
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/06/2022
Signature Name/Title On Earliest Reg Form:	PAUL PEMBERTON,DIRECTOR
Application Received Date On Earliest Reg Form:	09/09/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	365520692002075
Additional ID:	991316872002255
Ai Number:	34932
Operator CN:	CN600918452
Operator Name:	TEXAS ENTERPRISES INC
Operator Effective Begin Date:	05/14/2012
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	BROCK ISBELL/SITE REP
Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	2702 INDUSTRIAL BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ABILENE TX 79605-7213
Contact Phone Country Code:	1
Contact Phone Area Code:	325
Contact Phone Number:	6950150
Contact Phone Extension:	0

EXPRESS FOOD MART (Continued) **U003421927**

Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600918452
Owner Last Name:	TEXAS ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6156
Contact Phone Number/Ext:	1 512 3852020/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	365520692002075
Additional ID:	991316872002255
AI Number:	34932
Owner Effective Begin Date:	05/14/2012
State Tax ID:	17418588749
Contact Role:	OWNOPRCON
Contact Name/Title:	PAUL PEMBERTON/
Contact Organization Name:	TEXAS ENTERPRISES INC

Self Certification:

Self Cert ID:	77360
Cert ID:	376642
AI Number:	34932
Self Certification Date:	09/06/2022
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	358225
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	08/02/2021
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	343141
AI Number:	34932
Self Certification Date:	08/28/2020
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	324441
AI Number:	34932
Self Certification Date:	07/30/2019
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	308605
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	08/21/2018
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMPLIANCE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	293413
AI Number:	34932
Self Certification Date:	08/23/2017
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	274762
AI Number:	34932
Self Certification Date:	08/08/2016
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	259995
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	08/27/2015
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	242152
AI Number:	34932
Self Certification Date:	07/24/2014
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	224733
AI Number:	34932
Self Certification Date:	08/15/2013
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77360
Cert ID:	115427
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	06/29/2012
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115426
AI Number:	34932
Self Certification Date:	05/31/2012
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115425
AI Number:	34932
Self Certification Date:	06/08/2011
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115424
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	07/09/2010
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115423
AI Number:	34932
Self Certification Date:	06/18/2009
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115422
AI Number:	34932
Self Certification Date:	05/16/2008
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115421
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	06/04/2007
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115420
AI Number:	34932
Self Certification Date:	07/01/2006
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115419
AI Number:	34932
Self Certification Date:	06/30/2005
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115418
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	06/24/2004
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115417
AI Number:	34932
Self Certification Date:	07/01/2003
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115416
AI Number:	34932
Self Certification Date:	06/06/2002
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77360
Cert ID:	115415
AI Number:	34932

EXPRESS FOOD MART (Continued) **U003421927**

Self Certification Date:	12/19/2000
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92353
Facility ID:	77360
Ai Number:	34932
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

EXPRESS FOOD MART (Continued) **U003421927**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	120144
UST ID:	92353
AI Number:	34932
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

EXPRESS FOOD MART (Continued) **U003421927**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92354
Facility ID:	77360
Ai Number:	34932
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

EXPRESS FOOD MART (Continued) **U003421927**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	120145
UST ID:	92354
AI Number:	34932
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

EXPRESS FOOD MART (Continued) **U003421927**

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92355
Facility ID:	77360
Ai Number:	34932
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

EXPRESS FOOD MART (Continued) **U003421927**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	120146
UST ID:	92355
AI Number:	34932
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92356

EXPRESS FOOD MART (Continued) **U003421927**

Facility ID:	77360
Ai Number:	34932
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000

EXPRESS FOOD MART (Continued) **U003421927**

UST Comprt ID:	120147
UST ID:	92356
AI Number:	34932
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	38404
Facility ID:	77360
AI Number:	34932
Application Received Date:	06/16/2021
Scheduled Construction Date:	06/17/2021
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N

EXPRESS FOOD MART (Continued) **U003421927**

Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	06/16/2021
Signature Date On Form:	06/16/2021
Signature Name On Form:	AUDREY PRATHER
Signature Company On Form:	Not reported
Signature Title On Form:	CONS ADMIN
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS ENTERPRISES INC
Owner CN At Time Of Construction:	CN600918452
Owner AR At Time Of Construction:	18379
General Desc Of Prop Construct:	REPLACING 4 SPILL BUCKETS

NOC ID:	27825
Facility ID:	77360
AI Number:	34932
Application Received Date:	06/26/2015
Scheduled Construction Date:	06/24/2015
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	06/16/2021
Signature Date On Form:	06/16/2021
Signature Name On Form:	AUDREY PRATHER
Signature Company On Form:	Not reported
Signature Title On Form:	CONS ADMIN
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS ENTERPRISES INC
Owner CN At Time Of Construction:	CN600918452
Owner AR At Time Of Construction:	18379
General Desc Of Prop Construct:	REMOVE TANK TOP CONCRETE, CHECK TANK FITTINGS.

NOC ID:	10917
Facility ID:	77360
AI Number:	34932
Application Received Date:	11/30/2005
Scheduled Construction Date:	12/10/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N

EXPRESS FOOD MART (Continued) **U003421927**

AST Stage I:	N
Historical Tracking Number:	M51130002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	06/16/2021
Signature Date On Form:	06/16/2021
Signature Name On Form:	AUDREY PRATHER
Signature Company On Form:	Not reported
Signature Title On Form:	CONS ADMIN
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22907
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	91465
UST ID:	Not reported
NOC ID:	38404
AI Number:	34932
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	JF PETROLEUM GROUP
Representative Name:	LARRY HOLYBEE
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11752
UST ID:	Not reported
NOC ID:	10917
AI Number:	34932
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported

EXPRESS FOOD MART (Continued) **U003421927**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	65308
UST ID:	Not reported
NOC ID:	27825
AI Number:	34932
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 2346
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MCALLEN
Mailing State:	TX
Mailing Zip:	78502
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	956
Phone Number:	6869582
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	65307
UST ID:	Not reported
NOC ID:	27825
AI Number:	34932
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	PEFFER BRENT ALLYN
Representative Name:	Not reported
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS ENTERPRISES INC

EXPRESS FOOD MART (Continued) **U003421927**

Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77360
Additional ID:	991316872002255
Princ ID:	365520692002075
AI Number:	34932
Facility Name:	EXPRESS FOOD MART
AR Number:	18379
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PAUL PEMBERTON/

HIST UST AUSTIN:

Name:	FOOD MART #24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	304
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ED AQUIF:

Name:	SHOPPERS MART 24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	11-92032601
Primary SIC Code:	5411
Primary NAICS Code:	447110
Regulated entity #:	RN102759008
Type Of Project:	UNDERGROUND STORAGE TANK FACILITY PLAN
Receive Date:	03/26/1992
General Location:	Not reported
Mailing Address:	PO BOX 306
Mailing Address2:	Not reported
Mailing City,St,Zip:	MANOR, TX 78653 0306
Lat/Long:	0.0000 / 0.0000
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Applicant Name:	Not reported
Applicant Address:	PO BOX 306
Applicant City,St,Zip:	MANOR, TX 78653 0306
Application Phone:	Not reported
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

EXPRESS FOOD MART (Continued) **U003421927**

TX Financial Assurance 2:

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	274442
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2022
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000028792
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	254980
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2021
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000019174
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	237531
AI:	34932
Mechanism Type Other:	Not reported

EXPRESS FOOD MART (Continued) **U003421927**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2020
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000010223
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	218117
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2019
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-005000860
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	202046
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2018
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO

EXPRESS FOOD MART (Continued) **U003421927**

Issuer Phone:	1 800 366
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	186516
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2017
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	800 336 1336
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	167105
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2016
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD

EXPRESS FOOD MART (Continued) **U003421927**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	151561
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2015
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	133272
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2014
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	114324
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

EXPRESS FOOD MART (Continued) **U003421927**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2013
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	10321
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2012
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 0 0
Policy Number:	9989929
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/14/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	61374
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2011
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000

EXPRESS FOOD MART (Continued) **U003421927**

Coverage Expiration Date:	03/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	61375
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2010
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	61376
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2009
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360

EXPRESS FOOD MART (Continued) **U003421927**

Finass ID:	61377
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2008
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	EXPRESS FOOD MART
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	77360
Finass ID:	61378
AI:	34932
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/1994
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

COMP HIST:

RN Number:	RN102759008
Name:	SHOPPERS MART 24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	REGION 11 - AUSTIN
CN Number:	CN601388382
CN Name:	SMITH, FORD JR
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED

EXPRESS FOOD MART (Continued) **U003421927**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	5541
Related Number:	11-92032601,34932,34932

RN Number:	RN102759008
Name:	SHOPPERS MART 24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	REGION 11 - AUSTIN
CN Number:	CN600918452
CN Name:	TEXAS ENTERPRISES INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	1611
Related Number:	11-92032601,34932,34932

RN Number:	RN102759008
Name:	SHOPPERS MART 24
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	REGION 11 - AUSTIN
CN Number:	CN601163454
CN Name:	TRIPLE S PETROLEUM COMPANY
CN Rating:	5
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	5541
Related Number:	11-92032601,34932,34932

JR1567 **EXPRESS MART 7** **TX RDR** **S127530928**
WNW **10500 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
135 ft. **Site 2 of 6 in cluster JR**

Actual:
729 ft.

Focus Map:
3

RDR:

RDR ID:	28231
Facility ID:	34932
RN:	Not reported
CN:	Not reported
Name:	EXPRESS MART 7
Address:	10500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX

EXPRESS MART 7 (Continued) **S127530928**

Date Report Received:	2/14/2020
Due Date:	4/14/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/24/2020
Project Manager:	Corbin Reyes
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JR1568 **SLAUSONS TEXACO** **EDR Hist Auto** **1013755503**
WNW **10500 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.026 mi.
135 ft. **Site 3 of 6 in cluster JR**

Actual:
729 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1972	SLAUSON DEAN	Gasoline Service Stations
1973	SLAUSON DEAN	Gasoline Service Stations
1974	SLAUSON DEAN	Gasoline Service Stations
1975	SLAUSON DEAN	Gasoline Service Stations
1976	SLAUSON DEAN	Gasoline Service Stations
1977	SLAUSON DEAN	Gasoline Service Stations
1978	SLAUSON DEAN	Gasoline Service Stations
1979	SLAUSON DEAN	Gasoline Service Stations
1980	SLAUSONS TEXACO	GASOLINE STATIONS
1980	SLAUSON DEAN	Gasoline Service Stations
1982	SLAUSON DEAN	Gasoline Service Stations
1983	SLAUSON DEAN	Gasoline Service Stations
1985	SLAUSON DEAN	Gasoline Service Stations
1986	SLAUSON DEAN	Gasoline Service Stations
1986	SHOPPERS MART 24	Gasoline Service Stations
1987	SLAUSON DEAN	Gasoline Service Stations
1987	SHOPPERS MART 24	Gasoline Service Stations
1988	SLAUSON DEAN	Gasoline Service Stations
1988	SHOPPERS MART 24	Gasoline Service Stations
1989	SHOPPERS MART 24	Gasoline Service Stations
1990	SHOPPER MART NO 24 SERV STA	GASOLINE STATIONS
1990	SHOPPERS MART 24	Gasoline Service Stations
1991	SHOPPERS MART 24	Gasoline Service Stations
1992	SHOPPERS MART 24	Gasoline Service Stations
1993	SHOPPERS MART 24	Gasoline Service Stations
1994	SHOPPERS MART 24	Gasoline Service Stations
1995	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1996	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations

SLAUSONS TEXACO (Continued) **1013755503**

1997	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1998	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
1999	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2000	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2001	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2002	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2003	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2004	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2005	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2006	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2007	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2008	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2009	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations
2010	TRIPLE S PETROLEUM COMPANY	Gasoline Service Stations

CK1569 **GUTHTLRIE J C DCLO CLNR** **EDR Hist Cleaner** **1013778182**
ESE **1712 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
136 ft. **Site 3 of 3 in cluster CK**

Actual:
537 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	GUTHTLRIE J C DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

JS1570 **7 ELEVEN 30467** **TX RDR** **S127533572**
ESE **10111 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
136 ft. **Site 1 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

RDR:

RDR ID:	17160
Facility ID:	45165
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 30467
Address:	10111 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/18/2008
Due Date:	5/17/2008
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Helen Welch
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED AN LPST#? WITH 26.406 DWS
Review Coordinator:	HMW
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported

7 ELEVEN 30467 (Continued) **S127533572**

NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JS1571 **B PAC PITSTOP AUTO MTCE** **EDR Hist Auto** **1013765379**
ESE **10111 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.026 mi.
136 ft. **Site 2 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

EDR Hist Auto

Year:	Name:	Type:
1990	B PAC PITSTOP AUTO MTCE	AUTOMOBILE REPAIRING
2012	N & N AUTOMOTIVE ENTERPRISES	Automotive Repair Shops, NEC
2013	N & N AUTOMOTIVE ENTERPRISES	Automotive Repair Shops, NEC
2013	TRUE BALANCE AUTOMOTIVE	Automotive Repair Shops, NEC
2014	TRUE BALANCE AUTOMOTIVE	Automotive Repair Shops, NEC

JS1572 **7 ELEVEN STORE 30467** **TX LPST** **S109028880**
ESE **10111 N LAMAR BLVD** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.026 mi.
136 ft. **Site 3 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

LPST:

Name:	7 ELEVEN STORE 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0045165
LPST Id:	117647
Facility Location:	10111 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/14/2007
Entered Date:	03/20/2008
Reported Date:	08/14/2007
Closure Date:	04/02/2009
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	AMA
Responsible Party Name:	Not reported
Responsible Party Contact:	KEN HILLIARD
Responsible Party Address:	PO BOX 711
Responsible Party City,St,Zip:	DALLAS, TX 75221 0711
Responsible Party Telephone:	214/841-6592
Reported Date:	08/14/2007
Case Start Date:	04/02/2009
Reference Number:	RN102033123
Project Manager:	AARTEAGA

7 ELEVEN STORE 30467 (Continued) **S109028880**

GCC:

Name:	7 ELEVEN INC
Address:	10111 N LAMAR
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	Not reported
File Number:	117647
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	3/20/2008
Enforcement Status - Level Of Agency Response:	6 -
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	7 ELEVEN INC
Address:	10111 N LAMAR
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	*
File Number:	117647
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	3/20/2008
Enforcement Status - Level Of Agency Response:	1A -
Enforcement Status - Site Activity Status:	1A -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

JS1573 **7-ELEVEN 30467** **TX UST** **U001276803**
ESE **10111 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.026 mi.
136 ft. **Site 4 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

UST:

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533601
AI Number:	45165
Facility Type:	RETAIL
Facility Begin Date:	01/01/1973
Facility Status:	INACTIVE
Additional ID:	866539252002117
Facility Exempt Status:	N
Records Off-Site:	Yes

7-ELEVEN 30467 (Continued) **U001276803**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	SHANE PARTRIDGE,ENV MGR
Contact Organization Name:	7-ELEVEN 30467
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2148611277
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/11/1987
Signature Name/Title On Earliest Reg Form:	PETE NEUSE,DIV GAS MGR
Application Received Date On Earliest Reg Form:	10/06/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	866539252002117
Ai Number:	45165
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	10/08/1987
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	866539252002117
AI Number:	45165
Owner Effective Begin Date:	10/08/1987
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46524
Cert ID:	229502
AI Number:	45165
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46524
Cert ID:	28526
AI Number:	45165
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	46524
Cert ID:	28525
AI Number:	45165
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28524
AI Number:	45165
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28523
AI Number:	45165
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	46524
Cert ID:	28522
AI Number:	45165
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28521
AI Number:	45165
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28520
AI Number:	45165
Self Certification Date:	11/21/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	46524
Cert ID:	28519
AI Number:	45165
Self Certification Date:	12/12/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28518
AI Number:	45165
Self Certification Date:	12/10/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28517
AI Number:	45165
Self Certification Date:	11/03/2003
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	46524
Cert ID:	28516
AI Number:	45165
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28515
AI Number:	45165
Self Certification Date:	11/29/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46524
Cert ID:	28514
AI Number:	45165
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	46524
Cert ID:	28513
AI Number:	45165
Self Certification Date:	01/10/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1973
Tank Registration Date:	10/06/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118222
Facility ID:	46524
Ai Number:	45165
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/14/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

7-ELEVEN 30467 (Continued) **U001276803**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	34654
UST ID:	118222
AI Number:	45165
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N

7-ELEVEN 30467 (Continued) **U001276803**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17631
Cert ID:	268560
UST Comprt ID:	773638
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	235310
UST Comprt ID:	675474
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	284974
UST Comprt ID:	822383
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	301938
UST Comprt ID:	873155
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	318522
UST Comprt ID:	922687
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	335606
UST Comprt ID:	973806
UST ID:	116755
AI Number:	45165

7-ELEVEN 30467 (Continued) **U001276803**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	352840
UST Comprt ID:	1025782
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	369545
UST Comprt ID:	1076045
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121511
UST Comprt ID:	352031
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121512
UST Comprt ID:	352032
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121513
UST Comprt ID:	352033
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121514
UST Comprt ID:	352030
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121515
UST Comprt ID:	352029
UST ID:	116755
AI Number:	45165
Tank ID:	4

7-ELEVEN 30467 (Continued) **U001276803**

Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121516
UST Comprt ID:	352028
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121517
UST Comprt ID:	352027
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121518
UST Comprt ID:	352026
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121519
UST Comprt ID:	352025
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121520
UST Comprt ID:	352024
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121521
UST Comprt ID:	352023
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121772
UST Comprt ID:	352022
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	17631
Cert ID:	121773
UST Comprt ID:	352021
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121774
UST Comprt ID:	352020
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	227512
UST Comprt ID:	652862
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	251927
UST Comprt ID:	724316
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1973
Tank Registration Date:	10/06/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118223
Facility ID:	46524
Ai Number:	45165
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/14/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 30467 (Continued) **U001276803**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	34655
UST ID:	118223
AI Number:	45165
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

7-ELEVEN 30467 (Continued) **U001276803**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17631
Cert ID:	268560
UST Comprt ID:	773638
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	235310
UST Comprt ID:	675474
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	284974
UST Comprt ID:	822383
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	301938
UST Comprt ID:	873155
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

7-ELEVEN 30467 (Continued) **U001276803**

Self Cert ID:	17631
Cert ID:	318522
UST Comprt ID:	922687
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	335606
UST Comprt ID:	973806
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	352840
UST Comprt ID:	1025782
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	369545
UST Comprt ID:	1076045
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	121511
UST Comprt ID:	352031
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	121512
UST Comprt ID:	352032
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631
Cert ID:	121513
UST Comprt ID:	352033
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A

Self Cert ID:	17631

7-ELEVEN 30467 (Continued) **U001276803**

Cert ID:	121514
UST Comprt ID:	352030
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121515
UST Comprt ID:	352029
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121516
UST Comprt ID:	352028
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121517
UST Comprt ID:	352027
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121518
UST Comprt ID:	352026
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121519
UST Comprt ID:	352025
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121520
UST Comprt ID:	352024
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121521

7-ELEVEN 30467 (Continued) **U001276803**

UST Comprt ID:	352023
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121772
UST Comprt ID:	352022
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121773
UST Comprt ID:	352021
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121774
UST Comprt ID:	352020
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	227512
UST Comprt ID:	652862
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	251927
UST Comprt ID:	724316
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1973
Tank Registration Date:	10/06/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118224
Facility ID:	46524
Ai Number:	45165

7-ELEVEN 30467 (Continued) **U001276803**

Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/14/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	34656
UST ID:	118224

7-ELEVEN 30467 (Continued) **U001276803**

AI Number:	45165
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17631
Cert ID:	268560
UST Comprt ID:	773638
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	235310
UST Comprt ID:	675474
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	284974

7-ELEVEN 30467 (Continued) **U001276803**

UST Comprt ID:	822383
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	301938
UST Comprt ID:	873155
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	318522
UST Comprt ID:	922687
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	335606
UST Comprt ID:	973806
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	352840
UST Comprt ID:	1025782
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	369545
UST Comprt ID:	1076045
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121511
UST Comprt ID:	352031
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121512
UST Comprt ID:	352032

7-ELEVEN 30467 (Continued) **U001276803**

UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121513
UST Comprt ID: 352033
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121514
UST Comprt ID: 352030
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121515
UST Comprt ID: 352029
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121516
UST Comprt ID: 352028
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121517
UST Comprt ID: 352027
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121518
UST Comprt ID: 352026
UST ID: 116755
AI Number: 45165
Tank ID: 4
Compartment ID: A

Self Cert ID: 17631
Cert ID: 121519
UST Comprt ID: 352025
UST ID: 116755

7-ELEVEN 30467 (Continued) **U001276803**

AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121520
UST Comprt ID:	352024
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121521
UST Comprt ID:	352023
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121772
UST Comprt ID:	352022
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121773
UST Comprt ID:	352021
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	121774
UST Comprt ID:	352020
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	227512
UST Comprt ID:	652862
UST ID:	116755
AI Number:	45165
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17631
Cert ID:	251927
UST Comprt ID:	724316
UST ID:	116755
AI Number:	45165

7-ELEVEN 30467 (Continued) **U001276803**

Tank ID: 4
Compartment ID: A

Construction Notification:
NOC ID: 25298
Facility ID: 46524
AI Number: 45165
Application Received Date: 02/05/2014
Scheduled Construction Date: 04/07/2014
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: Not reported
Waiver Flag: N
Late Filing Flag: N
Form Received Date: 03/07/2014
Signature Date On Form: 03/07/2014
Signature Name On Form: KIM TAPIA
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: 7-ELEVEN INC
Owner CN At Time Of Construction: CN600240329
Owner AR At Time Of Construction: 3971
General Desc Of Prop Construct: REMOVAL & DISPOSAL OF (3) 10,000 GAL SW FIBERGLASS REINFORCED PLASTIC UST'S, PIPING AND VENTS.

NOC ID: 2957
Facility ID: 46524
AI Number: 45165
Application Received Date: 08/29/2007
Scheduled Construction Date: 09/05/2007
UST Improvement: Y
UST Installation: N
UST Removal: N
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M70829002
Waiver Flag: N
Late Filing Flag: Y
Form Received Date: 03/07/2014
Signature Date On Form: 03/07/2014
Signature Name On Form: KIM TAPIA
Signature Company On Form: Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	59294
UST ID:	Not reported
NOC ID:	25298
AI Number:	45165
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CB&I
Representative Name:	KIM TAPIA
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738449
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	7738401
Email Address:	Not reported

Cont/Cons/Installer ID:	3329
UST ID:	Not reported
NOC ID:	2957
AI Number:	45165
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	59486

7-ELEVEN 30467 (Continued) **U001276803**

UST ID:	Not reported
NOC ID:	25298
AI Number:	45165
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	MCCON BUILDING AND PETROLEUM
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	8120 JETSTAR STE 150
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46524
Additional ID:	866539252002117
Princ ID:	959578622001257
AI Number:	45165
Facility Name:	7-ELEVEN 30467
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1965
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD

7-ELEVEN 30467 (Continued) **U001276803**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	118212
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	120467
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	2435
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported

7-ELEVEN 30467 (Continued) **U001276803**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	28549
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	28550
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000

7-ELEVEN 30467 (Continued) **U001276803**

Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	28551
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	28552
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524

7-ELEVEN 30467 (Continued) **U001276803**

Finass ID:	28553
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 30467
Address:	10111 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46524
Finass ID:	28554
AI:	45165
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

JS1574 **7 ELEVEN STORE 30467** **TX RDR** **S127533573**
ESE **10111 N LAMAR ST** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
136 ft. **Site 5 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

RDR:

RDR ID:	22125
Facility ID:	45165
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 30467
Address:	10111 N LAMAR ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/3/2014

7 ELEVEN STORE 30467 (Continued) **S127533573**

Due Date:	9/1/2014
Tank Owner:	7 ELEVEN INC
Contact Person:	JOSE RIOS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/27/2014
Project Manager:	Stacey Dunahoo
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JS1575 **7-11** **TX RDR** **S127533574**
ESE **10111 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
136 ft. **Site 6 of 6 in cluster JS**

Actual:
712 ft.

Focus Map:
3

RDR:

RDR ID:	6419
Facility ID:	45165
RN:	Not reported
CN:	Not reported
Name:	7-11
Address:	10111 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	SOUTHLAND
Contact Person:	K. JANE LOMAS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/30/1996
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 19
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/30/1996
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DR1576 **G F DURDEN C** **EDR Hist Cleaner** **1013782939**
NE **504 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
136 ft. **Site 28 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1906	G F DURDEN C	LAUNDRIES

BW1577 **KWIK WASH COIN LAUNDRIES** **EDR Hist Cleaner** **1013786059**
East **704 24TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.026 mi.
136 ft. **Site 11 of 12 in cluster BW**

Actual:
597 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1975	KWIK WASH COIN LAUNDRIES	LAUNDRIES-SELF SERVE

HS1578 **HEB 628** **TX LPST** **U001286075**
NE **2512 E RIVERSIDE DR** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX HIST UST**
0.026 mi. **TX Financial Assurance**
137 ft. **Site 2 of 6 in cluster HS** **TX CENTRAL REGISTRY**

Actual:
480 ft.

Focus Map:
15

LPST:

Name:	EXXON 60103
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0055951
LPST Id:	114520
Facility Location:	2512 E RIVERSIDE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	02/25/1999
Entered Date:	03/24/1999
Reported Date:	02/25/1999
Closure Date:	11/04/1999
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	JES
Responsible Party Name:	Not reported
Responsible Party Contact:	HARRY JANKE
Responsible Party Address:	1201 E AIRPORT FWY STE 100
Responsible Party City,St,Zip:	IRVING, TX 75062
Responsible Party Telephone:	972/579-3627
Reported Date:	02/25/1999
Case Start Date:	11/04/1999
Reference Number:	RN101620326
Project Manager:	JSIROTA

HEB 628 (Continued) **U001286075**

UST:

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787413037
AI Number:	55951
Facility Type:	RETAIL
Facility Begin Date:	09/28/1990
Facility Status:	ACTIVE
Additional ID:	764641652002175
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/11/1989
Signature Name/Title On Earliest Reg Form:	G J MEYER,UGT ANALYST
Application Received Date On Earliest Reg Form:	03/15/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	691789092002161
Additional ID:	764641652002175
Ai Number:	55951
Operator CN:	CN601297963
Operator Name:	H-E-B LP
Operator Effective Begin Date:	05/23/2011
Operator Type:	PA
Operator Role:	OWNOPRCON
Contact Name:	TERRY PARR/
Contact Organization Name:	H-E-B LP
Contact Mailing Address (Delivery):	PO BOX 839968
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78283-3968
Contact Phone Country Code:	0
Contact Phone Area Code:	210
Contact Phone Number:	9384040
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

HEB 628 (Continued) **U001286075**

Contact Email Address:	PARR.TERRY@HEB.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601297963
Owner Last Name:	H-E-B LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	PO BOX 839968
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	SAN ANTONIO
Contact Mailing State:	TX
Contact Mailing Zip:	78283
Contact Mailing Zip5:	3968
Contact Phone Number/Ext:	0 210 9384040/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	PARR.TERRY@HEB.COM
Contact Address Deliverable:	Not reported
Princ ID:	691789092002161
Additional ID:	764641652002175
AI Number:	55951
Owner Effective Begin Date:	05/23/2011
State Tax ID:	17430106579
Contact Role:	OWNOPRCON
Contact Name/Title:	TERRY PARR/
Contact Organization Name:	H-E-B LP

Self Certification:

Self Cert ID:	48586
Cert ID:	373451
AI Number:	55951
Self Certification Date:	07/29/2022
Signature Name/Title:	REGINA LOPEZ PETROLEUM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	356996
AI Number:	55951
Self Certification Date:	07/29/2021
Signature Name/Title:	Regina Lopez Petroleum Operations
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	339639
AI Number:	55951
Self Certification Date:	07/21/2020
Signature Name/Title:	Regina Lopez Operations Trainer
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	323626
AI Number:	55951
Self Certification Date:	07/26/2019
Signature Name/Title:	Jude A Fournier Petroleum Ops Traing
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	307061
AI Number:	55951
Self Certification Date:	07/30/2018
Signature Name/Title:	Jude A Fournier Petroleum Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	289971
AI Number:	55951
Self Certification Date:	08/07/2017
Signature Name/Title:	Jude A Fournier Petroleum Manager
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	273812
AI Number:	55951
Self Certification Date:	08/19/2016
Signature Name/Title:	Rosie Espinoza petroluem advisor
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	256145
AI Number:	55951
Self Certification Date:	08/06/2015
Signature Name/Title:	Rosie Espinoza petroleum advisor
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	238536
AI Number:	55951
Self Certification Date:	07/08/2014
Signature Name/Title:	Rosie Espinoza petroleum advisor
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	221954
AI Number:	55951
Self Certification Date:	07/11/2013
Signature Name/Title:	Rosie Espinoza Administrative
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	48586
Cert ID:	37750
AI Number:	55951
Self Certification Date:	07/12/2012
Signature Name/Title:	ROSIE ESPINOZA PETROLEUM ADVISOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37749
AI Number:	55951
Self Certification Date:	06/11/2011
Signature Name/Title:	TERRY PARR OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37748
AI Number:	55951
Self Certification Date:	06/10/2011
Signature Name/Title:	TERRY PARR OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37747
AI Number:	55951
Self Certification Date:	04/01/2011
Signature Name/Title:	TARONZA L GRAVES REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37746
AI Number:	55951
Self Certification Date:	03/15/2010
Signature Name/Title:	TARONZA L GRAVES OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37745
AI Number:	55951
Self Certification Date:	03/27/2009
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37744
AI Number:	55951
Self Certification Date:	03/26/2008
Signature Name/Title:	ADRIANNE RUTHERFORD OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37743
AI Number:	55951
Self Certification Date:	04/17/2007
Signature Name/Title:	HEATHER GILMORE AUTH REP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37742
AI Number:	55951
Self Certification Date:	03/06/2006
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37741
AI Number:	55951
Self Certification Date:	03/15/2005
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37740
AI Number:	55951
Self Certification Date:	03/12/2004
Signature Name/Title:	ERIC M. MCPHEE CMS PERMITTING MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37488
AI Number:	55951
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37487
AI Number:	55951
Self Certification Date:	03/12/2002
Signature Name/Title:	WENDY SALAS PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

HEB 628 (Continued) **U001286075**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	48586
Cert ID:	37486
AI Number:	55951
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	11/01/1989
Tank Registration Date:	03/15/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	135783
Facility ID:	48586
Ai Number:	55951
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N

HEB 628 (Continued) **U001286075**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	27295
UST ID:	135783
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

HEB 628 (Continued) **U001286075**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791

HEB 628 (Continued) **U001286075**

Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051

HEB 628 (Continued) **U001286075**

UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343

HEB 628 (Continued) **U001286075**

UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Install Date:	11/01/1989
Tank Registration Date:	03/15/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	135784
Facility ID:	48586
Ai Number:	55951
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

HEB 628 (Continued) **U001286075**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	27296
UST ID:	135784
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

HEB 628 (Continued) **U001286075**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900

HEB 628 (Continued) **U001286075**

UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515

HEB 628 (Continued) **U001286075**

AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951

HEB 628 (Continued) **U001286075**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Install Date:	11/01/1989
Tank Registration Date:	03/15/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	135785
Facility ID:	48586
Ai Number:	55951
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

HEB 628 (Continued) **U001286075**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	27297
UST ID:	135785
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

HEB 628 (Continued) **U001286075**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951

HEB 628 (Continued) **U001286075**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4

HEB 628 (Continued) **U001286075**

Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A

HEB 628 (Continued) **U001286075**

Install Date:	11/01/1989
Tank Registration Date:	03/15/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	135786
Facility ID:	48586
Ai Number:	55951
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/24/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

HEB 628 (Continued) **U001286075**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	3A
Tank Capacity:	10000
UST Comprt ID:	27298
UST ID:	135786
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A

HEB 628 (Continued) **U001286075**

Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791

HEB 628 (Continued) **U001286075**

Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765

HEB 628 (Continued) **U001286075**

UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Install Date:	03/02/1999
Tank Registration Date:	11/02/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	192498
Facility ID:	48586
Ai Number:	55951

HEB 628 (Continued) **U001286075**

Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	03/02/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	27299
UST ID:	192498

HEB 628 (Continued) **U001286075**

AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/02/1999

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979

HEB 628 (Continued) **U001286075**

UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332

HEB 628 (Continued) **U001286075**

UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515

HEB 628 (Continued) **U001286075**

AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Install Date:	03/02/1999
Tank Registration Date:	11/02/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	192499
Facility ID:	48586
Ai Number:	55951
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	03/02/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

HEB 628 (Continued) **U001286075**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1999

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	27300
UST ID:	192499
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y

HEB 628 (Continued) **U001286075**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/02/1999

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515

HEB 628 (Continued) **U001286075**

AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951

HEB 628 (Continued) **U001286075**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4

HEB 628 (Continued) **U001286075**

Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Install Date:	03/02/1999
Tank Registration Date:	03/02/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	192500
Facility ID:	48586
Ai Number:	55951
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	03/02/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

HEB 628 (Continued) **U001286075**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1999

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	27301
UST ID:	192500
AI Number:	55951
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

HEB 628 (Continued) **U001286075**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/02/1999

More Self Certification:

Self Cert ID:	21791
Cert ID:	134760
UST Comprt ID:	415341
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	303130
UST Comprt ID:	876612
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	285979
UST Comprt ID:	825227
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	269842
UST Comprt ID:	777396
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	253063
UST Comprt ID:	727662
UST ID:	136515
AI Number:	55951
Tank ID:	4

HEB 628 (Continued) **U001286075**

Compartment ID:	A
Self Cert ID:	21791
Cert ID:	236828
UST Comprt ID:	679900
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	220190
UST Comprt ID:	631213
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135056
UST Comprt ID:	415330
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135055
UST Comprt ID:	415331
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135054
UST Comprt ID:	415332
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135052
UST Comprt ID:	415334
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135051
UST Comprt ID:	415335
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A

HEB 628 (Continued) **U001286075**

Self Cert ID:	21791
Cert ID:	134768
UST Comprt ID:	415336
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134767
UST Comprt ID:	415337
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134766
UST Comprt ID:	415338
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134765
UST Comprt ID:	415339
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134764
UST Comprt ID:	415340
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134763
UST Comprt ID:	415344
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	134762
UST Comprt ID:	415343
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791

HEB 628 (Continued) **U001286075**

Cert ID:	134761
UST Comprt ID:	415342
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21791
Cert ID:	135053
UST Comprt ID:	415333
UST ID:	136515
AI Number:	55951
Tank ID:	4
Compartment ID:	A

Construction Notification:

NOC ID:	3502
Facility ID:	48586
AI Number:	55951
Application Received Date:	06/10/2011
Scheduled Construction Date:	06/20/2011
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	4194
General Desc Of Prop Construct:	UPGRADE TANK TOP IE: INSTALL 22" MANWAYS FRP STP SUMPS, MULTIPOINT SPILL AND VAP OR MANHOLES, MANIFOLD TANK 1&2 UNLEADED TANK 3-SUPER UNLEADED. REPIPE PRODUCT L INES. INSTALL FRP DISPENSER SUMPS, LIQUID SENSORS @ ALL CONT SUMPS.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	27595
UST ID:	192500
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280

HEB 628 (Continued) **U001286075**

Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	27593
UST ID:	192498
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280
Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	27594
UST ID:	192499
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280
Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

HEB 628 (Continued) **U001286075**

Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42760
UST ID:	192498
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002170
Company Name:	Not reported
Representative Name:	JOSEPH JOHNSON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42762
UST ID:	192500
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002170
Company Name:	Not reported
Representative Name:	JOSEPH JOHNSON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

HEB 628 (Continued) **U001286075**

Cont/Cons/Installer ID:	42761
UST ID:	192499
NOC ID:	Not reported
AI Number:	55951
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002170
Company Name:	Not reported
Representative Name:	JOSEPH JOHNSON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	H-E-B LP
Contact Mailing Address (Delivery):	PO BOX 839968
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78283 3968
Phone Number/Ext:	210 9384040/0
Contact Fax Number/Ext:	/
Contact Email Address:	parr.terry@heb.com
Contact Address Deliverable:	Y
Facility ID:	48586
Additional ID:	764641652002175
Princ ID:	691789092002161
AI Number:	55951
Facility Name:	HEB 628
AR Number:	58478
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	TERRY PARR/

HIST UST AUSTIN:

Name:	HEB #628 AUSTIN #12 "C" STORE
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	3092
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	HEB 628

HEB 628 (Continued) **U001286075**

Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	271298
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 6888254
Policy Number:	ISPILLSCFI7W001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	253760
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	233858
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

HEB 628 (Continued) **U001286075**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	216969
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606901
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	200170
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900

HEB 628 (Continued) **U001286075**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	182126
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	165947
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2

HEB 628 (Continued) **U001286075**

Facility ID:	48586
Finass ID:	165819
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	002606900
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	147027
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	AIG INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	129845
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

HEB 628 (Continued) **U001286075**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	OTHER
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	110376
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	CHARTIS SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	112481
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/29/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	CHARTIS SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	PLC 2183057
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/29/2013
Ins Premium Pre-Paid For Entire Yr:	No

HEB 628 (Continued) **U001286075**

Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	2819
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/05/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9384934
Policy Number:	0
Coverage Amount:	1000000
Coverage Expiration Date:	01/05/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32249
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32248
AI:	55951

HEB 628 (Continued) **U001286075**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 9384934
Policy Number:	0
Coverage Amount:	1000000
Coverage Expiration Date:	04/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32250
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32251
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported

HEB 628 (Continued) **U001286075**

Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32252
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32253
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEB 628

HEB 628 (Continued) **U001286075**

Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	48586
Finass ID:	32254
AI:	55951
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

CENTRAL REGISTRY:

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1990-03-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1990-03-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190

HEB 628 (Continued) **U001286075**

Primary NAICS Industry Type Description: Other Gasoline Stations
Physical Location Description: Not reported

Regulated Entity Number: RN101620326
Name: HEB 628
Address: 2512 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-3037
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN600123939
Customer Name: EXXON MOBIL CORPORATION
Customer Legal Name: Exxon Mobil Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 1990-03-15
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447190
Primary NAICS Industry Type Description: Other Gasoline Stations
Physical Location Description: Not reported

Regulated Entity Number: RN101620326
Name: HEB 628
Address: 2512 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-3037
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN601297963
Customer Name: H-E-B LP
Customer Legal Name: H-E-B, LP
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 2011-05-23
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447190
Primary NAICS Industry Type Description: Other Gasoline Stations
Physical Location Description: Not reported

Regulated Entity Number: RN101620326
Name: HEB 628
Address: 2512 E RIVERSIDE DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-3037
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN601297963
Customer Name: H-E-B LP
Customer Legal Name: H-E-B, LP
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 2011-05-23
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447190
Primary NAICS Industry Type Description: Other Gasoline Stations
Physical Location Description: Not reported

HEB 628 (Continued) **U001286075**

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN601297963
Customer Name:	H-E-B LP
Customer Legal Name:	H-E-B, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2011-05-23
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR

HEB 628 (Continued) **U001286075**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN601463607
Customer Name:	EXXON COMPANY USA
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/15/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Regulated Entity Number:	RN101620326
Name:	HEB 628
Address:	2512 E RIVERSIDE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3037
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/15/1990
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447190
Primary NAICS Industry Type Description:	Other Gasoline Stations
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
11 additional TX CENTRAL REG: record(s) in the EDR Site Report.

HS1579 **EXXON TIGERMART RS 60103** **TX Ind. Haz Waste** **S102757916**
NE **2512 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.026 mi.
137 ft. **Site 3 of 6 in cluster HS**

Actual:
480 ft.

Focus Map:
15

Ind. Haz Waste:

Name:	EXXON TIGERMART RS 60103
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	77278
Registration Initial Notification Date:	04/19/1991
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988032173
Primary NAICS Code:	Not reported
Status Change Date:	19910419
Land Type:	PRIVATE
Description of Facility Site Location:	2512 E Riverside Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6569075
Mailing Address:	PO BOX 4552
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 772104552
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	98370
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

EXXON TIGERMART RS 60103 (Continued) **S102757916**

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 4552
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77210
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 4552
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 4552
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 4552
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 4552
Contact Address 2:	Not reported

EXXON TIGERMART RS 60103 (Continued) **S102757916**

Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6569075
Contact Fax:	Not reported
Contact Email:	Not reported

HS1580 **EXXON #6-01033** **TX RDR** **S127535794**
NE **2512 EAST RIVERSIDE DRIVE** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
137 ft. **Site 4 of 6 in cluster HS**

Actual:
480 ft.

Focus Map:
15

RDR:

RDR ID:	7765
Facility ID:	55951
RN:	Not reported
CN:	Not reported
Name:	EXXON #6-01033
Address:	2512 EAST RIVERSIDE DRIVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	EXXON
Contact Person:	TOM VALERY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/27/1996
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 4
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/27/1996
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

HS1581 **EXXON MOBIL CORPORATION** **RCRA NonGen / NLR** **1004785592**
NE **2512 E RIVERSIDE DR** **FINDS** **TXD988032173**
< 1/8 **AUSTIN, TX 78741** **ECHO**
0.026 mi.
137 ft. **Site 5 of 6 in cluster HS**

Actual:
480 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	E RIVERSIDE DR
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXD988032173
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 4552

EXXON MOBIL CORPORATION (Continued) **1004785592**

Contact City,State,Zip:	HOUSTON, TX 77210
Contact Telephone:	713-656-9075
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 4552
Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060111
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

EXXON MOBIL CORPORATION (Continued) **1004785592**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D018
Waste Description: Benzene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Not reported
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4999
Owner/Operator City,State,Zip: THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone: 281-296-3655
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Not reported
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210

EXXON MOBIL CORPORATION (Continued) **1004785592**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000215
Handler Name: EXXON RAS NO 60103
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

EXXON MOBIL CORPORATION (Continued) **1004785592**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005132588

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004785592
Registry ID:	110005132588
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005132588
Name:	EXXON MOBIL CORPORATION
Address:	2512 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

HS1582 **EXXON MOBIL CORPORATION** **EDR Hist Auto** **1013772458**
NE **2512 E RIVERSIDE DR** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.026 mi.
137 ft. **Site 6 of 6 in cluster HS**

Actual:
480 ft.

EDR Hist Auto

Focus Map:
15

Year:	Name:	Type:
1990	EXXON SHOP GASOLINE	GASOLINE STATIONS
1991	EXXON SHOP 6 0103	Petroleum Products, NEC
2007	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2008	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2009	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2010	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2011	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC

IX1583 **MAGNOLIA PETROLEUM** **EDR Hist Auto** **1013754792**
WNW **220 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.026 mi.
137 ft. **Site 2 of 6 in cluster IX**

Actual:
438 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	MAGNOLIA PETROLEUM	GASOLINE AND OIL SERVICE STATIONS

IX1584 **WILLIAMS MOTOR INC** **TX HIST UST** **S128729509**
NNE **200 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
137 ft. **Site 3 of 6 in cluster IX**

Actual:
449 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	WILLIAMS MOTOR INC
Address:	200 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	N0050
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IX1585 **W.A. STEPHENS** **TX HIST UST** **S128729185**
NNE **200 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
137 ft. **Site 4 of 6 in cluster IX**

Actual:
449 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	W.A. STEPHENS
Address:	200 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0102
HID UST:	102
Inspection:	02/06/2009
Due:	02/06/2012

IR1586 **HYDE PARK GARAGE AUTO REPR** **EDR Hist Auto** **1013757392**
SW **513 43RD W** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
138 ft. **Site 2 of 7 in cluster IR**

Actual:
622 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1947	HYDE PARK GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1953	HYDE PARK GARAGE	AUTOMOBILE REPAIRING
1958	HYDE PARK GARAGE	AUTOMOBILE REPAIRING
1962	HYDE PARK GARAGE	AUTOMOBILE REPAIRING

IR1587 **HYDE PARK GARAGE AUTO RBPR** **EDR Hist Auto** **1013754379**
SW **513 43RD ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
138 ft. **Site 3 of 7 in cluster IR**

Actual:
622 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1965	HYDE PARK GARAGE AUTO RBPR	AUTOMOBILE REPAIRING

IR1588 **HYDE PARK GARAGE** **EDR Hist Auto** **1013772588**
SW **513 43RD ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78751**
0.026 mi.
138 ft. **Site 4 of 7 in cluster IR**

Actual:
622 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1970	HYDE PARK GARAGE	AUTOMOBILE REPAIRING
1975	HYDE PARK GARAGE	AUTOMOBILE REPAIRING

DR1589 **DOYLE DARBY TAILOR** **EDR Hist Cleaner** **1013785567**
NE **506 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
138 ft. **Site 29 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	DOYLE DARBY TAILOR	CLOTHES PRESSERS AND CLEANERS

DQ1590 **C. O. LANDAHL** **TX HIST UST** **S111678581**
NNE **300 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
139 ft. **Site 9 of 11 in cluster DQ**

Actual:
489 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	C. O. LANDAHL
Address:	300 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0045
HID UST:	45
Inspection:	Not reported
Due:	06/01/2012

R1591 WNW < 1/8 0.026 mi. 139 ft. | **7-ELEVEN 25445**
8900 N LAMAR
AUSTIN, TX
Site 9 of 12 in cluster R | **TX RDR** | **S127538708**
N/A

Actual: 663 ft.
Focus Map: 6

RDR:

RDR ID:	19732
Facility ID:	7161
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN 25445
Address:	8900 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/18/2011
Due Date:	7/17/2011
Tank Owner:	7-ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	7/26/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	97544
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	7/26/2011
Region:	Not reported
DKC RDR (misfiled):	Not reported

R1592 WNW < 1/8 0.026 mi. 139 ft. | **GRIFFS TEXACO SERVICE STATION**
8900 LAMAR BLVD N
TRAVIS (County), TX 78753
Site 10 of 12 in cluster R | **EDR Hist Auto** | **1013760196**
N/A

Actual: 663 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1969	SIDS TEXACO SERVICE STATION	Gasoline Service Stations
1970	WARDS TEXACO SERVICE STATION	GASOLINE STATIONS
1970	SIDS TEXACO SERVICE STATION	Gasoline Service Stations
1973	GRIFFIN VERNON E	Gasoline Service Stations
1974	GRIFFIN VERNON E	Gasoline Service Stations
1975	GRIFFS TEXACO SERVICE STATION	GASOLINE STATIONS
1975	GRIFFIN VERNON E	Gasoline Service Stations
1976	GRIFFIN VERNON E	Gasoline Service Stations
1977	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1978	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1979	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1980	HOLLOWAY TEXACO SERV ST	GASOLINE STATIONS
1980	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1982	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1983	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1984	FBLLOWAY TEXACO SERVICE ST	GASOLINE STATIONS

GRIFFS TEXACO SERVICE STATION (Continued) **1013760196**

1985	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1986	NORMAN BROTHERS TEXACO	Gasoline Service Stations
1987	NORMAN BROTHERS TEXACO	Gasoline Service Stations

R1593 **7-ELEVEN 25445** **TX LPST** **U001243584**
WNW **8900 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX HIST UST**
0.026 mi. **TX Financial Assurance**
139 ft. **Site 11 of 12 in cluster R**

Actual:
663 ft.

Focus Map:
6

LPST:

Name:	7 ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78758
Facility ID:	0007161
LPST Id:	097544
Facility Location:	8900 N LAMAR BLVD @ PEYTON GIN RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/06/1990
Entered Date:	12/17/1990
Reported Date:	12/07/1990
Closure Date:	02/22/1996
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	JES
Responsible Party Name:	Not reported
Responsible Party Contact:	KEN HILLIARD
Responsible Party Address:	PO BOX 711
Responsible Party City,St,Zip:	DALLAS, TX 75221 0711
Responsible Party Telephone:	214/841-6592
Reported Date:	12/07/1990
Case Start Date:	02/22/1996
Reference Number:	RN102008117
Project Manager:	JSIROTA

UST:

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535012
AI Number:	7161
Facility Type:	RETAIL
Facility Begin Date:	07/08/1986
Facility Status:	ACTIVE
Additional ID:	490562012002116
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

7-ELEVEN 25445 (Continued) **U001243584**

Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BICK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	490562012002116
Ai Number:	7161
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported

7-ELEVEN 25445 (Continued) **U001243584**

Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	490562012002116
AI Number:	7161
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46163
Cert ID:	381576
AI Number:	7161
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	364252
AI Number:	7161
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	347646
AI Number:	7161
Self Certification Date:	01/18/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	330872
AI Number:	7161
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	314558
AI Number:	7161
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	296366
AI Number:	7161
Self Certification Date:	12/28/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	280947
AI Number:	7161
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	263381
AI Number:	7161
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	247278
AI Number:	7161
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	229605
AI Number:	7161
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46163
Cert ID:	27546
AI Number:	7161
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27545
AI Number:	7161
Self Certification Date:	12/15/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27544
AI Number:	7161
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27543
AI Number:	7161
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27542
AI Number:	7161
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27541
AI Number:	7161
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27540
AI Number:	7161
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27539
AI Number:	7161
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27538
AI Number:	7161
Self Certification Date:	12/13/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27537
AI Number:	7161
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27536
AI Number:	7161
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER

7-ELEVEN 25445 (Continued) **U001243584**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27535
AI Number:	7161
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46163
Cert ID:	27534
AI Number:	7161
Self Certification Date:	01/10/2001
Signature Name/Title:	WILLO A SMITH ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y

7-ELEVEN 25445 (Continued) **U001243584**

Tank Doublewall:	N
Pipe Type:	P
UST ID:	18573
Facility ID:	46163
Ai Number:	7161
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

7-ELEVEN 25445 (Continued) **U001243584**

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26036
UST ID:	18573
AI Number:	7161
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18574
Facility ID:	46163
Ai Number:	7161
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1986

7-ELEVEN 25445 (Continued) **U001243584**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26037
UST ID:	18574
AI Number:	7161
Compartment ID:	A
Substance Stored1:	GASOLINE

7-ELEVEN 25445 (Continued) **U001243584**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18575
Facility ID:	46163
Ai Number:	7161
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 25445 (Continued) **U001243584**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26038
UST ID:	18575
AI Number:	7161
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

7-ELEVEN 25445 (Continued) **U001243584**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	2504
Facility ID:	46163
AI Number:	7161
Application Received Date:	07/01/2010
Scheduled Construction Date:	06/21/2010
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REPLACE MUL SPILL BUCKET

7-ELEVEN 25445 (Continued) **U001243584**

NOC ID:	2503
Facility ID:	46163
AI Number:	7161
Application Received Date:	04/13/2011
Scheduled Construction Date:	04/14/2011
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REPLACE RUL SPILL BUCKET WITH NEW OPW DOUBLE-WALLED SPILL BUCKET.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	2765
UST ID:	Not reported
NOC ID:	2504
AI Number:	7161
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	JENNIFER DART
Mailing Address (Delivery):	6330 COMMMERCE ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	214
Phone Number:	2777848
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2762
UST ID:	Not reported
NOC ID:	2503

7-ELEVEN 25445 (Continued) **U001243584**

AI Number:	7161
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	JENNIFER DART
Mailing Address (Delivery):	6330 COMMERCE ST
Mailing Address (Internal Delivery):	STE 190
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	214
Phone Number:	2777848
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2761
UST ID:	Not reported
NOC ID:	2503
AI Number:	7161
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	STE 150
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2764
UST ID:	Not reported
NOC ID:	2504
AI Number:	7161
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SVCS
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	8426 STERLING ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX

7-ELEVEN 25445 (Continued) **U001243584**

Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2766
UST ID:	Not reported
NOC ID:	2504
AI Number:	7161
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2763
UST ID:	Not reported
NOC ID:	2503
AI Number:	7161
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

7-ELEVEN 25445 (Continued) **U001243584**

Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46163
Additional ID:	490562012002116
Princ ID:	959578622001257
AI Number:	7161
Facility Name:	7-ELEVEN 25445
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN STORE #25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	811
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	278701
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes

7-ELEVEN 25445 (Continued) **U001243584**

Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	261550
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	242257
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	223520
AI:	7161

7-ELEVEN 25445 (Continued) **U001243584**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	224120
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	207929
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported

7-ELEVEN 25445 (Continued) **U001243584**

Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	189237
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	172742
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445

7-ELEVEN 25445 (Continued) **U001243584**

Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	154085
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	138245
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	120379
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

7-ELEVEN 25445 (Continued) **U001243584**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	118166
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	1533
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401

7-ELEVEN 25445 (Continued) **U001243584**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	28527
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	28528
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2

7-ELEVEN 25445 (Continued) **U001243584**

Facility ID:	46163
Finass ID:	28529
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	28530
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	28531
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7-ELEVEN 25445 (Continued) **U001243584**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 25445
Address:	8900 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	46163
Finass ID:	28532
AI:	7161
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

R1594 **7 ELEVEN 25445** **TX RDR** **S127538707**
WNW **8900 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
139 ft. **Site 12 of 12 in cluster R**

Actual:
663 ft.

Focus Map:
6

RDR:

RDR ID:	18541
Facility ID:	7161
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 25445
Address:	8900 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/3/2009
Due Date:	1/2/2010
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	2/19/2010
Project Manager:	PST Privitization Contract
Team:	#N/A

7 ELEVEN 25445 (Continued) **S127538707**

New LPST Number:	Not reported
Pre-Existing LPST Number:	97544
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	2/19/2010
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	19015
Facility ID:	7161
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 25445
Address:	8900 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/7/2010
Due Date:	9/5/2010
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	9/1/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	97544
Comments:	SEE RDR 18541
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	9/1/2010
Region:	Not reported
DKC RDR (misfiled):	Not reported

1595 **STOP N SAVE 3** **TX LPST** **U001272108**
ENE **1800 BURTON DR** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX HIST UST**
0.026 mi. **TX ASBESTOS**
139 ft. **TX ENF**
TX Financial Assurance

Actual:
519 ft.

Focus Map:
14

LPST:

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0039565
LPST Id:	091818
Facility Location:	1800 BURTON DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/15/1988
Entered Date:	04/15/1988

STOP N SAVE 3 (Continued) **U001272108**

Reported Date:	04/15/1988
Closure Date:	08/09/1998
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3/2/1
Coordinators RPR:	SLR
Responsible Party Name:	Not reported
Responsible Party Contact:	ROBIN SHAVER
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	TX
Responsible Party Telephone:	/-
Reported Date:	04/15/1988
Case Start Date:	08/09/1998
Reference Number:	RN101499796
Project Manager:	SLR

UST:

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 787414266
AI Number:	39565
Facility Type:	RETAIL
Facility Begin Date:	01/01/1973
Facility Status:	ACTIVE
Additional ID:	554547622002054
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	SAHIL SOMANI,
Contact Organization Name:	STOP N SAVE 3
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124473373
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/10/2019
Signature Name/Title On Earliest Reg Form:	MONSIN KAROWALIA,OPERATOR
Application Received Date On Earliest Reg Form:	11/21/2019
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	444308192011159

STOP N SAVE 3 (Continued) **U001272108**

Additional ID:	554547622002054
Ai Number:	39565
Operator CN:	CN603862509
Operator Name:	BURTON GROCERS INC
Operator Effective Begin Date:	06/01/2011
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	SAHIL SOMAIN/
Contact Organization Name:	BURTON GROCERS INC
Contact Mailing Address (Delivery):	1800 BURTON DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78741-4266
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4473373
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603862509
Owner Last Name:	BURTON GROCERS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1800 BURTON DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78741
Contact Mailing Zip5:	4266
Contact Phone Number/Ext:	1 512 4473373/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	444308192011159
Additional ID:	554547622002054
AI Number:	39565
Owner Effective Begin Date:	06/01/2011
State Tax ID:	32043622409
Contact Role:	OWNOPRCON
Contact Name/Title:	SAHIL SOMAIN/
Contact Organization Name:	BURTON GROCERS INC

Self Certification:

Self Cert ID:	87640
Cert ID:	265585
AI Number:	39565
Self Certification Date:	02/22/2016
Signature Name/Title:	SAHIL SOMANI OFFICER
Signature Type Role:	OPERATOR

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	N
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	87640
Cert ID:	234665
AI Number:	39565
Self Certification Date:	03/28/2014
Signature Name/Title:	SAHIL SOMAIN OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	N
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	87640
Cert ID:	143844
AI Number:	39565
Self Certification Date:	04/01/2013
Signature Name/Title:	SAHIL SOMANI OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143843
AI Number:	39565
Self Certification Date:	03/31/2013
Signature Name/Title:	SAHIL SOMANI OFFICER
Signature Type Role:	OPERATOR

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143842
AI Number:	39565
Self Certification Date:	03/31/2012
Signature Name/Title:	SAHIL SOMANI OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143841
AI Number:	39565
Self Certification Date:	03/30/2011
Signature Name/Title:	SAHIL SOMANI OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143840
AI Number:	39565
Self Certification Date:	03/10/2010
Signature Name/Title:	BASSAM QUSSAD PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143839
AI Number:	39565
Self Certification Date:	02/13/2009
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143838
AI Number:	39565
Self Certification Date:	02/07/2008
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143837
AI Number:	39565
Self Certification Date:	02/18/2007
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143836
AI Number:	39565
Self Certification Date:	01/30/2006
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143835
AI Number:	39565
Self Certification Date:	03/30/2005
Signature Name/Title:	BASSAM QUASSAD PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143834
AI Number:	39565
Self Certification Date:	02/18/2004
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	OWNER

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143833
AI Number:	39565
Self Certification Date:	03/03/2003
Signature Name/Title:	BASSA QUSSAD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143832
AI Number:	39565
Self Certification Date:	02/03/2002
Signature Name/Title:	BASSAM QUSSAD PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87640
Cert ID:	143831
AI Number:	39565
Self Certification Date:	12/22/2000
Signature Name/Title:	BASSAM QUSSAD PRESIDENT
Signature Type Role:	OPERATOR

STOP N SAVE 3 (Continued) **U001272108**

Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104606
Facility ID:	87640
Ai Number:	39565
Tank Id:	1
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	01/30/2017
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

STOP N SAVE 3 (Continued) **U001272108**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	147946
UST ID:	104606
AI Number:	39565
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

STOP N SAVE 3 (Continued) **U001272108**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104607
Facility ID:	87640
Ai Number:	39565
Tank Id:	2
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	01/30/2017
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

STOP N SAVE 3 (Continued) **U001272108**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	147947
UST ID:	104607
AI Number:	39565
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

STOP N SAVE 3 (Continued) **U001272108**

NOC ID:	25532
Facility ID:	87640
AI Number:	39565
Application Received Date:	04/02/2014
Scheduled Construction Date:	04/07/2014
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	04/02/2014
Signature Date On Form:	04/02/2014
Signature Name On Form:	DAVID FINBERG
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	BURTON GROCERS INC
Owner CN At Time Of Construction:	CN603862509
Owner AR At Time Of Construction:	74314
General Desc Of Prop Construct:	DRILLING AND INSTALLING CATHODIC PROTECTION SYSTEM INCLUDING RECTIFIER.

NOC ID:	14184
Facility ID:	87640
AI Number:	39565
Application Received Date:	08/14/2000
Scheduled Construction Date:	08/11/2000
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00814003
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	04/02/2014
Signature Date On Form:	04/02/2014
Signature Name On Form:	DAVID FINBERG
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	46306

STOP N SAVE 3 (Continued) **U001272108**

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	59772
UST ID:	Not reported
NOC ID:	25532
AI Number:	39565
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PETRO-TANK SOLUTIONS
Representative Name:	ANIL MOMIN
Mailing Address (Delivery):	PO BOX 18467
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SUGARLAND
Mailing State:	TX
Mailing Zip:	77407
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	832
Phone Number:	2766144
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	59773
UST ID:	Not reported
NOC ID:	25532
AI Number:	39565
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001326
Company Name:	CITY SURVEY CO
Representative Name:	Not reported
Mailing Address (Delivery):	13013 KATHY LN
Mailing Address (Internal Delivery):	Not reported
Mailing City:	CYPRESS
Mailing State:	TX
Mailing Zip:	77429
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	281
Phone Number:	3774558
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	281
Fax Number:	3774559
Email Address:	Not reported

Cont/Cons/Installer ID:	15227
UST ID:	Not reported
NOC ID:	14184
AI Number:	39565
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000281

STOP N SAVE 3 (Continued) **U001272108**

Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	59774
UST ID:	Not reported
NOC ID:	25532
AI Number:	39565
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000934
Company Name:	MILLER CHRIS ROBERT
Representative Name:	Not reported
Mailing Address (Delivery):	13013 KATHY LN
Mailing Address (Internal Delivery):	Not reported
Mailing City:	CYPRESS
Mailing State:	TX
Mailing Zip:	77429
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	281
Phone Number:	3774558
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BURTON GROCERS INC
Contact Mailing Address (Delivery):	1800 BURTON DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 4266
Phone Number/Ext:	512 4473373/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87640
Additional ID:	554547622002054
Princ ID:	444308192011159
AI Number:	39565
Facility Name:	STOP N SAVE 3
AR Number:	74314

STOP N SAVE 3 (Continued) **U001272108**

AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	SAHIL SOMAIN/

HIST UST AUSTIN:

Name:	STOP-N-SAVE #3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX
Id UST:	1191
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	STOP N SAVE
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/20/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported

STOP N SAVE 3 (Continued) **U001272108**

Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	STOP N SAVE
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

STOP N SAVE 3 (Continued) **U001272108**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Unique TCEQ Ref Number Of Customer:	CN603862509
Unique TCEQ Ref Number Of Reg. Entity:	RN101499796
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	30 TAC Chapter 334, SubChapter A
Regulated Entity Associated With An NOV:	BURTON GROCERS INC
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	1165259
Status Code:	WITHDRAWN

STOP N SAVE 3 (Continued) **U001272108**

Status Date:	05/09/2014
Violation Tracking Number:	195,425,912,014,121.00
Violation Category:	A
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	Not reported
Description 1:	30 TAC 334.10(b)(1)(B) - RECORDS- Failure to maintain legible copies of all required records pertaining to an UST system and make available for inspection by the TCEQ or their UST Contractor.
Description 2:	Not reported
Category of the NOV:	Not reported
Method Of Notice Issuance:	Not reported
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	Not reported
Status Of The NOV:	DAPPROVED
Investigation:	Not reported
Investigation ID:	261407222014121
Regulated Entity ID:	541547592002054
Date of Notice Enforcement:	05/09/2014
Violation Date:	2014-06-09 00:00:00
Rejected:	NO
Type Code:	ADMINORDER
Date Resolved:	10/06/2014
Assessed Amount:	2438
Deferred Amount:	487
Payable Amount:	1951
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	STOP N SAVE 3
Address:	Not reported
City,State,Zip:	TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN101499796
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	11/23/1998
Description 1:	FAILURE TO COMPLY
Description 2:	Not reported
Category of the NOV:	Minor
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	334.7(d)(3)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported

STOP N SAVE 3 (Continued) **U001272108**

Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

TX Financial Assurance 2:

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	243504
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2020
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000008673
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/10/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	157335
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2015
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00091959
Coverage Amount:	1,000,000

STOP N SAVE 3 (Continued) **U001272108**

Coverage Expiration Date:	03/10/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	125840
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2014
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04-TO-00087869
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/10/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	8423
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2013
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00083805
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/10/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640

STOP N SAVE 3 (Continued) **U001272108**

Finass ID:	71236
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2012
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00079951
Coverage Amount:	1000000
Coverage Expiration Date:	03/10/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	71237
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/10/2011
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00077611
Coverage Amount:	1000000
Coverage Expiration Date:	03/10/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	71238
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

STOP N SAVE 3 (Continued) **U001272108**

Financial Assurance Begin Date:	12/18/2009
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 0 0
Policy Number:	G24675245 001
Coverage Amount:	1000000
Coverage Expiration Date:	12/18/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	71239
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/24/2008
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 9873373
Policy Number:	USC851083608
Coverage Amount:	1000000
Coverage Expiration Date:	09/24/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	71240
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/24/2007
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 9873373
Policy Number:	USC851083608
Coverage Amount:	1000000
Coverage Expiration Date:	09/24/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

STOP N SAVE 3 (Continued) **U001272108**

Name:	STOP N SAVE 3
Address:	1800 BURTON DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	87640
Finass ID:	71241
AI:	39565
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	11/21/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

DP1596 **CUNNINGHAM & VOSS** **TX HIST UST** **S111678617**
NNE **218 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.026 mi.
139 ft. **Site 9 of 16 in cluster DP**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CUNNINGHAM & VOSS
Address:	218 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0022
HID UST:	22
Inspection:	Not reported
Due:	06/01/2012

1597 **WASHTUB & PUB COIN OPERATED INDRY** **EDR Hist Cleaner** **1013777794**
NE **1717 PLEASANT VALLEY RD** **N/A**
< 1/8 **TRAVIS (County), TX 78741**
0.026 mi.
139 ft.

Actual:
472 ft.

Focus Map:
15

EDR Hist Cleaner

Year:	Name:	Type:
1990	WASHTUB & PUB COIN OPERATED IND	LAUNDRIES-SELF SERVE
1990	OXFORD CLEANERS DRY CLEANERS	CLEANERS AND DYERS

CX1598 ESE < 1/8 0.026 mi. 139 ft. — **ALL-PRO CLEANERS INC**, **602 W 7TH ST**, **AUSTIN, TX 78701** — **EDR Hist Cleaner** — **1019923670** / **N/A**

Site 2 of 2 in cluster CX

Actual: 499 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1995	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs
1996	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs

DF1599 ESE < 1/8 0.027 mi. 140 ft. — **AUSTIN STEPHEN F HOTEL**, **102 7TH E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013777249** / **N/A**

Site 20 of 25 in cluster DF

Actual: 498 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1929	AUSTIN STEPHEN F HOTEL	LAUNDRIES
1935	AUSTIN STEPHEN F HO	LAUNDRIES

BW1600 East < 1/8 0.027 mi. 140 ft. — **AUSTIN LAUNDRY & DRY**, **608 W 24TH ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013786618** / **N/A**

Site 12 of 12 in cluster BW

Actual: 597 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1965	AUSTIN LAUNDRY & DRY	LAUNDRIES

DN1601 NNE < 1/8 0.027 mi. 140 ft. — **DANNY LITTLE**, **106 E 6TH STREET**, **AUSTIN, TX** — **TX RDR** — **S127536743** / **N/A**

Site 5 of 8 in cluster DN

Actual: 493 ft.

Focus Map: 11

RDR:

RDR ID:	8380
Facility ID:	61542
RN:	Not reported
CN:	Not reported
Name:	DANNY LITTLE
Address:	106 E 6TH STREET
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/1/2000
Due Date:	12/31/2000
Tank Owner:	THOMAS PROPERTIES GROUP
Contact Person:	JOHN S O'NEAL
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/5/2001
Project Manager:	Laurie Daniel

DANNY LITTLE (Continued) **S127536743**

Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	PREVIOUS OWNER, CONNIE LITTLE, DIED AND OWNER CHANGED
Review Coordinator:	LLD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	4/5/2001
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DN1602 **LITTLEFIELD DRISKILL GHOST TANK** **TX LPST** **S109514782**
NNE **106 E 6TH ST** **TX VCP** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX ASBESTOS**
0.027 mi. **TX GCC**
140 ft. **Site 6 of 8 in cluster DN**

Actual:
493 ft.

Focus Map:
11

LPST:

Name:	LITTLEFIELD BUILDING
Address:	106 E 6TH ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	117973
Facility Location:	106 E 6TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/10/2008
Entered Date:	02/10/2009
Reported Date:	01/10/2008
Closure Date:	01/29/2010
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	KJF
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	AUSTIN, TX
Responsible Party Telephone:	/-
Reported Date:	01/10/2008
Case Start Date:	01/29/2010
Reference Number:	RN105527584
Project Manager:	KFROSS

VCP TCEQ:

Name:	LITTLEFIELD DRISKILL GHOST TANK
Address:	106 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2172
VCP Record Date:	05/16/2008
Facility Type:	ABANDONED PROPERTY

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

PCA Number:	34367
Project Manager:	PLALL
Phase:	COMPLETED
Acres at Site:	20 X 50
REM Program:	VCP
RN Number:	RN105527584
Former Facility Type:	Not reported
Site Address Description:	SOUTH END OF THE ALLEY BETWEEN LITTLEFIELD AND DRISKILL BUILDINGS
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	05/16/2008
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/29/2010
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	05/15/2008
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2008-06-30 00:00:00
Soil Target COC Class:	TPH
Surface Water Target COC Class:	TPH
Alternate VCP ID:	2172
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	343670
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	30.27
Longitude:	-97.74

Contact:

REM Program:	VCP
Program ID:	2172
RN Number:	RN105527584
CN Number:	CN603362484
CN Name:	HVP AUSTIN LITTLEFIELD LP
Role Code:	BILLCONT
Contact Name:	KRUMWIEDE, THOMAS
Contact Title:	Not reported
Organization Name:	HVP AUSTIN LITTLEFIELD LP
Mailing Address:	191 N WACKER DR STE 2500

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Mailing City:	CHICAGO
Mailing State:	IL
Mailing Zip:	60606
Contact Telephone:	(312) 423-1370
Contact Telephone Ext:	0

ASBESTOS:

Name:	LITTLEFIELD BUILDING
Address:	106 E. 6TH ST.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	02/22/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013001270
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	03/25/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LITTLEFIELD BUILDING
Address:	106 E. 6TH ST.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	12/11/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013008385
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	12/16/2013
Date Routed by Supervisor:	12/19/2013
Date Routed to PSQA:	12/19/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	LITTLEFIELD BLDG.
Address:	106 E 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/10/2017
Notification Number:	2017008001
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/26/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/26/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GCC:

Name:	ENVIRONMENTAL IMPACT
Address:	106 E 6TH ST
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	Not reported
File Number:	117973
Contamination Description: OTHER	
Date Of Earliest Known Contamination Confirmation:	2/10/2009
Enforcement Status - Level Of Agency Response:	2 - Staff Action

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: ENVIRONMENTAL IMPACT
Address: 106 E 6TH ST
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 117973
Contamination Description: OTHER
Date Of Earliest Known Contamination Confirmation: 2/10/2009
Enforcement Status - Level Of Agency Response: 1A -
Enforcement Status - Site Activity Status: 1A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: ENVIRONMENTAL IMPACT
Address: 106 E 6TH ST
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 117973
Contamination Description: OTHER
Date Of Earliest Known Contamination Confirmation: 2/10/2009
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD DRISKILL GHOST TANK
Address: 106 E 6TH ST
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 2172

LITTLEFIELD DRISKILL GHOST TANK (Continued) **S109514782**

Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 5/16/2008
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: LITTLEFIELD DRISKILL GHOST TANK
Address: 106 E 6TH ST
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 2172
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 5/16/2008
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

DN1603 **LITTLEFIELD BUILDING** **TX HIST UST** **S128729162**
NNE **106 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
140 ft. **Site 7 of 8 in cluster DN**

Actual:
493 ft.

Focus Map:
11

HIST UST AUSTIN:
Name: LITTLEFIELD BUILDING
Address: 106 E 6TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0012
HID UST: 12
Inspection: 10/20/2010
Due: 10/20/2013

DN1604 NNE < 1/8 0.027 mi. 140 ft. — **LITTLEFIELD BLDING IN ALLEY**, **106 E 6TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S128728731** / **N/A**

Site 8 of 8 in cluster DN

Actual: 493 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	LITTLEFIELD BLDING IN ALLEY
Address:	106 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	3326
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FT1605 WNW < 1/8 0.027 mi. 140 ft. — **BROWN & ELLIOTT INC**, **2326 S CONGRESS**, **AUSTIN, TX 78767** — **EDR Hist Cleaner** — **1019944165** / **N/A**

Site 15 of 15 in cluster FT

Actual: 598 ft.
Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1969	BROWN & ELLIOTT ONE HR MRTNANG	Drycleaning Plants, Except Rugs
1970	BROWN & ELLIOTT INC	Drycleaning Plants, Except Rugs
1971	BROWN & ELLIOTT INC	Drycleaning Plants, Except Rugs

IR1606 SW < 1/8 0.027 mi. 140 ft. — **COPELAND GARAGE**, **514 43RD ST W**, **TRAVIS (County), TX 78751** — **EDR Hist Auto** — **1013760036** / **N/A**

Site 5 of 7 in cluster IR

Actual: 622 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1970	COPELAND GARAGE	AUTOMOBILE REPAIRING

IR1607 SW < 1/8 0.027 mi. 140 ft. — **MURRAYS GAR AUTO**, **514 43RD W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013776050** / **N/A**

Site 6 of 7 in cluster IR

Actual: 622 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1962	MURRAYS GAR AUTO	AUTOMOBILE REPAIRING

IR1608 SW < 1/8 0.027 mi. 140 ft. — **HYDE PARK GARAGE**, **514 43RD ST W**, **AUSTIN, TX 78751** — **EDR Hist Auto** — **1013757393** / **N/A**

Site 7 of 7 in cluster IR

Actual: 622 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1980	HYDE PARK GARAGE	AUTOMOBILE REPAIRING

IX1609 WNW < 1/8 0.027 mi. 140 ft. — **J.V. SIEGMUND**, **228 S CONGRESS AVE**, **AUSTIN, TX** — **TX HIST UST** — **S111678697** / **N/A**

Site 5 of 6 in cluster IX

Actual: 440 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	J.V. SIEGMUND
Address:	228 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0309
HID UST:	309
Inspection:	04/24/2009
Due:	04/24/2012

IX1610 WNW < 1/8 0.027 mi. 140 ft. — **LACKIE CONSTRUCTION**, **228 S CONGRESS AVE**, **AUSTIN, TX** — **TX HIST UST** — **S111678719** / **N/A**

Site 6 of 6 in cluster IX

Actual: 440 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	LACKIE CONSTRUCTION
Address:	228 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0509
HID UST:	509
Inspection:	04/24/2009
Due:	04/24/2012

1611 NE < 1/8 0.027 mi. 140 ft. — **METROLOGY LABORATORY**, **119 CUMBERLAND RD**, **AUSTIN, TX 78704** — **TX Ind. Haz Waste** — **S104854711** / **N/A**

Actual: 604 ft.

Focus Map: 14

Ind. Haz Waste:

Name:	METROLOGY LABORATORY
Address:	119 CUMBERLAND RD
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	75088
Registration Initial Notification Date:	01/04/1990
Registration Last Amendment Date:	07/27/2001

METROLOGY LABORATORY (Continued) **S104854711**

EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19900104
Land Type:	Not reported
Description of Facility Site Location:	119 Cumberland Rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF AGRICULTURE
Contact Name:	JAMES H ESKEW
Contact Telephone Number:	512-4621441
Mailing Address:	119 CUMBERLAND RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787045412
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29443
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040423
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF AGRICULTURE
Operator Address:	119 CUMBERLAND RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4621441
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

METROLOGY LABORATORY (Continued) **S104854711**

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF AGRICULTURE
Owner Mailing Address:	119 CUMBERLAND RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4621441
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	119 CUMBERLAND RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4621441
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	119 CUMBERLAND RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4621441
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JAMES ESKEW
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	119 CUMBERLAND RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4621441
Contact Fax:	Not reported
Contact Email:	Not reported

EE1612 **ACME CLEANERS** **EDR Hist Cleaner** **1013781211**
WNW **320 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
141 ft. **Site 4 of 4 in cluster EE**

Actual:
470 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1940	ACME CLEANERS CLDO	CLOTHES PRESSERS AND CLEANERS
1947	ACME CLEANERS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1953	ACME CLEANERS	CLEANERS AND DYERS
1958	SASSMAN CLNS	CLEANERS AND DYERS

DA1613 **AUSTIN LACQUER COMPANY AUTO PAINT & BODY SPECIALIS** **EDR Hist Auto** **1013774390**
ESE **604 W 6TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.027 mi.
141 ft. **Site 20 of 25 in cluster DA**

Actual:
481 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1969	PIT STOP INC	General Automotive Repair Shops
1970	AUSTIN LACQUER COMPANY AUTO PAI	AUTOMOBILE REPAIRING
1970	PIT STOP INC	General Automotive Repair Shops
1987	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1988	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1988	VARLIE & CHICKIE INC	General Automotive Repair Shops
1989	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1989	VARLIE & CHICKIE INC	General Automotive Repair Shops
1990	VARLIE & CHICKIE INC	General Automotive Repair Shops
1990	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1991	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1992	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1993	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1994	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1995	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1995	VARLIE & CHICKIE INC	General Automotive Repair Shops
1996	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1997	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1998	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
1999	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
2000	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
2001	C VAN R AUTOMOTIVE SERVICE	General Automotive Repair Shops
2006	VARLIE & CHICKIE INC	General Automotive Repair Shops
2007	VARLIE & CHICKIE INC	General Automotive Repair Shops
2008	VARLIE & CHICKIE INC	General Automotive Repair Shops
2009	VARLIE & CHICKIE INC	General Automotive Repair Shops
2010	VARLIE & CHICKIE INC	General Automotive Repair Shops
2011	VARLIE & CHICKIE INC	General Automotive Repair Shops
2012	VARLIE & CHICKIE INC	General Automotive Repair Shops

DA1614 **C VAN R AUTOMOTIVE** **TX ASBESTOS** **S102752138**
ESE **604 W 6TH ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX CENTRAL REGISTRY**
0.027 mi.
141 ft. **Site 21 of 25 in cluster DA**

Actual:
481 ft.

Focus Map:
11

ASBESTOS:

Name:	AUTO REPAIR SHOP STRUCTURE AT THE 604 WEST 6TH STREET
Address:	604 WEST 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	05/22/2018
Notification Number:	2018003697
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/08/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/22/2018
Client Code:	Not reported
Client Name:	Not reported

C VAN R AUTOMOTIVE (Continued) **S102752138**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	C VAN R AUTOMOTIVE
Address:	604 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	69471
Registration Initial Notification Date:	03/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19860307
Land Type:	Not reported
Description of Facility Site Location:	604 W 6th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	C VAN R AUTOMOTIVE
Contact Name:	CHARLES FOWLER
Contact Telephone Number:	512-4785998
Mailing Address:	604 W 6TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787012706
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24348
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031103

C VAN R AUTOMOTIVE (Continued) **S102752138**

Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	C VAN R AUTOMOTIVE
Operator Address:	604 W 6THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4785998
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	C VAN R AUTOMOTIVE
Owner Mailing Address:	604 W 6THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4785998
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	604 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4785998
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON

C VAN R AUTOMOTIVE (Continued) **S102752138**

Contact Address:	604 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4785998
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	CHARLES FOWLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	604 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4785998
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100658244
Name:	C VAN R AUTOMOTIVE
Address:	604 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2706
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600367221
Customer Name:	C VAN R AUTOMOTIVE
Customer Legal Name:	C Van R Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	604 W 6th St, Austin, TX

JI1615 **GULF REFG CO STA NO** **EDR Hist Auto** **1013760504**
ESE **1811 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
141 ft. **Site 2 of 3 in cluster JI**

Actual: EDR Hist Auto
536 ft.

Focus Map:
11

Year:	Name:	Type:
1929	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS

1616
SSW
< 1/8
0.027 mi.
141 ft.

422 E 6TH ST
AUSTIN, TX

TX HIST UST **S111678406**
N/A

Actual:
486 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	422 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0122
HID UST:	122
Inspection:	Not reported
Due:	06/01/2012

DB1617
WNW
< 1/8
0.027 mi.
142 ft.

OHENRY GAR
110 8TH E
AUSTIN, TX

Site 10 of 11 in cluster DB

EDR Hist Auto **1013770987**
N/A

Actual:
502 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	110 12 TEXAN GARAGE	AUTOMOBILE GARAGES
1940	OHENRY GAR	AUTOMOBILE GARAGES

FJ1618
ENE
< 1/8
0.027 mi.
142 ft.

SPICK SPAN LAUNDRY
1421 ARENA DR
TRAVIS (County), TX 78741

Site 3 of 3 in cluster FJ

EDR Hist Cleaner **1013779715**
N/A

Actual:
466 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1970	SPICK SPAN LAUNDRY	LAUNDRIES
1975	SPICK SPAN LAUNDRY COIN OPERATE	LAUNDRIES AND DRY CLEANERS
1980	SPICK SPAN LAUNDRY COIN OPERATE	LAUNDRIES AND DRY CLEANERS

DF1619
WNW
< 1/8
0.027 mi.
142 ft.

CASH AND CARRY
111 7TH E
AUSTIN, TX

Site 21 of 25 in cluster DF

EDR Hist Cleaner **1013786705**
N/A

Actual:
497 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1922	DRISKILL HOTEL LAUNDRY	LAUNDRIES
1929	CASH & CARRY CLEANERS	CLOTHES CLEANERS AND PRESSERS
1935	CASH & CARRY	CLOTHES PRESSERS AND CLEANERS
1940	CASH AND CARRY	CLOTHES PRESSERS AND CLEANERS
1947	MASTER VALET SERVICE CLO CLNR	CLOTHES PRESSERS AND CLEANERS
1953	MASTER VALET SER	CLEANERS AND DYERS

1620 WNW < 1/8 0.027 mi. 142 ft. | **A. E. SULLIVAN**
400 W MONROE ST
AUSTIN, TX | **TX HIST UST** | **S111678536**
N/A

Actual: 507 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	A. E. SULLIVAN
Address:	400 W MONROE ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0202
HID UST:	202
Inspection:	Not reported
Due:	06/01/2012

JG1621 ESE < 1/8 0.027 mi. 142 ft. | **KWIK WASH LAUNDRY**
718 LAMAR PL
TRAVIS (County), TX 78757
Site 2 of 3 in cluster JG | **EDR Hist Cleaner** | **1013778055**
N/A

Actual: 713 ft.
Focus Map: 6

EDR Hist Cleaner

Year:	Name:	Type:
1975	KWIK WASH LAUNDRY	LAUNDRIES-SELF SERVE
1980	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE
1984	KWIK WASH COIN LAUNDRIES NO	LAUNDRIES-SELF SERVE

JT1622 WNW < 1/8 0.027 mi. 142 ft. | **YOUNG & PRATT**
702 E 3RD ST
AUSTIN, TX 78701
Site 1 of 3 in cluster JT | **TX UST**
TX ASBESTOS | **U001257301**
N/A

Actual: 459 ft.
Focus Map: 11

UST:

Name:	YOUNG & PRATT
Address:	702 E 3RD ST
City,State,Zip:	AUSTIN, TX 787014668
AI Number:	22893
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/23/1986
Facility Status:	INACTIVE
Additional ID:	775576292002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	G L RANDLE,VICE PRES
Contact Organization Name:	YOUNG & PRATT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

YOUNG & PRATT (Continued) **U001257301**

Contact Telephone:	5124726858
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/09/1986
Signature Name/Title On Earliest Reg Form:	G L RANDLE,VICE PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600779730
Owner Last Name:	YOUNG & PRATT INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765576282002053
Additional ID:	775576292002053
AI Number:	22893
Owner Effective Begin Date:	09/23/1986
State Tax ID:	17417395658
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	58470
Facility ID:	59427
Ai Number:	22893
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/05/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

YOUNG & PRATT (Continued) **U001257301**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	55335
UST ID:	58470
AI Number:	22893
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

YOUNG & PRATT (Continued) **U001257301**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8686
Cert ID:	167147
UST Comprt ID:	482357
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167149
UST Comprt ID:	482355
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167146
UST Comprt ID:	482358
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167148

YOUNG & PRATT (Continued) **U001257301**

UST Comprt ID:	482356
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167143
UST Comprt ID:	482359
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167145
UST Comprt ID:	482361
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	8686
Cert ID:	167144
UST Comprt ID:	482360
UST ID:	154813
AI Number:	22893
Tank ID:	3A
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	YOUNG & PRATT INC
Contact Mailing Address (Delivery):	PO BOX 957
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 0957
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	59427
Additional ID:	775576292002053
Princ ID:	765576282002053
AI Number:	22893
Facility Name:	YOUNG & PRATT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

ASBESTOS:

Name:	BLOCK 36 DEVELOPMENT
Address:	702 E. 3RD STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/01/2019

YOUNG & PRATT (Continued) **U001257301**

Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	10/04/2018
Notification Number:	2018007081
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/26/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/26/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	10/04/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

YOUNG & PRATT (Continued) **U001257301**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	BLOCK 36 DEVELOPMENT
Address:	702 E. 3RD STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/01/2019
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	10/01/2018
Notification Number:	2018007081
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/14/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/14/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI

YOUNG & PRATT (Continued) **U001257301**

Analytical Method:	PLM
Start Date:	10/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BLOCK 36 DEVELOPMENT
Address:	702 E. 3RD STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/10/04
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

YOUNG & PRATT (Continued) **U001257301**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	10/04/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018007081
File Number:	34470
License Status Description:	Paid
Expiration Date:	10/04/2018
Original Date:	09/14/2018
Rank Effective Date:	09/14/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	12052
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

JT1623 **C. G. PURYEAR** **TX HIST UST** **S128729402**
WNW **702 E 3RD ST** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
142 ft. **Site 2 of 3 in cluster JT**

Actual:
459 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	C. G. PURYEAR
Address:	702 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0736
HID UST:	736
Inspection:	Not reported
Due:	06/01/2012

JT1624 WNW < 1/8 0.027 mi. 142 ft. | **YOUNG & PRATT 702 E 3RD ST AUSTIN, TX** | **TX HIST UST** | **S128728904 N/A**

Site 3 of 3 in cluster JT

Actual: 459 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	YOUNG & PRATT
Address:	702 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0105
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CZ1625 WNW < 1/8 0.027 mi. 142 ft. | **PAGE SOUTHERLAND PAGE 606 WEST AVE AUSTIN, TX 78701** | **RCRA NonGen / NLR FINDS ECHO TX Ind. Haz Waste** | **1000470046 TXD988019295**

Site 6 of 9 in cluster CZ

Actual: 464 ft.
Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20011030
Handler Name:	Page Southerland Page
Handler Address:	WEST AVE
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD988019295
Contact Name:	CHRIS DEVILLIE
Contact Address:	PO BOX 2004
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Telephone:	512-472-6721
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2004
Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Name:	Page Southerland Page
Owner Type:	Private
Operator Name:	Page Southerland Page
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

PAGE SOUTHERLAND PAGE (Continued) **1000470046**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAGE SOUTHERLAND PAGE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: PAGE SOUTHERLAND PAGE	
Legal Status:	Private
Date Became Current:	20011030
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2004
Owner/Operator City,State,Zip:	AUSTIN, TX 78768

PAGE SOUTHERLAND PAGE (Continued) **1000470046**

Owner/Operator Telephone: 512-472-6721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PAGE SOUTHERLAND PAGE
Legal Status: Private
Date Became Current: 20011030
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2004
Owner/Operator City,State,Zip: AUSTIN, TX 78768
Owner/Operator Telephone: 512-472-6721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19901017
Handler Name: PAGE SOUTHERLAND PAGE
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011030
Handler Name: PAGE SOUTHERLAND PAGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

PAGE SOUTHERLAND PAGE (Continued) **1000470046**

FINDS:
Registry ID: 110005124070

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000470046
Registry ID:	110005124070
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005124070
Name:	PAGE SOUTHERLAND PAGE
Address:	606 WEST AVE
City,State,Zip:	AUSTIN, TX 78701

Ind. Haz Waste:

Name:	PAGE SOUTHERLAND PAGE
Address:	606 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	75295
Registration Initial Notification Date:	04/04/1991
Registration Last Amendment Date:	10/30/2001
EPA Identification:	TXD988019295
Primary NAICS Code:	Not reported
Status Change Date:	19910404
Land Type:	PRIVATE
Description of Facility Site Location:	606 West Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	PAGE SOUTHERLAND PAGE
Contact Name:	CHRIS DEVILLIE
Contact Telephone Number:	512-4726721
Mailing Address:	PO BOX 2004
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787682004
Mailing County:	UNITED STATES

PAGE SOUTHERLAND PAGE (Continued) **1000470046**

Facility Country:	UNITED STATES
TNRCC Facility ID:	29648
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	PAGE SOUTHERLAND PAGE
Operator Address:	PO BOX 2004
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78768
Operator Country:	UNITED STA
Operator Telephone:	1-512-4726721
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	PAGE SOUTHERLAND PAGE
Owner Mailing Address:	PO BOX 2004
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Country:	UNITED STA
Owner Telephone:	1-512-4726721
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2004
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4726721

PAGE SOUTHERLAND PAGE (Continued) **1000470046**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2004
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4726721
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	CHRIS DEVILLIE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2004
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4726721
Contact Fax:	Not reported
Contact Email:	Not reported

DR1626 **STEVENSON J C C DCLO CLNR** **EDR Hist Cleaner** **1013782356**
NE **510 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
143 ft. **Site 30 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	STEVENSON J C C DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

DR1627 **AXLE & WHEEL ALIGN** **EDR Hist Auto** **1013756142**
NE **510 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
143 ft. **Site 31 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	AUSTIN BODY WKS	AUTOMOBILE REPAIRING
1940	AXLE & WHEEL ALIGN	AUTOMOBILE REPAIRING
1947	AXLE & WHEEL ALIGNING SERVICE A	AUTOMOBILE REPAIRING

DR1628 NE < 1/8 0.027 mi. 143 ft. | **VACANT 2 CASTROS CLEANERS** | **EDR Hist Cleaner** | **1013786384** **N/A**
511 6TH ST E
AUSTIN, TX 78701

Site 32 of 38 in cluster DR

Actual: 484 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1980	VACANT 2 CASTROS CLEANERS	CLEANERS AND DYERS

DC1629 WNW < 1/8 0.027 mi. 143 ft. | **803 05 DEPENDABLE MTRS** | **EDR Hist Auto** | **1013755906** **N/A**
803 5TH W
AUSTIN, TX

Site 6 of 11 in cluster DC

Actual: 463 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	803 05 DEPENDABLE MTRS	AUTOMOBILE REPAIRING

DC1630 WNW < 1/8 0.027 mi. 143 ft. | **DEPENDABLE MOTORS INC AUTO** | **EDR Hist Auto** | **1013763106** **N/A**
803 5TH ST W
AUSTIN, TX

Site 7 of 11 in cluster DC

Actual: 463 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	DEPENDABLE MOTORS INC AUTO	AUTOMOBILE REPAIRING

1631 WNW < 1/8 0.027 mi. 144 ft. | **BOZEMAN & HAGOOD SERVICE STATION** | **EDR Hist Auto** | **1013765556** **N/A**
1811 CONGRESS AVE
AUSTIN, TX

Actual: 532 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1940	PILAND A C FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	BOZEMAN & HAGOOD SERVICE STATIO	GASOLINE AND OIL SERVICE STATIONS
1953	BOZEMAN GULF SER	GASOLINE STATIONS
1958	BOZEMAN GULF SERV	GASOLINE STATIONS
1962	BOZEMAN GULF	GASOLINE STATIONS

CO1632	**AUSTIN COMMUNITY COLLEGE**	**TX LPST**	**1000412181**
WNW	**1212 RIO GRANDE ST**	**RCRA NonGen / NLR**	**TXD980878078**
< 1/8	**AUSTIN, TX 78701**	**FINDS**	
0.027 mi.		**ECHO**	
144 ft.	**Site 4 of 4 in cluster CO**	**TX Ind. Haz Waste**	
Actual:		**TX IHW CORR ACTION**	
513 ft.		**TX CENTRAL REGISTRY**	

Focus Map:
11

LPST:

Name:	ACC RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	113790
Facility Location:	1212 RIO GRANDE ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/13/1998
Entered Date:	12/08/1998
Reported Date:	11/13/1998
Closure Date:	01/10/2007
Priority:	2.2 - FORMER VAPOR IMPACT/NAPL NEAR UTILITY POTENTL VAPOR PTHWY
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	A former vapor impact is associated with this site, or NAPL is present in close proximity to subsurface utilities or other natural or man-made conduit and there is potential for the accumulation of explosive vapors or vapors that could cause acute effects in a building or other structure.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1P/1P/1
Coordinators RPR:	TH2
Responsible Party Name:	Not reported
Responsible Party Contact:	BECKY COLE
Responsible Party Address:	9101 TUSCANY WAY
Responsible Party City,St,Zip:	AUSTIN, TX 78754
Responsible Party Telephone:	/-
Reported Date:	11/13/1998
Case Start Date:	01/10/2007
Reference Number:	RN100558378
Project Manager:	THASAN

RCRA Listings:

Date Form Received by Agency:	20171122
Handler Name:	Austin Community College
Handler Address:	1212 RIO GRANDE ST
Handler City,State,Zip:	AUSTIN, TX 78701-1710
EPA ID:	TXD980878078
Contact Name:	BECKY COLE
Contact Address:	9101 TUSCANY WAY
Contact City,State,Zip:	AUSTIN, TX 78754-4700
Contact Telephone:	512-223-7000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	9101 TUSCANY WAY
Mailing City,State,Zip:	AUSTIN, TX 78754-4700
Owner Name:	Austin Community College
Owner Type:	Private
Operator Name:	Austin Community College
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171221
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE	
Legal Status:	Municipal
Date Became Current:	20081209
Date Ended Current:	Not reported
Owner/Operator Address:	5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-223-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE,	
Legal Status:	Municipal
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752-4390
Owner/Operator Telephone:	512-223-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE	
Legal Status:	Municipal
Date Became Current:	20120616
Date Ended Current:	Not reported
Owner/Operator Address:	5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-223-7000

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20080902
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20100706
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20100706
Date Ended Current: Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE,
Legal Status: Municipal
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4390
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20100323
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE,

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Legal Status: Municipal
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4390
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20060801
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20080902
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20090804
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20060801
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20060801
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20090804
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20081209
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20100323
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20120616
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Municipal
Date Became Current: 20060801
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE,
Legal Status: Municipal
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4390
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 5930 MIDDLE FISKVILLE RD
Owner/Operator City,State,Zip: AUSTIN, TX 78752-4341
Owner/Operator Telephone: 512-223-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19840820
Handler Name: AUSTIN COMMUNITY COLLEGE--RIO GRANDE

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010214
Handler Name:	AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060804
Handler Name:	AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060825
Handler Name:	AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20080902
Handler Name:	AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081209
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090804
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100323
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100706
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Receive Date: 20101222
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110112
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120616
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160303
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160303
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20171122
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20171122
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61121
NAICS Description: JUNIOR COLLEGES

NAICS Code: 61131
NAICS Description: COLLEGES, UNIVERSITIES, AND PROFESSIONAL SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005081277

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412181
Registry ID:	110005081277
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005081277
Name:	AUSTIN COMMUNITY COLLEGE
Address:	1212 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701

Ind. Haz Waste:

Name:	AUSTIN COMMUNITY COLLEGE
Address:	1212 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	66189
Registration Initial Notification Date:	08/17/1984
Registration Last Amendment Date:	11/22/2017
EPA Identification:	TXD980878078
Primary NAICS Code:	611210
Status Change Date:	20160311
Land Type:	PRIVATE
Description of Facility Site Location:	1212 RIO GRANDE STREET AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN COMMUNITY COLLEGE
Contact Name:	BECKY COLE
Contact Telephone Number:	512-2237000
Mailing Address:	9101 TUSCANY WAY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787544700
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21485
Site Owner Tax ID:	741742036
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20171127
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN COMMUNITY COLLEGE
Operator Address:	5930 MIDDLE FISKVILLE RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-2237000
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

One-time Shipper ID:	41006
Location Description:	Not reported
Broker Name:	GRUENE ENVIRONMENTAL COMPANIES LLC
Broker Telephone:	830-626-7575 x131
Date Processing Complete:	20191016
Date Request Sent:	20191016
Company Name:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACIL
Waste ID:	G96N319H
Waste Form Code:	319
Waste Class Code:	H
Waste Origin Code:	2
Site Name:	AUSTIN COMMUNITY COLLEGE RGC
Location Address:	Not reported
Location City:	Not reported
Location Zip:	Not reported
Site Region Code:	Not reported
EPA Waste Source Code:	G19
EPA ID:	TXD980878078
EPA System Type Code:	Not reported
Land Site Type:	OTHER
EPA Form:	W319
Site County Fips:	Not reported
EPA Waste Number:	LEAD
Location County:	Not reported
Contact Name or Organization:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY
Owner Address:	5930 MIDDLE FISKVILLE RD
Owner City,State,Zip:	AUSTIN, TX 78752
Owner County Code:	USA
Owner Telephone:	512-223-7020
Owner Fax:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner NAICS:	611210
Broker Mailing Address:	11 NAFTA CIR
Broker City,State,Zip:	NEW BRAUNFELS, TX 78132
Broker Mailing County:	USA
Broker Fax:	830-626-7576
NAICS Code:	611310
TWC ID:	413534
One-time Shipper ID:	39499
Location Description:	Not reported
Broker Name:	Not reported
Broker Telephone:	Not reported
Date Processing Complete:	20170601
Date Request Sent:	20170601
Company Name:	AUSTIN COMMUNITY COLLEGE
Waste ID:	G4N6003H
Waste Form Code:	003
Waste Class Code:	H
Waste Origin Code:	1
Site Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Location Address:	1212 RIO GRANDE ST
Location City:	AUSTIN
Location Zip:	78701
Site Region Code:	11
EPA Waste Source Code:	G11
EPA ID:	TXD980878078
EPA System Type Code:	Not reported
Land Site Type:	PRIVATE
EPA Form:	W001
Site County Fips:	453
EPA Waste Number:	CHEM
Location County:	TRAVIS
Contact Name or Organization:	AUSTIN COMMUNITY COLLEGE
Owner Address:	9101 TUSCANY WAY
Owner City,State,Zip:	AUSTIN, TX 78754
Owner County Code:	USA
Owner Telephone:	512-223-1015
Owner Fax:	512-223-1035
Owner NAICS:	611210
Broker Mailing Address:	Not reported
Broker City,State,Zip:	Not reported
Broker Mailing County:	Not reported
Broker Fax:	Not reported
NAICS Code:	611210
TWC ID:	392803

Ind. Haz Waste:

Owner Name:	AUSTIN COMMUNITY COLLEGE
Owner Mailing Address:	5930 MIDDLE FISKVILLE RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-2237000
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	5930 MIDDLE FISKVILLE RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-2237000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	5930 MIDDLE FISKVILLE RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-2237000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BECKY COLE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	9101 TUSCANY WAY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78754
Contact Phone:	1-512-2237000
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	68169
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Classroom waste in chemistry dept. of college
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68170
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Laboratory waste from chemistry dept. at college
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste ID:	246367
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010113H
Waste Code Status:	INACTIVE
Waste Form:	113
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wash water contaminated with chips of lead paint from power washing concrete wal
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	LEAD PAINT CHIPS
Primary NAICS Code:	611210
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228383
Texas Waste Code:	Not reported
Texas Waste Code 2:	08010031
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab Packs of non-regulated, non-hazardous chemicals and specimens; Initial waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ LAB PACK
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	228384
Texas Waste Code:	Not reported
Texas Waste Code 2:	0802003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab Packs of spent laboratory chemicals
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HAZ LAB PACKS
Primary NAICS Code:	611210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228385
Texas Waste Code:	Not reported
Texas Waste Code 2:	0803409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Rags contaminated with petroleum distillates from art print shop solvents
Standard Industrial Code:	Not reported
Primary Source:	G04
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PRINT SHOP RAGS
Primary NAICS Code:	611210
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste ID:	228386
Texas Waste Code:	Not reported
Texas Waste Code 2:	08046031
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oil and water liquid from elevator pit clean out; Initial waste code determinati
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ELEV PIT OILY WATER
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	229627
Texas Waste Code:	Not reported
Texas Waste Code 2:	08064091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab specimens: fetal pigs, cats; A new hazardous waste determination has been pe
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Waste ID:	235178
Texas Waste Code:	Not reported
Texas Waste Code 2:	0901103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Generators Waste Description:	Aqeuous acidic wastes from educational chemistry lab experiments
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ORGANIC ACID SOL
Primary NAICS Code:	611210
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	235179
Texas Waste Code:	Not reported
Texas Waste Code 2:	0902101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous heavy metal waste from educational chemistry lab experiments
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HEAVY METAL EXP
Primary NAICS Code:	611210
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	235180
Texas Waste Code:	Not reported
Texas Waste Code 2:	0903202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Generators Waste Description:	Spent halogenated and non-halogenated corrosive wastes from educational chemistr
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT LAB CHEMICALS
Primary NAICS Code:	611210
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	235181
Texas Waste Code:	Not reported
Texas Waste Code 2:	0904119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Potassium permanganate solution from educational chemistry lab
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	KMNO4 WASTE
Primary NAICS Code:	621210
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	235182
Texas Waste Code:	Not reported
Texas Waste Code 2:	0905003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Generators Waste Description:	Spent or out of date inorganic mercury compounds
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MERCURY COMPOUNDS
Primary NAICS Code:	621210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	243646
Texas Waste Code:	Not reported
Texas Waste Code 2:	09104091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-hazardous paper, plastic, debris from college chemistry lab experiments; Ini
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ SOLID WASTE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	249382
Texas Waste Code:	Not reported
Texas Waste Code 2:	20103091
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent lead acid batteries for recycle; Hazardous waste currently being managed u
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PB ACID BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	249383
Texas Waste Code:	Not reported
Texas Waste Code 2:	20113091
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent lithium batteries for recycle; Initial waste code determination used in in
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	LITHIUM BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	249384
Texas Waste Code:	Not reported
Texas Waste Code 2:	20123091
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent nickel cadmium batteries for recycle; Initial waste code determination use
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	NICD BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Ind. Haz Waste:

Waste ID:	249385
Texas Waste Code:	Not reported
Texas Waste Code 2:	20133091
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	spent alkaline batteries for incineration; Hazardous waste currently being manag
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ALKALINE BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Waste ID:	249386
Texas Waste Code:	Not reported
Texas Waste Code 2:	20143191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Fluorescent tubes for mercury recovery; Hazardous waste currently being managed
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLUORESCENT TUBES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Waste ID:	249387
Texas Waste Code:	Not reported
Texas Waste Code 2:	2015316H
Waste Code Status:	INACTIVE
Waste Form:	316

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury debris sent for retort
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MERCURY DEBRIS
Primary NAICS Code:	611210
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	249388
Texas Waste Code:	Not reported
Texas Waste Code 2:	2016219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent aerosol cans for incineration
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT AEROSOL CANS
Primary NAICS Code:	611210
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	249389
Texas Waste Code:	Not reported
Texas Waste Code 2:	2017319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury for retort
Standard Industrial Code:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MERCURY
Primary NAICS Code:	611210
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	249390
Texas Waste Code:	Not reported
Texas Waste Code 2:	20182091
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	waste latex paint; Initial waste code determination used in incorrect form and/o
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	LATEX PAINT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Ind. Haz Waste:

Waste ID:	262385
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4XP204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262386
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4XQ003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	263716
Texas Waste Code:	Not reported
Texas Waste Code 2:	C6HS0011
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	392803
Texas Waste Code:	Not reported
Texas Waste Code 2:	G4N6003H
Waste Code Status:	INACTIVE

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CHEMISTRY AND BIOLOGY LAB CHEMICALS FROM CAMPUS CLOSURE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	BECKY COLE
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9101 TUSCANY WAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78754
AR Number:	0000314183
Principal Name:	AUSTIN COMMUNITY COLLEGE
Attention Name:	COLE ,BECKY
Attention Suffix:	HWG

Contact Name:	BECKY COLE
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	9101 TUSCANY WAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78754
AR Number:	0000314183
Principal Name:	AUSTIN COMMUNITY COLLEGE
Attention Name:	COLE ,BECKY
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	UST NEAR PEDESTRIAN TUNNEL
Address:	1212 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	66189
Location Desc:	1212 Rio Grande Street, Austin, TX
RN NUM:	RN100558378
Status:	INACTIVE
Status Date:	10/29/2004
EDR Link ID:	66189
Project Phase:	TRANSFERRED
Phase Status Date:	10/29/2004
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	###########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605711902
Customer Name:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY CORPORATION
Customer Legal Name:	Austin Community College District Public Facility Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/16/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605711902
Customer Name:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY CORPORATION
Customer Legal Name:	Austin Community College District Public Facility Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/16/2019
Affiliation End Date:	12/31/3000

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605711902
Customer Name:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY CORPORATION
Customer Legal Name:	Austin Community College District Public Facility Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/16/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Regulated Entity Number:	RN100558378
Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Physical Location Description: 1212 Rio Grande Street, Austin, TX

Regulated Entity Number: RN100558378
Name: AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address: 1212 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1710
Status: ACTIVE
Status Date: ##########
Customer Number: CN600269211
Customer Name: AUSTIN COMMUNITY COLLEGE
Customer Legal Name: Austin Community College
Customer Ownership Type: OTHER GOVERNMENT
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 611210
Primary NAICS Industry Type Description: Junior Colleges
Physical Location Description: 1212 Rio Grande Street, Austin, TX

Regulated Entity Number: RN100558378
Name: AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address: 1212 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1710
Status: ACTIVE
Status Date: ##########
Customer Number: CN600269211
Customer Name: AUSTIN COMMUNITY COLLEGE
Customer Legal Name: Austin Community College
Customer Ownership Type: OTHER GOVERNMENT
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 611210
Primary NAICS Industry Type Description: Junior Colleges
Physical Location Description: 1212 Rio Grande Street, Austin, TX

Regulated Entity Number: RN100558378
Name: AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address: 1212 RIO GRANDE ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1710
Status: ACTIVE
Status Date: ##########
Customer Number: CN605711902
Customer Name: AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY CORPORATION
Customer Legal Name: Austin Community College District Public Facility Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 10/16/2019
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 611210
Primary NAICS Industry Type Description: Junior Colleges
Physical Location Description: 1212 Rio Grande Street, Austin, TX

Regulated Entity Number: RN100558378

AUSTIN COMMUNITY COLLEGE (Continued) **1000412181**

Name:	AUSTIN COMMUNITY COLLEGE RIO GRANDE CAMPUS
Address:	1212 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1710
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605711902
Customer Name:	AUSTIN COMMUNITY COLLEGE DISTRICT PUBLIC FACILITY CORPORATION
Customer Legal Name:	Austin Community College District Public Facility Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/16/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611210
Primary NAICS Industry Type Description:	Junior Colleges
Physical Location Description:	1212 Rio Grande Street, Austin, TX

Click this hyperlink while viewing on your computer to access
8 additional TX CENTRAL REG: record(s) in the EDR Site Report.

JU1633 **GUTHRIE CLEANERS** **TX DRYCLEANERS** **S109361000**
WNW **9200 N LAMAR BLVD STE 108** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.027 mi.
144 ft. **Site 1 of 2 in cluster JU**

Actual:
682 ft.

Focus Map:
6

DRYCLEANERS:

Name:	GUTHRIE CLEANERS
Address:	9200 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN104090733
Region:	11
CN Number:	CN602527186
DCR Number:	Not reported
AR Number:	24001877
Principal Name:	GWG ENTERPRISES INC
Bill Addr1:	307 FARLEY ST
Bill Addr2:	Not reported
Bill City/State/Zip:	HUTTO, TX 78634 4325
EMail:	Not reported
Phone Number:	Not reported
Site Name:	GUTHRIE CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

JU1634 **GUTHRIES CLEANERS** **EDR Hist Cleaner** **1013783511**
WNW **9200 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.027 mi.
144 ft. **Site 2 of 2 in cluster JU**

Actual:
682 ft.

Focus Map:
6

EDR Hist Cleaner

Year:	Name:	Type:
1988	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1989	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1990	GUTHRIES CLEANERS	CLEANERS AND DYERS
1990	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1991	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1992	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1993	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1994	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1995	GUTHERIE CLEANERS	Drycleaning Plants, Except Rugs
1996	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
1997	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
1998	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
1999	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
2000	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
2001	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
2002	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs
2003	GUTHRIE CLEANERS	Drycleaning Plants, Except Rugs

IV1635 **THE UNIVERSITY OF TEXAS MAIN CAMPUS** **TX SPILLS** **S103606340**
East **2617 SPEEDWAY STE 104** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78712**
0.027 mi.
144 ft. **Site 2 of 4 in cluster IV**

Actual:
559 ft.

Focus Map:
11

SPILLS:

Name:	UT SERVICE CENTER, MANOR ROAD AND IH-35, AUSTIN
Address:	UT SERVICE CENTER, MANOR ROAD AND IH-35, AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	05/10/1991
Seq Num:	Not reported
Responsible Party Name:	UNIVERSITY OF TEXAS AT AUSTIN
Responsible Party Address:	2617 SPEEDWAY
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	Not reported
Responsible Party Telephone:	5124713511
Substance:	CHROMIUM WATER
Material Code:	2120
Media Affected:	NO
Permit Number:	66154
District:	14
Origin:	001
Cause:	003
Basin Code:	1429
Notify Date:	Not reported
Adequate Clean:	007
Classification:	005
Basin Name:	COLORADO
Water Affected:	NONE

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Amnt Spilled:	15 GAL
Amnt in Water:	NONE GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	J. YOUNG
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

Ind. Haz Waste:

Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Address:	2617 SPEEDWAY STE 104
City,State,Zip:	AUSTIN, TX 78712
Permit Number:	Not reported
Registration Number:	66154
Registration Initial Notification Date:	02/06/1984
Registration Last Amendment Date:	12/13/2022
EPA Identification:	TXD980869184
Primary NAICS Code:	611310
Status Change Date:	19840206
Land Type:	PRIVATE
Description of Facility Site Location:	2617 Speedway, Ste 104, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	THE UNIVERSITY OF TEXAS SYSTEM
Contact Name:	IREZAMA ANDERSON
Contact Telephone Number:	512-4713511
Mailing Address:	PO BOX 7729
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787137729
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21453
Site Owner Tax ID:	746001118
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20221213
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Operator Address:	304 W 24TH ST STE 202
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78712
Operator Country:	UNITED STA
Operator Telephone:	1-512-4717137
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE UNIVERSITY OF TEXAS SYSTEM
Owner Mailing Address:	304 W 24TH ST STE 202
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78712
Owner Country:	UNITED STA
Owner Telephone:	1-512-4717137

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Building is approximately 50 feet by 40 feet and is constructed of cinder b loc
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20201102
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	640
Capacity Measurement:	C
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Two 8 foot by 40 foot hazmat self-contained storage buildings. The hazmat buildi
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20201102
Deed Record Needed:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Building is approximately 90 feet by 40 feet and is constructed of cinder block/
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150812
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	304 W 24TH ST STE 202
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78712
Contact Phone:	1-512-4717137
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	IREZAMA ANDERSON
Contact Title:	ASSISTANT DIRECTOR
Contact Role:	PRICONT
Contact Address:	PO BOX 7729
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78713
Contact Phone:	1-512-4713511
Contact Fax:	1-512-4716918
Contact Email:	n-anderson@mail.utexas.edu

Ind. Haz Waste:

Waste ID:	68441
Texas Waste Code:	Not reported
Texas Waste Code 2:	00012981
Waste Code Status:	INACTIVE

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Form:	298
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Light ballast which contain PCBs; Material has been excluded from being a solid
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	68442
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002310H
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent oil & fuel filters; Due to waste minimization, ingredient changes or proce
Standard Industrial Code:	82210
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W310
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68443
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic inks; Due to waste minimization, ingredient changes or process

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

	changes t
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68444
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Halogenated/non-halogenated solvents & waste oils.
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68445
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005211H
Waste Code Status:	INACTIVE
Waste Form:	211

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint & thinners; Hazardous waste currently being managed under Universal Waste
Standard Industrial Code:	82210
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68446
Texas Waste Code:	Not reported
Texas Waste Code 2:	00065191
Waste Code Status:	INACTIVE
Waste Form:	519
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Inorganic sludge
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	68447
Texas Waste Code:	Not reported
Texas Waste Code 2:	00072111
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	1
Waste is Radioactive:	0

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Treated Off Site:	1
Generators Waste Description:	Petroleum distillates
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	68448
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Halogenated/non-halogenated solvents & waste oils.
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68449
Texas Waste Code:	Not reported
Texas Waste Code 2:	00092191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Multigear lubricant
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	68450
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Paint thinner or petroleum distillates
Standard Industrial Code:	82210
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68451
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113081
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty metal drums or containers; Material has been excluded from being a solid w
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	68452
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012315H
Waste Code Status:	INACTIVE
Waste Form:	315
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Other reactive or explosive salts/chemicals; Due to waste minimization, ingredie
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68453
Texas Waste Code:	Not reported
Texas Waste Code 2:	00134951
Waste Code Status:	INACTIVE
Waste Form:	495
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB debris (Non-soil); Material has been excluded from being a solid waste or ha
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Waste ID:	70062
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Cleaning residue from silkscreen and printing operations. Acetone contaminateds
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73310
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead contaminated debris from work on campus. June,1993-initial date of generat
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste ID:	73315
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016206H
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil with water.; Due to waste minimization, ingredient changes or process
Standard Industrial Code:	82210
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W206
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	73329
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017519H
Waste Code Status:	INACTIVE
Waste Form:	519
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sludge from operation of cooling tower.; Due to waste minimization, ingredient c
Standard Industrial Code:	82210
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W519
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72574
Texas Waste Code:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Texas Waste Code 2:	0018205H
Waste Code Status:	INACTIVE
Waste Form:	205
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil from cooling tower operations at power plant. Initial generation 7/15
Standard Industrial Code:	82210
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W205
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72575
Texas Waste Code:	Not reported
Texas Waste Code 2:	00194891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spill clean up of motor oils. Initial generation on 9/9/93.; Material has been
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	72577
Texas Waste Code:	Not reported
Texas Waste Code 2:	00202011
Waste Code Status:	INACTIVE
Waste Form:	201
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Generators Waste Description:	Petroleum solvent (25%) in water.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	72579
Texas Waste Code:	Not reported
Texas Waste Code 2:	0021219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Diesel # 2 mixed with shale mud.
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72582
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022201H
Waste Code Status:	INACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Mixed organic and aqueous
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72587
Texas Waste Code:	Not reported
Texas Waste Code 2:	00232061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oils (motor oil, hydraulic mineral Etc.) Research Labs , maintenance oper
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	76233
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-Halogenated Solvents 1/93-Initial Generated.
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	87531
Texas Waste Code:	Not reported
Texas Waste Code 2:	00253901
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Construction Debris; Due to waste minimization, ingredient changes or process ch
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	91021
Texas Waste Code:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Texas Waste Code 2:	0026004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab packs Generated 1990
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Waste ID:	203461
Texas Waste Code:	Not reported
Texas Waste Code 2:	00270031
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non hazardous lab pack; Material has been excluded from being a solid waste or h
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	159760
Texas Waste Code:	Not reported
Texas Waste Code 2:	0028206H
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil contaminated with solvents generated through routine activities at ani
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W206
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste ID:	204530
Texas Waste Code:	Not reported
Texas Waste Code 2:	00301011
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water with organics; Material has been excluded from being a solid waste or haza
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	159761
Texas Waste Code:	Not reported
Texas Waste Code 2:	0032309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead-acid, nickel-cadmium or lithium batteries generated through routine activit
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	203462
Texas Waste Code:	Not reported
Texas Waste Code 2:	00333191

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Silica Gel; Material has been excluded from being a solid waste or hazardous was
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	159762
Texas Waste Code:	Not reported
Texas Waste Code 2:	0034202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Halogenated solvents generated through routine activities at an institution of h
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	126395
Texas Waste Code:	Not reported
Texas Waste Code 2:	0035104H
Waste Code Status:	ACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Generators Waste Description:	Spent acid, not containing metals, generated through day to day activitiesat an
Standard Industrial Code:	82210
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	159763
Texas Waste Code:	Not reported
Texas Waste Code 2:	0036119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Other inorganic liquids (photofixer high in silver) generated through routine ac
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199075
Texas Waste Code:	Not reported
Texas Waste Code 2:	0039701H
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	INORGANIC GASES

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	125240
Texas Waste Code:	Not reported
Texas Waste Code 2:	0044302H
Waste Code Status:	INACTIVE
Waste Form:	302
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil contaminated with inorganics, water and metals, generated as a waste byprod
Standard Industrial Code:	82210
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W301
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	126397

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0045103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent acid solution with metals generated by routine activities undertaken at an
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	131012
Texas Waste Code:	Not reported
Texas Waste Code 2:	0046203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste liquid scintillation cocktail generated routine activities at an instituti
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Waste ID:	131248
Texas Waste Code:	Not reported
Texas Waste Code 2:	00472061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Recyclable waste oil that is generated by automotive maintenance and related act
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	131363
Texas Waste Code:	Not reported
Texas Waste Code 2:	00481981
Waste Code Status:	INACTIVE
Waste Form:	198
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nonhazardous photographic chemical wastes (inorganic) generated by normal activi
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	132821
Texas Waste Code:	Not reported
Texas Waste Code 2:	0049307H
Waste Code Status:	INACTIVE
Waste Form:	307

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Metal Scale, Filings, and / or scrap generated through the day-To-Day activities
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	132824
Texas Waste Code:	Not reported
Texas Waste Code 2:	00504031
Waste Code Status:	INACTIVE
Waste Form:	403
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nonhazardous solidified (polymerized) organics or resins generated through the d
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	135187
Texas Waste Code:	Not reported
Texas Waste Code 2:	0051110H
Waste Code Status:	INACTIVE

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Caustic aqueous waste generated through routine activities at an institution ofr
Standard Industrial Code:	82210
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	135188
Texas Waste Code:	Not reported
Texas Waste Code 2:	00523011
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil contaminated with organics; generated through routine activities at an inst
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	135189
Texas Waste Code:	Not reported
Texas Waste Code 2:	00533051
Waste Code Status:	INACTIVE
Waste Form:	305
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Dry caustic solids (eg, lime) generated through routine activities at an institu

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	147022
Texas Waste Code:	Not reported
Texas Waste Code 2:	0054388H
Waste Code Status:	ACTIVE
Waste Form:	388
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Crushed glass/metal containers, contaminated with various solvents, generated th
Standard Industrial Code:	82210
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	148896
Texas Waste Code:	Not reported
Texas Waste Code 2:	0055110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic aqueous waste generated through routine actiities at an institution of r
Standard Industrial Code:	82210
Primary Source:	G02
Primary Measurement Point:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	151814
Texas Waste Code:	Not reported
Texas Waste Code 2:	0056204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixed flammable halogenated and non-halogenated solvents with a corrosive aqueou
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	159764
Texas Waste Code:	Not reported
Texas Waste Code 2:	0058319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Generators Waste Description:	Apparatus containing elemental mercury generated through routine activities at a
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	168441
Texas Waste Code:	Not reported
Texas Waste Code 2:	0059319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Silica gel contaminated with organics. Generated through routine activities ata
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	171566
Texas Waste Code:	Not reported
Texas Waste Code 2:	0060114H
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Generators Waste Description:	Contaminated floor rinse. Date of initial generation: 5/1/98; Due to waste minim
Standard Industrial Code:	82210
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	172357
Texas Waste Code:	Not reported
Texas Waste Code 2:	0061210H
Waste Code Status:	INACTIVE
Waste Form:	210
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Adhesives and epoxies generated through routine activities at an institution ofh
Standard Industrial Code:	82210
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199076
Texas Waste Code:	Not reported
Texas Waste Code 2:	0062319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glaze waste containing chromium, barium and lead; Due to waste minimization, ing
Standard Industrial Code:	82210

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199077
Texas Waste Code:	Not reported
Texas Waste Code 2:	00632961
Waste Code Status:	INACTIVE
Waste Form:	296
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ethylene glycol based antifreeze liquid; Material has been excluded from being a
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	199078
Texas Waste Code:	Not reported
Texas Waste Code 2:	00644091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	non-halogenated organic solids; Material has been excluded from being a solid wa
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	199079
Texas Waste Code:	Not reported
Texas Waste Code 2:	00654091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	non-halogenated organic solid
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	199080
Texas Waste Code:	Not reported
Texas Waste Code 2:	0066219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent and used Aerosol Cans; Hazardous waste currently being managed under Unive
Standard Industrial Code:	82210
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Waste ID:	199081
Texas Waste Code:	Not reported
Texas Waste Code 2:	0067211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Petroleum distillates containing elemental mercury
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199082
Texas Waste Code:	Not reported
Texas Waste Code 2:	0069499H
Waste Code Status:	ACTIVE
Waste Form:	499
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic mercury compounds
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W301
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199083

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00701191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Grit trap waste; Due to waste minimization, ingredient changes or process change
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	199084
Texas Waste Code:	Not reported
Texas Waste Code 2:	00712971
Waste Code Status:	INACTIVE
Waste Form:	297
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB contaminated oil>=50 PPM and <500 PPM; Due to waste minimization, ingredient
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	199085
Texas Waste Code:	Not reported
Texas Waste Code 2:	0072801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic Gases

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199086
Texas Waste Code:	Not reported
Texas Waste Code 2:	00737011
Waste Code Status:	INACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Inorganic gas - non-hazardous; Material has been excluded from being a solid was
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	199087
Texas Waste Code:	Not reported
Texas Waste Code 2:	00748011
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic Gas- Non-hazardous; Material has been excluded from being a solid waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	199088
Texas Waste Code:	Not reported
Texas Waste Code 2:	00753191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	spill clean up debris; Material has been excluded from being a solid waste or ha
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	EXCLUSION

Ind. Haz Waste:

Waste ID:	199089
Texas Waste Code:	Not reported
Texas Waste Code 2:	0076102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Inorganic aqueous solution; Due to waste minimization, ingredient changes or pro
Standard Industrial Code:	82210
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	199090
Texas Waste Code:	Not reported
Texas Waste Code 2:	00771191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	inks - nonhazardous; Due to waste minimization, ingredient changes or process ch
Standard Industrial Code:	Not reported
Primary Source:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	199091
Texas Waste Code:	Not reported
Texas Waste Code 2:	00783101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solid filters; Due to waste minimization, ingredient changes or process ch
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	199092
Texas Waste Code:	Not reported
Texas Waste Code 2:	00793191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Inorganic solids and water; Due to waste minimization, ingredient changes or pro
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Reason Waste Form No Longer Gen: SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID: 215784
Texas Waste Code: Not reported
Texas Waste Code 2: 0080405H
Waste Code Status: INACTIVE
Waste Form: 405
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Organic reactive solids; Due to waste minimization, ingredient changes or proces
Standard Industrial Code: Not reported
Primary Source: G11
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: REACTIVE SOLIDS ORG
Primary NAICS Code: 611310
EPA Waste Form Code: W409
Reason Waste Form No Longer Gen: SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 392293
Texas Waste Code: Not reported
Texas Waste Code 2: 0081119H
Waste Code Status: INACTIVE
Waste Form: 119
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Inorganic aqueous solution; Due to waste minimization, ingredient changes or pro
Standard Industrial Code: Not reported
Primary Source: G11
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: INORGANIC LIQUIDS
Primary NAICS Code: 611310
EPA Waste Form Code: W119
Reason Waste Form No Longer Gen: SOURCE REDUCTIO

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Waste ID:	426801
Texas Waste Code:	Not reported
Texas Waste Code 2:	0085212H
Waste Code Status:	ACTIVE
Waste Form:	212
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Reactive or polymerizeable organic liquids
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	432655
Texas Waste Code:	Not reported
Texas Waste Code 2:	0086106H
Waste Code Status:	ACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Bulk caustic wastes containing metals but no cyanides generated through routine
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Waste ID:	433605
Texas Waste Code:	Not reported
Texas Waste Code 2:	0087119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Other inorganic liquids (Flammable and Reactive waste from disposal of unwanted/
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	611310
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	68440
Texas Waste Code:	Not reported
Texas Waste Code 2:	99993191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Latex Paint waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **S103606340**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-4717137 x0
Mailing Address:	PO BOX 7729
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78713
AR Number:	0000303517
Principal Name:	THE UNIVERSITY OF TEXAS SYSTEM
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-4717137 x0
Mailing Address:	PO BOX 7729
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78713
AR Number:	0000303517
Principal Name:	THE UNIVERSITY OF TEXAS SYSTEM
Attention Name:	Not reported
Attention Suffix:	NWG

IV1636 **THE UNIVERSITY OF TEXAS MAIN CAMPUS** **RCRA-LQG** **1000429149**
East **2617 SPEEDWAY STE 104** **PADS** **TXD980869184**
< 1/8 **AUSTIN, TX 78712** **NY MANIFEST**
0.027 mi.
144 ft. **Site 3 of 4 in cluster IV**

Actual:
559 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20221213
Handler Name:	The University Of Texas Main Campus
Handler Address:	SPEEDWAY STE 104
Handler City,State,Zip:	AUSTIN, TX 78712-1763
EPA ID:	TXD980869184
Contact Name:	IREZAMA ANDERSON
Contact Address:	PO BOX 7729
Contact City,State,Zip:	AUSTIN, TX 78713-7729
Contact Telephone:	512-471-3511
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 7729
Mailing City,State,Zip:	AUSTIN, TX 78713-7729
Owner Name:	The University Of Texas System
Owner Type:	Private
Operator Name:	The University Of Texas System

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230103
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:
Year: 2019

Click Here for Biennial Reporting System Data:
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Click Here for Biennial Reporting System Data:
Year: 2011

Click Here for Biennial Reporting System Data:
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: D012
Waste Description: Endrin (1,2,3,4,10,10-Hexachloro-1,7-Epoxy-1,4,4a,5,6,7,8,8a-Octahydro-1,4-Endo, Endo-5,8-Dimeth-Ano-Naphthalene)

Waste Code: D013
Waste Description: Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)

Waste Code: D014
Waste Description: Methoxychlor (1,1,1-Trichloro-2,2-Bis [P-Methoxyphenyl] Ethane)

Waste Code: D015
Waste Description: Toxaphene (C10 H10 Cl8, Technical Chlorinated Camphene, 67-69 Percent Chlorine)

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D017
Waste Description: 2,4,5-Tp Silvex (2,4,5-Trichlorophenoxypropionic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D019
Waste Description: Carbon Tetrachloride

Waste Code: D020
Waste Description: Chlordane

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D022
Waste Description: Chloroform

Waste Code: D023
Waste Description: O-Cresol

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D025
Waste Description: P-Cresol

Waste Code: D026
Waste Description: Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D028
Waste Description: 1,2-Dichloroethane

Waste Code: D029
Waste Description: 1,1-Dichloroethylene

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: D030
Waste Description: 2,4-Dinitrotoluene

Waste Code: D031
Waste Description: Heptachlor (And Its Epoxide)

Waste Code: D032
Waste Description: Hexachlorobenzene

Waste Code: D033
Waste Description: Hexachlorobutadiene

Waste Code: D034
Waste Description: Hexachloroethane

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D036
Waste Description: Nitrobenzene

Waste Code: D037
Waste Description: Pentachlorophenol

Waste Code: D038
Waste Description: Pyridine

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D041
Waste Description: 2,4,5-Trichlorophenol

Waste Code: D042
Waste Description: 2,4,6-Trichlorophenol

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2,

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F007
Waste Description: Spent Cyanide Plating Bath Solutions From Electroplating Operations.

Waste Code: K001
Waste Description: Bottom Sediment Sludge From The Treatment Of Wastewaters From Wood Preserving Processes That Use Creosote And/Or Pentachlorophenol.

Waste Code: K048
Waste Description: Dissolved Air Flotation (Daf) Float From The Petroleum Refining Industry.

Waste Code: K049
Waste Description: Slop Oil Emulsion Solids From The Petroleum Refining Industry.

Waste Code: K050
Waste Description: Heat Exchanger Bundle Cleaning Sludge From The Petroleum Refining Industry.

Waste Code: K051
Waste Description: Api Separator Sludge From The Petroleum Refining Industry.

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: K052
Waste Description: Tank Bottoms (Leaded) From The Petroleum Refining Industry.

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P002
Waste Description: 1-Acetyl-2-Thiourea (Or) Acetamide, N-(Aminothioxomethyl)-

Waste Code: P003
Waste Description: 2-Propenal (Or) Acrolein

Waste Code: P004
Waste Description: 1,4,5,8-Dimethanonaphthalene, 1,2,3,4,10,10-Hexa-Chloro-1,4,4a,5,8,8a,-Hexahydro-, (1alpha, 4alpha, 4abeta, 5alpha, 8alpha, 8abeta)- (Or) Aldrin

Waste Code: P005
Waste Description: 2-Propen-1-Ol (Or) Allyl Alcohol

Waste Code: P006
Waste Description: Aluminum Phosphide (R,T)

Waste Code: P007
Waste Description: 3(2h)-Isoxazolone, 5-(Aminomethyl)- (Or) 5-(Aminomethyl)-3-Isoxazolol

Waste Code: P008
Waste Description: 4-Aminopyridine (Or) 4-Pyridinamine

Waste Code: P009
Waste Description: Ammonium Picrate (R) (Or) Phenol, 2,4,6-Trinitro-, Ammonium Salt (R)

Waste Code: P010
Waste Description: Arsenic Acid H3aso4

Waste Code: P011
Waste Description: Arsenic Oxide As2o5 (Or) Arsenic Pentoxide

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P013
Waste Description: Barium Cyanide

Waste Code: P014
Waste Description: Benzenethiol (Or) Thiophenol

Waste Code: P015
Waste Description: Beryllium

Waste Code: P016
Waste Description: Dichloromethyl Ether (Or) Methane, Oxybis[Chloro-

Waste Code: P017
Waste Description: 2-Propanone, 1-Bromo- (Or) Bromoacetone

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P018
Waste Description: Brucine (Or) Strychnidin-10-One, 2,3-Dimethoxy-

Waste Code: P020
Waste Description: Dinoseb (Or) Phenol, 2-(1-Methylpropyl)-4,6-Dinitro-

Waste Code: P021
Waste Description: Calcium Cyanide (Or) Calcium Cyanide Ca(Cn)2

Waste Code: P022
Waste Description: Carbon Disulfide

Waste Code: P023
Waste Description: Acetaldehyde, Chloro- (Or) Chloroacetaldehyde

Waste Code: P024
Waste Description: Benzenamine, 4-Chloro- (Or) P-Chloraniline

Waste Code: P026
Waste Description: 1-(O-Chlorophenyl)Thiourea (Or) Thiourea, (2-Chlorophenyl)-

Waste Code: P027
Waste Description: 3-Chloropropionitrile (Or) Propanenitrile, 3-Chloro-

Waste Code: P028
Waste Description: Benzene, (Chloromethyl)- (Or) Benzyl Chloride

Waste Code: P029
Waste Description: Copper Cyanide (Or) Copper Cyanide Cu(Cn)

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P031
Waste Description: Cyanogen (Or) Ethanedinitrile

Waste Code: P033
Waste Description: Cyanogen Chloride (Or) Cyanogen Chloride (Cn)Cl

Waste Code: P034
Waste Description: 2-Cyclohexyl-4,6-Dinitrophenol (Or) Phenol, 2-Cyclohexyl-4,6-Dinitro-

Waste Code: P036
Waste Description: Arsonous Dichloride, Phenyl- (Or) Dichlorophenylarsine

Waste Code: P037
Waste Description: 2,7:3,6-Dimethanonaphth[2,3-B]Oxirene, 3,4,5,6,9,9-Hexachloro-1a,2,2a,3,6,6a,7,7a-Octahydro-, (1aalpha, 2beta, 2aalpha, 3beta, 6beta, 6aalpha, 7beta, 7aalpha)- (Or) Dieldrin

Waste Code: P038
Waste Description: Arsine, Diethyl- (Or) Diethylarsine

Waste Code: P039
Waste Description: Disulfoton (Or) Phosphorodithioic Acid, O,O-Diethyl S-[2-(Ethylthio)Ethyl] Ester

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P040
Waste Description: O,O-Diethyl O-Pyrazinyl Phosphorothioate (Or) Phosphorothioic Acid, O,O-Diethyl O-Pyrazinyl Ester

Waste Code: P041
Waste Description: Diethyl-P-Nitrophenyl Phosphate (Or) Phosphoric Acid, Diethyl 4-Nitrophenyl Ester

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P043
Waste Description: Diisopropylfluorophosphate (Dfp) (Or) Phosphorofluoridic Acid, Bis(1-Methylethyl) Ester

Waste Code: P044
Waste Description: Dimethoate (Or) Phosphorodithioic Acid, O,O-Dimethyl S-[2-(Methylamino)-2-Oxoethyl] Ester

Waste Code: P045
Waste Description: 2-Butanone, 3,3-Dimethyl-1-(Methylthio)-, O-[Methylamino)Carbonyl] Oxime (Or) Thiofanox

Waste Code: P046
Waste Description: Alpha,Alpha-Dimethylphenethylamine (Or) Benzeneethanamine, Alpha, Alpha-Dimethyl-

Waste Code: P047
Waste Description: 4,6-Dinitro-O-Cresol, & Salts (Or) Phenol, 2-Methyl-4,6-Dinitro-, & Salts

Waste Code: P048
Waste Description: 2,4-Dinitrophenol (Or) Phenol, 2,4-Dinitro-

Waste Code: P049
Waste Description: Dithiobiuret (Or) Thioimidodicarbonic Diamide [(H2n)C(S)]2nh

Waste Code: P050
Waste Description: 6,9-Methano-2,4,3-Benzodioxathiepin,6,7,8,9,10,10-Hexachloro-1,5,5a,6, 9,9a-Hexahydro-,3-Oxide (Or) Endosulfan

Waste Code: P051
Waste Description: 2,7:3,6-Dimethanonaphth[2,3-B]Oxirene, 3,4,5,6,9,9-Hexachloro-1a,2,2a,3,6,6a,7,7a-Octahydro-, (1aalpha, 2beta, 2abeta, 3alpha, 6alpha, 6abeta, 7beta, 7aalpha)- & Metabolites (Or) Endrin (Or) Endrin, & Metabolites

Waste Code: P054
Waste Description: Aziridine (Or) Ethyleneimine

Waste Code: P056
Waste Description: Fluorine

Waste Code: P057
Waste Description: Acetamide, 2-Fluoro- (Or) Fluoroacetamide

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P058
Waste Description: Acetic Acid, Fluoro-, Sodium Salt (Or) Fluoroacetic Acid, Sodium Salt

Waste Code: P059
Waste Description: 4,7-Methano-1h-Indene, 1,4,5,6,7,8,8-Heptachloro-3a,4,7,7a-Tetrahydro- (Or) Heptachlor

Waste Code: P060
Waste Description: 1,4,5,8-Dimethanonaphthalene, 1,2,3,4,10,10-Hexa-Chloro-1,4,4a,5,8,8a,-Hexahydro-, (1alpha, 4alpha, 4abeta, 5beta, 8beta, 8abeta)- (Or) Isodrin

Waste Code: P062
Waste Description: Hexaethyl Tetraphosphate (Or) Tetraphosphoric Acid, Hexaethyl Ester

Waste Code: P063
Waste Description: Hydrocyanic Acid (Or) Hydrogen Cyanide

Waste Code: P064
Waste Description: Methane, Isocyanato- (Or) Methyl Isocyanate

Waste Code: P065
Waste Description: Fulminic Acid, Mercury(2+) Salt (R,T) (Or) Mercury Fulminate (R,T)

Waste Code: P066
Waste Description: Ethanimidothioic Acid, N-[[(Methylamino)Carbonyl]Oxy]-, Methyl Ester (Or) Methomyl

Waste Code: P067
Waste Description: 1,2-Propylenimine (Or) Aziridine, 2-Methyl-

Waste Code: P068
Waste Description: Hydrazine, Methyl- (Or) Methyl Hydrazine

Waste Code: P069
Waste Description: 2-Methyllactonitrile (Or) Propanenitrile, 2-Hydroxy-2-Methyl-

Waste Code: P070
Waste Description: Aldicarb (Or) Propanal, 2-Methyl-2-(Methylthio)-, O-[(Methylamino)Carbonyl]Oxime

Waste Code: P071
Waste Description: Methyl Parathion (Or) Phosphorothioic Acid, O,O,-Dimethyl O-(4-Nitrophenyl) Ester

Waste Code: P072
Waste Description: Alpha-Naphthylthiourea (Or) Thiourea, 1-Naphthalenyl-

Waste Code: P073
Waste Description: Nickel Carbonyl (Or) Nickel Carbonyl Ni(Co)4, (T-4)-

Waste Code: P074
Waste Description: Nickel Cyanide (Or) Nickel Cyanide Ni(Cn)2

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P076
Waste Description: Nitric Oxide (Or) Nitrogen Oxide No

Waste Code: P077
Waste Description: Benzenamine, 4-Nitro- (Or) P-Nitroaniline

Waste Code: P078
Waste Description: Nitrogen Dioxide (Or) Nitrogen Oxide No2

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P082
Waste Description: Methanimine, N-Methyl-N-Nitroso- (Or) N-Nitrosodimethylamine

Waste Code: P084
Waste Description: N-Nitrosomethylvinylamine (Or) Vinylamine, N-Methyl-N-Nitroso-

Waste Code: P085
Waste Description: Diphosphoramide, Octamethyl- (Or) Octamethylpyrophosphoramide

Waste Code: P087
Waste Description: Osmium Oxide Oso4, (T-4)- (Or) Osmium Tetroxide

Waste Code: P088
Waste Description: 7-Oxabicyclo[2.2.1]Heptane-2,3-Dicarboxylic Acid (Or) Endothall

Waste Code: P089
Waste Description: Parathion (Or) Phosphorothioic Acid, O,O-Diethyl-O-(4-Nitrophenyl) Ester

Waste Code: P092
Waste Description: Mercury, (Acetato-O)Phenyl- (Or) Phenylmercury Acetate

Waste Code: P093
Waste Description: Phenylthiourea (Or) Thiourea, Phenyl-

Waste Code: P094
Waste Description: Phorate (Or) Phosphorodithioic Acid, O,O-Diethyl S-[(Ethylthio)Methyl] Ester

Waste Code: P095
Waste Description: Carbonic Dichloride (Or) Phosgene

Waste Code: P096
Waste Description: Hydrogen Phosphide (Or) Phosphine

Waste Code: P097
Waste Description: Famphur (Or) Phosphorothioic Acid O-[4-[(Dimethylamino)Sulfonyl]Phenyl] O,O-Dimethyl Ester

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P099
Waste Description: Argentate (1-), Bis(Cyano-C)-, Potassium (Or) Potassium Silver Cyanide

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P101
Waste Description: Ethyl Cyanide (Or) Propanenitrile

Waste Code: P102
Waste Description: 2-Propyn-1-Ol (Or) Propargyl Alcohol

Waste Code: P103
Waste Description: Selenourea

Waste Code: P104
Waste Description: Silver Cyanide (Or) Silver Cyanide Ag(Cn)

Waste Code: P105
Waste Description: Sodium Azide

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: P108
Waste Description: Strychnidin-10-One, & Salts (Or) Strychnine, & Salts

Waste Code: P109
Waste Description: Tetraethyldithiopyrophosphate (Or) Thiodiphosphoric Acid, Tetraethyl Ester

Waste Code: P110
Waste Description: Plumbane, Tetraethyl- (Or) Tetraethyl Lead

Waste Code: P111
Waste Description: Diphosphoric Acid, Tetraethyl Ester (Or) Tetraethyl Pyrophosphate

Waste Code: P112
Waste Description: Methane, Tetranitro- (R) (Or) Tetranitromethane (R)

Waste Code: P113
Waste Description: Thallic Oxide (Or) Thallium Oxide Tl2o3

Waste Code: P114
Waste Description: Selenious Acid, Dithallium (1+) Salt (Or) Thallium(I) Selenite

Waste Code: P115
Waste Description: Sulfuric Acid, Dithallium (1+) Salt (Or) Thallium(I) Sulfate

Waste Code: P116
Waste Description: Hydrazinecarbothioamide (Or) Thiosemicarbazide

Waste Code: P118
Waste Description: Methanethiol, Trichloro- (Or) Trichloromethanethiol

Waste Code: P119
Waste Description: Ammonium Vanadate (Or) Vanadic Acid, Ammonium Salt

Waste Code: P120
Waste Description: Vanadium Oxide V2o5 (Or) Vanadium Pentoxide

Waste Code: P121
Waste Description: Zinc Cyanide (Or) Zinc Cyanide Zn(Cn)2

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P122
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Greater Than 10% (R,T)

Waste Code: P123
Waste Description: Toxaphene

Waste Code: P127
Waste Description: P127

Waste Code: P128
Waste Description: P128

Waste Code: P185
Waste Description: 1,3-Dithiolane-2-Carboxaldehyde, 2,4-Dimethyl-, O-[(Methylamino)-Carbonyl]Oxime (Or) Tirpate

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: P189
Waste Description: Carbamic Acid, [(Dibutylamino)-Thio]Methyl-, 2,3-Dihydro-2,2-Dimethyl -7-Benzofuranyl Ester (Or) Carbosulfan

Waste Code: P190
Waste Description: Carbamic Acid, Methyl-, 3-Methylphenyl Ester (Or) Metolcarb

Waste Code: P191
Waste Description: Carbamic Acid, Dimethyl-, 1-[(Dimethyl-Amino)Carbonyl]- 5-Methyl-1h-Pyrazol-3-Yl Ester (Or) Dimetilan

Waste Code: P192
Waste Description: Isolan (Or) Carbamic Acid, Dimethyl-, 3-Methy-L-(1-Methylethyl)-1h-Pyrazol-5-Yl Ester

Waste Code: P194
Waste Description: Ethanimidothioc Acid, 2-(Dimethylamino)-N-[[(Methylamino) Carbonyl]Oxy]-2-Oxo-, Methyl Ester (Or) Oxamyl

Waste Code: P196
Waste Description: Manganese Dimethyldithiocarbamate (Or) Manganese, Bis(Dimethylcarbamodithioato-S,S')-,

Waste Code: P197
Waste Description: Formparanate (Or) Methanimidamide, N,N-Dimethyl-N'-[2-Methyl-4-[[(Methylamino)Carbonyl]Oxy]Phenyl]

Waste Code: P198
Waste Description: Methanimidamide, N,N-Dimethyl-N'-[3-[[(Methylamino)-Carbonyl]Oxy]Phenyl]-, Monohydrochloride (Or) Formetanate Hydrochloride

Waste Code: P199
Waste Description: P199

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: P201
Waste Description: Phenol, 3-Methyl-5-(1-Methylethyl)-, Methyl Carbamate (Or) Promecarb

Waste Code: P202
Waste Description: M-Cumenyl Methylcarbamate (Or) 3-Isopropylphenyl N-Methylcarbamate (Or) Phenol, 3-(1-Methylethyl)-, Methyl Carbamate

Waste Code: P203
Waste Description: Aldicarb Sulfone (Or) Propanal, 2-Methyl-2-(Methyl-Sulfonyl)-, O-[(Methylamino)Carbonyl] Oxime

Waste Code: P204
Waste Description: Physostigmine (Or) Pyrrolo[2,3-B]Indol-5-Ol, 1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethyl-Methylcarbamate (Ester), (3as-Cis)-

Waste Code: P205
Waste Description: Zinc, Bis(Dimethylcarbamodithioato-S,S')-, (Or) Ziram

Waste Code: U001
Waste Description: Acetaldehyde (I) (Or) Ethanal (I)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U003
Waste Description: Acetonitrile (I,T)

Waste Code: U004
Waste Description: Acetophenone (Or) Ethanone, 1-Phenyl-

Waste Code: U005
Waste Description: 2-Acetylaminofluorene (Or) Acetamide, N-9h-Fluoren-2-Yl

Waste Code: U006
Waste Description: Acetyl Chloride (C,R,T)

Waste Code: U007
Waste Description: 2-Propenamide (Or) Acrylamide

Waste Code: U008
Waste Description: 2-Propenoic Acid (I) (Or) Acrylic Acid (I)

Waste Code: U009
Waste Description: 2-Propenenitrile (Or) Acrylonitrile

Waste Code: U010
Waste Description: Azirino [2',3':3,4]Pyrrolo[1,2-A]Indole-4,7-Dione, 6-Amino-8-[[(Aminocarbonyl)Oxy]Methyl]-1,1a,2,8,8a,8b-Hexahydro-8a-Methoxy-5-Methyl-, [1as-(1aalpha, 8beta, 8aalpha, 8balpha)]- (Or) Mitomycin C

Waste Code: U011
Waste Description: 1h-1,2,4-Triazol-3-Amine (Or) Amitrole

Waste Code: U012
Waste Description: Aniline (I,T) (Or) Benzenamine (I,T)

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U014
Waste Description: Auramine (Or) Benzenamine, 4,4'-Carbonimidoylbis[N,N-Dimethyl-

Waste Code: U015
Waste Description: Azaserine (Or) L-Serine, Diazoacetate (Ester)

Waste Code: U016
Waste Description: Benz[C]Acridine

Waste Code: U017
Waste Description: Benzal Chloride (Or) Benzene, (Dichloromethyl)-

Waste Code: U018
Waste Description: Benz[A]Anthracene

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U020
Waste Description: Benzenesulfonic Acid Chloride (C,R) (Or) Benzenesulfonyl Chloride (C,R)

Waste Code: U021
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine (Or) Benzidine

Waste Code: U022
Waste Description: Benzo[A]Pyrene

Waste Code: U023
Waste Description: Benzene, (Trichloromethyl)- (Or) Benzotrichloride (C,R,T)

Waste Code: U024
Waste Description: Dichloromethoxy Ethane (Or) Ethane, 1,1'-[Methylenebis(Oxy)]Bis[2-Chloro-

Waste Code: U025
Waste Description: Dichloroethyl Ether (Or) Ethane, 1,1'-Oxybis[2-Chloro-

Waste Code: U026
Waste Description: Chlornaphazin (Or) Naphthalenamine, N,N'-Bis(2-Chloroethyl)-

Waste Code: U027
Waste Description: Dichloroisopropyl Ether (Or) Propane, 2,2'-Oxybis[2-Chloro-

Waste Code: U028
Waste Description: 1,2-Benzenedicarboxylic Acid, Bis(2-Ethylhexyl) Ester (Or) Diethylhexyl Phthalate

Waste Code: U029
Waste Description: Methane, Bromo- (Or) Methyl Bromide

Waste Code: U030
Waste Description: 4-Bromophenyl Phenyl Ether (Or) Benzene, 1-Bromo-4-Phenoxy-

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U032
Waste Description: Calcium Chromate (Or) Chromic Acid H2cro4, Calcium Salt

Waste Code: U033
Waste Description: Carbon Oxyfluoride (R,T) (Or) Carbonic Difluoride

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U036
Waste Description: 4,7-Methano-1h-Indene, 1,2,4,5,6,7,8,8-Octachloro-2,3,3a,4,7,7a-Hexahydro- (Or) Chlordane, Alpha & Gamma Isomers

Waste Code: U037
Waste Description: Benzene, Chloro- (Or) Chlorobenzene

Waste Code: U038
Waste Description: Benzeneacetic Acid, 4-Chloro-Alpha-(4-Chlorophenyl)-Alpha-Hydroxy-, Ethyl Ester (Or) Chlorobenzilate

Waste Code: U039
Waste Description: P-Chloro-M-Cresol (Or) Phenol, 4-Chloro-3-Methyl-

Waste Code: U041
Waste Description: Epichlorohydrin (Or) Oxirane, (Chloromethyl)-

Waste Code: U042
Waste Description: 2-Chloroethyl Vinyl Ether (Or) Ethene, (2-Chloroethoxy)-

Waste Code: U043
Waste Description: Ethene, Chloro- (Or) Vinyl Chloride

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U045
Waste Description: Methane, Chloro- (I,T) (Or) Methyl Chloride (I,T)

Waste Code: U046
Waste Description: Chloromethyl Methyl Ether (Or) Methane, Chloromethoxy-

Waste Code: U047
Waste Description: Beta-Chloronaphthalene (Or) Naphthalene, 2-Chloro-

Waste Code: U048
Waste Description: O-Chlorophenol (Or) Phenol, 2-Chloro-

Waste Code: U049
Waste Description: 4-Chloro-O-Toluidine, Hydrochloride (Or) Benzenamine, 4-Chloro-2-Methyl-, Hydrochloride

Waste Code: U050
Waste Description: Chrysene

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U051
Waste Description: Creosote

Waste Code: U052
Waste Description: Cresol (Cresylic Acid) (Or) Phenol, Methyl-

Waste Code: U053
Waste Description: 2-Butenal (Or) Crotonaldehyde

Waste Code: U055
Waste Description: Benzene, (1-Methylethyl)- (I) (Or) Cumene (I)

Waste Code: U056
Waste Description: Benzene, Hexahydro- (I) (Or) Cyclohexane (I)

Waste Code: U057
Waste Description: Cyclohexanone (I)

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U059
Waste Description: 5,12-Naphthacenedione, 8-Acetyl-10-[(3-Amino-2,3,6-Trideoxy)-Alpha-L-Lyxo-Hexopyranosyl)Oxy]-7,8,9,10-Tetrahydro-6,8,11-Trihydroxy-1-Methoxy-, (8s-Cis)- (Or) Daunomycin

Waste Code: U060
Waste Description: Benzene, 1,1'-(2,2-Dichloroethylidene)Bis[4-Chloro- (Or) Ddd

Waste Code: U061
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Chloro- (Or) Ddt

Waste Code: U062
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3-Dichloro-2-Propenyl) Ester (Or) Diallate

Waste Code: U063
Waste Description: Dibenz[A,H]Anthracene

Waste Code: U064
Waste Description: Benzo[Rst]Pentaphene (Or) Dibenzo[A,I]Pyrene

Waste Code: U066
Waste Description: 1,2-Dibromo-3-Chloropropane (Or) Propane, 1,2-Dibromo-3-Chloro-

Waste Code: U067
Waste Description: Ethane, 1,2-Dibromo- (Or) Ethylene Dibromide

Waste Code: U068
Waste Description: Methane, Dibromo- (Or) Methylene Bromide

Waste Code: U069
Waste Description: 1,2-Benzenedicarboxylic Acid, Dibutyl Ester (Or) Dibutyl Phthalate

Waste Code: U070

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

Waste Code: U071
Waste Description: Benzene, 1,3-Dichloro- (Or) M-Dichlorobenzene

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U073
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dichloro- (Or) 3,3'-Dichlorobenzidine

Waste Code: U074
Waste Description: 1,4-Dichloro-2-Butene (I,T) (Or) 2-Butene, 1,4-Dichloro- (I,T)

Waste Code: U075
Waste Description: Dichlorodifluoromethane (Or) Methane, Dichlorodifluoro-

Waste Code: U076
Waste Description: Ethane, 1,1-Dichloro- (Or) Ethylidene Dichloride

Waste Code: U077
Waste Description: Ethane, 1,2-Dichloro- (Or) Ethylene Dichloride

Waste Code: U078
Waste Description: 1,1-Dichloroethylene (Or) Ethene, 1,1-Dichloro-

Waste Code: U079
Waste Description: 1,2-Dichloroethylene (Or) Ethene, 1,2-Dichloro-,(E)-

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U081
Waste Description: 2,4-Dichlorophenol (Or) Phenol, 2,4-Dichloro-

Waste Code: U082
Waste Description: 2,6-Dichlorophenol (Or) Phenol, 2,6-Dichloro-

Waste Code: U083
Waste Description: Propane, 1,2-Dichloro- (Or) Propylene Dichloride

Waste Code: U084
Waste Description: 1,3-Dichloropropene (Or) 1-Propene, 1,3-Dichloro-

Waste Code: U085
Waste Description: 1,2:3,4-Diepoxybutane (I,T) (Or) 2,2'-Bioxirane

Waste Code: U086
Waste Description: Hydrazine, 1,2-Diethyl- (Or) N,N'-Diethylhydrazine

Waste Code: U087
Waste Description: O,O-Diethyl S-Methyl Dithiophosphate (Or) Phosphorodithioic Acid, O,O-Diethyl S-Methyl Ester

Waste Code: U088
Waste Description: 1,2-Benzenedicarboxylic Acid, Diethyl Ester (Or) Diethyl Phthalate

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4'-(1,2-Diethyl-1,2-Ethenediyl)Bis, (E)-

Waste Code: U090
Waste Description: 1,3-Benzodioxole, 5-Propyl- (Or) Dihydrosafrole

Waste Code: U091
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethoxy- (Or) 3,3'-Dimethoxybenzidine

Waste Code: U092
Waste Description: Dimethylamine (I) (Or) Methanamine, N-Methyl- (I)

Waste Code: U093
Waste Description: Benzenamine, N,N-Dimethyl-4-(Phenylazo)- (Or) P-Dimethylaminoazobenzene

Waste Code: U094
Waste Description: 7,12-Dimethylbenz[A]Anthracene (Or) Benz[A]Anthracene, 7,12-Dimethyl-

Waste Code: U095
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethyl- (Or) 3,3'-Dimethylbenzidine

Waste Code: U096
Waste Description: Alpha,Alpha-Dimethylbenzylhydroperoxide (R) (Or) Hydroperoxide, 1-Methyl-1-Phenylethyl- (R)

Waste Code: U097
Waste Description: Carbamic Chloride, Dimethyl- (Or) Dimethylcarbamoyl Chloride

Waste Code: U098
Waste Description: 1,1-Dimethylhydrazine (Or) Hydrazine, 1,1-Dimethyl-

Waste Code: U099
Waste Description: 1,2-Dimethylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U101
Waste Description: 2,4-Dimethylphenol (Or) Phenol, 2,4-Dimethyl-

Waste Code: U102
Waste Description: 1,2-Benzenedicarboxylic Acid, Dimethyl Ester (Or) Dimethyl Phthalate

Waste Code: U103
Waste Description: Dimethyl Sulfate (Or) Sulfuric Acid, Dimethyl Ester

Waste Code: U105
Waste Description: 2,4-Dinitrotoluene (Or) Benzene, 1-Methyl-2,4-Dinitro-

Waste Code: U106
Waste Description: 2,6-Dinitrotoluene (Or) Benzene, 2-Methyl-1,3-Dinitro-

Waste Code: U107
Waste Description: 1,2-Benzenedicarboxylic Acid, Dioctyl Ester (Or) Di-N-Octyl Phthalate

Waste Code: U108

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Description: 1,4-Diethyleneoxide (Or) 1,4-Dioxane

Waste Code: U109
Waste Description: 1,2-Diphenylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U110
Waste Description: 1-Propanimine, N-Propyl-(I) (Or) Dipropylamine (I)

Waste Code: U111
Waste Description: 1-Propanamine, N-Nitroso-N-Propyl- (Or) Di-N-Propylnitrosamine

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U113
Waste Description: 2-Propenoic Acid, Ethyl Ester (I) (Or) Ethyl Acrylate (I)

Waste Code: U114
Waste Description: Carbamodithioic Acid, 1,2-Ethanediylbis-, Salts & Esters (Or) Ethylenebisdithiocarbamic Acid, Salts & Esters

Waste Code: U115
Waste Description: Ethylene Oxide (I,T) (Or) Oxirane (I,T)

Waste Code: U116
Waste Description: 2-Imidazolidinethione (Or) Ethylenethiourea

Waste Code: U117
Waste Description: Ethane, 1,1'-Oxybis-(I) (Or) Ethyl Ether (I)

Waste Code: U118
Waste Description: 2-Propenoic Acid, 2-Methyl-, Ethyl Ester (Or) Ethyl Methacrylate

Waste Code: U119
Waste Description: Ethyl Methanesulfonate (Or) Methanesulfonic Acid, Ethyl Ester

Waste Code: U120
Waste Description: Fluoranthene

Waste Code: U121
Waste Description: Methane, Trichlorofluoro- (Or) Trichloromonofluoromethane

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U123
Waste Description: Formic Acid (C,T)

Waste Code: U124
Waste Description: Furan (I) (Or) Furfuran (I)

Waste Code: U125
Waste Description: 2-Furancarboxaldehyde (I) (Or) Furfural (I)

Waste Code: U126
Waste Description: Glycidylaldehyde (Or) Oxiranecarboxyaldehyde

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U127
Waste Description: Benzene, Hexachloro- (Or) Hexachlorobenzene

Waste Code: U128
Waste Description: 1,3-Butadiene, 1,1,2,3,4,4-Hexachloro- (Or) Hexachlorobutadiene

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U130
Waste Description: 1,3-Cyclopentadiene, 1,2,3,4,5,5-Hexachloro- (Or) Hexachlorocyclopentadiene

Waste Code: U131
Waste Description: Ethane, Hexachloro- (Or) Hexachloroethane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2'-Methylenebis[3,4,6-Trichloro-

Waste Code: U133
Waste Description: Hydrazine (R,T)

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Waste Code: U135
Waste Description: Hydrogen Sulfide (Or) Hydrogen Sulfide H2s

Waste Code: U136
Waste Description: Arsinic Acid, Dimethyl- (Or) Cacodylic Acid

Waste Code: U137
Waste Description: Indeno[1,2,3-Cd]Pyrene

Waste Code: U138
Waste Description: Methane, Iodo- (Or) Methyl Iodide

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U141
Waste Description: 1,3-Benzodioxole, 5-(1-Propenyl)- (Or) Isosafrole

Waste Code: U142
Waste Description: 1,3,4-Metheno-2h-Cyclobuta[Cd]Pentalen-2-One, 1,1a,3,3a,4,5,5,5a,5b,6-Decachlorooctahydro- (Or) Kepone

Waste Code: U143
Waste Description: 2-Butenoic Acid, 2-Methyl-, 7-[[2,3-Dihydroxy-2-(1-Methoxyethyl)-3-Methyl-1-Oxobutoxy]Methyl]-2,3,5,7a-Tetrahydro-1h-Pyrrolizin-1-Yl Ester, [1s-[1alpha(Z), 7(2s*,3r*), 7aalpha]]- (Or) Lasiocarpine

Waste Code: U144
Waste Description: Acetic Acid, Lead(2+) Salt (Or) Lead Acetate

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U145
Waste Description: Lead Phosphate (Or) Phosphoric Acid, Lead(2+) Salt (2:3)

Waste Code: U146
Waste Description: Lead Subacetate (Or) Lead, Bis(Acetato-O)Tetrahydroxytri-

Waste Code: U147
Waste Description: 2,5-Furandione (Or) Maleic Anhydride

Waste Code: U148
Waste Description: 3,6-Pyridazinedione, 1,2-Dihydro- (Or) Maleic Hydrazide

Waste Code: U149
Waste Description: Malononitrile (Or) Propanedinitrile

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U151
Waste Description: Mercury

Waste Code: U152
Waste Description: 2-Propenenitrile, 2-Methyl- (I,T) (Or) Methacrylonitrile (I,T)

Waste Code: U153
Waste Description: Methanethiol (I,T) (Or) Thiomethanol (I,T)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U155
Waste Description: 1,2-Ethanediamine, N,N-Dimethyl-N'-2-Pyridinyl-N'-(2-Thienylmethyl)- (Or) Methapyrilene

Waste Code: U156
Waste Description: Carbonochloridic Acid, Methyl Ester, (I,T) (Or) Methyl Chlorocarbonate (I,T)

Waste Code: U157
Waste Description: 3-Methylcholanthrene (Or) Benz[J]Aceanthrylene, 1,2-Dihydro-3-Methyl-

Waste Code: U158
Waste Description: 4,4'-Methylenebis(2-Chloroaniline) (Or) Benzenamine, 4,4'-Methylenebis[2-Chloro-

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U162
Waste Description: 2-Propenoic Acid, 2-Methyl-, Methyl Ester (I,T) (Or) Methyl

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Methacrylate (I,T)

Waste Code: U163
Waste Description: Guanidine, N-Methyl-N'-Nitro-N-Nitroso- (Or) Mnng

Waste Code: U164
Waste Description: 4(1h)-Pyrimidinone, 2,3-Dihydro-6-Methyl-2-Thioxo- (Or) Methylthiouracil

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U166
Waste Description: 1,4-Naphthalenedione (Or) 1,4-Naphthoquinone

Waste Code: U167
Waste Description: 1-Napthalenamine (Or) Alpha-Naphthylamine

Waste Code: U168
Waste Description: 2-Napthalenamine (Or) Beta-Naphthylamine

Waste Code: U169
Waste Description: Benzene, Nitro- (Or) Nitrobenzene (I,T)

Waste Code: U170
Waste Description: P-Nitrophenol (I,T) (Or) Phenol, 4-Nitro-

Waste Code: U171
Waste Description: 2-Nitropropane (I,T) (Or) Propane, 2-Nitro- (I,T)

Waste Code: U172
Waste Description: 1-Butanamine, N-Butyl-N-Nitroso- (Or) N-Nitrosodi-N-Butylamine

Waste Code: U173
Waste Description: Ethanol, 2,2'-(Nitrosoimino)Bis- (Or) N-Nitrosodiethanolamine

Waste Code: U174
Waste Description: Ethanamine, N-Ethyl-N-Nitroso- (Or) N-Nitrosodiethylamine

Waste Code: U176
Waste Description: N-Nitroso-N-Ethylurea (Or) Urea, N-Ethyl-N-Nitroso-

Waste Code: U177
Waste Description: N-Nitroso-N-Methylurea (Or) Urea, N-Methyl-N-Nitroso-

Waste Code: U178
Waste Description: Carbamic Acid, Methylnitroso-, Ethyl Ester (Or) N-Nitroso-N-Methylurethane

Waste Code: U179
Waste Description: N-Nitrosopiperidine (Or) Piperidine, 1-Nitroso-

Waste Code: U180
Waste Description: N-Nitrosopyrrolidine (Or) Pyrrolidine, 1-Nitroso-

Waste Code: U181
Waste Description: 5-Nitro-O-Toluidine (Or) Benzenamine, 2-Methyl-5-Nitro

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U182
Waste Description: 1,3,5-Trioxane, 2,4,6-Trimethyl- (Or) Paraldehyde

Waste Code: U183
Waste Description: Benzene, Pentachloro- (Or) Pentachlorobenzene

Waste Code: U184
Waste Description: Ethane, Pentachloro- (Or) Pentachloroethane

Waste Code: U185
Waste Description: Benzene, Pentachloronitro- (Or) Pentachloronitrobenzene (Pcnb)

Waste Code: U186
Waste Description: 1,3-Pentadiene (I) (Or) 1-Methylbutadiene (I)

Waste Code: U187
Waste Description: Acetamide, N-(4-Ethoxyphenyl)- (Or) Phenacetin

Waste Code: U188
Waste Description: Phenol

Waste Code: U189
Waste Description: Phosphorus Sulfide (R) (Or) Sulfur Phosphide (R)

Waste Code: U190
Waste Description: 1,3-Isobenzofurandione (Or) Phthalic Anhydride

Waste Code: U191
Waste Description: 2-Picoline (Or) Pyridine, 2-Methyl-

Waste Code: U192
Waste Description: Benzamide, 3,5-Dichloro-N-(1,1-Dimethyl-2-Propynyl)- (Or) Pronamide

Waste Code: U193
Waste Description: 1,2-Oxathiolane, 2,2-Dioxide (Or) 1,3-Propane Sultone

Waste Code: U194
Waste Description: 1-Propanamine (I,T) (Or) N-Propylamine (I,T)

Waste Code: U196
Waste Description: Pyridine

Waste Code: U197
Waste Description: 2,5-Cyclohexadiene-1,4-Dione (Or) P-Benzoquinone

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U202
Waste Description: 1,2-Benzisothiazol-3(2h)-One, 1,1-Dioxide, & Salts (Or) Saccharin, & Salts

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U203
Waste Description: 1,3-Benzodioxole, 5-(2-Propenyl)- (Or) Safrole

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U206
Waste Description: D-Glucose, 2-Deoxy-2-[[(Methylnitrosoamino)-Carbonyl]Amino]- (Or) Glucopyranose, 2-Deoxy-2-(3-Methyl-3-Nitrosoureido)-,D- (Or) Streptozotocin

Waste Code: U207
Waste Description: 1,2,4,5-Tetrachlorobenzene (Or) Benzene, 1,2,4,5-Tetrachloro-

Waste Code: U208
Waste Description: 1,1,1,2-Tetrachloroethane (Or) Ethane, 1,1,1,2-Tetrachloro-

Waste Code: U209
Waste Description: 1,1,2,2-Tetrachloroethane (Or) Ethane, 1,1,2,2-Tetrachloro-

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U213
Waste Description: Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)

Waste Code: U214
Waste Description: Acetic Acid, Thallium(1+) Salt (Or) Thallium(I) Acetate

Waste Code: U215
Waste Description: Carbonic Acid, Dithallium(1+) Salt (Or) Thallium(I) Carbonate

Waste Code: U216
Waste Description: Thallium Chloride Tlcl (Or) Thallium(I) Chloride

Waste Code: U217
Waste Description: Nitric Acid, Thallium(1+) Salt (Or) Thallium(I) Nitrate

Waste Code: U218
Waste Description: Ethanethioamide (Or) Thioacetamide

Waste Code: U219
Waste Description: Thiourea

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U221
Waste Description: Benzenediamine, Ar-Methyl- (Or) Toluenediamine

Waste Code: U222

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Description: Benzenamine, 2-Methyl-, Hydrochloride (Or) O-Toluidine Hydrochloride

Waste Code: U223
Waste Description: Benzene, 1,3-Diisocyanatomethyl- (R,T) (Or) Toluene Diisocyanate (R,T)

Waste Code: U225
Waste Description: Bromoform (Or) Methane, Tribromo-

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U227
Waste Description: 1,1,2-Trichloroethane (Or) Ethane, 1,1,2-Trichloro-

Waste Code: U228
Waste Description: Ethene, Trichloro- (Or) Trichloroethylene

Waste Code: U234
Waste Description: 1,3,5-Trinitrobenzene (R,T) (Or) Benzene, 1,3,5-Trinitro-

Waste Code: U235
Waste Description: 1-Propanol, 2,3-Dibromo-, Phosphate (3:1) (Or) Tris(2,3,-Dibromopropyl) Phosphate

Waste Code: U236
Waste Description: 2,7-Naphthalenedisulfonic Acid,3,3'-[(3,3'-Dimethyl[1,1'-Biphenyl]-4,4'-Diyl)Bis(Azo)Bis[5-Amino -4-Hydroxy]-, Tetrasodium Salt (Or) Trypan Blue

Waste Code: U237
Waste Description: 2,4-(1h,3h)-Pyrimidinedione, 5-[Bis(2-Chloroethyl)Amino]- (Or) Uracil Mustard

Waste Code: U238
Waste Description: Carbamic Acid, Ethyl Ester (Or) Ethyl Carbamate (Urethane)

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U243
Waste Description: 1-Propene, 1,1,2,3,3,3-Hexachloro- (Or) Hexachloropropene

Waste Code: U244
Waste Description: Thioperoxydicarbonic Diamide [(H2n)C(S)]2s2, Tetramethyl- (Or) Thiram

Waste Code: U246
Waste Description: Cyanogen Bromide (Cn)Br

Waste Code: U247
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Methoxy- (Or) Methoxychlor

Waste Code: U248

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenyl-Butyl)-, & Salts, When Present At Concentrations Of 0.3% Or Less (Or) Warfarin, & Salts, When Present At Concentrations Of 0.3% Or Less

Waste Code: U249
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Of 10% Or Less

Waste Code: U271
Waste Description: Benomyl (Or) Carbamic Acid, [1-[(Butylamino)Carbonyl]-1h-Benzimidazol-2-Yl]-, Methyl Ester

Waste Code: U277
Waste Description: Sulfallate (Or) Carbamodithioic Acid, Diethyl-, 2-Chloro-2-Propenyl Ester

Waste Code: U278
Waste Description: Bendiocarb (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-, Methyl Carbamate

Waste Code: U279
Waste Description: U279

Waste Code: U280
Waste Description: Barban (Or) Carbamic Acid, (3-Chlorophenyl)-, 4-Chloro-2-Butynyl Ester

Waste Code: U328
Waste Description: Benzenamine, 2-Methyl- (Or) O-Toluidine

Waste Code: U353
Waste Description: Benzenamine, 4-Methyl- (Or) P-Toluidine

Waste Code: U359
Waste Description: Ethanol, 2-Ethoxy- (Or) Ethylene Glycol Monoethyl Ether

Waste Code: U364
Waste Description: Bendiocarb Phenol (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-

Waste Code: U365
Waste Description: H-Azepine-1-Carbothioic Acid, Hexahydro-, S-Ethyl Ester (Or) Molinate

Waste Code: U366
Waste Description: Dazomet (Or) 2h-1,3,5-Thiadiazine- 2-Thione, Tetrahydro-3,5-Dimethyl-

Waste Code: U367
Waste Description: 7-Benzofuranol, 2,3-Dihydro-2,2-Dimethyl- (Or) Carbofuran Phenol

Waste Code: U372
Waste Description: Carbamic Acid, 1h-Benzimidazol-2-Yl, Methyl Ester (Or) Carbendazim

Waste Code: U373
Waste Description: Carbamic Acid, Phenyl-, 1-Methylethyl Ester (Or) Propham

Waste Code: U375
Waste Description: Carbamic Acid, Butyl-, 3-Iodo-2-Propynyl Ester (Or) 3-Iodo-2-Propynyl N-Butylcarbamate

Waste Code: U376
Waste Description: Carbamodithioic Acid, Dimethyl-, Tetraanhydrosulfide With

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Orthothiosetenious Acid (Or) Selenium, Tetrakis (Dimethyldithiocarbamate)

Waste Code: U377
Waste Description: Carbamodithioic Acid, Methyl-, Monopotassium Salt (Or) Potassium N-Methyldithiocarbamate

Waste Code: U378
Waste Description: Carbamodithioic Acid, (Hydroxymethyl) Methyl-, Monopotassium Salt (Or) Potassium N-Hydroxymethyl- N-Methyldi-Thiocarbamate

Waste Code: U379
Waste Description: Sodium Dibutyldithiocarbamate (Or) Carbamodithioic Acid, Dibutyl, Sodium Salt

Waste Code: U381
Waste Description: Carbamodithioic Acid, Diethyl-, Sodium Salt (Or) Sodium Diethyldithiocarbamate

Waste Code: U382
Waste Description: Carbamodithioic Acid, Dimethyl-, Sodium Salt (Or) Sodium Dimethyldithiocarbamate

Waste Code: U383
Waste Description: Carbamodithioic Acid, Dimethyl, Potassium Salt (Or) Potassium Dimethyldithiocarbamate

Waste Code: U384
Waste Description: Carbamodithioic Acid, Methyl-, Monosodium Salt (Or) Metam Sodium

Waste Code: U385
Waste Description: Carbamothioic Acid, Dipropyl-, S-Propyl Ester

Waste Code: U386
Waste Description: Carbamothioic Acid, Cyclohexylethyl-, S-Ethyl Ester (Or) Cycloate

Waste Code: U387
Waste Description: Carbamothioic Acid, Dipropyl-, S-(Phenylmethyl) Ester (Or) Prosulfocarb

Waste Code: U389
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3,3-Trichloro-2-Propenyl) Ester (Or) Triallate

Waste Code: U390
Waste Description: Carbamothioic Acid, Dipropyl-, S-Ethyl Ester (Or) Eptc

Waste Code: U391
Waste Description: Carbamothioic Acid, Butylethyl-, S-Propyl Ester (Or) Pebulate

Waste Code: U392
Waste Description: Butylate (Or) Carbamothioic Acid, Bis(2-Methylpropyl)-, S-Ethyl Ester

Waste Code: U393
Waste Description: Copper, Bis(Dimethylcarbamodithioato-S,S')- (Or) Copper Dimethyldithiocarbamate

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Waste Code: U394
Waste Description: A2213 (Or) Ethanimidothioic Acid, 2-(Dimethylamino)-N-Hydroxy-2-Oxo-, Methyl Ester

Waste Code: U395
Waste Description: Diethylene Glycol, Dicarbamate (Or) Ethanol, 2,2'-Oxybis-, Dicarbamate

Waste Code: U396
Waste Description: Ferbam (Or) Iron, Tris(Dimethylcarbamodithioato-S,S')-,

Waste Code: U400
Waste Description: Bis(Pentamethylene)Thiuram Tetrasulfide (Or) Piperidine, 1,1'-(Tetrathiodicarbonothioyl)-Bis-

Waste Code: U401
Waste Description: Bis(Dimethylthiocarbamoyl) Sulfide (Or) Tetramethylthiuram Monosulfide

Waste Code: U402
Waste Description: Tetrabutylthiuram Disulfide (Or) Thioperoxydicarbonic Diamide, Tetrabutyl

Waste Code: U403
Waste Description: Disulfiram (Or) Thioperoxydicarbonic Diamide, Tetraethyl

Waste Code: U404
Waste Description: U404

Waste Code: U407
Waste Description: Ethyl Ziram

Waste Code: U409
Waste Description: Carbamic Acid, [1,2-Phenylenebis (Iminocarbonothioyl)]Bis-, Dimethyl Ester (Or) Thiophanate-Methyl

Waste Code: U410
Waste Description: Ethanimidothioic Acid, N,N'-[Thiobis[(Methylimino)Carbonyloxy]]Bis-, Dimethyl Ester (Or) Thiodicarb

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN	
Legal Status:	Private
Date Became Current:	20040407
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH STREET STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status:	Not reported
Date Became Current:	20040129
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78705
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20040407
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Other

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20040407
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20080819
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20100316
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE STATE OF TEXAS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20060601
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20080819
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20040407
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH STREET STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20060601
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH STREET STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20100316
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Private
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM	
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78712
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN	
Legal Status:	Not reported
Date Became Current:	20040407
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78705
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Other
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20060601
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS SYSTEM
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712-5709
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20040407
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH STREET STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE UNIVERSITY OF TEXAS SYSTEM
Legal Status:	Other
Date Became Current:	20020313
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78712-5709
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status:	Not reported
Date Became Current:	20040129
Date Ended Current:	Not reported
Owner/Operator Address:	304 W 24TH ST STE 202
Owner/Operator City,State,Zip:	AUSTIN, TX 78705
Owner/Operator Telephone:	512-471-7137
Owner/Operator Telephone Ext:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Not reported
Date Became Current: 20040407
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH ST STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 304 W 24TH STREET STE 202
Owner/Operator City,State,Zip: AUSTIN, TX 78712
Owner/Operator Telephone: 512-471-7137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100301
Handler Name: THE UNIVERSITY OF TEXAS SYSTEM
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120301
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140301
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160301
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180301
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20200301
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220301
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19831129
Handler Name: UNIV OF TEXAS AUSTIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040129
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040407
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Receive Date: 20060606
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060721
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080819
Handler Name: THE UNIVERSITY OF TEXAS SYSTEM
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100316
Handler Name: THE UNIVERSITY OF TEXAS SYSTEM
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140523
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140924
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150812
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160308
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160308
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160510
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160818
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170504
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170504
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170730
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180425
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200813
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200824
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20220520
Handler Name:	THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220728
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220803
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221118
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221213
Handler Name: THE UNIVERSITY OF TEXAS MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Receive Date: 19920331
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN -MAIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940415
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN-MAIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960301
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980125
Handler Name: MAIN CAMPUS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000125
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040301
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060301
Handler Name: THE UNIVERSITY OF TEXAS AT AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080301
Handler Name: THE UNIVERSITY OF TEXAS SYSTEM
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61131
NAICS Description: COLLEGES, UNIVERSITIES, AND PROFESSIONAL SCHOOLS

NAICS Code: 611310
NAICS Description: COLLEGES, UNIVERSITIES, AND PROFESSIONAL SCHOOLS

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20030430
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19861203
Actual Return to Compliance Date:	19870505
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Container Use and Management
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130617
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20130617
Actual Return to Compliance Date:	20130617
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20130807
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20030326
Actual Return to Compliance Date:	20030424
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20030430
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Used Oil - Generators
Date Violation was Determined:	20130617
Actual Return to Compliance Date:	20130617
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20130807
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20130807
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19861203
Actual Return to Compliance Date:	19870505
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20030430
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	LDR - General
Date Violation was Determined:	19871203
Actual Return to Compliance Date:	19880615
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19880615
Enforcement Identifier:	010
Date of Enforcement Action:	19880510
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19861203
Actual Return to Compliance Date: 19870505
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20030326
Actual Return to Compliance Date: 20030424
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130617
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130617
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20200813
Actual Return to Compliance Date:	20201109
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	3
Date of Enforcement Action:	20200825
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Container Use and Management
Date Violation was Determined:	20030326
Actual Return to Compliance Date:	20030424
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20030430
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20130617
Actual Return to Compliance Date: 20130701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20130807
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Container Use and Management
Date Violation was Determined:	20130617
Actual Return to Compliance Date:	20130617
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20130807
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Actual Return to Compliance Date:	20130701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20201130
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Former Citation:	Not reported

Evaluation Date:	19861203
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R6RM
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870505
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130701
Scheduled Compliance Date:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19861203
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R6RM
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870505
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19871203
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19880615
Scheduled Compliance Date:	19880615
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Evaluation Date:	19861203
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R6RM
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870505
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20200813
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20201109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20030326
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20030424
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20130617
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20130617
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

PADS:

Name:	UNIVERSITY OF TEXAS AT AUSTIN
Address:	2617 SPEEDWAY #104,ENV HLTH & SFTY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-5720
EDR ID:	1000429149
EPAID:	TXD980869184
Region:	06
Generator:	Y
Storer:	N
Disposer:	N
Transporter:	N
Smelter:	N
Research Facility:	N
Mailing Address:	2617 SPEEDWAY #104,ENV HLTH & SFTY
Mailing Address 2:	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78705-5720
Mailing Country:	US
Owner Name:	STATE OF TEXAS
Certification Date:	09/26/1990
Contact Name:	CHARLES S JAMISON
Contact Title:	Not reported
Contact Telephone:	512-471-3511
Contact Text:	Not reported
Contact Email:	Not reported

NY MANIFEST:

Name:	UNIVERSITY OF TEXAS
Address:	2617 SPEEDWAY STE 104
City,State,Zip:	AUSTIN, TX 78712-1763
Country:	USA
EPA ID:	TXD980869184
Facility Status:	Not reported
Location Address 1:	2617 SPEDWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

THE UNIVERSITY OF TEXAS MAIN CAMPUS (Continued) **1000429149**

Location City:	AUSTIN
Location State:	TX
Location Zip:	78705
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	TXD980869184
Mailing Name:	UNIVERSITY OF TEXAS
Mailing Contact:	UNIVERSITY OF TEXAS
Mailing Address 1:	P.O. BOX 7580-2617 SPEEDWAY
Mailing Address 2:	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78713
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5124714467

IV1637 **MAIN CAMPUS** **TX IHW CORR ACTION** **S126476560**
East **2617 SPEEDWAY STE 104** **N/A**
< 1/8 **AUSTIN, TX 78712**
0.027 mi.
144 ft. **Site 4 of 4 in cluster IV**

Actual:
559 ft.

Focus Map:
11

IHW CORR ACTION:

Name:	MAIN CAMPUS
Address:	2617 SPEEDWAY STE 104
City,State,Zip:	AUSTIN, TX 78712
Program Id:	66154
Location Desc:	2617 SPEEDWAY STE 104 AUSTIN TX
RN NUM:	RN102797719
Status:	INACTIVE
Status Date:	11/02/2020
EDR Link ID:	66154
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	11/02/2020
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

JV1638 **CITY OF AUSTIN** **TX HIST UST** **S111678607**
ENE **654 W CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 1 of 2 in cluster JV**

Actual:
436 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CITY OF AUSTIN
Address:	654 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0404
HID UST:	404
Inspection:	Not reported
Due:	06/01/2012

JV1639 ENE < 1/8 0.027 mi. 145 ft. | **COA 654 W CESAR CHAVEZ ST AUSTIN, TX** | **TX HIST UST** | **S111678608 N/A**

Site 2 of 2 in cluster JV

Actual: 436 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	COA
Address:	654 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0497
HID UST:	497
Inspection:	Not reported
Due:	06/01/2012

EJ1640 WNW < 1/8 0.027 mi. 145 ft. | **RIVERSIDE CHEVRON 400 S CONGRESS AVE AUSTIN, TX 78704** | **TX LPST TX UST TX ASBESTOS TX Financial Assurance TX GCC** | **U002262967 N/A**

Site 15 of 19 in cluster EJ

Actual: 454 ft.

Focus Map: 14

LPST:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	121027
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	07/21/2020
Entered Date:	09/01/2020
Reported Date:	07/21/2020
Closure Date:	11/19/2021
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT500FT
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	07/21/2020
Case Start Date:	11/19/2021
Reference Number:	RN103730206
Project Manager:	REIDE

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0033141
LPST Id:	107107
Facility Location:	400 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN

RIVERSIDE CHEVRON (Continued) **U002262967**

Discovered Date:	07/29/1993
Entered Date:	09/15/1993
Reported Date:	07/29/1993
Closure Date:	10/13/1994
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	MARK GRUGGETT
Responsible Party Address:	520 POST OAK RD STE 250
Responsible Party City,St,Zip:	HOUSTON, TX 77027
Responsible Party Telephone:	214/445-1207
Reported Date:	07/29/1993
Case Start Date:	10/13/1994
Reference Number:	RN103730206
Project Manager:	HWELCH

UST:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041730
AI Number:	33141
Facility Type:	RETAIL
Facility Begin Date:	12/01/1986
Facility Status:	ACTIVE
Additional ID:	263595602003195
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	SCOTT D CARTER,PRESIDENT
Contact Organization Name:	RIVERSIDE CHEVRON
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129702523
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	scarter81@gmail.com
Signature Date On Earliest Reg Form:	08/09/2022
Signature Name/Title On Earliest Reg Form:	SCOTT CARTER,PRES
Application Received Date On Earliest Reg Form:	08/12/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

RIVERSIDE CHEVRON (Continued) **U002262967**

Operator:

Princ ID:	713403352020309
Additional ID:	263595602003195
Ai Number:	33141
Operator CN:	CN605828516
Operator Name:	400 S AVENUE LLC
Operator Effective Begin Date:	08/12/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605828524
Owner Last Name:	RIVERSIDE PARTNERS SW UST LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	906405442020309
Additional ID:	263595602003195
AI Number:	33141
Owner Effective Begin Date:	09/18/2020
State Tax ID:	32075867781
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	45109
Cert ID:	374981
AI Number:	33141
Self Certification Date:	08/09/2022

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	SCOTT CARTER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	358195
AI Number:	33141
Self Certification Date:	07/01/2021
Signature Name/Title:	SCOTT CARTER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	346020
AI Number:	33141
Self Certification Date:	10/02/2020
Signature Name/Title:	SCOTT CARTER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	329363
AI Number:	33141
Self Certification Date:	12/03/2019

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	45109
Cert ID:	312491
AI Number:	33141
Self Certification Date:	11/30/2018
Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	45109
Cert ID:	295729
AI Number:	33141
Self Certification Date:	12/08/2017
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	45109
Cert ID:	279319
AI Number:	33141
Self Certification Date:	12/15/2016

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	262937
AI Number:	33141
Self Certification Date:	12/16/2015
Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	245334
AI Number:	33141
Self Certification Date:	11/21/2014
Signature Name/Title:	KEN SLACK COOWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	228388
AI Number:	33141
Self Certification Date:	12/04/2013

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45109
Cert ID:	22511
AI Number:	33141
Self Certification Date:	11/21/2012
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22510
AI Number:	33141
Self Certification Date:	12/08/2011
Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22509
AI Number:	33141
Self Certification Date:	11/22/2010

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22508
AI Number:	33141
Self Certification Date:	12/07/2009
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22507
AI Number:	33141
Self Certification Date:	11/18/2008
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22506
AI Number:	33141
Self Certification Date:	12/03/2007

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22505
AI Number:	33141
Self Certification Date:	11/28/2006
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22504
AI Number:	33141
Self Certification Date:	11/21/2005
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22503
AI Number:	33141
Self Certification Date:	11/17/2004

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22502
AI Number:	33141
Self Certification Date:	01/07/2004
Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22501
AI Number:	33141
Self Certification Date:	12/04/2002
Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22500
AI Number:	33141
Self Certification Date:	11/19/2001

RIVERSIDE CHEVRON (Continued) **U002262967**

Signature Name/Title:	KEN SLACK CO-OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45109
Cert ID:	22499
AI Number:	33141
Self Certification Date:	01/09/2001
Signature Name/Title:	KEN SLACK CO OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87431
Facility ID:	45109
Ai Number:	33141
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1970
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	22767
UST ID:	87431
AI Number:	33141
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1997

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87432
Facility ID:	45109
Ai Number:	33141
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1970
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	22768
UST ID:	87432
AI Number:	33141
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1997

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87433
Facility ID:	45109
Ai Number:	33141
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1970
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	22769
UST ID:	87433
AI Number:	33141
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y

RIVERSIDE CHEVRON (Continued) **U002262967**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1997

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87434
Facility ID:	45109
Ai Number:	33141
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/15/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	22770
UST ID:	87434
AI Number:	33141
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

RIVERSIDE CHEVRON (Continued) **U002262967**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169851
Facility ID:	45109
Ai Number:	33141
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1970
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	44
UST Comprt ID:	22771
UST ID:	169851
AI Number:	33141
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169852
Facility ID:	45109
Ai Number:	33141
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1970
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

RIVERSIDE CHEVRON (Continued) **U002262967**

Compartment Records:

Tank ID:	5
Tank Capacity:	44
UST Comprt ID:	22772
UST ID:	169852
AI Number:	33141
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RIVERSIDE PARTNERS SW UST LLC
Contact Mailing Address (Delivery):	2710 BEE CAVES RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 5642
Phone Number/Ext:	512 3283240/0
Contact Fax Number/Ext:	/
Contact Email Address:	billpc@aol.com
Contact Address Deliverable:	Y
Facility ID:	45109
Additional ID:	263595602003195
Princ ID:	906405442020309

RIVERSIDE CHEVRON (Continued) **U002262967**

AI Number:	33141
Facility Name:	RIVERSIDE CHEVRON
AR Number:	82218
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	SCOTT D CARTER/PRESIDENT

ASBESTOS:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/13/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/18/2013
Date Routed by Supervisor:	03/18/2013
Date Routed to PSQA:	03/18/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

RIVERSIDE CHEVRON (Continued) **U002262967**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	04/11/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.9
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/14/2014
Date Routed by Supervisor:	04/16/2014
Date Routed to PSQA:	04/17/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

RIVERSIDE CHEVRON (Continued) **U002262967**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	272793
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2021
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000022139
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2022

RIVERSIDE CHEVRON (Continued) **U002262967**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	240800
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2020
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000012905
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	254895
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2020
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000012905
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	223196

RIVERSIDE CHEVRON (Continued) **U002262967**

AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2019
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000000564
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	205936
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2018
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	188808
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2017

RIVERSIDE CHEVRON (Continued) **U002262967**

Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	172989
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2016
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	155238
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2015
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

RIVERSIDE CHEVRON (Continued) **U002262967**

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	136278
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2014
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	118080
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2013
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	15786
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/31/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	1819
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

RIVERSIDE CHEVRON (Continued) **U002262967**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2011
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	15786
Coverage Amount:	1000000
Coverage Expiration Date:	01/31/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	26912
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2011
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	15786
Coverage Amount:	1000000
Coverage Expiration Date:	01/31/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	26913
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2010
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338

RIVERSIDE CHEVRON (Continued) **U002262967**

Policy Number:	15786
Coverage Amount:	1000000
Coverage Expiration Date:	01/31/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	26914
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2008
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	15786
Coverage Amount:	1000000
Coverage Expiration Date:	01/31/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	45109
Finass ID:	26915
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/31/2007
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	15786
Coverage Amount:	1000000
Coverage Expiration Date:	01/31/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

RIVERSIDE CHEVRON (Continued) **U002262967**

Region:	2
Facility ID:	45109
Finass ID:	26916
AI:	33141
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	08/12/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	121027
Contamination Description:	UNKNOWN, GASOLINE
Date Of Earliest Known Contamination Confirmation:	7/21/2020
Enforcement Status - Level Of Agency Response:	1B -
Enforcement Status - Site Activity Status:	1A - Contamination Confirmed
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	Not reported
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	121027
Contamination Description:	UNKNOWN, GASOLINE
Date Of Earliest Known Contamination Confirmation:	7/21/2020
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 - Action Completed
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	Not reported
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported

RIVERSIDE CHEVRON (Continued) **U002262967**

Location: Not reported
Data Quality 2: Not reported

EJ1641 **RIVERSIDE CHEVRON** **TX RDR** **S127530435**
WNW **400 SOUTH CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 16 of 19 in cluster EJ**

Actual:
454 ft.

Focus Map:
14

RDR:

RDR ID:	28853
Facility ID:	33141
RN:	Not reported
CN:	Not reported
Name:	RIVERSIDE CHEVRON
Address:	400 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/17/2020
Due Date:	10/16/2020
Tank Owner:	KEN SLACK
Contact Person:	KEN SLACK
Report:	Phase II
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	9/1/2020
Project Manager:	Ross Eide
Team:	Team 2
New LPST Number:	121027
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

EJ1642 **RIVERSIDE SHELLSHAPE DIAGN CTR** **EDR Hist Auto** **1020260047**
WNW **400 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.027 mi.
145 ft. **Site 17 of 19 in cluster EJ**

Actual:
454 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1971	RIVERSIDE SHELL SERVICE CENTER	Gasoline Service Stations
1972	RIVERSIDE SHELLSHAPE DIAGN CTR	Gasoline Service Stations
1974	SLACK SHELLSHAPE	Gasoline Service Stations
1975	SLACK SHELLSHAPE	Gasoline Service Stations
1976	SLACK SHELLSHAPE	Gasoline Service Stations
1977	SLACK SHELLSHAPE	Gasoline Service Stations
1978	SLACK SHELLSHAPE	Gasoline Service Stations
1979	SLACK SHELLSHAPE	Gasoline Service Stations
1980	SLACK SHELLSHAPE	Gasoline Service Stations

RIVERSIDE SHELLSHAPE DIAGN CTR (Continued) **1020260047**

1982	SLACK SHELLSHAPE	Gasoline Service Stations
1983	SLACK SHELLSHAPE	Gasoline Service Stations
1987	SLACKS EDDIE COMPANY	New And Used Car Dealers
1988	SLACKS EDDIE COMPANY	New And Used Car Dealers
1989	SLACKS EDDIE COMPANY	New And Used Car Dealers, NEC
1990	SLACKS EDDIE COMPANY	New And Used Car Dealers, NEC
1991	SLACKS EDDIE COMPANY	New And Used Car Dealers, NEC
1992	SLACKS EDDIE COMPANY	New And Used Car Dealers, NEC
1993	SLACKS EDDIE COMPANY	Gasoline Service Stations
1994	SLACKS EDDIE COMPANY	Gasoline Service Stations
1995	SLACKS EDDIE COMPANY	Gasoline Service Stations
1996	SLACKS EDDIE COMPANY	Gasoline Service Stations
1997	SLACKS EDDIE COMPANY	Gasoline Service Stations
1998	SLACKS EDDIE COMPANY	Gasoline Service Stations
2001	SLACK BROTHERS INC	Gasoline Service Stations
2002	SLACK BROTHERS INC	Gasoline Service Stations
2003	SLACK BROTHERS INC	Gasoline Service Stations
2004	SLACK BROTHERS INC	Gasoline Service Stations
2005	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2006	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2007	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2008	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2009	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2010	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2011	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2012	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2013	SLACK BROTHERS INC	Gasoline Service Stations, NEC
2014	SLACK BROTHERS INC	Gasoline Service Stations, NEC

EJ1643 **RIVERSIDE CHEVRON** **TX HIST UST** **S128728824**
WNW **400 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 18 of 19 in cluster EJ**

Actual:
454 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	RIVERSIDE CHEVRON
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	720
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

EJ1644 **R.E. LEIGH** **TX HIST UST** **S128729249**
WNW **400 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 19 of 19 in cluster EJ**

Actual:
454 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	R.E. LEIGH
Address:	400 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0355

R.E. LEIGH (Continued) **S128729249**

HID UST: 355
Inspection: 04/24/2009
Due: 04/24/2012

JI1645 **1801 03 DYE SLS & SERV** **EDR Hist Auto** **1013767988**
WNW **1801 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.027 mi.
145 ft. **Site 3 of 3 in cluster JI**

Actual:
534 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	1801 03 DYE SLS & SERV	GASOLINE STATIONS

DR1646 **GALVAN IGNACIO CLDO** **EDR Hist Cleaner** **1013782865**
NE **512 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 33 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	SMITH & WEAVER C TAIL	CLOTHES PRESSERS AND CLEANERS
1911	SMITH & WEAVER C TAIL	DYERS AND SCOURERS
1922	DOTSON ISHMAEL C	CLOTHES CLEANERS AND PRESSERS
1935	GALVAN IGNACIO CLDO	CLOTHES PRESSERS AND CLEANERS

DR1647 **SHARPS SERVICE STA** **EDR Hist Auto** **1013762260**
NE **512 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.027 mi.
145 ft. **Site 34 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	SHARPS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	AUSTIN BODY WORKS	AUTOMOBILE REPAIRING

IL1648 **D & S SERVICE STATION** **EDR Hist Auto** **1013760030**
NNE **500 7TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.028 mi.
146 ft. **Site 3 of 21 in cluster IL**

Actual:
492 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	D & S SERVICE STATION	GASOLINE STATIONS

IL1649 NNE < 1/8 0.028 mi. 146 ft. — **D&S SERV STA**, **500 7TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775188** / **N/A**

Site 4 of 21 in cluster IL

Actual: 492 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	D&S SERV STA	GASOLINE STATIONS

IL1650 NNE < 1/8 0.028 mi. 146 ft. — **D & S SERVICE STATION**, **500 7TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013753902** / **N/A**

Site 5 of 21 in cluster IL

Actual: 492 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	D & S SERVICE STATION	GASOLINE STATIONS
1980	D & S SERVICE STATION	GASOLINE STATIONS
1984	D & S SERVICE STATION	GASOLINE STATIONS

1651 WNW < 1/8 0.028 mi. 146 ft. — **MONTGOMERY WARD 2276**, **10600 N LAMAR BLVD**, **AUSTIN, TX 78753** — **TX Ind. Haz Waste** — **S102750142** / **N/A**

Actual: 742 ft. Ind. Haz Waste:

Focus Map: 3

Name:	MONTGOMERY WARD 2276
Address:	10600 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66715
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	10600 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MONTGOMERY WARD LLC
Contact Name:	AJ GROSSI

MONTGOMERY WARD 2276 (Continued) **S102750142**

Contact Telephone Number:	Not reported
Mailing Address:	10600 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787533462
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21977
Site Owner Tax ID:	362659374
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030711
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MONTGOMERY WARD LLC
Operator Address:	10600 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	13626593746
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MONTGOMERY WARD LLC
Owner Mailing Address:	10600 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	13626593746
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON

MONTGOMERY WARD 2276 (Continued) **S102750142**

Contact Address:	10600 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	10600 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	AJ GROSSI
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	10600 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

IP1652 **LUDWIG ROBERT W TAILOR DYER** **EDR Hist Cleaner** **1013783502**
NNE **402 E 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
146 ft. **Site 5 of 5 in cluster IP**

Actual:
489 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1901	LUDWIG ROBERT W TAILOR DYER	DYERS AND SCOURERS

BV1653 **FERDINANDTSEN G E N** **EDR Hist Cleaner** **1013782920**
West **2406 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
146 ft. **Site 5 of 5 in cluster BV**

Actual:
590 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	FERDINANDTSEN G E N	LAUNDRIES
1929	PETERSON EDW DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

DL1654 **M.H. CROCKETT** **TX HIST UST** **S111678734**
WNW **306 W WEST 29TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
146 ft. **Site 12 of 17 in cluster DL**

Actual:
466 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	M.H. CROCKETT
Address:	306 W WEST 29TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0358
HID UST:	358
Inspection:	Not reported
Due:	06/01/2012

CV1655 **BIGGS & CO TAILORS** **EDR Hist Cleaner** **1013783980**
ESE **1007 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
146 ft. **Site 10 of 14 in cluster CV**

Actual:
513 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1929	BIGGS & CO TAILORS	CLOTHES CLEANERS AND PRESSERS

DC1656 **C.B. SMITH MOTORS** **TX HIST UST** **S128729345**
WNW **805 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
147 ft. **Site 8 of 11 in cluster DC**

Actual:
463 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	C.B. SMITH MOTORS
Address:	805 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0626
HID UST:	626
Inspection:	04/29/2009
Due:	04/29/2012

DC1657 **AUSTIN TOYOTA** **TX LPST** **1000412168**
WNW **1127 W 6TH STREET** **TX UST** **TXD052642477**
< 1/8 **AUSTIN, TX 78703** **TX VCP**
0.028 mi. **RCRA NonGen / NLR**
147 ft. **Site 9 of 11 in cluster DC** **FINDS**
ECHO

Actual:
463 ft.

Focus Map:
11

LPST:

Name:	AUSTIN TOYOTA
Address:	805 W 5TH ST
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0044471
LPST Id:	099907
Facility Location:	W 5TH ST VCP 1333

AUSTIN TOYOTA (Continued) **1000412168**

TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/12/1991
Entered Date:	09/25/1991
Reported Date:	08/12/1991
Closure Date:	01/06/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	STEVE KILPATRICK
Responsible Party Address:	211 W FORT ST
Responsible Party City,St,Zip:	DETROIT, MI 48275 1019
Responsible Party Telephone:	313/222-6285
Reported Date:	08/12/1991
Case Start Date:	01/06/1992
Reference Number:	RN101053700
Project Manager:	HWELCH

UST:

Name:	AUSTIN TOYOTA
Address:	805 W 5TH ST
City,State,Zip:	AUSTIN, TX 787035401
AI Number:	44471
Facility Type:	UNKNOWN
Facility Begin Date:	02/10/1987
Facility Status:	INACTIVE
Additional ID:	974697452002154
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	,
Contact Organization Name:	AUSTIN TOYOTA
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124785676
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/12/1987
Signature Name/Title On Earliest Reg Form:	PHILIP VERNON,MGR.
Application Received Date On Earliest Reg Form:	01/16/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

AUSTIN TOYOTA (Continued) **1000412168**

Owner:

Owner CN:	CN601261209
Owner Last Name:	AUSTIN TOYOTA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	982697452002154
Additional ID:	974697452002154
AI Number:	44471
Owner Effective Begin Date:	02/10/1987
State Tax ID:	17416688343
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171134
Facility ID:	72689
Ai Number:	44471
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

AUSTIN TOYOTA (Continued) **1000412168**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	40
UST Comprt ID:	104870
UST ID:	171134
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

AUSTIN TOYOTA (Continued) **1000412168**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171135
Facility ID:	72689
Ai Number:	44471
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

AUSTIN TOYOTA (Continued) **1000412168**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	40
UST Comprt ID:	104871
UST ID:	171135
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

AUSTIN TOYOTA (Continued) **1000412168**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171136
Facility ID:	72689
Ai Number:	44471
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

AUSTIN TOYOTA (Continued) **1000412168**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	40
UST Comprt ID:	104872
UST ID:	171136
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

AUSTIN TOYOTA (Continued) **1000412168**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171137
Facility ID:	72689
Ai Number:	44471
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

AUSTIN TOYOTA (Continued) **1000412168**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	40
UST Comprt ID:	104873
UST ID:	171137
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40

AUSTIN TOYOTA (Continued) **1000412168**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171138
Facility ID:	72689
Ai Number:	44471
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

AUSTIN TOYOTA (Continued) **1000412168**

Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	4
Tank Capacity:	40
UST Comprt ID:	104874
UST ID:	171138
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171139
Facility ID:	72689
Ai Number:	44471
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND

AUSTIN TOYOTA (Continued) **1000412168**

Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	40
UST Comprt ID:	104875
UST ID:	171139
AI Number:	44471
Compartment ID:	A

AUSTIN TOYOTA (Continued) **1000412168**

Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171140
Facility ID:	72689
Ai Number:	44471
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/18/1995
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

AUSTIN TOYOTA (Continued) **1000412168**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	40
UST Comprt ID:	104876
UST ID:	171140
AI Number:	44471
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

AUSTIN TOYOTA (Continued) **1000412168**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1962
Tank Registration Date:	01/16/1987
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	116574
Facility ID:	72689
Ai Number:	44471
Tank Id:	8
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/30/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

AUSTIN TOYOTA (Continued) **1000412168**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	8
Tank Capacity:	500
UST Comprt ID:	104869
UST ID:	116574
AI Number:	44471
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

AUSTIN TOYOTA (Continued) **1000412168**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUSTIN TOYOTA INC
Contact Mailing Address (Delivery):	707 INDUSTRIAL BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 1214
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	72689
Additional ID:	974697452002154
Princ ID:	982697452002154
AI Number:	44471
Facility Name:	AUSTIN TOYOTA
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PHILLIP G VESCOVO/

VCP TCEQ:

Name:	STRAIT MUSIC
Address:	805 W 5TH ST
City,State,Zip:	AUSTIN, TX 78703
Region:	REGION 11 - AUSTIN
Facility ID:	1333
VCP Record Date:	03/20/2001
Facility Type:	RETAIL
PCA Number:	33433
Project Manager:	MPALMIE
Phase:	COMPLETED
Acres at Site:	2.148
REM Program:	VCP
RN Number:	RN101053700
Former Facility Type:	Not reported

AUSTIN TOYOTA (Continued) **1000412168**

Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	03/20/2001
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/13/2003
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	03/15/2001
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2001-05-02 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1333
Leaking Petroleum Storage Registration Tank:	92907
Project Number:	334330
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	208/D; 200-43/D; 200-38
Latitude:	30.27
Longitude:	-97.75

Contact:

REM Program:	VCP
Program ID:	1333
RN Number:	RN101053700
CN Number:	CN600613095
CN Name:	POST WEST AVE LOFTS LP
Role Code:	BILLCONT
Contact Name:	COHEN, SHERRY
Contact Title:	Not reported
Organization Name:	POST WEST AVENUE LOFTS LP
Mailing Address:	4401 NORTHSIDE PKWY NW STE 800
Mailing City:	ATLANTA
Mailing State:	GA
Mailing Zip:	30327
Contact Telephone:	(404) 846-5025
Contact Telephone Ext:	0

AUSTIN TOYOTA (Continued) **1000412168**

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Austin Toyota
Handler Address:	W 6TH STREET
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD052642477
Contact Name:	JOHN KERN
Contact Address:	W 5TH STREET
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Telephone:	512-478-5676
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W 5TH STREET
Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Name:	Austin Toyota
Owner Type:	Private
Operator Name:	Austin Toyota
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

AUSTIN TOYOTA (Continued) **1000412168**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN TOYOTA	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	805 W 5TH STREET
Owner/Operator City,State,Zip:	AUSTIN, TX 78703
Owner/Operator Telephone:	512-478-5676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PETE VESCOVO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

AUSTIN TOYOTA (Continued) **1000412168**

Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN TOYOTA	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	805 W 5TH STREET
Owner/Operator City,State,Zip:	AUSTIN, TX 78703
Owner/Operator Telephone:	512-478-5676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19841024
Handler Name: AUSTIN TOYOTA	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010727
Handler Name: AUSTIN TOYOTA	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AUSTIN TOYOTA (Continued) **1000412168**

FINDS:
Registry ID: 110070167403

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.
Registry ID: 110005052067

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412168
Registry ID:	110005052067
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005052067
Name:	AUSTIN TOYOTA
Address:	1127 W 6TH STREET
City,State,Zip:	AUSTIN, TX 78703

DC1658 **AUSTIN TOYOTA INC** **TX HIST UST** **S128728952**
WNW **805 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
147 ft. **Site 10 of 11 in cluster DC**

Actual:
463 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	AUSTIN TOYOTA INC
Address:	805 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0203
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DR1659 NE < 1/8 0.028 mi. 147 ft. | **ATTAL THOS SHOE REPR 515 6TH E AUSTIN, TX** | **EDR Hist Cleaner** | **1013783965 N/A**

Site 35 of 38 in cluster DR

Actual: 484 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1940	ATTAL THOS SHOE REPR	CLOTHES PRESSERS AND CLEANERS

DA1660 ESE < 1/8 0.028 mi. 147 ft. | **COTHRAN'S TEXACO 700 W 6TH ST AUSTIN, TX** | **TX HIST UST** | **S128728965 N/A**

Site 22 of 25 in cluster DA

Actual: 471 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	COTHRAN'S TEXACO
Address:	700 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0232
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CV1661 WNW < 1/8 0.028 mi. 147 ft. | **BIGGS & CO TAILOR 1007 CONGRESS AVE AUSTIN, TX** | **EDR Hist Cleaner** | **1013782584 N/A**

Site 11 of 14 in cluster CV

Actual: 514 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	BIGGS & CO TAILORS	DYERS AND SCOURERS
1922	BIGGS & CO TAILOR	CLOTHES CLEANERS AND PRESSERS

CV1662 WNW < 1/8 0.028 mi. 147 ft. | **BOBS GARAGE & 1007 CONGRESS AVE SOUTH AUSTIN, TX** | **EDR Hist Auto** | **1013753338 N/A**

Site 12 of 14 in cluster CV

Actual: 514 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	BOBS GARAGE &	AUTOMOBILE REPAIRING

DA1663 WNW < 1/8 0.028 mi. 148 ft. — **DEEP EDDY RUG & CARPET CLEANERS INC**, **512 RIO GRANDE ST**, **AUSTIN, TX 78701** — **EDR Hist Cleaner** — **1013777487** / **N/A**

Site 23 of 25 in cluster DA

Actual: 470 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1975	DEEP EDDY RUG CLEANERS	CARPET AND RUG CLEANERS
1977	DEEP EDDY RUG & CARPET CLRS	Carpet And Upholstery Cleaning
1978	DEEP EDDY RUG & CARPET CLRS	Carpet And Upholstery Cleaning
1979	DEEP EDDY RUG & CARPET CLRS	Carpet And Upholstery Cleaning
1980	DEEP EDDY RUG & CARPET CLEANERS	CARPET AND RUG CLEANERS
1980	DEEP EDDY RUG & CARPET CLRS	Carpet And Upholstery Cleaning
1982	DEEP EDDY RUG AND CARPET CLRS*	Carpet And Upholstery Cleaning
1983	DEEP EDDY RUG AND CARPET CLRS*	Carpet And Upholstery Cleaning
1984	DEEP EDDY RUG CLEANERS INC	CARPET AND RUG CLEANERS
1985	DEEP EDDY RUG CRPT CLNRS INC	Carpet And Upholstery Cleaning

---

DA1664 WNW < 1/8 0.028 mi. 148 ft. — **SPRINKLES BODY SHOP**, **512 RIO GRANDE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013764611** / **N/A**

Site 24 of 25 in cluster DA

Actual: 470 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	SPRINKLES BODY SHOP	AUTOMOBILE REPAIRING
1953	SPRINKLES BODY SHOP	AUTOMOBILE RADIATOR REPAIRING

DA1665 WNW < 1/8 0.028 mi. 148 ft. — **BEE BOP PRINTING**, **512 RIO GRANDE ST**, **AUSTIN, TX 78701** — **TX Ind. Haz Waste**, **TX CENTRAL REGISTRY** — **S102755327** / **N/A**

Site 25 of 25 in cluster DA

Actual: 470 ft. Ind. Haz Waste:

Focus Map: 11

Name:	BEE BOP PRINTING
Address:	512 RIO GRANDE ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	73873
Registration Initial Notification Date:	10/23/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19891023
Land Type:	Not reported
Description of Facility Site Location:	512 Rio Grande, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1

BEE BOP PRINTING (Continued) **S102755327**

Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	BEE BOP PRINTING
Contact Name:	JERRY MOTCHIE
Contact Telephone Number:	512-4748444
Mailing Address:	512 RIO GRANDE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787012716
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28282
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BEE BOP PRINTING
Operator Address:	512 RIOGRANDE ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4748444
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BEE BOP PRINTING
Owner Mailing Address:	512 RIOGRANDE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4748444
Owner Fax:	Not reported
Owner Email Address:	Not reported

BEE BOP PRINTING (Continued) **S102755327**

Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	512 RIOGRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748444
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	512 RIOGRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748444
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JERRY MOTCHIE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	512 RIOGRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4748444
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100710409
Name:	BEE BOP PRINTING
Address:	512 RIO GRANDE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2716
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600304059
Customer Name:	BEE BOP PRINTING
Customer Legal Name:	Bee Bop Printing
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

BEE BOP PRINTING (Continued) **S102755327**

Physical Location Description: 512 Rio Grande, Austin, TX

DL1666 **COA SERVICE CENTER #12** **TX HIST UST** **S128728623**
WNW **300 WEST AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
148 ft. **Site 13 of 17 in cluster DL**

Actual:
464 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	COA SERVICE CENTER #12
Address:	300 WEST AVE
City,State,Zip:	AUSTIN, TX
Id UST:	1913
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DL1667 **ELECTRIC UTILITY** **TX LPST** **S103608274**
WNW **300 WEST AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.028 mi.
148 ft. **Site 14 of 17 in cluster DL**

Actual:
464 ft.

Focus Map:
11

LPST:

Name:	ELECTRIC UTILITY
Address:	300 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0018149
LPST Id:	096554
Facility Location:	300 WEST AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/22/1990
Entered Date:	08/24/1990
Reported Date:	08/22/1990
Closure Date:	05/01/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	JOHN LINNEMANN
Responsible Party Address:	PO BOX 1088
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	512/499-8331
Reported Date:	08/22/1990
Case Start Date:	05/01/1992
Reference Number:	RN100531847
Project Manager:	HWELCH

Ind. Haz Waste:

Name: POLE YARD

ELECTRIC UTILITY (Continued) **S103608274**

Address:	300 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72380
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	02/26/2020
EPA Identification:	TXD981901499
Primary NAICS Code:	221122
Status Change Date:	19870501
Land Type:	Not reported
Description of Facility Site Location:	300 West Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Contact Name:	SUE MURRAY
Contact Telephone Number:	512-3226207
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address2:	ELECTRIC DEPT
Mailing City,State,Zip:	AUSTIN, TX 787041328
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26821
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200227
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Operator Address:	721 BARTON SPRINGS RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA

ELECTRIC UTILITY (Continued) **S103608274**

Operator Telephone:	1-512-3226207
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Owner Mailing Address:	721 BARTON SPRINGS RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-3226207
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	SUE MURRAY
Contact Title:	WASTE PROGRAM COORDINATOR
Contact Role:	PRICONT
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	ELECTRIC DEPT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

ELECTRIC UTILITY (Continued) **S103608274**

Ind. Haz Waste:

Waste ID:	155307
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvents/ Used for parts degreasing/ Date of initial generation unknown.
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	155306
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solvent (spent)/ Used for parts degreasing. Date of initial generation unknown.
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

ELECTRIC UTILITY (Continued) **S103608274**

Ind. Haz Waste:

Waste ID:	175734
Texas Waste Code:	Not reported
Texas Waste Code 2:	0567319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	One-time shipment code - ending 7-31-99 - soil and debris contaminated with RCRA
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175735
Texas Waste Code:	Not reported
Texas Waste Code 2:	0568319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	One-time shipment code - ending 7/31/99. Soil and debris contaminated with RCRA
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

ELECTRIC UTILITY (Continued) **S103608274**

Ind. Haz Waste:

Waste ID:	175736
Texas Waste Code:	Not reported
Texas Waste Code 2:	0569119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	One-time shipment code - ending 7/31/99 from water contaminated with RCRA metals
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306213
Principal Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000306213
Principal Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Attention Name:	Not reported
Attention Suffix:	NWG

DL1668 **POLE YARD** **RCRA NonGen / NLR** **1000412195**
WNW **300 WEST AVE** **FINDS** **TXD981901499**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.028 mi.
148 ft. **Site 15 of 17 in cluster DL**

Actual:
464 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20200226
Handler Name:	Pole Yard
Handler Address:	300 WEST AVE
Handler City,State,Zip:	AUSTIN, TX 78701-3840
EPA ID:	TXD981901499
Contact Name:	SUE MURRAY
Contact Address:	721 BARTON SPRINGS RD
Contact City,State,Zip:	AUSTIN, TX 78704-1328
Contact Telephone:	512-322-6207
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing City,State,Zip:	AUSTIN, TX 78704-1328
Owner Name:	City Of Austin Dba Austin Energy
Owner Type:	Private
Operator Name:	City Of Austin Dba Austin Energy
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

POLE YARD (Continued) **1000412195**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200304
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

POLE YARD (Continued) **1000412195**

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Not reported
Date Became Current: 19991229
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC DE
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 19991229
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD
Owner/Operator City,State,Zip: AUSTIN, TX 78704-1328
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Not reported
Date Became Current: 19991229
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC DE
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 19991229
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD
Owner/Operator City,State,Zip: AUSTIN, TX 78704-1328
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported

POLE YARD (Continued) **1000412195**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19870126
Handler Name: AUSTIN CITY SC12
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19991229
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200226
Handler Name: POLE YARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: AUSTIN CITY SC12
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000125

POLE YARD (Continued) **1000412195**

Handler Name: CITY OF AUSTIN - ELECTRIC UTILITY DEPART
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005097411

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000412195
Registry ID: 110005097411
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005097411
Name: POLE YARD
Address: 300 WEST AVE
City,State,Zip: AUSTIN, TX 78701

DL1669 **AUSTIN ENERGY POLE YARD** **TX VCP** **S123820359**
WNW **300 WEST AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.028 mi.
148 ft. **Site 16 of 17 in cluster DL**

Actual:
464 ft.

Focus Map:
11

VCP TCEQ:

Name:	AUSTIN ENERGY POLE YARD
Address:	300 WEST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	880
VCP Record Date:	11/23/1998
Facility Type:	UTILITY
PCA Number:	31790
Project Manager:	MFREW
Phase:	COMPLETED
Acres at Site:	2.8
REM Program:	VCP
RN Number:	RN100531847
Former Facility Type:	Not reported
Site Address Description:	300 WEST AVENUE
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	11/23/1998
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	TXP490189524
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	72380
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	08/04/1999; 08/04/1999
Standards:	1/2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	EXCAVATE DISPOSE
Air Target COC Class:	Not reported
Date Cashier Check Received:	11/23/1998
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1998-12-20 00:00:00
Soil Target COC Class:	METALS; PAHS; PCBS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	880
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	317900
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.32

AUSTIN ENERGY POLE YARD (Continued) **S123820359**

Longitude:	-97.77
Contact:	
REM Program:	VCP
Program ID:	880
RN Number:	RN100531847
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
Role Code:	BILLCONT
Contact Name:	MULLIN, WADE
Contact Title:	Not reported
Organization Name:	CITY OF AUSTIN
Mailing Address:	505 BARTON SPRINGS RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78704
Contact Telephone:	(512) 499-7154
Contact Telephone Ext:	0

DL1670 **CITY OF AUSTIN ELECTRIC UTILITY** **TX UST** **U001542524**
WNW **300 WEST AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.028 mi.
148 ft. **Site 17 of 17 in cluster DL**

Actual:
464 ft.

Focus Map:
11

UST:

Name:	CITY OF AUSTIN ELECTRIC UTILITY
Address:	300 WEST AVE
City,State,Zip:	AUSTIN, TX 787013840
AI Number:	18149
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/01/1989
Facility Status:	INACTIVE
Additional ID:	390006192002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	CITY OF AUSTIN ELECTRIC UTILITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129281492
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	J A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported

CITY OF AUSTIN ELECTRIC UTILITY (Continued) **U001542524**

Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	390006192002156
AI Number:	18149
Owner Effective Begin Date:	09/01/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	174136
Facility ID:	37553
Ai Number:	18149
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/20/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

CITY OF AUSTIN ELECTRIC UTILITY (Continued) **U001542524**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	9550
UST Comprt ID:	274
UST ID:	174136
AI Number:	18149
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

CITY OF AUSTIN ELECTRIC UTILITY (Continued) **U001542524**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46947
Facility ID:	37553
Ai Number:	18149
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/20/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

CITY OF AUSTIN ELECTRIC UTILITY (Continued) **U001542524**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9550
UST Comprt ID:	273
UST ID:	46947
AI Number:	18149
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N

CITY OF AUSTIN ELECTRIC UTILITY (Continued) **U001542524**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37553
Additional ID:	390006192002156
Princ ID:	840354562001227
AI Number:	18149
Facility Name:	CITY OF AUSTIN ELECTRIC UTILITY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

FY1671 **TWIN OAKS PHILLIPS 66 STATION** **EDR Hist Auto** **1020762709**
SE **620 E OLTORF** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.028 mi.
148 ft. **Site 4 of 4 in cluster FY**

Actual:
560 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1971	TWIN OAKS PHILLIPS 66 STATION	Gasoline Service Stations
1972	TWIN OAKS PHILLIPS 66 STATION	Gasoline Service Stations
1973	TWIN OAKS PHILLIPS 66 STATION	Gasoline Service Stations
1973	BROWNS 66 SERVICE	Gasoline Service Stations
1974	BROWNS 66 SERVICE	Gasoline Service Stations
1975	BROWNS 66 SERVICE	Gasoline Service Stations
1976	BROWNS 66 SERVICE	Gasoline Service Stations
1977	BROWNS 66 SERVICE	Gasoline Service Stations
1978	BROWNS 66 SERVICE	Gasoline Service Stations
1979	BROWNS 66 SERVICE	Gasoline Service Stations

IL1672 **CAPITAL CITY MOTOR** **EDR Hist Auto** **1013771887**
NNE **505 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
149 ft. **Site 6 of 21 in cluster IL**

Actual:
492 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	CAPITAL CITY MOTOR	AUTOMOBILE REPAIRING

CM1673 **FIRST STATE BANK TOWER** **TX UST** **U001267804**
WNW **400 W 15TH ST STE 711** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.028 mi.
149 ft. **Site 2 of 2 in cluster CM**

Actual:
538 ft.

Focus Map:
11

UST:

Name:	FIRST STATE BANK TOWER
Address:	400 W 15TH ST STE 711
City,State,Zip:	AUSTIN, TX 787011647
AI Number:	34800
Facility Type:	Not reported
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	839733452002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	FIRST STATE BANK TOWER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124741191
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	DOROTHY SHELTON,BLDG. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784854
Owner Last Name:	METROPOLITAN LIFE INSURANCE COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

FIRST STATE BANK TOWER (Continued) **U001267804**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	830733442002053
Additional ID:	839733452002053
AI Number:	34800
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	91941
Facility ID:	81132
Ai Number:	34800
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

FIRST STATE BANK TOWER (Continued) **U001267804**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	124416
UST ID:	91941
AI Number:	34800
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

FIRST STATE BANK TOWER (Continued) **U001267804**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	91942
Facility ID:	81132
Ai Number:	34800
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

FIRST STATE BANK TOWER (Continued) **U001267804**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	124417
UST ID:	91942
AI Number:	34800
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

FIRST STATE BANK TOWER (Continued) **U001267804**

Stage 1 Installation Date: Not reported

Facility Billing Contacts:

Contact Organization Name:	METROPOLITAN LIFE INSURANCE CO
Contact Mailing Address (Delivery):	400 W 15TH ST STE 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1647
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	81132
Additional ID:	839733452002053
Princ ID:	830733442002053
AI Number:	34800
Facility Name:	FIRST STATE BANK TOWER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	FIRST STATE BANK TOWER
Address:	400 W 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0209
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

FO1674 **CLOSED CAR WASH** **TX HIST UST** **S128728866**
NE **1510 TOWN CREEK DR.** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
149 ft. **Site 10 of 10 in cluster FO**

Actual:
469 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	CLOSED CAR WASH
Address:	1510 TOWN CREEK DR.
City,State,Zip:	AUSTIN, TX
Id UST:	C0005
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CV1675 WNW < 1/8 0.028 mi. 149 ft. — **PEELER JOHN F TAILOR**, **1003 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780391** / **N/A**

Site 13 of 14 in cluster CV

Actual: 514 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1916	PEELER JOHN F TAILOR	CLOTHES CLEANERS AND PRESSERS
1916	PEELER JOHN F TAILOR	CLEANERS AND PRESSERS

JW1676 WNW < 1/8 0.028 mi. 150 ft. — **SPEEDY STOP 405**, **7715 E BEN WHITE**, **AUSTIN, TX** — **TX RDR** — **S127539973** / **N/A**

Site 1 of 3 in cluster JW

Actual: 543 ft. RDR:

Focus Map: 19

RDR ID:	20493
Facility ID:	76634
RN:	Not reported
CN:	Not reported
Name:	SPEEDY STOP 405
Address:	7715 E BEN WHITE
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/7/2012
Due Date:	11/6/2012
Tank Owner:	SPEEDY STOP FOOD STORES L
Contact Person:	MEGAN ZETTLEMOYER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	11/5/2012
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SIR ltr issued 7/12/12; RDR 1ST SUB 5/21/12; 7/12/2012 RTN LET BY PPC; 2ND SUB 9/7/12;
Review Coordinator:	EAE
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

JW1677 WNW < 1/8 0.028 mi. 150 ft. — **EXXON MOBIL CORPORATION**, **7715 E BEN WHITE BLVD**, **AUSTIN, TX 78744** — **EDR Hist Auto** — **1021349348** / **N/A**

Site 2 of 3 in cluster JW

Actual: 543 ft. EDR Hist Auto

Focus Map: 19

Year:	Name:	Type:
2007	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC

EXXON MOBIL CORPORATION (Continued) **1021349348**

2008	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2009	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2010	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2011	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2012	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2013	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2014	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC

JW1678 **7-ELEVEN STORE 36642** **TX UST** **U003974638**
WNW **7715 E BEN WHITE BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78744** **TX ASBESTOS**
0.028 mi. **TX Financial Assurance**
150 ft. **Site 3 of 3 in cluster JW** **TX PST STAGE 2**
TX CENTRAL REGISTRY
Actual: **TX RDR**
543 ft.

Focus Map: **19**

UST:

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787441773
AI Number:	76634
Facility Type:	RETAIL
Facility Begin Date:	07/08/2004
Facility Status:	ACTIVE
Additional ID:	513525442004222
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PEGGY BETZ,ENV SPECIALIST
Contact Organization Name:	7-ELEVEN STORE 36642
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/05/2004
Signature Name/Title On Earliest Reg Form:	ERIC M MCPHEE,CMS PERM MANAGER
Application Received Date On Earliest Reg Form:	07/28/2004
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	513525442004222
Ai Number:	76634
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	12/28/2012

7-ELEVEN STORE 36642 (Continued) **U003974638**

Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	513525442004222
AI Number:	76634
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	117664
Cert ID:	382522
AI Number:	76634
Self Certification Date:	01/17/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	365152
AI Number:	76634
Self Certification Date:	01/19/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	348417
AI Number:	76634
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	330928
AI Number:	76634
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	314198
AI Number:	76634
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	296673
AI Number:	76634
Self Certification Date:	12/29/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	280827
AI Number:	76634
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	263599
AI Number:	76634
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	247262
AI Number:	76634
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	230924
AI Number:	76634
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	117664
Cert ID:	211676
AI Number:	76634
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211675
AI Number:	76634
Self Certification Date:	01/09/2012
Signature Name/Title:	CARLTON LABEFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211674
AI Number:	76634
Self Certification Date:	04/01/2011
Signature Name/Title:	TARONZA L GRAVES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211673
AI Number:	76634
Self Certification Date:	03/15/2010
Signature Name/Title:	TARONZA L GRAVES OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211672
AI Number:	76634
Self Certification Date:	03/27/2009
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211671
AI Number:	76634
Self Certification Date:	03/28/2008
Signature Name/Title:	JOEY WEISMAN OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117664
Cert ID:	211670
AI Number:	76634
Self Certification Date:	04/09/2007
Signature Name/Title:	HEATHER GILMORE AUTH AGENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117664
Cert ID:	211669
AI Number:	76634
Self Certification Date:	04/03/2006
Signature Name/Title:	ERIC M MCPHEE PERM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117664
Cert ID:	211434
AI Number:	76634
Self Certification Date:	04/06/2005
Signature Name/Title:	ERIC M MCPHEE PERM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	117664
Cert ID:	211433
AI Number:	76634
Self Certification Date:	04/05/2004
Signature Name/Title:	ERIC M MCPHEE CMS PERM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	07/08/2004
Tank Registration Date:	07/28/2004
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	203450
Facility ID:	117664
Ai Number:	76634
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	07/08/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/2004

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	184493
UST ID:	203450
AI Number:	76634
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/08/2004

Install Date:	07/08/2004
Tank Registration Date:	07/28/2004
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	203451
Facility ID:	117664
Ai Number:	76634
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	07/08/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	15000
UST Comprt ID:	184494
UST ID:	203451
AI Number:	76634
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/08/2004

Install Date:	07/08/2004
Tank Registration Date:	07/28/2004
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	203452
Facility ID:	117664
Ai Number:	76634
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	07/08/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	184495
UST ID:	203452
AI Number:	76634
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/08/2004
Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	184496
UST ID:	203452
AI Number:	76634
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/08/2004

Construction Notification:

NOC ID:	40192
Facility ID:	117664
AI Number:	76634
Application Received Date:	07/12/2022
Scheduled Construction Date:	07/08/2022
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	07/12/2022
Signature Date On Form:	07/07/2022
Signature Name On Form:	AMELIA BEARD
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ COORD
Signature Role:	OWNER
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REPLACE RUL FILL SPILL BUCKET

NOC ID:	37986
Facility ID:	117664
AI Number:	76634
Application Received Date:	04/14/2021
Scheduled Construction Date:	04/26/2021
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	07/12/2022
Signature Date On Form:	07/07/2022
Signature Name On Form:	AMELIA BEARD
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ COORD
Signature Role:	OWNER
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	21314
Facility ID:	117664
AI Number:	76634
Application Received Date:	04/12/2005
Scheduled Construction Date:	07/20/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50412069
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	07/12/2022
Signature Date On Form:	07/07/2022
Signature Name On Form:	AMELIA BEARD
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ COORD
Signature Role:	OWNER
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	4194
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	90370
UST ID:	Not reported
NOC ID:	37986
AI Number:	76634
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	APTIM
Representative Name:	KIM FORD
Mailing Address (Delivery):	12005 FORD DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738400
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	0
Fax Number:	0
Email Address:	KTAPIA@MCCONBUILDING.COM

Cont/Cons/Installer ID:	22377
UST ID:	Not reported
NOC ID:	21314
AI Number:	76634
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000665
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported

7-ELEVEN STORE 36642 (Continued) **U003974638**

Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	35542
UST ID:	203450
NOC ID:	Not reported
AI Number:	76634
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001317
Company Name:	MC Services
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	96015
UST ID:	Not reported
NOC ID:	40192
AI Number:	76634
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

7-ELEVEN STORE 36642 (Continued) **U003974638**

Fax Number:	Not reported
Email Address:	ACCOUNTING@MCCONBUILDING.COM
Cont/Cons/Installer ID:	90369
UST ID:	Not reported
NOC ID:	37986
AI Number:	76634
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	NATE.LAWSON@JFPETROGROUP.COM
Cont/Cons/Installer ID:	96016
UST ID:	Not reported
NOC ID:	40192
AI Number:	76634
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001286
Company Name:	Not reported
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	50707
UST ID:	203450
NOC ID:	Not reported
AI Number:	76634
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000496

7-ELEVEN STORE 36642 (Continued) **U003974638**

Company Name:	Not reported
Representative Name:	MIKE BEEVERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	117664
Additional ID:	513525442004222
Princ ID:	959578622001257
AI Number:	76634
Facility Name:	7-ELEVEN STORE 36642
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN #36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3295
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Date of inspection:	10/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported

7-ELEVEN STORE 36642 (Continued) **U003974638**

Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.7
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

7-ELEVEN STORE 36642 (Continued) **U003974638**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	279692
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	262717
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 817 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD

7-ELEVEN STORE 36642 (Continued) **U003974638**

City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	242454
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	224877
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	208119
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	189379
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	173222
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000

7-ELEVEN STORE 36642 (Continued) **U003974638**

Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	154743
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	138390
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664

7-ELEVEN STORE 36642 (Continued) **U003974638**

Finass ID:	120924
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	118530
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	16326
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN STORE 36642 (Continued) **U003974638**

Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99593
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99594
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN STORE 36642 (Continued) **U003974638**

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99595
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99596
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99597
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN STORE 36642 (Continued) **U003974638**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99598
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99599
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000

7-ELEVEN STORE 36642 (Continued) **U003974638**

Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Region:	2
Facility ID:	117664
Finass ID:	99600
AI:	76634
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

PST STAGE 2:

Regulated Number:	RN104362827
Region Location:	11
Has Active Violation:	NO
PST ID:	76634
Start Date:	07/08/2004
Stage 2 Type:	ASSIST SYSTEM
Stage 2 Install Date:	08/08/2004
Last Inspection Activity:	Not reported
EACT Status:	ACTIVE
ADDN ID:	76634
Last Inspection Number:	Not reported
Last Inspection Status Date:	Not reported
Last Inspection Status:	Not reported
Last Inspection Activity 2:	Not reported
Last Inspection Conducted By:	Not reported
Facility Not Inspected:	Not reported
Facility Not Inspected Reason:	Not reported
ADDN Status:	ACTIVE
Status:	ACTIVE
Signed Date:	01/23/2019
Expired Date:	01/31/2020
Tank Status:	IN USE
Type:	RETAIL
UST Number:	3
Latitude:	0
Longitude:	0

7-ELEVEN STORE 36642 (Continued) **U003974638**

Stage2 Detail:

RN:	RN104362827
Reg Status:	FULLY REGULATED
CN:	CN600240329
Princ Name:	7-ELEVEN INC
Princ Legal Name:	7-Eleven, Inc.
Role:	OWNOPR
First Name:	Not reported
Middle Name:	Not reported
Last Name:	Not reported
PST UST ID:	203450
UST Tank ID:	1
Num UST Comprt:	1
Install Date:	07/08/2004
Regis Date:	07/28/2004
Capacity Qty:	15000
Substance Type:	GASOLINE

CENTRAL REGISTRY:

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-07-08
Affiliation End Date:	2011-12-18
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2004-07-08
Affiliation End Date:	2011-12-18
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110

7-ELEVEN STORE 36642 (Continued) **U003974638**

Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: 7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number: RN104362827
Name: 7-ELEVEN STORE 36642
Address: 7715 E BEN WHITE BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1773
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN600123939
Customer Name: EXXON MOBIL CORPORATION
Customer Legal Name: Exxon Mobil Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2004-07-08
Affiliation End Date: 2011-12-18
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: 7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number: RN104362827
Name: 7-ELEVEN STORE 36642
Address: 7715 E BEN WHITE BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1773
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN603234246
Customer Name: SPEEDY STOP FOOD STORES LLC
Customer Legal Name: Speedy Stop Food Stores, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2011-12-19
Affiliation End Date: 2012-12-27
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: 7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number: RN104362827
Name: 7-ELEVEN STORE 36642
Address: 7715 E BEN WHITE BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1773
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN603234246
Customer Name: SPEEDY STOP FOOD STORES LLC
Customer Legal Name: Speedy Stop Food Stores, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 2011-12-19
Affiliation End Date: 2012-12-27
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: 7715 E BEN WHITE BLVD AUSTIN, TX 78704

7-ELEVEN STORE 36642 (Continued) **U003974638**

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603234246
Customer Name:	SPEEDY STOP FOOD STORES LLC
Customer Legal Name:	Speedy Stop Food Stores, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2011-12-19
Affiliation End Date:	2012-12-27
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-12-28
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-12-28
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD

7-ELEVEN STORE 36642 (Continued) **U003974638**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2012-12-28
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600123939
Customer Name:	EXXON MOBIL CORPORATION
Customer Legal Name:	Exxon Mobil Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/8/2004
Affiliation End Date:	12/18/2011
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Regulated Entity Number:	RN104362827
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1773
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603234246
Customer Name:	SPEEDY STOP FOOD STORES LLC
Customer Legal Name:	Speedy Stop Food Stores, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	12/19/2011
Affiliation End Date:	12/27/2012
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	7715 E BEN WHITE BLVD AUSTIN, TX 78704

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

RDR:

RDR ID:	32210
Facility ID:	76634

7-ELEVEN STORE 36642 (Continued) **U003974638**

RN:	104362827
CN:	600240329
Name:	7-ELEVEN STORE 36642
Address:	7715 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/5/2022
Due Date:	12/4/2022
Tank Owner:	7-ELEVEN INC
Contact Person:	CHARLES CHIARA
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	12/2/2022
Project Manager:	Rodney Bryant
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DR1679 **2 RODRIGUEZ JOS CLDO** **EDR Hist Cleaner** **1013785130**
NE **517 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.028 mi.
150 ft. **Site 36 of 38 in cluster DR**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	2 RODRIGUEZ JOS CLDO	CLOTHES PRESSERS AND CLEANERS

DF1680 **MASTER VALET CLNS** **EDR Hist Cleaner** **1013784680**
WNW **109 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
151 ft. **Site 22 of 25 in cluster DF**

Actual:
497 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1958	MASTER VALET	CLEANERS AND DYERS
1962	MASTER VALET CLNS	CLEANERS AND DYERS

DF1681 **MASTER VALET CLEANERS** **EDR Hist Cleaner** **1013780693**
WNW **109 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
151 ft. **Site 23 of 25 in cluster DF**

Actual:
497 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	MASTER VALET CLEANERS	CLEANERS AND DYERS

FU1682 **CONTINENTAL OIL COMP.** **TX HIST UST** **S111678614**
NW **2336 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
152 ft. **Site 11 of 13 in cluster FU**

Actual:
600 ft.
HIST UST AUSTIN:

Focus Map:
14

Name:	CONTINENTAL OIL COMP.
Address:	2336 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0666
HID UST:	666
Inspection:	Not reported
Due:	06/01/2012

FU1683 **SOUTH AUSTIN CONOCO** **EDR Hist Auto** **1013776623**
NW **2336 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.029 mi.
152 ft. **Site 12 of 13 in cluster FU**

Actual:
600 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1962	SOUTH AUSTIN CONOCO	GASOLINE STATIONS

DM1684 **NOWLIN R A AUTO REPR** **EDR Hist Auto** **1013762288**
SSW **602 TRINITY ST** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
152 ft. **Site 22 of 22 in cluster DM**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	NOWLIN R A AUTO REPR	AUTOMOBILE REPAIRERS
1935	AUTOMOTIVE SERVICE	AUTOMOBILE MOTOR REBUILDING
1953	AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING

GX1685 ESE < 1/8 0.029 mi. 152 ft. — **NUZ FRANK GARAGE**, **4237 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013764179** / **N/A**

Site 2 of 5 in cluster GX

Actual: 667 ft. EDR Hist Auto

Focus Map: 18

Year:	Name:	Type:
1953	NUZ FRANK GARAGE	AUTOMOBILE REPAIRING
1958	REAR NUZ FRANK GARAGE	AUTOMOBILE REPAIRING

GX1686 ESE < 1/8 0.029 mi. 152 ft. — **SUNDBECK GAR**, **4241 CONGRESS AVE**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013773732** / **N/A**

Site 3 of 5 in cluster GX

Actual: 666 ft. EDR Hist Auto

Focus Map: 18

Year:	Name:	Type:
1962	SUNDBECK GAR	AUTOMOBILE REPAIRING

GX1687 ESE < 1/8 0.029 mi. 152 ft. — **SUNDBECK GARAGE**, **4241 CONGRESS AVE S**, **TRAVIS (County), TX 78745** — **EDR Hist Auto** — **1013770686** / **N/A**

Site 4 of 5 in cluster GX

Actual: 666 ft. EDR Hist Auto

Focus Map: 18

Year:	Name:	Type:
1965	SUNDBECK GARAGE H	AUTOMOBILE REPAIRING
1969	SUNDBECK GARAGE	General Automotive Repair Shops
1970	SUNDBECK GARAGE	AUTOMOBILE REPAIRING
1970	SUNDBECK GARAGE	General Automotive Repair Shops
1971	SUNDBECK GARAGE	General Automotive Repair Shops
1972	SUNDBECK GARAGE	General Automotive Repair Shops
1973	SUNDBECK GARAGE	General Automotive Repair Shops
1974	SUNDBECK GARAGE	General Automotive Repair Shops
1975	SUNDBECK G	AUTOMOBILE REPAIRING
1975	SUNDBECK GARAGE	General Automotive Repair Shops
1976	SUNDBECK GARAGE	General Automotive Repair Shops
1977	SUNDBECK GARAGE	General Automotive Repair Shops
1978	SUNDBECK GARAGE	General Automotive Repair Shops
1979	SUNDBECK GARAGE	General Automotive Repair Shops
1980	SUNBECK AUTOMOTIVE	AUTOMOBILE REPAIRING
1980	SUNBECK AUTOMOTIVE	General Automotive Repair Shops
1982	HANNAH INC	General Automotive Repair Shops
1983	E & B HARPER INC	General Automotive Repair Shops
1984	SUNBECK AUTOMOTIVE	AUTOMOBILE REPAIRING
1985	S & L PRESLEY INC	General Automotive Repair Shops
1986	IRESCO INC	General Automotive Repair Shops
1987	IRESCO INC	General Automotive Repair Shops
1988	IRESCO INC	General Automotive Repair Shops
1989	IRESCO INC	Engine Repair
1990	SUNBECK AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	IRESCO INC	Engine Repair

SUNDBECK GARAGE (Continued) **1013770686**

1991	IRESCO INC	Engine Repair
1992	IRESCO INC	Engine Repair
1993	IRESCO INC	Engine Repair
1994	CHESHIER AUTO REPAIR	General Automotive Repair Shops
1994	IRESCO INC	Engine Repair
1995	CHESHIER AUTO REPAIR	General Automotive Repair Shops
1995	IRESCO INC	Engine Repair
1996	CHESHIER AUTO REPAIR	General Automotive Repair Shops
1997	CHESHIER AUTO REPAIR	General Automotive Repair Shops
1998	CHESHIER AUTO REPAIR	General Automotive Repair Shops
1999	CHESHIER AUTO REPAIR	General Automotive Repair Shops
2000	CHESHIER AUTO REPAIR	General Automotive Repair Shops
2001	CHESHIER AUTO REPAIR	General Automotive Repair Shops
2002	CHESHIER AUTO REPAIR	General Automotive Repair Shops
2003	CHESHIRE AUTO REPAIR	General Automotive Repair Shops
2005	MCSPADDEN RAYMOND	General Automotive Repair Shops
2006	MCSPADDEN RAYMOND	General Automotive Repair Shops
2007	MCSPADDEN RAYMOND	General Automotive Repair Shops
2008	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2008	MCSPADDEN RAYMOND	General Automotive Repair Shops
2009	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2010	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2011	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2012	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2013	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops
2014	MCSPADDEN AUTOMOTIVE INC	General Automotive Repair Shops

---

GX1688 **SUNBECK AUTOMOTIVE** **RCRA NonGen / NLR** **1000162290**
ESE **4241 S CONGRESS AVE** **FINDS** **TXD982759730**
< 1/8 **AUTIN, TX 78745** **ECHO**
0.029 mi. **TX Ind. Haz Waste**
152 ft. **Site 5 of 5 in cluster GX** **TX CENTRAL REGISTRY**

Actual:
666 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20020115
Handler Name:	Sunbeck Automotive
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD982759730
Contact Name:	TOMAS DALIN
Contact Address:	S CONGRESS AVE
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-442-4817
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Sunbeck Automotive

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Owner Type:	Private
Operator Name:	Sunbeck Automotive
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: IRESCO INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: SUNBECK AUTOMOTIVE	
Legal Status:	Private
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	4241 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-442-4817
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: SUNBECK AUTOMOTIVE	
Legal Status:	Private
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	4241 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-442-4817
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19890717
Handler Name: SUNBECK AUTOMOTIVE	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20020115
Handler Name: SUNBECK AUTOMOTIVE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

SUNBECK AUTOMOTIVE (Continued) **1000162290**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005113215

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000162290
Registry ID:	110005113215
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005113215
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745

Ind. Haz Waste:

Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	74906
Registration Initial Notification Date:	09/21/1989
Registration Last Amendment Date:	01/15/2002
EPA Identification:	TXD982759730
Primary NAICS Code:	Not reported
Status Change Date:	19890921
Land Type:	PRIVATE
Description of Facility Site Location:	4241 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	SUNBECK AUTOMOTIVE
Contact Name:	TOMAS DALIN
Contact Telephone Number:	512-4424817
Mailing Address:	4241 S CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787453326
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29267
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020115
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	SUNBECK AUTOMOTIVE
Operator Address:	4241 S CONGRESS AVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4424817
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	SUNBECK AUTOMOTIVE
Owner Mailing Address:	4241 S CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4424817
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Owner Bankruptcy Code: Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4241 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4424817
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4241 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4424817
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	TOMAS DALIN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4241 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4424817
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600254585
Customer Name:	SUNBECK AUTOMOTIVE
Customer Legal Name:	Sunbeck Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600254585
Customer Name:	SUNBECK AUTOMOTIVE
Customer Legal Name:	Sunbeck Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604987537
Customer Name:	CHESHIER AUTO REPAIR
Customer Legal Name:	Cheshier Auto Repair
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604987537
Customer Name:	CHESHIER AUTO REPAIR
Customer Legal Name:	Cheshier Auto Repair
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE

SUNBECK AUTOMOTIVE (Continued) **1000162290**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600254585
Customer Name:	SUNBECK AUTOMOTIVE
Customer Legal Name:	Sunbeck Automotive
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/15/2002
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

Regulated Entity Number:	RN100543404
Name:	SUNBECK AUTOMOTIVE
Address:	4241 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3326
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604987537
Customer Name:	CHESHIER AUTO REPAIR
Customer Legal Name:	Cheshier Auto Repair
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4241 S Congress Ave, Austin, TX

IA1689 **L & M GARAGE AUTO REPRS** **EDR Hist Auto** **1013766703**
NE **301 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.029 mi.
152 ft. **Site 2 of 2 in cluster IA**

Actual:
454 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	L & M GARAGE AUTO REPRS	AUTOMOBILE REPAIRING

L1690 **HILL ELECTRIC** **TX UST** **U003040369**
WNW **10100 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.029 mi.
152 ft. **Site 3 of 3 in cluster L**

Actual:
712 ft.

UST:

Focus Map:
3

Name:	HILL ELECTRIC
Address:	10100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533602
AI Number:	68149
Facility Type:	Not reported

HILL ELECTRIC (Continued) **U003040369**

Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	517604132002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	TOM GAMOND,
Contact Organization Name:	HILL ELECTRIC
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128363950
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/11/1996
Signature Name/Title On Earliest Reg Form:	TOM GAMOND,PLANT MGR
Application Received Date On Earliest Reg Form:	01/13/1996
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780621
Owner Last Name:	JACK T HILL ELECTRIC CO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	507604122002053
Additional ID:	517604132002053
AI Number:	68149
Owner Effective Begin Date:	08/31/1987
State Tax ID:	17416968075
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987

HILL ELECTRIC (Continued) **U003040369**

Tank Registration Date:	01/13/1996
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	178405
Facility ID:	102902
Ai Number:	68149
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/29/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

HILL ELECTRIC (Continued) **U003040369**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	177923
UST ID:	178405
AI Number:	68149
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HILL ELECTRIC CO
Contact Mailing Address (Delivery):	PO BOX 80009
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78708 0009
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

HILL ELECTRIC (Continued) **U003040369**

Contact Address Deliverable:	Y
Facility ID:	102902
Additional ID:	517604132002053
Princ ID:	507604122002053
AI Number:	68149
Facility Name:	HILL ELECTRIC
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	TOM GAMOND/

HIST UST AUSTIN:

Name:	HILL ELECTRIC
Address:	10100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0607
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DE1691 **SHIRLEY CLEANERS & HATTERS** **EDR Hist Cleaner** **1013782387**
ESE **310 W 6TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.029 mi.
153 ft. **Site 12 of 13 in cluster DE**

Actual:
500 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1970	SHIRLEY CLEANERS & HATTERS	CLEANERS AND DYERS

CN1692 **ROBERT E JOHNSON BUILDING** **TX UST** **U003921134**
WNW **1501 CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.029 mi.
153 ft. **Site 2 of 4 in cluster CN**

Actual:
546 ft.

Focus Map:
11

UST:

Name:	ROBERT E JOHNSON BUILDING
Address:	1501 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787011418
AI Number:	76048
Facility Type:	Not reported
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	635333862003344
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/05/2022
Signature Name/Title On Earliest Reg Form:	RICHARD BRYANT,OPERATOR
Application Received Date On Earliest Reg Form:	01/10/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	167546612009246
Additional ID:	635333862003344
Ai Number:	76048
Operator CN:	CN603527441
Operator Name:	TEXAS FACILITIES COMMISSION
Operator Effective Begin Date:	09/11/2003
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78711-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9000333
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603527441
Owner Last Name:	TEXAS FACILITIES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78711
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 9000333/0
Contact Fax Country Code:	Not reported

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Contact Fax Number/Ext:	/
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	167546612009246
Additional ID:	635333862003344
AI Number:	76048
Owner Effective Begin Date:	09/11/2003
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION

Self Certification:

Self Cert ID:	116670
Cert ID:	383125
AI Number:	76048
Self Certification Date:	01/09/2023
Signature Name/Title:	RICHARD BRYANT FACILITY MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	366804
AI Number:	76048
Self Certification Date:	01/05/2022
Signature Name/Title:	RICHARD BRYANT OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	350454
AI Number:	76048
Self Certification Date:	01/12/2021
Signature Name/Title:	RICHARD BRYANT FAC OPER
Signature Type Role:	LEGAL AUTH REP OWNER

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	330337
AI Number:	76048
Self Certification Date:	01/02/2020
Signature Name/Title:	RICHARD BRYANT TFFA CLASS AB FAC OPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	313781
AI Number:	76048
Self Certification Date:	01/10/2019
Signature Name/Title:	JEFFERY PARNELL ELECTRICIAN III
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	298655
AI Number:	76048
Self Certification Date:	01/31/2018
Signature Name/Title:	KEN HULIN FAC MAINT MGR
Signature Type Role:	LEGAL AUTH REP OWNER

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	281063
AI Number:	76048
Self Certification Date:	01/10/2017
Signature Name/Title:	KEN HULIN FAC MAINT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	265497
AI Number:	76048
Self Certification Date:	01/12/2016
Signature Name/Title:	KEN HULIN FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	248017
AI Number:	76048
Self Certification Date:	01/27/2015
Signature Name/Title:	KEN HULIN ELEC SUPERVISOR
Signature Type Role:	LEGAL AUTH REP OWNER

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	230642
AI Number:	76048
Self Certification Date:	01/16/2014
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116670
Cert ID:	208192
AI Number:	76048
Self Certification Date:	02/12/2013
Signature Name/Title:	KEN HULIN ELEC SUPVR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116670
Cert ID:	208191
AI Number:	76048
Self Certification Date:	01/31/2012
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	OPERATOR

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116670
Cert ID:	208190
AI Number:	76048
Self Certification Date:	02/11/2011
Signature Name/Title:	KEN HULIN ELECTRICAL SPVR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116670
Cert ID:	208189
AI Number:	76048
Self Certification Date:	01/05/2010
Signature Name/Title:	JONATHAN HICKMAN ELECTRICAL SUPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116670
Cert ID:	208188
AI Number:	76048
Self Certification Date:	10/23/2009
Signature Name/Title:	JONATHAN HICKMAN ELEC SUPVR
Signature Type Role:	OPERATOR

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116670
Cert ID:	208187
AI Number:	76048
Self Certification Date:	09/11/2003
Signature Name/Title:	MEL BULLOCK
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/07/1995
Tank Registration Date:	09/15/2003
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	202086
Facility ID:	116670
Ai Number:	76048
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/07/1995
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	12/07/1995
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	183129
UST ID:	202086
AI Number:	76048
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y

ROBERT E JOHNSON BUILDING (Continued) **U003921134**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78711 3047
Phone Number/Ext:	512 9000333/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	116670
Additional ID:	635333862003344
Princ ID:	167546612009246
AI Number:	76048
Facility Name:	ROBERT E JOHNSON BUILDING
AR Number:	55232
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	RICHARD BRYANT/

HIST UST AUSTIN:

Name:	JOHNSON LEGISLATIVE BLDG
Address:	1501 CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	EX085
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DB1693 WNW < 1/8 0.029 mi. 153 ft. | **108 10 12 HENRV GARAGE WILLIAMS AUTO WORKS**
108 8TH E
AUSTIN, TX

Site 11 of 11 in cluster DB

EDR Hist Auto | **1013764938**
N/A

Actual: 502 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	108 10 12 HENRV GARAGE WILLIAMS	AUTOMOBILE REPAIRERS
1935	108 10 12 HENRV GARAGE WILLIAMS	AUTOMOBILE GARAGES

EM1694 SW < 1/8 0.029 mi. 153 ft. | **CENTRAL TEXAS EQUIPMENT**
127 E RIVERSIDE DR
AUSTIN, TX 78704

Site 3 of 3 in cluster EM

TX LPST
TX UST
TX VCP
TX HIST UST

U001249911
N/A

Actual: 448 ft.

Focus Map: 14

LPST:

Name:	CENTRAL TEXAS EQUIPMENT
Address:	127 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0014486
LPST Id:	093963
Facility Location:	127 E RIVERSIDE DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/27/1989
Entered Date:	11/28/1989
Reported Date:	10/27/1989
Closure Date:	01/07/1998
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/3/1
Coordinators RPR:	ARB
Responsible Party Name:	Not reported
Responsible Party Contact:	H C BELL
Responsible Party Address:	PO BOX 116
Responsible Party City,St,Zip:	AUSTIN, TX 78767 0116
Responsible Party Telephone:	512/442-2371
Reported Date:	10/27/1989
Case Start Date:	01/07/1998
Reference Number:	RN104700117
Project Manager:	ABATCHEL

UST:

Name:	CENTRAL TEXAS EQUIPMENT
Address:	127 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787041270
AI Number:	14486
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/12/1986
Facility Status:	INACTIVE
Additional ID:	826592582002053
Facility Exempt Status:	N
Records Off-Site:	No

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	H C BELL,PRES
Contact Organization Name:	CENTRAL TEXAS EQUIPMENT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124422371
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/18/1986
Signature Name/Title On Earliest Reg Form:	H C BELL,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780241
Owner Last Name:	CENTRAL TEXAS EQUIPMENT CO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	817592572002053
Additional ID:	826592582002053
AI Number:	14486
Owner Effective Begin Date:	08/12/1986
State Tax ID:	17412156782
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

Pipe Type:	Not reported
UST ID:	37270
Facility ID:	53158
Ai Number:	14486
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/31/1991

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	41283
UST ID:	37270
AI Number:	14486
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	5703
Cert ID:	73650
UST Comprt ID:	209873
UST ID:	69095
AI Number:	14486
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5703
Cert ID:	73649
UST Comprt ID:	209872
UST ID:	69095

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

AI Number:	14486
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37269
Facility ID:	53158
Ai Number:	14486
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/31/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	41282
UST ID:	37269
AI Number:	14486
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	5703
Cert ID:	73650

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

UST Comprt ID:	209873
UST ID:	69095
AI Number:	14486
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5703
Cert ID:	73649
UST Comprt ID:	209872
UST ID:	69095
AI Number:	14486
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CENTRAL TEXAS EQUIPMENT CO
Contact Mailing Address (Delivery):	127 E RIVERSIDE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 1270
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	53158
Additional ID:	826592582002053
Princ ID:	817592572002053
AI Number:	14486
Facility Name:	CENTRAL TEXAS EQUIPMENT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	H C BELL/

VCP TCEQ:

Name:	CRESCENT MACHINERY
Address:	127 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78704
Region:	REGION 11 - AUSTIN
Facility ID:	1835
VCP Record Date:	07/12/2005
Facility Type:	MFG
PCA Number:	34034
Project Manager:	OEKPOOTU
Phase:	COMPLETED
Acres at Site:	1.6
REM Program:	VCP
RN Number:	RN104700117
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	07/14/2005
RCRIS Number:	Not reported
Air REM Method:	Not reported

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	11/21/2006
Standards:	PLAN A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	07/07/2005
GW Target COC Class:	METALS; VOCS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2005-08-18 00:00:00
Soil Target COC Class:	METALS; VOCS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1835
Leaking Petroleum Storage Registration Tank:	92963
Project Number:	340340
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/211
Latitude:	30.15
Longitude:	-97.44

Contact:

REM Program:	VCP
Program ID:	1835
RN Number:	RN104700117
CN Number:	CN602876401
CN Name:	127 E RIVERSIDE LTD
Role Code:	BILLCONT
Contact Name:	NEEDHAM, JOHN
Contact Title:	Not reported
Organization Name:	127 E RIVERSIDE LTD
Mailing Address:	100 CONGRESS AVE STE 1540
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78701
Contact Telephone:	(512) 476-7806
Contact Telephone Ext:	0

HIST UST AUSTIN:

Name:	CENTRAL TEXAS EQUIPMENT
Address:	127 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0077

CENTRAL TEXAS EQUIPMENT (Continued) **U001249911**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

JX1695 **OSF CONGRESS** **TX TANKS** **S126921542**
NNE **2701 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX CENTRAL REGISTRY**
0.029 mi.
154 ft. **Site 1 of 3 in cluster JX**

Actual:
634 ft.

Focus Map:
14

TANKS:

Facility ID:	134449
Name:	OSF CONGRESS
Address:	2701 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787046413
Total UST:	Not reported
Additional ID:	431547702017199
AI Number:	89336
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	Not reported
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	Not reported
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

HIST UST AUSTIN:

Name:	SPILLAR CUSTOM HITCHES
Address:	2701 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX
Id UST:	C0042
HID UST:	Not reported
Inspection:	Not reported

OSF CONGRESS (Continued) **S126921542**

Due: Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN109850750
Name:	OSF CONGRESS
Address:	2701 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6413
Status:	ACTIVE
Status Date:	7/18/2017
Customer Number:	CN605391937
Customer Name:	OSF CONGRESS LP
Customer Legal Name:	OSF Congress, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	7/17/2017
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

JX1696 **OSF CONGRESS LP** **TX RDR** **S127541142**
NNE **2701 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
154 ft. **Site 2 of 3 in cluster JX**

Actual:
634 ft.

Focus Map:
14

RDR:

RDR ID:	24854
Facility ID:	89336
RN:	Not reported
CN:	Not reported
Name:	OSF CONGRESS LP
Address:	2701 S CONGRESS
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/14/2017
Due Date:	10/13/2017
Tank Owner:	OSF CONGRESS LP
Contact Person:	CLAY LIKOVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/13/2017
Project Manager:	Bria Patterson
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

GK1697 **DALES AUTO PARTS & MACHINE SHOP** **RCRA NonGen / NLR** **1000220361**
WNW **3600 S CONGRESS AVE** **FINDS** **TXD080256993**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.029 mi.
155 ft. **Site 2 of 4 in cluster GK**

Actual:
620 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20200325
Handler Name:	Dales Auto Parts & Machine Shop
Handler Address:	3600 S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78704-7214
EPA ID:	TXD080256993
Contact Name:	DALE WATKINS
Contact Address:	3600 S CONGRESS AVE
Contact City,State,Zip:	AUSTIN, TX 78704-7214
Contact Telephone:	512-442-7843
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3600 S CONGRESS AVE
Mailing City,State,Zip:	AUSTIN, TX 78704-7214
Owner Name:	Dales Auto Parts & Machine Shop
Owner Type:	Private
Operator Name:	Dales Auto Parts & Machine Shop
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DALES AUTO PARTS & MACHINE SHOP (Continued) **1000220361**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DALES AUTO PARTS & MACHINE SHOP
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	3600 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78702
Owner/Operator Telephone:	512-442-7843
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DALES AUTO PARTS & MACHINE SHOP
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	3600 S CONGRESS AVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78702
Owner/Operator Telephone:	512-442-7843
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **1000220361**

Owner/Operator Indicator: Owner
Owner/Operator Name: DALES AUTO PARTS & MACHINE SHOP
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 3600 S CONGRESS AVE
Owner/Operator City,State,Zip: AUSTIN, TX 78704-7214
Owner/Operator Telephone: 512-442-7843
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DALES AUTO PARTS & MACHINE SHOP
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 3600 S CONGRESS AVE
Owner/Operator City,State,Zip: AUSTIN, TX 78704-7214
Owner/Operator Telephone: 512-442-7843
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DALE WATKINS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19871005
Handler Name: DALES AUTO PARTS & MACHINES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: DALES AUTO PARTS & MACHINE SHOP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

DALES AUTO PARTS & MACHINE SHOP (Continued) **1000220361**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200325
Handler Name: DALES AUTO PARTS & MACHINE SHOP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 453998
NAICS Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT TOBACCO STORES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005063741

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000220361
Registry ID: 110005063741
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005063741
Name: DALES AUTO PARTS & MACHINE SHOP
Address: 3600 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78704

GK1698 **SIGMOR NUMBER 232 INC** **EDR Hist Auto** **1020655318**
WNW **3600 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.029 mi.
155 ft. **Site 3 of 4 in cluster GK**

Actual:
620 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1987	DALES AUTO PARTS INC	Motor Vehicle Supplies And New Parts
1988	DEL VALLE AUTO CENTER INC	General Automotive Repair Shops
1989	DEL VALLE AUTO CENTER INC	General Automotive Repair Shops
1990	DEL VALLE AUTO CENTER INC	General Automotive Repair Shops
1994	DEL VALLE AUTO CENTER INC	General Automotive Repair Shops
2001	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2001	DALES EASTSIDE AUTO SUPPLY	General Automotive Repair Shops
2002	DALES EASTSIDE AUTO SUPPLY	General Automotive Repair Shops
2002	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2003	DALES EASTSIDE AUTO SUPPLY	General Automotive Repair Shops
2003	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2004	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2004	DALES EASTSIDE AUTO SUPPLY	General Automotive Repair Shops
2005	DALES EASTSIDE AUTO SUPPLY	General Automotive Repair Shops
2005	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2006	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2007	SIGMOR NUMBER 232 INC	Gasoline Service Stations
2008	SIGMOR NUMBER 232 INC	Gasoline Service Stations

GK1699 **DALES AUTO PARTS & MACHINE SHOP** **TX ASBESTOS** **S103608337**
WNW **3600 S CONGRESS AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX CENTRAL REGISTRY**
0.029 mi.
155 ft. **Site 4 of 4 in cluster GK**

Actual:
620 ft.

ASBESTOS:

Focus Map:
14

Name:	HH-AUSTEXAS, LLC
Address:	3600 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/03/23
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/23/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022001594
File Number:	69755
License Status Description:	Paid
Expiration Date:	03/24/2022
Original Date:	03/07/2022
Rank Effective Date:	03/07/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	31908
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	HH-AUSTEXAS, LLC
Address:	3600 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/23/2022
Reason for Inspection:	Jarrett Aldrich
Violation:	Not reported
Complaint Date:	03/24/2022
Notification Number:	2022001594
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/07/2022
Certification Statement Phone:	210-336-7452
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Name:	HH-AUSTEXAS, LLC
Address:	3600 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/23/2022
Reason for Inspection:	Jarrett D Aldrich
Violation:	Not reported
Complaint Date:	03/24/2022
Notification Number:	2022001594
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/07/2022
Certification Statement Phone:	210-336-7452
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	03/23/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	DALES AUTO PARTS & MACHINE SHOP
Address:	3600 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	72599
Registration Initial Notification Date:	10/16/1987
Registration Last Amendment Date:	03/25/2020
EPA Identification:	TXD080256993
Primary NAICS Code:	453998
Status Change Date:	19871016
Land Type:	PRIVATE
Description of Facility Site Location:	3600 S Congress, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	DALES AUTO PARTS & MACH SHOP
Contact Name:	DALE WATKINS
Contact Telephone Number:	512-4427843
Mailing Address:	3600 S CONGRESS AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787047214
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27038
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200325
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	DALES AUTO PARTS & MACH SHOP
Operator Address:	3600 S CONGRESS AVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4427843
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DALES AUTO PARTS & MACH SHOP
Owner Mailing Address:	3600 S CONGRESS AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4427843
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3600 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427843
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3600 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427843
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DALE WATKINS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3600 S CONGRESS AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427843
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600405484
Customer Name:	DALES AUTO PARTS & MACH SHOP
Customer Legal Name:	Dales Auto Parts & Mach Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600405484
Customer Name:	DALES AUTO PARTS & MACH SHOP
Customer Legal Name:	Dales Auto Parts & Mach Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600405484
Customer Name:	DALES AUTO PARTS & MACH SHOP
Customer Legal Name:	Dales Auto Parts & Mach Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600405484
Customer Name:	DALES AUTO PARTS & MACH SHOP
Customer Legal Name:	Dales Auto Parts & Mach Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600247142
Customer Name:	JARA OIL INC
Customer Legal Name:	Jara Oil, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100529908
Name:	A LINE AUTO PARTS SOUTH
Address:	3600 S CONGRESS AVE

DALES AUTO PARTS & MACHINE SHOP (Continued) **S103608337**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7214
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600405484
Customer Name:	DALES AUTO PARTS & MACH SHOP
Customer Legal Name:	Dales Auto Parts & Mach Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	453998
Primary NAICS Industry Type Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

CV1700 **BARKER B M AUTOMO** **EDR Hist Auto** **1013756245**
WNW **105 10TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.029 mi.
155 ft. **Site 14 of 14 in cluster CV**

Actual:
512 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1911	BARKER B M AUTOMO	AUTOMOBILE GARAGES

CN1701 **TEXAS EMPLOYMENT COMMISSION** **TX UST** **U001284165**
ESE **101 E 15TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78778** **TX ASBESTOS**
0.030 mi.
156 ft. **Site 3 of 4 in cluster CN**

Actual:
547 ft.

Focus Map:
11

UST:

Name:	TEXAS EMPLOYMENT COMMISSION
Address:	101 E 15TH ST
City,State,Zip:	AUSTIN, TX 787781442
AI Number:	53740
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/17/1990
Facility Status:	INACTIVE
Additional ID:	69692932002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78778
Contact Name/Title:	,
Contact Organization Name:	TEXAS EMPLOYMENT COMMISSION
Contact Mailing Address1:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124632371
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/14/1990
Signature Name/Title On Earliest Reg Form:	DOYLE W COX,PROGRAM DIR
Application Received Date On Earliest Reg Form:	05/16/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600783526
Owner Last Name:	TEXAS EMPLOYMENT COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	60692922002053
Additional ID:	69692932002053
AI Number:	53740
Owner Effective Begin Date:	05/17/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	02/01/1981
Tank Registration Date:	05/16/1990
Number of Compartments:	1
Tank Capacity:	100
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	132161
Facility ID:	83550
Ai Number:	53740
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/14/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/07/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	100
UST Comprt ID:	127299
UST ID:	132161
AI Number:	53740
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS EMPLOYMENT COMMISSION
Contact Mailing Address (Delivery):	101 E 15TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78778 1442
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83550
Additional ID:	69692932002053
Princ ID:	60692922002053
AI Number:	53740
Facility Name:	TEXAS EMPLOYMENT COMMISSION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DOYLE COX/

HIST UST AUSTIN:

Name:	TEXAS EMPLOYMENT COMMISSION
Address:	101 E 15TH ST

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

City,State,Zip:	AUSTIN, TX
Id UST:	C0143
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/22/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/25/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/20/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Start Date:	09/12/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/22/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/25/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Certification Statement Date:	08/21/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/12/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	KAMAL HUSSEIN
Violation:	Not reported
Complaint Date:	09/20/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/16/2016
Certification Statement Phone:	713-856-5354
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/19/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	KAMAL HUSSEIN
Violation:	Not reported
Complaint Date:	09/27/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/16/2016
Certification Statement Phone:	713-856-5354
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/20/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/08/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/19/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/27/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/08/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/27/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	09/08/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/26/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/07/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/21/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/17/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/05/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	01/24/2017
Reason for Inspection:	JOE R ORTIZ
Violation:	Not reported
Complaint Date:	09/13/2015
Notification Number:	2015005350
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/21/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	08/17/2015
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	198
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/12/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	Not reported
Reason for Inspection:	JOE R. ORTIZ
Violation:	Not reported
Complaint Date:	02/07/2016
Notification Number:	2016000893
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/19/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/11/2016
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	13
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TWC MAIN BUILDING
Address:	101 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78778
Date of inspection:	Not reported
Reason for Inspection:	JOE R. ORTIZ
Violation:	Not reported
Complaint Date:	02/14/2016
Notification Number:	2016000893
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0

TEXAS EMPLOYMENT COMMISSION (Continued) **U001284165**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/20/2016
Certification Statement Phone:	832-552-3285
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	13
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DR1702 **CENTRAL SEWING MACH EXCH REPRS** **EDR Hist Auto** **1013756639**
NE **522 6TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
156 ft. **Site 37 of 38 in cluster DR**

Actual:
483 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	ELLIS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1935	ELLIS SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1947	CENTRAL SEWING MACH EXCH REPRS	REPAIR SHOPS

JY1703 **CNANO TECHNOLOGY USA, INC.** **FINDS** **1027140576**
NNE **303 COLORADO ST** **ECHO** **N/A**
< 1/8 **AUSTIN, TX 78701** **PFAS ECHO**
0.030 mi.
157 ft. **Site 1 of 6 in cluster JY**

Actual:
479 ft.

Focus Map:
11

FINDS:
Registry ID: 110071301885

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
TSCA SUBMITTER
Registry ID: 110071194505

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
COMPLIANCE AND EMISSIONS REPORTING
GREENHOUSE GAS REPORTER

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1027140576
Registry ID:	110071194505
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110071194505
Name:	FORMENTERA ANADARKO G&B
Address:	303 COLORADO ST., SUITE 2050
City,State,Zip:	AUSTIN, TX 78701

PFAS ECHO:

Name:	FORMENTERA ANADARKO G&B
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.265668
Longitude:	-97.745153
Count:	1
County:	TRAVIS COUNTY
Status:	Unknown
Region:	06
Industry:	Oil and Gas
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071194505
Facility Percent Minority:	45.908
Facility Derived Tribes:	-
Facility Population:	5634.71
EPA Programs:	-
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	-
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	21
Facility Derived CB2010:	484530011001112
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0

CNANO TECHNOLOGY USA, INC. (Continued) **1027140576**

Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	-
Facility Programs With SNC:	0
Facility Compliance Status:	-
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	Y
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.745153,%22y%22:30.265668,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

JQ1704 **GRAYBURG OIL CO STATION NO** **EDR Hist Auto** **1013763028**
WNW **1601 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
157 ft. **Site 2 of 2 in cluster JQ**

Actual:
543 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	GRAYBURG OIL CO STATION NO	AUTOMOBILE FILLING STATIONS
1935	DEALEY AL SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

GRAYBURG OIL CO STATION NO (Continued) **1013763028**

1940	STROMS SERVICE STA	AUTOMOBILE FILLING STATIONS
1940	STROMS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

DJ1705 **ZUAUTO PARTS LLC** **EDR Hist Auto** **1020433591**
NNE **701 BRAZOS ST STE 720** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.030 mi.
157 ft. **Site 6 of 7 in cluster DJ**

Actual:
506 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2010	LOAN RANGERS AUTOMOTIVE INC	General Automotive Repair Shops
2011	VANEMAN AUTOWORKS INC	General Automotive Repair Shops
2011	ZUAUTO PARTS LLC	General Automotive Repair Shops
2011	MASTODONIC GAS & OIL INC	Gasoline Service Stations, NEC
2011	TRANSMISSION KING INC	Automotive Transmission Repair Shops
2011	HUNT TRANSMISSION	Automotive Transmission Repair Shops
2011	AUTOMOTIVE VENTURES INC	General Automotive Repair Shops
2012	ZUAUTO PARTS LLC	General Automotive Repair Shops
2012	HUNT TRANSMISSION	Automotive Transmission Repair Shops
2012	VANEMAN AUTOWORKS INC	General Automotive Repair Shops
2013	ZUAUTO PARTS LLC	General Automotive Repair Shops

JZ1706 **7-ELEVEN 20079** **TX UST** **U001243547**
WNW **6702 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX Financial Assurance**
0.030 mi.
159 ft. **Site 1 of 3 in cluster JZ**

Actual:
657 ft.

Focus Map:
17

UST:

Name:	7-ELEVEN 20079
Address:	6702 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787454497
AI Number:	7124
Facility Type:	RETAIL
Facility Begin Date:	04/01/1978
Facility Status:	INACTIVE
Additional ID:	559037272002139
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported

7-ELEVEN 20079 (Continued) **U001243547**

Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	559037272002139
Ai Number:	7124
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/03/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	559037272002139
AI Number:	7124
Owner Effective Begin Date:	07/03/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON

7-ELEVEN 20079 (Continued) **U001243547**

Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46131
Cert ID:	26344
AI Number:	7124
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46131
Cert ID:	26343
AI Number:	7124
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46131
Cert ID:	26342
AI Number:	7124
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MANANGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

7-ELEVEN 20079 (Continued) **U001243547**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46131
Cert ID:	26341
AI Number:	7124
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46131
Cert ID:	26340
AI Number:	7124
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46131
Cert ID:	26339
AI Number:	7124
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

7-ELEVEN 20079 (Continued) **U001243547**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46131
Cert ID:	26338
AI Number:	7124
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18452
Facility ID:	46131
Ai Number:	7124
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/19/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

7-ELEVEN 20079 (Continued) **U001243547**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	25917
UST ID:	18452
AI Number:	7124
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N

7-ELEVEN 20079 (Continued) **U001243547**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18453
Facility ID:	46131
Ai Number:	7124
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/19/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

7-ELEVEN 20079 (Continued) **U001243547**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	25918
UST ID:	18453
AI Number:	7124
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

7-ELEVEN 20079 (Continued) **U001243547**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18451
Facility ID:	46131
Ai Number:	7124
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/19/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7-ELEVEN 20079 (Continued) **U001243547**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	25916
UST ID:	18451
AI Number:	7124
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

7-ELEVEN 20079 (Continued) **U001243547**

Construction Notification:

NOC ID:	2474
Facility ID:	46131
AI Number:	7124
Application Received Date:	11/16/2007
Scheduled Construction Date:	12/17/2007
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M71116002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46131
Additional ID:	559037272002139
Princ ID:	959578622001257
AI Number:	7124
Facility Name:	7-ELEVEN 20079
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #20079
Address:	6702 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	1139
HID UST:	Not reported

7-ELEVEN 20079 (Continued) **U001243547**

Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 20079
Address:	6702 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	46131
Finass ID:	28187
AI:	7124
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

JZ1707 **FORMER 7 ELEVEN STORE 20079** **TX LPST** **S109172310**
WNW **6702 S CONGRESS AVE** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.030 mi.
159 ft. **Site 2 of 3 in cluster JZ**

Actual:
657 ft.

Focus Map:
17

LPST:

Name:	FORMER 7 ELEVEN STORE 20079
Address:	6702 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0007124
LPST Id:	117722
Facility Location:	6702 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/16/2007
Entered Date:	06/05/2008
Reported Date:	11/16/2007
Closure Date:	06/13/2008
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	DB2
Responsible Party Name:	Not reported
Responsible Party Contact:	JACK REYNOLDS

FORMER 7 ELEVEN STORE 20079 (Continued) **S109172310**

Responsible Party Address: 6330 COMMERCE DR STE 190
Responsible Party City,St,Zip: IRVING, TX 75063
Responsible Party Telephone: 214/841-6592
Reported Date: 11/16/2007
Case Start Date: 06/13/2008
Reference Number: RN102253721
Project Manager: DBRATBER

GCC:
Name: 7 ELEVEN INC/SHAW ENV
Address: 6702 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 117722
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 6/5/2008
Enforcement Status - Level Of Agency Response: 6 -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

JZ1708 **FORMER 7 ELEVEN 20079** **TX RDR** **S127538595**
WNW **6702 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 3 of 3 in cluster JZ**

Actual:
657 ft.

Focus Map:
17

RDR:
RDR ID: 17217
Facility ID: 7124
RN: Not reported
CN: Not reported
Name: FORMER 7 ELEVEN 20079
Address: 6702 CONGRESS AVE
City,State,Zip: AUSTIN, TX
Date Report Received: 4/10/2008
Due Date: 6/9/2008
Tank Owner: 7 ELEVEN INC
Contact Person: KEN HILLIARD
Report: RDR
Latest TCEQ Letter: New LPST
Date of Latest TCEQ Letter: 6/5/2008
Project Manager: PST Privitization Contract
Team: #N/A
New LPST Number: 117722
Pre-Existing LPST Number: Not reported
Comments: DOES THIS NEED A LPST#?;LADnoAPAR SENT 6/13/08
Review Coordinator: PPC
Date Release Reported: Not reported
Suspected: Not reported

FORMER 7 ELEVEN 20079 (Continued) **S127538595**

Confirmed: Not reported
NOLPST Letter Date: Not reported
Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

IL1709 **MARSHALL BODY WORKS AUTO REPRS** **EDR Hist Auto** **1013776097**
NNE **515 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 7 of 21 in cluster IL**

Actual:
491 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	MARSHALL BODY WORKS AUTO REPRS	AUTOMOBILE REPAIRING

DG1710 **MILLER BRESTE** **TX HIST UST** **S111678748**
NNE **112 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 11 of 16 in cluster DG**

Actual:
502 ft.

HIST UST AUSTIN:

Focus Map:
11

Name: MILLER BRESTE
Address: 112 E 7TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0058
HID UST: 58
Inspection: 04/14/2009
Due: 04/14/2012

DG1711 **GRAYBURG OIL CO.** **TX HIST UST** **S111678651**
NNE **112 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 12 of 16 in cluster DG**

Actual:
502 ft.

HIST UST AUSTIN:

Focus Map:
11

Name: GRAYBURG OIL CO.
Address: 112 E 7TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0234
HID UST: 234
Inspection: 04/14/2009
Due: 04/14/2012

DG1712 **TX HIST UST** **S111678055**
NNE **112 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 13 of 16 in cluster DG**

Actual:
502 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	112 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0035
HID UST:	35
Inspection:	Not reported
Due:	06/01/2012

DG1713 **SCOTT & GREGG** **TX HIST UST** **S111678803**
NNE **112 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 14 of 16 in cluster DG**

Actual:
502 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SCOTT & GREGG
Address:	112 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0105
HID UST:	105
Inspection:	04/14/2009
Due:	04/14/2012

DG1714 **MILLERS GARAGE** **TX HIST UST** **S111678749**
NNE **112 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.030 mi.
159 ft. **Site 15 of 16 in cluster DG**

Actual:
502 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	MILLERS GARAGE
Address:	112 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0204
HID UST:	204
Inspection:	04/14/2009
Due:	04/14/2012

DR1715 NE < 1/8 0.030 mi. 160 ft. | **ELLIS SERVICE STATION FILLING ST**
524 6TH E
AUSTIN, TX
Site 38 of 38 in cluster DR | **EDR Hist Auto** | **1013775593**
N/A

Actual: 483 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	ELLIS SERVICE STATION FILLING S	GASOLINE AND OIL SERVICE STATIONS
1947	WHITEHEAD SERV STA NO 2	GASOLINE AND OIL SERVICE STATIONS

1716 NE < 1/8 0.030 mi. 160 ft. | **JD MARKET 5**
7310 E RIVERSIDE DR
AUSTIN, TX 78741 | **TX UST**
TX HIST UST
TX ASBESTOS
TX Financial Assurance | **U004186409**
N/A

Actual: 506 ft.
Focus Map: 19

UST:

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787416702
AI Number:	84265
Facility Type:	RETAIL
Facility Begin Date:	07/14/2022
Facility Status:	ACTIVE
Additional ID:	334464502011350
Facility Exempt Status:	N
Records Off-Site:	Not reported
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	ADAM AHMAD,PRES
Contact Organization Name:	A M PETROLEUM INC
Contact Mailing Address1:	1900 E ANDERSON LN STE 103
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787521979
Contact Telephone:	5123396008
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	AMPETROLEUM@AOL.COM
Signature Date On Earliest Reg Form:	07/15/2021
Signature Name/Title On Earliest Reg Form:	ADAM AHMOUD,PRES
Application Received Date On Earliest Reg Form:	08/02/2021
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	621521472004118
Additional ID:	334464502011350
Ai Number:	84265
Operator CN:	CN602618324
Operator Name:	A M PETROLEUM INC
Operator Effective Begin Date:	04/27/2011

JD MARKET 5 (Continued) **U004186409**

Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	ADAM AHMAD/PRES
Contact Organization Name:	A M PETROLEUM INC
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78752-1979
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3396008
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	AMPETROLEUM@AOL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602618324
Owner Last Name:	A M PETROLEUM INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78752
Contact Mailing Zip5:	1979
Contact Phone Number/Ext:	1 512 3396008/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	AMPETROLEUM@AOL.COM
Contact Address Deliverable:	Not reported
Princ ID:	621521472004118
Additional ID:	334464502011350
AI Number:	84265
Owner Effective Begin Date:	04/27/2011
State Tax ID:	17429784329
Contact Role:	OWNOPRCON
Contact Name/Title:	ADAM AHMAD/PRES
Contact Organization Name:	A M PETROLEUM INC

Self Certification:

Self Cert ID:	129133
Cert ID:	372811
AI Number:	84265
Self Certification Date:	07/14/2022
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JD MARKET 5 (Continued) **U004186409**

Delivery Certificate Expiration Date:	07/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	357203
AI Number:	84265
Self Certification Date:	07/15/2021
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	340681
AI Number:	84265
Self Certification Date:	07/29/2020
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	322833
AI Number:	84265
Self Certification Date:	07/03/2019
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JD MARKET 5 (Continued) **U004186409**

Delivery Certificate Expiration Date:	07/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	305230
AI Number:	84265
Self Certification Date:	06/07/2018
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	288654
AI Number:	84265
Self Certification Date:	06/26/2017
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	129133
Cert ID:	272354
AI Number:	84265
Self Certification Date:	07/11/2016
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JD MARKET 5 (Continued) **U004186409**

Delivery Certificate Expiration Date:	07/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	129133
Cert ID:	254949
AI Number:	84265
Self Certification Date:	06/13/2015
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	129133
Cert ID:	238248
AI Number:	84265
Self Certification Date:	06/10/2014
Signature Name/Title:	ADAM K AHMAD OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	129133
Cert ID:	221800
AI Number:	84265
Self Certification Date:	07/02/2013
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

JD MARKET 5 (Continued) **U004186409**

Delivery Certificate Expiration Date:	07/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	129133
Cert ID:	216408
AI Number:	84265
Self Certification Date:	05/18/2012
Signature Name/Title:	ADAM AHMAD PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	129133
Cert ID:	216407
AI Number:	84265
Self Certification Date:	12/15/2011
Signature Name/Title:	ADAM AHMAD PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/27/2011
Tank Registration Date:	12/16/2011
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	215856
Facility ID:	129133
Ai Number:	84265

JD MARKET 5 (Continued) **U004186409**

Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/27/2011
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	12/05/2011

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	180189
UST ID:	215856

JD MARKET 5 (Continued) **U004186409**

AI Number:	84265
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/01/2011

Install Date:	04/27/2011
Tank Registration Date:	12/16/2011
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	215857
Facility ID:	129133
Ai Number:	84265
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/27/2011
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

JD MARKET 5 (Continued) **U004186409**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	12/05/2011

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	180190
UST ID:	215857
AI Number:	84265
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

JD MARKET 5 (Continued) **U004186409**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/01/2011
Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	180191
UST ID:	215857
AI Number:	84265
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

JD MARKET 5 (Continued) **U004186409**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/01/2011

Construction Notification:

NOC ID:	23485
Facility ID:	129133
AI Number:	84265
Application Received Date:	02/09/2011
Scheduled Construction Date:	02/25/2011
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	59197
General Desc Of Prop Construct:	INSTALLATION OF NEW UST SYSTEM.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	40650
UST ID:	215856
NOC ID:	Not reported
AI Number:	84265
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported

JD MARKET 5 (Continued) **U004186409**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	40651
UST ID:	215857
NOC ID:	Not reported
AI Number:	84265
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	25181
UST ID:	Not reported
NOC ID:	23485
AI Number:	84265
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000

JD MARKET 5 (Continued) **U004186409**

Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	55793
UST ID:	215857
NOC ID:	Not reported
AI Number:	84265
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	25182
UST ID:	Not reported
NOC ID:	23485
AI Number:	84265
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	55792
UST ID:	215856
NOC ID:	Not reported

JD MARKET 5 (Continued) **U004186409**

AI Number:	84265
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	A M PETROLEUM INC
Contact Mailing Address (Delivery):	1900 E ANDERSON LN STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 1979
Phone Number/Ext:	512 3396008/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	129133
Additional ID:	334464502011350
Princ ID:	621521472004118
AI Number:	84265
Facility Name:	JD MARKET 5
AR Number:	59197
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ADAM AHMAD/

HIST UST AUSTIN:

Name:	JD'S MARKET #5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	3349
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	JDS MARKET
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/23/2014

JD MARKET 5 (Continued) **U004186409**

Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.7
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

JD MARKET 5 (Continued) **U004186409**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JD'S MARKET
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/28/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.9
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported

JD MARKET 5 (Continued) **U004186409**

Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	270662
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2021
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 722499
Policy Number:	04-TO-00012591
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	254022
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

JD MARKET 5 (Continued) **U004186409**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2020
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000012591
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	235512
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2019
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000004066
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	216385
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2018
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-000107704

JD MARKET 5 (Continued) **U004186409**

Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	198724
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2017
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-000102627
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	181826
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2016
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00098123
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2

JD MARKET 5 (Continued) **U004186409**

Facility ID:	129133
Finass ID:	164819
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2015
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-93855
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	152219
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2015
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-93855
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	145928
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

JD MARKET 5 (Continued) **U004186409**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2014
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00089711
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	129702
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2013
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00081735
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	110883
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2012
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00081735
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/25/2013
Ins Premium Pre-Paid For Entire Yr:	Yes

JD MARKET 5 (Continued) **U004186409**

Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	105686
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2011
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000078901
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	JD MARKET 5
Address:	7310 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	129133
Finass ID:	16625
AI:	84265
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/25/2011
Date Financial Assurance Form Rec:	08/02/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000078901
Coverage Amount:	2000000
Coverage Expiration Date:	08/25/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

DF1717 ESE < 1/8 0.030 mi. 160 ft. — **AUSTIN STEPH F HOTEL LNDRY**, **106 7TH E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013782571** / **N/A**

Site 24 of 25 in cluster DF

Actual: 497 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1940	AUSTIN S F HOTEL	LAUNDRIES
1947	AUSTIN STEPH F HOTEL LNDRY	LAUNDRIES

KA1718 SW < 1/8 0.031 mi. 162 ft. — **BEVERAGE BARN**, **2001 E RIVERSIDE BLVD**, **AUSTIN, TX** — **TX RDR** — **S128622461** / **N/A**

Site 1 of 4 in cluster KA

Actual: 497 ft. RDR:

Focus Map: 14

RDR ID:	31542
Facility ID:	19617
RN:	102822178
CN:	605646710
Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/24/2022
Due Date:	4/25/2022
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK oLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/31/2022
Project Manager:	Ross Eide
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KA1719 SW < 1/8 0.031 mi. 162 ft. — **BEVERAGE BARN**, **2001 EAST RIVERSIDE BLVD**, **AUSTIN, TX** — **TX RDR** — **S127526663** / **N/A**

Site 2 of 4 in cluster KA

Actual: 497 ft. RDR:

Focus Map: 14

RDR ID:	29437
Facility ID:	19617
RN:	Not reported
CN:	Not reported

BEVERAGE BARN (Continued) **S127526663**

Name:	BEVERAGE BARN
Address:	2001 EAST RIVERSIDE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/21/2020
Due Date:	2/19/2021
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	2/23/2021
Project Manager:	Kristine Elliott
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	29505
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN
Address:	2001 EAST RIVERSIDE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/8/2021
Due Date:	3/9/2021
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/9/2021
Project Manager:	Kristine Elliott
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORIG PM: OLUSOLA AYILARA
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	29635
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN

BEVERAGE BARN (Continued) **S127526663**

Address:	2001 EAST RIVERSIDE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/1/2021
Due Date:	4/2/2021
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/12/2021
Project Manager:	Ross Eide
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	29795
Facility ID:	19617
RN:	102822178
CN:	601265929
Name:	BEVERAGE BARN
Address:	2001 EAST RIVERSIDE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/10/2021
Due Date:	5/9/2021
Tank Owner:	8700 LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	5/7/2021
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	30158
Facility ID:	19617
RN:	102822178
CN:	601265929
Name:	BEVERAGE BARN
Address:	2001 EAST RIVERSIDE BLVD

BEVERAGE BARN (Continued) **S127526663**

City,State,Zip:	AUSTIN, TX
Date Report Received:	6/4/2021
Due Date:	8/3/2021
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	6/28/2021
Project Manager:	Frank Clayworth
Team:	Team 2
New LPST Number:	121203
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KA1720 **BEVERAGE BARN** **TX RDR** **S127526662**
SW **2001 E RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
162 ft. **Site 3 of 4 in cluster KA**

Actual:
497 ft.

Focus Map:
14

RDR:

RDR ID:	19524
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/10/2011
Due Date:	4/11/2011
Tank Owner:	8700 NORTH LAMAR LIMITED
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/4/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	104786
Comments:	6A
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	4/4/2011
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KA1721	**BEVERAGE BARN**	**TX LPST**	**U001254491**
SW	**2001 E RIVERSIDE DR**	**TX UST**	**N/A**
< 1/8	**AUSTIN, TX 78741**	**TX HIST UST**	
0.031 mi.		**TX ASBESTOS**	
162 ft.	**Site 4 of 4 in cluster KA**	**TX Financial Assurance**	
Actual:		**TX GCC**	
497 ft.		**TX RDR**	

Focus Map:
14

LPST:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0019617
LPST Id:	104786
Facility Location:	1923 E RIVERSIDE DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/28/1992
Entered Date:	10/26/1992
Reported Date:	09/28/1992
Closure Date:	08/07/1996
Priority:	1A - IMPACT/THREAT TO HUMAN HEALTH AND/OR SAFETY
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	IMPACT/THREAT TO HUMAN HEALTH AND/OR SAFETY
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BILL THOMPSON
Responsible Party Address:	609 W 10TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/478-4059
Reported Date:	09/28/1992
Case Start Date:	08/07/1996
Reference Number:	RN102822178
Project Manager:	HWELCH

Name:	BEVERAGE BARN FORMER CITGO STATION
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0019617
LPST Id:	093488
Facility Location:	1923 E RIVERSIDE DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/26/1989
Entered Date:	08/21/1989
Reported Date:	07/26/1989
Closure Date:	08/24/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	BOD
Responsible Party Name:	Not reported

BEVERAGE BARN (Continued) **U001254491**

Responsible Party Contact:	STEPHEN SATHER
Responsible Party Address:	201 W STASSNEY STE 512
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/448-0585
Reported Date:	07/26/1989
Case Start Date:	08/24/1995
Reference Number:	RN102822178
Project Manager:	BOD

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	121203
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	05/17/2021
Entered Date:	06/25/2021
Reported Date:	05/18/2021
Closure Date:	02/08/2022
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	05/18/2021
Case Start Date:	02/08/2022
Reference Number:	RN102822178
Project Manager:	FCLAYWOR

UST:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411324
AI Number:	19617
Facility Type:	RETAIL
Facility Begin Date:	09/05/1986
Facility Status:	ACTIVE
Additional ID:	330727352002225
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	5
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	PATRICK OLIVER,

BEVERAGE BARN (Continued) **U001254491**

Contact Organization Name:	BEVERAGE BARN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123376744
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/11/2022
Signature Name/Title On Earliest Reg Form:	PATRICK OLIVER,VICE PRESIDENT
Application Received Date On Earliest Reg Form:	07/22/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	582485052019102
Additional ID:	330727352002225
Ai Number:	19617
Operator CN:	CN605646710
Operator Name:	V&S ENTERPRISES LC
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601265929
Owner Last Name:	8700 N LAMAR LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

BEVERAGE BARN (Continued) **U001254491**

Contact Address Deliverable:	Not reported
Princ ID:	226664472002155
Additional ID:	330727352002225
AI Number:	19617
Owner Effective Begin Date:	08/01/2002
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	56677
Cert ID:	374107
AI Number:	19617
Self Certification Date:	07/11/2022
Signature Name/Title:	PATRICK OLIVER VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56677
Cert ID:	357376
AI Number:	19617
Self Certification Date:	07/12/2021
Signature Name/Title:	PATRICK OLIVER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56677
Cert ID:	340328
AI Number:	19617
Self Certification Date:	07/10/2020
Signature Name/Title:	PATRICK OLIVER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56677
Cert ID:	324222
AI Number:	19617
Self Certification Date:	08/05/2019
Signature Name/Title:	PATRICK OLIVER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56677
Cert ID:	306285
AI Number:	19617
Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56677
Cert ID:	290655
AI Number:	19617
Self Certification Date:	08/25/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	56677
Cert ID:	272813
AI Number:	19617
Self Certification Date:	07/28/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	56677
Cert ID:	255697
AI Number:	19617
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	56677
Cert ID:	238868
AI Number:	19617
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	56677
Cert ID:	223239
AI Number:	19617
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	56677
Cert ID:	51345
AI Number:	19617
Self Certification Date:	07/11/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51344
AI Number:	19617
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51343
AI Number:	19617
Self Certification Date:	07/20/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51342
AI Number:	19617
Self Certification Date:	07/06/2009
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51341
AI Number:	19617
Self Certification Date:	07/02/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51340
AI Number:	19617
Self Certification Date:	07/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51339
AI Number:	19617
Self Certification Date:	07/05/2006
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56677
Cert ID:	51338
AI Number:	19617
Self Certification Date:	07/11/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56677
Cert ID:	51337
AI Number:	19617
Self Certification Date:	07/06/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56677
Cert ID:	51336
AI Number:	19617
Self Certification Date:	07/02/2003
Signature Name/Title:	GUY NEWELL OLIVER LEGAL AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56677
Cert ID:	51335
AI Number:	19617
Self Certification Date:	08/16/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56677
Cert ID:	51334
AI Number:	19617
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50459
Facility ID:	56677
Ai Number:	19617
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

BEVERAGE BARN (Continued) **U001254491**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	61784
UST ID:	50459
AI Number:	19617
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

BEVERAGE BARN (Continued) **U001254491**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50460
Facility ID:	56677
Ai Number:	19617
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

BEVERAGE BARN (Continued) **U001254491**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	61785
UST ID:	50460
AI Number:	19617
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

BEVERAGE BARN (Continued) **U001254491**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50463
Facility ID:	56677
Ai Number:	19617
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	Y
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

BEVERAGE BARN (Continued) **U001254491**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	4000
UST Comprt ID:	61788
UST ID:	50463
AI Number:	19617
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y

BEVERAGE BARN (Continued) **U001254491**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50462
Facility ID:	56677
Ai Number:	19617
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

BEVERAGE BARN (Continued) **U001254491**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	8000
UST Comprt ID:	61787
UST ID:	50462
AI Number:	19617
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985

BEVERAGE BARN (Continued) **U001254491**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50461
Facility ID:	56677
Ai Number:	19617
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

BEVERAGE BARN (Continued) **U001254491**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	61786
UST ID:	50461
AI Number:	19617
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	33723
Facility ID:	56677
AI Number:	19617
Application Received Date:	10/22/2018
Scheduled Construction Date:	10/23/2018
UST Improvement:	N
UST Installation:	N

BEVERAGE BARN (Continued) **U001254491**

UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	10/22/2018
Signature Date On Form:	10/22/2018
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	PARTNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	8700 N LAMAR LTD
Owner CN At Time Of Construction:	CN601265929
Owner AR At Time Of Construction:	38158
General Desc Of Prop Construct:	REPLACE FLEX HOSE ON DISPENSER 3 & 4 THAT HAS A PIN HOLE LEAD IN IT.

NOC ID:	32320
Facility ID:	56677
AI Number:	19617
Application Received Date:	12/14/2017
Scheduled Construction Date:	01/22/2018
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	10/22/2018
Signature Date On Form:	10/22/2018
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	PARTNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	8700 N LAMAR LTD
Owner CN At Time Of Construction:	CN601265929
Owner AR At Time Of Construction:	38158
General Desc Of Prop Construct:	REPLACE VENT LINES

NOC ID:	28583
Facility ID:	56677
AI Number:	19617
Application Received Date:	12/01/2015
Scheduled Construction Date:	12/31/2015
UST Improvement:	Y

BEVERAGE BARN (Continued) **U001254491**

UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	10/22/2018
Signature Date On Form:	10/22/2018
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	PARTNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	8700 N LAMAR LTD
Owner CN At Time Of Construction:	CN601265929
Owner AR At Time Of Construction:	38158
General Desc Of Prop Construct:	LINE (2) TANKS AND DISCHARGE THE WATER FROM THE TANKS THROUGH CARBON FILTER.

NOC ID:	5281
Facility ID:	56677
AI Number:	19617
Application Received Date:	11/30/2010
Scheduled Construction Date:	12/02/2010
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	Y
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	10/22/2018
Signature Date On Form:	10/22/2018
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	PARTNER
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	38158
General Desc Of Prop Construct:	EXCAVATE DIESEL PRODUCT LINE AT TURBINE TO UNCOVER FLEX HOSE AND TEST FOR LEAK.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	67257
UST ID:	Not reported

BEVERAGE BARN (Continued) **U001254491**

NOC ID:	28583
AI Number:	19617
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	RANGER ENVIRONMENTAL
Representative Name:	DAN AIRY
Mailing Address (Delivery):	7215 MCNEIL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78729
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3351785
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	79900
UST ID:	Not reported
NOC ID:	33723
AI Number:	19617
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	RANGER ENVIRONMENTAL
Representative Name:	TODD STANDLEE
Mailing Address (Delivery):	PO BOX 201179
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78720
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3351785
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3350527
Email Address:	Not reported
Cont/Cons/Installer ID:	79901
UST ID:	Not reported
NOC ID:	33723
AI Number:	19617
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C&J PETROLEUM
Representative Name:	CHUCK NADEAU
Mailing Address (Delivery):	PO BOX 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE

BEVERAGE BARN (Continued) **U001254491**

Mailing State:	TX
Mailing Zip:	76503
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7705454
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	888
Fax Number:	5631655
Email Address:	Not reported
Cont/Cons/Installer ID:	5774
UST ID:	Not reported
NOC ID:	5281
AI Number:	19617
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS
Representative Name:	CHUCK MADEAU
Mailing Address (Delivery):	2305 E ADAMS AVE
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE
Mailing State:	TX
Mailing Zip:	76501
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7700440
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	67258
UST ID:	Not reported
NOC ID:	28583
AI Number:	19617
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C & J PETROLEUM
Representative Name:	CHUCK NADEAU
Mailing Address (Delivery):	150 PRIVATE ROAD 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7219939
Phone Number Extension:	Not reported
Fax Number Country Code:	1

BEVERAGE BARN (Continued) **U001254491**

Fax Number Area Code:	254
Fax Number:	5843325
Email Address:	Not reported
Cont/Cons/Installer ID:	76448
UST ID:	Not reported
NOC ID:	32320
AI Number:	19617
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C & J PETROLEUM
Representative Name:	CHUCK NADEAU
Mailing Address (Delivery):	PO BOX 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE
Mailing State:	TX
Mailing Zip:	76503
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7219939
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	888
Fax Number:	5631656
Email Address:	Not reported
Cont/Cons/Installer ID:	76449
UST ID:	Not reported
NOC ID:	32320
AI Number:	19617
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	NADEAU CHUCK
Representative Name:	Not reported
Mailing Address (Delivery):	150 PR 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	5840408
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	chuck@cjpetro.com
Cont/Cons/Installer ID:	79899
UST ID:	Not reported
NOC ID:	33723
AI Number:	19617
Type Of Contact:	INSTALLER

BEVERAGE BARN (Continued) **U001254491**

Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	NADEAU CHUCK
Representative Name:	Not reported
Mailing Address (Delivery):	150 PR 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7700727
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	chuck@cjpetro.com
Cont/Cons/Installer ID:	5775
UST ID:	Not reported
NOC ID:	5281
AI Number:	19617
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	8700 N LAMAR LTD
Contact Mailing Address (Delivery):	3267 BEE CAVES RD STE 107-92
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6700
Phone Number/Ext:	512 3376744/0
Contact Fax Number/Ext:	/
Contact Email Address:	PBOVENTURES@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	56677
Additional ID:	330727352002225
Princ ID:	226664472002155
AI Number:	19617
Facility Name:	BEVERAGE BARN

BEVERAGE BARN (Continued) **U001254491**

AR Number:	38158
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK OLIVER/

HIST UST AUSTIN:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	828
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

BEVERAGE BARN (Continued) **U001254491**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/17/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

BEVERAGE BARN (Continued) **U001254491**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	271954
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

BEVERAGE BARN (Continued) **U001254491**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2022
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000027614
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	254268
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000018086
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	235170
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000009237
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2021

BEVERAGE BARN (Continued) **U001254491**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	217900
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	213189
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000003193
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	199552

BEVERAGE BARN (Continued) **U001254491**

AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	183385
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	165138
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015

BEVERAGE BARN (Continued) **U001254491**

Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	146487
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-to-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	130233
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

BEVERAGE BARN (Continued) **U001254491**

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	112289
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	112238
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	3613
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

BEVERAGE BARN (Continued) **U001254491**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	37599
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	37600
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

BEVERAGE BARN (Continued) **U001254491**

Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	37601
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	37602
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

BEVERAGE BARN (Continued) **U001254491**

Region:	2
Facility ID:	56677
Finass ID:	37603
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	56677
Finass ID:	37604
AI:	19617
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	07/22/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	121203
Contamination Description: GASOLINE	
Date Of Earliest Known Contamination Confirmation:	5/18/2021
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	2A - Investigation
Data Quality 1:	E,Q

BEVERAGE BARN (Continued) **U001254491**

Section 5236:		Not reported
Type:	Not reported	
Agency:		Not reported
Section:		Not reported
Year Deleted:		Not reported
Location:		Not reported
Data Quality 2:		Not reported

RDR:

RDR ID:	26467
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/18/2018
Due Date:	2/16/2019
Tank Owner:	MTG MANAGEMENT INC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/15/2019
Project Manager:	Reagan Stephens
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	27812
Facility ID:	19617
RN:	Not reported
CN:	Not reported
Name:	BEVERAGE BARN
Address:	2001 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/2019
Due Date:	2/8/2020
Tank Owner:	8700 N LAMAR LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/6/2020
Project Manager:	Saul Garza
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported

BEVERAGE BARN (Continued) **U001254491**

Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KB1722 **AUSTIN TENNYSON 836** **TX RDR** **S127526388**
ESE **11409 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
162 ft. **Site 1 of 3 in cluster KB**

Actual:
763 ft.

Focus Map:
3

RDR:

RDR ID:	13639
Facility ID:	19360
RN:	Not reported
CN:	Not reported
Name:	AUSTIN TENNYSON 836
Address:	11409 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/4/2005
Due Date:	4/5/2005
Tank Owner:	SBC SERVICES INC
Contact Person:	BILL PARK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/22/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	6/29/04
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/22/2005
Date Report Returned:	9/24/2004
Region:	Not reported
DKC RDR (misfiled):	Not reported

KB1723 **TENNYSON 836** **TX UST** **U002262965**
ESE **11409 N LAMAR BLVD** **TX AST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX HIST UST**
0.031 mi. **TX Financial Assurance**
162 ft. **Site 2 of 3 in cluster KB**

Actual:
763 ft.

Focus Map:
3

UST:

Name:	TENNYSON 836
Address:	11409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532662
AI Number:	19360
Facility Type:	Not reported
Facility Begin Date:	09/01/1988

TENNYSON 836 (Continued) **U002262965**

Facility Status:	ACTIVE
Additional ID:	273654602002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	TENNYSON 836 CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8664926836
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	G BEAN,ASST SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	35290742001297
Additional ID:	273654602002150
Ai Number:	19360
Operator CN:	CN600261663
Operator Name:	SOUTHWESTERN BELL TELEPHONE LP
Operator Effective Begin Date:	09/01/1988
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	WILLIAM EISCLE/
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	4119 BROADWAY
Contact Mailing Address (Internal Delivery):	RM 610 ATTN RUBEN VASQUEZ
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78209-6315
Contact Phone Country Code:	0
Contact Phone Area Code:	210
Contact Phone Number:	2831636
Contact Phone Extension:	0
Contact Fax Country Code:	0
Contact Fax Area Code:	210
Contact Fax Number:	8042912
Contact Fax Extension:	0
Contact Email Address:	RV1515@ATT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600261663
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE LP
Owner First Name:	Not reported

TENNYSON 836 (Continued) **U002262965**

Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75202
Contact Mailing Zip5:	5315
Contact Phone Number/Ext:	1 214 4647047/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	35290742001297
Additional ID:	273654602002150
AI Number:	19360
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	ROBERT PICKENS/ENV HLTH & SAFETY MGR
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP

Self Certification:

Self Cert ID:	76477
Cert ID:	116373
AI Number:	19360
Self Certification Date:	02/19/2003
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76477
Cert ID:	116372
AI Number:	19360
Self Certification Date:	03/06/2002
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

TENNYSON 836 (Continued) **U002262965**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76477
Cert ID:	116371
AI Number:	19360
Self Certification Date:	01/15/2001
Signature Name/Title:	MICHAEL A OLIVER SEN ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	50083
Facility ID:	76477
Ai Number:	19360
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/28/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

TENNYSON 836 (Continued) **U002262965**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	113882
UST ID:	50083
AI Number:	19360
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

TENNYSON 836 (Continued) **U002262965**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	11969
Facility ID:	76477
AI Number:	19360
Application Received Date:	08/04/2003
Scheduled Construction Date:	09/22/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	Y
AST Stage I:	N
Historical Tracking Number:	M30804006
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573

General Desc Of Prop Construct: Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76477

TENNYSON 836 (Continued) **U002262965**

Additional ID:	273654602002150
Princ ID:	35290742001297
AI Number:	19360
Facility Name:	TENNYSON 836
AR Number:	22573
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	/

AST:

Name:	TENNYSON 836
Address:	11409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787532662
Facility ID:	76477
Additional ID:	273654602002150
AI Number:	19360
Facility Type:	Not reported
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	Y
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	/
Contact Organization Name:	TENNYSON 836 CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	8664926836
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	05/05/1986
Signature First Name on Earliest Reg Form:	G
Application Received Date on Earliest Reg Form:	05/08/1986
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	BEAN
Signature Title on Earliest Reg Form:	ASST SUPV
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	76477
Tank ID:	1
AST ID:	202800
AI Number:	19360

TENNYSON 836 (Continued) **U002262965**

Install Date:	01/01/2004
Tank Registration Date:	02/25/2004
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/2004
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	10000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

HIST UST AUSTIN:

Name:	S W BELL - TENNYSON
Address:	11409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	975
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	TENNYSON 836
Address:	11409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	76477
Finass ID:	60145
AI:	19360
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No

TENNYSON 836 (Continued) **U002262965**

Proof of Financial Assurance: No

KB1724 **SAME** **TX RDR** **S127526389**
ESE **11409 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
162 ft. **Site 3 of 3 in cluster KB**

Actual:
763 ft.

Focus Map:
3

RDR:

RDR ID:	1679
Facility ID:	19360
RN:	Not reported
CN:	Not reported
Name:	SAME
Address:	11409 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	SOUTHWESTERN BELL
Contact Person:	JONELL WESTERBERG
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	4/22/1997
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	4/22/1997
Region:	Not reported
DKC RDR (misfiled):	Not reported

DP1725 **GRANT JAMES C CLNR** **EDR Hist Cleaner** **1013786191**
SSW **505 BRAZOS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
162 ft. **Site 10 of 16 in cluster DP**

Actual:
487 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1916	GRANT JAMES C CLNR	CLOTHES CLEANERS AND PRESSERS
1922	GRANT JAS DCLO CLNR C	CLOTHES CLEANERS AND PRESSERS

1726 WNW < 1/8 0.031 mi. 163 ft. | **GOLDIE CORPORATION**
3822 S CONGRESS AVE
AUSTIN, TX 78704 | **EDR Hist Auto** | **1021260589**
N/A

Actual: 646 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1973	BEVSCO CORP	Service Establishment Equipment
1974	BEVSCO CORP	Service Establishment Equipment
1976	BEVSCO CORPORATION	General Automotive Repair Shops
1977	BEVSCO CORPORATION	General Automotive Repair Shops
1978	BEVSCO CORPORATION	General Automotive Repair Shops
1979	BEVSCO CORPORATION	General Automotive Repair Shops
1980	S M K INC	General Automotive Repair Shops
1982	S M K INC	General Automotive Repair Shops
1983	S M K INC	General Automotive Repair Shops
1985	COX B G COMPANY*	Automotive Repair Shops, NEC
1986	COX B G COMPANY*	Automotive Repair Shops, NEC
1987	COX B G COMPANY*	Automotive Repair Shops, NEC
1988	COX B G COMPANY	Automotive Repair Shops, NEC
1989	COX B G COMPANY	Automotive Transmission Repair Shops
1990	COX B G COMPANY	Automotive Transmission Repair Shops
1991	COX B G COMPANY	Automotive Transmission Repair Shops
1992	COX B G COMPANY	Automotive Transmission Repair Shops
1993	COX B G COMPANY	Automotive Transmission Repair Shops
1994	COX B G COMPANY	Automotive Transmission Repair Shops
1995	GOLDIE CORPORATION	Automotive Transmission Repair Shops
1996	GOLDIE CORPORATION	Automotive Transmission Repair Shops
1997	GOLDIE CORPORATION	General Automotive Repair Shops
1998	GOLDIE CORPORATION	General Automotive Repair Shops
1999	GOLDIE CORPORATION	General Automotive Repair Shops
2000	GOLDIE CORPORATION	General Automotive Repair Shops
2001	GOLDIE CORPORATION	General Automotive Repair Shops
2002	GOLDIE CORPORATION	General Automotive Repair Shops
2003	GOLDIE CORPORATION	General Automotive Repair Shops
2004	GOLDIE CORPORATION	General Automotive Repair Shops
2005	GOLDIE CORPORATION	General Automotive Repair Shops
2006	GOLDIE CORPORATION	General Automotive Repair Shops
2007	AMERICAN HOMESTEAD	General Automotive Repair Shops
2008	AMERICAN HOMESTEAD	General Automotive Repair Shops
2009	AMERICAN HOMESTEAD	General Automotive Repair Shops
2010	ALOTUS AUTO CENTERS	General Automotive Repair Shops
2010	AMERICAN HOMESTEAD	General Automotive Repair Shops
2011	AMERICAN HOMESTEAD	General Automotive Repair Shops
2011	JEEP MASTERS	General Automotive Repair Shops
2012	JEEP MASTERS	General Automotive Repair Shops
2012	AMERICAN HOMESTEAD	General Automotive Repair Shops
2013	AMERICAN HOMESTEAD	General Automotive Repair Shops
2013	JEEP MASTERS	General Automotive Repair Shops
2014	JEEP MASTERS	General Automotive Repair Shops
2014	AMERICAN HOMESTEAD	General Automotive Repair Shops

IL1727 **HAGOOD SERV STA** **EDR Hist Auto** **1013768716**
NE **519 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
163 ft. **Site 8 of 21 in cluster IL**

Actual:
490 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	CITIES SERVICE OIL CO FILLING S	GASOLINE AND OIL SERVICE STATIONS
1947	JACKSON JACK L F SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	HAGOOD SERV STA	GASOLINE STATIONS
1958	HAGOOD SERV STA	GASOLINE STATIONS
1962	HAGOOD SERV STA	GASOLINE STATIONS

IL1728 **HAGOOD SERVICE STATION** **EDR Hist Auto** **1013766570**
NE **519 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
163 ft. **Site 9 of 21 in cluster IL**

Actual:
490 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	HAGOOD SERVICE STATION	GASOLINE STATIONS

DV1729 **AUS TEX ENGINE** **EDR Hist Auto** **1013756139**
NNE **304 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
163 ft. **Site 4 of 4 in cluster DV**

Actual:
479 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	AUS TEX ENGINE RE	AUTOMOBILE REPAIRING
1958	AUS TEX ENGINE	AUTOMOBILE REPAIRING
1962	AUS TEX ENGINE	AUTOMOBILE REPAIRING

DY1730 **PACKERY CHANNEL BAIT STN LLC** **EDR Hist Auto** **1020289623**
NNE **308 CONGRESS AVE STE B** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.031 mi.
164 ft. **Site 10 of 11 in cluster DY**

Actual:
479 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2013	PACKERY CHANNEL BAIT STN LLC	Gasoline Service Stations
2014	PACKERY CHANNEL BAIT STN LLC	Gasoline Service Stations

KC1731 **CENTEX AUTO REPAIR** **EDR Hist Auto** **1013762675**
SSW **202 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
165 ft. **Site 1 of 3 in cluster KC**

Actual:
475 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	REHFELD HERBERT	AUTOMOBILE REPAIRERS
1940	REHFELD HERBERT	AUTOMOBILE REPAIRING
1947	CARTERS GARAGE	AUTOMOBILE REPAIRING
1953	MIKE!S GARAGE	AUTOMOBILE REPAIRING
1958	JOSEPH AUTO CLINIC	AUTOMOBILE REPAIRING
1962	CENTEX AUTO REPR	AUTOMOBILE REPAIRING
1965	CENTEX AUTO REPAIR	AUTOMOBILE REPAIRING
1970	HOPKINS AUTOMOTIVE	AUTOMOBILE REPAIRING
1980	J W AUTOMOTIVE	AUTOMOBILE REPAIRING
1983	J W AUTOMOTIVE	Automotive Repair Shops, NEC
1984	J W TRANSMISSION AUTO REPR	AUTOMOBILE REPAIRING
1985	J W AUTOMOTIVE	Automotive Repair Shops, NEC
1986	J W AUTOMOTIVE	Automotive Repair Shops, NEC
1987	J W AUTOMOTIVE	Automotive Repair Shops, NEC
1988	J W AUTOMOTIVE	Automotive Repair Shops, NEC
1989	J W AUTOMOTIVE	Automotive Transmission Repair Shops
1990	J W AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	J W AUTOMOTIVE	Automotive Transmission Repair Shops
1991	J W AUTOMOTIVE	Automotive Transmission Repair Shops
1992	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2003	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2004	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2005	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2006	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2007	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2008	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2009	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2010	J W AUTOMOTIVE	Automotive Transmission Repair Shops
2011	J W AUTOMOTIVE	Automotive Transmission Repair Shops

IS1732 **7 ELEVEN 38289** **TX UST** **U004316178**
ESE **701 W BRAKER LN** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Financial Assurance**
0.031 mi.
165 ft. **Site 3 of 3 in cluster IS**

Actual:
776 ft.

Focus Map:
3

UST:

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 787532754
AI Number:	90329
Facility Type:	RETAIL
Facility Begin Date:	09/27/2019
Facility Status:	ACTIVE
Additional ID:	925332512018354
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN

7 ELEVEN 38289 (Continued) **U004316178**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 38289
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	PEGGIE.BETZ@7-11.COM
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Application Received Date On Earliest Reg Form:	Not reported
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	925332512018354
Ai Number:	90329
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	09/27/2019
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711

7 ELEVEN 38289 (Continued) **U004316178**

Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	925332512018354
AI Number:	90329
Owner Effective Begin Date:	09/27/2019
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	135435
Cert ID:	382893
AI Number:	90329
Self Certification Date:	01/17/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	135435
Cert ID:	365522
AI Number:	90329
Self Certification Date:	01/19/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	135435
Cert ID:	347922
AI Number:	90329
Self Certification Date:	01/20/2021

7 ELEVEN 38289 (Continued) **U004316178**

Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	135435
Cert ID:	330957
AI Number:	90329
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	135435
Cert ID:	328561
AI Number:	90329
Self Certification Date:	10/16/2019
Signature Name/Title:	RAYMOND MCNIECE REG COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	09/27/2019
Tank Registration Date:	10/18/2019
Number of Compartments:	1

7 ELEVEN 38289 (Continued) **U004316178**

Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	224133
Facility ID:	135435
Ai Number:	90329
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	09/27/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y

7 ELEVEN 38289 (Continued) **U004316178**

Tank Tested Flag:	Y
Installation Signature Date:	10/09/2019

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	194777
UST ID:	224133
AI Number:	90329
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	09/27/2019
Tank Registration Date:	10/18/2019
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	224134
Facility ID:	135435
Ai Number:	90329
Tank Id:	2

7 ELEVEN 38289 (Continued) **U004316178**

Tank Status (Current):	IN USE
Tank Status Date:	09/27/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	10/09/2019

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	194778
UST ID:	224134
AI Number:	90329

7 ELEVEN 38289 (Continued) **U004316178**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported
Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	194779
UST ID:	224134
AI Number:	90329
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

7 ELEVEN 38289 (Continued) **U004316178**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	33961
Facility ID:	135435
AI Number:	90329
Application Received Date:	12/19/2018
Scheduled Construction Date:	01/14/2019
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	12/19/2018
Signature Date On Form:	12/19/2018
Signature Name On Form:	ANTHONY LEWIS
Signature Company On Form:	PRESTIGE TANK & PUMP SERVICES INC
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	REQUEST 30 DAY WAIVER - INSTALL ONE 20K AND ONE 20K (12K/8K) DW FRP TANKS AND LINES

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	80467

7 ELEVEN 38289 (Continued) **U004316178**

UST ID:	Not reported
NOC ID:	33961
AI Number:	90329
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	APTIM
Representative Name:	JOHN RUFF
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	84116
UST ID:	224134
NOC ID:	Not reported
AI Number:	90329
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK AND PUMP SERVICES INC
Representative Name:	ANTHONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	Not reported
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	84115
UST ID:	224133
NOC ID:	Not reported
AI Number:	90329
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK AND PUMP SERVICES INC
Representative Name:	ANTHONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

7 ELEVEN 38289 (Continued) **U004316178**

Mailing City:	AUSTIN
Mailing State:	Not reported
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	80468
UST ID:	Not reported
NOC ID:	33961
AI Number:	90329
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK & PUMP SERVICES INC
Representative Name:	ANTHONY LEWIS
Mailing Address (Delivery):	PO BOX 170398
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	Not reported
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	84117
UST ID:	224134
NOC ID:	Not reported
AI Number:	90329
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645
Phone Number Extension:	0

7 ELEVEN 38289 (Continued) **U004316178**

Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	80469
UST ID:	Not reported
NOC ID:	33961
AI Number:	90329
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	84114
UST ID:	224133
NOC ID:	Not reported
AI Number:	90329
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	9401 ALTONA WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	6989645
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported

7 ELEVEN 38289 (Continued) **U004316178**

Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 5070913/0
Contact Fax Number/Ext:	/
Contact Email Address:	RAYMOND.MCNIECE@7-11.COM
Contact Address Deliverable:	Y
Facility ID:	135435
Additional ID:	925332512018354
Princ ID:	959578622001257
AI Number:	90329
Facility Name:	7 ELEVEN 38289
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN #38289
Address:	701 W. BRAKER LN.
City,State,Zip:	AUSTIN, TX
Id UST:	3430
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	135435
Finass ID:	280063
AI:	90329
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	135435

7 ELEVEN 38289 (Continued) **U004316178**

Finass ID:	263087
AI:	90329
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 817 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	135435
Finass ID:	242835
AI:	90329
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	135435
Finass ID:	225223
AI:	90329
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7 ELEVEN 38289 (Continued) **U004316178**

Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7 ELEVEN 38289
Address:	701 W BRAKER LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	135435
Finass ID:	222574
AI:	90329
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 646 8266600
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

DG1733 **LINZ NICK TAILOR** **EDR Hist Cleaner** **1013783326**
WSW **607 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.031 mi.
166 ft. **Site 16 of 16 in cluster DG**

Actual:
495 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	LINZ NICK SHOESHINER	CLOTHES PRESSERS AND CLEANERS
1916	LINZ NICK TAILOR	HAT CLEANERS
1916	LINZ NICK TAILOR	CLOTHES CLEANERS AND PRESSERS

DD1734 ESE < 1/8 0.031 mi. 166 ft. — **UNITED STATES CLEANERS INC**, **601 W 5TH ST**, **AUSTIN, TX 78701** — **EDR Hist Cleaner** — **1020111155** / **N/A**

Site 4 of 6 in cluster DD

Actual: 467 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1997	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
1998	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
1999	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
2000	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
2001	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs
2002	UNITED STATES CLEANERS INC	Drycleaning Plants, Except Rugs

---

1735 West < 1/8 0.031 mi. 166 ft. — **QUALITY CLEANERS GR**, **111 E 19TH ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013781858** / **N/A**

Actual: 547 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1965	QUALITY CLEANERS GR	CLEANERS AND DYERS

1736 WNW < 1/8 0.032 mi. 167 ft. — **B & M AUTOMOTIVE AUTO REPAIR**, **511 LIVE OAK ST W**, **TRAVIS (County), TX 78704** — **EDR Hist Auto** — **1013768340** / **N/A**

Actual: 518 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1990	B & M AUTOMOTIVE AUTO REPAIR	AUTOMOBILE REPAIRING

BH1737 WNW < 1/8 0.032 mi. 167 ft. — **TWENTY NINTH STREET**, **604 W 29TH ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783646** / **N/A**

Site 4 of 7 in cluster BH

Actual: 596 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1965	TWENTY NINTH STREET	CLEANERS AND DYERS

KD1738 **SHELL MINI MART 2** **TX UST** **U003188156**
WNW **3906 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX ASBESTOS**
0.032 mi. **TX Financial Assurance**
168 ft. **Site 1 of 4 in cluster KD**

Actual:
664 ft.

Focus Map:
14

UST:

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787047220
AI Number:	69933
Facility Type:	RETAIL
Facility Begin Date:	02/02/2023
Facility Status:	ACTIVE
Additional ID:	667025812002208
Facility Exempt Status:	N
Records Off-Site:	Not reported
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PERVEZ MANASIYA,MANAGER
Contact Organization Name:	SHELL MINI MART 2
Contact Mailing Address1:	3906 S CONGRESS AVE
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787047220
Contact Telephone:	5122933208
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/31/2022
Signature Name/Title On Earliest Reg Form:	SOMI MAREDIA,REP
Application Received Date On Earliest Reg Form:	02/07/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	235394312008105
Additional ID:	667025812002208
Ai Number:	69933
Operator CN:	CN603344102
Operator Name:	HOUSTONAUSTIN INVESTMENTS LLC
Operator Effective Begin Date:	07/15/2011
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	NAVEED QAMAR/MGR
Contact Organization Name:	HOUSTONAUSTIN INVESTMENTS LLC
Contact Mailing Address (Delivery):	2241 S INTERSTATE 35
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78741-3802
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9474501
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

SHELL MINI MART 2 (Continued) **U003188156**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	NAVEEDQAMAR75@GMAIL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603344102
Owner Last Name:	HOUSTONAUSTIN INVESTMENTS LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	2241 S INTERSTATE 35
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78741
Contact Mailing Zip5:	3802
Contact Phone Number/Ext:	1 512 9474501/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	NAVEEDQAMAR75@GMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	235394312008105
Additional ID:	667025812002208
AI Number:	69933
Owner Effective Begin Date:	07/15/2011
State Tax ID:	12239168748
Contact Role:	OWNOPRCON
Contact Name/Title:	NAVEED QAMAR/MGR
Contact Organization Name:	HOUSTONAUSTIN INVESTMENTS LLC

Self Certification:

Self Cert ID:	106201
Cert ID:	383701
AI Number:	69933
Self Certification Date:	02/02/2023
Signature Name/Title:	AMIRALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	367030
AI Number:	69933
Self Certification Date:	01/31/2022

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	356841
AI Number:	69933
Self Certification Date:	07/07/2021
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	339531
AI Number:	69933
Self Certification Date:	06/23/2020
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	323105
AI Number:	69933
Self Certification Date:	07/10/2019

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	AMIR ALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	306473
AI Number:	69933
Self Certification Date:	07/11/2018
Signature Name/Title:	AMIR ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	287876
AI Number:	69933
Self Certification Date:	06/01/2017
Signature Name/Title:	AMIR ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	272014
AI Number:	69933
Self Certification Date:	06/22/2016

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	AMIR ALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	254456
AI Number:	69933
Self Certification Date:	06/03/2015
Signature Name/Title:	AMIRALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	238433
AI Number:	69933
Self Certification Date:	06/30/2014
Signature Name/Title:	AMIRALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106201
Cert ID:	222349
AI Number:	69933
Self Certification Date:	07/18/2013

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	AMIRALI ZINDANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106201
Cert ID:	180359
AI Number:	69933
Self Certification Date:	07/30/2012
Signature Name/Title:	AMIRALI ZINDANI MEMBER/MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106201
Cert ID:	180358
AI Number:	69933
Self Certification Date:	06/30/2011
Signature Name/Title:	FAZIAH MANIAR MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106201
Cert ID:	180357
AI Number:	69933
Self Certification Date:	08/05/2010

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	MUHAMMAD Y AHMED MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180356
AI Number:	69933
Self Certification Date:	07/20/2009
Signature Name/Title:	MUHAMMAD AHMED MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180355
AI Number:	69933
Self Certification Date:	08/11/2008
Signature Name/Title:	SALEEM A/C
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180354
AI Number:	69933
Self Certification Date:	06/16/2007

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	AL ZINDANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180353
AI Number:	69933
Self Certification Date:	06/15/2007
Signature Name/Title:	AL ZINDANI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180352
AI Number:	69933
Self Certification Date:	02/17/2005
Signature Name/Title:	SCOTT HAGGERTON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180351
AI Number:	69933
Self Certification Date:	01/16/2004

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	SCOTT HAGGERTON HSE COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180350
AI Number:	69933
Self Certification Date:	03/04/2003
Signature Name/Title:	SCOTT HAGGERTON HSE COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180349
AI Number:	69933
Self Certification Date:	03/01/2002
Signature Name/Title:	GEORGE CARTWRIGHT SHE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106201
Cert ID:	180348
AI Number:	69933
Self Certification Date:	11/27/2000

SHELL MINI MART 2 (Continued) **U003188156**

Signature Name/Title:	R I RENEAU SH & E COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/01/1994
Tank Registration Date:	08/22/1997
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	184352
Facility ID:	106201
Ai Number:	69933
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

SHELL MINI MART 2 (Continued) **U003188156**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	176525
UST ID:	184352
AI Number:	69933
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

SHELL MINI MART 2 (Continued) **U003188156**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1994
Tank Registration Date:	08/22/1997
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	184353
Facility ID:	106201
Ai Number:	69933
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

SHELL MINI MART 2 (Continued) **U003188156**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	176526
UST ID:	184353
AI Number:	69933
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

SHELL MINI MART 2 (Continued) **U003188156**

Install Date:	08/01/1994
Tank Registration Date:	08/22/1997
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	184354
Facility ID:	106201
Ai Number:	69933
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

SHELL MINI MART 2 (Continued) **U003188156**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	176527
UST ID:	184354
AI Number:	69933
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1994
Tank Registration Date:	08/22/1997
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	184355

SHELL MINI MART 2 (Continued) **U003188156**

Facility ID:	106201
Ai Number:	69933
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	12000

SHELL MINI MART 2 (Continued) **U003188156**

UST Comprt ID:	176528
UST ID:	184355
AI Number:	69933
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	30328
Facility ID:	106201
AI Number:	69933
Application Received Date:	10/14/2016
Scheduled Construction Date:	10/31/2016
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N

SHELL MINI MART 2 (Continued) **U003188156**

Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	10/14/2016
Signature Date On Form:	10/13/2016
Signature Name On Form:	JOEY VALDEZ
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	HOUSTONAUSTIN INVESTMENTS LLC
Owner CN At Time Of Construction:	CN603344102
Owner AR At Time Of Construction:	67587
General Desc Of Prop Construct:	REWORK VENT LINES TO CHANGE TANKS. DIESEL WILL CONVERT TO REGULAR AND PLUS WILL CONVERT TO DIESEL.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	71749
UST ID:	Not reported
NOC ID:	30328
AI Number:	69933
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	MSCS LTD
Representative Name:	CHRIS SHIELD
Mailing Address (Delivery):	109 SHOOTING CLUB A
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BOERNE
Mailing State:	TX
Mailing Zip:	78006
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	8162225
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	830
Fax Number:	2495551
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HOUSTONAUSTIN INVESTMENTS LLC
Contact Mailing Address (Delivery):	9301 SOUTHWEST FWY STE 425
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77074 1430
Phone Number/Ext:	512 2933208/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	106201
Additional ID:	667025812002208
Princ ID:	235394312008105
AI Number:	69933
Facility Name:	SHELL MINI MART 2
AR Number:	82862
AR UST Number Suffix:	Not reported

SHELL MINI MART 2 (Continued) **U003188156**

AR AST Number Suffix:	U
Contact Name/Title:	AMIRALI ZINDANI/OWNER

HIST UST AUSTIN:

Name:	SHELL MINI MART #2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3134
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	COURTESY SHELL
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/27/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	07
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported

SHELL MINI MART 2 (Continued) **U003188156**

ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	COURTESY SHELL
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/20/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/24/2014
Date Routed by Supervisor:	03/24/2014
Date Routed to PSQA:	03/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

SHELL MINI MART 2 (Continued) **U003188156**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	280846
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SHELL MINI MART 2 (Continued) **U003188156**

Financial Assurance Begin Date:	02/13/2022
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 587722
Policy Number:	04-TOP-000026251
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2023
Ins Premium Pre-Paid For Entire Yr:	Not reported
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	253737
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2021
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP005003813
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	264631
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2021
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005003813
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

SHELL MINI MART 2 (Continued) **U003188156**

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	234441
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2020
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	1 800 8428972
Policy Number:	CST2031332-10
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	216721
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2019
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000000297
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	199791
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SHELL MINI MART 2 (Continued) **U003188156**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2018
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000104748
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	180732
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2017
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04-TO-000100101
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	164479
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2016
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

SHELL MINI MART 2 (Continued) **U003188156**

Policy Number:	04-TO-00096237
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	145508
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2014
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-101638
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	130151
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2014
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 800 6905220
Policy Number:	STP101539
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

SHELL MINI MART 2 (Continued) **U003188156**

Region:	2
Facility ID:	106201
Finass ID:	15359
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2012
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	1 713 4811691
Policy Number:	179E04512-12-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	111244
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2012
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	AMERICAN SAFETY INDEM CO
Issuer Phone:	1 832 2074900
Policy Number:	179E04512-12-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/13/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	88517
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

SHELL MINI MART 2 (Continued) **U003188156**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2011
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP76586103
Coverage Amount:	1000000
Coverage Expiration Date:	02/13/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	88518
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2010
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP76586002
Coverage Amount:	1000000
Coverage Expiration Date:	02/13/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	88519
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2009
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP76586101
Coverage Amount:	1000000
Coverage Expiration Date:	02/13/2010

SHELL MINI MART 2 (Continued) **U003188156**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	88520
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/13/2008
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP765861
Coverage Amount:	1000000
Coverage Expiration Date:	02/13/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL MINI MART 2
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	106201
Finass ID:	88521
AI:	69933
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

KD1739 **SHELL** **TX RDR** **S127538244**
WNW **3906 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
168 ft. **Site 2 of 4 in cluster KD**

Actual:
664 ft.

Focus Map:
14

RDR:

RDR ID:	14673
Facility ID:	69933
RN:	Not reported
CN:	Not reported
Name:	SHELL
Address:	3906 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/4/2005
Due Date:	10/3/2005
Tank Owner:	SHELL OIL PRODUCTS US
Contact Person:	JOYCE DAVIS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/2/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/2/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KD1740 **BISHOP GARY** **EDR Hist Auto** **1020395151**
WNW **3906 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.032 mi.
168 ft. **Site 3 of 4 in cluster KD**

Actual:
664 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
2005	BISHOP GARY	Gasoline Service Stations, NEC
2006	BISHOP GARY	Gasoline Service Stations, NEC
2014	COURTESY SHELL 2	Gasoline Service Stations, NEC

KD1741 **TEXACO SERVICE STATION** **TX RDR** **S127538245**
WNW **3906 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
168 ft. **Site 4 of 4 in cluster KD**

Actual:
664 ft.

Focus Map:
14

RDR:

RDR ID:	9340
Facility ID:	69933
RN:	Not reported

TEXACO SERVICE STATION (Continued) **S127538245**

CN:	Not reported
Name:	TEXACO SERVICE STATION
Address:	3906 S CONGRESS
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	STAR ENTERPRISE
Contact Person:	KIRK BRAMMER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/16/1998
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 10
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/16/1998
Date Report Returned:	9/30/1997
Region:	Not reported
DKC RDR (misfiled):	Not reported

1742 **A & M TRAILER REPAIRS** **EDR Hist Auto** **1013765062**
SSE **2702 SHERWOOD LN** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.032 mi.
168 ft.

Actual:
605 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1984	A & M TRAILER REPAIRS	AUTOMOBILE REPAIRING

DP1743 **SAVE WAY SERV** **EDR Hist Auto** **1013770503**
SSW **503 BRAZOS** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
168 ft. **Site 11 of 16 in cluster DP**

Actual:
487 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	SAVE WAY SERV	GASOLINE STATIONS
1962	SAVE WAY SERV	GASOLINE STATIONS
1969	DEAN LUCIEN B	Gasoline Service Stations
1970	DEAN LUCIEN B	Gasoline Service Stations

KE1744 **STEWART DON A INC** **EDR Hist Auto** **1021170095**
ESE **3909 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.032 mi.
168 ft. **Site 1 of 4 in cluster KE**

Actual:
664 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
2006	STEWART DON A INC	Gasoline Service Stations, NEC
2007	STEWART DON A INC	Gasoline Service Stations, NEC
2008	STEWART DON A INC	Gasoline Service Stations, NEC
2009	STEWART DON A INC	Gasoline Service Stations, NEC
2010	STEWART DON A INC	Gasoline Service Stations, NEC
2011	STEWART DON A INC	Gasoline Service Stations, NEC
2012	STEWART DON A INC	Gasoline Service Stations, NEC
2013	STEWART DON A INC	Gasoline Service Stations, NEC
2014	STEWART DON A INC	Gasoline Service Stations, NEC

KE1745 **SOUTH CONGRESS CHEVRON** **TX HIST UST** **S128728706**
ESE **3909 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
168 ft. **Site 2 of 4 in cluster KE**

Actual:
664 ft.
HIST UST AUSTIN:

Focus Map:
14

Name:	SOUTH CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3269
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KE1746 **CONGRESS CHEVRON** **TX UST** **U001275951**
ESE **3909 S CONGRESS AVE** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX ENF**
0.032 mi. **TX Financial Assurance**
168 ft. **Site 3 of 4 in cluster KE**

Actual:
664 ft.
UST:

Focus Map:
14

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787047219
AI Number:	44057
Facility Type:	RETAIL
Facility Begin Date:	02/09/1987
Facility Status:	ACTIVE
Additional ID:	9108872002139
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

CONGRESS CHEVRON (Continued) **U001275951**

Site Location (Location Zip):	78704
Contact Name/Title:	RACHEL ARELLANO,MGR
Contact Organization Name:	CONGRESS CHEVRON
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123122950
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	MANJIYANIRAHIM@GMAIL.COM
Signature Date On Earliest Reg Form:	08/01/2022
Signature Name/Title On Earliest Reg Form:	RAHIM MANIIYANI,MNGR
Application Received Date On Earliest Reg Form:	08/01/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	143482402013162
Additional ID:	9108872002139
Ai Number:	44057
Operator CN:	CN604338228
Operator Name:	SUNSET MANAGEMENT LLC
Operator Effective Begin Date:	04/18/2013
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAHIM MANJIYANI/
Contact Organization Name:	SUNSET MANAGEMENT LLC
Contact Mailing Address (Delivery):	3909 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-7219
Contact Phone Country Code:	1
Contact Phone Area Code:	347
Contact Phone Number:	6838011
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	MANJIYANIRAHIM@GMAIL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604338228
Owner Last Name:	SUNSET MANAGEMENT LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	3909 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	7219
Contact Phone Number/Ext:	1 347 6838011/0
Contact Fax Country Code:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Contact Fax Number/Ext:	/
Contact Email Address:	MANJIYANIRAHIM@GMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	143482402013162
Additional ID:	9108872002139
AI Number:	44057
Owner Effective Begin Date:	04/18/2013
State Tax ID:	32050397887
Contact Role:	OWNOPRCON
Contact Name/Title:	RAHIM MANJIYANI/
Contact Organization Name:	SUNSET MANAGEMENT LLC

Self Certification:

Self Cert ID:	72523
Cert ID:	373777
AI Number:	44057
Self Certification Date:	08/01/2022
Signature Name/Title:	RAHIM MANIIYANI MNGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	357326
AI Number:	44057
Self Certification Date:	06/19/2021
Signature Name/Title:	RAHIM MANJIYANI MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	357257
AI Number:	44057
Self Certification Date:	05/19/2021
Signature Name/Title:	RAHIM MANIIYANI MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	337268
AI Number:	44057
Self Certification Date:	05/26/2020
Signature Name/Title:	RAHIM MAJIYANI MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	320104
AI Number:	44057
Self Certification Date:	04/04/2019
Signature Name/Title:	RAHIM MANJIYANI MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	303601
AI Number:	44057
Self Certification Date:	05/08/2018
Signature Name/Title:	BHAVESH SAVALIA MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	286718
AI Number:	44057
Self Certification Date:	05/14/2017
Signature Name/Title:	BHAVESH SAVALIA MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	268495
AI Number:	44057
Self Certification Date:	03/21/2016
Signature Name/Title:	BHAVESH SAVALIA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	253156
AI Number:	44057
Self Certification Date:	05/12/2015
Signature Name/Title:	BHAVESH SAVALIA MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	236032
AI Number:	44057
Self Certification Date:	04/28/2014
Signature Name/Title:	BHAVESH SAVALIA MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	221107
AI Number:	44057
Self Certification Date:	06/06/2013
Signature Name/Title:	BHAVESH SAVALIA MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72523
Cert ID:	93414
AI Number:	44057
Self Certification Date:	07/31/2012
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93413
AI Number:	44057
Self Certification Date:	07/28/2011
Signature Name/Title:	DOUG STATON GENERAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93412
AI Number:	44057
Self Certification Date:	08/19/2010
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93411
AI Number:	44057
Self Certification Date:	09/01/2009
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93410
AI Number:	44057
Self Certification Date:	08/01/2008
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93409
AI Number:	44057
Self Certification Date:	08/28/2007
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93408
AI Number:	44057
Self Certification Date:	08/31/2006
Signature Name/Title:	DOUG STATON GENERAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93407
AI Number:	44057
Self Certification Date:	07/07/2005
Signature Name/Title:	DOUG STATON GEN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93406
AI Number:	44057
Self Certification Date:	07/07/2004
Signature Name/Title:	DOUGLAS STATON GENERAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93405
AI Number:	44057
Self Certification Date:	08/11/2003
Signature Name/Title:	DOUGLAS STATON GEN MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CONGRESS CHEVRON (Continued) **U001275951**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93404
AI Number:	44057
Self Certification Date:	09/10/2002
Signature Name/Title:	DOUGLAS STATON SALES MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72523
Cert ID:	93403
AI Number:	44057
Self Certification Date:	11/19/2001
Signature Name/Title:	DOUG STATON SALES MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	11/18/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N

CONGRESS CHEVRON (Continued) **U001275951**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	115835
Facility ID:	72523
Ai Number:	44057
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/14/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Compartment Records:

Tank ID:	1A
Tank Capacity:	8000
UST Comprt ID:	103115
UST ID:	115835
AI Number:	44057
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/26/2001
Tank Registration Date:	11/20/2001
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	198837
Facility ID:	72523
Ai Number:	44057
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/26/2001

CONGRESS CHEVRON (Continued) **U001275951**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/15/2001

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	103116
UST ID:	198837
AI Number:	44057
Compartment ID:	A
Substance Stored1:	GASOLINE

CONGRESS CHEVRON (Continued) **U001275951**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/26/2001

Install Date:	06/26/2001
Tank Registration Date:	11/20/2001
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	198838
Facility ID:	72523
Ai Number:	44057
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/26/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

CONGRESS CHEVRON (Continued) **U001275951**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/15/2001

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	103117
UST ID:	198838
AI Number:	44057
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

CONGRESS CHEVRON (Continued) **U001275951**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/26/2001
Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	103118
UST ID:	198838
AI Number:	44057
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N

CONGRESS CHEVRON (Continued) **U001275951**

SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/26/2001

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	29970
UST ID:	198838
NOC ID:	Not reported
AI Number:	44057
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	29969
UST ID:	198837
NOC ID:	Not reported
AI Number:	44057
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45133
UST ID:	198837
NOC ID:	Not reported
AI Number:	44057
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001815
Company Name:	Not reported
Representative Name:	NEIL SMITH
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45134
UST ID:	198838
NOC ID:	Not reported
AI Number:	44057
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001815
Company Name:	Not reported
Representative Name:	NEIL SMITH
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SUNSET MANAGEMENT LLC
Contact Mailing Address (Delivery):	3909 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Contact Mailing City/State/Zip:	AUSTIN, TX 78704 7219
Phone Number/Ext:	512 3850510/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72523
Additional ID:	9108872002139
Princ ID:	143482402013162
AI Number:	44057
Facility Name:	CONGRESS CHEVRON
AR Number:	81758
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAHIM MANJIYANI/

ASBESTOS:

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/27/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MR ZIP
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/20/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	3.3
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/24/2014
Date Routed by Supervisor:	03/24/2014
Date Routed to PSQA:	03/25/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	CONGRESS CHEVRON
Address:	Not reported
City,State,Zip:	TX
Unique TCEQ Ref Number Of Customer:	CN600246607
Unique TCEQ Ref Number Of Reg. Entity:	RN102264629
Contact Person For The Reg. Entity:	DOUG STATON
Owner/operator Of A Regulated Entity:	DON A STEWART INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	GENERAL MANAGER
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	03/24/2006
Description 1:	Failure to ensure that each vapor balance system vent line is equipped with a pressure-vacuum relief valve set to open at a pressure of no more than eight ounces per square inch (3.4 kPa).
Description 2:	On October 3, 2006, Mr. Doug Staton faxed a copy of an invoice, indicating Don A. Stewart, Inc. purchased ten pressure/vaccum vent caps, to the Austin Region Office.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	115.222(6)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704-7219
Unique TCEQ Ref Number Of Customer:	CN604338228
Unique TCEQ Ref Number Of Reg. Entity:	RN102264629
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	SUNSET MANAGEMENT LLC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001557546
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	848,613,072,019,148.00
Role Code:	Not reported
Date Notice Of Violation Issued:	05/30/2019
Description 1:	Failure to maintain spill prevention equipment.
Description 2:	On July 12, 2019, an email with attachments was received by the Austin Regional Office demonstrating the violation noted during the investigation was addressed.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported

CONGRESS CHEVRON (Continued) **U001275951**

TCEQ Rule Number Cited For The Violation:	334.51(b)(2)
Status Of The NOV:	DAPPROVED
Investigation:	1557546
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

TX Financial Assurance 2:

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	271626
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2022
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000026714
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	254154
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2021
Date Financial Assurance Form Rec:	08/01/2022

CONGRESS CHEVRON (Continued) **U001275951**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000017225
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	254219
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2021
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000017225
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	232132
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2020
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-0000008437
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON

CONGRESS CHEVRON (Continued) **U001275951**

Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	213672
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2019
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005000412
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	196942
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2018
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	3744320
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	179691
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

CONGRESS CHEVRON (Continued) **U001275951**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2017
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9991356
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	160216
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2016
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9991356
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/01/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	144208
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/18/2015
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9990409

CONGRESS CHEVRON (Continued) **U001275951**

Coverage Amount:	1,000,000
Coverage Expiration Date:	04/18/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	127166
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/18/2014
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9990409
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/18/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	127608
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/18/2014
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9990409
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/18/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2

CONGRESS CHEVRON (Continued) **U001275951**

Facility ID:	72523
Finass ID:	109556
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/18/2013
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9990409
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/18/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	106917
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2013
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18180
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/01/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	7145
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

CONGRESS CHEVRON (Continued) **U001275951**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2012
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	55003
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2011
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CONGRESS CHEVRON
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	72523
Finass ID:	55004
AI:	44057
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2010
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2011
Ins Premium Pre-Paid For Entire Yr:	Yes

CONGRESS CHEVRON (Continued) **U001275951**

Proof of Financial Assurance: No

Name: CONGRESS CHEVRON
Address: 3909 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78704
Region: 2
Facility ID: 72523
Finass ID: 55005
AI: 44057
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: INSURANCE OR RISK RETENTION
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 01/01/2009
Date Financial Assurance Form Rec: 08/01/2022
Issuer Name: TANK OWNERS MEMBERS INS CO
Issuer Phone: 1 800 3361338
Policy Number: 12120
Coverage Amount: 1000000
Coverage Expiration Date: 01/01/2010
Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: Yes

Name: CONGRESS CHEVRON
Address: 3909 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78704
Region: 2
Facility ID: 72523
Finass ID: 55006
AI: 44057
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: INSURANCE OR RISK RETENTION
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 01/01/2008
Date Financial Assurance Form Rec: 08/01/2022
Issuer Name: TANK OWNERS MEMBERS INS CO
Issuer Phone: 1 800 3361338
Policy Number: 12120
Coverage Amount: 1000000
Coverage Expiration Date: 01/01/2009
Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: Yes

Name: CONGRESS CHEVRON
Address: 3909 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78704
Region: 2
Facility ID: 72523
Finass ID: 55007
AI: 44057

CONGRESS CHEVRON (Continued) **U001275951**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	08/01/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

KE1747 **AUSTIN ARMATURE WORKS** **TX HIST UST** **S128728977**
ESE **3909 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
168 ft. **Site 4 of 4 in cluster KE**

Actual:
664 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	AUSTIN ARMATURE WORKS
Address:	3909 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0261
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KF1748 **TEXAS SCHOOL FOR THE DEAF** **TX LPST** **U003566353**
ESE **1102 S CONGRESS AVE** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX HIST UST**
0.032 mi. **TX ASBESTOS**
169 ft. **Site 1 of 3 in cluster KF**

Actual:
499 ft.

Focus Map:
14

LPST:

Name:	TEXAS SCHOOL FOR DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0048216
LPST Id:	108546
Facility Location:	1102 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/08/1993
Entered Date:	10/05/1994
Reported Date:	10/08/1993
Closure Date:	08/31/1994
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

	assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	TOM HAYS
Responsible Party Address:	PO BOX 13047
Responsible Party City,St,Zip:	AUSTIN, TX 78711
Responsible Party Telephone:	512/463-3217
Reported Date:	10/08/1993
Case Start Date:	08/31/1994
Reference Number:	RN100691435
Project Manager:	HWELCH

UST:

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041728
AI Number:	48216
Facility Type:	FLEET REFUELING
Facility Begin Date:	04/17/1989
Facility Status:	ACTIVE
Additional ID:	344705912002155
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	NICK SULTEMEIER,MAINT MGR
Contact Organization Name:	TEXAS SCHOOL FOR THE DEAF
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124625385
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/05/2022
Signature Name/Title On Earliest Reg Form:	RICHARD BRYANT,OPERTATOR
Application Received Date On Earliest Reg Form:	01/10/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	167546612009246
Additional ID:	344705912002155
Ai Number:	48216
Operator CN:	CN603527441
Operator Name:	TEXAS FACILITIES COMMISSION
Operator Effective Begin Date:	09/01/2016
Operator Type:	SG

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Operator Role:	OWNOPRCON
Contact Name:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78711-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9000333
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603527441
Owner Last Name:	TEXAS FACILITIES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78711
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 9000333/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	167546612009246
Additional ID:	344705912002155
AI Number:	48216
Owner Effective Begin Date:	09/01/2016
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION

Self Certification:

Self Cert ID:	79920
Cert ID:	383124
AI Number:	48216
Self Certification Date:	01/09/2023
Signature Name/Title:	RICHARD BRYANT FACILITY MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	366803
AI Number:	48216
Self Certification Date:	01/05/2022
Signature Name/Title:	RICHARD BRYANT Opertator
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	350452
AI Number:	48216
Self Certification Date:	01/12/2021
Signature Name/Title:	RICHARD BRYANT FAC OPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	330338
AI Number:	48216
Self Certification Date:	01/02/2020
Signature Name/Title:	RICHARD BRYANT TFFA CLASS AB FAC OPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2021

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	316201
AI Number:	48216
Self Certification Date:	02/11/2019
Signature Name/Title:	JEFFREY PARNELL ELECTRICIAN
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	286333
AI Number:	48216
Self Certification Date:	05/09/2017
Signature Name/Title:	KEN HULIN FACILITY MAINTENANACE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	274538
AI Number:	48216
Self Certification Date:	09/01/2016
Signature Name/Title:	KEN HULIN FAC MAINT MGR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2017

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	259385
AI Number:	48216
Self Certification Date:	09/14/2015
Signature Name/Title:	CLAIRE BUGEN SUPERINTENDENT
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	241424
AI Number:	48216
Self Certification Date:	07/31/2014
Signature Name/Title:	DAVID ROES MAINTENANCE MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	227023
AI Number:	48216
Self Certification Date:	08/05/2013
Signature Name/Title:	DAVID ROES MAINT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79920
Cert ID:	128225
AI Number:	48216
Self Certification Date:	07/26/2012
Signature Name/Title:	DAVID ROES MAINT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128224
AI Number:	48216
Self Certification Date:	08/02/2011
Signature Name/Title:	DAVID ROES MAINT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128223
AI Number:	48216
Self Certification Date:	09/13/2010
Signature Name/Title:	MICHAEL WALTERS PLANT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128222
AI Number:	48216
Self Certification Date:	08/13/2009
Signature Name/Title:	MICHAEL WALTERS PLANT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128221
AI Number:	48216
Self Certification Date:	08/27/2008
Signature Name/Title:	MICHAEL WALTERS PLANT MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128220
AI Number:	48216
Self Certification Date:	10/01/2007
Signature Name/Title:	MIKE WALTERS PLANT MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128219
AI Number:	48216
Self Certification Date:	08/02/2006
Signature Name/Title:	MICHAEL WALTERS PLANT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128218
AI Number:	48216
Self Certification Date:	08/23/2005
Signature Name/Title:	MIKE WLATERS PLANT MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128217
AI Number:	48216
Self Certification Date:	09/08/2004
Signature Name/Title:	MIKE WALTERS PLANT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128216
AI Number:	48216
Self Certification Date:	07/29/2003
Signature Name/Title:	RICHARD L DEKING
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128215
AI Number:	48216
Self Certification Date:	07/18/2002
Signature Name/Title:	RICHARD L DEKING
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79920
Cert ID:	128214
AI Number:	48216
Self Certification Date:	11/01/2000
Signature Name/Title:	RICHARD L DEKING PLANT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1975
Tank Registration Date:	04/17/1989
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125554
Facility ID:	79920
Ai Number:	48216
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/07/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	112755
UST ID:	125554
AI Number:	48216
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

More Self Certification:

Self Cert ID:	18560
Cert ID:	98742
UST Comprt ID:	290422
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98745
UST Comprt ID:	290419
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98738
UST Comprt ID:	290424
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98743
UST Comprt ID:	290421
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98741
UST Comprt ID:	290423
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98740
UST Comprt ID:	290426
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98747
UST Comprt ID:	290418
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Self Cert ID:	18560
Cert ID:	98744
UST Comprt ID:	290420
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98739
UST Comprt ID:	290425
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Install Date:	05/01/1981
Tank Registration Date:	04/17/1989
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125555
Facility ID:	79920
Ai Number:	48216
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/07/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	3000
UST Comprt ID:	112756
UST ID:	125555
AI Number:	48216
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	18560
Cert ID:	98742
UST Comprt ID:	290422
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98745
UST Comprt ID:	290419
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98738
UST Comprt ID:	290424
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98743
UST Comprt ID:	290421
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98741
UST Comprt ID:	290423
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98740
UST Comprt ID:	290426
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Self Cert ID:	18560
Cert ID:	98747
UST Comprt ID:	290418
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98744
UST Comprt ID:	290420
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98739
UST Comprt ID:	290425
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Install Date:	09/01/1984
Tank Registration Date:	04/17/1989
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125556
Facility ID:	79920
Ai Number:	48216
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/07/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	500
UST Comprt ID:	112757
UST ID:	125556
AI Number:	48216
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	18560
Cert ID:	98742
UST Comprt ID:	290422
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98745
UST Comprt ID:	290419
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98738
UST Comprt ID:	290424
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98743
UST Comprt ID:	290421
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98741
UST Comprt ID:	290423
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Self Cert ID:	18560
Cert ID:	98740
UST Comprt ID:	290426
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98747
UST Comprt ID:	290418
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98744
UST Comprt ID:	290420
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98739
UST Comprt ID:	290425
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Install Date:	04/01/1992
Tank Registration Date:	04/17/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	125557
Facility ID:	79920
Ai Number:	48216
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	112758
UST ID:	125557
AI Number:	48216
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	18560
Cert ID:	98742
UST Comprt ID:	290422
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98745
UST Comprt ID:	290419
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98738
UST Comprt ID:	290424
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98743
UST Comprt ID:	290421
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Self Cert ID:	18560
Cert ID:	98741
UST Comprt ID:	290423
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98740
UST Comprt ID:	290426
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98747
UST Comprt ID:	290418
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98744
UST Comprt ID:	290420
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98739
UST Comprt ID:	290425
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Install Date:	04/01/1992
Tank Registration Date:	04/17/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	125558
Facility ID:	79920
Ai Number:	48216
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	112759
UST ID:	125558
AI Number:	48216
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	18560
Cert ID:	98742
UST Comprt ID:	290422
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98745
UST Comprt ID:	290419
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A
Self Cert ID:	18560
Cert ID:	98738
UST Comprt ID:	290424
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Self Cert ID:	18560
Cert ID:	98743
UST Comprt ID:	290421
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98741
UST Comprt ID:	290423
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98740
UST Comprt ID:	290426
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98747
UST Comprt ID:	290418
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98744
UST Comprt ID:	290420
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Self Cert ID:	18560
Cert ID:	98739
UST Comprt ID:	290425
UST ID:	108218
AI Number:	48216
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	39097
Facility ID:	79920
AI Number:	48216
Application Received Date:	11/08/2021
Scheduled Construction Date:	12/08/2021
UST Improvement:	N
UST Installation:	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	11/06/2019
Signature Date On Form:	11/06/2019
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	PROJECT MANAGER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	TEXAS FACILITIES COMMISSION
Owner CN At Time Of Construction:	CN603527441
Owner AR At Time Of Construction:	55232
General Desc Of Prop Construct:	Not reported

NOC ID:	35610
Facility ID:	79920
AI Number:	48216
Application Received Date:	11/06/2019
Scheduled Construction Date:	11/06/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	11/06/2019
Signature Date On Form:	11/06/2019
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	PROJECT MANAGER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	TEXAS FACILITIES COMMISSION
Owner CN At Time Of Construction:	CN603527441
Owner AR At Time Of Construction:	55232
General Desc Of Prop Construct:	REPAIR SUMP ENTRY BOOTS ON UNLEADED AND DIESEL TANKS. CUSTOMER REQUEST 30-DAY WAIVER TO REPAIR ENTRIES

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	93147
UST ID:	Not reported
NOC ID:	39097
AI Number:	48216

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	CHRIS MAYS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	CHRIS.MAYS@EXCELLFS.COM

Cont/Cons/Installer ID:	84359
UST ID:	Not reported
NOC ID:	35610
AI Number:	48216
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	84360
UST ID:	Not reported
NOC ID:	35610
AI Number:	48216
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Facility Billing Contacts:

Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78711 3047
Phone Number/Ext:	512 9000333/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79920
Additional ID:	344705912002155
Princ ID:	167546612009246
AI Number:	48216
Facility Name:	TEXAS SCHOOL FOR THE DEAF
AR Number:	55232
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH

HIST UST AUSTIN:

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	EX005
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	RL DAVIS AUDITORIUM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/08/2018
Notification Number:	2018007153
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/05/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/03/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RL DAVIS AUDITORIUM

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/05/2018
Notification Number:	2018007153
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/02/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/03/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	RL DAVIS AUDITORIUM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/05/2018
Notification Number:	2018007153
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/18/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/18/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

TEXAS SCHOOL FOR THE DEAF (Continued) **U003566353**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/03/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

KF1749 **TEXAS SCHOOL FOR THE DEAF** **RCRA NonGen / NLR** **1000157732**
ESE **1102 S CONGRESS AVE** **FTTS** **TXD100077478**
< 1/8 **AUSTIN, TX 78704** **HIST FTTS**
0.032 mi. **FINDS**
169 ft. **Site 2 of 3 in cluster KF** **ECHO**

Actual:
499 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20020115
Handler Name:	Texas School For The Deaf
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD100077478
Contact Name:	M J MELANDER
Contact Address:	PO BOX 3538
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-440-5363
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 3538
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Texas School For The Deaf
Owner Type:	Municipal
Operator Name:	Texas School For The Deaf

TEXAS SCHOOL FOR THE DEAF (Continued) **1000157732**

Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	P039
Waste Description:	Disulfoton (Or) Phosphorodithioic Acid, O,O-Diethyl S-[2-(Ethylthio)Ethyl] Ester
Waste Code:	U226
Waste Description:	Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform
Waste Code:	U239
Waste Description:	Benzene, Dimethyl- (I,T) (Or) Xylene (I)
Waste Code:	U242
Waste Description:	Not Defined

TEXAS SCHOOL FOR THE DEAF (Continued) **1000157732**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE OF TEXAS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TEXAS SCHOOL FOR THE DEAF	
Legal Status:	Municipal
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3538
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-440-5363
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TEXAS SCHOOL FOR THE DEAF	
Legal Status:	Municipal
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3538
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-440-5363
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19870803
Handler Name: TEXAS SCHOOL FOR THE DEAF	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020115
Handler Name: TEXAS SCHOOL FOR THE DEAF	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

TEXAS SCHOOL FOR THE DEAF (Continued) **1000157732**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FTTS INSP:

Inspection Number:	19901130TX004 1
Region:	06
Inspection Date:	11/30/90
Inspector:	THOMAS
Violation occurred:	No
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

HIST FTTS INSP:

Inspection Number:	19901130TX004 1
Region:	06
Inspection Date:	Not reported
Inspector:	THOMAS
Violation occurred:	No
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

FINDS:

Registry ID:	110005069754

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

TEXAS SCHOOL FOR THE DEAF (Continued) **1000157732**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000157732
Registry ID:	110005069754
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005069754
Name:	TEXAS SCHOOL FOR THE DEAF 20-21 DEFERRED CAMPUS MAINTENANCE
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704

KF1750 **TEXAS SCHOOL FOR THE DEAF** **TX ASBESTOS** **S102755654**
ESE **1102 S CONGRESS AVE** **TX LEAD** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX Ind. Haz Waste**
0.032 mi. **TX CENTRAL REGISTRY**
169 ft. **Site 3 of 3 in cluster KF**

Actual:
499 ft.

Focus Map:
14

ASBESTOS:

Name:	TEXAS SCHOOL FOR THE DEAF - DEAF SMITH CENTER
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/21/2018
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/05/2018
Notification Number:	2018000524
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Date Report Received:	01/22/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/22/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF - SEEGER GYM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	06/15/2018

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Notification Number:	2018004575
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/31/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/31/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/14/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/16/2018
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/18/2017
Notification Number:	2017008927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/04/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/04/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/18/2017
Client Code:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/16/2018
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/19/2017
Notification Number:	2017008927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/18/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/18/2017
Certification Statement Phone:	512-260-7171

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF - COTTAGE 570
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	09/17/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/09/2020
Notification Number:	2019009731
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/08/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF - COTTAGE 570
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	09/17/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/08/2020
Notification Number:	2019009731
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/19/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Name:	TEXAS SCHOOL FOR THE DEAF - COTTAGE 568
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	08/04/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/04/2020
Notification Number:	2020004770
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/21/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/21/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	08/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/07/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/07/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/07/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/07/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/14/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/20/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/20/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/31/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/14/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/30/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/30/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/03/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Violation:	Not reported
Complaint Date:	02/21/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/03/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/03/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/07/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/08/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/06/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Start Date:	02/07/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	02/14/2023
Notification Number:	2023000436
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/18/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Certification Statement Date:	01/18/2023
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/31/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVENUE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	04/15/2016
Notification Number:	2016002794
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/30/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/30/2016
Certification Statement Phone:	210-336-8421
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/14/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	01/03/2023
Notification Number:	2022007958
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/14/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	01/03/2023
Notification Number:	2022007958
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/08/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	30
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/06/2017
Notification Number:	2017006717
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/15/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/15/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

ARU:	22
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/02/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF - SEEGER GYM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/06/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/14/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018004575
File Number:	31757
License Status Description:	Current
Expiration Date:	06/15/2018
Original Date:	05/31/2018
Rank Effective Date:	05/31/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	10887
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	TEXAS SCHOOL FOR THE DEAF - COTTAGE 568
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/08/04
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/04/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020004770
File Number:	53868
License Status Description:	Current
Expiration Date:	08/04/2020
Original Date:	07/21/2020
Rank Effective Date:	07/21/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	22753
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/11/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	11/14/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022006853
File Number:	75638
License Status Description:	Current
Expiration Date:	11/14/2022
Original Date:	10/26/2022
Rank Effective Date:	10/26/2022
Mod Code:	ANOT

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	36623
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/14/2022
Reason for Inspection:	Cameron Keeble
Violation:	Not reported
Complaint Date:	11/14/2022
Notification Number:	2022006853
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/31/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/31/2022
Certification Statement Phone:	210-408-8131
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	24
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	11/14/2022
Reason for Inspection:	Cameron Keeble
Violation:	Not reported
Complaint Date:	11/14/2022
Notification Number:	2022006853
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/26/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/26/2022
Certification Statement Phone:	210-408-8131
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	24
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/09/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS SCHOOL FOR THE DEAF - SEEGER GYM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/21/2018
Notification Number:	2018008115
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Date Report Received:	11/19/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/19/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	11/21/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF - SEEGER GYM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/19/2018

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Notification Number:	2018008115
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/02/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	11/19/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS SCHOOL FOR THE DEAF - SEEGER GYM
Address:	1102 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/07/2019
Notification Number:	2019003266
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/23/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/23/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	PLM
Start Date:	05/07/2019
Client Code:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

LEAD:

License Number:	201900021
Address:	1102 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	Region 7
Owner Name:	TEXAS FACILITIES COMMISSION
Client Code:	1400
Client Name:	Environmental Facilities/Notification
Primary Name:	Not reported
DBA Name:	Not reported
Address Type:	Not reported
Mail Name:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State:	Not reported
Mail Zip:	Not reported
File Number:	132904
Expiration Date:	03/16/2019
Origination Date:	03/07/2019
Rank Effective Date:	04/04/2019
License Status Description:	Paid
Modifier Code:	Not reported
Area:	Area 09
Inspector:	VARGAS, JOSEPH
Staff Operator ID:	jvargas
Inspection Number:	48975
Inspection End Date:	03/14/2019
Inspection Status:	Closed
Inspection Type Description:	Notified
Disposition:	Not reported
Inspection Visit ID:	1522192
Inspection Visit End Date:	03/14/2019
Visit Disposition:	Not reported
Inspection Discipline ID:	Not reported
Inspection Discipline Description:	On Site (Facility)
Inspection Class Description:	Environmental
Inspection Secondary Code:	Not reported
Inspection Secondary Code Description:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Results:	Pass
Inspection Number Grade:	Not reported
Inspection Start Date:	03/14/2019
Board Name:	Not reported
License Type Code:	Not reported
Status Date:	Not reported
Rank Description:	Not reported
Entity Number ID:	Not reported

Ind. Haz Waste:

Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	74310
Registration Initial Notification Date:	08/31/1987
Registration Last Amendment Date:	01/15/2002
EPA Identification:	TXD100077478
Primary NAICS Code:	Not reported
Status Change Date:	19870831
Land Type:	Not reported
Description of Facility Site Location:	1102 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS SCHOOL FOR THE DEAF
Contact Name:	M J MELANDER
Contact Telephone Number:	512-4405363
Mailing Address:	PO BOX 3538
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787643538
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28690
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS SCHOOL FOR THE DEAF
Operator Address:	PO BOX 3538
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78764
Operator Country:	UNITED STA
Operator Telephone:	1-512-4405363
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS SCHOOL FOR THE DEAF
Owner Mailing Address:	PO BOX 3538
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78764
Owner Country:	UNITED STA
Owner Telephone:	1-512-4405363
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 3538
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4405363
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 3538
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4405363
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	M MELANDER

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 3538
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4405363
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600397947
Customer Name:	TEXAS SCHOOL FOR THE BLIND
Customer Legal Name:	Texas School for the Blind
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	9/25/2002
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600397947
Customer Name:	TEXAS SCHOOL FOR THE BLIND
Customer Legal Name:	Texas School for the Blind
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	9/25/2002
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601253487
Customer Name:	TEXAS SCHOOL FOR THE DEAF

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Customer Legal Name:	Texas School for the Deaf
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	4/20/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601253487
Customer Name:	TEXAS SCHOOL FOR THE DEAF
Customer Legal Name:	Texas School for the Deaf
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	4/20/1989
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605347285
Customer Name:	CHARTER COMMUNICATIONS VI LLC
Customer Legal Name:	Charter Communications VI, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/8/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605347285
Customer Name:	CHARTER COMMUNICATIONS VI LLC
Customer Legal Name:	Charter Communications VI, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/8/2018

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603527441
Customer Name:	TEXAS FACILITIES COMMISSION
Customer Legal Name:	Texas Facilities Commission
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	9/1/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603527441
Customer Name:	TEXAS FACILITIES COMMISSION
Customer Legal Name:	Texas Facilities Commission
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	9/1/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110
Primary NAICS Industry Type Description:	Elementary and Secondary Schools
Physical Location Description:	1102 S Congress Avenue, Austin, TX

Regulated Entity Number:	RN100691435
Name:	TEXAS SCHOOL FOR THE DEAF
Address:	1102 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-1728
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600311591
Customer Name:	GENERAL SERVICES ADMINISTRATION
Customer Legal Name:	General Services Administration
Customer Ownership Type:	FEDERAL GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	611110

TEXAS SCHOOL FOR THE DEAF (Continued) **S102755654**

Primary NAICS Industry Type Description: Elementary and Secondary Schools
Physical Location Description: 1102 S Congress Avenue, Austin, TX

Regulated Entity Number: RN100691435
Name: TEXAS SCHOOL FOR THE DEAF
Address: 1102 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1728
Status: ACTIVE
Status Date: ##########
Customer Number: CN600311591
Customer Name: GENERAL SERVICES ADMINISTRATION
Customer Legal Name: General Services Administration
Customer Ownership Type: FEDERAL GOVERNMENT
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 611110
Primary NAICS Industry Type Description: Elementary and Secondary Schools
Physical Location Description: 1102 S Congress Avenue, Austin, TX

Regulated Entity Number: RN100691435
Name: TEXAS SCHOOL FOR THE DEAF
Address: 1102 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-1728
Status: ACTIVE
Status Date: ##########
Customer Number: CN602506420
Customer Name: SATTERFIELD AND PONTIKES CONSTRUCTION INC
Customer Legal Name: Satterfield and Pontikes Construction, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 5/26/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 611110
Primary NAICS Industry Type Description: Elementary and Secondary Schools
Physical Location Description: 1102 S Congress Avenue, Austin, TX

Click this hyperlink while viewing on your computer to access
20 additional TX CENTRAL REG: record(s) in the EDR Site Report.

1751 SW < 1/8 0.032 mi. 170 ft. | **RED BALL TAXI CO.** **301 W RIVERSIDE DR** **AUSTIN, TX** | **TX HIST UST** | **S111678788** **N/A**

Actual: 455 ft.
Focus Map: 14

HIST UST AUSTIN:
Name: RED BALL TAXI CO.
Address: 301 W RIVERSIDE DR
City,State,Zip: AUSTIN, TX
Id UST: H0448
HID UST: 448
Inspection: 04/24/2009
Due: 04/24/2012

JA1752 **MILLNER BROS SERVICE STA FILLING** **EDR Hist Auto** **1013773049**
WNW **813 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
170 ft. **Site 3 of 15 in cluster JA**

Actual:
505 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	MILLNER BROS SERVICE STA FILLIN	GASOLINE AND OIL SERVICE STATIONS

1753 **GREASERS** **TX UST** **U001272937**
SE **8415 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.032 mi.
170 ft.

Actual:
711 ft.

Focus Map:
6

UST:

Name:	GREASERS
Address:	8415 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535922
AI Number:	40439
Facility Type:	UNKNOWN
Facility Begin Date:	01/19/1987
Facility Status:	INACTIVE
Additional ID:	720614302002186
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	GREASERS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128377667
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	GARY GUSTAFSON,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601381445
Owner Last Name:	PHAN
Owner First Name:	TRONG
Owner Middle Name:	Q
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

GREASERS (Continued) **U001272937**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	706614292002186
Additional ID:	720614302002186
AI Number:	40439
Owner Effective Begin Date:	06/15/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Owner CN:	CN601381452
Owner Last Name:	PHAN
Owner First Name:	HAI
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	712614292002186
Additional ID:	720614302002186
AI Number:	40439
Owner Effective Begin Date:	06/15/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	107172
Facility ID:	89549
Ai Number:	40439
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1994

GREASERS (Continued) **U001272937**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/11/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	150875
UST ID:	107172
AI Number:	40439
Compartment ID:	A
Substance Stored1:	NEW OIL

GREASERS (Continued) **U001272937**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	107173
Facility ID:	89549
Ai Number:	40439
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

GREASERS (Continued) **U001272937**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/11/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	150876
UST ID:	107173
AI Number:	40439
Compartment ID:	A
Substance Stored1:	NEW OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

GREASERS (Continued) **U001272937**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	18000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	107174
Facility ID:	89549
Ai Number:	40439
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

GREASERS (Continued) **U001272937**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/11/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	18000
UST Comprt ID:	150877
UST ID:	107174
AI Number:	40439
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

GREASERS (Continued) **U001272937**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PHAN TRONG Q AND PHAN HAI V
Contact Mailing Address (Delivery):	11605 AUS TEX ACRES LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	MANOR, TX 78653 3649
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89549
Additional ID:	720614302002186
Princ ID:	712614292002186
AI Number:	40439
Facility Name:	GREASERS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HOAN PHAN/

HIST UST AUSTIN:

Name:	NOVA BODY SHOP
Address:	8415 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0489
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

JP1754 **NUNEZ BROS TAILORS** **EDR Hist Cleaner** **1020052045**
SSW **506 BRAZOS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.032 mi.
170 ft. **Site 3 of 27 in cluster JP**

Actual:
487 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1969	NUNEZ BROS TAILORS	Drycleaning Plants, Except Rugs

KG1755 **CONSUMERS HOME ICE CO.** **TX HIST UST** **S111678612**
ESE **361 W 4TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
170 ft. **Site 1 of 4 in cluster KG**

Actual:
478 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	CONSUMERS HOME ICE CO.
Address:	361 W 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0321
HID UST:	321
Inspection:	Not reported
Due:	06/01/2012

KH1756 **AUSTIN MOTOR INN** **EDR Hist Auto** **1013753110**
SSW **207 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
171 ft. **Site 1 of 19 in cluster KH**

Actual:
476 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	AUSTIN MOTOR INN	AUTOMOBILE GARAGES

KH1757 **TX HIST UST** **S128729213**
SSW **207 CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.032 mi.
171 ft. **Site 2 of 19 in cluster KH**

Actual:
476 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	Not reported
Address:	207 CONGRESS
City,State,Zip:	AUSTIN, TX
Id UST:	H0205
HID UST:	Not reported
Inspection:	06/28/1928
Due:	Not reported

KI1758 **EXXON MOBIL CORPORATION** **EDR Hist Auto** **1020712670**
West **1100 W PARMER LN** **N/A**
< 1/8 **AUSTIN, TX 78727**
0.033 mi.
173 ft. **Site 1 of 4 in cluster KI**

Actual:
709 ft.

EDR Hist Auto

Focus Map:
2

Year:	Name:	Type:
2000	EXXON TIGER MART	Gasoline Service Stations
2001	EXXON TIGER MART	Gasoline Service Stations
2002	EXXON TIGER MART	Gasoline Service Stations
2003	EXXON TIGER MART	Gasoline Service Stations
2004	EXXON TIGER MART	Gasoline Service Stations
2005	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2006	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2007	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2008	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2009	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2010	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2011	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2012	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC

KI1759 **EXXON RAS NO 60117** **RCRA NonGen / NLR** **1004787941**
West **1100 W PARMER** **FINDS** **TXR000034850**
< 1/8 **AUSTIN, TX 78748** **ECHO**
0.033 mi.
173 ft. **Site 2 of 4 in cluster KI**

Actual:
709 ft.

RCRA Listings:

Focus Map:
2

Date Form Received by Agency:	20140108
Handler Name:	Exxon Ras No 60117
Handler Address:	W PARMER
Handler City,State,Zip:	AUSTIN, TX 78748
EPA ID:	TXR000034850
Contact Name:	ALDA S POOL
Contact Address:	1200 TIMBERLOCH PLACE
Contact City,State,Zip:	THE WOODLANDS, TX 77380
Contact Telephone:	281-296-3579
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	TIMBERLOCH PLACE
Mailing City,State,Zip:	THE WOODLANDS, TX 77380
Owner Name:	Exxon Mobil
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

EXXON RAS NO 60117 (Continued) **1004787941**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140109
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4999
Owner/Operator City,State,Zip:	THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone:	281-296-3655
Owner/Operator Telephone Ext:	Not reported

EXXON RAS NO 60117 (Continued) **1004787941**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4999
Owner/Operator City,State,Zip: THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone: 281-296-3655
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000215
Handler Name: EXXON RAS NO 60117
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140108
Handler Name: EXXON RAS NO 60117
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005187412

EXXON RAS NO 60117 (Continued) **1004787941**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004787941
Registry ID:	110005187412
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005187412
Name:	EXXON RAS NO 60117
Address:	1100 W PARMER
City,State,Zip:	AUSTIN, TX 78748

KI1760 **7-ELEVEN STORE 36588** **TX UST** **U003666171**
West **1100 W PARMER LN** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78727** **TX ASBESTOS**
0.033 mi. **TX ED AQUIF**
173 ft. **Site 3 of 4 in cluster KI** **TX Financial Assurance**

Actual:
709 ft.

Focus Map:
2

UST:

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 787274607
AI Number:	72244
Facility Type:	RETAIL
Facility Begin Date:	12/02/1998
Facility Status:	ACTIVE
Additional ID:	914631072002175
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 36588
Contact Mailing Address1:	1100 W PARMER LN
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787274607
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/16/1999
Signature Name/Title On Earliest Reg Form:	B H HUNTER,REG ADMIN
Application Received Date On Earliest Reg Form:	07/23/1999
Signature Role On Earliest Reg Form:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	914631072002175
Ai Number:	72244
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	12/28/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	914631072002175
AI Number:	72244
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	382225
AI Number:	72244
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	364909
AI Number:	72244
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	347701
AI Number:	72244
Self Certification Date:	01/18/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	330532
AI Number:	72244
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	314503
AI Number:	72244
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	295992
AI Number:	72244
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	280551
AI Number:	72244
Self Certification Date:	01/18/2017
Signature Name/Title:	Raymond Mcniece Enironmental Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	263879
AI Number:	72244
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	247409
AI Number:	72244
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	230805
AI Number:	72244
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109944
Cert ID:	186254
AI Number:	72244
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186253
AI Number:	72244
Self Certification Date:	01/09/2012
Signature Name/Title:	CARLTON LABEFF AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	186252
AI Number:	72244
Self Certification Date:	04/01/2011
Signature Name/Title:	TARONZA L GRAVES REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186251
AI Number:	72244
Self Certification Date:	03/15/2010
Signature Name/Title:	TARONZA L GRAVES OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186250
AI Number:	72244
Self Certification Date:	03/27/2009
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	186249
AI Number:	72244
Self Certification Date:	03/26/2008
Signature Name/Title:	ADRIANNE RUTHERFORD OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186248
AI Number:	72244
Self Certification Date:	04/01/2007
Signature Name/Title:	HEATHER GILLMORE AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186247
AI Number:	72244
Self Certification Date:	03/06/2006
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	186246
AI Number:	72244
Self Certification Date:	03/15/2005
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186245
AI Number:	72244
Self Certification Date:	03/12/2004
Signature Name/Title:	ERIC M. MCPHEE CMS PERMITTING MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186244
AI Number:	72244
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cert ID:	186243
AI Number:	72244
Self Certification Date:	03/13/2002
Signature Name/Title:	WENDY SALAS PERMIT LEAD TEAM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109944
Cert ID:	186242
AI Number:	72244
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/02/1998
Tank Registration Date:	07/23/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191481
Facility ID:	109944
Ai Number:	72244
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/02/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

7-ELEVEN STORE 36588 (Continued) **U003666171**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/19/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	170595
UST ID:	191481
AI Number:	72244
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y

7-ELEVEN STORE 36588 (Continued) **U003666171**

CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/02/1998

Install Date:	12/02/1998
Tank Registration Date:	07/23/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191482
Facility ID:	109944
Ai Number:	72244
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	12/02/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

7-ELEVEN STORE 36588 (Continued) **U003666171**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/19/1999

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	170596
UST ID:	191482
AI Number:	72244
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y

7-ELEVEN STORE 36588 (Continued) **U003666171**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/02/1998

Install Date:	12/02/1998
Tank Registration Date:	07/23/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191483
Facility ID:	109944
Ai Number:	72244
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	12/02/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

7-ELEVEN STORE 36588 (Continued) **U003666171**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/19/1999

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	170597
UST ID:	191483
AI Number:	72244
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

7-ELEVEN STORE 36588 (Continued) **U003666171**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/02/1998

Construction Notification:

NOC ID:	26062
Facility ID:	109944
AI Number:	72244
Application Received Date:	07/07/2014
Scheduled Construction Date:	08/03/2014
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	07/07/2014
Signature Date On Form:	07/03/2014
Signature Name On Form:	NATE LAWSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REPLACE 8 EXISTING DISPENSERS WITH NEW WAYNE DISPENSERS. CONVERT EXISTING PREMIUM TANK TO DIESEL, BREAK CONCRETE AND INSTALL NEW VENT LINE FOR PROPOSED DIESEL TANKS.

NOC ID:	19236
Facility ID:	109944
AI Number:	72244
Application Received Date:	04/12/2005
Scheduled Construction Date:	07/27/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N

7-ELEVEN STORE 36588 (Continued) **U003666171**

UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50412065
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	07/07/2014
Signature Date On Form:	07/03/2014
Signature Name On Form:	NATE LAWSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	4194
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	60852
UST ID:	Not reported
NOC ID:	26062
AI Number:	72244
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CB&I
Representative Name:	JENNIFER DART
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	Not reported

Cont/Cons/Installer ID:	38345
UST ID:	191482
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001163
Company Name:	J & S Fuel Systems
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	38344
UST ID:	191481
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001163
Company Name:	J & S Fuel Systems
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	38346
UST ID:	191483
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001163
Company Name:	J & S Fuel Systems
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Cont/Cons/Installer ID:	60853
UST ID:	Not reported
NOC ID:	26062
AI Number:	72244
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	20564
UST ID:	Not reported
NOC ID:	19236
AI Number:	72244
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000665
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	60851
UST ID:	Not reported
NOC ID:	26062
AI Number:	72244
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	STOVALL BOBBY GEORGE
Representative Name:	Not reported
Mailing Address (Delivery):	902 BOWER DR

7-ELEVEN STORE 36588 (Continued) **U003666171**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75061
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	BSTOVALL@MCCONBUILDING.COM

Cont/Cons/Installer ID:	53503
UST ID:	191483
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000110
Company Name:	Not reported
Representative Name:	JOE WIGGINTON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	53501
UST ID:	191481
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000110
Company Name:	Not reported
Representative Name:	JOE WIGGINTON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	53502
UST ID:	191482
NOC ID:	Not reported
AI Number:	72244
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000110
Company Name:	Not reported
Representative Name:	JOE WIGGINTON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	109944
Additional ID:	914631072002175
Princ ID:	959578622001257
AI Number:	72244
Facility Name:	7-ELEVEN STORE 36588
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN #36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX
Id UST:	3228
HID UST:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	07/12/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.9
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/15/2013
Date Routed by Supervisor:	07/15/2013
Date Routed to PSQA:	08/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ED AQUIF:

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Permit Number:	11-14082601
Primary SIC Code:	5411
Primary NAICS Code:	447110
Regulated entity #:	RN102137015
Type Of Project:	MODIFIED UST
Receive Date:	08/26/2014
General Location:	WEST OF 1 35 ON PARMER
Mailing Address:	12005 FORD RD STE 600
Mailing Address2:	Not reported
Mailing City,St,Zip:	DALLAS, TX 75234 7253
Lat/Long:	30.4074 / -97.6785
Owner Type:	CUSTCONT
Owner Name:	VICTOR RUIZ
Owner Address:	PO BOX 711
Owner City,St,Zip:	DALLAS, TX 75221 0711
Owner Phone:	2142136525
Applicant Name:	JACK REYNOLDS
Applicant Address:	12005 FORD RD STE 600
Applicant City,St,Zip:	DALLAS, TX 75234 7253
Application Phone:	9727739443
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Permit Number:	11-14082601
Primary SIC Code:	5411
Primary NAICS Code:	447110
Regulated entity #:	RN102137015
Type Of Project:	MODIFIED UST
Receive Date:	08/26/2014
General Location:	WEST OF 1 35 ON PARMER
Mailing Address:	12005 FORD RD STE 600

7-ELEVEN STORE 36588 (Continued) **U003666171**

Mailing Address2:	Not reported
Mailing City,St,Zip:	DALLAS, TX 75234 7253
Lat/Long:	30.4074 / -97.6785
Owner Type:	CUSTCONT
Owner Name:	VICTOR RUIZ
Owner Address:	PO BOX 711
Owner City,St,Zip:	DALLAS, TX 75221 0711
Owner Phone:	2142136525
Applicant Name:	JACK REYNOLDS
Applicant Address:	12005 FORD RD STE 600
Applicant City,St,Zip:	DALLAS, TX 75234 7253
Application Phone:	9727739443
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Permit Number:	11-14082601
Primary SIC Code:	5411
Primary NAICS Code:	447110
Regulated entity #:	RN102137015
Type Of Project:	MODIFIED UST
Receive Date:	08/26/2014
General Location:	WEST OF 1 35 ON PARMER
Mailing Address:	PO BOX 711
Mailing Address2:	Not reported
Mailing City,St,Zip:	DALLAS, TX 75221 0711
Lat/Long:	30.4074 / -97.6785
Owner Type:	CUSTCONT
Owner Name:	VICTOR RUIZ
Owner Address:	PO BOX 711
Owner City,St,Zip:	DALLAS, TX 75221 0711
Owner Phone:	2142136525
Applicant Name:	JACK REYNOLDS
Applicant Address:	12005 FORD RD STE 600
Applicant City,St,Zip:	DALLAS, TX 75234 7253
Application Phone:	9727739443
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Permit Number:	11-14082601
Primary SIC Code:	5411
Primary NAICS Code:	447110
Regulated entity #:	RN102137015
Type Of Project:	MODIFIED UST
Receive Date:	08/26/2014
General Location:	WEST OF 1 35 ON PARMER
Mailing Address:	PO BOX 711
Mailing Address2:	Not reported
Mailing City,St,Zip:	DALLAS, TX 75221 0711
Lat/Long:	30.4074 / -97.6785

7-ELEVEN STORE 36588 (Continued) **U003666171**

Owner Type:	CUSTCONT
Owner Name:	VICTOR RUIZ
Owner Address:	PO BOX 711
Owner City,St,Zip:	DALLAS, TX 75221 0711
Owner Phone:	2142136525
Applicant Name:	JACK REYNOLDS
Applicant Address:	12005 FORD RD STE 600
Applicant City,St,Zip:	DALLAS, TX 75234 7253
Application Phone:	9727739443
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	279350
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	262207
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001

7-ELEVEN STORE 36588 (Continued) **U003666171**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	242281
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	224733
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2

7-ELEVEN STORE 36588 (Continued) **U003666171**

Facility ID:	109944
Finass ID:	207947
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	189252
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	173476
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7-ELEVEN STORE 36588 (Continued) **U003666171**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	154708
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	138265
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No

7-ELEVEN STORE 36588 (Continued) **U003666171**

Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	118481
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	120840
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	13773
AI:	72244

7-ELEVEN STORE 36588 (Continued) **U003666171**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90272
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90273
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2011
Date Financial Assurance Form Rec:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	177722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90274
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90275
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588

7-ELEVEN STORE 36588 (Continued) **U003666171**

Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90276
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90277
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90278
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

7-ELEVEN STORE 36588 (Continued) **U003666171**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN STORE 36588
Address:	1100 W PARMER LN
City,State,Zip:	AUSTIN, TX 78727
Region:	2
Facility ID:	109944
Finass ID:	90279
AI:	72244
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

1761 East < 1/8 0.033 mi. 173 ft. **JAMES DREW RENTAL INC** **TX HIST UST** **S128728909**
408 N I 35 **N/A**
AUSTIN, TX

Actual: 467 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	JAMES DREW RENTAL INC
Address:	408 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0119
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Q1762 ESE < 1/8 0.033 mi. 173 ft. | **SAFETY RIDE CAR CARE CENTER**
9307 LAMAR BLVD N
TRAVIS (County), TX 78753
Site 2 of 2 in cluster Q | **EDR Hist Auto** | **1013756076**
N/A

Actual: 684 ft.
Focus Map: 6

EDR Hist Auto

Year:	Name:	Type:
1976	LOVE TIRE COMPANY INC	Auto And Home Supply Stores
1977	LOVE TIRE COMPANY INC	Auto And Home Supply Stores
1987	T & H INDUSTRIES INC	Auto And Home Supply Stores
1988	T & H INDUSTRIES INC	Auto And Home Supply Stores
1990	SAFETY RIDE CAR CARE CENTER	AUTOMOBILE REPAIRING
1990	AMERICAN CAR CARE CENTER	AUTOMOBILE REPAIRING
1991	ESSAR-N LAMAR INC	General Automotive Repair Shops
1999	YOUNGBLOOD AUTOMOTIVE AND TIRE	General Automotive Repair Shops
2000	YOUNGBLOOD AUTOMOTIVE AND TIRE	General Automotive Repair Shops
2001	YOUNGBLOOD AUTOMOTIVE AND TIRE	General Automotive Repair Shops
2002	YOUNGBLOOD AUTOMOTIVE AND TIRE	General Automotive Repair Shops

---

GO1763 WNW < 1/8 0.033 mi. 174 ft. | **DOCS SMALL ENGINE REPAIR**
104 KREBS LN
AUSTIN, TX 78704
Site 4 of 4 in cluster GO | **EDR Hist Auto** | **1013759932**
N/A

Actual: 637 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1984	DOCS SMALL ENGINE REPAIR	AUTOMOBILE REPAIRING

1764 WNW < 1/8 0.033 mi. 174 ft. | **ACC RIO GRANDE CAMPUS**
1218 WEST AVE.
AUSTIN, TX | **TX HIST UST** | **S128729132**
N/A

Actual: 509 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	ACC RIO GRANDE CAMPUS
Address:	1218 WEST AVE.
City,State,Zip:	AUSTIN, TX
Id UST:	C0714
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DC1765 WNW < 1/8 0.033 mi. 174 ft. | **BELL JIM GARAGE AUTO REPR PAINT & BODY SHOP**
811 5TH ST W
TRAVIS (County), TX 78703
Site 11 of 11 in cluster DC | **EDR Hist Auto** | **1013765427**
N/A

Actual: 463 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1970	BELL JIM GARAGE AUTO REPR PAINT	AUTOMOBILE REPAIRING
1980	GABES GARAGE	AUTOMOBILE REPAIRING

1766 East < 1/8 0.033 mi. 175 ft. | **AUSTIN MUSIC HALL**
208 NUECES ST
AUSTIN, TX | **TX HIST UST**
TX RDR | **S127541779**
N/A

Actual: 458 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	AUSTIN MUSIC HALL
Address:	208 NUECES ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0171
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	16044
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	AUSTIN MUSIC HALL
Address:	208 NUECES ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/25/2007
Due Date:	6/24/2007
Tank Owner:	DIMENSION PROPERTIES
Contact Person:	MICHAEL KAHN
Report:	TANK CLSR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/6/2012
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?;Delinquent Fee Ltr. sent 7/10/07
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/6/2012
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DF1767 **MAJIK IRONERS INC** **EDR Hist Cleaner** **1013784789**
WNW **114 W 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
175 ft. **Site 25 of 25 in cluster DF**

Actual:
508 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	MAJIK IRONERS INC	LAUNDRY SUPPLIES AND EQUIPMENT DEALERS

DP1768 **VACANT PROPERTY BRAZOS ST** **TX RDR** **S127540276**
SSW **501 BRAZOS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
175 ft. **Site 12 of 16 in cluster DP**

Actual:
487 ft.
RDR:

Focus Map:
11

RDR ID:	26458
Facility ID:	80009
RN:	Not reported
CN:	Not reported
Name:	VACANT PROPERTY BRAZOS ST
Address:	501 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/14/2018
Due Date:	2/12/2019
Tank Owner:	5TH & BRAZOS PROPERTY OWNER LLC
Contact Person:	DAVID CARLINS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/6/2019
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

DP1769 **BRADSHAW ED SERV** **EDR Hist Auto** **1013756380**
SSW **501 BRAZOS** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
175 ft. **Site 13 of 16 in cluster DP**

Actual:
487 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	BRADSHAW ED STA	GASOLINE STATIONS
1958	BRADSHAW ED SERV	GASOLINE STATIONS
1962	BRADSHAW ED SERV	GASOLINE STATIONS

DP1770 SSW < 1/8 0.033 mi. 175 ft. | **FORMER BANK DRIVE THRU/PARKING 501 BRAZOS AUSTIN, TX** | **TX RDR** | **S127540275 N/A**

Site 14 of 16 in cluster DP

Actual: 487 ft.

Focus Map: 11

RDR:

RDR ID:	18773
Facility ID:	80009
RN:	Not reported
CN:	Not reported
Name:	FORMER BANK DRIVE THRU/PARKING
Address:	501 BRAZOS
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/11/2010
Due Date:	5/10/2010
Tank Owner:	T STACY ASSOC
Contact Person:	PAUL WORKMAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/2/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/2/2010
Date Report Returned:	4/29/2010
Region:	Not reported
DKC RDR (misfiled):	Not reported

DP1771 SSW < 1/8 0.033 mi. 175 ft. | **5TH AND BRAZOS TOWER 501 BRAZOS ST AUSTIN, TX 78701** | **TX IHW CORR ACTION** | **S123345866 N/A**

Site 15 of 16 in cluster DP

Actual: 487 ft.

Focus Map: 11

IHW CORR ACTION:

Name:	5TH AND BRAZOS TOWER
Address:	501 BRAZOS ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	T3489
Location Desc:	Not reported
RN NUM:	RN106100159
Status:	INACTIVE
Status Date:	02/13/2019
EDR Link ID:	T3489
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	02/13/2019
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

DP1772 **VACANT PROPERTY** **TX UST** **U004144044**
SSW **501 BRAZOS ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.033 mi.
175 ft. **Site 16 of 16 in cluster DP**

Actual:
487 ft.

Focus Map:
11

UST:

Name:	VACANT PROPERTY
Address:	501 BRAZOS ST
City,State,Zip:	AUSTIN, TX 787013683
AI Number:	80009
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	685138232011075
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/12/2009
Signature Name/Title On Earliest Reg Form:	PAUL D WORKMAN,DIR OF DEV
Application Received Date On Earliest Reg Form:	08/14/2009
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Owner:

Owner CN:	CN603822693
Owner Last Name:	WALTON STACY DEVELOPMENT PARTNERS IV LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	679138222011075
Additional ID:	685138232011075

VACANT PROPERTY (Continued) **U004144044**

AI Number:	80009
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/14/2009
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	212613
Facility ID:	124160
Ai Number:	80009
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/11/2009
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

VACANT PROPERTY (Continued) **U004144044**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	184709
UST ID:	212613
AI Number:	80009
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

VACANT PROPERTY (Continued) **U004144044**

Construction Notification:

NOC ID:	33831
Facility ID:	124160
AI Number:	80009
Application Received Date:	11/13/2018
Scheduled Construction Date:	11/13/2018
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	11/13/2018
Signature Date On Form:	11/12/2018
Signature Name On Form:	ARCHIE WALTER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	WALTON STACY DEVELOPMENT PARTNERS IV LP
Owner CN At Time Of Construction:	CN603822693
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	REMOVAL OF ONE APPROXIMATELY 1000 GALLON GHOST UST

NOC ID:	22260
Facility ID:	124160
AI Number:	80009
Application Received Date:	07/31/2009
Scheduled Construction Date:	08/15/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90731006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	11/13/2018
Signature Date On Form:	11/12/2018
Signature Name On Form:	ARCHIE WALTER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	70146

VACANT PROPERTY (Continued) **U004144044**

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	80138
UST ID:	Not reported
NOC ID:	33831
AI Number:	80009
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON CONSULTANTS INC
Representative Name:	RUSS FORD
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS BLVD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	23135
UST ID:	Not reported
NOC ID:	22260
AI Number:	80009
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	80139
UST ID:	Not reported
NOC ID:	33831
AI Number:	80009
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported

VACANT PROPERTY (Continued) **U004144044**

Company Name:	GRUENE ENVIRONMENTAL CONSTRUCTION
Representative Name:	CURTIS GRAY
Mailing Address (Delivery):	11 NAFTA CIR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WALTON STACY DEVELOPMENT PARTNERS IV LP
Contact Mailing Address (Delivery):	823 CONGRESS AVE STE 1111
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2401
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	124160
Additional ID:	685138232011075
Princ ID:	679138222011075
AI Number:	80009
Facility Name:	VACANT PROPERTY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PAUL D WORKMAN/

HIST UST AUSTIN:

Name:	FORMER DRIVE THRU BANK
Address:	501 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Id UST:	3325
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KJ1773 **CITY HALL ANNEX BLOCK 4** **US BROWNFIELDS** **1016352622**
ESE **UNKNOWN** **FINDS** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.033 mi.
176 ft. **Site 1 of 4 in cluster KJ**

Actual:
472 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	CITY HALL ANNEX BLOCK 4
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.264952
Longitude:	-97.74721
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11972
IC Data Access:	Not reported
Start Date:	12/31/2001
Redev Completition Date:	Not reported
Completed Date:	12/31/2001
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

CITY HALL ANNEX BLOCK 4 (Continued) **1016352622**

Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	322
Below Poverty Percent:	12.92
Meidan Income:	11955
Meidan Income Number:	464
Meidan Income Percent:	18.61
Vacant Housing Number:	413
Vacant Housing Percent:	22.18
Unemployed Number:	145
Unemployed Percent:	5.82

FINDS:
Registry ID: 110041504814

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AIR EMISSIONS CLASSIFICATION UNKNOWN
AIR MINOR
Registry ID: 110071201651

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AIR EMISSIONS CLASSIFICATION UNKNOWN
Registry ID: 110039555371

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DQ1774 **AUSTIN BRAKE** **EDR Hist Auto** **1013756143**
SSW **506 TRINITY ST** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
176 ft. **Site 10 of 11 in cluster DQ**

Actual:
484 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1922	MC CLELLAN & DELZELL	AUTOMOBILE REPAIRERS
1958	AUSTIN BRAKE	AUTOMOBILE REPAIRING
1962	AUSTIN BRAKE & CLUTCH	AUTOMOBILE REPAIRING
1962	AUSTIN BRAKE & CLUTCH	BRAKE AND CLUTCH SERVICE
1965	AUSTIN BRAKE 6 CLUTCH	BRAKE AND CLUTCH SERVICE
1965	AUSTIN BRAKE 6 CLUTCH	AUTOMOBILE REPAIRING
1969	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1970	AUSTIN BRAKE & CLUTCL I SERVICE	AUTOMOBILE REPAIRING
1970	AUSTIN BRAKE & CLUTCL I SERVICE	BRAKE AND CLUTCH SERVICE
1970	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1971	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1972	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1973	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1974	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1975	AUSTIN BRAKE & CLUTCH SERVICE	AUTOMOBILE REPAIRING
1975	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1976	AUSTIN BRAKE & CLUTCH SERVICE	Automotive Repair Shops, NEC
1977	AUSTIN BRAKE & CLUTCH SUPPLY*	Automotive Repair Shops, NEC
1978	AUSTIN BRAKE & CLUTCH SUPPLY*	Automotive Repair Shops, NEC
1980	AUSTIN BRAKE & CLUTCH SUPPLY IN	AUTOMOBILE REPAIRING
1980	AUSTIN BRAKE & CLUTCH SUPPLY IN	BRAKE SERVICE

DQ1775 **DEAN MILLER** **TX HIST UST** **S111678623**
SSW **506 E TRINITY ST** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
176 ft. **Site 11 of 11 in cluster DQ**

Actual:
484 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DEAN MILLER
Address:	506 E TRINITY ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0094
HID UST:	94
Inspection:	Not reported
Due:	06/01/2012

JC1776 **DIXIE OIL COMPANY** **TX HIST UST** **S111678628**
NE **407 W CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.033 mi.
176 ft. **Site 2 of 2 in cluster JC**

Actual:
454 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DIXIE OIL COMPANY
Address:	407 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0036

DIXIE OIL COMPANY (Continued) **S111678628**

HID UST: 36
Inspection: 03/11/2010
Due: 03/11/2013

1777 ESE < 1/8 0.033 mi. 176 ft. | **WILKERSON TRUCK LINES** | **TX HIST UST** | **S111678858**
6613 N LAMAR BLVD | **N/A**
AUSTIN, TX

Actual: 713 ft.
Focus Map: 6

HIST UST AUSTIN:
Name: WILKERSON TRUCK LINES
Address: 6613 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: H0445
HID UST: 445
Inspection: Not reported
Due: 06/01/2012

KJ1778 ESE < 1/8 0.034 mi. 177 ft. | **COA - ANNEX** | **TX HIST UST** | **S128729070**
301 W 2ND ST | **N/A**
AUSTIN, TX

Site 2 of 4 in cluster KJ

Actual: 472 ft.
Focus Map: 11

HIST UST AUSTIN:
Name: COA - ANNEX
Address: 301 W 2ND ST
City,State,Zip: AUSTIN, TX
Id UST: C0546
HID UST: Not reported
Inspection: Not reported
Due: Not reported

KJ1779 ESE < 1/8 0.034 mi. 177 ft. | **CITY OF AUSTIN EME|S STATION # 10** | **TX HIST UST** | **S128729248**
301 WEST 2ND STREET | **TX ASBESTOS** | **N/A**
AUSTIN, TX 78701

Site 3 of 4 in cluster KJ

Actual: 472 ft.
Focus Map: 11

HIST UST AUSTIN:
Name: CALCASIEU LUMBER CO.
Address: 301 W 2ND ST
City,State,Zip: AUSTIN, TX
Id UST: H0350
HID UST: 350
Inspection: Not reported
Due: 06/01/2012

ASBESTOS:

CITY OF AUSTIN EME|S STATION # 10 (Continued) **S128729248**

Name:	CITY OF AUSTIN EME|S STATION # 10
Address:	301 WEST 2ND STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2022005142
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/02/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/02/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/16/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

CITY OF AUSTIN EME|S STATION # 10 (Continued) **S128729248**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN EME|S STATION # 10
Address:	301 WEST 2ND STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Scott Agnor for the Owner
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2022005142
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/02/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/02/2022
Certification Statement Phone:	817-681-3336
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

CITY OF AUSTIN EME|S STATION # 10 (Continued) **S128729248**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/16/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

1780
WSW
< 1/8
0.034 mi.
177 ft.

DUKES GAR REPRS **EDR Hist Auto** **1013766047**
406 RED RIVER **N/A**
AUSTIN, TX

Actual:
468 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1953	DUKES GAR REPRS	AUTOMOBILE REPAIRING

CN1781
WNW
< 1/8
0.034 mi.
177 ft.

TEXAS HOUSE OF REPRESENTATIVES **TX Ind. Haz Waste** **S103613602**
105 W 15TH ST **TX CENTRAL REGISTRY** **N/A**
AUSTIN, TX 78701

Site 4 of 4 in cluster CN

Actual:
555 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	TEXAS HOUSE OF REPRESENTATIVES
Address:	105 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	84308
Registration Initial Notification Date:	01/02/1996
Registration Last Amendment Date:	12/10/2007
EPA Identification:	Not reported
Primary NAICS Code:	511199
Status Change Date:	19960102
Land Type:	Not reported
Description of Facility Site Location:	105 W 15th St, Austin, TX

TEXAS HOUSE OF REPRESENTATIVES (Continued) **S103613602**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS HOUSE OF REPRESENTATIVES
Contact Name:	RONNIE WELCH
Contact Telephone Number:	512-4630885
Mailing Address:	PO BOX 2910
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787682910
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	103190
Site Owner Tax ID:	746000116
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20071228
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	TEXAS HOUSE OF REPRESENTATIVES
Owner Mailing Address:	PO BOX 2910
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Country:	UNITED STA
Owner Telephone:	1-512-4630885
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

TEXAS HOUSE OF REPRESENTATIVES (Continued) **S103613602**

Contact Role:	OWNCON
Contact Address:	PO BOX 2910
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4630885
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RONNIE WELCH
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2910
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4630885
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	143608
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste petroleum Naphtha / Printer Cleaning / 1/91.
Standard Industrial Code:	27410
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	511199
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100669704

TEXAS HOUSE OF REPRESENTATIVES (Continued) **S103613602**

Name:	TEXAS HOUSE OF REPRESENTATIVES
Address:	105 W 15TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1933
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600377618
Customer Name:	TEXAS HOUSE OF REPRESENTATIVES
Customer Legal Name:	Texas House of Representatives
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/31/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	511199
Primary NAICS Industry Type Description:	All Other Publishers
Physical Location Description:	105 W 15th St, Austin, TX

Regulated Entity Number:	RN100669704
Name:	TEXAS HOUSE OF REPRESENTATIVES
Address:	105 W 15TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1933
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600377618
Customer Name:	TEXAS HOUSE OF REPRESENTATIVES
Customer Legal Name:	Texas House of Representatives
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/31/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	511199
Primary NAICS Industry Type Description:	All Other Publishers
Physical Location Description:	105 W 15th St, Austin, TX

KK1782 **CIRCLE K STORES INC** **EDR Hist Auto** **1020597723**
ESE **4619 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.034 mi.
178 ft. **Site 1 of 2 in cluster KK**

Actual:
637 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1993	CIRCLE K CORPORATION	Convenience Stores
1994	CIRCLE K CORPORATION	Convenience Stores
1995	CIRCLE K STORES INC	Convenience Stores
1996	CIRCLE K STORES INC	Convenience Stores
1997	TOSCO MARKETING COMPANY	Convenience Stores
1998	TOSCO MARKETING COMPANY INC	Convenience Stores
1999	TOSCO MARKETING COMPANY	Convenience Stores
2000	TOSCO MARKETING COMPANY	Convenience Stores
2002	CIRCLE K STORES INC	Convenience Stores
2003	CIRCLE K STORES INC	Convenience Stores
2004	CIRCLE K STORES INC	Convenience Stores
2005	CIRCLE K STORES INC	Convenience Stores
2006	CIRCLE K STORES INC	Convenience Stores
2007	CIRCLE K STORES INC	Convenience Stores

CIRCLE K STORES INC (Continued) **1020597723**

2008	CIRCLE K STORES INC	Convenience Stores
2009	CIRCLE K STORES INC	Convenience Stores

KK1783 ALL STAR GROCERY 1 **TX LPST** **U001246992**
ESE 4619 S CONGRESS AVE **TX UST** **N/A**
< 1/8 AUSTIN, TX 78745 **TX HIST UST**
0.034 mi. **TX ASBESTOS**
178 ft. Site 2 of 2 in cluster KK **TX Financial Assurance**

Actual:
637 ft.

Focus Map:
17

LPST:

Name:	CIRCLE K 3216
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010998
LPST Id:	109419
Facility Location:	4619 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/06/1995
Entered Date:	05/16/1995
Reported Date:	04/06/1995
Closure Date:	07/24/1996
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	MJS
Responsible Party Name:	Not reported
Responsible Party Contact:	KEN YOUNGER
Responsible Party Address:	906 E ANDERSON LN
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/339-8836
Reported Date:	04/06/1995
Case Start Date:	07/24/1996
Reference Number:	RN101640480
Project Manager:	MERSMITH

UST:

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787452380
AI Number:	10998
Facility Type:	RETAIL
Facility Begin Date:	07/25/1986
Facility Status:	ACTIVE
Additional ID:	524005172002069
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

ALL STAR GROCERY 1 (Continued) **U001246992**

Site Location (Location Zip):	78745
Contact Name/Title:	SULTAN MOMIN,PRES
Contact Organization Name:	ALL STAR GROCERY 1
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5126934786
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/14/2021
Signature Name/Title On Earliest Reg Form:	SULTAN MOMIN,PRESIDENT
Application Received Date On Earliest Reg Form:	08/17/2021
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	533005162002069
Additional ID:	524005172002069
Ai Number:	10998
Operator CN:	CN600881841
Operator Name:	DNS INC
Operator Effective Begin Date:	06/01/2000
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	SULTAN MOMIN/PRES
Contact Organization Name:	DNS INC
Contact Mailing Address (Delivery):	4619 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78745-2380
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	6934786
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600881841
Owner Last Name:	DNS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	4619 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78745
Contact Mailing Zip5:	2380
Contact Phone Number/Ext:	1 512 6934786/0
Contact Fax Country Code:	Not reported

ALL STAR GROCERY 1 (Continued) **U001246992**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	533005162002069
Additional ID:	524005172002069
AI Number:	10998
Owner Effective Begin Date:	06/01/2000
State Tax ID:	17429535572
Contact Role:	OWNCON
Contact Name/Title:	SULTAN MOMIN/PRES
Contact Organization Name:	DNS INC

Self Certification:

Self Cert ID:	43998
Cert ID:	381504
AI Number:	10998
Self Certification Date:	01/12/2023
Signature Name/Title:	MURAD SAMNANI REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	358022
AI Number:	10998
Self Certification Date:	08/14/2021
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	340167
AI Number:	10998
Self Certification Date:	07/08/2020
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	323212
AI Number:	10998
Self Certification Date:	07/18/2019
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	306435
AI Number:	10998
Self Certification Date:	07/09/2018
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	289300
AI Number:	10998
Self Certification Date:	06/06/2017
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	273106
AI Number:	10998
Self Certification Date:	07/25/2016
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	255881
AI Number:	10998
Self Certification Date:	07/30/2015
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	240339
AI Number:	10998
Self Certification Date:	07/24/2014
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	222424
AI Number:	10998
Self Certification Date:	06/25/2013
Signature Name/Title:	S V MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	43998
Cert ID:	19020
AI Number:	10998
Self Certification Date:	07/04/2012
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19019
AI Number:	10998
Self Certification Date:	06/29/2011
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19018
AI Number:	10998
Self Certification Date:	06/20/2010
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19017
AI Number:	10998
Self Certification Date:	06/23/2009
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19016
AI Number:	10998
Self Certification Date:	06/23/2008
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19015
AI Number:	10998
Self Certification Date:	08/20/2007
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19014
AI Number:	10998
Self Certification Date:	11/13/2006
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19013
AI Number:	10998
Self Certification Date:	07/26/2005
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19012
AI Number:	10998
Self Certification Date:	07/14/2004
Signature Name/Title:	SULTAN MOMIN
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19011
AI Number:	10998
Self Certification Date:	07/01/2003
Signature Name/Title:	SULTON MOMIN OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19010
AI Number:	10998
Self Certification Date:	11/12/2002
Signature Name/Title:	SULTAN MOMIN PRESIDENT
Signature Type Role:	OWNER

ALL STAR GROCERY 1 (Continued) **U001246992**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	43998
Cert ID:	19009
AI Number:	10998
Self Certification Date:	08/23/2000
Signature Name/Title:	SULTAN MOMIN PRES
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28923
Facility ID:	43998
Ai Number:	10998
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/15/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	8000
UST Comprt ID:	17407
UST ID:	28923
AI Number:	10998
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28924
Facility ID:	43998
Ai Number:	10998
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/15/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	8000
UST Comprt ID:	17408
UST ID:	28924
AI Number:	10998
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1995
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9684
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	175407
Facility ID:	43998
Ai Number:	10998
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	9684
UST Comprt ID:	17411
UST ID:	175407
AI Number:	10998
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

ALL STAR GROCERY 1 (Continued) **U001246992**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/2000

Install Date:	08/01/1995
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9684
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	175352
Facility ID:	43998
Ai Number:	10998
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

ALL STAR GROCERY 1 (Continued) **U001246992**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	9684
UST Comprt ID:	17410
UST ID:	175352
AI Number:	10998
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/2000

ALL STAR GROCERY 1 (Continued) **U001246992**

Install Date:	08/01/1995
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9684
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	175351
Facility ID:	43998
Ai Number:	10998
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

ALL STAR GROCERY 1 (Continued) **U001246992**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	9684
UST Comprt ID:	17409
UST ID:	175351
AI Number:	10998
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/01/2000

Construction Notification:

NOC ID:	1594
Facility ID:	43998
AI Number:	10998
Application Received Date:	08/09/2012
Scheduled Construction Date:	08/20/2012
UST Improvement:	Y

ALL STAR GROCERY 1 (Continued) **U001246992**

UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	56118
General Desc Of Prop Construct:	REPLACE EXISTING MANHOLES. REQUEST 30 DAY WAIVER.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	1838
UST ID:	Not reported
NOC ID:	1594
AI Number:	10998
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113A REGAL ROW
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	1839
UST ID:	Not reported
NOC ID:	1594
AI Number:	10998
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported

ALL STAR GROCERY 1 (Continued) **U001246992**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DNS INC
Contact Mailing Address (Delivery):	4619 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 2380
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	43998
Additional ID:	524005172002069
Princ ID:	533005162002069
AI Number:	10998
Facility Name:	ALL STAR GROCERY 1
AR Number:	56118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	SULTAN MOMIN/

HIST UST AUSTIN:

Name:	ALL STAR GROCERY
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	642
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	ALL STAR GROCERY
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/12/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported

ALL STAR GROCERY 1 (Continued) **U001246992**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/19/2013
Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

ALL STAR GROCERY 1 (Continued) **U001246992**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ALL STAR GROCERY
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	03/12/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	2.5
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/17/2014
Date Routed by Supervisor:	03/18/2014
Date Routed to PSQA:	03/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

ALL STAR GROCERY 1 (Continued) **U001246992**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	278628
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2022
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 7224994
Policy Number:	04-TOP-000027370
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	254735
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2021
Date Financial Assurance Form Rec:	08/17/2021

ALL STAR GROCERY 1 (Continued) **U001246992**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000017863
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	234824
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2020
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005002377
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	216830
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2019
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	Not reported
Policy Number:	STP-126261
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1

ALL STAR GROCERY 1 (Continued) **U001246992**

Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	199755
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2018
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP121559
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	182488
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2017
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-116707
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	165560
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000

ALL STAR GROCERY 1 (Continued) **U001246992**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2016
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641204-05
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	146864
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2015
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	800 577 6614
Policy Number:	PP3641204-04
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	131700
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2014
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP3641204-03

ALL STAR GROCERY 1 (Continued) **U001246992**

Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	111326
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2013
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	800 577 6614
Policy Number:	PP3641204-01
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/24/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	1067
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2012
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP364120401
Coverage Amount:	1000000
Coverage Expiration Date:	03/24/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2

ALL STAR GROCERY 1 (Continued) **U001246992**

Facility ID:	43998
Finass ID:	24385
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2011
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP36412-04
Coverage Amount:	1000000
Coverage Expiration Date:	03/24/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	24386
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2010
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688847-04
Coverage Amount:	1000000
Coverage Expiration Date:	03/24/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	24387
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

ALL STAR GROCERY 1 (Continued) **U001246992**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/24/2008
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688847-02
Coverage Amount:	1000000
Coverage Expiration Date:	03/24/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ALL STAR GROCERY 1
Address:	4619 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	43998
Finass ID:	24388
AI:	10998
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	08/17/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

KL1784 **SOUTHWESTERN BELL TELEPHONE** **TX HIST UST** **S111678810**
WNW **120 W 9TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.034 mi.
178 ft. **Site 1 of 5 in cluster KL**

Actual:
526 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SOUTHWESTERN BELL TELEPHONE
Address:	120 W 9TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0872
HID UST:	872
Inspection:	06/29/2010
Due:	06/29/2013

KL1785 WNW < 1/8 0.034 mi. 178 ft. — **SOUTHWESTERN BELL TELEPHONE COMPANY**, **120 W 9TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678809** / **N/A**

Site 2 of 5 in cluster KL

Actual: 526 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Address:	120 W 9TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0352
HID UST:	352
Inspection:	06/29/2010
Due:	06/29/2013

DY1786 NNE < 1/8 0.034 mi. 179 ft. — **PARSLEY W L DCLO CLNR**, **310 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013779267** / **N/A**

Site 11 of 11 in cluster DY

Actual: 479 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1911	PARSLEY WM L HATTER	CLOTHES PRESSERS AND CLEANERS
1911	PARSLEY WM L HATTER	DYERS AND SCOURERS
1916	PARSLEY WM L CLNR	CLOTHES CLEANERS AND PRESSERS
1922	PARSLEY W L DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

KM1787 SE < 1/8 0.034 mi. 179 ft. — **NORTH LAMAR QUICK STOP**, **8545 N LAMAR BLVD**, **AUSTIN, TX 78753** — **TX LPST**, **TX UST**, **TX HIST UST**, **TX Financial Assurance**, **TX GCC**, **TX RDR** — **U003566330** / **N/A**

Site 1 of 2 in cluster KM

Actual: 694 ft.
Focus Map: 6

LPST:

Name:	LAMAR FOOD MART
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120073
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	06/14/2016
Entered Date:	11/18/2016
Reported Date:	06/20/2016
Closure Date:	01/11/2017
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	06/20/2016
Case Start Date:	01/11/2017
Reference Number:	RN101499358
Project Manager:	JHALFHIL

UST:

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787535542
AI Number:	45196
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	55494242002054
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	SHAHID IQBAL,
Contact Organization Name:	NORTH LAMAR QUICK STOP
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5126629593
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	SHELL2204@YAHOO.COM
Signature Date On Earliest Reg Form:	01/23/2023
Signature Name/Title On Earliest Reg Form:	SHAHID MAJEED,OWNER
Application Received Date On Earliest Reg Form:	01/26/2023
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	846326312017201
Additional ID:	55494242002054
Ai Number:	45196
Operator CN:	CN605394410
Operator Name:	HIGHWAY FOOD MART INC
Operator Effective Begin Date:	05/01/2021
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	SHAHID IQBAL/
Contact Organization Name:	HIGHWAY FOOD MART INC
Contact Mailing Address (Delivery):	4535 HIGHWAY 71 E
Contact Mailing Address (Internal Delivery):	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Contact Mailing City/State/Zip:	DEL VALLE TX 78617-3212
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	2476165
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	SHELL2204@YAHOO.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605394410
Owner Last Name:	HIGHWAY FOOD MART INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1317 HIGHWAY 71 E
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	BASTROP
Contact Mailing State:	TX
Contact Mailing Zip:	78602
Contact Mailing Zip5:	5044
Contact Phone Number/Ext:	0 512 6629593/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MAJEED2244@HOTMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	846326312017201
Additional ID:	55494242002054
AI Number:	45196
Owner Effective Begin Date:	05/01/2021
State Tax ID:	32058943245
Contact Role:	OWNOPRCON
Contact Name/Title:	SHAHID IQBAL/
Contact Organization Name:	HIGHWAY FOOD MART INC

Self Certification:

Self Cert ID:	74582
Cert ID:	384006
AI Number:	45196
Self Certification Date:	01/23/2023
Signature Name/Title:	SHAHID MAJEED OWNER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	367600
AI Number:	45196
Self Certification Date:	02/09/2022
Signature Name/Title:	SHAHID MEJEED MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	355731
AI Number:	45196
Self Certification Date:	06/02/2021
Signature Name/Title:	SHAHID IQBAL MGR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	344202
AI Number:	45196
Self Certification Date:	09/16/2020
Signature Name/Title:	ALI KARIM REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	327394
AI Number:	45196
Self Certification Date:	09/19/2019
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	310676
AI Number:	45196
Self Certification Date:	09/25/2018
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	293008
AI Number:	45196
Self Certification Date:	09/06/2017
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	276452
AI Number:	45196
Self Certification Date:	09/15/2016
Signature Name/Title:	SOMI MAREDIA REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	260614
AI Number:	45196
Self Certification Date:	10/08/2015
Signature Name/Title:	SALIM MOMIN MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74582
Cert ID:	243395
AI Number:	45196
Self Certification Date:	09/26/2014
Signature Name/Title:	SALIM MOMIN MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74582
Cert ID:	227274
AI Number:	45196
Self Certification Date:	10/03/2013
Signature Name/Title:	SALIM MOMIN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74582
Cert ID:	104787
AI Number:	45196
Self Certification Date:	04/10/2013
Signature Name/Title:	SALIM MOMIN OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104786
AI Number:	45196
Self Certification Date:	09/08/2011
Signature Name/Title:	SALIM MOMIN MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104785
AI Number:	45196
Self Certification Date:	09/16/2010
Signature Name/Title:	SALIM MOMIN MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104784
AI Number:	45196
Self Certification Date:	04/26/2010
Signature Name/Title:	SALIM MOMIN MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104783
AI Number:	45196
Self Certification Date:	06/22/2007
Signature Name/Title:	AMIR ALI MAKANOJIA MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104782
AI Number:	45196
Self Certification Date:	09/16/2006
Signature Name/Title:	MOHAMMAD OPERATOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104781
AI Number:	45196
Self Certification Date:	09/11/2005
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74582
Cert ID:	104780
AI Number:	45196
Self Certification Date:	08/31/2004
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74582
Cert ID:	104779
AI Number:	45196
Self Certification Date:	09/01/2003
Signature Name/Title:	KHUSHI MOHAMMAD MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74582
Cert ID:	104778
AI Number:	45196
Self Certification Date:	08/14/2002
Signature Name/Title:	KHUSHI MOHAMMAD MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74582
Cert ID:	104777
AI Number:	45196
Self Certification Date:	04/19/2001
Signature Name/Title:	KHUSHI MOHAMMAD MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1973
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118330
Facility ID:	74582
Ai Number:	45196
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	104315
UST ID:	118330
AI Number:	45196
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	05/26/2002

Install Date:	01/01/1973
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Tank Doublewall:	N
Pipe Type:	P
UST ID:	118331
Facility ID:	74582
Ai Number:	45196
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	104316
UST ID:	118331
AI Number:	45196
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	05/26/2002

Install Date:	01/01/1973
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118332
Facility ID:	74582
Ai Number:	45196
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1973

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/24/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	104317
UST ID:	118332
AI Number:	45196
Compartment ID:	A
Substance Stored1:	GASOLINE

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	05/26/2002

Construction Notification:

NOC ID:	11029
Facility ID:	74582
AI Number:	45196
Application Received Date:	11/07/2001
Scheduled Construction Date:	11/19/2001
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M01107006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	54149
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	11846
UST ID:	Not reported
NOC ID:	11029
AI Number:	45196
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HIGHWAY FOOD MART INC
Contact Mailing Address (Delivery):	8545 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 5542
Phone Number/Ext:	512 6629593/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74582
Additional ID:	55494242002054
Princ ID:	846326312017201
AI Number:	45196
Facility Name:	NORTH LAMAR QUICK STOP
AR Number:	82782
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	SHAHD IQBAL/

HIST UST AUSTIN:

Name:	LAMAR FOOD MART

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1153
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	281141
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/26/2022
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04TOP000028277
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/26/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	252470
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/26/2021
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000021696
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/26/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	265205
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/26/2021
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000021696
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/26/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	238976
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2020
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000012219
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	221869
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2019
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000001345
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	204082
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2018
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000105441
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	186190
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2017
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Policy Number:	04TO000100721
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	168784
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2016
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-96338
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	152145
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2015
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00092154
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Region:	2
Facility ID:	74582
Finass ID:	134643
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2014
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00088051
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	7932
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2013
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 5776614
Policy Number:	04-TO-00083996
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	116987
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2013
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 2523439
Policy Number:	04TO00080105
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/28/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	57920
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2012
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 5776614
Policy Number:	04-TO-00080105
Coverage Amount:	1000000
Coverage Expiration Date:	03/28/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	57921
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2011
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 5776614
Policy Number:	04-TO-00077410
Coverage Amount:	1000000
Coverage Expiration Date:	03/28/2012

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	57922
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2010
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688948-03
Coverage Amount:	1000000
Coverage Expiration Date:	03/28/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	NORTH LAMAR QUICK STOP
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	74582
Finass ID:	57923
AI:	45196
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	01/26/2023
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	LAMAR FOOD MART
Address:	8545 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

File Number: 120073
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 6/20/2016
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: LAMAR FOOD MART
Address: 8545 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: *
File Number: 120073
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 6/20/2016
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

RDR:
RDR ID: 24022
Facility ID: 45196
RN: Not reported
CN: Not reported
Name: LAMAR FOOD MART
Address: 8545 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Date Report Received: 9/20/2016
Due Date: 11/19/2016
Tank Owner: BLUFF SPRINGS FOOD MART INC
Contact Person: TARIQ MAJEED
Report: RDR
Latest TCEQ Letter: New LPST
Date of Latest TCEQ Letter: 11/21/2016
Project Manager: Jake Halfhill
Team: #N/A
New LPST Number: 120073
Pre-Existing LPST Number: Not reported
Comments: Not reported
Review Coordinator: Not reported
Date Release Reported: Not reported

NORTH LAMAR QUICK STOP (Continued) **U003566330**

Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KM1788
SE
< 1/8
0.034 mi.
179 ft.

SIGMOR SHAMROCK SERVICE STATION NO
8545 LAMAR BLVD N
AUSTIN, TX 78763

EDR Hist Auto **1013758414**
N/A

Site 2 of 2 in cluster KM

Actual:
694 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1970	SIGMOR SERVICE INC NO 181 GAS S	GASOLINE STATIONS
1980	SIGMOR SHAM DROCK SERVICE INC N	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1987	DIAMOND SHAMROCK CORP	Petroleum Products, NEC
1990	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS

1789
WNW
< 1/8
0.034 mi.
179 ft.

TEXAS PEST CONTROL
3510 CONGRESS AVE
SOUTH AUSTIN, TX

EDR Hist Cleaner **1013786380**
N/A

Actual:
619 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1962	TEXAS PEST CONTROL	CLEANERS AND DYERS

1790
WNW
< 1/8
0.034 mi.
180 ft.

ROBERT HATCHETT
1004 W WEST 24TH ST
AUSTIN, TX

TX HIST UST **S111678794**
N/A

Actual:
505 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ROBERT HATCHETT
Address:	1004 W WEST 24TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0488
HID UST:	488
Inspection:	Not reported
Due:	06/01/2012

DJ1791 NNE < 1/8 0.034 mi. 180 ft. | **704 6 BUSTIN MC CUTCHEON MOTORS INC**
704 BRAZOS ST
AUSTIN, TX
Site 7 of 7 in cluster DJ | **EDR Hist Auto** | **1013771069**
N/A

Actual: 507 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	704 6 BUSTIN MC CUTCHEON MOTORS	AUTOMOBILE SERVICE
1929	704 6 BUSTIN MC CUTCHEON MOTORS	AUTOMOBILE REPAIRERS

1792 NNE < 1/8 0.034 mi. 180 ft. | **GPM STORE 4567**
2001 BASTROP HWY E
DEL VALLE, TX 78617 | **TX LPST**
TX UST
TX Financial Assurance
TX GCC | **U001276841**
N/A

Actual: 487 ft.

Focus Map: 20

LPST:

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX
Facility ID:	Not reported
LPST Id:	121207
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	05/10/2020
Entered Date:	06/24/2021
Reported Date:	04/30/2021
Closure Date:	12/31/3000
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	2 - SITE ASSESSMENT
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	04/30/2021
Case Start Date:	12/31/3000
Reference Number:	RN102361730
Project Manager:	THAMMITT

UST:

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 786172138
AI Number:	45206
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	278615832002149
Facility Exempt Status:	N
Records Off-Site:	Yes

GPM STORE 4567 (Continued) **U001276841**

UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78617
Contact Name/Title:	ROLFE LANN,
Contact Organization Name:	GPM STORE 4567
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8047301568
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/01/2021
Signature Name/Title On Earliest Reg Form:	ROLFE LANN,VP
Application Received Date On Earliest Reg Form:	04/01/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	366570652018142
Additional ID:	278615832002149
Ai Number:	45206
Operator CN:	CN605529908
Operator Name:	GPM SOUTHEAST LLC
Operator Effective Begin Date:	10/06/2020
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	ROLFE LANN/
Contact Organization Name:	GPM SOUTHEAST LLC
Contact Mailing Address (Delivery):	8565 MAGELLAN PKWY STE 400
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	RICHMOND VA 23227-1172
Contact Phone Country Code:	0
Contact Phone Area Code:	804
Contact Phone Number:	7301568
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RLANN@GPMINVESTMENTS.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605529908
Owner Last Name:	GPM SOUTHEAST LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	8565 MAGELLAN PKWY STE 400
Contact Mailing Address (Internal Delivery):	Not reported

GPM STORE 4567 (Continued) **U001276841**

Contact Mailing City:	RICHMOND
Contact Mailing State:	VA
Contact Mailing Zip:	23227
Contact Mailing Zip5:	1172
Contact Phone Number/Ext:	0 804 7301568/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	RLANN@GPMINVESTMENTS.COM
Contact Address Deliverable:	Not reported
Princ ID:	366570652018142
Additional ID:	278615832002149
AI Number:	45206
Owner Effective Begin Date:	10/06/2020
State Tax ID:	32065325667
Contact Role:	OWNOPRCON
Contact Name/Title:	ROLFE LANN/
Contact Organization Name:	GPM SOUTHEAST LLC

Self Certification:

Self Cert ID:	74592
Cert ID:	367269
AI Number:	45206
Self Certification Date:	02/17/2022
Signature Name/Title:	KIRSTEN WILSON REGIONAL ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	352394
AI Number:	45206
Self Certification Date:	04/01/2021
Signature Name/Title:	ROLFE LANN VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	346687
AI Number:	45206
Self Certification Date:	10/16/2020
Signature Name/Title:	ROLFE LANN VP OF ENV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	334660
AI Number:	45206
Self Certification Date:	03/13/2020
Signature Name/Title:	DENNIE MATHES CORP ENV COMPL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	317125
AI Number:	45206
Self Certification Date:	02/21/2019
Signature Name/Title:	DENNIE MATHES CORP ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	301085
AI Number:	45206
Self Certification Date:	03/15/2018
Signature Name/Title:	DENNIE MATHES DIR OF ENV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	294637
AI Number:	45206
Self Certification Date:	10/02/2017
Signature Name/Title:	DENNIE MATHES DIRECTOR OF ENVIRONMENTAL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	292370
AI Number:	45206
Self Certification Date:	08/24/2017
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	274937
AI Number:	45206
Self Certification Date:	08/22/2016
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	258399
AI Number:	45206
Self Certification Date:	08/26/2015
Signature Name/Title:	JENNIFER RESNIK COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	242775
AI Number:	45206
Self Certification Date:	08/29/2014
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	226093
AI Number:	45206
Self Certification Date:	08/24/2013
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74592
Cert ID:	105087
AI Number:	45206
Self Certification Date:	08/24/2012
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105086
AI Number:	45206
Self Certification Date:	08/24/2011
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	105085
AI Number:	45206
Self Certification Date:	09/14/2010
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105084
AI Number:	45206
Self Certification Date:	07/28/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105083
AI Number:	45206
Self Certification Date:	07/27/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	105082
AI Number:	45206
Self Certification Date:	08/29/2008
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105081
AI Number:	45206
Self Certification Date:	03/11/2008
Signature Name/Title:	TERRY HANKINS O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105080
AI Number:	45206
Self Certification Date:	08/28/2007
Signature Name/Title:	KENT HAMEL COMPLIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	105079
AI Number:	45206
Self Certification Date:	08/01/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105078
AI Number:	45206
Self Certification Date:	07/26/2005
Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105077
AI Number:	45206
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Self Cert ID:	74592
Cert ID:	105076
AI Number:	45206
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105075
AI Number:	45206
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74592
Cert ID:	105074
AI Number:	45206
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Tank:

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118364
Facility ID:	74592
Ai Number:	45206
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

GPM STORE 4567 (Continued) **U001276841**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9994
UST Comprt ID:	104351
UST ID:	118364
AI Number:	45206
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	9994
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P

GPM STORE 4567 (Continued) **U001276841**

UST ID:	118365
Facility ID:	74592
Ai Number:	45206
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	3

GPM STORE 4567 (Continued) **U001276841**

Tank Capacity:	9994
UST Comprt ID:	104352
UST ID:	118365
AI Number:	45206
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	4006
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118366
Facility ID:	74592
Ai Number:	45206
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

GPM STORE 4567 (Continued) **U001276841**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	4006
UST Comprt ID:	104353
UST ID:	118366
AI Number:	45206
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

GPM STORE 4567 (Continued) **U001276841**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	35507
Facility ID:	74592
AI Number:	45206
Application Received Date:	10/18/2019
Scheduled Construction Date:	10/23/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	10/18/2019
Signature Date On Form:	10/18/2019
Signature Name On Form:	RACHAEL PETTIT
Signature Company On Form:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	QUIK-WAY RETAIL ASSOCIATES II LTD
Owner CN At Time Of Construction:	CN603378738
Owner AR At Time Of Construction:	68233
General Desc Of Prop Construct:	CP REPAIR

NOC ID:	33196
Facility ID:	74592
AI Number:	45206
Application Received Date:	06/27/2018
Scheduled Construction Date:	05/21/2018
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	10/18/2019
Signature Date On Form:	10/18/2019
Signature Name On Form:	RACHAEL PETTIT
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	QUIK-WAY RETAIL ASSOCIATES II LTD
Owner CN At Time Of Construction:	CN603378738
Owner AR At Time Of Construction:	68233
General Desc Of Prop Construct:	MANWAY CONSTRUCTION-INSTALLATION OF 3 RISERS AT EACH TANK, PROBE WIRING AND PROGRAMMING TO EXISTING ATG

NOC ID:	32198
Facility ID:	74592
AI Number:	45206
Application Received Date:	11/16/2017
Scheduled Construction Date:	11/08/2017
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	10/18/2019
Signature Date On Form:	10/18/2019

GPM STORE 4567 (Continued) **U001276841**

Signature Name On Form:	RACHAEL PETTIT
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	QUIK-WAY RETAIL ASSOCIATES II LTD
Owner CN At Time Of Construction:	CN603378738
Owner AR At Time Of Construction:	68233
General Desc Of Prop Construct:	BREAK CONCRETE ON AREA OF UST TO INSTALL NEW RISERS AND PROBES FOR TANKS. REQUEST 30 DAY WAIVER.

NOC ID:	11161
Facility ID:	74592
AI Number:	45206
Application Received Date:	11/04/2008
Scheduled Construction Date:	12/08/2008
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M81104001
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	10/18/2019
Signature Date On Form:	10/18/2019
Signature Name On Form:	RACHAEL PETTIT
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	78643
UST ID:	Not reported
NOC ID:	33196
AI Number:	45206
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	ERLING SALES & SERVICE
Representative Name:	ERIKA CUELLAR
Mailing Address (Delivery):	2330 PATTERSON INDUSTRIAL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	PFLUGERVILLE
Mailing State:	TX
Mailing Zip:	78660
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	737

GPM STORE 4567 (Continued) **U001276841**

Phone Number:	2269550
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	76072
UST ID:	Not reported
NOC ID:	32198
AI Number:	45206
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TEXAS STAGE II TESTING LLC
Representative Name:	GONZALO ESTRADA
Mailing Address (Delivery):	2210 PECH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77055
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	713
Phone Number:	4635412
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	713
Fax Number:	7220921
Email Address:	Not reported
Cont/Cons/Installer ID:	84107
UST ID:	Not reported
NOC ID:	35507
AI Number:	45206
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000152
Company Name:	FDR & CP SERVICES LLC
Representative Name:	JUNIOR WATSON
Mailing Address (Delivery):	PO BOX 3930
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BRYAN
Mailing State:	TX
Mailing Zip:	77805
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	979
Phone Number:	7780333
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	979
Fax Number:	7784444
Email Address:	Not reported
Cont/Cons/Installer ID:	78644
UST ID:	Not reported

GPM STORE 4567 (Continued) **U001276841**

NOC ID:	33196
AI Number:	45206
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	ERLING SALES & SERVICE
Representative Name:	DAVID KMIEC
Mailing Address (Delivery):	2330 PATTERSON INDUSTRIAL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	PFLUGERVILLE
Mailing State:	TX
Mailing Zip:	78660
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	832
Phone Number:	6065098
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	76073
UST ID:	Not reported
NOC ID:	32198
AI Number:	45206
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TEXAS STAGE II TESTING LLC
Representative Name:	GONZALO ESTRADA
Mailing Address (Delivery):	2210 PECH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77055
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	713
Phone Number:	4635412
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	713
Fax Number:	7220921
Email Address:	Not reported

Cont/Cons/Installer ID:	11996
UST ID:	Not reported
NOC ID:	11161
AI Number:	45206
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	GPM SOUTHEAST LLC
Contact Mailing Address (Delivery):	8565 MAGELLAN PKWY STE 400
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	RICHMOND, VA 23227 1172
Phone Number/Ext:	804 7301568/0
Contact Fax Number/Ext:	/
Contact Email Address:	RLANN@GPMINVESTMENTS.COM
Contact Address Deliverable:	Y
Facility ID:	74592
Additional ID:	278615832002149
Princ ID:	366570652018142
AI Number:	45206
Facility Name:	GPM STORE 4567
AR Number:	79773
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ROLFE LANN/

TX Financial Assurance 2:

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	264878
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2021
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4766411
Policy Number:	003017801
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2022
Ins Premium Pre-Paid For Entire Yr:	Yes

GPM STORE 4567 (Continued) **U001276841**

Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	245280
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2020
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003017800
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	248435
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2020
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003017801
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	240751
AI:	45206

GPM STORE 4567 (Continued) **U001276841**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2019
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003017801
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	241479
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2019
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003017801
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	229460
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2019
Date Financial Assurance Form Rec:	04/01/2021

GPM STORE 4567 (Continued) **U001276841**

Issuer Name:	OTHER
Issuer Phone:	Not reported
Policy Number:	PPK1975832
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	210732
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	OTHER
Issuer Phone:	Not reported
Policy Number:	PPK1815367
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	187728
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2017
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	CST2002546 16
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567

GPM STORE 4567 (Continued) **U001276841**

Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	194360
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2017
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	NAUTILUS INS CO
Issuer Phone:	Not reported
Policy Number:	CST2002546-16
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	185466
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2017
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	167281
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

GPM STORE 4567 (Continued) **U001276841**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/15/2016
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	149021
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2015
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/09/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	133889
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/2014
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported

GPM STORE 4567 (Continued) **U001276841**

Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	115850
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2013
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 6922275
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	7937
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2012
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3454670
Policy Number:	None
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2

GPM STORE 4567 (Continued) **U001276841**

Facility ID:	74592
Finass ID:	57950
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/25/2008
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	57951
AI:	45206
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2007
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	09/12/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Region:	2
Facility ID:	74592
Finass ID:	57952
AI:	45206
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y

GPM STORE 4567 (Continued) **U001276841**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	04/01/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	GPM STORE 4567
Address:	2001 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX
Division:	REM/PST
New Cases:	*
File Number:	121207
Contamination Description:	UNKNOWN
Date Of Earliest Known Contamination Confirmation:	4/30/2021
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	2A - Investigation
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	Not reported
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

IL1793 **EWINGS CONOCO SERVICE STATION** **EDR Hist Auto** **1013769371**
NE **519 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.034 mi.
181 ft. **Site 10 of 21 in cluster IL**

Actual:
484 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	EWINGS CONOCO SERVICE STATION	GASOLINE STATIONS

IL1794 **MERCHANTS TRANSFER STATION CO** **TX HIST UST** **S128729216**
NE **519 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.034 mi.
181 ft. **Site 11 of 21 in cluster IL**

Actual:
484 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	MERCHANTS TRANSFER STATION CO
Address:	519 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0216
HID UST:	216
Inspection:	Not reported
Due:	06/01/2012

IL1795 **TWIN LIQUORS** **TX UST** **U001440839**
NE **519 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.034 mi.
181 ft. **Site 12 of 21 in cluster IL**

Actual:
484 ft.

Focus Map:
11

UST:

Name:	TWIN LIQUORS
Address:	519 E 7TH ST
City,State,Zip:	AUSTIN, TX 787013318
AI Number:	64661
Facility Type:	RETAIL
Facility Begin Date:	06/03/1993
Facility Status:	INACTIVE
Additional ID:	346615062002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	TWIN LIQUORS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124769974
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/29/1993
Signature Name/Title On Earliest Reg Form:	DAVID JABOUR,PARTNER
Application Received Date On Earliest Reg Form:	06/03/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600781082
Owner Last Name:	TWIN LIQUORS GP LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	337615052002053
Additional ID:	346615062002053

TWIN LIQUORS (Continued) **U001440839**

AI Number:	64661
Owner Effective Begin Date:	06/03/1993
State Tax ID:	32016445937
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	06/01/1972
Tank Registration Date:	06/03/1993
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148461
Facility ID:	95995
Ai Number:	64661
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

TWIN LIQUORS (Continued) **U001440839**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/12/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	153752
UST ID:	148461
AI Number:	64661
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TWIN LIQUORS (Continued) **U001440839**

Install Date:	06/01/1972
Tank Registration Date:	06/03/1993
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148460
Facility ID:	95995
Ai Number:	64661
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

TWIN LIQUORS (Continued) **U001440839**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/12/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	153751
UST ID:	148460
AI Number:	64661
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1972
Tank Registration Date:	06/03/1993
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148462

TWIN LIQUORS (Continued) **U001440839**

Facility ID:	95995
Ai Number:	64661
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/12/1993

Compartment Records:

Tank ID:	4
Tank Capacity:	2000

TWIN LIQUORS (Continued) **U001440839**

UST Comprt ID:	153753
UST ID:	148462
AI Number:	64661
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1972
Tank Registration Date:	06/03/1993
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	148463
Facility ID:	95995
Ai Number:	64661
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

TWIN LIQUORS (Continued) **U001440839**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	05/12/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	153754
UST ID:	148463
AI Number:	64661
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

TWIN LIQUORS (Continued) **U001440839**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TWIN LIQUORS
Contact Mailing Address (Delivery):	107 W STASSNEY LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 3143
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95995
Additional ID:	346615062002053
Princ ID:	337615052002053
AI Number:	64661
Facility Name:	TWIN LIQUORS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GABRIEL DIAB/

IL1796 **TWIN LIQUORS** **TX RDR** **S126523779**
NE **519 E 7TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.034 mi.
181 ft. **Site 13 of 21 in cluster IL**

Actual:
484 ft.

Focus Map:
11

RDR:

RDR ID:	15009
Facility ID:	64661
RN:	Not reported
CN:	Not reported
Name:	TWIN LIQUORS
Address:	519 E 7TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/4/2006
Due Date:	3/5/2006
Tank Owner:	GABREIL DIAB
Contact Person:	DAVID JABOUR
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/31/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	REC PH II; DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/31/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101492635
Name:	TWIN LIQUORS
Address:	519 E 7TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3318
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600781082
Customer Name:	TWIN LIQUORS GP LLC
Customer Legal Name:	Twin Liquors GP LLC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	6/3/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

IL1797 **F. W. STERNENBERG** **TX HIST UST** **S128729464**
NE **519 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.034 mi.
181 ft. **Site 14 of 21 in cluster IL**

Actual:
484 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	F. W. STERNENBERG
Address:	519 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0895
HID UST:	895
Inspection:	Not reported
Due:	06/01/2012

IL1798 **TWIN LIQUORS** **TX HIST UST** **S128728990**
NE **519 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.034 mi.
181 ft. **Site 15 of 21 in cluster IL**

Actual:
484 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TWIN LIQUORS
Address:	519 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0300
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

DU1799 **JOHNSON J W SERVICE STATION GAS** **EDR Hist Auto** **1013775867**
SW **510 5TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.034 mi.
181 ft. **Site 15 of 19 in cluster DU**

Actual:
478 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1970	JOHNSON J W SERVICE STATION GAS	GASOLINE STATIONS

DU1800 **CUNNINGHAM GEO L FILLING STA** **EDR Hist Auto** **1013765978**
SW **510 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.034 mi.
181 ft. **Site 16 of 19 in cluster DU**

Actual:
478 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	CUNNINGHAM GEO L FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1953	JOHNSON J W SERV	GASOLINE STATIONS
1958	JOHNSON J W SERV	GASOLINE STATIONS
1962	JOHNSON J W SERV STA	GASOLINE STATIONS

DU1801 SW < 1/8 0.034 mi. 181 ft. | **CUNNINGHAM G L**
510 5TH ST E
AUSTIN, TX
Site 17 of 19 in cluster DU | **EDR Hist Auto** | **1013753827**
N/A

Actual: 478 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	YOUNG & SCHIEFFER GARAGE	GASOLINE AND OIL SERVICE STATIONS
1929	YOUNG & SCHIEFFER GARAGE	AUTOMOBILE GARAGES
1935	CUNNINGHAM G L	GASOLINE AND OIL SERVICE STATIONS
1965	JOHNSON J W SERVICE	GASOLINE STATIONS

KN1802 WSW < 1/8 0.035 mi. 183 ft. | **BEN HIBBETTS**
1725 E RIVERSIDE DR
AUSTIN, TX 78741
Site 1 of 4 in cluster KN | **TX UST** | **U003566283**
N/A

Actual: 459 ft.

Focus Map: 14

UST:

Name:	BEN HIBBETTS
Address:	1725 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 787411331
AI Number:	23280
Facility Type:	RETAIL
Facility Begin Date:	09/25/1986
Facility Status:	INACTIVE
Additional ID:	214155852002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	R L EBERT,DIV MGR
Contact Organization Name:	BEN HIBBETTS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7136861311
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	R L EBERT,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601583016
Owner Last Name:	HIBBETTS
Owner First Name:	BEN
Owner Middle Name:	Not reported

BEN HIBBETTS (Continued) **U003566283**

Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	779564012003087
Additional ID:	214155852002156
AI Number:	23280
Owner Effective Begin Date:	09/25/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59943
Facility ID:	87639
Ai Number:	23280
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

BEN HIBBETTS (Continued) **U003566283**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	6000
UST Comprt ID:	147941
UST ID:	59943
AI Number:	23280
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

BEN HIBBETTS (Continued) **U003566283**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8825
Cert ID:	237950
UST Comprt ID:	683312
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39650
UST Comprt ID:	120793
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39649
UST Comprt ID:	120794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39648
UST Comprt ID:	120795
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39647
UST Comprt ID:	120796
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39646
UST Comprt ID:	120797

BEN HIBBETTS (Continued) **U003566283**

UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39645
UST Comprt ID:	120798
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39644
UST Comprt ID:	120799
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39643
UST Comprt ID:	120800
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39642
UST Comprt ID:	120801
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39641
UST Comprt ID:	120802
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39640
UST Comprt ID:	120805
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39395
UST Comprt ID:	120804
UST ID:	28020

BEN HIBBETTS (Continued) **U003566283**

AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39394
UST Comprt ID:	120803
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	322908
UST Comprt ID:	935794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	306170
UST Comprt ID:	885885
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	288668
UST Comprt ID:	833412
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	272022
UST Comprt ID:	784041
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	253495
UST Comprt ID:	728969
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	221740
UST Comprt ID:	636052
UST ID:	28020
AI Number:	23280

BEN HIBBETTS (Continued) **U003566283**

Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59944
Facility ID:	87639
Ai Number:	23280
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

BEN HIBBETTS (Continued) **U003566283**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	147942
UST ID:	59944
AI Number:	23280
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8825
Cert ID:	237950
UST Comprt ID:	683312

BEN HIBBETTS (Continued) **U003566283**

UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39650
UST Comprt ID:	120793
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39649
UST Comprt ID:	120794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39648
UST Comprt ID:	120795
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39647
UST Comprt ID:	120796
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39646
UST Comprt ID:	120797
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39645
UST Comprt ID:	120798
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39644
UST Comprt ID:	120799
UST ID:	28020

BEN HIBBETTS (Continued) **U003566283**

AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39643
UST Comprt ID:	120800
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39642
UST Comprt ID:	120801
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39641
UST Comprt ID:	120802
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39640
UST Comprt ID:	120805
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39395
UST Comprt ID:	120804
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39394
UST Comprt ID:	120803
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	322908
UST Comprt ID:	935794
UST ID:	28020
AI Number:	23280

BEN HIBBETTS (Continued) **U003566283**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	306170
UST Comprt ID:	885885
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	288668
UST Comprt ID:	833412
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	272022
UST Comprt ID:	784041
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	253495
UST Comprt ID:	728969
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	221740
UST Comprt ID:	636052
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59947
Facility ID:	87639
Ai Number:	23280
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1987

BEN HIBBETTS (Continued) **U003566283**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	147945
UST ID:	59947
AI Number:	23280
Compartment ID:	A
Substance Stored1:	USED OIL

BEN HIBBETTS (Continued) **U003566283**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8825
Cert ID:	237950
UST Comprt ID:	683312
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39650
UST Comprt ID:	120793
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39649
UST Comprt ID:	120794
UST ID:	28020
AI Number:	23280

BEN HIBBETTS (Continued) **U003566283**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39648
UST Comprt ID:	120795
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39647
UST Comprt ID:	120796
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39646
UST Comprt ID:	120797
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39645
UST Comprt ID:	120798
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39644
UST Comprt ID:	120799
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39643
UST Comprt ID:	120800
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39642
UST Comprt ID:	120801
UST ID:	28020
AI Number:	23280
Tank ID:	1

BEN HIBBETTS (Continued) **U003566283**

Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39641
UST Comprt ID:	120802
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39640
UST Comprt ID:	120805
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39395
UST Comprt ID:	120804
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39394
UST Comprt ID:	120803
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	322908
UST Comprt ID:	935794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	306170
UST Comprt ID:	885885
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	288668
UST Comprt ID:	833412
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A

BEN HIBBETTS (Continued) **U003566283**

Self Cert ID:	8825
Cert ID:	272022
UST Comprt ID:	784041
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	253495
UST Comprt ID:	728969
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	221740
UST Comprt ID:	636052
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59946
Facility ID:	87639
Ai Number:	23280
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

BEN HIBBETTS (Continued) **U003566283**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	147944
UST ID:	59946
AI Number:	23280
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

BEN HIBBETTS (Continued) **U003566283**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8825
Cert ID:	237950
UST Comprt ID:	683312
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39650
UST Comprt ID:	120793
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39649
UST Comprt ID:	120794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39648
UST Comprt ID:	120795
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39647
UST Comprt ID:	120796
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A

BEN HIBBETTS (Continued) **U003566283**

Self Cert ID:	8825
Cert ID:	39646
UST Comprt ID:	120797
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39645
UST Comprt ID:	120798
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39644
UST Comprt ID:	120799
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39643
UST Comprt ID:	120800
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39642
UST Comprt ID:	120801
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39641
UST Comprt ID:	120802
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39640
UST Comprt ID:	120805
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825

BEN HIBBETTS (Continued) **U003566283**

Cert ID:	39395
UST Comprt ID:	120804
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39394
UST Comprt ID:	120803
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	322908
UST Comprt ID:	935794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	306170
UST Comprt ID:	885885
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	288668
UST Comprt ID:	833412
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	272022
UST Comprt ID:	784041
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	253495
UST Comprt ID:	728969
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	221740

BEN HIBBETTS (Continued) **U003566283**

UST Comprt ID:	636052
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59945
Facility ID:	87639
Ai Number:	23280
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

BEN HIBBETTS (Continued) **U003566283**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	147943
UST ID:	59945
AI Number:	23280
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

BEN HIBBETTS (Continued) **U003566283**

Self Cert ID:	8825
Cert ID:	237950
UST Comprt ID:	683312
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39650
UST Comprt ID:	120793
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39649
UST Comprt ID:	120794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39648
UST Comprt ID:	120795
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39647
UST Comprt ID:	120796
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39646
UST Comprt ID:	120797
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39645
UST Comprt ID:	120798
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825

BEN HIBBETTS (Continued) **U003566283**

Cert ID:	39644
UST Comprt ID:	120799
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39643
UST Comprt ID:	120800
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39642
UST Comprt ID:	120801
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39641
UST Comprt ID:	120802
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39640
UST Comprt ID:	120805
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39395
UST Comprt ID:	120804
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	39394
UST Comprt ID:	120803
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	322908

BEN HIBBETTS (Continued) **U003566283**

UST Comprt ID:	935794
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	306170
UST Comprt ID:	885885
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	288668
UST Comprt ID:	833412
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	272022
UST Comprt ID:	784041
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	253495
UST Comprt ID:	728969
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8825
Cert ID:	221740
UST Comprt ID:	636052
UST ID:	28020
AI Number:	23280
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	HIBBETTS BEN
Contact Mailing Address (Delivery):	3213 CHURCHILL DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 1417
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87639

BEN HIBBETTS (Continued) **U003566283**

Additional ID:	214155852002156
Princ ID:	779564012003087
AI Number:	23280
Facility Name:	BEN HIBBETTS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BEN HIBBITTS/

1803 ESE < 1/8 0.035 mi. 183 ft. **NORTH LAMAR SAFTI BRAKE** **TX Ind. Haz Waste** **S102748182**
701 PROVINES DR STE A **N/A**
AUSTIN, TX 78753

Actual: 754 ft.

Focus Map: 3

Ind. Haz Waste:

Name:	NORTH LAMAR SAFTI BRAKE
Address:	701 PROVINES DR STE A
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61253
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	701 A Provines Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	NORTH LAMAR SAFTI-BRAKE
Contact Name:	MIKE WEBER
Contact Telephone Number:	Not reported
Mailing Address:	701 PROVINES DR STE A
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787533008
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19611
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1

NORTH LAMAR SAFTI BRAKE (Continued) **S102748182**

MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	NORTH LAMAR SAFTI-BRAKE
Operator Address:	701 PROVINES DR STE A
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	NORTH LAMAR SAFTI-BRAKE
Owner Mailing Address:	701 PROVINES DR STE A
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	701 PROVINES DR STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	701 PROVINES DR STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported

NORTH LAMAR SAFTI BRAKE (Continued) **S102748182**

Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	MIKE WEBER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	701 PROVINES DR STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

JR1804 **AUSTIN KAWASKI** **TX Ind. Haz Waste** **S103605598**
WNW **10426 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.035 mi.
184 ft. **Site 4 of 6 in cluster JR**

Actual:
727 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	AUSTIN KAWASKI
Address:	10426 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61147
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	10426 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN KAWASKI
Contact Name:	MARK BLOHM
Contact Telephone Number:	Not reported
Mailing Address:	10426 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787533647
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19508

AUSTIN KAWASKI (Continued) **S103605598**

Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN KAWASKI
Operator Address:	10426 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN KAWASKI
Owner Mailing Address:	10426 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	10426 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

AUSTIN KAWASKI (Continued) **S103605598**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	10426 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MARK BLOHM
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	10426 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100589746
Name:	AUSTIN KAWASKI
Address:	10426 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3647
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600299770
Customer Name:	AUSTIN KAWASKI
Customer Legal Name:	Austin Kawaski
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10426 N Lamar, Austin, TX

Regulated Entity Number:	RN100589746
Name:	AUSTIN KAWASKI
Address:	10426 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3647
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600299770
Customer Name:	AUSTIN KAWASKI
Customer Legal Name:	Austin Kawaski
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

AUSTIN KAWASKI (Continued) **S103605598**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: 10426 N Lamar, Austin, TX

Regulated Entity Number: RN100589746
Name: AUSTIN KAWASKI
Address: 10426 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-3647
Status: ACTIVE
Status Date: ##########
Customer Number: CN603894288
Customer Name: AUSTIN KAWASKI CTR INC
Customer Legal Name: AUSTIN KAWASKI CTR INC
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 12/30/1997
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 10426 N Lamar, Austin, TX

Regulated Entity Number: RN100589746
Name: AUSTIN KAWASKI
Address: 10426 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-3647
Status: ACTIVE
Status Date: ##########
Customer Number: CN603894288
Customer Name: AUSTIN KAWASKI CTR INC
Customer Legal Name: AUSTIN KAWASKI CTR INC
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 12/30/1997
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 10426 N Lamar, Austin, TX

JR1805 **AUSTIN KAWASAKI** **EDR Hist Auto** **1013759188**
WNW **10426 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78763**
0.035 mi.
184 ft. **Site 5 of 6 in cluster JR**

Actual:
727 ft.
EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1984	AUSTIN KAWASAKI	MOTORCYCLE DEALERS AND REPAIRERS

JR1806 **UNDELIVERABLE** **TX Ind. Haz Waste** **S110294003**
WNW **10426 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.035 mi.
184 ft. **Site 6 of 6 in cluster JR**

Actual:
727 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	UNDELIVERABLE
Address:	10426 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	67348
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	12/30/1997
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN KAWASKI CTR INC
Contact Name:	JAMES PARKER
Contact Telephone Number:	Not reported
Mailing Address:	10426 N LAMAR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 78758
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22475
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

UNDELIVERABLE (Continued) **S110294003**

Ind. Haz Waste:

Owner Name:	AUSTIN KAWASKI CTR INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	JAMES PARKER
Contact Title:	Not reported
Contact Role:	PRICONT
Contact Address:	10426 NLAMAR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

BG1807 **DRY CIN VILLAGE** **EDR Hist Cleaner** **1013786890**
WNW **604 29TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.035 mi.
184 ft. **Site 7 of 8 in cluster BG**

Actual:
600 ft.

Focus Map:
8

EDR Hist Cleaner

Year:	Name:	Type:
1962	DRY CIN VILLAGE	CLEANERS-SELF SERVICE
1962	DRY CIN VILLAGE	CLEANERS AND DYERS

1808 **AMERICAN TAXI CAB CO.** **TX HIST UST** **S111678554**
WNW **408 W 11TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.035 mi.
184 ft.

Actual:
543 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	AMERICAN TAXI CAB CO.
Address:	408 W 11TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0415
HID UST:	415
Inspection:	Not reported
Due:	06/01/2012

BG1809
WNW
< 1/8
0.035 mi.
185 ft.

MASTER DICKENS CLEANERS & LAUNDRY
604 29TH ST W
AUSTIN, TX 78705
Site 8 of 8 in cluster BG

EDR Hist Cleaner **1013786051**
N/A

Actual:
600 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1980	MASTER DICKENS CLEANERS & LAUND	CLEANERS AND DYERS

DU1810
SW
< 1/8
0.035 mi.
185 ft.

HART BUBBA SERVICE STA & GARAGE
509 5TH E
AUSTIN, TX
Site 18 of 19 in cluster DU

EDR Hist Auto **1013763489**
N/A

Actual:
478 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	HART BUBBA SERVICE STA & GARAGE	GASOLINE AND OIL SERVICE STATIONS

DU1811
SW
< 1/8
0.035 mi.
185 ft.

JOHNSONS SERVICE STATION FILL STA
508 5TH E
AUSTIN, TX
Site 19 of 19 in cluster DU

EDR Hist Auto **1013760750**
N/A

Actual:
478 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	JOHNSONS SERVICE STATION FILL S	GASOLINE AND OIL SERVICE STATIONS

KH1812
SSW
< 1/8
0.035 mi.
187 ft.

WALKER J M CLDO CLNR 2 60 S
208 CONGRESS AVE
AUSTIN, TX
Site 3 of 19 in cluster KH

EDR Hist Cleaner **1013779671**
N/A

Actual:
476 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1940	WALKER J M CLDO CLNR 2 60 S	CLOTHES PRESSERS AND CLEANERS

AD1813
WNW
< 1/8
0.035 mi.
187 ft.

B & M DISCOUNT TRANSMISSION
808 JUSTIN LN
AUSTIN, TX 78757
Site 6 of 6 in cluster AD

EDR Hist Auto **1013759261**
N/A

Actual:
719 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1980	B & M DISCOUNT TRANSMISSION	AUTOMOBILE REPAIRING
1984	B & M DISCOUNT TRANSMISSIONS AU	AUTOMOBILE REPAIRING

B & M DISCOUNT TRANSMISSION (Continued) **1013759261**

1985	B & M DISCOUNT TRANSMISSION	Automotive Repair Shops, NEC
1986	C & S IRON INC	Automotive Repair Shops, NEC
1987	C & S IRON INC	Automotive Repair Shops, NEC
1990	B & M DISCOUNT TRANSMISSIONS AU	AUTOMOBILE REPAIRING
1992	B&M TRANSMISSIONS	Automotive Transmission Repair Shops
1993	B&M TRANSMISSIONS	Automotive Transmission Repair Shops
1994	B&M TRANSMISSIONS	Automotive Transmission Repair Shops
1995	B&M TRANSMISSIONS	Automotive Transmission Repair Shops
1996	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
1997	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
1998	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
1999	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2000	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2001	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2002	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2003	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2004	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2005	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2006	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2007	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2008	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops
2009	B&M TRANSMISSIONS INC	Automotive Transmission Repair Shops

---

BK1814 **A MASTER DICKENS CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1013779859**
ENE **2815 FRUTH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.036 mi.
188 ft. **Site 7 of 8 in cluster BK**

Actual:
592 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1984	A MASTER DICKENS CLEANERS & LAU	CLEANERS AND DYERS
1990	A SIR DICKENS CLEANERS & LAUNDR	CLEANERS AND DYERS
1992	DICKENS CLEANERS & SHIRT LDRY	Drycleaning Plants, Except Rugs

---

BK1815 **ANN STUMPF** **TX UST** **U001284163**
ENE **2815 FRUTH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.036 mi.
188 ft. **Site 8 of 8 in cluster BK**

Actual:
592 ft.

UST:

Focus Map:
11

Name:	ANN STUMPF
Address:	2815 FRUTH ST
City,State,Zip:	AUSTIN, TX 787053765
AI Number:	53738
Facility Type:	FARM OR RESIDENTIAL
Facility Begin Date:	05/17/1990
Facility Status:	INACTIVE
Additional ID:	582685532002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

ANN STUMPF (Continued) **U001284163**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	ANN STUMPF
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7134825003
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/14/1990
Signature Name/Title On Earliest Reg Form:	ANN STUMPF,OWNER
Application Received Date On Earliest Reg Form:	05/16/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600783294
Owner Last Name:	STUMPF ANN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	572685522002053
Additional ID:	582685532002053
AI Number:	53738
Owner Effective Begin Date:	05/17/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/16/1990
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	132155
Facility ID:	83552

ANN STUMPF (Continued) **U001284163**

Ai Number:	53738
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/27/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/07/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	127304

ANN STUMPF (Continued) **U001284163**

UST ID:	132155
AI Number:	53738
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/16/1990
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	132156
Facility ID:	83552
Ai Number:	53738
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/27/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

ANN STUMPF (Continued) **U001284163**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/07/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	127305
UST ID:	132156
AI Number:	53738
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

ANN STUMPF (Continued) **U001284163**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	STUMPF ANN
Contact Mailing Address (Delivery):	518 N BOWIE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SEGUIN, TX 78155 4436
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83552
Additional ID:	582685532002053
Princ ID:	572685522002053
AI Number:	53738
Facility Name:	ANN STUMPF
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOHN STUMPF/

HIST UST AUSTIN:

Name:	LET'S GO WINDSURF
Address:	2815 FRUTH ST
City,State,Zip:	AUSTIN, TX

ANN STUMPF (Continued) **U001284163**

Id UST:	C0172
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KO1816 **J.E. RICKS** **TX HIST UST** **S111678693**
ESE **6215 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.036 mi.
188 ft. **Site 1 of 2 in cluster KO**

Actual:
709 ft.

Focus Map:
9

HIST UST AUSTIN:

Name:	J.E. RICKS
Address:	6215 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0431
HID UST:	431
Inspection:	Not reported
Due:	06/01/2012

KO1817 **T JS CYCLE SALES & SERVICE MOTORCYCLE DIRS & REPR** **EDR Hist Auto** **1013770558**
ESE **6215 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.036 mi.
188 ft. **Site 2 of 2 in cluster KO**

Actual:
709 ft.

Focus Map:
9

EDR Hist Auto

Year:	Name:	Type:
1990	T JS CYCLE SALES & SERVICE MOTO	MOTORCYCLE DEALERS AND REPAIRERS
1990	T JS SALES & SERVICE	General Automotive Repair Shops

KP1818 **GULF REFG CO STA NO** **EDR Hist Auto** **1013757409**
SW **507 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.036 mi.
188 ft. **Site 1 of 7 in cluster KP**

Actual:
478 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS

KP1819 SW < 1/8 0.036 mi. 188 ft. | **HALEY MALCOLM M FILLING STA**
507 5TH E
AUSTIN, TX
Site 2 of 7 in cluster KP | **EDR Hist Auto** | **1013754451**
N/A

Actual: 478 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	HALEY MALCOLM M FILLING STA	GASOLINE AND OIL SERVICE STATIONS

KN1820 WSW < 1/8 0.036 mi. 189 ft. | **PARKER LN AND RIVERSIDE**
PARKER LN AND RIVERSIDE DR.
TRAVIS (County), TX
Site 2 of 4 in cluster KN | **TX CLI** | **S119135340**
N/A

Actual: 459 ft. CAPCOG LI:

Focus Map: 14

Name:	PARKER LN AND RIVERSIDE
Address:	PARKER LN AND RIVERSIDE DR.
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	1930
Date Close:	1935
Unum:	894
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	14.609999999999999
Longitude Deg:	97
Longitude Min:	43.810000000000002
Lat Dd:	30.243500000000001
Long Dd:	-97.730166999999994
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	0
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Ted and John Latouf
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported

PARKER LN AND RIVERSIDE (Continued) **S119135340**

Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	5
Reviewer1:	Contested; City Of Austin Doesn't Believe This Is A Site
Confidence:	NO SUPPORTING DOCUMENTATION
Cog1:	12
Twc Dist:	14
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Y
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Inspection:	???
Comment:	Identified in list of Travis County sites;
Latitude:	30.2435
Longitude:	-97.73016667
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part1.pdf#page=262

KN1821 **PARKER LN & RIVERSIDE** **TX CLI** **S103259068**
WSW **N/A**
< 1/8 **, TX**
0.036 mi.
189 ft. **Site 3 of 4 in cluster KN**

Actual:
459 ft.

Focus Map:
14

CLI:

Name:	PARKER LN & RIVERSIDE
Address:	Not reported
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported

PARKER LN & RIVERSIDE (Continued) **S103259068**

Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	*********
Source Code:	Not reported
Date Opened:	1930
Date Closed:	1935
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	14.61
Long Deg:	97
Long Min:	43.81
Lat/Long (deg):	30.243500 / -97.730167
Owner:	Not reported
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	14
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Yes
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Uk
Inspc Comments:	???
Comments:	Identified in list of Travis County sites;
Update:	5
Reviewer:	Contested; City Of Austin Doesn't Believe This Is A Site
Flag:	Not reported

KN1822 WSW | **PARKER LN & RIVERSIDE** | **TX HIST LF** | **S129375050** **N/A**

< 1/8 0.036 mi. 189 ft. | **TRAVIS (County), TX**

Site 4 of 4 in cluster KN

Actual: 459 ft.

Focus Map: 14

HIST LF:

Name:	PARKER LN & RIVERSIDE
Name 2:	Not reported
Address:	Not reported
City,State,Zip:	TX
Latitude:	30.243500
Longitude:	-97.730167
Lat Deg:	30
Lat MM:	14.61
Lon DD:	97
Lon MM:	43.81
UNUM:	894
Comments:	Identified in list of Travis County sites;
Inspection:	???
COG Number:	12
COOR CD:	Not reported
TWC District:	14
Owner Name:	Not reported
Owner Code:	Not reported
Open Date:	1930
Close Date:	1935
Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Y
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Update:	Contested Site
Reviewer:	Contested; City Of Austin Doesn't Believe This Is A Site
Accuracy:	TNRCC files
Source:	Not reported

JX1823 **BILL KASSON MOTORCYCLES** **TX HIST UST** **S119139637**
SE **2603 S CONGRESS AVE** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.036 mi.
189 ft. **Site 3 of 3 in cluster JX**

Actual:
625 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	JONES BLAIR PAINT
Address:	2603 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0041
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	BILL KASSON MOTORCYCLES
Address:	2603 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	4.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Email from
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported

BILL KASSON MOTORCYCLES (Continued) **S119139637**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

KH1824 **AUSTIN RADIATOR CO** **EDR Hist Auto** **1013771318**
SSW **205 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.036 mi.
189 ft. **Site 4 of 19 in cluster KH**

Actual:
476 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	AUSTIN RADIATOR CO	AUTOMOBILE RADIATOR REPAIRERS
1922	AUSTIN RADIATOR CO	RADIATOR REPAIRING
1922	AUSTIN RADIATOR CO	AUTOMOBILE REPAIRERS

JA1825 **HUMBLE OIL & REFG** **EDR Hist Auto** **1013769467**
WNW **816 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.036 mi.
190 ft. **Site 4 of 15 in cluster JA**

Actual:
504 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	HUMBLE OIL & REF CO SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1935	HUMBLE OIL & REFG	GASOLINE AND OIL SERVICE STATIONS

1826 ESE < 1/8 0.036 mi. 191 ft. | **HOME STEAM LAUNDRY**
601 E 14TH ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013787330**
N/A

Actual: 520 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1965	HOME STEAM LAUNDRY	LAUNDRIES

DE1827 WNW < 1/8 0.036 mi. 191 ft. | **POLAR ICE CREAM**
417 W 6TH ST
AUSTIN, TX | **TX HIST UST** | **S111678779**
N/A

Site 13 of 13 in cluster DE

Actual: 488 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	POLAR ICE CREAM
Address:	417 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0694
HID UST:	694
Inspection:	03/19/2009
Due:	03/19/2012

KQ1828 ENE < 1/8 0.036 mi. 192 ft. | **VACANT BUILDING**
701 E 6TH ST
AUSTIN, TX 78701 | **TX LPST** | **S104876285**
N/A

Site 1 of 2 in cluster KQ

Actual: 458 ft. LPST:

Focus Map: 11

Name:	VACANT BUILDING
Address:	701 E 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	099450
Facility Location:	E 6TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/03/1991
Entered Date:	07/10/1991
Reported Date:	06/25/1991
Closure Date:	03/18/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	/-

VACANT BUILDING (Continued) **S104876285**

Reported Date: 06/25/1991
Case Start Date: 03/18/1993
Reference Number: RN106976236
Project Manager: HWELCH

DI1829 **B&N AXLE SERV** **EDR Hist Auto** **1013762352**
ESE **314 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
193 ft. **Site 8 of 9 in cluster DI**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	HAMS AUTO SERV REPRS	AUTOMOBILE REPAIRING
1958	B&N AXLE SERV	AUTOMOBILE REPAIRING
1962	B&N AXLE SERV AUTO	AUTOMOBILE REPAIRING

CZ1830 **ME MORRIS FORD INCORPORATED** **EDR Hist Auto** **1013754904**
WNW **808 6TH ST W** **N/A**
< 1/8 **AUSTIN, TX 78703**
0.037 mi.
193 ft. **Site 7 of 9 in cluster CZ**

Actual:
454 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1980	ME MORRIS FORD INC	AUTOMOBILE REPAIRING
1984	ME MORRIS FORD INCORPORATED	AUTOMOBILE REPAIRING

CZ1831 **MC MORRIS FORD INCORPORATED** **EDR Hist Auto** **1013773096**
WNW **808 6TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78703**
0.037 mi.
193 ft. **Site 8 of 9 in cluster CZ**

Actual:
454 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	ME MORRIS FORD INC	AUTOMOBILE REPAIRING
1990	MC MORRIS FORD INCORPORATED	AUTOMOBILE REPAIRING

1832 **JENSENS HARRY AUTO REPAIRS** **EDR Hist Auto** **1013769799**
NNE **408 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.037 mi.
194 ft.

Actual:
494 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1969	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1970	JENSENS HARRY AUTO REPAIRS	AUTOMOBILE REPAIRING

JENSENS HARRY AUTO REPAIRS (Continued) **1013769799**

1970	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1971	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1972	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1973	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1974	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1975	JENSEN HARRY AUTO REPAIR	General Automotive Repair Shops
1990	AUTO REPAIRS	Auto And Home Supply Stores

1833 SW < 1/8 0.037 mi. 194 ft. **FRANKS FIX IT** **EDR Hist Auto** **1013766205**
4214 AVENUE A **N/A**
HYDE PARK, TX

Actual: 619 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1958	FRANKS FIX IT	REPAIR SHOPS

IC1834 WNW < 1/8 0.037 mi. 195 ft. **FRANK HUNT PROPERTY** **TX RDR** **S127540700**
605 W 37TH ST **N/A**
AUSTIN, TX

Site 7 of 10 in cluster IC

Actual: 598 ft. RDR:

Focus Map: 8

RDR ID:	21524
Facility ID:	86176
RN:	Not reported
CN:	Not reported
Name:	FRANK HUNT PROPERTY
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/24/2013
Due Date:	12/23/2013
Tank Owner:	Not reported
Contact Person:	FRANK HUNT
Report:	TANK CLOS
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/30/2013
Project Manager:	Anne Miller
Team:	#N/A
New LPST Number:	119240
Pre-Existing LPST Number:	Not reported
Comments:	9/16/2013 TANK CLOS; 10/24/2013 RDR
Review Coordinator:	ASM
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

IC1835 WNW < 1/8 0.037 mi. 195 ft. | **FURNITURE REJUVENATION 605 W 37TH ST AUSTIN, TX** | **TX HIST UST** | **S128729137 N/A**

Site 8 of 10 in cluster IC

Actual: 598 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	FURNITURE REJUVENATION
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0722
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IC1836 WNW < 1/8 0.037 mi. 195 ft. | **FURNITURE REJUVENATORS 605 W 37TH ST AUSTIN, TX 78705** | **TX LPST TX TANKS TX GCC** | **S111678639 N/A**

Site 9 of 10 in cluster IC

Actual: 598 ft.
Focus Map: 8

LPST:

Name:	FURNITURE REJUVENATORS
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0086176
LPST Id:	119240
Facility Location:	605 W 37TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/05/2013
Entered Date:	10/30/2013
Reported Date:	08/06/2013
Closure Date:	03/13/2015
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**PREASSESSMENT/RELEASE DETERMINATION**
Coordinators Primary:	1
Coordinators RPR:	ANNE MILLER
Responsible Party Name:	Not reported
Responsible Party Contact:	FRANK HUNT
Responsible Party Address:	1600 PRESTON AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/452-8880
Reported Date:	08/06/2013
Case Start Date:	03/13/2015
Reference Number:	RN106842057
Project Manager:	ASMILLER

TANKS:

Facility ID:	131302
Name:	FURNITURE REJUVENATORS
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX 787051210
Total UST:	Not reported
Additional ID:	821531722013189

FURNITURE REJUVENATORS (Continued) **S111678639**

AI Number:	86176
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

GCC:

Name:	FURNITURE REJUVENATORS
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	119240
Contamination Description:	UNKNOWN
Date Of Earliest Known Contamination Confirmation:	8/6/2013
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	FURNITURE REJUVENATORS
Address:	605 W 37TH ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST

FURNITURE REJUVENATORS (Continued) **S111678639**

New Cases: Not reported
File Number: 119240
Contamination Description: UNKNOWN
Date Of Earliest Known Contamination Confirmation: 10/30/2013
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

IC1837 **ERNEST M. DURBIN** **TX HIST UST** **S128729442**
WNW **605 W 37TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
195 ft. **Site 10 of 10 in cluster IC**

Actual:
598 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: ERNEST M. DURBIN
Address: 605 W 37TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0840
HID UST: 840
Inspection: Not reported
Due: 06/01/2012

KR1838 **GULF OIL CORPORATION** **TX HIST UST** **S111678659**
ESE **601 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
197 ft. **Site 1 of 10 in cluster KR**

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:
Name: GULF OIL CORPORATION
Address: 601 W 6TH ST
City,State,Zip: AUSTIN, TX
Id UST: H0915
HID UST: 915
Inspection: Not reported
Due: 06/01/2012

KS1839 **PEARL LAUNDRY** **EDR Hist Cleaner** **1013777908**
ESE **401 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
197 ft. **Site 1 of 5 in cluster KS**

Actual:
462 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	PEARL LAUNDRY	LAUNDRIES
1940	PEARL LAUNDRY	LAUNDRIES

KS1840 **REDDS HUMBLE SERV FILL STA** **EDR Hist Auto** **1013757768**
ESE **401 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
197 ft. **Site 2 of 5 in cluster KS**

Actual:
462 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	LEIGH SERVICE STA NO 4	GASOLINE AND OIL SERVICE STATIONS
1953	REDDS HUMBLE SERV FILL STA	GASOLINE STATIONS

KT1841 **AUSTIN MUNICIPAL BUILDING** **TX UST** **U001962407**
WNW **124 W 8TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.037 mi.
197 ft. **Site 1 of 4 in cluster KT**

Actual:
522 ft.
UST:

Focus Map:
11

Name:	AUSTIN MUNICIPAL BUILDING
Address:	124 W 8TH ST
City,State,Zip:	AUSTIN, TX 787012302
AI Number:	65899
Facility Type:	Not reported
Facility Begin Date:	01/01/1988
Facility Status:	INACTIVE
Additional ID:	44550902002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MARC CHILDERS,
Contact Organization Name:	AUSTIN MUNICIPAL BUILDING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129281492
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/08/1994

AUSTIN MUNICIPAL BUILDING (Continued) **U001962407**

Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRES
Application Received Date On Earliest Reg Form:	08/11/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	44550902002138
AI Number:	65899
Owner Effective Begin Date:	01/01/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	08/11/1994
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171668
Facility ID:	98273
Ai Number:	65899
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/21/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

AUSTIN MUNICIPAL BUILDING (Continued) **U001962407**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	163556
UST ID:	171668
AI Number:	65899
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

AUSTIN MUNICIPAL BUILDING (Continued) **U001962407**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	98273
Additional ID:	44550902002138
Princ ID:	840354562001227
AI Number:	65899
Facility Name:	AUSTIN MUNICIPAL BUILDING
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COA - MUNICIPAL BLDG
Address:	124 W 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0493
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KU1842 ESE < 1/8 0.037 mi. 197 ft. | **OSCAR KUNTZ? 800 E CESAR CHAVEZ ST AUSTIN, TX** | **TX HIST UST** | **S111678768 N/A**

Site 1 of 3 in cluster KU

Actual: 470 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	OSCAR KUNTZ?
Address:	800 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0057
HID UST:	57
Inspection:	11/08/2011
Due:	11/08/2014

AM1843 ESE < 1/8 0.037 mi. 197 ft. | **GREAT HALL GAMES 5501 N LAMAR BLVD AUSTIN, TX 78751** | **TX HIST UST TX ASBESTOS** | **S111678563 N/A**

Site 4 of 4 in cluster AM

Actual: 679 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	AUSTIN FIREPROOF WAREHOUSE CO
Address:	5501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0503
HID UST:	503
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	BLUSH BRIDAL LOUNGE
Address:	5501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/01/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Discretionary/Special
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

GREAT HALL GAMES (Continued) **S111678563**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/15/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	58531
License Status Description:	Current
Expiration Date:	01/27/2026
Original Date:	01/28/2021
Rank Effective Date:	01/28/2021
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25526
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	GREAT HALL GAMES
Address:	5501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	05/30/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5

GREAT HALL GAMES (Continued) **S111678563**

Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/03/2013
Date Routed by Supervisor:	06/03/2013
Date Routed to PSQA:	06/06/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GREAT HALL GAMES (Continued) **S111678563**

Name:	GREAT HALL GAMES
Address:	5501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78751
Date of inspection:	06/06/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

GREAT HALL GAMES (Continued) **S111678563**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DI1844 **MISSION CITY PONTIAC CO AUTO DLRS** **EDR Hist Auto** **1013769963**
ESE **312 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.037 mi.
197 ft. **Site 9 of 9 in cluster DI**

Actual:
489 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	MISSION CITY PONTIAC CO AUTO DL	AUTOMOBILE REPAIRING

FU1845 **FAMILY DOLLAR #3834** **RCRA-VSQG** **1017780857**
SE **118 E. OLTORF ST** **TXR000082522**
< 1/8 **AUSTIN, TX 78704**
0.038 mi.
198 ft. **Site 13 of 13 in cluster FU**

Actual:
600 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20150114
Handler Name:	Family Dollar #3834
Handler Address:	E. OLTORF ST
Handler City,State,Zip:	AUSTIN, TX 78704-5529
EPA ID:	TXR000082522
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported
Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PRG MGR, ENVR COMP
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1017
Mailing City,State,Zip:	CHARLOTTE, NC 28201
Owner Name:	Twin Oaks Assoc., Ltd
Owner Type:	Private

FAMILY DOLLAR #3834 (Continued) **1017780857**

Operator Name:	Family Dollar Stores
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150203
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium

FAMILY DOLLAR #3834 (Continued) **1017780857**

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: FAMILY DOLLAR STORES	
Legal Status:	Private
Date Became Current:	19991124
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TWIN OAKS ASSOC., LTD	
Legal Status:	Private
Date Became Current:	20100101
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 41149
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-442-6779
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20150114
Handler Name: FAMILY DOLLAR #3834	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

FAMILY DOLLAR #3834 (Continued) **1017780857**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

KP1846 **SMITH B C TIRE SHOP** **EDR Hist Auto** **1013769399**
SW **500 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
198 ft. **Site 3 of 7 in cluster KP**

Actual:
479 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	HICKMAN R L AUTO	AUTOMOBILE REPAIRERS
1929	SMITH B C TIRE SHOP	AUTOMOBILE GARAGES

KP1847 **WALLACE GARAGE AUTO REPRS** **EDR Hist Auto** **1013761653**
SW **500 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
198 ft. **Site 4 of 7 in cluster KP**

Actual:
479 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	SMITHS B GARAGE	AUTOMOBILE REPAIRING
1947	WALLACE GARAGE AUTO REPRS	AUTOMOBILE REPAIRING

IT1848 **BALCARS HUMBLE** **EDR Hist Auto** **1013753497**
ESE **4501 GUADALUPE ST** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
199 ft. **Site 2 of 2 in cluster IT**

Actual:
630 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1947	CARLSON SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	CARLSON HUMBLE STA	GASOLINE STATIONS

BALCARS HUMBLE (Continued) **1013753497**

1958	BALCARS HUMBLE	GASOLINE STATIONS
1962	BALCARS HUMBLE	GASOLINE STATIONS
1965	WILLIAMS ENCO SERVICE	GASOLINE STATIONS

GS1849 **EXXON MOBIL CORPORATION** **EDR Hist Auto** **1020512997**
WNW **201 W BEN WHITE BLVD** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.038 mi.
199 ft. **Site 4 of 6 in cluster GS**

Actual:
666 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
2007	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2008	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2009	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2010	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2011	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2012	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC
2013	EXXON MOBIL CORPORATION	Gasoline Service Stations, NEC

GS1850 **7-ELEVEN STORE 36591** **TX UST** **U003653044**
WNW **201 W BEN WHITE BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX ASBESTOS**
0.038 mi. **TX Financial Assurance**
199 ft. **Site 5 of 6 in cluster GS**

Actual:
666 ft.

UST:

Focus Map:
14

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047154
AI Number:	72099
Facility Type:	RETAIL
Facility Begin Date:	09/22/1998
Facility Status:	ACTIVE
Additional ID:	658642402002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 36591
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/28/1999
Signature Name/Title On Earliest Reg Form:	B H HUNTER,REG ADMIN

7-ELEVEN STORE 36591 (Continued) **U003653044**

Application Received Date On Earliest Reg Form:	06/11/1999
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	658642402002175
Ai Number:	72099
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	12/28/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	658642402002175
AI Number:	72099
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Certification:

Self Cert ID:	109721
Cert ID:	382222
AI Number:	72099
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	364906
AI Number:	72099
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	348147
AI Number:	72099
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	331104
AI Number:	72099
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	314607
AI Number:	72099
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	295991
AI Number:	72099
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	280799
AI Number:	72099
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	263811
AI Number:	72099
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	247248
AI Number:	72099
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	230804
AI Number:	72099
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	109721
Cert ID:	188914
AI Number:	72099
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188913
AI Number:	72099
Self Certification Date:	01/09/2012
Signature Name/Title:	CARLTON LABEFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	188912
AI Number:	72099
Self Certification Date:	04/01/2011
Signature Name/Title:	TARONZA L GRAVES REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188911
AI Number:	72099
Self Certification Date:	03/15/2010
Signature Name/Title:	TARONZA L GRAVES OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188910
AI Number:	72099
Self Certification Date:	03/27/2009
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	188909
AI Number:	72099
Self Certification Date:	03/26/2008
Signature Name/Title:	ADRIANNE RUTHERFORD OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188908
AI Number:	72099
Self Certification Date:	04/04/2007
Signature Name/Title:	HEATHER GILMORE AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188907
AI Number:	72099
Self Certification Date:	03/06/2006
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	188906
AI Number:	72099
Self Certification Date:	03/15/2005
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188905
AI Number:	72099
Self Certification Date:	03/12/2004
Signature Name/Title:	ERIC M. MCPHEE CMS PERMITTING MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188904
AI Number:	72099
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Self Cert ID:	109721
Cert ID:	188903
AI Number:	72099
Self Certification Date:	03/13/2002
Signature Name/Title:	WENDY SALAS PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	109721
Cert ID:	188902
AI Number:	72099
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	09/22/1998
Tank Registration Date:	06/11/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191003
Facility ID:	109721
Ai Number:	72099
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	09/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	12/04/1998

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	169734
UST ID:	191003
AI Number:	72099
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

7-ELEVEN STORE 36591 (Continued) **U003653044**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/22/1998

More Self Certification:

Self Cert ID:	27544
Cert ID:	302567
UST Comprt ID:	875056
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	286858
UST Comprt ID:	827752
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	337321
UST Comprt ID:	978767
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	336927

7-ELEVEN STORE 36591 (Continued) **U003653044**

UST Comprt ID:	977606
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	352316
UST Comprt ID:	1024348
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70762
UST Comprt ID:	203691
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70763
UST Comprt ID:	203690
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70764
UST Comprt ID:	203689
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70765
UST Comprt ID:	203688
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	370593
UST Comprt ID:	1079430
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70757
UST Comprt ID:	203694

7-ELEVEN STORE 36591 (Continued) **U003653044**

UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	320050
UST Comprt ID:	927109
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	269223
UST Comprt ID:	775612
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	253268
UST Comprt ID:	728291
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	235836
UST Comprt ID:	677005
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	219980
UST Comprt ID:	630496
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70758
UST Comprt ID:	203695
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70759
UST Comprt ID:	203696
UST ID:	73346

7-ELEVEN STORE 36591 (Continued) **U003653044**

AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70760
UST Comprt ID:	203693
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70761
UST Comprt ID:	203692
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70766
UST Comprt ID:	203687
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70767
UST Comprt ID:	203686
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70768
UST Comprt ID:	203685
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Install Date:	09/22/1998
Tank Registration Date:	06/11/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	191004
Facility ID:	109721
Ai Number:	72099
Tank Id:	2
Tank Status (Current):	IN USE

7-ELEVEN STORE 36591 (Continued) **U003653044**

Tank Status Date:	09/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	12/04/1998

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	169735
UST ID:	191004
AI Number:	72099
Compartment ID:	A

7-ELEVEN STORE 36591 (Continued) **U003653044**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/22/1998

More Self Certification:

Self Cert ID:	27544
Cert ID:	302567
UST Comprt ID:	875056
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	286858
UST Comprt ID:	827752
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	337321
UST Comprt ID:	978767
UST ID:	73346

7-ELEVEN STORE 36591 (Continued) **U003653044**

AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	336927
UST Comprt ID:	977606
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	352316
UST Comprt ID:	1024348
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70762
UST Comprt ID:	203691
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70763
UST Comprt ID:	203690
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70764
UST Comprt ID:	203689
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70765
UST Comprt ID:	203688
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	370593
UST Comprt ID:	1079430
UST ID:	73346
AI Number:	72099

7-ELEVEN STORE 36591 (Continued) **U003653044**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70757
UST Comprt ID:	203694
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	320050
UST Comprt ID:	927109
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	269223
UST Comprt ID:	775612
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	253268
UST Comprt ID:	728291
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	235836
UST Comprt ID:	677005
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	219980
UST Comprt ID:	630496
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70758
UST Comprt ID:	203695
UST ID:	73346
AI Number:	72099
Tank ID:	4

7-ELEVEN STORE 36591 (Continued) **U003653044**

Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70759
UST Comprt ID:	203696
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70760
UST Comprt ID:	203693
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70761
UST Comprt ID:	203692
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70766
UST Comprt ID:	203687
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70767
UST Comprt ID:	203686
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70768
UST Comprt ID:	203685
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Install Date:	09/22/1998
Tank Registration Date:	06/11/1999
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Pipe Type:	P
UST ID:	191005
Facility ID:	109721
Ai Number:	72099
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	09/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	12/04/1998

7-ELEVEN STORE 36591 (Continued) **U003653044**

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	169736
UST ID:	191005
AI Number:	72099
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	09/22/1998

More Self Certification:

Self Cert ID:	27544
Cert ID:	302567
UST Comprt ID:	875056
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	286858
UST Comprt ID:	827752
UST ID:	73346

7-ELEVEN STORE 36591 (Continued) **U003653044**

AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	337321
UST Comprt ID:	978767
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	336927
UST Comprt ID:	977606
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	352316
UST Comprt ID:	1024348
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70762
UST Comprt ID:	203691
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70763
UST Comprt ID:	203690
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70764
UST Comprt ID:	203689
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70765
UST Comprt ID:	203688
UST ID:	73346
AI Number:	72099

7-ELEVEN STORE 36591 (Continued) **U003653044**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	370593
UST Comprt ID:	1079430
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70757
UST Comprt ID:	203694
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	320050
UST Comprt ID:	927109
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	269223
UST Comprt ID:	775612
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	253268
UST Comprt ID:	728291
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	235836
UST Comprt ID:	677005
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	219980
UST Comprt ID:	630496
UST ID:	73346
AI Number:	72099
Tank ID:	4

7-ELEVEN STORE 36591 (Continued) **U003653044**

Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70758
UST Comprt ID:	203695
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70759
UST Comprt ID:	203696
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70760
UST Comprt ID:	203693
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70761
UST Comprt ID:	203692
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70766
UST Comprt ID:	203687
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70767
UST Comprt ID:	203686
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A
Self Cert ID:	27544
Cert ID:	70768
UST Comprt ID:	203685
UST ID:	73346
AI Number:	72099
Tank ID:	4
Compartment ID:	A

7-ELEVEN STORE 36591 (Continued) **U003653044**

Construction Notification:

NOC ID:	31284
Facility ID:	109721
AI Number:	72099
Application Received Date:	04/20/2017
Scheduled Construction Date:	05/14/2017
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	04/20/2017
Signature Date On Form:	04/14/2017
Signature Name On Form:	JUDY TRASKELL
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	DIESEL CONVERSION.

NOC ID:	18898
Facility ID:	109721
AI Number:	72099
Application Received Date:	04/12/2005
Scheduled Construction Date:	07/13/2005
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50412073
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	04/20/2017
Signature Date On Form:	04/14/2017
Signature Name On Form:	JUDY TRASKELL
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	4194

7-ELEVEN STORE 36591 (Continued) **U003653044**

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	74113
UST ID:	Not reported
NOC ID:	31284
AI Number:	72099
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C B & I
Representative Name:	JOHN RUFF
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	39258
UST ID:	191004
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280
Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	39257
UST ID:	191003
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280

7-ELEVEN STORE 36591 (Continued) **U003653044**

Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	39259
UST ID:	191005
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280
Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	74112
UST ID:	Not reported
NOC ID:	31284
AI Number:	72099
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	ACCOUNTING@MCCONBUILDING.COM
Cont/Cons/Installer ID:	20209
UST ID:	Not reported
NOC ID:	18898
AI Number:	72099
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000665
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	54422
UST ID:	191005
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000982
Company Name:	Not reported
Representative Name:	TERRENCE GREEN
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Cont/Cons/Installer ID:	54420
UST ID:	191003
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000982
Company Name:	Not reported
Representative Name:	TERRENCE GREEN
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	54421
UST ID:	191004
NOC ID:	Not reported
AI Number:	72099
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000982
Company Name:	Not reported
Representative Name:	TERRENCE GREEN
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

Facility ID:	109721
Additional ID:	658642402002175
Princ ID:	959578622001257
AI Number:	72099
Facility Name:	7-ELEVEN STORE 36591
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN #36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3218
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/12/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/17/2014
Date Routed by Supervisor:	03/18/2014
Date Routed to PSQA:	03/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported

7-ELEVEN STORE 36591 (Continued) **U003653044**

Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SPEEDY STOP
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/12/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.7
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/19/2013

7-ELEVEN STORE 36591 (Continued) **U003653044**

Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	279347
AI:	72099

7-ELEVEN STORE 36591 (Continued) **U003653044**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	262204
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	242278
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	02/14/0208

7-ELEVEN STORE 36591 (Continued) **U003653044**

Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	224730
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	207944
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591

7-ELEVEN STORE 36591 (Continued) **U003653044**

Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	189248
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	173475
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	154705
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

7-ELEVEN STORE 36591 (Continued) **U003653044**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	138258
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	118553
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401

7-ELEVEN STORE 36591 (Continued) **U003653044**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	120960
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	13722
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2

7-ELEVEN STORE 36591 (Continued) **U003653044**

Facility ID:	109721
Finass ID:	88482
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2012
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88483
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2011
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88484
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y

7-ELEVEN STORE 36591 (Continued) **U003653044**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88485
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88486
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No

7-ELEVEN STORE 36591 (Continued) **U003653044**

Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88487
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88488
AI:	72099
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	109721
Finass ID:	88489
AI:	72099

7-ELEVEN STORE 36591 (Continued) **U003653044**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	02/14/0208
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GS1851 **7-ELEVEN STORE 36591** **RCRA NonGen / NLR** **1004787945**
WNW **201 W BEN WHITE** **FINDS** **TXR000034892**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.038 mi.
199 ft. **Site 6 of 6 in cluster GS**

Actual:
666 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20140108
Handler Name:	Exxon Ras No 60135
Handler Address:	W BEN WHITE
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXR000034892
Contact Name:	ALDA S POOL
Contact Address:	1200 TIMBERLOCH PLACE
Contact City,State,Zip:	THE WOODLANDS, TX 77380
Contact Telephone:	281-296-3579
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	TIMBERLOCH PLACE
Mailing City,State,Zip:	THE WOODLANDS, TX 77380
Owner Name:	Exxon Mobil
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

7-ELEVEN STORE 36591 (Continued) **1004787945**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140109
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4999
Owner/Operator City,State,Zip:	THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone:	281-296-3655
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

7-ELEVEN STORE 36591 (Continued) **1004787945**

Owner/Operator Name: EXXON MOBIL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4999
Owner/Operator City,State,Zip: THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone: 281-296-3655
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000215
Handler Name: EXXON RAS NO 60135
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140108
Handler Name: EXXON RAS NO 60135
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005187458

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
TSCA SUBMITTER

7-ELEVEN STORE 36591 (Continued) **1004787945**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004787945
Registry ID:	110005187458
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005187458
Name:	7-ELEVEN STORE 36591
Address:	201 W BEN WHITE
City,State,Zip:	AUSTIN, TX 78704

JA1852 **ACC BOOK STORE** **TX LPST** **U001289681**
WNW **801 W 12TH ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.038 mi.
199 ft. **Site 5 of 15 in cluster JA**

Actual:
503 ft.

Focus Map:
11

LPST:

Name:	ACC BOOK STORE
Address:	801 W 12TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0060134
LPST Id:	104949
Facility Location:	801 WEST 12TH STREET
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/09/1992
Entered Date:	11/06/1992
Reported Date:	10/12/1992
Closure Date:	03/10/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	CHARLES HUMPHREYS
Responsible Party Address:	PO BOX 550
Responsible Party City,St,Zip:	AUSTIN, TX 78789
Responsible Party Telephone:	512/479-2672
Reported Date:	10/12/1992
Case Start Date:	03/10/1993

ACC BOOK STORE (Continued) **U001289681**

Reference Number: RN102409869
Project Manager: HWELCH

UST:

Name:	ACC BOOK STORE
Address:	801 W 12TH ST
City,State,Zip:	AUSTIN, TX 787011701
AI Number:	60134
Facility Type:	RETAIL
Facility Begin Date:	10/07/1991
Facility Status:	INACTIVE
Additional ID:	562848142002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	IRVIN HAMILTON,
Contact Organization Name:	ACC BOOK STORE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123278540
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/27/1991
Signature Name/Title On Earliest Reg Form:	C HAROLD MONTGOMERY,V.P.
Application Received Date On Earliest Reg Form:	09/30/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601243264
Owner Last Name:	TEXAS COMMERCE BANK-AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	177609202002150
Additional ID:	562848142002150

ACC BOOK STORE (Continued) **U001289681**

AI Number:	60134
Owner Effective Begin Date:	10/07/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/30/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	141563
Facility ID:	77533
Ai Number:	60134
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/06/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

ACC BOOK STORE (Continued) **U001289681**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	122667
UST ID:	141563
AI Number:	60134
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

ACC BOOK STORE (Continued) **U001289681**

Install Date:	08/31/1987
Tank Registration Date:	09/30/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	141564
Facility ID:	77533
Ai Number:	60134
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/06/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

ACC BOOK STORE (Continued) **U001289681**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	122668
UST ID:	141564
AI Number:	60134
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/30/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	141562

ACC BOOK STORE (Continued) **U001289681**

Facility ID:	77533
Ai Number:	60134
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/06/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	0

ACC BOOK STORE (Continued) **U001289681**

UST Comprt ID:	122666
UST ID:	141562
AI Number:	60134
Compartment ID:	A
Substance Stored1:	NEW OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS COMMERCE BANK AUSTIN
Contact Mailing Address (Delivery):	PO BOX 550
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 0550
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77533
Additional ID:	562848142002150
Princ ID:	177609202002150
AI Number:	60134
Facility Name:	ACC BOOK STORE
AR Number:	Not reported
AR UST Number Suffix:	Not reported

ACC BOOK STORE (Continued) **U001289681**

AR AST Number Suffix: Not reported
Contact Name/Title: /

JA1853 **W.T. CASWELL** **TX HIST UST** **S128729245**
WNW **801 W 12TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
199 ft. **Site 6 of 15 in cluster JA**

Actual:
503 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	W.T. CASWELL
Address:	801 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0326
HID UST:	326
Inspection:	03/26/2009
Due:	03/26/2012

JA1854 **LANE AUTO & ELECTRIC** **EDR Hist Auto** **1013754637**
WNW **801 12TH ST W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.038 mi.
199 ft. **Site 7 of 15 in cluster JA**

Actual:
503 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	FRYMIRE TEXACO SERVICE	GASOLINE STATIONS
1969	FRYMIRE L C	Gasoline Service Stations
1970	FRYMIRE L C	Gasoline Service Stations
1975	C & W FOREIGN CAR SERVICE	AUTOMOBILE REPAIRING
1980	LANE AUTO & ELECTRIC	AUTOMOBILE REPAIRING
1990	CAMPUS AUTOMOTIVE REPR	AUTOMOBILE REPAIRING

JA1855 **BILL'S ACC BOOKSTORE** **TX HIST UST** **S128729010**
WNW **801 W 12TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
199 ft. **Site 8 of 15 in cluster JA**

Actual:
503 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	BILL'S ACC BOOKSTORE
Address:	801 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0353
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

U1856
SE
< 1/8
0.038 mi.
200 ft.

BUSKES GARAGE
8609 LAMAR BLVD
AUSTIN, TX

EDR Hist Auto **1013765704**
N/A

Site 5 of 5 in cluster U

Actual:
686 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1953	BUSKES GARAGE	AUTOMOBILE REPAIRING

KR1857
ESE
< 1/8
0.038 mi.
201 ft.

FICKELS SERV STA
617 6TH W
AUSTIN, TX

EDR Hist Auto **1013772288**
N/A

Site 2 of 10 in cluster KR

Actual:
479 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	MAG PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	HARRELL SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	FICKELS SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	FICKELS SERVICE	GASOLINE STATIONS

KV1858
ESE
< 1/8
0.038 mi.
202 ft.

IMPORT CAR REPAIR
10631 LAMAR BLVD N
AUSTIN, TX 78753

EDR Hist Auto **1013760519**
N/A

Site 1 of 3 in cluster KV

Actual:
749 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1980	IMPORT CAR REPAIR	AUTOMOBILE REPAIRING
1980	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1982	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1983	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1984	IMPORT CAR REPAIR	AUTOMOBILE REPAIRING
1985	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1986	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1987	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1988	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1989	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1990	IMPORT CAR REPAIR INC	AUTOMOBILE REPAIRING
1990	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1991	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1992	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1993	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1994	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1995	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1996	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1997	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1998	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1999	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
2000	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
2001	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2002	AUSTIN AUTOMOTIVE	General Automotive Repair Shops

IMPORT CAR REPAIR (Continued) **1013760519**

2003	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2004	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2005	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2006	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2007	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2008	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2009	HOLLAND AUTOMOTIVE	Automotive Repair Shops, NEC
2009	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2010	HOLLAND AUTOMOTIVE	Automotive Repair Shops, NEC
2010	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2011	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2011	HOLLAND AUTOMOTIVE	Automotive Repair Shops, NEC
2012	HOLLAND AUTOMOTIVE	Automotive Repair Shops, NEC
2012	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2013	AUSTIN AUTOMOTIVE	General Automotive Repair Shops
2014	AUSTIN AUTOMOTIVE	General Automotive Repair Shops

KV1859 **IMPORT CAR REPAIR** **TX RDR** **S127528089**
ESE **10631 N LAMAR** **N/A**
< 1/8 **AUSTIN, TX**
0.038 mi.
202 ft. **Site 2 of 3 in cluster KV**

Actual:
749 ft.

Focus Map:
3

RDR:

RDR ID:	2856
Facility ID:	25401
RN:	Not reported
CN:	Not reported
Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/13/1999
Due Date:	11/12/1999
Tank Owner:	WMW ASSOCIATION
Contact Person:	ALVIE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	11/18/1999
Project Manager:	Brent Rice
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	APPROVED
Review Coordinator:	BJR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	11/18/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KV1860 **IMPORT CAR REPAIR** **TX UST** **U001259479**
ESE **10631 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX Ind. Haz Waste**
0.038 mi. **TX CENTRAL REGISTRY**
202 ft. **Site 3 of 3 in cluster KV**

Actual:
749 ft.

Focus Map:
3

UST:

Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533461
AI Number:	25401
Facility Type:	Not reported
Facility Begin Date:	10/08/1986
Facility Status:	INACTIVE
Additional ID:	581654322002205
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	IMPORT CAR REPAIR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128352990
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	ALVIE WEED,TREASURER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600307904
Owner Last Name:	IMPORT CAR REPAIR INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	599432392001297
Additional ID:	581654322002205

IMPORT CAR REPAIR (Continued) **U001259479**

AI Number:	25401
Owner Effective Begin Date:	10/08/1986
State Tax ID:	17418529818
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	300
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	65241
Facility ID:	62043
Ai Number:	25401
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/14/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

IMPORT CAR REPAIR (Continued) **U001259479**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	300
UST Comprt ID:	80157
UST ID:	65241
AI Number:	25401
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

IMPORT CAR REPAIR (Continued) **U001259479**

Facility Billing Contacts:

Contact Organization Name:	IMPORT CAR REPAIR INC
Contact Mailing Address (Delivery):	10631 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3461
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	62043
Additional ID:	581654322002205
Princ ID:	599432392001297
AI Number:	25401
Facility Name:	IMPORT CAR REPAIR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ALVIE WEED JR/

HIST UST AUSTIN:

Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0681
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61222
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	10631 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS

IMPORT CAR REPAIR (Continued) **U001259479**

Company Name:	IMPORT CAR REPAIR INC
Contact Name:	ALVIE WEED JR
Contact Telephone Number:	512-8352990
Mailing Address:	10631 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787533461
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19581
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060622
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	IMPORT CAR REPAIR INC
Operator Address:	10631 NLAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8352990
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17418529818
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	IMPORT CAR REPAIR INC
Owner Mailing Address:	10631 NLAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8352990
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17418529818
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported

IMPORT CAR REPAIR (Continued) **U001259479**

Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	10631 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8352990
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	10631 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8352990
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALVIE WEED JR
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	10631 NLAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8352990
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100598101
Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3461
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600307904
Customer Name:	IMPORT CAR REPAIR INC
Customer Legal Name:	Import Car Repair, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10631 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100598101
Name:	IMPORT CAR REPAIR
Address:	10631 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-3461

IMPORT CAR REPAIR (Continued) **U001259479**

Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600307904
Customer Name:	IMPORT CAR REPAIR INC
Customer Legal Name:	Import Car Repair, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	10631 N Lamar Blvd, Austin, TX

1861 WNW < 1/8 0.038 mi. 202 ft. **GEORGES WAGON WORKS** **TX UST** **U001279361**
1311 S 1ST ST **TX HIST UST** **N/A**
AUSTIN, TX 78704

Actual: 502 ft.

Focus Map: 14

UST:

Name:	GEORGES WAGON WORKS
Address:	1311 S 1ST ST
City,State,Zip:	AUSTIN, TX 787043038
AI Number:	48177
Facility Type:	UNKNOWN
Facility Begin Date:	04/12/1989
Facility Status:	INACTIVE
Additional ID:	692795742002057
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	IRA MOORE,OWNER
Contact Organization Name:	GEORGES WAGON WORKS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123276552
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/31/1988
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	04/04/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600787451
Owner Last Name:	MOORE
Owner First Name:	IRA

GEORGES WAGON WORKS (Continued) **U001279361**

Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	682795732002057
Additional ID:	692795742002057
AI Number:	48177
Owner Effective Begin Date:	04/12/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1968
Tank Registration Date:	04/04/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125468
Facility ID:	79851
Ai Number:	48177
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/21/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

GEORGES WAGON WORKS (Continued) **U001279361**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	111975
UST ID:	125468
AI Number:	48177
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

GEORGES WAGON WORKS (Continued) **U001279361**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MOORE IRA
Contact Mailing Address (Delivery):	300 VALE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 5729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79851
Additional ID:	692795742002057
Princ ID:	682795732002057
AI Number:	48177
Facility Name:	GEORGES WAGON WORKS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	GEORGES WAGON WORKS
Address:	1311 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0103
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KW1862 **PERRY BROOKS BLDG** **TX LPST** **U001291893**
ESE **720 BRAZOS ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX HIST UST**
0.038 mi. **TX ASBESTOS**
203 ft. **Site 1 of 5 in cluster KW**

Actual:
508 ft.

Focus Map:
11

LPST:

Name:	BROOKS PERRY PARKING GARAGE
Address:	720 BRAZOS ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0062765
LPST Id:	101630

PERRY BROOKS BLDG (Continued) **U001291893**

Facility Location:	720 BRAZOS ST @ E 7TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/30/1991
Entered Date:	01/31/1992
Reported Date:	01/14/1992
Closure Date:	01/10/1995
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	CHARLES MORRISON
Responsible Party Address:	720 BRAZOS ST STE 1006
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	/-
Reported Date:	01/14/1992
Case Start Date:	01/10/1995
Reference Number:	RN101494144
Project Manager:	HWELCH

UST:

Name:	PERRY BROOKS BLDG
Address:	720 BRAZOS ST
City,State,Zip:	AUSTIN, TX 787013251
AI Number:	62765
Facility Type:	RETAIL
Facility Begin Date:	04/06/1992
Facility Status:	INACTIVE
Additional ID:	539648022002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	CHARLES MORRISON,
Contact Organization Name:	PERRY BROOKS BLDG
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124787332
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/01/1992
Signature Name/Title On Earliest Reg Form:	CHARLES MORRISON,
Application Received Date On Earliest Reg Form:	04/02/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported

PERRY BROOKS BLDG (Continued) **U001291893**

Facility Not Inspectable:	No

Owner:

Owner CN:	CN600782189
Owner Last Name:	AUSTIN PERRY BROOKS LTDE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	529648012002053
Additional ID:	539648022002053
AI Number:	62765
Owner Effective Begin Date:	04/06/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/02/1992
Number of Compartments:	1
Tank Capacity:	575
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145275
Facility ID:	93269
Ai Number:	62765
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	10/29/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

PERRY BROOKS BLDG (Continued) **U001291893**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	139014
UST ID:	145275
AI Number:	62765
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

PERRY BROOKS BLDG (Continued) **U001291893**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	04/02/1992
Number of Compartments:	1
Tank Capacity:	575
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145276
Facility ID:	93269
Ai Number:	62765
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	10/29/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

PERRY BROOKS BLDG (Continued) **U001291893**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	139015
UST ID:	145276
AI Number:	62765
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

PERRY BROOKS BLDG (Continued) **U001291893**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	04/02/1992
Number of Compartments:	1
Tank Capacity:	575
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145277
Facility ID:	93269
Ai Number:	62765
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	10/29/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

PERRY BROOKS BLDG (Continued) **U001291893**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	139016
UST ID:	145277
AI Number:	62765
Compartment ID:	A
Substance Stored1:	KEROSENE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

PERRY BROOKS BLDG (Continued) **U001291893**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	08/31/1987
Tank Registration Date:	04/02/1992
Number of Compartments:	1
Tank Capacity:	575
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145278
Facility ID:	93269
Ai Number:	62765
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	10/29/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

PERRY BROOKS BLDG (Continued) **U001291893**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	139017
UST ID:	145278
AI Number:	62765
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUSTIN PERRY BROOKS LTDE

PERRY BROOKS BLDG (Continued) **U001291893**

Contact Mailing Address (Delivery):	720 BRAZOS ST STE 900
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2565
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93269
Additional ID:	539648022002053
Princ ID:	529648012002053
AI Number:	62765
Facility Name:	PERRY BROOKS BLDG
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHARLES MORRISON/

HIST UST AUSTIN:

Name:	PERRY-BROOKS BLDG
Address:	720 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0518
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	CROSSOVER HEALTH MANAGEMENT
Address:	720 BRAZOS STREET SUITE B700
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erin M Oppermann
Violation:	Not reported
Complaint Date:	09/30/2022
Notification Number:	2022005975
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/26/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

PERRY BROOKS BLDG (Continued) **U001291893**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/26/2022
Certification Statement Phone:	817-266-3774
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	16
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/27/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CROSSOVER HEALTH MANAGEMENT
Address:	720 BRAZOS STREET SUITE B700
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Erin Oppermann
Violation:	Not reported
Complaint Date:	09/30/2022
Notification Number:	2022005975
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

PERRY BROOKS BLDG (Continued) **U001291893**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/12/2022
Certification Statement Phone:	512-705-2130
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	16
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/26/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BE1863 **31ST ST GARAGE** **TX Ind. Haz Waste** **S102748721**
WNW **609 W 31ST ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.039 mi.
204 ft. **Site 12 of 13 in cluster BE**

Actual:
592 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	31ST ST GARAGE
Address:	609 W 31ST ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	61879
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	609 W 31st St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	31ST ST GARAGE
Contact Name:	MR RIND
Contact Telephone Number:	Not reported
Mailing Address:	609 W 31ST ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787052211
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20218
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030102
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

31ST ST GARAGE (Continued) **S102748721**

Ind. Haz Waste:

Operator Name:	31ST ST GARAGE
Operator Address:	609 W 31ST ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	31ST ST GARAGE
Owner Mailing Address:	609 W 31ST ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	609 W 31ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	609 W 31ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MR RIND
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	609 W 31ST ST
Contact Address 2:	Not reported

31ST ST GARAGE (Continued) **S102748721**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100636067
Name:	31ST ST GARAGE
Address:	609 W 31ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2211
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346688
Customer Name:	31ST ST GARAGE
Customer Legal Name:	31st St Garage
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	609 W 31st St, Austin, TX

BE1864 **CARLSONS GARAGE** **EDR Hist Auto** **1013759617**
WNW **609 31ST ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.039 mi.
204 ft. **Site 13 of 13 in cluster BE**

Actual:
592 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1965	CARLSONS GARAGE GL	AUTOMOBILE REPAIRING
1969	CARLSON DAVE GARAGE	General Automotive Repair Shops
1969	CARLSONS GARAGE	General Automotive Repair Shops
1970	CARLISONS GARAGE	AUTOMOBILE REPAIRING
1970	CARLSON DAVE GARAGE	General Automotive Repair Shops
1970	CARLSONS GARAGE	General Automotive Repair Shops
1971	CARLSON DAVE GARAGE	General Automotive Repair Shops
1971	CARLSONS GARAGE	General Automotive Repair Shops
1972	CARLSONS GARAGE	General Automotive Repair Shops
1972	CARLSON DAVE GARAGE	General Automotive Repair Shops
1973	CARLSON DAVE GARAGE	General Automotive Repair Shops
1973	CARLSONS GARAGE	General Automotive Repair Shops
1974	CARLSON DAVE GARAGE	General Automotive Repair Shops
1974	CARLSONS GARAGE	General Automotive Repair Shops
1975	CARLSONS GARAGE	AUTOMOBILE REPAIRING
1975	CARLSON DAVE GARAGE	General Automotive Repair Shops
1975	CARLSONS GARAGE	General Automotive Repair Shops
1976	CARLSON DAVE GARAGE	General Automotive Repair Shops
1980	CARLSONS GARAGE	AUTOMOBILE REPAIRING

KX1865 **7 ELEVEN STORE 19097** **TX RDR** **S126054788**
ENE **1705 S LAKESHORE BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.039 mi.
204 ft. **Site 1 of 5 in cluster KX**

Actual:
465 ft.

Focus Map:
14

RDR:

RDR ID:	27102
Facility ID:	7143
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/18/2019
Due Date:	8/17/2019
Tank Owner:	7 ELEVEN INC
Contact Person:	SHELLENA HUSSEIN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/19/2019
Project Manager:	Ryan Kraft
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	4/28/2002
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/1/1977
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226

7 ELEVEN STORE 19097 (Continued) **S126054788**

Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329

7 ELEVEN STORE 19097 (Continued) **S126054788**

Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION

7 ELEVEN STORE 19097 (Continued) **S126054788**

Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102057189
Name:	7 ELEVEN STORE 19097
Address:	1705 S LAKESHORE BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-1226
Status:	ACTIVE
Status Date:	2002-04-28
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1977-04-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

KX1866 **7-ELEVEN 19097** **TX UST** **U001243566**
ENE **1705 S LAKESHORE BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX ASBESTOS**
0.039 mi. **TX Financial Assurance**
204 ft. **Site 2 of 5 in cluster KX**

Actual:
465 ft.

Focus Map:
14

UST:

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 787411226
AI Number:	7143
Facility Type:	RETAIL

7-ELEVEN 19097 (Continued) **U001243566**

Facility Begin Date:	04/01/1977
Facility Status:	INACTIVE
Additional ID:	364418012002118
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78746
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/2019
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,REG COMP MGR
Application Received Date On Earliest Reg Form:	04/30/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	364418012002118
Ai Number:	7143
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC

7-ELEVEN 19097 (Continued) **U001243566**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	364418012002118
AI Number:	7143
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46147
Cert ID:	314252
AI Number:	7143
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	296476
AI Number:	7143
Self Certification Date:	12/28/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	280944
AI Number:	7143
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	263737
AI Number:	7143
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	246996
AI Number:	7143
Self Certification Date:	01/16/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	230067
AI Number:	7143
Self Certification Date:	01/13/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46147
Cert ID:	27175
AI Number:	7143
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	27174
AI Number:	7143
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	27173
AI Number:	7143
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26935
AI Number:	7143
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26934
AI Number:	7143
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46147
Cert ID:	26933
AI Number:	7143
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46147
Cert ID:	26932
AI Number:	7143
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46147
Cert ID:	26931
AI Number:	7143
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26930
AI Number:	7143
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MANANGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26929
AI Number:	7143
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26928
AI Number:	7143
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26927
AI Number:	7143
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46147
Cert ID:	26926
AI Number:	7143
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18514
Facility ID:	46147
Ai Number:	7143
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2019

7-ELEVEN 19097 (Continued) **U001243566**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	25978
UST ID:	18514
AI Number:	7143
Compartment ID:	A
Substance Stored1:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18515
Facility ID:	46147
Ai Number:	7143
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 19097 (Continued) **U001243566**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	25979
UST ID:	18515
AI Number:	7143
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

7-ELEVEN 19097 (Continued) **U001243566**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18516
Facility ID:	46147
Ai Number:	7143
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

7-ELEVEN 19097 (Continued) **U001243566**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	25980
UST ID:	18516
AI Number:	7143
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y

7-ELEVEN 19097 (Continued) **U001243566**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	34320
Facility ID:	46147
AI Number:	7143
Application Received Date:	03/07/2019
Scheduled Construction Date:	04/15/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	03/07/2019
Signature Date On Form:	03/07/2019
Signature Name On Form:	ANTHONY LEWIS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL OF 3-10K SW STEEL UST'S DISPENSERS AND LINES.

NOC ID:	27048
Facility ID:	46147
AI Number:	7143
Application Received Date:	01/28/2015
Scheduled Construction Date:	03/30/2015
UST Improvement:	N
UST Installation:	N

7-ELEVEN 19097 (Continued) **U001243566**

UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	03/07/2019
Signature Date On Form:	03/07/2019
Signature Name On Form:	ANTHONY LEWIS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL AND DISPOSAL OF THREE (3) 10,000-GALLON STEEL USTS; PIPING, VENTS AND DISPENSERS.

NOC ID:	2487
Facility ID:	46147
AI Number:	7143
Application Received Date:	05/17/2006
Scheduled Construction Date:	05/30/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60517005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	03/07/2019
Signature Date On Form:	03/07/2019
Signature Name On Form:	ANTHONY LEWIS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	63318
UST ID:	Not reported
NOC ID:	27048
AI Number:	7143

7-ELEVEN 19097 (Continued) **U001243566**

Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CB&I ENVIRONMENTAL & INFRASTRUCTURE INC
Representative Name:	HOLLY M FLAHERTY
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738413
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	7738400
Email Address:	Not reported

Cont/Cons/Installer ID:	81396
UST ID:	Not reported
NOC ID:	34320
AI Number:	7143
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	APTIM
Representative Name:	MONIKA URGRINSKA
Mailing Address (Delivery):	1250 CAPITOL OF TEXAS HWY BLDG 3 STE 400
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3292041
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2746
UST ID:	Not reported
NOC ID:	2487
AI Number:	7143
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	81398
UST ID:	Not reported
NOC ID:	34320
AI Number:	7143
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PRESTIGE TANK AND PUMP SERVICES INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 170398
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3105611
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3105610
Email Address:	Not reported

Cont/Cons/Installer ID:	81397
UST ID:	Not reported
NOC ID:	34320
AI Number:	7143
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	LEWIS ANTHONY DON
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 170398
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78717
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3105611
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3105610

7-ELEVEN 19097 (Continued) **U001243566**

Email Address: Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46147
Additional ID:	364418012002118
Princ ID:	959578622001257
AI Number:	7143
Facility Name:	7-ELEVEN 19097
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1137
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/27/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.4
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/03/2013
Date Routed by Supervisor:	04/03/2013
Date Routed to PSQA:	04/04/2013

7-ELEVEN 19097 (Continued) **U001243566**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	207918
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 19097 (Continued) **U001243566**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	189227
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	173784
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported

7-ELEVEN 19097 (Continued) **U001243566**

Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	172708
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	154050
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741

7-ELEVEN 19097 (Continued) **U001243566**

Region:	2
Facility ID:	46147
Finass ID:	138239
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	120375
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	1522
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN 19097 (Continued) **U001243566**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28245
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28246
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011

7-ELEVEN 19097 (Continued) **U001243566**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28247
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28248
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28476

7-ELEVEN 19097 (Continued) **U001243566**

AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	46147
Finass ID:	28477
AI:	7143
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	04/30/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

KX1867 **7 ELEVEN STORE NO 19097** **TX RDR** **S127538654**
ENE **1705 S LAKESHORE BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.039 mi.
204 ft. **Site 3 of 5 in cluster KX**

Actual:
465 ft.

Focus Map:
14

RDR:

RDR ID:	15437
Facility ID:	7143
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE NO 19097
Address:	1705 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/5/2007
Due Date:	6/4/2007

7 ELEVEN STORE NO 19097 (Continued) **S127538654**

Tank Owner:	7 ELEVEN INC
Contact Person:	RON FULENCHEK
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	6/29/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#? REC TECH RESP 9/18/2006; REC TECH RESP 04/05/07
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	6/29/2007
Region:	Not reported
DKC RDR (misfiled):	Not reported

1868 West < 1/8 0.039 mi. 204 ft. **FIRST NATIONAL BANK OF YORKTOWN** **TX LPST** **U003566376**
12800 N LAMAR BLVD **TX UST** **N/A**
AUSTIN, TX 78753 **TX HIST UST**

Actual: 717 ft.
Focus Map: 2

LPST:

Name:	VACANT BUILDING
Address:	12800 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0058316
LPST Id:	098946
Facility Location:	N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/13/1991
Entered Date:	05/15/1991
Reported Date:	05/14/1991
Closure Date:	08/21/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	LOU GIPPS
Responsible Party Address:	PO BOX 185
Responsible Party City,St,Zip:	YORKTOWN, TX 78164
Responsible Party Telephone:	512/564-4242
Reported Date:	05/14/1991
Case Start Date:	08/21/1991
Reference Number:	RN104350392
Project Manager:	HWELCH

UST:

FIRST NATIONAL BANK OF YORKTOWN (Continued) **U003566376**

Name:	FIRST NATIONAL BANK OF YORKTOWN
Address:	12800 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787531102
AI Number:	58316
Facility Type:	UNKNOWN
Facility Begin Date:	05/21/1991
Facility Status:	INACTIVE
Additional ID:	208607612004211
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	LOU GIPPS,
Contact Organization Name:	FIRST NATIONAL BANK OF YORKTOWN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5125644242
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/14/1991
Signature Name/Title On Earliest Reg Form:	GREG BLOMQUIST,V.P.
Application Received Date On Earliest Reg Form:	05/17/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602673477
Owner Last Name:	FIRST NATIONAL BANK OF YORKTOWN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	193607602004211
Additional ID:	208607612004211
AI Number:	58316
Owner Effective Begin Date:	05/21/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/

FIRST NATIONAL BANK OF YORKTOWN (Continued) **U003566376**

Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/17/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	139270
Facility ID:	81968
Ai Number:	58316
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/07/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

FIRST NATIONAL BANK OF YORKTOWN (Continued) **U003566376**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	132607
UST ID:	139270
AI Number:	58316
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FIRST NATIONAL BANK OF YORKTOWN
Contact Mailing Address (Delivery):	PO BOX 185
Contact Mailing Address (Internal Delivery):	Not reported

FIRST NATIONAL BANK OF YORKTOWN (Continued) **U003566376**

Contact Mailing City/State/Zip:	YORKTOWN, TX 78164 0185
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	81968
Additional ID:	208607612004211
Princ ID:	193607602004211
AI Number:	58316
Facility Name:	FIRST NATIONAL BANK OF YORKTOWN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	LOU GIPPS/

HIST UST AUSTIN:

Name:	PROPOSED APARTMENT COMPLEX
Address:	12800 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0648
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KY1869 **HAMS AUTO SERV** **EDR Hist Auto** **1013757491**
ESE **310 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.039 mi.
204 ft. **Site 1 of 21 in cluster KY**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	HAMS AUTO SERV	AUTOMOBILE REPAIRING

KW1870 **WILLIE FOO CHINESE LAUNDRY** **EDR Hist Cleaner** **1013787481**
ESE **113 E 8TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.039 mi.
205 ft. **Site 2 of 5 in cluster KW**

Actual:
510 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1901	WILLIE FOO CHINESE LAUNDRY	LAUNDRIES

JP1871 SSW < 1/8 0.039 mi. 205 ft. — **FOSTERS GARAGE**, **504 BRAZOS ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013757008** / **N/A**

Site 4 of 27 in cluster JP

Actual: 487 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1935	FOSTERS GARAGE	AUTOMOBILE GARAGES
1935	FOSTERS GARAGE	AUTOMOBILE REPAIRERS
1940	FOSTERS GARAGE	AUTOMOBILE REPAIRING

KZ1872 WNW < 1/8 0.039 mi. 206 ft. — **WALTER JOHNSON**, **1207 S 1ST ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678857** / **N/A**

Site 1 of 4 in cluster KZ

Actual: 495 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	WALTER JOHNSON
Address:	1207 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0960
HID UST:	960
Inspection:	Not reported
Due:	06/01/2012

KH1873 SSW < 1/8 0.039 mi. 206 ft. — **206-214 CONGRESS AVE**, **206 CONGRESS AVE**, **AUSTIN, TX 78701** — **TX UST**, **TX HIST UST** — **U003768492** / **N/A**

Site 5 of 19 in cluster KH

Actual: 476 ft.

Focus Map: 11

UST:

Name:	206-214 CONGRESS AVE
Address:	206 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787014022
AI Number:	63160
Facility Type:	Not reported
Facility Begin Date:	06/17/1992
Facility Status:	INACTIVE
Additional ID:	859612182002155
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	206-214 CONGRESS
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

206-214 CONGRESS AVE (Continued) **U003768492**

Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/11/1992
Signature Name/Title On Earliest Reg Form:	KEVIN NUNNINK,ASSET MANAGER
Application Received Date On Earliest Reg Form:	06/15/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601265226
Owner Last Name:	RTC REC FIRST FED ESTHERVILLE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	867612182002155
Additional ID:	859612182002155
AI Number:	63160
Owner Effective Begin Date:	06/17/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	06/15/1992
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145978
Facility ID:	94024
Ai Number:	63160
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

206-214 CONGRESS AVE (Continued) **U003768492**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/01/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	9999
UST Comprt ID:	161175
UST ID:	145978
AI Number:	63160
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

206-214 CONGRESS AVE (Continued) **U003768492**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24555
Cert ID:	289546
UST Comprt ID:	835940
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	305149
UST Comprt ID:	882896
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	339950
UST Comprt ID:	987027
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	355134

206-214 CONGRESS AVE (Continued) **U003768492**

UST Comprt ID:	1032821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	372275
UST Comprt ID:	1084438
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64114
UST Comprt ID:	180177
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64115
UST Comprt ID:	180178
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64116
UST Comprt ID:	180179
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64117
UST Comprt ID:	180180
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64118
UST Comprt ID:	180176
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64119
UST Comprt ID:	180175

206-214 CONGRESS AVE (Continued) **U003768492**

UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64120
UST Comprt ID:	180174
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64121
UST Comprt ID:	180173
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64122
UST Comprt ID:	180172
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64123
UST Comprt ID:	180171
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64124
UST Comprt ID:	180170
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64125
UST Comprt ID:	180169
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64126
UST Comprt ID:	180168
UST ID:	62286

206-214 CONGRESS AVE (Continued) **U003768492**

AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	220399
UST Comprt ID:	631821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	236507
UST Comprt ID:	678955
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	253702
UST Comprt ID:	729557
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	270472
UST Comprt ID:	779111
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	322373
UST Comprt ID:	934059
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	06/15/1992
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145979
Facility ID:	94024
Ai Number:	63160
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND

206-214 CONGRESS AVE (Continued) **U003768492**

Tank Status Date:	12/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/01/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	9999
UST Comprt ID:	161176
UST ID:	145979
AI Number:	63160
Compartment ID:	A

206-214 CONGRESS AVE (Continued) **U003768492**

Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24555
Cert ID:	289546
UST Comprt ID:	835940
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	305149
UST Comprt ID:	882896
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	339950
UST Comprt ID:	987027
UST ID:	62286

206-214 CONGRESS AVE (Continued) **U003768492**

AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	355134
UST Comprt ID:	1032821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	372275
UST Comprt ID:	1084438
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64114
UST Comprt ID:	180177
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64115
UST Comprt ID:	180178
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64116
UST Comprt ID:	180179
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64117
UST Comprt ID:	180180
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64118
UST Comprt ID:	180176
UST ID:	62286
AI Number:	63160

206-214 CONGRESS AVE (Continued) **U003768492**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64119
UST Comprt ID:	180175
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64120
UST Comprt ID:	180174
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64121
UST Comprt ID:	180173
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64122
UST Comprt ID:	180172
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64123
UST Comprt ID:	180171
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64124
UST Comprt ID:	180170
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64125
UST Comprt ID:	180169
UST ID:	62286
AI Number:	63160
Tank ID:	1

206-214 CONGRESS AVE (Continued) **U003768492**

Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64126
UST Comprt ID:	180168
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	220399
UST Comprt ID:	631821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	236507
UST Comprt ID:	678955
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	253702
UST Comprt ID:	729557
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	270472
UST Comprt ID:	779111
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	322373
UST Comprt ID:	934059
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	06/15/1992
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	N
Tank Doublewall:	N

206-214 CONGRESS AVE (Continued) **U003768492**

Pipe Type:	Not reported
UST ID:	145980
Facility ID:	94024
Ai Number:	63160
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/01/1992

206-214 CONGRESS AVE (Continued) **U003768492**

Compartment Records:

Tank ID:	1
Tank Capacity:	9999
UST Comprt ID:	161177
UST ID:	145980
AI Number:	63160
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24555
Cert ID:	289546
UST Comprt ID:	835940
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	305149
UST Comprt ID:	882896
UST ID:	62286

206-214 CONGRESS AVE (Continued) **U003768492**

AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	339950
UST Comprt ID:	987027
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	355134
UST Comprt ID:	1032821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	372275
UST Comprt ID:	1084438
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64114
UST Comprt ID:	180177
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64115
UST Comprt ID:	180178
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64116
UST Comprt ID:	180179
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64117
UST Comprt ID:	180180
UST ID:	62286
AI Number:	63160

206-214 CONGRESS AVE (Continued) **U003768492**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64118
UST Comprt ID:	180176
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64119
UST Comprt ID:	180175
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64120
UST Comprt ID:	180174
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64121
UST Comprt ID:	180173
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64122
UST Comprt ID:	180172
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64123
UST Comprt ID:	180171
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64124
UST Comprt ID:	180170
UST ID:	62286
AI Number:	63160
Tank ID:	1

206-214 CONGRESS AVE (Continued) **U003768492**

Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64125
UST Comprt ID:	180169
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	64126
UST Comprt ID:	180168
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	220399
UST Comprt ID:	631821
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	236507
UST Comprt ID:	678955
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	253702
UST Comprt ID:	729557
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	270472
UST Comprt ID:	779111
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24555
Cert ID:	322373
UST Comprt ID:	934059
UST ID:	62286
AI Number:	63160
Tank ID:	1
Compartment ID:	A

206-214 CONGRESS AVE (Continued) **U003768492**

Facility Billing Contacts:

Contact Organization Name:	RTC REC FIRST FED ESTHERVILLE
Contact Mailing Address (Delivery):	1901 W 47TH PL
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	WESTWOOD, KS 66205 1805
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94024
Additional ID:	859612182002155
Princ ID:	867612182002155
AI Number:	63160
Facility Name:	206-214 CONGRESS AVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOHN WOOD/

HIST UST AUSTIN:

Name:	VACANT LOT
Address:	206 CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0410
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KH1874 **FORMER RTC PROPERTY** **TX LPST** **S116696168**
SSW **206 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.039 mi.
206 ft. **Site 6 of 19 in cluster KH**

Actual:
476 ft.

Focus Map:
11

LPST:

Name:	FORMER RTC PROPERTY
Address:	206 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0063160
LPST Id:	103123
Facility Location:	200 NORTH CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/23/1992
Entered Date:	06/09/1992
Reported Date:	05/18/1992
Closure Date:	07/18/2000
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6P - FINAL PENDING WELL PLUG
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING**
Coordinators Primary:	1/2
Coordinators RPR:	ZL
Responsible Party Name:	Not reported

FORMER RTC PROPERTY (Continued) **S116696168**

Responsible Party Contact:	STUART SHAW
Responsible Party Address:	200 COLORADO ST
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/476-9559
Reported Date:	05/18/1992
Case Start Date:	07/18/2000
Reference Number:	RN102451283
Project Manager:	ZLI

HA1875 **A 1 AUTO ELECTRIC AUTOMOBILE REPR** **EDR Hist Auto** **1013765067**
WNW **4408 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.039 mi.
206 ft. **Site 4 of 4 in cluster HA**

Actual:
649 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1990	A 1 AUTO ELECTRIC AUTOMOBILE RE	AUTOMOBILE REPAIRING
1990	A ONE AUTO ELECTRIC	Automotive Repair Shops, NEC
1991	A ONE AUTO ELECTRIC	Automotive Repair Shops, NEC
1992	A ONE AUTO ELECTRIC	Automotive Repair Shops, NEC
1993	A ONE AUTO ELECTRIC	Automotive Repair Shops, NEC
1994	A ONE AUTO ELECTRIC	Automotive Repair Shops, NEC
1995	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
1996	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
1997	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
1998	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
1999	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2000	A ONE AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2001	AUSTIN A-1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2002	AUSTIN A-1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2003	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2004	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2005	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2006	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2007	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2008	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2009	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2010	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2011	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2012	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2013	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC
2014	AUSTIN A1 AUTO ELECTRIC INC	Automotive Repair Shops, NEC

LA1876 **COMPTROLLER OF PUBLIC ACCOUNTS** **TX Ind. Haz Waste** **S105479935**
West **111 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.039 mi.
207 ft. **Site 1 of 15 in cluster LA**

Actual:
493 ft.

Ind. Haz Waste:

Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported

Focus Map:
11

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479935**

Registration Number:	72461
Registration Initial Notification Date:	05/08/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981914948
Primary NAICS Code:	Not reported
Status Change Date:	19870508
Land Type:	Not reported
Description of Facility Site Location:	111 W 6th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Contact Name:	GILLMORE KRUEGER
Contact Telephone Number:	512-4634112
Mailing Address:	111 E 17TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787740001
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26901
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Operator Address:	111 E 17TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78774
Operator Country:	UNITED STA
Operator Telephone:	1-512-4634112
Operator Fax Number:	Not reported
Operator Email:	Not reported

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **S105479935**

Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Owner Mailing Address:	111 E 17TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78774
Owner Country:	UNITED STA
Owner Telephone:	1-512-4634112
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	111 E 17TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Phone:	1-512-4634112
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	111 E 17TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Phone:	1-512-4634112
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	GILLMORE KRUEGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	111 E 17TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Phone:	1-512-4634112
Contact Fax:	Not reported
Contact Email:	Not reported

LA1877 **COMPTROLLER OF PUBLIC ACCOUNTS** **RCRA NonGen / NLR** **1000156810**
West **111 W 6TH ST** **FINDS** **TXD981914948**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.039 mi.
207 ft. **Site 2 of 15 in cluster LA**

Actual:
493 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Comptroller Of Public Accounts
Handler Address:	W 6TH ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981914948
Contact Name:	GILLMORE KRUEGER
Contact Address:	E 17TH ST
Contact City,State,Zip:	AUSTIN, TX 78774
Contact Telephone:	512-463-4112
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E 17TH ST
Mailing City,State,Zip:	AUSTIN, TX 78774
Owner Name:	Comptroller Of Public Accounts
Owner Type:	Municipal
Operator Name:	Comptroller Of Public Accounts
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000156810**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D011
Waste Description:	Silver

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: COMPTROLLER OF PUBLIC ACCOUNTS	
Legal Status:	Municipal
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	111 E 17TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78774
Owner/Operator Telephone:	512-463-4112
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE OF TEXAS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000156810**

Owner/Operator Name: COMPTROLLER OF PUBLIC ACCOUNTS
Legal Status: Municipal
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 111 E 17TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78774
Owner/Operator Telephone: 512-463-4112
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870515
Handler Name: TEXAS COMPTROLLER TAX PUBS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: COMPTROLLER OF PUBLIC ACCOUNTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005100372

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

COMPTROLLER OF PUBLIC ACCOUNTS (Continued) **1000156810**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000156810
Registry ID:	110005100372
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005100372
Name:	COMPTROLLER OF PUBLIC ACCOUNTS
Address:	111 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701

LB1878 **SUPERIOR DAIRIES** **TX LPST** **U001264578**
WNW **600 E 1ST ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX HIST UST**
0.039 mi.
207 ft. **Site 1 of 9 in cluster LB**

Actual:
460 ft.

Focus Map:
11

LPST:

Name:	SUPERIOR DAIRIES
Address:	600 E 1ST ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0031210
LPST Id:	093871
Facility Location:	213 RED RIVER @ 2ND ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/29/1989
Entered Date:	11/01/1989
Reported Date:	09/29/1989
Closure Date:	06/24/1991
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE ABERNATHY
Responsible Party Address:	PO BOX 7580
Responsible Party City,St,Zip:	AUSTIN, TX 78713
Responsible Party Telephone:	512/471-5050
Reported Date:	09/29/1989
Case Start Date:	06/24/1991
Reference Number:	RN102715166
Project Manager:	REGION

UST:

Name:	SUPERIOR DAIRIES
Address:	600 E 1ST ST
City,State,Zip:	AUSTIN, TX 787014122
AI Number:	31210

SUPERIOR DAIRIES (Continued) **U001264578**

Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	11/10/1986
Facility Status:	INACTIVE
Additional ID:	148440462002186
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	SUPERIOR DAIRIES
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124760683
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/07/1986
Signature Name/Title On Earliest Reg Form:	THOMAS HEATON,ENVIRON SPECIALIST
Application Received Date On Earliest Reg Form:	05/12/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601097413
Owner Last Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	583604122002106
Additional ID:	148440462002186
AI Number:	31210
Owner Effective Begin Date:	11/10/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

SUPERIOR DAIRIES (Continued) **U001264578**

Install Date:	01/01/1966
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	82020
Facility ID:	50478
Ai Number:	31210
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/04/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

SUPERIOR DAIRIES (Continued) **U001264578**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	27530
UST ID:	82020
AI Number:	31210
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	82021

SUPERIOR DAIRIES (Continued) **U001264578**

Facility ID:	50478
Ai Number:	31210
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/04/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000

SUPERIOR DAIRIES (Continued) **U001264578**

UST Comprt ID:	27531
UST ID:	82021
AI Number:	31210
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	82022
Facility ID:	50478
Ai Number:	31210
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/04/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

SUPERIOR DAIRIES (Continued) **U001264578**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	27532
UST ID:	82022
AI Number:	31210
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

SUPERIOR DAIRIES (Continued) **U001264578**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	82023
Facility ID:	50478
Ai Number:	31210
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/04/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

SUPERIOR DAIRIES (Continued) **U001264578**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	27533
UST ID:	82023
AI Number:	31210
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

SUPERIOR DAIRIES (Continued) **U001264578**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Contact Mailing Address (Delivery):	PO BOX 7729
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78713 7729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	50478
Additional ID:	148440462002186
Princ ID:	583604122002106
AI Number:	31210
Facility Name:	SUPERIOR DAIRIES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHIP ROGERS/

HIST UST AUSTIN:

Name:	SUPERIOR DARIES
Address:	600 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0407
HID UST:	407
Inspection:	Not reported
Due:	06/01/2012

LB1879 WNW < 1/8 0.039 mi. 207 ft. | **FAIRMONT HOTEL 600 E CESAR CHAVEZ ST AUSTIN, TX** | **TX HIST UST TX RDR** | **S127542278 N/A**

Site 2 of 9 in cluster LB

Actual: 460 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	FAIRMONT HOTEL
Address:	600 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	3386
HID UST:	Not reported
Inspection:	02/20/2015
Due:	Not reported

RDR:

RDR ID:	22721
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FAIRMONT HOTEL
Address:	600 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/25/2015
Due Date:	5/24/2015
Tank Owner:	WALLER CREEK ELEVEN LTD
Contact Person:	PERRY LORENZ
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/15/2015
Project Manager:	Ronnie Eason
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KU1880 ESE < 1/8 0.039 mi. 208 ft. | **HOWARDS CLEANERS 804 1ST E AUSTIN, TX** | **EDR Hist Cleaner** | **1013787357 N/A**

Site 2 of 3 in cluster KU

Actual: 470 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1940	HOWARDS CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	HOWARDS CLEANERS	CLOTHES PRESSERS AND CLEANERS
1953	HOWARDS CLEANERS	CLEANERS AND DYERS
1958	HOWARDS CLEANERS	CLEANERS AND DYERS

KR1881 ESE < 1/8 0.039 mi. 208 ft. — **MAGNOLIA PET CO STA NO**, **615 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013769907** / **N/A**

Site 3 of 10 in cluster KR

Actual: 479 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	MAGNOLIA PET CO STA NO	GASOLINE AND OIL SERVICE STATIONS

LC1882 ESE < 1/8 0.040 mi. 209 ft. — **TEXAS STATE ASSO OF FIRE FIGHTERS**, **1000 BRAZOS ST**, **AUSTIN, TX 78701** — **TX UST**, **TX HIST UST** — **U002112550** / **N/A**

Site 1 of 2 in cluster LC

Actual: 532 ft.

Focus Map: 11

UST:

Name:	TEXAS STATE ASSO OF FIRE FIGHTERS
Address:	1000 BRAZOS ST
City,State,Zip:	AUSTIN, TX 787012351
AI Number:	66434
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	94624752002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MIKE HIGGINS,
Contact Organization Name:	TEXAS STATE ASSO OF FIRE FIGHTERS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124783798
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/31/1995
Signature Name/Title On Earliest Reg Form:	TERRY BROOKS,SALES/CONTRACTOR
Application Received Date On Earliest Reg Form:	02/08/1995
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600781421
Owner Last Name:	TEXAS STATE ASSOCIATION OF FIRE FIGHTERS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

TEXAS STATE ASSO OF FIRE FIGHTERS (Continued) **U002112550**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	85624752002053
Additional ID:	94624752002053
AI Number:	66434
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	02/08/1995
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	173498
Facility ID:	99653
Ai Number:	66434
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/12/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

TEXAS STATE ASSO OF FIRE FIGHTERS (Continued) **U002112550**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	152244
UST ID:	173498
AI Number:	66434
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

TEXAS STATE ASSO OF FIRE FIGHTERS (Continued) **U002112550**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS STATE ASSOCIATION OF FIRE FIGHTERS
Contact Mailing Address (Delivery):	1000 BRAZOS ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2351
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	99653
Additional ID:	94624752002053
Princ ID:	85624752002053
AI Number:	66434
Facility Name:	TEXAS STATE ASSO OF FIRE FIGHTERS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MIKE HIGGINS/

HIST UST AUSTIN:

Name:	COMMERCIAL BUILDING
Address:	1000 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0562
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LD1883 **DIAMOND SHAMROCK 2070** **TX RDR** **S127532150**
SE **628 E OLTROF** **N/A**
< 1/8 **AUSTIN, TX**
0.040 mi.
210 ft. **Site 1 of 4 in cluster LD**

Actual:
560 ft.

Focus Map:
14

RDR:

RDR ID:	13016
Facility ID:	39561
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 2070
Address:	628 E OLTROF
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/9/2004
Due Date:	1/8/2005

DIAMOND SHAMROCK 2070 (Continued) **S127532150**

Tank Owner:	NATIONAL CONVENIENCE STOR
Contact Person:	C SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	9/9/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	116084
Pre-Existing LPST Number:	Not reported
Comments:	LADSCREEN SENT 09/16/04
Review Coordinator:	PPC/SNW
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LD1884 **DIAMOND SHAMROCK 2070** **TX LPST** **S106620719**
SE **628 E OLTORF ST** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX ENF**
0.040 mi. **TX Financial Assurance**
210 ft. **Site 2 of 4 in cluster LD** **TX COMP HIST**

Actual:
560 ft.

Focus Map:
14

LPST:

Name:	DIAMOND SHAMROCK 2070
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0039561
LPST Id:	116084
Facility Location:	628 E OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	09/12/2003
Entered Date:	09/09/2004
Reported Date:	09/12/2003
Closure Date:	12/29/2004
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	RD2
Responsible Party Name:	Not reported
Responsible Party Contact:	C SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/592-4663
Reported Date:	09/12/2003
Case Start Date:	12/29/2004
Reference Number:	RN102370640
Project Manager:	RDOWD

ASBESTOS:

Name:	QUAD FOOD MART

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/25/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	QUAD FOOD STORE
Address:	628 E OLTORF
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	CN602904807
Unique TCEQ Ref Number Of Reg. Entity:	RN102370640
Contact Person For The Reg. Entity:	AGNI SANJEL
Owner/operator Of A Regulated Entity:	QUAD FOOD STORE INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	04/17/2009
Description 1:	Failure to equip storage container vent line with a pressure-vacuum (PV) relief valve set to open at a pressure of no more than eight ounces per square inch (3.4 kPa) in the covered attainment counties, as defined in ?115.10 of this title (relating to Definitions).
Description 2:	Documentation was submitted to the Austin Region Office on March 31, 2009 indicating that PV valves were installed at the site.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	115.222(6)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

TX Financial Assurance 2:

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	266903
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2021
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP414514
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/27/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	249097
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2019
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	Not reported
Policy Number:	STP-127782
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/27/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	230810
AI:	39561
Mechanism Type Other:	Not reported

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2019
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4306600
Policy Number:	STP127782
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/27/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	211699
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2017
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-118435
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/27/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	194668
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/27/2017
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	CRUM & FORSTER SPECIALTY INS

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Issuer Phone:	1 973 4906600
Policy Number:	STP118435
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/27/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	177716
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2017
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641078-08
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	160050
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2016
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3841078-07
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	142013
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2015
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641078-06
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	124777
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2014
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP384107805
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	4993
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2013
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641078-04
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	43453
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2012
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641078-03
Coverage Amount:	1000000
Coverage Expiration Date:	01/11/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	43454
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2011
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641078-02
Coverage Amount:	1000000

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Coverage Expiration Date:	01/11/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	43455
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2010
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 3431106
Policy Number:	PP3641078-01
Coverage Amount:	1000000
Coverage Expiration Date:	01/11/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	43456
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2009
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 3431106
Policy Number:	PP3641078
Coverage Amount:	1000000
Coverage Expiration Date:	01/11/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Finass ID:	43457
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2008
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 3431106
Policy Number:	PP 68639203
Coverage Amount:	1000000
Coverage Expiration Date:	01/11/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61081
Finass ID:	43458
AI:	39561
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	04/23/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

COMP HIST:

RN Number:	RN102370640
Name:	QUAD FOOD STORE
Address:	628 E OLTORF
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605878479
CN Name:	M&A AMBROSIA LLC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH

DIAMOND SHAMROCK 2070 (Continued) **S106620719**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236220
SIC Code:	6513
Related Number:	39561,39561

RN Number:	RN102370640
Name:	QUAD FOOD STORE
Address:	628 E OLTORF
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN602904799
CN Name:	QUADINVESTMENTS INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447110
SIC Code:	1629
Related Number:	39561,39561

RN Number:	RN102370640
Name:	QUAD FOOD STORE
Address:	628 E OLTORF
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604467175
CN Name:	VALERO ENERGY CORP
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	447190
SIC Code:	1771
Related Number:	39561,39561

LD1885 **VALERO ENERGY STATION** **EDR Hist Auto** **1021084171**
SE **628 E OLTORF ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.040 mi.
210 ft. **Site 3 of 4 in cluster LD**

Actual: EDR Hist Auto
560 ft.

Focus Map:
14

Year:	Name:	Type:
2011	VALERO ENERGY STATION	Gasoline Service Stations

LD1886 **QUAD FOOD MART** **TX UST** **U004221866**
SE **628 E OLTORF ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX ASBESTOS**
0.040 mi.
210 ft. **Site 4 of 4 in cluster LD**

Actual:
560 ft.

Focus Map:
14

UST:

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 787045667
AI Number:	39561
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	ACTIVE
Additional ID:	88761582002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	628 E OLTORF
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	AMRIT JHANJI,
Contact Organization Name:	QUAD FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127078900
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	QUADFOOD@GMAIL.COM
Signature Date On Earliest Reg Form:	03/24/2020
Signature Name/Title On Earliest Reg Form:	AMRIT JHANJI,OWNER
Application Received Date On Earliest Reg Form:	04/23/2020
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	455304142021104
Additional ID:	88761582002149
Ai Number:	39561
Operator CN:	CN605878479
Operator Name:	M&A AMBROSIA LLC
Operator Effective Begin Date:	02/01/2013
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

QUAD FOOD MART (Continued) **U004221866**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602904799
Owner Last Name:	QUADINVESTMENTS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	340358612005250
Additional ID:	88761582002149
AI Number:	39561
Owner Effective Begin Date:	06/30/2005
State Tax ID:	32014448438
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	61081
Cert ID:	369262
AI Number:	39561
Self Certification Date:	03/16/2022
Signature Name/Title:	AMRIT JHANJI OPERATOR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	352828
AI Number:	39561
Self Certification Date:	03/17/2021

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	335991
AI Number:	39561
Self Certification Date:	03/24/2020
Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	318030
AI Number:	39561
Self Certification Date:	03/12/2019
Signature Name/Title:	AMRIT JHANI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	301459
AI Number:	39561
Self Certification Date:	03/07/2018

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AMRIT JHANHI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	284875
AI Number:	39561
Self Certification Date:	03/08/2017
Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	268306
AI Number:	39561
Self Certification Date:	03/06/2016
Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	251041
AI Number:	39561
Self Certification Date:	03/02/2015

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	233695
AI Number:	39561
Self Certification Date:	02/26/2014
Signature Name/Title:	AMRIT JHANJI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61081
Cert ID:	63114
AI Number:	39561
Self Certification Date:	02/26/2013
Signature Name/Title:	AMRIT JHANHI OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63113
AI Number:	39561
Self Certification Date:	02/21/2012

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AMRIT JHANJI DIRECTOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63112
AI Number:	39561
Self Certification Date:	02/22/2011
Signature Name/Title:	AMRIT JHANJI DIR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63111
AI Number:	39561
Self Certification Date:	03/31/2010
Signature Name/Title:	AGNI SANJEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63110
AI Number:	39561
Self Certification Date:	03/08/2009

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AGNI SANJEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61081
Cert ID:	63109
AI Number:	39561
Self Certification Date:	04/16/2008
Signature Name/Title:	ANGI SANJEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61081
Cert ID:	63108
AI Number:	39561
Self Certification Date:	03/21/2007
Signature Name/Title:	AGNY SANJEL VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61081
Cert ID:	63107
AI Number:	39561
Self Certification Date:	03/18/2006

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	AGNI SANJEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63106
AI Number:	39561
Self Certification Date:	08/10/2005
Signature Name/Title:	SANDEEP MATHUR DIR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63105
AI Number:	39561
Self Certification Date:	02/11/2004
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63104
AI Number:	39561
Self Certification Date:	02/10/2004

QUAD FOOD MART (Continued) **U004221866**

Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63103
AI Number:	39561
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61081
Cert ID:	63102
AI Number:	39561
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1

QUAD FOOD MART (Continued) **U004221866**

Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104596
Facility ID:	61081
Ai Number:	39561
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/10/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

QUAD FOOD MART (Continued) **U004221866**

Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	9816
UST Comprt ID:	54699
UST ID:	104596
AI Number:	39561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104597
Facility ID:	61081
Ai Number:	39561
Tank Id:	2

QUAD FOOD MART (Continued) **U004221866**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/10/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	9816
UST Comprt ID:	54700
UST ID:	104597
AI Number:	39561

QUAD FOOD MART (Continued) **U004221866**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104598
Facility ID:	61081
Ai Number:	39561
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/10/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

QUAD FOOD MART (Continued) **U004221866**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	9816
UST Comprt ID:	54701
UST ID:	104598
AI Number:	39561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

QUAD FOOD MART (Continued) **U004221866**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	11/15/2003
Tank Registration Date:	02/13/2004
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	202757
Facility ID:	61081
Ai Number:	39561
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	11/15/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y

QUAD FOOD MART (Continued) **U004221866**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/09/2004

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	54702
UST ID:	202757
AI Number:	39561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y

QUAD FOOD MART (Continued) **U004221866**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	11/15/2003
Tank Registration Date:	02/13/2004
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	202758
Facility ID:	61081
Ai Number:	39561
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	11/15/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

QUAD FOOD MART (Continued) **U004221866**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/09/2004

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	54703
UST ID:	202758
AI Number:	39561
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

QUAD FOOD MART (Continued) **U004221866**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	7041
Facility ID:	61081
AI Number:	39561
Application Received Date:	10/15/2003
Scheduled Construction Date:	10/27/2003
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M31015003
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	54003
General Desc Of Prop Construct:	Not reported

NOC ID:	7040
Facility ID:	61081
AI Number:	39561
Application Received Date:	02/06/2003
Scheduled Construction Date:	03/10/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N

QUAD FOOD MART (Continued) **U004221866**

AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30206002
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	7588
UST ID:	Not reported
NOC ID:	7040
AI Number:	39561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001424
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	7589
UST ID:	Not reported
NOC ID:	7041
AI Number:	39561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1

QUAD FOOD MART (Continued) **U004221866**

Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	28441
UST ID:	202757
NOC ID:	Not reported
AI Number:	39561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	28442
UST ID:	202758
NOC ID:	Not reported
AI Number:	39561
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	43608

QUAD FOOD MART (Continued) **U004221866**

UST ID:	202757
NOC ID:	Not reported
AI Number:	39561
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	43609
UST ID:	202758
NOC ID:	Not reported
AI Number:	39561
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	QUADINVESTMENTS INC
Contact Mailing Address (Delivery):	628 E OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5667
Phone Number/Ext:	512 7078900/0
Contact Fax Number/Ext:	/
Contact Email Address:	QUADFOOD@GMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	61081

QUAD FOOD MART (Continued) **U004221866**

Additional ID:	88761582002149
Princ ID:	340358612005250
AI Number:	39561
Facility Name:	QUAD FOOD MART
AR Number:	64634
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	AMRIT JHANJI/

HIST UST AUSTIN:

Name:	QUAD FOOD MART
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	1178
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	QUAD FOOD STORE
Address:	628 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported

QUAD FOOD MART (Continued) **U004221866**

Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

JA1887 **SMITH J B** **EDR Hist Cleaner** **1013779645**
WNW **821 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.040 mi.
210 ft. **Site 9 of 15 in cluster JA**

Actual:
503 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	SMITH J B	CLOTHES PRESSERS AND CLEANERS

JG1888 **AMMOCO TRANSMISSIONS** **TX HIST UST** **S128728880**
ESE **712 LAMAR PL** **N/A**
< 1/8 **AUSTIN, TX**
0.040 mi.
211 ft. **Site 3 of 3 in cluster JG**

Actual:
712 ft.
HIST UST AUSTIN:

Name:	AMMOCO TRANSMISSIONS
Address:	712 LAMAR PL
City,State,Zip:	AUSTIN, TX

Focus Map:
6

AMMOCO TRANSMISSIONS (Continued) **S128728880**

Id UST:	C0060
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IB1889 **DALES AUTO PARTS** **TX Ind. Haz Waste** **S102752093**
WNW **602 W 34TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.040 mi.
211 ft. **Site 6 of 6 in cluster IB**

Actual:
600 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	DALES AUTO PARTS
Address:	602 W 34TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	69418
Registration Initial Notification Date:	03/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19860307
Land Type:	Not reported
Description of Facility Site Location:	602 W 34th, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	DALES AUTO PARTS
Contact Name:	DALE BALLARD
Contact Telephone Number:	Not reported
Mailing Address:	602 W 34TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787051203
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24296
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030911
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported

DALES AUTO PARTS (Continued) **S102752093**

Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	DALES AUTO PARTS
Operator Address:	602 W 34TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17415578503
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DALES AUTO PARTS
Owner Mailing Address:	602 W 34TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17415578503
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	602 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	602 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

DALES AUTO PARTS (Continued) **S102752093**

Contact Name:	DALE BALLARD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	602 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

FM1890 **AUSTIN NURSING & CONVALESCENT CENTER INC** **TX HIST UST** **1000412162**
ESE **110 E LIVE OAK** **RCRA NonGen / NLR** **TXD010531176**
< 1/8 **AUSTIN, TX 78704** **FINDS**
0.040 mi. **ECHO**
212 ft. **Site 3 of 3 in cluster FM** **TX Ind. Haz Waste**

Actual:
589 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	E. G. KINGSBURY
Address:	110 E LIVE OAK ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0273
HID UST:	273
Inspection:	Not reported
Due:	06/01/2012

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Nursing & Convalescent Center Inc
Handler Address:	E LIVE OAK
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD010531176
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	E LIVE OAK
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-444-3511
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E LIVE OAK
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Austin Nursing & Convalescent Center Inc
Owner Type:	Not reported
Operator Name:	Austin Nursing & Convalescent Center Inc
Operator Type:	Not reported
Short-Term Generator Activity:	No

AUSTIN NURSING & CONVALESCENT CENTER INC (Continued) **1000412162**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CHARLES TAYLOR	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN NURSING & CONVALESCENT CENTER INC	
Legal Status:	Not reported

AUSTIN NURSING & CONVALESCENT CENTER INC (Continued) **1000412162**

Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	110 E LIVE OAK
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-444-3511
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Legal Status:	Not reported
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	110 E LIVE OAK
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-444-3511
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19800626
Handler Name:	AUSTIN NURSING CONVALSCNT CTR#
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	62311
NAICS Description:	NURSING CARE FACILITIES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

AUSTIN NURSING & CONVALESCENT CENTER INC (Continued) **1000412162**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005039760

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412162
Registry ID:	110005039760
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005039760
Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Address:	110 E LIVE OAK
City,State,Zip:	AUSTIN, TX 78704

Ind. Haz Waste:

Name:	AUSTIN NURSING CONVALESCENT
Address:	110 E LIVE OAK ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66110
Registration Initial Notification Date:	08/23/2001
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD010531176
Primary NAICS Code:	Not reported
Status Change Date:	20010823
Land Type:	Not reported
Description of Facility Site Location:	110 E Live Oak, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CLASS1
Type of Generator:	Not reported
Company Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Contact Name:	Not reported
Contact Telephone Number:	512-4443511

AUSTIN NURSING & CONVALESCENT CENTER INC (Continued) **1000412162**

Mailing Address:	110 E LIVE OAK ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787044355
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21413
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030402
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Operator Address:	110 E LIVE OAK ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4443511
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17416017865
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN NURSING & CONVALESCENT CENTER INC
Owner Mailing Address:	110 E LIVE OAK ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4443511
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17416017865
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	110 E LIVE OAK ST

AUSTIN NURSING & CONVALESCENT CENTER INC (Continued) **1000412162**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443511
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	110 E LIVE OAK ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443511
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	110 E LIVE OAK ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4443511
Contact Fax:	Not reported
Contact Email:	Not reported

JY1891 **AUS TEX AUTOMOTIVE SERVICE** **EDR Hist Auto** **1013755459**
NNE **308 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.040 mi.
213 ft. **Site 2 of 6 in cluster JY**

Actual:
480 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	MARSHALL CAL AUTO BODY SHOP	AUTOMOBILE REPAIRING
1965	AUS TEX AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1973	FOREIGN MOTORS INC	General Automotive Repair Shops
1974	FOREIGN MOTORS INC	General Automotive Repair Shops
1984	SPECIFIC MOTOR WORKS AUTO REPR	AUTOMOBILE REPAIRING
1990	SPECIFIC MOTOR WORKS AUTO REPR	AUTOMOBILE REPAIRING

AI1892 **JIMS BODY SHOP** **RCRA NonGen / NLR** **1001197984**
WNW **6324 N LAMAR BLVD** **FINDS** **TXR000020610**
< 1/8 **AUSTIN, TX 78752** **ECHO**
0.040 mi.
213 ft. **Site 6 of 8 in cluster AI**

Actual:
710 ft.

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Jims Body Shop
Handler Address:	N LAMAR BLVD

Focus Map:
6

JIMS BODY SHOP (Continued) **1001197984**

Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXR000020610
Contact Name:	RAY COFFEY
Contact Address:	N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-450-0700
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Jims Body Shop
Owner Type:	Not reported
Operator Name:	Jims Body Shop
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325

JIMS BODY SHOP (Continued) **1001197984**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JIMS BODY SHOP	
Legal Status:	Not reported

JIMS BODY SHOP (Continued) **1001197984**

Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	6324 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-450-0700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JIMMY VASQUEZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6324 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-450-0700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JIMS BODY SHOP	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	6324 N LAMAR BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-450-0700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19970324
Handler Name: JIMS BODY SHOP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010214
Handler Name: JIMS BODY SHOP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

JIMS BODY SHOP (Continued) **1001197984**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005177058

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001197984
Registry ID: 110005177058
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005177058
Name: JIMS BODY SHOP
Address: 6324 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78752

AI1893 **A CAR 4 YOU INC** **EDR Hist Auto** **1021398570**
WNW **6324 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.040 mi.
213 ft. **Site 7 of 8 in cluster AI**

Actual:
710 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
2005	AUSTIN AUTO DENT & COLOR	General Automotive Repair Shops
2010	TOKYO AUTOS	Used Car Dealers, NEC
2011	TRANSMISSION KING SA INC	Automotive Transmission Repair Shops

A CAR 4 YOU INC (Continued) **1021398570**

2011	TOKYO AUTOS	Used Car Dealers, NEC
2012	TOKYO AUTOS	Used Car Dealers, NEC
2013	TOKYO AUTOS	Used Car Dealers, NEC
2014	TOKYO AUTOS	Used Car Dealers, NEC

AI1894 **JIMS BODY SHOP** **TX HIST UST** **S103605822**
WNW **6324 N LAMAR BLVD** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78752** **TX Ind. Haz Waste**
0.040 mi.
213 ft. **Site 8 of 8 in cluster AI**

Actual:
710 ft.

Focus Map:
6

HIST UST AUSTIN:

Name:	J. R. PFAU
Address:	6324 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0863
HID UST:	863
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	WAREHOUSE / SERVICE SHOPS
Address:	6324 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	10/06/2021
Reason for Inspection:	Karen Rodewald
Violation:	Not reported
Complaint Date:	08/13/2020
Notification Number:	2020004603
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/13/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original

JIMS BODY SHOP (Continued) **S103605822**

Work Type Flag:	D
Certification Statement Date:	07/13/2020
Certification Statement Phone:	512-453-4646
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	JIMS BODY SHOP
Address:	6324 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61871
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXR000020610
Primary NAICS Code:	811121
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6324 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1

JIMS BODY SHOP (Continued) **S103605822**

Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	JIMS BODY SHOP
Contact Name:	RAY COFFEY
Contact Telephone Number:	512-4500700
Mailing Address:	6324 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524006
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20210
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	JIMS BODY SHOP
Operator Address:	6324 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4500700
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JIMS BODY SHOP
Owner Mailing Address:	6324 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4500700
Owner Fax:	Not reported
Owner Email Address:	Not reported

JIMS BODY SHOP (Continued) **S103605822**

Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	11
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Storage area for hazardous waste generated.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970304
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6324 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4500700
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6324 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4500700
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RAY COFFEY
Contact Title:	MANAGER
Contact Role:	PRICONT

JIMS BODY SHOP (Continued) **S103605822**

Contact Address:	6324 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4500700
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	157975
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Automobile painting operation
Standard Industrial Code:	75320
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

LE1895 **TURK EQUIPMENT** **TX UST** **U003529610**
ESE **400 NUECES ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.040 mi.
213 ft. **Site 1 of 2 in cluster LE**

Actual:
468 ft.

Focus Map:
11

UST:

Name:	TURK EQUIPMENT
Address:	400 NUECES ST
City,State,Zip:	AUSTIN, TX 787013828
AI Number:	71661
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	08/31/1987

TURK EQUIPMENT (Continued) **U003529610**

Facility Status:	INACTIVE
Additional ID:	731510472002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	RICHARD TURK,
Contact Organization Name:	TURK EQUIPMENT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124777415
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/15/1999
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRESIDENT/EXCELL ENV
Application Received Date On Earliest Reg Form:	02/16/1999
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777734
Owner Last Name:	TURK RICHARD G
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OT
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	721510462002053
Additional ID:	731510472002053
AI Number:	71661
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	02/16/1999

TURK EQUIPMENT (Continued) **U003529610**

Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	189647
Facility ID:	109044
Ai Number:	71661
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/11/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

TURK EQUIPMENT (Continued) **U003529610**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	167169
UST ID:	189647
AI Number:	71661
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	02/16/1999
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	189646
Facility ID:	109044
Ai Number:	71661

TURK EQUIPMENT (Continued) **U003529610**

Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/11/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	167168
UST ID:	189646

TURK EQUIPMENT (Continued) **U003529610**

AI Number:	71661
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TURK RICHARD G
Contact Mailing Address (Delivery):	9805 TALLEYRAN DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78750 3808
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	109044
Additional ID:	731510472002053
Princ ID:	721510462002053
AI Number:	71661
Facility Name:	TURK EQUIPMENT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RICHARD TURK/

LF1896 **JACK BROWN CLEANERS SUITE 1** **RCRA-SQG** **1004784568**
East **615 W MARTIN LUTHER KING JR BL** **TXD981590664**
< 1/8 **AUSTIN, TX 78701**
0.041 mi.
214 ft. **Site 1 of 7 in cluster LF**

Actual:
560 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20140123
Handler Name:	Jack Brown Cleaners Suite 1
Handler Address:	615 W MARTIN LUTHER KING JR BL
Handler City,State,Zip:	AUSTIN, TX 78701-1115
EPA ID:	TXD981590664
Contact Name:	PAUL BROWN
Contact Address:	PO BOX 28159
Contact City,State,Zip:	AUSTIN, TX 78755-8159
Contact Telephone:	512-451-1333 120
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 28159
Mailing City,State,Zip:	AUSTIN, TX 78755-8159
Owner Name:	Jack Brown Cleaners Inc
Owner Type:	Private
Operator Name:	Jack Brown Cleaners Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D028
Waste Description:	1,2-Dichloroethane
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20020128
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-478-4621
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Legal Status:	Private
Date Became Current:	20080930
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-478-4621
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20090831
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-478-4621
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20090831
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-478-4621
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20080930
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-478-4621
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK T BROWN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 28159
Owner/Operator City,State,Zip:	AUSTIN, TX 78755-8159
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-478-4621
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-478-4621
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20020128
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755-8159
Owner/Operator Telephone: 512-478-4621
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20091006
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-478-4621
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20091006
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 28159
Owner/Operator City,State,Zip: AUSTIN, TX 78755
Owner/Operator Telephone: 512-478-4621
Owner/Operator Telephone Ext: Not reported

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19860902
Handler Name: JACK BROWN CLNRS #1
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020228
Handler Name: JACK BROWN CLNRS #1
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020128
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080930
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090831

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091006
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140123
Handler Name: JACK BROWN CLEANERS SUITE 1
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: JACK BROWN CLNRS #1
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violations:

JACK BROWN CLEANERS SUITE 1 (Continued) **1004784568**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LF1897 **JACK BROWN CLEANERS 1** **TX VCP** **S103606395**
East **615 W MARTIN LUTHER KING JR BLVD** **TX APAR** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX DRYCLEANERS**
0.041 mi. **TX GCC**
214 ft. **Site 2 of 7 in cluster LF** **TX Ind. Haz Waste**
TX COMP HIST

Actual:
560 ft.

Focus Map:
11

VCP TCEQ:

Name:	JACK BROWN CLEANERS
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	1658
VCP Record Date:	11/10/2003
Facility Type:	PROPERTY COMMERCIAL
PCA Number:	33858
Project Manager:	HPODLIPN
Phase:	COMPLETED
Acres at Site:	0.68
REM Program:	VCP
RN Number:	RN102798402
Former Facility Type:	DRY CLEANER
Site Address Description:	615 W MARTIN LUTHER KING AUSTIN TX
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	11/13/2003
RCRIS Number:	Not reported
Air REM Method:	NA
GW REM Method:	NA
EPA Texas ID/CERCLIS Registration:	TXD981590664
Soil REM Method:	EXCAVATION/REMOVAL
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	NA
TNRCC Solid Waste Registration:	66309
GW Inst Eng Controls:	NA
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	NA
Certificate of Completion Date:	12/14/2021; 07/07/2021
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	CHLORINATED SOLVENTS
Date Cashier Check Received:	11/06/2003
GW Target COC Class:	TPH; CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2003-12-12 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS; TPH; SVOCS

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1658
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	338580
Off Site?:	NO
Media:	ELECTRONIC
IOP Number:	Not reported
File Location:	WCC
Latitude:	30.28
Longitude:	-97.74

Contact:

REM Program:	VCP
Program ID:	1658
RN Number:	RN102798402
CN Number:	CN605937267
CN Name:	JACK BROWN FAMILY II LIMITED PARTNERSHIP
Role Code:	APPLCONT
Contact Name:	BROWN, PAUL
Contact Title:	MANAGER
Organization Name:	JACK BROWN FAMILY II LIMITED PARTNERSHIP
Mailing Address:	PO BOX 28159
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78755
Contact Telephone:	(512) 451-1333
Contact Telephone Ext:	120

APAR:

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING, AUSTIN, TX
City,State,Zip:	AUSTIN, TX 78701
Comm Id Number:	12943715
Comm Type Code:	APAR
Comm Received Date:	12/30/2009
Legal Identifier:	1658
Legal Description Text:	VOLUNTARY CLEANUP
Legal Status:	INACTIVE
Physical Name:	JACK BROWN CLEANERS
Physical Status:	COMPLETED
Physical Attribute Value Text:	PROPERTY COMMERCIAL
Reference Number Text:	RN102798402
Delivery Text:	615 W MARTIN LUTHER KING JR BLVD
Physical Location Desc:	Not reported
Latitude:	30.282222
Longitude:	-97.744722

Detail:

Comm Id Number:	12943715
Comm Received Date:	12/30/2009
Legal Ident Text:	1658
Legal Description Text:	VOLUNTARY CLEANUP
Soil Contamination:	Not reported

DRYCLEANERS:

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	YES
Gross Receipts:	> $150,000

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	400
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	520
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	500
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	11
CN Number:	CN600264543
DCR Number:	Not reported
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	JACK BROWN CLEANERS 1
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	360
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN102798402
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR11067
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

JACK BROWN CLEANERS 1 (Continued) **S103606395**

GCC:

Name:	JACK BROWN CLEANERS
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Division:	REM/VCP
New Cases:	Not reported
File Number:	1658
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/10/2003
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	4 -
Data Quality 1:	Not reported
Section 5236:	Not reported
Type:	2019 GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	JACK BROWN CLEANER S
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	1658
Contamination Description:	VOCS, TPH, CHLORIN ATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/10/2003
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	0 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	JACK BROWN CLEANERS
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Division:	REM/VCP
New Cases:	Not reported
File Number:	1658
Contamination Description:	CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/10/2003
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	6C - Action Completed - determination that no further action is needed
Data Quality 1:	E
Section 5236:	Not reported
Type:	Not reported
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANER S
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 1658
Contamination Description: VOCS, TPH, CHLORIN ATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/10/2003
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 0 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANERS
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 1658
Contamination Description: CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 2020
Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANERS
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 1658
Contamination Description: CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/10/2003
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANER S
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 1658
Contamination Description: TPH, PCBS
Date Of Earliest Known Contamination Confirmation: 11/10/2003
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANER S
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 1658
Contamination Description: TPH, PCBS
Date Of Earliest Known Contamination Confirmation: 11/10/2003
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: JACK BROWN CLEANERS
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 1658
Contamination Description: CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/10/2003
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 0B/L2 -
Data Quality 1: E
Section 5236: Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Ind. Haz Waste:
Name: JACK BROWN CLEANERS SUITE 1
Address: 615 W MARTIN LUTHER KING JR BLVD
City,State,Zip: AUSTIN, TX 78701
Permit Number: Not reported
Registration Number: 66309
Registration Initial Notification Date: 04/15/1985
Registration Last Amendment Date: 01/23/2014
EPA Identification: TXD981590664
Primary NAICS Code: 812320
Status Change Date: 20140310
Land Type: PRIVATE
Description of Facility Site Location: 615 W Martin Luther King, Austin, TX
Site Primary Standard Industrial Code: Not reported
Registration is Generator of Waste: 1
TNRCC Region Number: 11
Registration is Receivers of Waste: 1
Registration is Transporter of Waste: 1
Registration is Transfer Facility: 1
Facility is STEERS Reporter: 1
Reqired to Submit Annual Waste Summary: 1
Facility Involved In Recycling: 1
Revcr Has Monthly Reporting Requirement: 0
Mexican Facility: Not reported
Type of Generator HW: SQG
Type of Generator: NON INDUS
Company Name: JACK BROWN CLEANERS INC
Contact Name: PAUL BROWN
Contact Telephone Number: 512-4511333-120
Mailing Address: PO BOX 28159
Mailing Address2: Not reported
Mailing City,State,Zip: AUSTIN, TX 787558159
Mailing County: UNITED STATES
Facility Country: UNITED STATES
TNRCC Facility ID: 21588
Site Owner Tax ID: 741395502
Site Location Latitude: -00.000
Site Location Longitude: -000.000
Last Update to NOR Data: 20140310
Ind. Waste Permit Number: Not reported
Mun Waste Permit Number: Not reported
Non Notifier: 1
MSW: Not reported
Medical Waste: Not reported
Other: Not reported
Sludge: Not reported
Used Oil: Not reported
Used Tires: Not reported
Permit Status: Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	JACK BROWN CLEANERS INC
Operator Address:	PO BOX 28159
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78755
Operator Country:	UNITED STA
Operator Telephone:	1-512-4784621
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17413955026
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JACK BROWN CLEANERS INC
Owner Mailing Address:	PO BOX 28159
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78755
Owner Country:	UNITED STA
Owner Telephone:	1-512-4784621
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17413955026
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	N
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum (unrated) for waste liquid tetrachloroethylene.
Unit Description 2:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	N
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum used to dry & sstore filters
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4784621
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4784621
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	PAUL BROWN
Contact Title:	PRESIDENT
Contact Role:	PRICONT
Contact Address:	PO BOX 28159

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-4511333 x120
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	164050
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste liquid tetrachloroethylene from the distillation in the dry cleaning proce
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	164052
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	The carbon filters used to clean up the tetrachloroethylene in the dry cleaningp
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228734
Texas Waste Code:	Not reported
Texas Waste Code 2:	3603301H
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil and concrete rubble contaminated with chlorinated solvents and petroleum hy
Standard Industrial Code:	Not reported
Primary Source:	G44
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W301
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	228735
Texas Waste Code:	Not reported
Texas Waste Code 2:	3604101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water containing trace amounts of chlorinated solvents and petroleum hydrocarbon
Standard Industrial Code:	Not reported
Primary Source:	G44
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

JACK BROWN CLEANERS 1 (Continued) **S103606395**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236803
Texas Waste Code:	Not reported
Texas Waste Code 2:	3605601H
Waste Code Status:	INACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Tetra-chloroethylene still bottom (sludge)
Standard Industrial Code:	Not reported
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301761
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301761
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWG

JACK BROWN CLEANERS 1 (Continued) **S103606395**

COMP HIST:

RN Number:	RN102798402
Name:	JACK BROWN CLEANERS 1
Address:	615 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
CN Name:	JACK BROWN CLEANERS INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	81232
SIC Code:	1521
Related Number:	TXD981590664,DCR11067,DCR11067

LF1898 **BROWN JACK CLEANERS** **EDR Hist Cleaner** **1019944353**
East **615 W MLK BLVD** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.041 mi.
214 ft. **Site 3 of 7 in cluster LF**

Actual:
560 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1980	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1989	BROWN JACK CLEANERS	Drycleaning Plants, Except Rugs, NEC
1989	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1990	BROWN JACK CLEANERS	Drycleaning Plants, Except Rugs, NEC
1990	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1991	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1992	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1993	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1994	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1995	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1996	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1997	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1998	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
1999	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2000	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2001	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2002	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2003	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2004	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2005	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2006	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2007	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2008	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2009	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2010	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2011	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2012	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC
2013	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

BROWN JACK CLEANERS (Continued) **1019944353**

2014	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs, NEC

J1899
WNW
< 1/8
0.041 mi.
214 ft.

TRAN RICHMOND
10800 N LAMAR BLVD
AUSTIN, TX 78753

EDR Hist Auto **1021506189**
N/A

Site 10 of 10 in cluster J

Actual:
750 ft.

Focus Map:
3

EDR Hist Auto

Year:	Name:	Type:
2005	TRAN RICHMOND	Automotive Transmission Repair Shops
2006	TRAN RICHMOND	Automotive Transmission Repair Shops
2007	TRAN RICHMOND	Automotive Transmission Repair Shops
2008	TRAN RICHMOND	Automotive Transmission Repair Shops
2009	TRAN RICHMOND	Automotive Transmission Repair Shops
2010	TRAN RICHMOND	Automotive Transmission Repair Shops
2011	TRAN RICHMOND	Automotive Transmission Repair Shops

1900
WNW
< 1/8
0.041 mi.
215 ft.

CHAMPION PROPERTIES
UNKNOWN
AUSTIN, TX 78701

US BROWNFIELDS FINDS **1016352624**
N/A

Actual:
462 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	CHAMPION PROPERTIES
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.365945
Longitude:	-97.797386
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11981
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	88
Below Poverty Percent:	5.19
Meidan Income:	9258
Meidan Income Number:	178
Meidan Income Percent:	10.51
Vacant Housing Number:	89
Vacant Housing Percent:	9.23
Unemployed Number:	38
Unemployed Percent:	2.24

Name:	1ST TEE GOLF/YMCA
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.291933

CHAMPION PROPERTIES (Continued) **1016352624**

Longitude:	-97.662593
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11980
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	959
Below Poverty Percent:	47.31
Meidan Income:	3265
Meidan Income Number:	1143
Meidan Income Percent:	56.39
Vacant Housing Number:	69
Vacant Housing Percent:	9.94
Unemployed Number:	87
Unemployed Percent:	4.29

Name:	FEATHERLIGHT
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.282112
Longitude:	-97.70923
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Former Use: sand and construction materials distributor
Datum:	Not reported
Acres Property ID:	11975
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	sand and construction materials distributor
Below Poverty Number:	672
Below Poverty Percent:	18.56
Meidan Income:	5113
Meidan Income Number:	1241
Meidan Income Percent:	34.27
Vacant Housing Number:	132
Vacant Housing Percent:	7.07
Unemployed Number:	169
Unemployed Percent:	4.67

Name:	SPRINKLE CUTOFF
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.361439
Longitude:	-97.654107
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11977
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	4
Below Poverty Percent:	8.7
Meidan Income:	42
Meidan Income Number:	9
Meidan Income Percent:	19.57
Vacant Housing Number:	2
Vacant Housing Percent:	9.52
Unemployed Number:	2
Unemployed Percent:	4.35

CHAMPION PROPERTIES (Continued) **1016352624**

Name:	AUSTIN ENERGY POLE YARD
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.12
Latitude:	30.268096
Longitude:	-97.751731
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11970
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	342
Below Poverty Percent:	10.87
Meidan Income:	9215
Meidan Income Number:	551
Meidan Income Percent:	17.52
Vacant Housing Number:	451
Vacant Housing Percent:	19.88
Unemployed Number:	161
Unemployed Percent:	5.12

Name:	ROBERT MUELLER MUNIC AIRPORT
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	709
Latitude:	30.296122
Longitude:	-97.701039
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11971
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	182
Below Poverty Percent:	15.13
Meidan Income:	6045
Meidan Income Number:	286
Meidan Income Percent:	23.77
Vacant Housing Number:	42
Vacant Housing Percent:	7.1
Unemployed Number:	34
Unemployed Percent:	2.83

Name:	SEAHOLM POWER PLANT
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2.34
Latitude:	30.267498
Longitude:	-97.751922
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

Datum:	Not reported
Acres Property ID:	11973
IC Data Access:	Not reported
Start Date:	3/31/2002
Redev Completition Date:	Not reported
Completed Date:	3/31/2002
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	325

CHAMPION PROPERTIES (Continued) **1016352624**

Below Poverty Percent:	10.77
Meidan Income:	9047
Meidan Income Number:	530
Meidan Income Percent:	17.56
Vacant Housing Number:	431
Vacant Housing Percent:	19.8
Unemployed Number:	152
Unemployed Percent:	5.04

Name:	4TH STREET STEEL YARD
Address:	UNKNOWN
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.5
Latitude:	30.262826
Longitude:	-97.732757
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	Not reported
Acres Property ID:	11978
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Not reported
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

CHAMPION PROPERTIES (Continued) **1016352624**

IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	332
Below Poverty Percent:	14.31
Meidan Income:	7174
Meidan Income Number:	539
Meidan Income Percent:	23.23
Vacant Housing Number:	100
Vacant Housing Percent:	8.06
Unemployed Number:	75
Unemployed Percent:	3.23

FINDS:

Registry ID: 110060761894

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Registry ID: 110060762731

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Registry ID: 110060762839

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Registry ID: 110060763080

CHAMPION PROPERTIES (Continued) **1016352624**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.
Registry ID: 110060763320

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.
Registry ID: 110060786430

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.
Registry ID: 110039555406

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

LG1901 **CVS PHARMACY 7483** **TX ASBESTOS** **S118467295**
SSW **500 CONGRESS AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.041 mi.
216 ft. **Site 1 of 26 in cluster LG**

Actual:
490 ft.

Focus Map:
11

ASBESTOS:

Name:	CVS PHARMACY
Address:	500 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/24/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals

CVS PHARMACY 7483 (Continued) **S118467295**

Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 7483
Address:	500 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	96145

CVS PHARMACY 7483 (Continued) **S118467295**

Registration Initial Notification Date:	12/04/2015
Registration Last Amendment Date:	03/22/2022
EPA Identification:	TXR000081081
Primary NAICS Code:	446110
Status Change Date:	20161214
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	NICOLE WILKINSON
Contact Telephone Number:	401-7707132
Mailing Address:	1 CVS DR
Mailing Address2:	MAIL CODE 2340
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	131490
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220713
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	MAIL CODE 2340
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA

CVS PHARMACY 7483 (Continued) **S118467295**

Operator Telephone:	1-401-7707132
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	MAIL CODE 2340
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7707132
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 GALLON CONTAINERS ARE STORED IN THE BACK STORAGE AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20151204
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

CVS PHARMACY 7483 (Continued) **S118467295**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 GALLON CONTAINERS IN THE PHARMACY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20160226
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	MAIL CODE 2340
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7707132
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	NICOLE WILKINSON
Contact Title:	SENIOR CORPORATE ENV MANA
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	MAIL CODE 2340
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7707132
Contact Fax:	Not reported
Contact Email:	NICOLE.WILKINSON@CVSHEALTH.COM

Ind. Haz Waste:

Waste ID:	382000
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Aerosols and Gas
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

CVS PHARMACY 7483 (Continued) **S118467295**

Company Waste ID:	AEROSOLS GAS FLAM
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	378593
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FLAMMABLE LIQUIDS, DAMAGED OR RETURNED GOODS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382001
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

CVS PHARMACY 7483 (Continued) **S118467295**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382002
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acute Toxic Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389304
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

CVS PHARMACY 7483 (Continued) **S118467295**

Ind. Haz Waste:

Waste ID:	382003
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	DIANNE DURAND
Contact Title:	Not reported
Contact Telephone:	1-401-7703315 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	DURAND ,DIANNE
Attention Suffix:	HWG

Contact Name:	DIANNE DURAND
Contact Title:	Not reported
Contact Telephone:	1-401-7703315 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000301294
Principal Name:	CVS PHARMACY INC
Attention Name:	DURAND ,DIANNE
Attention Suffix:	NWG

LG1902 **CVS PHARMACY 7483** **RCRA NonGen / NLR** **1014961817**
SSW **500 500 CONGRESS AVE** **TXR000081081**
< 1/8 **AUSTIN, TX 78701**
0.041 mi.
216 ft. **Site 2 of 26 in cluster LG**

Actual:
490 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20220322
Handler Name:	Cvs Pharmacy 7483
Handler Address:	500 CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78701-3502
EPA ID:	TXR000081081
Contact Name:	NICOLE WILKINSON
Contact Address:	1 CVS DR
Contact City,State,Zip:	WOONSOCKET, RI 02895-6146
Contact Telephone:	401-770-7132
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1 CVS DR
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cvs Pharmacy Inc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CVS PHARMACY 7483 (Continued) **1014961817**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220719
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018

CVS PHARMACY 7483 (Continued) **1014961817**

Waste Description: Benzene

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U010
Waste Description: Azirino [2',3':3,4]Pyrrolo[1,2-A]Indole-4,7-Dione, 6-Amino-8-[[(Aminocarbonyl)Oxy]Methyl]-1,1a,2,8,8a,8b-Hexahydro-8a-Methoxy-5-Methyl-, [1as-(1aalpha, 8beta, 8aalpha, 8balpha)]- (Or) Mitomycin C

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U044

CVS PHARMACY 7483 (Continued) **1014961817**

Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U059
Waste Description: 5,12-Naphthacenedione, 8-Acetyl-10-[(3-Amino-2,3,6-Trideoxy)-Alpha-L-Lyxo-Hexopyranosyl)Oxy]-7,8,9,10-Tetrahydro-6,8,11-Trihydroxy-1-Methoxy-, (8s-Cis)- (Or) Daunomycin

Waste Code: U070
Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4'-(1,2-Diethyl-1,2-Ethenediyl)Bis, (E)-

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2'-Methylenebis[3,4,6-Trichloro-

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U206
Waste Description: D-Glucose, 2-Deoxy-2-[[(Methylnitrosoamino)-Carbonyl]Amino]- (Or) Glucopyranose, 2-Deoxy-2-(3-Methyl-3-Nitrosoureido)-,D- (Or) Streptozotocin

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

CVS PHARMACY 7483 (Continued) **1014961817**

Waste Code: U279
Waste Description: U279

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: JOHN COLEMAN HORTON III
Legal Status: Private
Date Became Current: 20151116
Date Ended Current: Not reported
Owner/Operator Address: 903 NUECES ST.
Owner/Operator City,State,Zip: AUSTIN, TX 78701-2217
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20151204
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20151204
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-770-7132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20040801
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC

CVS PHARMACY 7483 (Continued) **1014961817**

Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY 7483 (Continued) **1014961817**

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOHN COLEMAN HORTON, III & BENNIE C.	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	903 NUECES ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-477-9966
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-770-7132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20151204
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

CVS PHARMACY 7483 (Continued) **1014961817**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20160301
Handler Name: CVS PHARMACY 7483
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120725
Handler Name: CVS PHARMACY #7483
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160226
Handler Name: CVS PHARMACY 7483
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170207
Handler Name: CVS PHARMACY 7483
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20171220

CVS PHARMACY 7483 (Continued) **1014961817**

Handler Name: CVS PHARMACY #10888
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20180412
Handler Name: CVS PHARMACY 7483
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220322
Handler Name: CVS PHARMACY 7483
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LH1903 SSW < 1/8 0.041 mi. 216 ft. | **FOUND ON SANBORN MAPS**
318 E 5TH ST
AUSTIN, TX
Site 1 of 26 in cluster LH | **TX HIST UST** | **S111678642**
N/A

Actual: 484 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	FOUND ON SANBORN MAPS
Address:	318 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H1006
HID UST:	1006
Inspection:	Not reported
Due:	06/01/2012

LI1904 East < 1/8 0.041 mi. 216 ft. | **MRS. ROBT. W. SHIPP**
303 W MARTIN LUTHER KING JR BLVD
AUSTIN, TX
Site 1 of 3 in cluster LI | **TX HIST UST** | **S111678754**
N/A

Actual: 574 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	MRS. ROBT. W. SHIPP
Address:	303 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0297
HID UST:	297
Inspection:	Not reported
Due:	06/01/2012

1905 ESE < 1/8 0.041 mi. 217 ft. | **ORTEGON AUTO BODY REPAIR**
111 E WOODWARD ST
AUSTIN, TX 78704 | **RCRA NonGen / NLR**
FINDS
ECHO
TX Ind. Haz Waste
TX CENTRAL REGISTRY | **1000202526**
TXD117568808

Actual: 637 ft.
Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Ortegon Auto Body Repair
Handler Address:	E WOODWARD ST
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD117568808
Contact Name:	ARNOLD ORTEGON
Contact Address:	E WOODWARD ST
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-448-3433
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

ORTEGON AUTO BODY REPAIR (Continued) **1000202526**

State District Owner:	Tx
State District:	11
Mailing Address:	E WOODWARD ST
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040615
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ARNOLD ORTEGON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN

ORTEGON AUTO BODY REPAIR (Continued) **1000202526**

Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19850701
Handler Name: ORTEGON AUTO BODY REPAIR
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: ORTEGON AUTO BODY REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005072018

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ORTEGON AUTO BODY REPAIR (Continued) **1000202526**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000202526
Registry ID:	110005072018
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005072018
Name:	ORTEGON AUTO BODY REPAIR
Address:	111 E WOODWARD ST
City,State,Zip:	AUSTIN, TX 78704

Ind. Haz Waste:

Name:	ORTEGON AUTO BODY REPAIR
Address:	111 WOODWARD ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66356
Registration Initial Notification Date:	07/16/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD117568808
Primary NAICS Code:	Not reported
Status Change Date:	19850716
Land Type:	Not reported
Description of Facility Site Location:	111 E Woodward St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	ORTEGON AUTO BODY REPAIR
Contact Name:	ARNOLD ORTEGON
Contact Telephone Number:	512-4483433
Mailing Address:	111 WOODWARD ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787047228
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21635
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

ORTEGON AUTO BODY REPAIR (Continued) **1000202526**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	ORTEGON AUTO BODY REPAIR
Owner Mailing Address:	111 WOODWARD ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4483433
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	111 WOODWARD ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4483433
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ARNOLD ORTEGON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	111 WOODWARD ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4483433
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100585173
Name:	ORTEGON AUTO BODY REPAIR
Address:	111 WOODWARD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7228
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295323
Customer Name:	ORTEGON AUTO BODY REPAIR
Customer Legal Name:	Ortegon Auto Body Repair

ORTEGON AUTO BODY REPAIR (Continued) **1000202526**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E Woodward St, Austin, TX

Regulated Entity Number:	RN100585173
Name:	ORTEGON AUTO BODY REPAIR
Address:	111 WOODWARD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-7228
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295323
Customer Name:	ORTEGON AUTO BODY REPAIR
Customer Legal Name:	Ortegon Auto Body Repair
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	111 E Woodward St, Austin, TX

1906 **ALLMANS GROCERY & SERVICE STN** **EDR Hist Auto** **1020879524**
SW **7207 E RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.041 mi.
218 ft.

Actual:
523 ft.

EDR Hist Auto

Focus Map:
19

Year:	Name:	Type:
1970	ALLMANS GROCERY & SERVICE STN	Grocery Stores
1971	ALLMANS GROCERY & SERVICE STN	Grocery Stores
1972	ALLMANS GROCERY & SERVICE STN	Grocery Stores

KY1907 **AUSTIN WELDIN E** **EDR Hist Auto** **1013756165**
ESE **304 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.041 mi.
218 ft. **Site 2 of 21 in cluster KY**

Actual:
489 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	AUSTIN WELDIN E	AUTOMOBILE REPAIRERS

KY1908 ESE < 1/8 0.041 mi. 218 ft. — **CLYDES WIDG**, **304 5TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768562** / **N/A**

Site 3 of 21 in cluster KY

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	CLYDES WIDG	AUTOMOBILE RADIATOR REPAIRING
1953	CLYDES WIDG	RADIATOR REPAIRERS-AUTOMOBILE
1958	CLYDES WIDG	AUTOMOBILE RADIATOR REPAIRERS

LJ1909 WNW < 1/8 0.041 mi. 218 ft. — **ZADAS AUTOMOTIVE & COLLISION AUTO REPR & BODY SHOP**, **816 KRAMER LN**, **TRAVIS (County), TX 78768** — **EDR Hist Auto** — **1013753175** / **N/A**

Site 1 of 2 in cluster LJ

Actual: 770 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1984	B AUTOSYSTEMS WORKSHOP THE AUTO	AUTOMOBILE REPAIRING
1990	ZADAS AUTOMOTIVE & COLLISION AU	AUTOMOBILE REPAIRING
1991	CROFT CUSTOM AUTO DETAIL	General Automotive Repair Shops
1992	CROFT CUSTOM AUTO DETAIL	General Automotive Repair Shops
1993	CROFT CUSTOM AUTO DETAIL	General Automotive Repair Shops
1996	SWEDISH AUTO SERVICE	Auto And Truck Equipment And Parts
1997	SWEDISH AUTO SERVICE	Auto And Truck Equipment And Parts
1999	EDS MUFFLERS	General Automotive Repair Shops
2000	EDS MUFFLERS	General Automotive Repair Shops
2001	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2001	EDS MUFFLERS	General Automotive Repair Shops
2002	EDS MUFFLERS	General Automotive Repair Shops
2002	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2003	EDS MUFFLERS	General Automotive Repair Shops
2003	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2004	EDS MUFFLERS	General Automotive Repair Shops
2004	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2005	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2005	EDS MUFFLERS	General Automotive Repair Shops
2006	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2006	EDS MUFFLERS	General Automotive Repair Shops
2007	EDS MUFFLERS	General Automotive Repair Shops
2007	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2008	TRI STAR AUTOS	General Automotive Repair Shops
2008	ADVANCE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2008	EDS MUFFLERS	General Automotive Repair Shops
2009	EDS MUFFLERS	General Automotive Repair Shops
2009	TRI STAR AUTOS	General Automotive Repair Shops
2010	EDS MUFFLERS	General Automotive Repair Shops
2011	EDS MUFFLERS	General Automotive Repair Shops
2012	EDS MUFFLERS	General Automotive Repair Shops
2013	RICKS AUTO REPAIR	General Automotive Repair Shops
2013	EDS MUFFLERS	General Automotive Repair Shops
2014	RICKS AUTO REPAIR	General Automotive Repair Shops

LA1910 **H. C. FRISTOE** **TX HIST UST** **S111678662**
WNW **121 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.041 mi.
218 ft. **Site 3 of 15 in cluster LA**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	H. C. FRISTOE
Address:	121 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0071
HID UST:	71
Inspection:	Not reported
Due:	06/01/2012

LK1911 **AMERICAN TAXI CAB CO.** **TX HIST UST** **S111678553**
ESE **305 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.042 mi.
221 ft. **Site 1 of 10 in cluster LK**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	AMERICAN TAXI CAB CO.
Address:	305 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0384
HID UST:	384
Inspection:	03/19/2009
Due:	03/19/2012

JA1912 **TYLER F A FILL STA** **EDR Hist Auto** **1013758698**
WNW **823 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.042 mi.
222 ft. **Site 10 of 15 in cluster JA**

Actual:
502 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	TYLER F A FILL STA	GASOLINE AND OIL SERVICE STATIONS

KR1913 **REYES CLNRS** **EDR Hist Cleaner** **1013779273**
ESE **611 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.042 mi.
222 ft. **Site 4 of 10 in cluster KR**

Actual:
479 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1935	ODORLESS DRY CLEAN	CLOTHES PRESSERS AND CLEANERS
1940	ODORLESS DRY CLNRS	CLOTHES PRESSERS AND CLEANERS
1947	REYES CLNRS	CLOTHES PRESSERS AND CLEANERS

1914 NE < 1/8 0.042 mi. 223 ft. | **LUCAS GULF STATION**
1221 INTERREGIONAL HWY S
AUSTIN, TX 78702 | **EDR Hist Auto** | **1013764513**
N/A

Actual: 495 ft.

Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1965	MORRIS GULF SERVICE	GASOLINE STATIONS
1970	SIMMONS INTERREGIONAL GULF SERV	GASOLINE STATIONS
1975	SOUTH INTERREGIONAL GULF	GASOLINE STATIONS
1980	LUCAS GULF STATION	GASOLINE STATIONS

1915 WNW < 1/8 0.042 mi. 224 ft. | **CARLSONS GARAGE AUTO**
609 31ST W
AUSTIN, TX | **EDR Hist Auto** | **1013756520**
N/A

Actual: 593 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1958	CARLSONS GARAGE	AUTOMOBILE REPAIRING
1962	CARLSONS GARAGE AUTO	AUTOMOBILE REPAIRING

LL1916 ESE < 1/8 0.042 mi. 224 ft. | **7-ELEVEN STORE 38608**
105 E STASSNEY LN
AUSTIN, TX 78745
Site 1 of 4 in cluster LL | **TX LPST**
TX UST
TX HIST UST
TX ASBESTOS
TX Financial Assurance
TX GCC
TX RDR | **U004194716**
N/A

Actual: 632 ft.

Focus Map: 17

LPST:

Name:	STASSNEY Q MART
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120685
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	09/20/2018
Entered Date:	03/15/2019
Reported Date:	01/29/2019
Closure Date:	06/28/2019
Priority:	3.2 - IMPACTED GW W/IN 500FT-0.25MI TO SW USED BY HUMANENDGR SPEC
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Responsible Party Telephone:	Not reported
Reported Date:	01/29/2019
Case Start Date:	06/28/2019
Reference Number:	RN106528961
Project Manager:	KFROSS

UST:

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 787453224
AI Number:	85082
Facility Type:	RETAIL
Facility Begin Date:	07/03/2012
Facility Status:	ACTIVE
Additional ID:	403623762012289
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	PEGGIE BETZ,REGION COMPLIANCE SPECIALIST
Contact Organization Name:	7-ELEVEN STORE 38608
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	9728286898
Contact Email Address:	peggie.betz@7-11.com
Signature Date On Earliest Reg Form:	06/19/2019
Signature Name/Title On Earliest Reg Form:	FAZIL MALIK,CEO
Application Received Date On Earliest Reg Form:	06/24/2019
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	403623762012289
Ai Number:	85082
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	10/22/2019
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210

7-ELEVEN STORE 38608 (Continued) **U004194716**

Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	403623762012289
AI Number:	85082
Owner Effective Begin Date:	10/22/2019
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	130236
Cert ID:	382675
AI Number:	85082
Self Certification Date:	01/17/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236

7-ELEVEN STORE 38608 (Continued) **U004194716**

Cert ID:	365306
AI Number:	85082
Self Certification Date:	01/19/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	347724
AI Number:	85082
Self Certification Date:	01/18/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	329331
AI Number:	85082
Self Certification Date:	11/28/2019
Signature Name/Title:	RAYMOND MCNIECE REGION COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236

7-ELEVEN STORE 38608 (Continued) **U004194716**

Cert ID:	329330
AI Number:	85082
Self Certification Date:	11/27/2019
Signature Name/Title:	RAYMOND MCNIECE REGION COMPLIANCE MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	322378
AI Number:	85082
Self Certification Date:	06/19/2019
Signature Name/Title:	FAZIL MALIK CEO
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	305289
AI Number:	85082
Self Certification Date:	06/05/2018
Signature Name/Title:	FAZIL MALIK CEO
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236

7-ELEVEN STORE 38608 (Continued) **U004194716**

Cert ID:	288705
AI Number:	85082
Self Certification Date:	06/06/2017
Signature Name/Title:	FAZIL MALIK CEO
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	270093
AI Number:	85082
Self Certification Date:	05/03/2016
Signature Name/Title:	FAZIL MALIK PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	254973
AI Number:	85082
Self Certification Date:	07/07/2015
Signature Name/Title:	FAZIL MALIK PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236

7-ELEVEN STORE 38608 (Continued) **U004194716**

Cert ID:	237866
AI Number:	85082
Self Certification Date:	06/01/2014
Signature Name/Title:	FAZIL MALIK PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	130236
Cert ID:	220817
AI Number:	85082
Self Certification Date:	06/01/2013
Signature Name/Title:	FAZIL MALIK OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130236
Cert ID:	217931
AI Number:	85082
Self Certification Date:	02/14/2013
Signature Name/Title:	FAZIL MALIK MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Tank:

Install Date:	07/03/2012
Tank Registration Date:	02/14/2013
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	218149
Facility ID:	130236
Ai Number:	85082
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	07/03/2012
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

7-ELEVEN STORE 38608 (Continued) **U004194716**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/14/2013

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	181922
UST ID:	218149
AI Number:	85082
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/2013

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	181923
UST ID:	218149
AI Number:	85082
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/2013

Install Date:	07/03/2012
Tank Registration Date:	02/14/2013
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	218148
Facility ID:	130236
Ai Number:	85082
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	07/03/2012
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

7-ELEVEN STORE 38608 (Continued) **U004194716**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/14/2013

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	181921
UST ID:	218148
AI Number:	85082
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

7-ELEVEN STORE 38608 (Continued) **U004194716**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/2013

Construction Notification:

NOC ID:	22742
Facility ID:	130236
AI Number:	85082
Application Received Date:	05/07/2012
Scheduled Construction Date:	06/15/2012
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	49906
General Desc Of Prop Construct:	INSTALLATION OF (2) 12,000 GAL UST'S AND (5) DISPENSERS.

7-ELEVEN STORE 38608 (Continued) **U004194716**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	37036
UST ID:	218148
NOC ID:	Not reported
AI Number:	85082
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	37037
UST ID:	218149
NOC ID:	Not reported
AI Number:	85082
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	23830
UST ID:	Not reported
NOC ID:	22742
AI Number:	85082
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000021
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER

7-ELEVEN STORE 38608 (Continued) **U004194716**

Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	52193
UST ID:	218149
NOC ID:	Not reported
AI Number:	85082
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	23831
UST ID:	Not reported
NOC ID:	22742
AI Number:	85082
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000021
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	52192
UST ID:	218148
NOC ID:	Not reported
AI Number:	85082
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 5070913/0
Contact Fax Number/Ext:	972 8286898/0
Contact Email Address:	RAYMOND.MCNIECE@7-11.COM
Contact Address Deliverable:	Y
Facility ID:	130236
Additional ID:	403623762012289
Princ ID:	959578622001257
AI Number:	85082
Facility Name:	7-ELEVEN STORE 38608
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/REGION COMPLIANCE MANAGER

HIST UST AUSTIN:

Name:	7-ELEVEN #38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX
Id UST:	3360

7-ELEVEN STORE 38608 (Continued) **U004194716**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	C-STORE / SHELL GAS STATION
Address:	105 E. STASSNEY LN.
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	10/30/2012
Reason for Inspection:	Discretionary
Violation:	No
Complaint Date:	Not reported
Notification Number:	N/A
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	03
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/27/2012
Date Routed by Supervisor:	11/29/2012
Date Routed to PSQA:	12/04/2012
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	Q MART STASSNEY
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/28/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2014
Date Routed by Supervisor:	03/04/2014
Date Routed to PSQA:	03/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported

7-ELEVEN STORE 38608 (Continued) **U004194716**

Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	279845
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

7-ELEVEN STORE 38608 (Continued) **U004194716**

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	262871
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 817 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	242613
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	225022
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN STORE 38608 (Continued) **U004194716**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	216009
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/22/2019
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G46631420 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	223164
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 619 3915680

7-ELEVEN STORE 38608 (Continued) **U004194716**

Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	198771
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/22/2018
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G46631420 002
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/22/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	181847
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/22/2017
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G46631420 001
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/22/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745

7-ELEVEN STORE 38608 (Continued) **U004194716**

Region:	2
Facility ID:	130236
Finass ID:	162375
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/04/2016
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24801883-002
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/04/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	145945
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2015
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24801883001
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	129342
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN STORE 38608 (Continued) **U004194716**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/11/2014
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 800 0
Policy Number:	G2186903A-007
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/11/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	13113
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/14/2013
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 713 8807100
Policy Number:	G24740857 001
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/14/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	109631
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/14/2013
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24741023 001
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/14/2014

7-ELEVEN STORE 38608 (Continued) **U004194716**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 38608
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	130236
Finass ID:	109671
AI:	85082
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/25/2013
Date Financial Assurance Form Rec:	06/24/2019
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	Not reported
Policy Number:	FEI-EST-12778-00
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/25/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

GCC:

Name:	STASSNEY Q MART
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	120685
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	1/29/2019
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	Not reported
Section 5236:	Not reported
Type:	2019 GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

RDR:

RDR ID:	26606
Facility ID:	85082
RN:	Not reported
CN:	Not reported
Name:	STASSNEY Q MART
Address:	105 E STASSNEY LN
City,State,Zip:	AUSTIN, TX

7-ELEVEN STORE 38608 (Continued) **U004194716**

Date Report Received:	1/29/2019
Due Date:	3/30/2019
Tank Owner:	NORTHWEST PETROLEUM LLC
Contact Person:	FRANK MALIK
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	3/15/2019
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	120685
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LL1917 **QMART STASSNEY** **TX RDR** **S127540560**
ESE **105 E STASSNEY** **N/A**
< 1/8 **AUSTIN, TX**
0.042 mi.
224 ft. **Site 2 of 4 in cluster LL**

Actual:
632 ft.

Focus Map:
17

RDR:

RDR ID:	27356
Facility ID:	85082
RN:	Not reported
CN:	Not reported
Name:	QMART STASSNEY
Address:	105 E STASSNEY
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/13/2019
Due Date:	10/12/2019
Tank Owner:	NORTHWEST PETROLEUM LP
Contact Person:	FRANK MALIK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/27/2019
Project Manager:	Zebao Li
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KY1918 **MARTIN DELL BRAKE** **EDR Hist Auto** **1013754890**
ESE **302 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.043 mi.
225 ft. **Site 4 of 21 in cluster KY**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	MARTIN DELL BRAKE	AUTOMOBILE REPAIRING

BH1919 **CONVENIENCE COIN LAUNDRY NO** **EDR Hist Cleaner** **1013778812**
WNW **606 29TH ST W** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.043 mi.
227 ft. **Site 5 of 7 in cluster BH**

Actual:
597 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1980	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

BH1920 **CONVENIENCE COIN LAUNDRY NO** **EDR Hist Cleaner** **1013780131**
WNW **606 W 29TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.043 mi.
227 ft. **Site 6 of 7 in cluster BH**

Actual:
597 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1984	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

BH1921 **GUADALUPE LAUNDROMAT** **EDR Hist Cleaner** **1013784606**
WNW **606 29TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.043 mi.
228 ft. **Site 7 of 7 in cluster BH**

Actual:
597 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1962	GUADALUPE LAUNDROMAT	LAUNDRIES-SELF SERVE

IL1922 **ALEX & IDA DOCHEN TRUST** **TX UST** **U001263482**
NNE **500 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.043 mi.
229 ft. **Site 16 of 21 in cluster IL**

Actual:
491 ft.
UST:

Focus Map:
11

Name:	ALEX & IDA DOCHEN TRUST
Address:	500 E 7TH ST
City,State,Zip:	AUSTIN, TX 787013319
AI Number:	29963

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Facility Type:	UNKNOWN
Facility Begin Date:	10/31/1986
Facility Status:	INACTIVE
Additional ID:	934446672005049
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	ALEX & IDA DOCHEN TRUST
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123972587
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/07/1986
Signature Name/Title On Earliest Reg Form:	D K IRVIN,ASST. VP
Application Received Date On Earliest Reg Form:	05/09/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602786212
Owner Last Name:	INTERFIRST BANK TRUSTEE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	924446662005049
Additional ID:	934446672005049
AI Number:	29963
Owner Effective Begin Date:	10/31/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79028
Facility ID:	64551
Ai Number:	29963
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported
UST Comprt ID:	71210
UST ID:	79028
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79029

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Facility ID:	64551
Ai Number:	29963
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

UST Comprt ID:	71211
UST ID:	79029
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79026
Facility ID:	64551
Ai Number:	29963
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	71208
UST ID:	79026
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79027
Facility ID:	64551
Ai Number:	29963
Tank Id:	6
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	6
Tank Capacity:	Not reported
UST Comprt ID:	71209
UST ID:	79027
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79024
Facility ID:	64551
Ai Number:	29963
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	71206
UST ID:	79024
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1961
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79025
Facility ID:	64551
Ai Number:	29963
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	02/28/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/07/1989

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	71207
UST ID:	79025
AI Number:	29963
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

ALEX & IDA DOCHEN TRUST (Continued) **U001263482**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	INTERFIRST BANK TRUSTEE
Contact Mailing Address (Delivery):	5TH & CONGRESS
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	64551
Additional ID:	934446672005049
Princ ID:	924446662005049
AI Number:	29963
Facility Name:	ALEX & IDA DOCHEN TRUST
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

IL1923 **D&S** **TX HIST UST** **S128728907**
NNE **500 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.043 mi.
229 ft. **Site 17 of 21 in cluster IL**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	D&S
Address:	500 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0112
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

IL1924 **D & S SERVICE STATION** **EDR Hist Auto** **1013763026**
NNE **500 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.043 mi.
229 ft. **Site 18 of 21 in cluster IL**

Actual:
491 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1969	D & S ONE STOP SERVICE CO	Gasoline Service Stations
1970	D & S SERVICE STATION	GASOLINE STATIONS

D & S SERVICE STATION (Continued) **1013763026**

1970	D & S ONE STOP SERVICE CO	Gasoline Service Stations
1972	SANDGARTEN INC	Gasoline Service Stations
1973	SANDGARTEN INC	Gasoline Service Stations
1974	SANDGARTEN INC	Gasoline Service Stations
1975	SANDGARTEN INC	Gasoline Service Stations
1976	SANDGARTEN INC	Gasoline Service Stations
1977	SANDGARTEN INC	Gasoline Service Stations
1978	SANDGARTEN INC	Gasoline Service Stations
1979	SANDGARTEN INC	Gasoline Service Stations
1980	SANDGARTEN INC	Gasoline Service Stations
1982	SANDGARTEN INC	Gasoline Service Stations
1983	SANDGARTEN INC	Gasoline Service Stations
1985	SANDGARTEN INC	Gasoline Service Stations

IL1925 **ALEX DOCHEN** **TX HIST UST** **S128729449**
NNE **500 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.043 mi.
229 ft. **Site 19 of 21 in cluster IL**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ALEX DOCHEN
Address:	500 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0855
HID UST:	855
Inspection:	Not reported
Due:	06/01/2012

IL1926 **ALEX DOCHEN** **TX HIST UST** **S128729419**
NNE **500 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.043 mi.
229 ft. **Site 20 of 21 in cluster IL**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ALEX DOCHEN
Address:	500 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0791
HID UST:	791
Inspection:	Not reported
Due:	06/01/2012

KY1927 ESE < 1/8 0.043 mi. 229 ft. | **BADGER WALTER H JR FILLING STA**
300 5TH W
AUSTIN, TX
Site 5 of 21 in cluster KY | **EDR Hist Auto** | **1013756140**
N/A

Actual: 489 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	BADGER WALTER H JR FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1953	AUSTIN BATTERY	AUTOMOBILE ELECTRIC REPAIRS

HY1928 ENE < 1/8 0.044 mi. 230 ft. | **RREEF HEMPHILL PARK**
2810 HEMPHILL PARK
AUSTIN, TX 78705
Site 6 of 7 in cluster HY | **TX LPST** | **S108974750**
TX GCC | **N/A**

Actual: 602 ft.
Focus Map: 11

LPST:

Name:	RREEF HEMPHILL PARK
Address:	2810 HEMPHILL PARK
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	Not reported
LPST Id:	117561
Facility Location:	2810 HEMPHILL PARK
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/17/2007
Entered Date:	01/30/2008
Reported Date:	12/11/2007
Closure Date:	04/04/2008
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	IG
Responsible Party Name:	Not reported
Responsible Party Contact:	YVETTE GEORGE
Responsible Party Address:	1406 HALSEY WAY STE 110
Responsible Party City,St,Zip:	CARROLLTON, TX 75007
Responsible Party Telephone:	972/323-8405
Reported Date:	12/11/2007
Case Start Date:	04/04/2008
Reference Number:	RN106989494
Project Manager:	IGLOVER

GCC:

Name:	RREF
Address:	2810 HEMPHILL PK
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	*
File Number:	117561
Contamination Description:	UNKNOWN
Date Of Earliest Known Contamination Confirmation:	1/30/2008
Enforcement Status - Level Of Agency Response:	6 -
Enforcement Status - Site Activity Status:	6 -

RREEF HEMPHILL PARK (Continued) **S108974750**

Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

HY1929 **2810 HEMPHILL** **TX RDR** **S127529072**
ENE **2810 HEMPHILL PK** **N/A**
< 1/8 **AUSTIN, TX**
0.044 mi.
230 ft. **Site 7 of 7 in cluster HY**

Actual:
602 ft.

Focus Map:
11

RDR:

RDR ID:	16860
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	2810 HEMPHILL
Address:	2810 HEMPHILL PK
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/11/2007
Due Date:	2/9/2008
Tank Owner:	Not reported
Contact Person:	Not reported
Report:	PHASE II
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Joyce Sirota
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	JES
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KH1930 **PARKING LOT & BUILDING** **TX CLI** **S113416550**
SSW **206 CONGRESS AVE** **N/A**
< 1/8 **TRAVIS (County), TX**
0.044 mi.
231 ft. **Site 7 of 19 in cluster KH**

Actual:
475 ft.

Focus Map:
11

CAPCOG LI:

Name:	PARKING LOT & BUILDING
Address:	206 CONGRESS AVE
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported

PARKING LOT & BUILDING (Continued) **S113416550**

Date Open:	0
Date Close:	0
Unum:	1247
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	15.880000000000001
Longitude Deg:	97
Longitude Min:	44.649999999999999
Lat Dd:	30.264666999999999
Long Dd:	-97.744167000000004
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	5
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Third and Colorado LLC
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	14
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Austin
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported

PARKING LOT & BUILDING (Continued) **S113416550**

Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Inspection:	???
Comment:	Reported in 09/01/92 list of RTC sites in Texas; Responsible entity is Nunnink & Associates-AMDA Contract 0731-91-0681-001; RTC REOMS Property No.850507498; Environmental Hazards: Historic Disposal/Contamination; Asbestos; Underground Storage Tanks;
Latitude:	30.26466667
Longitude:	-97.74416667
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=1

KH1931 **PARKING LOT & BUILDING** **TX HIST LF** **S129372670**
SSW **206 CONGRESS AVE** **N/A**
< 1/8 **TRAVIS (County), TX**
0.044 mi.
231 ft. **Site 8 of 19 in cluster KH**

Actual:
475 ft.

Focus Map:
11

HIST LF:

Name:	PARKING LOT & BUILDING
Name 2:	Not reported
Address:	206 CONGRESS AVE
City,State,Zip:	TX
Latitude:	30.264667
Longitude:	-97.744167
Lat Deg:	30
Lat MM:	15.88
Lon DD:	97
Lon MM:	44.65
UNUM:	1247
Comments:	Reported in 09/01/92 list of RTC sites in Texas; Responsible entity is Nunnink & Associates-AMDA Contract 0731-91-0681-001; RTC REOMS Property No.850507498; Environmental Hazards: Historic Disposal/Contamination; Asbestos; Underground Storage Tanks;
Inspection:	???
COG Number:	12
COOR CD:	Not reported
TWC District:	14
Owner Name:	Resolution Trust Corp
Owner Code:	A
Open Date:	0
Close Date:	0
Acres:	0
Yards:	0
Parties:	Austin
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported

PARKING LOT & BUILDING (Continued) **S129372670**

Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	5

KH1932 **PARKING LOT & BUILDING** **TX CLI** **S103258939**
SSW **206 CONGRESS AVE** **N/A**
< 1/8 **, TX**
0.044 mi.
231 ft. **Site 9 of 19 in cluster KH**

Actual:
475 ft.

Focus Map:
11

CLI:

Name:	PARKING LOT & BUILDING
Address:	206 CONGRESS AVE
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	5
Source Code:	Not reported
Date Opened:	**********
Date Closed:	**********
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	15.88
Long Deg:	97
Long Min:	44.65
Lat/Long (deg):	30.264667 / -97.744167
Owner:	Resolution Trust Corp
Owner Address:	Not reported
Owner C,S,Z:	Not reported

PARKING LOT & BUILDING (Continued) **S103258939**

Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	14
Code for Landfill:	1
Parties:	Austin
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Uk
Inspc Comments:	???
Comments:	Reported in 09/01/92 list of RTC sites in Texas; Responsible entity is Nunnink & Associates-AMDA Contract 0731-91-0681-001; RTC REOMS Property No.850507498; Environmental Hazards: Historic Disposal/Contamination; Asbestos; Underground Storage Tanks;
Update:	0
Reviewer:	Not reported
Flag:	Not reported

1933 ENE < 1/8 0.044 mi. 231 ft. | **ASTRO CLEANERS** | **EDR Hist Cleaner** | **1018738110**
1900 E RIVERSIDE DR | **N/A**
AUSTIN, TX 78741

Actual: 468 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1986	ASTRO CLEANERS	Garment Pressing And Cleaners' Agents
1987	ASTRO CLEANERS	Garment Pressing And Cleaners' Agents
1988	ASTRO CLEANERS	Garment Pressing And Cleaners' Agents

LM1934 WNW < 1/8 0.044 mi. 232 ft. | **HOMESTEAD 451 CENTRAL OFF**
817 N LOOP
AUSTIN, TX
Site 1 of 3 in cluster LM | **TX RDR** | **S127526387**
N/A

Actual: 683 ft.
Focus Map: 8

RDR:

RDR ID:	1678
Facility ID:	19359
RN:	Not reported
CN:	Not reported
Name:	HOMESTEAD 451 CENTRAL OFF
Address:	817 N LOOP
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/24/2002
Due Date:	12/23/2002
Tank Owner:	SOUTHWESTERN BELL TEL
Contact Person:	BRET KENRICK
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/18/2003
Project Manager:	Michael L'Heureux
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	91998
Comments:	6A; 104122 6A; RTN: PC SAMPLING, REG, WATER IN TANKHOLD;11/1/01
Review Coordinator:	MAL/SAW
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/18/2003
Date Report Returned:	12/14/2001
Region:	Not reported
DKC RDR (misfiled):	Not reported

LH1935 SSW < 1/8 0.044 mi. 232 ft. | **CADILLAC SALES COMPANY**
304 E 5TH ST
AUSTIN, TX
Site 2 of 26 in cluster LH | **TX HIST UST** | **S111678589**
N/A

Actual: 485 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CADILLAC SALES COMPANY
Address:	304 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0020
HID UST:	20
Inspection:	Not reported
Due:	06/01/2012

LH1936 SSW < 1/8 0.044 mi. 232 ft. | **DEEN MILLER**
324 E 5TH ST
AUSTIN, TX
Site 3 of 26 in cluster LH | **TX HIST UST** | **S111678624**
N/A

Actual: 484 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	DEEN MILLER
Address:	324 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0095
HID UST:	95
Inspection:	Not reported
Due:	06/01/2012

JA1937 WNW < 1/8 0.044 mi. 233 ft. | **AUSTIN COMMUNITY COLLEGE (AUSTINS PIZZA)**
800 W 12TH STREET
AUSTIN, TX 78701
Site 11 of 15 in cluster JA | **TX HIST UST**
TX ASBESTOS | **S111678670**
N/A

Actual: 502 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	HARRY P. BICKLER
Address:	800 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0968
HID UST:	968
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	AUSTIN COMMUNITY COLLEGE (AUSTINS PIZZA)
Address:	800 W 12TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	01/27/2022
Notification Number:	2022000191
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

AUSTIN COMMUNITY COLLEGE (AUSTINS PIZZA) (Continued) **S111678670**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/10/2022
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN COMMUNITY COLLEGE (AUSTINS PIZZA)
Address:	800 W 12TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	01/27/2022
Notification Number:	2022000191
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

AUSTIN COMMUNITY COLLEGE (AUSTINS PIZZA) (Continued) **S111678670**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/10/2022
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

JA1938 **GRIFFIN A C HUMBLE** **EDR Hist Auto** **1013757090**
WNW **800 W 12TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.044 mi.
233 ft. **Site 12 of 15 in cluster JA**

Actual:
502 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	GRIFFIN A C HUMBLE	GASOLINE STATIONS
1969	GRIFFIN ANTHONY C	Gasoline Service Stations
1970	GRIFFIN A C HUMBLE PRODUCTS SER	GASOLINE STATIONS
1970	GRIFFIN ANTHONY C	Gasoline Service Stations

JA1939 **HUMBLE OIL & REFINING CO.** **TX HIST UST** **S111678686**
WNW **800 W 12TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.044 mi.
233 ft. **Site 13 of 15 in cluster JA**

Actual:
502 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	HUMBLE OIL & REFINING CO.
Address:	800 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0970
HID UST:	970
Inspection:	Not reported
Due:	06/01/2012

LN1940 **LUCKY CLEANERS** **EDR Hist Cleaner** **1020030597**
ESE **7601 N LAMAR BLVD STE H** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.044 mi.
234 ft. **Site 1 of 2 in cluster LN**

Actual:
758 ft.

Focus Map:
6

EDR Hist Cleaner

Year:	Name:	Type:
2006	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC

LN1941 **LUCKY CLEANERS** **TX DRYCLEANERS** **S109360819**
ESE **7601 N LAMAR BLVD STE H** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.044 mi.
234 ft. **Site 2 of 2 in cluster LN**

Actual:
758 ft.

Focus Map:
6

DRYCLEANERS:

Name:	LUCKY CLEANERS
Address:	7601 N LAMAR BLVD STE H
City,State,Zip:	AUSTIN, TX 78752
RN Number:	RN105029813
Region:	11
CN Number:	CN603086448
DCR Number:	Not reported
AR Number:	24004098

LUCKY CLEANERS (Continued) **S109360819**

Principal Name:	DUONG, QUEN T
Bill Addr1:	6937 THISTLE HILL WAY
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78754 5804
EMail:	Not reported
Phone Number:	Not reported
Site Name:	LUCKY CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

1942 WNW < 1/8 0.045 mi. 235 ft. **CUNNINGHAM HENRY** **EDR Hist Auto** **1013775092**
403 16TH ST E **N/A**
AUSTIN, TX

Actual: 538 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	CUNNINGHAM HENRY	AUTOMOBILE SERVICE STATIONS
1916	CUNNINGHAM HENRY	AUTOMOBILE REPAIRERS

LO1943 WNW < 1/8 0.045 mi. 235 ft. **TRANS TECH AUTOMOTIVE** **EDR Hist Auto** **1013767812**
805 CAPITOL ST **N/A**
TRAVIS (County), TX 78756

Site 1 of 5 in cluster LO

Actual: 665 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1988	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1989	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1990	TRANS TECH AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1992	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1993	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1994	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1995	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1996	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1997	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1998	TRANS TECH AUTOMOTIVE	General Automotive Repair Shops
1999	EILERS ROBERT	General Automotive Repair Shops
2000	EILERS ROBERT	General Automotive Repair Shops

LP1944 **CONGRESS EXXON** **EDR Hist Auto** **1020907330**
ESE **6721 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.045 mi.
236 ft. **Site 1 of 5 in cluster LP**

Actual:
663 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1995	CONGRESS EXXON	Gasoline Service Stations
1996	CONGRESS EXXON	Gasoline Service Stations

LP1945 **EXXON 6-9404** **TX RDR** **S127536225**
ESE **6721 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.045 mi.
236 ft. **Site 2 of 5 in cluster LP**

Actual:
663 ft.

RDR:

Focus Map:
17

RDR ID:	8007
Facility ID:	58226
RN:	Not reported
CN:	Not reported
Name:	EXXON 6-9404
Address:	6721 S CONGRESS
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/22/2001
Due Date:	10/21/2001
Tank Owner:	EXXON MOBIL
Contact Person:	DALE GOMM
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/29/2004
Project Manager:	Jeff Beckage
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RECOMMEND NO FURTHER ACTION. SNW. 5/28/2004
Review Coordinator:	JSB
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/29/2004
Date Report Returned:	12/5/2002
Region:	Not reported
DKC RDR (misfiled):	Not reported

LP1946 **EXXON RS 69404** **TX UST** **U001288001**
ESE **6721 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX Financial Assurance**
0.045 mi.
236 ft. **Site 3 of 5 in cluster LP**

Actual:
663 ft.

UST:

Focus Map:
17

Name:	EXXON RS 69404
Address:	6721 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787455744
AI Number:	58226

EXXON RS 69404 (Continued) **U001288001**

Facility Type:	RETAIL
Facility Begin Date:	05/09/1991
Facility Status:	INACTIVE
Additional ID:	944487162002054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	EXXON RS 69404
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2813122566
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1991
Signature Name/Title On Earliest Reg Form:	WILLIAM B MATNEY,UST ENG
Application Received Date On Earliest Reg Form:	05/07/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600785968
Owner Last Name:	JIMMY NASSOUR TRUSTEE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	934487152002054
Additional ID:	944487162002054
AI Number:	58226
Owner Effective Begin Date:	09/14/2001
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

EXXON RS 69404 (Continued) **U001288001**

Install Date:	08/01/1987
Tank Registration Date:	05/07/1991
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	139128
Facility ID:	48602
Ai Number:	58226
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/20/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

EXXON RS 69404 (Continued) **U001288001**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/25/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	27361
UST ID:	139128
AI Number:	58226
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	22787
Cert ID:	59880
UST Comprt ID:	172971
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A

EXXON RS 69404 (Continued) **U001288001**

Self Cert ID:	22787
Cert ID:	60130
UST Comprt ID:	172970
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60131
UST Comprt ID:	172969
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60133
UST Comprt ID:	172967
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60134
UST Comprt ID:	172966
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60132
UST Comprt ID:	172968
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60135
UST Comprt ID:	172965
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60136
UST Comprt ID:	172964
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787

EXXON RS 69404 (Continued) **U001288001**

Cert ID:	60137
UST Comprt ID:	172963
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60138
UST Comprt ID:	172962
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60139
UST Comprt ID:	172961
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59877
UST Comprt ID:	172972
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59878
UST Comprt ID:	172973
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59879
UST Comprt ID:	172974
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Install Date:	08/01/1987
Tank Registration Date:	05/07/1991
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	139129
Facility ID:	48602

EXXON RS 69404 (Continued) **U001288001**

Ai Number:	58226
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/20/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/25/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	27362

EXXON RS 69404 (Continued) **U001288001**

UST ID:	139129
AI Number:	58226
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	22787
Cert ID:	59880
UST Comprt ID:	172971
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60130
UST Comprt ID:	172970
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787

EXXON RS 69404 (Continued) **U001288001**

Cert ID:	60131
UST Comprt ID:	172969
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60133
UST Comprt ID:	172967
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60134
UST Comprt ID:	172966
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60132
UST Comprt ID:	172968
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60135
UST Comprt ID:	172965
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60136
UST Comprt ID:	172964
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60137
UST Comprt ID:	172963
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60138

EXXON RS 69404 (Continued) **U001288001**

UST Comprt ID:	172962
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60139
UST Comprt ID:	172961
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59877
UST Comprt ID:	172972
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59878
UST Comprt ID:	172973
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59879
UST Comprt ID:	172974
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Install Date:	08/01/1987
Tank Registration Date:	05/07/1991
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	139130
Facility ID:	48602
Ai Number:	58226
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/20/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

EXXON RS 69404 (Continued) **U001288001**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/25/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	27363
UST ID:	139130
AI Number:	58226
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EXXON RS 69404 (Continued) **U001288001**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	22787
Cert ID:	59880
UST Comprt ID:	172971
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60130
UST Comprt ID:	172970
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60131
UST Comprt ID:	172969
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60133

EXXON RS 69404 (Continued) **U001288001**

UST Comprt ID:	172967
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60134
UST Comprt ID:	172966
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60132
UST Comprt ID:	172968
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60135
UST Comprt ID:	172965
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60136
UST Comprt ID:	172964
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60137
UST Comprt ID:	172963
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60138
UST Comprt ID:	172962
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	60139
UST Comprt ID:	172961

EXXON RS 69404 (Continued) **U001288001**

UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59877
UST Comprt ID:	172972
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59878
UST Comprt ID:	172973
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A
Self Cert ID:	22787
Cert ID:	59879
UST Comprt ID:	172974
UST ID:	54529
AI Number:	58226
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	3517
Facility ID:	48602
AI Number:	58226
Application Received Date:	05/07/2001
Scheduled Construction Date:	06/01/2001
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10507008
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported

EXXON RS 69404 (Continued) **U001288001**

Owner AR At Time Of Construction: 4194
General Desc Of Prop Construct: Not reported

Facility Billing Contacts:
Contact Organization Name: JIMMY NASSOUR TRUSTEE
Contact Mailing Address (Delivery): 1016 LA POSADA DR STE 155
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: AUSTIN, TX 78752 3817
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 48602
Additional ID: 944487162002054
Princ ID: 934487152002054
AI Number: 58226
Facility Name: EXXON RS 69404
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: /

HIST UST AUSTIN:
Name: EXXON #69404
Address: 6721 S CONGRESS AVE
City,State,Zip: AUSTIN, TX
Id UST: 2036
HID UST: Not reported
Inspection: Not reported
Due: Not reported

TX Financial Assurance 2:
Name: EXXON RS 69404
Address: 6721 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78745
Region: 2
Facility ID: 48602
Finass ID: 32539
AI: 58226
Mechanism Type Other: Not reported
Multiple Mechanism Types: N
Coverage Amt per Annual Aggregate: Not reported
Meets Financial Assurance Req Flag: Not reported
Financial Responsibility Type: FINANCIAL TEST
Corrective Action MET Flag: Y
3rd Party MET Flag: Y
Financial Assurance Begin Date: 12/31/1992
Date Financial Assurance Form Rec: Not reported
Issuer Name: Not reported
Issuer Phone: Not reported
Policy Number: Unknown
Coverage Amount: 0
Coverage Expiration Date: 01/01/1901
Ins Premium Pre-Paid For Entire Yr: No

EXXON RS 69404 (Continued) **U001288001**

Proof of Financial Assurance: No

LP1947 **EXXON MOBIL CORPORATION** **RCRA NonGen / NLR** **1004785565**
ESE **6721 S CONGRESS AVE** **FINDS** **TXD988031860**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.045 mi.
236 ft. **Site 4 of 5 in cluster LP**

Actual:
663 ft.

Focus Map:
17

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD988031860
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 2180
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Telephone:	713-656-7709
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2180
Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

EXXON MOBIL CORPORATION (Continued) **1004785565**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON CO USA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4415
Owner/Operator City,State,Zip:	HOUSTON, TX 77210
Owner/Operator Telephone:	713-656-7761
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

EXXON MOBIL CORPORATION (Continued) **1004785565**

Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910401
Handler Name: EXXON CO USA #69404
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

EXXON MOBIL CORPORATION (Continued) **1004785565**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005132338

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004785565
Registry ID: 110005132338
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005132338
Name: EXXON MOBIL CORPORATION
Address: 6721 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78745

LP1948 **EXXON RSL 69404** **TX ASBESTOS** **S102757869**
ESE **6721 S CONGRESS AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.045 mi.
236 ft. **Site 5 of 5 in cluster LP**

Actual:
663 ft.

Focus Map:
17

ASBESTOS:

Name:	WALGREENS
Address:	6721 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.7
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/05/2013
Date Routed by Supervisor:	02/07/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

EXXON RSL 69404 (Continued) **S102757869**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALGREENS
Address:	6721 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/21/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported

EXXON RSL 69404 (Continued) **S102757869**

Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	EXXON RSL 69404
Address:	6721 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	77187
Registration Initial Notification Date:	06/28/1991
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988031860
Primary NAICS Code:	Not reported
Status Change Date:	19910628
Land Type:	PRIVATE
Description of Facility Site Location:	6721 S Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS

EXXON RSL 69404 (Continued) **S102757869**

Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6567709
Mailing Address:	PO BOX 2180
Mailing Address2:	ROOM 2753X
Mailing City,State,Zip:	HOUSTON, TX 772522180
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31495
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 2180
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77252
Operator Country:	UNITED STA
Operator Telephone:	1-713-6567709
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 2180
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Country:	UNITED STA
Owner Telephone:	1-713-6567709
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

EXXON RSL 69404 (Continued) **S102757869**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	WASTE ADMINISTRATOR
Contact Role:	PRICONT
Contact Address:	PO BOX 2180
Contact Address 2:	ROOM 2753X
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252

EXXON RSL 69404 (Continued) **S102757869**

Contact Phone: 1-713-6567709
Contact Fax: Not reported
Contact Email: Not reported

LI1949 **RITTERS SERVICE STATION** **EDR Hist Auto** **1013764434**
East **301 W 19TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.045 mi.
236 ft. **Site 2 of 3 in cluster LI**

Actual:
575 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	RITTERS SERVICE STATION	GASOLINE STATIONS

JY1950 **CAPITOL SPRING & BRAKE** **EDR Hist Auto** **1013753491**
NNE **310 COLORADO ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.045 mi.
237 ft. **Site 3 of 6 in cluster JY**

Actual:
480 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	BURKHALTER SPRING	AUTOMOBILE REPAIRERS
1940	BURKHALTER SPRING	AUTOMOBILE REPAIRING
1947	BURKHALTER SPRING & ALIGNMENT S	AUTOMOBILE REPAIRING
1953	BURKHALTER SPRING	AUTOMOBILE REPAIRING
1958	BURKHALTER SPRING	AUTOMOBILE REPAIRING
1962	BURKHALTER SPRING &	AUTOMOBILE REPAIRING
1965	BURKHALTER SPRING	AUTOMOBILE REPAIRING
1970	BURKHALTER SPRING & ALIGNMENT S	AUTOMOBILE REPAIRING
1975	CAPITOL SPRING & BRAKE	AUTOMOBILE REPAIRING
1976	CAPITAL SPRING & BRAKE	Automotive Repair Shops, NEC
1977	CAPITAL SPRING & BRAKE	Automotive Repair Shops, NEC
1978	CAPITAL SPRING & BRAKE	Automotive Repair Shops, NEC
1980	CAPITAL SPRING & BRAKE SERV	AUTOMOBILE REPAIRING

1951 **CPCG AUTO TX LP** **EDR Hist Auto** **1021084143**
WNW **408 W 17TH ST OFC 101** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.045 mi.
238 ft.

Actual:
543 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2005	CPCG AUTO TX LP	General Automotive Repair Shops
2006	CPCG AUTO TX LP	General Automotive Repair Shops
2007	CPCG AUTO TX LP	General Automotive Repair Shops
2008	CPCG AUTO TX LP	General Automotive Repair Shops
2011	GULF COAST INSULATION INC	Gasoline Service Stations, NEC

1952 NNE < 1/8 0.045 mi. 239 ft. | **ROAD RUNNERS COMMERCIAL CLEANE** | **EDR Hist Cleaner** | **1020075705** | **N/A**
1511 FARO DR
AUSTIN, TX 78741

Actual: 456 ft. EDR Hist Cleaner

Focus Map: 15

Year:	Name:	Type:
2007	ROAD RUNNERS COMMERCIAL CLEANE	Drycleaning Plants, Except Rugs
2008	ROAD RUNNERS COMMERCIAL CLEANE	Drycleaning Plants, Except Rugs
2009	ROAD RUNNERS COMMERCIAL CLEANE	Drycleaning Plants, Except Rugs

---

KX1953 ENE < 1/8 0.045 mi. 239 ft. | **MARIES TAILOR SHOP** | **EDR Hist Cleaner** | **1020034862** | **N/A**
1708 S LAKESHORE BLVD
AUSTIN, TX 78741
Site 4 of 5 in cluster KX

Actual: 464 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1996	ALL-PRO CLEANERS INC	Drycleaning Plants, Except Rugs

DD1954 ESE < 1/8 0.045 mi. 240 ft. | **KEESES ENCO PRODUCTS** | **EDR Hist Auto** | **1021649113** | **N/A**
600 W 5TH
AUSTIN, TX 78701
Site 5 of 6 in cluster DD

Actual: 468 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1969	KEESES ENCO PRODUCTS	Gasoline Service Stations
1970	KEESES ENCO PRODUCTS	Gasoline Service Stations
1971	KEESES ENCO PRODUCTS	Gasoline Service Stations
1972	KEESES ENCO PRODUCTS	Gasoline Service Stations
1973	KEESES ENCO PRODUCTS	Gasoline Service Stations
1974	KEESES ENCO PRODUCTS	Gasoline Service Stations
1975	KEESES ENCO PRODUCTS	Gasoline Service Stations
1976	KEESES ENCO PRODUCTS	Gasoline Service Stations
1977	KEESES ENCO PRODUCTS	Gasoline Service Stations
1978	KEESES ENCO PRODUCTS	Gasoline Service Stations
1979	KEESES ENCO PRODUCTS	Gasoline Service Stations

DD1955 ESE < 1/8 0.045 mi. 240 ft. | **HORIZON BANK - 600 W 5TH STREET** | **TX HIST UST** | **S128246542**
600 W 5TH ST | **TX CENTRAL REGISTRY** | **N/A**
AUSTIN, TX 78701
Site 6 of 6 in cluster DD

Actual: 468 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	COVERT BUICK (NUECES 5TH)
Address:	600 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0237
HID UST:	Not reported

HORIZON BANK - 600 W 5TH STREET (Continued) **S128246542**

Inspection: Not reported
Due: Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN111261525
Name:	HORIZON BANK - 600 W 5TH STREET
Address:	600 W 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2702
Status:	ACTIVE
Status Date:	2021-05-17
Customer Number:	CN602630477
Customer Name:	HCBECK LTD
Customer Legal Name:	HCBeck, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2021-05-17
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

LE1956 **NW COR WEAVER MARGT MRS** **EDR Hist Cleaner** **1013781866**
ESE **612 4TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.045 mi.
240 ft. **Site 2 of 2 in cluster LE**

Actual:
468 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	NW COR WEAVER MARGT MRS	LAUNDRIES

1957 **CAPITOL TRANSMISSION SERVICE** **EDR Hist Auto** **1013756457**
SW **7401 RIVERSIDE DR E** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.046 mi.
241 ft.

Actual:
529 ft.

EDR Hist Auto

Focus Map:
19

Year:	Name:	Type:
1984	CAPITOL TRANSMISSION SERVICE	AUTOMOBILE REPAIRING

1958 SSW < 1/8 0.046 mi. 241 ft. | **BELL JIM AUTOS INC**
201 BRAZOS ST
TRAVIS (County), TX 78701 | **EDR Hist Auto** | **1013762429**
N/A

Actual: 475 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1990	BELL JIM AUTOS INC	AUTOMOBILE REPAIRING

LQ1959 NE < 1/8 0.046 mi. 241 ft. | **M. H. CROCKETT**
300 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678730**
N/A

Site 1 of 7 in cluster LQ

Actual: 454 ft. HIST UST AUSTIN:

Focus Map: 14

Name:	M. H. CROCKETT
Address:	300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0890
HID UST:	890
Inspection:	04/24/2009
Due:	04/24/2012

LQ1960 NE < 1/8 0.046 mi. 241 ft. | **C.A. MAUFRAIS**
300 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678583**
N/A

Site 2 of 7 in cluster LQ

Actual: 454 ft. HIST UST AUSTIN:

Focus Map: 14

Name:	C.A. MAUFRAIS
Address:	300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0385
HID UST:	385
Inspection:	04/24/2009
Due:	04/24/2012

LQ1961 NE < 1/8 0.046 mi. 241 ft. | **METCALF L A SERVICE STATION**
300 S CONGRESS
AUSTIN, TX 78704 | **EDR Hist Auto** | **1020256188**
N/A

Site 3 of 7 in cluster LQ

Actual: 454 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1970	ELLIOTS CARL GULF SERVICE STN	Gasoline Service Stations
1974	METCALF L A SERVICE STATION	Gasoline Service Stations
1975	METCALF L A SERVICE STATION	Gasoline Service Stations
1976	METCALF L A SERVICE STATION	Gasoline Service Stations
1977	METCALF L A SERVICE STATION	Gasoline Service Stations

METCALF L A SERVICE STATION (Continued) **1020256188**

1978	METCALF L A SERVICE STATION	Gasoline Service Stations
1979	METCALF L A SERVICE STATION	Gasoline Service Stations
1980	METCALF L A SERVICE STATION	Gasoline Service Stations
1982	METCALF L A SERVICE STATION	Gasoline Service Stations
1983	METCALF L A SERVICE STATION	Gasoline Service Stations

LQ1962 **MAGNOLIA PETROLEUM CO.** **TX HIST UST** **S111678738**
NE **300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
241 ft. **Site 4 of 7 in cluster LQ**

Actual:
454 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM CO.
Address:	300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0317
HID UST:	317
Inspection:	04/24/2009
Due:	04/24/2012

LQ1963 **A.E. SCHUTZE** **TX HIST UST** **S111678540**
NE **300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
241 ft. **Site 5 of 7 in cluster LQ**

Actual:
454 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	A.E. SCHUTZE
Address:	300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0277
HID UST:	277
Inspection:	04/24/2009
Due:	04/24/2012

LQ1964 **J.H. STELFOX** **TX HIST UST** **S111678695**
NE **300 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
241 ft. **Site 6 of 7 in cluster LQ**

Actual:
454 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	J.H. STELFOX
Address:	300 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0451
HID UST:	451
Inspection:	04/24/2009
Due:	04/24/2012

LM1965 WNW < 1/8 0.046 mi. 241 ft. | **AT&T SOC XU3382**
819 N LOOP W
AUSTIN, TX
Site 2 of 3 in cluster LM | **TX RDR** | **S127526966**
N/A

Actual: 683 ft.
Focus Map: 8

RDR:

RDR ID:	17569
Facility ID:	20853
RN:	Not reported
CN:	Not reported
Name:	AT&T SOC XU3382
Address:	819 N LOOP W
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/19/2008
Due Date:	10/18/2008
Tank Owner:	SOUTHWESTERN BELL
Contact Person:	MARK DINUBILA
Report:	REL DET
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/26/2008
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	104122
Comments:	DOES IT NEED TO BE REOPENED?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/26/2008
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

1966 WNW < 1/8 0.046 mi. 241 ft. | **WESTERN AUTO**
9316 N LAMAR BLVD
AUSTIN, TX 78753 | **TX LPST** **TX UST** | **U003566363**
N/A

Actual: 679 ft.
Focus Map: 6

LPST:

Name:	WESTERN AUTO
Address:	9316 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0053408
LPST Id:	097847
Facility Location:	N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/28/1991
Entered Date:	01/29/1991
Reported Date:	01/28/1991
Closure Date:	06/01/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2

WESTERN AUTO (Continued) **U003566363**

Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	ALAN TERHUNE
Responsible Party Address:	2107 GRAND AVE
Responsible Party City,St,Zip:	KANSAS CITY, MO 64108
Responsible Party Telephone:	816/346-4281
Reported Date:	01/28/1991
Case Start Date:	06/01/1991
Reference Number:	RN101506301
Project Manager:	HWELCH

UST:

Name:	WESTERN AUTO
Address:	9316 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787534104
AI Number:	53408
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	384186332002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	WESTERN AUTO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128379991
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/12/1990
Signature Name/Title On Earliest Reg Form:	LEE MECHAM,PRES
Application Received Date On Earliest Reg Form:	04/20/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600263578
Owner Last Name:	WESTERN AUTO SUPPLY COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

WESTERN AUTO (Continued) **U003566363**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	788295422001297
Additional ID:	384186332002156
AI Number:	53408
Owner Effective Begin Date:	09/01/1987
State Tax ID:	15419116866
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	03/01/1987
Tank Registration Date:	04/20/1990
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	131740
Facility ID:	72446
Ai Number:	53408
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/17/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

WESTERN AUTO (Continued) **U003566363**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	103011
UST ID:	131740
AI Number:	53408
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

WESTERN AUTO (Continued) **U003566363**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WESTERN AUTO SUPPLY COMPANY
Contact Mailing Address (Delivery):	9680 MARION RDG
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	KANSAS CITY, MO 64137 1284
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72446
Additional ID:	384186332002156
Princ ID:	788295422001297
AI Number:	53408
Facility Name:	WESTERN AUTO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ALAN TERHUNE/

LR1967 **F M PAULS CONCRETE CONTRACTOR** **TX UST** **U001263773**
ESE **6506 SHIRLEY AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.046 mi.
241 ft. **Site 1 of 5 in cluster LR**

Actual:
713 ft.

Focus Map:
6

UST:

Name:	F M PAULS CONCRETE CONTRACTOR
Address:	6506 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX 787524024
AI Number:	30301
Facility Type:	UNKNOWN
Facility Begin Date:	11/03/1986
Facility Status:	INACTIVE
Additional ID:	421520772002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	BOBBY GENE DORAN,PRESIDENT
Contact Organization Name:	F M PAULS CONCRETE CONTRACTOR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

F M PAULS CONCRETE CONTRACTOR (Continued) **U001263773**

Contact Telephone:	5124530644
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/03/1986
Signature Name/Title On Earliest Reg Form:	BOBBY GENE DORAN,PRESIDENT
Application Received Date On Earliest Reg Form:	06/24/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778070
Owner Last Name:	PAULS F M
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	411520762002053
Additional ID:	421520772002053
AI Number:	30301
Owner Effective Begin Date:	11/03/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	06/24/1986
Number of Compartments:	1
Tank Capacity:	1030
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	79768
Facility ID:	64780
Ai Number:	30301
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/24/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

F M PAULS CONCRETE CONTRACTOR (Continued) **U001263773**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1030
UST Comprt ID:	73760
UST ID:	79768
AI Number:	30301
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

F M PAULS CONCRETE CONTRACTOR (Continued) **U001263773**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PAULS F M
Contact Mailing Address (Delivery):	5300 FENCE ROW
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 3010
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	64780
Additional ID:	421520772002053
Princ ID:	411520762002053
AI Number:	30301
Facility Name:	F M PAULS CONCRETE CONTRACTOR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	F M PAUL CONCRETE
Address:	6506 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0247

F M PAULS CONCRETE CONTRACTOR (Continued) **U001263773**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LS1968 **COMMUNICATION SPECIALISTS** **TX Ind. Haz Waste** **S102758139**
WNW **603 DAVIS ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.046 mi.
242 ft. **Site 1 of 3 in cluster LS**

Actual:
463 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	COMMUNICATION SPECIALISTS
Address:	603 DAVIS ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	77588
Registration Initial Notification Date:	07/28/1992
Registration Last Amendment Date:	07/08/2020
EPA Identification:	TXD988075248
Primary NAICS Code:	323110
Status Change Date:	19920728
Land Type:	PRIVATE
Description of Facility Site Location:	603 Davis St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CAPITAL SPECTRUM LP
Contact Name:	STAN ELLIOTT
Contact Telephone Number:	512-4824270
Mailing Address:	PO BOX 17936
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787607936
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31814
Site Owner Tax ID:	741930638
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200709
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported

COMMUNICATION SPECIALISTS (Continued) **S102758139**

Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CAPITAL SPECTRUM LP
Operator Address:	PO BOX 17936
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78760
Operator Country:	UNITED STA
Operator Telephone:	1-512-4824270
Operator Fax Number:	1-512-4783863
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17419306380
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITAL SPECTRUM LP
Owner Mailing Address:	PO BOX 17936
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78760
Owner Country:	UNITED STA
Owner Telephone:	1-512-4824270
Owner Fax:	1-512-4783863
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17419306380
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported

COMMUNICATION SPECIALISTS (Continued) **S102758139**

Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 17936
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4824270
Contact Fax:	1-512-4783863
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 17936
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4824270
Contact Fax:	1-512-4783863
Contact Email:	Not reported

Contact Name:	STAN ELLIOTT
Contact Title:	PRODUCTION MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 17936
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4824270
Contact Fax:	1-512-4783863
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	151657
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001604H
Waste Code Status:	INACTIVE
Waste Form:	604
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	WASTE INK THROUGH OPERATION PROCEDURES
Standard Industrial Code:	27520
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

COMMUNICATION SPECIALISTS (Continued) **S102758139**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323110
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	172405
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Printing press blanket and roller wash solvent mixture which is used for cleanin
Standard Industrial Code:	27520
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	259390
Texas Waste Code:	Not reported
Texas Waste Code 2:	B2B46041
Waste Code Status:	INACTIVE
Waste Form:	604
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported

COMMUNICATION SPECIALISTS (Continued) **S102758139**

EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 17936
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78760
AR Number:	0000310222
Principal Name:	CAPITAL SPECTRUM LP
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 17936
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78760
AR Number:	0000310222
Principal Name:	CAPITAL SPECTRUM LP
Attention Name:	Not reported
Attention Suffix:	HWG

LS1969 **COMMUNICATION SPECIALISTS** **RCRA NonGen / NLR** **1000836384**
WNW **603 DAVIS ST** **FINDS** **TXD988075248**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.046 mi.
242 ft. **Site 2 of 3 in cluster LS**

Actual:
463 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20200708
Handler Name:	Communication Specialists
Handler Address:	603 DAVIS ST
Handler City,State,Zip:	AUSTIN, TX 78701-4207
EPA ID:	TXD988075248
Contact Name:	STAN ELLIOTT
Contact Address:	PO BOX 17936
Contact City,State,Zip:	AUSTIN, TX 78760-7936
Contact Telephone:	512-482-4270
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported

COMMUNICATION SPECIALISTS (Continued) **1000836384**

Mailing Address:	PO BOX 17936
Mailing City,State,Zip:	AUSTIN, TX 78760-7936
Owner Name:	Communication Specialists Inc
Owner Type:	Private
Operator Name:	Communication Specialists Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200716
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent

COMMUNICATION SPECIALISTS (Continued) **1000836384**

Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COMMUNICATION SPECIALISTS INC
Legal Status:	Private
Date Became Current:	20081118
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 17936
Owner/Operator City,State,Zip:	AUSTIN, TX 78760
Owner/Operator Telephone:	512-482-4270
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COMMUNICATION SPECIALISTS INC
Legal Status:	Private
Date Became Current:	20081118
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 17936
Owner/Operator City,State,Zip:	AUSTIN, TX 78760
Owner/Operator Telephone:	512-482-4270
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COMMUNICATION SPECIALISTS INC
Legal Status:	Private
Date Became Current:	20020709
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 17936
Owner/Operator City,State,Zip:	AUSTIN, TX 78760-7936
Owner/Operator Telephone:	512-482-4270
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COMMUNICATION SPECIALISTS INC
Legal Status:	Not reported
Date Became Current:	20020709
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 17936
Owner/Operator City,State,Zip:	AUSTIN, TX 78760
Owner/Operator Telephone:	512-482-4270
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

COMMUNICATION SPECIALISTS (Continued) **1000836384**

Owner/Operator Name: COMMUNICATION SPECIALISTS INC
Legal Status: Not reported
Date Became Current: 20020709
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 17936
Owner/Operator City,State,Zip: AUSTIN, TX 78760
Owner/Operator Telephone: 512-482-4270
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMUNICATION SPECIALISTS INC
Legal Status: Private
Date Became Current: 20020709
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 17936
Owner/Operator City,State,Zip: AUSTIN, TX 78760-7936
Owner/Operator Telephone: 512-482-4270
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOHN H GRAY JR
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 0000000000
Owner/Operator City,State,Zip: 0000000000, TX 00000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19920721
Handler Name: COMMUNICATION SPECLST INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020709
Handler Name: COMMUNICATION SPECIALISTS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

COMMUNICATION SPECIALISTS (Continued) **1000836384**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081118
Handler Name: COMMUNICATION SPECIALISTS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200708
Handler Name: COMMUNICATION SPECIALISTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32311
NAICS Description: PRINTING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005152271

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

COMMUNICATION SPECIALISTS (Continued) **1000836384**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836384
Registry ID:	110005152271
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005152271
Name:	COMMUNICATION SPECIALISTS
Address:	603 DAVIS ST
City,State,Zip:	AUSTIN, TX 78701

JA1970 **MILLNERS SERVICE STATION FILL STA** **EDR Hist Auto** **1013763932**
WNW **827 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
242 ft. **Site 14 of 15 in cluster JA**

Actual:
501 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	MILLNERS SERVICE STATION FILL S	GASOLINE AND OIL SERVICE STATIONS
1953	MILLNERS SERVICE	GASOLINE STATIONS

1971 **CHAMBERLAIN S M GARAGE AUTO REPR** **EDR Hist Auto** **1013756672**
ESE **7209 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.046 mi.
242 ft.

Actual:
731 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1953	CHANEY G M GARAGE	AUTOMOBILE REPAIRING
1965	MURRAYS GARAGE GL	AUTOMOBILE REPAIRING
1970	CHAMBERLAIN S M GARAGE AUTO REP	AUTOMOBILE REPAIRING

JE1972 **MC KEAN W L R** **EDR Hist Auto** **1013760959**
ESE **1610 BRAZOS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
243 ft. **Site 4 of 6 in cluster JE**

Actual:
524 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	MC KEAN W L R	REPAIR SHOPS

CZ1973 WNW < 1/8 0.046 mi. 244 ft. | **OLD HUTS HAMBURGERS 807 WEST 6TH STREET AUSTIN, TX 78702** | **TX HIST UST TX ASBESTOS** | **S111678826 N/A**

Site 9 of 9 in cluster CZ

Actual: 444 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	TEXAS PACIFIC COAL & OIL CO.
Address:	807 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0301
HID UST:	301
Inspection:	02/26/2010
Due:	02/26/2013

ASBESTOS:

Name:	OLD HUTS HAMBURGERS
Address:	807 WEST 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	01/17/2020
Notification Number:	2020000022
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/02/2020
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4

OLD HUTS HAMBURGERS (Continued) **S111678826**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/16/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

KR1974 **RIVER CITY Z SHOP AUTO REPS** **EDR Hist Auto** **1013758360**
ESE **604 6TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.046 mi.
244 ft. **Site 5 of 10 in cluster KR**

Actual:
478 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	RIVER CITY Z SHOP AUTO REPS	AUTOMOBILE REPAIRING

KR1975 **PIT SHOP THE AUTO REPR** **EDR Hist Auto** **1013759262**
ESE **604 6TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
244 ft. **Site 6 of 10 in cluster KR**

Actual:
478 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	PIT SHOP THE AUTO REPR	AUTOMOBILE REPAIRING
1984	B & M DISCOUNT TRANSMISSION AUT	AUTOMOBILE REPAIRING

LO1976 WNW < 1/8 0.046 mi. 244 ft. — **TEXAS GLASS, 808 CAPITOL CT, AUSTIN, TX 78756** — **EDR Hist Auto** — **1022186422 / N/A**

Site 2 of 5 in cluster LO

Actual: 666 ft. — **Focus Map: 8**

EDR Hist Auto

Year:	Name:	Type:
1989	TEXAS GLASS	Automotive Transmission Repair Shops
1990	TEXAS GLASS	Automotive Transmission Repair Shops
1991	TEXAS GLASS	Automotive Transmission Repair Shops
1992	TEXAS GLASS	Automotive Transmission Repair Shops
1993	TEXAS GLASS	Automotive Transmission Repair Shops

KH1977 SSW < 1/8 0.046 mi. 245 ft. — **FRY JOHN L CLOTHES CLNR, 202 CONGRESS AVE, AUSTIN, TX** — **EDR Hist Cleaner** — **1013781624 / N/A**

Site 10 of 19 in cluster KH

Actual: 475 ft. — **Focus Map: 11**

EDR Hist Cleaner

Year:	Name:	Type:
1916	FRY JOHN L CLOTHES CLNR	CLOTHES CLEANERS AND PRESSERS

IZ1978 ESE < 1/8 0.046 mi. 245 ft. — **AUSTEX INTERIORS, 6910 SHIRLEY AVE, AUSTIN, TX 78752** — **TX UST, TX HIST UST** — **U003886480 / N/A**

Site 3 of 3 in cluster IZ

Actual: 714 ft. — **Focus Map: 6**

UST:

Name:	AUSTEX INTERIORS
Address:	6910 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX 787523524
AI Number:	75578
Facility Type:	WHOLESALE
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	759577712003020
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	GUY HOLCOMB,
Contact Organization Name:	AUSTEX INTERIORS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8176927130
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported

AUSTEX INTERIORS (Continued) **U003886480**

Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/10/1991
Signature Name/Title On Earliest Reg Form:	TERRY BROOKS,ENV TEST SERV MGR
Application Received Date On Earliest Reg Form:	04/23/1991
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601532500
Owner Last Name:	HOLCOMB
Owner First Name:	GUY
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	767577702003020
Additional ID:	759577712003020
AI Number:	75578
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/23/1991
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	200992
Facility ID:	115807
Ai Number:	75578
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/18/1991
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

AUSTEX INTERIORS (Continued) **U003886480**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	170174
UST ID:	200992
AI Number:	75578
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

AUSTEX INTERIORS (Continued) **U003886480**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	28746
Cert ID:	75146
UST Comprt ID:	226996
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75408
UST Comprt ID:	226991
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75148
UST Comprt ID:	226998
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75149
UST Comprt ID:	226999
UST ID:	77037
AI Number:	75578

AUSTEX INTERIORS (Continued) **U003886480**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75150
UST Comprt ID:	226995
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75410
UST Comprt ID:	226989
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75411
UST Comprt ID:	226988
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75412
UST Comprt ID:	226987
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75409
UST Comprt ID:	226990
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	75413
UST Comprt ID:	226986
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	229104
UST Comprt ID:	657557
UST ID:	77037
AI Number:	75578
Tank ID:	1

AUSTEX INTERIORS (Continued) **U003886480**

Compartment ID:	A
Self Cert ID:	28746
Cert ID:	245280
UST Comprt ID:	705080
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	261929
UST Comprt ID:	754173
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	280275
UST Comprt ID:	808365
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	297703
UST Comprt ID:	859900
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	299953
UST Comprt ID:	866871
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	315038
UST Comprt ID:	911954
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28746
Cert ID:	330621
UST Comprt ID:	958415
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

AUSTEX INTERIORS (Continued) **U003886480**

Self Cert ID:	28746
Cert ID:	348477
UST Comprt ID:	1012859
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	364558
UST Comprt ID:	1061187
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	381880
UST Comprt ID:	1113977
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	75151
UST Comprt ID:	226994
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	75152
UST Comprt ID:	226993
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	75407
UST Comprt ID:	226992
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28746
Cert ID:	75147
UST Comprt ID:	226997
UST ID:	77037
AI Number:	75578
Tank ID:	1
Compartment ID:	A

AUSTEX INTERIORS (Continued) **U003886480**

Facility Billing Contacts:

Contact Organization Name:	HOLCOMB GUY
Contact Mailing Address (Delivery):	PO BOX 4165
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	WICHITA FALLS, TX 76308 0165
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	115807
Additional ID:	759577712003020
Princ ID:	767577702003020
AI Number:	75578
Facility Name:	AUSTEX INTERIORS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GUY HOLCOMB/

HIST UST AUSTIN:

Name:	AUSTEX INTERIORS
Address:	6910 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0230
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KS1979 **SIMPSON IRA AUTO** **EDR Hist Auto** **1013759755**
ESE **409 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.046 mi.
245 ft. **Site 3 of 5 in cluster KS**

Actual:
460 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	SIMPSON IRA AUTO	AUTOMOBILE REPAIRING
1958	CHAMBERLAINS	AUTOMOBILE REPAIRING

LT1980 **AUSTIN LAUNDRY & DRY CLEANING** **TX HIST UST** **S111678564**
ESE **304 W 15TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.047 mi.
246 ft. **Site 1 of 9 in cluster LT**

Actual:
545 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	AUSTIN LAUNDRY & DRY CLEANING
Address:	304 W 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0400
HID UST:	400
Inspection:	Not reported

AUSTIN LAUNDRY & DRY CLEANING (Continued) **S111678564**

Due: 06/01/2012

1981
NW
< 1/8
0.047 mi.
246 ft.

BRODIE MARKET INC
812 THURMOND ST
AUSTIN, TX 78758

EDR Hist Auto **1021640815**
N/A

Actual:
708 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1997	BRODIE MARKET INC	Gasoline Service Stations, NEC
1998	BRODIE MARKET INC	Gasoline Service Stations, NEC
1999	BRODIE MARKET INC	Gasoline Service Stations, NEC
2000	BRODIE MARKET INC	Gasoline Service Stations, NEC
2001	BRODIE MARKET INC	Gasoline Service Stations, NEC
2002	BRODIE MARKET INC	Gasoline Service Stations, NEC
2003	BRODIE MARKET INC	Gasoline Service Stations, NEC
2004	BRODIE MARKET INC	Gasoline Service Stations, NEC
2005	BRODIE MARKET INC	Gasoline Service Stations, NEC
2011	OMKAR FOOD PLAZA	Grocery Stores
2012	OMKAR FOOD PLAZA	Grocery Stores
2013	OMKAR FOOD PLAZA	Grocery Stores
2014	OMKAR FOOD PLAZA	Grocery Stores

LS1982
WNW
< 1/8
0.047 mi.
246 ft.

TRAMMELL CROW DAVIS STREET WAREHOUSE AUSTIN
602 DAVIS ST
AUSTIN, TX 78701

TX IHW CORR ACTION **S113416909**
N/A

Site 3 of 3 in cluster LS

Actual:
463 ft.

Focus Map:
11

IHW CORR ACTION:

Name:	TRAMMELL CROW DAVIS STREET WAREHOUSE AUSTIN
Address:	602 DAVIS ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	T2013
Location Desc:	Not reported
RN NUM:	RN104657903
Status:	INACTIVE
Status Date:	09/15/2005
EDR Link ID:	T2013
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	09/15/2005
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

LU1983 WNW < 1/8 0.047 mi. 246 ft. | **TUXEDO JUNCTION CLEANERS**
611 W 29TH ST
TRAVIS (County), TX 78705
Site 1 of 5 in cluster LU | **EDR Hist Cleaner** | **1013779701**
N/A

Actual: 595 ft.
Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1970	TUXEDO JUNCTION CLEANERS	CLEANERS AND DYERS

ED1984 WNW < 1/8 0.047 mi. 246 ft. | **U T SUPERIOR DAIRIES**
213 RED RIVER ST
AUSTIN, TX
Site 4 of 4 in cluster ED | **TX HIST UST** | **S128728906**
N/A

Actual: 462 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	U T SUPERIOR DAIRIES
Address:	213 RED RIVER ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0107
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LV1985 ESE < 1/8 0.047 mi. 246 ft. | **SPEEDWAY SER STA**
3706 SPEEDWAY
AUSTIN, TX
Site 1 of 9 in cluster LV | **EDR Hist Auto** | **1013755477**
N/A

Actual: 610 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1935	SPEEDWAY SER STA	GASOLINE AND OIL SERVICE STATIONS

LV1986 ESE < 1/8 0.047 mi. 246 ft. | **FORMER STATION**
3706 SPEEDWAY
AUSTIN, TX
Site 2 of 9 in cluster LV | **TX RDR** | **S127542580**
N/A

Actual: 610 ft.
Focus Map: 8

RDR:

RDR ID:	17067
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FORMER STATION
Address:	3706 SPEEDWAY
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/20/2008
Due Date:	4/20/2008
Tank Owner:	3706 SPEEDWAY LLC
Contact Person:	NICOLO ANDREANI
Report:	RDR

FORMER STATION (Continued) **S127542580**

Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/1/2008
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/1/2008
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LW1987 **STOCKTON J F** **EDR Hist Auto** **1020654039**
WNW **1501 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.047 mi.
247 ft. **Site 1 of 3 in cluster LW**

Actual:
504 ft. EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1969	STOCKTON J F	Gasoline Service Stations
1970	STOCKTON J F	Gasoline Service Stations

1988 **UNIVERSITY WRECKER** **EDR Hist Auto** **1013776951**
NNE **2114 MAXWELL LN** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.047 mi.
247 ft.

Actual:
530 ft. EDR Hist Auto

Focus Map:
19

Year:	Name:	Type:
1975	UNIVERSITY WRECKER ME MAHON JOH	AUTOMOBILE REPAIRING
1996	J&N AUTOMOTIVE	General Automotive Repair Shops
2002	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2003	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2004	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2005	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2006	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2007	ROMY TRANSMISSION	Automotive Transmission Repair Shops
2008	ROMY TRANSMISSION	Automotive Transmission Repair Shops

KW1989 NNE < 1/8 0.047 mi. 247 ft. | **ARMY FUTURES COMMAND, TX** | **DOD** | **CUSA401794 N/A**

Site 3 of 5 in cluster KW

Actual: 513 ft.
Focus Map: 11

DOD:

Site Name:	ARMY FUTURES COMMAND
DOD Component:	Army Active
Joint Base:	N/A
Operating Status:	ACT (Active): Site has an on-going operational/support mission (s).

1990 ESE < 1/8 0.047 mi. 249 ft. | **KXAN-TV 910 BRAZOS ST AUSTIN, TX** | **TX HIST UST** | **S128729557 N/A**

Actual: 531 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	KXAN-TV
Address:	910 BRAZOS ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0165
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KW1991 ESE < 1/8 0.047 mi. 249 ft. | **GULF STATES POWER LTD 800 BRAZOS ST STE 400 AUSTIN, TX 78701** | **EDR Hist Auto** | **1020989480 N/A**

Site 4 of 5 in cluster KW

Actual: 513 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
2010	ETROA GULF COAST LLC	Gasoline Service Stations, NEC
2011	GULF STATES POWER LTD	Gasoline Service Stations, NEC

1992 SW < 1/8 0.047 mi. 250 ft. | **AMERICAN CLEANERS 1717 S PLEASANT VALLEY RD STE 220 AUSTIN, TX 78741** | **TX DRYCLEANERS** | **S108995456 N/A**

Actual: 473 ft.
Focus Map: 15

DRYCLEANERS:

Name:	AMERICAN CLEANERS
Address:	1717 S PLEASANT VALLEY RD STE 220
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104410824
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335

AMERICAN CLEANERS (Continued) **S108995456**

Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	1717 S PLEASANT VALLEY RD STE 220
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104410824
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	1717 S PLEASANT VALLEY RD STE 220
City,State,Zip:	AUSTIN, TX 78741
RN Number:	RN104410824
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES

AMERICAN CLEANERS (Continued) **S108995456**

Gross Receipts: $150,000 OR LESS

Name: AMERICAN CLEANERS
Address: 1717 S PLEASANT VALLEY RD STE 220
City,State,Zip: AUSTIN, TX 78741
RN Number: RN104410824
Region: 11
CN Number: CN600404552
DCR Number: Not reported
AR Number: 24000170
Principal Name: JOASH ENTERPRISES INC
Bill Addr1: PO BOX 160335
Bill Addr2: Not reported
Bill City/State/Zip: AUSTIN, TX 78716 0335
EMail: Not reported
Phone Number: Not reported
Site Name: AMERICAN CLEANERS
Site Type: DROP STATION REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2007
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: $150,000 OR LESS

Name: AMERICAN CLEANERS
Address: 1717 S PLEASANT VALLEY RD STE 220
City,State,Zip: AUSTIN, TX 78741
RN Number: RN104410824
Region: 11
CN Number: CN600404552
DCR Number: Not reported
AR Number: 24000170
Principal Name: JOASH ENTERPRISES INC
Bill Addr1: PO BOX 160335
Bill Addr2: Not reported
Bill City/State/Zip: AUSTIN, TX 78716 0335
EMail: Not reported
Phone Number: Not reported
Site Name: AMERICAN CLEANERS
Site Type: DROP STATION REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2008
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: $150,000 OR LESS

Name: AMERICAN CLEANERS
Address: 1717 S PLEASANT VALLEY RD STE 220
City,State,Zip: AUSTIN, TX 78741
RN Number: RN104410824
Region: 11
CN Number: CN600404552
DCR Number: Not reported
AR Number: 24000170
Principal Name: JOASH ENTERPRISES INC

AMERICAN CLEANERS (Continued) **S108995456**

Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

1993 **NISHIO INTERNATIONAL INC** **EDR Hist Cleaner** **1013785665**
NW **8610 N LAMAR STE 101** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.047 mi.
250 ft.

Actual:
684 ft.

EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1984	GARNETT LEWIS CLEANERS	CLEANERS AND DYERS
1986	NISHIO INTERNATIONAL INC	Drycleaning Plants, Except Rugs
1987	NISHIO INTERNATIONAL INC	Drycleaning Plants, Except Rugs

---

LX1994 **RUSHINGS SYLVAN W ENCO PRODUCTS GAS ST** **EDR Hist Auto** **1013761337**
WNW **800 W 6TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78703**
0.048 mi.
251 ft. **Site 1 of 15 in cluster LX**

Actual:
447 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1969	RUSHING SYLVAN W	Gasoline Service Stations
1970	RUSHINGS SYLVAN W ENCO PRODUCTS	GASOLINE STATIONS
1970	RUSHING SYLVAN W	Gasoline Service Stations
1971	RUSHING SYLVAN W	Gasoline Service Stations
1972	RUSHING SYLVAN W	Gasoline Service Stations
1973	RUSHING SYLVAN W	Gasoline Service Stations
1974	RUSHING SYLVAN W	Gasoline Service Stations
1975	RUSHING SYLVAN W	Gasoline Service Stations

LX1995 WNW < 1/8 0.048 mi. 251 ft. **CHARLTON & CROCKET, INC.** **TX HIST UST** **S128729187**
800 W 6TH ST **N/A**
AUSTIN, TX

Site 2 of 15 in cluster LX

Actual: 447 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CHARLTON & CROCKET, INC.
Address:	800 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0115
HID UST:	115
Inspection:	11/02/2009
Due:	11/02/2012

LX1996 WNW < 1/8 0.048 mi. 251 ft. **FORMER DOWNTOWN AUTOMOTIIVE** **TX HIST UST** **S128728735**
800 W 6TH ST **N/A**
AUSTIN, TX

Site 3 of 15 in cluster LX

Actual: 447 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	FORMER DOWNTOWN AUTOMOTIIVE
Address:	800 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	3335
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LX1997 WNW < 1/8 0.048 mi. 251 ft. **FORMER DOWNTOWN AUTOMOTIVE** **TX UST** **U004154745**
800 W 6TH ST **N/A**
AUSTIN, TX 78701

Site 4 of 15 in cluster LX

Actual: 447 ft.
Focus Map: 11

UST:

Name:	FORMER DOWNTOWN AUTOMOTIVE
Address:	800 W 6TH ST
City,State,Zip:	AUSTIN, TX 787012722
AI Number:	83660
Facility Type:	RETAIL
Facility Begin Date:	03/01/2010
Facility Status:	INACTIVE
Additional ID:	763485032010133
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	DAVID COX,
Contact Organization Name:	FORMER DOWNTOWN AUTOMOTIVE

FORMER DOWNTOWN AUTOMOTIVE (Continued) **U004154745**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124931084
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/05/2010
Signature Name/Title On Earliest Reg Form:	DAVID COX,
Application Received Date On Earliest Reg Form:	04/08/2010
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN603673484
Owner Last Name:	FORTIS COMMUNITIES-AUSTIN LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	321479562010138
Additional ID:	763485032010133
AI Number:	83660
Owner Effective Begin Date:	03/01/2010
State Tax ID:	32036788407
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/09/2010
Number of Compartments:	1
Tank Capacity:	750
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	213338
Facility ID:	128034
Ai Number:	83660
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/26/2010
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS

FORMER DOWNTOWN AUTOMOTIVE (Continued) **U004154745**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	750
UST Comprt ID:	178896
UST ID:	213338
AI Number:	83660
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported

FORMER DOWNTOWN AUTOMOTIVE (Continued) **U004154745**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	22791
Facility ID:	128034
AI Number:	83660
Application Received Date:	03/01/2010
Scheduled Construction Date:	03/22/2010
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported

FORMER DOWNTOWN AUTOMOTIVE (Continued) **U004154745**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	70760
General Desc Of Prop Construct:	REMOVAL OF UNKNOWN WAST OIL UST LOCATED BEHIND HISTORIC SERVICE STATION BUILDING . BASE ON FIELD OBSERVATIONS, UST IS ASSUMED TO HAVE CAPACITY OF 500 GALLONS. R ELEASE DERMINATION ACTIVITIES WILL BE CONDUCTED IN ACCORDANCE WITH RG-11.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	23916
UST ID:	Not reported
NOC ID:	22791
AI Number:	83660
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON
Representative Name:	KEVIN DENSON
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	23915
UST ID:	Not reported
NOC ID:	22791
AI Number:	83660
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000050
Company Name:	GAINCO INC
Representative Name:	KEVIN MURPHY
Mailing Address (Delivery):	11 NAFTA CIRCLE
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

FORMER DOWNTOWN AUTOMOTIVE (Continued) **U004154745**

Email Address:	Not reported
Cont/Cons/Installer ID:	23917
UST ID:	Not reported
NOC ID:	22791
AI Number:	83660
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000050
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FORTIS COMMUNITIES AUSTIN LP
Contact Mailing Address (Delivery):	3801 BEE CAVES RD STE 125
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	WEST LAKE HILLS, TX 78746 6761
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	128034
Additional ID:	763485032010133
Princ ID:	321479562010138
AI Number:	83660
Facility Name:	FORMER DOWNTOWN AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DAVID COX/

LX1998 **FORMER DOWNTOWN AUTOMOTIVE** **TX RDR** **S126814128**
WNW **800 W 6TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.048 mi.
251 ft. **Site 5 of 15 in cluster LX**

Actual:
447 ft.

Focus Map:
11

RDR:

RDR ID:	18816
Facility ID:	0
RN:	Not reported
CN:	Not reported

FORMER DOWNTOWN AUTOMOTIVE (Continued) **S126814128**

Name:	FORMER DOWNTOWN AUTOMOTIVE
Address:	800 W 6TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/6/2010
Due Date:	6/5/2010
Tank Owner:	FORTIS COMMUNITIES-AUSTIN
Contact Person:	MR DAVID COX
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/3/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/3/2010
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN105927735
Name:	FORMER DOWNTOWN AUTOMOTIVE
Address:	800 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2722
Status:	ACTIVE
Status Date:	5/13/2010
Customer Number:	CN603673484
Customer Name:	FORTIS COMMUNITIES-AUSTIN LP
Customer Legal Name:	Fortis Communities-Austin, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	3/1/2010
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN105927735
Name:	FORMER DOWNTOWN AUTOMOTIVE
Address:	800 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2722
Status:	ACTIVE
Status Date:	5/13/2010
Customer Number:	CN601254600
Customer Name:	UNIVERSAL ENTERPRISES INC
Customer Legal Name:	Universal Enterprises, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/1/2010
Affiliation End Date:	3/1/2010 1
Customer Status:	ACTIVE

FORMER DOWNTOWN AUTOMOTIVE (Continued) **S126814128**

Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN105927735
Name:	FORMER DOWNTOWN AUTOMOTIVE
Address:	800 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2722
Status:	ACTIVE
Status Date:	5/13/2010
Customer Number:	CN600367262
Customer Name:	CIRRUS LOGIC INC
Customer Legal Name:	Cirrus Logic, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/14/2019
Affiliation End Date:	8/22/2019
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

LY1999 **CRANE & LOCK SERV** **EDR Hist Auto** **1013762525**
NE **344 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.048 mi.
253 ft. **Site 1 of 6 in cluster LY**

Actual:
451 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1935	TEXAS CO THE NO	GASOLINE AND OIL SERVICE STATIONS
1947	LOCK SERVICE STATION FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	CRANE & LOCK SERV	GASOLINE STATIONS
1958	BRALTON CHAS R	GASOLINE STATIONS

LY2000 **BESHEARS C A TEXACO** **EDR Hist Auto** **1020570837**
NE **344 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.048 mi.
253 ft. **Site 2 of 6 in cluster LY**

Actual:
451 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1969	BESHEARS C A TEXACO	Gasoline Service Stations
1969	BESHEARS C A TEXACO	Gasoline Service Stations
1970	BESHEARS C A TEXACO	Gasoline Service Stations
1971	BESHEARS C A TEXACO	Gasoline Service Stations
1972	BESHEARS C A TEXACO	Gasoline Service Stations
1972	SABRSULA LAMBERT	Gasoline Service Stations

LY2001
NE
< 1/8
0.048 mi.
253 ft.

LOCK SERVICE STA FILLING ST
344 CONGRESS AVE S
AUSTIN, TX

Site 3 of 6 in cluster LY

EDR Hist Auto **1013760716**
N/A

Actual:
451 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1940	LOCK SERVICE STA FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1965	MC COWN ED TEXACO SERVICE	GASOLINE STATIONS
1970	LAMBERTS TEXACO SERVICE STATION	GASOLINE STATIONS

LX2002
WNW
< 1/8
0.048 mi.
254 ft.

RUSHINGS SYLVAN W EXXON PRODUCTS GAS ST
800 6TH ST W
TRAVIS (County), TX 78703

Site 6 of 15 in cluster LX

EDR Hist Auto **1013767324**
N/A

Actual:
447 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	RUSHINGS SYLVAN W EXXON PRODUCT	GASOLINE STATIONS

LX2003
WNW
< 1/8
0.048 mi.
254 ft.

RUSHINGS SYLVAN W ENCO
800 6TH ST W
AUSTIN, TX

Site 7 of 15 in cluster LX

EDR Hist Auto **1013753717**
N/A

Actual:
447 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	RUSHINGS SYLVAN W ENCO	GASOLINE STATIONS
1980	DEVORSKY ROBT EXXON PRODUCTS GA	GASOLINE STATIONS

LX2004
WNW
< 1/8
0.048 mi.
254 ft.

HUMBLE OIL & REF CO
800 6TH W
AUSTIN, TX

Site 8 of 15 in cluster LX

EDR Hist Auto **1013772521**
N/A

Actual:
447 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	HUMBLE OIL & REF CO	GASOLINE AND OIL SERVICE STATIONS
1935	HUMBLE OIL & REFG	GASOLINE AND OIL SERVICE STATIONS
1947	WHITEHEAD SERV STA	GASOLINE AND OIL SERVICE STATIONS

LR2005 **PARAGON PRINTING & MAILING** **TX Ind. Haz Waste** **S102756723**
ESE **706 BRENTWOOD ST STE C** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.048 mi.
254 ft. **Site 2 of 5 in cluster LR**

Actual:
712 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	PARAGON PRINTING & MAILING
Address:	706 BRENTWOOD ST STE C
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	75720
Registration Initial Notification Date:	02/27/1992
Registration Last Amendment Date:	12/28/2021
EPA Identification:	Not reported
Primary NAICS Code:	323119
Status Change Date:	19920227
Land Type:	PRIVATE
Description of Facility Site Location:	706 C Brentwood, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	HARP ENTERPRISES INC
Contact Name:	JIM BERRY
Contact Telephone Number:	512-4591273
Mailing Address:	706 BRENTWOOD ST # C
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524042
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30066
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20211229
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

PARAGON PRINTING & MAILING (Continued) **S102756723**

Ind. Haz Waste:

Operator Name:	HARP ENTERPRISES INC
Operator Address:	706 BRENTWOOD ST STE C
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4591273
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17426638056
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	HARP ENTERPRISES INC
Owner Mailing Address:	706 BRENTWOOD ST STE C
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4591273
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17426638056
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	706 BRENTWOOD ST STE C
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4591273
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	706 BRENTWOOD ST STE C
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4591273
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JIM BERRY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	706 BRENTWOOD ST # C
Contact Address 2:	Not reported

PARAGON PRINTING & MAILING (Continued) **S102756723**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4591273
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	140223
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	27590
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013925
Primary NAICS Code:	323119
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100658145
Name:	PARAGON PRINTING & MAILING
Address:	706 BRENTWOOD ST STE C
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4042
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603895095
Customer Name:	HARP ENTERPRISES INC
Customer Legal Name:	Harp Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323119
Primary NAICS Industry Type Description:	Other Commercial Printing
Physical Location Description:	706 C Brentwood, Austin, TX

Regulated Entity Number:	RN100658145

PARAGON PRINTING & MAILING (Continued) **S102756723**

Name:	PARAGON PRINTING & MAILING
Address:	706 BRENTWOOD ST STE C
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4042
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603895095
Customer Name:	HARP ENTERPRISES INC
Customer Legal Name:	Harp Enterprises, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	323119
Primary NAICS Industry Type Description:	Other Commercial Printing
Physical Location Description:	706 C Brentwood, Austin, TX

LZ2006 **STOP N GO MARKET 2101** **TX LPST** **U001276603**
WNW **111 W WILLIAM CANNON DR** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX HIST UST**
0.048 mi.
255 ft. **Site 1 of 5 in cluster LZ**

Actual:
664 ft.

Focus Map:
17

LPST:

Name:	AUSTIN FOUR CORNERS OLD STOP N GO
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0044924
LPST Id:	105550
Facility Location:	111 WEST WILLIAM CANNON
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/14/1992
Entered Date:	01/11/1993
Reported Date:	12/14/1992
Closure Date:	03/23/1993
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE NORWICH
Responsible Party Address:	3655 RUFFIN RD 210
Responsible Party City,St,Zip:	SAN DIEGO, CA 92123
Responsible Party Telephone:	619/268-0255
Reported Date:	12/14/1992
Case Start Date:	03/23/1993
Reference Number:	RN100694439
Project Manager:	HWELCH

UST:

Name:	STOP N GO MARKET 2101
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 787455675

STOP N GO MARKET 2101 (Continued) **U001276603**

AI Number:	44924
Facility Type:	RETAIL
Facility Begin Date:	10/21/1987
Facility Status:	INACTIVE
Additional ID:	641844092002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	STOP N GO MARKET 2101
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123235807
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/05/1987
Signature Name/Title On Earliest Reg Form:	WILLIAM CALVERT,GAS MKTG MGR
Application Received Date On Earliest Reg Form:	06/11/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	641844092002156
AI Number:	44924
Owner Effective Begin Date:	10/10/2000
State Tax ID:	17425053794
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

STOP N GO MARKET 2101 (Continued) **U001276603**

Tank:

Install Date:	03/01/1987
Tank Registration Date:	06/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	117654
Facility ID:	61297
Ai Number:	44924
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/10/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N

STOP N GO MARKET 2101 (Continued) **U001276603**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	59972
UST ID:	117654
AI Number:	44924
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17582
Cert ID:	153550
UST Comprt ID:	453855
UST ID:	163941
AI Number:	44924
Tank ID:	2A

STOP N GO MARKET 2101 (Continued) **U001276603**

Compartment ID:	A
Self Cert ID:	17582
Cert ID:	153549
UST Comprt ID:	453854
UST ID:	163941
AI Number:	44924
Tank ID:	2A
Compartment ID:	A
Install Date:	03/01/1987
Tank Registration Date:	06/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	117655
Facility ID:	61297
Ai Number:	44924
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/10/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

STOP N GO MARKET 2101 (Continued) **U001276603**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	59973
UST ID:	117655
AI Number:	44924
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

STOP N GO MARKET 2101 (Continued) **U001276603**

Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17582
Cert ID:	153550
UST Comprt ID:	453855
UST ID:	163941
AI Number:	44924
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17582
Cert ID:	153549
UST Comprt ID:	453854
UST ID:	163941
AI Number:	44924
Tank ID:	2A
Compartment ID:	A
Install Date:	03/01/1987
Tank Registration Date:	06/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	117656
Facility ID:	61297
Ai Number:	44924
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/10/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

STOP N GO MARKET 2101 (Continued) **U001276603**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	59974
UST ID:	117656
AI Number:	44924
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

STOP N GO MARKET 2101 (Continued) **U001276603**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17582
Cert ID:	153550
UST Comprt ID:	453855
UST ID:	163941
AI Number:	44924
Tank ID:	2A
Compartment ID:	A
Self Cert ID:	17582
Cert ID:	153549
UST Comprt ID:	453854
UST ID:	163941
AI Number:	44924
Tank ID:	2A
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61297
Additional ID:	641844092002156
Princ ID:	765580132003199
AI Number:	44924
Facility Name:	STOP N GO MARKET 2101
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	STOP-N-GO #2101
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0368
HID UST:	Not reported
Inspection:	Not reported

STOP N GO MARKET 2101 (Continued) **U001276603**

Due: Not reported

LZ2007 **CLASSY CLEANERS SOUTH OAKS** **TX Ind. Haz Waste** **S103608259**
WNW **111 W WILLIAM CANNON DR** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.048 mi.
255 ft. **Site 2 of 5 in cluster LZ**

Actual:
664 ft.

Focus Map:
17

Ind. Haz Waste:

Name:	CLASSY CLEANERS SOUTH OAKS
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	72344
Registration Initial Notification Date:	03/06/1987
Registration Last Amendment Date:	01/15/2002
EPA Identification:	TXD982555492
Primary NAICS Code:	Not reported
Status Change Date:	19870306
Land Type:	PRIVATE
Description of Facility Site Location:	111 W William Cannon Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CLASSY CLEANERS
Contact Name:	ROBERT WHEELER
Contact Telephone Number:	512-4421442
Mailing Address:	PO BOX 43062
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787040045
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26785
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040303
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported

CLASSY CLEANERS SOUTH OAKS (Continued) **S103608259**

Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CLASSY CLEANERS INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	CLASSY CLEANERS
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	30008976885
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CLASSY CLEANERS INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	CLASSY CLEANERS
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	30008976885
Owner Bankruptcy Code:	Not reported

CLASSY CLEANERS SOUTH OAKS (Continued) **S103608259**

Ind. Haz Waste:

Contact Name:	ROBERT WHEELER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 43062
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4421442
Contact Fax:	Not reported
Contact Email:	Not reported

LZ2008 **CLASSY CLEANERS INC** **RCRA NonGen / NLR** **1000386969**
WNW **111 W WILLIAM CANNON DR** **FINDS** **TXD982555492**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.048 mi.
255 ft. **Site 3 of 5 in cluster LZ**

Actual:
664 ft.

Focus Map:
17

RCRA Listings:

Date Form Received by Agency:	20020115
Handler Name:	Classy Cleaners Inc
Handler Address:	W WILLIAM CANNON DR
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD982555492
Contact Name:	ROBERT WHEELER
Contact Address:	PO BOX 43062
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-442-1442
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 43062
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Classy Cleaners Inc
Owner Type:	Private
Operator Name:	Classy Cleaners Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CLASSY CLEANERS INC (Continued) **1000386969**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: TQS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CLASSY CLEANERS INC (Continued) **1000386969**

Owner/Operator Indicator:	Owner
Owner/Operator Name: CLASSY CLEANERS INC	
Legal Status:	Private
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 43062
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-442-1442
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CLASSY CLEANERS INC	
Legal Status:	Private
Date Became Current:	20020115
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 43062
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-442-1442
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19880804
Handler Name: CLASSY CLNRS FOUR CORNERS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020115
Handler Name: CLASSY CLEANERS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CLASSY CLEANERS INC (Continued) **1000386969**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005108285

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000386969
Registry ID:	110005108285
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005108285
Name:	CLASSY CLEANERS INC
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745

LZ2009 **TQS** **TX Ind. Haz Waste** **S102755918**
WNW **111 W WILLIAM CANNON DR** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.048 mi.
255 ft. **Site 4 of 5 in cluster LZ**

Actual:
664 ft.

Focus Map:
17

Ind. Haz Waste:

Name:	TQS
Address:	111 W WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	74633
Registration Initial Notification Date:	08/08/1988
Registration Last Amendment Date:	12/02/2019
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19880808
Land Type:	PRIVATE
Description of Facility Site Location:	111 W William Cannon Drive, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

TQS (Continued) **S102755918**

Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	TQS INC
Contact Name:	RN WHEELER
Contact Telephone Number:	512-4421442
Mailing Address:	PO BOX 43062
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787040045
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29002
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191203
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	TQS INC
Owner Mailing Address:	PO BOX 43062
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4421442
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17605128911
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 43062
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4421442
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RN WHEELER
Contact Title:	ENV MGR

TQS (Continued) **S102755918**

Contact Role:	PRICONT
Contact Address:	PO BOX 43062
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4421442
Contact Fax:	Not reported
Contact Email:	Not reported

LZ2010 **BRAKE SPECIALIST INC** **EDR Hist Auto** **1021615446**
WNW **111 W WILLIAM CANNON DR** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.048 mi.
255 ft. **Site 5 of 5 in cluster LZ**

Actual:
664 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1992	BRAKE SPECIALIST INC	General Automotive Repair Shops
1993	BRAKE SPECIALIST INC	General Automotive Repair Shops
1994	JOHNSON-SAVAGE INC	Automotive Repair Shops, NEC
1994	BRAKE SPECIALIST INC	General Automotive Repair Shops
1995	BRAKE SPECIALIST INC	General Automotive Repair Shops
1995	JOHNSON-SAVAGE INC	Automotive Repair Shops, NEC
1996	JOHNSON-SAVAGE INC	Automotive Repair Shops, NEC
1996	BRAKE SPECIALIST INC	General Automotive Repair Shops
1997	JOHNSON-SAVAGE INC	Automotive Repair Shops, NEC
1997	BRAKE SPECIALIST INC	General Automotive Repair Shops
1998	BRAKE SPECIALIST INC	General Automotive Repair Shops
1998	JOHNSON-SAVAGE INC	Automotive Repair Shops, NEC
1999	BRAKE SPECIALIST INC	General Automotive Repair Shops
2000	GENOA TRANSMISSIONS INC	General Automotive Repair Shops
2001	GENOA TRANSMISSIONS INC	General Automotive Repair Shops
2002	GENOA TRANSMISSIONS INC	General Automotive Repair Shops
2003	GENOA TRANSMISSIONS INC	General Automotive Repair Shops
2004	GENOA TRANSMISSIONS INC	General Automotive Repair Shops
2005	GENOA TRANSMISSIONS INC	Automotive Transmission Repair Shops
2007	LUGNUTS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2008	LUGNUTS AUTOMOTIVE SERVICE	General Automotive Repair Shops
2010	SUPERIOR AUTOMOTIVE	General Automotive Repair Shops
2011	SUPERIOR AUTOMOTIVE	General Automotive Repair Shops
2012	SUPERIOR AUTOMOTIVE	General Automotive Repair Shops
2013	SUPERIOR AUTOMOTIVE	General Automotive Repair Shops
2014	SUPERIOR AUTOMOTIVE	General Automotive Repair Shops

MA2011 **200 24 AVENUE SERVICE STA** **EDR Hist Auto** **1013761978**
SSW **200 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.048 mi.
255 ft. **Site 1 of 2 in cluster MA**

Actual:
475 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	200 24 AVENUE SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

2012 ESE < 1/8 0.048 mi. 256 ft. | **MEYER CREAMERY COMPANY**
311 W 7TH ST
AUSTIN, TX | **TX HIST UST** | **S111678747**
N/A

Actual: 514 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	MEYER CREAMERY COMPANY
Address:	311 W 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0215
HID UST:	215
Inspection:	03/19/2009
Due:	03/19/2012

MB2013 WNW < 1/8 0.049 mi. 257 ft. | **1601 S 1ST ST**
1601 S 1ST ST
AUSTIN, TX 78704
Site 1 of 7 in cluster MB | **TX UST** | **U003566398**
N/A

Actual: 508 ft.
Focus Map: 14

UST:

Name:	1601 S 1ST ST
Address:	1601 S 1ST ST
City,State,Zip:	AUSTIN, TX 787043046
AI Number:	68903
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	401396472002075
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	TIM PINSON,OWNER
Contact Organization Name:	1601 S 1ST ST
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128369467
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/12/1996
Signature Name/Title On Earliest Reg Form:	TIM PINSON,OWNER
Application Received Date On Earliest Reg Form:	09/13/1996
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600916811
Owner Last Name:	PINSON TIM

1601 S 1ST ST (Continued) **U003566398**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	391396472002075
Additional ID:	401396472002075
AI Number:	68903
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/13/1996
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181346
Facility ID:	104324
Ai Number:	68903
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1996
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

1601 S 1ST ST (Continued) **U003566398**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	170363
UST ID:	181346
AI Number:	68903
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

1601 S 1ST ST (Continued) **U003566398**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/13/1996
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181347
Facility ID:	104324
Ai Number:	68903
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1996
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

1601 S 1ST ST (Continued) **U003566398**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	170364
UST ID:	181347
AI Number:	68903
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

1601 S 1ST ST (Continued) **U003566398**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/13/1996
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181348
Facility ID:	104324
Ai Number:	68903
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1996
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

1601 S 1ST ST (Continued) **U003566398**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	170365
UST ID:	181348
AI Number:	68903
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

1601 S 1ST ST (Continued) **U003566398**

Install Date:	08/31/1987
Tank Registration Date:	09/13/1996
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181349
Facility ID:	104324
Ai Number:	68903
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/30/1996
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

1601 S 1ST ST (Continued) **U003566398**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	170366
UST ID:	181349
AI Number:	68903
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/13/1996
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181350

1601 S 1ST ST (Continued) **U003566398**

Facility ID:	104324
Ai Number:	68903
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/12/1996
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported

1601 S 1ST ST (Continued) **U003566398**

UST Comprt ID:	170367
UST ID:	181350
AI Number:	68903
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PINSON TIM
Contact Mailing Address (Delivery):	11639 RIVER OAKS TRL
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 2835
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	104324
Additional ID:	401396472002075
Princ ID:	391396472002075
AI Number:	68903
Facility Name:	1601 S 1ST ST
AR Number:	Not reported
AR UST Number Suffix:	Not reported

1601 S 1ST ST (Continued) **U003566398**

AR AST Number Suffix: Not reported
Contact Name/Title: TIM PINSON/

MB2014 **J. H. JOHNSON** **TX HIST UST** **S128729469**
WNW **1601 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX**
0.049 mi.
257 ft. **Site 2 of 7 in cluster MB**

Actual:
508 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	J. H. JOHNSON
Address:	1601 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0911
HID UST:	911
Inspection:	Not reported
Due:	06/01/2012

MB2015 **AUTO-FROST** **EDR Hist Auto** **1020799571**
WNW **1601 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.049 mi.
257 ft. **Site 3 of 7 in cluster MB**

Actual:
508 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1969	SCHNELL LEWIS SERVICE STATION	Gasoline Service Stations
1993	AUTO-FROST	Automotive Repair Shops, NEC, NEC
1994	AUTO-FROST	Automotive Repair Shops, NEC, NEC
1995	AUTO-FROST	Automotive Repair Shops, NEC, NEC
1996	AUTO-FROST	Automotive Repair Shops, NEC, NEC

MB2016 **LEWIS SCHNELL** **TX HIST UST** **S128729412**
WNW **1601 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX**
0.049 mi.
257 ft. **Site 4 of 7 in cluster MB**

Actual:
508 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	LEWIS SCHNELL
Address:	1601 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0772
HID UST:	772
Inspection:	Not reported
Due:	06/01/2012

MB2017 WNW < 1/8 0.049 mi. 257 ft. — **LEWIS SCHNELL, 1601 S 1ST ST, AUSTIN, TX** — **TX HIST UST** — **S128729255, N/A**

Site 5 of 7 in cluster MB

Actual: 508 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	LEWIS SCHNELL
Address:	1601 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0370
HID UST:	370
Inspection:	Not reported
Due:	06/01/2012

MB2018 WNW < 1/8 0.049 mi. 257 ft. — **EAGLE BODY SHOP, 1601 S 1ST ST, AUSTIN, TX** — **TX HIST UST** — **S128729092, N/A**

Site 6 of 7 in cluster MB

Actual: 508 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	EAGLE BODY SHOP
Address:	1601 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0629
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KR2019 ESE < 1/8 0.049 mi. 258 ft. — **RUCKER CASS GULF SERV, 601 6TH W, AUSTIN, TX** — **EDR Hist Auto** — **1013757410, N/A**

Site 7 of 10 in cluster KR

Actual: 477 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1940	WALLACES GULF SERVICE STA FILLI	GASOLINE AND OIL SERVICE STATIONS
1947	RUCKER CASS GULF SERV	GASOLINE AND OIL SERVICE STATIONS
1953	WILSONS GULF SERV	GASOLINE STATIONS

IL2020 NE < 1/8 0.049 mi. 259 ft. — **GULF OIL CORPORATION, 504 E 7TH ST, AUSTIN, TX** — **TX HIST UST** — **S111678658, N/A**

Site 21 of 21 in cluster IL

Actual: 489 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	GULF OIL CORPORATION
Address:	504 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0881

GULF OIL CORPORATION (Continued) **S111678658**

HID UST:	881
Inspection:	Not reported
Due:	06/01/2012

LO2021 **FRENCH REVOLUTION AUTO REPR** **EDR Hist Auto** **1013755339**
WNW **807 CAPITOL ST** **N/A**
< 1/8 **TRAVIS (County), TX 78756**
0.049 mi.
260 ft. **Site 3 of 5 in cluster LO**

Actual:
665 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1980	RIVER CITY Z SHOP DATSUN SERV	AUTOMOBILE REPAIRING
1984	RIVER CITY Z SHOP DATSUN SERV	AUTOMOBILE REPAIRING
1988	HAIGHT J & EILERS R	General Automotive Repair Shops
1989	HAIGHT J & EILERS R	General Automotive Repair Shops
1990	FRENCH REVOLUTION AUTO REPR	AUTOMOBILE REPAIRING
1993	FRENCH REVOLUTION	Automotive Repair Shops, NEC
1995	FRENCH REVOLUTION	Automotive Repair Shops, NEC
1996	FRENCH REVOLUTION	Automotive Repair Shops, NEC
1997	FRENCH REVOLUTION	Automotive Repair Shops, NEC
1998	FRENCH REVOLUTION	Automotive Repair Shops, NEC
2014	ERICS EUROPEAN MOTORWERKS LLC	Automotive Repair Shops, NEC

MC2022 **STRUTS CLEANERS** **RCRA NonGen / NLR** **1000428756**
WNW **1106 S 1ST ST 1106-1108 1ST ST** **TXD982759318**
< 1/8 **AUSTIN, TX 78704**
0.049 mi.
261 ft. **Site 1 of 2 in cluster MC**

Actual:
501 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Struts Cleaners
Handler Address:	S 1ST ST 1106-1108 1ST ST
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD982759318
Contact Name:	DAN WIMMER
Contact Address:	PO BOX 27304
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Telephone:	512-371-0020
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 27304
Mailing City,State,Zip:	AUSTIN, TX 78755

STRUTS CLEANERS (Continued) **1000428756**

Owner Name:	Struts Cleaners
Owner Type:	Private
Operator Name:	Struts Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

STRUTS CLEANERS (Continued) **1000428756**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: STRUTS CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 27304
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-371-0020
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: DANIAL B WIMMER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STRUTS CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 27304
Owner/Operator City,State,Zip:	AUSTIN, TX 78755
Owner/Operator Telephone:	512-371-0020
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19890717
Handler Name: STRUTS CLNRS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name: STRUTS CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

STRUTS CLEANERS (Continued) **1000428756**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

MC2023 **STRUTS CLEANERS** **TX Ind. Haz Waste** **S104273942**
WNW **1106 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.049 mi.
261 ft. **Site 2 of 2 in cluster MC**

Actual:
501 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	STRUTS CLEANERS
Address:	1106 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	74797
Registration Initial Notification Date:	06/08/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD982759318
Primary NAICS Code:	Not reported
Status Change Date:	19890608
Land Type:	PRIVATE
Description of Facility Site Location:	1106 S 1st St, 1106-1108 1st St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	STRUTS CLEANERS INC
Contact Name:	DAN WIMMER
Contact Telephone Number:	512-3710020
Mailing Address:	PO BOX 27304
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787552304

STRUTS CLEANERS (Continued) **S104273942**

Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29160
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040428
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	STRUTS CLEANERS INC
Operator Address:	PO BOX 27304
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78755
Operator Country:	UNITED STA
Operator Telephone:	1-512-3710020
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17424330300
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	STRUTS CLEANERS INC
Owner Mailing Address:	PO BOX 27304
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78755
Owner Country:	UNITED STA
Owner Telephone:	1-512-3710020
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17424330300
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 27304
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755

STRUTS CLEANERS (Continued) **S104273942**

Contact Phone:	1-512-3710020
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 27304
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-3710020
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	DAN WIMMER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 27304
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	1-512-3710020
Contact Fax:	Not reported
Contact Email:	Not reported

MD2024 **KINSEYS AUTOMOTIVE** **EDR Hist Auto** **1013757714**
WNW **819 HOUSTON ST** **N/A**
< 1/8 **TRAVIS (County), TX 78756**
0.050 mi.
262 ft. **Site 1 of 2 in cluster MD**

Actual: EDR Hist Auto
692 ft.

Focus Map:
8

Year:	Name:	Type:
1990	KINSEYS AUTOMOTIVE	AUTOMOBILE REPAIRING
1993	SWANNS GARAGE AND RADIATOR	General Automotive Repair Shops
1994	SWANNS GARAGE AND RADIATOR	General Automotive Repair Shops
1995	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
1996	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
1997	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
1998	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
1999	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
2000	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
2001	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
2002	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
2003	SWANNS GARAGE AND RADIATOR SP	General Automotive Repair Shops
2004	SWANNS GARAGE	General Automotive Repair Shops
2005	SWANNS GARAGE	General Automotive Repair Shops
2006	SWANNS GARAGE	General Automotive Repair Shops
2007	SWANNS GARAGE	General Automotive Repair Shops
2008	SWANNS GARAGE	General Automotive Repair Shops
2009	SWANNS GARAGE	General Automotive Repair Shops
2010	SWANNS GARAGE	General Automotive Repair Shops
2011	SWANNS GARAGE	General Automotive Repair Shops
2012	SWANNS GARAGE	General Automotive Repair Shops
2013	SWANNS GARAGE	General Automotive Repair Shops

KINSEYS AUTOMOTIVE (Continued) **1013757714**

2014 SWANNS GARAGE General Automotive Repair Shops

MD2025 **AUSTIN PAN AM CHEMICALS** **TX Ind. Haz Waste** **S102749685**
WNW **819 HOUSTON ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.050 mi.
262 ft. **Site 2 of 2 in cluster MD**

Actual:
692 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	AUSTIN PAN AM CHEMICALS
Address:	819 HOUSTON ST
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	66145
Registration Initial Notification Date:	08/22/1983
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19830822
Land Type:	Not reported
Description of Facility Site Location:	819 Houston ST, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN PAN AM CHEMICALS
Contact Name:	GERALD HIRSCH PHD
Contact Telephone Number:	512-4598762
Mailing Address:	819 HOUSTON ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787562205
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21445
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021106
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported

AUSTIN PAN AM CHEMICALS (Continued) **S102749685**

Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN PAN AM CHEMICALS
Operator Address:	819 HOUSTON ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78756
Operator Country:	UNITED STA
Operator Telephone:	1-512-4598762
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17422453583
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN PAN AM CHEMICALS
Owner Mailing Address:	819 HOUSTON ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Country:	UNITED STA
Owner Telephone:	1-512-4598762
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17422453583
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	819 HOUSTON ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4598762
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	819 HOUSTON ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4598762
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	GERALD HIRSCH PHD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT

AUSTIN PAN AM CHEMICALS (Continued) **S102749685**

Contact Address:	819 HOUSTON ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4598762
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100622323
Name:	AUSTIN PAN AM CHEMICALS
Address:	819 HOUSTON ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-2205
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600331193
Customer Name:	AUSTIN PAN AM CHEMICALS
Customer Legal Name:	Austin Pan Am Chemical, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	819 Houston ST, Austin, TX

JY2026 **0 K GARAGE** **EDR Hist Auto** **1013774018**
NNE **312 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
262 ft. **Site 4 of 6 in cluster JY**

Actual:
481 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	0 K GARAGE	AUTOMOBILE GARAGES

ME2027 **B&N AXLE SERV** **TX Ind. Haz Waste** **S102754062**
NNE **219 W 4TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.050 mi.
263 ft. **Site 1 of 4 in cluster ME**

Actual:
479 ft.

Ind. Haz Waste:

Focus Map:
11

Name:	B&N AXLE SERV
Address:	219 W 4TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72263
Registration Initial Notification Date:	11/14/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD026010702
Primary NAICS Code:	Not reported
Status Change Date:	19861114

B&N AXLE SERV (Continued) **S102754062**

Land Type:	PRIVATE
Description of Facility Site Location:	219 W 4th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	B&N AXLE SERV INC
Contact Name:	TOMMY NOWOTNY
Contact Telephone Number:	512-4768733
Mailing Address:	219 W 4TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787013916
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26705
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030519
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	B&N AXLE SERV INC
Operator Address:	219 W 4THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4768733
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17421785191
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

B&N AXLE SERV (Continued) **S102754062**

Owner Name:	B&N AXLE SERV INC
Owner Mailing Address:	219 W 4THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4768733
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17421785191
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	219 W 4THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4768733
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	219 W 4THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4768733
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	TOMMY NOWOTNY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	219 W 4THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4768733
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100568955
Name:	B&N AXLE SERV
Address:	219 W 4TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3916
Status:	ACTIVE
Status Date:	##########

B&N AXLE SERV (Continued) **S102754062**

Customer Number:	CN600279574
Customer Name:	B&N AXLE SERV INC
Customer Legal Name:	B & N Axle Service, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	219 W 4th St, Austin, TX

Regulated Entity Number:	RN100568955
Name:	B&N AXLE SERV
Address:	219 W 4TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3916
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600279574
Customer Name:	B&N AXLE SERV INC
Customer Legal Name:	B & N Axle Service, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	219 W 4th St, Austin, TX

ME2028 **B&N AXLE SERV INC** **RCRA NonGen / NLR** **1000103477**
NNE **219 W 4TH ST** **FINDS** **TXD026010702**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.050 mi.
263 ft. **Site 2 of 4 in cluster ME**

Actual:
479 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	B&N Axle Serv Inc
Handler Address:	W 4TH ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD026010702
Contact Name:	TOMMY NOWOTNY
Contact Address:	W 4TH ST
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-476-8733
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W 4TH ST

B&N AXLE SERV INC (Continued) **1000103477**

Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	B&N Axle Serv Inc
Owner Type:	Private
Operator Name:	B&N Axle Serv Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before

B&N AXLE SERV INC (Continued) **1000103477**

Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: B&N AXLE SERV INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	219 W 4TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-476-8733
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: B&N AXLE SERV INC	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	219 W 4TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-476-8733
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NOWOTNY TOMMY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19861110
Handler Name: B & N AXLE SVC INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

B&N AXLE SERV INC (Continued) **1000103477**

Receive Date:	20010823
Handler Name: B&N AXLE SERV INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005041418

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000103477
Registry ID:	110005041418
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005041418
Name:	B&N AXLE SERV INC
Address:	219 W 4TH ST
City,State,Zip:	AUSTIN, TX 78701

MF2029 **STOP N GO 2126** **TX UST** **U003040319**
NE **1516 TINNIN FORD RD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX Financial Assurance**
0.050 mi.
263 ft. **Site 1 of 3 in cluster MF**

Actual:
468 ft.

Focus Map:
14

UST:

Name:	STOP N GO 2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX 787413039
AI Number:	39564
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	INACTIVE
Additional ID:	873774132002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	KENT HAMEL,O&E
Contact Organization Name:	STOP N GO 2126
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2103454865
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/25/1986
Signature Name/Title On Earliest Reg Form:	WILLIAM CALVERT,GAS MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	765580132003199
Additional ID:	873774132002149
Ai Number:	39564
Operator CN:	CN602277386
Operator Name:	CST SERVICES LLC
Operator Effective Begin Date:	10/10/2000
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	KENT HAMEL/COORD
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78269-6000
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	3454670
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

STOP N GO 2126 (Continued) **U003040319**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	SAN ANTONIO
Contact Mailing State:	TX
Contact Mailing Zip:	78269
Contact Mailing Zip5:	6000
Contact Phone Number/Ext:	1 210 3454670/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	873774132002149
AI Number:	39564
Owner Effective Begin Date:	10/10/2000
State Tax ID:	17425053794
Contact Role:	OWNCON
Contact Name/Title:	KENT HAMEL/COORDINATOR
Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY

Self Certification:

Self Cert ID:	61084
Cert ID:	63391
AI Number:	39564
Self Certification Date:	08/03/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61084
Cert ID:	63390
AI Number:	39564
Self Certification Date:	07/27/2005

STOP N GO 2126 (Continued) **U003040319**

Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61084
Cert ID:	63389
AI Number:	39564
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61084
Cert ID:	63388
AI Number:	39564
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61084
Cert ID:	63387
AI Number:	39564
Self Certification Date:	07/24/2002

STOP N GO 2126 (Continued) **U003040319**

Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61084
Cert ID:	63386
AI Number:	39564
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104603
Facility ID:	61084
Ai Number:	39564
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	03/26/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

STOP N GO 2126 (Continued) **U003040319**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	54712
UST ID:	104603
AI Number:	39564
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

STOP N GO 2126 (Continued) **U003040319**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104604
Facility ID:	61084
Ai Number:	39564
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	03/26/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

STOP N GO 2126 (Continued) **U003040319**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	54713
UST ID:	104604
AI Number:	39564
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N

STOP N GO 2126 (Continued) **U003040319**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104605
Facility ID:	61084
Ai Number:	39564
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/21/2007
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

STOP N GO 2126 (Continued) **U003040319**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	9816
UST Comprt ID:	54714
UST ID:	104605
AI Number:	39564
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

STOP N GO 2126 (Continued) **U003040319**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	7047
Facility ID:	61084
AI Number:	39564
Application Received Date:	12/05/2006
Scheduled Construction Date:	01/12/2007
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M61205006
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	7046
Facility ID:	61084
AI Number:	39564
Application Received Date:	03/01/2007
Scheduled Construction Date:	03/19/2007
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M70301008

STOP N GO 2126 (Continued) **U003040319**

Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61084
Additional ID:	873774132002149
Princ ID:	765580132003199
AI Number:	39564
Facility Name:	STOP N GO 2126
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	DIAMOND SHAMROCK #2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX
Id UST:	1190
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	STOP N GO 2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	61084
Finass ID:	43469
AI:	39564
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

STOP N GO 2126 (Continued) **U003040319**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

MF2030 **DIAMOND SHAMROCK 2126** **TX LPST** **S108652560**
NE **1516 TINNIN FORD RD** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX GCC**
0.050 mi.
263 ft. **Site 2 of 3 in cluster MF**

Actual:
468 ft.

Focus Map:
14

LPST:

Name:	DIAMOND SHAMROCK 2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0039564
LPST Id:	117256
Facility Location:	1516 TINNIN FORD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/21/2007
Entered Date:	06/25/2007
Reported Date:	04/25/2007
Closure Date:	04/12/2016
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P
Coordinators RPR:	CLW
Responsible Party Name:	Not reported
Responsible Party Contact:	C SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/345-4663
Reported Date:	04/25/2007
Case Start Date:	04/12/2016
Reference Number:	RN102371432
Project Manager:	JHALFHIL

ASBESTOS:

Name:	TINNIN FOOD MART
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/22/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported

DIAMOND SHAMROCK 2126 (Continued) **S108652560**

Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

DIAMOND SHAMROCK 2126 (Continued) **S108652560**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TINNIN FOOD MART
Address:	1516 TINNIN RD
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/16/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported

DIAMOND SHAMROCK 2126 (Continued) **S108652560**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

GCC:

Name:	DIAMOND SHAMROCK 2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	117256
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	4/25/2007
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	-
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	DIAMOND SHAMROCK 2126
Address:	1516 TINNIN FORD RD
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	117256
Contamination Description:	UNKNOWN
Date Of Earliest Known Contamination Confirmation:	4/25/2007
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported

DIAMOND SHAMROCK 2126 (Continued) **S108652560**

Location: Not reported
Data Quality 2: Not reported

Name: DIAMOND SHAMROCK 2126
Address: 1516 TINNIN FORD RD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 117256
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 6/25/2007
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: DIAMOND SHAMROCK 2126
Address: 1516 TINNIN FORD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: *
File Number: 117256
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 6/25/2007
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

MF2031 **DIAMOND SHAMROCK NO 2126** **TX RDR** **S127532152**
NE **1516 TINNIN FORD** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
263 ft. **Site 3 of 3 in cluster MF**

Actual:
468 ft.

Focus Map:
14

RDR:
RDR ID: 15673
Facility ID: 39564
RN: Not reported
CN: Not reported
Name: DIAMOND SHAMROCK NO 2126
Address: 1516 TINNIN FORD
City,State,Zip: AUSTIN, TX
Date Report Received: 11/7/2006

DIAMOND SHAMROCK NO 2126 (Continued) **S127532152**

Due Date:	1/6/2007
Tank Owner:	NATIONAL CONVENIENCE
Contact Person:	SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/3/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/3/2007
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	16043
Facility ID:	39564
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK NO 2126
Address:	1516 TINNIN FORD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/25/2007
Due Date:	6/24/2007
Tank Owner:	NATIONAL CONVENIENCE
Contact Person:	SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	6/25/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	117256
Pre-Existing LPST Number:	Not reported
Comments:	ORIG REC 11/7/2006; LTR 1/3/2007; DOES THIS NEED A LPST#?;LADSCREN SENT 7/2/07
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KY2032 ESE < 1/8 0.050 mi. 263 ft. | **TIRE SERVICE COMPANY**
301 W 5TH ST
AUSTIN, TX | **TX HIST UST** | **S111678833**
N/A

Site 6 of 21 in cluster KY

Actual: 487 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	TIRE SERVICE COMPANY
Address:	301 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0192
HID UST:	192
Inspection:	03/31/2009
Due:	03/31/2012

MG2033 SE < 1/8 0.050 mi. 263 ft. | **THE GOODYEAR TIRE & RUBBER COMPANY**
115 E OLTORF ST
AUSTIN, TX 78704 | **RCRA NonGen / NLR**
FINDS
ECHO | **1000194775**
TXD149980559

Site 1 of 4 in cluster MG

Actual: 600 ft.
Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	The Goodyear Tire & Rubber Company
Handler Address:	E OLTORF ST
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD149980559
Contact Name:	J D TREAT
Contact Address:	N WW WHITE RD
Contact City,State,Zip:	SAN ANTONIO, TX 78219
Contact Telephone:	512-333-1210
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N WW WHITE RD
Mailing City,State,Zip:	SAN ANTONIO, TX 78219
Owner Name:	The Goodyear Tire & Rubber Company
Owner Type:	Private
Operator Name:	The Goodyear Tire & Rubber Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

THE GOODYEAR TIRE & RUBBER COMPANY (Continued) **1000194775**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: THE GOODYEAR TIRE & RUBBER COMPANY	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	631 N WW WHITE RD
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78219
Owner/Operator Telephone:	512-333-1210
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: THE GOODYEAR TIRE & RUBBER COMPANY	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	631 N WW WHITE RD
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78219

THE GOODYEAR TIRE & RUBBER COMPANY (Continued) **1000194775**

Owner/Operator Telephone: 512-333-1210
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GOODYEAR T&R CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19861110
Handler Name: GOODYEAR AUTO SVC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: THE GOODYEAR TIRE & RUBBER COMPANY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

THE GOODYEAR TIRE & RUBBER COMPANY (Continued) **1000194775**

FINDS:
Registry ID: 110005074775

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000194775
Registry ID:	110005074775
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005074775
Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Address:	115 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704

MG2034 **GOODYEAR AUTO SERVICE CENTER AUSTIN** **TX Ind. Haz Waste** **S105491436**
SE **115 E OLTORF ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.050 mi.
263 ft. **Site 2 of 4 in cluster MG**

Actual:
600 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	GOODYEAR AUTO SERVICE CENTER AUSTIN
Address:	115 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	73068
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD149980559
Primary NAICS Code:	Not reported
Status Change Date:	19861107
Land Type:	PRIVATE
Description of Facility Site Location:	115 E Oltorf St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1

GOODYEAR AUTO SERVICE CENTER AUSTIN (Continued) **S105491436**

Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Contact Name:	J D TREAT
Contact Telephone Number:	512-3331210
Mailing Address:	631 N WW WHITE RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	SAN ANTONIO, TX 782192817
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27501
Site Owner Tax ID:	134025324
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030423
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Operator Address:	631 N WW WHITE RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	SAN ANTONIO, TX 78219
Operator Country:	UNITED STA
Operator Telephone:	1-512-3331210
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13402532405
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Owner Mailing Address:	631 N WW WHITE RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	SAN ANTONIO, TX 78219
Owner Country:	UNITED STA
Owner Telephone:	1-512-3331210
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation

GOODYEAR AUTO SERVICE CENTER AUSTIN (Continued) **S105491436**

Owner Tax ID: 13402532405
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OPRCON
Contact Address: 631 N WW WHITE RD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: SAN ANTONIO, TX 78219
Contact Phone: 1-512-3331210
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 631 N WW WHITE RD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: SAN ANTONIO, TX 78219
Contact Phone: 1-512-3331210
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: J TREAT
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 631 N WW WHITE RD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: SAN ANTONIO, TX 78219
Contact Phone: 1-512-3331210
Contact Fax: Not reported
Contact Email: Not reported

CENTRAL REGISTRY:
Regulated Entity Number: RN100705003
Name: GOODYEAR AUTO SERVICE CENTER AUSTIN
Address: 115 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5528
Status: ACTIVE
Status Date: ##########
Customer Number: CN600616049
Customer Name: THE GOODYEAR TIRE & RUBBER COMPANY
Customer Legal Name: The Goodyear Tire & Rubber Company
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/8/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 115 E Oltorf St, Austin, TX

GOODYEAR AUTO SERVICE CENTER AUSTIN (Continued) **S105491436**

Regulated Entity Number:	RN100705003
Name:	GOODYEAR AUTO SERVICE CENTER AUSTIN
Address:	115 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5528
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600616049
Customer Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Customer Legal Name:	The Goodyear Tire & Rubber Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	115 E Oltorf St, Austin, TX

Regulated Entity Number:	RN100705003
Name:	GOODYEAR AUTO SERVICE CENTER AUSTIN
Address:	115 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5528
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600616049
Customer Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Customer Legal Name:	The Goodyear Tire & Rubber Company
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	115 E Oltorf St, Austin, TX

MG2035 **GOODYEAR TIRE & RUBBER AUSTIN** **TX UST** **U003566249**
SE **115 E OLTORF ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.050 mi.
263 ft. **Site 3 of 4 in cluster MG**

Actual:
600 ft.

Focus Map:
14

UST:

Name:	GOODYEAR TIRE & RUBBER AUSTIN
Address:	115 E OLTORF ST
City,State,Zip:	AUSTIN, TX 787045528
AI Number:	13174
Facility Type:	RETAIL
Facility Begin Date:	08/08/1986
Facility Status:	INACTIVE
Additional ID:	875653592002241
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS

GOODYEAR TIRE & RUBBER AUSTIN (Continued) **U003566249**

Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	GOODYEAR TIRE & RUBBER AUSTIN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124521010
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/17/1986
Signature Name/Title On Earliest Reg Form:	R M HELDRIDGE,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600616049
Owner Last Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	231678652001354
Additional ID:	875653592002241
AI Number:	13174
Owner Effective Begin Date:	08/08/1986
State Tax ID:	13402532405
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	34177
Facility ID:	52267
Ai Number:	13174
Tank Id:	1

GOODYEAR TIRE & RUBBER AUSTIN (Continued) **U003566249**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/03/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/05/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	46298
UST ID:	34177
AI Number:	13174

GOODYEAR TIRE & RUBBER AUSTIN (Continued) **U003566249**

Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE GOODYEAR TIRE & RUBBER COMPANY
Contact Mailing Address (Delivery):	1144 E MKT REAL EST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AKRON, OH 44316 0001
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	52267
Additional ID:	875653592002241
Princ ID:	231678652001354
AI Number:	13174
Facility Name:	GOODYEAR TIRE & RUBBER AUSTIN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	S C MAKARA/

LV2036 ESE < 1/8 0.050 mi. 264 ft. | **SPEEDWAY SERVICE STATION**
3714 SPEEDWAY
AUSTIN, TX | **EDR Hist Auto** | **1013758496**
N/A

Site 3 of 9 in cluster LV

Actual: 610 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1929	SPEEDWAY SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS

JY2037 NNE < 1/8 0.050 mi. 264 ft. | **ROBINSON SAML**
316 COLORADO
AUSTIN, TX | **EDR Hist Auto** | **1013755374**
N/A

Site 5 of 6 in cluster JY

Actual: 481 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	ROBINSON SAML	AUTOMOBILE REPAIRING

MH2038 WNW < 1/8 0.050 mi. 264 ft. | **CVS PHARMACY 0213**
5526 5526 S CONGRESS AVE
AUSTIN, TX 78745 | **RCRA NonGen / NLR**
FINDS
ECHO | **1015751296**
TXR000081076

Site 1 of 6 in cluster MH

Actual: 630 ft.

Focus Map: 17

RCRA Listings:

Date Form Received by Agency:	20220328
Handler Name:	Cvs Pharmacy 0213
Handler Address:	5526 S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78745-3106
EPA ID:	TXR000081076
Contact Name:	WENDY BRANT
Contact Address:	1 CVS DR
Contact City,State,Zip:	WOONSOCKET, RI 02895-6146
Contact Telephone:	401-765-1500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1 CVS DR
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cvs Pharmacy Inc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

CVS PHARMACY 0213 (Continued) **1015751296**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220718
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

CVS PHARMACY 0213 (Continued) **1015751296**

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D007
Waste Description: Chromium

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D024
Waste Description: M-Cresol

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U145
Waste Description: Lead Phosphate (Or) Phosphoric Acid, Lead(2+) Salt (2:3)

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20120420
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

CVS PHARMACY 0213 (Continued) **1015751296**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895

CVS PHARMACY 0213 (Continued) **1015751296**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420

CVS PHARMACY 0213 (Continued) **1015751296**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120716
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

CVS PHARMACY 0213 (Continued) **1015751296**

Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120716
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CVS PHARMACY 0213 (Continued) **1015751296**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146

CVS PHARMACY 0213 (Continued) **1015751296**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140301
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160301
Handler Name: CVS PHARMACY 0213	

CVS PHARMACY 0213 (Continued) **1015751296**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180301
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220301
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20120716
Handler Name: CVS PHARMACY INC - STORE 0213	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130212
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CVS PHARMACY 0213 (Continued) **1015751296**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130513
Handler Name: CVS PHARMACY 0213
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140210
Handler Name: CVS PHARMACY 0213
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141023
Handler Name: CVS PHARMACY 0213
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150211
Handler Name: CVS PHARMACY 0213
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CVS PHARMACY 0213 (Continued) **1015751296**

Receive Date:	20180412
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20181206
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20220328
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220328
Handler Name: CVS PHARMACY 0213	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

NAICS Code:	446110

CVS PHARMACY 0213 (Continued) **1015751296**

NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 456110
NAICS Description: PHARMACIES AND DRUG RETAILERS

NAICS Code: 812922
NAICS Description: ONE-HOUR PHOTOFINISHING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070737289

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110054866445

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1015751296
Registry ID: 110054866445
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110054866445
Name: CVS PHARMACY 0213
Address: 5526 5526 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78745

MH2039 **CVS PHARMACY** **TX ASBESTOS** **S112202649**
WNW **5526 S CONGRESS AVE** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.050 mi.
264 ft. **Site 2 of 6 in cluster MH**

Actual:
630 ft.

Focus Map:
17

ASBESTOS:
Name: CVS PHARMACY
Address: 5526 S CONGRESS AVE
City,State,Zip: AUSTIN, TX 78745
Date of inspection: 02/06/2013
Reason for Inspection: Routine
Violation: No

CVS PHARMACY (Continued) **S112202649**

Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/11/2013
Date Routed by Supervisor:	02/11/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

CVS PHARMACY (Continued) **S112202649**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CVS PHARMACY
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2014
Date Routed by Supervisor:	03/04/2014
Date Routed to PSQA:	03/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported

CVS PHARMACY (Continued) **S112202649**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 0213
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	91424
Registration Initial Notification Date:	04/20/2012
Registration Last Amendment Date:	03/28/2022
EPA Identification:	TXR000081076
Primary NAICS Code:	456110
Status Change Date:	20220515
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130391
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000

CVS PHARMACY (Continued) **S112202649**

Site Location Longitude:	-000.000
Last Update to NOR Data:	20220712
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	ATTN WENDY BRANT
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA
Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	ATTN WENDY BRANT
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500
Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported

CVS PHARMACY (Continued) **S112202649**

Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the back storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150211
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150211
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	ATTN WENDY BRANT
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM
Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Role:	PRICONT

CVS PHARMACY (Continued) **S112202649**

Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	349151
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (SILVER, AMMONIUM THIOSULFATE) 9 PGIII
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOTO FIXERDEVELOPER
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	359476
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	UN1760 WASTE CORROSIVE LIQUIDS, N.O.S. (SULFURIC ACID, POTASSIUM HYDROXIDE) 8 PG
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PHOTO CHEMICAL
Primary NAICS Code:	446110
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

CVS PHARMACY (Continued) **S112202649**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349148
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE GAS
Primary NAICS Code:	446110
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	369366
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive liquids, Acidic, n.o.s.; A new hazardous waste determination has been
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACIDIC LIQUID CORRO
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

CVS PHARMACY (Continued) **S112202649**

Ind. Haz Waste:

Waste ID:	349144
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1950 Aerosols, [flammable, (each not exceeding 1 L capacity)] 2.1, PG , ERG-1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349145
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1760 Corrosive liquids, n.o.s. (Sodium Hydroxide, Potassium Carbonate) 8, PG
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC LIQUID CORROSI
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

CVS PHARMACY (Continued) **S112202649**

Waste ID:	349147
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349149
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3139 Oxidizing liquid, n.o.s. (Hydrogen Peroxide) 5.1, PG II, ERG-140
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUID
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	359456
Texas Waste Code:	Not reported

CVS PHARMACY (Continued) **S112202649**

Texas Waste Code 2:	0018001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable solids, organic, n.o.s.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	337625
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077114H
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT PHOTO PROCESSING SOLUTIONS CONTAINING SILVER FROM PHOTO LAB PROCESSING
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349150
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001

CVS PHARMACY (Continued) **S112202649**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349132
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	349146
Texas Waste Code:	Not reported
Texas Waste Code 2:	0211009H
Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H

CVS PHARMACY (Continued) **S112202649**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3077 Environmentally hazardous substances, solid, n.o.s. (Mercury, Silver) 9,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN LAMPS PHOTO
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	407665
Texas Waste Code:	Not reported
Texas Waste Code 2:	0217001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic, liquids, organic, n.o.s., Rx Toxic Liquids, Chloral Hydrate, Chloroform,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	379527
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H

CVS PHARMACY (Continued) **S112202649**

Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389099
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895

CVS PHARMACY (Continued) **S112202649**

AR Number:	0000316732
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316732
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316732
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1 CVS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WOONSOCKET, RI 02895
AR Number:	0000316732
Principal Name:	CVS PHARMACY INC
Attention Name:	Not reported
Attention Suffix:	NWG

MH2040 **FAST STOP STORES INC** **EDR Hist Auto** **1020539295**
WNW **5526 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.050 mi.
264 ft. **Site 3 of 6 in cluster MH**

Actual:
630 ft.

EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1992	FAST STOP STORES INC	Gasoline Service Stations, NEC
1993	FAST STOP STORES INC	Gasoline Service Stations, NEC
1994	FAST STOP STORES INC	Gasoline Service Stations, NEC
1995	FAST STOP STORES INC	Gasoline Service Stations, NEC
1996	FAST STOP STORES INC	Gasoline Service Stations, NEC

MH2041 **FAST STOP 11** **TX UST** **U001277342**
WNW **5526 S CONGRESS AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX Financial Assurance**
0.050 mi.
264 ft. **Site 4 of 6 in cluster MH**

Actual:
630 ft.

Focus Map:
17

UST:

Name:	FAST STOP 11
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787453106
AI Number:	45817
Facility Type:	RETAIL
Facility Begin Date:	08/31/1989
Facility Status:	INACTIVE
Additional ID:	705285312002156
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	JACK RITTER,
Contact Organization Name:	FAST STOP 11
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127626655
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/03/1988
Signature Name/Title On Earliest Reg Form:	JACK RITTER,PRES
Application Received Date On Earliest Reg Form:	03/04/1988
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	904230042002156
Additional ID:	705285312002156
Ai Number:	45817
Operator CN:	CN601272735
Operator Name:	RICON PRODUCTS INC
Operator Effective Begin Date:	05/01/2004
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	JACK RITTER/
Contact Organization Name:	RICON PRODUCTS INC
Contact Mailing Address (Delivery):	PO BOX 2068
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78768-2068
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	7626655
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

FAST STOP 11 (Continued) **U001277342**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601272735
Owner Last Name:	RICON PRODUCTS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 2068
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78768
Contact Mailing Zip5:	2068
Contact Phone Number/Ext:	1 512 4582507/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	904230042002156
Additional ID:	705285312002156
AI Number:	45817
Owner Effective Begin Date:	05/01/2004
State Tax ID:	17422701510
Contact Role:	OWNCON
Contact Name/Title:	/
Contact Organization Name:	RICON PRODUCTS INC

Self Certification:

Self Cert ID:	93097
Cert ID:	149176
AI Number:	45817
Self Certification Date:	01/05/2004
Signature Name/Title:	JACK RITTER PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93097
Cert ID:	149175
AI Number:	45817
Self Certification Date:	01/21/2003

FAST STOP 11 (Continued) **U001277342**

Signature Name/Title:	OCSAR RITTER JR PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93097
Cert ID:	149174
AI Number:	45817
Self Certification Date:	01/07/2002
Signature Name/Title:	JACK D RITTER JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93097
Cert ID:	149173
AI Number:	45817
Self Certification Date:	11/29/2000
Signature Name/Title:	JACK RITTER PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	03/01/1988
Tank Registration Date:	03/04/1988
Number of Compartments:	1

FAST STOP 11 (Continued) **U001277342**

Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	119905
Facility ID:	93097
Ai Number:	45817
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/05/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

FAST STOP 11 (Continued) **U001277342**

Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	151274
UST ID:	119905
AI Number:	45817
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/03/1988

Install Date:	03/01/1988
Tank Registration Date:	03/04/1988
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	119906
Facility ID:	93097
Ai Number:	45817
Tank Id:	4

FAST STOP 11 (Continued) **U001277342**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/05/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	151275
UST ID:	119906
AI Number:	45817

FAST STOP 11 (Continued) **U001277342**

Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/03/1988

Install Date:	03/01/1988
Tank Registration Date:	03/04/1988
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	119907
Facility ID:	93097
Ai Number:	45817
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/05/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

FAST STOP 11 (Continued) **U001277342**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	151276
UST ID:	119907
AI Number:	45817
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

FAST STOP 11 (Continued) **U001277342**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/03/1988

Install Date:	03/01/1988
Tank Registration Date:	03/04/1988
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	119908
Facility ID:	93097
Ai Number:	45817
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/05/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y

FAST STOP 11 (Continued) **U001277342**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	151277
UST ID:	119908
AI Number:	45817
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

FAST STOP 11 (Continued) **U001277342**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/03/1988

Construction Notification:

NOC ID:	14759
Facility ID:	93097
AI Number:	45817
Application Received Date:	03/31/2004
Scheduled Construction Date:	04/19/2004
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M40331012
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	37912

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	15834
UST ID:	Not reported
NOC ID:	14759

FAST STOP 11 (Continued) **U001277342**

AI Number:	45817
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000089
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RICON PRODUCTS INC
Contact Mailing Address (Delivery):	PO BOX 2068
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78768 2068
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93097
Additional ID:	705285312002156
Princ ID:	904230042002156
AI Number:	45817
Facility Name:	FAST STOP 11
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JACK RITTER/

HIST UST AUSTIN:

Name:	FAST STOP STORE #11
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3065
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	FAST STOP 11
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2

FAST STOP 11 (Continued) **U001277342**

Facility ID:	93097
Finass ID:	74214
AI:	45817
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

MH2042 **FAST STOP STORE 11** **TX RDR** **S127533809**
WNW **5526 S CONGRESS** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
264 ft. **Site 5 of 6 in cluster MH**

Actual:
630 ft.

Focus Map:
17

RDR:

RDR ID:	13540
Facility ID:	45817
RN:	Not reported
CN:	Not reported
Name:	FAST STOP STORE 11
Address:	5526 S CONGRESS
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/3/2004
Due Date:	8/2/2004
Tank Owner:	FAST STOP STORES INC
Contact Person:	JACK RITTER
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	7/29/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	116040
Pre-Existing LPST Number:	Not reported
Comments:	LPST# 116040 DB2 PROPERTY SALE PENDING AND WOULD APPRECIATE A RUSH JOB.
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

MH2043 **PROPOSED CVS PHARMACY** **TX LPST** **S106497765**
WNW **5526 S CONGRESS AVE** **TX IHW CORR ACTION** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.050 mi.
264 ft. **Site 6 of 6 in cluster MH**

Actual:
630 ft.

Focus Map:
17

LPST:

Name:	FAST STOP STORE 11
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0045817
LPST Id:	116040
Facility Location:	5526 S CONGRESS AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	06/04/2004
Entered Date:	07/29/2004
Reported Date:	06/04/2004
Closure Date:	10/22/2004
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P
Coordinators RPR:	RLD
Responsible Party Name:	Not reported
Responsible Party Contact:	JACK RITTER
Responsible Party Address:	PO BOX 2068
Responsible Party City,St,Zip:	AUSTIN, TX 78768
Responsible Party Telephone:	512/765-6655
Reported Date:	06/04/2004
Case Start Date:	10/22/2004
Reference Number:	RN104921812
Project Manager:	RDILDINE

IHW CORR ACTION:

Name:	PROPOSED CVS PHARMACY
Address:	5526 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Program Id:	T2087
Location Desc:	INCLUDES ADJACENT SITE 120 STASSNEY AUSTIN TX
RN NUM:	RN104921812
Status:	INACTIVE
Status Date:	09/06/2006
EDR Link ID:	T2087
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	09/06/2006
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

MI2044 **CAPITOL LAUNDRY 6 DRY** **EDR Hist Cleaner** **1013784071**
ESE **301 W 8TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
265 ft. **Site 1 of 2 in cluster MI**

Actual:
535 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	CAPITOL LAUNDRY 6 DRY	LAUNDRIES
1970	CAPITAL LAUNDRY SUBSTATION	LAUNDRIES

LK2045 **321 3 COVERT AUTO CO** **EDR Hist Auto** **1013761960**
ESE **321 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
265 ft. **Site 2 of 10 in cluster LK**

Actual:
498 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	COVERT AUTO CO	AUTOMOBILE SERVICE STATIONS
1929	321 3 COVERT AUTO CO	AUTOMOBILE SERVICE STATIONS
1935	COVERT AUTO CO	AUTOMOBILE SERVICE STATIONS
1940	COVERT AUTO	AUTOMOBILE SERVICE STATIONS

KH2046 **ALAMO TRANSMISSION SERVICE** **EDR Hist Auto** **1013756042**
SSW **200 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.050 mi.
265 ft. **Site 11 of 19 in cluster KH**

Actual:
475 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	TEXAS CO THE	GASOLINE AND OIL SERVICE STATIONS
1940	JACKSON NORMAN M FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1947	WILLIAMS P K NASH CO AUTOS	AUTOMOBILE REPAIRING
1978	GUSTO J ENTERPRISES INC	Automotive Repair Shops, NEC
1979	GUSTO J ENTERPRISES INC	Automotive Repair Shops, NEC
1980	ALAMO TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1980	GUSTO J ENTERPRISES INC	Automotive Repair Shops, NEC
1982	GUSTO J ENTERPRISES INC	Automotive Repair Shops, NEC
1983	GUSTO J ENTERPRISES INC	Automotive Repair Shops, NEC
1984	ALAMO TRANSMISSION SERVICE	AUTOMOBILE REPAIRING

MJ2047 **KEESES ENCO HUMBLE SERVICE STATION** **EDR Hist Auto** **1013772797**
ESE **600 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.050 mi.
265 ft. **Site 1 of 4 in cluster MJ**

Actual:
468 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	KEESES ENCO HUMBLE SERVICE STAT	GASOLINE STATIONS
1975	LONNIES EXXON	GASOLINE STATIONS

MJ2048 **WHEELERS ENCO HUMBLE** **EDR Hist Auto** **1013774014**
ESE **600 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
265 ft. **Site 2 of 4 in cluster MJ**

Actual:
468 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	WHEELERS ENCO HUMBLE	GASOLINE STATIONS

MJ2049 **ACME SERVICE STA** **EDR Hist Auto** **1013755983**
ESE **600 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.050 mi.
265 ft. **Site 3 of 4 in cluster MJ**

Actual:
468 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	ACME SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	GLISMANNS CHRYSLER & PLYMOUTH G	AUTOMOBILE REPAIRING
1953	GLISMANNS GARAGE	AUTOMOBILE REPAIRING
1953	TOMLINSON SERV	GASOLINE STATIONS
1958	GLISMANNS GARAGE	AUTOMOBILE REPAIRING
1958	GLISMANNS SERV	GASOLINE STATIONS
1958	AUSTIN WIDG & RADI	AUTOMOBILE RADIATOR REPAIRERS
1962	AUSTIN WLDG & RADIATOR WKS	AUTOMOBILE RADIATOR REPAIRERS
1962	GLISMANNS GARAGE	AUTOMOBILE REPAIRING
1962	GLISMANNS SERV STA	GASOLINE STATIONS

LA2050 **PRUDENCE BAILEY** **TX HIST UST** **S111678780**
SW **122 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.051 mi.
267 ft. **Site 4 of 15 in cluster LA**

Actual:
491 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	PRUDENCE BAILEY
Address:	122 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0364
HID UST:	364
Inspection:	03/06/2009
Due:	03/06/2012

LQ2051 NE < 1/8 0.051 mi. 268 ft. — **ROGERS & SALYER FILLING STATION**, **204 BARTON SPRINGS RD**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013771799** / **N/A**

Site 7 of 7 in cluster LQ

Actual: 453 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	ROGERS & SALYER FILLING STATION	GASOLINE AND OIL SERVICE STATIONS
1947	CENTEX MOTORS & HOME APPLIANCE	GASOLINE AND OIL SERVICE STATIONS

KW2052 ESE < 1/8 0.051 mi. 268 ft. — **OCONNELL & WORLEY**, **201 8TH E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013787206** / **N/A**

Site 5 of 5 in cluster KW

Actual: 514 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1958	OCONNELL & WORLEY	CARPET AND RUG CLEANERS

2053 ESE < 1/8 0.051 mi. 268 ft. — **NELSON CHESTER B**, **603 9TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013781776** / **N/A**

Actual: 497 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1953	NELSON CHESTER B	CARPET AND RUG CLEANERS

2054 West < 1/8 0.051 mi. 269 ft. — **ROOHI JOOHI INC**, **7700 E MRTN LTHR KING JR**, **AUSTIN, TX 78724** — **EDR Hist Auto** — **1021209790** / **N/A**

Actual: 571 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
2014	ROOHI JOOHI INC	Gasoline Service Stations

2055 ESE < 1/8 0.051 mi. 269 ft. — **SAM HOUSTON BUILDING**, **201 E 14TH ST**, **AUSTIN, TX 78701** — **TX AST** — **A100348801** / **N/A**

Actual: 536 ft.

Focus Map: 11

AST:

Name:	SAM HOUSTON BUILDING
Address:	201 E 14TH ST
City,State,Zip:	AUSTIN, TX 787011445

SAM HOUSTON BUILDING (Continued) **A100348801**

Facility ID:	124330
Additional ID:	917497782010006
AI Number:	80103
Facility Type:	Not reported
Facility Begin Date:	12/17/1984
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78701
Contact Name/Title:	JONATHAN HICKMAN/ELEC SUPR
Contact Organization Name:	SAM HOUSTON BUILDING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124634202
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	11/05/2009
Signature First Name on Earliest Reg Form:	JONATHAN
Application Received Date on Earliest Reg Form:	11/09/2009
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	HICKMAN
Signature Title on Earliest Reg Form:	ELEC SUPR
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	124330
Tank ID:	1
AST ID:	212868
AI Number:	80103
Install Date:	12/17/1984
Tank Registration Date:	11/09/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	12/17/1984
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	Y
Aluminum:	N
Metal:	N
Concrete:	N

SAM HOUSTON BUILDING (Continued) **A100348801**

Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

MJ2056 **AUTOMOTIVE SPECIALISTS** **EDR Hist Auto** **1013756159**
ESE **502 NUECES ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.051 mi.
269 ft. **Site 4 of 4 in cluster MJ**

Actual:
468 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	AUTOMOTIVE SPECIALISTS	AUTOMOBILE REPAIRING
1969	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1970	AUTOMOTIVE SPECIALISTS REPR	AUTOMOBILE REPAIRING
1970	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1971	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1972	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1973	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1974	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1975	AUTOMOTIVE SPECIALISTS	AUTOMOBILE REPAIRING
1975	AUTOMOTIVE SPECIALISTS	General Automotive Repair Shops
1975	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1976	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1977	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1978	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1979	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1980	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1982	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops
1983	AUTOMOBILE SPECIALISTS	General Automotive Repair Shops

MK2057 **DEWEY PURYEAR** **TX HIST UST** **S111678626**
NNE **201 W CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.051 mi.
270 ft. **Site 1 of 6 in cluster MK**

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DEWEY PURYEAR
Address:	201 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0037
HID UST:	37
Inspection:	Not reported
Due:	06/01/2012

ML2058 **JERRYS GARAGE** **EDR Hist Auto** **1013763807**
NNE **1902 MONTOPOLIS DR** **N/A**
< 1/8 **AUSTIN, TX**
0.051 mi.
271 ft. **Site 1 of 2 in cluster ML**

Actual:
508 ft.

EDR Hist Auto

Focus Map:
15

Year:	Name:	Type:
1958	JERRYS GARAGE	AUTOMOBILE REPAIRING

2059 **CAPITAL PREFABRICATORS** **TX HIST UST** **S111678596**
WNW **6926 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
272 ft.

Actual:
720 ft.

HIST UST AUSTIN:

Name:	CAPITAL PREFABRICATORS
Address:	6926 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0412
HID UST:	412
Inspection:	04/21/2009
Due:	04/21/2012

Focus Map:
6

MM2060 **MIOTORAMP STGE** **EDR Hist Auto** **1013757867**
WNW **713 COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
272 ft. **Site 1 of 2 in cluster MM**

Actual:
515 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	MIOTORAMP STGE	AUTOMOBILE GARAGES
1958	MOTORAMP STGE	AUTOMOBILE GARAGES
1962	MOTORAMP STGE	AUTOMOBILE GARAGES
1965	MOTORAMP STORAGE GARAGE	AUTOMOBILE GARAGES
1969	MOTORAMP GARAGE INC OF AUSTIN	General Automotive Repair Shops
1970	MOTORAMP STORAGE GAT AGE AUTO	AUTOMOBILE GARAGES

2061 **GRAY CLEANERS** **EDR Hist Cleaner** **1013778181**
ESE **3912 SPEEDWAY** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft.

Actual:
615 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1940	GRAY CLEANERS	CLOTHES PRESSERS AND CLEANERS

KS2062 **FORMER GLO FACILITY** **TX UST** **U001292270**
ESE **421 E CESAR CHAVEZ ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.052 mi.
273 ft. **Site 4 of 5 in cluster KS**

Actual:
458 ft.

Focus Map:
11

UST:

Name:	FORMER GLO FACILITY
Address:	421 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 787014101
AI Number:	63213
Facility Type:	FLEET REFUELING
Facility Begin Date:	06/25/1992
Facility Status:	INACTIVE
Additional ID:	988546812002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	JOHN BEAUCHAMP,
Contact Organization Name:	FORMER GLO FACILITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2102253053
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/15/1991
Signature Name/Title On Earliest Reg Form:	JACK GIBERSON,CHIEF CLERK
Application Received Date On Earliest Reg Form:	10/15/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778732
Owner Last Name:	TRINITY STREET JOINT VENTURE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	JV
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	978546802002053
Additional ID:	988546812002053

FORMER GLO FACILITY (Continued) **U001292270**

AI Number:	63213
Owner Effective Begin Date:	05/13/1999
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/15/1991
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146067
Facility ID:	94056
Ai Number:	63213
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/19/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

FORMER GLO FACILITY (Continued) **U001292270**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/08/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	161251
UST ID:	146067
AI Number:	63213
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

FORMER GLO FACILITY (Continued) **U001292270**

Construction Notification:

NOC ID:	15572
Facility ID:	94056
AI Number:	63213
Application Received Date:	07/17/2000
Scheduled Construction Date:	08/16/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00717033
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	55374

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16701
UST ID:	Not reported
NOC ID:	15572
AI Number:	63213
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

FORMER GLO FACILITY (Continued) **U001292270**

Facility Billing Contacts:

Contact Organization Name:	TRINITY STREET JOINT VENTURE
Contact Mailing Address (Delivery):	315 E COMMERCE ST STE 300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78205 2947
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94056
Additional ID:	988546812002053
Princ ID:	978546802002053
AI Number:	63213
Facility Name:	FORMER GLO FACILITY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOHN BEAUCHAMP/

HIST UST AUSTIN:

Name:	FORMER GENERAL LAND OFFICE
Address:	421 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0691
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MN2063 **ORIENTAL OIL COMPANY** **TX HIST UST** **S128729171**
NNE **101 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 1 of 11 in cluster MN**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ORIENTAL OIL COMPANY
Address:	101 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0065
HID UST:	65
Inspection:	Not reported
Due:	06/01/2012

MN2064 **PIERCE PETROLEUM** **TX HIST UST** **S111678777**
NNE **101 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 2 of 11 in cluster MN**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	PIERCE PETROLEUM
Address:	101 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0201
HID UST:	201
Inspection:	Not reported
Due:	06/01/2012

MN2065 **DAVIS BROTHERS** **TX HIST UST** **S111678622**
NNE **101 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 3 of 11 in cluster MN**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	DAVIS BROTHERS
Address:	101 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0129
HID UST:	129
Inspection:	Not reported
Due:	06/01/2012

MN2066 **ORIENTAL OIL COMPANY** **TX HIST UST** **S128729172**
NNE **101 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 4 of 11 in cluster MN**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ORIENTAL OIL COMPANY
Address:	101 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0070
HID UST:	70
Inspection:	Not reported
Due:	06/01/2012

MK2067 **SILICON LABRITORIES AUSTIN** **PFAS ECHO** **1027419709**
NNE **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 2 of 6 in cluster MK**

Actual:
471 ft.

Focus Map:
11

PFAS ECHO:

Name:	SILICON LABRITORIES AUSTIN
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.26371
Longitude:	-97.74587
Count:	1
County:	TRAVIS COUNTY
Status:	Active
Region:	06
Industry:	Electronics Industry
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070364147
Facility Percent Minority:	46.51
Facility Derived Tribes:	-
Facility Population:	5685.93
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	21
Facility Derived CB2010:	484530011001140
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXRNEY880

SILICON LABRITORIES AUSTIN (Continued) **1027419709**

CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	3674
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	Y
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.74587,%22y%22:30.26371,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

JH2068 **601 03 GAGE BROS** **EDR Hist Auto** **1013755890**
NE **601 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 2 of 13 in cluster JH**

Actual:
483 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	601 03 GAGE BROS	RADIATOR REPAIRING

JH2069 **REDS GARAGE AUTO REPRS** **EDR Hist Auto** **1013767458**
NE **600 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 3 of 13 in cluster JH**

Actual:
483 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	REDS GARAGE AUTO REPRS	AUTOMOBILE REPAIRING

KT2070 **AMERICAN CLEANERS** **TX DRYCLEANERS** **S109360399**
WNW **719A COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.052 mi.
273 ft. **Site 2 of 4 in cluster KT**

Actual:
518 ft.

DRYCLEANERS:

Focus Map:
11

Name:	AMERICAN CLEANERS
Address:	719A COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104409966
Region:	11

AMERICAN CLEANERS (Continued) **S109360399**

CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	719A COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104409966
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

MB2071 **SCHNELL BROS WHEEL** **EDR Hist Auto** **1013758215**
WNW **501 MONROE ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
273 ft. **Site 7 of 7 in cluster MB**

Actual: EDR Hist Auto
507 ft.

Focus Map:
14

Year:	Name:	Type:
1965	SCHNELL BROS WHEEL	AUTOMOBILE REPAIRING
1970	SCHNELL BROS WHEEL ALIGNMENT	AUTOMOBILE REPAIRING
1975	SCHNELL BROS WHEEL ALIGNMENT	AUTOMOBILE REPAIRING
1980	SCHNELL BROS WHEEL ALIGNMENT	AUTOMOBILE REPAIRING

2072 ESE < 1/8 0.052 mi. 274 ft. | **LAY WALLACE DCLO CLNR**
3808 SPEEDWAY
AUSTIN, TX | **EDR Hist Cleaner** | **1013778164**
N/A

Actual: 611 ft.

EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1935	LAY WALLACE DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

KL2073 WNW < 1/8 0.052 mi. 274 ft. | **AUSTIN GREENWOOD CONDO SWBT OW XP2690**
909 COLORADO ST
AUSTIN, TX 78701
Site 3 of 5 in cluster KL | **TX LPST**
TX UST
TX HIST UST
TX Financial Assurance | **U003040303**
N/A

Actual: 528 ft.

Focus Map: 11

LPST:

Name:	AUSTIN GREENWOOD CONDO
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0019352
LPST Id:	105043
Facility Location:	909 COLORADO ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/11/1992
Entered Date:	11/05/1992
Reported Date:	09/14/1992
Closure Date:	01/10/1997
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	HLN
Responsible Party Name:	Not reported
Responsible Party Contact:	HARRY HIXSON
Responsible Party Address:	308 S AKARD RM 900
Responsible Party City,St,Zip:	DALLAS, TX 75202 5399
Responsible Party Telephone:	214/464-1805
Reported Date:	09/14/1992
Case Start Date:	01/10/1997
Reference Number:	RN102390275
Project Manager:	HLN

UST:

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 787012324
AI Number:	19352
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	101678402002150
Facility Exempt Status:	N
Records Off-Site:	Yes

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	JULIANNA BROCK,
Contact Organization Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2547577700
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/22/2016
Signature Name/Title On Earliest Reg Form:	JURANDIR FELIPE-ORTEGA,EHS MGR
Application Received Date On Earliest Reg Form:	01/25/2016
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	576368792017305
Additional ID:	101678402002150
Ai Number:	19352
Operator CN:	CN605433374
Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Operator Effective Begin Date:	09/24/2018
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	DERONICA LAMB/MANAGER EH&S ENVIRONMENTAL SERVICES
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75202-5315
Contact Phone Country Code:	1
Contact Phone Area Code:	214
Contact Phone Number:	7410464
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	DR1429@ATT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605433374
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75202
Contact Mailing Zip5:	5315
Contact Phone Number/Ext:	1 214 7410630/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MP0873@ATT.COM
Contact Address Deliverable:	Not reported
Princ ID:	576368792017305
Additional ID:	101678402002150
AI Number:	19352
Owner Effective Begin Date:	09/24/2018
State Tax ID:	14305297104
Contact Role:	OWNOPRCON
Contact Name/Title:	MICHAEL PERRY/AREA MANAGER, EH&S ENVIRONMENTAL SERVICE
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY

Self Certification:

Self Cert ID:	76469
Cert ID:	381322
AI Number:	19352
Self Certification Date:	01/10/2023
Signature Name/Title:	CAMERON SPARKS TANK PROGRAM MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	362248
AI Number:	19352
Self Certification Date:	10/26/2021
Signature Name/Title:	Vyrl L Naumann EH&S Tank Manager
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	345835
AI Number:	19352
Self Certification Date:	11/10/2020
Signature Name/Title:	Vyrl L Naumann Tank Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	328669
AI Number:	19352
Self Certification Date:	10/24/2019
Signature Name/Title:	Vyrl L Naumann EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	310214
AI Number:	19352
Self Certification Date:	09/20/2018
Signature Name/Title:	Rayshell T Wamsley Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	292803
AI Number:	19352
Self Certification Date:	09/13/2017
Signature Name/Title:	Jurandir Felipe-Ortega EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	275742
AI Number:	19352
Self Certification Date:	09/13/2016
Signature Name/Title:	Jurandir Felipe-Ortega EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	266412
AI Number:	19352
Self Certification Date:	01/22/2016
Signature Name/Title:	JURANDIR FELIPE-ORTEGA EHS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	248811
AI Number:	19352
Self Certification Date:	02/12/2015
Signature Name/Title:	Lisa Espinosa EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	233843
AI Number:	19352
Self Certification Date:	03/19/2014
Signature Name/Title:	Lisa Espinosa Manager EH&S
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76469
Cert ID:	116098
AI Number:	19352
Self Certification Date:	03/28/2013
Signature Name/Title:	TAMEKA JACKSON EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	116097
AI Number:	19352
Self Certification Date:	03/30/2012
Signature Name/Title:	ROBERT D PICKENS EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116096
AI Number:	19352
Self Certification Date:	03/21/2011
Signature Name/Title:	ROBERT D PICKENS SR ADMIN ENVIR HEALT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116095
AI Number:	19352
Self Certification Date:	03/30/2010
Signature Name/Title:	TAMEKA JACKSON MANAGER-EH&S
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	116094
AI Number:	19352
Self Certification Date:	03/09/2009
Signature Name/Title:	MARK E DINUBILA ENVIRONMENTAL MANAGE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116093
AI Number:	19352
Self Certification Date:	03/05/2008
Signature Name/Title:	ROBERT D TAYLOR SOUTHWEST REGIONAL M
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116092
AI Number:	19352
Self Certification Date:	03/22/2007
Signature Name/Title:	ROBERT D TAYLOR ENVIRONMENTAL MANAGE
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	116091
AI Number:	19352
Self Certification Date:	02/24/2006
Signature Name/Title:	CHERYL ALLEN ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116090
AI Number:	19352
Self Certification Date:	02/07/2005
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116089
AI Number:	19352
Self Certification Date:	01/21/2004
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Self Cert ID:	76469
Cert ID:	116088
AI Number:	19352
Self Certification Date:	02/19/2003
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116087
AI Number:	19352
Self Certification Date:	03/06/2002
Signature Name/Title:	HARRY C HIXSON SENIOR ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76469
Cert ID:	116086
AI Number:	19352
Self Certification Date:	01/15/2001
Signature Name/Title:	MICHAEL A OLIVER SR ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5760
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	50071
Facility ID:	76469
Ai Number:	19352
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	5760
UST Comprt ID:	113869
UST ID:	50071
AI Number:	19352
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	7056
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

UST ID:	50073
Facility ID:	76469
Ai Number:	19352
Tank Id:	ST1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/29/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	ST1

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Tank Capacity:	7056
UST Comprt ID:	113871
UST ID:	50073
AI Number:	19352
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5760
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	50072
Facility ID:	76469
Ai Number:	19352
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	5760
UST Comprt ID:	113870
UST ID:	50072
AI Number:	19352
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	38013
Facility ID:	76469
AI Number:	19352
Application Received Date:	04/09/2021
Scheduled Construction Date:	04/23/2021
UST Improvement:	Y
UST Installation:	N
UST Removal:	Y
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	04/09/2021
Signature Date On Form:	04/09/2021
Signature Name On Form:	CLAY WYATT
Signature Company On Form:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Signature Title On Form:	OWNER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	SOUTHWESTERN BELL TELEPHONE COMPANY;SOUTHWESTERN BE
Owner CN At Time Of Construction:	CN602245615,CN602245615
Owner AR At Time Of Construction:	73410A,73410U
General Desc Of Prop Construct:	REQUESTING 30 DAY WAIVER - REPLACING SPILL BUCKET AND OVERFLOW PREVENTION VALVE

NOC ID:	30715
Facility ID:	76469
AI Number:	19352
Application Received Date:	01/09/2017
Scheduled Construction Date:	01/10/2017
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	04/09/2021
Signature Date On Form:	04/09/2021
Signature Name On Form:	CLAY WYATT
Signature Company On Form:	Not reported
Signature Title On Form:	OWNER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	SOUTHWESTERN BELL TELEPHONE COMPANY;SOUTHWESTERN BE
Owner CN At Time Of Construction:	CN603545674,CN603545674
Owner AR At Time Of Construction:	73410A,73410U
General Desc Of Prop Construct:	REPAIR TWO LEAKING SHEAR VALVES.

NOC ID:	11961
Facility ID:	76469
AI Number:	19352
Application Received Date:	06/05/2007
Scheduled Construction Date:	07/05/2007
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M70605006
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	04/09/2021
Signature Date On Form:	04/09/2021

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Signature Name On Form:	CLAY WYATT
Signature Company On Form:	Not reported
Signature Title On Form:	OWNER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	90435
UST ID:	Not reported
NOC ID:	38013
AI Number:	19352
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TAIT ENVIRONMENTAL SERVICES
Representative Name:	BILLY BOB BATES
Mailing Address (Delivery):	1819 FIRMAN DR STE 115
Mailing Address (Internal Delivery):	Not reported
Mailing City:	RICHARDSON
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	90434
UST ID:	Not reported
NOC ID:	38013
AI Number:	19352
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CARBON ENVIRONMENTAL LLC
Representative Name:	Not reported
Mailing Address (Delivery):	661 E MAIN ST 200-254
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MIDLOTHIAN
Mailing State:	TX
Mailing Zip:	76065
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	6822440
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Cont/Cons/Installer ID:	72872
UST ID:	Not reported
NOC ID:	30715
AI Number:	19352
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TAIT ENVIRONMENTAL SERVICES
Representative Name:	ERIC HAMMER
Mailing Address (Delivery):	1819 FIRMAN RD STE 118
Mailing Address (Internal Delivery):	Not reported
Mailing City:	RICHARDSON
Mailing State:	TX
Mailing Zip:	75081
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	469
Phone Number:	7092200
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	12750
UST ID:	Not reported
NOC ID:	11961
AI Number:	19352
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001141
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	90436
UST ID:	Not reported
NOC ID:	38013
AI Number:	19352
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	CLAY WYATT
Mailing Address (Delivery):	661 E MAIN ST 200-254

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	MIDLOTHIAN
Mailing State:	TX
Mailing Zip:	76066
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	6822440
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76469
Additional ID:	101678402002150
Princ ID:	576368792017305
AI Number:	19352
Facility Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
AR Number:	83091
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	VYRL NAUMANN/

HIST UST AUSTIN:

Name:	AT&T - GREENWOOD XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX
Id UST:	980
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	278449
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2022
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	0 800 7475256
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2024
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	251354
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2021
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	240524
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2019
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	203599
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2018
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	166474
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Facility ID:	76469
Finass ID:	185947
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	158151
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2015
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	9409
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	123381
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2013
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ50593
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60108
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60110
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60109
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2010
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60111
AI:	19352

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50514
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60112
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2008
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	9723041
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60113
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	01/25/2016

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **U003040303**

Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 0 0
Policy Number:	1595289
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60114
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	Not reported
Policy Number:	1595289
Coverage Amount:	1000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	76469
Finass ID:	60115
AI:	19352
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	01/25/2016
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

KL2074 **AUSTIN GREENWOOD CONDO SWBT OW XP2690** **TX AST** **S107988585**
WNW **909 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.052 mi.
274 ft. **Site 4 of 5 in cluster KL**

Actual:
528 ft.

Focus Map:
11

AST:

Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Address:	909 COLORADO ST
City,State,Zip:	AUSTIN, TX 787012324
Facility ID:	76469
Additional ID:	101678402002150
AI Number:	19352
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	Y
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78701
Contact Name/Title:	JULIANNA BROCK/
Contact Organization Name:	AUSTIN GREENWOOD CONDO SWBT OW XP2690
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	2547577700
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	01/22/2016
Signature First Name on Earliest Reg Form:	JURANDIR
Application Received Date on Earliest Reg Form:	01/25/2016
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	FELIPE-ORTEGA
Signature Title on Earliest Reg Form:	EHS MGR
Signature Role on Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	76469
Tank ID:	4
AST ID:	210582
AI Number:	19352
Install Date:	01/13/2008
Tank Registration Date:	08/21/2008
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/13/2008
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	20000

AUSTIN GREENWOOD CONDO SWBT OW XP2690 (Continued) **S107988585**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

LF2075 **BROWNS JACK CLEANERS CLNS** **EDR Hist Cleaner** **1013785361**
East **615 MARTIN LUTHER KING JR BLVD W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.052 mi.
275 ft. **Site 4 of 7 in cluster LF**

Actual:
559 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1980	BROWNS JACK CLEANERS CLNS	CLEANERS AND DYERS
1984	BROWNS JACK CLEANERS	CLEANERS AND DYERS

KU2076 **CAMPOS MANUEL** **EDR Hist Auto** **1013759724**
ESE **801 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
276 ft. **Site 3 of 3 in cluster KU**

Actual:
469 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	C & R SERVICE CEN	GASOLINE STATIONS
1958	CAMPOS MANUEL	GASOLINE STATIONS

2077 **SOUTH CENTRAL WATERFRONT** **TX BROWNFIELDS** **S116385814**
NE **NEC OF S FIRST ST AND E RIVERSIDE** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.052 mi.
276 ft.

Actual:
448 ft.

BROWNFIELDS:

Focus Map:
14

Name:	SOUTH CENTRAL WATERFRONT
Address:	NEC OF S FIRST ST AND E RIVERSIDE
City,State,Zip:	AUSTIN, TX 78704
BF Site Assessment Received:	03/03/2014
PCA number:	99690
BF Grant Number:	G157
Facility Type:	Commercial/Residential
Lead Type:	City

SOUTH CENTRAL WATERFRONT (Continued) **S116385814**

Project manager:	PALLEN
Phase:	COMPLETED
Lat/Long:	30.257205 / -97.745706999999996
Lat/Long (deg):	30.257205 / -97.745706999999996
Acres:	97
TCEQ Region:	11
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Austin (Austin Resource Recovery
Applicant Title:	Brownfields Program Manager
Applicant Address:	PO Box 1088
Applicant City,St,Zip:	Austin, TX 78767
Applicant Phone:	512-974-6085
Applicant Fax:	Not reported
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	104432
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported
Status Date:	10/14/2014

ML2078 **JERRYS GARAGE AUTO** **EDR Hist Auto** **1013766816**
NNE **1900 MONTOPOLIS DR** **N/A**
< 1/8 **AUSTIN, TX**
0.052 mi.
277 ft. **Site 2 of 2 in cluster ML**

Actual:
508 ft.

EDR Hist Auto

Focus Map:
15

Year:	Name:	Type:
1962	JERRYS GARAGE AUTO	AUTOMOBILE REPAIRING
1962	JERRYS USED CARS	AUTOMOBILE REPAIRING
1993	RODRIGUEZ MARCIANO AUTO REPAIR	General Automotive Repair Shops
1994	RODRIGUEZ MARCIANO ATO RPR	General Automotive Repair Shops
1995	RODRIGUEZ MARCIANO ATO RPR	General Automotive Repair Shops
1996	RODRIGUEZ MARCIANO ATO RPR	General Automotive Repair Shops
2000	PEREZ AUTO REPAIR	General Automotive Repair Shops
2001	PEREZ AUTO REPAIR	General Automotive Repair Shops

JP2079 SSW < 1/8 0.052 mi. 277 ft. | **TRAVIS COUNTY OIL**
500 BRAZOS ST
AUSTIN, TX
Site 5 of 27 in cluster JP | **EDR Hist Auto** | **1013755685**
N/A

Actual: 486 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	TRAVIS COUNTY OIL	GASOLINE AND OIL SERVICE STATIONS

2080 East < 1/8 0.052 mi. 277 ft. | **SCARBROUGH HOUSE TRACT**
2612 WHITIS AVE
AUSTIN, TX 78705 | **TX VCP** | **S105153072**
N/A

Actual: 613 ft.

Focus Map: 11

VCP TCEQ:

Name:	SCARBROUGH HOUSE TRACT
Address:	2612 WHITIS AVE
City,State,Zip:	AUSTIN, TX 78705
Region:	REGION 11 - AUSTIN
Facility ID:	1414
VCP Record Date:	12/03/2001
Facility Type:	PROPERTY VACANT
PCA Number:	33614
Project Manager:	DCHRISTI
Phase:	COMPLETED
Acres at Site:	1.5
REM Program:	VCP
RN Number:	RN101053221
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	12/03/2001
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	05/02/2002
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	11/19/2001
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2001-12-07 00:00:00

SCARBROUGH HOUSE TRACT (Continued) **S105153072**

Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1414
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	336140
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR; 200-38; 208/D
Latitude:	30.17
Longitude:	-97.44

Contact:

REM Program:	VCP
Program ID:	1414
RN Number:	RN101053221
CN Number:	CN601538192
CN Name:	SCARBROUGH, LEMUEL JR
Role Code:	BILLCONT
Contact Name:	SCARBROUGH, LEMUEL
Contact Title:	Not reported
Organization Name:	LEMUEL SCARBROUGH JR
Mailing Address:	101 W 6TH ST
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78701
Contact Telephone:	(512) 480-5600
Contact Telephone Ext:	0

MO2081 **BROADDUS CHEVRON RIVERSIDE GROCERY** **TX UST** **U004119138**
NE **30 IH 35 N** **TX Financial Assurance** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.052 mi.
277 ft. **Site 1 of 5 in cluster MO**

Actual:
455 ft.

Focus Map:
14

UST:

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 787014326
AI Number:	28644
Facility Type:	RETAIL
Facility Begin Date:	12/01/1986
Facility Status:	ACTIVE
Additional ID:	133264732002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DAN DAWSON,
Contact Organization Name:	RIVERSIDE GROCERY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129702513
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	5123470302
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/17/2021
Signature Name/Title On Earliest Reg Form:	SCOTT W BROADDUS JR,PRES
Application Received Date On Earliest Reg Form:	09/16/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	692510012002053
Additional ID:	133264732002156
Ai Number:	28644
Operator CN:	CN600777718
Operator Name:	BROADDUS ENTERPRISES INC
Operator Effective Begin Date:	09/04/2013
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	SCOTT W BROADDUS/
Contact Organization Name:	BROADDUS ENTERPRISES INC
Contact Mailing Address (Delivery):	2710 BEE CAVES RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78746-5642
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3283240
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600777718
Owner Last Name:	BROADDUS ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	2710 BEE CAVES RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78746
Contact Mailing Zip5:	5642
Contact Phone Number/Ext:	1 512 9702513/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	692510012002053
Additional ID:	133264732002156

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

AI Number:	28644
Owner Effective Begin Date:	09/04/2013
State Tax ID:	17420470027
Contact Role:	OWNCON
Contact Name/Title:	DAN DAWSON/
Contact Organization Name:	BROADDUS ENTERPRISES INC

Self Certification:

Self Cert ID:	87650
Cert ID:	377158
AI Number:	28644
Self Certification Date:	09/06/2022
Signature Name/Title:	SCOTT W BROADDUS JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	87650
Cert ID:	360097
AI Number:	28644
Self Certification Date:	08/17/2021
Signature Name/Title:	SCOTT BROADDUS JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	87650
Cert ID:	343115
AI Number:	28644
Self Certification Date:	08/06/2020
Signature Name/Title:	SCOTT W BROADDUS JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	326426
AI Number:	28644
Self Certification Date:	09/11/2019
Signature Name/Title:	SCOTT W BROADDUS JR PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	308050
AI Number:	28644
Self Certification Date:	07/30/2018
Signature Name/Title:	SCOTT BROADDUS JR PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	291430
AI Number:	28644
Self Certification Date:	08/15/2017
Signature Name/Title:	SCOTT BROADDUS JR PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	274959
AI Number:	28644
Self Certification Date:	09/02/2016
Signature Name/Title:	SCOTT BROADDUS JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	259475
AI Number:	28644
Self Certification Date:	09/10/2015
Signature Name/Title:	SCOTT BROADDUS JR PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	242108
AI Number:	28644
Self Certification Date:	09/11/2014
Signature Name/Title:	SCOTT W BROADDUS PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	242107
AI Number:	28644
Self Certification Date:	09/04/2013
Signature Name/Title:	SCOTT W BROADDUS JR PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	87650
Cert ID:	143864
AI Number:	28644
Self Certification Date:	02/27/2013
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143863
AI Number:	28644
Self Certification Date:	02/06/2012
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143862
AI Number:	28644
Self Certification Date:	01/27/2011
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143861
AI Number:	28644
Self Certification Date:	01/29/2010
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143860
AI Number:	28644
Self Certification Date:	01/30/2009
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143859
AI Number:	28644
Self Certification Date:	04/04/2008
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143858
AI Number:	28644
Self Certification Date:	04/04/2007
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143857
AI Number:	28644
Self Certification Date:	02/16/2006
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143856
AI Number:	28644
Self Certification Date:	02/10/2005
Signature Name/Title:	DAN DAWSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143855
AI Number:	28644
Self Certification Date:	02/04/2004
Signature Name/Title:	DAN DAWSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	87650
Cert ID:	143854
AI Number:	28644
Self Certification Date:	03/06/2003
Signature Name/Title:	DAN DAWSON GEN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87650
Cert ID:	143853
AI Number:	28644
Self Certification Date:	02/28/2002
Signature Name/Title:	DAN DAWSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	87650
Cert ID:	143852
AI Number:	28644
Self Certification Date:	01/19/2001
Signature Name/Title:	DAN DAWSON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75210
Facility ID:	87650
Ai Number:	28644

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	147984
UST ID:	75210

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1986

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	75203
Facility ID:	87650
Ai Number:	28644
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	147977
UST ID:	75203
AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	75204
Facility ID:	87650
Ai Number:	28644
Tank Id:	1AA
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	1AA
Tank Capacity:	550
UST Comprt ID:	147978
UST ID:	75204
AI Number:	28644
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	75205
Facility ID:	87650
Ai Number:	28644
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	147979
UST ID:	75205
AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	75206
Facility ID:	87650
Ai Number:	28644
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	3A
Tank Capacity:	10000
UST Comprt ID:	147980
UST ID:	75206
AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75207
Facility ID:	87650
Ai Number:	28644
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	147981
UST ID:	75207
AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1986

Install Date:	12/01/1986

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	75208
Facility ID:	87650
Ai Number:	28644
Tank Id:	1A
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	06/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	1000
UST Comprt ID:	147982
UST ID:	75208
AI Number:	28644
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	75209
Facility ID:	87650

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Ai Number:	28644
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	147983

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

UST ID:	75209
AI Number:	28644
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/01/1986

Construction Notification:

NOC ID:	24402
Facility ID:	87650
AI Number:	28644
Application Received Date:	07/23/2013
Scheduled Construction Date:	07/23/2013
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	07/23/2013
Signature Date On Form:	07/23/2013
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	BROADDUS PETROLEUM CORPORATION
Owner CN At Time Of Construction:	CN601675143
Owner AR At Time Of Construction:	32323
General Desc Of Prop Construct:	INSTALL (3) FLEX CONNECTORS AND BALL VALVES ON EXISTING LINES.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	57291
UST ID:	Not reported
NOC ID:	24402
AI Number:	28644
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	PO BOX 2346
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MCALLEN
Mailing State:	TX
Mailing Zip:	78502
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	956
Phone Number:	6869582
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	57290
UST ID:	Not reported
NOC ID:	24402
AI Number:	28644
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	PEFFER BRENT ALLYN
Representative Name:	Not reported
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BROADDUS ENTERPRISES INC
Contact Mailing Address (Delivery):	2710 BEE CAVES RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 5642
Phone Number/Ext:	512 3283240/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87650
Additional ID:	133264732002156
Princ ID:	692510012002053
AI Number:	28644
Facility Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
AR Number:	2729
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	SCOTT W BROADDUS/

TX Financial Assurance 2:

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	274961
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2022
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000031937
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	257140

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2021
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000022138
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	237512
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2020
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000012905
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	220545
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2019

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-top-005001339
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	201433
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2018
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	184664
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2017
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	167359
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2016
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	150917
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2015
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	133227
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2014
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	114766
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2013
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	8424
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2012
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Policy Number:	18160
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/04/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	71243
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2010
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18160
Coverage Amount:	2000000
Coverage Expiration Date:	09/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	71244
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2009
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18160
Coverage Amount:	2000000
Coverage Expiration Date:	09/04/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Region:	2
Facility ID:	87650
Finass ID:	71245
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2008
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18160
Coverage Amount:	2000000
Coverage Expiration Date:	09/04/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	71246
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/04/2007
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18160
Coverage Amount:	2000000
Coverage Expiration Date:	09/04/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	BROADDUS CHEVRON RIVERSIDE GROCERY
Address:	30 IH 35 N
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	87650
Finass ID:	71247
AI:	28644
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

BROADDUS CHEVRON RIVERSIDE GROCERY (Continued) **U004119138**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/03/1993
Date Financial Assurance Form Rec:	09/16/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

LR2082 **RAYS REPAIR** **EDR Hist Auto** **1013761385**
ESE **6516 SHIRLEY AVE** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.053 mi.
279 ft. **Site 3 of 5 in cluster LR**

Actual:
712 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1990	RAYS REPAIR	AUTOMOBILE REPAIRING
1993	RAYS REPAIR	General Automotive Repair Shops
1994	RAYS REPAIR	General Automotive Repair Shops
1995	RAYS REPAIR	General Automotive Repair Shops
1996	RAYS REPAIR	General Automotive Repair Shops
1997	RAYS REPAIR	General Automotive Repair Shops
1998	RAYS REPAIR	General Automotive Repair Shops
1999	RAYS REPAIR	General Automotive Repair Shops
2000	RAYS REPAIR	General Automotive Repair Shops
2001	RAYS REPAIR	General Automotive Repair Shops
2002	RAYS REPAIR	General Automotive Repair Shops
2003	RAYS REPAIR	General Automotive Repair Shops

MO2083 **BROADDUS ENTERPRISES INC** **EDR Hist Auto** **1020968638**
NE **30 N I 35** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.053 mi.
279 ft. **Site 2 of 5 in cluster MO**

Actual:
455 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1993	BROADDUS ENTERPRISES INC	Gasoline Service Stations
1997	BROADDUS ENTERPRISES INC	Gasoline Service Stations
1998	BROADDUS ENTERPRISES INC	Gasoline Service Stations

MO2084 **RIVERSIDE GROCERY** **TX HIST UST** **S128728596**
NE **30 N I 35** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
279 ft. **Site 3 of 5 in cluster MO**

Actual:
455 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	RIVERSIDE GROCERY
Address:	30 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	1007
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LG2085 **TEXAS CO THE FILLING** **EDR Hist Auto** **1013768318**
SSW **101 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
279 ft. **Site 3 of 26 in cluster LG**

Actual:
489 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1916	AUTO SERVICE CO	AUTOMOBILE SERVICE
1922	TEXAS CO THE FILLING	AUTOMOBILE FILLING STATIONS

JH2086 **EMPIRE AUTOMOTIVE SERVICE** **EDR Hist Auto** **1013772319**
NE **604 7TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.053 mi.
279 ft. **Site 4 of 13 in cluster JH**

Actual:
483 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1975	EMPIRE AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING

JH2087 **LOPEZ FRANK S** **EDR Hist Auto** **1013770012**
NE **604 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
279 ft. **Site 5 of 13 in cluster JH**

Actual:
483 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1953	LOPEZ FRANK S GAR	AUTOMOBILE REPAIRING
1958	LOPEZ FRANK S	AUTOMOBILE REPAIRING
1962	LOPEZ FRANK S	AUTOMOBILE REPAIRING

JH2088 NE < 1/8 0.053 mi. 279 ft. — **EMPIRE AUTOMOTIVE SERVICE**, **604 7TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013760241** / **N/A**

Site 6 of 13 in cluster JH

Actual: 483 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	EMPIRE AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1980	EMPIRE AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1984	EMPIRE AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING
1990	EMPIRE AUTOMOTIVE SERVICE	AUTOMOBILE REPAIRING

LG2089 SSW < 1/8 0.053 mi. 279 ft. — **THURMAN WAVERLY**, **120 5TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013779796** / **N/A**

Site 4 of 26 in cluster LG

Actual: 489 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1940	THURMAN WAVERLY	CLOTHES PRESSERS AND CLEANERS

LG2090 SSW < 1/8 0.053 mi. 279 ft. — **PAGE SAM F DCLO CLNR**, **109 5TH ST W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013785863** / **N/A**

Site 5 of 26 in cluster LG

Actual: 489 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	PAGE SAM F DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

LG2091 SSW < 1/8 0.053 mi. 280 ft. — **STROBURG & BLOMQUIST**, **103 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013758520** / **N/A**

Site 6 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	STROBURG & BLOMQUIST	AUTOMOBILE REPAIRERS
1922	STROBURG & BLOMQUIST	AUTOMOBILE GARAGES

LG2092 GOSLIN J W T & CO **EDR Hist Auto** **1013754244**
SSW 108 5TH ST E **N/A**
< 1/8 AUSTIN, TX
0.053 mi.
280 ft. Site 7 of 26 in cluster LG

Actual:
488 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1922	GOSLIN J W T & CO	AUTOMOBILE RADIATOR REPAIRERS
1922	GOSLIN J W T & CO	RADIATOR REPAIRING
1929	GOSLIN J W T & CO TINNERS	RADIATOR REPAIRING

LX2093 APPLE TRACT **TX UST** **U003421901**
WNW 811-814 W 6TH **N/A**
< 1/8 AUSTIN, TX
0.053 mi.
280 ft. Site 9 of 15 in cluster LX

Actual:
449 ft.

Focus Map:
11

UST:

Name:	APPLE TRACT
Address:	811-814 W 6TH
City,State,Zip:	AUSTIN, TX
AI Number:	4424
Facility Type:	Not reported
Facility Begin Date:	08/31/1989
Facility Status:	INACTIVE
Additional ID:	923561262002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	0
Site Location Description:	811-814 W 6TH
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	JACK APPLE,
Contact Organization Name:	APPLE TRACT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2818203355
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1986
Signature Name/Title On Earliest Reg Form:	L SMITH,FLEET MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601114945
Owner Last Name:	A & B PROPERTIES HAWAII LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR

APPLE TRACT (Continued) **U003421901**

Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	932561262002118
Additional ID:	923561262002118
AI Number:	4424
Owner Effective Begin Date:	09/01/1989
State Tax ID:	19900704297
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1958
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	10718
Facility ID:	93952
Ai Number:	4424
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/30/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

APPLE TRACT (Continued) **U003421901**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	160317
UST ID:	10718
AI Number:	4424
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

APPLE TRACT (Continued) **U003421901**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167951
Facility ID:	93952
Ai Number:	4424
Tank Id:	10
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

APPLE TRACT (Continued) **U003421901**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	10
Tank Capacity:	99
UST Comprt ID:	160318
UST ID:	167951
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

APPLE TRACT (Continued) **U003421901**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167952
Facility ID:	93952
Ai Number:	4424
Tank Id:	9
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

APPLE TRACT (Continued) **U003421901**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	9
Tank Capacity:	99
UST Comprt ID:	160319
UST ID:	167952
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1

APPLE TRACT (Continued) **U003421901**

Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167953
Facility ID:	93952
Ai Number:	4424
Tank Id:	8
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

APPLE TRACT (Continued) **U003421901**

Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	8
Tank Capacity:	99
UST Comprt ID:	160320
UST ID:	167953
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167954
Facility ID:	93952
Ai Number:	4424
Tank Id:	7

APPLE TRACT (Continued) **U003421901**

Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	99
UST Comprt ID:	160321
UST ID:	167954
AI Number:	4424

APPLE TRACT (Continued) **U003421901**

Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167955
Facility ID:	93952
Ai Number:	4424
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

APPLE TRACT (Continued) **U003421901**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	99
UST Comprt ID:	160322
UST ID:	167955
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

APPLE TRACT (Continued) **U003421901**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167956
Facility ID:	93952
Ai Number:	4424
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

APPLE TRACT (Continued) **U003421901**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	99
UST Comprt ID:	160323
UST ID:	167956
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

APPLE TRACT (Continued) **U003421901**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167957
Facility ID:	93952
Ai Number:	4424
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

APPLE TRACT (Continued) **U003421901**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	99
UST Comprt ID:	160324
UST ID:	167957
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

APPLE TRACT (Continued) **U003421901**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167958
Facility ID:	93952
Ai Number:	4424
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

APPLE TRACT (Continued) **U003421901**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	99
UST Comprt ID:	160325
UST ID:	167958
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

APPLE TRACT (Continued) **U003421901**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167959
Facility ID:	93952
Ai Number:	4424
Tank Id:	16
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

APPLE TRACT (Continued) **U003421901**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	16
Tank Capacity:	99
UST Comprt ID:	160326
UST ID:	167959
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986

APPLE TRACT (Continued) **U003421901**

Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167960
Facility ID:	93952
Ai Number:	4424
Tank Id:	15
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

APPLE TRACT (Continued) **U003421901**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	15
Tank Capacity:	99
UST Comprt ID:	160327
UST ID:	167960
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167961
Facility ID:	93952
Ai Number:	4424

APPLE TRACT (Continued) **U003421901**

Tank Id:	14
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	14
Tank Capacity:	99
UST Comprt ID:	160328
UST ID:	167961

APPLE TRACT (Continued) **U003421901**

AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167962
Facility ID:	93952
Ai Number:	4424
Tank Id:	13
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

APPLE TRACT (Continued) **U003421901**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	13
Tank Capacity:	99
UST Comprt ID:	160329
UST ID:	167962
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

APPLE TRACT (Continued) **U003421901**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167963
Facility ID:	93952
Ai Number:	4424
Tank Id:	12
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

APPLE TRACT (Continued) **U003421901**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	12
Tank Capacity:	99
UST Comprt ID:	160330
UST ID:	167963
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

APPLE TRACT (Continued) **U003421901**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	99
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	167964
Facility ID:	93952
Ai Number:	4424
Tank Id:	11
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

APPLE TRACT (Continued) **U003421901**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	11
Tank Capacity:	99
UST Comprt ID:	160331
UST ID:	167964
AI Number:	4424
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

APPLE TRACT (Continued) **U003421901**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	A & B PROPERTIES INC
Contact Mailing Address (Delivery):	11655 NORTH FWY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77060 3705
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93952
Additional ID:	923561262002118
Princ ID:	932561262002118
AI Number:	4424
Facility Name:	APPLE TRACT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JACK APPLE/

LX2094 **APPLE TRACT** **TX VCP** **S123820326**
WNW **811 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX 78703**
0.053 mi.
280 ft. **Site 10 of 15 in cluster LX**

Actual:
449 ft.

Focus Map:
11

VCP TCEQ:

Name:	APPLE TRACT
Address:	811 W 6TH ST
City,State,Zip:	AUSTIN, TX 78703
Region:	REGION 11 - AUSTIN
Facility ID:	780
VCP Record Date:	05/27/1998
Facility Type:	AUTO DEALERSHIP
PCA Number:	31690
Project Manager:	MDUNN
Phase:	COMPLETED
Acres at Site:	2.7
REM Program:	VCP
RN Number:	RN102061397
Former Facility Type:	Not reported
Site Address Description:	811-814 WEST 6TH STREET

APPLE TRACT (Continued) **S123820326**

Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	05/27/1998
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	TXD980879795
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	07/24/2000
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	05/27/1998
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1998-06-30 00:00:00
Soil Target COC Class:	TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	780
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	316900
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	200-37/D
Latitude:	30.27
Longitude:	-97.75

LG2095 **NIEMAN ELECTRICAL** **EDR Hist Auto** **1013767263**
SSW **107 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
280 ft. **Site 8 of 26 in cluster LG**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	NIEMAN ELECTRICAL	AUTOMOBILE REPAIRING
1940	NIEMAN ELECTRICAL	AUTOMOBILE ELECTRICAL SERVICE

LG2096 SSW < 1/8 0.053 mi. 280 ft. — **NIEMAN ELEC SER**, **107 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013767262** / **N/A**

Site 9 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	NIEMAN ELEC SER	AUTOMOBILE REPAIRERS

LG2097 SSW < 1/8 0.053 mi. 280 ft. — **ABADIE & ROLAND TAILORS**, **107 5TH ST W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013786539** / **N/A**

Site 10 of 26 in cluster LG

Actual: 489 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	ABADIE & ROLAND TAILORS	CLOTHES PRESSERS AND CLEANERS

LG2098 SSW < 1/8 0.053 mi. 280 ft. — **TAYLOR VIVIEN REPR SHOP**, **123 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013755445** / **N/A**

Site 11 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	TAYLOR VIVIEN REPR SHOP	REPAIR SHOPS

ME2099 NNE < 1/8 0.053 mi. 280 ft. — **B & N AXLE SERVICE**, **219 4TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013753169** / **N/A**

Site 3 of 4 in cluster ME

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	B & N AXLE SERVICE	AUTOMOBILE REPAIRING
1980	B & N AXLE SERVICE	AUTOMOBILE REPAIRING
1984	B & N AXLE SERVICE	AUTOMOBILE REPAIRING

ME2100 NNE < 1/8 0.053 mi. 280 ft. — **B & N AXLE SERVICE**, **219 4TH ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013753168** / **N/A**

Site 4 of 4 in cluster ME

Actual: 479 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1970	B & N AXLE SERVICE	AUTOMOBILE REPAIRING
1975	B & N AXLE SERVICE	AUTOMOBILE REPAIRING
1990	B & N AXLE SERVICE INC AUTO REP	AUTOMOBILE REPAIRING

LG2101 SSW < 1/8 0.053 mi. 280 ft. — **DICKARD R AUTO REPR**, **104 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013762889** / **N/A**

Site 12 of 26 in cluster LG

Actual: 488 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	DICKARD R AUTO REPR	AUTOMOBILE REPAIRERS

MP2102 ESE < 1/8 0.053 mi. 280 ft. — **BAKER LEONARD**, **1700 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013777235** / **N/A**

Site 1 of 4 in cluster MP

Actual: 561 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	BAKER LEONARD DCLO CLNR	CLOTHES CLEANERS AND PRESSERS
1935	BAKER LEONARD	CLOTHES PRESSERS AND CLEANERS
1940	BAKER LEONARD CLDO	CLOTHES PRESSERS AND CLEANERS
1947	DARLING L L CLEANERS	CLOTHES PRESSERS AND CLEANERS
1953	DARLING L L CLEAN	CLEANERS AND DYERS
1958	DARLING L L CLNS	CLEANERS AND DYERS
1962	DARLING L L CLN	CLEANERS AND DYERS
1965	DARLING L L CLEANERS	CLEANERS AND DYERS
1969	DARLING L L	Drycleaning Plants, Except Rugs
1970	DAILING L L CLEANERS	CLEANERS AND DYERS
1970	DARLING L L	Drycleaning Plants, Except Rugs
1971	DARLING L L	Drycleaning Plants, Except Rugs
1972	DARLING L L	Drycleaning Plants, Except Rugs
1973	DARLING L L	Drycleaning Plants, Except Rugs
1974	DARLING L L	Drycleaning Plants, Except Rugs
1975	DARLING L L CLEANERS	CLEANERS AND DYERS
1975	DARLING L L	Drycleaning Plants, Except Rugs
1976	DARLING L L	Drycleaning Plants, Except Rugs
1977	DARLING L L	Drycleaning Plants, Except Rugs
1980	DARTING L L CLEANERS	CLEANERS AND DYERS

LG2103 SSW < 1/8 0.053 mi. 280 ft. — **111 13 BARGE ROBT AUTO REPR**, **111 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774031** / **N/A**

Site 13 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	111 13 BARGE ROBT AUTO REPR	AUTOMOBILE REPAIRERS

LG2104 SSW < 1/8 0.053 mi. 280 ft. — **LUNCEFORD THOMAS J AU**, **127 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013764048** / **N/A**

Site 14 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1911	LUNCEFORD THOMAS J AU	AUTOMOBILE GARAGES

LG2105 SSW < 1/8 0.053 mi. 280 ft. — **111 15 BENSON MOTOR CO**, **111 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013767947** / **N/A**

Site 15 of 26 in cluster LG

Actual: 488 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	111 15 BENSON MOTOR CO	AUTOMOBILE SERVICE
1929	111 15 BENSON MOTOR CO	AUTOMOBILE REPAIRERS
1935	111 15 BENSON MOTOR CO	AUTOMOBILE SERVICE
1935	111 15 BENSON MOTOR CO	AUTOMOBILE REPAIRERS

LG2106 SSW < 1/8 0.053 mi. 280 ft. — **EPPLER J LAYTON REPR**, **115 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775389** / **N/A**

Site 16 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	EPPLER J LAYTON REPR	REPAIR SHOPS

LG2107 SSW < 1/8 0.053 mi. 280 ft. — **SE COR BLUE PENNANT TIRE**, **114 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013761340** / **N/A**

Site 17 of 26 in cluster LG

Actual: 489 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1935	SE COR BLUE PENNANT TIRE	AUTOMOBILE SERVICE STATIONS

MQ2108 ENE < 1/8 0.053 mi. 280 ft. — **TOSCO MARKETING COMPANY**, **3208 EAST AVE**, **AUSTIN, TX 78705** — **EDR Hist Auto** — **1021833440** / **N/A**

Site 1 of 18 in cluster MQ

Actual: 588 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1997	TOSCO MARKETING COMPANY	Convenience Stores

MQ2109 ENE < 1/8 0.053 mi. 280 ft. — **7-ELEVEN #36560**, **3208 E SH 71**, **AUSTIN, TX** — **TX HIST UST** — **S128728694** / **N/A**

Site 2 of 18 in cluster MQ

Actual: 588 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	7-ELEVEN #36560
Address:	3208 E SH 71
City,State,Zip:	AUSTIN, TX
Id UST:	3244
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LG2110 SSW < 1/8 0.053 mi. 280 ft. — **CITIES SERVICE STA**, **120 5TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013756575** / **N/A**

Site 18 of 26 in cluster LG

Actual: 488 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	HANCHEY J LEE FILLING	GASOLINE AND OIL SERVICE STATIONS
1940	SW COR STEVENS STORES	GASOLINE AND OIL SERVICE STATIONS
1953	CITIES SERVICE STA	GASOLINE STATIONS

LG2111 SSW < 1/8 0.053 mi. 280 ft. — **BERGSTROM BROS**, **119 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013756306** / **N/A**

Site 19 of 26 in cluster LG

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	BERGSTROM BROS	AUTOMOBILE REPAIRERS

LG2112 SSW < 1/8 0.053 mi. 280 ft. — **NE COR COX REALIZATION CO**, **117 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013763566** / **N/A**

Site 20 of 26 in cluster LG

Actual: 488 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	NE COR COX REALIZATION CO	AUTOMOBILE FILLING STATIONS
1922	HEIERMAN WELDING	AUTOMOBILE REPAIRERS

MR2113 ESE < 1/8 0.053 mi. 280 ft. — **JIMS CONOCO**, **1308 LAVACA ST**, **AUSTIN, TX 78701** — **TX LPST**, **TX Ind. Haz Waste** — **S102748661** / **N/A**

Site 1 of 12 in cluster MR

Actual: 540 ft. LPST:

Focus Map: 11

Name:	JIMS CONOCO
Address:	1308 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0046616
LPST Id:	097790
Facility Location:	LAVACA ST @ 14TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/30/1991
Entered Date:	01/30/1991
Reported Date:	01/30/1991
Closure Date:	02/15/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	KMC
Responsible Party Name:	Not reported
Responsible Party Contact:	BRAD HEY
Responsible Party Address:	PO BOX 15605
Responsible Party City,St,Zip:	AUSTIN, TX 78761
Responsible Party Telephone:	512/926-4132
Reported Date:	01/30/1991
Case Start Date:	02/15/1993
Reference Number:	RN102042611
Project Manager:	KMC

JIMS CONOCO (Continued) **S102748661**

Ind. Haz Waste:

Name:	JIMS CONOCO
Address:	1308 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	61811
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	1308 Lavaca St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	JIMS CONOCO
Contact Name:	JIM OCONNER
Contact Telephone Number:	512-4782626
Mailing Address:	1308 LAVACA ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787011633
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20151
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JIMS CONOCO
Operator Address:	Not reported
Operator Address 2:	Not reported

JIMS CONOCO (Continued) **S102748661**

Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JIMS CONOCO
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	JIM OCONNER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1308 LAVACA ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4782626
Contact Fax:	Not reported
Contact Email:	Not reported

MR2114 **JIMS CONOCO** **TX UST** **U001278047**
ESE **1308 LAVACA ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.053 mi.
280 ft. **Site 2 of 12 in cluster MR**

Actual:
540 ft.

Focus Map:
11

UST:

Name:	JIMS CONOCO
Address:	1308 LAVACA ST
City,State,Zip:	AUSTIN, TX 787011633
AI Number:	46616
Facility Type:	RETAIL
Facility Begin Date:	12/07/1988
Facility Status:	INACTIVE
Additional ID:	976819302002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

JIMS CONOCO (Continued) **U001278047**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	BRAD HEY,PRESIDENT
Contact Organization Name:	JIMS CONOCO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129264132
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/21/1988
Signature Name/Title On Earliest Reg Form:	BREAD HEY,PRESIDENT
Application Received Date On Earliest Reg Form:	10/21/1988
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780068
Owner Last Name:	HEY DISTRIBUTING CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	461586832002053
Additional ID:	976819302002117
AI Number:	46616
Owner Effective Begin Date:	12/07/1988
State Tax ID:	17424481657
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121973
Facility ID:	43892

JIMS CONOCO (Continued) **U001278047**

Ai Number:	46616
Tank Id:	5A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5A
Tank Capacity:	500
UST Comprt ID:	17114

JIMS CONOCO (Continued) **U001278047**

UST ID:	121973
AI Number:	46616
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	250
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121974
Facility ID:	43892
Ai Number:	46616
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y

JIMS CONOCO (Continued) **U001278047**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	250
UST Comprt ID:	17115
UST ID:	121974
AI Number:	46616
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

JIMS CONOCO (Continued) **U001278047**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121971
Facility ID:	43892
Ai Number:	46616
Tank Id:	5B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

JIMS CONOCO (Continued) **U001278047**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5B
Tank Capacity:	500
UST Comprt ID:	17112
UST ID:	121971
AI Number:	46616
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

JIMS CONOCO (Continued) **U001278047**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121970
Facility ID:	43892
Ai Number:	46616
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

JIMS CONOCO (Continued) **U001278047**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	17111
UST ID:	121970
AI Number:	46616
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

JIMS CONOCO (Continued) **U001278047**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121969
Facility ID:	43892
Ai Number:	46616
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

JIMS CONOCO (Continued) **U001278047**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	17110
UST ID:	121969
AI Number:	46616
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

JIMS CONOCO (Continued) **U001278047**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	10/21/1988
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	121972
Facility ID:	43892
Ai Number:	46616
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

JIMS CONOCO (Continued) **U001278047**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	2000
UST Comprt ID:	17113
UST ID:	121972
AI Number:	46616
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

JIMS CONOCO (Continued) **U001278047**

Facility Billing Contacts:

Contact Organization Name:	HEY DISTRIBUTING CORPORATION
Contact Mailing Address (Delivery):	107 BIRDIE DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	THE HILLS, TX 78738 1347
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	43892
Additional ID:	976819302002117
Princ ID:	461586832002053
AI Number:	46616
Facility Name:	JIMS CONOCO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BRAD HEY/

HIST UST AUSTIN:

Name:	JIM'S CONOCO
Address:	1308 LAVACA ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0224
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MR2115 **OCONNERS JIM MOBIL GAS SERVICE** **EDR Hist Auto** **1013753777**
ESE **1308 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX 78713**
0.053 mi.
280 ft. **Site 3 of 12 in cluster MR**

Actual:
540 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1947	AYERS BROS FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	AKERS SERV STA	GASOLINE STATIONS
1958	DONS MOBILGAS	GASOLINE STATIONS
1962	DONS MOBILGAS STA	GASOLINE STATIONS
1965	DONS MOBILGAS STATION	GASOLINE STATIONS
1969	DONS MOBIL GAS	Gasoline Service Stations
1970	DONS MOBILGAS STATION	GASOLINE STATIONS
1970	DONS MOBIL GAS	Gasoline Service Stations
1971	DONS MOBIL GAS	Gasoline Service Stations
1972	DONS MOBIL GAS	Gasoline Service Stations
1975	OCONNERS JIM MOBIL GAS SERVICE	GASOLINE STATIONS
1976	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1977	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1978	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1979	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1980	OCONNERS JIM MOBIL GAS SERVICE	GASOLINE STATIONS
1980	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1982	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations

OCONNERS JIM MOBIL GAS SERVICE (Continued) **1013753777**

1983	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1984	OCONNERS JIM MOBIL GAS SERVICE	GASOLINE STATIONS
1985	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1986	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1987	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1988	O CONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1989	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1990	OCONNERS JIM CONOCO GAS SERV	GASOLINE STATIONS
1990	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1991	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1992	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1993	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1994	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1995	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
1999	JIM AUTO SERVICE	Automotive Repair Shops, NEC
2000	JIM AUTO SERVICE	Automotive Repair Shops, NEC
2001	JIM OCONNAR AUTO SERVICE	Automotive Repair Shops, NEC
2002	JIM OCONNAR AUTO SERVICE	Automotive Repair Shops, NEC
2003	JIM OCONNAR AUTO SERVICE	Automotive Repair Shops, NEC
2004	OCONNOR JIM AUTO SERVICE	Automotive Repair Shops, NEC
2004	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
2005	OCONNOR JIM AUTO SERVICE	Automotive Repair Shops, NEC
2005	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
2006	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
2006	OCONNOR JIM AUTO SERVICE	Automotive Repair Shops, NEC
2007	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
2007	OCONNOR JIM AUTO SERVICE	Automotive Repair Shops, NEC
2008	OCONNOR JIM MOBIL SERVICE STN	Gasoline Service Stations
2008	OCONNOR JIM AUTO SERVICE	Automotive Repair Shops, NEC

2116 **CRUZ AUTOMOTIVE** **EDR Hist Auto** **1013762936**
SE **8827 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.053 mi.
281 ft.

Actual: EDR Hist Auto
657 ft.

Focus Map:
6

Year:	Name:	Type:
1990	CRUZ AUTOMOTIVE	AUTOMOBILE REPAIRING

LH2117 **ALEXANDER CLY D FILL** **EDR Hist Auto** **1013755995**
SSW **301 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 4 of 26 in cluster LH**

Actual: EDR Hist Auto
484 ft.

Focus Map:
11

Year:	Name:	Type:
1940	ALEXANDER CLY D FILL	GASOLINE AND OIL SERVICE STATIONS

LH2118 **302 12 FROMME MOTOR CO** **EDR Hist Auto** **1013755874**
SSW **302 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 5 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	302 12 FROMME MOTOR CO	AUTOMOBILE REPAIRERS

LH2119 **0 & M AUTO REPAIR GR** **EDR Hist Auto** **1013758860**
SSW **318 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 6 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	0 & M AUTO REPAIR GR	AUTOMOBILE REPAIRING

LH2120 **D & M AUTO REPAIR** **EDR Hist Auto** **1013763006**
SSW **318 5TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.053 mi.
281 ft. **Site 7 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	D & M AUTO REPAIR	AUTOMOBILE REPAIRING
1975	D & M AUTO REPAIR	AUTOMOBILE REPAIRING

LH2121 **ELLIOTT EUNICE E RADIATOR REPR** **EDR Hist Auto** **1013769096**
SSW **318 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 8 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	ELLIOTT EUNICE E RADIATOR REPR	RADIATOR REPAIRERS-AUTOMOBILE
1958	D&M AUTO REPRS	AUTOMOBILE REPAIRING

JP2122 **DARTER HOWARD T** **EDR Hist Auto** **1013760110**
SSW **217 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 6 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	DARTER HOWARD T	AUTOMOBILE REPAIRING

JP2123 **DARTER H T AUTO** **EDR Hist Auto** **1013769142**
SSW **217 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 7 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	SANDSTROM C R GAR	AUTOMOBILE GARAGES
1922	SANDSTROM C R GAR	AUTOMOBILE REPAIRERS
1935	DARTER H T AUTO	AUTOMOBILE REPAIRERS

LH2124 **PILAND & ELLIOTT SER** **EDR Hist Auto** **1013764256**
SSW **311 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
281 ft. **Site 9 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	PILAND & ELLIOTT SER	GASOLINE AND OIL SERVICE STATIONS
1935	PILAND & ELLIOTT SER	AUTOMOBILE REPAIRERS

LH2125 **TRAVIS MOTOR EXCHANGE REPR** **EDR Hist Auto** **1013773909**
SSW **311 5TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.053 mi.
281 ft. **Site 10 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	TRAVIS MOTOR EXCHANGE REPR	AUTOMOBILE REPAIRING

LH2126 SSW < 1/8 0.053 mi. 281 ft. | **PILAND & ELLIOTT**
311 5TH E
AUSTIN, TX
Site 11 of 26 in cluster LH | **EDR Hist Auto** | **1013764255**
N/A

Actual: 484 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	PILAND & ELLIOTT FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1947	PILAND & ELLIOTT FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1953	PILAND & ELLIOTT GAS STA	GASOLINE STATIONS
1958	PILAND & ELLIOTT	AUTOMOBILE REPAIRING

LX2127 WNW < 1/8 0.053 mi. 282 ft. | **MCMORRIS FORD**
808 W 6TH ST
AUSTIN, TX 78703
Site 11 of 15 in cluster LX | **TX UST** | **U003566443**
N/A

Actual: 454 ft.
Focus Map: 11

UST:

Name:	MCMORRIS FORD
Address:	808 W 6TH ST
City,State,Zip:	AUSTIN, TX 787035404
AI Number:	68769
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	611852022002204
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	SCOTT YOUNG,
Contact Organization Name:	MCMORRIS FORD
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124776131
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/26/1995
Signature Name/Title On Earliest Reg Form:	ROY BUTLER,
Application Received Date On Earliest Reg Form:	08/05/1996
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601414600
Owner Last Name:	BUTLER
Owner First Name:	ROY
Owner Middle Name:	Not reported

MCMORRIS FORD (Continued) **U003566443**

Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	619852012002204
Additional ID:	611852022002204
AI Number:	68769
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/05/1996
Number of Compartments:	1
Tank Capacity:	750
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	180947
Facility ID:	104079
Ai Number:	68769
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/07/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

MCMORRIS FORD (Continued) **U003566443**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	750
UST Comprt ID:	168857
UST ID:	180947
AI Number:	68769
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

MCMORRIS FORD (Continued) **U003566443**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BUTLER ROY
Contact Mailing Address (Delivery):	PO BOX 9190
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78766 9190
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	104079
Additional ID:	611852022002204
Princ ID:	619852012002204
AI Number:	68769
Facility Name:	MCMORRIS FORD
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ROY BUTLER/

LX2128 **MCMORRIS FORD** **TX LPST** **S116698454**
WNW **808 W 6TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78703**
0.053 mi.
282 ft. **Site 12 of 15 in cluster LX**

Actual:
454 ft.

Focus Map:
11

LPST:

Name:	MCMORRIS FORD
Address:	808 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0068769
LPST Id:	109726
Facility Location:	808 W 6TH
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/07/1995
Entered Date:	10/12/1995
Reported Date:	06/19/1995
Closure Date:	09/04/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the

MCMORRIS FORD (Continued) **S116698454**

assessment results document that groundwater is not affected.

Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	SCOTT YOUNG
Responsible Party Address:	PO BOX 1525
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	/-
Reported Date:	06/19/1995
Case Start Date:	09/04/1996
Reference Number:	RN100587419
Project Manager:	XYZ

CENTRAL REGISTRY:

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600297501
Customer Name:	MCMORRIS FORD
Customer Legal Name:	McMorris Downtown Ford, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600297501
Customer Name:	MCMORRIS FORD
Customer Legal Name:	McMorris Downtown Ford, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE

MCMORRIS FORD (Continued) **S116698454**

Status Date:	##########
Customer Number:	CN601414600
Customer Name:	BUTLER, ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601414600
Customer Name:	BUTLER, ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604452334
Customer Name:	BUTLER ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604452334
Customer Name:	BUTLER ROY

MCMORRIS FORD (Continued) **S116698454**

Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600297501
Customer Name:	MCMORRIS FORD
Customer Legal Name:	McMorris Downtown Ford, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601414600
Customer Name:	BUTLER, ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604452334
Customer Name:	BUTLER ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########

MCMORRIS FORD (Continued) **S116698454**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600297501
Customer Name:	MCMORRIS FORD
Customer Legal Name:	McMorris Downtown Ford, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Regulated Entity Number:	RN100587419
Name:	MCMORRIS FORD
Address:	808 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5404
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601414600
Customer Name:	BUTLER, ROY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	808 W 6th, Austin, TX

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

LX2129 **MCMORRIS FORD** **RCRA NonGen / NLR** **1000341837**
WNW **808 W 6TH** **FINDS** **TXD981155153**
< 1/8 **AUSTIN, TX 78703** **ECHO**
0.053 mi. **TX Ind. Haz Waste**
282 ft. **Site 13 of 15 in cluster LX**

Actual:
454 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Mcmorris Ford
Handler Address:	W 6TH
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD981155153
Contact Name:	KEN NEECK

MCMORRIS FORD (Continued) **1000341837**

Contact Address:	PO BOX 18149
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Telephone:	512-443-5000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 18149
Mailing City,State,Zip:	AUSTIN, TX 78760
Owner Name:	Mcmorris Ford
Owner Type:	Other
Operator Name:	Mcmorris Ford
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

MCMORRIS FORD (Continued) **1000341837**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MCMORRIS FORD
Legal Status: Other

MCMORRIS FORD (Continued) **1000341837**

Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 18149
Owner/Operator City,State,Zip:	AUSTIN, TX 78760
Owner/Operator Telephone:	512-443-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MCMORRIS FORD	
Legal Status:	Other
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 18149
Owner/Operator City,State,Zip:	AUSTIN, TX 78760
Owner/Operator Telephone:	512-443-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: WILLIAM D MCMORRIS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	808 W 6TH
Owner/Operator City,State,Zip:	AUSTIN, TX 78703-0000
Owner/Operator Telephone:	512-472-8481
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960522
Handler Name: MCMORRIS FORD	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010727
Handler Name: MCMORRIS FORD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

MCMORRIS FORD (Continued) **1000341837**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005088528

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000341837
Registry ID:	110005088528
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005088528
Name:	MCMORRIS FORD
Address:	808 W 6TH
City,State,Zip:	AUSTIN, TX 78703

Ind. Haz Waste:

Name:	MCMORRIS FORD
Address:	808 W 6TH ST
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66293
Registration Initial Notification Date:	02/12/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981155153
Primary NAICS Code:	Not reported
Status Change Date:	19850212
Land Type:	OTHER
Description of Facility Site Location:	808 W 6th, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1

MCMORRIS FORD (Continued) **1000341837**

Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	MCMORRIS FORD
Contact Name:	KEN NEECK
Contact Telephone Number:	512-4435000
Mailing Address:	PO BOX 18149
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787608149
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21573
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031021
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MCMORRIS FORD
Operator Address:	PO BOX 18149
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78760
Operator Country:	UNITED STA
Operator Telephone:	1-512-4435000
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	17416051328
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MCMORRIS FORD
Owner Mailing Address:	PO BOX 18149
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78760
Owner Country:	UNITED STA
Owner Telephone:	1-512-4435000
Owner Fax:	Not reported

MCMORRIS FORD (Continued) **1000341837**

Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	17416051328
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 18149
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4435000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 18149
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4435000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	KEN NEECK
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 18149
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78760
Contact Phone:	1-512-4435000
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	808 W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000302668
Principal Name:	MCMORRIS FORD
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	808 W 6TH ST
Mailing Address 2:	Not reported

MCMORRIS FORD (Continued) **1000341837**

Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000302668
Principal Name:	MCMORRIS FORD
Attention Name:	Not reported
Attention Suffix:	NWG

LX2130 **ME MORRIS FORD INC** **EDR Hist Auto** **1013776131**
WNW **808 W 6TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78703**
0.053 mi.
282 ft. **Site 14 of 15 in cluster LX**

Actual:
454 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	ME MORRIS FORD INC	AUTOMOBILE REPAIRING

LH2131 **316 18 DELZELL & DEMENT AUTO REPR** **EDR Hist Auto** **1013771015**
SSW **316 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 12 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	316 18 DELZELL & DEMENT AUTO RE	AUTOMOBILE REPAIRERS

LH2132 **DELZELL & DEMENT AUTO REPRS** **EDR Hist Auto** **1013756956**
SSW **316 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 13 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	ELLIOTTS RADIATOR	RADIATOR REPAIRERS-AUTOMOBILE
1940	DELZELL & DEMENT AUTO REPRS	AUTOMOBILE REPAIRING
1947	DEMENT & PETMECKY AUTO REPRS	AUTOMOBILE REPAIRING
1953	DEMENT & PETMECKY BRAKE SERV AU	AUTOMOBILE REPAIRING

JP2133 **CULLEN HUGH H GARAGE** **EDR Hist Auto** **1013759941**
SSW **206 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 8 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	CULLEN HUGH H GARAGE	AUTOMOBILE GARAGES

CULLEN HUGH H GARAGE (Continued) **1013759941**

1922	MALMBERG AUTO REPR	AUTOMOBILE GARAGES
1922	MALMBERG AUTO REPR	AUTOMOBILE REPAIRERS

JP2134 **RUMSEYS GARAGE** **EDR Hist Auto** **1013760143**
SSW **211 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 9 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	FOWLER J W AUTO REPR	AUTOMOBILE REPAIRERS
1922	RUMSEYS GARAGE	AUTOMOBILE GARAGES

JP2135 **HOME STEAM LNDY** **EDR Hist Cleaner** **1013782005**
SSW **211 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 10 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	HOME STEAM LNDY	LAUNDRIES

LH2136 **D&M AUTO REPR** **EDR Hist Auto** **1013775186**
SSW **305 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 14 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	D&M AUTO REPR	AUTOMOBILE REPAIRING

LH2137 **REAR SMITH AUTO SERVICE** **EDR Hist Auto** **1013772582**
SSW **305 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 15 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	HART A W CO GARAGE	AUTOMOBILE GARAGES
1922	HART A W CO GARAGE	AUTOMOBILE REPAIRERS
1922	HART A W CO GARAGE	AUTOMOBILE SERVICE STATIONS
1965	REAR SMITH AUTO SERVICE	AUTOMOBILE REPAIRING
1965	RIEGERS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1980	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING
1984	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING

LH2138 **FROMME MOTOR CO** **EDR Hist Auto** **1013757172**
SSW **304 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 16 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	FROMME MOTOR CO	AUTOMOBILE REPAIRERS

LH2139 **SAN JACINTO GARAGE** **EDR Hist Auto** **1013761421**
SSW **305 5TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.053 mi.
282 ft. **Site 17 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING
1975	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING

JP2140 **DARTER SLIM** **EDR Hist Auto** **1013775237**
SSW **213 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 11 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	DARTER SLIM	RADIATOR REPAIRING

LH2141 **LOCKE WILL MOTOR** **EDR Hist Auto** **1013757886**
SSW **306 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 18 of 26 in cluster LH**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	LOCKE WILL MOTOR	AUTOMOBILE REPAIRERS
1940	LOCKE WILL MOTOR	AUTOMOBILE GARAGES

LH2142 SSW < 1/8 0.053 mi. 282 ft. — **RIEGERS GARAGE**, **307 5TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013755285** / **N/A**

Site 19 of 26 in cluster LH

Actual: 484 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1953	RIEGERS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1958	RIEGERS GARAGE	AUTOMOBILE REPAIRING
1962	RIEGERS GARAGE AUTO	AUTOMOBILE REPAIRING

MP2143 ESE < 1/8 0.053 mi. 282 ft. — **CAMPBELL CLEANERS**, **1620 LAVACA**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013784067** / **N/A**

Site 2 of 4 in cluster MP

Actual: 559 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	CAMPBELL CLEANERS	CLEANERS AND DYERS

JP2144 SSW < 1/8 0.053 mi. 282 ft. — **WATT STUART SERVICE STATION**, **200 5TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013776957** / **N/A**

Site 12 of 27 in cluster JP

Actual: 486 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	WATT STUART SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS

JP2145 SSW < 1/8 0.053 mi. 282 ft. — **FIFTH & BRAZOS SERVICE**, **200 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775341** / **N/A**

Site 13 of 27 in cluster JP

Actual: 486 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	FIFTH & BRAZOS SERVICE	GASOLINE AND OIL SERVICE STATIONS

LH2146 SSW < 1/8 0.053 mi. 282 ft. — **MILES DEAN DCLO CLNR**, **324 5TH ST E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013784579** / **N/A**

Site 20 of 26 in cluster LH

Actual: 484 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1922	MILES DEAN DCLO CLNR	CLOTHES CLEANERS AND PRESSERS
1929	MILES BROS CLO CLNRS	CLOTHES CLEANERS AND PRESSERS

JP2147 SSW < 1/8 0.053 mi. 282 ft. — **QUICK SERVICE GAR PIERCE MOTOR CO**, **204 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013767998** / **N/A**

Site 14 of 27 in cluster JP

Actual: 486 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	QUICK SERVICE GAR PIERCE MOTOR	AUTOMOBILE GARAGES
1929	204 6 HASTON AUTO BODY	AUTOMOBILE REPAIRERS

JP2148 SSW < 1/8 0.053 mi. 282 ft. — **205 7 AUSTIN RUBBER CO**, **205 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013755858** / **N/A**

Site 15 of 27 in cluster JP

Actual: 486 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	205 7 AUSTIN RUBBER CO	AUTOMOBILE GARAGES

JP2149 SSW < 1/8 0.053 mi. 282 ft. — **CAPITOL CHEVROLET**, **218 5TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774689** / **N/A**

Site 16 of 27 in cluster JP

Actual: 486 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	CAPITOL CHEVROLET	AUTOMOBILE REPAIRING

JP2150 **BOWDIN M L SPRING** **EDR Hist Auto** **1013753386**
SSW **218 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 17 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	CLUCK 0 S AUTO REPR	AUTOMOBILE GARAGES
1922	BOWDIN M L SPRING	AUTOMOBILE REPAIRERS
1922	CLUCK 0 S AUTO REPR	AUTOMOBILE REPAIRERS

JP2151 **BEATY WELDING & RADIATOR** **EDR Hist Auto** **1013762444**
SSW **219 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.053 mi.
282 ft. **Site 18 of 27 in cluster JP**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	REESE G A AUTO REPR	AUTOMOBILE REPAIRERS
1929	BEATY WELDING & RADIATOR	AUTOMOBILE REPAIRERS

JP2152 **CAPITOL CHEVROLET CO** **EDR Hist Auto** **1013765565**
SSW **220 5TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
283 ft. **Site 19 of 27 in cluster JP**

Actual:
485 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	CAPITOL CHEVROLET CO	AUTOMOBILE REPAIRING

JP2153 **ELECTRICAL SERVICE CO THE** **EDR Hist Auto** **1013774795**
SSW **221 5TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
283 ft. **Site 20 of 27 in cluster JP**

Actual:
485 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	MILLER AUTO SUP CO	AUTOMOBILE REPAIRERS
1929	ELECTRICAL SERVICE CO THE	AUTOMOBILE REPAIRERS
1935	CARSON & HEDBLOM	GASOLINE AND OIL SERVICE STATIONS

JP2154 SSW < 1/8 0.054 mi. 283 ft. — **BURKHALTER E E AUTO**, **223 5TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774760** / **N/A**

Site 21 of 27 in cluster JP

Actual: 485 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	BURKHALTER M F GAR	AUTOMOBILE GARAGES
1922	BURKHALTER M F GAR	AUTOMOBILE REPAIRERS
1929	BURKHALTER E E AUTO	AUTOMOBILE REPAIRERS

LB2155 WNW < 1/8 0.054 mi. 283 ft. — **AUSTIN FRAME & WHEEL SERVICE AUTO REPR**, **526 1ST ST S**, **TRAVIS (County), TX 78704** — **EDR Hist Auto** — **1013774388** / **N/A**

Site 3 of 9 in cluster LB

Actual: 457 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	AUSTIN FRAME & WHEEL SERVICE AU	AUTOMOBILE REPAIRING

KQ2156 ENE < 1/8 0.054 mi. 283 ft. — **SMITH LANDRY C CLDO**, **706 6TH E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013786255** / **N/A**

Site 2 of 2 in cluster KQ

Actual: 456 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1922	SMITH LANDRY C CLDO	CLOTHES CLEANERS AND PRESSERS

KY2157 ESE < 1/8 0.054 mi. 283 ft. — **LINDSAY AUTO ELEC**, **504 LAVACA**, **AUSTIN, TX** — **EDR Hist Auto** — **1013760687** / **N/A**

Site 7 of 21 in cluster KY

Actual: 491 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	LINDSAY AUTO ELEC	AUTOMOBILE REPAIRING
1947	LINDSAY AUTO ELEC AUTO REPR	AUTOMOBILE REPAIRING

LB2158 WNW < 1/8 0.054 mi. 284 ft. | **AUSTIN FRAME & WHEEL SERVICE AUTO REPR**
525 1ST ST S
TRAVIS (County), TX 78704
Site 4 of 9 in cluster LB | **EDR Hist Auto** | **1013765294**
N/A

Actual: 459 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1965	AUSTIN FRAME & WHEEL	AUTOMOBILE REPAIRING
1970	AUSTIN FRAME & WHEEL SERVICE AU	AUTOMOBILE REPAIRING

MS2159 SSW < 1/8 0.054 mi. 284 ft. | **MASSEVS GARAGE AUTO REPR**
6507 RIVERSIDE DR E
TRAVIS (County), TX 78704
Site 1 of 2 in cluster MS | **EDR Hist Auto** | **1013754561**
N/A

Actual: 517 ft.
Focus Map: 15

EDR Hist Auto

Year:	Name:	Type:
1965	KASPERS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1970	MASSEVS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

MS2160 SSW < 1/8 0.054 mi. 284 ft. | **MASSEYS GARAGE**
6507 RIVERSIDE DR E
SOUTH AUSTIN, TX
Site 2 of 2 in cluster MS | **EDR Hist Auto** | **1013764032**
N/A

Actual: 517 ft.
Focus Map: 15

EDR Hist Auto

Year:	Name:	Type:
1958	MASSEYS GARAGE	AUTOMOBILE REPAIRING

KG2161 ESE < 1/8 0.054 mi. 285 ft. | **400 LAVACA ST AUSTIN**
400 LAVACA ST
AUSTIN, TX 78701
Site 2 of 4 in cluster KG | **TX NON REGIST PST** | **S122568135**
N/A

Actual: 482 ft.
Focus Map: 11

NON REGIST PST:

RN Number:	RN103931283
Name:	400 LAVACA ST AUSTIN
Address:	400 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701 4736
Physical Location:	NORTHWEST CORNER LAVACA & 4TH ST
CN Number:	CN601238710
Customer Name:	DICKEY, WILLIAM M
Customer Role:	OWNER
Primary Business:	Parking Lot
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported

400 LAVACA ST AUSTIN (Continued) **S122568135**

ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=987313722003253
RN Number:	RN103931283
Name:	400 LAVACA ST AUSTIN
Address:	400 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701 4736
Physical Location:	NORTHWEST CORNER LAVACA & 4TH ST
CN Number:	CN602438954
Customer Name:	SUSAN MORRIS TRUST AND ANN GRAHAM TRUST CARE OF DELL BOYKIN AUSTIN TRUST
Customer Role:	N/A
Primary Business:	Parking Lot
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=987313722003253

KG2162 **ABANDONED** **TX RDR** **S127541712**
ESE **400 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
285 ft. **Site 3 of 4 in cluster KG**

Actual:
482 ft.

Focus Map:
11

RDR:

RDR ID:	13265
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	ABANDONED
Address:	400 LAVACA ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/4/2007
Due Date:	7/3/2007
Tank Owner:	SUSAN MORRIS/ANN GRAMHAM
Contact Person:	DELL BAYKIN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/18/2007
Project Manager:	Brandy Brooks
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RETURN LETTER SENT: INSUFFICIENT SITE MAP, ANALYSES, NO TEMP, NO TANK DEST. CERTIFICATE, ETC. 1ST ISSUE RC'D 3/1/2004- 5/4/07 RC'D TECH RESP
Review Coordinator:	BLB
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/18/2007
Date Report Returned:	5/27/2004
Region:	Not reported

ABANDONED (Continued) **S127541712**

DKC RDR (misfiled): Not reported

KG2163 **400 LAVACA ST AUSTIN** **TX TANKS** **S126680035**
ESE **400 LAVACA ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.054 mi.
285 ft. **Site 4 of 4 in cluster KG**

Actual:
482 ft.

Focus Map:
11

TANKS:

Facility ID:	126122
Name:	NAME UNKNOWN
Address:	400 LAVACA ST
City,State,Zip:	AUSTIN, TX 787014736
Total UST:	0
Additional ID:	584537082012320
AI Number:	81875
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	Not reported
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN103931283
Name:	400 LAVACA ST AUSTIN
Address:	400 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4736
Status:	ACTIVE
Status Date:	9/10/2003
Customer Number:	CN602438954
Customer Name:	SUSAN MORRIS TRUST AND ANN GRAHAM TRUST CARE OF DELL BOYKIN AUSTIN

400 LAVACA ST AUSTIN (Continued) **S126680035**

	TRUST
Customer Legal Name:	Susan Morris Trust and Ann Graham Trust Care of Dell Boykin Austin Trust
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812930
Primary NAICS Industry Type Description:	Parking Lots and Garages
Physical Location Description:	NORTHWEST CORNER LAVACA & 4TH ST

Regulated Entity Number:	RN103931283
Name:	400 LAVACA ST AUSTIN
Address:	400 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4736
Status:	ACTIVE
Status Date:	9/10/2003
Customer Number:	CN601238710
Customer Name:	DICKEY, WILLIAM M
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	12/12/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812930
Primary NAICS Industry Type Description:	Parking Lots and Garages
Physical Location Description:	NORTHWEST CORNER LAVACA & 4TH ST

IY2164 **KEALHOFER STARR TIRE** **EDR Hist Auto** **1013763676**
ESE **910 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
285 ft. **Site 2 of 3 in cluster IY**

Actual:
545 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	KEALHOFER STARR TIRE	GASOLINE STATIONS

IY2165 **COMMERICAL TITLE BUILDING** **TX LPST** **S105121882**
ESE **910 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.054 mi.
285 ft. **Site 3 of 3 in cluster IY**

Actual:
545 ft.

LPST:

Focus Map:
11

Name:	COMMERICAL TITLE BUILDING
Address:	910 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	095340
Facility Location:	LAVACA
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/30/1990

COMMERICAL TITLE BUILDING (Continued) **S105121882**

Entered Date:	05/02/1990
Reported Date:	04/30/1990
Closure Date:	01/26/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	C AUBREY SMITH
Responsible Party Address:	PO BOX 5910
Responsible Party City,St,Zip:	AUSTIN, TX 78763
Responsible Party Telephone:	512/472-8355
Reported Date:	04/30/1990
Case Start Date:	01/26/1993
Reference Number:	RN106975642
Project Manager:	HWELCH

MT2166 **EKSTROM G A** **EDR Hist Cleaner** **1013778964**
ESE **303 CROCKETT** **N/A**
< 1/8 **WEST AUSTIN, TX**
0.054 mi.
285 ft. **Site 1 of 2 in cluster MT**

Actual:
566 ft.

EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1940	EKSTROM G A	LAUNDRIES

2167 **EURO SPORT CYCLES** **TX Ind. Haz Waste** **S102748099**
WNW **616 W 34TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.054 mi.
286 ft.

Actual:
601 ft.

Ind. Haz Waste:

Focus Map:
8

Name:	EURO SPORT CYCLES
Address:	616 W 34TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	61158
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	02/19/2002
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	616 W 34th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1

EURO SPORT CYCLES (Continued) **S102748099**

Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	EURO SPORT CYCLES
Contact Name:	SARAH B FOSTER
Contact Telephone Number:	Not reported
Mailing Address:	616 W 34TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787051203
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19519
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	EURO SPORT CYCLES
Operator Address:	616 W 34TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17425641374
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EURO SPORT CYCLES
Owner Mailing Address:	616 W 34TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported

EURO SPORT CYCLES (Continued) **S102748099**

Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17425641374
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	616 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	616 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	SARAH FOSTER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	616 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	616 W 34TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000307916
Principal Name:	EURO SPORT CYCLES
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	616 W 34TH ST
Mailing Address 2:	Not reported

EURO SPORT CYCLES (Continued) **S102748099**

Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000307916
Principal Name:	EURO SPORT CYCLES
Attention Name:	Not reported
Attention Suffix:	HWG

JE2168 **AUTOMATIC BENDIX** **EDR Hist Cleaner** **1013785305**
ESE **207 17TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
287 ft. **Site 5 of 6 in cluster JE**

Actual:
522 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1958	AUTOMATIC BENDIX	LAUNDRIES

MU2169 **327 27 HICKS RUBBER CO** **EDR Hist Auto** **1013774062**
NNE **325 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
287 ft. **Site 1 of 5 in cluster MU**

Actual:
480 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	327 27 HICKS RUBBER CO	GASOLINE AND OIL SERVICE STATIONS
1971	ROSE PERRY TRUCK TIRE CENTER*	Auto And Home Supply Stores

---

2170 **YOUNGS REPAIR SHOP** **EDR Hist Auto** **1013777039**
WNW **607 37TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
287 ft.

Actual:
600 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1962	YOUNGS REPAIR SHOP	REPAIR SHOPS

LB2171 **LINDSAY AUTO ELEC** **EDR Hist Auto** **1013760675**
WNW **515 1ST S** **N/A**
< 1/8 **AUSTIN, TX**
0.054 mi.
287 ft. **Site 5 of 9 in cluster LB**

Actual:
459 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	LINDSAY AUTO ELEC	AUTOMOBILE REPAIRING
1965	LINDSAY AUTO ELECTRIC AUTO	AUTOMOBILE REPAIRING
1970	LINDSAV AUTO ELECTRIC AUTO REPR	AUTOMOBILE REPAIRING

LINDSAY AUTO ELEC (Continued) **1013760675**

1970	LINDSAV AUTO ELECTRIC AUTO REPR	AUTOMOBILE ELECTRICAL SERVICE
1975	LINDSAY AUTO ELECTRIC AUTO REPR	AUTOMOBILE REPAIRING
1980	LINDSAY AUTO ELECTRIC SMALL ENG	AUTOMOBILE REPAIRING

2172 SE < 1/8 0.054 mi. 287 ft. **B ALL AUTO SERVICE WOLJOC INC** **EDR Hist Auto** **1013759275**
607 DEEN AVE **N/A**
AUSTIN, TX 78753

Actual: 660 ft. EDR Hist Auto

Focus Map: 6

Year:	Name:	Type:
1980	B ALL AUTO SERVICE WOLJOC INC	AUTOMOBILE REPAIRING

MV2173 WNW < 1/8 0.055 mi. 288 ft. **7-ELEVEN 12705** **TX LPST** **U003103747**
408 W 15TH ST **TX UST** **N/A**
AUSTIN, TX 78701 **TX HIST UST**
TX ASBESTOS
Site 1 of 2 in cluster MV **TX ENF**
TX Financial Assurance

Actual: 535 ft.

Focus Map: 11

LPST:

Name:	7 ELEVEN STORE 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0007176
LPST Id:	118292
Facility Location:	408 W 15TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/03/2009
Entered Date:	04/23/2010
Reported Date:	12/04/2009
Closure Date:	03/07/2011
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	TH2
Responsible Party Name:	Not reported
Responsible Party Contact:	JACK REYNOLDS
Responsible Party Address:	6330 COMMERCE DR STE 190
Responsible Party City,St,Zip:	IRVING, TX 75063
Responsible Party Telephone:	214/277-7820
Reported Date:	12/04/2009
Case Start Date:	03/07/2011
Reference Number:	RN102021409
Project Manager:	THASAN

UST:

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 787011625

7-ELEVEN 12705 (Continued) **U003103747**

AI Number:	7176
Facility Type:	RETAIL
Facility Begin Date:	04/01/1973
Facility Status:	ACTIVE
Additional ID:	868202132002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	PEGGIE BETZ,REG GAS COMP SPEC
Contact Organization Name:	7-ELEVEN 12705
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	868202132002117
Ai Number:	7176
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

7-ELEVEN 12705 (Continued) **U003103747**

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	868202132002117
AI Number:	7176
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46178
Cert ID:	381581
AI Number:	7176
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	364257
AI Number:	7176
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	348205
AI Number:	7176
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	329983
AI Number:	7176
Self Certification Date:	01/03/2020
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	314451
AI Number:	7176
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	296297
AI Number:	7176
Self Certification Date:	12/24/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	280741
AI Number:	7176
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	263835
AI Number:	7176
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	247279
AI Number:	7176
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	229607
AI Number:	7176
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46178
Cert ID:	28130
AI Number:	7176
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28129
AI Number:	7176
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28128
AI Number:	7176
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28127
AI Number:	7176
Self Certification Date:	12/28/2009
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28126
AI Number:	7176
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28125
AI Number:	7176
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28124
AI Number:	7176
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28123
AI Number:	7176
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28122
AI Number:	7176
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28121
AI Number:	7176
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28120
AI Number:	7176
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28119
AI Number:	7176
Self Certification Date:	11/26/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46178
Cert ID:	28118
AI Number:	7176
Self Certification Date:	01/11/2001
Signature Name/Title:	WILLO A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002

7-ELEVEN 12705 (Continued) **U003103747**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/10/2009
Tank Registration Date:	01/04/2010
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	212997
Facility ID:	46178
Ai Number:	7176
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	12/10/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7-ELEVEN 12705 (Continued) **U003103747**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	12/28/2009

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	26107
UST ID:	212997
AI Number:	7176
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/15/2009

7-ELEVEN 12705 (Continued) **U003103747**

Install Date:	04/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18619
Facility ID:	46178
Ai Number:	7176
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/02/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

7-ELEVEN 12705 (Continued) **U003103747**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	26103
UST ID:	18619
AI Number:	7176
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18620

7-ELEVEN 12705 (Continued) **U003103747**

Facility ID:	46178
Ai Number:	7176
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/02/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000

7-ELEVEN 12705 (Continued) **U003103747**

UST Comprt ID:	26104
UST ID:	18620
AI Number:	7176
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18621
Facility ID:	46178
Ai Number:	7176
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/02/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	26105
UST ID:	18621
AI Number:	7176
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

7-ELEVEN 12705 (Continued) **U003103747**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	12/10/2009
Tank Registration Date:	01/04/2010
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	212996
Facility ID:	46178
Ai Number:	7176
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	12/10/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

7-ELEVEN 12705 (Continued) **U003103747**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	12/28/2009

Compartment Records:

Tank ID:	4
Tank Capacity:	12000
UST Comprt ID:	26106
UST ID:	212996
AI Number:	7176
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

7-ELEVEN 12705 (Continued) **U003103747**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/15/2009

Construction Notification:

NOC ID:	2524
Facility ID:	46178
AI Number:	7176
Application Received Date:	01/12/2007
Scheduled Construction Date:	01/15/2007
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M70112007
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2523
Facility ID:	46178

7-ELEVEN 12705 (Continued) **U003103747**

AI Number:	7176
Application Received Date:	10/14/2009
Scheduled Construction Date:	11/13/2009
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91014005
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2522
Facility ID:	46178
AI Number:	7176
Application Received Date:	10/14/2009
Scheduled Construction Date:	11/13/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91014005
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	26899
UST ID:	212996
NOC ID:	Not reported
AI Number:	7176
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2790
UST ID:	Not reported
NOC ID:	2523
AI Number:	7176
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2791
UST ID:	Not reported
NOC ID:	2524
AI Number:	7176
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP011100
Company Name:	Not reported
Representative Name:	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	2789
UST ID:	Not reported
NOC ID:	2522
AI Number:	7176
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	26900
UST ID:	212997
NOC ID:	Not reported
AI Number:	7176
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42064
UST ID:	212997
NOC ID:	Not reported
AI Number:	7176
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42063
UST ID:	212996
NOC ID:	Not reported
AI Number:	7176
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC

7-ELEVEN 12705 (Continued) **U003103747**

Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46178
Additional ID:	868202132002117
Princ ID:	959578622001257
AI Number:	7176
Facility Name:	7-ELEVEN 12705
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	1142
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.8
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	7-ELEVEN
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/08/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1

7-ELEVEN 12705 (Continued) **U003103747**

Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	08/11/2014
Date Routed by Supervisor:	08/19/2014
Date Routed to PSQA:	08/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

7-ELEVEN 12705 (Continued) **U003103747**

ENFORCEMENT:

Name:	7 ELEVEN STORE 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701-1625
Unique TCEQ Ref Number Of Customer:	CN600240329
Unique TCEQ Ref Number Of Reg. Entity:	RN102021409
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	7-ELEVEN INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001293704
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	843,487,742,016,006.00
Role Code:	Not reported
Date Notice Of Violation Issued:	01/11/2016
Description 1:	Failure to comply with annual Stage I vapor recovery testing requirements.
Description 2:	On November 24, 2015, Stage I vapor recovery equipment was tested and the results of CARB Vapor Recovery Test Procedure TP 201.3 were submitted to the investigator. The violation was resolved.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	115.225
Status Of The NOV:	DAPPROVED
Investigation:	1293704
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	7 ELEVEN STORE 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701-1625
Unique TCEQ Ref Number Of Customer:	CN600240329
Unique TCEQ Ref Number Of Reg. Entity:	RN102021409
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	7-ELEVEN INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001293704
Status Code:	RESOLVED

7-ELEVEN 12705 (Continued) **U003103747**

Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	843,487,742,016,006.00
Role Code:	Not reported
Date Notice Of Violation Issued:	01/11/2016
Description 1:	Failure to test the line leak detectors (LLDs) at least once per year for performance and operational reliability.
Description 2:	On December 17, 2015, test results were received indicating that Tanknology performed the annual LLD tests on November 2, 2015.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.50(b)(2)(A)(i)(III)
Status Of The NOV:	DAPPROVED
Investigation:	1293704
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

TX Financial Assurance 2:

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	278706
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701

7-ELEVEN 12705 (Continued) **U003103747**

Region:	2
Facility ID:	46178
Finass ID:	261555
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	242262
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	223525
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN 12705 (Continued) **U003103747**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	224125
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	207934
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019

7-ELEVEN 12705 (Continued) **U003103747**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	189242
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	173787
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	172711

7-ELEVEN 12705 (Continued) **U003103747**

AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	154036
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	138251
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014

7-ELEVEN 12705 (Continued) **U003103747**

Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	119938
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 972 8287805
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	120384
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 12705 (Continued) **U003103747**

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	2249
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28816
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28817
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 12705 (Continued) **U003103747**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28819
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28818
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000

7-ELEVEN 12705 (Continued) **U003103747**

Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28820
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	46178
Finass ID:	28821
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX 78701

7-ELEVEN 12705 (Continued) **U003103747**

Region:	2
Facility ID:	46178
Finass ID:	28822
AI:	7176
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

MV2174 **7 ELEVEN 12705** **TX RDR** **S127538749**
WNW **408 W 15TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
288 ft. **Site 2 of 2 in cluster MV**

Actual:
535 ft.

Focus Map:
11

RDR:

RDR ID:	18717
Facility ID:	7176
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 12705
Address:	408 W 15TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/16/2010
Due Date:	4/17/2010
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	4/23/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	118292
Pre-Existing LPST Number:	Not reported
Comments:	LAD SENT 4/28/10
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LF2175 **BURTONS LAUNDRY & CLEANERS** **EDR Hist Cleaner** **1013780064**
East **615 W 19TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.055 mi.
289 ft. **Site 5 of 7 in cluster LF**

Actual:
558 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	BURTONS LAUNDRY	LAUNDRIES
1970	BURTONS LAUNDRY & CLEANERS	LAUNDRIES
1971	BROWNS FABRIC CARE CENTER	Garment Pressing And Cleaners' Agents
1972	BROWNS FABRIC CARE CENTER	Garment Pressing And Cleaners' Agents
1972	BROWN & ELLIOTT INC	Drycleaning Plants, Except Rugs
1973	BROWNS FABRIC CARE CENTER	Laundry And Garment Services, NEC
1973	BROWN & ELLIOTT INC	Drycleaning Plants, Except Rugs
1974	BROWN & ELLIOTT INC	Drycleaning Plants, Except Rugs
1974	BROWNS JACK FABRIC CARE CENTER	Power Laundries, Family And Commercial
1975	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1976	BROWNS FABRIC CARE CENTER	Power Laundries, Family And Commercial
1976	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1977	BROWNS FABRIC CARE CENTER	Power Laundries, Family And Commercial
1977	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1978	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1979	BROWN & ELLIOT INC	Drycleaning Plants, Except Rugs
1986	BROWN JACK CLEANERS	Drycleaning Plants, Except Rugs
1987	BROWN JACK CLEANERS	Drycleaning Plants, Except Rugs
1988	BROWN JACK CLEANERS	Drycleaning Plants, Except Rugs

JH2176 **TRAVIS MOTOR EX** **EDR Hist Auto** **1013770856**
NE **611 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
289 ft. **Site 7 of 13 in cluster JH**

Actual:
482 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	TRAVIS MOTOR EX	AUTOMOBILE REPAIRING

JH2177 **B & L CLUTCH & BRAKE SERVICE AUTO REPR** **EDR Hist Auto** **1013765364**
NE **611 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.055 mi.
289 ft. **Site 8 of 13 in cluster JH**

Actual:
482 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1980	B & L CLUTCH & BRAKE SERVICE AU	AUTOMOBILE REPAIRING

JH2178 NE < 1/8 0.055 mi. 289 ft. | **B & L CLUTCH & BRAKE SERVICE AUTO REPR** | **EDR Hist Auto** | **1013759257** **N/A**
611 7TH ST E
TRAVIS (County), TX 78701
Site 9 of 13 in cluster JH

Actual: 482 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	B & L CLUTCH & BRAKE SERVICE AU	AUTOMOBILE REPAIRING

MW2179 ESE < 1/8 0.055 mi. 290 ft. | **CINBAR ENGINEERING CO.** | **TX HIST UST** | **S111678604** **N/A**
711 W ST. JOHNS AVE
AUSTIN, TX
Site 1 of 2 in cluster MW

Actual: 729 ft. HIST UST AUSTIN:

Focus Map: 6

Name:	CINBAR ENGINEERING CO.
Address:	711 W ST. JOHNS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0825
HID UST:	825
Inspection:	02/26/2009
Due:	02/26/2012

KH2180 SSW < 1/8 0.055 mi. 290 ft. | **LAWSHA LEE C DCLO CLNR** | **EDR Hist Cleaner** | **1013787436** **N/A**
215 CONGRESS AVE E
AUSTIN, TX
Site 12 of 19 in cluster KH

Actual: 475 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	LAWSHA LEE C DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

LO2181 WNW < 1/8 0.055 mi. 290 ft. | **AUSTIN RADIATOR WORKS** | **EDR Hist Auto** | **1013753130** **N/A**
810 CAPITOL CT
AUSTIN, TX 78756
Site 4 of 5 in cluster LO

Actual: 667 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1978	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1979	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1980	AUSTIN RADIATOR WORKS	AUTOMOBILE RADIATOR REPAIRERS
1984	AUSTIN RADIATOR WORKS	AUTOMOBILE RADIATOR REPAIRERS
1985	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1986	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1987	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1988	AUSTIN WELDING & RADIATOR WKS	Automotive Repair Shops, NEC
1989	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1990	AUSTIN RADIATOR WORKS INC	AUTOMOBILE RADIATOR REPAIRERS

AUSTIN RADIATOR WORKS (Continued) **1013753130**

1990	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1991	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1992	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1993	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1994	AUSTIN WELDING & RAD WORKS	Powertrain Components Repair Services
1995	AUSTIN CITY RADIATOR	Powertrain Components Repair Services
1996	AUSTIN CITY RADIATOR SERVICE	Powertrain Components Repair Services
1997	AUSTIN CITY RADIATOR SERVICE	Powertrain Components Repair Services

---

MN2182 **GARDNERS SERVICE STA** **EDR Hist Auto** **1013753657**
NNE **99 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
291 ft. **Site 5 of 11 in cluster MN**

Actual:
472 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	ORIENTAL OIL CO	AUTOMOBILE FILLING STATIONS
1929	CAMPBELL SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1935	GREEN J H GARAGE	AUTOMOBILE REPAIRERS
1935	MILLERS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1940	MILLERS FRED SERVICE STA FILLIN	GASOLINE AND OIL SERVICE STATIONS
1947	NICHOLS ERNEST G AUTO REPR	AUTOMOBILE REPAIRING
1947	GARDNERS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	DANFORD CLYDE A AUTO REPR	AUTOMOBILE REPAIRING

MT2183 **EKSTROM GUS AUTO REPR** **EDR Hist Auto** **1013756795**
ESE **301 CROCKETT ST** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
291 ft. **Site 2 of 2 in cluster MT**

Actual:
566 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1929	EKSTROM GUS AUTO REPR	AUTOMOBILE REPAIRERS

JA2184 **AUTOMOTIVE SPECIA** **EDR Hist Auto** **1013771310**
WNW **837 12TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
292 ft. **Site 15 of 15 in cluster JA**

Actual:
497 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	AUTOMOTIVE SPECIA	AUTOMOBILE REPAIRING

JH2185 **TRAVIS MTR EX** **EDR Hist Auto** **1013776932**
NE **613 7TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
292 ft. **Site 10 of 13 in cluster JH**

Actual:
482 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	TRAVIS MTR EX	AUTOMOBILE REPAIRING
1962	TRAVIS MTR EXCHANGC	AUTOMOBILE REPAIRING

JH2186 **TRAVIS MOTOR EXCHANGE AUTO** **EDR Hist Auto** **1013767833**
NE **613 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
292 ft. **Site 11 of 13 in cluster JH**

Actual:
482 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	TRAVIS MOTOR EXCHANGE AUTO	AUTOMOBILE REPAIRING

MX2187 **WELLS H P GARAGE** **EDR Hist Auto** **1013767705**
ESE **206 18TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
292 ft. **Site 1 of 2 in cluster MX**

Actual:
516 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	WELLS H P GARAGE	AUTOMOBILE REPAIRING
1958	WELLS H P GARAGE	AUTOMOBILE REPAIRING

LB2188 **ACUNAS** **TX UST** **U001293011**
WNW **511 E 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.055 mi.
293 ft. **Site 6 of 9 in cluster LB**

Actual:
459 ft.

UST:

Focus Map:
11

Name:	ACUNAS
Address:	511 E 1ST ST
City,State,Zip:	AUSTIN, TX 787014650
AI Number:	63471
Facility Type:	UNKNOWN
Facility Begin Date:	01/20/1993
Facility Status:	INACTIVE
Additional ID:	227532802003204
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS

ACUNAS (Continued) **U001293011**

Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	PERRY LORENZ,
Contact Organization Name:	ACUNAS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124788774
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/13/1992
Signature Name/Title On Earliest Reg Form:	PERRY LORENZ,PRES
Application Received Date On Earliest Reg Form:	08/17/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602285710
Owner Last Name:	LORENZCO INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	237532802003204
Additional ID:	227532802003204
AI Number:	63471
Owner Effective Begin Date:	01/20/1993
State Tax ID:	30113857772
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/17/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146495
Facility ID:	94402
Ai Number:	63471
Tank Id:	1

ACUNAS (Continued) **U001293011**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	164637
UST ID:	146495
AI Number:	63471

ACUNAS (Continued) **U001293011**

Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/17/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146496
Facility ID:	94402
Ai Number:	63471
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

ACUNAS (Continued) **U001293011**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	164638
UST ID:	146496
AI Number:	63471
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

ACUNAS (Continued) **U001293011**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/17/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146497
Facility ID:	94402
Ai Number:	63471
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

ACUNAS (Continued) **U001293011**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	164639
UST ID:	146497
AI Number:	63471
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

ACUNAS (Continued) **U001293011**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/17/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	146498
Facility ID:	94402
Ai Number:	63471
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

ACUNAS (Continued) **U001293011**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	0
UST Comprt ID:	164640
UST ID:	146498
AI Number:	63471
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

ACUNAS (Continued) **U001293011**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	LORENZCO INC
Contact Mailing Address (Delivery):	1311 E 6TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78702 3367
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94402
Additional ID:	227532802003204
Princ ID:	237532802003204
AI Number:	63471
Facility Name:	ACUNAS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PERY LORENZ/

LB2189 **TAYLORS SERIVCE** **EDR Hist Auto** **1013757678**
WNW **511 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.055 mi.
293 ft. **Site 7 of 9 in cluster LB**

Actual:
459 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	LUCAS & TAYLOR SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1947	TAYLORS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	TAYLORS SERIVCE	GASOLINE STATIONS
1958	TAYLORS OIL CO	GASOLINE STATIONS
1962	TAYLOR OIL CO GAS STA	GASOLINE STATIONS
1970	KEY PETROLEUM CO STA NO	GASOLINE STATIONS
1975	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1980	TAKE OUT SHOPPE	GASOLINE STATIONS

LM2190 NEELLEY VENDING — **TX LPST** — **S116702014**
WNW 813 W NORTH LOOP BLVD — **TX HIST UST** — **N/A**
< 1/8 AUSTIN, TX 78756
0.055 mi.
293 ft. Site 3 of 3 in cluster LM

Actual: 683 ft.
Focus Map: 8

LPST:

Name:	NEELLEY VENDING
Address:	813 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	Not reported
LPST Id:	092244
Facility Location:	813 NORTH LOOP
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/01/1987
Entered Date:	10/01/1987
Reported Date:	10/01/1987
Closure Date:	07/06/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	GORDON NEELLEY
Responsible Party Address:	7969 MESA TRAILS CIR
Responsible Party City,St,Zip:	AUSTIN, TX 78731 1447
Responsible Party Telephone:	512/327-2302
Reported Date:	10/01/1987
Case Start Date:	07/06/1993
Reference Number:	RN106974264
Project Manager:	HWELCH

HIST UST AUSTIN:

Name:	NEELLEY VENDING CO
Address:	813 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0070
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MK2191 BLOCK 4 — **TX VCP** — **S104275467**
NNE 100 COLORADO ST — **TX GCC** — **N/A**
< 1/8 AUSTIN, TX 78701 — **TX IOP**
0.055 mi. — **TX CENTRAL REGISTRY**
293 ft. Site 3 of 6 in cluster MK

Actual: 471 ft.
Focus Map: 11

VCP TCEQ:

Name:	BLOCK 4, 100 COLORADO STREET
Address:	100 COLORADO ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	1110
VCP Record Date:	12/20/1999

BLOCK 4 (Continued) **S104275467**

Facility Type:	PROPERTY COMMERCIAL
PCA Number:	33233
Project Manager:	RSCHARLA
Phase:	COMPLETED
Acres at Site:	1.8
REM Program:	VCP
RN Number:	RN100247758
Former Facility Type:	Not reported
Site Address Description:	100 COLORADO STREET
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	12/17/1999
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/14/2000
Standards:	3
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	12/17/1999
GW Target COC Class:	PAHS; TPH; PETROLEUM (BTEX)
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	2000-01-20 00:00:00
Soil Target COC Class:	TPH; PETROLEUM (BTEX); PAHS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1110
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	332330
Off Site?:	Not reported
Media:	PAPER
IOP Number:	78
File Location:	CR; 200-43N
Latitude:	30.27
Longitude:	-97.08

Contact:

REM Program:	VCP
Program ID:	1110
RN Number:	RN100247758
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
Role Code:	BILLCONT
Contact Name:	ONEAL, LARRY
Contact Title:	Not reported
Organization Name:	CITY OF AUSTIN

BLOCK 4 (Continued) **S104275467**

Mailing Address: PO BOX 1088
Mailing City: AUSTIN
Mailing State: TX
Mailing Zip: 78767
Contact Telephone: (512) 499-7078
Contact Telephone Ext: 0

GCC:
Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO ST
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: INACTIVE GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2018
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2012
Agency: TCEQ
Section: VC
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported

BLOCK 4 (Continued) **S104275467**

Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2015
Agency: TCEQ
Section: VC/VC
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2011
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 1110

BLOCK 4 (Continued) **S104275467**

Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2008
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2013
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: RMD

BLOCK 4 (Continued) **S104275467**

New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2007
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO ST
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2016
Agency: TCEQ
Section: Not reported
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET

BLOCK 4 (Continued) **S104275467**

Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

Name: BLOCK 4, 100 COLORADO STREET
Address: 100 COLORADO STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 1110
Contamination Description: PAH, BTEX, TPH
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2014
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1999
Location: Not reported
Data Quality 2: Not reported

IOP:
Name: BLOCK 4
Address: 100 COLORADO ST
City,State,Zip: AUSTIN, TX 78701
Program ID: 78
Date IOP Received: Not reported
Region: REGION 11 - AUSTIN
Phase: TRANSFERRED TO VCP
Interest In Site: Not reported
PCA Number: 32078
Property Use: PROPERTY COMMERCIAL
Project Manager: RSCHARLA
Project Number: 320780
Latitude: 30.27
Longitude: -97.08
Acres: 1.8
Media Affected: Not reported
LPST Number: Not reported

BLOCK 4 (Continued) **S104275467**

VCP ID:	Not reported
Cert Issued:	Not reported
Solid Waste Regn Number:	Not reported
EPA TX ID/Cerclis regn Number:	Not reported
Contaminant Categories:	Not reported
Applicant Information:	Not reported
Applicant First Name:	Not reported
Applicant Last Name:	Not reported
Applicant Title:	Not reported
Applicant Address:	Not reported
Applicant City,State,Zip:	Not reported
Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN100247758
Consultant/Attorney Phone:	Not reported
Site Address Description:	100 COLORADO STREET
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	12/01/1998
Application Received Date:	12/03/1998
Application Acceptance Date:	Not reported
IOP Application Accepted:	Y
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER
File Location:	200-43/D

Customer:

REM Program:	IOP
Program ID:	78
RN Number:	RN100247758
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
Role CD:	BILLCONT
Contact Name:	ONEAL, LARRY
Contact Title:	Not reported
Organization Name:	CITY OF AUSTIN
Mailing Address:	PO BOX 1088
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Phone:	(512) 499-7078
Contact Ext:	0

REM Program:	IOP
Program ID:	78
RN Number:	RN100247758
CN Number:	CN600135198

BLOCK 4 (Continued) **S104275467**

CN Name:	CITY OF AUSTIN
Role CD:	APPLCONT
Contact Name:	ONEAL, LARRY
Contact Title:	Not reported
Organization Name:	CITY OF AUSTIN
Mailing Address:	PO BOX 1088
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Phone:	(512) 499-7078
Contact Ext:	0

CENTRAL REGISTRY:

Regulated Entity Number:	RN100247758
Name:	BLOCK 4
Address:	100 COLORADO ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4147
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 COLORADO STREET

Regulated Entity Number:	RN100247758
Name:	BLOCK 4
Address:	100 COLORADO ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4147
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 COLORADO STREET

Regulated Entity Number:	RN100247758
Name:	BLOCK 4
Address:	100 COLORADO ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4147
Status:	ACTIVE
Status Date:	##########

BLOCK 4 (Continued) **S104275467**

Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 COLORADO STREET

Regulated Entity Number:	RN100247758
Name:	BLOCK 4
Address:	100 COLORADO ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4147
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 COLORADO STREET

MK2192 **AUSTIN GAS LIGHT CO** **EDR MGP** **1008408362**
NNE **100 COLORADO ST (CORNER OF 2ND AND COLORADO)** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.055 mi.
293 ft. **Site 4 of 6 in cluster MK**

Actual:
471 ft.

Focus Map:
11

Manufactured Gas Plants:

Alternate Name:AUSTIN GAS CO; AUSTIN GAS WORKS. No additional information available

---

KX2193 **SOUTH LAKESHORE BOULEVARD LAUNDROMAT** **EDR Hist Cleaner** **1013786275**
ENE **1717 LAKESHORE BLVD S** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.055 mi.
293 ft. **Site 5 of 5 in cluster KX**

Actual:
458 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1984	SOUTH LAKESHORE BOULEVARD LAUND	LAUNDRIES-SELF SERVE
1990	B GEM LAUNDRY CARE	LAUNDRIES-SELF SERVE

MN2194 NNE < 1/8 0.056 mi. 294 ft. | **LINCOLN PROPERTIES FIRST AND CONGRESS AUSTIN, TX 78701** | **SEMS-ARCHIVE** | **1003875184 TXD981155971**

Site 6 of 11 in cluster MN

Actual: 472 ft.

Focus Map: 11

SEMS Archive:

Site ID:	0603312
EPA ID:	TXD981155971
Name:	LINCOLN PROPERTIES
Address:	FIRST AND CONGRESS
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Cong District:	02
FIPS Code:	48453
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	06
Site ID:	0603312
EPA ID:	TXD981155971
Site Name:	LINCOLN PROPERTIES
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1994-08-23 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	06
Site ID:	0603312
EPA ID:	TXD981155971
Site Name:	LINCOLN PROPERTIES
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1986-08-01 04:00:00
Finish Date:	1986-08-01 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0603312
EPA ID:	TXD981155971
Site Name:	LINCOLN PROPERTIES
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

LINCOLN PROPERTIES (Continued) **1003875184**

Start Date:	1986-04-17 05:00:00
Finish Date:	1986-04-17 05:00:00
Qual:	Not reported
Current Action Lead:	St Perf
Region:	06
Site ID:	0603312
EPA ID:	TXD981155971
Site Name:	LINCOLN PROPERTIES
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1986-11-01 05:00:00
Finish Date:	1986-11-01 05:00:00
Qual:	L
Current Action Lead:	St Perf

JE2195 **GRAY CLNRS** **EDR Hist Cleaner** **1013784827**
ESE **209 17TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
294 ft. **Site 6 of 6 in cluster JE**

Actual:
522 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1953	GRAY CLNRS	CLEANERS AND DYERS

MY2196 **AUSTIN CONV. CTR. EXPANSI** **TX RDR** **S127539077**
WNW **3RD & RED RIVER** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
294 ft. **Site 1 of 3 in cluster MY**

Actual:
464 ft.

RDR:

Focus Map:
11

RDR ID:	9861
Facility ID:	72756
RN:	Not reported
CN:	Not reported
Name:	AUSTIN CONV. CTR. EXPANSI
Address:	3RD & RED RIVER
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/1999
Due Date:	2/8/2000
Tank Owner:	CITY OF AUSTIN
Contact Person:	TOM WOOD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/13/2000
Project Manager:	Michelle Sefcik
Team:	#N/A
New LPST Number:	Not reported

AUSTIN CONV. CTR. EXPANSI (Continued) **S127539077**

Pre-Existing LPST Number:	Not reported
Comments:	APPROVED
Review Coordinator:	MDS
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/13/2000
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

MZ2197 **PARKING GARAGE E** **TX Ind. Haz Waste** **S103609094**
ESE **1604 LAVACA ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.056 mi.
297 ft. **Site 1 of 6 in cluster MZ**

Actual:
553 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	PARKING GARAGE E
Address:	1604 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	75085
Registration Initial Notification Date:	01/03/1990
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19900103
Land Type:	Not reported
Description of Facility Site Location:	1604 Lavaca, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	GENERAL SERVICES COMMISSION
Contact Name:	JAMES D REID
Contact Telephone Number:	512-4752436
Mailing Address:	PO BOX 13047
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787113047
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29440
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031010
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported

PARKING GARAGE E (Continued) **S103609094**

Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Operator Address:	PO BOX 13047
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78711
Operator Country:	UNITED STA
Operator Telephone:	1-512-4752436
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17460000742
Operator Bankruptcy Code:	Not reported

Operator Name:	GENERAL SERVICES COMMISSION
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Owner Mailing Address:	PO BOX 13047
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78711
Owner Country:	UNITED STA
Owner Telephone:	1-512-4752436
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17460000742
Owner Bankruptcy Code:	Not reported

Owner Name:	GENERAL SERVICES COMMISSION
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported

PARKING GARAGE E (Continued) **S103609094**

Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4752436
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4752436
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JAMES REID
Contact Title:	WASTE MANGER
Contact Role:	PRICONT
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4752436
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100624071
Name:	PARKING GARAGE E
Address:	1604 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1314
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600240618
Customer Name:	GENERAL SERVICES COMMISSION
Customer Legal Name:	General Services Commission
Customer Ownership Type:	CITY GOVERNMENT

PARKING GARAGE E (Continued) **S103609094**

Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1604 Lavaca, Austin, TX

Regulated Entity Number:	RN100624071
Name:	PARKING GARAGE E
Address:	1604 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1314
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602482838
Customer Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Customer Legal Name:	Texas Building and Procurement Commission
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1604 Lavaca, Austin, TX

MZ2198 **THRIFTY CLEANERS** **EDR Hist Cleaner** **1013782335**
ESE **1604 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
297 ft. **Site 2 of 6 in cluster MZ**

Actual:
553 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	THRIFTY CLEANERS	CLOTHES PRESSERS AND CLEANERS

MR2199 **LAVACA ST GARAGE** **EDR Hist Auto** **1013775913**
ESE **1404 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
297 ft. **Site 4 of 12 in cluster MR**

Actual:
541 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	LAVACA ST GARAGE	AUTOMOBILE GARAGES

MR2200 ESE < 1/8 0.056 mi. 297 ft. — **DAVIS H R DCLO CLNR**, **1404 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013781517** / **N/A**

Site 5 of 12 in cluster MR

Actual: 541 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	DAVIS H R DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

MR2201 ESE < 1/8 0.056 mi. 297 ft. — **KALLGREN & HAMILTON**, **1402 LAVACA**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013780764** / **N/A**

Site 6 of 12 in cluster MR

Actual: 541 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	KALLGREN & HAMILTON	CLEANERS AND DYERS

MR2202 ESE < 1/8 0.056 mi. 297 ft. — **MAGNOLIA PET CO STI**, **1312 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013766908** / **N/A**

Site 7 of 12 in cluster MR

Actual: 540 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	MAGNOLIA PET CO STATION NO	AUTOMOBILE FILLING STATIONS
1935	MAGNOLIA PET CO STI	GASOLINE AND OIL SERVICE STATIONS

LT2203 ESE < 1/8 0.056 mi. 297 ft. — **BAKER LEONARD CLNR**, **1516 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013785268** / **N/A**

Site 2 of 9 in cluster LT

Actual: 547 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1922	BAKER LEONARD CLNR	CLOTHES CLEANERS AND PRESSERS
1929	AMERICAN CLNRS & DYERS	CLOTHES CLEANERS AND PRESSERS
1980	BROWN JACK LAUNDRY	LAUNDRIES AND DRY CLEANERS

LK2204 ESE < 1/8 0.056 mi. 297 ft. — **LINDSAY AUTO ELEC, 506 LAVACA ST, AUSTIN, TX** — **EDR Hist Auto** — **1013757597 / N/A**

Site 3 of 10 in cluster LK

Actual: 494 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1958	LINDSAY AUTO ELEC	AUTOMOBILE REPAIRING

2205 ESE < 1/8 0.056 mi. 298 ft. — **BEN AUTO REPAIR, 5409 WASSON RD, AUSTIN, TX 78745** — **EDR Hist Auto** — **1013774540 / N/A**

Actual: 617 ft. EDR Hist Auto

Focus Map: 17

Year:	Name:	Type:
1980	BEN AUTO REPAIR	AUTOMOBILE REPAIRING
1984	BENS AUTO REPAIR	AUTOMOBILE REPAIRING
1993	BJ AUTO	General Automotive Repair Shops
1994	BJ AUTO	General Automotive Repair Shops
1995	BJ AUTO	General Automotive Repair Shops
2002	BJ AUTO	General Automotive Repair Shops
2003	BJ AUTO	General Automotive Repair Shops
2004	BJ AUTO	General Automotive Repair Shops
2005	BJ AUTO	General Automotive Repair Shops
2006	BJ AUTO	General Automotive Repair Shops
2006	BEST AUTOMOTIVE	General Automotive Repair Shops
2007	BJ AUTO	General Automotive Repair Shops
2007	BEST AUTOMOTIVE	General Automotive Repair Shops
2008	BEST AUTOMOTIVE	General Automotive Repair Shops
2008	BJ AUTO	General Automotive Repair Shops
2009	BEST AUTOMOTIVE	General Automotive Repair Shops
2010	BEST AUTOMOTIVE	General Automotive Repair Shops
2011	BEST AUTOMOTIVE	General Automotive Repair Shops
2012	BEST AUTOMOTIVE	General Automotive Repair Shops
2013	BEST AUTOMOTIVE	General Automotive Repair Shops
2014	BEST AUTOMOTIVE	General Automotive Repair Shops

LT2206 ESE < 1/8 0.056 mi. 298 ft. — **FRIENDLY PRESSING SHOP, 1504 LAVACA ST, AUSTIN, TX** — **EDR Hist Cleaner** — **1013780325 / N/A**

Site 3 of 9 in cluster LT

Actual: 547 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	MODEL STEAM LAUNDRY	LAUNDRIES
1922	DAVIS H R CLNR	CLOTHES CLEANERS AND PRESSERS
1929	FRIENDLY PRESSING SHOP	CLOTHES CLEANERS AND PRESSERS
1935	FRIENDLY CLEANING	CLOTHES PRESSERS AND CLEANERS
1940	FRIENDLY CLEANING	CLOTHES PRESSERS AND CLEANERS
1947	FRIENDLY CLEANERS	CLOTHES PRESSERS AND CLEANERS
1953	FRIENDLY CLEANERS	CLEANERS AND DYERS

FRIENDLY PRESSING SHOP (Continued) **1013780325**

1958	FRIENDLY C LNS	CLEANERS AND DYERS

LT2207 **11 AUSTIN LAUNDRY** **EDR Hist Cleaner** **1013782569**
ESE **1514 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
298 ft. **Site 4 of 9 in cluster LT**

Actual:
547 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	11 AUSTIN LAUNDRY	CLOTHES CLEANERS AND PRESSERS
1922	11 AUSTIN LAUNDRY	LAUNDRIES
1929	AUSTIN LAUNDRY & DRY	LAUNDRIES
1929	AUSTIN LAUNDRY & DRY	CLEANERS PRESSERS AND DYERS
1929	AUSTIN LAUNDRY & DRY	CLOTHES CLEANERS AND PRESSERS
1929	AUSTIN LAUNDRY & DRY	DYERS AND CLEANERS
1935	AUSTIN LNDRY & DRY	LAUNDRIES
1935	1514 16 AMERICAN CLNRS DYERS	CLOTHES PRESSERS AND CLEANERS
1940	AUSTIN LNDRY & DRY	LAUNDRIES
1940	AUSTIN LNDRY & DRY	CLOTHES PRESSERS AND CLEANERS
1940	CLEANING CO	DRY CLEANERS
1947	AUSTIN LNDRY & DRY CLNG CO	LAUNDRIES
1947	AUSTIN LNDRY & DRY CLNG CO	CLOTHES PRESSERS AND CLEANERS
1947	AUSTIN LNDRY & DRY CLNG CO	DRY CLEANERS
1953	AUSTIN LNDRY & DRY	LAUNDRIES
1958	AUSTIN LNDRY	LAUNDRIES
1958	AUSTIN LNDRY	CLEANERS AND DYERS
1962	AUSTIN LNDRY & DRY	LAUNDRIES
1965	AUSTIN LAUNDRY & DRY	CLEANERS AND DYERS
1970	AUSTIN LAUNDRY & DRY CLEANING C	CLEANERS AND DYERS
1975	BROWN JACK LAUNDRY	LAUNDRIES AND DRY CLEANERS

LT2208 **1504 AUSTIN LAUNDRY** **EDR Hist Cleaner** **1013778475**
ESE **1510 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.056 mi.
298 ft. **Site 5 of 9 in cluster LT**

Actual:
547 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	1504 AUSTIN LAUNDRY	LAUNDRIES

LT2209 **QUINN & SMITH CLNRS** **EDR Hist Cleaner** **1013784552**
ESE **1506 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
299 ft. **Site 6 of 9 in cluster LT**

Actual:
547 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1916	QUINN & SMITH CLNRS	CLOTHES CLEANERS AND PRESSERS

LK2210 ESE < 1/8 0.057 mi. 299 ft. — **SHIRLEYS HATTER**, **310 6TH W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013781714** / **N/A**

Site 4 of 10 in cluster LK

Actual: 498 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1953	RAPP CLEANERS	CLEANERS AND DYERS
1958	SHIRLEYS HATTER	HAT CLEANERS AND BLOCKERS
1958	RAPP CINS	CLEANERS AND DYERS
1962	SHIRLEYS HATTER CLNS	HAT CLEANERS AND BLOCKERS
1962	RAPP CLNS	CLEANERS AND DYERS

LK2211 ESE < 1/8 0.057 mi. 299 ft. — **SHIRLEY CLEANERS & HATTERS**, **310 6TH ST W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013778465** / **N/A**

Site 5 of 10 in cluster LK

Actual: 498 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1965	SHIRLEY CLEANERS & HATTERS	CLEANERS AND DYERS

2212 SE < 1/8 0.057 mi. 299 ft. — **WESTERN AUTO**, **137 W OLTORF ST**, **AUSTIN, TX 78704** — **TX LPST** / **TX UST** — **U003566373** / **N/A**

Actual: 595 ft.

Focus Map: 14

LPST:

Name:	WESTERN AUTO STORE
Address:	137 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78700
Facility ID:	0056892
LPST Id:	097478
Facility Location:	137 W OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/10/1990
Entered Date:	12/11/1990
Reported Date:	12/10/1990
Closure Date:	03/13/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	ALAN TERHUNE
Responsible Party Address:	2107 GRAND AVE
Responsible Party City,St,Zip:	KANSAS CITY, MO 64108
Responsible Party Telephone:	816/346-4281
Reported Date:	12/10/1990

WESTERN AUTO (Continued) **U003566373**

Case Start Date:	03/13/1991
Reference Number:	RN102269081
Project Manager:	HWELCH
Name:	WESTERN AUTO
Address:	137 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0056892
LPST Id:	111290
Facility Location:	137 W OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/27/1996
Entered Date:	07/09/1996
Reported Date:	06/28/1996
Closure Date:	10/09/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	ALAN TERHUNE
Responsible Party Address:	2107 GRAND AVE
Responsible Party City,St,Zip:	KANSAS CITY, MO 64108
Responsible Party Telephone:	816/346-4281
Reported Date:	06/28/1996
Case Start Date:	10/09/1996
Reference Number:	RN102269081
Project Manager:	XYZ

UST:

Name:	WESTERN AUTO
Address:	137 W OLTORF ST
City,State,Zip:	AUSTIN, TX 787045209
AI Number:	56892
Facility Type:	RETAIL
Facility Begin Date:	11/27/1990
Facility Status:	INACTIVE
Additional ID:	947144012002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	ALAN TERHUNE,
Contact Organization Name:	WESTERN AUTO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

WESTERN AUTO (Continued) **U003566373**

Contact Telephone:	8163464281
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/19/1990
Signature Name/Title On Earliest Reg Form:	ALAN TERHUNE,STORE DEV.
Application Received Date On Earliest Reg Form:	11/26/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600263578
Owner Last Name:	WESTERN AUTO SUPPLY COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	788295422001297
Additional ID:	947144012002139
AI Number:	56892
Owner Effective Begin Date:	11/27/1990
State Tax ID:	15419116866
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	04/01/1961
Tank Registration Date:	11/26/1990
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	137065
Facility ID:	72449
Ai Number:	56892
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/21/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

WESTERN AUTO (Continued) **U003566373**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/01/1987

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	103014
UST ID:	137065
AI Number:	56892
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

WESTERN AUTO (Continued) **U003566373**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	09/19/1996
Number of Compartments:	1
Tank Capacity:	250
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	181373
Facility ID:	72449
Ai Number:	56892
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	07/12/1996
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

WESTERN AUTO (Continued) **U003566373**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	103015
UST ID:	181373
AI Number:	56892
Compartment ID:	A
Substance Stored1:	OIL WATER SEPARATOR
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

WESTERN AUTO (Continued) **U003566373**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WESTERN AUTO SUPPLY COMPANY
Contact Mailing Address (Delivery):	9680 MARION RDG
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	KANSAS CITY, MO 64137 1284
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72449
Additional ID:	947144012002139
Princ ID:	788295422001297
AI Number:	56892
Facility Name:	WESTERN AUTO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ALAN TERHUNE/

NA2213 **PEARSON WESLEY** **EDR Hist Auto** **1013773367**
SSW **301 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.057 mi.
299 ft. **Site 1 of 12 in cluster NA**

Actual:
451 ft. EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	PEARSON WESLEY	GASOLINE STATIONS

NA2214 SSW < 1/8 0.057 mi. 299 ft. — **GULF REFINING CO.**, **301 S CONGRESS AVE**, **AUSTIN, TX** — **TX HIST UST** — **S111678661** / **N/A**

Site 2 of 12 in cluster NA

Actual: 451 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	GULF REFINING CO.
Address:	301 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0248
HID UST:	248
Inspection:	Not reported
Due:	06/01/2012

NA2215 SSW < 1/8 0.057 mi. 299 ft. — **SMITTY AUTO SERVICE REPR**, **301 CONGRESS AVE S**, **AUSTIN, TX** — **EDR Hist Auto** — **1013761569** / **N/A**

Site 3 of 12 in cluster NA

Actual: 451 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	MILLER VALCOUR V FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1965	SMITTY AUTO SERVICE REPR	AUTOMOBILE REPAIRING
1970	SOUTHSIDE MOTORS AUTO REPAIL	AUTOMOBILE REPAIRING

KY2216 ESE < 1/8 0.057 mi. 300 ft. — **CARLSONS T P SERV**, **500 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013765659** / **N/A**

Site 8 of 21 in cluster KY

Actual: 491 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1935	CARLSONS T P SERV	GASOLINE AND OIL SERVICE STATIONS

JH2217 NE < 1/8 0.057 mi. 300 ft. — **BETHKE BRAKE SERVICE**, **617 7TH ST E**, **AUSTIN, TX 78701** — **EDR Hist Auto** — **1013759421** / **N/A**

Site 12 of 13 in cluster JH

Actual: 481 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1980	BETHKE BRAKE SERVICE	AUTOMOBILE REPAIRING
1980	BETHKE BRAKE SERVICE	BRAKE SERVICE
1984	BETHKE BRAKE SERVICE	BRAKE SERVICE
1984	BETHKE BRAKE SERVICE	AUTOMOBILE REPAIRING
1990	BETHKE BRAKE SERVICE INC	BRAKE SERVICE
1990	BETHKE BRAKE SERVICE INC	AUTOMOBILE REPAIRING

JH2218 NE < 1/8 0.057 mi. 300 ft. — **BETHKE BRAKE SERVICE**, **617 7TH ST E**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013759420** / **N/A**

Site 13 of 13 in cluster JH

Actual: 481 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1975	BETHKE BRAKE SERVICE	BRAKE SERVICE
1975	BETHKE BRAKE SERVICE	AUTOMOBILE REPAIRING

NB2219 NNE < 1/8 0.057 mi. 300 ft. — **DIAMOND SHAMROCK REF & MKTG CO**, **2001 BASTROP HWY E**, **DEL VALLE, TX 78617** — **EDR Hist Auto** — **1021856593** / **N/A**

Site 1 of 5 in cluster NB

Actual: 493 ft.

Focus Map: 20

EDR Hist Auto

Year:	Name:	Type:
2014	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2014	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations

---

NB2220 NNE < 1/8 0.057 mi. 300 ft. — **DIAMOND SHAMROCK REF & MKTG CO**, **2001 BASTROP HWY**, **DEL VALLE, TX 78617** — **EDR Hist Auto** — **1020538501** / **N/A**

Site 2 of 5 in cluster NB

Actual: 493 ft.

Focus Map: 20

EDR Hist Auto

Year:	Name:	Type:
1991	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1992	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1995	DIAMOND SHAMROCK INC	Gasoline Service Stations
1996	DIAMOND SHAMROCK INC	Gasoline Service Stations
1997	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
1998	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
1999	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
2000	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
2001	ULTRAMAR DIAMOND SHAMROCK CORP	Gasoline Service Stations
2001	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2002	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2002	VALERO ENERGY CORPORATION	Gasoline Service Stations
2003	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2003	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2004	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2004	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2005	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2005	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2006	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2006	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2007	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2007	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2008	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2008	SIGMOR NUMBER 238 INC	Gasoline Service Stations
2009	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations

DIAMOND SHAMROCK REF & MKTG CO (Continued) **1020538501**

2010	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2011	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2012	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2013	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations

---

NB2221 **DIAMOND SHAMROCK REF MKTG CO** **EDR Hist Auto** **1021443461**
NNE **2001 BASTHROP HWY** **N/A**
< 1/8 **DEL VALLE, TX 78617**
0.057 mi.
300 ft. **Site 3 of 5 in cluster NB**

Actual:
493 ft.
EDR Hist Auto

Focus Map:
20

Year:	Name:	Type:
1993	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1994	DIAMOND SHAMROCK INC	Gasoline Service Stations

NB2222 **SIGMORE DIAMOND SHAMROCK** **EDR Hist Auto** **1021253010**
NNE **2001 BASTHROP HIGHWAY** **N/A**
< 1/8 **DEL VALLE, TX 78617**
0.057 mi.
300 ft. **Site 4 of 5 in cluster NB**

Actual:
493 ft.
EDR Hist Auto

Focus Map:
20

Year:	Name:	Type:
1986	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1987	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1988	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1989	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations
1990	SIGMORE DIAMOND SHAMROCK	Gasoline Service Stations

NB2223 **SIGMOR SHAMROCK SERVICE STATION GAS ST** **EDR Hist Auto** **1013776634**
NNE **2001 BASTROP HWY** **N/A**
< 1/8 **TRAVIS (County), TX 78741**
0.057 mi.
300 ft. **Site 5 of 5 in cluster NB**

Actual:
493 ft.
EDR Hist Auto

Focus Map:
20

Year:	Name:	Type:
1990	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS

KY2224 **502 04 WHITING ROBT E BATTERY AND ELECTRICAL SUPPL** **EDR Hist Auto** **1013758932**
ESE **502 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
300 ft. **Site 9 of 21 in cluster KY**

Actual:
491 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	502 04 WHITING ROBT E BATTERY A	AUTOMOBILE BRAKE SERVICE

NC2225 **MARTIN J E SERVICE STA** **EDR Hist Auto** **1013773117**
WNW **1710 1ST** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.057 mi.
301 ft. **Site 1 of 2 in cluster NC**

Actual:
514 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1929	MARTIN J E SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

NC2226 **HAYNES R E FILL STA** **EDR Hist Auto** **1013772625**
WNW **1710 1ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
301 ft. **Site 2 of 2 in cluster NC**

Actual:
514 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1935	HAYNES R E FILL STA	GASOLINE AND OIL SERVICE STATIONS

LA2227 **AUSTIN GARAGE AUTOMO** **EDR Hist Auto** **1013762266**
West **511 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
301 ft. **Site 5 of 15 in cluster LA**

Actual:
494 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1911	AUSTIN GARAGE AUTOMO	AUTOMOBILE GARAGES

MG2228 **GOODYEAR TIRE & RUBBER** **TX HIST UST** **S128729148**
SE **117 E OLTORF ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
301 ft. **Site 4 of 4 in cluster MG**

Actual:
599 ft.
HIST UST AUSTIN:

Focus Map:
14

Name:	GOODYEAR TIRE & RUBBER
Address:	117 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX035
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MU2229 NNE < 1/8 0.057 mi. 302 ft. — **NIELSON GULF SERVICE**, **329 CONGRESS AVE**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013755170** / **N/A**

Site 2 of 5 in cluster MU

Actual: 481 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	NIELSON GULF SERVICE	GASOLINE STATIONS

JP2230 SSW < 1/8 0.057 mi. 302 ft. — **M. C. PARRISH**, **219 E 5TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678729** / **N/A**

Site 22 of 27 in cluster JP

Actual: 485 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	M. C. PARRISH
Address:	219 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0307
HID UST:	307
Inspection:	12/31/2010
Due:	12/31/2013

JP2231 SSW < 1/8 0.057 mi. 302 ft. — **YELLOW CAB**, **219 E 5TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678862** / **N/A**

Site 23 of 27 in cluster JP

Actual: 485 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	YELLOW CAB
Address:	219 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0516
HID UST:	516
Inspection:	Not reported
Due:	06/01/2012

JP2232 SSW < 1/8 0.057 mi. 302 ft. — **F. O. SWENSEN**, **219 E 5TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678640** / **N/A**

Site 24 of 27 in cluster JP

Actual: 485 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	F. O. SWENSEN
Address:	219 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0072
HID UST:	72
Inspection:	Not reported
Due:	06/01/2012

JP2233 **NCNB TEXAS** **TX LPST** **S105050034**
SSW **201 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.057 mi.
302 ft. **Site 25 of 27 in cluster JP**

Actual:
486 ft.

Focus Map:
11

LPST:

Name:	NCNB TEXAS
Address:	201 E 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	099343
Facility Location:	E 5TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/29/1991
Entered Date:	06/25/1991
Reported Date:	05/29/1991
Closure Date:	10/19/1993
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	KBS
Responsible Party Name:	Not reported
Responsible Party Contact:	WOODY OGLESBY
Responsible Party Address:	1201 MAIN ST INSP DEPT
Responsible Party City,St,Zip:	DALLAS, TX 75283
Responsible Party Telephone:	512/508-4748
Reported Date:	05/29/1991
Case Start Date:	10/19/1993
Reference Number:	RN106997265
Project Manager:	KBS

JP2234 **CLOSED SITE** **TX HIST UST** **S128728764**
SSW **201 E. 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.057 mi.
302 ft. **Site 26 of 27 in cluster JP**

Actual:
486 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CLOSED SITE
Address:	201 E. 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	3404
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

JP2235 SSW < 1/8 0.057 mi. 302 ft. | **CHRISTAL-FRAZIER METER COMPANY**
201 E 5TH ST
AUSTIN, TX
Site 27 of 27 in cluster JP | **TX HIST UST** | **S128729165**
N/A

Actual: 486 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CHRISTAL-FRAZIER METER COMPANY
Address:	201 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0034
HID UST:	34
Inspection:	Not reported
Due:	06/01/2012

ND2236 East < 1/8 0.057 mi. 303 ft. | **BANK63**
CORNER OF 3RD BRAZOS
AUSTIN, TX
Site 1 of 3 in cluster ND | **TX UST** | **U001289506**
N/A

Actual: 467 ft.
Focus Map: 11

UST:

Name:	BANK63
Address:	CORNER OF 3RD BRAZOS
City,State,Zip:	AUSTIN, TX
AI Number:	60035
Facility Type:	RETAIL
Facility Begin Date:	09/25/1991
Facility Status:	INACTIVE
Additional ID:	821192582002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	CORNER OF 3RD BRAZOS
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	STEVEN T WAREING,
Contact Organization Name:	BANK63
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123973124
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/22/1991
Signature Name/Title On Earliest Reg Form:	STEVEN T WAREING,ENVIR SPECIALIST
Application Received Date On Earliest Reg Form:	09/24/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600845093
Owner Last Name:	FEDERAL DEPOSIT INSURANCE CORPORATION

BANK63 (Continued) **U001289506**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	31443472002064
Additional ID:	821192582002139
AI Number:	60035
Owner Effective Begin Date:	01/31/1995
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/24/1991
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	141384
Facility ID:	85722
Ai Number:	60035
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

BANK63 (Continued) **U001289506**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	132087
UST ID:	141384
AI Number:	60035
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

BANK63 (Continued) **U001289506**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Contact Mailing Address (Delivery):	1910 PACIFIC AVE STE 1300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75201 4529
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85722
Additional ID:	821192582002139
Princ ID:	31443472002064
AI Number:	60035
Facility Name:	BANK63
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SHARON K ALLEN/

2237 **BOWMAN RESIDENCE** **TX TANKS** **S126843348**
WNW **212 W 33RD ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX RDR**
0.057 mi. **TX CENTRAL REGISTRY**
303 ft.

Actual:
575 ft.

Focus Map:
8

TANKS:

Facility ID:	129504
Name:	BOWMAN RESIDENCE
Address:	212 W 33RD ST
City,State,Zip:	AUSTIN, TX 787052316
Total UST:	0
Additional ID:	508421302012230
AI Number:	84522
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Site Location Description:	Not reported

BOWMAN RESIDENCE (Continued) **S126843348**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

HIST UST AUSTIN:

Name:	BOWMAN RESIDENCE
Address:	212 W 33RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	3351
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	19922
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	BOWMAN RESIDENCE
Address:	212 W 33RD ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/16/2011
Due Date:	10/15/2011
Tank Owner:	MR ANDY BOWMAN
Contact Person:	MR ANDY BOWMAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/30/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	TECH RESP 10/24/11
Review Coordinator:	PPC
Date Release Reported:	Not reported

BOWMAN RESIDENCE (Continued) **S126843348**

Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/30/2011
Date Report Returned:	9/30/2011
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN106493505
Name:	BOWMAN RESIDENCE
Address:	212 W 33RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-2316
Status:	ACTIVE
Status Date:	8/17/2012
Customer Number:	CN604127001
Customer Name:	BOWMAN, ANDY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

LA2238 **505 11 BARKER MOTOR CO** **EDR Hist Auto** **1013764897**
West **505 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
305 ft. **Site 6 of 15 in cluster LA**

Actual:
493 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	505 11 BARKER MOTOR CO	AUTOMOBILE REPAIRERS
1929	505 11 BARKER MOTOR CO	AUTOMOBILE GARAGES
1935	WICKLINE GARAGE	AUTOMOBILE SERVICE
1935	WICKLINE GARAGE	AUTOMOBILE BRAKE SERVICE
1935	WICKLINE GARAGE	AUTOMOBILE GARAGES
1935	WICKLINE GARAGE	AUTOMOBILE REPAIRERS
1935	WICKLINE GARAGE	AUTOMOBILE MOTOR REBUILDING
1935	WICKLINE GARAGE	AUTOMOBILE LAUNDRIES
1940	WICKLINE GAR	AUTOMOBILE GARAGES

MU2239 **MC GOWAN ED TEXACO** **EDR Hist Auto** **1013763965**
NNE **344 CONGRESS AVE** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.058 mi.
305 ft. **Site 3 of 5 in cluster MU**

Actual:
481 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	MC GOWAN ED TEXACO	GASOLINE STATIONS

NE2240 ESE < 1/8 0.058 mi. 305 ft. | **MAJESTIC PRODUCTS 118 E ALPINE RD AUSTIN, TX 78704** | **TX HIST UST TX Ind. Haz Waste TX IHW CORR ACTION** | **S103603744 N/A**

Site 1 of 4 in cluster NE

Actual: 670 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	WOODWARD INC
Address:	118 E ALPINE RD
City,State,Zip:	AUSTIN, TX
Id UST:	H0834
HID UST:	834
Inspection:	06/06/2012
Due:	06/06/2015

Ind. Haz Waste:

Name:	MAJESTIC PRODUCTS
Address:	118 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	38485
Registration Initial Notification Date:	07/22/1988
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TX0000957415
Primary NAICS Code:	332322
Status Change Date:	19880722
Land Type:	PRIVATE
Description of Facility Site Location:	118 E Alpine Rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	THE VERMONT CASTINGS MAJESTIC PRODUCTS COMPANY
Contact Name:	RICHARD MCHENRY
Contact Telephone Number:	219-3568000
Mailing Address:	1000 E MARKET ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	HUNTINGTON, IN 467502576
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	15106
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	THE VERMONT CASTINGS MAJESTIC PRODUCTS COMPANY
Operator Address:	1000 E MARKET ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HUNTINGTON, IN 46750
Operator Country:	UNITED STA
Operator Telephone:	1-219-3568000
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13519632965
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE VERMONT CASTINGS MAJESTIC PRODUCTS COMPANY
Owner Mailing Address:	1000 E MARKET ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HUNTINGTON, IN 46750
Owner Country:	UNITED STA
Owner Telephone:	1-219-3568000
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13519632965
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	OUTDOOR STORAGE OF WASTE MATERIALS IN SOUND METAL CONTAINE Cap: 100 CBS
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19790601
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	010
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumester 40 yd North of Main building.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940901
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	132
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster 40 yd North of Main building small parts area.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940901
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	132
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster, 40 yd North of refactory building.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940901
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Permit Sequence Number:	Not reported
Unit Description:	Distiller, 5 gal distillor room.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940901
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	007
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster outside black iron
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Unit Number:	008
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum storage area located at southwest corner of property
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	009
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster (sheet metal recycled)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	010
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster (trash compactor)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	011
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster north of refractory building
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	012
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Distiller
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1000 E MARKET ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HUNTINGTON, IN 46750
Contact Phone:	1-219-3568000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1000 E MARKET ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HUNTINGTON, IN 46750
Contact Phone:	1-219-3568000
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RICHARD MCHENRY
Contact Title:	HAZARDOUS WASTE COORDINAT
Contact Role:	PRICONT
Contact Address:	1000 E MARKET ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HUNTINGTON, IN 46750
Contact Phone:	1-219-3568000
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	162112
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint waste thinned with solvents (occasional off-spec paint); 1992
Standard Industrial Code:	34330

MAJESTIC PRODUCTS (Continued) **S103603744**

Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	162111
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint waste solid dried paint (still bottoms from RCRA exempt solvent); 19921
Standard Industrial Code:	34330
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	162110
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent toluene paint thinning, (generated from cleaning paint guns treated in a R
Standard Industrial Code:	34330
Primary Source:	G06
Primary Measurement Point:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	162109
Texas Waste Code:	Not reported
Texas Waste Code 2:	00043101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solid filters or absorbents/paint filters, frompaint booths; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162108
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Concrete brick logs from manufacturing process; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162107
Texas Waste Code:	Not reported
Texas Waste Code 2:	00129012
Waste Code Status:	INACTIVE
Waste Form:	901
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production refuse; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162106
Texas Waste Code:	Not reported
Texas Waste Code 2:	00139032
Waste Code Status:	INACTIVE
Waste Form:	903
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant office refuse; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162105
Texas Waste Code:	Not reported
Texas Waste Code 2:	00144882
Waste Code Status:	INACTIVE
Waste Form:	488

MAJESTIC PRODUCTS (Continued) **S103603744**

Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wooden packaging crates (scrap wood); 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162104
Texas Waste Code:	Not reported
Texas Waste Code 2:	00153072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sheet metal scrap pieces
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162103
Texas Waste Code:	Not reported
Texas Waste Code 2:	00163082
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty containers; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

MAJESTIC PRODUCTS (Continued) **S103603744**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162102
Texas Waste Code:	Not reported
Texas Waste Code 2:	00172061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste oil from air compressor and machinery; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	162101
Texas Waste Code:	Not reported
Texas Waste Code 2:	00253022
Waste Code Status:	INACTIVE
Waste Form:	302
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Contaminated Soil resulting from receipt of contaminated fill material. Initialg
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	294189

MAJESTIC PRODUCTS (Continued) **S103603744**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DGLZ001H
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294190
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM20011
Waste Code Status:	Not reported
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294191
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM33191
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294192
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM4105H
Waste Code Status:	Not reported
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294193
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM5209H
Waste Code Status:	Not reported
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Ind. Haz Waste:

Waste ID:	294194
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM6211H
Waste Code Status:	Not reported
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294195
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM74891
Waste Code Status:	Not reported
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294196
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM82191
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0

MAJESTIC PRODUCTS (Continued) **S103603744**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294197
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGM9219H
Waste Code Status:	Not reported
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294198
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMB2101
Waste Code Status:	Not reported
Waste Form:	210
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294199
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMC210H
Waste Code Status:	Not reported
Waste Form:	210
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294200
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMD2111
Waste Code Status:	Not reported
Waste Form:	211
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294201
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMF1011
Waste Code Status:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294202
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMG1011
Waste Code Status:	Not reported
Waste Form:	101
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294203
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMH2061
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

MAJESTIC PRODUCTS (Continued) **S103603744**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294204
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMJ3191
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	294205
Texas Waste Code:	Not reported
Texas Waste Code 2:	DGMK101H
Waste Code Status:	Not reported
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	286218

MAJESTIC PRODUCTS (Continued) **S103603744**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DH7H3081
Waste Code Status:	Not reported
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	286219
Texas Waste Code:	Not reported
Texas Waste Code 2:	DH7J4061
Waste Code Status:	Not reported
Waste Form:	406
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1000 E MARKET ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HUNTINGTON, IN 46750
AR Number:	0000306077
Principal Name:	THE VERMONT CASTINGS MAJESTIC PRODUCTS COMPANY
Attention Name:	Not reported
Attention Suffix:	HWG

MAJESTIC PRODUCTS (Continued) **S103603744**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1000 E MARKET ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HUNTINGTON, IN 46750
AR Number:	0000306077
Principal Name:	THE VERMONT CASTINGS MAJESTIC PRODUCTS COMPANY
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	MAJESTIC PRODUCTS AUSTIN
Address:	118 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704
Program Id:	38485
Location Desc:	TRAVIS
RN NUM:	RN100615277
Status:	INACTIVE
Status Date:	08/20/1998
EDR Link ID:	38485
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	08/20/1998
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

NE2241 **BROYHILL FURNITURE INDUSTRIES** **TX UST** **U001237663**
ESE **118 E ALPINE RD** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.058 mi.
305 ft. **Site 2 of 4 in cluster NE**

Actual:
670 ft.

Focus Map:
14

UST:

Name:	BROYHILL FURNITURE INDUSTRIES
Address:	118 E ALPINE RD
City,State,Zip:	AUSTIN, TX 787046529
AI Number:	278
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	05/27/1986
Facility Status:	INACTIVE
Additional ID:	380655572003100
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	RON TUCKER,MAINT MGR
Contact Organization Name:	BROYHILL FURNITURE INDUSTRIES
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

BROYHILL FURNITURE INDUSTRIES (Continued) **U001237663**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124449511
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/27/1986
Signature Name/Title On Earliest Reg Form:	RON TUCKER,MAINT. MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601617418
Owner Last Name:	BROYHILL FURNITURE INDUSTRIES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	388655572003100
Additional ID:	380655572003100
AI Number:	278
Owner Effective Begin Date:	05/27/1986
State Tax ID:	15612232171
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	659
Facility ID:	38200
Ai Number:	278
Tank Id:	THINNER
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/14/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

BROYHILL FURNITURE INDUSTRIES (Continued) **U001237663**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	THINNER
Tank Capacity:	Not reported
UST Comprt ID:	2623
UST ID:	659
AI Number:	278
Compartment ID:	A
Substance Stored1:	TOLUENE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

BROYHILL FURNITURE INDUSTRIES (Continued) **U001237663**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	660
Facility ID:	38200
Ai Number:	278
Tank Id:	GASOLINE
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/14/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

BROYHILL FURNITURE INDUSTRIES (Continued) **U001237663**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	GASOLINE
Tank Capacity:	Not reported
UST Comprt ID:	2624
UST ID:	660
AI Number:	278
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

BROYHILL FURNITURE INDUSTRIES (Continued) **U001237663**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BROYHILL FURNITURE INDUSTRIES INC
Contact Mailing Address (Delivery):	118 E ALPINE RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 6529
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	38200
Additional ID:	380655572003100
Princ ID:	388655572003100
AI Number:	278
Facility Name:	BROYHILL FURNITURE INDUSTRIES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

NE2242 **MAJESTIC PRODUCTS CO** **RCRA NonGen / NLR** **1000982579**
ESE **118 E ALPINE RD** **TX0000957415**
< 1/8 **AUSTIN, TX 78704**
0.058 mi.
305 ft. **Site 3 of 4 in cluster NE**

Actual:
670 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Majestic Products Co
Handler Address:	E ALPINE RD
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TX0000957415
Contact Name:	RICHARD MCHENRY

MAJESTIC PRODUCTS CO (Continued) **1000982579**

Contact Address:	E MARKET ST
Contact City,State,Zip:	HUNTINGTON, IN 46750
Contact Telephone:	219-356-8000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E MARKET ST
Mailing City,State,Zip:	HUNTINGTON, IN 46750
Owner Name:	Majestic Products Co
Owner Type:	Private
Operator Name:	Majestic Products Co
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

MAJESTIC PRODUCTS CO (Continued) **1000982579**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MAJESTIC PRODUCTS CO
Legal Status: Private

MAJESTIC PRODUCTS CO (Continued) **1000982579**

Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	1000 E MARKET ST
Owner/Operator City,State,Zip:	HUNTINGTON, IN 46750
Owner/Operator Telephone:	219-356-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MAJESTIC PRODUCTS CO	
Legal Status:	Private
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	1000 E MARKET ST
Owner/Operator City,State,Zip:	HUNTINGTON, IN 46750
Owner/Operator Telephone:	219-356-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MAJCO BLDG SPECIALISTS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1000 E MARKET ST
Owner/Operator City,State,Zip:	HUNTINGTON, IN 46750
Owner/Operator Telephone:	219-356-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19980218
Handler Name: MAJESTIC PRODUCTS CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010214
Handler Name: MAJESTIC PRODUCTS CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

MAJESTIC PRODUCTS CO (Continued) **1000982579**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332322
NAICS Description: SHEET METAL WORK MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NE2243 **MAJESTIC PRODUCTS** **TX Ind. Haz Waste** **S110293583**
ESE **118 E ALPINE RD** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.058 mi.
305 ft. **Site 4 of 4 in cluster NE**

Actual:
670 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	MAJESTIC PRODUCTS
Address:	118 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	30501
Registration Initial Notification Date:	04/14/1976
Registration Last Amendment Date:	02/19/1997
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19760414
Land Type:	Not reported
Description of Facility Site Location:	TRAVIS
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	MAJCO BLDG SPECIALTIES LP
Contact Name:	RICHARD MCHENRY
Contact Telephone Number:	219-3568000
Mailing Address:	PO BOX 800
Mailing Address2:	Not reported
Mailing City,State,Zip:	HUNTINGTON, IN 467500800
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	8066
Site Owner Tax ID:	0

MAJESTIC PRODUCTS (Continued) **S110293583**

Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	19970821
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	MAJESTIC COMPANY
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MAJCO BLDG SPECIALTIES LP
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14

MAJESTIC PRODUCTS (Continued) **S110293583**

Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum storage area located at southwest corner of property
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	40
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster (sheet metal recycled)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	40
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster (trash compactor)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	20
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster north of refractory building
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	5
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Distiller
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	40
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	007
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	40
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster outside black iron
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941118
Deed Record Needed:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

Deed Recording Date: Not reported

Ind. Haz Waste:

Contact Name:	RICHARD MCHENRY
Contact Title:	MANUF. ENGIN. MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 800
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HUNTINGTON, IN 46750
Contact Phone:	1-219-3568000
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	126045
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint waste thinned with solvents (occasional off-spec paint); 1992
Standard Industrial Code:	34330
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	126047
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint waste solid dried paint (still bottoms from RCRA exempt solvent); 19921
Standard Industrial Code:	34330
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	126049
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent toluene paint thinning, (generated from cleaning paint guns treated in a R
Standard Industrial Code:	34330
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333414
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	126050
Texas Waste Code:	Not reported
Texas Waste Code 2:	00043101
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solid filters or absorbents/paint filters, frompaint booths; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

MAJESTIC PRODUCTS (Continued) **S110293583**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126051
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Concrete brick logs from manufacturing process; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126052
Texas Waste Code:	Not reported
Texas Waste Code 2:	00129012
Waste Code Status:	INACTIVE
Waste Form:	901
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production refuse; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126053
Texas Waste Code:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

Texas Waste Code 2:	00139032
Waste Code Status:	INACTIVE
Waste Form:	903
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant office refuse; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126054
Texas Waste Code:	Not reported
Texas Waste Code 2:	00144882
Waste Code Status:	INACTIVE
Waste Form:	488
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wooden packaging crates (scrap wood); 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126055
Texas Waste Code:	Not reported
Texas Waste Code 2:	00153072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sheet metal scrap pieces
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

MAJESTIC PRODUCTS (Continued) **S110293583**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126056
Texas Waste Code:	Not reported
Texas Waste Code 2:	00163082
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty containers; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	126057
Texas Waste Code:	Not reported
Texas Waste Code 2:	00172061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste oil from air compressor and machinery; 1992
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

MAJESTIC PRODUCTS (Continued) **S110293583**

Waste ID:	136295
Texas Waste Code:	Not reported
Texas Waste Code 2:	00253022
Waste Code Status:	INACTIVE
Waste Form:	302
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Contaminated Soil resulting from receipt of contaminated fill material. Initialg
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1000 E MARKET ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HUNTINGTON, IN 46750
AR Number:	0000311753
Principal Name:	MAJCO BLDG SPECIALTIES LP
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1000 E MARKET ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	HUNTINGTON, IN 46750
AR Number:	0000311753
Principal Name:	MAJCO BLDG SPECIALTIES LP
Attention Name:	Not reported
Attention Suffix:	NWG

NF2244 **DIAMOND SHAMROCK** **EDR Hist Auto** **1020710130**
WNW **806 W RUNDBERG LN** **N/A**
< 1/8 **AUSTIN, TX 78758**
0.058 mi.
307 ft. **Site 1 of 2 in cluster NF**

Actual:
678 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1990	DIAMOND SHAMROCK	Grocery Stores
1991	DIAMOND SHAMROCK	Grocery Stores
1992	DIAMOND SHAMROCK	Grocery Stores
1993	DIAMOND SHAMROCK	Grocery Stores
1994	DIAMOND SHAMROCK	Grocery Stores
1995	DIAMOND SHAMROCK	Grocery Stores

NF2245 **DIAMOND SHAMROCK 964** **TX LPST** **U001276884**
WNW **806 W RUNDBERG LN** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78758** **TX HIST UST**
0.058 mi.
307 ft. **Site 2 of 2 in cluster NF**

Actual:
678 ft.

Focus Map:
6

LPST:

Name:	964
Address:	806 W RUNDBERG LN
City,State,Zip:	AUSTIN, TX 78758
Facility ID:	0045251
LPST Id:	110737
Facility Location:	802 RUNDBERG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	03/28/1996
Reported Date:	12/31/3000
Closure Date:	03/28/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	SHAY WIDEMAN
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/641-6800
Reported Date:	12/31/3000
Case Start Date:	03/28/1996
Reference Number:	RN102370343
Project Manager:	XYZ

UST:

Name:	DIAMOND SHAMROCK 964
Address:	806 W RUNDBERG LN
City,State,Zip:	AUSTIN, TX 787586737
AI Number:	45251
Facility Type:	RETAIL

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	430756082002149
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	SHAY WIDEMAN,
Contact Organization Name:	DIAMOND SHAMROCK 964
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2106418606
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	JAMES MANNING,DIV MGR
Application Received Date On Earliest Reg Form:	10/08/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602277386
Owner Last Name:	CST SERVICES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	765580132003199
Additional ID:	430756082002149
AI Number:	45251
Owner Effective Begin Date:	09/01/1987
State Tax ID:	17425053794
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1975

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	118529
Facility ID:	74626
Ai Number:	45251
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	104488
UST ID:	118529
AI Number:	45251
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	61007
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	61008
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	61009
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	61010
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	61011
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61012
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61013
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61014
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A

Self Cert ID:	17646

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Cert ID:	23104
UST Comprt ID:	61017
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61016
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61015
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901798
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836775
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745480
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699917
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716

DIAMOND SHAMROCK 964 (Continued) **U001276884**

UST Comprt ID:	650672
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	61006
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	118530
Facility ID:	74626
Ai Number:	45251
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

DIAMOND SHAMROCK 964 (Continued) **U001276884**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	104489
UST ID:	118530
AI Number:	45251
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	61007
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	61008
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	61009
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	61010
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	61011
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61012
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106

DIAMOND SHAMROCK 964 (Continued) **U001276884**

UST Comprt ID:	61013
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61014
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23104
UST Comprt ID:	61017
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61016
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61015
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901798
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836775
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745480

DIAMOND SHAMROCK 964 (Continued) **U001276884**

UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699917
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650672
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	61006
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	118531
Facility ID:	74626
Ai Number:	45251
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	104490
UST ID:	118531
AI Number:	45251
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

DIAMOND SHAMROCK 964 (Continued) **U001276884**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	61007
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	61008
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	61009
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	61010
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	61011

DIAMOND SHAMROCK 964 (Continued) **U001276884**

UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61012
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61013
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61014
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23104
UST Comprt ID:	61017
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61016
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61015
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901798
UST ID:	20553

DIAMOND SHAMROCK 964 (Continued) **U001276884**

AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836775
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745480
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699917
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650672
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	61006
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1975
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	118532
Facility ID:	74626
Ai Number:	45251
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Tank Status Date:	12/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	104491
UST ID:	118532
AI Number:	45251
Compartment ID:	A

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17646
Cert ID:	23112
UST Comprt ID:	61007
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23111
UST Comprt ID:	61008
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23110
UST Comprt ID:	61009
UST ID:	20553

DIAMOND SHAMROCK 964 (Continued) **U001276884**

AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23109
UST Comprt ID:	61010
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23108
UST Comprt ID:	61011
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23107
UST Comprt ID:	61012
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23106
UST Comprt ID:	61013
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23105
UST Comprt ID:	61014
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23104
UST Comprt ID:	61017
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23103
UST Comprt ID:	61016
UST ID:	20553
AI Number:	45251

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23102
UST Comprt ID:	61015
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	311598
UST Comprt ID:	901798
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	289831
UST Comprt ID:	836775
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	259016
UST Comprt ID:	745480
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	243581
UST Comprt ID:	699917
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	226716
UST Comprt ID:	650672
UST ID:	20553
AI Number:	45251
Tank ID:	1
Compartment ID:	A
Self Cert ID:	17646
Cert ID:	23113
UST Comprt ID:	61006
UST ID:	20553
AI Number:	45251
Tank ID:	1

DIAMOND SHAMROCK 964 (Continued) **U001276884**

Compartment ID: A

Facility Billing Contacts:

Contact Organization Name:	DIAMOND SHAMROCK REFINING AND MARKETING COMPANY
Contact Mailing Address (Delivery):	PO BOX 696000
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78269 6000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	74626
Additional ID:	430756082002149
Princ ID:	765580132003199
AI Number:	45251
Facility Name:	DIAMOND SHAMROCK 964
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	DIAMOND SHAMROCK #0964
Address:	806 W RUNDBERG LN
City,State,Zip:	AUSTIN, TX
Id UST:	C0602
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LV2246 **CONVENIENCE COIN LAUNDRY NO** **EDR Hist Cleaner** **1013782762**
ESE **101 38TH ST E** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.058 mi.
307 ft. **Site 4 of 9 in cluster LV**

Actual:
610 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1980	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

LV2247 **CONVENIENCE COIN LAUNDRY NO** **EDR Hist Cleaner** **1013780130**
ESE **101 38TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.058 mi.
307 ft. **Site 5 of 9 in cluster LV**

Actual:
610 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1990	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

2248 West < 1/8 0.058 mi. 307 ft. | **STUDENT CO OPERATIVE ASSN 2412 SAN ANTONIO AUSTIN, TX** | **EDR Hist Auto** | **1013758531 N/A**

Actual: 590 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	STUDENT CO OPERATIVE ASSN	REPAIR SHOPS

LL2249 ESE < 1/8 0.058 mi. 307 ft. | **VALENTA SERVICE STATION 5607 CONGRESS AVE S AUSTIN, TX** | **EDR Hist Auto** | **1013758793 N/A**

Site 3 of 4 in cluster LL

Actual: 632 ft. EDR Hist Auto

Focus Map: 17

Year:	Name:	Type:
1965	VALENTA SERVICE STATION	GASOLINE STATIONS

LL2250 ESE < 1/8 0.058 mi. 307 ft. | **VALENTA SERV STA 5607 CONGRESS AVE SOUTH AUSTIN, TX** | **EDR Hist Auto** | **1013761860 N/A**

Site 4 of 4 in cluster LL

Actual: 632 ft. EDR Hist Auto

Focus Map: 17

Year:	Name:	Type:
1962	VALENTA SERV STA	GASOLINE STATIONS

LW2251 WNW < 1/8 0.058 mi. 307 ft. | **PRATHER F H FILL STA 1601 1ST AUSTIN, TX** | **EDR Hist Auto** | **1013758054 N/A**

Site 2 of 3 in cluster LW

Actual: 508 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1935	PRATHER F H FILL STA	GASOLINE AND OIL SERVICE STATIONS

LW2252 WNW < 1/8 0.058 mi. 307 ft. | **MC CLAIN HORACE C CDO 1600 1ST SOUTH AUSTIN, TX** | **EDR Hist Cleaner** | **1013779043 N/A**

Site 3 of 3 in cluster LW

Actual: 508 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1929	MC CLAIN HORACE C CDO	CLOTHES CLEANERS AND PRESSERS

MQ2253 **CINDERELLA CLNS** **EDR Hist Cleaner** **1013781426**
ENE **3500 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
307 ft. **Site 3 of 18 in cluster MQ**

Actual:
588 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1962	CINDERELLA CLNS	CLEANERS AND DYERS
1965	CINDERELLA CLEANERS	CLEANERS AND DYERS

MQ2254 **NOACK BENJ FILL STA** **EDR Hist Auto** **1013758002**
ENE **3500 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
307 ft. **Site 4 of 18 in cluster MQ**

Actual:
588 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1929	VEHLING HENRY FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	URBAN W P FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	NOACK BENJ FILL STA	GASOLINE AND OIL SERVICE STATIONS

LA2255 **203 5 SMITH KELLY DCLO CLNR** **EDR Hist Cleaner** **1013781131**
WNW **203 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
308 ft. **Site 7 of 15 in cluster LA**

Actual:
497 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	203 5 SMITH KELLY DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

LA2256 **STARR BLDG HISTORIC SVC STATION** **TX RDR** **S127543529**
West **501 COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
308 ft. **Site 8 of 15 in cluster LA**

Actual:
493 ft.

Focus Map:
11

RDR:

RDR ID:	18446
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	STARR BLDG HISTORIC SVC STATION
Address:	501 COLORADO
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/21/2009
Due Date:	11/20/2009
Tank Owner:	KEMP PROPERTIES
Contact Person:	CASEY BEASLEY
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/15/2009

STARR BLDG HISTORIC SVC STATION (Continued) **S127543529**

Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	118164
Pre-Existing LPST Number:	Not reported
Comments:	LAD AND RQT DWS SENT 10/30/09
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LA2257 **KEMP PROPERTIES** **TX LPST** **S109957278**
West **501 COLORADO ST** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
308 ft. **Site 9 of 15 in cluster LA**

Actual:
493 ft.

Focus Map:
11

LPST:

Name:	STARR BUILDING HISTORICAL SS
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	118164
Facility Location:	501 COLORADO ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/29/2009
Entered Date:	10/15/2009
Reported Date:	09/18/2009
Closure Date:	11/03/2009
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6P - FINAL PENDING WELL PLUG
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE PENDING DOCUMENTATION OF WELL PLUGGING**
Coordinators Primary:	1P
Coordinators RPR:	DB2
Responsible Party Name:	Not reported
Responsible Party Contact:	CASEY BEASLEY
Responsible Party Address:	3809 S 2ND ST STE D-200
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/463-4103
Reported Date:	09/18/2009
Case Start Date:	11/03/2009
Reference Number:	RN106989213
Project Manager:	DBRATBER

GCC:

Name:	KEMP PROPERTIES
Address:	501 COLORADO ST
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	*
File Number:	118164

KEMP PROPERTIES (Continued) **S109957278**

Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 10/15/2009
Enforcement Status - Level Of Agency Response: 6 -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

LA2258 **WOFFORD S D FILLING ST** **EDR Hist Auto** **1013764873**
West **501 COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.058 mi.
308 ft. **Site 10 of 15 in cluster LA**

Actual:
493 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	ANDERSON E W TIRE	AUTOMOBILE FILLING STATIONS
1940	WOFFORD S D FILLING ST	GASOLINE AND OIL SERVICE STATIONS

LO2259 **Z TECH AUTO REPR** **EDR Hist Auto** **1013770948**
WNW **809 CAPITOL ST** **N/A**
< 1/8 **TRAVIS (County), TX 78756**
0.059 mi.
310 ft. **Site 5 of 5 in cluster LO**

Actual:
665 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1971	CECIL AUTO TRIM	Automotive Repair Shops, NEC
1972	CECIL AUTO TRIM	Automotive Repair Shops, NEC
1973	CECIL AUTO TRIM	Automotive Repair Shops, NEC
1974	CECIL AUTO TRIM	Automotive Repair Shops, NEC
1988	Z-TECH	Automotive Repair Shops, NEC
1990	Z TECH AUTO REPR	AUTOMOBILE REPAIRING
1991	FRENCH REVOLUTION	Engine Repair
1992	FRENCH REVOLUTION	Engine Repair
1999	FRENCH REVOLUTION THE	Automotive Repair Shops, NEC
2000	FRENCH REVOLUTION THE	Automotive Repair Shops, NEC
2001	FRENCH REVOLUTION THE	Automotive Repair Shops, NEC
2002	FRENCH REVOLUTION	Automotive Repair Shops, NEC
2003	FRENCH REVOLUTION	Automotive Repair Shops, NEC
2004	FRENCH REVOLUTION	Automotive Repair Shops, NEC
2005	FRENCH REVOLUTION	Automotive Repair Shops, NEC
2006	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC
2007	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC
2008	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC
2009	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC
2010	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC
2011	REVOLUTION MOTORS INC	Automotive Repair Shops, NEC

KJ2260 ESE < 1/8 0.059 mi. 311 ft. — **SCHNEIDER ALBERT REP SHOP**, **310 2ND W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013761301** / **N/A**

Site 4 of 4 in cluster KJ

Actual: 472 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	SCHNEIDER ALBERT REP SHOP	REPAIR SHOPS
1935	SCHNEIDER ALBERT	REPAIR SHOPS

KY2261 ESE < 1/8 0.059 mi. 313 ft. — **SING FRANCES MRS LNDRY**, **311 5TH ST W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013784907** / **N/A**

Site 10 of 21 in cluster KY

Actual: 489 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1929	SING FRANCES MRS LNDRY	LAUNDRIES

MY2262 WNW < 1/8 0.059 mi. 313 ft. — **AUSTIN CONVENTION CENTER**, **300 RED RIVER ST**, **AUSTIN, TX** — **TX HIST UST** — **S128729116** / **N/A**

Site 2 of 3 in cluster MY

Actual: 464 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	AUSTIN CONVENTION CENTER
Address:	300 RED RIVER ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0682
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LX2263 WNW < 1/8 0.059 mi. 313 ft. — **GREGORY FENDER**, **815 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775308** / **N/A**

Site 15 of 15 in cluster LX

Actual: 462 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	GREGORY FENDER	AUTOMOBILE REPAIRING

LV2264 ESE < 1/8 0.059 mi. 314 ft. — **M F ROUTE LAUNDRIES**, **103 38TH ST E**, **AUSTIN, TX 78705** — **EDR Hist Cleaner** — **1013783363** / **N/A**

Site 6 of 9 in cluster LV

Actual: 610 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1980	M F ROUTE LAUNDRIES	LAUNDRIES AND DRY CLEANERS

LV2265 ESE < 1/8 0.059 mi. 314 ft. — **CONVENIENCE COIN LAUNDRY NO**, **103 38TH ST E**, **TRAVIS (County), TX 78705** — **EDR Hist Cleaner** — **1013786776** / **N/A**

Site 7 of 9 in cluster LV

Actual: 610 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1975	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE
1990	M F ROUTE LAUNDRIES	LAUNDRIES AND DRY CLEANERS

2266 ESE < 1/8 0.060 mi. 315 ft. — **WALKERS LAUNDRY**, **1903 NEWTON ST**, **SOUTH AUSTIN, TX** — **EDR Hist Cleaner** — **1013779775** / **N/A**

Actual: 546 ft. EDR Hist Cleaner

Focus Map: 14

Year:	Name:	Type:
1922	WALKERS LAUNDRY	CLEANERS, PRESSERS AND DYERS
1922	WALKERS LAUNDRY	LAUNDRIES
1922	WALKERS LAUNDRY	DYERS AND CLEANERS
1922	WALKERS LAUNDRY	CLOTHES CLEANERS AND PRESSERS

KL2267 WNW < 1/8 0.060 mi. 316 ft. — **BELL AIRDOME FILLING**, **900 COLORADO**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768409** / **N/A**

Site 5 of 5 in cluster KL

Actual: 530 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	BELL AIRDOME FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1935	BELL AIRDOME FILLING	GASOLINE AND OIL SERVICE STATIONS
1940	BELL AIRDOME FILLING	GASOLINE AND OIL SERVICE STATIONS

2268 ESE < 1/8 0.060 mi. 316 ft. | **MEACHAM W W R**
3104 KING ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013787222**
N/A

Actual: 600 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1922	MEACHAM W W R	CLOTHES CLEANERS AND PRESSERS

KS2269 ESE < 1/8 0.060 mi. 317 ft. | **FORMER GLO FAC**
421 E 1ST
AUSTIN, TX | **TX RDR** | **S127536966**
N/A

Site 5 of 5 in cluster KS

Actual: 457 ft. RDR:

Focus Map: 11

RDR ID:	8544
Facility ID:	63213
RN:	Not reported
CN:	Not reported
Name:	FORMER GLO FAC
Address:	421 E 1ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/29/2001
Due Date:	1/28/2002
Tank Owner:	TRINITY STREEET JOINT VEN
Contact Person:	JOHN BEAUCHAMP
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/19/2003
Project Manager:	Diana Kalich
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RTN:SAMPLING METHODS, SITE MAP, PIPE/DISP. SAMPLE;10/6/00;11/29/0
Review Coordinator:	DRK/LLD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/19/2003
Date Report Returned:	9/24/2001
Region:	Not reported
DKC RDR (misfiled):	Not reported

NG2270 WNW < 1/8 0.060 mi. 318 ft. | **THURMAN WAVERLY**
620 COLORADO ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013787685**
N/A

Site 1 of 16 in cluster NG

Actual: 498 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	THURMAN WAVERLY	CLOTHES PRESSERS AND CLEANERS

LA2271 **HOUGH ROY AUTO REPR** **EDR Hist Auto** **1013755894**
WNW **608 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.060 mi.
319 ft. **Site 11 of 15 in cluster LA**

Actual:
497 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	HOUGH ROY AUTO REPR	AUTOMOBILE REPAIRERS
1922	608 10 WEBB J E TIRES	AUTOMOBILE FILLING STATIONS

NH2272 **WHITLEY CO** **TX UST** **1000414749**
ESE **801 BRAZOS TO 805** **RCRA NonGen / NLR** **TXD008143729**
< 1/8 **AUSTIN, TX 78701**
0.060 mi.
319 ft. **Site 1 of 2 in cluster NH**

Actual:
523 ft.

Focus Map:
11

UST:

Name:	ACE TRANSPORTATION
Address:	1000 HARRELL DR
City,State,Zip:	ROBSTOWN, TX 783804415
AI Number:	17140
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/25/1986
Facility Status:	INACTIVE
Additional ID:	973043482002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	NUECES
Site Location (Tceq Region):	14
Site Location (Location Zip):	78380
Contact Name/Title:	ROBERT WHITLEY,
Contact Organization Name:	ACE TRANSPORTATION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	3188374567
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/22/1986
Signature Name/Title On Earliest Reg Form:	R W WHITLEY,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600357248
Owner Last Name:	ACE TRANSPORTATION INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported

WHITLEY CO (Continued) **1000414749**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	950336182001309
Additional ID:	973043482002118
AI Number:	17140
Owner Effective Begin Date:	04/29/1994
State Tax ID:	17209482060
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	43569
Facility ID:	55609
Ai Number:	17140
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/19/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

WHITLEY CO (Continued) **1000414749**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/21/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	51217
UST ID:	43569
AI Number:	17140
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

WHITLEY CO (Continued) **1000414749**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	43568
Facility ID:	55609
Ai Number:	17140
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/19/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

WHITLEY CO (Continued) **1000414749**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/21/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	51216
UST ID:	43568
AI Number:	17140
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

WHITLEY CO (Continued) **1000414749**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ACE TRANSPORTATION INC
Contact Mailing Address (Delivery):	PO BOX 91714
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	LAFAYETTE, LA 70509 1714
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	55609
Additional ID:	973043482002118
Princ ID:	950336182001309
AI Number:	17140
Facility Name:	ACE TRANSPORTATION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	G STUTER/

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Whitley Co
Handler Address:	BRAZOS TO 805
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD008143729
Contact Name:	ENVIRONMENTAL M MANAGER
Contact Address:	PO BOX 1564
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1564
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	Whitley Co
Owner Type:	Not reported
Operator Name:	Whitley Co
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

WHITLEY CO (Continued) **1000414749**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WHITLEY CO	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1564
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WHITLEY CO	
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1564

WHITLEY CO (Continued) **1000414749**

Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERT W WHITLEY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860508
Handler Name: WHITLEY TRUCKS INC.
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: WHITLEY CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48411
NAICS Description: GENERAL FREIGHT TRUCKING, LOCAL

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NH2273 **WHITLEY** **TX Ind. Haz Waste** **S102740926**
ESE **801 BRAZOS TO 805** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.060 mi.
319 ft. **Site 2 of 2 in cluster NH**

Actual:
523 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	WHITLEY
Address:	801 BRAZOS TO 805
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	33359
Registration Initial Notification Date:	02/14/2001
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXD008143729
Primary NAICS Code:	484110
Status Change Date:	20010214
Land Type:	Not reported
Description of Facility Site Location:	801-805 Brazos, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	THE WHITLEY COMPANY LP
Contact Name:	ENVIRONMENTAL MANAGER MANAGER
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 1564
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671564
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	10858
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020828
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

WHITLEY (Continued) **S102740926**

Ind. Haz Waste:

Operator Name:	THE WHITLEY COMPANY LP
Operator Address:	PO BOX 1564
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17413840301
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE WHITLEY COMPANY LP
Owner Mailing Address:	PO BOX 1564
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17413840301
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 1564
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 1564
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ENVIRONMENTAL MANAGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1564
Contact Address 2:	Not reported

WHITLEY (Continued) **S102740926**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1564
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

NI2274 **SOUTH FIRST CLEANERS** **TX Ind. Haz Waste** **S102753011**
WNW **1905 S 1ST ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.060 mi.
319 ft. **Site 1 of 6 in cluster NI**

Actual:
521 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	SOUTH FIRST CLEANERS
Address:	1905 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	70592
Registration Initial Notification Date:	09/01/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19860901
Land Type:	Not reported
Description of Facility Site Location:	1905 S 1st St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	SOUTH FIRST CLEANERS
Contact Name:	PETE CASTRO
Contact Telephone Number:	512-4427463
Mailing Address:	1905 S 1ST ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787044253
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

SOUTH FIRST CLEANERS (Continued) **S102753011**

TNRCC Facility ID:	25404
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	SOUTH FIRST CLEANERS
Operator Address:	1905 S 1ST ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4427463
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	SOUTH FIRST CLEANERS
Owner Mailing Address:	1905 S 1ST ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4427463
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1905 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427463
Contact Fax:	Not reported

SOUTH FIRST CLEANERS (Continued) **S102753011**

Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1905 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427463
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	PETE CASTRO
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1905 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4427463
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100623917
Name:	SOUTH FIRST CLEANERS
Address:	1905 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-4253
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600332738
Customer Name:	SOUTH FIRST CLEANERS
Customer Legal Name:	South First Cleaners
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1905 S 1st St, Austin, TX

NI2275 **SOUTH FIRST CLEANERS** **EDR Hist Cleaner** **1018746341**
WNW **1905 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.060 mi.
319 ft. **Site 2 of 6 in cluster NI**

Actual:
521 ft.

EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1992	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents
1993	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents
1994	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents
1996	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents

SOUTH FIRST CLEANERS (Continued) **1018746341**

1997	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents
1998	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents
1999	SOUTH FIRST CLEANERS	Garment Pressing And Cleaners' Agents

---

KY2276 **AMERICAN CLEANERS** **EDR Hist Cleaner** **1013783926**
ESE **309 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.061 mi.
320 ft. **Site 11 of 21 in cluster KY**

Actual:
489 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1990	AMERICAN CLEANERS	CLEANERS AND DYERS

KY2277 **FAULKNER RUSSELL C** **EDR Hist Auto** **1013769207**
ESE **309 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.061 mi.
320 ft. **Site 12 of 21 in cluster KY**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	FAULKNER RUSSELL C	AUTOMOBILE MOTOR REBUILDING
1940	FAULKNER RUSSELL C	AUTOMOBILE SERVICE
1940	FAULKNER RUSSELL C	AUTOMOBILE REPAIRERS

NJ2278 **MC CUTCHEON U S AUTO** **EDR Hist Auto** **1013769878**
NNE **106 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.061 mi.
320 ft. **Site 1 of 4 in cluster NJ**

Actual:
471 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	MC CUTCHEON U S AUTO	AUTOMOBILE REPAIRERS

NK2279 **DOWNS R L & CO** **EDR Hist Cleaner** **1013786628**
ESE **309 10TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.061 mi.
321 ft. **Site 1 of 2 in cluster NK**

Actual:
547 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	BIGGS & CO DCLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1940	BIGGS & CO CLDO	CLOTHES PRESSERS AND CLEANERS
1947	DOWNS R L & CO CLNRS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1953	DOWNS R L & CO	CLEANERS AND DYERS

KH2280 SSW < 1/8 0.061 mi. 321 ft. | **WARDROBE CLNRS THE**
207 CONGRESS AVE E
AUSTIN, TX
Site 13 of 19 in cluster KH | **EDR Hist Cleaner** | **1013779813**
N/A

Actual: 475 ft.
EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1929	WARDROBE CLNRS THE	CLOTHES CLEANERS AND PRESSERS

NA2281 SSW < 1/8 0.061 mi. 322 ft. | **FIRESTONE TIRE & SERVICE CENTER**
311 S CONGRESS AVE
AUSTIN, TX 78704
Site 4 of 12 in cluster NA | **TX LPST**
TX UST
TX HIST UST | **U003566395**
N/A

Actual: 451 ft.

Focus Map: 11

LPST:

Name:	FIRESTONE TIRE SERVICE CENTER
Address:	311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0064640
LPST Id:	106686
Facility Location:	311 S CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/15/1993
Entered Date:	06/17/1993
Reported Date:	04/19/1993
Closure Date:	02/05/2002
Priority:	3.2 - IMPACTED GW W/IN 500ft-0.25mi TO SW USED BY HUMANENDGR SPEC
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and the affected groundwater zone may discharge between 500 feet and 0.25 miles of the UST/AST or source area to a surface water body used for human drinking water, contact recreation, or habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/1P/1/2
Coordinators RPR:	RWD
Responsible Party Name:	Not reported
Responsible Party Contact:	DEBRA HAMLIN
Responsible Party Address:	333 E LAKE ST
Responsible Party City,St,Zip:	BLOOMINGDALE, IL 60108
Responsible Party Telephone:	630/259-9379
Reported Date:	04/19/1993
Case Start Date:	02/05/2002
Reference Number:	RN101499291
Project Manager:	RWD

UST:

Name:	FIRESTONE TIRE & SERVICE CENTER
Address:	311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787041200
AI Number:	64640
Facility Type:	RETAIL
Facility Begin Date:	05/25/1993
Facility Status:	INACTIVE

FIRESTONE TIRE & SERVICE CENTER (Continued) **U003566395**

Additional ID:	990489392002054
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	FIRESTONE TIRE & SERVICE CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124431782
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/19/1993
Signature Name/Title On Earliest Reg Form:	JOHN C BERNSTEIN,PROJECT MANAGER
Application Received Date On Earliest Reg Form:	05/25/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600785984
Owner Last Name:	SOUTH CONGRESS PROPERTIES
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	980489382002054
Additional ID:	990489392002054
AI Number:	64640
Owner Effective Begin Date:	05/25/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/25/1993
Number of Compartments:	1

FIRESTONE TIRE & SERVICE CENTER (Continued) **U003566395**

Tank Capacity:	400
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	148423
Facility ID:	95965
Ai Number:	64640
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/19/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

FIRESTONE TIRE & SERVICE CENTER (Continued) **U003566395**

Tank Tested Flag:	N
Installation Signature Date:	05/12/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	400
UST Comprt ID:	153686
UST ID:	148423
AI Number:	64640
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTH CONGRESS PROPERTIES
Contact Mailing Address (Delivery):	1206 W 6TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 5209
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95965

FIRESTONE TIRE & SERVICE CENTER (Continued) **U003566395**

Additional ID:	990489392002054
Princ ID:	980489382002054
AI Number:	64640
Facility Name:	FIRESTONE TIRE & SERVICE CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BALIE J GRIFFIN/

HIST UST AUSTIN:

Name:	FIRESTONE MASTERCARE STORE
Address:	311 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0398
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KT2282 **209 11 BLUE BONNET ODORLESS DRY CLNRS** **EDR Hist Cleaner** **1013779832**
WNW **209 8TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.061 mi.
323 ft. **Site 3 of 4 in cluster KT**

Actual:
527 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	209 11 BLUE BONNET ODORLESS DRY	CLOTHES PRESSERS AND CLEANERS

NA2283 **GULF REFG CO STA NO** **EDR Hist Auto** **1013775588**
SSW **300 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.061 mi.
323 ft. **Site 5 of 12 in cluster NA**

Actual:
452 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1947	ELLIOT CARL L FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	ELLIOTT CARL L SER	GASOLINE STATIONS
1958	ELLIOTT CARL L SERV	GASOLINE STATIONS

NA2284 **KINGSLEY AUTOMOTIVE** **EDR Hist Auto** **1013754367**
SSW **300 CONGRESS AVE S** **N/A**
< 1/8 **TRAVIS (County), TX 78704**
0.061 mi.
323 ft. **Site 6 of 12 in cluster NA**

Actual:
452 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	ELLIOTT CARL L FILLING	GASOLINE AND OIL SERVICE STATIONS
1965	ELLIOTT CARL L SERVICE	GASOLINE STATIONS
1970	ELLIOTT CARL L SEI VICE STATION	GASOLINE STATIONS
1975	KINGSLEY AUTOMOTIVE	AUTOMOBILE REPAIRING
1975	METCALF L A SERVICE STATION BEE	GASOLINE STATIONS

LI2285 **GREGG J EARLE CLNR** **EDR Hist Cleaner** **1013785759**
East **1808 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.061 mi.
324 ft. **Site 3 of 3 in cluster LI**

Actual:
575 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	MOORE & MORRISON GRO	CLOTHES PRESSERS AND CLEANERS
1916	GREGG J EARLE CLNR	CLOTHES CLEANERS AND PRESSERS

MW2286 **ALLEN RADIATORS** **EDR Hist Auto** **1013762144**
ESE **707 ST JOHNS AVE W** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.061 mi.
324 ft. **Site 2 of 2 in cluster MW**

Actual:
726 ft.
EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1980	ALLENS RADIATOR SHOP	AUTOMOBILE RADIATOR REPAIRERS
1984	ALLEN RADIATORS	AUTOMOBILE RADIATOR REPAIRERS

LY2287 **HUMBLE PRODUCTS SERVICE** **EDR Hist Auto** **1013767474**
NE **343 CONGRESS AVE S** **N/A**
< 1/8 **AUSTIN, TX**
0.062 mi.
326 ft. **Site 4 of 6 in cluster LY**

Actual:
451 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1940	SUTHERLAND SAML S FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1965	HUMBLE PRODUCTS SERVICE	GASOLINE STATIONS
1970	REEDY G V HUMBLE SETVICE STATIO	GASOLINE STATIONS
1975	REEDY G V EXXON SERVICE STATION	GASOLINE STATIONS
1980	SHERRILL PAUL K EXXON SERV STAT	GASOLINE STATIONS
1984	SHERRILL PAUL K EXXON SERVICE S	GASOLINE STATIONS

LY2288 NE < 1/8 0.062 mi. 326 ft. — **RIVERSIDE SERVICE STA**, **343 CONGRESS AVE S**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013770476** / **N/A**

Site 5 of 6 in cluster LY

Actual: 451 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1935	RIVERSIDE SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1947	REEDYS HUMBLE SERVICE	GASOLINE AND OIL SERVICE STATIONS
1953	REEDYS HUMBLE	GASOLINE STATIONS
1958	REEDYS HUMBLE	GASOLINE STATIONS

LK2289 ESE < 1/8 0.062 mi. 328 ft. — **WEBB J E TIRES**, **608 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013773953** / **N/A**

Site 6 of 10 in cluster LK

Actual: 499 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	WEBB J E TIRES	AUTOMOBILE REPAIRERS

2290 SSW < 1/8 0.062 mi. 328 ft. — **FIRE STATION 1**, **401 E 5TH ST**, **AUSTIN, TX 78701** — **TX LPST**, **TX UST**, **TX HIST UST**, **TX ASBESTOS** — **U003566410** / **N/A**

Actual: 482 ft.

Focus Map: 11

LPST:

Name:	FIRE STATION 1
Address:	401 E 5TH ST
City,State,Zip:	AUSTIN, TX 78767
Facility ID:	0018162
LPST Id:	113612
Facility Location:	401 E 5TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/19/1998
Entered Date:	11/05/1998
Reported Date:	10/29/1998
Closure Date:	01/15/2002
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1
Coordinators RPR:	LEM
Responsible Party Name:	Not reported
Responsible Party Contact:	MARC CHILDERS
Responsible Party Address:	6301 A HAROLD CT
Responsible Party City,St,Zip:	AUSTIN, TX 78721
Responsible Party Telephone:	512/927-3266
Reported Date:	10/29/1998

FIRE STATION 1 (Continued) **U003566410**

Case Start Date:	01/15/2002
Reference Number:	RN102239019
Project Manager:	LEM

UST:

Name:	FIRE STATION 1
Address:	401 E 5TH ST
City,State,Zip:	AUSTIN, TX 787013705
AI Number:	18162
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	INACTIVE
Additional ID:	241809322002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	MARC CHILDERS,
Contact Organization Name:	FIRE STATION 1
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124720512
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	J A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227

FIRE STATION 1 (Continued) **U003566410**

Additional ID:	241809322002138
AI Number:	18162
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46974
Facility ID:	37566
Ai Number:	18162
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

FIRE STATION 1 (Continued) **U003566410**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	303
UST ID:	46974
AI Number:	18162
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

FIRE STATION 1 (Continued) **U003566410**

More Self Certification:

Self Cert ID:	7028
Cert ID:	160542
UST Comprt ID:	472526
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160545
UST Comprt ID:	472521
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160543
UST Comprt ID:	472523
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160540
UST Comprt ID:	472524
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160541
UST Comprt ID:	472525
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160544
UST Comprt ID:	472522
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported

FIRE STATION 1 (Continued) **U003566410**

UST ID:	46973
Facility ID:	37566
Ai Number:	18162
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1

FIRE STATION 1 (Continued) **U003566410**

Tank Capacity:	560
UST Comprt ID:	302
UST ID:	46973
AI Number:	18162
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7028
Cert ID:	160542
UST Comprt ID:	472526
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Self Cert ID:	7028
Cert ID:	160545
UST Comprt ID:	472521
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

FIRE STATION 1 (Continued) **U003566410**

Self Cert ID:	7028
Cert ID:	160543
UST Comprt ID:	472523
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Self Cert ID:	7028
Cert ID:	160540
UST Comprt ID:	472524
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Self Cert ID:	7028
Cert ID:	160541
UST Comprt ID:	472525
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Self Cert ID:	7028
Cert ID:	160544
UST Comprt ID:	472522
UST ID:	154567
AI Number:	18162
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37566
Additional ID:	241809322002138
Princ ID:	840354562001227
AI Number:	18162
Facility Name:	FIRE STATION 1
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COA AFD FIRE STATION #01
Address:	401 E 5TH ST

FIRE STATION 1 (Continued) **U003566410**

City,State,Zip:	AUSTIN, TX
Id UST:	189
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	FIRE STATION 01/EMS 06
Address:	401 E. 5TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2017009601
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/18/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/18/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

FIRE STATION 1 (Continued) **U003566410**

Start Date:	01/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

NJ2291 **ALLMAN JESS** **EDR Hist Auto** **1013755998**
NE **112 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.062 mi.
328 ft. **Site 2 of 4 in cluster NJ**

Actual:
471 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	MASONS FENDER SHOP	AUTOMOBILE REPAIRERS
1940	MASON FENDER	AUTOMOBILE REPAIRING
1953	ALLMAN JESS GARAGE	AUTOMOBILE REPAIRING
1958	ALLMAN JESS	AUTOMOBILE REPAIRING
1965	ALLMANS JESS GARAGE AUTO REPR G	AUTOMOBILE REPAIRING
1970	ALLMANS JESS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	ALIMANS JESS GARAGE	AUTOMOBILE REPAIRING

KY2292 **AAMCO TRANSMISSIONS** **EDR Hist Auto** **1013768091**
ESE **307 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.062 mi.
329 ft. **Site 13 of 21 in cluster KY**

Actual:
489 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	AAMCO TRANSMISSIONS	AUTOMOBILE REPAIRING
1975	A A M C 0 TRANSMISSIONS	AUTOMOBILE REPAIRING

KY2293 ESE < 1/8 0.062 mi. 329 ft. — **307 9 KNIGHT WHIPPET CO**, **307 5TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013765004** / **N/A**

Site 14 of 21 in cluster KY

Actual: 489 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	307 9 KNIGHT WHIPPET CO	AUTOMOBILE SERVICE STATIONS
1929	307 9 KNIGHT WHIPPET CO	AUTOMOBILE REPAIRERS
1929	307 9 KNIGHT WHIPPET CO	AUTOMOBILE GARAGES

KH2294 SSW < 1/8 0.062 mi. 329 ft. — **TEXAS OIL COMPANY**, **100 W 2ND ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678824** / **N/A**

Site 14 of 19 in cluster KH

Actual: 475 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	TEXAS OIL COMPANY
Address:	100 W 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0158
HID UST:	158
Inspection:	Not reported
Due:	06/01/2012

2295 WNW < 1/8 0.062 mi. 329 ft. — **WARD HAROLD**, **703 BARTON SPGS RD**, **AUSTIN, TX 78704** — **EDR Hist Auto** — **1013766889** / **N/A**

Actual: 452 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1969	WARD HAROLD	Gasoline Service Stations
1970	WARD HAROLD	Gasoline Service Stations
1971	WARD HAROLD	Gasoline Service Stations
1980	MOTORCYCLE RESURRECTION	MOTORCYCLE DEALERS AND REPAIRERS

KH2296 SSW < 1/8 0.062 mi. 329 ft. — **AVENUE GARAGE**, **205 CONGRESS AVE E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013762295** / **N/A**

Site 15 of 19 in cluster KH

Actual: 475 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	AVENUE GARAGE	AUTOMOBILE GARAGES

KZ2297 WNW < 1/8 0.062 mi. 330 ft. | **MARY DAWSON 1214 S 1ST ST AUSTIN, TX** | **TX HIST UST** | **S128729237 N/A**

Site 2 of 4 in cluster KZ

Actual: 493 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	MARY DAWSON
Address:	1214 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0292
HID UST:	292
Inspection:	Not reported
Due:	06/01/2012

KZ2298 WNW < 1/8 0.062 mi. 330 ft. | **DIANA D ZUMWALT ETAL 1214 S 1ST ST AUSTIN, TX 78704** | **TX LPST TX UST** | **U003421953 N/A**

Site 3 of 4 in cluster KZ

Actual: 493 ft.
Focus Map: 14

LPST:

Name:	ZUMWALT PROPERTY
Address:	1214 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0063598
LPST Id:	104920
Facility Location:	1214 S 1ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/02/1992
Entered Date:	11/10/1992
Reported Date:	10/08/1992
Closure Date:	01/06/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	CEB
Responsible Party Name:	Not reported
Responsible Party Contact:	DIANA ZUMWALT
Responsible Party Address:	PO BOX 161473
Responsible Party City,St,Zip:	AUSTIN, TX 78716
Responsible Party Telephone:	512/327-5243
Reported Date:	10/08/1992
Case Start Date:	01/06/1992
Reference Number:	RN101495869
Project Manager:	CEB

UST:

Name:	DIANA D ZUMWALT ETAL
Address:	1214 S 1ST ST
City,State,Zip:	AUSTIN, TX 787043037
AI Number:	63598
Facility Type:	RETAIL
Facility Begin Date:	11/10/1992

DIANA D ZUMWALT ETAL (Continued) **U003421953**

Facility Status:	INACTIVE
Additional ID:	192695222002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	DIANA ZUMWALT,
Contact Organization Name:	DIANA D ZUMWALT ETAL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123275243
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/21/1992
Signature Name/Title On Earliest Reg Form:	DIANA ZUMWALT,
Application Received Date On Earliest Reg Form:	09/15/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600783583
Owner Last Name:	DIANA D ZUMWALT ET AL
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	182695212002053
Additional ID:	192695222002053
AI Number:	63598
Owner Effective Begin Date:	11/10/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1964
Tank Registration Date:	09/15/1992

DIANA D ZUMWALT ETAL (Continued) **U003421953**

Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	146705
Facility ID:	94508
Ai Number:	63598
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

DIANA D ZUMWALT ETAL (Continued) **U003421953**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	151709
UST ID:	146705
AI Number:	63598
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	09/15/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	146706
Facility ID:	94508
Ai Number:	63598

DIANA D ZUMWALT ETAL (Continued) **U003421953**

Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	151710
UST ID:	146706

DIANA D ZUMWALT ETAL (Continued) **U003421953**

AI Number:	63598
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	09/15/1992
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	146707
Facility ID:	94508
Ai Number:	63598
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

DIANA D ZUMWALT ETAL (Continued) **U003421953**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	151711
UST ID:	146707
AI Number:	63598
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

DIANA D ZUMWALT ETAL (Continued) **U003421953**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIANA D ZUMWALT ET AL
Contact Mailing Address (Delivery):	PO BOX 161473
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78716 1473
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94508
Additional ID:	192695222002053
Princ ID:	182695212002053
AI Number:	63598
Facility Name:	DIANA D ZUMWALT ETAL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DIANA ZUMWALT/

KZ2299 WNW < 1/8 0.062 mi. 330 ft. | **OLD AUTO SHOP 1214 S 1ST ST AUSTIN, TX** | **TX HIST UST** | **S128729050 N/A**

Site 4 of 4 in cluster KZ

Actual: 493 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	OLD AUTO SHOP
Address:	1214 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0483
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2300 WNW < 1/8 0.062 mi. 330 ft. | **K AND S INTERCONNECT INC 3709-B PROMONTORY POINT DR AUSTIN, TX 78744** | **RCRA-VSQG** | **1004787091 TXR000002022**

Actual: 605 ft.
Focus Map: 8

RCRA Listings:

Date Form Received by Agency:	20010612
Handler Name:	K And S Interconnect Inc
Handler Address:	PROMONTORY POINT DR
Handler City,State,Zip:	AUSTIN, TX 78744
EPA ID:	TXR000002022
Contact Name:	CHARLES PAULAUSKY
Contact Address:	1150 N FIESTA BLVD
Contact City,State,Zip:	GILBERT, AZ 85233-2237
Contact Telephone:	480-333-1761
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PROMONTORY POINT DR
Mailing City,State,Zip:	AUSTIN, TX 78744
Owner Name:	Kulicke And Soffa Industries Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

K AND S INTERCONNECT INC (Continued) **1004787091**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20010612
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KULICKE AND SOFFA INDUSTRIES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	143 WITMER ROAD
Owner/Operator City,State,Zip:	WILLOW GROVE, PA 19090
Owner/Operator Telephone:	215-784-6000
Owner/Operator Telephone Ext:	Not reported

K AND S INTERCONNECT INC (Continued) **1004787091**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950315
Handler Name: K AND S INTERCONNECT INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010612
Handler Name: K AND S INTERCONNECT INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NG2301 **SMITH KELLY CLEANERS** **EDR Hist Cleaner** **1013784861**
WNW **209 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.062 mi.
330 ft. **Site 2 of 16 in cluster NG**

Actual:
497 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	WILLIAMS & WILLIAMS C	CLOTHES PRESSERS AND CLEANERS
1935	SMITH KELLY CLDO	CLEANERS, PRESSERS AND DYERS
1935	SMITH KELLY CLDO	CLOTHES PRESSERS AND CLEANERS
1940	SMITH KELLEY CLDO	CLOTHES PRESSERS AND CLEANERS
1947	SMITH KELLY CLEANERS	HAT CLEANERS AND BLOCKERS
1947	SMITH KELLY CLEANERS	FUR CLEANERS AND DYERS
1947	SMITH KELLY CLEANERS	CLOTHES PRESSERS AND CLEANERS

NL2302 **PHILLIPS BUILDING** **TX VCP** **S103865192**
SSW **103 E 5TH ST** **TX GCC** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.062 mi.
330 ft. **Site 1 of 5 in cluster NL**

Actual:
487 ft.

Focus Map:
11

VCP TCEQ:

Name:	PHILLIPS BUILDING
Address:	103 E 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	690
VCP Record Date:	02/02/1998
Facility Type:	AUTO DEALERSHIP
PCA Number:	31600
Project Manager:	JCARSTEN
Phase:	COMPLETED
Acres at Site:	>1
REM Program:	VCP
RN Number:	RN101055549
Former Facility Type:	Not reported
Site Address Description:	103 EAST 5TH STREET
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	02/02/1998
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	05/07/1998
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	3
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	02/02/1998
GW Target COC Class:	TPH; CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1998-03-02 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	690
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	316000
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	208/D
Latitude:	30.27

PHILLIPS BUILDING (Continued) **S103865192**

Longitude: -97.74

GCC:

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: INACTIVE GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2018
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2008
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2012

PHILLIPS BUILDING (Continued) **S103865192**

Agency: TCEQ
Section: VC
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 690
Contamination Description: TPH, SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: Not reported
New Cases: Not reported
File Number: 690
Contamination Description: TPH, SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C - Action Completed - determination that no further action is needed
Data Quality 1: Not reported
Section 5236: Not reported
Type: Not reported
Agency: TCEQ
Section: Not reported
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL

PHILLIPS BUILDING (Continued) **S103865192**

AGENCIES, 1994-2013

Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2015

Agency: TCEQ
Section: VC/VC
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2011

Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -

PHILLIPS BUILDING (Continued) **S103865192**

Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2007
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH ST
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVENTS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2016
Agency: TCEQ
Section: Not reported
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: RMD
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS

PHILLIPS BUILDING (Continued) **S103865192**

Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: 6C -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2009
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

Name: PHILLIPS BUILDING
Address: 103 EAST 5TH STREET
City,State,Zip: AUSTIN, TX
Division: REM
New Cases: Not reported
File Number: 690
Contamination Description: TPH/SOLVEN TS
Date Of Earliest Known Contamination Confirmation: Not reported
Enforcement Status - Level Of Agency Response: 0 -
Enforcement Status - Site Activity Status: -
Data Quality 1: Not reported
Section 5236: Not reported
Type: HISTORIC GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY ALL AGENCIES, 1994-2014
Agency: TCEQ
Section: VC/VCP
Year Deleted: 1998
Location: Not reported
Data Quality 2: Not reported

NJ2303 **112 14 ALLMANS JESS** **EDR Hist Auto** **1013752790**
NE **114 1ST E** **N/A**
< 1/8 **AUSTIN, TX**
0.062 mi.
330 ft. **Site 3 of 4 in cluster NJ**

Actual:
471 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	ALLMANS JESSE DAY & NIGHT GAR S	AUTOMOBILE REPAIRING
1940	ALLMANS JESSE DAY & NIGHT GAR S	GASOLINE AND OIL SERVICE STATIONS
1962	112 14 ALLMANS JESS	AUTOMOBILE REPAIRING
1980	ALLMANS JESS GARAGE	AUTOMOBILE REPAIRING

2304 WNW < 1/8 0.063 mi. 331 ft. — **BOUCHARD E A GARAGE**, **207 14TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013762543**, **N/A**

Actual: 547 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	BOUCHARD E A GARAGE	AUTOMOBILE GARAGES

NM2305 ESE < 1/8 0.063 mi. 332 ft. — **MAGNOLIA PET CO STA**, **100 31ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013769475**, **N/A**

Site 1 of 6 in cluster NM

Actual: 594 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1935	MAGNOLIA PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	VINSON RUFUS L FILLING ST	GASOLINE AND OIL SERVICE STATIONS
1947	HARRELL FRANK A FILLING STA	GASOLINE AND OIL SERVICE STATIONS

KI2306 West < 1/8 0.063 mi. 332 ft. — **BROWN JACK CLEANERS INC**, **1109 W PARMER LN**, **AUSTIN, TX 78727** — **EDR Hist Cleaner** — **1019944287**, **N/A**

Site 4 of 4 in cluster KI

Actual: 699 ft. EDR Hist Cleaner

Focus Map: 2

Year:	Name:	Type:
1992	JACK BROWN CLEANERS	Drycleaning Plants, Except Rugs
1993	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1994	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1995	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1996	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1997	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1998	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1999	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2000	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs

NN2307 WNW < 1/8 0.063 mi. 332 ft. — **AUTOMATIC TRANSMISSION SERV**, **811 PRAIRIE TRL**, **AUSTIN, TX 78758** — **EDR Hist Auto** — **1013753157**, **N/A**

Site 1 of 2 in cluster NN

Actual: 757 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1979	AUTOMATIC TRANSMISSION SV CO	Automotive Repair Shops, NEC
1980	AUTOMATIC TRANSMISSION SERV	AUTOMOBILE REPAIRING
1980	AUTOMATIC TRANSMISSION SV CO	Automotive Repair Shops, NEC
1982	AUTOMATIC TRANSMISSION SV CO	Automotive Repair Shops, NEC
1983	AUTOMATIC TRANSMISSION SV CO	Automotive Repair Shops, NEC

AUTOMATIC TRANSMISSION SERV (Continued) **1013753157**

1984	AUTOMATIC TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1985	AUTOMOTIVE TRANSMISSN SRVC CO	Automotive Repair Shops, NEC
1986	AUTOMOTIVE TRANSMISSION SV CO	Automotive Repair Shops, NEC
1987	AUTOMOTIVE TRANSMISSION SV CO	Automotive Repair Shops, NEC
1988	AUTOMOTIVE TRANSMISSION SV CO	Automotive Repair Shops, NEC
1989	AUTOMOTIVE TRANSMISSION SVC CO	Automotive Transmission Repair Shops
1990	AUTOMATIC TRANSMISSION SERVICE	AUTOMOBILE REPAIRING
1990	AUTOMOTIVE TRANSMISSION SVC CO	Automotive Transmission Repair Shops
1991	AUTOMOTIVE TRANSMISSION SVC CO	Automotive Transmission Repair Shops
1992	AUTOMOTIVE TRANSMISSION SVC CO	Automotive Transmission Repair Shops
1993	JOHNTONS TRANSMISSION SERVICE	Automotive Transmission Repair Shops
1994	JOHNTONS TRANSMISSION SERVICE	Automotive Transmission Repair Shops
1995	JOHNTONS TRANSMISSION SERVICE	Automotive Transmission Repair Shops
1996	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
1996	JOHNTONS TRANSMISSION SERVICE	Automotive Transmission Repair Shops
1997	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
1997	JOHNTONS TRANSMISSION SERVICE	Automotive Transmission Repair Shops
1998	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
1999	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2000	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2001	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2002	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2003	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2004	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2005	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2006	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2007	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops
2008	JOHNSTON WP ATMTC TRNSMISSIONS	Automotive Transmission Repair Shops

---

LC2308 **EXXON 6 8082** **TX UST** **U001271548**
ESE **2324 N ST MARYS** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.063 mi.
333 ft. **Site 2 of 2 in cluster LC**

Actual:
535 ft.

Focus Map:
11

UST:

Name:	EXXON 6 8082
Address:	2324 N ST MARYS
City,State,Zip:	AUSTIN, TX 78745
AI Number:	38970
Facility Type:	RETAIL
Facility Begin Date:	01/12/1987
Facility Status:	INACTIVE
Additional ID:	148477152002133
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	BEXAR
Site Location (Tceq Region):	13
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	EXXON 6 8082
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

EXXON 6 8082 (Continued) **U001271548**

Contact Telephone:	5127320080
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/08/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,ENG SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600123939
Owner Last Name:	EXXON MOBIL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	679380312001134
Additional ID:	148477152002133
AI Number:	38970
Owner Effective Begin Date:	01/12/1987
State Tax ID:	11354090059
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	102940
Facility ID:	48518
Ai Number:	38970
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/27/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

EXXON 6 8082 (Continued) **U001271548**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	39572
UST ID:	102940
AI Number:	38970
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

EXXON 6 8082 (Continued) **U001271548**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	102941
Facility ID:	48518
Ai Number:	38970
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/27/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

EXXON 6 8082 (Continued) **U001271548**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	39573
UST ID:	102941
AI Number:	38970
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

EXXON 6 8082 (Continued) **U001271548**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	102942
Facility ID:	48518
Ai Number:	38970
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/27/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

EXXON 6 8082 (Continued) **U001271548**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	39574
UST ID:	102942
AI Number:	38970
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

EXXON 6 8082 (Continued) **U001271548**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	EXXON MOBIL CORPORATION
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	48518
Additional ID:	148477152002133
Princ ID:	679380312001134
AI Number:	38970
Facility Name:	EXXON 6 8082
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HEATHER GILMORE/

NO2309 **AUSTIN COMPLETE AUTO REFINISH** **RCRA NonGen / NLR** **1000412187**
WNW **821 BRENTWOOD** **FINDS** **TXD981151939**
< 1/8 **AUSTIN, TX 78757** **ECHO**
0.063 mi. **TX Ind. Haz Waste**
334 ft. **Site 1 of 2 in cluster NO** **TX CENTRAL REGISTRY**

Actual:
712 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Complete Auto Refinish
Handler Address:	BRENTWOOD
Handler City,State,Zip:	AUSTIN, TX 78757
EPA ID:	TXD981151939
Contact Name:	DUSTY WOMDLE
Contact Address:	BRENTWOOD
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Telephone:	512-467-6606
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	BRENTWOOD
Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Name:	Austin Complete Auto Refinish
Owner Type:	Private
Operator Name:	Austin Complete Auto Refinish
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	AUSTIN COMPLETE AUTO REFINISH
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	821 BRENTWOOD
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	512-467-6606
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DUSTY WOMBLE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AUSTIN COMPLETE AUTO REFINISH
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	821 BRENTWOOD
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	512-467-6606
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19860128
Handler Name:	AUSTIN COMPLETE AUTO REFINISHING
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010823
Handler Name:	AUSTIN COMPLETE AUTO REFINISH
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005087681

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412187
Registry ID:	110005087681
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005087681
Name:	AUSTIN COMPLETE AUTO REFINISH
Address:	821 BRENTWOOD
City,State,Zip:	AUSTIN, TX 78757

Ind. Haz Waste:

Name:	AUSTIN COMPLETE AUTO REFINISH
Address:	821 BRENTWOOD ST
City,State,Zip:	AUSTIN, TX 78757
Permit Number:	Not reported
Registration Number:	69464
Registration Initial Notification Date:	03/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981151939
Primary NAICS Code:	Not reported
Status Change Date:	19860307
Land Type:	PRIVATE
Description of Facility Site Location:	821 Brentwood, Austin, TX
Site Primary Standard Industrial Code:	Not reported

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN COMPLETE AUTO REFINISH
Contact Name:	DUSTY WOMDLE
Contact Telephone Number:	512-4676606
Mailing Address:	821 BRENTWOOD ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787573030
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24342
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030519
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN COMPLETE AUTO REFINISH
Operator Address:	821 BRENTWOOD ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78757
Operator Country:	UNITED STA
Operator Telephone:	1-512-4676606
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN COMPLETE AUTO REFINISH
Owner Mailing Address:	821 BRENTWOOD ST
Owner Mailing Address 2:	Not reported

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Country:	UNITED STA
Owner Telephone:	1-512-4676606
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	821 BRENTWOOD ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4676606
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	821 BRENTWOOD ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4676606
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DUSTY WOMDLE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	821 BRENTWOOD ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4676606
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100652346
Name:	AUSTIN COMPLETE AUTO REFINISH
Address:	821 BRENTWOOD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-3030
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600361919
Customer Name:	AUSTIN COMPLETE AUTO REFINISH
Customer Legal Name:	Austin Complete Auto Refinish

AUSTIN COMPLETE AUTO REFINISH (Continued) **1000412187**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	821 Brentwood, Austin, TX

Regulated Entity Number:	RN100652346
Name:	AUSTIN COMPLETE AUTO REFINISH
Address:	821 BRENTWOOD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-3030
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600361919
Customer Name:	AUSTIN COMPLETE AUTO REFINISH
Customer Legal Name:	Austin Complete Auto Refinish
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	821 Brentwood, Austin, TX

NO2310 **B & B BODY & PAINT REPAIR** **EDR Hist Auto** **1013771398**
WNW **821 BRANTWOOD ST** **N/A**
< 1/8 **TRAVIS (County), TX 78757**
0.063 mi.
334 ft. **Site 2 of 2 in cluster NO**

Actual:
712 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1990	B & B BODY & PAINT REPAIR	AUTOMOBILE REPAIRING

2311 **MINGOS BODY SHOP** **RCRA NonGen / NLR** **1000236125**
WNW **811 MCPAUL** **FINDS** **TXD981145055**
< 1/8 **AUSTIN, TX 78758** **ECHO**
0.063 mi.
334 ft.

Actual:
737 ft.

RCRA Listings:

Focus Map:
3

Date Form Received by Agency:	20010727
Handler Name:	Mingos Body Shop
Handler Address:	MCPAUL
Handler City,State,Zip:	AUSTIN, TX 78758
EPA ID:	TXD981145055
Contact Name:	VERA RICHARD
Contact Address:	MCPHAUL ST
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Telephone:	512-836-0600
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

MINGOS BODY SHOP (Continued) **1000236125**

EPA Region:	06
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	MCPHAUL ST
Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Name:	Mingos Body Shop
Owner Type:	Other
Operator Name:	Mingos Body Shop
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

MINGOS BODY SHOP (Continued) **1000236125**

Hazardous Waste Summary:

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Operator
Owner/Operator Name: MINGOS BODY SHOP
Legal Status: Other
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 815 MCPHAUL ST
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-0600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DOMINGO VERA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MINGOS BODY SHOP
Legal Status: Other
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 815 MCPHAUL ST
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-0600
Owner/Operator Telephone Ext: Not reported

MINGOS BODY SHOP (Continued) **1000236125**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date:	19850927
Handler Name: MINGOS BODY SHOP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name: MINGOS BODY SHOP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005085610

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

MINGOS BODY SHOP (Continued) **1000236125**

ECHO:

Envid:	1000236125
Registry ID:	110005085610
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005085610
Name:	MINGOS BODY SHOP
Address:	811 MCPAUL
City,State,Zip:	AUSTIN, TX 78758

2312 **LYNN SMITH** **TX HIST UST** **S111678727**
East **300 W DEAN KEETON ST** **N/A**
< 1/8 **AUSTIN, TX**
0.063 mi.
334 ft.

Actual:
603 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	LYNN SMITH
Address:	300 W DEAN KEETON ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0266
HID UST:	266
Inspection:	05/14/2009
Due:	05/14/2012

KY2313 **ANDYS AUTO ELECTRIC REPR** **EDR Hist Auto** **1013774342**
ESE **305 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.064 mi.
336 ft. **Site 15 of 21 in cluster KY**

Actual:
489 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1965	ANDYS AUTO ELECTRIC REPR	AUTOMOBILE REPAIRING

KY2314 **S & D AUTO ELECTRIC REPR** **EDR Hist Auto** **1013762225**
ESE **305 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.064 mi.
336 ft. **Site 16 of 21 in cluster KY**

Actual:
489 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1970	ANDYS AUTO ELECTRIC REPR	AUTOMOBILE REPAIRING
1975	S & D AUTO ELECTRIC REPR	AUTOMOBILE REPAIRING

KY2315 **ANDYS AUTO ELEC REPR** **EDR Hist Auto** **1013753065**
ESE **305 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.064 mi.
336 ft. **Site 17 of 21 in cluster KY**

Actual:
489 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	ANDYS AUTO ELEC	AUTOMOBILE REPAIRING
1962	ANDYS AUTO ELEC REPR	AUTOMOBILE REPAIRING

NP2316 **I DEAL TIRE** **TX SPILLS** **S102748656**
NE **2415 BASTROP HWY E** **TX Ind. Haz Waste** **N/A**
< 1/8 **DEL VALLE, TX 78617** **TX CENTRAL REGISTRY**
0.064 mi.
336 ft. **Site 1 of 2 in cluster NP**

Actual:
500 ft.

Focus Map:
20

SPILLS:

Name:	3900 RIVER PLACE BLVD., OFF 2222
Address:	3900 RIVER PLACE BLVD., OFF 2222
City,State,Zip:	TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	11/17/1994
Seq Num:	7
Responsible Party Name:	J-V DIRT & LOAM
Responsible Party Address:	2415 BASTROP HWY
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78617
Responsible Party Telephone:	5122767810
Substance:	DIESEL
Material Code:	1040
Media Affected:	Not reported
Permit Number:	NONE
District:	11
Origin:	005
Cause:	002
Basin Code:	1403
Notify Date:	Not reported
Adequate Clean:	001
Classification:	003
Basin Name:	COLORADO
Water Affected:	LAKE AUSTIN
Amnt Spilled:	89 GAL
Amnt in Water:	NONE GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	TWC
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	K. OTTO
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported

I DEAL TIRE (Continued) **S102748656**

Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

Ind. Haz Waste:

Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 78617
Permit Number:	Not reported
Registration Number:	61805
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	2415 Bastrop Hwy, Del Valle, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	I DEAL TIRE
Contact Name:	BARBARA CRAWFORD
Contact Telephone Number:	512-3853802
Mailing Address:	2415 BASTROP HWY E
Mailing Address2:	Not reported
Mailing City,State,Zip:	DEL VALLE, TX 786172202
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20145
Site Owner Tax ID:	0
Site Location Latitude:	-00.000

I DEAL TIRE (Continued) **S102748656**

Site Location Longitude:	-000.000
Last Update to NOR Data:	20040105
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	I DEAL TIRE
Operator Address:	2415 BASTROP HWY E
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	DEL VALLE, TX 78617
Operator Country:	UNITED STA
Operator Telephone:	1-512-3853802
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	I DEAL TIRE
Owner Mailing Address:	2415 BASTROP HWY E
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	DEL VALLE, TX 78617
Owner Country:	UNITED STA
Owner Telephone:	1-512-3853802
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2415 BASTROP HWY E
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	DEL VALLE, TX 78617
Contact Phone:	1-512-3853802
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported

I DEAL TIRE (Continued) **S102748656**

Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2415 BASTROP HWY E
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	DEL VALLE, TX 78617
Contact Phone:	1-512-3853802
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BARBARA CRAWFORD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	2415 BASTROP HWY E
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	DEL VALLE, TX 78617
Contact Phone:	1-512-3853802
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600349559
Customer Name:	I DEAL TIRE
Customer Legal Name:	I Deal Tires Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX

Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601585961
Customer Name:	RAYMOND RAMSEY & JERRY R REED
Customer Legal Name:	Raymond Ramsey & Jerry R. Reed
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/8/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

I DEAL TIRE (Continued) **S102748656**

Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX
Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605030733
Customer Name:	IDEAL TIRES
Customer Legal Name:	Ideal Tires
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX
Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600349559
Customer Name:	I DEAL TIRE
Customer Legal Name:	I Deal Tires Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX
Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601585961
Customer Name:	RAYMOND RAMSEY & JERRY R REED
Customer Legal Name:	Raymond Ramsey & Jerry R. Reed
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/8/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX
Regulated Entity Number:	RN100639046

I DEAL TIRE (Continued) **S102748656**

Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605030733
Customer Name:	IDEAL TIRES
Customer Legal Name:	Ideal Tires
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX

Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600349559
Customer Name:	I DEAL TIRE
Customer Legal Name:	I Deal Tires Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX

Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported
City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601585961
Customer Name:	RAYMOND RAMSEY & JERRY R REED
Customer Legal Name:	Raymond Ramsey & Jerry R. Reed
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1/8/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX

Regulated Entity Number:	RN100639046
Name:	I DEAL TIRE
Address:	2415 BASTROP HWY E
Address 2:	Not reported

I DEAL TIRE (Continued) **S102748656**

City,State,Zip:	DEL VALLE, TX 78617-2202
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605030733
Customer Name:	IDEAL TIRES
Customer Legal Name:	Ideal Tires
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2415 Bastrop Hwy, Del Valle, TX

NP2317 **RAYMOND RAMSEY & JERRY R REED** **TX UST** **U003421972**
NE **2415 BASTROP HWY E** **N/A**
< 1/8 **DEL VALLE, TX 78617**
0.064 mi.
336 ft. **Site 2 of 2 in cluster NP**

Actual:
500 ft.

Focus Map:
20

UST:

Name:	RAYMOND RAMSEY & JERRY R REED
Address:	2415 BASTROP HWY E
City,State,Zip:	DEL VALLE, TX 786172202
AI Number:	38370
Facility Type:	RETAIL
Facility Begin Date:	01/08/1987
Facility Status:	INACTIVE
Additional ID:	106406952003091
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78617
Contact Name/Title:	RAYMOND RAMSEY,
Contact Organization Name:	RAYMOND RAMSEY & JERRY R REED
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124441941
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	TIM RAMSEY,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601585961
Owner Last Name:	RAYMOND RAMSEY & JERRY R REED

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	113406942003091
Additional ID:	106406952003091
AI Number:	38370
Owner Effective Begin Date:	01/08/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1965
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101129
Facility ID:	95529
Ai Number:	38370
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/17/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	162180
UST ID:	101129
AI Number:	38370
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1965
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101130
Facility ID:	95529
Ai Number:	38370
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/17/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	162181
UST ID:	101130
AI Number:	38370
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1965
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101131
Facility ID:	95529
Ai Number:	38370
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/17/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	162182
UST ID:	101131
AI Number:	38370
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

RAYMOND RAMSEY & JERRY R REED (Continued) **U003421972**

Facility Billing Contacts:

Contact Organization Name:	RAMSEY RAYMOND AND REED JERRY R
Contact Mailing Address (Delivery):	PO BOX 18463
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78760 8463
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95529
Additional ID:	106406952003091
Princ ID:	113406942003091
AI Number:	38370
Facility Name:	RAYMOND RAMSEY & JERRY R REED
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RAYMOND RAMSEY/

NA2318 **LINDHOLM GARAGE** **EDR Hist Auto** **1013766710**
SSW **219 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.064 mi.
337 ft. **Site 7 of 12 in cluster NA**

Actual:
453 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	LINDHOLM GARAGE	AUTOMOBILE REPAIRING

NG2319 **CAPITAL CITY AUTO CO** **EDR Hist Auto** **1013753684**
WNW **211 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.064 mi.
337 ft. **Site 3 of 16 in cluster NG**

Actual:
497 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1911	CAPITAL CITY AUTO CO	AUTOMOBILE GARAGES

LA2320 **JOHNSON ARVEL G** **EDR Hist Auto** **1013766741**
West **510 COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.064 mi.
338 ft. **Site 12 of 15 in cluster LA**

Actual:
494 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	510 12 STUMPF JOS & SONS BLKSMI	AUTOMOBILE REPAIRERS
1940	JOHNSON ARVEL G	AUTOMOBILE REPAIRING

NQ2321 ESE < 1/8 0.064 mi. 338 ft. — **WARREN CLNRS**, **3209 SPEEDWAY**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013779702** / **N/A**

Site 1 of 2 in cluster NQ

Actual: 602 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1953	WARREN CLNRS	CLEANERS AND DYERS
1958	WARRENS CLNS	CLEANERS AND DYERS

NR2322 SE < 1/8 0.064 mi. 338 ft. — **AUSTIN SHEET METAL SHOP**, **715 W POWELL LN**, **AUSTIN, TX** — **TX HIST UST** — **S111678566** / **N/A**

Site 1 of 2 in cluster NR

Actual: 739 ft.

Focus Map: 6

HIST UST AUSTIN:

Name:	AUSTIN SHEET METAL SHOP
Address:	715 W POWELL LN
City,State,Zip:	AUSTIN, TX
Id UST:	H0777
HID UST:	777
Inspection:	Not reported
Due:	06/01/2012

NQ2323 ESE < 1/8 0.064 mi. 338 ft. — **WARREN J A CLC CLNR**, **3207 SPEEDWAY**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013778332** / **N/A**

Site 2 of 2 in cluster NQ

Actual: 602 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1935	WARREN J A CLC CLNR	CLOTHES PRESSERS AND CLEANERS
1940	WARREN J A CLOTHES	CLOTHES PRESSERS AND CLEANERS
1947	WARREN JOHN A CLO CLNR	CLOTHES PRESSERS AND CLEANERS

LJ2324 WNW < 1/8 0.064 mi. 338 ft. — **REBREU BODY & FRAME**, **822 KRAMER LN**, **AUSTIN, TX 78758** — **RCRA NonGen / NLR**, **FINDS**, **ECHO**, **TX Ind. Haz Waste** — **1000356798** / **TXD982283772**

Site 2 of 2 in cluster LJ

Actual: 764 ft.

Focus Map: 3

RCRA Listings:

Date Form Received by Agency:	20200711
Handler Name:	Rebreu Body & Frame
Handler Address:	822 KRAMER LN
Handler City,State,Zip:	AUSTIN, TX 78758-4348
EPA ID:	TXD982283772
Contact Name:	JOHN REID
Contact Address:	822 KRAMER LN
Contact City,State,Zip:	AUSTIN, TX 78758-4348
Contact Telephone:	512-836-4498

REBREU BODY & FRAME (Continued) **1000356798**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	822 KRAMER LN
Mailing City,State,Zip:	AUSTIN, TX 78758-4348
Owner Name:	Abrew James
Owner Type:	Private
Operator Name:	Abrew James
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200729
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

REBREU BODY & FRAME (Continued) **1000356798**

Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent

REBREU BODY & FRAME (Continued) **1000356798**

Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U359
Waste Description: Ethanol, 2-Ethoxy- (Or) Ethylene Glycol Monoethyl Ether

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: ABREW JAMES
Legal Status: Private
Date Became Current: 18000101
Date Ended Current: Not reported
Owner/Operator Address: 822 KRAMER LN
Owner/Operator City,State,Zip: AUSTIN, TX 78758-4348
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: PP
Owner/Operator Name: ABREWJAMES
Legal Status: Private
Date Became Current: 20030522
Date Ended Current: 20150727
Owner/Operator Address: 822 KRAMER LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CALIBER COLLISION CENTER
Legal Status: Private
Date Became Current: 20150727
Date Ended Current: Not reported
Owner/Operator Address: 401 E CORPORATE DR STE 150
Owner/Operator City,State,Zip: LEWISVILLE, TX 75057
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator

REBREU BODY & FRAME (Continued) **1000356798**

Owner/Operator Name: ABREW JAMES
Legal Status: Private
Date Became Current: 18000101
Date Ended Current: Not reported
Owner/Operator Address: 822 KRAMER LN
Owner/Operator City,State,Zip: AUSTIN, TX 78758-4348
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ABREWJAMES
Legal Status: Private
Date Became Current: 20030522
Date Ended Current: Not reported
Owner/Operator Address: 822 KRAMER LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ABREWJAMES
Legal Status: Private
Date Became Current: 20030522
Date Ended Current: Not reported
Owner/Operator Address: 822 KRAMER LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CALIBER COLLISION CENTER
Legal Status: Private
Date Became Current: 20150727
Date Ended Current: Not reported
Owner/Operator Address: 401 E CORPORATE DR STE 150
Owner/Operator City,State,Zip: LEWISVILLE, TX 75057
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JAMES ABREW
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 822 KRAMER LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78758-0000
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

REBREU BODY & FRAME (Continued) **1000356798**

Owner/Operator Email: Not reported

Owner/Operator Indicator: PO
Owner/Operator Name: ABREWJAMES
Legal Status: Private
Date Became Current: 20030522
Date Ended Current: 20150727
Owner/Operator Address: 822 KRAMER LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78758
Owner/Operator Telephone: 512-836-4498
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870917
Handler Name: REBREU BODY & FRAME
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030522
Handler Name: REBREU BODY & FRAME INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150812
Handler Name: CALIBER COLLISION CENTERS - AUSTIN KRAMER LN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200711
Handler Name: REBREU BODY & FRAME
Federal Waste Generator Description: Not a generator, verified

REBREU BODY & FRAME (Continued) **1000356798**

State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811121
NAICS Description:	AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005101040

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000356798
Registry ID:	110005101040
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005101040
Name:	REBREU BODY & FRAME
Address:	822 KRAMER LN
City,State,Zip:	AUSTIN, TX 78758

Ind. Haz Waste:

Name:	REBREU BODY & FRAME
Address:	822 KRAMER LN
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	74336
Registration Initial Notification Date:	08/31/1987
Registration Last Amendment Date:	07/11/2020
EPA Identification:	TXD982283772
Primary NAICS Code:	811121
Status Change Date:	19870831

REBREU BODY & FRAME (Continued) **1000356798**

Land Type:	PRIVATE
Description of Facility Site Location:	822 Kramer Lane, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	ABREW, JAMES
Contact Name:	JOHN REID
Contact Telephone Number:	512-8364498
Mailing Address:	822 KRAMER LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787584348
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	28715
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200720
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	JAMES ABREW
Operator Address:	822 KRAMER LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78758
Operator Country:	UNITED STA

REBREU BODY & FRAME (Continued) **1000356798**

Operator Telephone:	1-512-8364498
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JAMES ABREW
Owner Mailing Address:	822 KRAMER LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Country:	UNITED STA
Owner Telephone:	1-512-8364498
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	11
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Safety Kleen parts washer
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	6
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

REBREU BODY & FRAME (Continued) **1000356798**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Immersion parts cleaner
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum storage area by paint booth
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

REBREU BODY & FRAME (Continued) **1000356798**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Aqueous solution brake cleaning machine
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum storage area at north end of building
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Five gallon bucket storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported

REBREU BODY & FRAME (Continued) **1000356798**

Deed Recording Date:	Not reported
Unit Number:	007
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Waste solvent distillation unit. Still bottoms disposed off-site.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970630
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	822 KRAMER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8364498
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JOHN REID
Contact Title:	Not reported
Contact Role:	PRICONT
Contact Address:	822 KRAMER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8364498
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	162430
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001296H
Waste Code Status:	INACTIVE
Waste Form:	296

REBREU BODY & FRAME (Continued) **1000356798**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste antifreeze/Drainal from automobiles in shop/1997
Standard Industrial Code:	75320
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139955
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solvent
Standard Industrial Code:	75320
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012255
Primary NAICS Code:	811121
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161508
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0

REBREU BODY & FRAME (Continued) **1000356798**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Used lacquer thinner - Used enamel reducer - paint booth ends/Generated during c
Standard Industrial Code:	75320
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139956
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Immersion cleaner
Standard Industrial Code:	75320
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012255
Primary NAICS Code:	811121
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139957

REBREU BODY & FRAME (Continued) **1000356798**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0638310H
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint booth filters
Standard Industrial Code:	Not reported
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169415254
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W310
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161507
Texas Waste Code:	Not reported
Texas Waste Code 2:	0839102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous brake cleaning solution - late 1995/Used to clean dust off brake parts b
Standard Industrial Code:	75320
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported

REBREU BODY & FRAME (Continued) **1000356798**

Mailing Address:	822 KRAMER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78758
AR Number:	0000306308
Principal Name:	ABREW, JAMES
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	822 KRAMER LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78758
AR Number:	0000306308
Principal Name:	ABREW, JAMES
Attention Name:	Not reported
Attention Suffix:	NWG

KT2325 **BARRS BLUE BONNET** **EDR Hist Cleaner** **1013785331**
WNW **213 8TH W** **N/A**
< 1/8 **3D WARD, TX**
0.064 mi.
339 ft. **Site 4 of 4 in cluster KT**

Actual:
528 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1940	BARRS BLUE BONNET	CLOTHES PRESSERS AND CLEANERS

KP2326 **SODIES AUTO REPAIR** **EDR Hist Auto** **1013761678**
SW **405 NECHES ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.064 mi.
339 ft. **Site 5 of 7 in cluster KP**

Actual:
476 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	SODIES AUTO REPAIR	AUTOMOBILE REPAIRING
1970	SODIES AUTO REPAIR	AUTOMOBILE REPAIRING

KP2327 **CAPITAL SPRING & BRAKE** **EDR Hist Auto** **1013753686**
SW **403 NECHES ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.065 mi.
341 ft. **Site 6 of 7 in cluster KP**

Actual:
476 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	NICHOLS GARAGE	AUTOMOBILE REPAIRERS
1940	NICHOLS GARAGE	AUTOMOBILE REPAIRING
1947	NICHOLS GARAGE	AUTOMOBILE REPAIRING

CAPITAL SPRING & BRAKE (Continued) **1013753686**

1984	CAPITAL SPRING & BRAKE	AUTOMOBILE REPAIRING
1990	CARTERS AUTOMOTIVE	AUTOMOBILE REPAIRING
1992	CARTERS TRANSMISSION	General Automotive Repair Shops
1993	CARTERS TRANSMISSION	General Automotive Repair Shops
1994	CARTERS TRANSMISSION	General Automotive Repair Shops
1995	CARTERS TRANSMISSION	General Automotive Repair Shops
1996	CARTERS TRANSMISSION INC	General Automotive Repair Shops
1997	CARTERS TRANSMISSION INC	General Automotive Repair Shops
1998	CARTERS TRANSMISSION INC	General Automotive Repair Shops
1999	CARTERS TRANSMISSION INC	General Automotive Repair Shops
2000	CARTERS TRANSMISSION INC	General Automotive Repair Shops

---

NJ2328 **NW COR SWEARINGEN ARM** **EDR Hist Auto** **1013772106**
NE **120 1ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
341 ft. **Site 4 of 4 in cluster NJ**

Actual:
471 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	COR JOHNS BROS AUTO DIRS	AUTOMOBILE REPAIRERS
1940	NW COR SWEARINGEN ARM	AUTOMOBILE REPAIRERS

KC2329 **BUMPER-TO-BUMPER CAR PARTS AND MACHINE** **TX Ind. Haz Waste** **S102753977**
WNW **201 SAN JACINTO BLVD** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.065 mi.
341 ft. **Site 2 of 3 in cluster KC**

Actual:
473 ft.

Ind. Haz Waste:

Focus Map:
11

Name:	BUMPER-TO-BUMPER CAR PARTS AND MACHINE
Address:	201 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72161
Registration Initial Notification Date:	01/23/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981902612
Primary NAICS Code:	Not reported
Status Change Date:	19870123
Land Type:	PRIVATE
Description of Facility Site Location:	201 San Jacinito, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS

BUMPER-TO-BUMPER CAR PARTS AND MACHINE (Continued) **S102753977**

Company Name:	BUMPER-TO-BUMPER CAR PARTS AND
Contact Name:	DAN CURTISS
Contact Telephone Number:	512-4775967
Mailing Address:	201 SAN JACINTO BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787014027
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26608
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	BUMPER-TO-BUMPER CAR PARTS AND
Operator Address:	201 SANJACINTO BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4775967
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BUMPER-TO-BUMPER CAR PARTS AND
Owner Mailing Address:	201 SANJACINTO BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4775967
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

BUMPER-TO-BUMPER CAR PARTS AND MACHINE (Continued) **S102753977**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	18
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	201 SANJACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4775967
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	201 SANJACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4775967
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	DAN CURTISS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	201 SANJACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701

BUMPER-TO-BUMPER CAR PARTS AND MACHINE (Continued) **S102753977**

Contact Phone: 1-512-4775967
Contact Fax: Not reported
Contact Email: Not reported

KC2330 **BUMPER-TO-BUMPER CAR PARTS AND** **RCRA NonGen / NLR** **1000346290**
WNW **201 SAN JACINITO** **FINDS** **TXD981902612**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.065 mi.
341 ft. **Site 3 of 3 in cluster KC**

Actual:
473 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Bumper-To-Bumper Car Parts And
Handler Address:	SAN JACINITO
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981902612
Contact Name:	DAN CURTISS
Contact Address:	SAN JACINTO
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-477-5967
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	SAN JACINTO
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Bumper-To-Bumper Car Parts And
Owner Type:	Private
Operator Name:	Bumper-To-Bumper Car Parts And
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

BUMPER-TO-BUMPER CAR PARTS AND (Continued) **1000346290**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: BUMPER-TO-BUMPER CAR PARTS AND	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	201 SAN JACINTO
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-477-5967
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: R G MUELLER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

BUMPER-TO-BUMPER CAR PARTS AND (Continued) **1000346290**

Owner/Operator Name: BUMPER-TO-BUMPER CAR PARTS AND
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 201 SAN JACINTO
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-477-5967
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870130
Handler Name: BUMPER TO BUMPER CP & M
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: BUMPER-TO-BUMPER CAR PARTS AND
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005097661

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

BUMPER-TO-BUMPER CAR PARTS AND (Continued) **1000346290**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000346290
Registry ID:	110005097661
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005097661
Name:	BUMPER-TO-BUMPER CAR PARTS AND
Address:	201 SAN JACINITO
City,State,Zip:	AUSTIN, TX 78701

NS2331 **PROPOSED CHICK FIL A RESTAURANT 2992** **TX VCP** **S111382720**
West **503 W MARTIN LUTHER KING JR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.065 mi.
342 ft. **Site 1 of 4 in cluster NS**

Actual:
550 ft.

Focus Map:
11

VCP TCEQ:

Name:	PROPOSED CHICK FIL A RESTAURANT 2992
Address:	503 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2468
VCP Record Date:	12/09/2011
Facility Type:	RETAIL
PCA Number:	34661
Project Manager:	JBECKAGE
Phase:	COMPLETED
Acres at Site:	0.59
REM Program:	VCP
RN Number:	RN106313539
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	12/06/2011
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	09/11/2013
Standards:	Not reported

PROPOSED CHICK FIL A RESTAURANT 2992 (Continued) **S111382720**

Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	12/06/2011
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2012-01-23 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2468
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	346610
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	30.28
Longitude:	-97.74

LU2332 **7-ELEVEN STORE 36656** **TX LPST** **U003040311**
WNW **620 W 29TH ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.065 mi. **TX ASBESTOS**
342 ft. **Site 2 of 5 in cluster LU** **TX Financial Assurance**
TX GCC

Actual:
598 ft.

Focus Map:
8

LPST:

Name:	7 ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	119478
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	11/12/2013
Entered Date:	10/08/2014
Reported Date:	11/12/2013
Closure Date:	11/02/2015
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	11/12/2013
Case Start Date:	11/02/2015
Reference Number:	RN102369428
Project Manager:	SDUNAHOO

7-ELEVEN STORE 36656 (Continued) **U003040311**

UST:

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 787053618
AI Number:	39556
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	INACTIVE
Additional ID:	482740612002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 36656
Contact Mailing Address1:	620 W 29TH ST
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787053618
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/18/2013
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,
Application Received Date On Earliest Reg Form:	12/19/2013
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	961346052007212
Additional ID:	482740612002149
Ai Number:	39556
Operator CN:	CN603223793
Operator Name:	THOMAS PETROLEUM LLC
Operator Effective Begin Date:	12/28/2012
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	482740612002149
AI Number:	39556
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	61076
Cert ID:	63059
AI Number:	39556
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63058
AI Number:	39556
Self Certification Date:	02/20/2012
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN STORE 36656 (Continued) **U003040311**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63057
AI Number:	39556
Self Certification Date:	02/28/2011
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63056
AI Number:	39556
Self Certification Date:	02/15/2010
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63055
AI Number:	39556
Self Certification Date:	02/23/2009
Signature Name/Title:	JEFFREY JOHANSON AUTH AGT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN STORE 36656 (Continued) **U003040311**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63054
AI Number:	39556
Self Certification Date:	02/26/2008
Signature Name/Title:	BILL THOMAS REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63053
AI Number:	39556
Self Certification Date:	01/09/2007
Signature Name/Title:	BILL THOMAS AUTHORIZED REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63052
AI Number:	39556
Self Certification Date:	01/08/2007
Signature Name/Title:	BILL THOMAS AUTHORIZED REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

7-ELEVEN STORE 36656 (Continued) **U003040311**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63051
AI Number:	39556
Self Certification Date:	04/03/2006
Signature Name/Title:	DOUGLAS SCHRAM OPERATIONS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63050
AI Number:	39556
Self Certification Date:	04/12/2005
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63049
AI Number:	39556
Self Certification Date:	02/03/2004
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN STORE 36656 (Continued) **U003040311**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63048
AI Number:	39556
Self Certification Date:	02/02/2004
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63047
AI Number:	39556
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	63046
AI Number:	39556
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

7-ELEVEN STORE 36656 (Continued) **U003040311**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61076
Cert ID:	62796
AI Number:	39556
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	10/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104579
Facility ID:	61076
Ai Number:	39556
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/13/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

7-ELEVEN STORE 36656 (Continued) **U003040311**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8081
UST Comprt ID:	54679
UST ID:	104579
AI Number:	39556
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	10/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104580
Facility ID:	61076
Ai Number:	39556
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/13/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8081
UST Comprt ID:	54680
UST ID:	104580
AI Number:	39556
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	12/23/2003
Tank Registration Date:	02/24/2004
Number of Compartments:	2
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	202775
Facility ID:	61076
Ai Number:	39556
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/08/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/23/2004

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	54682
UST ID:	202775
AI Number:	39556
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

7-ELEVEN STORE 36656 (Continued) **U003040311**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/23/2003
Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	54683
UST ID:	202775
AI Number:	39556
Compartment ID:	B
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/23/2003
Install Date:	12/23/2003
Tank Registration Date:	02/24/2004
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P

7-ELEVEN STORE 36656 (Continued) **U003040311**

UST ID:	202774
Facility ID:	61076
Ai Number:	39556
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/08/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/23/2004

Compartment Records:

Tank ID:	3

7-ELEVEN STORE 36656 (Continued) **U003040311**

Tank Capacity:	8000
UST Comprt ID:	54681
UST ID:	202774
AI Number:	39556
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/23/2003

Construction Notification:

NOC ID:	24607
Facility ID:	61076
AI Number:	39556
Application Received Date:	08/29/2013
Scheduled Construction Date:	10/07/2013
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	08/29/2013
Signature Date On Form:	08/28/2013
Signature Name On Form:	HOLLY FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVAL OF (2) 8,000 GAL DW UST'S, PIPING & VENTS.

NOC ID:	7036
Facility ID:	61076
AI Number:	39556
Application Received Date:	10/30/2003
Scheduled Construction Date:	11/11/2003
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M31030006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	08/29/2013
Signature Date On Form:	08/28/2013
Signature Name On Form:	HOLLY FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	7035
Facility ID:	61076
AI Number:	39556
Application Received Date:	09/26/2003
Scheduled Construction Date:	11/07/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N

7-ELEVEN STORE 36656 (Continued) **U003040311**

AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30926003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	08/29/2013
Signature Date On Form:	08/28/2013
Signature Name On Form:	HOLLY FLAHERTY
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	57659
UST ID:	Not reported
NOC ID:	24607
AI Number:	39556
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	HOLLY FLAHERTY
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738413
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	7738400
Email Address:	Not reported

Cont/Cons/Installer ID:	7583
UST ID:	Not reported
NOC ID:	7036
AI Number:	39556
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1

7-ELEVEN STORE 36656 (Continued) **U003040311**

Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	7582
UST ID:	Not reported
NOC ID:	7035
AI Number:	39556
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	28439
UST ID:	202774
NOC ID:	Not reported
AI Number:	39556
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	28440

7-ELEVEN STORE 36656 (Continued) **U003040311**

UST ID:	202775
NOC ID:	Not reported
AI Number:	39556
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	43606
UST ID:	202774
NOC ID:	Not reported
AI Number:	39556
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	Not reported
Representative Name:	TONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	43607
UST ID:	202775
NOC ID:	Not reported
AI Number:	39556
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001252
Company Name:	Not reported
Representative Name:	TONY LEWIS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	61076
Additional ID:	482740612002149
Princ ID:	959578622001257
AI Number:	39556
Facility Name:	7-ELEVEN STORE 36656
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN #36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	1730
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	GRANDE MART
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/02/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.3
Mileage:	7.4
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Inspection Number Grade:	Not reported
Name:	GRANDE MART
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	06/03/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	GRANDE MART
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/09/2015
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	09/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	09/18/2015
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	09/17/2015
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported

7-ELEVEN STORE 36656 (Continued) **U003040311**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	61076
Finass ID:	4989
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2

7-ELEVEN STORE 36656 (Continued) **U003040311**

Facility ID:	61076
Finass ID:	43435
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2011
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	61076
Finass ID:	43436
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2010
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	61076
Finass ID:	43437
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7-ELEVEN STORE 36656 (Continued) **U003040311**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2009
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	61076
Finass ID:	43438
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2008
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 0 0
Policy Number:	17722
Coverage Amount:	2000000
Coverage Expiration Date:	12/31/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	61076
Finass ID:	43439
AI:	39556
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	12/19/2013
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No

7-ELEVEN STORE 36656 (Continued) **U003040311**

Proof of Financial Assurance: No

GCC:

Name:	7 ELEVEN STORE 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	Not reported
File Number:	119478
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	11/12/2013
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

LU2333 **DIAMOND SHAMROCK 2063** **TX RDR** **S127532141**
WNW **620 W 29TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
342 ft. **Site 3 of 5 in cluster LU**

Actual:
598 ft.

Focus Map:
8

RDR:

RDR ID:	13195
Facility ID:	39556
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 2063
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/6/2004
Due Date:	4/6/2004
Tank Owner:	NATIONAL CONVENIENCE STOR
Contact Person:	C SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/16/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RTN 4/23/04; NO PAHS, WASTE DOC NOT SIGNED, NO TEMP ON COC
Review Coordinator:	PPC/SJD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/16/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

LU2334 **TP 2533** **TX RDR** **S127532143**
WNW **620 W 29TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
342 ft. **Site 4 of 5 in cluster LU**

Actual:
598 ft.

Focus Map:
8

RDR:

RDR ID:	19176
Facility ID:	39556
RN:	Not reported
CN:	Not reported
Name:	TP 2533
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/20/2010
Due Date:	11/19/2010
Tank Owner:	G L THOMAS PETROLEUM LLC
Contact Person:	KIM BUESING
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	11/18/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NO FURTHER SITE CHECK REQUIRED
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	11/18/2010
Region:	Not reported
DKC RDR (misfiled):	Not reported

LU2335 **FROMER 7 ELEVEN 36656** **TX RDR** **S127532142**
WNW **620 W 29TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
342 ft. **Site 5 of 5 in cluster LU**

Actual:
598 ft.

Focus Map:
8

RDR:

RDR ID:	22227
Facility ID:	39556
RN:	Not reported
CN:	Not reported
Name:	FROMER 7 ELEVEN 36656
Address:	620 W 29TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/12/2014
Due Date:	10/11/2014
Tank Owner:	7 ELEVEN INC
Contact Person:	JOSE RIOS
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/8/2014
Project Manager:	Stacey Dunahoo
Team:	Team A
New LPST Number:	119478
Pre-Existing LPST Number:	Not reported

FROMER 7 ELEVEN 36656 (Continued) **S127532142**

Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

KP2336 **LANDMARK ORGANIZATION AUSTIN** **TX IHW CORR ACTION** **S113416835**
SW **401 NECES ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.065 mi.
342 ft. **Site 7 of 7 in cluster KP**

Actual:
475 ft.

Focus Map:
11

IHW CORR ACTION:

Name:	LANDMARK ORGANIZATION AUSTIN
Address:	401 NECES ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	T1783
Location Desc:	TRAVIS
RN NUM:	RN104646625
Status:	INACTIVE
Status Date:	02/20/2002
EDR Link ID:	T1783
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	11/22/2002
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

LA2337 **TEXAS MOTORS** **EDR Hist Auto** **1013756518**
West **502 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
343 ft. **Site 13 of 15 in cluster LA**

Actual:
493 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	TEXAS MOTORS	AUTOMOBILE REPAIRERS
1940	CARLSON DAVE GAR	AUTOMOBILE REPAIRING

MA2338 SSW < 1/8 0.065 mi. 343 ft. — **FORDEX SERVICE AUTO**, **201 2ND W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768891** / **N/A**

Site 2 of 2 in cluster MA

Actual: 474 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	WELLS L 0 SERVICE	GASOLINE AND OIL SERVICE STATIONS
1940	FORDEX SERVICE AUTO	AUTOMOBILE REPAIRING
1947	PURYEAR DEWEY RADIATOR WKS	RADIATOR REPAIRERS-AUTOMOBILE
1947	PURYEAR DEWEY RADIATOR WKS	AUTOMOBILE REPAIRING
1953	DEWEYS RADIATOR	RADIATOR REPAIRERS-AUTOMOBILE
1953	DEWEYS RADIATOR	AUTOMOBILE RADIATOR REPAIRING
1958	DEWEYS RADIATOR	AUTOMOBILE RADIATOR REPAIRERS

KY2339 ESE < 1/8 0.065 mi. 344 ft. — **AUTOMATIC TRANSMISSION CENTER**, **303 5TH ST W**, **AUSTIN, TX 78701** — **EDR Hist Auto** — **1013765349** / **N/A**

Site 18 of 21 in cluster KY

Actual: 489 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1980	AUTOMATIC TRANSMISSION CENTER	AUTOMOBILE REPAIRING

NT2340 NNE < 1/8 0.065 mi. 344 ft. — **OLD SPAGHETTI WAREHOUSE**, **117 W 4TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S128729000** / **N/A**

Site 1 of 3 in cluster NT

Actual: 482 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	OLD SPAGHETTI WAREHOUSE
Address:	117 W 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0331
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NG2341 WNW < 1/8 0.065 mi. 344 ft. — **CAPITAL CITY REPAIR CO**, **213 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768863** / **N/A**

Site 4 of 16 in cluster NG

Actual: 497 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	CAPITAL CITY REPAIR CO	AUTOMOBILE REPAIRERS
1916	CAPITAL CITY REPAIR CO	AUTOMOBILE GARAGES

LA2342 **LONE STAR GARAGE AUTO** **EDR Hist Auto** **1013757903**
West **500 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
344 ft. **Site 14 of 15 in cluster LA**

Actual:
493 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1911	LONE STAR GARAGE AUTO	AUTOMOBILE GARAGES

NU2343 **ESCUELA MONTESSORI** **US BROWNFIELDS** **1025442247**
SSW **2013 MONTOPOLIS DRIVE** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.065 mi.
344 ft. **Site 1 of 2 in cluster NU**

Actual:
519 ft.

Focus Map:
15

US BROWNFIELDS:

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2608.23
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	12/11/2018
Ownership Entity:	Not reported
Completion Date:	2/7/2019
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment

ESCUELA MONTESSORI (Continued) **1025442247**

Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	75000
Redev. Funding Source:	GNDC
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	9/1/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and

ESCUELA MONTESSORI (Continued) **1025442247**

intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.

Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	225000
Redev. Funding Source:	Private grant
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	9/1/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment

ESCUELA MONTESSORI (Continued) **1025442247**

Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and

ESCUELA MONTESSORI (Continued) **1025442247**

intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.

Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74
Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	17699796
Redev. Funding Source:	Private lenders

ESCUELA MONTESSORI (Continued) **1025442247**

Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	9/1/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment

ESCUELA MONTESSORI (Continued) **1025442247**

Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.
Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DRIVE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	2
Latitude:	30.2239539
Longitude:	-97.7030773
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	GNDC is partnering with Escuela Montessori de Montopolis, a nonprofit pre-school in Montopolis, to expand the pre-school and increase affordable housing opportunities in the Montopolis neighborhood. Escuela Montessori has 2 acres of land where GNDC will develop a new "state of the art" campus for the preschool students while creating 93 units of affordable, family oriented housing, with 14 units dedicated to seniors. The project, "Escuela Nueva" will double the number of children currently served by the pre-k. The campus will integrate the pre-k, family housing, and senior housing within a green, energy efficient, learning-focused development designed to increase social interaction, outdoor engagement, and

ESCUELA MONTESSORI (Continued) **1025442247**

intergenerational experiences, while enhancing the educational opportunities in the neighborhood. The project is currently in its early stages in the development process and GNDC is seeking community input regarding the design, and services provided within the development. Please complete this survey by October 1st, available in English and Spanish.

Datum:	Not reported
Acres Property ID:	238654
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	300000
Redev. Funding Source:	City of Austin Bond funding
Redev. Funding Entity Name:	Local Funding
Redevelopment Start Date:	9/1/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	1.5
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

ESCUELA MONTESSORI (Continued) **1025442247**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1543
Below Poverty Percent:	45.99
Meidan Income:	3616
Meidan Income Number:	2424
Meidan Income Percent:	72.25
Vacant Housing Number:	77
Vacant Housing Percent:	6.69
Unemployed Number:	159
Unemployed Percent:	4.74

NU2344 **ESCUELA MONTESSORI** **TX HIST UST** **S128729049**
SSW **2013 MONTOPOLIS DR** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
344 ft. **Site 2 of 2 in cluster NU**

Actual:
519 ft.

Focus Map:
15

HIST UST AUSTIN:

Name:	ESCUELA MONTESSORI
Address:	2013 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0481
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NV2345 **UNITED MTR EXCH** **EDR Hist Auto** **1013776926**
WNW **111 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.065 mi.
344 ft. **Site 1 of 2 in cluster NV**

Actual:
472 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1958	UNITED MTR EXCH	AUTOMOBILE REPAIRING

MZ2346 **TX HIST UST** **S128729206**
ESE **W 16TH & LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
346 ft. **Site 3 of 6 in cluster MZ**

Actual:
552 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	W 16TH & LAVACA
City,State,Zip:	AUSTIN, TX
Id UST:	H0175
HID UST:	Not reported
Inspection:	09/29/1927

(Continued) **S128729206**

Due: Not reported

MO2347 **BROADDUS CHEVRON** **TX LPST** **S102748227**
NE **30 N IH 35** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
346 ft. **Site 4 of 5 in cluster MO**

Actual:
455 ft.

Focus Map:
14

LPST:

Name:	BROADDUS CHEVRON
Address:	30 N IH 35
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0028644
LPST Id:	105305
Facility Location:	30 IH 35
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/12/1992
Entered Date:	02/12/1993
Reported Date:	08/21/1992
Closure Date:	05/29/1995
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	OUE
Responsible Party Name:	Not reported
Responsible Party Contact:	GRAIG DODD
Responsible Party Address:	PO BOX 4256
Responsible Party City,St,Zip:	HOUSTON, TX 77210
Responsible Party Telephone:	713/219-5229
Reported Date:	08/21/1992
Case Start Date:	05/29/1995
Reference Number:	RN102472586
Project Manager:	OEKPOOTU

Ind. Haz Waste:

Name:	TOWN LAKE GULF
Address:	30 N IH 35
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	61306
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/27/2020
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	PRIVATE
Description of Facility Site Location:	30 N IH-35, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1

BROADDUS CHEVRON (Continued) **S102748227**

Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TOWN LAKE GULF
Contact Name:	MARTY GILL
Contact Telephone Number:	Not reported
Mailing Address:	30 N IH 35
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787014326
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19661
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200827
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TOWN LAKE GULF
Operator Address:	30 N IH35
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TOWN LAKE GULF
Owner Mailing Address:	30 N IH35
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	Not reported

BROADDUS CHEVRON (Continued) **S102748227**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	30 N IH35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	30 N IH35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MARTY GILL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	30 N IH35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

2348 WNW < 1/8 0.066 mi. 346 ft. | **PRO CLEAN CARPET CLNG MAHANAY EUG JR** | **EDR Hist Cleaner** | **1013787166**
6411 STARSTREAK DR | **N/A**
TRAVIS (County), TX 78745

Actual: 669 ft. EDR Hist Cleaner

Focus Map: 17

Year:	Name:	Type:
1990	PRO CLEAN CARPET CLNG MAHANAY E	CARPET AND RUG CLEANERS
1992	PRO CLEAN	Carpet And Upholstery Cleaning
1993	PRO CLEAN	Carpet And Upholstery Cleaning
1994	PRO CLEAN	Carpet And Upholstery Cleaning
1995	PRO CLEAN	Carpet And Upholstery Cleaning
1996	PRO CLEAN	Carpet And Upholstery Cleaning
1997	PRO CLEAN	Carpet And Upholstery Cleaning

PRO CLEAN CARPET CLNG MAHANAY EUG JR (Continued) **1013787166**

1998	PRO CLEAN	Carpet And Upholstery Cleaning
1999	PRO CLEAN	Carpet And Upholstery Cleaning
2000	PRO CLEAN	Carpet And Upholstery Cleaning

LH2349 **CAPITOL TIRE** **TX HIST UST** **S128729103**
SSW **301 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
347 ft. **Site 21 of 26 in cluster LH**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CAPITOL TIRE
Address:	301 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0655
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LH2350 **GENERAL TIRE STORE** **TX HIST UST** **S128729215**
SSW **301 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
347 ft. **Site 22 of 26 in cluster LH**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	GENERAL TIRE STORE
Address:	301 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0213
HID UST:	213
Inspection:	Not reported
Due:	06/01/2012

LH2351 **CAPITOL TIRE SERVICE CTR** **TX UST** **U003291873**
SSW **301 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
347 ft. **Site 23 of 26 in cluster LH**

Actual:
483 ft.

Focus Map:
11

UST:

Name:	CAPITOL TIRE SERVICE CTR
Address:	301 E 5TH ST
City,State,Zip:	AUSTIN, TX 787013615
AI Number:	70342
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	229724922002053
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	KEVIN WILEY,
Contact Organization Name:	CAPITOL TIRE SERVICE CTR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124725466
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/19/1998
Signature Name/Title On Earliest Reg Form:	TERI B OGLEE,CHAIRMAN
Application Received Date On Earliest Reg Form:	01/21/1998
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784607
Owner Last Name:	301 E 5TH INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	219724912002053
Additional ID:	229724922002053
AI Number:	70342
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	01/21/1998
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	185524

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Facility ID:	106879
Ai Number:	70342
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/17/1998
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	0

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

UST Comprt ID:	166344
UST ID:	185524
AI Number:	70342
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26837
Cert ID:	157290
UST Comprt ID:	472888
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

Self Cert ID:	26837
Cert ID:	157292
UST Comprt ID:	472884
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Self Cert ID:	26837
Cert ID:	157289
UST Comprt ID:	472887
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157291
UST Comprt ID:	472885
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157288
UST Comprt ID:	472886
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Install Date:	12/01/1935
Tank Registration Date:	03/05/1998
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	185916
Facility ID:	106879
Ai Number:	70342
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/17/1998
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	0
UST Comprt ID:	166345
UST ID:	185916
AI Number:	70342
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26837
Cert ID:	157290
UST Comprt ID:	472888
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157292
UST Comprt ID:	472884
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157289
UST Comprt ID:	472887
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157291
UST Comprt ID:	472885
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157288
UST Comprt ID:	472886
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Install Date:	08/31/1987
Tank Registration Date:	01/21/1998
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	185522
Facility ID:	106879
Ai Number:	70342
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/17/1998
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	166342
UST ID:	185522
AI Number:	70342
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26837
Cert ID:	157290
UST Comprt ID:	472888
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Self Cert ID:	26837
Cert ID:	157292
UST Comprt ID:	472884
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157289
UST Comprt ID:	472887
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157291
UST Comprt ID:	472885
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157288
UST Comprt ID:	472886
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/21/1998
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	185523
Facility ID:	106879
Ai Number:	70342
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/17/1998
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	166343
UST ID:	185523
AI Number:	70342
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	26837
Cert ID:	157290
UST Comprt ID:	472888
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157292
UST Comprt ID:	472884
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157289
UST Comprt ID:	472887
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A
Self Cert ID:	26837
Cert ID:	157291
UST Comprt ID:	472885
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

CAPITOL TIRE SERVICE CTR (Continued) **U003291873**

Self Cert ID:	26837
Cert ID:	157288
UST Comprt ID:	472886
UST ID:	157943
AI Number:	70342
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	301 E 5TH INC
Contact Mailing Address (Delivery):	PO BOX 740
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 0740
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	106879
Additional ID:	229724922002053
Princ ID:	219724912002053
AI Number:	70342
Facility Name:	CAPITOL TIRE SERVICE CTR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JACK OWEN/

2352 WNW < 1/8 0.066 mi. 347 ft. **JONES JOHN H CLNR** **EDR Hist Cleaner** **1013783397**
212 17TH W **N/A**
AUSTIN, TX

Actual: 557 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1916	JONES JOHN H CLNR	CLOTHES CLEANERS AND PRESSERS

LH2353 SSW < 1/8 0.066 mi. 347 ft. **ACTION SCREEN GRAPHICS** **TX Ind. Haz Waste** **S104855273**
305 E 5TH ST STE B **N/A**
AUSTIN, TX 78701

Site 24 of 26 in cluster LH

Actual: 483 ft.

Focus Map: 11

Ind. Haz Waste:

Name:	ACTION SCREEN GRAPHICS
Address:	305 E 5TH ST STE B
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	81596
Registration Initial Notification Date:	09/15/1993
Registration Last Amendment Date:	12/12/2003
EPA Identification:	Not reported
Primary NAICS Code:	Not reported

ACTION SCREEN GRAPHICS (Continued) **S104855273**

Status Change Date:	19930915
Land Type:	Not reported
Description of Facility Site Location:	305 E 5th St, Ste B, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	ACTION SCREEN GRAPHICS
Contact Name:	JERRY B MUTCHIE
Contact Telephone Number:	512-4786248
Mailing Address:	305 E 5TH ST STE B
Mailing Address2:	STE B
Mailing City,State,Zip:	AUSTIN, TX 787013778
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	36616
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20070611
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JOHN SCHEXNAYDER
Operator Address:	305 E 5THST STE B
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

ACTION SCREEN GRAPHICS (Continued) **S104855273**

Ind. Haz Waste:

Owner Name:	ACTION SCREEN GRAPHICS
Owner Mailing Address:	305 E 5THST STE B
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4786248
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	JOHN SCHEXNAYDER
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	305 E 5THST STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	305 E 5THST STE B
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4786248
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JERRY MUTCHIE
Contact Title:	PROD MGR
Contact Role:	PRICONT
Contact Address:	305 E 5THST STE B
Contact Address 2:	STE B
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4786248
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	75391
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0

ACTION SCREEN GRAPHICS (Continued) **S104855273**

Waste Treated Off Site:	1
Generators Waste Description:	Spent solvent, cleaning silk screens, 1-92
Standard Industrial Code:	27590
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323119
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

2354 **BRUNDRETT ARNOLD 0 AUTO** **EDR Hist Auto** **1013765841**
ESE **404 32ND W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
347 ft.

Actual:
580 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1929	BRUNDRETT ARNOLD 0 AUTO	AUTOMOBILE REPAIRERS

LH2355 **CAPITOL AUTO & TRANSMISSIONS** **EDR Hist Auto** **1021555244**
SSW **311 E 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
347 ft. **Site 25 of 26 in cluster LH**

Actual:
483 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1992	CAPITOL AUTO & TRANSMISSIONS	Automotive Transmission Repair Shops

LH2356 **HERMINE WILDE ESTATE** **TX UST** **U001736078**
SSW **311 E 5TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
347 ft. **Site 26 of 26 in cluster LH**

Actual:
483 ft.

Focus Map:
11

UST:

Name:	HERMINE WILDE ESTATE
Address:	311 E 5TH ST
City,State,Zip:	AUSTIN, TX 787013615
AI Number:	65235
Facility Type:	RETAIL
Facility Begin Date:	12/29/1993
Facility Status:	INACTIVE
Additional ID:	245712452002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/21/1993
Signature Name/Title On Earliest Reg Form:	MARGARET E BUSH,EXECUTRIX
Application Received Date On Earliest Reg Form:	12/29/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784110
Owner Last Name:	HERMINE WILDE ESTATE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	237712442002053
Additional ID:	245712452002053

HERMINE WILDE ESTATE (Continued) **U001736078**

AI Number:	65235
Owner Effective Begin Date:	12/29/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/29/1993
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149334
Facility ID:	96988
Ai Number:	65235
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/11/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

HERMINE WILDE ESTATE (Continued) **U001736078**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/25/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	165074
UST ID:	149334
AI Number:	65235
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

HERMINE WILDE ESTATE (Continued) **U001736078**

Install Date:	08/31/1987
Tank Registration Date:	12/29/1993
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149335
Facility ID:	96988
Ai Number:	65235
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/11/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

HERMINE WILDE ESTATE (Continued) **U001736078**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/25/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	165075
UST ID:	149335
AI Number:	65235
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HERMINE WILDE ESTATE
Contact Mailing Address (Delivery):	12715 ROCKY MEADOW DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	HOUSTON, TX 77024 4039
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

HERMINE WILDE ESTATE (Continued) **U001736078**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96988
Additional ID:	245712452002053
Princ ID:	237712442002053
AI Number:	65235
Facility Name:	HERMINE WILDE ESTATE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MARGARET BUSH/

HIST UST AUSTIN:

Name:	SASSER PROPERTIES
Address:	311 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0450
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NW2357 **G. L. ROWE** **TX HIST UST** **S111678646**
WNW **816 W 12TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
348 ft. **Site 1 of 5 in cluster NW**

Actual:
492 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	G. L. ROWE
Address:	816 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0142
HID UST:	142
Inspection:	Not reported
Due:	06/01/2012

KH2358 **ELLIOTTS RADIATOR SHOP** **EDR Hist Auto** **1013757371**
SSW **102 2ND ST W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
348 ft. **Site 16 of 19 in cluster KH**

Actual:
474 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1980	ELLIOTTS RADIATOR SHOP	AUTOMOBILE RADIATOR REPAIRERS
1984	ELLIOTTS RADIATOR SHOP	AUTOMOBILE RADIATOR REPAIRERS

KH2359 SSW < 1/8 0.066 mi. 348 ft. — **ELLIOTTS RADIATOR SHOP REPAIRS**, **102 2ND ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013757372** / **N/A**

Site 17 of 19 in cluster KH

Actual: 474 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1970	ELLIOTTS RADIATOR SHOP REPAIRS	AUTOMOBILE RADIATOR REPAIRERS
1975	ELLIOTTS RADIATOR SHOP REPAIRS	AUTOMOBILE RADIATOR REPAIRERS

NX2360 NNE < 1/8 0.066 mi. 348 ft. — **SILBEY FIREPROOF WAREHOUSE CO**, **309 E 4TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678805** / **N/A**

Site 1 of 7 in cluster NX

Actual: 481 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	SILBEY FIREPROOF WAREHOUSE CO
Address:	309 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0339
HID UST:	339
Inspection:	Not reported
Due:	06/01/2012

NX2361 NNE < 1/8 0.066 mi. 348 ft. — **AUSTIN FIREPROOF WAREHOUSE CO**, **309 E 4TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678562** / **N/A**

Site 2 of 7 in cluster NX

Actual: 481 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	AUSTIN FIREPROOF WAREHOUSE CO
Address:	309 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0985
HID UST:	985
Inspection:	Not reported
Due:	06/01/2012

NY2362 NE < 1/8 0.066 mi. 349 ft. — **ALMQUIST SINCLAIR SERV STA**, **700 RED RIVER**, **AUSTIN, TX** — **EDR Hist Auto** — **1013763620** / **N/A**

Site 1 of 5 in cluster NY

Actual: 486 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	FRUTH ROY F FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	ALMQUIST SINCLAIR SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	PETERSON LEO HUM	GASOLINE STATIONS
1958	PETERSON LEO	GASOLINE STATIONS

ALMQUIST SINCLAIR SERV STA (Continued) **1013763620**

1962	PETERSON LEO SERV	GASOLINE STATIONS
1965	PETERSON LEO SERVICE	GASOLINE STATIONS
1969	PETERSON LEO F	Gasoline Service Stations
1970	PETERSON LEO SERVICE STATION &	GASOLINE STATIONS
1970	PETERSON LEO F	Gasoline Service Stations
1971	PETERSON LEO F	Gasoline Service Stations
1972	PETERSON LEO F	Gasoline Service Stations
1973	PETERSON LEO F	Gasoline Service Stations
1974	PETERSON LEO F	Gasoline Service Stations
1975	LEO PETERSON CAR CARE CLINIC	AUTOMOBILE REPAIRING
1975	PETERSON LEO F	Gasoline Service Stations
1979	MC AULEY SERVICE	Gasoline Service Stations
1980	ME AULEY SERVICE CO	AUTOMOBILE REPAIRING
1980	MC AULEY SERVICE	Gasoline Service Stations
1982	MC AULEY SERVICE	Gasoline Service Stations

NX2363 **M&T RAILWAY COMPANY** **TX HIST UST** **S111678728**
NNE **301 E 4TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
349 ft. **Site 3 of 7 in cluster NX**

Actual:
481 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	M&T RAILWAY COMPANY
Address:	301 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0008
HID UST:	8
Inspection:	06/29/2010
Due:	06/29/2013

NX2364 **K&B STORAGE CO.** **TX HIST UST** **S111678711**
NNE **301 E 4TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
349 ft. **Site 4 of 7 in cluster NX**

Actual:
481 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	K&B STORAGE CO.
Address:	301 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0348
HID UST:	348
Inspection:	06/29/2010
Due:	06/29/2013

MQ2365 **MC GINNIS & GRIMES** **EDR Hist Cleaner** **1013784352**
ENE **3810 E AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
350 ft. **Site 5 of 18 in cluster MQ**

Actual:
587 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1929	MC GINNIS & GRIMES	CLOTHES CLEANERS AND PRESSERS

MQ2366 **DYNA TUNE** **TX Ind. Haz Waste** **S102748635**
ENE **3810 EAST AVE** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.066 mi.
350 ft. **Site 6 of 18 in cluster MQ**

Actual:
587 ft.
Ind. Haz Waste:

Focus Map:
8

Name:	DYNA TUNE
Address:	3810 EAST AVE
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	61779
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	3810 East Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	DYNA TUNE
Contact Name:	ENVIRONMENTAL MANAGER
Contact Telephone Number:	Not reported
Mailing Address:	3810 EAST AVE
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787515201
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20120
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

DYNA TUNE (Continued) **S102748635**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	DYNA TUNE
Operator Address:	3810 EASTAVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78751
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17517037424
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DYNA TUNE
Owner Mailing Address:	3810 EASTAVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78751
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17517037424
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3810 EASTAVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3810 EASTAVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751

DYNA TUNE (Continued) **S102748635**

Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3810 EASTAVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	ENVIRONMENTAL MANAGER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3810 EASTAVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78751
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100568161
Name:	DYNA TUNE
Address:	3810 EAST AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78751-5201
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600278808
Customer Name:	DYNA TUNE
Customer Legal Name:	Dyna-Tune, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3810 East Ave, Austin, TX

MI2367 **CAPITOL LNDRY & CLN** **EDR Hist Cleaner** **1013786736**
ESE **301 8TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 2 of 2 in cluster MI**

Actual:
534 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1958	CAPITOL LNDRY & CLN	CLEANERS AND DYERS
1958	CAPITOL LNDRY & CLN	LAUNDRIES

CAPITOL LNDRY & CLN (Continued) **1013786736**

1962 CAPITOL LNDRY & DRY LAUNDRIES

NG2368 **NASH JOHN H MOTOR CO** **EDR Hist Auto** **1013764981**
WNW **215 6TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 5 of 16 in cluster NG**

Actual:
497 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	215 17 WICKLINE GARAGE	AUTOMOBILE GARAGES
1929	NASH JOHN H MOTOR CO	AUTOMOBILE REPAIRERS
1929	NASH JOHN H MOTOR CO	AUTOMOBILE GARAGES

NZ2369 **FOWLER ELECTRIC** **TX UST** **U001283812**
NE **621 E 7TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.066 mi.
351 ft. **Site 1 of 4 in cluster NZ**

Actual:
466 ft.

UST:

Focus Map:
11

Name:	FOWLER ELECTRIC
Address:	621 E 7TH ST
City,State,Zip:	AUSTIN, TX 787013304
AI Number:	53154
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/01/1990
Facility Status:	INACTIVE
Additional ID:	463556372002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	RANDY MERRITT,PROPERTY MANAGER
Contact Organization Name:	FOWLER ELECTRIC
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124441814
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/15/1990
Signature Name/Title On Earliest Reg Form:	RANDY MERRITT,PROPERTY MANAGER
Application Received Date On Earliest Reg Form:	03/19/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

FOWLER ELECTRIC (Continued) **U001283812**

Owner:

Owner CN:	CN600778963
Owner Last Name:	ESTATE OF VERNON FOWLER
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	453556362002053
Additional ID:	463556372002053
AI Number:	53154
Owner Effective Begin Date:	05/01/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/19/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	131480
Facility ID:	83025
Ai Number:	53154
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/19/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

FOWLER ELECTRIC (Continued) **U001283812**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	136886
UST ID:	131480
AI Number:	53154
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

FOWLER ELECTRIC (Continued) **U001283812**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ESTATE OF VERNON FOWLER
Contact Mailing Address (Delivery):	RT 2 BOX 82A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	MANOR, TX 78653
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	83025
Additional ID:	463556372002053
Princ ID:	453556362002053
AI Number:	53154
Facility Name:	FOWLER ELECTRIC
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RANDY MERRITT/

HIST UST AUSTIN:

Name:	FOWLER ELECTRIC
Address:	621 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0113
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LG2370 **JACOBSON TYRE & REPAIR** **TX HIST UST** **S111678700**
SSW **101 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 21 of 26 in cluster LG**

Actual:
489 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JACOBSON TYRE & REPAIR
Address:	101 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0016
HID UST:	16
Inspection:	03/06/2009
Due:	03/06/2012

LG2371 **TX HIST UST** **S128729166**
SSW **101 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 22 of 26 in cluster LG**

Actual:
489 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	101 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0041
HID UST:	41
Inspection:	03/06/2009
Due:	03/06/2012

LG2372 **TEXAS OIL COMPANY** **TX HIST UST** **S111678825**
SSW **101 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 23 of 26 in cluster LG**

Actual:
489 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TEXAS OIL COMPANY
Address:	101 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0039
HID UST:	39
Inspection:	03/06/2009
Due:	03/06/2012

LG2373 **TX HIST UST** **S128729168**
SSW **101 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 24 of 26 in cluster LG**

Actual:
489 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	101 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0052
HID UST:	52
Inspection:	03/06/2009
Due:	03/06/2012

KY2374 **SMITH C B MOTORS** **EDR Hist Auto** **1013760268**
ESE **301 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 19 of 21 in cluster KY**

Actual:
489 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	FIRESTONE AUTO SUPPLY & SERVLCE	BRAKE SERVICE
1953	SMITH C B MOTORS	AUTOMOBILE REPAIRING

KY2375 **CARREON MARCIEL CLNR** **EDR Hist Cleaner** **1013786699**
ESE **301 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 20 of 21 in cluster KY**

Actual:
489 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1916	CARREON MARCIEL CLNR	CLOTHES CLEANERS AND PRESSERS
1922	CARRION RAYMOND DO	CLOTHES CLEANERS AND PRESSERS

KY2376 **301 3 TIRE SERVICE CO** **EDR Hist Auto** **1013768021**
ESE **301 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.066 mi.
351 ft. **Site 21 of 21 in cluster KY**

Actual:
489 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	301 3 TIRE SERVICE CO	AUTOMOBILE FILLING STATIONS

KH2377 SSW < 1/8 0.067 mi. 352 ft. — **DEWEYS WELDING & RADIATOR SERVICE**, **110 2ND W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774972** / **N/A**

Site 18 of 19 in cluster KH

Actual: 474 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	DEWEYS WELDING & RADIATOR SERVI	AUTOMOBILE REPAIRERS

KH2378 SSW < 1/8 0.067 mi. 352 ft. — **108 10 0 0 K GARAGE**, **108 2ND W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013770986** / **N/A**

Site 19 of 19 in cluster KH

Actual: 474 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	108 10 0 0 K GARAGE	AUTOMOBILE GARAGES

2379 NNE < 1/8 0.067 mi. 353 ft. — **APPLE MART**, **2101 WICKERSHAM LN**, **AUSTIN, TX 78741** — **TX UST**, **TX HIST UST**, **TX ASBESTOS**, **TX Financial Assurance**, **TX CENTRAL REGISTRY** — **U004217117** / **N/A**

Actual: 485 ft.

Focus Map: 15

UST:

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 787415374
AI Number:	85576
Facility Type:	RETAIL
Facility Begin Date:	04/15/2013
Facility Status:	ACTIVE
Additional ID:	863537082013011
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	PARVEZ BADARPURA,PRESIDENT
Contact Organization Name:	APPLE MART
Contact Mailing Address1:	2101 WICKERSHAM LN STE A
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787415374
Contact Telephone:	5125775955
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	APP786MART@GMAIL.COM
Signature Date On Earliest Reg Form:	02/16/2022
Signature Name/Title On Earliest Reg Form:	PARVEZ BADARPURA,PRESIDENT
Application Received Date On Earliest Reg Form:	03/24/2022

APPLE MART (Continued) **U004217117**

Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	766474932013267
Additional ID:	863537082013011
Ai Number:	85576
Operator CN:	CN604380436
Operator Name:	PREMIER BUSINESS INVESTMENT INC
Operator Effective Begin Date:	04/15/2013
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604380428
Owner Last Name:	JIMMY & NASH ENTERPRISE LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	567472262013267
Additional ID:	863537082013011
AI Number:	85576
Owner Effective Begin Date:	04/15/2013
State Tax ID:	32045497024
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

APPLE MART (Continued) **U004217117**

Self Certification:

Self Cert ID:	130837
Cert ID:	368858
AI Number:	85576
Self Certification Date:	02/16/2022
Signature Name/Title:	PARVEZ BADARPURA PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	351381
AI Number:	85576
Self Certification Date:	03/03/2021
Signature Name/Title:	PARVEZ BADARPURA PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	334041
AI Number:	85576
Self Certification Date:	02/12/2020
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

APPLE MART (Continued) **U004217117**

Self Cert ID:	130837
Cert ID:	317313
AI Number:	85576
Self Certification Date:	02/28/2019
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	300714
AI Number:	85576
Self Certification Date:	02/15/2018
Signature Name/Title:	PARVEZ BADAPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	283096
AI Number:	85576
Self Certification Date:	02/09/2017
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

APPLE MART (Continued) **U004217117**

Self Cert ID:	130837
Cert ID:	267262
AI Number:	85576
Self Certification Date:	01/28/2016
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	249201
AI Number:	85576
Self Certification Date:	02/11/2015
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	130837
Cert ID:	232831
AI Number:	85576
Self Certification Date:	02/02/2014
Signature Name/Title:	PARVEZ BADARPURA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

APPLE MART (Continued) **U004217117**

Self Cert ID:	130837
Cert ID:	226544
AI Number:	85576
Self Certification Date:	09/09/2013
Signature Name/Title:	PARVEZ BADARPURA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Tank:

Install Date:	04/15/2013
Tank Registration Date:	09/23/2013
Number of Compartments:	3
Tank Capacity:	24000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	218835
Facility ID:	130837
Ai Number:	85576
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/15/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

APPLE MART (Continued) **U004217117**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	Y
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/09/2013

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	186301
UST ID:	218835
AI Number:	85576
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y

APPLE MART (Continued) **U004217117**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/17/2013
Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	186303
UST ID:	218835
AI Number:	85576
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/17/2013
Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	186304
UST ID:	218835

APPLE MART (Continued) **U004217117**

AI Number:	85576
Compartment ID:	C
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/17/2013

Construction Notification:

NOC ID:	24492
Facility ID:	130837
AI Number:	85576
Application Received Date:	08/12/2013
Scheduled Construction Date:	09/09/2013
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported

APPLE MART (Continued) **U004217117**

Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	RIVERSIDE VILLAGE LP
Owner CN At Time Of Construction:	CN604254672
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	COMPLETE INSTALLATION OF UST, PIPING & DISPENSER.

NOC ID:	23328
Facility ID:	130837
AI Number:	85576
Application Received Date:	01/07/2013
Scheduled Construction Date:	01/29/2013
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	74003
General Desc Of Prop Construct:	INSTALLATION OF NEW UST, PIPING, DIPENSERS, ETC.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	24892
UST ID:	Not reported
NOC ID:	23328
AI Number:	85576
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	TYLER PUMP AND SERVICES
Representative Name:	KHALID MAHMOOD
Mailing Address (Delivery):	2026 E FRONT ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TYLER
Mailing State:	TX
Mailing Zip:	75702
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

APPLE MART (Continued) **U004217117**

Phone Number Country Code:	1
Phone Number Area Code:	800
Phone Number:	6071142
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	57473
UST ID:	Not reported
NOC ID:	24492
AI Number:	85576
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	UST SYSTEMS
Representative Name:	MANUEL TAVIRA
Mailing Address (Delivery):	4313 DELHI
Mailing Address (Internal Delivery):	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77022
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	832
Phone Number:	8802343
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	713
Fax Number:	6993750
Email Address:	Not reported
Cont/Cons/Installer ID:	57954
UST ID:	218835
NOC ID:	Not reported
AI Number:	85576
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	UST SYSTEMS
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

APPLE MART (Continued) **U004217117**

Cont/Cons/Installer ID:	24893
UST ID:	Not reported
NOC ID:	23328
AI Number:	85576
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	57953
UST ID:	218835
NOC ID:	Not reported
AI Number:	85576
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001988
Company Name:	TAVIRA MANUEL PORCAYO
Representative Name:	Not reported
Mailing Address (Delivery):	4313 DELHI ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77022
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	832
Phone Number:	8802343
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	JIMMY & NASH ENTERPRISE LLC
Contact Mailing Address (Delivery):	2101 WICKERSHAM LN STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 5374
Phone Number/Ext:	512 3865222/0
Contact Fax Number/Ext:	/
Contact Email Address:	APP786MART@GMAIL.COM
Contact Address Deliverable:	Y

APPLE MART (Continued) **U004217117**

Facility ID:	130837
Additional ID:	863537082013011
Princ ID:	567472262013267
AI Number:	85576
Facility Name:	APPLE MART
AR Number:	75113
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PARVEZ BADARPURA/PRESIDENT

HIST UST AUSTIN:

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX
Id UST:	3370
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/23/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.3
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/28/2014
Date Routed by Supervisor:	04/28/2014
Date Routed to PSQA:	04/28/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported

APPLE MART (Continued) **U004217117**

Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	266501
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2021
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24794366 008
Coverage Amount:	1,000,000

APPLE MART (Continued) **U004217117**

Coverage Expiration Date:	08/29/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	247367
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2020
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	G24794386 007
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	228942
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2019
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24794386006
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837

APPLE MART (Continued) **U004217117**

Finass ID:	211004
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2018
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24794386 005
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	194019
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2017
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24794386004
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	175932
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

APPLE MART (Continued) **U004217117**

Financial Assurance Begin Date:	08/29/2016
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24794386 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	158980
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2015
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24794386002
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	140500
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2014
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 214 2391609
Policy Number:	G24794-386001
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

APPLE MART (Continued) **U004217117**

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	116195
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/30/2013
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-86778
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	APPLE MART
Address:	2101 WICKERSHAM LN
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	130837
Finass ID:	123855
AI:	85576
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/30/2013
Date Financial Assurance Form Rec:	03/24/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00086778
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

CENTRAL REGISTRY:

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	1/11/2013
Customer Number:	CN604254672

APPLE MART (Continued) **U004217117**

Customer Name:	RIVERSIDE VILLAGE LP
Customer Legal Name:	RIVERSIDE VILLAGE, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	4/14/2013
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	1/11/2013
Customer Number:	CN604380436
Customer Name:	PREMIER BUSINESS INVESTMENT INC
Customer Legal Name:	PREMIER BUSINESS INVESTMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/15/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	1/11/2013
Customer Number:	CN604380428
Customer Name:	JIMMY & NASH ENTERPRISE LLC
Customer Legal Name:	JIMMY & NASH ENTERPRISE, LLC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	4/15/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604254672
Customer Name:	RIVERSIDE VILLAGE LP
Customer Legal Name:	RIVERSIDE VILLAGE, LP
Customer Ownership Type:	PARTNERSHIP

APPLE MART (Continued) **U004217117**

Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2013-04-14
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604254672
Customer Name:	RIVERSIDE VILLAGE LP
Customer Legal Name:	RIVERSIDE VILLAGE, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2013-04-14
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604254672
Customer Name:	RIVERSIDE VILLAGE LP
Customer Legal Name:	RIVERSIDE VILLAGE, LP
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2013-04-14
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604380436
Customer Name:	PREMIER BUSINESS INVESTMENT INC
Customer Legal Name:	PREMIER BUSINESS INVESTMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-04-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE

APPLE MART (Continued) **U004217117**

Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604380436
Customer Name:	PREMIER BUSINESS INVESTMENT INC
Customer Legal Name:	PREMIER BUSINESS INVESTMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-04-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604380436
Customer Name:	PREMIER BUSINESS INVESTMENT INC
Customer Legal Name:	PREMIER BUSINESS INVESTMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-04-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604380428
Customer Name:	JIMMY & NASH ENTERPRISE LLC
Customer Legal Name:	JIMMY & NASH ENTERPRISE, LLC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2013-04-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

APPLE MART (Continued) **U004217117**

Regulated Entity Number:	RN106583073
Name:	APPLE MART
Address:	2101 WICKERSHAM LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-5374
Status:	ACTIVE
Status Date:	2013-01-11
Customer Number:	CN604380428
Customer Name:	JIMMY & NASH ENTERPRISE LLC
Customer Legal Name:	JIMMY & NASH ENTERPRISE, LLC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2013-04-15
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

2380 **912 HWY 183** **US BROWNFIELDS** **1024456201**
ENE **912 HWY 183** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.067 mi.
353 ft.

Actual:
472 ft.

Focus Map:
15

US BROWNFIELDS:

Name:	912 HWY 183
Address:	912 HWY 183
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	4.39
Latitude:	30.2293312
Longitude:	-97.6831372
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City was looking to acquire this property, but the sale fell through after due diligence was complete. Former Use: The property was developed in the 1980s as a bank, and was most recently a Wells Fargo bank. The City of Austin was going to purchase the property for office space, and this report was part of the due diligence. The property transaction fell through, and the sale was not completed.
Datum:	Not reported
Acres Property ID:	237538
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported

912 HWY 183 (Continued) **1024456201**

Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.39
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	4.39
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was developed in the 1980s as a bank, and was most recently a Wells Fargo bank. The City of Austin was going to purchase the property for office space, and this report was part of the due diligence. The property transaction fell through, and the sale was not completed.
Below Poverty Number:	219
Below Poverty Percent:	39.04
Meidan Income:	610
Meidan Income Number:	389
Meidan Income Percent:	69.34
Vacant Housing Number:	11
Vacant Housing Percent:	5.46
Unemployed Number:	37
Unemployed Percent:	6.6

912 HWY 183 (Continued) **1024456201**

Name:	912 HWY 183
Address:	912 HWY 183
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	4.39
Latitude:	30.2293312
Longitude:	-97.6831372
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City was looking to acquire this property, but the sale fell through after due diligence was complete. Former Use: The property was developed in the 1980s as a bank, and was most recently a Wells Fargo bank. The City of Austin was going to purchase the property for office space, and this report was part of the due diligence. The property transaction fell through, and the sale was not completed.
Datum:	Not reported
Acres Property ID:	237538
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6077
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	5/1/2018
Ownership Entity:	Private
Completion Date:	6/28/2018
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

912 HWY 183 (Continued) **1024456201**

Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.39
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	4.39
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was developed in the 1980s as a bank, and was most recently a Wells Fargo bank. The City of Austin was going to purchase the property for office space, and this report was part of the due diligence. The property transaction fell through, and the sale was not completed.
Below Poverty Number:	219
Below Poverty Percent:	39.04
Meidan Income:	610
Meidan Income Number:	389
Meidan Income Percent:	69.34
Vacant Housing Number:	11
Vacant Housing Percent:	5.46
Unemployed Number:	37
Unemployed Percent:	6.6

2381 WNW < 1/8 0.067 mi. 355 ft. | **MURPHYS GARAGE AUTO REPR** | **EDR Hist Auto** | **1013754815**
3801 WADFORD ST | **N/A**
TRAVIS (County), TX 78704

Actual: 652 ft. EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
1975	MURPHYS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1980	MURPHYS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1984	MURPHYS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1986	MURPHYS GARAGE	General Automotive Repair Shops
1987	MURPHYS GARAGE	General Automotive Repair Shops
1988	MURPHYS GARAGE	General Automotive Repair Shops
1989	MURPHYS GARAGE	General Automotive Repair Shops
1990	MURPHYS GARAGE	General Automotive Repair Shops
1991	MURPHYS GARAGE	General Automotive Repair Shops
1992	MURPHYS GARAGE	General Automotive Repair Shops
1993	MURPHYS GARAGE	General Automotive Repair Shops
1994	MURPHYS GARAGE	General Automotive Repair Shops
1995	MURPHYS GARAGE	General Automotive Repair Shops
1996	MURPHYS GARAGE	General Automotive Repair Shops
1997	MURPHYS GARAGE	General Automotive Repair Shops
1998	MURPHYS GARAGE	General Automotive Repair Shops
1999	MURPHYS GARAGE	General Automotive Repair Shops
2000	MURPHYS GARAGE	General Automotive Repair Shops

MURPHYS GARAGE AUTO REPR (Continued) **1013754815**

2001	MURPHYS GARAGE	General Automotive Repair Shops
2002	MURPHYS GARAGE	General Automotive Repair Shops
2003	MURPHYS GARAGE	General Automotive Repair Shops
2004	MURPHYS GARAGE	General Automotive Repair Shops
2005	MURPHYS GARAGE	General Automotive Repair Shops
2006	MURPHYS GARAGE	General Automotive Repair Shops
2007	MURPHYS GARAGE	General Automotive Repair Shops
2008	MURPHYS GARAGE	General Automotive Repair Shops
2009	MURPHYS GARAGE	General Automotive Repair Shops
2010	MURPHYS GARAGE	General Automotive Repair Shops
2011	MURPHYS GARAGE	General Automotive Repair Shops
2012	MURPHYS GARAGE	General Automotive Repair Shops
2013	MURPHYS GARAGE	General Automotive Repair Shops
2014	MURPHYS GARAGE	General Automotive Repair Shops

MQ2382 **EXXON STATION 67383** **TX LPST** **S105050096**
ENE **3807 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX 78722**
0.067 mi.
355 ft. **Site 7 of 18 in cluster MQ**

Actual:
589 ft.

Focus Map:
8

LPST:

Name:	EXXON STATION 67383
Address:	3807 EAST AVE
City,State,Zip:	AUSTIN, TX 78722
Facility ID:	0026118
LPST Id:	099887
Facility Location:	EAST ST IH 35 @ E 38 1/2 ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/05/1991
Entered Date:	08/16/1991
Reported Date:	04/15/1991
Closure Date:	02/03/1993
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	DEBBIE H HUNTER
Responsible Party Address:	PO BOX 2180
Responsible Party City,St,Zip:	HOUSTON, TX 77252 2180
Responsible Party Telephone:	713/656-2312
Reported Date:	04/15/1991
Case Start Date:	02/03/1993
Reference Number:	RN102154465
Project Manager:	HWELCH

MQ2383 **EXXON MOBIL CORPORATION** **RCRA NonGen / NLR** **1004785569**
ENE **3807 EAST AVE** **TXD988031910**
< 1/8 **AUSTIN, TX 78722**
0.067 mi.
355 ft. **Site 8 of 18 in cluster MQ**

Actual:
589 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	EAST AVE
Handler City,State,Zip:	AUSTIN, TX 78722
EPA ID:	TXD988031910
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 2180
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Telephone:	713-656-7709
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2180
Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

EXXON MOBIL CORPORATION (Continued) **1004785569**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 2180
Owner/Operator City,State,Zip:	HOUSTON, TX 77252
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON CO USA	
Legal Status:	Private
Date Became Current:	Not reported

EXXON MOBIL CORPORATION (Continued) **1004785569**

Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4415
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-7761
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2180
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910401
Handler Name: EXXON CO USA #67383
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

EXXON MOBIL CORPORATION (Continued) **1004785569**

Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

MQ2384 **SS 6 7383** **TX UST** **U001260122**
ENE **3807 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX 78722**
0.067 mi.
355 ft. **Site 9 of 18 in cluster MQ**

Actual:
589 ft.

Focus Map:
8

UST:

Name:	SS 6 7383
Address:	3807 EAST AVE
City,State,Zip:	AUSTIN, TX 787221531
AI Number:	26118
Facility Type:	RETAIL
Facility Begin Date:	10/06/1986
Facility Status:	INACTIVE
Additional ID:	644602322002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78722
Contact Name/Title:	B TALLEY,MGR
Contact Organization Name:	SS 6 7383
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124590539
Facility Contact Address Deliverable:	Not reported

SS 6 7383 (Continued) **U001260122**

Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,ENG SUPERVISOR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600123939
Owner Last Name:	EXXON MOBIL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	679380312001134
Additional ID:	644602322002175
AI Number:	26118
Owner Effective Begin Date:	10/06/1986
State Tax ID:	11354090059
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67324
Facility ID:	47985
Ai Number:	26118
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

SS 6 7383 (Continued) **U001260122**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	36608
UST ID:	67324
AI Number:	26118
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

SS 6 7383 (Continued) **U001260122**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	67325
Facility ID:	47985
Ai Number:	26118
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

SS 6 7383 (Continued) **U001260122**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	36609
UST ID:	67325
AI Number:	26118
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

SS 6 7383 (Continued) **U001260122**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67328
Facility ID:	47985
Ai Number:	26118
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

SS 6 7383 (Continued) **U001260122**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	3000
UST Comprt ID:	36612
UST ID:	67328
AI Number:	26118
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

SS 6 7383 (Continued) **U001260122**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67327
Facility ID:	47985
Ai Number:	26118
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

SS 6 7383 (Continued) **U001260122**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	36611
UST ID:	67327
AI Number:	26118
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

SS 6 7383 (Continued) **U001260122**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67326
Facility ID:	47985
Ai Number:	26118
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

SS 6 7383 (Continued) **U001260122**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	36610
UST ID:	67326
AI Number:	26118
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	EXXON MOBIL CORPORATION

SS 6 7383 (Continued) **U001260122**

Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47985
Additional ID:	644602322002175
Princ ID:	679380312001134
AI Number:	26118
Facility Name:	SS 6 7383
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HEATHER GILMORE/

MQ2385 **EXXON MOBIL NO 67383** **TX Ind. Haz Waste** **S102757842**
ENE **3807 EAST AVE** **N/A**
< 1/8 **AUSTIN, TX 78722**
0.067 mi.
355 ft. **Site 10 of 18 in cluster MQ**

Actual:
589 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	EXXON MOBIL NO 67383
Address:	3807 EAST AVE
City,State,Zip:	AUSTIN, TX 78722
Permit Number:	Not reported
Registration Number:	77157
Registration Initial Notification Date:	06/28/1991
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988031910
Primary NAICS Code:	Not reported
Status Change Date:	19910628
Land Type:	PRIVATE
Description of Facility Site Location:	3807 East Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6567709
Mailing Address:	PO BOX 2180
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 772522180
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

EXXON MOBIL NO 67383 (Continued) **S102757842**

TNRCC Facility ID:	31465
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 2180
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77252
Operator Country:	UNITED STA
Operator Telephone:	1-713-6567709
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 2180
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77252
Owner Country:	UNITED STA
Owner Telephone:	1-713-6567709
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported

EXXON MOBIL NO 67383 (Continued) **S102757842**

Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	WASTE ADMINISTRATOR
Contact Role:	PRICONT
Contact Address:	PO BOX 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77252
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

MQ2386 ENE < 1/8 0.067 mi. 355 ft. — **BALKOS HUMBLE**, **3807 EAST AVE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013768379** / **N/A**

Site 11 of 18 in cluster MQ

Actual: 589 ft. — EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1953	BALKOS HUMBLE	GASOLINE STATIONS
1958	BALKOS HUMBLE	GASOLINE STATIONS
1962	BALKO G E HUMBLE	GASOLINE STATIONS
1965	BALKO G E HUMBLE PRODUCTS	GASOLINE STATIONS
1969	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1970	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1971	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1972	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1973	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1974	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1975	BALKOS HUMBLE SERVICE STATION	Gasoline Service Stations
1980	TALLEYS BILL DELWOOD EXXON	Gasoline Service Stations
1982	TALLEYS BILL DELWOOD EXXON	Gasoline Service Stations
1983	TALLEYS BILL DELWOOD EXXON	Gasoline Service Stations
1985	TALLEYS BILL DELWOOD EXXON	Gasoline Service Stations
1986	TALLEY WILLIAM R INC	Gasoline Service Stations
1987	TALLEY WILLIAM R INC	Gasoline Service Stations
1988	TALLEY WILLIAM R INC	Gasoline Service Stations
1989	TALLEY WILLIAM R INC	Gasoline Service Stations
1990	TALLEY WILLIAM R INC	Gasoline Service Stations

2387 SW < 1/8 0.067 mi. 355 ft. — **MUD PPPIES SELF SERVE DOG WASH**, **2015 E RIVERSIDE DR**, **AUSTIN, TX 78741** — **EDR Hist Auto** — **1020799835** / **N/A**

Actual: 502 ft. — EDR Hist Auto

Focus Map: 14

Year:	Name:	Type:
2013	MUD PPPIES SELF SERVE DOG WASH	Gasoline Service Stations, NEC
2014	MUD PUPPIES DOG WASH & PLAYCAR	Gasoline Service Stations, NEC

KR2388 ESE < 1/8 0.067 mi. 355 ft. — **MRS. PRUDENCE BAILEY**, **520 W 6TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S128729467** / **N/A**

Site 8 of 10 in cluster KR

Actual: 478 ft. — HIST UST AUSTIN:

Focus Map: 11

Name:	MRS. PRUDENCE BAILEY
Address:	520 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0908
HID UST:	908
Inspection:	Not reported
Due:	06/01/2012

KR2389 ESE < 1/8 0.067 mi. 355 ft. — **WILLIAMS MOTORS, 520 W 6TH ST, AUSTIN, TX** — **TX HIST UST** — **S128729038** / **N/A**

Site 9 of 10 in cluster KR

Actual: 478 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	WILLIAMS MOTORS
Address:	520 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0457
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

KR2390 ESE < 1/8 0.067 mi. 355 ft. — **520 W 6TH ST LLC, 520 W 6TH, AUSTIN, TX** — **TX RDR** — **S127535188** / **N/A**

Site 10 of 10 in cluster KR

Actual: 478 ft.
Focus Map: 11

RDR:

RDR ID:	12107
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	520 W 6TH ST LLC
Address:	520 W 6TH
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/31/2003
Due Date:	9/29/2003
Tank Owner:	520 W 6TH ST LLC
Contact Person:	MIKE MCGINNIS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/8/2003
Project Manager:	Tim Rupert
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR ORIG RECD 2/27/2003
Review Coordinator:	TSR/TOI/EGS
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/8/2003
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

2391 ESE < 1/8 0.067 mi. 355 ft. | **RPS TRANSMISSION & AUTO SVC**
700 W APPLEGATE DR
AUSTIN, TX 78753 | **EDR Hist Auto** | **1021224359**
N/A

Actual: 727 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1992	DON JUAN AUTOMOTIVE	General Automotive Repair Shops
1993	DON JUAN AUTOMOTIVE	General Automotive Repair Shops
1994	DON JUAN AUTOMOTIVE	General Automotive Repair Shops
1995	DON JUAN AUTOMOTIVE	General Automotive Repair Shops
1996	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
1997	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
1997	HASSELL AUTOMOTIVE	General Automotive Repair Shops
1998	HASSELL AUTOMOTIVE	General Automotive Repair Shops
1998	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
1999	HASSELL AUTOMOTIVE	General Automotive Repair Shops
1999	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2000	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2000	HASSELL AUTOMOTIVE	General Automotive Repair Shops
2001	HASSELL AUTOMOTIVE	General Automotive Repair Shops
2001	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2002	HASSELL AUTOMOTIVE	General Automotive Repair Shops
2002	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2003	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2004	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2005	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2006	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2007	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2008	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops
2009	RPS TRANSMISSION & AUTO SVC	Automotive Transmission Repair Shops

---

NR2392 SE < 1/8 0.067 mi. 356 ft. | **COLD**
704 W POWELL LN
AUSTIN, TX 78753 | **TX LPST** | **U001271103**
TX UST | **N/A**
TX HIST UST

Site 2 of 2 in cluster NR

Actual: 734 ft. LPST:

Focus Map: 6

Name:	COLD
Address:	704 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0038471
LPST Id:	108068
Facility Location:	704 WEST POWELL LANE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/03/1994
Entered Date:	05/10/1994
Reported Date:	04/03/1994
Closure Date:	11/15/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2

COLD (Continued) **U001271103**

Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BERNADINE GUTIERREZ
Responsible Party Address:	704 W POWELL LN
Responsible Party City,St,Zip:	AUSTIN, TX 78753
Responsible Party Telephone:	512/837-7783
Reported Date:	04/03/1994
Case Start Date:	11/15/1995
Reference Number:	RN101642965
Project Manager:	HWELCH

UST:

Name:	COLD
Address:	704 W POWELL LN
City,State,Zip:	AUSTIN, TX 787536253
AI Number:	38471
Facility Type:	UNKNOWN
Facility Begin Date:	01/09/1987
Facility Status:	INACTIVE
Additional ID:	453081232002069
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	VICTOR H HOULE,PRES
Contact Organization Name:	COLD
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128377783
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/07/1986
Signature Name/Title On Earliest Reg Form:	VICTOR H HOULE,PRES
Application Received Date On Earliest Reg Form:	01/09/1987
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600883409
Owner Last Name:	COLD INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

COLD (Continued) **U001271103**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	444081232002069
Additional ID:	453081232002069
AI Number:	38471
Owner Effective Begin Date:	01/09/1987
State Tax ID:	17416080111
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1977
Tank Registration Date:	01/09/1987
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	101411
Facility ID:	69515
Ai Number:	38471
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

COLD (Continued) **U001271103**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	84875
UST ID:	101411
AI Number:	38471
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

COLD (Continued) **U001271103**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	COLD INC
Contact Mailing Address (Delivery):	704 W POWELL LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 6253
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	69515
Additional ID:	453081232002069
Princ ID:	444081232002069
AI Number:	38471
Facility Name:	COLD
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COLD, INC.
Address:	704 W POWELL LN
City,State,Zip:	AUSTIN, TX
Id UST:	C0461
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MK2393 **R. A. JOHN** **TX HIST UST** **S111678782**
NNE **200 W CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.067 mi.
356 ft. **Site 5 of 6 in cluster MK**

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	R. A. JOHN
Address:	200 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0896
HID UST:	896
Inspection:	Not reported
Due:	06/01/2012

MK2394 **PAUL O. SIMMS** **TX HIST UST** **S111678775**
NNE **200 W CESAR CHAVEZ STREET ST** **N/A**
< 1/8 **AUSTIN, TX**
0.067 mi.
356 ft. **Site 6 of 6 in cluster MK**

Actual:
471 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	PAUL O. SIMMS
Address:	200 W CESAR CHAVEZ STREET ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0281
HID UST:	281
Inspection:	Not reported
Due:	06/01/2012

OA2395 **CONCRETE CORING** **TX Ind. Haz Waste** **S102749902**
East **820 W YAGER LN** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.067 mi.
356 ft. **Site 1 of 4 in cluster OA**

Actual:
694 ft.

Focus Map:
4

Ind. Haz Waste:

Name:	CONCRETE CORING
Address:	820 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66438
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD041129016
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	820 Yeager Ln, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CONCRETE CORING COMPANY
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	820 W YAGER LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787531308
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21712
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000

CONCRETE CORING (Continued) **S102749902**

Last Update to NOR Data:	20030604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CONCRETE CORING COMPANY
Operator Address:	820 W YAGER LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17514122161
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CONCRETE CORING COMPANY
Owner Mailing Address:	820 W YAGER LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17514122161
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	820 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported

CONCRETE CORING (Continued) **S102749902**

Contact Role:	OWNCON
Contact Address:	820 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	820 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

OA2396 **CONCRETE CORING** **TX Ind. Haz Waste** **S102750552**
East **820 W YAGER LN** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.067 mi.
356 ft. **Site 2 of 4 in cluster OA**

Actual:
694 ft.

Focus Map:
4

Ind. Haz Waste:

Name:	CONCRETE CORING
Address:	820 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	67361
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD041129016
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	820 Yeager Ln, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CONCRETE CORING CO
Contact Name:	FRANK DAY
Contact Telephone Number:	Not reported
Mailing Address:	820 W YAGER LN
Mailing Address2:	Not reported

CONCRETE CORING (Continued) **S102750552**

Mailing City,State,Zip:	AUSTIN, TX 787531308
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22484
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030106
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CONCRETE CORING CO
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	CONCRETE CORING COMPANY
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17514122161
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CONCRETE CORING COMPANY
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported

CONCRETE CORING (Continued) **S102750552**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17514122161
Owner Bankruptcy Code:	Not reported

Owner Name:	CONCRETE CORING CO
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	FRANK DAY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	820 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

OA2397 **COTTMAN TRANSMISSION** **EDR Hist Auto** **1022018715**
East **820 W YAGER LN** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.067 mi.
356 ft. **Site 3 of 4 in cluster OA**

Actual:
694 ft.

EDR Hist Auto

Focus Map:
4

Year:	Name:	Type:
2002	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2002	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2003	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2003	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2004	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2004	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2005	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2005	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2006	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2006	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2007	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2007	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2008	HEART OF TEXAS TRANSMISSION	Automotive Transmission Repair Shops
2008	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2009	COTTMAN TRANSMISSION	Automotive Transmission Repair Shops
2010	DESANTO ENTERPRISES INC	Automotive Transmission Repair Shops

COTTMAN TRANSMISSION (Continued) **1022018715**

2010	HEART TEXAS TRANSMISSION INC	Automotive Transmission Repair Shops
2011	DESANTO ENTERPRISES INC	Automotive Transmission Repair Shops
2012	DESANTO ENTERPRISES INC	Automotive Transmission Repair Shops
2013	DESANTO ENTERPRISES INC	Automotive Transmission Repair Shops
2014	DESANTO ENTERPRISES INC	Automotive Transmission Repair Shops

---

OB2398 **CAPITOL CLEANERS** **RCRA NonGen / NLR** **1004784900**
WNW **1408 S 1ST STREET** **FINDS** **TXD987988532**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.068 mi. **TX DRYCLEANERS**
357 ft. **Site 1 of 4 in cluster OB** **TX CENTRAL REGISTRY**

Actual:
506 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Capitol Cleaners
Handler Address:	S 1ST STREET
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD987988532
Contact Name:	EDDIE LEDESMA
Contact Address:	S 1ST STREET
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-445-4505
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S 1ST STREET
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Capitol Cleaners
Owner Type:	Private
Operator Name:	Capitol Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

CAPITOL CLEANERS (Continued) **1004784900**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CAPITOL CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	1408 S 1ST STREET
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-445-4505
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CAPITOL CLEANERS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	1408 S 1ST STREET
Owner/Operator City,State,Zip:	AUSTIN, TX 78704

CAPITOL CLEANERS (Continued) **1004784900**

Owner/Operator Telephone:	512-445-4505
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: EDDIE REDESMA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1408 S 1ST ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78704-0000
Owner/Operator Telephone:	512-445-4505
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19970812
Handler Name: CAPITOL CLNRS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010823
Handler Name: CAPITOL CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CAPITOL CLEANERS (Continued) **1004784900**

FINDS:
Registry ID: 110005116640

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004784900
Registry ID:	110005116640
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005116640
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST STREET
City,State,Zip:	AUSTIN, TX 78704

DRYCLEANERS:

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST

CAPITOL CLEANERS (Continued) **1004784900**

City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM

CAPITOL CLEANERS (Continued) **1004784900**

Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	PETROLEUM
Gallons:	220
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS

CAPITOL CLEANERS (Continued) **1004784900**

Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	220
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	PETROLEUM
Gallons:	220
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041

CAPITOL CLEANERS (Continued) **1004784900**

EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $150,000

CAPITOL CLEANERS (Continued) **1004784900**

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	420
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	420
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported

CAPITOL CLEANERS (Continued) **1004784900**

Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $150,000

CAPITOL CLEANERS (Continued) **1004784900**

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	11
CN Number:	CN602458135
DCR Number:	Not reported
AR Number:	24000518
Principal Name:	EDDIES DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	720
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN100654136
Region:	REGION 11 - AUSTIN
CN Number:	CN602458135
DCR Number:	DCR10379
AR Number:	24000518
Principal Name:	EDDIE S DIRTY LAUNDRY INC
Bill Addr1:	1408 S 1ST ST
Bill Addr2:	Not reported

CAPITOL CLEANERS (Continued) **1004784900**

Bill City/State/Zip:	AUSTIN, TX 78704 3041
EMail:	CAPITOLCLEANERS@AUSTIN.RR.COM
Phone Number:	512 4454505
Site Name:	CAPITOL CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

CENTRAL REGISTRY:

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600363592
Customer Name:	W L & L INC
Customer Legal Name:	W L & L, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1408 S 1st Street, Austin, TX

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600363592
Customer Name:	W L & L INC
Customer Legal Name:	W L & L, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1408 S 1st Street, Austin, TX

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600363592

CAPITOL CLEANERS (Continued) **1004784900**

Customer Name:	W L & L INC
Customer Legal Name:	W L & L, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1408 S 1st Street, Austin, TX

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600363592
Customer Name:	W L & L INC
Customer Legal Name:	W L & L, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1408 S 1st Street, Austin, TX

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600363592
Customer Name:	W L & L INC
Customer Legal Name:	W L & L, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1408 S 1st Street, Austin, TX

Regulated Entity Number:	RN100654136
Name:	CAPITOL CLEANERS
Address:	1408 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3041
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602458135
Customer Name:	EDDIES DIRTY LAUNDRY INC
Customer Legal Name:	Eddie's Dirty Laundry, Inc.
Customer Ownership Type:	CORPORATION

CAPITOL CLEANERS (Continued) **1004784900**

Affiliation Begin Date: 9/1/2003
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Regulated Entity Number: RN100654136
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-3041
Status: ACTIVE
Status Date: ##########
Customer Number: CN602458135
Customer Name: EDDIES DIRTY LAUNDRY INC
Customer Legal Name: Eddie's Dirty Laundry, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/2003
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Regulated Entity Number: RN100654136
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-3041
Status: ACTIVE
Status Date: ##########
Customer Number: CN602458135
Customer Name: EDDIES DIRTY LAUNDRY INC
Customer Legal Name: Eddie's Dirty Laundry, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/2003
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Regulated Entity Number: RN100654136
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-3041
Status: ACTIVE
Status Date: ##########
Customer Number: CN602458135
Customer Name: EDDIES DIRTY LAUNDRY INC
Customer Legal Name: Eddie's Dirty Laundry, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/2003
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE

CAPITOL CLEANERS (Continued) **1004784900**

Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Regulated Entity Number: RN100654136
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-3041
Status: ACTIVE
Status Date: ##########
Customer Number: CN602458135
Customer Name: EDDIES DIRTY LAUNDRY INC
Customer Legal Name: Eddie's Dirty Laundry, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/1/2003
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Regulated Entity Number: RN100654136
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-3041
Status: ACTIVE
Status Date: ##########
Customer Number: CN603912130
Customer Name: CAPITOL CLEANERS
Customer Legal Name: CAPITOL CLEANERS
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 1408 S 1st Street, Austin, TX

Click this hyperlink while viewing on your computer to access
11 additional TX CENTRAL REG: record(s) in the EDR Site Report.

OB2399 **CAPITOL CLEANERS** **TX Ind. Haz Waste** **S103609406**
WNW **1408 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.068 mi.
357 ft. **Site 2 of 4 in cluster OB**

Actual:
506 ft.

Focus Map:
14

Ind. Haz Waste:
Name: CAPITOL CLEANERS
Address: 1408 S 1ST ST
City,State,Zip: AUSTIN, TX 78704
Permit Number: Not reported
Registration Number: 76060
Registration Initial Notification Date: 03/16/1990
Registration Last Amendment Date: 08/23/2001
EPA Identification: TXD987988532

CAPITOL CLEANERS (Continued) **S103609406**

Primary NAICS Code:	Not reported
Status Change Date:	19900316
Land Type:	PRIVATE
Description of Facility Site Location:	1408 S 1st Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	CAPITOL CLEANERS
Contact Name:	EDDIE LEDESMA
Contact Telephone Number:	512-4454505
Mailing Address:	1408 S 1ST ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787043041
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30390
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020123
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CAPITOL CLEANERS
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown

CAPITOL CLEANERS (Continued) **S103609406**

Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITOL CLEANERS
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	EDDIE LEDESMA
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1408 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4454505
Contact Fax:	Not reported
Contact Email:	Not reported

OB2400 WNW < 1/8 0.068 mi. 357 ft. — **TRIPLE L INC**, **1408 S FIRST ST**, **AUSTIN, TX 78704** — **EDR Hist Cleaner** — **1018833146** / **N/A**

Site 3 of 4 in cluster OB

Actual: 506 ft.

Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1988	TRIPLE L INC	Power Laundries, Family And Commercial
1989	TRIPLE L INC	Power Laundries, Family And Commercial
1990	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1991	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1992	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1993	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1994	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1995	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1996	E M C TRIPLE L INC	Power Laundries, Family And Commercial
1997	GT INC	Power Laundries, Family And Commercial
1998	GT INC	Power Laundries, Family And Commercial
1999	GT INC	Power Laundries, Family And Commercial
2000	DRESS FOR SUCCESS CLEANERS	Drycleaning Plants, Except Rugs
2002	WL&L INC	Laundry And Drycleaner Agents
2010	EDDIES DIRTY LAUNDRY INC	Power Laundries, Family And Commercial
2011	EDDIES DIRTY LAUNDRY INC	Power Laundries, Family And Commercial
2012	EDDIES DIRTY LAUNDRY INC	Power Laundries, Family And Commercial
2013	EDDIES DIRTY LAUNDRY INC	Power Laundries, Family And Commercial
2014	EDDIES DIRTY LAUNDRY INC	Power Laundries, Family And Commercial

---

2401 WNW < 1/8 0.068 mi. 357 ft. — **JIM WIMBERLY**, **1720 S 1ST ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678705** / **N/A**

Actual: 520 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	JIM WIMBERLY
Address:	1720 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0310
HID UST:	310
Inspection:	Not reported
Due:	06/01/2012

OB2402 WNW < 1/8 0.068 mi. 357 ft. — **W. RAYMOND CANION**, **1406 S 1ST ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678848** / **N/A**

Site 4 of 4 in cluster OB

Actual: 506 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	W. RAYMOND CANION
Address:	1406 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0468
HID UST:	468
Inspection:	Not reported

W. RAYMOND CANION (Continued) **S111678848**

Due: 06/01/2012

OC2403 **SERVICE CENTER 2** **TX UST** **U001542518**
WNW **600 RIVER ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.068 mi.
357 ft. **Site 1 of 5 in cluster OC**

Actual:
462 ft.

Focus Map:
11

UST:

Name:	SERVICE CENTER 2
Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX 787014218
AI Number:	18143
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	INACTIVE
Additional ID:	100293522002133
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	,
Contact Organization Name:	SERVICE CENTER 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124800613
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1992
Signature Name/Title On Earliest Reg Form:	JOHN A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported

SERVICE CENTER 2 (Continued) **U001542518**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	100293522002133
AI Number:	18143
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3006
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46919
Facility ID:	37547
Ai Number:	18143
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/30/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

SERVICE CENTER 2 (Continued) **U001542518**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3006
UST Comprt ID:	241
UST ID:	46919
AI Number:	18143
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

SERVICE CENTER 2 (Continued) **U001542518**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7021
Cert ID:	160241
UST Comprt ID:	471538
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160243
UST Comprt ID:	471540
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160242
UST Comprt ID:	471539
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3006
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46922
Facility ID:	37547
Ai Number:	18143
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/07/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

SERVICE CENTER 2 (Continued) **U001542518**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3006
UST Comprt ID:	244
UST ID:	46922
AI Number:	18143
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

SERVICE CENTER 2 (Continued) **U001542518**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7021
Cert ID:	160241
UST Comprt ID:	471538
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160243
UST Comprt ID:	471540
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160242
UST Comprt ID:	471539
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2004
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46921
Facility ID:	37547
Ai Number:	18143

SERVICE CENTER 2 (Continued) **U001542518**

Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/30/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	2004
UST Comprt ID:	243
UST ID:	46921

SERVICE CENTER 2 (Continued) **U001542518**

AI Number:	18143
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7021
Cert ID:	160241
UST Comprt ID:	471538
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160243
UST Comprt ID:	471540
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160242

SERVICE CENTER 2 (Continued) **U001542518**

UST Comprt ID:	471539
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2004
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46920
Facility ID:	37547
Ai Number:	18143
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/07/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

SERVICE CENTER 2 (Continued) **U001542518**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	2004
UST Comprt ID:	242
UST ID:	46920
AI Number:	18143
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

SERVICE CENTER 2 (Continued) **U001542518**

Self Cert ID:	7021
Cert ID:	160241
UST Comprt ID:	471538
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160243
UST Comprt ID:	471540
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7021
Cert ID:	160242
UST Comprt ID:	471539
UST ID:	154552
AI Number:	18143
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37547
Additional ID:	100293522002133
Princ ID:	840354562001227
AI Number:	18143
Facility Name:	SERVICE CENTER 2
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COA SERVICE CENTER #02
Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX
Id UST:	200
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OC2404 **CITY OF AUSTIN FLEET SERVICES** **RCRA NonGen / NLR** **1000412198**
WNW **600 RIVER ST** **FINDS** **TXD981901523**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.068 mi.
357 ft. **Site 2 of 5 in cluster OC**

Actual:
462 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	City Of Austin Fleet Services
Handler Address:	RIVER ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981901523
Contact Name:	JIM ELMAN
Contact Address:	PO BOX 1088
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-499-8331
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1088
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	City Of Austin Fleet Services
Owner Type:	Not reported
Operator Name:	City Of Austin Fleet Services
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CITY OF AUSTIN FLEET SERVICES (Continued) **1000412198**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CITY OF AUSTIN FLEET SERVICES
Legal Status:	Not reported
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1088
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-499-8331
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CITY OF AUSTIN FLEET SERVICES (Continued) **1000412198**

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN FLEET SERVICES
Legal Status: Not reported
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1088
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-499-8331
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 600 RIVER ST
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-478-0867
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870126
Handler Name: CITY OF AUSTIN SVC CNTR
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: CITY OF AUSTIN FLEET SERVICES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: AUSTIN CITY SC2
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CITY OF AUSTIN FLEET SERVICES (Continued) **1000412198**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005097448

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000412198
Registry ID: 110005097448
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005097448
Name: CITY OF AUSTIN FLEET SERVICES
Address: 600 RIVER ST
City,State,Zip: AUSTIN, TX 78701

OC2405 **CITY OF AUSTIN SERVICE CENTER 2 TWO** **TX Ind. Haz Waste** **S110294482**
WNW **600 RIVER ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.068 mi.
357 ft. **Site 3 of 5 in cluster OC**

Actual:
462 ft.

Focus Map:
11

Ind. Haz Waste:
Name: CITY OF AUSTIN SERVICE CENTER 2 TWO
Address: 600 RIVER ST
City,State,Zip: AUSTIN, TX 78701
Permit Number: Not reported
Registration Number: 81211
Registration Initial Notification Date: 08/31/1993
Registration Last Amendment Date: 05/02/1996
EPA Identification: Not reported

CITY OF AUSTIN SERVICE CENTER 2 TWO (Continued) **S110294482**

Primary NAICS Code:	Not reported
Status Change Date:	20120523
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CITY OF AUSTIN
Contact Name:	EDWARD A HEJL
Contact Telephone Number:	512-4780867
Mailing Address:	600 RIVER ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787014218
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	36118
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20120523
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

CITY OF AUSTIN SERVICE CENTER 2 TWO (Continued) **S110294482**

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	EDWARD HEJL
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	600 RIVERST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4780867
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	72251
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste petroleum naphtha waste from circulating parts cleaner, May 20, 1991.
Standard Industrial Code:	75380
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811111
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

CITY OF AUSTIN SERVICE CENTER 2 TWO (Continued) **S110294482**

Ind. Haz Waste:

Contact Name:	EDWARD HEJL
Contact Title:	MANAGER
Contact Telephone:	1-512-4780867 x0
Mailing Address:	600 RIVER ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000317156
Principal Name:	CITY OF AUSTIN
Attention Name:	HEJL ,EDWARD
Attention Suffix:	NWG

Contact Name:	EDWARD HEJL
Contact Title:	MANAGER
Contact Telephone:	1-512-4780867 x0
Mailing Address:	600 RIVER ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000317156
Principal Name:	CITY OF AUSTIN
Attention Name:	HEJL ,EDWARD
Attention Suffix:	HWG

OC2406 **SERVICE CENTER 2** **TX SWF/LF** **S104273859**
WNW **600 RIVER ST** **TX LPST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX Ind. Haz Waste**
0.068 mi.
357 ft. **Site 4 of 5 in cluster OC**

Actual:
462 ft.

Focus Map:
11

SWF/LF:

Name:	ESB - MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX 78701-4218
Region:	11
Permit Number:	67078
Facility Status:	NOT CONSTRUCTED
Facility Type:	SUBT
Permit Status:	ISSUED
Status Date:	09/03/2021
Mailing Address:	Not reported
Client Name:	Not reported
Client Address:	Not reported
Client Telephone:	N/A
Business Type:	Not reported
Area Served:	Not reported
Estimated Closure Date:	Not reported
Permit Acreage:	Not reported
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	0.00000 / 0.00000

Name:	ESB MEXICAN AMERICAN CULTURAL CENTER

SERVICE CENTER 2 (Continued) **S104273859**

Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX 78701-4218
Region:	11
Permit Number:	67101
Facility Status:	NOT CONSTRUCTED
Facility Type:	SUBT
Permit Status:	ISSUED
Status Date:	02/13/2023
Mailing Address:	Not reported
Client Name:	Not reported
Client Address:	Not reported
Client Telephone:	N/A
Business Type:	Not reported
Area Served:	Not reported
Estimated Closure Date:	Not reported
Permit Acreage:	Not reported
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	0.00000 / 0.00000

LPST:

Name:	SERVICE CENTER 2
Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX 78767
Facility ID:	0018143
LPST Id:	091466
Facility Location:	600 RIVER ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/08/1987
Entered Date:	09/16/1987
Reported Date:	09/16/1987
Closure Date:	06/05/1990
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	PAM CHAPPELL
Responsible Party Name:	Not reported
Responsible Party Contact:	L ARREDONDO
Responsible Party Address:	PO BOX 1088
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	512/499-2737
Reported Date:	09/16/1987
Case Start Date:	06/05/1990
Reference Number:	RN102125515
Project Manager:	PEC

Ind. Haz Waste:

Name:	SERVICE CENTER 2

SERVICE CENTER 2 (Continued) **S104273859**

Address:	600 RIVER ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72383
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TXD981901523
Primary NAICS Code:	811111
Status Change Date:	19870501
Land Type:	Not reported
Description of Facility Site Location:	600 River St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	CITY OF AUSTIN
Contact Name:	JIM ELMAN
Contact Telephone Number:	512-4998331
Mailing Address:	PO BOX 1088
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671088
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26824
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031104
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported

SERVICE CENTER 2 (Continued) **S104273859**

Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	JIM ELMAN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1088
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4998331
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	147395
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste petroleum naphtha waste from circulating parts cleaner, May 20, 1991.
Standard Industrial Code:	75380
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811111
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

SERVICE CENTER 2 (Continued) **S104273859**

Ind. Haz Waste:

Ind. Haz Waste:

OC2407 **EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER** **US BROWNFIELDS** **1027609031**
WNW **600 RIVER STREET** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.068 mi.
357 ft. **Site 5 of 5 in cluster OC**

Actual:
462 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER STREET
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	190772, 190753, 190764, 190763, 190762, 190761, 190760
Parcel size:	4
Latitude:	30.25839298
Longitude:	-97.74032703
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The idea of establishing a cultural facility for Latino artists and the community emerged in the early 1970s. Several Hispanic visionaries and artists approached the City of Austin to request support for the development of a Hispanic focused cultural arts facility. In 1986, the City Council appointed a task force to determine the feasibility of building a Mexican American Cultural Center. In 1992, the center was part of the citywide bond package put before the voters. The referendum did not pass. By 1998, the community had regrouped and with the leadership provided by Hispanic elected officials and other leaders of the community, the 1999 bond package was approved by the voters. A Master Plan for the Mexican American Cultural Center was also developed with input from the community and from various Mexican American arts organizations. The long-awaited groundbreaking ceremony took place in November of 2005. Construction of the Mexican American Cultural Center began in January of 2006, and the facility was completed in June of 2007. The reality of the long-time dream was finalized on September 15, 2007, with a ribbon cutting ceremony attended by thousands from the community Currently, the ESB-MACC building, a large patio/open terrace, walking trails, and gardens are on the site. Portions of the property are currently undeveloped which is where the expansion/second phase of the ESB-MACC development will be taking place. Following the site's Master Plan, the ESB MACC is beginning work on Phase 2 of the 2018 Facility Expansion Plan (2018 Plan) approved by City Council. Phase 2 includes expansion and renovation of the facility in addition to site improvements to meet the growing needs of the community. This facility has become an iconic cultural hub for the Mexican-American community and is seeking expansion following growing and continuing community engagement. A groundbreaking ceremony is being planned for

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

	December when the building closes for construction to begin. Completion of Phase 2 construction is estimated to take place over the next several years with a grand opening in early 2025.
Datum:	Not reported
Acres Property ID:	253498
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	3
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER STREET
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	190772, 190753, 190764, 190763, 190762, 190761, 190760
Parcel size:	4
Latitude:	30.25839298
Longitude:	-97.74032703
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The idea of establishing a cultural facility for Latino artists and the community emerged in the early 1970s. Several Hispanic visionaries and artists approached the City of Austin to request support for the development of a Hispanic focused cultural arts facility. In 1986, the City Council appointed a task force to determine the feasibility of building a Mexican American Cultural Center. In 1992, the center was part of the citywide bond package put before the voters. The referendum did not pass. By 1998, the community had regrouped and with the leadership provided by Hispanic elected officials and other leaders of the community, the 1999 bond package was approved by the voters. A Master Plan for the Mexican American Cultural Center was also developed with input from the community and from various Mexican American arts organizations. The long-awaited groundbreaking ceremony took place in November of 2005. Construction of the Mexican American Cultural Center began in January of 2006, and the facility was completed in June of 2007. The reality of the long-time dream was finalized on September 15, 2007, with a ribbon cutting ceremony attended by thousands from the community Currently, the ESB-MACC building, a large patio/open terrace, walking trails, and gardens are on the site. Portions of the property are currently undeveloped which is where the expansion/second phase of the ESB-MACC development will be taking place. Following the site's Master Plan, the ESB MACC is beginning work on Phase 2 of the 2018 Facility Expansion Plan (2018 Plan) approved by City Council. Phase 2 includes expansion and renovation of the facility in addition to site improvements to meet the growing needs of the community. This facility has become an iconic cultural hub for the Mexican-American community and is seeking expansion following growing and continuing community engagement. A groundbreaking ceremony is being planned for December when the building closes for construction to begin. Completion of Phase 2 construction is estimated to take place over the next several years with a grand opening in early 2025.
Datum:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Acres Property ID:	253498
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	3
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER STREET
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	190772, 190753, 190764, 190763, 190762, 190761, 190760
Parcel size:	4
Latitude:	30.25839298
Longitude:	-97.74032703
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The idea of establishing a cultural facility for Latino artists and the community emerged in the early 1970s. Several Hispanic visionaries and artists approached the City of Austin to request support for the development of a Hispanic focused cultural arts facility. In 1986, the City Council appointed a task force to determine the feasibility of building a Mexican American Cultural Center. In 1992, the center was part of the citywide bond package put before the voters. The referendum did not pass. By 1998, the community had regrouped and with the leadership provided by Hispanic elected officials and other leaders of the community, the 1999 bond package was approved by the voters. A Master Plan for the Mexican American Cultural Center was also developed with input from the community and from various Mexican American arts organizations. The long-awaited groundbreaking ceremony took place in November of 2005. Construction of the Mexican American Cultural Center began in January of 2006, and the facility was completed in June of 2007. The reality of the long-time dream was finalized on September 15, 2007, with a ribbon cutting ceremony attended by thousands from the community Currently, the ESB-MACC building, a large patio/open terrace, walking trails, and gardens are on the site. Portions of the property are currently undeveloped which is where the expansion/second phase of the ESB-MACC development will be taking place. Following the site's Master Plan, the ESB MACC is beginning work on Phase 2 of the 2018 Facility Expansion Plan (2018 Plan) approved by City Council. Phase 2 includes expansion and renovation of the facility in addition to site improvements to meet the growing needs of the community. This facility has become an iconic cultural hub for the Mexican-American community and is seeking expansion following growing and continuing community engagement. A groundbreaking ceremony is being planned for December when the building closes for construction to begin. Completion of Phase 2 construction is estimated to take place over the next several years with a grand opening in early 2025.
Datum:	Not reported
Acres Property ID:	253498
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	3
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported
Name:	EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER STREET
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	190772, 190753, 190764, 190763, 190762, 190761, 190760
Parcel size:	4
Latitude:	30.25839298
Longitude:	-97.74032703
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The idea of establishing a cultural facility for Latino artists and the community emerged in the early 1970s. Several Hispanic visionaries and artists approached the City of Austin to request support for the development of a Hispanic focused cultural arts facility. In 1986, the City Council appointed a task force to determine the feasibility of building a Mexican American Cultural Center. In 1992, the center was part of the citywide bond package put before the voters. The referendum did not pass. By 1998, the community had regrouped and with the leadership provided by Hispanic elected officials and other leaders of the community, the 1999 bond package was approved by the voters. A Master Plan for the Mexican American Cultural Center was also developed with input from the community and from various Mexican American arts organizations. The long-awaited groundbreaking ceremony took place in November of 2005. Construction of the Mexican American Cultural Center began in January of 2006, and the facility was completed in June of 2007. The reality of the long-time dream was finalized on September 15, 2007, with a ribbon cutting ceremony attended by thousands from the community Currently, the ESB-MACC building, a large patio/open terrace, walking trails, and gardens are on the site. Portions of the property are currently undeveloped which is where the expansion/second phase of the ESB-MACC development will be taking place. Following the site's Master Plan, the ESB MACC is beginning work on Phase 2 of the 2018 Facility Expansion Plan (2018 Plan) approved by City Council. Phase 2 includes expansion and renovation of the facility in addition to site improvements to meet the growing needs of the community. This facility has become an iconic cultural hub for the Mexican-American community and is seeking expansion following growing and continuing community engagement. A groundbreaking ceremony is being planned for December when the building closes for construction to begin. Completion of Phase 2 construction is estimated to take place over the next several years with a grand opening in early 2025.
Datum:	Not reported
Acres Property ID:	253498
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Assessment Funding:	3900
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F96301
Start Date:	5/6/2022
Ownership Entity:	Government
Completion Date:	9/8/2022
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	3
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Name:	EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER
Address:	600 RIVER STREET
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	190772, 190753, 190764, 190763, 190762, 190761, 190760
Parcel size:	4
Latitude:	30.25839298
Longitude:	-97.74032703
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The idea of establishing a cultural facility for Latino artists and the community emerged in the early 1970s. Several Hispanic visionaries and artists approached the City of Austin to request support for the development of a Hispanic focused cultural arts facility. In 1986, the City Council appointed a task force to determine the feasibility of building a Mexican American Cultural Center. In 1992, the center was part of the citywide bond package put before the voters. The referendum did not pass. By 1998, the community had regrouped and with the leadership provided by Hispanic elected officials and other leaders of the community, the 1999 bond package was approved by the voters. A Master Plan for the Mexican American Cultural Center was also developed with input from the community and from various Mexican American arts organizations. The long-awaited groundbreaking ceremony took place in November of 2005. Construction of the Mexican American Cultural Center began in January of 2006, and the facility was completed in June of 2007. The reality of the long-time dream was finalized on September 15, 2007, with a ribbon cutting ceremony attended by thousands from the community Currently, the ESB-MACC building, a large patio/open terrace, walking trails, and gardens are on the site. Portions of the property are currently undeveloped which is where the expansion/second phase of the ESB-MACC development will be taking place. Following the site's Master Plan, the ESB MACC is beginning work on Phase 2 of the 2018 Facility Expansion Plan (2018 Plan) approved by City Council. Phase 2 includes expansion and renovation of the facility in addition to site improvements to meet the growing needs of the community. This facility has become an iconic cultural hub for the Mexican-American community and is seeking expansion following growing and continuing community engagement. A groundbreaking ceremony is being planned for December when the building closes for construction to begin. Completion of Phase 2 construction is estimated to take place over the next several years with a grand opening in early 2025.
Datum:	Not reported
Acres Property ID:	253498
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported

EMMA BARRIENTOS MEXICAN AMERICAN CULTURAL CENTER (Continued) **1027609031**

Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	3
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

LG2408 SSW < 1/8 0.068 mi. 358 ft. — **417 19 PATTON AUTO LIVE & TRANSFER CO**, **417 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013752883** / **N/A**

Site 25 of 26 in cluster LG

Actual: 487 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	417 19 PATTON AUTO LIVE & TRANS	AUTOMOBILE GARAGES
1922	417 19 PATTON AUTO LIVE & TRANS	AUTOMOBILE SERVICE STATIONS
1922	417 19 PATTON AUTO LIVE & TRANS	AUTOMOBILE SERVICE
1922	417 19 PATTON AUTO LIVE & TRANS	AUTOMOBILE REPAIRERS

NG2409 WNW < 1/8 0.068 mi. 358 ft. — **ESTES & CO AUTO**, **216 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013754192** / **N/A**

Site 6 of 16 in cluster NG

Actual: 497 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	ESTES & CO AUTO	AUTOMOBILE REPAIRERS
1922	ESTES & CO AUTO	AUTOMOBILE GARAGES

NG2410 WNW < 1/8 0.068 mi. 358 ft. — **FIEGELS GARAGE**, **217 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013754104** / **N/A**

Site 7 of 16 in cluster NG

Actual: 497 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1916	FIEGELS GARAGE	AUTOMOBILE REPAIRERS
1916	FIEGELS GARAGE	AUTOMOBILE GARAGES

NZ2411 NE < 1/8 0.068 mi. 358 ft. — **BETHKE BRAKE SERVICE**, **617 E 7TH ST**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013771487** / **N/A**

Site 2 of 4 in cluster NZ

Actual: 469 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1970	BETHKE BRAKE SERVICE	AUTOMOBILE REPAIRING
1970	BETHKE BRAKE SERVICE	BRAKE SERVICE
1970	BETHKE BRAKE SERVICE	General Automotive Repair Shops
1971	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1972	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1973	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1974	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1975	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1976	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1977	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC

BETHKE BRAKE SERVICE (Continued) **1013771487**

1978	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1979	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1980	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1982	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1983	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1985	BETHKE BRAKE SERVICE	Automotive Repair Shops, NEC
1986	BETHKE BRAKE SERVICE INC	Automotive Repair Shops, NEC
1987	BETHKE BRAKE SERVICE INC	Automotive Repair Shops, NEC
1988	BETHKE BRAKE SERVICE INC	Automotive Repair Shops, NEC
1992	BETHKE BRAKE SERVICE INC	Brake Services
1993	BETHKE BRAKE SERVICE INC	Brake Services
1994	BETHKE BRAKE SERVICE INC	Brake Services
1995	BETHKE BRAKE SERVICE INC	Brake Services
1996	BETHKE BRAKE SERVICE INC	Brake Services
1997	BETHKE BRAKE SERVICE INC	Brake Services
1998	BETHKE BRAKE SERVICE INC	Brake Services
1999	BETHKE BRAKE SERVICE INC	Brake Services
2000	BETHKE BRAKE SERVICE INC	Brake Services
2001	BETHKE BRAKE SERVICE INC	Brake Services
2002	BETHKE BRAKE SERVICE INC	Brake Services
2003	BETHKE BRAKE SERVICE INC	Brake Services
2004	BETHKE BRAKE SERVICE INC	Brake Services

LF2412 **LONGHORN CLNRS** **RCRA-SQG** **1000836852**
East **510 W MARTIN LUTHUR KING** **FINDS** **TXD988081204**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.068 mi.
359 ft. **Site 6 of 7 in cluster LF**

Actual:
557 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	19921216
Handler Name:	Longhorn Clnrs
Handler Address:	W MARTIN LUTHUR KING
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD988081204
Contact Name:	ROBERT LUDWIG
Contact Address:	510 W MARTIN LUTHUR KING
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-442-7463
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	W MARTIN LUTHUR KING
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Donnie Williams
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

LONGHORN CLNRS (Continued) **1000836852**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: F002

Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Owner

Owner/Operator Name: DONNIE WILLIAMS

LONGHORN CLNRS (Continued) **1000836852**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	510 W MARTIN LUTHUR KING
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-442-7463
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19921216
Handler Name: LONGHORN CLNRS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005155553

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836852
Registry ID:	110005155553
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005155553
Name:	LONGHORN CLNRS
Address:	510 W MARTIN LUTHUR KING

LONGHORN CLNRS (Continued) **1000836852**

City,State,Zip: AUSTIN, TX 78701

2413 WNW < 1/8 0.068 mi. 360 ft. | **MORGAN PRINTING**
900 OLD KOENIG LANE NO 135
AUSTIN, TX 78756 | **RCRA NonGen / NLR**
FINDS
ECHO
TX Ind. Haz Waste | **1001225754**
TXR000025924

Actual: 714 ft.

Focus Map: 8

RCRA Listings:

Date Form Received by Agency:	20061121
Handler Name:	Morgan Printing
Handler Address:	OLD KOENIG LANE NO 135
Handler City,State,Zip:	AUSTIN, TX 78756
EPA ID:	TXR000025924
Contact Name:	MARK S HILLIS
Contact Address:	OLD KOENIG LANE NO 135
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Telephone:	512-459-5194
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	OLD KOENIG LANE NO 135
Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Name:	Morgan Printing
Owner Type:	Private
Operator Name:	Morgan Printing
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

MORGAN PRINTING (Continued) **1001225754**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20061204
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D011
Waste Description:	Silver

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MIKE MORGAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	900 OLD KOENIG LANE STE 135
Owner/Operator City,State,Zip:	AUSTIN, TX 78756
Owner/Operator Telephone:	512-459-5194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MORGAN PRINTING	
Legal Status:	Not reported
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 144
Owner/Operator City,State,Zip:	PORTLAND, CT 06480
Owner/Operator Telephone:	512-459-5194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MORGAN PRINTING	
Legal Status:	Private
Date Became Current:	20061108
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 144
Owner/Operator City,State,Zip:	PORTLAND, CT 06480

MORGAN PRINTING (Continued) **1001225754**

Owner/Operator Telephone:	512-459-5194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MORGAN PRINTING	
Legal Status:	Private
Date Became Current:	20061108
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 144
Owner/Operator City,State,Zip:	PORTLAND, CT 06480
Owner/Operator Telephone:	512-459-5194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MORGAN PRINTING	
Legal Status:	Not reported
Date Became Current:	20010726
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 144
Owner/Operator City,State,Zip:	PORTLAND, CT 06480
Owner/Operator Telephone:	512-459-5194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19980303
Handler Name: MORGAN PRINTING	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010726
Handler Name: MORGAN PRINTING	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20061121

MORGAN PRINTING (Continued) **1001225754**

Handler Name: MORGAN PRINTING
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32311
NAICS Description: PRINTING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005180785

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001225754
Registry ID: 110005180785
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005180785
Name: MORGAN PRINTING
Address: 900 OLD KOENIG LANE NO 135
City,State,Zip: AUSTIN, TX 78756

Ind. Haz Waste:
Name: MORGAN PRINTING
Address: 900 OLD KOENIG LN STE 135
City,State,Zip: AUSTIN, TX 78756
Permit Number: Not reported
Registration Number: 85575
Registration Initial Notification Date: 02/24/1998
Registration Last Amendment Date: 11/02/2017
EPA Identification: TXR000025924

MORGAN PRINTING (Continued) **1001225754**

Primary NAICS Code:	323110
Status Change Date:	19980224
Land Type:	PRIVATE
Description of Facility Site Location:	900 OLD KOENIG LANE NO 135 AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUGUSTINE INCORPORATED
Contact Name:	MARK S HILLIS
Contact Telephone Number:	512-4595194
Mailing Address:	900 OLD KOENIG LN STE 135
Mailing Address2:	NO 135
Mailing City,State,Zip:	AUSTIN, TX 787561514
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	107273
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20171229
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUGUSTINE INCORPORATED
Operator Address:	PO BOX 144
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	PORTLAND, CT 06480
Operator Country:	UNITED STA
Operator Telephone:	1-512-4595194
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation

MORGAN PRINTING (Continued) **1001225754**

Operator Tax ID:	17425859521
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUGUSTINE INCORPORATED
Owner Mailing Address:	PO BOX 144
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	PORTLAND, CT 06480
Owner Country:	UNITED STA
Owner Telephone:	1-512-4595194
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17425859521
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	010
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Storage of drums (waste)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19980224
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 144
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	PORTLAND, CT 06480
Contact Phone:	1-512-4595194
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported

MORGAN PRINTING (Continued) **1001225754**

Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 144
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	PORTLAND, CT 06480
Contact Phone:	1-512-4595194
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MARK HILLIS
Contact Title:	VICE PRESIDENT
Contact Role:	PRICONT
Contact Address:	900 OLDKOENIG LN STE 135
Contact Address 2:	NO 135
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4595194
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	168413
Texas Waste Code:	Not reported
Texas Waste Code 2:	0629119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Photo fixer silver solution from developing and printing operations. Recycling n
Standard Industrial Code:	27520
Primary Source:	G25
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323110
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

NW2414 WNW < 1/8 0.068 mi. 361 ft. | **CONVENIENCE COIN LAUNDRY COIN OPERATED** | **EDR Hist Cleaner** | **1013782764** **N/A**
817 12TH ST W
TRAVIS (County), TX 78701
Site 2 of 5 in cluster NW

Actual: 491 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1975	CONVENIENCE COIN LAUNDRY COIN O	LAUNDRIES-SELF SERVE
1980	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

LV2415 ESE < 1/8 0.069 mi. 363 ft. | **CONVENIENCE COIN LAUNDRY NO** | **EDR Hist Cleaner** | **1013786775** **N/A**
101 E 38TH ST
AUSTIN, TX 78705
Site 8 of 9 in cluster LV

Actual: 609 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1984	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

LK2416 ESE < 1/8 0.069 mi. 364 ft. | **RIEGERS GARAGE AUTO REPR** | **EDR Hist Auto** | **1013767380** **N/A**
513 LAVACA
AUSTIN, TX
Site 7 of 10 in cluster LK

Actual: 498 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	RIEGERS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

LK2417 ESE < 1/8 0.069 mi. 364 ft. | **REIGER MOTOR SALES** | **EDR Hist Auto** | **1013773576** **N/A**
505 LAVACA
AUSTIN, TX
Site 8 of 10 in cluster LK

Actual: 497 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	REIGER MOTOR SALES	AUTOMOBILE REPAIRING

OD2418 SSW < 1/8 0.069 mi. 364 ft. | **EARL E. SIMMS** | **TX HIST UST** | **S111678635** **N/A**
119 E 5TH ST
AUSTIN, TX
Site 1 of 3 in cluster OD

Actual: 485 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	EARL E. SIMMS
Address:	119 E 5TH ST
City,State,Zip:	AUSTIN, TX

EARL E. SIMMS (Continued) **S111678635**

Id UST:	H0285
HID UST:	285
Inspection:	Not reported
Due:	06/01/2012

JY2419 **29WAT R907222** **TX UST** **U001287723**
NNE **4TH & COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.069 mi.
364 ft. **Site 6 of 6 in cluster JY**

Actual:
483 ft.

Focus Map:
11

UST:

Name:	29WAT R907222
Address:	4TH & COLORADO
City,State,Zip:	AUSTIN, TX
AI Number:	57898
Facility Type:	Not reported
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	391476382002133
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	4TH & COLORADO
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DON BABEL,
Contact Organization Name:	29WAT R907222
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123972690
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/27/1991
Signature Name/Title On Earliest Reg Form:	EDWARD MCGARRAHAN,REAL ESTATE MGR
Application Received Date On Earliest Reg Form:	04/01/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600845093
Owner Last Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

29WAT R907222 (Continued) **U001287723**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	31443472002064
Additional ID:	391476382002133
AI Number:	57898
Owner Effective Begin Date:	01/31/1995
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/01/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	138545
Facility ID:	85716
Ai Number:	57898
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	07/14/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

29WAT R907222 (Continued) **U001287723**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/13/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	132081
UST ID:	138545
AI Number:	57898
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

29WAT R907222 (Continued) **U001287723**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Contact Mailing Address (Delivery):	1910 PACIFIC AVE STE 1300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75201 4529
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85716
Additional ID:	391476382002133
Princ ID:	31443472002064
AI Number:	57898
Facility Name:	29WAT R907222
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SHARON K ALLEN/

NL2420 **EAST 9TH STREET COMPANY LP** **EDR Hist Auto** **1021718663**
SSW **115 E 5TH ST STE 200** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.069 mi.
364 ft. **Site 2 of 5 in cluster NL**

Actual:
485 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2001	EAST 9TH STREET COMPANY LP	Gasoline Service Stations
2002	EAST 9TH STREET COMPANY LP	Gasoline Service Stations

LK2421 **MC CUTCHEON U S AUTO REPR** **EDR Hist Auto** **1013766881**
ESE **503 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.069 mi.
364 ft. **Site 9 of 10 in cluster LK**

Actual:
497 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	MC CUTCHEON U S AUTO REPR	AUTOMOBILE REPAIRERS

LK2422 ESE < 1/8 0.069 mi. 365 ft. — **AUSTIN BTRY & ELEC**, **501 LAVACA**, **AUSTIN, TX** — **EDR Hist Auto** — **1013774386** / **N/A**

Site 10 of 10 in cluster LK

Actual: 496 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	MC CUTCHEAN & DEATS	AUTOMOBILE REPAIRERS
1940	MORROWS MAGNOLIA	GASOLINE AND OIL SERVICE STATIONS
1947	KOCUREK SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	AUSTIN BTRY & ELEC	GASOLINE STATIONS

OE2423 WNW < 1/8 0.069 mi. 365 ft. — **CAPITOL LAUNDRY & DRY**, **806 KOENIG LN W**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013782696** / **N/A**

Site 1 of 4 in cluster OE

Actual: 708 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1965	CAPITOL LAUNDRY & DRY	LAUNDRIES

2424 NNE < 1/8 0.069 mi. 365 ft. — **AUTOMATIC TRANSMISSION CENTER**, **211 4TH ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013771354** / **N/A**

Actual: 483 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	AUTOMATIC TRANSMISSION CENTER	AUTOMOBILE REPAIRING

MQ2425 ENE < 1/8 0.070 mi. 367 ft. — **DELWOOD CLNS**, **3925 EAST AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013782851** / **N/A**

Site 12 of 18 in cluster MQ

Actual: 589 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1953	DELWOOD CLNS	CLEANERS AND DYERS
1958	DELWOOD CLNS	CLEANERS AND DYERS

NS2426 **KELLY SMITH CLEANERS** **EDR Hist Cleaner** **1013784799**
West **511 MARTIN LUTHER KING JR BLVD W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.070 mi.
368 ft. **Site 2 of 4 in cluster NS**

Actual: EDR Hist Cleaner
552 ft.

Focus Map: 11

Year:	Name:	Type:
1980	KELLY SMITH CLEANERS	CLEANERS AND DYERS
1984	KELLY SMITH CLEANERS	CLEANERS AND DYERS

OF2427 **COVERT BUICK INC** **EDR Hist Auto** **1013756993**
WNW **500 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.070 mi.
368 ft. **Site 1 of 8 in cluster OF**

Actual: EDR Hist Auto
482 ft.

Focus Map: 11

Year:	Name:	Type:
1984	COVERT BUICK INC	AUTOMOBILE REPAIRING

2428 **BATH CREST OF AUSTIN INC BATHROOM FIXTURES RET** **EDR Hist Cleaner** **1013781301**
WNW **111 RAMBLE LN** **N/A**
< 1/8 **TRAVIS (County), TX 78745**
0.070 mi.
369 ft.

Actual: EDR Hist Cleaner
611 ft.

Focus Map: 17

Year:	Name:	Type:
1990	BATH CREST OF AUSTIN INC BATHRO	CARPET AND RUG CLEANERS

NA2429 **PEARSON WESLEY H** **EDR Hist Auto** **1013755155**
SSW **313 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.070 mi.
369 ft. **Site 8 of 12 in cluster NA**

Actual: EDR Hist Auto
451 ft.

Focus Map: 11

Year:	Name:	Type:
1953	PEARSON WESLEY H	GASOLINE STATIONS

NA2430 **PEARSON WESLEY H FILLING ST** **EDR Hist Auto** **1013767242**
SSW **313 CONGRESS AVE S** **N/A**
< 1/8 **AUSTIN, TX**
0.070 mi.
369 ft. **Site 9 of 12 in cluster NA**

Actual: EDR Hist Auto
451 ft.

Focus Map: 11

Year:	Name:	Type:
1940	PEARSON WESLEY H FILLING ST	GASOLINE AND OIL SERVICE STATIONS

MP2431 **CORLEY & BERRY SERVICE STA FILLING** **EDR Hist Auto** **1013759410**
ESE **1701 LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.070 mi.
370 ft. **Site 3 of 4 in cluster MP**

Actual:
561 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1935	GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS
1940	CORLEY & BERRY SERVICE STA FILL	GASOLINE AND OIL SERVICE STATIONS
1947	BERRYS GULF SERV STA BATTERIES	GASOLINE AND OIL SERVICE STATIONS
1953	BERRY 0 L GULF STA	GASOLINE STATIONS
1958	BERRY 0 L GULF	GASOLINE STATIONS
1962	MAXWELL TEXACO	GASOLINE STATIONS
1965	MAXWELL TEXACO SERVICE	GASOLINE STATIONS

MP2432 **M D PHARMACY** **TX LPST** **U001294250**
ESE **1701 LAVACA ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX HIST UST**
0.070 mi.
370 ft. **Site 4 of 4 in cluster MP**

Actual:
561 ft.

Focus Map:
11

LPST:

Name:	M D PHARMACY
Address:	1701 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0063341
LPST Id:	103931
Facility Location:	1701 LAVACA
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/20/1992
Entered Date:	08/09/1992
Reported Date:	07/21/1992
Closure Date:	09/09/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	VIRGINIA ROBERTSON
Responsible Party Address:	999 NW GRAND BLVD STE 200
Responsible Party City,St,Zip:	OKLAHOMA CITY, OK 73118 6077
Responsible Party Telephone:	214/701-7249
Reported Date:	07/21/1992
Case Start Date:	09/09/1992
Reference Number:	RN102233913
Project Manager:	HWELCH

UST:

Name:	M D PHARMACY
Address:	1701 LAVACA ST
City,State,Zip:	AUSTIN, TX 787011315
AI Number:	63341

M D PHARMACY (Continued) **U001294250**

Facility Type:	Not reported
Facility Begin Date:	07/22/1992
Facility Status:	INACTIVE
Additional ID:	645740392002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MARIE WEBB,MANAGER
Contact Organization Name:	M D PHARMACY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2147017249
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/14/1992
Signature Name/Title On Earliest Reg Form:	JOHN D COCHRAN,
Application Received Date On Earliest Reg Form:	07/21/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600845093
Owner Last Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	31443472002064
Additional ID:	645740392002138
AI Number:	63341
Owner Effective Begin Date:	07/22/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

M D PHARMACY (Continued) **U001294250**

Install Date:	08/31/1987
Tank Registration Date:	07/21/1992
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146285
Facility ID:	89743
Ai Number:	63341
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

M D PHARMACY (Continued) **U001294250**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	138563
UST ID:	146285
AI Number:	63341
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/1992
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146286

M D PHARMACY (Continued) **U001294250**

Facility ID:	89743
Ai Number:	63341
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported

M D PHARMACY (Continued) **U001294250**

UST Comprt ID:	138564
UST ID:	146286
AI Number:	63341
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/1992
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146287
Facility ID:	89743
Ai Number:	63341
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

M D PHARMACY (Continued) **U001294250**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	138565
UST ID:	146287
AI Number:	63341
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

M D PHARMACY (Continued) **U001294250**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/1992
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146288
Facility ID:	89743
Ai Number:	63341
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

M D PHARMACY (Continued) **U001294250**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	5
Tank Capacity:	Not reported
UST Comprt ID:	138566
UST ID:	146288
AI Number:	63341
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

M D PHARMACY (Continued) **U001294250**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/21/1992
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146289
Facility ID:	89743
Ai Number:	63341
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

M D PHARMACY (Continued) **U001294250**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	138567
UST ID:	146289
AI Number:	63341
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

M D PHARMACY (Continued) **U001294250**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Contact Mailing Address (Delivery):	1910 PACIFIC AVE STE 1300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75201 4529
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89743
Additional ID:	645740392002138
Princ ID:	31443472002064
AI Number:	63341
Facility Name:	M D PHARMACY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SHARON K ALLEN/

HIST UST AUSTIN:

Name:	M D PHARMACY
Address:	1701 LAVACA ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0329
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2433 ESE < 1/8 0.070 mi. 370 ft. | **HOPF WOLBERT VAULT CO.**
4515 S CONGRESS AVE
AUSTIN, TX | **TX HIST UST** | **S111678679**
N/A

Actual: 635 ft.
Focus Map: 17

HIST UST AUSTIN:

Name:	HOPF WOLBERT VAULT CO.
Address:	4515 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0716
HID UST:	716
Inspection:	06/06/2012
Due:	06/06/2015

OF2434 WNW < 1/8 0.070 mi. 371 ft. | **AUSTIN FEDERAL COURTHOUSE**
501 W 5TH ST
AUSTIN, TX 78701 | **TX UST**
TX HIST UST | **U003566243**
N/A

Site 2 of 8 in cluster OF

Actual: 482 ft.
Focus Map: 11

UST:

Name:	AUSTIN FEDERAL COURTHOUSE
Address:	501 W 5TH ST
City,State,Zip:	AUSTIN, TX 787013813
AI Number:	4268
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	06/19/1986
Facility Status:	ACTIVE
Additional ID:	105057982002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	SAM VASQUEZ,
Contact Organization Name:	AUSTIN FEDERAL COURTHOUSE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124828164
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/08/2022
Signature Name/Title On Earliest Reg Form:	JENNIFER ZENUCH,INDUSTRIAL HYGENIST
Application Received Date On Earliest Reg Form:	08/10/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	72444872001297
Additional ID:	105057982002156

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Ai Number:	4268
Operator CN:	CN600311591
Operator Name:	GENERAL SERVICES ADMINISTRATION
Operator Effective Begin Date:	08/20/2012
Operator Type:	FG
Operator Role:	OWNOPRCON
Contact Name:	JORGE CAMERO/
Contact Organization Name:	GENERAL SERVICES ADMINISTRATION
Contact Mailing Address (Delivery):	1501 MATAMOROS ST RM 100
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	LAREDO TX 78040-4912
Contact Phone Country Code:	1
Contact Phone Area Code:	956
Contact Phone Number:	7184129
Contact Phone Extension:	0
Contact Fax Country Code:	1
Contact Fax Area Code:	956
Contact Fax Number:	7262325
Contact Fax Extension:	0
Contact Email Address:	JORGE.CAMERO@GSA.GOV
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600311591
Owner Last Name:	GENERAL SERVICES ADMINISTRATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	1919 SMITH ST STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	HOUSTON
Contact Mailing State:	TX
Contact Mailing Zip:	77002
Contact Mailing Zip5:	8070
Contact Phone Number/Ext:	1 713 6533075/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	72444872001297
Additional ID:	105057982002156
AI Number:	4268
Owner Effective Begin Date:	08/20/2012
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	ROLLIN REYNOLDS/
Contact Organization Name:	GENERAL SERVICES ADMINISTRATION

Self Certification:

Self Cert ID:	42960
Cert ID:	374047
AI Number:	4268
Self Certification Date:	08/08/2022
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	359119
AI Number:	4268
Self Certification Date:	09/01/2021
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	335585
AI Number:	4268
Self Certification Date:	04/13/2020
Signature Name/Title:	JENNIFER ZENUCH INDURSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	320313
AI Number:	4268
Self Certification Date:	04/01/2019
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	285300
AI Number:	4268
Self Certification Date:	04/06/2017
Signature Name/Title:	HANS RIEDEL PROP MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	268009
AI Number:	4268
Self Certification Date:	03/30/2016
Signature Name/Title:	CAROLINA MOLINA PROPERTY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	248668
AI Number:	4268
Self Certification Date:	02/02/2015
Signature Name/Title:	CAROLINA MOLINA PROP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42960
Cert ID:	248667
AI Number:	4268
Self Certification Date:	11/03/2014
Signature Name/Title:	CAROLINA MOLINA PROP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	08/20/2012
Tank Registration Date:	02/02/2015
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	220062
Facility ID:	42960
Ai Number:	4268
Tank Id:	7
Tank Status (Current):	IN USE
Tank Status Date:	08/20/2012
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	08/22/2012

Compartment Records:

Tank ID:	7
Tank Capacity:	6000
UST Comprt ID:	188207
UST ID:	220062
AI Number:	4268
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	10397
Facility ID:	42960
Ai Number:	4268
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	14098
UST ID:	10397
AI Number:	4268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	10398
Facility ID:	42960
Ai Number:	4268
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	14099
UST ID:	10398
AI Number:	4268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	10399
Facility ID:	42960
Ai Number:	4268
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	14100
UST ID:	10399
AI Number:	4268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Install Date:	12/01/1972
Tank Registration Date:	11/16/1990
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	10400
Facility ID:	42960
Ai Number:	4268
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	5
Tank Capacity:	4000
UST Comprt ID:	14101
UST ID:	10400
AI Number:	4268
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1972
Tank Registration Date:	11/16/1990
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	10401

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Facility ID:	42960
Ai Number:	4268
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	4
Tank Capacity:	8000

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

UST Comprt ID:	14102
UST ID:	10401
AI Number:	4268
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1972
Tank Registration Date:	11/16/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	185677
Facility ID:	42960
Ai Number:	4268
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	1000
UST Comprt ID:	14103
UST ID:	185677
AI Number:	4268
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	1515
Facility ID:	42960
AI Number:	4268
Application Received Date:	10/18/2011
Scheduled Construction Date:	11/15/2011
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	2731
General Desc Of Prop Construct:	INSTALLATION OF ONE 6K GALLON UST, INCLUDING PIPING FOR GENERATOR SYSTEM.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	1760
UST ID:	Not reported
NOC ID:	1515
AI Number:	4268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113 REGAL ROW
Mailing Address (Internal Delivery):	STE A
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	63480
UST ID:	220062
NOC ID:	Not reported
AI Number:	4268
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICHARD ROLLINS
Mailing Address (Delivery):	1113 REGAL ROW STE A
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	1761

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

UST ID:	Not reported
NOC ID:	1515
AI Number:	4268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	63481
UST ID:	220062
NOC ID:	Not reported
AI Number:	4268
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Facility Billing Contacts:

Contact Organization Name:	GENERAL SERVICES ADMINISTRATION
Contact Mailing Address (Delivery):	300 E 8TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 3233
Phone Number/Ext:	512 5396674/0
Contact Fax Number/Ext:	/
Contact Email Address:	CAROLINA.MOLINA@GSA.GOV
Contact Address Deliverable:	Y
Facility ID:	42960

AUSTIN FEDERAL COURTHOUSE (Continued) **U003566243**

Additional ID:	105057982002156
Princ ID:	72444872001297
AI Number:	4268
Facility Name:	AUSTIN FEDERAL COURTHOUSE
AR Number:	39934
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	CAROLINA MOLINA/

HIST UST AUSTIN:

Name:	COVERT BUICK
Address:	501 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	1696
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OF2435 **AUSTIN FEDERAL COURTHOUSE** **RCRA NonGen / NLR** **1000876535**
WNW **501 W 5TH ST** **FINDS** **TX0000012161**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.070 mi. **TX Ind. Haz Waste**
371 ft. **Site 3 of 8 in cluster OF**

Actual:
482 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Covert Buick Inc
Handler Address:	W 5TH ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TX0000012161
Contact Name:	RICKEY CMEREK
Contact Address:	PO BOX 1744
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-476-4761
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1744
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	Covert Buick Inc
Owner Type:	Private
Operator Name:	Covert Buick
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D021
Waste Description:	Chlorobenzene

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: COVERT BUICK INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1744
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 513-476-4761
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COVERT BUICK INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 501 W 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COVERT BUICK
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 501 W 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19930927
Handler Name: COVERT BUICK
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: COVERT BUICK INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070167733

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.
Registry ID: 110005009604

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

ECHO:

Envid:	1000876535
Registry ID:	110005009604
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005009604
Name:	COVERT BUICK INC
Address:	501 W 5TH ST
City,State,Zip:	AUSTIN, TX 78701

Ind. Haz Waste:

Name:	COVERT BUICK AUSTIN
Address:	501 W 5TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	81564
Registration Initial Notification Date:	01/27/1994
Registration Last Amendment Date:	02/14/2001
EPA Identification:	TX0000012161
Primary NAICS Code:	Not reported
Status Change Date:	19940127
Land Type:	PRIVATE
Description of Facility Site Location:	501 W 5th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	COVERT BUICK INC
Contact Name:	RICKEY CMEREK
Contact Telephone Number:	512-4764761
Mailing Address:	PO BOX 1744
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671744
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	36571
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021002
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	COVERT BUICK INC
Operator Address:	501 W 5THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17419827419
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COVERT BUICK INC
Owner Mailing Address:	501 W 5THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17419827419
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	501 W 5THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	501 W 5THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RICKEY CMEREK

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Contact Title:	SERVICE MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1744
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4764761
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	75133
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvent - parts cleaning; 1983
Standard Industrial Code:	75380
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811111
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	75134
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Immersion cleaner - parts cleaning; 1983
Standard Industrial Code:	75380
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

AUSTIN FEDERAL COURTHOUSE (Continued) **1000876535**

Primary NAICS Code:	811111
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

OG2436 **THE WALTER TIPS CO.** **TX HIST UST** **S111678831**
SSW **115 W 2ND ST** **N/A**
< 1/8 **AUSTIN, TX**
0.070 mi.
371 ft. **Site 1 of 7 in cluster OG**

Actual:
474 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	THE WALTER TIPS CO.
Address:	115 W 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0801
HID UST:	801
Inspection:	Not reported
Due:	06/01/2012

OH2437 **CITY OF AUSTIN RIGHT OF WAY** **TX TANKS** **S126903596**
WNW **3RD & SAN ANTONIO** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.070 mi.
371 ft. **Site 1 of 5 in cluster OH**

Actual:
472 ft.

Focus Map:
11

TANKS:

Facility ID:	133595
Name:	CITY OF AUSTIN RIGHT OF WAY
Address:	3RD & SAN ANTONIO
City,State,Zip:	AUSTIN, TX
Total UST:	Not reported
Additional ID:	995501752016147
AI Number:	88481
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	3RD & SAN ANTONIO
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS

CITY OF AUSTIN RIGHT OF WAY (Continued) **S126903596**

Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN109230177
Name:	CITY OF AUSTIN RIGHT OF WAY
Address:	3RD & SAN ANTONIO
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	5/26/2016
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3RD & SAN ANTONIO

2438 SSW < 1/8 0.070 mi. 371 ft. | **EXXON MOBIL CORPORATION 619 N IH 35 AUSTIN, TX 78702** | **RCRA NonGen / NLR FINDS ECHO** | **1004785588 TXD988032124**

Actual: 474 ft.
Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	N IH 35
Handler City,State,Zip:	AUSTIN, TX 78702
EPA ID:	TXD988032124
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 4552
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Telephone:	713-656-9075

EXXON MOBIL CORPORATION (Continued) **1004785588**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 4552
Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

EXXON MOBIL CORPORATION (Continued) **1004785588**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D018
Waste Description: Benzene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4999
Owner/Operator City,State,Zip: THE WOODLANDS, TX 77380-4999
Owner/Operator Telephone: 281-296-3655
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-9075
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-9075
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-9075
Owner/Operator Telephone Ext: Not reported

EXXON MOBIL CORPORATION (Continued) **1004785588**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4552
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-9075
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000215
Handler Name: EXXON RAS NO 62790
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

EXXON MOBIL CORPORATION (Continued) **1004785588**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005132542

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004785588
Registry ID:	110005132542
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005132542
Name:	EXXON MOBIL CORPORATION
Address:	619 N IH 35
City,State,Zip:	AUSTIN, TX 78702

OI2439 **TX HIST UST** **S128729210**
WNW **W 6TH ST & SAN ANTONIO** **N/A**
< 1/8 **AUSTIN, TX**
0.070 mi.
371 ft. **Site 1 of 15 in cluster OI**

Actual:
483 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	W 6TH ST & SAN ANTONIO
City,State,Zip:	AUSTIN, TX
Id UST:	H0188
HID UST:	Not reported
Inspection:	03/22/1928
Due:	Not reported

OI2440 WNW < 1/8 0.070 mi. 371 ft. — **KUHLMAN HOW**, **501 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013769676** / **N/A**

Site 2 of 15 in cluster OI

Actual: 483 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	KUHLMAN HOWARD P AUTO DLR	AUTOMOBILE REPAIRING
1953	KUHLMAN HOW	AUTOMOBILE REPAIRING

OF2441 WNW < 1/8 0.071 mi. 375 ft. — **LINDHOLM TORSTEN**, **502 5TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013760674** / **N/A**

Site 4 of 8 in cluster OF

Actual: 482 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	LINDHOLM TORSTEN	AUTOMOBILE REPAIRING

LF2442 East < 1/8 0.071 mi. 375 ft. — **LONGHOM CLEANERS**, **510 MARTIN LUTHER KING JR BLVD W**, **AUSTIN, TX 78701** — **EDR Hist Cleaner** — **1013782827** / **N/A**

Site 7 of 7 in cluster LF

Actual: 559 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1980	DISCOUNT CLEANERS	CLEANERS AND DYERS
1984	DISCOUNT CLEANERS	CLEANERS AND DYERS
1990	LONGHOM CLEANERS	CLEANERS AND DYERS
1995	P ANH & COMPANY INC	Laundry And Drycleaner Agents
1999	FICORP INC	Laundry And Drycleaner Agents
2000	FICORP INC	Laundry And Drycleaner Agents
2001	FICORP INC	Laundry And Drycleaner Agents
2002	FICORP INC	Laundry And Drycleaner Agents
2003	FICORP INC	Laundry And Drycleaner Agents
2004	FICORP INC	Laundry And Drycleaner Agents
2005	FICORP INC	Laundry And Drycleaner Agents
2006	FICORP INC	Laundry And Drycleaner Agents
2007	FICORP INC	Laundry And Drycleaner Agents

2443 WNW < 1/8 0.071 mi. 376 ft. — **NORTH AUSTIN FRAME & ALIGNMENT**, **825 KRAMER LN**, **AUSTIN, TX 78758** — **EDR Hist Auto** — **1013764099** / **N/A**

Actual: 762 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1980	NORTH AUSTIN FRAME & ALIGNMENT	AUTOMOBILE REPAIRING

2444 WNW < 1/8 0.071 mi. 377 ft. | **TRAVIS COUNTY JAIL**
1000 SAN ANTONIO ST
AUSTIN, TX 78701 | **TX UST**
TX HIST UST | **U003177614**
N/A

Actual: 526 ft.

Focus Map: 11

UST:

Name:	TRAVIS COUNTY JAIL
Address:	1000 SAN ANTONIO ST
City,State,Zip:	AUSTIN, TX 787012119
AI Number:	69575
Facility Type:	Not reported
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	334830632002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DAVE FOWLER,
Contact Organization Name:	TRAVIS COUNTY JAIL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124739383
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1997
Signature Name/Title On Earliest Reg Form:	DAVID L FOWLER,ENV. PROJ. MGR.
Application Received Date On Earliest Reg Form:	05/08/1997
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600338388
Owner Last Name:	TRAVIS COUNTY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	178448372001300
Additional ID:	334830632002138

TRAVIS COUNTY JAIL (Continued) **U003177614**

AI Number:	69575
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1979
Tank Registration Date:	05/08/1997
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	183310
Facility ID:	105588
Ai Number:	69575
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/24/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

TRAVIS COUNTY JAIL (Continued) **U003177614**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	174644
UST ID:	183310
AI Number:	69575
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TRAVIS COUNTY JAIL (Continued) **U003177614**

More Self Certification:

Self Cert ID:	26633
Cert ID:	38344
UST Comprt ID:	101380
UST ID:	37657
AI Number:	69575
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	26633
Cert ID:	38343
UST Comprt ID:	101381
UST ID:	37657
AI Number:	69575
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	26633
Cert ID:	38340
UST Comprt ID:	101382
UST ID:	37657
AI Number:	69575
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	26633
Cert ID:	38341
UST Comprt ID:	101383
UST ID:	37657
AI Number:	69575
Tank ID:	3A
Compartment ID:	A
Self Cert ID:	26633
Cert ID:	38342
UST Comprt ID:	101384
UST ID:	37657
AI Number:	69575
Tank ID:	3A
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	TRAVIS COUNTY
Contact Mailing Address (Delivery):	PO BOX 1748
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1748
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	105588
Additional ID:	334830632002138
Princ ID:	178448372001300
AI Number:	69575
Facility Name:	TRAVIS COUNTY JAIL

TRAVIS COUNTY JAIL (Continued) **U003177614**

AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KEITH COBURN/

HIST UST AUSTIN:

Name:	TRAVIS COUNTY JAIL
Address:	1000 SAN ANTONIO ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX014
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LB2445 **J. G. MASON** **TX HIST UST** **S128729232**
WNW **511 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.071 mi.
377 ft. **Site 8 of 9 in cluster LB**

Actual:
461 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	J. G. MASON
Address:	511 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0282
HID UST:	282
Inspection:	Not reported
Due:	06/01/2012

LB2446 **ACUNA'S** **TX HIST UST** **S128729062**
WNW **511 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.071 mi.
377 ft. **Site 9 of 9 in cluster LB**

Actual:
461 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ACUNA'S
Address:	511 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0510
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MQ2447 ENE < 1/8 0.071 mi. 377 ft. — **TAYLORS DELWOOO CONOCO, 4021 EAST AVE, AUSTIN, TX** — **EDR Hist Auto** — **1013776672 / N/A**

Site 13 of 18 in cluster MQ

Actual: 589 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1953	TAYLORS DELWOOD	GASOLINE STATIONS
1958	TAYLORS DELWOOD	GASOLINE STATIONS
1962	TAYLORS DELWOOD	GASOLINE STATIONS
1965	TAYLORS DELWOOO CONOCO	GASOLINE STATIONS

OJ2448 SSW < 1/8 0.072 mi. 378 ft. — **GULF OIL COMPANY, 201 W 2ND ST, AUSTIN, TX** — **TX HIST UST** — **S111678655 / N/A**

Site 1 of 2 in cluster OJ

Actual: 474 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	GULF OIL COMPANY
Address:	201 W 2ND ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0165
HID UST:	165
Inspection:	Not reported
Due:	06/01/2012

OI2449 WNW < 1/8 0.072 mi. 378 ft. — **ZIMMERMANH E E, 503 6TH W, AUSTIN, TX** — **EDR Hist Cleaner** — **1013787473 / N/A**

Site 3 of 15 in cluster OI

Actual: 483 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1911	ZIMMERMANH E E	DYERS AND SCOURERS
1911	ZIMMERMANH E E	CLOTHES PRESSERS AND CLEANERS

2450 NNE < 1/8 0.072 mi. 379 ft. — **MUELLER & BENSON, 403 BRAZOS, AUSTIN, TX** — **EDR Hist Auto** — **1013776014 / N/A**

Actual: 481 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1958	MUELLER & BENSON	AUTOMOBILE REPAIRING

2451 WNW < 1/8 0.072 mi. 380 ft. | **UNIVERSITY GARAGE AUTO**
1806 SAN ANTONIO ST
AUSTIN, TX | **EDR Hist Auto** | **1013767835**
N/A

Actual: 543 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	WRIGHTS UNIVERSITY GARAGE	AUTOMOBILE GARAGES
1935	WRIGHTS UNIVERSITY	AUTOMOBILE REPAIRERS
1940	WRIGHTS UNIVERSITY	AUTOMOBILE REPAIRING
1947	WRIGHTS UNIVERSITY GARAGE	AUTOMOBILE REPAIRING
1953	WRIGHTS UNIVERSITY	AUTOMOBILE REPAIRING
1958	WRIGHTS GARAGE	AUTOMOBILE REPAIRING
1962	UNIV GARAGE	AUTOMOBILE REPAIRING
1965	UNIVERSITY GARAGE AUTO	AUTOMOBILE REPAIRING

MQ2452 ENE < 1/8 0.072 mi. 380 ft. | **SWEET ONE HOUR DRY CLEANERS GL**
4100 EAST AVE
AUSTIN, TX
Site 14 of 18 in cluster MQ | **EDR Hist Cleaner** | **1013783670**
N/A

Actual: 586 ft.

Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1965	SWEET ONE HOUR DRY CLEANERS GL	CLEANERS AND DYERS

2453 ESE < 1/8 0.072 mi. 381 ft. | **JAMES W L GARAGE**
703 38TH W
AUSTIN, TX | **EDR Hist Auto** | **1013769755**
N/A

Actual: 612 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1929	JAMES W L GARAGE	AUTOMOBILE GARAGES

MU2454 NNE < 1/8 0.072 mi. 381 ft. | **WESTBANK DRY CLEANING**
112 E 4TH ST
AUSTIN, TX 78701
Site 4 of 5 in cluster MU | **TX DRYCLEANERS** | **S107982676**
N/A

Actual: 482 ft.

Focus Map: 11

DRYCLEANERS:

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN605452960
DCR Number:	DCR13979
AR Number:	24007714
Principal Name:	WESTBANK COUTURE CLEANERS LLC
Bill Addr1:	Not reported

WESTBANK DRY CLEANING (Continued) **S107982676**

Bill Addr2:	Not reported
Bill City/State/Zip:	Not reported
EMail:	Not reported
Phone Number:	0 0
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN600381610
DCR Number:	DCR13979
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	4245 N CENTRAL EXPY STE 510
Bill Addr2:	Not reported
Bill City/State/Zip:	DALLAS, TX 75205 4506
EMail:	KORI.BAKER@WESTBANKDRYCLEANING.COM
Phone Number:	512 2368602
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN605452960
DCR Number:	DCR13979
AR Number:	24007714
Principal Name:	WESTBANK COUTURE CLEANERS LLC
Bill Addr1:	4245 N CENTRAL EXPY STE 510
Bill Addr2:	Not reported
Bill City/State/Zip:	DALLAS, TX 75205 4506
EMail:	KORI.BAKER@WESTBANKDRYCLEANING.COM
Phone Number:	512 2368602
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO

WESTBANK DRY CLEANING (Continued) **S107982676**

Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN600381610
DCR Number:	DCR13979
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN605452960
DCR Number:	DCR13979
AR Number:	24007714
Principal Name:	WESTBANK COUTURE CLEANERS LLC
Bill Addr1:	4245 N CENTRAL EXPY STE 510
Bill Addr2:	Not reported
Bill City/State/Zip:	DALLAS, TX 75205 4506
EMail:	MKABRANE@BIBBENTUCKERS.COM
Phone Number:	214 2671700
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC

WESTBANK DRY CLEANING (Continued) **S107982676**

Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported

WESTBANK DRY CLEANING (Continued) **S107982676**

Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102

WESTBANK DRY CLEANING (Continued) **S107982676**

Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported

WESTBANK DRY CLEANING (Continued) **S107982676**

Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	11
CN Number:	CN600381610
DCR Number:	Not reported

WESTBANK DRY CLEANING (Continued) **S107982676**

AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	WBCLEAN@TEXAS.NET
Phone Number:	512 2368602
Site Name:	WESTBANK DRY CLEANING
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	WESTBANK DRY CLEANING
Address:	112 E 4TH ST
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104400213
Region:	REGION 11 - AUSTIN
CN Number:	CN600381610
DCR Number:	DCR13979
AR Number:	24001102
Principal Name:	WESTBANK DRY CLEANING INC
Bill Addr1:	1300 E 38TH 1/2 ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78722 1822
EMail:	KSEIFERT@TEXAS.NET
Phone Number:	512 2368602
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	> $150,000

OF2455 **LINDHOLM T F AUTO** **EDR Hist Auto** **1013763693**
WNW **500 SAN ANTONIO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.072 mi.
381 ft. **Site 5 of 8 in cluster OF**

Actual:
482 ft. EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	LINDHOLM T F AUTO	AUTOMOBILE REPAIRERS

OF2456 WNW < 1/8 0.072 mi. 382 ft. — **COVERT BUICK CO**, **505 5TH ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013753992** / **N/A**

Site 6 of 8 in cluster OF

Actual: 482 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	COVERT BUICK CO	AUTOMOBILE REPAIRING

OF2457 WNW < 1/8 0.072 mi. 382 ft. — **COVERT BUICK CO**, **505 5TH ST W**, **AUSTIN, TX 78701** — **EDR Hist Auto** — **1013756992** / **N/A**

Site 7 of 8 in cluster OF

Actual: 482 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1980	COVERT BUICK CO	AUTOMOBILE REPAIRING

2458 WNW < 1/8 0.072 mi. 382 ft. — **COR EZELLE JACK SERVICE**, **8 SAN JACINTO ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775180** / **N/A**

Actual: 470 ft. — EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	COR EZELLE JACK SERVICE	GASOLINE AND OIL SERVICE STATIONS

NM2459 ESE < 1/8 0.073 mi. 386 ft. — **MASTER VALET CLEANERS**, **3101 SPEEDWAY**, **AUSTIN, TX 78705** — **TX DRYCLEANERS** — **S109361484** / **N/A**

Site 2 of 6 in cluster NM

Actual: 591 ft. — DRYCLEANERS:

Focus Map: 8

Name:	MASTER VALET CLEANERS
Address:	3101 SPEEDWAY
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN104090568
Region:	11
CN Number:	CN602523649
DCR Number:	Not reported
AR Number:	24001773
Principal Name:	AMIN INVESTMENTS CO LLC
Bill Addr1:	PO BOX 90577
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78709 0577
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MASTER VALET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE

MASTER VALET CLEANERS (Continued) **S109361484**

Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	MASTER VALET CLEANERS
Address:	3101 SPEEDWAY
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN104090568
Region:	11
CN Number:	CN602523649
DCR Number:	Not reported
AR Number:	24001773
Principal Name:	AMIN INVESTMENTS CO LLC
Bill Addr1:	PO BOX 90577
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78709 0577
EMail:	Not reported
Phone Number:	Not reported
Site Name:	MASTER VALET CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

NM2460 **MASTER VALET CLEANERS** **EDR Hist Cleaner** **1013779393**
ESE **3101 SPEEDWAY ST** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.073 mi.
386 ft. **Site 3 of 6 in cluster NM**

Actual:
591 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1980	MASTER VALET CLEANERS & COIN LA	LAUNDRIES-SELF SERVE
1984	MASTER VALET CLEANERS	LAUNDRIES-SELF SERVE
1990	MASTER VALET CLEANERS	LAUNDRIES-SELF SERVE

NM2461 **MITTAG WILLIAM O** **EDR Hist Cleaner** **1013778029**
ESE **3101 SPEEDWAY** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.073 mi.
386 ft. **Site 4 of 6 in cluster NM**

Actual:
591 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1975	MASTER VALET COIN LAUNDRY	LAUNDRIES-SELF SERVE
1992	MASTER VALET CLEANERS	Drycleaning Plants, Except Rugs
1993	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
1994	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
1995	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs

MITTAG WILLIAM O (Continued) **1013778029**

1996	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
1997	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
1998	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
1999	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
2000	MITTAG WILLIAM O	Drycleaning Plants, Except Rugs
2001	AMIN SAROOQA	Drycleaning Plants, Except Rugs
2002	AMIN SAROOQA	Drycleaning Plants, Except Rugs
2003	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs
2004	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs
2005	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs
2006	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs
2007	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs
2008	MASTER VLET CLR SHIRT LNDERING	Drycleaning Plants, Except Rugs

---

OK2462 **BADGER AUTO SUPPLY CO.** **TX HIST UST** **S111678571**
SW **119 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.073 mi.
386 ft. **Site 1 of 21 in cluster OK**

Actual:
490 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	BADGER AUTO SUPPLY CO.
Address:	119 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0251
HID UST:	251
Inspection:	03/06/2009
Due:	03/06/2012

OK2463 **KENICHI RESTAURANT** **TX HIST UST** **S127542936**
SW **121 W 5TH ST** **TX RDR** **N/A**
< 1/8 **AUSTIN, TX**
0.073 mi.
386 ft. **Site 2 of 21 in cluster OK**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	KENICHI
Address:	121 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0696
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	10848
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	KENICHI RESTAURANT
Address:	121 W 5TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/24/2008
Due Date:	12/23/2008

KENICHI RESTAURANT (Continued) **S127542936**

Tank Owner:	THE KUCERA CO
Contact Person:	TED MECKLIN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/14/2009
Project Manager:	Denise Crawford
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RTN1 7/25/01,VOC/RCRA,TEMP,PART A,RTN2 10/26/01,NO MAP,COC,LAB,ETC; 6/21/01 1ST SUB 10/26/2001.
Review Coordinator:	SDC/SAW
Date Release Reported:	12/14/00
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/14/2009
Date Report Returned:	7/13/2001
Region:	Not reported
DKC RDR (misfiled):	Not reported

2464 East < 1/8 0.073 mi. 387 ft. **AUSTIN LNDRY & DRY** **EDR Hist Cleaner** **1013779974**
608 24TH W **N/A**
AUSTIN, TX

Actual: 593 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1962	AUSTIN LNDRY & DRY	LAUNDRIES

2465 SSW < 1/8 0.073 mi. 387 ft. **FORMER SKEET & TRAP RANGE (SWMU 204)** **UXO** **1024717551**
N/A
AUSTIN, TX

Actual: 509 ft. UXO:

Focus Map: 20

DoD Component:	Air Force
Installation Name:	BERGSTROM
Name:	FORMER SKEET & TRAP RANGE (SWMU 204)
Address:	Not reported
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX
Site ID:	SR400
Site Type:	Small Arms Range
Latitude:	30.216311
Longitude:	-97.668138

2466
WNW
< 1/8
0.073 mi.
387 ft.

COVERT AUTOMO
420 SAN ANTONIO ST
AUSTIN, TX

EDR Hist Auto **1013760105**
N/A

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	COVERT AUTOMO	AUTOMOBILE REPAIRING

OH2467
WNW
< 1/8
0.073 mi.
387 ft.

416 20 COVERT AUTO CO
416 SAN ANTONIO ST
AUSTIN, TX

Site 2 of 5 in cluster OH

EDR Hist Auto **1013755915**
N/A

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	COVERT AUTOMO	AUTOMOBILE REPAIRING
1962	416 20 COVERT AUTO CO	AUTOMOBILE REPAIRING
1965	COVERT AUTOMOBILE CO	AUTOMOBILE REPAIRING

OI2468
WNW
< 1/8
0.073 mi.
387 ft.

LARSONS GARAGE AUTO REPR
504 6TH ST W
AUSTIN, TX

Site 4 of 15 in cluster OI

EDR Hist Auto **1013757698**
N/A

Actual:
482 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	LARSONS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

OI2469
WNW
< 1/8
0.073 mi.
387 ft.

LARSONS GAR AUTO REPR
504 6TH W
AUSTIN, TX

Site 5 of 15 in cluster OI

EDR Hist Auto **1013757697**
N/A

Actual:
482 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	LARSONS GAR AUTO REPR	AUTOMOBILE REPAIRING

OL2470 **HOWARD MCELROY** **TX UST** **U001291165**
ESE **6607 SHIRLEY AVE** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.073 mi.
388 ft. **Site 1 of 2 in cluster OL**

Actual:
710 ft.

Focus Map:
6

UST:

Name:	HOWARD MCELROY
Address:	6607 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX 787524025
AI Number:	61655
Facility Type:	FARM OR RESIDENTIAL
Facility Begin Date:	12/12/1991
Facility Status:	INACTIVE
Additional ID:	745575882002053
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	HOWARD MCELROY,
Contact Organization Name:	HOWARD MCELROY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124478528
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/06/1991
Signature Name/Title On Earliest Reg Form:	MICHELLE NAUMAN,GEOLOGIST
Application Received Date On Earliest Reg Form:	12/10/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600779714
Owner Last Name:	MCELROY HOWARD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	736575882002053
Additional ID:	745575882002053

HOWARD MCELROY (Continued) **U001291165**

AI Number:	61655
Owner Effective Begin Date:	12/12/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/10/1991
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	143818
Facility ID:	92156
Ai Number:	61655
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/30/1991
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

HOWARD MCELROY (Continued) **U001291165**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/14/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	142308
UST ID:	143818
AI Number:	61655
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

HOWARD MCELROY (Continued) **U001291165**

Facility Billing Contacts:

Contact Organization Name:	MCELROY HOWARD
Contact Mailing Address (Delivery):	6607 SHIRLEY AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 4025
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	92156
Additional ID:	745575882002053
Princ ID:	736575882002053
AI Number:	61655
Facility Name:	HOWARD MCELROY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HOWARD MCELROY/

HIST UST AUSTIN:

Name:	HOWARD MCELROY
Address:	6607 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0191
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OL2471 **AUTOMOTIVE REFINISH TECHNOLOGIES** **RCRA-SQG** **1004788407**
ESE **6615 SHIRLEY AVENUE** **FINDS** **TXR000040196**
< 1/8 **AUSTIN, TX 78752** **ECHO**
0.073 mi.
388 ft. **Site 2 of 2 in cluster OL**

Actual:
710 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20001127
Handler Name:	Automotive Refinish Technologies
Handler Address:	SHIRLEY AVENUE
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXR000040196
Contact Name:	CARYE DOWELL
Contact Address:	6615 SHIRLEY AVENUE
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-451-7347
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx

AUTOMOTIVE REFINISH TECHNOLOGIES (Continued) **1004788407**

State District:	11
Mailing Address:	SHIRLEY AVENUE
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	John Montez
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20001127
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018

AUTOMOTIVE REFINISH TECHNOLOGIES (Continued) **1004788407**

Waste Description: Benzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOHN MONTEZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	400 GALLERIA OFF CNTR STE 217
Owner/Operator City,State,Zip:	SOUTHFIELD, MI 48034
Owner/Operator Telephone:	248-304-5555
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20001127
Handler Name:	AUTOMOTIVE REFINISH TECHNOLOGIES
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

AUTOMOTIVE REFINISH TECHNOLOGIES (Continued) **1004788407**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005191559

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004788407
Registry ID:	110005191559
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005191559
Name:	AUTOMOTIVE REFINISH TECHNOLOGIES
Address:	6615 SHIRLEY AVENUE
City,State,Zip:	AUSTIN, TX 78752

LG2472 **NATIONAL FINANCE CO** **EDR Hist Auto** **1013756048**
SSW **413 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.073 mi.
388 ft. **Site 26 of 26 in cluster LG**

Actual:
486 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	NATIONAL FINANCE CO	AUTOMOBILE REPAIRERS
1935	ALLISON & POPE AUTO	AUTOMOBILE REPAIRERS

OM2473 **REFUEL 329** **TX UST** **U003103742**
NNE **31 N IH 35** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78702** **TX Financial Assurance**
0.074 mi.
389 ft. **Site 1 of 4 in cluster OM**

Actual:
460 ft.

Focus Map:
14

UST:

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 787025201
AI Number:	26067
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	ACTIVE
Additional ID:	360663632002053
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	SALEEM VIRANI,
Contact Organization Name:	REFUEL 329
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124761776
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	REFUEL329@REFUELMARKET.COM
Signature Date On Earliest Reg Form:	04/15/2021
Signature Name/Title On Earliest Reg Form:	ISMAIL ALI,PRES
Application Received Date On Earliest Reg Form:	04/19/2021
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	429495502021203
Additional ID:	360663632002053
Ai Number:	26067
Operator CN:	CN605914696
Operator Name:	REFUEL OPERATING COMPANY LLC
Operator Effective Begin Date:	06/14/2022
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	TRAVIS SMITH/CHIEF DEVELOPMENT OFFICE
Contact Organization Name:	REFUEL OPERATING COMPANY LLC
Contact Mailing Address (Delivery):	547 LONG POINT RD STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	MOUNT PLEASANT SC 29464-8337
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	7690409
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

REFUEL 329 (Continued) **U003103742**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	tsmith@refuelmarket.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605914696
Owner Last Name:	REFUEL OPERATING COMPANY LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	547 LONG POINT RD STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	MOUNT PLEASANT
Contact Mailing State:	SC
Contact Mailing Zip:	29464
Contact Mailing Zip5:	8337
Contact Phone Number/Ext:	1 512 7690409/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	tsmith@refuelmarket.com
Contact Address Deliverable:	Not reported
Princ ID:	429495502021203
Additional ID:	360663632002053
AI Number:	26067
Owner Effective Begin Date:	06/14/2022
State Tax ID:	32078444992
Contact Role:	OWNOPRCON
Contact Name/Title:	TRAVIS SMITH/CHIEF DEVELOPMENT OFFICE
Contact Organization Name:	REFUEL OPERATING COMPANY LLC

Self Certification:

Self Cert ID:	90370
Cert ID:	372981
AI Number:	26067
Self Certification Date:	06/14/2022
Signature Name/Title:	TRAVIS SMITH CDO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	369715
AI Number:	26067
Self Certification Date:	04/20/2022

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	MOHAMMED I ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	90370
Cert ID:	353114
AI Number:	26067
Self Certification Date:	04/15/2021
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	90370
Cert ID:	335618
AI Number:	26067
Self Certification Date:	04/05/2020
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	90370
Cert ID:	319033
AI Number:	26067
Self Certification Date:	04/03/2019

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	302251
AI Number:	26067
Self Certification Date:	04/09/2018
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	284302
AI Number:	26067
Self Certification Date:	03/07/2017
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	268992
AI Number:	26067
Self Certification Date:	04/29/2016

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	250940
AI Number:	26067
Self Certification Date:	03/09/2015
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	235002
AI Number:	26067
Self Certification Date:	04/07/2014
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	90370
Cert ID:	141897
AI Number:	26067
Self Certification Date:	03/11/2013

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141896
AI Number:	26067
Self Certification Date:	04/05/2012
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141895
AI Number:	26067
Self Certification Date:	03/07/2011
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141894
AI Number:	26067
Self Certification Date:	03/04/2010

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141893
AI Number:	26067
Self Certification Date:	03/09/2009
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141892
AI Number:	26067
Self Certification Date:	02/25/2008
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141891
AI Number:	26067
Self Certification Date:	03/22/2007

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141890
AI Number:	26067
Self Certification Date:	03/31/2006
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141889
AI Number:	26067
Self Certification Date:	03/08/2005
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141888
AI Number:	26067
Self Certification Date:	03/24/2004

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141887
AI Number:	26067
Self Certification Date:	04/08/2003
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141886
AI Number:	26067
Self Certification Date:	09/25/2002
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	90370
Cert ID:	141885
AI Number:	26067
Self Certification Date:	01/04/2001

REFUEL 329 (Continued) **U003103742**

Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67086
Facility ID:	90370
Ai Number:	26067
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1967
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

REFUEL 329 (Continued) **U003103742**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	150016
UST ID:	67086
AI Number:	26067
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

REFUEL 329 (Continued) **U003103742**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9825
Cert ID:	123866
UST Comprt ID:	356930
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123865
UST Comprt ID:	356929
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123868
UST Comprt ID:	356928
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123869
UST Comprt ID:	356927
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123870
UST Comprt ID:	356926
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123871
UST Comprt ID:	356925
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825

REFUEL 329 (Continued) **U003103742**

Cert ID:	123872
UST Comprt ID:	356924
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123873
UST Comprt ID:	356923
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123874
UST Comprt ID:	356922
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123875
UST Comprt ID:	356921
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123876
UST Comprt ID:	356920
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123877
UST Comprt ID:	356919
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123878
UST Comprt ID:	356918
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	221061

REFUEL 329 (Continued) **U003103742**

UST Comprt ID:	633916
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	237947
UST Comprt ID:	683302
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123867
UST Comprt ID:	356931
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67089
Facility ID:	90370
Ai Number:	26067
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1967
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

REFUEL 329 (Continued) **U003103742**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	150019
UST ID:	67089
AI Number:	26067
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

REFUEL 329 (Continued) **U003103742**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9825
Cert ID:	123866
UST Comprt ID:	356930
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123865
UST Comprt ID:	356929
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123868
UST Comprt ID:	356928
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123869
UST Comprt ID:	356927
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123870
UST Comprt ID:	356926
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123871

REFUEL 329 (Continued) **U003103742**

UST Comprt ID:	356925
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123872
UST Comprt ID:	356924
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123873
UST Comprt ID:	356923
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123874
UST Comprt ID:	356922
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123875
UST Comprt ID:	356921
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123876
UST Comprt ID:	356920
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123877
UST Comprt ID:	356919
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123878
UST Comprt ID:	356918

REFUEL 329 (Continued) **U003103742**

UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	221061
UST Comprt ID:	633916
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	237947
UST Comprt ID:	683302
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123867
UST Comprt ID:	356931
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67088
Facility ID:	90370
Ai Number:	26067
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/29/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

REFUEL 329 (Continued) **U003103742**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	150018
UST ID:	67088
AI Number:	26067
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

REFUEL 329 (Continued) **U003103742**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9825
Cert ID:	123866
UST Comprt ID:	356930
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123865
UST Comprt ID:	356929
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123868
UST Comprt ID:	356928
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123869
UST Comprt ID:	356927
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123870
UST Comprt ID:	356926

REFUEL 329 (Continued) **U003103742**

UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123871
UST Comprt ID:	356925
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123872
UST Comprt ID:	356924
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123873
UST Comprt ID:	356923
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123874
UST Comprt ID:	356922
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123875
UST Comprt ID:	356921
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123876
UST Comprt ID:	356920
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123877
UST Comprt ID:	356919
UST ID:	116983

REFUEL 329 (Continued) **U003103742**

AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123878
UST Comprt ID:	356918
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	221061
UST Comprt ID:	633916
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	237947
UST Comprt ID:	683302
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123867
UST Comprt ID:	356931
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67087
Facility ID:	90370
Ai Number:	26067
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1967
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

REFUEL 329 (Continued) **U003103742**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	150017
UST ID:	67087
AI Number:	26067
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N

REFUEL 329 (Continued) **U003103742**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9825
Cert ID:	123866
UST Comprt ID:	356930
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123865
UST Comprt ID:	356929
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123868
UST Comprt ID:	356928
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123869
UST Comprt ID:	356927
UST ID:	116983

REFUEL 329 (Continued) **U003103742**

AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123870
UST Comprt ID:	356926
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123871
UST Comprt ID:	356925
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123872
UST Comprt ID:	356924
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123873
UST Comprt ID:	356923
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123874
UST Comprt ID:	356922
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123875
UST Comprt ID:	356921
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123876
UST Comprt ID:	356920
UST ID:	116983
AI Number:	26067

REFUEL 329 (Continued) **U003103742**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123877
UST Comprt ID:	356919
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123878
UST Comprt ID:	356918
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	221061
UST Comprt ID:	633916
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	237947
UST Comprt ID:	683302
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A
Self Cert ID:	9825
Cert ID:	123867
UST Comprt ID:	356931
UST ID:	116983
AI Number:	26067
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	15056
Facility ID:	90370
AI Number:	26067
Application Received Date:	12/21/2000
Scheduled Construction Date:	12/26/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N

REFUEL 329 (Continued) **U003103742**

UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M11221004
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	48254
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	16139
UST ID:	Not reported
NOC ID:	15056
AI Number:	26067
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	REFUEL OPERATING COMPANY LLC
Contact Mailing Address (Delivery):	547 LONG POINT RD STE 103
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	MOUNT PLEASANT, SC 29464 8337
Phone Number/Ext:	843 3884966/0
Contact Fax Number/Ext:	/
Contact Email Address:	LEGAL@REFUELMARKET.COM
Contact Address Deliverable:	Y
Facility ID:	90370
Additional ID:	360663632002053
Princ ID:	429495502021203
AI Number:	26067
Facility Name:	REFUEL 329

REFUEL 329 (Continued) **U003103742**

AR Number:	82855
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	TRAVIS SMITH/CDO

ASBESTOS:

Name:	CITY STAR FOODS
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	04/05/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.1
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/09/2013
Date Routed by Supervisor:	04/09/2013
Date Routed to PSQA:	04/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported

REFUEL 329 (Continued) **U003103742**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	270828
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/07/2022
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	NAVIGATORS INS CO
Issuer Phone:	Not reported
Policy Number:	SF20ESPZ04YVAIC
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/17/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	267349
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

REFUEL 329 (Continued) **U003103742**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2021
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000021176
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	249322
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2020
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000011996
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	230452
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2019
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000003657
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2020

REFUEL 329 (Continued) **U003103742**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	212555
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2018
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-000107312
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	195472
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2017
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000102283
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	177227

REFUEL 329 (Continued) **U003103742**

AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2016
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00097805
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	160710
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2015
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 979 7762626
Policy Number:	04-TO-93526
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	141917
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2014

REFUEL 329 (Continued) **U003103742**

Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 979 7762626
Policy Number:	04-TO-00089389
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	126164
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2013
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-85340
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	9568
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2012
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO81444
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/29/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

REFUEL 329 (Continued) **U003103742**

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	76781
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2011
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO77626
Coverage Amount:	1000000
Coverage Expiration Date:	07/29/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	76782
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2010
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO73912
Coverage Amount:	1000000
Coverage Expiration Date:	07/29/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	76783
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

REFUEL 329 (Continued) **U003103742**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/29/2008
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	83817
Coverage Amount:	1000000
Coverage Expiration Date:	07/29/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	76784
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/26/2007
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USC9416971-02
Coverage Amount:	1000000
Coverage Expiration Date:	08/26/2008
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	REFUEL 329
Address:	31 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	90370
Finass ID:	76785
AI:	26067
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	04/19/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported

REFUEL 329 (Continued) **U003103742**

Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

2474 NW
< 1/8
0.074 mi.
390 ft.

AUSTIN BERGSTROM INTERNATIONAL AIRPORT ABIA **PFAS ECHO** **1027328026**
N/A
AUSTIN, TX

Actual:
507 ft.

Focus Map:
20

PFAS ECHO:

Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT ABIA
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.21234
Longitude:	-97.66653
Count:	1
County:	TRAVIS
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110033324052
Facility Percent Minority:	83.233
Facility Derived Tribes:	-
Facility Population:	766.72
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001016
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N

AUSTIN BERGSTROM INTERNATIONAL AIRPORT ABIA (Continued) **1027328026**

TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05DA02 TXR05N459
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66653,%22y%22:30.21234,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

OM2475 **FAST N EASY SHELL** **EDR Hist Auto** **1020313896**
NNE **31 N HWY 35** **N/A**
< 1/8 **AUSTIN, TX 78702**
0.074 mi.
392 ft. **Site 2 of 4 in cluster OM**

Actual:
460 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
2006	FAST N EASY SHELL	Gasoline Service Stations

OM2476 **CITY STAR FOODS** **TX HIST UST** **S127528314**
NNE **31 N I 35** **TX RDR** **N/A**
< 1/8 **AUSTIN, TX**
0.074 mi.
392 ft. **Site 3 of 4 in cluster OM**

Actual:
460 ft.

HIST UST AUSTIN:

Focus Map:
14

Name:	CITY STAR FOODS
Address:	31 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	1097
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CITY STAR FOODS (Continued) **S127528314**

RDR:

RDR ID:	2995
Facility ID:	26067
RN:	Not reported
CN:	Not reported
Name:	CITY STAR FOODS
Address:	31 N I 35
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/25/2001
Due Date:	3/26/2001
Tank Owner:	LARI INC
Contact Person:	ISMAIL ALI
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/13/2003
Project Manager:	Laurie Daniel
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ISSUE NO LEAKER, PENDING 2ND REVIEW
Review Coordinator:	LLD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/13/2003
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

2477 WNW < 1/8 0.074 mi. 393 ft. **GREENBERG GRANT & RICHARDS** **EDR Hist Auto** **1021589352**
80 RED RIVER ST **N/A**
AUSTIN, TX 78701

Actual: 459 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1996	GREENBERG GRANT & RICHARDS	Automotive Transmission Repair Shops
1997	GREENBERG GRANT & RICHARDS	Automotive Transmission Repair Shops
1998	GREENBERG GRANT & RICHARDS	Automotive Transmission Repair Shops

---

2478 WNW < 1/8 0.075 mi. 394 ft. **CONANN DEVELOPMENT** **TX UST** **U001271023**
11220 N LAMAR BLVD **TX HIST UST** **N/A**
AUSTIN, TX 78753

Actual: 759 ft.

Focus Map: 3

UST:

Name:	CONANN DEVELOPMENT
Address:	11220 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787533000
AI Number:	38382
Facility Type:	UNKNOWN
Facility Begin Date:	01/08/1987
Facility Status:	INACTIVE

CONANN DEVELOPMENT (Continued) **U001271023**

Additional ID:	38354502003197
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	W H LEMORE,GEN SUPT
Contact Organization Name:	CONANN DEVELOPMENT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128360331
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/27/1986
Signature Name/Title On Earliest Reg Form:	W H LEMORE,GEN SUPT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN604203802
Owner Last Name:	CONANN DEVELOPMENT CO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	482333922012345
Additional ID:	38354502003197
AI Number:	38382
Owner Effective Begin Date:	01/08/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1

CONANN DEVELOPMENT (Continued) **U001271023**

Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	101148
Facility ID:	69458
Ai Number:	38382
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

CONANN DEVELOPMENT (Continued) **U001271023**

Tank Tested Flag:	N
Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	84048
UST ID:	101148
AI Number:	38382
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	14939
Cert ID:	137549
UST Comprt ID:	404950
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137548

CONANN DEVELOPMENT (Continued) **U001271023**

UST Comprt ID:	404951
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137547
UST Comprt ID:	404952
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137546
UST Comprt ID:	404953
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137545
UST Comprt ID:	404954
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137544
UST Comprt ID:	404955
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137543
UST Comprt ID:	404958
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137542
UST Comprt ID:	404957
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137541
UST Comprt ID:	404956

CONANN DEVELOPMENT (Continued) **U001271023**

UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	373109
UST Comprt ID:	1087186
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	356307
UST Comprt ID:	1036468
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	339565
UST Comprt ID:	986019
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	323250
UST Comprt ID:	936791
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	318547
UST Comprt ID:	922754
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	236214
UST Comprt ID:	678103
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	219669
UST Comprt ID:	629635
UST ID:	125020

CONANN DEVELOPMENT (Continued) **U001271023**

AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	303275
UST Comprt ID:	877070
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	287194
UST Comprt ID:	828927
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	269213
UST Comprt ID:	775580
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	253675
UST Comprt ID:	729486
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137552
UST Comprt ID:	404947
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137550
UST Comprt ID:	404949
UST ID:	125020
AI Number:	38382
Tank ID:	2
Compartment ID:	A
Self Cert ID:	14939
Cert ID:	137551
UST Comprt ID:	404948
UST ID:	125020
AI Number:	38382

CONANN DEVELOPMENT (Continued) **U001271023**

Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CONANN DEVELOPMENT CO
Contact Mailing Address (Delivery):	11220 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3000
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	69458
Additional ID:	38354502003197
Princ ID:	482333922012345
AI Number:	38382
Facility Name:	CONANN DEVELOPMENT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	AUSTIN AUTOMOTIVE
Address:	11220 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0072
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MZ2479 **HASSE SERVICE STATION FILLING ST** **EDR Hist Auto** **1013759547**
ESE **1511 LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
395 ft. **Site 4 of 6 in cluster MZ**

Actual:
551 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	PUBLIX SERVICE CO INC	AUTOMOBILE GARAGES
1929	SEVERN BROS FILL STA	GASOLINE AND OIL SERVICE STATIONS
1935	BARROW SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1940	SIMON AUTO ELEC	AUTOMOBILE REPAIRING
1940	HASSE SERVICE STATION FILLING S	GASOLINE AND OIL SERVICE STATIONS
1947	CAPITOL MOTOR CO	AUTOMOBILE REPAIRING
1953	JOHNSON GENE SERV	GASOLINE STATIONS
1953	STEINER B M GARAGE	AUTOMOBILE REPAIRING
1958	STEINER MORRISS	AUTOMOBILE REPAIRING
1958	JOHNSON GENE SERV	GASOLINE STATIONS
1962	JOHNSON GENE SERV	GASOLINE STATIONS
1965	JOHNSON GENE SERVICE	GASOLINE STATIONS

ON2480 ESE < 1/8 0.075 mi. 396 ft. | **ST. EDWARDS UNIVERSITY**
3001 S CONGRESS
AUSTIN, TX | **TX RDR** | **S127529727**
N/A

Site 1 of 3 in cluster ON

Actual: 632 ft.

Focus Map: 14

RDR:

RDR ID:	3998
Facility ID:	3075
RN:	Not reported
CN:	Not reported
Name:	ST. EDWARDS UNIVERSITY
Address:	3001 S CONGRESS
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/18/1999
Due Date:	12/17/1999
Tank Owner:	ST. EDWARDS UNIVERSITY
Contact Person:	JIM FLETCHER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/3/1999
Project Manager:	Brent Rice
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	APPROVED
Review Coordinator:	BJR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/3/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

ON2481 ESE < 1/8 0.075 mi. 396 ft. | **ST EDWARDS UNIVERSITY**
3001 S CONGRESS AVE
AUSTIN, TX 78704 | **TX AST** | **A100173942**
N/A

Site 2 of 3 in cluster ON

Actual: 632 ft.

Focus Map: 14

AST:

Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787046425
Facility ID:	41670
Additional ID:	149799842002068
AI Number:	3075
Facility Type:	UNKNOWN
Facility Begin Date:	06/12/1986
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78704

ST EDWARDS UNIVERSITY (Continued) **A100173942**

Contact Name/Title:	JJ FLETCHER/DIRECTOR
Contact Organization Name:	ST EDWARDS UNIVERSITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124488787
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	03/12/1986
Signature First Name on Earliest Reg Form:	J J
Application Received Date on Earliest Reg Form:	05/08/1986
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	FLETCHER
Signature Title on Earliest Reg Form:	DIRECTOR
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	41670
Tank ID:	1
AST ID:	189068
AI Number:	3075
Install Date:	11/01/1998
Tank Registration Date:	12/11/1998
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	11/01/1998
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000
Substance:	UNKNOWN
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

ON2482	**ST EDWARDS UNIVERSITY**	**TX UST**	**U003841439**
ESE	**3001 S CONGRESS AVE**	**TX HIST UST**	**N/A**
< 1/8	**AUSTIN, TX 78704**	**TX AIRS**	
0.075 mi.		**TX ASBESTOS**	
396 ft.	**Site 3 of 3 in cluster ON**	**TX Financial Assurance**	
Actual:		**TX COMP HIST**	
632 ft.		**TX CENTRAL REGISTRY**	

Focus Map:
14

UST:

Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787046425
AI Number:	3075
Facility Type:	UNKNOWN
Facility Begin Date:	06/12/1986
Facility Status:	ACTIVE
Additional ID:	149799842002068
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	JJ FLETCHER,DIRECTOR
Contact Organization Name:	ST EDWARDS UNIVERSITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124488787
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/12/1986
Signature Name/Title On Earliest Reg Form:	J J FLETCHER,DIRECTOR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600410898
Owner Last Name:	SAINT EDWARDS UNIVERSITY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Princ ID:	47532102001313
Additional ID:	149799842002068
AI Number:	3075
Owner Effective Begin Date:	06/12/1986
State Tax ID:	17411096419
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	7526
Facility ID:	41670
Ai Number:	3075
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/16/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/08/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	10549
UST ID:	7526
AI Number:	3075
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	7527
Facility ID:	41670
Ai Number:	3075
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/01/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/08/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	10550
UST ID:	7527
AI Number:	3075
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	7528

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Facility ID:	41670
Ai Number:	3075
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/16/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/08/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	550

ST EDWARDS UNIVERSITY (Continued) **U003841439**

UST Comprt ID:	10551
UST ID:	7528
AI Number:	3075
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SAINT EDWARDS UNIVERSITY INC
Contact Mailing Address (Delivery):	3001 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 6425
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	41670
Additional ID:	149799842002068
Princ ID:	47532102001313
AI Number:	3075
Facility Name:	ST EDWARDS UNIVERSITY
AR Number:	1866
AR UST Number Suffix:	A

ST EDWARDS UNIVERSITY (Continued) **U003841439**

AR AST Number Suffix: U
Contact Name/Title: PHYSICAL PLANT/

HIST UST AUSTIN:

Name:	ST. EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	253
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AIRS:

Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Permit Num:	98802
Regulated Id:	RN100723147
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	11/10/2011
Expiration Date:	12/31/3000
Customer Id:	CN600410898
Company Name:	SAINT EDWARDS UNIVERSITY INC
Physical Location Desc:	3001 S CONGRESS
Rep Official(RO):	ASSOCIATE VP FACILITIES
RO Name:	MR MICHAEL PETERSON
RO Delivery Address:	3001 S CONGRESS AVE
RO City/State/Zip:	AUSTIN, T 78704-642
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	MICHAELP@STEDWARDS.EDU
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

ASBESTOS:

Name:	CHAPEL
Address:	3001 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/03/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2012009996
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	02/01/2013
Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/28/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. EDWARD'S UNIVERSITY-MANG HOUSE
Address:	3001 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	10/15/2013
Reason for Inspection:	Notified

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Violation:	Yes
Complaint Date:	Not reported
Notification Number:	2013006664
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/13/2013
Date Routed by Supervisor:	11/19/2013
Date Routed to PSQA:	11/20/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SEU CHAPEL
Address:	3001 SOUTH CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/25/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2014000969
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/02/2014
Date Routed by Supervisor:	05/15/2014
Date Routed to PSQA:	05/16/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. EDWARD'S UNIVERSITY-ALUMNI GYM
Address:	3001 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	09/30/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013006533
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/16/2013
Date Routed by Supervisor:	11/04/2013
Date Routed to PSQA:	11/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. EDWARD'S UNIVERSITY - MOODY HALL
Address:	3001 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Bill Bishop
Violation:	Not reported
Complaint Date:	04/23/2021
Notification Number:	2021002231
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/06/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/06/2021
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	04/21/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MOODY HALL
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/19/2022
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	05/25/2022
Notification Number:	2022002664
ASB Priority:	Not reported
PIF State:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/20/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	68
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/06/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MOODY HALL
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/19/2022
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	05/25/2022
Notification Number:	2022002664
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/20/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	68
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/06/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST EDWARDS UNIVERSITY HOLY CROSS HALL ROOM 120 AND 220
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	BILL BISHOP
Violation:	Not reported
Complaint Date:	02/02/2016
Notification Number:	2016001002
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/28/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/14/2016
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

ST EDWARDS UNIVERSITY (Continued) **U003841439**

ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST EDWARDS UNIVERSITY HOLY CROSS HALL ROOM 120 AND 220
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	BILL BISHOP
Violation:	Not reported
Complaint Date:	02/05/2016
Notification Number:	2016001002
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/26/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/22/2016
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	02/05/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST EDWARDS UNIVERSITY THEATER BUILDING
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	BILL BISHOP
Violation:	Not reported
Complaint Date:	09/01/2016
Notification Number:	2016007078
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/19/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/18/2016
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST EDWARDS UNIVERSITY - CARRIAGE HOUSE
Address:	3001 S CONGRESS AVE

ST EDWARDS UNIVERSITY (Continued) **U003841439**

City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	BILL BISHOP
Violation:	Not reported
Complaint Date:	08/28/2016
Notification Number:	2016007337
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/30/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/25/2016
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/26/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. EDWARD'S UNIVERSITY - PREMONT HALL MECHANICAL ROOM
Address:	3001 S. CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Lee Thompson
Violation:	Not reported
Complaint Date:	08/19/2021
Notification Number:	2021005274
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/29/2021
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

ST EDWARDS UNIVERSITY (Continued) **U003841439**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/19/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST EDWARDS CLASSROOM BUILDING
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/23/2022
Notification Number:	2022007387
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/15/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	12/13/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST EDWARDS CLASSROOM BUILDING
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/16/2022
Notification Number:	2022007387
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Date Report Received:	12/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/12/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	12/13/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST EDWARDS CLASSROOM BUILDING
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew Kubasta
Violation:	Not reported
Complaint Date:	12/16/2022

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Notification Number:	2022007387
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/21/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/21/2022
Certification Statement Phone:	737-444-0877
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	12/12/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ST. EDWARD'S UNIVERSITY - ANDRE HALL
Address:	3001 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew Zappa
Violation:	Not reported
Complaint Date:	01/31/2019
Notification Number:	2018008468
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/20/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/03/2018
Certification Statement Phone:	512-708-9390
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	101
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/02/2019
Client Code:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ST. EDWARD'S UNIVERSITY - ANDRE HALL
Address:	3001 S. CONGRESS AVE.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Matthew Zappa
Violation:	Not reported
Complaint Date:	12/28/2018
Notification Number:	2018008468
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/19/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/19/2018
Certification Statement Phone:	512-708-9390

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	101
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/04/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MOODY HALL
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/05/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/19/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022002664
File Number:	70942
License Status Description:	Paid
Expiration Date:	05/25/2022
Original Date:	04/20/2022
Rank Effective Date:	04/20/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	33334
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	MOODY HALL
Address:	3001 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/05/11
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/11/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022002664
File Number:	70942
License Status Description:	Paid
Expiration Date:	05/25/2022
Original Date:	04/20/2022
Rank Effective Date:	04/20/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	33047
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

ST EDWARDS UNIVERSITY (Continued) **U003841439**

TX Financial Assurance 2:

Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	41670
Finass ID:	22574
AI:	3075
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

COMP HIST:

RN Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600410898
CN Name:	SAINT EDWARDS UNIVERSITY INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	0115
Related Number:	TXP490355286,42013,TH0380S,98802,TXR15229U,TXR15118T,3075,3075

RN Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603705898
CN Name:	HILL & WILKINSON CONSTRUCTION GROUP LTD
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	7999
Related Number:	TXP490355286,42013,TH0380S,98802,TXR15229U,TXR15118T,3075,3075

RN Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603796467
CN Name:	JT VAUGHN CONSTRUCTION LLC
CN Rating:	.53
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	1542
Related Number:	TXP490355286,42013,TH0380S,98802,TXR15229U,TXR15118T,3075,3075

RN Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604082230
CN Name:	FLINTCO LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	1542
Related Number:	TXP490355286,42013,TH0380S,98802,TXR15229U,TXR15118T,3075,3075

RN Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN602605107
CN Name:	BAILEY ELLIOTT CONSTRUCTION INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236210
SIC Code:	1522
Related Number:	TXP490355286,42013,TH0380S,98802,TXR15229U,TXR15118T,3075,3075

CENTRAL REGISTRY:

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600410898
Customer Name:	SAINT EDWARDS UNIVERSITY INC
Customer Legal Name:	Saint Edward's University, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/12/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600410898
Customer Name:	SAINT EDWARDS UNIVERSITY INC
Customer Legal Name:	Saint Edward's University, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/12/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604052191
Customer Name:	ST EDWARDS UNIVERSITY
Customer Legal Name:	ST EDWARDS UNIVERSITY
Customer Ownership Type:	OTHER
Affiliation Begin Date:	3/13/2012

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604052191
Customer Name:	ST EDWARDS UNIVERSITY
Customer Legal Name:	ST EDWARDS UNIVERSITY
Customer Ownership Type:	OTHER
Affiliation Begin Date:	3/13/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/2/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603796467
Customer Name:	JT VAUGHN CONSTRUCTION LLC
Customer Legal Name:	J.T. Vaughn Construction, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/2/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Primary NAICS Industry Type Description: Industrial Building Construction
Physical Location Description: 3001 S. CONGRESS

Regulated Entity Number: RN100723147
Name: ST EDWARDS UNIVERSITY
Address: 3001 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-6425
Status: ACTIVE
Status Date: ##########
Customer Number: CN604082230
Customer Name: FLINTCO LLC
Customer Legal Name: Flintco, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/30/2007
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236210
Primary NAICS Industry Type Description: Industrial Building Construction
Physical Location Description: 3001 S. CONGRESS

Regulated Entity Number: RN100723147
Name: ST EDWARDS UNIVERSITY
Address: 3001 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-6425
Status: ACTIVE
Status Date: ##########
Customer Number: CN604082230
Customer Name: FLINTCO LLC
Customer Legal Name: Flintco, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/30/2007
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236210
Primary NAICS Industry Type Description: Industrial Building Construction
Physical Location Description: 3001 S. CONGRESS

Regulated Entity Number: RN100723147
Name: ST EDWARDS UNIVERSITY
Address: 3001 S CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-6425
Status: ACTIVE
Status Date: ##########
Customer Number: CN602605107
Customer Name: BAILEY ELLIOTT CONSTRUCTION INC
Customer Legal Name: Bailey Elliott Construction, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 4/5/2006
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236210
Primary NAICS Industry Type Description: Industrial Building Construction
Physical Location Description: 3001 S. CONGRESS

ST EDWARDS UNIVERSITY (Continued) **U003841439**

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602605107
Customer Name:	BAILEY ELLIOTT CONSTRUCTION INC
Customer Legal Name:	Bailey Elliott Construction, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/5/2006
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Regulated Entity Number:	RN100723147
Name:	ST EDWARDS UNIVERSITY
Address:	3001 S CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-6425
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603705898
Customer Name:	HILL & WILKINSON CONSTRUCTION GROUP LTD
Customer Legal Name:	Hill & Wilkinson Construction Group, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	11/7/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236210
Primary NAICS Industry Type Description:	Industrial Building Construction
Physical Location Description:	3001 S. CONGRESS

Click this hyperlink while viewing on your computer to access
182 additional TX CENTRAL REG: record(s) in the EDR Site Report.

2483 **UNIVERSITY BODY** **EDR Hist Auto** **1013761957**
ESE **1409 LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
396 ft.

Actual:
543 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	1409 11 AUSTIN BRAKE SERVICE	AUTOMOBILE REPAIRERS
1940	UNIVERSITY BODY	AUTOMOBILE REPAIRING

OO2484 **WR ROBBINS SECONDARY SCHOOL** **TX Ind. Haz Waste** **S103607402**
WNW **3908 AVENUE B** **N/A**
< 1/8 **AUSTIN, TX 78751**
0.075 mi.
396 ft. **Site 1 of 2 in cluster OO**

Actual:
613 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	WR ROBBINS SECONDARY SCHOOL
Address:	3908 AVENUE B
City,State,Zip:	AUSTIN, TX 78751
Permit Number:	Not reported
Registration Number:	69681
Registration Initial Notification Date:	08/30/1986
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981585292
Primary NAICS Code:	Not reported
Status Change Date:	19860830
Land Type:	Not reported
Description of Facility Site Location:	3908 Avenue B, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	WAYNE SCHADE PHD
Contact Telephone Number:	512-4518411
Mailing Address:	6100 GUADALUPE ST RM 210
Mailing Address2:	ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 787524420
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24553
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

WR ROBBINS SECONDARY SCHOOL (Continued) **S103607402**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	6100 GUADALUPE ST RM 210
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4518411
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	6100 GUADALUPE ST RM 210
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4518411
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

WR ROBBINS SECONDARY SCHOOL (Continued) **S103607402**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WAYNE SCHADE PHD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	ROOM 210
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

OO2485 **AUSTIN ISD** **RCRA NonGen / NLR** **1000130157**
WNW **3908 AVENUE B** **FINDS** **TXD981585292**
< 1/8 **AUSTIN, TX 78751** **ECHO**
0.075 mi.
396 ft. **Site 2 of 2 in cluster OO**

Actual:
613 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Austin Isd
Handler Address:	AVENUE B
Handler City,State,Zip:	AUSTIN, TX 78751
EPA ID:	TXD981585292
Contact Name:	WAYNE SCHADE PHD
Contact Address:	GUADALUPE ROOM 210
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-451-8411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

AUSTIN ISD (Continued) **1000130157**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Austin Isd
Owner Type:	Not reported
Operator Name:	Austin Isd
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

AUSTIN ISD (Continued) **1000130157**

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: District
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860814
Handler Name: W R ROBBINS SECONDART SCHOOL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

AUSTIN ISD (Continued) **1000130157**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: AUSTIN ISD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005090766

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000130157
Registry ID: 110005090766
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005090766
Name: AUSTIN ISD
Address: 3908 AVENUE B
City,State,Zip: AUSTIN, TX 78751

LT2486 ESE < 1/8 0.075 mi. 396 ft. — **LAVACA ST GARAGE**, **1417 LAVACA ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013760786** / **N/A**

Site 7 of 9 in cluster LT

Actual: 546 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1922	LAVACA ST GARAGE	AUTOMOBILE GARAGES

MQ2487 ENE < 1/8 0.075 mi. 396 ft. — **EVANS DELWOOD CONOCO**, **4201 EAST AVE**, **AUSTIN, TX 78723** — **EDR Hist Auto** — **1021062133** / **N/A**

Site 15 of 18 in cluster MQ

Actual: 588 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1969	EVANS DELWOOD CONOCO	Gasoline Service Stations
1970	EVANS DELWOOD CONOCO	Gasoline Service Stations

OP2488 ESE < 1/8 0.075 mi. 396 ft. — **DOLLARS & SENSE DRY CLEANERS**, **6929 AIRPORT BLVD STE 165**, **AUSTIN, TX 78752** — **TX ASBESTOS**, **TX DRYCLEANERS** — **S109360389** / **N/A**

Site 1 of 2 in cluster OP

Actual: 716 ft. ASBESTOS:

Focus Map: 6

Name:	HIGHLAND VILLAGE SHOPPING CENTER
Address:	6929 AIRPORT BLVD.
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	07/29/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013005180
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	01
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	08/20/2013
Date Routed by Supervisor:	08/28/2013
Date Routed to PSQA:	09/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOLLAR GENERAL
Address:	6929 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	06/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

Reg:	07
Init:	EJ
Seq:	07
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/01/2013
Date Routed by Supervisor:	07/01/2013
Date Routed to PSQA:	07/09/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FUTURE DOMINO'S
Address:	6929 AIRPORT BLVD.,

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	PAUL B DEHLINGER
Violation:	Not reported
Complaint Date:	01/18/2021
Notification Number:	2021000006
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/16/2021
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FUTURE DOMINO'S
Address:	6929 AIRPORT BLVD.,
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	PAUL B DEHLINGER
Violation:	Not reported
Complaint Date:	01/18/2021
Notification Number:	2021000006
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/04/2021
Certification Statement Phone:	979-229-4385
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/18/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DRYCLEANERS:

Name:	DOLLARS & SENSE DRY CLEANERS
Address:	6929 AIRPORT BLVD STE 165
City,State,Zip:	AUSTIN, TX 78752
RN Number:	RN103993713
Region:	11
CN Number:	CN602616617
DCR Number:	Not reported
AR Number:	24002565
Principal Name:	DOLLARS AND SENSE DRY CLEANERS
Bill Addr1:	6929 AIRPORT BLVD STE 165
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78752 3616
EMail:	Not reported
Phone Number:	Not reported
Site Name:	DOLLARS & SENSE DRY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $100,000 AND < $200,000

Name:	DOLLARS & SENSE DRY CLEANERS
Address:	6929 AIRPORT BLVD STE 165
City,State,Zip:	AUSTIN, TX 78752
RN Number:	RN103993713
Region:	11
CN Number:	CN602616617
DCR Number:	Not reported
AR Number:	24002565
Principal Name:	DOLLARS AND SENSE DRY CLEANERS

DOLLARS & SENSE DRY CLEANERS (Continued) **S109360389**

Bill Addr1:	6929 AIRPORT BLVD STE 165
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78752 3616
EMail:	Not reported
Phone Number:	Not reported
Site Name:	DOLLARS & SENSE DRY CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	250
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

OP2489 **RAILYARD** **EDR Hist Cleaner** **1018881989**
ESE **6929 AIRPORT BLVD** **N/A**
< 1/8 **AUSTIN, TX 78752**
0.075 mi.
396 ft. **Site 2 of 2 in cluster OP**

Actual:
716 ft. EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1995	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
1996	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
1997	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
1998	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
1999	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2000	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2001	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2002	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2003	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2004	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2005	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2006	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2007	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2008	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2008	RAILYARD	Laundry And Drycleaner Agents
2009	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2010	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2011	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2012	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2013	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2014	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents

---

MR2490 **1311 13 YOUNG & SCHIEFFER AUTO REPRS** **EDR Hist Auto** **1013755822**
ESE **1311 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
396 ft. **Site 8 of 12 in cluster MR**

Actual:
539 ft. EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	1311 13 YOUNG & SCHIEFFER AUTO	AUTOMOBILE REPAIRERS
1940	YOUNG & SCHIEFFER FILLING STA	GASOLINE AND OIL SERVICE STATIONS

1311 13 YOUNG & SCHIEFFER AUTO REPRS (Continued) **1013755822**

1940	YOUNG & SCHIEFFER FILLING STA	AUTOMOBILE REPAIRERS

MR2491 **SPRINKLES BODY SHOP** **EDR Hist Auto** **1013776613**
ESE **1305 LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
396 ft. **Site 9 of 12 in cluster MR**

Actual:
539 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	SWEETS GARAGE	AUTOMOBILE REPAIRING
1947	SPRINKLES BODY SHOP	AUTOMOBILE REPAIRING

MZ2492 **BATTERY SERVICE CO** **EDR Hist Auto** **1013756222**
ESE **1603 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
397 ft. **Site 5 of 6 in cluster MZ**

Actual:
557 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	BATTERY SERVICE CO	AUTOMOBILE ELECTRIC REPAIRS
1929	BATTERY SERVICE CO	AUTOMOBILE REPAIRERS
1935	TRAVELERS GARAGE	AUTOMOBILE REPAIRERS
1940	TRAVELERS GARAGE	AUTOMOBILE REPAIRING

LT2493 **KALLGREN & HAMILTON** **EDR Hist Cleaner** **1013779464**
ESE **1419 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
397 ft. **Site 8 of 9 in cluster LT**

Actual:
546 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1935	KALLGREN & HAMILTON	CLOTHES PRESSERS AND CLEANERS
1940	KALLGREN & HAMIL	CLOTHES PRESSERS AND CLEANERS
1947	KALLGREN & HAMILTON CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1958	KALLGREN & HAMIL	CLEANERS AND DYERS

LT2494 **KING I B STOVE** **EDR Hist Auto** **1013760770**
ESE **1419 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.075 mi.
397 ft. **Site 9 of 9 in cluster LT**

Actual:
546 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	KING I B STOVE	REPAIR SHOPS

MR2495
ESE
< 1/8
0.075 mi.
397 ft.

LUDER FRED AUTO REPR
1313 LAVACA ST
AUSTIN, TX

Site 10 of 12 in cluster MR

EDR Hist Auto **1013767492**
N/A

Actual:
539 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	LUDER FRED AUTO REPR	AUTOMOBILE REPAIRERS
1947	SCHIEFFERS ROGER SERV FILL STA	GASOLINE AND OIL SERVICE STATIONS
1947	SCHIEFFERS ROGER SERV FILL STA	AUTOMOBILE REPAIRING

2496
WNW
< 1/8
0.075 mi.
397 ft.

FERRIS FRAME ALLGNMENT INC
830 SAGEBRUSH DR
TRAVIS (County), TX 78758

EDR Hist Auto **1013760202**
N/A

Actual:
725 ft.

Focus Map:
3

EDR Hist Auto

Year:	Name:	Type:
1979	FERRIS FRANK ALLIGNMENT INC	Automotive Repair Shops, NEC
1980	FERRIS FRAME ALIGNMENT INC	AUTOMOBILE REPAIRING
1980	FERRIS FRANK ALLIGNMENT INC	Automotive Repair Shops, NEC
1982	FERRIS FRANK ALIGNMENT INC	Automotive Repair Shops, NEC
1983	FERRIS FRANK ALIGNMENT INC	Automotive Repair Shops, NEC
1984	FERRIS FRAME ALIGNMENT INC	AUTOMOBILE REPAIRING
1985	FERRIS FRAME ALIGNMENT INC	Automotive Repair Shops, NEC
1986	FERRIS FRAME ALIGNMENT INC	Automotive Repair Shops, NEC
1987	FERRIS FRAME ALIGNMENT INC	Automotive Repair Shops, NEC
1988	FERRIS FRAME ALIGNMENT INC	Automotive Repair Shops, NEC
1990	FERRIS FRAME ALLGNMENT INC	AUTOMOBILE REPAIRING

2497
ESE
< 1/8
0.076 mi.
399 ft.

EXXON MOBIL CORPORATION
619 W NORTH LOOP 35
AUSTIN, TX 78751

EDR Hist Auto **1020517159**
N/A

Actual:
665 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1994	EXXON CORPORATION	Gasoline Service Stations
1995	EXXON CORPORATION	Gasoline Service Stations
1996	EXXON CORPORATION	Gasoline Service Stations
1997	EXXON CORPORATION	Gasoline Service Stations
1998	EXXON CORPORATION	Gasoline Service Stations
1999	EXXON MOBIL CORPORATION	Gasoline Service Stations
2000	EXXON MOBIL CORPORATION	Gasoline Service Stations
2001	EXXON MOBIL CORPORATION	Gasoline Service Stations
2002	EXXON MOBIL CORPORATION	Gasoline Service Stations

OQ2498 **WALLACE ENGRAVING CO INC** **RCRA NonGen / NLR** **1000275822**
ESE **407 LAVACA STREET** **FINDS** **TXD000017970**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.076 mi.
400 ft. **Site 1 of 5 in cluster OQ**

Actual:
483 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Wallace Engraving Co Inc
Handler Address:	LAVACA STREET
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD000017970
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	PO BOX 1485
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 1485
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	Wallace Engraving Co Inc
Owner Type:	Private
Operator Name:	Wallace Engraving Co Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

WALLACE ENGRAVING CO INC (Continued) **1000275822**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: WALLACE ENGRAVING CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1485
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: H S WALLACE JR	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALLACE ENGRAVING CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1485
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19800818

WALLACE ENGRAVING CO INC (Continued) **1000275822**

Handler Name: WALLACE ENGRAVING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: WALLACE ENGRAVING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 339999
NAICS Description: ALL OTHER MISCELLANEOUS MANUFACTURING

NAICS Code: 453998
NAICS Description: ALL OTHER MISCELLANEOUS STORE RETAILERS (EXCEPT TOBACCO STORES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005026408

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

WALLACE ENGRAVING CO INC (Continued) **1000275822**

Envid:	1000275822
Registry ID:	110005026408
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005026408
Name:	WALLACE ENGRAVING CO INC
Address:	407 LAVACA STREET
City,State,Zip:	AUSTIN, TX 78701

OQ2499 **WALLACE ENGRAVING** **TX Ind. Haz Waste** **S102740914**
ESE **407 LAVACA ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.076 mi.
400 ft. **Site 2 of 5 in cluster OQ**

Actual:
483 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	WALLACE ENGRAVING
Address:	407 LAVACA ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	33347
Registration Initial Notification Date:	07/27/2001
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD000017970
Primary NAICS Code:	Not reported
Status Change Date:	20010727
Land Type:	PRIVATE
Description of Facility Site Location:	407 Lavaca Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	THE WHITLEY COMPANY LP
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 1485
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671485
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	10846
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

WALLACE ENGRAVING (Continued) **S102740914**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	WALLACE ENGRAVING CO INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	THE WHITLEY COMPANY LP
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17413840301
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	THE WHITLEY COMPANY LP
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17413840301
Owner Bankruptcy Code:	Not reported

Owner Name:	WALLACE ENGRAVING CO INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported

WALLACE ENGRAVING (Continued) **S102740914**

Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1485
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100616085
Name:	WALLACE ENGRAVING
Address:	407 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2927
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600325203
Customer Name:	THE WHITLEY COMPANY LP
Customer Legal Name:	The Whitley Company, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	407 Lavaca Street, Austin, TX

Regulated Entity Number:	RN100616085
Name:	WALLACE ENGRAVING
Address:	407 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2927
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600325203
Customer Name:	THE WHITLEY COMPANY LP
Customer Legal Name:	The Whitley Company, L.P.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	407 Lavaca Street, Austin, TX

Regulated Entity Number:	RN100616085

WALLACE ENGRAVING (Continued) **S102740914**

Name:	WALLACE ENGRAVING
Address:	407 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2927
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603908526
Customer Name:	WALLACE ENGRAVING CO INC
Customer Legal Name:	WALLACE ENGRAVING CO INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	407 Lavaca Street, Austin, TX

Regulated Entity Number:	RN100616085
Name:	WALLACE ENGRAVING
Address:	407 LAVACA ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2927
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603908526
Customer Name:	WALLACE ENGRAVING CO INC
Customer Legal Name:	WALLACE ENGRAVING CO INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	407 Lavaca Street, Austin, TX

2500 ESE < 1/8 0.076 mi. 401 ft. | **CENTRAL ELECTRICAL APPLIANCE 6719 SHIRLEY AVE AUSTIN, TX** | **TX HIST UST** | **S128728896 N/A**

Actual: 711 ft.

Focus Map: 6

HIST UST AUSTIN:

Name:	CENTRAL ELECTRICAL APPLIANCE
Address:	6719 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX
Id UST:	C0088
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MO2501
NE
< 1/8
0.076 mi.
401 ft.

TOWN LAKE CHEVRON SERVICE STATION
30 INTERREGIONAL HWY N
TRAVIS (County), TX 78701

EDR Hist Auto **1013761764**
N/A

Site 5 of 5 in cluster MO

Actual:
456 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1970	TOWN LAKE GULF GAS ST	GASOLINE STATIONS
1975	TOWN LAKE GULF SERVICE STATION	GASOLINE STATIONS
1980	TOWN LAKE GULF SERVICE STATION	GASOLINE STATIONS
1984	TOWN LAKE GULF SERVICE STATION	GASOLINE STATIONS
1990	TOWN LAKE CHEVRON SERVICE STATI	GASOLINE STATIONS

NX2502
NNE
< 1/8
0.076 mi.
402 ft.

DARTER WELDING
408 SAN JACINTO ST
AUSTIN, TX

EDR Hist Auto **1013769143**
N/A

Site 5 of 7 in cluster NX

Actual:
482 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	TUMEY T L GARAGE	AUTOMOBILE GARAGES
1929	TUMEY T L GARAGE	AUTOMOBILE REPAIRERS
1935	DARTER WELDING	AUTOMOBILE REPAIRERS
1935	UZZELL AUTO SERVICE	AUTOMOBILE REPAIRERS

NX2503
NNE
< 1/8
0.076 mi.
402 ft.

SAN JACINTO CLEANERS
408 SAN JACINTO BLVD
AUSTIN, TX

EDR Hist Cleaner **1013783558**
N/A

Site 6 of 7 in cluster NX

Actual:
482 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1935	SAN JACINTO CLEANERS	CLOTHES PRESSERS AND CLEANERS

2504
WNW
< 1/8
0.076 mi.
402 ft.

WATTINGER CO., INC.
114 RALPH ABLANEDO DR
AUSTIN, TX

TX HIST UST **S128728995**
N/A

Actual:
688 ft.

Focus Map:
21

HIST UST AUSTIN:

Name:	WATTINGER CO., INC.
Address:	114 RALPH ABLANEDO DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0321
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

LA2505 WSW < 1/8 0.076 mi. 403 ft. — **J. C. BRYANT CREAMERY**, **200 W 5TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678689** / **N/A**

Site 15 of 15 in cluster LA

Actual: 492 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	J. C. BRYANT CREAMERY
Address:	200 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0995
HID UST:	995
Inspection:	03/19/2009
Due:	03/19/2012

NM2506 ESE < 1/8 0.077 mi. 404 ft. — **AUSTINS HOME LNDRY**, **104 31ST E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783972** / **N/A**

Site 5 of 6 in cluster NM

Actual: 588 ft.
Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1940	AUSTINS HOME LNDRY	LAUNDRIES

NM2507 ESE < 1/8 0.077 mi. 404 ft. — **MALMBERG H G AUTO**, **104 31ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013769936** / **N/A**

Site 6 of 6 in cluster NM

Actual: 588 ft.
Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1935	MALMBERG H G AUTO	AUTOMOBILE REPAIRERS

NL2508 SSW < 1/8 0.077 mi. 404 ft. — **HONG LEE MRS CHINESE LAUNDRY**, **411 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013777452** / **N/A**

Site 3 of 5 in cluster NL

Actual: 486 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1896	HONG LEE MRS CHINESE LAUNDRY	LAUNDRIES
1901	JOE LEE CHINESE LAUNDRY UMBIE	LAUNDRIES
1906	DAN SING	LAUNDRIES

2509 ESE < 1/8 0.077 mi. 404 ft. | **GULF INTRACOASTAL CANAL ASSOC**
221 E 9TH ST STE 206
AUSTIN, TX 78701 | **EDR Hist Auto** | **1021500691**
N/A

Actual: 529 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1991	GULF INTRACOASTAL CANAL ASSOC	Gasoline Service Stations

OR2510 WNW < 1/8 0.077 mi. 405 ft. | **POWELL OFFSET SERVICE**
2007 S 1ST ST
AUSTIN, TX 78704
Site 1 of 4 in cluster OR | **TX Ind. Haz Waste** | **S104855371**
N/A

Actual: 530 ft.

Focus Map: 14

Ind. Haz Waste:

Name:	POWELL OFFSET SERVICE
Address:	2007 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	81992
Registration Initial Notification Date:	05/06/1994
Registration Last Amendment Date:	12/06/2007
EPA Identification:	Not reported
Primary NAICS Code:	323119
Status Change Date:	19940506
Land Type:	Not reported
Description of Facility Site Location:	2007 S 1st St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	Not reported
Company Name:	POWELL OFFSET SERVICE INC
Contact Name:	BOBBY POWELL
Contact Telephone Number:	512-4426446
Mailing Address:	2007 S 1ST ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787045194
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	37100
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20071212
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

POWELL OFFSET SERVICE (Continued) **S104855371**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	POWELL OFFSET SERVICE INC
Operator Address:	2007 S 1ST ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-4426446
Operator Fax Number:	1-512-3265556
Operator Email:	powellinc@swbell.net
Operator Business Type:	Unknown
Operator Tax ID:	17422444285
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	POWELL OFFSET SERVICE INC
Owner Mailing Address:	2007 S 1ST ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-4426446
Owner Fax:	1-512-3265556
Owner Email Address:	powellinc@swbell.net
Owner Business Type:	Unknown
Owner Tax ID:	17422444285
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2007 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4426446
Contact Fax:	1-512-3265556
Contact Email:	powellinc@swbell.net

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2007 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704

POWELL OFFSET SERVICE (Continued) **S104855371**

Contact Phone:	1-512-4426446
Contact Fax:	1-512-3265556
Contact Email:	powellinc@swbell.net
Contact Name:	BOBBY POWELL
Contact Title:	VICE PRESIDENT
Contact Role:	PRICONT
Contact Address:	2007 S 1ST ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-4426446
Contact Fax:	1-512-3265556
Contact Email:	powellinc@swbell.net

Ind. Haz Waste:

Waste ID:	80627
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001489H
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solid tank bottoms and drill cuttings (hydrocarbon contaminated). Drilling moni
Standard Industrial Code:	42260
Primary Source:	G14
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	EPA (TX D091698951)
Primary NAICS Code:	493190
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	80626
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvent cleaning parts. 1-93
Standard Industrial Code:	27590
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

POWELL OFFSET SERVICE (Continued) **S104855371**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	323119
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

NA2511 **M. H. CROCKETT** **TX HIST UST** **S111678731**
SSW **319 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.077 mi.
405 ft. **Site 10 of 12 in cluster NA**

Actual:
451 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	M. H. CROCKETT
Address:	319 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0892
HID UST:	892
Inspection:	Not reported
Due:	06/01/2012

2512 **REX CLEANERS DCLO CLNR** **EDR Hist Cleaner** **1013783169**
WNW **200 MARY W** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.077 mi.
405 ft.

Actual:
555 ft.

Focus Map:
14

EDR Hist Cleaner

Year:	Name:	Type:
1940	REX CLEANERS DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

OQ2513 **TEXAS COMPANY** **TX HIST UST** **S128729197**
ESE **213 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.077 mi.
406 ft. **Site 3 of 5 in cluster OQ**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TEXAS COMPANY
Address:	213 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0152
HID UST:	152

TEXAS COMPANY (Continued) **S128729197**

Inspection: 03/31/2009
Due: 03/31/2012

OQ2514 **CATHERINE UMSTATTD** **TX UST** **U003566393**
ESE **213 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.077 mi.
406 ft. **Site 4 of 5 in cluster OQ**

Actual:
487 ft.

Focus Map:
11

UST:

Name:	CATHERINE UMSTATTD
Address:	213 W 5TH ST
City,State,Zip:	AUSTIN, TX 787012910
AI Number:	64107
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	840192622002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	TIM DALTON,MANAGER
Contact Organization Name:	CATHERINE UMSTATTD
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123271340
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/06/1993
Signature Name/Title On Earliest Reg Form:	MATTHEW MAHONEY,PROJECT MANAGER
Application Received Date On Earliest Reg Form:	01/12/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601209174
Owner Last Name:	UMSTATTD
Owner First Name:	CATHERINE
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/

CATHERINE UMSTATTD (Continued) **U003566393**

Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	832192622002139
Additional ID:	840192622002139
AI Number:	64107
Owner Effective Begin Date:	09/01/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	01/12/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147543
Facility ID:	96486
Ai Number:	64107
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

CATHERINE UMSTATTD (Continued) **U003566393**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/23/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	159702
UST ID:	147543
AI Number:	64107
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

CATHERINE UMSTATTD (Continued) **U003566393**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24886
Cert ID:	237897
UST Comprt ID:	683166
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	254962
UST Comprt ID:	733326
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	221638
UST Comprt ID:	635734
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70894
UST Comprt ID:	205395
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70893
UST Comprt ID:	205396
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70892
UST Comprt ID:	205397
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70891
UST Comprt ID:	205398

CATHERINE UMSTATTD (Continued) **U003566393**

UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70890
UST Comprt ID:	205399
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70889
UST Comprt ID:	205400
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70888
UST Comprt ID:	205401
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70887
UST Comprt ID:	205402
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70886
UST Comprt ID:	205403
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70885
UST Comprt ID:	205406
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70884
UST Comprt ID:	205405
UST ID:	75718

CATHERINE UMSTATTD (Continued) **U003566393**

AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70883
UST Comprt ID:	205404
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	372563
UST Comprt ID:	1085557
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	355923
UST Comprt ID:	1035342
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	338986
UST Comprt ID:	984361
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	324319
UST Comprt ID:	939722
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	305154
UST Comprt ID:	882905
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	288430
UST Comprt ID:	832702
UST ID:	75718
AI Number:	64107

CATHERINE UMSTATTD (Continued) **U003566393**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	271393
UST Comprt ID:	782018
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/12/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147544
Facility ID:	96486
Ai Number:	64107
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

CATHERINE UMSTATTD (Continued) **U003566393**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/23/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	159703
UST ID:	147544
AI Number:	64107
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

CATHERINE UMSTATTD (Continued) **U003566393**

Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 24886
Cert ID: 237897
UST Comprt ID: 683166
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 254962
UST Comprt ID: 733326
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 221638
UST Comprt ID: 635734
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 70894
UST Comprt ID: 205395
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 70893
UST Comprt ID: 205396
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 70892
UST Comprt ID: 205397
UST ID: 75718
AI Number: 64107
Tank ID: 1
Compartment ID: A

Self Cert ID: 24886
Cert ID: 70891
UST Comprt ID: 205398
UST ID: 75718
AI Number: 64107

CATHERINE UMSTATTD (Continued) **U003566393**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70890
UST Comprt ID:	205399
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70889
UST Comprt ID:	205400
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70888
UST Comprt ID:	205401
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70887
UST Comprt ID:	205402
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70886
UST Comprt ID:	205403
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70885
UST Comprt ID:	205406
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70884
UST Comprt ID:	205405
UST ID:	75718
AI Number:	64107
Tank ID:	1

CATHERINE UMSTATTD (Continued) **U003566393**

Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70883
UST Comprt ID:	205404
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	372563
UST Comprt ID:	1085557
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	355923
UST Comprt ID:	1035342
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	338986
UST Comprt ID:	984361
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	324319
UST Comprt ID:	939722
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	305154
UST Comprt ID:	882905
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	288430
UST Comprt ID:	832702
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

CATHERINE UMSTATTD (Continued) **U003566393**

Self Cert ID:	24886
Cert ID:	271393
UST Comprt ID:	782018
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	01/12/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147545
Facility ID:	96486
Ai Number:	64107
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

CATHERINE UMSTATTD (Continued) **U003566393**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/23/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	159704
UST ID:	147545
AI Number:	64107
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

CATHERINE UMSTATTD (Continued) **U003566393**

More Self Certification:

Self Cert ID:	24886
Cert ID:	237897
UST Comprt ID:	683166
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	254962
UST Comprt ID:	733326
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	221638
UST Comprt ID:	635734
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70894
UST Comprt ID:	205395
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70893
UST Comprt ID:	205396
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70892
UST Comprt ID:	205397
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70891
UST Comprt ID:	205398
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

CATHERINE UMSTATTD (Continued) **U003566393**

Self Cert ID:	24886
Cert ID:	70890
UST Comprt ID:	205399
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70889
UST Comprt ID:	205400
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70888
UST Comprt ID:	205401
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70887
UST Comprt ID:	205402
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70886
UST Comprt ID:	205403
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70885
UST Comprt ID:	205406
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70884
UST Comprt ID:	205405
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886

CATHERINE UMSTATTD (Continued) **U003566393**

Cert ID:	70883
UST Comprt ID:	205404
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	372563
UST Comprt ID:	1085557
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	355923
UST Comprt ID:	1035342
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	338986
UST Comprt ID:	984361
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	324319
UST Comprt ID:	939722
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	305154
UST Comprt ID:	882905
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	288430
UST Comprt ID:	832702
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	271393

CATHERINE UMSTATTD (Continued) **U003566393**

UST Comprt ID:	782018
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/12/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147546
Facility ID:	96486
Ai Number:	64107
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/22/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

CATHERINE UMSTATTD (Continued) **U003566393**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/23/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	159705
UST ID:	147546
AI Number:	64107
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

CATHERINE UMSTATTD (Continued) **U003566393**

Self Cert ID:	24886
Cert ID:	237897
UST Comprt ID:	683166
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	254962
UST Comprt ID:	733326
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	221638
UST Comprt ID:	635734
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	70894
UST Comprt ID:	205395
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	70893
UST Comprt ID:	205396
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	70892
UST Comprt ID:	205397
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886
Cert ID:	70891
UST Comprt ID:	205398
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Self Cert ID:	24886

CATHERINE UMSTATTD (Continued) **U003566393**

Cert ID:	70890
UST Comprt ID:	205399
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70889
UST Comprt ID:	205400
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70888
UST Comprt ID:	205401
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70887
UST Comprt ID:	205402
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70886
UST Comprt ID:	205403
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70885
UST Comprt ID:	205406
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70884
UST Comprt ID:	205405
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	70883

CATHERINE UMSTATTD (Continued) **U003566393**

UST Comprt ID:	205404
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	372563
UST Comprt ID:	1085557
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	355923
UST Comprt ID:	1035342
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	338986
UST Comprt ID:	984361
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	324319
UST Comprt ID:	939722
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	305154
UST Comprt ID:	882905
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	288430
UST Comprt ID:	832702
UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A
Self Cert ID:	24886
Cert ID:	271393
UST Comprt ID:	782018

CATHERINE UMSTATTD (Continued) **U003566393**

UST ID:	75718
AI Number:	64107
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	UMSTATTD CATHERINE
Contact Mailing Address (Delivery):	4903 BULL MOUNTAIN CV
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 2402
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96486
Additional ID:	840192622002139
Princ ID:	832192622002139
AI Number:	64107
Facility Name:	CATHERINE UMSTATTD
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	WM R SMITH/

OQ2515 **VACANT COMMERCIAL BLDG** **TX HIST UST** **S128729016**
ESE **213 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.077 mi.
406 ft. **Site 5 of 5 in cluster OQ**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	VACANT COMMERCIAL BLDG
Address:	213 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0383
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2516 **KNIGHT WM Y** **EDR Hist Auto** **1013772957**
ESE **207 MILTON E** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.077 mi.
406 ft.

Actual:
563 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1940	KNIGHT WM Y	REPAIR SHOPS

2517 WNW < 1/8 0.077 mi. 406 ft. | **J RS AUTO REPR**
406 38 1/2 W
AUSTIN, TX | **EDR Hist Auto** | **1013760438**
N/A

Actual: 609 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1958	J RS AUTO REPR	AUTOMOBILE REPAIRING

OS2518 ESE < 1/8 0.077 mi. 408 ft. | **5901 S CONGRESS**
6001 S CONGRESS AVE
AUSTIN, TX 78745 | **TX SWF/LF** | **S121200122**
N/A

Site 1 of 4 in cluster OS

Actual: 646 ft. SWF/LF:

Focus Map: 17

Name:	5901 S CONGRESS
Address:	6001 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745-2014
Region:	11
Permit Number:	67009
Facility Status:	NOT CONSTRUCTED
Facility Type:	SUBT
Permit Status:	ISSUED
Status Date:	10/13/2017
Mailing Address:	Not reported
Client Name:	Not reported
Client Address:	Not reported
Client Telephone:	N/A
Business Type:	Not reported
Area Served:	Not reported
Estimated Closure Date:	Not reported
Permit Acreage:	Not reported
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	30.20161 / -97.77447

OI2519 WNW < 1/8 0.078 mi. 410 ft. | **AUSTIN FOREIGN CAR CENTER**
510 6TH ST W
AUSTIN, TX 78701 | **EDR Hist Auto** | **1013756145**
N/A

Site 6 of 15 in cluster OI

Actual: 482 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1984	AUSTIN FOREIGN CAR CENTER	AUTOMOBILE REPAIRING

OI2520 WNW < 1/8 0.078 mi. 410 ft. — **EUROPEAN SPECIALIZED AUTOMOTIVE**, **510 6TH ST W**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013754207** / **N/A**

Site 7 of 15 in cluster OI

Actual: 482 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1990	EUROPEAN SPECIALIZED AUTOMOTIVE	AUTOMOBILE REPAIRING

OI2521 WNW < 1/8 0.078 mi. 410 ft. — **510 12 AUSTIN AUTOMATIC**, **510 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013765011** / **N/A**

Site 8 of 15 in cluster OI

Actual: 482 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	510 12 AUSTIN AUTOMATIC	AUTOMOBILE REPAIRING

LR2522 ESE < 1/8 0.078 mi. 410 ft. — **CERTIFIED BRAKES**, **6507 SHIRLEY AVE**, **AUSTIN, TX 78752** — **TX Ind. Haz Waste**, **TX CENTRAL REGISTRY** — **S102748108** / **N/A**

Site 4 of 5 in cluster LR

Actual: 711 ft. Ind. Haz Waste:

Focus Map: 6

Name:	CERTIFIED BRAKES
Address:	6507 SHIRLEY AVE
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	61168
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	6507 Shirley, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CERTIFIED BRAKES
Contact Name:	JOSEIN ARGHOMI
Contact Telephone Number:	Not reported
Mailing Address:	6507 SHIRLEY AVE

CERTIFIED BRAKES (Continued) **S102748108**

Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787524024
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19529
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CERTIFIED BRAKES
Operator Address:	6507 SHIRLEY AVE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CERTIFIED BRAKES
Owner Mailing Address:	6507 SHIRLEY AVE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6507 SHIRLEY AVE
Contact Address 2:	Not reported

CERTIFIED BRAKES (Continued) **S102748108**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6507 SHIRLEY AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JOSEIN ARGHOMI
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6507 SHIRLEY AVE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100551241
Name:	CERTIFIED BRAKES
Address:	6507 SHIRLEY AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-4024
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600262208
Customer Name:	CERTIFIED BRAKES
Customer Legal Name:	Certified Brakes
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	6507 Shirley, Austin, TX

LR2523 **OVERSEAS MOTORS AUTO MTCE** **EDR Hist Auto** **1013770116**
ESE **6507 SHIRLEY AVE** **N/A**
< 1/8 **TRAVIS (County), TX 78752**
0.078 mi.
410 ft. **Site 5 of 5 in cluster LR**

Actual:
711 ft.

Focus Map:
6

EDR Hist Auto

Year:	Name:	Type:
1988	HOSSEIN-JOE-ARGHAMI	General Automotive Repair Shops
1988	AUTO MASTER	General Automotive Repair Shops
1989	HOSSEIN-JOE-ARGHAMI	General Automotive Repair Shops
1989	AUTO MASTER	General Automotive Repair Shops
1990	OVERSEAS MOTORS AUTO MTCE	AUTOMOBILE REPAIRING
1990	AUTO MASTER	General Automotive Repair Shops
1990	HOSSEIN-JOE-ARGHAMI	General Automotive Repair Shops
1998	NEUSPEED AUTOMOTIVE	General Automotive Repair Shops
1999	NEUSPEED AUTOMOTIVE	General Automotive Repair Shops
2000	NEUSPEED AUTOMOTIVE	General Automotive Repair Shops
2001	NEUSPEED AUTOMOTIVE	General Automotive Repair Shops
2002	NEUSPEED AUTOMOTIVE	General Automotive Repair Shops
2003	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2004	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2005	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2006	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2007	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2008	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2009	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2010	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops
2011	NEWSPEED AUTOMOTIVE	General Automotive Repair Shops

OF2524 **COVERT BUICK** **TX UST** **U003566305**
WNW **500 W 5TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.078 mi.
410 ft. **Site 8 of 8 in cluster OF**

Actual:
482 ft.

Focus Map:
11

UST:

Name:	COVERT BUICK
Address:	500 W 5TH ST
City,State,Zip:	AUSTIN, TX 787013830
AI Number:	34978
Facility Type:	UNKNOWN
Facility Begin Date:	12/10/1986
Facility Status:	INACTIVE
Additional ID:	696619102002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	YVONNE MOODY,C&I REP
Contact Organization Name:	COVERT BUICK
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

COVERT BUICK (Continued) **U003566305**

Contact Telephone:	7137543709
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1986
Signature Name/Title On Earliest Reg Form:	H J ODONNELL,ENG
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600132484
Owner Last Name:	CHEVRON USA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	329482572001157
Additional ID:	696619102002156
AI Number:	34978
Owner Effective Begin Date:	12/10/1986
State Tax ID:	12505279252
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92458
Facility ID:	63751
Ai Number:	34978
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

COVERT BUICK (Continued) **U003566305**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	74506
UST ID:	92458
AI Number:	34978
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

COVERT BUICK (Continued) **U003566305**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	13523
Cert ID:	232577
UST Comprt ID:	667845
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	249130
UST Comprt ID:	716163
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	264998
UST Comprt ID:	763308
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	283282

COVERT BUICK (Continued) **U003566305**

UST Comprt ID: 817289
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 300840
UST Comprt ID: 869911
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 317103
UST Comprt ID: 918239
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 334628
UST Comprt ID: 970556
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 346676
UST Comprt ID: 1007303
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 352395
UST Comprt ID: 1024610
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 367235
UST Comprt ID: 1069274
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126428
UST Comprt ID: 367140

COVERT BUICK (Continued) **U003566305**

UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126429
UST Comprt ID: 367141
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126430
UST Comprt ID: 367142
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126437
UST Comprt ID: 367133
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126431
UST Comprt ID: 367139
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126432
UST Comprt ID: 367138
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126433
UST Comprt ID: 367137
UST ID: 118683
AI Number: 34978
Tank ID: 2
Compartment ID: A

Self Cert ID: 13523
Cert ID: 126434
UST Comprt ID: 367136
UST ID: 118683

COVERT BUICK (Continued) **U003566305**

AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126435
UST Comprt ID:	367135
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126436
UST Comprt ID:	367134
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126438
UST Comprt ID:	367132
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126439
UST Comprt ID:	367131
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A
Self Cert ID:	13523
Cert ID:	126440
UST Comprt ID:	367130
UST ID:	118683
AI Number:	34978
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CHEVRON USA INC
Contact Mailing Address (Delivery):	PO BOX 6004
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN RAMON, CA 94583 0904
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	63751
Additional ID:	696619102002156
Princ ID:	329482572001157

COVERT BUICK (Continued) **U003566305**

AI Number:	34978
Facility Name:	COVERT BUICK
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PERMIT DESK/

HIST UST AUSTIN:

Name:	FAULK & MONROE
Address:	500 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0050
HID UST:	50
Inspection:	02/19/2009
Due:	02/19/2012

OK2525 **AUSTIN FOUNDRY** **EDR Hist Auto** **1013759186**
WSW **200 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.078 mi.
411 ft. **Site 3 of 21 in cluster OK**

Actual:
491 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1916	AUSTIN FOUNDRY	AUTOMOBILE REPAIRERS

OT2526 **SIGMOR SHAMROCK SERVICE STATION 110 GAS ST** **EDR Hist Auto** **1013756749**
WNW **3515 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.078 mi.
411 ft. **Site 1 of 8 in cluster OT**

Actual:
603 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1970	SIGMOR SERVICE INC NO 110 GAS S	GASOLINE STATIONS
1975	SIGMOR SERVICE INC NO 110 GAS S	GASOLINE STATIONS
1980	SIGMOR SHAMROCK SERVICE INC NO	GASOLINE STATIONS
1984	SIGMOR SHAMROCK SERVICE STATION	GASOLINE STATIONS
1990	DIAMOND SHAMROCK SERVICE STATIO	GASOLINE STATIONS
1991	STATION 0110	Gasoline Service Stations
1992	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1993	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1994	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1995	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1996	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1997	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1998	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
1999	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
2000	DIAMOND SHAMROCK REF MKTG CO	Gasoline Service Stations
2001	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2002	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2003	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations

SIGMOR SHAMROCK SERVICE STATION 110 GAS ST (Continued) **1013756749**

2004	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2005	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2006	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2007	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2008	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2009	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2010	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2011	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2012	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2013	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations
2014	DIAMOND SHAMROCK REF & MKTG CO	Gasoline Service Stations

---

OT2527 **SNAX BASKET 3 TX0297** **TX LPST** **U004144058**
WNW **3515 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.078 mi. **TX ASBESTOS**
411 ft. **Site 2 of 8 in cluster OT** **TX Financial Assurance**

Actual:
603 ft.

Focus Map:
8

LPST:

Name:	DIAMOND SHAMROCK CORNER STORE 1
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0045191
LPST Id:	110658
Facility Location:	3515 N LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	03/28/1996
Reported Date:	12/31/3000
Closure Date:	11/03/1999
Priority:	3.2 - IMPACTED GW W/IN 500ft-0.25mi TO SW USED BY HUMANENDGR SPEC
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and the affected groundwater zone may discharge between 500 feet and 0.25 miles of the UST/AST or source area to a surface water body used for human drinking water, contact recreation, or habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/1P/1
Coordinators RPR:	PHG
Responsible Party Name:	Not reported
Responsible Party Contact:	MACK N BRICE
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	972/252-1880
Reported Date:	12/31/3000
Case Start Date:	11/03/1999
Reference Number:	RN102376910
Project Manager:	PHG

UST:

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787051117
AI Number:	45191

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Facility Type:	RETAIL
Facility Begin Date:	01/01/1985
Facility Status:	ACTIVE
Additional ID:	618863602002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/03/2022
Signature Name/Title On Earliest Reg Form:	JEREMY HOLLAND,ENVIRONMENTAL COMPLIANCE MGR
Application Received Date On Earliest Reg Form:	02/07/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	361422452019267
Additional ID:	618863602002149
Ai Number:	45191
Operator CN:	CN605703495
Operator Name:	AANI DIAMOND 004 LLC
Operator Effective Begin Date:	05/21/2019
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605703396

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Owner Last Name:	LEHIGH GAS WHOLESALE SERVICES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	345376412019267
Additional ID:	618863602002149
AI Number:	45191
Owner Effective Begin Date:	05/21/2019
State Tax ID:	32055121712
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	74577
Cert ID:	376549
AI Number:	45191
Self Certification Date:	09/20/2022
Signature Name/Title:	JEREMY HOLLAND ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74577
Cert ID:	359388
AI Number:	45191
Self Certification Date:	09/07/2021
Signature Name/Title:	JEREMY HOLLAND ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	E

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	345621
AI Number:	45191
Self Certification Date:	10/07/2020
Signature Name/Title:	JEREMY HOLLAND ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	328162
AI Number:	45191
Self Certification Date:	10/01/2019
Signature Name/Title:	TAMMY HESSLER ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	328043
AI Number:	45191
Self Certification Date:	07/08/2019
Signature Name/Title:	TAMMY HESSLER ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74577
Cert ID:	311071
AI Number:	45191
Self Certification Date:	10/01/2018
Signature Name/Title:	Annette S Toale WC Enviro Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74577
Cert ID:	292562
AI Number:	45191
Self Certification Date:	08/24/2017
Signature Name/Title:	JENNIFER RESNIK COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74577
Cert ID:	276066
AI Number:	45191
Self Certification Date:	08/22/2016
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	257910
AI Number:	45191
Self Certification Date:	08/25/2015
Signature Name/Title:	JENNIFER RESNIK COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	242646
AI Number:	45191
Self Certification Date:	08/29/2014
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	226265
AI Number:	45191
Self Certification Date:	08/24/2013
Signature Name/Title:	KENT HAMEL COMPIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74577
Cert ID:	104500
AI Number:	45191
Self Certification Date:	08/24/2012
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104499
AI Number:	45191
Self Certification Date:	08/24/2011
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104498
AI Number:	45191
Self Certification Date:	08/24/2010
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104497
AI Number:	45191
Self Certification Date:	08/29/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104496
AI Number:	45191
Self Certification Date:	08/29/2008
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104495
AI Number:	45191
Self Certification Date:	03/11/2008
Signature Name/Title:	TERRY HANKINS O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104494
AI Number:	45191
Self Certification Date:	08/28/2007
Signature Name/Title:	KENT HAMEL COMPLIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104493
AI Number:	45191
Self Certification Date:	08/01/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104492
AI Number:	45191
Self Certification Date:	07/26/2005
Signature Name/Title:	KENT HAMEL O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104491
AI Number:	45191
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104490
AI Number:	45191
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	74577
Cert ID:	104489
AI Number:	45191
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74577
Cert ID:	104488
AI Number:	45191
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118306
Facility ID:	74577
Ai Number:	45191
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	12098
UST Comprt ID:	104291
UST ID:	118306
AI Number:	45191
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

SNAX BASKET 3 TX0297 (Continued) **U004144058**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118307
Facility ID:	74577
Ai Number:	45191
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

SNAX BASKET 3 TX0297 (Continued) **U004144058**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	12098
UST Comprt ID:	104292
UST ID:	118307
AI Number:	45191
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	10/08/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	118308
Facility ID:	74577
Ai Number:	45191
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	12098
UST Comprt ID:	104293
UST ID:	118308
AI Number:	45191
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Construction Notification:

NOC ID:	11021
Facility ID:	74577
AI Number:	45191
Application Received Date:	11/14/2007
Scheduled Construction Date:	12/16/2007
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M71114005
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

Facility Billing Contacts:

Contact Organization Name:	LEHIGH GAS WHOLESALE SERVICES INC
Contact Mailing Address (Delivery):	600 HAMILTON ST STE 500
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ALLENTOWN, PA 18101 2130
Phone Number/Ext:	610 6258086/0
Contact Fax Number/Ext:	/
Contact Email Address:	TAMMY.HESSLER@CIRCLEK.COM
Contact Address Deliverable:	Y
Facility ID:	74577
Additional ID:	618863602002149
Princ ID:	345376412019267
AI Number:	45191
Facility Name:	SNAX BASKET 3 TX0297
AR Number:	81120
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	TAMMY HESSLER/

HIST UST AUSTIN:

Name:	CORNER STORE NO. 110
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	379
HID UST:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	VALERO CORNER STORE
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.3
Mileage:	6.8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Email from Michelle
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	274349
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/17/2022
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	LIBERTY SURPLUS INS CO
Issuer Phone:	0 610 6258000
Policy Number:	IRONTX0902621401
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/17/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	256281
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Financial Assurance Begin Date:	05/17/2021
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	LIBERTY SURPLUS INS CO
Issuer Phone:	0 800 6779163
Policy Number:	IRONTX009026214
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/17/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	240309
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/17/2020
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	LIBERTY SURPLUS INS CO
Issuer Phone:	Not reported
Policy Number:	IRONTX009026213
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/17/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	222023
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/17/2019
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	LIBERTY SURPLUS INS CO
Issuer Phone:	Not reported
Policy Number:	IRONTX 00902621
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/17/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	204810
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	NAVIGATORS INS CO
Issuer Phone:	Not reported
Policy Number:	CH18ESP0BDKNONC
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	185512
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2017
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	168286
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/15/2016
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	148876
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2015
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/09/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	133758
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/2014
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	116007
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2013
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	7928
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2012
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Region:	2
Facility ID:	74577
Finass ID:	57667
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	57897
AI:	45191
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	57898
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/27/2009
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	57899
AI:	45191
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/06/2007
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2000000
Coverage Expiration Date:	09/06/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SNAX BASKET 3 TX0297
Address:	3515 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	74577
Finass ID:	57900
AI:	45191
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	02/07/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901

SNAX BASKET 3 TX0297 (Continued) **U004144058**

Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: No

MZ2528
ESE
< 1/8
0.078 mi.
412 ft.

CITIES SERVICE OIL CO
1601 LAVACA ST
AUSTIN, TX

Site 6 of 6 in cluster MZ

EDR Hist Auto **1013758459**
N/A

Actual:
557 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	CITIES SERVICE OIL CO	GASOLINE AND OIL SERVICE STATIONS
1940	TANNERS CITIES SERVICE STA FILL	GASOLINE AND OIL SERVICE STATIONS
1947	TANNERS CITIES SERV STA FILL ST	GASOLINE AND OIL SERVICE STATIONS
1958	LAVACA CITIES	GASOLINE STATIONS
1962	LAVACA PHILLIPS 66	GASOLINE STATIONS
1965	LAVACA PHILLIPS SIXTY SIX	GASOLINE STATIONS

NI2529
WNW
< 1/8
0.078 mi.
413 ft.

GULF STATION
1900 S 1ST ST
AUSTIN, TX

Site 3 of 6 in cluster NI

TX HIST UST **S128729037**
N/A

Actual:
523 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	GULF STATION
Address:	1900 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0454
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NI2530
WNW
< 1/8
0.078 mi.
413 ft.

BARBARA LOVELESS HARRIS
1900 S 1ST ST
AUSTIN, TX 78704

Site 4 of 6 in cluster NI

TX UST **U003421954**
N/A

Actual:
523 ft.

Focus Map:
14

UST:

Name:	BARBARA LOVELESS HARRIS
Address:	1900 S 1ST ST
City,State,Zip:	AUSTIN, TX 787044254
AI Number:	65060
Facility Type:	RETAIL
Facility Begin Date:	10/11/1993
Facility Status:	INACTIVE
Additional ID:	955750042002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	BARBARA L HARRIS,OWNER
Contact Organization Name:	BARBARA LOVELESS HARRIS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122828880
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/05/1993
Signature Name/Title On Earliest Reg Form:	BARBARA L HARRIS,OWNER
Application Received Date On Earliest Reg Form:	10/07/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600785323
Owner Last Name:	HARRIS BARBARA LOVELESS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	945750032002053
Additional ID:	955750042002053
AI Number:	65060
Owner Effective Begin Date:	10/11/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/07/1993
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149075
Facility ID:	96772

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Ai Number:	65060
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/29/1993

Compartment Records:

Tank ID:	4
Tank Capacity:	500
UST Comprt ID:	162530

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST ID:	149075
AI Number:	65060
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25321
Cert ID:	146556
UST Comprt ID:	422884
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146557
UST Comprt ID:	422883
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Cert ID:	224205
UST Comprt ID:	643147
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	240589
UST Comprt ID:	691086
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	256837
UST Comprt ID:	738794
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	278630
UST Comprt ID:	803272
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	294434
UST Comprt ID:	850218
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	307880
UST Comprt ID:	890699
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	341324
UST Comprt ID:	991102
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	358199

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST Comprt ID:	1041872
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	380038
UST Comprt ID:	1108313
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	324995
UST Comprt ID:	941677
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146545
UST Comprt ID:	422893
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146546
UST Comprt ID:	422894
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146547
UST Comprt ID:	422895
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146548
UST Comprt ID:	422892
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146549
UST Comprt ID:	422891

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146550
UST Comprt ID:	422890
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146551
UST Comprt ID:	422889
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146552
UST Comprt ID:	422888
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146553
UST Comprt ID:	422887
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146554
UST Comprt ID:	422886
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146555
UST Comprt ID:	422885
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	10/07/1993
Number of Compartments:	1

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149076
Facility ID:	96772
Ai Number:	65060
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Tank Tested Flag:	Y
Installation Signature Date:	09/29/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	162531
UST ID:	149076
AI Number:	65060
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25321
Cert ID:	146556
UST Comprt ID:	422884
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146557

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST Comprt ID:	422883
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	224205
UST Comprt ID:	643147
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	240589
UST Comprt ID:	691086
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	256837
UST Comprt ID:	738794
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	278630
UST Comprt ID:	803272
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	294434
UST Comprt ID:	850218
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	307880
UST Comprt ID:	890699
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	341324
UST Comprt ID:	991102

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	358199
UST Comprt ID:	1041872
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	380038
UST Comprt ID:	1108313
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	324995
UST Comprt ID:	941677
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146545
UST Comprt ID:	422893
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146546
UST Comprt ID:	422894
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146547
UST Comprt ID:	422895
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146548
UST Comprt ID:	422892
UST ID:	144003

BARBARA LOVELESS HARRIS (Continued) **U003421954**

AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146549
UST Comprt ID:	422891
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146550
UST Comprt ID:	422890
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146551
UST Comprt ID:	422889
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146552
UST Comprt ID:	422888
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146553
UST Comprt ID:	422887
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146554
UST Comprt ID:	422886
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146555
UST Comprt ID:	422885
UST ID:	144003
AI Number:	65060

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Tank ID:	2
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	10/07/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149077
Facility ID:	96772
Ai Number:	65060
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

BARBARA LOVELESS HARRIS (Continued) **U003421954**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/29/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	162532
UST ID:	149077
AI Number:	65060
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25321
Cert ID:	146556
UST Comprt ID:	422884

BARBARA LOVELESS HARRIS (Continued) **U003421954**

UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146557
UST Comprt ID:	422883
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	224205
UST Comprt ID:	643147
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	240589
UST Comprt ID:	691086
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	256837
UST Comprt ID:	738794
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	278630
UST Comprt ID:	803272
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	294434
UST Comprt ID:	850218
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	307880
UST Comprt ID:	890699
UST ID:	144003

BARBARA LOVELESS HARRIS (Continued) **U003421954**

AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	341324
UST Comprt ID:	991102
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	358199
UST Comprt ID:	1041872
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	380038
UST Comprt ID:	1108313
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	324995
UST Comprt ID:	941677
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146545
UST Comprt ID:	422893
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146546
UST Comprt ID:	422894
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146547
UST Comprt ID:	422895
UST ID:	144003
AI Number:	65060

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146548
UST Comprt ID:	422892
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146549
UST Comprt ID:	422891
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146550
UST Comprt ID:	422890
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146551
UST Comprt ID:	422889
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146552
UST Comprt ID:	422888
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146553
UST Comprt ID:	422887
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146554
UST Comprt ID:	422886
UST ID:	144003
AI Number:	65060
Tank ID:	2

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146555
UST Comprt ID:	422885
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	10/07/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149078
Facility ID:	96772
Ai Number:	65060
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/15/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/29/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	162533
UST ID:	149078
AI Number:	65060
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID:	25321
Cert ID:	146556
UST Comprt ID:	422884
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146557
UST Comprt ID:	422883
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	224205
UST Comprt ID:	643147
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	240589
UST Comprt ID:	691086
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	256837
UST Comprt ID:	738794
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	278630
UST Comprt ID:	803272
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	294434
UST Comprt ID:	850218
UST ID:	144003
AI Number:	65060
Tank ID:	2

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Compartment ID:	A
Self Cert ID:	25321
Cert ID:	307880
UST Comprt ID:	890699
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	341324
UST Comprt ID:	991102
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	358199
UST Comprt ID:	1041872
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	380038
UST Comprt ID:	1108313
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	324995
UST Comprt ID:	941677
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146545
UST Comprt ID:	422893
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146546
UST Comprt ID:	422894
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Self Cert ID:	25321
Cert ID:	146547
UST Comprt ID:	422895
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146548
UST Comprt ID:	422892
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146549
UST Comprt ID:	422891
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146550
UST Comprt ID:	422890
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146551
UST Comprt ID:	422889
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146552
UST Comprt ID:	422888
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146553
UST Comprt ID:	422887
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321

BARBARA LOVELESS HARRIS (Continued) **U003421954**

Cert ID:	146554
UST Comprt ID:	422886
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25321
Cert ID:	146555
UST Comprt ID:	422885
UST ID:	144003
AI Number:	65060
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	HARRIS BARBARA LOVELESS
Contact Mailing Address (Delivery):	10929 CROWN COLONY DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78747 1635
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96772
Additional ID:	955750042002053
Princ ID:	945750032002053
AI Number:	65060
Facility Name:	BARBARA LOVELESS HARRIS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BARBARA L HARRIS/

NI2531 **JOHN B. LOVELESS** **TX HIST UST** **S128729270**
WNW **1900 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX**
0.078 mi.
413 ft. **Site 5 of 6 in cluster NI**

Actual:
523 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	JOHN B. LOVELESS
Address:	1900 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0408
HID UST:	408
Inspection:	01/21/2009
Due:	01/21/2012

NI2532 WNW < 1/8 0.078 mi. 413 ft. | **JOHN LOVELESS**
1900 S 1ST ST
AUSTIN, TX | **TX HIST UST** | **S128729487**
N/A

Site 6 of 6 in cluster NI

Actual: 523 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	JOHN LOVELESS
Address:	1900 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0974
HID UST:	974
Inspection:	Not reported
Due:	06/01/2012

2533 WNW < 1/8 0.078 mi. 413 ft. | **A PAYLESS AUTOMOTIVE REPR & SERV AUTO REPRS**
11116 LAMAR BLVD N
TRAVIS (County), TX 78753 | **EDR Hist Auto** | **1013774148**
N/A

Actual: 758 ft.
Focus Map: 3

EDR Hist Auto

Year:	Name:	Type:
1990	A PAYLESS AUTOMOTIVE REPR & SER	AUTOMOBILE REPAIRING
1992	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1993	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1994	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1996	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1997	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1998	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
1999	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
2000	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
2001	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
2002	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC
2003	PAYLESS AUTOMOTIVE	Automotive Repair Shops, NEC

NS2534 West < 1/8 0.078 mi. 413 ft. | **KELLY SMITH CLEANERS INC**
509-511 W 19TH
AUSTIN, TX 78701 | **EDR Hist Cleaner** | **1020018415**
N/A

Site 3 of 4 in cluster NS

Actual: 552 ft.
Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1971	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1972	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1973	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1974	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1975	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1976	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs

2535
SW
< 1/8
0.078 mi.
414 ft.

MORELL ARTH D
500 ACADEMY DR
AUSTIN, TX

EDR Hist Auto **1013767022**
N/A

Actual:
497 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1940	MORELL ARTH D	AUTOMOBILE REPAIRING

2536
WNW
< 1/8
0.079 mi.
415 ft.

MR SERVICE CENTERS
10200 N LAMAR BLVD
AUSTIN, TX 78753

EDR Hist Auto **1021924603**
N/A

Actual:
711 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
2006	MR SERVICE CENTERS	Gasoline Service Stations
2007	MR SERVICE CENTERS	Gasoline Service Stations
2007	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2008	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2008	MR SERVICE CENTERS	Gasoline Service Stations
2009	MR SERVICE CENTERS	Gasoline Service Stations
2009	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2010	5STAR AUTO	General Automotive Repair Shops
2010	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2010	MR SERVICE CENTERS	Gasoline Service Stations
2011	MR SERVICE CENTERS	Gasoline Service Stations
2011	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2012	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2012	MR SERVICE CENTERS	Gasoline Service Stations
2013	BRINK MOTORSPORTS	General Automotive Repair Shops
2013	MR SERVICE CENTERS	Gasoline Service Stations
2013	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2014	MR SERVICE CENTERS	Gasoline Service Stations
2014	SIDEWAYS AUTO SOUND INC	General Automotive Repair Shops
2014	BRINK MOTORSPORTS	General Automotive Repair Shops

OU2537
NW
< 1/8
0.079 mi.
415 ft.

PIERPOINT MOTORS
8140 LAMAR BLVD N
AUSTIN, TX 78763

Site 1 of 7 in cluster OU

EDR Hist Auto **1013764241**
N/A

Actual:
738 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1984	PIERPOINT MOTORS	AUTOMOBILE REPAIRING
1990	IMPORTANT MOTORS	AUTOMOBILE REPAIRING
1994	J RS AUTOMOTIVE	General Automotive Repair Shops
1995	J RS AUTOMOTIVE	General Automotive Repair Shops
1996	J RS AUTOMOTIVE	General Automotive Repair Shops
1997	J RS AUTOMOTIVE	General Automotive Repair Shops
1998	J RS AUTOMOTIVE	General Automotive Repair Shops
1999	J RS AUTOMOTIVE	General Automotive Repair Shops

PIERPOINT MOTORS (Continued) **1013764241**

2000	J RS AUTOMOTIVE	General Automotive Repair Shops
2001	J RS AUTOMOTIVE	General Automotive Repair Shops
2002	J RS AUTOMOTIVE	General Automotive Repair Shops
2003	J RS AUTOMOTIVE	General Automotive Repair Shops
2004	J RS AUTOMOTIVE	General Automotive Repair Shops
2005	J RS AUTOMOTIVE	General Automotive Repair Shops
2006	J RS AUTOMOTIVE	General Automotive Repair Shops
2007	J RS AUTOMOTIVE	General Automotive Repair Shops
2008	J RS AUTOMOTIVE	General Automotive Repair Shops

OV2538 **OLD FIRESTONE** **TX HIST UST** **S128729101**
ESE **901 LAVACA ST** **N/A**
< 1/8 **AUSTIN, TX**
0.079 mi.
415 ft. **Site 1 of 2 in cluster OV**

Actual:
542 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	OLD FIRESTONE
Address:	901 LAVACA ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0649
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OW2539 **CAPITOL SERVICE STATION FILLING STA** **EDR Hist Auto** **1013774208**
ESE **1301 LAVACA** **N/A**
< 1/8 **AUSTIN, TX**
0.079 mi.
416 ft. **Site 1 of 2 in cluster OW**

Actual:
540 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	ABRAHAM S A FILL	GASOLINE AND OIL SERVICE STATIONS
1940	CAPITOL SERVICE STATION FILLING	GASOLINE AND OIL SERVICE STATIONS
1953	SCHLIEFFERS ROGER	GASOLINE STATIONS
1953	SCHLIEFFERS ROGER	AUTOMOBILE REPAIRING
1958	SCHIEFFERS ROGER	AUTOMOBILE REPAIRING
1962	SCHIEFFERS ROGER	AUTOMOBILE REPAIRING
1965	SCHIEFFERS ROGER SERVICE	AUTOMOBILE REPAIRING
1969	SCHIEFFER ROGER A	Gasoline Service Stations
1970	SCHIEFFEI S ROGER SERVICE AUTO	AUTOMOBILE REPAIRING

NZ2540 **EMPIRE AUTOMOTIVE SERVICE AUTO REPR** **EDR Hist Auto** **1013754141**
NE **604 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.080 mi.
420 ft. **Site 3 of 4 in cluster NZ**

Actual:
473 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1969	LOPEZ FRANK S	General Automotive Repair Shops
1970	EMPIRE AUTOMOTIVE SERVICE AUTO	AUTOMOBILE REPAIRING
1970	LOPEZ FRANK S	General Automotive Repair Shops
1971	LOPES FRANK S	General Automotive Repair Shops
1972	LOPES FRANK S	General Automotive Repair Shops
1973	LOPES FRANK S	General Automotive Repair Shops
1974	LOPES FRANK S	General Automotive Repair Shops
1975	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1975	LOPES FRANK S	General Automotive Repair Shops
1976	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1977	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1978	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1979	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1980	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1982	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1983	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1985	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1986	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1987	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1988	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1989	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1990	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1991	EMPIRE AUTOMOTIVE	General Automotive Repair Shops
1992	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1993	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1994	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1995	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1996	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1997	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1998	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
1999	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2000	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2001	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2002	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2003	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2004	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2005	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2006	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2007	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops
2008	EMPIRE AUTOMOTIVE SERVICE	General Automotive Repair Shops

NY2541 **TX HIST UST** **S128729209**
NE **705 RED RIVER** **N/A**
< 1/8 **AUSTIN, TX**
0.080 mi.
421 ft. **Site 2 of 5 in cluster NY**

Actual:
482 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	705 RED RIVER
City,State,Zip:	AUSTIN, TX
Id UST:	H0187
HID UST:	Not reported
Inspection:	02/23/1928
Due:	Not reported

OK2542 **FISHER FRANK C AUTO RE** **EDR Hist Auto** **1013775405**
WSW **205 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.080 mi.
421 ft. **Site 4 of 21 in cluster OK**

Actual:
491 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1911	FISHER FRANK C AUTO RE	AUTOMOBILE GARAGES
1916	NOWLIN R ASA GENI REPR	REPAIR SHOPS
1929	STEINERS GARAGE	AUTOMOBILE GARAGES
1935	STEINERS GARAGE	AUTOMOBILE GARAGES

OK2543 **STEINERS SERVICE** **EDR Hist Auto** **1013770570**
WSW **205 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.080 mi.
421 ft. **Site 5 of 21 in cluster OK**

Actual:
491 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	STEINERS SERVICE	AUTOMOBILE REPAIRING
1947	STEINERS SERVICE GARAGE AUTO RE	AUTOMOBILE REPAIRING

2544 **AUBRY HILLS** **TX IHW CORR ACTION** **S129190264**
WNW **8926 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.080 mi.
422 ft.

Actual:
668 ft.

Focus Map:
6

IHW CORR ACTION:

Name:	AUBRY HILLS
Address:	8926 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Program Id:	T3789
Location Desc:	Not reported
RN NUM:	RN111679080
Status:	ACTIVE
Status Date:	02/08/2023

AUBRY HILLS (Continued) **S129190264**

EDR Link ID:	T3789
Project Phase:	ONGOING WORKLOAD
Phase Status Date:	02/08/2023
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

2545 South < 1/8 0.080 mi. 422 ft. **PALM HARBOR HOMES, INC. - AUSTIN**
830 BASTROP HIGHWAY
AUSTIN, TX 78741
TX Ind. Haz Waste **S112001855**
TX TIER 2 **N/A**

Actual: 479 ft.

Focus Map: 15

Ind. Haz Waste:

Name:	PALM HARBOR HOMES
Address:	830 BASTROP HWY S
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	81766
Registration Initial Notification Date:	03/28/1994
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19940328
Land Type:	Not reported
Description of Facility Site Location:	830 Bastrop Hwy, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	PALM HARBOR HOMES
Contact Name:	JAMES R FLEACE
Contact Telephone Number:	512-3851110
Mailing Address:	830 BASTROP HWY S
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787413646
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	36838
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Owner Name:	PALM HARBOR HOMES
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Container storage area for compator, open top roll offs, bailer, drums of steel
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940328
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	JAMES FLEACE
Contact Title:	MATERIALS
Contact Role:	PRICONT

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Contact Address:	830 BASTROP HWY S
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3851110
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	77505
Texas Waste Code:	Not reported
Texas Waste Code 2:	00019012
Waste Code Status:	INACTIVE
Waste Form:	901
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production refuse.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77506
Texas Waste Code:	Not reported
Texas Waste Code 2:	00029022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Supplemental Plant Production Refuse
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77507

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00039032
Waste Code Status:	INACTIVE
Waste Form:	903
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant office refuse
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77512
Texas Waste Code:	Not reported
Texas Waste Code 2:	00043902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Gypsum and wood scrap
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77511
Texas Waste Code:	Not reported
Texas Waste Code 2:	00053072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Steel Scrap, steel bands, sold to recycler.
Standard Industrial Code:	Not reported
Primary Source:	Not reported

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77510
Texas Waste Code:	Not reported
Texas Waste Code 2:	00064062
Waste Code Status:	INACTIVE
Waste Form:	406
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Cardboard barrels and cardboard boxes sold to recycler.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	77509
Texas Waste Code:	Not reported
Texas Waste Code 2:	00073192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Recycled Paper
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Ind. Haz Waste:

Waste ID:	143680
Texas Waste Code:	Not reported
Texas Waste Code 2:	00089992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant trash
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

TIER 2:

Facility Id:	FATR20128EAWYS00299F
Facility Name:	PALM HARBOR HOMES, INC. - AUSTIN
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/22/2013
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Keith Alexander, General Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Additional Mail Addr:	Not reported

Facility Id:	FATR20118EAWYS00299F
Facility Name:	PALM HARBOR HOMES, INC. - AUSTIN
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	02/24/2012
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Keith Alexander, General Manager
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	2451
Id Type:	SIC
Description:	MOBILE HOMES
Last Modified:	2/15/2012
Id:	321991
Id Type:	NAICS
Description:	Manufactured Home (Mobile Home) Manufacturing
Last Modified:	2/16/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	1001 N. Central Avenue, Suite 800
Contact City/State/Zip:	Phoenix, AZ 85004
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Palm Harbor Homes, Inc.
Title:	Not reported
Modification Date:	3/8/2013

Contact Email:	Not reported
Contact Mail Address:	1001 N. Central Avenue, Suite 800
Contact City/State/Zip:	Phoenix, AZ 85004
Contact Mail Country:	USA

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Contact Type 1:	Owner / Operator
Contact Name:	Palm Harbor Homes, Inc.
Title:	Not reported
Modification Date:	3/8/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	830 Bastrop Highway
Contact City/State/Zip:	Austin, TX 78741
Contact Mail Country:	USA
Contact Type 1:	Submitter
Contact Name:	Keith Alexander
Title:	General Manager
Modification Date:	2/16/2012

Contact:

Contact Email:	Not reported
Contact Mail Address:	830 Bastrop Highway
Contact City/State/Zip:	Austin, TX 78741
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Regulatory Point of Contact
Contact Name:	Bill Birch
Title:	Production Manager
Modification Date:	3/8/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	830 Bastrop Highway
Contact City/State/Zip:	Austin, TX 78741
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	John Abel
Title:	Assistant General Manager
Modification Date:	3/8/2013

Chemical Inventory:

Facility Id:	FATR20128EAWYS00299F
Chemical Name:	Ultra-Hide Speedcote Satin House Paint-Intermediate Tint Base (2452-X301V)
Chemical Inv Record Id:	CVTR20128EAYRF008R52
CAS Number:	Not reported
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	47
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	3/8/2013
Days On Site:	365
Fire Hazard:	Not reported

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20128EAYVC0094GA
Chemical Inventory Record Id:	CVTR20128EAYRF008R52
Amt Of Sub Stored Or Transported:	23725
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside plant
Last Modified:	3/8/2013

Facility Id:	FATR20128EAWYS00299F
Chemical Name:	Speedhide Exterior Satin White (6-2045XI)
Chemical Inv Record Id:	CVTR20128EAYWR00ABE0
CAS Number:	Not reported
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/8/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20128EAZ0000B5GS
Chemical Inventory Record Id:	CVTR20128EAYWR00ABE0
Amt Of Sub Stored Or Transported:	15262
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Plant exterior department
Last Modified: 3/8/2013

Facility Id: FATR20128EAWYS00299F
Chemical Name: DORUS FP 7919 formerly XB-7919
Chemical Inv Record Id: CVTR20128EAZ2700C263
CAS Number: Not reported
Chemical Same As Last Year: Not reported
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: Not reported
Chronic Health Risks: T
EHS Substance: T
Last Modified: 3/8/2013
Days On Site: 365
Fire Hazard: Not reported
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2012
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20128EAZ5A00DR69
Chemical Inventory Record Id: CVTR20128EAZ2700C263
Amt Of Sub Stored Or Transported: 10091
Amount Units: pounds
Type Of Storage: Tote bin
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Plant
Last Modified: 3/8/2013

Mixture:
Record Key: CMTR20128EAZ5S00E4SP
Chemical Inv Record Id: CVTR20128EAZ2700C263
Mix Chemical: hydrogen sulfide
Percentage: 1
Facility Id: FATR20128EAWYS00299F
Mixture Cas: 7783-06-4
Weight/Volume: Wt
Mixture Ehs: T
Mixture Last Modified: 3/8/2013

Facility Id: FATR20128EAWYS00299F
Chemical Name: Ready-Mix Texture MH
Chemical Inv Record Id: CVTR20128EAZ8800F90K
CAS Number: Not reported

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/8/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20128EAZAY00GLN0
Chemical Inventory Record Id:	CVTR20128EAZ8800F90K
Amt Of Sub Stored Or Transported:	14960
Amount Units:	pounds
Type Of Storage:	Tote bin
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Plant
Last Modified:	3/8/2013

Mixture:

Record Key:	CMTR20128EAZBG00H2T1
Chemical Inv Record Id:	CVTR20128EAZ8800F90K
Mix Chemical:	vinyl acetate monomer
Percentage:	0.02
Facility Id:	FATR20128EAWYS00299F
Mixture Cas:	108-05-4
Weight/Volume:	Wt
Mixture Ehs:	T
Mixture Last Modified:	3/8/2013

Notes: Not reported
Validation: Not reported

Facility Info:

Id:	2451
Id Type:	SIC
Description:	MOBILE HOMES
Last Modified:	2/15/2012
Id:	321991
Id Type:	NAICS
Description:	Manufactured Home (Mobile Home) Manufacturing

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Last Modified: 2/16/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 1001 N. Central Avenue, Suite 800
Contact City/State/Zip: Phoenix, AZ 85004
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: Palm Harbor Homes, Inc.
Title: Not reported
Modification Date: 2/29/2012

Contact Email: Not reported
Contact Mail Address: 1001 N. Central Avenue, Suite 800
Contact City/State/Zip: Phoenix, AZ 85004
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: Palm Harbor Homes, Inc.
Title: Not reported
Modification Date: 2/29/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 830 Bastrop Highway
Contact City/State/Zip: Austin, TX 78741
Contact Mail Country: USA
Contact Type 1: Submitter
Contact Name: Keith Alexander
Title: General Manager
Modification Date: 2/16/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 830 Bastrop Highway
Contact City/State/Zip: Austin, TX 78741
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Regulatory Point of Contact
Contact Name: Bill Birch
Title: Production Manager
Modification Date: 2/29/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 830 Bastrop Highway
Contact City/State/Zip: Austin, TX 78741
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: John Abel
Title: Assistant General Manager
Modification Date: 2/29/2012

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Chemical Inventory:

Facility Id:	FATR20118EAWYS00299F
Chemical Name:	Ultra-Hide Speedcote Satin House Paint-Intermediate Tint Base (2452-X301V)
Chemical Inv Record Id:	CVTR20118EAYRF008R52
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	47
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/29/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAYVC0094GA
Chemical Inventory Record Id:	CVTR20118EAYRF008R52
Amt Of Sub Stored Or Transported:	23725
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Inside plant
Last Modified:	2/29/2012

Facility Id:	FATR20118EAWYS00299F
Chemical Name:	Speedhide Exterior Satin White (6-2045XI)
Chemical Inv Record Id:	CVTR20118EAYWR00ABE0
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	51
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/29/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAZ0000B5GS
Chemical Inventory Record Id:	CVTR20118EAYWR00ABE0
Amt Of Sub Stored Or Transported:	15262
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Plant exterior department
Last Modified:	2/29/2012

Facility Id:	FATR20118EAWYS00299F
Chemical Name:	DORUS FP 7919 formerly XB-7919
Chemical Inv Record Id:	CVTR20118EAZ2700C263
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	2523
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/29/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAZ5A00DR69
Chemical Inventory Record Id:	CVTR20118EAZ2700C263
Amt Of Sub Stored Or Transported:	10091
Amount Units:	pounds
Type Of Storage:	Tote bin
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Plant
Last Modified:	2/29/2012

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Mixture:

Record Key:	CMTR20118EAZ5S00E4SP
Chemical Inv Record Id:	CVTR20118EAZ2700C263
Mix Chemical:	hydrogen sulfide
Percentage:	1
Facility Id:	FATR20118EAWYS00299F
Mixture Cas:	7783-06-4
Weight/Volume:	Wt
Mixture Ehs:	Not reported
Mixture Last Modified:	2/29/2012

Facility Id:	FATR20118EAWYS00299F
Chemical Name:	Ready-Mix Texture MH
Chemical Inv Record Id:	CVTR20118EAZ8800F90K
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	3740
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/29/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EAZAY00GLN0
Chemical Inventory Record Id:	CVTR20118EAZ8800F90K
Amt Of Sub Stored Or Transported:	14960
Amount Units:	pounds
Type Of Storage:	Tote bin
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Plant
Last Modified:	2/29/2012

Mixture:

Record Key:	CMTR20118EAZBG00H2T1
Chemical Inv Record Id:	CVTR20118EAZ8800F90K
Mix Chemical:	vinyl acetate monomer
Percentage:	0.02
Facility Id:	FATR20118EAWYS00299F
Mixture Cas:	108-05-4
Weight/Volume:	Wt

PALM HARBOR HOMES, INC. - AUSTIN (Continued) **S112001855**

Mixture Ehs: Not reported
Mixture Last Modified: 2/29/2012

Notes: Not reported
Validation: Not reported

OE2546 **KOENIG LANE SERVICE CTR** **TX RDR** **S127525909**
WNW **901 W KOENIG LN** **N/A**
< 1/8 **AUSTIN, TX**
0.080 mi.
423 ft. **Site 2 of 4 in cluster OE**

Actual:
708 ft.

Focus Map:
8

RDR:

RDR ID:	1390
Facility ID:	18147
RN:	Not reported
CN:	Not reported
Name:	KOENIG LANE SERVICE CTR
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/4/1999
Due Date:	12/3/1999
Tank Owner:	CITY OF AUSTIN
Contact Person:	MARC CHILDERS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/21/1999
Project Manager:	Valerie Miller
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	APPROVED
Review Coordinator:	VAM
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/21/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

OE2547 **KOENIG LANE SERVICE CENTER** **TX UST** **U001542522**
WNW **901 W KOENIG LN** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78756** **TX Financial Assurance**
0.080 mi.
423 ft. **Site 3 of 4 in cluster OE**

Actual:
708 ft.

Focus Map:
8

UST:

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 787561503
AI Number:	18147
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Facility Status:	ACTIVE
Additional ID:	965388942003098
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78757
Contact Name/Title:	DANIEL CARDENA,BUILDING SUPERVISOR
Contact Organization Name:	KOENIG LANE SERVICE CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129720855
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/04/2021
Signature Name/Title On Earliest Reg Form:	WILLIAM OCONNOR,FLEET PR MGR
Application Received Date On Earliest Reg Form:	05/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	840354562001227
Additional ID:	965388942003098
Ai Number:	18147
Operator CN:	CN600135198
Operator Name:	CITY OF AUSTIN
Operator Effective Begin Date:	09/02/1986
Operator Type:	CI
Operator Role:	OPRCON
Contact Name:	SANDRA CREIGHTON/
Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	505 BARTON SPRINGS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-1216
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78721
Contact Mailing Zip5:	3639
Contact Phone Number/Ext:	1 512 9782649/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	965388942003098
AI Number:	18147
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JIMMY TUBBS/FUEL OPS COORD
Contact Organization Name:	CITY OF AUSTIN

Self Certification:

Self Cert ID:	37551
Cert ID:	370933
AI Number:	18147
Self Certification Date:	05/25/2022
Signature Name/Title:	WILLIAM OCONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37551
Cert ID:	353843
AI Number:	18147
Self Certification Date:	05/04/2021
Signature Name/Title:	WILLIAM OCONNOR FLEET PR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	336485
AI Number:	18147
Self Certification Date:	04/29/2020
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	320617
AI Number:	18147
Self Certification Date:	05/15/2019
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	303812
AI Number:	18147
Self Certification Date:	05/10/2018
Signature Name/Title:	WILLIAM O'CONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	286239
AI Number:	18147
Self Certification Date:	04/18/2017
Signature Name/Title:	WILLIAM OCONNOR FLT PRG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	270483
AI Number:	18147
Self Certification Date:	05/24/2016
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	253947
AI Number:	18147
Self Certification Date:	06/01/2015
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	236394
AI Number:	18147
Self Certification Date:	04/23/2014
Signature Name/Title:	VALERIE SPINELLI GRANTS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37551
Cert ID:	218920
AI Number:	18147
Self Certification Date:	04/18/2013
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N
Self Cert ID:	37551
Cert ID:	379
AI Number:	18147
Self Certification Date:	05/07/2012
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	378
AI Number:	18147
Self Certification Date:	04/08/2011
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SENIOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	377
AI Number:	18147
Self Certification Date:	05/10/2010
Signature Name/Title:	WILL O'CONNOR FLEET PROGRAM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	376
AI Number:	18147
Self Certification Date:	04/06/2009
Signature Name/Title:	STACEY MONROE FUEL OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	375
AI Number:	18147
Self Certification Date:	06/05/2008
Signature Name/Title:	WILL OCONNOR FLT PGM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	374
AI Number:	18147
Self Certification Date:	05/01/2007
Signature Name/Title:	PAUL GROSS FUEL OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	373
AI Number:	18147
Self Certification Date:	05/01/2006
Signature Name/Title:	PAUL GROSS FULE OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	372
AI Number:	18147
Self Certification Date:	05/02/2005
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	371
AI Number:	18147
Self Certification Date:	05/21/2004
Signature Name/Title:	MARC CHILDERS FUEL OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	370
AI Number:	18147
Self Certification Date:	04/29/2003
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	369
AI Number:	18147
Self Certification Date:	04/25/2002
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37551
Cert ID:	368
AI Number:	18147
Self Certification Date:	01/30/2001
Signature Name/Title:	MARC CHILDERS FIELD OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46940
Facility ID:	37551
Ai Number:	18147
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/19/1995
Empty:	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	262
UST ID:	46940
AI Number:	18147
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46941
Facility ID:	37551
Ai Number:	18147
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	263
UST ID:	46941
AI Number:	18147
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	03/22/1999
Tank Registration Date:	08/05/1999
Number of Compartments:	1
Tank Capacity:	9728
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	191663
Facility ID:	37551
Ai Number:	18147
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	03/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/22/1999

Compartment Records:

Tank ID:	2
Tank Capacity:	9728
UST Comprt ID:	266
UST ID:	191663
AI Number:	18147
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/22/1999

Install Date:	03/22/1999
Tank Registration Date:	08/05/1999
Number of Compartments:	1
Tank Capacity:	9728
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	191662
Facility ID:	37551
Ai Number:	18147
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	03/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/22/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	9728
UST Comprt ID:	265
UST ID:	191662
AI Number:	18147
Compartment ID:	A
Substance Stored1:	GASOHOL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/22/1999

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46942
Facility ID:	37551
Ai Number:	18147
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	264
UST ID:	46942
AI Number:	18147
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Stage 1 Installation Date:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	25786
UST ID:	191663
NOC ID:	Not reported
AI Number:	18147
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000964
Company Name:	TECOM UST SYSTEMS
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	25785
UST ID:	191662
NOC ID:	Not reported
AI Number:	18147
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000964
Company Name:	TECOM UST SYSTEMS
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	40943
UST ID:	191663
NOC ID:	Not reported
AI Number:	18147
Type Of Contact:	INSTALLER

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Contractor CRP Number Or Installer ILP Number:	ILP002153
Company Name:	Not reported
Representative Name:	STEVE SMITH
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	40942
UST ID:	191662
NOC ID:	Not reported
AI Number:	18147
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002153
Company Name:	Not reported
Representative Name:	STEVE SMITH
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	4411 MEINARDUS DR STE D
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 1170
Phone Number/Ext:	512 9782649/0
Contact Fax Number/Ext:	512 9121524/0
Contact Email Address:	WILLIAM.OCONNOR@AUSTINTEXAS.GOV
Contact Address Deliverable:	Y
Facility ID:	37551
Additional ID:	965388942003098
Princ ID:	840354562001227
AI Number:	18147
Facility Name:	KOENIG LANE SERVICE CENTER

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

AR Number:	5
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	WILLIAM OCONNOR/

HIST UST AUSTIN:

Name:	COA WWW WEST LIFT STATION #10
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Id UST:	195
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	268741
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/31/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	250072
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/26/2021

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/26/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	231294
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/25/2020
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/25/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	214216
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2019
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/15/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	197128
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/19/2018
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/19/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	179196
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/23/2017
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/23/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	162769
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2016
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	03/28/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	144995
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2015
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	127539
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2013
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	107469
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	283
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Region:	2
Facility ID:	37551
Finass ID:	17415
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	17416
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/04/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	02/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	17417
AI:	18147
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LETTER OF CREDIT

KOENIG LANE SERVICE CENTER (Continued) **U001542522**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2008
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	1 213 4817841
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	06/06/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KOENIG LANE SERVICE CENTER
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	37551
Finass ID:	17418
AI:	18147
Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

OE2548 **AUSTIN WATER WASTEWATER SER BLDG** **TX LPST** **S105943102**
WNW **901 W KOENIG LN** **N/A**
< 1/8 **AUSTIN, TX 78757**
0.080 mi.
423 ft. **Site 4 of 4 in cluster OE**

Actual:
708 ft.

Focus Map:
8

LPST:

Name:	AUSTIN WATER WASTEWATER SER BLDG
Address:	901 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78757
Facility ID:	018147
LPST Id:	115765
Facility Location:	901 W KOENIG
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	10/14/1997
Entered Date:	06/25/2003
Reported Date:	10/14/1997
Closure Date:	06/25/2003
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED

AUSTIN WATER WASTEWATER SER BLDG (Continued) **S105943102**

Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3
Coordinators RPR:	RWS
Responsible Party Name:	Not reported
Responsible Party Contact:	ROBIN SHAVER
Responsible Party Address:	CORRECTIVE ACTION
Responsible Party City,St,Zip:	TX
Responsible Party Telephone:	/-
Reported Date:	10/14/1997
Case Start Date:	06/25/2003
Reference Number:	RN103061800
Project Manager:	RSHAVER

OG2549 **SMITH MOTOR CO AUTO** **EDR Hist Auto** **1013761638**
SSW **119 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.080 mi.
424 ft. **Site 2 of 7 in cluster OG**

Actual:
474 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	SMITH DURANT SERVICE	AUTOMOBILE REPAIRERS
1940	SMITH MOTOR CO AUTO	AUTOMOBILE REPAIRING

OI2550 **MILLER BLUEPRINT** **TX Ind. Haz Waste** **S102751657**
ESE **513 W 6TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.081 mi.
426 ft. **Site 9 of 15 in cluster OI**

Actual:
476 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	MILLER BLUEPRINT
Address:	513 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	68813
Registration Initial Notification Date:	09/19/1986
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981607088
Primary NAICS Code:	Not reported
Status Change Date:	19860919
Land Type:	PRIVATE
Description of Facility Site Location:	513 W 6th Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

MILLER BLUEPRINT (Continued) **S102751657**

Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MILLER IMAGING AND DIGITAL SOLUTIONS INC
Contact Name:	BOB MILLER
Contact Telephone Number:	512-4788793
Mailing Address:	PO BOX 2065
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787682065
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	23740
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031024
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MILLER IMAGING AND DIGITAL SOLUTIONS INC
Operator Address:	PO BOX 2065
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78768
Operator Country:	UNITED STA
Operator Telephone:	1-512-4788793
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17420495057
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MILLER IMAGING AND DIGITAL SOLUTIONS INC
Owner Mailing Address:	PO BOX 2065
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Country:	UNITED STA
Owner Telephone:	1-512-4788793
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17420495057
Owner Bankruptcy Code:	Not reported

MILLER BLUEPRINT (Continued) **S102751657**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2065
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4788793
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2065
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4788793
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BOB MILLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2065
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4788793
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100572320
Name:	MILLER BLUEPRINT
Address:	513 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2805
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600282875
Customer Name:	MILLER IMAGING AND DIGITAL SOLUTIONS INC
Customer Legal Name:	Miller Imaging And Digital Solutions, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	513 W 6th Street, Austin, TX

Regulated Entity Number:	RN100572320
Name:	MILLER BLUEPRINT

MILLER BLUEPRINT (Continued) **S102751657**

Address:	513 W 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2805
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600282875
Customer Name:	MILLER IMAGING AND DIGITAL SOLUTIONS INC
Customer Legal Name:	Miller Imaging And Digital Solutions, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	513 W 6th Street, Austin, TX

OI2551 **MILLER BLUEPRINT COMPANY** **RCRA NonGen / NLR** **1000280895**
ESE **513 W 6TH STREET** **FINDS** **TXD981607088**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.081 mi.
426 ft. **Site 10 of 15 in cluster OI**

Actual:
476 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Miller Blueprint Company
Handler Address:	W 6TH STREET
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981607088
Contact Name:	BOB MILLER
Contact Address:	PO BOX 2065
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Telephone:	512-478-8793
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2065
Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Name:	Miller Blueprint Company
Owner Type:	Private
Operator Name:	Miller Blueprint Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

MILLER BLUEPRINT COMPANY (Continued) **1000280895**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROBERT L MILLER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MILLER BLUEPRINT COMPANY	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported

MILLER BLUEPRINT COMPANY (Continued) **1000280895**

Owner/Operator Address: PO BOX 2065
Owner/Operator City,State,Zip: AUSTIN, TX 78768
Owner/Operator Telephone: 512-478-8793
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MILLER BLUEPRINT COMPANY
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2065
Owner/Operator City,State,Zip: AUSTIN, TX 78768
Owner/Operator Telephone: 512-478-8793
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860922
Handler Name: MILLER BLUEPRINT CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: MILLER BLUEPRINT COMPANY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

MILLER BLUEPRINT COMPANY (Continued) **1000280895**

FINDS:
Registry ID: 110005095066

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000280895
Registry ID:	110005095066
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005095066
Name:	MILLER BLUEPRINT COMPANY
Address:	513 W 6TH STREET
City,State,Zip:	AUSTIN, TX 78701

OK2552 **VIOLET CROWN GARAGE** **EDR Hist Auto** **1013759775**
WSW **207 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.081 mi.
426 ft. **Site 6 of 21 in cluster OK**

Actual:
491 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	CALLAN J P AUTO REPR	AUTOMOBILE REPAIRERS
1929	VIOLET CROWN GARAGE	AUTOMOBILE GARAGES

OK2553 **FREUND ROLAND R** **EDR Hist Auto** **1013766074**
WSW **207 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.081 mi.
426 ft. **Site 7 of 21 in cluster OK**

Actual:
491 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	COOLEY TOP SHOP	AUTOMOBILE REPAIRING
1947	FREUND ROLAND R GARAGE AUTO REP	AUTOMOBILE REPAIRING
1953	FREUND ROLAND R	AUTOMOBILE REPAIRING

MQ2554 ENE < 1/8 0.081 mi. 427 ft. | **BURCH FOOD MART**
4535 E SH 71
AUSTIN, TX
Site 16 of 18 in cluster MQ | **TX HIST UST** | **S128729631**
N/A

Actual: 587 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	BURCH FOOD MART
Address:	4535 E SH 71
City,State,Zip:	AUSTIN, TX
Id UST:	OJ133
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

MY2555 WNW < 1/8 0.081 mi. 428 ft. | **AUSTIN CONVENTION CENTER EXPANSION**
THIRD ST RED RIVER
AUSTIN, TX
Site 3 of 3 in cluster MY | **TX UST** | **U003711470**
N/A

Actual: 464 ft.
Focus Map: 11

UST:

Name:	AUSTIN CONVENTION CENTER EXPANSION
Address:	THIRD ST RED RIVER
City,State,Zip:	AUSTIN, TX
AI Number:	72576
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	768044302002139
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	THIRD ST RED RIVER
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	TOM WOOD,
Contact Organization Name:	AUSTIN CONVENTION CENTER EXPANSION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124044084
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/27/1999
Signature Name/Title On Earliest Reg Form:	CHRISTOPHER J KOPEC,SENIOR PROJECT MGR
Application Received Date On Earliest Reg Form:	10/27/1999
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN

AUSTIN CONVENTION CENTER EXPANSION (Continued) **U003711470**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	768044302002139
AI Number:	72576
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/27/1999
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	192434
Facility ID:	110466
Ai Number:	72576
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/12/1999
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

AUSTIN CONVENTION CENTER EXPANSION (Continued) **U003711470**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	172361
UST ID:	192434
AI Number:	72576
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

AUSTIN CONVENTION CENTER EXPANSION (Continued) **U003711470**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	19712
Facility ID:	110466
AI Number:	72576
Application Received Date:	10/08/1999
Scheduled Construction Date:	10/12/1999
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	991008002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	5

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	20987
UST ID:	Not reported
NOC ID:	19712
AI Number:	72576
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000936
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported

AUSTIN CONVENTION CENTER EXPANSION (Continued) **U003711470**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	110466
Additional ID:	768044302002139
Princ ID:	840354562001227
AI Number:	72576
Facility Name:	AUSTIN CONVENTION CENTER EXPANSION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

MU2556 **417 21 PATTON TRANSFER CO** **EDR Hist Auto** **1013752850**
NNE **417 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.081 mi.
428 ft. **Site 5 of 5 in cluster MU**

Actual:
483 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	417 21 PATTON TRANSFER CO	AUTOMOBILE GARAGES
1929	417 21 PATTON TRANSFER CO	AUTOMOBILE SERVICE STATIONS
1929	417 21 PATTON TRANSFER CO	AUTOMOBILE SERVICE

NT2557 NNE < 1/8 0.081 mi. 428 ft. — **RUDYS PHILLIPS**, **400 CONGRESS AVE**, **SOUTH AUSTIN, TX** — **EDR Hist Auto** — **1013770362** / **N/A**

Site 2 of 3 in cluster NT

Actual: 484 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1962	RUDYS PHILLIPS	GASOLINE STATIONS

MN2558 NNE < 1/8 0.081 mi. 429 ft. — **AUSTIN GOODYEAR CO**, **101 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013753107** / **N/A**

Site 7 of 11 in cluster MN

Actual: 473 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	GOODYEAR SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1940	GOODYEAR SERVICE	GASOLINE AND OIL SERVICE STATIONS
1953	AUSTIN GOODYEAR CO	GASOLINE STATIONS
1958	GOODYEAR SERV STA	GASOLINE STATIONS
1990	CRASH PARTS OF TEXAS AUTO RESTO	AUTOMOBILE REPAIRING

OX2559 ESE < 1/8 0.081 mi. 430 ft. — **E-Z PAWN**, **99 N I 35**, **AUSTIN, TX** — **TX HIST UST** — **S128728908** / **N/A**

Site 1 of 4 in cluster OX

Actual: 467 ft. HIST UST AUSTIN:

Focus Map: 11

Name:	E-Z PAWN
Address:	99 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0118
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OX2560 ESE < 1/8 0.081 mi. 430 ft. — **E-Z PAWN SHOP**, **99 N INTERSTATE 35**, **AUSTIN, TX 78701** — **TX UST** — **U004177825** / **N/A**

Site 2 of 4 in cluster OX

Actual: 467 ft. UST:

Focus Map: 11

Name:	E-Z PAWN SHOP
Address:	99 N INTERSTATE 35
City,State,Zip:	AUSTIN, TX 78701
AI Number:	27903
Facility Type:	UNKNOWN
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	939211052002156

E-Z PAWN SHOP (Continued) **U004177825**

Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	A FERNANDEZ,MGR
Contact Organization Name:	E-Z PAWN SHOP
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124788366
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/02/1986
Signature Name/Title On Earliest Reg Form:	M F SPEARS,VP OPER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601272271
Owner Last Name:	TRANSAMERICA PAWN CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	930211042002156
Additional ID:	939211052002156
AI Number:	27903
Owner Effective Begin Date:	09/01/1987
State Tax ID:	17425401464
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000

E-Z PAWN SHOP (Continued) **U004177825**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	73018
Facility ID:	87055
Ai Number:	27903
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y

E-Z PAWN SHOP (Continued) **U004177825**

Installation Signature Date:	09/27/1990
Compartment Records:	
Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	127750
UST ID:	73018
AI Number:	27903
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	73017
Facility ID:	87055
Ai Number:	27903
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE

E-Z PAWN SHOP (Continued) **U004177825**

Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	127749
UST ID:	73017
AI Number:	27903
Compartment ID:	A

E-Z PAWN SHOP (Continued) **U004177825**

Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRANSAMERICA PAWN CORPORATION
Contact Mailing Address (Delivery):	1901 CAPITAL PKWY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 7679
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87055
Additional ID:	939211052002156
Princ ID:	930211042002156
AI Number:	27903
Facility Name:	E-Z PAWN SHOP
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

2561 WNW < 1/8 0.081 mi. 430 ft. | **ABIA FOOD & FUEL**
2901 SPIRIT OF TEXAS DR STE 200
AUSTIN, TX 78719 | **TX UST** | **U004290124**
TX HIST UST | **N/A**
TX Financial Assurance

Actual: 506 ft.

Focus Map: 20

UST:

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 787192322
AI Number:	88987
Facility Type:	RETAIL
Facility Begin Date:	06/09/2017
Facility Status:	ACTIVE
Additional ID:	242336952017055
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78719
Contact Name/Title:	IRFAN DHUKA,
Contact Organization Name:	ABIA FOOD & FUEL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5125840072
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/29/2022
Signature Name/Title On Earliest Reg Form:	IRFAN DHUKA,OWNER
Application Received Date On Earliest Reg Form:	08/24/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	312515052018194
Additional ID:	242336952017055
Ai Number:	88987
Operator CN:	CN605548155
Operator Name:	ATCS LLC
Operator Effective Begin Date:	06/09/2017
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

ABIA FOOD & FUEL (Continued) **U004290124**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605320373
Owner Last Name:	ABIA RETAIL LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	322337342017055
Additional ID:	242336952017055
AI Number:	88987
Owner Effective Begin Date:	02/23/2017
State Tax ID:	32046521459
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	134101
Cert ID:	374729
AI Number:	88987
Self Certification Date:	07/29/2022
Signature Name/Title:	IRFAN DHUKA OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	134101
Cert ID:	356837
AI Number:	88987
Self Certification Date:	07/21/2021

ABIA FOOD & FUEL (Continued) **U004290124**

Signature Name/Title:	IRFAN DHUKA OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	134101
Cert ID:	340656
AI Number:	88987
Self Certification Date:	07/10/2020
Signature Name/Title:	IRFAN DHUKA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	134101
Cert ID:	324829
AI Number:	88987
Self Certification Date:	08/13/2019
Signature Name/Title:	IRFAN DHUKA OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	134101
Cert ID:	306512
AI Number:	88987
Self Certification Date:	07/09/2018

ABIA FOOD & FUEL (Continued) **U004290124**

Signature Name/Title:	GEORGE FADDOUL MEMBER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	06/09/2017
Tank Registration Date:	07/12/2018
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	223202
Facility ID:	134101
Ai Number:	88987
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/09/2017
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N

ABIA FOOD & FUEL (Continued) **U004290124**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/25/2018

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	193259
UST ID:	223202
AI Number:	88987
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

ABIA FOOD & FUEL (Continued) **U004290124**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/25/2018
Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	193260
UST ID:	223202
AI Number:	88987
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported
Install Date:	06/09/2017
Tank Registration Date:	07/12/2018
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P

ABIA FOOD & FUEL (Continued) **U004290124**

UST ID:	223201
Facility ID:	134101
Ai Number:	88987
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/09/2017
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	06/25/2018

Compartment Records:

Tank ID:	1

ABIA FOOD & FUEL (Continued) **U004290124**

Tank Capacity:	20000
UST Comprt ID:	193258
UST ID:	223201
AI Number:	88987
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	06/25/2018

Construction Notification:

NOC ID:	30972
Facility ID:	134101
AI Number:	88987
Application Received Date:	02/23/2017
Scheduled Construction Date:	03/25/2017
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N

ABIA FOOD & FUEL (Continued) **U004290124**

AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	02/23/2017
Signature Date On Form:	02/22/2017
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ MGR
Signature Role:	Not reported
Owner Name At Time Of Construction:	ABIA RETAIL LLC
Owner CN At Time Of Construction:	CN605320373
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	INSTALLATION OF NEW UST SYSTEM

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	78798
UST ID:	223202
NOC ID:	Not reported
AI Number:	88987
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 2346
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MCALLEN
Mailing State:	TX
Mailing Zip:	78502
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	956
Phone Number:	6869582
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	78796
UST ID:	223201
NOC ID:	Not reported
AI Number:	88987
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 2346
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MCALLEN
Mailing State:	TX
Mailing Zip:	78502
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	956

ABIA FOOD & FUEL (Continued) **U004290124**

Phone Number:	6869582
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	73407
UST ID:	Not reported
NOC ID:	30972
AI Number:	88987
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported
Cont/Cons/Installer ID:	78795
UST ID:	223201
NOC ID:	Not reported
AI Number:	88987
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	PEFFER BRENT ALLYN
Representative Name:	Not reported
Mailing Address (Delivery):	58 HEARTHSHIRE CIR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MAGNOLIA
Mailing State:	TX
Mailing Zip:	77354
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported
Cont/Cons/Installer ID:	78797
UST ID:	223202

ABIA FOOD & FUEL (Continued) **U004290124**

NOC ID:	Not reported
AI Number:	88987
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	PEFFER BRENT ALLYN
Representative Name:	Not reported
Mailing Address (Delivery):	58 HEARTHSHIRE CIR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	MAGNOLIA
Mailing State:	TX
Mailing Zip:	77354
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2781006
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ABIA RETAIL LLC
Contact Mailing Address (Delivery):	400 S CONGRESS AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 1730
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	134101
Additional ID:	242336952017055
Princ ID:	322337342017055
AI Number:	88987
Facility Name:	ABIA FOOD & FUEL
AR Number:	79908
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	IRFAN DHUKA/

HIST UST AUSTIN:

Name:	ABIA RETAIL
Address:	2901 SPIRIT OF TEXAS DR.
City,State,Zip:	AUSTIN, TX
Id UST:	3411
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 78719

ABIA FOOD & FUEL (Continued) **U004290124**

Region:	2
Facility ID:	134101
Finass ID:	272556
AI:	88987
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/02/2022
Date Financial Assurance Form Rec:	08/24/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005005711
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/02/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	134101
Finass ID:	235488
AI:	88987
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/02/2020
Date Financial Assurance Form Rec:	08/24/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP-409201
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/02/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	134101
Finass ID:	253733
AI:	88987
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

ABIA FOOD & FUEL (Continued) **U004290124**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/02/2020
Date Financial Assurance Form Rec:	08/24/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4906600
Policy Number:	STP409201
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/02/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	134101
Finass ID:	218999
AI:	88987
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/02/2018
Date Financial Assurance Form Rec:	08/24/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 973 4306600
Policy Number:	STP 122997
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/02/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA FOOD & FUEL
Address:	2901 SPIRIT OF TEXAS DR STE 200
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	134101
Finass ID:	199831
AI:	88987
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/02/2018
Date Financial Assurance Form Rec:	08/24/2022
Issuer Name:	CRUM & FORSTER SPECIALTY INS
Issuer Phone:	1 512 6277353
Policy Number:	STP122997
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/02/2019

ABIA FOOD & FUEL (Continued) **U004290124**

Ins Premium Pre-Paid For Entire Yr: Yes
Proof of Financial Assurance: Yes

NX2562 **CABANISS-BROWN FURNITURE CO.** **TX HIST UST** **S111678588**
NNE **216 E 4TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.081 mi.
430 ft. **Site 7 of 7 in cluster NX**

Actual:
482 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CABANISS-BROWN FURNITURE CO.
Address:	216 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0859
HID UST:	859
Inspection:	Not reported
Due:	06/01/2012

NS2563 **KELLV SMITH CLEANERS** **EDR Hist Cleaner** **1013778150**
West **511 W 19TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.082 mi.
433 ft. **Site 4 of 4 in cluster NS**

Actual:
552 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1965	KELLY SMITH CLEANERS INC	CLEANERS AND DYERS
1965	KELLY SMITH CLEANERS INC	CLEANERS
1969	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs
1970	KELLV SMITH CLEANERS	CLEANERS AND DYERS
1970	KELLV SMITH CLEANERS	CLEANERS
1970	KELLY SMITH CLEANERS INC	Drycleaning Plants, Except Rugs

---

OK2564 **ROBINSON A A AUTO** **EDR Hist Auto** **1013767484**
WSW **209 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.082 mi.
433 ft. **Site 8 of 21 in cluster OK**

Actual:
491 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1922	ROBINSON A A AUTO	AUTOMOBILE REPAIRERS

OK2565 **LONE STAR SUPPLY CO BRAKES & CLUTCH SERV** **EDR Hist Auto** **1013766964**
WSW **209 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.082 mi.
433 ft. **Site 9 of 21 in cluster OK**

Actual:
491 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	LONE STAR SUPPLY CO BRAKES & CL	AUTOMOBILE REPAIRING

OY2566 **JIFFY LUBE #2925** **TX LPST** **S108451818**
WNW **3401 N LAMAR BLVD** **TX TIER 2** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX CENTRAL REGISTRY**
0.082 mi.
434 ft. **Site 1 of 12 in cluster OY**

Actual:
592 ft.

Focus Map:
8

LPST:

Name:	QUICK LUBE
Address:	3401 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78700
Facility ID:	Not reported
LPST Id:	091708
Facility Location:	3401 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/26/1988
Entered Date:	02/26/1988
Reported Date:	02/26/1988
Closure Date:	03/24/1988
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	RAY JANSS
Responsible Party Address:	8711 BURNET RD
Responsible Party City,St,Zip:	AUSTIN, TX 78758
Responsible Party Telephone:	512/454-6714
Reported Date:	02/26/1988
Case Start Date:	03/24/1988
Reference Number:	RN100625771
Project Manager:	REGION

TIER 2:

Facility Id/Name:	FATR20128C8V1P041FAS/JIFFY LUBE #2925
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/8/2013
Mailing Address:	105 DECKER COURT, STE 900
Mailing City/State/Country:	IRVING, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	50.00

JIFFY LUBE #2925 (Continued) **S108451818**

Number Of Employess On Site:	9
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	GREG LONGSTROM
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20118C8V1P041FAS/JIFFY LUBE #2925
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	01/14/2012
Mailing Address:	105 DECKER COURT, STE 900
Mailing City/State/Country:	IRVING, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	GREG LONGSTROM, CONTROLLER
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20103G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	2/16/2011
Mailing Address:	11235 DAVENPORT ST, STE 100
Mailing City/State/Country:	OMAHA, NE USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True

JIFFY LUBE #2925 (Continued) **S108451818**

State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	BRIAN D CLARK, VP
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20093G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/4/2010
Mailing Address:	11308 DAVENPORT ST
Mailing City/State/Country:	OMAHA, NE USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	BRIAN D CLARK, VP / TREASURER
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20083G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	1/16/2009
Mailing Address:	11308 DAVENPORT ST
Mailing City/State/Country:	OMAHA, NE USA
Dikes/Other Safeguard Meas Emp:	Not reported

JIFFY LUBE #2925 (Continued) **S108451818**

All Chemicals Same As Last Year:	True
State Fees Total:	7.14
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	BRIAN D CLARK, VP - TREASURER
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR20073G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	12/12/2007
Mailing Address:	11308 DAVENPORT ST
Mailing City/State/Country:	OMAHA, NE USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	BRIAN D CLARK, VP AND TREASURER
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR20063G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2/5/2007
Mailing Address:	11308 DAVENPORT ST
Mailing City/State/Country:	OMAHA, NE USA

JIFFY LUBE #2925 (Continued) **S108451818**

Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	BRIAN D CLARK, VP - TREASURER
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20053G2YPN03NXU7/JIFFY LUBE #2925
Reporting Year:	2005
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	2/27/2007
Date Tier 2 Signed:	1/17/2006
Mailing Address:	11308 DAVENPORT ST
Mailing City/State/Country:	OMAHA, NE USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Rozmiarek-Corporate Officer
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	811191
Id Type:	NAICS
Description:	Not reported
Last Modified:	1/14/2012
Id:	834872400
Id Type:	Dun & Bradstreet

JIFFY LUBE #2925 (Continued) **S108451818**

Description: Not reported
Last Modified: 1/14/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 105 DECKER COURT, STE 900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: HEARTLAND AUTO SVCS II INC
Title: Not reported
Modification Date: 2/10/2012

Contact Email: Not reported
Contact Mail Address: 105 DECKER COURT, STE 900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: HEARTLAND AUTO SVCS II INC
Title: Not reported
Modification Date: 2/10/2012

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: JERRY NICHOLS
Title: COMPLIANCE MANAGER
Modification Date: 2/10/2012

Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: JERRY NICHOLS
Title: COMPLIANCE MANAGER
Modification Date: 2/10/2012

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: JERRY BONNET
Title: MARKET MANAGER
Modification Date: 2/10/2012

Chemical Inventory:
Facility Id: FATR20118C8V1P041FAS

JIFFY LUBE #2925 (Continued) **S108451818**

Chemical Name:	MOTOR OIL
Chemical Inv Record Id:	CVTR20118C8V780498KT
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/10/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118C8V8Z04ARF4
Chemical Inventory Record Id:	CVTR20118C8V780498KT
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	pounds
Type Of Storage:	Tank inside building
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	INSIDE RETAIL STORE (GARAGE AREA)
Last Modified:	2/10/2012

Notes: Not reported
Validation: Not reported

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:

Id:	7549
Id Type:	SIC
Description:	AUTO SERV, EXC REP & CARWASHES
Last Modified:	12/31/2004
Id:	811191
Id Type:	NAICS
Description:	Automotive Oil Change and Lubrication Shops
Last Modified:	1/16/2009
Id:	834872400
Id Type:	Dun & Bradstreet

JIFFY LUBE #2925 (Continued) **S108451818**

Description:	Not reported
Last Modified:	12/31/2004

Contact:

Contact Email:	Not reported
Contact Mail Address:	2711 B W ANDERSON LANE
Contact City/State/Zip:	AUSTIN, TX 78757
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	MARK ROWBERRY
Title:	DIVISION DIRECTOR
Modification Date:	2/24/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	11308 DAVENPORT ST
Contact City/State/Zip:	OMAHA, NE 68154
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	HEARTLAND AUTO SVCS II INC
Title:	OWNER
Modification Date:	2/24/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	3201 GILLHAM PLZ
Contact City/State/Zip:	KANSAS CITY, MO 64109
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	JERRY NICHOLS
Title:	SAFETY/EPA
Modification Date:	2/24/2010

Chemical Inventory:

Facility Id:	FATR20093G2YPN03NXU7
Chemical Name:	MOTOR OIL
Chemical Inv Record Id:	CVTR20093G2YPN03UXXW
CAS Number:	Not reported
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/24/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported

JIFFY LUBE #2925 (Continued) **S108451818**

Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2009
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20093G2YPN03VXZ9
Chemical Inventory Record Id: CVTR20093G2YPN03UXXW
Amt Of Sub Stored Or Transported: Not reported
Amount Units: pounds
Type Of Storage: Tank inside building
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: INSIDE RETAIL STORE (GARAGE AREA)
Last Modified: 2/24/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 811191
Id Type: NAICS
Description: Automotive Oil Change and Lubrication Shops
Last Modified: 2/8/2013
Id: 834872400
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 1/14/2012
Id: 7549
Id Type: SIC
Description: AUTO SERV, EXC REP & CARWASHES
Last Modified: 2/8/2013

Contact:
Contact Email: JERRY.NICHOLS@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: JERRY NICHOLS
Title: COMPLIANCE MANAGER
Modification Date: 2/23/2013

Contact Email: JERRY.NICHOLS@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Emergency Contact

JIFFY LUBE #2925 (Continued) **S108451818**

Contact Name: JERRY NICHOLS
Title: COMPLIANCE MANAGER
Modification Date: 2/23/2013

Contact:
Contact Email: COMPLIANCE@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: HEARTLAND AUTOMOTIVE SERVICES II, INC
Title: OWNER
Modification Date: 2/23/2013

Contact Email: COMPLIANCE@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: HEARTLAND AUTOMOTIVE SERVICES II, INC
Title: OWNER
Modification Date: 2/23/2013

Contact:
Contact Email: EARNIE.ROCK@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: EARNIE ROCK
Title: REGIONAL VP
Modification Date: 2/23/2013

Contact Email: EARNIE.ROCK@JIFFYWORLD.COM
Contact Mail Address: 105 DECKER COURT #900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: EARNIE ROCK
Title: REGIONAL VP
Modification Date: 2/23/2013

Chemical Inventory:
Facility Id: FATR20128C8V1P041FAS
Chemical Name: MOTOR OIL
Chemical Inv Record Id: CVTR20128C8V780498KT
CAS Number: Not reported
Chemical Same As Last Year: Not reported
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: Not reported
Chronic Health Risks: Not reported
EHS Substance: Not reported

JIFFY LUBE #2925 (Continued) **S108451818**

Last Modified:	2/23/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20128C8V8Z04ARF4
Chemical Inventory Record Id:	CVTR20128C8V780498KT
Amt Of Sub Stored Or Transported:	Not reported
Amount Units:	pounds
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	INSIDE RETAIL STORE (GARAGE AREA)
Last Modified:	2/23/2013

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

Facility Info:

Id:	834872400
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	12/31/2004
Id:	7549
Id Type:	SIC
Description:	AUTO SERV, EXC REP & CARWASHES
Last Modified:	12/31/2004
Id:	811191
Id Type:	NAICS
Description:	Automotive Oil Change and Lubrication Shops
Last Modified:	1/16/2009

Contact:

Contact Email:	jerry.nichols@jiffyworld.com
Contact Mail Address:	3201 GILLHAM PLZ
Contact City/State/Zip:	KANSAS CITY, MO 64109
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	JERRY NICHOLS
Title:	COMPLIANCE MANAGER

JIFFY LUBE #2925 (Continued) **S108451818**

Modification Date: 3/10/2011

Contact:
Contact Email: Not reported
Contact Mail Address: 105 DECKER COURT, STE 900
Contact City/State/Zip: IRVING, TX 75062
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: HEARTLAND AUTO SVCS II INC
Title: OWNER
Modification Date: 3/10/2011

Contact:
Contact Email: Not reported
Contact Mail Address: 2711 B W ANDERSON LN
Contact City/State/Zip: AUSTIN, TX 78757
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: JERRY BONNET
Title: MARKET MANAGER
Modification Date: 3/10/2011

Chemical Inventory:
Facility Id: FATR20103G2YPN03NXU7
Chemical Name: MOTOR OIL
Chemical Inv Record Id: CVTR20103G2YPN03UXXW
CAS Number: Not reported
Chemical Same As Last Year: Not reported
Acute Health Risks: Not reported
Average Daily Amount: 10,000 - 99,999 pounds
Max Daily Amount: 10,000 - 99,999 pounds
Max Amount In Largest Container: Not reported
Chronic Health Risks: Not reported
EHS Substance: Not reported
Last Modified: 3/10/2011
Days On Site: 365
Fire Hazard: T
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2010
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20103G2YPN03VXZ9
Chemical Inventory Record Id: CVTR20103G2YPN03UXXW
Amt Of Sub Stored Or Transported: Not reported

JIFFY LUBE #2925 (Continued) **S108451818**

Amount Units: pounds
Type Of Storage: Tank inside building
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: INSIDE RETAIL STORE (GARAGE AREA)
Last Modified: 3/10/2011

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

CENTRAL REGISTRY:

Regulated Entity Number: RN100625771
Name: JIFFY LUBE 2925
Address: 3401 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-1115
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN601225915
Customer Name: TEXAS LUBE CENTERS INC
Customer Legal Name: Texas Lube Centers, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811191
Primary NAICS Industry Type Description: Automotive Oil Change and Lubrication Shops
Physical Location Description: 3401 NORTH LAMAR

Regulated Entity Number: RN100625771
Name: JIFFY LUBE 2925
Address: 3401 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-1115
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600246094
Customer Name: JIFFY LUBE INTERNATIONAL INC
Customer Legal Name: Jiffy Lube International, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 811191
Primary NAICS Industry Type Description: Automotive Oil Change and Lubrication Shops
Physical Location Description: 3401 NORTH LAMAR

Regulated Entity Number: RN100625771
Name: JIFFY LUBE 2925
Address: 3401 N LAMAR BLVD
Address 2: Not reported

JIFFY LUBE #2925 (Continued) **S108451818**

City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600245716
Customer Name:	HEARTLAND AUTOMOTIVE SERVICES INC
Customer Legal Name:	Heartland Automotive Services, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/24/2003
Affiliation End Date:	7/20/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601589260
Customer Name:	JIFFY LUBE
Customer Legal Name:	Jiffy Lube
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	6/24/2003
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605397389
Customer Name:	HEARTLAND AUTOMOTIVE SERVICES OF AUSTIN INC
Customer Legal Name:	HEARTLAND AUTOMOTIVE SERVICES OF AUSTIN, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/21/2017
Affiliation End Date:	7/23/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001

JIFFY LUBE #2925 (Continued) **S108451818**

Customer Number:	CN605550730
Customer Name:	TEAM CAR CARE LLC
Customer Legal Name:	Team Car Care, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/29/2018
Affiliation End Date:	8/11/2018
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603812025
Customer Name:	HEARTLAND AUTOMOTIVE SERVICES II INC
Customer Legal Name:	HEARTLAND AUTOMOTIVE SERVICES II, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/24/2017
Affiliation End Date:	5/28/2018
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605558956
Customer Name:	TEAM CAR CARE EAST LLC
Customer Legal Name:	Team Car Care East, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/12/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601225915
Customer Name:	TEXAS LUBE CENTERS INC
Customer Legal Name:	Texas Lube Centers, Inc.

JIFFY LUBE #2925 (Continued) **S108451818**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601225915
Customer Name:	TEXAS LUBE CENTERS INC
Customer Legal Name:	Texas Lube Centers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Regulated Entity Number:	RN100625771
Name:	JIFFY LUBE 2925
Address:	3401 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1115
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601225915
Customer Name:	TEXAS LUBE CENTERS INC
Customer Legal Name:	Texas Lube Centers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811191
Primary NAICS Industry Type Description:	Automotive Oil Change and Lubrication Shops
Physical Location Description:	3401 NORTH LAMAR

Click this hyperlink while viewing on your computer to access
22 additional TX CENTRAL REG: record(s) in the EDR Site Report.

OY2567 **QUICK LUBE** **TX HIST UST** **S128728879**
WNW **3401 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.082 mi.
434 ft. **Site 2 of 12 in cluster OY**

Actual:
592 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	QUICK LUBE
Address:	3401 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0054

QUICK LUBE (Continued) **S128728879**

HID UST: Not reported
Inspection: Not reported
Due: Not reported

OY2568 **QUICK LUBE AUTO LUBRICATION** **EDR Hist Auto** **1013761454**
WNW **3401 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.082 mi.
434 ft. **Site 3 of 12 in cluster OY**

Actual:
592 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1987	AUSTIN STAR MOTORS	New And Used Car Dealers
1988	B & T KOON-TEX INC	General Automotive Repair Shops
1990	QUICK LUBE AUTO LUBRICATION	AUTOMOBILE OIL AND LUBRICATING SERVICE
1990	QUICK LUBE AUTO LUBRICATION	AUTOMOBILE REPAIRING

OY2569 **MAGNOLIA PETROLEUM** **TX HIST UST** **S128729315**
WNW **3401 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.082 mi.
434 ft. **Site 4 of 12 in cluster OY**

Actual:
592 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM
Address:	3401 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0532
HID UST:	532
Inspection:	Not reported
Due:	06/01/2012

MR2570 **ADOLPH KOHN** **TX HIST UST** **S111678547**
ESE **217 W 14TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.082 mi.
434 ft. **Site 11 of 12 in cluster MR**

Actual:
540 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ADOLPH KOHN
Address:	217 W 14TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0108
HID UST:	108
Inspection:	Not reported
Due:	06/01/2012

MR2571 ESE < 1/8 0.082 mi. 434 ft. | **TOM BAKING COMPANY 217 W 14TH ST AUSTIN, TX** | **TX HIST UST** | **S111678834 N/A**

Site 12 of 12 in cluster MR

Actual: 540 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	TOM BAKING COMPANY
Address:	217 W 14TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0180
HID UST:	180
Inspection:	Not reported
Due:	06/01/2012

OZ2572 WNW < 1/8 0.082 mi. 435 ft. | **TRAM STOP 3201 N LAMAR BLVD AUSTIN, TX 78705** | **TX UST TX HIST UST** | **U004318338 N/A**

Site 1 of 6 in cluster OZ

Actual: 578 ft.
Focus Map: 8

UST:

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787052014
AI Number:	36614
Facility Type:	RETAIL
Facility Begin Date:	05/08/1986
Facility Status:	ACTIVE
Additional ID:	453768712002205
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/27/2018
Signature Name/Title On Earliest Reg Form:	GUY OLIVER,AUTH REP
Application Received Date On Earliest Reg Form:	09/10/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	264324162020029
Additional ID:	453768712002205

TRAM STOP (Continued) **U004318338**

Ai Number:	36614
Operator CN:	CN605745975
Operator Name:	GOZIG HOLDINGS LLC
Operator Effective Begin Date:	01/01/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601235310
Owner Last Name:	38 1 2 STREET LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	194656322002148
Additional ID:	453768712002205
AI Number:	36614
Owner Effective Begin Date:	08/08/2012
State Tax ID:	17426811067
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	44057
Cert ID:	380229
AI Number:	36614
Self Certification Date:	12/08/2022
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	363207
AI Number:	36614
Self Certification Date:	12/14/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	349195
AI Number:	36614
Self Certification Date:	02/02/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	333923
AI Number:	36614
Self Certification Date:	01/15/2020
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	313469
AI Number:	36614
Self Certification Date:	01/07/2019
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	298383
AI Number:	36614
Self Certification Date:	01/25/2018
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	280400
AI Number:	36614
Self Certification Date:	01/11/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	263264
AI Number:	36614
Self Certification Date:	01/15/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	245546
AI Number:	36614
Self Certification Date:	12/08/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	228427
AI Number:	36614
Self Certification Date:	12/11/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	44057
Cert ID:	15486
AI Number:	36614
Self Certification Date:	12/17/2012
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15485
AI Number:	36614
Self Certification Date:	12/13/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15484
AI Number:	36614
Self Certification Date:	01/07/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15483
AI Number:	36614
Self Certification Date:	01/26/2010
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15482
AI Number:	36614
Self Certification Date:	12/15/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15481
AI Number:	36614
Self Certification Date:	12/18/2007
Signature Name/Title:	GUY OLIVER AUTHO REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15480
AI Number:	36614
Self Certification Date:	01/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15479
AI Number:	36614
Self Certification Date:	12/02/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15478
AI Number:	36614
Self Certification Date:	12/02/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15477
AI Number:	36614
Self Certification Date:	01/07/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15476
AI Number:	36614
Self Certification Date:	12/23/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15475
AI Number:	36614
Self Certification Date:	01/07/2002
Signature Name/Title:	GUY OLIVER AUTHORIZED REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

TRAM STOP (Continued) **U004318338**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	44057
Cert ID:	15474
AI Number:	36614
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	02/04/1997
Tank Registration Date:	03/12/1997
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	182905
Facility ID:	44057
Ai Number:	36614
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	02/04/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N

TRAM STOP (Continued) **U004318338**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	Y
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	03/05/1997

Compartment Records:

Tank ID:	1
Tank Capacity:	14000
UST Comprt ID:	18039
UST ID:	182905
AI Number:	36614
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

TRAM STOP (Continued) **U004318338**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported
Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	18040
UST ID:	182905
AI Number:	36614
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

TRAM STOP (Continued) **U004318338**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96866
Facility ID:	44057
Ai Number:	36614
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/19/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

TRAM STOP (Continued) **U004318338**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	18037
UST ID:	96866
AI Number:	36614
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TRAM STOP (Continued) **U004318338**

Install Date:	01/01/1950
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	96867
Facility ID:	44057
Ai Number:	36614
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/19/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

TRAM STOP (Continued) **U004318338**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	2000
UST Comprt ID:	18038
UST ID:	96867
AI Number:	36614
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	37972
Facility ID:	44057
AI Number:	36614
Application Received Date:	04/06/2021
Scheduled Construction Date:	04/15/2021
UST Improvement:	Y

TRAM STOP (Continued) **U004318338**

UST Installation:	Y
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	04/06/2021
Signature Date On Form:	04/06/2021
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	PARTNER
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	38 1 2 STREET LC
Owner CN At Time Of Construction:	CN601235310
Owner AR At Time Of Construction:	45881
General Desc Of Prop Construct:	EXCAVATE TO THE TOPS OF (2) TANKS AND LINE THE INSIDE OF THEM WITH TANK TECH. AFTER LINING IS COMPLETED TEST TANKS

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	26271
UST ID:	182905
NOC ID:	Not reported
AI Number:	36614
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000281
Company Name:	MOFFITT MAINTENANCE INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	90338
UST ID:	Not reported
NOC ID:	37972
AI Number:	36614
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C&J PETROLEUM
Representative Name:	Not reported

TRAM STOP (Continued) **U004318338**

Mailing Address (Delivery):	PO BOX 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE
Mailing State:	TX
Mailing Zip:	76503
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7705454
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	888
Fax Number:	5631656
Email Address:	Not reported
Cont/Cons/Installer ID:	41437
UST ID:	182905
NOC ID:	Not reported
AI Number:	36614
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000858
Company Name:	Not reported
Representative Name:	STEPHEN MOFFITT T
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	90339
UST ID:	Not reported
NOC ID:	37972
AI Number:	36614
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	NADEAU CHUCK
Representative Name:	Not reported
Mailing Address (Delivery):	150 PR 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	254

TRAM STOP (Continued) **U004318338**

Phone Number:	7705454
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	888
Fax Number:	5631656
Email Address:	chuck@cjpetro.com

Facility Billing Contacts:

Contact Organization Name:	38 1 2 STREET LC
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	44057
Additional ID:	453768712002205
Princ ID:	194656322002148
AI Number:	36614
Facility Name:	TRAM STOP
AR Number:	45881
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3211
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OZ2573 **TRAM STOP** **TX ASBESTOS** **U003566308**
WNW **3201 N LAMAR BLVD** **TX Financial Assurance** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX RDR**
0.082 mi.
435 ft. **Site 2 of 6 in cluster OZ**

Actual:
578 ft.

Focus Map:
8

ASBESTOS:

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5

TRAM STOP (Continued) **U003566308**

Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TRAM STOP (Continued) **U003566308**

TX Financial Assurance 2:

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	277383
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2022
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 3066963
Policy Number:	04-TOP-000034751
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	260667
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000024781
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	243821
AI:	36614
Mechanism Type Other:	Not reported

TRAM STOP (Continued) **U003566308**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	228851
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	205940
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/28/2018
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO

TRAM STOP (Continued) **U003566308**

Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/28/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	189665
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	173695
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD

TRAM STOP (Continued) **U003566308**

City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	188379
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	155445
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	153778
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

TRAM STOP (Continued) **U003566308**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	136181
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	117900
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000

TRAM STOP (Continued) **U003566308**

Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	1095
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24529
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057

TRAM STOP (Continued) **U003566308**

Finass ID:	24530
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24531
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24532
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

TRAM STOP (Continued) **U003566308**

Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24533
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24534
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

TRAM STOP (Continued) **U003566308**

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24535
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 817 2329000
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24536
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 817 2329000
Policy Number:	04TO66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	44057
Finass ID:	24537
AI:	36614
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

TRAM STOP (Continued) **U003566308**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	09/10/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	27946
Facility ID:	36614
RN:	Not reported
CN:	Not reported
Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/16/2019
Due Date:	2/14/2020
Tank Owner:	38 1/2 STREET LC
Contact Person:	GUY OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/4/2020
Project Manager:	Jake Halfhill
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	22045
Facility ID:	36614
RN:	Not reported
CN:	Not reported
Name:	TRAM STOP
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/27/2014
Due Date:	7/26/2014
Tank Owner:	38 1/2 STREET
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check

TRAM STOP (Continued) **U003566308**

Date of Latest TCEQ Letter:	7/15/2014
Project Manager:	Victoria Modak
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

OZ2574 **THOMSON PREMIER SERV ST** **EDR Hist Auto** **1013755567**
WNW **3201 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.082 mi.
435 ft. **Site 3 of 6 in cluster OZ**

Actual:
578 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1970	THOMSON PREMIER SERV ST	GASOLINE STATIONS

OZ2575 **CIRCLE K 3245** **TX LPST** **U003566390**
WNW **3201 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 77630**
0.082 mi.
435 ft. **Site 4 of 6 in cluster OZ**

Actual:
578 ft.

LPST:

Focus Map:
8

Name:	CIRCLE K 3245
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 77630
Facility ID:	0036614
LPST Id:	105084
Facility Location:	3201 NORTH LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/22/1992
Entered Date:	11/16/1992
Reported Date:	10/23/1992
Closure Date:	10/19/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	HLN
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported

CIRCLE K 3245 (Continued) **U003566390**

Responsible Party Telephone: /-
Reported Date: 10/23/1992
Case Start Date: 10/19/1993
Reference Number: RN102790789
Project Manager: HLN

HIST UST AUSTIN:

Name:	LUCIEN DEAN
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0524
HID UST:	524
Inspection:	Not reported
Due:	06/01/2012

OZ2576 **CIRCLE K 3245** **TX UST** **U004319318**
WNW **3201 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.082 mi.
435 ft. **Site 5 of 6 in cluster OZ**

Actual:
578 ft.

Focus Map:
8

UST:

Name:	CIRCLE K 3245
Address:	3201 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787052014
AI Number:	63547
Facility Type:	RETAIL
Facility Begin Date:	01/20/1993
Facility Status:	INACTIVE
Additional ID:	405536852002054
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78722
Contact Name/Title:	THOMAS PENN JOHNSON,
Contact Organization Name:	CIRCLE K 3245
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	4098830760
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/20/1992
Signature Name/Title On Earliest Reg Form:	DANIEL MCCLELLAN,PRINCIPAL
Application Received Date On Earliest Reg Form:	08/24/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

CIRCLE K 3245 (Continued) **U004319318**

Owner:

Owner CN:	CN600786057
Owner Last Name:	THE JOHNSON ESTATE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	395536842002054
Additional ID:	405536852002054
AI Number:	63547
Owner Effective Begin Date:	01/20/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146633
Facility ID:	94478
Ai Number:	63547
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

CIRCLE K 3245 (Continued) **U004319318**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	5
Tank Capacity:	3000
UST Comprt ID:	151644
UST ID:	146633
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

CIRCLE K 3245 (Continued) **U004319318**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146634
Facility ID:	94478
Ai Number:	63547
Tank Id:	8
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

CIRCLE K 3245 (Continued) **U004319318**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	8
Tank Capacity:	3000
UST Comprt ID:	151645
UST ID:	146634
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

CIRCLE K 3245 (Continued) **U004319318**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146626
Facility ID:	94478
Ai Number:	63547
Tank Id:	9
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

CIRCLE K 3245 (Continued) **U004319318**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	9
Tank Capacity:	3000
UST Comprt ID:	151637
UST ID:	146626
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

CIRCLE K 3245 (Continued) **U004319318**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146627
Facility ID:	94478
Ai Number:	63547
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

CIRCLE K 3245 (Continued) **U004319318**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	151638
UST ID:	146627
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000

CIRCLE K 3245 (Continued) **U004319318**

Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146628
Facility ID:	94478
Ai Number:	63547
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

CIRCLE K 3245 (Continued) **U004319318**

Installation Signature Date:	07/08/1992
Compartment Records:	
Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	151639
UST ID:	146628
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146629
Facility ID:	94478
Ai Number:	63547
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND

CIRCLE K 3245 (Continued) **U004319318**

Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	6
Tank Capacity:	3000
UST Comprt ID:	151640
UST ID:	146629
AI Number:	63547
Compartment ID:	A

CIRCLE K 3245 (Continued) **U004319318**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146630
Facility ID:	94478
Ai Number:	63547
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

CIRCLE K 3245 (Continued) **U004319318**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	7
Tank Capacity:	3000
UST Comprt ID:	151641
UST ID:	146630
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

CIRCLE K 3245 (Continued) **U004319318**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146631
Facility ID:	94478
Ai Number:	63547
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

CIRCLE K 3245 (Continued) **U004319318**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	151642
UST ID:	146631
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

CIRCLE K 3245 (Continued) **U004319318**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1948
Tank Registration Date:	08/24/1992
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	146632
Facility ID:	94478
Ai Number:	63547
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/09/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

CIRCLE K 3245 (Continued) **U004319318**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/08/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	151643
UST ID:	146632
AI Number:	63547
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

CIRCLE K 3245 (Continued) **U004319318**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE JOHNSON ESTATE
Contact Mailing Address (Delivery):	PO BOX 246
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ORANGE, TX 77631 0246
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	94478
Additional ID:	405536852002054
Princ ID:	395536842002054
AI Number:	63547
Facility Name:	CIRCLE K 3245
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	THOMAS JOHNSON/

OY2577 **REIDS LAUNDRY & DRY CLEANERS INC** **RCRA NonGen / NLR** **1000891559**
WNW **3317 N LAMAR BLVD** **TX0000363747**
< 1/8 **AUSTIN, TX 78705**
0.083 mi.
436 ft. **Site 5 of 12 in cluster OY**

Actual:
587 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20120412
Handler Name:	Reids Laundry & Dry Cleaners Inc
Handler Address:	3317 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TX0000363747
Contact Name:	TOMMY L REID
Contact Address:	3317 N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Telephone:	512-302-1870
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

REIDS LAUNDRY & DRY CLEANERS INC (Continued) **1000891559**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	3317 N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Name:	Reids Laundry & Dry Cleaners Inc
Owner Type:	Private
Operator Name:	Reids Laundry & Dry Cleaners Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002

REIDS LAUNDRY & DRY CLEANERS INC (Continued) **1000891559**

Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	REIDS LAUNDRY AND DRY CLEANERS INC
Legal Status:	Private
Date Became Current:	20090311
Date Ended Current:	Not reported
Owner/Operator Address:	7010 W HIGHWAY 71
Owner/Operator City,State,Zip:	AUSTIN, TX 78735
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	REIDS LAUNDRY & DRY CLEANERS INC
Legal Status:	Private
Date Became Current:	20120412
Date Ended Current:	Not reported
Owner/Operator Address:	7010 W HIGHWAY 71
Owner/Operator City,State,Zip:	AUSTIN, TX 78735
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	REIDS LAUNDRY & DRY CLEANERS INC
Legal Status:	Private
Date Became Current:	20080924
Date Ended Current:	Not reported
Owner/Operator Address:	7010 W HIGHWAY 71
Owner/Operator City,State,Zip:	AUSTIN, TX 78735
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TOMMY L REID
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7010 HWY 71 W
Owner/Operator City,State,Zip:	AUSTIN, TX 78735
Owner/Operator Telephone:	512-288-3713
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

REIDS LAUNDRY & DRY CLEANERS INC (Continued) **1000891559**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: REIDS LAUNDRY & DRY CLEANERS INC
Legal Status: Private
Date Became Current: 20120412
Date Ended Current: Not reported
Owner/Operator Address: 7010 W HIGHWAY 71
Owner/Operator City,State,Zip: AUSTIN, TX 78735
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: REIDS LAUNDRY & DRY CLEANERS INC
Legal Status: Private
Date Became Current: 20010927
Date Ended Current: Not reported
Owner/Operator Address: 7010 W HIGHWAY 71
Owner/Operator City,State,Zip: AUSTIN, TX 78735
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: REIDS LAUNDRY & DRY CLEANERS INC
Legal Status: Private
Date Became Current: 20080924
Date Ended Current: Not reported
Owner/Operator Address: 7010 W HIGHWAY 71
Owner/Operator City,State,Zip: AUSTIN, TX 78735
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: REIDS LAUNDRY AND DRY CLEANERS INC
Legal Status: Private
Date Became Current: 20090311
Date Ended Current: Not reported
Owner/Operator Address: 7010 W HIGHWAY 71
Owner/Operator City,State,Zip: AUSTIN, TX 78735
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: REIDS LAUNDRY & DRY CLEANERS INC
Legal Status: Private
Date Became Current: 20010927
Date Ended Current: Not reported
Owner/Operator Address: 7010 W HIGHWAY 71
Owner/Operator City,State,Zip: AUSTIN, TX 78735

REIDS LAUNDRY & DRY CLEANERS INC (Continued) **1000891559**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20010927
Handler Name: REIDS LAUNDRY & DRY CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080924
Handler Name: REIDS LAUNDRY & DRY CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090311
Handler Name: REIDS LAUNDRY AND DRY CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120412
Handler Name: REIDS LAUNDRY & DRY CLEANERS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

REIDS LAUNDRY & DRY CLEANERS INC (Continued) **1000891559**

Receive Date:	19940609
Handler Name:	REIDS LAUNDRY & DRY CLEANERS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	81232
NAICS Description:	DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

OY2578 **REIDS CLEANERS 5** **TX HIST UST** **S103612407**
WNW **3317 N LAMAR BLVD** **TX DRYCLEANERS** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX Ind. Haz Waste**
0.083 mi. **TX COMP HIST**
436 ft. **Site 6 of 12 in cluster OY**

Actual:
587 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	HUMBLE OIL & REFINING CO.
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0466
HID UST:	466
Inspection:	Not reported
Due:	06/01/2012

DRYCLEANERS:

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5

REIDS CLEANERS 5 (Continued) **S103612407**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705

REIDS CLEANERS 5 (Continued) **S103612407**

RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	PETROLEUM
Gallons:	800
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039

REIDS CLEANERS 5 (Continued) **S103612407**

Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REID S LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD

REIDS CLEANERS 5 (Continued) **S103612407**

City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR11485
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported

REIDS CLEANERS 5 (Continued) **S103612407**

Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5

REIDS CLEANERS 5 (Continued) **S103612407**

Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841

REIDS CLEANERS 5 (Continued) **S103612407**

EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

REIDS CLEANERS 5 (Continued) **S103612407**

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	REIDS CLEANERS 5
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN103955803
Region:	11
CN Number:	CN600304638
DCR Number:	Not reported
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 5
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Ind. Haz Waste:

Name:	REIDS LAUNDRY & DRY CLEANERS
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	82714
Registration Initial Notification Date:	05/06/1994
Registration Last Amendment Date:	04/04/2012
EPA Identification:	TX0000363747
Primary NAICS Code:	812320
Status Change Date:	20120412

REIDS CLEANERS 5 (Continued) **S103612407**

Land Type:	PRIVATE
Description of Facility Site Location:	3317 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	REIDS LAUNDRY & DRY CLEANERS INC
Contact Name:	TOMMY L REID
Contact Telephone Number:	512-3021870
Mailing Address:	3317 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787052016
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	98858
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20120412
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	REIDS LAUNDRY & DRY CLEANERS INC
Operator Address:	7010 W HIGHWAY 71
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78735
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported

REIDS CLEANERS 5 (Continued) **S103612407**

Operator Business Type:	Corporation
Operator Tax ID:	17423907595
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	REIDS LAUNDRY & DRY CLEANERS INC
Owner Mailing Address:	7010 W HIGHWAY 71
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78735
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17423907595
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	039
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Distillation solvent recovery unit
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940506
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported

REIDS CLEANERS 5 (Continued) **S103612407**

System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	RCRA EXEMPT UNRATED DRUM OPEN TOP USED FOR DRAINING AND STORING TH SPENT CARTRI
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990121
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	RCRA EXEMPT 55 GAL METAL OPEN TOP UNRATED DRUM
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990121
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	004
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported

REIDS CLEANERS 5 (Continued) **S103612407**

Unit Description:	55GAL UN RATED METAL OPEN TOP DRUM
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20010129
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	7010 W HIGHWAY 71
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78735
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	7010 W HIGHWAY 71
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78735
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	TOMMY REID
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	3317 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	1-512-3021870
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	174533
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT TETRACHLOROETHYLENE LIQUID THAT CAN NO LONGER BE USED IN THE PROCESS OF DR
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1

REIDS CLEANERS 5 (Continued) **S103612407**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	174534
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	TETRACHLOROETHYLENE CONTAMINATED FILTERS USED TO CLEAN THE CHEMIC IT IS USE
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	95734
Texas Waste Code:	Not reported
Texas Waste Code 2:	3605202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Distilled solvents from dry cleaning clothes
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

REIDS CLEANERS 5 (Continued) **S103612407**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	187929
Texas Waste Code:	Not reported
Texas Waste Code 2:	3606601H
Waste Code Status:	INACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	TETRACHLOROETHYLENE STILL BOTTOM FROM THE DRY CLEANING PROCESS
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3317 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000311538
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3317 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705

REIDS CLEANERS 5 (Continued) **S103612407**

AR Number: 0000311538
Principal Name: REIDS LAUNDRY & DRY CLEANERS INC
Attention Name: Not reported
Attention Suffix: NWG

COMP HIST:

RN Number: RN103955803
Name: REIDS CLEANERS 5
Address: 3317 N LAMAR BLVD
City,State,Zip: TX 78705
Region: REGION 11 - AUSTIN
CN Number: CN601236110
CN Name: LLOYD DON
CN Rating: 0
Classification: UNCLASSIFIED
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: UNCLASSIFIED
Date Rated 2: 09/01/2022
Date Published to Web 2: 11/15/2022
NAICS Code: 812320
SIC Code: 1542
Related Number: TX0000363747,DCR11485,DCR11485

RN Number: RN103955803
Name: REIDS CLEANERS 5
Address: 3317 N LAMAR BLVD
City,State,Zip: TX 78705
Region: REGION 11 - AUSTIN
CN Number: CN600304638
CN Name: REIDS LAUNDRY & DRY CLEANERS INC
CN Rating: 0
Classification: UNCLASSIFIED
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: UNCLASSIFIED
Date Rated 2: 09/01/2022
Date Published to Web 2: 11/15/2022
NAICS Code: 812320
SIC Code: 6552
Related Number: TX0000363747,DCR11485,DCR11485

OY2579 **MARKLAND EXXON SERVICE STATION** **EDR Hist Auto** **1013766737**
WNW **3317 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.083 mi.
436 ft. **Site 7 of 12 in cluster OY**

Actual:
587 ft. EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1962	TANNER STUART & SON	GASOLINE STATIONS
1965	TANNER HUMBLE SERV STA	GASOLINE STATIONS
1969	TANNER HAROLD L	Gasoline Service Stations

MARKLAND EXXON SERVICE STATION (Continued) **1013766737**

1970	TANNER HUMBLE SERV ST	GASOLINE STATIONS
1970	TANNER HAROLD L	Gasoline Service Stations
1971	TANNER HAROLD L	Gasoline Service Stations
1972	TANNER HAROLD L	Gasoline Service Stations
1973	TANNER HAROLD L	Gasoline Service Stations
1974	TANNER HAROLD L	Gasoline Service Stations
1975	TANNER EXXON SERVICE STATION	GASOLINE STATIONS
1975	TANNER HAROLD L	Gasoline Service Stations
1976	WALL RONALD N	Gasoline Service Stations
1977	WALL RONALD N	Gasoline Service Stations
1980	MARKLAND EXXON SERVICE STATION	GASOLINE STATIONS
1984	MARKLANDS JACK EXXON	GASOLINE STATIONS
1986	MARKLAND EXXON	Gasoline Service Stations
1987	MARKLAND EXXON	Gasoline Service Stations
1988	LLOYD DON SERVICE STATION	Gasoline Service Stations
1988	DON LLOYD SERVICE STATION	Gasoline Service Stations
1988	MARKLAND EXXON	Gasoline Service Stations
1989	DON LLOYD SERVICE STATION	Gasoline Service Stations
1989	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1990	LLOYDS SERVICE STATION	GASOLINE STATIONS
1990	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1990	DON LLOYD SERVICE STATION	Gasoline Service Stations
1991	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1992	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1993	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1994	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC
1995	LLOYD DON SERVICE STATION	Gasoline Service Stations, NEC

OY2580 **DON LLOYDS TEXACO** **TX UST** **U001265044**
WNW **3317 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.083 mi.
436 ft. **Site 8 of 12 in cluster OY**

Actual:
587 ft.

Focus Map:
8

UST:

Name:	DON LLOYDS TEXACO
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787052016
AI Number:	31749
Facility Type:	RETAIL
Facility Begin Date:	11/17/1986
Facility Status:	INACTIVE
Additional ID:	497823672002148
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	DON LLOYD,OWNER
Contact Organization Name:	DON LLOYDS TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124500956

DON LLOYDS TEXACO (Continued) **U001265044**

Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/27/1992
Signature Name/Title On Earliest Reg Form:	JERRY LLOYD,MANAGER
Application Received Date On Earliest Reg Form:	05/20/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601236110
Owner Last Name:	LLOYD DON
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	505823672002148
Additional ID:	497823672002148
AI Number:	31749
Owner Effective Begin Date:	11/17/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/20/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	83412
Facility ID:	88679
Ai Number:	31749
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

DON LLOYDS TEXACO (Continued) **U001265044**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	145324
UST ID:	83412
AI Number:	31749
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

DON LLOYDS TEXACO (Continued) **U001265044**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/20/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	83413
Facility ID:	88679
Ai Number:	31749
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

DON LLOYDS TEXACO (Continued) **U001265044**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	145325
UST ID:	83413
AI Number:	31749
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

DON LLOYDS TEXACO (Continued) **U001265044**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/20/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	83414
Facility ID:	88679
Ai Number:	31749
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

DON LLOYDS TEXACO (Continued) **U001265044**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	145326
UST ID:	83414
AI Number:	31749
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N

DON LLOYDS TEXACO (Continued) **U001265044**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/20/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	83415
Facility ID:	88679
Ai Number:	31749
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

DON LLOYDS TEXACO (Continued) **U001265044**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	145327
UST ID:	83415
AI Number:	31749
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

DON LLOYDS TEXACO (Continued) **U001265044**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	LLOYD DON
Contact Mailing Address (Delivery):	3317 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78705 2016
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	88679
Additional ID:	497823672002148
Princ ID:	505823672002148
AI Number:	31749
Facility Name:	DON LLOYDS TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DON LLOYD/

HIST UST AUSTIN:

Name:	LLOYD'S TEXACO
Address:	3317 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0446
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OY2581 **REIDS CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1020073337**
WNW **3317 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.083 mi.
436 ft. **Site 9 of 12 in cluster OY**

Actual:
587 ft.

EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
2001	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2002	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2003	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2004	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2005	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2006	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2007	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2008	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2009	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2010	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2011	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2012	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

REIDS CLEANERS & LAUNDRY (Continued) **1020073337**

2013	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2014	REIDS CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

---

OY2582 **JOASH ENTERPRISES INC** **EDR Hist Cleaner** **1020014287**
WNW **3419 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.083 mi.
436 ft. **Site 10 of 12 in cluster OY**

Actual: EDR Hist Cleaner
596 ft.

Focus Map:
8

Year:	Name:	Type:
1992	N & K INVESTMENTS INC	Drycleaning Plants, Except Rugs
1993	N & K INVESTMENTS INC	Drycleaning Plants, Except Rugs
1994	N & K INVESTMENTS INC	Drycleaning Plants, Except Rugs
1995	N & K INVESTMENTS INC	Drycleaning Plants, Except Rugs
1996	N & K INVESTMENTS INC	Drycleaning Plants, Except Rugs
1997	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
1998	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
1999	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2000	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2001	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2002	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2003	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2004	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2005	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2006	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2007	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs
2008	JOASH ENTERPRISES INC	Drycleaning Plants, Except Rugs

LY2583 **DEISON AUTO REPR** **EDR Hist Auto** **1013775194**
NE **320 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.083 mi.
436 ft. **Site 6 of 6 in cluster LY**

Actual: EDR Hist Auto
453 ft.

Focus Map:
14

Year:	Name:	Type:
1947	DEISON AUTO REPR	AUTOMOBILE REPAIRING

PA2584 **DISCOUNT CLEANERS** **EDR Hist Cleaner** **1013779125**
East **510 19TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.083 mi.
438 ft. **Site 1 of 10 in cluster PA**

Actual: EDR Hist Cleaner
556 ft.

Focus Map:
11

Year:	Name:	Type:
1965	ONE HOUR MARTINIZING	CLEANERS AND DYERS
1969	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs
1970	ONE HOUR MARTINIZING	CLEANERS AND DYERS
1970	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs
1971	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs

DISCOUNT CLEANERS (Continued) **1013779125**

1972	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs
1973	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs
1974	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs
1975	DISCOUNT CLEANERS	CLEANERS AND DYERS
1975	NUECES DRY CLEANING CO INC	Drycleaning Plants, Except Rugs

---

PB2585 **JAS. LUCAS** **TX HIST UST** **S111678703**
ESE **503 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.083 mi.
438 ft. **Site 1 of 6 in cluster PB**

Actual:
448 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JAS. LUCAS
Address:	503 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0411
HID UST:	411
Inspection:	Not reported
Due:	06/01/2012

OK2586 **NE COR MAGNOLIA PET CO** **EDR Hist Auto** **1013770232**
WSW **211 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.083 mi.
439 ft. **Site 10 of 21 in cluster OK**

Actual:
491 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1922	NE COR MAGNOLIA PET CO	AUTOMOBILE FILLING STATIONS

PC2587 **THE CLOSET FACTORY** **RCRA NonGen / NLR** **1010333376**
ESE **113 INDUSTRIAL BLVD SUITE C-1** **TXR000049577**
< 1/8 **AUSTIN, TX 78745**
0.083 mi.
440 ft. **Site 1 of 4 in cluster PC**

Actual:
671 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20020711
Handler Name:	The Closet Factory
Handler Address:	INDUSTRIAL BLVD SUITE C-1
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXR000049577
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

THE CLOSET FACTORY (Continued) **1010333376**

Non-Notifier:	E
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	INDUSTRIAL BLVD SUITE C-1
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Unknown
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN

THE CLOSET FACTORY (Continued) **1010333376**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	113 INDUSTRIAL BLVD SUITE C-1
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	999-999-9999
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20020711
Handler Name: THE CLOSET FACTORY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

OU2588 **AUSTIN HWY TRK PARTS** **TX Ind. Haz Waste** **S103605832**
NW **8204 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.083 mi.
440 ft. **Site 2 of 7 in cluster OU**

Actual:
733 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	AUSTIN HWY TRK PARTS
Address:	8204 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61898
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	8204 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11

AUSTIN HWY TRK PARTS (Continued) **S103605832**

Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN HWY TRK PARTS INC
Contact Name:	MR LEDEN
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 180028
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787180028
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20236
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030603
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN HWY TRK PARTS INC
Operator Address:	PO BOX 180028
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78718
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN HWY TRK PARTS INC
Owner Mailing Address:	PO BOX 180028
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78718

AUSTIN HWY TRK PARTS (Continued) **S103605832**

Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 180028
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 180028
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MR LEDEN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 180028
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78718
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

OU2589 **DISCOUNT DRIVE AXLE OF AUSTIN** **RCRA NonGen / NLR** **1000655867**
NW **8204 N LAMAR BLVD SUITE C 26** **FINDS** **TXD988058111**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.083 mi.
440 ft. **Site 3 of 7 in cluster OU**

Actual:
733 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20010127
Handler Name:	Discount Drive Axle Of Austin
Handler Address:	N LAMAR BLVD SUITE C 26
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD988058111
Contact Name:	RON OFNER
Contact Address:	N LAMAR BLVD SUITE C 26

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **1000655867**

Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-339-9868
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD SUITE C 26
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Discount Drive Axle Of Austin
Owner Type:	Private
Operator Name:	Discount Drive Axle Of Austin
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **1000655867**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D007
Waste Description: Chromium

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: DISCOUNT DRIVE AXLE OF AUSTIN
Legal Status: Private
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 8204 N LAMAR BLVD SUITE C 26
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9868
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DISCOUNT DRIVE AXLE OF AUSTIN
Legal Status: Private
Date Became Current: 20010127

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **1000655867**

Date Ended Current: Not reported
Owner/Operator Address: 8204 N LAMAR BLVD SUITE C 26
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9868
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERT MARTIN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 301 BRONZE
Owner/Operator City,State,Zip: GARLAND, TX 75042
Owner/Operator Telephone: 214-339-9868
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19911122
Handler Name: SUPERIOR DIRVE AXLE REMFG
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010127
Handler Name: DISCOUNT DRIVE AXLE OF AUSTIN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332313
NAICS Description: PLATE WORK MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **1000655867**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005144539

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000655867
Registry ID:	110005144539
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005144539
Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Address:	8204 N LAMAR BLVD SUITE C 26
City,State,Zip:	AUSTIN, TX 78753

OU2590 **BEAVER & SON AUTO & TRUCK REPAIR** **EDR Hist Auto** **1013774558**
NW **8204 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.083 mi.
440 ft. **Site 4 of 7 in cluster OU**

Actual:
733 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1980	BEAVER & SON AUTO & TRUCK REPAI	AUTOMOBILE REPAIRING
1982	BEAVER & SON WRECKER SV & GAR	General Automotive Repair Shops
1983	BEAVER & SON WRECKER SV & GAR	General Automotive Repair Shops

---

OU2591 **FLASHCARDS** **RCRA NonGen / NLR** **1004785147**
NW **8204 N LAMAR SUITE C20** **FINDS** **TXD988024774**
< 1/8 **AUSTIN, TX 78759** **ECHO**
0.083 mi.
440 ft. **Site 5 of 7 in cluster OU**

Actual:
733 ft.

RCRA Listings:

Focus Map:
6

Date Form Received by Agency:	20010823
Handler Name:	Flashcards
Handler Address:	N LAMAR SUITE C20
Handler City,State,Zip:	AUSTIN, TX 78759
EPA ID:	TXD988024774
Contact Name:	CLEM EVANS
Contact Address:	N LAMAR SUITE C20
Contact City,State,Zip:	AUSTIN, TX 78759
Contact Telephone:	512-339-3013
Contact Fax:	Not reported

FLASHCARDS (Continued) **1004785147**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR SUITE C20
Mailing City,State,Zip:	AUSTIN, TX 78759
Owner Name:	Flashcards
Owner Type:	Private
Operator Name:	Flashcards
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

FLASHCARDS (Continued) **1004785147**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: FLASHCARDS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8204 N LAMAR SUITE C20
Owner/Operator City,State,Zip:	AUSTIN, TX 78759
Owner/Operator Telephone:	512-339-3013
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: FLASHCARDS	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	8204 N LAMAR SUITE C20
Owner/Operator City,State,Zip:	AUSTIN, TX 78759
Owner/Operator Telephone:	512-339-3013
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CLEM EVANS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	8301 APPALACHAIN DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78759
Owner/Operator Telephone:	512-495-5039
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19910207
Handler Name: FLASH CARDS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

FLASHCARDS (Continued) **1004785147**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: FLASHCARDS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005127460

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004785147
Registry ID: 110005127460
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005127460
Name: FLASHCARDS
Address: 8204 N LAMAR SUITE C20
City,State,Zip: AUSTIN, TX 78759

OU2592 **FLASHCARDS** **TX Ind. Haz Waste** **S110294342**
NW **8204 N LAMAR BLVD STE C20** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.083 mi.
440 ft. **Site 6 of 7 in cluster OU**

Actual:
733 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	FLASHCARDS
Address:	8204 N LAMAR BLVD STE C20
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	77714
Registration Initial Notification Date:	07/08/1992
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD988024774
Primary NAICS Code:	Not reported
Status Change Date:	19920708
Land Type:	PRIVATE
Description of Facility Site Location:	8204 N Lamar, Suite C20, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	FLASHCARDS INCORPORATED
Contact Name:	CLEM EVANS
Contact Telephone Number:	512-3393013
Mailing Address:	8204 N LAMAR SUITE C20
Mailing Address2:	SUITE C20
Mailing City,State,Zip:	AUSTIN, TX 78759
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31940
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030123
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

FLASHCARDS (Continued) **S110294342**

Ind. Haz Waste:

Operator Name:	FLASHCARDS INCORPORATED
Operator Address:	8204 N LAMAR BLVD STE C20
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-3393013
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17422850358
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FLASHCARDS INCORPORATED
Owner Mailing Address:	8204 N LAMAR BLVD STE C20
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-3393013
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17422850358
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8204 N LAMAR BLVD STE C20
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3393013
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8204 N LAMAR BLVD STE C20
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3393013
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	CLEM EVANS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8204 N LAMAR SUITE C20
Contact Address 2:	SUITE C20

FLASHCARDS (Continued) **S110294342**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78759
Contact Phone:	1-512-3393013
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100605567
Name:	FLASHCARDS
Address:	8204 N LAMAR BLVD STE C20
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5944
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600315071
Customer Name:	FLASHCARDS INCORPORATED
Customer Legal Name:	Flashcards, Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8204 N Lamar, Suite C20, Austin, TX

Regulated Entity Number:	RN100605567
Name:	FLASHCARDS
Address:	8204 N LAMAR BLVD STE C20
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5944
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600315071
Customer Name:	FLASHCARDS INCORPORATED
Customer Legal Name:	Flashcards, Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	8204 N Lamar, Suite C20, Austin, TX

OU2593 **DISCOUNT DRIVE AXLE OF AUSTIN** **TX Ind. Haz Waste** **S103598432**
NW **8204 N LAMAR BLVD STE C26** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.083 mi.
440 ft. **Site 7 of 7 in cluster OU**

Actual:
733 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Address:	8204 N LAMAR BLVD STE C26
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	20579
Registration Initial Notification Date:	05/27/1991

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **S103598432**

Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD988058111
Primary NAICS Code:	332313
Status Change Date:	19910527
Land Type:	PRIVATE
Description of Facility Site Location:	8204 N Lamar, Suite C-26, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Contact Name:	RON OFNER
Contact Telephone Number:	512-3399868
Mailing Address:	8204 N LAMAR BLVD STE C26
Mailing Address2:	SUITE C 26
Mailing City,State,Zip:	AUSTIN, TX 787535945
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	7041
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020123
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Operator Address:	8204 N LAMAR BLVD STE C26
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-3399868
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **S103598432**

Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Owner Mailing Address:	8204 N LAMAR BLVD STE C26
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-3399868
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8204 N LAMAR BLVD STE C26
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3399868
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8204 N LAMAR BLVD STE C26
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3399868
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RON OFNER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8204 N LAMAR BLVD STE C26
Contact Address 2:	SUITE C 26
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3399868
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	149961
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **S103598432**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	34430
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	332313
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	149962
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	PAINT WASTE
Standard Industrial Code:	34430
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	332313
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8204 N LAMAR BLVD STE C26
Mailing Address 2:	Not reported

DISCOUNT DRIVE AXLE OF AUSTIN (Continued) **S103598432**

Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310370
Principal Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8204 N LAMAR BLVD STE C26
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310370
Principal Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8204 N LAMAR BLVD STE C26
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310370
Principal Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8204 N LAMAR BLVD STE C26
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78753
AR Number:	0000310370
Principal Name:	DISCOUNT DRIVE AXLE OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	NWG

OK2594 **AUTO SALVAGE CO** **EDR Hist Auto** **1013762501**
SW **419 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.083 mi.
440 ft. **Site 11 of 21 in cluster OK**

Actual:
490 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	AUTO SALVAGE CO	AUTOMOBILE REPAIRERS
1935	BLUE PENNANT TIRE CO	GASOLINE AND OIL SERVICE STATIONS
1940	BLUE PENNANT TIRE CO	AUTOMOBILE SERVICE STATIONS
1940	BLUE PENNANT TIRE CO	GASOLINE AND OIL SERVICE STATIONS
1947	BLUE PENNANT TIRE CO	GASOLINE AND OIL SERVICE STATIONS
1947	BLUE PENNANT TIRE CO	AUTOMOBILE SERVICE STATIONS

2595 West < 1/8 0.084 mi. 441 ft. | **CAPITOL LAUNDRY & DRY CLEANING CO STA NO**
501 W 24TH ST
TRAVIS (County), TX 78705 | **EDR Hist Cleaner** | **1013782695**
N/A

Actual: 591 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1965	CAPITOL LAUNDRY & DRY	LAUNDRIES
1970	CAPITOL LAUNDRY & DRY CLEANING	LAUNDRIES

PB2596 ESE < 1/8 0.084 mi. 442 ft. | **AUSTIN CONVENTION CENTER**
500 E CESAR CHAVEZ ST
AUSTIN, TX 78701 | **RCRA NonGen / NLR** | **1016976811**
TXR000082023

Site 2 of 6 in cluster PB

Actual: 455 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20180910
Handler Name:	Austin Convention Center
Handler Address:	500 E CESAR CHAVEZ ST
Handler City,State,Zip:	AUSTIN, TX 78701-4121
EPA ID:	TXR000082023
Contact Name:	CAMALA JONES
Contact Address:	PO BOX 1088
Contact City,State,Zip:	AUSTIN, TX 78767-1088
Contact Telephone:	512-404-4309
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1088
Mailing City,State,Zip:	AUSTIN, TX 78767-1088
Owner Name:	City Of Austin
Owner Type:	Private
Operator Name:	City Of Austin
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

AUSTIN CONVENTION CENTER (Continued) **1016976811**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181130
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Private
Date Became Current:	20140819
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1088
Owner/Operator City,State,Zip:	AUSTIN, TX 78767-1088
Owner/Operator Telephone:	512-404-4000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Private
Date Became Current:	20140819
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1088
Owner/Operator City,State,Zip:	AUSTIN, TX 78767-1088
Owner/Operator Telephone:	512-404-4000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

AUSTIN CONVENTION CENTER (Continued) **1016976811**

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Private
Date Became Current: 20140819
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1088
Owner/Operator City,State,Zip: AUSTIN, TX 78767-1088
Owner/Operator Telephone: 512-404-4000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Private
Date Became Current: 20140819
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1088
Owner/Operator City,State,Zip: AUSTIN, TX 78767-1088
Owner/Operator Telephone: 512-404-4000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140819
Handler Name: AUSTIN CONVENTION CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180910
Handler Name: AUSTIN CONVENTION CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53112
NAICS Description: LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

AUSTIN CONVENTION CENTER (Continued) **1016976811**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

PB2597 **AUSTIN CONVENTION CENTER** **TX HIST UST** **S121973650**
ESE **500 E CESAR CHAVEZ ST** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.084 mi.
442 ft. **Site 3 of 6 in cluster PB**

Actual:
455 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CONVENTION CENTER
Address:	500 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0180
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	AUSTIN CONVENTION CENTER
Address:	500 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	95778
Registration Initial Notification Date:	08/19/2014
Registration Last Amendment Date:	09/10/2018
EPA Identification:	TXR000082023
Primary NAICS Code:	531120
Status Change Date:	20180924
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CITY OF AUSTIN
Contact Name:	CAMALA JONES
Contact Telephone Number:	512-4044309
Mailing Address:	PO BOX 1088
Mailing Address2:	AUSTIN CONVENTION CENTER DEPARTMENT
Mailing City,State,Zip:	AUSTIN, TX 787671088
Mailing County:	UNITED STATES

AUSTIN CONVENTION CENTER (Continued) **S121973650**

Facility Country:	UNITED STATES
TNRCC Facility ID:	131123
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20180924
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	PO BOX 1088
Operator Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	1-512-4044000 x4309
Operator Fax Number:	1-512-4044416
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	PO BOX 1088
Owner Mailing Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	1-512-4044000 x4309
Owner Fax:	1-512-4044416
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported

AUSTIN CONVENTION CENTER (Continued) **S121973650**

Capacity:	55
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	STORAGE AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20140819
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	PO BOX 1088
Contact Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4044000 x4309
Contact Fax:	1-512-4044416
Contact Email:	Not reported

Contact Name:	CAMALA JONES
Contact Title:	SUSTAINABILITY COORDINATO
Contact Role:	PRICONT
Contact Address:	PO BOX 1088
Contact Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4044309
Contact Fax:	1-512-4044416
Contact Email:	CAMALA.JONES@AUSTINTEXAS.GOV

Ind. Haz Waste:

Waste ID:	365157
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	METAL CANS WITH REMAINING LIQUID CHAFING FUEL STERNO FUEL
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported

AUSTIN CONVENTION CENTER (Continued) **S121973650**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	531120
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-512-4044000 x4309
Mailing Address:	PO BOX 1088
Mailing Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Mailing City,St,Zip:	AUSTIN, TX 78767
AR Number:	0000318161
Principal Name:	CITY OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-512-4044000 x4309
Mailing Address:	PO BOX 1088
Mailing Address 2:	AUSTIN CONVENTION CENTER DEPARTMENT
Mailing City,St,Zip:	AUSTIN, TX 78767
AR Number:	0000318161
Principal Name:	CITY OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	NWG

PB2598 **NEW CONVENTION CENTER** **TX UST** **U001286149**
ESE **500 E 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.084 mi.
442 ft. **Site 4 of 6 in cluster PB**

Actual:
455 ft.

Focus Map:
11

UST:

Name:	NEW CONVENTION CENTER
Address:	500 E 1ST ST
City,State,Zip:	AUSTIN, TX 787014121
AI Number:	56024
Facility Type:	RETAIL
Facility Begin Date:	10/03/1990
Facility Status:	INACTIVE
Additional ID:	273193602002118
Facility Exempt Status:	N
Records Off-Site:	No

NEW CONVENTION CENTER (Continued) **U001286149**

UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	GEOFF STEWART,UST PROJECT MGR
Contact Organization Name:	NEW CONVENTION CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124997192
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/12/1990
Signature Name/Title On Earliest Reg Form:	GEOFF STEWART,UST PROJECT MGR
Application Received Date On Earliest Reg Form:	10/01/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	273193602002118
AI Number:	56024
Owner Effective Begin Date:	10/03/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1940
Tank Registration Date:	10/01/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N

NEW CONVENTION CENTER (Continued) **U001286149**

Pipe Type:	S
UST ID:	135837
Facility ID:	85875
Ai Number:	56024
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/13/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

NEW CONVENTION CENTER (Continued) **U001286149**

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	133059
UST ID:	135837
AI Number:	56024
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21816
Cert ID:	61040
UST Comprt ID:	178448
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61039
UST Comprt ID:	178449
UST ID:	54257

NEW CONVENTION CENTER (Continued) **U001286149**

AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61042
UST Comprt ID:	178446
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61043
UST Comprt ID:	178445
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61044
UST Comprt ID:	178444
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	286979
UST Comprt ID:	828275
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	302687
UST Comprt ID:	875423
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	319704
UST Comprt ID:	926061
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	335408
UST Comprt ID:	973173
UST ID:	54257
AI Number:	56024

NEW CONVENTION CENTER (Continued) **U001286149**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	353814
UST Comprt ID:	1028692
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	370648
UST Comprt ID:	1079615
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60779
UST Comprt ID:	178452
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60780
UST Comprt ID:	178453
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60781
UST Comprt ID:	178454
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60782
UST Comprt ID:	178455
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60783
UST Comprt ID:	178451
UST ID:	54257
AI Number:	56024
Tank ID:	4

NEW CONVENTION CENTER (Continued) **U001286149**

Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60784
UST Comprt ID:	178450
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61045
UST Comprt ID:	178443
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61046
UST Comprt ID:	178442
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	222516
UST Comprt ID:	638176
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	236649
UST Comprt ID:	679363
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	253926
UST Comprt ID:	730174
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	269671
UST Comprt ID:	776891
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A

NEW CONVENTION CENTER (Continued) **U001286149**

Self Cert ID:	21816
Cert ID:	61041
UST Comprt ID:	178447
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1940
Tank Registration Date:	10/01/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135838
Facility ID:	85875
Ai Number:	56024
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/13/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

NEW CONVENTION CENTER (Continued) **U001286149**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	133060
UST ID:	135838
AI Number:	56024
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

NEW CONVENTION CENTER (Continued) **U001286149**

More Self Certification:

Self Cert ID:	21816
Cert ID:	61040
UST Comprt ID:	178448
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61039
UST Comprt ID:	178449
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61042
UST Comprt ID:	178446
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61043
UST Comprt ID:	178445
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61044
UST Comprt ID:	178444
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	286979
UST Comprt ID:	828275
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	302687
UST Comprt ID:	875423
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A

NEW CONVENTION CENTER (Continued) **U001286149**

Self Cert ID:	21816
Cert ID:	319704
UST Comprt ID:	926061
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	335408
UST Comprt ID:	973173
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	353814
UST Comprt ID:	1028692
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	370648
UST Comprt ID:	1079615
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60779
UST Comprt ID:	178452
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60780
UST Comprt ID:	178453
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60781
UST Comprt ID:	178454
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816

NEW CONVENTION CENTER (Continued) **U001286149**

Cert ID:	60782
UST Comprt ID:	178455
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60783
UST Comprt ID:	178451
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60784
UST Comprt ID:	178450
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61045
UST Comprt ID:	178443
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61046
UST Comprt ID:	178442
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	222516
UST Comprt ID:	638176
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	236649
UST Comprt ID:	679363
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	253926

NEW CONVENTION CENTER (Continued) **U001286149**

UST Comprt ID:	730174
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	269671
UST Comprt ID:	776891
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61041
UST Comprt ID:	178447
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1940
Tank Registration Date:	10/01/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135839
Facility ID:	85875
Ai Number:	56024
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/13/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

NEW CONVENTION CENTER (Continued) **U001286149**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	133061
UST ID:	135839
AI Number:	56024
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

NEW CONVENTION CENTER (Continued) **U001286149**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21816
Cert ID:	61040
UST Comprt ID:	178448
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61039
UST Comprt ID:	178449
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61042
UST Comprt ID:	178446
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61043
UST Comprt ID:	178445
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61044
UST Comprt ID:	178444
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	286979

NEW CONVENTION CENTER (Continued) **U001286149**

UST Comprt ID:	828275
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	302687
UST Comprt ID:	875423
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	319704
UST Comprt ID:	926061
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	335408
UST Comprt ID:	973173
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	353814
UST Comprt ID:	1028692
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	370648
UST Comprt ID:	1079615
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60779
UST Comprt ID:	178452
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60780
UST Comprt ID:	178453

NEW CONVENTION CENTER (Continued) **U001286149**

UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60781
UST Comprt ID:	178454
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60782
UST Comprt ID:	178455
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60783
UST Comprt ID:	178451
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	60784
UST Comprt ID:	178450
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61045
UST Comprt ID:	178443
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61046
UST Comprt ID:	178442
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	222516
UST Comprt ID:	638176
UST ID:	54257

NEW CONVENTION CENTER (Continued) **U001286149**

AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	236649
UST Comprt ID:	679363
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	253926
UST Comprt ID:	730174
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	269671
UST Comprt ID:	776891
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21816
Cert ID:	61041
UST Comprt ID:	178447
UST ID:	54257
AI Number:	56024
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	3600 MANOR RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78723 5817
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85875
Additional ID:	273193602002118
Princ ID:	840354562001227
AI Number:	56024
Facility Name:	NEW CONVENTION CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	NATHAN SHCNIEDER/

PB2599 ESE < 1/8 0.084 mi. 442 ft. | **GENES MAGNOLIA SER**
500 1ST E
AUSTIN, TX
Site 5 of 6 in cluster PB | **EDR Hist Auto** | **1013753061**
N/A

Actual: 455 ft.
EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1935	MAGNOLIA PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1940	GENES MAGNOLIA SER	GASOLINE AND OIL SERVICE STATIONS
1947	ANDERSONS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	LEWIS SERVICE STA	GASOLINE STATIONS

LV2600 ESE < 1/8 0.084 mi. 443 ft. | **M F ROUTE LAUNDRIES**
103 E 38TH ST
AUSTIN, TX 78705
Site 9 of 9 in cluster LV | **EDR Hist Cleaner** | **1013783364**
N/A

Actual: 607 ft.
EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1984	M F ROUTE LAUNDRIES	LAUNDRIES AND DRY CLEANERS

OK2601 WSW < 1/8 0.084 mi. 444 ft. | **TEXAS AMERICAN RESOURCES COMPANY**
AUSTIN, TX
Site 12 of 21 in cluster OK | **PFAS ECHO** | **1027427814**
N/A

Actual: 491 ft.
PFAS ECHO:

Focus Map: 11

Name:	TEXAS AMERICAN RESOURCES COMPANY
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.26753
Longitude:	-97.74461
Count:	1
County:	TRAVIS COUNTY
Status:	Unknown
Region:	06
Industry:	Oil and Gas
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070864197
Facility Percent Minority:	45.013
Facility Derived Tribes:	-
Facility Population:	5583.98
EPA Programs:	-
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050306
Facility Derived CD113:	21
Facility Derived CB2010:	484530011001086
Facility Major Flag:	-
Facility Active Flag:	-

TEXAS AMERICAN RESOURCES COMPANY (Continued) **1027427814**

Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	-
Facility Programs With SNC:	0
Facility Compliance Status:	-
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.74461,%22y%22:30.26753,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

2602 **CONOCOPHILLIPS COMPANY** **EDR Hist Auto** **1020570076**
WNW **1122 COLORADO ST STE 2323** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.084 mi.
444 ft.

Actual:
535 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2005	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2006	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC

CONOCOPHILLIPS COMPANY (Continued) **1020570076**

2008	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2008	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2009	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2009	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2010	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2010	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2011	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2011	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2012	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2012	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2013	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2013	CONOCOPHILLIPS COMPANY	Gasoline Service Stations
2014	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC
2014	CONOCOPHILLIPS COMPANY	Gasoline Service Stations, NEC

OK2603 **BEARD SPRING** **EDR Hist Auto** **1013774555**
WSW **213 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.084 mi.
444 ft. **Site 13 of 21 in cluster OK**

Actual:
491 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	BEARD SPRING	AUTOMOBILE REPAIRING
1958	BEARD SPRING	AUTOMOBILE REPAIRING
1962	BEARD SPRING & BRAKE	AUTOMOBILE REPAIRING

OK2604 **BEARD SPRING C BRAKE** **EDR Hist Auto** **1013768426**
WSW **213 5TH ST W** **N/A**
< 1/8 **AUSTIN, TX**
0.084 mi.
444 ft. **Site 14 of 21 in cluster OK**

Actual:
491 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	BEARD SPRING C BRAKE	AUTOMOBILE REPAIRING

OK2605 **PURYEAR DEWEY** **EDR Hist Auto** **1013764411**
WSW **206 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.084 mi.
444 ft. **Site 15 of 21 in cluster OK**

Actual:
491 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1958	PURYEAR DEWEY	AUTOMOBILE RADIATOR REPAIRERS
1962	PURYEAR DEWEY	AUTOMOBILE RADIATOR REPAIRERS

OI2606 WNW < 1/8 0.084 mi. 446 ft. — **WILBURN SINCLAIR SERVICE**, **520 6TH ST W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013777043** / **N/A**

Site 11 of 15 in cluster OI

Actual: 481 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1965	WILBURN SINCLAIR SERVICE	GASOLINE STATIONS

OI2607 WNW < 1/8 0.084 mi. 446 ft. — **BASS SERV STA**, **520 6TH W**, **AUSTIN, TX** — **EDR Hist Auto** — **1013756259** / **N/A**

Site 12 of 15 in cluster OI

Actual: 481 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	MASON IRA SERVICE STA FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	BROWN & COX SERY STA	GASOLINE AND OIL SERVICE STATIONS
1953	BASS SERV STA	GASOLINE STATIONS
1958	TOMLINSON SERV	GASOLINE STATIONS
1962	WILBURN SERV STA	GASOLINE STATIONS

2608 WNW < 1/8 0.085 mi. 449 ft. — **CENTRAL PROPERTIES INC.**, **6008 N LAMAR BLVD**, **AUSTIN, TX** — **TX HIST UST** — **S128729517** / **N/A**

Actual: 702 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	CENTRAL PROPERTIES INC.
Address:	6008 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0070
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OY2609 WNW < 1/8 0.085 mi. 450 ft. — **RICKS CLEANERS**, **3411 N LAMAR BLVD**, **AUSTIN, TX 78705** — **TX DRYCLEANERS** — **S117667193** / **N/A**

Site 11 of 12 in cluster OY

Actual: 595 ft.

Focus Map: 8

DRYCLEANERS:

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399

RICKS CLEANERS (Continued) **S117667193**

Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	CELESTE@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN601536972
DCR Number:	DCR15768
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399
Principal Name:	RICK S OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported

RICKS CLEANERS (Continued) **S117667193**

Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399
Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	CELESTE@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399
Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	CELESTE@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768

RICKS CLEANERS (Continued) **S117667193**

AR Number:	24007399
Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	CELESTE@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399
Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN605126432
DCR Number:	DCR15768
AR Number:	24007399
Principal Name:	RICKS OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017

RICKS CLEANERS (Continued) **S117667193**

Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	RICKS CLEANERS
Address:	3411 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN107167249
Region:	REGION 11 - AUSTIN
CN Number:	CN601536972
DCR Number:	DCR15768
AR Number:	24000713
Principal Name:	CARERA INC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

PD2610 **LEWIS PAUL C LAUNDRY REAR** **EDR Hist Cleaner** **1013786017**
ESE **205 E 15TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.085 mi.
450 ft. **Site 1 of 5 in cluster PD**

Actual:
522 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1896	LEWIS PAUL C LAUNDRY REAR	LAUNDRIES

NL2611 **KOCH CHARLES J DYER** **EDR Hist Cleaner** **1013778023**
SSW **405 CONGRESS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.085 mi.
450 ft. **Site 4 of 5 in cluster NL**

Actual:
485 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1896	KOCH CHARLES DYER SCOURER TAILO	DYERS AND SCOURERS
1901	KOCH CHARLES L. TAILOR DYER	DYERS AND SCOURERS
1911	KOCH CHARLES J DYER	CLOTHES PRESSERS AND CLEANERS
1911	KOCH CHARLES J DYER	DYERS AND SCOURERS
1916	KOCH CHARLES J DYER	CLOTHES CLEANERS AND PRESSERS
1922	KOCH C J DCLO CLNR	CLOTHES CLEANERS AND PRESSERS

OH2612 ESE < 1/8 0.085 mi. 451 ft. | **AUSTIN CARBONICS**
501 E 3RD ST
AUSTIN, TX | **TX HIST UST** | **S128728928**
N/A

Site 3 of 5 in cluster OH

Actual: 468 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	AUSTIN CARBONICS
Address:	501 E 3RD ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0142
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OH2613 ESE < 1/8 0.085 mi. 451 ft. | **FIELDON BERRY**
501 W 3RD ST
AUSTIN, TX 78701 | **TX UST** | **U001245540**
N/A

Site 4 of 5 in cluster OH

Actual: 468 ft.
Focus Map: 11

UST:

Name:	FIELDON BERRY
Address:	501 W 3RD ST
City,State,Zip:	AUSTIN, TX 787013807
AI Number:	9297
Facility Type:	UNKNOWN
Facility Begin Date:	07/16/1986
Facility Status:	INACTIVE
Additional ID:	803585412003204
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	FIELDON BERRY,
Contact Organization Name:	FIELDON BERRY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124764693
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/28/1986
Signature Name/Title On Earliest Reg Form:	F BERRY,
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602285983
Owner Last Name:	BERRY FIELDON

FIELDON BERRY (Continued) **U001245540**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	794585402003204
Additional ID:	803585412003204
AI Number:	9297
Owner Effective Begin Date:	07/16/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	24631
Facility ID:	48902
Ai Number:	9297
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/01/1990
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

FIELDON BERRY (Continued) **U001245540**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/25/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	30669
UST ID:	24631
AI Number:	9297
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

FIELDON BERRY (Continued) **U001245540**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BERRY FIELDON
Contact Mailing Address (Delivery):	501 W 3RD ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 3807
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	48902
Additional ID:	803585412003204
Princ ID:	794585402003204
AI Number:	9297
Facility Name:	FIELDON BERRY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	FIELDON BERRY/

PE2614 **STAR BRITE CLEANERS** **TX DRYCLEANERS** **S126682958**
WNW **501 W 15TH ST STE A** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.085 mi.
451 ft. **Site 1 of 2 in cluster PE**

Actual:
530 ft.

Focus Map:
11

DRYCLEANERS:

Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177
DCR Number:	DCR12250
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264

STAR BRITE CLEANERS (Continued) **S126682958**

Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN604848820
DCR Number:	DCR12250
AR Number:	24007272
Principal Name:	GARMENT BAG INC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264
Site Name:	STAR BRITE CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN604848820
DCR Number:	DCR12250
AR Number:	24007272
Principal Name:	GARMENT BAG INC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	IN PROGRESS
Fiscal Year:	FY2023
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A

STAR BRITE CLEANERS (Continued) **S126682958**

City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN604848820
DCR Number:	DCR12250
AR Number:	24007272
Principal Name:	GARMENT BAG INC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

CENTRAL REGISTRY:

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

STAR BRITE CLEANERS (Continued) **S126682958**

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A

STAR BRITE CLEANERS (Continued) **S126682958**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN602462483
Customer Name:	EVANS AND KOCHER INCORPORATED
Customer Legal Name:	Evans and Kocher Incorporated
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	10/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN602462483
Customer Name:	EVANS AND KOCHER INCORPORATED
Customer Legal Name:	Evans and Kocher Incorporated
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	10/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN602462483
Customer Name:	EVANS AND KOCHER INCORPORATED
Customer Legal Name:	Evans and Kocher Incorporated
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	10/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE

STAR BRITE CLEANERS (Continued) **S126682958**

Status Date:	10/17/2003
Customer Number:	CN602462483
Customer Name:	EVANS AND KOCHER INCORPORATED
Customer Legal Name:	Evans and Kocher Incorporated
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	10/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN602462483
Customer Name:	EVANS AND KOCHER INCORPORATED
Customer Legal Name:	Evans and Kocher Incorporated
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	10/30/2017
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN103970935
Name:	STAR BRITE CLEANERS
Address:	501 W 15TH ST STE A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1534
Status:	ACTIVE
Status Date:	10/17/2003
Customer Number:	CN604848820
Customer Name:	GARMENT BAG INC
Customer Legal Name:	Garment Bag Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/1/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
10 additional TX CENTRAL REG: record(s) in the EDR Site Report.

PE2615 **MARTINIZING 94177 15TH** **TX DRYCLEANERS** **S108109017**
WNW **501 W 15TH ST STE A** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.085 mi.
451 ft. **Site 2 of 2 in cluster PE**

Actual:
530 ft.

Focus Map:
11

DRYCLEANERS:

Name:	MARTINIZING 94177 15TH
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177
DCR Number:	DCR12250
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	100
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MARTINIZING 94177 15TH
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN602462483
DCR Number:	DCR12250
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	180
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN600255533

MARTINIZING 94177 15TH (Continued) **S108109017**

DCR Number:	Not reported
AR Number:	24000387
Principal Name:	COMET CLEANERS
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	180
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

MARTINIZING 94177 15TH (Continued) **S108109017**

Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	140
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11

MARTINIZING 94177 15TH (Continued) **S108109017**

CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION

MARTINIZING 94177 15TH (Continued) **S108109017**

Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	130
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	180
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	180
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935

MARTINIZING 94177 15TH (Continued) **S108109017**

Region:	11
CN Number:	CN602462483
DCR Number:	Not reported
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MARTINIZING 94177 15TH
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN602462483
DCR Number:	DCR12250
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MARTINIZING 94177 15TH
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177
DCR Number:	DCR12250
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	STAR BRITE 15TH ST

MARTINIZING 94177 15TH (Continued) **S108109017**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	1
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN602462483
DCR Number:	DCR12250
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE 15TH ST
Address:	501 W 15TH ST STE A
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN103970935
Region:	REGION 11 - AUSTIN
CN Number:	CN602462483
DCR Number:	DCR12250
AR Number:	24002872
Principal Name:	EVANS AND KOCHER INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE 15TH ST
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

2616 ESE < 1/8 0.086 mi. 452 ft. | **ACCUGRAPHICS 7801 N LAMAR BLVD STE C51 AUSTIN, TX 78752** | **TX Ind. Haz Waste** | **S102749700 N/A**

Actual: 761 ft.

Focus Map: 6

Ind. Haz Waste:

Name:	ACCUGRAPHICS
Address:	7801 N LAMAR BLVD STE C51
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	66163
Registration Initial Notification Date:	08/23/2001
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	20010823
Land Type:	Not reported
Description of Facility Site Location:	7801 N Lamar Blvd, Ste C51, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MEYERS MANAGEMENT COMPANY
Contact Name:	TERRY MEYERS
Contact Telephone Number:	512-4594929
Mailing Address:	7801 N LAMAR BLVD STE C51
Mailing Address2:	STE C51
Mailing City,State,Zip:	AUSTIN, TX 787521033
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21461
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031030
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

ACCUGRAPHICS (Continued) **S102749700**

Ind. Haz Waste:

Operator Name:	MEYERS MANAGEMENT COMPANY
Operator Address:	7801 N LAMAR BLVD STE C51
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4594929
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17421040555
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MEYERS MANAGEMENT COMPANY
Owner Mailing Address:	7801 N LAMAR BLVD STE C51
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4594929
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17421040555
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	7801 N LAMAR BLVD STE C51
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4594929
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	7801 N LAMAR BLVD STE C51
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4594929
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	TERRY MEYERS
Contact Title:	PRESIDENT
Contact Role:	PRICONT
Contact Address:	7801 N LAMAR BLVD STE C51
Contact Address 2:	STE C51

ACCUGRAPHICS (Continued) **S102749700**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4594929
Contact Fax:	Not reported
Contact Email:	Not reported

MX2617 **REBECCA A. HEARN** **TX HIST UST** **S111678787**
ESE **200 E 18TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
452 ft. **Site 2 of 2 in cluster MX**

Actual:
510 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	REBECCA A. HEARN
Address:	200 E 18TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0343
HID UST:	343
Inspection:	Not reported
Due:	06/01/2012

MM2618 **JOHNSON TIRE COMP.** **TX HIST UST** **S111678710**
WNW **210 W 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
452 ft. **Site 2 of 2 in cluster MM**

Actual:
517 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JOHNSON TIRE COMP.
Address:	210 W 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0033
HID UST:	33
Inspection:	Not reported
Due:	06/01/2012

OR2619 **PECAN FOOD MART** **TX LPST** **U003421920**
WNW **2101 S 1ST ST** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78704** **TX HIST UST**
0.086 mi. **TX ASBESTOS**
453 ft. **Site 2 of 4 in cluster OR** **TX Financial Assurance**
TX GCC
TX RDR

Actual:
532 ft.

Focus Map:
14

LPST:

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	120452
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN

PECAN FOOD MART (Continued) **U003421920**

Region City:	Not reported
Discovered Date:	01/26/2018
Entered Date:	04/12/2018
Reported Date:	02/15/2018
Closure Date:	08/24/2018
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT500FT
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	02/15/2018
Case Start Date:	08/24/2018
Reference Number:	RN101382018
Project Manager:	DCRAWFOR

UST:

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 787045152
AI Number:	27721
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	175420552002154
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	MUBASHIR ANWER,MANAGER
Contact Organization Name:	PECAN FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124427741
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/26/2018
Signature Name/Title On Earliest Reg Form:	RAMESH PATEL,PRES
Application Received Date On Earliest Reg Form:	02/27/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

PECAN FOOD MART (Continued) **U003421920**

Operator:

Princ ID:	628360462002026
Additional ID:	175420552002154
Ai Number:	27721
Operator CN:	CN600733281
Operator Name:	AMBICA CORPORATION
Operator Effective Begin Date:	01/15/2015
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	MOHAMMAD OVIAS/
Contact Organization Name:	AMBICA CORPORATION
Contact Mailing Address (Delivery):	2101 S 1ST ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-5152
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4427741
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600733281
Owner Last Name:	AMBICA CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	2101 S 1ST ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	5152
Contact Phone Number/Ext:	1 512 4427741/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	628360462002026
Additional ID:	175420552002154
AI Number:	27721
Owner Effective Begin Date:	01/15/2015
State Tax ID:	32020484211
Contact Role:	OWNOPRCON
Contact Name/Title:	MOHAMMAD OVIAS/
Contact Organization Name:	AMBICA CORPORATION

Self Certification:

Self Cert ID:	91702
Cert ID:	285752
AI Number:	27721
Self Certification Date:	04/26/2017

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	MUBASHIR ANWER MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91702
Cert ID:	268403
AI Number:	27721
Self Certification Date:	03/26/2016
Signature Name/Title:	BOUCHAIB CHEMACHI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91702
Cert ID:	252276
AI Number:	27721
Self Certification Date:	04/12/2015
Signature Name/Title:	BOUCHAIB CHEMACHI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91702
Cert ID:	246807
AI Number:	27721
Self Certification Date:	01/15/2015

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	BOUCHAIB CHEMACHI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91702
Cert ID:	235486
AI Number:	27721
Self Certification Date:	03/31/2014
Signature Name/Title:	BOUCHAIB CHEMACHI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	91702
Cert ID:	147843
AI Number:	27721
Self Certification Date:	03/05/2013
Signature Name/Title:	MOHAMMAD OVAIS OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	91702
Cert ID:	147842
AI Number:	27721
Self Certification Date:	03/15/2012

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	MOHAMMAD OVAIS OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147841
AI Number:	27721
Self Certification Date:	03/28/2011
Signature Name/Title:	MOHAMMAD OVAIS OPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147840
AI Number:	27721
Self Certification Date:	03/24/2010
Signature Name/Title:	MOHAMMAD OVAIS OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147839
AI Number:	27721
Self Certification Date:	03/18/2009

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	MOHAMMAD OVIAS OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147838
AI Number:	27721
Self Certification Date:	08/15/2008
Signature Name/Title:	MOHAMMAD OVAIS OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147837
AI Number:	27721
Self Certification Date:	04/29/2005
Signature Name/Title:	MICHAEL MEMON PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	91702
Cert ID:	147836
AI Number:	27721
Self Certification Date:	08/21/2004

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	JOSE OVIAS MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	91702
Cert ID:	147835
AI Number:	27721
Self Certification Date:	04/29/2003
Signature Name/Title:	MICHAEL MEMON OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	91702
Cert ID:	147834
AI Number:	27721
Self Certification Date:	04/28/2003
Signature Name/Title:	MICHAEL MEMON OFFICER
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	91702
Cert ID:	147833
AI Number:	27721
Self Certification Date:	04/26/2002

PECAN FOOD MART (Continued) **U003421920**

Signature Name/Title:	MICHAEL MEMON MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	91702
Cert ID:	147580
AI Number:	27721
Self Certification Date:	02/17/2001
Signature Name/Title:	RABIA MEMON MGR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	72548
Facility ID:	91702
Ai Number:	27721
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/11/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

PECAN FOOD MART (Continued) **U003421920**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	09/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	144745
UST ID:	72548
AI Number:	27721
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

PECAN FOOD MART (Continued) **U003421920**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	10510
Cert ID:	41792
UST Comprt ID:	122618
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41787
UST Comprt ID:	122625
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41791
UST Comprt ID:	122619
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41788
UST Comprt ID:	122622
UST ID:	35272
AI Number:	27721
Tank ID:	3

PECAN FOOD MART (Continued) **U003421920**

Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41789
UST Comprt ID:	122621
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41786
UST Comprt ID:	122624
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41785
UST Comprt ID:	122623
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41793
UST Comprt ID:	122617
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41794
UST Comprt ID:	122616
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41790
UST Comprt ID:	122620
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N

PECAN FOOD MART (Continued) **U003421920**

Pipe Type:	P
UST ID:	72550
Facility ID:	91702
Ai Number:	27721
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/11/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	09/27/1990

PECAN FOOD MART (Continued) **U003421920**

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	144747
UST ID:	72550
AI Number:	27721
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	10510
Cert ID:	41792
UST Comprt ID:	122618
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41787
UST Comprt ID:	122625
UST ID:	35272

PECAN FOOD MART (Continued) **U003421920**

AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41791
UST Comprt ID:	122619
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41788
UST Comprt ID:	122622
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41789
UST Comprt ID:	122621
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41786
UST Comprt ID:	122624
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41785
UST Comprt ID:	122623
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41793
UST Comprt ID:	122617
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41794
UST Comprt ID:	122616
UST ID:	35272
AI Number:	27721

PECAN FOOD MART (Continued) **U003421920**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41790
UST Comprt ID:	122620
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	72549
Facility ID:	91702
Ai Number:	27721
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/11/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N

PECAN FOOD MART (Continued) **U003421920**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	09/27/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	144746
UST ID:	72549
AI Number:	27721
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

PECAN FOOD MART (Continued) **U003421920**

Stage I Vapor Recovery: TWO POINT SYSTEM
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 10510
Cert ID: 41792
UST Comprt ID: 122618
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41787
UST Comprt ID: 122625
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41791
UST Comprt ID: 122619
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41788
UST Comprt ID: 122622
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41789
UST Comprt ID: 122621
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41786
UST Comprt ID: 122624
UST ID: 35272
AI Number: 27721
Tank ID: 3
Compartment ID: A

Self Cert ID: 10510
Cert ID: 41785
UST Comprt ID: 122623
UST ID: 35272
AI Number: 27721

PECAN FOOD MART (Continued) **U003421920**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41793
UST Comprt ID:	122617
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41794
UST Comprt ID:	122616
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A
Self Cert ID:	10510
Cert ID:	41790
UST Comprt ID:	122620
UST ID:	35272
AI Number:	27721
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	32310
Facility ID:	91702
AI Number:	27721
Application Received Date:	12/12/2017
Scheduled Construction Date:	01/02/2018
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	12/12/2017
Signature Date On Form:	12/12/2017
Signature Name On Form:	CAROLYN NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	AMBICA CORPORATION
Owner CN At Time Of Construction:	CN600733281
Owner AR At Time Of Construction:	36594
General Desc Of Prop Construct:	REMOVE 3 TANKS (ONE 8K AND TWO 4K) AND ALL PRODUCT LINES- REQUEST 30

PECAN FOOD MART (Continued) **U003421920**

DAY WAIVER

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	76376
UST ID:	Not reported
NOC ID:	32310
AI Number:	27721
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C & J PETROLEUM
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE
Mailing State:	TX
Mailing Zip:	76503
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7219938
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	888
Fax Number:	5631656
Email Address:	Not reported

Cont/Cons/Installer ID:	76375
UST ID:	Not reported
NOC ID:	32310
AI Number:	27721
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	NADEAU CHUCK
Representative Name:	Not reported
Mailing Address (Delivery):	150 PR 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	5840408
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	chuck@cjpetro.com

Facility Billing Contacts:

Contact Organization Name:	AMBICA CORPORATION
Contact Mailing Address (Delivery):	2101 S 1ST ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5152

PECAN FOOD MART (Continued) **U003421920**

Phone Number/Ext:	512 4427741/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	91702
Additional ID:	175420552002154
Princ ID:	628360462002026
AI Number:	27721
Facility Name:	PECAN FOOD MART
AR Number:	36594
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	MOHAMMAD OVIAS/

HIST UST AUSTIN:

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	1269
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	BLIND SIDE TATTOO
Address:	2101 S 1ST STREET
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	01/30/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	1
Travel Time:	0.1
Mileage:	1.9
Reg:	07
Init:	RC
Seq:	02
Facility Type:	Tattooing
Inspector Name:	Rudolphe Cherenfant
Date Report Received:	02/06/2014
Date Routed by Supervisor:	02/10/2014
Date Routed to PSQA:	02/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

PECAN FOOD MART (Continued) **U003421920**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/27/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.1
Reg:	07
Init:	EJ

PECAN FOOD MART (Continued) **U003421920**

Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/13/2013

PECAN FOOD MART (Continued) **U003421920**

Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/18/2013
Date Routed by Supervisor:	03/18/2013
Date Routed to PSQA:	03/18/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

PECAN FOOD MART (Continued) **U003421920**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	178570
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/15/2017
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68694102
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/15/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	160138
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/15/2016
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68694101
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/15/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

PECAN FOOD MART (Continued) **U003421920**

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	143427
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/15/2015
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP686941
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/15/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	126606
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/15/2014
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	3641309 01
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/15/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	9885
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

PECAN FOOD MART (Continued) **U003421920**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/15/2013
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641309
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	74436
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/06/2011
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP213219
Coverage Amount:	1000000
Coverage Expiration Date:	10/06/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	74437
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/25/2010
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614

PECAN FOOD MART (Continued) **U003421920**

Policy Number:	PP213218
Coverage Amount:	1000000
Coverage Expiration Date:	07/25/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	74438
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/25/2009
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP213218
Coverage Amount:	1000000
Coverage Expiration Date:	07/25/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	74439
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/25/2009
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP209935
Coverage Amount:	1000000
Coverage Expiration Date:	07/25/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704

PECAN FOOD MART (Continued) **U003421920**

Region:	2
Facility ID:	91702
Finass ID:	74440
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/25/2008
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP209935
Coverage Amount:	1000000
Coverage Expiration Date:	07/25/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	91702
Finass ID:	74441
AI:	27721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	02/27/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	120452
Contamination Description:	UNKNOWN
Date Of Earliest Known Contamination Confirmation:	2/15/2018
Enforcement Status - Level Of Agency Response:	-
Enforcement Status - Site Activity Status:	2/L2 -
Data Quality 1:	E,Q

PECAN FOOD MART (Continued) **U003421920**

Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

RDR:

RDR ID:	25428
Facility ID:	27721
RN:	Not reported
CN:	Not reported
Name:	PECAN FOOD MART
Address:	2101 S 1ST ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/15/2018
Due Date:	4/16/2018
Tank Owner:	AMBICA PARTNERS CORP
Contact Person:	RAMESH PATEL
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	4/12/2018
Project Manager:	Denise Crawford
Team:	Team 2
New LPST Number:	120452
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

OR2620 **CURTS OIL CO INC** **EDR Hist Auto** **1021215697**
WNW **2101 S FIRST** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.086 mi.
453 ft. **Site 3 of 4 in cluster OR**

Actual:
532 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1973	CURTS OIL CO INC	Gasoline Service Stations
1974	CURTS OIL CO INC	Gasoline Service Stations
1975	CURTS OIL CO INC	Gasoline Service Stations
1976	CURTS OIL CO INC	Gasoline Service Stations
1977	CURTS OIL CO INC	Gasoline Service Stations

PF2621 **7 ELEVEN STORE 35069** **TX RDR** **S127538361**
ESE **6607 CIRCLE S RD** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
454 ft. **Site 1 of 3 in cluster PF**

Actual:
657 ft.

Focus Map:
17

RDR:

RDR ID:	19125
Facility ID:	70378
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 35069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/21/2012
Due Date:	11/20/2012
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	10/18/2012
Project Manager:	Stacey Dunahoo
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	1ST SUB PPC; RTN LT PPC 10/21/10
Review Coordinator:	SJD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	10/18/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

PF2622 **7-ELEVEN 39069** **TX UST** **U004144055**
ESE **6607 CIRCLE S RD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX ASBESTOS**
0.086 mi. **TX Financial Assurance**
454 ft. **Site 2 of 3 in cluster PF** **TX CENTRAL REGISTRY**

Actual:
657 ft.

Focus Map:
17

UST:

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 787454505
AI Number:	70378
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	219033542002139
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	PEGGIE BETZ,GAS & ENV COMP SPEC

7-ELEVEN 39069 (Continued) **U004144055**

Contact Organization Name:	7-ELEVEN 39069
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/27/1998
Signature Name/Title On Earliest Reg Form:	MAX MCBRAYER,VP
Application Received Date On Earliest Reg Form:	01/30/1998
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	219033542002139
Ai Number:	70378
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/01/2009
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com

7-ELEVEN 39069 (Continued) **U004144055**

Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	219033542002139
AI Number:	70378
Owner Effective Begin Date:	07/01/2009
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	106940
Cert ID:	382178
AI Number:	70378
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106940
Cert ID:	364862
AI Number:	70378
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	106940
Cert ID:	347971
AI Number:	70378
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	331013
AI Number:	70378
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	314183
AI Number:	70378
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	296069
AI Number:	70378
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	280543
AI Number:	70378
Self Certification Date:	01/18/2017
Signature Name/Title:	Raymond Mcniece Enironmental Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	263440
AI Number:	70378
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	247407
AI Number:	70378
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	229525
AI Number:	70378
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	106940
Cert ID:	183185
AI Number:	70378
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183184
AI Number:	70378
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106940
Cert ID:	183183
AI Number:	70378
Self Certification Date:	02/11/2011
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106940
Cert ID:	183182
AI Number:	70378
Self Certification Date:	01/21/2010
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106940
Cert ID:	183181
AI Number:	70378
Self Certification Date:	07/01/2009
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183180
AI Number:	70378
Self Certification Date:	02/03/2009
Signature Name/Title:	RONNIE MICHAELS DM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183179
AI Number:	70378
Self Certification Date:	03/14/2008
Signature Name/Title:	RONNIE MICHAELS DM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183178
AI Number:	70378
Self Certification Date:	03/31/2007
Signature Name/Title:	KATHLEEN WRIGHT DIST MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183177
AI Number:	70378
Self Certification Date:	04/27/2006
Signature Name/Title:	KATHLEEN WRAIGHT DIST SUP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183176
AI Number:	70378
Self Certification Date:	09/02/2005
Signature Name/Title:	JAY SEEWALD PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183175
AI Number:	70378
Self Certification Date:	01/17/2005
Signature Name/Title:	LISA A CIOTOLI DIRECTOR OF ENVIRON
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183174
AI Number:	70378
Self Certification Date:	01/08/2004
Signature Name/Title:	LISA A CIOTOLI DIRECTOR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183173
AI Number:	70378
Self Certification Date:	11/29/2002
Signature Name/Title:	MAX MCBRAYER JR VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	106940
Cert ID:	183172
AI Number:	70378
Self Certification Date:	12/11/2001
Signature Name/Title:	MAX MCBRAYER JR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	106940
Cert ID:	183171
AI Number:	70378
Self Certification Date:	12/01/2000
Signature Name/Title:	MAX MCBRAYER JR VP
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/15/1998
Tank Registration Date:	01/30/1998
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	185633
Facility ID:	106940
Ai Number:	70378
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/15/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

7-ELEVEN 39069 (Continued) **U004144055**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	01/16/1998

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	166400
UST ID:	185633
AI Number:	70378
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

7-ELEVEN 39069 (Continued) **U004144055**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/15/1998
Tank Registration Date:	01/30/1998
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	185635
Facility ID:	106940
Ai Number:	70378
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/15/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

7-ELEVEN 39069 (Continued) **U004144055**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/16/1998

Compartment Records:

Tank ID:	1
Tank Capacity:	15000
UST Comprt ID:	166402
UST ID:	185635
AI Number:	70378
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

7-ELEVEN 39069 (Continued) **U004144055**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/15/1998
Tank Registration Date:	01/30/1998
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	185634
Facility ID:	106940
Ai Number:	70378
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/15/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y

7-ELEVEN 39069 (Continued) **U004144055**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/16/1998

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	166401
UST ID:	185634
AI Number:	70378
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	27566
Facility ID:	106940
AI Number:	70378
Application Received Date:	05/07/2015
Scheduled Construction Date:	05/07/2015
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	05/07/2015
Signature Date On Form:	04/27/2015
Signature Name On Form:	NATE LAWSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	DISPENSER UPGRADE:CONVERT PUL TANK TO DSL TANK BY DEMANIFOLDING EXISTING VENTS AND RUNNING NEW VENT LINE TO SERVE DSL.

NOC ID:	18607
Facility ID:	106940
AI Number:	70378
Application Received Date:	09/10/2009
Scheduled Construction Date:	10/10/2009
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90910011
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	05/07/2015

7-ELEVEN 39069 (Continued) **U004144055**

Signature Date On Form:	04/27/2015
Signature Name On Form:	NATE LAWSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	64721
UST ID:	Not reported
NOC ID:	27566
AI Number:	70378
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C B & I
Representative Name:	KIM TAPIA
Mailing Address (Delivery):	12005 FORD RD STE 600
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	32322
UST ID:	185634
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001204
Company Name:	DNB Enterprises
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Email Address:	Not reported
Cont/Cons/Installer ID:	32321
UST ID:	185633
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001204
Company Name:	DNB Enterprises
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	32323
UST ID:	185635
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001204
Company Name:	DNB Enterprises
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	64722
UST ID:	Not reported
NOC ID:	27566
AI Number:	70378
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC

7-ELEVEN 39069 (Continued) **U004144055**

Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	Not reported
Cont/Cons/Installer ID:	19942
UST ID:	Not reported
NOC ID:	18607
AI Number:	70378
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	47487
UST ID:	185635
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000181
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	47485
UST ID:	185633
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000181
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	47486
UST ID:	185634
NOC ID:	Not reported
AI Number:	70378
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000181
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	106940
Additional ID:	219033542002139
Princ ID:	959578622001257
AI Number:	70378
Facility Name:	7-ELEVEN 39069
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN STORE #39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX
Id UST:	3215
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	01/31/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/05/2013
Date Routed by Supervisor:	02/06/2013
Date Routed to PSQA:	02/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	7-ELEVEN
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/21/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Time Spent:	0.5
Travel Time:	0.1
Mileage:	2
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

TX Financial Assurance 2:

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	279303
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	262160
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	242220
AI:	70378
Mechanism Type Other:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	224692
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	207889
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO

7-ELEVEN 39069 (Continued) **U004144055**

Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	189201
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	173419
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD

7-ELEVEN 39069 (Continued) **U004144055**

City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	154693
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	138209
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	118393
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	118348
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	120721
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000

7-ELEVEN 39069 (Continued) **U004144055**

Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	16138
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91818
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940

7-ELEVEN 39069 (Continued) **U004144055**

Finass ID:	91819
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91821
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G2379486A 004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91820
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN 39069 (Continued) **U004144055**

Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91822
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/06/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USC9416984-03
Coverage Amount:	1000000
Coverage Expiration Date:	09/06/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91823
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/06/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	USC9416984-02
Coverage Amount:	1000000
Coverage Expiration Date:	09/06/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 39069 (Continued) **U004144055**

Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	106940
Finass ID:	91824
AI:	70378
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

CENTRAL REGISTRY:

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE

7-ELEVEN 39069 (Continued) **U004144055**

Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

7-ELEVEN 39069 (Continued) **U004144055**

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD

7-ELEVEN 39069 (Continued) **U004144055**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN600505283
Customer Name:	RACETRAC INC
Customer Legal Name:	Racetrac, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1987-08-31
Affiliation End Date:	2005-09-05
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN602934143
Customer Name:	6607 INC
Customer Legal Name:	6607, INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2005-09-06
Affiliation End Date:	2009-06-30
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102253127
Name:	7-ELEVEN 39069
Address:	6607 CIRCLE S RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4505
Status:	ACTIVE
Status Date:	2002-05-19
Customer Number:	CN602934143
Customer Name:	6607 INC
Customer Legal Name:	6607, INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2005-09-06
Affiliation End Date:	2009-06-30
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
34 additional TX CENTRAL REG: record(s) in the EDR Site Report.

PF2623 ESE < 1/8 0.086 mi. 454 ft. — **RACETRAC PETROLEUM INC**, **6607 CIRCLE S RD**, **AUSTIN, TX 78745** — **EDR Hist Auto** — **1021702277** / **N/A**

Site 3 of 3 in cluster PF

Actual: 657 ft.

Focus Map: 17

EDR Hist Auto

Year:	Name:	Type:
1999	RACETRAC PETROLEUM INC	Gasoline Service Stations
2000	RACETRAC PETROLEUM INC	Gasoline Service Stations
2001	RACETRAC PETROLEUM INC	Gasoline Service Stations
2002	RACETRAC PETROLEUM INC	Gasoline Service Stations
2003	RACETRAC PETROLEUM INC	Gasoline Service Stations
2004	RACETRAC PETROLEUM INC	Gasoline Service Stations
2005	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC

PA2624 West < 1/8 0.086 mi. 454 ft. — **CHOTE'S SERVICE CO.**, **500 W MARTIN LUTHER KING BLVD**, **AUSTIN, TX** — **TX HIST UST** — **S128728612** / **N/A**

Site 2 of 10 in cluster PA

Actual: 556 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	CHOTE'S SERVICE CO.
Address:	500 W MARTIN LUTHER KING BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	144
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PA2625 West < 1/8 0.086 mi. 454 ft. — **FORMER CHOTES CHEVRON**, **500 W MARTIN LUTHER KING JR BLVD**, **AUSTIN, TX 78701** — **TX LPST** — **S116701085** / **N/A**

Site 3 of 10 in cluster PA

Actual: 556 ft.

Focus Map: 11

LPST:

Name:	FORMER CHOTES CHEVRON
Address:	500 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0014803
LPST Id:	117820
Facility Location:	500 W M L K BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/17/2008
Entered Date:	08/27/2008
Reported Date:	04/21/2008
Closure Date:	07/03/2009
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P

FORMER CHOTES CHEVRON (Continued) **S116701085**

Coordinators RPR:	DB2
Responsible Party Name:	Not reported
Responsible Party Contact:	RANDY HAGMAN
Responsible Party Address:	1600 CONGRESS AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/554-7154
Reported Date:	04/21/2008
Case Start Date:	07/03/2009
Reference Number:	RN101494763
Project Manager:	DBRATBER

PA2626 **FORMER CHOTES CHEVRON** **TX RDR** **S127525066**
West **500 W MARTIN LUTHER KING** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
454 ft. **Site 4 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

RDR:

RDR ID:	17466
Facility ID:	14803
RN:	Not reported
CN:	Not reported
Name:	FORMER CHOTES CHEVRON
Address:	500 W MARTIN LUTHER KING
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/9/2008
Due Date:	9/7/2008
Tank Owner:	CATHOLIC DIOCESE OF AUSTI
Contact Person:	RANDY HAGMAN
Report:	REL DET
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	8/27/2008
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	117820
Pre-Existing LPST Number:	Not reported
Comments:	THE REST OF THE TANKS ALREADY RECEIVED A CLEAN CLOSURE -SEE YELLOW TAB.;LADSCREEN SENT 9/5/2008
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

PA2627 **CHOTES CHEVRON** **TX UST** **U001250189**
West **500 W MARTIN LUTHER KING JR BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.086 mi.
454 ft. **Site 5 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

UST:

Name:	CHOTES CHEVRON
Address:	500 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 787011261
AI Number:	14803
Facility Type:	RETAIL
Facility Begin Date:	08/13/1986
Facility Status:	INACTIVE
Additional ID:	409665082002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	CHOTES CHEVRON
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124783282
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/28/1986
Signature Name/Title On Earliest Reg Form:	R CHOTE,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600261697
Owner Last Name:	CHOTE SERVICE COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	70290802001297
Additional ID:	409665082002053

CHOTES CHEVRON (Continued) **U001250189**

AI Number:	14803
Owner Effective Begin Date:	08/13/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	37996
Facility ID:	53664
Ai Number:	14803
Tank Id:	SUPER
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/25/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

CHOTES CHEVRON (Continued) **U001250189**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	SUPER
Tank Capacity:	5000
UST Comprt ID:	46566
UST ID:	37996
AI Number:	14803
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	37999
Facility ID:	53664
Ai Number:	14803
Tank Id:	WASTEOIL
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/25/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CHOTES CHEVRON (Continued) **U001250189**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	WASTEOIL
Tank Capacity:	0
UST Comprt ID:	46569
UST ID:	37999
AI Number:	14803
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	37998

CHOTES CHEVRON (Continued) **U001250189**

Facility ID:	53664
Ai Number:	14803
Tank Id:	GOOD
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/25/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	GOOD
Tank Capacity:	4000

CHOTES CHEVRON (Continued) **U001250189**

UST Comprt ID:	46568
UST ID:	37998
AI Number:	14803
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	37997
Facility ID:	53664
Ai Number:	14803
Tank Id:	CREST
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/25/2000
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	CREST
Tank Capacity:	8000
UST Comprt ID:	46567
UST ID:	37997
AI Number:	14803
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

CHOTES CHEVRON (Continued) **U001250189**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	4165
Facility ID:	53664
AI Number:	14803
Application Received Date:	05/18/2000
Scheduled Construction Date:	06/17/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00518009
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	7206
General Desc Of Prop Construct:	Not reported

NOC ID:	4164
Facility ID:	53664
AI Number:	14803
Application Received Date:	05/14/2008
Scheduled Construction Date:	05/15/2008
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M80514010
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	7206
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	4507
UST ID:	Not reported
NOC ID:	4164
AI Number:	14803
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000209
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	4508
UST ID:	Not reported
NOC ID:	4165
AI Number:	14803
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000068
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CHOTE SERVICE COMPANY
Contact Mailing Address (Delivery):	PO BOX 301810
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 0031
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	53664
Additional ID:	409665082002053
Princ ID:	70290802001297
AI Number:	14803
Facility Name:	CHOTES CHEVRON
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ROBERT CHOATE/

Ind. Haz Waste:

Name:	CHOTE SERVICE
Address:	500 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72409
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Primary NAICS Code:	Not reported
Status Change Date:	19870501
Land Type:	Not reported
Description of Facility Site Location:	500 W Martin Luther King Jr Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CHOTE SERVICE COMPANY
Contact Name:	ROBERT CHOTE
Contact Telephone Number:	512-4529843
Mailing Address:	500 W MARTIN LUTHER KING JR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787011261
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26850
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CHOTE SERVICE COMPANY
Operator Address:	500 W MARTIN LUTHER KING JR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4529843
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

CHOTES CHEVRON (Continued) **U001250189**

Ind. Haz Waste:

Owner Name:	CHOTE SERVICE COMPANY
Owner Mailing Address:	500 W MARTIN LUTHER KING JR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4529843
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	500 W MARTIN LUTHER KING JR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4529843
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	500 W MARTIN LUTHER KING JR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4529843
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ROBERT CHOTE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	500 W MARTIN LUTHER KING JR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4529843
Contact Fax:	Not reported
Contact Email:	Not reported

PA2628 **LASSBURG & SCHMEDES** **TX HIST UST** **S128729250**
West **500 W MARTIN LUTHER KING JR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
454 ft. **Site 6 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	LASSBURG & SCHMEDES
Address:	500 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0357
HID UST:	357
Inspection:	Not reported
Due:	06/01/2012

PA2629 **CHOTES CHEVRON** **TX RDR** **S127525065**
West **500 W MARTIN LUTHER KING** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
454 ft. **Site 7 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

RDR:

RDR ID:	795
Facility ID:	14803
RN:	Not reported
CN:	Not reported
Name:	CHOTES CHEVRON
Address:	500 W MARTIN LUTHER KING
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/27/2000
Due Date:	8/26/2000
Tank Owner:	CHOTES SERVICE CO
Contact Person:	ROBERT CHOTE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/30/2000
Project Manager:	Michelle Sefcik
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RTND: LAB REPORTS NOT SIGNED
Review Coordinator:	MDS, CGN
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/30/2000
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

PA2630 **CATHYS CLEANERS MLK** **TX DRYCLEANERS** **S117667203**
West **500 W MARTIN LUTHER KING JR BLVD STE B** **TX ENF** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.086 mi.
454 ft. **Site 8 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

DRYCLEANERS:

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN107247181
Region:	REGION 11 - AUSTIN
CN Number:	CN604567529
DCR Number:	DCR15787
AR Number:	24007052
Principal Name:	CATHYS CLEANERS MLK LLC
Bill Addr1:	500 W MARTIN LUTHER KING JR BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 1262
EMail:	MIA@CATHYSCLEANERS.NET
Phone Number:	512 4748887
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN107247181
Region:	REGION 11 - AUSTIN
CN Number:	CN604567529
DCR Number:	DCR15787
AR Number:	24007052
Principal Name:	CATHY S CLEANERS MLK LLC
Bill Addr1:	500 W MARTIN LUTHER KING JR BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 1262
EMail:	MIA@CATHYSCLEANERS.NET
Phone Number:	512 4748887
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN107247181
Region:	REGION 11 - AUSTIN
CN Number:	CN604567529

CATHYS CLEANERS MLK (Continued) **S117667203**

DCR Number:	DCR15787
AR Number:	24007052
Principal Name:	CATHYS CLEANERS MLK LLC
Bill Addr1:	500 W MARTIN LUTHER KING JR BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 1262
EMail:	MIA@CATHYSCLEANERS.NET
Phone Number:	512 4748887
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN107247181
Region:	REGION 11 - AUSTIN
CN Number:	CN604567529
DCR Number:	DCR15787
AR Number:	24007052
Principal Name:	CATHYS CLEANERS MLK LLC
Bill Addr1:	500 W MARTIN LUTHER KING JR BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 1262
EMail:	MIA@CATHYSCLEANERS.NET
Phone Number:	512 4748887
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN107247181
Region:	REGION 11 - AUSTIN
CN Number:	CN604567529
DCR Number:	DCR15787
AR Number:	24007052
Principal Name:	CATHYS CLEANERS MLK LLC
Bill Addr1:	500 W MARTIN LUTHER KING JR BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 1262
EMail:	MIA@CATHYSCLEANERS.NET
Phone Number:	512 4748887
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE

CATHYS CLEANERS MLK (Continued) **S117667203**

Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

ENFORCEMENT:

Name:	CATHYS CLEANERS MLK
Address:	500 W MARTIN LUTHER KING JR BLVD STE B
City,State,Zip:	AUSTIN, TX 78701-1262
Unique TCEQ Ref Number Of Customer:	CN604567529
Unique TCEQ Ref Number Of Reg. Entity:	RN107247181
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	CATHYS CLEANERS MLK LLC
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	000000001625120
Status Code:	ACTIVE
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	998,627,092,020,029.00
Role Code:	Not reported
Date Notice Of Violation Issued:	01/29/2020
Description 1:	Failure to submit an annual registration renewal for a dry-cleaning facility or drop station.
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	337.11(e)(3)
Status Of The NOV:	DAPPROVED
Investigation:	1625120
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

PA2631 **CHOTES CHEVRON SERVICE STATION** **EDR Hist Auto** **1013753498**
West **500 MARTIN LUTHER KING JR BLVD W** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.086 mi.
454 ft. **Site 9 of 10 in cluster PA**

Actual:
556 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1978	CHOTES SHELL SERVICE	Gasoline Service Stations
1979	CHOTES SHELL SERVICE	Gasoline Service Stations
1980	CHOTES SHELL SERVICE	Gasoline Service Stations
1982	CHOTES GULF SERVICE	Gasoline Service Stations
1983	CHOTES GULF SERVICE	Gasoline Service Stations
1984	CHOTES GULF SERVICE STATION	GASOLINE STATIONS
1985	CHOTES GULF SERVICE	Gasoline Service Stations
1986	CHOTES GULF SERVICE	Gasoline Service Stations
1990	CHOTES CHEVRON SERVICE STATION	GASOLINE STATIONS
1991	CHOTE SHELL SERVICE	Gasoline Service Stations
1992	CHOTE SHELL SERVICE	Gasoline Service Stations
1993	CHOTE SHELL SERVICE	Gasoline Service Stations
1998	CHOTES SERVICES CO	Gasoline Service Stations

PG2632 **SEAHOLM POWER PLANT** **TX UST** **U004144066**
West **800 W CESAR CHAVEZ ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.086 mi.
454 ft. **Site 1 of 4 in cluster PG**

Actual:
455 ft.

Focus Map:
11

UST:

Name:	SEAHOLM POWER PLANT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 787014008
AI Number:	20546
Facility Type:	Not reported
Facility Begin Date:	09/10/1986
Facility Status:	INACTIVE
Additional ID:	650721302002325
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	TODD SHAW,
Contact Organization Name:	SEAHOLM POWER PLANT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123226267
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/27/1986
Signature Name/Title On Earliest Reg Form:	E EVANS,SUPV OF POWER PLANT
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported

SEAHOLM POWER PLANT (Continued) **U004144066**

Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	650721302002325
AI Number:	20546
Owner Effective Begin Date:	09/10/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	282111
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	52834
Facility ID:	37574
Ai Number:	20546
Tank Id:	SEAHOLMSE
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

SEAHOLM POWER PLANT (Continued) **U004144066**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	Y
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	SEAHOLMSE
Tank Capacity:	Not reported
UST Comprt ID:	314
UST ID:	52834
AI Number:	20546
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

SEAHOLM POWER PLANT (Continued) **U004144066**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7887
Cert ID:	35119
UST Comprt ID:	97010
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	356282
UST Comprt ID:	1036386
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35113
UST Comprt ID:	97016
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35109
UST Comprt ID:	97020
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35118

SEAHOLM POWER PLANT (Continued) **U004144066**

UST Comprt ID:	97011
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35108
UST Comprt ID:	97019
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35111
UST Comprt ID:	97018
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	306718
UST Comprt ID:	887438
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35117
UST Comprt ID:	97012
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	290248
UST Comprt ID:	837867
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35112
UST Comprt ID:	97017
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	272419
UST Comprt ID:	785240

SEAHOLM POWER PLANT (Continued) **U004144066**

UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	339457
UST Comprt ID:	985702
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	255345
UST Comprt ID:	734428
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35116
UST Comprt ID:	97013
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	238117
UST Comprt ID:	683794
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	222587
UST Comprt ID:	638381
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	372918
UST Comprt ID:	1086665
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35115
UST Comprt ID:	97014
UST ID:	39090

SEAHOLM POWER PLANT (Continued) **U004144066**

AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35122
UST Comprt ID:	97007
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	322917
UST Comprt ID:	935819
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35121
UST Comprt ID:	97008
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35114
UST Comprt ID:	97015
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35120
UST Comprt ID:	97009
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35110
UST Comprt ID:	97021
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1953
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	33000

SEAHOLM POWER PLANT (Continued) **U004144066**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	52836
Facility ID:	37574
Ai Number:	20546
Tank Id:	WEST
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y

SEAHOLM POWER PLANT (Continued) **U004144066**

Installation Signature Date:	07/18/1990
Compartment Records:	
Tank ID:	WEST
Tank Capacity:	Not reported
UST Comprt ID:	316
UST ID:	52836
AI Number:	20546
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
More Self Certification:	
Self Cert ID:	7887
Cert ID:	35119
UST Comprt ID:	97010
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	356282
UST Comprt ID:	1036386

SEAHOLM POWER PLANT (Continued) **U004144066**

UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35113
UST Comprt ID:	97016
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35109
UST Comprt ID:	97020
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35118
UST Comprt ID:	97011
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35108
UST Comprt ID:	97019
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35111
UST Comprt ID:	97018
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	306718
UST Comprt ID:	887438
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35117
UST Comprt ID:	97012
UST ID:	39090

SEAHOLM POWER PLANT (Continued) **U004144066**

AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	290248
UST Comprt ID:	837867
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35112
UST Comprt ID:	97017
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	272419
UST Comprt ID:	785240
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	339457
UST Comprt ID:	985702
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	255345
UST Comprt ID:	734428
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35116
UST Comprt ID:	97013
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	238117
UST Comprt ID:	683794
UST ID:	39090
AI Number:	20546

SEAHOLM POWER PLANT (Continued) **U004144066**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	222587
UST Comprt ID:	638381
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	372918
UST Comprt ID:	1086665
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35115
UST Comprt ID:	97014
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35122
UST Comprt ID:	97007
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	322917
UST Comprt ID:	935819
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35121
UST Comprt ID:	97008
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35114
UST Comprt ID:	97015
UST ID:	39090
AI Number:	20546
Tank ID:	3

SEAHOLM POWER PLANT (Continued) **U004144066**

Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35120
UST Comprt ID:	97009
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35110
UST Comprt ID:	97021
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1953
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	33000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	52835
Facility ID:	37574
Ai Number:	20546
Tank Id:	EAST
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/01/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

SEAHOLM POWER PLANT (Continued) **U004144066**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	EAST
Tank Capacity:	Not reported
UST Comprt ID:	315
UST ID:	52835
AI Number:	20546
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

SEAHOLM POWER PLANT (Continued) **U004144066**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7887
Cert ID:	35119
UST Comprt ID:	97010
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	356282
UST Comprt ID:	1036386
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35113
UST Comprt ID:	97016
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35109
UST Comprt ID:	97020
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35118
UST Comprt ID:	97011
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35108
UST Comprt ID:	97019
UST ID:	39090
AI Number:	20546
Tank ID:	3

SEAHOLM POWER PLANT (Continued) **U004144066**

Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35111
UST Comprt ID:	97018
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	306718
UST Comprt ID:	887438
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35117
UST Comprt ID:	97012
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	290248
UST Comprt ID:	837867
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35112
UST Comprt ID:	97017
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	272419
UST Comprt ID:	785240
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	339457
UST Comprt ID:	985702
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

SEAHOLM POWER PLANT (Continued) **U004144066**

Self Cert ID:	7887
Cert ID:	255345
UST Comprt ID:	734428
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	35116
UST Comprt ID:	97013
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	238117
UST Comprt ID:	683794
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	222587
UST Comprt ID:	638381
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	372918
UST Comprt ID:	1086665
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	35115
UST Comprt ID:	97014
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887
Cert ID:	35122
UST Comprt ID:	97007
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Self Cert ID:	7887

SEAHOLM POWER PLANT (Continued) **U004144066**

Cert ID:	322917
UST Comprt ID:	935819
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35121
UST Comprt ID:	97008
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35114
UST Comprt ID:	97015
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35120
UST Comprt ID:	97009
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7887
Cert ID:	35110
UST Comprt ID:	97021
UST ID:	39090
AI Number:	20546
Tank ID:	3
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37574
Additional ID:	650721302002325
Princ ID:	840354562001227
AI Number:	20546
Facility Name:	SEAHOLM POWER PLANT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported

SEAHOLM POWER PLANT (Continued) **U004144066**

Contact Name/Title: /

HIST UST AUSTIN:

Name:	COA SEAHOLM POWER PLANT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	330
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PG2633 **SEAHOLM POWER PLANT** **TX VCP** **S103601463**
West **800 W CESAR CHAVEZ ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX GCC**
0.086 mi. **TX Ind. Haz Waste**
454 ft. **Site 2 of 4 in cluster PG** **TX IHW CORR ACTION**

Actual:
455 ft.

Focus Map:
11

VCP TCEQ:

Name:	CITY OF AUSTIN ELECTRIC UTILITY DEPT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	283
VCP Record Date:	07/01/1996
Facility Type:	EDUCATIONAL SERVICES
PCA Number:	38193
Project Manager:	MFREW
Phase:	COMPLETED
Acres at Site:	9.0
REM Program:	VCP
RN Number:	RN102744109
Former Facility Type:	Not reported
Site Address Description:	800 WEST CESAR CHAVEZ
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	06/27/1996
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	981049745
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	33939
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/16/2004; 01/22/1999
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	EXCAVATION/REMOVAL TO OFF-SITE LANDFILL
Air Target COC Class:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Date Cashier Check Received:	06/27/1996
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1996-08-15 00:00:00
Soil Target COC Class:	PCBS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	283
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	311930
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	212/D
Latitude:	30.27
Longitude:	-97.75

Name:	SEAHOLM SUBSTATION
Address:	800 W CESAR CHAVEZ
City,State,Zip:	AUSTIN, TX 78703
Region:	REGION 11 - AUSTIN
Facility ID:	2324
VCP Record Date:	06/10/2010
Facility Type:	PROPERTY
PCA Number:	78285
Project Manager:	RKYGAR
Phase:	COMPLETED
Acres at Site:	1.3
REM Program:	VCP
RN Number:	RN100217348
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	06/10/2010
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/23/2013
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	Not reported
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Application Accepted?: Not reported
Application Accepted Date: 2010-07-23 00:00:00
Soil Target COC Class: TPH; METALS; SVOCS; PCBS
Surface Water Target COC Class: Not reported
Alternate VCP ID: 2324
Leaking Petroleum Storage Registration Tank: Not reported
Project Number: Not reported
Off Site?: Not reported
Media: ELECTRONIC
IOP Number: Not reported
File Location: CR; D/200-37
Latitude: 0.00
Longitude: 0.00

HIST UST AUSTIN:
Name: 1
Address: 800 W CESAR CHAVEZ ST
City,State,Zip: AUSTIN, TX
Id UST: H0098
HID UST: 98
Inspection: Not reported
Due: 06/01/2012

GCC:
Name: SEAHOLM SUBSTATION
Address: 800 W CESAR CHAVEZ STREET
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: *
File Number: 2324
Contamination Description: HEAVY METALS
Date Of Earliest Known Contamination Confirmation: 7/23/2010
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: SEAHOLM SUBSTATION
Address: 800 W CESAR CHAVEZ STREET
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 2324
Contamination Description: METALS
Date Of Earliest Known Contamination Confirmation: 7/23/2010
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E

SEAHOLM POWER PLANT (Continued) **S103601463**

Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Ind. Haz Waste:

Name:	SEAHOLM POWER PLANT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	33939
Registration Initial Notification Date:	03/15/1984
Registration Last Amendment Date:	03/06/2013
EPA Identification:	TXD981049745
Primary NAICS Code:	221122
Status Change Date:	19840315
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Contact Name:	SURAIYA MURRAY
Contact Telephone Number:	512-3226207
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address2:	ELECTRIC UTILITY DEPARTMENT
Mailing City,State,Zip:	AUSTIN, TX 787041328
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	11409
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Operator Address:	721 BARTON SPRINGS RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	1-512-3226207
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

One-time Shipper ID:	37398
Location Description:	Not reported
Broker Name:	Not reported
Broker Telephone:	Not reported
Date Processing Complete:	20140324
Date Request Sent:	20140320
Company Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Waste ID:	FWG43981
Waste Form Code:	398
Waste Class Code:	1
Waste Origin Code:	2
Site Name:	SEAHOLM POWER PLANT
Location Address:	800 W CESAR CHAVEZ ST
Location City:	AUSTIN
Location Zip:	78701
Site Region Code:	11
EPA Waste Source Code:	G32
EPA ID:	Not reported
EPA System Type Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Land Site Type:	Not reported
EPA Form:	Not reported
Site County Fips:	453
EPA Waste Number:	SOIL
Location County:	TRAVIS
Contact Name or Organization:	CITY OF AUSTIN
Owner Address:	721 BARTON SPRINGS RD
Owner City,State,Zip:	AUSTIN, TX 78704
Owner County Code:	USA
Owner Telephone:	512-322-6205
Owner Fax:	Not reported
Owner NAICS:	221122
Broker Mailing Address:	Not reported
Broker City,State,Zip:	Not reported
Broker Mailing County:	Not reported
Broker Fax:	Not reported
NAICS Code:	Not reported
TWC ID:	361786

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Owner Mailing Address:	721 BARTON SPRINGS RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	1-512-3226207
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	19
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	STEEL REINFORCED CONCRETE
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006

SEAHOLM POWER PLANT (Continued) **S103601463**

Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	20
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	CLAY PIT AT DECKER PLT SITE #33938
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	19
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	CONCRETE
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	004
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	8'X8'X20' STEEL OCEAN CARGO CONTAINER ALSO FROM REG. #'S 32507 & 33938
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	01
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940815
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	01
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940815
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	007
Unit Type Code:	19
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	2-25 FT DIAMETER UNDERGROUND STORAGE TANKS
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940815
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	008
Unit Type Code:	22
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Unit Description:	Dumpster located at north of plant: west dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	009
Unit Type Code:	22
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpster located at north of plant: east dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	010
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Fuels storage building at north side of plant.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Unit Number:	011
Unit Type Code:	18
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Waste oil storage tank at Holly (SWR 32507) near tank 42.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	012
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Container storage area at Holly (SWR 32507) near boiler house.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	013
Unit Type Code:	22
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Temporary storage for excavated soils; NE corner of substation
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20031006
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	014
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Area for temporary roll-offs; behind unit #9 at West end of plant; next to 004
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19950501
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	015
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	2
Capacity Measurement:	T
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141

SEAHOLM POWER PLANT (Continued) **S103601463**

System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Room with controlled access at northwestend of main plant building.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990222
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	016
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	2000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Miscellaneous vacuum box or tank to holdwastewater.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990222
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	017
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	10000
Capacity Measurement:	P
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	temporary enclosed cargo boxes for the storage of decomissioning waste
Unit Description 2:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Unit Description 3:	Not reported
Last Changed Date:	20050906
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	SURAIYA MURRAY
Contact Title:	WASTE PROGRAM COORDINATOR
Contact Role:	PRICONT
Contact Address:	721 BARTON SPRINGS RD
Contact Address 2:	ELECTRIC UTILITY DEPARTMENT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	1-512-3226207
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	97256
Texas Waste Code:	Not reported
Texas Waste Code 2:	10013111
Waste Code Status:	INACTIVE
Waste Form:	311
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Galbestos removed during remodeling, demolition, and/or construction activities.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	97258
Texas Waste Code:	Not reported
Texas Waste Code 2:	10023111
Waste Code Status:	INACTIVE
Waste Form:	311
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos, friable insulation, removed during remodeling, demolition, and/or cons
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	97259
Texas Waste Code:	Not reported
Texas Waste Code 2:	10033112
Waste Code Status:	INACTIVE
Waste Form:	311
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos, non-friable roofing, gaskets or floor tile removed during remodeling,d
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste ID:	97261
Texas Waste Code:	Not reported
Texas Waste Code 2:	10043112
Waste Code Status:	INACTIVE
Waste Form:	311
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos, non-friable transite, removed during remodeling, demolition and/or con
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	136764
Texas Waste Code:	Not reported
Texas Waste Code 2:	10053011
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil & debris from historical spills of dielectric oil, unknown PCB conc.; PCBsi
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85742
Texas Waste Code:	Not reported
Texas Waste Code 2:	1006203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Generators Waste Description:	Solvent, non-halogenated, spent;collected from solvent accumulation areas;usedto
Standard Industrial Code:	49110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85743
Texas Waste Code:	Not reported
Texas Waste Code 2:	1007203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solvent, non-halogenated, spent; collected from parts washer; used to degrease e
Standard Industrial Code:	49110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85745
Texas Waste Code:	Not reported
Texas Waste Code 2:	1008204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Solvent-halogenated & non-halogenated; collected from satellite accumulation are
Standard Industrial Code:	49110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	142635
Texas Waste Code:	Not reported
Texas Waste Code 2:	1009319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint debris; paint not chemically removed, not sandblasted; Change to ruleor po
Standard Industrial Code:	49110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	108187
Texas Waste Code:	Not reported
Texas Waste Code 2:	1012211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Generators Waste Description:	Paint solvents and paints; generated when petroleum distillates are used toclean
Standard Industrial Code:	49110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161398
Texas Waste Code:	Not reported
Texas Waste Code 2:	10201131
Waste Code Status:	INACTIVE
Waste Form:	113
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint, liquid, latex; unused; discarded due to age or condition; 7/97; Dueto was
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	142636
Texas Waste Code:	Not reported
Texas Waste Code 2:	10224891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solids contaminated with oil, no PCBs; generated from wiping equipment andcleanu
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85746
Texas Waste Code:	Not reported
Texas Waste Code 2:	1027117H
Waste Code Status:	INACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury, elemental, liquid; removed from decommissioned and broken equipment; Du
Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85744
Texas Waste Code:	Not reported
Texas Waste Code 2:	1028319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury-contaminated debris; collected from cleanup of mercury spills; Dueto was
Standard Industrial Code:	49110
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319

SEAHOLM POWER PLANT (Continued) **S103601463**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	85752
Texas Waste Code:	Not reported
Texas Waste Code 2:	10304882
Waste Code Status:	INACTIVE
Waste Form:	488
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wood debris, not chemically treated; includes packing material refuse and lumber
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85753
Texas Waste Code:	Not reported
Texas Waste Code 2:	10321192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Water, contaminated by dielectric oil & solids; no PCBs; from secondary containm
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID: 85754

SEAHOLM POWER PLANT (Continued) **S103601463**

Texas Waste Code:	Not reported
Texas Waste Code 2:	10331192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Water, contaminated by dielectric oil & solids; < 50 ppm PCBs; from sec. contain
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	143109
Texas Waste Code:	Not reported
Texas Waste Code 2:	10341191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water contam. by dielectric oil & solids; source >50ppm PCBs; equip. decontam.,s
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	158612
Texas Waste Code:	Not reported
Texas Waste Code 2:	10351191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Water contaminated by dielectric oil w/ <50 ppm PCBs; >= 1500 ppm TPH;

SEAHOLM POWER PLANT (Continued) **S103601463**

	fromequip
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	157413
Texas Waste Code:	Not reported
Texas Waste Code 2:	1040001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Lab pack, unused or old chemicals; Due to waste minimization, ingredient changes
Standard Industrial Code:	49110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	157414
Texas Waste Code:	Not reported
Texas Waste Code 2:	10410011
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Lab pack, unused or old chemicals; Due to waste minimization, ingredient changes
Standard Industrial Code:	Not reported
Primary Source:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	129064
Texas Waste Code:	Not reported
Texas Waste Code 2:	10493092
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Alkaline batteries, spent; generated from replacement in small electrical equipm
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85747
Texas Waste Code:	Not reported
Texas Waste Code 2:	10553882
Waste Code Status:	INACTIVE
Waste Form:	388
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glass containers, empty; generated as a result of using up container contents; D
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Waste ID: 85748
Texas Waste Code: Not reported
Texas Waste Code 2: 10573082
Waste Code Status: INACTIVE
Waste Form: 308
Waste Classification: 2
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Metal containers, empty; generated as a result of using up container contents
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Waste ID: 85749
Texas Waste Code: Not reported
Texas Waste Code 2: 10594062
Waste Code Status: INACTIVE
Waste Form: 406
Waste Classification: 2
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Plastic containers, empty; generated as a result of using up container contents
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Waste ID: 85755
Texas Waste Code: Not reported
Texas Waste Code 2: 10639012
Waste Code Status: INACTIVE

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Form:	901
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Refuse prod. by plant activ: paper, cardboard, linings, wrappings, paper packagi
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85756
Texas Waste Code:	Not reported
Texas Waste Code 2:	10649022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Refuse, class 2, produced as a result of plant operations (but not listed in seq
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85757
Texas Waste Code:	Not reported
Texas Waste Code 2:	10659032
Waste Code Status:	INACTIVE
Waste Form:	903
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Refuse, office prod. from office & food serv. op.: paper, cardboard, plastic, fo
Standard Industrial Code:	Not reported
Primary Source:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85750
Texas Waste Code:	Not reported
Texas Waste Code 2:	10672061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Turbine lubrication oil, spent; w/o PCBs; collected during maintenance activitie
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	85751
Texas Waste Code:	Not reported
Texas Waste Code 2:	10682061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Turbine lubrication oil, spent; w/< 50 ppm PCBs; collected during decommissionin
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Waste ID:	108188
Texas Waste Code:	Not reported
Texas Waste Code 2:	1070103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acid cleaner, spent; used to remove rust and prepare metal surfaces for processe
Standard Industrial Code:	49110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	113072
Texas Waste Code:	Not reported
Texas Waste Code 2:	10711052
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acidic aqueous waste from surface-cleaning; acid-based cleansers used to prepare
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

SEAHOLM POWER PLANT (Continued) **S103601463**

Ind. Haz Waste:

Waste ID:	113073
Texas Waste Code:	Not reported
Texas Waste Code 2:	10721012
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous liquid with traces of organics; generation includes empty drums filled w
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	152816
Texas Waste Code:	Not reported
Texas Waste Code 2:	10733981
Waste Code Status:	INACTIVE
Waste Form:	398
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil & debris contaminated with transformer oil (historic spills), source 50-500
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	117680
Texas Waste Code:	Not reported
Texas Waste Code 2:	10743111
Waste Code Status:	INACTIVE
Waste Form:	311

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos insulation contaminated with oil containing < 50 ppm PCBs from leaks an
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	117681
Texas Waste Code:	Not reported
Texas Waste Code 2:	10754891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint debris; solids w/mineral spirits used to prepare surfaces for painting ort
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	136765
Texas Waste Code:	Not reported
Texas Waste Code 2:	10769992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant trash from facility or offices; paper, cardboard, linings, wrapping,packag
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	159095
Texas Waste Code:	Not reported
Texas Waste Code 2:	1077110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic water treatment solution; EDTA; discarded due to age or condition;4/97;
Standard Industrial Code:	49110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	159096
Texas Waste Code:	Not reported
Texas Waste Code 2:	10781192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Dispersant chemical for water treatment;with polystyrene; discarded due toageor
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	159097
Texas Waste Code:	Not reported
Texas Waste Code 2:	1079609H
Waste Code Status:	INACTIVE
Waste Form:	609
Waste Classification:	H
Waste is Radioactive:	1
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water treatment dispersant slurry; with octadecylamine; discarded due to age orc
Standard Industrial Code:	49110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W609
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	170739
Texas Waste Code:	Not reported
Texas Waste Code 2:	10806031
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	#5 fuel oil sludge, tank bottoms; Due to change(s) in the product produced,this
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste ID:	173349
Texas Waste Code:	Not reported
Texas Waste Code 2:	10814941
Waste Code Status:	INACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Asbestos, friable insulation and debris from decommissioning, contaminated w/=>5
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175002
Texas Waste Code:	Not reported
Texas Waste Code 2:	1082110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Sodium Hydroxide - unused chemical; Due to waste minimization, ingredient change
Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175003
Texas Waste Code:	Not reported
Texas Waste Code 2:	10833191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead Paint Contaminated Debris
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175004
Texas Waste Code:	Not reported
Texas Waste Code 2:	10843192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-hazardous paint removal debris; PPE,Rags & Poly
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175005
Texas Waste Code:	Not reported
Texas Waste Code 2:	1085319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead Paint Removal Waste, some removed by chemical means, calcium hydroxideandso
Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175006
Texas Waste Code:	Not reported
Texas Waste Code 2:	10871191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Water w/ >/= 50ppm <500ppm PCBs, small amount of sediment
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175007
Texas Waste Code:	Not reported
Texas Waste Code 2:	10883981
Waste Code Status:	INACTIVE
Waste Form:	398
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soils contaminated w/ PCBs, source >/= 50ppm, TPH <1500ppm, W/WW Shoal CreekPro
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste ID:	175008
Texas Waste Code:	Not reported
Texas Waste Code 2:	1089319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead paint contaminated debris w/ calcium hydroxide or sodium hydroxidestripper;
Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	175436
Texas Waste Code:	Not reported
Texas Waste Code 2:	10902061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Transformer Oil with >/= 50 to <500 ppm PCBs. Oil was drained from transformers.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175437
Texas Waste Code:	Not reported
Texas Waste Code 2:	10913941
Waste Code Status:	INACTIVE
Waste Form:	394
Waste Classification:	1

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solids contaminated by transformer oil with >/= 50 ppm to <500 ppm PCBs. Genera
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175438
Texas Waste Code:	Not reported
Texas Waste Code 2:	10923961
Waste Code Status:	INACTIVE
Waste Form:	396
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Transformers that had contained transformer oil with >/= 50 ppm to <500 ppmPCBs.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175439
Texas Waste Code:	Not reported
Texas Waste Code 2:	1093119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water with RCRA Metals. Generated during decommissioning of facility.
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175440
Texas Waste Code:	Not reported
Texas Waste Code 2:	10941191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water, non-hazardous from various locations. Being disposed of during decommiss
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175441
Texas Waste Code:	Not reported
Texas Waste Code 2:	1095319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil and debris contaminated with RCRA Metals. Generated during remediationofsit
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Ind. Haz Waste:

Waste ID:	175442
Texas Waste Code:	Not reported
Texas Waste Code 2:	10964891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil and debris from historical transformer spills, no PCBs, >1500 TPH. Generate
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175443
Texas Waste Code:	Not reported
Texas Waste Code 2:	10974892
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soil and debris from historical transformer spills, no PCBs, <1500 TPH. Generate
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175444
Texas Waste Code:	Not reported
Texas Waste Code 2:	10985981
Waste Code Status:	INACTIVE
Waste Form:	598

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sediment and water sludge containing >/= 50 ppm and < 500 ppm PCBs. Generated d
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175445
Texas Waste Code:	Not reported
Texas Waste Code 2:	1099119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sediment and water slurry containing RCRA Metals. Generated during remediationo
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175446
Texas Waste Code:	Not reported
Texas Waste Code 2:	11001191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sediment and water slurry, non-hazardous, unlimited TPH. Generated during remed
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	175447
Texas Waste Code:	Not reported
Texas Waste Code 2:	11011192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sediment and water slurry, non-hazardous, <1500 TPH. Generated during remediati
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	7
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	181575
Texas Waste Code:	Not reported
Texas Waste Code 2:	11021192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water, non-hazardous, <1500 ppm TPH. Seepage or stormwater run-off that has ent
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

SEAHOLM POWER PLANT (Continued) **S103601463**

Ind. Haz Waste:

Waste ID:	183570
Texas Waste Code:	Not reported
Texas Waste Code 2:	11033961
Waste Code Status:	INACTIVE
Waste Form:	396
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB-Contaminated equipment, non-hazardous, >/=50 - <500 ppm PCBs. Generated dur
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	183571
Texas Waste Code:	Not reported
Texas Waste Code 2:	11043192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Equipment, non-hazardous, <1500 ppm TPH; discarded during plant decommissioning.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	183572
Texas Waste Code:	Not reported
Texas Waste Code 2:	11053192
Waste Code Status:	INACTIVE
Waste Form:	319

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Scrap Metal, non-hazardous, <1500 ppm TPH; generated during plant decommissionin
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	183573
Texas Waste Code:	Not reported
Texas Waste Code 2:	11063951
Waste Code Status:	INACTIVE
Waste Form:	395
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB-Contaminated concrete and construction debris, non-hazardous, >/= 500ppm PCB
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	183574
Texas Waste Code:	Not reported
Texas Waste Code 2:	1107319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hazardous concrete and construction debris, contaminated with RCRA metals and/or
Standard Industrial Code:	49110
Primary Source:	G49
Primary Measurement Point:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183575
Texas Waste Code:	Not reported
Texas Waste Code 2:	11084891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oil-contaminated solids, non-hazardous, TPH >/=1500ppm. Generated during plantd
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	183576
Texas Waste Code:	Not reported
Texas Waste Code 2:	11093902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Concrete and construction debris, non-hazardous, <1500ppm TPH. Generated during
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	184594
Texas Waste Code:	Not reported
Texas Waste Code 2:	11103192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater generated from cleaning plant floors and equipment during decommissio
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	184595
Texas Waste Code:	Not reported
Texas Waste Code 2:	11111192
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater generated from cleaning plant floors & equipment during decommissioni
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	185007
Texas Waste Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Texas Waste Code 2:	11123192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Fiberglass Insulation. Generated during decommissioning of the facility.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	185196
Texas Waste Code:	Not reported
Texas Waste Code 2:	11133912
Waste Code Status:	INACTIVE
Waste Form:	391
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PPE, non-hazardous, <1500ppm TPH, not considered TSCA under 40CFR761.61(a)(5)(v)
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	186554
Texas Waste Code:	Not reported
Texas Waste Code 2:	1114319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Decommissioned power plant pumps & equipment; TCLP'ed hazardous for lead-based p

SEAHOLM POWER PLANT (Continued) **S103601463**

Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186945
Texas Waste Code:	Not reported
Texas Waste Code 2:	11153892
Waste Code Status:	INACTIVE
Waste Form:	389
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Sandblast Grit, non-hazardous, generated during removal of paint from decommissi
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	186946
Texas Waste Code:	Not reported
Texas Waste Code 2:	11163891
Waste Code Status:	INACTIVE
Waste Form:	389
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Sandblast grit, non-hazardous, generated during removal of paint from decommissi
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	187067
Texas Waste Code:	Not reported
Texas Waste Code 2:	11172061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Lube oil with 2 - <50ppm PCBs, from decommissioning of facility equipment.;Due t
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	189668
Texas Waste Code:	Not reported
Texas Waste Code 2:	11184891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Pipe and equipment contaminated with >/= 1500 ppm TPH, <50ppm PCBs; generated du
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste ID:	189669
Texas Waste Code:	Not reported
Texas Waste Code 2:	1119319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Mercury-contaminated equipment; generated during facility decommissioning.;Due t
Standard Industrial Code:	49110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	221122
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	190026
Texas Waste Code:	Not reported
Texas Waste Code 2:	11202981
Waste Code Status:	INACTIVE
Waste Form:	298
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Kerosene contaminated with >/= 500ppm PCBs; from chemical extraction of PCBs fro
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	190027
Texas Waste Code:	Not reported
Texas Waste Code 2:	11212981
Waste Code Status:	INACTIVE
Waste Form:	298
Waste Classification:	1

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Hydrogen Peroxide contaminated with >/=500 ppm PCBs from extracting PCBs from co
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	192558
Texas Waste Code:	Not reported
Texas Waste Code 2:	11226031
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Oily sludge from portable water treatment unit; > 1500ppm TPH, no PCBs. One-time
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	194142
Texas Waste Code:	Not reported
Texas Waste Code 2:	11236031
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Oily sludge and concrete debris.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	194298
Texas Waste Code:	Not reported
Texas Waste Code 2:	11243191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Stabilized spent lead paint remover with > 1500ppm TPH.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212536
Texas Waste Code:	Not reported
Texas Waste Code 2:	11253192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint, concrete, w/ free liquid; from decomissioning facility; 5/2/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212537

SEAHOLM POWER PLANT (Continued) **S103601463**

Texas Waste Code:	Not reported
Texas Waste Code 2:	11265981
Waste Code Status:	INACTIVE
Waste Form:	598
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	paint chips and water w/ PCB's >=50 <500 ppm from plant decommissioning; 3/28/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212538
Texas Waste Code:	Not reported
Texas Waste Code 2:	11274941
Waste Code Status:	INACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	paint chips, concrete, and water w/ PCB's >=50 and < 500 PPM; 3/28/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212539
Texas Waste Code:	Not reported
Texas Waste Code 2:	11283192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	concrete, nonhazardous; generated from plant decomissioning, 6/29/05
Standard Industrial Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212540
Texas Waste Code:	Not reported
Texas Waste Code 2:	11293941
Waste Code Status:	INACTIVE
Waste Form:	394
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB contaminated PPE and debris; generated from plant decomissioning 9/8/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212541
Texas Waste Code:	Not reported
Texas Waste Code 2:	11303072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	rust, non-hazardous; mechanically removed 8/30/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	RUST AND BLAST GRIT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Waste ID:	212735
Texas Waste Code:	Not reported
Texas Waste Code 2:	11323192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PPE generated during plant decomissioning 9/27/05
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212982
Texas Waste Code:	Not reported
Texas Waste Code 2:	11334941
Waste Code Status:	INACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent activated carbon, non-hazardous, >50ppm PCBs; from filtering water used to
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	212835
Texas Waste Code:	Not reported
Texas Waste Code 2:	11344941
Waste Code Status:	INACTIVE
Waste Form:	494

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent activated carbon, non-hazardous, >50ppm PCBs; from filtering water used to
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	326454
Texas Waste Code:	Not reported
Texas Waste Code 2:	11364981
Waste Code Status:	INACTIVE
Waste Form:	498
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	soil contaminated with > or equal to 50 ppm and <500 ppm pcbs and friable asbest
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SOIL ASBESTOS PCBS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	OTS

Ind. Haz Waste:

Waste ID:	257450
Texas Waste Code:	Not reported
Texas Waste Code 2:	ACML1191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	260544
Texas Waste Code:	Not reported
Texas Waste Code 2:	C2PC3902
Waste Code Status:	INACTIVE
Waste Form:	390
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262648
Texas Waste Code:	Not reported
Texas Waste Code 2:	C58V4091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	8
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste ID:	262695
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5BJ209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	262696
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5BK103H
Waste Code Status:	INACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	268211
Texas Waste Code:	Not reported
Texas Waste Code 2:	CCYB3192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271666
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ66519H
Waste Code Status:	INACTIVE
Waste Form:	519
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271667
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ673191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Ind. Haz Waste:

Waste ID:	271668
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ683192
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271669
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ69307H
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271670
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ6B307H
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	H
Waste is Radioactive:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271671
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ6C303H
Waste Code Status:	INACTIVE
Waste Form:	303
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271672
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ6D1051
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271673
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJ6F1052
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272111
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJPP209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272112
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJPQ2092
Waste Code Status:	INACTIVE

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Form:	209
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272171
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJRR4891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	273118
Texas Waste Code:	Not reported
Texas Waste Code 2:	CKWW3071
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	273119
Texas Waste Code:	Not reported
Texas Waste Code 2:	CKWX3072
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	273166
Texas Waste Code:	Not reported
Texas Waste Code 2:	CKYJ106H
Waste Code Status:	INACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290672

SEAHOLM POWER PLANT (Continued) **S103601463**

Texas Waste Code:	Not reported
Texas Waste Code 2:	DJQC4941
Waste Code Status:	INACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290673
Texas Waste Code:	Not reported
Texas Waste Code 2:	DJQD4892
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290674
Texas Waste Code:	Not reported
Texas Waste Code 2:	DJQF4881
Waste Code Status:	INACTIVE
Waste Form:	488
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290675
Texas Waste Code:	Not reported
Texas Waste Code 2:	DJQG4941
Waste Code Status:	INACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	290676
Texas Waste Code:	Not reported
Texas Waste Code 2:	DJQH4891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

Ind. Haz Waste:

Waste ID:	298056
Texas Waste Code:	Not reported
Texas Waste Code 2:	DP8L4891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	302887
Texas Waste Code:	Not reported
Texas Waste Code 2:	DT726031
Waste Code Status:	INACTIVE
Waste Form:	603
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	361786
Texas Waste Code:	Not reported
Texas Waste Code 2:	FWG43981
Waste Code Status:	INACTIVE
Waste Form:	398
Waste Classification:	1
Waste is Radioactive:	0

SEAHOLM POWER PLANT (Continued) **S103601463**

Waste Treated Off Site:	Not reported
Generators Waste Description:	SOIL W/PCBS LESS THAN 50PPM PCB TREATED AS TSCA UNDER 40 CFR 761.61 (b)
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000301192
Principal Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78704
AR Number:	0000301192
Principal Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	SEAHOLM POWER PLANT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	33939
Location Desc:	Not reported
RN NUM:	RN100217348
Status:	INACTIVE
Status Date:	07/21/2004
EDR Link ID:	33939
Project Phase:	TRANSFERRED
Phase Status Date:	07/21/2004
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported

SEAHOLM POWER PLANT (Continued) **S103601463**

GW Remediation: Not reported

PG2634 **SEAHOLM POWER PLANT** **RCRA-VSQG** **1000412183**
West **800 W CESAR CHAVEZ ST** **FINDS** **TXD981049745**
< 1/8 **AUSTIN, TX 78703** **ECHO**
0.086 mi.
454 ft. **Site 3 of 4 in cluster PG**

Actual:
455 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20130306
Handler Name:	Seaholm Power Plant
Handler Address:	800 W CESAR CHAVEZ ST
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD981049745
Contact Name:	SURAIYA MURRAY
Contact Address:	721 BARTON SPRINGS RD
Contact City,State,Zip:	AUSTIN, TX 78704-1145
Contact Telephone:	512-322-6207
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	721 BARTON SPRINGS RD
Mailing City,State,Zip:	AUSTIN, TX 78704-1145
Owner Name:	City Of Austin Dba Austin Energy
Owner Type:	Private
Operator Name:	City Of Austin Dba Austin Energy
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

SEAHOLM POWER PLANT (Continued) **1000412183**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D018
Waste Description: Benzene

Waste Code: F003

SEAHOLM POWER PLANT (Continued) **1000412183**

Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status:	Private
Date Became Current:	20051020
Date Ended Current:	Not reported
Owner/Operator Address:	721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-322-6207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status:	Private
Date Became Current:	20051020
Date Ended Current:	Not reported
Owner/Operator Address:	721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-322-6207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status:	Private
Date Became Current:	20031006
Date Ended Current:	Not reported
Owner/Operator Address:	721 BARTON SPRINGS RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78704-1145
Owner/Operator Telephone:	512-322-6207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SEAHOLM POWER PLANT (Continued) **1000412183**

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20050929
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20051010
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20050912
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20090424
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UTI
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20050912
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported

SEAHOLM POWER PLANT (Continued) **1000412183**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20031006
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD
Owner/Operator City,State,Zip: AUSTIN, TX 78704-1145
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20050929
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 800 W 1ST ST
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-322-6267
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20031006
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT

SEAHOLM POWER PLANT (Continued) **1000412183**

Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20031006
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20051010
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20060217
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private

SEAHOLM POWER PLANT (Continued) **1000412183**

Date Became Current: 20060217
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UT
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20090424
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD ELECTRIC UTI
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20111122
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Legal Status: Private
Date Became Current: 20111122
Date Ended Current: Not reported
Owner/Operator Address: 721 BARTON SPRINGS RD
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-322-6207
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19850114
Handler Name: AUSTIN CITY/SEAHOLM PWR PLT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

SEAHOLM POWER PLANT (Continued) **1000412183**

Electronic Manifest Broker: Not reported

Receive Date: 20031006
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050912
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050929
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051010
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051020
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator

SEAHOLM POWER PLANT (Continued) **1000412183**

State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060217
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090424
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20111122
Handler Name: CITY OF AUSTIN DBA AUSTIN ENERGY - SEAHOLM POWER PLANT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

SEAHOLM POWER PLANT (Continued) **1000412183**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130306
Handler Name: SEAHOLM POWER PLANT
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301
Handler Name: CITY OF AUSTIN ELECTRIC UTILITY DEPARTME
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070745605

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110005082301

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
CAMDBS (Clean Air Markets Division Business System) is a national information system that supports the implementation of market-based

SEAHOLM POWER PLANT (Continued) **1000412183**

air pollution control programs administered by the Clean Air Markets Division, within the Office of Air and Radiation. These programs include the Acid Rain Program, established by Title IV of the Clean Air Act Amendments of 1990, and regional programs designed reduce the transport of ozone. These emissions trading programs allows regulated facilities (primarily electric utilities) to adopt the most cost-effective strategies to reduce emissions at their units. Units that reduce their emissions below the number of allowances they hold -- each allowance is equivalent to one ton of sulfur dioxide or nitrogen oxides -- may trade allowances with other units in their system, sell them to other utilities on the open market or through EPA auctions, or bank them to cover emissions in future years. CAMDBS functions include registering responsible officials, establishing allowance accounts, reporting hourly emissions data, and transferring allowances between accounts.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412183
Registry ID:	110005082301
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005082301
Name:	SEAHOLM POWER PLANT
Address:	800 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX 78703

PH2635 **HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID** **TX UST** **U003906613**
WNW **3801 N LAMAR BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78756** **TX Financial Assurance**
0.086 mi. **TX Ind. Haz Waste**
455 ft. **Site 1 of 4 in cluster PH**

Actual:
614 ft.

Focus Map:
8

UST:

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787564080
AI Number:	75714
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	01/19/1998
Facility Status:	ACTIVE
Additional ID:	181386552003092
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	WAYNE GOODMAN,FACILITIES DIRECTOR
Contact Organization Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124077506
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	5124077194
Contact Email Address:	wayne.goodman@hcahealthcare.com
Signature Date On Earliest Reg Form:	03/03/2021
Signature Name/Title On Earliest Reg Form:	V PAUL WEAVER,REP
Application Received Date On Earliest Reg Form:	03/03/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	462344022007276
Additional ID:	181386552003092
Ai Number:	75714
Operator CN:	CN603250861
Operator Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Operator Effective Begin Date:	10/16/2019
Operator Type:	PA
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605533124
Owner Last Name:	HCA HEALTHCARE INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	630391742018151
Additional ID:	181386552003092
AI Number:	75714
Owner Effective Begin Date:	10/16/2019
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	116064
Cert ID:	351585
AI Number:	75714
Self Certification Date:	03/03/2021
Signature Name/Title:	V PAUL WEAVER REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064
Cert ID:	335519
AI Number:	75714
Self Certification Date:	04/04/2020
Signature Name/Title:	V PAUL WEAVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Cert ID:	328544
AI Number:	75714
Self Certification Date:	10/16/2019
Signature Name/Title:	V PAUL WALKER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064
Cert ID:	319887
AI Number:	75714
Self Certification Date:	04/30/2019
Signature Name/Title:	V PAUL WEAVER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064
Cert ID:	302051
AI Number:	75714
Self Certification Date:	04/05/2018
Signature Name/Title:	V WEAVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Cert ID:	277705
AI Number:	75714
Self Certification Date:	09/29/2016
Signature Name/Title:	VINCENT WEAVER REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064
Cert ID:	272903
AI Number:	75714
Self Certification Date:	07/29/2016
Signature Name/Title:	VINCENT WEAVER REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064
Cert ID:	234149
AI Number:	75714
Self Certification Date:	03/10/2014
Signature Name/Title:	WAYNE GOODMAN FAC MNGT DIR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	116064

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Cert ID:	207834
AI Number:	75714
Self Certification Date:	03/05/2012
Signature Name/Title:	WAYNE GOODMAN ENG
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064
Cert ID:	207833
AI Number:	75714
Self Certification Date:	12/17/2009
Signature Name/Title:	WAYNE GOODMAN FAC DIR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064
Cert ID:	207832
AI Number:	75714
Self Certification Date:	05/17/2006
Signature Name/Title:	WAYNE MARTIN FAC ENG
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Cert ID:	207831
AI Number:	75714
Self Certification Date:	05/16/2006
Signature Name/Title:	WAYNE MARTIN FAC ENG
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064
Cert ID:	207830
AI Number:	75714
Self Certification Date:	05/24/2004
Signature Name/Title:	ROY C VINSON PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064
Cert ID:	207829
AI Number:	75714
Self Certification Date:	06/30/2003
Signature Name/Title:	ROY C VINSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116064

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Cert ID:	207828
AI Number:	75714
Self Certification Date:	02/26/2003
Signature Name/Title:	ROY C VINSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/19/1998
Tank Registration Date:	03/12/2003
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	201318
Facility ID:	116064
Ai Number:	75714
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/19/1998
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	182027
UST ID:	201318
AI Number:	75714
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/19/1998
Tank Registration Date:	03/12/2003
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	201319
Facility ID:	116064
Ai Number:	75714
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/19/1998
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	182028
UST ID:	201319
AI Number:	75714
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HCA HEALTHCARE INC
Contact Mailing Address (Delivery):	3801 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78756 4080
Phone Number/Ext:	512 4077506/0
Contact Fax Number/Ext:	/
Contact Email Address:	wayne.goodman@hcahealthcare.com
Contact Address Deliverable:	Y
Facility ID:	116064
Additional ID:	181386552003092
Princ ID:	630391742018151
AI Number:	75714
Facility Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
AR Number:	81184
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	WAYNE GOODMAN/

HIST UST AUSTIN:

Name:	HEART HOSPITAL OF AUSTIN, CAMPUS OF ST. *
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3217
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	247555
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2020
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	CHUBB CUSTOM INS CO
Issuer Phone:	1 888 8888888
Policy Number:	USTG7182553A001
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	222557
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2019
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	PPI G2706517A 008
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	230352
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2019
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	PPI G2706517A008
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	213525
AI:	75714

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2018
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G2706517A 007
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	195252
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2017
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 866 2837122
Policy Number:	G2706517A006
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	170041
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2016
Date Financial Assurance Form Rec:	03/03/2021

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	PPI G2706517A005
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	165355
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2015
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	PPI G2706517A 004
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/01/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	125280
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2014
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	866 283 7122
Policy Number:	G2706517A 001
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	110139
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2012
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	Not reported
Policy Number:	PPI G2706517A 001
Coverage Amount:	2,000,000
Coverage Expiration Date:	09/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	15170
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2011
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	EPC 5877465-069
Coverage Amount:	1000000
Coverage Expiration Date:	09/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	101765
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2008
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	INDIAN HARBOR INS CO
Issuer Phone:	Not reported
Policy Number:	PEC000433006
Coverage Amount:	3000000
Coverage Expiration Date:	09/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	116064
Finass ID:	101766
AI:	75714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/03/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Ind. Haz Waste:

Name:	HEART HOSPITAL OF AUSTIN
Address:	3801 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	91603
Registration Initial Notification Date:	11/01/2010
Registration Last Amendment Date:	04/10/2014
EPA Identification:	TXR000081316
Primary NAICS Code:	622110
Status Change Date:	20121204
Land Type:	PRIVATE
Description of Facility Site Location:	3801 N LAMAR BLVD AUSTIN TX 78756
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Contact Name:	WAYNE GOODMAN
Contact Telephone Number:	512-4077506
Mailing Address:	3801 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787564080
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130571
Site Owner Tax ID:	0
Site Location Latitude:	-30.306
Site Location Longitude:	-97.741
Last Update to NOR Data:	20140414
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Operator Address:	98 SAN JACINTO BLVD
Operator Address 2:	STE 1800
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4077506
Operator Fax Number:	1-512-4077527
Operator Email:	WAYNE.GOODMAN@HCAHEALTHCARE.COM
Operator Business Type:	Not reported
Operator Tax ID:	17427818129
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Owner Mailing Address:	98 SAN JACINTO BLVD
Owner Mailing Address 2:	STE 1800
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Owner Country:	UNITED STA
Owner Telephone:	1-512-4077506
Owner Fax:	1-512-4077527
Owner Email Address:	WAYNE.GOODMAN@HCAHEALTHCARE.COM
Owner Business Type:	Not reported
Owner Tax ID:	17427818129
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	HOSPITAL CENTRAL ACCUMULATION ROOM OFF AMBULANCE BAY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20121105
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	HOSPITAL CHEMICAL CONTAINER IN BACK PARKING STORAGE BUILDING
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20121105
Deed Record Needed:	Not reported

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	98 SAN JACINTO BLVD
Contact Address 2:	STE 1800
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4077506
Contact Fax:	1-512-4077527
Contact Email:	WAYNE.GOODMAN@HCAHEALTHCARE.COM

Contact Name:	WAYNE GOODMAN
Contact Title:	DIRECTOR ENGINEERING
Contact Role:	PRICONT
Contact Address:	3801 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4077506
Contact Fax:	1-512-4077527
Contact Email:	WAYNE.GOODMAN@HCAHEALTHCARE.COM

Ind. Haz Waste:

Waste ID:	345556
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	RCRA HAZARDOUS PHARMACEUTICAL WASTE
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Ind. Haz Waste:

Waste ID:	348581
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	HOSPITAL LABORATORY HAZARDOUS WASTE
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	362380
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	HAZARDOUS LABORATORY WASTE - XYLENE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

HEART HOSPITAL OF AUSTIN - CAMPUS OF ST DAVID (Continued) **U003906613**

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-512-4077561 x0
Mailing Address:	3801 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78756
AR Number:	0000317438
Principal Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-512-4077561 x0
Mailing Address:	3801 N LAMAR BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78756
AR Number:	0000317438
Principal Name:	ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Attention Name:	Not reported
Attention Suffix:	HWG

PH2636 **HEART HOSPITAL OF AUSTIN** **RCRA-SQG** **1016455977**
WNW **3801 N LAMAR BLVD** **TXR000081316**
< 1/8 **AUSTIN, TX 78756**
0.086 mi.
455 ft. **Site 2 of 4 in cluster PH**

Actual:
614 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20220426
Handler Name:	Heart Hospital Of Austin
Handler Address:	3801 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78756-4080
EPA ID:	TXR000081316
Contact Name:	WAYNE GOODMAN
Contact Address:	3801 N LAMAR BLVD
Contact City,State,Zip:	AUSTIN, TX 78756-4080
Contact Telephone:	512-796-9740
Contact Fax:	Not reported
Contact Email:	WAYNE.GOODMAN@HCAHEALTHCARE.COM
Contact Title:	DIR FACILITIES MGMT
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities

HEART HOSPITAL OF AUSTIN (Continued) **1016455977**

State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3801 N LAMAR BLVD
Mailing City,State,Zip:	AUSTIN, TX 78756-4080
Owner Name:	St Davids Healthcare Partnership Lp Llp
Owner Type:	Private
Operator Name:	St Davids Healthcare Partnership Lp Llp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220510
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	H

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D009
Waste Description:	Mercury

HEART HOSPITAL OF AUSTIN (Continued) **1016455977**

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D022
Waste Description: Chloroform

Waste Code: D024
Waste Description: M-Cresol

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F027
Waste Description: Discarded Unused Formulations Containing Tri-, Tetra-, Or Pentachlorophenol Or Discarded Unused Formulations Containing Compounds Derived From These Chlorophenols. (This Listing Does Not Include Formulations Containing Hexachlorophene Synthesized From Prepurified 2,4,5-Trichlorophenol As The Sole Component.)

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

HEART HOSPITAL OF AUSTIN (Continued) **1016455977**

Waste Code: U188
Waste Description: Phenol

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Legal Status: Private
Date Became Current: 20101101
Date Ended Current: Not reported
Owner/Operator Address: 98 SAN JACINTO BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78701-4082
Owner/Operator Telephone: 512-407-7506
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Legal Status: Private
Date Became Current: 20121105
Date Ended Current: Not reported
Owner/Operator Address: 3801 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Legal Status: Private
Date Became Current: 20121105
Date Ended Current: Not reported
Owner/Operator Address: 3801 N LAMAR BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Legal Status: Private
Date Became Current: 20101101
Date Ended Current: Not reported
Owner/Operator Address: 98 SAN JACINTO BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78701-4082
Owner/Operator Telephone: 512-407-7506
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP

HEART HOSPITAL OF AUSTIN (Continued) **1016455977**

Legal Status: Private
Date Became Current: 20101101
Date Ended Current: Not reported
Owner/Operator Address: 98 SAN JACINTO BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78701-4082
Owner/Operator Telephone: 512-407-7506
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ST DAVIDS HEALTHCARE PARTNERSHIP LP LLP
Legal Status: Private
Date Became Current: 20101101
Date Ended Current: Not reported
Owner/Operator Address: 98 SAN JACINTO BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78701-4082
Owner/Operator Telephone: 512-407-7506
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20130111
Handler Name: HEART HOSPITAL OF AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140410
Handler Name: HEART HOSPITAL OF AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220426
Handler Name: HEART HOSPITAL OF AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

HEART HOSPITAL OF AUSTIN (Continued) **1016455977**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 62211
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

NAICS Code: 622110
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

OK2637 **TRATEX AUTO STORAGE** **EDR Hist Auto** **1013767826**
WSW **208 5TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
455 ft. **Site 16 of 21 in cluster OK**

Actual:
491 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	TRATEX AUTO STORAGE	AUTOMOBILE GARAGES

OD2638 **SMITH & HUDLER BROS** **EDR Hist Auto** **1013755510**
SSW **406 BRAZOS ST** **N/A**
< 1/8 **AUSTIN, TX**
0.086 mi.
456 ft. **Site 2 of 3 in cluster OD**

Actual:
484 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1922	SMITH & HUDLER BROS	AUTOMOBILE GARAGES

OI2639 **AUSTIN FOREIGN CAR** **TX Ind. Haz Waste** **S102748602**
ESE **510 W 6TH ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.087 mi.
457 ft. **Site 13 of 15 in cluster OI**

Actual:
477 ft.
Ind. Haz Waste:

Focus Map:
11

Name: AUSTIN FOREIGN CAR
Address: 510 W 6TH ST
City,State,Zip: AUSTIN, TX 78701
Permit Number: Not reported
Registration Number: 61742

AUSTIN FOREIGN CAR (Continued) **S102748602**

Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	510 W 6th, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN FOREIGN CAR
Contact Name:	MR HUGHES
Contact Telephone Number:	Not reported
Mailing Address:	510 W 6TH
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 78710
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20083
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030519
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN FOREIGN CAR
Operator Address:	510 W 6THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown

AUSTIN FOREIGN CAR (Continued) **S102748602**

Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN FOREIGN CAR
Owner Mailing Address:	510 W 6THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	510 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	510 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MR HUGHES
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	510 W 6TH
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78710
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100651397
Name:	AUSTIN FOREIGN CAR
Address:	510 W 6TH ST

AUSTIN FOREIGN CAR (Continued) **S102748602**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2806
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600361000
Customer Name:	AUSTIN FOREIGN CAR
Customer Legal Name:	Austin Foreign Car
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	510 W 6th, Austin, TX

2640 NNE < 1/8 0.087 mi. 457 ft. **THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENT** **US BROWNFIELDS FINDS** **1024008897 N/A**
501 E. 8TH
AUSTIN, TX 78702

Actual: 499 ft.

Focus Map: 11

US BROWNFIELDS:

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3695
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	3/24/2017
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12
Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

	finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8621
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	3/24/2017
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

Name:	THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER
Address:	501 E. 8TH
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.61
Latitude:	30.2682476
Longitude:	-97.7372481

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property is a homeless shelter and social services center for Austin's vulnerable population. The Salvation Army needs a federal Home Loan Bank loan in order to renovate this much-used structure. A Phase I ESA is a requirement of that loan. Future plans for the property include substantial refurbishment and replacement of mechanical, electrical, plumbing and elevator systems, replacement of finishes/materials for flooring, walls and ceilings. Additional security features will be installed. The exterior brick facade will also undergo substantial refurbishment due to some system failure. While the renovation/refurbishment of the facility will not change it's use, it will be able to serve the homeless clients in a cleaner and safer environment.
Datum:	Not reported
Acres Property ID:	231122
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media

THE SALVATION ARMY CENTER AND SOCIAL SERVICES CENTER (Continued) **1024008897**

Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.61
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.61
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	264
Below Poverty Percent:	14.55
Meidan Income:	1100
Meidan Income Number:	341
Meidan Income Percent:	18.79
Vacant Housing Number:	227
Vacant Housing Percent:	19.65
Unemployed Number:	111
Unemployed Percent:	6.12

FINDS:
Registry ID: 110070100686

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

MN2641 **SCHRAMM GULF SERV** **EDR Hist Auto** **1013756511**
NNE **107 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.087 mi.
458 ft. **Site 8 of 11 in cluster MN**

Actual:
473 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1935	GULF REFG STA NO	GASOLINE AND OIL SERVICE STATIONS
1940	BURCH J PERRY JR FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1947	ROELYN ROLL IN FILL STA	GASOLINE AND OIL SERVICE STATIONS
1953	SCHRAMM GULF SERV	GASOLINE STATIONS
1958	SCHRAMM GULF SERV	GASOLINE STATIONS

PI2642 **AUSTIN BEN WHITE FACILITY** **TX AST** **A100492067**
SW **7401 E BEN WHITE BLVD BLDG 1150** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.087 mi.
458 ft. **Site 1 of 4 in cluster PI**

Actual:
537 ft.

Focus Map:
19

AST:

Name:	AUSTIN BEN WHITE FACILITY
Address:	7401 E BEN WHITE BLVD BLDG 1150
City,State,Zip:	AUSTIN, TX 787416822
Facility ID:	120529
Additional ID:	268557152006271
AI Number:	78195
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	01/01/1999
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	Y
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	AUSTIN
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	Not reported
Contact Name/Title:	BOBBY ALVARADO/
Contact Organization Name:	AUSTIN BEN WHITE FACILITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5123890401
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	08/30/2006
Signature First Name on Earliest Reg Form:	JOHN
Application Received Date on Earliest Reg Form:	09/05/2006
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	FERGUSON
Signature Title on Earliest Reg Form:	MGR
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	120529
Tank ID:	1
AST ID:	207219
AI Number:	78195
Install Date:	01/01/1999
Tank Registration Date:	09/05/2006
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	01/01/1999
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2000

AUSTIN BEN WHITE FACILITY (Continued) **A100492067**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	Y
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

PI2643 **CYRUSONE** **TX AST** **A100492196**
SW **7401 E BEN WHITE BLVD** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.087 mi.
458 ft. **Site 2 of 4 in cluster PI**

Actual:
537 ft.

Focus Map:
19

AST:

Name:	CYRUSONE
Address:	7401 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787416822
Facility ID:	127774
Additional ID:	344478432010130
AI Number:	83527
Facility Type:	Not reported
Facility Begin Date:	04/01/2009
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	3
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78741
Contact Name/Title:	RON WILLIAMS/MANAGER
Contact Organization Name:	CYRUSONE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5129215080
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	12/09/2009
Signature First Name on Earliest Reg Form:	RON
Application Received Date on Earliest Reg Form:	12/09/2009
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	WILLIAMS
Signature Title on Earliest Reg Form:	MANAGER
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported

CYRUSONE (Continued) **A100492196**

Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	127774
Tank ID:	1
AST ID:	212950
AI Number:	83527
Install Date:	04/01/2009
Tank Registration Date:	12/09/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/01/2009
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	3000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	127774
Tank ID:	2
AST ID:	212951
AI Number:	83527
Install Date:	04/01/2009
Tank Registration Date:	12/09/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/01/2009
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	3000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

CYRUSONE (Continued) **A100492196**

Facility ID:	127774
Tank ID:	3
AST ID:	212952
AI Number:	83527
Install Date:	04/01/2009
Tank Registration Date:	12/09/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/01/2009
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

PI2644 **GENERAL MOTORS - AUSTIN CUSTOMER ENGAGEMENT CENTER** **RCRA-VSQG** **1019326655**
SW **7401 E. BEN WHITE BLVD.** **TXR000083824**
< 1/8 **AUSTIN, TX 78741**
0.087 mi.
458 ft. **Site 3 of 4 in cluster PI**

Actual:
537 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20160706
Handler Name:	General Motors - Austin Customer Engagement Center
Handler Address:	E. BEN WHITE BLVD.
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXR000083824
Contact Name:	MICAH HART
Contact Address:	E. BEN WHITE BLVD.
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Telephone:	512-840-3803
Contact Fax:	Not reported
Contact Email:	MICAH.HART@GM.COM
Contact Title:	SITE MGR.
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	E. BEN WHITE BLVD.
Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Name:	Digital Metcenter 7-9, Llc

GENERAL MOTORS - AUSTIN CUSTOMER ENGAGEMENT CENTER (Continued) **1019326655**

Owner Type:	Private
Operator Name:	General Motors, Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160708
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: GENERAL MOTORS, LLC	
Legal Status:	Private
Date Became Current:	19990201
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported

GENERAL MOTORS - AUSTIN CUSTOMER ENGAGEMENT CENTER (Continued) **1019326655**

Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DIGITAL METCENTER 7-9, LLC
Legal Status: Private
Date Became Current: 20130522
Date Ended Current: Not reported
Owner/Operator Address: FOUR EMBARCADERO CENTER
Owner/Operator City,State,Zip: SAN FRANCISCO, CA 94111
Owner/Operator Telephone: 415-874-2345
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160706
Handler Name: GENERAL MOTORS - AUSTIN CUSTOMER ENGAGEMENT CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 541990
NAICS Description: ALL OTHER PROFESSIONAL, SCIENTIFIC, AND TECHNICAL SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

PI2645 **AUSTIN DATA CENTER AUS 02** **TX AST** **A100491898**
SW **7401 E BEN WHITE BLVD** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.087 mi.
458 ft. **Site 4 of 4 in cluster PI**

Actual:
537 ft.

Focus Map:
19

AST:
Name: AUSTIN DATA CENTER AUS 02
Address: 7401 E BEN WHITE BLVD
City,State,Zip: AUSTIN, TX 787416822
Facility ID: 111677
Additional ID: 15690562002150
AI Number: 73308

AUSTIN DATA CENTER AUS 02 (Continued) **A100491898**

Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78741
Contact Name/Title:	AJ KLUNDT/
Contact Organization Name:	AUSTIN DATA CENTER AUS 02
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5126849644
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	06/28/2000
Signature First Name on Earliest Reg Form:	DON R
Application Received Date on Earliest Reg Form:	07/05/2000
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	POPE
Signature Title on Earliest Reg Form:	ASST COUNCIL FACILIT
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	111677
Tank ID:	1
AST ID:	194547
AI Number:	73308
Install Date:	05/27/2000
Tank Registration Date:	07/05/2000
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	05/27/2000
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	5000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	Y
Dike:	N
Liner:	Y
Contains CO:	N

AUSTIN DATA CENTER AUS 02 (Continued) **A100491898**

Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

NY2646 **A CRENSHAW GARAGE AUTO REPRS** **EDR Hist Auto** **1013768107**
NE **711 RED RIVER CT** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.087 mi.
460 ft. **Site 3 of 5 in cluster NY**

Actual:
482 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	CRENSHAW GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1953	CRENSHAW GAR AUTO	AUTOMOBILE REPAIRING
1958	CRENSHAW GARAGE	AUTOMOBILE REPAIRING
1962	CRENSHA N GARAGE	AUTOMOBILE REPAIRING
1970	A CRENSHAW GARAGE AUTO REPRS	AUTOMOBILE REPAIRING

OS2647 **BRADSHERE-FLOURNOY** **TX CLI** **S103258979**
ESE **EAST OF 6000 BLOCK OF S. CONGRESS** **N/A**
< 1/8 **, TX**
0.087 mi.
461 ft. **Site 2 of 4 in cluster OS**

Actual:
649 ft.

Focus Map:
17

CLI:

Name:	BRADSHERE-FLOURNOY
Address:	EAST OF 6000 BLOCK OF S. CONGRESS
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	2
Source Code:	Not reported
Date Opened:	**********
Date Closed:	**********
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	12.09
Long Deg:	97
Long Min:	46.46

BRADSHERE-FLOURNOY (Continued) **S103258979**

Lat/Long (deg):	30.201500 / -97.774333
Owner:	Not reported
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	**********
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported
Inspc Comments:	JUNKED CARS, TIRES, CAR PARTS, ETC.
Comments:	???
Update:	0
Reviewer:	Not reported
Flag:	Not reported

OS2648 **BRADSHERE-FLOURNOY** **TX HIST LF** **S129373075**
ESE **EAST OF 6000 BLOCK OF S. CONGRESS** **N/A**
< 1/8 **TRAVIS (County), TX**
0.087 mi.
461 ft. **Site 3 of 4 in cluster OS**

Actual:
649 ft.

Focus Map:
17

HIST LF:

Name:	BRADSHERE-FLOURNOY
Name 2:	Not reported
Address:	EAST OF 6000 BLOCK OF S. CONGRESS
City,State,Zip:	TX
Latitude:	30.201500
Longitude:	-97.774333
Lat Deg:	30
Lat MM:	12.09

BRADSHERE-FLOURNOY (Continued) **S129373075**

Lon DD:	97
Lon MM:	46.46
UNUM:	1617
Comments:	???
Inspection:	JUNKED CARS, TIRES, CAR PARTS, ETC.
COG Number:	12
COOR CD:	Not reported
TWC District:	Not reported
Owner Name:	Not reported
Owner Code:	Not reported
Open Date:	0
Close Date:	0
Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	2

OS2649 **BRADSHERE-FLOURNOY** **TX CLI** **S113416460**
ESE **EAST OF 6000 BLOCK OF S. CONGRESS** **N/A**
< 1/8 **TRAVIS (County), TX**
0.087 mi.
461 ft. **Site 4 of 4 in cluster OS**

Actual:
649 ft.

Focus Map:
17

CAPCOG LI:

Name:	BRADSHERE-FLOURNOY
Address:	EAST OF 6000 BLOCK OF S. CONGRESS
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	0
Date Close:	0
Unum:	1617
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	12.09
Longitude Deg:	97
Longitude Min:	46.460000000000001

BRADSHERE-FLOURNOY (Continued) **S113416460**

Lat Dd:	30.201499999999999
Long Dd:	-97.774332999999999
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	2
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Emmit Cohen Joint Venture
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	0
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported

BRADSHERE-FLOURNOY (Continued) **S113416460**

Min Thick:	Not reported
Use:	Not reported
Inspection:	JUNKED CARS, TIRES, CAR PARTS, ETC.
Comment:	???
Latitude:	30.2015
Longitude:	-97.77433333
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=249

PJ2650 **BRYANT AUTOMOTIVE** **EDR Hist Auto** **1013768858**
West **505 OLTORF ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78704**
0.088 mi.
463 ft. **Site 1 of 2 in cluster PJ**

Actual:
548 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1970	THOMSON SERVICE STATION	GASOLINE STATIONS
1980	BRYANT AUTOMOTIVE	AUTOMOBILE REPAIRING
1984	BRYANT AUTOMOTIVE	AUTOMOBILE REPAIRING
1990	BRYANT AUTOMOTIVE	AUTOMOBILE REPAIRING

NK2651 **AUSTIN DAILY TRIBUNE BUILDING** **TX HIST UST** **S111678561**
ESE **213 W 10TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.088 mi.
464 ft. **Site 2 of 2 in cluster NK**

Actual:
546 ft.

HIST UST AUSTIN:

Focus Map:
11

Name:	AUSTIN DAILY TRIBUNE BUILDING
Address:	213 W 10TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0980
HID UST:	980
Inspection:	06/16/2011
Due:	06/16/2014

NL2652 **SING LEE CHINESE LAUNDRY** **EDR Hist Cleaner** **1013781994**
SSW **403 CONGRESS AVE R SAME** **N/A**
< 1/8 **AUSTIN, TX**
0.088 mi.
465 ft. **Site 5 of 5 in cluster NL**

Actual:
485 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1896	SING LEE CHINESE LAUNDRY	LAUNDRIES
1901	JIM LEE CHINESE LAUNDRY	LAUNDRIES

MQ2653 ENE < 1/8 0.088 mi. 465 ft. | **HERWICK DON PHILLIPS**
4834 EAST AVE
AUSTIN, TX
Site 17 of 18 in cluster MQ | **EDR Hist Auto** | **1013754450**
N/A

Actual: 582 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1962	HERWICK DON PHILLIPS	GASOLINE STATIONS
1965	INTERREGIONAL PHILLIPS	GASOLINE STATIONS

PK2654 WNW < 1/8 0.088 mi. 465 ft. | **TEXAS GOVERNORS MANSION**
1010 COLORADO ST
AUSTIN, TX 78701
Site 1 of 2 in cluster PK | **TX RDR**
TX CENTRAL REGISTRY | **S126826165**
N/A

Actual: 550 ft.

Focus Map: 11

RDR:

RDR ID:	19630
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	TEXAS GOVERNORS MANSION
Address:	1010 COLORADO ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/31/2011
Due Date:	5/30/2011
Tank Owner:	STATE PRESERVATION BOARD
Contact Person:	MS DEALEY HERNDON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/13/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/13/2011
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN106134299
Name:	TEXAS GOVERNORS MANSION
Address:	1010 COLORADO ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-2334
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600257091
Customer Name:	STATE OF TEXAS
Customer Legal Name:	State of Texas
Customer Ownership Type:	STATE GOVERNMENT

TEXAS GOVERNORS MANSION (Continued) **S126826165**

Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

PK2655 **TEXAS GOVERNORS MANSION** **TX UST** **U004177998**
WNW **1010 COLORADO ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.088 mi.
465 ft. **Site 2 of 2 in cluster PK**

Actual:
550 ft.

Focus Map:
11

UST:

Name:	TEXAS GOVERNORS MANSION
Address:	1010 COLORADO ST
City,State,Zip:	AUSTIN, TX 787012334
AI Number:	84275
Facility Type:	Not reported
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	763330302011131
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	DEALEY HERNDON,
Contact Organization Name:	TEXAS GOVERNORS MANSION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124634842
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/11/2011
Signature Name/Title On Earliest Reg Form:	DEALEY HERNDON,PROJ MGR
Application Received Date On Earliest Reg Form:	03/28/2011
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600257091
Owner Last Name:	STATE OF TEXAS
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported

TEXAS GOVERNORS MANSION (Continued) **U004177998**

Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	310279772001297
Additional ID:	763330302011131
AI Number:	84275
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/28/2011
Number of Compartments:	1
Tank Capacity:	1600
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	214722
Facility ID:	129148
Ai Number:	84275
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/17/2011
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

TEXAS GOVERNORS MANSION (Continued) **U004177998**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1600
UST Comprt ID:	180210
UST ID:	214722
AI Number:	84275
Compartment ID:	A
Substance Stored1:	DISTILLATE FUEL OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

TEXAS GOVERNORS MANSION (Continued) **U004177998**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	23491
Facility ID:	129148
AI Number:	84275
Application Received Date:	02/14/2011
Scheduled Construction Date:	02/17/2011
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	71828
General Desc Of Prop Construct:	REMOVAL OF (1) APPROXIMATE 1,000 GAL FUEL OIL UST DISCOVERED DURING SITE CONSTRU CTION.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	25192
UST ID:	Not reported
NOC ID:	23491
AI Number:	84275
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON CONSULTANTS INC
Representative Name:	KEVIN PG
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

TEXAS GOVERNORS MANSION (Continued) **U004177998**

Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	25191
UST ID:	Not reported
NOC ID:	23491
AI Number:	84275
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000079
Company Name:	GRUENE ENVIRONMENTAL CONST
Representative Name:	DOUG ANDERSON
Mailing Address (Delivery):	11 NAFTA CIRCLE
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRUANFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	25193
UST ID:	Not reported
NOC ID:	23491
AI Number:	84275
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000079
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

TEXAS GOVERNORS MANSION (Continued) **U004177998**

Facility Billing Contacts:

Contact Organization Name:	STATE OF TEXAS
Contact Mailing Address (Delivery):	201 E 14TH ST STE 950
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1445
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	129148
Additional ID:	763330302011131
Princ ID:	310279772001297
AI Number:	84275
Facility Name:	TEXAS GOVERNORS MANSION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	TEXAS GOVERNOR'S MANSION
Address:	1010 COLORADO ST
City,State,Zip:	AUSTIN, TX
Id UST:	3346
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NA2656 **RAMIREZ GULF SERVICE GAS** **EDR Hist Auto** **1013759749**
NE **329 CONGRESS AVE S** **N/A**
< 1/8 **AUSTIN, TX**
0.088 mi.
466 ft. **Site 11 of 12 in cluster NA**

Actual:
452 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1940	BROWN ESTIN A FILLING	GASOLINE AND OIL SERVICE STATIONS
1965	RAMIREZ GULF SERVICE GAS	GASOLINE STATIONS

NA2657 **BUTLERS GULF SERV** **EDR Hist Auto** **1013753546**
NE **329 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.088 mi.
466 ft. **Site 12 of 12 in cluster NA**

Actual:
452 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1953	BUTLER WA SERV	GASOLINE STATIONS
1958	BUTLERS GULF SERV	GASOLINE STATIONS

2658 NNE < 1/8 0.088 mi. 467 ft. | **HARVEY MASSEY 6505 E RIVERSIDE DR AUSTIN, TX** | **TX HIST UST** | **S111678671 N/A**

Actual: 533 ft.
Focus Map: 15

HIST UST AUSTIN:

Name:	HARVEY MASSEY
Address:	6505 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX
Id UST:	H0723
HID UST:	723
Inspection:	Not reported
Due:	06/01/2012

2659 SE < 1/8 0.089 mi. 469 ft. | **AUSTIN AMERICAN STATESMAN 305 S CONGRESS AVE AUSTIN, TX 78704** | **TX LPST** | **S116696643 N/A**

Actual: 442 ft.
Focus Map: 11

LPST:

Name:	AUSTIN AMERICAN STATESMAN
Address:	305 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0019681
LPST Id:	104432
Facility Location:	305 SOUTH CONGRESS
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/24/1992
Entered Date:	10/05/1992
Reported Date:	08/24/1992
Closure Date:	09/17/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	SAMMY POWELL
Responsible Party Address:	305 S CONGRESS AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78704
Responsible Party Telephone:	512/445-3737
Reported Date:	08/24/1992
Case Start Date:	09/17/1992
Reference Number:	RN101489169
Project Manager:	HWELCH

NG2660 **CAPITAL CITY TIRE** **TX HIST UST** **S111678594**
WNW **221 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.089 mi.
470 ft. **Site 8 of 16 in cluster NG**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CAPITAL CITY TIRE
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0006
HID UST:	6
Inspection:	03/19/2009
Due:	03/19/2012

NG2661 **TX HIST UST** **S111678182**
WNW **221 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.089 mi.
470 ft. **Site 9 of 16 in cluster NG**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0040
HID UST:	40
Inspection:	03/19/2009
Due:	03/19/2012

NG2662 **CHASE TOWER 14TH FLOOR** **TX HIST UST** **S111678724**
WNW **221 W. 6TH STREET** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.089 mi.
470 ft. **Site 10 of 16 in cluster NG**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	LONE STAR GARAGE
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0005
HID UST:	5
Inspection:	03/19/2009
Due:	03/19/2012

ASBESTOS:

Name:	CHASE TOWER 14TH FLOOR
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Olivia Espinoza
Violation:	Not reported
Complaint Date:	01/10/2016
Notification Number:	2015008505
ASB Priority:	Not reported

CHASE TOWER 14TH FLOOR (Continued) **S111678724**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/17/2015
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

CHASE TOWER 14TH FLOOR (Continued) **S111678724**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER 14TH FLOOR
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Olivia Espinoza
Violation:	Not reported
Complaint Date:	12/20/2015
Notification Number:	2015008505
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/04/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/04/2015
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/18/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

CHASE TOWER 14TH FLOOR (Continued) **S111678724**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CHASE TOWER 14TH FLOOR
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Olivia Espinoza
Violation:	Not reported
Complaint Date:	01/10/2016
Notification Number:	2015008505
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/23/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/23/2015
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07

CHASE TOWER 14TH FLOOR (Continued) **S111678724**

Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER 14TH FLOOR
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Olivia Espinoza
Violation:	Not reported
Complaint Date:	01/10/2016
Notification Number:	2015008505
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/23/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

CHASE TOWER 14TH FLOOR (Continued) **S111678724**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/23/2015
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

NG2663 **GOODYEAR TIRE COMP.** **TX HIST UST** **S111678650**
WNW **221 W 6TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.089 mi.
470 ft. **Site 11 of 16 in cluster NG**

Actual:
496 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	GOODYEAR TIRE COMP.
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0059
HID UST:	59
Inspection:	03/19/2009
Due:	03/19/2012

NG2664 WNW < 1/8 0.089 mi. 470 ft. | **GULF REFINING CO. 221 W 6TH ST AUSTIN, TX** | **TX HIST UST** | **S111678660 N/A**

Site 12 of 16 in cluster NG

Actual: 496 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	GULF REFINING CO.
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0018
HID UST:	18
Inspection:	03/19/2009
Due:	03/19/2012

NG2665 WNW < 1/8 0.089 mi. 470 ft. | **NONO SCHUTZ 221 W 6TH ST AUSTIN, TX** | **TX HIST UST** | **S111678757 N/A**

Site 13 of 16 in cluster NG

Actual: 496 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	NONO SCHUTZ
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0077
HID UST:	77
Inspection:	03/19/2009
Due:	03/19/2012

NG2666 WNW < 1/8 0.089 mi. 470 ft. | **NOT AVAILABLE 221 W 6TH ST AUSTIN, TX** | **TX HIST UST** | **S111678759 N/A**

Site 14 of 16 in cluster NG

Actual: 496 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	NOT AVAILABLE
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0879
HID UST:	879
Inspection:	03/19/2009
Due:	03/19/2012

NG2667 WNW < 1/8 0.089 mi. 470 ft. | **CHASE TOWER 221 W 6TH STREET AUSTIN, TX 78701** | **TX HIST UST TX ASBESTOS** | **S111678656 N/A**

Site 15 of 16 in cluster NG

Actual: 496 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	GULF OIL COMPANY
Address:	221 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0054
HID UST:	54
Inspection:	03/19/2009
Due:	03/19/2012

ASBESTOS:

Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	02/04/2020
Notification Number:	2020000707
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/21/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/21/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0

CHASE TOWER (Continued) **S111678656**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CHASE TOWER
Address:	221 W 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	11/16/2018
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	12/17/2017
Notification Number:	2017008819
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

CHASE TOWER (Continued) **S111678656**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/15/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	11/29/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

CHASE TOWER (Continued) **S111678656**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/29/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701

CHASE TOWER (Continued) **S111678656**

Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/22/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/05/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

CHASE TOWER (Continued) **S111678656**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/05/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/19/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/19/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

CHASE TOWER (Continued) **S111678656**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/12/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement

CHASE TOWER (Continued) **S111678656**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/03/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	11/26/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/10/2017

CHASE TOWER (Continued) **S111678656**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/10/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	12/02/2017
Notification Number:	2017007371

CHASE TOWER (Continued) **S111678656**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/22/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/22/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

CHASE TOWER (Continued) **S111678656**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	10/22/2017
Notification Number:	2017007371
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/05/2017
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/20/2017
Client Code:	Not reported
Client Name:	Not reported

CHASE TOWER (Continued) **S111678656**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/02/2021
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	06/08/2020
Notification Number:	2020002292
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/29/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/29/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N

CHASE TOWER (Continued) **S111678656**

Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/01/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/02/2021
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	05/28/2020
Notification Number:	2020002292
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

CHASE TOWER (Continued) **S111678656**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/03/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/25/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/02/2021
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	06/08/2020
Notification Number:	2020002292
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

CHASE TOWER (Continued) **S111678656**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/22/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/01/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CHASE TOWER (Continued) **S111678656**

Name:	CHASE TOWER
Address:	221 W. 6TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/02/2021
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	04/09/2020
Notification Number:	2020002292
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/16/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/16/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

CHASE TOWER (Continued) **S111678656**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

NN2668 **AUSTIN SALES** **TX LPST** **U001283822**
WNW **825 PRAIRIE TRL** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78758** **TX HIST UST**
0.089 mi.
471 ft. **Site 2 of 2 in cluster NN**

Actual:
752 ft.

Focus Map:
3

LPST:

Name:	AUSTIN SALES
Address:	825 PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78700
Facility ID:	0053148
LPST Id:	095261
Facility Location:	PRAIRIE TR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/23/1990
Entered Date:	04/19/1990
Reported Date:	03/23/1990
Closure Date:	06/19/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	LEWIS F MIEARS
Responsible Party Address:	2410 PEGRAM AVE
Responsible Party City,St,Zip:	AUSTIN, TX 78757
Responsible Party Telephone:	512/459-9558
Reported Date:	03/23/1990
Case Start Date:	06/19/1990
Reference Number:	RN101510055
Project Manager:	HWELCH

UST:

Name:	AUSTIN SALES
Address:	825 PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 787584339
AI Number:	53148
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/01/1990
Facility Status:	INACTIVE

AUSTIN SALES (Continued) **U001283822**

Additional ID:	789662532002057
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/18/1990
Signature Name/Title On Earliest Reg Form:	MICHAEL D PATTILLO,AGENT
Application Received Date On Earliest Reg Form:	02/22/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600787220
Owner Last Name:	MIEARS
Owner First Name:	LEWIS
Owner Middle Name:	F
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	781662512002057
Additional ID:	789662532002057
AI Number:	53148
Owner Effective Begin Date:	05/01/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	02/22/1990
Number of Compartments:	1

AUSTIN SALES (Continued) **U001283822**

Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	131468
Facility ID:	83019
Ai Number:	53148
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/23/1990
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

AUSTIN SALES (Continued) **U001283822**

Tank Tested Flag:	N
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	136875
UST ID:	131468
AI Number:	53148
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MIEARS LEWIS F JR
Contact Mailing Address (Delivery):	2710 PEGRAM AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78757 2347
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83019

AUSTIN SALES (Continued) **U001283822**

Additional ID:	789662532002057
Princ ID:	781662512002057
AI Number:	53148
Facility Name:	AUSTIN SALES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JAKE MIEAR/

HIST UST AUSTIN:

Name:	AUSTIN SALES INC
Address:	825 PRAIRIE TRL
City,State,Zip:	AUSTIN, TX
Id UST:	C0091
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OT2669 **LABORATORY CORPORATION OF AMERICA** **RCRA NonGen / NLR** **1004783848**
WNW **3701 N LAMAR STE 200** **FINDS** **TX0000933713**
< 1/8 **AUSTIN, TX 78705** **ECHO**
0.089 mi.
471 ft. **Site 3 of 8 in cluster OT**

Actual:
609 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	19981019
Handler Name:	Laboratory Corporation Of America
Handler Address:	N LAMAR STE 200
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TX0000933713
Contact Name:	BRIAN MORONEY
Contact Address:	W FIRST PARK TEN BLVD
Contact City,State,Zip:	SAN ANTONIO, TX 78213
Contact Telephone:	210-735-9461
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W FIRST PARK TEN BLVD
Mailing City,State,Zip:	SAN ANTONIO, TX 78213
Owner Name:	Laboratory Corporation Of America Holdin
Owner Type:	Private
Operator Name:	National Health Laboratories Austin
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

LABORATORY CORPORATION OF AMERICA (Continued) **1004783848**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

LABORATORY CORPORATION OF AMERICA (Continued) **1004783848**

Owner/Operator Indicator: Owner
Owner/Operator Name: LABORATORY CORPORATION OF AMERICA HOLDIN
Legal Status: Private
Date Became Current: 19981019
Date Ended Current: Not reported
Owner/Operator Address: 358 S MAIN ST
Owner/Operator City,State,Zip: BURLINGTON, NC 27215
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: LABORATORY CORP OF AMERICA HOLDINGS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 358 S MAIN ST
Owner/Operator City,State,Zip: BURLINGTON, NC 27215
Owner/Operator Telephone: 210-735-9461
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NATIONAL HEALTH LABORATORIES AUSTIN
Legal Status: Not reported
Date Became Current: 19981019
Date Ended Current: Not reported
Owner/Operator Address: 711 W 38TH ST STE C 11
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950925
Handler Name: LABCORP - AUSTIN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19981019
Handler Name: LABORATORY CORPORATION OF AMERICA
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

LABORATORY CORPORATION OF AMERICA (Continued) **1004783848**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 621511
NAICS Description: MEDICAL LABORATORIES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005022073

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004783848
Registry ID: 110005022073
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005022073
Name: LABORATORY CORPORATION OF AMERICA
Address: 3701 N LAMAR STE 200
City,State,Zip: AUSTIN, TX 78705

OT2670 **LABCORP AUSTIN** **TX Ind. Haz Waste** **S103613056**
WNW **3701 N LAMAR BLVD STE 200** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.089 mi.
471 ft. **Site 4 of 8 in cluster OT**

Actual:
609 ft.

Focus Map:
8

Ind. Haz Waste:
Name: LABCORP AUSTIN
Address: 3701 N LAMAR BLVD STE 200
City,State,Zip: AUSTIN, TX 78705
Permit Number: Not reported
Registration Number: 83603
Registration Initial Notification Date: 10/13/1994
Registration Last Amendment Date: 10/19/1998
EPA Identification: TX0000933713
Primary NAICS Code: Not reported

LABCORP AUSTIN (Continued) **S103613056**

Status Change Date:	19941013
Land Type:	PRIVATE
Description of Facility Site Location:	3701 N Lamar, Ste 200, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	LABORATORY CORPORATION OF AMERICA HOLDINGS
Contact Name:	BRIAN MORONEY
Contact Telephone Number:	210-7359461
Mailing Address:	6603 FIRST PARK TEN BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	SAN ANTONIO, TX 782134303
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	100848
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040220
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Owner Name:	LABORATORY CORPORATION OF AMERICA HOLDINGS
Owner Mailing Address:	358 S MAIN ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	BURLINGTON, NC 27215
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11337573700

LABCORP AUSTIN (Continued) **S103613056**

Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	272.16
Capacity Measurement:	K
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Flammable liquid storage cabinet. Annex hallway.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19941013
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	711 W 38TH ST STE C11
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	358 S MAIN ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BURLINGTON, NC 27215
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BRIAN MORONEY
Contact Title:	SAFETY & COMPLIANCE OFFIC
Contact Role:	PRICONT
Contact Address:	6603 FIRST PARK TEN BLVD
Contact Address 2:	Not reported

LABCORP AUSTIN (Continued) **S103613056**

Contact Address 3:	Not reported
Contact City,State,Zip:	SAN ANTONIO, TX 78213
Contact Phone:	1-210-7359461
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	123760
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquid wastes (xylene and petroleum naphtha) are generated as human ti
Standard Industrial Code:	80710
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	621511
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

OJ2671 **DEWEYS RADIATOR** **EDR Hist Auto** **1013768890**
SSW **112 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.089 mi.
472 ft. **Site 2 of 2 in cluster OJ**

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1962	DEWEYS RADIATOR	AUTOMOBILE RADIATOR REPAIRERS
1965	DEWEYS RADIATOR WORKS	AUTOMOBILE RADIATOR REPAIRERS
1969	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC
1970	DEWEYS RADIATOR WORKS	Automotive Repair Shops, NEC

2672 ESE < 1/8 0.089 mi. 472 ft. | **CITY CONSERVATION 625 BRENTWOOD ST AUSTIN, TX** | **TX HIST UST** | **S128729542 N/A**

Actual: 709 ft.
Focus Map: 6

HIST UST AUSTIN:

Name:	CITY CONSERVATION
Address:	625 BRENTWOOD ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0130
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PL2673 NW < 1/8 0.090 mi. 473 ft. | **TS CLEANERS AT TWIN OAKS 300 E OLTORF ST AUSTIN, TX 78704** | **TX DRYCLEANERS** | **S106206769 N/A**

Site 1 of 3 in cluster PL

Actual: 599 ft.
Focus Map: 14

DRYCLEANERS:

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	FITASANCH@YAHOO.COM
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	600
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	FITASANCH@YAHOO.COM
Phone Number:	512 4421501

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

Site Name:	Not reported
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	FIFASANCH@YAHOO.COM
Phone Number:	512 4421581
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	30
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	780
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	600
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PETROLEUM
Gallons:	30
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN602476236
DCR Number:	Not reported
AR Number:	24000894
Principal Name:	MARY ROSE HERRERA DBA TWIN OAKS CLEANERS
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	600
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN604099226
DCR Number:	Not reported
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	600
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN604099226
DCR Number:	Not reported
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	720
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	11
CN Number:	CN604099226
DCR Number:	Not reported
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421581
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	25
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported

TS CLEANERS AT TWIN OAKS (Continued) **S106206769**

Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	720
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	TS CLEANERS AT TWIN OAKS
Address:	300 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN103988093
Region:	REGION 11 - AUSTIN
CN Number:	CN604099226
DCR Number:	DCR12405
AR Number:	24006619
Principal Name:	THERESA SANCHEZ
Bill Addr1:	300 E OLTORF ST
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78704 5533
EMail:	Not reported
Phone Number:	512 4421501
Site Name:	TS CLEANERS AT TWIN OAKS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	360
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

PL2674 **GAHAU CLEANERS** **EDR Hist Cleaner** **1013780330**
NW **300 OLTORF ST E** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.090 mi.
473 ft. **Site 2 of 3 in cluster PL**

Actual:
599 ft.
EDR Hist Cleaner

Focus Map:
14

Year:	Name:	Type:
1958	TWIN OAKS CLNS	CLEANERS AND DYERS
1962	TWIN OAKS CLNS	CLEANERS AND DYERS
1965	TWIN OAKS CLEANERS	CLEANERS AND DYERS
1970	TWIN OAKS CLEANERS	CLEANERS AND DYERS
1975	TWIN OAKS CLEANERS	CLEANERS AND DYERS
1980	GAHAU CLEANERS	CLEANERS AND DYERS
1984	GALVAN CLEANERS	CLEANERS AND DYERS

PL2675 NW < 1/8 0.090 mi. 473 ft. | **TWIN OAKS CLEANERS**
300 E OLTORF
AUSTIN, TX 78704
Site 3 of 3 in cluster PL | **EDR Hist Cleaner** | **1019993530**
N/A

Actual: 599 ft.

Focus Map: 14

EDR Hist Cleaner

Year:	Name:	Type:
1969	TWIN OAKS CLEANERS	Drycleaning Plants, Except Rugs
1988	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1989	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1990	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1991	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1992	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1993	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1994	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1995	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1996	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1997	GALVAN CLEANERS	Drycleaning Plants, Except Rugs
1998	GALVAN CLEANERS	Drycleaning Plants, Except Rugs

MN2676 NNE < 1/8 0.090 mi. 476 ft. | **LINCOLN PROPERTY COMPANY**
100 CONGRESS AVE
AUSTIN, TX 78701
Site 9 of 11 in cluster MN | **RCRA NonGen / NLR**
FINDS
ECHO
TX Ind. Haz Waste
TX IHW CORR ACTION
TX CENTRAL REGISTRY | **1000178939**
TXD981058209

Actual: 473 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Lincoln Property Company
Handler Address:	CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981058209
Contact Name:	KEVIN FLEMING CONS
Contact Address:	CONGRESS AVE STE 2180
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-499-8811
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	CONGRESS AVE STE 2180
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Lincoln Property Company
Owner Type:	Private
Operator Name:	Lincoln Property Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LINCOLN PROPERTY COMPANY	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	600 CONGRESS AVE STE 2180
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-499-8811
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: LINCOLN PROPERTY CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: LINCOLN PROPERTY COMPANY
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 600 CONGRESS AVE STE 2180
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-499-8811
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19850728
Handler Name: LINCOLN PROPERTY CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: LINCOLN PROPERTY COMPANY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

FINDS:
Registry ID: 110005084345

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000178939
Registry ID:	110005084345
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005084345
Name:	LINCOLN PROPERTY COMPANY
Address:	100 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701

Ind. Haz Waste:

Name:	LINCOLN PROPERTY
Address:	100 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	66361
Registration Initial Notification Date:	07/22/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981058209
Primary NAICS Code:	Not reported
Status Change Date:	19850722
Land Type:	PRIVATE
Description of Facility Site Location:	100 Congress Ave, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	LINCOLN PROPERTY COMPANY
Contact Name:	KEVIN FLEMING CONS
Contact Telephone Number:	512-4998811
Mailing Address:	600 CONGRESS AVE STE 2180
Mailing Address2:	STE 2180
Mailing City,State,Zip:	AUSTIN, TX 787013238
Mailing County:	UNITED STATES

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Facility Country:	UNITED STATES
TNRCC Facility ID:	21640
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	LINCOLN PROPERTY COMPANY
Operator Address:	600 CONGRESS AVE STE 2180
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4998811
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	17516565219
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	LINCOLN PROPERTY COMPANY
Owner Mailing Address:	600 CONGRESS AVE STE 2180
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4998811
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	17516565219
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	600 CONGRESS AVE STE 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4998811

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	600 CONGRESS AVE STE 2180
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4998811
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	KEVIN FLEMING CONS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	600 CONGRESS AVE STE 2180
Contact Address 2:	STE 2180
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4998811
Contact Fax:	Not reported
Contact Email:	Not reported

IHW CORR ACTION:

Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78701
Program Id:	66361
Location Desc:	TRAVIS
RN NUM:	RN100594738
Status:	INACTIVE
Status Date:	11/05/2002
EDR Link ID:	66361
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	11/22/2002
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600304612
Customer Name:	LINCOLN PROPERTY COMPANY
Customer Legal Name:	Lincoln Property Company
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	8/23/2001

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601385685
Customer Name:	JPI APARTMENT DEVELOPMENT LP
Customer Legal Name:	JPI Apartment Development, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	11/22/2002
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600304612
Customer Name:	LINCOLN PROPERTY COMPANY
Customer Legal Name:	Lincoln Property Company
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: 100 Congress Ave, Austin, TX

Regulated Entity Number: RN100594738
Name: LINCOLN PROPERTY AUSTIN
Address: 100 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-4072
Status: ACTIVE
Status Date: ##########
Customer Number: CN600304612
Customer Name: LINCOLN PROPERTY COMPANY
Customer Legal Name: Lincoln Property Company
Customer Ownership Type: SOLE PROPRIETORSHIP
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 100 Congress Ave, Austin, TX

Regulated Entity Number: RN100594738
Name: LINCOLN PROPERTY AUSTIN
Address: 100 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-4072
Status: ACTIVE
Status Date: ##########
Customer Number: CN601385685
Customer Name: JPI APARTMENT DEVELOPMENT LP
Customer Legal Name: JPI Apartment Development, L.P.
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 11/22/2002
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 100 Congress Ave, Austin, TX

Regulated Entity Number: RN100594738
Name: LINCOLN PROPERTY AUSTIN
Address: 100 CONGRESS AVE
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-4072
Status: ACTIVE
Status Date: ##########
Customer Number: CN601385685
Customer Name: JPI APARTMENT DEVELOPMENT LP
Customer Legal Name: JPI Apartment Development, L.P.
Customer Ownership Type: PARTNERSHIP
Affiliation Begin Date: 11/22/2002
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 100 Congress Ave, Austin, TX

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600304612
Customer Name:	LINCOLN PROPERTY COMPANY
Customer Legal Name:	Lincoln Property Company
Customer Ownership Type:	SOLE PROPRIETORSHIP
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Regulated Entity Number:	RN100594738
Name:	LINCOLN PROPERTY AUSTIN
Address:	100 CONGRESS AVE

LINCOLN PROPERTY COMPANY (Continued) **1000178939**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-4072
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601385685
Customer Name:	JPI APARTMENT DEVELOPMENT LP
Customer Legal Name:	JPI Apartment Development, L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	11/22/2002
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	100 Congress Ave, Austin, TX

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

MN2677 **GRAYBURG OIL CO NO** **EDR Hist Auto** **1013763759**
NNE **100 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.090 mi.
476 ft. **Site 10 of 11 in cluster MN**

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	GRAYBURG OIL CO NO	GASOLINE AND OIL SERVICE STATIONS
1935	MAGNOLIA PET CO STA	GASOLINE AND OIL SERVICE STATIONS
1947	LANGFORD CAL SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
2007	HANOVER	Engine Repair
2013	HANOVER	Engine Repair
2014	HANOVER	Engine Repair

2678 **SUPER TRANSMISSION** **EDR Hist Auto** **1013755548**
WSW **2704 WILSON ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.090 mi.
476 ft.

Actual:
571 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1984	SUPER TRANSMISSION	AUTOMOBILE REPAIRING
1988	LUU AUTO REPAIR TRANSMISSIONS	General Automotive Repair Shops
1989	LUU AUTO REPAIR TRANSMISSIONS	General Automotive Repair Shops
1990	LUU AUTO REPAIR TRANSMISSIONS	General Automotive Repair Shops

PM2679 SW < 1/8 0.090 mi. 476 ft. | **CVS PHARMACY 6945**
4405 E RIVERSIDE DR
AUSTIN, TX 78741

Site 1 of 2 in cluster PM

RCRA-VSQG **1015751250**
FINDS **TXR000081004**
ECHO

Actual: 511 ft.

Focus Map: 15

RCRA Listings:

Date Form Received by Agency:	20220328
Handler Name:	Cvs Pharmacy 6945
Handler Address:	E RIVERSIDE DR
Handler City,State,Zip:	AUSTIN, TX 78741-4726
EPA ID:	TXR000081004
Contact Name:	NICOLE WILKINSON
Contact Address:	CVS DR MC2340
Contact City,State,Zip:	WOONSOCKET, RI 02895-6146
Contact Telephone:	401-770-1732
Contact Fax:	Not reported
Contact Email:	NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:	DIR, CORP ENVR
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	CVS DR MC2340
Mailing City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner Name:	Cole Cv Austin Tx, Llc
Owner Type:	Private
Operator Name:	Cvs Pharmacy Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CVS PHARMACY 6945 (Continued) **1015751250**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220823
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	H

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	P001
Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P012
Waste Description:	Arsenic Oxide As2o3 (Or) Arsenic Trioxide

CVS PHARMACY 6945 (Continued) **1015751250**

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U188
Waste Description: Phenol

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420

CVS PHARMACY 6945 (Continued) **1015751250**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120716
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20040801
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR MC2340
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	CORPORATEENVIRONMENTALTEAM@CVSHEALTH.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420

CVS PHARMACY 6945 (Continued) **1015751250**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20120420
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20120716
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20120420
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CVS PHARMACY INC
Legal Status: Private
Date Became Current: 20120420
Date Ended Current: Not reported
Owner/Operator Address: 1 CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895-6146
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COLE CV AUSTIN TX, LLC
Legal Status: Private
Date Became Current: 20040801
Date Ended Current: Not reported
Owner/Operator Address: 2555 E CAMELBACK RD, STE 400
Owner/Operator City,State,Zip: PHOENIX, AZ 85016
Owner/Operator Telephone: 602-778-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CVS PHARMACY INC	
Legal Status:	Private
Date Became Current:	20120420
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895-6146

CVS PHARMACY 6945 (Continued) **1015751250**

Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140301
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160301
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180301
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220301
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

CVS PHARMACY 6945 (Continued) **1015751250**

Receive Date:	20120716
Handler Name:	CVS PHARMACY INC - STORE 6945
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130226
Handler Name:	CVS PHARMACY 6945
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130503
Handler Name:	CVS PHARMACY 6945
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140218
Handler Name:	CVS PHARMACY 6945
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20141023
Handler Name:	CVS PHARMACY 6945
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

CVS PHARMACY 6945 (Continued) **1015751250**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150217
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180220
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20181206
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20190211
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CVS PHARMACY 6945 (Continued) **1015751250**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20201210
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20211014
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	20220328
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	20220328
Handler Name: CVS PHARMACY 6945	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	20220328
Handler Name: CVS PHARMACY 6945	

CVS PHARMACY 6945 (Continued) **1015751250**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES
NAICS Code:	456110
NAICS Description:	PHARMACIES AND DRUG RETAILERS
NAICS Code:	812922
NAICS Description:	ONE-HOUR PHOTOFINISHING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070737691

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110054865963

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1015751250
Registry ID:	110054865963
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110054865963

CVS PHARMACY 6945 (Continued) **1015751250**

Name:	CVS PHARMACY 6945
Address:	4405 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741

PM2680 **CVS PHARMACY** **TX ASBESTOS** **S112202603**
SW **4405 E RIVERSIDE DR** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.090 mi.
476 ft. **Site 2 of 2 in cluster PM**

Actual:
511 ft.

Focus Map:
15

ASBESTOS:

Name:	CVS PHARMACY
Address:	4405 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/20/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

CVS PHARMACY (Continued) **S112202603**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CVS PHARMACY
Address:	4405 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/16/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	5.9
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported

CVS PHARMACY (Continued) **S112202603**

Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CVS PHARMACY 6945
Address:	4405 E RIVERSIDE DR
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	91378
Registration Initial Notification Date:	04/20/2012
Registration Last Amendment Date:	03/28/2022
EPA Identification:	TXR000081004
Primary NAICS Code:	456110
Status Change Date:	20220530
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1

CVS PHARMACY (Continued) **S112202603**

Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	NON INDUS
Company Name:	CVS PHARMACY INC
Contact Name:	WENDY BRANT
Contact Telephone Number:	401-7651500
Mailing Address:	1 CVS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	WOONSOCKET, RI 028956146
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130345
Site Owner Tax ID:	50340626
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220712
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CVS PHARMACY INC
Operator Address:	1 CVS DR
Operator Address 2:	ATTN WENDY BRANT
Operator Address 3:	Not reported
Operator City,State,Zip:	WOONSOCKET, RI 02895
Operator Country:	UNITED STA
Operator Telephone:	1-401-7651500
Operator Fax Number:	1-401-2160138
Operator Email:	WENDY.BRANT@CVSCAREMARK.COM
Operator Business Type:	Corporation
Operator Tax ID:	10503406265
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CVS PHARMACY INC
Owner Mailing Address:	1 CVS DR
Owner Mailing Address 2:	ATTN WENDY BRANT
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Country:	UNITED STA
Owner Telephone:	1-401-7651500

CVS PHARMACY (Continued) **S112202603**

Owner Fax:	1-401-2160138
Owner Email Address:	WENDY.BRANT@CVSCAREMARK.COM
Owner Business Type:	Corporation
Owner Tax ID:	10503406265
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the back storage area
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150217
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	10 gallon containers in the pharmacy
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20150217
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

CVS PHARMACY (Continued) **S112202603**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1 CVS DR
Contact Address 2:	ATTN WENDY BRANT
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Contact Name:	WENDY BRANT
Contact Title:	CORPORATE ENVIRONMENTAL M
Contact Role:	PRICONT
Contact Address:	1 CVS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	WOONSOCKET, RI 02895
Contact Phone:	1-401-7651500
Contact Fax:	1-401-2160138
Contact Email:	WENDY.BRANT@CVSCAREMARK.COM

Ind. Haz Waste:

Waste ID:	360165
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (SILVER, AMMONIUM THIOSULFATE) 9 PGIII
Standard Industrial Code:	Not reported
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	D011
Primary NAICS Code:	446110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350876
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011801H
Waste Code Status:	INACTIVE
Waste Form:	801

CVS PHARMACY (Continued) **S112202603**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed gas, flammable, n.o.s.,Lighters, Petroleum gases, liquefied, Butane,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE GAS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350871
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1950 Aerosols, [flammable, (each not exceeding 1 L capacity)] 2.1, PG , ERG-1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	AEROSOLS FLAMMABLE
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350872
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0

CVS PHARMACY (Continued) **S112202603**

Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1760 Corrosive liquids, n.o.s. (Sodium Hydroxide, Potassium Carbonate) 8, PG
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BASIC LIQUID CORROS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350874
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids, n.o.s., Rx Flammable Liquids, Isopropyl Alcohol, Ethanol, Com
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	369548
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s.; A new hazardous waste determination has been

CVS PHARMACY (Continued) **S112202603**

	performed
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUID
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350875
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1325 Flammable solids, organic, n.o.s. (Napthalene, Sulfur) 4.1, PG II, ERG-1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	337468
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077114H
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT PHOTO PROCESSING SOLUTIONS CONTAINING SILVER FROM PHOTO LAB PROCESSING
Standard Industrial Code:	Not reported

CVS PHARMACY (Continued) **S112202603**

Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812922
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	369549
Texas Waste Code:	Not reported
Texas Waste Code 2:	0114001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s., Rx Toxic Solids , Ammoniated Mercury, Pesticides,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350870
Texas Waste Code:	Not reported
Texas Waste Code 2:	0125004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids, organic, n.o.s. , Residue Last Contained, Medicine, solid, toxic,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported

CVS PHARMACY (Continued) **S112202603**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ACUTE TOXIC SOLIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350873
Texas Waste Code:	Not reported
Texas Waste Code 2:	0211009H
Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3077 Environmentally hazardous substances, solid, n.o.s. (Mercury, Silver) 9,
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN LAMPS PHOTO
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	380037
Texas Waste Code:	Not reported
Texas Waste Code 2:	0220001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids Acid & Base, Rx Corrosive Liquids Acid & Base, Hypochlorite so
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1

CVS PHARMACY (Continued) **S112202603**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	398686
Texas Waste Code:	Not reported
Texas Waste Code 2:	0224002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Environmentally hazardous substances, solid, n.o.s., Mercury
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	BROKEN FLUORESCENT L
Primary NAICS Code:	446110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	380039
Texas Waste Code:	Not reported
Texas Waste Code 2:	8888001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing liquid, n.o.s., Hydrogen Peroxide, Sodium Hypochlorite
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	446110

CVS PHARMACY (Continued) **S112202603**

EPA Waste Form Code: W001
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: 0-0-0 x0
Mailing Address: 1 CVS DR
Mailing Address 2: Not reported
Mailing City,St,Zip: WOONSOCKET, RI 02895
AR Number: 0000316686
Principal Name: CVS PHARMACY INC
Attention Name: Not reported
Attention Suffix: HWF

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: 0-0-0 x0
Mailing Address: 1 CVS DR
Mailing Address 2: Not reported
Mailing City,St,Zip: WOONSOCKET, RI 02895
AR Number: 0000316686
Principal Name: CVS PHARMACY INC
Attention Name: Not reported
Attention Suffix: HWG

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: 0-0-0 x0
Mailing Address: 1 CVS DR
Mailing Address 2: Not reported
Mailing City,St,Zip: WOONSOCKET, RI 02895
AR Number: 0000316686
Principal Name: CVS PHARMACY INC
Attention Name: Not reported
Attention Suffix: NWG

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: 0-0-0 x0
Mailing Address: 1 CVS DR
Mailing Address 2: Not reported
Mailing City,St,Zip: WOONSOCKET, RI 02895
AR Number: 0000316686
Principal Name: CVS PHARMACY INC
Attention Name: Not reported
Attention Suffix: NWF

PB2681 WNW < 1/8 0.090 mi. 476 ft. — **ACME CLEANERS**, **504 1ST E**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013779907** / **N/A**

Site 6 of 6 in cluster PB

Actual: 446 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1935	ACME CLEANERS	CLOTHES PRESSERS AND CLEANERS

OG2682 SSW < 1/8 0.090 mi. 477 ft. — **B & B GARAGE**, **117 CONGRESS AVE**, **TRAVIS (County), TX 78701** — **EDR Hist Auto** — **1013753160** / **N/A**

Site 3 of 7 in cluster OG

Actual: 473 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	117 19 HENDERSONS GARAGE	AUTOMOBILE GARAGES
1940	B & B GARAGE	AUTOMOBILE REPAIRING
1947	B & B GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1953	B & B GARAGE	AUTOMOBILE REPAIRING
1958	B&B GARAGE REPR	AUTOMOBILE REPAIRING
1962	B&B GARAGE AUTO	AUTOMOBILE REPAIRING
1965	B & B GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1969	B & B GARAGE	General Automotive Repair Shops
1970	B & B GARAGE	AUTOMOBILE REPAIRING
1970	B & B GARAGE	General Automotive Repair Shops
1971	B & B GARAGE	General Automotive Repair Shops
1972	B & B GARAGE	General Automotive Repair Shops
1973	B & B GARAGE	General Automotive Repair Shops
1974	B & B GARAGE	General Automotive Repair Shops
1975	B & B GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	B & B GARAGE	General Automotive Repair Shops

OG2683 SSW < 1/8 0.090 mi. 477 ft. — **MC CULLOUGH D T**, **116 CONGRESS AVE**, **AUSTIN, TX** — **EDR Hist Auto** — **1013755815** / **N/A**

Site 4 of 7 in cluster OG

Actual: 473 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1911	116 18 AUSTIN MOTOR CAR CO	AUTOMOBILE GARAGES
1922	MC CULLOUGH D T	AUTOMOBILE GARAGES

PN2684 ENE < 1/8 0.090 mi. 477 ft. | **HERMAN GARAGE**
608 INTERREGIONAL HWY N
TRAVIS (County), TX 78701
Site 1 of 2 in cluster PN | **EDR Hist Auto** | **1013772712**
N/A

Actual: 471 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1970	HERMAN GARAGE	AUTOMOBILE GARAGES

NW2685 WNW < 1/8 0.090 mi. 477 ft. | **AUSTIN COMMUNITY COLLEGE SKILL CENTER**
824 W 12TH ST
AUSTIN, TX 78701
Site 3 of 5 in cluster NW | **TX Ind. Haz Waste**
TX CENTRAL REGISTRY | **S104854523**
N/A

Actual: 483 ft. Ind. Haz Waste:

Focus Map: 11

Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	72452
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	07/28/1997
EPA Identification:	TXD981910078
Primary NAICS Code:	611310
Status Change Date:	19870501
Land Type:	Not reported
Description of Facility Site Location:	824 W 12th, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN COMMUNITY COLLEGE
Contact Name:	LUANNE ALLEN
Contact Telephone Number:	512-4957113
Mailing Address:	1212 RIO GRANDE ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787011710
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26892
Site Owner Tax ID:	741742036
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

AUSTIN COMMUNITY COLLEGE SKILL CENTER (Continued) **S104854523**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN COMMUNITY COLLEGE
Operator Address:	1212 RIO GRANDE ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4957113
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN COMMUNITY COLLEGE
Owner Mailing Address:	1212 RIO GRANDE ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4957113
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1212 RIO GRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4957113
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1212 RIO GRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701

AUSTIN COMMUNITY COLLEGE SKILL CENTER (Continued) **S104854523**

Contact Phone:	1-512-4957113
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	LUANNE ALLEN
Contact Title:	CAMPUS MANAGER
Contact Role:	PRICONT
Contact Address:	1212 RIO GRANDE ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4957113
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	322003
Texas Waste Code:	Not reported
Texas Waste Code 2:	FKD2206H
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W206
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	7/28/1997

AUSTIN COMMUNITY COLLEGE SKILL CENTER (Continued) **S104854523**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	7/28/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	7/28/1997
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602557092
Customer Name:	SPAW GLASS CONTRACTORS INC
Customer Legal Name:	Spaw Glass Contractors, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/6/2008
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220

AUSTIN COMMUNITY COLLEGE SKILL CENTER (Continued) **S104854523**

Primary NAICS Industry Type Description: Commercial and Institutional Building Construction
Physical Location Description: 824 W 12th, Austin, TX

Regulated Entity Number: RN100707116
Name: AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address: 824 W 12TH ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1702
Status: ACTIVE
Status Date: ##########
Customer Number: CN602557092
Customer Name: SPAW GLASS CONTRACTORS INC
Customer Legal Name: Spaw Glass Contractors, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/6/2008
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236220
Primary NAICS Industry Type Description: Commercial and Institutional Building Construction
Physical Location Description: 824 W 12th, Austin, TX

Regulated Entity Number: RN100707116
Name: AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address: 824 W 12TH ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1702
Status: ACTIVE
Status Date: ##########
Customer Number: CN602557092
Customer Name: SPAW GLASS CONTRACTORS INC
Customer Legal Name: Spaw Glass Contractors, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/6/2008
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236220
Primary NAICS Industry Type Description: Commercial and Institutional Building Construction
Physical Location Description: 824 W 12th, Austin, TX

Regulated Entity Number: RN100707116
Name: AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address: 824 W 12TH ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78701-1702
Status: ACTIVE
Status Date: 1800-01-01
Customer Number: CN600269211
Customer Name: AUSTIN COMMUNITY COLLEGE
Customer Legal Name: Austin Community College
Customer Ownership Type: OTHER GOVERNMENT
Affiliation Begin Date: 1997-07-28
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 236220
Primary NAICS Industry Type Description: Commercial and Institutional Building Construction
Physical Location Description: 824 W 12th, Austin, TX

AUSTIN COMMUNITY COLLEGE SKILL CENTER (Continued) **S104854523**

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600269211
Customer Name:	AUSTIN COMMUNITY COLLEGE
Customer Legal Name:	Austin Community College
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	1997-07-28
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN602557092
Customer Name:	SPAW GLASS CONTRACTORS INC
Customer Legal Name:	Spaw Glass Contractors, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2008-09-06
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Regulated Entity Number:	RN100707116
Name:	AUSTIN COMMUNITY COLLEGE SKILL CENTER
Address:	824 W 12TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-1702
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN602557092
Customer Name:	SPAW GLASS CONTRACTORS INC
Customer Legal Name:	Spaw Glass Contractors, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2008-09-06
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	824 W 12th, Austin, TX

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

NW2686 **AUSTIN COMMUNITY COLLEGE** **RCRA NonGen / NLR** **1000412208**
WNW **824 W 12TH** **FINDS** **TXD981910078**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.090 mi.
477 ft. **Site 4 of 5 in cluster NW**

Actual:
483 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	19970728
Handler Name:	Austin Community College
Handler Address:	W 12TH
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981910078
Contact Name:	LUANNE ALLEN
Contact Address:	RIO GRANDE
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-495-7113
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	RIO GRANDE
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Austin Community College
Owner Type:	Municipal
Operator Name:	Austin Community College
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

AUSTIN COMMUNITY COLLEGE (Continued) **1000412208**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE	
Legal Status:	Municipal
Date Became Current:	19970728
Date Ended Current:	Not reported
Owner/Operator Address:	1212 RIO GRANDE
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-495-7113
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN COMMUNITY COLLEGE	
Legal Status:	Municipal
Date Became Current:	19970728
Date Ended Current:	Not reported
Owner/Operator Address:	1212 RIO GRANDE
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-495-7113
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

AUSTIN COMMUNITY COLLEGE (Continued) **1000412208**

Owner/Operator Indicator: Owner
Owner/Operator Name: DISTRICT
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870427
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970728
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: AUSTIN COMMUNITY COLLEGE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61131
NAICS Description: COLLEGES, UNIVERSITIES, AND PROFESSIONAL SCHOOLS

AUSTIN COMMUNITY COLLEGE (Continued) **1000412208**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005099712

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412208
Registry ID:	110005099712
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005099712
Name:	AUSTIN COMMUNITY COLLEGE
Address:	824 W 12TH
City,State,Zip:	AUSTIN, TX 78701

MN2687 **PINNERGY** **TX Ind. Haz Waste** **S118941506**
NNE **111 CONGRESS AVE STE 2020** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.090 mi.
477 ft. **Site 11 of 11 in cluster MN**

Actual:
473 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	PINNERGY
Address:	111 CONGRESS AVE STE 2020
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	96523
Registration Initial Notification Date:	09/27/2016
Registration Last Amendment Date:	09/27/2016
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	20160927
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1

PINNERGY (Continued) **S118941506**

Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	PINNERGY LTD
Contact Name:	JOSH RICH
Contact Telephone Number:	512-3438880
Mailing Address:	111 CONGRESS AVE STE 2020
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787014080
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	131868
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20160927
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	1
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	PINNERGY LTD
Operator Address:	111 CONGRESS AVE STE 2020
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	0-512-3438880 x2837
Operator Fax Number:	0-512-3438885
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	17524097866
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	PINNERGY LTD
Owner Mailing Address:	111 CONGRESS AVE STE 2020
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	0-512-3438880 x2837
Owner Fax:	0-512-3438885
Owner Email Address:	Not reported

PINNERGY (Continued) **S118941506**

Owner Business Type: Other/Misc
Owner Tax ID: 17524097866
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNOPRCON
Contact Address: 111 CONGRESS AVE STE 2020
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78701
Contact Phone: 0-512-3438880 x2837
Contact Fax: 0-512-3438885
Contact Email: Not reported

Contact Name: JOSH RICH
Contact Title: VICE PRESIDENT HSE
Contact Role: PRICONT
Contact Address: 111 CONGRESS AVE STE 2020
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78701
Contact Phone: 1-512-3438880
Contact Fax: 1-512-3438885
Contact Email: JRICH@PINNERGY.COM

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: 0-512-3438880 x0
Mailing Address: 111 CONGRESS AVE STE 2020
Mailing Address 2: Not reported
Mailing City,St,Zip: AUSTIN, TX 78701
AR Number: Not reported
Principal Name: PINNERGY LTD
Attention Name: Not reported
Attention Suffix: Not reported

2688 ESE < 1/8 0.090 mi. 477 ft. | **ONE HOUR MARTINIZING**
704 W 29TH ST
AUSTIN, TX | **EDR Hist Cleaner** | **1013779126**
N/A

Actual: 589 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1965	ONE HOUR MARTINIZING	CLEANERS AND DYERS
1970	ONE HOUR MARTINIZING NO	CLEANERS AND DYERS

OK2689 **413 15 POWELL GARAGE & BODY** **EDR Hist Auto** **1013768065**
SW **413 COLORADO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.091 mi.
478 ft. **Site 17 of 21 in cluster OK**

Actual:
489 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	413 15 POWELL GARAGE & BODY	AUTOMOBILE GARAGES

OV2690 **E L STECK** **TX HIST UST** **S111678630**
ESE **217 W 9TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.091 mi.
478 ft. **Site 2 of 2 in cluster OV**

Actual:
539 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	E L STECK
Address:	217 W 9TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0177
HID UST:	177
Inspection:	Not reported
Due:	06/01/2012

2691 **GRAY P B DCLO CLNR** **EDR Hist Cleaner** **1013787445**
NE **4413 AVENUE B** **N/A**
< 1/8 **HYDE PARK, TX**
0.091 mi.
478 ft.

Actual:
630 ft.
EDR Hist Cleaner

Focus Map:
8

Year:	Name:	Type:
1935	GRAY P B DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

OH2692 **PARKING GARAGE N** **TX UST** **U004144057**
WNW **300 SAN ANTONIO ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.091 mi.
478 ft. **Site 5 of 5 in cluster OH**

Actual:
472 ft.
UST:

Focus Map:
11

Name:	PARKING GARAGE N
Address:	300 SAN ANTONIO ST
City,State,Zip:	AUSTIN, TX 787013834
AI Number:	72718
Facility Type:	Not reported
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	517234992002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1

PARKING GARAGE N (Continued) **U004144057**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/05/2022
Signature Name/Title On Earliest Reg Form:	RICHARD BRYANT,OPERATOR
Application Received Date On Earliest Reg Form:	01/10/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	167546612009246
Additional ID:	517234992002117
Ai Number:	72718
Operator CN:	CN603527441
Operator Name:	TEXAS FACILITIES COMMISSION
Operator Effective Begin Date:	08/31/1995
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78711-3047
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9000333
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603527441
Owner Last Name:	TEXAS FACILITIES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX

PARKING GARAGE N (Continued) **U004144057**

Contact Mailing Zip:	78711
Contact Mailing Zip5:	3047
Contact Phone Number/Ext:	1 512 9000333/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	RICHARD.BRYANT@TFC.STATE.TX.US
Contact Address Deliverable:	Not reported
Princ ID:	167546612009246
Additional ID:	517234992002117
AI Number:	72718
Owner Effective Begin Date:	08/31/1995
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	RICHARD BRYANT/GENERATOR TECH
Contact Organization Name:	TEXAS FACILITIES COMMISSION

Self Certification:

Self Cert ID:	110705
Cert ID:	383129
AI Number:	72718
Self Certification Date:	01/09/2023
Signature Name/Title:	RICHARD BRYANT FACILITY MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	366805
AI Number:	72718
Self Certification Date:	01/05/2022
Signature Name/Title:	RICHARD BRYANT OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	350453

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	01/12/2021
Signature Name/Title:	RICHARD BRYANT FAC OPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	330339
AI Number:	72718
Self Certification Date:	01/02/2020
Signature Name/Title:	RICHARD BRYANT TFFA CLASS AB FAC OPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	315379
AI Number:	72718
Self Certification Date:	01/25/2019
Signature Name/Title:	JEFFERY PARNELL ELECTRICIAN III
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	310415

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	09/20/2018
Signature Name/Title:	JONATHAN HICKMAN OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	281061
AI Number:	72718
Self Certification Date:	01/10/2017
Signature Name/Title:	KEN HULIN FAC MAINT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	265496
AI Number:	72718
Self Certification Date:	01/16/2016
Signature Name/Title:	KEN HULIN ELECTRICAL SUPV
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	248019

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	01/27/2015
Signature Name/Title:	KEN HULIN ELEC SUPERVISOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	230643
AI Number:	72718
Self Certification Date:	01/16/2014
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	110705
Cert ID:	190258
AI Number:	72718
Self Certification Date:	02/12/2013
Signature Name/Title:	KEN HULIN ELEC SUPVR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190257

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	01/31/2012
Signature Name/Title:	KEN HULIN ELEC SUPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190256
AI Number:	72718
Self Certification Date:	02/11/2011
Signature Name/Title:	KEN HULIN ELECTRICAL SPVR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190255
AI Number:	72718
Self Certification Date:	01/05/2010
Signature Name/Title:	JONATHAN HICKMAN ELECTRICAL SUPER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190254

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	09/18/2009
Signature Name/Title:	JONATHAN HICKMAN ELEC SUPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190253
AI Number:	72718
Self Certification Date:	02/20/2004
Signature Name/Title:	MEL BULLOCK FACILITY MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190252
AI Number:	72718
Self Certification Date:	01/15/2003
Signature Name/Title:	JOHN BOREMAN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	110705
Cert ID:	190251

PARKING GARAGE N (Continued) **U004144057**

AI Number:	72718
Self Certification Date:	02/09/2001
Signature Name/Title:	WAYNE WILSON ESD DIV DIR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	10/17/1995
Tank Registration Date:	12/03/1999
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	192851
Facility ID:	110705
Ai Number:	72718
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	10/17/1995
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

PARKING GARAGE N (Continued) **U004144057**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	167457
UST ID:	192851
AI Number:	72718
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

PARKING GARAGE N (Continued) **U004144057**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	41234
Facility ID:	110705
AI Number:	72718
Application Received Date:	02/20/2023
Scheduled Construction Date:	03/06/2023
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS FACILITIES COMMISSION
Owner CN At Time Of Construction:	CN603527441
Owner AR At Time Of Construction:	55232
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	98803
UST ID:	Not reported
NOC ID:	41234
AI Number:	72718
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	CHRIS MAYS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

PARKING GARAGE N (Continued) **U004144057**

Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	SUSAN.ROLLINS@EXCELLFS.COM

Facility Billing Contacts:

Contact Organization Name:	TEXAS FACILITIES COMMISSION
Contact Mailing Address (Delivery):	PO BOX 13047
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78711 3047
Phone Number/Ext:	512 9000333/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	110705
Additional ID:	517234992002117
Princ ID:	167546612009246
AI Number:	72718
Facility Name:	PARKING GARAGE N
AR Number:	55232
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	RICHARD BRYANT/

HIST UST AUSTIN:

Name:	HOBBY COMPLEX PARKING GARAGE
Address:	300 SAN ANTONIO ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX076
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

OW2693 **LANG CLEANERS** **EDR Hist Cleaner** **1013780785**
WNW **208 13TH W** **N/A**
< 1/8 **AUSTIN, TX**
0.091 mi.
479 ft. **Site 2 of 2 in cluster OW**

Actual:
538 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1929	LANG CLEANERS	CLOTHES CLEANERS AND PRESSERS

PH2694 WNW < 1/8 0.091 mi. 479 ft. | **KASPER CHAS E CLNS** | **EDR Hist Cleaner** | **1013778109** | **N/A**
3810 LAMAR BLVD N
AUSTIN, TX

Site 3 of 4 in cluster PH

Actual: 613 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1962	KASPER CHAS E CLNS	CLEANERS AND DYERS
1965	KASPER CHARLES E CLEANERS	CLEANERS AND DYERS

OK2695 WSW < 1/8 0.091 mi. 479 ft. | **MAGNOLIA PET CO NO** | **EDR Hist Auto** | **1013763897** | **N/A**
212 5TH ST W
AUSTIN, TX

Site 18 of 21 in cluster OK

Actual: 491 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1929	MAGNOLIA PET CO NO	GASOLINE AND OIL SERVICE STATIONS

MQ2696 ENE < 1/8 0.091 mi. 479 ft. | **JAMES BOYCE** | **TX HIST UST** | **S111678701** | **N/A**
5021 E CSSAR CHAVEZ ST
AUSTIN, TX

Site 18 of 18 in cluster MQ

Actual: 586 ft. HIST UST AUSTIN:

Focus Map: 8

Name:	JAMES BOYCE
Address:	5021 E CSSAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0343
HID UST:	817
Inspection:	10/21/2010
Due:	10/21/2013

PN2697 ENE < 1/8 0.091 mi. 481 ft. | **ADAMS QUADRACYCLE** | **EDR Hist Auto** | **1013752967** | **N/A**
610 INTERREGIONAL HWY N
TRAVIS (County), TX 78701

Site 2 of 2 in cluster PN

Actual: 471 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	ADAMS QUADRACYCLE	MOTORCYCLE DEALERS AND REPAIRERS

PO2698 ESE < 1/8 0.091 mi. 482 ft. | **JOHNSONS GARAGE**
504 7TH W
AUSTIN, TX
Site 1 of 2 in cluster PO | **EDR Hist Auto** | **1013763766**
N/A

Actual: 482 ft.
EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	JOHNSONS GARAGE	AUTOMOBILE REPAIRING

OI2699 WNW < 1/8 0.091 mi. 482 ft. | **D. A. GROVER**
501 W 6TH ST
AUSTIN, TX
Site 14 of 15 in cluster OI | **TX HIST UST** | **S128729188**
N/A

Actual: 480 ft.
HIST UST AUSTIN:

Focus Map: 11

Name:	D. A. GROVER
Address:	501 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0118
HID UST:	118
Inspection:	Not reported
Due:	06/01/2012

OI2700 WNW < 1/8 0.091 mi. 482 ft. | **D. A. GROVER**
501 W 6TH ST
AUSTIN, TX
Site 15 of 15 in cluster OI | **TX HIST UST** | **S128729190**
N/A

Actual: 480 ft.
HIST UST AUSTIN:

Focus Map: 11

Name:	D. A. GROVER
Address:	501 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0123
HID UST:	123
Inspection:	Not reported
Due:	06/01/2012

OK2701 WSW < 1/8 0.091 mi. 482 ft. | **EAST 9TH STREET COMPANY LP**
201 W 5TH ST STE 220
AUSTIN, TX 78701
Site 19 of 21 in cluster OK | **EDR Hist Auto** | **1020397739**
N/A

Actual: 490 ft.
EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
2003	EAST 9TH STREET COMPANY LP	Gasoline Service Stations

OK2702 **TX HIST UST** **S111678159**
WSW **201 W 5TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.091 mi.
482 ft. **Site 20 of 21 in cluster OK**

Actual:
490 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	201 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0060
HID UST:	60
Inspection:	03/06/2009
Due:	03/06/2012

2703 **WILSON OXYGEN & SUPPLY** **TX UST** **U001274053**
ESE **150 E BEN WHITE BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.092 mi.
484 ft.

Actual:
664 ft.

Focus Map:
14

UST:

Name:	WILSON OXYGEN & SUPPLY
Address:	150 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047210
AI Number:	41712
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1989
Facility Status:	INACTIVE
Additional ID:	591379572002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	WILSON OXYGEN & SUPPLY CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124446533
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	SAM A WILSON,PRES.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600803456
Owner Last Name:	TEXAS DEPARTMENT OF TRANSPORTATION

WILSON OXYGEN & SUPPLY (Continued) **U001274053**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	976653722002061
Additional ID:	591379572002075
AI Number:	41712
Owner Effective Begin Date:	09/01/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	110476
Facility ID:	73761
Ai Number:	41712
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

WILSON OXYGEN & SUPPLY (Continued) **U001274053**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	104236
UST ID:	110476
AI Number:	41712
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

WILSON OXYGEN & SUPPLY (Continued) **U001274053**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	110477
Facility ID:	73761
Ai Number:	41712
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

WILSON OXYGEN & SUPPLY (Continued) **U001274053**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	104237
UST ID:	110477
AI Number:	41712
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

WILSON OXYGEN & SUPPLY (Continued) **U001274053**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Mailing Address (Delivery):	PO BOX 15426
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78761 5426
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	73761
Additional ID:	591379572002075
Princ ID:	976653722002061
AI Number:	41712
Facility Name:	WILSON OXYGEN & SUPPLY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GENE STABENO/

HIST UST AUSTIN:

Name:	WILSON OXYGEN CO.
Address:	150 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0414
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PA2704 **CHOTES SINCLAIR SERVICE** **EDR Hist Auto** **1013753499**
East **500 W 19TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.092 mi.
485 ft. **Site 10 of 10 in cluster PA**

Actual:
555 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1965	CHOTES SINCLAIR SERVICE	GASOLINE STATIONS
1969	CHOTES SINCLAIR SERVICE STN	Gasoline Service Stations
1970	CHOTES SINCLAIR SERVICE STATION	GASOLINE STATIONS
1970	CHOTES SINCLAIR SERVICE STN	Gasoline Service Stations
1971	CHOTES SINCLAIR SERVICE STN	Gasoline Service Stations
1972	CHOTES ARCO SERVICE STATION	Gasoline Service Stations
1973	CHOTES ARCO SERVICE STATION	Gasoline Service Stations
1974	CHOTES ARCO SERVICE STATION	Gasoline Service Stations
1975	CHOTES ARCO SERVICE STATION	GASOLINE STATIONS
1975	CHOTES ARCO SERVICE STATION	Gasoline Service Stations

CHOTES SINCLAIR SERVICE (Continued) **1013753499**

1976	CHOTES ARCO SERVICE STATION	Gasoline Service Stations
1977	CHOTES ARCO SERVICE STATION	Gasoline Service Stations

2705 SE < 1/8 0.092 mi. 485 ft.

FURROW BUILDING MATERIALS
8319 N LAMAR
AUSTIN, TX 78753

RCRA-VSQG **1004786572**
FINDS **TXD988078606**
ECHO

Actual: 713 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	19920921
Handler Name:	Furrow Building Materials
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD988078606
Contact Name:	DAVE MCKEE
Contact Address:	PO BOX 419466
Contact City,State,Zip:	KANSAS CITY, MO 64141-0466
Contact Telephone:	817-234-6000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 419466
Mailing City,State,Zip:	KANSAS CITY, MO 64141-0466
Owner Name:	Payless Cashways Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

FURROW BUILDING MATERIALS (Continued) **1004786572**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAYLESS CASHWAYS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 419466
Owner/Operator City,State,Zip:	KANSAS CITY, MO 64141-0466
Owner/Operator Telephone:	816-234-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19920921
Handler Name: FURROW BUILDING MATERIALS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

FURROW BUILDING MATERIALS (Continued) **1004786572**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005154082

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004786572
Registry ID: 110005154082
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005154082
Name: FURROW BUILDING MATERIALS
Address: 8319 N LAMAR
City,State,Zip: AUSTIN, TX 78753

NT2706 **WESLEY GEORGE M TAILOR** **EDR Hist Cleaner** **1013778384**
NNE **404 CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.092 mi.
486 ft. **Site 3 of 3 in cluster NT**

Actual:
484 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1911	WESLEY GEORGE M TAILOR	CLOTHES PRESSERS AND CLEANERS

OG2707 NNE < 1/8 0.092 mi. 488 ft. | **DARRELL ROYAL WORK SHOP**
104 CONGRESS AVE
TRAVIS (County), TX 78701
Site 5 of 7 in cluster OG | **EDR Hist Auto** | **1013756994**
N/A

Actual: 473 ft.

EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1975	DARRELL ROYAL WORK SHOP	REPAIR SHOPS

PP2708 SE < 1/8 0.092 mi. 488 ft. | **HELIOVOLT**
8201 E RIVERSIDE DR
AUSTIN, TX 78744
Site 1 of 6 in cluster PP | **RCRA NonGen / NLR** | **1010334827**
TXR000077969

Actual: 502 ft.

Focus Map: 19

RCRA Listings:

Date Form Received by Agency:	20110208
Handler Name:	Heliovolt
Handler Address:	8201 E RIVERSIDE DR
Handler City,State,Zip:	AUSTIN, TX 78744-1604
EPA ID:	TXR000077969
Contact Name:	HERBERT GANZ
Contact Address:	6301 E STASSNEY LN
Contact City,State,Zip:	AUSTIN, TX 78744-3055
Contact Telephone:	512-767-6079
Contact Fax:	Not reported
Contact Email:	HGANZ@HELIOVOLT.COM
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	6301 E STASSNEY LN
Mailing City,State,Zip:	AUSTIN, TX 78744-3055
Owner Name:	Heliovolt Corporation,
Owner Type:	Private
Operator Name:	Heliovolt Corporation,
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

HELIOVOLT (Continued) **1010334827**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140203
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years

Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D034
Waste Description:	Hexachloroethane
Waste Code:	P022
Waste Description:	Carbon Disulfide

HELIOVOLT (Continued) **1010334827**

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20091124
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION,
Legal Status: Private
Date Became Current: 20090801
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN
Owner/Operator City,State,Zip: AUSTIN, TX 78744-3055
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

HELIOVOLT (Continued) **1010334827**

Owner/Operator Indicator:	Operator
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20090819
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20091006
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20090602
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20090728
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20090819
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported

HELIOVOLT (Continued) **1010334827**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20091124
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20100112
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN
Owner/Operator City,State,Zip: AUSTIN, TX 78744-3055
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090602
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600

HELIOVOLT (Continued) **1010334827**

Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20091006
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20100112
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20100119
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private

HELIOVOLT (Continued) **1010334827**

Date Became Current:	20090616
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20100223
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20100223
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HELIOVOLT CORPORATION	
Legal Status:	Private
Date Became Current:	20100504
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HELIOVOLT CORPORATION,	
Legal Status:	Private
Date Became Current:	20070316
Date Ended Current:	Not reported
Owner/Operator Address:	6301 E STASSNEY LN
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-3055
Owner/Operator Telephone:	512-767-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

HELIOVOLT (Continued) **1010334827**

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090203
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION,
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN
Owner/Operator City,State,Zip: AUSTIN, TX 78744-3055
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090801
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN
Owner/Operator City,State,Zip: AUSTIN, TX 78744-3055
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20100119
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported

HELIOVOLT (Continued) **1010334827**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20100504
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN BLDG 8100
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION,
Legal Status: Private
Date Became Current: 20090801
Date Ended Current: Not reported
Owner/Operator Address: 6301 E STASSNEY LN
Owner/Operator City,State,Zip: AUSTIN, TX 78744-3055
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20070316
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090203
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090616
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600

HELIOVOLT (Continued) **1010334827**

Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HELIOVOLT CORPORATION
Legal Status: Private
Date Became Current: 20090728
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-767-6000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100301
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070420
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070515
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

HELIOVOLT (Continued) **1010334827**

Receive Date: 20070521
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090203
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090602
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090616
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090728
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No

HELIOVOLT (Continued) **1010334827**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090819
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091006
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091124
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100112
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

HELIOVOLT (Continued) **1010334827**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100119
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100223
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100504
Handler Name: HELIOVOLT CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20101122
Handler Name: HELIOVOLT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110208
Handler Name: HELIOVOLT

HELIOVOLT (Continued) **1010334827**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	334418
NAICS Description:	PRINTED CIRCUIT ASSEMBLY (ELECTRONIC ASSEMBLY) MANUFACTURING
NAICS Code:	541712
NAICS Description:	RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING, AND LIFE SCIENCES (EXCEPT BIOTECHNOLOGY)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

PP2709 **EBARA TECHNOLOGIES INC** **RCRA NonGen / NLR** **1004788025**
SE **8201 E RIVERSIDE DR STE 600** **FINDS** **TXR000036145**
< 1/8 **AUSTIN, TX 78744** **ECHO**
0.092 mi.
488 ft. **Site 2 of 6 in cluster PP**

Actual:
502 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20060607
Handler Name:	Ebara Technologies Inc
Handler Address:	E RIVERSIDE DR STE 600
Handler City,State,Zip:	AUSTIN, TX 78744
EPA ID:	TXR000036145
Contact Name:	MIKE MCCLUNG
Contact Address:	FREIDRICH LN STE 120
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Telephone:	512-389-3993
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	FREIDRICH LN STE 120
Mailing City,State,Zip:	AUSTIN, TX 78744

EBARA TECHNOLOGIES INC (Continued) **1004788025**

Owner Name:	Ebara Technologies Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

EBARA TECHNOLOGIES INC (Continued) **1004788025**

Waste Code: D004
Waste Description: Arsenic

Waste Code: D008
Waste Description: Lead

Waste Code: D034
Waste Description: Hexachloroethane

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EBARA TECHNOLOGIES INC	
Legal Status:	Private
Date Became Current:	20050708
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-389-3993
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: EBARA TECHNOLOGIES INC	
Legal Status:	Private
Date Became Current:	20050708
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-389-3993
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: EBARA TECHNOLOGIES INC	
Legal Status:	Not reported
Date Became Current:	20031028
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip:	AUSTIN, TX 78744
Owner/Operator Telephone:	512-389-3993
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EBARA CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 1 HON FUJISAWA 4 C HOME
Owner/Operator City,State,Zip:	FUJISAWA 00000
Owner/Operator Telephone:	814-668-2561
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

EBARA TECHNOLOGIES INC (Continued) **1004788025**

Owner/Operator Indicator: Owner
Owner/Operator Name: EBARA TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20031028
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EBARA TECHNOLOGIES INC
Legal Status: Not reported
Date Became Current: 20031028
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-389-3993
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EBARA TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20031028
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DRIVE SUITE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EBARA TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20050708
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 600
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: 512-389-3993
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000614
Handler Name: EBARA TECHNOLOGIES INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

EBARA TECHNOLOGIES INC (Continued) **1004788025**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20031028
Handler Name: EBARA TECHNOLOGIES INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20050708
Handler Name: EBARA TECHNOLOGIES INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060607
Handler Name: EBARA TECHNOLOGIES INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040301
Handler Name: EBARA TECHNOLOGIES INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

EBARA TECHNOLOGIES INC (Continued) **1004788025**

List of NAICS Codes and Descriptions:
NAICS Code: 333912
NAICS Description: AIR AND GAS COMPRESSOR MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070745631

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110005188411

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004788025
Registry ID: 110005188411
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005188411
Name: EBARA TECHNOLOGIES INC
Address: 8201 E RIVERSIDE DR STE 600
City,State,Zip: AUSTIN, TX 78744

PP2710 **PENTAGON TECHNOLOGIES GROUP** **RCRA-SQG** **1001489993**
SE **8201 E RIVERSIDE DR BLDG 5** **TX AIRS** **TXR000031542**
< 1/8 **AUSTIN, TX 78744** **TX Ind. Haz Waste**
0.092 mi. **TX IHW CORR ACTION**
488 ft. **Site 3 of 6 in cluster PP** **TX CENTRAL REGISTRY**

Actual:
502 ft.

Focus Map:
19

RCRA Listings:
Date Form Received by Agency: 20190905
Handler Name: Pentagon Technologies Group
Handler Address: 8201 E RIVERSIDE DR BLDG 5
Handler City,State,Zip: AUSTIN, TX 78744-1601
EPA ID: TXR000031542
Contact Name: THOMAS HAMPSON
Contact Address: 8201 E RIVERSIDE DR BLDG 5
Contact City,State,Zip: AUSTIN, TX 78744-1601
Contact Telephone: 512-386-7250

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	8201 E RIVERSIDE DR BLDG 5
Mailing City,State,Zip:	AUSTIN, TX 78744-1601
Owner Name:	Mpw Industrial Services Inc
Owner Type:	Private
Operator Name:	Pentagon Technologies Group Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190913
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER ROAD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: 800-827-8790
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20090127
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20090127
Date Ended Current: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Not reported
Date Became Current: 20031112
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Not reported
Date Became Current: 20040329
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20090623
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025-9640
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Legal Status: Not reported
Date Became Current: 20040329
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20100223
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20100622
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025-9640
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025-9640
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Not reported
Date Became Current: 20031112
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025-9640
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20080930
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1601
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20040329
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20060308
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20090623
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1601
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Owner/Operator City,State,Zip: AUSTIN, TX 78744-1601
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1601
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20060308
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20080930
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Date Became Current: 20100223
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20100525
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20100525
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025-9640
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MPW INDUSTRIAL SERVICES INC
Legal Status: Private
Date Became Current: 20060713
Date Ended Current: Not reported
Owner/Operator Address: 9211 LANCASTER RD
Owner/Operator City,State,Zip: HEBRON, OH 43025
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20100622
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 19990524
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1601
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENTAGON TECHNOLOGIES GROUP INC
Legal Status: Private
Date Became Current: 20040329
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR BLDG 5
Owner/Operator City,State,Zip: AUSTIN, TX 78744
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990602
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20031112
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040329
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060308
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060718
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Receive Date: 20000125
Handler Name: PENTAGON TECHNOLOGIES GROUP, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040301
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080930
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090127
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090623
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100223
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100525
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100622
Handler Name: PENTAGON TECHNOLOGIES GROUP INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150428
Handler Name: PENTAGON TECHNOLOGIES GROUP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150807
Handler Name: PENTAGON TECHNOLOGIES GROUP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160516
Handler Name: PENTAGON TECHNOLOGIES GROUP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160516
Handler Name: PENTAGON TECHNOLOGIES GROUP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190905
Handler Name: PENTAGON TECHNOLOGIES GROUP

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	514199
NAICS Description:	ALL OTHER INFORMATION SERVICES
NAICS Code:	54162
NAICS Description:	ENVIRONMENTAL CONSULTING SERVICES
NAICS Code:	54199
NAICS Description:	ALL OTHER PROFESSIONAL, SCIENTIFIC, AND TECHNICAL SERVICES

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20100218
Actual Return to Compliance Date:	20100324
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100223
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20100218
Actual Return to Compliance Date:	20100324
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100223
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100218
Actual Return to Compliance Date: 20100324
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20100218
Actual Return to Compliance Date: 20100324
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20100218
Actual Return to Compliance Date:	20100324
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100223
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20100218
Actual Return to Compliance Date:	20100324
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100223
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100218
Actual Return to Compliance Date: 20100324
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20100223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined:	20100218
Actual Return to Compliance Date:	20100324
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20100223
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20140708
Actual Return to Compliance Date:	20140718
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20140708
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20100218
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: 20100324
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20040224
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20100218
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: 20100324

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020917
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100420
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100218
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100324
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20140708
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20140718
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

AIRS:

Name:	PENTAGON TECH AUSTIN
Address:	8201 E RIVERSIDE DR BLDG 5
City,State,Zip:	TX
Permit Num:	50732
Regulated Id:	RN100562818
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	06/07/2002
Expiration Date:	12/31/3000
Customer Id:	CN600273577
Company Name:	PENTAGON TECHNOLOGIES GROUP INC
Physical Location Desc:	8201 E Riverside Dr, Bldg 5, Austin, TX
Rep Official(RO):	DIRECTOR OF OPERATIONS-AUSTIN
RO Name:	MR JAMES R STONESTREET
RO Delivery Address:	8201 E RIVERSIDE DR BLDG 5
RO City/State/Zip:	AUSTIN, T 78744-160
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

Ind. Haz Waste:

Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	86110
Registration Initial Notification Date:	05/24/1999
Registration Last Amendment Date:	09/05/2019
EPA Identification:	TXR000031542
Primary NAICS Code:	541990
Status Change Date:	19990524
Land Type:	PRIVATE
Description of Facility Site Location:	8201 E Riverside Dr, Bldg 5, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	MPW INDUSTRIAL WATER SERVICES INC
Contact Name:	THOMAS HAMPSON
Contact Telephone Number:	512-3867250
Mailing Address:	8201 E RIVERSIDE DR BLDG 5
Mailing Address2:	BLDG 5
Mailing City,State,Zip:	AUSTIN, TX 787441601
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	109596
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	PENTAGON TECHNOLOGIES GROUP INC
Operator Address:	8201 E RIVERSIDE DR BLDG 5
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78744
Operator Country:	UNITED STA
Operator Telephone:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	13116223606
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MPW INDUSTRIAL WATER SERVICES INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13116295950
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	100
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	100
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	120
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Unit Number:	007
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	135
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	END OF PROCESS DISCHARGE TO POTW ONLY
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	008
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	009
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	010
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	011
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	012
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	013
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	014
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19990524
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	015
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020221
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	016
Unit Type Code:	13
Unit Status:	ACTIVE

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	POTW ONLY AND NO UNITS RCRA REGULATED
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020221
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	017
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Reaction/neutralization tank
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020221
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	018
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Reaction/neutralization tank
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20020221
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	019
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	1000
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Spent caustic used in neutralization of waste water prior to duscharge to t he
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20030314
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8201 E RIVERSIDE DR BLDG 5
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	9211 LANCASTER RD

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HEBRON, OH 43025
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	THOMAS HAMPSON
Contact Title:	ENGINEERING MANAGER
Contact Role:	PRICONT
Contact Address:	8201 E RIVERSIDE DR BLDG 5
Contact Address 2:	BLDG 5
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-3867250
Contact Fax:	1-512-3867252
Contact Email:	thampson@pen-tec.com

Ind. Haz Waste:

Waste ID:	176239
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acidic rinse water; rinsing of metal or ceramic tooling that is removed from aci
Standard Industrial Code:	89990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176240
Texas Waste Code:	Not reported
Texas Waste Code 2:	00021141
Waste Code Status:	ACTIVE
Waste Form:	114
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Neutralized rinse water; following neutralization of corrosive rinse water in th
Standard Industrial Code:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	176241
Texas Waste Code:	Not reported
Texas Waste Code 2:	00045041
Waste Code Status:	INACTIVE
Waste Form:	504
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Inorganic wastewater treatment sludge; from filter press unit after neutralizedr
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	176242
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent acid; metal and ceramic cleaning process baths; 6/15/99.
Standard Industrial Code:	89990
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W103

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 176243
Texas Waste Code: Not reported
Texas Waste Code 2: 00061142
Waste Code Status: INACTIVE
Waste Form: 114
Waste Classification: 2
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Soapy rinse water; manual cleaning and rinsing of metal or ceramics; 6/15/99. Ma
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 1
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 176244
Texas Waste Code: Not reported
Texas Waste Code 2: 00073892
Waste Code Status: ACTIVE
Waste Form: 389
Waste Classification: 2
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Glass media; metal tool surfaces abraded in bead blasting unit; 6/15/99.
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 1
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 176245

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00083892
Waste Code Status:	ACTIVE
Waste Form:	389
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aluminium oxide media; metal tool surfaces abraded in bead blasiting unit; 6/15/
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	176247
Texas Waste Code:	Not reported
Texas Waste Code 2:	00094062
Waste Code Status:	ACTIVE
Waste Form:	406
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty containers, triple rinsed; fiber or plastic acid containers; 6/15/99.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	176248
Texas Waste Code:	Not reported
Texas Waste Code 2:	00109992
Waste Code Status:	ACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant office trash; general office operations; 6/15/99.

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	176249
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011109H
Waste Code Status:	ACTIVE
Waste Form:	109
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent caustic; metal and ceramic cleaning process baths; 6/15/99.
Standard Industrial Code:	89990
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176250
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic rinse water; rinsing of metal or ceramic tooling that is removed from ca
Standard Industrial Code:	89990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176251
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013519H
Waste Code Status:	ACTIVE
Waste Form:	519
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive sludges; chemical stripping/dissolving of metallic deposits; 6/15/99.
Standard Industrial Code:	89990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W519
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176252
Texas Waste Code:	Not reported
Texas Waste Code 2:	00141151
Waste Code Status:	ACTIVE
Waste Form:	115
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Scrubber water; from acid scrubber; overflow or changeout for general maintenanc
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 194479
Texas Waste Code: Not reported
Texas Waste Code 2: 00151142
Waste Code Status: ACTIVE
Waste Form: 114
Waste Classification: 2
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Neutralized rinse water; following neutralization of corrosive rinse water in th
Standard Industrial Code: Not reported
Primary Source: Not reported
Primary Measurement Point: Not reported
Primary Origin: 5
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 1
Company Waste ID: Not reported
Primary NAICS Code: Not reported
EPA Waste Form Code: Not reported
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID: 196538
Texas Waste Code: Not reported
Texas Waste Code 2: 0016319H
Waste Code Status: INACTIVE
Waste Form: 319
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Filter cake generated from waste water treatment process, sent for recycling for
Standard Industrial Code: Not reported
Primary Source: G23
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: WWT FILTER CAKE
Primary NAICS Code: 541990
EPA Waste Form Code: W319
Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 196539

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00173892
Waste Code Status:	ACTIVE
Waste Form:	389
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidized aluminum dust & particulate generated from Twin Wire Arc Spray
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT BLAST MEDIA
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	196540
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018310H
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Filtercartridges and bags from Moly Mask operation. Due to change(s) in theprodu
Standard Industrial Code:	Not reported
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MOLY MASK FILTERS
Primary NAICS Code:	332813
EPA Waste Form Code:	W310
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	202421
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Due to process and procedural changes, this waste is no longer generated; Due to
Standard Industrial Code:	Not reported
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT ISOPROPYL ALCO
Primary NAICS Code:	541990
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	204408
Texas Waste Code:	Not reported
Texas Waste Code 2:	00205041
Waste Code Status:	ACTIVE
Waste Form:	504
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Filter cake generated from dewatering neutralized waste water
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	WWT FILTER CAKE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	216461
Texas Waste Code:	Not reported
Texas Waste Code 2:	00213192
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Polypropylene fume scrubber packing media removed from (and replaced by new) equ
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	SCRUBBER PACK MEDIA
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	234451
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022104H
Waste Code Status:	ACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Discarding off-spec / out-of-date / no longer used chemicals
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OUT-OF-DATE CHEMICAL
Primary NAICS Code:	541990
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	234452
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023109H
Waste Code Status:	ACTIVE
Waste Form:	109
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Discarding off-spec / out-of-date / no longer used chemicals
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OUT-OF-DATE CHEMICAL
Primary NAICS Code:	541990
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	234453
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Discarding off-spec / out-of-date / no longer used chemicals
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OUT-OF-DATE-CHEMICAL
Primary NAICS Code:	541990
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	234560
Texas Waste Code:	Not reported
Texas Waste Code 2:	00250011
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Class 1 Landfill disposal of non RCRA listed out-of-date reagent / lab chemicals
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OUT-OF-DATE REAGENTS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	244510

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0026002H
Waste Code Status:	ACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used PPE, parts storage packaging, scrub pads contaminated with trace arsenic so
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CONTAMINATED DEBRIS
Primary NAICS Code:	541990
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	245680
Texas Waste Code:	Not reported
Texas Waste Code 2:	0027319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent blast media with 10 to 100 ppm Arsenic solids
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	IMPLANT BLAST MEDIA
Primary NAICS Code:	541990
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	372173
Texas Waste Code:	Not reported
Texas Waste Code 2:	00283191
Waste Code Status:	ACTIVE
Waste Form:	319

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-Haz dry Etch residual flake
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ DRY PR RESID
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	372174
Texas Waste Code:	Not reported
Texas Waste Code 2:	00293921
Waste Code Status:	ACTIVE
Waste Form:	392
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-Haz SCR cleanout mud/sludge
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ SCR CLEANOUT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	374808
Texas Waste Code:	Not reported
Texas Waste Code 2:	00303191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	POLYCELLULOSE WIPES CONTAMINATED WITH ACETONE, NO FREE LIQUIDS
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Audit Performed:	0
Company Waste ID:	SOLVENT WIPES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	412878
Texas Waste Code:	Not reported
Texas Waste Code 2:	0040319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive solids; chemical stripping/dissolving of metallic deposits.
Standard Industrial Code:	Not reported
Primary Source:	G14
Primary Measurement Point:	Not reported
Primary Origin:	5
Primary System Type:	141
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541620
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8201 E RIVERSIDE DR BLDG 5
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000313372
Principal Name:	PENTAGON TECHNOLOGIES GROUP INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8201 E RIVERSIDE DR BLDG 5
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000313372
Principal Name:	PENTAGON TECHNOLOGIES GROUP INC
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	XBIOTECH
Address:	8201 E RIVERSIDE DR STE 100
City,State,Zip:	AUSTIN, TX 78744
Program Id:	96348
Location Desc:	8201 E RIVERSIDE DR BLDG 4 STE 100 AUSTIN TX 78744
RN NUM:	RN108626706
Status:	INACTIVE
Status Date:	03/20/2019
EDR Link ID:	96348
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	03/20/2019
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100562818
Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1601
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600273577
Customer Name:	PENTAGON TECHNOLOGIES GROUP INC
Customer Legal Name:	Pentagon Technologies Group, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Primary NAICS Industry Type Code: 541990
Primary NAICS Industry Type Description: All Other Professional, Scientific, and Technical Services
Physical Location Description: 8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number: RN100562818
Name: PENTAGON TECHNOLOGIES GROUP
Address: 8201 E RIVERSIDE DR BLDG 5
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1601
Status: ACTIVE
Status Date: ##########
Customer Number: CN600273577
Customer Name: PENTAGON TECHNOLOGIES GROUP INC
Customer Legal Name: Pentagon Technologies Group, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 541990
Primary NAICS Industry Type Description: All Other Professional, Scientific, and Technical Services
Physical Location Description: 8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number: RN100562818
Name: PENTAGON TECHNOLOGIES GROUP
Address: 8201 E RIVERSIDE DR BLDG 5
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1601
Status: ACTIVE
Status Date: ##########
Customer Number: CN600273577
Customer Name: PENTAGON TECHNOLOGIES GROUP INC
Customer Legal Name: Pentagon Technologies Group, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 541990
Primary NAICS Industry Type Description: All Other Professional, Scientific, and Technical Services
Physical Location Description: 8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number: RN100562818
Name: PENTAGON TECHNOLOGIES GROUP
Address: 8201 E RIVERSIDE DR BLDG 5
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1601
Status: ACTIVE
Status Date: ##########
Customer Number: CN603957044
Customer Name: MPW INDUSTRIAL WATER SERVICES INC
Customer Legal Name: Mpw Industrial Water Services, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 5/24/1999
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 541990
Primary NAICS Industry Type Description: All Other Professional, Scientific, and Technical Services
Physical Location Description: 8201 E Riverside Dr, Bldg 5, Austin, TX

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Regulated Entity Number:	RN100562818
Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1601
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603957044
Customer Name:	MPW INDUSTRIAL WATER SERVICES INC
Customer Legal Name:	Mpw Industrial Water Services, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/24/1999
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541990
Primary NAICS Industry Type Description:	All Other Professional, Scientific, and Technical Services
Physical Location Description:	8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number:	RN100562818
Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1601
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603957044
Customer Name:	MPW INDUSTRIAL WATER SERVICES INC
Customer Legal Name:	Mpw Industrial Water Services, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/24/1999
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541990
Primary NAICS Industry Type Description:	All Other Professional, Scientific, and Technical Services
Physical Location Description:	8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number:	RN100562818
Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1601
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600273577
Customer Name:	PENTAGON TECHNOLOGIES GROUP INC
Customer Legal Name:	Pentagon Technologies Group, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541990
Primary NAICS Industry Type Description:	All Other Professional, Scientific, and Technical Services
Physical Location Description:	8201 E Riverside Dr, Bldg 5, Austin, TX

Regulated Entity Number:	RN100562818
Name:	PENTAGON TECHNOLOGIES GROUP
Address:	8201 E RIVERSIDE DR BLDG 5

PENTAGON TECHNOLOGIES GROUP (Continued) **1001489993**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1601
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603957044
Customer Name:	MPW INDUSTRIAL WATER SERVICES INC
Customer Legal Name:	Mpw Industrial Water Services, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/24/1999
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	541990
Primary NAICS Industry Type Description:	All Other Professional, Scientific, and Technical Services
Physical Location Description:	8201 E Riverside Dr, Bldg 5, Austin, TX

PP2711 **PRODUCT RESEARCH FACILITY** **TX AIRS** **S105837440**
SE **8201 E RIVERSIDE DR STE 600** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78744** **TX IHW CORR ACTION**
0.092 mi. **TX COMP HIST**
488 ft. **Site 4 of 6 in cluster PP** **TX CENTRAL REGISTRY**

Actual:
502 ft.

Focus Map:
19

AIRS:

Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
City,State,Zip:	AUSTIN, TX
Permit Num:	78634
Regulated Id:	RN101449874
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	05/15/2006
Expiration Date:	12/31/3000
Customer Id:	CN603006685
Company Name:	HELIOVOLT CORPORATION
Physical Location Desc:	8201 E Riverside Dr, Ste 600, Austin, TX
Rep Official(RO):	VICE PRESIDENT OF ENGINEERING
RO Name:	MR BOB OSWALD
RO Delivery Address:	8201 E RIVERSIDE DR STE 600
RO City/State/Zip:	AUSTIN, T 78744-160
RO Phone:	512-327-2725
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.215277
Long Dec Coord Num:	-97.687221

Ind. Haz Waste:

Name:	HELIOVOLT
Address:	8201 E RIVERSIDE DR STE 600
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	86453
Registration Initial Notification Date:	04/18/2000
Registration Last Amendment Date:	02/01/2011
EPA Identification:	TXR000077969
Primary NAICS Code:	Not reported
Status Change Date:	20000418
Land Type:	PRIVATE
Description of Facility Site Location:	8201 E Riverside Dr, Ste 600, Austin, TX

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	HELIOVOLT CORPORATION
Contact Name:	HERBERT GANZ
Contact Telephone Number:	512-7676079
Mailing Address:	6301 E STASSNEY LN BLDG 8-100
Mailing Address2:	BLDG 8-100
Mailing City,State,Zip:	AUSTIN, TX 787443055
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	111419
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110208
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	HELIOVOLT CORPORATION
Operator Address:	6301 E STASSNEY LN BLDG 8-100
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78744
Operator Country:	UNITED STA
Operator Telephone:	1-512-7676000
Operator Fax Number:	1-512-7676090
Operator Email:	Hganz@heliovolt.com
Operator Business Type:	Corporation
Operator Tax ID:	17428618767
Operator Bankruptcy Code:	Not reported

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Ind. Haz Waste:

Owner Name:	HELIOVOLT CORPORATION
Owner Mailing Address:	6301 E STASSNEY LN BLDG 8-100
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78744
Owner Country:	UNITED STA
Owner Telephone:	1-512-7676000
Owner Fax:	1-512-7676090
Owner Email Address:	Hganz@heliovolt.com
Owner Business Type:	Corporation
Owner Tax ID:	17428618767
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6301 E STASSNEY LN BLDG 8-100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-7676000
Contact Fax:	1-512-7676090
Contact Email:	Hganz@heliovolt.com

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6301 E STASSNEY LN BLDG 8-100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-7676000
Contact Fax:	1-512-7676090
Contact Email:	Hganz@heliovolt.com

Contact Name:	HERBERT GANZ
Contact Title:	SR FACILITIES MANAGER
Contact Role:	PRICONT
Contact Address:	6301 E STASSNEY LN BLDG 8-100
Contact Address 2:	BLDG 8-100
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-7676079
Contact Fax:	1-866-2080989
Contact Email:	Hganz@heliovolt.com

Ind. Haz Waste:

Waste ID:	220462
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001105H
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Cadmium sulfate contaminated wastewater; cleaning/rinsing of wafersDate of Gen e
Standard Industrial Code:	Not reported
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541712
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	220463
Texas Waste Code:	Not reported
Texas Waste Code 2:	00025191
Waste Code Status:	INACTIVE
Waste Form:	519
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Cadmium sulfate contaminated sludge; settling of solids in waste container,stori
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	220464
Texas Waste Code:	Not reported
Texas Waste Code 2:	00031191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Wastewater; rinsing and wafer production Date of Generation: 3/1/06; Due tochang
Standard Industrial Code:	Not reported
Primary Source:	Not reported

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Waste ID:	220465
Texas Waste Code:	Not reported
Texas Waste Code 2:	00049022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Miscellaneous process solids; personnel protection and cleaning materialsDateof
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	220466
Texas Waste Code:	Not reported
Texas Waste Code 2:	00059992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Office trash; office support activitiesDate of Generation: 3/1/06
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Ind. Haz Waste:

Waste ID:	234454
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Soda lime glass with Cadmium or Selenium deposited on the surface.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	GLASS SUBSTRATES
Primary NAICS Code:	541712
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	235131
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Miscellaneous process solids contaminated with Cadmium. PPE, cleaning cloths, ab
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MISC PROCESS SOLIDS
Primary NAICS Code:	541712
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Waste ID:	237267
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixed Lab pack of materials used within the facility.
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MIXED LAB PACK
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	182291
Texas Waste Code:	Not reported
Texas Waste Code 2:	00101061
Waste Code Status:	INACTIVE
Waste Form:	106
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic soda waste water with traces of arsine and phosphine
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	182893
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113191

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glass oxide impact beads (soda-lime glass). Generated from cleaning machine par
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	182894
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012106H
Waste Code Status:	INACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Glass oxide impact beads with caustic soda waste water with traces of arsine and
Standard Industrial Code:	35630
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183638
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Debris contaminated w/paint, generated from painting process of

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

	machine parts. J
Standard Industrial Code:	35630
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	183637
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PPE Debris generated from clothing / personal protective equipment used in decon
Standard Industrial Code:	35630
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	185224
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015119H
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint thinner-naphtha. Cleaning paint gun associated with paint booth used to p
Standard Industrial Code:	35630
Primary Source:	G01

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191563
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016109H
Waste Code Status:	INACTIVE
Waste Form:	109
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	35630
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	203391
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017106H
Waste Code Status:	INACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Bulk waste water generated from acid pump cleaning.
Standard Industrial Code:	35630
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333912
EPA Waste Form Code:	W110

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	231314
Texas Waste Code:	Not reported
Texas Waste Code 2:	00182191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Chiller loop waste containing propylene glycol
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	DOWFROST WATER
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	241712
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019106H
Waste Code Status:	INACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Liquid waste created from Buffering that contains dilute Ammonia Hydroxideand Ca
Standard Industrial Code:	Not reported
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	LIQUID WITH CADMIUM
Primary NAICS Code:	541712
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Waste ID:	242719
Texas Waste Code:	Not reported
Texas Waste Code 2:	0020319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Metal and plastic debris resulting from the wreck out of a plastic wet bench and
Standard Industrial Code:	Not reported
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	DEBRIS W CD AND SE
Primary NAICS Code:	541712
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	242720
Texas Waste Code:	Not reported
Texas Waste Code 2:	00213191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plastic and metal debris resulting from the defit of a wet bench and exhaust pip
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	DEBRIS WET BENCH
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	241621
Texas Waste Code:	Not reported
Texas Waste Code 2:	01013101
Waste Code Status:	INACTIVE
Waste Form:	310

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Miscellaneous process solids, PPE, cleaning cloths, absorbent pads, filters, pla
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MISC PROCESS SOLIDS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6301 E STASSNEY LN BLDG 8-100
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000313645
Principal Name:	HELIOVOLT CORPORATION
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6301 E STASSNEY LN BLDG 8-100
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000313645
Principal Name:	HELIOVOLT CORPORATION
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
City,State,Zip:	AUSTIN, TX 78744
Program Id:	86453
Location Desc:	8201 E RIVERSIDE DR STE 600 AUSTIN TX
RN NUM:	RN101449874
Status:	INACTIVE
Status Date:	06/06/2011
EDR Link ID:	86453
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	06/06/2011
Soil COC Class:	Not reported

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Soil Remediation: Not reported
GW COC Class: Not reported
GW Remediation: Not reported

COMP HIST:

RN Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603006685
CN Name:	HELIOVOLT CORPORATION
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	334418
SIC Code:	1541
Related Number:	TXR000077969,78634,78634

RN Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600754386
CN Name:	EBARA TECHNOLOGIES INCORPORATED
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	334418
SIC Code:	3273
Related Number:	TXR000077969,78634,78634

CENTRAL REGISTRY:

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN600754386
Customer Name:	EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name:	EBARA Technologies Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN603006685
Customer Name:	HELIOVOLT CORPORATION
Customer Legal Name:	HelioVolt Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600754386
Customer Name:	EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name:	EBARA Technologies Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603006685
Customer Name:	HELIOVOLT CORPORATION
Customer Legal Name:	HelioVolt Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Primary NAICS Industry Type Description: Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description: 8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number: RN101449874
Name: PRODUCT RESEARCH FACILITY
Address: 8201 E RIVERSIDE DR STE 600
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1604
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600754386
Customer Name: EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name: EBARA Technologies Incorporated
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 334418
Primary NAICS Industry Type Description: Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description: 8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number: RN101449874
Name: PRODUCT RESEARCH FACILITY
Address: 8201 E RIVERSIDE DR STE 600
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1604
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600754386
Customer Name: EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name: EBARA Technologies Incorporated
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 334418
Primary NAICS Industry Type Description: Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description: 8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number: RN101449874
Name: PRODUCT RESEARCH FACILITY
Address: 8201 E RIVERSIDE DR STE 600
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78744-1604
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN603006685
Customer Name: HELIOVOLT CORPORATION
Customer Legal Name: HelioVolt Corporation
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 334418
Primary NAICS Industry Type Description: Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description: 8201 E Riverside Dr, Ste 600, Austin, TX

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603006685
Customer Name:	HELIOVOLT CORPORATION
Customer Legal Name:	HelioVolt Corporation
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600754386
Customer Name:	EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name:	EBARA Technologies Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600754386
Customer Name:	EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name:	EBARA Technologies Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Regulated Entity Number:	RN101449874
Name:	PRODUCT RESEARCH FACILITY
Address:	8201 E RIVERSIDE DR STE 600

PRODUCT RESEARCH FACILITY (Continued) **S105837440**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78744-1604
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600754386
Customer Name:	EBARA TECHNOLOGIES INCORPORATED
Customer Legal Name:	EBARA Technologies Incorporated
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	334418
Primary NAICS Industry Type Description:	Printed Circuit/Electronics Assembly Manufacturing
Physical Location Description:	8201 E Riverside Dr, Ste 600, Austin, TX

Click this hyperlink while viewing on your computer to access
4 additional TX CENTRAL REG: record(s) in the EDR Site Report.

PP2712 **XBIOTECH USA** **RCRA NonGen / NLR** **1018282317**
SE **8201 E RIVERSIDE DR STE 100** **TXR000083744**
< 1/8 **AUSTIN, TX 78744**
0.092 mi.
488 ft. **Site 5 of 6 in cluster PP**

Actual:
502 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20190326
Handler Name:	Xbiotech Usa
Handler Address:	8201 E RIVERSIDE DR STE 100
Handler City,State,Zip:	AUSTIN, TX 78744-1602
EPA ID:	TXR000083744
Contact Name:	MARK SHEPHERD
Contact Address:	8201 E RIVERSIDE DR STE 100
Contact City,State,Zip:	AUSTIN, TX 78744-1602
Contact Telephone:	512-386-2976
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	8201 E RIVERSIDE DR STE 100
Mailing City,State,Zip:	AUSTIN, TX 78744-1602
Owner Name:	Xbiotech Usa Inc
Owner Type:	Private
Operator Name:	Xbiotech Usa Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

XBIOTECH USA (Continued) **1018282317**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190418
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D011
Waste Description:	Silver
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

XBIOTECH USA (Continued) **1018282317**

Waste Code: P105
Waste Description: Sodium Azide

Waste Code: U188
Waste Description: Phenol

Waste Code: U196
Waste Description: Pyridine

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: XBIOTECH USA INC
Legal Status: Private
Date Became Current: 20160310
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1602
Owner/Operator Telephone: 512-386-2976
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: XBIOTECH USA INC
Legal Status: Private
Date Became Current: 20160310
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1602
Owner/Operator Telephone: 512-386-2976
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: XBIOTECH USA INC
Legal Status: Private
Date Became Current: 20160310
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1602
Owner/Operator Telephone: 512-386-2976
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: XBIOTECH USA INC
Legal Status: Private
Date Became Current: 20160310
Date Ended Current: Not reported
Owner/Operator Address: 8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1602
Owner/Operator Telephone: 512-386-2976

XBIOTECH USA (Continued) **1018282317**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: XBIOTECH USA INC	
Legal Status:	Private
Date Became Current:	20160310
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1602
Owner/Operator Telephone:	512-386-2976
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: XBIOTECH USA INC	
Legal Status:	Private
Date Became Current:	20160310
Date Ended Current:	Not reported
Owner/Operator Address:	8201 E RIVERSIDE DR STE 100
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1602
Owner/Operator Telephone:	512-386-2976
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160310
Handler Name: XBIOTECH USA	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20180607
Handler Name: XBIOTECH USA	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20190326
Handler Name: XBIOTECH USA	

XBIOTECH USA (Continued) **1018282317**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	541711
NAICS Description:	RESEARCH AND DEVELOPMENT IN BIOTECHNOLOGY
NAICS Code:	541714
NAICS Description:	RESEARCH AND DEVELOPMENT IN BIOTECHNOLOGY (EXCEPT NANOBIOTECHNOLOGY

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

PP2713 **XBIOTECH USA** **TX Ind. Haz Waste** **S118719590**
SE **8201 E RIVERSIDE DR STE 100** **N/A**
< 1/8 **AUSTIN, TX 78744**
0.092 mi.
488 ft. **Site 6 of 6 in cluster PP**

Actual:
502 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	XBIOTECH USA
Address:	8201 E RIVERSIDE DR STE 100
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	96348
Registration Initial Notification Date:	03/10/2016
Registration Last Amendment Date:	03/26/2019
EPA Identification:	TXR000083744
Primary NAICS Code:	541714
Status Change Date:	20190326
Land Type:	PRIVATE
Description of Facility Site Location:	8201 E RIVERSIDE DR BLDG 4 STE 100 AUSTIN TX 78744
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG

XBIOTECH USA (Continued) **S118719590**

Type of Generator:	INDUS
Company Name:	XBIOTECH USA INC
Contact Name:	MARK SHEPHERD
Contact Telephone Number:	512-3862976
Mailing Address:	8201 E RIVERSIDE DR STE 100
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787441602
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	131693
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20190326
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	XBIOTECH USA INC
Operator Address:	8201 E RIVERSIDE DR STE 100
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78744
Operator Country:	UNITED STA
Operator Telephone:	1-512-3862976
Operator Fax Number:	Not reported
Operator Email:	MSHEPHERD@XBIOTECH.COM
Operator Business Type:	Corporation
Operator Tax ID:	12614524671
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	XBIOTECH USA INC
Owner Mailing Address:	8201 E RIVERSIDE DR STE 100
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78744
Owner Country:	UNITED STA
Owner Telephone:	1-512-3862976
Owner Fax:	Not reported
Owner Email Address:	MSHEPHERD@XBIOTECH.COM
Owner Business Type:	Corporation
Owner Tax ID:	12614524671
Owner Bankruptcy Code:	Not reported

XBIOTECH USA (Continued) **S118719590**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	330
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	CONTAINER STORAGE AREA CLOSED PER APPROVAL LTR DATED 03/20/2019
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20190326
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	8201 E RIVERSIDE DR STE 100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-3862976
Contact Fax:	Not reported
Contact Email:	MSHEPHERD@XBIOTECH.COM
Contact Name:	MARK SHEPHERD
Contact Title:	SENIOR EHS SPECIALIST
Contact Role:	PRICONT
Contact Address:	8201 E RIVERSIDE DR STE 100
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-3862976
Contact Fax:	Not reported
Contact Email:	MSHEPHERD@XBIOTECH.COM

Ind. Haz Waste:

Waste ID:	383062
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H

XBIOTECH USA (Continued) **S118719590**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Various off specification chemicals and unused chemicals used in pharmaceutical
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541711
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	386891
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Fast protein liquid chromatography (FPLC), is a form of liquid chromatography us
Standard Industrial Code:	Not reported
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FPLC WASTE
Primary NAICS Code:	325412
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389123
Texas Waste Code:	Not reported

XBIOTECH USA (Continued) **S118719590**

Texas Waste Code 2:	0003219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	HPLC waste containing sodium chloride, sodium phosphate, dilute acetonitrile, di
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HPLC WASTE
Primary NAICS Code:	325412
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	389124
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	20% ethanol waste used in used as a disinfection chemical of biobags in the manu
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ETHANOL WASTE 20
Primary NAICS Code:	325412
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	391766
Texas Waste Code:	Not reported
Texas Waste Code 2:	00059992
Waste Code Status:	INACTIVE
Waste Form:	999

XBIOTECH USA (Continued) **S118719590**

Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Some wastes such as plastic, aluminum cans, and glass are recycled.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PLANT TRASH
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	402085
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste sodium hydroxide generated from the disinfection of process equipment used
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SODIUM HYDROXIDE
Primary NAICS Code:	325412
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	402086
Texas Waste Code:	Not reported
Texas Waste Code 2:	00073881
Waste Code Status:	INACTIVE
Waste Form:	388
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty plastic and glass containers
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

XBIOTECH USA (Continued) **S118719590**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	EMPTY CONTAINERS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-3862900 x0
Mailing Address:	8201 E RIVERSIDE DR STE 100
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000318630
Principal Name:	XBIOTECH USA INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	1-512-3862900 x0
Mailing Address:	8201 E RIVERSIDE DR STE 100
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78744
AR Number:	0000318630
Principal Name:	XBIOTECH USA INC
Attention Name:	Not reported
Attention Suffix:	NWG

PQ2714 **AMERICAN CLEANERS** **TX DRYCLEANERS** **S122570400**
WNW **2201 S 1ST ST STE M** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.093 mi.
490 ft. **Site 1 of 3 in cluster PQ**

Actual:
534 ft.

Focus Map:
14

DRYCLEANERS:

Name:	AMERICAN CLEANERS
Address:	2201 S 1ST ST STE M
City,State,Zip:	AUSTIN, TX 78704
RN Number:	RN109983494
Region:	REGION 11 - AUSTIN
CN Number:	CN600404552
DCR Number:	DCR16106
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	Not reported
Bill Addr2:	Not reported
Bill City/State/Zip:	Not reported
EMail:	Not reported
Phone Number:	0 0
Site Name:	Not reported

AMERICAN CLEANERS (Continued) **S122570400**

Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

2715 **AUSTIN ISD** **RCRA NonGen / NLR** **1000301981**
ESE **201 E MARY** **FINDS** **TXD128098928**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.093 mi. **TX ASBESTOS**
492 ft. **TX Ind. Haz Waste**
TX CENTRAL REGISTRY

Actual:
586 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Isd
Handler Address:	E MARY
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD128098928
Contact Name:	WAYNE SCHADE PHD
Contact Address:	GUADALUPE RM 210
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-451-8411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE RM 210
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Austin Isd
Owner Type:	Not reported
Operator Name:	Austin Isd
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

AUSTIN ISD (Continued) **1000301981**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	U072
Waste Description:	Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene
Waste Code:	U122
Waste Description:	Formaldehyde
Waste Code:	U151
Waste Description:	Mercury
Waste Code:	U210
Waste Description:	Ethene, Tetrachloro- (Or) Tetrachloroethylene
Waste Code:	U211
Waste Description:	Carbon Tetrachloride (Or) Methane, Tetrachloro-

Handler - Owner Operator:

AUSTIN ISD (Continued) **1000301981**

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE RM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: District
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE RM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860814
Handler Name: FULMORE JUNIOR HIGH SCHOOL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: AUSTIN ISD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

AUSTIN ISD (Continued) **1000301981**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110005072973

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000301981
Registry ID:	110005072973
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005072973
Name:	AUSTIN ISD
Address:	201 E MARY
City,State,Zip:	AUSTIN, TX 78704

ASBESTOS:

Name:	FULMORE MIDDLE SCHOOL
Address:	201 E. MARY ST.
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/23/2016
Reason for Inspection:	Complaint
Violation:	No
Complaint Date:	42451
Notification Number:	N/A
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AUSTIN ISD (Continued) **1000301981**

Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	05/16/2016
Date Reviewed by PSQA:	2016-05-16 00:00:00
Date Routed by Supervisor1:	05/09/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	FULMORE JR HIGH SCHOOL

AUSTIN ISD (Continued) **1000301981**

Address:	201 E MARY ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	69674
Registration Initial Notification Date:	08/30/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD128098928
Primary NAICS Code:	Not reported
Status Change Date:	19860830
Land Type:	Not reported
Description of Facility Site Location:	201 E Mary, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	WAYNE SCHADE PHD
Contact Telephone Number:	512-4518411
Mailing Address:	6100 GUADALUPE ST RM 210
Mailing Address2:	RM 210
Mailing City,State,Zip:	AUSTIN, TX 787524420
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24546
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	6100 GUADALUPE ST RM 210
Operator Address 2:	Not reported

AUSTIN ISD (Continued) **1000301981**

Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4518411
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	6100 GUADALUPE ST RM 210
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4518411
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported

AUSTIN ISD (Continued) **1000301981**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WAYNE SCHADE PHD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	RM 210
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100647387
Name:	AUSTIN ISD FULMORE JR HIGH SCHOOL
Address:	201 E MARY ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3554
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600345573
Customer Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Customer Legal Name:	Austin Independent School District
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100647387
Name:	AUSTIN ISD FULMORE JR HIGH SCHOOL
Address:	201 E MARY ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-3554
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600345573
Customer Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT

AUSTIN ISD (Continued) **1000301981**

Customer Legal Name:	Austin Independent School District
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

OG2716 **113 15 GULF REFG CO STA NO** **EDR Hist Auto** **1013767956**
NNE **113 CONGRESS AVE E** **N/A**
< 1/8 **AUSTIN, TX**
0.093 mi.
492 ft. **Site 6 of 7 in cluster OG**

Actual:
473 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	113 15 GULF REFG CO STA NO	GASOLINE AND OIL SERVICE STATIONS

OM2717 **LAKESICE EXXON PRODUCTS SERV ST** **EDR Hist Auto** **1013763733**
NNE **31 INTERREGIONAL HWY N** **N/A**
< 1/8 **AUSTIN, TX 78702**
0.093 mi.
492 ft. **Site 4 of 4 in cluster OM**

Actual:
459 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1970	LAKESIDE ENCO	GASOLINE STATIONS
1973	PENAK CLIFFORD F	Gasoline Service Stations
1974	PENAK CLIFFORD F	Gasoline Service Stations
1975	LAKESIDE EXXON PRODUCTS SERV ST	GASOLINE STATIONS
1975	PENAK CLIFFORD F	Gasoline Service Stations
1976	PENAK CLIFFORD F	Gasoline Service Stations
1977	PENAK CLIFFORD F	Gasoline Service Stations
1978	PENAK CLIFFORD F	Gasoline Service Stations
1979	PENAK CLIFFORD F	Gasoline Service Stations
1980	LAKESICE EXXON PRODUCTS SERV ST	GASOLINE STATIONS
1980	PENAK CLIFFORD F	Gasoline Service Stations
1982	PENAK CLIFFORD F	Gasoline Service Stations
1983	PENAK BILL	Gasoline Service Stations
1984	LAKESIDE EXXON PRODUCTS SERVICE	GASOLINE STATIONS
1985	PENAK BILL	Gasoline Service Stations
1986	PENAK BILL	Gasoline Service Stations
1987	PENAK BILL	Gasoline Service Stations
1988	PENAK BILL	Gasoline Service Stations
1989	PENAK BILL	Gasoline Service Stations, NEC
1990	LAKESIDE TEXACO PRODUCTS SERVIC	GASOLINE STATIONS
1990	PENAK BILL	Gasoline Service Stations, NEC
1991	PENAK BILL	Gasoline Service Stations, NEC

OR2718 WNW < 1/8 0.093 mi. 493 ft. | **P H BORING 2000 S 1ST ST AUSTIN, TX** | **TX HIST UST** | **S111678770 N/A**

Site 4 of 4 in cluster OR

Actual: 529 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	P H BORING
Address:	2000 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0170
HID UST:	170
Inspection:	04/22/2009
Due:	04/22/2012

OG2719 SSW < 1/8 0.093 mi. 493 ft. | **DEWEY GARAGE 115 CONGRESS AVE AUSTIN, TX** | **EDR Hist Auto** | **1013774971 N/A**

Site 7 of 7 in cluster OG

Actual: 473 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1922	DEWEY GARAGE	AUTOMOBILE REPAIRERS

2720 NE < 1/8 0.094 mi. 494 ft. | **TOM WALLACE MILLER 313 S CONGRESS AVE AUSTIN, TX** | **TX HIST UST** | **S111678837 N/A**

Actual: 451 ft.
Focus Map: 14

HIST UST AUSTIN:

Name:	TOM WALLACE MILLER
Address:	313 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0945
HID UST:	945
Inspection:	Not reported
Due:	06/01/2012

PH2721 WNW < 1/8 0.094 mi. 494 ft. | **DOLLARS & SENSE DRY CLEANERS 3816 N LAMAR BLVD AUSTIN, TX 78756** | **EDR Hist Cleaner** | **1018828109 N/A**

Site 4 of 4 in cluster PH

Actual: 613 ft.
Focus Map: 8

EDR Hist Cleaner

Year:	Name:	Type:
1996	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
1997	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2000	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents
2001	DOLLARS & SENSE DRY CLEANERS	Garment Pressing And Cleaners' Agents

OK2722 **POWELL AUTO BODY** **EDR Hist Auto** **1013756867**
SW **409 COLORADO** **N/A**
< 1/8 **AUSTIN, TX**
0.094 mi.
495 ft. **Site 21 of 21 in cluster OK**

Actual:
488 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1929	DAY & NIGHT GARAGE	AUTOMOBILE GARAGES
1935	DAY & NIGHT GARAGE	AUTOMOBILE GARAGES
1940	POWELL AUTO BODY	AUTOMOBILE REPAIRING
1940	DAY & NIGHT STORAGE	AUTOMOBILE GARAGES

PO2723 **TX HIST UST** **S111678478**
ESE **504 W 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.094 mi.
496 ft. **Site 2 of 2 in cluster PO**

Actual:
482 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	504 W 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0193
HID UST:	193
Inspection:	Not reported
Due:	06/01/2012

PR2724 **CHARLES T SIKES** **TX TANKS** **S128250236**
WNW **1000 W 39TH ST** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78756** **TX CENTRAL REGISTRY**
0.094 mi.
496 ft. **Site 1 of 5 in cluster PR**

Actual:
619 ft.

Focus Map:
8

TANKS:

Facility ID:	137129
Name:	CHARLES T SIKES
Address:	1000 W 39TH ST
City,State,Zip:	AUSTIN, TX 787564008
Total UST:	Not reported
Additional ID:	295338902021208
AI Number:	92039
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	Not reported
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported

CHARLES T SIKES (Continued) **S128250236**

Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	Not reported
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

ASBESTOS:

Name:	1000 W 39TH STREET
Address:	1000 W 39TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Alex Boogren
Violation:	Not reported
Complaint Date:	01/27/2023
Notification Number:	2023000091
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/17/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/17/2023
Certification Statement Phone:	8172663774
Is The Facility a School or K-12?:	N

CHARLES T SIKES (Continued) **S128250236**

Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/23/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	1000 W 39TH STREET
Address:	1000 W 39TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Alex Boogren
Violation:	Not reported
Complaint Date:	01/24/2023
Notification Number:	2023000091
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/04/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

CHARLES T SIKES (Continued) **S128250236**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	01/04/2023
Certification Statement Phone:	8172663774
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/18/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN111302808
Name:	CHARLES T SIKES
Address:	1000 W 39TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-4008
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605915784
Customer Name:	SIKES, CHARLES
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########

CHARLES T SIKES (Continued) **S128250236**

Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN111302808
Name:	CHARLES T SIKES
Address:	1000 W 39TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-4008
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN605915784
Customer Name:	SIKES, CHARLES
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

PR2725 **FORMER FUELING FACILITY** **TX LPST** **S128184269**
WNW **1000 W 39TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.094 mi.
496 ft. **Site 2 of 5 in cluster PR**

Actual:
619 ft.

Focus Map:
8

LPST:

Name:	FORMER FUELING FACILITY
Address:	1000 W 39TH ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	121264
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	08/11/2021
Entered Date:	09/30/2021
Reported Date:	08/12/2021
Closure Date:	12/10/2021
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	08/12/2021
Case Start Date:	12/10/2021
Reference Number:	RN111302808

FORMER FUELING FACILITY (Continued) **S128184269**

Project Manager: MOGEE

PR2726 **FORMER FUELING FACILITY GHOST TANK** **TX RDR** **S128622774**
WNW **1000 WEST 39TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.094 mi.
496 ft. **Site 3 of 5 in cluster PR**

Actual:
619 ft.

Focus Map:
8

RDR:

RDR ID:	30676
Facility ID:	92039
RN:	111302808
CN:	605915784
Name:	FORMER FUELING FACILITY GHOST TANK
Address:	1000 WEST 39TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/14/2021
Due Date:	11/13/2021
Tank Owner:	CHARLES SIKES
Contact Person:	CHARLES T SIKES
Report:	Tank Closure
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	9/30/2021
Project Manager:	Michelle Ogee
Team:	Team 3
New LPST Number:	121264
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

2727 **HID GLOBAL** **TX AST** **A100408036**
ESE **611 CENTER RIDGE DR** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.094 mi.
498 ft.

Actual:
737 ft.

Focus Map:
2

AST:

Name:	HID GLOBAL
Address:	611 CENTER RIDGE DR
City,State,Zip:	AUSTIN, TX 787531013
Facility ID:	132504
Additional ID:	693504022015020
AI Number:	87380
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	06/11/2013
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	Not reported

HID GLOBAL (Continued) **A100408036**

Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	JULIO VASQUEZ/
Contact Organization Name:	HID GLOBAL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5127769153
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	01/17/2015
Signature First Name on Earliest Reg Form:	JEFF
Application Received Date on Earliest Reg Form:	01/26/2015
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	HANCOCK
Signature Title on Earliest Reg Form:	Not reported
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	132504
Tank ID:	1
AST ID:	220554
AI Number:	87380
Install Date:	06/11/2013
Tank Registration Date:	01/26/2015
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	06/11/2013
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2500
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

NG2728 ESE < 1/8 0.094 mi. 498 ft. — **PETMECKY COIS (COOF?)**, **220 W 6TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678776**, **N/A**

Site 16 of 16 in cluster NG

Actual: 499 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	PETMECKY COIS (COOF?)
Address:	220 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0017
HID UST:	17
Inspection:	Not reported
Due:	06/01/2012

OD2729 NNE < 1/8 0.095 mi. 499 ft. — **MC FARLAND F H**, **404 BRAZOS ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013753344**, **N/A**

Site 3 of 3 in cluster OD

Actual: 483 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1929	CALLAN JOS GARAGE	AUTOMOBILE GARAGES
1935	MC FARLAND F H	AUTOMOBILE REPAIRERS
1940	MC FARLAND F H	AUTOMOBILE REPAIRING
1947	BLACK LEO M MTRS AUTO DLRS	AUTOMOBILE REPAIRING

2730 NNE < 1/8 0.095 mi. 500 ft. — **RIVERSIDE FINA SERVICE STATION**, **1100 INTERREGIONAL HWY S**, **AUSTIN, TX 78702** — **EDR Hist Auto** — **1013755341**, **N/A**

Actual: 462 ft.
Focus Map: 14

EDR Hist Auto

Year:	Name:	Type:
1970	RIVERSIDE FINA SERVICE STATION	GASOLINE STATIONS
1975	RIVERSIDE FINA SERVICE STATION	GASOLINE STATIONS
1980	RIVERSIDE FINA SERVICE STATION	GASOLINE STATIONS

ND2731 WNW < 1/8 0.095 mi. 500 ft. — **FOUR SEASONS HOTEL**, **98 SAN JACINTO BLVD**, **AUSTIN, TX 78701** — **RCRA-VSQG**, **FINDS**, **ECHO** — **1004785661**, **TXD988033759**

Site 2 of 3 in cluster ND

Actual: 469 ft.
Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	19910417
Handler Name:	Four Seasons Hotel
Handler Address:	SAN JACINTO BLVD
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD988033759
Contact Name:	DAVID GREIS
Contact Address:	98 SAN JACINTO BLVD

FOUR SEASONS HOTEL (Continued) **1004785661**

Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-478-4500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	SAN JACINTO BLVD
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	Town Lake Center Corp
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

FOUR SEASONS HOTEL (Continued) **1004785661**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TOWN LAKE CENTER CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 981/2 SAN JACINTO BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-320-5678
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910417
Handler Name: FOUR SEASONS HOTEL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FOUR SEASONS HOTEL (Continued) **1004785661**

FINDS:
Registry ID: 110005133667

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004785661
Registry ID:	110005133667
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005133667
Name:	FOUR SEASONS HOTEL
Address:	98 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701

ND2732 **THE SHORELINE BUILDING** **TX ASBESTOS** **S109360733**
WNW **98 SAN JACINTO BOULEVARD** **TX DRYCLEANERS** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.095 mi.
500 ft. **Site 3 of 3 in cluster ND**

Actual:
469 ft.

Focus Map:
11

ASBESTOS:

Name:	THE SHORELINE BUILDING
Address:	98 SAN JACINTO BOULEVARD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	01/09/2014
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	201300826
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	EE
Seq:	01
Facility Type:	Mold
Inspector Name:	Emmanuel Enemkpali

THE SHORELINE BUILDING (Continued) **S109360733**

Date Report Received:	01/22/2014
Date Routed by Supervisor:	01/22/2014
Date Routed to PSQA:	01/23/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FOUR SEASONS HOTEL
Address:	98 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	02/08/2019
Reason for Inspection:	Esther Contreras
Violation:	Not reported
Complaint Date:	07/06/2018

THE SHORELINE BUILDING (Continued) **S109360733**

Notification Number:	2018005171
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/21/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/21/2018
Certification Statement Phone:	281-449-5911
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

THE SHORELINE BUILDING (Continued) **S109360733**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

DRYCLEANERS:

Name:	FOUR SEASONS HOTEL
Address:	98 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
RN Number:	RN104101597
Region:	11
CN Number:	CN600311765
DCR Number:	Not reported
AR Number:	24002150
Principal Name:	FOUR SEASONS HOTEL
Bill Addr1:	98 SAN JACINTO BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78701 4082
EMail:	Not reported
Phone Number:	Not reported
Site Name:	FOUR SEASONS HOTEL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

NY2733 **PATTERSONS GARAGE C** **EDR Hist Auto** **1013755102**
NE **716 RED RIVER CT** **N/A**
< 1/8 **AUSTIN, TX**
0.095 mi.
504 ft. **Site 4 of 5 in cluster NY**

Actual:
486 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	PATTERSONS GARAGE C	AUTOMOBILE REPAIRERS

PS2734 **ONE HOUR MARTINIZING NO** **EDR Hist Cleaner** **1013777778**
West **907 24TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.095 mi.
504 ft. **Site 1 of 7 in cluster PS**

Actual:
599 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1969	BRAZOS DRY CLEANING CO	Drycleaning Plants, Except Rugs
1970	ONE HOUR MARTINIZING CLN	CLEANERS AND DYERS
1970	BRAZOS DRY CLEANING CO	Drycleaning Plants, Except Rugs
1971	BRAZOS DRY CLEANING CO	Drycleaning Plants, Except Rugs
1972	BRAZOS DRY CLEANING CO	Drycleaning Plants, Except Rugs
1975	ONE HOUR MARTINIZING NO	CLEANERS AND DYERS

ONE HOUR MARTINIZING NO (Continued) **1013777778**

1980	ONE HOUR MARTINIZING NO	CLEANERS AND DYERS
1984	BROWN JACK CLEANERS	CLEANERS AND DYERS
1990	BROWN JACK CLEANERS	CLEANERS AND DYERS
1992	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1993	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1994	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1995	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1996	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1997	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1998	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
1999	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs
2000	BROWN JACK CLEANERS INC	Drycleaning Plants, Except Rugs

PS2735 **JACK BROWN CLEANERS NO 3** **TX Ind. Haz Waste** **S103606396**
West **907 W 24TH ST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.095 mi.
504 ft. **Site 2 of 7 in cluster PS**

Actual:
599 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	JACK BROWN CLEANERS NO 3
Address:	907 W 24TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	66310
Registration Initial Notification Date:	04/15/1985
Registration Last Amendment Date:	08/10/2006
EPA Identification:	TXD981590672
Primary NAICS Code:	812320
Status Change Date:	19850415
Land Type:	PRIVATE
Description of Facility Site Location:	907 W 24th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	JACK BROWN CLEANERS INC
Contact Name:	PAUL BROWN
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 28159
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787558159
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21589
Site Owner Tax ID:	741395502
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060825

JACK BROWN CLEANERS NO 3 (Continued) **S103606396**

Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	JACK BROWN CLEANERS INC
Operator Address:	3415 NORTHLAND DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78731
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	1-512-4511303
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17413955026
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JACK BROWN CLEANERS INC
Owner Mailing Address:	3415 NORTHLAND DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78731
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	1-512-4511303
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17413955026
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported

JACK BROWN CLEANERS NO 3 (Continued) **S103606396**

Off Site Class 3 Waste:	N
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Drum for waste tetrachloroethylene
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	N
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Containers (either 5 gal un or 55 gal un) depending on which disposal site is ch
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19971030
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3415 NORTHLAND DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78731
Contact Phone:	Not reported
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3415 NORTHLAND DR

JACK BROWN CLEANERS NO 3 (Continued) **S103606396**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78731
Contact Phone:	Not reported
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Contact Name:	PAUL BROWN
Contact Title:	SAFETY DIRECTOR
Contact Role:	PRICONT
Contact Address:	PO BOX 28159
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Phone:	Not reported
Contact Fax:	1-512-4511303
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	164057
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This is the waste tetrachloroethylene from the distillation in the dry cleaningp
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	70322
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	New machine does not so far produce this waste stream.
Standard Industrial Code:	Not reported

JACK BROWN CLEANERS NO 3 (Continued) **S103606396**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	164058
Texas Waste Code:	Not reported
Texas Waste Code 2:	3605601H
Waste Code Status:	INACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This is the sludge from tetrachloroethylene from the distillation in the dry cle
Standard Industrial Code:	72160
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	812320
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301762
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported

JACK BROWN CLEANERS NO 3 (Continued) **S103606396**

Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301762
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301762
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	3415 NORTHLAND DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78731
AR Number:	0000301762
Principal Name:	JACK BROWN CLEANERS INC
Attention Name:	Not reported
Attention Suffix:	HWF

PS2736 **JACK BROWN CLEANERS INC** **RCRA NonGen / NLR** **1000265993**
West **907 W 24TH ST** **FINDS** **TXD981590672**
< 1/8 **AUSTIN, TX 78705** **ECHO**
0.095 mi.
504 ft. **Site 3 of 7 in cluster PS**

Actual:
599 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20060825
Handler Name:	Jack Brown Cleaners Inc
Handler Address:	W 24TH ST
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TXD981590672
Contact Name:	PAUL BROWN
Contact Address:	PO BOX 28159
Contact City,State,Zip:	AUSTIN, TX 78755
Contact Telephone:	512-451-1333 1
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx

JACK BROWN CLEANERS INC (Continued) **1000265993**

State District:	11
Mailing Address:	PO BOX 28159
Mailing City,State,Zip:	AUSTIN, TX 78755
Owner Name:	Jack Brown Cleaners Inc
Owner Type:	Private
Operator Name:	Jack Brown Cleaners Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060829
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane,

JACK BROWN CLEANERS INC (Continued) **1000265993**

Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK T BROWN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20040114
Date Ended Current:	Not reported
Owner/Operator Address:	3415 NORTHLAND DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78731
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	1
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20060810
Date Ended Current:	Not reported
Owner/Operator Address:	3415 NORTHLAND DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78731
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JACK BROWN CLEANERS INC	
Legal Status:	Private
Date Became Current:	20040114
Date Ended Current:	Not reported
Owner/Operator Address:	3415 NORTHLAND DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78731
Owner/Operator Telephone:	512-451-1333
Owner/Operator Telephone Ext:	1
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

JACK BROWN CLEANERS INC (Continued) **1000265993**

Owner/Operator Name: JACK BROWN CLEANERS INC
Legal Status: Private
Date Became Current: 20060810
Date Ended Current: Not reported
Owner/Operator Address: 3415 NORTHLAND DR
Owner/Operator City,State,Zip: AUSTIN, TX 78731
Owner/Operator Telephone: 512-451-1333
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19980319
Handler Name: JACK BROWN CLEANERS NO 3
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010129
Handler Name: JACK BROWN CLEANERS NO 3
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040114
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060825
Handler Name: JACK BROWN CLEANERS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

JACK BROWN CLEANERS INC (Continued) **1000265993**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19900301
Handler Name: JACK BROWN CLNRS #3	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	81232
NAICS Description:	DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005091408

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000265993
Registry ID:	110005091408
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005091408
Name:	JACK BROWN CLEANERS INC
Address:	907 W 24TH ST
City,State,Zip:	AUSTIN, TX 78705

PC2737 **CLEANING CO H** **EDR Hist Cleaner** **1013778781**
ESE **115 INDUSTRIAL BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.096 mi.
506 ft. **Site 2 of 4 in cluster PC**

Actual:
671 ft.
EDR Hist Cleaner

Focus Map:
18

Year:	Name:	Type:
1962	HOME RUG & UPHOL	CARPET AND RUG CLEANERS
1965	CLEANING CO H	CARPET AND RUG CLEANERS
1969	HOME RUG CLEANING CO	Carpet And Upholstery Cleaning
1970	HOME RUG CLEANING CO	Carpet And Upholstery Cleaning

OT2738 **LAMAR VILLAGE SHELL SERV STA** **EDR Hist Auto** **1013769737**
WNW **3724 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.096 mi.
507 ft. **Site 5 of 8 in cluster OT**

Actual:
610 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1965	DECKARDS LAMAR VILLAGE	GASOLINE STATIONS
1970	JACKSONS LAMAR VILLAGE SHELL GA	GASOLINE STATIONS
1970	JACKSONS LAMAR VILLAGE SHELL	Gasoline Service Stations
1971	JACKSONS LAMAR VILLAGE SHELL	Gasoline Service Stations
1972	JACKSONS LAMAR VILLAGE SHELL	Gasoline Service Stations
1973	JACKSONS LAMAR VILLAGE SHELL	Gasoline Service Stations
1974	JACKSONS LAMAR VILLAGE SHELL	Gasoline Service Stations
1975	LAMAR VILLAGE SHELL SERV STA	GASOLINE STATIONS
1975	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1976	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1977	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1978	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1979	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1980	LAMAR VILLAGE SHELL SERVICE STA	GASOLINE STATIONS
1980	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1982	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1983	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1984	LAMAR VILLAGE SHELL SERVICE STA	GASOLINE STATIONS
1985	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1986	DAUPHEN JACKSON & SONS INC	Gasoline Service Stations
1986	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1987	JACKSON LAMAR VILLAGE SHELL	Gasoline Service Stations
1988	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations
1988	LAMAR VILLAGE SHELL	Gasoline Service Stations
1989	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1989	LAMAR VILLAGE SHELL	Gasoline Service Stations
1990	JACKSONS PHILIP 66 SERVICE STAT	GASOLINE STATIONS
1990	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1990	LAMAR VILLAGE SHELL	Gasoline Service Stations
1991	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1992	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1994	LAMAR VILLAGE SHELL	Gasoline Service Stations
1995	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1997	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1998	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC
1999	JACKSON DAUPHEN & SONS INC	Gasoline Service Stations, NEC

OT2739 **SUB WAY** **TX LPST** **U001266297**
WNW **3724 N LAMAR BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78705** **TX HIST UST**
0.096 mi.
507 ft. **Site 6 of 8 in cluster OT**

Actual:
610 ft.

Focus Map:
8

LPST:

Name:	SUB WAY
Address:	3724 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0033138
LPST Id:	106533
Facility Location:	3724 NORTH LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/14/1993
Entered Date:	06/03/1993
Reported Date:	04/14/1993
Closure Date:	10/08/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	LILLIAN CHILDS
Responsible Party Address:	1812 VANCE CIRCLE
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/478-2927
Reported Date:	04/14/1993
Case Start Date:	10/08/1993
Reference Number:	RN101488302
Project Manager:	HWELCH

UST:

Name:	SUB WAY
Address:	3724 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787051120
AI Number:	33138
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	839499742002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	SUB WAY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

SUB WAY (Continued) **U001266297**

Contact Telephone:	5124520761
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/05/1986
Signature Name/Title On Earliest Reg Form:	B T BATY,DIST. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777312
Owner Last Name:	SALAMAR LTD PARTNERSHIP E GRAHAM
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	829499732002053
Additional ID:	839499742002053
AI Number:	33138
Owner Effective Begin Date:	09/01/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87419
Facility ID:	96758
Ai Number:	33138
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

SUB WAY (Continued) **U001266297**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	162484
UST ID:	87419
AI Number:	33138
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

SUB WAY (Continued) **U001266297**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	87420
Facility ID:	96758
Ai Number:	33138
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

SUB WAY (Continued) **U001266297**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	162485
UST ID:	87420
AI Number:	33138
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

SUB WAY (Continued) **U001266297**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87421
Facility ID:	96758
Ai Number:	33138
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

SUB WAY (Continued) **U001266297**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	162486
UST ID:	87421
AI Number:	33138
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

SUB WAY (Continued) **U001266297**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87422
Facility ID:	96758
Ai Number:	33138
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

SUB WAY (Continued) **U001266297**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	550
UST Comprt ID:	162487
UST ID:	87422
AI Number:	33138
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

SUB WAY (Continued) **U001266297**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	S
UST ID:	87423
Facility ID:	96758
Ai Number:	33138
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

SUB WAY (Continued) **U001266297**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	8000
UST Comprt ID:	162488
UST ID:	87423
AI Number:	33138
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1969

SUB WAY (Continued) **U001266297**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169845
Facility ID:	96758
Ai Number:	33138
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

SUB WAY (Continued) **U001266297**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	44
UST Comprt ID:	162489
UST ID:	169845
AI Number:	33138
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169846
Facility ID:	96758

SUB WAY (Continued) **U001266297**

Ai Number:	33138
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1993
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	44
UST Comprt ID:	162490

SUB WAY (Continued) **U001266297**

UST ID:	169846
AI Number:	33138
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SALAMAR LTD PARTNERSHIP
Contact Mailing Address (Delivery):	1812 VANCE CIR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1035
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96758
Additional ID:	839499742002053
Princ ID:	829499732002053
AI Number:	33138
Facility Name:	SUB WAY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported

SUB WAY (Continued) **U001266297**

Contact Name/Title: E GRAHAM/

HIST UST AUSTIN:

Name:	JACKSON'S PHILLIPS 66
Address:	3724 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0394
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

NY2740 **HICKMAN R L C AUTO** **EDR Hist Auto** **1013760371**
NE **718 RED RIVER CT** **N/A**
< 1/8 **AUSTIN, TX**
0.096 mi.
509 ft. **Site 5 of 5 in cluster NY**

Actual:
487 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1929	HICKMAN R L C AUTO	AUTOMOBILE REPAIRERS

PS2741 **CONVENIENCE INC WASHATER** **EDR Hist Cleaner** **1013781442**
West **916 24TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78705**
0.097 mi.
511 ft. **Site 4 of 7 in cluster PS**

Actual:
600 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1975	CONVENIENCE INC WASHATER	LAUNDRIES-SELF SERVE

2742 **KEMAC CORPORATION** **EDR Hist Auto** **1021209858**
WNW **113 METEOR DR A** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.097 mi.
511 ft.

Actual:
678 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1989	KEMAC CORPORATION	Gasoline Service Stations
1990	KEMAC CORPORATION	Gasoline Service Stations

PQ2743 **MOTORCYCLE RESSURECTIONS** **EDR Hist Auto** **1021053409**
WNW **2209 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.097 mi.
514 ft. **Site 2 of 3 in cluster PQ**

Actual:
534 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1991	LEO & STEVES AUTOMOTIVE	General Automotive Repair Shops
1991	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops
1992	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops
1992	J&L TRANSMISSIONS	Automotive Transmission Repair Shops
1992	LEO & STEVES AUTOMOTIVE	General Automotive Repair Shops
1993	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops
1993	LEO & STEVES AUTOMOTIVE	General Automotive Repair Shops
1993	J&L TRANSMISSIONS	Automotive Transmission Repair Shops
1994	J&L TRANSMISSIONS	Automotive Transmission Repair Shops
1994	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops
1995	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops
1996	MOTORCYCLE RESSURECTIONS	General Automotive Repair Shops

---

OZ2744 **THOMSON PREMIER SERV STA** **EDR Hist Auto** **1013758611**
WNW **3201 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX**
0.098 mi.
515 ft. **Site 6 of 6 in cluster OZ**

Actual:
577 ft.

Focus Map:
8

EDR Hist Auto

Year:	Name:	Type:
1965	THOMSON PREMIER SERV STA	GASOLINE STATIONS

2745 **COASTAL STATES CRUDE GATHERING** **TX Ind. Haz Waste** **S105532933**
East **7901 E BEN WHITE BLVD** **N/A**
< 1/8 **AUSTIN, TX 78744**
0.098 mi.
518 ft.

Actual:
504 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	COASTAL STATES CRUDE GATHERING
Address:	7901 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	83388
Registration Initial Notification Date:	08/22/2003
Registration Last Amendment Date:	08/22/2003
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	20030822
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1

COASTAL STATES CRUDE GATHERING (Continued) **S105532933**

Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	COASTAL STATES CRUDE GATHERING
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	9 GREENWAY PLZ
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 770460905
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	100443
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	COASTAL STATES CRUDE GATHERING
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	30001262564
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	ENV MGR
Contact Role:	PRICONT
Contact Address:	9 GREENWAY PLZ
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77046
Contact Phone:	Not reported

COASTAL STATES CRUDE GATHERING (Continued) **S105532933**

Contact Fax: Not reported
Contact Email: Not reported

PT2746 **GEST DUTCH CLEANERS** **EDR Hist Cleaner** **1013780862**
ESE **209 E 19TH** **N/A**
< 1/8 **AUSTIN, TX 78722**
0.098 mi.
519 ft. **Site 1 of 3 in cluster PT**

Actual:
516 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	GEST DUTCH CLEANERS CLNRS	CLEANERS AND DYERS
1969	GEST DUTCH CLEANERS	Drycleaning Plants, Except Rugs

OX2747 **INTERRIGIONAL CONOCO SERVICE STATION** **EDR Hist Auto** **1013772675**
ESE **901 1ST ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78702**
0.098 mi.
519 ft. **Site 3 of 4 in cluster OX**

Actual:
468 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	INTERRIGIONAL CONOCO SERVICE ST	GASOLINE STATIONS

PG2748 **TRANSMIX CONCRETE** **TX HIST UST** **S111678839**
West **812 W CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.098 mi.
520 ft. **Site 4 of 4 in cluster PG**

Actual:
451 ft.
HIST UST AUSTIN:

Focus Map:
11

Name:	TRANSMIX CONCRETE
Address:	812 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0554
HID UST:	554
Inspection:	04/29/2009
Due:	04/29/2012

PU2749 **CUSTOM ENGINE RE** **EDR Hist Auto** **1013759967**
WNW **603 MARY W** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.098 mi.
520 ft. **Site 1 of 2 in cluster PU**

Actual:
522 ft.
EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1953	CUSTOM ENGINE RE	AUTOMOBILE REPAIRING

CUSTOM ENGINE RE (Continued) **1013759967**

1958	WEST MARY GARAGE	AUTOMOBILE REPAIRING
1962	WEST MARY GARAGE	AUTOMOBILE REPAIRING

PU2750
WNW
< 1/8
0.098 mi.
520 ft.

AUSTIN AUTOMOTIVE
603 MARY ST W
TRAVIS (County), TX 78704
Site 2 of 2 in cluster PU

EDR Hist Auto **1013762259**
N/A

Actual:
522 ft.

Focus Map:
14

EDR Hist Auto

Year:	Name:	Type:
1965	WEST MARY GARAGE REPR	AUTOMOBILE REPAIRING
1970	WEST MARY TRANSMISSION	AUTOMOBILE REPAIRING
1975	AUSTIN AUTOMOTIVE	AUTOMOBILE REPAIRING

PV2751
WNW
< 1/8
0.099 mi.
522 ft.

RAILTON MANUFACTURING
906 JUSTIN LN
AUSTIN, TX 78757
Site 1 of 2 in cluster PV

TX LPST **U001264548**
TX UST **N/A**
TX HIST UST
TX ASBESTOS

Actual:
722 ft.

Focus Map:
6

LPST:

Name:	COMFORT SUPPLY RAILTON MANUFACTURE
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78757
Facility ID:	0031174
LPST Id:	099116
Facility Location:	JUSTIN LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/31/1991
Entered Date:	05/31/1991
Reported Date:	05/31/1991
Closure Date:	07/17/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	RON BEARD
Responsible Party Address:	5120 BIRCH 1ST FLOOR
Responsible Party City,St,Zip:	NEWPORT BEACH, CA 92660
Responsible Party Telephone:	714/752-2155
Reported Date:	05/31/1991
Case Start Date:	07/17/1996
Reference Number:	RN101490324
Project Manager:	HWELCH

UST:

Name:	RAILTON MANUFACTURING
Address:	906 JUSTIN LN

RAILTON MANUFACTURING (Continued) **U001264548**

City,State,Zip:	AUSTIN, TX 787572626
AI Number:	31174
Facility Type:	UNKNOWN
Facility Begin Date:	11/10/1986
Facility Status:	INACTIVE
Additional ID:	779560952002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78757
Contact Name/Title:	B MICKLER,BRANCH MGR
Contact Organization Name:	RAILTON MANUFACTURING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124524820
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/11/1986
Signature Name/Title On Earliest Reg Form:	,BRANCH MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600779177
Owner Last Name:	SOUTHLAND EQUITIES
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	769560942002053
Additional ID:	779560952002053
AI Number:	31174
Owner Effective Begin Date:	11/10/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	81932
Facility ID:	65383
Ai Number:	31174
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/14/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

RAILTON MANUFACTURING (Continued) **U001264548**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	80088
UST ID:	81932
AI Number:	31174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

UST ID:	81933
Facility ID:	65383
Ai Number:	31174
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/14/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/08/1990

Compartment Records:

Tank ID:	2

RAILTON MANUFACTURING (Continued) **U001264548**

Tank Capacity:	2000
UST Comprt ID:	80089
UST ID:	81933
AI Number:	31174
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHLAND EQUITIES
Contact Mailing Address (Delivery):	5120 BIRCH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	NEWPORT BEACH, CA 92660 2153
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	65383
Additional ID:	779560952002053
Princ ID:	769560942002053
AI Number:	31174
Facility Name:	RAILTON MANUFACTURING
AR Number:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COMFORT SUPPLY
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX
Id UST:	C0242
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	03/21/2023
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	01/20/2023
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/20/2023
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07

RAILTON MANUFACTURING (Continued) **U001264548**

Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	12/30/2022
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	10/26/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	10/26/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	01/14/2023
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	11/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/07/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/14/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS

RAILTON MANUFACTURING (Continued) **U001264548**

Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	01/21/2023
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	11/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/11/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

RAILTON MANUFACTURING (Continued) **U001264548**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	01/21/2023
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	11/19/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/19/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

RAILTON MANUFACTURING (Continued) **U001264548**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN DEPARTMENT OF PUBLIC WORKS
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	Not reported
Reason for Inspection:	Ange Collins
Violation:	Not reported
Complaint Date:	12/30/2022
Notification Number:	2022006710
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Industrial/Manufacturing
Inspector Name:	Not reported
Date Report Received:	10/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

RAILTON MANUFACTURING (Continued) **U001264548**

Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	10/18/2022
Certification Statement Phone:	512-247-9485
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/01/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

PV2752 **6909 RYAN DRIVE PROPERTY** **TX VCP** **S127780405**
WNW **906 JUSTIN LN** **N/A**
< 1/8 **AUSTIN, TX 78757**
0.099 mi.
522 ft. **Site 2 of 2 in cluster PV**

Actual:
722 ft.

Focus Map:
6

VCP TCEQ:

Name:	6909 RYAN DRIVE PROPERTY
Address:	906 JUSTIN LN
City,State,Zip:	AUSTIN, TX 78757
Region:	REGION 11 - AUSTIN
Facility ID:	3152
VCP Record Date:	06/03/2021
Facility Type:	PROPERTY INDUSTRIAL; PROPERTY RESIDENTIAL; PROPERTY COMMERCIAL
PCA Number:	68451
Project Manager:	JNOREM
Phase:	AFFIDAVIT
Acres at Site:	5.475
REM Program:	VCP
RN Number:	RN101490324

6909 RYAN DRIVE PROPERTY (Continued) **S127780405**

Former Facility Type:	PROPERTY INDUSTRIAL; PROPERTY RESIDENTIAL; AGRICULTURE/AG SUPPORT; AUTO SVC STN/REPAIR/VEH MAINTE; PROPERTY COMMERCIAL
Site Address Description:	6909 RYAN DR AND 906 JUSTIN LN
Near City Name:	AUSTIN
Administrative Status:	ACTIVE
Region Notified of Application:	06/23/2021
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	NA
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	NA
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP; PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	NA
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	NA
Certificate of Completion Date:	06/13/2023
Standards:	PLAN A; A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	06/03/2021
GW Target COC Class:	VOCS; CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2021-07-15 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	3152
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	684510
Off Site?:	NO
Media:	PAPER
IOP Number:	Not reported
File Location:	D-211
Latitude:	30.34
Longitude:	-97.72

Contact:

REM Program:	VCP
Program ID:	3152
RN Number:	RN101490324
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
Role Code:	APPLCONT
Contact Name:	BALESTIERE, THOMAS
Contact Title:	SR APPRAISER
Organization Name:	CITY OF AUSTIN
Mailing Address:	PO BOX 1088
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Telephone:	(512) 974-7090
Contact Telephone Ext:	0

OX2753 ESE < 1/8 0.099 mi. 523 ft. — **HILES JOHN L WASHING MACH REPR**, **900 1ST ST E**, **TRAVIS (County), TX 78702** — **EDR Hist Auto** — **1013769527** / **N/A**

Site 4 of 4 in cluster OX

Actual: 468 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1975	HILES JOHN L WASHING MACH REPR	REPAIR SHOPS

2754 ENE < 1/8 0.100 mi. 526 ft. — **FORMADORY TEXACO**, **5326 E SH 71**, **AUSTIN, TX** — **TX HIST UST** — **S128729620** / **N/A**

Actual: 581 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	FORMADORY TEXACO
Address:	5326 E SH 71
City,State,Zip:	AUSTIN, TX
Id UST:	OJ089
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PW2755 WNW < 1/8 0.100 mi. 527 ft. — **RICHMOND AUTO**, **828 PRAIRIE TRL**, **AUSTIN, TX 78758** — **EDR Hist Auto** — **1020203636** / **N/A**

Site 1 of 2 in cluster PW

Actual: 751 ft.

Focus Map: 3

EDR Hist Auto

Year:	Name:	Type:
1996	RICHMOND AUTO	Automotive Transmission Repair Shops
1997	RICHMOND AUTO	Automotive Transmission Repair Shops
1998	RICHMOND AUTO	Automotive Transmission Repair Shops
1999	RICHMOND AUTO	Automotive Transmission Repair Shops
2000	RICHMOND AUTO	Automotive Transmission Repair Shops
2001	RICHMOND AUTO	Automotive Transmission Repair Shops
2002	RICHMOND AUTO	Automotive Transmission Repair Shops
2003	TRAN RICHMOND	Automotive Transmission Repair Shops
2004	TRAN RICHMOND	Automotive Transmission Repair Shops

PX2756 NW < 1/8 0.100 mi. 528 ft. — **FRANKES SLS &**, **4126 LAMAR BLVD N**, **AUSTIN, TX** — **EDR Hist Auto** — **1013766185** / **N/A**

Site 1 of 4 in cluster PX

Actual: 633 ft.

Focus Map: 8

EDR Hist Auto

Year:	Name:	Type:
1962	FRANKES SLS &	GASOLINE STATIONS

PY2757 ROGERS BROS SERV STA **EDR Hist Auto** **1013756611**
ENE 200 1ST E **N/A**
< 1/8 AUSTIN, TX
0.100 mi.
528 ft. Site 1 of 2 in cluster PY

Actual:
472 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	D & S SERVICE STATION FILLING S	GASOLINE AND OIL SERVICE STATIONS
1947	ROGERS BROS SERV STA	GASOLINE AND OIL SERVICE STATIONS
1947	SWEARINGEN ARMSTRONG INC AUTO R	AUTOMOBILE REPAIRING
1953	SWEARINGEN	AUTOMOBILE REPAIRING
1953	HOUGH WESLEY SERV	GASOLINE STATIONS
1958	B&G AUTOMOTIVE	AUTOMOBILE REPAIRING
1958	REDDS HUMBLE SERV	GASOLINE STATIONS
1962	CLARES AUTOMOTIVE REPR	AUTOMOBILE REPAIRING
1965	FINO SERVICE STATION NO	GASOLINE STATIONS
1965	CLARES AUTOMOTIVE AUTO REPR GR	AUTOMOBILE REPAIRING
1984	FRANKS EXXON SERVICE	GASOLINE STATIONS

PY2758 J. F. ROBINSON **TX HIST UST** **S111678691**
ENE 200 E CESAR CHAVEZ ST **N/A**
< 1/8 AUSTIN, TX
0.100 mi.
528 ft. Site 2 of 2 in cluster PY

Actual:
472 ft.

HIST UST AUSTIN:

Name:	J. F. ROBINSON
Address:	200 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0928
HID UST:	928
Inspection:	Not reported
Due:	06/01/2012

Focus Map:
11

2759 KXAN TV STUDIO **TX UST** **U004240572**
West 908 W MARTIN LUTHER KING JR BLVD **TX HIST UST** **N/A**
< 1/8 AUSTIN, TX 78701 **TX Financial Assurance**
0.100 mi.
529 ft.

Actual:
600 ft.

UST:

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 787011018
AI Number:	87736
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	10/01/1995
Facility Status:	ACTIVE
Additional ID:	399509062015167
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported

Focus Map:
11

KXAN TV STUDIO (Continued) **U004240572**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MARK DUNHAM,
Contact Organization Name:	KXAN TV STUDIO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127035234
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/25/2019
Signature Name/Title On Earliest Reg Form:	MARK DUNHAM,CHIEF ENGINEER
Application Received Date On Earliest Reg Form:	04/29/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	462497952017314
Additional ID:	399509062015167
Ai Number:	87736
Operator CN:	CN605436906
Operator Name:	NEXSTAR MEDIA INC
Operator Effective Begin Date:	01/17/2017
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	MARK DUNHAM/
Contact Organization Name:	NEXSTAR BROADCASTING INC
Contact Mailing Address (Delivery):	908 W MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78701-1018
Contact Phone Country Code:	0
Contact Phone Area Code:	512
Contact Phone Number:	7035234
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605436906
Owner Last Name:	NEXSTAR MEDIA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	908 W MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78701
Contact Mailing Zip5:	1018

KXAN TV STUDIO (Continued) **U004240572**

Contact Phone Number/Ext:	0 512 7035234/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	462497952017314
Additional ID:	399509062015167
AI Number:	87736
Owner Effective Begin Date:	01/17/2017
State Tax ID:	12330631529
Contact Role:	OWNOPRCON
Contact Name/Title:	MARK DUNHAM/
Contact Organization Name:	NEXSTAR BROADCASTING INC

Self Certification:

Self Cert ID:	132862
Cert ID:	320076
AI Number:	87736
Self Certification Date:	04/25/2019
Signature Name/Title:	MARK DUNHAM CHIEF ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	132862
Cert ID:	303444
AI Number:	87736
Self Certification Date:	04/17/2018
Signature Name/Title:	MARK DUMHAM CHIEF ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	132862
Cert ID:	295204
AI Number:	87736
Self Certification Date:	08/28/2017

KXAN TV STUDIO (Continued) **U004240572**

Signature Name/Title:	MARK DUNHAM CHIEF ENG
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	132862
Cert ID:	277595
AI Number:	87736
Self Certification Date:	05/31/2016
Signature Name/Title:	MARK DUNHAM CHIEF ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	132862
Cert ID:	254341
AI Number:	87736
Self Certification Date:	05/19/2015
Signature Name/Title:	MARK DUNHAM CHIEF ENGINEER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	N

Tank:

Install Date:	10/01/1995
Tank Registration Date:	06/15/2015
Number of Compartments:	1

KXAN TV STUDIO (Continued) **U004240572**

Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	220380
Facility ID:	132862
Ai Number:	87736
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	10/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	Y
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N

KXAN TV STUDIO (Continued) **U004240572**

Tank Tested Flag:	Not reported
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	188686
UST ID:	220380
AI Number:	87736
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	NEXSTAR BROADCASTING INC
Contact Mailing Address (Delivery):	908 W MARTIN LUTHER KING JR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1018
Phone Number/Ext:	512 7035234/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	132862

KXAN TV STUDIO (Continued) **U004240572**

Additional ID:	399509062015167
Princ ID:	462497952017314
AI Number:	87736
Facility Name:	KXAN TV STUDIO
AR Number:	79315
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	MARK DUNHAM/

HIST UST AUSTIN:

Name:	KXAN CH 36 TV
Address:	908 W MARTIN LUTHER KING BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3188
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	132862
Finass ID:	213648
AI:	87736
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2018
Date Financial Assurance Form Rec:	04/29/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G46647683 002
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	132862
Finass ID:	196743
AI:	87736
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y

KXAN TV STUDIO (Continued) **U004240572**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2017
Date Financial Assurance Form Rec:	04/29/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G46647683001
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	132862
Finass ID:	188307
AI:	87736
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2017
Date Financial Assurance Form Rec:	04/29/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G46647683001
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	132862
Finass ID:	169945
AI:	87736
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/08/2016
Date Financial Assurance Form Rec:	04/29/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G2465803A 009
Coverage Amount:	1,000,000

KXAN TV STUDIO (Continued) **U004240572**

Coverage Expiration Date:	09/08/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KXAN TV STUDIO
Address:	908 W MARTIN LUTHER KING JR BLVD
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	132862
Finass ID:	145378
AI:	87736
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/26/2014
Date Financial Assurance Form Rec:	04/29/2019
Issuer Name:	ACE AMERICAN INS CO
Issuer Phone:	1 215 6401000
Policy Number:	G24728948 003
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/26/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

PZ2760 **GOODNIGHT SERV STA** **EDR Hist Auto** **1013772423**
WNW **4700 CONGRESS AVE S** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.100 mi.
530 ft. **Site 1 of 2 in cluster PZ**

Actual:
650 ft.
EDR Hist Auto

Focus Map:
17

Year:	Name:	Type:
1953	GOODNIGHT SERV STA	GASOLINE STATIONS

PZ2761 **ARCHIE FITZGERALD** **TX HIST UST** **S111678557**
WNW **4700 S CONGRESS AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.100 mi.
530 ft. **Site 2 of 2 in cluster PZ**

Actual:
650 ft.
HIST UST AUSTIN:

Focus Map:
17

Name:	ARCHIE FITZGERALD
Address:	4700 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	H0553
HID UST:	553
Inspection:	05/09/2012
Due:	05/09/2015

NW2762 WNW < 1/8 0.101 mi. 532 ft. | **MAGNOLIA PETROLEUM CO.** | **TX HIST UST** | **S111678739** | **N/A**

837 W 12TH ST
AUSTIN, TX

Site 5 of 5 in cluster NW

Actual: 482 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM CO.
Address:	837 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0366
HID UST:	366
Inspection:	Not reported
Due:	06/01/2012

2763 NNE < 1/8 0.101 mi. 535 ft. | **J J PICKLE FEDERAL OFFICE BUILDING** | **TX UST** | **U001293126** | **TX HIST UST** | **N/A** | **TX ASBESTOS**

300 E 8TH ST
AUSTIN, TX 78701

Actual: 511 ft.
Focus Map: 11

UST:

Name:	J J PICKLE FEDERAL OFFICE BUILDING
Address:	300 E 8TH ST
City,State,Zip:	AUSTIN, TX 787013233
AI Number:	64191
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	02/02/1993
Facility Status:	ACTIVE
Additional ID:	542413032002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	JOHN CHINNICI,PROJ MGR
Contact Organization Name:	J J PICKLE FEDERAL OFFICE BUILDING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127613801
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	JCHINNICI@WILSONFIVE.COM
Signature Date On Earliest Reg Form:	08/08/2022
Signature Name/Title On Earliest Reg Form:	JENNIFER ZENUCH,INDUSTRIAL HYGENIST
Application Received Date On Earliest Reg Form:	08/10/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	956393062021118
Additional ID:	542413032002117

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Ai Number:	64191
Operator CN:	CN605883305
Operator Name:	WILSON 5 SERVICE COMPANY INC
Operator Effective Begin Date:	03/01/2021
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600311591
Owner Last Name:	GENERAL SERVICES ADMINISTRATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	72444872001297
Additional ID:	542413032002117
AI Number:	64191
Owner Effective Begin Date:	03/01/2021
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	95131
Cert ID:	374046
AI Number:	64191
Self Certification Date:	08/08/2022
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95131
Cert ID:	353507
AI Number:	64191
Self Certification Date:	04/26/2021
Signature Name/Title:	JOHN CHINNICI PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95131
Cert ID:	335477
AI Number:	64191
Self Certification Date:	03/31/2020
Signature Name/Title:	JENNIFER ZENUCH INDURSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95131
Cert ID:	320312
AI Number:	64191
Self Certification Date:	04/01/2019
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95131
Cert ID:	312703
AI Number:	64191
Self Certification Date:	12/07/2018
Signature Name/Title:	JENNIFER ZENUCH INDUSTRIAL HYGIENIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95131
Cert ID:	285299
AI Number:	64191
Self Certification Date:	04/06/2017
Signature Name/Title:	RANDY OWENS PROP MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	09/01/1989
Tank Registration Date:	02/01/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Pipe Type:	S
UST ID:	147686
Facility ID:	95131
Ai Number:	64191
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	09/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	06/21/1993

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	157798
UST ID:	147686
AI Number:	64191
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24925
Cert ID:	271494
UST Comprt ID:	782331
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	289091
UST Comprt ID:	834674
UST ID:	150736

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	306942
UST Comprt ID:	888079
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	321671
UST Comprt ID:	932039
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	339435
UST Comprt ID:	985641
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	355985
UST Comprt ID:	1035532
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	363985
UST Comprt ID:	1059521
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	374555
UST Comprt ID:	1091364
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143298
UST Comprt ID:	400247
UST ID:	150736
AI Number:	64191

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143299
UST Comprt ID:	400248
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143300
UST Comprt ID:	400249
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143301
UST Comprt ID:	400246
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143302
UST Comprt ID:	400245
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143303
UST Comprt ID:	400244
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143304
UST Comprt ID:	400243
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143305
UST Comprt ID:	400242
UST ID:	150736
AI Number:	64191
Tank ID:	2

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Compartment ID:	A
Self Cert ID:	24925
Cert ID:	143306
UST Comprt ID:	400241
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	224387
UST Comprt ID:	643689
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	243539
UST Comprt ID:	699792
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A
Self Cert ID:	24925
Cert ID:	256103
UST Comprt ID:	736791
UST ID:	150736
AI Number:	64191
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	GENERAL SERVICES ADMINISTRATION
Contact Mailing Address (Delivery):	300 E 8TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 3233
Phone Number/Ext:	915 3191482/0
Contact Fax Number/Ext:	/
Contact Email Address:	AARON.BOLLINGER@GSA.GOV
Contact Address Deliverable:	Y
Facility ID:	95131
Additional ID:	542413032002117
Princ ID:	72444872001297
AI Number:	64191
Facility Name:	J J PICKLE FEDERAL OFFICE BUILDING
AR Number:	39934
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	AARON BOLLINGER/

HIST UST AUSTIN:

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Name:	FEDERAL BUILDING
Address:	300 E 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX018
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA P.E.
Violation:	Not reported
Complaint Date:	01/15/2022
Notification Number:	2021008554
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	12/28/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/28/2021
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA P.E.
Violation:	Not reported
Complaint Date:	01/07/2022
Notification Number:	2021008554
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	12/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/16/2021
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA P.E.
Violation:	Not reported
Complaint Date:	01/15/2022
Notification Number:	2021008554
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	01/10/2022

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/10/2022
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA P.E.
Violation:	Not reported
Complaint Date:	01/15/2022
Notification Number:	2021008554

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	01/03/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/03/2022
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA
Violation:	Not reported
Complaint Date:	01/15/2022
Notification Number:	2021008554
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	01/05/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/05/2022
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/07/2022
Client Code:	Not reported
Client Name:	Not reported

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	JJ PICKLE BUILDING
Address:	300 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	J. MARK SWINNEA
Violation:	Not reported
Complaint Date:	01/15/2022
Notification Number:	2021008554
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Federal
Inspector Name:	Not reported
Date Report Received:	01/05/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/05/2022
Certification Statement Phone:	903-882-6865
Is The Facility a School or K-12?:	N

J J PICKLE FEDERAL OFFICE BUILDING (Continued) **U001293126**

Region:	07
Priority:	HIGH
ARU:	28
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	01/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

PJ2764 **BRYANT AUTOMOTIVE** **TX UST** **U002112551**
NW **505 W OLTORF ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.102 mi.
541 ft. **Site 2 of 2 in cluster PJ**

Actual:
546 ft.

Focus Map:
14

UST:

Name:	BRYANT AUTOMOTIVE
Address:	505 W OLTORF ST
City,State,Zip:	AUSTIN, TX 787045447
AI Number:	66474
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	220573582005250
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	RON BRYANT,
Contact Organization Name:	BRYANT AUTOMOTIVE
Contact Mailing Address1:	Not reported

BRYANT AUTOMOTIVE (Continued) **U002112551**

Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2109643797
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/14/1995
Signature Name/Title On Earliest Reg Form:	CHARLES RONALD BRYANT,PRES
Application Received Date On Earliest Reg Form:	02/16/1995
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602905424
Owner Last Name:	BRYANT
Owner First Name:	CHARLES
Owner Middle Name:	RONALD
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	200573572005250
Additional ID:	220573582005250
AI Number:	66474
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	02/16/1995
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	173607
Facility ID:	99718
Ai Number:	66474
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

BRYANT AUTOMOTIVE (Continued) **U002112551**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	152314
UST ID:	173607
AI Number:	66474
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

BRYANT AUTOMOTIVE (Continued) **U002112551**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	02/16/1995
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	173608
Facility ID:	99718
Ai Number:	66474
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/14/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

BRYANT AUTOMOTIVE (Continued) **U002112551**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	152315
UST ID:	173608
AI Number:	66474
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

BRYANT AUTOMOTIVE (Continued) **U002112551**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BRYANT CHARLES RONALD
Contact Mailing Address (Delivery):	2322 VALLEY FRG
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	CANYON LAKE, TX 78133 2505
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	99718
Additional ID:	220573582005250
Princ ID:	200573572005250
AI Number:	66474
Facility Name:	BRYANT AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RON BRYANT/

HIST UST AUSTIN:

Name:	BRYANT AUTOMOTIVE
Address:	505 W OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0551
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

PR2765 WNW < 1/8 0.103 mi. 542 ft. — **STA & GARAGE, 3900 LAMAR BLVD N, AUSTIN, TX** — **EDR Hist Auto** — **1013758539, N/A**

Site 4 of 5 in cluster PR

Actual: 619 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1962	STA & GARAGE	GASOLINE STATIONS
1965	TEMPLETON SERVICE STATION	GASOLINE STATIONS
1970	TEMPLETON SERVICE STATION & GAR	GASOLINE STATIONS
1972	TEMPLETON SERVICE STATION GAR	Gasoline Service Stations
1973	TEMPLETON SERVICE STATION GAR	Gasoline Service Stations
1974	TEMPLETON SERVICE STATION GAR	Gasoline Service Stations
1975	TEMPLETON SERVICE STATION & GAR	GASOLINE STATIONS
1975	TEMPLETON SERVICE STATION GAR	Gasoline Service Stations
1980	TEMPLETON SERVICE STATION & GAR	GASOLINE STATIONS

2766 WNW < 1/8 0.103 mi. 546 ft. — **CHIEF CLEANERS, 1001 W 34TH ST, TRAVIS (County), TX 78705** — **EDR Hist Cleaner** — **1013781417, N/A**

Actual: 583 ft. EDR Hist Cleaner

Focus Map: 8

Year:	Name:	Type:
1965	CHIEF CLEANERS GL	CLEANERS AND DYERS
1970	CHIEF CLEANERS	CLEANERS AND DYERS
1973	JONES BEVERLY	Drycleaning Plants, Except Rugs
1974	JONES BEVERLY	Drycleaning Plants, Except Rugs
1975	JONES BEVERLY	Drycleaning Plants, Except Rugs

OA2767 East < 1/8 0.103 mi. 546 ft. — **BOSS MANUFACTURING, 818 W YAGER LN, AUSTIN, TX 78753** — **TX DRYCLEANERS, TX Ind. Haz Waste, TX CENTRAL REGISTRY** — **S103606508, N/A**

Site 4 of 4 in cluster OA

Actual: 687 ft. DRYCLEANERS:

Focus Map: 4

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN
CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	Not reported
Phone Number:	512 8005536
Site Name:	Not reported
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

BOSS MANUFACTURING (Continued) **S103606508**

Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN
CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	ANEUMANN@TEXASCUSTOMCLEANERS.COM
Phone Number:	512 8005536
Site Name:	TEXAS CUSTOM CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	55
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN
CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	ANEUMANN@TEXASCUSTOMCLEANERS.COM
Phone Number:	512 8005536
Site Name:	TEXAS CUSTOM CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	10
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN

BOSS MANUFACTURING (Continued) **S103606508**

CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	ANEUMANN@TEXASCUSTOMCLEANERS.COM
Phone Number:	512 8005536
Site Name:	TEXAS CUSTOM CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	PETROLEUM
Gallons:	55
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN
CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	ANEUMANN@TEXASCUSTOMCLEANERS.COM
Phone Number:	512 8005536
Site Name:	TEXAS CUSTOM CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	55
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100635911
Region:	REGION 11 - AUSTIN
CN Number:	CN605478189
DCR Number:	DCR16131
AR Number:	24007743
Principal Name:	TEXAS CUSTOM CLEANERS LLC
Bill Addr1:	818 W YAGER LN
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 1308
EMail:	ANEUMANN@TEXASCUSTOMCLEANERS.COM
Phone Number:	512 8005536
Site Name:	TEXAS CUSTOM CLEANERS
Site Type:	FACILITY REGISTRATION

BOSS MANUFACTURING (Continued) **S103606508**

Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	PETROLEUM
Gallons:	55
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Ind. Haz Waste:

Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	66585
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	818 Yager Lane, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	BOSS MANUFACTURING COMPANY
Contact Name:	BOB DESPAIN
Contact Telephone Number:	Not reported
Mailing Address:	818 W YAGER LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787531308
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21853
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20060922
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported

BOSS MANUFACTURING (Continued) **S103606508**

Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BOSS MANUFACTURING COMPANY
Operator Address:	818 W YAGER LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	13608273408
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BOSS MANUFACTURING COMPANY
Owner Mailing Address:	818 W YAGER LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	13608273408
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	818 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	818 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	BOB DESPAIN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT

BOSS MANUFACTURING (Continued) **S103606508**

Contact Address:	818 W YAGER LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346530
Customer Name:	BOSS MANUFACTURING COMPANY
Customer Legal Name:	Boss Manufacturing Company
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346530
Customer Name:	BOSS MANUFACTURING COMPANY
Customer Legal Name:	Boss Manufacturing Company
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346530
Customer Name:	BOSS MANUFACTURING COMPANY
Customer Legal Name:	Boss Manufacturing Company
Customer Ownership Type:	ORGANIZATION

BOSS MANUFACTURING (Continued) **S103606508**

Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600346530
Customer Name:	BOSS MANUFACTURING COMPANY
Customer Legal Name:	Boss Manufacturing Company
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605478189
Customer Name:	TEXAS CUSTOM CLEANERS LLC
Customer Legal Name:	TEXAS CUSTOM CLEANERS, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/1/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605478189
Customer Name:	TEXAS CUSTOM CLEANERS LLC
Customer Legal Name:	TEXAS CUSTOM CLEANERS, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/1/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

BOSS MANUFACTURING (Continued) **S103606508**

Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 818 Yager Lane, Austin, TX

Regulated Entity Number: RN100635911
Name: BOSS MANUFACTURING
Address: 818 W YAGER LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1308
Status: ACTIVE
Status Date: ##########
Customer Number: CN605478189
Customer Name: TEXAS CUSTOM CLEANERS LLC
Customer Legal Name: TEXAS CUSTOM CLEANERS, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/1/2018
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 818 Yager Lane, Austin, TX

Regulated Entity Number: RN100635911
Name: BOSS MANUFACTURING
Address: 818 W YAGER LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1308
Status: ACTIVE
Status Date: ##########
Customer Number: CN605478189
Customer Name: TEXAS CUSTOM CLEANERS LLC
Customer Legal Name: TEXAS CUSTOM CLEANERS, LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 3/1/2018
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 818 Yager Lane, Austin, TX

Regulated Entity Number: RN100635911
Name: BOSS MANUFACTURING
Address: 818 W YAGER LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78753-1308
Status: ACTIVE
Status Date: ##########
Customer Number: CN600346530
Customer Name: BOSS MANUFACTURING COMPANY
Customer Legal Name: Boss Manufacturing Company
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 812320
Primary NAICS Industry Type Description: Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description: 818 Yager Lane, Austin, TX

BOSS MANUFACTURING (Continued) **S103606508**

Regulated Entity Number:	RN100635911
Name:	BOSS MANUFACTURING
Address:	818 W YAGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1308
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN605478189
Customer Name:	TEXAS CUSTOM CLEANERS LLC
Customer Legal Name:	TEXAS CUSTOM CLEANERS, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	3/1/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	818 Yager Lane, Austin, TX

Click this hyperlink while viewing on your computer to access additional TX CENTRAL REG: detail in the EDR Site Report.

NV2768 **BRADSHAW AND PURYEAR** **TX HIST UST** **S111678576**
WNW **206 E CESAR CHAVEZ ST** **N/A**
< 1/8 **AUSTIN, TX**
0.103 mi.
546 ft. **Site 2 of 2 in cluster NV**

Actual:
473 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	BRADSHAW AND PURYEAR
Address:	206 E CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0514
HID UST:	514
Inspection:	Not reported
Due:	06/01/2012

QA2769 **AT&T - HOMESTEAD 451 C.O. XP3010** **TX HIST UST** **S128728849**
WNW **817 W NORTH LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.104 mi.
547 ft. **Site 1 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	AT&T - HOMESTEAD 451 C.O. XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	960
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QA2770 HOMESTEAD 451 CO XP3010 **TX UST** **U003040304**
WNW 817 W NORTH LOOP BLVD **TX Financial Assurance** **N/A**
< 1/8 AUSTIN, TX 78756 **TX TIER 2**
0.104 mi.
547 ft. Site 2 of 9 in cluster QA

Actual:
684 ft.

Focus Map:
8

UST:

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 787562214
AI Number:	19359
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	961528002002085
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	JULIANNA BROCK,
Contact Organization Name:	HOMESTEAD 451 CO XP3010
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	2547577700
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/17/2016
Signature Name/Title On Earliest Reg Form:	JURANDIR FELIPE-ORTEGA,EHS MGR
Application Received Date On Earliest Reg Form:	03/17/2016
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	576368792017305
Additional ID:	961528002002085
Ai Number:	19359
Operator CN:	CN605433374
Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Operator Effective Begin Date:	09/24/2018
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	DERONICA LAMB/MANAGER EH&S ENVIRONMENTAL SERVICES
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75202-5315
Contact Phone Country Code:	1
Contact Phone Area Code:	214
Contact Phone Number:	7410464
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	DR1429@ATT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605433374
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75202
Contact Mailing Zip5:	5315
Contact Phone Number/Ext:	1 214 7410630/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	MP0873@ATT.COM
Contact Address Deliverable:	Not reported
Princ ID:	576368792017305
Additional ID:	961528002002085
AI Number:	19359
Owner Effective Begin Date:	09/24/2018
State Tax ID:	14305297104
Contact Role:	OWNOPRCON
Contact Name/Title:	MICHAEL PERRY/AREA MANAGER, EH&S ENVIRONMENTAL SERVICE
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY

Self Certification:

Self Cert ID:	76476
Cert ID:	381324
AI Number:	19359
Self Certification Date:	01/10/2023
Signature Name/Title:	CAMERON SPARKS TANK PROGRAM MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	362456
AI Number:	19359
Self Certification Date:	11/01/2021

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	VYRL NAUMANN TANK MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	345907
AI Number:	19359
Self Certification Date:	11/16/2020
Signature Name/Title:	Vyrl L Naumann Tank Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	328671
AI Number:	19359
Self Certification Date:	10/24/2019
Signature Name/Title:	Vyrl L Naumann EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	311904
AI Number:	19359
Self Certification Date:	10/16/2018

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	Rayshell T Wamsley Tank Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	294234
AI Number:	19359
Self Certification Date:	10/03/2017
Signature Name/Title:	Jurandir Felipe-Ortega EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	275744
AI Number:	19359
Self Certification Date:	09/13/2016
Signature Name/Title:	Jurandir Felipe-Ortega EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	76476
Cert ID:	267047
AI Number:	19359
Self Certification Date:	03/17/2016

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	JURANDIR FELIPE-ORTEGA EHS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76476
Cert ID:	248698
AI Number:	19359
Self Certification Date:	02/12/2015
Signature Name/Title:	Lisa Espinosa EH&S Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76476
Cert ID:	232760
AI Number:	19359
Self Certification Date:	02/26/2014
Signature Name/Title:	Lisa Espinosa Manager EH&S
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	76476
Cert ID:	116370
AI Number:	19359
Self Certification Date:	03/28/2013

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	TAMEKA JACKSON EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116369
AI Number:	19359
Self Certification Date:	03/30/2012
Signature Name/Title:	ROBERT D PICKENS EH&S MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116368
AI Number:	19359
Self Certification Date:	03/21/2011
Signature Name/Title:	ROBERT D PICKENS SR ADMIN ENVIR HEALT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116367
AI Number:	19359
Self Certification Date:	03/30/2010

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	TAMEKA JACKSON MGR-EH&S
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76476
Cert ID:	116366
AI Number:	19359
Self Certification Date:	03/09/2009
Signature Name/Title:	MARK E DINUBILA ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76476
Cert ID:	116365
AI Number:	19359
Self Certification Date:	03/05/2008
Signature Name/Title:	ROBERT D TAYLOR SOUTHWEST REGIONAL M
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	76476
Cert ID:	116364
AI Number:	19359
Self Certification Date:	03/22/2007

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	ROBERT D TAYLOR ENVIRONMENTAL MANAGE
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116363
AI Number:	19359
Self Certification Date:	02/24/2006
Signature Name/Title:	CHERYL ALLEN ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116362
AI Number:	19359
Self Certification Date:	02/07/2005
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116361
AI Number:	19359
Self Certification Date:	01/21/2004

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116360
AI Number:	19359
Self Certification Date:	02/19/2003
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116359
AI Number:	19359
Self Certification Date:	03/01/2002
Signature Name/Title:	HARRY C HIXSON MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116358
AI Number:	19359
Self Certification Date:	02/28/2002

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Signature Name/Title:	HARRY C HIXSON MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76476
Cert ID:	116357
AI Number:	19359
Self Certification Date:	01/15/2001
Signature Name/Title:	MICHAEL A OLIVER SEN ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/10/2001
Tank Registration Date:	03/28/2002
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	199657
Facility ID:	76476
Ai Number:	19359
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	12/10/2001
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/09/2002

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	113881
UST ID:	199657
AI Number:	19359
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7424
Cert ID:	99957
UST Comprt ID:	303389
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99962
UST Comprt ID:	303386
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99960
UST Comprt ID:	303388
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99961
UST Comprt ID:	303387
UST ID:	105897
AI Number:	19359
Tank ID:	3

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99958
UST Comprt ID:	303390
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99959
UST Comprt ID:	303391
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Install Date:	12/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	50082
Facility ID:	76476
Ai Number:	19359
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/16/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	113880
UST ID:	50082
AI Number:	19359
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7424
Cert ID:	99957
UST Comprt ID:	303389
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99962
UST Comprt ID:	303386
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99960
UST Comprt ID:	303388
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99961
UST Comprt ID:	303387
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99958
UST Comprt ID:	303390
UST ID:	105897
AI Number:	19359
Tank ID:	3
Compartment ID:	A
Self Cert ID:	7424
Cert ID:	99959
UST Comprt ID:	303391
UST ID:	105897
AI Number:	19359
Tank ID:	3

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Compartment ID: A

Construction Notification:

NOC ID:	11968
Facility ID:	76476
AI Number:	19359
Application Received Date:	02/20/2001
Scheduled Construction Date:	03/26/2001
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10220012
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

NOC ID:	11967
Facility ID:	76476
AI Number:	19359
Application Received Date:	06/01/2001
Scheduled Construction Date:	08/01/2001
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10601004
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	12756
UST ID:	Not reported
NOC ID:	11967
AI Number:	19359
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001141
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	12757
UST ID:	Not reported
NOC ID:	11968
AI Number:	19359
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000964
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	30149
UST ID:	199657
NOC ID:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

AI Number:	19359
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001141
Company Name:	ERS Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	45313
UST ID:	199657
NOC ID:	Not reported
AI Number:	19359
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001048
Company Name:	Not reported
Representative Name:	TRUMAN COPE
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Mailing Address (Delivery):	308 S AKARD ST FL 17
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76476
Additional ID:	961528002002085
Princ ID:	576368792017305

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

AI Number:	19359
Facility Name:	HOMESTEAD 451 CO XP3010
AR Number:	83091
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	VYRL NAUMANN/

TX Financial Assurance 2:

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	278451
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2022
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	0 800 7475256
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2024
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	259468
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2021
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/30/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	251356
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2021
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	259127
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2021
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	0 800 5669347
Policy Number:	MWZZ316143
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	240526
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2019
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	203601
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2018
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ313649
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	166476
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	185949
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2016
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	158153
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2015
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ304781
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Region:	2
Facility ID:	76476
Finass ID:	9413
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60137
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2012
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50593
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	123478
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2013
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	Not reported
Policy Number:	MWZZ50593
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/01/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60138
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2010
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60139
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50517
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2012

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60140
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2009
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	OLD REPUBLIC INS CO
Issuer Phone:	1 800 5536938
Policy Number:	MWZZ50514
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60141
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2008
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	9723041
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60142

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 0 0
Policy Number:	1595289
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60143
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	Not reported
Policy Number:	1595289
Coverage Amount:	1000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	HOMESTEAD 451 CO XP3010
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76476
Finass ID:	60144
AI:	19359
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Date Financial Assurance Form Rec:	03/17/2016
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

TIER 2:

Facility Id/Name:	FA201145152ZXXXXXXXX/HOMESTEAD 451 CO - XP3010
Reporting Year:	2011
Facility Country:	USA
Facility Department:	HOMESTEAD 451 CO - XP3010
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	02/06/2012
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	54
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	30.000000
Longitude:	-97.000000
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FA201045152ZXXXXXXXX/HOMESTEAD 451 CO - XP3010
Reporting Year:	2010
Facility Country:	USA
Facility Department:	HOMESTEAD 451 CO - XP3010
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	01/05/2011
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	58
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0.000000
Longitude:	0.000000
Lat/Long Location Desc:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FA200945152ZXXXXXXXX/HOMESTEAD 451 CO XP3010
Reporting Year:	2009
Facility Country:	USA
Facility Department:	HOMESTEAD 451 CO - XP3010
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	01/06/2010
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	63
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0.000000
Longitude:	0.000000
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FA200845152ZXXXXXXXX/HOMESTEAD 451 CO - XP3010
Reporting Year:	2008
Facility Country:	USA
Facility Department:	HOMESTEAD 451 CO - XP3010
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	02/20/2009
Mailing Address:	898 Marie Lane
Mailing City/State/Country:	Conyers, GA USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	0
Number Of Employess On Site:	52
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Lynn Ragsdale
Latitude:	0
Longitude:	0

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	108024050
Id Type:	Dun & Bradstreet
Description:	other
Last Modified:	01/06/2010
Id:	4813
Id Type:	SIC
Description:	Unknown
Last Modified:	01/06/2010
Id:	517110
Id Type:	NAICS
Description:	Unknown
Last Modified:	01/06/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Mail Country:	USA
Contact Type 1:	Alternate Contact
Contact Name:	EH&S Hotline
Title:	Alternative Contact (IMS/EPCRA)
Modification Date:	1/6/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	4544 S LAMAR BLVD
Contact City/State/Zip:	AUSTIN, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	ROBERT ROHLF
Title:	Property Manager
Modification Date:	3/14/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	898 Marie Lane
Contact City/State/Zip:	Conyers, GA 30094
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Lynn Ragsdale

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Title:	EH&S Manager
Modification Date:	3/14/2010

Chemical Inventory:

Facility Id:	FA200945152ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA200945152Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	1/29/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA200945152Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA200945152Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	1/29/2010

Facility Id:	FA200945152ZXXXXXXXX
Chemical Name:	LEAD
Chemical Inv Record Id:	FA200945152Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	1/29/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA200945152Z31Z1ZZXX
Chemical Inventory Record Id:	FA200945152Z31ZXXXXX
Amt Of Sub Stored Or Transported:	156016
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	1/29/2010

Facility Id:	FA200945152ZXXXXXXXX
Chemical Name:	DIESEL FUEL #2 LOW SULFUR
Chemical Inv Record Id:	FA200945152Z70ZXXXXX
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	69858
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	1/29/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA200945152Z70Z0ZZXX
Chemical Inventory Record Id:	FA200945152Z70ZXXXXX
Amt Of Sub Stored Or Transported:	69144
Amount Units:	pounds
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 1/29/2010

Record Key: FA200945152Z70Z0ZZXX
Chemical Inventory Record Id: FA200945152Z70ZXXXXX
Amt Of Sub Stored Or Transported: 714
Amount Units: pounds
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 1/29/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:
Id: 4813
Id Type: SIC
Description: Unknown
Last Modified: 02/06/2012
Id: 517110
Id Type: NAICS
Description: Unknown
Last Modified: 02/06/2012
Id: 108024050
Id Type: Dun & Bradstreet
Description: other
Last Modified: 02/06/2012

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)
Modification Date: 02/06/2012

Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)
Modification Date: 02/06/2012

Contact:
Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Contact Mail Country:	USA
Contact Type 1:	Certifier
Contact Name:	Lynn Ragsdale
Title:	EH&S Manager
Modification Date:	02/06/2012
Contact Email:	lrragsdale@att.com
Contact Mail Address:	898 Marie Lane
Contact City/State/Zip:	Conyers, GA 30094
Contact Mail Country:	USA
Contact Type 1:	Certifier
Contact Name:	Lynn Ragsdale
Title:	EH&S Manager
Modification Date:	02/06/2012

Contact:

Contact Email:	lrragsdale@att.com
Contact Mail Address:	898 Marie Lane
Contact City/State/Zip:	Conyers, GA 30094
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	SWBT Texas, LLC
Title:	Not reported
Modification Date:	2/14/2012
Contact Email:	lrragsdale@att.com
Contact Mail Address:	898 Marie Lane
Contact City/State/Zip:	Conyers, GA 30094
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	SWBT Texas, LLC
Title:	Not reported
Modification Date:	2/14/2012

Contact:

Contact Email:	rr4284@us.att.com
Contact Mail Address:	4544 S LAMAR BLVD
Contact City/State/Zip:	AUSTIN, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	ROBERT ROHLF
Title:	Property Manager
Modification Date:	2/14/2012

Chemical Inventory:

Facility Id:	FA201145152ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA201145152Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/9/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201145152Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA201145152Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	2/9/2012

Facility Id:	FA201145152ZXXXXXXXX
Chemical Name:	LEAD
Chemical Inv Record Id:	FA201145152Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/9/2012
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201145152Z31Z1ZZXX

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Chemical Inventory Record Id: FA201145152Z31ZXXXXX
Amt Of Sub Stored Or Transported: 156016
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A
Last Modified: 2/9/2012

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 517110
Id Type: NAICS
Description: Unknown
Last Modified: 01/05/2011
Id: 108024050
Id Type: Dun & Bradstreet
Description: other
Last Modified: 01/05/2011
Id: 4813
Id Type: SIC
Description: Unknown
Last Modified: 01/05/2011

Contact:
Contact Email: Not reported
Contact Mail Address: Not reported
Contact City/State/Zip: Not reported
Contact Mail Country: USA
Contact Type 1: Alternate Contact
Contact Name: EH&S Hotline
Title: Alternative Contact (IMS/EPCRA)
Modification Date: 01/05/2011

Contact:
Contact Email: rr4284@semail.att.com
Contact Mail Address: 4544 S LAMAR BLVD
Contact City/State/Zip: AUSTIN, TX 78745
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: ROBERT ROHLF
Title: Property Manager
Modification Date: 4/3/2011

Contact:
Contact Email: lrragsdale@att.com
Contact Mail Address: 898 Marie Lane
Contact City/State/Zip: Conyers, GA 30094
Contact Mail Country: USA
Contact Type 1: Owner / Operator

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Contact Name:	Lynn Ragsdale
Title:	EH&S Manager
Modification Date:	4/4/2011

Chemical Inventory:

Facility Id:	FA201045152ZXXXXXXXX
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	FA201045152Z1ZZXXXXX
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	16276
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/16/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045152Z1ZZ1ZZXX
Chemical Inventory Record Id:	FA201045152Z1ZZXXXXX
Amt Of Sub Stored Or Transported:	16276
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	2/16/2011

Facility Id:	FA201045152ZXXXXXXXX
Chemical Name:	LEAD
Chemical Inv Record Id:	FA201045152Z31ZXXXXX
CAS Number:	7439-92-1
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	156016
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/16/2011
Days On Site:	365
Fire Hazard:	Not reported

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Gas:	Not reported
Liquid:	Not reported
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	T
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045152Z31Z1ZZXX
Chemical Inventory Record Id:	FA201045152Z31ZXXXXX
Amt Of Sub Stored Or Transported:	156016
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	N/A
Last Modified:	2/16/2011

Facility Id:	FA201045152ZXXXXXXXX
Chemical Name:	DIESEL FUEL #2 LOW SULFUR
Chemical Inv Record Id:	FA201045152Z70ZXXXXX
CAS Number:	68476-34-6
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	69858
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/16/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	FA201045152Z70Z0ZZXX
Chemical Inventory Record Id:	FA201045152Z70ZXXXXX
Amt Of Sub Stored Or Transported:	69144
Amount Units:	pounds
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1

HOMESTEAD 451 CO XP3010 (Continued) **U003040304**

Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 2/16/2011

Record Key: FA201045152Z70Z0ZZXX
Chemical Inventory Record Id: FA201045152Z70ZXXXXX
Amt Of Sub Stored Or Transported: 69144
Amount Units: pounds
Type Of Storage: Below ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: N/A - N/A
Last Modified: 2/16/2011

Notes: Not reported
Validation: Not reported

Notes: Added from Chris Mach spreadsheet.

Validation: This facility passed all validation checks.

QA2771 **SOUTHWESTERN BELL TELEPHONE** **TX HIST UST** **S128729359**
WNW **817 W NORTH LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.104 mi.
547 ft. **Site 3 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: SOUTHWESTERN BELL TELEPHONE
Address: 817 W NORTH LOOP BLVD
City,State,Zip: AUSTIN, TX
Id UST: H0649
HID UST: 649
Inspection: Not reported
Due: 06/01/2012

QA2772 **SBC HOMESTEAD 451 CENTRAL OFFICE** **TX Ind. Haz Waste** **S105491190**
WNW **817 W NO LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.104 mi.
547 ft. **Site 4 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

Ind. Haz Waste:
Name: SBC HOMESTEAD 451 CENTRAL OFFICE
Address: 817 W NO LOOP BLVD
City,State,Zip: AUSTIN, TX 78756
Permit Number: Not reported
Registration Number: 66066
Registration Initial Notification Date: 02/28/2003
Registration Last Amendment Date: 02/28/2003
EPA Identification: TXT490014826

SBC HOMESTEAD 451 CENTRAL OFFICE (Continued) **S105491190**

Primary NAICS Code:	Not reported
Status Change Date:	20030228
Land Type:	PRIVATE
Description of Facility Site Location:	817 N Loop Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CLASS1
Type of Generator:	Not reported
Company Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Contact Name:	LARRY HARRELL
Contact Telephone Number:	214-4641942
Mailing Address:	308 S AKARD ST RM 900
Mailing Address2:	ROOM 900
Mailing City,State,Zip:	DALLAS, TX 752025315
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21369
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110706
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

SBC HOMESTEAD 451 CENTRAL OFFICE (Continued) **S105491190**

Operator Name:	SOUTHWESTERN BELL TELEPHONE LP
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	SOUTHWESTERN BELL TELEPHONE LP
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	LARRY HARRELL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	308 S AKARD ST RM 900
Contact Address 2:	ROOM 900
Contact Address 3:	Not reported
Contact City,State,Zip:	DALLAS, TX 75202
Contact Phone:	1-214-4641942
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported

SBC HOMESTEAD 451 CENTRAL OFFICE (Continued) **S105491190**

Mailing Address:	ONE BELL CTR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ST. LOUIS, MO 63101
AR Number:	0000307935
Principal Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	ONE BELL CTR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ST. LOUIS, MO 63101
AR Number:	0000307935
Principal Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Attention Name:	Not reported
Attention Suffix:	HWG

QA2773 **SOUTHWESTERN BELL TELEPHONE** **TX LPST** **S116701934**
WNW **817 W NORTH LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.104 mi.
547 ft. **Site 5 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

LPST:

Name:	SOUTHWESTERN BELL TELEPHONE
Address:	817 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0019359
LPST Id:	091998
Facility Location:	819 NORTH LOOP
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/28/1988
Entered Date:	07/06/1988
Reported Date:	06/28/1988
Closure Date:	11/13/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	BOD
Responsible Party Name:	Not reported
Responsible Party Contact:	HARRY HIXSON
Responsible Party Address:	308 S AKARD RM 900
Responsible Party City,St,Zip:	DALLAS, TX 75202 5399
Responsible Party Telephone:	214/464-1805
Reported Date:	06/28/1988
Case Start Date:	11/13/1997
Reference Number:	RN100708882
Project Manager:	BOD

QA2774 WNW < 1/8 0.104 mi. 547 ft. | **SBC**
817 N LOOP BLVD
AUSTIN, TX 78756
Site 6 of 9 in cluster QA | **RCRA NonGen / NLR** | **1000410913**
TXT490014826

Actual: 684 ft.

Focus Map: 8

RCRA Listings:

Date Form Received by Agency:	20030228
Handler Name:	Sbc
Handler Address:	N LOOP BLVD
Handler City,State,Zip:	AUSTIN, TX 78756
EPA ID:	TXT490014826
Contact Name:	LARRY HARRELL
Contact Address:	S AKARD ROOM 900
Contact City,State,Zip:	DALLAS, TX 75202
Contact Telephone:	214-464-1942
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S AKARD ROOM 900
Mailing City,State,Zip:	DALLAS, TX 75202
Owner Name:	Southwestern Bell Telephone Company
Owner Type:	Private
Operator Name:	Southwestern Bell Telephone Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

SBC (Continued) **1000410913**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	U151
Waste Description:	Mercury

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SOUTHWESTERN BEL TEL CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Legal Status:	Private
Date Became Current:	20030228
Date Ended Current:	Not reported
Owner/Operator Address:	1 BELL CTR
Owner/Operator City,State,Zip:	ST LOUIS, MO 63101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	SOUTHWESTERN BELL TELEPHONE COMPANY
Legal Status:	Private
Date Became Current:	20030228

SBC (Continued) **1000410913**

Date Ended Current: Not reported
Owner/Operator Address: 1 BELL CTR
Owner/Operator City,State,Zip: ST LOUIS, MO 63101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19810603
Handler Name: SOUTHWESTERN BEL TEL CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030228
Handler Name: SBC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

QA2775 **NORTH LOOP SOC** **TX LPST** **S116701790**
WNW **819 W NO LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.104 mi.
548 ft. **Site 7 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

LPST:
Name: NORTH LOOP SOC
Address: 819 W NO LOOP BLVD
City,State,Zip: AUSTIN, TX 78756
Facility ID: 0020853

NORTH LOOP SOC (Continued) **S116701790**

LPST Id:	091504
Facility Location:	817 NORTH LOOP
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/01/1987
Entered Date:	09/16/1987
Reported Date:	09/16/1987
Closure Date:	07/27/1992
Priority:	2C - GROUP 1 GROUNDWATER OFF-SITE MIGRATION UNLIKELY
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUP 1 GROUNDWATER, OFF-SITE MIGRATION UNLIKELY
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RAY YORK
Responsible Party Name:	Not reported
Responsible Party Contact:	M JEFFERS
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	AUSTIN, TX
Responsible Party Telephone:	/-
Reported Date:	09/16/1987
Case Start Date:	07/27/1992
Reference Number:	RN102382157
Project Manager:	RRY

QA2776 **AUSTIN HOMESTEAD 451** **TX LPST** **S116696529**
WNW **819 W NO LOOP BLVD** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.104 mi.
548 ft. **Site 8 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

LPST:

Name:	AUSTIN HOMESTEAD 451
Address:	819 W NO LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0020853
LPST Id:	104122
Facility Location:	817 NORTH LOOP RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/03/1992
Entered Date:	01/25/1993
Reported Date:	08/03/1992
Closure Date:	02/16/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	HARRY HIXSON
Responsible Party Address:	308 S AKARD RM 900
Responsible Party City,St,Zip:	DALLAS, TX 75202 5399
Responsible Party Telephone:	214/464-1805
Reported Date:	08/03/1992
Case Start Date:	02/16/1993

AUSTIN HOMESTEAD 451 (Continued) **S116696529**

Reference Number: RN102382157
Project Manager: HWELCH

QA2777 **NORTH LOOP SOC PORT XP3184** **TX UST** **U001255577**
WNW **819 W NO LOOP BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78756** **TX Financial Assurance**
0.104 mi.
548 ft. **Site 9 of 9 in cluster QA**

Actual:
684 ft.

Focus Map:
8

UST:

Name:	NORTH LOOP SOC PORT XP3184
Address:	819 W NO LOOP BLVD
City,State,Zip:	AUSTIN, TX 787562214
AI Number:	20853
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/01/1988
Facility Status:	INACTIVE
Additional ID:	210615462002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	HARRY C HIXSON,SR MGR ENV MGMT
Contact Organization Name:	NORTH LOOP SOC PORT XP3184
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	8664926836
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/19/1986
Signature Name/Title On Earliest Reg Form:	G BEAN,ASST SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	35290742001297
Additional ID:	210615462002150
Ai Number:	20853
Operator CN:	CN600261663
Operator Name:	SOUTHWESTERN BELL TELEPHONE LP
Operator Effective Begin Date:	09/01/1988
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	WILLIAM EISCLE/
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	4119 BROADWAY
Contact Mailing Address (Internal Delivery):	RM 610 ATTN RUBEN VASQUEZ
Contact Mailing City/State/Zip:	SAN ANTONIO TX 78209-6315

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Contact Phone Country Code:	0
Contact Phone Area Code:	210
Contact Phone Number:	2831636
Contact Phone Extension:	0
Contact Fax Country Code:	0
Contact Fax Area Code:	210
Contact Fax Number:	8042912
Contact Fax Extension:	0
Contact Email Address:	RV1515@ATT.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600261663
Owner Last Name:	SOUTHWESTERN BELL TELEPHONE LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75202
Contact Mailing Zip5:	5315
Contact Phone Number/Ext:	1 214 4647047/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	35290742001297
Additional ID:	210615462002150
AI Number:	20853
Owner Effective Begin Date:	09/01/1988
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	ROBERT PICKENS/ENV HLTH & SAFETY MGR
Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP

Self Certification:

Self Cert ID:	76709
Cert ID:	118365
AI Number:	20853
Self Certification Date:	05/22/2008
Signature Name/Title:	MARK DINUBILA MANAGER EHS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Self Cert ID:	76709
Cert ID:	118364
AI Number:	20853
Self Certification Date:	03/22/2007
Signature Name/Title:	ROBERT D TAYLOR ENVIRONMENTAL MANAGE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76709
Cert ID:	118363
AI Number:	20853
Self Certification Date:	02/24/2006
Signature Name/Title:	CHERYL ALLEN ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76709
Cert ID:	118362
AI Number:	20853
Self Certification Date:	02/07/2005
Signature Name/Title:	HARRY C HIXSON
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Self Cert ID:	76709
Cert ID:	118361
AI Number:	20853
Self Certification Date:	01/21/2004
Signature Name/Title:	HARRY C HIXSON SR ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76709
Cert ID:	118360
AI Number:	20853
Self Certification Date:	02/20/2003
Signature Name/Title:	HARRY C HIXSON SEN ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	76709
Cert ID:	118359
AI Number:	20853
Self Certification Date:	03/06/2002
Signature Name/Title:	HARRY C HIXSON SR ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Self Cert ID:	76709
Cert ID:	118358
AI Number:	20853
Self Certification Date:	01/15/2001
Signature Name/Title:	MICHAEL A OLIVER SR ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	12/01/1990
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10058
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	53566
Facility ID:	76709
Ai Number:	20853
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/03/2008
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	10058
UST Comprt ID:	114855
UST ID:	53566
AI Number:	20853
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	Y
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8003
Cert ID:	31335
UST Comprt ID:	101582
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31333
UST Comprt ID:	101584
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31332
UST Comprt ID:	101585
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31331
UST Comprt ID:	101586
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31330
UST Comprt ID:	101587
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31329
UST Comprt ID:	101590
UST ID:	27951
AI Number:	20853

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31328
UST Comprt ID:	101589
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	380994
UST Comprt ID:	1111642
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	363933
UST Comprt ID:	1059365
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	347266
UST Comprt ID:	1008994
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31327
UST Comprt ID:	101588
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	248128
UST Comprt ID:	713417
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	230840
UST Comprt ID:	662670
UST ID:	27951
AI Number:	20853
Tank ID:	1

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31339
UST Comprt ID:	101578
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	329564
UST Comprt ID:	955247
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	312842
UST Comprt ID:	905372
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	295282
UST Comprt ID:	852778
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	279096
UST Comprt ID:	804626
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	262496
UST Comprt ID:	755888
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31338
UST Comprt ID:	101579
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Self Cert ID:	8003
Cert ID:	31337
UST Comprt ID:	101580
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31336
UST Comprt ID:	101581
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31334
UST Comprt ID:	101583
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	53565
Facility ID:	76709
Ai Number:	20853
Tank Id:	XY1904U
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	XY1904U
Tank Capacity:	10000
UST Comprt ID:	114854
UST ID:	53565
AI Number:	20853
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	8003
Cert ID:	31335
UST Comprt ID:	101582
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31333
UST Comprt ID:	101584
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31332
UST Comprt ID:	101585
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31331
UST Comprt ID:	101586
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31330
UST Comprt ID:	101587
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Self Cert ID:	8003
Cert ID:	31329
UST Comprt ID:	101590
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	31328
UST Comprt ID:	101589
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	380994
UST Comprt ID:	1111642
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	363933
UST Comprt ID:	1059365
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	347266
UST Comprt ID:	1008994
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	31327
UST Comprt ID:	101588
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	248128
UST Comprt ID:	713417
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Cert ID:	230840
UST Comprt ID:	662670
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	31339
UST Comprt ID:	101578
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	329564
UST Comprt ID:	955247
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	312842
UST Comprt ID:	905372
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	295282
UST Comprt ID:	852778
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	279096
UST Comprt ID:	804626
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	262496
UST Comprt ID:	755888
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Self Cert ID:	8003
Cert ID:	31338

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

UST Comprt ID:	101579
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31337
UST Comprt ID:	101580
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31336
UST Comprt ID:	101581
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A
Self Cert ID:	8003
Cert ID:	31334
UST Comprt ID:	101583
UST ID:	27951
AI Number:	20853
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	9687
Facility ID:	76709
AI Number:	20853
Application Received Date:	11/27/2000
Scheduled Construction Date:	12/16/2000
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M11127026
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

NOC ID:	9686
Facility ID:	76709
AI Number:	20853
Application Received Date:	04/09/2008
Scheduled Construction Date:	05/12/2008
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M80409004
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22573
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	10397
UST ID:	Not reported
NOC ID:	9687
AI Number:	20853
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000001
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Cont/Cons/Installer ID:	10396
UST ID:	Not reported
NOC ID:	9686
AI Number:	20853
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001431
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHWESTERN BELL TELEPHONE LP
Contact Mailing Address (Delivery):	308 S AKARD ST RM 1700
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75202 5315
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	76709
Additional ID:	210615462002150
Princ ID:	35290742001297
AI Number:	20853
Facility Name:	NORTH LOOP SOC PORT XP3184
AR Number:	22573
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	NORTH LOOP SBC PORT
Address:	819 W NORTH LOOP BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	961
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	NORTH LOOP SOC PORT XP3184

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Address:	819 W NO LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76709
Finass ID:	64050
AI:	20853
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	Not reported
Policy Number:	1595289
Coverage Amount:	1000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LOOP SOC PORT XP3184
Address:	819 W NO LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76709
Finass ID:	9758
AI:	20853
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/01/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 0 0
Policy Number:	1595289
Coverage Amount:	2000000
Coverage Expiration Date:	06/01/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	NORTH LOOP SOC PORT XP3184
Address:	819 W NO LOOP BLVD
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	76709
Finass ID:	64051
AI:	20853
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

NORTH LOOP SOC PORT XP3184 (Continued) **U001255577**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

2778 **TOWN LAKE GULF SERVICE** **EDR Hist Auto** **1013758709**
NE **901 CLERMONT AVE** **N/A**
< 1/8 **AUSTIN, TX**
0.104 mi.
549 ft.

Actual:
460 ft.

EDR Hist Auto

Focus Map:
14

Year:	Name:	Type:
1965	TOWN LAKE GULF SERVICE	GASOLINE STATIONS

QB2779 **COMMEMORATIVE BRANDS** **TX LPST** **S104275261**
ESE **7211 CIRCLE S RD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78745** **TX IHW CORR ACTION**
0.104 mi.
549 ft. **Site 1 of 3 in cluster QB**

Actual:
671 ft.

Focus Map:
17

LPST:

Name:	C J C HOLDINGS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78714
Facility ID:	0006726
LPST Id:	105722
Facility Location:	7211 CIRCLE S RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/07/1993
Entered Date:	01/23/1995
Reported Date:	01/07/1993
Closure Date:	02/12/1993
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	J R HOWARD
Responsible Party Address:	7211 CIRCLE S RD
Responsible Party City,St,Zip:	AUSTIN, TX 78714
Responsible Party Telephone:	512/440-2434

COMMEMORATIVE BRANDS (Continued) **S104275261**

Reported Date:	01/07/1993
Case Start Date:	02/12/1993
Reference Number:	RN102413382
Project Manager:	HWELCH

Ind. Haz Waste:

Name:	COMMEMORATIVE BRANDS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	32601
Registration Initial Notification Date:	01/14/1983
Registration Last Amendment Date:	08/15/2022
EPA Identification:	TXD026028357
Primary NAICS Code:	339910
Status Change Date:	19830114
Land Type:	PRIVATE
Description of Facility Site Location:	7211 CIRCLE S RD AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	1
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	COMMEMORATIVE BRANDS INC
Contact Name:	HARRY A LEONARD
Contact Telephone Number:	512-4402110
Mailing Address:	PO BOX 149056
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787149056
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	10138
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220815
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

COMMEMORATIVE BRANDS (Continued) **S104275261**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	COMMEMORATIVE BRANDS INC
Operator Address:	PO BOX 149056
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78714
Operator Country:	UNITED STA
Operator Telephone:	1-512-4402320
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11339158013
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COMMEMORATIVE BRANDS INC
Owner Mailing Address:	PO BOX 149056
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78714
Owner Country:	UNITED STA
Owner Telephone:	1-512-4402320
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11339158013
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	17
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	010
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Wastewater collection and treatment system for metals as required by City o f A
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	17
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	070
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Cynadie destruction unit for rinse waterfrom gold plating line. Permited as pr
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	17
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Investment settling tanks
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960223
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	004
Unit Type Code:	23
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Hazardous material building.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960223
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Maintenance yard container storage area.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960223

COMMEMORATIVE BRANDS (Continued) **S104275261**

Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	006
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Reovery lab container storage area. Request to inactivate unit received 6/23/06.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20060623
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	007
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	R&D lab container storage area. Request to inactivate unit received 6/23/06.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20060623
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	008
Unit Type Code:	22

COMMEMORATIVE BRANDS (Continued) **S104275261**

Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dumpsters for plant trash.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960223
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	009
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	11
UIC Permit Number:	Not reported
Capacity:	12000
Capacity Measurement:	P
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	2
Off Site Class 2 Waste:	3
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Prescious metals scrap collection and storage area for gold recovery. Totally en
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20080625
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	010
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	1100
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Container storage area for WWT. Capacity in lbs is 9471
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20060623
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	011
Unit Type Code:	23
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	4000
Capacity Measurement:	P
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Caustic waste container storage area (Kolene)
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100203
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	012
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Dry Investment dumpster at building C
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100203
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	013
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	15
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Investment sludge dumpster disposed of by BFI
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100203
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	014
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	15
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Construction trash roll off dumpster
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100203

COMMEMORATIVE BRANDS (Continued) **S104275261**

Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	015
Unit Type Code:	24
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	10
Capacity Measurement:	Y
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Yard clippings and misc. yard trash
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100203
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 149056
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78714
Contact Phone:	1-512-4402320
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 149056
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78714
Contact Phone:	1-512-4402320
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	HARRY LEONARD
Contact Title:	E H S TECHNICIAN
Contact Role:	PRICONT
Contact Address:	PO BOX 149056
Contact Address 2:	Not reported
Contact Address 3:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Contact City,State,Zip:	AUSTIN, TX 78714
Contact Phone:	1-512-4402110
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	127149
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001313H
Waste Code Status:	INACTIVE
Waste Form:	313
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SOLID CYANIDE SALTS AND BOTTOM SLUDGES HAVING BEEN GENERATED IN PLATING PROCESS/
Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W312
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145242
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002316H
Waste Code Status:	INACTIVE
Waste Form:	316
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CAUSTIC AND/OR METAL SALTS HAVING BEEN GENERATED AS A RESIDUE OR DISCARDEDPRODUC
Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W316
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

COMMEMORATIVE BRANDS (Continued) **S104275261**

Ind. Haz Waste:

Waste ID:	145243
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003113H
Waste Code Status:	INACTIVE
Waste Form:	113
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT CYANIDE PLATING LIQUID GENERATED FROM PLATING PROCESSES/ 1994.; Due to was
Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145244
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	METHYLENE CHLORIDE WITH ADHESIVE GENERATED IN CLEANING/1994
Standard Industrial Code:	39110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145245

COMMEMORATIVE BRANDS (Continued) **S104275261**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00055192
Waste Code Status:	ACTIVE
Waste Form:	519
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CERAMIC INVESTMENT MATERIAL GENERATED IN MOLDING PROCESSES/1994.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	145246
Texas Waste Code:	Not reported
Texas Waste Code 2:	00061132
Waste Code Status:	ACTIVE
Waste Form:	113
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	WASTEWATER WITH INVESTMENT MATERIAL GENERATED IN MOLDING PROCESSE 1994.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	145249
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007113H
Waste Code Status:	INACTIVE
Waste Form:	113
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	WASTEWATER GENERATED FROM GOLD-PLATING PROCESSES/ 1994.; Due to waste minimizati

COMMEMORATIVE BRANDS (Continued) **S104275261**

Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145253
Texas Waste Code:	Not reported
Texas Waste Code 2:	00081142
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NEAUTRALIZED WASTEWATER FROM GOLD RECOVERY-CYANIDE; Due to waste minimization, i
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	145254
Texas Waste Code:	Not reported
Texas Waste Code 2:	00091142
Waste Code Status:	ACTIVE
Waste Form:	114
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PLANT WASTEWATER THAT CAN CONTAIN METALS AND/OR INVESTMENT MATERIA 1994.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

COMMEMORATIVE BRANDS (Continued) **S104275261**

Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	145256
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MISCELLANEOUS LABPACKS OF DISCARDED OR EXPIRED LAB CHEMICALS OR OBSOLETE PRODUCT
Standard Industrial Code:	39110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145257
Texas Waste Code:	Not reported
Texas Waste Code 2:	00112061
Waste Code Status:	ACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	USED OIL GENERATED IN MACHINE MAINTENANCE/1994.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Waste ID:	145258
Texas Waste Code:	Not reported
Texas Waste Code 2:	00123071
Waste Code Status:	ACTIVE
Waste Form:	307
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SCRAP METAL (stainless steel, aluminum, iron, copper) generated in manufacturin
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	145259
Texas Waste Code:	Not reported
Texas Waste Code 2:	00139992
Waste Code Status:	ACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PLANT OFFICE/PRODUCTION REFUSE/1994.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	188661
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014296H
Waste Code Status:	ACTIVE
Waste Form:	296

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT ANTIFREEZE GENERATED FROM PLATING PROCESSES/ 2001
Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SAME
Primary NAICS Code:	339911
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	189843
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OVEN BURNERS WITH BUILDUP OF CORROSIVE SOLID SODIUM HYDROXIDE/2001
Standard Industrial Code:	39110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	same
Primary NAICS Code:	339911
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	190132
Texas Waste Code:	Not reported
Texas Waste Code 2:	00169022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	RCRA EMPTY CONTAINERS-(TRIPLE RINSED)

COMMEMORATIVE BRANDS (Continued) **S104275261**

Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	145260
Texas Waste Code:	Not reported
Texas Waste Code 2:	00179022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUPPLEMENTAL PLANT PRODUCTION REFUSE THAT MAY CONTAIN SMALL AMOUN OFSANDBLAST
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	190872
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018313H
Waste Code Status:	INACTIVE
Waste Form:	313
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PPE, PAPER TOWELS AND MISCELLANEOUS CLEANING MATERIALS CONTAMINATE WITH CYANIDE
Standard Industrial Code:	39110
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SAME

COMMEMORATIVE BRANDS (Continued) **S104275261**

Primary NAICS Code:	339911
EPA Waste Form Code:	W312
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191808
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT SOLVENT WITH MOTOR OIL AND PLASTIC SHAVINGS
Standard Industrial Code:	39110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	0019
Primary NAICS Code:	339911
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191809
Texas Waste Code:	Not reported
Texas Waste Code 2:	0020207H
Waste Code Status:	ACTIVE
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT LUBRICANT WITH WAX (MOOSEMILK)
Standard Industrial Code:	39110
Primary Source:	G04
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	0020
Primary NAICS Code:	339911
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191810
Texas Waste Code:	Not reported
Texas Waste Code 2:	00214891
Waste Code Status:	ACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SOCKS,RAGS,TOWELS AND OTHER DEBRIS USED TO SOAK UP OIL AND/OR WIPE SURFACES ANDE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	0021
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	194012
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OVEN BURNERS WITH BUILDUP OF CORROSIVE SOLID SODIUM HYDROXIDE; Due t waste mini
Standard Industrial Code:	39110
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	0022
Primary NAICS Code:	339911
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste ID:	197542
Texas Waste Code:	Not reported
Texas Waste Code 2:	00233021
Waste Code Status:	ACTIVE
Waste Form:	302
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SOIL CONTAMINATED WITH RESIDUAL SODIUM HYDROXIDE/SODIUM PHOSPHATE ANDEXTHOYLATED
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	201387
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024201H
Waste Code Status:	ACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT WASH FROM CLEANING PROCESS OF RING TOPS.
Standard Industrial Code:	Not reported
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPECIAL TOPS WASTE
Primary NAICS Code:	339911
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste ID:	221614
Texas Waste Code:	Not reported
Texas Waste Code 2:	0025113H
Waste Code Status:	ACTIVE
Waste Form:	113
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent oxiguard dip from ring cleaning process containing >120 ppm of chrome.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT OXIGUARD DIP
Primary NAICS Code:	339911
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	216886
Texas Waste Code:	Not reported
Texas Waste Code 2:	0026319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used flourescent light tubes from a major construction rennovation.
Standard Industrial Code:	Not reported
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W320
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	236852
Texas Waste Code:	Not reported
Texas Waste Code 2:	00271141
Waste Code Status:	ACTIVE

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste Form:	114
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent synergy lubricant (96% water) containing less than 5.0 mg/L lead. Used asa
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT SYNERGY 15 LUB
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	236853
Texas Waste Code:	Not reported
Texas Waste Code 2:	00283101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent snygery 15 lubricant filters containing less than 5.0 mg/L of lead
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT SNYERGY 15 FIL
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	92479
Texas Waste Code:	Not reported
Texas Waste Code 2:	1030312H
Waste Code Status:	INACTIVE
Waste Form:	312
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Cyandide Diating Salts from Class Rings Gold Plating.
Standard Industrial Code:	39110
Primary Source:	G09
Primary Measurement Point:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339911
EPA Waste Form Code:	W312
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	204231
Texas Waste Code:	Not reported
Texas Waste Code 2:	18009022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	metal parts, refractory, and construction debris from decommissioning of trash i
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	TRASH INCINERATOR
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Waste ID:	123851
Texas Waste Code:	Not reported
Texas Waste Code 2:	2000203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Ethyl alcohol and ethyl polysilicate, outdated material; 1995
Standard Industrial Code:	39110
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TSOCL - 44803
Primary NAICS Code:	339911
EPA Waste Form Code:	W203

COMMEMORATIVE BRANDS (Continued) **S104275261**

Reason Waste Form No Longer Gen: UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	209148
Texas Waste Code:	Not reported
Texas Waste Code 2:	20010031
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixed lab packs of non-hazardous chemicals and materials
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HAZ LAB PACK
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	211363
Texas Waste Code:	Not reported
Texas Waste Code 2:	2005002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	cyanide contaminated construction debris after decommissioning plating room.; Du
Standard Industrial Code:	Not reported
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CONSTRUCTION DEBRIS
Primary NAICS Code:	332813
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste ID:	244228
Texas Waste Code:	Not reported
Texas Waste Code 2:	2006003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Equipment, piping, tanks, and other debris associated with decomissioned salt ba
Standard Industrial Code:	Not reported
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	KOLENE ROOM DECONTAM
Primary NAICS Code:	339911
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	361665
Texas Waste Code:	Not reported
Texas Waste Code 2:	20140091
Waste Code Status:	ACTIVE
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Used emergency exit signs containing low level tritium
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	USED EXIT SIGNS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	379301
Texas Waste Code:	Not reported
Texas Waste Code 2:	2015103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H

COMMEMORATIVE BRANDS (Continued) **S104275261**

Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Corrosive spent rhodium plating solution sent for precious metal recovery
Standard Industrial Code:	Not reported
Primary Source:	G03
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	RHODIUM PLATING
Primary NAICS Code:	339911
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	404096
Texas Waste Code:	Not reported
Texas Waste Code 2:	2019204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	85-90% Isopropyl Alcohol. Remaining 15% constituents - ethylene glycol, hydroxyl
Standard Industrial Code:	Not reported
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	3D PRINTING WASTE
Primary NAICS Code:	339910
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	259865
Texas Waste Code:	Not reported
Texas Waste Code 2:	B3RC110H
Waste Code Status:	Not reported
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272759
Texas Waste Code:	Not reported
Texas Waste Code 2:	CH8P203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	271348
Texas Waste Code:	Not reported
Texas Waste Code 2:	CHQN203H
Waste Code Status:	Not reported
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported

COMMEMORATIVE BRANDS (Continued) **S104275261**

EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	273358
Texas Waste Code:	Not reported
Texas Waste Code 2:	CL75114H
Waste Code Status:	Not reported
Waste Form:	114
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	286133
Texas Waste Code:	Not reported
Texas Waste Code 2:	DH4H306H
Waste Code Status:	Not reported
Waste Form:	306
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

COMMEMORATIVE BRANDS (Continued) **S104275261**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 149107
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78714
AR Number:	0000306769
Principal Name:	COMMEMORATIVE BRANDS INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 149107
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78714
AR Number:	0000306769
Principal Name:	COMMEMORATIVE BRANDS INC
Attention Name:	Not reported
Attention Suffix:	HWG

IHW CORR ACTION:

Name:	COMMEMORATIVE BRANDS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745
Program Id:	32601
Location Desc:	7211 CIRCLE S RD AUSTIN TX
RN NUM:	RN102413382
Status:	INACTIVE
Status Date:	02/15/2022
EDR Link ID:	32601
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	02/15/2022
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

QB2780 **CJC HOLDINGS** **TX UST** **U001243177**
ESE **7211 CIRCLE S RD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.104 mi.
549 ft. **Site 2 of 3 in cluster QB**

Actual:
671 ft.

Focus Map:
17

UST:

Name:	CJC HOLDINGS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 787456603
AI Number:	6726
Facility Type:	UNKNOWN
Facility Begin Date:	06/09/1986
Facility Status:	INACTIVE
Additional ID:	125612372003202
Facility Exempt Status:	N

CJC HOLDINGS (Continued) **U001243177**

Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78714
Contact Name/Title:	,
Contact Organization Name:	CJC HOLDINGS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124402320
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/07/1986
Signature Name/Title On Earliest Reg Form:	JOHN PERSON,GENERAL SER MGR
Application Received Date On Earliest Reg Form:	05/09/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600409973
Owner Last Name:	ARTCARVED CLASS RINGS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	216527972001313
Additional ID:	125612372003202
AI Number:	6726
Owner Effective Begin Date:	06/09/1986
State Tax ID:	17306281977
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1975
Tank Registration Date:	05/09/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N

CJC HOLDINGS (Continued) **U001243177**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	17257
Facility ID:	45729
Ai Number:	6726
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/12/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

CJC HOLDINGS (Continued) **U001243177**

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	23598
UST ID:	17257
AI Number:	6726
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ARTCARVED CLASS RINGS INC
Contact Mailing Address (Delivery):	PO BOX 149156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78714 9156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	45729
Additional ID:	125612372003202
Princ ID:	216527972001313

CJC HOLDINGS (Continued) **U001243177**

AI Number:	6726
Facility Name:	CJC HOLDINGS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	C J C HOLDINGS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0379
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QB2781 **COMMEMORATIVE BRANDS** **RCRA-VSQG** **1000168017**
ESE **7211 CIRCLE S RD** **FINDS** **TXD026028357**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.104 mi.
549 ft. **Site 3 of 3 in cluster QB**

Actual:
671 ft.

Focus Map:
17

RCRA Listings:

Date Form Received by Agency:	20220815
Handler Name:	Commemorative Brands
Handler Address:	7211 CIRCLE S RD
Handler City,State,Zip:	AUSTIN, TX 78745-6603
EPA ID:	TXD026028357
Contact Name:	HARRY LEONARD
Contact Address:	PO BOX 149056
Contact City,State,Zip:	AUSTIN, TX 78714-9056
Contact Telephone:	512-440-2110
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 149056
Mailing City,State,Zip:	AUSTIN, TX 78714-9056
Owner Name:	Commemorative Brands Inc
Owner Type:	Private
Operator Name:	Commemorative Brands Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

COMMEMORATIVE BRANDS (Continued) **1000168017**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220826
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

COMMEMORATIVE BRANDS (Continued) **1000168017**

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends

COMMEMORATIVE BRANDS (Continued) **1000168017**

Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F006
Waste Description: Wastewater Treatment Sludges From Electroplating Operations, Except From The Following Processes: (1) Sulfuric Acid Anodizing Of Aluminum; (2) Tin Plating On Carbon Steel; (3) Zinc Plating (Segregated Basis) On Carbon Steel; (4) Aluminum Or Zinc-Aluminum Plating On Carbon Steel; (5) Cleaning/Stripping Associated With Tin, Zinc, And Aluminum Plating On Carbon Steel; And (6) Chemical Etching And Milling Of Aluminum.

Waste Code: F007
Waste Description: Spent Cyanide Plating Bath Solutions From Electroplating Operations.

Waste Code: F008
Waste Description: Plating Bath Residues From The Bottom Of Plating Baths From Electroplating Operations In Which Cyanides Are Used In The Process.

Waste Code: F009
Waste Description: Spent Stripping And Cleaning Bath Solutions From Electroplating Operations In Which Cyanides Are Used In The Process.

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ARTCARVED CLASSRINGS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2905
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 512-444-0571
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20080701
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC	
Legal Status:	Private
Date Became Current:	20090901
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC	
Legal Status:	Private
Date Became Current:	20070724
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714-9056
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC	
Legal Status:	Not reported
Date Became Current:	20040309
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC	
Legal Status:	Private
Date Became Current:	20080429
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC	
Legal Status:	Private
Date Became Current:	20080429
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20080701
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20100504
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20030902

COMMEMORATIVE BRANDS (Continued) **1000168017**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714-9056
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COMMEMORATIVE BRANDS INC
Legal Status:	Private
Date Became Current:	20070724
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714-9056
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COMMEMORATIVE BRANDS INC
Legal Status:	Private
Date Became Current:	20050602
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COMMEMORATIVE BRANDS INC
Legal Status:	Private
Date Became Current:	20100209
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COMMEMORATIVE BRANDS INC
Legal Status:	Private
Date Became Current:	20070724
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 149056
Owner/Operator City,State,Zip:	AUSTIN, TX 78714-9056
Owner/Operator Telephone:	512-440-2320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Other
Date Became Current: 20030902
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20040309
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ARTCARVED CLASSRINGS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2905
Owner/Operator City,State,Zip: AUSTIN, TX 78769
Owner/Operator Telephone: 512-444-0571
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20050216
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20060504
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20060623

COMMEMORATIVE BRANDS (Continued) **1000168017**

Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20060825
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20090901
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20100209
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20100504
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20040309
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20030902
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Private
Date Became Current: 20070724
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 149056
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: 512-440-2320
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMMEMORATIVE BRANDS INC
Legal Status: Other
Date Became Current: 20030902
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: AUSTIN, TX 78714-9056
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100301
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

COMMEMORATIVE BRANDS (Continued) **1000168017**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970121
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040309
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050216
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050602
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060504
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060628
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060825
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070731
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator

COMMEMORATIVE BRANDS (Continued) **1000168017**

State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080429
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080701
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090901
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100209
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

COMMEMORATIVE BRANDS (Continued) **1000168017**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20100504
Handler Name:	COMMEMORATIVE BRANDS INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140318
Handler Name:	COMMEMORATIVE BRANDS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160126
Handler Name:	COMMEMORATIVE BRANDS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180926
Handler Name:	COMMEMORATIVE BRANDS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Receive Date: 20191025
Handler Name: COMMEMORATIVE BRANDS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200218
Handler Name: COMMEMORATIVE BRANDS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200622
Handler Name: COMMEMORATIVE BRANDS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220218
Handler Name: COMMEMORATIVE BRANDS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220815
Handler Name: COMMEMORATIVE BRANDS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No

COMMEMORATIVE BRANDS (Continued) **1000168017**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19980125
Handler Name: COMMEMORATIVE BRANDS, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000125
Handler Name: COMMEMORATIVE BRANDS, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040301
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

COMMEMORATIVE BRANDS (Continued) **1000168017**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060301
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080301
Handler Name: COMMEMORATIVE BRANDS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332211
NAICS Description: CUTLERY AND FLATWARE (EXCEPT PRECIOUS) MANUFACTURING

NAICS Code: 33991
NAICS Description: JEWELRY AND SILVERWARE MANUFACTURING

NAICS Code: 339910
NAICS Description: JEWELRY AND SILVERWARE MANUFACTURING

NAICS Code: 339911
NAICS Description: JEWELRY (EXCEPT COSTUME) MANUFACTURING

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060823
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060823
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Container Use and Management
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060426
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Container Use and Management
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060823
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060823
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060823
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060823
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060426
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060823
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060823
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-General Facility Standards
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20100121
Actual Return to Compliance Date:	20100311
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	2
Date of Enforcement Action:	20100218
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	11
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20060426
Actual Return to Compliance Date:	20060426
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	1
Date of Enforcement Action:	20060510
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060426
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20060426
Actual Return to Compliance Date: 20060823
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20060510
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Date Violation was Determined: 20100121
Actual Return to Compliance Date: 20100311
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 2
Date of Enforcement Action: 20100218
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060426
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes

COMMEMORATIVE BRANDS (Continued) **1000168017**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060823
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060426
Scheduled Compliance Date:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100415
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060426
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

COMMEMORATIVE BRANDS (Continued) **1000168017**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060426
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060426
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20060823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100121
Evaluation Responsible Agency:	State

COMMEMORATIVE BRANDS (Continued) **1000168017**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20100311
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110070753098

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS WASTE BIENNIAL REPORTER
Registry ID: 110000822030

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

COMMEMORATIVE BRANDS (Continued) **1000168017**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000168017
Registry ID:	110000822030
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000822030
Name:	COMMEMORATIVE BRANDS
Address:	7211 CIRCLE S RD
City,State,Zip:	AUSTIN, TX 78745

PS2782 **AUSTIN LAUNDRY & DRY** **EDR Hist Cleaner** **1013779973**
West **911 W 24TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.105 mi.
552 ft. **Site 5 of 7 in cluster PS**

Actual:
599 ft.

Focus Map:
11

EDR Hist Cleaner

Year:	Name:	Type:
1965	AUSTIN LAUNDRY & DRY	LAUNDRIES

2783 **FOOD SPOT 2** **TX UST** **U001283383**
NE **2538 ELMONT DR** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78741** **TX ASBESTOS**
0.105 mi. **TX Financial Assurance**
552 ft. **TX RDR**

Actual:
466 ft.

Focus Map:
15

UST:

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 787411733
AI Number:	52881
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	634207132002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	FAIZAN MOTIWALA,MGR
Contact Organization Name:	FOOD SPOT 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124421931
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/29/2016

FOOD SPOT 2 (Continued) **U001283383**

Signature Name/Title On Earliest Reg Form:	FAIZAM MOTIWALA,
Application Received Date On Earliest Reg Form:	01/10/2017
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	194061942012346
Additional ID:	634207132002139
Ai Number:	52881
Operator CN:	CN604216168
Operator Name:	RIAZ HASHMANI
Operator Effective Begin Date:	01/01/2004
Operator Type:	IN
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603545583
Owner Last Name:	FOODSPOT GROCERIES LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	657542852009286
Additional ID:	634207132002139
AI Number:	52881
Owner Effective Begin Date:	08/01/1993
State Tax ID:	17431681273
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Self Certification:

Self Cert ID:	82902
Cert ID:	280404
AI Number:	52881
Self Certification Date:	11/29/2016
Signature Name/Title:	FAIZAM MOTIWALA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	82902
Cert ID:	265588
AI Number:	52881
Self Certification Date:	01/16/2016
Signature Name/Title:	RIAZ HASHMANI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	82902
Cert ID:	248141
AI Number:	52881
Self Certification Date:	01/25/2015
Signature Name/Title:	RIAZ HASHMANI OPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

FOOD SPOT 2 (Continued) **U001283383**

Self Cert ID:	82902
Cert ID:	244051
AI Number:	52881
Self Certification Date:	10/06/2014
Signature Name/Title:	RIAZ HASHMANI OPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	82902
Cert ID:	129947
AI Number:	52881
Self Certification Date:	12/26/2012
Signature Name/Title:	RIAZ HASHMANI OPER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129946
AI Number:	52881
Self Certification Date:	12/20/2011
Signature Name/Title:	RIAZ HABHMANI OPERATOR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Self Cert ID:	82902
Cert ID:	129945
AI Number:	52881
Self Certification Date:	11/20/2010
Signature Name/Title:	RIAZ HASHMANI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129944
AI Number:	52881
Self Certification Date:	12/27/2009
Signature Name/Title:	RIAZ HASMANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129943
AI Number:	52881
Self Certification Date:	12/01/2008
Signature Name/Title:	RIAZ HASHMANI OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Self Cert ID:	82902
Cert ID:	129942
AI Number:	52881
Self Certification Date:	12/31/2007
Signature Name/Title:	RIAZ HASHMANI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129941
AI Number:	52881
Self Certification Date:	01/01/2007
Signature Name/Title:	RIAZ HASHMANI MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129940
AI Number:	52881
Self Certification Date:	01/09/2006
Signature Name/Title:	RAIZ HASHMANI
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Self Cert ID:	82902
Cert ID:	129939
AI Number:	52881
Self Certification Date:	02/15/2005
Signature Name/Title:	RAIZ HASHMANI
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129938
AI Number:	52881
Self Certification Date:	12/28/2003
Signature Name/Title:	RIAZ HASHMANI MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129937
AI Number:	52881
Self Certification Date:	12/04/2002
Signature Name/Title:	ASIF SATTAR MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Self Cert ID:	82902
Cert ID:	129936
AI Number:	52881
Self Certification Date:	12/13/2001
Signature Name/Title:	ASIF SATTAR MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	82902
Cert ID:	129935
AI Number:	52881
Self Certification Date:	01/17/2001
Signature Name/Title:	ASIF SATTAR MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/28/1990
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	131193
Facility ID:	82902
Ai Number:	52881
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/21/2020
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

FOOD SPOT 2 (Continued) **U001283383**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	136004
UST ID:	131193
AI Number:	52881
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

FOOD SPOT 2 (Continued) **U001283383**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/31/1987

Install Date:	08/31/1987
Tank Registration Date:	03/28/1990
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	131194
Facility ID:	82902
Ai Number:	52881
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/21/2020
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

FOOD SPOT 2 (Continued) **U001283383**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	136005
UST ID:	131194
AI Number:	52881
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

FOOD SPOT 2 (Continued) **U001283383**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/31/2087

Construction Notification:

NOC ID:	36571
Facility ID:	82902
AI Number:	52881
Application Received Date:	06/10/2020
Scheduled Construction Date:	07/27/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	06/10/2020
Signature Date On Form:	06/10/2020
Signature Name On Form:	KEVIN MORRISON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	FOODSPOT GROCERIES LP
Owner CN At Time Of Construction:	CN603545583
Owner AR At Time Of Construction:	45971
General Desc Of Prop Construct:	REMOVAL OF 2 8K USTS

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	86740
UST ID:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

NOC ID:	36571
AI Number:	52881
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	ALAMO ENVIRONMENTAL INC
Representative Name:	Not reported
Mailing Address (Delivery):	2900 NACOGDOCHES RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78217
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	210
Phone Number:	4041220
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	210
Fax Number:	8203636
Email Address:	alex@alamo1.com

Cont/Cons/Installer ID:	86738
UST ID:	Not reported
NOC ID:	36571
AI Number:	52881
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001410
Company Name:	ALAMO ENVIRONMENTAL INC
Representative Name:	Not reported
Mailing Address (Delivery):	2900 NACOGDOCHES RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78217
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	210
Phone Number:	4041220
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	210
Fax Number:	8203636
Email Address:	alex@alamo1.com

Cont/Cons/Installer ID:	86739
UST ID:	Not reported
NOC ID:	36571
AI Number:	52881
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002282
Company Name:	SCHRIBER RICHARD EDWARD
Representative Name:	Not reported
Mailing Address (Delivery):	12656 WILLIS WAUKEGAN RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	CONROE

FOOD SPOT 2 (Continued) **U001283383**

Mailing State:	TX
Mailing Zip:	77303
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	4041220
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	713
Fax Number:	8859898
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FOODSPOT GROCERIES LP
Contact Mailing Address (Delivery):	2538 ELMONT DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 1733
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	82902
Additional ID:	634207132002139
Princ ID:	657542852009286
AI Number:	52881
Facility Name:	FOOD SPOT 2
AR Number:	45971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RIAZ HASHMANI/

HIST UST AUSTIN:

Name:	FOOD SPOT #2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX
Id UST:	3085
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	FOOD SPOT
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/22/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

TX Financial Assurance 2:

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	173846
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2016
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	800 577 6614
Policy Number:	PP3641120-07
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/30/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	157339
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2015
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP364112006
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/30/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	139423
AI:	52881
Mechanism Type Other:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2014
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 804 5602000
Policy Number:	PP3641120 05
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/30/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	135213
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2013
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641120 04
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	10396
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2012
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO

FOOD SPOT 2 (Continued) **U001283383**

Issuer Phone:	1 800 5776614
Policy Number:	PP3641120-03
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	69210
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2010
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641120-01
Coverage Amount:	1000000
Coverage Expiration Date:	11/30/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	69211
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2009
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641120
Coverage Amount:	1000000
Coverage Expiration Date:	11/30/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR

FOOD SPOT 2 (Continued) **U001283383**

City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	69212
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/07/2008
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641004-01
Coverage Amount:	1000000
Coverage Expiration Date:	11/07/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	69213
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/07/2007
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641004
Coverage Amount:	1000000
Coverage Expiration Date:	11/07/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	82902
Finass ID:	69214
AI:	52881
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported

FOOD SPOT 2 (Continued) **U001283383**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	01/10/2017
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	29347
Facility ID:	52881
RN:	Not reported
CN:	Not reported
Name:	FOOD SPOT 2
Address:	2538 ELMONT DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/17/2020
Due Date:	2/15/2021
Tank Owner:	FAIZAN MOTIWALA
Contact Person:	FAIZAN MOTIWALA
Report:	Tank Closure
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/2/2021
Project Manager:	Emily Chen
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

QC2784 **C.A. PETERS** **TX HIST UST** **S111678584**
ENE **719 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.105 mi.
553 ft. **Site 1 of 12 in cluster QC**

Actual:
469 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	C.A. PETERS
Address:	719 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0330
HID UST:	330
Inspection:	04/15/2009
Due:	04/15/2012

QC2785 ENE < 1/8 0.105 mi. 553 ft. | **WALSH SERVICE STATION**
719 E 7TH ST
AUSTIN, TX 78701
Site 2 of 12 in cluster QC | **EDR Hist Auto** | **1020338099**
N/A

Actual: 469 ft.
Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1969	WALSH SERVICE STATION	Gasoline Service Stations
1970	WALSH SERVICE STATION	Gasoline Service Stations

NZ2786 ENE < 1/8 0.105 mi. 555 ft. | **MOBIL STATION**
E 7TH ST
AUSTIN, TX 78701
Site 4 of 4 in cluster NZ | **TX LPST** | **S104174809**
N/A

Actual: 463 ft.
Focus Map: 11

LPST:

Name:	MOBIL STATION
Address:	E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	Not reported
LPST Id:	091022
Facility Location:	E 7TH ST @ IH 35
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/16/1984
Entered Date:	10/17/1984
Reported Date:	10/17/1984
Closure Date:	03/06/1989
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	GB
Responsible Party Name:	Not reported
Responsible Party Contact:	DAVID NOE
Responsible Party Address:	3800 W ALAMEDA AVE STE 700
Responsible Party City,St,Zip:	BURBANK, CA 91505
Responsible Party Telephone:	818/953-2519
Reported Date:	10/17/1984
Case Start Date:	03/06/1989
Reference Number:	RN106972441
Project Manager:	GB

OT2787 WNW < 1/8 0.105 mi. 556 ft. | **IMPORT MOTORS**
3520 N LAMAR BLVD
AUSTIN, TX 78705
Site 7 of 8 in cluster OT | **TX HIST UST**
TX Ind. Haz Waste
TX CENTRAL REGISTRY | **S102748657**
N/A

Actual: 600 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	IMPORTS MOTORS INC
Address:	3520 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX

IMPORT MOTORS (Continued) **S102748657**

Id UST:	N0132
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	IMPORT MOTORS
Address:	3520 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	61806
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	3520 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	IMPORT MOTORS
Contact Name:	MR NORWOOD
Contact Telephone Number:	Not reported
Mailing Address:	3520 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787051118
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20146
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0

IMPORT MOTORS (Continued) **S102748657**

Transport Own Waste: 0

Ind. Haz Waste:

Operator Name:	IMPORT MOTORS
Operator Address:	3520 N LAMAR BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17415875321
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	IMPORT MOTORS
Owner Mailing Address:	3520 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17415875321
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3520 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3520 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MR NORWOOD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	3520 N LAMAR BLVD

IMPORT MOTORS (Continued) **S102748657**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100640150
Name:	IMPORT MOTORS
Address:	3520 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1118
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600350607
Customer Name:	IMPORT MOTORS
Customer Legal Name:	Import Motors, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	3520 N Lamar Blvd, Austin, TX

2788 WNW < 1/8 0.105 mi. 556 ft. **BANYON AUTOMOTIVE AUTO REPAIR** **EDR Hist Auto** **1013759339**
916 BANYAN ST **N/A**
AUSTIN, TX 78757

Actual: 751 ft. EDR Hist Auto

Focus Map: 6

Year:	Name:	Type:
1984	BANYON AUTOMOTIVE AUTO REPAIR	AUTOMOBILE REPAIRING

PD2789 ESE < 1/8 0.105 mi. 556 ft. **BERANS CONOCO SERV STA** **EDR Hist Auto** **1013756225**
1500 SAN JACINTO **N/A**
AUSTIN, TX

Site 2 of 5 in cluster PD

Actual: 516 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	BERANS CONOCO SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	BAYS CONOCO SERV	GASOLINE STATIONS
1958	BAYS CONOCO SERV	GASOLINE STATIONS
1962	FRANKES SLS & SERV	GASOLINE STATIONS
1965	FRANKES SALES & SERVICE	GASOLINE STATIONS
1970	FRANKES SALES & SERVICE GAS STA	GASOLINE STATIONS
1973	FRANKES SALES & SERVICE	Gasoline Service Stations
1974	FRANKES SALES & SERVICE	Gasoline Service Stations
1975	FRANKES SALES & SERVICE GAS STA	GASOLINE STATIONS

BERANS CONOCO SERV STA (Continued) **1013756225**

1975	FRANKES SALES & SERVICE	Gasoline Service Stations
1976	FRANKES SALES & SERVICE	Gasoline Service Stations
1977	FRANKES SALES & SERVICE	Gasoline Service Stations
1978	FRANKES SALES & SERVICE	Gasoline Service Stations
1979	FRANKES SALES & SERVICE	Gasoline Service Stations
1980	FRANKES SALES & SERVICE	Gasoline Service Stations
1982	FRANKES SALES & SERVICE	Gasoline Service Stations
1983	FRANKES SALES & SERVICE	Gasoline Service Stations

PD2790 **TEXAS GENERAL SERVICES COMMISSION** **TX HIST UST** **S105836298**
ESE **1500 SAN JACINTO BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.105 mi.
556 ft. **Site 3 of 5 in cluster PD**

Actual:
516 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	HUEVO LEON TACO EXPRESS
Address:	1500 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3318
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	TEXAS GENERAL SERVICES COMMISSION
Address:	1500 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	75087
Registration Initial Notification Date:	01/03/1990
Registration Last Amendment Date:	10/29/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19900103
Land Type:	Not reported
Description of Facility Site Location:	1500 San Jacinto Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Contact Name:	JESSE WILLIAMS
Contact Telephone Number:	512-4633345
Mailing Address:	1711 SAN JACINTO BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787011416

TEXAS GENERAL SERVICES COMMISSION (Continued) **S105836298**

Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29442
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030902
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Operator Address:	1711 SAN JACINTO BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4633345
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Owner Mailing Address:	1711 SAN JACINTO BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4633345
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1711 SAN JACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701

TEXAS GENERAL SERVICES COMMISSION (Continued) **S105836298**

Contact Phone:	1-512-4633345
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1711 SAN JACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4633345
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JESSE WILLIAMS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1711 SAN JACINTO BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4633345
Contact Fax:	Not reported
Contact Email:	Not reported

2791 **T&T TRANSMISSION** **EDR Hist Auto** **1020143181**
ESE **601 FERGUSON DR** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.105 mi.
557 ft.

Actual:
764 ft.
EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
2003	T&T TRANSMISSION	Automotive Transmission Repair Shops
2004	T&T TRANSMISSION	Automotive Transmission Repair Shops
2005	T&T TRANSMISSION	Automotive Transmission Repair Shops
2006	T&T TRANSMISSION	Automotive Transmission Repair Shops
2007	T&T TRANSMISSION	Automotive Transmission Repair Shops
2008	T&T TRANSMISSION	Automotive Transmission Repair Shops
2010	T&T TRANSMISSION	Automotive Transmission Repair Shops
2011	T&T TRANSMISSION	Automotive Transmission Repair Shops
2012	T&T TRANSMISSION	Automotive Transmission Repair Shops
2013	T&T TRANSMISSION	Automotive Transmission Repair Shops
2014	T&T TRANSMISSION	Automotive Transmission Repair Shops

QD2792 ESE < 1/8 0.105 mi. 557 ft. | **7 ELEVEN 16084**
1700 SAN JACINTO BLVD
AUSTIN, TX 78701
Site 1 of 5 in cluster QD | **TX UST** **TX HIST UST** | **U001265600** **N/A**

Actual: 510 ft.

Focus Map: 11

UST:

Name:	7 ELEVEN 16084
Address:	1700 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 787011417
AI Number:	32373
Facility Type:	RETAIL
Facility Begin Date:	11/20/1986
Facility Status:	INACTIVE
Additional ID:	197240962002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	P NEUSE,MGR
Contact Organization Name:	7 ELEVEN 16084
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123462260
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/02/1986
Signature Name/Title On Earliest Reg Form:	C BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	197240962002118

7 ELEVEN 16084 (Continued) **U001265600**

AI Number:	32373
Owner Effective Begin Date:	11/20/1986
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	85019
Facility ID:	46477
Ai Number:	32373
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7 ELEVEN 16084 (Continued) **U001265600**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/16/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	33841
UST ID:	85019
AI Number:	32373
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

7 ELEVEN 16084 (Continued) **U001265600**

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	85020
Facility ID:	46477
Ai Number:	32373
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

7 ELEVEN 16084 (Continued) **U001265600**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/16/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	33842
UST ID:	85020
AI Number:	32373
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/

7 ELEVEN 16084 (Continued) **U001265600**

Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46477
Additional ID:	197240962002118
Princ ID:	959578622001257
AI Number:	32373
Facility Name:	7 ELEVEN 16084
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN
Address:	1700 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0085
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QD2793 **BURNETTE SERVICE STATION** **EDR Hist Auto** **1013753509**
ESE **1700 SAN JACINTO** **N/A**
< 1/8 **AUSTIN, TX**
0.105 mi.
557 ft. **Site 2 of 5 in cluster QD**

Actual:
510 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	BURNETTES GAR	AUTOMOBILE REPAIRING
1940	BURNETTES SERVICE	GASOLINE AND OIL SERVICE STATIONS
1947	BURNETTE SERVICE STATION	GASOLINE AND OIL SERVICE STATIONS
1947	BURNETTS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1953	BURNETTES SERV STA	GASOLINE STATIONS
1958	STA & GARAGE	GASOLINE STATIONS
1965	BURNETTES SERVICE	GASOLINE STATIONS
1969	BURNETTE SERVICE STATION & GAR	Gasoline Service Stations
1970	BURNETTES SERVICE STATION & GAR	GASOLINE STATIONS
1970	BURNETTE SERVICE STATION & GAR	Gasoline Service Stations
1971	BURNETTE SERVICE STATION & GAR	Gasoline Service Stations

---

OY2794 **MAGNOLIA PETROLEUM CO.** **TX HIST UST** **S111678736**
WNW **1002 W 34TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.105 mi.
557 ft. **Site 12 of 12 in cluster OY**

Actual:
587 ft.

HIST UST AUSTIN:

Name:	MAGNOLIA PETROLEUM CO.
Address:	1002 W 34TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0425
HID UST:	425

Focus Map:
8

MAGNOLIA PETROLEUM CO. (Continued) **S111678736**

Inspection: Not reported
Due: 06/01/2012

QE2795 **FLOWER STATION** **TX UST** **U001277658**
WNW **3100 N LAMAR BLVD** **TX DRYCLEANERS** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.106 mi.
559 ft. **Site 1 of 4 in cluster QE**

Actual:
574 ft.

Focus Map:
8

UST:

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787052013
AI Number:	46163
Facility Type:	RETAIL
Facility Begin Date:	06/23/1988
Facility Status:	INACTIVE
Additional ID:	167609202002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	FLOWER STATION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124766611
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	06/06/1988
Signature Name/Title On Earliest Reg Form:	WALTER HEIDMANN,REP
Application Received Date On Earliest Reg Form:	06/13/1988
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601243264
Owner Last Name:	TEXAS COMMERCE BANK-AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/

FLOWER STATION (Continued) **U001277658**

Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	177609202002150
Additional ID:	167609202002150
AI Number:	46163
Owner Effective Begin Date:	06/23/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1958
Tank Registration Date:	06/13/1988
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120850
Facility ID:	77530
Ai Number:	46163
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

FLOWER STATION (Continued) **U001277658**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	122659
UST ID:	120850
AI Number:	46163
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

FLOWER STATION (Continued) **U001277658**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1958
Tank Registration Date:	06/13/1988
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120851
Facility ID:	77530
Ai Number:	46163
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

FLOWER STATION (Continued) **U001277658**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	122660
UST ID:	120851
AI Number:	46163
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1958
Tank Registration Date:	06/13/1988

FLOWER STATION (Continued) **U001277658**

Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120852
Facility ID:	77530
Ai Number:	46163
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

FLOWER STATION (Continued) **U001277658**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	122661
UST ID:	120852
AI Number:	46163
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1958
Tank Registration Date:	06/13/1988
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120853
Facility ID:	77530
Ai Number:	46163

FLOWER STATION (Continued) **U001277658**

Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	122662
UST ID:	120853

FLOWER STATION (Continued) **U001277658**

AI Number:	46163
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS COMMERCE BANK AUSTIN
Contact Mailing Address (Delivery):	PO BOX 550
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 0550
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77530
Additional ID:	167609202002150
Princ ID:	177609202002150
AI Number:	46163
Facility Name:	FLOWER STATION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

FLOWER STATION (Continued) **U001277658**

DRYCLEANERS:

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102381365
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR15813
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	Not reported
Bill Addr2:	Not reported
Bill City/State/Zip:	Not reported
EMail:	Not reported
Phone Number:	0 0
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102381365
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR15813
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102381365
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR15813
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159

FLOWER STATION (Continued) **U001277658**

Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102381365
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR15813
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	FLOWER STATION
Address:	3100 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
RN Number:	RN102381365
Region:	REGION 11 - AUSTIN
CN Number:	CN600264543
DCR Number:	DCR15813
AR Number:	24000524
Principal Name:	JACK BROWN CLEANERS INC
Bill Addr1:	PO BOX 28159
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78755 8159
EMail:	PAULBJBC@AOL.COM
Phone Number:	512 4511333
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES

FLOWER STATION (Continued) **U001277658**

Gross Receipts: $150,000 OR LESS

Name: FLOWER STATION
Address: 3100 N LAMAR BLVD
City,State,Zip: AUSTIN, TX 78705
RN Number: RN102381365
Region: REGION 11 - AUSTIN
CN Number: CN600264543
DCR Number: DCR15813
AR Number: 24000524
Principal Name: JACK BROWN CLEANERS INC
Bill Addr1: PO BOX 28159
Bill Addr2: Not reported
Bill City/State/Zip: AUSTIN, TX 78755 8159
EMail: PAULBJBC@AOL.COM
Phone Number: 512 4511333
Site Name: Not reported
Site Type: DROP STATION REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2017
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: $150,000 OR LESS

QE2796 **R E LEIGH** **TX HIST UST** **S128729293**
WNW **3100 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.106 mi.
559 ft. **Site 2 of 4 in cluster QE**

Actual:
574 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: R E LEIGH
Address: 3100 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: H0489
HID UST: 489
Inspection: Not reported
Due: 06/01/2012

QE2797 **THE FLOWER STATION** **TX HIST UST** **S128728878**
WNW **3100 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.106 mi.
559 ft. **Site 3 of 4 in cluster QE**

Actual:
574 ft.

Focus Map:
8

HIST UST AUSTIN:
Name: THE FLOWER STATION
Address: 3100 N LAMAR BLVD
City,State,Zip: AUSTIN, TX
Id UST: C0053
HID UST: Not reported
Inspection: Not reported
Due: Not reported

QE2798 **CAR CARE BV ISSAC** **EDR Hist Auto** **1013765583**
WNW **3100 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.106 mi.
559 ft. **Site 4 of 4 in cluster QE**

Actual:
574 ft.

EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1962	LAMAR TEXACO	GASOLINE STATIONS
1965	LAMAR TEXACO SERVICE	GASOLINE STATIONS
1971	LIMBRICK TEXACO	Gasoline Service Stations
1971	GOULD WILLIAM J	Gasoline Service Stations
1975	NELSONS GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	BILLS TEXACO SERVICE	GASOLINE STATIONS
1980	CAR CARE BV ISSAC	AUTOMOBILE REPAIRING
1982	CAR CARE BY ISSAC	General Automotive Repair Shops
1983	CAR CARE BY ISSAC	General Automotive Repair Shops
1985	CAR CARE BY ISSAC	General Automotive Repair Shops

PC2799 **CHATLEFF CONTROLS** **TX Ind. Haz Waste** **S102738877**
ESE **205 INDUSTRIAL BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78745**
0.106 mi.
560 ft. **Site 3 of 4 in cluster PC**

Actual:
671 ft.

Ind. Haz Waste:

Focus Map:
18

Name:	CHATLEFF CONTROLS
Address:	205 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	30859
Registration Initial Notification Date:	02/09/1977
Registration Last Amendment Date:	07/26/2021
EPA Identification:	TXD000352823
Primary NAICS Code:	332919
Status Change Date:	19770209
Land Type:	PRIVATE
Description of Facility Site Location:	205 Industrial Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	HENDERSON CONTROLS INC
Contact Name:	JAMES R PARRISH
Contact Telephone Number:	512-4422387
Mailing Address:	205 INDUSTRIAL BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787451204
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

CHATLEFF CONTROLS (Continued) **S102738877**

TNRCC Facility ID:	8419
Site Owner Tax ID:	741995944
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20210727
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	HENDERSON CONTROLS INC
Operator Address:	205 INDUSTRIAL BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4422387
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17419959444
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	HENDERSON CONTROLS INC
Owner Mailing Address:	205 INDUSTRIAL BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4422387
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17419959444
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	205 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4422387
Contact Fax:	Not reported

CHATLEFF CONTROLS (Continued) **S102738877**

Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	205 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4422387
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JAMES PARRISH
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	205 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4422387
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100652791
Name:	CHATLEFF CONTROLS
Address:	205 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1204
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603394743
Customer Name:	HENDERSON CONTROLS INC
Customer Legal Name:	Henderson Controls, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332919
Primary NAICS Industry Type Description:	Other Metal Valve and Pipe Fitting Manufacturing
Physical Location Description:	205 Industrial Blvd, Austin, TX
Regulated Entity Number:	RN100652791
Name:	CHATLEFF CONTROLS
Address:	205 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1204
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603394743
Customer Name:	HENDERSON CONTROLS INC
Customer Legal Name:	Henderson Controls, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000

CHATLEFF CONTROLS (Continued) **S102738877**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332919
Primary NAICS Industry Type Description:	Other Metal Valve and Pipe Fitting Manufacturing
Physical Location Description:	205 Industrial Blvd, Austin, TX

Regulated Entity Number:	RN100652791
Name:	CHATLEFF CONTROLS
Address:	205 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1204
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603394743
Customer Name:	HENDERSON CONTROLS INC
Customer Legal Name:	Henderson Controls, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332919
Primary NAICS Industry Type Description:	Other Metal Valve and Pipe Fitting Manufacturing
Physical Location Description:	205 Industrial Blvd, Austin, TX

PC2800 **CHATLEFF CONTROLS** **RCRA NonGen / NLR** **1000414527**
ESE **205 INDUSTRIAL BLVD** **FINDS** **TXD000352823**
< 1/8 **AUSTIN, TX 78745** **ECHO**
0.106 mi.
560 ft. **Site 4 of 4 in cluster PC**

Actual:
671 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20210726
Handler Name:	Chatleff Controls
Handler Address:	205 INDUSTRIAL BLVD
Handler City,State,Zip:	AUSTIN, TX 78745-1204
EPA ID:	TXD000352823
Contact Name:	JAMES PARRISH
Contact Address:	205 INDUSTRIAL BLVD
Contact City,State,Zip:	AUSTIN, TX 78745-1204
Contact Telephone:	512-442-2387
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	205 INDUSTRIAL BLVD
Mailing City,State,Zip:	AUSTIN, TX 78745-1204
Owner Name:	Chatleff Controls Inc
Owner Type:	Private
Operator Name:	Chatleff Controls Inc
Operator Type:	Private
Short-Term Generator Activity:	No

CHATLEFF CONTROLS (Continued) **1000414527**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211229
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CHATLEFF CONTROLS INC	
Legal Status:	Private
Date Became Current:	20010214
Date Ended Current:	Not reported
Owner/Operator Address:	205 INDUSTRIAL BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-442-2387
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CHATLEFF CONTROLS (Continued) **1000414527**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CHATLEFF CONTROLS INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 205 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1204
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHATLEFF CONTROLS INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 205 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1204
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHATLEFF CONTROLS INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 205 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-442-2387
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHATLEFF CTRL INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800721
Handler Name: CHATLEFF CTRLS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CHATLEFF CONTROLS (Continued) **1000414527**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010214
Handler Name: CHATLEFF CONTROLS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210726
Handler Name: CHATLEFF CONTROLS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 332919
NAICS Description: OTHER METAL VALVE AND PIPE FITTING MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005026569

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CHATLEFF CONTROLS (Continued) **1000414527**

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000414527
Registry ID:	110005026569
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005026569
Name:	CHATLEFF CONTROLS
Address:	205 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745

2801 WNW < 1/8 0.106 mi. 562 ft. **SMS TRADING USA INC** **EDR Hist Cleaner** **1020089515**
9036 N LAMAR BLVD APT 180 **N/A**
AUSTIN, TX 78753

Actual: 674 ft.

Focus Map: 6

EDR Hist Cleaner

Year:	Name:	Type:
2005	SMS TRADING USA INC	Drycleaning Plants, Except Rugs, NEC
2006	SMS TRADING USA INC	Drycleaning Plants, Except Rugs, NEC
2007	SMS TRADING USA INC	Drycleaning Plants, Except Rugs, NEC
2008	SMS TRADING USA INC	Drycleaning Plants, Except Rugs, NEC

2802 WSW < 1/8 0.107 mi. 564 ft. **MESSER & HATCHER** **TX HIST UST** **S111678746**
205 W 5TH ST **N/A**
AUSTIN, TX

Actual: 490 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	MESSER & HATCHER
Address:	205 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0081
HID UST:	81
Inspection:	03/31/2009
Due:	03/31/2012

QF2803 WNW < 1/8 0.107 mi. 565 ft. **AUSTIN WATER LIGHT AND POWER CO** **EDR MGP** **1008408363**
W. 5TH STREET **N/A**
AUSTIN, TX 78701

Site 1 of 3 in cluster QF

Actual: 460 ft.

Focus Map: 11

Manufactured Gas Plants:

No additional information available

QG2804 ESE < 1/8 0.107 mi. 566 ft. — **A&B RUG & CARPET, 654 CANION, AUSTIN, TX** — **EDR Hist Cleaner** — **1013786537, N/A**

Site 1 of 2 in cluster QG

Actual: 709 ft.

Focus Map: 6

EDR Hist Cleaner

Year:	Name:	Type:
1962	A&B RUG & CARPET	CARPET AND RUG CLEANERS

QH2805 WNW < 1/8 0.108 mi. 568 ft. — **HERBERT MEYER, 828 W 6TH ST, AUSTIN, TX** — **TX HIST UST** — **S111678675, N/A**

Site 1 of 3 in cluster QH

Actual: 468 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	HERBERT MEYER
Address:	828 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0758
HID UST:	758
Inspection:	Not reported
Due:	06/01/2012

QI2806 East < 1/8 0.108 mi. 568 ft. — **DOWNTOWN RAILYARD PROPERTY, 800 E 4TH ST, AUSTIN, TX 78702** — **TX AUL, TX VCP, TX BROWNFIELDS, TX GCC** — **S111075177, N/A**

Site 1 of 2 in cluster QI

Actual: 468 ft.

Focus Map: 11

AUL:

Name:	DOWNTOWN RAILYARD PROPERTY
Address:	800 E 4TH ST
City,State,Zip:	AUSTIN, TX 78702
Facility ID:	2601
Facility Type:	VACANT PROPERTY
Phase:	PRAA
VCP Received:	Not reported
Rules:	TRRP
Standards:	B
Tier:	1
Pca No.:	95713
Project Manager:	ROANDERS
Acres:	10.3468
SW No.:	Not reported
LPST No.:	Not reported
RCRIS No.:	Not reported
Date/agreement:	Not reported
Region:	REGION 11 - AUSTIN
Type Remedy:	Not reported
Site Tract Notes:	Not reported
RN Number:	RN106158793
REM Program:	VCP
Project Number:	782800
Former Facility Type:	RAILYARD/CAR CLEANING/REPAIR

DOWNTOWN RAILYARD PROPERTY (Continued) **S111075177**

Site Address Description:	800 E 4TH ST E 5TH ST AUSTIN TX 78702
Near City Name:	AUSTIN
Administrative Status:	ACTIVE
Cashier Received Date:	Not reported
VCP Application Accepted:	Not reported
Application Acceptance Date:	2013-09-11 00:00:00
Region Notified of Application:	08/07/2013
Air Target COC Class:	Not reported
Groundwater Target COC Class:	METALS; TPH
Sediment Target COC Class:	Not reported
Soils Target COC Class:	METALS; TPH; VOCS; PAHS
Surface Water Target COC Class:	Not reported
IOP ID:	Not reported
EPA CERCLIS Number:	Not reported
File Media:	PAPER
File Location:	D2/211
Air REM Method:	Not reported
GW REM Method:	NA
SUP No:	Not reported
Soil REM Method:	EXCAVATION/REMOVAL; ENGINEERED CAP
Multiple Property:	Not reported
Surf Water REM Method:	Not reported
SUP Tract No:	Not reported
Sediment REM Method:	Not reported
Property Owner:	Not reported
CCOC Date:	12/04/2017
Air INST ENG Controls:	Not reported
TRRP Vol#, PG#, CO#, ID#:	Not reported
Inst Control Req?:	Not reported
GW INST ENG Controls:	NA
Eng Control Req?:	Not reported
Sediment INST ENG Controls:	Not reported
Soil INST ENG Controls:	PHYSICAL CONTROL; COMMERCIAL/INDUSTRIAL
Notes:	Not reported
Filing Type:	Not reported
Filing Date:	Not reported
Property Description:	Not reported

VCP TCEQ:

Name:	DOWNTOWN RAILYARD PROPERTY
Address:	800 E 4TH ST
City,State,Zip:	AUSTIN, TX 78702
Region:	REGION 11 - AUSTIN
Facility ID:	2601
VCP Record Date:	Not reported
Facility Type:	VACANT PROPERTY
PCA Number:	95713
Project Manager:	ROANDERS
Phase:	PRAA
Acres at Site:	10.3468
REM Program:	VCP
RN Number:	RN106158793
Former Facility Type:	RAILYARD/CAR CLEANING/REPAIR
Site Address Description:	800 E 4TH ST E 5TH ST AUSTIN TX 78702
Near City Name:	AUSTIN
Administrative Status:	ACTIVE
Region Notified of Application:	08/07/2013

DOWNTOWN RAILYARD PROPERTY (Continued) **S111075177**

RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	NA
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	EXCAVATION/REMOVAL; ENGINEERED CAP
Surf Water REM Method:	Not reported
CCOC Date:	12/04/2017
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	NA
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	PHYSICAL CONTROL; COMMERCIAL/INDUSTRIAL
Certificate of Completion Date:	05/15/2018; 05/17/2022
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	Not reported
GW Target COC Class:	PAHS; VOCS; METALS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2013-09-11 00:00:00
Soil Target COC Class:	METALS; TPH; VOCS; PAHS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2601
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	782800
Off Site?:	NO
Media:	PAPER
IOP Number:	Not reported
File Location:	D2/211
Latitude:	30.26
Longitude:	-97.73

Contact:

REM Program:	VCP
Program ID:	2601
RN Number:	RN106158793
CN Number:	CN602490906
CN Name:	CAPITAL METROPOLITAN TRANSPORTATION AUTHORITY
Role Code:	APPLCONT
Contact Name:	DAVIS, SHANEA
Contact Title:	VP REAL ESTATE AND ASSET MGMT
Organization Name:	CAPITAL METROPOLITAN TRANSPORTATION AUTHORITY
Mailing Address:	PO BOX 1088
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Telephone:	(512) 369-6295
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	2601
RN Number:	RN106158793
CN Number:	CN605380799
CN Name:	PLAZA SALTILLO TOD LLC

DOWNTOWN RAILYARD PROPERTY (Continued) **S111075177**

Role Code:	APPLCONT
Contact Name:	DAVIS, SHANEA
Contact Title:	VP REAL ESTATE AND ASSET MGMT
Organization Name:	CAPITAL METROPOLITAN TRANSPORTATION AUTHORITY
Mailing Address:	PO BOX 1088
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78767
Contact Telephone:	(512) 369-6295
Contact Telephone Ext:	0

BROWNFIELDS:

Name:	DOWNTOWN RAILYARD PROPERTY
Address:	800 E 4TH ST
City,State,Zip:	AUSTIN, TX 78702
BF Site Assessment Received:	05/23/2011
PCA number:	78226
BF Grant Number:	G131
Facility Type:	Transportation of Passengers and Freight
Lead Type:	Owner
Project manager:	PALLEN
Phase:	COMPLETED
Lat/Long:	30.154600 / -97.435000000000002
Lat/Long (deg):	30.154600 / -97.435000000000002
Acres:	10
TCEQ Region:	11
Facility Type:	BSA
Contaminant Categories:	2003 ESA Phase I,1997June Limited Phase II,
Media Affected:	Only Surface Soil Sampling
Applicant:	City of Austin, WPD-Brownfields
Applicant Title:	Contact
Applicant Address:	P.O. Box 1088
Applicant City,St,Zip:	Austin, TX 78767
Applicant Phone:	512-974-1954
Applicant Fax:	512-974-2492
Consultant Attorney:	CapitalMetroTransportationAuthority
Consultant Atty Name:	Lucy Galbraith
Consultant Atty Title:	Contact Person
Consultant Atty Addr:	2910 East 5th Street
Consultant Atty City,St,Zip:	Austin, TX 78702
Consultant Atty Phone:	512-974-6515
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported
Status Date:	08/04/2014

GCC:

DOWNTOWN RAILYARD PROPERTY (Continued) **S111075177**

Name: DOWNTOWN RAILYARD PROPERTY
Address: 800 E 4TH ST
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 2601
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 09/11/2013
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 4 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: DOWNTOWN RAILYARD PROPERTY
Address: 800 E 4TH ST
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 2601
Contamination Description: TPH
Date Of Earliest Known Contamination Confirmation: 9/11/2013
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 0B/L2 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

QI2807 **PLAZA SALTILLO** **RCRA NonGen / NLR** **1019909991**
East **800 E 4TH ST** **TXP490352566**
< 1/8 **AUSTIN, TX 78702**
0.108 mi.
568 ft. **Site 2 of 2 in cluster QI**

Actual:
468 ft.

Focus Map:
11

RCRA Listings:
Date Form Received by Agency: 20170620
Handler Name: Plaza Saltillo
Handler Address: E 4TH ST
Handler City,State,Zip: AUSTIN, TX 78702
EPA ID: TXP490352566
Contact Name: RUSSELL BAUER
Contact Address: E 5TH ST
Contact City,State,Zip: AUSTIN, TX 78702-4817
Contact Telephone: 512-389-7444
Contact Fax: Not reported
Contact Email: Not reported

PLAZA SALTILLO (Continued) **1019909991**

Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	E 5TH ST
Mailing City,State,Zip:	AUSTIN, TX 78702-4817
Owner Name:	Capital Metropolitan Transportation Auth
Owner Type:	Other
Operator Name:	Capital Metropolitan Transportation Auth
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170620
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

PLAZA SALTILLO (Continued) **1019909991**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CAPITAL METROPOLITAN TRANSPORTATION AUTH
Legal Status: Other
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 2910 E 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702-4817
Owner/Operator Telephone: 512-389-7444
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CAPITAL METROPOLITAN TRANSPORTATION AUTH
Legal Status: Other
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 2910 E 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702-4817
Owner/Operator Telephone: 512-389-7444
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CAPITAL METROPOLITAN TRANSPORTATION AUTH
Legal Status: Other
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 2910 E 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702-4817
Owner/Operator Telephone: 512-389-7444
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CAPITAL METROPOLITAN TRANSPORTATION AUTH
Legal Status: Other
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 2910 E 5TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702-4817
Owner/Operator Telephone: 512-389-7444
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

PLAZA SALTILLO (Continued) **1019909991**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date:	20160301
Handler Name: PLAZA SALTILLO	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170620
Handler Name: PLAZA SALTILLO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

QJ2808 **UNIVERSITY SCHWINN CYCLERY** **TX HIST UST** **S111678859**
WNW **2901 N LAMAR BLVD** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.108 mi.
570 ft. **Site 1 of 2 in cluster QJ**

Actual:
571 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	WILLIAM D. GASTON
Address:	2901 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H1004
HID UST:	1004
Inspection:	Not reported
Due:	06/01/2012

UNIVERSITY SCHWINN CYCLERY (Continued) **S111678859**

ASBESTOS:

Name:	UNIVERSITY CYCLERY
Address:	2901 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	10/18/2019
Notification Number:	2019006963
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/27/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	57
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/07/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported

UNIVERSITY SCHWINN CYCLERY (Continued) **S111678859**

Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	UNIVERSITY CYCLERY
Address:	2901 NORTH LAMAR BLVD.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Bill Post
Violation:	Not reported
Complaint Date:	09/30/2019
Notification Number:	2019006963
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/16/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/16/2019
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	57
Is this a phased abatement project?:	N

UNIVERSITY SCHWINN CYCLERY (Continued) **S111678859**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/30/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	UNIVERSITY SCHWINN CYCLERY
Address:	2901 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/07/2013
Date Routed by Supervisor:	05/07/2013
Date Routed to PSQA:	05/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

UNIVERSITY SCHWINN CYCLERY (Continued) **S111678859**

Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

QK2809 **GENERAL SERVICES COMMISSION** **RCRA-VSQG** **1000836083**
ESE **1518 SAN JACINTO BLVD** **FINDS** **TXD988059598**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.109 mi.
573 ft. **Site 1 of 4 in cluster QK**

Actual:
515 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20130604
Handler Name:	General Services Commission
Handler Address:	1518 SAN JACINTO BLVD
Handler City,State,Zip:	AUSTIN, TX 78701-1435
EPA ID:	TXD988059598
Contact Name:	WAYNE WILSON
Contact Address:	PO BOX 13047
Contact City,State,Zip:	AUSTIN, TX 78711-3047
Contact Telephone:	512-463-3353
Contact Fax:	Not reported
Contact Email:	Not reported

GENERAL SERVICES COMMISSION (Continued) **1000836083**

Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 13047
Mailing City,State,Zip:	AUSTIN, TX 78711-3047
Owner Name:	Texas Building And Procurement Commissi
Owner Type:	Private
Operator Name:	Texas Building And Procurement Commissi
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

GENERAL SERVICES COMMISSION (Continued) **1000836083**

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D012
Waste Description: Endrin (1,2,3,4,10,10-Hexachloro-1,7-Epoxy-1,4,4a,5,6,7,8,8a-Octahydro-1,4-En do, Endo-5,8-Dimeth-Ano-Naphthalene)

Waste Code: D020
Waste Description: Chlordane

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D031
Waste Description: Heptachlor (And Its Epoxide)

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And

GENERAL SERVICES COMMISSION (Continued) **1000836083**

F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TEXAS GEN SVC COMM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 13047
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-463-3281
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS BUILDING AND PROCUREMENT COMMISSIO
Legal Status: Not reported
Date Became Current: 20030829
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 13047
Owner/Operator City,State,Zip: AUSTIN, TX 78711
Owner/Operator Telephone: 512-463-3353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

GENERAL SERVICES COMMISSION (Continued) **1000836083**

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS BUILDING AND PROCUREMENT COMMISSIO
Legal Status: Not reported
Date Became Current: 20030829
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 13047
Owner/Operator City,State,Zip: AUSTIN, TX 78711
Owner/Operator Telephone: 512-463-3353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS BUILDING AND PROCUREMENT COMMISSI
Legal Status: Private
Date Became Current: 20030829
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 13047
Owner/Operator City,State,Zip: AUSTIN, TX 78711-3047
Owner/Operator Telephone: 512-463-3353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS BUILDING AND PROCUREMENT COMMISSI
Legal Status: Private
Date Became Current: 20030829
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 13047
Owner/Operator City,State,Zip: AUSTIN, TX 78711-3047
Owner/Operator Telephone: 512-463-3353
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19930323
Handler Name: TEXAS STATE GEN SVC COMM
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030829
Handler Name: TEXAS BUILDING AND PROCUREMENT COMMISSIO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

GENERAL SERVICES COMMISSION (Continued) **1000836083**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130604
Handler Name: GENERAL SERVICES COMMISSION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92119
NAICS Description: OTHER GENERAL GOVERNMENT SUPPORT

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005145431

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

GENERAL SERVICES COMMISSION (Continued) **1000836083**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000836083
Registry ID:	110005145431
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005145431
Name:	GENERAL SERVICES COMMISSION
Address:	1518 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701

QK2810 **GENERAL SERVICES COMMISSION** **TX LPST** **S104273957**
ESE **1518 SAN JACINTO BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX Ind. Haz Waste**
0.109 mi.
573 ft. **Site 2 of 4 in cluster QK**

Actual:
515 ft.

Focus Map:
11

LPST:

Name:	STATE PROPERTY
Address:	1518 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	111590
Facility Location:	1518 SAN JACINTO BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	09/11/1996
Reported Date:	12/31/3000
Closure Date:	01/16/1997
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	JAMES REID
Responsible Party Address:	1711 SAN JACINTO BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78711 3047
Responsible Party Telephone:	512/475-2436
Reported Date:	12/31/3000
Case Start Date:	01/16/1997
Reference Number:	RN103054102
Project Manager:	XYZ

HIST UST AUSTIN:

Name:	GENERAL SERVICES COMMISSION
Address:	1518 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0628
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Ind. Haz Waste:

Name:	GENERAL SERVICES COMMISSION
Address:	1518 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	75086
Registration Initial Notification Date:	01/03/1990
Registration Last Amendment Date:	06/04/2013
EPA Identification:	TXD988059598
Primary NAICS Code:	921190
Status Change Date:	20130614
Land Type:	PRIVATE
Description of Facility Site Location:	1518 San Jacinto, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Contact Name:	WAYNE WILSON
Contact Telephone Number:	512-4633353
Mailing Address:	PO BOX 13047
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787113047
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29441
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20130627
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	1

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Operator Address:	PO BOX 13047
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78711
Operator Country:	UNITED STA
Operator Telephone:	1-512-4633353
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17460000742
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Owner Mailing Address:	PO BOX 13047
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78711
Owner Country:	UNITED STA
Owner Telephone:	1-512-4633353
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17460000742
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	800 sq. ft. slab enc. in a 6’ chain linked fence. Area is located on the west s
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940304
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Contact Role:	OPRCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633353
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633353
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WAYNE WILSON
Contact Title:	ENVIRONMENTAL CONTACT
Contact Role:	PRICONT
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633353
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	122155
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Solvent / parts washing / 1989
Standard Industrial Code:	91990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Waste ID:	122154
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint thinner / Painting Bldgs. (interiors) / 1989
Standard Industrial Code:	91990
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	122153
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste paint k/ painting buildings (interior) / 1989
Standard Industrial Code:	91990
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	122152

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Texas Waste Code:	Not reported
Texas Waste Code 2:	00052061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil / machine maintenance / 1989
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	122151
Texas Waste Code:	Not reported
Texas Waste Code 2:	00064951
Waste Code Status:	INACTIVE
Waste Form:	495
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB ballasts / changing light fixtures/ 1989
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	122150
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Developer/ Copier Machine / 1989
Standard Industrial Code:	91990
Primary Source:	G19

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	160374
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008309H
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent lead acid batteries
Standard Industrial Code:	91990
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste batteries
Primary NAICS Code:	921190
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	194972
Texas Waste Code:	Not reported
Texas Waste Code 2:	0046204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Halogenated solvent mixture tetrachloroethylene unused product.
Standard Industrial Code:	91990
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	195533
Texas Waste Code:	Not reported
Texas Waste Code 2:	0247001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab packs of old chemicals only unused products ONE TIME NUMBER. 06/02/2002
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191651
Texas Waste Code:	Not reported
Texas Waste Code 2:	3108207H
Waste Code Status:	INACTIVE
Waste Form:	207
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Concentrated Aqueous Solution or other organic. ONE TIME SHIPMENT. Generated f
Standard Industrial Code:	91990
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191652
Texas Waste Code:	Not reported
Texas Waste Code 2:	3111001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab Pack of Old Chemical only. ONE TIME SHIPMENT Generated from left over prod
Standard Industrial Code:	91990
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191653
Texas Waste Code:	Not reported
Texas Waste Code 2:	3113310H
Waste Code Status:	INACTIVE
Waste Form:	310
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solid filters generated from maintence activities. 08/01/2001
Standard Industrial Code:	91990
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190

GENERAL SERVICES COMMISSION (Continued) **S104273957**

EPA Waste Form Code: W310
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 193062
Texas Waste Code: Not reported
Texas Waste Code 2: 3450409H
Waste Code Status: INACTIVE
Waste Form: 409
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Other non halogenated solid acid solid generated from an unknown material that w
Standard Industrial Code: 91990
Primary Source: G11
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: 921190
EPA Waste Form Code: W409
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 184639
Texas Waste Code: Not reported
Texas Waste Code 2: 9001110H
Waste Code Status: INACTIVE
Waste Form: 110
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Caustic aqueous waste generated from off-speculation product. Initial date of g
Standard Industrial Code: Not reported
Primary Source: G11
Primary Measurement Point: Not reported
Primary Origin: 2
Primary System Type: Not reported
New Chemical Substance: 0

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	184640
Texas Waste Code:	Not reported
Texas Waste Code 2:	9002219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Other inorganic liquids generated from disposing of off-specification product. O
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	193063
Texas Waste Code:	Not reported
Texas Waste Code 2:	9005110H
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous caustic waste generated from off specification product. ONE TIME SHIPME
Standard Industrial Code:	91990
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	921190

GENERAL SERVICES COMMISSION (Continued) **S104273957**

EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	260425
Texas Waste Code:	Not reported
Texas Waste Code 2:	C2K6203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	260426
Texas Waste Code:	Not reported
Texas Waste Code 2:	C2K7206H
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	260427
Texas Waste Code:	Not reported

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Texas Waste Code 2:	C2K82111
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272099
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJP93011
Waste Code Status:	INACTIVE
Waste Form:	301
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	6
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	272100
Texas Waste Code:	Not reported
Texas Waste Code 2:	CJPB2051
Waste Code Status:	INACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

GENERAL SERVICES COMMISSION (Continued) **S104273957**

Primary Origin:	6
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1711 SAN JACINTO BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000310802
Principal Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1711 SAN JACINTO BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78701
AR Number:	0000310802
Principal Name:	TEXAS BUILDING AND PROCUREMENT COMMISSION
Attention Name:	Not reported
Attention Suffix:	HWG

PD2811 **STATE SERVICE STATION** **TX LPST** **U001279453**
ESE **1502 SAN JACINTO BLVD** **TX UST** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.109 mi.
573 ft. **Site 4 of 5 in cluster PD**

Actual:
515 ft.

Focus Map:
11

LPST:

Name:	STATE SERVICE STATION
Address:	1502 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78711
Facility ID:	0048285
LPST Id:	097342
Facility Location:	1502 SAN JACINTO
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/28/1990
Entered Date:	11/28/1990
Reported Date:	11/28/1990
Closure Date:	09/15/1999
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED

STATE SERVICE STATION (Continued) **U001279453**

Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/3/1
Coordinators RPR:	KKC
Responsible Party Name:	Not reported
Responsible Party Contact:	WAYNE WILSON
Responsible Party Address:	1711 SAN JACINTO
Responsible Party City,St,Zip:	AUSTIN, TX 78711
Responsible Party Telephone:	512/463-3353
Reported Date:	11/28/1990
Case Start Date:	09/15/1999
Reference Number:	RN104805403
Project Manager:	KKC

UST:

Name:	STATE SERVICE STATION
Address:	1502 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 787011435
AI Number:	48285
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/03/1989
Facility Status:	INACTIVE
Additional ID:	174454832005353
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78711
Contact Name/Title:	KENNETH LIMBRICK,FLEET MANAGER
Contact Organization Name:	STATE SERVICE STATION
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124633551
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/27/1989
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	04/28/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600327530
Owner Last Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported

STATE SERVICE STATION (Continued) **U001279453**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	339516662001297
Additional ID:	174454832005353
AI Number:	48285
Owner Effective Begin Date:	05/03/1989
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1959
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125714
Facility ID:	79981
Ai Number:	48285
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

STATE SERVICE STATION (Continued) **U001279453**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	6
Tank Capacity:	1000
UST Comprt ID:	112888
UST ID:	125714
AI Number:	48285
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

STATE SERVICE STATION (Continued) **U001279453**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1959
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125715
Facility ID:	79981
Ai Number:	48285
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

STATE SERVICE STATION (Continued) **U001279453**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	112889
UST ID:	125715
AI Number:	48285
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

STATE SERVICE STATION (Continued) **U001279453**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1959
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125716
Facility ID:	79981
Ai Number:	48285
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

STATE SERVICE STATION (Continued) **U001279453**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	1000
UST Comprt ID:	112890
UST ID:	125716
AI Number:	48285
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1987
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	6000

STATE SERVICE STATION (Continued) **U001279453**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125717
Facility ID:	79981
Ai Number:	48285
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

STATE SERVICE STATION (Continued) **U001279453**

Installation Signature Date:	12/20/1990
Compartment Records:	
Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	112891
UST ID:	125717
AI Number:	48285
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1987
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125718
Facility ID:	79981
Ai Number:	48285
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND

STATE SERVICE STATION (Continued) **U001279453**

Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	112892
UST ID:	125718
AI Number:	48285
Compartment ID:	A

STATE SERVICE STATION (Continued) **U001279453**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1959
Tank Registration Date:	04/28/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	125719
Facility ID:	79981
Ai Number:	48285
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/01/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

STATE SERVICE STATION (Continued) **U001279453**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/20/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	112893
UST ID:	125719
AI Number:	48285
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

STATE SERVICE STATION (Continued) **U001279453**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Contact Mailing Address (Delivery):	1711 SAN JACINTO BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 1416
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79981
Additional ID:	174454832005353
Princ ID:	339516662001297
AI Number:	48285
Facility Name:	STATE SERVICE STATION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

QK2812 ESE < 1/8 0.109 mi. 573 ft. | **DOC & BUSTER SERV**
1508 SAN JACINTO
AUSTIN, TX | **EDR Hist Auto** | **1013758846**
N/A

Site 3 of 4 in cluster QK

Actual: 515 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	DOC & BUSTER SERV	GASOLINE AND OIL SERVICE STATIONS
1947	DOC & BUSTER SERVICE STA FILLIN	GASOLINE AND OIL SERVICE STATIONS
1953	SMITTYS SERV STA	GASOLINE STATIONS
1958	WILEYS MOBILE	GASOLINE STATIONS

PS2813 West < 1/8 0.109 mi. 575 ft. | **AUSTIN LAUNDRY & DRYV CLEANING CO INC BR**
913 W 24TH ST
TRAVIS (County), TX 78705 | **EDR Hist Cleaner** | **1013778638**
N/A

Site 6 of 7 in cluster PS

Actual: 599 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1970	AUSTIN LAUNDRY & DRYV CLEANING	LAUNDRIES

QL2814 South < 1/8 0.109 mi. 578 ft. | **TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B**
3600 3600 PRESIDENTIAL BLVD STE 305
AUSTIN, TX 78719 | **RCRA-SQG** | **1007449432**
TXR000058446

Site 1 of 3 in cluster QL

Actual: 498 ft. RCRA Listings:

Focus Map: 20

Date Form Received by Agency:	20220421
Handler Name:	Transportation Security Administration At Austin-B
Handler Address:	3600 PRESIDENTIAL BLVD STE 305
Handler City,State,Zip:	AUSTIN, TX 78719-2357
EPA ID:	TXR000058446
Contact Name:	KEVIN SWINTON
Contact Address:	3600 PRESIDENTIAL BLVD STE 305
Contact City,State,Zip:	AUSTIN, TX 78719-2357
Contact Telephone:	512-386-2004
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3600 PRESIDENTIAL BLVD STE 305
Mailing City,State,Zip:	AUSTIN, TX 78719-2357
Owner Name:	Transportation Security Administration
Owner Type:	Private
Operator Name:	Transportation Security Administration

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220518
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D012
Waste Description: Endrin
(1,2,3,4,10,10-Hexachloro-1,7-Epoxy-1,4,4a,5,6,7,8,8a-Octahydro-1,4-En
do, Endo-5,8-Dimeth-Ano-Naphthalene)

Waste Code: D013
Waste Description: Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)

Waste Code: D014
Waste Description: Methoxychlor (1,1,1-Trichloro-2,2-Bis [P-Methoxyphenyl] Ethane)

Waste Code: D015
Waste Description: Toxaphene (C10 H10 Cl8, Technical Chlorinated Camphene, 67-69 Percent
Chlorine)

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D017
Waste Description: 2,4,5-Tp Silvex (2,4,5-Trichlorophenoxypropionic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D019
Waste Description: Carbon Tetrachloride

Waste Code: D020
Waste Description: Chlordane

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D022
Waste Description: Chloroform

Waste Code: D023

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Waste Description: O-Cresol

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D025
Waste Description: P-Cresol

Waste Code: D026
Waste Description: Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D028
Waste Description: 1,2-Dichloroethane

Waste Code: D029
Waste Description: 1,1-Dichloroethylene

Waste Code: D030
Waste Description: 2,4-Dinitrotoluene

Waste Code: D031
Waste Description: Heptachlor (And Its Epoxide)

Waste Code: D032
Waste Description: Hexachlorobenzene

Waste Code: D033
Waste Description: Hexachlorobutadiene

Waste Code: D034
Waste Description: Hexachloroethane

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D036
Waste Description: Nitrobenzene

Waste Code: D037
Waste Description: Pentachlorophenol

Waste Code: D038
Waste Description: Pyridine

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D041
Waste Description: 2,4,5-Trichlorophenol

Waste Code: D042

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Waste Description: 2,4,6-Trichlorophenol

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U033
Waste Description: Carbon Oxyfluoride (R,T) (Or) Carbonic Difluoride

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U052
Waste Description: Cresol (Cresylic Acid) (Or) Phenol, Methyl-

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U151
Waste Description: Mercury

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U188

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Waste Description: Phenol

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U247
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Methoxy- (Or) Methoxychlor

Waste Code: U248
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenyl-Butyl)-, & Salts, When Present At Concentrations Of 0.3% Or Less (Or) Warfarin, & Salts, When Present At Concentrations Of 0.3% Or Less

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Federal
Date Became Current: 20020904
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20160101
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20160101
Date Ended Current: Not reported

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: 19970601
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD STE 3
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2357
Owner/Operator Telephone: 512-386-2004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2363
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TRANSPORTATION SECURITY ADMINISTRATION
Legal Status: Private
Date Became Current: 20151215
Date Ended Current: Not reported
Owner/Operator Address: 3600 PRESIDENTIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78719-2363
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20040802
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160101
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180406
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20181024
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190626
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B (Continued) **1007449432**

Receive Date: 20200117
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210111
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220421
Handler Name: TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 488119
NAICS Description: OTHER AIRPORT OPERATIONS

NAICS Code: 92612
NAICS Description: REGULATION AND ADMINISTRATION OF TRANSPORTATION PROGRAMS

NAICS Code: 926120
NAICS Description: REGULATION AND ADMINISTRATION OF TRANSPORTATION PROGRAMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

QL2815 **GAT AIRLINE GROUND SUPPORT** **FINDS** **1011401367**
South **3600 PRESIDENTIAL BLVD** **ECHO** **N/A**
< 1/8 **AUSTIN, TX 78719** **PFAS ECHO**
0.109 mi.
578 ft. **Site 2 of 3 in cluster QL**

Actual:
498 ft.

Focus Map:
20

FINDS:
Registry ID: 110035370130

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.
Registry ID: 110070370831

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
Registry ID: 110070356280

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1011401367
Registry ID:	110070370831
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070370831
Name:	AUSTIN- BERGSTROM INTERNATIONAL AIRPORT
Address:	3600 PRESIDENTIAL BLVD STE 2133
City,State,Zip:	AUSTIN, TX 78719

Envid:	1011401367
Registry ID:	110070356280
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070356280
Name:	GAT AIRLINE GROUND SUPPORT

GAT AIRLINE GROUND SUPPORT (Continued) **1011401367**

Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719

PFAS ECHO:

Name:	AUSTIN- BERGSTROM INTERNATIONAL AIRPORT
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.187428
Longitude:	-97.650981
Count:	1
County:	TRAVIS COUNTY
Status:	Active
Region:	06
Industry:	Airports
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110070370831
Facility Percent Minority:	82.528
Facility Derived Tribes:	-
Facility Population:	552.01
EPA Programs:	CWA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	-
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050409
Facility Derived CD113:	35
Facility Derived CB2010:	484539800001034
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05CJ55 TXR05DJ99 TXR05DM18 TXR05FE38
CWA Permit Types:	Minor

GAT AIRLINE GROUND SUPPORT (Continued) **1011401367**

CWA NAICS:	-
CWA SICS:	4512 4581
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.650981,%22y%22:30.187428,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

QL2816 **UNITED AIRLINES** **TX ASBESTOS** **S111057059**
South **3600 PRESIDENTIAL BLVD** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78719** **TX TIER 2**
0.109 mi.
578 ft. **Site 3 of 3 in cluster QL**

Actual:
498 ft.

Focus Map:
20

ASBESTOS:

Name:	ABIA - TERMINAL EXPANSION APRON - AC PIPE REMOVAL
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	08/15/2017
Notification Number:	2017005449
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	08/07/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/07/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	08/14/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA - TERMINAL EXPANSION APRON - AC PIPE REMOVAL
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	08/09/2017
Notification Number:	2017005449
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	07/21/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/21/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	08/08/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT (ABIA)
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018004284
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/23/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/23/2018
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/07/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2021008264
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/07/2022
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2021008264
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/10/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original

UNITED AIRLINES (Continued) **S111057059**

Work Type Flag:	A
Certification Statement Date:	12/10/2021
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/03/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	12-INCH AC PIPE
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	11/10/2016
Notification Number:	2016008703
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/09/2016
Date Routed by Supervisor:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/09/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	11/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	12-INCH AC PIPE
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	11/08/2016
Notification Number:	2016008703
ASB Priority:	Not reported

UNITED AIRLINES (Continued) **S111057059**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/31/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/31/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	11/07/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	12-INCH AC PIPE
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	11/09/2016
Notification Number:	2016008703
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/04/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	11/08/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

UNITED AIRLINES (Continued) **S111057059**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	12-INCH AC PIPE
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	11/10/2016
Notification Number:	2016008703
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	10/20/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/20/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07

UNITED AIRLINES (Continued) **S111057059**

Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	11/04/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA MAIN TERMINAL
Address:	3600 PRESIDENTIAL BLVD.
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	05/11/2018
Notification Number:	2018003376
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	05/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/08/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/11/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA MAIN TERMINAL
Address:	3600 PRESIDENTIAL BLVD.
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	05/09/2018
Notification Number:	2018003376
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/25/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/25/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/09/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT

UNITED AIRLINES (Continued) **S111057059**

Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2019009508
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/17/2019
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/02/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN BERGESTROM INTERNATIONAL AIRPORT-CATEGORY I &II BUILDINGS
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/19/2016
Notification Number:	2016002304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/18/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	40
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

UNITED AIRLINES (Continued) **S111057059**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/04/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN BERGESTROM INTERNATIONAL AIRPORT-CATEGORY I &II BUILDINGS
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/22/2016
Notification Number:	2016002304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/18/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current

UNITED AIRLINES (Continued) **S111057059**

Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/18/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	40
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/20/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN BERGESTROM INTERNATIONAL AIRPORT-CATEGORY I &II BUILDINGS
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/22/2016
Notification Number:	2016002304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

UNITED AIRLINES (Continued) **S111057059**

Inspector Name:	Not reported
Date Report Received:	03/10/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/10/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	40
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/04/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN BERGESTROM INTERNATIONAL AIRPORT-CATEGORY I &II BUILDINGS
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Complaint Date:	05/06/2016
Notification Number:	2016002304
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/10/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/10/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	40
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	REMOVAL OF AC PIPE AT ABIA
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/10/2017
Notification Number:	2017002109
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/10/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/06/2017

UNITED AIRLINES (Continued) **S111057059**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	REMOVAL OF AC PIPE AT ABIA
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/07/2017
Notification Number:	2017002109
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/27/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/27/2017

UNITED AIRLINES (Continued) **S111057059**

Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	REMOVAL OF AC PIPE AT ABIA
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/11/2017
Notification Number:	2017002109
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/06/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	REMOVAL OF AC PIPE AT ABIA
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	04/05/2017
Notification Number:	2017002109
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/14/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/14/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	04/04/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Inspection Number Grade:	Not reported
Name:	ABIA SOUTH CAMPUS ABATEMENT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/09/22
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	09/22/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021005258
File Number:	63748
License Status Description:	Paid

UNITED AIRLINES (Continued) **S111057059**

Expiration Date:	11/19/2021
Original Date:	07/28/2021
Rank Effective Date:	07/28/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	28889
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT
Address:	3600 PRESIDENTIAL
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2020008290
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/22/2020
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7

UNITED AIRLINES (Continued) **S111057059**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/06/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ABIA SOUTH CAMPUS ABATEMENT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	09/22/2021
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	11/19/2021
Notification Number:	2021005258
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/28/2021
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	212
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA SOUTH CAMPUS ABATEMENT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	09/22/2021
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	11/06/2021
Notification Number:	2021005258
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/27/2021
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	212
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA SOUTH CAMPUS ABATEMENT
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719

UNITED AIRLINES (Continued) **S111057059**

Date of inspection:	09/22/2021
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	11/06/2021
Notification Number:	2021005258
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/28/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/28/2021
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	212
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/16/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ABIA - AC PIPES AT VARIOUS LOCATIONS NEAR THE TERMINAL APRON
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	09/07/2017
Notification Number:	2017006217
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/01/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/01/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

UNITED AIRLINES (Continued) **S111057059**

Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	09/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ABIA - AC PIPES AT VARIOUS LOCATIONS NEAR THE TERMINAL APRON
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	09/08/2017
Notification Number:	2017006217
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	08/21/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement

UNITED AIRLINES (Continued) **S111057059**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/21/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	Assumed Asbestos
Start Date:	09/06/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT (ABIA)
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2018009511
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/25/2019

UNITED AIRLINES (Continued) **S111057059**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/25/2019
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN BERGSTROM INTERNATIONAL AIRPORT (ABIA)
Address:	3600 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	Linda Arredondo
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2018009511

UNITED AIRLINES (Continued) **S111057059**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/17/2018
Certification Statement Phone:	512-530-2466
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	TRANSPORTATION SECURITY ADMINISTRATION AT AUSTIN-B
Address:	3600 PRESIDENTIAL BLVD STE 305
City,State,Zip:	AUSTIN, TX 78719
Permit Number:	Not reported
Registration Number:	96192
Registration Initial Notification Date:	01/01/2016
Registration Last Amendment Date:	04/21/2022
EPA Identification:	TXR000058446
Primary NAICS Code:	926120
Status Change Date:	20160101
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TRANSPORTATION SECURITY ADMINISTRATION TSA
Contact Name:	KEVIN SWINTON
Contact Telephone Number:	512-3862004
Mailing Address:	3600 PRESIDENTIAL BLVD STE 305
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787192357
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	131537
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220427
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TRANSPORTATION SECURITY ADMINISTRATION TSA
Operator Address:	3600 PRESIDENTIAL BLVD
Operator Address 2:	STE 305
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78719
Operator Country:	UNITED STA
Operator Telephone:	1-512-3862004
Operator Fax Number:	Not reported
Operator Email:	KEVIN.SWINTON@DHS.GOV
Operator Business Type:	Federal Government Ownership
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TRANSPORTATION SECURITY ADMINISTRATION TSA
Owner Mailing Address:	3600 PRESIDENTIAL BLVD
Owner Mailing Address 2:	STE 305
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78719
Owner Country:	UNITED STA
Owner Telephone:	1-512-3862004
Owner Fax:	Not reported
Owner Email Address:	KEVIN.SWINTON@DHS.GOV
Owner Business Type:	Federal Government Ownership
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	SQG HAZARDOUS WASTE ACCUMULATION AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20160101
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	3600 PRESIDENTIAL BLVD
Contact Address 2:	STE 305
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78719
Contact Phone:	1-512-3862004
Contact Fax:	Not reported
Contact Email:	KEVIN.SWINTON@DHS.GOV

Contact Name:	KEVIN SWINTON
Contact Title:	ENVIRONMETAL MANAGEMENT C
Contact Role:	PRICONT
Contact Address:	3600 PRESIDENTIAL BLVD STE 305
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78719
Contact Phone:	1-512-3862004
Contact Fax:	Not reported
Contact Email:	KEVIN.SWINTON@DHS.GOV

Ind. Haz Waste:

Waste ID:	379352
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	BUTANE LIGHTER REFILLS-HAZMAT IS VOLUNTARILY ABANDONED AT AIRPORT SCREENING CHEC
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	404701
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003801H
Waste Code Status:	ACTIVE

UNITED AIRLINES (Continued) **S111057059**

Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Butane Lighters
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382291
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005701H
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1013, WASTE CARBON DIOXIDE, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CARBON DIOXIDE CYLIN
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382292
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006701H
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Generators Waste Description:	Nitrous Oxide cartridges-Hazmat is voluntarily abandoned at airport screening
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382294
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mace/red pepper defense spray-Hazmat is voluntarily abandoned at airport screeni
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382295
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable aerosols-Hazmat is voluntarily abandoned at airport screening

UNITED AIRLINES (Continued) **S111057059**

Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382297
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Ethanol products (alcoholic beverages)-Hazmat is voluntarily abandoned at airpor
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382298
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Liquids (labpacked) Hazmat is voluntarily abandoned at airport screeni
Standard Industrial Code:	Not reported
Primary Source:	G09

UNITED AIRLINES (Continued) **S111057059**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382299
Texas Waste Code:	Not reported
Texas Waste Code 2:	00140011
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Nonhaz liquids (consumer products:profiled) Material voluntarily abandoned at ai
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	411593
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1978, Waste Propane, 2.1
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0

UNITED AIRLINES (Continued) **S111057059**

Company Waste ID:	PROPANE CYLINDERS
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382300
Texas Waste Code:	Not reported
Texas Waste Code 2:	00223081
Waste Code Status:	ACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty Drum previously used for Haz Mat storage (ex. acetone, mouthwash, fragranc
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	3
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	382304
Texas Waste Code:	Not reported
Texas Waste Code 2:	00232191
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Drinking alcohol for recycling-material voluntarily abandoned at airport screeni
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411513
Texas Waste Code:	Not reported
Texas Waste Code 2:	0025319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste Consumer Comodity, (small arm ammunition in consumer packaging), ORM-D
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SMALL ARMS
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411510
Texas Waste Code:	Not reported
Texas Waste Code 2:	0026405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3268, Waste safety devices, 9, (Airbag inflator)
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	AIR BAG
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411508
Texas Waste Code:	Not reported
Texas Waste Code 2:	0027003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3264, Waste Corrosive Liquid, Acidic, Inorganic, n.o.s (Sulfuric acid, hydorch
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUID ACI
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411518
Texas Waste Code:	Not reported
Texas Waste Code 2:	00287011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1956, Compressed Gas, n.o.s. (carbon dioxide, argon), 2.2
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ARGON CO2 GAS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	411519
Texas Waste Code:	Not reported
Texas Waste Code 2:	0029003H

UNITED AIRLINES (Continued) **S111057059**

Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3266, Waste Corrosive Liquid, Basic, Inorganic, n.o.s, (ammonium hydroxide, po
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BASE CORROSIVE LIQUI
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411522
Texas Waste Code:	Not reported
Texas Waste Code 2:	00303091
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Batteries, dry, sealed, n.o.s. (universal waste-batteries)
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ALKALINE NICAD B
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	411526
Texas Waste Code:	Not reported
Texas Waste Code 2:	0031003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1760, Waste Corrosive Liquids, n.o.s., (sodium hypochlorite, potassium hydroxi

UNITED AIRLINES (Continued) **S111057059**

Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HYPOCHLORITE SOLUTIO
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411534
Texas Waste Code:	Not reported
Texas Waste Code 2:	0032003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2037, Waste Receptacles, Small, Containing Gas (Gas Cartridges) 2.1
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BUTANE CARTRIDGE
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	432070
Texas Waste Code:	Not reported
Texas Waste Code 2:	00332191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1950, AEROSOLS, FLAMMABLE, (EACH NOT EXCEEDING 1 L CAPACITY), 2.1, (UNIVERSAL
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1

UNITED AIRLINES (Continued) **S111057059**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	UWA
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	ERROR

Waste ID:	411529
Texas Waste Code:	Not reported
Texas Waste Code 2:	00343191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3077, Hazardous Waste Solid, n.o.s., (mercury), 9, PG III, Universal Waste-La
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	STRAIGHT FLUORESCENT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	411530
Texas Waste Code:	Not reported
Texas Waste Code 2:	0035319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	non-DOT Regulated Material, (Misc Fluorescent bulbs)Universal Waste-Lamp
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BULBS-MISC SHAPED
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411532
Texas Waste Code:	Not reported
Texas Waste Code 2:	0036319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non DOT Regulated Material,(HID Bulbs) Universal Waste-Lamp,
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	BULBS SHATTERED
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411533
Texas Waste Code:	Not reported
Texas Waste Code 2:	0037319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non DOT Regulated Material, (Compact Fluorescent bulbs) Universal Waste-Lamp,
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BULBS-COMPACT
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411536

UNITED AIRLINES (Continued) **S111057059**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0039801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1002, Waste Air, Compressed, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	COMPRESSED AIR
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411535
Texas Waste Code:	Not reported
Texas Waste Code 2:	0040801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1013, WASTE CARBON DIOXIDE, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	CARBON DIOXIDE CYLIN
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411537
Texas Waste Code:	Not reported
Texas Waste Code 2:	0042801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H

UNITED AIRLINES (Continued) **S111057059**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1044, Fire Extinguishers, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	FIRE EXTINGUISHERS
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411541
Texas Waste Code:	Not reported
Texas Waste Code 2:	0044001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1325, Wste Flammable Solids, Organic, n.o.s., (camphor, alcohol), 4.1, PGII
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	FLAMABLE SOLIDS
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411563
Texas Waste Code:	Not reported
Texas Waste Code 2:	0045409H
Waste Code Status:	ACTIVE

UNITED AIRLINES (Continued) **S111057059**

Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA1325, Waste Fusee, 4.1, PGII
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	FLARES
Primary NAICS Code:	488119
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411569
Texas Waste Code:	Not reported
Texas Waste Code 2:	0046801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1046, Waste Helium, Compressed, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HELIUM
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411570
Texas Waste Code:	Not reported
Texas Waste Code 2:	0047119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2014, Waste Hydrogen Peroxide, Aqueous Solutions, 5.1 (8), PG II

UNITED AIRLINES (Continued) **S111057059**

	Class II Oxid
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HYDROGEN PEROXIDE
Primary NAICS Code:	488119
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411523
Texas Waste Code:	Not reported
Texas Waste Code 2:	00483191
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2794, Batteries, wet, filled with acid, (UWB), 8
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	LEAD ACID BATTERIES
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	411524
Texas Waste Code:	Not reported
Texas Waste Code 2:	0049309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2794 Batteriers, wet filled w/acid, 8, (universal waste-batteries), 8
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1

UNITED AIRLINES (Continued) **S111057059**

Audit Performed:	0
Company Waste ID:	LEAD ACID BATTERIES
Primary NAICS Code:	488119
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411573
Texas Waste Code:	Not reported
Texas Waste Code 2:	0050801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1060 Methyl Acetlen and propadiene mixtures, Stabalized, 2.1
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MAPP GAS
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411576
Texas Waste Code:	Not reported
Texas Waste Code 2:	0051319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3506, Mercury contained in manufactured artricles, 8 (6.1), Universal waste-me
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	MERCURY
Primary NAICS Code:	488119

UNITED AIRLINES (Continued) **S111057059**

EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411577
Texas Waste Code:	Not reported
Texas Waste Code 2:	0052001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2813, Waste water-reactive solid, n.o.s. (magnesium-iron mixture) 4., PGI
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	HAND WARMERS
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411579
Texas Waste Code:	Not reported
Texas Waste Code 2:	0053004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1654, Waste Nicotine, 6.1, PGII
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	NICOTINE
Primary NAICS Code:	488119
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411580
Texas Waste Code:	Not reported
Texas Waste Code 2:	0054801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1066, Nitrogen, compressed, 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	NITROGEN
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411582
Texas Waste Code:	Not reported
Texas Waste Code 2:	0055409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3178, WASTE FLAMMABLE SOLID, INORGANIC, N.O.S., (NOVELTIES), 4.1, PG II
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	NOVELTIES FIREWORKS
Primary NAICS Code:	488119
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411585
Texas Waste Code:	Not reported
Texas Waste Code 2:	0056001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3265, Waste Corrosive Liquid, Acidic, Organic, no.s. (oxalic acid, acetic acid
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ORGANIC ACID
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411587
Texas Waste Code:	Not reported
Texas Waste Code 2:	0057210H
Waste Code Status:	ACTIVE
Waste Form:	210
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3105, Waste Organic Peroxide Type D, Liquid, (methly ethly ketone peroxide) 5.
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ORGANIC PEROXIDE
Primary NAICS Code:	488119
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Waste ID:	411589
Texas Waste Code:	Not reported
Texas Waste Code 2:	0058001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3139, Waste Oxidizing Liquid, n.o.s. (sodium hypochlorite, potassium permangan
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411588
Texas Waste Code:	Not reported
Texas Waste Code 2:	0059001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1479, Waste Oxidizing Solid, n.o.s. (Trichloroisocyanuric acid, potassium dich
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	OXIDIZING SOLIDS
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411571
Texas Waste Code:	Not reported
Texas Waste Code 2:	0060601H

UNITED AIRLINES (Continued) **S111057059**

Waste Code Status:	ACTIVE
Waste Form:	601
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2810, Waste Toxic Liquid, Organic, n.o.s (Barium, Phenol), 6.1, PGII
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	LIQUIDS TOXIC
Primary NAICS Code:	488119
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411591
Texas Waste Code:	Not reported
Texas Waste Code 2:	0061209H
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1263, Waste Paint, 3, PG II
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	OIL PAINT
Primary NAICS Code:	488119
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411592
Texas Waste Code:	Not reported
Texas Waste Code 2:	0062801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1978, Propane, 2.1
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	LIQUIFIED PROPANE
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411594
Texas Waste Code:	Not reported
Texas Waste Code 2:	0063801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1078, Refrigerant Gasses, n.o.s, (R13AA), 2.2
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	REFRIDGERANTS
Primary NAICS Code:	488119
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411574
Texas Waste Code:	Not reported
Texas Waste Code 2:	0064409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1944, Waste matches, Safety, 4.1, PGIII
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SAFETY MATCHES
Primary NAICS Code:	488119
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411575
Texas Waste Code:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Texas Waste Code 2:	0065001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1331, WASTE MATCHES, STRIKE ANYWHERE, 4.1, PG III;
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	STRIKE ANYWHERE
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	422074
Texas Waste Code:	Not reported
Texas Waste Code 2:	0066001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN2810, Waste Toxic Liquids, Organic, 6.1
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	TOXIC LIQUID ORGANIC
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Waste ID:	411538
Texas Waste Code:	Not reported
Texas Waste Code 2:	0068004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN0336, Waste Fireworks, 1.4G
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	FIREWORKS
Primary NAICS Code:	488119
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411540
Texas Waste Code:	Not reported
Texas Waste Code 2:	0069004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN0337, Waste Fireworks, 1.4S
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	FIREWORKS
Primary NAICS Code:	488119
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411561
Texas Waste Code:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Texas Waste Code 2:	0070405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN3012, Waste Cartridges, Signal, 1.4G
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	AERIAL FLARES
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411509
Texas Waste Code:	Not reported
Texas Waste Code 2:	0071405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN0403, Waste Flares, Aerial, I.4g,
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	AERIAL FLARES
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411525
Texas Waste Code:	Not reported
Texas Waste Code 2:	0072001H

UNITED AIRLINES (Continued) **S111057059**

Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA0027, Waste Black Powder for small arms, 4.1, PG I
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BLACK POWDER
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411572
Texas Waste Code:	Not reported
Texas Waste Code 2:	0073319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1869, Waste Magnesium 4,1 PG III
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MAGNESIUM
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411568
Texas Waste Code:	Not reported
Texas Waste Code 2:	0074405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0

UNITED AIRLINES (Continued) **S111057059**

Waste Treated Off Site:	Not reported
Generators Waste Description:	UN0312, Waste Cartridiges, Signal,1.4G
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SIGNAL CARTRIDGES
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411514
Texas Waste Code:	Not reported
Texas Waste Code 2:	0075405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN0044, Waste Primers, cap type,1.4S
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	PISTOL PRIMER CAPS
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411516
Texas Waste Code:	Not reported
Texas Waste Code 2:	0076001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA3178, Waste Smokeliss powder for small arms, 4.1 PGI

UNITED AIRLINES (Continued) **S111057059**

Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SMOKELESS POWDER
Primary NAICS Code:	488119
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	411527
Texas Waste Code:	Not reported
Texas Waste Code 2:	0077319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NA3077, Hazardous Waste Solid, n.o.s., (mercury), 9, PG III (broken fluorescent
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	BROKEN FLUORESCENT B
Primary NAICS Code:	488119
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	415141
Texas Waste Code:	Not reported
Texas Waste Code 2:	0078801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1072, WASTE OXYGEN, COMPRESSED, 2.2, (5.1)
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1

UNITED AIRLINES (Continued) **S111057059**

Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	OXYGEN CYLINDER
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	432086
Texas Waste Code:	Not reported
Texas Waste Code 2:	00798011
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UN1950, AEROSOLS, FLAMMABLE, (EACH NOT EXCEEDING 1 L CAPACITY), 2.1, (UNIVERSAL
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	UW AEROSOLS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	411512
Texas Waste Code:	Not reported
Texas Waste Code 2:	0254405H
Waste Code Status:	ACTIVE
Waste Form:	405
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste Consumer Comodity, (small arm ammunition in consumer packaging), ORM-D
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SMALL ARMS
Primary NAICS Code:	488119
EPA Waste Form Code:	W405
Reason Waste Form No Longer Gen:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	382305
Texas Waste Code:	Not reported
Texas Waste Code 2:	1111001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hazwaste (non-profiles: labpacked)-Hazmat voluntarily abandoned at airport check
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	926120
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

UNITED AIRLINES (Continued) **S111057059**

Ind. Haz Waste:

Contact Name:	KEVIN SWINTON
Contact Title:	Not reported
Contact Telephone:	0-512-3862004 x0
Mailing Address:	3600 PRESIDENTIAL BLVD STE 305
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78719
AR Number:	0000318236
Principal Name:	TRANSPORTATION SECURITY ADMINISTRATION TSA
Attention Name:	SWINTON ,KEVIN
Attention Suffix:	NWG

Contact Name:	KEVIN SWINTON
Contact Title:	Not reported
Contact Telephone:	0-512-3862004 x0
Mailing Address:	3600 PRESIDENTIAL BLVD STE 305
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78719
AR Number:	0000318236
Principal Name:	TRANSPORTATION SECURITY ADMINISTRATION TSA
Attention Name:	SWINTON ,KEVIN
Attention Suffix:	HWG

TIER 2:

Facility Id/Name:	FATR20107RKBUS0022TN/UNITED AIRLINES
Reporting Year:	2010
Facility Country:	USA
Facility Department:	AUS-OZ
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	2/28/2011
Mailing Address:	3600 Presidential Blvd. Mailbox#105
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	Not reported
Number Of Employess On Site:	48
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Frank Bessenyei
Latitude:	30.21
Longitude:	-97.66
Lat/Long Location Desc:	OT - Other
Lat/Long Method:	OT - Other
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	00-693-3030

UNITED AIRLINES (Continued) **S111057059**

Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/28/2011
Id:	48111
Id Type:	NAICS
Description:	Scheduled Air Transportation
Last Modified:	2/28/2011

Contact:

Contact Email:	frank.bessenyei@united.com
Contact Mail Address:	3600 Presidential Blvd. #105
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Frank Bessenyei
Title:	General Manager
Modification Date:	3/11/2011

Contact:

Contact Email:	john.rogers@united.com
Contact Mail Address:	Austin-Bergstrom Int'l Airport, 3600 Presidential Blvd. #105
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	John Rogers
Title:	Environmental Coordinator
Modification Date:	3/11/2011

Chemical Inventory:

Facility Id:	FATR20107RKBUS0022TN
Chemical Name:	Electrolyte (Sulfuric Acid)
Chemical Inv Record Id:	CVTR20107RKDA800HVSD
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	150
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/11/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

UNITED AIRLINES (Continued) **S111057059**

Chemical Inventory Location:

Record Key:	CLTR20107RKE0900JNLK
Chemical Inventory Record Id:	CVTR20107RKDA800HVSD
Amt Of Sub Stored Or Transported:	300
Amount Units:	pounds
Type Of Storage:	Other
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	2 Electric Belt Loaders located on the Ramp level gates 21 and 23
Last Modified:	3/11/2011

Mixture:

Record Key:	CMTR20107RKE4200KXFE
Chemical Inv Record Id:	CVTR20107RKDA800HVSD
Mix Chemical:	Electrolyte (Sulfuric Acid)
Percentage:	20
Facility Id:	FATR20107RKBUS0022TN
Mixture Cas:	7664-93-9
Weight/Volume:	Wt
Mixture Ehs:	T
Mixture Last Modified:	3/11/2011

Facility Id:	FATR20107RKBUS0022TN
Chemical Name:	Propylene Glycol (Type IV Anti-ice Fluid)
Chemical Inv Record Id:	CVTR20107RKET600LXNQ
CAS Number:	57-55-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	750
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/11/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20107RKF8D00M3C7
Chemical Inventory Record Id:	CVTR20107RKET600LXNQ
Amt Of Sub Stored Or Transported:	750
Amount Units:	pounds
Type Of Storage:	Tank wagon
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4

UNITED AIRLINES (Continued) **S111057059**

Desc of Loc(Or Transported) Subs: Di-icing truck located at gate 21 or located at the cargo building with ground equipment mechanics (next to post office)
Last Modified: 3/11/2011

Mixture:
Record Key: CMTR20107RKFDV00NTWD
Chemical Inv Record Id: CVTR20107RKET600LXNQ
Mix Chemical: Propanediol
Percentage: 1
Facility Id: FATR20107RKBUS0022TN
Mixture Cas: 57-55-6
Weight/Volume: Wt
Mixture Ehs: T
Mixture Last Modified: 3/11/2011

Facility Id: FATR20107RKBUS0022TN
Chemical Name: Aqueos Mono-propylene Glycol Mixture (Type-I Di-icing Fluid)
Chemical Inv Record Id: CVTR20107RKFJ600PK47
CAS Number: 57-55-6
Chemical Same As Last Year: T
Acute Health Risks: T
Average Daily Amount: 1,000 - 9,999 pounds
Max Daily Amount: 1,000 - 9,999 pounds
Max Amount In Largest Container: 1000
Chronic Health Risks: Not reported
EHS Substance: T
Last Modified: 3/11/2011
Days On Site: 365
Fire Hazard: Not reported
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: T
Reactive Hazard: Not reported
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2010
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20107RKFXA00QWWY
Chemical Inventory Record Id: CVTR20107RKFJ600PK47
Amt Of Sub Stored Or Transported: 1000
Amount Units: pounds
Type Of Storage: Other
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: Di-icing truck located on gate 21 or located at the cargo building with ground equipment mechanics (next to post office)
Last Modified: 3/11/2011

Mixture:
Record Key: CMTR20107RKG0X00R0VF
Chemical Inv Record Id: CVTR20107RKFJ600PK47

UNITED AIRLINES (Continued) **S111057059**

Mix Chemical:	monopropylene glycol
Percentage:	88
Facility Id:	FATR20107RKBUS0022TN
Mixture Cas:	57-55-6
Weight/Volume:	Wt
Mixture Ehs:	T
Mixture Last Modified:	3/11/2011

Facility Id:	FATR20107RKBUS0022TN
Chemical Name:	Propelyne Glycol (Type-I De-icing Fluid)
Chemical Inv Record Id:	CVTR20107RKG4500STZT
CAS Number:	57-55-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	1858
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	3/11/2011
Days On Site:	26
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20107RKGC500TRU6
Chemical Inventory Record Id:	CVTR20107RKG4500STZT
Amt Of Sub Stored Or Transported:	1858
Amount Units:	pounds
Type Of Storage:	Tote bin
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Gate 21, Cargo cart
Last Modified:	3/11/2011

Mixture:

Record Key:	CMTR20107RKGE200UE2E
Chemical Inv Record Id:	CVTR20107RKG4500STZT
Mix Chemical:	Propylene Glycol
Percentage:	88
Facility Id:	FATR20107RKBUS0022TN
Mixture Cas:	57-55-6
Weight/Volume:	Wt
Mixture Ehs:	T
Mixture Last Modified:	3/11/2011

UNITED AIRLINES (Continued) **S111057059**

Record Key:	CMTR20107RKGG600V7T7
Chemical Inv Record Id:	CVTR20107RKG4500STZT
Mix Chemical:	Water
Percentage:	11.4
Facility Id:	FATR20107RKBUS0022TN
Mixture Cas:	7732-18-5
Weight/Volume:	Wt
Mixture Ehs:	T
Mixture Last Modified:	3/11/2011

Notes: Not reported
Validation: Not reported

QF2817 **SMITH JAY BODY SHOP** **EDR Hist Auto** **1013773726**
WNW **832 5TH ST W** **N/A**
< 1/8 **TRAVIS (County), TX 78703**
0.109 mi.
578 ft. **Site 2 of 3 in cluster QF**

Actual:
463 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	SMITH JAY BODY SHOP	AUTOMOBILE REPAIRING

2818 **DAVE TRANSPORTATION SERVICES INC** **RCRA NonGen / NLR** **1000656470**
ESE **8300 IH 35 S ACCESS RD** **TXD988064614**
< 1/8 **AUSTIN, TX 78745**
0.111 mi.
584 ft.

Actual:
661 ft.
RCRA Listings:

Focus Map:
21

Date Form Received by Agency:	20130213
Handler Name:	Dave Transportation Services Inc
Handler Address:	IH 35 S ACCESS RD
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD988064614
Contact Name:	BRUCE ABEL
Contact Address:	8300 IH 35 S ACCESS RD
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-280-0088
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	IH 35 S ACCESS RD
Mailing City,State,Zip:	AUSTIN, TX 78745

DAVE TRANSPORTATION SERVICES INC (Continued) **1000656470**

Owner Name:	Dave Transportation Svc Inc
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130213
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAVE TRANSPORTATION SVC INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

DAVE TRANSPORTATION SERVICES INC (Continued) **1000656470**

Owner/Operator Address: 201 E SANDPOINTE STE 800
Owner/Operator City,State,Zip: SANTA ANA, CA 92707
Owner/Operator Telephone: 714-549-3283
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DAVE TRANSPORTATION SVC INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 201 E SANDPOINTE STE 800
Owner/Operator City,State,Zip: SANTA ANA, CA 92707
Owner/Operator Telephone: 714-549-3283
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20130213
Handler Name: DAVE TRANSPORTATION SERVICES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920320
Handler Name: DAVE TRANSPORTATION SERVICES INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

2819 SSW < 1/8 0.111 mi. 587 ft. | **MONTOPOLIS CDC 2404 THRASHER AUSTIN, TX 78741** | **US BROWNFIELDS** | **1026110179 N/A**

Actual: 570 ft.

Focus Map: 19

US BROWNFIELDS:

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

MONTOPOLIS CDC (Continued) **1026110179**

IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

MONTOPOLIS CDC (Continued) **1026110179**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

MONTOPOLIS CDC (Continued) **1026110179**

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants

MONTOPOLIS CDC (Continued) **1026110179**

Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

MONTOPOLIS CDC (Continued) **1026110179**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6

MONTOPOLIS CDC (Continued) **1026110179**

Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported

MONTOPOLIS CDC (Continued) **1026110179**

Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

Name:	MONTOPOLIS CDC
Address:	2404 THRASHER
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.96
Latitude:	30.219471
Longitude:	-97.703982
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The Montopolis NDC is a nonprofit affordable housing provider in the East Austin Montopolis neighborhood. They plan to purchase this property to put cottage , energy efficient affordable housing units on the property, and prevent existing residents from being displaced out of their community
Datum:	Not reported
Acres Property ID:	241993
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	7060
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment

MONTOPOLIS CDC (Continued) **1026110179**

Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	9/12/2019
Ownership Entity:	Private
Completion Date:	12/9/2019
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.96
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	539
Below Poverty Percent:	36.87
Meidan Income:	116
Meidan Income Number:	988
Meidan Income Percent:	67.58
Vacant Housing Number:	14
Vacant Housing Percent:	2.62
Unemployed Number:	106
Unemployed Percent:	7.25

QM2820 **UNIVERSITY SIGN SHOP** **TX RDR** **S127543786**
East **2920 SAN JACINTO** **N/A**
< 1/8 **AUSTIN, TX**
0.111 mi.
587 ft. **Site 1 of 4 in cluster QM**

Actual:
534 ft.

Focus Map:
11

RDR:

RDR ID:	18786
Facility ID:	0
RN:	Not reported
CN:	Not reported

UNIVERSITY SIGN SHOP (Continued) **S127543786**

Name:	UNIVERSITY SIGN SHOP
Address:	2920 SAN JACINTO
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/24/2010
Due Date:	5/23/2010
Tank Owner:	UT OF TX AUSTIN
Contact Person:	MR CHIP ROGERS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/2/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/2/2010
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

QM2821 **UNIVERSITY SIGN SHOP** **TX UST** **U004154747**
East **2920 SAN JACINTO BLVD** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.111 mi.
587 ft. **Site 2 of 4 in cluster QM**

Actual:
534 ft.

Focus Map:
11

UST:

Name:	UNIVERSITY SIGN SHOP
Address:	2920 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 787053804
AI Number:	83456
Facility Type:	Not reported
Facility Begin Date:	03/25/2010
Facility Status:	INACTIVE
Additional ID:	972499192011158
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/22/2010

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Signature Name/Title On Earliest Reg Form:	CHIP ROGERS,ASSOCIATE DIR
Application Received Date On Earliest Reg Form:	03/25/2010
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	583604122002106
Additional ID:	972499192011158
Ai Number:	83456
Operator CN:	CN601097413
Operator Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Operator Effective Begin Date:	03/25/2010
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	PETER SCHNEIDER/DIRECTOR
Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Contact Mailing Address (Delivery):	PO BOX 7580
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78713-7580
Contact Phone Country Code:	0
Contact Phone Area Code:	512
Contact Phone Number:	4421122
Contact Phone Extension:	0
Contact Fax Country Code:	0
Contact Fax Area Code:	512
Contact Fax Number:	4421181
Contact Fax Extension:	0
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601097413
Owner Last Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	PO BOX 7729
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78713
Contact Mailing Zip5:	7729
Contact Phone Number/Ext:	1 512 4756522/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	583604122002106
Additional ID:	972499192011158
AI Number:	83456
Owner Effective Begin Date:	03/25/2010
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	MARK KALIGAN/FLT OPS MGR
Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/25/2010
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	213297
Facility ID:	127703
Ai Number:	83456
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	185205
UST ID:	213297
AI Number:	83456
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	03/25/2010
Number of Compartments:	1
Tank Capacity:	750
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported

UNIVERSITY SIGN SHOP (Continued) **U004154747**

UST ID:	213300
Facility ID:	127703
Ai Number:	83456
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Tank Capacity:	0
UST Comprt ID:	185208
UST ID:	213300
AI Number:	83456
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	03/25/2010
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	213299
Facility ID:	127703
Ai Number:	83456
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	0
UST Comprt ID:	185207
UST ID:	213299
AI Number:	83456
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

UNIVERSITY SIGN SHOP (Continued) **U004154747**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	03/25/2010
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	213298
Facility ID:	127703
Ai Number:	83456
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	09/17/2009
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	185206
UST ID:	213298
AI Number:	83456
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

UNIVERSITY SIGN SHOP (Continued) **U004154747**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	22556
Facility ID:	127703
AI Number:	83456
Application Received Date:	09/11/2009
Scheduled Construction Date:	10/11/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	Y
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M90911001
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	Not reported

UNIVERSITY SIGN SHOP (Continued) **U004154747**

Facility Billing Contacts:

Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Contact Mailing Address (Delivery):	PO BOX 7729
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78713 7729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	127703
Additional ID:	972499192011158
Princ ID:	583604122002106
AI Number:	83456
Facility Name:	UNIVERSITY SIGN SHOP
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHIP ROGERS/

HIST UST AUSTIN:

Name:	UT SIGN SHOP
Address:	2920 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3317
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QM2822 **UT SIGN SHOP** **TX NON REGIST PST** **S126253288**
East **2920 SAN JACINTO BLVD** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.111 mi.
587 ft. **Site 3 of 4 in cluster QM**

Actual:
534 ft.

Focus Map:
11

NON REGIST PST:

RN Number:	RN105808810
Name:	UT SIGN SHOP
Address:	2920 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78705 3804
Physical Location:	No physical location description ON file.
CN Number:	CN601097413
Customer Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Customer Role:	OWNER OPERATOR
Primary Business:	MAKES UNIVERSITY SIGNS
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=645447312009267

QN2823 **CAPITOL LAUNDRY** **EDR Hist Cleaner** **1013782694**
WNW **801 BARTON SPRINGS RD** **N/A**
< 1/8 **SOUTH AUSTIN, TX**
0.112 mi.
590 ft. **Site 1 of 2 in cluster QN**

Actual:
455 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1940	CAPITOL LAUNDRY	CLOTHES PRESSERS AND CLEANERS
1940	CAPITOL LAUNDRY	LAUNDRIES
1947	CAPITOL LNDRY & CLNG CO	LAUNDRIES

QN2824 **CAPITOL LAUNDRY & DRY** **EDR Hist Cleaner** **1013780083**
WNW **801 BARTON SPRINGS RD** **N/A**
< 1/8 **AUSTIN, TX**
0.112 mi.
590 ft. **Site 2 of 2 in cluster QN**

Actual:
455 ft.
EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1965	CAPITOL LAUNDRY & DRY	LAUNDRIES
1970	CAPITOL LAUNDRY & DRY CLEANING	LAUNDRIES
1971	CAPITOL LAUNDRY & DRY CLG CO	Power Laundries, Family And Commercial
1972	CAPITOL LAUNDRY & DRY CLG CO	Power Laundries, Family And Commercial
1973	CAPITOL LAUNDRY & DRY CLG CO	Power Laundries, Family And Commercial
1975	CAPITOL LAUNDRY & DRY CLEANING	LAUNDRIES AND DRY CLEANERS

OT2825 **BRAKE CHECK** **EDR Hist Auto** **1013759495**
WNW **3700 LAMAR BLVD N** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.112 mi.
590 ft. **Site 8 of 8 in cluster OT**

Actual:
610 ft.
EDR Hist Auto

Focus Map:
8

Year:	Name:	Type:
1980	BRAKE CHECK	AUTOMOBILE REPAIRING
1983	BEXAR BRAKE CENTERS*	Automotive Repair Shops, NEC
1984	BRAKE CHECK	AUTOMOBILE REPAIRING
1985	BEXAR BRAKE CENTERS*	Automotive Repair Shops, NEC
1986	BEXAR BRAKE CENTERS*	Automotive Repair Shops, NEC
1987	PEVETO COMPANIES INC	Automotive Repair Shops, NEC
1988	PEVETO COMPANIES INC	Automotive Repair Shops, NEC

QC2826 **MOBIL MART** **EDR Hist Auto** **1013763984**
ENE **717 7TH ST E** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.113 mi.
595 ft. **Site 3 of 12 in cluster QC**

Actual:
467 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1980	WALSH SERVICE CENTER	GASOLINE STATIONS
1984	TOWNE LAKE MOBILE GAS ST	GASOLINE STATIONS

MOBIL MART (Continued) **1013763984**

1990	MOBIL MART	GASOLINE STATIONS

QC2827 **WALSH SERVICE CENTER** **EDR Hist Auto** **1013773884**
ENE **717 7TH ST E** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.113 mi.
595 ft. **Site 4 of 12 in cluster QC**

Actual:
467 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1975	WALSH SERVICE CENTER	SERVICE STATIONS
1975	WALSH SERVICE CENTER	GASOLINE STATIONS

QO2828 **Z CAR SHOP** **EDR Hist Auto** **1013758838**
WNW **811 MCPHAUL** **N/A**
< 1/8 **AUSTIN, TX 78758**
0.113 mi.
596 ft. **Site 1 of 3 in cluster QO**

Actual:
733 ft.

EDR Hist Auto

Focus Map:
3

Year:	Name:	Type:
1975	RENNSPORT PORSCHE WORKS	General Automotive Repair Shops
1976	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1977	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1978	IMPORT CAR REPAIRS INC	General Automotive Repair Shops
1980	Z CAR SHOP	AUTOMOBILE REPAIRING
1980	Z CAR SHOP*	General Automotive Repair Shops
1982	Z CAR SHOP*	General Automotive Repair Shops
1984	Z CAR SHOP	AUTOMOBILE REPAIRING
2004	WILLS MERCEDES & AUTOMOTIVE	General Automotive Repair Shops

---

QO2829 **MINGOS BODY SHOP** **TX Ind. Haz Waste** **S104854199**
WNW **811 MCPHAUL ST** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78758**
0.113 mi.
596 ft. **Site 2 of 3 in cluster QO**

Actual:
733 ft.

Ind. Haz Waste:

Focus Map:
3

Name:	MINGOS BODY SHOP
Address:	811 MCPHAUL ST
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	66776
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981145055
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	OTHER
Description of Facility Site Location:	811 McPaul, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11

MINGOS BODY SHOP (Continued) **S104854199**

Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	MINGOS BODY SHOP
Contact Name:	VERA RICHARD
Contact Telephone Number:	512-8360600
Mailing Address:	815 MCPHAUL ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787584805
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22030
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	MINGOS BODY SHOP
Operator Address:	815 MCPHAUL ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78758
Operator Country:	UNITED STA
Operator Telephone:	1-512-8360600
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MINGOS BODY SHOP
Owner Mailing Address:	815 MCPHAUL ST
Owner Mailing Address 2:	Not reported

MINGOS BODY SHOP (Continued) **S104854199**

Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Country:	UNITED STA
Owner Telephone:	1-512-8360600
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19920120
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	815 MCPHAUL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8360600
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	815 MCPHAUL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8360600

MINGOS BODY SHOP (Continued) **S104854199**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	VERA RICHARD
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	815 MCPHAUL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8360600
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100556695
Name:	MINGOS BODY SHOP
Address:	811 MCPHAUL ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4805
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267595
Customer Name:	MINGOS BODY SHOP
Customer Legal Name:	Mingo's Body Shop
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	811 McPaul, Austin, TX
Regulated Entity Number:	RN100556695
Name:	MINGOS BODY SHOP
Address:	811 MCPHAUL ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4805
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267595
Customer Name:	MINGOS BODY SHOP
Customer Legal Name:	Mingo's Body Shop
Customer Ownership Type:	OTHER
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	811 McPaul, Austin, TX

PS2830 West < 1/8 0.113 mi. 599 ft. — **CONVENIENCE COIN LAUNDRY NO**, **915 W 24TH ST**, **AUSTIN, TX 78705** — **EDR Hist Cleaner** — **1013780132** / **N/A**

Site 7 of 7 in cluster PS

Actual: 599 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1980	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE
1984	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE
1990	CONVENIENCE COIN LAUNDRY NO	LAUNDRIES-SELF SERVE

2831 ESE < 1/8 0.113 mi. 599 ft. — **BROWN BROS**, **1600 SAN JACINTO**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013777296** / **N/A**

Actual: 515 ft.

Focus Map: 11

EDR Hist Cleaner

Year:	Name:	Type:
1940	BROWN BROS	LAUNDRIES
1940	SAN JACINTO LAUNDRY	LAUNDRIES
1947	SAN JACINTO LAUNDRY & DRY CLEAN	CLOTHES PRESSERS AND CLEANERS
1947	SAN JACINTO LAUNDRY & DRY CLEAN	LAUNDRIES
1953	SAN JACINTO LNDRY	LAUNDRIES
1958	SAN JACINTO LNDRY	LAUNDRIES
1962	SAN JACINTO LNDRY &	LAUNDRIES
1965	SAN JACINTO LAUNDRY	LAUNDRIES
1970	SAN JACINTO LAUNDRY & CLEANERS	LAUNDRIES

PR2832 WNW < 1/8 0.114 mi. 600 ft. — **CARL M. TEMPLETON**, **3906 N LAMAR BLVD**, **AUSTIN, TX** — **TX HIST UST** — **S111678597** / **N/A**

Site 5 of 5 in cluster PR

Actual: 622 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	CARL M. TEMPLETON
Address:	3906 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0656
HID UST:	656
Inspection:	Not reported
Due:	06/01/2012

QP2833 **CAPITAL PRINTING CO INC** **RCRA NonGen / NLR** **1000264279**
ESE **213 E ALPINE RD** **FINDS** **TXD063101331**
< 1/8 **AUSTIN, TX 78704** **ECHO**
0.114 mi. **TX Ind. Haz Waste**
600 ft. **Site 1 of 2 in cluster QP**

Actual:
671 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Capital Printing Co Inc
Handler Address:	E ALPINE RD
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD063101331
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	E ALPINE RD
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E ALPINE RD
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Capital Printing Co Inc
Owner Type:	Private
Operator Name:	Capital Printing Co Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CAPITAL PRINTING CO INC (Continued) **1000264279**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CAPITAL PRINTING CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	213 E ALPINE RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CAPITAL PRINTING CO INC	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	213 E ALPINE RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EDWARDS BARKLEY AND RABY WILLIAM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19800815

CAPITAL PRINTING CO INC (Continued) **1000264279**

Handler Name: CAPITAL PRINTING CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: CAPITAL PRINTING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 323117
NAICS Description: BOOKS PRINTING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005057142

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000264279
Registry ID: 110005057142
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005057142

CAPITAL PRINTING CO INC (Continued) **1000264279**

Name:	CAPITAL PRINTING CO INC
Address:	213 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704

Ind. Haz Waste:

Name:	CAPITAL PRINTING
Address:	213 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	36353
Registration Initial Notification Date:	07/27/2001
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD063101331
Primary NAICS Code:	Not reported
Status Change Date:	20010727
Land Type:	PRIVATE
Description of Facility Site Location:	213 E Alpine Rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CLASS1
Type of Generator:	Not reported
Company Name:	CAPITAL PRINTING CO INC
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	213 E ALPINE RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787047201
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	13236
Site Owner Tax ID:	740543560
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110911
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

CAPITAL PRINTING CO INC (Continued) **1000264279**

Ind. Haz Waste:

Operator Name:	CAPITAL PRINTING CO INC
Operator Address:	213 E ALPINE RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78704
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17405435607
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITAL PRINTING CO INC
Owner Mailing Address:	213 E ALPINE RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17405435607
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	213 E ALPINE RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	213 E ALPINE RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	213 E ALPINE RD
Contact Address 2:	Not reported

CAPITAL PRINTING CO INC (Continued) **1000264279**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

QP2834 **CAPITAL PRINTING** **TX Ind. Haz Waste** **S108167233**
ESE **213 E ALPINE RD** **N/A**
< 1/8 **AUSTIN, TX 78704**
0.114 mi.
600 ft. **Site 2 of 2 in cluster QP**

Actual:
671 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	CAPITAL PRINTING
Address:	213 E ALPINE RD
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66229
Registration Initial Notification Date:	08/23/2001
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD063101331
Primary NAICS Code:	Not reported
Status Change Date:	20010823
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CLASS1
Type of Generator:	NON INDUS
Company Name:	CAPITAL PRINTING CO INC
Contact Name:	BARTLEY EDWARDS
Contact Telephone Number:	512-4421415
Mailing Address:	PO BOX 3275
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787643275
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21520
Site Owner Tax ID:	740543560
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031013
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

CAPITAL PRINTING (Continued) **S108167233**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CAPITAL PRINTING CO INC
Operator Address:	PO BOX 3275
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78764
Operator Country:	UNITED STA
Operator Telephone:	1-512-4421415
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17405435607
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITAL PRINTING CO INC
Owner Mailing Address:	PO BOX 3275
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78764
Owner Country:	UNITED STA
Owner Telephone:	1-512-4421415
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17405435607
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 3275
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4421415
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 3275
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4421415
Contact Fax:	Not reported

CAPITAL PRINTING (Continued) **S108167233**

Contact Email:	Not reported
Contact Name:	BARTLEY EDWARDS
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 3275
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4421415
Contact Fax:	Not reported
Contact Email:	Not reported

PX2835 **A-TEX AUSTIN INC** **RCRA NonGen / NLR** **1000225434**
NW **4106 N LAMAR** **FINDS** **TXD008126773**
< 1/8 **AUSTIN, TX 78756** **ECHO**
0.114 mi. **TX ASBESTOS**
603 ft. **Site 2 of 4 in cluster PX** **TX Ind. Haz Waste**
TX CENTRAL REGISTRY

Actual:
634 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	A-Tex Austin Inc
Handler Address:	N LAMAR
Handler City,State,Zip:	AUSTIN, TX 78756
EPA ID:	TXD008126773
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	N LAMAR
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR
Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Name:	A-Tex Austin Inc
Owner Type:	Not reported
Operator Name:	A-Tex Austin Inc
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

A-TEX AUSTIN INC (Continued) **1000225434**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ATEX AUSTIN INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: A-TEX AUSTIN INC	
Legal Status:	Not reported
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	4106 N LAMAR
Owner/Operator City,State,Zip:	AUSTIN, TX 78756
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Owner/Operator Indicator: Operator
Owner/Operator Name: A-TEX AUSTIN INC
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 4106 N LAMAR
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800729
Handler Name: A-TEX AUSTIN INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: A-TEX AUSTIN INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005038538

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

A-TEX AUSTIN INC (Continued) **1000225434**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000225434
Registry ID:	110005038538
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005038538
Name:	A-TEX AUSTIN INC
Address:	4106 N LAMAR
City,State,Zip:	AUSTIN, TX 78756

ASBESTOS:

Name:	AUSTIN VET CARE
Address:	4106 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	01/02/2020
Notification Number:	2019009221
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/03/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/03/2020
Certification Statement Phone:	512-778-6069

A-TEX AUSTIN INC (Continued) **1000225434**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/02/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN VET CARE
Address:	4106 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	01/03/2020
Notification Number:	2019009221
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/02/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN VET CARE
Address:	4106 N. LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/03
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/03/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019009221
File Number:	47821
License Status Description:	Current
Expiration Date:	01/02/2020
Original Date:	12/11/2019
Rank Effective Date:	12/11/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20051
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Ind. Haz Waste:

Name:	A-TEX AUSTIN
Address:	4106 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	66043
Registration Initial Notification Date:	02/16/1983
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD008126773
Primary NAICS Code:	Not reported
Status Change Date:	19830216
Land Type:	Not reported
Description of Facility Site Location:	4106 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	A-TEX AUSTIN INC
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	4106 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787563716
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21346
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030328
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	A-TEX AUSTIN INC
Operator Address:	4106 N LAMAR BLVD
Operator Address 2:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78756
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	A-TEX AUSTIN INC
Owner Mailing Address:	4106 N LAMAR BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4106 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4106 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4106 N LAMAR BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	Not reported
Contact Fax:	Not reported

A-TEX AUSTIN INC (Continued) **1000225434**

Contact Email: Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100565449
Name:	A-TEX AUSTIN
Address:	4106 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-3716
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600276125
Customer Name:	A-TEX AUSTIN INC
Customer Legal Name:	A-Tex Austin, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4106 N Lamar, Austin, TX

Regulated Entity Number:	RN100565449
Name:	A-TEX AUSTIN
Address:	4106 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-3716
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600276125
Customer Name:	A-TEX AUSTIN INC
Customer Legal Name:	A-Tex Austin, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	4106 N Lamar, Austin, TX

2836 **BLACK & DECKER** **TX Ind. Haz Waste** **S108167185**
WNW **911 W ANDERSON LN** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78757**
0.115 mi.
606 ft.

Actual:
772 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	BLACK & DECKER
Address:	911 W ANDERSON LN
City,State,Zip:	AUSTIN, TX 78757
Permit Number:	Not reported
Registration Number:	61752
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	10/20/2006
EPA Identification:	Not reported
Primary NAICS Code:	333923
Status Change Date:	19850930

BLACK & DECKER (Continued) **S108167185**

Land Type:	Not reported
Description of Facility Site Location:	911 W Anderson Lane, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	BLACK & DECKER US INC
Contact Name:	DAVE JOHNSON
Contact Telephone Number:	317-3347087
Mailing Address:	911 W ANDERSON LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787571501
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20093
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20090226
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BLACK & DECKER US INC
Operator Address:	911 W ANDERSON LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78757
Operator Country:	UNITED STA
Operator Telephone:	1-317-3347087
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	15211273576
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

BLACK & DECKER (Continued) **S108167185**

Owner Name:	BLACK & DECKER US INC
Owner Mailing Address:	911 W ANDERSON LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Country:	UNITED STA
Owner Telephone:	1-317-3347087
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	15211273576
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	911 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-317-3347087
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	911 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-317-3347087
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DAVE JOHNSON
Contact Title:	SAFTEY REPRESENTATIVE
Contact Role:	PRICONT
Contact Address:	911 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-317-3347087
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	138760
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1

BLACK & DECKER (Continued) **S108167185**

Generators Waste Description:	SPENT SOLVENT. Facility has moved operations and is not generating any waste.
Standard Industrial Code:	35360
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013623
Primary NAICS Code:	333923
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100705979
Name:	BLACK & DECKER
Address:	911 W ANDERSON LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-1501
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600274187
Customer Name:	BLACK & DECKER US INC
Customer Legal Name:	Black & Decker (U.S.) Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/20/2006
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333923
Primary NAICS Industry Type Description:	Hoist and Monorail System Manufacturing
Physical Location Description:	911 W Anderson Lane, Austin, TX

Regulated Entity Number:	RN100705979
Name:	BLACK & DECKER
Address:	911 W ANDERSON LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-1501
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600274187
Customer Name:	BLACK & DECKER US INC
Customer Legal Name:	Black & Decker (U.S.) Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/20/2006
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333923
Primary NAICS Industry Type Description:	Hoist and Monorail System Manufacturing

BLACK & DECKER (Continued) **S108167185**

Physical Location Description: 911 W Anderson Lane, Austin, TX

PQ2837 **LEE MANERS** **TX HIST UST** **S111678720**
WNW **601 W LIVE OAK ST** **N/A**
< 1/8 **AUSTIN, TX**
0.115 mi.
609 ft. **Site 3 of 3 in cluster PQ**

Actual:
535 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	LEE MANERS
Address:	601 W LIVE OAK ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0374
HID UST:	374
Inspection:	02/06/2009
Due:	02/06/2012

QQ2838 **HUMBLE OIL REFG CO** **EDR Hist Auto** **1013763455**
ESE **1800 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.115 mi.
609 ft. **Site 1 of 4 in cluster QQ**

Actual:
507 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1935	HUMBLE OIL REFG CO	GASOLINE AND OIL SERVICE STATIONS
1953	NOBLE HUMBLE SERV	GASOLINE STATIONS
1958	WELLS S T HUMBLE	GASOLINE STATIONS

QQ2839 **KOCUREK WILLIE** **EDR Hist Auto** **1013758308**
ESE **1822 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.116 mi.
610 ft. **Site 2 of 4 in cluster QQ**

Actual:
509 ft.

Focus Map:
11

EDR Hist Auto

Year:	Name:	Type:
1940	PUCKETT WALTER SERV STATION	GASOLINE AND OIL SERVICE STATIONS
1958	KOCUREK WILLIE	GASOLINE STATIONS
1962	KOCUREK WILLIE SERV STA	GASOLINE STATIONS
1965	KOCUREK WILLIE SERVICE	GASOLINE STATIONS

QQ2840 ESE < 1/8 0.116 mi. 610 ft. — **WESLEY GEO DCLO CLNR**, **1818 SAN JACINTO**, **AUSTIN, TX** — **EDR Hist Cleaner** — **1013783710** / **N/A**

Site 3 of 4 in cluster QQ

Actual: 508 ft. EDR Hist Cleaner

Focus Map: 11

Year:	Name:	Type:
1940	WESLEY GEO DCLO CLNR	CLEANERS, PRESSERS AND DYERS
1940	WESLEY GEO DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1940	WESLEY GEO DCLO CLNR	RUG CLEANERS
1940	WESLEY GEO DCLO CLNR	DYERS AND CLEANERS
1940	WESLEY GEO DCLO CLNR	DRY CLEANERS

QQ2841 ESE < 1/8 0.116 mi. 610 ft. — **KOCUREKS SERVICE STA & AUTO SUPPLY**, **1818 SAN JACINTO**, **AUSTIN, TX** — **EDR Hist Auto** — **1013754535** / **N/A**

Site 4 of 4 in cluster QQ

Actual: 508 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1947	KOCUREKS SERVICE STA & AUTO SUP	GASOLINE AND OIL SERVICE STATIONS

QC2842 ENE < 1/8 0.116 mi. 611 ft. — **WALSH NORMAN SERVICE**, **719 7TH ST E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013767805** / **N/A**

Site 5 of 12 in cluster QC

Actual: 468 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1965	WALSH NORMAN SERVICE	GASOLINE STATIONS

QC2843 ENE < 1/8 0.116 mi. 611 ft. — **BROWN & WALSH SERV STA FILLING ST**, **719 7TH E**, **AUSTIN, TX** — **EDR Hist Auto** — **1013771827** / **N/A**

Site 6 of 12 in cluster QC

Actual: 468 ft. EDR Hist Auto

Focus Map: 11

Year:	Name:	Type:
1940	BROWN & WALSH SERV STA FILLING	GASOLINE AND OIL SERVICE STATIONS
1947	WALSH NORMAN SERVICE STA	GASOLINE AND OIL SERVICE STATIONS
1953	WALSH SERVICE STA	GASOLINE STATIONS
1958	WALSH NORMAN SERV	GASOLINE STATIONS
1962	WALSH NORMAN SERV STA	GASOLINE STATIONS

PW2844 WNW < 1/8 0.116 mi. 611 ft. — **PRONTO ENGINE & TRANSMISSION**, **830 PRAIRIE TRL**, **AUSTIN, TX 78758** — **EDR Hist Auto** — **1021252971** / **N/A**

Site 2 of 2 in cluster PW

Actual: 749 ft. EDR Hist Auto

Focus Map: 3

Year:	Name:	Type:
1992	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1993	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1994	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
1995	SCHWABE AUTOMOTIVE	Automotive Repair Shops, NEC
2001	ENGINE TRANSMISSION	Automotive Transmission Repair Shops
2002	PRONTO ENGINE TRANSMISSION	Automotive Transmission Repair Shops
2002	ENGINE TRANSMISSION	Automotive Transmission Repair Shops
2003	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2003	ENGINE TRANSMISSION	Automotive Transmission Repair Shops
2004	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2004	ENGINE TRANSMISSION	Automotive Transmission Repair Shops
2005	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2006	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2007	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2008	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2009	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2010	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2011	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2012	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2013	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops
2014	PRONTO ENGINE & TRANSMISSION	Automotive Transmission Repair Shops

---

QR2845 SE < 1/8 0.116 mi. 612 ft. — **A E D AUTO UPHOLSTERY AUTO UPHOL**, **615 POWELL LN W**, **TRAVIS (County), TX 78763** — **EDR Hist Auto** — **1013768109** / **N/A**

Site 1 of 3 in cluster QR

Actual: 729 ft. EDR Hist Auto

Focus Map: 6

Year:	Name:	Type:
1990	A E D AUTO UPHOLSTERY AUTO UPHO	AUTOMOBILE REPAIRING

PX2846 NW < 1/8 0.117 mi. 618 ft. — **LONE STAR CYCLE MOTIVE MOTORCYLE ACCESSORIES**, **4108 LAMAR BLVD N**, **TRAVIS (County), TX 78756** — **EDR Hist Auto** — **1013766963** / **N/A**

Site 3 of 4 in cluster PX

Actual: 634 ft. EDR Hist Auto

Focus Map: 8

Year:	Name:	Type:
1990	LONE STAR CYCLE MOTIVE MOTORCYL	MOTORCYCLE DEALERS AND REPAIRERS
1990	LONE STAR B M W MOTORCYCLE SLS	MOTORCYCLE DEALERS AND REPAIRERS

PX2847 **REED PHILLIPS OIL CO.** **TX HIST UST** **S111678790**
NW **4108 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.117 mi.
618 ft. **Site 4 of 4 in cluster PX**

Actual:
634 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	REED PHILLIPS OIL CO.
Address:	4108 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0659
HID UST:	659
Inspection:	03/24/2009
Due:	03/24/2012

QS2848 **COMET CLEANERS** **RCRA NonGen / NLR** **1000223387**
ESE **9515 N LAMAR STE 108** **FINDS** **TXD981590516**
< 1/8 **AUSTIN, TX 78753** **ECHO**
0.117 mi.
620 ft. **Site 1 of 3 in cluster QS**

Actual:
681 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20070918
Handler Name:	Comet One-Hour Cleaners
Handler Address:	N LAMAR STE 108
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXD981590516
Contact Name:	KEITH A KOCHER
Contact Address:	N LAMAR BLVD STE 108
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Telephone:	512-339-9932
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	N LAMAR BLVD STE 108
Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Name:	Comet One-Hour Cleaners
Owner Type:	Private
Operator Name:	Comet One-Hour Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

COMET CLEANERS (Continued) **1000223387**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20070928
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SUPERE PROPERTY MGMT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000

COMET CLEANERS (Continued) **1000223387**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMET ONE-HOUR CLEANERS
Legal Status: Private
Date Became Current: 20070918
Date Ended Current: Not reported
Owner/Operator Address: 9515 N LAMAR BLVD STE 108
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9932
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMET ONE-HOUR CLEANERS
Legal Status: Private
Date Became Current: 20070918
Date Ended Current: Not reported
Owner/Operator Address: 9515 N LAMAR BLVD STE 108
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9932
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COMET ONE-HOUR CLEANERS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 9515 N LAMAR BLVD STE 108
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9932
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COMET ONE-HOUR CLEANERS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 9515 N LAMAR BLVD STE 108
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-339-9932
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860908
Handler Name: COMET CLNRS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx

COMET CLEANERS (Continued) **1000223387**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: COMET ONE-HOUR CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070918
Handler Name: COMET ONE-HOUR CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005091266

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

COMET CLEANERS (Continued) **1000223387**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000223387
Registry ID:	110005091266
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005091266
Name:	COMET CLEANERS
Address:	9515 N LAMAR STE 108
City,State,Zip:	AUSTIN, TX 78753

QS2849 **COMET CLEANERS** **EDR Hist Cleaner** **1013777436**
ESE **9515 LAMAR BLVD N** **N/A**
< 1/8 **TRAVIS (County), TX 78753**
0.117 mi.
620 ft. **Site 2 of 3 in cluster QS**

Actual:
681 ft.

EDR Hist Cleaner

Focus Map:
6

Year:	Name:	Type:
1985	COMET ONE HOUR CLEANERS	Drycleaning Plants, Except Rugs
1986	EVANS-KOCHER	Drycleaning Plants, Except Rugs
1987	EVANS-KOCHER	Drycleaning Plants, Except Rugs
1988	EVANS-KOCHER	Drycleaning Plants, Except Rugs
1989	EVANS-KOCHER	Drycleaning Plants, Except Rugs, NEC
1990	COMET CLEANERS	CLEANERS AND DYERS
1990	EVANS-KOCHER	Drycleaning Plants, Except Rugs, NEC
1991	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC
1992	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC
1993	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC
1994	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC
1995	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC
1996	KOCHER & EVANS INCORPORATED	Drycleaning Plants, Except Rugs, NEC

QS2850 **STAR BRITE CLEANERS** **TX DRYCLEANERS** **S105491097**
ESE **9515 N LAMAR BLVD STE 108** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78753** **TX CENTRAL REGISTRY**
0.117 mi.
620 ft. **Site 3 of 3 in cluster QS**

Actual:
681 ft.

DRYCLEANERS:

Name:	MARTINIZING 941477 NORTH LAMAR
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177

Focus Map:
6

STAR BRITE CLEANERS (Continued) **S105491097**

DCR Number:	DCR10600
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	MARTINIZING 941477 NORTH LAMAR
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PETROLEUM
Gallons:	400
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN602776890
DCR Number:	DCR10600
AR Number:	24003006
Principal Name:	KAK FAR WEST INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MARTINIZING 941477 NORTH LAMAR
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN600255533
DCR Number:	DCR10600
AR Number:	24003006
Principal Name:	COMET CLEANERS
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	Not reported
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

STAR BRITE CLEANERS (Continued) **S105491097**

Fiscal Year:	FY2017
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177
DCR Number:	DCR10600
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264
Site Name:	MARTINIZING 941477 NORTH LAMAR
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	MARTINIZING 941477 NORTH LAMAR
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN605442177
DCR Number:	DCR10600
AR Number:	24007703
Principal Name:	B&K LLC
Bill Addr1:	9515 N LAMAR BLVD STE 108
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4136
EMail:	SCHUURMAN78746@YAHOO.COM
Phone Number:	512 7960636
Site Name:	MARTINIZING 941477 NORTH LAMAR
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN

STAR BRITE CLEANERS (Continued) **S105491097**

CN Number:	CN604848820
DCR Number:	DCR10600
AR Number:	24007272
Principal Name:	GARMENT BAG INC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264
Site Name:	STAR BRITE CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	PETROLEUM
Gallons:	150
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN600255533
DCR Number:	Not reported
AR Number:	24000668
Principal Name:	COMET CLEANERS
Bill Addr1:	9515 N LAMAR BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78753 4188
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION

STAR BRITE CLEANERS (Continued) **S105491097**

Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	420
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744

STAR BRITE CLEANERS (Continued) **S105491097**

Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL

STAR BRITE CLEANERS (Continued) **S105491097**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PETROLEUM
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	250
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753

STAR BRITE CLEANERS (Continued) **S105491097**

RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	11
CN Number:	CN602776833
DCR Number:	Not reported
AR Number:	24003005
Principal Name:	KE COMET AUSTIN INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4122
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN604848820
DCR Number:	DCR10600
AR Number:	24007272
Principal Name:	GARMENT BAG INC
Bill Addr1:	2402 CATAMARAN CV
Bill Addr2:	Not reported
Bill City/State/Zip:	CEDAR PARK, TX 78613 1588
EMail:	THE.GARMENT.BAG@GMAIL.COM
Phone Number:	512 5770264

STAR BRITE CLEANERS (Continued) **S105491097**

Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	STAR BRITE CLEANERS NL
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
RN Number:	RN100712744
Region:	REGION 11 - AUSTIN
CN Number:	CN602776890
DCR Number:	DCR10600
AR Number:	24003006
Principal Name:	KAK FAR WEST INCORPORATED
Bill Addr1:	3637 FAR WEST BLVD STE B
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78731 4126
EMail:	KAKCOMET@SBCGLOBAL.NET
Phone Number:	512 3380141
Site Name:	STAR BRITE CLEANERS NL
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Ind. Haz Waste:

Name:	COMET ONE-HOUR CLEANERS
Address:	9515 N LAMAR BLVD STE 108
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	61663
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981590516
Primary NAICS Code:	812320
Status Change Date:	19850930
Land Type:	PRIVATE
Description of Facility Site Location:	9515 N Lamar, Ste 108, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG

STAR BRITE CLEANERS (Continued) **S105491097**

Type of Generator:	NON INDUS
Company Name:	COMET ONE-HOUR CLEANERS
Contact Name:	KEITH A KOCHER
Contact Telephone Number:	512-3399932
Mailing Address:	9515 N LAMAR BLVD STE 108
Mailing Address2:	STE 108
Mailing City,State,Zip:	AUSTIN, TX 787534136
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20007
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20070918
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	COMET ONE-HOUR CLEANERS
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	COMET ONE-HOUR CLEANERS
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

STAR BRITE CLEANERS (Continued) **S105491097**

Ind. Haz Waste:

Contact Name:	KEITH KOCHER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	9515 N LAMAR BLVD STE 108
Contact Address 2:	STE 108
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-3399932
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	9/1/2003
Affiliation End Date:	8/31/2004
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	9/1/2003
Affiliation End Date:	8/31/2004
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE

STAR BRITE CLEANERS (Continued) **S105491097**

Status Date:	##########
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	9/1/2003
Affiliation End Date:	8/31/2004
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	9/1/2003
Affiliation End Date:	8/31/2004
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600255533
Customer Name:	COMET CLEANERS
Customer Legal Name:	Kak Farwest, Incorporated
Customer Ownership Type:	OTHER
Affiliation Begin Date:	9/1/2003
Affiliation End Date:	8/31/2004
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602776833
Customer Name:	KE COMET AUSTIN INCORPORATED

STAR BRITE CLEANERS (Continued) **S105491097**

Customer Legal Name:	Ke Comet Austin, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	8/31/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602776833
Customer Name:	KE COMET AUSTIN INCORPORATED
Customer Legal Name:	Ke Comet Austin, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	8/31/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602776833
Customer Name:	KE COMET AUSTIN INCORPORATED
Customer Legal Name:	Ke Comet Austin, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	8/31/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602776833
Customer Name:	KE COMET AUSTIN INCORPORATED
Customer Legal Name:	Ke Comet Austin, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2004

STAR BRITE CLEANERS (Continued) **S105491097**

Affiliation End Date:	8/31/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602776833
Customer Name:	KE COMET AUSTIN INCORPORATED
Customer Legal Name:	Ke Comet Austin, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/2004
Affiliation End Date:	8/31/2014
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Regulated Entity Number:	RN100712744
Name:	STAR BRITE CLEANERS
Address:	9515 N LAMAR BLVD STE 108
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-4136
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602477176
Customer Name:	COMET ONE-HOUR CLEANERS
Customer Legal Name:	Comet One-Hour Cleaners
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
56 additional TX CENTRAL REG: record(s) in the EDR Site Report.

QJ2851 **MCBRIDES GUNS** **TX Ind. Haz Waste** **S102748684**
WNW **2913 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.117 mi.
620 ft. **Site 2 of 2 in cluster QJ**

Actual:
570 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	MCBRIDES GUNS
Address:	2913 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	61835
Registration Initial Notification Date:	09/30/1985

MCBRIDES GUNS (Continued) **S102748684**

Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	2913 N Lamar, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	MCBRIDES GUNS INC
Contact Name:	MR HAMILTON
Contact Telephone Number:	Not reported
Mailing Address:	2913 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787053516
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20175
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	MCBRIDES GUNS INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17419004159

MCBRIDES GUNS (Continued) **S102748684**

Operator Bankruptcy Code: Not reported

Ind. Haz Waste:
Owner Name: MCBRIDES GUNS INC
Owner Mailing Address: 2913 N LAMAR BLVD
Owner Mailing Address 2: Not reported
Owner Mailing Address 3: Not reported
Owner Mailing City,State,Zip: AUSTIN, TX 78705
Owner Country: UNITED STA
Owner Telephone: Not reported
Owner Fax: Not reported
Owner Email Address: Not reported
Owner Business Type: Unknown
Owner Tax ID: 17419004159
Owner Bankruptcy Code: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 2913 N LAMAR BLVD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78705
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: MR HAMILTON
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 2913 N LAMAR BLVD
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78705
Contact Phone: Not reported
Contact Fax: Not reported
Contact Email: Not reported

CENTRAL REGISTRY:
Regulated Entity Number: RN100605302
Name: MCBRIDES GUNS
Address: 2913 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78705-3516
Status: ACTIVE
Status Date: ##########
Customer Number: CN600314835
Customer Name: MCBRIDES GUNS INC
Customer Legal Name: McBride's Guns, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported

MCBRIDES GUNS (Continued) **S102748684**

Primary NAICS Industry Type Description: Not reported
Physical Location Description: 2913 N Lamar, Austin, TX

2852 East < 1/8 0.117 mi. 620 ft. **CENTRAL FREIGHT LINES 901 E 4TH ST AUSTIN, TX** **TX HIST UST** **S111678600 N/A**

Actual: 468 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CENTRAL FREIGHT LINES
Address:	901 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0336
HID UST:	336
Inspection:	02/03/2009
Due:	02/03/2012

QR2853 SE < 1/8 0.118 mi. 621 ft. **BRITISH MOTOR CAR SERVICE 617 W POWELL LN # A AUSTIN, TX 78753** **TX Ind. Haz Waste TX CENTRAL REGISTRY** **S102750521 N/A**

Site 2 of 3 in cluster QR

Actual: 731 ft.
Focus Map: 6

Ind. Haz Waste:

Name:	BRITISH MOTOR CAR SERVICE
Address:	617 W POWELL LN # A
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	67321
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	02/14/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	617 Powell Ln, No A, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	BRITISH MOTOR CAR SERVICE
Contact Name:	ALBERT HUTCHINSON
Contact Telephone Number:	Not reported
Mailing Address:	617 POWELL LN NO A
Mailing Address2:	NO A

BRITISH MOTOR CAR SERVICE (Continued) **S102750521**

Mailing City,State,Zip:	AUSTIN, TX 78753
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22449
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021018
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	BRITISH MOTOR CAR SERVICE
Operator Address:	617 W POWELL LN # A
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BRITISH MOTOR CAR SERVICE
Owner Mailing Address:	617 W POWELL LN # A
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	617 W POWELL LN # A
Contact Address 2:	Not reported
Contact Address 3:	Not reported

BRITISH MOTOR CAR SERVICE (Continued) **S102750521**

Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	617 W POWELL LN # A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	ALBERT HUTCHINSON
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	617 POWELL LN NO A
Contact Address 2:	NO A
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100843481
Name:	BRITISH MOTOR CAR SERVICE
Address:	617 W POWELL LN # A
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-5909
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521595
Customer Name:	BRITISH MOTOR CAR SERVICE
Customer Legal Name:	British Motor Car Service
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	617 Powell Ln, No A, Austin, TX

PD2854 **LES & MACS SERV** **EDR Hist Auto** **1013771506**
ESE **301 15TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.118 mi.
623 ft. **Site 5 of 5 in cluster PD**

Actual:
513 ft.
EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1947	BLAKESLE SERV STA	GASOLINE AND OIL SERVICE STATIONS

LES & MACS SERV (Continued) **1013771506**

1953 LES & MACS SERV GASOLINE STATIONS

QR2855 **B CAMERON AUTOMOTIVE** **EDR Hist Auto** **1013768344**
SE **611 POWELL LN W** **N/A**
< 1/8 **AUSTIN, TX 78753**
0.118 mi.
623 ft. **Site 3 of 3 in cluster QR**

Actual:
729 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1980	B CAMERON AUTOMOTIVE	AUTOMOBILE REPAIRING

2856 **STANFORD GUY REPR SHOP** **EDR Hist Auto** **1013755545**
ESE **508 JOAN OF ARC** **N/A**
< 1/8 **AUSTIN, TX**
0.119 mi.
628 ft.

Actual:
658 ft.

EDR Hist Auto

Focus Map:
6

Year:	Name:	Type:
1962	STANFORD GUY REPR SHOP	REPAIR SHOPS

2857 **RUTLAND AUTO PARTS** **EDR Hist Auto** **1013755254**
ENE **1127 BASTROP HWY** **N/A**
< 1/8 **AUSTIN, TX 78741**
0.120 mi.
633 ft.

Actual:
461 ft.

EDR Hist Auto

Focus Map:
16

Year:	Name:	Type:
1980	RUTLAND AUTO PARTS	AUTOMOBILE REPAIRING
2009	LIMONS ROAD SERVICE	General Automotive Repair Shops
2010	LIMONS ROAD SERVICE	General Automotive Repair Shops
2011	LIMONS ROAD SERVICE	General Automotive Repair Shops
2012	LIMONS ROAD SERVICE	General Automotive Repair Shops

PT2858 **TXDOT RIGHT OF WAY** **TX RDR** **S127543731**
ESE **S MLK & E SAN JACINTO** **N/A**
< 1/8 **AUSTIN, TX**
0.120 mi.
636 ft. **Site 2 of 3 in cluster PT**

Actual:
507 ft.

RDR:

Focus Map:
11

RDR ID:	16511
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	TXDOT RIGHT OF WAY
Address:	S MLK & E SAN JACINTO
City,State,Zip:	AUSTIN, TX

TXDOT RIGHT OF WAY (Continued) **S127543731**

Date Report Received:	9/11/2007
Due Date:	11/10/2007
Tank Owner:	TXDOT
Contact Person:	MR DANNY JACKSON
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	11/30/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED AN LPST #?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	11/30/2007
Region:	Not reported
DKC RDR (misfiled):	Not reported

PT2859 **TX DOT ROW** **TX TANKS** **S126846819**
ESE **E MARTIN LUTHER KING JR BLVD & SAN JACINTO BLVD** **TX CENTRAL REGISTRY** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.120 mi.
636 ft. **Site 3 of 3 in cluster PT**

Actual:
507 ft.

Focus Map:
11

TANKS:

Facility ID:	127118
Name:	TX DOT ROW
Address:	E MARTIN LUTHER KING JR BLVD & SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Total UST:	0
Additional ID:	988488322012320
AI Number:	82871
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Site Location Description:	E MARTIN LUTHER KING JR BLVD & SAN JACINTO BLVD
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,

TX DOT ROW (Continued) **S126846819**

Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN106550692
Name:	TX DOT ROW
Address:	E MARTIN LUTHER KING JR BLVD & SAN JACINTO BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	11/15/2012
Customer Number:	CN600803456
Customer Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Customer Legal Name:	Texas Department of Transportation
Customer Ownership Type:	STATE GOVERNMENT
Affiliation Begin Date:	4/18/2007
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	E MARTIN LUTHER KING JR BLVD & SAN JACINTO BLVD

QT2860 **H.A. GUERRERO CARPET CLEANERS** **TX HIST UST** **S128729121**
West **2313 S 1ST ST** **N/A**
< 1/8 **AUSTIN, TX**
0.121 mi.
640 ft. **Site 1 of 3 in cluster QT**

Actual:
531 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	H.A. GUERRERO CARPET CLEANERS
Address:	2313 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0693
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QT2861 **H A GUERRO CARPET CLEANER** **TX RDR** **S127542783**
West **2313 S 1ST** **N/A**
< 1/8 **AUSTIN, TX**
0.121 mi.
640 ft. **Site 2 of 3 in cluster QT**

Actual:
531 ft.

Focus Map:
14

RDR:

RDR ID:	10880
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	H A GUERRO CARPET CLEANER
Address:	2313 S 1ST

H A GUERRO CARPET CLEANER (Continued) **S127542783**

City,State,Zip:	AUSTIN, TX
Date Report Received:	6/2/2003
Due Date:	8/1/2003
Tank Owner:	H A GUERRO
Contact Person:	H A GUERRO
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	4/20/2004
Project Manager:	Joe Brown
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR ORIG RECD 12/19/01. DRAFT RTN LTR TO JES 4/12/04
Review Coordinator:	JHB
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	4/20/2004
Region:	Not reported
DKC RDR (misfiled):	Not reported

2862 **PRIME MOBILE LUBE** **RCRA NonGen / NLR** **1005418450**
NNE **1405 MONTOPOLIS DRIVE** **FINDS** **TXR000041160**
< 1/8 **AUSTIN, TX 78741** **ECHO**
0.121 mi.
641 ft.

Actual:
493 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20010517
Handler Name:	Prime Mobile Lube
Handler Address:	MONTOPOLIS DRIVE
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXR000041160
Contact Name:	COLETTE E MAYFIELD
Contact Address:	1405 MONTOPOLIS DRIVE
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Telephone:	512-385-1111
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	MONTOPOLIS DRIVE
Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Name:	Colette And Jerrold Mayfield
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

PRIME MOBILE LUBE (Continued) **1005418450**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20010518
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COLETTE AND JERROLD MAYFIELD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1405 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-385-1111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20010301
Handler Name:	PRIME MOBILE LUBE

PRIME MOBILE LUBE (Continued) **1005418450**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010517
Handler Name: PRIME MOBILE LUBE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012256012

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1005418450
Registry ID:	110012256012
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012256012
Name:	PRIME MOBILE LUBE
Address:	1405 MONTOPOLIS DRIVE

PRIME MOBILE LUBE (Continued) **1005418450**

City,State,Zip: AUSTIN, TX 78741

QD2863 **DEATHE TEXACO SERV** **EDR Hist Auto** **1013754845**
ESE **1701 SAN JACINTO** **N/A**
< 1/8 **AUSTIN, TX**
0.122 mi.
642 ft. **Site 3 of 5 in cluster QD**

Actual:
509 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	YOUNG & SCHIEFFER FILL ST	AUTOMOBILE REPAIRERS
1947	WEEDOM COOKE SERV STA	GASOLINE AND OIL SERVICE STATIONS
1953	DEATHE TEXACO SERV	GASOLINE STATIONS
1958	JACKSON SERV STA	GASOLINE STATIONS

QD2864 **STATE PURCHASING AND GENERAL SERVICES COMMISSION** **TX ASBESTOS** **S102755935**
ESE **1711 SAN JACINTO BLVD STE 105** **TX Ind. Haz Waste** **N/A**
< 1/8 **AUSTIN, TX 78701**
0.122 mi.
642 ft. **Site 4 of 5 in cluster QD**

Actual:
508 ft.

Focus Map:
11

ASBESTOS:

Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	03/11/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	02/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/14/2022
Certification Statement Phone:	512-446-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Robert Abbott
Violation:	Not reported
Complaint Date:	03/23/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Date Report Received:	03/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/08/2022
Certification Statement Phone:	512-466-7293
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Carlos Hung
Violation:	Not reported
Complaint Date:	03/25/2022

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/18/2022
Certification Statement Phone:	512-820-9659
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	03/08/2022
Reason for Inspection:	Carlos Hung
Violation:	Not reported
Complaint Date:	03/03/2022
Notification Number:	2022000816
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	01/31/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/31/2022
Certification Statement Phone:	512-820-9659
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/14/2022
Client Code:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TFC CENTRAL SERVICES BUILDING
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/08/2021
Notification Number:	2021002660
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/30/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/30/2021
Certification Statement Phone:	512-260-7171

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/08/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TFC CENTRAL SERVICES BUILDING
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/07/2021
Notification Number:	2021002660
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/22/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/22/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/06/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/03/08
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/08/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022000816
File Number:	68891
License Status Description:	Current
Expiration Date:	03/25/2022
Original Date:	01/31/2022
Rank Effective Date:	01/31/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	31632
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Name:	TEXAS FACILITIES COMMISSION
Address:	1711 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/02/22
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	02/22/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022000816
File Number:	68891
License Status Description:	Current
Expiration Date:	03/25/2022
Original Date:	01/31/2022

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Rank Effective Date:	01/31/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	31693
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	STATE PURCHASING AND GENERAL SERVICES COMMISSION
Address:	1711 SAN JACINTO BLVD STE 105
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	74655
Registration Initial Notification Date:	11/03/1988
Registration Last Amendment Date:	01/14/2002
EPA Identification:	TXD982559908
Primary NAICS Code:	Not reported
Status Change Date:	19881103
Land Type:	Not reported
Description of Facility Site Location:	1711 San Jacinto Blvd, Ste 105, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	STATE PURCHASING & GENERAL SERVICES
Contact Name:	JESSE WILLIAMS
Contact Telephone Number:	512-4633345
Mailing Address:	PO BOX 13047
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787113047
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	29024
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	STATE PURCHASING & GENERAL SERVICES
Operator Address:	PO BOX 13047
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78711
Operator Country:	UNITED STA
Operator Telephone:	1-512-4633345
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	STATE PURCHASING & GENERAL SERVICES
Owner Mailing Address:	PO BOX 13047
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78711
Owner Country:	UNITED STA
Owner Telephone:	1-512-4633345
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633345
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633345

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JESSE WILLIAMS
Contact Title:	ENVIRONMENTAL CONTACT
Contact Role:	PRICONT
Contact Address:	PO BOX 13047
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Phone:	1-512-4633345
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 13047
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78711
AR Number:	0000308017
Principal Name:	STATE PURCHASING & GENERAL SERVICES
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 13047
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78711
AR Number:	0000308017
Principal Name:	STATE PURCHASING & GENERAL SERVICES
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 13047
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78711
AR Number:	0000308017
Principal Name:	STATE PURCHASING & GENERAL SERVICES
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 13047
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78711
AR Number:	0000308017
Principal Name:	STATE PURCHASING & GENERAL SERVICES
Attention Name:	Not reported

STATE PURCHASING AND GENERAL SERVICES COMMISSION (Continued) **S102755935**

Attention Suffix: NWF

QD2865 **STATE PURCHASING AND GENERAL SERVICES CO** **RCRA NonGen / NLR** **1000412215**
ESE **1711 SAN JACINTO BLVD STE 105** **FINDS** **TXD982559908**
< 1/8 **AUSTIN, TX 78701** **ECHO**
0.122 mi.
642 ft. **Site 5 of 5 in cluster QD**

Actual:
508 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20020114
Handler Name:	State Purchasing And General Services Co
Handler Address:	SAN JACINTO BLVD STE 105
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD982559908
Contact Name:	JESSE WILLIAMS
Contact Address:	PO BOX 13047
Contact City,State,Zip:	AUSTIN, TX 78711
Contact Telephone:	512-463-3345
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 13047
Mailing City,State,Zip:	AUSTIN, TX 78711
Owner Name:	State Purchasing And General Services Co
Owner Type:	Not reported
Operator Name:	State Purchasing And General Services Co
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

STATE PURCHASING AND GENERAL SERVICES CO (Continued) **1000412215**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PURCH & GEN SERV COMM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: STATE PURCHASING AND GENERAL SERVICES CO	
Legal Status:	Not reported
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 13047
Owner/Operator City,State,Zip:	AUSTIN, TX 78711
Owner/Operator Telephone:	512-463-3345
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE PURCHASING AND GENERAL SERVICES CO	
Legal Status:	Not reported
Date Became Current:	20020114
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 13047

STATE PURCHASING AND GENERAL SERVICES CO (Continued) **1000412215**

Owner/Operator City,State,Zip: AUSTIN, TX 78711
Owner/Operator Telephone: 512-463-3345
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19881109
Handler Name: AUSTIN STATE PUR & GEN SVC ADMIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020114
Handler Name: STATE PURCHASING AND GENERAL SERVICES CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005109596

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

STATE PURCHASING AND GENERAL SERVICES CO (Continued) **1000412215**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412215
Registry ID:	110005109596
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005109596
Name:	STATE PURCHASING AND GENERAL SERVICES CO
Address:	1711 SAN JACINTO BLVD STE 105
City,State,Zip:	AUSTIN, TX 78701

QU2866 **SMITH J E R** **EDR Hist Cleaner** **1013783590**
ESE **305 13TH E** **N/A**
< 1/8 **AUSTIN, TX**
0.122 mi.
643 ft. **Site 1 of 2 in cluster QU**

Actual:
533 ft.

EDR Hist Cleaner

Focus Map:
11

Year:	Name:	Type:
1922	SMITH J E R	CLOTHES CLEANERS AND PRESSERS

QK2867 **SAN JACINTO GARAGE** **EDR Hist Auto** **1013767417**
ESE **1511 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.122 mi.
643 ft. **Site 4 of 4 in cluster QK**

Actual:
512 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1940	SCHIEFFER CLARENCE	AUTOMOBILE REPAIRING
1947	SCHIEFFER CLARENCE GARAGE	AUTOMOBILE REPAIRING
1953	SCHIEFFER CLARENCE	AUTOMOBILE REPAIRING
1958	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING
1962	SAN JACINTO GARAGE	AUTOMOBILE REPAIRING
1965	SAN JACINTO GARAGE AUTO	AUTOMOBILE REPAIRING
1969	SAN JACINTO GARAGE	General Automotive Repair Shops
1970	SAN JACINTO GARAGE	General Automotive Repair Shops

QC2868 **TETCO #1167** **TX RDR** **S127525774**
ENE **717 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.122 mi.
644 ft. **Site 7 of 12 in cluster QC**

Actual:
471 ft.

RDR:

Focus Map:
11

RDR ID:	1307
Facility ID:	17721
RN:	Not reported
CN:	Not reported
Name:	TETCO #1167
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX

TETCO #1167 (Continued) **S127525774**

Date Report Received:	7/8/1999
Due Date:	9/6/1999
Tank Owner:	TETCO STORES LP
Contact Person:	MICHAEL K GARROTT
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/10/1999
Project Manager:	Cardellia Anderson
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	CAA
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/10/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

QC2869 **MOBIL OIL 00AFT** **RCRA NonGen / NLR** **1000653996**
ENE **717 E 7TH ST** **TXD988038402**
< 1/8 **AUSTIN, TX 78701**
0.122 mi.
644 ft. **Site 8 of 12 in cluster QC**

Actual:
471 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20200615
Handler Name:	Mobil Oil 00aft
Handler Address:	717 E 7TH ST
Handler City,State,Zip:	AUSTIN, TX 78701-3306
EPA ID:	TXD988038402
Contact Name:	ROBIN BUNN
Contact Address:	3225 GALLOWS RD
Contact City,State,Zip:	FAIRFAX, VA 22037-0002
Contact Telephone:	703-849-3330
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3225 GALLOWS RD
Mailing City,State,Zip:	FAIRFAX, VA 22037-0002
Owner Name:	Mobil Oil Corporation
Owner Type:	Private
Operator Name:	Mobil Oil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

MOBIL OIL 00AFT (Continued) **1000653996**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200709
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 E GALLOWS RD

MOBIL OIL 00AFT (Continued) **1000653996**

Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037-0002
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 E GALLOWS ROAD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORP MKTG ENVIRON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037-0002
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private

MOBIL OIL 00AFT (Continued) **1000653996**

Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037-0002
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	3225 GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037-0002
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	3225 E GALLOWS ROAD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	703-849-3330
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOBIL OIL CORPORATION	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	3225 E GALLOWS RD
Owner/Operator City,State,Zip:	FAIRFAX, VA 22037
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19910501
Handler Name: MOBIL OIL CORP SS# AF7	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

MOBIL OIL 00AFT (Continued) **1000653996**

Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: MOBIL OIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: MOBIL OIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200615
Handler Name: MOBIL OIL 00AFT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200615
Handler Name: MOBIL OIL 00AFT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42311
NAICS Description: AUTOMOBILE AND OTHER MOTOR VEHICLE MERCHANT WHOLESALERS

MOBIL OIL 00AFT (Continued) **1000653996**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

QC2870 **7-ELEVEN 36422** **TX UST** **U001252741**
ENE **717 E 7TH ST** **TX HIST UST** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX ENF**
0.122 mi. **TX Financial Assurance**
644 ft. **Site 9 of 12 in cluster QC** **TX RDR**

Actual:
471 ft.

Focus Map:
11

UST:

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 787013306
AI Number:	17721
Facility Type:	RETAIL
Facility Begin Date:	09/01/1989
Facility Status:	ACTIVE
Additional ID:	975573522003345
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	PEGGIE BETZ,ENV SPEC
Contact Organization Name:	7-ELEVEN 36422
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/21/2013
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,
Application Received Date On Earliest Reg Form:	11/25/2013
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	528583882003345
Additional ID:	975573522003345
Ai Number:	17721
Operator CN:	CN602519811
Operator Name:	AKBAR S MOMIN
Operator Effective Begin Date:	06/01/1998
Operator Type:	IN
Operator Role:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	975573522003345
AI Number:	17721
Owner Effective Begin Date:	11/01/2012
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	95647
Cert ID:	381723
AI Number:	17721
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	364401
AI Number:	17721
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	347200
AI Number:	17721
Self Certification Date:	01/12/2021
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	331181
AI Number:	17721
Self Certification Date:	01/10/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	314468
AI Number:	17721
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	296036
AI Number:	17721
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	280729
AI Number:	17721
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	263529
AI Number:	17721
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	247068
AI Number:	17721
Self Certification Date:	01/16/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	95647
Cert ID:	230851
AI Number:	17721
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	95647
Cert ID:	153224
AI Number:	17721
Self Certification Date:	11/13/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153223
AI Number:	17721
Self Certification Date:	11/12/2012
Signature Name/Title:	SCOTT JOHNSON GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153222
AI Number:	17721
Self Certification Date:	09/30/2012
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153221
AI Number:	17721
Self Certification Date:	10/03/2011
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153220
AI Number:	17721
Self Certification Date:	09/30/2010
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153219
AI Number:	17721
Self Certification Date:	10/01/2009
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153218
AI Number:	17721
Self Certification Date:	07/02/2008
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153217
AI Number:	17721
Self Certification Date:	07/01/2008
Signature Name/Title:	RAYMOND MCNIECE ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153216
AI Number:	17721
Self Certification Date:	09/30/2007
Signature Name/Title:	RAYMOND MCNIECE ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2008
Reporting Method:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153215
AI Number:	17721
Self Certification Date:	09/18/2006
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153214
AI Number:	17721
Self Certification Date:	09/28/2005
Signature Name/Title:	RAYMOND MCNIECE ENV MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153213
AI Number:	17721
Self Certification Date:	09/30/2004
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153212
AI Number:	17721
Self Certification Date:	09/23/2003
Signature Name/Title:	RAYMOND MCNIECE ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153211
AI Number:	17721
Self Certification Date:	09/09/2002
Signature Name/Title:	AKBAR S MOMIN OPERATOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	95647
Cert ID:	153210
AI Number:	17721
Self Certification Date:	01/16/2001
Signature Name/Title:	MICHAEL K GARROTT, SR ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	45612
Facility ID:	95647
Ai Number:	17721
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

7-ELEVEN 36422 (Continued) **U001252741**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	163236
UST ID:	45612
AI Number:	17721
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1989

Install Date:	01/01/1989

7-ELEVEN 36422 (Continued) **U001252741**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	45611
Facility ID:	95647
Ai Number:	17721
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

7-ELEVEN 36422 (Continued) **U001252741**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	163235
UST ID:	45611
AI Number:	17721
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1989

Install Date:	01/01/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	45613
Facility ID:	95647

7-ELEVEN 36422 (Continued) **U001252741**

Ai Number:	17721
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	163237

7-ELEVEN 36422 (Continued) **U001252741**

UST ID:	45613
AI Number:	17721
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1989

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	45610
Facility ID:	95647
Ai Number:	17721
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

7-ELEVEN 36422 (Continued) **U001252741**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	163234
UST ID:	45610
AI Number:	17721
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

7-ELEVEN 36422 (Continued) **U001252741**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	45607
Facility ID:	95647
Ai Number:	17721
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

7-ELEVEN 36422 (Continued) **U001252741**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	1A
Tank Capacity:	4000
UST Comprt ID:	163231
UST ID:	45607
AI Number:	17721
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

7-ELEVEN 36422 (Continued) **U001252741**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	45608
Facility ID:	95647
Ai Number:	17721
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

7-ELEVEN 36422 (Continued) **U001252741**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	3A
Tank Capacity:	10000
UST Comprt ID:	163232
UST ID:	45608
AI Number:	17721
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

7-ELEVEN 36422 (Continued) **U001252741**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	45609
Facility ID:	95647
Ai Number:	17721
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

7-ELEVEN 36422 (Continued) **U001252741**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/26/1993

Compartment Records:

Tank ID:	2A
Tank Capacity:	8000
UST Comprt ID:	163233
UST ID:	45609
AI Number:	17721
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

7-ELEVEN 36422 (Continued) **U001252741**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1988
Tank Registration Date:	02/20/1997
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	182753
Facility ID:	95647
Ai Number:	17721
Tank Id:	4A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/14/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7-ELEVEN 36422 (Continued) **U001252741**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4A
Tank Capacity:	1000
UST Comprt ID:	163238
UST ID:	182753
AI Number:	17721
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Construction Notification:

NOC ID:	37342
Facility ID:	95647
AI Number:	17721
Application Received Date:	11/20/2020
Scheduled Construction Date:	11/23/2020
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	Not reported

NOC ID:	15647
Facility ID:	95647
AI Number:	17721
Application Received Date:	09/22/2008
Scheduled Construction Date:	09/22/2008
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M80922007
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	24251

7-ELEVEN 36422 (Continued) **U001252741**

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	88625
UST ID:	Not reported
NOC ID:	37342
AI Number:	17721
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	KIM TAPIA
Mailing Address (Delivery):	12005 FORD RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75234
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	7738400
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	0
Fax Number:	0
Email Address:	KTAPIA@MCCONBUILDING.COM

Cont/Cons/Installer ID:	16783
UST ID:	Not reported
NOC ID:	15647
AI Number:	17721
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001391
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	88626
UST ID:	Not reported
NOC ID:	37342
AI Number:	17721
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100

7-ELEVEN 36422 (Continued) **U001252741**

Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	NLAWSON@MCCONBUILDING.COM

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	95647
Additional ID:	975573522003345
Princ ID:	959578622001257
AI Number:	17721
Facility Name:	7-ELEVEN 36422
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	7-ELEVEN STORE #36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	715
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ENFORCEMENT:

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701-3306
Unique TCEQ Ref Number Of Customer:	CN600240329
Unique TCEQ Ref Number Of Reg. Entity:	RN104081229
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	7-ELEVEN INC

7-ELEVEN 36422 (Continued) **U001252741**

Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001293710
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	888,610,592,016,005.00
Role Code:	Not reported
Date Notice Of Violation Issued:	01/11/2016
Description 1:	Failure to comply with annual Stage I vapor recovery testing requirements.
Description 2:	On January 27 and February 10, 2016, Stage I vapor recovery equipment was tested and passed. The results of CARB Vapor Recovery Test Procedure TP 201.3 and TP 201.1E were submitted to the investigator.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	115.225
Status Of The NOV:	DAPPROVED
Investigation:	1293710
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701-3306
Unique TCEQ Ref Number Of Customer:	CN600240329
Unique TCEQ Ref Number Of Reg. Entity:	RN104081229
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	7-ELEVEN INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001293710
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	888,610,592,016,005.00
Role Code:	Not reported
Date Notice Of Violation Issued:	01/11/2016
Description 1:	Failure to provide proper corrosion protection (CP) for the UST system. Specifically, the metal components in the submersible turbine

7-ELEVEN 36422 (Continued) **U001252741**

	pump (STP) containment sumps were in contact with water and some metal components under the dispensers were in contact with backfill material.
Description 2:	On December 17, 2015, documentation was received demonstrating that the metal components are now protected from corrosion. On November 20, 2015, anodes were installed in each STP containment sump and under each dispenser.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.49(a)(4)
Status Of The NOV:	DAPPROVED
Investigation:	1293710
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

TX Financial Assurance 2:

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	278848
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	261699

7-ELEVEN 36422 (Continued) **U001252741**

AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	241719
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	223659
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018

7-ELEVEN 36422 (Continued) **U001252741**

Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	224259
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	207418
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN 36422 (Continued) **U001252741**

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	188945
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	173354
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	154501
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 36422 (Continued) **U001252741**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	137942
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	120957
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported

7-ELEVEN 36422 (Continued) **U001252741**

Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	8776
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79723
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2011
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	001215401
Coverage Amount:	2000000
Coverage Expiration Date:	12/01/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701

7-ELEVEN 36422 (Continued) **U001252741**

Region:	2
Facility ID:	95647
Finass ID:	79722
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2012
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235400
Coverage Amount:	1000000
Coverage Expiration Date:	12/18/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79724
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/01/2009
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	000026400
Coverage Amount:	1000000
Coverage Expiration Date:	12/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79725
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN 36422 (Continued) **U001252741**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8058109
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79727
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 877 2546564
Policy Number:	ST8067698
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79726
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	AMERICAN INTL SPECIALTY LINES
Issuer Phone:	1 800 5536938
Policy Number:	ST8057698
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2008

7-ELEVEN 36422 (Continued) **U001252741**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79728
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2006
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 0 0
Policy Number:	USC 9220603 00
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2007
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	95647
Finass ID:	79729
AI:	17721
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/1993
Date Financial Assurance Form Rec:	11/25/2013
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	32437
Facility ID:	17721
RN:	104081229
CN:	600240329
Name:	7-ELEVEN STORE NO 36422

7-ELEVEN 36422 (Continued) **U001252741**

Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/23/2022
Due Date:	2/21/2023
Tank Owner:	7-ELEVEN INC
Contact Person:	SAMANTHA KRAMER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	2/17/2023
Project Manager:	Rodney Bryant
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

QC2871 **MOBIL OIL 00AFT** **TX LPST** **S104854997**
ENE **717 E 7TH ST** **TX ASBESTOS** **N/A**
< 1/8 **AUSTIN, TX 78701** **TX Ind. Haz Waste**
0.122 mi.
644 ft. **Site 10 of 12 in cluster QC**

Actual:
471 ft.

Focus Map:
11

LPST:

Name:	TETCO 1167
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0017721
LPST Id:	107633
Facility Location:	717 E 7TH ST & IH 17 E 7TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/26/1993
Entered Date:	02/24/1995
Reported Date:	03/31/1993
Closure Date:	08/07/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	EAE
Responsible Party Name:	Not reported
Responsible Party Contact:	BRUCE MORLOCK
Responsible Party Address:	4200 SINGLETON BLVD
Responsible Party City,St,Zip:	DALLAS, TX 75212
Responsible Party Telephone:	214/905-0506
Reported Date:	03/31/1993
Case Start Date:	08/07/1997
Reference Number:	RN104081229
Project Manager:	EEKPO

MOBIL OIL 00AFT (Continued) **S104854997**

ASBESTOS:

Name:	MOBIL FOOD MART
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	04/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.5
Reg:	07
Init:	EJ
Seq:	07
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported

MOBIL OIL 00AFT (Continued) **S104854997**

Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	MOBIL OIL 00AFT
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	80296
Registration Initial Notification Date:	07/28/1992
Registration Last Amendment Date:	11/10/2020
EPA Identification:	TXD988038402
Primary NAICS Code:	423110
Status Change Date:	19920728
Land Type:	PRIVATE
Description of Facility Site Location:	717 E 7TH AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXONMOBIL OIL CORPORATION
Contact Name:	ROBIN A BUNN
Contact Telephone Number:	703-8493330
Mailing Address:	3225 GALLOWS RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	FAIRFAX, VA 220370002
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	35008
Site Owner Tax ID:	135401570
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20201110
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported

MOBIL OIL 00AFT (Continued) **S104854997**

Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXONMOBIL OIL CORPORATION
Operator Address:	3225 GALLOWS RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	FAIRFAX, VA 22037
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354015700
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXONMOBIL OIL CORPORATION
Owner Mailing Address:	3225 GALLOWS RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	FAIRFAX, VA 22037
Owner Country:	UNITED STA
Owner Telephone:	1-703-8493330
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354015700
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported

MOBIL OIL 00AFT (Continued) **S104854997**

System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19920728
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8493330
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ROBIN BUNN
Contact Title:	MANAGER
Contact Role:	PRICONT
Contact Address:	3225 GALLOWS RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	FAIRFAX, VA 22037
Contact Phone:	1-703-8493330
Contact Fax:	Not reported
Contact Email:	Not reported

QC2872 **WALSH SERVICE CENTER** **EDR Hist Auto** **1013755659**
ENE **717 E 7TH ST** **N/A**
< 1/8 **TRAVIS (County), TX 78701**
0.122 mi.
644 ft. **Site 11 of 12 in cluster QC**

Actual:
471 ft. EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1970	WALSH SERVICE CENTER	GASOLINE STATIONS
1975	WALSH SERVICE CENTER	Gasoline Service Stations
1976	WALSH SERVICE CENTER	Gasoline Service Stations

WALSH SERVICE CENTER (Continued) **1013755659**

1977	WALSH SERVICE CENTER	Gasoline Service Stations
1978	WALSH SERVICE CENTER	Gasoline Service Stations
1979	TRIAD GROUP	Gasoline Service Stations
1980	TRIAD GROUP	Gasoline Service Stations
1982	WALSH SERVICE CENTER	Gasoline Service Stations
1987	TOWNE LAKE MOBILE	Gasoline Service Stations
1988	TOWNE LAKE MOBILE	Gasoline Service Stations
1989	TOWNE LAKE MOBILE	Gasoline Service Stations
1990	TOWNE LAKE MOBILE	Gasoline Service Stations
1991	TOWNE LAKE MOBILE	Gasoline Service Stations
1992	TOWNE LAKE MOBILE	Gasoline Service Stations
1996	7TH ST MOBIL	Gasoline Service Stations
1997	7TH ST MOBIL	Gasoline Service Stations
1998	7TH ST MOBIL	Gasoline Service Stations

QC2873 **7-ELEVEN INC STORE NO 36422** **TX RDR** **S127525773**
ENE **717 E 7TH ST** **N/A**
< 1/8 **AUSTIN, TX**
0.122 mi.
644 ft. **Site 12 of 12 in cluster QC**

Actual:
471 ft.

Focus Map:
11

RDR:

RDR ID:	29603
Facility ID:	17721
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN INC STORE NO 36422
Address:	717 E 7TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/25/2021
Due Date:	3/26/2021
Tank Owner:	7-ELEVEN INC
Contact Person:	SHELLENA HUSSEIN
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/25/2021
Project Manager:	Ryan Kraft
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

QV2874 ESE < 1/8 0.122 mi. 644 ft. — **CULLEN SERVICE STA**, **1407 SAN JACINTO**, **AUSTIN, TX** — **EDR Hist Auto** — **1013775085** / **N/A**

Site 1 of 2 in cluster QV

Actual: 515 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1940	CULLEN SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

QV2875 ESE < 1/8 0.122 mi. 644 ft. — **EMMETT SINCLAIR SERVICE**, **1409 SAN JACINTO ST**, **AUSTIN, TX** — **EDR Hist Auto** — **1013766123** / **N/A**

Site 2 of 2 in cluster QV

Actual: 514 ft.

Focus Map: 11

EDR Hist Auto

Year:	Name:	Type:
1958	MAINOUS ED SINTERSECTS	GASOLINE STATIONS
1962	E&R SINCLAIR SERV	GASOLINE STATIONS
1965	EMMETT SINCLAIR SERVICE	GASOLINE STATIONS
1970	JOHNSONS BILL TEXACO SERVICE ST	GASOLINE STATIONS

QG2876 ESE < 1/8 0.122 mi. 646 ft. — **BANNER SIGNS**, **650 CANION ST**, **AUSTIN, TX 78752** — **TX Ind. Haz Waste** / **TX CENTRAL REGISTRY** — **S103612273** / **N/A**

Site 2 of 2 in cluster QG

Actual: 708 ft.

Focus Map: 6

Ind. Haz Waste:

Name:	BANNER SIGNS
Address:	650 CANION ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	82546
Registration Initial Notification Date:	02/15/1994
Registration Last Amendment Date:	02/14/2001
EPA Identification:	Not reported
Primary NAICS Code:	339950
Status Change Date:	19940215
Land Type:	Not reported
Description of Facility Site Location:	650 Canion, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	PAPST, JEFF

BANNER SIGNS (Continued) **S103612273**

Contact Name:	NITA F BROWN
Contact Telephone Number:	512-4585348
Mailing Address:	650 CANION
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 78757
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	98552
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040426
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	JEFF PAPST
Operator Address:	650 CANION ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	JEFF PAPST
Owner Mailing Address:	650 CANION ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	JEFF PAPST
Contact Title:	Not reported

BANNER SIGNS (Continued) **S103612273**

Contact Role:	OPRCON
Contact Address:	650 CANION ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JEFF PAPST
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	650 CANION ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	NITA BROWN
Contact Title:	PRODUCTION MGR
Contact Role:	PRICONT
Contact Address:	650 CANION
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4585348
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	92535
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste petroleum naphtha, circulating parts washer, 1-2-92
Standard Industrial Code:	39930
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	339950
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

BANNER SIGNS (Continued) **S103612273**

CENTRAL REGISTRY:

Regulated Entity Number:	RN100550755
Name:	BANNER SIGNS
Address:	650 CANION ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3510
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600261721
Customer Name:	PAPST, JEFF
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	9/26/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	339950
Primary NAICS Industry Type Description:	Sign Manufacturing
Physical Location Description:	650 Canion, Austin, TX

Regulated Entity Number:	RN100550755
Name:	BANNER SIGNS
Address:	650 CANION ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3510
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600261721
Customer Name:	PAPST, JEFF
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	9/26/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	339950
Primary NAICS Industry Type Description:	Sign Manufacturing
Physical Location Description:	650 Canion, Austin, TX

QW2877 **TEXAS ALLERGY & ASTHMA CENTER** **TX UST** **U001290059**
NW **4150 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX 78756**
0.123 mi.
647 ft. **Site 1 of 3 in cluster QW**

Actual:
635 ft.

Focus Map:
8

UST:

Name:	TEXAS ALLERGY & ASTHMA CENTER
Address:	4150 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787563716
AI Number:	60525
Facility Type:	OTHER
Facility Begin Date:	10/22/1991
Facility Status:	INACTIVE
Additional ID:	70146672002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	,
Contact Organization Name:	TEXAS ALLERGY & ASTHMA CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124670978
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/14/1991
Signature Name/Title On Earliest Reg Form:	ROBERT D COOK,OWNER
Application Received Date On Earliest Reg Form:	10/17/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601206972
Owner Last Name:	COOK
Owner First Name:	ROBERT
Owner Middle Name:	D
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	79146662002139
Additional ID:	70146672002139
AI Number:	60525
Owner Effective Begin Date:	10/22/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/17/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142295
Facility ID:	90921

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Ai Number:	60525
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1991
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	140210

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

UST ID:	142295
AI Number:	60525
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/17/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142296
Facility ID:	90921
Ai Number:	60525
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	140211
UST ID:	142296
AI Number:	60525
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/17/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142297
Facility ID:	90921
Ai Number:	60525
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	140212
UST ID:	142297
AI Number:	60525
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/17/1991
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142298
Facility ID:	90921
Ai Number:	60525
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	01/20/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	140213
UST ID:	142298
AI Number:	60525
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/17/1991
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	142299
Facility ID:	90921
Ai Number:	60525
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	3000
UST Comprt ID:	140214
UST ID:	142299
AI Number:	60525
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

TEXAS ALLERGY & ASTHMA CENTER (Continued) **U001290059**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	COOK ROBERT D
Contact Mailing Address (Delivery):	4150 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78756 3716
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	90921
Additional ID:	70146672002139
Princ ID:	79146662002139
AI Number:	60525
Facility Name:	TEXAS ALLERGY & ASTHMA CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHERYL COOK/

QW2878 **CONTINENTAL OIL COMP.** **TX HIST UST** **S128729376**
NW **4150 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.123 mi.
647 ft. **Site 2 of 3 in cluster QW**

Actual:
635 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	CONTINENTAL OIL COMP.
Address:	4150 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0692
HID UST:	692
Inspection:	03/24/2009
Due:	03/24/2012

QW2879 **TX ALLERGY ASTHMA CENTER** **TX HIST UST** **S128728989**
NW **4150 N LAMAR BLVD** **N/A**
< 1/8 **AUSTIN, TX**
0.123 mi.
647 ft. **Site 3 of 3 in cluster QW**

Actual:
635 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	TX ALLERGY ASTHMA CENTER
Address:	4150 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0298
HID UST:	Not reported

TX ALLERGY ASTHMA CENTER (Continued) **S128728989**

Inspection: Not reported
Due: Not reported

QM2880 **PAYLESS GAS NO 657** **EDR Hist Auto** **1020167481**
East **2805 SAN JACINTO BLVD** **N/A**
< 1/8 **AUSTIN, TX 78705**
0.123 mi.
647 ft. **Site 4 of 4 in cluster QM**

Actual:
538 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1991	PAYLESS GAS NO 657	Grocery Stores
1992	PAYLESS GAS NO 657	Grocery Stores
1993	PAYLESS GAS NO 657	Grocery Stores

QX2881 **TRANSMISSION EVENTS** **EDR Hist Auto** **1022026011**
East **501 N INTERSTATE 35** **N/A**
< 1/8 **AUSTIN, TX 78702**
0.123 mi.
648 ft. **Site 1 of 3 in cluster QX**

Actual:
472 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
2014	TRANSMISSION EVENTS	Automotive Transmission Repair Shops

---

QU2882 **DAY R L GARAGE** **EDR Hist Auto** **1013753872**
ESE **1301 SAN JACINTO ST** **N/A**
< 1/8 **AUSTIN, TX**
0.123 mi.
648 ft. **Site 2 of 2 in cluster QU**

Actual:
532 ft.

EDR Hist Auto

Focus Map:
11

Year:	Name:	Type:
1953	DAY R L GARAGE AUTO	AUTOMOBILE REPAIRING
1958	DAY R L GARAGE	AUTOMOBILE REPAIRING
1962	CLYDES AUTOMOTIVE	AUTOMOBILE REPAIRING
1965	VICTORS GARAGE AUTO	AUTOMOBILE REPAIRING

QO2883 **AMS INC** **TX HIST UST** **S128728884**
WNW **903 MC PHAUL ST** **N/A**
< 1/8 **AUSTIN, TX**
0.123 mi.
650 ft. **Site 3 of 3 in cluster QO**

Actual:
732 ft.

HIST UST AUSTIN:

Focus Map:
3

Name:	AMS INC
Address:	903 MC PHAUL ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0065

AMS INC (Continued) **S128728884**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QY2884 **FESTIVAL BEACH FOOD FOREST** **TX BROWNFIELDS** **S116385813**
NNE **35 WALLER ST** **N/A**
< 1/8 **AUSTIN, TX 78702**
0.124 mi.
655 ft. **Site 1 of 2 in cluster QY**

Actual:
461 ft.

Focus Map:
14

BROWNFIELDS:

Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER ST
City,State,Zip:	AUSTIN, TX 78702
BF Site Assessment Received:	02/20/2014
PCA number:	99690
BF Grant Number:	G156
Facility Type:	Possible Food Forest Site
Lead Type:	Owner/Operator
Project manager:	PALLEN
Phase:	COMPLETED
Lat/Long:	30.252680 / -97.734859999999998
Lat/Long (deg):	30.252680 / -97.734859999999998
Acres:	9.3
TCEQ Region:	11
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Austin
Applicant Title:	Conservation Program Coordinator
Applicant Address:	919 W 28 1/2 St
Applicant City,St,Zip:	Austin, TX 78705
Applicant Phone:	512-974-9450
Applicant Fax:	Not reported
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported
Status Date:	04/13/2015

QY2885	**FESTIVAL BEACH FOOD FOREST**	**US BROWNFIELDS**	**1018273138**
NNE	**35 WALLER STREET**		**N/A**
< 1/8	**AUSTIN, TX 78702**		
0.124 mi.			
655 ft.	**Site 2 of 2 in cluster QY**		

Actual:
461 ft.

Focus Map:
14

US BROWNFIELDS:

Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	4.6
Latitude:	30.25374532
Longitude:	-97.73505198
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Planned to continue to be used as a community garden. Former Use: The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Datum:	North American Datum of 1983
Acres Property ID:	208792
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	39352
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F67501
Start Date:	10/6/2014
Ownership Entity:	Government
Completion Date:	3/25/2015
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	3/6/2014
State/tribal program ID:	G156
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.6
Past use industrial acreage:	Not reported
Future use greenspace acreage:	4.6
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Below Poverty Number:	913
Below Poverty Percent:	28.71
Meidan Income:	7760
Meidan Income Number:	1434
Meidan Income Percent:	45.09
Vacant Housing Number:	398
Vacant Housing Percent:	19.11
Unemployed Number:	165
Unemployed Percent:	5.19

Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	4.6

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Latitude:	30.25374532
Longitude:	-97.73505198
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Planned to continue to be used as a community garden. Former Use: The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Datum:	North American Datum of 1983
Acres Property ID:	208792
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	39352
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F67501
Start Date:	10/6/2014
Ownership Entity:	Government
Completion Date:	3/25/2015
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	3/6/2014
State/tribal program ID:	G156
State/tribal NFA date:	Not reported

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.6
Past use industrial acreage:	Not reported
Future use greenspace acreage:	4.6
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Below Poverty Number:	913
Below Poverty Percent:	28.71
Meidan Income:	7760
Meidan Income Number:	1434
Meidan Income Percent:	45.09
Vacant Housing Number:	398
Vacant Housing Percent:	19.11
Unemployed Number:	165
Unemployed Percent:	5.19

Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	4.6
Latitude:	30.25374532
Longitude:	-97.73505198
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Planned to continue to be used as a community garden. Former Use: The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

	were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Datum:	North American Datum of 1983
Acres Property ID:	208792
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4951
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F67501
Start Date:	3/19/2014
Ownership Entity:	Government
Completion Date:	5/8/2014
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	3/6/2014
State/tribal program ID:	G156
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.6
Past use industrial acreage:	Not reported
Future use greenspace acreage:	4.6
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Below Poverty Number:	913
Below Poverty Percent:	28.71
Meidan Income:	7760
Meidan Income Number:	1434
Meidan Income Percent:	45.09
Vacant Housing Number:	398
Vacant Housing Percent:	19.11
Unemployed Number:	165
Unemployed Percent:	5.19

Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	4.6
Latitude:	30.25374532
Longitude:	-97.73505198
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Planned to continue to be used as a community garden. Former Use: The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Datum:	North American Datum of 1983
Acres Property ID:	208792
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F67501
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	3/6/2014
State/tribal program ID:	G156
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.6
Past use industrial acreage:	Not reported
Future use greenspace acreage:	4.6
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

	materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Below Poverty Number:	913
Below Poverty Percent:	28.71
Meidan Income:	7760
Meidan Income Number:	1434
Meidan Income Percent:	45.09
Vacant Housing Number:	398
Vacant Housing Percent:	19.11
Unemployed Number:	165
Unemployed Percent:	5.19
Name:	FESTIVAL BEACH FOOD FOREST
Address:	35 WALLER STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	4.6
Latitude:	30.25374532
Longitude:	-97.73505198
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Planned to continue to be used as a community garden. Former Use: The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Datum:	North American Datum of 1983
Acres Property ID:	208792
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4951
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F67501
Start Date:	3/19/2014
Ownership Entity:	Government
Completion Date:	5/8/2014
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	3/6/2014
State/tribal program ID:	G156
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	4.6
Past use industrial acreage:	Not reported
Future use greenspace acreage:	4.6
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site is developed with a community garden in the north portion and City park in the south. The general vicinity is developed with mixed uses that include residential, medical offices, and park land. The Site appears to have been first developed with a single-family residence circa 1935. Former U.S. Department of the Interior fish hatchery ponds located at the Site from the period circa 1950 to 1970 were apparently filled by 1973. The presence of fill of unknown origin at the Site represents a REC due to the possibility that hazardous materials and/or petroleum products were deposited with the fill. The proximity of the Site to Interstate Highway 35 represents a REC due to intensive automotive exhaust that has occurred near the Site prior to phasing out the addition of tetraethyl lead in fuel.
Below Poverty Number:	913
Below Poverty Percent:	28.71
Meidan Income:	7760
Meidan Income Number:	1434
Meidan Income Percent:	45.09
Vacant Housing Number:	398
Vacant Housing Percent:	19.11
Unemployed Number:	165

FESTIVAL BEACH FOOD FOREST (Continued) **1018273138**

Unemployed Percent: 5.19

2886 West < 1/8 0.124 mi. 657 ft. | **SEAHOLM DISTRICT UPRR** | **TX BROWNFIELDS** | **S105589923**
NO ADDRESS RAILROAD RIGHT OF WAY AND POWER PLANT SOUTH SIDE | **N/A**
AUSTIN, TX 78701

Actual: 457 ft.

Focus Map: 11

BROWNFIELDS:

Name:	SEAHOLM DISTRICT UPRR
Address:	NO ADDRESS RAILROAD RIGHT OF WAY AND POWER PLANT SOUTH SIDE OF 3RD ST BETWEEN
City,State,Zip:	AUSTIN, TX 78701
BF Site Assessment Received:	04/11/2002
PCA number:	78221
BF Grant Number:	G059
Facility Type:	Power Plant
Lead Type:	Purchaser
Project manager:	PALLEN
Phase:	COMPLETED
Lat/Long:	30.163000 / -97.450999999999993
Lat/Long (deg):	30.163000 / -97.450999999999993
Acres:	4.8
TCEQ Region:	11
Facility Type:	BSA
Contaminant Categories:	Not reported
Media Affected:	Not reported
Applicant:	City of Austin
Applicant Title:	Brownfields Project Officer
Applicant Address:	P.O. Box 1088
Applicant City,St,Zip:	Austin, TX 78767-1088
Applicant Phone:	512-974-1954
Applicant Fax:	512-974-3360
Consultant Attorney:	Not reported
Consultant Atty Name:	Not reported
Consultant Atty Title:	Not reported
Consultant Atty Addr:	Not reported
Consultant Atty City,St,Zip:	Not reported
Consultant Atty Phone:	Not reported
Consultant Atty Fax:	Not reported
SW Number:	Not reported
LPST Number:	Not reported
EPA TX id/registration:	Not reported
Risk Reduction Rules:	Not reported
Risk Reduction Standard:	Not reported
TRRP Tier:	Not reported
Certificate Issued:	Not reported
Conditional Or Final Certificate:	Not reported
Institutional Controls:	Not reported
Type Remedy:	Not reported
Status Date:	08/31/2002

2887 ESE < 1/8 0.125 mi. 658 ft. | **EXXON 6 2790**
619 N IH 35
AUSTIN, TX | **TX RDR** | **S127528300**
N/A

Actual: 656 ft.

Focus Map: 8

RDR:

RDR ID:	12679
Facility ID:	26050
RN:	Not reported
CN:	Not reported
Name:	EXXON 6 2790
Address:	619 N IH 35
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/25/2003
Due Date:	10/24/2003
Tank Owner:	EXXON MOBIL CORP
Contact Person:	DALE GOMM
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/18/2003
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC/DMR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/18/2003
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

2888 WNW < 1/8 0.125 mi. 659 ft. | **SAM PAYNE**
1010 W 38TH ST
AUSTIN, TX | **TX HIST UST** | **S111678801**
N/A

Actual: 614 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	SAM PAYNE
Address:	1010 W 38TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0340
HID UST:	340
Inspection:	Not reported
Due:	06/01/2012

QZ2889 **HAIS AUTOMOTIVE** **TX UST** **U001261881**
WNW **842 SAGEBRUSH DR** **N/A**
< 1/8 **AUSTIN, TX 78758**
0.125 mi.
660 ft. **Site 1 of 2 in cluster QZ**

Actual:
725 ft.

Focus Map:
3

UST:

Name:	HAIS AUTOMOTIVE
Address:	842 SAGEBRUSH DR
City,State,Zip:	AUSTIN, TX 787584823
AI Number:	28185
Facility Type:	FLEET REFUELING
Facility Begin Date:	10/23/1986
Facility Status:	INACTIVE
Additional ID:	180421562003020
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	HAI NGUYEN,OWNER
Contact Organization Name:	HAIS AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129979000
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/15/1986
Signature Name/Title On Earliest Reg Form:	TONA W HUNTER,OWNER
Application Received Date On Earliest Reg Form:	05/15/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN603116047
Owner Last Name:	NGUYEN
Owner First Name:	HAI
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	217556192006311
Additional ID:	180421562003020

HAIS AUTOMOTIVE (Continued) **U001261881**

AI Number:	28185
Owner Effective Begin Date:	08/13/2000
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/15/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	73737
Facility ID:	88500
Ai Number:	28185
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/15/2000
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

HAIS AUTOMOTIVE (Continued) **U001261881**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	143541
UST ID:	73737
AI Number:	28185
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

HAIS AUTOMOTIVE (Continued) **U001261881**

Facility Billing Contacts:

Contact Organization Name:	NGUYEN HAI
Contact Mailing Address (Delivery):	842 SAGEBRUSH DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78758 4823
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	88500
Additional ID:	180421562003020
Princ ID:	217556192006311
AI Number:	28185
Facility Name:	HAIS AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HAI NGUYEN/

RA2890 **NETTLE WELDING WORKS** **TX Ind. Haz Waste** **S104852445**
WNW **825 WAGON TRL** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78758**
0.127 mi.
670 ft. **Site 1 of 4 in cluster RA**

Actual:
741 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	20506
Registration Initial Notification Date:	05/22/1992
Registration Last Amendment Date:	02/14/2001
EPA Identification:	Not reported
Primary NAICS Code:	332999
Status Change Date:	19920522
Land Type:	Not reported
Description of Facility Site Location:	825 Wagon Trail, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	NETTLE WELDING WORKS INC
Contact Name:	V MICHAEL NETTLE
Contact Telephone Number:	512-8362287
Mailing Address:	825 WAGON TRL
Mailing Address2:	Not reported

NETTLE WELDING WORKS (Continued) **S104852445**

Mailing City,State,Zip:	AUSTIN, TX 787584328
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	6974
Site Owner Tax ID:	742206139
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030919
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	NETTLE WELDING WORKS INC
Operator Address:	825 WAGONTRL
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78758
Operator Country:	UNITED STA
Operator Telephone:	1-512-8362287
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17422061394
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	NETTLE WELDING WORKS INC
Owner Mailing Address:	825 WAGONTRL
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Country:	UNITED STA
Owner Telephone:	1-512-8362287
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17422061394
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE

NETTLE WELDING WORKS (Continued) **S104852445**

Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	825 WAGONTRL
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8362287
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	825 WAGONTRL
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8362287
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	V MICHAEL NETTLE
Contact Title:	PRESIDENT
Contact Role:	PRICONT
Contact Address:	825 WAGONTRL
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8362287
Contact Fax:	Not reported
Contact Email:	Not reported

NETTLE WELDING WORKS (Continued) **S104852445**

Ind. Haz Waste:

Waste ID:	137837
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	34990
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169013240
Primary NAICS Code:	332999
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CENTRAL REGISTRY:

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600377881
Customer Name:	NETTLE WELDING WORKS INC
Customer Legal Name:	Nettle Welding Works, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########

NETTLE WELDING WORKS (Continued) **S104852445**

Customer Number:	CN600377881
Customer Name:	NETTLE WELDING WORKS INC
Customer Legal Name:	Nettle Welding Works, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600377881
Customer Name:	NETTLE WELDING WORKS INC
Customer Legal Name:	Nettle Welding Works, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/14/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603910373
Customer Name:	NETTLE INC
Customer Legal Name:	NETTLE INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603910373
Customer Name:	NETTLE INC
Customer Legal Name:	NETTLE INC

NETTLE WELDING WORKS (Continued) **S104852445**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

Regulated Entity Number:	RN100669985
Name:	NETTLE WELDING WORKS
Address:	825 WAGON TRL
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4328
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603910373
Customer Name:	NETTLE INC
Customer Legal Name:	NETTLE INC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	332999
Primary NAICS Industry Type Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing
Physical Location Description:	825 Wagon Trail, Austin, TX

RA2891 **NETTLE** **TX Ind. Haz Waste** **S102758532**
WNW **825 WAGON TRL** **N/A**
1/8-1/4 **AUSTIN, TX 78758**
0.127 mi.
670 ft. **Site 2 of 4 in cluster RA**

Actual:
741 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	NETTLE
Address:	825 WAGON TRL
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	78098
Registration Initial Notification Date:	06/10/1992
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19920610
Land Type:	Not reported
Description of Facility Site Location:	TRAVIS
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS

NETTLE (Continued) **S102758532**

Company Name:	NETTLE INC
Contact Name:	JAMES NETTLES
Contact Telephone Number:	512-8362287
Mailing Address:	825 WAGON TRL
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787584328
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	32321
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020814
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	NETTLE INC
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	NETTLE INC
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

NETTLE (Continued) **S102758532**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	JAMES NETTLES
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	825 WAGONTRL
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8362287
Contact Fax:	Not reported
Contact Email:	Not reported

QT2892 **I. E. STUBBS** **TX HIST UST** **S111678687**
WNW **2318 S 1ST ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.128 mi.
676 ft. **Site 3 of 3 in cluster QT**

Actual:
538 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	I. E. STUBBS
Address:	2318 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0746
HID UST:	746
Inspection:	Not reported
Due:	06/01/2012

RB2893 ESE 1/8-1/4 0.129 mi. 680 ft. | **US POSTAL SERVICE AUSTIN P&DC**
300 E 9TH ST
AUSTIN, TX 78710
Site 1 of 2 in cluster RB | **RCRA-VSQG FINDS ECHO** | **1000349138 TX8180000301**

Actual: 532 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	20101020
Handler Name:	Us Postal Service Austin P&Dc
Handler Address:	300 E 9TH ST
Handler City,State,Zip:	AUSTIN, TX 78710-2400
EPA ID:	TX8180000301
Contact Name:	JAMES GRAHAM JR
Contact Address:	1 POST OFFICE DR
Contact City,State,Zip:	SAN ANTONIO, TX 78284-8401
Contact Telephone:	210-368-5519
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Federal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1 POST OFFICE DR
Mailing City,State,Zip:	SAN ANTONIO, TX 78284-8401
Owner Name:	United States Postal Service,
Owner Type:	Private
Operator Name:	United States Postal Service,
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

US POSTAL SERVICE AUSTIN P&DC (Continued) **1000349138**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20101027
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: USPS	
Legal Status:	Federal
Date Became Current:	19860915
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

US POSTAL SERVICE AUSTIN P&DC (Continued) **1000349138**

Owner/Operator Indicator:	Owner
Owner/Operator Name: UNITED STATES POSTAL SERVICE	
Legal Status:	Private
Date Became Current:	20100803
Date Ended Current:	Not reported
Owner/Operator Address:	1 POST OFFICE DR
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78284
Owner/Operator Telephone:	210-368-5519
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: USPS	
Legal Status:	Federal
Date Became Current:	19860915
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: UNITED STATES POSTAL SERVICE	
Legal Status:	Not reported
Date Became Current:	20021127
Date Ended Current:	Not reported
Owner/Operator Address:	1 POST OFFICE DR
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78284
Owner/Operator Telephone:	210-368-5519
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: UNITED STATES POSTAL SERVICE	
Legal Status:	Private
Date Became Current:	20100803
Date Ended Current:	Not reported
Owner/Operator Address:	1 POST OFFICE DR
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78284
Owner/Operator Telephone:	210-368-5519
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: UNITED STATES POSTAL SERVICE	
Legal Status:	Not reported
Date Became Current:	20021127
Date Ended Current:	Not reported
Owner/Operator Address:	1 POST OFFICE DR
Owner/Operator City,State,Zip:	SAN ANTONIO, TX 78284
Owner/Operator Telephone:	210-368-5519
Owner/Operator Telephone Ext:	Not reported

US POSTAL SERVICE AUSTIN P&DC (Continued) **1000349138**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: UNITED STATES POSTAL SERVICE
Legal Status: Private
Date Became Current: 20100714
Date Ended Current: Not reported
Owner/Operator Address: 1 POST OFFICE DR
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78284
Owner/Operator Telephone: 210-368-5519
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: UNITED STATES POSTAL SERVICE,
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1 POST OFFICE DR
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78284-8401
Owner/Operator Telephone: 210-368-5519
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNITED STATES POSTAL SERVICE
Legal Status: Private
Date Became Current: 20100714
Date Ended Current: Not reported
Owner/Operator Address: 1 POST OFFICE DR
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78284
Owner/Operator Telephone: 210-368-5519
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNITED STATES POSTAL SERVICE,
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1 POST OFFICE DR
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78284-8401
Owner/Operator Telephone: 210-368-5519
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100714
Handler Name: UNITED STATES POSTAL SERVICE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No

US POSTAL SERVICE AUSTIN P&DC (Continued) **1000349138**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20030127
Handler Name:	USPS AUSTIN P AND DC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20021127
Handler Name:	UNITED STATES POSTAL SERVICE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20100803
Handler Name:	UNITED STATES POSTAL SERVICE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20101020
Handler Name:	US POSTAL SERVICE AUSTIN P&DC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

US POSTAL SERVICE AUSTIN P&DC (Continued) **1000349138**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 49111
NAICS Description: POSTAL SERVICE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110042294353

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000349138
Registry ID: 110042294353
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110042294353
Name: US POSTAL SERVICE AUSTIN P&DC
Address: 300 E 9TH ST
City,State,Zip: AUSTIN, TX 78710

RB2894 **US POSTAL SERVICE AUSTIN P&DC** **TX Ind. Haz Waste** **S102752953**
ESE **300 E 9TH ST** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.129 mi.
680 ft. **Site 2 of 2 in cluster RB**

Actual:
532 ft.

Focus Map:
11

Ind. Haz Waste:
Name: US POSTAL SERVICE AUSTIN P&DC
Address: 300 E 9TH ST
City,State,Zip: AUSTIN, TX 78701
Permit Number: Not reported
Registration Number: 70524
Registration Initial Notification Date: 09/01/1986
Registration Last Amendment Date: 10/19/2010
EPA Identification: TX8180000301
Primary NAICS Code: Not reported
Status Change Date: 19860901
Land Type: FEDERAL
Description of Facility Site Location: 300 E 9th St, Austin, TX

US POSTAL SERVICE AUSTIN P&DC (Continued) **S102752953**

Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	UNITED STATES POSTAL SERVICE
Contact Name:	JAMES GRAHAM JR
Contact Telephone Number:	210-3685519
Mailing Address:	1 POST OFFICE DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	SAN ANTONIO, TX 782848401
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25338
Site Owner Tax ID:	941308560
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20101020
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	UNITED STATES POSTAL SERVICE
Operator Address:	1 POST OFFICE DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	SAN ANTONIO, TX 78284
Operator Country:	UNITED STA
Operator Telephone:	1-210-3685519
Operator Fax Number:	1-210-3685533
Operator Email:	Not reported
Operator Business Type:	Federal Government Ownership
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	UNITED STATES POSTAL SERVICE
Owner Mailing Address:	1 POST OFFICE DR

US POSTAL SERVICE AUSTIN P&DC (Continued) **S102752953**

Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	SAN ANTONIO, TX 78284
Owner Country:	UNITED STA
Owner Telephone:	1-210-3685519
Owner Fax:	1-210-3685533
Owner Email Address:	Not reported
Owner Business Type:	Federal Government Ownership
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1 POST OFFICE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN ANTONIO, TX 78284
Contact Phone:	1-210-3685519
Contact Fax:	1-210-3685533
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1 POST OFFICE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN ANTONIO, TX 78284
Contact Phone:	1-210-3685519
Contact Fax:	1-210-3685533
Contact Email:	Not reported

Contact Name:	JAMES GRAHAM JR
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1 POST OFFICE DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SAN ANTONIO, TX 78284
Contact Phone:	1-210-3685519
Contact Fax:	1-210-3685533
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	246842
Texas Waste Code:	Not reported
Texas Waste Code 2:	0050219H
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Zep product sun solve degreaser, unused commercial product, contains D-Limonene,

US POSTAL SERVICE AUSTIN P&DC (Continued) **S102752953**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	491110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	246845
Texas Waste Code:	Not reported
Texas Waste Code 2:	00512191
Waste Code Status:	INACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Non-hazardous zep shield, unused commercial product, contains 2 - (2-ethoxyethox
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8225 CROSS PARK DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78710
AR Number:	0000301889
Principal Name:	UNITED STATES POSTAL SERVICE
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported

US POSTAL SERVICE AUSTIN P&DC (Continued) **S102752953**

Mailing Address:	8225 CROSS PARK DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78710
AR Number:	0000301889
Principal Name:	UNITED STATES POSTAL SERVICE
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8225 CROSS PARK DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78710
AR Number:	0000301889
Principal Name:	UNITED STATES POSTAL SERVICE
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	8225 CROSS PARK DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78710
AR Number:	0000301889
Principal Name:	UNITED STATES POSTAL SERVICE
Attention Name:	Not reported
Attention Suffix:	HWG

2895
NE
1/8-1/4
0.130 mi.
685 ft.

RBJ REDEVELOPMENT PROJECT
21 WALLER ST
AUSTIN, TX 78702

TX TANKS **S126931260**
TX HIST UST **N/A**
TX RDR
TX CENTRAL REGISTRY

Actual:
461 ft.

Focus Map:
14

TANKS:

Facility ID:	134895
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
City,State,Zip:	AUSTIN, TX 787025240
Total UST:	Not reported
Additional ID:	966338632018071
AI Number:	89784
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	Not reported

RBJ REDEVELOPMENT PROJECT (Continued) **S126931260**

Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

HIST UST AUSTIN:

Name:	Not reported
Address:	21 WALLER ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3421
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	25673
Facility ID:	89784
RN:	Not reported
CN:	Not reported
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/1/2018
Due Date:	6/30/2018
Tank Owner:	AUSTIN GERIATRIC CENTER INC
Contact Person:	MEGAN SHANNON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/21/2018
Project Manager:	Jake Halfhill
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RBJ REDEVELOPMENT PROJECT (Continued) **S126931260**

CENTRAL REGISTRY:

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605559236
Customer Name:	THE AUSTIN GERIATRIC CENTER INC
Customer Legal Name:	The Austin Geriatric Center, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-08-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605559236
Customer Name:	THE AUSTIN GERIATRIC CENTER INC
Customer Legal Name:	The Austin Geriatric Center, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-08-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605559236
Customer Name:	THE AUSTIN GERIATRIC CENTER INC
Customer Legal Name:	The Austin Geriatric Center, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-08-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT

RBJ REDEVELOPMENT PROJECT (Continued) **S126931260**

Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605559236
Customer Name:	THE AUSTIN GERIATRIC CENTER INC
Customer Legal Name:	The Austin Geriatric Center, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-08-14
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN603653213
Customer Name:	CHASCO CONSTRUCTORS LTD LLP
Customer Legal Name:	Chasco Constructors, Ltd., L.L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-02
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN603653213
Customer Name:	CHASCO CONSTRUCTORS LTD LLP
Customer Legal Name:	Chasco Constructors, Ltd., L.L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-02
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216

RBJ REDEVELOPMENT PROJECT (Continued) **S126931260**

Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN603653213
Customer Name:	CHASCO CONSTRUCTORS LTD LLP
Customer Legal Name:	Chasco Constructors, Ltd., L.L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-02
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN603653213
Customer Name:	CHASCO CONSTRUCTORS LTD LLP
Customer Legal Name:	Chasco Constructors, Ltd., L.L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	2018-08-02
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605479450
Customer Name:	CESAR CHAVEZ LAKEVIEW VILLAGE LLC
Customer Legal Name:	Cesar Chavez Lakeview Village, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605479450

RBJ REDEVELOPMENT PROJECT (Continued) **S126931260**

Customer Name:	CESAR CHAVEZ LAKEVIEW VILLAGE LLC
Customer Legal Name:	Cesar Chavez Lakeview Village, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN110286846
Name:	RBJ REDEVELOPMENT PROJECT
Address:	21 WALLER ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5216
Status:	ACTIVE
Status Date:	2018-03-12
Customer Number:	CN605479450
Customer Name:	CESAR CHAVEZ LAKEVIEW VILLAGE LLC
Customer Legal Name:	Cesar Chavez Lakeview Village, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
15 additional TX CENTRAL REG: record(s) in the EDR Site Report.

2896 **LAMAR VILLAGE SHOPPING CTR** **TX TANKS** **S126523858**
WNW **3800 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78756**
0.130 mi.
686 ft.

Actual:
615 ft.

Focus Map:
8

TANKS:

Facility ID:	102686
Name:	LAMAR VILLAGE SHOPPING CTR
Address:	3800 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787564011
Total UST:	0
Additional ID:	648632842002053
AI Number:	67961
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Facility Exempt Status:	Y
Records Off-Site:	N
UST Financial Assurance Required:	N
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	JEFF SIMMONS,PROPERTY MGR
Contact Organization Name:	LAMAR VILLAGE SHOPPING CTR

LAMAR VILLAGE SHOPPING CTR (Continued) **S126523858**

Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124746491
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	12/29/1995
Signature Date On Earliest Reg Form:	12/27/1995
Signature Name/Title On Earliest Reg Form:	JEFF SIMMONS,PROPERTY MGR
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101493534
Name:	LAMAR VILLAGE SHOPPING CTR
Address:	3800 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-4011
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600781728
Customer Name:	LAMAR VILLAGE SHOPPING CTR LC
Customer Legal Name:	Lamar Village Shopping Center, LC
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/31/1987
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

RC2897 **RUDYS AUTOMOTIVE** **TX COMP HIST** **S106950994**
ESE **4431 LUCKSINGER LN** **TX RDR** **N/A**
1/8-1/4 **AUSTIN, TX 78745** **TX CENTRAL REGISTRY**
0.132 mi.
696 ft. **Site 1 of 2 in cluster RC**

Actual:
653 ft.

Focus Map:
17

COMP HIST:

RN Number:	RN102429750
Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604394361
CN Name:	VILLARREAL, RUDY
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED

RUDYS AUTOMOTIVE (Continued) **S106950994**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236220
SIC Code:	7538
Related Number:	R11102429750,R11102429750

RN Number:	RN102429750
Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN601255227
CN Name:	BENOIT FRANCIS E
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	484110
SIC Code:	7538
Related Number:	R11102429750,R11102429750

RDR:

RDR ID:	13066
Facility ID:	25515
RN:	Not reported
CN:	Not reported
Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/2003
Due Date:	2/8/2004
Tank Owner:	FRANCIS BENOIT
Contact Person:	FRANCIA BENOIT
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/14/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC/KJF
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/14/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102429750

RUDYS AUTOMOTIVE (Continued) **S106950994**

Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-2003
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN601255227
Customer Name:	BENOIT FRANCIS E
Customer Legal Name:	Benoit Francis E.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	10/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102429750
Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-2003
Status:	ACTIVE
Status Date:	6/1/2002
Customer Number:	CN604394361
Customer Name:	VILLARREAL, RUDY
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	8/30/2013
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

RC2898 **RUDYS AUTOMOTIVE** **TX UST** **U001259581**
ESE **4431 LUCKSINGER LN** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.132 mi.
696 ft. **Site 2 of 2 in cluster RC**

Actual:
653 ft.

Focus Map:
17

UST:

Name:	RUDYS AUTOMOTIVE
Address:	4431 LUCKSINGER LN
City,State,Zip:	AUSTIN, TX 787452003
AI Number:	25515
Facility Type:	FLEET REFUELING
Facility Begin Date:	10/08/1986
Facility Status:	INACTIVE
Additional ID:	458689222002152
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

RUDYS AUTOMOTIVE (Continued) **U001259581**

Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	RUDYS AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124423213
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/11/1986
Signature Name/Title On Earliest Reg Form:	S BRIGGS,GEOLOGIST
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601255227
Owner Last Name:	BENOIT FRANCIS E
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	448689222002152
Additional ID:	458689222002152
AI Number:	25515
Owner Effective Begin Date:	10/08/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	65513
Facility ID:	62112
Ai Number:	25515
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND

RUDYS AUTOMOTIVE (Continued) **U001259581**

Tank Status Date:	11/19/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	500
UST Comprt ID:	80347
UST ID:	65513
AI Number:	25515
Compartment ID:	A

RUDYS AUTOMOTIVE (Continued) **U001259581**

Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9633
Cert ID:	35375
UST Comprt ID:	123311
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35861
UST Comprt ID:	123307
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35371
UST Comprt ID:	123315
UST ID:	28379

RUDYS AUTOMOTIVE (Continued) **U001259581**

AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35374
UST Comprt ID:	123312
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35373
UST Comprt ID:	123313
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35372
UST Comprt ID:	123314
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35376
UST Comprt ID:	123310
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35369
UST Comprt ID:	123317
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35368
UST Comprt ID:	123316
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35370
UST Comprt ID:	123318
UST ID:	28379
AI Number:	25515

RUDYS AUTOMOTIVE (Continued) **U001259581**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35377
UST Comprt ID:	123309
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35862
UST Comprt ID:	123306
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35860
UST Comprt ID:	123308
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	65512
Facility ID:	62112
Ai Number:	25515
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/19/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

RUDYS AUTOMOTIVE (Continued) **U001259581**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	500
UST Comprt ID:	80346
UST ID:	65512
AI Number:	25515
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

RUDYS AUTOMOTIVE (Continued) **U001259581**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	9633
Cert ID:	35375
UST Comprt ID:	123311
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35861
UST Comprt ID:	123307
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35371
UST Comprt ID:	123315
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35374
UST Comprt ID:	123312
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35373
UST Comprt ID:	123313
UST ID:	28379
AI Number:	25515

RUDYS AUTOMOTIVE (Continued) **U001259581**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35372
UST Comprt ID:	123314
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35376
UST Comprt ID:	123310
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35369
UST Comprt ID:	123317
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35368
UST Comprt ID:	123316
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35370
UST Comprt ID:	123318
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35377
UST Comprt ID:	123309
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35862
UST Comprt ID:	123306
UST ID:	28379
AI Number:	25515
Tank ID:	4

RUDYS AUTOMOTIVE (Continued) **U001259581**

Compartment ID:	A
Self Cert ID:	9633
Cert ID:	35860
UST Comprt ID:	123308
UST ID:	28379
AI Number:	25515
Tank ID:	4
Compartment ID:	A

Construction Notification:

NOC ID:	6375
Facility ID:	62112
AI Number:	25515
Application Received Date:	11/13/2003
Scheduled Construction Date:	11/24/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M31113003
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	12903
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	6855
UST ID:	Not reported
NOC ID:	6375
AI Number:	25515
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001075
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported

RUDYS AUTOMOTIVE (Continued) **U001259581**

Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	BENOIT FRANCIS E
Contact Mailing Address (Delivery):	290 TURKEY RUN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	MEADOWLAKES, TX 78654 7020
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	62112
Additional ID:	458689222002152
Princ ID:	448689222002152
AI Number:	25515
Facility Name:	RUDYS AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

RD2899 **PENSKE TRUCK LEASING** **TX NON REGIST PST** **S120830668**
SW **8800 S CONGRESS AVE** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.132 mi.
699 ft. **Site 1 of 4 in cluster RD**

Actual:
664 ft.

Focus Map:
21

NON REGIST PST:

RN Number:	RN105547889
Name:	PENSKE TRUCK LEASING
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745 7318
Physical Location:	No physical location description ON file.
CN Number:	CN601573330
Customer Name:	PENSKE TRUCK LEASING CO LP
Customer Role:	OWNER OPERATOR
Primary Business:	FLEET REFUELING
Code:	1542
Classification:	SIC
Industry Name:	General Contractors-Nonresidential Buildings
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=875573842008161
RN Number:	RN105547889

PENSKE TRUCK LEASING (Continued) **S120830668**

Name:	PENSKE TRUCK LEASING
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745 7318
Physical Location:	No physical location description ON file.
CN Number:	CN602544181
Customer Name:	TEAL CONSTRUCTION COMPANY
Customer Role:	OPERATOR
Primary Business:	FLEET REFUELING
Code:	1542
Classification:	SIC
Industry Name:	General Contractors-Nonresidential Buildings
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=875573842008161

RN Number:	RN105547889
Name:	PENSKE TRUCK LEASING
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745 7318
Physical Location:	No physical location description ON file.
CN Number:	CN603219346
Customer Name:	TEAL BUILDING AND CONSTRUCTION LTD
Customer Role:	OPERATOR
Primary Business:	FLEET REFUELING
Code:	1542
Classification:	SIC
Industry Name:	General Contractors-Nonresidential Buildings
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=875573842008161

RD2900 **PENSKE TRUCK LEASING AUSTIN CONGRESS** **TX UST** **U004127546**
SW **8800 S CONGRESS AVE** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78745** **TX Financial Assurance**
0.132 mi.
699 ft. **Site 2 of 4 in cluster RD**

Actual:
664 ft.

Focus Map:
21

UST:

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 787457318
AI Number:	79443
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/23/2008
Facility Status:	ACTIVE
Additional ID:	248491372008253
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	BRIAN YAZEMBOSKI,MGR ENVIR SV
Contact Organization Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	6106038450
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	6107756442
Contact Email Address:	BRIAN.YAZEMBOSKI@PENSKE.COM
Signature Date On Earliest Reg Form:	08/06/2021
Signature Name/Title On Earliest Reg Form:	BRIAN YAZEMBOSKI,MGR ENV SRV
Application Received Date On Earliest Reg Form:	05/24/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	915486472003084
Additional ID:	248491372008253
Ai Number:	79443
Operator CN:	CN601573330
Operator Name:	PENSKE TRUCK LEASING CO LP
Operator Effective Begin Date:	06/15/2008
Operator Type:	PA
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	PENSKE TRUCK LEASING CO LP
Contact Mailing Address (Delivery):	PO BOX 7635
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	READING PA 19603-7635
Contact Phone Country Code:	1
Contact Phone Area Code:	610
Contact Phone Number:	7756298
Contact Phone Extension:	0
Contact Fax Country Code:	1
Contact Fax Area Code:	620
Contact Fax Number:	7756442
Contact Fax Extension:	0
Contact Email Address:	www.pensketruckleasing.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601573330
Owner Last Name:	PENSKE TRUCK LEASING CO LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	PO BOX 7635
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	READING
Contact Mailing State:	PA
Contact Mailing Zip:	19603
Contact Mailing Zip5:	7635

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Contact Phone Number/Ext:	1 214 8728481/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	915486472003084
Additional ID:	248491372008253
AI Number:	79443
Owner Effective Begin Date:	06/15/2008
State Tax ID:	12325186182
Contact Role:	OWNCON
Contact Name/Title:	/
Contact Organization Name:	PENSKE TRUCK LEASING CO LP

Self Certification:

Self Cert ID:	123066
Cert ID:	371954
AI Number:	79443
Self Certification Date:	06/20/2022
Signature Name/Title:	MORGAN MCCUSKER ENV RECORDS COORDINATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	357666
AI Number:	79443
Self Certification Date:	08/06/2021
Signature Name/Title:	BRIAN YAZEMBOSKI MGR ENV SRV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	340455
AI Number:	79443
Self Certification Date:	07/06/2020

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Signature Name/Title:	BRIAN YAZEMBOSKI MANAGER ENVIRONMENTAL SERVICES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	324858
AI Number:	79443
Self Certification Date:	08/26/2019
Signature Name/Title:	MICHAEL COSTANZA DIR OF ENV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	306398
AI Number:	79443
Self Certification Date:	06/28/2018
Signature Name/Title:	MICHAEL CONSTANZA DIR OF ENV SERV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	289490
AI Number:	79443
Self Certification Date:	07/05/2017

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Signature Name/Title:	MICHAEL CONSTANZA DIRECTOR OF ENVIRO SERVICES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	272776
AI Number:	79443
Self Certification Date:	06/24/2016
Signature Name/Title:	MICHAEL COSTANZA DIR OF ENVIRONMENTAL SERVICES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	256581
AI Number:	79443
Self Certification Date:	06/24/2015
Signature Name/Title:	MICHAEL COSTANZA DIR ENV SRV
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	240657
AI Number:	79443
Self Certification Date:	07/02/2014

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Signature Name/Title:	MICHAEL CONSTANZA DIR EHS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	222965
AI Number:	79443
Self Certification Date:	06/20/2013
Signature Name/Title:	MICHAEL COSTANZA DIR EHS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	123066
Cert ID:	217995
AI Number:	79443
Self Certification Date:	06/25/2012
Signature Name/Title:	MICHAEL COSTANZA DIR ENV SVCS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	123066
Cert ID:	217994
AI Number:	79443
Self Certification Date:	06/22/2011

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Signature Name/Title:	ANDREW E CULLEN VP ENERGY & TELECOM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	123066
Cert ID:	217993
AI Number:	79443
Self Certification Date:	06/23/2010
Signature Name/Title:	ANDREW E CULLEN VP ENERGY & TELECOM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	123066
Cert ID:	217992
AI Number:	79443
Self Certification Date:	06/26/2009
Signature Name/Title:	ANDREW E CULLEN VP, ENERGY & TELECOM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	123066
Cert ID:	217991
AI Number:	79443
Self Certification Date:	08/01/2008

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Signature Name/Title:	MICHAEL COSTANZA MGR ENV SVR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	05/23/2008
Tank Registration Date:	08/26/2008
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	210545
Facility ID:	123066
Ai Number:	79443
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	05/23/2008
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/05/2008

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	183762
UST ID:	210545
AI Number:	79443
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	05/23/2008
Tank Registration Date:	08/26/2008
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	210546
Facility ID:	123066
Ai Number:	79443
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	05/23/2008
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/05/2008

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	183763
UST ID:	210546
AI Number:	79443
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Construction Notification:

NOC ID:	34484
Facility ID:	123066
AI Number:	79443
Application Received Date:	04/03/2019
Scheduled Construction Date:	04/01/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	04/03/2019
Signature Date On Form:	04/01/2019
Signature Name On Form:	LARRY HOLYBEE
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	PENSKE TRUCK LEASING CO LP;PENSKE TRUCK LEASING CO LP
Owner CN At Time Of Construction:	CN601573330,CN601573330
Owner AR At Time Of Construction:	17958A,17958U
General Desc Of Prop Construct:	DIESEL LINE FAILED LINE TEST SO REPIPING DIESEL LINE

NOC ID:	21387
Facility ID:	123066
AI Number:	79443
Application Received Date:	03/27/2008
Scheduled Construction Date:	04/07/2008
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M80327006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	04/03/2019
Signature Date On Form:	04/01/2019
Signature Name On Form:	LARRY HOLYBEE
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	17958

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	81860
UST ID:	Not reported
NOC ID:	34484
AI Number:	79443
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	RANGER ENVIRONMENTAL
Representative Name:	DAN AIREY
Mailing Address (Delivery):	7215 MCNIEL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78729
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	3351785
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	35814
UST ID:	210545
NOC ID:	Not reported
AI Number:	79443
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	35815
UST ID:	210546
NOC ID:	Not reported
AI Number:	79443
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	22431
UST ID:	Not reported
NOC ID:	21387
AI Number:	79443
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	81858
UST ID:	Not reported
NOC ID:	34484
AI Number:	79443
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PETROLEUM SOLUTIONS
Representative Name:	LARRY HOLYBEE
Mailing Address (Delivery):	1404 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	81859
UST ID:	Not reported
NOC ID:	34484
AI Number:	79443
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000092
Company Name:	KVETON DAVID OTTO
Representative Name:	Not reported
Mailing Address (Delivery):	5731 FM 2218 RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	RICHMOND
Mailing State:	TX
Mailing Zip:	77469
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	281
Phone Number:	3425256
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	50981
UST ID:	210545
NOC ID:	Not reported
AI Number:	79443
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000748
Company Name:	Not reported
Representative Name:	MARK BARRON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Cont/Cons/Installer ID:	50982
UST ID:	210546
NOC ID:	Not reported
AI Number:	79443
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000748
Company Name:	Not reported
Representative Name:	MARK BARRON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PENSKE TRUCK LEASING CO LP
Contact Mailing Address (Delivery):	PO BOX 7635
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	READING, PA 19603 7635
Phone Number/Ext:	610 6038450/0
Contact Fax Number/Ext:	610 7756442/0
Contact Email Address:	BRIAN.YAZEMBOSKI@PENSKE.COM
Contact Address Deliverable:	Y
Facility ID:	123066
Additional ID:	248491372008253
Princ ID:	915486472003084
AI Number:	79443
Facility Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
AR Number:	17958
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	BRIAN YAZEMBOSKI/MGR ENVIR SV

HIST UST AUSTIN:

Name:	PENSKE TRUCK LEASING
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Id UST:	3314
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	269766
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/18/2022
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/18/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	253269
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2021
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	235281
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2020
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	219024
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2019
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	199716
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2018
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	182683
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2017
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/15/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	182118
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2017
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Facility ID:	123066
Finass ID:	165218
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/14/2016
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 610 6038450
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/14/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	147598
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2014
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/31/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	126942
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2014
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	132002
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2014
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	107952
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2013
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	No

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	112223
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/01/2013
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/01/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	14681
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/09/2012
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 610 7756298
Policy Number:	0
Coverage Amount:	2,000,000
Coverage Expiration Date:	08/09/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	104750
AI:	79443

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/28/2011
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	Not reported
Issuer Phone:	1 267 6454080
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	05/28/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	104749
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/28/2011
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	Not reported
Issuer Phone:	1 267 6454080
Policy Number:	5274
Coverage Amount:	1000000
Coverage Expiration Date:	05/28/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	104751
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/28/2010
Date Financial Assurance Form Rec:	05/24/2021

PENSKE TRUCK LEASING AUSTIN CONGRESS (Continued) **U004127546**

Issuer Name:	Not reported
Issuer Phone:	1 267 6454080
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	05/28/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	104752
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	TRUST FUND
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/28/2009
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	Not reported
Issuer Phone:	1 267 6454080
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	05/28/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PENSKE TRUCK LEASING AUSTIN CONGRESS
Address:	8800 S CONGRESS AVE
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	123066
Finass ID:	104753
AI:	79443
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	N
Financial Responsibility Type:	LETTER OF CREDIT
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/28/2008
Date Financial Assurance Form Rec:	05/24/2021
Issuer Name:	Not reported
Issuer Phone:	1 267 6854080
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	08/28/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

RD2901 SW 1/8-1/4 0.132 mi. 699 ft. | **PENSKE TRUCK RENTAL**
8800 SOUTH CONGRESS AVE
AUSTIN, TX
Site 3 of 4 in cluster RD | **TX RDR** | **S127540238**
N/A

Actual: 664 ft.
Focus Map: 21

RDR:

RDR ID:	27270
Facility ID:	79443
RN:	Not reported
CN:	Not reported
Name:	PENSKE TRUCK RENTAL
Address:	8800 SOUTH CONGRESS AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/19/2019
Due Date:	9/17/2019
Tank Owner:	PENSKE TRUCK LEASING CO
Contact Person:	LORI DONALD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/16/2019
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RD2902 SW 1/8-1/4 0.132 mi. 699 ft. | **PENSKE TRUCK LEASING CO LP**
8800 S CONGRESS AVE
AUSTIN, TX 78745
Site 4 of 4 in cluster RD | **RCRA-VSQG** | **1011491227**
TXR000079188

Actual: 664 ft.
Focus Map: 21

RCRA Listings:

Date Form Received by Agency:	20180731
Handler Name:	Penske Truck Leasing Co Lp
Handler Address:	S CONGRESS AVE
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXR000079188
Contact Name:	CHRIS HAWK
Contact Address:	RT 10 GREEN HILLS P O BOX 7635
Contact City,State,Zip:	READING, PA 19603
Contact Telephone:	610-775-6123
Contact Fax:	610-775-6442
Contact Email:	CHRISTOPHER.HAWK@PENSKE.COM
Contact Title:	SR. ENV. COMPL. ENG.
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

PENSKE TRUCK LEASING CO LP (Continued) **1011491227**

Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	RT 10 GREEN HILLS P O BOX 7635
Mailing City,State,Zip:	READING, PA 19603
Owner Name:	Penske Truck Leasing Co Lp
Owner Type:	Private
Operator Name:	Penske Truck Leasing Co Lp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180808
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D003
Waste Description:	Reactive Waste

PENSKE TRUCK LEASING CO LP (Continued) **1011491227**

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: PENSKE TRUCK LEASING CO LP
Legal Status: Private
Date Became Current: 20080615
Date Ended Current: Not reported
Owner/Operator Address: RT 10 GREEN HILLS PO BOX 7635
Owner/Operator City,State,Zip: READING, PA 19603
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PENSKE TRUCK LEASING CO LP
Legal Status: Private
Date Became Current: 20080615
Date Ended Current: Not reported
Owner/Operator Address: RT 10 GREEN HILLS PO BOX 7635
Owner/Operator City,State,Zip: READING, PA 19603
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PENSKE TRUCK LEASING CO LP
Legal Status: Private
Date Became Current: 20080615
Date Ended Current: Not reported
Owner/Operator Address: RT 10 GREEN HILLS PO BOX 7635
Owner/Operator City,State,Zip: READING, PA 19603
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

PENSKE TRUCK LEASING CO LP (Continued) **1011491227**

Owner/Operator Indicator: Operator
Owner/Operator Name: PENSKE TRUCK LEASING CO LP
Legal Status: Private
Date Became Current: 20080615
Date Ended Current: Not reported
Owner/Operator Address: RT 10 GREEN HILLS PO BOX 7635
Owner/Operator City,State,Zip: READING, PA 19603
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080610
Handler Name: PENSKE TRUCK LEASING CO LP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180731
Handler Name: PENSKE TRUCK LEASING CO LP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 53212
NAICS Description: TRUCK, UTILITY TRAILER, AND RV (RECREATIONAL VEHICLE) RENTAL AND LEASING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

RE2903 ESE 1/8-1/4 0.134 mi. 706 ft. | **BUTLER PAPER**
200 E SAINT ELMO RD
AUSTIN, TX 78745
Site 1 of 6 in cluster RE | **TX UST** | **U001246847**
N/A

Actual: 662 ft.

Focus Map: 18

UST:

Name:	BUTLER PAPER
Address:	200 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 787451218
AI Number:	10844
Facility Type:	UNKNOWN
Facility Begin Date:	07/24/1986
Facility Status:	INACTIVE
Additional ID:	11374962002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	200-210
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	J DEEDS,OPS MGR
Contact Organization Name:	BUTLER PAPER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124426746
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	J DEEDS,OPS MANAGER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600916647
Owner Last Name:	BUTLER PAPER CO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	992374952002075
Additional ID:	11374962002075

BUTLER PAPER (Continued) **U001246847**

AI Number:	10844
Owner Effective Begin Date:	07/24/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1967
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28464
Facility ID:	50151
Ai Number:	10844
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

BUTLER PAPER (Continued) **U001246847**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	37180
UST ID:	28464
AI Number:	10844
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

BUTLER PAPER (Continued) **U001246847**

Facility Billing Contacts:

Contact Organization Name:	BUTLER PAPER CO
Contact Mailing Address (Delivery):	PO BOX 3568
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ENGLEWOOD, CO 80155 3568
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	50151
Additional ID:	11374962002075
Princ ID:	992374952002075
AI Number:	10844
Facility Name:	BUTLER PAPER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

RE2904 **BUTLER PAPER CO** **TX HIST UST** **S128728891**
ESE **200 E ST ELMO RD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.134 mi.
706 ft. **Site 2 of 6 in cluster RE**

Actual:
662 ft.

Focus Map:
18

HIST UST AUSTIN:

Name:	BUTLER PAPER CO
Address:	200 E ST ELMO RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0081
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

QF2905 **LITTLE & GOSLIN** **TX HIST UST** **S111678722**
WNW **817 W 5TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.136 mi.
716 ft. **Site 3 of 3 in cluster QF**

Actual:
464 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	LITTLE & GOSLIN
Address:	817 W 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0456
HID UST:	456
Inspection:	Not reported
Due:	06/01/2012

RF2906 **FREEWHEELING** **TX Ind. Haz Waste** **S102748132**
West **2404 SAN GABRIEL ST** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.136 mi.
717 ft. **Site 1 of 4 in cluster RF**

Actual:
598 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	FREEWHEELING
Address:	2404 SAN GABRIEL ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	61193
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	2404 San Gabriel, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	FREEWHEELING INC
Contact Name:	DAVID COLF
Contact Telephone Number:	Not reported
Mailing Address:	2404 SAN GABRIEL ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787054714
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	19554
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

FREEWHEELING (Continued) **S102748132**

Ind. Haz Waste:

Operator Name:	FREEWHEELING INC
Operator Address:	2404 SAN GABRIEL ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	32002037664
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	FREEWHEELING INC
Owner Mailing Address:	2404 SAN GABRIEL ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	32002037664
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2404 SAN GABRIEL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2404 SAN GABRIEL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	DAVID COLF
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	2404 SAN GABRIEL ST
Contact Address 2:	Not reported

FREEWHEELING (Continued) **S102748132**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100644533
Name:	FREEWHEELING
Address:	2404 SAN GABRIEL ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-4714
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600354757
Customer Name:	FREEWHEELING INC
Customer Legal Name:	Freewheeling, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2404 San Gabriel, Austin, TX

2907 ESE 1/8-1/4 0.137 mi. 722 ft. | **US DEPARTMENT OF JUSTICE** | **RCRA NonGen / NLR** | **1004601669**
55 N IH 35 | **TX0981903305**
AUSTIN, TX 78702

Actual: 460 ft.

Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Us Department Of Justice
Handler Address:	N IH 35
Handler City,State,Zip:	AUSTIN, TX 78702
EPA ID:	TX0981903305
Contact Name:	FREDERICK SMITH
Contact Address:	PO BOX 8
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Telephone:	512-482-5631
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Federal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 8
Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Name:	Us Department Of Justice

US DEPARTMENT OF JUSTICE (Continued) **1004601669**

Owner Type:	Federal
Operator Name:	Us Department Of Justice
Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned, The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	US DEPARTMENT OF JUSTICE
Legal Status:	Federal
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 8
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-482-5631
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

US DEPARTMENT OF JUSTICE (Continued) **1004601669**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NAME UNKNOWN
Legal Status: Federal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: US DEPARTMENT OF JUSTICE
Legal Status: Federal
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 8
Owner/Operator City,State,Zip: AUSTIN, TX 78767
Owner/Operator Telephone: 512-482-5631
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASPEN CORP.
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860930
Handler Name: US DOJ DEA AUSTIN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: US DEPARTMENT OF JUSTICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No

US DEPARTMENT OF JUSTICE (Continued) **1004601669**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

RG2908 **CAPITOL CITY CHEVRON** **TX HIST UST** **S128728843**
ENE **601 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.137 mi.
723 ft. **Site 1 of 4 in cluster RG**

Actual:
478 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CAPITOL CITY CHEVRON
Address:	601 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	878
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RE2909 **DELSTAR TECHNOLOGIES** **PFAS ECHO** **1027350428**
ESE **N/A**
1/8-1/4 **AUSTIN, TX**
0.141 mi.
744 ft. **Site 3 of 6 in cluster RE**

Actual:
661 ft.

Focus Map:
18

PFAS ECHO:

Name:	DELSTAR TECHNOLOGIES
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.216527
Longitude:	-97.765202
Count:	1
County:	TRAVIS
Status:	Active
Region:	06
Industry:	Plastics and Resins
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110005164838
Facility Percent Minority:	61.307
Facility Derived Tribes:	-
Facility Population:	5006.37

DELSTAR TECHNOLOGIES (Continued) **1027350428**

EPA Programs:	CWA; RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050408
Facility Derived CD113:	35
Facility Derived CB2010:	484530024031014
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	Y
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	TXR05AA42
CWA Permit Types:	Minor
CWA NAICS:	-
CWA SICS:	3089
RCRA IDS:	TXR000003426
RCRA Permit Types:	SQG
RCRA NAICS:	326199
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	N
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.765202,%22y%22:30.216527,%22spatialReference%22:%7B%22wk

DELSTAR TECHNOLOGIES (Continued) **1027350428**

id%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

2910 SSW 1/8-1/4 0.141 mi. 744 ft. **MABEL DAVIS PARK - CITY OF AUSTIN**
INT. OF WOODWARD & BEN WHITE BLVD.
AUSTIN, TX 78701
SEMS-ARCHIVE **1003874484**
TXD980623219

Actual: 558 ft.

Focus Map: 15

SEMS Archive:

Site ID:	0602524
EPA ID:	TXD980623219
Name:	MABEL DAVIS PARK - CITY OF AUSTIN
Address:	INT. OF WOODWARD & BEN WHITE BLVD.
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Cong District:	10
FIPS Code:	48453
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	06
Site ID:	0602524
EPA ID:	TXD980623219
Site Name:	MABEL DAVIS PARK - CITY OF AUSTIN
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1995-09-05 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	06
Site ID:	0602524
EPA ID:	TXD980623219
Site Name:	MABEL DAVIS PARK - CITY OF AUSTIN
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1979-08-01 04:00:00
Finish Date:	1979-08-01 04:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0602524
EPA ID:	TXD980623219
Site Name:	MABEL DAVIS PARK - CITY OF AUSTIN
NPL:	N

MABEL DAVIS PARK - CITY OF AUSTIN (Continued) **1003874484**

FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1979-05-01 04:00:00
Finish Date:	1979-05-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0602524
EPA ID:	TXD980623219
Site Name:	MABEL DAVIS PARK - CITY OF AUSTIN
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1979-07-01 04:00:00
Finish Date:	1979-07-01 04:00:00
Qual:	N
Current Action Lead:	St Perf

RE2911 **VERITIV CORPORATION** **RCRA-SQG** **1026727558**
ESE **210 E ST ELMO RD** **TXR000085481**
1/8-1/4 **AUSTIN, TX 78745**
0.142 mi.
750 ft. **Site 4 of 6 in cluster RE**

Actual:
662 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20210125
Handler Name:	Veritiv Corporation
Handler Address:	E ST ELMO RD
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXR000085481
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	X
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported

VERITIV CORPORATION (Continued) **1026727558**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210126
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20210125
Handler Name: VERITIV CORPORATION	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

VERITIV CORPORATION (Continued) **1026727558**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Federal or State Statute
Date Violation was Determined: 20201208
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20210816
Enforcement Responsible Agency: EPA
Enforcement Docket Number: 06-2021-0909
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: R6GS
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20201208
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20210816
Enforcement Responsible Agency: EPA
Enforcement Docket Number: 06-2021-0909
Enforcement Attorney: Not reported
Corrective Action Component: No

VERITIV CORPORATION (Continued) **1026727558**

Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: R6GS
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20201208
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: R6GS
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20201208
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: R6GS
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

RE2912 ESE 1/8-1/4 0.142 mi. 750 ft. | **VERITIV OPERATING**
210 E SAINT ELMO RD
AUSTIN, TX 78745

Site 5 of 6 in cluster RE

TX Ind. Haz Waste | **S127990656**
N/A

Actual: 662 ft.

Focus Map: 18

Ind. Haz Waste:

Name:	VERITIV OPERATING
Address:	210 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	97946
Registration Initial Notification Date:	05/10/2021
Registration Last Amendment Date:	05/10/2021
EPA Identification:	TXR000085559
Primary NAICS Code:	424110
Status Change Date:	20210510
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	VERITIV OPERATING COMPANY
Contact Name:	NATALIE HERNANDEZ
Contact Telephone Number:	512-7381564
Mailing Address:	210 E SAINT ELMO RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787451218
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	133283
Site Owner Tax ID:	135369500
Site Location Latitude:	-30.217
Site Location Longitude:	-97.765
Last Update to NOR Data:	20210914
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

VERITIV OPERATING (Continued) **S127990656**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	VERITIV OPERATING COMPANY
Operator Address:	210 E SAINT ELMO RD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-972-5155096
Operator Fax Number:	Not reported
Operator Email:	PHILLIP.BELCHER@VERITIVCORP.COM
Operator Business Type:	Corporation
Operator Tax ID:	11353695007
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	VERITIV OPERATING COMPANY
Owner Mailing Address:	210 E SAINT ELMO RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-972-5155096
Owner Fax:	Not reported
Owner Email Address:	PHILLIP.BELCHER@VERITIVCORP.COM
Owner Business Type:	Corporation
Owner Tax ID:	11353695007
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	205
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	MISC LAB PACK PRODUCTS AND MATERIALS
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20210510
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

VERITIV OPERATING (Continued) **S127990656**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	210 E SAINT ELMO RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-972-5155096
Contact Fax:	Not reported
Contact Email:	PHILLIP.BELCHER@VERITIVCORP.COM

Contact Name:	NATALIE HERNANDEZ
Contact Title:	OPERATIONS MANAGER
Contact Role:	PRICONT
Contact Address:	210 E SAINT ELMO RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-7381564
Contact Fax:	Not reported
Contact Email:	NATALIE.HERNANDEZ@VERITIVCORP.COM

Ind. Haz Waste:

Waste ID:	425168
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MISC LAB PACK WASTE FROM WAREHOUSE OPERATIONS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	424110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	NATALIE HERNANDEZ
Contact Title:	OPERATIONS MANAGER

VERITIV OPERATING (Continued) **S127990656**

Contact Telephone:	0-512-7381564 x0
Mailing Address:	210 E SAINT ELMO RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	Not reported
Principal Name:	VERITIV OPERATING COMPANY
Attention Name:	HERNANDEZ ,NATALIE
Attention Suffix:	Not reported

RE2913 **VERITIV OPERATING** **RCRA-SQG** **1026835239**
ESE **210 210 E SAINT ELMO RD** **TXR000085559**
1/8-1/4 **AUSTIN, TX 78745**
0.142 mi.
750 ft. **Site 6 of 6 in cluster RE**

Actual:
662 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20210510
Handler Name:	Veritiv Operating
Handler Address:	210 E SAINT ELMO RD
Handler City,State,Zip:	AUSTIN, TX 78745-1218
EPA ID:	TXR000085559
Contact Name:	NATALIE HERNANDEZ
Contact Address:	210 E SAINT ELMO RD
Contact City,State,Zip:	AUSTIN, TX 78745-1218
Contact Telephone:	512-738-1564
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	210 E SAINT ELMO RD
Mailing City,State,Zip:	AUSTIN, TX 78745-1218
Owner Name:	Veritiv Operating Company
Owner Type:	Private
Operator Name:	Veritiv Operating Company
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

VERITIV OPERATING (Continued) **1026835239**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220114
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: VERITIV OPERATING COMPANY	
Legal Status:	Private
Date Became Current:	20210510
Date Ended Current:	Not reported
Owner/Operator Address:	210 E SAINT ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745-1218
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: VERITIV OPERATING COMPANY	
Legal Status:	Private
Date Became Current:	20210510
Date Ended Current:	Not reported
Owner/Operator Address:	210 E SAINT ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745-1218
Owner/Operator Telephone:	972-515-5096
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

VERITIV OPERATING (Continued) **1026835239**

Owner/Operator Indicator: Owner
Owner/Operator Name: VERITIV OPERATING COMPANY
Legal Status: Private
Date Became Current: 20210510
Date Ended Current: Not reported
Owner/Operator Address: 210 E SAINT ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1218
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: VERITIV OPERATING COMPANY
Legal Status: Private
Date Became Current: 20210510
Date Ended Current: Not reported
Owner/Operator Address: 210 E SAINT ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1218
Owner/Operator Telephone: 972-515-5096
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20210510
Handler Name: VERITIV OPERATING COMPANY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210510
Handler Name: VERITIV OPERATING
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 42411
NAICS Description: PRINTING AND WRITING PAPER MERCHANT WHOLESALERS

NAICS Code: 424110

VERITIV OPERATING (Continued) **1026835239**

NAICS Description: PRINTING AND WRITING PAPER MERCHANT WHOLESALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

RG2914 ENE 1/8-1/4 0.143 mi. 754 ft. **EXXON #62790** **TX HIST UST** **S128728823**
619 N I 35 **N/A**
AUSTIN, TX

Site 2 of 4 in cluster RG

Actual: 479 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	EXXON #62790
Address:	619 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	719
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RH2915 WNW 1/8-1/4 0.143 mi. 754 ft. **AMERICAN CLEANERS** **TX DRYCLEANERS** **S109360701**
907 W 12TH ST **N/A**
AUSTIN, TX 78703

Site 1 of 4 in cluster RH

Actual: 478 ft.
Focus Map: 11

DRYCLEANERS:

Name:	AMERICAN CLEANERS
Address:	907 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961660
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

AMERICAN CLEANERS (Continued) **S109360701**

Name:	AMERICAN CLEANERS
Address:	907 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961660
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	907 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961660
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	907 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961660
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported

AMERICAN CLEANERS (Continued) **S109360701**

Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	907 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961660
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	INACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

RH2916 **AMERICAN CLEANERS** **RCRA-VSQG** **1010334309**
WNW **907 W 12TH STREET** **TXR000074021**
1/8-1/4 **AUSTIN, TX 78703**
0.143 mi.
754 ft. **Site 2 of 4 in cluster RH**

Actual:
478 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20060803
Handler Name:	American Cleaners
Handler Address:	W 12TH STREET
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXR000074021
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	E

AMERICAN CLEANERS (Continued) **1010334309**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	W 12TH STREET
Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20060804
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20060803
Handler Name:	AMERICAN CLEANERS
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator

AMERICAN CLEANERS (Continued) **1010334309**

State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

QX2917 **W.C. ROUNDTREE** **TX HIST UST** **S128729228**
East **900 E 5TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.146 mi.
770 ft. **Site 2 of 3 in cluster QX**

Actual:
470 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	W.C. ROUNDTREE
Address:	900 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0249
HID UST:	249
Inspection:	02/25/2009
Due:	02/25/2012

QX2918 **SOUTHERN PACIFIC TRANSPT** **TX HIST UST** **S128728937**
East **900 E 5TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.146 mi.
770 ft. **Site 3 of 3 in cluster QX**

Actual:
470 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SOUTHERN PACIFIC TRANSPT
Address:	900 E 5TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0163
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2919 ESE 1/8-1/4 0.146 mi. 773 ft. | **AUSTIN WASTE OIL SERVICE**
7300B MARCELL ST
AUSTIN, TX 78752 | **TX Ind. Haz Waste** | **S103604768**
N/A

Actual: 729 ft.

Focus Map: 6

Ind. Haz Waste:

Name:	AUSTIN WASTE OIL SERVICE
Address:	7300B MARCELL ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	40706
Registration Initial Notification Date:	04/16/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850416
Land Type:	Not reported
Description of Facility Site Location:	7300B Marcell Street, Austin Texas 78752
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	AUSTIN WASTE OIL SERVICE
Contact Name:	WALTER MARTIN JR
Contact Telephone Number:	512-4514161
Mailing Address:	7300B MARCELL ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787522324
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17121
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021106
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	1
Transport Own Waste:	0

AUSTIN WASTE OIL SERVICE (Continued) **S103604768**

Ind. Haz Waste:

Operator Name:	AUSTIN WASTE OIL SERVICE
Operator Address:	7300B MARCELL ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4514161
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN WASTE OIL SERVICE
Owner Mailing Address:	7300B MARCELL ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4514161
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	7300B MARCELL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4514161
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	7300B MARCELL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4514161
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WALTER MARTIN JR
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	7300B MARCELL ST
Contact Address 2:	Not reported

AUSTIN WASTE OIL SERVICE (Continued) **S103604768**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4514161
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WALTER MARTIN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	7300B MARCELL ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4514161
Contact Fax:	Not reported
Contact Email:	Not reported

QH2920 **RED MCCOMBS COLLISDION CENTER** **TX Ind. Haz Waste** **S110294567**
WNW **841 W 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.147 mi.
778 ft. **Site 2 of 3 in cluster QH**

Actual:
474 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	RED MCCOMBS COLLISDION CENTER
Address:	841 W 6TH ST
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	83309
Registration Initial Notification Date:	07/05/1994
Registration Last Amendment Date:	05/08/1997
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19940705
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	RED MCCOMBS COLLISDION CENTER
Contact Name:	Not reported
Contact Telephone Number:	512-4783312
Mailing Address:	841 W 6TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787035403
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

RED MCCOMBS COLLISDION CENTER (Continued) **S110294567**

TNRCC Facility ID:	100222
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	19970807
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	RED MCCOMBS COLLISDION CENTER
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	PRICONT
Contact Address:	841 W 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4783312
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	115026
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Paint waste/painting operations
Standard Industrial Code:	55110
Primary Source:	G06

RED MCCOMBS COLLISDION CENTER (Continued) **S110294567**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	441110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

QH2921 **RED MCCOMBS COLLISION CENTER** **TX HIST UST** **1000305414**
WNW **841 W 6TH STREET** **RCRA NonGen / NLR** **TXD980879795**
1/8-1/4 **AUSTIN, TX 78703** **FINDS**
0.147 mi. **ECHO**
778 ft. **Site 3 of 3 in cluster QH** **TX Ind. Haz Waste**

Actual:
474 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TOWN LAKE CHRYSLER PLYMOUTH
Address:	841 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX032
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RCRA Listings:

Date Form Received by Agency:	20000517
Handler Name:	Red Mccombs Collision Center
Handler Address:	W 6TH STREET
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD980879795
Contact Name:	LARRY NIX
Contact Address:	WEIDEMAR LANE
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-478-8609
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	WEIDEMAR LANE

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Red Mccombs Collision Center
Owner Type:	Not reported
Operator Name:	Red Mccombs Collision Center
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RED MCCOMBS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RED MCCOMBS COLLISION CENTER	
Legal Status:	Not reported
Date Became Current:	20000517
Date Ended Current:	Not reported
Owner/Operator Address:	4901 WEIDEMAR LANE
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-478-8609
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Owner/Operator Indicator: Operator
Owner/Operator Name: RED MCCOMBS COLLISION CENTER
Legal Status: Not reported
Date Became Current: 20000517
Date Ended Current: Not reported
Owner/Operator Address: 4901 WEIDEMAR LANE
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-478-8609
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19980114
Handler Name: RED MCCOMBS COLLISION CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000517
Handler Name: RED MCCOMBS COLLISION CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44111
NAICS Description: NEW CAR DEALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005081516

Click Here for FRS Facility Detail Report:

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000305414
Registry ID:	110005081516
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005081516
Name:	RED MCCOMBS COLLISION CENTER
Address:	841 W 6TH STREET
City,State,Zip:	AUSTIN, TX 78703

Ind. Haz Waste:

Name:	RED MCCOMBS COLLISION CENTER
Address:	841 W 6TH ST
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66194
Registration Initial Notification Date:	09/24/1986
Registration Last Amendment Date:	05/17/2000
EPA Identification:	TXD980879795
Primary NAICS Code:	441110
Status Change Date:	19860924
Land Type:	Not reported
Description of Facility Site Location:	841 W 6th Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	RED MCCOMBS COLLISION CENTER
Contact Name:	LARRY NIX
Contact Telephone Number:	512-4788609
Mailing Address:	4901 WEIDEMAR LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787452452
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21490
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Last Update to NOR Data:	20011023
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	RED MCCOMBS COLLISION CENTER
Operator Address:	4901 WEIDEMAR LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4788609
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	RED MCCOMBS COLLISION CENTER
Owner Mailing Address:	4901 WEIDEMAR LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4788609
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	4901 WEIDEMAR LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4788609
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

Contact Role:	OWNCON
Contact Address:	4901 WEIDEMAR LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4788609
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LARRY NIX
Contact Title:	DIRECTOR
Contact Role:	PRICONT
Contact Address:	4901 WEIDEMAR LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4788609
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	161678
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Paint waste/painting operations
Standard Industrial Code:	55110
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	441110
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4901 WEIDEMAR LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745

RED MCCOMBS COLLISION CENTER (Continued) **1000305414**

AR Number:	0000302653
Principal Name:	RED MCCOMBS COLLISION CENTER
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	4901 WEIDEMAR LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000302653
Principal Name:	RED MCCOMBS COLLISION CENTER
Attention Name:	Not reported
Attention Suffix:	NWG

RF2922 **EXXON CO. USA 64674** **TX HIST UST** **S110294323**
West **1004 W 24TH ST** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.151 mi.
799 ft. **Site 2 of 4 in cluster RF**

Actual:
597 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	GLEN HILL EXXON
Address:	1004 W 24TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0151
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	EXXON CO. USA 64674
Address:	1004 W 24TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	77513
Registration Initial Notification Date:	07/26/1991
Registration Last Amendment Date:	07/26/1991
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	20130128
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported

EXXON CO. USA 64674 (Continued) **S110294323**

Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXON CO USA 64674
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	Not reported
Mailing Address2:	Not reported
Mailing City,State,Zip:	Not reported
Mailing County:	Not reported
Facility Country:	UNITED STATES
TNRCC Facility ID:	31741
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20130128
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Owner Name:	EXXON CO USA 64674
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported

EXXON CO. USA 64674 (Continued) **S110294323**

Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

RF2923 **EXXON MOBIL** **TX Ind. Haz Waste** **S102757816**
West **1004 W 24TH ST** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.151 mi.
799 ft. **Site 3 of 4 in cluster RF**

Actual:
597 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	EXXON MOBIL
Address:	1004 W 24TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	77127
Registration Initial Notification Date:	06/28/1991
Registration Last Amendment Date:	11/29/2005
EPA Identification:	TXD988031936
Primary NAICS Code:	Not reported
Status Change Date:	19910628
Land Type:	PRIVATE
Description of Facility Site Location:	1004 W 24th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6567709
Mailing Address:	PO BOX 4415
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 772104415
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	31435
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000

EXXON MOBIL (Continued) **S102757816**

Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 4415
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77210
Operator Country:	UNITED STA
Operator Telephone:	1-713-6567709
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 4415
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Country:	UNITED STA
Owner Telephone:	1-713-6567709
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported

EXXON MOBIL (Continued) **S102757816**

Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 4415
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 4415
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	STAFF ASSISTANT
Contact Role:	PRICONT
Contact Address:	PO BOX 4415
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

RF2924 **EXXON MOBIL CORPORATION** **RCRA NonGen / NLR** **1004785571**
West **1004 W 24TH ST** **FINDS** **TXD988031936**
1/8-1/4 **AUSTIN, TX 78705** **ECHO**
0.151 mi.
799 ft. **Site 4 of 4 in cluster RF**

Actual:
597 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20051129
Handler Name:	Exxon Mobil Corporation
Handler Address:	W 24TH ST
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TXD988031936
Contact Name:	ALDA S POOL
Contact Address:	PO BOX 4415
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Telephone:	713-656-7709
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 4415
Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Name:	Exxon Mobil Corporation
Owner Type:	Private
Operator Name:	Exxon Mobil Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

EXXON MOBIL CORPORATION (Continued) **1004785571**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20051206
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON CO USA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4415
Owner/Operator City,State,Zip:	HOUSTON, TX 77210
Owner/Operator Telephone:	713-656-7761
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4415
Owner/Operator City,State,Zip:	HOUSTON, TX 77210
Owner/Operator Telephone:	713-656-7709
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: EXXON MOBIL CORPORATION	
Legal Status:	Private
Date Became Current:	20010823

EXXON MOBIL CORPORATION (Continued) **1004785571**

Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4415
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4415
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EXXON MOBIL CORPORATION
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 4415
Owner/Operator City,State,Zip: HOUSTON, TX 77210
Owner/Operator Telephone: 713-656-7709
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910401
Handler Name: EXXON CO USA #64674
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

EXXON MOBIL CORPORATION (Continued) **1004785571**

Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: EXXON MOBIL CORPORATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005132383

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004785571
Registry ID: 110005132383
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005132383
Name: EXXON MOBIL CORPORATION
Address: 1004 W 24TH ST
City,State,Zip: AUSTIN, TX 78705

2925 ESE 1/8-1/4 0.155 mi. 816 ft. | **EMIL HAENEL, JR.**
311 E 15TH ST
AUSTIN, TX | **TX HIST UST** | **S111678638**
N/A

Actual: 500 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	EMIL HAENEL, JR.
Address:	311 E 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0936
HID UST:	936
Inspection:	Not reported
Due:	06/01/2012

RI2926 WNW 1/8-1/4 0.156 mi. 825 ft. | **THE HERTZ CORPORATION**
9401 RENTAL CAR LANE
AUSTIN, TX 78719
Site 1 of 2 in cluster RI | **TX HIST UST**
TX TIER 2 | **S108885815**
N/A

Actual: 507 ft.
Focus Map: 20

HIST UST AUSTIN:

Name:	HERTZ RENT A CAR
Address:	9401 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX
Id UST:	A0022
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TIER 2:

Facility Id/Name:	FATR20118EF5VF002FWK/THE HERTZ CORPORATION
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012
Date Tier 2 Signed:	2-17-2012
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Robert Sala
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported

THE HERTZ CORPORATION (Continued) **S108885815**

Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR20107NDLPZ002Z5A/THE HERTZ CORPORATION
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	01/10/2011
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	120
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Amber Anderson
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR20096YDRL6002Q20/HERTZ CORPORATION
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	1/4/2010
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	50.00
Number Of Employess On Site:	130
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Amber Anderson
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported

THE HERTZ CORPORATION (Continued) **S108885815**

Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR200968XVYX002BQB/HERTZ CORPORATION
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	Not reported
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	130
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported
Facility Id/Name:	FATR200868XVYX002BQB/HERTZ CORPORATION
Reporting Year:	2008
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/30/2009
Date Tier 2 Signed:	1/6/2009
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	130
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Amber Anderson
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported

THE HERTZ CORPORATION (Continued) **S108885815**

Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20064Y98ZD002F9E/THE HERTZ CORPORATION
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	2/22/2007
Mailing Address:	Not reported
Mailing City/State/Country:	Not reported
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	153
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Robert Sala , City Manager
Latitude:	30.2094
Longitude:	97.6713
Lat/Long Location Desc:	AB - Administrative Building
Lat/Long Method:	G4 - GPS (Precise Positioning Service)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes:	Not reported
Validation:	Not reported

Notes:	Not reported
Validation:	This facility passed all validation checks.

Facility Info:

Id:	7514
Id Type:	SIC
Description:	Not reported
Last Modified:	1/6/2009
Id:	532111
Id Type:	NAICS
Description:	Passenger Car Rental
Last Modified:	1/6/2009
Id:	Not reported
Id Type:	Not reported
Description:	Not reported
Last Modified:	1/6/2009
Id:	6985196

THE HERTZ CORPORATION (Continued) **S108885815**

Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/6/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	Amber Anderson
Title:	Area Manager
Modification Date:	2/8/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	Richard Jellison
Title:	Maint Manager
Modification Date:	2/8/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	The Hertz Corporation
Title:	Not reported
Modification Date:	2/8/2010

Chemical Inventory:

Facility Id:	FATR200968XVYX002BQB
Chemical Name:	FUELS, GASOLINE-unleaded
Chemical Inv Record Id:	CVTR200968XW7F00FQJT
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/8/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T

THE HERTZ CORPORATION (Continued) **S108885815**

Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200968XWDE00GVRM
Chemical Inventory Record Id:	CVTR200968XW7F00FQJT
Amt Of Sub Stored Or Transported:	18000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	3 tanks SW corner of service center lot
Last Modified:	2/8/2010

Facility Id:	FATR200968XVYX002BQB
Chemical Name:	PETROLEUM LUBRICATING OIL
Chemical Inv Record Id:	CVTR200968XWKW00HFUD
CAS Number:	7440-66-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	2/8/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200968XWPD00JHCM
Chemical Inventory Record Id:	CVTR200968XWKW00HFUD
Amt Of Sub Stored Or Transported:	500
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	SE corner of Maint fluids room

THE HERTZ CORPORATION (Continued) **S108885815**

Last Modified: 2/8/2010

Notes: Not reported

Validation: Signature is required for submission. Date Signed is required for submission.

Facility Info:
Id: 6985196
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 2/17/2012
Id: 532111
Id Type: NAICS
Description: Passenger Car Rental
Last Modified: 2/17/2012
Id: 7514
Id Type: SIC
Description: PASSENGER CAR RENTAL
Last Modified: 2/17/2012

Contact:
Contact Email: rsala@hertz.com
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin, TX 78719
Contact Mail Country: USA
Contact Type 1: Submitter
Contact Name: Robert Sala
Title: Area Manager
Modification Date: 2/17/2012

Contact:
Contact Email: lherbst@hertz.com
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin, TX 78719
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: Larry Herbst
Title: Maint Manager
Modification Date: 2/24/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin, TX 78719
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: The Hertz Corporation
Title: Owner/Operator
Modification Date: 2/24/2012

Chemical Inventory:
Facility Id: FATR20118EF5VF002FWK

THE HERTZ CORPORATION (Continued) **S108885815**

Chemical Name:	PETROLEUM LUBRICATING OIL
Chemical Inv Record Id:	CVTR20118EF7YP00K2SP
CAS Number:	7440-66-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	2/24/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EF87Z00L3RG
Chemical Inventory Record Id:	CVTR20118EF7YP00K2SP
Amt Of Sub Stored Or Transported:	500
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	SE corner of Maint fluid room
Last Modified:	2/24/2012

Mixture:

Record Key:	CMTR20118EF8C500MQGQ
Chemical Inv Record Id:	CVTR20118EF7YP00K2SP
Mix Chemical:	Component
Percentage:	Not reported
Facility Id:	FATR20118EF5VF002FWK
Mixture Cas:	7440-66-6
Weight/Volume:	Not reported
Mixture Ehs:	T
Mixture Last Modified:	2/24/2012

Facility Id:	FATR20118EF5VF002FWK
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR20118EF8K600NTHB
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported

THE HERTZ CORPORATION (Continued) **S108885815**

Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	2/24/2012
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2011
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20118EF8PP00PQEM
Chemical Inventory Record Id:	CVTR20118EF8K600NTHB
Amt Of Sub Stored Or Transported:	18000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	3 Tanks NW corner of service center lot
Last Modified:	2/24/2012

Mixture:

Record Key:	CMTR20118EF8WK00RNKT
Chemical Inv Record Id:	CVTR20118EF8K600NTHB
Mix Chemical:	component
Percentage:	Not reported
Facility Id:	FATR20118EF5VF002FWK
Mixture Cas:	8006-61-9
Weight/Volume:	Not reported
Mixture Ehs:	T
Mixture Last Modified:	2/24/2012

Notes: Not reported
Validation: Not reported

Facility Info:

Id:	6985196
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/4/2010
Id:	7514
Id Type:	SIC
Description:	PASSENGER CAR RENTAL
Last Modified:	1/4/2010
Id:	532111
Id Type:	NAICS
Description:	Passenger Car Rental
Last Modified:	1/4/2010

THE HERTZ CORPORATION (Continued) **S108885815**

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	Amber Anderson
Title:	Area Manager
Modification Date:	1/20/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Emergency Contact
Contact Name:	Larry Herbst
Title:	Maint. Manager
Modification Date:	1/20/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	9401 Rental Car Lane
Contact City/State/Zip:	Austin, TX 78719
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	The Hertz Corporation
Title:	Not reported
Modification Date:	1/20/2010

Chemical Inventory:

Facility Id:	FATR20096YDRL6002Q20
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR20096YDRVV00G351
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	1/20/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported

THE HERTZ CORPORATION (Continued) **S108885815**

Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20096YDS2000HDZF
Chemical Inventory Record Id:	CVTR20096YDRVV00G351
Amt Of Sub Stored Or Transported:	18000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	3 tanks SW corner of service center lot
Last Modified:	1/20/2010

Mixture:

Record Key:	CMTR20096YDS3800JG3V
Chemical Inv Record Id:	CVTR20096YDRVV00G351
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR20096YDRL6002Q20
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	1/20/2010

Facility Id:	FATR20096YDRL6002Q20
Chemical Name:	PETROLEUM LUBRICATING OIL
Chemical Inv Record Id:	CVTR20096YDS5A00L8LV
CAS Number:	7440-66-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	1/20/2010
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20096YDS8200MN69

THE HERTZ CORPORATION (Continued) **S108885815**

Chemical Inventory Record Id: CVTR20096YDS5A00L8LV
Amt Of Sub Stored Or Transported: 500
Amount Units: gallons
Type Of Storage: Above ground tank
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: SE corner of Maint fluid room
Last Modified: 1/20/2010

Notes: Not reported

Validation: This facility passed all validation checks.

Facility Info:
Id: 7514
Id Type: SIC
Description: PASSENGER CAR RENTAL
Last Modified: 1/10/2011
Id: 532111
Id Type: NAICS
Description: Passenger Car Rental
Last Modified: 1/10/2011
Id: 6985196
Id Type: Dun & Bradstreet
Description: Not reported
Last Modified: 1/10/2011

Contact:
Contact Email: lherbst@hertz.com
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin, TX 78719
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Name: Larry Herbst
Title: Maint Manager
Modification Date: 2/3/2011

Contact:
Contact Email: Not reported
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin, TX 78716
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: The Hertz Corporation
Title: Not reported
Modification Date: 2/3/2011

Contact:
Contact Email: alanderson@hertz.com
Contact Mail Address: 9401 Rental Car Lane
Contact City/State/Zip: Austin 78719
Contact Mail Country: USA

THE HERTZ CORPORATION (Continued) **S108885815**

Contact Type 1:	Submitter
Contact Name:	Amber Anderson
Title:	Area Manager
Modification Date:	1/10/2011

Chemical Inventory:

Facility Id:	FATR20107NDLPZ002Z5A
Chemical Name:	FUELS, GASOLINE
Chemical Inv Record Id:	CVTR20107NDMQ000EDJM
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	100,000 - 999,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	Not reported
Last Modified:	2/3/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20107NDN4800HQ63
Chemical Inventory Record Id:	CVTR20107NDMQ000EDJM
Amt Of Sub Stored Or Transported:	18000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	3 tanks SW corner of service center lot
Last Modified:	2/3/2011

Mixture:

Record Key:	CMTR20107NDN6V00JZVM
Chemical Inv Record Id:	CVTR20107NDMQ000EDJM
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR20107NDLPZ002Z5A
Mixture Cas:	8006-61-9
Weight/Volume:	Not reported
Mixture Ehs:	T
Mixture Last Modified:	2/3/2011

Facility Id:	FATR20107NDLPZ002Z5A
Chemical Name:	PETROLEUM LUBRICATING OIL

THE HERTZ CORPORATION (Continued) **S108885815**

Chemical Inv Record Id:	CVTR20107NDN7W00KVGJ
CAS Number:	7440-66-6
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/3/2011
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	Not reported
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	T
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20107NDNBS00L8D8
Chemical Inventory Record Id:	CVTR20107NDN7W00KVGJ
Amt Of Sub Stored Or Transported:	500
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	SE corner of Maint fluid room
Last Modified:	2/3/2011

Mixture:

Record Key:	CMTR20107NDNDF00MPC7
Chemical Inv Record Id:	CVTR20107NDN7W00KVGJ
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR20107NDLPZ002Z5A
Mixture Cas:	7440-66-6
Weight/Volume:	Not reported
Mixture Ehs:	T
Mixture Last Modified:	2/3/2011

Notes: Not reported
Validation: Not reported

RI2927 **HERTZ RENT-A-CAR 1636** **TX AST** **A100182339**
WNW **9401 RENTAL CAR LN** **N/A**
1/8-1/4 **AUSTIN, TX 78719**
0.156 mi.
825 ft. **Site 2 of 2 in cluster RI**

Actual:
507 ft.

Focus Map:
20

AST:

Name:	HERTZ RENT-A-CAR 1636
Address:	9401 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX 787192312
Facility ID:	109681
Additional ID:	665074622002087
AI Number:	72074
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78719
Contact Name/Title:	PAUL GIORDANA/
Contact Organization Name:	HERTZ RENT-A-CAR 1636
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5125303600
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	11/11/2016
Signature First Name on Earliest Reg Form:	ALEX
Application Received Date on Earliest Reg Form:	11/17/2016
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	DODARD
Signature Title on Earliest Reg Form:	Not reported
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	109681
Tank ID:	1
AST ID:	190910
AI Number:	72074
Install Date:	05/19/1999
Tank Registration Date:	06/04/1999
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/23/2016
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000

HERTZ RENT-A-CAR 1636 (Continued) **A100182339**

Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	109681
Tank ID:	2
AST ID:	190911
AI Number:	72074
Install Date:	05/19/1999
Tank Registration Date:	06/04/1999
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	05/19/1999
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	109681
Tank ID:	3
AST ID:	190912
AI Number:	72074
Install Date:	05/19/1999
Tank Registration Date:	06/04/1999
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/23/2016
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N

HERTZ RENT-A-CAR 1636 (Continued) **A100182339**

Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

2928 North 1/8-1/4 0.158 mi. 833 ft.

Actual: 759 ft.

Focus Map: 2

CARMAX 7154
13300 N IH 35
AUSTIN, TX 78753

TX UST **U003974635**
TX HIST UST **N/A**
TX AIRS
TX Financial Assurance
TX Ind. Haz Waste
TX PST STAGE 2
TX COMP HIST
TX CENTRAL REGISTRY
TX NON REGIST PST

UST:

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 787531073
AI Number:	76495
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	731446322006201
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	NICK LINGGAJAYA,OPS MGR
Contact Organization Name:	CARMAX 7154
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128732315
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	ENVIRONMENTAL@CARMAX.COM
Signature Date On Earliest Reg Form:	02/28/2022
Signature Name/Title On Earliest Reg Form:	CHRISTINA MCCLELLAND,SNR EHS MGR
Application Received Date On Earliest Reg Form:	02/28/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	166396902001309

CARMAX 7154 (Continued) **U003974635**

Additional ID:	731446322006201
Ai Number:	76495
Operator CN:	CN600366355
Operator Name:	CARMAX AUTO SUPERSTORES INC
Operator Effective Begin Date:	08/31/1987
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	CHRISTINA MCCLELLAND/SNR ENV MGR
Contact Organization Name:	CARMAX AUTO SUPERSTORES INC
Contact Mailing Address (Delivery):	12800 TUCKAHOE CREEK PKWY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	RICHMOND VA 23238-1115
Contact Phone Country Code:	1
Contact Phone Area Code:	804
Contact Phone Number:	7470422
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	ENVIRONMENTAL@CARMAX.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600366355
Owner Last Name:	CARMAX AUTO SUPERSTORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	12800 TUCKAHOE CREEK PKWY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	RICHMOND
Contact Mailing State:	VA
Contact Mailing Zip:	23238
Contact Mailing Zip5:	1115
Contact Phone Number/Ext:	1 804 7470422/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	ENVIRONMENTAL@CARMAX.COM
Contact Address Deliverable:	Not reported
Princ ID:	166396902001309
Additional ID:	731446322006201
AI Number:	76495
Owner Effective Begin Date:	08/31/1987
State Tax ID:	15406499499
Contact Role:	OWNOPRCON
Contact Name/Title:	CHRISTINA MCCLELLAND/SNR ENV MGR
Contact Organization Name:	CARMAX AUTO SUPERSTORES INC

Self Certification:

Self Cert ID:	117431
Cert ID:	368833
AI Number:	76495
Self Certification Date:	02/28/2022
Signature Name/Title:	CHRISTINA MCCLELLAND SNR EHS MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	350926
AI Number:	76495
Self Certification Date:	02/24/2021
Signature Name/Title:	JOHANNA GRISCNIK SR ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	333049
AI Number:	76495
Self Certification Date:	01/27/2020
Signature Name/Title:	JOHANNA GRISCIK SENIOR EM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	316130
AI Number:	76495
Self Certification Date:	01/30/2019
Signature Name/Title:	JOHANNA GRISCIK SENIOR ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	299269
AI Number:	76495
Self Certification Date:	01/29/2018
Signature Name/Title:	JOHANNA GRISCIK ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	282021
AI Number:	76495
Self Certification Date:	01/27/2017
Signature Name/Title:	JOHANNA GRISCIK ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	265065
AI Number:	76495
Self Certification Date:	01/15/2016
Signature Name/Title:	JOHANNA GRISCIK ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	248057
AI Number:	76495
Self Certification Date:	01/12/2015
Signature Name/Title:	JOHANNA GRISCIK ENVIR PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/29/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	231503
AI Number:	76495
Self Certification Date:	01/22/2014
Signature Name/Title:	JOHANNA GRISCIK EN PR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	117431
Cert ID:	208940
AI Number:	76495
Self Certification Date:	01/09/2013
Signature Name/Title:	JOHANNA GRICIK ENV PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208939
AI Number:	76495
Self Certification Date:	01/17/2012
Signature Name/Title:	ALI WOODWORTH EHS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208938
AI Number:	76495
Self Certification Date:	01/03/2011
Signature Name/Title:	ALI WOODWORTH EH&S MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208937
AI Number:	76495
Self Certification Date:	01/11/2010
Signature Name/Title:	ALI WOODWORTH EH&S MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208936
AI Number:	76495
Self Certification Date:	12/31/2008
Signature Name/Title:	ALI WOODWORTH EH&S MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208935
AI Number:	76495
Self Certification Date:	01/09/2008
Signature Name/Title:	ALI WOODWORTH MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208934
AI Number:	76495
Self Certification Date:	06/04/2007
Signature Name/Title:	ALI WOODWORTH ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208933
AI Number:	76495
Self Certification Date:	01/13/2006
Signature Name/Title:	ALI WOODWORTH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208932
AI Number:	76495
Self Certification Date:	01/17/2005
Signature Name/Title:	ALI WOODWORTH EH&S COORDINATOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	117431
Cert ID:	208931
AI Number:	76495
Self Certification Date:	05/05/2004
Signature Name/Title:	PAT GANGWER EHS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER

CARMAX 7154 (Continued) **U003974635**

Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	03/24/2004
Tank Registration Date:	05/10/2004
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	203143
Facility ID:	117431
Ai Number:	76495
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	03/24/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

CARMAX 7154 (Continued) **U003974635**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/21/2004

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	184091
UST ID:	203143
AI Number:	76495
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

CARMAX 7154 (Continued) **U003974635**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	04/13/2004

Construction Notification:

NOC ID:	21122
Facility ID:	117431
AI Number:	76495
Application Received Date:	01/30/2004
Scheduled Construction Date:	02/29/2004
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M40130005
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	34180
UST ID:	203143
NOC ID:	Not reported
AI Number:	76495
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	precision Fuels, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported

CARMAX 7154 (Continued) **U003974635**

Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	22209
UST ID:	Not reported
NOC ID:	21122
AI Number:	76495
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	49336
UST ID:	203143
NOC ID:	Not reported
AI Number:	76495
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002129
Company Name:	Not reported
Representative Name:	ERNEST VASQUEZ
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CARMAX AUTO SUPERSTORES INC
Contact Mailing Address (Delivery):	12800 TUCKAHOE CREEK PKWY
Contact Mailing Address (Internal Delivery):	Not reported

CARMAX 7154 (Continued) **U003974635**

Contact Mailing City/State/Zip:	RICHMOND, VA 23238 1115
Phone Number/Ext:	804 7470422/6115
Contact Fax Number/Ext:	/
Contact Email Address:	ENVIRONMENTAL@CARMAX.COM
Contact Address Deliverable:	Y
Facility ID:	117431
Additional ID:	731446322006201
Princ ID:	166396902001309
AI Number:	76495
Facility Name:	CARMAX 7154
AR Number:	50232
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	CHRISTINA MCCLELLAND/SNR EHS MGR

HIST UST AUSTIN:

Name:	CARMAX #7154
Address:	13300 N. IH 35
City,State,Zip:	AUSTIN, TX
Id UST:	3293
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AIRS:

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	TX
Permit Num:	71896
Regulated Id:	RN105001614
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	05/13/2004
Expiration Date:	12/31/3000
Customer Id:	CN600366355
Company Name:	CARMAX AUTO SUPERSTORES INC
Physical Location Desc:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35
Rep Official(RO):	BACKGROUND SCREENING AND EHS MANAGER
RO Name:	MR PAT GANGWER
RO Delivery Address:	4900 COX RD
RO City/State/Zip:	GLEN ALLEN, V 23060-650
RO Phone:	Not reported
RO Ext Num:	6163
RO EMail Address:	Not reported
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

TX Financial Assurance 2:

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	266089

CARMAX 7154 (Continued) **U003974635**

AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	Not reported
Policy Number:	STPE78425300
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	246819
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224011
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	227891
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019

CARMAX 7154 (Continued) **U003974635**

Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224010
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	209768
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224009
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	192661
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224 008
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

CARMAX 7154 (Continued) **U003974635**

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	175125
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224 007
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	156822
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224006
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	139351
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

CARMAX 7154 (Continued) **U003974635**

Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	UST G24893224 005
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	122355
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	Not reported
Policy Number:	ustg24893224004
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	16061
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000

CARMAX 7154 (Continued) **U003974635**

Policy Number:	UST G24893224 003
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	97834
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G24893224 001
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	97835
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 770 9556895
Policy Number:	USC 5337829-06
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753

CARMAX 7154 (Continued) **U003974635**

Region:	2
Facility ID:	117431
Finass ID:	98059
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 770 9556895
Policy Number:	USC5337829-05
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	98058
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 770 9556895
Policy Number:	USC5337829-05
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	98060
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

CARMAX 7154 (Continued) **U003974635**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 770 9556895
Policy Number:	USC5337829-04
Coverage Amount:	2000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117431
Finass ID:	98061
AI:	76495
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	02/28/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Ind. Haz Waste:

Name:	CARMAX AUTO SUPERSTORES 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	87436
Registration Initial Notification Date:	03/16/2004
Registration Last Amendment Date:	07/30/2018
EPA Identification:	TXR000057786
Primary NAICS Code:	441120
Status Change Date:	20040316
Land Type:	PRIVATE
Description of Facility Site Location:	13300 N I H 35, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1

CARMAX 7154 (Continued) **U003974635**

Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CARMAX AUTO SUPERSTORES INC
Contact Name:	ALI WOODWORTH
Contact Telephone Number:	804-7470422-6293
Mailing Address:	12800 TUCKAHOE CREEK PKWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	RICHMOND, VA 232381115
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	117352
Site Owner Tax ID:	540649949
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20180731
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	CARMAX AUTO SUPERSTORES INC
Operator Address:	13300 NIH 35
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-804-7470422
Operator Fax Number:	1-804-9356158
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	15406499499
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CARMAX AUTO SUPERSTORES INC
Owner Mailing Address:	12800 TUCKAHOE CREEK PKWY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	RICHMOND, VA 23238
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	1-804-9356158

CARMAX 7154 (Continued) **U003974635**

Owner Email Address:	pat-gangwer@carmax.com
Owner Business Type:	Corporation
Owner Tax ID:	15406499499
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	25
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Paint/painter thinner waste sotred in 55 gallon container until removal by Safet
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20040316
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	13300 NIH 35
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-804-7470422
Contact Fax:	1-804-9356158
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	12800 TUCKAHOE CREEK PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	RICHMOND, VA 23238
Contact Phone:	Not reported
Contact Fax:	1-804-9356158
Contact Email:	pat-gangwer@carmax.com

Contact Name:	ALI WOODWORTH

CARMAX 7154 (Continued) **U003974635**

Contact Title:	ENVIRONMENTAL MGR
Contact Role:	PRICONT
Contact Address:	12800 TUCKAHOE CREEK PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	RICHMOND, VA 23238
Contact Phone:	1-804-7470422 x6293
Contact Fax:	1-804-9356158 x6293
Contact Email:	ali_woodworth@carmax.com

Ind. Haz Waste:

Waste ID:	204550
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Touch up painting process generates paint thinner waste. anticipated date 7/15/
Standard Industrial Code:	55110
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	441120
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

PST STAGE 2:

Regulated Number:	RN105001614
Region Location:	11
Has Active Violation:	NO
PST ID:	76495
Start Date:	08/31/1987
Stage 2 Type:	BALANCE SYSTEM
Stage 2 Install Date:	04/13/2004
Last Inspection Activity:	Not reported
EACT Status:	ACTIVE
ADDN ID:	76495
Last Inspection Number:	Not reported
Last Inspection Status Date:	Not reported
Last Inspection Status:	Not reported
Last Inspection Activity 2:	Not reported

CARMAX 7154 (Continued) **U003974635**

Last Inspection Conducted By:	Not reported
Facility Not Inspected:	Not reported
Facility Not Inspected Reason:	Not reported
ADDN Status:	ACTIVE
Status:	ACTIVE
Signed Date:	01/30/2019
Expired Date:	02/29/2020
Tank Status:	IN USE
Type:	RETAIL
UST Number:	1
Latitude:	0
Longitude:	0

Stage2 Detail:

RN:	RN105001614
Reg Status:	FULLY REGULATED
CN:	CN600366355
Princ Name:	CARMAX AUTO SUPERSTORES INC
Princ Legal Name:	Carmax Auto Superstores, Inc.
Role:	OWN
First Name:	Not reported
Middle Name:	Not reported
Last Name:	Not reported
PST UST ID:	203143
UST Tank ID:	1
Num UST Comprt:	1
Install Date:	03/24/2004
Regis Date:	05/10/2004
Capacity Qty:	12000
Substance Type:	GASOLINE

COMP HIST:

RN Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600366355
CN Name:	CARMAX AUTO SUPERSTORES INC
CN Rating:	.5
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811121
SIC Code:	6552
Related Number:	68119,71896,76495,76495

CENTRAL REGISTRY:

Regulated Entity Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35

CARMAX 7154 (Continued) **U003974635**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1073
Status:	ACTIVE
Status Date:	7/20/2006
Customer Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Legal Name:	Carmax Auto Superstores, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35

Regulated Entity Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1073
Status:	ACTIVE
Status Date:	7/20/2006
Customer Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Legal Name:	Carmax Auto Superstores, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35

Regulated Entity Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1073
Status:	ACTIVE
Status Date:	7/20/2006
Customer Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Legal Name:	Carmax Auto Superstores, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35

Regulated Entity Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1073
Status:	ACTIVE

CARMAX 7154 (Continued) **U003974635**

Status Date:	7/20/2006
Customer Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Legal Name:	Carmax Auto Superstores, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35

Regulated Entity Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1073
Status:	ACTIVE
Status Date:	7/20/2006
Customer Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Legal Name:	Carmax Auto Superstores, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811121
Primary NAICS Industry Type Description:	Paint and Interior Repair and Maintenance
Physical Location Description:	13500 N LAMAR BLVD AUSTIN TX INTX OF LAMAR BLVD HOWARD & I-35

NON REGIST PST:

RN Number:	RN105001614
Name:	CARMAX 7154
Address:	13300 N IH 35
City,State,Zip:	AUSTIN, TX 78753 1073
Physical Location:	13500 N LAMAR BLVD AUSTIN TXINTX OF LAMAR BLVD HOWARD & I-35
CN Number:	CN600366355
Customer Name:	CARMAX AUTO SUPERSTORES INC
Customer Role:	OWNER OPERATOR
Primary Business:	RETAIL
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=722446312006201

2929 NE 1/8-1/4 0.158 mi. 835 ft. | **ORACLE AMERICA WATERFRONT**
2300 CLOUD WAY
AUSTIN, TX 78741 | **TX AST** | **A100445611**
N/A

Actual: 448 ft.

Focus Map: 15

AST:

Name:	ORACLE AMERICA WATERFRONT
Address:	2300 CLOUD WAY
City,State,Zip:	AUSTIN, TX 787411400
Facility ID:	134642
Additional ID:	456528352017293
AI Number:	89530
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	10/06/2017
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	RON SKIPPER/
Contact Organization Name:	ORACLE AMERICA WATERFRONT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5128138194
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	03/28/2018
Signature First Name on Earliest Reg Form:	MICHELLE
Application Received Date on Earliest Reg Form:	04/03/2018
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	MYER
Signature Title on Earliest Reg Form:	VP
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	134642
Tank ID:	1
AST ID:	222726
AI Number:	89530
Install Date:	10/06/2017
Tank Registration Date:	10/19/2017
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	10/06/2017
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	1968

ORACLE AMERICA WATERFRONT (Continued) **A100445611**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

QZ2930 **GERMAN AUTOHAUS** **TX Ind. Haz Waste** **S102751204**
WNW **902 SAGEBRUSH DR** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78758**
0.159 mi.
839 ft. **Site 2 of 2 in cluster QZ**

Actual:
728 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	GERMAN AUTOHAUS
Address:	902 SAGEBRUSH DR
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	68275
Registration Initial Notification Date:	03/31/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19860331
Land Type:	Not reported
Description of Facility Site Location:	902 Sagebrush, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	GERMAN AUTOHAUS
Contact Name:	JOSEPH MUELLER
Contact Telephone Number:	Not reported
Mailing Address:	902 SAGEBRUSH DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787584825
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	23228
Site Owner Tax ID:	0

GERMAN AUTOHAUS (Continued) **S102751204**

Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	GERMAN AUTOHAUS
Operator Address:	902 SAGEBRUSH DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78758
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17604528889
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	GERMAN AUTOHAUS
Owner Mailing Address:	902 SAGEBRUSH DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17604528889
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	902 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

GERMAN AUTOHAUS (Continued) **S102751204**

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	902 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JOSEPH MUELLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	902 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100592096
Name:	GERMAN AUTOHAUS
Address:	902 SAGEBRUSH DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4825
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600302020
Customer Name:	GERMAN AUTOHAUS
Customer Legal Name:	Image Imports, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	902 Sagebrush, Austin, TX

RG2931 **EXXON RS 62790** **TX UST** **U001260057**
ENE **619 N IH 35** **TX Financial Assurance** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.159 mi.
839 ft. **Site 3 of 4 in cluster RG**

Actual:
484 ft.

Focus Map:
11

UST:

Name:	EXXON RS 62790
Address:	619 N IH 35
City,State,Zip:	AUSTIN, TX 787023202
AI Number:	26050
Facility Type:	RETAIL
Facility Begin Date:	10/13/1986
Facility Status:	INACTIVE
Additional ID:	956297932002175

EXXON RS 62790 (Continued) **U001260057**

Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	EXXON RS 62790
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9725427070
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	RN ATHERTON,ENG SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	469374782004153
Additional ID:	956297932002175
Ai Number:	26050
Operator CN:	CN602637696
Operator Name:	PISCES FOODS LP
Operator Effective Begin Date:	12/10/2003
Operator Type:	PA
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	PISCES FOODS LP
Contact Mailing Address (Delivery):	5407 PARKCREST DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78731-4992
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602637696
Owner Last Name:	PISCES FOODS LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA

EXXON RS 62790 (Continued) **U001260057**

Contact Mailing Address (Delivery):	5407 PARKCREST DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78731
Contact Mailing Zip5:	4992
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	469374782004153
Additional ID:	956297932002175
AI Number:	26050
Owner Effective Begin Date:	12/10/2003
State Tax ID:	17427574375
Contact Role:	OWNCON
Contact Name/Title:	/
Contact Organization Name:	PISCES FOODS LP

Self Certification:

Self Cert ID:	47936
Cert ID:	33345
AI Number:	26050
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	47936
Cert ID:	33344
AI Number:	26050
Self Certification Date:	03/13/2002
Signature Name/Title:	WENDY SALAS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported

EXXON RS 62790 (Continued) **U001260057**

Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47936
Cert ID:	33343
AI Number:	26050
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67008
Facility ID:	47936
Ai Number:	26050
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/11/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

EXXON RS 62790 (Continued) **U001260057**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	35677
UST ID:	67008
AI Number:	26050
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

EXXON RS 62790 (Continued) **U001260057**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1988

More Self Certification:

Self Cert ID:	9820
Cert ID:	81444
UST Comprt ID:	226171
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81441
UST Comprt ID:	226174
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81442
UST Comprt ID:	226173
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81446
UST Comprt ID:	226169
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81443
UST Comprt ID:	226172
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81448
UST Comprt ID:	226167

EXXON RS 62790 (Continued) **U001260057**

UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81447
UST Comprt ID:	226168
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81445
UST Comprt ID:	226170
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67010
Facility ID:	47936
Ai Number:	26050
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/11/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

EXXON RS 62790 (Continued) **U001260057**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	35679
UST ID:	67010
AI Number:	26050
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

EXXON RS 62790 (Continued) **U001260057**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1988

More Self Certification:

Self Cert ID:	9820
Cert ID:	81444
UST Comprt ID:	226171
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81441
UST Comprt ID:	226174
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81442
UST Comprt ID:	226173
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81446
UST Comprt ID:	226169
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81443
UST Comprt ID:	226172
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81448
UST Comprt ID:	226167

EXXON RS 62790 (Continued) **U001260057**

UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81447
UST Comprt ID:	226168
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81445
UST Comprt ID:	226170
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	67009
Facility ID:	47936
Ai Number:	26050
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/11/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

EXXON RS 62790 (Continued) **U001260057**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	35678
UST ID:	67009
AI Number:	26050
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

EXXON RS 62790 (Continued) **U001260057**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	01/01/1988

More Self Certification:

Self Cert ID:	9820
Cert ID:	81444
UST Comprt ID:	226171
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81441
UST Comprt ID:	226174
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81442
UST Comprt ID:	226173
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81446
UST Comprt ID:	226169
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81443
UST Comprt ID:	226172
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81448
UST Comprt ID:	226167

EXXON RS 62790 (Continued) **U001260057**

UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81447
UST Comprt ID:	226168
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A
Self Cert ID:	9820
Cert ID:	81445
UST Comprt ID:	226170
UST ID:	71112
AI Number:	26050
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	PISCES FOODS LP
Contact Mailing Address (Delivery):	5407 PARKCREST DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78731 4992
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47936
Additional ID:	956297932002175
Princ ID:	469374782004153
AI Number:	26050
Facility Name:	EXXON RS 62790
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

TX Financial Assurance 2:

Name:	EXXON RS 62790
Address:	619 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	47936
Finass ID:	35480
AI:	26050
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y

EXXON RS 62790 (Continued) **U001260057**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RJ2932 **TARGET STORE T3342** **RCRA-SQG** **1026060124**
East **901 E 5TH ST STE 140** **TXR000085241**
1/8-1/4 **AUSTIN, TX 78702**
0.159 mi.
842 ft. **Site 1 of 3 in cluster RJ**

Actual:
469 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20220531
Handler Name:	Target Store T3342
Handler Address:	E 5TH ST STE 140
Handler City,State,Zip:	AUSTIN, TX 78702-4072
EPA ID:	TXR000085241
Contact Name:	STEVE MUSSER
Contact Address:	PO BOX 111
Contact City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Contact Telephone:	800-587-2228
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 111
Mailing City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner Name:	Target Corporation
Owner Type:	Private
Operator Name:	Target Corporation
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

TARGET STORE T3342 (Continued) **1026060124**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230531
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010

TARGET STORE T3342 (Continued) **1026060124**

Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20200210
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20200210
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION

TARGET STORE T3342 (Continued) **1026060124**

Legal Status:	Private
Date Became Current:	20200210
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	800-587-2228
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TARGET CORPORATION	
Legal Status:	Private
Date Became Current:	20200210
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TARGET CORPORATION	
Legal Status:	Private
Date Became Current:	20200210
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	800-587-2228
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	POC@TARGET.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: TARGET CORPORATION	
Legal Status:	Private
Date Became Current:	20200210
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TARGET CORPORATION	
Legal Status:	Private
Date Became Current:	20200210
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 111
Owner/Operator City,State,Zip:	MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

TARGET STORE T3342 (Continued) **1026060124**

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20200210
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: POC@TARGET.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20200210
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: 800-587-2228
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TARGET CORPORATION
Legal Status: Private
Date Became Current: 20200210
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 111
Owner/Operator City,State,Zip: MINNEAPOLIS, MN 55440-0111
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20220301
Handler Name: TARGET STORE T3342
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200210
Handler Name: TARGET STORE T3342
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

TARGET STORE T3342 (Continued) **1026060124**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200210
Handler Name: TARGET STORE T3342
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220531
Handler Name: TARGET STORE T3342
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220531
Handler Name: TARGET STORE T3342
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 45221
NAICS Description: DEPARTMENT STORES

NAICS Code: 452210
NAICS Description: DEPARTMENT STORES

NAICS Code: 455110
NAICS Description: DEPARTMENT STORES

Facility Has Received Notices of Violations:

TARGET STORE T3342 (Continued) **1026060124**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

RJ2933 **TARGET STORE T3342** **TX Ind. Haz Waste** **S126476448**
East **901 E 5TH ST STE 140** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.159 mi.
842 ft. **Site 2 of 3 in cluster RJ**

Actual:
469 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	TARGET STORE T3342
Address:	901 E 5TH ST STE 140
City,State,Zip:	AUSTIN, TX 78702
Permit Number:	Not reported
Registration Number:	97639
Registration Initial Notification Date:	02/10/2020
Registration Last Amendment Date:	05/31/2022
EPA Identification:	TXR000085241
Primary NAICS Code:	452210
Status Change Date:	20200210
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TARGET CORPORATION
Contact Name:	STEVE MUSSER
Contact Telephone Number:	800-5872228
Mailing Address:	PO BOX 111
Mailing Address2:	Not reported
Mailing City,State,Zip:	MINNEAPOLIS, MN 554400111
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	132976
Site Owner Tax ID:	410215170
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220531
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

TARGET STORE T3342 (Continued) **S126476448**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TARGET CORPORATION
Operator Address:	PO BOX 111
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	MINNEAPOLIS, MN 55440
Operator Country:	UNITED STA
Operator Telephone:	1-800-5872228
Operator Fax Number:	Not reported
Operator Email:	POC@TARGET.COM
Operator Business Type:	Corporation
Operator Tax ID:	14102151702
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TARGET CORPORATION
Owner Mailing Address:	PO BOX 111
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	MINNEAPOLIS, MN 55440
Owner Country:	UNITED STA
Owner Telephone:	1-800-5872228
Owner Fax:	Not reported
Owner Email Address:	POC@TARGET.COM
Owner Business Type:	Corporation
Owner Tax ID:	14102151702
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	03
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported

TARGET STORE T3342 (Continued) **S126476448**

Permit Sequence Number:	Not reported
Unit Description:	WASTE STORAGE AREA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20200210
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	PO BOX 111
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	MINNEAPOLIS, MN 55440
Contact Phone:	1-800-5872228
Contact Fax:	Not reported
Contact Email:	POC@TARGET.COM

Contact Name:	STEVE MUSSER
Contact Title:	SR COMPLIANCE DIRECTOR
Contact Role:	PRICONT
Contact Address:	PO BOX 111
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	MINNEAPOLIS, MN 55440
Contact Phone:	1-800-5872228
Contact Fax:	Not reported
Contact Email:	POC@TARGET.COM

Ind. Haz Waste:

Waste ID:	416147
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	AEROSOLS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452210
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TARGET STORE T3342 (Continued) **S126476448**

Ind. Haz Waste:

Waste ID:	430078
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE LIQUIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430079
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE SOLIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TARGET STORE T3342 (Continued) **S126476448**

Waste ID:	430080
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquids - Acidic
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430082
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Solids - Acidic
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE SOLIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430083
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Liquid - Basic
Standard Industrial Code:	Not reported

TARGET STORE T3342 (Continued) **S126476448**

Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE LIQUID
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430084
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive Solids - Basic
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CORROSIVE SOLIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430085
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING SOLIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

TARGET STORE T3342 (Continued) **S126476448**

Ind. Haz Waste:

Waste ID:	430086
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing Liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430087
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Solids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC SOLIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430088

TARGET STORE T3342 (Continued) **S126476448**

Texas Waste Code:	Not reported
Texas Waste Code 2:	0011219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic Liquids
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	TOXIC LIQUIDS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430089
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Compressed Gas - Lighters
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	COMPRESSED GAS
Primary NAICS Code:	452210
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430090
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015004H
Waste Code Status:	ACTIVE
Waste Form:	004

TARGET STORE T3342 (Continued) **S126476448**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Pharmaceuticals, P-listed Nicotine
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	P-LISTED NICOTINE
Primary NAICS Code:	452210
EPA Waste Form Code:	W005
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430091
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercury Containing Waste
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452112
EPA Waste Form Code:	W320
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430092
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022309H
Waste Code Status:	ACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Batteries, Lead Acid
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

TARGET STORE T3342 (Continued) **S126476448**

Audit Performed:	0
Company Waste ID:	BATTERIES LEAD ACID
Primary NAICS Code:	452210
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	430093
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023209H
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint and/or Paint-Related Material
Standard Industrial Code:	Not reported
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	PAINT PAINT-RELATED
Primary NAICS Code:	452210
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	STEVE MUSSER

TARGET STORE T3342 (Continued) **S126476448**

Contact Title:	SR COMPLIANCE DIRECTOR
Contact Telephone:	0-800-5872228 x0
Mailing Address:	PO BOX 111
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MINNEAPOLIS, MN 55440
AR Number:	0000315309
Principal Name:	TARGET CORPORATION
Attention Name:	MUSSER ,STEVE
Attention Suffix:	HWG

Contact Name:	STEVE MUSSER
Contact Title:	SR COMPLIANCE DIRECTOR
Contact Telephone:	0-800-5872228 x0
Mailing Address:	PO BOX 111
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MINNEAPOLIS, MN 55440
AR Number:	0000315309
Principal Name:	TARGET CORPORATION
Attention Name:	MUSSER ,STEVE
Attention Suffix:	NWG

2934 WNW 1/8-1/4 0.161 mi. 848 ft. **SALVATION ARMY SOUTH CONGRESS 4216 SOUTH CONGRESS AVENUE AUSTIN, TX 78745** **US BROWNFIELDS** **1024008846 N/A**

Actual: 674 ft.

Focus Map: 17

US BROWNFIELDS:

Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

	undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	7701
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	2/16/2016
Ownership Entity:	Private
Completion Date:	4/29/2016
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	7701
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	2/16/2016
Ownership Entity:	Private
Completion Date:	4/29/2016
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5

Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8952
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F90901
Start Date:	11/30/2015
Ownership Entity:	Private
Completion Date:	12/22/2015
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5

Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.

Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

	affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

	Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	5000000
Redev. Funding Source:	Salvatation Army
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	15
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5
Name:	SALVATION ARMY SOUTH CONGRESS
Address:	4216 SOUTH CONGRESS AVENUE
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	3.25
Latitude:	30.2214019
Longitude:	-97.7678972
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Currently, the Site accommodates two structures: the Salvation Army Thrift Store and the Salvation Army Adult Rehabilitation Center. A baseball field is located on the northwestern portion of the Site, as well as a vacant and heavily vegetated area located west and southwest of the baseball field. Additionally, a green space exists south of the two structures along the southern boundary of the Site. A ?spoil pile? located on the western portion of the Site is illustrated on the site plan provided in the ?Application for Environmental Services? submitted by the Salvation Army to the Austin Brownfields Redevelopment Office. Because of the unknown contents of the debris pile, the City used funds to determine whether the debris pile had contamination. The resulting report showed no contamination. The Salvation Army is seeking $5 million from the City of Austin in order to expand their operations at this site. As of October 2016, it is unknown where the required funding will come from. Former Use: The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Datum:	North American Datum of 1983
Acres Property ID:	206321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8952
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment

SALVATION ARMY SOUTH CONGRESS (Continued) **1024008846**

Accomplishment Count:	Y
Cooperative Agreement Number:	00F90901
Start Date:	11/30/2015
Ownership Entity:	Private
Completion Date:	12/22/2015
Current Owner:	Salvation Army
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	3.25
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	2.5
Future use commercial acreage:	0.75
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Site consists of both developed and undeveloped areas, and the Salvation Army plans to develop approximately 3.25 acres of an undeveloped part of the property for commercial/residential purposes. A multistory structure, parking lot, and landscaping is proposed for construction to support a rehabilitation center (including affordable, supportive housing) for women.
Below Poverty Number:	549
Below Poverty Percent:	19.3
Meidan Income:	2102
Meidan Income Number:	1293
Meidan Income Percent:	45.45
Vacant Housing Number:	179
Vacant Housing Percent:	12.58
Unemployed Number:	128
Unemployed Percent:	4.5

RG2935 **PRIME FOOD MART** **TX UST** **U003566298**
ENE **601 N IH 35** **TX Financial Assurance** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.162 mi.
853 ft. **Site 4 of 4 in cluster RG**

Actual:
484 ft.

Focus Map:
11

UST:

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 787023202
AI Number:	33136
Facility Type:	RETAIL
Facility Begin Date:	12/01/1986
Facility Status:	ACTIVE
Additional ID:	762607152002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	PRASLA ALTAF,
Contact Organization Name:	PRIME FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124763468
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/22/2022
Signature Name/Title On Earliest Reg Form:	KAOIMBRUI PADSZA,OWNER
Application Received Date On Earliest Reg Form:	12/27/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	158397122017151
Additional ID:	762607152002053
Ai Number:	33136
Operator CN:	CN605373471
Operator Name:	CAPITAL GROCERY LLC
Operator Effective Begin Date:	04/24/2018
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

PRIME FOOD MART (Continued) **U003566298**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600750855
Owner Last Name:	E & V SLACK INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	318530122002030
Additional ID:	762607152002053
AI Number:	33136
Owner Effective Begin Date:	04/24/2018
State Tax ID:	17420537908
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	45105
Cert ID:	380984
AI Number:	33136
Self Certification Date:	12/22/2022
Signature Name/Title:	KAOIMBRUI PADSZA OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	363953
AI Number:	33136
Self Certification Date:	12/02/2021

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	KARIMIHMI PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	346147
AI Number:	33136
Self Certification Date:	11/27/2020
Signature Name/Title:	KARIMBHAI PRASLA SELF OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	329423
AI Number:	33136
Self Certification Date:	12/09/2019
Signature Name/Title:	KARIM BHAI PRASLA SELF OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	313984
AI Number:	33136
Self Certification Date:	01/10/2019

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	KARIMBHAI PRASLA OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	298829
AI Number:	33136
Self Certification Date:	01/31/2018
Signature Name/Title:	KURIMEHLAI PRASLA OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	287291
AI Number:	33136
Self Certification Date:	04/10/2017
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	278815
AI Number:	33136
Self Certification Date:	11/30/2016

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	262363
AI Number:	33136
Self Certification Date:	12/07/2015
Signature Name/Title:	DAVID SLACK GENERAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	245331
AI Number:	33136
Self Certification Date:	11/24/2014
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	45105
Cert ID:	230608
AI Number:	33136
Self Certification Date:	01/06/2014

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	45105
Cert ID:	22212
AI Number:	33136
Self Certification Date:	11/20/2012
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	45105
Cert ID:	22211
AI Number:	33136
Self Certification Date:	11/22/2011
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	45105
Cert ID:	22210
AI Number:	33136
Self Certification Date:	11/17/2010

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22209
AI Number:	33136
Self Certification Date:	11/23/2009
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22208
AI Number:	33136
Self Certification Date:	11/18/2008
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22207
AI Number:	33136
Self Certification Date:	11/27/2007

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	45105
Cert ID:	22206
AI Number:	33136
Self Certification Date:	11/28/2006
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	45105
Cert ID:	22205
AI Number:	33136
Self Certification Date:	12/01/2005
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	45105
Cert ID:	22204
AI Number:	33136
Self Certification Date:	12/08/2004

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GENERAL MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22203
AI Number:	33136
Self Certification Date:	12/04/2003
Signature Name/Title:	DAVID SLACK
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22202
AI Number:	33136
Self Certification Date:	11/27/2002
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22201
AI Number:	33136
Self Certification Date:	11/27/2001

PRIME FOOD MART (Continued) **U003566298**

Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	45105
Cert ID:	22200
AI Number:	33136
Self Certification Date:	12/05/2000
Signature Name/Title:	DAVID SLACK GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87411
Facility ID:	45105
Ai Number:	33136
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

PRIME FOOD MART (Continued) **U003566298**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	22742
UST ID:	87411
AI Number:	33136
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

PRIME FOOD MART (Continued) **U003566298**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1998

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87412
Facility ID:	45105
Ai Number:	33136
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

PRIME FOOD MART (Continued) **U003566298**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	22743
UST ID:	87412
AI Number:	33136
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

PRIME FOOD MART (Continued) **U003566298**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1998

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	87413
Facility ID:	45105
Ai Number:	33136
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

PRIME FOOD MART (Continued) **U003566298**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	22744
UST ID:	87413
AI Number:	33136
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

PRIME FOOD MART (Continued) **U003566298**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1998

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	87414
Facility ID:	45105
Ai Number:	33136
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

PRIME FOOD MART (Continued) **U003566298**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/14/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	22745
UST ID:	87414
AI Number:	33136
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

PRIME FOOD MART (Continued) **U003566298**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1969
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169841
Facility ID:	45105
Ai Number:	33136
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1969
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

PRIME FOOD MART (Continued) **U003566298**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	44
UST Comprt ID:	22746
UST ID:	169841
AI Number:	33136
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	44
Tank Singlewall:	N

PRIME FOOD MART (Continued) **U003566298**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169842
Facility ID:	45105
Ai Number:	33136
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1972
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

PRIME FOOD MART (Continued) **U003566298**

Compartment Records:

Tank ID:	6
Tank Capacity:	44
UST Comprt ID:	22747
UST ID:	169842
AI Number:	33136
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	E & V SLACK INC
Contact Mailing Address (Delivery):	PO BOX 93188
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78709 3188
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	45105
Additional ID:	762607152002053
Princ ID:	318530122002030

PRIME FOOD MART (Continued) **U003566298**

AI Number:	33136
Facility Name:	PRIME FOOD MART
AR Number:	46641
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	DAVID SLACK/GM

TX Financial Assurance 2:

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	278120
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2022
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000031453
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	261260
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2021
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000021727
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

PRIME FOOD MART (Continued) **U003566298**

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	240877
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2020
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000012510
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	223265
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2019
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-005001271
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	207356
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

PRIME FOOD MART (Continued) **U003566298**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2018
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	192244
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2017
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	180248
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2016
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336

PRIME FOOD MART (Continued) **U003566298**

Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	171055
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2016
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	153897
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2015
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702

PRIME FOOD MART (Continued) **U003566298**

Region:	2
Facility ID:	45105
Finass ID:	136274
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2014
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	121523
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2013
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	1816
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

PRIME FOOD MART (Continued) **U003566298**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2012
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/20/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	26898
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2011
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1000000
Coverage Expiration Date:	08/20/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	26899
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2009
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1000000
Coverage Expiration Date:	08/20/2010

PRIME FOOD MART (Continued) **U003566298**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	26900
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/20/2008
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1000000
Coverage Expiration Date:	08/20/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	26901
AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/20/2007
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18156
Coverage Amount:	1000000
Coverage Expiration Date:	08/20/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PRIME FOOD MART
Address:	601 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	45105
Finass ID:	26902

PRIME FOOD MART (Continued) **U003566298**

AI:	33136
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	12/27/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RK2936 **WHITAKER FIELDS** **TX UST** **U003373829**
ESE **4901 N GUADALUPE** **N/A**
1/8-1/4 **AUSTIN, TX 78751**
0.162 mi.
855 ft. **Site 1 of 2 in cluster RK**

Actual:
654 ft.

Focus Map:
8

UST:

Name:	WHITAKER FIELDS
Address:	4901 N GUADALUPE
City,State,Zip:	AUSTIN, TX 78751
AI Number:	11350
Facility Type:	FLEET REFUELING
Facility Begin Date:	07/28/1986
Facility Status:	INACTIVE
Additional ID:	265500132005280
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	HORACE MITCHELL,
Contact Organization Name:	WHITAKER FIELDS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124520597
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/25/1986
Signature Name/Title On Earliest Reg Form:	B A THOMPSON,DIRECTOR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

WHITAKER FIELDS (Continued) **U003373829**

Owner:

Owner CN:	CN601097413
Owner Last Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	583604122002106
Additional ID:	265500132005280
AI Number:	11350
Owner Effective Begin Date:	07/28/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	515
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29803
Facility ID:	50474
Ai Number:	11350
Tank Id:	A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/07/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

WHITAKER FIELDS (Continued) **U003373829**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	A
Tank Capacity:	515
UST Comprt ID:	27516
UST ID:	29803
AI Number:	11350
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

WHITAKER FIELDS (Continued) **U003373829**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Contact Mailing Address (Delivery):	PO BOX 7729
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78713 7729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	50474
Additional ID:	265500132005280
Princ ID:	583604122002106
AI Number:	11350
Facility Name:	WHITAKER FIELDS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHIP ROGERS/

RK2937 **WHITAKER FIELDS** **TX HIST UST** **S128729151**
ESE **4901 GUADALUPE ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.162 mi.
855 ft. **Site 2 of 2 in cluster RK**

Actual:
654 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	WHITAKER FIELDS
Address:	4901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX057
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RL2938 **SAFE WAY RENTAL TOWER SITE** **TX VCP** **S116703109**
WNW **311 BOWIE ST** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX CENTRAL REGISTRY**
0.162 mi.
857 ft. **Site 1 of 6 in cluster RL**

Actual:
466 ft.

Focus Map:
11

VCP TCEQ:

Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX 78703
Region:	REGION 11 - AUSTIN
Facility ID:	2409
VCP Record Date:	05/18/2011
Facility Type:	RETAIL
PCA Number:	34602
Project Manager:	OEKPOOTU
Phase:	COMPLETED
Acres at Site:	0.7359
REM Program:	VCP
RN Number:	RN101053411
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	05/18/2011
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	Not reported
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	03/12/2013
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	05/18/2011
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2011-06-16 00:00:00
Soil Target COC Class:	METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2409; 1266
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	346020
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	32.00

SAFE WAY RENTAL TOWER SITE (Continued) **S116703109**

Longitude:	-97.00

ASBESTOS:

Name:	SAFEWAY RENTAL
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/24/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

SAFE WAY RENTAL TOWER SITE (Continued) **S116703109**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133979
Customer Name:	SPRINT SPECTRUM LLC
Customer Legal Name:	Sprint Spectrum LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600779797
Customer Name:	SAFEWAY RENTAL EQUIP CO INC
Customer Legal Name:	SAFE WAY RENTAL EQUIPMENT COMPANY, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/30/1987
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported

SAFE WAY RENTAL TOWER SITE (Continued) **S116703109**

City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603864562
Customer Name:	BOWIE STREET PARTNERS LTD
Customer Legal Name:	Bowie Street Partners, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	5/18/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604421891
Customer Name:	SAFEWAY RENTAL
Customer Legal Name:	Safeway Rental
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133979
Customer Name:	SPRINT SPECTRUM LLC
Customer Legal Name:	Sprint Spectrum LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001

SAFE WAY RENTAL TOWER SITE (Continued) **S116703109**

Customer Number:	CN600779797
Customer Name:	SAFEWAY RENTAL EQUIP CO INC
Customer Legal Name:	SAFE WAY RENTAL EQUIPMENT COMPANY, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/30/1987
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN603864562
Customer Name:	BOWIE STREET PARTNERS LTD
Customer Legal Name:	Bowie Street Partners, Ltd.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	5/18/2011
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN604421891
Customer Name:	SAFEWAY RENTAL
Customer Legal Name:	Safeway Rental
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133979
Customer Name:	SPRINT SPECTRUM LLC
Customer Legal Name:	Sprint Spectrum LLC

SAFE WAY RENTAL TOWER SITE (Continued) **S116703109**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133979
Customer Name:	SPRINT SPECTRUM LLC
Customer Legal Name:	Sprint Spectrum LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053411
Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5124
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600133979
Customer Name:	SPRINT SPECTRUM LLC
Customer Legal Name:	Sprint Spectrum LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
10 additional TX CENTRAL REG: record(s) in the EDR Site Report.

RL2939 **SAFEWAY RENTAL EQUIP** **TX LPST** **S105049611**
WNW **311 BOWIE ST** **TX VCP** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.162 mi.
857 ft. **Site 2 of 6 in cluster RL**

Actual:
466 ft.

Focus Map:
11

LPST:

Name:	SAFEWAY RENTAL EQUIP
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0042881

SAFEWAY RENTAL EQUIP (Continued) **S105049611**

LPST Id:	095362
Facility Location:	BOWIE VCP 1266
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/03/1990
Entered Date:	05/04/1990
Reported Date:	04/03/1990
Closure Date:	09/11/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	TERRY NORRIS
Responsible Party Address:	311 BOWIE
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/476-7301
Reported Date:	04/03/1990
Case Start Date:	09/11/1990
Reference Number:	RN101053411
Project Manager:	HWELCH

VCP TCEQ:

Name:	SAFE WAY RENTAL TOWER SITE
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX 78703
Region:	REGION 11 - AUSTIN
Facility ID:	1266
VCP Record Date:	10/05/2000
Facility Type:	RETAIL
PCA Number:	33366
Project Manager:	SRAINEY
Phase:	TERMINATED
Acres at Site:	0.012
REM Program:	VCP
RN Number:	RN101053411
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	10/05/2000
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	TIER 1
Sediment Inst Eng Controls:	Not reported

SAFEWAY RENTAL EQUIP (Continued) **S105049611**

Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	10/10/2000
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	10/05/2000
Application Accepted Date:	2000-11-05 00:00:00
Soil Target COC Class:	PETROLEUM (BTEX); METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2409; 1266
Leaking Petroleum Storage Registration Tank:	025392
Project Number:	333660
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	208/D; FILM CR
Latitude:	32.00
Longitude:	-97.00

Contact:

REM Program:	VCP
Program ID:	1266
RN Number:	RN101053411
CN Number:	CN600133979
CN Name:	SPRINT SPECTRUM LLC
Role Code:	BILLCONT
Contact Name:	BRYANT, KRISTEN
Contact Title:	Not reported
Organization Name:	SPRINT SPECTRUM LP
Mailing Address:	1341 W MOCKINGBIRD LN STE 600E
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75247
Contact Telephone:	(214) 525-4061
Contact Telephone Ext:	0

RL2940 **SAFEWAY RENTAL TRACT** **TX RDR** **S127532991**
WNW **311 BOWIE ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.162 mi.
857 ft. **Site 3 of 6 in cluster RL**

Actual:
466 ft.

Focus Map:
11

RDR:

RDR ID:	20715
Facility ID:	42881
RN:	Not reported
CN:	Not reported
Name:	SAFEWAY RENTAL TRACT
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/27/2012
Due Date:	10/26/2012
Tank Owner:	BOWIE STREET PARTNERS LTD

SAFEWAY RENTAL TRACT (Continued) **S127532991**

Contact Person:	LARRY WARSHAW
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/26/2012
Project Manager:	Prasanthi Bollineni
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	95362
Comments:	6A
Review Coordinator:	PVB
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RL2941 **SAFEWAY RENTAL EQUIP** **TX UST** **U001274974**
WNW **311 BOWIE ST** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.162 mi.
857 ft. **Site 4 of 6 in cluster RL**

Actual:
466 ft.

Focus Map:
11

UST:

Name:	SAFEWAY RENTAL EQUIP
Address:	311 BOWIE ST
City,State,Zip:	AUSTIN, TX 787035124
AI Number:	42881
Facility Type:	RETAIL
Facility Begin Date:	01/30/1987
Facility Status:	INACTIVE
Additional ID:	783040482002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	JAMES M STEWART,AGENT
Contact Organization Name:	SAFEWAY RENTAL EQUIP
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124767301
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/20/1986
Signature Name/Title On Earliest Reg Form:	JAMES M STEWART,AGENT
Application Received Date On Earliest Reg Form:	06/17/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Owner:

Owner CN:	CN600779797
Owner Last Name:	SAFEWAY RENTAL EQUIP CO INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	876577412002053
Additional ID:	783040482002156
AI Number:	42881
Owner Effective Begin Date:	01/30/1987
State Tax ID:	17415934847
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	06/17/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	113315
Facility ID:	71768
Ai Number:	42881
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	550
UST Comprt ID:	96110
UST ID:	113315
AI Number:	42881
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	06/17/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	113316
Facility ID:	71768
Ai Number:	42881
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	96111
UST ID:	113316
AI Number:	42881
Compartment ID:	A
Substance Stored1:	KEROSENE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	06/17/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	113317
Facility ID:	71768
Ai Number:	42881
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	96112
UST ID:	113317
AI Number:	42881
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	9111
Facility ID:	71768
AI Number:	42881
Application Received Date:	08/02/2012
Scheduled Construction Date:	08/08/2012
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	19830
General Desc Of Prop Construct:	REMOVAL OF (2) POTENTIAL 500 GAL "GHOST TANKS".

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	9769
UST ID:	Not reported
NOC ID:	9111
AI Number:	42881
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON CONSULTANTS INC
Representative Name:	KEVIN DENSON
Mailing Address (Delivery):	5307 INDUSTRIAL OAKS
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	9768
UST ID:	Not reported
NOC ID:	9111
AI Number:	42881
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000079
Company Name:	GRUENE ENVIRONMENTAL CONSTRUCTION
Representative Name:	RYAN LAMBERT
Mailing Address (Delivery):	11 NAFTA CIRCLE
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	9770
UST ID:	Not reported
NOC ID:	9111
AI Number:	42881
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000079
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SAFEWAY RENTAL EQUIP CO INC
Contact Mailing Address (Delivery):	311 BOWIE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 5124
Phone Number/Ext:	/

SAFEWAY RENTAL EQUIP (Continued) **U001274974**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	71768
Additional ID:	783040482002156
Princ ID:	876577412002053
AI Number:	42881
Facility Name:	SAFEWAY RENTAL EQUIP
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	TERRY NORRIS/

RM2942 **CITY OF AUSTIN** **RCRA NonGen / NLR** **1000412193**
NE **715 E 8TH ST** **FINDS** **TXD981610637**
1/8-1/4 **AUSTIN, TX 78701** **ECHO**
0.163 mi.
863 ft. **Site 1 of 7 in cluster RM**

Actual:
471 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20011108
Handler Name:	City Of Austin
Handler Address:	E 8TH ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981610637
Contact Name:	RUDY BOHAC
Contact Address:	E 8TH ST POLICE DEPARTMENT
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Telephone:	512-480-5249
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	E 8TH ST POLICE DEPARTMENT
Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Name:	City Of Austin
Owner Type:	Not reported
Operator Name:	City Of Austin
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CITY OF AUSTIN (Continued) **1000412193**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	U123
Waste Description:	Formic Acid (C,T)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Not reported
Date Became Current:	20011108
Date Ended Current:	Not reported
Owner/Operator Address:	715 E 8TH ST POLICE DEPARTMENT
Owner/Operator City,State,Zip:	AUSTIN, TX 78701
Owner/Operator Telephone:	512-480-5249
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

CITY OF AUSTIN (Continued) **1000412193**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Not reported
Date Became Current: 20011108
Date Ended Current: Not reported
Owner/Operator Address: 715 E 8TH ST POLICE DEPARTMENT
Owner/Operator City,State,Zip: AUSTIN, TX 78701
Owner/Operator Telephone: 512-480-5249
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19861006
Handler Name: AUSTIN CITY POLICE DEPT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011108
Handler Name: CITY OF AUSTIN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

CITY OF AUSTIN (Continued) **1000412193**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005096154

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412193
Registry ID:	110005096154
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005096154
Name:	CITY OF AUSTIN
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701

RM2943 **CITY OF AUSTIN POLICE DEPARTMENT** **TX ASBESTOS** **S102752345**
NE **715 E 8TH ST** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.163 mi.
863 ft. **Site 2 of 7 in cluster RM**

Actual:
471 ft.

Focus Map:
11

ASBESTOS:

Name:	AUSTIN POLICE DEPARTMENT HEADQUARTER
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	01/21/2018
Notification Number:	2017009289
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Inspector Name:	Not reported
Date Report Received:	01/19/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/19/2018
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/20/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN POLICE DEPARTMENT - PATROL BUILDING
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Complaint Date:	01/11/2018
Notification Number:	2017009289
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/19/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/19/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/09/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN POLICE DEPARTMENT - PATROL BUILDING
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	01/14/2018
Notification Number:	2017009289
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/02/2018
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/12/2018

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN POLICE DEPARTMENT - PATROL BUILDING
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	01/21/2018
Notification Number:	2017009289
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/08/2018

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/19/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	APD PATROL BUILDING
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/08/20
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Complaint/Incident
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/20/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	Not reported
File Number:	45103
License Status Description:	Current
Expiration Date:	09/10/2024
Original Date:	09/11/2019
Rank Effective Date:	09/11/2019
Mod Code:	NONL
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	18071
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Fail
Inspection Number Grade:	Not reported
Name:	MAIN AUSTIN POLICE HEADQUARTER BLDG.
Address:	715 E. 8TH ST.
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	10/07/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013007223
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/30/2013
Date Routed by Supervisor:	11/08/2013
Date Routed to PSQA:	11/13/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Inspection Number Grade:	Not reported
Name:	AUSTIN POLICE DEPARTMENT - HEADQUARTER BUILDING
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2015009077
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/25/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	O & M
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/25/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN POLICE DEPARTMENT - HEADQUARTER BUILDING
Address:	715 EAST 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2015009077
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/14/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/14/2015
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	0

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CITY OF AUSTIN POLICE DEPARTMENT
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported
Registration Number:	69741
Registration Initial Notification Date:	10/10/1986
Registration Last Amendment Date:	11/08/2001
EPA Identification:	TXD981610637
Primary NAICS Code:	Not reported
Status Change Date:	19861010
Land Type:	Not reported
Description of Facility Site Location:	715 E 8th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CITY OF AUSTIN
Contact Name:	RUDY BOHAC
Contact Telephone Number:	512-4805249

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Mailing Address:	715 E 8TH ST POLICE DEPARTMENT
Mailing Address2:	POLICE DEPARTMENT
Mailing City,State,Zip:	AUSTIN, TX 78701
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24612
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	715 E 8THST POLICE DEPARTMENT
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78701
Operator Country:	UNITED STA
Operator Telephone:	1-512-4805249
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	715 E 8THST POLICE DEPARTMENT
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78701
Owner Country:	UNITED STA
Owner Telephone:	1-512-4805249
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	715 E 8THST POLICE DEPARTMENT

CITY OF AUSTIN POLICE DEPARTMENT (Continued) **S102752345**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4805249
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	715 E 8THST POLICE DEPARTMENT
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4805249
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RUDY BOHAC
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	715 E 8THST POLICE DEPARTMENT
Contact Address 2:	POLICE DEPARTMENT
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78701
Contact Phone:	1-512-4805249
Contact Fax:	Not reported
Contact Email:	Not reported

RM2944 **POLICE DEPARTMENT HEADQUARTERS GENERATOR** **TX UST** **U001542543**
NE **715 E 8TH ST** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78701** **TX Financial Assurance**
0.163 mi.
863 ft. **Site 3 of 7 in cluster RM**

Actual:
471 ft.

Focus Map:
11

UST:

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 787013300
AI Number:	18169
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	ACTIVE
Additional ID:	566665092002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MIGUEL GALINDO,SEC SUPERVISOR
Contact Organization Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129745044
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/04/2021
Signature Name/Title On Earliest Reg Form:	WILLIAM OCONNOR,FLEET PR MGR
Application Received Date On Earliest Reg Form:	05/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	840354562001227
Additional ID:	566665092002149
Ai Number:	18169
Operator CN:	CN600135198
Operator Name:	CITY OF AUSTIN
Operator Effective Begin Date:	02/06/2001
Operator Type:	CI
Operator Role:	OPRCON
Contact Name:	SANDRA CREIGHTON/
Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	505 BARTON SPRINGS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-1216
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78721
Contact Mailing Zip5:	3639
Contact Phone Number/Ext:	1 512 9782649/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	566665092002149

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

AI Number:	18169
Owner Effective Begin Date:	02/06/2001
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JIMMY TUBBS/FUEL OPS COORD
Contact Organization Name:	CITY OF AUSTIN

Self Certification:

Self Cert ID:	37573
Cert ID:	370938
AI Number:	18169
Self Certification Date:	05/25/2022
Signature Name/Title:	WILLIAM OCONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	353848
AI Number:	18169
Self Certification Date:	05/04/2021
Signature Name/Title:	WILLIAM OCONNOR FLEET PR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	336486
AI Number:	18169
Self Certification Date:	04/29/2020
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37573
Cert ID:	320622
AI Number:	18169
Self Certification Date:	05/15/2019
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37573
Cert ID:	303822
AI Number:	18169
Self Certification Date:	05/10/2018
Signature Name/Title:	WILLIAM O'CONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37573
Cert ID:	286249
AI Number:	18169
Self Certification Date:	04/11/2017
Signature Name/Title:	WILLIAM OCONNOR FLT PRG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	270493
AI Number:	18169
Self Certification Date:	05/24/2016
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	253953
AI Number:	18169
Self Certification Date:	06/01/2015
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	236389
AI Number:	18169
Self Certification Date:	04/23/2014
Signature Name/Title:	VALERIE SPINELLI GRANTS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37573
Cert ID:	218904
AI Number:	18169
Self Certification Date:	04/18/2013
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	37573
Cert ID:	32
AI Number:	18169
Self Certification Date:	05/08/2012
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37573
Cert ID:	31
AI Number:	18169
Self Certification Date:	04/08/2011
Signature Name/Title:	JIMMY TUBBS FUEL SPECIALIST SNR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	30
AI Number:	18169
Self Certification Date:	05/10/2010
Signature Name/Title:	WILL O'CONNOR FLEET PROGRAM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	29
AI Number:	18169
Self Certification Date:	05/01/2007
Signature Name/Title:	PAUL GROSS FUEL OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	28
AI Number:	18169
Self Certification Date:	05/01/2006
Signature Name/Title:	PAUL GROSS FUEL OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	27
AI Number:	18169
Self Certification Date:	05/02/2005
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	26
AI Number:	18169
Self Certification Date:	05/21/2004
Signature Name/Title:	MARC CHILDERS FUEL OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37573
Cert ID:	25
AI Number:	18169
Self Certification Date:	04/29/2003
Signature Name/Title:	MARC CHILDERS FUEL OPERATIONS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37573
Cert ID:	24
AI Number:	18169
Self Certification Date:	04/25/2002
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37573
Cert ID:	23
AI Number:	18169
Self Certification Date:	01/30/2001
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	46984
Facility ID:	37573
Ai Number:	18169

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	313
UST ID:	46984

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

AI Number:	18169
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7030
Cert ID:	160560
UST Comprt ID:	472585
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160559
UST Comprt ID:	472584
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160562

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

UST Comprt ID:	472581
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160558
UST Comprt ID:	472583
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160561
UST Comprt ID:	472582
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160563
UST Comprt ID:	472580
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7030
Cert ID:	160564
UST Comprt ID:	472579
UST ID:	154574
AI Number:	18169
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	4411 MEINARDUS DR STE D
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 1170
Phone Number/Ext:	512 9782649/0
Contact Fax Number/Ext:	512 9121524/0
Contact Email Address:	WILLIAM.OCONNOR@AUSTINTEXAS.GOV
Contact Address Deliverable:	Y
Facility ID:	37573
Additional ID:	566665092002149
Princ ID:	840354562001227
AI Number:	18169
Facility Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
AR Number:	5
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	WILLIAM OCONNOR/

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

HIST UST AUSTIN:

Name:	COA POLICE DEPT.
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	1976
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	268746
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/31/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	250077
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/26/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/26/2022

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	231299
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/25/2020
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/25/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	214221
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2019
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/15/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	197133

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/19/2018
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/19/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	179201
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/23/2017
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/23/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	162774
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2016

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	03/28/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	145000
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2015
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	127544
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2013
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	107458
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	291
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2011
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	17435
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	17436
AI:	18169
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 9745044
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	07/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	POLICE DEPARTMENT HEADQUARTERS GENERATOR
Address:	715 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37573
Finass ID:	17437
AI:	18169
Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported

POLICE DEPARTMENT HEADQUARTERS GENERATOR (Continued) **U001542543**

Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

2945 West 1/8-1/4 0.163 mi. 863 ft. | **UNION PACIFIC REALTY** | **TX HIST UST** | **S128728930**
900 W CESAR CHAVEZ ST | **N/A**
AUSTIN, TX

Actual: 446 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	UNION PACIFIC REALTY
Address:	900 W CESAR CHAVEZ ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0149
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2946 East 1/8-1/4 0.164 mi. 864 ft. | **CLOSED GASOLINE STATION** | **TX LPST** | **U001293699**
2803 SAN JACINTO BLVD | **TX UST** | **N/A**
AUSTIN, TX 78705 | **TX HIST UST**

Actual: 535 ft.
Focus Map: 11

LPST:

Name:	CLOSED GASOLINE STATION
Address:	2803 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0055851
LPST Id:	096737
Facility Location:	2803 SAN JACINTO AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/11/1990
Entered Date:	09/18/1990
Reported Date:	09/11/1990
Closure Date:	03/18/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	RICHARD GOTHARD
Responsible Party Address:	2803 SAN JACINTO
Responsible Party City,St,Zip:	AUSTIN, TX 78705
Responsible Party Telephone:	512/472-6612
Reported Date:	09/11/1990
Case Start Date:	03/18/1997
Reference Number:	RN101492007

CLOSED GASOLINE STATION (Continued) **U001293699**

Project Manager: HWELCH

UST:

Name:	CLOSED GASOLINE STATION
Address:	2803 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX 787053815
AI Number:	55851
Facility Type:	RETAIL
Facility Begin Date:	09/25/1990
Facility Status:	INACTIVE
Additional ID:	382601832002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/12/1990
Signature Name/Title On Earliest Reg Form:	BRENT PEFFER,AGENT
Application Received Date On Earliest Reg Form:	09/14/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780548
Owner Last Name:	DOR-WELL ENTERPRISES LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	373601822002053
Additional ID:	382601832002053
AI Number:	55851

CLOSED GASOLINE STATION (Continued) **U001293699**

Owner Effective Begin Date:	09/25/1990
State Tax ID:	17508868308
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	135570
Facility ID:	85634
Ai Number:	55851
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

CLOSED GASOLINE STATION (Continued) **U001293699**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	6
Tank Capacity:	500
UST Comprt ID:	131203
UST ID:	135570
AI Number:	55851
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

CLOSED GASOLINE STATION (Continued) **U001293699**

Self Cert ID:	21757
Cert ID:	60398
UST Comprt ID:	177166
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60397
UST Comprt ID:	177165
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60396
UST Comprt ID:	177164
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60407
UST Comprt ID:	177155
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60406
UST Comprt ID:	177156
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60405
UST Comprt ID:	177157
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	373139
UST Comprt ID:	1087272
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757

CLOSED GASOLINE STATION (Continued) **U001293699**

Cert ID: 357188
UST Comprt ID: 1038923
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 341139
UST Comprt ID: 990493
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 325445
UST Comprt ID: 943148
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 292174
UST Comprt ID: 843762
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 274965
UST Comprt ID: 792560
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 256604
UST Comprt ID: 738118
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 239648
UST Comprt ID: 688322
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 223034

CLOSED GASOLINE STATION (Continued) **U001293699**

UST Comprt ID:	639666
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60404
UST Comprt ID:	177158
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60403
UST Comprt ID:	177159
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60402
UST Comprt ID:	177160
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60401
UST Comprt ID:	177161
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60400
UST Comprt ID:	177162
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60399
UST Comprt ID:	177163
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	308698
UST Comprt ID:	893148

CLOSED GASOLINE STATION (Continued) **U001293699**

UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135571
Facility ID:	85634
Ai Number:	55851
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

CLOSED GASOLINE STATION (Continued) **U001293699**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	131204
UST ID:	135571
AI Number:	55851
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21757

CLOSED GASOLINE STATION (Continued) **U001293699**

Cert ID:	60398
UST Comprt ID:	177166
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60397
UST Comprt ID:	177165
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60396
UST Comprt ID:	177164
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60407
UST Comprt ID:	177155
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60406
UST Comprt ID:	177156
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60405
UST Comprt ID:	177157
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	373139
UST Comprt ID:	1087272
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	357188

CLOSED GASOLINE STATION (Continued) **U001293699**

UST Comprt ID:	1038923
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	341139
UST Comprt ID:	990493
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	325445
UST Comprt ID:	943148
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	292174
UST Comprt ID:	843762
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	274965
UST Comprt ID:	792560
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	256604
UST Comprt ID:	738118
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	239648
UST Comprt ID:	688322
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	223034
UST Comprt ID:	639666

CLOSED GASOLINE STATION (Continued) **U001293699**

UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60404
UST Comprt ID: 177158
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60403
UST Comprt ID: 177159
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60402
UST Comprt ID: 177160
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60401
UST Comprt ID: 177161
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60400
UST Comprt ID: 177162
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60399
UST Comprt ID: 177163
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 308698
UST Comprt ID: 893148
UST ID: 54172

CLOSED GASOLINE STATION (Continued) **U001293699**

AI Number:	55851
Tank ID:	4
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135572
Facility ID:	85634
Ai Number:	55851
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

CLOSED GASOLINE STATION (Continued) **U001293699**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	3000
UST Comprt ID:	131205
UST ID:	135572
AI Number:	55851
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21757
Cert ID:	60398

CLOSED GASOLINE STATION (Continued) **U001293699**

UST Comprt ID: 177166
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60397
UST Comprt ID: 177165
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60396
UST Comprt ID: 177164
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60407
UST Comprt ID: 177155
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60406
UST Comprt ID: 177156
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60405
UST Comprt ID: 177157
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 373139
UST Comprt ID: 1087272
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 357188
UST Comprt ID: 1038923

CLOSED GASOLINE STATION (Continued) **U001293699**

UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 341139
UST Comprt ID: 990493
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 325445
UST Comprt ID: 943148
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 292174
UST Comprt ID: 843762
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 274965
UST Comprt ID: 792560
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 256604
UST Comprt ID: 738118
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 239648
UST Comprt ID: 688322
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 223034
UST Comprt ID: 639666
UST ID: 54172

CLOSED GASOLINE STATION (Continued) **U001293699**

AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60404
UST Comprt ID:	177158
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60403
UST Comprt ID:	177159
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60402
UST Comprt ID:	177160
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60401
UST Comprt ID:	177161
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60400
UST Comprt ID:	177162
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60399
UST Comprt ID:	177163
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	308698
UST Comprt ID:	893148
UST ID:	54172
AI Number:	55851

CLOSED GASOLINE STATION (Continued) **U001293699**

Tank ID:	4
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135573
Facility ID:	85634
Ai Number:	55851
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

CLOSED GASOLINE STATION (Continued) **U001293699**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	131206
UST ID:	135573
AI Number:	55851
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21757
Cert ID:	60398
UST Comprt ID:	177166

CLOSED GASOLINE STATION (Continued) **U001293699**

UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60397
UST Comprt ID: 177165
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60396
UST Comprt ID: 177164
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60407
UST Comprt ID: 177155
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60406
UST Comprt ID: 177156
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60405
UST Comprt ID: 177157
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 373139
UST Comprt ID: 1087272
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 357188
UST Comprt ID: 1038923
UST ID: 54172

CLOSED GASOLINE STATION (Continued) **U001293699**

AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	341139
UST Comprt ID:	990493
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	325445
UST Comprt ID:	943148
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	292174
UST Comprt ID:	843762
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	274965
UST Comprt ID:	792560
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	256604
UST Comprt ID:	738118
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	239648
UST Comprt ID:	688322
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	223034
UST Comprt ID:	639666
UST ID:	54172
AI Number:	55851

CLOSED GASOLINE STATION (Continued) **U001293699**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60404
UST Comprt ID:	177158
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60403
UST Comprt ID:	177159
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60402
UST Comprt ID:	177160
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60401
UST Comprt ID:	177161
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60400
UST Comprt ID:	177162
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60399
UST Comprt ID:	177163
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	308698
UST Comprt ID:	893148
UST ID:	54172
AI Number:	55851
Tank ID:	4

CLOSED GASOLINE STATION (Continued) **U001293699**

Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135574
Facility ID:	85634
Ai Number:	55851
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

CLOSED GASOLINE STATION (Continued) **U001293699**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	131207
UST ID:	135574
AI Number:	55851
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21757
Cert ID:	60398
UST Comprt ID:	177166
UST ID:	54172

CLOSED GASOLINE STATION (Continued) **U001293699**

AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60397
UST Comprt ID:	177165
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60396
UST Comprt ID:	177164
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60407
UST Comprt ID:	177155
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60406
UST Comprt ID:	177156
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60405
UST Comprt ID:	177157
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	373139
UST Comprt ID:	1087272
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	357188
UST Comprt ID:	1038923
UST ID:	54172
AI Number:	55851

CLOSED GASOLINE STATION (Continued) **U001293699**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	341139
UST Comprt ID:	990493
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	325445
UST Comprt ID:	943148
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	292174
UST Comprt ID:	843762
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	274965
UST Comprt ID:	792560
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	256604
UST Comprt ID:	738118
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	239648
UST Comprt ID:	688322
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	223034
UST Comprt ID:	639666
UST ID:	54172
AI Number:	55851
Tank ID:	4

CLOSED GASOLINE STATION (Continued) **U001293699**

Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60404
UST Comprt ID:	177158
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60403
UST Comprt ID:	177159
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60402
UST Comprt ID:	177160
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60401
UST Comprt ID:	177161
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60400
UST Comprt ID:	177162
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60399
UST Comprt ID:	177163
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	308698
UST Comprt ID:	893148
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A

CLOSED GASOLINE STATION (Continued) **U001293699**

Install Date:	08/31/1987
Tank Registration Date:	09/14/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	135575
Facility ID:	85634
Ai Number:	55851
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CLOSED GASOLINE STATION (Continued) **U001293699**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	131208
UST ID:	135575
AI Number:	55851
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	21757
Cert ID:	60398
UST Comprt ID:	177166
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A

CLOSED GASOLINE STATION (Continued) **U001293699**

Self Cert ID:	21757
Cert ID:	60397
UST Comprt ID:	177165
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60396
UST Comprt ID:	177164
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60407
UST Comprt ID:	177155
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60406
UST Comprt ID:	177156
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60405
UST Comprt ID:	177157
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	373139
UST Comprt ID:	1087272
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	357188
UST Comprt ID:	1038923
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757

CLOSED GASOLINE STATION (Continued) **U001293699**

Cert ID: 341139
UST Comprt ID: 990493
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 325445
UST Comprt ID: 943148
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 292174
UST Comprt ID: 843762
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 274965
UST Comprt ID: 792560
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 256604
UST Comprt ID: 738118
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 239648
UST Comprt ID: 688322
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 223034
UST Comprt ID: 639666
UST ID: 54172
AI Number: 55851
Tank ID: 4
Compartment ID: A

Self Cert ID: 21757
Cert ID: 60404

CLOSED GASOLINE STATION (Continued) **U001293699**

UST Comprt ID:	177158
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60403
UST Comprt ID:	177159
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60402
UST Comprt ID:	177160
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60401
UST Comprt ID:	177161
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60400
UST Comprt ID:	177162
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	60399
UST Comprt ID:	177163
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A
Self Cert ID:	21757
Cert ID:	308698
UST Comprt ID:	893148
UST ID:	54172
AI Number:	55851
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	DORWELL ENTERPRISES

CLOSED GASOLINE STATION (Continued) **U001293699**

Contact Mailing Address (Delivery):	1805 MARKET CTR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75207 3314
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85634
Additional ID:	382601832002053
Princ ID:	373601822002053
AI Number:	55851
Facility Name:	CLOSED GASOLINE STATION
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	L BIRDWELL/

HIST UST AUSTIN:

Name:	OLD EXXON
Address:	2803 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0175
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

2947 West 1/8-1/4 0.164 mi. 868 ft. | **SUNRISE MINI MART 8**
539 W OLTORF ST
AUSTIN, TX 78704

TX LPST **U003040310**
TX UST **N/A**
TX HIST UST
TX ASBESTOS
TX Financial Assurance

Actual: 534 ft.

Focus Map: 14

LPST:

Name:	STOP N GO 2062
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0039554
LPST Id:	113083
Facility Location:	539 W OLTORF1
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/03/1997
Entered Date:	04/02/1998
Reported Date:	10/03/1997
Closure Date:	08/05/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	PHG
Responsible Party Name:	Not reported
Responsible Party Contact:	MACK N BRICE
Responsible Party Address:	PO BOX 69600

SUNRISE MINI MART 8 (Continued) **U003040310**

Responsible Party City,St,Zip:	SAN ANTONIO, TX 78629 2308
Responsible Party Telephone:	972/252-1880
Reported Date:	10/03/1997
Case Start Date:	08/05/1999
Reference Number:	RN102368990
Project Manager:	PHG

UST:

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 787045537
AI Number:	39554
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	ACTIVE
Additional ID:	410733132002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	AMIN MAREDIA,
Contact Organization Name:	SUNRISE MINI MART 8
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124407188
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/05/2022
Signature Name/Title On Earliest Reg Form:	AMIN MAREDIA,PRESIDENT
Application Received Date On Earliest Reg Form:	12/08/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	215533302005005
Additional ID:	410733132002149
Ai Number:	39554
Operator CN:	CN602762601
Operator Name:	PEACEFUL INC
Operator Effective Begin Date:	11/01/2006
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	AMIN MAREDIA/
Contact Organization Name:	PEACEFUL INC
Contact Mailing Address (Delivery):	539 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-5537
Contact Phone Country Code:	1

SUNRISE MINI MART 8 (Continued) **U003040310**

Contact Phone Area Code:	512
Contact Phone Number:	4407188
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602762601
Owner Last Name:	PEACEFUL INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	539 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	5537
Contact Phone Number/Ext:	1 512 5777905/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	215533302005005
Additional ID:	410733132002149
AI Number:	39554
Owner Effective Begin Date:	11/01/2006
State Tax ID:	17430254742
Contact Role:	OWNCON
Contact Name/Title:	AMIN MAREDIA/
Contact Organization Name:	PEACEFUL INC

Self Certification:

Self Cert ID:	61074
Cert ID:	380540
AI Number:	39554
Self Certification Date:	12/05/2022
Signature Name/Title:	AMIN MAREDIA PRESIDENT
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	363384
AI Number:	39554
Self Certification Date:	12/15/2021
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	346403
AI Number:	39554
Self Certification Date:	12/10/2020
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	329912
AI Number:	39554
Self Certification Date:	12/26/2019
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	312369
AI Number:	39554
Self Certification Date:	11/23/2018
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	295899
AI Number:	39554
Self Certification Date:	12/15/2017
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	278987
AI Number:	39554
Self Certification Date:	12/05/2016
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	263262
AI Number:	39554
Self Certification Date:	01/07/2016
Signature Name/Title:	AMIN MAREDIA PRESIDENT
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	246323
AI Number:	39554
Self Certification Date:	12/12/2014
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61074
Cert ID:	229775
AI Number:	39554
Self Certification Date:	12/31/2013
Signature Name/Title:	AMIN MAREDIA PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	62795
AI Number:	39554
Self Certification Date:	01/03/2013
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62794
AI Number:	39554
Self Certification Date:	12/15/2011
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62793
AI Number:	39554
Self Certification Date:	12/29/2010
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	62792
AI Number:	39554
Self Certification Date:	12/08/2009
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62791
AI Number:	39554
Self Certification Date:	12/18/2008
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62790
AI Number:	39554
Self Certification Date:	12/17/2007
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	62789
AI Number:	39554
Self Certification Date:	11/17/2006
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62788
AI Number:	39554
Self Certification Date:	11/16/2006
Signature Name/Title:	AMIN MAREDIA PRES
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62787
AI Number:	39554
Self Certification Date:	04/03/2006
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	62786
AI Number:	39554
Self Certification Date:	08/15/2005
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	02/28/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62785
AI Number:	39554
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62784
AI Number:	39554
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Self Cert ID:	61074
Cert ID:	62783
AI Number:	39554
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61074
Cert ID:	62782
AI Number:	39554
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104574
Facility ID:	61074
Ai Number:	39554
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1983
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	54674
UST ID:	104574
AI Number:	39554
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

SUNRISE MINI MART 8 (Continued) **U003040310**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104575
Facility ID:	61074
Ai Number:	39554
Tank Id:	2A
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	11/18/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2A
Tank Capacity:	Not reported
UST Comprt ID:	54675
UST ID:	104575
AI Number:	39554
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

SUNRISE MINI MART 8 (Continued) **U003040310**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104576
Facility ID:	61074
Ai Number:	39554
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	04/01/1983
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

SUNRISE MINI MART 8 (Continued) **U003040310**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	54676
UST ID:	104576
AI Number:	39554
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PEACEFUL INC
Contact Mailing Address (Delivery):	539 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5537
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61074
Additional ID:	410733132002149
Princ ID:	215533302005005
AI Number:	39554
Facility Name:	SUNRISE MINI MART 8
AR Number:	66661
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	AMIN MAREDIA/

HIST UST AUSTIN:

Name:	SUNRISE MINI MART #8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	1176
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	SUNRISE MINI MART
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SUNRISE MINI MART
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/27/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

SUNRISE MINI MART 8 (Continued) **U003040310**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	277693
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2022
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04TOP000033109
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	260649
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2021
Date Financial Assurance Form Rec:	12/08/2022

SUNRISE MINI MART 8 (Continued) **U003040310**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000023261
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	241177
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2020
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000013929
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	225526
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2019
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000005384
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8

SUNRISE MINI MART 8 (Continued) **U003040310**

Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	205814
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2018
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000108513
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	189620
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2017
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000104673
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	172487
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000

SUNRISE MINI MART 8 (Continued) **U003040310**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2016
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	155529
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2015
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	137636
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2014
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156

SUNRISE MINI MART 8 (Continued) **U003040310**

Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	120142
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2013
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	4988
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2012
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/18/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2

SUNRISE MINI MART 8 (Continued) **U003040310**

Facility ID:	61074
Finass ID:	43429
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2011
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1000000
Coverage Expiration Date:	10/18/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	43430
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2010
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1000000
Coverage Expiration Date:	10/18/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	43431
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

SUNRISE MINI MART 8 (Continued) **U003040310**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2009
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1000000
Coverage Expiration Date:	10/18/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	43432
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2008
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1000000
Coverage Expiration Date:	10/18/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	43433
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/18/2007
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210156
Coverage Amount:	1000000
Coverage Expiration Date:	10/18/2008
Ins Premium Pre-Paid For Entire Yr:	No

SUNRISE MINI MART 8 (Continued) **U003040310**

Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 8
Address:	539 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	61074
Finass ID:	43434
AI:	39554
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	12/08/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RA2948 **MOLINA AUTOMOTIVE** **TX UST** **U003721536**
WNW **903 WAGON TRL** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78758**
0.165 mi.
869 ft. **Site 3 of 4 in cluster RA**

Actual:
739 ft.

Focus Map:
3

UST:

Name:	MOLINA AUTOMOTIVE
Address:	903 WAGON TRL
City,State,Zip:	AUSTIN, TX 787584330
AI Number:	72869
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	277568412002053
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	GARY BOULDIN,
Contact Organization Name:	MOLINA AUTOMOTIVE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124761097
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported

MOLINA AUTOMOTIVE (Continued) **U003721536**

Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/26/2000
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRES-EXCEL ENVIR
Application Received Date On Earliest Reg Form:	01/26/2000
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600779433
Owner Last Name:	DIMENSION PROPERTIES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	267568402002053
Additional ID:	277568412002053
AI Number:	72869
Owner Effective Begin Date:	08/31/1987
State Tax ID:	17419915552
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	01/26/2000
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	193346
Facility ID:	110952
Ai Number:	72869
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/25/2000
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N

MOLINA AUTOMOTIVE (Continued) **U003721536**

Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	168331
UST ID:	193346
AI Number:	72869
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N

MOLINA AUTOMOTIVE (Continued) **U003721536**

CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	27848
Cert ID:	73246
UST Comprt ID:	210642
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73252
UST Comprt ID:	210636
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73250
UST Comprt ID:	210638
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	361732
UST Comprt ID:	1052702
UST ID:	75920
AI Number:	72869

MOLINA AUTOMOTIVE (Continued) **U003721536**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	344477
UST Comprt ID:	1000862
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73245
UST Comprt ID:	210643
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	326324
UST Comprt ID:	945860
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73248
UST Comprt ID:	210640
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73244
UST Comprt ID:	210646
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	311884
UST Comprt ID:	902639
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	303245
UST Comprt ID:	876981
UST ID:	75920
AI Number:	72869
Tank ID:	2

MOLINA AUTOMOTIVE (Continued) **U003721536**

Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73251
UST Comprt ID:	210637
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	276585
UST Comprt ID:	797396
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73243
UST Comprt ID:	210645
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	272340
UST Comprt ID:	784964
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73247
UST Comprt ID:	210641
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	225829
UST Comprt ID:	648017
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73242
UST Comprt ID:	210644
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A

MOLINA AUTOMOTIVE (Continued) **U003721536**

Self Cert ID:	27848
Cert ID:	73253
UST Comprt ID:	210635
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73249
UST Comprt ID:	210639
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	377197
UST Comprt ID:	1099560
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	01/26/2000
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	193347
Facility ID:	110952
Ai Number:	72869
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/25/2000
Empty:	N
Tank Regulatory Status:	EXEMPT REM WITHIN 60 DAYS
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

MOLINA AUTOMOTIVE (Continued) **U003721536**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	168332
UST ID:	193347
AI Number:	72869
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

MOLINA AUTOMOTIVE (Continued) **U003721536**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	27848
Cert ID:	73246
UST Comprt ID:	210642
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73252
UST Comprt ID:	210636
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73250
UST Comprt ID:	210638
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	361732
UST Comprt ID:	1052702
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	344477
UST Comprt ID:	1000862
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A

MOLINA AUTOMOTIVE (Continued) **U003721536**

Self Cert ID:	27848
Cert ID:	73245
UST Comprt ID:	210643
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	326324
UST Comprt ID:	945860
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73248
UST Comprt ID:	210640
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73244
UST Comprt ID:	210646
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	311884
UST Comprt ID:	902639
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	303245
UST Comprt ID:	876981
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73251
UST Comprt ID:	210637
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848

MOLINA AUTOMOTIVE (Continued) **U003721536**

Cert ID:	276585
UST Comprt ID:	797396
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73243
UST Comprt ID:	210645
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	272340
UST Comprt ID:	784964
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73247
UST Comprt ID:	210641
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	225829
UST Comprt ID:	648017
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73242
UST Comprt ID:	210644
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73253
UST Comprt ID:	210635
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	73249

MOLINA AUTOMOTIVE (Continued) **U003721536**

UST Comprt ID:	210639
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A
Self Cert ID:	27848
Cert ID:	377197
UST Comprt ID:	1099560
UST ID:	75920
AI Number:	72869
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	17492
Facility ID:	110952
AI Number:	72869
Application Received Date:	01/20/2000
Scheduled Construction Date:	01/25/2000
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M00120027
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	55253
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	18913
UST ID:	Not reported
NOC ID:	17492
AI Number:	72869
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported

MOLINA AUTOMOTIVE (Continued) **U003721536**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	DIMENSION PROPERTIES INC
Contact Mailing Address (Delivery):	609 WOOD ST STE B
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 5417
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	110952
Additional ID:	277568412002053
Princ ID:	267568402002053
AI Number:	72869
Facility Name:	MOLINA AUTOMOTIVE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MICHAEL KUHN/

HIST UST AUSTIN:

Name:	ELMER AUTO REPAIR
Address:	903 WAGON TRL
City,State,Zip:	AUSTIN, TX
Id UST:	N0154
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RA2949 **MOLINA AUTOMOTIVE** **TX RDR** **S127539136**
WNW **903 WAGON TRAIL** **N/A**
1/8-1/4 **AUSTIN, TX**
0.165 mi.
869 ft. **Site 4 of 4 in cluster RA**

Actual:
739 ft.

Focus Map:
3

RDR:

RDR ID:	9884
Facility ID:	72869
RN:	Not reported
CN:	Not reported
Name:	MOLINA AUTOMOTIVE
Address:	903 WAGON TRAIL

MOLINA AUTOMOTIVE (Continued) **S127539136**

City,State,Zip:	AUSTIN, TX
Date Report Received:	2/9/2000
Due Date:	4/9/2000
Tank Owner:	DIMENSION PROPERTIES
Contact Person:	GARY BOULDEN
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RN2950 **AMERICAN PRINTERS EXCHANGE** **TX Ind. Haz Waste** **S102757324**
ESE **630 CANION ST** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.166 mi.
877 ft. **Site 1 of 2 in cluster RN**

Actual:
706 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	AMERICAN PRINTERS EXCHANGE
Address:	630 CANION ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	76533
Registration Initial Notification Date:	11/17/1991
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19911117
Land Type:	Not reported
Description of Facility Site Location:	630 Canion St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AMERICAN PRINTERS EXCHANGE INC
Contact Name:	JIM SPANO
Contact Telephone Number:	512-4525058
Mailing Address:	630 CANION ST

AMERICAN PRINTERS EXCHANGE (Continued) **S102757324**

Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787523510
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	30848
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AMERICAN PRINTERS EXCHANGE INC
Operator Address:	630 CANION ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4525058
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17421175310
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AMERICAN PRINTERS EXCHANGE INC
Owner Mailing Address:	630 CANION ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4525058
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17421175310
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	630 CANION ST
Contact Address 2:	Not reported

AMERICAN PRINTERS EXCHANGE (Continued) **S102757324**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4525058
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	630 CANION ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4525058
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JIM SPANO
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	630 CANION ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4525058
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100557933
Name:	AMERICAN PRINTERS EXCHANGE
Address:	630 CANION ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3510
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600268767
Customer Name:	AMERICAN PRINTERS EXCHANGE INC
Customer Legal Name:	American Printers Exchange, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	630 Canion St, Austin, TX

RO2951 **SB WINGFIELD LANDFILL** **TX Ind. Haz Waste** **S106524630**
East **1111 OLD BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78742**
0.167 mi.
880 ft. **Site 1 of 7 in cluster RO**

Actual:
472 ft.

Focus Map:
16

Ind. Haz Waste:

Name:	SB WINGFIELD LANDFILL
Address:	1111 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742
Permit Number:	Not reported
Registration Number:	H1390
Registration Initial Notification Date:	05/02/1980
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19800502
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	S B WINGFIELD
Contact Name:	SG WINGFIELD
Contact Telephone Number:	512-3853770
Mailing Address:	1111 OLD BASTROP HWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787422632
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	34163
Site Owner Tax ID:	0
Site Location Latitude:	-30.220
Site Location Longitude:	-97.670
Last Update to NOR Data:	20100426
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

SB WINGFIELD LANDFILL (Continued) **S106524630**

Ind. Haz Waste:

Operator Name:	SB WINGFIELD
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	S B WINGFIELD
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	SB WINGFIELD
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	SG WINGFIELD
Contact Title:	ENV MG
Contact Role:	PRICONT
Contact Address:	1111 OLD BASTROP HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Phone:	1-512-3853770
Contact Fax:	Not reported
Contact Email:	Not reported

RO2952 **AUSTIN VEE DUB** **RCRA NonGen / NLR** **1000412163**
East **1111 OLD BASTROP HWY** **FINDS** **TXD018778183**
1/8-1/4 **AUSTIN, TX 78742** **ECHO**
0.167 mi. **TX Ind. Haz Waste**
880 ft. **Site 2 of 7 in cluster RO**

Actual:
472 ft.

Focus Map:
16

RCRA Listings:

Date Form Received by Agency:	20010127
Handler Name:	Austin Vee Dub Inc
Handler Address:	OLD BASTROP HWY
Handler City,State,Zip:	AUSTIN, TX 78742
EPA ID:	TXD018778183
Contact Name:	CHARLES FUSSELMAN
Contact Address:	BASTROP HWY
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Telephone:	512-385-2462
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	BASTROP HWY
Mailing City,State,Zip:	AUSTIN, TX 78742
Owner Name:	Austin Vee Dub Inc
Owner Type:	Not reported
Operator Name:	Austin Vee Dub Salvage
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

AUSTIN VEE DUB (Continued) **1000412163**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D021
Waste Description:	Chlorobenzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene,

AUSTIN VEE DUB (Continued) **1000412163**

Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN VEE DUB INC	
Legal Status:	Not reported
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	1111 BASTROP HWY
Owner/Operator City,State,Zip:	AUSTIN, TX 78742
Owner/Operator Telephone:	512-385-2462
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN VEE DUB SALVAGE	
Legal Status:	Not reported
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	1111 BASTROP HWY
Owner/Operator City,State,Zip:	AUSTIN, TX 78742
Owner/Operator Telephone:	512-385-2462
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: EDWARD M MARTIN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19970825
Handler Name: AUSTIN VEE-DUB SALVAGE	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

AUSTIN VEE DUB (Continued) **1000412163**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010127
Handler Name: AUSTIN VEE DUB INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811118
NAICS Description:	OTHER AUTOMOTIVE MECHANICAL AND ELECTRICAL REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005040222

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

AUSTIN VEE DUB (Continued) **1000412163**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412163
Registry ID:	110005040222
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005040222
Name:	AUSTIN VEE DUB
Address:	1111 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742

Ind. Haz Waste:

Name:	AUSTIN VEE DUB SALVAGE
Address:	1111 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742
Permit Number:	Not reported
Registration Number:	61743
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD018778183
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	1111 Old Bastrop Hwy, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN VEE DUB SALVAGE
Contact Name:	CHARLES FUSSELMAN
Contact Telephone Number:	512-3852462
Mailing Address:	1111 BASTROP HWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 78742
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	20084
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030327
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported

AUSTIN VEE DUB (Continued) **1000412163**

Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN VEE DUB SALVAGE
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN VEE DUB SALVAGE
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	CHARLES FUSSELMAN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1111 BASTROP HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Phone:	1-512-3852462
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	138758
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0

AUSTIN VEE DUB (Continued) **1000412163**

Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	75390
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012828
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	138759
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	IMMERSION CLEANER
Standard Industrial Code:	75390
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012828
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:
Contact Name: Not reported

AUSTIN VEE DUB (Continued) **1000412163**

Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 BASTROP HWY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78742
AR Number:	0000301688
Principal Name:	AUSTIN VEE DUB SALVAGE
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 BASTROP HWY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78742
AR Number:	0000301688
Principal Name:	AUSTIN VEE DUB SALVAGE
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 BASTROP HWY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78742
AR Number:	0000301688
Principal Name:	AUSTIN VEE DUB SALVAGE
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 BASTROP HWY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78742
AR Number:	0000301688
Principal Name:	AUSTIN VEE DUB SALVAGE
Attention Name:	Not reported
Attention Suffix:	NWG

RO2953 **HARMON PROPERTIES LANDFILL** **TX SWF/LF** **S126998821**
East **1111 OLD BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78742**
0.167 mi.
880 ft. **Site 3 of 7 in cluster RO**

Actual:
472 ft.

Focus Map:
16

SWF/LF:

Name:	HARMON PROPERTIES LANDFILL
Address:	1111 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742-2632
Region:	11
Permit Number:	1569
Facility Status:	CLOSED
Facility Type:	3

HARMON PROPERTIES LANDFILL (Continued) **S126998821**

Permit Status:	REVOKED
Status Date:	12/28/1982
Mailing Address:	4708 N IH 35 AUSTIN, TX 78751-3402
Client Name:	CN600712426, Harmon Properties
Client Address:	4708 N IH 35 AUSTIN, TX 78751-3402
Client Telephone:	(512) 459 - 7668
Business Type:	03
Area Served:	Not reported
Estimated Closure Date:	1/1/1988
Permit Acreage:	27.67
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	500
Tons per Day:	10
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	30.23000 / -97.68000

RO2954 **SB WINGFIELD LANDFILL** **TX SWF/LF** **S126998727**
East **1111 OLD BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78742**
0.167 mi.
880 ft. **Site 4 of 7 in cluster RO**

Actual:
472 ft.

Focus Map:
16

SWF/LF:

Name:	SB WINGFIELD LANDFILL
Address:	1111 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742-2632
Region:	11
Permit Number:	1390
Facility Status:	CLOSED
Facility Type:	1
Permit Status:	ISSUED
Status Date:	05/02/1980
Mailing Address:	Not reported
Client Name:	CN601410996, WINGFIELD, SB
Client Address:	1111 OLD BASTROP HWY AUSTIN, TX 78742-2632
Client Telephone:	(512) 385 - 3770
Business Type:	INDIVIDUAL
Area Served:	AUSTIN
Estimated Closure Date:	5/1/1982
Permit Acreage:	18
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	500
Tons per Day:	10
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	30.22000 / -97.67000

RP2955 AUSTIN METAL & IRON **TX UST** **U001250790**
ESE 301 SAN MARCOS ST **TX HIST UST** **N/A**
1/8-1/4 AUSTIN, TX 78702
0.168 mi.
886 ft. **Site 1 of 2 in cluster RP**

Actual:
467 ft.

Focus Map:
11

UST:

Name:	AUSTIN METAL & IRON
Address:	301 SAN MARCOS ST
City,State,Zip:	AUSTIN, TX 78702
AI Number:	15501
Facility Type:	UNKNOWN
Facility Begin Date:	08/15/1986
Facility Status:	INACTIVE
Additional ID:	389193362002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	AUSTIN METAL & IRON CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124726452
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	ROBERT SHAPRIO,MANAGER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601271943
Owner Last Name:	AUSTIN METAL & IRON CO LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	380193352002156
Additional ID:	389193362002156

AUSTIN METAL & IRON (Continued) **U001250790**

AI Number:	15501
Owner Effective Begin Date:	08/15/1986
State Tax ID:	17420733374
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	900
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	39744
Facility ID:	54209
Ai Number:	15501
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/26/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

AUSTIN METAL & IRON (Continued) **U001250790**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/29/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	900
UST Comprt ID:	52058
UST ID:	39744
AI Number:	15501
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

AUSTIN METAL & IRON (Continued) **U001250790**

More Self Certification:

Self Cert ID:	6076
Cert ID:	214
UST Comprt ID:	1019
UST ID:	566
AI Number:	15501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6076
Cert ID:	211
UST Comprt ID:	1022
UST ID:	566
AI Number:	15501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6076
Cert ID:	213
UST Comprt ID:	1020
UST ID:	566
AI Number:	15501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6076
Cert ID:	210
UST Comprt ID:	1021
UST ID:	566
AI Number:	15501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6076
Cert ID:	212
UST Comprt ID:	1023
UST ID:	566
AI Number:	15501
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	AUSTIN METAL & IRON CO INC
Contact Mailing Address (Delivery):	PO BOX 2115
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78768 2115
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	54209
Additional ID:	389193362002156
Princ ID:	380193352002156
AI Number:	15501
Facility Name:	AUSTIN METAL & IRON

AUSTIN METAL & IRON (Continued) **U001250790**

AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: ROBERT SHAPIRO/

HIST UST AUSTIN:
Name: AUSTIN METAL & IRON
Address: 301 SAN MARCOS ST
City,State,Zip: AUSTIN, TX
Id UST: C0211
HID UST: Not reported
Inspection: Not reported
Due: Not reported

RP2956 **AUSTIN METAL IRON** **TX LPST** **S103865174**
ESE **301 SAN MARCOS ST** **TX VCP** **N/A**
1/8-1/4 **AUSTIN, TX 78702** **TX GCC**
0.168 mi. **TX COMP HIST**
886 ft. **Site 2 of 2 in cluster RP** **TX CENTRAL REGISTRY**

Actual:
467 ft.

Focus Map:
11

LPST:
Name: AUSTIN METAL IRON
Address: 301 SAN MARCOS ST
City,State,Zip: AUSTIN, TX 78702
Facility ID: 0015501
LPST Id: 097147
Facility Location: 301 SAN MARCOS ST
TCEQ Region# and City: REGION 11 - AUSTIN
Region City: AUSTIN
Discovered Date: 10/11/1990
Entered Date: 11/06/1990
Reported Date: 10/11/1990
Closure Date: 07/16/2007
Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 11 - VCP
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Groundwater is affected.
Status: **MONITORING**
Coordinators Primary: 11/7/11/1P/1/3/1/
Coordinators RPR: RPR
Responsible Party Name: Not reported
Responsible Party Contact: ROBERT SHAPIRO
Responsible Party Address: PO BOX 2115
Responsible Party City,St,Zip: AUSTIN, TX 78768
Responsible Party Telephone: 512/472-6452
Reported Date: 10/11/1990
Case Start Date: 07/16/2007
Reference Number: RN101053379
Project Manager: HWELCH

VCP TCEQ:
Name: 300 MEDINA
Address: 301 SAN MARCOS ST
City,State,Zip: AUSTIN, TX 78702
Region: REGION 11 - AUSTIN

AUSTIN METAL IRON (Continued) **S103865174**

Facility ID:	646
VCP Record Date:	11/07/1997
Facility Type:	MFG
PCA Number:	31556
Project Manager:	JSWITEK
Phase:	CONDITIONAL
Acres at Site:	2.4
REM Program:	VCP
RN Number:	RN101053379
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	ACTIVE
Region Notified of Application:	11/03/1997
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	TXD981918162
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	07/16/2007
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	11/03/1997
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1998-01-15 00:00:00
Soil Target COC Class:	TPH; METALS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	646
Leaking Petroleum Storage Registration Tank:	97147
Project Number:	315560
Off Site?:	Not reported
Media:	ELECTRONIC AND PAPER
IOP Number:	Not reported
File Location:	D217 AND WCC; 299N, RACK 3, BOX 140
Latitude:	0.00
Longitude:	0.00

Contact:

REM Program:	VCP
Program ID:	646
RN Number:	RN101053379
CN Number:	CN600612907
CN Name:	300 MEDINA INCORPORATED
Role Code:	APPLCONT
Contact Name:	SHAPIRO, ROBERT

AUSTIN METAL IRON (Continued) **S103865174**

Contact Title:	Not reported
Organization Name:	300 MEDINA CORP
Mailing Address:	PO BOX 2115
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78768
Contact Telephone:	(512) 477-4640
Contact Telephone Ext:	0

GCC:

Name:	300 MEDINA CORPORATION
Address:	301 SAN MARCOS STREET
City,State,Zip:	AUSTIN, TX
Division:	RMD/VC
New Cases:	Not reported
File Number:	0646
Contamination Description:	TPH, METALS
Date Of Earliest Known Contamination Confirmation:	11/7/1997
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	2 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	300 MEDINA CORPORATION
Address:	301 SAN MARCOS STREET
City,State,Zip:	AUSTIN, TX
Division:	REM/VC
New Cases:	Not reported
File Number:	646
Contamination Description:	TPH, CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation:	11/7/1997
Enforcement Status - Level Of Agency Response:	0B -
Enforcement Status - Site Activity Status:	5 -
Data Quality 1:	E
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	300 MEDINA
Address:	301 SAN MARCOS ST
City,State,Zip:	AUSTIN, TX
Division:	REM/VC
New Cases:	Not reported
File Number:	646
Contamination Description:	TPH, CHLORINATED SOLVENTS

AUSTIN METAL IRON (Continued) **S103865174**

Date Of Earliest Known Contamination Confirmation: 09/05/1996
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 6D -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 646
Contamination Description: TPH, CHLORINATED SOLVENTS
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: REM/DCRP
New Cases: Not reported
File Number: 646
Contamination Description: TPH, CHLORINATED SOLVENTS TPH
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5D -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VC

AUSTIN METAL IRON (Continued) **S103865174**

New Cases: Not reported
File Number: 646
Contamination Description: TPH, METALS
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 646
Contamination Description: TPH, METALS
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 5 -
Enforcement Status - Site Activity Status: 5 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: RMD/VC
New Cases: Not reported
File Number: 646
Contamination Description: TPH, METALS
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION

AUSTIN METAL IRON (Continued) **S103865174**

Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 646
Contamination Description: TPH, CHLORINATED SOLVENTS TPH
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5D -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: 300 MEDINA CORPORATION
Address: 301 SAN MARCOS STREET
City,State,Zip: AUSTIN, TX
Division: REM/VC
New Cases: Not reported
File Number: 646
Contamination Description: TPH, CHLORINATED SOLVENTS TPH
Date Of Earliest Known Contamination Confirmation: 11/7/1997
Enforcement Status - Level Of Agency Response: 0B -
Enforcement Status - Site Activity Status: 5D -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

COMP HIST:
RN Number: RN101053379
Name: 300 MEDINA
Address: Not reported
City,State,Zip: AUSTIN, TX
Region: REGION 11 - AUSTIN
CN Number: CN601271943
CN Name: AUSTIN METAL & IRON CO LP
CN Rating: 0
Classification: UNCLASSIFIED
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: UNCLASSIFIED
Date Rated 2: 09/01/2022
Date Published to Web 2: 11/15/2022
NAICS Code: 236116
SIC Code: 4225

AUSTIN METAL IRON (Continued) **S103865174**

Related Number: 646,646

CENTRAL REGISTRY:

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600612907
Customer Name:	300 MEDINA INCORPORATED
Customer Legal Name:	300 Medina, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601271943
Customer Name:	AUSTIN METAL & IRON CO LP
Customer Legal Name:	Austin Metal & Iron Co., L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600612907
Customer Name:	300 MEDINA INCORPORATED
Customer Legal Name:	300 Medina, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

AUSTIN METAL IRON (Continued) **S103865174**

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601271943
Customer Name:	AUSTIN METAL & IRON CO LP
Customer Legal Name:	Austin Metal & Iron Co., L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600612907
Customer Name:	300 MEDINA INCORPORATED
Customer Legal Name:	300 Medina, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600612907
Customer Name:	300 MEDINA INCORPORATED
Customer Legal Name:	300 Medina, Incorporated
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST

AUSTIN METAL IRON (Continued) **S103865174**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601271943
Customer Name:	AUSTIN METAL & IRON CO LP
Customer Legal Name:	Austin Metal & Iron Co., L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN101053379
Name:	300 MEDINA
Address:	301 SAN MARCOS ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3845
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601271943
Customer Name:	AUSTIN METAL & IRON CO LP
Customer Legal Name:	Austin Metal & Iron Co., L.P.
Customer Ownership Type:	PARTNERSHIP
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

RO2957 **UNIVAC OF TEXAS** **RCRA NonGen / NLR** **1000429284**
East **1115 OLD BASTROP HWY** **FINDS** **TXD199840935**
1/8-1/4 **AUSTIN, TX 78742** **ECHO**
0.168 mi. **TX Ind. Haz Waste**
886 ft. **Site 5 of 7 in cluster RO**

Actual:
473 ft.

Focus Map:
16

RCRA Listings:

Date Form Received by Agency:	20200129
Handler Name:	Univac Of Texas
Handler Address:	1115 OLD BASTROP HWY
Handler City,State,Zip:	AUSTIN, TX 78742-2632
EPA ID:	TXD199840935
Contact Name:	JOE GARCIA
Contact Address:	1115 OLD BASTROP HWY
Contact City,State,Zip:	AUSTIN, TX 78742-2632
Contact Telephone:	512-385-8394
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

UNIVAC OF TEXAS (Continued) **1000429284**

Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1115 OLD BASTROP HWY
Mailing City,State,Zip:	AUSTIN, TX 78742-2632
Owner Name:	Univac Of Texas
Owner Type:	Private
Operator Name:	Univac Of Texas
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200204
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: UNIVAC OF TEXAS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

UNIVAC OF TEXAS (Continued) **1000429284**

Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: UNIVAC OF TEXAS
Legal Status: Private
Date Became Current: 20010213
Date Ended Current: Not reported
Owner/Operator Address: 1115 OLD BASTROP HWY
Owner/Operator City,State,Zip: AUSTIN, TX 78742
Owner/Operator Telephone: 512-385-8394
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: UNIVAC OF TEXAS
Legal Status: Private
Date Became Current: 20010213
Date Ended Current: Not reported
Owner/Operator Address: 1115 OLD BASTROP HWY
Owner/Operator City,State,Zip: AUSTIN, TX 78742-2632
Owner/Operator Telephone: 512-385-8394
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNIVAC OF TEXAS
Legal Status: Private
Date Became Current: 20010213
Date Ended Current: Not reported
Owner/Operator Address: 1115 OLD BASTROP HWY
Owner/Operator City,State,Zip: AUSTIN, TX 78742
Owner/Operator Telephone: 512-385-8394
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNIVAC OF TEXAS
Legal Status: Private
Date Became Current: 20010213
Date Ended Current: Not reported
Owner/Operator Address: 1115 OLD BASTROP HWY
Owner/Operator City,State,Zip: AUSTIN, TX 78742-2632
Owner/Operator Telephone: 512-385-8394
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19891010

UNIVAC OF TEXAS (Continued) **1000429284**

Handler Name: UNIVAC OF TEXAS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010213
Handler Name: UNIVAC OF TEXAS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200129
Handler Name: UNIVAC OF TEXAS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48411
NAICS Description: GENERAL FREIGHT TRUCKING, LOCAL

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005076880

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

UNIVAC OF TEXAS (Continued) **1000429284**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000429284
Registry ID:	110005076880
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005076880
Name:	UNIVAC OF TEXAS
Address:	1115 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742

Ind. Haz Waste:

Name:	UNIVAC OF TEXAS
Address:	1115 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 78742
Permit Number:	Not reported
Registration Number:	41484
Registration Initial Notification Date:	09/18/1989
Registration Last Amendment Date:	01/29/2020
EPA Identification:	TXD199840935
Primary NAICS Code:	484110
Status Change Date:	19890918
Land Type:	PRIVATE
Description of Facility Site Location:	1115 Old Bastrop Hwy, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	UNIVAC OF TEXAS
Contact Name:	JOE GARCIA
Contact Telephone Number:	512-3858394
Mailing Address:	1115 OLD BASTROP HWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787422632
Mailing County:	UNITED STATES

UNIVAC OF TEXAS (Continued) **1000429284**

Facility Country:	UNITED STATES
TNRCC Facility ID:	17873
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200130
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	1
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	UNIVAC OF TEXAS
Operator Address:	1115 OLD BASTROP HWY
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78742
Operator Country:	UNITED STA
Operator Telephone:	1-512-3858394
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	UNIVAC OF TEXAS
Owner Mailing Address:	1115 OLD BASTROP HWY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78742
Owner Country:	UNITED STA
Owner Telephone:	1-512-3858394
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1115 OLD BASTROP HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Phone:	1-512-3858394

UNIVAC OF TEXAS (Continued) **1000429284**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1115 OLD BASTROP HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Phone:	1-512-3858394
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JOE GARCIA
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1115 OLD BASTROP HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78742
Contact Phone:	1-512-3858394
Contact Fax:	Not reported
Contact Email:	Not reported

RO2958 **AA AUTO & EQUIPMENT** **TX UST** **U004144060**
East **1115 OLD BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78742**
0.168 mi.
886 ft. **Site 6 of 7 in cluster RO**

Actual:
473 ft.

Focus Map:
16

UST:

Name:	AA AUTO & EQUIPMENT
Address:	1115 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 787422632
AI Number:	56977
Facility Type:	RETAIL
Facility Begin Date:	12/03/1990
Facility Status:	INACTIVE
Additional ID:	383337672003221
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78742
Contact Name/Title:	,
Contact Organization Name:	AA AUTO & EQUIPMENT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123890676
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported

AA AUTO & EQUIPMENT (Continued) **U004144060**

Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/03/1990
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,TANK CHECK ENV SVCS
Application Received Date On Earliest Reg Form:	12/03/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	845313432009295
Additional ID:	383337672003221
Ai Number:	56977
Operator CN:	CN603573510
Operator Name:	ALI ARABZADEGAN
Operator Effective Begin Date:	12/13/1991
Operator Type:	IN
Operator Role:	OPRCON
Contact Name:	/
Contact Organization Name:	ARABZADEGAN ALI
Contact Mailing Address (Delivery):	PO BOX 92303
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78709-2303
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	3890676
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603573510
Owner Last Name:	ARABZADEGAN
Owner First Name:	ALI
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	PO BOX 92303
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78709
Contact Mailing Zip5:	2303
Contact Phone Number/Ext:	1 512 3890676/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	845313432009295
Additional ID:	383337672003221
AI Number:	56977
Owner Effective Begin Date:	12/13/1991
State Tax ID:	Not reported
Contact Role:	OWNCON

AA AUTO & EQUIPMENT (Continued) **U004144060**

Contact Name/Title:	/
Contact Organization Name:	ARABZADEGAN ALI

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/03/1990
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	137172
Facility ID:	80459
Ai Number:	56977
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/18/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

AA AUTO & EQUIPMENT (Continued) **U004144060**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/01/1987

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	131328
UST ID:	137172
AI Number:	56977
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1991
Tank Registration Date:	10/22/2009
Number of Compartments:	1
Tank Capacity:	500

AA AUTO & EQUIPMENT (Continued) **U004144060**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	212799
Facility ID:	80459
Ai Number:	56977
Tank Id:	2
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	12/01/1994
Empty:	Y
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

AA AUTO & EQUIPMENT (Continued) **U004144060**

Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	131329
UST ID:	212799
AI Number:	56977
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ARABZADEGAN ALI
Contact Mailing Address (Delivery):	PO BOX 92303
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78709 2303
Phone Number/Ext:	512 3890676/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80459
Additional ID:	383337672003221

AA AUTO & EQUIPMENT (Continued) **U004144060**

Princ ID:	845313432009295
AI Number:	56977
Facility Name:	AA AUTO & EQUIPMENT
AR Number:	70319
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

RH2959 **RILEY SEVERN** **TX HIST UST** **S128729246**
WNW **919 W 12TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.170 mi.
896 ft. **Site 3 of 4 in cluster RH**

Actual:
479 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	RILEY SEVERN
Address:	919 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0335
HID UST:	335
Inspection:	Not reported
Due:	06/01/2012

RH2960 **RILEY SEVERN** **TX HIST UST** **S128729288**
WNW **919 W 12TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.170 mi.
896 ft. **Site 4 of 4 in cluster RH**

Actual:
479 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	RILEY SEVERN
Address:	919 W 12TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0477
HID UST:	477
Inspection:	Not reported
Due:	06/01/2012

2961 **MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS** **RCRA NonGen / NLR** **1000149216**
WNW **5600 SUNSHINE DR** **FINDS** **TXD120710421**
1/8-1/4 **AUSTIN, TX 78756** **ECHO**
0.170 mi. **TX ASBESTOS**
899 ft. **TX Ind. Haz Waste**

Actual:
697 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Isd
Handler Address:	SUNSHINE DR
Handler City,State,Zip:	AUSTIN, TX 78756
EPA ID:	TXD120710421
Contact Name:	WAYNE SCHADE PHD
Contact Address:	GUADALUPE ROOM 210

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-451-8411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Austin Isd
Owner Type:	Not reported
Operator Name:	Austin Isd
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P005
Waste Description: 2-Propen-1-Ol (Or) Allyl Alcohol

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U012
Waste Description: Aniline (I,T) (Or) Benzenamine (I,T)

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U056
Waste Description: Benzene, Hexahydro- (I) (Or) Cyclohexane (I)

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U077
Waste Description: Ethane, 1,2-Dichloro- (Or) Ethylene Dichloride

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U082
Waste Description: 2,6-Dichlorophenol (Or) Phenol, 2,6-Dichloro-

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U123
Waste Description: Formic Acid (C,T)

Waste Code: U144
Waste Description: Acetic Acid, Lead(2+) Salt (Or) Lead Acetate

Waste Code: U146
Waste Description: Lead Subacetate (Or) Lead, Bis(Acetato-O)Tetrahydroxytri-

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U170
Waste Description: P-Nitrophenol (I,T) (Or) Phenol, 4-Nitro-

Waste Code: U188
Waste Description: Phenol

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U218
Waste Description: Ethanethioamide (Or) Thioacetamide

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: District
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN ISD
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860814
Handler Name: MCCALLUM HIGH SCHOOL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Receive Date:	20010823
Handler Name: AUSTIN ISD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005072330

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000149216
Registry ID:	110005072330
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005072330
Name:	MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS
Address:	5600 SUNSHINE DR
City,State,Zip:	AUSTIN, TX 78756

ASBESTOS:
Name: MCCALLUM HIGH SCHOOL

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2021
Notification Number:	2020007407
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/07/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/07/2020
Certification Statement Phone:	512-414-3239
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DR
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	ANGELA KIZZEE
Violation:	Not reported
Complaint Date:	12/31/2015
Notification Number:	2015008449
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/03/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/16/2014
Certification Statement Phone:	512-414-3299
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM
Address:	5600 SUNSHINE DR.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016009865
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/09/2016
Certification Statement Phone:	512-414-3299
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Matthew Gonterman
Violation:	Not reported
Complaint Date:	12/31/2022
Notification Number:	2021008261
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Inspector Name:	Not reported
Date Report Received:	12/10/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/10/2021
Certification Statement Phone:	512-414-3239
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/06/2016
Reason for Inspection:	Dana Mitchell
Violation:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Complaint Date:	06/17/2016
Notification Number:	2016003894
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/24/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/24/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	5
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/28/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/06/2016
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	06/17/2016
Notification Number:	2016003894
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/11/2016
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	5
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/26/2016

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2017009133
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/06/2017

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Certification Statement Phone:	512-414-3299
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2019009038
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/09/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/09/2019
Certification Statement Phone:	512-414-3239
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MACCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Dana Mitchell
Violation:	Not reported
Complaint Date:	09/21/2021
Notification Number:	2021006070
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	09/07/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/07/2021
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/21/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Arthur Kent Burcham
Violation:	Not reported
Complaint Date:	06/24/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/24/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/24/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/20/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/20/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/07/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Arthur Kent Burcham
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/06/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/06/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/16/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Arthur Kent Burcham
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/14/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Date of inspection:	Not reported
Reason for Inspection:	Arthur Burcham
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/31/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/31/2022
Certification Statement Phone:	512-750-8432
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Arthur Kent Burcham
Violation:	Not reported
Complaint Date:	07/08/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/10/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/10/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/17/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Arthur Kent Burcham
Violation:	Not reported
Complaint Date:	05/31/2022
Notification Number:	2022002413
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/08/2022
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	619
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Matthew Gonterman
Violation:	Not reported
Complaint Date:	12/31/2023
Notification Number:	2022008182
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/13/2022

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/13/2022
Certification Statement Phone:	512-414-3239
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2023
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DR.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2015009159

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/15/2015
Certification Statement Phone:	512-414-3299
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/06/06
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/06/2016
Client Code:	1500
Client Name:	Environmental Notification

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

License Number:	2016003894
File Number:	8816
License Status Description:	Paid
Expiration Date:	06/17/2016
Original Date:	05/11/2016
Rank Effective Date:	05/11/2016
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	1422
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DRIVE
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Les Green
Violation:	Not reported
Complaint Date:	12/31/2019
Notification Number:	2018009108
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2018
Certification Statement Phone:	512-414-3299
Is The Facility a School or K-12?:	Y

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	MCCALLUM HIGH SCHOOL
Address:	5600 SUNSHINE DR
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	69668
Registration Initial Notification Date:	08/30/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD120710421
Primary NAICS Code:	Not reported
Status Change Date:	19860830
Land Type:	Not reported
Description of Facility Site Location:	5600 Sunshine Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	WAYNE SCHADE PHD
Contact Telephone Number:	512-4518411
Mailing Address:	6100 GUADALUPE ST RM 210
Mailing Address2:	ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 787524420
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24540
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	6100 GUADALUPE ST RM 210
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4518411
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	6100 GUADALUPE ST RM 210
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4518411
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	WAYNE SCHADE PHD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	ROOM 210
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752

MCCALLUM HIGH SCHOOL ADDITIONS AND RENOVATIONS (Continued) **1000149216**

Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

2962 WSW 1/8-1/4 0.171 mi. 905 ft. | **THE LITHOPRINT CO**
1825 S IH 35
AUSTIN, TX 78741 | **RCRA NonGen / NLR** | **1000982580**
TX0000957423

Actual: 541 ft.

Focus Map: 14

RCRA Listings:

Date Form Received by Agency:	20040526
Handler Name:	The Lithoprint Co
Handler Address:	S IH 35
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TX0000957423
Contact Name:	JEFF MABBETT
Contact Address:	S IH 35
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Telephone:	512-440-8822
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	S IH 35
Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Name:	Eckholmdennis
Owner Type:	Private
Operator Name:	Eckholmdennis
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

THE LITHOPRINT CO (Continued) **1000982580**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20050330
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DENNIS ECKHOLM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1825 S INTERSTATE 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78759
Owner/Operator Telephone:	512-330-8822
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ECKHOLMDENNIS	
Legal Status:	Private
Date Became Current:	20030123
Date Ended Current:	Not reported
Owner/Operator Address:	1825 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ECKHOLMDENNIS	
Legal Status:	Private
Date Became Current:	20030123

THE LITHOPRINT CO (Continued) **1000982580**

Date Ended Current:	Not reported
Owner/Operator Address:	1825 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: ECKHOLMDENNIS	
Legal Status:	Private
Date Became Current:	20040526
Date Ended Current:	Not reported
Owner/Operator Address:	1825 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: ECKHOLMDENNIS	
Legal Status:	Private
Date Became Current:	20040526
Date Ended Current:	Not reported
Owner/Operator Address:	1825 S IH 35
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19941201
Handler Name: THE LITHOPRINT CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20030123
Handler Name: THE LITHOPRINT CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

THE LITHOPRINT CO (Continued) **1000982580**

Electronic Manifest Broker: Not reported

Receive Date: 20040526
Handler Name: THE LITHOPRINT CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 323119
NAICS Description: OTHER COMMERCIAL PRINTING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

RQ2963 **SOUTH AUSTIN SERVICE CENTER** **TX LPST** **U001273550**
ESE **3815 WOODBURY DR** **TX UST** **N/A**
1/8-1/4 **AUSTIN, TX 78704** **TX HIST UST**
0.171 mi.
905 ft. **Site 1 of 3 in cluster RQ**

Actual:
664 ft.

Focus Map:
14

LPST:
Name: SOUTH AUSTIN SERVICE CENTER
Address: 3815 WOODBURY DR
City,State,Zip: AUSTIN, TX 78785
Facility ID: 0041137
LPST Id: 102299
Facility Location: 3815 WOODBURY
TCEQ Region# and City: REGION 11 - AUSTIN
Region City: AUSTIN
Discovered Date: 03/13/1992
Entered Date: 04/23/1992
Reported Date: 03/24/1992
Closure Date: 04/16/1993
Priority: 5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program: 2 - REGION
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary: 2
Coordinators RPR: RPR
Responsible Party Name: Not reported
Responsible Party Contact: DARREN LEDDY
Responsible Party Address: 400 W 14TH ST STE 900
Responsible Party City,St,Zip: AUSTIN, TX 78701

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Responsible Party Telephone:	512/465-1100
Reported Date:	03/24/1992
Case Start Date:	04/16/1993
Reference Number:	RN104091822
Project Manager:	HWELCH

UST:

Name:	SOUTH AUSTIN SERVICE CENTER
Address:	3815 WOODBURY DR
City,State,Zip:	AUSTIN, TX 787047318
AI Number:	41137
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/22/1987
Facility Status:	INACTIVE
Additional ID:	954398502003357
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78785
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/02/1986
Signature Name/Title On Earliest Reg Form:	JAMES C WELLS,DIV SAFETY COORD
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602276305
Owner Last Name:	SOUTHERN UNION COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Contact Address Deliverable:	Not reported
Princ ID:	242547782003199
Additional ID:	954398502003357
AI Number:	41137
Owner Effective Begin Date:	01/22/1987
State Tax ID:	17505715924
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108988
Facility ID:	55549
Ai Number:	41137
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	50373
UST ID:	108988
AI Number:	41137
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	108989
Facility ID:	55549
Ai Number:	41137
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/09/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	50374
UST ID:	108989
AI Number:	41137
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	SOUTHERN UNION COMPANY
Contact Mailing Address (Delivery):	1301 S MO PAC EXPY STE 400
Contact Mailing Address (Internal Delivery):	Not reported

SOUTH AUSTIN SERVICE CENTER (Continued) **U001273550**

Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6918
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	55549
Additional ID:	954398502003357
Princ ID:	242547782003199
AI Number:	41137
Facility Name:	SOUTH AUSTIN SERVICE CENTER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SUSAN GROCE/

HIST UST AUSTIN:

Name:	SOUTHERN UNION GAS CO.
Address:	3815 WOODBURY DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0317
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RR2964 **GEORGE COFFEY LINCOLN-MERCURY** **TX HIST UST** **S128729029**
WNW **900 W 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.172 mi.
907 ft. **Site 1 of 2 in cluster RR**

Actual:
477 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	GEORGE COFFEY LINCOLN-MERCURY
Address:	900 W 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0421
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RR2965 **GEORGE COFFEY LINC-MERC** **TX UST** **U001274231**
WNW **900 W 6TH** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.172 mi.
907 ft. **Site 2 of 2 in cluster RR**

Actual:
477 ft.

Focus Map:
11

UST:

Name:	GEORGE COFFEY LINC-MERC
Address:	900 W 6TH
City,State,Zip:	AUSTIN, TX 78703
AI Number:	41953
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/27/1987
Facility Status:	INACTIVE

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Additional ID:	354590992005285
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	ROY BUTLER,
Contact Organization Name:	GEORGE COFFEY LINC-MERC
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128376550
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/29/1986
Signature Name/Title On Earliest Reg Form:	J B ARGERSINGER,DIR PARTS SEV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601414600
Owner Last Name:	BUTLER
Owner First Name:	ROY
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	619852012002204
Additional ID:	354590992005285
AI Number:	41953
Owner Effective Begin Date:	01/31/1991
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	111092
Facility ID:	71307
Ai Number:	41953
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	104659
UST ID:	111092
AI Number:	41953
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	111093
Facility ID:	71307
Ai Number:	41953
Tank Id:	1

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	104660
UST ID:	111093
AI Number:	41953

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	111094
Facility ID:	71307
Ai Number:	41953
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/01/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	550
UST Comprt ID:	104661
UST ID:	111094
AI Number:	41953
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170368
Facility ID:	71307
Ai Number:	41953
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	30
UST Comprt ID:	104662
UST ID:	170368
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170369
Facility ID:	71307
Ai Number:	41953
Tank Id:	7
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	30
UST Comprt ID:	104663
UST ID:	170369
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170370
Facility ID:	71307
Ai Number:	41953
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	30
UST Comprt ID:	104664
UST ID:	170370
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170371
Facility ID:	71307
Ai Number:	41953
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	30
UST Comprt ID:	104665
UST ID:	170371
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170372
Facility ID:	71307
Ai Number:	41953
Tank Id:	14
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	14
Tank Capacity:	30
UST Comprt ID:	104666
UST ID:	170372
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170373
Facility ID:	71307
Ai Number:	41953

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Id:	13
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	13
Tank Capacity:	30
UST Comprt ID:	104667
UST ID:	170373

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170374
Facility ID:	71307
Ai Number:	41953
Tank Id:	12
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	12
Tank Capacity:	30
UST Comprt ID:	104668
UST ID:	170374
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170375
Facility ID:	71307
Ai Number:	41953
Tank Id:	11
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	11
Tank Capacity:	30
UST Comprt ID:	104669
UST ID:	170375
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170376
Facility ID:	71307
Ai Number:	41953
Tank Id:	10
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	10
Tank Capacity:	30
UST Comprt ID:	104670
UST ID:	170376
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170377
Facility ID:	71307
Ai Number:	41953
Tank Id:	9
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	9
Tank Capacity:	30
UST Comprt ID:	104671
UST ID:	170377
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	30
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	170378
Facility ID:	71307
Ai Number:	41953
Tank Id:	8
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1976
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	8
Tank Capacity:	30
UST Comprt ID:	104672
UST ID:	170378
AI Number:	41953
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

GEORGE COFFEY LINC-MERC (Continued) **U001274231**

Facility Billing Contacts:

Contact Organization Name:	BUTLER ROY
Contact Mailing Address (Delivery):	PO BOX 9190
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78766 9190
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	71307
Additional ID:	354590992005285
Princ ID:	619852012002204
AI Number:	41953
Facility Name:	GEORGE COFFEY LINC-MERC
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	ROY BUTLER/

RQ2966 **PREFERRED PUMP** **TX UST** **U004159582**
ESE **3805 WOODBURY DR** **N/A**
1/8-1/4 **AUSTIN, TX 78704**
0.174 mi.
917 ft. **Site 2 of 3 in cluster RQ**

Actual:
664 ft.

Focus Map:
14

UST:

Name:	PREFERRED PUMP
Address:	3805 WOODBURY DR
City,State,Zip:	AUSTIN, TX 787047318
AI Number:	76675
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	215514282004239
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/06/2004
Signature Name/Title On Earliest Reg Form:	MAUREEN FLETCHER,OWNER
Application Received Date On Earliest Reg Form:	08/13/2004
Signature Role On Earliest Reg Form:	OWNER

PREFERRED PUMP (Continued) **U004159582**

Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602659997
Owner Last Name:	KIM-BOB REALTY CORP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	477359372004194
Additional ID:	215514282004239
AI Number:	76675
Owner Effective Begin Date:	08/31/1987
State Tax ID:	11332397774
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/13/2004
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	203543
Facility ID:	117717
Ai Number:	76675
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/01/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

PREFERRED PUMP (Continued) **U004159582**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	184526
UST ID:	203543
AI Number:	76675
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

PREFERRED PUMP (Continued) **U004159582**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/13/2004
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	203544
Facility ID:	117717
Ai Number:	76675
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/01/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

PREFERRED PUMP (Continued) **U004159582**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	184527
UST ID:	203544
AI Number:	76675
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

PREFERRED PUMP (Continued) **U004159582**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/13/2004
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	203545
Facility ID:	117717
Ai Number:	76675
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/01/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

PREFERRED PUMP (Continued) **U004159582**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	184528
UST ID:	203545
AI Number:	76675
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

PREFERRED PUMP (Continued) **U004159582**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	KIM-BOB REALTY CORP
Contact Mailing Address (Delivery):	3381 ROLAND RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	WHITESBORO, TX 76273 7518
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	117717
Additional ID:	215514282004239
Princ ID:	477359372004194
AI Number:	76675
Facility Name:	PREFERRED PUMP
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

RQ2967 **PERFERRED PUMP** **TX RDR** **S127543254**
ESE **3805 WOODBURY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.174 mi.
917 ft. **Site 3 of 3 in cluster RQ**

Actual:
664 ft.

Focus Map:
14

RDR:

RDR ID:	13758
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	PERFERRED PUMP
Address:	3805 WOODBURY
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/29/2004
Due Date:	1/28/2005
Tank Owner:	KIM/BOB REALTY
Contact Person:	MAUREEN FLETCHER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/25/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	8/13/04
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported

PERFERRED PUMP (Continued) **S127543254**

NOLPST Letter Date:	1/25/2005
Date Report Returned:	10/20/2004
Region:	Not reported
DKC RDR (misfiled):	Not reported

2968 WNW 1/8-1/4 0.174 mi. 917 ft. **SEAHOLM DISTRICT UPRR**
S 3RD STREET BETWEEN WEST AVENUE AND LAMAR
AUSTIN, TX 77502

US BROWNFIELDS FINDS **1012089629 N/A**

Actual: 457 ft.

Focus Map: 11

US BROWNFIELDS:

Name:	SEAHOLM DISTRICT UPRR
Address:	S 3RD STREET BETWEEN WEST AVENUE AND LAMAR
Recipient name:	R6 TBA - Texas (Pre-law Superfund TBA)
Grant type:	TBA
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.267711
Longitude:	-97.754162
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	10934
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - TBA Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	n/a
Start Date:	3/12/2003
Ownership Entity:	Not reported
Completion Date:	3/12/2003
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported

SEAHOLM DISTRICT UPRR (Continued) **1012089629**

IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	282
Below Poverty Percent:	9.29
Meidan Income:	8894
Meidan Income Number:	541
Meidan Income Percent:	17.83
Vacant Housing Number:	425
Vacant Housing Percent:	19.28
Unemployed Number:	131
Unemployed Percent:	4.32

Name:	SEAHOLM DISTRICT UPRR
Address:	S 3RD STREET BETWEEN WEST AVENUE AND LAMAR
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0
Latitude:	30.267711
Longitude:	-97.754162
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Not reported
Datum:	World Geodetic System of 1984
Acres Property ID:	10934
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported

SEAHOLM DISTRICT UPRR (Continued) **1012089629**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	98609301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	282
Below Poverty Percent:	9.29
Meidan Income:	8894
Meidan Income Number:	541
Meidan Income Percent:	17.83
Vacant Housing Number:	425
Vacant Housing Percent:	19.28
Unemployed Number:	131
Unemployed Percent:	4.32

FINDS:
Registry ID: 110038692885

SEAHOLM DISTRICT UPRR (Continued) **1012089629**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

RL2969 **PROPOSED SPRING CONDOMINIUMS** **TX IHW CORR ACTION** **S113416944**
WNW **302 BOWIE ST** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.176 mi.
928 ft. **Site 5 of 6 in cluster RL**

Actual:
466 ft.

Focus Map:
11

IHW CORR ACTION:

Name:	PROPOSED SPRING CONDOMINIUMS
Address:	302 BOWIE ST
City,State,Zip:	AUSTIN, TX 78703
Program Id:	T2118
Location Desc:	NORTHWEST CORNER OF 3RD ST AND BOWIE ST
RN NUM:	RN105023113
Status:	ACTIVE
Status Date:	07/14/2006
EDR Link ID:	T2118
Project Phase:	ONGOING WORKLOAD
Phase Status Date:	08/24/2006
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

RS2970 **7 ELEVEN STO4RE 36643** **TX LPST** **1010715702**
ENE **814 E 7TH ST** **FINDS** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.176 mi.
929 ft. **Site 1 of 9 in cluster RS**

Actual:
484 ft.

Focus Map:
11

LPST:

Name:	AUSTIN SHELL 411
Address:	814 E 7TH ST
City,State,Zip:	AUSTIN, TX 78702
Facility ID:	0073993
LPST Id:	117501
Facility Location:	814 E 7TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/19/2006
Entered Date:	12/04/2007
Reported Date:	12/19/2006
Closure Date:	12/05/2007
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**

7 ELEVEN STO4RE 36643 (Continued) **1010715702**

Coordinators Primary:	1P
Coordinators RPR:	DB2
Responsible Party Name:	Not reported
Responsible Party Contact:	CLIFF SNYDER
Responsible Party Address:	PO BOX 2523
Responsible Party City,St,Zip:	GEORGETOWN, TX 78627
Responsible Party Telephone:	512/388-1312
Reported Date:	12/19/2006
Case Start Date:	12/05/2007
Reference Number:	RN101490043
Project Manager:	DBRATBER

FINDS:
Registry ID: 110033368237

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

RS2971 **AUSTIN SHELL/STORE 411** **TX RDR** **S127539485**
ENE **814 E 7TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.176 mi.
929 ft. **Site 2 of 9 in cluster RS**

Actual:
484 ft.

Focus Map:
11

RDR:

RDR ID:	16481
Facility ID:	73993
RN:	Not reported
CN:	Not reported
Name:	AUSTIN SHELL/STORE 411
Address:	814 E 7TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/30/2007
Due Date:	10/29/2007
Tank Owner:	METRO SUPPLIERS INC
Contact Person:	CLIFF SYNDER
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED AN LPST#?RDR
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported

AUSTIN SHELL/STORE 411 (Continued) **S127539485**

NOLPST Letter Date: Not reported
Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

RS2972 **TP 2519** **TX RDR** **S127539486**
ENE **814 E 7TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.176 mi.
929 ft. **Site 3 of 9 in cluster RS**

Actual:
484 ft.

Focus Map:
11

RDR:

RDR ID:	19173
Facility ID:	73993
RN:	Not reported
CN:	Not reported
Name:	TP 2519
Address:	814 E 7TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/20/2010
Due Date:	11/19/2010
Tank Owner:	G L THOMAS PETROLEUM LLC
Contact Person:	KIM BUESING
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	3/15/2012
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR 11/15/10;NO FURTHER SITE CHECK REQUIRED. RDR 1/7/2011;SIR 3/4/11; RDR 4/29/11;SIR3 SENT 7/15/11; RDR 8/9/2011;SIR4 SENT 9/27/11; RDR 10/26/2011;rdr 11/14/11.
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	3/15/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

RT2973 **COFFEY LINCOLN MERCURY** **RCRA NonGen / NLR** **1000228691**
ENE **900 6TH ST** **FINDS** **TXD030917090**
1/8-1/4 **AUSTIN, TX 78702** **ECHO**
0.176 mi.
929 ft. **Site 1 of 5 in cluster RT**

Actual:
488 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Coffey Lincoln Mercury
Handler Address:	6TH ST
Handler City,State,Zip:	AUSTIN, TX 78702
EPA ID:	TXD030917090
Contact Name:	AARON OVERSTREET
Contact Address:	6TH ST

COFFEY LINCOLN MERCURY (Continued) **1000228691**

Contact City,State,Zip:	AUSTIN, TX 78702
Contact Telephone:	512-472-8401
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	6TH ST
Mailing City,State,Zip:	AUSTIN, TX 78702
Owner Name:	Coffey Lincoln Mercury
Owner Type:	Not reported
Operator Name:	Coffey Lincoln Mercury
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

COFFEY LINCOLN MERCURY (Continued) **1000228691**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: COFFEY LINCOLN MERCURY
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 900 6TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702
Owner/Operator Telephone: 512-472-8401
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GEORGE COFFEY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COFFEY LINCOLN MERCURY
Legal Status: Not reported
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 900 6TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78702
Owner/Operator Telephone: 512-472-8401
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19841126
Handler Name: COFFEY LINCOLN-MERCURY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

COFFEY LINCOLN MERCURY (Continued) **1000228691**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: COFFEY LINCOLN MERCURY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005046066

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000228691
Registry ID: 110005046066
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005046066
Name: COFFEY LINCOLN MERCURY
Address: 900 6TH ST
City,State,Zip: AUSTIN, TX 78702

RT2974 **COFFEY LINCOLN MERCURY** **TX Ind. Haz Waste** **S102749764**
ENE **900 E 6TH ST** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.176 mi.
929 ft. **Site 2 of 5 in cluster RT**

Actual:
488 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	COFFEY LINCOLN MERCURY
Address:	900 E 6TH ST
City,State,Zip:	AUSTIN, TX 78702
Permit Number:	Not reported
Registration Number:	66260
Registration Initial Notification Date:	11/07/1984
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD030917090
Primary NAICS Code:	Not reported
Status Change Date:	19841107
Land Type:	Not reported
Description of Facility Site Location:	900 6th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Contact Name:	AARON OVERSTREET
Contact Telephone Number:	512-4728401
Mailing Address:	900 E 6TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787023280
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21544
Site Owner Tax ID:	741847491
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030910
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

COFFEY LINCOLN MERCURY (Continued) **S102749764**

Ind. Haz Waste:

Operator Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Operator Address:	900 E 6THST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78702
Operator Country:	UNITED STA
Operator Telephone:	1-512-4728401
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17418474916
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Owner Mailing Address:	900 E 6THST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78702
Owner Country:	UNITED STA
Owner Telephone:	1-512-4728401
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17418474916
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	900 E 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-4728401
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	900 E 6THST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-4728401
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	AARON OVERSTREET
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	900 E 6THST
Contact Address 2:	Not reported

COFFEY LINCOLN MERCURY (Continued) **S102749764**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-4728401
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	900W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000302655
Principal Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	900W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000302655
Principal Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Attention Name:	Not reported
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100843648
Name:	COFFEY LINCOLN MERCURY
Address:	900 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3280
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600521751
Customer Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Customer Legal Name:	George Coffey Lincoln-Mercury, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	900 6th St, Austin, TX

Regulated Entity Number:	RN100843648
Name:	COFFEY LINCOLN MERCURY
Address:	900 E 6TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-3280
Status:	ACTIVE
Status Date:	##########

COFFEY LINCOLN MERCURY (Continued) **S102749764**

Customer Number:	CN600521751
Customer Name:	GEORGE COFFEY LINCOLN-MERCURY INC
Customer Legal Name:	George Coffey Lincoln-Mercury, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	900 6th St, Austin, TX

RT2975 **ARMADILLO AUTOMOTIVE** **TX RDR** **S127541769**
East **901 E 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.177 mi.
936 ft. **Site 3 of 5 in cluster RT**

Actual:
487 ft.

Focus Map:
11

RDR:

RDR ID:	18146
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	ARMADILLO AUTOMOTIVE
Address:	901 E 6TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/12/2009
Due Date:	7/11/2009
Tank Owner:	HORACE JOSEPH
Contact Person:	HORACE JOSEPH
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/15/2009
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	7/15/2009
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RT2976 **VACANT BRICK BUILDING** **TX HIST UST** **S111678756**
East **901 E. 6TH STREET** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.177 mi.
936 ft. **Site 4 of 5 in cluster RT**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	NASSOUR BROS.
Address:	901 E 6TH ST
City,State,Zip:	AUSTIN, TX

VACANT BRICK BUILDING (Continued) **S111678756**

Id UST:	H0253
HID UST:	253
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	VACANT BRICK BUILDING
Address:	901 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	DEBORAH MAYNARD
Violation:	Not reported
Complaint Date:	01/30/2017
Notification Number:	2016009223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/10/2017
Certification Statement Phone:	512-489-2306
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/16/2017

VACANT BRICK BUILDING (Continued) **S111678756**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VACANT BRICK BUILDING
Address:	901 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Deborah Maynard
Violation:	Not reported
Complaint Date:	01/19/2017
Notification Number:	2016009223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/05/2016

VACANT BRICK BUILDING (Continued) **S111678756**

Certification Statement Phone:	512-489-2306
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/05/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BRICK BUILDING
Address:	901 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	DEBORAH MAYNARD
Violation:	Not reported
Complaint Date:	01/24/2017
Notification Number:	2016009223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/04/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

VACANT BRICK BUILDING (Continued) **S111678756**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/04/2017
Certification Statement Phone:	512-489-2306
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/10/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VACANT BRICK BUILDING
Address:	901 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	DEBORAH MAYNARD
Violation:	Not reported
Complaint Date:	01/25/2017
Notification Number:	2016009223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

VACANT BRICK BUILDING (Continued) **S111678756**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	01/09/2017
Certification Statement Phone:	512-489-2306
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/11/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

VACANT BRICK BUILDING (Continued) **S111678756**

Inspection Number Grade:	Not reported
Name:	VACANT BRICK BUILDING
Address:	901 E. 6TH STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Deborah Maynard
Violation:	Not reported
Complaint Date:	12/16/2016
Notification Number:	2016009223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/11/2016
Certification Statement Phone:	512-489-2306
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/12/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

VACANT BRICK BUILDING (Continued) **S111678756**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

RT2977 **ARMADILLO AUTO** **TX HIST UST** **S128233840**
East **901 E 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.177 mi.
936 ft. **Site 5 of 5 in cluster RT**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ARMADILLO AUTO
Address:	901 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	3322
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RU2978 **TEXACO CHEMICALS** **TX CLI** **S103259070**
WNW **7114 N. LAMAR BLVD** **N/A**
1/8-1/4 **, TX**
0.178 mi.
940 ft. **Site 1 of 3 in cluster RU**

Actual:
749 ft.

Focus Map:
6

CLI:

Name:	TEXACO CHEMICALS
Address:	7114 N. LAMAR BLVD
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported

TEXACO CHEMICALS (Continued) **S103259070**

Engineer:	Not reported
Source:	1
Source Code:	Not reported
Date Opened:	1951
Date Closed:	1969
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	20.62
Long Deg:	97
Long Min:	43.11
Lat/Long (deg):	30.343667 / -97.718500
Owner:	Texaco Chemical Co
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	14
Code for Landfill:	2
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Yes
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Y
Accepts Other Description:	Laboratory
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Yes
Legal:	Yes
Maximum Depth:	5
Depth Code:	B
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	B
In Use Inspector:	Uk
Inspc Comments:	???
Comments:	Identified in list of Travis County sites; Estimate-1,040,000 lbs. of waste. Stream includes urethane polyols, filter cake, alcohols and aldehydes, and hydrocarbons
Update:	0
Reviewer:	Not reported
Flag:	Not reported

RU2979 WNW 1/8-1/4 0.178 mi. 940 ft. | **TEXACO CHEMICALS 7114 N. LAMAR BLVD TRAVIS (County), TX** | **TX CLI** | **S113416576 N/A**

Site 2 of 3 in cluster RU

Actual: 749 ft.

Focus Map: 6

CAPCOG LI:

Name:	TEXACO CHEMICALS
Address:	7114 N. LAMAR BLVD
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	1951
Date Close:	1969
Unum:	896
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	20.620000000000001
Longitude Deg:	97
Longitude Min:	43.109999999999999
Lat Dd:	30.343667
Long Dd:	-97.718500000000006
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	1
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Huntsman Petrochemical Corp.
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0
Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	14
Size Acres:	0

TEXACO CHEMICALS (Continued) **S113416576**

Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Y
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Y
Other Des:	Laboratory
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	Y
Unauthor:	Not reported
Max Depth:	5
Depth Cd:	B
Final Cov:	Not reported
Min Thick:	B
Use:	Uk
Inspection:	???
Comment:	Identified in list of Travis County sites; Estimate-1,040,000 lbs. of waste. Stream includes urethane polyols, filter cake, alcohols and aldehydes, and hydrocarbons
Latitude:	30.33816667
Longitude:	-97.7185
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part1.pdf#page=278

RU2980 **TEXACO CHEMICALS** **TX HIST LF** **S129375052**
WNW **7114 N. LAMAR BLVD** **N/A**
1/8-1/4 **TRAVIS (County), TX**
0.178 mi.
940 ft. **Site 3 of 3 in cluster RU**

Actual:
749 ft.

Focus Map:
6

HIST LF:

Name:	TEXACO CHEMICALS
Name 2:	Not reported
Address:	7114 N. LAMAR BLVD
City,State,Zip:	TX
Latitude:	30.343667
Longitude:	-97.718500
Lat Deg:	30
Lat MM:	20.62
Lon DD:	97
Lon MM:	43.11
UNUM:	896
Comments:	Identified in list of Travis County sites; Estimate-1,040,000 lbs. of waste. Stream includes urethane polyols, filter cake, alcohols and aldehydes, and hydrocarbons
Inspection:	???
COG Number:	12
COOR CD:	Not reported
TWC District:	14
Owner Name:	Texaco Chemical Co
Owner Code:	Not reported
Open Date:	1951
Close Date:	1969

TEXACO CHEMICALS (Continued) **S129375052**

Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Not reported
Industrial:	Y
Tires:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Y
Other Description:	Laboratory
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	Y
Un-Author:	Not reported
Max Depth:	5
Depth Code:	B
Final Cov:	Not reported
Min Thick:	B
Use:	Uk
Update:	No Change
Reviewer:	Not reported
Accuracy:	Geocoded at Southwest Texas State University (SWTSU) from good location information, high confidence level
Source:	1

RL2981 **BALCONES SPORTSWEAR** **TX Ind. Haz Waste** **S102758682**
WNW **910 W 3RD ST** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.178 mi.
940 ft. **Site 6 of 6 in cluster RL**

Actual:
465 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	BALCONES SPORTSWEAR
Address:	910 W 3RD ST
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	78307
Registration Initial Notification Date:	10/20/1992
Registration Last Amendment Date:	08/23/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19921020
Land Type:	Not reported
Description of Facility Site Location:	910 W 3rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG

BALCONES SPORTSWEAR (Continued) **S102758682**

Type of Generator:	NON INDUS
Company Name:	BALCONES SPORTSWEAR
Contact Name:	JACK SWINGLER
Contact Telephone Number:	512-4781126
Mailing Address:	910 W 3RD ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787035421
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	32498
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040226
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	BALCONES SPORTSWEAR
Operator Address:	910 W 3RDST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78703
Operator Country:	UNITED STA
Operator Telephone:	1-512-4781126
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BALCONES SPORTSWEAR
Owner Mailing Address:	910 W 3RDST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Country:	UNITED STA
Owner Telephone:	1-512-4781126
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

BALCONES SPORTSWEAR (Continued) **S102758682**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	SILK SCREENING SHOP
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20010823
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	910 W 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4781126
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	910 W 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4781126
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JACK SWINGLER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	910 W 3RDST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703

BALCONES SPORTSWEAR (Continued) **S102758682**

Contact Phone:	1-512-4781126
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100612829
Name:	BALCONES SPORTSWEAR
Address:	910 W 3RD ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-5421
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600322069
Customer Name:	BALCONES SPORTSWEAR
Customer Legal Name:	Balcones Sportswear
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	910 W 3rd, Austin, TX

RM2982 **CITY OF AUSTIN FLEET SERVICE CENTER 5** **RCRA NonGen / NLR** **1000412197**
NE **714 E 8TH ST** **FINDS** **TXD981901515**
1/8-1/4 **AUSTIN, TX 78701** **ECHO**
0.179 mi.
945 ft. **Site 4 of 7 in cluster RM**

Actual:
471 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20080909
Handler Name:	City Of Austin
Handler Address:	E 8TH ST
Handler City,State,Zip:	AUSTIN, TX 78701
EPA ID:	TXD981901515
Contact Name:	WILL OCONNOR
Contact Address:	BOLM RD
Contact City,State,Zip:	AUSTIN, TX 78721
Contact Telephone:	512-927-3297
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	BOLM RD
Mailing City,State,Zip:	AUSTIN, TX 78721
Owner Name:	City Of Austin
Owner Type:	Municipal
Operator Name:	City Of Austin

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20080930
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

Waste Description: Benzene

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip: AUSTIN, TX 78721
Owner/Operator Telephone: 512-927-3260
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip: AUSTIN, TX 78721
Owner/Operator Telephone: 512-927-3260
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN
Legal Status: Municipal
Date Became Current: 20080708
Date Ended Current: Not reported
Owner/Operator Address: 6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip: AUSTIN, TX 78721
Owner/Operator Telephone: 512-927-3260
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF AUSTIN

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20071220
Date Ended Current:	Not reported
Owner/Operator Address:	6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip:	AUSTIN, TX 78721
Owner/Operator Telephone:	512-927-3260
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20080708
Date Ended Current:	Not reported
Owner/Operator Address:	6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip:	AUSTIN, TX 78721
Owner/Operator Telephone:	512-927-3260
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20080909
Date Ended Current:	Not reported
Owner/Operator Address:	6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip:	AUSTIN, TX 78721
Owner/Operator Telephone:	512-927-3260
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20080909
Date Ended Current:	Not reported
Owner/Operator Address:	6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip:	AUSTIN, TX 78721
Owner/Operator Telephone:	512-927-3260
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF AUSTIN	
Legal Status:	Municipal
Date Became Current:	20071220
Date Ended Current:	Not reported
Owner/Operator Address:	6301A HAROLD CT FLEET SERVICES
Owner/Operator City,State,Zip:	AUSTIN, TX 78721
Owner/Operator Telephone:	512-927-3260
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19870126
Handler Name: AUSTIN CITY SC5	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010127
Handler Name: CITY OF AUSTIN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20071220
Handler Name: CITY OF AUSTIN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20080708
Handler Name: CITY OF AUSTIN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20080909
Handler Name: CITY OF AUSTIN	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19900301
Handler Name: AUSTIN CITY SC5	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19920922
Handler Name: AUSTIN, CITY OF	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811111
NAICS Description:	GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CITY OF AUSTIN FLEET SERVICE CENTER 5 (Continued) **1000412197**

FINDS:
Registry ID: 110005097439

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412197
Registry ID:	110005097439
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005097439
Name:	CITY OF AUSTIN FLEET SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701

RM2983 **VES SERVICE CENTER 5** **TX UST** **U001542521**
NE **714 E 8TH ST** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78701** **TX AIRS**
0.179 mi. **TX Financial Assurance**
945 ft. **Site 5 of 7 in cluster RM** **TX COMP HIST**
TX CENTRAL REGISTRY

Actual:
471 ft.

Focus Map:
11

UST:

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 787013305
AI Number:	18146
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	ACTIVE
Additional ID:	936527342002246
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	ANDY ETTLES,SVC MGR
Contact Organization Name:	VES SERVICE CENTER 5

VES SERVICE CENTER 5 (Continued) **U001542521**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129741804
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/04/2021
Signature Name/Title On Earliest Reg Form:	WILLIAM OCONNOR,FLEET PR MGR
Application Received Date On Earliest Reg Form:	05/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	840354562001227
Additional ID:	936527342002246
Ai Number:	18146
Operator CN:	CN600135198
Operator Name:	CITY OF AUSTIN
Operator Effective Begin Date:	09/02/1986
Operator Type:	CI
Operator Role:	OPRCON
Contact Name:	SANDRA CREIGHTON/
Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	505 BARTON SPRINGS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-1216
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78721
Contact Mailing Zip5:	3639
Contact Phone Number/Ext:	1 512 9782649/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

VES SERVICE CENTER 5 (Continued) **U001542521**

Princ ID:	840354562001227
Additional ID:	936527342002246
AI Number:	18146
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JIMMY TUBBS/FUEL OPS COORD
Contact Organization Name:	CITY OF AUSTIN

Self Certification:

Self Cert ID:	37550
Cert ID:	370932
AI Number:	18146
Self Certification Date:	05/25/2022
Signature Name/Title:	WILLIAM OCONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37550
Cert ID:	353842
AI Number:	18146
Self Certification Date:	05/04/2021
Signature Name/Title:	WILLIAM OCONNOR FLEET PR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37550
Cert ID:	336405
AI Number:	18146
Self Certification Date:	04/29/2020
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	320616
AI Number:	18146
Self Certification Date:	05/15/2019
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	303807
AI Number:	18146
Self Certification Date:	05/10/2018
Signature Name/Title:	WILLIAM O'CONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	286235
AI Number:	18146
Self Certification Date:	04/11/2017
Signature Name/Title:	WILLIAM OCONNOR FLT PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	270491
AI Number:	18146
Self Certification Date:	05/24/2016
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	253951
AI Number:	18146
Self Certification Date:	06/01/2015
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	236395
AI Number:	18146
Self Certification Date:	04/23/2014
Signature Name/Title:	VALERIE SPINELLI GRANTS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37550
Cert ID:	218805
AI Number:	18146
Self Certification Date:	04/18/2013
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N
Self Cert ID:	37550
Cert ID:	367
AI Number:	18146
Self Certification Date:	05/07/2012
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	366
AI Number:	18146
Self Certification Date:	04/08/2011
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SENIOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	365
AI Number:	18146
Self Certification Date:	05/10/2010
Signature Name/Title:	WILL O'CONNOR FLEET PROGRAM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	364
AI Number:	18146
Self Certification Date:	04/06/2009
Signature Name/Title:	STACEY MONROE FUEL OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	363
AI Number:	18146
Self Certification Date:	06/03/2008
Signature Name/Title:	WILL OCONNOR FLT PGM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	362
AI Number:	18146
Self Certification Date:	05/01/2007
Signature Name/Title:	PAUL GROSS FUEL OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	361
AI Number:	18146
Self Certification Date:	05/01/2006
Signature Name/Title:	PAUL GROSS FUEL OPER COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	360
AI Number:	18146
Self Certification Date:	05/02/2005
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	359
AI Number:	18146
Self Certification Date:	05/21/2004
Signature Name/Title:	MARC CHILDERS FUEL OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	358
AI Number:	18146
Self Certification Date:	04/28/2003
Signature Name/Title:	MARC CHILDERS FUEL OPERATIONS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	357
AI Number:	18146
Self Certification Date:	04/25/2002
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37550
Cert ID:	356
AI Number:	18146
Self Certification Date:	01/30/2001
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46935
Facility ID:	37550
Ai Number:	18146
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/14/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

VES SERVICE CENTER 5 (Continued) **U001542521**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	1000
UST Comprt ID:	257
UST ID:	46935
AI Number:	18146
Compartment ID:	A
Substance Stored1:	NEW OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

VES SERVICE CENTER 5 (Continued) **U001542521**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7022
Cert ID:	160248
UST Comprt ID:	471562
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160246
UST Comprt ID:	471566
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160244
UST Comprt ID:	471564
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160245
UST Comprt ID:	471565
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160249
UST Comprt ID:	471561

VES SERVICE CENTER 5 (Continued) **U001542521**

UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160247
UST Comprt ID:	471563
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160250
UST Comprt ID:	471560
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	46936
Facility ID:	37550
Ai Number:	18146
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/14/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

VES SERVICE CENTER 5 (Continued) **U001542521**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	258
UST ID:	46936
AI Number:	18146
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

VES SERVICE CENTER 5 (Continued) **U001542521**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7022
Cert ID:	160248
UST Comprt ID:	471562
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160246
UST Comprt ID:	471566
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160244
UST Comprt ID:	471564
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160245
UST Comprt ID:	471565
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160249
UST Comprt ID:	471561
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160247
UST Comprt ID:	471563

VES SERVICE CENTER 5 (Continued) **U001542521**

UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160250
UST Comprt ID:	471560
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	46939
Facility ID:	37550
Ai Number:	18146
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1977
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

VES SERVICE CENTER 5 (Continued) **U001542521**

TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	9550
UST Comprt ID:	261
UST ID:	46939
AI Number:	18146
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

VES SERVICE CENTER 5 (Continued) **U001542521**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1999

More Self Certification:

Self Cert ID:	7022
Cert ID:	160248
UST Comprt ID:	471562
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160246
UST Comprt ID:	471566
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160244
UST Comprt ID:	471564
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160245
UST Comprt ID:	471565
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160249
UST Comprt ID:	471561
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160247
UST Comprt ID:	471563
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160250
UST Comprt ID:	471560

VES SERVICE CENTER 5 (Continued) **U001542521**

UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1977
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	46938
Facility ID:	37550
Ai Number:	18146
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1977
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	9550
UST Comprt ID:	260
UST ID:	46938
AI Number:	18146
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1999

More Self Certification:

Self Cert ID:	7022

VES SERVICE CENTER 5 (Continued) **U001542521**

Cert ID:	160248
UST Comprt ID:	471562
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160246
UST Comprt ID:	471566
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160244
UST Comprt ID:	471564
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160245
UST Comprt ID:	471565
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160249
UST Comprt ID:	471561
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160247
UST Comprt ID:	471563
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160250
UST Comprt ID:	471560
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1977

VES SERVICE CENTER 5 (Continued) **U001542521**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	9550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	46937
Facility ID:	37550
Ai Number:	18146
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1977
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

VES SERVICE CENTER 5 (Continued) **U001542521**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	9550
UST Comprt ID:	259
UST ID:	46937
AI Number:	18146
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7022
Cert ID:	160248
UST Comprt ID:	471562
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A

VES SERVICE CENTER 5 (Continued) **U001542521**

Self Cert ID:	7022
Cert ID:	160246
UST Comprt ID:	471566
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160244
UST Comprt ID:	471564
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160245
UST Comprt ID:	471565
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160249
UST Comprt ID:	471561
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160247
UST Comprt ID:	471563
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7022
Cert ID:	160250
UST Comprt ID:	471560
UST ID:	154555
AI Number:	18146
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	37762
Facility ID:	37550
AI Number:	18146
Application Received Date:	02/11/2021
Scheduled Construction Date:	03/01/2021
UST Improvement:	N
UST Installation:	N

VES SERVICE CENTER 5 (Continued) **U001542521**

UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	02/11/2021
Signature Date On Form:	02/11/2021
Signature Name On Form:	RICK ROLLINS
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ MGR
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN;CITY OF AUSTIN
Owner CN At Time Of Construction:	CN600135198,CN600135198
Owner AR At Time Of Construction:	5A,5U
General Desc Of Prop Construct:	REMOVE AND REPLACE OVERSPILL BASIN AND OVERFILL DEVICE ON E-85 DIESEL AND UNLEADED TANKS

NOC ID:	34926
Facility ID:	37550
AI Number:	18146
Application Received Date:	06/26/2019
Scheduled Construction Date:	07/11/2019
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	02/11/2021
Signature Date On Form:	02/11/2021
Signature Name On Form:	RICK ROLLINS
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ MGR
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN;CITY OF AUSTIN
Owner CN At Time Of Construction:	CN600135198,CN600135198
Owner AR At Time Of Construction:	5A,5U
General Desc Of Prop Construct:	REPLACE TANK AND DISPENSER SUMPS, AS WELL AS THE FUEL LINES. ADD DEF TOTE AND LINES.

NOC ID:	90
Facility ID:	37550
AI Number:	18146
Application Received Date:	06/22/2011

VES SERVICE CENTER 5 (Continued) **U001542521**

Scheduled Construction Date:	06/22/2011
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	02/11/2021
Signature Date On Form:	02/11/2021
Signature Name On Form:	RICK ROLLINS
Signature Company On Form:	Not reported
Signature Title On Form:	PROJ MGR
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	5
General Desc Of Prop Construct:	INSTALLATION OF (1) NEW E85 DISPENSER AND NEW UL 971 DOUBLEWALL FLEXIBLE PIPING TO THE NEW DISPENSER. REQUEST WAIVER FOR 30 DAY NOTICE.*PER STELL ORTEGON WAI VER GRANTED*

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	82884
UST ID:	Not reported
NOC ID:	34926
AI Number:	18146
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	RICHARD ROLLINS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	89799
UST ID:	Not reported
NOC ID:	37762
AI Number:	18146
Type Of Contact:	CONTRACTOR

VES SERVICE CENTER 5 (Continued) **U001542521**

Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	108
UST ID:	Not reported
NOC ID:	90
AI Number:	18146
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	1113A REGAL ROW
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	82883
UST ID:	Not reported
NOC ID:	34926
AI Number:	18146
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported

VES SERVICE CENTER 5 (Continued) **U001542521**

Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	109
UST ID:	Not reported
NOC ID:	90
AI Number:	18146
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	89798
UST ID:	Not reported
NOC ID:	37762
AI Number:	18146
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	Not reported
Representative Name:	RICK ROLLINS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

VES SERVICE CENTER 5 (Continued) **U001542521**

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	4411 MEINARDUS DR STE D
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 1170
Phone Number/Ext:	512 9782649/0
Contact Fax Number/Ext:	512 9121524/0
Contact Email Address:	WILLIAM.OCONNOR@AUSTINTEXAS.GOV
Contact Address Deliverable:	Y
Facility ID:	37550
Additional ID:	936527342002246
Princ ID:	840354562001227
AI Number:	18146
Facility Name:	VES SERVICE CENTER 5
AR Number:	5
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	WILLIAM OCONNOR/

HIST UST AUSTIN:

Name:	COA SERVICE CENTER #5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	197
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AIRS:

Name:	CITY OF AUSTIN FLEET SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX
Permit Num:	94167
Regulated Id:	RN100625250
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	12/15/2010
Expiration Date:	12/31/3000
Customer Id:	CN600135198
Company Name:	CITY OF AUSTIN
Physical Location Desc:	714 E 8th St, Austin, TX
Rep Official(RO):	FLEET OFFICER
RO Name:	MR GERRY CALK
RO Delivery Address:	1190 HARGRAVE ST
RO City/State/Zip:	AUSTIN, T 78702-242
RO Phone:	512-453-3733
RO Ext Num:	0
RO EMail Address:	GERRY.CALK@CI.AUSTIN.TX.US
Lat Dec Coord Num:	30.324900
Long Dec Coord Num:	-97.772199

TX Financial Assurance 2:

Name:	VES SERVICE CENTER 5

VES SERVICE CENTER 5 (Continued) **U001542521**

Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	268740
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/31/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	250071
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/26/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/26/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	231293
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000

VES SERVICE CENTER 5 (Continued) **U001542521**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/25/2020
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/25/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	214215
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2019
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/15/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	197127
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/19/2018
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported

VES SERVICE CENTER 5 (Continued) **U001542521**

Coverage Amount:	1,000,000
Coverage Expiration Date:	07/19/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	179195
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/23/2017
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/23/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	162768
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2016
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	03/28/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2

VES SERVICE CENTER 5 (Continued) **U001542521**

Facility ID:	37550
Finass ID:	144994
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2015
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	127538
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2013
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	107293
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y

VES SERVICE CENTER 5 (Continued) **U001542521**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	Not reported
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	286
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	17411
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No

VES SERVICE CENTER 5 (Continued) **U001542521**

Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	17412
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/04/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	02/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	17413
AI:	18146
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LETTER OF CREDIT
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2008
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	1 213 4817841
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	06/06/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37550
Finass ID:	17414
AI:	18146

VES SERVICE CENTER 5 (Continued) **U001542521**

Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

COMP HIST:

RN Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
CN Rating:	3.38
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811111
SIC Code:	6512
Related Number:	67077,94167,18146,18146

CENTRAL REGISTRY:

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

VES SERVICE CENTER 5 (Continued) **U001542521**

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST

VES SERVICE CENTER 5 (Continued) **U001542521**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

Regulated Entity Number:	RN100625250
Name:	CITY OF AUSTIN SERVICE CENTER 5
Address:	714 E 8TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701-3305
Status:	ACTIVE

VES SERVICE CENTER 5 (Continued) **U001542521**

Status Date:	##########
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	5/8/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	811111
Primary NAICS Industry Type Description:	General Automotive Repair
Physical Location Description:	Not reported

RM2984 **CITY OF AUSTIN VES SERVICE CENTER 5** **TX ASBESTOS** **S103608273**
NE **714 E 8TH ST** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.179 mi.
945 ft. **Site 6 of 7 in cluster RM**

Actual:
471 ft.

Focus Map:
11

ASBESTOS:

Name:	APD - SERVICE CENTER #5
Address:	714 E 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/08/2018
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	08/09/2018
Notification Number:	2018005733
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/08/2018
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	APD - SERVICE CENTER #5
Address:	714 E 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/08/2018
Reason for Inspection:	Arthur D. Potts
Violation:	Not reported
Complaint Date:	08/11/2018
Notification Number:	2018005733
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/16/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/16/2018
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN POLICE DEPARTMENT - SERVICE CENTER #5
Address:	714 E. 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	05/06/2016
Notification Number:	2016003355
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/21/2016
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Name:	SERVICE CENTER #5
Address:	714 E. 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/10/2020
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	08/04/2020
Notification Number:	2020004730
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/29/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SERVICE CENTER #5
Address:	714 E. 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	08/10/2020
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	08/04/2020
Notification Number:	2020004730
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/20/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/04/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	APD - SERVICE CENTER #5
Address:	714 E 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/08/08
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/08/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018005733
File Number:	32989
License Status Description:	Paid
Expiration Date:	08/09/2018
Original Date:	07/16/2018
Rank Effective Date:	07/16/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	11518
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	SERVICE CENTER #5
Address:	714 E. 8TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/08/10
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Facility Type:	Notified
Inspector Name:	HARRIS, BRETT
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/10/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020004730
File Number:	53826
License Status Description:	Paid
Expiration Date:	08/04/2020
Original Date:	07/20/2020
Rank Effective Date:	07/20/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	bharris2
Inspection Number:	22751
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	CITY OF AUSTIN VES SERVICE CENTER 5
Address:	714 E 8TH ST
City,State,Zip:	AUSTIN, TX 78701
Permit Number:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Registration Number:	72378
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	09/20/2017
EPA Identification:	TXD981901515
Primary NAICS Code:	811111
Status Change Date:	19870501
Land Type:	MUNICIPAL
Description of Facility Site Location:	714 E 8th St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CITY OF AUSTIN
Contact Name:	WILL OCONNOR
Contact Telephone Number:	512-9273297
Mailing Address:	6400 BOLM RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787213639
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26819
Site Owner Tax ID:	746000085
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20170921
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CITY OF AUSTIN
Operator Address:	6301 HAROLD CT STE A
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78721
Operator Country:	UNITED STA
Operator Telephone:	1-512-9273260
Operator Fax Number:	Not reported
Operator Email:	Not reported

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Operator Business Type:	Not reported
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CITY OF AUSTIN
Owner Mailing Address:	6301 HAROLD CT STE A
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78721
Owner Country:	UNITED STA
Owner Telephone:	1-512-9273260
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Not reported
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6301 HAROLD CT STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78721
Contact Phone:	1-512-9273260
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6301 HAROLD CT STE A
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78721
Contact Phone:	1-512-9273260
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WILL OCONNOR
Contact Title:	OCC HLTH & SFTY SPECIALIS
Contact Role:	PRICONT
Contact Address:	6400 BOLMRD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78721
Contact Phone:	1-512-9273297
Contact Fax:	Not reported
Contact Email:	will.oconnor@ci.austin.tx.us

Ind. Haz Waste:

Waste ID:	155305
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Spent solvents/ used for parts degreasing/ Date of initial generation unknown.
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	155304
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solvent (spent)/ used for parts degreasing / Date of initial generation date unk
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Waste ID:	155303
Texas Waste Code:	Not reported
Texas Waste Code 2:	0839102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Aqueous waste with low other toxic organics. From brake cleaning. Initial gene
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	157661
Texas Waste Code:	Not reported
Texas Waste Code 2:	1269409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Parts cleaning, maintenance shop, (date unknown)
Standard Industrial Code:	75380
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811111
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	155302
Texas Waste Code:	Not reported
Texas Waste Code 2:	1331409H
Waste Code Status:	INACTIVE

CITY OF AUSTIN VES SERVICE CENTER 5 (Continued) **S103608273**

Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Other non-halogenated organic solids. Debris and floor sweep from cleaning of s
Standard Industrial Code:	75390
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811118
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6301 HAROLD CT
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78721
AR Number:	0000303629
Principal Name:	CITY OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6301 HAROLD CT
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78721
AR Number:	0000303629
Principal Name:	CITY OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	NWG

RV2985	**SHELL FOOD MART**	**TX UST**	**U003566411**
WNW	**4001 MEDICAL PKWY**	**TX HIST UST**	**N/A**
1/8-1/4	**AUSTIN, TX 78756**	**TX ASBESTOS**	
0.179 mi.		**TX Financial Assurance**	
947 ft.	**Site 1 of 2 in cluster RV**	**TX RDR**	

Actual:
633 ft.

Focus Map:
8

UST:

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 787563702
AI Number:	19601
Facility Type:	RETAIL
Facility Begin Date:	09/05/1986
Facility Status:	ACTIVE
Additional ID:	301700682002148
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/15/2020
Signature Name/Title On Earliest Reg Form:	GUY OLIVER,AUTH REP
Application Received Date On Earliest Reg Form:	03/16/2020
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	264324162020029
Additional ID:	301700682002148
Ai Number:	19601
Operator CN:	CN605745975
Operator Name:	GOZIG HOLDINGS LLC
Operator Effective Begin Date:	01/01/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

SHELL FOOD MART (Continued) **U003566411**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601235310
Owner Last Name:	38 1 2 STREET LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	194656322002148
Additional ID:	301700682002148
AI Number:	19601
Owner Effective Begin Date:	08/08/2012
State Tax ID:	17426811067
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	56665
Cert ID:	380228
AI Number:	19601
Self Certification Date:	12/08/2022
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	363206
AI Number:	19601
Self Certification Date:	12/14/2021

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	349194
AI Number:	19601
Self Certification Date:	02/02/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	334572
AI Number:	19601
Self Certification Date:	01/16/2020
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	332216
AI Number:	19601
Self Certification Date:	01/15/2020

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	313468
AI Number:	19601
Self Certification Date:	01/07/2019
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	298382
AI Number:	19601
Self Certification Date:	01/25/2018
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	280399
AI Number:	19601
Self Certification Date:	01/11/2017

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	263263
AI Number:	19601
Self Certification Date:	01/15/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	245545
AI Number:	19601
Self Certification Date:	12/08/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	228426
AI Number:	19601
Self Certification Date:	12/11/2013

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	56665
Cert ID:	55387
AI Number:	19601
Self Certification Date:	12/17/2012
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55386
AI Number:	19601
Self Certification Date:	12/13/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55385
AI Number:	19601
Self Certification Date:	01/07/2011

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56665
Cert ID:	55384
AI Number:	19601
Self Certification Date:	01/26/2010
Signature Name/Title:	GUY OLIVER OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56665
Cert ID:	55383
AI Number:	19601
Self Certification Date:	12/15/2008
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	56665
Cert ID:	55382
AI Number:	19601
Self Certification Date:	12/18/2007

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	GUY OLIVER AUTHO REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55381
AI Number:	19601
Self Certification Date:	01/02/2007
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55380
AI Number:	19601
Self Certification Date:	12/02/2005
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55379
AI Number:	19601
Self Certification Date:	12/02/2004

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55378
AI Number:	19601
Self Certification Date:	01/07/2004
Signature Name/Title:	GUY N OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55377
AI Number:	19601
Self Certification Date:	12/23/2002
Signature Name/Title:	GUY OLIVER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55376
AI Number:	19601
Self Certification Date:	01/07/2002

SHELL FOOD MART (Continued) **U003566411**

Signature Name/Title:	GUY OLIVER AUTHORIZED REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	56665
Cert ID:	55375
AI Number:	19601
Self Certification Date:	02/01/2001
Signature Name/Title:	GUY OLIVER REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50401
Facility ID:	56665
Ai Number:	19601
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

SHELL FOOD MART (Continued) **U003566411**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	61741
UST ID:	50401
AI Number:	19601
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

SHELL FOOD MART (Continued) **U003566411**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	172949
Facility ID:	56665
Ai Number:	19601
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

SHELL FOOD MART (Continued) **U003566411**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	61742
UST ID:	172949
AI Number:	19601
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N

SHELL FOOD MART (Continued) **U003566411**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50400
Facility ID:	56665
Ai Number:	19601
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

SHELL FOOD MART (Continued) **U003566411**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	61740
UST ID:	50400
AI Number:	19601
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

SHELL FOOD MART (Continued) **U003566411**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50399
Facility ID:	56665
Ai Number:	19601
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

SHELL FOOD MART (Continued) **U003566411**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	61739
UST ID:	50399
AI Number:	19601
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE

SHELL FOOD MART (Continued) **U003566411**

Stage 1 Installation Date: Not reported

Construction Notification:

NOC ID:	36264
Facility ID:	56665
AI Number:	19601
Application Received Date:	03/26/2020
Scheduled Construction Date:	04/01/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	03/26/2020
Signature Date On Form:	03/26/2020
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	38 1 2 STREET LC
Owner CN At Time Of Construction:	CN601235310
Owner AR At Time Of Construction:	45881
General Desc Of Prop Construct:	EXCAVATE THE SYPHON LINE ON TANK #2 AND INSTALL NEW FITTINGS AND BALL VALVE

NOC ID:	5274
Facility ID:	56665
AI Number:	19601
Application Received Date:	06/12/2006
Scheduled Construction Date:	07/05/2006
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M60612009
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	03/26/2020
Signature Date On Form:	03/26/2020
Signature Name On Form:	CHUCK NADEAU
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported

SHELL FOOD MART (Continued) **U003566411**

Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	45881
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	85940
UST ID:	Not reported
NOC ID:	36264
AI Number:	19601
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C & J PETROLEUM
Representative Name:	CHUCK NADEAU
Mailing Address (Delivery):	PO BO 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPE
Mailing State:	TX
Mailing Zip:	76503
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	5767
UST ID:	Not reported
NOC ID:	5274
AI Number:	19601
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000005
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	85939
UST ID:	Not reported

SHELL FOOD MART (Continued) **U003566411**

NOC ID:	36264
AI Number:	19601
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001755
Company Name:	NADEAU CHUCK
Representative Name:	Not reported
Mailing Address (Delivery):	150 PR 810
Mailing Address (Internal Delivery):	Not reported
Mailing City:	LOTT
Mailing State:	TX
Mailing Zip:	76656
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	254
Phone Number:	7705454
Phone Number Extension:	0
Fax Number Country Code:	0
Fax Number Area Code:	888
Fax Number:	5631656
Email Address:	chuck@cjpetro.com

Facility Billing Contacts:

Contact Organization Name:	38 1 2 STREET LC
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	56665
Additional ID:	301700682002148
Princ ID:	194656322002148
AI Number:	19601
Facility Name:	SHELL FOOD MART
AR Number:	45881
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX
Id UST:	909
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	NEW DEV'S SHELL
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756

SHELL FOOD MART (Continued) **U003566411**

Date of inspection:	05/21/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	05/28/2013
Date Routed by Supervisor:	05/28/2013
Date Routed to PSQA:	06/04/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

SHELL FOOD MART (Continued) **U003566411**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	NEW DEV'S SHELL
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/04/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/10/2014
Date Routed by Supervisor:	06/10/2014
Date Routed to PSQA:	06/10/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

SHELL FOOD MART (Continued) **U003566411**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	277382
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2022
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 800 3066963
Policy Number:	04-TOP-000034751
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	260666
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SHELL FOOD MART (Continued) **U003566411**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000024781
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	243820
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	227179
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

SHELL FOOD MART (Continued) **U003566411**

Policy Number:	04TOP00006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	205939
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/28/2018
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/28/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	189664
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756

SHELL FOOD MART (Continued) **U003566411**

Region:	2
Facility ID:	56665
Finass ID:	173694
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	188382
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	155444
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

SHELL FOOD MART (Continued) **U003566411**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	153777
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	136180
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014

SHELL FOOD MART (Continued) **U003566411**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	117899
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	3604
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37303

SHELL FOOD MART (Continued) **U003566411**

AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37304
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37305
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010

SHELL FOOD MART (Continued) **U003566411**

Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37306
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37307
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SHELL FOOD MART (Continued) **U003566411**

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37308
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 817 2329000
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37309
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 817 2329000
Policy Number:	04TO66839
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Region:	2
Facility ID:	56665
Finass ID:	37310
AI:	19601
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SHELL FOOD MART (Continued) **U003566411**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/16/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	24927
Facility ID:	19601
RN:	Not reported
CN:	Not reported
Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/22/2017
Due Date:	1/21/2018
Tank Owner:	381/2 STREET LLC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	1/19/2018
Project Manager:	Meagan Kunze-Nevarez
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	ORG RDR REC 9/18/17; DEF LTR ISSUED 11/9/17; RESP DUE 1/8/18; NOD-RESP REC 11/22/17; RDR-SIR LTR ISSUED 1/19/18
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	20517
Facility ID:	19601
RN:	Not reported
CN:	Not reported
Name:	SHELL FOOD MART
Address:	4001 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/5/2012
Due Date:	8/4/2012
Tank Owner:	38 1/2 STREET LC
Contact Person:	GUY OLIVER
Report:	RDR

SHELL FOOD MART (Continued) **U003566411**

Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SIR ltr 7/25/12
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

2986 WNW 1/8-1/4 0.179 mi. 947 ft. **K & M SUPPLY** **TX HIST UST** **S128729544**
908 MC PHAUL ST **N/A**
AUSTIN, TX

Actual: 730 ft.
Focus Map: 3

HIST UST AUSTIN:

Name:	K & M SUPPLY
Address:	908 MC PHAUL ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0136
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RW2987 NNW 1/8-1/4 0.180 mi. 949 ft. **TERMINIX COMPANY** **TX HIST UST** **S111678816**
4326 N LAMAR BLVD **N/A**
AUSTIN, TX

Site 1 of 2 in cluster RW

Actual: 640 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	TERMINIX COMPANY
Address:	4326 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0537
HID UST:	537
Inspection:	Not reported
Due:	06/01/2012

RN2988 **KO MACHINE** **RCRA NonGen / NLR** **1000891221**
ESE **620 CANION ST** **FINDS** **TX0000141424**
1/8-1/4 **AUSTIN, TX 78752** **ECHO**
0.180 mi. **TX Ind. Haz Waste**
952 ft. **Site 2 of 2 in cluster RN**

Actual:
703 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20020726
Handler Name:	Ko Machine
Handler Address:	CANION ST
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TX0000141424
Contact Name:	DARIN HINKLE
Contact Address:	WOOTEN DR
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Telephone:	512-454-5602
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	WOOTEN DR
Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Name:	Kowalczykcarl
Owner Type:	Private
Operator Name:	Kowalczykcarl
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

KO MACHINE (Continued) **1000891221**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: KOWALCZYKCARL	
Legal Status:	Private
Date Became Current:	20020726
Date Ended Current:	Not reported
Owner/Operator Address:	2006 WOOTEN DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: KOWALCZYKCARL	
Legal Status:	Private
Date Became Current:	20020726
Date Ended Current:	Not reported
Owner/Operator Address:	2006 WOOTEN DR
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

KO MACHINE (Continued) **1000891221**

Owner/Operator Name: CARL KOWALCZYK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 620 CANION
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-454-5602
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19940309
Handler Name: KO MACHINE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020726
Handler Name: KO MACHINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 336311
NAICS Description: CARBURETOR, PISTON, PISTON RING, AND VALVE MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005014224

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

KO MACHINE (Continued) **1000891221**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000891221
Registry ID:	110005014224
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005014224
Name:	KO MACHINE
Address:	620 CANION ST
City,State,Zip:	AUSTIN, TX 78752

Ind. Haz Waste:

Name:	KO MACHINE
Address:	620 CANION ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	82064
Registration Initial Notification Date:	05/24/1994
Registration Last Amendment Date:	07/26/2002
EPA Identification:	TX0000141424
Primary NAICS Code:	336311
Status Change Date:	19940524
Land Type:	PRIVATE
Description of Facility Site Location:	620 Canion St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	KOWALCZYK, CARL
Contact Name:	DARIN HINKLE
Contact Telephone Number:	512-4545602
Mailing Address:	2006 WOOTEN DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787577704
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	37189
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020730

KO MACHINE (Continued) **1000891221**

Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CARL KOWALCZYK
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Operator Name:	CARL KOWALCZYK
Operator Address:	Not reported
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	Not reported
Operator Country:	Not reported
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CARL KOWALCZYK
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Owner Name:	CARL KOWALCZYK
Owner Mailing Address:	Not reported

KO MACHINE (Continued) **1000891221**

Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	DARIN HINKLE
Contact Title:	SERVICE MANAGER
Contact Role:	PRICONT
Contact Address:	2006 WOOTEN DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4545602
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	94364
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Waste petroleum naptha Circulating parts washer 1/11/94
Standard Industrial Code:	35920
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	336311
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

RX2989 **SOUTHLAND REDDY ICE** **TX LPST** **S107747624**
NE **901 RED RIVER ST** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.181 mi.
956 ft. **Site 1 of 4 in cluster RX**

Actual:
482 ft.

Focus Map:
11

LPST:

Name:	SOUTHLAND REDDY ICE
Address:	901 RED RIVER ST
City,State,Zip:	AUSTIN, TX 78702
Facility ID:	0024217
LPST Id:	092275
Facility Location:	901 RED RIVER
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/12/1988
Entered Date:	11/04/1988
Reported Date:	09/12/1988
Closure Date:	03/25/1998
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/2
Coordinators RPR:	VYF
Responsible Party Name:	Not reported
Responsible Party Contact:	PATRICIA LAMBERT
Responsible Party Address:	PO BOX 711
Responsible Party City,St,Zip:	DALLAS, TX 75221 0711
Responsible Party Telephone:	972/341-8300
Reported Date:	09/12/1988
Case Start Date:	03/25/1998
Reference Number:	RN102056074
Project Manager:	VYF

RX2990 **REDDY ICE** **TX UST** **U003566287**
NE **901 RED RIVER ST** **TX SPILLS** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.181 mi.
956 ft. **Site 2 of 4 in cluster RX**

Actual:
482 ft.

Focus Map:
11

UST:

Name:	REDDY ICE
Address:	901 RED RIVER ST
City,State,Zip:	AUSTIN, TX 787012699
AI Number:	24217
Facility Type:	FLEET REFUELING
Facility Begin Date:	10/01/1986
Facility Status:	INACTIVE
Additional ID:	873376262002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

REDDY ICE (Continued) **U003566287**

Site Location (Location Zip):	78701
Contact Name/Title:	H BENAVIDES,ROUTE SUPV
Contact Organization Name:	REDDY ICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124823151
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/01/1986
Signature Name/Title On Earliest Reg Form:	R SMITH,PROJECT MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	873376262002118
AI Number:	24217
Owner Effective Begin Date:	11/20/2000
State Tax ID:	17510851318
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1968
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	62222
Facility ID:	60317
Ai Number:	24217
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND

REDDY ICE (Continued) **U003566287**

Tank Status Date:	06/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	57957
UST ID:	62222
AI Number:	24217
Compartment ID:	A

REDDY ICE (Continued) **U003566287**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	62221
Facility ID:	60317
Ai Number:	24217
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

REDDY ICE (Continued) **U003566287**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/27/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	57956
UST ID:	62221
AI Number:	24217
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

REDDY ICE (Continued) **U003566287**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	60317
Additional ID:	873376262002118
Princ ID:	959578622001257
AI Number:	24217
Facility Name:	REDDY ICE
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

SPILLS:

Name:	CRYSTAL FALLS GOLF COURSE 3400 CRYSTAL FALLS PARKWAY, LEANDER
Address:	CRYSTAL FALLS GOLF COURSE 3400 CRYSTAL FALLS PARKWAY, LEANDER
City,State,Zip:	LEANDER, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	07/28/1993

REDDY ICE (Continued) **U003566287**

Seq Num:	Not reported
Responsible Party Name:	SOUTHERN ICE COMPANY
Responsible Party Address:	901 RED RIVER
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	78767
Responsible Party Telephone:	5124777089
Substance:	DIESEL
Material Code:	9000
Media Affected:	Not reported
Permit Number:	NONE
District:	11
Origin:	005
Cause:	002
Basin Code:	1250
Notify Date:	Not reported
Adequate Clean:	001
Classification:	006
Basin Name:	BRAZOS
Water Affected:	NONE
Amnt Spilled:	25 GAL
Amnt in Water:	NONE GAL
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	TWC
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	C. SMITH
Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

RO2991 ENE 1/8-1/4 0.185 mi. 975 ft. — **AUTOMOTIVE RECYCLING CENTER**, **1125 BASTROP HWY**, **AUSTIN, TX** — **TX HIST UST** — **S128729066** / **N/A**

Site 7 of 7 in cluster RO

Actual: 472 ft.
Focus Map: 16

HIST UST AUSTIN:

Name:	AUTOMOTIVE RECYCLING CENTER
Address:	1125 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	C0517
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RY2992 East 1/8-1/4 0.185 mi. 976 ft. — **OLD TOWNSENDS TEXACO**, **2511 SAN JACINTO**, **AUSTIN, TX 78705** — **TX LPST** — **S103930331** / **N/A**

Site 1 of 2 in cluster RY

Actual: 521 ft.
Focus Map: 11

LPST:

Name:	OLD TOWNSENDS TEXACO
Address:	2511 SAN JACINTO
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	Not reported
LPST Id:	106331
Facility Location:	2511 SAN JACINTO
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/19/1990
Entered Date:	04/19/1993
Reported Date:	11/20/1990
Closure Date:	10/16/1998
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	PWW
Responsible Party Name:	Not reported
Responsible Party Contact:	RUSTY OSBORNE
Responsible Party Address:	PO BOX 7580
Responsible Party City,St,Zip:	AUSTIN, TX 78713 7580
Responsible Party Telephone:	512/471-5050
Reported Date:	11/20/1990
Case Start Date:	10/16/1998
Reference Number:	RN106982275
Project Manager:	PWINSOR

RY2993 East 1/8-1/4 0.185 mi. 976 ft. — **OLD TOWNSENDS TEXACO**, **2511 SAN JACINTO BLVD**, **AUSTIN, TX** — **TX HIST UST** — **S128729553** / **N/A**

Site 2 of 2 in cluster RY

Actual: 521 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	OLD TOWNSENDS TEXACO
Address:	2511 SAN JACINTO BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0159
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RX2994 NE 1/8-1/4 0.185 mi. 978 ft. — **OAK FARMS DAIRY**, **611 E 9TH ST**, **AUSTIN, TX** — **TX HIST UST** — **S111678762** / **N/A**

Site 3 of 4 in cluster RX

Actual: 476 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	OAK FARMS DAIRY
Address:	611 E 9TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0563
HID UST:	563
Inspection:	Not reported
Due:	06/01/2012

RZ2995 ESE 1/8-1/4 0.188 mi. 994 ft. — **RAVEN INDUSTRIES INC**, **AUSTIN, TX** — **PFAS ECHO** — **1027411026** / **N/A**

Site 1 of 3 in cluster RZ

Actual: 741 ft.
Focus Map: 2

PFAS ECHO:

Name:	RAVEN INDUSTRIES INC
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.41452
Longitude:	-97.66453
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Electronics Industry
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110014439900
Facility Percent Minority:	60.173
Facility Derived Tribes:	-
Facility Population:	3434.85
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N

RAVEN INDUSTRIES INC (Continued) **1027411026**

Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050307
Facility Derived CD113:	17
Facility Derived CB2010:	484530018391007
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TXR000052944
RCRA Permit Types:	Other
RCRA NAICS:	334419
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.66453,%22y%22:30.41452,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

RW2996 NNW 1/8-1/4 0.189 mi. 1000 ft. | **CENTRAL TEX. REG. BLOOD CENTER**
4300 N LAMAR BLVD
AUSTIN, TX

Site 2 of 2 in cluster RW

TX HIST UST | **S128729094**
N/A

Actual: 640 ft.
Focus Map: 8

HIST UST AUSTIN:

Name:	CENTRAL TEX. REG. BLOOD CENTER
Address:	4300 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0633
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SA2997 ESE 1/8-1/4 0.191 mi. 1010 ft. | **TCI COATINGS INC**
220 INDUSTRIAL BLVD
AUSTIN, TX 78745

Site 1 of 4 in cluster SA

RCRA NonGen / NLR | **1000243094**
TXD030927057

Actual: 668 ft.
Focus Map: 18

RCRA Listings:

Date Form Received by Agency:	20021104
Handler Name:	Tci Coatings Inc
Handler Address:	INDUSTRIAL BLVD
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD030927057
Contact Name:	KATHLEEN H TIMS
Contact Address:	INDUSTRIAL BLVD
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Telephone:	512-442-1488
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	INDUSTRIAL BLVD
Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Name:	Tci Coatings Inc
Owner Type:	Not reported
Operator Name:	Tci Coatings Inc
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

TCI COATINGS INC (Continued) **1000243094**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D011
Waste Description:	Silver
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

TCI COATINGS INC (Continued) **1000243094**

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F017
Waste Description: Not Defined

Waste Code: K046
Waste Description: Wastewater Treatment Sludges From The Manufacturing, Formulation, And Loading Of Lead-Based Initiating Compounds.

Waste Code: K078
Waste Description: Not Defined

Waste Code: K079
Waste Description: Not Defined

Waste Code: P092
Waste Description: Mercury, (Acetato-O)Phenyl- (Or) Phenylmercury Acetate

TCI COATINGS INC (Continued) **1000243094**

Waste Code: P100
Waste Description: Not Defined

Waste Code: U013
Waste Description: Not Defined

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U069
Waste Description: 1,2-Benzenedicarboxylic Acid, Dibutyl Ester (Or) Dibutyl Phthalate

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U238
Waste Description: Carbamic Acid, Ethyl Ester (Or) Ethyl Carbamate (Urethane)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TCI COATINGS INC
Legal Status: Not reported
Date Became Current: 20021104
Date Ended Current: Not reported
Owner/Operator Address: 220 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-442-1488
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TECHNICAL COATINGS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 312 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-442-1488
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

TCI COATINGS INC (Continued) **1000243094**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TECHNICAL COATINGS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 312 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-442-1488
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TCI COATINGS INC
Legal Status: Not reported
Date Became Current: 20021104
Date Ended Current: Not reported
Owner/Operator Address: 220 INDUSTRIAL BLVD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-442-1488
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800818
Handler Name: TECHNICAL COATINGS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20021104
Handler Name: TCI COATINGS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32551
NAICS Description: PAINT AND COATING MANUFACTURING

TCI COATINGS INC (Continued) **1000243094**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SA2998 **TECHNICAL COATINGS** **TX UST** **U001250085**
ESE **220 INDUSTRIAL BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.191 mi.
1010 ft. **Site 2 of 4 in cluster SA**

Actual:
668 ft.

Focus Map:
18

UST:

Name:	TECHNICAL COATINGS
Address:	220 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 787451257
AI Number:	14685
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	08/13/1986
Facility Status:	INACTIVE
Additional ID:	430822092002068
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	KATHLEEN TIMS,
Contact Organization Name:	TECHNICAL COATINGS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124421488
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1986
Signature Name/Title On Earliest Reg Form:	JOHN SCHOEDEL,GEN MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600295141
Owner Last Name:	TCI COATINGS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported

TECHNICAL COATINGS (Continued) **U001250085**

Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	598385362001297
Additional ID:	430822092002068
AI Number:	14685
Owner Effective Begin Date:	08/13/1986
State Tax ID:	17526301647
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37719
Facility ID:	53343
Ai Number:	14685
Tank Id:	11
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

TECHNICAL COATINGS (Continued) **U001250085**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	11
Tank Capacity:	4000
UST Comprt ID:	43067
UST ID:	37719
AI Number:	14685
Compartment ID:	A
Substance Stored1:	XYLOL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

TECHNICAL COATINGS (Continued) **U001250085**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37720
Facility ID:	53343
Ai Number:	14685
Tank Id:	10
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

TECHNICAL COATINGS (Continued) **U001250085**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	10
Tank Capacity:	10000
UST Comprt ID:	43068
UST ID:	37720
AI Number:	14685
Compartment ID:	A
Substance Stored1:	MINERAL SPIRITS
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TECHNICAL COATINGS (Continued) **U001250085**

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37721
Facility ID:	53343
Ai Number:	14685
Tank Id:	9B
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

TECHNICAL COATINGS (Continued) **U001250085**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	9B
Tank Capacity:	4000
UST Comprt ID:	43069
UST ID:	37721
AI Number:	14685
Compartment ID:	A
Substance Stored1:	XYLOL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37722

TECHNICAL COATINGS (Continued) **U001250085**

Facility ID:	53343
Ai Number:	14685
Tank Id:	9A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	9A
Tank Capacity:	10000

TECHNICAL COATINGS (Continued) **U001250085**

UST Comprt ID:	43070
UST ID:	37722
AI Number:	14685
Compartment ID:	A
Substance Stored1:	MINERAL SPIRITS
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37723
Facility ID:	53343
Ai Number:	14685
Tank Id:	12
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

TECHNICAL COATINGS (Continued) **U001250085**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	12
Tank Capacity:	2000
UST Comprt ID:	43071
UST ID:	37723
AI Number:	14685
Compartment ID:	A
Substance Stored1:	TOLUOL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

TECHNICAL COATINGS (Continued) **U001250085**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	37729
Facility ID:	53343
Ai Number:	14685
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

TECHNICAL COATINGS (Continued) **U001250085**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	43077
UST ID:	37729
AI Number:	14685
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

TECHNICAL COATINGS (Continued) **U001250085**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37725
Facility ID:	53343
Ai Number:	14685
Tank Id:	13
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

TECHNICAL COATINGS (Continued) **U001250085**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	13
Tank Capacity:	2000
UST Comprt ID:	43073
UST ID:	37725
AI Number:	14685
Compartment ID:	A
Substance Stored1:	NAPHTHA
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

TECHNICAL COATINGS (Continued) **U001250085**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	37726
Facility ID:	53343
Ai Number:	14685
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

TECHNICAL COATINGS (Continued) **U001250085**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	43074
UST ID:	37726
AI Number:	14685
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

TECHNICAL COATINGS (Continued) **U001250085**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	37727
Facility ID:	53343
Ai Number:	14685
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

TECHNICAL COATINGS (Continued) **U001250085**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	2000
UST Comprt ID:	43075
UST ID:	37727
AI Number:	14685
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

TECHNICAL COATINGS (Continued) **U001250085**

Install Date:	02/01/1988
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	S
UST ID:	37728
Facility ID:	53343
Ai Number:	14685
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

TECHNICAL COATINGS (Continued) **U001250085**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	43076
UST ID:	37728
AI Number:	14685
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37724

TECHNICAL COATINGS (Continued) **U001250085**

Facility ID:	53343
Ai Number:	14685
Tank Id:	14
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/28/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	14
Tank Capacity:	2000

TECHNICAL COATINGS (Continued) **U001250085**

UST Comprt ID:	43072
UST ID:	37724
AI Number:	14685
Compartment ID:	A
Substance Stored1:	NAPHTHA
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	3884
Facility ID:	53343
AI Number:	14685
Application Received Date:	02/07/2005
Scheduled Construction Date:	03/09/2005
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N

TECHNICAL COATINGS (Continued) **U001250085**

Historical Tracking Number:	M50207003
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	7110
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	4256
UST ID:	Not reported
NOC ID:	3884
AI Number:	14685
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TCI COATINGS INC
Contact Mailing Address (Delivery):	220 INDUSTRIAL BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 1257
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	53343
Additional ID:	430822092002068
Princ ID:	598385362001297
AI Number:	14685
Facility Name:	TECHNICAL COATINGS
AR Number:	7110
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U

TECHNICAL COATINGS (Continued) **U001250085**

Contact Name/Title: KATHLEEN TIMS/

SA2999 **TCI COATINGS** **TX Ind. Haz Waste** **S102740869**
ESE **220 INDUSTRIAL BLVD** **TX RDR** **N/A**
1/8-1/4 **AUSTIN, TX 78745** **TX CENTRAL REGISTRY**
0.191 mi.
1010 ft. **Site 3 of 4 in cluster SA**

Actual:
668 ft.

Focus Map:
18

Ind. Haz Waste:

Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	33277
Registration Initial Notification Date:	11/30/1983
Registration Last Amendment Date:	11/04/2002
EPA Identification:	TXD030927057
Primary NAICS Code:	325510
Status Change Date:	19831130
Land Type:	Not reported
Description of Facility Site Location:	220 Industrial Blvd, Austin, Texas 78745
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	LQG
Type of Generator:	INDUS
Company Name:	TCI COATINGS INC
Contact Name:	KATHLEEN H TIMS
Contact Telephone Number:	512-4421488
Mailing Address:	220 INDUSTRIAL BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787451257
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	10783
Site Owner Tax ID:	752630164
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021212
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported

TCI COATINGS (Continued) **S102740869**

Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TCI COATINGS INC
Operator Address:	220 INDUSTRIAL BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4421488
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17526301647
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TCI COATINGS INC
Owner Mailing Address:	220 INDUSTRIAL BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4421488
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17526301647
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	15
Unit Status:	INACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported

TCI COATINGS (Continued) **S102740869**

System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	WASTE RECOVERY - LIVE STEAM DISTILLATION
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19831001
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19860401
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported

TCI COATINGS (Continued) **S102740869**

Deed Recording Date:	Not reported
Unit Number:	004
Unit Type Code:	18
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19850601
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	005
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	006
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported

TCI COATINGS (Continued) **S102740869**

Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	220 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4421488
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	220 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4421488
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	KATHLEEN TIMS
Contact Title:	PRESIDENT
Contact Role:	PRICONT
Contact Address:	220 INDUSTRIAL BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4421488
Contact Fax:	Not reported
Contact Email:	Not reported

RDR:

TCI COATINGS (Continued) **S102740869**

RDR ID:	14645
Facility ID:	14685
RN:	Not reported
CN:	Not reported
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/22/2005
Due Date:	9/20/2005
Tank Owner:	TCI COATINGS INC
Contact Person:	KATHLEEN TIMS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	9/1/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/1/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.

TCI COATINGS (Continued) **S102740869**

Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31

TCI COATINGS (Continued) **S102740869**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing

TCI COATINGS (Continued) **S102740869**

Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

Regulated Entity Number:	RN100584994
Name:	TCI COATINGS
Address:	220 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1257
Status:	ACTIVE
Status Date:	1800-01-01
Customer Number:	CN600295141
Customer Name:	TCI COATINGS INC
Customer Legal Name:	TCI Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	Not reported

TCI COATINGS (Continued) **S102740869**

Click this hyperlink while viewing on your computer to access
1 additional TX CENTRAL REG: record(s) in the EDR Site Report.

RS3000 **JIM TENNISON ONE STOP** **TX HIST UST** **S128729039**
ENE **701 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.192 mi.
1015 ft. **Site 4 of 9 in cluster RS**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	JIM TENNISON ONE STOP
Address:	701 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0458
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RS3001 **7-ELEVEN #36643** **TX HIST UST** **S128728670**
ENE **701 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.192 mi.
1015 ft. **Site 5 of 9 in cluster RS**

Actual:
487 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	7-ELEVEN #36643
Address:	701 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	3175
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RZ3002 **AUSTIN TECHNOLOGY CENTER** **TX Ind. Haz Waste** **S105837712**
ESE **500 CENTER RIDGE DR STE 600** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.192 mi.
1016 ft. **Site 2 of 3 in cluster RZ**

Actual:
740 ft.

Focus Map:
2

Ind. Haz Waste:

Name:	AUSTIN TECHNOLOGY CENTER
Address:	500 CENTER RIDGE DR STE 600
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	87221
Registration Initial Notification Date:	03/25/2003
Registration Last Amendment Date:	12/29/2006
EPA Identification:	TXR000052944
Primary NAICS Code:	334419
Status Change Date:	20030325
Land Type:	PRIVATE
Description of Facility Site Location:	500 Center Ridge Dr, Ste 600, Austin, TX
Site Primary Standard Industrial Code:	Not reported

AUSTIN TECHNOLOGY CENTER (Continued) **S105837712**

Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	INDUS
Company Name:	RAVEN INDUSTRIES INC
Contact Name:	HUGH DODSON
Contact Telephone Number:	Not reported
Mailing Address:	PO BOX 5107
Mailing Address2:	Not reported
Mailing City,State,Zip:	SIOUX FALLS, SD 571175107
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	116167
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20070307
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	RAVEN INDUSTRIES INC
Operator Address:	PO BOX 5107
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	SIOUX FALLS, SD 57117
Operator Country:	UNITED STA
Operator Telephone:	1-605-3362750
Operator Fax Number:	1-605-3310419
Operator Email:	kurt.doeden@ravenind.com
Operator Business Type:	Corporation
Operator Tax ID:	14602461718
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	RAVEN INDUSTRIES INC
Owner Mailing Address:	PO BOX 5107
Owner Mailing Address 2:	Not reported

AUSTIN TECHNOLOGY CENTER (Continued) **S105837712**

Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	SIOUX FALLS, SD 57117
Owner Country:	UNITED STA
Owner Telephone:	1-605-3362750
Owner Fax:	1-605-3310419
Owner Email Address:	kurt.doeden@ravenind.com
Owner Business Type:	Corporation
Owner Tax ID:	14602461718
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 5107
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SIOUX FALLS, SD 57117
Contact Phone:	1-605-3362750
Contact Fax:	1-605-3310419
Contact Email:	kurt.doeden@ravenind.com

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 5107
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SIOUX FALLS, SD 57117
Contact Phone:	1-605-3362750
Contact Fax:	1-605-3310419
Contact Email:	kurt.doeden@ravenind.com

Contact Name:	HUGH DODSON
Contact Title:	FACILITY MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 5107
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	SIOUX FALLS, SD 57117
Contact Phone:	Not reported
Contact Fax:	1-605-3310419
Contact Email:	Kurt.Doeden@RavenInd.com

Ind. Haz Waste:

Waste ID:	199327
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001307H
Waste Code Status:	INACTIVE
Waste Form:	307
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Tin and lead waste from soldering process. Electronic circuit boards. 1/1/03
Standard Industrial Code:	36790

AUSTIN TECHNOLOGY CENTER (Continued) **S105837712**

Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	334310
EPA Waste Form Code:	W307
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

RZ3003 **QUANTUM CLEAN** **RCRA NonGen / NLR** **1006811770**
ESE **500 CENTER RIDGE DR** **FINDS** **TXR000052944**
1/8-1/4 **AUSTIN, TX 78753** **ECHO**
0.192 mi.
1016 ft. **Site 3 of 3 in cluster RZ**

Actual:
740 ft.

Focus Map:
2

RCRA Listings:

Date Form Received by Agency:	20070307
Handler Name:	Raven Industries Inc
Handler Address:	CENTER RIDGE DR STE 600
Handler City,State,Zip:	AUSTIN, TX 78753
EPA ID:	TXR000052944
Contact Name:	HUGH DODSON
Contact Address:	PO BOX 5107
Contact City,State,Zip:	SIOUX FALLS, SD 57117
Contact Telephone:	605-336-2750 1
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 5107
Mailing City,State,Zip:	SIOUX FALLS, SD 57117
Owner Name:	Raven Industries Inc
Owner Type:	Private
Operator Name:	Raven Industries Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

QUANTUM CLEAN (Continued) **1006811770**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20070326
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20040121
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5107
Owner/Operator City,State,Zip:	SIOUX FALLS, SD 57117
Owner/Operator Telephone:	605-336-2750
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20060118

QUANTUM CLEAN (Continued) **1006811770**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5107
Owner/Operator City,State,Zip:	SIOUX FALLS, SD 57117
Owner/Operator Telephone:	605-336-2750
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20011228
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20061229
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5107
Owner/Operator City,State,Zip:	SIOUX FALLS, SD 57117
Owner/Operator Telephone:	605-336-2750
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20040121
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5107
Owner/Operator City,State,Zip:	SIOUX FALLS, SD 57117
Owner/Operator Telephone:	605-336-2750
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RAVEN INDUSTRIES INC	
Legal Status:	Private
Date Became Current:	20060118
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 5107
Owner/Operator City,State,Zip:	SIOUX FALLS, SD 57117
Owner/Operator Telephone:	605-336-2750
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

QUANTUM CLEAN (Continued) **1006811770**

Owner/Operator Name: RAVEN INDUSTRIES INC
Legal Status: Private
Date Became Current: 20060118
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5107
Owner/Operator City,State,Zip: SIOUX FALLS, SD 57117
Owner/Operator Telephone: 605-336-2750
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RAVEN INDUSTRIES INC
Legal Status: Private
Date Became Current: 20060118
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5107
Owner/Operator City,State,Zip: SIOUX FALLS, SD 57117
Owner/Operator Telephone: 605-336-2750
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: AMB TR THREE 2000 LTD
Legal Status: Private
Date Became Current: 20001207
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RAVEN INDUSTRIES INC
Legal Status: Private
Date Became Current: 20061229
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 5107
Owner/Operator City,State,Zip: SIOUX FALLS, SD 57117
Owner/Operator Telephone: 605-336-2750
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20030421
Handler Name: RAVEN INDUSTRIES INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

QUANTUM CLEAN (Continued) **1006811770**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040121
Handler Name: RAVEN INDUSTRIES INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060118
Handler Name: RAVEN INDUSTRIES INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070228
Handler Name: RAVEN INDUSTRIES INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070307
Handler Name: RAVEN INDUSTRIES INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

QUANTUM CLEAN (Continued) **1006811770**

List of NAICS Codes and Descriptions:
NAICS Code: 334419
NAICS Description: OTHER ELECTRONIC COMPONENT MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110014439900

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Registry ID: 110071344724

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
TSCA SUBMITTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1006811770
Registry ID: 110014439900
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110014439900
Name: RAVEN INDUSTRIES INC
Address: 500 CENTER RIDGE DR STE 600
City,State,Zip: AUSTIN, TX 78753

3004 ESE 1/8-1/4 0.193 mi. 1017 ft. | **BEN WHITE U HAUL**
304 E BEN WHITE BLVD
AUSTIN, TX 78704 | **TX LPST** **TX UST** **TX HIST UST** | **U001269286** **N/A**

Actual: 656 ft.
Focus Map: 18

LPST:
Name: BEN WHITE U HAUL
Address: 304 E BEN WHITE BLVD
City,State,Zip: AUSTIN, TX 78704
Facility ID: 0036411
LPST Id: 110012
Facility Location: 304 E BEN WHITE
TCEQ Region# and City: REGION 11 - AUSTIN
Region City: AUSTIN
Discovered Date: 11/03/1995

BEN WHITE U HAUL (Continued) **U001269286**

Entered Date:	11/13/1995
Reported Date:	11/03/1995
Closure Date:	01/30/1996
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	DOUG DUNHAM
Responsible Party Address:	2721 N CENTRAL AVE STE 7000
Responsible Party City,St,Zip:	PHOENIX, AZ 85004
Responsible Party Telephone:	602/263-6647
Reported Date:	11/03/1995
Case Start Date:	01/30/1996
Reference Number:	RN101696359
Project Manager:	XYZ

UST:

Name:	BEN WHITE U HAUL
Address:	304 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047304
AI Number:	36411
Facility Type:	UNKNOWN
Facility Begin Date:	12/19/1986
Facility Status:	INACTIVE
Additional ID:	454367822002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	BEN WHITE U HAUL CO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123984718
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/21/1986
Signature Name/Title On Earliest Reg Form:	VERNA M CLEMINGS,OFF. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

BEN WHITE U HAUL (Continued) **U001269286**

Owner CN:	CN600349617
Owner Last Name:	U-HAUL CO OF SAN ANTONIO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	545292462001309
Additional ID:	454367822002075
AI Number:	36411
Owner Effective Begin Date:	12/19/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96303
Facility ID:	43091
Ai Number:	36411
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

BEN WHITE U HAUL (Continued) **U001269286**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	14901
UST ID:	96303
AI Number:	36411
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

BEN WHITE U HAUL (Continued) **U001269286**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14134
Cert ID:	47202
UST Comprt ID:	142344
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	46933
UST Comprt ID:	142345
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47203
UST Comprt ID:	142343
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47208
UST Comprt ID:	142338
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47207
UST Comprt ID:	142339
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

BEN WHITE U HAUL (Continued) **U001269286**

Self Cert ID:	14134
Cert ID:	47204
UST Comprt ID:	142342
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47200
UST Comprt ID:	142346
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47206
UST Comprt ID:	142340
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47205
UST Comprt ID:	142341
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47210
UST Comprt ID:	142336
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47201
UST Comprt ID:	142347
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Self Cert ID:	14134
Cert ID:	47209
UST Comprt ID:	142337
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

BEN WHITE U HAUL (Continued) **U001269286**

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96304
Facility ID:	43091
Ai Number:	36411
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

BEN WHITE U HAUL (Continued) **U001269286**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	550
UST Comprt ID:	14902
UST ID:	96304
AI Number:	36411
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14134
Cert ID:	47202
UST Comprt ID:	142344
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

BEN WHITE U HAUL (Continued) **U001269286**

Self Cert ID:	14134
Cert ID:	46933
UST Comprt ID:	142345
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47203
UST Comprt ID:	142343
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47208
UST Comprt ID:	142338
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47207
UST Comprt ID:	142339
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47204
UST Comprt ID:	142342
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47200
UST Comprt ID:	142346
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47206
UST Comprt ID:	142340
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134

BEN WHITE U HAUL (Continued) **U001269286**

Cert ID:	47205
UST Comprt ID:	142341
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47210
UST Comprt ID:	142336
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47201
UST Comprt ID:	142347
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47209
UST Comprt ID:	142337
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Install Date:	01/01/1980
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96302
Facility ID:	43091
Ai Number:	36411
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/31/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

BEN WHITE U HAUL (Continued) **U001269286**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	14900
UST ID:	96302
AI Number:	36411
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

BEN WHITE U HAUL (Continued) **U001269286**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	14134
Cert ID:	47202
UST Comprt ID:	142344
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	46933
UST Comprt ID:	142345
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47203
UST Comprt ID:	142343
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47208
UST Comprt ID:	142338
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134

BEN WHITE U HAUL (Continued) **U001269286**

Cert ID:	47207
UST Comprt ID:	142339
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47204
UST Comprt ID:	142342
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47200
UST Comprt ID:	142346
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47206
UST Comprt ID:	142340
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47205
UST Comprt ID:	142341
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47210
UST Comprt ID:	142336
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47201
UST Comprt ID:	142347
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A
Self Cert ID:	14134
Cert ID:	47209

BEN WHITE U HAUL (Continued) **U001269286**

UST Comprt ID:	142337
UST ID:	52625
AI Number:	36411
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	U-HAUL CO OF SAN ANTONIO
Contact Mailing Address (Delivery):	5810 SAN PEDRO AVE
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78212 1250
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	43091
Additional ID:	454367822002075
Princ ID:	545292462001309
AI Number:	36411
Facility Name:	BEN WHITE U HAUL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HORACE ROYAL/

HIST UST AUSTIN:

Name:	U-HAUL
Address:	304 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0593
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SB3005 **KOLPACK PROPERTY** **TX LPST** **S104272393**
WNW **901-905 BARTON SPRINGS RD** **N/A**
1/8-1/4 **AUSTIN, TX 78704**
0.193 mi.
1021 ft. **Site 1 of 2 in cluster SB**

Actual:
458 ft.

Focus Map:
11

LPST:

Name:	KOLPACK PROPERTY
Address:	901-905 BARTON SPRINGS RD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	Not reported
LPST Id:	112262
Facility Location:	901-905 BARTON SPRINGS RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/30/1996
Entered Date:	04/24/1997
Reported Date:	10/30/1996
Closure Date:	08/28/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS

KOLPACK PROPERTY (Continued) **S104272393**

Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RAB
Responsible Party Name:	Not reported
Responsible Party Contact:	JERI KOLPACK
Responsible Party Address:	5802 OCEAN DR
Responsible Party City,St,Zip:	CORPUS CHRISTI, TX 78412
Responsible Party Telephone:	512/992-9103
Reported Date:	10/30/1996
Case Start Date:	08/28/1997
Reference Number:	RN106984511
Project Manager:	BBELECKI

RJ3006 **SPTCO** **TX UST** **U001285450**
East **SAN MARCOS & E 5TH** **N/A**
1/8-1/4 **AUSTIN, TX**
0.194 mi.
1024 ft. **Site 3 of 3 in cluster RJ**

Actual:
470 ft.

Focus Map:
11

UST:

Name:	SPTCO
Address:	SAN MARCOS & E 5TH
City,State,Zip:	AUSTIN, TX
AI Number:	55193
Facility Type:	FLEET REFUELING
Facility Begin Date:	07/30/1990
Facility Status:	INACTIVE
Additional ID:	262812212002150
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	SAN MARCOS & E 5TH
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	SPTCO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5122243587
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/10/1990
Signature Name/Title On Earliest Reg Form:	PATRICIA CURL,AGENT FOR SPTCO
Application Received Date On Earliest Reg Form:	07/13/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

SPTCO (Continued) **U001285450**

Owner CN:	CN601543341
Owner Last Name:	SOUTHERN PACIFIC TRANSPORTATION COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	70586942003045
Additional ID:	262812212002150
AI Number:	55193
Owner Effective Begin Date:	07/30/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/13/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	134438
Facility ID:	47343
Ai Number:	55193
Tank Id:	4401702
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

SPTCO (Continued) **U001285450**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/20/1990

Compartment Records:

Tank ID:	4401702
Tank Capacity:	10000
UST Comprt ID:	27746
UST ID:	134438
AI Number:	55193
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

SPTCO (Continued) **U001285450**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/13/1990
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	134439
Facility ID:	47343
Ai Number:	55193
Tank Id:	4401703
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

SPTCO (Continued) **U001285450**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/20/1990

Compartment Records:

Tank ID:	4401703
Tank Capacity:	1000
UST Comprt ID:	27747
UST ID:	134439
AI Number:	55193
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

SPTCO (Continued) **U001285450**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	07/13/1990
Number of Compartments:	1
Tank Capacity:	13000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	134437
Facility ID:	47343
Ai Number:	55193
Tank Id:	4401701
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

SPTCO (Continued) **U001285450**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/20/1990

Compartment Records:

Tank ID:	4401701
Tank Capacity:	13000
UST Comprt ID:	27745
UST ID:	134437
AI Number:	55193
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

SPTCO (Continued) **U001285450**

Facility Billing Contacts:

Contact Organization Name:	SOUTHERN PACIFIC TRANSPORTATION COMPANY
Contact Mailing Address (Delivery):	1416 DODGE ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	OMAHA, NE 68179 0001
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47343
Additional ID:	262812212002150
Princ ID:	70586942003045
AI Number:	55193
Facility Name:	SPTCO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	STEVE MCNAUGHTON/

RS3007 **7-ELEVEN STORE 36643** **TX UST** **U004270553**
ENE **701 N IH 35** **TX Financial Assurance** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.194 mi.
1026 ft. **Site 6 of 9 in cluster RS**

Actual:
488 ft.

Focus Map:
11

UST:

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 787023203
AI Number:	73993
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	351554402002053
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	PEGGIE BETZ,
Contact Organization Name:	7-ELEVEN STORE 36643
Contact Mailing Address1:	701 EAST AVE
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787023203
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/24/2017
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,COMP MGR
Application Received Date On Earliest Reg Form:	03/06/2017
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER

7-ELEVEN STORE 36643 (Continued) **U004270553**

Signature Company On Earliest Reg Form: Not reported
Enforcement Action: No
Facility Not Inspectable: No

Operator:
Princ ID: 340554382002053
Additional ID: 351554402002053
Ai Number: 73993
Operator CN: CN600778914
Operator Name: MURAD RAZA MIR
Operator Effective Begin Date: 08/28/1996
Operator Type: IN
Operator Role: Not reported
Contact Name: /
Contact Organization Name: Not reported
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: -
Contact Phone Country Code: Not reported
Contact Phone Area Code: Not reported
Contact Phone Number: Not reported
Contact Phone Extension: Not reported
Contact Fax Country Code: Not reported
Contact Fax Area Code: Not reported
Contact Fax Number: Not reported
Contact Fax Extension: Not reported
Contact Email Address: Not reported
Contact Address Deliverable: Not reported

Owner:
Owner CN: CN600240329
Owner Last Name: 7-ELEVEN INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported
Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 959578622001257
Additional ID: 351554402002053
AI Number: 73993
Owner Effective Begin Date: 12/28/2012
State Tax ID: 17510851318
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Self Certification:
Self Cert ID: 112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	382289
AI Number:	73993
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	364972
AI Number:	73993
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	348415
AI Number:	73993
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	331316
AI Number:	73993
Self Certification Date:	01/10/2020
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	314192
AI Number:	73993
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	296159
AI Number:	73993
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	281188
AI Number:	73993
Self Certification Date:	01/20/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	264424
AI Number:	73993
Self Certification Date:	02/02/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	247254
AI Number:	73993
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	230914
AI Number:	73993
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	112819
Cert ID:	197628
AI Number:	73993
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197627
AI Number:	73993
Self Certification Date:	02/20/2012
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	197626
AI Number:	73993
Self Certification Date:	02/28/2011
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197625
AI Number:	73993
Self Certification Date:	02/15/2010
Signature Name/Title:	JEFFREY JOHANSON AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197624
AI Number:	73993
Self Certification Date:	02/23/2009
Signature Name/Title:	JEFFREY JOHANSON AUTH AGT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	197623
AI Number:	73993
Self Certification Date:	11/04/2008
Signature Name/Title:	JEFF JOHANSON REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197622
AI Number:	73993
Self Certification Date:	07/19/2008
Signature Name/Title:	CIFF SNYDER CFO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197621
AI Number:	73993
Self Certification Date:	07/18/2007
Signature Name/Title:	CLIFF SNYDER CFO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	197620
AI Number:	73993
Self Certification Date:	04/03/2006
Signature Name/Title:	DOUGLAS SCHRAM OPERATIONS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197619
AI Number:	73993
Self Certification Date:	04/12/2005
Signature Name/Title:	DOUGLAS G SCHRAM OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197618
AI Number:	73993
Self Certification Date:	03/01/2004
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	197617
AI Number:	73993
Self Certification Date:	03/04/2003
Signature Name/Title:	DOUGLAS G SCHRAM OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197616
AI Number:	73993
Self Certification Date:	02/14/2002
Signature Name/Title:	DOUGLAS G SCHRAM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	112819
Cert ID:	197615
AI Number:	73993
Self Certification Date:	10/05/2000
Signature Name/Title:	DOUGLAS G SCHRAM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

7-ELEVEN STORE 36643 (Continued) **U004270553**

Tank:

Install Date:	01/01/1995
Tank Registration Date:	11/15/2000
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196472
Facility ID:	112819
Ai Number:	73993
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

7-ELEVEN STORE 36643 (Continued) **U004270553**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	175917
UST ID:	196472
AI Number:	73993
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1995

More Self Certification:

Self Cert ID:	28312
Cert ID:	133605
UST Comprt ID:	370347
UST ID:	132281
AI Number:	73993
Tank ID:	1

7-ELEVEN STORE 36643 (Continued) **U004270553**

Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133874
UST Comprt ID:	370341
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133604
UST Comprt ID:	370348
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133871
UST Comprt ID:	370344
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133603
UST Comprt ID:	370349
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	286095
UST Comprt ID:	825578
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133602
UST Comprt ID:	370350
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133873
UST Comprt ID:	370342
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

7-ELEVEN STORE 36643 (Continued) **U004270553**

Self Cert ID:	28312
Cert ID:	133601
UST Comprt ID:	370353
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	269021
UST Comprt ID:	775021
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133600
UST Comprt ID:	370352
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133606
UST Comprt ID:	370346
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133599
UST Comprt ID:	370351
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	369831
UST Comprt ID:	1076911
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	251921
UST Comprt ID:	724301
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	133872
UST Comprt ID:	370343
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	352633
UST Comprt ID:	1025180
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	234230
UST Comprt ID:	672297
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	335794
UST Comprt ID:	974212
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133870
UST Comprt ID:	370345
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	319377
UST Comprt ID:	925041
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	301829
UST Comprt ID:	872842
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1995

7-ELEVEN STORE 36643 (Continued) **U004270553**

Tank Registration Date:	11/15/2000
Number of Compartments:	2
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196473
Facility ID:	112819
Ai Number:	73993
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

7-ELEVEN STORE 36643 (Continued) **U004270553**

Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	175918
UST ID:	196473
AI Number:	73993
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1995

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	175919
UST ID:	196473
AI Number:	73993
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

7-ELEVEN STORE 36643 (Continued) **U004270553**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1995

More Self Certification:

Self Cert ID:	28312
Cert ID:	133605
UST Comprt ID:	370347
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133874
UST Comprt ID:	370341
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133604
UST Comprt ID:	370348
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

7-ELEVEN STORE 36643 (Continued) **U004270553**

Self Cert ID:	28312
Cert ID:	133871
UST Comprt ID:	370344
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	133603
UST Comprt ID:	370349
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	286095
UST Comprt ID:	825578
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	133602
UST Comprt ID:	370350
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	133873
UST Comprt ID:	370342
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	133601
UST Comprt ID:	370353
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312
Cert ID:	269021
UST Comprt ID:	775021
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Self Cert ID:	28312

7-ELEVEN STORE 36643 (Continued) **U004270553**

Cert ID:	133600
UST Comprt ID:	370352
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133606
UST Comprt ID:	370346
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133599
UST Comprt ID:	370351
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	369831
UST Comprt ID:	1076911
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	251921
UST Comprt ID:	724301
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133872
UST Comprt ID:	370343
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	352633
UST Comprt ID:	1025180
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	234230

7-ELEVEN STORE 36643 (Continued) **U004270553**

UST Comprt ID:	672297
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	335794
UST Comprt ID:	974212
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	133870
UST Comprt ID:	370345
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	319377
UST Comprt ID:	925041
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A
Self Cert ID:	28312
Cert ID:	301829
UST Comprt ID:	872842
UST ID:	132281
AI Number:	73993
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	112819
Additional ID:	351554402002053
Princ ID:	959578622001257
AI Number:	73993
Facility Name:	7-ELEVEN STORE 36643
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

7-ELEVEN STORE 36643 (Continued) **U004270553**

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	279414
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	262270
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	242358
AI:	73993
Mechanism Type Other:	Not reported

7-ELEVEN STORE 36643 (Continued) **U004270553**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	224793
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	208025
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO

7-ELEVEN STORE 36643 (Continued) **U004270553**

Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	189309
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	173219
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35

7-ELEVEN STORE 36643 (Continued) **U004270553**

City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	156004
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4766411
Policy Number:	1235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	156353
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	138325
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN STORE 36643 (Continued) **U004270553**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	120931
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	118535
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000

7-ELEVEN STORE 36643 (Continued) **U004270553**

Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	16549
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	95822
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2011
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819

7-ELEVEN STORE 36643 (Continued) **U004270553**

Finass ID:	95823
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2010
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	95824
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2009
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361338
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	95825
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN STORE 36643 (Continued) **U004270553**

Financial Assurance Begin Date:	12/31/2008
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 0 0
Policy Number:	17722
Coverage Amount:	2000000
Coverage Expiration Date:	12/31/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	95826
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/23/2007
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	ZURICH AMERICAN INS CO
Issuer Phone:	1 800 7131158
Policy Number:	USC 5337993 04
Coverage Amount:	1000000
Coverage Expiration Date:	12/23/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36643
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	112819
Finass ID:	95827
AI:	73993
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/06/2017
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

SC3008 **JACK RITTER OIL CO.** **TX HIST UST** **S128729340**
West **2617 S 1ST ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.195 mi.
1032 ft. **Site 1 of 4 in cluster SC**

Actual:
567 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	JACK RITTER OIL CO.
Address:	2617 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0606
HID UST:	606
Inspection:	Not reported
Due:	06/01/2012

SC3009 **SOUTHSIDE BODY & FRAME** **TX RDR** **S127529936**
West **2617 S. FIRST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.195 mi.
1032 ft. **Site 2 of 4 in cluster SC**

Actual:
567 ft.

Focus Map:
14

RDR:

RDR ID:	4160
Facility ID:	31833
RN:	Not reported
CN:	Not reported
Name:	SOUTHSIDE BODY & FRAME
Address:	2617 S. FIRST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/8/1999
Due Date:	6/7/1999
Tank Owner:	SOUTHSIDE BODY & FRAME
Contact Person:	RUBEN CORTEZ
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/14/1999
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	5/14/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SC3010 West 1/8-1/4 0.195 mi. 1032 ft. | **SOUTHSIDE BODY & FRAME 2617 S 1ST ST AUSTIN, TX** | **TX HIST UST** | **S128729111 N/A**

Site 3 of 4 in cluster SC

Actual: 567 ft.

Focus Map: 14

HIST UST AUSTIN:

Name:	SOUTHSIDE BODY & FRAME
Address:	2617 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0672
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SC3011 West 1/8-1/4 0.195 mi. 1032 ft. | **SOUTH SIDE MOTOR 2617 S 1ST ST AUSTIN, TX 78704** | **TX UST** | **U001265116 N/A**

Site 4 of 4 in cluster SC

Actual: 567 ft.

Focus Map: 14

UST:

Name:	SOUTH SIDE MOTOR
Address:	2617 S 1ST ST
City,State,Zip:	AUSTIN, TX 787045451
AI Number:	31833
Facility Type:	UNKNOWN
Facility Begin Date:	03/05/1987
Facility Status:	INACTIVE
Additional ID:	829681962002057
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	JOE GONZALES,OWNER
Contact Organization Name:	SOUTH SIDE MOTOR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124427303
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/08/1986
Signature Name/Title On Earliest Reg Form:	JOE GONZALES,OWNER
Application Received Date On Earliest Reg Form:	05/12/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600787246
Owner Last Name:	SOUTH SIDE MOTOR

SOUTH SIDE MOTOR (Continued) **U001265116**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	820681932002057
Additional ID:	829681962002057
AI Number:	31833
Owner Effective Begin Date:	03/05/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	83600
Facility ID:	65831
Ai Number:	31833
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

SOUTH SIDE MOTOR (Continued) **U001265116**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	70431
UST ID:	83600
AI Number:	31833
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

SOUTH SIDE MOTOR (Continued) **U001265116**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	12207
Cert ID:	40911
UST Comprt ID:	133451
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40914
UST Comprt ID:	133448
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40910
UST Comprt ID:	133450
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40912
UST Comprt ID:	133452
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40913
UST Comprt ID:	133449
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A

SOUTH SIDE MOTOR (Continued) **U001265116**

Install Date:	08/31/1987
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	83601
Facility ID:	65831
Ai Number:	31833
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/11/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

SOUTH SIDE MOTOR (Continued) **U001265116**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	70432
UST ID:	83601
AI Number:	31833
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	12207
Cert ID:	40911
UST Comprt ID:	133451
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A

SOUTH SIDE MOTOR (Continued) **U001265116**

Self Cert ID:	12207
Cert ID:	40914
UST Comprt ID:	133448
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40910
UST Comprt ID:	133450
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40912
UST Comprt ID:	133452
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40913
UST Comprt ID:	133449
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	05/12/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	83602
Facility ID:	65831
Ai Number:	31833
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

SOUTH SIDE MOTOR (Continued) **U001265116**

Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	07/13/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	70433
UST ID:	83602
AI Number:	31833
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

SOUTH SIDE MOTOR (Continued) **U001265116**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	12207
Cert ID:	40911
UST Comprt ID:	133451
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40914
UST Comprt ID:	133448
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40910
UST Comprt ID:	133450
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A
Self Cert ID:	12207
Cert ID:	40912
UST Comprt ID:	133452
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A

SOUTH SIDE MOTOR (Continued) **U001265116**

Self Cert ID:	12207
Cert ID:	40913
UST Comprt ID:	133449
UST ID:	48856
AI Number:	31833
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	SOUTH SIDE MOTOR
Contact Mailing Address (Delivery):	2617 S 1ST ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5451
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	65831
Additional ID:	829681962002057
Princ ID:	820681932002057
AI Number:	31833
Facility Name:	SOUTH SIDE MOTOR
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOE GONZALEZ/

RS3012 **TEXACO FOOD MART** **TX LPST** **S116703891**
ENE **701 EAST AVE** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.196 mi.
1035 ft. **Site 7 of 9 in cluster RS**

Actual:
488 ft.

Focus Map:
11

LPST:

Name:	TEXACO FOOD MART
Address:	701 EAST AVE
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0023198
LPST Id:	097519
Facility Location:	701 EAST AVE @ 7TH ST & IH 35 N ACCESS RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/06/1990
Entered Date:	12/14/1990
Reported Date:	12/07/1990
Closure Date:	02/22/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JOAN BECKNER

TEXACO FOOD MART (Continued) **S116703891**

Responsible Party Address:	PO BOX 152045
Responsible Party City,St,Zip:	IRVING, TX 75015 2045
Responsible Party Telephone:	214/650-0200
Reported Date:	12/07/1990
Case Start Date:	02/22/1991
Reference Number:	RN105020283
Project Manager:	HWELCH

SD3013 **FORMER UNLIMITED AUTO SERVICE** **TX UST** **U003886479**
West **1023 W 24TH ST** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.196 mi.
1035 ft. **Site 1 of 4 in cluster SD**

Actual:
592 ft.

Focus Map:
11

UST:

Name:	FORMER UNLIMITED AUTO SERVICE
Address:	1023 W 24TH ST
City,State,Zip:	AUSTIN, TX 787054745
AI Number:	74979
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	373481802003020
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/19/2002
Signature Name/Title On Earliest Reg Form:	FARLEY DAKAN,
Application Received Date On Earliest Reg Form:	03/05/2002
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601532088
Owner Last Name:	ENFIELD HOMES LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported

FORMER UNLIMITED AUTO SERVICE (Continued) **U003886479**

Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	365481802003020
Additional ID:	373481802003020
AI Number:	74979
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/06/2002
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	199468
Facility ID:	114640
Ai Number:	74979
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/29/2001
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

FORMER UNLIMITED AUTO SERVICE (Continued) **U003886479**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	168550
UST ID:	199468
AI Number:	74979
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

FORMER UNLIMITED AUTO SERVICE (Continued) **U003886479**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	18358
Facility ID:	114640
AI Number:	74979
Application Received Date:	11/29/2001
Scheduled Construction Date:	12/29/2001
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M01129007
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	59199
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	19711
UST ID:	Not reported
NOC ID:	18358
AI Number:	74979
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000068
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

FORMER UNLIMITED AUTO SERVICE (Continued) **U003886479**

Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ENFIELD HOMES LTD
Contact Mailing Address (Delivery):	4407 BEE CAVES RD STE 511
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	WEST LAKE HILLS, TX 78746 6496
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	114640
Additional ID:	373481802003020
Princ ID:	365481802003020
AI Number:	74979
Facility Name:	FORMER UNLIMITED AUTO SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	FARLEY DAKAN/

SD3014 **TEXACO INC** **TX HIST UST** **S128729448**
West **1023 W 24TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.196 mi.
1035 ft. **Site 2 of 4 in cluster SD**

Actual:
592 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TEXACO INC
Address:	1023 W 24TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0853
HID UST:	853
Inspection:	Not reported
Due:	06/01/2012

SD3015 **FORMER UNLIMITED AUTO SER** **TX RDR** **S127539695**
West **1023 W 24TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.196 mi.
1035 ft. **Site 3 of 4 in cluster SD**

Actual:
592 ft.

Focus Map:
11

RDR:

RDR ID:	10085
Facility ID:	74979
RN:	Not reported
CN:	Not reported

FORMER UNLIMITED AUTO SER (Continued) **S127539695**

Name:	FORMER UNLIMITED AUTO SER
Address:	1023 W 24TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/16/2002
Due Date:	6/15/2002
Tank Owner:	ENFIELD HOMES LTD
Contact Person:	MR FARLEY DAKAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/6/2004
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC/TSR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	4/6/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SD3016 **UNLIMITED AUTO SERVICE** **TX HIST UST** **S128729552**
West **1023 W 24TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.196 mi.
1035 ft. **Site 4 of 4 in cluster SD**

Actual:
592 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	UNLIMITED AUTO SERVICE
Address:	1023 W 24TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0152
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RS3017 **TEXACO** **TX LPST** **S116697879**
ENE **701 N IH 35** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.196 mi.
1035 ft. **Site 8 of 9 in cluster RS**

Actual:
488 ft.

Focus Map:
11

LPST:

Name:	TEXACO
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0023198
LPST Id:	107988
Facility Location:	701 EAST AVENUE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/22/1994

TEXACO (Continued) **S116697879**

Entered Date:	08/22/1994
Reported Date:	02/22/1994
Closure Date:	08/10/1994
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	SCOTT HENDERSON
Responsible Party Address:	4500 FULLER DR SUITE 400
Responsible Party City,St,Zip:	IRVING, TX 75038
Responsible Party Telephone:	214/719-3480
Reported Date:	02/22/1994
Case Start Date:	08/10/1994
Reference Number:	RN105020283
Project Manager:	HWELCH

RS3018 **TEXACO** **TX LPST** **S116701751**
ENE **701 N IH 35** **N/A**
1/8-1/4 **AUSTIN, TX 78705**
0.196 mi.
1037 ft. **Site 9 of 9 in cluster RS**

Actual:
488 ft.

Focus Map:
11

LPST:

Name:	TEXACO
Address:	701 N IH 35
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0023198
LPST Id:	091374
Facility Location:	701 N IH 35
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/27/1987
Entered Date:	07/01/1987
Reported Date:	06/27/1987
Closure Date:	01/10/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	PETE WEHNER
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE HAWTHORNE
Responsible Party Address:	PO BOX 152045
Responsible Party City,St,Zip:	IRVING, TX 75015 0000
Responsible Party Telephone:	214/650-0200
Reported Date:	06/27/1987
Case Start Date:	01/10/1991
Reference Number:	RN105020283
Project Manager:	PJW

RV3019 **KWIK KOPY** **TX Ind. Haz Waste** **S102749792**
WNW **4011 MEDICAL PKWY** **N/A**
1/8-1/4 **AUSTIN, TX 78756**
0.197 mi.
1038 ft. **Site 2 of 2 in cluster RV**

Actual:
632 ft.

Focus Map:
8

Ind. Haz Waste:

Name:	KWIK KOPY
Address:	4011 MEDICAL PKWY
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	66301
Registration Initial Notification Date:	03/18/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19850318
Land Type:	Not reported
Description of Facility Site Location:	4011 Medical Pkwy, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	NON INDUS
Company Name:	KWIK KOPY
Contact Name:	LEAH LINNEY
Contact Telephone Number:	512-4591339
Mailing Address:	4011 MEDICAL PKWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787563702
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21580
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100604
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

KWIK KOPY (Continued) **S102749792**

Ind. Haz Waste:

Owner Name:	KWIK KOPY
Owner Mailing Address:	4011 MEDICAL PKWY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Country:	UNITED STA
Owner Telephone:	1-512-4591339
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	4011 MEDICAL PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4591339
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LEAH LINNEY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	4011 MEDICAL PKWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4591339
Contact Fax:	Not reported
Contact Email:	Not reported

SE3020 **FORMER RITLER OIL** **TX UST** **U003921131**
North **1250 BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78761**
0.197 mi.
1040 ft. **Site 1 of 5 in cluster SE**

Actual:
476 ft.

Focus Map:
16

UST:

Name:	FORMER RITLER OIL
Address:	1250 BASTROP HWY
City,State,Zip:	AUSTIN, TX 78761
AI Number:	75974
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	459498912005280
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

FORMER RITLER OIL (Continued) **U003921131**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78761
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/04/2003
Signature Name/Title On Earliest Reg Form:	RONNIE KENNEDY,UST CONTRACTOR
Application Received Date On Earliest Reg Form:	08/07/2003
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600803456
Owner Last Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	976653722002061
Additional ID:	459498912005280
AI Number:	75974
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/07/2003
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	201903

FORMER RITLER OIL (Continued) **U003921131**

Facility ID:	116539
Ai Number:	75974
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/31/2003
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	Y
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000

FORMER RITLER OIL (Continued) **U003921131**

UST Comprt ID:	182769
UST ID:	201903
AI Number:	75974
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/07/2003
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	201904
Facility ID:	116539
Ai Number:	75974
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/31/2003
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported

FORMER RITLER OIL (Continued) **U003921131**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	Y
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	182770
UST ID:	201904
AI Number:	75974
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

FORMER RITLER OIL (Continued) **U003921131**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	08/07/2003
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	201905
Facility ID:	116539
Ai Number:	75974
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/31/2003
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

FORMER RITLER OIL (Continued) **U003921131**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	Y
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	182771
UST ID:	201905
AI Number:	75974
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

FORMER RITLER OIL (Continued) **U003921131**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	20246
Facility ID:	116539
AI Number:	75974
Application Received Date:	07/18/2003
Scheduled Construction Date:	07/21/2003
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30718006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21479
General Desc Of Prop Construct:	Not reported

Facility Billing Contacts:

FORMER RITLER OIL (Continued) **U003921131**

Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Mailing Address (Delivery):	PO BOX 15426
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78761 5426
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	116539
Additional ID:	459498912005280
Princ ID:	976653722002061
AI Number:	75974
Facility Name:	FORMER RITLER OIL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GENE STABENO/

SE3021 **LARRY'S AUTO SALES** **TX HIST UST** **S128729129**
North **1250 OLD BASTROP RD.** **N/A**
1/8-1/4 **AUSTIN, TX**
0.197 mi.
1040 ft. **Site 2 of 5 in cluster SE**

Actual:
476 ft.

Focus Map:
16

HIST UST AUSTIN:

Name:	LARRY'S AUTO SALES
Address:	1250 OLD BASTROP RD.
City,State,Zip:	AUSTIN, TX
Id UST:	C0708
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SE3022 **TXDOT RIGHT OF AWAY** **TX RDR** **S127543720**
North **1250 BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.197 mi.
1040 ft. **Site 3 of 5 in cluster SE**

Actual:
476 ft.

Focus Map:
16

RDR:

RDR ID:	12796
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	TXDOT RIGHT OF AWAY
Address:	1250 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/8/2003
Due Date:	11/7/2003
Tank Owner:	TXDOT
Contact Person:	STEVE BARBRE
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/25/2004

TXDOT RIGHT OF AWAY (Continued) **S127543720**

Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC/REP
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	10/25/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SF3023 **MRS. WILLIE EAGLETON** **TX HIST UST** **S111678755**
WNW **1001 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.197 mi.
1042 ft. **Site 1 of 5 in cluster SF**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	MRS. WILLIE EAGLETON
Address:	1001 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0996
HID UST:	996
Inspection:	Not reported
Due:	06/01/2012

SG3024 **B&B LAND CLEARING** **TX HIST UST** **S128729068**
ESE **1212 BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.198 mi.
1043 ft. **Site 1 of 2 in cluster SG**

Actual:
475 ft.

Focus Map:
16

HIST UST AUSTIN:

Name:	B&B LAND CLEARING
Address:	1212 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	C0534
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SG3025 ESE 1/8-1/4 0.198 mi. 1043 ft. | **B&B LAND CLEARING**
1212 OLD BASTROP HWY
AUSTIN, TX 78742

Site 2 of 2 in cluster SG

TX UST | **U001278876**
N/A

Actual: 475 ft.

Focus Map: 16

UST:

Name:	B&B LAND CLEARING
Address:	1212 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX 787422633
AI Number:	47607
Facility Type:	UNKNOWN
Facility Begin Date:	03/13/1989
Facility Status:	INACTIVE
Additional ID:	715651442002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	BRUCE HYDE,PRES
Contact Organization Name:	B&B LAND CLEARING
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123853781
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/23/1988
Signature Name/Title On Earliest Reg Form:	SAME,
Application Received Date On Earliest Reg Form:	12/30/1988
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600782288
Owner Last Name:	B & B LAND CLEARING COMPANY INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	706651432002053
Additional ID:	715651442002053

B&B LAND CLEARING (Continued) **U001278876**

AI Number:	47607
Owner Effective Begin Date:	03/13/1989
State Tax ID:	17418260513
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	12/30/1988
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	124114
Facility ID:	79054
Ai Number:	47607
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/27/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

B&B LAND CLEARING (Continued) **U001278876**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/03/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	113397
UST ID:	124114
AI Number:	47607
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

B&B LAND CLEARING (Continued) **U001278876**

Facility Billing Contacts:

Contact Organization Name:	B & B LAND CLEARING CO INC
Contact Mailing Address (Delivery):	1212 OLD BASTROP HWY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	N
Facility ID:	79054
Additional ID:	715651442002053
Princ ID:	706651432002053
AI Number:	47607
Facility Name:	B&B LAND CLEARING
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

3026 WNW 1/8-1/4 0.198 mi. 1043 ft. **RECREATIONAL EQUIPMENT INC** **TX HIST UST** **S111678804**
601 N LAMAR BLVD **TX ASBESTOS** **N/A**
AUSTIN, TX 78703

Actual: 488 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	SELECT MOTORS
Address:	601 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0763
HID UST:	763
Inspection:	Not reported
Due:	06/01/2012

ASBESTOS:

Name:	RECREATIONAL EQUIPMENT INC
Address:	601 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson

RECREATIONAL EQUIPMENT INC (Continued) **S111678804**

Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	RECREATIONAL EQUIPMENT INC
Address:	601 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	05/23/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported

RECREATIONAL EQUIPMENT INC (Continued) **S111678804**

Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	4.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/02/2014
Date Routed by Supervisor:	06/02/2014
Date Routed to PSQA:	06/03/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

RECREATIONAL EQUIPMENT INC (Continued) **S111678804**

Inspection Class Descriptio: Not reported
Inspection Secondary Class Code: Not reported
Inspection Secondary Class Code Description: Not reported
Results: Not reported
Inspection Number Grade: Not reported

SH3027 **TXDOT SPECIAL CREWS WAREHOUSE** **TX LPST** **U003040300**
NNE **760 BASTROP HWY S** **TX UST** **N/A**
1/8-1/4 **AUSTIN, TX 78741** **TX HIST UST**
0.198 mi.
1044 ft. **Site 1 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

LPST:

Name:	TXDOT MAIN FACILITY
Address:	760 BASTROP HWY S
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0010054
LPST Id:	097012
Facility Location:	760 BASTROP HWY
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/15/1990
Entered Date:	10/23/1990
Reported Date:	10/15/1990
Closure Date:	08/09/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BILL WILSON
Responsible Party Address:	760 BASTROP HWY
Responsible Party City,St,Zip:	AUSTIN, TX 78753
Responsible Party Telephone:	512/463-0258
Reported Date:	10/15/1990
Case Start Date:	08/09/1991
Reference Number:	RN101696235
Project Manager:	HWELCH

UST:

Name:	TXDOT SPECIAL CREWS WAREHOUSE
Address:	760 BASTROP HWY S
City,State,Zip:	AUSTIN, TX 787413647
AI Number:	10054
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/01/1983
Facility Status:	INACTIVE
Additional ID:	904361522002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	ROBERT NORMENT,FAC COORD
Contact Organization Name:	TXDOT SPECIAL CREWS WAREHOUSE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128327067
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	01/07/2014
Signature Name/Title On Earliest Reg Form:	TIM NICHOLES,
Application Received Date On Earliest Reg Form:	01/07/2014
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	976653722002061
Additional ID:	904361522002075
Ai Number:	10054
Operator CN:	CN600803456
Operator Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Operator Effective Begin Date:	05/08/1986
Operator Type:	SG
Operator Role:	OPRCON
Contact Name:	SEVERIANO K SISNEROS/BROWNFIELD AREA ENGINEER
Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Mailing Address (Delivery):	135 SLATON RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	LUBBOCK TX 79404-5201
Contact Phone Country Code:	1
Contact Phone Area Code:	806
Contact Phone Number:	6374501
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	SEVE.SISNEROS@TXDOT.GOV
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600803456
Owner Last Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	150 E RIVERSIDE DR
Contact Mailing Address (Internal Delivery):	MAINTENANCE DIVISION
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	1202

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Contact Phone Number/Ext:	1 512 4163056/0
Contact Fax Country Code:	1
Contact Fax Number/Ext:	512 4162914/0
Contact Email Address:	DEBA.DUTTA@TXDOT.GOV
Contact Address Deliverable:	Not reported
Princ ID:	976653722002061
Additional ID:	904361522002075
AI Number:	10054
Owner Effective Begin Date:	05/08/1986
State Tax ID:	Not reported
Contact Role:	OWNCON
Contact Name/Title:	JAMES STEVENSON/MAINTENANCE DEPUTY DIVISION DIRECTOR
Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION

Self Certification:

Self Cert ID:	73754
Cert ID:	102646
AI Number:	10054
Self Certification Date:	07/27/2005
Signature Name/Title:	ROBERT NORMENT FACILITY COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	73754
Cert ID:	102645
AI Number:	10054
Self Certification Date:	07/26/2005
Signature Name/Title:	ROBERT NORMENT FACILITY COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	73754
Cert ID:	102644
AI Number:	10054
Self Certification Date:	07/11/2002

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Signature Name/Title:	ROBERT H NORMENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	73754
Cert ID:	102643
AI Number:	10054
Self Certification Date:	08/07/2000
Signature Name/Title:	GENE STABENO DIST MAINT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1951
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	26563
Facility ID:	73754
Ai Number:	10054
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/27/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	1A
Tank Capacity:	3000
UST Comprt ID:	104207
UST ID:	26563
AI Number:	10054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1991
Tank Registration Date:	02/14/1992
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	179675
Facility ID:	73754
Ai Number:	10054
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/19/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/30/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	104210
UST ID:	179675
AI Number:	10054
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4380
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	26565
Facility ID:	73754
Ai Number:	10054
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/19/2013
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	104209
UST ID:	26565
AI Number:	10054
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	26564
Facility ID:	73754
Ai Number:	10054
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/27/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/21/1993

Compartment Records:

Tank ID:	2A
Tank Capacity:	1000
UST Comprt ID:	104208
UST ID:	26564
AI Number:	10054
Compartment ID:	A
Substance Stored1:	SOLVENTS
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Stage 1 Installation Date: Not reported

Construction Notification:

NOC ID:	24940
Facility ID:	73754
AI Number:	10054
Application Received Date:	11/18/2013
Scheduled Construction Date:	12/16/2013
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	11/18/2013
Signature Date On Form:	11/18/2013
Signature Name On Form:	JERRY WICK
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner CN At Time Of Construction:	CN600803456
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	REMOVAL OF TANKS & ASSOCIATED PIPING.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	58476
UST ID:	Not reported
NOC ID:	24940
AI Number:	10054
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PARK CENTRE BLVD 1
Representative Name:	JERRY WICK
Mailing Address (Delivery):	8601 RR 2222
Mailing Address (Internal Delivery):	PARK CENTRE BLVD. 1
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78730
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4990437
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	4990438

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Email Address:	Not reported
Cont/Cons/Installer ID:	58475
UST ID:	Not reported
NOC ID:	24940
AI Number:	10054
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PARK CENTRE BLVD 1
Representative Name:	JERRY WICK
Mailing Address (Delivery):	8601 RR 2222
Mailing Address (Internal Delivery):	PARK CENTRE BLVD. 1
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78730
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4990437
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	4991416
Email Address:	Not reported
Cont/Cons/Installer ID:	29802
UST ID:	179675
NOC ID:	Not reported
AI Number:	10054
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000050
Company Name:	Sundrop Services, Inc
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	44966
UST ID:	179675
NOC ID:	Not reported
AI Number:	10054
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001035
Company Name:	Not reported

TXDOT SPECIAL CREWS WAREHOUSE (Continued) **U003040300**

Representative Name:	CHRIS BAKER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Mailing Address (Delivery):	PO BOX 15426
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78761 5426
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	73754
Additional ID:	904361522002075
Princ ID:	976653722002061
AI Number:	10054
Facility Name:	TXDOT SPECIAL CREWS WAREHOUSE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GENE STABENO/

HIST UST AUSTIN:

Name:	STATE DEPT OF HWYS
Address:	760 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	EX002
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SH3028 **TEXAS DEPARTMENT OF TRANSPORTATION** **RCRA NonGen / NLR** **1000156883**
NNE **760 LOCKHART HWY** **FINDS** **TXD981606338**
1/8-1/4 **AUSTIN, TX 78741** **ECHO**
0.198 mi.
1044 ft. **Site 2 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20010127
Handler Name:	Texas Department Of Transportation
Handler Address:	LOCKHART HWY
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXD981606338
Contact Name:	LLOYD CARSTEDER
Contact Address:	LOCKHART HWY
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Telephone:	512-331-5361
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	LOCKHART HWY
Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Name:	Texas Department Of Transportation
Owner Type:	Not reported
Operator Name:	Texas Department Of Transportation
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1000156883**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: TEXAS DEPARTMENT OF TRANSPORTATION	
Legal Status:	Not reported
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	760 LOCKHART HWY
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-331-5361
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE DEPT OF HWYS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1000156883**

Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF TRANSPORTATION
Legal Status: Not reported
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 760 LOCKHART HWY
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-331-5361
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860919
Handler Name: TEXAS DEPT OF HWYS SPECIAL MAINTENANCE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010127
Handler Name: TEXAS DEPARTMENT OF TRANSPORTATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23411
NAICS Description: HIGHWAY AND STREET CONSTRUCTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1000156883**

FINDS:
Registry ID: 110005094682

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Registry ID: 110070165030

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000156883
Registry ID:	110005094682
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005094682
Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Address:	760 LOCKHART HWY
City,State,Zip:	AUSTIN, TX 78741

SH3029 **TEXAS DEPARTMENT OF TRANSPORTATION** **RCRA NonGen / NLR** **1004784656**
NNE **760 US HIGHWAY 183 S** **FINDS** **TXD981908429**
1/8-1/4 **AUSTIN, TX 78741** **ECHO**
0.198 mi.
1044 ft. **Site 3 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Texas Department Of Transportation
Handler Address:	US HIGHWAY 183 S
Handler City,State,Zip:	AUSTIN, TX 78741
EPA ID:	TXD981908429
Contact Name:	WILLIE HAVERLAND
Contact Address:	US HIGHWAY 183 S
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Telephone:	512-385-0862
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1004784656**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	US HIGHWAY 183 S
Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Name:	Texas Department Of Transportation
Owner Type:	Not reported
Operator Name:	Texas Department Of Transportation
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1004784656**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	760 US HIGHWAY 183 S
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-385-0862
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TEXAS HIGHWAY DEPT
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Legal Status:	Not reported
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	760 US HIGHWAY 183 S
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-385-0862
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19870331
Handler Name:	TEXAS DEPT OF HWYS TRAVIS E WAREHOUSE
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **1004784656**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005099008

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Registry ID: 110070170610

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004784656
Registry ID:	110005099008
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005099008
Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Address:	760 US HIGHWAY 183 S
City,State,Zip:	AUSTIN, TX 78741

SH3030 **TEXAS DEPARTMENT OF TRANSPORTATION** **TX Ind. Haz Waste** **S104854173**
NNE **760 LOCKHART HWY** **N/A**
1/8-1/4 **AUSTIN, TX 78741**
0.198 mi.
1044 ft. **Site 4 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

Ind. Haz Waste:

Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Address:	760 LOCKHART HWY
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	66333
Registration Initial Notification Date:	06/04/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981606338
Primary NAICS Code:	237310
Status Change Date:	19850604
Land Type:	Not reported
Description of Facility Site Location:	760 Lockhart Hwy, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Name:	LLOYD CARSTEDER
Contact Telephone Number:	512-3315361
Mailing Address:	760 LOCKHART HWY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787413606
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21612
Site Owner Tax ID:	760441591
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040616
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Operator Address:	760 LOCKHART HWY
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78741
Operator Country:	UNITED STA
Operator Telephone:	1-512-3315361
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner Mailing Address:	760 LOCKHART HWY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Country:	UNITED STA
Owner Telephone:	1-512-3315361
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	760 LOCKHART HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3315361
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	760 LOCKHART HWY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3315361
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LLOYD CARSTEDER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	760 LOCKHART HWY
Contact Address 2:	Not reported

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3315361
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	68202
Texas Waste Code:	Not reported
Texas Waste Code 2:	2000319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solvent base white traffic paint solids, off-specification product from equipmen
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68203
Texas Waste Code:	Not reported
Texas Waste Code 2:	2100604H
Waste Code Status:	INACTIVE
Waste Form:	604
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	White sludge. Solvent base white traffic paint, off-specification product frome
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	NOR INACTIVATED

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68204
Texas Waste Code:	Not reported
Texas Waste Code 2:	2200209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	White liquid. Solvent base white traffic paint, off-specification product frome
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68205
Texas Waste Code:	Not reported
Texas Waste Code 2:	3000319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Solvent base yellow traffic paint solids, off-specification product from equipme
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	NOR INACTIVATED

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	68206
Texas Waste Code:	Not reported
Texas Waste Code 2:	3100604H
Waste Code Status:	INACTIVE
Waste Form:	604
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Yellow sludge. Solvent base yellow traffic paint, off-specification product fro
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W604
Reason Waste Form No Longer Gen:	NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	46691
Texas Waste Code:	Not reported
Texas Waste Code 2:	3200209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Yellow liquid. Solvent base yellow traffic paint, off-specification product fro
Standard Industrial Code:	16110
Primary Source:	G13
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	237310
EPA Waste Form Code:	W209

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Reason Waste Form No Longer Gen: NOR INACTIVATED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	261779
Texas Waste Code:	Not reported
Texas Waste Code 2:	C47J209H
Waste Code Status:	Not reported
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	760 BASTROP HWY S
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000308265
Principal Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	760 BASTROP HWY S
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000308265
Principal Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported

TEXAS DEPARTMENT OF TRANSPORTATION (Continued) **S104854173**

Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	760 BASTROP HWY S
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000308265
Principal Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	760 BASTROP HWY S
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000308265
Principal Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Attention Name:	Not reported
Attention Suffix:	NWG

SH3031 **TEXAS DEPT OF TRANSPORTATION TRAVIS EAST WAREHOUSE** **TX Ind. Haz Waste** **S104854229**
NNE **760 US HIGHWAY 183 S** **N/A**
1/8-1/4 **AUSTIN, TX 78741**
0.198 mi.
1044 ft. **Site 5 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

Ind. Haz Waste:

Name:	TEXAS DEPT OF TRANSPORTATION TRAVIS EAST WAREHOUSE
Address:	760 US HIGHWAY 183 S
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	67567
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981908429
Primary NAICS Code:	Not reported
Status Change Date:	19850930
Land Type:	Not reported
Description of Facility Site Location:	760 US Highway 183 S, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Name:	WILLIE HAVERLAND
Contact Telephone Number:	512-3850862
Mailing Address:	760 US HIGHWAY 183 S

TEXAS DEPT OF TRANSPORTATION TRAVIS EAST WAREHOUSE (Continued) **S104854229**

Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787413606
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	22680
Site Owner Tax ID:	760441591
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030314
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Operator Address:	760 US HIGHWAY 183 S
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78741
Operator Country:	UNITED STA
Operator Telephone:	1-512-3850862
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner Mailing Address:	760 US HIGHWAY 183 S
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Country:	UNITED STA
Owner Telephone:	1-512-3850862
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	760 US HIGHWAY 183 S
Contact Address 2:	Not reported

TEXAS DEPT OF TRANSPORTATION TRAVIS EAST WAREHOUSE (Continued) **S104854229**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3850862
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	760 US HIGHWAY 183 S
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3850862
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	WILLIE HAVERLAND
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	760 US HIGHWAY 183 S
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3850862
Contact Fax:	Not reported
Contact Email:	Not reported

SH3032 **TXDOT OLD AUSTIN SPECIAL CREWS MAIN** **TX RDR** **S127523901**
NNE **760 BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.198 mi.
1044 ft. **Site 6 of 6 in cluster SH**

Actual:
460 ft.

Focus Map:
15

RDR:

RDR ID:	21816
Facility ID:	10054
RN:	Not reported
CN:	Not reported
Name:	TXDOT OLD AUSTIN SPECIAL CREWS MAIN
Address:	760 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/13/2014
Due Date:	4/14/2014
Tank Owner:	TXDOT
Contact Person:	TERRY DEMPSEY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/9/2014
Project Manager:	Michelle Ogee
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	MAO
Date Release Reported:	Not reported
Suspected:	Not reported

TXDOT OLD AUSTIN SPECIAL CREWS MAIN (Continued) **S127523901**

Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SF3033 **7 ELEVEN 21884** **TX RDR** **S127538744**
WNW **917 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.199 mi.
1053 ft. **Site 2 of 5 in cluster SF**

Actual:
469 ft.

Focus Map:
11

RDR:

RDR ID:	19565
Facility ID:	7174
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/3/2011
Due Date:	5/2/2011
Tank Owner:	7 ELEVEN
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	4/25/2011
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	103888
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	4/25/2011
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SF3034 **7 ELEVEN STORE 21884** **TX PST STAGE 2** **S121999803**
WNW **917 N LAMAR BLVD** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.199 mi.
1053 ft. **Site 3 of 5 in cluster SF**

Actual:
469 ft.

Focus Map:
11

PST STAGE 2:

Regulated Number:	RN102019692
Region Location:	11
Has Active Violation:	NO
PST ID:	7174
Start Date:	07/08/1986
Stage 2 Type:	ASSIST SYSTEM
Stage 2 Install Date:	12/30/2010
Last Inspection Activity:	Not reported

7 ELEVEN STORE 21884 (Continued) **S121999803**

EACT Status:	ACTIVE
ADDN ID:	7174
Last Inspection Number:	Not reported
Last Inspection Status Date:	Not reported
Last Inspection Status:	Not reported
Last Inspection Activity 2:	Not reported
Last Inspection Conducted By:	Not reported
Facility Not Inspected:	Not reported
Facility Not Inspected Reason:	Not reported
ADDN Status:	ACTIVE
Status:	ACTIVE
Signed Date:	01/23/2019
Expired Date:	01/31/2020
Tank Status:	IN USE
Type:	RETAIL
UST Number:	2
Latitude:	0
Longitude:	0

Stage2 Detail:

RN:	RN102019692
Reg Status:	FULLY REGULATED
CN:	CN600240329
Princ Name:	7-ELEVEN INC
Princ Legal Name:	7-Eleven, Inc.
Role:	OWNOPR
First Name:	Not reported
Middle Name:	Not reported
Last Name:	Not reported
PST UST ID:	18613
UST Tank ID:	2
Num UST Comprt:	1
Install Date:	01/01/1981
Regis Date:	05/08/1986
Capacity Qty:	12000
Substance Type:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC

7 ELEVEN STORE 21884 (Continued) **S121999803**

Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08

7 ELEVEN STORE 21884 (Continued) **S121999803**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN600240329
Customer Name:	7-ELEVEN INC
Customer Legal Name:	7-Eleven, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1986-07-08
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP
Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110

7 ELEVEN STORE 21884 (Continued) **S121999803**

Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: Not reported

Regulated Entity Number: RN102019692
Name: 7 ELEVEN STORE 21884
Address: 917 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4946
Status: ACTIVE
Status Date: 2002-04-27
Customer Number: CN604401562
Customer Name: SOUTHLAND CORP
Customer Legal Name: Southland Corp
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: Not reported

Regulated Entity Number: RN102019692
Name: 7 ELEVEN STORE 21884
Address: 917 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4946
Status: ACTIVE
Status Date: 2002-04-27
Customer Number: CN604401562
Customer Name: SOUTHLAND CORP
Customer Legal Name: Southland Corp
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: Not reported

Regulated Entity Number: RN102019692
Name: 7 ELEVEN STORE 21884
Address: 917 N LAMAR BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4946
Status: ACTIVE
Status Date: 2002-04-27
Customer Number: CN604401562
Customer Name: SOUTHLAND CORP
Customer Legal Name: Southland Corp
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 447110
Primary NAICS Industry Type Description: Gasoline Stations with Convenience Stores
Physical Location Description: Not reported

7 ELEVEN STORE 21884 (Continued) **S121999803**

Regulated Entity Number:	RN102019692
Name:	7 ELEVEN STORE 21884
Address:	917 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4946
Status:	ACTIVE
Status Date:	2002-04-27
Customer Number:	CN604401562
Customer Name:	SOUTHLAND CORP
Customer Legal Name:	Southland Corp
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	447110
Primary NAICS Industry Type Description:	Gasoline Stations with Convenience Stores
Physical Location Description:	Not reported

Click this hyperlink while viewing on your computer to access
6 additional TX CENTRAL REG: record(s) in the EDR Site Report.

SF3035 **7-ELEVEN 21884** **TX LPST** **U003103746**
WNW **917 N LAMAR BLVD** **TX UST** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX HIST UST**
0.199 mi. **TX ASBESTOS**
1053 ft. **Site 4 of 5 in cluster SF** **TX Financial Assurance**

Actual:
469 ft.

Focus Map:
11

LPST:

Name:	7 11 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0007174
LPST Id:	103888
Facility Location:	917 NORTH LAMAR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/22/1991
Entered Date:	08/04/1992
Reported Date:	07/13/1992
Closure Date:	06/01/1999
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT 500F
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater or storm water runoff is affected and discharges within 500 feet of the known extent of contamination to a surface water body used for human drinking water, contact recreation, habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/2
Coordinators RPR:	KKC
Responsible Party Name:	Not reported
Responsible Party Contact:	JANE LOMAS
Responsible Party Address:	1201 BELTLINE RD
Responsible Party City,St,Zip:	COPPELL, TX 75019
Responsible Party Telephone:	817/341-8313
Reported Date:	07/13/1992
Case Start Date:	06/01/1999
Reference Number:	RN102019692

7-ELEVEN 21884 (Continued) **U003103746**

Project Manager: KKC

UST:

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787034946
AI Number:	7174
Facility Type:	RETAIL
Facility Begin Date:	07/08/1986
Facility Status:	ACTIVE
Additional ID:	781158282002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	CHAS BECK,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	781158282002117
Ai Number:	7174
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	07/08/1986
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	781158282002117
AI Number:	7174
Owner Effective Begin Date:	07/08/1986
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46176
Cert ID:	381579
AI Number:	7174
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	364255
AI Number:	7174
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	347749
AI Number:	7174
Self Certification Date:	01/18/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	330874
AI Number:	7174
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	314560
AI Number:	7174
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	296189
AI Number:	7174
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	280850
AI Number:	7174
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	263383
AI Number:	7174
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	247376
AI Number:	7174
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	230173
AI Number:	7174
Self Certification Date:	01/13/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46176
Cert ID:	28103
AI Number:	7174
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28102
AI Number:	7174
Self Certification Date:	12/16/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28101
AI Number:	7174
Self Certification Date:	01/12/2011
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28100
AI Number:	7174
Self Certification Date:	01/11/2011
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28099
AI Number:	7174
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28098
AI Number:	7174
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28097
AI Number:	7174
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28096
AI Number:	7174
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28095
AI Number:	7174
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28094
AI Number:	7174
Self Certification Date:	12/15/2004
Signature Name/Title:	RON FULENCHEK GAS & ENV COMPL MGR

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28093
AI Number:	7174
Self Certification Date:	10/27/2003
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28092
AI Number:	7174
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH REG ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28091
AI Number:	7174
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR

7-ELEVEN 21884 (Continued) **U003103746**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46176
Cert ID:	28090
AI Number:	7174
Self Certification Date:	01/17/2001
Signature Name/Title:	WILLOW A SMITH ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18613
Facility ID:	46176
Ai Number:	7174
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/25/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

7-ELEVEN 21884 (Continued) **U003103746**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	26093
UST ID:	18613
AI Number:	7174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

7-ELEVEN 21884 (Continued) **U003103746**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18614
Facility ID:	46176
Ai Number:	7174
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/25/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y

7-ELEVEN 21884 (Continued) **U003103746**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	26094
UST ID:	18614
AI Number:	7174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

7-ELEVEN 21884 (Continued) **U003103746**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	18615
Facility ID:	46176
Ai Number:	7174
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/25/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y

7-ELEVEN 21884 (Continued) **U003103746**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	26095
UST ID:	18615
AI Number:	7174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N

7-ELEVEN 21884 (Continued) **U003103746**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	12/21/2010
Tank Registration Date:	01/11/2011
Number of Compartments:	1
Tank Capacity:	15000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	214397
Facility ID:	46176
Ai Number:	7174
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	12/21/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

7-ELEVEN 21884 (Continued) **U003103746**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/07/2011

Compartment Records:

Tank ID:	4
Tank Capacity:	15000
UST Comprt ID:	26096
UST ID:	214397
AI Number:	7174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	12/30/2010

7-ELEVEN 21884 (Continued) **U003103746**

Install Date:	12/21/2010
Tank Registration Date:	01/11/2011
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	214398
Facility ID:	46176
Ai Number:	7174
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	12/21/2010
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

7-ELEVEN 21884 (Continued) **U003103746**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/07/2011

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	26097
UST ID:	214398
AI Number:	7174
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	12/30/2010

Construction Notification:

NOC ID:	2519
Facility ID:	46176
AI Number:	7174
Application Received Date:	10/11/2010
Scheduled Construction Date:	11/01/2010
UST Improvement:	N

7-ELEVEN 21884 (Continued) **U003103746**

UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVE 3-12,000 SINGLE WALLED TANKS AND EXISTING UNDERGROUND PIPING. INSTALL 1-1 5,000 GALLON DOUBLE-WALLED FIBERGLASS TANK AND 1-10,000 GALLON DOUBLE-WALLED FIB ERGLASS TANK. INSTALL NEW DOUBLE-WALLED FIBERGLASS PIPING.

NOC ID:	2518
Facility ID:	46176
AI Number:	7174
Application Received Date:	10/11/2010
Scheduled Construction Date:	11/01/2010
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REMOVE 3-12,000 SINGLE WALLED TANKS AND EXISTING UNDERGROUND PIPING. INSTALL 1-1 5,000 GALLON DOUBLE-WALLED FIBERGLASS TANK AND 1-10,000 GALLON DOUBLE-WALLED FIB ERGLASS TANK. INSTALL NEW DOUBLE-WALLED FIBERGLASS PIPING.

7-ELEVEN 21884 (Continued) **U003103746**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	2785
UST ID:	Not reported
NOC ID:	2519
AI Number:	7174
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	JENNIFER DART
Mailing Address (Delivery):	6330 COMMERCE ST
Mailing Address (Internal Delivery):	STE 190
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	214
Phone Number:	2777848
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2782
UST ID:	Not reported
NOC ID:	2518
AI Number:	7174
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	JENNIFER DART
Mailing Address (Delivery):	6330 COMMERCE ST
Mailing Address (Internal Delivery):	STE 190
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	214
Phone Number:	2777848
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2784
UST ID:	Not reported
NOC ID:	2519
AI Number:	7174
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING & PETROLEUM SVCS
Representative Name:	BOBBY STOVALL

7-ELEVEN 21884 (Continued) **U003103746**

Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	STE 150
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	26896
UST ID:	214398
NOC ID:	Not reported
AI Number:	7174
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	26895
UST ID:	214397
NOC ID:	Not reported
AI Number:	7174
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	McCon Build & Petro.
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	2781
UST ID:	Not reported
NOC ID:	2518
AI Number:	7174
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING & PETROLEUM SVCS
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	8120 JETSTAR DR
Mailing Address (Internal Delivery):	STE 150
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42059
UST ID:	214397
NOC ID:	Not reported
AI Number:	7174
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	42060
UST ID:	214398

7-ELEVEN 21884 (Continued) **U003103746**

NOC ID:	Not reported
AI Number:	7174
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP002181
Company Name:	Not reported
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2783
UST ID:	Not reported
NOC ID:	2518
AI Number:	7174
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	2786
UST ID:	Not reported
NOC ID:	2519
AI Number:	7174
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46176
Additional ID:	781158282002117
Princ ID:	959578622001257
AI Number:	7174
Facility Name:	7-ELEVEN 21884
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	1143
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

TX Financial Assurance 2:

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	278704
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	261553
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	242260
AI:	7174
Mechanism Type Other:	Not reported

7-ELEVEN 21884 (Continued) **U003103746**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	223523
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	224123
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO

7-ELEVEN 21884 (Continued) **U003103746**

Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	207932
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	189240
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD

7-ELEVEN 21884 (Continued) **U003103746**

City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	172745
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	154053
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	138249
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN 21884 (Continued) **U003103746**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	120382
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	2247
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000

7-ELEVEN 21884 (Continued) **U003103746**

Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	28804
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	28805
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST G2379486A 005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176

7-ELEVEN 21884 (Continued) **U003103746**

Finass ID:	28806
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	28807
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 21884
Address:	917 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	46176
Finass ID:	28808
AI:	7174
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN 21884 (Continued) **U003103746**

Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

3036 **TX HIST UST** **S128729516**
WNW **1107 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.200 mi.
1054 ft.

Actual:
476 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	Not reported
Address:	1107 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	N0066
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SI3037 **MURPHY USA #6967** **TX HIST UST** **S128728711**
ESE **13000 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.200 mi.
1055 ft. **Site 1 of 3 in cluster SI**

Actual:
741 ft.

Focus Map:
2

HIST UST AUSTIN:

Name:	MURPHY USA #6967
Address:	13000 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	3282
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RM3038 **WALKER TIRE CO.** **TX HIST UST** **S128729020**
NE **814 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.200 mi.
1058 ft. **Site 7 of 7 in cluster RM**

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	WALKER TIRE CO.
Address:	814 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0391
HID UST:	Not reported
Inspection:	Not reported

WALKER TIRE CO. (Continued) **S128729020**

Due: Not reported

3039 NW 1/8-1/4 0.202 mi. 1065 ft. **NATIONAL TIRE & BATTERY #8688** **8002 RESEARCH BLVD** **AUSTIN, TX 78758** **RCRA-VSQG** **1008375300** **TXR000063271**

Actual: 763 ft.

Focus Map: 6

RCRA Listings:

Date Form Received by Agency:	20190212
Handler Name:	National Tire & Battery #8688
Handler Address:	RESEARCH BLVD
Handler City,State,Zip:	AUSTIN, TX 78758
EPA ID:	TXR000063271
Contact Name:	AARON ENGI
Contact Address:	PROFESSIONAL CENTER DR.
Contact City,State,Zip:	PALM BEACH GARDENS, FL 33410
Contact Telephone:	561-383-3000
Contact Fax:	Not reported
Contact Email:	EHS@TBCCORP.COM
Contact Title:	SR., MGR. EHS
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PROFESSIONAL CENTER DR.
Mailing City,State,Zip:	PALM BEACH GARDENS, FL 33410
Owner Name:	Tire Kingdom
Owner Type:	Private
Operator Name:	Tire Kingdom
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

NATIONAL TIRE & BATTERY #8688 (Continued) **1008375300**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: TIRE KINGDOM	
Legal Status:	Private
Date Became Current:	20031130
Date Ended Current:	Not reported
Owner/Operator Address:	823 DONALD ROSS ROAD
Owner/Operator City,State,Zip:	JUNO BEACH, FL 33408
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NATIONAL TIRE & BATTERY #8688	
Legal Status:	Private
Date Became Current:	20051117
Date Ended Current:	Not reported
Owner/Operator Address:	4280 PROFESSIONAL CENTER DR.
Owner/Operator City,State,Zip:	PALM BEACH GARDENS, FL 33410
Owner/Operator Telephone:	561-383-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	EHS@TBCCORP.COM

NATIONAL TIRE & BATTERY #8688 (Continued) **1008375300**

Owner/Operator Indicator: Owner
Owner/Operator Name: TIRE KINGDOM
Legal Status: Private
Date Became Current: 20031130
Date Ended Current: Not reported
Owner/Operator Address: 823 DONALD ROSS ROAD
Owner/Operator City,State,Zip: JUNO BEACH, FL 33408
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TIRE KINGDOM
Legal Status: Private
Date Became Current: 20031130
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TIRE KINGDOM
Legal Status: Private
Date Became Current: 20031130
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANDERSON SQUARE INVESTMENTS, LLC
Legal Status: Private
Date Became Current: 20051117
Date Ended Current: Not reported
Owner/Operator Address: 3839 BEE CAVE ROAD
Owner/Operator City,State,Zip: AUSTIN, TX 78746
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: EHS@TBCCORP.COM

Historic Generators:
Receive Date: 20050408
Handler Name: NTB NO 688
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

NATIONAL TIRE & BATTERY #8688 (Continued) **1008375300**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190212
Handler Name: NATIONAL TIRE & BATTERY #8688
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SJ3040 **AUSTIN GAS LIGHT COMPANY** **SEMS-ARCHIVE** **1003875386**
ESE **300 MEDINA STREET** **TXD981918162**
1/8-1/4 **AUSTIN, TX 78702**
0.202 mi.
1067 ft. **Site 1 of 3 in cluster SJ**

Actual:
468 ft.

Focus Map:
11

SEMS Archive:
Site ID: 0603536
EPA ID: TXD981918162
Name: AUSTIN GAS LIGHT COMPANY
Address: 300 MEDINA STREET
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78702
Cong District: 02
FIPS Code: 48453
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:
Region: 06
Site ID: 0603536
EPA ID: TXD981918162
Site Name: AUSTIN GAS LIGHT COMPANY
NPL: N
FF: N
OU: 00
Action Code: VS

AUSTIN GAS LIGHT COMPANY (Continued) **1003875386**

Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1987-06-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	06
Site ID:	0603536
EPA ID:	TXD981918162
Site Name:	AUSTIN GAS LIGHT COMPANY
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1987-03-01 05:00:00
Finish Date:	1987-03-01 05:00:00
Qual:	Not reported
Current Action Lead:	St Perf
Region:	06
Site ID:	0603536
EPA ID:	TXD981918162
Site Name:	AUSTIN GAS LIGHT COMPANY
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1987-06-01 04:00:00
Finish Date:	1987-06-01 04:00:00
Qual:	N
Current Action Lead:	St Perf

SK3041 **WAL-MART SUPERCENTER 3569** **RCRA-VSQG** **1010334148**
East **12900 12900 N INTERSTATE 35** **TXR000072363**
1/8-1/4 **AUSTIN, TX 78753**
0.203 mi.
1071 ft. **Site 1 of 3 in cluster SK**

Actual:
738 ft.

Focus Map:
2

RCRA Listings:

Date Form Received by Agency:	20220801
Handler Name:	Wal-Mart Supercenter 3569
Handler Address:	12900 N INTERSTATE 35
Handler City,State,Zip:	AUSTIN, TX 78753-1049
EPA ID:	TXR000072363
Contact Name:	ROSE ARNOLD
Contact Address:	PO BOX 8041
Contact City,State,Zip:	BENTONVILLE, AR 72712-2841
Contact Telephone:	479-277-8972
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 8041
Mailing City,State,Zip:	BENTONVILLE, AR 72712-2841
Owner Name:	Walmart Stores Texas Llc
Owner Type:	Private
Operator Name:	Walmart Stores Texas Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220823
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D022
Waste Description:	Chloroform
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	D026
Waste Description:	Cresol
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4’-(1,2-Diethyl-1,2-Ethenediyl)Bis, (E)-

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2’-Methylenebis[3,4,6-Trichloro-

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U182
Waste Description: 1,3,5-Trioxane, 2,4,6-Trimethyl- (Or) Paraldehyde

Waste Code: U188
Waste Description: Phenol

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U248
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenyl-Butyl)-, & Salts, When Present At Concentrations Of 0.3% Or Less (Or) Warfarin, & Salts, When Present At Concentrations Of 0.3% Or Less

Waste Code: U249
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Of 10% Or Less

Waste Code: U279
Waste Description: U279

Waste Code: U409
Waste Description: Carbamic Acid, [1,2-Phenylenebis (Iminocarbonothioyl)]Bis-, Dimethyl Ester (Or) Thiophanate-Methyl

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WAL-MART STORES TEXAS LLC,
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WAL-MART STORES TEXAS LP
Legal Status: Private
Date Became Current: 20031003
Date Ended Current: Not reported
Owner/Operator Address: 702 S W 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72716
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WAL-MART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20090217
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WAL-MART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20090217
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Owner/Operator Indicator: Operator
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WAL-MART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20090303
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WAL-MART STORES TEXAS LP
Legal Status: Private
Date Became Current: 20031003
Date Ended Current: Not reported
Owner/Operator Address: 702 S W 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72716
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WAL-MART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20090303
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WAL-MART STORES TEXAS LLC,
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALMART STORES TEXAS LLC
Legal Status: Private
Date Became Current: 20081224
Date Ended Current: Not reported
Owner/Operator Address: 1300 SE 8TH ST
Owner/Operator City,State,Zip: BENTONVILLE, AR 72712-6561
Owner/Operator Telephone: 479-204-2231
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060726
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090217
Handler Name: WAL-MART STORES TEXAS LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090303
Handler Name: WAL-MART STORES TEXAS LLC
Federal Waste Generator Description: Small Quantity Generator

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110126
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131216
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141218
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200410
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

WAL-MART SUPERCENTER 3569 (Continued) **1010334148**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20211209
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220801
Handler Name: WAL-MART SUPERCENTER 3569
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 452311
NAICS Description: WAREHOUSE CLUBS AND SUPERCENTERS

NAICS Code: 45291
NAICS Description: WAREHOUSE CLUBS AND SUPERCENTERS

NAICS Code: 455211
NAICS Description: WAREHOUSE CLUBS AND SUPERCENTERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SK3042 East 1/8-1/4 0.203 mi. 1071 ft. | **WAL-MART SUPERCENTER 3569**
12900 N INTERSTATE 35
AUSTIN, TX 78753

Site 2 of 3 in cluster SK

TX Ind. Haz Waste | **S109956171**
N/A

Actual: 738 ft.

Focus Map: 2

Ind. Haz Waste:

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N INTERSTATE 35
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	88692
Registration Initial Notification Date:	12/24/2008
Registration Last Amendment Date:	08/01/2022
EPA Identification:	TXR000072363
Primary NAICS Code:	455211
Status Change Date:	20081224
Land Type:	PRIVATE
Description of Facility Site Location:	12900 N INTERSTATE 35 AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	WAL-MART STORES TEXAS LLC
Contact Name:	ROSE ARNOLD
Contact Telephone Number:	479-2778972
Mailing Address:	PO BOX 8041
Mailing Address2:	Not reported
Mailing City,State,Zip:	BENTONVILLE, AR 727122841
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	123519
Site Owner Tax ID:	743019386
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220808
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	WAL-MART STORES TEXAS LLC
Operator Address:	1300 SE8TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	BENTONVILLE, AR 72712
Operator Country:	UNITED STA
Operator Telephone:	1-479-2042231
Operator Fax Number:	1-479-2775844
Operator Email:	teresa.pruitt@wal-mart.com
Operator Business Type:	Corporation
Operator Tax ID:	17430193866
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	WAL-MART STORES TEXAS LLC
Owner Mailing Address:	1300 SE8TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	BENTONVILLE, AR 72712
Owner Country:	UNITED STA
Owner Telephone:	1-479-2042231
Owner Fax:	1-479-2775844
Owner Email Address:	teresa.pruitt@wal-mart.com
Owner Business Type:	Corporation
Owner Tax ID:	17430193866
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	50
Capacity Measurement:	C
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Back room of store near the claim’s processing area.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1300 SE8TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BENTONVILLE, AR 72712
Contact Phone:	1-479-2042231
Contact Fax:	1-479-2775844
Contact Email:	teresa.pruitt@wal-mart.com

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1300 SE8TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BENTONVILLE, AR 72712
Contact Phone:	1-479-2042231
Contact Fax:	1-479-2775844
Contact Email:	teresa.pruitt@wal-mart.com

Contact Name:	ROSE ARNOLD
Contact Title:	SENIOR MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 8041
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	BENTONVILLE, AR 72712
Contact Phone:	1-479-2778972
Contact Fax:	1-479-2049675
Contact Email:	ROSE.ARNOLD@WALMART.COM

Ind. Haz Waste:

Waste ID:	230366
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable solids 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230367
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002801H
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aerosols 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230368
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corrosive liquids 1/1/2008

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230370
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Flammable liquids 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230372
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005801H
Waste Code Status:	ACTIVE
Waste Form:	801

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lighters 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230374
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oxidizing solids 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230377
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007801H
Waste Code Status:	INACTIVE
Waste Form:	801
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Propane cylinders 1/1/2008; Due to change(s) in the product produced, thiswaste

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W801
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230379
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008409H
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic solids 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Ind. Haz Waste:

Waste ID:	230381
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Toxic liquids 1/1/2008
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	230384
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010319H

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Corrosive solids 1/1/2008; Due to waste minimization, ingredient changes orproce
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	452910
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	SOURCE REDUCTIO

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	250194
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	P-LISTED WASTE PHARMACEUTICALS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	P-LISTED WASTE PHARM
Primary NAICS Code:	452910
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	250195
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012219H
Waste Code Status:	ACTIVE
Waste Form:	219

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	FLAMMABLE WASTE PHARMACEUTICALS
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FLAMMABLE WASTE PHAR
Primary NAICS Code:	452910
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	250196
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013210H
Waste Code Status:	ACTIVE
Waste Form:	210
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ORGANIC PEROXIDES
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ORGANIC PEROXIDES
Primary NAICS Code:	452910
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	250197
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	OXIDIZING LIQUIDS

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	OXIDIZING LIQUIDS
Primary NAICS Code:	452910
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	358219
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	P-LISTED WASTE-NICOTINE
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	P-LISTED WASTE-NICOT
Primary NAICS Code:	452910
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

WAL-MART SUPERCENTER 3569 (Continued) **S109956171**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1300 SE 8TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BENTONVILLE, AR 72712
AR Number:	0000315920
Principal Name:	WAL-MART STORES TEXAS LLC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1300 SE 8TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BENTONVILLE, AR 72712
AR Number:	0000315920
Principal Name:	WAL-MART STORES TEXAS LLC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1300 SE 8TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BENTONVILLE, AR 72712
AR Number:	0000315920
Principal Name:	WAL-MART STORES TEXAS LLC
Attention Name:	Not reported
Attention Suffix:	HWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	0-0-0 x0
Mailing Address:	1300 SE 8TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BENTONVILLE, AR 72712
AR Number:	0000315920
Principal Name:	WAL-MART STORES TEXAS LLC
Attention Name:	Not reported
Attention Suffix:	NWG

RX3043 **SOUTHLAND ICE CO.** **TX HIST UST** **S111678808**
NE **612 E 9TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.203 mi.
1073 ft. **Site 4 of 4 in cluster RX**

Actual:
475 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SOUTHLAND ICE CO.
Address:	612 E 9TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0383

SOUTHLAND ICE CO. (Continued) **S111678808**

HID UST:	383
Inspection:	Not reported
Due:	06/01/2012

3044 NE 1/8-1/4 0.205 mi. 1080 ft. **AIRPORT FAST PARK 2300 SPIRIT OF TEXAS DR DEL VALLE, TX 78617** **TX AST** **A100299328 N/A**

Actual: 499 ft.

Focus Map: 20

AST:

Name:	AIRPORT FAST PARK
Address:	2300 SPIRIT OF TEXAS DR
City,State,Zip:	DEL VALLE, TX 786172286
Facility ID:	120449
Additional ID:	812663052006234
AI Number:	78145
Facility Type:	FLEET REFUELING
Facility Begin Date:	07/28/2006
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78617
Contact Name/Title:	/
Contact Organization Name:	AIRPORT FAST PARK
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5123858877
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	06/09/2006
Signature First Name on Earliest Reg Form:	MANUEL
Application Received Date on Earliest Reg Form:	08/14/2006
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	CHAVEZ
Signature Title on Earliest Reg Form:	MGR
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	120449
Tank ID:	1
AST ID:	207097
AI Number:	78145

AIRPORT FAST PARK (Continued) **A100299328**

Install Date:	07/28/2006
Tank Registration Date:	08/14/2006
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	07/28/2006
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

SL3045 **NALTEX** **TX HIST UST** **S128729074**
ESE **220 E ST ELMO RD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.205 mi.
1084 ft. **Site 1 of 4 in cluster SL**

Actual:
658 ft.

Focus Map:
18

HIST UST AUSTIN:

Name:	NALTEX
Address:	220 E ST ELMO RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0564
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SL3046 **DELSTAR TECHNOLOGIES** **RCRA-SQG** **1000992436**
ESE **220 E SAINT ELMO RD** **FINDS** **TXR000003426**
1/8-1/4 **AUSTIN, TX 78745** **ECHO**
0.205 mi. **TX Ind. Haz Waste**
1084 ft. **Site 2 of 4 in cluster SL**

Actual:
658 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20160125
Handler Name:	Delstar Technologies Austin
Handler Address:	220 E SAINT ELMO RD
Handler City,State,Zip:	AUSTIN, TX 78745-1218
EPA ID:	TXR000003426
Contact Name:	DAVID CARLIN
Contact Address:	220 E SAINT ELMO RD
Contact City,State,Zip:	AUSTIN, TX 78745-1218
Contact Telephone:	512-447-7000
Contact Fax:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	220 E SAINT ELMO RD
Mailing City,State,Zip:	AUSTIN, TX 78745-1218
Owner Name:	Delstar Technologies Inc
Owner Type:	Private
Operator Name:	Delstar Technologies Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DELSTAR TECHNOLOGIES INC	
Legal Status:	Private
Date Became Current:	20040309
Date Ended Current:	Not reported
Owner/Operator Address:	220 E ST ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745
Owner/Operator Telephone:	512-447-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: DELSTAR TECHNOLOGIES INC	
Legal Status:	Private
Date Became Current:	20030730
Date Ended Current:	Not reported
Owner/Operator Address:	220 E SAINT ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745-1218
Owner/Operator Telephone:	512-447-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: DELSTAR TECHNOLOGIES INC	
Legal Status:	Private
Date Became Current:	20030730
Date Ended Current:	Not reported
Owner/Operator Address:	220 E SAINT ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745-1218
Owner/Operator Telephone:	512-447-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HOWARD KONIEG	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	220 E ST ELMO RD
Owner/Operator City,State,Zip:	AUSTIN, TX 78745-1218
Owner/Operator Telephone:	512-447-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Owner/Operator Indicator: Owner
Owner/Operator Name: DELSTAR TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20030730
Date Ended Current: Not reported
Owner/Operator Address: 220 E SAINT ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1218
Owner/Operator Telephone: 512-447-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DELSTAR TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20090505
Date Ended Current: Not reported
Owner/Operator Address: 220 E ST ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-447-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DELSTAR TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20090505
Date Ended Current: Not reported
Owner/Operator Address: 220 E ST ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-447-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DELSTAR TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20040309
Date Ended Current: Not reported
Owner/Operator Address: 220 E ST ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745
Owner/Operator Telephone: 512-447-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DELSTAR TECHNOLOGIES INC
Legal Status: Private
Date Became Current: 20030730
Date Ended Current: Not reported
Owner/Operator Address: 220 E SAINT ELMO RD
Owner/Operator City,State,Zip: AUSTIN, TX 78745-1218
Owner/Operator Telephone: 512-447-7000
Owner/Operator Telephone Ext: Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20000626
Handler Name: US NETTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040309
Handler Name: DELSTAR TECHNOLOGIES INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090505
Handler Name: DELSTAR TECHNOLOGIES INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140129
Handler Name: DELSTAR TECHNOLOGIES AUSTIN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160125

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Handler Name: DELSTAR TECHNOLOGIES AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 326199
NAICS Description: ALL OTHER PLASTICS PRODUCT MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005164838

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000992436
Registry ID: 110005164838
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005164838
Name: DELSTAR TECHNOLOGIES
Address: 220 E SAINT ELMO RD
City,State,Zip: AUSTIN, TX 78745

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Ind. Haz Waste:

Name:	DELSTAR TECHNOLOGIES AUSTIN
Address:	220 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	23102
Registration Initial Notification Date:	10/19/1992
Registration Last Amendment Date:	01/25/2018
EPA Identification:	TXR000003426
Primary NAICS Code:	326199
Status Change Date:	20181214
Land Type:	PRIVATE
Description of Facility Site Location:	220 E St Elmo Rd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	US NETTING INC
Contact Name:	DAVID CARLIN
Contact Telephone Number:	512-4477000
Mailing Address:	220 E SAINT ELMO RD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787451218
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	7295
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20181214
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	US NETTING INC
Operator Address:	220 E SAINT ELMO RD
Operator Address 2:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78745
Operator Country:	UNITED STA
Operator Telephone:	1-512-4477000
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17602244349
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	US NETTING INC
Owner Mailing Address:	220 E SAINT ELMO RD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78745
Owner Country:	UNITED STA
Owner Telephone:	1-512-4477000
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17602244349
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	220 E SAINT ELMO RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4477000
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	DAVID CARLIN
Contact Title:	MAINTENANCE MANAGER
Contact Role:	PRICONT
Contact Address:	220 E SAINT ELMO RD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	1-512-4477000
Contact Fax:	Not reported
Contact Email:	bmees@delstarinc.com

Ind. Haz Waste:

Waste ID:	131387
Texas Waste Code:	Not reported
Texas Waste Code 2:	00022051
Waste Code Status:	INACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Generators Waste Description:	Cooling oil for a metal grinder. The waste is a mixture of water soluble oil an
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	131386
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003315H
Waste Code Status:	INACTIVE
Waste Form:	315
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent caustic solid containing sodium nitrate, potassium hydroxide and dissolved
Standard Industrial Code:	30890
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	326199
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	WASTE DELISTED

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	141494
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Parts washer. Generation is continuous from 8/95
Standard Industrial Code:	30890
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	326199
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	296497
Texas Waste Code:	Not reported
Texas Waste Code 2:	D39K2051
Waste Code Status:	Not reported
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	296498
Texas Waste Code:	Not reported
Texas Waste Code 2:	D39L315H
Waste Code Status:	Not reported
Waste Form:	315
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Ind. Haz Waste:

Waste ID:	296499
Texas Waste Code:	Not reported
Texas Waste Code 2:	D39M4062
Waste Code Status:	Not reported
Waste Form:	406
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	296500
Texas Waste Code:	Not reported
Texas Waste Code 2:	D39N206H
Waste Code Status:	Not reported
Waste Form:	206
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	220 E SAINT ELMO RD
Mailing Address 2:	Not reported

DELSTAR TECHNOLOGIES (Continued) **1000992436**

Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000312339
Principal Name:	US NETTING INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	220 E SAINT ELMO RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78745
AR Number:	0000312339
Principal Name:	US NETTING INC
Attention Name:	Not reported
Attention Suffix:	NWG

SL3047 **220 EAST ST ELMO ROAD** **TX IHW CORR ACTION** **S122004982**
ESE **220 E SAINT ELMO RD** **TX COMP HIST** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.205 mi.
1084 ft. **Site 3 of 4 in cluster SL**

Actual:
658 ft.

Focus Map:
18

IHW CORR ACTION:

Name:	220 EAST ST ELMO ROAD
Address:	220 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745
Program Id:	T3648
Location Desc:	220 E ST ELMO RD AUSTIN TX
RN NUM:	RN100665652
Status:	INACTIVE
Status Date:	02/04/2021
EDR Link ID:	T3648
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	02/04/2021
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

COMP HIST:

RN Number:	RN100665652
Name:	NALTEX
Address:	220 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745-1218
Region:	REGION 11 - AUSTIN
CN Number:	CN600373906
CN Name:	US NETTING INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022

220 EAST ST ELMO ROAD (Continued) **S122004982**

NAICS Code:	326199
SIC Code:	4231
Related Number:	TXR000003426,TH0567A,P09735,P09735

RN Number:	RN100665652
Name:	NALTEX
Address:	220 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745-1218
Region:	REGION 11 - AUSTIN
CN Number:	CN603800756
CN Name:	US NETTING INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	326199
SIC Code:	4231
Related Number:	TXR000003426,TH0567A,P09735,P09735

RN Number:	RN100665652
Name:	NALTEX
Address:	220 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745-1218
Region:	REGION 11 - AUSTIN
CN Number:	CN605849504
CN Name:	UNGAR BROTHERS LLC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	326199
SIC Code:	6513
Related Number:	TXR000003426,TH0567A,P09735,P09735

3048 **CIRCLE K 3213** **TX UST** **U001269406**
ESE **6812 AIRPORT BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.206 mi.
1090 ft.

Actual:
704 ft.

Focus Map:
6

UST:

Name:	CIRCLE K 3213
Address:	6812 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 787523613
AI Number:	36539
Facility Type:	RETAIL
Facility Begin Date:	12/22/1986
Facility Status:	INACTIVE
Additional ID:	647577282002117
Facility Exempt Status:	N

CIRCLE K 3213 (Continued) **U001269406**

Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78723
Contact Name/Title:	B SAXON,DIST. MGR.
Contact Organization Name:	CIRCLE K 3213
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123398836
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	D ESPERSON,GAS. FACIL. MGR.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600134456
Owner Last Name:	CIRCLE K STORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	658325792001221
Additional ID:	647577282002117
AI Number:	36539
Owner Effective Begin Date:	05/08/1986
State Tax ID:	17411495405
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N

CIRCLE K 3213 (Continued) **U001269406**

Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96620
Facility ID:	44044
Ai Number:	36539
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

CIRCLE K 3213 (Continued) **U001269406**

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	17993
UST ID:	96620
AI Number:	36539
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	96621
Facility ID:	44044
Ai Number:	36539
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1988

CIRCLE K 3213 (Continued) **U001269406**

Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	11/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	17994
UST ID:	96621
AI Number:	36539
Compartment ID:	A
Substance Stored1:	GASOLINE

CIRCLE K 3213 (Continued) **U001269406**

Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PHOENIX, AZ 85072 2085
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	44044
Additional ID:	647577282002117
Princ ID:	658325792001221
AI Number:	36539
Facility Name:	CIRCLE K 3213
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BERLIN ANDERSON/

3049 WNW 1/8-1/4 0.207 mi. 1094 ft. | **AUSTIN NEURO DIAGNOSTICS**
1111 W 34TH STREET
AUSTIN, TX 78705

RCRA NonGen / NLR
FINDS
ECHO
TX Ind. Haz Waste
TX CENTRAL REGISTRY

1000412167
TXD030930705

Actual: 576 ft.

Focus Map: 8

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Neuro Diagnostics
Handler Address:	W 34TH STREET
Handler City,State,Zip:	AUSTIN, TX 78705
EPA ID:	TXD030930705
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	W 34TH
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W 34TH
Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Name:	Austin Neuro Diagnostics
Owner Type:	Private
Operator Name:	Austin Neuro Diagnostics
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P098

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U093
Waste Description: Benzenamine, N,N-Dimethyl-4-(Phenylazo)- (Or) P-Dimethylaminoazobenzene

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U194
Waste Description: 1-Propanamine (I,T) (Or) N-Propylamine (I,T)

Waste Code: U219
Waste Description: Thiourea

Waste Code: U222
Waste Description: Benzenamine, 2-Methyl-, Hydrochloride (Or) O-Toluidine Hydrochloride

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN NEURO DIAGNOSTICS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1111 W 34TH STREET SUITE 208
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-458-2291
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN NEURO DIAGNOSTICS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1111 W 34TH STREET SUITE 208
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 512-458-2291
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Owner/Operator Name: AUSTIN NEURO DIAGNOSTICS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 1111 W 34TH
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN NEURO DIAGNOSTICS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 1111 W 34TH
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800818
Handler Name: AUSTIN NEURO DIAGNOSTICS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: AUSTIN NEURO DIAGNOSTICS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 621511
NAICS Description: MEDICAL LABORATORIES

Facility Has Received Notices of Violations:
Violations: No Violations Found

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005046119

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412167
Registry ID:	110005046119
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005046119
Name:	AUSTIN NEURO DIAGNOSTICS
Address:	1111 W 34TH STREET
City,State,Zip:	AUSTIN, TX 78705

Ind. Haz Waste:

Name:	AUSTIN NEURO DIAGNOSTICS
Address:	1111 W 34TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	66008
Registration Initial Notification Date:	08/23/2001
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD030930705
Primary NAICS Code:	Not reported
Status Change Date:	20010823
Land Type:	PRIVATE
Description of Facility Site Location:	1111 W 34th Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN NEURO DIAGNOSTICS
Contact Name:	Not reported
Contact Telephone Number:	Not reported

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Mailing Address:	1111 W 34TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787051900
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21315
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030709
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN NEURO DIAGNOSTICS
Operator Address:	1111 W 34TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78705
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN NEURO DIAGNOSTICS
Owner Mailing Address:	1111 W 34TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78705
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1111 W 34TH ST

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1111 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1111 W 34TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100692508
Name:	AUSTIN NEURO DIAGNOSTICS
Address:	1111 W 34TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1900
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600398937
Customer Name:	AUSTIN NEURO DIAGNOSTICS
Customer Legal Name:	Austin Neuro Diagnostics
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1111 W 34th Street, Austin, TX

Regulated Entity Number:	RN100692508
Name:	AUSTIN NEURO DIAGNOSTICS
Address:	1111 W 34TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78705-1900
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600398937

AUSTIN NEURO DIAGNOSTICS (Continued) **1000412167**

Customer Name:	AUSTIN NEURO DIAGNOSTICS
Customer Legal Name:	Austin Neuro Diagnostics
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1111 W 34th Street, Austin, TX

SM3050 **ASCENSION SETON MEDICAL CENTER AUSTIN** **RCRA-SQG** **1000337148**
WNW **1201 W 38TH STREET** **TX SWF/LF** **TXD078495868**
1/8-1/4 **AUSTIN, TX 78705** **TX LPST**
0.208 mi. **TX UST**
1098 ft. **Site 1 of 3 in cluster SM** **FINDS**
ECHO
Actual: **TX AIRS**
597 ft. **TX ASBESTOS**
Focus Map: **TX Financial Assurance**
8 **TX Ind. Haz Waste**
WI MANIFEST
TX COMP HIST

RCRA Listings:

Date Form Received by Agency:	20221117
Handler Name:	Ascension Seton Medical Center Austin
Handler Address:	W 38TH ST
Handler City,State,Zip:	AUSTIN, TX 78705-1006
EPA ID:	TXD078495868
Contact Name:	KERI JONES
Contact Address:	W 38TH ST
Contact City,State,Zip:	AUSTIN, TX 78705-1006
Contact Telephone:	409-728-5444
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	W 38TH ST
Mailing City,State,Zip:	AUSTIN, TX 78705-1006
Owner Name:	Ascension Seton
Owner Type:	Private
Operator Name:	Ascension Seton
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221130
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D012
Waste Description: Endrin (1,2,3,4,10,10-Hexachloro-1,7-Epoxy-1,4,4a,5,6,7,8,8a-Octahydro-1,4-Endo, Endo-5,8-Dimeth-Ano-Naphthalene)

Waste Code: D013
Waste Description: Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)

Waste Code: D014
Waste Description: Methoxychlor (1,1,1-Trichloro-2,2-Bis [P-Methoxyphenyl] Ethane)

Waste Code: D015
Waste Description: Toxaphene (C10 H10 Cl8, Technical Chlorinated Camphene, 67-69 Percent Chlorine)

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D017
Waste Description: 2,4,5-Tp Silvex (2,4,5-Trichlorophenoxypropionic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D019
Waste Description: Carbon Tetrachloride

Waste Code: D020
Waste Description: Chlordane

Waste Code: D021
Waste Description: Chlorobenzene

Waste Code: D022
Waste Description: Chloroform

Waste Code: D023

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: O-Cresol

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D025
Waste Description: P-Cresol

Waste Code: D026
Waste Description: Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D028
Waste Description: 1,2-Dichloroethane

Waste Code: D029
Waste Description: 1,1-Dichloroethylene

Waste Code: D030
Waste Description: 2,4-Dinitrotoluene

Waste Code: D031
Waste Description: Heptachlor (And Its Epoxide)

Waste Code: D032
Waste Description: Hexachlorobenzene

Waste Code: D033
Waste Description: Hexachlorobutadiene

Waste Code: D034
Waste Description: Hexachloroethane

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D036
Waste Description: Nitrobenzene

Waste Code: D037
Waste Description: Pentachlorophenol

Waste Code: D038
Waste Description: Pyridine

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D041
Waste Description: 2,4,5-Trichlorophenol

Waste Code: D042

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: 2,4,6-Trichlorophenol

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F006

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: Wastewater Treatment Sludges From Electroplating Operations, Except From The Following Processes: (1) Sulfuric Acid Anodizing Of Aluminum; (2) Tin Plating On Carbon Steel; (3) Zinc Plating (Segregated Basis) On Carbon Steel; (4) Aluminum Or Zinc-Aluminum Plating On Carbon Steel; (5) Cleaning/Stripping Associated With Tin, Zinc, And Aluminum Plating On Carbon Steel; And (6) Chemical Etching And Milling Of Aluminum.

Waste Code: F007
Waste Description: Spent Cyanide Plating Bath Solutions From Electroplating Operations.

Waste Code: F008
Waste Description: Plating Bath Residues From The Bottom Of Plating Baths From Electroplating Operations In Which Cyanides Are Used In The Process.

Waste Code: F009
Waste Description: Spent Stripping And Cleaning Bath Solutions From Electroplating Operations In Which Cyanides Are Used In The Process.

Waste Code: F010
Waste Description: Quenching Bath Residues From Oil Baths From Metal Heat Treating Operations In Which Cyanides Are Used In The Process.

Waste Code: F011
Waste Description: Spent Cyanide Solutions From Slat Bath Pot Cleaning From Metal Heat Treating Operations.

Waste Code: F012
Waste Description: Quenching Wastewater Treatment Sludges From Metal Heat Treating Operations In Which Cyanides Are Used In The Process.

Waste Code: F019
Waste Description: Wastewater Treatment Sludges From The Chemical Conversion Coating Of Aluminum, Except From Zirconium Phosphating In Aluminum Can Washing When Such Phosphating Is An Exclusive Conversion Coating Process.

Waste Code: F020
Waste Description: Wastes (Except Wastewater And Spent Carbon From Hydrogen Chloride Purification) From The Production Or Manufacturing Use (As A Reactant, Chemical Intermediate, Or Component In A Formulating Process) Of Tri- Or Tetrachlorophenol Or Of Intermediates Used To Produce Their Pesticide Derivatives. (This Listing Does Not Include Wastes From The Production Of Hexachlorophene From Highly Purified 2,4,5-Trichlorophenol.)

Waste Code: F021
Waste Description: Wastes (Except Wastewater And Spent Carbon From Hydrogen Chloride Purification) From The Production Or Manufacturing Use (As A Reactant, Chemical Intermediate, Or Component In A Formulating Process) Of Pentachlorophenol, Or Of Intermediates Used To Produce Derivatives.

Waste Code: F022
Waste Description: Wastes (Except Wastewater And Spent Carbon From Hydrogen Chloride Purification) From The Manufacturing Use (As A Reactant, Chemical Intermediate, Or Component In A Formulating Process) Of Tetra-, Penta-, Or Hexachlorobenzenes Under Alkaline Conditions.

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: F023
Waste Description: Wastes (Except Wastewater And Spent Carbon From Hydrogen Chloride Purification) From The Production Of Materials On Equipment Previously Used For The Production Or Manufacturing Use (As A Reactant, Chemical Intermediate, Or Component In A Formulating Process) Of Tri- And Tetrachlorophenols. (This Listing Does Not Include Wastes From Equipment Used Only For The Production Or Use Of Hexachlorophene From Highly Purified 2,4,5-Trichlorophenol.)

Waste Code: F024
Waste Description: Process Wastes Including, But Not Limited To, Distillation Residues, Heavy Ends, Tars, And Reactor Clean-Out Wastes From The Production Of Certain Chlorinated Aliphatic Hydrocarbons By Free Radical Catalyzed Processes. These Chlorinated Aliphatic Hydrocarbons Are Those Having Carbon Chain Lengths Ranging From One To, And Including Five, With Varying Amounts And Positions Of Chlorine Substitution. (This Listing Does Not Include Wastewaters, Wastewater Treatment Sludge, Spent Catalysts, And Wastes Listed In Sections 261.31. Or 261.32)

Waste Code: F025
Waste Description: Condensed Light Ends, Spent Filters And Filter Aids, And Spent Desiccant Wastes From The Production Of Certain Chlorinated Aliphatic Hydrocarbons By Free Radical Catalyzed Processes. These Chlorinated Aliphatic Hydrocarbons Are Those Having Carbon Chain Lengths Ranging From One To, And Including Five, With Varying Amounts And Positions Of Chlorine Substitution.

Waste Code: F026
Waste Description: Wastes (Except Wastewater And Spent Carbon From Hydrogen Chloride Purification) From The Production Of Materials On Equipment Previously Used For The Manufacturing Use (As A Reactant, Chemical Intermediate, Or Component In A Formulating Process) Of Tetra-, Penta-, Or Hexachlorobenzene Under Alkaline Conditions.

Waste Code: F027
Waste Description: Discarded Unused Formulations Containing Tri-, Tetra-, Or Pentachlorophenol Or Discarded Unused Formulations Containing Compounds Derived From These Chlorophenols. (This Listing Does Not Include Formulations Containing Hexachlorophene Synthesized From Prepurified 2,4,5-Trichlorophenol As The Sole Component.)

Waste Code: F028
Waste Description: Residues Resulting From The Incineration Or Thermal Treatment Of Soil Contaminated With Epa Hazardous Waste Nos. F020, F021, F022, F023, F026, And F027.

Waste Code: F032
Waste Description: Wastewaters, Process Residuals, Preservative Drippage, And Spent Formulations From Wood Preserving Processes Generated At Plants That Currently Use, Or Have Previously Used, Chlorophenolic Formulations [Except Potentially Cross-Contaminated Wastes That Have Had The F032 Waste Code Deleted In Accordance With Section 261.35 (I.E., The Newly Promulgated Equipment Cleaning Or Replacement Standards), And Where The Generator Does Not Resume Or Initiate Use Of Chlorophenolic Formulations]. (This Listing Does Not Include K001 Bottom Sediment Sludge From The Treatment Of Wastewater From Wood Preserving Processes That Use Creosote And/Or Pentachlorophenol.)

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: F034
Waste Description: Wastewaters, Process Residuals, Preservative Drippage, And Spent Formulations From Wood Preserving Processes Generated At Plants That Use Creosote Formulations. This Listing Does Not Include K001 Bottom Sediment Sludge From The Treatment Of Wastewater From Wood Preserving Processes That Use Creosote And/Or Pentachlorophenol.

Waste Code: F035
Waste Description: Wastewaters, Process Residuals, Preservative Drippage, And Spent Formulations From Wood Preserving Processes Generated At Plants That Use Inorganic Preservatives Containing Arsenic Or Chromium. This Listing Does Not Include K001 Bottom Sediment Sludge From The Treatment Of Wastewater From Wood Preserving Processes That Use Creosote And/Or Pentachlorophenol.

Waste Code: F037
Waste Description: Petroleum Refinery Primary Oil/Water/Solids Separation Sludge - Any Sludge Generated From The Gravitational Separation Of Oil/Water/Solids During The Storage Or Treatment Of Process Wastewaters And Oily Cooling Wastewaters From Petroleum Refineries. Such Sludges Include, But Are Not Limited To, Those Generated In Oil/Water/Solids Separators; Tanks And Impoundments; Ditches And Other Conveyances; Sumps; And Storm Water Units Receiving Dry Weather Flow. Sludges Generated In Storm Water Units That Do Not Receive Dry Weather Flow, Sludges Generated In Aggressive Biological Treatment Units As Defined In Section 261.31(B)(2) (Including Sludges Generated In One Or More Additional Units After Wastewaters Have Been Treated In Aggressive Biological Treatment Units), And K051 Wastes Are Exempted From This Listing.

Waste Code: F038
Waste Description: Petroleum Refinery Secondary (Emulsified) Oil/Water/Solids Separation Sludge - Any Sludge And/Or Float Generated From The Physical And/Or Chemical Separation Of Oil/Water/Solids In Process Wastewaters And Oily Cooling Wastewaters From Petroleum Refineries. Such Wastes Include, But Are Not Limited To, All Sludges And Floats Generated In Induced Air Flotation (Iaf) Units, Tanks And Impoundments, And All Sludges Generated In Daf Units. Sludges Generated In Stormwater Units That Do Not Receive Dry Weather Flow, Sludges Generated In Aggressive Biological Treatment Units As Defined In Section 261.31(B)(2) (Including Sludges Generated In One Or More Additional Units After Wastewaters Have Been Treated In Aggressive Biological Treatment Units), And F037, K048, And K051 Wastes Are Exempted From This Listing.

Waste Code: F039
Waste Description: Leachate Resulting From The Treatment, Storage, Or Disposal Of Wastes Classified By More Than One Waste Code Under Subpart D, Or From A Mixture Of Wastes Classified Under Subparts C And D Of This Part. (Leachate Resulting From The Management Of One Or More Of The Following Epa Hazardous Wastes And No Other Hazardous Wastes Retains Its Hazardous Waste Code(S): F020, F021, F022, F023, F026, F027, And/Or F028.)

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, &

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P002
Waste Description: 1-Acetyl-2-Thiourea (Or) Acetamide, N-(Aminothioxomethyl)-

Waste Code: P003
Waste Description: 2-Propenal (Or) Acrolein

Waste Code: P004
Waste Description: 1,4,5,8-Dimethanonaphthalene, 1,2,3,4,10,10-Hexa-Chloro-1,4,4a,5,8,8a,-Hexahydro-, (1alpha, 4alpha, 4abeta, 5alpha, 8alpha, 8abeta)- (Or) Aldrin

Waste Code: P005
Waste Description: 2-Propen-1-Ol (Or) Allyl Alcohol

Waste Code: P006
Waste Description: Aluminum Phosphide (R,T)

Waste Code: P007
Waste Description: 3(2h)-Isoxazolone, 5-(Aminomethyl)- (Or) 5-(Aminomethyl)-3-Isoxazolol

Waste Code: P008
Waste Description: 4-Aminopyridine (Or) 4-Pyridinamine

Waste Code: P009
Waste Description: Ammonium Picrate (R) (Or) Phenol, 2,4,6-Trinitro-, Ammonium Salt (R)

Waste Code: P010
Waste Description: Arsenic Acid H3aso4

Waste Code: P011
Waste Description: Arsenic Oxide As2o5 (Or) Arsenic Pentoxide

Waste Code: P012
Waste Description: Arsenic Oxide As2o3 (Or) Arsenic Trioxide

Waste Code: P013
Waste Description: Barium Cyanide

Waste Code: P014
Waste Description: Benzenethiol (Or) Thiophenol

Waste Code: P015
Waste Description: Beryllium

Waste Code: P016
Waste Description: Dichloromethyl Ether (Or) Methane, Oxybis[Chloro-

Waste Code: P017
Waste Description: 2-Propanone, 1-Bromo- (Or) Bromoacetone

Waste Code: P018
Waste Description: Brucine (Or) Strychnidin-10-One, 2,3-Dimethoxy-

Waste Code: P020
Waste Description: Dinoseb (Or) Phenol, 2-(1-Methylpropyl)-4,6-Dinitro-

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: P021
Waste Description: Calcium Cyanide (Or) Calcium Cyanide Ca(Cn)2

Waste Code: P022
Waste Description: Carbon Disulfide

Waste Code: P023
Waste Description: Acetaldehyde, Chloro- (Or) Chloroacetaldehyde

Waste Code: P024
Waste Description: Benzenamine, 4-Chloro- (Or) P-Chloraniline

Waste Code: P026
Waste Description: 1-(O-Chlorophenyl)Thiourea (Or) Thiourea, (2-Chlorophenyl)-

Waste Code: P027
Waste Description: 3-Chloropropionitrile (Or) Propanenitrile, 3-Chloro-

Waste Code: P028
Waste Description: Benzene, (Chloromethyl)- (Or) Benzyl Chloride

Waste Code: P029
Waste Description: Copper Cyanide (Or) Copper Cyanide Cu(Cn)

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P031
Waste Description: Cyanogen (Or) Ethanedinitrile

Waste Code: P033
Waste Description: Cyanogen Chloride (Or) Cyanogen Chloride (Cn)Cl

Waste Code: P034
Waste Description: 2-Cyclohexyl-4,6-Dinitrophenol (Or) Phenol, 2-Cyclohexyl-4,6-Dinitro-

Waste Code: P036
Waste Description: Arsonous Dichloride, Phenyl- (Or) Dichlorophenylarsine

Waste Code: P037
Waste Description: 2,7:3,6-Dimethanonaphth[2,3-B]Oxirene, 3,4,5,6,9,9-Hexachloro-1a,2,2a,3,6,6a,7,7a-Octahydro-, (1aalpha, 2beta, 2aalpha, 3beta, 6beta, 6aalpha, 7beta, 7aalpha)- (Or) Dieldrin

Waste Code: P038
Waste Description: Arsine, Diethyl- (Or) Diethylarsine

Waste Code: P039
Waste Description: Disulfoton (Or) Phosphorodithioic Acid, O,O-Diethyl S-[2-(Ethylthio)Ethyl] Ester

Waste Code: P040
Waste Description: O,O-Diethyl O-Pyrazinyl Phosphorothioate (Or) Phosphorothioic Acid, O,O-Diethyl O-Pyrazinyl Ester

Waste Code: P041
Waste Description: Diethyl-P-Nitrophenyl Phosphate (Or) Phosphoric Acid, Diethyl

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

4-Nitrophenyl Ester

Waste Code: P042
Waste Description: 1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine

Waste Code: P043
Waste Description: Diisopropylfluorophosphate (Dfp) (Or) Phosphorofluoridic Acid, Bis(1-Methylethyl) Ester

Waste Code: P044
Waste Description: Dimethoate (Or) Phosphorodithioic Acid, O,O-Dimethyl S-[2-(Methylamino)-2-Oxoethyl] Ester

Waste Code: P045
Waste Description: 2-Butanone, 3,3-Dimethyl-1-(Methylthio)-, O-[Methylamino)Carbonyl] Oxime (Or) Thiofanox

Waste Code: P046
Waste Description: Alpha,Alpha-Dimethylphenethylamine (Or) Benzeneethanamine, Alpha, Alpha-Dimethyl-

Waste Code: P047
Waste Description: 4,6-Dinitro-O-Cresol, & Salts (Or) Phenol, 2-Methyl-4,6-Dinitro-, & Salts

Waste Code: P048
Waste Description: 2,4-Dinitrophenol (Or) Phenol, 2,4-Dinitro-

Waste Code: P049
Waste Description: Dithiobiuret (Or) Thioimidodicarbonic Diamide [(H2n)C(S)]2nh

Waste Code: P050
Waste Description: 6,9-Methano-2,4,3-Benzodioxathiepin,6,7,8,9,10,10-Hexachloro-1,5,5a,6, 9,9a-Hexahydro-,3-Oxide (Or) Endosulfan

Waste Code: P051
Waste Description: 2,7:3,6-Dimethanonaphth[2,3-B]Oxirene, 3,4,5,6,9,9-Hexachloro-1a,2,2a,3,6,6a,7,7a-Octahydro-, (1aalpha, 2beta, 2abeta, 3alpha, 6alpha, 6abeta, 7beta, 7aalpha)- & Metabolites (Or) Endrin (Or) Endrin, & Metabolites

Waste Code: P054
Waste Description: Aziridine (Or) Ethyleneimine

Waste Code: P056
Waste Description: Fluorine

Waste Code: P057
Waste Description: Acetamide, 2-Fluoro- (Or) Fluoroacetamide

Waste Code: P058
Waste Description: Acetic Acid, Fluoro-, Sodium Salt (Or) Fluoroacetic Acid, Sodium Salt

Waste Code: P059
Waste Description: 4,7-Methano-1h-Indene, 1,4,5,6,7,8,8-Heptachloro-3a,4,7,7a-Tetrahydro- (Or) Heptachlor

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: P060
Waste Description: 1,4,5,8-Dimethanonaphthalene, 1,2,3,4,10,10-Hexa-Chloro-1,4,4a,5,8,8a,-Hexahydro-, (1alpha, 4alpha, 4abeta, 5beta, 8beta, 8abeta)- (Or) Isodrin

Waste Code: P062
Waste Description: Hexaethyl Tetraphosphate (Or) Tetraphosphoric Acid, Hexaethyl Ester

Waste Code: P063
Waste Description: Hydrocyanic Acid (Or) Hydrogen Cyanide

Waste Code: P064
Waste Description: Methane, Isocyanato- (Or) Methyl Isocyanate

Waste Code: P065
Waste Description: Fulminic Acid, Mercury(2+) Salt (R,T) (Or) Mercury Fulminate (R,T)

Waste Code: P066
Waste Description: Ethanimidothioic Acid, N-[[(Methylamino)Carbonyl]Oxy]-, Methyl Ester (Or) Methomyl

Waste Code: P067
Waste Description: 1,2-Propylenimine (Or) Aziridine, 2-Methyl-

Waste Code: P068
Waste Description: Hydrazine, Methyl- (Or) Methyl Hydrazine

Waste Code: P069
Waste Description: 2-Methyllactonitrile (Or) Propanenitrile, 2-Hydroxy-2-Methyl-

Waste Code: P070
Waste Description: Aldicarb (Or) Propanal, 2-Methyl-2-(Methylthio)-, O-[(Methylamino)Carbonyl]Oxime

Waste Code: P071
Waste Description: Methyl Parathion (Or) Phosphorothioic Acid, O,O,-Dimethyl O-(4-Nitrophenyl) Ester

Waste Code: P072
Waste Description: Alpha-Naphthylthiourea (Or) Thiourea, 1-Naphthalenyl-

Waste Code: P073
Waste Description: Nickel Carbonyl (Or) Nickel Carbonyl Ni(Co)4, (T-4)-

Waste Code: P074
Waste Description: Nickel Cyanide (Or) Nickel Cyanide Ni(Cn)2

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: P076
Waste Description: Nitric Oxide (Or) Nitrogen Oxide No

Waste Code: P077
Waste Description: Benzenamine, 4-Nitro- (Or) P-Nitroaniline

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: P078
Waste Description: Nitrogen Dioxide (Or) Nitrogen Oxide No2

Waste Code: P081
Waste Description: 1,2,3-Propanetriol, Trinitrate (R) (Or) Nitroglycerine (R)

Waste Code: P082
Waste Description: Methanimine, N-Methyl-N-Nitroso- (Or) N-Nitrosodimethylamine

Waste Code: P084
Waste Description: N-Nitrosomethylvinylamine (Or) Vinylamine, N-Methyl-N-Nitroso-

Waste Code: P085
Waste Description: Diphosphoramide, Octamethyl- (Or) Octamethylpyrophosphoramide

Waste Code: P087
Waste Description: Osmium Oxide Oso4, (T-4)- (Or) Osmium Tetroxide

Waste Code: P088
Waste Description: 7-Oxabicyclo[2.2.1]Heptane-2,3-Dicarboxylic Acid (Or) Endothall

Waste Code: P089
Waste Description: Parathion (Or) Phosphorothioic Acid, O,O-Diethyl-O-(4-Nitrophenyl) Ester

Waste Code: P092
Waste Description: Mercury, (Acetato-O)Phenyl- (Or) Phenylmercury Acetate

Waste Code: P093
Waste Description: Phenylthiourea (Or) Thiourea, Phenyl-

Waste Code: P094
Waste Description: Phorate (Or) Phosphorodithioic Acid, O,O-Diethyl S-[(Ethylthio)Methyl] Ester

Waste Code: P095
Waste Description: Carbonic Dichloride (Or) Phosgene

Waste Code: P096
Waste Description: Hydrogen Phosphide (Or) Phosphine

Waste Code: P097
Waste Description: Famphur (Or) Phosphorothioic Acid O-[4-[(Dimethylamino)Sulfonyl]Phenyl] O,O-Dimethyl Ester

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P099
Waste Description: Argentate (1-), Bis(Cyano-C)-, Potassium (Or) Potassium Silver Cyanide

Waste Code: P101
Waste Description: Ethyl Cyanide (Or) Propanenitrile

Waste Code: P102
Waste Description: 2-Propyn-1-Ol (Or) Propargyl Alcohol

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: P103
Waste Description: Selenourea

Waste Code: P104
Waste Description: Silver Cyanide (Or) Silver Cyanide Ag(Cn)

Waste Code: P105
Waste Description: Sodium Azide

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: P107
Waste Description: Strontium Sulfide Srs

Waste Code: P108
Waste Description: Strychnidin-10-One, & Salts (Or) Strychnine, & Salts

Waste Code: P109
Waste Description: Tetraethyldithiopyrophosphate (Or) Thiodiphosphoric Acid, Tetraethyl Ester

Waste Code: P110
Waste Description: Plumbane, Tetraethyl- (Or) Tetraethyl Lead

Waste Code: P111
Waste Description: Diphosphoric Acid, Tetraethyl Ester (Or) Tetraethyl Pyrophosphate

Waste Code: P112
Waste Description: Methane, Tetranitro- (R) (Or) Tetranitromethane (R)

Waste Code: P113
Waste Description: Thallic Oxide (Or) Thallium Oxide Tl2o3

Waste Code: P114
Waste Description: Selenious Acid, Dithallium (1+) Salt (Or) Thallium(I) Selenite

Waste Code: P115
Waste Description: Sulfuric Acid, Dithallium (1+) Salt (Or) Thallium(I) Sulfate

Waste Code: P116
Waste Description: Hydrazinecarbothioamide (Or) Thiosemicarbazide

Waste Code: P118
Waste Description: Methanethiol, Trichloro- (Or) Trichloromethanethiol

Waste Code: P119
Waste Description: Ammonium Vanadate (Or) Vanadic Acid, Ammonium Salt

Waste Code: P120
Waste Description: Vanadium Oxide V2o5 (Or) Vanadium Pentoxide

Waste Code: P121
Waste Description: Zinc Cyanide (Or) Zinc Cyanide Zn(Cn)2

Waste Code: P122
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Greater Than 10%

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

(R,T)

Waste Code: P123
Waste Description: Toxaphene

Waste Code: P127
Waste Description: P127

Waste Code: P128
Waste Description: P128

Waste Code: P185
Waste Description: 1,3-Dithiolane-2-Carboxaldehyde, 2,4-Dimethyl-, O-[(Methylamino)-Carbonyl]Oxime (Or) Tirpate

Waste Code: P188
Waste Description: Benzoic Acid, 2-Hydroxy-, Compd. With (3as-Cis)-1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethylpyrrolo[2,3-B]Indol-5-Yl Methylcarbamate Ester (1:1) (Or) Physostigmine Salicylate

Waste Code: P189
Waste Description: Carbamic Acid, [(Dibutylamino)-Thio]Methyl-, 2,3-Dihydro-2,2-Dimethyl -7-Benzofuranyl Ester (Or) Carbosulfan

Waste Code: P190
Waste Description: Carbamic Acid, Methyl-, 3-Methylphenyl Ester (Or) Metolcarb

Waste Code: P191
Waste Description: Carbamic Acid, Dimethyl-, 1-[(Dimethyl-Amino)Carbonyl]- 5-Methyl-1h-Pyrazol-3-Yl Ester (Or) Dimetilan

Waste Code: P192
Waste Description: Isolan (Or) Carbamic Acid, Dimethyl-, 3-Methy-L-(1-Methylethyl)-1h-Pyrazol-5-Yl Ester

Waste Code: P194
Waste Description: Ethanimidothioc Acid, 2-(Dimethylamino)-N-[[(Methylamino) Carbonyl]Oxy]-2-Oxo-, Methyl Ester (Or) Oxamyl

Waste Code: P196
Waste Description: Manganese Dimethyldithiocarbamate (Or) Manganese, Bis(Dimethylcarbamodithioato-S,S')-,

Waste Code: P197
Waste Description: Formparanate (Or) Methanimidamide, N,N-Dimethyl-N'-[2-Methyl-4-[[(Methylamino)Carbonyl]Oxy]Phenyl]

Waste Code: P198
Waste Description: Methanimidamide, N,N-Dimethyl-N'-[3-[[(Methylamino)-Carbonyl]Oxy]Phenyl]-, Monohydrochloride (Or) Formetanate Hydrochloride

Waste Code: P199
Waste Description: P199

Waste Code: P201
Waste Description: Phenol, 3-Methyl-5-(1-Methylethyl)-, Methyl Carbamate (Or) Promecarb

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: P202
Waste Description: M-Cumenyl Methylcarbamate (Or) 3-Isopropylphenyl N-Methylcarbamate (Or) Phenol, 3-(1-Methylethyl)-, Methyl Carbamate

Waste Code: P203
Waste Description: Aldicarb Sulfone (Or) Propanal, 2-Methyl-2-(Methyl-Sulfonyl)-, O-[(Methylamino)Carbonyl] Oxime

Waste Code: P204
Waste Description: Physostigmine (Or) Pyrrolo[2,3-B]Indol-5-Ol, 1,2,3,3a,8,8a-Hexahydro-1,3a,8-Trimethyl-Methylcarbamate (Ester), (3as-Cis)-

Waste Code: P205
Waste Description: Zinc, Bis(Dimethylcarbamodithioato-S,S')-, (Or) Ziram

Waste Code: U001
Waste Description: Acetaldehyde (I) (Or) Ethanal (I)

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U003
Waste Description: Acetonitrile (I,T)

Waste Code: U004
Waste Description: Acetophenone (Or) Ethanone, 1-Phenyl-

Waste Code: U005
Waste Description: 2-Acetylaminofluorene (Or) Acetamide, N-9h-Fluoren-2-Yl

Waste Code: U006
Waste Description: Acetyl Chloride (C,R,T)

Waste Code: U007
Waste Description: 2-Propenamide (Or) Acrylamide

Waste Code: U008
Waste Description: 2-Propenoic Acid (I) (Or) Acrylic Acid (I)

Waste Code: U009
Waste Description: 2-Propenenitrile (Or) Acrylonitrile

Waste Code: U010
Waste Description: Azirino [2',3':3,4]Pyrrolo[1,2-A]Indole-4,7-Dione, 6-Amino-8-[[(Aminocarbonyl)Oxy]Methyl]-1,1a,2,8,8a,8b-Hexahydro-8a-Methoxy-5-Methyl-, [1as-(1aalpha, 8beta, 8aalpha, 8balpha)]- (Or) Mitomycin C

Waste Code: U011
Waste Description: 1h-1,2,4-Triazol-3-Amine (Or) Amitrole

Waste Code: U012
Waste Description: Aniline (I,T) (Or) Benzenamine (I,T)

Waste Code: U014
Waste Description: Auramine (Or) Benzenamine, 4,4'-Carbonimidoylbis[N,N-Dimethyl-

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U015
Waste Description: Azaserine (Or) L-Serine, Diazoacetate (Ester)

Waste Code: U016
Waste Description: Benz[C]Acridine

Waste Code: U017
Waste Description: Benzal Chloride (Or) Benzene, (Dichloromethyl)-

Waste Code: U018
Waste Description: Benz[A]Anthracene

Waste Code: U019
Waste Description: Benzene (I,T)

Waste Code: U020
Waste Description: Benzenesulfonic Acid Chloride (C,R) (Or) Benzenesulfonyl Chloride (C,R)

Waste Code: U021
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine (Or) Benzidine

Waste Code: U022
Waste Description: Benzo[A]Pyrene

Waste Code: U023
Waste Description: Benzene, (Trichloromethyl)- (Or) Benzotrichloride (C,R,T)

Waste Code: U024
Waste Description: Dichloromethoxy Ethane (Or) Ethane, 1,1'-[Methylenebis(Oxy)]Bis[2-Chloro-

Waste Code: U025
Waste Description: Dichloroethyl Ether (Or) Ethane, 1,1'-Oxybis[2-Chloro-

Waste Code: U026
Waste Description: Chlornaphazin (Or) Naphthalenamine, N,N'-Bis(2-Chloroethyl)-

Waste Code: U027
Waste Description: Dichloroisopropyl Ether (Or) Propane, 2,2'-Oxybis[2-Chloro-

Waste Code: U028
Waste Description: 1,2-Benzenedicarboxylic Acid, Bis(2-Ethylhexyl) Ester (Or) Diethylhexyl Phthalate

Waste Code: U029
Waste Description: Methane, Bromo- (Or) Methyl Bromide

Waste Code: U030
Waste Description: 4-Bromophenyl Phenyl Ether (Or) Benzene, 1-Bromo-4-Phenoxy-

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U032
Waste Description: Calcium Chromate (Or) Chromic Acid H2cro4, Calcium Salt

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U033
Waste Description: Carbon Oxyfluoride (R,T) (Or) Carbonic Difluoride

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U035
Waste Description: Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil

Waste Code: U036
Waste Description: 4,7-Methano-1h-Indene, 1,2,4,5,6,7,8,8-Octachloro-2,3,3a,4,7,7a-Hexahydro- (Or) Chlordane, Alpha & Gamma Isomers

Waste Code: U037
Waste Description: Benzene, Chloro- (Or) Chlorobenzene

Waste Code: U038
Waste Description: Benzeneacetic Acid, 4-Chloro-Alpha-(4-Chlorophenyl)-Alpha-Hydroxy-, Ethyl Ester (Or) Chlorobenzilate

Waste Code: U039
Waste Description: P-Chloro-M-Cresol (Or) Phenol, 4-Chloro-3-Methyl-

Waste Code: U041
Waste Description: Epichlorohydrin (Or) Oxirane, (Chloromethyl)-

Waste Code: U042
Waste Description: 2-Chloroethyl Vinyl Ether (Or) Ethene, (2-Chloroethoxy)-

Waste Code: U043
Waste Description: Ethene, Chloro- (Or) Vinyl Chloride

Waste Code: U044
Waste Description: Chloroform (Or) Methane, Trichloro-

Waste Code: U045
Waste Description: Methane, Chloro- (I,T) (Or) Methyl Chloride (I,T)

Waste Code: U046
Waste Description: Chloromethyl Methyl Ether (Or) Methane, Chloromethoxy-

Waste Code: U047
Waste Description: Beta-Chloronaphthalene (Or) Naphthalene, 2-Chloro-

Waste Code: U048
Waste Description: O-Chlorophenol (Or) Phenol, 2-Chloro-

Waste Code: U049
Waste Description: 4-Chloro-O-Toluidine, Hydrochloride (Or) Benzenamine, 4-Chloro-2-Methyl-, Hydrochloride

Waste Code: U050
Waste Description: Chrysene

Waste Code: U051
Waste Description: Creosote

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U052
Waste Description: Cresol (Cresylic Acid) (Or) Phenol, Methyl-

Waste Code: U053
Waste Description: 2-Butenal (Or) Crotonaldehyde

Waste Code: U055
Waste Description: Benzene, (1-Methylethyl)- (I) (Or) Cumene (I)

Waste Code: U056
Waste Description: Benzene, Hexahydro- (I) (Or) Cyclohexane (I)

Waste Code: U057
Waste Description: Cyclohexanone (I)

Waste Code: U058
Waste Description: 2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide

Waste Code: U059
Waste Description: 5,12-Naphthacenedione, 8-Acetyl-10-[(3-Amino-2,3,6-Trideoxy)-Alpha-L-Lyxo-Hexopyranosyl)Oxy]-7,8,9,10-Tetrahydro-6,8,11-Trihydroxy-1-Methoxy-, (8s-Cis)- (Or) Daunomycin

Waste Code: U060
Waste Description: Benzene, 1,1'-(2,2-Dichloroethylidene)Bis[4-Chloro- (Or) Ddd

Waste Code: U061
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Chloro- (Or) Ddt

Waste Code: U062
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3-Dichloro-2-Propenyl) Ester (Or) Diallate

Waste Code: U063
Waste Description: Dibenz[A,H]Anthracene

Waste Code: U064
Waste Description: Benzo[Rst]Pentaphene (Or) Dibenzo[A,I]Pyrene

Waste Code: U066
Waste Description: 1,2-Dibromo-3-Chloropropane (Or) Propane, 1,2-Dibromo-3-Chloro-

Waste Code: U067
Waste Description: Ethane, 1,2-Dibromo- (Or) Ethylene Dibromide

Waste Code: U068
Waste Description: Methane, Dibromo- (Or) Methylene Bromide

Waste Code: U069
Waste Description: 1,2-Benzenedicarboxylic Acid, Dibutyl Ester (Or) Dibutyl Phthalate

Waste Code: U070
Waste Description: Benzene, 1,2-Dichloro- (Or) O-Dichlorobenzene

Waste Code: U071

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: Benzene, 1,3-Dichloro- (Or) M-Dichlorobenzene

Waste Code: U072
Waste Description: Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene

Waste Code: U073
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dichloro- (Or) 3,3'-Dichlorobenzidine

Waste Code: U074
Waste Description: 1,4-Dichloro-2-Butene (I,T) (Or) 2-Butene, 1,4-Dichloro- (I,T)

Waste Code: U075
Waste Description: Dichlorodifluoromethane (Or) Methane, Dichlorodifluoro-

Waste Code: U076
Waste Description: Ethane, 1,1-Dichloro- (Or) Ethylidene Dichloride

Waste Code: U077
Waste Description: Ethane, 1,2-Dichloro- (Or) Ethylene Dichloride

Waste Code: U078
Waste Description: 1,1-Dichloroethylene (Or) Ethene, 1,1-Dichloro-

Waste Code: U079
Waste Description: 1,2-Dichloroethylene (Or) Ethene, 1,2-Dichloro-,(E)-

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U081
Waste Description: 2,4-Dichlorophenol (Or) Phenol, 2,4-Dichloro-

Waste Code: U082
Waste Description: 2,6-Dichlorophenol (Or) Phenol, 2,6-Dichloro-

Waste Code: U083
Waste Description: Propane, 1,2-Dichloro- (Or) Propylene Dichloride

Waste Code: U084
Waste Description: 1,3-Dichloropropene (Or) 1-Propene, 1,3-Dichloro-

Waste Code: U085
Waste Description: 1,2:3,4-Diepoxybutane (I,T) (Or) 2,2'-Bioxirane

Waste Code: U086
Waste Description: Hydrazine, 1,2-Diethyl- (Or) N,N'-Diethylhydrazine

Waste Code: U087
Waste Description: O,O-Diethyl S-Methyl Dithiophosphate (Or) Phosphorodithioic Acid, O,O-Diethyl S-Methyl Ester

Waste Code: U088
Waste Description: 1,2-Benzenedicarboxylic Acid, Diethyl Ester (Or) Diethyl Phthalate

Waste Code: U089
Waste Description: Diethylstilbesterol (Or) Phenol, 4,4'-(1,2-Diethyl-1,2-Ethenediyl)Bis,

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

(E)-

Waste Code: U090
Waste Description: 1,3-Benzodioxole, 5-Propyl- (Or) Dihydrosafrole

Waste Code: U091
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethoxy- (Or) 3,3'-Dimethoxybenzidine

Waste Code: U092
Waste Description: Dimethylamine (I) (Or) Methanamine, N-Methyl- (I)

Waste Code: U093
Waste Description: Benzenamine, N,N-Dimethyl-4-(Phenylazo)- (Or) P-Dimethylaminoazobenzene

Waste Code: U094
Waste Description: 7,12-Dimethylbenz[A]Anthracene (Or) Benz[A]Anthracene, 7,12-Dimethyl-

Waste Code: U095
Waste Description: [1,1'-Biphenyl]-4,4'-Diamine, 3,3'-Dimethyl- (Or) 3,3'-Dimethylbenzidine

Waste Code: U096
Waste Description: Alpha,Alpha-Dimethylbenzylhydroperoxide (R) (Or) Hydroperoxide, 1-Methyl-1-Phenylethyl- (R)

Waste Code: U097
Waste Description: Carbamic Chloride, Dimethyl- (Or) Dimethylcarbamoyl Chloride

Waste Code: U098
Waste Description: 1,1-Dimethylhydrazine (Or) Hydrazine, 1,1-Dimethyl-

Waste Code: U099
Waste Description: 1,2-Dimethylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U101
Waste Description: 2,4-Dimethylphenol (Or) Phenol, 2,4-Dimethyl-

Waste Code: U102
Waste Description: 1,2-Benzenedicarboxylic Acid, Dimethyl Ester (Or) Dimethyl Phthalate

Waste Code: U103
Waste Description: Dimethyl Sulfate (Or) Sulfuric Acid, Dimethyl Ester

Waste Code: U105
Waste Description: 2,4-Dinitrotoluene (Or) Benzene, 1-Methyl-2,4-Dinitro-

Waste Code: U106
Waste Description: 2,6-Dinitrotoluene (Or) Benzene, 2-Methyl-1,3-Dinitro-

Waste Code: U107
Waste Description: 1,2-Benzenedicarboxylic Acid, Dioctyl Ester (Or) Di-N-Octyl Phthalate

Waste Code: U108
Waste Description: 1,4-Diethyleneoxide (Or) 1,4-Dioxane

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U109
Waste Description: 1,2-Diphenylhydrazine (Or) Hydrazine, 1,2-Diphenyl-

Waste Code: U110
Waste Description: 1-Propanimine, N-Propyl-(I) (Or) Dipropylamine (I)

Waste Code: U111
Waste Description: 1-Propanamine, N-Nitroso-N-Propyl- (Or) Di-N-Propylnitrosamine

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U113
Waste Description: 2-Propenoic Acid, Ethyl Ester (I) (Or) Ethyl Acrylate (I)

Waste Code: U114
Waste Description: Carbamodithioic Acid, 1,2-Ethanediylbis-, Salts & Esters (Or) Ethylenebisdithiocarbamic Acid, Salts & Esters

Waste Code: U115
Waste Description: Ethylene Oxide (I,T) (Or) Oxirane (I,T)

Waste Code: U116
Waste Description: 2-Imidazolidinethione (Or) Ethylenethiourea

Waste Code: U117
Waste Description: Ethane, 1,1'-Oxybis-(I) (Or) Ethyl Ether (I)

Waste Code: U118
Waste Description: 2-Propenoic Acid, 2-Methyl-, Ethyl Ester (Or) Ethyl Methacrylate

Waste Code: U119
Waste Description: Ethyl Methanesulfonate (Or) Methanesulfonic Acid, Ethyl Ester

Waste Code: U120
Waste Description: Fluoranthene

Waste Code: U121
Waste Description: Methane, Trichlorofluoro- (Or) Trichloromonofluoromethane

Waste Code: U122
Waste Description: Formaldehyde

Waste Code: U123
Waste Description: Formic Acid (C,T)

Waste Code: U124
Waste Description: Furan (I) (Or) Furfuran (I)

Waste Code: U125
Waste Description: 2-Furancarboxaldehyde (I) (Or) Furfural (I)

Waste Code: U126
Waste Description: Glycidylaldehyde (Or) Oxiranecarboxyaldehyde

Waste Code: U127
Waste Description: Benzene, Hexachloro- (Or) Hexachlorobenzene

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U128
Waste Description: 1,3-Butadiene, 1,1,2,3,4,4-Hexachloro- (Or) Hexachlorobutadiene

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U130
Waste Description: 1,3-Cyclopentadiene, 1,2,3,4,5,5-Hexachloro- (Or) Hexachlorocyclopentadiene

Waste Code: U131
Waste Description: Ethane, Hexachloro- (Or) Hexachloroethane

Waste Code: U132
Waste Description: Hexachlorophene (Or) Phenol, 2,2'-Methylenebis[3,4,6-Trichloro-

Waste Code: U133
Waste Description: Hydrazine (R,T)

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Waste Code: U135
Waste Description: Hydrogen Sulfide (Or) Hydrogen Sulfide H2s

Waste Code: U136
Waste Description: Arsinic Acid, Dimethyl- (Or) Cacodylic Acid

Waste Code: U137
Waste Description: Indeno[1,2,3-Cd]Pyrene

Waste Code: U138
Waste Description: Methane, Iodo- (Or) Methyl Iodide

Waste Code: U139
Waste Description: Not Defined

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U141
Waste Description: 1,3-Benzodioxole, 5-(1-Propenyl)- (Or) Isosafrole

Waste Code: U142
Waste Description: 1,3,4-Metheno-2h-Cyclobuta[Cd]Pentalen-2-One, 1,1a,3,3a,4,5,5,5a,5b,6-Decachlorooctahydro- (Or) Kepone

Waste Code: U143
Waste Description: 2-Butenoic Acid, 2-Methyl-, 7-[[2,3-Dihydroxy-2-(1-Methoxyethyl)-3-Methyl-1-Oxobutoxy]Methyl]-2,3,5,7a-Tetrahydro-1h-Pyrrolizin-1-Yl Ester, [1s-[1alpha(Z), 7(2s*,3r*), 7aalpha]]- (Or) Lasiocarpine

Waste Code: U144
Waste Description: Acetic Acid, Lead(2+) Salt (Or) Lead Acetate

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U145
Waste Description: Lead Phosphate (Or) Phosphoric Acid, Lead(2+) Salt (2:3)

Waste Code: U146
Waste Description: Lead Subacetate (Or) Lead, Bis(Acetato-O)Tetrahydroxytri-

Waste Code: U147
Waste Description: 2,5-Furandione (Or) Maleic Anhydride

Waste Code: U148
Waste Description: 3,6-Pyridazinedione, 1,2-Dihydro- (Or) Maleic Hydrazide

Waste Code: U149
Waste Description: Malononitrile (Or) Propanedinitrile

Waste Code: U150
Waste Description: L-Phenylalanine, 4-[Bis(2-Chloroethyl)Amino]- (Or) Melphalan

Waste Code: U151
Waste Description: Mercury

Waste Code: U152
Waste Description: 2-Propenenitrile, 2-Methyl- (I,T) (Or) Methacrylonitrile (I,T)

Waste Code: U153
Waste Description: Methanethiol (I,T) (Or) Thiomethanol (I,T)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U155
Waste Description: 1,2-Ethanediamine, N,N-Dimethyl-N'-2-Pyridinyl-N'-(2-Thienylmethyl)- (Or) Methapyrilene

Waste Code: U156
Waste Description: Carbonochloridic Acid, Methyl Ester, (I,T) (Or) Methyl Chlorocarbonate (I,T)

Waste Code: U157
Waste Description: 3-Methylcholanthrene (Or) Benz[J]Aceanthrylene, 1,2-Dihydro-3-Methyl-

Waste Code: U158
Waste Description: 4,4'-Methylenebis(2-Chloroaniline) (Or) Benzenamine, 4,4'-Methylenebis[2-Chloro-

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U162
Waste Description: 2-Propenoic Acid, 2-Methyl-, Methyl Ester (I,T) (Or) Methyl

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Methacrylate (I,T)

Waste Code: U163
Waste Description: Guanidine, N-Methyl-N'-Nitro-N-Nitroso- (Or) Mnng

Waste Code: U164
Waste Description: 4(1h)-Pyrimidinone, 2,3-Dihydro-6-Methyl-2-Thioxo- (Or) Methylthiouracil

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U166
Waste Description: 1,4-Naphthalenedione (Or) 1,4-Naphthoquinone

Waste Code: U167
Waste Description: 1-Napthalenamine (Or) Alpha-Naphthylamine

Waste Code: U168
Waste Description: 2-Napthalenamine (Or) Beta-Naphthylamine

Waste Code: U169
Waste Description: Benzene, Nitro- (Or) Nitrobenzene (I,T)

Waste Code: U170
Waste Description: P-Nitrophenol (I,T) (Or) Phenol, 4-Nitro-

Waste Code: U171
Waste Description: 2-Nitropropane (I,T) (Or) Propane, 2-Nitro- (I,T)

Waste Code: U172
Waste Description: 1-Butanamine, N-Butyl-N-Nitroso- (Or) N-Nitrosodi-N-Butylamine

Waste Code: U173
Waste Description: Ethanol, 2,2'-(Nitrosoimino)Bis- (Or) N-Nitrosodiethanolamine

Waste Code: U174
Waste Description: Ethanamine, N-Ethyl-N-Nitroso- (Or) N-Nitrosodiethylamine

Waste Code: U176
Waste Description: N-Nitroso-N-Ethylurea (Or) Urea, N-Ethyl-N-Nitroso-

Waste Code: U177
Waste Description: N-Nitroso-N-Methylurea (Or) Urea, N-Methyl-N-Nitroso-

Waste Code: U178
Waste Description: Carbamic Acid, Methylnitroso-, Ethyl Ester (Or) N-Nitroso-N-Methylurethane

Waste Code: U179
Waste Description: N-Nitrosopiperidine (Or) Piperidine, 1-Nitroso-

Waste Code: U180
Waste Description: N-Nitrosopyrrolidine (Or) Pyrrolidine, 1-Nitroso-

Waste Code: U181
Waste Description: 5-Nitro-O-Toluidine (Or) Benzenamine, 2-Methyl-5-Nitro

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U182
Waste Description: 1,3,5-Trioxane, 2,4,6-Trimethyl- (Or) Paraldehyde

Waste Code: U183
Waste Description: Benzene, Pentachloro- (Or) Pentachlorobenzene

Waste Code: U184
Waste Description: Ethane, Pentachloro- (Or) Pentachloroethane

Waste Code: U185
Waste Description: Benzene, Pentachloronitro- (Or) Pentachloronitrobenzene (Pcnb)

Waste Code: U186
Waste Description: 1,3-Pentadiene (I) (Or) 1-Methylbutadiene (I)

Waste Code: U187
Waste Description: Acetamide, N-(4-Ethoxyphenyl)- (Or) Phenacetin

Waste Code: U188
Waste Description: Phenol

Waste Code: U189
Waste Description: Phosphorus Sulfide (R) (Or) Sulfur Phosphide (R)

Waste Code: U190
Waste Description: 1,3-Isobenzofurandione (Or) Phthalic Anhydride

Waste Code: U191
Waste Description: 2-Picoline (Or) Pyridine, 2-Methyl-

Waste Code: U192
Waste Description: Benzamide, 3,5-Dichloro-N-(1,1-Dimethyl-2-Propynyl)- (Or) Pronamide

Waste Code: U193
Waste Description: 1,2-Oxathiolane, 2,2-Dioxide (Or) 1,3-Propane Sultone

Waste Code: U194
Waste Description: 1-Propanamine (I,T) (Or) N-Propylamine (I,T)

Waste Code: U196
Waste Description: Pyridine

Waste Code: U197
Waste Description: 2,5-Cyclohexadiene-1,4-Dione (Or) P-Benzoquinone

Waste Code: U200
Waste Description: Reserpine (Or) Yohimban-16-Carboxylic Acid, 11,17-Dimethoxy-18-[(3,4,5-Trimethoxybenzoyl)Oxy]-, Methyl Ester, (3beta, 16beta, 17alpha, 18beta, 20alpha)-

Waste Code: U201
Waste Description: 1,3-Benzenediol (Or) Resorcinol

Waste Code: U202
Waste Description: 1,2-Benzisothiazol-3(2h)-One, 1,1-Dioxide, & Salts (Or) Saccharin, & Salts

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Code: U203
Waste Description: 1,3-Benzodioxole, 5-(2-Propenyl)- (Or) Safrole

Waste Code: U204
Waste Description: Selenious Acid (Or) Selenium Dioxide

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U206
Waste Description: D-Glucose, 2-Deoxy-2-[[(Methylnitrosoamino)-Carbonyl]Amino]- (Or) Glucopyranose, 2-Deoxy-2-(3-Methyl-3-Nitrosoureido)-,D- (Or) Streptozotocin

Waste Code: U207
Waste Description: 1,2,4,5-Tetrachlorobenzene (Or) Benzene, 1,2,4,5-Tetrachloro-

Waste Code: U208
Waste Description: 1,1,1,2-Tetrachloroethane (Or) Ethane, 1,1,1,2-Tetrachloro-

Waste Code: U209
Waste Description: 1,1,2,2-Tetrachloroethane (Or) Ethane, 1,1,2,2-Tetrachloro-

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U213
Waste Description: Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)

Waste Code: U214
Waste Description: Acetic Acid, Thallium(1+) Salt (Or) Thallium(I) Acetate

Waste Code: U215
Waste Description: Carbonic Acid, Dithallium(1+) Salt (Or) Thallium(I) Carbonate

Waste Code: U216
Waste Description: Thallium Chloride Tlcl (Or) Thallium(I) Chloride

Waste Code: U217
Waste Description: Nitric Acid, Thallium(1+) Salt (Or) Thallium(I) Nitrate

Waste Code: U218
Waste Description: Ethanethioamide (Or) Thioacetamide

Waste Code: U219
Waste Description: Thiourea

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U221
Waste Description: Benzenediamine, Ar-Methyl- (Or) Toluenediamine

Waste Code: U222

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: Benzenamine, 2-Methyl-, Hydrochloride (Or) O-Toluidine Hydrochloride

Waste Code: U223
Waste Description: Benzene, 1,3-Diisocyanatomethyl- (R,T) (Or) Toluene Diisocyanate (R,T)

Waste Code: U225
Waste Description: Bromoform (Or) Methane, Tribromo-

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U227
Waste Description: 1,1,2-Trichloroethane (Or) Ethane, 1,1,2-Trichloro-

Waste Code: U228
Waste Description: Ethene, Trichloro- (Or) Trichloroethylene

Waste Code: U234
Waste Description: 1,3,5-Trinitrobenzene (R,T) (Or) Benzene, 1,3,5-Trinitro-

Waste Code: U235
Waste Description: 1-Propanol, 2,3-Dibromo-, Phosphate (3:1) (Or) Tris(2,3,-Dibromopropyl) Phosphate

Waste Code: U236
Waste Description: 2,7-Naphthalenedisulfonic Acid,3,3'-[(3,3'-Dimethyl[1,1'-Biphenyl]-4,4'-Diyl)Bis(Azo)Bis[5-Amino -4-Hydroxy]-, Tetrasodium Salt (Or) Trypan Blue

Waste Code: U237
Waste Description: 2,4-(1h,3h)-Pyrimidinedione, 5-[Bis(2-Chloroethyl)Amino]- (Or) Uracil Mustard

Waste Code: U238
Waste Description: Carbamic Acid, Ethyl Ester (Or) Ethyl Carbamate (Urethane)

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U243
Waste Description: 1-Propene, 1,1,2,3,3,3-Hexachloro- (Or) Hexachloropropene

Waste Code: U244
Waste Description: Thioperoxydicarbonic Diamide [(H2n)C(S)]2s2, Tetramethyl- (Or) Thiram

Waste Code: U246
Waste Description: Cyanogen Bromide (Cn)Br

Waste Code: U247
Waste Description: Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Methoxy- (Or) Methoxychlor

Waste Code: U248

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenyl-Butyl)-, & Salts, When Present At Concentrations Of 0.3% Or Less (Or) Warfarin, & Salts, When Present At Concentrations Of 0.3% Or Less

Waste Code: U249
Waste Description: Zinc Phosphide Zn3p2, When Present At Concentrations Of 10% Or Less

Waste Code: U271
Waste Description: Benomyl (Or) Carbamic Acid, [1-[(Butylamino)Carbonyl]-1h-Benzimidazol-2-Yl]-, Methyl Ester

Waste Code: U278
Waste Description: Bendiocarb (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-, Methyl Carbamate

Waste Code: U279
Waste Description: U279

Waste Code: U280
Waste Description: Barban (Or) Carbamic Acid, (3-Chlorophenyl)-, 4-Chloro-2-Butynyl Ester

Waste Code: U328
Waste Description: Benzenamine, 2-Methyl- (Or) O-Toluidine

Waste Code: U353
Waste Description: Benzenamine, 4-Methyl- (Or) P-Toluidine

Waste Code: U359
Waste Description: Ethanol, 2-Ethoxy- (Or) Ethylene Glycol Monoethyl Ether

Waste Code: U364
Waste Description: Bendiocarb Phenol (Or) 1,3-Benzodioxol-4-Ol, 2,2-Dimethyl-

Waste Code: U367
Waste Description: 7-Benzofuranol, 2,3-Dihydro-2,2-Dimethyl- (Or) Carbofuran Phenol

Waste Code: U372
Waste Description: Carbamic Acid, 1h-Benzimidazol-2-Yl, Methyl Ester (Or) Carbendazim

Waste Code: U373
Waste Description: Carbamic Acid, Phenyl-, 1-Methylethyl Ester (Or) Propham

Waste Code: U387
Waste Description: Carbamothioic Acid, Dipropyl-, S-(Phenylmethyl) Ester (Or) Prosulfocarb

Waste Code: U389
Waste Description: Carbamothioic Acid, Bis(1-Methylethyl)-, S-(2,3,3-Trichloro-2-Propenyl) Ester (Or) Triallate

Waste Code: U394
Waste Description: A2213 (Or) Ethanimidothioic Acid, 2-(Dimethylamino)-N-Hydroxy-2-Oxo-, Methyl Ester

Waste Code: U395
Waste Description: Diethylene Glycol, Dicarbamate (Or) Ethanol, 2,2'-Oxybis-, Dicarbamate

Waste Code: U401

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Description: Bis(Dimethylthiocarbamoyl) Sulfide (Or) Tetramethylthiuram Monosulfide

Waste Code: U404
Waste Description: U404

Waste Code: U409
Waste Description: Carbamic Acid, [1,2-Phenylenebis (Iminocarbonothioyl)]Bis-, Dimethyl Ester (Or) Thiophanate-Methyl

Waste Code: U410
Waste Description: Ethanimidothioic Acid, N,N'-[Thiobis[(Methylimino)Carbonyloxy]]Bis-, Dimethyl Ester (Or) Thiodicarb

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Ended Current:	Not reported
Owner/Operator Address:	1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip:	AUSTIN, TX 78723-3210
Owner/Operator Telephone:	512-324-8905
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ASCENSION SETON	
Legal Status:	Private
Date Became Current:	20190401
Date Ended Current:	Not reported
Owner/Operator Address:	200 N HEATHERWILDE BLVD
Owner/Operator City,State,Zip:	PFLUGERVILLE, TX 78660-3530
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ASCENSION SETON	
Legal Status:	Private
Date Became Current:	20190401
Date Ended Current:	Not reported
Owner/Operator Address:	200 N HEATHERWILDE BLVD
Owner/Operator City,State,Zip:	PFLUGERVILLE, TX 78660-3530
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE	
Legal Status:	Private
Date Became Current:	20040126
Date Ended Current:	Not reported
Owner/Operator Address:	1201 W 38TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78705
Owner/Operator Telephone:	512-324-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE	
Legal Status:	Private
Date Became Current:	20040126
Date Ended Current:	Not reported
Owner/Operator Address:	1201 W 38TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78705
Owner/Operator Telephone:	512-324-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST # 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20040126
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH STREET
Owner/Operator City,State,Zip: AUSTIN, TX 78705

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Telephone: 512-324-1000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20040126
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-324-1000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20040126

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH STREET
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-324-1000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20090630
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-324-1000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20090630
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705
Owner/Operator Telephone: 512-324-1000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 200 N HEATHERWILDE BLVD
Owner/Operator City,State,Zip: PFLUGERVILLE, TX 78660-3530
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST # 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST # 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DAUGHTERS OF CHARITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION HEALTH DBA SETON HEALTHCARE
Legal Status: Private
Date Became Current: 20021127
Date Ended Current: Not reported
Owner/Operator Address: 1201 W 38TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78705-1006

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST STE 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: 512-324-8905
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 200 N HEATHERWILDE BLVD
Owner/Operator City,State,Zip: PFLUGERVILLE, TX 78660-3530
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ASCENSION SETON
Legal Status: Private
Date Became Current: 20190401
Date Ended Current: Not reported
Owner/Operator Address: 1345 PHILOMENA ST # 357
Owner/Operator City,State,Zip: AUSTIN, TX 78723-3210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160301
Handler Name: SEATON HEALTHCARE SETON MEDICAL CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19861110
Handler Name: SETON MEDICAL CENTER

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040126
Handler Name: ASCENSION HEALTH	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060621
Handler Name: ASCENSION HEALTH	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20061220
Handler Name: ASCENSION HEALTH	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090630
Handler Name: ASCENSION HEALTH	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130226
Handler Name: SEATON HEALTHCARE SETON MEDICAL CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140128
Handler Name: SEATON HEALTHCARE SETON MEDICAL CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180620
Handler Name: SEATON HEALTHCARE SETON MEDICAL CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180620
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Receive Date: 20190808
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190401
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210405
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210405
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210405
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210412
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210802
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220210
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220325
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221109
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221117
Handler Name: ASCENSION SETON MEDICAL CENTER AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 62211
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

NAICS Code: 622110
NAICS Description: GENERAL MEDICAL AND SURGICAL HOSPITALS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SWF/LF:
Name: SETON MEDICAL CENTER WASTE INCINERATOR
Address: 1201 W 38TH ST
City,State,Zip: AUSTIN, TX 78705-1006
Region: 11
Permit Number: 2128
Facility Status: NOT CONSTRUCTED
Facility Type: 5WI
Permit Status: WITHDRAWN
Status Date: 11/14/1990
Mailing Address: Not reported
Client Name: Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Client Address:	Not reported
Client Telephone:	N/A
Business Type:	03
Area Served:	Not reported
Estimated Closure Date:	1/1/1901
Permit Acreage:	.1
Permit Start:	Not reported
Permit End:	Not reported
Polution Served:	2465
Tons per Day:	35
Yards per Day:	Not reported
Application:	Not reported
Lat/Long:	30.30489 / -97.74549

LPST:

Name:	SETON MEDICAL CENTER
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0056515
LPST Id:	097017
Facility Location:	1201 W 38TH ST TANKS ARE ACTUALLY ON WABASH AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/08/1990
Entered Date:	10/23/1990
Reported Date:	10/08/1990
Closure Date:	11/26/1996
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	LAS
Responsible Party Name:	Not reported
Responsible Party Contact:	PETER KAHARL
Responsible Party Address:	1201 W 38TH
Responsible Party City,St,Zip:	AUSTIN, TX 78705
Responsible Party Telephone:	512/323-1950
Reported Date:	10/08/1990
Case Start Date:	11/26/1996
Reference Number:	RN102338217
Project Manager:	LAS

UST:

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 787051006
AI Number:	56515
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	10/25/1990
Facility Status:	ACTIVE
Additional ID:	548071502002156
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	JOHN DEARRINGTON,
Contact Organization Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123241700
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/04/2022
Signature Name/Title On Earliest Reg Form:	MARK A WEHNER,REG SAFTY OFF
Application Received Date On Earliest Reg Form:	10/06/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	548617422002149
Additional ID:	548071502002156
Ai Number:	56515
Operator CN:	CN601238181
Operator Name:	ASCENSION SETON
Operator Effective Begin Date:	04/01/2019
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	MARK WEHNER/
Contact Organization Name:	ASCENSION SETON
Contact Mailing Address (Delivery):	1345 PHILOMENA ST STE 357
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78723-3210
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9342918
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	mark.wehner@medxcel.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601238181
Owner Last Name:	ASCENSION SETON
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1345 PHILOMENA ST STE 357
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Contact Mailing State:	TX
Contact Mailing Zip:	78723
Contact Mailing Zip5:	3210
Contact Phone Number/Ext:	1 512 9342918/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	mark.wehner@medxcel.com
Contact Address Deliverable:	Not reported
Princ ID:	548617422002149
Additional ID:	548071502002156
AI Number:	56515
Owner Effective Begin Date:	04/01/2019
State Tax ID:	17411096435
Contact Role:	OWNOPRCON
Contact Name/Title:	MARK WEHNER/
Contact Organization Name:	ASCENSION SETON

Self Certification:

Self Cert ID:	86372
Cert ID:	378598
AI Number:	56515
Self Certification Date:	10/04/2022
Signature Name/Title:	MARK WEHNER REG SAFTY OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	361313
AI Number:	56515
Self Certification Date:	09/14/2021
Signature Name/Title:	MARK A WEHNER REGION HAZMAT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	350099
AI Number:	56515
Self Certification Date:	12/22/2020
Signature Name/Title:	MARK WEHNER REG HAZ
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	328258
AI Number:	56515
Self Certification Date:	09/27/2019
Signature Name/Title:	MARK WEHNER REGIONAL HAZMAT SAFETY OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	322512
AI Number:	56515
Self Certification Date:	06/28/2019
Signature Name/Title:	REGINA WEST REG HAZ MAT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	310174
AI Number:	56515
Self Certification Date:	09/19/2018
Signature Name/Title:	MARK WEHNER REG HAZ SAFETY
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	294503
AI Number:	56515
Self Certification Date:	09/06/2017
Signature Name/Title:	MARK WEHNER REG HAZMAT SFTY OFCR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	277741
AI Number:	56515
Self Certification Date:	09/27/2016
Signature Name/Title:	MARK WEHNER HAZMAT SAFETY OFFICE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	260849
AI Number:	56515
Self Certification Date:	10/06/2015
Signature Name/Title:	MARK WEHNER SAFETY OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	243782
AI Number:	56515
Self Certification Date:	09/29/2014
Signature Name/Title:	MARK A WEHNER NHSO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372
Cert ID:	228039
AI Number:	56515
Self Certification Date:	10/30/2013
Signature Name/Title:	MARK A WEHNER NETWORK HAZMAT SO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	135812
AI Number:	56515
Self Certification Date:	09/25/2012
Signature Name/Title:	MARK A WEHNER SAFETY OFFICER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135811
AI Number:	56515
Self Certification Date:	09/24/2012
Signature Name/Title:	MARK A WEHNER NETWORK HAZMAT SO
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135810
AI Number:	56515
Self Certification Date:	06/22/2012
Signature Name/Title:	MARK A WEHNER NETWORK HAZMAT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	135809
AI Number:	56515
Self Certification Date:	02/16/2011
Signature Name/Title:	MARK A WEHNER NTWK SFTY OFCR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135808
AI Number:	56515
Self Certification Date:	01/26/2010
Signature Name/Title:	MARK A WEHNER NETWORK SAF OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135807
AI Number:	56515
Self Certification Date:	09/26/2006
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFFIC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	135806
AI Number:	56515
Self Certification Date:	11/03/2005
Signature Name/Title:	MARK WEHNER NETWORK SAF OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135805
AI Number:	56515
Self Certification Date:	09/20/2004
Signature Name/Title:	MARK WEHMER NETWORK SAFETY OFFIC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135804
AI Number:	56515
Self Certification Date:	09/30/2003
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFFIC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Cert ID:	135803
AI Number:	56515
Self Certification Date:	11/05/2002
Signature Name/Title:	MARK A WEHNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	86372
Cert ID:	135802
AI Number:	56515
Self Certification Date:	01/11/2001
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	08/01/1972
Tank Registration Date:	10/25/1990
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	136478
Facility ID:	86372
Ai Number:	56515
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/24/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	5000
UST Comprt ID:	137355
UST ID:	136478
AI Number:	56515
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	09/01/1985
Tank Registration Date:	10/25/1990
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	136479
Facility ID:	86372
Ai Number:	56515
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/06/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/24/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	137356
UST ID:	136479
AI Number:	56515
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1991
Tank Registration Date:	10/25/1990
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	G
UST ID:	136480
Facility ID:	86372
Ai Number:	56515
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/01/1991
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/24/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	137357
UST ID:	136480
AI Number:	56515
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ASCENSION SETON
Contact Mailing Address (Delivery):	1345 PHILOMENA ST STE 357
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78723 3210
Phone Number/Ext:	512 3248905/0
Contact Fax Number/Ext:	/
Contact Email Address:	MARK.WEHNER@MEDXCELFM.COM
Contact Address Deliverable:	Y
Facility ID:	86372
Additional ID:	548071502002156
Princ ID:	548617422002149
AI Number:	56515
Facility Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
AR Number:	31080
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	MARK WEHNER/

FINDS:

Registry ID: 110005062957

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

ECHO:

Envid:	1000337148
Registry ID:	110005062957
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005062957
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH STREET
City,State,Zip:	AUSTIN, TX 78705

AIRS:

Name:	SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Permit Num:	14288
Regulated Id:	RN102338217
Permit Type:	EXEMPT
Permit Status:	CANCELLED
Permit Issued Date:	08/21/2006
Expiration Date:	12/31/3000
Customer Id:	CN601233364
Company Name:	DCHSA DBA SETON MEDICAL CENTER
Physical Location Desc:	1201 38th St W, Austin, TX
Rep Official(RO):	NETWORK HAZMAT SAFETY OFFICER
RO Name:	MR MARK A WEHNER
RO Delivery Address:	1201 W 38TH ST
RO City/State/Zip:	AUSTIN, T 78705-100
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.304891
Long Dec Coord Num:	-97.745494

Emission:

Region Code:	11
SIC Code:	8062
SIC Description:	Not reported
EPA Emission Amount Class:	B
Company Contact:	HOWARD SCALES
Mailing Address:	1201 W 38TH ST
Mailing City,St,Zip:	AUSTIN, TX 78705 78705
Mailing County:	TRAVIS
Facility Telephone:	(512) 459-2121
Date of Last Emission Inventory:	Not reported
Total Suspected Pariculate Actuals:	0
Pariculate Matter 10 Microns or Less Actuals:	0
Sulfur Dioxide Actual Emission Amounts:	0
Nitrogen Oxide Actual Emission Amounts:	0
Non-Methane Organic Coumpound Actuals:	0
Carbon Monoxide Actual Emission Amounts:	0
Lead Actual emission Amounts:	0
Company Name of a TNRCC Account:	SETON MEDICAL CENTER
Unique TNRCC Account Id. Number:	TH0211T
Operating Status:	O
Investigation Status of Account:	IA
EPA ID:	45300000
Reported Year:	Not reported
PM 2.5:	Not reported
VOC:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Name:	SETON MEDICAL CENTER
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Permit Num:	19582
Regulated Id:	RN102338217
Permit Type:	CONSTRUCT
Permit Status:	CANCELLED
Permit Issued Date:	11/21/1990
Expiration Date:	12/31/3000
Customer Id:	CN601233364
Company Name:	DCHSA DBA SETON MEDICAL CENTER
Physical Location Desc:	1201 38th St W, Austin, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.304891
Long Dec Coord Num:	-97.745494

Emission:

Region Code:	11
SIC Code:	8062
SIC Description:	Not reported
EPA Emission Amount Class:	B
Company Contact:	HOWARD SCALES
Mailing Address:	1201 W 38TH ST
Mailing City,St,Zip:	AUSTIN, TX 78705 78705
Mailing County:	TRAVIS
Facility Telephone:	(512) 459-2121
Date of Last Emission Inventory:	Not reported
Total Suspected Pariculate Actuals:	0
Pariculate Matter 10 Microns or Less Actuals:	0
Sulfur Dioxide Actual Emission Amounts:	0
Nitrogen Oxide Actual Emission Amounts:	0
Non-Methane Organic Coumpound Actuals:	0
Carbon Monoxide Actual Emission Amounts:	0
Lead Actual emission Amounts:	0
Company Name of a TNRCC Account:	SETON MEDICAL CENTER
Unique TNRCC Account Id. Number:	TH0211T
Operating Status:	O
Investigation Status of Account:	IA
EPA ID:	45300000
Reported Year:	Not reported
PM 2.5:	Not reported
VOC:	Not reported

ASBESTOS:

Name:	SETON FAMILY OF HOSPITALS
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Complaint Date:	03/24/2020
Notification Number:	2020002099
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/09/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	3
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/23/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/27/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	06/25/2021
Notification Number:	2021003812
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/07/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/07/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	16
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/21/2021

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/22/2022
Notification Number:	2022000974
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/07/2022

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/19/2022
Notification Number:	2022005232
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/05/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/05/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/27/2022
Notification Number:	2022005627
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/27/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2022
Notification Number:	2022005627
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/07/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/08/2022
Notification Number:	2022005627
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/25/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/25/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/21/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/31/2018
Notification Number:	2018004737
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/06/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	06/20/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/21/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/31/2018
Notification Number:	2018004737
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/06/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	06/20/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date of inspection:	02/15/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/08/2018
Notification Number:	2018005618
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/23/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/23/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/15/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/01/2018
Notification Number:	2018005618
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/13/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/13/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/15/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/06/2018
Notification Number:	2018005618
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/17/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/17/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	02/15/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/27/2018
Notification Number:	2018005618
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/10/2018

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/10/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/31/2018
Notification Number:	2018006461

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/16/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/16/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/30/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2018
Notification Number:	2018006461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/18/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/18/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/30/2018
Client Code:	Not reported
Client Name:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2018
Notification Number:	2018006461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/31/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/31/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/30/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2018
Notification Number:	2018006461
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/12/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/12/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/30/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/19/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/29/2022
Notification Number:	2022004442
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/01/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/01/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	42
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/19/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/01/2022
Notification Number:	2022004442
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/29/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	42
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/19/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/29/2022
Notification Number:	2022004442
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/19/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/19/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	42
Is this a phased abatement project?:	N
Ordered:	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	07/19/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/28/2017
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/28/2017
Notification Number:	2017004231
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/10/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/10/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/27/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/28/2017
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	06/28/2017
Notification Number:	2017004231
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/20/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/20/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/26/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/28/2017
Reason for Inspection:	Jimmy Stafford

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Violation:	Not reported
Complaint Date:	07/28/2017
Notification Number:	2017004231
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/21/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/21/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/26/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/28/2017
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	06/23/2017
Notification Number:	2017004231
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/05/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/05/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Start Date:	06/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/22/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/04/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Certification Statement Date:	01/04/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	02/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/09/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/10/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/10/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/09/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/19/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/19/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/09/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/22/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/22/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	27
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/26/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/28/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/11/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/30/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/13/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	8
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/13/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/28/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/02/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	29
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/16/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/17/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/17/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/30/2018
Notification Number:	2017009926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/08/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/08/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	50
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	01/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/17/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/09/2018
Notification Number:	2018003333
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/23/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/23/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/08/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/31/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/23/2018
Notification Number:	2018003590
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Report Received:	05/14/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/14/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/22/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	01/31/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/17/2018

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Number:	2018003590
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/02/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/16/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/13/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/29/2021
Notification Number:	2021001635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/28/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/28/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	137
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/31/2021
Client Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/13/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/23/2021
Notification Number:	2021001635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/29/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/29/2021
Certification Statement Phone:	512-260-7171

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	137
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/31/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/13/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/28/2021
Notification Number:	2021001635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/21/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	137
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/31/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	07/13/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/23/2021
Notification Number:	2021001635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/16/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/16/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	137
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/30/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Name:	SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/15/2017
Notification Number:	2016008466
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/11/2016
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	37
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	Assumed Asbestos
Start Date:	10/29/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION PARKING GARAGE
Address:	1201 W. 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/11/23
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	11/23/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022006908
File Number:	75695
License Status Description:	Current
Expiration Date:	01/22/2023
Original Date:	10/31/2022
Rank Effective Date:	10/31/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	36841
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/05/22
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/22/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020003085
File Number:	52090
License Status Description:	Current
Expiration Date:	06/12/2020
Original Date:	04/27/2020
Rank Effective Date:	04/27/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	21667
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/04/15
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/15/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022002053
File Number:	70260
License Status Description:	Current
Expiration Date:	04/15/2022
Original Date:	03/25/2022
Rank Effective Date:	03/25/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	32601
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Fail
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Violation:	Not reported
Complaint Date:	2022/05/11
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/11/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022002801
File Number:	71084
License Status Description:	Current
Expiration Date:	05/12/2022
Original Date:	04/27/2022
Rank Effective Date:	04/27/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	33048

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2022/07/19
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Start Date:	07/19/2022
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2022004442
File Number:	72894
License Status Description:	Current
Expiration Date:	08/01/2022
Original Date:	07/01/2022
Rank Effective Date:	07/01/2022
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	34831
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	SETON HOSPITAL
Address:	1201 W. 38TH ST.
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	03/11/2014
Reason for Inspection:	Complaint
Violation:	Yes
Complaint Date:	3/11/2014
Notification Number:	N/A
ASB Priority:	n/a
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	03
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	04/25/2014
Date Routed by Supervisor:	05/09/2014
Date Routed to PSQA:	05/12/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	2014-04-25 00:00:00
Date Rcvd Back:	2014-04-28 00:00:00
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	11/22/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	09/30/2021
Notification Number:	2021005884
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/03/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/26/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/09/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/15/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2022002053
ASB Priority:	Not reported
PIF State:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/12/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/13/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/15/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/15/2022
Notification Number:	2022002053
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/11/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/12/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/15/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	04/14/2022
Notification Number:	2022002053
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/25/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/25/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/11/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	05/12/2022
Notification Number:	2022002801
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/27/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/27/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/07/28
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	07/28/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017004231
File Number:	20725
License Status Description:	Paid
Expiration Date:	07/28/2017
Original Date:	06/05/2017
Rank Effective Date:	06/05/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	7266
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/04/13
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/13/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017009926
File Number:	26803
License Status Description:	Paid
Expiration Date:	04/30/2018
Original Date:	12/28/2017
Rank Effective Date:	12/28/2017
Mod Code:	ANOT

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	10040
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/02/17
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	02/17/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017009926
File Number:	26803
License Status Description:	Paid
Expiration Date:	04/30/2018
Original Date:	12/28/2017
Rank Effective Date:	12/28/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	9405
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2018/01/25
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/25/2018
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017009926
File Number:	26803
License Status Description:	Paid
Expiration Date:	04/30/2018
Original Date:	12/28/2017
Rank Effective Date:	12/28/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	11552
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/08/27
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	08/27/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019006148
File Number:	44311
License Status Description:	Paid
Expiration Date:	08/27/2019
Original Date:	08/12/2019
Rank Effective Date:	08/12/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	18106
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/23/2019

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Number:	2019004865
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/28/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	07/22/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	07/03/2019
Notification Number:	2019004865
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/17/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	07/01/2019
Client Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/26/2020
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	08/27/2019
Notification Number:	2019006148
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/12/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/12/2019
Certification Statement Phone:	512-260-7171

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/27/2021
Reason for Inspection:	Cheni Vazquez
Violation:	Not reported
Complaint Date:	05/08/2020
Notification Number:	2020002223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/27/2020
Certification Statement Phone:	704-960-2623
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/27/2021
Reason for Inspection:	Cheni Vazquez
Violation:	Not reported
Complaint Date:	05/08/2020
Notification Number:	2020002223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/20/2020
Certification Statement Phone:	704-960-2623
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	04/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Name:	SEATON HEALTHCARE FAMILY - CAPITAL CRAWLSPACE PROJECT
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/27/2021
Reason for Inspection:	Cheni Vazquez
Violation:	Not reported
Complaint Date:	05/29/2020
Notification Number:	2020002223
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/12/2020
Certification Statement Phone:	704-273-1500
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/27/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/31/2021
Reason for Inspection:	Cheni Vazquez
Violation:	Not reported
Complaint Date:	06/12/2020
Notification Number:	2020003085
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/22/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/22/2020
Certification Statement Phone:	704-960-2623
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	05/31/2021
Reason for Inspection:	Cheni Vazquez
Violation:	Not reported
Complaint Date:	06/12/2020
Notification Number:	2020003085
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/27/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/27/2020
Certification Statement Phone:	704-960-2623
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	05/11/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	04/20/2022
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/27/2020
Notification Number:	2020007690
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/11/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/11/2020
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/27/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	10/26/2022
Reason for Inspection:	Jimmy Stafford

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Violation:	Not reported
Complaint Date:	08/06/2021
Notification Number:	2021005068
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/21/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	07/21/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/04/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/22/2022
Notification Number:	2022006550
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/09/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Start Date:	10/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/11/2022
Notification Number:	2022006895
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/09/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Certification Statement Date:	11/09/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/11/2022
Notification Number:	2022006895
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/28/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/11/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION PARKING GARAGE
Address:	1201 W. 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	11/23/2022
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	01/22/2023
Notification Number:	2022006908
ASB Priority:	Not reported
PIF State:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/18/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/18/2022
Certification Statement Phone:	5122124994
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/22/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ASCENSION PARKING GARAGE
Address:	1201 W. 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	11/23/2022
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	01/22/2023
Notification Number:	2022006908
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/11/2022
Certification Statement Phone:	3163050593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/21/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION PARKING GARAGE
Address:	1201 W. 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	11/23/2022
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	01/22/2023
Notification Number:	2022006908
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	11/11/2022
Certification Statement Phone:	3163050593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/18/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION PARKING GARAGE
Address:	1201 W. 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	11/23/2022
Reason for Inspection:	Josh Hook
Violation:	Not reported
Complaint Date:	01/15/2023
Notification Number:	2022006908
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/31/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	10/31/2022
Certification Statement Phone:	3163050593
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/02/2022
Notification Number:	2022007170
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/29/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/29/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W. 38TH STREET

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	12/02/2022
Notification Number:	2022007170
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/14/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/14/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	4
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/28/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER AUSTIN - 2ND PHASE
Address:	1201 W. 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	03/04/2017
Notification Number:	2017000509
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/19/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/19/2017
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	02/04/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/28/2019
Notification Number:	2018007927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/08/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/08/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/14/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/07/2019
Notification Number:	2018007927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Date Report Received:	11/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/06/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	13
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/14/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/31/2019

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Notification Number:	2018007927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/04/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/04/2018
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/14/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	02/28/2019
Notification Number:	2018007927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/15/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/15/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/14/2018
Client Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	SETON MEDICAL CENTER - AUSTIN
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Date of inspection:	09/04/2019
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/07/2019
Notification Number:	2018007927
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/24/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/24/2018
Certification Statement Phone:	512-260-7171

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	13
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	11/07/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	276339
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2022
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSCAYWR002
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	258308
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2021
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	IPSILLSCAYWR001
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	246182
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2020
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003207103
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	222268
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2019
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	003207102
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	203773
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2018
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	003207101
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	216133
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2018
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Policy Number:	003207101
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	187571
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2017
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 617 3915680
Policy Number:	003207100
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	170077
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/05/2016
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/05/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Region:	2
Facility ID:	86372
Finass ID:	152409
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2015
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	117678
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2013
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	12082
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	12/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	72370
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	72369
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	72371
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Region:	2
Facility ID:	86372
Finass ID:	72372
AI:	56515
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	10/06/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Ind. Haz Waste:

Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX 78705
Permit Number:	Not reported
Registration Number:	70743

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Registration Initial Notification Date:	11/21/1986
Registration Last Amendment Date:	11/17/2022
EPA Identification:	TXD078495868
Primary NAICS Code:	622110
Status Change Date:	19861121
Land Type:	PRIVATE
Description of Facility Site Location:	1201 38TH ST W AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	ASCENSION SETON
Contact Name:	KERI JONES
Contact Telephone Number:	409-7285444
Mailing Address:	1201 W 38TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787051006
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25551
Site Owner Tax ID:	741109643
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20221117
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	ASCENSION SETON
Operator Address:	1345 PHILOMENA ST # 357
Operator Address 2:	Not reported
Operator Address 3:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Operator City,State,Zip:	AUSTIN, TX 78723
Operator Country:	UNITED STA
Operator Telephone:	1-512-9342918
Operator Fax Number:	Not reported
Operator Email:	MARK.WEHNER@MEDXCEL.COM
Operator Business Type:	Corporation
Operator Tax ID:	17411096435
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ASCENSION SETON
Owner Mailing Address:	1345 PHILOMENA ST # 357
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78723
Owner Country:	UNITED STA
Owner Telephone:	1-512-9342918
Owner Fax:	Not reported
Owner Email Address:	MARK.WEHNER@MEDXCEL.COM
Owner Business Type:	Corporation
Owner Tax ID:	17411096435
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Includes adjacent indoor and outdoor storage areas.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940920
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	03
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Compactor/dumpster located behind facility at shipping and loading ducks.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19970627
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	50
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	SATELLITE ACCUMULATION AREA FOR MERCURIC CHLORIDE WASTE (0018117H) LOCATED AT LA
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20000809
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	004
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	10
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

System Type Code 1:	010
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	IN-DRUM PERMIT EXEMPT TREATMENT OF CHARACTERISTICALLY HAZARDOUS SO WASTE (001
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20000809
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	1345 PHILOMENA ST # 357
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78723
Contact Phone:	1-512-9342918
Contact Fax:	Not reported
Contact Email:	MARK.WEHNER@MEDXCEL.COM

Contact Name:	KERI JONES
Contact Title:	BUILDING MANAGER
Contact Role:	PRICONT
Contact Address:	1201 W 38TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78705
Contact Phone:	1-409-7285444
Contact Fax:	Not reported
Contact Email:	KERI.JONES@MEDXCEL.COM

Ind. Haz Waste:

Waste ID:	92523
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Laboratory solvents
Standard Industrial Code:	80620
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Xylene
Primary NAICS Code:	622110

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	92524
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used Oil with Solvents. Initial generation 1990.; One time shipment.
Standard Industrial Code:	80620
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Used Oil and Solvents.
Primary NAICS Code:	622110
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	OTS

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	92525
Texas Waste Code:	Not reported
Texas Waste Code 2:	00033081
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty Drums. Initial generation 1991.; A new hazardous waste determination has
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Empty Drums
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Reason Waste Form No Longer Gen: RECLASSIFIED

Ind. Haz Waste:

Waste ID: 122000
Texas Waste Code: Not reported
Texas Waste Code 2: 0009309H
Waste Code Status: INACTIVE
Waste Form: 309
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Mercury batteries / depletion of battery use / 1994; Due to change(s) in the pro
Standard Industrial Code: 80620
Primary Source: G16
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Not reported
Primary NAICS Code: 622110
EPA Waste Form Code: W309
Reason Waste Form No Longer Gen: PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID: 92528
Texas Waste Code: Not reported
Texas Waste Code 2: 0010003H
Waste Code Status: ACTIVE
Waste Form: 003
Waste Classification: H
Waste is Radioactive: 0
Waste Treated Off Site: Not reported
Generators Waste Description: Hazardous mixed lab pack
Standard Industrial Code: 80620
Primary Source: G11
Primary Measurement Point: Not reported
Primary Origin: 1
Primary System Type: Not reported
New Chemical Substance: 0
Audit Performed: 0
Company Waste ID: Hazardous Lab Pack
Primary NAICS Code: 622110
EPA Waste Form Code: W001
Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Ind. Haz Waste:

Waste ID:	92530
Texas Waste Code:	Not reported
Texas Waste Code 2:	00110031
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Non-Hazardous mixed Lab Pack. Out of date materials 1994.; A new hazardous waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Non-Hazardous Lab Pack
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Waste ID:	92531
Texas Waste Code:	Not reported
Texas Waste Code 2:	00123191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Class 1 Non-Hazardous materials. 1994.; A new hazardous waste determination has
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Class 1 Non-Haz Solids
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Waste ID:	92532
Texas Waste Code:	Not reported
Texas Waste Code 2:	00133091
Waste Code Status:	INACTIVE
Waste Form:	309

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Alkaline and Zinc Batteries, 1994.; A new hazardous waste determination has bee
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Alkaline and Zine Batteries.
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	RECLASSIFIED

Ind. Haz Waste:

Waste ID:	120840
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Photo processing waste / generated during photographic processing. 1994; Due to
Standard Industrial Code:	80620
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161473
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Painting and clean-up/5-96/liquidChanging to universal paint waste. Inactivate3

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Standard Industrial Code:	80620
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161472
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Painting and clean-up/5-96/Solid with small amount of liquids; Hazardous waste c
Standard Industrial Code:	80620
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Ind. Haz Waste:

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste ID:	161471
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018117H
Waste Code Status:	INACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mercuric chloride waste generated from use as a fixative in tissue preparation 5
Standard Industrial Code:	80620
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	161470
Texas Waste Code:	Not reported
Texas Waste Code 2:	00199992
Waste Code Status:	ACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant production and office refuse generated during routine operations.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	161469
Texas Waste Code:	Not reported
Texas Waste Code 2:	00209022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Supplemental plant production refuse generated during routine operations.; Due t
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Waste ID:	164227
Texas Waste Code:	Not reported
Texas Waste Code 2:	0021219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	RCRA-regulated chemotherapy agents, non-trace, non-infecteous, no-sharps
Standard Industrial Code:	80620
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Non-trace chemotherapy
Primary NAICS Code:	622110
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	184616
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Off-spec latex paints occasionally contaminated with small quantities

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

	of oil-bas
Standard Industrial Code:	80620
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Latex paint with low solvents
Primary NAICS Code:	622110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNIV WASTE ONLY

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	190840
Texas Waste Code:	Not reported
Texas Waste Code 2:	00231142
Waste Code Status:	INACTIVE
Waste Form:	114
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Contaminated water from elevator shafts and other on site sources, not to contai
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	1
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Waste ID:	197258
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024489H
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Petroleum contaminated solids. Generating process: oil filters; Hazardous waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	622110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	EXEMPTION

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	234630
Texas Waste Code:	Not reported
Texas Waste Code 2:	0025319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Decommissioned mercury-containing apparatus and spill clean up materials
Standard Industrial Code:	Not reported
Primary Source:	G15
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MERCURY APPARATUS
Primary NAICS Code:	622110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	234631
Texas Waste Code:	Not reported
Texas Waste Code 2:	0026319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	X-ray vests are sent off site where the lead is extracted and recycled.
Standard Industrial Code:	Not reported
Primary Source:	G11

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	X-RAY VESTS
Primary NAICS Code:	622110
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	358800
Texas Waste Code:	Not reported
Texas Waste Code 2:	0027004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Unused RCRA-regulated waste pharmaceuticals
Standard Industrial Code:	Not reported
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HAZ RX WASTE
Primary NAICS Code:	622110
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Ind. Haz Waste:

Waste ID:	402317
Texas Waste Code:	Not reported
Texas Waste Code 2:	0028101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous waste with low organics and solvents contaminated with chromium and silv
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	VENTANA STAINER
Primary NAICS Code:	621511
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	412360
Texas Waste Code:	Not reported
Texas Waste Code 2:	0029104H
Waste Code Status:	ACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent "RDO" bone decalcifier (HCl) and other compatible acid wastes
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT ACID WASTE
Primary NAICS Code:	622110
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste ID:	435160
Texas Waste Code:	Not reported
Texas Waste Code 2:	00314892
Waste Code Status:	ACTIVE
Waste Form:	489
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Clay absorbent contaminated with diesel fuel and water
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	ABSORBENT W DIESEL
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	435303
Texas Waste Code:	Not reported
Texas Waste Code 2:	0032489H
Waste Code Status:	ACTIVE
Waste Form:	489
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Clay absorbent used to clean up a diesel spill
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	DIESEL AND ABSORBENT
Primary NAICS Code:	622110
EPA Waste Form Code:	W310
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	264040
Texas Waste Code:	Not reported
Texas Waste Code 2:	C4ZX0091
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	263018
Texas Waste Code:	Not reported
Texas Waste Code 2:	C5PX009H
Waste Code Status:	Not reported
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	268600
Texas Waste Code:	Not reported
Texas Waste Code 2:	CDFV3091
Waste Code Status:	Not reported
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste ID:	268601
Texas Waste Code:	Not reported
Texas Waste Code 2:	CDFW3091
Waste Code Status:	Not reported
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	268602
Texas Waste Code:	Not reported
Texas Waste Code 2:	CDFX309H
Waste Code Status:	Not reported
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287213
Texas Waste Code:	Not reported
Texas Waste Code 2:	D6FY117H
Waste Code Status:	Not reported
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	287214
Texas Waste Code:	Not reported
Texas Waste Code 2:	D6FZ319H
Waste Code Status:	Not reported
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	289516
Texas Waste Code:	Not reported
Texas Waste Code 2:	DF4W117H
Waste Code Status:	Not reported
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Ind. Haz Waste:

Waste ID:	311202
Texas Waste Code:	Not reported
Texas Waste Code 2:	DMQP119H
Waste Code Status:	Not reported
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	310672
Texas Waste Code:	Not reported
Texas Waste Code 2:	DNRK101H
Waste Code Status:	Not reported
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	4
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	300345
Texas Waste Code:	Not reported
Texas Waste Code 2:	DS2P205H
Waste Code Status:	Not reported
Waste Form:	205
Waste Classification:	H
Waste is Radioactive:	0

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	KERI JONES
Contact Title:	BUILDING MANAGER
Contact Telephone:	1-409-7285444 x0
Mailing Address:	1201 W 38TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000318920
Principal Name:	ASCENSION SETON
Attention Name:	JONES ,KERI
Attention Suffix:	NWG

Contact Name:	KERI JONES
Contact Title:	BUILDING MANAGER
Contact Telephone:	1-409-7285444 x0
Mailing Address:	1201 W 38TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000318920
Principal Name:	ASCENSION SETON
Attention Name:	JONES ,KERI
Attention Suffix:	HWG

Contact Name:	KERI JONES
Contact Title:	BUILDING MANAGER
Contact Telephone:	1-409-7285444 x0

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

Mailing Address:	1201 W 38TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000307007
Principal Name:	ASCENSION SETON
Attention Name:	JONES ,KERI
Attention Suffix:	NWG
Contact Name:	KERI JONES
Contact Title:	BUILDING MANAGER
Contact Telephone:	1-409-7285444 x0
Mailing Address:	1201 W 38TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78705
AR Number:	0000307007
Principal Name:	ASCENSION SETON
Attention Name:	JONES ,KERI
Attention Suffix:	HWG

WI MANIFEST:

Name:	SETON HEALTH CARE NETWORK
Address:	1201 WEST 38TH STREET
City,State,Zip:	AUSTIN, TX 78705
Year:	2004
EPA ID:	TXD078495868
FID:	0
ACT Code:	202
ACT Status:	A
ACT Code 1:	202
ACT Name:	HW Generator - Small
Contact Title:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact EMail Address:	Not reported

COMP HIST:

RN Number:	RN102338217
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN603421694
CN Name:	J T VAUGHN ENTERPRISES INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	622110

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

SIC Code:	1521
Related Number:	TXD078495868,70743,66709,56515,P04633,P04633

RN Number:	RN102338217
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604424036
CN Name:	SETON MEDICAL CENTER
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	622110
SIC Code:	1521
Related Number:	TXD078495868,70743,66709,56515,P04633,P04633

RN Number:	RN102338217
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN601233364
CN Name:	DCHSA DBA SETON MEDICAL CENTER
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	622110
SIC Code:	1521
Related Number:	TXD078495868,70743,66709,56515,P04633,P04633

RN Number:	RN102338217
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN601238181
CN Name:	ASCENSION SETON
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	622110

ASCENSION SETON MEDICAL CENTER AUSTIN (Continued) **1000337148**

SIC Code:	2051
Related Number:	TXD078495868,70743,66709,56515,P04633,P04633
RN Number:	RN102338217
Name:	ASCENSION SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604397935
CN Name:	ASCENSION TEXAS
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	622110
SIC Code:	2051
Related Number:	TXD078495868,70743,66709,56515,P04633,P04633

SM3051 **W. F. SMITH** **TX HIST UST** **S128729200**
WNW **1201 W 38TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.208 mi.
1098 ft. **Site 2 of 3 in cluster SM**

Actual:
597 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	W. F. SMITH
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0161
HID UST:	161
Inspection:	Not reported
Due:	06/01/2012

SM3052 **SETON MEDICAL CENTER AUSTIN** **TX HIST UST** **S128728597**
WNW **1201 W 38TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.208 mi.
1098 ft. **Site 3 of 3 in cluster SM**

Actual:
597 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	SETON MEDICAL CENTER AUSTIN
Address:	1201 W 38TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	1018
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SJ3053 **SALTILLO PLAZA-DOWNTOWN RAILYARD** **US BROWNFIELDS** **1015985728**
East **1000 E. 4TH STREET** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.208 mi.
1098 ft. **Site 2 of 3 in cluster SJ**

Actual:
469 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	1080000
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Local Funding
Redevelopment Start Date:	10/10/2012
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96671601
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.

Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49
Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

	previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	4320000
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Other Federal Funding
Redevelopment Start Date:	10/10/2012
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96671601
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49
Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.

Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6725
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	96671601
Start Date:	5/21/2011
Ownership Entity:	Government
Completion Date:	8/31/2011
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Assessment Funding:	4359
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	96671601
Start Date:	6/6/2011
Ownership Entity:	Government
Completion Date:	7/13/2011
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.

Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49
Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

	previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	5538
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	96671601
Start Date:	6/15/2011
Ownership Entity:	Government
Completion Date:	8/31/2011
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49
Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

Name:	SALTILLO PLAZA-DOWNTOWN RAILYARD
Address:	1000 E. 4TH STREET
Recipient name:	Texas Commission on Environmental Quality
Grant type:	Section 128(a) State/Tribal
Region:	6
Property Number:	Not reported
Parcel size:	12
Latitude:	30.263569
Longitude:	-97.732652
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	CapMetro, the transit authority in Austin, TX is approved for 5.4M from the Federal Transit Authority to design and construct double

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

railroad tracks from Plaza Saltillo light rail commuter station to I-35. Approval to draw down 5.4M was recently given to CapMetro by FTA in October 2012. Jobs created will be added during the design and construction phases of this project. Former Use: The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.

Datum:	North American Datum of 1983
Acres Property ID:	135663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	84927
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - State & Tribal Section 128(a) Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	96671601
Start Date:	1/1/2012
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	Capital Metro
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	N

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	5/28/2011
State/tribal program ID:	G131
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	12
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The Plaza Saltillo Railyard Property Site is made up of approximately 12 acres of land located in the area of 4th and 5th Streets, east of Interstate 35, in Austin, TX. The site is primarily vacant land with unpaved parking areas and five leased portions comprised of a scrap metal yard staging area, a market/art gallery, a construction staging area, a scrap yard parking/staging area, and a commercially leased property that appears to be utilized as a residence. On the northern portion of the Site, an active railroad line operated by Capital Metro. The Site is bordered on the north by 5th Street, on the west by IH-35, on the east by Onion Street and on the south by 4th Street. The Phase I Environmental Site Assessment ESA identified many potential RECs at the site based on historical and present day uses. RECs include oil storage/transfer, coal storage, railroad roundhouse, transloading activities typically associated with rail yards and light industrial activities, and scrap metal processing. Also, issues identified in previously completed environmental reports indicate the site may have elevated concentrations of chemicals of concern, primarily lead and mercury in the on-Site soil, documentation of improper waste disposal activities, and a diesel spill reported at 1000 East 4th Street. Several underground storage tanks USTs were reportedly located on or immediately adjacent to the Site and their status and/or presence has not been verified. Without further investigation, these USTs constitute a REC. The VCP/LPST property historic coal gasification facility, currently Austin Metal & Iron Co. located adjacent and to the south, is a potential off-Site REC.
Below Poverty Number:	817
Below Poverty Percent:	23.77
Meidan Income:	10368
Meidan Income Number:	1151
Meidan Income Percent:	33.49

SALTILLO PLAZA-DOWNTOWN RAILYARD (Continued) **1015985728**

Vacant Housing Number:	369
Vacant Housing Percent:	18.08
Unemployed Number:	191
Unemployed Percent:	5.56

SJ3054 **SOUTHERN OIL** **TX HIST UST** **S111678807**
East **1000 E 4TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.208 mi.
1098 ft. **Site 3 of 3 in cluster SJ**

Actual:
469 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SOUTHERN OIL
Address:	1000 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0003
HID UST:	3
Inspection:	03/04/2010
Due:	03/04/2013

SN3055 **GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR** **TX UST** **1000414517**
NNE **817 W HOWARD LN** **RCRA NonGen / NLR** **TXD002775757**
1/8-1/4 **AUSTIN, TX 78753** **FINDS**
0.209 mi. **ECHO**
1102 ft. **Site 1 of 3 in cluster SN** **TX GCC**

Actual:
760 ft.

Focus Map:
2

UST:

Name:	MTM TRANSIT
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 787531052
AI Number:	14678
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	08/13/1986
Facility Status:	ACTIVE
Additional ID:	644605812002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	MIKE HALIK,MAINTENANCE MANAGER
Contact Organization Name:	MTM TRANSIT
Contact Mailing Address1:	817 W HOWARD LN
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 787531052
Contact Telephone:	5857505250
Facility Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1986
Signature Name/Title On Earliest Reg Form:	RALPH POSEY,SAFETY OFCR

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	259351292014118
Additional ID:	644605812002053
Ai Number:	14678
Operator CN:	CN604563171
Operator Name:	MTM TRANSIT LLC
Operator Effective Begin Date:	05/01/2018
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	CHRIS WESTBROOK/GM
Contact Organization Name:	MTM TRANSIT LLC
Contact Mailing Address (Delivery):	817 W HOWARD LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78753-1052
Contact Phone Country Code:	0
Contact Phone Area Code:	850
Contact Phone Number:	5169989
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	CPWESTBROOK@MTM-INC.NET
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604563171
Owner Last Name:	MTM TRANSIT LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	817 W HOWARD LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78753
Contact Mailing Zip5:	1052
Contact Phone Number/Ext:	0 850 5169989/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	CPWESTBROOK@MTM-INC.NET
Contact Address Deliverable:	Not reported
Princ ID:	259351292014118
Additional ID:	644605812002053
AI Number:	14678
Owner Effective Begin Date:	05/01/2018
State Tax ID:	32051953613
Contact Role:	OWNOPRCON
Contact Name/Title:	CHRIS WESTBROOK/GM
Contact Organization Name:	MTM TRANSIT LLC

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Tank:

Install Date:	01/01/1975
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1250
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	37706
Facility ID:	53337
Ai Number:	14678
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/05/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	Y
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/01/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	1250
UST Comprt ID:	43055
UST ID:	37706
AI Number:	14678
Compartment ID:	A
Substance Stored1:	WASTE ALK. DISPERSIN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	5756
Cert ID:	344880
UST Comprt ID:	1002048
UST ID:	159142
AI Number:	14678
Tank ID:	4

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167969
UST Comprt ID:	482803
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	379755
UST Comprt ID:	1107443
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167970
UST Comprt ID:	482802
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167971
UST Comprt ID:	482801
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167972
UST Comprt ID:	482800
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167973
UST Comprt ID:	482799
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	226441
UST Comprt ID:	649868
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Self Cert ID:	5756
Cert ID:	243288
UST Comprt ID:	699179
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	260847
UST Comprt ID:	750810
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	278434
UST Comprt ID:	802677
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	295151
UST Comprt ID:	852373
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	312219
UST Comprt ID:	903542
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	328530
UST Comprt ID:	952490
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167961
UST Comprt ID:	482809
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Cert ID:	167962
UST Comprt ID:	482810
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167963
UST Comprt ID:	482811
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167964
UST Comprt ID:	482808
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167965
UST Comprt ID:	482807
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167966
UST Comprt ID:	482806
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167967
UST Comprt ID:	482805
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	167968
UST Comprt ID:	482804
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A
Self Cert ID:	5756
Cert ID:	361916

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

UST Comprt ID:	1053258
UST ID:	159142
AI Number:	14678
Tank ID:	4
Compartment ID:	A

Construction Notification:

NOC ID:	40927
Facility ID:	53337
AI Number:	14678
Application Received Date:	12/20/2022
Scheduled Construction Date:	11/15/2018
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	Y
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	10/16/2019
Signature Date On Form:	10/16/2019
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	MTM TRANSIT LLC
Owner CN At Time Of Construction:	CN604563171
Owner AR At Time Of Construction:	81208
General Desc Of Prop Construct: AST Inst:	

NOC ID:	35562
Facility ID:	53337
AI Number:	14678
Application Received Date:	10/16/2019
Scheduled Construction Date:	10/23/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	Y
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	10/16/2019
Signature Date On Form:	10/16/2019

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	RIDE RIGHT LLC
Owner CN At Time Of Construction:	CN604563171
Owner AR At Time Of Construction:	81208
General Desc Of Prop Construct:	INSTALL A 6000 GALLON UL2085 FOR REFUELING CUSTOMER REQUEST 30 DAY WAIVER TO INSTALL TANK 10/23/2019

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	84211
UST ID:	Not reported
NOC ID:	35562
AI Number:	14678
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	RICAHRD ROLLINS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Facility Billing Contacts:

Contact Organization Name:	MTM TRANSIT LLC
Contact Mailing Address (Delivery):	817 W HOWARD LN
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 1052
Phone Number/Ext:	850 5169989/0
Contact Fax Number/Ext:	/
Contact Email Address:	CPWESTBROOK@MTM-INC.NET
Contact Address Deliverable:	Y
Facility ID:	53337
Additional ID:	644605812002053
Princ ID:	259351292014118
AI Number:	14678
Facility Name:	MTM TRANSIT
AR Number:	81208
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	CHRIS WESTBROOK/GM

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

RCRA Listings:

Date Form Received by Agency:	20200323
Handler Name:	Goodrich Aerospace Component Overhaul & Repair
Handler Address:	817 W HOWARD LN
Handler City,State,Zip:	AUSTIN, TX 78753-1052
EPA ID:	TXD002775757
Contact Name:	STEVE VAUGHN
Contact Address:	817 W HOWARD LN
Contact City,State,Zip:	AUSTIN, TX 78753-1052
Contact Telephone:	512-251-3441
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	817 W HOWARD LN
Mailing City,State,Zip:	AUSTIN, TX 78753-1052
Owner Name:	Bf Goodrich Aerospace
Owner Type:	Private
Operator Name:	Bf Goodrich Aerospace
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200408
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U134
Waste Description: Hydrofluoric Acid (C,T) (Or) Hydrogen Fluoride (C,T)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: BF GOODRICH CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 817 DESSAU RD
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BF GOODRICH AEROSPACE
Legal Status: Private
Date Became Current: 20021015
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN
Owner/Operator City,State,Zip: AUSTIN, TX 78753-1052
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BF GOODRICH AEROSPACE
Legal Status: Private
Date Became Current: 20021015
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN
Owner/Operator City,State,Zip: AUSTIN, TX 78753-1052
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BF GOODRICH AEROSPACE
Legal Status: Private
Date Became Current: 20081203
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: B F GOODRICH AEROSPACE
Legal Status: Not reported
Date Became Current: 20021015
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GOODRICH AEROSPACE COMPONENT OVERHAUL &
Legal Status: Not reported
Date Became Current: 20021015
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BF GOODRICH AEROSPACE
Legal Status: Private
Date Became Current: 20081203
Date Ended Current: Not reported
Owner/Operator Address: 817 W HOWARD LN
Owner/Operator City,State,Zip: AUSTIN, TX 78753
Owner/Operator Telephone: 512-251-3441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20081203
Handler Name: BFGOODRICH AEROSPACE COMPONENT OVERHAUL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970825
Handler Name: BF GOODRICH AEROSPACE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20021021
Handler Name: BF GOODRICH AEROSPACE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Receive Date: 20021015
Handler Name: GOODRICH AEROSPACE COMPONENT OVERHAUL &
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200323
Handler Name: GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920804
Handler Name: B F GOODRICH AEROSPACE COR
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48819
NAICS Description: OTHER SUPPORT ACTIVITIES FOR AIR TRANSPORTATION

NAICS Code: 8112
NAICS Description: ELECTRONIC AND PRECISION EQUIPMENT REPAIR AND MAINTENANCE

NAICS Code: 811211
NAICS Description: CONSUMER ELECTRONICS REPAIR AND MAINTENANCE

NAICS Code: 81149
NAICS Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005031919

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000414517
Registry ID: 110005031919
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005031919
Name: GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR
Address: 817 W HOWARD LN
City,State,Zip: AUSTIN, TX 78753

GCC:
Name: CASTLEBERRY AVIONICS
Address: 3800 DESSAU
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 095273
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 4/19/1990
Enforcement Status - Level Of Agency Response: 1A -
Enforcement Status - Site Activity Status: 1A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CASTLEBERRY AVIONICS
Address: 3800 DESSAU
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 095273
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 4/19/1990

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **1000414517**

Enforcement Status - Level Of Agency Response:	1A -
Enforcement Status - Site Activity Status:	1A -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

SN3056 **GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR** **TX AST** **S104854549**
NNE **817 W HOWARD LN** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78753** **TX IHW CORR ACTION**
0.209 mi.
1102 ft. **Site 2 of 3 in cluster SN**

Actual:
760 ft.

Focus Map:
2

AST:

Name:	MTM TRANSIT
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 787531052
Facility ID:	53337
Additional ID:	644605812002053
AI Number:	14678
Facility Type:	INDUST/MFG/CHEM PLANT
Facility Begin Date:	08/13/1986
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	AUSTIN
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	MIKE HALIK/MAINTENANCE MANAGER
Contact Organization Name:	MTM TRANSIT
Contact Mailing Address1:	817 W HOWARD LN
Contact Mailing Address2:	Not reported
Contact CityStateZip:	AUSTIN TX 787531052
Contact Telephone:	5857505250
Contact Address Deliverable:	Y
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	04/15/1986
Signature First Name on Earliest Reg Form:	RALPH
Application Received Date on Earliest Reg Form:	05/08/1986
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	POSEY
Signature Title on Earliest Reg Form:	SAFETY OFCR
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Facility:

Facility ID:	53337
Tank ID:	1
AST ID:	227721
AI Number:	14678
Install Date:	11/15/2018
Tank Registration Date:	12/29/2022
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	11/15/2018
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	6000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Ind. Haz Waste:

Name:	GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 78753
Permit Number:	Not reported
Registration Number:	72925
Registration Initial Notification Date:	10/28/1988
Registration Last Amendment Date:	03/23/2020
EPA Identification:	TXD002775757
Primary NAICS Code:	488190
Status Change Date:	19881028
Land Type:	PRIVATE
Description of Facility Site Location:	817 W Howard Ln, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	BF GOODRICH AEROSPACE
Contact Name:	STEVE VAUGHN

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Contact Telephone Number:	512-2513441
Mailing Address:	817 W HOWARD LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787531052
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27361
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200402
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	BF GOODRICH AEROSPACE
Operator Address:	817 W HOWARD LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-2513441
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	13111747773
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	BF GOODRICH AEROSPACE
Owner Mailing Address:	817 W HOWARD LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-2513441
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	13111747773
Owner Bankruptcy Code:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Larger of two portable storage buildings located inside fenced area next to midd
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20021015
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Smaller of two portable storage buildings located inside fenced area next to mid
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20021015
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Contact Role:	OPRCON
Contact Address:	817 W HOWARD LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-2513441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	817 W HOWARD LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-2513441
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	STEVE VAUGHN
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	817 W HOWARD LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-2513441
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	79094
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solcents used in degreasing/cleansing operations (primarily 1,1,1 Trichlor
Standard Industrial Code:	76990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	79096
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002102H
Waste Code Status:	INACTIVE
Waste Form:	102
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Water contaminated with small amounts of Barium and chromium. Product comes fro
Standard Industrial Code:	76990
Primary Source:	G04
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	121243
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent solvents with a collection of no longer useable items. Taken from satelli
Standard Industrial Code:	76990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	129325
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004309H
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead acid batteries removed from computers and emergency lights - began storage1
Standard Industrial Code:	76990
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	130326
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005409H
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Rags from soldering and chemical (i.e. paint /glue) removal. Began generation 1
Standard Industrial Code:	76990
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	136858
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006309H
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Removal of solid and liquid filled nickel-cadmium batteries from customer units.
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	148625
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Began 1/1/96 spent solvents used in cleaning sircraft instrument parts
Standard Industrial Code:	76990
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	151649
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SPENT FLOURESCENT BULBS REMOED FROM FACILITY. BEING RECYCLED
Standard Industrial Code:	76990
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	158307
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab pack of old or no longer used chemicals/ chemical products. Initial generat
Standard Industrial Code:	76990
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	158308
Texas Waste Code:	Not reported
Texas Waste Code 2:	00100011
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lab pack of no longer used or needed products. Initial generation date unknown.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	158309
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113061
Waste Code Status:	INACTIVE
Waste Form:	306
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sodium hydroxide solid material no longer used. Initial generation date unknown
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	166529
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012319H
Waste Code Status:	INACTIVE
Waste Form:	319

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lead foil tape removed from aircraft instrument casings, aircraft unit component
Standard Industrial Code:	76990
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	166531
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013104H
Waste Code Status:	INACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aluminum brightener/cleaner used on aircraft instrument casings. Satellite coll
Standard Industrial Code:	76990
Primary Source:	G02
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	170262
Texas Waste Code:	Not reported
Texas Waste Code 2:	00142961
Waste Code Status:	INACTIVE
Waste Form:	296
Waste Classification:	1

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Antifreeze removed from a unit no longer in use; 4/98
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	170263
Texas Waste Code:	Not reported
Texas Waste Code 2:	00154891
Waste Code Status:	INACTIVE
Waste Form:	489
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Corncob absosrbent used to absorb oils, aviation fuel and/or water; 3/98.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	173525
Texas Waste Code:	Not reported
Texas Waste Code 2:	00162031
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	CT-1 multipurpose cleaner and CT-2 advanced cleaner and water displacement agent
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	196255
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018309H
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Lithium batteries removed form aircraft instuments over an uspecified period.
Standard Industrial Code:	Not reported
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	142154
Texas Waste Code:	Not reported
Texas Waste Code 2:	00493191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Painted dials on old aircraft instruments - typically WW II vintage. Paint is g
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Ind. Haz Waste:

Waste ID:	77203
Texas Waste Code:	Not reported
Texas Waste Code 2:	0050117H
Waste Code Status:	INACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Elemental mercury taken from airspeed manometers as part of manometer cleaning p
Standard Industrial Code:	76990
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	77205
Texas Waste Code:	Not reported
Texas Waste Code 2:	0051002H
Waste Code Status:	INACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Materials contaminated during a mercury spill and cleanup process -- satellite s
Standard Industrial Code:	76990
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Waste ID:	77206
Texas Waste Code:	Not reported
Texas Waste Code 2:	0052009H
Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Material used for etching circuit boards. Material was used over an unspecified
Standard Industrial Code:	76990
Primary Source:	G04
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	77208
Texas Waste Code:	Not reported
Texas Waste Code 2:	0053309H
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Batteries removed from customer units. Accumulation start date insatellite loca
Standard Industrial Code:	76990
Primary Source:	G16
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811211
EPA Waste Form Code:	W309
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	77209
Texas Waste Code:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Texas Waste Code 2:	00543091
Waste Code Status:	INACTIVE
Waste Form:	309
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Batteries removed rom customer units. Accumulation start date in satellite loca
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	195595
Texas Waste Code:	Not reported
Texas Waste Code 2:	09272051
Waste Code Status:	INACTIVE
Waste Form:	205
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Condensation water from compressor with small amounts of oil mixed in.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	196256
Texas Waste Code:	Not reported
Texas Waste Code 2:	1009209H
Waste Code Status:	INACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint no longer in use due to closing of facility.
Standard Industrial Code:	Not reported
Primary Source:	G06

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5250NW 33RD AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	FORT LAUDERDALE, FL 33309
AR Number:	0000307068
Principal Name:	BF GOODRICH AEROSPACE
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	5250NW 33RD AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	FORT LAUDERDALE, FL 33309
AR Number:	0000307068
Principal Name:	BF GOODRICH AEROSPACE
Attention Name:	Not reported
Attention Suffix:	NWG

IHW CORR ACTION:

Name:	GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 78753
Program Id:	72925
Location Desc:	817 W HOWARD LN AUSTIN TX
RN NUM:	RN101492189
Status:	INACTIVE
Status Date:	10/09/2002
EDR Link ID:	72925
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	11/22/2002
Soil COC Class:	Not reported
Soil Remediation:	Not reported

GOODRICH AEROSPACE COMPONENT OVERHAUL & REPAIR (Continued) **S104854549**

GW COC Class:	Not reported
GW Remediation:	Not reported
Name:	CASTLEBERRY INSTRUMTS & AVIONICS
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 78753
Program Id:	T2902
Location Desc:	Not reported
RN NUM:	RN101492189
Status:	INACTIVE
Status Date:	03/26/2013
EDR Link ID:	T2902
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	03/26/2013
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

SN3057 **CASTLEBERRY INSTRUMTS AVIONICS** **TX LPST** **S116703063**
NNE **817 W HOWARD LN** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.209 mi.
1102 ft. **Site 3 of 3 in cluster SN**

Actual:
760 ft.

Focus Map:
2

LPST:

Name:	CASTLEBERRY INSTRUMTS AVIONICS
Address:	817 W HOWARD LN
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0014678
LPST Id:	095273
Facility Location:	817 HOWARD LANE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/16/1990
Entered Date:	04/19/1990
Reported Date:	03/16/1990
Closure Date:	10/08/2002
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	7 - CAS
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	7/1/1P/1/7/1
Coordinators RPR:	MAO
Responsible Party Name:	Not reported
Responsible Party Contact:	RALPH POSEY
Responsible Party Address:	817 HOWARD LN
Responsible Party City,St,Zip:	AUSTIN, TX 78753
Responsible Party Telephone:	/-
Reported Date:	03/16/1990
Case Start Date:	10/08/2002
Reference Number:	RN101492189
Project Manager:	MOGEE

ASBESTOS:

Name:	OMEGA BROAD CASTING

CASTLEBERRY INSTRUMTS AVIONICS (Continued) **S116703063**

Address:	817 W. HOWARD LN.
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	06/07/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013004026
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	06/26/2013
Date Routed by Supervisor:	07/08/2013
Date Routed to PSQA:	07/12/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

CASTLEBERRY INSTRUMTS AVIONICS (Continued) **S116703063**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

SL3058 **BRYANT JANITORIAL SUPPLIERS** **TX Ind. Haz Waste** **S105170326**
ESE **305 E SAINT ELMO RD STE 10** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.210 mi.
1111 ft. **Site 4 of 4 in cluster SL**

Actual:
657 ft.

Focus Map:
18

Ind. Haz Waste:

Name:	BRYANT JANITORIAL SUPPLIERS
Address:	305 E SAINT ELMO RD STE 10
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	52136
Registration Initial Notification Date:	12/07/1992
Registration Last Amendment Date:	11/03/2010
EPA Identification:	Not reported
Primary NAICS Code:	Not reported
Status Change Date:	19921207
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	Not reported
Company Name:	BRYANT JANITORIAL SUPPLIERS
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	305 E ELMO STREET STE 10
Mailing Address2:	STE 10
Mailing City,State,Zip:	AUSTIN, TX 78745
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	18988
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20101103
Ind. Waste Permit Number:	Not reported

BRYANT JANITORIAL SUPPLIERS (Continued) **S105170326**

Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Owner Name:	BRYANT JANITORIAL SUPPLIERS
Owner Mailing Address:	Not reported
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	Not reported
Owner Country:	Not reported
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	ENV MGR
Contact Role:	PRICONT
Contact Address:	305 E ELMO STREET STE 10
Contact Address 2:	STE 10
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78745
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

SI3059 **LOWES OF NE AUSTIN TX 1725** **TX AST** **A100319220**
ESE **13000 N IH 35** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.210 mi.
1111 ft. **Site 2 of 3 in cluster SI**

Actual:
740 ft.

Focus Map:
2

AST:

Name:	LOWES OF NE AUSTIN TX 1725
Address:	13000 N IH 35
City,State,Zip:	AUSTIN, TX 787531030
Facility ID:	122565
Additional ID:	246617592008175
AI Number:	79154
Facility Type:	RETAIL
Facility Begin Date:	05/14/2003
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N

LOWES OF NE AUSTIN TX 1725 (Continued) **A100319220**

UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78753
Contact Name/Title:	/
Contact Organization Name:	LOWES OF NE AUSTIN TX 1725
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5126340070
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	04/11/2008
Signature First Name on Earliest Reg Form:	W LAYNE
Application Received Date on Earliest Reg Form:	04/16/2008
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	ADAMS
Signature Title on Earliest Reg Form:	VP RETAIL
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	122565
Tank ID:	172501
AST ID:	209741
AI Number:	79154
Install Date:	05/14/2003
Tank Registration Date:	04/16/2008
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	05/14/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	1500
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

SI3060 **MURPHY USA 6967** **TX UST** **U003921135**
ESE **13000 S IH 35** **TX Financial Assurance** **N/A**
1/8-1/4 **AUSTIN, TX 78747**
0.210 mi.
1111 ft. **Site 3 of 3 in cluster SI**

Actual:
740 ft.

Focus Map:
2

UST:

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 787471827
AI Number:	76078
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	164634282003307
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78747
Contact Name/Title:	,
Contact Organization Name:	MURPHY USA 6967
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128377178
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/26/2003
Signature Name/Title On Earliest Reg Form:	KEVIN ROUSSEL,MGR
Application Received Date On Earliest Reg Form:	09/29/2003
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	990456742002138
Additional ID:	164634282003307
Ai Number:	76078
Operator CN:	CN601187875
Operator Name:	MURPHY OIL USA INC
Operator Effective Begin Date:	09/26/2003
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	JENNIFER BRIDGES/
Contact Organization Name:	MURPHY OIL USA INC
Contact Mailing Address (Delivery):	200 E PEACH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	EL DORADO AR 71730-5836
Contact Phone Country Code:	1
Contact Phone Area Code:	870
Contact Phone Number:	8757600
Contact Phone Extension:	0
Contact Fax Country Code:	1

MURPHY USA 6967 (Continued) **U003921135**

Contact Fax Area Code:	870
Contact Fax Number:	8757670
Contact Fax Extension:	0
Contact Email Address:	PERMITS_LICENSING@MURPHYUSA.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601187875
Owner Last Name:	MURPHY OIL USA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	200 E PEACH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	EL DORADO
Contact Mailing State:	AR
Contact Mailing Zip:	71730
Contact Mailing Zip5:	5836
Contact Phone Number/Ext:	1 870 8757600/0
Contact Fax Country Code:	1
Contact Fax Number/Ext:	870 8757670/0
Contact Email Address:	PERMITS_LICENSING@MURPHYUSA.COM
Contact Address Deliverable:	Not reported
Princ ID:	990456742002138
Additional ID:	164634282003307
AI Number:	76078
Owner Effective Begin Date:	09/26/2003
State Tax ID:	17107274924
Contact Role:	OWNOPRCON
Contact Name/Title:	JENNIFER BRIDGES/
Contact Organization Name:	MURPHY OIL USA INC

Self Certification:

Self Cert ID:	116722
Cert ID:	376083
AI Number:	76078
Self Certification Date:	09/13/2022
Signature Name/Title:	KRYSTAL TERRELL PERMITS SPECIALIST
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	358668
AI Number:	76078
Self Certification Date:	08/27/2021

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	KRYSTAL TERRELL PERMITS SPECIALIST
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	116722
Cert ID:	342044
AI Number:	76078
Self Certification Date:	09/01/2020
Signature Name/Title:	Krystal Terrell Owner
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	116722
Cert ID:	325290
AI Number:	76078
Self Certification Date:	09/03/2019
Signature Name/Title:	Krystal Terrell Owner
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	116722
Cert ID:	308978
AI Number:	76078
Self Certification Date:	09/06/2018

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	Krystal Terrell Owner
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	291401
AI Number:	76078
Self Certification Date:	09/05/2017
Signature Name/Title:	Krystal Terrell Licnese & Permits Sp
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	274223
AI Number:	76078
Self Certification Date:	09/01/2016
Signature Name/Title:	Anna W Jones Hsse Coordinator
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	257523
AI Number:	76078
Self Certification Date:	09/08/2015

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	Anna W Jones HSSE Coordinator
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	240045
AI Number:	76078
Self Certification Date:	08/08/2014
Signature Name/Title:	Anna W Jones HSSE Coordinator
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	223989
AI Number:	76078
Self Certification Date:	08/23/2013
Signature Name/Title:	Anna W Jones HSSE Coordinator
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	116722
Cert ID:	208814
AI Number:	76078
Self Certification Date:	08/14/2012

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	ANNA W JONES SR ENV SPECIALISLT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208813
AI Number:	76078
Self Certification Date:	08/22/2011
Signature Name/Title:	ANNA W JONES SR ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208812
AI Number:	76078
Self Certification Date:	08/03/2010
Signature Name/Title:	ANNA W JONES SR ENV SPECIALIST
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208811
AI Number:	76078
Self Certification Date:	08/12/2009

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	ANNA W JONES SR. ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208810
AI Number:	76078
Self Certification Date:	08/23/2008
Signature Name/Title:	ANNA W JONES SR. ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208809
AI Number:	76078
Self Certification Date:	08/13/2007
Signature Name/Title:	ANNA W JONES ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208808
AI Number:	76078
Self Certification Date:	08/11/2006

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	ANNA W JONES ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208807
AI Number:	76078
Self Certification Date:	08/04/2005
Signature Name/Title:	ANNA W JONES ENV SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208806
AI Number:	76078
Self Certification Date:	09/09/2004
Signature Name/Title:	ROBERT A METZGER ENVIRONMENTAL COORDI
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	116722
Cert ID:	208805
AI Number:	76078
Self Certification Date:	09/26/2003

MURPHY USA 6967 (Continued) **U003921135**

Signature Name/Title:	KEVIN ROUSSEL
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/13/2003
Tank Registration Date:	09/29/2003
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	202165
Facility ID:	116722
Ai Number:	76078
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	06/13/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

MURPHY USA 6967 (Continued) **U003921135**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	09/05/2003

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	183176
UST ID:	202165
AI Number:	76078
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

MURPHY USA 6967 (Continued) **U003921135**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/11/2003

Install Date:	06/13/2003
Tank Registration Date:	09/29/2003
Number of Compartments:	2
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	202166
Facility ID:	116722
Ai Number:	76078
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	06/13/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y

MURPHY USA 6967 (Continued) **U003921135**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	09/05/2003

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	183177
UST ID:	202166
AI Number:	76078
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/12/2003
Tank ID:	2

MURPHY USA 6967 (Continued) **U003921135**

Tank Capacity:	8000
UST Comprt ID:	183178
UST ID:	202166
AI Number:	76078
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	08/12/2003

Construction Notification:

NOC ID:	20430
Facility ID:	116722
AI Number:	76078
Application Received Date:	08/15/2005
Scheduled Construction Date:	08/15/2005
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N

MURPHY USA 6967 (Continued) **U003921135**

AST Stage I:	N
Historical Tracking Number:	M50815001
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	35198
UST ID:	202165
NOC ID:	Not reported
AI Number:	76078
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001317
Company Name:	MC Services
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	35199
UST ID:	202166
NOC ID:	Not reported
AI Number:	76078
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001317
Company Name:	MC Services
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

MURPHY USA 6967 (Continued) **U003921135**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	21654
UST ID:	Not reported
NOC ID:	20430
AI Number:	76078
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000579
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	50356
UST ID:	202166
NOC ID:	Not reported
AI Number:	76078
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000496
Company Name:	Not reported
Representative Name:	MIKE BEEVERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	50355
UST ID:	202165

MURPHY USA 6967 (Continued) **U003921135**

NOC ID:	Not reported
AI Number:	76078
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000496
Company Name:	Not reported
Representative Name:	MIKE BEEVERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MURPHY OIL USA INC
Contact Mailing Address (Delivery):	200 E PEACH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	EL DORADO, AR 71730 5836
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	116722
Additional ID:	164634282003307
Princ ID:	990456742002138
AI Number:	76078
Facility Name:	MURPHY USA 6967
AR Number:	53479
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ANNA JONES/

TX Financial Assurance 2:

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	273886
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y

MURPHY USA 6967 (Continued) **U003921135**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2022
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/31/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	255404
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	250281
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2022
Ins Premium Pre-Paid For Entire Yr:	No

MURPHY USA 6967 (Continued) **U003921135**

Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	236979
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	218301
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	202303
AI:	76078

MURPHY USA 6967 (Continued) **U003921135**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	184473
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2017
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	161282
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2016
Date Financial Assurance Form Rec:	Not reported

MURPHY USA 6967 (Continued) **U003921135**

Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	148475
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	128095
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/13/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/13/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967

MURPHY USA 6967 (Continued) **U003921135**

Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	113337
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/22/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	15510
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 870 8626411
Policy Number:	None
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	99760
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

MURPHY USA 6967 (Continued) **U003921135**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/11/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 870 8626411
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	99761
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 870 8626411
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	99762
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/19/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 870 8626411
Policy Number:	None

MURPHY USA 6967 (Continued) **U003921135**

Coverage Amount:	1000000
Coverage Expiration Date:	09/19/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	99763
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/08/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 870 8626411
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	11/08/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MURPHY USA 6967
Address:	13000 S IH 35
City,State,Zip:	AUSTIN, TX 78747
Region:	2
Facility ID:	116722
Finass ID:	99764
AI:	76078
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

SK3061 **WAL-MART SUPERCENTER 3569** **TX UST** **U003979460**
East **12900 N IH 35** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78753** **TX Financial Assurance**
0.211 mi.
1116 ft. **Site 3 of 3 in cluster SK**

Actual:
738 ft.

Focus Map:
2

UST:

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 787531049
AI Number:	76874
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	954635462004328
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	SHEILA DEARING,
Contact Organization Name:	WAL-MART SUPERCENTER 3569
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	4792042188
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/16/2004
Signature Name/Title On Earliest Reg Form:	JANET LYNN,DIR OF LICENSING
Application Received Date On Earliest Reg Form:	09/29/2004
Signature Role On Earliest Reg Form:	LEGALLY-AUTHORIZED REP OF OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	627385722007269
Additional ID:	954635462004328
Ai Number:	76874
Operator CN:	CN603246240
Operator Name:	WAL-MART STORES TEXAS LLC
Operator Effective Begin Date:	06/29/2007
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	/
Contact Organization Name:	WALMART STORES TEXAS LLC
Contact Mailing Address (Delivery):	1300 SE 8TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	BENTONVILLE AR 72712-6561
Contact Phone Country Code:	1
Contact Phone Area Code:	479
Contact Phone Number:	2042231
Contact Phone Extension:	0
Contact Fax Country Code:	1

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Contact Fax Area Code:	479
Contact Fax Number:	2775844
Contact Fax Extension:	0
Contact Email Address:	teresa.pruitt@wal-mart.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603246240
Owner Last Name:	WAL-MART STORES TEXAS LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	1300 SE 8TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	BENTONVILLE
Contact Mailing State:	AR
Contact Mailing Zip:	72712
Contact Mailing Zip5:	6561
Contact Phone Number/Ext:	1 479 2042231/0
Contact Fax Country Code:	1
Contact Fax Number/Ext:	479 2775844/0
Contact Email Address:	teresa.pruitt@wal-mart.com
Contact Address Deliverable:	Not reported
Princ ID:	627385722007269
Additional ID:	954635462004328
AI Number:	76874
Owner Effective Begin Date:	06/29/2007
State Tax ID:	17430193866
Contact Role:	OWNOPRCON
Contact Name/Title:	/
Contact Organization Name:	WALMART STORES TEXAS LLC

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/29/2004
Number of Compartments:	1
Tank Capacity:	1
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	203910
Facility ID:	117999
Ai Number:	76874
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	WASTEWATER TREATMENT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	1
UST Comprt ID:	184928
UST ID:	203910
AI Number:	76874
Compartment ID:	A
Substance Stored1:	OIL WATER SEPARATOR
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	29185
Cert ID:	76904
UST Comprt ID:	222082
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76903
UST Comprt ID:	222083
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76902
UST Comprt ID:	222084
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76901
UST Comprt ID:	222085
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Self Cert ID:	29185
Cert ID:	76900
UST Comprt ID:	222086
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	76899
UST Comprt ID:	222087
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	76898
UST Comprt ID:	222088
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	377004
UST Comprt ID:	1098981
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	76897
UST Comprt ID:	222089
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	76896
UST Comprt ID:	222090
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185
Cert ID:	76895
UST Comprt ID:	222091
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Self Cert ID:	29185

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Cert ID:	76894
UST Comprt ID:	222092
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	359495
UST Comprt ID:	1045955
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	344160
UST Comprt ID:	999911
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	325915
UST Comprt ID:	944623
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	309367
UST Comprt ID:	895291
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76893
UST Comprt ID:	222095
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76892
UST Comprt ID:	222094
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	76891

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

UST Comprt ID:	222093
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	293046
UST Comprt ID:	846381
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	276267
UST Comprt ID:	796446
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	259768
UST Comprt ID:	747694
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	243686
UST Comprt ID:	700215
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A
Self Cert ID:	29185
Cert ID:	226171
UST Comprt ID:	649059
UST ID:	71774
AI Number:	76874
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	WAL-MART STORES TEXAS LLC
Contact Mailing Address (Delivery):	8725 ROSEHILL RD STE 450
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	LENEXA, KS 66215 4611
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	117999

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Additional ID:	954635462004328
Princ ID:	627385722007269
AI Number:	76874
Facility Name:	WAL-MART SUPERCENTER 3569
AR Number:	67469
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	/

ASBESTOS:

Name:	WALMART
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Date of inspection:	07/24/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	07/30/2013
Date Routed by Supervisor:	07/30/2013
Date Routed to PSQA:	08/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117999
Finass ID:	255862
AI:	76874
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	INDIAN HARBOR INS CO
Issuer Phone:	Not reported
Policy Number:	pec004100108
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117999
Finass ID:	236358
AI:	76874
Mechanism Type Other:	Not reported

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	INDIAN HARBOR INS CO
Issuer Phone:	Not reported
Policy Number:	PEC004100107
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117999
Finass ID:	219731
AI:	76874
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2019
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	INDIAN HARBOR INS CO
Issuer Phone:	Not reported
Policy Number:	PEC004100106
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	WAL-MART SUPERCENTER 3569
Address:	12900 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	117999
Finass ID:	149351
AI:	76874
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/30/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	INDIAN HARBOR INS CO

WAL-MART SUPERCENTER 3569 (Continued) **U003979460**

Issuer Phone:	Not reported
Policy Number:	PEC004100102
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/30/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SA3062 **TECHNICAL COATING** **TX HIST UST** **S123848192**
ESE **312 INDUSTRIAL BLVD** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78701**
0.212 mi.
1118 ft. **Site 4 of 4 in cluster SA**

Actual:
668 ft.

Focus Map:
18

HIST UST AUSTIN:

Name:	TCI COATINGS, INC.
Address:	312 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	481
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100719483
Name:	TECHNICAL COATING
Address:	312 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78701
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600929129
Customer Name:	TECHNICAL COATINGS INC
Customer Legal Name:	Technical Coatings, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	325510
Primary NAICS Industry Type Description:	Paint and Coating Manufacturing
Physical Location Description:	312 INDUSTRIAL BLVD

3063 **ABIA CLEAN FUEL CENTER** **TX HIST UST** **S128728858**
West **3100.5 SPIRIT OF TEXAS DR.** **N/A**
1/8-1/4 **AUSTIN, TX**
0.212 mi.
1119 ft.

Actual:
508 ft.

Focus Map:
20

HIST UST AUSTIN:

Name:	ABIA CLEAN FUEL CENTER
Address:	3100.5 SPIRIT OF TEXAS DR.
City,State,Zip:	AUSTIN, TX
Id UST:	A0033
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SO3064 **WALKER TIRE** **TX UST** **U001440750**
NE **814 IH BLVD # 35** **N/A**
1/8-1/4 **AUSTIN, TX 78721**
0.213 mi.
1124 ft. **Site 1 of 2 in cluster SO**

Actual:
472 ft.

Focus Map:
11

UST:

Name:	WALKER TIRE
Address:	814 IH BLVD # 35
City,State,Zip:	AUSTIN, TX 787213627
AI Number:	64486
Facility Type:	RETAIL
Facility Begin Date:	04/26/1993
Facility Status:	INACTIVE
Additional ID:	787105062002069
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	WALKER TIRE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124761545
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/20/1993
Signature Name/Title On Earliest Reg Form:	ODIS WALKER,OWNER
Application Received Date On Earliest Reg Form:	04/23/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600883805
Owner Last Name:	WALKER
Owner First Name:	ODIS
Owner Middle Name:	Not reported
Owner Type:	IN
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	776105052002069
Additional ID:	787105062002069

WALKER TIRE (Continued) **U001440750**

AI Number:	64486
Owner Effective Begin Date:	04/26/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1983
Tank Registration Date:	04/23/1993
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	G
UST ID:	148158
Facility ID:	95709
Ai Number:	64486
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/15/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

WALKER TIRE (Continued) **U001440750**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/14/1993

Compartment Records:

Tank ID:	3
Tank Capacity:	550
UST Comprt ID:	164062
UST ID:	148158
AI Number:	64486
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

WALKER TIRE (Continued) **U001440750**

Install Date:	01/01/1983
Tank Registration Date:	04/23/1993
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	148159
Facility ID:	95709
Ai Number:	64486
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/09/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

WALKER TIRE (Continued) **U001440750**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/14/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	164063
UST ID:	148159
AI Number:	64486
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1983
Tank Registration Date:	04/23/1993
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	148160

WALKER TIRE (Continued) **U001440750**

Facility ID:	95709
Ai Number:	64486
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/09/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	04/14/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	10000

WALKER TIRE (Continued) **U001440750**

UST Comprt ID:	164064
UST ID:	148160
AI Number:	64486
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WALKER ODIS
Contact Mailing Address (Delivery):	4017 BROOKVIEW RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78722 1215
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	95709
Additional ID:	787105062002069
Princ ID:	776105052002069
AI Number:	64486
Facility Name:	WALKER TIRE
AR Number:	Not reported
AR UST Number Suffix:	Not reported

WALKER TIRE (Continued) **U001440750**

AR AST Number Suffix: Not reported
Contact Name/Title: ODIS WALKER/

SP3065 **DON STEWART TEXACO** **TX RDR** **S127533723**
SSW **7110 E BEN WHITE** **N/A**
1/8-1/4 **AUSTIN, TX**
0.214 mi.
1131 ft. **Site 1 of 3 in cluster SP**

Actual:
584 ft.

Focus Map:
19

RDR:

RDR ID:	6490
Facility ID:	45535
RN:	Not reported
CN:	Not reported
Name:	DON STEWART TEXACO
Address:	7110 E BEN WHITE
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/4/2003
Due Date:	11/3/2003
Tank Owner:	DON STEWART
Contact Person:	DON STEWART
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/5/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NO SUMMARY. RDR 1ST RECD 6/5/01; RDR 1ST RTND 3/21/2003; TO DKC FOR 2ND REVIEW ON 2/21/03. 2ND RTN TO JES 5/19;9/04/03
Review Coordinator:	PPC/MAL/SL
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/5/2005
Date Report Returned:	5/21/2003
Region:	Not reported
DKC RDR (misfiled):	Not reported

SP3066 **CHAMELEON 71** **TX UST** **U001277126**
SSW **7110 E BEN WHITE BLVD** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78741** **TX Financial Assurance**
0.214 mi. **TX NON REGIST PST**
1131 ft. **Site 2 of 3 in cluster SP**

Actual:
584 ft.

Focus Map:
19

UST:

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787417708
AI Number:	45535
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/01/1986
Facility Status:	INACTIVE
Additional ID:	364830692002152
Facility Exempt Status:	N

CHAMELEON 71 (Continued) **U001277126**

Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	LILY SHARP,
Contact Organization Name:	CHAMELEON 71
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127849515
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	ADMIN@!CHAMELEONGP.COM
Signature Date On Earliest Reg Form:	01/17/2020
Signature Name/Title On Earliest Reg Form:	STUART THOMAJAN,REPRESENTATIVE
Application Received Date On Earliest Reg Form:	01/22/2020
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	505476432018243
Additional ID:	364830692002152
Ai Number:	45535
Operator CN:	CN605565480
Operator Name:	CHAMELEON 71 LP
Operator Effective Begin Date:	05/01/2017
Operator Type:	PA
Operator Role:	OWNOPRCON
Contact Name:	LILY SHARP/
Contact Organization Name:	CHAMELEON 71 LP
Contact Mailing Address (Delivery):	PO BOX 38
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78767-0038
Contact Phone Country Code:	0
Contact Phone Area Code:	512
Contact Phone Number:	7849515
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	ADMIN@CHAMELEONGP.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605565480
Owner Last Name:	CHAMELEON 71 LP
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	PO BOX 38

CHAMELEON 71 (Continued) **U001277126**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78767
Contact Mailing Zip5:	0038
Contact Phone Number/Ext:	0 512 7849515/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	ADMIN@CHAMELEONGP.COM
Contact Address Deliverable:	Not reported
Princ ID:	505476432018243
Additional ID:	364830692002152
AI Number:	45535
Owner Effective Begin Date:	05/01/2017
State Tax ID:	32056407433
Contact Role:	OWNOPRCON
Contact Name/Title:	LILY SHARP/
Contact Organization Name:	CHAMELEON 71 LP

Self Certification:

Self Cert ID:	67610
Cert ID:	220446
AI Number:	45535
Self Certification Date:	05/29/2013
Signature Name/Title:	DOUG STATON MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	67610
Cert ID:	85075
AI Number:	45535
Self Certification Date:	07/31/2012
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CHAMELEON 71 (Continued) **U001277126**

Self Cert ID:	67610
Cert ID:	85074
AI Number:	45535
Self Certification Date:	07/28/2011
Signature Name/Title:	DOUG STATON GENERAL MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85073
AI Number:	45535
Self Certification Date:	08/19/2010
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85072
AI Number:	45535
Self Certification Date:	09/01/2009
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CHAMELEON 71 (Continued) **U001277126**

Self Cert ID:	67610
Cert ID:	85071
AI Number:	45535
Self Certification Date:	08/01/2008
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85070
AI Number:	45535
Self Certification Date:	08/28/2007
Signature Name/Title:	DOUG STATON GM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85069
AI Number:	45535
Self Certification Date:	08/31/2006
Signature Name/Title:	DOUG STATON GENERAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CHAMELEON 71 (Continued) **U001277126**

Self Cert ID:	67610
Cert ID:	85068
AI Number:	45535
Self Certification Date:	07/07/2005
Signature Name/Title:	DOUG STATON GEN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85067
AI Number:	45535
Self Certification Date:	07/07/2004
Signature Name/Title:	DOUGLAS STATON GM
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85066
AI Number:	45535
Self Certification Date:	08/04/2003
Signature Name/Title:	DOUGLAS STATON GEN MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

CHAMELEON 71 (Continued) **U001277126**

Self Cert ID:	67610
Cert ID:	85065
AI Number:	45535
Self Certification Date:	09/10/2002
Signature Name/Title:	DOUGLAS STATON SALES MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	67610
Cert ID:	85064
AI Number:	45535
Self Certification Date:	08/07/2001
Signature Name/Title:	DOUG STATON SALES MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1986
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119259
Facility ID:	67610
Ai Number:	45535
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y

CHAMELEON 71 (Continued) **U001277126**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	93271
UST ID:	119259
AI Number:	45535
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

CHAMELEON 71 (Continued) **U001277126**

CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1986

Install Date:	01/01/1986
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119260
Facility ID:	67610
Ai Number:	45535
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

CHAMELEON 71 (Continued) **U001277126**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	93272
UST ID:	119260
AI Number:	45535
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

CHAMELEON 71 (Continued) **U001277126**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1986

Install Date:	01/01/1986
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119261
Facility ID:	67610
Ai Number:	45535
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

CHAMELEON 71 (Continued) **U001277126**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	93273
UST ID:	119261
AI Number:	45535
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

CHAMELEON 71 (Continued) **U001277126**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1986

Install Date:	01/01/1986
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119262
Facility ID:	67610
Ai Number:	45535
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/13/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

CHAMELEON 71 (Continued) **U001277126**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	93274
UST ID:	119262
AI Number:	45535
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y

CHAMELEON 71 (Continued) **U001277126**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1986

Install Date:	07/01/1988
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119263
Facility ID:	67610
Ai Number:	45535
Tank Id:	8
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

CHAMELEON 71 (Continued) **U001277126**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	8
Tank Capacity:	10000
UST Comprt ID:	93275
UST ID:	119263
AI Number:	45535
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/01/1988

CHAMELEON 71 (Continued) **U001277126**

Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119264
Facility ID:	67610
Ai Number:	45535
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

CHAMELEON 71 (Continued) **U001277126**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	6
Tank Capacity:	10000
UST Comprt ID:	93276
UST ID:	119264
AI Number:	45535
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/01/1988
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119265
Facility ID:	67610

CHAMELEON 71 (Continued) **U001277126**

Ai Number:	45535
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	7
Tank Capacity:	10000
UST Comprt ID:	93277

CHAMELEON 71 (Continued) **U001277126**

UST ID:	119265
AI Number:	45535
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/01/1988
Tank Registration Date:	11/11/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	119266
Facility ID:	67610
Ai Number:	45535
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/26/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

CHAMELEON 71 (Continued) **U001277126**

Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/18/1990

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	93278
UST ID:	119266
AI Number:	45535
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y

CHAMELEON 71 (Continued) **U001277126**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	35726
Facility ID:	67610
AI Number:	45535
Application Received Date:	12/06/2019
Scheduled Construction Date:	12/09/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	12/06/2019
Signature Date On Form:	12/05/2019
Signature Name On Form:	RUSSELL FORD
Signature Company On Form:	Not reported
Signature Title On Form:	SR ASSOCIATE
Signature Role:	Not reported

CHAMELEON 71 (Continued) **U001277126**

Owner Name At Time Of Construction: CHAMELEON 71 LP
Owner CN At Time Of Construction: CN605565480
Owner AR At Time Of Construction: 80212
General Desc Of Prop Construct: REMOVE AND DISPOSE OF (4) 10,000 GALLON, FRP USTS AND ASSOCIATED PIPING AND DISPENSERS

NOC ID: 9269
Facility ID: 67610
AI Number: 45535
Application Received Date: 04/20/2001
Scheduled Construction Date: 05/20/2001
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M10420006
Waiver Flag: N
Late Filing Flag: N
Form Received Date: 12/06/2019
Signature Date On Form: 12/05/2019
Signature Name On Form: RUSSELL FORD
Signature Company On Form: Not reported
Signature Title On Form: SR ASSOCIATE
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 16508
General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 84651
UST ID: Not reported
NOC ID: 35726
AI Number: 45535
Type Of Contact: CONSULTANT
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: TERRACON CONSULTANTS
Representative Name: RUSSELL FORD
Mailing Address (Delivery): 5307 INDUSTRIAL OAKS BLVD STE 160
Mailing Address (Internal Delivery): Not reported
Mailing City: AUSTIN
Mailing State: TX
Mailing Zip: 78735
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 512
Phone Number: 4421122
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported

CHAMELEON 71 (Continued) **U001277126**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	84652
UST ID:	Not reported
NOC ID:	35726
AI Number:	45535
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	GRUENE ENVIRONMENTAL COMPANIES
Representative Name:	RYAN METZ
Mailing Address (Delivery):	11 NAFTA CIR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	NEW BRAUNFELS
Mailing State:	TX
Mailing Zip:	78132
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	830
Phone Number:	6267575
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	9928
UST ID:	Not reported
NOC ID:	9269
AI Number:	45535
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CHAMELEON 71 LP
Contact Mailing Address (Delivery):	PO BOX 38
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 0038
Phone Number/Ext:	512 7849515/0

CHAMELEON 71 (Continued) **U001277126**

Contact Fax Number/Ext:	/
Contact Email Address:	ADMIN@CHAMELEONGP.COM
Contact Address Deliverable:	Y
Facility ID:	67610
Additional ID:	364830692002152
Princ ID:	505476432018243
AI Number:	45535
Facility Name:	CHAMELEON 71
AR Number:	80212
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	LILY SHARP/

HIST UST AUSTIN:

Name:	CHAMELEON 71, LP.
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	2012
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	106919
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2013
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	18180
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/01/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	109205
AI:	45535

CHAMELEON 71 (Continued) **U001277126**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/28/2012
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	Not reported
Policy Number:	9987519
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/28/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	6534
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2012
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	53182
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2011
Date Financial Assurance Form Rec:	01/22/2020

CHAMELEON 71 (Continued) **U001277126**

Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	53183
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2010
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	18180
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	53184
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2009
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	12120
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71

CHAMELEON 71 (Continued) **U001277126**

Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	53185
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2008
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	12120
Coverage Amount:	1000000
Coverage Expiration Date:	01/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CHAMELEON 71
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	67610
Finass ID:	53186
AI:	45535
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/1994
Date Financial Assurance Form Rec:	01/22/2020
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

NON REGIST PST:

RN Number:	RN100527688
Name:	DON A STEWART
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741 7708
Physical Location:	7110 E BEN WHITE BLVD
CN Number:	CN600681589
Customer Name:	AAA PETROLEUM DISTRIBUTORS INC
Customer Role:	N/A
Primary Business:	FLEET REFUELING

CHAMELEON 71 (Continued) **U001277126**

Code:	424720
Classification:	NAICS
Industry Name:	Petroleum and Petroleum Products Merchant Wholesalers (except Bulk Stations and Terminals)
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=202480272001288

RN Number:	RN100527688
Name:	DON A STEWART
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741 7708
Physical Location:	7110 E BEN WHITE BLVD
CN Number:	CN603303991
Customer Name:	CLASSIC STAR GROUP LP
Customer Role:	OWNER OPERATOR
Primary Business:	FLEET REFUELING
Code:	424720
Classification:	NAICS
Industry Name:	Petroleum and Petroleum Products Merchant Wholesalers (except Bulk Stations and Terminals)
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=202480272001288

RN Number:	RN100527688
Name:	DON A STEWART
Address:	7110 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78741 7708
Physical Location:	7110 E BEN WHITE BLVD
CN Number:	CN605565480
Customer Name:	CHAMELEON 71 LP
Customer Role:	OWNER OPERATOR
Primary Business:	FLEET REFUELING
Code:	424720
Classification:	NAICS
Industry Name:	Petroleum and Petroleum Products Merchant Wholesalers (except Bulk Stations and Terminals)
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=202480272001288

SP3067 SSW 1/8-1/4 0.214 mi. 1131 ft. | **FORMER DON STEWART**
7110 BEN WHITE BLVD
AUSTIN, TX

Site 3 of 3 in cluster SP | **TX RDR** | **S127533724**
N/A

Actual: 584 ft.

Focus Map: 19

RDR:

RDR ID:	28111
Facility ID:	45535
RN:	Not reported
CN:	Not reported
Name:	FORMER DON STEWART
Address:	7110 BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/22/2020
Due Date:	3/22/2020
Tank Owner:	CHAMELEON 71 LP
Contact Person:	STUART THOMAJAN
Report:	Tank Removal
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/9/2020
Project Manager:	Michelle Ogee
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3068 East 1/8-1/4 0.214 mi. 1132 ft. | **SERVICE BUILDING VEHICLE REFUEL STN**
304 E 24TH ST
AUSTIN, TX 78712 | **TX LPST** | **U001247290**
TX UST | **N/A**
TX ASBESTOS

Actual: 524 ft.

Focus Map: 11

LPST:

Name:	SERVICE BLDG VEHICLE REFUEL STN
Address:	304 E 24TH ST
City,State,Zip:	AUSTIN, TX 78713
Facility ID:	0011352
LPST Id:	096480
Facility Location:	304 E 24TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/06/1990
Entered Date:	08/16/1990
Reported Date:	08/06/1990
Closure Date:	07/02/1991
Priority:	2C - GROUP 1 GROUNDWATER OFF-SITE MIGRATION UNLIKELY
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUP 1 GROUNDWATER, OFF-SITE MIGRATION UNLIKELY
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Coordinators RPR:	CAROL WHITE
Responsible Party Name:	Not reported
Responsible Party Contact:	M P OSBORNE
Responsible Party Address:	PO BOX 7580
Responsible Party City,St,Zip:	AUSTIN, TX 78713
Responsible Party Telephone:	512/471-5050
Reported Date:	08/06/1990
Case Start Date:	07/02/1991
Reference Number:	RN103762134
Project Manager:	CAW

UST:

Name:	SERVICE BUILDING VEHICLE REFUEL STN
Address:	304 E 24TH ST
City,State,Zip:	AUSTIN, TX 787121535
AI Number:	11352
Facility Type:	FLEET REFUELING
Facility Begin Date:	07/28/1986
Facility Status:	INACTIVE
Additional ID:	187601122003202
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78713
Contact Name/Title:	H D WILSON,ASSOC DIR
Contact Organization Name:	SERVICE BUILDING VEHICLE REFUEL STN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124714110
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/23/1986
Signature Name/Title On Earliest Reg Form:	H D WILSON,ASSOC. DIR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601097413
Owner Last Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	583604122002106
Additional ID:	187601122003202
AI Number:	11352
Owner Effective Begin Date:	07/28/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29808
Facility ID:	50476
Ai Number:	11352
Tank Id:	55
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/30/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	55
Tank Capacity:	Not reported
UST Comprt ID:	27521
UST ID:	29808
AI Number:	11352
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29810
Facility ID:	50476
Ai Number:	11352
Tank Id:	53
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/30/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	53
Tank Capacity:	Not reported
UST Comprt ID:	27523
UST ID:	29810
AI Number:	11352
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Install Date:	01/01/1956
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29809
Facility ID:	50476
Ai Number:	11352
Tank Id:	54
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/30/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	54
Tank Capacity:	Not reported
UST Comprt ID:	27522
UST ID:	29809
AI Number:	11352
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Contact Mailing Address (Delivery):	PO BOX 7729
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78713 7729
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	50476
Additional ID:	187601122003202
Princ ID:	583604122002106
AI Number:	11352
Facility Name:	SERVICE BUILDING VEHICLE REFUEL STN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	CHIP ROGERS/

ASBESTOS:

Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Address:	304 E 24TH STREET
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported
Reason for Inspection:	JAMES WICHMAN
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020001798
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/26/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/20/2019
Certification Statement Phone:	512-471-3511
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	34
Is this a phased abatement project?:	N

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/06/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VARIOUS BUILDINGS ON CAMPUS
Address:	304 EAST 24TH STREET
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported
Reason for Inspection:	James L. Wichman
Violation:	Not reported
Complaint Date:	12/31/2017
Notification Number:	2016010167
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/16/2016
Certification Statement Phone:	512-471-3511
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	34
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	THE UNIVERSITY OF TEXAS AT AUSTIN
Address:	304 E 24TH ST
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	03/01/2018
Reason for Inspection:	JAMES L WICHMAN
Violation:	Not reported
Complaint Date:	12/31/2018
Notification Number:	2018000489
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/19/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/13/2017
Certification Statement Phone:	512-471-3511
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	34
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SERVICE BUILDING
Address:	304 E 24TH ST
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Reason for Inspection:	Kevin Alexander
Violation:	Not reported
Complaint Date:	11/20/2017
Notification Number:	2017008202
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/03/2017
Certification Statement Phone:	512-471-6227
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	RFCI Only
Analytical Method:	Assumed Asbestos
Start Date:	11/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VARIOUS BUILDINGS ON CAMPUS
Address:	304 EAST 24TH STREET
City,State,Zip:	AUSTIN, TX 78714
Date of inspection:	Not reported
Reason for Inspection:	JAMES L WICHMAN
Violation:	Not reported
Complaint Date:	12/31/2015
Notification Number:	2016000890
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/02/2014
Certification Statement Phone:	512-471-3511
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	31
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Analytical Method:	PLM
Start Date:	01/01/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	UT OF AUSTIN - VARIOUS BUILDINGS ON CAMPUS
Address:	304 E. 24TH ST.
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported
Reason for Inspection:	JAMES L. WICHMAN
Violation:	Not reported
Complaint Date:	12/31/2016
Notification Number:	2016006738
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Work Type Flag:	A
Certification Statement Date:	12/17/2015
Certification Statement Phone:	512-471-3511
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	31
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	01/01/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SERVICE BUILDING
Address:	304 E 24TH STREET
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2021/01/21
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/21/2021
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2021000060
File Number:	57951
License Status Description:	Paid
Expiration Date:	01/21/2021
Original Date:	01/05/2021
Rank Effective Date:	01/05/2021
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	25530
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	SERVICE BUILDING
Address:	304 E 24TH STREET
City,State,Zip:	AUSTIN, TX 78712
Date of inspection:	01/21/2021
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	01/21/2021
Notification Number:	2021000060
ASB Priority:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/05/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/05/2021
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	Assumed Asbestos
Start Date:	01/19/2021
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

SERVICE BUILDING VEHICLE REFUEL STN (Continued) **U001247290**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

SQ3069 **WHISENHUT** **TX CLI** **S119135376**
NNE **NE INTERSECTION OF DALTON LANE AND RAMIREZ LN** **N/A**
1/8-1/4 **TRAVIS (County), TX**
0.216 mi.
1140 ft. **Site 1 of 3 in cluster SQ**

Actual:
454 ft.

Focus Map:
16

CAPCOG LI:

Name:	WHISENHUT
Address:	NE INTERSECTION OF DALTON LANE AND RAMIREZ LN
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	0
Date Close:	0
Unum:	899
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	13.44
Longitude Deg:	97
Longitude Min:	40.399999999999999
Lat Dd:	30.224
Long Dd:	-97.673333
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	1
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	Michael and Lucinda Lopez
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	0

WHISENHUT (Continued) **S119135376**

Reviewer1:	Not reported
Confidence:	SITE WITHIN 500 FT OF POINT
Cog1:	12
Twc Dist:	14
Size Acres:	0
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Y
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Y
Other:	Y
Other Des:	inert
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Inspection:	???
Comment:	50 5-gallon cans of solvent from an Austin engraving co. deposited in fill; Identified in list of Travis County sites;
Latitude:	30.224
Longitude:	-97.67333333
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part1.pdf#page=319

SQ3070 **WHISENHUT** **TX CLI** **S103259073**
NNE **N/A**
1/8-1/4 **, TX**
0.216 mi.
1140 ft. **Site 2 of 3 in cluster SQ**

Actual:
454 ft.

Focus Map:
16

CLI:

Name:	WHISENHUT
Address:	Not reported
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	Not reported
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported

WHISENHUT (Continued) **S103259073**

Engineer:	Not reported
Source:	1
Source Code:	Not reported
Date Opened:	**********
Date Closed:	**********
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	13.44
Long Deg:	97
Long Min:	40.40
Lat/Long (deg):	30.224000 / -97.673333
Owner:	Otis Whisenhut
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	14
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Yes
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Yes
Accepts Other:	Y
Accepts Other Description:	inert
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Uk
Inspc Comments:	???
Comments:	50 5-gallon cans of solvent from an Austin engraving co. deposited in fill; Identified in list of Travis County sites;
Update:	0
Reviewer:	Not reported
Flag:	Not reported

SQ3071 NNE 1/8-1/4 0.216 mi. 1140 ft. | **WHISENHUT** | **TX HIST LF** | **S129375055** **N/A**

TRAVIS (County), TX

Site 3 of 3 in cluster SQ

Actual: 454 ft.

Focus Map: 16

HIST LF:

Name:	WHISENHUT
Name 2:	Not reported
Address:	Not reported
City,State,Zip:	TX
Latitude:	30.224000
Longitude:	-97.673333
Lat Deg:	30
Lat MM:	13.44
Lon DD:	97
Lon MM:	40.40
UNUM:	899
Comments:	50 5-gallon cans of solvent from an Austin engraving co. deposited in fill; Identified in list of Travis County sites;
Inspection:	???
COG Number:	12
COOR CD:	Not reported
TWC District:	14
Owner Name:	Otis Whisenhut
Owner Code:	Not reported
Open Date:	0
Close Date:	0
Acres:	0
Yards:	0
Parties:	Not reported
Household:	Not reported
Construct Demo:	Y
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Not reported
Brush:	Y
Other:	Y
Other Description:	inert
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Uk
Update:	No Change
Reviewer:	Not reported
Accuracy:	TNRCC files
Source:	1

SF3072 **STRAIT MUSIC** **TX UST** **U001267960**
WNW **10TH & LAMAR** **N/A**
1/8-1/4 **AUSTIN, TX**
0.217 mi.
1144 ft. **Site 5 of 5 in cluster SF**

Actual:
474 ft.

Focus Map:
11

UST:

Name:	STRAIT MUSIC
Address:	10TH & LAMAR
City,State,Zip:	AUSTIN, TX
AI Number:	34968
Facility Type:	UNKNOWN
Facility Begin Date:	12/10/1986
Facility Status:	INACTIVE
Additional ID:	631653962002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	10TH & LAMAR
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	YVONNE MOODY,ENG
Contact Organization Name:	STRAIT MUSIC
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	7137543709
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1986
Signature Name/Title On Earliest Reg Form:	H J ODONNELL,ENG
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600132484
Owner Last Name:	CHEVRON USA INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	329482572001157
Additional ID:	631653962002156

STRAIT MUSIC (Continued) **U001267960**

AI Number:	34968
Owner Effective Begin Date:	12/10/1986
State Tax ID:	12505279252
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1961
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92447
Facility ID:	63744
Ai Number:	34968
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	07/31/1986
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

STRAIT MUSIC (Continued) **U001267960**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	74499
UST ID:	92447
AI Number:	34968
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

STRAIT MUSIC (Continued) **U001267960**

More Self Certification:

Self Cert ID:	13520
Cert ID:	126130
UST Comprt ID:	366998
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126131
UST Comprt ID:	366995
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126132
UST Comprt ID:	366994
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126133
UST Comprt ID:	366993
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126134
UST Comprt ID:	366992
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126129
UST Comprt ID:	366997
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126136
UST Comprt ID:	366990
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A

STRAIT MUSIC (Continued) **U001267960**

Self Cert ID:	13520
Cert ID:	126138
UST Comprt ID:	366988
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126139
UST Comprt ID:	366987
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126137
UST Comprt ID:	366989
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126128
UST Comprt ID:	366996
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A
Self Cert ID:	13520
Cert ID:	126135
UST Comprt ID:	366991
UST ID:	118667
AI Number:	34968
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	CHEVRON USA INC
Contact Mailing Address (Delivery):	PO BOX 6004
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN RAMON, CA 94583 0904
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	63744
Additional ID:	631653962002156
Princ ID:	329482572001157
AI Number:	34968
Facility Name:	STRAIT MUSIC
AR Number:	Not reported
AR UST Number Suffix:	Not reported

STRAIT MUSIC (Continued) **U001267960**

AR AST Number Suffix: Not reported
Contact Name/Title: PERMIT DESK/

SR3073 **ODAS JUNG** **TX HIST UST** **S111678765**
WNW **921 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.217 mi.
1145 ft. **Site 1 of 3 in cluster SR**

Actual:
474 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	ODAS JUNG
Address:	921 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0478
HID UST:	478
Inspection:	Not reported
Due:	06/01/2012

SR3074 **W. L. STARK** **TX HIST UST** **S111678847**
WNW **921 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.217 mi.
1145 ft. **Site 2 of 3 in cluster SR**

Actual:
474 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	W. L. STARK
Address:	921 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0993
HID UST:	993
Inspection:	Not reported
Due:	06/01/2012

SS3075 **TEX-CON OIL COMPANY** **TX HIST UST** **S128729490**
WNW **1200 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.217 mi.
1148 ft. **Site 1 of 9 in cluster SS**

Actual:
485 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TEX-CON OIL COMPANY
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0981
HID UST:	981
Inspection:	Not reported
Due:	06/01/2012

SS3076 **KWIK MART 1** **TX LPST** **U001271012**
WNW **1200 N LAMAR BLVD** **TX UST** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX ASBESTOS**
0.217 mi. **TX ENF**
1148 ft. **Site 2 of 9 in cluster SS** **TX Financial Assurance**
TX RDR

Actual:
485 ft.

Focus Map:
11

LPST:

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0038369
LPST Id:	103025
Facility Location:	1200 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/01/1992
Entered Date:	05/19/1992
Reported Date:	05/01/1992
Closure Date:	01/13/2004
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/1P/1/1P/1
Coordinators RPR:	TH2
Responsible Party Name:	Not reported
Responsible Party Contact:	TIM RAMSEY
Responsible Party Address:	4906 BURLESON RD
Responsible Party City,St,Zip:	AUSTIN, TX 78760
Responsible Party Telephone:	512/444-1941
Reported Date:	05/01/1992
Case Start Date:	01/13/2004
Reference Number:	RN102870136
Project Manager:	THASAN

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	121586
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	09/08/2022
Entered Date:	02/03/2023
Reported Date:	09/09/2022
Closure Date:	12/31/3000
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1 - RPR
CA Status:	1 - RELEASE DETERMINATION
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported

KWIK MART 1 (Continued) **U001271012**

Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	09/09/2022
Case Start Date:	12/31/3000
Reference Number:	RN102870136
Project Manager:	YTAN

UST:

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787034131
AI Number:	38369
Facility Type:	RETAIL
Facility Begin Date:	01/01/1978
Facility Status:	ACTIVE
Additional ID:	971497472002259
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	HATUM NATSHEH,MGR
Contact Organization Name:	KWIK MART 1
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124789095
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/15/2021
Signature Name/Title On Earliest Reg Form:	DAN KOHL,SAFTEY MGR
Application Received Date On Earliest Reg Form:	05/14/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	843523822020169
Additional ID:	971497472002259
Ai Number:	38369
Operator CN:	CN605788017
Operator Name:	AL-QUDUS INCORPORATED
Operator Effective Begin Date:	06/01/1996
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported

KWIK MART 1 (Continued) **U001271012**

Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602402174
Owner Last Name:	HAYS CITY CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	327575342003232
Additional ID:	971497472002259
AI Number:	38369
Owner Effective Begin Date:	06/01/1996
State Tax ID:	17418292623
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	69441
Cert ID:	371914
AI Number:	38369
Self Certification Date:	05/15/2022
Signature Name/Title:	DAN KOHL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	355456
AI Number:	38369
Self Certification Date:	05/15/2021
Signature Name/Title:	DAN KOHL SAFTEY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	338315
AI Number:	38369
Self Certification Date:	05/24/2020
Signature Name/Title:	DAN KOHL SAFETY & COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	321225
AI Number:	38369
Self Certification Date:	05/24/2019
Signature Name/Title:	DAN KOHL SAFETY AND COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	304848
AI Number:	38369
Self Certification Date:	06/07/2018
Signature Name/Title:	KEVIN LITTLE OPR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	286709
AI Number:	38369
Self Certification Date:	04/26/2017
Signature Name/Title:	KEVIN LITTLE OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	269703
AI Number:	38369
Self Certification Date:	05/02/2016
Signature Name/Title:	KEVIN LITTLE SAFETY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	253234
AI Number:	38369
Self Certification Date:	04/28/2015
Signature Name/Title:	BOB STEHLING OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	237075
AI Number:	38369
Self Certification Date:	04/28/2014
Signature Name/Title:	BOB STEHLING OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	69441
Cert ID:	219645
AI Number:	38369
Self Certification Date:	05/08/2013
Signature Name/Title:	CLAY JOHNSON PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	92809
AI Number:	38369
Self Certification Date:	06/08/2012
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92808
AI Number:	38369
Self Certification Date:	05/17/2011
Signature Name/Title:	CLAY JOHNSON PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92807
AI Number:	38369
Self Certification Date:	06/14/2010
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	92806
AI Number:	38369
Self Certification Date:	04/23/2009
Signature Name/Title:	CLAY JOHNSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92805
AI Number:	38369
Self Certification Date:	04/22/2008
Signature Name/Title:	CLAY JOHNSON PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92804
AI Number:	38369
Self Certification Date:	05/01/2007
Signature Name/Title:	CLAY ANDERSON PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	92803
AI Number:	38369
Self Certification Date:	05/29/2006
Signature Name/Title:	TIM RAMSEY V P
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92802
AI Number:	38369
Self Certification Date:	05/29/2005
Signature Name/Title:	TIM RAMSEY VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92801
AI Number:	38369
Self Certification Date:	05/29/2004
Signature Name/Title:	TIM RAMSEY V PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

KWIK MART 1 (Continued) **U001271012**

Self Cert ID:	69441
Cert ID:	92800
AI Number:	38369
Self Certification Date:	05/29/2003
Signature Name/Title:	TIM RAMSEY VP
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92799
AI Number:	38369
Self Certification Date:	06/18/2002
Signature Name/Title:	TIM RAMSEY PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	69441
Cert ID:	92798
AI Number:	38369
Self Certification Date:	01/17/2000
Signature Name/Title:	TIM RAMSEY PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

KWIK MART 1 (Continued) **U001271012**

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	101125
Facility ID:	69441
Ai Number:	38369
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1978
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	09/09/1992
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

KWIK MART 1 (Continued) **U001271012**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	84029
UST ID:	101125
AI Number:	38369
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P

KWIK MART 1 (Continued) **U001271012**

UST ID:	101126
Facility ID:	69441
Ai Number:	38369
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1978
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	09/09/1992
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1

KWIK MART 1 (Continued) **U001271012**

Tank Capacity:	6000
UST Comprt ID:	84030
UST ID:	101126
AI Number:	38369
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	101127
Facility ID:	69441
Ai Number:	38369
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

KWIK MART 1 (Continued) **U001271012**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	84031
UST ID:	101127
AI Number:	38369
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported

KWIK MART 1 (Continued) **U001271012**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	101128
Facility ID:	69441
Ai Number:	38369
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

KWIK MART 1 (Continued) **U001271012**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	84032
UST ID:	101128
AI Number:	38369
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

KWIK MART 1 (Continued) **U001271012**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	37066
Facility ID:	69441
AI Number:	38369
Application Received Date:	09/25/2020
Scheduled Construction Date:	10/12/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	HAYS CITY CORPORATION
Owner CN At Time Of Construction:	CN602402174
Owner AR At Time Of Construction:	17806,17806
General Desc Of Prop Construct:	Not reported

NOC ID:	8139

KWIK MART 1 (Continued) **U001271012**

Facility ID:	69441
AI Number:	38369
Application Received Date:	10/19/2009
Scheduled Construction Date:	11/18/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91019007
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	17806
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	88011
UST ID:	Not reported
NOC ID:	37066
AI Number:	38369
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	CHRIS MAYS
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	8652
UST ID:	Not reported
NOC ID:	8139
AI Number:	38369

KWIK MART 1 (Continued) **U001271012**

Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	HAYS CITY CORPORATION
Contact Mailing Address (Delivery):	PO BOX 18463
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78760 8463
Phone Number/Ext:	512 6177777/0
Contact Fax Number/Ext:	/
Contact Email Address:	DKOHL@TEXCONOIL.COM
Contact Address Deliverable:	Y
Facility ID:	69441
Additional ID:	971497472002259
Princ ID:	327575342003232
AI Number:	38369
Facility Name:	KWIK MART 1
AR Number:	17806
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	DAN KOHL/

ASBESTOS:

Name:	KWIK MART
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0

KWIK MART 1 (Continued) **U001271012**

Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	KWIK MART
Address:	1200 N LAMAR BLVD

KWIK MART 1 (Continued) **U001271012**

City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	05/23/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.3
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/02/2014
Date Routed by Supervisor:	06/02/2014
Date Routed to PSQA:	06/03/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

KWIK MART 1 (Continued) **U001271012**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Unique TCEQ Ref Number Of Customer:	CN602402174
Unique TCEQ Ref Number Of Reg. Entity:	RN102870136
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	30 TAC Chapter 334, SubChapter A
Regulated Entity Associated With An NOV:	HAYS CITY CORPORATION
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	AUSTIN
Investigation Number:	1106454
Status Code:	RESOLVED
Status Date:	08/08/2013
Violation Tracking Number:	589,440,682,013,218.00
Violation Category:	A
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	Not reported
Description 1:	30 TAC 334.10(b)(1)(B) - RECORDS- Failure to maintain legible copies of all required records pertaining to an UST system and make available for inspection by the TCEQ or their UST Contractor.
Description 2:	The respondent submitted compliance documentation on April 30, 2013.
Category of the NOV:	Not reported
Method Of Notice Issuance:	Not reported
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	Not reported
Status Of The NOV:	DAPPROVED
Investigation:	Not reported
Investigation ID:	334426652013218
Regulated Entity ID:	961497472002259
Date of Notice Enforcement:	08/08/2013
Violation Date:	2013-08-07 00:00:00
Rejected:	NO
Type Code:	ADMINORDER
Date Resolved:	02/09/2014
Assessed Amount:	2937
Deferred Amount:	587
Payable Amount:	2350
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

TX Financial Assurance 2:

Name:	KWIK MART 1

KWIK MART 1 (Continued) **U001271012**

Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	269726
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2021
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000022654
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	252193
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2020
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000011650
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	232475
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

KWIK MART 1 (Continued) **U001271012**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2019
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top005001070
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	214809
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2018
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	198473
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2017
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	01436

KWIK MART 1 (Continued) **U001271012**

Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	179681
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2016
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	162073
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2015
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	1436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2

KWIK MART 1 (Continued) **U001271012**

Facility ID:	69441
Finass ID:	144279
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2014
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	128587
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2013
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	108287
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

KWIK MART 1 (Continued) **U001271012**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2012
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	6435
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2011
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	51205
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2009
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2010
Ins Premium Pre-Paid For Entire Yr:	No

KWIK MART 1 (Continued) **U001271012**

Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	51206
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2008
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	51207
AI:	38369
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/2007
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 817 3361336
Policy Number:	01436
Coverage Amount:	1000000
Coverage Expiration Date:	07/12/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	69441
Finass ID:	51208
AI:	38369

KWIK MART 1 (Continued) **U001271012**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/12/1991
Date Financial Assurance Form Rec:	05/14/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	32393
Facility ID:	38369
RN:	102870136
CN:	602402174
Name:	KWIK MART 1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/8/2022
Due Date:	2/6/2023
Tank Owner:	HAYS CITY CORPORATION
Contact Person:	LARRY HOLYBEE
Report:	Suspected Release
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	2/6/2023
Project Manager:	Yongrui Tan
Team:	Team 2
New LPST Number:	121586
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SS3077 **KWIK MART #1** **TX HIST UST** **S128728805**
WNW **1200 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.217 mi.
1148 ft. **Site 3 of 9 in cluster SS**

Actual:
485 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	KWIK MART #1
Address:	1200 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	622

KWIK MART #1 (Continued) **S128728805**

HID UST: Not reported
Inspection: Not reported
Due: Not reported

ST3078 **TOKYO ELECTRON TEXAS** **RCRA-VSQG** **1001225895**
SSW **2500 MONTOPOLIS DRIVE** **FINDS** **TXR000027524**
1/8-1/4 **AUSTIN, TX 78741** **ECHO**
0.218 mi.
1149 ft. **Site 1 of 3 in cluster ST**

Actual:
571 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20100929
Handler Name:	Tokyo Electron Texas
Handler Address:	2500 MONTOPOLIS DRIVE
Handler City,State,Zip:	AUSTIN, TX 78741-6404
EPA ID:	TXR000027524
Contact Name:	JIM ELDRED
Contact Address:	2500 MONTOPOLIS DRIVE
Contact City,State,Zip:	AUSTIN, TX 78741-6404
Contact Telephone:	512-322-6205
Contact Fax:	Not reported
Contact Email:	JIM.ELDRED@AUSTINENERGY.COM
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	2500 MONTOPOLIS DRIVE
Mailing City,State,Zip:	AUSTIN, TX 78741-6404
Owner Name:	Tokyo Electron Texas Inc,
Owner Type:	Private
Operator Name:	Tokyo Electron Texas Inc,
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

TOKYO ELECTRON TEXAS (Continued) **1001225895**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20101008
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC	
Legal Status:	Private
Date Became Current:	20051129
Date Ended Current:	Not reported
Owner/Operator Address:	2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-486-4221
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC	
Legal Status:	Private
Date Became Current:	20090902
Date Ended Current:	Not reported
Owner/Operator Address:	2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip:	AUSTIN, TX 78741
Owner/Operator Telephone:	512-486-4221
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20090902
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC,
Legal Status: Private
Date Became Current: 19980505
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741-6404
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20090331
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20100125
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20100531
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20040309
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20100531
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC,
Legal Status: Private
Date Became Current: 19980505
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741-6404
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DR
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20040309

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20020313
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20090331
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Owner/Operator Name: TOKYO ELECTRON TEXAS INC
Legal Status: Private
Date Became Current: 20100125
Date Ended Current: Not reported
Owner/Operator Address: 2500 MONTOPOLIS DRIVE
Owner/Operator City,State,Zip: AUSTIN, TX 78741
Owner/Operator Telephone: 512-486-4221
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19980521
Handler Name: TOYKO ELECTRON TEXAS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020313
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040309
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090331
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090902
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100125
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100531
Handler Name: TOKYO ELECTRON TEXAS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

TOKYO ELECTRON TEXAS (Continued) **1001225895**

Electronic Manifest Broker: Not reported

Receive Date: 20100929
Handler Name: TOKYO ELECTRON TEXAS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 333298
NAICS Description: ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005181846

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001225895
Registry ID: 110005181846
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005181846
Name: TOKYO ELECTRON TEXAS
Address: 2500 MONTOPOLIS DRIVE
City,State,Zip: AUSTIN, TX 78741

ST3079 **SYSTEM CONTROL CENTER** **TX Ind. Haz Waste** **S103614755**
SSW **2500 MONTOPOLIS DRIVE** **TX TIER 2** **N/A**
1/8-1/4 **AUSTIN, TX 78741** **TX IHW CORR ACTION**
0.218 mi. **TX CENTRAL REGISTRY**
1149 ft. **Site 2 of 3 in cluster ST**

Actual:
571 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX 78741
Permit Number:	Not reported
Registration Number:	85656
Registration Initial Notification Date:	05/05/1998
Registration Last Amendment Date:	09/23/2010
EPA Identification:	TXR000027524
Primary NAICS Code:	333298
Status Change Date:	19980505
Land Type:	PRIVATE
Description of Facility Site Location:	2500 Montopolis Drive, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TOKYO ELECTRON TEXAS INC
Contact Name:	JIM ELDRED
Contact Telephone Number:	512-3226205
Mailing Address:	2500 MONTOPOLIS DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787416404
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	107451
Site Owner Tax ID:	742789105
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

SYSTEM CONTROL CENTER (Continued) **S103614755**

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TOKYO ELECTRON TEXAS INC
Operator Address:	2500 MONTOPOLIS DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78741
Operator Country:	UNITED STA
Operator Telephone:	1-512-4864221
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17427891050
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TOKYO ELECTRON TEXAS INC
Owner Mailing Address:	2500 MONTOPOLIS DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78741
Owner Country:	UNITED STA
Owner Telephone:	1-512-4864221
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17427891050
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	13
Unit Status:	CLOSED
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	350 gal tank used to store spent isopropyl alcohol.Closure approval rcvd 9-23-10
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100923

SYSTEM CONTROL CENTER (Continued) **S103614755**

Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	002
Unit Type Code:	22
Unit Status:	CLOSED
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Roll off dumpster used for the temporary storage of plant trash and supplemental
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20100923
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	2500 MONTOPOLIS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-4864221
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	2500 MONTOPOLIS DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-4864221
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	JIM ELDRED
Contact Title:	ENVIRONMENTAL PROGRAM COO
Contact Role:	PRICONT
Contact Address:	2500 MONTOPOLIS DR
Contact Address 2:	Not reported

SYSTEM CONTROL CENTER (Continued) **S103614755**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78741
Contact Phone:	1-512-3226205
Contact Fax:	1-512-3226280
Contact Email:	jim.eldred@austinenergy.com

Ind. Haz Waste:

Waste ID:	169496
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent isopropyl alcohol used for final flushing of assembled process equipment.5
Standard Industrial Code:	35590
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	169497
Texas Waste Code:	Not reported
Texas Waste Code 2:	00024092
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Process wipes containing isopropyl alcohol from wipe down of process equipment.3
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SYSTEM CONTROL CENTER (Continued) **S103614755**

Waste ID:	169499
Texas Waste Code:	Not reported
Texas Waste Code 2:	00039022
Waste Code Status:	INACTIVE
Waste Form:	902
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Supplemental plant trash generated from manufacturing operations. 1/23/98
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	169498
Texas Waste Code:	Not reported
Texas Waste Code 2:	00049992
Waste Code Status:	INACTIVE
Waste Form:	999
Waste Classification:	2
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Plant trash generated from facility offices or plant production area. 1/23/98
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	185868
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006105H
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

SYSTEM CONTROL CENTER (Continued) **S103614755**

Generators Waste Description:	Used bath solution from dipping waffers.
Standard Industrial Code:	35590
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186021
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007204H
Waste Code Status:	INACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used in coater developing process - SOD tool
Standard Industrial Code:	35590
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186025
Texas Waste Code:	Not reported
Texas Waste Code 2:	0008210H
Waste Code Status:	INACTIVE
Waste Form:	210
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used in Coater Developing Process - ACT-8 Tool.
Standard Industrial Code:	35590
Primary Source:	G08
Primary Measurement Point:	Not reported

SYSTEM CONTROL CENTER (Continued) **S103614755**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W210
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186900
Texas Waste Code:	Not reported
Texas Waste Code 2:	0009319H
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Debris contaminated with Doo1 and D002 material generated from spill clean=up an
Standard Industrial Code:	35590
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	186902
Texas Waste Code:	Not reported
Texas Waste Code 2:	00113191
Waste Code Status:	INACTIVE
Waste Form:	319
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Debris contaminated with Hexamethyldisilazane generated from spill clean-up. In
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

SYSTEM CONTROL CENTER (Continued) **S103614755**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	186901
Texas Waste Code:	Not reported
Texas Waste Code 2:	00124091
Waste Code Status:	INACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Oil filters taken out of service. Initial date of generation: 1-3-01.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	190322
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013003H
Waste Code Status:	INACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Miscellaneous containers of chemicals, waste could be ingnitable, corrosive (aci
Standard Industrial Code:	35590
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

SYSTEM CONTROL CENTER (Continued) **S103614755**

Ind. Haz Waste:

Waste ID:	201334
Texas Waste Code:	Not reported
Texas Waste Code 2:	00144061
Waste Code Status:	INACTIVE
Waste Form:	406
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty Drums/Coater developing
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	201335
Texas Waste Code:	Not reported
Texas Waste Code 2:	00151101
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Ammonium hydroxide solution
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	201336
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016105H
Waste Code Status:	INACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0

SYSTEM CONTROL CENTER (Continued) **S103614755**

Waste Treated Off Site:	Not reported
Generators Waste Description:	Acidic Aqueous waste
Standard Industrial Code:	35590
Primary Source:	G08
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	333298
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	201337
Texas Waste Code:	Not reported
Texas Waste Code 2:	00171121
Waste Code Status:	INACTIVE
Waste Form:	112
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hydrogen peroxide solution
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	201338
Texas Waste Code:	Not reported
Texas Waste Code 2:	00183081
Waste Code Status:	INACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty Metal drums
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

SYSTEM CONTROL CENTER (Continued) **S103614755**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	2500 MONTOPOLIS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000313624
Principal Name:	TOKYO ELECTRON TEXAS INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	2500 MONTOPOLIS DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78741
AR Number:	0000313624
Principal Name:	TOKYO ELECTRON TEXAS INC
Attention Name:	Not reported
Attention Suffix:	HWG

TIER 2:

Facility Id/Name:	FATR200971PLQ80012SR/SYSTEM CONTROL CENTER
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Austin Energy
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/22/2010
Mailing Address:	721 Barton Springs Rd. (attn: Environmental Services)
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	550.00
Number Of Employess On Site:	32
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	David Wood
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported

SYSTEM CONTROL CENTER (Continued) **S103614755**

Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	4911
Id Type:	SIC
Description:	Not reported
Last Modified:	2/24/2010
Id:	221112
Id Type:	NAICS
Description:	Not reported
Last Modified:	2/24/2010
Id:	Not reported
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	2/24/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Name:	Fred Blood
Title:	Env Prog Coord
Modification Date:	2/22/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	301 West Ave
Contact City/State/Zip:	Austin, TX 78703
Contact Mail Country:	USA
Contact Type 1:	Manager
Contact Name:	David Wood
Title:	Director
Modification Date:	1/23/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Rd
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Regulatory Point of Contact
Contact Type 2:	Submitter
Contact Name:	Jim Eldred
Title:	Env Prog Coord'r
Modification Date:	2/22/2010

SYSTEM CONTROL CENTER (Continued) **S103614755**

Contact:

Contact Email:	Not reported
Contact Mail Address:	301 West Ave
Contact City/State/Zip:	Austin, TX 78703
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Geddy Rumsey
Title:	Facility Maintenance
Modification Date:	3/3/2010

Contact:

Contact Email:	Not reported
Contact Mail Address:	721 Barton Springs Road
Contact City/State/Zip:	Austin, TX 78704
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	City of Austin Electric Dep (dba Austin Energy)
Title:	Owner
Modification Date:	3/14/2010

Chemical Inventory:

Facility Id:	FATR200971PLQ80012SR
Chemical Name:	Sulfuric acid (in batteries)
Chemical Inv Record Id:	CVTR200971PLQ900C3U4
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	1,000 - 9,999 pounds
Max Daily Amount:	1,000 - 9,999 pounds
Max Amount In Largest Container:	24
Chronic Health Risks:	T
EHS Substance:	T
Last Modified:	3/3/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200971PLQA00D3V1
Chemical Inventory Record Id:	CVTR200971PLQ900C3U4
Amt Of Sub Stored Or Transported:	98
Amount Units:	gallons
Type Of Storage:	Other
Number Code/Storage Pressure:	1

SYSTEM CONTROL CENTER (Continued) **S103614755**

Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: in battery bank
Last Modified: 3/3/2010

Notes: Not reported

Validation: This facility passed all validation checks.

IHW CORR ACTION:

Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX 78741
Program Id:	85656
Location Desc:	2500 Montopolis Drive, Austin, TX
RN NUM:	RN100615350
Status:	INACTIVE
Status Date:	07/11/2022
EDR Link ID:	85656
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	07/11/2022
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600324503
Customer Name:	TOKYO ELECTRON TEXAS INC
Customer Legal Name:	Tokyo Electron Texas, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600324503
Customer Name:	TOKYO ELECTRON TEXAS INC
Customer Legal Name:	Tokyo Electron Texas, Inc

SYSTEM CONTROL CENTER (Continued) **S103614755**

Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 333298
Primary NAICS Industry Type Description: All Other Industrial Machinery Manufacturing
Physical Location Description: 2500 Montopolis Drive, Austin, TX

Regulated Entity Number: RN100615350
Name: TOKYO ELECTRON TEXAS
Address: 2500 MONTOPOLIS DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-6404
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN602551129
Customer Name: DPR CONSTRUCTION INC
Customer Legal Name: DPR Construction, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 5/4/2011
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 333298
Primary NAICS Industry Type Description: All Other Industrial Machinery Manufacturing
Physical Location Description: 2500 Montopolis Drive, Austin, TX

Regulated Entity Number: RN100615350
Name: TOKYO ELECTRON TEXAS
Address: 2500 MONTOPOLIS DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-6404
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN602551129
Customer Name: DPR CONSTRUCTION INC
Customer Legal Name: DPR Construction, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 5/4/2011
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 333298
Primary NAICS Industry Type Description: All Other Industrial Machinery Manufacturing
Physical Location Description: 2500 Montopolis Drive, Austin, TX

Regulated Entity Number: RN100615350
Name: TOKYO ELECTRON TEXAS
Address: 2500 MONTOPOLIS DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78741-6404
Status: ACTIVE
Status Date: 1/1/2001
Customer Number: CN600129118
Customer Name: CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name: City of Austin DBA Austin Energy
Customer Ownership Type: CITY GOVERNMENT
Affiliation Begin Date: 4/6/2018
Affiliation End Date: 12/31/3000

SYSTEM CONTROL CENTER (Continued) **S103614755**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600129118
Customer Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
Customer Legal Name:	City of Austin DBA Austin Energy
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/6/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/16/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600135198
Customer Name:	CITY OF AUSTIN
Customer Legal Name:	City of Austin
Customer Ownership Type:	CITY GOVERNMENT
Affiliation Begin Date:	4/16/2012
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing

SYSTEM CONTROL CENTER (Continued) **S103614755**

Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600324503
Customer Name:	TOKYO ELECTRON TEXAS INC
Customer Legal Name:	Tokyo Electron Texas, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600324503
Customer Name:	TOKYO ELECTRON TEXAS INC
Customer Legal Name:	Tokyo Electron Texas, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

Regulated Entity Number:	RN100615350
Name:	TOKYO ELECTRON TEXAS
Address:	2500 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-6404
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN600324503
Customer Name:	TOKYO ELECTRON TEXAS INC
Customer Legal Name:	Tokyo Electron Texas, Inc
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	333298
Primary NAICS Industry Type Description:	All Other Industrial Machinery Manufacturing
Physical Location Description:	2500 Montopolis Drive, Austin, TX

SYSTEM CONTROL CENTER (Continued) **S103614755**

Click this hyperlink while viewing on your computer to access
30 additional TX CENTRAL REG: record(s) in the EDR Site Report.

ST3080 **AUSTIN ENERGY SYSTEM CONTROL CENTER** **TX AST** **A100361970**
SSW **2500 MONTOPOLIS DR** **N/A**
1/8-1/4 **AUSTIN, TX 78741**
0.218 mi.
1149 ft. **Site 3 of 3 in cluster ST**

Actual:
571 ft.

Focus Map:
19

AST:

Name:	AUSTIN ENERGY SYSTEM CONTROL CENTER
Address:	2500 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX 787416404
Facility ID:	130316
Additional ID:	188402422012165
AI Number:	85147
Facility Type:	Not reported
Facility Begin Date:	04/16/2012
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	2
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78741
Contact Name/Title:	/
Contact Organization Name:	AUSTIN ENERGY SYSTEM CONTROL CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5129740988
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	06/06/2012
Signature First Name on Earliest Reg Form:	DAVID
Application Received Date on Earliest Reg Form:	06/11/2012
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	WOOD
Signature Title on Earliest Reg Form:	VP
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	130316
Tank ID:	1
AST ID:	216680
AI Number:	85147
Install Date:	04/16/2012
Tank Registration Date:	06/11/2012

AUSTIN ENERGY SYSTEM CONTROL CENTER (Continued) **A100361970**

Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/16/2012
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	13000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	130316
Tank ID:	2
AST ID:	216681
AI Number:	85147
Install Date:	04/16/2012
Tank Registration Date:	06/11/2012
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	04/16/2012
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	13000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

SU3081 **DOUG SCALES BODY SHOP** **TX HIST UST** **S118079661**
West **2707 S 1ST ST** **TX AIRS** **N/A**
1/8-1/4 **AUSTIN, TX**
0.218 mi.
1150 ft. **Site 1 of 3 in cluster SU**

Actual:
574 ft.

Focus Map:
14

HIST UST AUSTIN:

Name:	DOUG SCALES BODY SHOP
Address:	2707 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	N0002

DOUG SCALES BODY SHOP (Continued) **S118079661**

HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AIRS:

Name:	DOUG SCALES BODY SHOP
Address:	2707 S 1ST ST
City,State,Zip:	AUSTIN, TX
Permit Num:	25524
Regulated Id:	RN102598299
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	08/05/1994
Expiration Date:	12/31/3000
Customer Id:	CN600292445
Company Name:	DOUG SCALES BODY SHOP
Physical Location Desc:	2707 South First Street, Austin, TX
Rep Official(RO):	Not reported
RO Name:	Not reported
RO Delivery Address:	Not reported
RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

SB3082 **AUSTIN LYRIC OPERA CENTER** **TX HIST UST** **S127541778**
WNW **905 BARTON SPRINGS RD.** **TX RDR** **N/A**
1/8-1/4 **AUSTIN, TX**
0.218 mi.
1152 ft. **Site 2 of 2 in cluster SB**

Actual:
458 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	AUSTIN LYRIC OPERA
Address:	905 BARTON SPRINGS RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0675
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	11725
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	AUSTIN LYRIC OPERA CENTER
Address:	905 BARTON SPRINGS RD.
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/13/1999
Due Date:	9/11/1999
Tank Owner:	AUSTIN LYRIC OPERA
Contact Person:	JOE MCCLAIN
Report:	RDR

AUSTIN LYRIC OPERA CENTER (Continued) **S127541778**

Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/30/1999
Project Manager:	Brent Rice
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	112262
Comments:	SENT A NO FURTHER ACTION LETTER,RERTN WRONG ADDRESS
Review Coordinator:	BJR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/30/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3083 ESE 1/8-1/4 0.219 mi. 1157 ft.

SUPER K GRO
6700 GUADALUPE ST STE A
AUSTIN, TX 78752

TX UST **U003566408**
TX HIST UST **N/A**
TX Financial Assurance

Actual: 698 ft.

Focus Map: 6

UST:

Name:	SUPER K GRO
Address:	6700 GUADALUPE ST STE A
City,State,Zip:	AUSTIN, TX 787523537
AI Number:	11333
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	786576342002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	M MOTAMEDI,OWNER
Contact Organization Name:	SUPER K GRO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124585076
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	S D HOWLE,
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

SUPER K GRO (Continued) **U003566408**

Owner CN:	CN600775878
Owner Last Name:	METRO SUPPLIERS INCORPORATED
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	666553682002051
Additional ID:	786576342002053
AI Number:	11333
Owner Effective Begin Date:	01/01/1995
State Tax ID:	17426173260
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29775
Facility ID:	87026
Ai Number:	11333
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

SUPER K GRO (Continued) **U003566408**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	129700
UST ID:	29775
AI Number:	11333
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

SUPER K GRO (Continued) **U003566408**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29777
Facility ID:	87026
Ai Number:	11333
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

SUPER K GRO (Continued) **U003566408**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	129702
UST ID:	29777
AI Number:	11333
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

SUPER K GRO (Continued) **U003566408**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	29776
Facility ID:	87026
Ai Number:	11333
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/23/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

SUPER K GRO (Continued) **U003566408**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	129701
UST ID:	29776
AI Number:	11333
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

SUPER K GRO (Continued) **U003566408**

Facility Billing Contacts:

Contact Organization Name:	METRO SUPPLIERS INCORPORATED
Contact Mailing Address (Delivery):	PO BOX 2523
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GEORGETOWN, TX 78627 2523
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87026
Additional ID:	786576342002053
Princ ID:	666553682002051
AI Number:	11333
Facility Name:	SUPER K GRO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	DOUGLAS SCHRAM/

HIST UST AUSTIN:

Name:	SUPER K GROCERY
Address:	6700 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	885
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	SUPER K GRO
Address:	6700 GUADALUPE ST STE A
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	87026
Finass ID:	69375
AI:	11333
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/09/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name: SUPER K GRO

SUPER K GRO (Continued) **U003566408**

Address:	6700 GUADALUPE ST STE A
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	87026
Finass ID:	69374
AI:	11333
Mechanism Type Other:	PST REMEDIATION FUND
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/09/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

3084 **UNITED SHEET METAL WORKS** **TX HIST UST** **S111678842**
WNW **1100 W KOENIG LN** **N/A**
1/8-1/4 **AUSTIN, TX**
0.220 mi.
1161 ft.

Actual:
676 ft.

Focus Map:
8

HIST UST AUSTIN:

Name:	UNITED SHEET METAL WORKS
Address:	1100 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Id UST:	H0592
HID UST:	592
Inspection:	Not reported
Due:	06/01/2012

SU3085 **DOUG SCALES BODY SHOP** **TX Ind. Haz Waste** **S103606424**
West **2717 S 1ST ST** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78704**
0.220 mi.
1163 ft. **Site 2 of 3 in cluster SU**

Actual:
572 ft.

Focus Map:
14

Ind. Haz Waste:

Name:	DOUG SCALES BODY SHOP
Address:	2717 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	66355
Registration Initial Notification Date:	07/16/1985
Registration Last Amendment Date:	11/12/2003
EPA Identification:	TXD981058266
Primary NAICS Code:	Not reported
Status Change Date:	19850716

DOUG SCALES BODY SHOP (Continued) **S103606424**

Land Type:	Not reported
Description of Facility Site Location:	2717 S 1st St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	REEL SHALLOW INC
Contact Name:	DOUG SCALES
Contact Telephone Number:	512-4436464
Mailing Address:	PO BOX 3689
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787643689
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21634
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040128
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	REEL SHALLOW INC
Operator Address:	PO BOX 3689
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78764
Operator Country:	UNITED STA
Operator Telephone:	1-512-4436464
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17424256661
Operator Bankruptcy Code:	Not reported

DOUG SCALES BODY SHOP (Continued) **S103606424**

Ind. Haz Waste:

Owner Name:	REEL SHALLOW INC
Owner Mailing Address:	PO BOX 3689
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78764
Owner Country:	UNITED STA
Owner Telephone:	1-512-4436464
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17424256661
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	002
Unit Type Code:	16
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	020
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Mobile solvent recovery unit in side paint shop area.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19940221
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 3689
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4436464
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 3689

DOUG SCALES BODY SHOP (Continued) **S103606424**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4436464
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DOUG SCALES
Contact Title:	OWNER
Contact Role:	PRICONT
Contact Address:	PO BOX 3689
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78764
Contact Phone:	1-512-4436464
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 3689
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78764
AR Number:	0000309852
Principal Name:	REEL SHALLOW INC
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 3689
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78764
AR Number:	0000309852
Principal Name:	REEL SHALLOW INC
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 3689
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78764
AR Number:	0000309852
Principal Name:	REEL SHALLOW INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 3689
Mailing Address 2:	Not reported

DOUG SCALES BODY SHOP (Continued) **S103606424**

Mailing City,St,Zip:	AUSTIN, TX 78764
AR Number:	0000309852
Principal Name:	REEL SHALLOW INC
Attention Name:	Not reported
Attention Suffix:	HWF

CENTRAL REGISTRY:

Regulated Entity Number:	RN100582212
Name:	DOUG SCALES BODY SHOP
Address:	2717 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5453
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600292445
Customer Name:	REEL SHALLOW INC
Customer Legal Name:	Reel Shallow, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/21/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2717 S 1st St, Austin, TX

Regulated Entity Number:	RN100582212
Name:	DOUG SCALES BODY SHOP
Address:	2717 S 1ST ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5453
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600292445
Customer Name:	REEL SHALLOW INC
Customer Legal Name:	Reel Shallow, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	2/21/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	2717 S 1st St, Austin, TX

SU3086 **DOUG SCALES BODY SHOP** **RCRA NonGen / NLR** **1004784486**
West **2717 S 1ST ST** **FINDS** **TXD981058266**
1/8-1/4 **AUSTIN, TX 78704** **ECHO**
0.220 mi.
1163 ft. **Site 3 of 3 in cluster SU**

Actual:
572 ft.

Focus Map:
14

RCRA Listings:

Date Form Received by Agency:	20031112
Handler Name:	Doug Scales Body Shop
Handler Address:	S 1ST ST
Handler City,State,Zip:	AUSTIN, TX 78764
EPA ID:	TXD981058266
Contact Name:	DOUG SCALES

DOUG SCALES BODY SHOP (Continued) **1004784486**

Contact Address:	PO BOX 3689
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-443-6464
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 3689
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Doug Scales Body Shop
Owner Type:	Not reported
Operator Name:	Doug Scales Body Shop
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

DOUG SCALES BODY SHOP (Continued) **1004784486**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DOUG SCALES BODY SHOP	
Legal Status:	Not reported
Date Became Current:	20031112
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3689
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-443-6464
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: DOUG SCALES BODY SHOP	
Legal Status:	Not reported
Date Became Current:	20031112
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3689
Owner/Operator City,State,Zip:	AUSTIN, TX 78704
Owner/Operator Telephone:	512-443-6464
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: DOUGLAS SCALES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19850708
Handler Name: DOUG SCALES BODY SHOP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DOUG SCALES BODY SHOP (Continued) **1004784486**

Receive Date:	20031112
Handler Name:	DOUG SCALES BODY SHOP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005084390

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004784486
Registry ID:	110005084390
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005084390
Name:	DOUG SCALES BODY SHOP
Address:	2717 S 1ST ST
City,State,Zip:	AUSTIN, TX 78704

3087 NNE 1/8-1/4 0.221 mi. 1168 ft.

Actual: 460 ft.

Focus Map: 14

AUSTIN ISD
1601 HASKELL ST
AUSTIN, TX 78702

RCRA NonGen / NLR
FINDS
ECHO
TX ASBESTOS
TX Ind. Haz Waste
TX CENTRAL REGISTRY

1000412191
TXD981585151

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Austin Isd
Handler Address:	HASKELL ST
Handler City,State,Zip:	AUSTIN, TX 78702
EPA ID:	TXD981585151
Contact Name:	WAYNE SCHADE PHD
Contact Address:	GUADALUPE ROOM 210
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-451-8411
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Austin Isd
Owner Type:	Municipal
Operator Name:	Austin Isd
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

AUSTIN ISD (Continued) **1000412191**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN ISD	
Legal Status:	District
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: AUSTIN ISD	
Legal Status:	Municipal
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-451-8411
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

AUSTIN ISD (Continued) **1000412191**

Owner/Operator Indicator: Owner
Owner/Operator Name: AUSTIN ISD
Legal Status: Municipal
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 6100 GUADALUPE ROOM 210
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-451-8411
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19860814
Handler Name: MARTIN JUNIOR HIGH SCHOOL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: AUSTIN ISD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005090631

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

AUSTIN ISD (Continued) **1000412191**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412191
Registry ID:	110005090631
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005090631
Name:	AUSTIN ISD
Address:	1601 HASKELL ST
City,State,Zip:	AUSTIN, TX 78702

ASBESTOS:

Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	12/08/2020
Notification Number:	2020007031
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/02/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/02/2020
Certification Statement Phone:	512-778-6069

AUSTIN ISD (Continued) **1000412191**

Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/07/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	12/08/2020
Notification Number:	2020007031
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/19/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

AUSTIN ISD (Continued) **1000412191**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/19/2020
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/07/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

AUSTIN ISD (Continued) **1000412191**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/09/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

AUSTIN ISD (Continued) **1000412191**

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	08/14/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/09/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/14/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

AUSTIN ISD (Continued) **1000412191**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/12/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/12/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N

AUSTIN ISD (Continued) **1000412191**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/28/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/12/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

AUSTIN ISD (Continued) **1000412191**

Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/12/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/27/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

AUSTIN ISD (Continued) **1000412191**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/23/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/23/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham

AUSTIN ISD (Continued) **1000412191**

Violation:	Not reported
Complaint Date:	08/04/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/23/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	07/23/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/31/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

AUSTIN ISD (Continued) **1000412191**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/28/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM

AUSTIN ISD (Continued) **1000412191**

Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	08/11/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D

AUSTIN ISD (Continued) **1000412191**

Certification Statement Date:	07/28/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/07/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/07/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

AUSTIN ISD (Continued) **1000412191**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/07/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	08/18/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported

AUSTIN ISD (Continued) **1000412191**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/07/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/07/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/14/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

AUSTIN ISD (Continued) **1000412191**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/09/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/20/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

AUSTIN ISD (Continued) **1000412191**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	08/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/09/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	08/09/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH

AUSTIN ISD (Continued) **1000412191**

ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	08/21/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/21/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/30/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

AUSTIN ISD (Continued) **1000412191**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/30/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/17/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	07/20/2017
Reason for Inspection:	Kent Burcham
Violation:	Not reported
Complaint Date:	07/28/2017
Notification Number:	2017004950
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

AUSTIN ISD (Continued) **1000412191**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/30/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	06/30/2017
Certification Statement Phone:	512-396-5725
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	07/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET

AUSTIN ISD (Continued) **1000412191**

City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	12/21/2019
Notification Number:	2019008936
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/05/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

AUSTIN ISD (Continued) **1000412191**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Susan Gill
Violation:	Not reported
Complaint Date:	12/23/2019
Notification Number:	2019008936
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/05/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	12/05/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	HIGH
ARU:	9
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

AUSTIN ISD (Continued) **1000412191**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	12/21/2019
Notification Number:	2019008936
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1

AUSTIN ISD (Continued) **1000412191**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/17/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/20/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	MARTIN MIDDLE SCHOOL
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Kim Inga
Violation:	Not reported
Complaint Date:	12/23/2019
Notification Number:	2019008936
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

AUSTIN ISD (Continued) **1000412191**

Date Report Received:	12/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/17/2019
Certification Statement Phone:	512-778-6069
Is The Facility a School or K-12?:	Y
Region:	07
Priority:	TOP
ARU:	12
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/23/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	PORTABLE P-032
Address:	1601 HASKELL STREET
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/07/20

AUSTIN ISD (Continued) **1000412191**

Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	07/20/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017004950
File Number:	21489
License Status Description:	Paid
Expiration Date:	08/14/2017
Original Date:	06/30/2017
Rank Effective Date:	06/30/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	7095
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection

AUSTIN ISD (Continued) **1000412191**

Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

Ind. Haz Waste:

Name:	MARTIN JUNIOR JUNIOR HIGH SCHOOL
Address:	1601 HASKELL ST
City,State,Zip:	AUSTIN, TX 78702
Permit Number:	Not reported
Registration Number:	69676
Registration Initial Notification Date:	08/30/1986
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981585151
Primary NAICS Code:	Not reported
Status Change Date:	19860830
Land Type:	Not reported
Description of Facility Site Location:	1601 Haskell St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	WAYNE SCHADE
Contact Telephone Number:	512-4518411
Mailing Address:	6100 GUADALUPE ST RM 210
Mailing Address2:	ROOM 210
Mailing City,State,Zip:	AUSTIN, TX 787524420
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	24548
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20110418
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0

AUSTIN ISD (Continued) **1000412191**

Transport Own Waste: 0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	6100 GUADALUPE ST RM 210
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4518411
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	6100 GUADALUPE ST RM 210
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4518411
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	Not reported
Deed Record Needed:	Not reported

AUSTIN ISD (Continued) **1000412191**

Deed Recording Date: Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	WAYNE SCHADE
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6100 GUADALUPE ST RM 210
Contact Address 2:	ROOM 210
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4518411
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100650258
Name:	AUSTIN ISD MARTIN JUNIOR HIGH SCHOOL
Address:	1601 HASKELL ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5415
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600345573
Customer Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Customer Legal Name:	Austin Independent School District
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1601 Haskell St, Austin, TX

AUSTIN ISD (Continued) **1000412191**

Regulated Entity Number:	RN100650258
Name:	AUSTIN ISD MARTIN JUNIOR HIGH SCHOOL
Address:	1601 HASKELL ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-5415
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600345573
Customer Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Customer Legal Name:	Austin Independent School District
Customer Ownership Type:	OTHER GOVERNMENT
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1601 Haskell St, Austin, TX

3088 NNE 1/8-1/4 0.221 mi. 1168 ft. | **REDDY ICE OAK FARMS SOUTHLAND** | **910 RED RIVER ST** | **AUSTIN, TX 78701** | **TX LPST** | **TX UST** | **TX HIST UST** | **U003566346** | **N/A**

Actual: 479 ft.

Focus Map: 11

LPST:

Name:	REDDY ICE OAK FARMS SOUTHLAND
Address:	910 RED RIVER ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0046016
LPST Id:	091874
Facility Location:	910 RED RIVER
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/15/1988
Entered Date:	03/15/1988
Reported Date:	03/15/1988
Closure Date:	02/12/2001
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/1P/1/2
Coordinators RPR:	RWL
Responsible Party Name:	Not reported
Responsible Party Contact:	JANE LOMAS
Responsible Party Address:	1201 BELTLINE RD
Responsible Party City,St,Zip:	COPPELL, TX 75019
Responsible Party Telephone:	817/341-8313
Reported Date:	03/15/1988
Case Start Date:	02/12/2001
Reference Number:	RN101492056
Project Manager:	RWL

UST:

Name:	REDDY ICE OAK FARMS SOUTHLAND
Address:	910 RED RIVER ST

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

City,State,Zip:	AUSTIN, TX 787012625
AI Number:	46016
Facility Type:	FLEET REFUELING
Facility Begin Date:	05/16/1988
Facility Status:	INACTIVE
Additional ID:	466603332002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/12/1988
Signature Name/Title On Earliest Reg Form:	BREUT PEFFER,GEN MGR
Application Received Date On Earliest Reg Form:	04/13/1988
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780597
Owner Last Name:	REDDY ICE OAK FARMS SOUTHLAND
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OT
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	459603322002053
Additional ID:	466603332002053
AI Number:	46016
Owner Effective Begin Date:	05/16/1988
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Tank:

Install Date:	01/01/1968
Tank Registration Date:	04/13/1988
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120431
Facility ID:	77385
Ai Number:	46016
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	120869
UST ID:	120431
AI Number:	46016
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	04/13/1988
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

UST ID:	120432
Facility ID:	77385
Ai Number:	46016
Tank Id:	5
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Tank Capacity:	Not reported
UST Comprt ID:	120870
UST ID:	120432
AI Number:	46016
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	04/13/1988
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120433
Facility ID:	77385
Ai Number:	46016
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	120871
UST ID:	120433
AI Number:	46016
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	04/13/1988
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120429
Facility ID:	77385
Ai Number:	46016
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	120867
UST ID:	120429
AI Number:	46016
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1968
Tank Registration Date:	04/13/1988
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	120430
Facility ID:	77385
Ai Number:	46016
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	04/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	120868
UST ID:	120430
AI Number:	46016
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

REDDY ICE OAK FARMS SOUTHLAND (Continued) **U003566346**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	REDDY ICE OAK FARMS SOUTHLAND
Contact Mailing Address (Delivery):	910 RED RIVER ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2625
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77385
Additional ID:	466603332002053
Princ ID:	459603322002053
AI Number:	46016
Facility Name:	REDDY ICE OAK FARMS SOUTHLAND
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	REDDY ICE
Address:	910 RED RIVER ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0069
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3089 ENE 1/8-1/4 0.224 mi. 1181 ft. | **VACANT COMMERCIAL BLDG. 905 E. 7TH ST. AUSTIN, TX 78702** | **TX HIST UST TX ASBESTOS** | **S119160067 N/A**

Actual: 514 ft.

Focus Map: 11

HIST UST AUSTIN:

Name:	CITY VENDING
Address:	905 E 7TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0550
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	VACANT COMMERCIAL BLDG.
Address:	905 E. 7TH ST.
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	09/13/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013006399
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	10/03/2013
Date Routed by Supervisor:	11/04/2013
Date Routed to PSQA:	11/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported

VACANT COMMERCIAL BLDG. (Continued) **S119160067**

Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

SV3090 **J R BODY SHOP** **RCRA NonGen / NLR** **1000164083**
WNW **1001 SAGEBRUSH** **FINDS** **TXD981145071**
1/8-1/4 **AUSTIN, TX 78758** **ECHO**
0.224 mi.
1183 ft. **Site 1 of 2 in cluster SV**

Actual:
733 ft.

Focus Map:
3

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	J R Body Shop
Handler Address:	SAGEBRUSH
Handler City,State,Zip:	AUSTIN, TX 78758
EPA ID:	TXD981145071
Contact Name:	RICHARD RAMIREZ
Contact Address:	SAGEBRUSH
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Telephone:	512-837-5603
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	SAGEBRUSH
Mailing City,State,Zip:	AUSTIN, TX 78758

J R BODY SHOP (Continued) **1000164083**

Owner Name:	J R Body Shop
Owner Type:	Private
Operator Name:	J R Body Shop
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RICHARD RAMIREZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

J R BODY SHOP (Continued) **1000164083**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: J R BODY SHOP	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	1001 SAGEBRUSH
Owner/Operator City,State,Zip:	AUSTIN, TX 78758
Owner/Operator Telephone:	512-837-5603
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: J R BODY SHOP	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	1001 SAGEBRUSH
Owner/Operator City,State,Zip:	AUSTIN, TX 78758
Owner/Operator Telephone:	512-837-5603
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19850930
Handler Name: JR BODY SHOP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010727
Handler Name: J R BODY SHOP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

J R BODY SHOP (Continued) **1000164083**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005085629

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000164083
Registry ID:	110005085629
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005085629
Name:	J R BODY SHOP
Address:	1001 SAGEBRUSH
City,State,Zip:	AUSTIN, TX 78758

SV3091 **J R BODY SHOP** **TX Ind. Haz Waste** **S102749883**
WNW **1001 SAGEBRUSH DR** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78758**
0.224 mi.
1183 ft. **Site 2 of 2 in cluster SV**

Actual:
733 ft.

Focus Map:
3

Ind. Haz Waste:

Name:	J R BODY SHOP
Address:	1001 SAGEBRUSH DR
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	Not reported
Registration Number:	66413
Registration Initial Notification Date:	08/21/1985
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981145071
Primary NAICS Code:	Not reported
Status Change Date:	19850821
Land Type:	PRIVATE
Description of Facility Site Location:	1001 Sagebrush, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1

J R BODY SHOP (Continued) **S102749883**

Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	Not reported
Type of Generator:	NON INDUS
Company Name:	J R BODY SHOP
Contact Name:	RICHARD RAMIREZ
Contact Telephone Number:	512-8375603
Mailing Address:	1001 SAGEBRUSH DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787584855
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21689
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	J R BODY SHOP
Operator Address:	1001 SAGEBRUSH DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78758
Operator Country:	UNITED STA
Operator Telephone:	1-512-8375603
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	J R BODY SHOP
Owner Mailing Address:	1001 SAGEBRUSH DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78758
Owner Country:	UNITED STA
Owner Telephone:	1-512-8375603
Owner Fax:	Not reported
Owner Email Address:	Not reported

J R BODY SHOP (Continued) **S102749883**

Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1001 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8375603
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1001 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8375603
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	RICHARD RAMIREZ
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1001 SAGEBRUSH DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78758
Contact Phone:	1-512-8375603
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100545060
Name:	J R BODY SHOP
Address:	1001 SAGEBRUSH DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4855
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600256218
Customer Name:	J R BODY SHOP
Customer Legal Name:	J R Body Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported

J R BODY SHOP (Continued) **S102749883**

Physical Location Description:	1001 Sagebrush, Austin, TX
Regulated Entity Number:	RN100545060
Name:	J R BODY SHOP
Address:	1001 SAGEBRUSH DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78758-4855
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600256218
Customer Name:	J R BODY SHOP
Customer Legal Name:	J R Body Shop
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1001 Sagebrush, Austin, TX

SE3092 **E-CON-PLACER** **TX HIST UST** **S128729056**
North **1240 OLD BASTROP RD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.225 mi.
1186 ft. **Site 4 of 5 in cluster SE**

Actual:
475 ft.

Focus Map:
16

HIST UST AUSTIN:

Name:	E-CON-PLACER
Address:	1240 OLD BASTROP RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0496
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SE3093 **RIGHT OF WAY PARCEL** **TX RDR** **S127543390**
North **1240 OLD BASTROP HWY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.225 mi.
1186 ft. **Site 5 of 5 in cluster SE**

Actual:
475 ft.

Focus Map:
16

RDR:

RDR ID:	14793
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	RIGHT OF WAY PARCEL
Address:	1240 OLD BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/6/2005
Due Date:	11/5/2005
Tank Owner:	TXDOT
Contact Person:	RANDALL POTTS
Report:	RDR
Latest TCEQ Letter:	No Leaker

RIGHT OF WAY PARCEL (Continued) **S127543390**

Date of Latest TCEQ Letter:	11/29/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	11/29/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3094 East 1/8-1/4 0.225 mi. 1189 ft. **UNIV OF TEXAS DEPT GEOLOGY** **RCRA NonGen / NLR** **1000655879**
CORNER OF 23RD AND SAN JACINTO **TXD988058236**
AUSTIN, TX 78712

Actual: 521 ft.

Focus Map: 11

RCRA Listings:

Date Form Received by Agency:	19911122
Handler Name:	Univ Of Texas Dept Geology
Handler Address:	CORNER OF 23RD AND SAN JACINTO
Handler City,State,Zip:	AUSTIN, TX 78712
EPA ID:	TXD988058236
Contact Name:	PHILIP BENNETT
Contact Address:	PO BOX 7907
Contact City,State,Zip:	AUSTIN, TX 78713-7909
Contact Telephone:	512-471-5172
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 7907
Mailing City,State,Zip:	AUSTIN, TX 78713-7909
Owner Name:	State Of Texas
Owner Type:	State
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

UNIV OF TEXAS DEPT GEOLOGY (Continued) **1000655879**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20000902
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

UNIV OF TEXAS DEPT GEOLOGY (Continued) **1000655879**

Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: K044
Waste Description: Wastewater Treatment Sludges From The Manufacturing And Processing Of Explosives.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE OF TEXAS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 7907
Owner/Operator City,State,Zip:	AUSTIN, TX 78713-7909
Owner/Operator Telephone:	512-471-5172
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19911122
Handler Name: UNIV OF TEXAS DEPT GEOLOGY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

UNIV OF TEXAS DEPT GEOLOGY (Continued) **1000655879**

Evaluation Action Summary:
Evaluations: No Evaluations Found

SW3095 **1001 E 6TH** **TX UST** **U003529611**
East **1001 E 6TH ST** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78702**
0.226 mi.
1192 ft. **Site 1 of 4 in cluster SW**

Actual:
493 ft.

Focus Map:
11

UST:

Name:	1001 E 6TH
Address:	1001 E 6TH ST
City,State,Zip:	AUSTIN, TX 787023215
AI Number:	71691
Facility Type:	RETAIL
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	144501662002053
Facility Exempt Status:	Y
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	JOHN M BURATTI,
Contact Organization Name:	1001 E 6TH
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123355461
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	02/07/1999
Signature Name/Title On Earliest Reg Form:	JOHN M BURATTI,CO OWNER
Application Received Date On Earliest Reg Form:	02/17/1999
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600777437
Owner Last Name:	BURATTI JOHN M AND BURATTI DAVEY L
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/

1001 E 6TH (Continued) **U003529611**

Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	134501652002053
Additional ID:	144501662002053
AI Number:	71691
Owner Effective Begin Date:	08/31/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	02/17/1999
Number of Compartments:	1
Tank Capacity:	750
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	189729
Facility ID:	109094
Ai Number:	71691
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/03/1999
Empty:	N
Tank Regulatory Status:	EXEMPT NON-USE SINCE 1974
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

1001 E 6TH (Continued) **U003529611**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	750
UST Comprt ID:	167216
UST ID:	189729
AI Number:	71691
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

1001 E 6TH (Continued) **U003529611**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	27399
Cert ID:	70448
UST Comprt ID:	202611
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	305521
UST Comprt ID:	883992
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70447
UST Comprt ID:	202612
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70446
UST Comprt ID:	202613
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70445
UST Comprt ID:	202614
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70444
UST Comprt ID:	202617
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70443
UST Comprt ID:	202616

1001 E 6TH (Continued) **U003529611**

UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70442
UST Comprt ID:	202615
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70452
UST Comprt ID:	202607
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	384230
UST Comprt ID:	1121212
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	368207
UST Comprt ID:	1072229
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	350217
UST Comprt ID:	1018057
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	332469
UST Comprt ID:	964053
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	328379
UST Comprt ID:	952034
UST ID:	73254

1001 E 6TH (Continued) **U003529611**

AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	288845
UST Comprt ID:	833946
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	271861
UST Comprt ID:	783569
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	255169
UST Comprt ID:	733919
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	239280
UST Comprt ID:	687230
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	222837
UST Comprt ID:	639098
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70455
UST Comprt ID:	202604
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70454
UST Comprt ID:	202605
UST ID:	73254
AI Number:	71691

1001 E 6TH (Continued) **U003529611**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70453
UST Comprt ID:	202606
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70451
UST Comprt ID:	202608
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70450
UST Comprt ID:	202609
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A
Self Cert ID:	27399
Cert ID:	70449
UST Comprt ID:	202610
UST ID:	73254
AI Number:	71691
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	18280
Facility ID:	109094
AI Number:	71691
Application Received Date:	09/10/2012
Scheduled Construction Date:	09/11/2012
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported

1001 E 6TH (Continued) **U003529611**

Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	53372
General Desc Of Prop Construct:	REMOVAL OF "GHOST TANK" DISCOVERED DURING EARTH WORK AT THE SITE. APPROXIMATE 2 50 GALLON, STEEL UST WHICH WAS EMPTY AT THE TIME OF DISCOVERY. RELEASE DETERMIN ATION TO BE CONDUCTED IN ACCORDANCE WITH RG-411.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	19650
UST ID:	Not reported
NOC ID:	18280
AI Number:	71691
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	TERRACON
Representative Name:	KEVIN DENSON
Mailing Address (Delivery):	5307 INDUSTRIAL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78735
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	4421122
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	19649
UST ID:	Not reported
NOC ID:	18280
AI Number:	71691
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001398
Company Name:	USA ENVIRONMENT LP
Representative Name:	KLAY PATTESON
Mailing Address (Delivery):	18745 GOLL ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78266
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	4765920
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported

1001 E 6TH (Continued) **U003529611**

Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Facility Billing Contacts:
Contact Organization Name: BURATTI JOHN M AND BURATTI DAVEY L
Contact Mailing Address (Delivery): 11209 MATISSE TRL
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: AUSTIN, TX 78726 1449
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 109094
Additional ID: 144501662002053
Princ ID: 134501652002053
AI Number: 71691
Facility Name: 1001 E 6TH
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: JOHN M BURATTI/

HIST UST AUSTIN:
Name: COMMERCIAL PROPERTY
Address: 1001 E 6TH ST
City,State,Zip: AUSTIN, TX
Id UST: C0668
HID UST: Not reported
Inspection: Not reported
Due: Not reported

SW3096 **PROPOSED CORAZON** **TX RDR** **S127538728**
East **1001 E 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.226 mi.
1192 ft. **Site 2 of 4 in cluster SW**

Actual:
493 ft.

Focus Map:
11

RDR:
RDR ID: 20822
Facility ID: 71691
RN: Not reported
CN: Not reported
Name: PROPOSED CORAZON
Address: 1001 E 6TH ST
City,State,Zip: AUSTIN, TX
Date Report Received: 10/18/2012
Due Date: 12/17/2012
Tank Owner: CORAZON URBAN MF EAST LP
Contact Person: JOHN BURNHAM
Report: RDR
Latest TCEQ Letter: No Leaker
Date of Latest TCEQ Letter: 12/3/2012
Project Manager: Stacey Dunahoo
Team: Team A

PROPOSED CORAZON (Continued) **S127538728**

New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	SJD
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

SR3097 **STRAIT MUSIC CO** **TX HIST UST** **S128728938**
WNW **908 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.227 mi.
1199 ft. **Site 3 of 3 in cluster SR**

Actual:
486 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	STRAIT MUSIC CO
Address:	908 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0165
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SX3098 **UNICOPY CORP** **RCRA NonGen / NLR** **1000180115**
WNW **1011 W ANDERSON LN** **FINDS** **TXD981594906**
1/8-1/4 **AUSTIN, TX 78757** **ECHO**
0.228 mi.
1205 ft. **Site 1 of 2 in cluster SX**

Actual:
773 ft.

Focus Map:
6

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Unicopy Corp
Handler Address:	W ANDERSON LN
Handler City,State,Zip:	AUSTIN, TX 78757
EPA ID:	TXD981594906
Contact Name:	JACK MAXWELL
Contact Address:	W ANDERSON LN
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Telephone:	512-451-0251
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11

UNICOPY CORP (Continued) **1000180115**

Mailing Address:	W ANDERSON LN
Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Name:	Unicopy Corp
Owner Type:	Private
Operator Name:	Unicopy Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: UNICOPY CORP	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	1011 W ANDERSON LN
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	512-451-0251

UNICOPY CORP (Continued) **1000180115**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: UNICOPY CORP	
Legal Status:	Private
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	1011 W ANDERSON LN
Owner/Operator City,State,Zip:	AUSTIN, TX 78757
Owner/Operator Telephone:	512-451-0251
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19861031
Handler Name: UNICOPY CORP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010823
Handler Name: UNICOPY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

UNICOPY CORP (Continued) **1000180115**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005092808

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000180115
Registry ID:	110005092808
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005092808
Name:	UNICOPY CORP
Address:	1011 W ANDERSON LN
City,State,Zip:	AUSTIN, TX 78757

SX3099 **UNICOPY** **TX Ind. Haz Waste** **S102753136**
WNW **1011 W ANDERSON LN** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78757**
0.228 mi.
1205 ft. **Site 2 of 2 in cluster SX**

Actual:
773 ft.

Focus Map:
6

Ind. Haz Waste:

Name:	UNICOPY
Address:	1011 W ANDERSON LN
City,State,Zip:	AUSTIN, TX 78757
Permit Number:	Not reported
Registration Number:	70731
Registration Initial Notification Date:	10/30/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981594906
Primary NAICS Code:	Not reported
Status Change Date:	19861030
Land Type:	PRIVATE
Description of Facility Site Location:	1011 W Anderson Ln, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1

UNICOPY (Continued) **S102753136**

Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	UNICOPY CORPORATION OF AUSTIN
Contact Name:	JACK MAXWELL
Contact Telephone Number:	512-4510251
Mailing Address:	1011 W ANDERSON LN
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787571547
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25539
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	UNICOPY CORPORATION OF AUSTIN
Operator Address:	1011 W ANDERSON LN
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78757
Operator Country:	UNITED STA
Operator Telephone:	1-512-4510251
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	UNICOPY CORPORATION OF AUSTIN
Owner Mailing Address:	1011 W ANDERSON LN
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78757
Owner Country:	UNITED STA
Owner Telephone:	1-512-4510251

UNICOPY (Continued) **S102753136**

Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1011 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4510251
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1011 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4510251
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JACK MAXWELL
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1011 W ANDERSON LN
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78757
Contact Phone:	1-512-4510251
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1011 W ANDERSON LN
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78757
AR Number:	0000303072
Principal Name:	UNICOPY CORPORATION OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1011 W ANDERSON LN

UNICOPY (Continued) **S102753136**

Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78757
AR Number:	0000303072
Principal Name:	UNICOPY CORPORATION OF AUSTIN
Attention Name:	Not reported
Attention Suffix:	HWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100565183
Name:	UNICOPY
Address:	1011 W ANDERSON LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-1547
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600275861
Customer Name:	UNICOPY CORPORATION OF AUSTIN
Customer Legal Name:	Unicopy Corporation of Austin
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1011 W ANDERSON LN, AUSTIN, TX

Regulated Entity Number:	RN100565183
Name:	UNICOPY
Address:	1011 W ANDERSON LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78757-1547
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600275861
Customer Name:	UNICOPY CORPORATION OF AUSTIN
Customer Legal Name:	Unicopy Corporation of Austin
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1011 W ANDERSON LN, AUSTIN, TX

SS3100 **TERMINIX OF AUSTIN** **TX Ind. Haz Waste** **S103606298**
WNW **1206 PARKWAY** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.229 mi.
1210 ft. **Site 4 of 9 in cluster SS**

Actual:
489 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	TERMINIX OF AUSTIN
Address:	1206 PARKWAY
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66069

TERMINIX OF AUSTIN (Continued) **S103606298**

Registration Initial Notification Date:	07/27/2001
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD026031542
Primary NAICS Code:	Not reported
Status Change Date:	20010727
Land Type:	PRIVATE
Description of Facility Site Location:	1206 Parkway, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TERMINIX COMPANY OF AUSTIN
Contact Name:	Not reported
Contact Telephone Number:	Not reported
Mailing Address:	1206 PARKWAY
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787034133
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21372
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020411
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TERMINIX COMPANY OF AUSTIN
Operator Address:	1206 PARKWAY
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78703
Operator Country:	UNITED STA
Operator Telephone:	Not reported
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown

TERMINIX OF AUSTIN (Continued) **S103606298**

Operator Tax ID:	17416154999
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TERMINIX COMPANY OF AUSTIN
Owner Mailing Address:	1206 PARKWAY
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Country:	UNITED STA
Owner Telephone:	Not reported
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	17416154999
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1206 PARKWAY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1206 PARKWAY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1206 PARKWAY
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

SS3101 **TERMINIX INTERNAT'L OF AUSTIN** **TX HIST UST** **S128729036**
WNW **1206 PARKWAY** **N/A**
1/8-1/4 **AUSTIN, TX**
0.229 mi.
1210 ft. **Site 5 of 9 in cluster SS**

Actual:
489 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	TERMINIX INTERNAT'L OF AUSTIN
Address:	1206 PARKWAY
City,State,Zip:	AUSTIN, TX
Id UST:	C0448
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SS3102 **TERMINIX COMPANY OF AUSTIN** **RCRA NonGen / NLR** **1000300067**
WNW **1206 PARKWAY** **TXD026031542**
1/8-1/4 **AUSTIN, TX 78703**
0.229 mi.
1210 ft. **Site 6 of 9 in cluster SS**

Actual:
489 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Terminix Company Of Austin
Handler Address:	PARKWAY
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD026031542
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	PARKWAY
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PARKWAY
Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Name:	Terminix Company Of Austin
Owner Type:	Private
Operator Name:	Terminix Company Of Austin
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

TERMINIX COMPANY OF AUSTIN (Continued) **1000300067**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: BILL YOUNGBLOOD	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TERMINIX COMPANY OF AUSTIN	
Legal Status:	Private
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	1206 PARKWAY
Owner/Operator City,State,Zip:	AUSTIN, TX 78703
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

TERMINIX COMPANY OF AUSTIN (Continued) **1000300067**

Owner/Operator Indicator: Operator
Owner/Operator Name: TERMINIX COMPANY OF AUSTIN
Legal Status: Private
Date Became Current: 20010727
Date Ended Current: Not reported
Owner/Operator Address: 1206 PARKWAY
Owner/Operator City,State,Zip: AUSTIN, TX 78703
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19800820
Handler Name: TERMINIX CO OF AUSTIN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010727
Handler Name: TERMINIX COMPANY OF AUSTIN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56171
NAICS Description: EXTERMINATING AND PEST CONTROL SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SS3103 **TERMINIX INTERNATIONAL OF AUSTIN** **TX LPST** **U001736045**
WNW **1206 PARKWAY** **TX UST** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX CENTRAL REGISTRY**
0.229 mi.
1210 ft. **Site 7 of 9 in cluster SS**

Actual:
489 ft.

Focus Map:
11

LPST:

Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0065241
LPST Id:	107715
Facility Location:	1206 PARKWAY
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/13/1994
Entered Date:	03/16/1995
Reported Date:	01/13/1994
Closure Date:	02/24/1998
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BILL YOUNGBLOOD
Responsible Party Address:	2800 EDGEWATER
Responsible Party City,St,Zip:	AUSTIN, TX 78733
Responsible Party Telephone:	512/263-2301
Reported Date:	01/13/1994
Case Start Date:	02/24/1998
Reference Number:	RN100616499
Project Manager:	HWELCH

UST:

Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
City,State,Zip:	AUSTIN, TX 787034133
AI Number:	65241
Facility Type:	RETAIL
Facility Begin Date:	12/13/1993
Facility Status:	INACTIVE
Additional ID:	404664162002152
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	BILL YOUNGBLOOD,
Contact Organization Name:	TERMINIX INTERNATIONAL OF AUSTIN
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124767055
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	11/29/1993
Signature Name/Title On Earliest Reg Form:	BILL YOUNGBLOOD,PRES
Application Received Date On Earliest Reg Form:	12/10/1993
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601254709
Owner Last Name:	YOUNGBLOOD BILL
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	396664152002152
Additional ID:	404664162002152
AI Number:	65241
Owner Effective Begin Date:	12/13/1993
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/10/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149339
Facility ID:	96998
Ai Number:	65241
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/04/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/25/1993

Compartment Records:

Tank ID:	2
Tank Capacity:	1000
UST Comprt ID:	165102
UST ID:	149339
AI Number:	65241
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	12/10/1993
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149340
Facility ID:	96998
Ai Number:	65241
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/04/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/25/1993

Compartment Records:

Tank ID:	1
Tank Capacity:	1000
UST Comprt ID:	165103
UST ID:	149340
AI Number:	65241
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	YOUNGBLOOD BILL
Contact Mailing Address (Delivery):	1206 PARKWAY
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78703 4133
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	96998
Additional ID:	404664162002152
Princ ID:	396664152002152
AI Number:	65241
Facility Name:	TERMINIX INTERNATIONAL OF AUSTIN
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	BILL YOUNGBLOOD/

CENTRAL REGISTRY:

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604445858
Customer Name:	TERMINIX OF AUSTIN
Customer Legal Name:	Terminix Of Austin
Customer Ownership Type:	ORGANIZATION

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604445858
Customer Name:	TERMINIX OF AUSTIN
Customer Legal Name:	Terminix Of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600325591
Customer Name:	TERMINIX COMPANY OF AUSTIN
Customer Legal Name:	Terminix Company of Austin, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601254709
Customer Name:	YOUNGBLOOD BILL
Customer Legal Name:	Youngblood Bill
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	12/13/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 1206 Parkway, Austin, TX

Regulated Entity Number: RN100616499
Name: TERMINIX INTERNATIONAL OF AUSTIN
Address: 1206 PARKWAY
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4133
Status: ACTIVE
Status Date: ##########
Customer Number: CN604445858
Customer Name: TERMINIX OF AUSTIN
Customer Legal Name: Terminix Of Austin
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 1206 Parkway, Austin, TX

Regulated Entity Number: RN100616499
Name: TERMINIX INTERNATIONAL OF AUSTIN
Address: 1206 PARKWAY
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4133
Status: ACTIVE
Status Date: ##########
Customer Number: CN600325591
Customer Name: TERMINIX COMPANY OF AUSTIN
Customer Legal Name: Terminix Company of Austin, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 7/27/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 1206 Parkway, Austin, TX

Regulated Entity Number: RN100616499
Name: TERMINIX INTERNATIONAL OF AUSTIN
Address: 1206 PARKWAY
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78703-4133
Status: ACTIVE
Status Date: ##########
Customer Number: CN601254709
Customer Name: YOUNGBLOOD BILL
Customer Legal Name: Youngblood Bill
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 12/13/1993
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 1206 Parkway, Austin, TX

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604445858
Customer Name:	TERMINIX OF AUSTIN
Customer Legal Name:	Terminix Of Austin
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600325591
Customer Name:	TERMINIX COMPANY OF AUSTIN
Customer Legal Name:	Terminix Company of Austin, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600325591
Customer Name:	TERMINIX COMPANY OF AUSTIN
Customer Legal Name:	Terminix Company of Austin, Inc.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Regulated Entity Number:	RN100616499
Name:	TERMINIX INTERNATIONAL OF AUSTIN
Address:	1206 PARKWAY

TERMINIX INTERNATIONAL OF AUSTIN (Continued) **U001736045**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4133
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601254709
Customer Name:	YOUNGBLOOD BILL
Customer Legal Name:	Youngblood Bill
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	12/13/1993
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1206 Parkway, Austin, TX

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

3104 **HID SHELL** **TX HIST UST** **S126850100**
ESE **601 CENTER RIDGE DR** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.230 mi.
1213 ft.

Actual:
734 ft.

Focus Map:
2

HIST UST AUSTIN:

Name:	OLD EXECUTIVE AIRPORT
Address:	601 CENTER RIDGE DR
City,State,Zip:	AUSTIN, TX
Id UST:	3393
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN106609514
Name:	HID SHELL
Address:	601 CENTER RIDGE DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78753-1013
Status:	ACTIVE
Status Date:	2013-02-20
Customer Number:	CN602546517
Customer Name:	DAVID E HARVEY BUILDERS INC
Customer Legal Name:	David E. Harvey Builders, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2013-02-20
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	236220
Primary NAICS Industry Type Description:	Commercial and Institutional Building Construction
Physical Location Description:	Not reported

3105 East 1/8-1/4 0.230 mi. 1213 ft. | **ABIA CONSOLIDATED RENTAL CAR FACILITY**
3819 PRESIDENTIAL BLVD STE G63
AUSTIN, TX 78719

TX UST | **U004245831**
TX HIST UST | **N/A**
TX ASBESTOS
TX Financial Assurance

Actual: 496 ft.

Focus Map: 20

UST:

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 787192323
AI Number:	86714
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/21/2014
Facility Status:	ACTIVE
Additional ID:	828346992014092
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78719
Contact Name/Title:	JOHN DISNEY,
Contact Organization Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9073557868
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	JDISNEY@CONRACSOLUTIONS.COM
Signature Date On Earliest Reg Form:	07/10/2020
Signature Name/Title On Earliest Reg Form:	JOSH DISNEY,FCACILITY MANAGER
Application Received Date On Earliest Reg Form:	07/21/2020
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	603575262021237
Additional ID:	828346992014092
Ai Number:	86714
Operator CN:	CN605926542
Operator Name:	CONRAC SOLUTIONS OPERATORS LLC
Operator Effective Begin Date:	12/01/2017
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604924142
Owner Last Name:	AUSTIN CONRAC LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	103472562015253
Additional ID:	828346992014092
AI Number:	86714
Owner Effective Begin Date:	09/01/2015
State Tax ID:	32044844093
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	131839
Cert ID:	373712
AI Number:	86714
Self Certification Date:	06/08/2022
Signature Name/Title:	KIRISTI BEATTIE FAC MNGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	358268
AI Number:	86714
Self Certification Date:	08/06/2021

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Signature Name/Title:	JOSH DISNEY FACILITY MNGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	340419
AI Number:	86714
Self Certification Date:	07/10/2020
Signature Name/Title:	JOSH DISNEY FCACILITY MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	324231
AI Number:	86714
Self Certification Date:	08/08/2019
Signature Name/Title:	JOSH DISNEY FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	307533
AI Number:	86714
Self Certification Date:	07/27/2018

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Signature Name/Title:	JOSH DISNEY FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	289780
AI Number:	86714
Self Certification Date:	07/31/2017
Signature Name/Title:	KODY NELSON FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	272081
AI Number:	86714
Self Certification Date:	06/30/2016
Signature Name/Title:	KODY NELSON FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	131839
Cert ID:	259893
AI Number:	86714
Self Certification Date:	09/08/2015

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Signature Name/Title:	KODY NELSON FAC MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Tank:

Install Date:	08/21/2014
Tank Registration Date:	09/10/2015
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	220608
Facility ID:	131839
Ai Number:	86714
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	08/21/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/10/2015

Compartment Records:

Tank ID:	2
Tank Capacity:	20000
UST Comprt ID:	189054
UST ID:	220608
AI Number:	86714
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	32953
Cert ID:	107455
UST Comprt ID:	301820
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107458
UST Comprt ID:	301817
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107454
UST Comprt ID:	301819
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107456
UST Comprt ID:	301821
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107457
UST Comprt ID:	301818
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A

Install Date:	08/21/2014
Tank Registration Date:	09/10/2015
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	220609

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Facility ID:	131839
Ai Number:	86714
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	08/21/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/10/2015

Compartment Records:

Tank ID:	3
Tank Capacity:	20000

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

UST Comprt ID:	189055
UST ID:	220609
AI Number:	86714
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	32953
Cert ID:	107455
UST Comprt ID:	301820
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A

Self Cert ID:	32953
Cert ID:	107458
UST Comprt ID:	301817
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Self Cert ID:	32953
Cert ID:	107454
UST Comprt ID:	301819
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107456
UST Comprt ID:	301821
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107457
UST Comprt ID:	301818
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Install Date:	08/21/2014
Tank Registration Date:	09/10/2015
Number of Compartments:	1
Tank Capacity:	20000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	220607
Facility ID:	131839
Ai Number:	86714
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	08/21/2014
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	09/10/2015

Compartment Records:

Tank ID:	1
Tank Capacity:	20000
UST Comprt ID:	189053
UST ID:	220607
AI Number:	86714
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	32953
Cert ID:	107455
UST Comprt ID:	301820
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107458
UST Comprt ID:	301817
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107454
UST Comprt ID:	301819
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107456
UST Comprt ID:	301821
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A
Self Cert ID:	32953
Cert ID:	107457
UST Comprt ID:	301818
UST ID:	99956
AI Number:	86714
Tank ID:	1
Compartment ID:	A

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Construction Notification:

NOC ID:	27752
Facility ID:	131839
AI Number:	86714
Application Received Date:	06/15/2015
Scheduled Construction Date:	06/08/2015
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	03/31/2014
Signature Date On Form:	03/28/2014
Signature Name On Form:	HARRY WILSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN
Owner CN At Time Of Construction:	CN600135198
Owner AR At Time Of Construction:	Not reported
General Desc Of Prop Construct:	INSTALL (3) 20K UST'S, 24 DISPENSERS WITH ASSOCIATED PIPING, VALVES AND SUMPS FOR UNLEADED FUEL DISPENSING. REC'D AMENDED NOC 6-15-15 SHOWING NEW INSTALL DATE OF 6-8-15.

NOC ID:	25524
Facility ID:	131839
AI Number:	86714
Application Received Date:	03/31/2014
Scheduled Construction Date:	04/28/2014
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	03/31/2014
Signature Date On Form:	03/28/2014
Signature Name On Form:	HARRY WILSON
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Owner CN At Time Of Construction: CN600135198
Owner AR At Time Of Construction: Not reported
General Desc Of Prop Construct: INSTALL (3) 20K UST'S, (24) DISPENSERS WITH ASSOCIATED PIPING, VALVES AND SUMPS FOR UNLEADED FUEL DISPENSING.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	69425
UST ID:	220609
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	UNIFIED SERVICES OF TEXAS INCORPORATED
Representative Name:	Not reported
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	817
Fax Number:	4881729
Email Address:	ACCOUNTS@UST-INC.COM

Cont/Cons/Installer ID:	65138
UST ID:	Not reported
NOC ID:	27752
AI Number:	86714
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	UNIFIED SERVICES OF TEXAS INCORPORATED
Representative Name:	MARSHALL RYAN
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	817
Fax Number:	4881729
Email Address:	ACCOUNTS@UST-INC.COM

Cont/Cons/Installer ID:	59762
UST ID:	Not reported
NOC ID:	25524

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

AI Number:	86714
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	UNIFIED SERVICES OF TEXAS INCORPORATED
Representative Name:	Not reported
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	817
Fax Number:	4881729
Email Address:	ACCOUNTS@UST-INC.COM

Cont/Cons/Installer ID:	69424
UST ID:	220608
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	UNIFIED SERVICES OF TEXAS INCORPORATED
Representative Name:	Not reported
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	817
Fax Number:	4881729
Email Address:	ACCOUNTS@UST-INC.COM

Cont/Cons/Installer ID:	69422
UST ID:	220607
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000970
Company Name:	UNIFIED SERVICES OF TEXAS INCORPORATED
Representative Name:	Not reported
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	817
Fax Number:	4881729
Email Address:	ACCOUNTS@UST-INC.COM

Cont/Cons/Installer ID:	69426
UST ID:	220609
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	TONY LASOYA
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	69423
UST ID:	220608
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	TONY LASOYA
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	59761
UST ID:	Not reported
NOC ID:	25524
AI Number:	86714
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001210
Company Name:	RYAN MARSHALL D
Representative Name:	Not reported
Mailing Address (Delivery):	2110 GREENBRIAR DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SOUTHLAKE
Mailing State:	TX
Mailing Zip:	76092
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	817
Phone Number:	4819510
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	69421
UST ID:	220607
NOC ID:	Not reported
AI Number:	86714
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	TONY LASOYA
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AUSTIN CONRAC LLC
Contact Mailing Address (Delivery):	12130 COLWICK ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78216 2721
Phone Number/Ext:	210 9799990/0

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	131839
Additional ID:	828346992014092
Princ ID:	103472562015253
AI Number:	86714
Facility Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
AR Number:	77248
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	MARSHALL FEIN/

HIST UST AUSTIN:

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3380
HID UST:	Not reported
Inspection:	05/15/2014
Due:	Not reported

ASBESTOS:

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD
City,State,Zip:	AUSTIN, TX 78719
Date of inspection:	Not reported
Reason for Inspection:	KAREN DIANA
Violation:	Not reported
Complaint Date:	09/19/2016
Notification Number:	2016007116
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Notification Status:	Current
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	07/28/2016
Certification Statement Phone:	214-886-0396
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	271561
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Issuer Phone:	Not reported
Policy Number:	FEI-EIL-22910-05
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	10/01/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	255023
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2020
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	Not reported
Policy Number:	FEI-EIL-22910-04
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	10/01/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	235249
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2019
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	1 512 9135145
Policy Number:	FEI-EIL-22910-03
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	10/01/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	217908
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2018
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	1 512 9135145
Policy Number:	FEI EIL 22910 02
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	09/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	200847
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2017
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	1 907 5611250
Policy Number:	FEI EIL 22910 01
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	09/01/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	164561
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2015
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	CHUBB CUSTOM INS CO
Issuer Phone:	907 561 1250
Policy Number:	37314542
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	09/01/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	182986
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2016
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	ADMIRAL INS CO
Issuer Phone:	856 429 9200
Policy Number:	FEI-EIL-22910-00
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	09/01/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	ABIA CONSOLIDATED RENTAL CAR FACILITY
Address:	3819 PRESIDENTIAL BLVD STE G63
City,State,Zip:	AUSTIN, TX 78719
Region:	2
Facility ID:	131839
Finass ID:	151526
AI:	86714
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/01/2015
Date Financial Assurance Form Rec:	07/21/2020
Issuer Name:	CHUBB CUSTOM INS CO
Issuer Phone:	907 561 1250
Policy Number:	37314542
Coverage Amount:	OVER 2,000,000

ABIA CONSOLIDATED RENTAL CAR FACILITY (Continued) **U004245831**

Coverage Expiration Date: 09/01/2016
Ins Premium Pre-Paid For Entire Yr: No
Proof of Financial Assurance: Yes

SY3106 **AVIS RENT A CAR SYSTEM** **TX AST** **A100153656**
WNW **9320 RENTAL CAR LN** **N/A**
1/8-1/4 **AUSTIN, TX 78719**
0.231 mi.
1218 ft. **Site 1 of 5 in cluster SY**

Actual:
508 ft.

Focus Map:
20

AST:

Name:	AVIS RENT A CAR SYSTEM
Address:	9320 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX 787192412
Facility ID:	109608
Additional ID:	512543392002054
AI Number:	72022
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78719
Contact Name/Title:	CHRIS KARGER/
Contact Organization Name:	AVIS RENT A CAR SYSTEM
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5125303413
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	05/21/1999
Signature First Name on Earliest Reg Form:	AVIS RENT A CAR
Application Received Date on Earliest Reg Form:	05/24/1999
Signature Middle Name on Earliest Reg Form:	R
Signature Last Name on Earliest Reg Form:	SYSTEM
Signature Title on Earliest Reg Form:	REAL ESTATE COUNSEL
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	109608
Tank ID:	1
AST ID:	190744
AI Number:	72022
Install Date:	05/01/1999

AVIS RENT A CAR SYSTEM (Continued) **A100153656**

Tank Registration Date:	05/24/1999
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	05/01/1999
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

SY3107 **AVIS RENT A CAR SYSTEMS, INC.** **TX HIST UST** **S108861692**
WNW **9320 RENTAL CAR LN** **TX TIER 2** **N/A**
1/8-1/4 **AUSTIN, TX 78719**
0.231 mi.
1218 ft. **Site 2 of 5 in cluster SY**

Actual:
508 ft.

Focus Map:
20

HIST UST AUSTIN:

Name:	AVIS RENT A CAR
Address:	9320 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX
Id UST:	A0021
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TIER 2:

Facility Id/Name:	FATR20072VL2A403GW1H/AVIS RENT A CAR SYSTEMS, INC.
Reporting Year:	2007
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	8/5/2008
Date Tier 2 Signed:	1/25/2008
Mailing Address:	6 Sylvan Way
Mailing City/State/Country:	Parsippany, NJ USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Paul Fen, Env. Compliance Specialist
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported

AVIS RENT A CAR SYSTEMS, INC. (Continued) **S108861692**

Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	T
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20062VL2A403GW1H/AVIS RENT A CAR SYSTEMS INC.
Reporting Year:	2006
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	10/10/2007
Date Tier 2 Signed:	1/16/2007
Mailing Address:	6 Sylvan Way
Mailing City/State/Country:	Parsippany, NJ USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Paul Fen Env. Compliance Specialist
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Notes: Not reported
Validation: Not reported

Notes: Not reported
Validation: Not reported

SZ3108 ESE 1/8-1/4 0.234 mi. 1235 ft. — **TEXAS ALTERNATOR**, **1230 BASTROP HWY**, **AUSTIN, TX** — **TX HIST UST** — **S128728867** / **N/A**

Site 1 of 3 in cluster SZ

Actual: 475 ft.
Focus Map: 16

HIST UST AUSTIN:

Name:	TEXAS ALTERNATOR
Address:	1230 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	C0011
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

SZ3109 ESE 1/8-1/4 0.234 mi. 1235 ft. — **TX ALTERNATOR STARTER SERVICE**, **1230 BASTROP HWY**, **AUSTIN, TX** — **TX HIST UST** — **S128728722** / **N/A**

Site 2 of 3 in cluster SZ

Actual: 475 ft.
Focus Map: 16

HIST UST AUSTIN:

Name:	TX ALTERNATOR STARTER SERVICE
Address:	1230 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	3304
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3110 ENE 1/8-1/4 0.235 mi. 1239 ft. — **COLLIN'S GARAGE**, **1115 BASTROP HWY**, **AUSTIN, TX** — **TX HIST UST** — **S128728962** / **N/A**

Actual: 452 ft.
Focus Map: 16

HIST UST AUSTIN:

Name:	COLLIN'S GARAGE
Address:	1115 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	C0227
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TA3111 WNW 1/8-1/4 0.235 mi. 1239 ft. | **SAFEWAY RENTAL EQUIPMENT CO.** | **TX HIST UST** | **S111678800**
405 N LAMAR BLVD | **N/A**
AUSTIN, TX

Site 1 of 5 in cluster TA

Actual: 473 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	SAFEWAY RENTAL EQUIPMENT CO.
Address:	405 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0865
HID UST:	865
Inspection:	04/29/2009
Due:	04/29/2012

TA3112 WNW 1/8-1/4 0.235 mi. 1239 ft. | **CAPITOL CHEVROLET MAKE READY** | **TX UST** | **U001277214**
409 N LAMAR BLVD | **TX HIST UST** | **N/A**
AUSTIN, TX 78703

Site 2 of 5 in cluster TA

Actual: 473 ft.
Focus Map: 11

UST:

Name:	CAPITOL CHEVROLET MAKE READY
Address:	409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787035409
AI Number:	45654
Facility Type:	FLEET REFUELING
Facility Begin Date:	12/29/1987
Facility Status:	INACTIVE
Additional ID:	801071142002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	W M WILLIAMS,SERV MGR
Contact Organization Name:	CAPITOL CHEVROLET MAKE READY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124766641
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/30/1986
Signature Name/Title On Earliest Reg Form:	W M WILLIAMS,SERV MGR
Application Received Date On Earliest Reg Form:	12/31/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600246029
Owner Last Name:	CAPITOL CHEVROLET INC

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	68479132001288
Additional ID:	801071142002117
AI Number:	45654
Owner Effective Begin Date:	12/29/1987
State Tax ID:	17410470334
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	250
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119515
Facility ID:	77176
Ai Number:	45654
Tank Id:	9
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	9
Tank Capacity:	250
UST Comprt ID:	118324
UST ID:	119515
AI Number:	45654
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171411
Facility ID:	77176
Ai Number:	45654
Tank Id:	8
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	8
Tank Capacity:	40
UST Comprt ID:	118325
UST ID:	171411
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171412
Facility ID:	77176
Ai Number:	45654
Tank Id:	7
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	40
UST Comprt ID:	118326
UST ID:	171412
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171413
Facility ID:	77176
Ai Number:	45654
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	40
UST Comprt ID:	118327
UST ID:	171413
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171414

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Facility ID:	77176
Ai Number:	45654
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	40

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

UST Comprt ID:	118328
UST ID:	171414
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171415
Facility ID:	77176
Ai Number:	45654
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	40
UST Comprt ID:	118329
UST ID:	171415
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171416
Facility ID:	77176
Ai Number:	45654
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	40
UST Comprt ID:	118330
UST ID:	171416
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171417
Facility ID:	77176
Ai Number:	45654
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	40
UST Comprt ID:	118331
UST ID:	171417
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171418
Facility ID:	77176
Ai Number:	45654
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1966
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	40
UST Comprt ID:	118332
UST ID:	171418
AI Number:	45654
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

CAPITOL CHEVROLET MAKE READY (Continued) **U001277214**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CAPITOL CHEVROLET INC
Contact Mailing Address (Delivery):	PO BOX 1988
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1988
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77176
Additional ID:	801071142002117
Princ ID:	68479132001288
AI Number:	45654
Facility Name:	CAPITOL CHEVROLET MAKE READY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	CAPITOL CHEVROLET MAKE READY
Address:	409 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	EX031
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TB3113 **WHOLE FOODS MARKET** **TX TANKS** **S129182536**
WNW **525 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.235 mi.
1241 ft. **Site 1 of 3 in cluster TB**

Actual:
481 ft.

Focus Map:
11

TANKS:

Facility ID:	138007
Name:	WHOLE FOODS MARKET
Address:	525 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787035411
Total UST:	Not reported
Additional ID:	750424592022322
AI Number:	92923
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported

WHOLE FOODS MARKET (Continued) **S129182536**

Records Off-Site:	Not reported
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Enforcement Action Date:	Not reported
Facility Not Inspectable:	Not reported
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

TA3114 **AMERICAN CLEANERS** **TX DRYCLEANERS** **S108995462**
WNW **407 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.237 mi.
1249 ft. **Site 3 of 5 in cluster TA**

Actual:
473 ft.

Focus Map:
11

DRYCLEANERS:

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS

AMERICAN CLEANERS (Continued) **S108995462**

Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335

AMERICAN CLEANERS (Continued) **S108995462**

EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	Not reported

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

AMERICAN CLEANERS (Continued) **S108995462**

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	AMERICAN CLEANERS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN103961173
Region:	11
CN Number:	CN600404552
DCR Number:	Not reported
AR Number:	24000170
Principal Name:	JOASH ENTERPRISES INC
Bill Addr1:	PO BOX 160335
Bill Addr2:	Not reported

AMERICAN CLEANERS (Continued) **S108995462**

Bill City/State/Zip:	AUSTIN, TX 78716 0335
EMail:	Not reported
Phone Number:	Not reported
Site Name:	AMERICAN CLEANERS
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

TA3115 **CAPITOL CHEVROLET CO.** **TX HIST UST** **S128729332**
WNW **407 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.237 mi.
1249 ft. **Site 4 of 5 in cluster TA**

Actual:
473 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	CAPITOL CHEVROLET CO.
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0593
HID UST:	593
Inspection:	Not reported
Due:	06/01/2012

TA3116 **C. B. SMITH MOTORS** **TX HIST UST** **S128729426**
WNW **407 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.237 mi.
1249 ft. **Site 5 of 5 in cluster TA**

Actual:
473 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	C. B. SMITH MOTORS
Address:	407 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0802
HID UST:	802
Inspection:	Not reported
Due:	06/01/2012

TC3117 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **TX AST** **S102752981**
ESE **5710 GUADALUPE ST** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.238 mi.
1255 ft. **Site 1 of 4 in cluster TC**

Actual:
663 ft.

Focus Map:
9

AST:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5710 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787524536
Facility ID:	113114

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S102752981**

Additional ID:	716632952002156
AI Number:	74167
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78752
Contact Name/Title:	TIFFANEY S ADAMS/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124242410
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	07/29/2021
Signature First Name on Earliest Reg Form:	MARK
Application Received Date on Earliest Reg Form:	08/05/2021
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	BLOMQUIST
Signature Title on Earliest Reg Form:	ENVIRONMENTAL MANAGER
Signature Role on Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	113114
Tank ID:	1
AST ID:	226674
AI Number:	74167
Install Date:	02/19/2021
Tank Registration Date:	08/05/2021
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	02/19/2021
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	3000
Substance:	Not reported
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	N
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S102752981**

Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	EXEMPT BY TCEQ RULE
Inst Stage Date:	Not reported

Ind. Haz Waste:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5710 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	70558
Registration Initial Notification Date:	09/01/1986
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD981606361
Primary NAICS Code:	Not reported
Status Change Date:	19860901
Land Type:	OTHER
Description of Facility Site Location:	5710 Guadalupe St, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Name:	JERRY HARMS
Contact Telephone Number:	512-4242042
Mailing Address:	PO BOX 4087
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787730001
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25372
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020415
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S102752981**

Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Operator Address:	PO BOX 4087
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78773
Operator Country:	UNITED STA
Operator Telephone:	1-512-4242042
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Owner Mailing Address:	PO BOX 4087
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78773
Owner Country:	UNITED STA
Owner Telephone:	1-512-4242042
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 4087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78773
Contact Phone:	1-512-4242042
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 4087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78773
Contact Phone:	1-512-4242042
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JERRY HARMS
Contact Title:	SUPERVISOR OF AUTO SHOPS
Contact Role:	PRICONT

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **S102752981**

Contact Address:	PO BOX 4087
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78773
Contact Phone:	1-512-4242042
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4087
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78773
AR Number:	0000303039
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	NWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4087
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78773
AR Number:	0000303039
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	NWF

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4087
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78773
AR Number:	0000303039
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 4087
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78773
AR Number:	0000303039
Principal Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Attention Name:	Not reported
Attention Suffix:	HWF

TC3118 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **RCRA NonGen / NLR** **1000156885**
ESE **5710 GUADALUPE ST** **ICIS** **TXD981606361**
1/8-1/4 **AUSTIN, TX 78752** **FINDS**
0.238 mi. **ECHO**
1255 ft. **Site 2 of 4 in cluster TC**

Actual:
663 ft.

Focus Map:
9

RCRA Listings:

Date Form Received by Agency:	20010727
Handler Name:	Texas Department Of Public Safety
Handler Address:	GUADALUPE ST
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD981606361
Contact Name:	JERRY HARMS
Contact Address:	PO BOX 4087
Contact City,State,Zip:	AUSTIN, TX 78773
Contact Telephone:	512-424-2042
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 4087
Mailing City,State,Zip:	AUSTIN, TX 78773
Owner Name:	Texas Department Of Public Safety
Owner Type:	Other
Operator Name:	Texas Department Of Public Safety
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **1000156885**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Legal Status:	Other
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4087
Owner/Operator City,State,Zip:	AUSTIN, TX 78773
Owner/Operator Telephone:	512-424-2042
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF PUBLIC SAFETY

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **1000156885**

Legal Status:	Other
Date Became Current:	20010727
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 4087
Owner/Operator City,State,Zip:	AUSTIN, TX 78773
Owner/Operator Telephone:	512-424-2042
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STATE OF TEXAS	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19860915
Handler Name:	TEXAS DEPT OF PUBLIC SAFETY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010727
Handler Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19900301
Handler Name:	TEXAS DEPT OF PUBLIC SAFETY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **1000156885**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: 06-1997-0381
FRS ID: 110005094708
Action Name: TEXAS DEPT. OF PUBLIC SAFETY
Facility Name: TEXAS DEPT OF PUBLIC SAFETY
Facility Address: 5710 GUADALUPE ST
AUSTIN, TX 78752
Enforcement Action Type: RCRA 9006 Field Citation (UST)
Facility County: TRAVIS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 9006FC
Facility SIC Code: 9221
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.324356
Longitude in Decimal Degrees: -97.722912
Permit Type Desc: Not reported
Program System Acronym: 24118
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Address: 5710 GUADALUPE ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 9221

Facility Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Address: 5710 GUADALUPE ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 9221

Facility Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Address: 5710 GUADALUPE ST
Tribal Indicator: N
Fed Facility: No

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **1000156885**

NAIC Code: Not reported
SIC Code: 9221

Facility Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Address: 5710 GUADALUPE ST
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 9221

FINDS:
Registry ID: 110005094708

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000156885
Registry ID: 110005094708
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110005094708
Name: TEXAS DEPARTMENT OF PUBLIC SAFETY
Address: 5710 GUADALUPE ST
City,State,Zip: AUSTIN, TX 78752

TC3119 **TEXAS DEPT PUBLIC SAFETY** **TX RDR** **S127539526**
ESE **5710 GUADALUPE ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.238 mi.
1255 ft. **Site 3 of 4 in cluster TC**

Actual:
663 ft.

Focus Map:
9

RDR:

RDR ID:	27385
Facility ID:	74167
RN:	Not reported
CN:	Not reported
Name:	TEXAS DEPT PUBLIC SAFETY
Address:	5710 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/20/2019
Due Date:	10/19/2019
Tank Owner:	TEXAS DEPT PUBLIC SAFETY
Contact Person:	MARK BLOMQUIST
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/7/2019
Project Manager:	Saul Garza
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TC3120 **TEXAS DEPARTMENT OF PUBLIC SAFETY** **TX UST** **U003765101**
ESE **5710 GUADALUPE ST** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.238 mi.
1255 ft. **Site 4 of 4 in cluster TC**

Actual:
663 ft.

Focus Map:
9

UST:

Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Address:	5710 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787524536
AI Number:	74167
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	ACTIVE
Additional ID:	716632952002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	TIFFANEY S ADAMS,

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124242410
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/29/2021
Signature Name/Title On Earliest Reg Form:	MARK BLOMQUIST,ENVIRONMENTAL MANAGER
Application Received Date On Earliest Reg Form:	08/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	189570062001351
Additional ID:	716632952002156
Ai Number:	74167
Operator CN:	CN600610976
Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Operator Effective Begin Date:	04/27/2001
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	JERSEY VILLAGE TX 77065-4523
Contact Phone Country Code:	1
Contact Phone Area Code:	281
Contact Phone Number:	5171509
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600610976
Owner Last Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	JERSEY VILLAGE
Contact Mailing State:	TX
Contact Mailing Zip:	77065
Contact Mailing Zip5:	4523
Contact Phone Number/Ext:	1 281 5171509/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Contact Address Deliverable:	Not reported
Princ ID:	189570062001351
Additional ID:	716632952002156
AI Number:	74167
Owner Effective Begin Date:	04/27/2001
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY

Self Certification:

Self Cert ID:	113114
Cert ID:	374737
AI Number:	74167
Self Certification Date:	07/21/2022
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	113114
Cert ID:	358137
AI Number:	74167
Self Certification Date:	07/21/2021
Signature Name/Title:	MARK BLOMQUIST ENV. MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	113114
Cert ID:	341495
AI Number:	74167
Self Certification Date:	07/31/2020
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	324512
AI Number:	74167
Self Certification Date:	07/19/2019
Signature Name/Title:	MARK BLOMQUIST ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	301396
AI Number:	74167
Self Certification Date:	02/28/2018
Signature Name/Title:	MARK BLOMQUIST ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	284455
AI Number:	74167
Self Certification Date:	02/28/2017
Signature Name/Title:	MARK BLOMQUIST ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	268157
AI Number:	74167
Self Certification Date:	04/12/2016
Signature Name/Title:	PHILIP JOHNSON ASST MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	251114
AI Number:	74167
Self Certification Date:	03/24/2015
Signature Name/Title:	PHILIP JOHNSON ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	234756
AI Number:	74167
Self Certification Date:	04/01/2014
Signature Name/Title:	PHILIP JOHNSON ENVIRO MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	113114
Cert ID:	218950
AI Number:	74167
Self Certification Date:	04/29/2013
Signature Name/Title:	PHILIP JOHNSON ENV COORD
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N
Self Cert ID:	113114
Cert ID:	197041
AI Number:	74167
Self Certification Date:	03/12/2012
Signature Name/Title:	PHILIP JOHNSON ENV COORD
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197040
AI Number:	74167
Self Certification Date:	04/04/2011
Signature Name/Title:	PHILIP JOHNSON ENV COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197039
AI Number:	74167
Self Certification Date:	04/05/2010
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197038
AI Number:	74167
Self Certification Date:	06/25/2009
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197037
AI Number:	74167
Self Certification Date:	03/27/2008
Signature Name/Title:	ANDREW MOKRY MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197036
AI Number:	74167
Self Certification Date:	04/26/2007
Signature Name/Title:	ANDREW MOKRY MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197035
AI Number:	74167
Self Certification Date:	04/19/2006
Signature Name/Title:	CYNTHIA R LEFTWICH PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197034
AI Number:	74167
Self Certification Date:	06/01/2005
Signature Name/Title:	GERARDO R DE LA PENA ENV GROUP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197033
AI Number:	74167
Self Certification Date:	04/16/2004
Signature Name/Title:	CYNTHIA R LEFTWICH PRES LIBERTY EQUIP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197032
AI Number:	74167
Self Certification Date:	04/01/2003
Signature Name/Title:	TERRY SAULS VP OPERATIONS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	113114
Cert ID:	197031
AI Number:	74167
Self Certification Date:	04/18/2002
Signature Name/Title:	H D LARK PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	113114
Cert ID:	197030
AI Number:	74167
Self Certification Date:	04/20/2001
Signature Name/Title:	WILLIAM SCHRAMM
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1995
Tank Registration Date:	04/27/2001
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	197187
Facility ID:	113114
Ai Number:	74167
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	176886
UST ID:	197187
AI Number:	74167
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1995

Install Date:	01/01/1995
Tank Registration Date:	04/27/2001
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	197188
Facility ID:	113114
Ai Number:	74167
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	176887
UST ID:	197188
AI Number:	74167
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	01/01/1995

Construction Notification:

NOC ID:	34934
Facility ID:	113114
AI Number:	74167
Application Received Date:	06/27/2019
Scheduled Construction Date:	07/15/2019
UST Improvement:	Y
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	06/27/2019
Signature Date On Form:	06/27/2019
Signature Name On Form:	ALAN LOPEZ
Signature Company On Form:	Not reported
Signature Title On Form:	SR PROJ MGR
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS DEPARTMENT OF PUBLIC SAFETY;TEXAS DEPARTMENT OF P
Owner CN At Time Of Construction:	CN600610976,CN600610976
Owner AR At Time Of Construction:	79599A,79599U
General Desc Of Prop Construct:	INSTALLATION OF TWO GASBOY DISPENSERS, TWO UDCS, AND ASSOCIATED DW UNDERGROUND PIPING TO TWO SUBMERSIBLE PUMPS AT TWO EXISTING 6,000 UNLEADED GAS USTS. INSTALLATION OF ONE NEW VEEDER ROOT TLS 450 PLUS MONITORING CONSOLE

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	82907
UST ID:	Not reported
NOC ID:	34934
AI Number:	74167
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	D & H UNITED FUELING SOLUTIONS INC

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

Representative Name:	ANTHONY QUESSLER
Mailing Address (Delivery):	12100 CROWNPOINT DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78233
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6513882
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	210
Fax Number:	6513884
Email Address:	Not reported
Cont/Cons/Installer ID:	82906
UST ID:	Not reported
NOC ID:	34934
AI Number:	74167
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001740
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	PO BOX 4087 MSC0225
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78773 0001
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	113114
Additional ID:	716632952002156
Princ ID:	189570062001351
AI Number:	74167
Facility Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
AR Number:	79599
AR UST Number Suffix:	A

TEXAS DEPARTMENT OF PUBLIC SAFETY (Continued) **U003765101**

AR AST Number Suffix:	U
Contact Name/Title:	MARK BLOMQUIST/

HIST UST AUSTIN:

Name:	DEPT OF PUB SAFETY AUTO SHOP
Address:	5710 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	EX036
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TD3121 **PPD DEVELOPMENT** **TX Ind. Haz Waste** **S116387735**
SSW **7551 METRO CENTER DR STE 200** **N/A**
1/8-1/4 **AUSTIN, TX 78744**
0.239 mi.
1261 ft. **Site 1 of 3 in cluster TD**

Actual:
558 ft.

Focus Map:
19

Ind. Haz Waste:

Name:	PPD DEVELOPMENT
Address:	7551 METRO CENTER DR STE 200
City,State,Zip:	AUSTIN, TX 78744
Permit Number:	Not reported
Registration Number:	95475
Registration Initial Notification Date:	08/01/2013
Registration Last Amendment Date:	03/02/2023
EPA Identification:	TXR000081554
Primary NAICS Code:	541715
Status Change Date:	20130801
Land Type:	PRIVATE
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	PPD DEVELOPMENT LP
Contact Name:	JOHN ANDOE
Contact Telephone Number:	512-7475330
Mailing Address:	7551 METRO CENTER DR STE 300
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787441645
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	130820
Site Owner Tax ID:	742325267
Site Location Latitude:	-00.000

PPD DEVELOPMENT (Continued) **S116387735**

Site Location Longitude:	-000.000
Last Update to NOR Data:	20230302
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	PPD DEVELOPMENT LP
Operator Address:	7551 METRO CENTER DR STE 200
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78744
Operator Country:	UNITED STA
Operator Telephone:	1-512-4488850
Operator Fax Number:	1-512-6857260
Operator Email:	FARAH.ESCALANI@PPDI.COM
Operator Business Type:	Corporation
Operator Tax ID:	32046813195
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	PPD DEVELOPMENT LP
Owner Mailing Address:	7551 METRO CENTER DR STE 200
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78744
Owner Country:	UNITED STA
Owner Telephone:	1-512-4488850
Owner Fax:	1-512-6857260
Owner Email Address:	FARAH.ESCALANI@PPDI.COM
Owner Business Type:	Corporation
Owner Tax ID:	32046813195
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported

PPD DEVELOPMENT (Continued) **S116387735**

Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	55 GALLON DRUMS STORED IN A LOCKED CHEMICAL ROOM @WEST END OF BUILD
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20130801
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	50
Capacity Measurement:	C
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	040
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	LAB PACKs
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20230302
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	003
Unit Type Code:	04
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported

PPD DEVELOPMENT (Continued) **S116387735**

System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	LAB Packs of expired chemicals
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20230302
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	7551 METRO CENTER DR STE 200
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-4488850
Contact Fax:	1-512-6857260
Contact Email:	FARAH.ESCALANI@PPDI.COM

Contact Name:	JOHN ANDOE
Contact Title:	HEALTH & SAFETY SPECIALIS
Contact Role:	PRICONT
Contact Address:	7551 METRO CENTER DR STE 300
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78744
Contact Phone:	1-512-7475330
Contact Fax:	1-512-6857260
Contact Email:	JOHN.ANDOE@PPDI.COM

Ind. Haz Waste:

Waste ID:	356391
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUC
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541712
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

PPD DEVELOPMENT (Continued) **S116387735**

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	417699
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUCE
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541712
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	417700
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUCE
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541712
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

PPD DEVELOPMENT (Continued) **S116387735**

Ind. Haz Waste:

Waste ID:	417701
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004201H
Waste Code Status:	ACTIVE
Waste Form:	201
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUCE
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	541712
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	424129
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Subjects are dosed with experimental medications. We collect their urin produced
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	2-PROPANOL 0 5 M AMM
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

PPD DEVELOPMENT (Continued) **S116387735**

Waste ID:	424131
Texas Waste Code:	Not reported
Texas Waste Code 2:	00062071
Waste Code Status:	ACTIVE
Waste Form:	207
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Subjects are dosed with experimental medications. We collect their urine produce
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	3 URINE 1 DMSO TRIT
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	424132
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	each 20ml vial is Permafluor E 10 mL plus Carborsorb E 10 mL. Liquid scintillati
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SCINTILLIATION VIALS
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	424126
Texas Waste Code:	Not reported
Texas Waste Code 2:	20010011
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	1

PPD DEVELOPMENT (Continued) **S116387735**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sample oxidizer cocktail for tritium counting
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	MONOPHASE S
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	424127
Texas Waste Code:	Not reported
Texas Waste Code 2:	20020031
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Scintilliation Waste used in labratory, waste is 99% water and 1 % Monophase S
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SCINTILLIATION WASTE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	437679
Texas Waste Code:	Not reported
Texas Waste Code 2:	23012191
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	SUBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUCE
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

PPD DEVELOPMENT (Continued) **S116387735**

New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	20 IPA IN URINE
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	437681
Texas Waste Code:	Not reported
Texas Waste Code 2:	2302203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	UBJECTS ARE DOSED WITH EXPERIMENTAL MEDICATIONS. WE COLLECT THEIR URINE PRODUCED
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	20 IPA IN URINE
Primary NAICS Code:	541712
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	437687
Texas Waste Code:	Not reported
Texas Waste Code 2:	2303001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Labpack Acid & Acid Compatibles For Incineration
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	Not reported
Audit Performed:	0
Company Waste ID:	LAB PACK ACIDS
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	437688
Texas Waste Code:	Not reported

PPD DEVELOPMENT (Continued) **S116387735**

Texas Waste Code 2:	2304001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Labpack Organics for Incineration
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	LABPACK ORGANICS
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	437689
Texas Waste Code:	Not reported
Texas Waste Code 2:	2305001H
Waste Code Status:	ACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Labpack Flammables for Incineration
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	LABPACK FLAMMABLE
Primary NAICS Code:	541712
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	437690
Texas Waste Code:	Not reported
Texas Waste Code 2:	2306119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	500g of expired Sodium azide
Standard Industrial Code:	Not reported
Primary Source:	G22

PPD DEVELOPMENT (Continued) **S116387735**

Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	SODIUM AZIDE
Primary NAICS Code:	541712
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	LYDIA GLORIA
Contact Title:	Not reported
Contact Telephone:	0-512-7474752 x0
Mailing Address:	929 N FRONT ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WILMINGTON, NC 28401
AR Number:	0000317646
Principal Name:	PPD DEVELOPMENT LP
Attention Name:	GLORIA ,LYDIA
Attention Suffix:	HWG

Contact Name:	LYDIA GLORIA
Contact Title:	Not reported
Contact Telephone:	0-512-7474752 x0
Mailing Address:	929 N FRONT ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	WILMINGTON, NC 28401
AR Number:	0000317646
Principal Name:	PPD DEVELOPMENT LP
Attention Name:	GLORIA ,LYDIA
Attention Suffix:	NWG

TD3122 **PPD DEVELOPMENT** **RCRA-SQG** **1016452418**
SSW **7551 7551 METRO CENTER DR STE 200** **FINDS** **TXR000081554**
1/8-1/4 **AUSTIN, TX 78744** **ECHO**
0.239 mi.
1261 ft. **Site 2 of 3 in cluster TD**

Actual:
558 ft.

Focus Map:
19

RCRA Listings:

Date Form Received by Agency:	20230302
Handler Name:	Ppd Development
Handler Address:	METRO CENTER DR STE 200
Handler City,State,Zip:	AUSTIN, TX 78744-1645
EPA ID:	TXR000081554
Contact Name:	JOHN ANDOE
Contact Address:	METRO CENTER DR STE 300
Contact City,State,Zip:	AUSTIN, TX 78744-1645
Contact Telephone:	512-747-5330
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	METRO CENTER DR STE 300
Mailing City,State,Zip:	AUSTIN, TX 78744-1645
Owner Name:	Ppd Development Llc
Owner Type:	Private
Operator Name:	Ppd Development Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

PPD DEVELOPMENT (Continued) **1016452418**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230311
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	P105
Waste Description:	Sodium Azide

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801

PPD DEVELOPMENT (Continued) **1016452418**

Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

PPD DEVELOPMENT (Continued) **1016452418**

Owner/Operator Name: PPD DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20130801
Date Ended Current: Not reported
Owner/Operator Address: 7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1645
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PPD DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20130801
Date Ended Current: Not reported
Owner/Operator Address: 7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1645
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PPD DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20130801
Date Ended Current: Not reported
Owner/Operator Address: 7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1645
Owner/Operator Telephone: 512-448-8850
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PPD DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20130801
Date Ended Current: Not reported
Owner/Operator Address: 7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1645
Owner/Operator Telephone: 512-448-8850
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PPD DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20130801
Date Ended Current: Not reported
Owner/Operator Address: 7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip: AUSTIN, TX 78744-1645
Owner/Operator Telephone: 512-448-8850
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

PPD DEVELOPMENT (Continued) **1016452418**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: PPD DEVELOPMENT LLC	
Legal Status:	Private
Date Became Current:	20130801
Date Ended Current:	Not reported
Owner/Operator Address:	7551 METRO CENTER DR STE 200
Owner/Operator City,State,Zip:	AUSTIN, TX 78744-1645
Owner/Operator Telephone:	512-448-8850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20130801
Handler Name: PPD	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20130801
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20191211
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported

PPD DEVELOPMENT (Continued) **1016452418**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200421
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20210325
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20220112
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20230302
Handler Name: PPD DEVELOPMENT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

PPD DEVELOPMENT (Continued) **1016452418**

Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 541712
NAICS Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING, AND LIFE SCIENCES (EXCEPT BIOTECHNOLOGY)

NAICS Code: 541715
NAICS Description: RESEARCH AND DEVELOPMENT IN THE PHYSICAL, ENGINEERING, AND LIFE SCIENCES (EXCEPT NANOTECHNOLOGY AND BIOTECHNOLOGY

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056336157

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016452418
Registry ID: 110056336157
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056336157
Name: PPD DEVELOPMENT
Address: 7551 7551 METRO CENTER DR STE 200
City,State,Zip: AUSTIN, TX 78744

TD3123 **MET CENTER** **TX AST** **A100225426**
SSW **7551 METRO CENTER DR # 15** **N/A**
1/8-1/4 **AUSTIN, TX 78744**
0.239 mi.
1261 ft. **Site 3 of 3 in cluster TD**

Actual:
558 ft.

Focus Map:
19

AST:
Name: MET CENTER
Address: 7551 METRO CENTER DR # 15
City,State,Zip: AUSTIN, TX 787441625
Facility ID: 111814
Additional ID: 757409142002075
AI Number: 73387

MET CENTER (Continued) **A100225426**

Facility Type:	Not reported
Facility Begin Date:	03/01/2001
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78744
Contact Name/Title:	VERNON WILLIAMS/
Contact Organization Name:	MET CENTER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	7132651364
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	07/25/2000
Signature First Name on Earliest Reg Form:	MICHAEL
Application Received Date on Earliest Reg Form:	08/08/2000
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	BINDER
Signature Title on Earliest Reg Form:	MANAGER
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	111814
Tank ID:	1
AST ID:	194762
AI Number:	73387
Install Date:	03/01/2001
Tank Registration Date:	08/08/2000
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	07/19/2001
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N

MET CENTER (Continued) **A100225426**

Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	111814
Tank ID:	2
AST ID:	194763
AI Number:	73387
Install Date:	03/01/2001
Tank Registration Date:	08/08/2000
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	07/19/2001
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	111814
Tank ID:	3
AST ID:	194764
AI Number:	73387
Install Date:	03/01/2001
Tank Registration Date:	08/08/2000
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	07/19/2001
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported
Facility ID:	111814

MET CENTER (Continued) **A100225426**

Tank ID:	4
AST ID:	194765
AI Number:	73387
Install Date:	03/01/2001
Tank Registration Date:	08/08/2000
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	07/19/2001
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	Y
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	111814
Tank ID:	A
AST ID:	201252
AI Number:	73387
Install Date:	02/19/2003
Tank Registration Date:	02/24/2003
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	02/19/2003
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	8600
Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

3124 East 1/8-1/4 0.240 mi. 1266 ft. | **ROY AND MATIAS VELASQUEZ PLAZA**
1020 E 5TH ST
AUSTIN, TX 78702 | **US BROWNFIELDS** | **1026464445**
N/A

Actual: 477 ft.

Focus Map: 11

US BROWNFIELDS:

Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99

Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99

Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

	property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	12353.41
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	9/25/2017
Ownership Entity:	Government
Completion Date:	11/6/2017
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	12353.41
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Start Date:	9/25/2017
Ownership Entity:	Government
Completion Date:	11/6/2017
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99

Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA
Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8383
Assessment Funding Source:	EPA

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F90901
Start Date:	7/21/2016
Ownership Entity:	Government
Completion Date:	8/26/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99
Name:	ROY AND MATIAS VELASQUEZ PLAZA

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

Address:	1020 E 5TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.2
Latitude:	30.2643423
Longitude:	-97.7317275
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	This property is currently owned by the City. The planned use is a small plaza and an entrance to an historic trail. This site had two RECs; one due to historical dry cleaning sites upgradient to the property and two historical automotive stations upgradient to the property. When redevelopment occurs, the small space will be a gateway to a historic trail and a pocket park in East Austin. This will leverage $1m. Former Use: The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Datum:	North American Datum of 1983
Acres Property ID:	219985
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8383
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F90901
Start Date:	7/21/2016
Ownership Entity:	Government
Completion Date:	8/26/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported

ROY AND MATIAS VELASQUEZ PLAZA (Continued) **1026464445**

State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.2
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.2
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The site has been owned by the city since the blocks were platted in the early 1900's. It has never been developed.
Below Poverty Number:	761
Below Poverty Percent:	25.17
Meidan Income:	3590
Meidan Income Number:	1010
Meidan Income Percent:	33.4
Vacant Housing Number:	214
Vacant Housing Percent:	13.46
Unemployed Number:	181
Unemployed Percent:	5.99

Click this hyperlink while viewing on your computer to access additional US BROWNFIELDS: detail in the EDR Site Report.

3125 WNW 1/8-1/4 0.240 mi. 1268 ft. **PTP OPERATING 916A PRAIRIE TRL AUSTIN, TX 78758** **TX DRYCLEANERS** **S108995352 N/A**

Actual: 745 ft.

Focus Map: 3

DRYCLEANERS:

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN605126408
DCR Number:	DCR14068
AR Number:	24007397
Principal Name:	PT-P OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	PTP OPERATING
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2019

PTP OPERATING (Continued) **S108995352**

Solvent:	PETROLEUM
Gallons:	506
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN602563447
DCR Number:	DCR14068
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	PTP OPERATING
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	424
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN605126408
DCR Number:	DCR14068
AR Number:	24007397
Principal Name:	PT-P OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	PTP OPERATING
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PETROLEUM
Gallons:	424
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN602563447

PTP OPERATING (Continued) **S108995352**

DCR Number:	DCR14068
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PETROLEUM
Gallons:	340
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN605126408
DCR Number:	DCR14068
AR Number:	24007397
Principal Name:	PT-P OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	PTP OPERATING
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	PETROLEUM
Gallons:	309
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE

PTP OPERATING (Continued) **S108995352**

Fiscal Year:	FY2010
Solvent:	PETROLEUM
Gallons:	1093
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PETROLEUM
Gallons:	490
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PETROLEUM
Gallons:	445
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11

PTP OPERATING (Continued) **S108995352**

CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PETROLEUM
Gallons:	629
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2014
Solvent:	PETROLEUM
Gallons:	340
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN605126408
DCR Number:	DCR14068
AR Number:	24007397
Principal Name:	PT-P OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	PTP OPERATING
Site Type:	FACILITY REGISTRATION

PTP OPERATING (Continued) **S108995352**

Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PETROLEUM
Gallons:	400
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	REGION 11 - AUSTIN
CN Number:	CN605126408
DCR Number:	DCR14068
AR Number:	24007397
Principal Name:	PT-P OPERATING LLC
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	BARB@RICKSCLEANERS.COM
Phone Number:	512 4532916
Site Name:	Not reported
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	NO
Gross Receipts:	$150,000 OR LESS

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360

PTP OPERATING (Continued) **S108995352**

Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PETROLEUM
Gallons:	1100
Part Stat:	YES
Gross Receipts:	$100,000 OR LESS

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PETROLEUM
Gallons:	1099
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP

PTP OPERATING (Continued) **S108995352**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PETROLEUM
Gallons:	663
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PETROLEUM
Gallons:	0
Part Stat:	NO
Gross Receipts:	> $150,000

Name:	PTP OPERATING LP
Address:	916A PRAIRIE TRL
City,State,Zip:	AUSTIN, TX 78758
RN Number:	RN104467360
Region:	11
CN Number:	CN602563447
DCR Number:	Not reported
AR Number:	24002374
Principal Name:	PTP OPERATING LP
Bill Addr1:	5324 CAMERON RD
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78723 2419
EMail:	Not reported
Phone Number:	512 4532916
Site Name:	PTP OPERATING LP
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PETROLEUM
Gallons:	1830
Part Stat:	NO
Gross Receipts:	> $150,000

SY3126 **ALAMO RENT-A-CAR** **TX AST** **A100248020**
WNW **9310 RENTAL CAR LN** **N/A**
1/8-1/4 **AUSTIN, TX 78719**
0.240 mi.
1269 ft. **Site 3 of 5 in cluster SY**

Actual:
509 ft.

Focus Map:
20

AST:

Name:	ALAMO RENT-A-CAR
Address:	9310 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX 787192412
Facility ID:	113942
Additional ID:	117640732002053
AI Number:	74622
Facility Type:	FLEET REFUELING
Facility Begin Date:	03/15/2000
Facility Status:	Inactive
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	0
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78719
Contact Name/Title:	PHILLIP RUSSELL/
Contact Organization Name:	ALAMO RENT-A-CAR
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5129125354
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	10/18/2016
Signature First Name on Earliest Reg Form:	DONALD
Application Received Date on Earliest Reg Form:	10/18/2016
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	SCHWENT
Signature Title on Earliest Reg Form:	Not reported
Signature Role on Earliest Reg Form:	Not reported
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	N
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	113942
Tank ID:	1
AST ID:	198555
AI Number:	74622
Install Date:	03/15/2000
Tank Registration Date:	10/15/2001
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	03/15/2016
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000

ALAMO RENT-A-CAR (Continued) **A100248020**

Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	113942
Tank ID:	2
AST ID:	198556
AI Number:	74622
Install Date:	03/15/2001
Tank Registration Date:	10/15/2001
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	03/15/2016
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	12000
Substance:	GASOLINE
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

SY3127 **ALAMO CAR RENTAL** **TX HIST UST** **S113687180**
WNW **9310 RENTAL CAR LANE** **TX TIER 2** **N/A**
1/8-1/4 **AUSTIN, TX 78719**
0.240 mi.
1269 ft. **Site 4 of 5 in cluster SY**

Actual:
509 ft.

Focus Map:
20

HIST UST AUSTIN:

Name:	NATIONAL ALAMO CAR RENTAL
Address:	9310 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX
Id UST:	A0026
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ALAMO CAR RENTAL (Continued) **S113687180**

TIER 2:

Facility Id/Name:	FATR201292220F00SHF6/ALAMO CAR RENTAL
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	1/21/2013
Mailing Address:	4210 S. Congress Ave
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	Not reported
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Howard Zaroff
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	532111
Id Type:	NAICS
Description:	Passenger Car Rental
Last Modified:	1/16/2013
Id:	17-614-7684
Id Type:	Dun & Bradstreet
Description:	Not reported
Last Modified:	1/21/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	4210 S. Congress Ave.
Contact City/State/Zip:	Austin, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	EAN Holdings, LLC
Title:	Attn: Controller
Modification Date:	2/23/2013

Contact:

Contact Email:	Donald.G.Schwent@ehi.com
Contact Mail Address:	4210 S. Congress Ave
Contact City/State/Zip:	Austin, TX 78745

ALAMO CAR RENTAL (Continued) **S113687180**

Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Donald Schwent
Title:	Controller
Modification Date:	2/23/2013

Contact:

Contact Email:	Phillip.L.Russell@ehi.com
Contact Mail Address:	4210 S. Congress Ave.
Contact City/State/Zip:	Austin, TX 78745
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Phil Russell
Title:	Operations Manager
Modification Date:	2/23/2013

Chemical Inventory:

Facility Id:	FATR201292220F00SHF6
Chemical Name:	Gasoline
Chemical Inv Record Id:	CVTR201292220F00XHN2
CAS Number:	8006-61-9
Chemical Same As Last Year:	T
Acute Health Risks:	T
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	100,000 - 999,999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	2/22/2013
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201292220F00YHNZ
Chemical Inventory Record Id:	CVTR201292220F00XHN2
Amt Of Sub Stored Or Transported:	24000
Amount Units:	gallons
Type Of Storage:	Above ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	2 - 12,000 gallon ASTs located in the Northeast corner of the lot.
Last Modified:	2/22/2013

ALAMO CAR RENTAL (Continued) **S113687180**

Mixture:

Record Key:	CMTR201292220F00ZHQC
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	2/22/2013

Record Key:	CMTR201292220F010HQU
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	2/22/2013

Record Key:	CMTR201292220F011HR9
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	2/22/2013

Record Key:	CMTR201292220F012HRR
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	2/22/2013

Record Key:	CMTR201292220F013HS7
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported
Weight/Volume:	Not reported
Mixture Ehs:	Not reported
Mixture Last Modified:	2/22/2013

Record Key:	CMTR201292220F014HSN
Chemical Inv Record Id:	CVTR201292220F00XHN2
Mix Chemical:	Not reported
Percentage:	Not reported
Facility Id:	FATR201292220F00SHF6
Mixture Cas:	Not reported

ALAMO CAR RENTAL (Continued) **S113687180**

Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Record Key: CMTR201292220F015HT4
Chemical Inv Record Id: CVTR201292220F00XHN2
Mix Chemical: Not reported
Percentage: Not reported
Facility Id: FATR201292220F00SHF6
Mixture Cas: Not reported
Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Record Key: CMTR201292220F016HU1
Chemical Inv Record Id: CVTR201292220F00XHN2
Mix Chemical: Not reported
Percentage: Not reported
Facility Id: FATR201292220F00SHF6
Mixture Cas: Not reported
Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Record Key: CMTR201292220F017HUH
Chemical Inv Record Id: CVTR201292220F00XHN2
Mix Chemical: Not reported
Percentage: Not reported
Facility Id: FATR201292220F00SHF6
Mixture Cas: Not reported
Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Record Key: CMTR201292220F018HUY
Chemical Inv Record Id: CVTR201292220F00XHN2
Mix Chemical: Not reported
Percentage: Not reported
Facility Id: FATR201292220F00SHF6
Mixture Cas: Not reported
Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Record Key: CMTR201292220F019HVE
Chemical Inv Record Id: CVTR201292220F00XHN2
Mix Chemical: Not reported
Percentage: Not reported
Facility Id: FATR201292220F00SHF6
Mixture Cas: Not reported
Weight/Volume: Not reported
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Notes: Not reported
Validation: Not reported

TE3128 **TRAVIS COUNTY FLEET MAINT 5** **TX LPST** **S110413593**
WNW **1000 N LAMAR BLVD** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78701** **TX TIER 2**
0.241 mi.
1271 ft. **Site 1 of 6 in cluster TE**

Actual:
479 ft.

Focus Map:
11

LPST:

Name:	TRAVIS COUNTY FLEET MAINT 5
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0044492
LPST Id:	114336
Facility Location:	1000 N LAMAR BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	12/22/1998
Entered Date:	01/09/1999
Reported Date:	12/22/1998
Closure Date:	04/24/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1
Coordinators RPR:	RWD
Responsible Party Name:	Not reported
Responsible Party Contact:	DAVE FOWLER
Responsible Party Address:	PO BOX 1748
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	512/473-9383
Reported Date:	12/22/1998
Case Start Date:	04/24/2001
Reference Number:	RN102476082
Project Manager:	RWD

HIST UST AUSTIN:

Name:	HARVEY YOUNG
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0379
HID UST:	379
Inspection:	Not reported
Due:	06/01/2012

TIER 2:

Facility Id:	FATR200955AT0C01XL6Z
Facility Name:	TRAVIS COUNTY FLEET SEVICES 1000 N. LAMAR
Reporting Year:	2009
Facility Country:	USA
Facility Department:	Travis County TNR
Facility Date Modified:	5/24/2010
Date Tier 2 Signed:	2/23/2010
Mailing Address:	1000 North Lamar Blvd
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True

TRAVIS COUNTY FLEET MAINT 5 (Continued) **S110413593**

State Fees Total:	50
Number Of Employess On Site:	1
Site Map:	T
Fire District:	Austin
Submitted By:	Charles Williams, Conservation Coordinator
Latitude:	30.275278
Longitude:	97.75246
Lat/Long Location Desc:	ST - Storage Tank
Lat/Long Method:	A6 - Address Matching (Digitized)
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	9199
Id Type:	SIC
Description:	County Government
Last Modified:	6/4/2007
Id:	92119
Id Type:	NAICS
Description:	All Other General Government
Last Modified:	2/9/2009

Contact:

Contact Email:	Not reported
Contact Mail Address:	411 W 13th sreet
Contact City/State/Zip:	Austin, TX 78701
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Type 2:	Owner / Operator
Contact Name:	Mike Joyce
Title:	TNR Fleet Manager
Modification Date:	3/5/2010

Chemical Inventory:

Facility Id:	FATR200955AT0C01XL6Z
Chemical Name:	GASOLINES: AUTOMOTIVE (<4.23G LEAD/GAL)
Chemical Inv Record Id:	CVTR200955ATRP021GV0
CAS Number:	8006-61-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	Not reported
Average Daily Amount:	10,000 - 99,999 pounds
Max Daily Amount:	10,000 - 99,999 pounds
Max Amount In Largest Container:	63080
Chronic Health Risks:	T
EHS Substance:	Not reported
Last Modified:	3/5/2010
Days On Site:	365
Fire Hazard:	T
Gas:	Not reported

TRAVIS COUNTY FLEET MAINT 5 (Continued) **S110413593**

Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2009
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR200955AV2U001JMA
Chemical Inventory Record Id:	CVTR200955ATRP021GV0
Amt Of Sub Stored Or Transported:	10000
Amount Units:	gallons
Type Of Storage:	Below ground tank
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	Fuel Pump outside building
Last Modified:	3/5/2010

Notes: Not reported

Validation: This facility passed all validation checks.

TE3129 **FORMER TRAVIS CTY FLEET MAINT** **TX RDR** **S127533308**
WNW **1000 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.241 mi.
1271 ft. **Site 2 of 6 in cluster TE**

Actual:
479 ft.

Focus Map:
11

RDR:

RDR ID:	23381
Facility ID:	44492
RN:	Not reported
CN:	Not reported
Name:	FORMER TRAVIS CTY FLEET MAINT
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/7/2016
Due Date:	3/7/2016
Tank Owner:	JOURNEYMAN AUSTIN HOLDINGS
Contact Person:	PAT RIORDAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/4/2016
Project Manager:	Morgan Suhm
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported

FORMER TRAVIS CTY FLEET MAINT (Continued) **S127533308**

Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TE3130 **SATELLITE 5 FLEET MAINTENANCE** **TX UST** **U003421932**
WNW **1000 N LAMAR BLVD** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX Financial Assurance**
0.241 mi.
1271 ft. **Site 3 of 6 in cluster TE**

Actual:
479 ft.

Focus Map:
11

UST:

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787035552
AI Number:	44492
Facility Type:	FLEET REFUELING
Facility Begin Date:	01/22/1987
Facility Status:	INACTIVE
Additional ID:	859317852002156
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	MARK SOBECK,FLEET MGR
Contact Organization Name:	SATELLITE 5 FLEET MAINTENANCE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5128547766
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/23/2015
Signature Name/Title On Earliest Reg Form:	KEITH COBURN,
Application Received Date On Earliest Reg Form:	03/31/2015
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Owner:

Owner CN:	CN604671180
Owner Last Name:	JOURNEYMAN AUSTIN HOLDINGS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	699288922014258
Additional ID:	859317852002156
AI Number:	44492
Owner Effective Begin Date:	10/28/2015
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	72698
Cert ID:	251570
AI Number:	44492
Self Certification Date:	03/23/2015
Signature Name/Title:	KEITH COBURN ENV PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72698
Cert ID:	235818
AI Number:	44492
Self Certification Date:	05/02/2014
Signature Name/Title:	KEITH COBURN ENV PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	72698
Cert ID:	94451
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Certification Date:	02/25/2013
Signature Name/Title:	KEITH COBURN ENV PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94450
AI Number:	44492
Self Certification Date:	03/01/2012
Signature Name/Title:	KEITH COBURN ENVIRO PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94449
AI Number:	44492
Self Certification Date:	03/09/2011
Signature Name/Title:	KEITH COBURN ENV PORJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94448
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Certification Date:	02/23/2010
Signature Name/Title:	KEITH COBURN ENV PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94447
AI Number:	44492
Self Certification Date:	02/25/2009
Signature Name/Title:	KEITH COBURN ENV PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94170
AI Number:	44492
Self Certification Date:	04/10/2008
Signature Name/Title:	KEITH COBURN ENG PROJ MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94169
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Certification Date:	03/06/2007
Signature Name/Title:	KEITH COBURN ENV PROJECT MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94168
AI Number:	44492
Self Certification Date:	01/27/2006
Signature Name/Title:	KEITH COBURN ENV PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94167
AI Number:	44492
Self Certification Date:	02/28/2005
Signature Name/Title:	KEITH COBURN
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	72698
Cert ID:	94166
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Certification Date:	03/09/2004
Signature Name/Title:	KEITH COBURN ENVIRO PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	72698
Cert ID:	94165
AI Number:	44492
Self Certification Date:	03/25/2003
Signature Name/Title:	KEITH COBURN
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	72698
Cert ID:	94164
AI Number:	44492
Self Certification Date:	04/01/2002
Signature Name/Title:	DAVID L FOWLER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	72698
Cert ID:	94163
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Certification Date:	01/21/2001
Signature Name/Title:	DAVID L FOWLER ENV PROJECT MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	01/22/1987
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	116612
Facility ID:	72698
Ai Number:	44492
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/07/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	104896
UST ID:	116612
AI Number:	44492
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17497
Cert ID:	301986
UST Comprt ID:	873297
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	284332
UST Comprt ID:	820565
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119529
UST Comprt ID:	363229
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	352701
UST Comprt ID:	1025377
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	369452
UST Comprt ID:	1075787
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119530
UST Comprt ID:	363227
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Self Cert ID:	17497
Cert ID:	119531
UST Comprt ID:	363226
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119532
UST Comprt ID:	363225
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119533
UST Comprt ID:	363224
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119534
UST Comprt ID:	363223
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119535
UST Comprt ID:	363222
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119536
UST Comprt ID:	363221
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119537
UST Comprt ID:	363220
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Cert ID:	119538
UST Comprt ID:	363219
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119539
UST Comprt ID:	363218
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119540
UST Comprt ID:	363217
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	319137
UST Comprt ID:	924346
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	336114
UST Comprt ID:	975153
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	235738
UST Comprt ID:	676724
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	268708
UST Comprt ID:	774097
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	250693

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

UST Comprt ID:	720732
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119528
UST Comprt ID:	363228
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Install Date:	01/01/1972
Tank Registration Date:	01/22/1987
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	116613
Facility ID:	72698
Ai Number:	44492
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/20/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1A
Tank Capacity:	6000
UST Comprt ID:	104897
UST ID:	116613
AI Number:	44492
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17497
Cert ID:	301986
UST Comprt ID:	873297
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	284332
UST Comprt ID:	820565
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119529
UST Comprt ID:	363229
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	352701
UST Comprt ID:	1025377
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	369452
UST Comprt ID:	1075787
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119530
UST Comprt ID:	363227
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119531

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

UST Comprt ID:	363226
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119532
UST Comprt ID:	363225
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119533
UST Comprt ID:	363224
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119534
UST Comprt ID:	363223
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119535
UST Comprt ID:	363222
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119536
UST Comprt ID:	363221
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119537
UST Comprt ID:	363220
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119538
UST Comprt ID:	363219

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119539
UST Comprt ID:	363218
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119540
UST Comprt ID:	363217
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	319137
UST Comprt ID:	924346
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	336114
UST Comprt ID:	975153
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	235738
UST Comprt ID:	676724
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	268708
UST Comprt ID:	774097
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	250693
UST Comprt ID:	720732
UST ID:	115009

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119528
UST Comprt ID:	363228
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Install Date:	03/01/1999
Tank Registration Date:	09/30/1999
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	192191
Facility ID:	72698
Ai Number:	44492
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/03/2015
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	07/15/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	104898
UST ID:	192191
AI Number:	44492
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/01/1999

More Self Certification:

Self Cert ID:	17497
Cert ID:	301986
UST Comprt ID:	873297
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	284332
UST Comprt ID:	820565
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119529
UST Comprt ID:	363229
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	352701
UST Comprt ID:	1025377
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	369452
UST Comprt ID:	1075787
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119530
UST Comprt ID:	363227
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119531
UST Comprt ID:	363226
UST ID:	115009

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119532
UST Comprt ID:	363225
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119533
UST Comprt ID:	363224
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119534
UST Comprt ID:	363223
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119535
UST Comprt ID:	363222
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119536
UST Comprt ID:	363221
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119537
UST Comprt ID:	363220
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119538
UST Comprt ID:	363219
UST ID:	115009
AI Number:	44492

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119539
UST Comprt ID:	363218
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119540
UST Comprt ID:	363217
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	319137
UST Comprt ID:	924346
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	336114
UST Comprt ID:	975153
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	235738
UST Comprt ID:	676724
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	268708
UST Comprt ID:	774097
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A
Self Cert ID:	17497
Cert ID:	250693
UST Comprt ID:	720732
UST ID:	115009
AI Number:	44492
Tank ID:	4

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Compartment ID:	A
Self Cert ID:	17497
Cert ID:	119528
UST Comprt ID:	363228
UST ID:	115009
AI Number:	44492
Tank ID:	4
Compartment ID:	A

Construction Notification:

NOC ID:	28477
Facility ID:	72698
AI Number:	44492
Application Received Date:	11/10/2015
Scheduled Construction Date:	11/09/2015
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	TRAVIS COUNTY;TRAVIS COUNTY
Owner CN At Time Of Construction:	CN600338388,CN600338388
Owner AR At Time Of Construction:	7684A,7684U
General Desc Of Prop Construct:	REMOVE EXISTING 10,000 GALLON UST

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	29959
UST ID:	192191
NOC ID:	Not reported
AI Number:	44492
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000280
Company Name:	NESCO
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	67001
UST ID:	Not reported
NOC ID:	28477
AI Number:	44492
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	RICHARD ROLLINS
Mailing Address (Delivery):	1113 REGAL ROW STE A
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM
Cont/Cons/Installer ID:	45123
UST ID:	192191
NOC ID:	Not reported
AI Number:	44492
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001883
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Facility Billing Contacts:

Contact Organization Name:	JOURNEYMAN AUSTIN HOLDINGS INC
Contact Mailing Address (Delivery):	7701 N LAMAR BLVD STE 100
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 1012
Phone Number/Ext:	512 3742920/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	72698
Additional ID:	859317852002156
Princ ID:	699288922014258
AI Number:	44492
Facility Name:	SATELLITE 5 FLEET MAINTENANCE
AR Number:	77426
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	PATRICK RIORDAN/PROJECT MGR

HIST UST AUSTIN:

Name:	TRAVIS COUNTY TNR FLEET MAINTENANCE #5
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	3174
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	142635
AI:	44492
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2015
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name: SATELLITE 5 FLEET MAINTENANCE

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	126973
AI:	44492
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2014
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/31/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	7163
AI:	44492
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2012
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	55541
AI:	44492
Mechanism Type Other:	LOCAL GOV. GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/2011
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	12/31/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	55542
AI:	44492
Mechanism Type Other:	LOCAL GOV. GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/14/2009
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	12/14/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	55544
AI:	44492
Mechanism Type Other:	LOCAL GOV. GUARANTEE
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/08/2009
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Coverage Amount:	0
Coverage Expiration Date:	04/08/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	55543
AI:	44492
Mechanism Type Other:	LOCAL GOV. GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/08/2009
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	04/08/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2
Facility ID:	72698
Finass ID:	55545
AI:	44492
Mechanism Type Other:	LOCAL GOV. GUARANTEE
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/13/2008
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 8549383
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	05/13/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SATELLITE 5 FLEET MAINTENANCE
Address:	1000 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Region:	2

SATELLITE 5 FLEET MAINTENANCE (Continued) **U003421932**

Facility ID:	72698
Finass ID:	55546
AI:	44492
Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/31/2015
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

TF3131 **TEXAS DEPT OF PUBLIC SAFETY** **TX UST** **U004144067**
ESE **5900 GUADALUPE ST** **TX HIST UST** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.241 mi.
1272 ft. **Site 1 of 4 in cluster TF**

Actual:
664 ft.

Focus Map:
9

UST:

Name:	TEXAS DEPT OF PUBLIC SAFETY
Address:	5900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 787524418
AI Number:	10806
Facility Type:	UNKNOWN
Facility Begin Date:	07/23/1986
Facility Status:	INACTIVE
Additional ID:	288652822002205
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	RICHARD HALL,
Contact Organization Name:	TEXAS DEPT OF PUBLIC SAFETY
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124652167
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	G DUNLAP,SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

Enforcement Action:	Not reported
Facility Not Inspectable:	No

Operator:

Princ ID:	189570062001351
Additional ID:	288652822002205
Ai Number:	10806
Operator CN:	CN600610976
Operator Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Operator Effective Begin Date:	02/28/2018
Operator Type:	SG
Operator Role:	OWNOPRCON
Contact Name:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	JERSEY VILLAGE TX 77065-4523
Contact Phone Country Code:	1
Contact Phone Area Code:	281
Contact Phone Number:	5171509
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600610976
Owner Last Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	12230 WEST RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	JERSEY VILLAGE
Contact Mailing State:	TX
Contact Mailing Zip:	77065
Contact Mailing Zip5:	4523
Contact Phone Number/Ext:	1 281 5171509/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	189570062001351
Additional ID:	288652822002205
AI Number:	10806
Owner Effective Begin Date:	02/28/2018
State Tax ID:	Not reported
Contact Role:	OWNOPRCON
Contact Name/Title:	/
Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY

Tank:

Install Date:	01/01/1959
Tank Registration Date:	05/08/1986

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28394
Facility ID:	50125
Ai Number:	10806
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/12/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	37128
UST ID:	28394
AI Number:	10806
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	28393
Facility ID:	50125
Ai Number:	10806

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/12/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	37127
UST ID:	28393

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

AI Number:	10806
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS DEPARTMENT OF PUBLIC SAFETY
Contact Mailing Address (Delivery):	PO BOX 4087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78765 4087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	50125
Additional ID:	288652822002205
Princ ID:	189570062001351
AI Number:	10806
Facility Name:	TEXAS DEPT OF PUBLIC SAFETY
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PHILIP JOHNSON/

TEXAS DEPT OF PUBLIC SAFETY (Continued) **U004144067**

HIST UST AUSTIN:

Name:	DPS
Address:	5900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0540
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TF3132 **AUSTIN ISD** **RCRA NonGen / NLR** **1000412213**
ESE **5900 GUADALUPE** **FINDS** **TXD982549354**
1/8-1/4 **AUSTIN, TX 78752** **ECHO**
0.241 mi.
1272 ft. **Site 2 of 4 in cluster TF**

Actual:
664 ft.

Focus Map:
9

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Austin Isd
Handler Address:	GUADALUPE
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD982549354
Contact Name:	ROBERT GILES
Contact Address:	GUADALUPE
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-452-9415
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	GUADALUPE
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Austin Isd
Owner Type:	Municipal
Operator Name:	Austin Isd
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

AUSTIN ISD (Continued) **1000412213**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN ISD	
Legal Status:	Municipal
Date Became Current:	20010823
Date Ended Current:	Not reported
Owner/Operator Address:	5900 GUADALUPE
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-452-9415
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: AUSTIN ISD	
Legal Status:	District
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

AUSTIN ISD (Continued) **1000412213**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: AUSTIN ISD
Legal Status: Municipal
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 5900 GUADALUPE
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-452-9415
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19880328
Handler Name: AUSTIN ISD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: AUSTIN ISD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005106474

AUSTIN ISD (Continued) **1000412213**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412213
Registry ID:	110005106474
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005106474
Name:	AUSTIN ISD
Address:	5900 GUADALUPE
City,State,Zip:	AUSTIN, TX 78752

TF3133 **AUSTIN ISD** **TX Ind. Haz Waste** **S102754417**
ESE **5900 GUADALUPE ST** **N/A**
1/8-1/4 **AUSTIN, TX 78752**
0.241 mi.
1272 ft. **Site 3 of 4 in cluster TF**

Actual:
664 ft.

Focus Map:
9

Ind. Haz Waste:

Name:	AUSTIN ISD
Address:	5900 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	72711
Registration Initial Notification Date:	03/18/1988
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD982549354
Primary NAICS Code:	Not reported
Status Change Date:	19880318
Land Type:	Not reported
Description of Facility Site Location:	5900 Guadalupe, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	ROBERT GILES
Contact Telephone Number:	512-4529415
Mailing Address:	5900 GUADALUPE
Mailing Address2:	Not reported

AUSTIN ISD (Continued) **S102754417**

Mailing City,State,Zip:	AUSTIN, TX 78752
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27150
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021112
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	5900 GUADALUPE
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4529415
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Owner Mailing Address:	5900 GUADALUPE
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4529415
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	5900 GUADALUPE
Contact Address 2:	Not reported
Contact Address 3:	Not reported

AUSTIN ISD (Continued) **S102754417**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4529415
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	5900 GUADALUPE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4529415
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	ROBERT GILES
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	5900 GUADALUPE
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4529415
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000304019
Principal Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Attention Name:	Not reported
Attention Suffix:	HWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000304019
Principal Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Attention Name:	Not reported
Attention Suffix:	NWF
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000304019

AUSTIN ISD (Continued) **S102754417**

Principal Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Attention Name:	Not reported
Attention Suffix:	NWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1111 W 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000304019
Principal Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Attention Name:	Not reported
Attention Suffix:	HWG

TG3134 **RECREATIONAL EQUIPMENT** **TX UST** **U001280016**
WNW **1112 N LAMAR BLVD** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.242 mi.
1277 ft. **Site 1 of 3 in cluster TG**

Actual:
491 ft.

Focus Map:
11

UST:

Name:	RECREATIONAL EQUIPMENT
Address:	1112 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787034989
AI Number:	48979
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/28/1989
Facility Status:	INACTIVE
Additional ID:	419742782002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	,
Contact Organization Name:	RECREATIONAL EQUIPMENT
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124742393
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/18/1989
Signature Name/Title On Earliest Reg Form:	SAME,SAME
Application Received Date On Earliest Reg Form:	08/22/1989
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

RECREATIONAL EQUIPMENT (Continued) **U001280016**

Owner CN:	CN600785109
Owner Last Name:	B E R R PROPERTIES LTD
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	PA
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	409742772002053
Additional ID:	419742782002053
AI Number:	48979
Owner Effective Begin Date:	08/28/1989
State Tax ID:	32036508656
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	08/22/1989
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	127319
Facility ID:	87568
Ai Number:	48979
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/01/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

RECREATIONAL EQUIPMENT (Continued) **U001280016**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	147055
UST ID:	127319
AI Number:	48979
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N

RECREATIONAL EQUIPMENT (Continued) **U001280016**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	18834
Cert ID:	100468
UST Comprt ID:	297985
UST ID:	96424
AI Number:	48979
Tank ID:	1
Compartment ID:	A
Self Cert ID:	18834
Cert ID:	100467
UST Comprt ID:	297984
UST ID:	96424
AI Number:	48979
Tank ID:	1
Compartment ID:	A
Self Cert ID:	18834
Cert ID:	100701
UST Comprt ID:	297986
UST ID:	96424
AI Number:	48979
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	BERR PROPERTIES LTD
Contact Mailing Address (Delivery):	PO BOX 9190
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78766 9190
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	87568
Additional ID:	419742782002053
Princ ID:	409742772002053
AI Number:	48979

RECREATIONAL EQUIPMENT (Continued) **U001280016**

Facility Name:	RECREATIONAL EQUIPMENT
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	LAURA VALLE/

ASBESTOS:

Name:	CASTLE HILL CYCLES
Address:	1112 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/26/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.3
Mileage:	7.6
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

RECREATIONAL EQUIPMENT (Continued) **U001280016**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CASTLE HILL CYCLES
Address:	1112 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	05/23/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/02/2014
Date Routed by Supervisor:	06/02/2014
Date Routed to PSQA:	06/03/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

RECREATIONAL EQUIPMENT (Continued) **U001280016**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TG3135 **SIMMONS MOTOR CO.** **TX HIST UST** **S128729386**
WNW **1112 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.242 mi.
1277 ft. **Site 2 of 3 in cluster TG**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SIMMONS MOTOR CO.
Address:	1112 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0709
HID UST:	709
Inspection:	Not reported
Due:	06/01/2012

TG3136 **REI LEASE PROPERTY** **TX HIST UST** **S128728877**
WNW **1112 N LAMAR BLVD** **N/A**
1/8-1/4 **AUSTIN, TX**
0.242 mi.
1277 ft. **Site 3 of 3 in cluster TG**

Actual:
491 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	REI LEASE PROPERTY
Address:	1112 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0052
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TE3137 **ONION CREEK VOLKSWAGEN** **TX HIST UST** **1000336359**
WNW **1014 N LAMAR BLVD** **RCRA NonGen / NLR** **TXD980878870**
1/8-1/4 **AUSTIN, TX 78703** **FINDS**
0.242 mi. **ECHO**
1278 ft. **Site 4 of 6 in cluster TE** **TX ASBESTOS**
TX Ind. Haz Waste
TX CENTRAL REGISTRY

Actual:
480 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	PONTIAC COMPANY
Address:	1014 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0471
HID UST:	471
Inspection:	Not reported
Due:	06/01/2012

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Onion Creek Volkswagen
Handler Address:	N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78703
EPA ID:	TXD980878870
Contact Name:	JIM OLMSTREAD
Contact Address:	PO BOX 2147
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Telephone:	512-476-9181
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 2147
Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Name:	Onion Creek Volkswagen

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Owner Type:	Other
Operator Name:	Onion Creek Volkswagen
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LOWRANCE GEORGE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ONION CREEK VOLKSWAGEN
Legal Status: Other
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2147
Owner/Operator City,State,Zip: AUSTIN, TX 78768
Owner/Operator Telephone: 512-476-9181
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ONION CREEK VOLKSWAGEN
Legal Status: Other
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2147
Owner/Operator City,State,Zip: AUSTIN, TX 78768
Owner/Operator Telephone: 512-476-9181
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19840923
Handler Name: ONION CREEK VOLKSWAGEN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: ONION CREEK VOLKSWAGEN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009499532

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000336359
Registry ID:	110009499532
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009499532
Name:	ONION CREEK VOLKSWAGEN
Address:	1014 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703

ASBESTOS:

Name:	WHOLE EARTH PROVISION CO
Address:	1014 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	05/23/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	06/02/2014

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Date Routed by Supervisor:	06/02/2014
Date Routed to PSQA:	06/03/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WHOLE EARTH PROVISION
Address:	1014 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Date of inspection:	04/25/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	ONION CREEK VOLKSWAGEN
Address:	1014 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66195
Registration Initial Notification Date:	09/26/1984
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD980878870
Primary NAICS Code:	Not reported
Status Change Date:	19840926
Land Type:	OTHER
Description of Facility Site Location:	1014 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	ONION CREEK VOLKSWAGEN
Contact Name:	JIM OLMSTREAD
Contact Telephone Number:	512-4769181
Mailing Address:	PO BOX 2147
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787682147
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21491
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030912
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Ind. Haz Waste:

Operator Name:	ONION CREEK VOLKSWAGEN
Operator Address:	PO BOX 2147
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78768
Operator Country:	UNITED STA
Operator Telephone:	1-512-4769181
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Other/Misc
Operator Tax ID:	17423204084
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	ONION CREEK VOLKSWAGEN
Owner Mailing Address:	PO BOX 2147
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78768
Owner Country:	UNITED STA
Owner Telephone:	1-512-4769181
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Other/Misc
Owner Tax ID:	17423204084
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 2147
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4769181
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 2147
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4769181
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	JIM OLMSTREAD
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 2147
Contact Address 2:	Not reported

ONION CREEK VOLKSWAGEN (Continued) **1000336359**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78768
Contact Phone:	1-512-4769181
Contact Fax:	Not reported
Contact Email:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100569045
Name:	ONION CREEK VOLKSWAGEN
Address:	1014 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4972
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600279657
Customer Name:	ONION CREEK VOLKSWAGEN
Customer Legal Name:	Onion Creek Volkswagen, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1014 N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100569045
Name:	ONION CREEK VOLKSWAGEN
Address:	1014 N LAMAR BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4972
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600279657
Customer Name:	ONION CREEK VOLKSWAGEN
Customer Legal Name:	Onion Creek Volkswagen, Inc.
Customer Ownership Type:	OTHER
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	1014 N Lamar Blvd, Austin, TX

TE3138 **TIP TOP CLEANERS** **TX DRYCLEANERS** **S108419608**
WNW **1014 N LAMAR BLVD STE F** **TX CENTRAL REGISTRY** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.242 mi.
1278 ft. **Site 5 of 6 in cluster TE**

Actual:
480 ft.

Focus Map:
11

DRYCLEANERS:

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638

TIP TOP CLEANERS (Continued) **S108419608**

DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 4
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2018
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	100
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2020
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE

TIP TOP CLEANERS (Continued) **S108419608**

Fiscal Year:	FY2019
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2023
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2021
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN

TIP TOP CLEANERS (Continued) **S108419608**

CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 4
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	100
Part Stat:	YES
Gross Receipts:	$150,000 OR LESS

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN603982570
DCR Number:	DCR10237
AR Number:	24006422
Principal Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	REIDS CLEANERS 4
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2017
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	100
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN603982570
DCR Number:	DCR10237
AR Number:	24006422
Principal Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	SALVALIANI@GMAIL.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION

TIP TOP CLEANERS (Continued) **S108419608**

Site Status:	ACTIVE
Fiscal Year:	FY2015
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN603982570
DCR Number:	Not reported
AR Number:	24006422
Principal Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN603982570
DCR Number:	Not reported
AR Number:	24006422
Principal Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2013
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	180
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766

TIP TOP CLEANERS (Continued) **S108419608**

Region:	REGION 11 - AUSTIN
CN Number:	CN600304638
DCR Number:	DCR10237
AR Number:	24000073
Principal Name:	REIDS LAUNDRY & DRY CLEANERS INC
Bill Addr1:	11907 W HIGHWAY 290
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78737 2841
EMail:	Not reported
Phone Number:	512 2883039
Site Name:	Not reported
Site Type:	DROP STATION REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2022
Solvent:	Not reported
Gallons:	Not reported
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2004
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	0
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS

TIP TOP CLEANERS (Continued) **S108419608**

Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2005
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $200,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2006
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2007
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703

TIP TOP CLEANERS (Continued) **S108419608**

RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2008
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2009
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984

TIP TOP CLEANERS (Continued) **S108419608**

Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2010
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	300
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2011
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	11
CN Number:	CN600306575
DCR Number:	Not reported
AR Number:	24000670
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	DBRUSTKERN@BFA-LAW.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2012
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	200
Part Stat:	YES
Gross Receipts:	> $150,000

Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F

TIP TOP CLEANERS (Continued) **S108419608**

City,State,Zip:	AUSTIN, TX 78703
RN Number:	RN100596766
Region:	REGION 11 - AUSTIN
CN Number:	CN603982570
DCR Number:	DCR10237
AR Number:	24006422
Principal Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Bill Addr1:	1014 N LAMAR BLVD STE F
Bill Addr2:	Not reported
Bill City/State/Zip:	AUSTIN, TX 78703 4964
EMail:	SALVALIANI@GMAIL.COM
Phone Number:	512 4781984
Site Name:	TIP TOP CLEANERS
Site Type:	FACILITY REGISTRATION
Site Status:	ACTIVE
Fiscal Year:	FY2016
Solvent:	PERCHLOROETHYLENE (TETRACHLOROETHYLENE)
Gallons:	150
Part Stat:	YES
Gross Receipts:	> $150,000

CENTRAL REGISTRY:

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600306575
Customer Name:	TIP TOP CLEANERS LAUNDERERS INC
Customer Legal Name:	Tip Top Cleaners Launderers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600306575
Customer Name:	TIP TOP CLEANERS LAUNDERERS INC
Customer Legal Name:	Tip Top Cleaners Launderers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

TIP TOP CLEANERS (Continued) **S108419608**

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600306575
Customer Name:	TIP TOP CLEANERS LAUNDERERS INC
Customer Legal Name:	Tip Top Cleaners Launderers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600306575
Customer Name:	TIP TOP CLEANERS LAUNDERERS INC
Customer Legal Name:	Tip Top Cleaners Launderers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600306575
Customer Name:	TIP TOP CLEANERS LAUNDERERS INC
Customer Legal Name:	Tip Top Cleaners Launderers, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/2001
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F

TIP TOP CLEANERS (Continued) **S108419608**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603982570
Customer Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Customer Legal Name:	Quadriga Distressed Opportunities Fund Iv, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2011
Affiliation End Date:	11/25/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603982570
Customer Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Customer Legal Name:	Quadriga Distressed Opportunities Fund Iv, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2011
Affiliation End Date:	11/25/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603982570
Customer Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Customer Legal Name:	Quadriga Distressed Opportunities Fund Iv, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2011
Affiliation End Date:	11/25/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE

TIP TOP CLEANERS (Continued) **S108419608**

Status Date:	##########
Customer Number:	CN603982570
Customer Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Customer Legal Name:	Quadriga Distressed Opportunities Fund Iv, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2011
Affiliation End Date:	11/25/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603982570
Customer Name:	QUADRIGA DISTRESSED OPPORTUNITIES FUND IV LLC
Customer Legal Name:	Quadriga Distressed Opportunities Fund Iv, LLC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/1/2011
Affiliation End Date:	11/25/2016
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Regulated Entity Number:	RN100596766
Name:	TIP TOP CLEANERS
Address:	1014 N LAMAR BLVD STE F
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78703-4964
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600304638
Customer Name:	REIDS LAUNDRY & DRY CLEANERS INC
Customer Legal Name:	Reid's Laundry & Dry Cleaners, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	11/26/2016
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	812320
Primary NAICS Industry Type Description:	Drycleaning and Laundry Services (except Coin-Operated)
Physical Location Description:	1014 F N Lamar Blvd, Austin, TX

Click this hyperlink while viewing on your computer to access
11 additional TX CENTRAL REG: record(s) in the EDR Site Report.

TE3139 **TIP TOP CLEANERS LAUNDERERS** **TX Ind. Haz Waste** **S104854407**
WNW **1014 N LAMAR BLVD STE F** **N/A**
1/8-1/4 **AUSTIN, TX 78703**
0.242 mi.
1278 ft. **Site 6 of 6 in cluster TE**

Actual:
480 ft.

Focus Map:
11

Ind. Haz Waste:

Name:	TIP TOP CLEANERS LAUNDERERS
Address:	1014 N LAMAR BLVD STE F
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	70577
Registration Initial Notification Date:	09/01/1986
Registration Last Amendment Date:	10/02/2006
EPA Identification:	TXD981606411
Primary NAICS Code:	Not reported
Status Change Date:	19860901
Land Type:	PRIVATE
Description of Facility Site Location:	1014 F N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	TIP TOP CLEANERS LAUNDERERS INC
Contact Name:	SAL VALIANI
Contact Telephone Number:	512-4478329
Mailing Address:	1014 N LAMAR BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787034972
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	25390
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20061002
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

TIP TOP CLEANERS LAUNDERERS (Continued) **S104854407**

Ind. Haz Waste:

Operator Name:	TIP TOP CLEANERS LAUNDERERS INC
Operator Address:	1014 N LAMAR BLVD STE F
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78703
Operator Country:	UNITED STA
Operator Telephone:	1-512-4781984
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17600427920
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TIP TOP CLEANERS LAUNDERERS INC
Owner Mailing Address:	1014 N LAMAR BLVD STE F
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Country:	UNITED STA
Owner Telephone:	1-512-4781984
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17600427920
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1014 N LAMAR BLVD STE F
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4781984
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1014 N LAMAR BLVD STE F
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4781984
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Name:	SAL VALIANI
Contact Title:	Not reported
Contact Role:	PRICONT
Contact Address:	1014 N LAMAR BLVD
Contact Address 2:	Not reported

TIP TOP CLEANERS LAUNDERERS (Continued) **S104854407**

Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4478329
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	70357
Texas Waste Code:	Not reported
Texas Waste Code 2:	3601202H
Waste Code Status:	INACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	70358
Texas Waste Code:	Not reported
Texas Waste Code 2:	3602407H
Waste Code Status:	INACTIVE
Waste Form:	407
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	Not reported
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	W409
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported

TIP TOP CLEANERS LAUNDERERS (Continued) **S104854407**

Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1014N LAMAR F
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000303605
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1014N LAMAR F
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000303605
Principal Name:	TIP TOP CLEANERS LAUNDERERS INC
Attention Name:	Not reported
Attention Suffix:	NWG

SW3140 **A D BURRATTI** **TX HIST UST** **S111678534**
East **1007 E 6TH ST** **N/A**
1/8-1/4 **AUSTIN, TX**
0.243 mi.
1282 ft. **Site 3 of 4 in cluster SW**

Actual:
495 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	A D BURRATTI
Address:	1007 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0131
HID UST:	131
Inspection:	02/20/2009
Due:	02/20/2012

TH3141 **TCI COATINGS INC** **PFAS ECHO** **1027426472**
ESE **N/A**
1/8-1/4 **AUSTIN, TX**
0.243 mi.
1285 ft. **Site 1 of 5 in cluster TH**

Actual:
669 ft.

Focus Map:
18

PFAS ECHO:

Name:	TCI COATINGS INC
Address:	Not reported
City,State,Zip:	AUSTIN, TX
Latitude:	30.218614
Longitude:	-97.761958
Count:	1
County:	TRAVIS
Status:	Inactive
Region:	06
Industry:	Paints and Coatings
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110002135136

TCI COATINGS INC (Continued) **1027426472**

Facility Percent Minority:	61.145
Facility Derived Tribes:	-
Facility Population:	5071.62
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	48453
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	12090205
Facility Derived WBD:	120902050408
Facility Derived CD113:	35
Facility Derived CB2010:	484530024031013
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	TXD030927057
RCRA Permit Types:	Other
RCRA NAICS:	32551
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	78764TCHNC312IN
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-

TCI COATINGS INC (Continued) **1027426472**

EJSCREEN Flag US: N
EJSCREEN Report: https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-97.761958,%22y%22:30.218614,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

TH3142 **STONE INDUSTRIAL SOLVENTS** **RCRA NonGen / NLR** **1000311593**
ESE **301 INDUSTRIAL BLVD** **FINDS** **TXD982284549**
1/8-1/4 **AUSTIN, TX 78745** **ECHO**
0.244 mi.
1286 ft. **Site 2 of 5 in cluster TH**

Actual:
669 ft.

Focus Map:
18

RCRA Listings:

Date Form Received by Agency:	20010928
Handler Name:	Stone Industrial Solvents
Handler Address:	INDUSTRIAL BLVD
Handler City,State,Zip:	AUSTIN, TX 78745
EPA ID:	TXD982284549
Contact Name:	DEAN MCCORMICK
Contact Address:	PO BOX 739
Contact City,State,Zip:	GEORGETOWN, TX 78627
Contact Telephone:	512-441-0893
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	PO BOX 739
Mailing City,State,Zip:	GEORGETOWN, TX 78627
Owner Name:	Stonemax
Owner Type:	Private
Operator Name:	Stonemax
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

STONE INDUSTRIAL SOLVENTS (Continued) **1000311593**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or

STONE INDUSTRIAL SOLVENTS (Continued) **1000311593**

More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U210
Waste Description: Ethene, Tetrachloro- (Or) Tetrachloroethylene

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STONEMAX	
Legal Status:	Private
Date Became Current:	20010928
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 739
Owner/Operator City,State,Zip:	GEORGETOWN, TX 78627
Owner/Operator Telephone:	512-441-0893
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: STONEMAX	
Legal Status:	Private
Date Became Current:	20010928
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 739

STONE INDUSTRIAL SOLVENTS (Continued) **1000311593**

Owner/Operator City,State,Zip:	GEORGETOWN, TX 78627
Owner/Operator Telephone:	512-441-0893
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MAX STONE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19871029
Handler Name: STONE INDL SOLVENTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20010928
Handler Name: STONE INDUSTRIAL SOLVENTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

STONE INDUSTRIAL SOLVENTS (Continued) **1000311593**

FINDS:
Registry ID: 110005101326

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000311593
Registry ID:	110005101326
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005101326
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745

TH3143 **GULF CLEANING AND LAUNDRY SUPPLY** **TX AST** **A100201982**
ESE **301 INDUSTRIAL BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78745**
0.244 mi.
1286 ft. **Site 3 of 5 in cluster TH**

Actual:
669 ft.

Focus Map:
18

AST:

Name:	GULF CLEANING AND LAUNDRY SUPPLY
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 787451206
Facility ID:	114588
Additional ID:	434727002002256
AI Number:	74952
Facility Type:	Not reported
Facility Begin Date:	01/01/1974
Facility Status:	INACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	0
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78745
Contact Name/Title:	HOPPY WILLIAMS/
Contact Organization Name:	GULF CLEANING AND LAUNDRY SUPPLY

GULF CLEANING AND LAUNDRY SUPPLY (Continued) **A100201982**

Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124410893
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	02/15/2002
Signature First Name on Earliest Reg Form:	H B
Application Received Date on Earliest Reg Form:	02/19/2002
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	WILLIAMS
Signature Title on Earliest Reg Form:	VP OPERATIONS
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	114588
Tank ID:	1
AST ID:	199396
AI Number:	74952
Install Date:	09/01/2001
Tank Registration Date:	02/25/2002
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/31/2005
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	8800
Substance:	PETROLEUM DISTILLATES
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	114588
Tank ID:	2
AST ID:	199397
AI Number:	74952
Install Date:	09/01/2001
Tank Registration Date:	02/25/2002
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/31/2005
Tank Reg Status:	FULLY REGULATED

GULF CLEANING AND LAUNDRY SUPPLY (Continued) **A100201982**

Tank Capacity:	6700
Substance:	PETROLEUM DISTILLATES
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	114588
Tank ID:	3
AST ID:	199398
AI Number:	74952
Install Date:	09/01/2001
Tank Registration Date:	02/25/2002
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/31/2005
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2500
Substance:	PETROLEUM DISTILLATES
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	114588
Tank ID:	4
AST ID:	199399
AI Number:	74952
Install Date:	09/01/2001
Tank Registration Date:	02/25/2002
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/31/2005
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2500
Substance:	PETROLEUM DISTILLATES
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y

GULF CLEANING AND LAUNDRY SUPPLY (Continued) **A100201982**

Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

Facility ID:	114588
Tank ID:	5
AST ID:	199400
AI Number:	74952
Install Date:	09/01/2001
Tank Registration Date:	02/25/2002
Mult Comp:	N
Tank Status:	OUT OF USE
Tank Status Date:	05/31/2005
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2500
Substance:	PETROLEUM DISTILLATES
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	Y
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

TH3144 **STONE INDUSTRIAL SOLVENTS** **TX UST** **U002112544**
ESE **301 INDUSTRIAL BLVD** **TX VCP** **N/A**
1/8-1/4 **AUSTIN, TX 78745** **TX HIST UST**
0.244 mi. **TX Ind. Haz Waste**
1286 ft. **Site 4 of 5 in cluster TH** **TX CENTRAL REGISTRY**

Actual:
669 ft.

Focus Map:
18

UST:

Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 787451206
AI Number:	66284
Facility Type:	FLEET REFUELING
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	967000962002155
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	STONE INDUSTRIAL SOLVENTS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124410893
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/16/1994
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRES
Application Received Date On Earliest Reg Form:	12/16/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601264039
Owner Last Name:	STONE INDUSTRIAL SOLVENTS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	959000962002155
Additional ID:	967000962002155
AI Number:	66284
Owner Effective Begin Date:	08/31/1987
State Tax ID:	17424977019
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	12/16/1994
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	173028
Facility ID:	99373

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Ai Number:	66284
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/06/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	165446

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

UST ID:	173028
AI Number:	66284
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25838
Cert ID:	8261
UST Comprt ID:	23359
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838
Cert ID:	8265
UST Comprt ID:	23357
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Cert ID:	8267
UST Comprt ID:	23355
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838
Cert ID:	8262
UST Comprt ID:	23360
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838
Cert ID:	8266
UST Comprt ID:	23356
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838
Cert ID:	8263
UST Comprt ID:	23361
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A
Self Cert ID:	25838
Cert ID:	8264
UST Comprt ID:	23358
UST ID:	6756
AI Number:	66284
Tank ID:	2
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	STONE INDUSTRIAL SOLVENTS
Contact Mailing Address (Delivery):	608 LEANDER RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GEORGETOWN, TX 78626 8408
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	99373
Additional ID:	967000962002155
Princ ID:	959000962002155
AI Number:	66284
Facility Name:	STONE INDUSTRIAL SOLVENTS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Contact Name/Title: DORIS STONE/

VCP TCEQ:

Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745
Region:	REGION 11 - AUSTIN
Facility ID:	1138
VCP Record Date:	02/10/2000
Facility Type:	DRY CLEANER
PCA Number:	33261
Project Manager:	RGOLDSMI
Phase:	COMPLETED
Acres at Site:	111 X 165
REM Program:	VCP
RN Number:	RN100675339
Former Facility Type:	Not reported
Site Address Description:	301 INDUSTRIAL BOULEVARD
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	02/08/2000
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	03/27/2000
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	02/08/2000
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	2000-03-27 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS; PETROLEUM (BTEX)
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	1138; 3214
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	332610
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.32
Longitude:	-97.77

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

HIST UST AUSTIN:

Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0527
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745
Permit Number:	Not reported
Registration Number:	38205
Registration Initial Notification Date:	10/16/1987
Registration Last Amendment Date:	09/28/2001
EPA Identification:	TXD982284549
Primary NAICS Code:	Not reported
Status Change Date:	19871016
Land Type:	PRIVATE
Description of Facility Site Location:	301 Industrial Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	INDUS
Company Name:	STONE, MAX
Contact Name:	DEAN MCCORMICK
Contact Telephone Number:	512-4410893
Mailing Address:	PO BOX 739
Mailing Address2:	Not reported
Mailing City,State,Zip:	GEORGETOWN, TX 786270739
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	14833
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20031107
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	MAX STONE
Operator Address:	PO BOX 739
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	GEORGETOWN, TX 78627
Operator Country:	UNITED STA
Operator Telephone:	1-512-4410893
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Individual
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	MAX STONE
Owner Mailing Address:	PO BOX 739
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	GEORGETOWN, TX 78627
Owner Country:	UNITED STA
Owner Telephone:	1-512-4410893
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Individual
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	Not reported
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Unit Description:	ENCLOSED WAREHOUSE SPACE Cap: 15 DRUMS
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19871001
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	MAX STONE
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 739
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	GEORGETOWN, TX 78627
Contact Phone:	1-512-4410893
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	MAX STONE
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 739
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	GEORGETOWN, TX 78627
Contact Phone:	1-512-4410893
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	DEAN MCCORMICK
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 739
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	GEORGETOWN, TX 78627
Contact Phone:	1-512-4410893
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	261565
Texas Waste Code:	Not reported
Texas Waste Code 2:	C3XS211H
Waste Code Status:	Not reported
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Not reported
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 14763
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78761
AR Number:	0000312669
Principal Name:	STONE, MAX
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 14763
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78761
AR Number:	0000312669
Principal Name:	STONE, MAX
Attention Name:	Not reported
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600382907
Customer Name:	STONE, MAX
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/6/2000
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600382907
Customer Name:	STONE, MAX
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/6/2000
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601264039
Customer Name:	STONE INDUSTRIAL SOLVENTS INC
Customer Legal Name:	Stone Industrial Solvents, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	Not reported
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601264039
Customer Name:	STONE INDUSTRIAL SOLVENTS INC
Customer Legal Name:	Stone Industrial Solvents, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	Not reported
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Customer Number: CN601453129
Customer Name: AURACHEM INC
Customer Legal Name: Aurachem, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 4/14/2000
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN100675339
Name: STONE INDUSTRIAL SOLVENTS
Address: 301 INDUSTRIAL BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-1206
Status: ACTIVE
Status Date: ##########
Customer Number: CN601453129
Customer Name: AURACHEM INC
Customer Legal Name: Aurachem, Inc.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 4/14/2000
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN100675339
Name: STONE INDUSTRIAL SOLVENTS
Address: 301 INDUSTRIAL BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-1206
Status: ACTIVE
Status Date: ##########
Customer Number: CN605994656
Customer Name: 403 INDUSTRIAL ATX LLC
Customer Legal Name: 403 INDUSTRIAL ATX LLC
Customer Ownership Type: OTHER
Affiliation Begin Date: 2/22/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Regulated Entity Number: RN100675339
Name: STONE INDUSTRIAL SOLVENTS
Address: 301 INDUSTRIAL BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78745-1206
Status: ACTIVE
Status Date: ##########
Customer Number: CN605994656
Customer Name: 403 INDUSTRIAL ATX LLC
Customer Legal Name: 403 INDUSTRIAL ATX LLC

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Customer Ownership Type:	OTHER
Affiliation Begin Date:	2/22/2022
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601264039
Customer Name:	STONE INDUSTRIAL SOLVENTS INC
Customer Legal Name:	Stone Industrial Solvents, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/1/1974
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601264039
Customer Name:	STONE INDUSTRIAL SOLVENTS INC
Customer Legal Name:	Stone Industrial Solvents, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	1/1/1974
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN100675339
Name:	STONE INDUSTRIAL SOLVENTS
Address:	301 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1206
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600382907
Customer Name:	STONE, MAX
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	1/6/2000
Affiliation End Date:	12/31/3000

STONE INDUSTRIAL SOLVENTS (Continued) **U002112544**

Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: Not reported

Click this hyperlink while viewing on your computer to access
25 additional TX CENTRAL REG: record(s) in the EDR Site Report.

3145 SSE 1/8-1/4 0.245 mi. 1294 ft. **CIRCLE K STORE 2704673** **TX RDR** **S127539923**
8801 S I 35 **N/A**
AUSTIN, TX

Actual: 652 ft.
Focus Map: 21

RDR:

RDR ID:	24043
Facility ID:	76336
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K STORE 2704673
Address:	8801 S I 35
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/22/2016
Due Date:	2/20/2017
Tank Owner:	CIRCLE K STORES INC
Contact Person:	MINDY SZANISZLO
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/15/2017
Project Manager:	Terence Webb
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR REC 9/27/16; DEF LTR 11/14/16; TECH RESP REC12/22/16;
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TB3146 WNW 1/8-1/4 0.246 mi. 1297 ft. **CAPITOL CHEVROLET** **TX LPST** **U001259227**
501 N LAMAR BLVD **TX UST** **N/A**
AUSTIN, TX 78703 **TX HIST UST**
TX Ind. Haz Waste
Site 2 of 3 in cluster TB

Actual: 480 ft.
Focus Map: 11

LPST:

Name:	CAPITOL CHEVROLET
Address:	501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0025102
LPST Id:	095067
Facility Location:	501 N LAMAR BLVD

CAPITOL CHEVROLET (Continued) **U001259227**

TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/15/1990
Entered Date:	03/29/1990
Reported Date:	01/15/1990
Closure Date:	07/27/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	SKIP WILLIAMS
Responsible Party Address:	501 N LAMAR BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	/-
Reported Date:	01/15/1990
Case Start Date:	07/27/1990
Reference Number:	RN103198958
Project Manager:	HWELCH

UST:

Name:	CAPITOL CHEVROLET
Address:	501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787035411
AI Number:	25102
Facility Type:	RETAIL
Facility Begin Date:	10/07/1986
Facility Status:	INACTIVE
Additional ID:	20403372003094
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	SKIP WILLIAMS,SERV MGR
Contact Organization Name:	CAPITOL CHEVROLET
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124766641
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/14/1986
Signature Name/Title On Earliest Reg Form:	SKIP WILLIAMS,SERV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

CAPITOL CHEVROLET (Continued) **U001259227**

Owner:

Owner CN:	CN600246029
Owner Last Name:	CAPITOL CHEVROLET INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	68479132001288
Additional ID:	20403372003094
AI Number:	25102
Owner Effective Begin Date:	10/07/1986
State Tax ID:	17410470334
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64599
Facility ID:	61787
Ai Number:	25102
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	76778
UST ID:	64599
AI Number:	25102
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N

CAPITOL CHEVROLET (Continued) **U001259227**

PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169278
Facility ID:	61787
Ai Number:	25102
Tank Id:	14
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	14
Tank Capacity:	40
UST Comprt ID:	77467
UST ID:	169278
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N

CAPITOL CHEVROLET (Continued) **U001259227**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64601
Facility ID:	61787
Ai Number:	25102
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

CAPITOL CHEVROLET (Continued) **U001259227**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	76780
UST ID:	64601
AI Number:	25102
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169254
Facility ID:	61787
Ai Number:	25102
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	40
UST Comprt ID:	76781
UST ID:	169254
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169255
Facility ID:	61787
Ai Number:	25102
Tank Id:	12
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Installation Signature Date:	Not reported
Compartment Records:	
Tank ID:	12
Tank Capacity:	40
UST Comprt ID:	77444
UST ID:	169255
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169256
Facility ID:	61787
Ai Number:	25102
Tank Id:	11
Tank Status (Current):	IN USE

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	11
Tank Capacity:	40
UST Comprt ID:	77445
UST ID:	169256
AI Number:	25102
Compartment ID:	A

CAPITOL CHEVROLET (Continued) **U001259227**

Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169257
Facility ID:	61787
Ai Number:	25102
Tank Id:	10
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	10
Tank Capacity:	40
UST Comprt ID:	77446
UST ID:	169257
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

CAPITOL CHEVROLET (Continued) **U001259227**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169258
Facility ID:	61787
Ai Number:	25102
Tank Id:	9
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	9
Tank Capacity:	40
UST Comprt ID:	77447
UST ID:	169258
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

CAPITOL CHEVROLET (Continued) **U001259227**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169259
Facility ID:	61787
Ai Number:	25102
Tank Id:	8
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	8
Tank Capacity:	40
UST Comprt ID:	77448
UST ID:	169259
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169260
Facility ID:	61787
Ai Number:	25102
Tank Id:	7
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	7
Tank Capacity:	40
UST Comprt ID:	77449
UST ID:	169260
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169261
Facility ID:	61787
Ai Number:	25102
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	6
Tank Capacity:	40
UST Comprt ID:	77450
UST ID:	169261
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169262
Facility ID:	61787
Ai Number:	25102
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	40
UST Comprt ID:	77451
UST ID:	169262
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169263
Facility ID:	61787
Ai Number:	25102
Tank Id:	28

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	28
Tank Capacity:	40
UST Comprt ID:	77452
UST ID:	169263
AI Number:	25102

CAPITOL CHEVROLET (Continued) **U001259227**

Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169264
Facility ID:	61787
Ai Number:	25102
Tank Id:	27
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	27
Tank Capacity:	40
UST Comprt ID:	77453
UST ID:	169264
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

CAPITOL CHEVROLET (Continued) **U001259227**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169265
Facility ID:	61787
Ai Number:	25102
Tank Id:	26
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	26
Tank Capacity:	40
UST Comprt ID:	77454
UST ID:	169265
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169266
Facility ID:	61787
Ai Number:	25102
Tank Id:	25
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	25
Tank Capacity:	40
UST Comprt ID:	77455
UST ID:	169266
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N

CAPITOL CHEVROLET (Continued) **U001259227**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169267
Facility ID:	61787
Ai Number:	25102
Tank Id:	24
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

CAPITOL CHEVROLET (Continued) **U001259227**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	24
Tank Capacity:	40
UST Comprt ID:	77456
UST ID:	169267
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169268
Facility ID:	61787
Ai Number:	25102
Tank Id:	23
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	23
Tank Capacity:	40
UST Comprt ID:	77457
UST ID:	169268
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986

CAPITOL CHEVROLET (Continued) **U001259227**

Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169269
Facility ID:	61787
Ai Number:	25102
Tank Id:	22
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	22
Tank Capacity:	40
UST Comprt ID:	77458
UST ID:	169269
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169270
Facility ID:	61787
Ai Number:	25102

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Id:	21
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	21
Tank Capacity:	40
UST Comprt ID:	77459
UST ID:	169270

CAPITOL CHEVROLET (Continued) **U001259227**

AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169271
Facility ID:	61787
Ai Number:	25102
Tank Id:	20
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	20
Tank Capacity:	40
UST Comprt ID:	77460
UST ID:	169271
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

CAPITOL CHEVROLET (Continued) **U001259227**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169272
Facility ID:	61787
Ai Number:	25102
Tank Id:	19
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	19
Tank Capacity:	40
UST Comprt ID:	77461
UST ID:	169272
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169273
Facility ID:	61787
Ai Number:	25102
Tank Id:	18
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	18
Tank Capacity:	40
UST Comprt ID:	77462
UST ID:	169273
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

CAPITOL CHEVROLET (Continued) **U001259227**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169274
Facility ID:	61787
Ai Number:	25102
Tank Id:	17
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

CAPITOL CHEVROLET (Continued) **U001259227**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	17
Tank Capacity:	40
UST Comprt ID:	77463
UST ID:	169274
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169275
Facility ID:	61787
Ai Number:	25102
Tank Id:	16
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

CAPITOL CHEVROLET (Continued) **U001259227**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	16
Tank Capacity:	40
UST Comprt ID:	77464
UST ID:	169275
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952

CAPITOL CHEVROLET (Continued) **U001259227**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169276
Facility ID:	61787
Ai Number:	25102
Tank Id:	13
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

CAPITOL CHEVROLET (Continued) **U001259227**

Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	13
Tank Capacity:	40
UST Comprt ID:	77465
UST ID:	169276
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	169277
Facility ID:	61787

CAPITOL CHEVROLET (Continued) **U001259227**

Ai Number:	25102
Tank Id:	15
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1952
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	15
Tank Capacity:	40
UST Comprt ID:	77466

CAPITOL CHEVROLET (Continued) **U001259227**

UST ID:	169277
AI Number:	25102
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1952
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64600
Facility ID:	61787
Ai Number:	25102
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/16/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

CAPITOL CHEVROLET (Continued) **U001259227**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	0
UST Comprt ID:	76779
UST ID:	64600
AI Number:	25102
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

CAPITOL CHEVROLET (Continued) **U001259227**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CAPITOL CHEVROLET INC
Contact Mailing Address (Delivery):	PO BOX 1988
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1988
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61787
Additional ID:	20403372003094
Princ ID:	68479132001288
AI Number:	25102
Facility Name:	CAPITOL CHEVROLET
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KEVIN JOHNSON/

HIST UST AUSTIN:

Name:	CAPITOL CHEVROLET INC
Address:	501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX

CAPITOL CHEVROLET (Continued) **U001259227**

Id UST:	267
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	CAPITOL CHEVROLET
Address:	501 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66177
Registration Initial Notification Date:	07/16/1984
Registration Last Amendment Date:	08/11/2020
EPA Identification:	TXD008944928
Primary NAICS Code:	441110
Status Change Date:	19840716
Land Type:	PRIVATE
Description of Facility Site Location:	501 N Lamar Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CAPITOL CHEVROLET INC
Contact Name:	SKIP WILLIAMS
Contact Telephone Number:	512-4766641
Mailing Address:	PO BOX 1988
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787671988
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21475
Site Owner Tax ID:	741047033
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20200811
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0

CAPITOL CHEVROLET (Continued) **U001259227**

Transport Own Waste: 0

Ind. Haz Waste:

Operator Name:	CAPITOL CHEVROLET INC
Operator Address:	PO BOX 1988
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78767
Operator Country:	UNITED STA
Operator Telephone:	1-512-4766641
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	17410470334
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CAPITOL CHEVROLET INC
Owner Mailing Address:	PO BOX 1988
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78767
Owner Country:	UNITED STA
Owner Telephone:	1-512-4766641
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	17410470334
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	PO BOX 1988
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4766641
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 1988
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4766641
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	SKIP WILLIAMS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	PO BOX 1988

CAPITOL CHEVROLET (Continued) **U001259227**

Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78767
Contact Phone:	1-512-4766641
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	92520
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004101H
Waste Code Status:	INACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Liquid cleaning compound containing monoethanolamine.
Standard Industrial Code:	55110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste cleaning solution
Primary NAICS Code:	441110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	92521
Texas Waste Code:	Not reported
Texas Waste Code 2:	00052061
Waste Code Status:	INACTIVE
Waste Form:	206
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste oil
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

CAPITOL CHEVROLET (Continued) **U001259227**

Company Waste ID:	Waste oil
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	92522
Texas Waste Code:	Not reported
Texas Waste Code 2:	00062961
Waste Code Status:	INACTIVE
Waste Form:	296
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Ethylene glycol antifreeze
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste antifreeze coolant
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	138863
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	75380
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012027
Primary NAICS Code:	811111
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

CAPITOL CHEVROLET (Continued) **U001259227**

Waste ID:	123754
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Liquid cleaning compound containing monoethanolamine.
Standard Industrial Code:	55110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	441110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 1988
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78767
AR Number:	0000302645
Principal Name:	CAPITOL CHEVROLET INC
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	PO BOX 1988
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78767
AR Number:	0000302645
Principal Name:	CAPITOL CHEVROLET INC
Attention Name:	Not reported
Attention Suffix:	NWG

TB3147 **CAPITOL CHEVROLET** **TX UST** **1000264755**
WNW **501 N LAMAR BLVD** **TX HIST UST** **TXD008944928**
1/8-1/4 **AUSTIN, TX 78703** **RCRA NonGen / NLR**
0.246 mi.
1297 ft. **Site 3 of 3 in cluster TB**

Actual:
480 ft.

Focus Map:
11

UST:

Name:	CAPITOL CHEVROLET
Address:	500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787035264
AI Number:	45653
Facility Type:	FLEET REFUELING
Facility Begin Date:	12/29/1987
Facility Status:	INACTIVE
Additional ID:	321104442002117
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	WHIT HANKS,
Contact Organization Name:	CAPITOL CHEVROLET
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124782264
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	12/30/1986
Signature Name/Title On Earliest Reg Form:	W M WILLIAMS,SERV MGR
Application Received Date On Earliest Reg Form:	12/31/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600246029
Owner Last Name:	CAPITOL CHEVROLET INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	68479132001288
Additional ID:	321104442002117

CAPITOL CHEVROLET (Continued) **1000264755**

AI Number:	45653
Owner Effective Begin Date:	12/29/1987
State Tax ID:	17410470334
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1977
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119513
Facility ID:	77175
Ai Number:	45653
Tank Id:	BSG02
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/22/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

CAPITOL CHEVROLET (Continued) **1000264755**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	BSG02
Tank Capacity:	6000
UST Comprt ID:	118321
UST ID:	119513
AI Number:	45653
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

CAPITOL CHEVROLET (Continued) **1000264755**

Install Date:	01/01/1961
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	119514
Facility ID:	77175
Ai Number:	45653
Tank Id:	BSG01
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/22/1997
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

CAPITOL CHEVROLET (Continued) **1000264755**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	BSG01
Tank Capacity:	3000
UST Comprt ID:	118322
UST ID:	119514
AI Number:	45653
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1936
Tank Registration Date:	12/31/1986
Number of Compartments:	1
Tank Capacity:	40
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	171410

CAPITOL CHEVROLET (Continued) **1000264755**

Facility ID:	77175
Ai Number:	45653
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/27/2010
Empty:	N
Tank Regulatory Status:	EXEMPT
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	40

CAPITOL CHEVROLET (Continued) **1000264755**

UST Comprt ID:	118323
UST ID:	171410
AI Number:	45653
Compartment ID:	A
Substance Stored1:	HYDRAULIC LIFT OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CAPITOL CHEVROLET INC
Contact Mailing Address (Delivery):	PO BOX 1988
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78767 1988
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77175
Additional ID:	321104442002117
Princ ID:	68479132001288
AI Number:	45653
Facility Name:	CAPITOL CHEVROLET
AR Number:	Not reported
AR UST Number Suffix:	Not reported

CAPITOL CHEVROLET (Continued) **1000264755**

AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	CONSTANT SERVICE CO.
Address:	500 N LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	H0387
HID UST:	387
Inspection:	04/01/2009
Due:	04/01/2012

RCRA Listings:

Date Form Received by Agency:	20200811
Handler Name:	Capitol Chevrolet
Handler Address:	501 N LAMAR BLVD
Handler City,State,Zip:	AUSTIN, TX 78703-5411
EPA ID:	TXD008944928
Contact Name:	SKIP WILLIAMS
Contact Address:	PO BOX 1988
Contact City,State,Zip:	AUSTIN, TX 78767-1988
Contact Telephone:	512-476-6641
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 1988
Mailing City,State,Zip:	AUSTIN, TX 78767-1988
Owner Name:	Capitol Chevrolet Inc
Owner Type:	Private
Operator Name:	Capitol Chevrolet Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

CAPITOL CHEVROLET (Continued) **1000264755**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200818
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D021
Waste Description:	Chlorobenzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040

CAPITOL CHEVROLET (Continued) **1000264755**

Waste Description: Trichlorethylene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CAPITOL CHEVROLET INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1988
Owner/Operator City,State,Zip:	AUSTIN, TX 78767-1988
Owner/Operator Telephone:	512-476-6641
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CAPITOL CHEVROLET (Continued) **1000264755**

Owner/Operator Indicator:	Owner
Owner/Operator Name: CHARLES D NASH	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1988
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-476-6641
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CAPITOL CHEVROLET INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1988
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-476-6641
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CAPITOL CHEVROLET INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1988
Owner/Operator City,State,Zip:	AUSTIN, TX 78767
Owner/Operator Telephone:	512-476-6641
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CAPITOL CHEVROLET INC	
Legal Status:	Private
Date Became Current:	20010127
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1988
Owner/Operator City,State,Zip:	AUSTIN, TX 78767-1988
Owner/Operator Telephone:	512-476-6641
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19971229
Handler Name: CAPITOL CHEV INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CAPITOL CHEVROLET (Continued) **1000264755**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010127
Handler Name: CAPITOL CHEVROLET INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20200811
Handler Name: CAPITOL CHEVROLET
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44111
NAICS Description: NEW CAR DEALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

TI3148 **AUSTIN CULLIGAN** **TX LPST** **S111057576**
East **505 W YAGER LANE** **TX TIER 2** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.246 mi.
1297 ft. **Site 1 of 2 in cluster TI**

Actual:
664 ft.

Focus Map:
4

LPST:
Name: YAGER
Address: 505 W YAGER LN
City,State,Zip: AUSTIN, TX 78753
Facility ID: 0058012
LPST Id: 099146
Facility Location: YAGER LN W SIDE IH 35
TCEQ Region# and City: REGION 11 - AUSTIN

AUSTIN CULLIGAN (Continued) **S111057576**

Region City:	AUSTIN
Discovered Date:	05/22/1991
Entered Date:	06/05/1991
Reported Date:	05/22/1991
Closure Date:	10/14/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	DRR
Responsible Party Name:	Not reported
Responsible Party Contact:	STEVE WAREING
Responsible Party Address:	PO BOX 908
Responsible Party City,St,Zip:	AUSTIN, TX 78781
Responsible Party Telephone:	512/397-3124
Reported Date:	05/22/1991
Case Start Date:	10/14/1991
Reference Number:	RN102279734
Project Manager:	DROGERS

TIER 2:

Facility Id/Name:	FATR201293XAC9002EV8/AUSTIN CULLIGAN
Reporting Year:	2012
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/8/2013
Date Tier 2 Signed:	2/14/2013
Mailing Address:	PO Box 141339
Mailing City/State/Country:	Austin, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	Not reported
Number Of Employess On Site:	32
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	Karla Ford
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20118BNFSX002AQC/AUSTIN CULLIGAN
Reporting Year:	2011
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	5/16/2012

AUSTIN CULLIGAN (Continued) **S111057576**

Date Tier 2 Signed:	1/5/2012
Mailing Address:	PO BOX 141339
Mailing City/State/Country:	AUSTIN, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	True
State Fees Total:	50.00
Number Of Employess On Site:	30
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	KARLA FORD
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Id/Name:	FATR20107SFXE9002QVU/AUSTIN CULLIGAN
Reporting Year:	2010
Facility Country:	USA
Facility Department:	Not reported
Facility Date Modified:	6/1/2011
Date Tier 2 Signed:	3/14/2011
Mailing Address:	PO BOX 141339
Mailing City/State/Country:	AUSTIN, TX USA
Dikes/Other Safeguard Meas Emp:	Not reported
All Chemicals Same As Last Year:	Not reported
State Fees Total:	50.00
Number Of Employess On Site:	30
Site Map:	Not reported
Fire District:	Not reported
Submitted By:	KARLA FORD
Latitude:	Not reported
Longitude:	Not reported
Lat/Long Location Desc:	Not reported
Lat/Long Method:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Number Of Emp. Required:	Not reported
Fail Valid:	Not reported
Site Coordinate Abbr Submitted:	Not reported
Mail Address:	Not reported
Mail City:	Not reported
Mail State Req.:	Not reported
Fire District:	Not reported
Additional Mail Addr:	Not reported

Facility Info:

Id:	453998
Id Type:	NAICS
Description:	All Other Miscellaneous Store Retailers (except Tobacco Stores)

AUSTIN CULLIGAN (Continued) **S111057576**

Last Modified: 1/5/2012

Contact:
Contact Email: KARLA@ULTRAPURE.COM
Contact Mail Address: 505 W YAGER LANE
Contact City/State/Zip: AUSTIN, TX 78753
Contact Mail Country: USA
Contact Type 1: Submitter
Contact Name: KARLA FORD
Title: OFFICE MANAGER
Modification Date: 1/5/2012

Contact:
Contact Email: PERRY@ULTRAPURE.COM
Contact Mail Address: 505 W YAGER LANE
Contact City/State/Zip: AUSTIN, TX 78753
Contact Mail Country: USA
Contact Type 1: Emergency Contact
Contact Type 2: Emergency Contact
Contact Name: PERRY RATCLIFF
Title: GM
Modification Date: 2/14/2012

Contact:
Contact Email: Not reported
Contact Mail Address: 505 W YAGER LANE
Contact City/State/Zip: AUSTIN, TX 78753
Contact Mail Country: USA
Contact Type 1: Owner / Operator
Contact Name: PERRY RATCLIFF
Title: GM
Modification Date: 2/14/2012

Chemical Inventory:
Facility Id: FATR20118BNFSX002AQC
Chemical Name: SULFURIC ACID
Chemical Inv Record Id: CVTR20118BNGDV00GF4J
CAS Number: 7664-93-9
Chemical Same As Last Year: T
Acute Health Risks: T
Average Daily Amount: 100 - 999 pounds
Max Daily Amount: 100 - 999 pounds
Max Amount In Largest Container: Not reported
Chronic Health Risks: Not reported
EHS Substance: T
Last Modified: 2/14/2012
Days On Site: 365
Fire Hazard: Not reported
Gas: Not reported
Liquid: T
Mixture Form: T
Sudden Release Of Pressure Haz: Not reported
Pure Form: Not reported

AUSTIN CULLIGAN (Continued) **S111057576**

Reactive Hazard: T
Solid: Not reported
Trade Secret: Not reported
Contact Label: Not reported
Label Code: TX2011
Trade Secret: Not reported

Chemical Inventory Location:
Record Key: CLTR20118BNGGQ00HWSR
Chemical Inventory Record Id: CVTR20118BNGDV00GF4J
Amt Of Sub Stored Or Transported: 700
Amount Units: pounds
Type Of Storage: Plastic or non-metallic drum
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: WAREHOUSE
Last Modified: 2/14/2012

Mixture:
Record Key: CMTR20118BNGHJ00JLNT
Chemical Inv Record Id: CVTR20118BNGDV00GF4J
Mix Chemical: SULFURIC ACID
Percentage: 93
Facility Id: FATR20118BNFSX002AQC
Mixture Cas: 7664-93-9
Weight/Volume: Vol
Mixture Ehs: T
Mixture Last Modified: 2/14/2012

Record Key: CMTR20118BNGJX00KTM8
Chemical Inv Record Id: CVTR20118BNGDV00GF4J
Mix Chemical: WATER
Percentage: 7
Facility Id: FATR20118BNFSX002AQC
Mixture Cas: 7732-18-5
Weight/Volume: Vol
Mixture Ehs: Not reported
Mixture Last Modified: 2/14/2012

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 453998
Id Type: NAICS
Description: All Other Miscellaneous Store Retailers (except Tobacco Stores)
Last Modified: 2/14/2013

Contact:
Contact Email: karla@ultrapure.com
Contact Mail Address: 505 W Yager Lane
Contact City/State/Zip: Austin, TX 78753
Contact Mail Country: USA
Contact Type 1: Billing

AUSTIN CULLIGAN (Continued) **S111057576**

Contact Name:	Karla Ford
Title:	Office Manager
Modification Date:	2/14/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	505 W Yager Lane
Contact City/State/Zip:	Austin, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	Irma Bishop
Title:	GM
Modification Date:	2/22/2013

Contact:

Contact Email:	Not reported
Contact Mail Address:	505 W Yager Lane
Contact City/State/Zip:	Austin, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	Irma Bishop
Title:	GM
Modification Date:	2/22/2013

Chemical Inventory:

Facility Id:	FATR201293XAC9002EV8
Chemical Name:	DILUTE SULFURIC ACID
Chemical Inv Record Id:	CVTR201293XBBR00DDDU
CAS Number:	7664-93-9
Chemical Same As Last Year:	T
Acute Health Risks:	Not reported
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	2/22/2013
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	Not reported
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2012
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR201293XBFN00ESMS

AUSTIN CULLIGAN (Continued) **S111057576**

Chemical Inventory Record Id: CVTR201293XBBR00DDDU
Amt Of Sub Stored Or Transported: 700
Amount Units: pounds
Type Of Storage: Plastic or non-metallic drum
Number Code/Storage Pressure: 1
Number Code/Storage Temperature: 4
Desc of Loc(Or Transported) Subs: warehouse
Last Modified: 2/22/2013

Mixture:
Record Key: CMTR201293XBL100FKJX
Chemical Inv Record Id: CVTR201293XBBR00DDDU
Mix Chemical: Sulfuric Acid
Percentage: 93
Facility Id: FATR201293XAC9002EV8
Mixture Cas: 7664-93-9
Weight/Volume: Vol
Mixture Ehs: T
Mixture Last Modified: 2/22/2013

Record Key: CMTR201293XBN400GC7T
Chemical Inv Record Id: CVTR201293XBBR00DDDU
Mix Chemical: Water
Percentage: 7
Facility Id: FATR201293XAC9002EV8
Mixture Cas: 7732-18-5
Weight/Volume: Vol
Mixture Ehs: Not reported
Mixture Last Modified: 2/22/2013

Notes: Not reported
Validation: Not reported

Facility Info:
Id: 453998
Id Type: NAICS
Description: All Other Miscellaneous Store Retailers (except Tobacco Stores)
Last Modified: 3/14/2011

Contact:
Contact Email: KARLA@ULTRAPURE.COM
Contact Mail Address: PO BOX 141339
Contact City/State/Zip: AUSTIN, TX 78714-1339
Contact Mail Country: USA
Contact Type 1: Billing
Contact Name: KARLA FORD
Title: OFFICE MANAGER
Modification Date: 3/14/2011

Contact:
Contact Email: PERRY@ULTRAPURE.COM
Contact Mail Address: 505 W YAGER LN
Contact City/State/Zip: AUSTIN, TX 78753

AUSTIN CULLIGAN (Continued) **S111057576**

Contact Mail Country:	USA
Contact Type 1:	Emergency Contact
Contact Name:	PERRY RATCLIFF
Title:	GM
Modification Date:	4/2/2011

Contact:

Contact Email:	PERRY@ULTRAPURE.COM
Contact Mail Address:	505 W YAGER LN
Contact City/State/Zip:	AUSTIN, TX 78753
Contact Mail Country:	USA
Contact Type 1:	Owner / Operator
Contact Name:	PERRY RATCLIFF
Title:	GM
Modification Date:	4/2/2011

Chemical Inventory:

Facility Id:	FATR20107SFXE9002QVU
Chemical Name:	SULFURIC ACID
Chemical Inv Record Id:	CVTR20107SFYLG00FHBE
CAS Number:	7664-93-9
Chemical Same As Last Year:	Not reported
Acute Health Risks:	T
Average Daily Amount:	100 - 999 pounds
Max Daily Amount:	100 - 999 pounds
Max Amount In Largest Container:	Not reported
Chronic Health Risks:	Not reported
EHS Substance:	T
Last Modified:	4/2/2011
Days On Site:	365
Fire Hazard:	Not reported
Gas:	Not reported
Liquid:	T
Mixture Form:	T
Sudden Release Of Pressure Haz:	Not reported
Pure Form:	Not reported
Reactive Hazard:	T
Solid:	Not reported
Trade Secret:	Not reported
Contact Label:	Not reported
Label Code:	TX2010
Trade Secret:	Not reported

Chemical Inventory Location:

Record Key:	CLTR20107SG0GG00GWA3
Chemical Inventory Record Id:	CVTR20107SFYLG00FHBE
Amt Of Sub Stored Or Transported:	700
Amount Units:	pounds
Type Of Storage:	Plastic or non-metallic drum
Number Code/Storage Pressure:	1
Number Code/Storage Temperature:	4
Desc of Loc(Or Transported) Subs:	WAREHOUSE
Last Modified:	4/2/2011

AUSTIN CULLIGAN (Continued) **S111057576**

Mixture:

Record Key:	CMTR20107SG11800L3VB
Chemical Inv Record Id:	CVTR20107SFYLG00FHBE
Mix Chemical:	SULFURIC ACID
Percentage:	93
Facility Id:	FATR20107SFXE9002QVU
Mixture Cas:	7664-93-9
Weight/Volume:	Vol
Mixture Ehs:	T
Mixture Last Modified:	4/2/2011

Record Key:	CMTR20107SG0LE00H9TY
Chemical Inv Record Id:	CVTR20107SFYLG00FHBE
Mix Chemical:	WATER
Percentage:	7
Facility Id:	FATR20107SFXE9002QVU
Mixture Cas:	7732-18-5
Weight/Volume:	Vol
Mixture Ehs:	Not reported
Mixture Last Modified:	4/2/2011

Notes: Not reported
Validation: Not reported

TI3149 **YAGER** **TX UST** **U001287832**
East **505 W YAGER LN** **N/A**
1/8-1/4 **AUSTIN, TX 78753**
0.246 mi.
1297 ft. **Site 2 of 2 in cluster TI**

Actual:
664 ft.

Focus Map:
4

UST:

Name:	YAGER
Address:	505 W YAGER LN
City,State,Zip:	AUSTIN, TX 787531311
AI Number:	58012
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	134221292002139
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	YAGER
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123973124
Facility Contact Address Deliverable:	Not reported

YAGER (Continued) **U001287832**

Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/08/1991
Signature Name/Title On Earliest Reg Form:	TOM SHARP,PROJECT MGR
Application Received Date On Earliest Reg Form:	04/12/1991
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600845093
Owner Last Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	FG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	31443472002064
Additional ID:	134221292002139
AI Number:	58012
Owner Effective Begin Date:	01/31/1995
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/12/1991
Number of Compartments:	1
Tank Capacity:	Not reported
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	138763
Facility ID:	85717
Ai Number:	58012
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/20/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

YAGER (Continued) **U001287832**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/27/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	0
UST Comprt ID:	132082
UST ID:	138763
AI Number:	58012
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

YAGER (Continued) **U001287832**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	FEDERAL DEPOSIT INSURANCE CORPORATION
Contact Mailing Address (Delivery):	1910 PACIFIC AVE STE 1300
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75201 4529
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85717
Additional ID:	134221292002139
Princ ID:	31443472002064
AI Number:	58012
Facility Name:	YAGER
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SHARON K ALLEN/

SW3150 East 1/8-1/4 0.246 mi. 1298 ft. | **CITIES SERVICE OIL CO.**
1000 E 6TH ST
AUSTIN, TX
Site 4 of 4 in cluster SW | **TX HIST UST** | **S111678605**
N/A

Actual: 500 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	CITIES SERVICE OIL CO.
Address:	1000 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0223
HID UST:	223
Inspection:	02/20/2009
Due:	02/20/2012

TH3151 ESE 1/8-1/4 0.246 mi. 1300 ft. | **403 - 301 INDUSTRIAL BOULEVARD SITE**
403 INDUSTRIAL BLVD
AUSTIN, TX 78745
Site 5 of 5 in cluster TH | **TX VCP** | **S128621625**
N/A

Actual: 669 ft.
Focus Map: 18

VCP TCEQ:

Name:	403 - 301 INDUSTRIAL BOULEVARD SITE
Address:	403 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78745
Region:	REGION 11 - AUSTIN
Facility ID:	3214
VCP Record Date:	02/22/2022
Facility Type:	VACANT PROPERTY
PCA Number:	68513
Project Manager:	RSCHARLA
Phase:	INVESTIGATION
Acres at Site:	0.35
REM Program:	VCP
RN Number:	RN100675339
Former Facility Type:	MFG CHEMICAL
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	ACTIVE
Region Notified of Application:	03/15/2022
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	OTHER
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported

403 - 301 INDUSTRIAL BOULEVARD SITE (Continued) **S128621625**

Date Cashier Check Received:	02/22/2022
GW Target COC Class:	CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2022-03-18 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	3214; 1138
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	685130
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D-293
Latitude:	30.22
Longitude:	-97.76

Contact:

REM Program:	VCP
Program ID:	3214
RN Number:	RN100675339
CN Number:	CN605994656
CN Name:	403 INDUSTRIAL ATX LLC
Role Code:	APPLCONT
Contact Name:	LEIFER, MAXWELL
Contact Title:	AUTHORIZED REPRESENTATIVE
Organization Name:	403 INDUSTRIAL ATX LLC
Mailing Address:	220 INDUSTRIAL BLVD STE 101
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78745
Contact Telephone:	(203) 247-1883
Contact Telephone Ext:	0

SZ3152 **TEXAS ALTERNATOR STARTER SERVICE** **TX UST** **U003566317**
North **1230 E BEN WHITE BLVD** **N/A**
1/8-1/4 **AUSTIN, TX 78742**
0.247 mi.
1305 ft. **Site 3 of 3 in cluster SZ**

Actual:
471 ft.

Focus Map:
16

UST:

Name:	TEXAS ALTERNATOR STARTER SERVICE
Address:	1230 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78742
AI Number:	41169
Facility Type:	UNKNOWN
Facility Begin Date:	01/22/1987
Facility Status:	INACTIVE
Additional ID:	775543352005209
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11

TEXAS ALTERNATOR STARTER SERVICE (Continued) **U003566317**

Site Location (Location Zip):	78742
Contact Name/Title:	HAROLD FARREL,MGR
Contact Organization Name:	TEXAS ALTERNATOR STARTER SERVICE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123854545
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/24/1986
Signature Name/Title On Earliest Reg Form:	STEVE PFERTNER,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602880387
Owner Last Name:	THE MCADAMS GROUP LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	764543352005209
Additional ID:	775543352005209
AI Number:	41169
Owner Effective Begin Date:	01/22/1987
State Tax ID:	17428714491
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	109071
Facility ID:	70748
Ai Number:	41169
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE

TEXAS ALTERNATOR STARTER SERVICE (Continued) **U003566317**

Tank Status Date:	11/30/1979
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	85149
UST ID:	109071
AI Number:	41169
Compartment ID:	A

TEXAS ALTERNATOR STARTER SERVICE (Continued) **U003566317**

Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS ALTERNATOR STARTER SERVICE
Contact Mailing Address (Delivery):	9545 N INTERREGIONAL HWY # 35
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78753 3804
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	70748
Additional ID:	775543352005209
Princ ID:	764543352005209
AI Number:	41169
Facility Name:	TEXAS ALTERNATOR STARTER SERVICE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

3153 East 1/8-1/4 0.247 mi. 1306 ft. | **TEXACO RETAIL FAC**
2453 HWY 71
DEL VALLE, TX | **TX RDR** | **S127530905**
N/A

Actual: 501 ft.
Focus Map: 20

RDR:

RDR ID:	12538
Facility ID:	34915
RN:	Not reported
CN:	Not reported
Name:	TEXACO RETAIL FAC
Address:	2453 HWY 71
City,State,Zip:	DEL VALLE, TX
Date Report Received:	3/8/2013
Due Date:	5/7/2013
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	SCOTT BURKEY
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	10/12/2012
Project Manager:	Victor Lombeida
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	91829
Comments:	6A; 95400 6A REOPEN OR NEW LPST#? RPT RETURNED 4/6/04; REL DET 8/3/12; RDR 8/3/2012; SIR 3/8/13
Review Coordinator:	VHL
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	10/12/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

3154 South 1/8-1/4 0.248 mi. 1311 ft. | **MABRY ORDNANCE SHOP**
AUSTIN, TX | **FUDS** | **1024904644**
N/A

Actual: 637 ft.
Focus Map: 14

FUDS:

EPA Region:	06
Installation ID:	TX69799F660000
Congressional District Number:	37
Name:	MABRY ORDNANCE SHOP
FUDS Number:	K06TX0209
City:	AUSTIN
State:	TX
County:	TRAVIS
Object ID:	1414
USACE Division:	SWD
USACE District:	Fort Worth District (SWF)
Status:	Properties without projects
Current Owner:	STATE: STATE Texas National Guard
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=57899
Eligibility:	Ineligible
Has Projects:	No
NPL Status:	Not reported

MABRY ORDNANCE SHOP (Continued) **1024904644**

Project Required:	No
Feature Description:	The Army constructed a small base at the site.
Latitude:	30.23055556
Longitude:	-97.75416667

SS3155 **DONS PAINT AND BODY SHOP** **TX AIRS** **S103606417**
WNW **1006 W 12TH ST** **TX Ind. Haz Waste** **N/A**
1/8-1/4 **AUSTIN, TX 78703** **TX COMP HIST**
0.248 mi.
1312 ft. **Site 8 of 9 in cluster SS**

Actual:
494 ft.

Focus Map:
11

AIRS:

Name:	GERBER COLLISION & GLASS - AUSTIN12TH ST
Address:	1006 W 12TH ST
City,State,Zip:	TX
Permit Num:	166357
Regulated Id:	RN100646660
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	09/02/2021
Expiration Date:	12/31/3000
Customer Id:	CN605878586
Company Name:	GERBER COLLISION TEXAS INC
Physical Location Desc:	Not reported
Rep Official(RO):	AUTHORIZED REPRESENTATIVE
RO Name:	MRS COLETTE BRUCE
RO Delivery Address:	16076 FOSTER ST
RO City/State/Zip:	STILWELL, K 66085-887
RO Phone:	913-707-3974
RO Ext Num:	0
RO EMail Address:	COLETTE@TEAMSAFETY.US
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

Ind. Haz Waste:

Name:	DONS PAINT AND BODY SHOP
Address:	1006 W 12TH ST
City,State,Zip:	AUSTIN, TX 78703
Permit Number:	Not reported
Registration Number:	66335
Registration Initial Notification Date:	06/20/1985
Registration Last Amendment Date:	01/14/2016
EPA Identification:	TXD981057920
Primary NAICS Code:	811121
Status Change Date:	20160126
Land Type:	Not reported
Description of Facility Site Location:	1006 W 12TH AUSTIN TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0

DONS PAINT AND BODY SHOP (Continued) **S103606417**

Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	DONS PAINT & BODY SHOP INC
Contact Name:	KEN CALDWELL
Contact Telephone Number:	512-4765536
Mailing Address:	1006 W 12TH ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787034120
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21614
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20161117
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	DONS PAINT & BODY SHOP INC
Operator Address:	1006 W 12TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78703
Operator Country:	UNITED STA
Operator Telephone:	1-512-4765536
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	17419485960
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	DONS PAINT & BODY SHOP INC
Owner Mailing Address:	1006 W 12TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78703
Owner Country:	UNITED STA
Owner Telephone:	1-512-4765536
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown

DONS PAINT AND BODY SHOP (Continued) **S103606417**

Owner Tax ID:	17419485960
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	22
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	16 gallon and 55 gallon drums located inside southwest corner of building.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19960415
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1006 W 12TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4765536
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1006 W 12TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4765536
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	KEN CALDWELL
Contact Title:	Not reported
Contact Role:	PRICONT

DONS PAINT AND BODY SHOP (Continued) **S103606417**

Contact Address:	1006 W 12TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78703
Contact Phone:	1-512-4765536
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	147717
Texas Waste Code:	Not reported
Texas Waste Code 2:	0001211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Paint waste and wash thinner generated by refinishing automobiles.
Standard Industrial Code:	75320
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	811121
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1006 W 12TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000311809
Principal Name:	DONS PAINT & BODY SHOP INC
Attention Name:	Not reported
Attention Suffix:	HWG
Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1006 W 12TH ST
Mailing Address 2:	Not reported

DONS PAINT AND BODY SHOP (Continued) **S103606417**

Mailing City,St,Zip:	AUSTIN, TX 78703
AR Number:	0000311809
Principal Name:	DONS PAINT & BODY SHOP INC
Attention Name:	Not reported
Attention Suffix:	NWG

COMP HIST:

RN Number:	RN100646660
Name:	DONS PAINT & BODY SHOP
Address:	1006 W 12TH ST
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605878586
CN Name:	GERBER COLLISION TEXAS INC
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811121
SIC Code:	5261
Related Number:	166357,P04397,P04397

RN Number:	RN100646660
Name:	DONS PAINT & BODY SHOP
Address:	1006 W 12TH ST
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600356711
CN Name:	DONS PAINT & BODY SHOP INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	811121
SIC Code:	1542
Related Number:	166357,P04397,P04397

SS3156 **DONS PAINT AND BODY SHOP** **RCRA NonGen / NLR** **1004784484**
WNW **1006 W 12TH** **FINDS** **TXD981057920**
1/8-1/4 **AUSTIN, TX 78703** **ECHO**
0.248 mi.
1312 ft. **Site 9 of 9 in cluster SS**

Actual:
494 ft.

Focus Map:
11

RCRA Listings:

Date Form Received by Agency:	20160114
Handler Name:	Dons Paint And Body Shop
Handler Address:	1006 W 12TH ST
Handler City,State,Zip:	AUSTIN, TX 78703-4120

DONS PAINT AND BODY SHOP (Continued) **1004784484**

EPA ID:	TXD981057920
Contact Name:	KEN CALDWELL
Contact Address:	1006 W 12TH ST
Contact City,State,Zip:	AUSTIN, TX 78703-4120
Contact Telephone:	512-476-5536
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL MANAGER
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1006 W 12TH ST
Mailing City,State,Zip:	AUSTIN, TX 78703-4120
Owner Name:	Dons Paint & Body Shop Inc
Owner Type:	Private
Operator Name:	Dons Paint & Body Shop Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160414
Recognized Trader-Importer:	No

DONS PAINT AND BODY SHOP (Continued) **1004784484**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner

DONS PAINT AND BODY SHOP (Continued) **1004784484**

Owner/Operator Name: DONS PAINT & BODY SHOP INC
Legal Status: Private
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 1006 W 12TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78703-4120
Owner/Operator Telephone: 512-476-5536
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DONS PAINT & BODY SHOP INC
Legal Status: Private
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 1006 W 12TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78703-4120
Owner/Operator Telephone: 512-476-5536
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DON M CALDWELL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 5007 JEFFERY PLACE
Owner/Operator City,State,Zip: AUSTIN, TX 78746-0000
Owner/Operator Telephone: 512-327-2251
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DONS PAINT & BODY SHOP INC
Legal Status: Not reported
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 1006 W 12TH
Owner/Operator City,State,Zip: AUSTIN, TX 78703
Owner/Operator Telephone: 512-476-5536
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DONS PAINT & BODY SHOP INC
Legal Status: Not reported
Date Became Current: 20010127
Date Ended Current: Not reported
Owner/Operator Address: 1006 W 12TH
Owner/Operator City,State,Zip: AUSTIN, TX 78703
Owner/Operator Telephone: 512-476-5536
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

DONS PAINT AND BODY SHOP (Continued) **1004784484**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19850720
Handler Name: DONS PAINT BODY SHOP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010127
Handler Name: DONS PAINT AND BODY SHOP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160114
Handler Name: DONS PAINT AND BODY SHOP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

FINDS:

Registry ID: 110005084210

DONS PAINT AND BODY SHOP (Continued) **1004784484**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company names, addresses, and telephone numbers of those the TCEQ regulates. It also contains additional IDs (permits, registrations, authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004784484
Registry ID:	110005084210
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005084210
Name:	DONS PAINT AND BODY SHOP
Address:	1006 W 12TH
City,State,Zip:	AUSTIN, TX 78703

SO3157 **SIGNATURE #9** **TX HIST UST** **S128728702**
NE **900 N I 35** **N/A**
1/8-1/4 **AUSTIN, TX**
0.249 mi.
1314 ft. **Site 2 of 2 in cluster SO**

Actual:
472 ft.

Focus Map:
11

HIST UST AUSTIN:

Name:	SIGNATURE #9
Address:	900 N I 35
City,State,Zip:	AUSTIN, TX
Id UST:	325
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TJ3158 **TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS** **RCRA-SQG** **1000156869**
WNW **1100 W 49TH ST** **PADS** **TXD980627228**
1/8-1/4 **AUSTIN, TX 78756**
0.249 mi.
1314 ft. **Site 1 of 3 in cluster TJ**

Actual:
668 ft.

Focus Map:
8

RCRA Listings:

Date Form Received by Agency:	20230615
Handler Name:	Texas Department Of Health Bureau Of Labs
Handler Address:	W 49TH ST
Handler City,State,Zip:	AUSTIN, TX 78756-3126
EPA ID:	TXD980627228

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Contact Name:	ISAAC SALAZAR
Contact Address:	PO BOX 149347
Contact City,State,Zip:	AUSTIN, TX 78714-9347
Contact Telephone:	512-458-7318
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 149347
Mailing City,State,Zip:	AUSTIN, TX 78714-9347
Owner Name:	Texas Department Of Health
Owner Type:	Private
Operator Name:	Texas Department Of Health
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2007

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D020
Waste Description:	Chlordane
Waste Code:	D022
Waste Description:	Chloroform
Waste Code:	D025
Waste Description:	P-Cresol
Waste Code:	D028
Waste Description:	1,2-Dichloroethane

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Waste Code: D032
Waste Description: Hexachlorobenzene

Waste Code: D033
Waste Description: Hexachlorobutadiene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: D043
Waste Description: Vinyl Chloride

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: U188

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Waste Description: Phenol

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH,
Legal Status: Other
Date Became Current: 20001128
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3126
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Not reported
Date Became Current: 20021030
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Date Became Current: 20091027
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH,
Legal Status: Other
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3126
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH,
Legal Status: Other
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20120222
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Owner/Operator Indicator: Owner
Owner/Operator Name: STATE OF TX
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20080429
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH,
Legal Status: Other
Date Became Current: 20001128
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20120222
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20001128
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3199
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20050315
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20051129
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Owner/Operator City,State,Zip: AUSTIN, TX 78756-3126
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Private
Date Became Current: 20070531
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756-3126
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20080429
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20091110
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other
Date Became Current: 20091027
Date Ended Current: Not reported
Owner/Operator Address: 1100 W 49TH ST
Owner/Operator City,State,Zip: AUSTIN, TX 78756
Owner/Operator Telephone: 512-458-7318
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: TEXAS DEPARTMENT OF HEALTH
Legal Status: Other

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Date Became Current:	20091110
Date Ended Current:	Not reported
Owner/Operator Address:	1100 W 49TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78756
Owner/Operator Telephone:	512-458-7318
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TEXAS DEPARTMENT OF HEALTH
Legal Status:	Private
Date Became Current:	20070531
Date Ended Current:	Not reported
Owner/Operator Address:	1100 W 49TH ST
Owner/Operator City,State,Zip:	AUSTIN, TX 78756-3101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19810928
Handler Name:	TEXAS DEPT OF HEALTH
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20021030
Handler Name:	TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20050315
Handler Name:	TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20051129
Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070605
Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080429
Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091027
Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091110

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110111
Handler Name: TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110215
Handler Name: TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120222
Handler Name: TEXAS DEPARTMENT OF HEALTH - BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220323
Handler Name: TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220323
Handler Name: TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20230615
Handler Name: TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19940914
Handler Name: TEXAS DEPARTMENT OF HEALTH LABORATORY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960301
Handler Name: TEXAS DEPT. OF HEALTH LAB
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Electronic Manifest Broker: Not reported

Receive Date: 19980125
Handler Name: BUREAU OF LABS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080301
Handler Name: TEXAS DEPARTMENT OF HEALTH
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92312
NAICS Description: ADMINISTRATION OF PUBLIC HEALTH PROGRAMS

NAICS Code: 923120
NAICS Description: ADMINISTRATION OF PUBLIC HEALTH PROGRAMS

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20040406
Actual Return to Compliance Date: 20040510
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20040422
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20040406
Actual Return to Compliance Date: 20040510
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 1
Date of Enforcement Action: 20040422
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: 11
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20040812
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20040406
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: 11

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **1000156869**

Actual Return to Compliance Date:	20040510
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20040406
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	11
Actual Return to Compliance Date:	20040510
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

PADS:

Name:	TEXAS DEPT OF HEALTH LAB.
Address:	1100 WEST 49TH STREET
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756
EDR ID:	1000156869
EPAID:	TXD980627228
Region:	06
Generator:	Y
Storer:	N
Disposer:	N
Transporter:	N
Smelter:	N
Research Facility:	N
Mailing Address:	1100 WEST 49TH STREET
Mailing Address 2:	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78756
Mailing Country:	US
Owner Name:	TEXAS DEPARTMENT OF HEALTH
Certification Date:	05/18/1995
Contact Name:	SHERRY CLAY
Contact Title:	Not reported
Contact Telephone:	512-458-7318
Contact Text:	Not reported
Contact Email:	Not reported

TJ3159 **TEXAS DEPARTMENT OF HEALTH NEW LAB** **TX AST** **A100348802**
WNW **1100 W 49TH ST** **N/A**
1/8-1/4 **AUSTIN, TX 78756**
0.249 mi.
1314 ft. **Site 2 of 3 in cluster TJ**

Actual:
668 ft.

Focus Map:
8

AST:

Name:	TEXAS DEPARTMENT OF HEALTH NEW LAB
Address:	1100 W 49TH ST
City,State,Zip:	AUSTIN, TX 787563126
Facility ID:	124329
Additional ID:	381365902010159
AI Number:	80102
Facility Type:	Not reported
Facility Begin Date:	12/01/2000
Facility Status:	ACTIVE
Facility Exempt Status:	N
Records Off-Site:	N
UST Financial Assurance Required:	N
Number of Active ASTs:	1
Site Location Description:	Not reported
Site Location (nearest city name):	Not reported
Site Location (county name):	TRAVIS
Site Location (TCEQ region):	11
Site Location (location zip):	78736
Contact Name/Title:	JONATHAN HICKMAN/ELEC SUPR
Contact Organization Name:	TEXAS DEPARTMENT OF HEALTH NEW LAB
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact CityStateZip:	Not reported
Contact Telephone:	5124634202
Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date on Earliest Reg Form:	11/05/2009
Signature First Name on Earliest Reg Form:	JOHATHAN
Application Received Date on Earliest Reg Form:	11/09/2009
Signature Middle Name on Earliest Reg Form:	Not reported
Signature Last Name on Earliest Reg Form:	HICKMAN
Signature Title on Earliest Reg Form:	ELEC SUPR
Signature Role on Earliest Reg Form:	OWNER
Signature Company on Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported
Enforcement Action Date:	Not reported

Facility:

Facility ID:	124329
Tank ID:	1
AST ID:	212867
AI Number:	80102
Install Date:	12/01/2000
Tank Registration Date:	11/09/2009
Mult Comp:	N
Tank Status:	IN USE
Tank Status Date:	12/01/2000
Tank Reg Status:	FULLY REGULATED
Tank Capacity:	2183

TEXAS DEPARTMENT OF HEALTH NEW LAB (Continued) **A100348802**

Substance:	DIESEL
Other Substance B:	Not reported
Other Substance C:	Not reported
Steel:	Y
Fiber:	N
Aluminum:	N
Metal:	N
Concrete:	N
Dike:	N
Liner:	N
Contains CO:	N
Contains NO:	N
Vapor Rec:	Not reported
Inst Stage Date:	Not reported

TJ3160 **TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS** **TX SPILLS** **S103606317**
WNW **1100 W 49TH ST** **TX ASBESTOS** **N/A**
1/8-1/4 **AUSTIN, TX 78756** **TX Ind. Haz Waste**
0.249 mi.
1314 ft. **Site 3 of 3 in cluster TJ**

Actual:
668 ft.

Focus Map:
8

SPILLS:

Name:	1100 W49TH AUSTIN
Address:	1100 W49TH AUSTIN
City,State,Zip:	AUSTIN, TX
Incident Number:	Not reported
Facility Id:	Not reported
Date of Spill:	03/16/1993
Seq Num:	Not reported
Responsible Party Name:	TEXAS DEPT. OF HEALTH
Responsible Party Address:	1100 W 49TH
Responsible Party City:	AUSTIN
Responsible Party State:	TX
Responsible Party Zip:	999999999
Responsible Party Telephone:	4587318
Substance:	DIESEL
Material Code:	9000
Media Affected:	Not reported
Permit Number:	NONE
District:	14
Origin:	005
Cause:	004
Basin Code:	0000
Notify Date:	Not reported
Adequate Clean:	001
Classification:	003
Basin Name:	NONE
Water Affected:	NONE
Amnt Spilled:	UNK LBS
Amnt in Water:	NONE LBS
Latitude:	Not reported
Longitude:	Not reported
Inspected By:	NONE
Interim Report:	Not reported
Enforce:	Not reported
Information Final:	X
Coordinator:	J. YOUNG

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Time Reported:	Not reported
Spill Time:	Not reported
Incident Type:	Not reported
Near City Name:	Not reported
Importance Level:	Not reported
Received Date:	Not reported
Start Date:	Not reported
Status Date:	Not reported
Media Name:	Not reported
Customer:	Not reported
Effect:	Not reported
Num Complaining:	Not reported
Frequency:	Not reported
Nature:	Not reported
Watertext:	Not reported
Air Text:	Not reported
Incident Status:	Not reported
Disputed Status:	Not reported
Disputed Date:	Not reported
Comments:	Not reported
Incident Action:	Not reported
Incident Description:	Not reported
Invest Number:	Not reported
Invest Status:	Not reported
Customer Number:	Not reported

ASBESTOS:

Name:	DSHS TOWER
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	12/20/2015
Notification Number:	2015008533
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/04/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/04/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/19/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DHT 4TH FLOOR
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/05/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/14/2016
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2016003334
File Number:	8216
License Status Description:	Paid
Expiration Date:	05/15/2016
Original Date:	04/21/2016
Rank Effective Date:	04/21/2016
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	1305
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Fail
Inspection Number Grade:	0
Name:	DSHS TOWER BUILDING
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/06/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/24/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017003951
File Number:	20423
License Status Description:	Current
Expiration Date:	06/25/2017
Original Date:	05/23/2017
Rank Effective Date:	05/23/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Number:	6726
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	ROBERT BERNSTEIN BUILDING (RBB) - PENTHOUSE MECHANICAL ROOM
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	03/11/2019
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	11/01/2018
Notification Number:	2018007569
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/23/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/23/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Analytical Method:	PLM
Start Date:	11/01/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ROBERT BERNSTEIN BUILDING (RBB) - PENTHOUSE MECHANICAL ROOM
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	03/11/2019
Reason for Inspection:	Richard Ian Howes
Violation:	Not reported
Complaint Date:	10/24/2018
Notification Number:	2018007569
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/09/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Work Type Flag:	A
Certification Statement Date:	10/09/2018
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/24/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TEXAS STATE HEALTH SERVICES
Address:	1100 W. 49TH ST.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/11/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013004172
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	07/08/2013
Date Routed by Supervisor:	07/15/2013

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Routed to PSQA:	07/31/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS RECORDS BLDG R131
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/24/2015
Notification Number:	2015006675
ASB Priority:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/22/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/24/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS RECORDS BLDG R131
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/23/2015
Notification Number:	2015006675
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/15/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/09/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/23/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER T603 & T605
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78754
Date of inspection:	12/12/2015
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	12/13/2015
Notification Number:	2015006681
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/15/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/20/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/12/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER T603 & T605
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78754
Date of inspection:	12/12/2015
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	11/08/2015
Notification Number:	2015006681
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/16/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/22/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/07/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER T603 & T605
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78754
Date of inspection:	12/12/2015
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	11/15/2015
Notification Number:	2015006681
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/16/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/06/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/14/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name: DSHS TOWER T603 & T605

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78754
Date of inspection:	12/12/2015
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	11/22/2015
Notification Number:	2015006681
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/25/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/13/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	11
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/21/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER T601.5 & T601.6 CORRIDOR
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78754
Date of inspection:	12/12/2015
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/25/2015
Notification Number:	2015006681
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/15/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/09/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	8
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/24/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DHT - T407.4
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/24/2015
Notification Number:	2015006688
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/10/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/19/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/24/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DHT - T401.4
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/24/2015
Notification Number:	2015006688
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspector Name:	Not reported
Date Report Received:	10/15/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/09/2015
Certification Statement Phone:	210-485-8847
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/24/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - DR. ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	MITCH STOGNER
Violation:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Complaint Date:	05/20/2016
Notification Number:	2016003311
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/04/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/28/2016
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/20/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - DR. ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	MITCH STOGNER
Violation:	Not reported
Complaint Date:	04/29/2016
Notification Number:	2016003311
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/20/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/08/2016
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/29/2016

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DHT 4TH FLOOR
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	05/14/2016
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	05/15/2016
Notification Number:	2016003334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/13/2016

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	15
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DHT 4TH FLOOR
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	05/14/2016
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	05/15/2016
Notification Number:	2016003334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/21/2016
Certification Statement Phone:	210-336-8421
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DHT 4TH FLOOR
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	05/14/2016
Reason for Inspection:	Steve Daugherty
Violation:	Not reported
Complaint Date:	05/15/2016
Notification Number:	2016003334
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/21/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	04/21/2016
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	24
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	05/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Number Grade:	Not reported
Name:	DSHS TOWER BUILDING
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/24/2017
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	06/25/2017
Notification Number:	2017003951
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/16/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/16/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER BUILDING
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/24/2017
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	06/18/2017
Notification Number:	2017003951
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/02/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/17/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS TOWER BUILDING
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	06/24/2017
Reason for Inspection:	Mitch Stogner
Violation:	Not reported
Complaint Date:	06/18/2017
Notification Number:	2017003951
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/23/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	05/23/2017
Certification Statement Phone:	512-442-1122
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	14
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/17/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS-BUREAU OF VITAL RECORDS BLDG.
Address:	1100 W. 49TH ST.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	08/10/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013005722
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	08/30/2013
Date Routed by Supervisor:	09/05/2013
Date Routed to PSQA:	09/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS SERVICE BLDG.
Address:	1100 W. 49TH ST.
City,State,Zip:	AUSTIN, TX 78756

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date of inspection:	05/25/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013003737
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	01
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	06/18/2013
Date Routed by Supervisor:	07/02/2013
Date Routed to PSQA:	07/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TEXAS DEPT. OF STATE HEALTH SERVICES
Address:	1100 W. 49TH ST.
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	10/19/2013
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported
Notification Number:	2013007641
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	03
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	11/13/2013
Date Routed by Supervisor:	11/21/2013
Date Routed to PSQA:	11/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/11/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/23/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/23/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	06/30/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/26/2020

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/26/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/11/2020
Notification Number:	2020000082

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/26/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/26/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	142
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/11/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/17/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/17/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/11/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/20/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/20/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/11/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/05/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/05/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	02/28/2022
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	03/31/2020
Notification Number:	2020000082
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	01/06/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	233
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/11/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Name:	DSHS BUILDING G (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	GARY MORGAN
Violation:	Not reported
Complaint Date:	10/06/2015
Notification Number:	2015005437
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/26/2015
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/21/2015
Certification Statement Phone:	210-404-1220
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	09/05/2015
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/16/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/02/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	06/21/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/02/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Status:	Current
Amendo:	7
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	06/02/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	04/13/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/22/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Violation:	Not reported
Complaint Date:	04/27/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/22/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	03/22/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	04/20/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/29/2016
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Start Date:	04/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/04/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/29/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Certification Statement Date:	03/29/2016
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/20/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	04/27/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/05/2016
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/13/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/11/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/05/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/05/2016
Certification Statement Phone:	972-434-0800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/27/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/09/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/12/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/25/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/23/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/12/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/12/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/09/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/16/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/25/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/25/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/30/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/25/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/25/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/16/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	05/16/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/16/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/02/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	06/06/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	05/16/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	05/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	04/06/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/09/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/23/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	05/03/2016
Reason for Inspection:	Caitlin Griffin
Violation:	Not reported
Complaint Date:	04/20/2016
Notification Number:	2016002281
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Report Received:	03/09/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement/Demolition (Both)
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	03/09/2016
Certification Statement Phone:	281-846-3809
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	96
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/06/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS TOWER
Address:	1100 W. 49TH ST., T603 & T605
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	12/12/2015
Reason for Inspection:	Notified
Violation:	No
Complaint Date:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Number:	2015006681
ASB Priority:	Low
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	07
Init:	JM
Seq:	02
Facility Type:	Asbestos
Inspector Name:	Jorge Montemayor
Date Report Received:	01/13/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	02/04/2016
Date Reviewed by PSQA:	2016-02-04 00:00:00
Date Routed by Supervisor1:	02/04/2016
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS CENTRAL POWER PLANT
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Gary Morgan
Violation:	Not reported
Complaint Date:	08/26/2016
Notification Number:	2016006926
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/11/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/11/2016
Certification Statement Phone:	210-677-5549
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	08/25/2016
Client Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TDSHS CAMPUS CENTRAL POWER PLANT
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	03/27/2017
Reason for Inspection:	Chris Gonzales
Violation:	Not reported
Complaint Date:	03/16/2017
Notification Number:	2017001694
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/28/2017
Certification Statement Phone:	210-281-5379

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	03/15/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	TDSHS CAMPUS - BULIDINGS 400, 500 & 600
Address:	1100 WEST 49TH ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2016/05/03
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/03/2016
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2016002281
File Number:	7115
License Status Description:	Invoice Closed
Expiration Date:	06/21/2016
Original Date:	03/09/2016
Rank Effective Date:	03/09/2016
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	1037
Inspection Status:	Closed
Disposition:	0060 - Completed No Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	TDSHS CAMPUS CENTRAL POWER PLANT
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/03/27
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	03/27/2017
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017001694
File Number:	17987
License Status Description:	Paid
Expiration Date:	03/16/2017
Original Date:	02/28/2017
Rank Effective Date:	02/28/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	5653
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Name:	ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/22/2022
Notification Number:	2022006323
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/04/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/09/2022
Notification Number:	2022006323
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/11/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	11/05/2022
Notification Number:	2022006323
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/11/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/11/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/15/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	ROBERT BERNSTEIN BUILDING (RBB)
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	Not reported
Reason for Inspection:	Jimmy Stafford
Violation:	Not reported
Complaint Date:	10/14/2022
Notification Number:	2022006323
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/28/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/28/2022
Certification Statement Phone:	5122607171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/12/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Violation:	Not reported
Complaint Date:	12/10/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/06/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	16
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/06/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	304
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/11/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/05/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/05/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	134
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Start Date:	11/19/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/18/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/15/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Certification Statement Date:	11/15/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	169
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/26/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/25/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/21/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/21/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	169
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/28/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	02/08/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/27/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	11/27/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	169
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/05/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	02/15/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/04/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/04/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	169
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	03/15/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/28/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

ARU:	174
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	08/05/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	7
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	02/06/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	174
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	08/05/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/01/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	8
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/01/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	174
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	08/05/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/24/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	9
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/24/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	174
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	08/30/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	10
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/31/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	179
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	09/27/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/22/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	11

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/22/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	179
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	10/31/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Report Received:	09/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	12
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/06/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	179
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	12/31/2019

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/29/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	13
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/29/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	179
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	03/31/2020
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	14
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/31/2019
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	179
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	03/31/2020
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	15
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/31/2019
Certification Statement Phone:	512-576-2019

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	304
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/10/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DSHS BUILDING G
Address:	1100 WEST 49TH STREET
City,State,Zip:	AUSTIN, TX 78756
Date of inspection:	09/17/2020
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/11/2019
Notification Number:	2018008143
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/02/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/02/2018
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	134
Is this a phased abatement project?:	Y
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	11/19/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS
Address:	1100 W 49TH ST
City,State,Zip:	AUSTIN, TX 78756
Permit Number:	Not reported
Registration Number:	66101
Registration Initial Notification Date:	02/09/2011
Registration Last Amendment Date:	03/23/2022
EPA Identification:	TXD980627228
Primary NAICS Code:	923120
Status Change Date:	20110209
Land Type:	PRIVATE

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Description of Facility Site Location:	1100 W 49th Street, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	TEXAS DEPARTMENT OF HEALTH
Contact Name:	ISAAC SALAZAR
Contact Telephone Number:	512-4587318
Mailing Address:	PO BOX 149347
Mailing Address2:	MC 1947
Mailing City,State,Zip:	AUSTIN, TX 787149347
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21404
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220427
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	TEXAS DEPARTMENT OF HEALTH
Operator Address:	1100 W 49TH ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78756
Operator Country:	UNITED STA
Operator Telephone:	1-512-4587318
Operator Fax Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Operator Email:	Not reported
Operator Business Type:	State Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	TEXAS DEPARTMENT OF HEALTH
Owner Mailing Address:	1100 W 49TH ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78756
Owner Country:	UNITED STA
Owner Telephone:	1-512-4587318
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	State Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	23
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Explosion proof cider blo
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19930802
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	002
Unit Type Code:	13
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Tank equipped with an ele
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19930802
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	003
Unit Type Code:	14
Unit Status:	ACTIVE
Unit Regulatory Status:	13
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Paint storage room is 16.
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19930802
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported
Unit Number:	004
Unit Type Code:	18
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Unit Description:	Ten gallon tank filled wi
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19950816
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	005
Unit Type Code:	18
Unit Status:	ACTIVE
Unit Regulatory Status:	08
UIC Permit Number:	Not reported
Capacity:	Not reported
Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	121
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Ten gallon tank filled wi
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19950816
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Unit Number:	006
Unit Type Code:	23
Unit Status:	ACTIVE
Unit Regulatory Status:	05
UIC Permit Number:	Not reported
Capacity:	660
Capacity Measurement:	G
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	141
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Flammable materials stora
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	19981019
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1100 W 49TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4587318
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1100 W 49TH ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78756
Contact Phone:	1-512-4587318
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ISAAC SALAZAR
Contact Title:	SAFETY OFFICER
Contact Role:	PRICONT
Contact Address:	PO BOX 149347
Contact Address 2:	MC 1947
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78714
Contact Phone:	1-512-4587318
Contact Fax:	1-512-4587294
Contact Email:	Isaac.salazar@dshs.state.tx.us

Ind. Haz Waste:

Waste ID:	68282
Texas Waste Code:	Not reported
Texas Waste Code 2:	00014941
Waste Code Status:	ACTIVE
Waste Form:	494
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	PCB contaminated soil samples/sample testing/4-21-93
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Waste ID:	66161
Texas Waste Code:	Not reported
Texas Waste Code 2:	0002203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This waste consists of 90% acetone and 10% bleach. It is generated by the rabies
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Acetone/Bleach
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71697
Texas Waste Code:	Not reported
Texas Waste Code 2:	0003204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	70% Methanol and 30% methycene chloride. This waste is benerated by a HPLC proc
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HPLC MOBILE PHASE
Primary NAICS Code:	923120
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Waste ID:	66162
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004202H
Waste Code Status:	ACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Freon 113 used as a solvent in an extraction process in environmental chemistry.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Freon 113
Primary NAICS Code:	923120
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71698
Texas Waste Code:	Not reported
Texas Waste Code 2:	0005202H
Waste Code Status:	ACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent methylene chloride that is used as a solvent in the environmental chemistr
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Methylene chloride
Primary NAICS Code:	923120
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste ID:	46507
Texas Waste Code:	Not reported
Texas Waste Code 2:	0006211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This waste is petroleum ether which is used as a solvent in the environmental ch
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Petroleum Ether
Primary NAICS Code:	923120
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71699
Texas Waste Code:	Not reported
Texas Waste Code 2:	0007219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	67% Ethyl acetate & 33% TCA used in an extraction process in clinical chemistry.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	EPSDT WASTE
Primary NAICS Code:	923120
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	66164
Texas Waste Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Texas Waste Code 2:	0008106H
Waste Code Status:	ACTIVE
Waste Form:	106
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This aqueous waste is corrosive and contains mercury. It is generated by the kj
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Kjeldhal waste
Primary NAICS Code:	923120
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	46506
Texas Waste Code:	Not reported
Texas Waste Code 2:	00090031
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Outdated non-Hazardous chemicals & PCB contaminated oil, soil or liquids. Thisw
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Non-Hazardous Lab Packs
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	71703
Texas Waste Code:	Not reported
Texas Waste Code 2:	0010001H
Waste Code Status:	INACTIVE
Waste Form:	001
Waste Classification:	H
Waste is Radioactive:	0

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste Treated Off Site:	Not reported
Generators Waste Description:	This lab pak contains out dated chemicals & reagents. Generation of this waste
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Lab Pack-Old
Primary NAICS Code:	923120
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	46505
Texas Waste Code:	Not reported
Texas Waste Code 2:	0011003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	These mixed Lab packs may contain waste chemicals or environmental samplus submi
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Hazardous mixed Lab Packs
Primary NAICS Code:	923120

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71756
Texas Waste Code:	Not reported
Texas Waste Code 2:	0012004H
Waste Code Status:	INACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	We sometimes receive environmental samples that contain P or U listed materials.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Lab Pack acute waste.
Primary NAICS Code:	923120
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71758
Texas Waste Code:	Not reported
Texas Waste Code 2:	0013009H

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste Code Status:	INACTIVE
Waste Form:	009
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Environmental samples that are discarded after analysis.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Lab Pack Environmental samples.
Primary NAICS Code:	923120
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71500
Texas Waste Code:	Not reported
Texas Waste Code 2:	0014105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixture of H2S04, HCL and H20 resulting from collection of ACID Rinse of Glasswa
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	923120
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72938
Texas Waste Code:	Not reported
Texas Waste Code 2:	0015204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	A 50/50 mixture of methylene chloride and cyclohexane used in the extraction of
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Methylene chloride/cyclohexane
Primary NAICS Code:	923120
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	92170
Texas Waste Code:	Not reported
Texas Waste Code 2:	0016119H
Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste geenrated as a result of chloride analysis. It contains 5% Methanol, 95%w
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary NAICS Code:	923120
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	92477
Texas Waste Code:	Not reported
Texas Waste Code 2:	0017101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Generated by an HPLC procedure in the organic analysis section. Waste contains7
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Method 531.1 Waste
Primary NAICS Code:	923120
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	123105
Texas Waste Code:	Not reported
Texas Waste Code 2:	0018204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixture of 60methanol, 30methylene chloride and 10HCL. Generated by an HPLC pro
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HPLC mobile phase acidic

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary NAICS Code:	923120
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145827
Texas Waste Code:	Not reported
Texas Waste Code 2:	0019203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Gas chromatograph vials filled with hexane or methyl tert butyl ether or other f
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	GC vials-flammable liquid
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	145828
Texas Waste Code:	Not reported
Texas Waste Code 2:	0020117H
Waste Code Status:	ACTIVE
Waste Form:	117
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste mercury used in organic chemistry - to be redistilled & used again.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Company Waste ID:	Not reported
Primary NAICS Code:	923120
EPA Waste Form Code:	W117
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	146811
Texas Waste Code:	Not reported
Texas Waste Code 2:	00211021
Waste Code Status:	ACTIVE
Waste Form:	102
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	GC vials containing water and potential trace amounts of pesticides from Method5
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	531.1 vials
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	148215
Texas Waste Code:	Not reported
Texas Waste Code 2:	0022319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MERCURY CONTAMINATED GLASS - GENERATED BY ORGANIC CHEMISTRY
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HG/GLASS
Primary NAICS Code:	923120
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Waste ID:	155659
Texas Waste Code:	Not reported
Texas Waste Code 2:	0023319H
Waste Code Status:	ACTIVE
Waste Form:	319
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Light bulbs (HID) from changing bulbs
Standard Industrial Code:	94310
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	923120
EPA Waste Form Code:	W319
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	173370
Texas Waste Code:	Not reported
Texas Waste Code 2:	0024203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	ACETONE, METHYL-TERT-BUTYL-ETHER, METHANOL, ETHYL ACETATE, TOLUENE MIXTURE.recyc
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NONHALOGEN SOLVENT
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste ID:	176109
Texas Waste Code:	Not reported
Texas Waste Code 2:	0025103H
Waste Code Status:	ACTIVE
Waste Form:	103
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste Mercury Standards
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Hg Std. Waste
Primary NAICS Code:	923120
EPA Waste Form Code:	W103
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176930
Texas Waste Code:	Not reported
Texas Waste Code 2:	0027204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Mixture of halogenated/nonhalogenated solvents
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	waste solvent mix
Primary NAICS Code:	923120
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste ID:	190795
Texas Waste Code:	Not reported
Texas Waste Code 2:	0028203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	A mixture of spent ethanol solutions, formalin and ethyl acetate from testing i
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NBS/Parasit solvent
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	191514
Texas Waste Code:	Not reported
Texas Waste Code 2:	0029204H
Waste Code Status:	ACTIVE
Waste Form:	204
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste in vials generated from Method 525.2 and NIOSH for VOC's in air.
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MeCL2, EtAc,CS2
Primary NAICS Code:	923120
EPA Waste Form Code:	W204
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	196534
Texas Waste Code:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Texas Waste Code 2:	0030105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Haloacetic drinking water analysis waste
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	552.2
Primary NAICS Code:	923120
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	221077
Texas Waste Code:	Not reported
Texas Waste Code 2:	0031101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Method 531.1 and Method 552.2 waste combined in error.
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	531 1 552 2
Primary NAICS Code:	923120
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	431651
Texas Waste Code:	Not reported
Texas Waste Code 2:	0040203H
Waste Code Status:	ACTIVE
Waste Form:	203

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Organic Group-Non halogenated solvents (acetone, hexane, methanol, methyl-tert-b
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NON-HALOGENATED WAST
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	431653
Texas Waste Code:	Not reported
Texas Waste Code 2:	0041101H
Waste Code Status:	ACTIVE
Waste Form:	101
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	MagNA Pure 96 System Fluid (External)
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	MAGNA PURE 96 SYSTEM
Primary NAICS Code:	923120
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	431654
Texas Waste Code:	Not reported
Texas Waste Code 2:	0042105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Hydrofluoric Acid (HF) waste
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	HF WASTE
Primary NAICS Code:	923120
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	431652
Texas Waste Code:	Not reported
Texas Waste Code 2:	0043219H
Waste Code Status:	ACTIVE
Waste Form:	219
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Formamide-AMD
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	FORMAMIDE-AMD
Primary NAICS Code:	923120
EPA Waste Form Code:	W219
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	431655
Texas Waste Code:	Not reported
Texas Waste Code 2:	0044203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	NBS-LC MS/MS Flammable Waste (Methanol + Acetonitrile)
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	NBS-LC MS MS
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste ID:	66163
Texas Waste Code:	Not reported
Texas Waste Code 2:	10013081
Waste Code Status:	ACTIVE
Waste Form:	308
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty metal drum that contained water treatment chemicals or chemicals used by t
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Empty Metal Drums.
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	71759
Texas Waste Code:	Not reported
Texas Waste Code 2:	10024061
Waste Code Status:	ACTIVE
Waste Form:	406
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Empty fiber or plastic drum that contained water treatment chemicals, Printshop
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Empty Fiber or Plastic Drums.
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	72249
Texas Waste Code:	Not reported
Texas Waste Code 2:	1003002H
Waste Code Status:	ACTIVE
Waste Form:	002
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Generators Waste Description:	Waste generated as a result of a chemical spill of any of the waste codes listed
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Spill clean up debris
Primary NAICS Code:	923120
EPA Waste Form Code:	W002
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72763
Texas Waste Code:	Not reported
Texas Waste Code 2:	1004519H
Waste Code Status:	ACTIVE
Waste Form:	519
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	It is a mixture of water, dirt & glass fragments that was removed from aciddrain
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Acid line sludge
Primary NAICS Code:	923120
EPA Waste Form Code:	W519

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Reason Waste Form No Longer Gen: Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	72764
Texas Waste Code:	Not reported
Texas Waste Code 2:	10051101
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This waste consists of water & sludge that was removed during the process of cle
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Neutralization tank liquid
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	72766
Texas Waste Code:	Not reported
Texas Waste Code 2:	10065041
Waste Code Status:	ACTIVE
Waste Form:	504
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Sludge removed from acid neutralization tank. Consists of soil, ground glass an
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Neutralization tank sludge
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste ID:	77773
Texas Waste Code:	Not reported
Texas Waste Code 2:	10071101
Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Quaternary Ammonium-Cationic disinfectant solution that is not acceptable.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Double D Disinfectant waste
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	116658
Texas Waste Code:	Not reported
Texas Waste Code 2:	1008203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	This old drum was discovered in the power plant. It was analyzed by the TDH lab
Standard Industrial Code:	94310
Primary Source:	G19
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Power plant drum
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	140983
Texas Waste Code:	Not reported
Texas Waste Code 2:	1009110H

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste Code Status:	INACTIVE
Waste Form:	110
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Quaternary ammonia-cationic disinfectant solution that is not acceptable because
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	923120
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71760
Texas Waste Code:	Not reported
Texas Waste Code 2:	2001105H
Waste Code Status:	ACTIVE
Waste Form:	105
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Acidic Aqueous waste treated in the neturalization tank prior to entering the sa
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Acidic Aqueous waste.
Primary NAICS Code:	923120
EPA Waste Form Code:	W105
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71761
Texas Waste Code:	Not reported
Texas Waste Code 2:	2002110H
Waste Code Status:	ACTIVE
Waste Form:	110
Waste Classification:	H

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Caustic aqueous waste treated in neturalization tank prior to entering the sanit
Standard Industrial Code:	94310
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Caustic Aqueous waste.
Primary NAICS Code:	923120
EPA Waste Form Code:	W110
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	91200
Texas Waste Code:	Not reported
Texas Waste Code 2:	20031191
Waste Code Status:	INACTIVE
Waste Form:	119
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Class one waste resulting from the treatment of aqueous acidic and caustic waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Waste ID:	66165
Texas Waste Code:	Not reported
Texas Waste Code 2:	5001209H
Waste Code Status:	ACTIVE
Waste Form:	209
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Waste paint generated by the general services division..
Standard Industrial Code:	94310
Primary Source:	G06
Primary Measurement Point:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste Paint
Primary NAICS Code:	923120
EPA Waste Form Code:	W209
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	71762
Texas Waste Code:	Not reported
Texas Waste Code 2:	5002211H
Waste Code Status:	ACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent paint thinner generated by division of general services.
Standard Industrial Code:	94310
Primary Source:	G06
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Paint Thinner.
Primary NAICS Code:	923120
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	135043
Texas Waste Code:	Not reported
Texas Waste Code 2:	50033101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Used oil filters.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Used oil filters
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	135386
Texas Waste Code:	Not reported
Texas Waste Code 2:	50044091
Waste Code Status:	ACTIVE
Waste Form:	409
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Herbicide that is no longer used.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	71764
Texas Waste Code:	Not reported
Texas Waste Code 2:	6001198H
Waste Code Status:	INACTIVE
Waste Form:	198
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Aqueous waste containing silver.
Standard Industrial Code:	27520
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Itex Fixer.
Primary NAICS Code:	323110
EPA Waste Form Code:	W113
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Waste ID:	134738
Texas Waste Code:	Not reported
Texas Waste Code 2:	60026041
Waste Code Status:	ACTIVE
Waste Form:	604
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Printing press ink. We began collection of this waste for offsite disposal: Ju
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	135385
Texas Waste Code:	Not reported
Texas Waste Code 2:	6003202H
Waste Code Status:	ACTIVE
Waste Form:	202
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Outdated film cleaner.
Standard Industrial Code:	94310
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	923120
EPA Waste Form Code:	W202
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176931
Texas Waste Code:	Not reported
Texas Waste Code 2:	6004119H

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Waste Code Status:	ACTIVE
Waste Form:	119
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Spent fixer from photo processor, contains silver.
Standard Industrial Code:	94310
Primary Source:	G07
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Itek Fixer
Primary NAICS Code:	923120
EPA Waste Form Code:	W119
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	176932
Texas Waste Code:	Not reported
Texas Waste Code 2:	60053101
Waste Code Status:	ACTIVE
Waste Form:	310
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Absorbent pigs used to soak up machine oil leaks.
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Absorbent "pigs"
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	186085
Texas Waste Code:	Not reported
Texas Waste Code 2:	6006203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Blanket wash for printing presses; Due to change(s) in the product produced, thi
Standard Industrial Code:	94310

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Waste Wash V120
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	PRODUCT CHANGE

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	328093
Texas Waste Code:	Not reported
Texas Waste Code 2:	6007004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	Disposal of reactive cyanide salts/chemicals by lab packs due to changes of proc
Standard Industrial Code:	Not reported
Primary Source:	G11
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ACUTEHAZARDOUSWASTE
Primary NAICS Code:	923120
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	350385
Texas Waste Code:	Not reported
Texas Waste Code 2:	6008004H
Waste Code Status:	ACTIVE
Waste Form:	004
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	Not reported
Generators Waste Description:	We receive samples that contain P listed materials. These samples may be submit
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	CYANIDE SOLUTIONS
Primary NAICS Code:	923120
EPA Waste Form Code:	W004
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	390448
Texas Waste Code:	Not reported
Texas Waste Code 2:	6009203H
Waste Code Status:	ACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	This waste is generated from NBS-Galt testing.
Standard Industrial Code:	Not reported
Primary Source:	G22
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	SPENT ETHANOL WATER
Primary NAICS Code:	923120
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

TEXAS DEPARTMENT OF HEALTH BUREAU OF LABS (Continued) **S103606317**

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1100 W 49TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78756
AR Number:	0000301752
Principal Name:	TEXAS DEPARTMENT OF HEALTH
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	1100 W 49TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78756
AR Number:	0000301752
Principal Name:	TEXAS DEPARTMENT OF HEALTH
Attention Name:	Not reported
Attention Suffix:	NWG

SY3161 **DOLLAR CAR RENTAL** **TX HIST UST** **S128728857**
WNW **9301 RENTAL CAR LN** **N/A**
1/8-1/4 **AUSTIN, TX**
0.250 mi.
1320 ft. **Site 5 of 5 in cluster SY**

Actual:
509 ft.

Focus Map:
20

HIST UST AUSTIN:

Name:	DOLLAR CAR RENTAL
Address:	9301 RENTAL CAR LN
City,State,Zip:	AUSTIN, TX
Id UST:	A0028
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TK3162 **MONTOPOLIS GROCERY** **TX RDR** **S126577749**
NNE **1211 MONTOPOLIS DR** **TX CENTRAL REGISTRY** **N/A**
1/4-1/2 **AUSTIN, TX 78741**
0.252 mi.
1331 ft. **Site 1 of 2 in cluster TK**

Actual:
490 ft.

Focus Map:
15

RDR:

RDR ID:	32265
Facility ID:	19621
RN:	102390580
CN:	600750186
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/25/2022
Due Date:	12/24/2022

MONTOPOLIS GROCERY (Continued) **S126577749**

Tank Owner:	OFLP-2 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	12/9/2022
Project Manager:	Meagan Kunze-Nevarez
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	31540
Facility ID:	19621
RN:	102390580
CN:	605646710
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/24/2022
Due Date:	4/25/2022
Tank Owner:	V&S ENTERPRISES LC
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	4/25/2022
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102390580
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3434
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600733729
Customer Name:	OLIVER, GUY

MONTOPOLIS GROCERY (Continued) **S126577749**

Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	2/1/2001
Affiliation End Date:	8/7/2012 1
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102390580
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3434
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600750186
Customer Name:	OFLP-2 LTD
Customer Legal Name:	Oflp-2, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/8/1994
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102390580
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3434
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN600787402
Customer Name:	GP LEASING CO
Customer Legal Name:	GP Leasing, Co.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/5/1986
Affiliation End Date:	9/7/1994 1
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102390580
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3434
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN603661398
Customer Name:	MTG MANAGEMENT INC
Customer Legal Name:	MTG MANAGEMENT, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/8/2012

MONTOPOLIS GROCERY (Continued) **S126577749**

Affiliation End Date:	3/31/2019
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102390580
Name:	MONTOPOLIS GROCERY
Address:	1211 MONTOPOLIS DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78741-3434
Status:	ACTIVE
Status Date:	5/30/2002
Customer Number:	CN605646710
Customer Name:	V&S ENTERPRISES LC
Customer Legal Name:	V&S Enterprises, LC
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	4/1/2019
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

3163 **SIGNATURE 9** **TX LPST** **U001267911**
NE **900 EAST AVE** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78701** **TX Financial Assurance**
0.256 mi. **TX RDR**
1352 ft.

Actual:
471 ft.

Focus Map:
11

LPST:

Name:	SHOPPERS MART 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0034918
LPST Id:	096329
Facility Location:	900 EAST AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/03/1990
Entered Date:	08/03/1990
Reported Date:	07/03/1990
Closure Date:	03/07/1991
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	FORD SMITH
Responsible Party Address:	PO BOX 6156
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	512/385-2020
Reported Date:	07/03/1990
Case Start Date:	03/07/1991
Reference Number:	RN104162466

SIGNATURE 9 (Continued) **U001267911**

Project Manager: HWELCH

UST:

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 787012601
AI Number:	34918
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	579387842004054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	SIGNATURE 9
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123852020
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/06/2022
Signature Name/Title On Earliest Reg Form:	PAUL PEMBERTON,DIRECTOR
Application Received Date On Earliest Reg Form:	09/09/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	365520692002075
Additional ID:	579387842004054
Ai Number:	34918
Operator CN:	CN600918452
Operator Name:	TEXAS ENTERPRISES INC
Operator Effective Begin Date:	05/14/2012
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	BROCK ISBELL/SITE REP
Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	2702 INDUSTRIAL BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ABILENE TX 79605-7213
Contact Phone Country Code:	1
Contact Phone Area Code:	325
Contact Phone Number:	6950150
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600918452
Owner Last Name:	TEXAS ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6156
Contact Phone Number/Ext:	1 512 3852020/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	365520692002075
Additional ID:	579387842004054
AI Number:	34918
Owner Effective Begin Date:	05/14/2012
State Tax ID:	17418588749
Contact Role:	OWNOPRCON
Contact Name/Title:	PAUL PEMBERTON/
Contact Organization Name:	TEXAS ENTERPRISES INC

Self Certification:

Self Cert ID:	77354
Cert ID:	376651
AI Number:	34918
Self Certification Date:	09/06/2022
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	358221
AI Number:	34918
Self Certification Date:	08/02/2021
Signature Name/Title:	PAUL PEMBERTON DIRECTOR

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	343137
AI Number:	34918
Self Certification Date:	08/28/2020
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	324435
AI Number:	34918
Self Certification Date:	07/30/2019
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	308576
AI Number:	34918
Self Certification Date:	08/21/2018
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMPLIANCE

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	292038
AI Number:	34918
Self Certification Date:	08/23/2017
Signature Name/Title:	PAUL PEMBERTON DIR OF ENVIRONMENTAL COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	274757
AI Number:	34918
Self Certification Date:	08/08/2016
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	259987
AI Number:	34918
Self Certification Date:	08/27/2015
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	242159
AI Number:	34918
Self Certification Date:	07/24/2014
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	224740
AI Number:	34918
Self Certification Date:	08/15/2013
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77354
Cert ID:	115364
AI Number:	34918
Self Certification Date:	06/29/2012
Signature Name/Title:	FORD SMITH PRESIDENT

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115363
AI Number:	34918
Self Certification Date:	05/31/2012
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115362
AI Number:	34918
Self Certification Date:	06/08/2011
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115361
AI Number:	34918
Self Certification Date:	06/29/2010
Signature Name/Title:	FORD SMITH PRES

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115360
AI Number:	34918
Self Certification Date:	06/09/2009
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115359
AI Number:	34918
Self Certification Date:	05/16/2008
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115358
AI Number:	34918
Self Certification Date:	05/18/2007
Signature Name/Title:	FORD SMITH JR PRES

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115357
AI Number:	34918
Self Certification Date:	07/01/2006
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115356
AI Number:	34918
Self Certification Date:	06/23/2005
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115355
AI Number:	34918
Self Certification Date:	06/24/2004
Signature Name/Title:	ALLEN W SMITH PRES

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115354
AI Number:	34918
Self Certification Date:	06/30/2003
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115353
AI Number:	34918
Self Certification Date:	06/06/2002
Signature Name/Title:	ALLEN W SMITH
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115352
AI Number:	34918
Self Certification Date:	04/04/2001
Signature Name/Title:	ALLEN SMITH PRESIDENT

SIGNATURE 9 (Continued) **U001267911**

Signature Type Role:	OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115351
AI Number:	34918
Self Certification Date:	04/03/2001
Signature Name/Title:	ALLEN SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77354
Cert ID:	115350
AI Number:	34918
Self Certification Date:	12/19/2000
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000

SIGNATURE 9 (Continued) **U001267911**

Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92282
Facility ID:	77354
Ai Number:	34918
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/07/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N

SIGNATURE 9 (Continued) **U001267911**

Installation Signature Date:	06/20/1990
Compartment Records:	
Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	120113
UST ID:	92282
AI Number:	34918
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92283
Facility ID:	77354
Ai Number:	34918
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND

SIGNATURE 9 (Continued) **U001267911**

Tank Status Date:	03/07/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	120114
UST ID:	92283
AI Number:	34918
Compartment ID:	A

SIGNATURE 9 (Continued) **U001267911**

Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1982
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92284
Facility ID:	77354
Ai Number:	34918
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/07/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

SIGNATURE 9 (Continued) **U001267911**

Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	120115
UST ID:	92284
AI Number:	34918
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

SIGNATURE 9 (Continued) **U001267911**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	92285
Facility ID:	77354
Ai Number:	34918
Tank Id:	4A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N

SIGNATURE 9 (Continued) **U001267911**

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	4A
Tank Capacity:	6000
UST Comprt ID:	120116
UST ID:	92285
AI Number:	34918
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N

SIGNATURE 9 (Continued) **U001267911**

PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/01/1990
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92286
Facility ID:	77354
Ai Number:	34918
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	07/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N

SIGNATURE 9 (Continued) **U001267911**

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	120117
UST ID:	92286
AI Number:	34918
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N

SIGNATURE 9 (Continued) **U001267911**

SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	03/09/2001
Tank Registration Date:	04/04/2001
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196674
Facility ID:	77354
Ai Number:	34918
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	03/09/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

SIGNATURE 9 (Continued) **U001267911**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/02/2001

Compartment Records:

Tank ID:	5
Tank Capacity:	8000
UST Comprt ID:	120118
UST ID:	196674
AI Number:	34918
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

SIGNATURE 9 (Continued) **U001267911**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/11/2001
Install Date:	03/09/2001
Tank Registration Date:	04/04/2001
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196675
Facility ID:	77354
Ai Number:	34918
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	03/09/2001
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

SIGNATURE 9 (Continued) **U001267911**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/02/2001

Compartment Records:

Tank ID:	6
Tank Capacity:	8000
UST Comprt ID:	120119
UST ID:	196675
AI Number:	34918
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/11/2001

Construction Notification:

NOC ID:	24680

SIGNATURE 9 (Continued) **U001267911**

Facility ID:	77354
AI Number:	34918
Application Received Date:	09/13/2013
Scheduled Construction Date:	09/23/2013
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	09/13/2013
Signature Date On Form:	09/13/2013
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	TEXAS ENTERPRISES INC
Owner CN At Time Of Construction:	CN600918452
Owner AR At Time Of Construction:	18379
General Desc Of Prop Construct:	REPLACE DIESEL SPILL BUCKET

NOC ID:	10911
Facility ID:	77354
AI Number:	34918
Application Received Date:	02/21/2001
Scheduled Construction Date:	03/01/2001
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10221002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	09/13/2013
Signature Date On Form:	09/13/2013
Signature Name On Form:	BRENT PEFFER
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22907
General Desc Of Prop Construct:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	57842
UST ID:	Not reported
NOC ID:	24680
AI Number:	34918
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH ROAD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	30085
UST ID:	196674
NOC ID:	Not reported
AI Number:	34918
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	30086
UST ID:	196675
NOC ID:	Not reported
AI Number:	34918
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	11741
UST ID:	Not reported
NOC ID:	10911
AI Number:	34918
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45247
UST ID:	196674
NOC ID:	Not reported
AI Number:	34918
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000317
Company Name:	Not reported
Representative Name:	LARRY ALBERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45248
UST ID:	196675
NOC ID:	Not reported
AI Number:	34918
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000317
Company Name:	Not reported
Representative Name:	LARRY ALBERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77354
Additional ID:	579387842004054
Princ ID:	365520692002075
AI Number:	34918
Facility Name:	SIGNATURE 9
AR Number:	18379
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PAUL PEMBERTON/

TX Financial Assurance 2:

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2

SIGNATURE 9 (Continued) **U001267911**

Facility ID:	77354
Finass ID:	274451
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2022
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000028792
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	254976
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2021
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000019174
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	237527
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

SIGNATURE 9 (Continued) **U001267911**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2020
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000010223
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	218114
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2019
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-005000860
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	202035
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2018
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2019
Ins Premium Pre-Paid For Entire Yr:	No

SIGNATURE 9 (Continued) **U001267911**

Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	185163
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2017
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	167102
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2016
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	151558
AI:	34918

SIGNATURE 9 (Continued) **U001267911**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2015
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	133277
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2014
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	114321
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2013
Date Financial Assurance Form Rec:	09/09/2022

SIGNATURE 9 (Continued) **U001267911**

Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	10316
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2012
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 0 0
Policy Number:	9989929
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/14/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	62929
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2011
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9

SIGNATURE 9 (Continued) **U001267911**

Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	62930
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2010
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	62931
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2009
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	62932
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2008
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	77354
Finass ID:	61352
AI:	34918
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/1994
Date Financial Assurance Form Rec:	09/09/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	28238
Facility ID:	34918
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/14/2020
Due Date:	4/14/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	3/31/2020
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	28531
Facility ID:	34918
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/12/2020
Due Date:	7/11/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	SUSPECTED RELEASE
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	7/6/2020
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	27934
Facility ID:	34918
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 9
Address:	900 EAST AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/13/2019
Due Date:	2/11/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/6/2020
Project Manager:	Todd Hammitt
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported

SIGNATURE 9 (Continued) **U001267911**

Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TF3164 **AUSTIN ISD SNEED** **TX LPST** **S102754163**
ESE **5901 GUADALUPE ST** **TX Ind. Haz Waste** **N/A**
1/4-1/2 **AUSTIN, TX 78752**
0.259 mi.
1367 ft. **Site 4 of 4 in cluster TF**

Actual:
662 ft.

Focus Map:
9

LPST:

Name:	SNEAD BUS BARN
Address:	5901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0048091
LPST Id:	101331
Facility Location:	5901 GUADALUPE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/16/1991
Entered Date:	01/21/1992
Reported Date:	12/16/1991
Closure Date:	07/29/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	RICHARD HALL
Responsible Party Address:	PO BOX 4087
Responsible Party City,St,Zip:	AUSTIN, TX 78773
Responsible Party Telephone:	512/465-2167
Reported Date:	12/16/1991
Case Start Date:	07/29/1992
Reference Number:	RN100597277
Project Manager:	HWELCH

Ind. Haz Waste:

Name:	AUSTIN ISD SNEED
Address:	5901 GUADALUPE ST
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	72386
Registration Initial Notification Date:	05/01/1987
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981901671
Primary NAICS Code:	Not reported
Status Change Date:	19870501
Land Type:	Not reported

AUSTIN ISD SNEED (Continued) **S102754163**

Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	Not reported
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Contact Name:	FRED FILLEY
Contact Telephone Number:	512-9267940
Mailing Address:	1135 GUNTER ST
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787023169
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	26827
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20021108
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT
Operator Address:	1135 GUNTER ST
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78702
Operator Country:	UNITED STA
Operator Telephone:	1-512-9267940
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Local Government
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	AUSTIN INDEPENDENT SCHOOL DISTRICT

AUSTIN ISD SNEED (Continued) **S102754163**

Owner Mailing Address:	1135 GUNTER ST
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78702
Owner Country:	UNITED STA
Owner Telephone:	1-512-9267940
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Local Government
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1135 GUNTER ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-9267940
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1135 GUNTER ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-9267940
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	FRED FILLEY
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	1135 GUNTER ST
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78702
Contact Phone:	1-512-9267940
Contact Fax:	Not reported
Contact Email:	Not reported

3165 **LOPEZ PROPERTY** **US BROWNFIELDS** **1018163921**
ENE **809 E.9TH STREET** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.268 mi.
1416 ft.

Actual:
534 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of

LOPEZ PROPERTY (Continued) **1018163921**

Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8686
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001

LOPEZ PROPERTY (Continued) **1018163921**

Start Date:	1/15/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95

LOPEZ PROPERTY (Continued) **1018163921**

Unemployed Number:	117
Unemployed Percent:	5.06
Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2695
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	1/30/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446

LOPEZ PROPERTY (Continued) **1018163921**

Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Assessment Funding:	2695
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	1/30/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street

LOPEZ PROPERTY (Continued) **1018163921**

	was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06
Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10402
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	7/15/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900.

LOPEZ PROPERTY (Continued) **1018163921**

Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.

Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is

LOPEZ PROPERTY (Continued) **1018163921**

	covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8686
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	1/15/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06
Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is

LOPEZ PROPERTY (Continued) **1018163921**

located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.

Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10402
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	7/15/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a

LOPEZ PROPERTY (Continued) **1018163921**

residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.

Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2695
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	1/30/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials

LOPEZ PROPERTY (Continued) **1018163921**

Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have

LOPEZ PROPERTY (Continued) **1018163921**

impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.

Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6838
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	7/15/2015
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

LOPEZ PROPERTY (Continued) **1018163921**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station

LOPEZ PROPERTY (Continued) **1018163921**

Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4141
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	4/24/2015
Ownership Entity:	Private
Completion Date:	6/1/2015
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N

LOPEZ PROPERTY (Continued) **1018163921**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2896
Assessment Funding Source:	City of Austin
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	1/30/2015
Ownership Entity:	Private
Completion Date:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446
Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

LOPEZ PROPERTY (Continued) **1018163921**

Click this hyperlink while viewing on your computer to access
41 additional US BROWNFIELDS: record(s) in the EDR Site Report.

Name:	LOPEZ PROPERTY
Address:	809 E.9TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.17
Latitude:	30.268062
Longitude:	-97.732878
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	An historic single-family home had lead-based paint and asbestos containing materials removed and was renovated. The remainder of the property will be redeveloped as affordable housing for the elderly, with an estimated 12 apartments. There were initial concerns that an offsite leaking petroleum storage tank at a former gas station may have impacted the property. Although somewhat unlikely to have impacted the site due to the hill the site is located on, a monitor well was installed to make the determination whether the groundwater was impacted, and if so, whether the indoor air quality was affected. No groundwater was encountered at a depth of 30 feet. No evidence of impact was discovered. No other recognized environmental concerns existed at the site. Former Use: The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Datum:	North American Datum of 1983
Acres Property ID:	184541
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1790
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported

LOPEZ PROPERTY (Continued) **1018163921**

Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Cleanup Planning
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	7/6/2015
Ownership Entity:	Private
Completion Date:	8/31/2015
Current Owner:	Guadalupe Neighborhood Development Corporation
Did Owner Change:	Y
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.17
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.17
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property is currently a residential lot with a one-story house being the only structure on the site. The house is boarded up and has been vacant since 2010 after an electrical fire damaged the south end of the residence. A dirt crawl-space is located beneath the house. The house is believed to have been built around the year 1900. Access to the subject property is provided by East 9th Street. The subject property is located on the south side of East 9th Street where the street dead-ends into the easternmost IH-35 right-of-way. To the west of the subject property is a grassy embankment that slopes steeply down to the IH-35 access road. No other public thoroughfares adjoin the site. A short asphalt driveway connected to East 9th Street was observed on the north side of the property. The remainder of the property is covered in grasses/vegetation. According to the property owner, a second structure (an apartment) was formerly located on the south half of the property. This building was reportedly torn down in 2012.
Below Poverty Number:	446

LOPEZ PROPERTY (Continued) **1018163921**

Below Poverty Percent:	19.3
Meidan Income:	6589
Meidan Income Number:	638
Meidan Income Percent:	27.61
Vacant Housing Number:	195
Vacant Housing Percent:	14.95
Unemployed Number:	117
Unemployed Percent:	5.06

Click this hyperlink while viewing on your computer to access
41 additional US BROWNFIELDS: record(s) in the EDR Site Report.

3166 ESE 1/4-1/2 0.269 mi. 1421 ft. | **BUTCH WOOTEN INVESTMENT MOTORS** | **TX LPST** | **S116696766**
315 E SAINT ELMO RD | **N/A**
AUSTIN, TX 78704

Actual: 661 ft.

Focus Map: 18

LPST:

Name:	BUTCH WOOTEN INVESTMENT MOTORS
Address:	315 E SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0043179
LPST Id:	104781
Facility Location:	315 EAST SAINT ELMO
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/18/1992
Entered Date:	10/28/1992
Reported Date:	09/18/1992
Closure Date:	11/24/1992
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	LELAND EVERETT
Responsible Party Address:	4502 GREENBRIAR COURT
Responsible Party City,St,Zip:	AUSTIN, TX 78758
Responsible Party Telephone:	/-
Reported Date:	09/18/1992
Case Start Date:	11/24/1992
Reference Number:	RN101493872
Project Manager:	HWELCH

TK3167 **MONTOPOLIS PARK** **US BROWNFIELDS** **1023620237**
NNE **1200 MONTOPOLIS** **FINDS** **N/A**
1/4-1/2 **AUSTIN, TX 78741**
0.271 mi.
1431 ft. **Site 2 of 2 in cluster TK**

Actual:
489 ft.

Focus Map:
15

US BROWNFIELDS:

Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to

MONTOPOLIS PARK (Continued) **1023620237**

	EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020
Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F91001
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater

MONTOPOLIS PARK (Continued) **1023620237**

assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3059
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	12/12/2016
Ownership Entity:	Government
Completion Date:	12/29/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin

MONTOPOLIS PARK (Continued) **1023620237**

Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1175
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Cleanup Planning
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	5/1/2019
Ownership Entity:	Government
Completion Date:	7/31/2019
Current Owner:	City of Austin
Did Owner Change:	N

MONTOPOLIS PARK (Continued) **1023620237**

Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community

MONTOPOLIS PARK (Continued) **1023620237**

health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3059
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	12/12/2016
Ownership Entity:	Government
Completion Date:	12/29/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment

MONTOPOLIS PARK (Continued) **1023620237**

Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020
Datum:	North American Datum of 1983
Acres Property ID:	220002

MONTOPOLIS PARK (Continued) **1023620237**

IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3059
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	12/12/2016
Ownership Entity:	Government
Completion Date:	12/29/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45

MONTOPOLIS PARK (Continued) **1023620237**

Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81

Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of

MONTOPOLIS PARK (Continued) **1023620237**

	schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020
Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4488
Assessment Funding Source:	City of Austin Brownfields
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Supplemental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	5/1/2019
Ownership Entity:	Government
Completion Date:	7/31/2019
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A

MONTOPOLIS PARK (Continued) **1023620237**

groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	14764
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	12/12/2016
Ownership Entity:	Government
Completion Date:	12/29/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved

MONTOPOLIS PARK (Continued) **1023620237**

recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1175
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Cleanup Planning
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	5/1/2019
Ownership Entity:	Government

MONTOPOLIS PARK (Continued) **1023620237**

Completion Date:	7/31/2019
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81

Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community

MONTOPOLIS PARK (Continued) **1023620237**

for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	9/18/2019
Redev Completition Date:	Not reported
Completed Date:	10/4/2019
Acres Cleaned Up:	6.43
Cleanup Funding:	163807.14
Cleanup Funding Source:	EPA
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported

MONTOPOLIS PARK (Continued) **1023620237**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Brownfields RLF Grant Funds Loaned
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Government
Completion Date:	Not reported
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81
Name:	MONTOPOLIS PARK

MONTOPOLIS PARK (Continued) **1023620237**

Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on

MONTOPOLIS PARK (Continued) **1023620237**

	January 3, 2020
Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	3059
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F91001
Start Date:	12/12/2016
Ownership Entity:	Government
Completion Date:	12/29/2016
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it

MONTOPOLIS PARK (Continued) **1023620237**

	was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81

Click this hyperlink while viewing on your computer to access
57 additional US BROWNFIELDS: record(s) in the EDR Site Report.

Name:	MONTOPOLIS PARK
Address:	1200 MONTOPOLIS
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	6.43
Latitude:	30.2322315
Longitude:	-97.6998813
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The Montopolis Recreation Center has served the East Austin community for more than four decades. Montopolis Recreation Center was originally owned by Dolores Catholic Church. The property consisted of two structures, a 14,400 sq. ft. recreation center and a community health care center, a swimming pool, parking lot and undeveloped land. In 1971, the City of Austin began operating the building as part of the Parks and Recreation Division (PARD) services. In 1973, PARD purchased the building and the surrounding land, with 2.55 acres of land dedicated for community use. After 40 years, the facility was in poor condition and no longer meeting the needs of a growing and vibrant community. Voters approved the updates in 2012, and broke ground on the project in 2018. With bond funding of just over $15 million, the extensive redevelopment will provide improved recreational opportunities in East Austin. The Montopolis Recreation + Community Center will jointly replace two aging facilities and be co-operated by the Austin Parks and Recreation Department and Austin Public Health Department. The revitalized center features 33,000 square feet of new space, including a commercial kitchen, multisport gymnasium, fitness room, track, teen space, computer lab, conference rooms, and educational programming areas. The building's design seeks to support the initiatives of each partnering department by fostering mental and physical well-being through community recreation and the pursuit of healthy lifes. Brownfields Assessment and Cleanup at Montopolis Recreation Center: The 2017 Phase I report indicated a need for more investigation of the historic off-site gas station. A groundwater monitoring well was installed, to determine if groundwater was impacted. No potential chemicals of concern were detected above regulatory levels. Following the groundwater assessment, the applicant requested an asbestos and lead-based paint survey of the Recreation Center. Contractors investigated the presence and extent of asbestos and lead based paint in the existing

MONTOPOLIS PARK (Continued) **1023620237**

building in January 2018. The survey confirmed the presence of asbestos and lead-based paint. Abatement and appropriate handling were recommended during demolition and renovation of the property. ABRO completed asbestos and lead-based paint surveys to determine the extent of contamination present in the buildings. Asbestos abatement took place September-October 2019 and was completed 2 weeks ahead of schedule. More information about the renovation is on the City of Austin Montopolis Recreation and Community Center Project website Grant Documents & Important Dates: * ABCA and CRP were submitted to EPA July 31, 2019 * The loan agreement (MOU) was signed August 1, 2019 * 30-day Public Notice was given in the Austin-American Statesman August 4 -September 2, 2019 * The QAPP was reviewed and approved September 10, 2019 * Notice was provided to DSHS September 3, 2019 * Abatement began September 20, 2019, and was completed October 04, 2019 * Final Report was submitted to ABRO from the QEP on January 3, 2020

Datum:	North American Datum of 1983
Acres Property ID:	220002
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	7318
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	01F37601
Start Date:	11/1/2017
Ownership Entity:	Government
Completion Date:	3/29/2018
Current Owner:	City of Austin
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Asbestos Lead

MONTOPOLIS PARK (Continued) **1023620237**

Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	6.43
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	6.43
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The recreation center was built in the mid 1960's. Prior to that, it was undeveloped land.
Below Poverty Number:	2984
Below Poverty Percent:	51.45
Meidan Income:	5124
Meidan Income Number:	4369
Meidan Income Percent:	75.33
Vacant Housing Number:	179
Vacant Housing Percent:	9.24
Unemployed Number:	221
Unemployed Percent:	3.81

Click this hyperlink while viewing on your computer to access
57 additional US BROWNFIELDS: record(s) in the EDR Site Report.

FINDS:
Registry ID: 110070057811

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

3168 NNE 1/4-1/2 0.273 mi. 1441 ft. | **AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FAC** | **TX SWF/LF** | **S106169045**
751 BASTROP HWY | **TX AIRS** | **N/A**
AUSTIN, TX 78746 | **TX COMP HIST**
TX CENTRAL REGISTRY

Actual: 455 ft.
Focus Map: 15

SWF/LF:

Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
City,State,Zip:	AUSTIN, TX 78746
Region:	11
Permit Number:	1324
Facility Status:	CLOSED
Facility Type:	5GG
Permit Status:	REVOKED
Status Date:	11/21/2008
Mailing Address:	Not reported

AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY (Continued) **S106169045**

Client Name: Not reported
Client Address: Not reported
Client Telephone: N/A
Business Type: INDIVIDUAL
Area Served: AUSTIN AREA
Estimated Closure Date: Not reported
Permit Acreage: 1
Permit Start: Not reported
Permit End: Not reported
Polution Served: 350000
Tons per Day: 29
Yards per Day: Not reported
Application: Not reported
Lat/Long: 30.24000 / -97.68000

Name: AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address: 751 BASTROP HWY
City,State,Zip: AUSTIN, TX 78746
Region: 11
Permit Number: 1324
Facility Status: CLOSED
Facility Type: 5GG
Permit Status: REVOKED
Status Date: 11/21/2008
Mailing Address: Not reported
Client Name: Not reported
Client Address: Not reported
Client Telephone: N/A
Business Type: INDIVIDUAL
Area Served: AUSTIN AREA
Estimated Closure Date: Not reported
Permit Acreage: 1
Permit Start: 09/30/2008
Permit End: 11/21/2008
Polution Served: 350000
Tons per Day: 29
Yards per Day: Not reported
Application: VOLUNTARY REVOCATION
Lat/Long: 30.24000 / -97.68000

AIRS:
Name: AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address: 751 BASTROP HWY
City,State,Zip: AUSTIN, TX
Permit Num: 11343
Regulated Id: RN102668050
Permit Type: EXEMPT
Permit Status: EFFECTIVE
Permit Issued Date: 01/01/1900
Expiration Date: 12/31/3000
Customer Id: CN601048788
Company Name: AUSTIN LIQUID DISPOSAL CO INC
Physical Location Desc: 300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN
Rep Official(RO): Not reported
RO Name: Not reported
RO Delivery Address: Not reported

AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY (Continued) **S106169045**

RO City/State/Zip:	Not reported
RO Phone:	Not reported
RO Ext Num:	Not reported
RO EMail Address:	Not reported
Lat Dec Coord Num:	30.239999
Long Dec Coord Num:	-97.680000

COMP HIST:

RN Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN601048788
CN Name:	AUSTIN LIQUID DISPOSAL CO INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	335311
SIC Code:	1542
Related Number:	11343,TH0160L,TH0160L

CENTRAL REGISTRY:

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601048788
Customer Name:	AUSTIN LIQUID DISPOSAL CO INC
Customer Legal Name:	Austin Liquid Disposal Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601048788
Customer Name:	AUSTIN LIQUID DISPOSAL CO INC

AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY (Continued) **S106169045**

Customer Legal Name:	Austin Liquid Disposal Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602680399
Customer Name:	JONES, JOHN T JR TRUST
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602680399
Customer Name:	JONES, JOHN T JR TRUST
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601048788
Customer Name:	AUSTIN LIQUID DISPOSAL CO INC

AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY (Continued) **S106169045**

Customer Legal Name:	Austin Liquid Disposal Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN601048788
Customer Name:	AUSTIN LIQUID DISPOSAL CO INC
Customer Legal Name:	Austin Liquid Disposal Co., Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602680399
Customer Name:	JONES, JOHN T JR TRUST
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

Regulated Entity Number:	RN102668050
Name:	AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY
Address:	751 BASTROP HWY
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78746-
Status:	ACTIVE
Status Date:	1/1/2001
Customer Number:	CN602680399
Customer Name:	JONES, JOHN T JR TRUST

AUSTIN LIQUID DISPOSAL LIQUID WASTE PROCESSING FACILITY (Continued) **S106169045**

Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	300 FEET EAST US HIGHWAY 183 .75 MILES SOUTH COLORADO RIVER 700 BLOCK BASTROP HIGHWAY SOUTH SOUTHEAST AUSTIN

TL3169 **HLD FOOD MART** **TX LPST** **S116698022**
WNW **1112 W KOENIG LN** **N/A**
1/4-1/2 **AUSTIN, TX 78756**
0.274 mi.
1449 ft. **Site 1 of 4 in cluster TL**

Actual:
672 ft.

Focus Map:
8

LPST:

Name:	HLD FOOD MART
Address:	1112 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0014326
LPST Id:	108443
Facility Location:	1112 KOENIG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/20/1994
Entered Date:	08/19/1994
Reported Date:	06/20/1994
Closure Date:	02/04/1997
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/2
Coordinators RPR:	ANTONIO PENA
Responsible Party Name:	Not reported
Responsible Party Contact:	JACK CECCARELLI
Responsible Party Address:	205 S HOOVER BLVD
Responsible Party City,St,Zip:	TAMPA, FL 33609 9905
Responsible Party Telephone:	813/636-8111
Reported Date:	06/20/1994
Case Start Date:	02/04/1997
Reference Number:	RN101699114
Project Manager:	ARP

3170 **AUSTIN EXECUTIVE AIRPARK** **TX VCP** **S123820376**
NE **811 W HOWARD LN** **N/A**
1/4-1/2 **AUSTIN, TX 78753**
0.275 mi.
1450 ft.

Actual:
763 ft.

Focus Map:
2

VCP TCEQ:

Name:	AUSTIN EXECUTIVE AIRPARK
Address:	811 W HOWARD LN
City,State,Zip:	AUSTIN, TX 78753

AUSTIN EXECUTIVE AIRPARK (Continued) **S123820376**

Region:	REGION 11 - AUSTIN
Facility ID:	941
VCP Record Date:	03/08/1999
Facility Type:	PROPERTY VACANT
PCA Number:	31841
Project Manager:	KDUDEK
Phase:	COMPLETED
Acres at Site:	103.32
REM Program:	VCP
RN Number:	RN101054823
Former Facility Type:	Not reported
Site Address Description:	FORMER AIRPORT NO LONGER EXISTS NOW REDEVELOPED
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	03/03/1999
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	TXD980879795
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/13/2000
Standards:	2
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	NOT REQUIRED
Air Target COC Class:	Not reported
Date Cashier Check Received:	03/03/1999
GW Target COC Class:	SVOCS; VOCS
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1999-04-01 00:00:00
Soil Target COC Class:	VOCS; SVOCS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	941
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	318410
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	215/D
Latitude:	30.42
Longitude:	-97.67

Contact:

REM Program:	VCP
Program ID:	941
RN Number:	RN101054823
CN Number:	CN600613970
CN Name:	CENTERLINE PARTNERS LP
Role Code:	BILLCONT

AUSTIN EXECUTIVE AIRPARK (Continued) **S123820376**

Contact Name:	HAYS, KIRK
Contact Title:	Not reported
Organization Name:	CENTERLINE PARTNERS LP
Mailing Address:	PO BOX 160488
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78716
Contact Telephone:	(512) 990-7940
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	941
RN Number:	RN101054823
CN Number:	CN600613970
CN Name:	CENTERLINE PARTNERS LP
Role Code:	BILLCONT
Contact Name:	HAYS, KIRK
Contact Title:	Not reported
Organization Name:	CENTERLINE PARTNERS LP
Mailing Address:	PO BOX 160488
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78716
Contact Telephone:	(512) 990-7940
Contact Telephone Ext:	0

3171 ENE 1/4-1/2 0.285 mi. 1503 ft.

PARKS & RECREATION MAINTENANCE
2525 S LAKESHORE BLVD
AUSTIN, TX 78741

TX UST **U001542526**
TX HIST UST **N/A**
TX Financial Assurance
TX RDR

Actual: 453 ft.

Focus Map: 15

UST:

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 787411757
AI Number:	18151
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	ACTIVE
Additional ID:	990000862002139
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	AUSTIN
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	ADRIAN VILLAREAL,MECHANIC
Contact Organization Name:	PARKS & RECREATION MAINTENANCE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124405160
Facility Contact Address Deliverable:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/04/2021
Signature Name/Title On Earliest Reg Form:	WILLIAM OCONNOR,FL PRG MGR
Application Received Date On Earliest Reg Form:	05/05/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	840354562001227
Additional ID:	990000862002139
Ai Number:	18151
Operator CN:	CN600135198
Operator Name:	CITY OF AUSTIN
Operator Effective Begin Date:	05/01/2004
Operator Type:	CI
Operator Role:	OPRCON
Contact Name:	SANDRA CREIGHTON/
Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	505 BARTON SPRINGS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-1216
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78721
Contact Mailing Zip5:	3639
Contact Phone Number/Ext:	1 512 9782649/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	990000862002139
AI Number:	18151
Owner Effective Begin Date:	05/01/2004
State Tax ID:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Contact Role:	OWNCON
Contact Name/Title:	JIMMY TUBBS/FUEL OPS COORD
Contact Organization Name:	CITY OF AUSTIN

Self Certification:

Self Cert ID:	37555
Cert ID:	370936
AI Number:	18151
Self Certification Date:	05/25/2022
Signature Name/Title:	WILLIAM OCONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	353846
AI Number:	18151
Self Certification Date:	05/04/2021
Signature Name/Title:	WILLIAM OCONNOR FL PRG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	336403
AI Number:	18151
Self Certification Date:	04/29/2020
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37555
Cert ID:	320620
AI Number:	18151
Self Certification Date:	05/15/2019
Signature Name/Title:	WILLIAM OCONNOR FLEET PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37555
Cert ID:	303811
AI Number:	18151
Self Certification Date:	05/10/2018
Signature Name/Title:	WILLIAM O'CONNOR FLEET PROGRAM MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37555
Cert ID:	286245
AI Number:	18151
Self Certification Date:	04/18/2017
Signature Name/Title:	WILLIAM OCONNOR FLT PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	270484
AI Number:	18151
Self Certification Date:	05/24/2016
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	253948
AI Number:	18151
Self Certification Date:	06/01/2015
Signature Name/Title:	WILLIAM OCONNOR FLEET MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	236391
AI Number:	18151
Self Certification Date:	04/23/2014
Signature Name/Title:	VALERIE SPINELLI GRANTS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37555
Cert ID:	218863
AI Number:	18151
Self Certification Date:	04/18/2013
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	37555
Cert ID:	10
AI Number:	18151
Self Certification Date:	05/07/2012
Signature Name/Title:	JIMMT TUBBS FUEL SPEC SR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37555
Cert ID:	9
AI Number:	18151
Self Certification Date:	04/08/2011
Signature Name/Title:	JIMMY TUBBS FUEL SPEC SENIOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37555
Cert ID:	8
AI Number:	18151
Self Certification Date:	05/10/2010
Signature Name/Title:	WILL O'CONNOR FLEET PROGRAM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37555
Cert ID:	7
AI Number:	18151
Self Certification Date:	04/06/2009
Signature Name/Title:	STACEY MONROE FUEL OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37555
Cert ID:	6
AI Number:	18151
Self Certification Date:	06/05/2008
Signature Name/Title:	WILL OCONNOR FLT PGM MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	5
AI Number:	18151
Self Certification Date:	05/01/2007
Signature Name/Title:	PAUL GROSS FUEL OPS MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	4
AI Number:	18151
Self Certification Date:	05/01/2006
Signature Name/Title:	PAUL GROSS FUEL OPS COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	3
AI Number:	18151
Self Certification Date:	05/02/2005
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	2
AI Number:	18151
Self Certification Date:	05/21/2004
Signature Name/Title:	MARC CHILDERS FUEL OPER MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	1
AI Number:	18151
Self Certification Date:	04/29/2003
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	406
AI Number:	18151
Self Certification Date:	04/25/2002
Signature Name/Title:	MARC CHILDERS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37555
Cert ID:	405
AI Number:	18151
Self Certification Date:	01/30/2001
Signature Name/Title:	MARC CHILDERS FUEL OPS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5950
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	46954
Facility ID:	37555
Ai Number:	18151
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1981
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	5950
UST Comprt ID:	283
UST ID:	46954
AI Number:	18151
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7024
Cert ID:	160256
UST Comprt ID:	471588
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	378185
UST Comprt ID:	1102690
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	361599
UST Comprt ID:	1052323
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	345162
UST Comprt ID:	1002851
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	327139
UST Comprt ID:	948339
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Self Cert ID:	7024
Cert ID:	317456
UST Comprt ID:	919322
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	310077
UST Comprt ID:	897324
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	294219
UST Comprt ID:	849750
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	276835
UST Comprt ID:	798096
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	260023
UST Comprt ID:	748431
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	243496
UST Comprt ID:	699684
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	227175
UST Comprt ID:	651946
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Cert ID:	160515
UST Comprt ID:	471579
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160514
UST Comprt ID:	471580
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160513
UST Comprt ID:	471581
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160512
UST Comprt ID:	471582
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160511
UST Comprt ID:	471583
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160510
UST Comprt ID:	471584
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160509
UST Comprt ID:	471585
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160257

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

UST Comprt ID:	471589
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160259
UST Comprt ID:	471587
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160260
UST Comprt ID:	471586
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160258
UST Comprt ID:	471590
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1981
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	5950
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	46953
Facility ID:	37555
Ai Number:	18151
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1981
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	5950
UST Comprt ID:	282
UST ID:	46953
AI Number:	18151
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	Y
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/01/1981

More Self Certification:

Self Cert ID:	7024
Cert ID:	160256
UST Comprt ID:	471588
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	378185
UST Comprt ID:	1102690
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	361599
UST Comprt ID:	1052323
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	345162
UST Comprt ID:	1002851
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	327139

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

UST Comprt ID:	948339
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	317456
UST Comprt ID:	919322
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	310077
UST Comprt ID:	897324
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	294219
UST Comprt ID:	849750
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	276835
UST Comprt ID:	798096
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	260023
UST Comprt ID:	748431
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	243496
UST Comprt ID:	699684
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	227175
UST Comprt ID:	651946

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160515
UST Comprt ID:	471579
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160514
UST Comprt ID:	471580
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160513
UST Comprt ID:	471581
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160512
UST Comprt ID:	471582
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160511
UST Comprt ID:	471583
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160510
UST Comprt ID:	471584
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160509
UST Comprt ID:	471585
UST ID:	154557

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160257
UST Comprt ID:	471589
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160259
UST Comprt ID:	471587
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160260
UST Comprt ID:	471586
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7024
Cert ID:	160258
UST Comprt ID:	471590
UST ID:	154557
AI Number:	18151
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	37380
Facility ID:	37555
AI Number:	18151
Application Received Date:	12/02/2020
Scheduled Construction Date:	11/30/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	12/02/2020

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Signature Date On Form:	11/30/2020
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	CITY OF AUSTIN;CITY OF AUSTIN
Owner CN At Time Of Construction:	CN600135198,CN600135198
Owner AR At Time Of Construction:	5A,5U
General Desc Of Prop Construct:	REMOVE LEAKING FLEX LINE AND REPLACE WITH NEW APT FLEX LINE. PIPE IS INSTALLED INSIDE A PIPE DUCT NO CONCRETE TO BE BROKEN. REQUEST 30 DAY WAIVER

NOC ID:	91
Facility ID:	37555
AI Number:	18151
Application Received Date:	11/05/2009
Scheduled Construction Date:	11/09/2009
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91105001
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	12/02/2020
Signature Date On Form:	11/30/2020
Signature Name On Form:	CHRIS MAYS
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	5
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	110
UST ID:	Not reported
NOC ID:	91
AI Number:	18151
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	4411 MEINARDUS DR STE D
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78744 1170
Phone Number/Ext:	512 9782649/0
Contact Fax Number/Ext:	512 9121524/0
Contact Email Address:	WILLIAM.OCONNOR@AUSTINTEXAS.GOV
Contact Address Deliverable:	Y
Facility ID:	37555
Additional ID:	990000862002139
Princ ID:	840354562001227
AI Number:	18151
Facility Name:	PARKS & RECREATION MAINTENANCE
AR Number:	5
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	WILLIAM OCONNOR/

HIST UST AUSTIN:

Name:	COA PARD CENTRAL MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	163
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	268744
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2021
Date Financial Assurance Form Rec:	05/05/2021

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/31/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	250075
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/26/2021
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/26/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	231297
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/25/2020
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/25/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	214219
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/15/2019
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/15/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	197131
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/19/2018
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/19/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	179199
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/23/2017
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	03/23/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	162772
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	OVER 2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/28/2016
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	03/28/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	144998
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/27/2015
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Coverage Amount:	1,000,000
Coverage Expiration Date:	03/27/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	127542
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2013
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	107353
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/01/2012
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/01/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Facility ID:	37555
Finass ID:	289
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	17427
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	17428
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/04/2010
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	1000000
Coverage Expiration Date:	02/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	17429
AI:	18151
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LETTER OF CREDIT
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/06/2008
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	1 213 4817841
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	06/06/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	37555
Finass ID:	17430
AI:	18151
Mechanism Type Other:	LOCAL GOV. BOND RATING TEST
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/05/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No

PARKS & RECREATION MAINTENANCE (Continued) **U001542526**

Proof of Financial Assurance: No

RDR:

RDR ID:	29249
Facility ID:	18151
RN:	Not reported
CN:	Not reported
Name:	PARKS & RECREATION MAINTENANCE
Address:	2525 S LAKESHORE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/3/2022
Due Date:	5/2/2022
Tank Owner:	CITY OF AUSTIN
Contact Person:	WILLIAM OCONNOR
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	3/7/2022
Project Manager:	Hailey Reier
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Org Rpt Submitted 12/4/20; Delinquent Fee Ltr Send 1/26/21
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3172 WNW 1/4-1/2 0.285 mi. 1504 ft. | **WEED-CORLEY FUNERAL HOME** | **TX LPST** | **U001256093**
1301 W 34TH ST | **TX UST** | **N/A**
AUSTIN, TX 78705 | **TX HIST UST**

Actual: 575 ft.

Focus Map: 8

LPST:

Name:	WEED CORLEY CASKET WAREHOUSE
Address:	1301 W 34TH ST
City,State,Zip:	AUSTIN, TX 78705
Facility ID:	0021445
LPST Id:	102033
Facility Location:	1301 W 34TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/21/1992
Entered Date:	03/12/1992
Reported Date:	02/21/1992
Closure Date:	05/30/1995
Priority:	1A - IMPACT/THREAT TO HUMAN HEALTH AND/OR SAFETY
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	IMPACT/THREAT TO HUMAN HEALTH AND/OR SAFETY
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	KKC

WEED-CORLEY FUNERAL HOME (Continued) **U001256093**

Responsible Party Name:	Not reported
Responsible Party Contact:	LAURENS FISH
Responsible Party Address:	3125 N LAMAR BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78705
Responsible Party Telephone:	512/452-8811
Reported Date:	02/21/1992
Case Start Date:	05/30/1995
Reference Number:	RN101494680
Project Manager:	KKC

UST:

Name:	WEED-CORLEY FUNERAL HOME
Address:	1301 W 34TH ST
City,State,Zip:	AUSTIN, TX 787051911
AI Number:	21445
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/15/1986
Facility Status:	INACTIVE
Additional ID:	297662612002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78705
Contact Name/Title:	L FISH,OWNER
Contact Organization Name:	WEED-CORLEY FUNERAL HOME
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124528811
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/03/1986
Signature Name/Title On Earliest Reg Form:	L FISH,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600782619
Owner Last Name:	WEED-CORLEY FUNERAL HOME
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported

WEED-CORLEY FUNERAL HOME (Continued) **U001256093**

Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	287662602002053
Additional ID:	297662612002053
AI Number:	21445
Owner Effective Begin Date:	09/15/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	55100
Facility ID:	58158
Ai Number:	21445
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	02/12/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

WEED-CORLEY FUNERAL HOME (Continued) **U001256093**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	01/04/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	64519
UST ID:	55100
AI Number:	21445
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

WEED-CORLEY FUNERAL HOME (Continued) **U001256093**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WEED-CORLEY FUNERAL HOME
Contact Mailing Address (Delivery):	3125 N LAMAR BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78705 2012
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	58158
Additional ID:	297662612002053
Princ ID:	287662602002053
AI Number:	21445
Facility Name:	WEED-CORLEY FUNERAL HOME
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	L FISH/

HIST UST AUSTIN:

Name:	WEED CORLEY FUNERAL HOME
Address:	1301 W 34TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0307
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3173 **KING FOOD MART** **TX RDR** **S127526661**
WSW **2907 S FIRST ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.286 mi.
1509 ft.

Actual:
592 ft.

Focus Map:
14

RDR:

RDR ID:	28235
Facility ID:	19615
RN:	Not reported
CN:	Not reported
Name:	KING FOOD MART
Address:	2907 S FIRST ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/18/2020
Due Date:	4/18/2020
Tank Owner:	OFLP-3 LTD
Contact Person:	PATRICK OLIVER
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check

KING FOOD MART (Continued) **S127526661**

Date of Latest TCEQ Letter:	2/24/2020
Project Manager:	Corbin Reyes
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3174 NNE 1/4-1/2 0.287 mi. 1515 ft. **SPAW GLASS CONSTRUCTION SITE** **TX LPST** **S104956599**
1020 RED RIVER ST **N/A**
AUSTIN, TX 78701

Actual: 480 ft.

Focus Map: 11

LPST:

Name:	SPAW GLASS CONSTRUCTION SITE
Address:	1020 RED RIVER ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0048597
LPST Id:	093412
Facility Location:	11TH ST @ RED RIVER
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/19/1989
Entered Date:	08/08/1989
Reported Date:	07/19/1989
Closure Date:	08/30/1991
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JERRY GILBERT
Responsible Party Address:	1001 TRINITY ST
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/370-0523
Reported Date:	07/19/1989
Case Start Date:	08/30/1991
Reference Number:	RN101492841
Project Manager:	HWELCH

3175 ESE 1/4-1/2 0.291 mi. 1535 ft. | **MULDOON INTERESTS 6210 CROW LN AUSTIN, TX 78745** | **TX VCP** | **S123819861 N/A**

Actual: 654 ft.

Focus Map: 17

VCP TCEQ:

Name:	MULDOON INTERESTS
Address:	6210 CROW LN
City,State,Zip:	AUSTIN, TX 78745
Region:	REGION 11 - AUSTIN
Facility ID:	2074
VCP Record Date:	06/14/2007
Facility Type:	AUTO SVC STN/REPAIR/VEH MAINTE
PCA Number:	34270
Project Manager:	SLAWLESS
Phase:	COMPLETED
Acres at Site:	6
REM Program:	VCP
RN Number:	RN102479920
Former Facility Type:	Not reported
Site Address Description:	6210 - 6216 CROW LN
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	06/14/2007
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	1
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/28/2008
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	06/14/2007
GW Target COC Class:	Not reported
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2007-07-25 00:00:00
Soil Target COC Class:	METALS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2074
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	342700
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	30.20

MULDOON INTERESTS (Continued) **S123819861**

Longitude: -97.77

Contact:

REM Program:	VCP
Program ID:	2074
RN Number:	RN102479920
CN Number:	CN603210881
CN Name:	MULDOON INTERESTS LLC
Role Code:	APPLCONT
Contact Name:	DAVIS, DARIN
Contact Title:	PROFESSIONAL MANAGER
Organization Name:	MULDOON INTERESTS LLC
Mailing Address:	PO BOX 685316
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78768
Contact Telephone:	(512) 637-6377
Contact Telephone Ext:	0

REM Program:	VCP
Program ID:	2074
RN Number:	RN102479920
CN Number:	CN603210881
CN Name:	MULDOON INTERESTS LLC
Role Code:	BILLCONT
Contact Name:	DAVIS, DARIN
Contact Title:	Not reported
Organization Name:	MULDOON INTERESTS LLC
Mailing Address:	PO BOX 685316
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78768
Contact Telephone:	(512) 637-6377
Contact Telephone Ext:	0

3176 WNW 1/4-1/2 0.294 mi. 1552 ft. | **FIRE STATION 16 7000 REESE LN AUSTIN, TX 78757** | **TX LPST TX UST TX HIST UST TX ASBESTOS** | **U001542538 N/A**

Actual: 722 ft.

Focus Map: 6

LPST:

Name:	FIRE STATION 16
Address:	7000 REESE LN
City,State,Zip:	AUSTIN, TX 78767
Facility ID:	0018164
LPST Id:	103200
Facility Location:	7000 REESE LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/08/1992
Entered Date:	06/22/1992
Reported Date:	05/28/1992
Closure Date:	07/24/1992
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED

FIRE STATION 16 (Continued) **U001542538**

Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	IKE IKEMBA
Responsible Party Name:	Not reported
Responsible Party Contact:	MARC CHILDERS
Responsible Party Address:	6301A HAROLD CT
Responsible Party City,St,Zip:	AUSTIN, TX 78721
Responsible Party Telephone:	512/928-1492
Reported Date:	05/28/1992
Case Start Date:	07/24/1992
Reference Number:	RN102237229
Project Manager:	UIKEMBA

UST:

Name:	FIRE STATION 16
Address:	7000 REESE LN
City,State,Zip:	AUSTIN, TX 787571918
AI Number:	18164
Facility Type:	FLEET REFUELING
Facility Begin Date:	09/02/1986
Facility Status:	INACTIVE
Additional ID:	124799182002138
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	,
Contact Organization Name:	FIRE STATION 16
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124537954
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/04/1986
Signature Name/Title On Earliest Reg Form:	J A LINNEMANN,MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600135198
Owner Last Name:	CITY OF AUSTIN
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CI
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

FIRE STATION 16 (Continued) **U001542538**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	840354562001227
Additional ID:	124799182002138
AI Number:	18164
Owner Effective Begin Date:	09/02/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	560
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	46976
Facility ID:	37568
Ai Number:	18164
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/08/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

FIRE STATION 16 (Continued) **U001542538**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	03/20/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	560
UST Comprt ID:	305
UST ID:	46976
AI Number:	18164
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

FIRE STATION 16 (Continued) **U001542538**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7028
Cert ID:	160544
UST Comprt ID:	472534
UST ID:	154569
AI Number:	18164
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160543
UST Comprt ID:	472535
UST ID:	154569
AI Number:	18164
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160542
UST Comprt ID:	472538
UST ID:	154569
AI Number:	18164
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160541
UST Comprt ID:	472537
UST ID:	154569
AI Number:	18164
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160540
UST Comprt ID:	472536
UST ID:	154569
AI Number:	18164
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7028
Cert ID:	160545
UST Comprt ID:	472533
UST ID:	154569
AI Number:	18164
Tank ID:	2

FIRE STATION 16 (Continued) **U001542538**

Compartment ID: A

Facility Billing Contacts:

Contact Organization Name:	CITY OF AUSTIN
Contact Mailing Address (Delivery):	6400 BOLM RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78721 3639
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	37568
Additional ID:	124799182002138
Princ ID:	840354562001227
AI Number:	18164
Facility Name:	FIRE STATION 16
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	COA AFD FIRE STATION #16
Address:	7000 REESE LN
City,State,Zip:	AUSTIN, TX
Id UST:	C0320
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	Not reported
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	10/11/2019
Notification Number:	2019007135
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/24/2019
Date Routed by Supervisor:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	09/24/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/09/10
Notification Number:	Not reported
ASB Priority:	Not reported

FIRE STATION 16 (Continued) **U001542538**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	09/10/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019006020
File Number:	44175
License Status Description:	Paid
Expiration Date:	09/12/2019
Original Date:	08/06/2019
Rank Effective Date:	08/06/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	18116
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB

FIRE STATION 16 (Continued) **U001542538**

Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported
Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/04/16
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	04/16/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2020002447

FIRE STATION 16 (Continued) **U001542538**

File Number:	51416
License Status Description:	Paid
Expiration Date:	04/23/2020
Original Date:	03/25/2020
Rank Effective Date:	03/25/2020
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	21264
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	09/10/2019
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	09/12/2019
Notification Number:	2019006020
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/12/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/12/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07

FIRE STATION 16 (Continued) **U001542538**

Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/05/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	09/10/2019
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	09/04/2019
Notification Number:	2019006020
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/16/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/16/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/27/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	09/10/2019
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	09/13/2019
Notification Number:	2019006020
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/26/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/26/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/04/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CITY OF AUSTIN FIRE STATION #16

FIRE STATION 16 (Continued) **U001542538**

Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	09/10/2019
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	09/13/2019
Notification Number:	2019006020
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/04/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/04/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/05/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CITY OF AUSTIN FIRE STATION #16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	09/10/2019
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	08/30/2019
Notification Number:	2019006020
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/06/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	25
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

FIRE STATION 16 (Continued) **U001542538**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/21/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	04/21/2020
Notification Number:	2020002427
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/25/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Cancelled

FIRE STATION 16 (Continued) **U001542538**

Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/24/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/14/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	Not reported
Reason for Inspection:	Joseph Thomas
Violation:	Not reported
Complaint Date:	04/09/2020
Notification Number:	2020002427
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP

FIRE STATION 16 (Continued) **U001542538**

Inspector Name:	Not reported
Date Report Received:	03/18/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/18/2020
Certification Statement Phone:	512-974-9187
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/02/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	04/27/2021
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Complaint Date:	04/23/2020
Notification Number:	2020002447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/15/2020
Certification Statement Phone:	512-997-8532
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/13/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

FIRE STATION 16 (Continued) **U001542538**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	04/27/2021
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	04/17/2020
Notification Number:	2020002447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	04/08/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/08/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/13/2020

FIRE STATION 16 (Continued) **U001542538**

Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	FIRE STATION 16
Address:	7000 REESE LANE
City,State,Zip:	AUSTIN, TX 78757
Date of inspection:	04/27/2021
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	04/13/2020
Notification Number:	2020002447
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	03/25/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/25/2020

FIRE STATION 16 (Continued) **U001542538**

Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	04/09/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TM3177 **SHOPPERS MART 6** **TX LPST** **S116701879**
East **2453 HIGHWAY 71 E** **N/A**
1/4-1/2 **DEL VALLE, TX 78617**
0.296 mi.
1561 ft. **Site 1 of 2 in cluster TM**

Actual:
509 ft.

Focus Map:
20

LPST:

Name:	SHOPPERS MART 6
Address:	2453 HIGHWAY 71 E
City,State,Zip:	DEL VALLE, TX 78617
Facility ID:	0034915
LPST Id:	091829
Facility Location:	2453 BASTROP HWY
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/17/1988
Entered Date:	04/05/1988
Reported Date:	04/05/1988
Closure Date:	06/10/1988
Priority:	1D - GROUP 1 GROUNDWATER PLUME HAS/LIKELY TO MIGRATE OFF-SITE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUP 1 GROUNDWATER, PLUME HAS/LIKELY TO MIGRATE OFF-SITE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1

SHOPPERS MART 6 (Continued) **S116701879**

Coordinators RPR:	ANTONIO PENA
Responsible Party Name:	Not reported
Responsible Party Contact:	FORD SMITH
Responsible Party Address:	5001 E 5TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	/-
Reported Date:	04/05/1988
Case Start Date:	06/10/1988
Reference Number:	RN105053508
Project Manager:	ARP

TM3178 **SHOPPERS MART 6** **TX LPST** **S116703122**
East **2453 HIGHWAY 71 E** **N/A**
1/4-1/2 **DEL VALLE, TX 78617**
0.296 mi.
1561 ft. **Site 2 of 2 in cluster TM**

Actual:
509 ft.

Focus Map:
20

LPST:

Name:	SHOPPERS MART 6
Address:	2453 HIGHWAY 71 E
City,State,Zip:	DEL VALLE, TX 78617
Facility ID:	0034915
LPST Id:	095400
Facility Location:	BASTROP HWY
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/12/1990
Entered Date:	05/07/1990
Reported Date:	04/13/1990
Closure Date:	04/08/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SEL
Responsible Party Name:	Not reported
Responsible Party Contact:	KYLE LANDRENEAU
Responsible Party Address:	110 CYPRESS STATION DR STE 255
Responsible Party City,St,Zip:	HOUSTON, TX 77090
Responsible Party Telephone:	281/586-3613
Reported Date:	04/13/1990
Case Start Date:	04/08/1999
Reference Number:	RN105053508
Project Manager:	SLAWLESS

3179 WNW 1/4-1/2 0.299 mi. 1581 ft. | **MOFFITT MAINTENANCE INC**
11502 TITAN DR
AUSTIN, TX | **TX RDR** | **S127536469**
N/A

Actual: 748 ft.
Focus Map: 3

RDR:

RDR ID:	8163
Facility ID:	59917
RN:	Not reported
CN:	Not reported
Name:	MOFFITT MAINTENANCE INC
Address:	11502 TITAN DR
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/18/1999
Due Date:	12/17/1999
Tank Owner:	CARREJO INC
Contact Person:	ERIC CARREJO
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/13/2000
Project Manager:	Brent Rice
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	104737
Comments:	6A APPROVED
Review Coordinator:	BJR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	3/13/2000
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TN3180 SW 1/4-1/2 0.300 mi. 1582 ft. | **CIRCLE K STORE 2740552**
2222 E OLTORF
AUSTIN, TX
Site 1 of 4 in cluster TN | **TX RDR** | **S127533405**
N/A

Actual: 606 ft.
Focus Map: 14

RDR:

RDR ID:	27421
Facility ID:	44708
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/3/2019
Due Date:	11/2/2019
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	10/29/2019
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported

CIRCLE K STORE 2740552 (Continued) **S127533405**

Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TN3181 **CIRCLE K STORE #2740552** **TX RDR** **S127533404**
SW **2222 E OLTORF ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.300 mi.
1582 ft. **Site 2 of 4 in cluster TN**

Actual:
606 ft.

Focus Map:
14

RDR:

RDR ID:	30032
Facility ID:	44708
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K STORE #2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/16/2021
Due Date:	6/15/2021
Tank Owner:	CIRCLE K STORES INC
Contact Person:	KEVIN PAGSOLINGAN
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	6/9/2021
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TN3182 **CIRCLE K 2740552** **TX RDR** **S127533403**
SW **2222 E OLTORF ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.300 mi.
1582 ft. **Site 3 of 4 in cluster TN**

Actual:
606 ft.

Focus Map:
14

RDR:

RDR ID:	29291
Facility ID:	44708
RN:	Not reported
CN:	Not reported

CIRCLE K 2740552 (Continued) **S127533403**

Name:	CIRCLE K 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/8/2020
Due Date:	2/6/2021
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	Suspected Release
Latest TCEQ Letter:	No System/Site Check
Date of Latest TCEQ Letter:	1/19/2021
Project Manager:	Frank Clayworth
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported
RDR ID:	27485
Facility ID:	44708
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/9/2019
Due Date:	11/8/2019
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	10/29/2019
Project Manager:	Emmanuel Ekpo
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported
RDR ID:	27905
Facility ID:	44708
RN:	Not reported
CN:	Not reported
Name:	CIRCLE K 2740552

CIRCLE K 2740552 (Continued) **S127533403**

Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/10/2019
Due Date:	2/8/2020
Tank Owner:	CIRCLE K STORES INC
Contact Person:	VERONICA RIVERA
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	12/30/2019
Project Manager:	Frank Clayworth
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TN3183 **CIRCLE K STORE 2740552** **TX LPST** **U003566321**
SW **2222 E OLTORF ST** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78741** **TX HIST UST**
0.300 mi. **TX ASBESTOS**
1582 ft. **Site 4 of 4 in cluster TN** **TX Financial Assurance**

Actual:
606 ft.

Focus Map:
14

LPST:

Name:	DIAMOND SHAMROCK 552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0044708
LPST Id:	096255
Facility Location:	2222 E OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/07/1990
Entered Date:	07/26/1990
Reported Date:	02/07/1990
Closure Date:	07/31/1996
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1
Coordinators RPR:	VYF
Responsible Party Name:	Not reported
Responsible Party Contact:	TIM GEORGE
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	210/641-8869
Reported Date:	02/07/1990
Case Start Date:	07/31/1996
Reference Number:	RN102373354
Project Manager:	VYF

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST:

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 787414544
AI Number:	44708
Facility Type:	RETAIL
Facility Begin Date:	09/01/1987
Facility Status:	ACTIVE
Additional ID:	900805582002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	VERONICA RIVERA,
Contact Organization Name:	CORNER STORE 0552
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	6027288000
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/24/2017
Signature Name/Title On Earliest Reg Form:	JENNIFER RESNIK,COMP COOR
Application Received Date On Earliest Reg Form:	08/25/2017
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	658325792001221
Additional ID:	900805582002149
Ai Number:	44708
Operator CN:	CN600134456
Operator Name:	CIRCLE K STORES INC
Operator Effective Begin Date:	08/16/2021
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	PHOENIX AZ 85072-2085
Contact Phone Country Code:	0
Contact Phone Area Code:	602
Contact Phone Number:	7288000
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600134456
Owner Last Name:	CIRCLE K STORES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 52085
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	PHOENIX
Contact Mailing State:	AZ
Contact Mailing Zip:	85072
Contact Mailing Zip5:	2085
Contact Phone Number/Ext:	0 602 7288000/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	658325792001221
Additional ID:	900805582002149
AI Number:	44708
Owner Effective Begin Date:	08/16/2021
State Tax ID:	17411495405
Contact Role:	OWNOPRCON
Contact Name/Title:	VERONICA RIVERA/
Contact Organization Name:	CIRCLE K STORES INC

Self Certification:

Self Cert ID:	74563
Cert ID:	379533
AI Number:	44708
Self Certification Date:	09/29/2022
Signature Name/Title:	KELLIE BODDIE ENVIRONMENTAL SPECIA
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	360558
AI Number:	44708
Self Certification Date:	09/21/2021
Signature Name/Title:	KELLIE BODDIE ENVIRONMENTAL SPECIALIST
Signature Type Role:	OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74563
Cert ID:	342471
AI Number:	44708
Self Certification Date:	09/02/2020
Signature Name/Title:	Veronica Rivera OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74563
Cert ID:	327702
AI Number:	44708
Self Certification Date:	09/26/2019
Signature Name/Title:	Annette S Toale Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	74563
Cert ID:	310887
AI Number:	44708
Self Certification Date:	10/01/2018
Signature Name/Title:	Annette S Toale Enviro Manager
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	292477
AI Number:	44708
Self Certification Date:	08/24/2017
Signature Name/Title:	JENNIFER RESNIK COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	276054
AI Number:	44708
Self Certification Date:	08/22/2016
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	257895
AI Number:	44708
Self Certification Date:	08/25/2015
Signature Name/Title:	JENNIFER RESNIK COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	242849
AI Number:	44708
Self Certification Date:	08/29/2014
Signature Name/Title:	JENNIFER RESNIK COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	226259
AI Number:	44708
Self Certification Date:	08/24/2013
Signature Name/Title:	KENT HAMEL COMPIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	74563
Cert ID:	104146
AI Number:	44708
Self Certification Date:	08/24/2012
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104145
AI Number:	44708
Self Certification Date:	08/24/2011
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104144
AI Number:	44708
Self Certification Date:	08/24/2010
Signature Name/Title:	KENT HAMEL COMP SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104143
AI Number:	44708
Self Certification Date:	08/28/2009
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104142
AI Number:	44708
Self Certification Date:	08/29/2008
Signature Name/Title:	KENT HAMEL COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104141
AI Number:	44708
Self Certification Date:	03/20/2008
Signature Name/Title:	TERRY HANKINS O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104140
AI Number:	44708
Self Certification Date:	08/28/2007
Signature Name/Title:	KENT HAMEL COMPLIANCE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104139
AI Number:	44708
Self Certification Date:	08/01/2006
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104138
AI Number:	44708
Self Certification Date:	07/26/2005
Signature Name/Title:	KENT HAMEL O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104137
AI Number:	44708
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104136
AI Number:	44708
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104135
AI Number:	44708
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	74563
Cert ID:	104134
AI Number:	44708
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL

CIRCLE K STORE 2740552 (Continued) **U003566321**

Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1962
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117112
Facility ID:	74563
Ai Number:	44708
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1A
Tank Capacity:	12000
UST Comprt ID:	103558
UST ID:	117112
AI Number:	44708
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17538
Cert ID:	120516
UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880

CIRCLE K STORE 2740552 (Continued) **U003566321**

AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	227112
UST Comprt ID:	651792
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708

CIRCLE K STORE 2740552 (Continued) **U003566321**

Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	333268
UST Comprt ID:	966403
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3

CIRCLE K STORE 2740552 (Continued) **U003566321**

Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120517
UST Comprt ID:	348578
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Install Date:	03/01/1990
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117113
Facility ID:	74563
Ai Number:	44708
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	12098
UST Comprt ID:	103559
UST ID:	117113
AI Number:	44708
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM

CIRCLE K STORE 2740552 (Continued) **U003566321**

Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID:	17538
Cert ID:	120516
UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880
AI Number:	44708
Tank ID:	3

CIRCLE K STORE 2740552 (Continued) **U003566321**

Compartment ID:	A
Self Cert ID:	17538
Cert ID:	227112
UST Comprt ID:	651792
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A

CIRCLE K STORE 2740552 (Continued) **U003566321**

Self Cert ID:	17538
Cert ID:	333268
UST Comprt ID:	966403
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538

CIRCLE K STORE 2740552 (Continued) **U003566321**

Cert ID:	120517
UST Comprt ID:	348578
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A

Install Date:	03/01/1990
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117114
Facility ID:	74563
Ai Number:	44708
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	12098
UST Comprt ID:	103560
UST ID:	117114
AI Number:	44708
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

More Self Certification:

Self Cert ID:	17538
Cert ID:	120516
UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A

CIRCLE K STORE 2740552 (Continued) **U003566321**

Self Cert ID:	17538
Cert ID:	227112
UST Comprt ID:	651792
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538

CIRCLE K STORE 2740552 (Continued) **U003566321**

Cert ID:	333268
UST Comprt ID:	966403
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120517

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST Comprt ID:	348578
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Install Date:	03/01/1990
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12098
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117115
Facility ID:	74563
Ai Number:	44708
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	03/01/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	Y
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	12098
UST Comprt ID:	103561
UST ID:	117115
AI Number:	44708
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

CIRCLE K STORE 2740552 (Continued) **U003566321**

Self Cert ID:	17538
Cert ID:	120516
UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538

CIRCLE K STORE 2740552 (Continued) **U003566321**

Cert ID:	227112
UST Comprt ID:	651792
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	333268

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST Comprt ID:	966403
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120517
UST Comprt ID:	348578

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1962
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117110
Facility ID:	74563
Ai Number:	44708
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3A
Tank Capacity:	12000
UST Comprt ID:	103556
UST ID:	117110
AI Number:	44708
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17538

CIRCLE K STORE 2740552 (Continued) **U003566321**

Cert ID:	120516
UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	227112

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST Comprt ID:	651792
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	333268
UST Comprt ID:	966403

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120517
UST Comprt ID:	348578
UST ID:	115880

CIRCLE K STORE 2740552 (Continued) **U003566321**

AI Number:	44708
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1962
Tank Registration Date:	03/24/1987
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	117111
Facility ID:	74563
Ai Number:	44708
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	03/31/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2A
Tank Capacity:	12000
UST Comprt ID:	103557
UST ID:	117111
AI Number:	44708
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	17538
Cert ID:	120516

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST Comprt ID:	348579
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120515
UST Comprt ID:	348580
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120518
UST Comprt ID:	348577
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120519
UST Comprt ID:	348576
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120520
UST Comprt ID:	348575
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120521
UST Comprt ID:	348574
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120522
UST Comprt ID:	348573
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	227112
UST Comprt ID:	651792

CIRCLE K STORE 2740552 (Continued) **U003566321**

UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	243585
UST Comprt ID:	699923
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	260020
UST Comprt ID:	748423
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	276465
UST Comprt ID:	797029
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	293901
UST Comprt ID:	848796
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	310508
UST Comprt ID:	898366
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	316621
UST Comprt ID:	916775
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	333268
UST Comprt ID:	966403
UST ID:	115880

CIRCLE K STORE 2740552 (Continued) **U003566321**

AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	355884
UST Comprt ID:	1035223
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120510
UST Comprt ID:	348582
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120511
UST Comprt ID:	348583
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120512
UST Comprt ID:	348584
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120513
UST Comprt ID:	348585
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120514
UST Comprt ID:	348581
UST ID:	115880
AI Number:	44708
Tank ID:	3
Compartment ID:	A
Self Cert ID:	17538
Cert ID:	120517
UST Comprt ID:	348578
UST ID:	115880
AI Number:	44708

CIRCLE K STORE 2740552 (Continued) **U003566321**

Tank ID: 3
Compartment ID: A

Construction Notification:

NOC ID:	34613
Facility ID:	74563
AI Number:	44708
Application Received Date:	04/26/2019
Scheduled Construction Date:	04/26/2019
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	04/26/2019
Signature Date On Form:	04/26/2019
Signature Name On Form:	SEAN ARMSTRONG
Signature Company On Form:	PETROLEUM NETWORK SOLUTIONS
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	BIG DIAMOND LLC;BIG DIAMOND LLC
Owner CN At Time Of Construction:	CN604312421,CN604312421
Owner AR At Time Of Construction:	74569A,74569U
General Desc Of Prop Construct:	REPLACE ALL SPILL BUCKETS WITH EVOLUTION DW SPILL BUCKETS

NOC ID:	26106
Facility ID:	74563
AI Number:	44708
Application Received Date:	07/15/2014
Scheduled Construction Date:	08/15/2014
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	N
Form Received Date:	04/26/2019
Signature Date On Form:	04/26/2019
Signature Name On Form:	SEAN ARMSTRONG
Signature Company On Form:	PETROLEUM NETWORK SOLUTIONS
Signature Title On Form:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Signature Role:	Not reported
Owner Name At Time Of Construction:	BIG DIAMOND LLC;BIG DIAMOND LLC
Owner CN At Time Of Construction:	CN604312421,CN604312421
Owner AR At Time Of Construction:	74569A,74569U
General Desc Of Prop Construct:	INSTALL (3) NEW FRP SUMPS WITH (3) WATER TIGHT MANHOLES

NOC ID:	11008
Facility ID:	74563
AI Number:	44708
Application Received Date:	06/15/2003
Scheduled Construction Date:	06/16/2003
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30616017
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	04/26/2019
Signature Date On Form:	04/26/2019
Signature Name On Form:	SEAN ARMSTRONG
Signature Company On Form:	PETROLEUM NETWORK SOLUTIONS
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	11007
Facility ID:	74563
AI Number:	44708
Application Received Date:	04/28/2003
Scheduled Construction Date:	05/12/2003
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M30428006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	04/26/2019
Signature Date On Form:	04/26/2019
Signature Name On Form:	SEAN ARMSTRONG
Signature Company On Form:	PETROLEUM NETWORK SOLUTIONS

CIRCLE K STORE 2740552 (Continued) **U003566321**

Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599
General Desc Of Prop Construct:	Not reported

NOC ID:	11006
Facility ID:	74563
AI Number:	44708
Application Received Date:	02/13/2013
Scheduled Construction Date:	03/15/2013
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	04/26/2019
Signature Date On Form:	04/26/2019
Signature Name On Form:	SEAN ARMSTRONG
Signature Company On Form:	PETROLEUM NETWORK SOLUTIONS
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	68299
General Desc Of Prop Construct:	REPLACE OLD DISPENSERS WITH NEW BLENDING DISPENSERS AND CONVERTING THE PLUS TANK INTO DIESEL.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	11824
UST ID:	Not reported
NOC ID:	11006
AI Number:	44708
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	CST
Representative Name:	CHRIS TRINKLE
Mailing Address (Delivery):	ONE VALERO WAY
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONIO
Mailing State:	TX
Mailing Zip:	78269
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6612489
Phone Number Extension:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	82176
UST ID:	Not reported
NOC ID:	34613
AI Number:	44708
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	PETROLEUM NETWORK SOLUTIONS
Representative Name:	SEAN ARMSTRONG
Mailing Address (Delivery):	4401 LITTLE RD STE 550-324
Mailing Address (Internal Delivery):	Not reported
Mailing City:	ARLINGTON
Mailing State:	TX
Mailing Zip:	76016
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	11827
UST ID:	Not reported
NOC ID:	11008
AI Number:	44708
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	60935
UST ID:	Not reported
NOC ID:	26106
AI Number:	44708

CIRCLE K STORE 2740552 (Continued) **U003566321**

Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL FUELING SYSTEMS
Representative Name:	Not reported
Mailing Address (Delivery):	1113 REGAL ROW STE A
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78748
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	11823
UST ID:	Not reported
NOC ID:	11006
AI Number:	44708
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PSI
Representative Name:	BOB BISSEN
Mailing Address (Delivery):	14833 BULVERDE RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SAN ANTONTIO
Mailing State:	TX
Mailing Zip:	78247
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6612489
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11826
UST ID:	Not reported
NOC ID:	11007
AI Number:	44708
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	11825
UST ID:	Not reported
NOC ID:	11006
AI Number:	44708
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	60934
UST ID:	Not reported
NOC ID:	26106
AI Number:	44708
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Email Address: RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Facility Billing Contacts:

Contact Organization Name:	CIRCLE K STORES INC
Contact Mailing Address (Delivery):	3802 CORPOREX PARK DR STE 200
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	TAMPA, FL 33619 1125
Phone Number/Ext:	984 3891316/0
Contact Fax Number/Ext:	/
Contact Email Address:	kboddie@circlek.com
Contact Address Deliverable:	Y
Facility ID:	74563
Additional ID:	900805582002149
Princ ID:	658325792001221
AI Number:	44708
Facility Name:	CIRCLE K STORE 2740552
AR Number:	82920
AR UST Number Suffix:	A
AR AST Number Suffix:	U
Contact Name/Title:	KELLIE BODDIE/ENVIRONMENTAL SPECIALIST

HIST UST AUSTIN:

Name:	CORNER STORE NO. 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	1940
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	VALERO
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/19/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013

CIRCLE K STORE 2740552 (Continued) **U003566321**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	VALERO CORNER STORE
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/15/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.6
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

CIRCLE K STORE 2740552 (Continued) **U003566321**

Results: Not reported
Inspection Number Grade: Not reported

TX Financial Assurance 2:

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	275347
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/11/2022
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 984 3891316
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/11/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	257542
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/23/2020
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	0 0 0
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/27/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563

CIRCLE K STORE 2740552 (Continued) **U003566321**

Finass ID:	220921
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	GUARANTEE
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/27/2019
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	PARENT (GUARANTEE)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	204703
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/01/2018
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	NAVIGATORS INS CO
Issuer Phone:	Not reported
Policy Number:	CH18ESP0BDKNONC
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/01/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	185546
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

CIRCLE K STORE 2740552 (Continued) **U003566321**

Financial Assurance Begin Date:	03/27/2017
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	168285
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/15/2016
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	148875
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2015
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/09/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

CIRCLE K STORE 2740552 (Continued) **U003566321**

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	133963
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/16/2014
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	04/30/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	116005
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2013
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	7919
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

CIRCLE K STORE 2740552 (Continued) **U003566321**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/19/2012
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	2,000,000
Coverage Expiration Date:	04/30/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	57614
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	57615
AI:	44708
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/23/2010
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000

CIRCLE K STORE 2740552 (Continued) **U003566321**

Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	57616
AI:	44708
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/27/2009
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	74563
Finass ID:	57617
AI:	44708
Mechanism Type Other:	GUARANTEE
Multiple Mechanism Types:	Y
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	OTHER
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/12/2007
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 210 3452000
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	09/12/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	CIRCLE K STORE 2740552
Address:	2222 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741

CIRCLE K STORE 2740552 (Continued) **U003566321**

Region:	2
Facility ID:	74563
Finass ID:	57618
AI:	44708
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	08/25/2017
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

3184 **SIGNATURE 1** **TX RDR** **S127539924**
SSE **100 E SLAUGHTER LN** **N/A**
1/4-1/2 **AUSTIN, TX**
0.303 mi.
1601 ft.

Actual:
650 ft.

Focus Map:
21

RDR:

RDR ID:	20664
Facility ID:	76336
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 1
Address:	100 E SLAUGHTER LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/3/2012
Due Date:	10/2/2012
Tank Owner:	TRIPLE S PETROLEUM CO
Contact Person:	PAUL PEMBERTON
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	10/1/2012
Project Manager:	Prasanthi Bollineni
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PVB
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	10/1/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

3185
NNE
1/4-1/2
0.306 mi.
1614 ft.

1111 OLD BASTROP HIGHWAY
TRAVIS (County), TX

TX CLI **S104731741**
N/A

Actual:
442 ft.

Focus Map:
16

CLI:

Name:	Not reported
Address:	1111 OLD BASTROP HIGHWAY
City,State,Zip:	TX
Facility ID:	1390
Facility Name2:	Not reported
Site Status:	GRANDFATHER SITE
Date Recieved:	19800502
County:	Travis
Region:	Weslaco
Near City:	AUSTIN
Organic Acres:	18.00
Area Served:	AUSTIN
Population Srvd:	500
Tons per Day:	10
Yards per Day:	0.00
Permit Status:	K
Removal Status:	FILE UPDATED 9-24-93.
Status Date:	**********
Engineer:	Not reported
Source:	1
Source Code:	Not reported
Date Opened:	Not reported
Date Closed:	Not reported
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	13.48
Long Deg:	97
Long Min:	40.30
Lat/Long (deg):	30.224667 / -97.671667
Owner:	S B WINGFIELD
Owner Address:	1111 OLD BASTROP HIGHWAY
Owner C,S,Z:	AUSTIN, TX 78742
Business Type:	INDIVIDUAL
Facility Type:	1
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	AUSTIN
Applicant Name:	S B WINGFIELD
Applicant Address:	1111 OLD BASTROP HIGHWAY
Applicant City,St,Zip:	AUSTIN, TX 78742
Applicant Phone:	512 3853770
Est Cleanup Date:	19820501
River Basin Code:	14
Earliest Date in the Records:	19630101
Last Date in Records Site Accepted Waste:	19840601
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	Not reported
Code for Landfill:	1
Parties:	Not reported
Accepts House Hold:	Not reported
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported

(Continued) **S104731741**

Accepts Tires:	Not reported
Accepts Agriculture:	Not reported
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Not reported
Legal:	Not reported
Maximum Depth:	Not reported
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported
Inspc Comments:	Not reported
Comments:	Not reported
Update:	2
Reviewer:	NO PERMIT ISSUED / K STATUS ASSIGNED 19840601
Flag:	Not reported

CAPCOG LI:

Name:	Not reported
Address:	1111 OLD BASTROP HIGHWAY
City,State,Zip:	TX
Type Facility:	1
Site Status:	GF
Date Open:	Not reported
Date Close:	Not reported
Unum:	1390
Near City:	AUSTIN
Latitude Deg:	30
Latitude Min:	13.48
Longitude Deg:	97
Longitude Min:	40.299999999999997
Lat Dd:	30.224667
Long Dd:	-97.671666999999999
Accuracy:	Not reported
Date Rec:	19800502
County Cd:	227
Region Cd:	11
Etj1:	AUSTIN
Amendment:	Not reported
Source:	1
App Name:	S B WINGFIELD
App Addres:	1111 OLD BASTROP HIGHWAY
App City:	AUSTIN
App State:	TX
App Zip:	78742
App Areacd:	512
App Phone:	3853770
Per Status:	K
Orig Acres:	18
Pop Served:	500
Area Serve:	AUSTIN
Tons Day:	10
Yds Day:	0
Est Cl Dt:	19820501

(Continued) **S104731741**

River Cd:	14
Bus Cd:	2
Owner Name:	Edward Martin. Austin Vee Dub
Owner Add:	1111 OLD BASTROP HIGHWAY
Owner City/State/Zip:	Not reported
Stat Rem:	FILE UPDATED 04-17-00.
Resp Eng:	Not reported
Stat date:	0
A Open Dat:	19630101
A Close Da:	19840601
Update:	2
Reviewer1:	NO PERMIT ISSUED / K STATUS ASSIGNED 19840601
Confidence:	Not reported
Cog1:	Not reported
Twc Dist:	Not reported
Size Acres:	Not reported
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Not reported
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Not reported
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Not reported
Legal:	Not reported
Unauthor:	Not reported
Max Depth:	Not reported
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Inspection:	Not reported
Comment:	Deeds for two suspected parcles, plat map, TNRCC data sheet
Latitude:	30.22466667
Longitude:	-97.67166667
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=65

3186
ESE
1/4-1/2
0.308 mi.
1627 ft.

GARDNER IRON AND METAL
1201 E 4TH ST
AUSTIN, TX 78702

TX VCP **S111678648**
TX HIST UST **N/A**

Actual:
469 ft.

Focus Map:
11

VCP TCEQ:

Name:	GARDNER IRON AND METAL
Address:	1201 E 4TH ST
City,State,Zip:	AUSTIN, TX 78702
Region:	REGION 11 - AUSTIN
Facility ID:	2796
VCP Record Date:	12/18/2015
Facility Type:	PROPERTY COMMERCIAL; VACANT PROPERTY; PROPERTY RESIDENTIAL
PCA Number:	34989

GARDNER IRON AND METAL (Continued) **S111678648**

Project Manager:	RWINSOR
Phase:	COMPLETED
Acres at Site:	0.9
REM Program:	VCP
RN Number:	RN103161501
Former Facility Type:	RECYCLING
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	01/13/2016
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	NA
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	EXCAVATION/REMOVAL; STABILIZATION
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	NA
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	NA
Certificate of Completion Date:	03/22/2019
Standards:	A
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	12/18/2015
GW Target COC Class:	METALS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2016-01-20 00:00:00
Soil Target COC Class:	METALS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2796
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	349890
Off Site?:	NO
Media:	PAPER
IOP Number:	Not reported
File Location:	D2/295
Latitude:	30.26
Longitude:	-97.73

Contact:

REM Program:	VCP
Program ID:	2796
RN Number:	RN103161501
CN Number:	CN601694409
CN Name:	GARDNER IRON AND METAL CO INC
Role Code:	APPLCONT
Contact Name:	JOHNSON, JAMES
Contact Title:	PRESIDENT
Organization Name:	GARNER IRON AND METAL CO
Mailing Address:	8410 S CONGRESS AVE
Mailing City:	AUSTIN

GARDNER IRON AND METAL (Continued) **S111678648**

Mailing State:	TX
Mailing Zip:	78745
Contact Telephone:	(512) 247-8461
Contact Telephone Ext:	0

HIST UST AUSTIN:

Name:	GARDNER IRON AND METAL
Address:	1201 E 4TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0538
HID UST:	538
Inspection:	02/14/2009
Due:	02/14/2012

3187 **TXDOT** **TX RDR** **S127523904**
ESE **7901 N I 35 FRONTAGE RD** **N/A**
1/4-1/2 **AUSTIN, TX**
0.308 mi.
1628 ft.

Actual:
635 ft.

Focus Map:
21

RDR:

RDR ID:	23893
Facility ID:	10059
RN:	Not reported
CN:	Not reported
Name:	TXDOT
Address:	7901 N I 35 FRONTAGE RD
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/2/2016
Due Date:	10/1/2016
Tank Owner:	TXDOT
Contact Person:	RICK GREER
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	8/26/2016
Project Manager:	Ronnie Eason
Team:	#N/A
New LPST Number:	120009
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3188 ESE 1/4-1/2 0.310 mi. 1635 ft. | **GEORGE TORRES TEXACO 301 W KOENIG LN AUSTIN, TX 78751** | **TX LPST TX HIST UST TX ENF TX COMP HIST TX RDR** | **S107639190 N/A**

Actual: 652 ft.

Focus Map: 9

LPST:

Name:	GEORGE TORRES TEXACO
Address:	301 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0035774
LPST Id:	116141
Facility Location:	301 W KOENIG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin
Discovered Date:	04/09/2004
Entered Date:	09/28/2004
Reported Date:	09/03/2004
Closure Date:	02/04/2010
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT 500F
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater or storm water runoff is affected and discharges within 500 feet of the known extent of contamination to a surface water body used for human drinking water, contact recreation, habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/1P/1
Coordinators RPR:	MJK
Responsible Party Name:	Not reported
Responsible Party Contact:	GEORGE TORRES
Responsible Party Address:	301 W KOENIG LN
Responsible Party City,St,Zip:	AUSTIN, TX 78751
Responsible Party Telephone:	512/459-5869
Reported Date:	09/03/2004
Case Start Date:	02/04/2010
Reference Number:	RN101510295
Project Manager:	MKUNZENE

HIST UST AUSTIN:

Name:	B. O. DOERFLER
Address:	301 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Id UST:	H0657
HID UST:	657
Inspection:	Not reported
Due:	06/01/2012

ENFORCEMENT:

Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN101510295
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	RETAIL

GEORGE TORRES TEXACO (Continued) **S107639190**

Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	01/05/2000
Description 1:	FAILURE TO COMPLY
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	VERBAL
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	37.815[G]
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN101510295
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	01/05/2000
Description 1:	FAILURE TO COMPLY
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	VERBAL
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	334.50(d)(2)(A)

GEORGE TORRES TEXACO (Continued) **S107639190**

Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN101510295
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	01/05/2000
Description 1:	FAILURE TO COMPLY
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	VERBAL
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	334.49(e)[G]
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

Name:	TORRES TEXACO
Address:	301 W KOENIG LANE

GEORGE TORRES TEXACO (Continued) **S107639190**

City,State,Zip:	AUSTIN, TX
Unique TCEQ Ref Number Of Customer:	Not reported
Unique TCEQ Ref Number Of Reg. Entity:	RN101510295
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	Not reported
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	Not reported
Status Code:	Not reported
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	Not reported
Role Code:	Not reported
Date Notice Of Violation Issued:	03/14/2000
Description 1:	FAILURE TO COMPLY
Description 2:	Not reported
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	WASTE
TCEQ Rule Number Cited For The Violation:	334.50(b)(1)(A)
Status Of The NOV:	RESOLVED
Investigation:	Not reported
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	Not reported

COMP HIST:

RN Number:	RN101510295
Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN604471565
CN Name:	GEORGE TORRES TEXACO
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	337122
SIC Code:	5261
Related Number:	12650,12650

GEORGE TORRES TEXACO (Continued) **S107639190**

RN Number:	RN101510295
Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN605024066
CN Name:	TORRES TEXACO
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	315212
SIC Code:	1521
Related Number:	12650,12650

RN Number:	RN101510295
Name:	TORRES TEXACO
Address:	301 W KOENIG LANE
City,State,Zip:	AUSTIN, TX
Region:	REGION 11 - AUSTIN
CN Number:	CN600787378
CN Name:	TORRES, GEORGE
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	315212
SIC Code:	1521
Related Number:	12650,12650

RDR:

RDR ID:	13812
Facility ID:	35774
RN:	Not reported
CN:	Not reported
Name:	GEORGE TORRES TEXACO
Address:	301 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/3/2004
Due Date:	11/2/2004
Tank Owner:	GEORGE TORRES
Contact Person:	GEORGE TORRES
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Isiah Glover
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported

GEORGE TORRES TEXACO (Continued) **S107639190**

Comments:	IG - LADSCREEN. BENZENE, ETHYLBENZENE, AND TOLUENE CONCENTRATIONS IN TANKPIT WATER EXCEED ACTION LEVEL. NO MTBE ANALYSIS. SAW: TO HMW 9/27/04 FOR LPST #.
Review Coordinator:	IG
Date Release Reported:	9/3/04
Suspected:	N/A
Confirmed:	9/3/04
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	11
DKC RDR (misfiled):	Not reported

TL3189 **FORMER BROADDUS KOENIG LANE CHEVRON** **TX LPST** **S116701045**
WNW **1200 W KOENIG LN** **N/A**
1/4-1/2 **AUSTIN, TX 78752**
0.314 mi.
1657 ft. **Site 2 of 4 in cluster TL**

Actual:
672 ft.

Focus Map:
8

LPST:

Name:	FORMER BROADDUS KOENIG LANE CHEVRON
Address:	1200 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0000710
LPST Id:	117699
Facility Location:	1200 KOENIG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/17/2007
Entered Date:	05/01/2008
Reported Date:	02/28/2008
Closure Date:	11/20/2008
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	TH2
Responsible Party Name:	Not reported
Responsible Party Contact:	WILL HARDEMAN
Responsible Party Address:	6757 AIRPORT BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78756
Responsible Party Telephone:	512/454-6821
Reported Date:	02/28/2008
Case Start Date:	11/20/2008
Reference Number:	RN101697019
Project Manager:	THASAN

TL3190 WNW 1/4-1/2 0.314 mi. 1657 ft. | **FORMER KOENIG CHEVRON 1200 KOENIG LN AUSTIN, TX** | **TX RDR** | **S127538564 N/A**

Site 3 of 4 in cluster TL

Actual: 672 ft.

Focus Map: 8

RDR:

RDR ID:	17088
Facility ID:	710
RN:	Not reported
CN:	Not reported
Name:	FORMER KOENIG CHEVRON
Address:	1200 KOENIG LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/28/2008
Due Date:	4/28/2008
Tank Owner:	HARDEMAN FAMILY JOINT VEN
Contact Person:	WILL HARDEMAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	5/1/2008
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	117699
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?;LADSCREEN SENT 5/13/08
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TL3191 WNW 1/4-1/2 0.314 mi. 1657 ft. | **KOENIG LANE 66 1200 W KOENIG LN AUSTIN, TX 78752** | **TX LPST** | **S116703399 N/A**

Site 4 of 4 in cluster TL

Actual: 672 ft.

Focus Map: 8

LPST:

Name:	KOENIG LANE 66
Address:	1200 W KOENIG LN
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0000710
LPST Id:	096197
Facility Location:	1200 KOENIG LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/20/1990
Entered Date:	07/19/1990
Reported Date:	06/20/1990
Closure Date:	08/30/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2/5/2

KOENIG LANE 66 (Continued) **S116703399**

Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	DON BURNETT
Responsible Party Address:	2915 E 1ST ST
Responsible Party City,St,Zip:	AUSTIN, TX 78702
Responsible Party Telephone:	512/385-3030
Reported Date:	06/20/1990
Case Start Date:	08/30/1990
Reference Number:	RN101697019
Project Manager:	HWELCH

3192 ESE 1/4-1/2 0.314 mi. 1660 ft. **TEXACO SERVICE STATION 616 WILLIAM CANNON AUSTIN, TX** **TX RDR** **S127527616 N/A**

Actual: 653 ft.
Focus Map: 17

RDR:

RDR ID:	2511
Facility ID:	23189
RN:	Not reported
CN:	Not reported
Name:	TEXACO SERVICE STATION
Address:	616 WILLIAM CANNON
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	STAR ENTERPRISE
Contact Person:	Not reported
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/18/1997
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 6
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	7/18/1997
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3193 East 1/4-1/2 0.319 mi. 1686 ft. **ELIZABET NEY MUSEUM 304 E. 44TH STREET AUSTIN, TX 78751** **US BROWNFIELDS** **1026464115 N/A**

Actual: 613 ft.
Focus Map: 8

US BROWNFIELDS:

Name:	ELIZABET NEY MUSEUM
Address:	304 E. 44TH STREET
Recipient name:	Austin, City of

ELIZABET NEY MUSEUM (Continued) **1026464115**

Grant type:	BCRLF
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.306973
Longitude:	-97.726252
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The historic home and studio of Elisabet Ney, a wildly iconoclastic German sculptor who moved to Austin in 1882, The Elisabet Ney Museum enthusiastically celebrates her art, her history and her legacy through exhibitions and events for the whole family. The museum enjoys numerous historic designations and is a cornerstone of the Hyde Park National Register Historic Neighborhood. The Restoration Project will will include removal, restoration, and reinstallation of all the windows and doors as well as disturbance of some areas for new HVAC equipment.
Datum:	Not reported
Acres Property ID:	241059
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

ELIZABET NEY MUSEUM (Continued) **1026464115**

Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Building Materials
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	1
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1324
Below Poverty Percent:	23.62
Meidan Income:	7479
Meidan Income Number:	2303
Meidan Income Percent:	41.08
Vacant Housing Number:	98
Vacant Housing Percent:	3
Unemployed Number:	314
Unemployed Percent:	5.6

Name:	ELIZABET NEY MUSEUM
Address:	304 E. 44TH STREET
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.306973
Longitude:	-97.726252
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The historic home and studio of Elisabet Ney, a wildly iconoclastic German sculptor who moved to Austin in 1882, The Elisabet Ney Museum enthusiastically celebrates her art, her history and her legacy through exhibitions and events for the whole family. The museum enjoys numerous historic designations and is a cornerstone of the Hyde Park National Register Historic Neighborhood. The Restoration Project will will include removal, restoration, and reinstallation of all the windows and doors as well as disturbance of some areas for new HVAC equipment.
Datum:	Not reported
Acres Property ID:	241059
IC Data Access:	Not reported
Start Date:	10/21/2019
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	4354.81
Cleanup Funding Source:	City of Austin

ELIZABET NEY MUSEUM (Continued) **1026464115**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Cost Share
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Building Materials
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	1
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1324
Below Poverty Percent:	23.62
Meidan Income:	7479
Meidan Income Number:	2303
Meidan Income Percent:	41.08
Vacant Housing Number:	98
Vacant Housing Percent:	3
Unemployed Number:	314
Unemployed Percent:	5.6

ELIZABET NEY MUSEUM (Continued) **1026464115**

Name:	ELIZABET NEY MUSEUM
Address:	304 E. 44TH STREET
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.306973
Longitude:	-97.726252
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The historic home and studio of Elisabet Ney, a wildly iconoclastic German sculptor who moved to Austin in 1882, The Elisabet Ney Museum enthusiastically celebrates her art, her history and her legacy through exhibitions and events for the whole family. The museum enjoys numerous historic designations and is a cornerstone of the Hyde Park National Register Historic Neighborhood. The Restoration Project will will include removal, restoration, and reinstallation of all the windows and doors as well as disturbance of some areas for new HVAC equipment.
Datum:	Not reported
Acres Property ID:	241059
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N

ELIZABET NEY MUSEUM (Continued) **1026464115**

State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Building Materials
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	1
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1324
Below Poverty Percent:	23.62
Meidan Income:	7479
Meidan Income Number:	2303
Meidan Income Percent:	41.08
Vacant Housing Number:	98
Vacant Housing Percent:	3
Unemployed Number:	314
Unemployed Percent:	5.6

Name:	ELIZABET NEY MUSEUM
Address:	304 E. 44TH STREET
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.306973
Longitude:	-97.726252
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The historic home and studio of Elisabet Ney, a wildly iconoclastic German sculptor who moved to Austin in 1882, The Elisabet Ney Museum enthusiastically celebrates her art, her history and her legacy through exhibitions and events for the whole family. The museum enjoys numerous historic designations and is a cornerstone of the Hyde Park National Register Historic Neighborhood. The Restoration Project will will include removal, restoration, and reinstallation of all the windows and doors as well as disturbance of some areas for new HVAC equipment.
Datum:	Not reported
Acres Property ID:	241059
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported

ELIZABET NEY MUSEUM (Continued) **1026464115**

Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos Lead
Contaminant Cleanup:	Not reported
Media Affected:	Building Materials
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	1
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	1324
Below Poverty Percent:	23.62
Meidan Income:	7479
Meidan Income Number:	2303
Meidan Income Percent:	41.08
Vacant Housing Number:	98
Vacant Housing Percent:	3

ELIZABET NEY MUSEUM (Continued) **1026464115**

Unemployed Number: 314
Unemployed Percent: 5.6

3194 WNW 1/4-1/2 0.328 mi. 1732 ft. | **ST ELMO 502 W SAINT ELMO RD AUSTIN, TX 78745** | **TX LPST** | **S116696603 N/A**

Actual: 669 ft.
Focus Map: 17

LPST:

Name:	ST ELMO
Address:	502 W SAINT ELMO RD
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010995
LPST Id:	104325
Facility Location:	502 ST ELMO RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/11/1992
Entered Date:	09/03/1992
Reported Date:	08/13/1992
Closure Date:	07/25/1994
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	HLN
Responsible Party Name:	Not reported
Responsible Party Contact:	WES WALTERS
Responsible Party Address:	8830 BUSINESS PARK
Responsible Party City,St,Zip:	AUSTIN, TX 78759
Responsible Party Telephone:	512/345-2060
Reported Date:	08/13/1992
Case Start Date:	07/25/1994
Reference Number:	RN101491868
Project Manager:	HLN

3195 East 1/4-1/2 0.334 mi. 1764 ft. | **CAZARES PROPERTY 1112 E 6TH ST AUSTIN, TX 78702** | **TX HIST UST TX IHW CORR ACTION TX RDR TX NON REGIST PST** | **S111678649 N/A**

Actual: 496 ft.
Focus Map: 11

HIST UST AUSTIN:

Name:	GEORGES SERVICE STATION
Address:	1112 E 6TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	H0156
HID UST:	156
Inspection:	12/15/2010
Due:	12/15/2013

CAZARES PROPERTY (Continued) **S111678649**

IHW CORR ACTION:

Name:	CAZARES PROPERTY
Address:	1112 E 6TH ST
City,State,Zip:	AUSTIN, TX 78702
Program Id:	T0497
Location Desc:	CORNER OF 6TH AND MEDINA
RN NUM:	RN104285804
Status:	INACTIVE
Status Date:	01/05/2017
EDR Link ID:	T0497
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	01/05/2017
Soil COC Class:	Not reported
Soil Remediation:	Not reported
GW COC Class:	Not reported
GW Remediation:	Not reported

RDR:

RDR ID:	13687
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	CAZARES PROPERTY
Address:	1112 E 6TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/16/2004
Due Date:	9/14/2004
Tank Owner:	JOHN CAZARES
Contact Person:	JOHN CAZARES
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/18/2004
Project Manager:	Trudy Hasan
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NOL RECOMMENDED.
Review Coordinator:	TH2
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	10/18/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

NON REGIST PST:

RN Number:	RN104285804
Name:	CAZARES PROPERTY
Address:	1112 E 6TH ST
City,State,Zip:	AUSTIN, TX 78702 3211
Physical Location:	Corner of 6th and Medina
CN Number:	CN602639304
Customer Name:	CAZARES, JOHN A
Customer Role:	N/A
Primary Business:	Vacant lot

CAZARES PROPERTY (Continued) **S111678649**

Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=995546062004155

RN Number:	RN104285804
Name:	CAZARES PROPERTY
Address:	1112 E 6TH ST
City,State,Zip:	AUSTIN, TX 78702 3211
Physical Location:	Corner of 6th and Medina
CN Number:	CN602859803
Customer Name:	ROBERTOS RADIATOR SERVICE
Customer Role:	OWNER OPERATOR
Primary Business:	Vacant lot
Code:	Not reported
Classification:	Not reported
Industry Name:	Not reported
Program:	PETROLEUM STORAGE TANK NON REGISTERED
ID Number:	Not reported
ID Type:	Not reported
ID Status:	Not reported
URL:	https://www15.tceq.texas.gov/crpub/index.cfm?fuseaction=regent.showSingleRN&re_id=995546062004155

3196 **MERCEDES BENZ OF AUSTIN** **TX LPST** **1000412782**
ESE **6757 AIRPORT BLVD** **RCRA NonGen / NLR** **TXD982556425**
1/4-1/2 **AUSTIN, TX 78752** **FINDS**
0.339 mi. **ECHO**
1788 ft. **TX Ind. Haz Waste**
TX CENTRAL REGISTRY

Actual:
694 ft.

Focus Map:
6

LPST:

Name:	CONTINENTAL CARS
Address:	6757 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0060930
LPST Id:	105936
Facility Location:	6757 AIRPORT
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/21/1993
Entered Date:	02/19/1993
Reported Date:	01/21/1993
Closure Date:	02/09/1993
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	BRYAN HARDEMAN

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Responsible Party Address:	6757 AIRPORT BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/454-4579
Reported Date:	01/21/1993
Case Start Date:	02/09/1993
Reference Number:	RN100708072
Project Manager:	HWELCH

RCRA Listings:

Date Form Received by Agency:	20030821
Handler Name:	Continental Cars Ltd
Handler Address:	AIRPORT BLVD
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD982556425
Contact Name:	DON BECKER
Contact Address:	AIRPORT BLVD
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-454-6821
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	AIRPORT BLVD
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Continental Cars Ltd
Owner Type:	Not reported
Operator Name:	Continental Cars Ltd
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D021
Waste Description:	Chlorobenzene
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CONTINENTAL CARS LTD	
Legal Status:	Not reported
Date Became Current:	20030821
Date Ended Current:	Not reported
Owner/Operator Address:	6757 AIRPORT BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-6821
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BRYAN HARDEMAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	000-000-0000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CONTINENTAL CARS LTD	
Legal Status:	Not reported
Date Became Current:	20030821
Date Ended Current:	Not reported
Owner/Operator Address:	6757 AIRPORT BLVD
Owner/Operator City,State,Zip:	AUSTIN, TX 78752
Owner/Operator Telephone:	512-454-6821
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19880902
Handler Name: CONTINENTAL CARS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20030821
Handler Name: CONTINENTAL CARS LTD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	42111
NAICS Description:	AUTOMOBILE AND OTHER MOTOR VEHICLE WHOLESALERS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110005108588

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Texas Commission on Environmental Quality - Agency Central Registry (TX-TCEQ ACR) is a computer application that allows the Texas Commission on Environmental Quality (TCEQ) to use a single, centralized area to record common information, such as the company

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

names, addresses, and telephone numbers of those the TCEQ regulates.
It also contains additional IDs (permits, registrations,
authorizations, etc) and their status.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412782
Registry ID:	110005108588
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005108588
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752

Ind. Haz Waste:

Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	72834
Registration Initial Notification Date:	08/05/1988
Registration Last Amendment Date:	08/21/2003
EPA Identification:	TXD982556425
Primary NAICS Code:	423110
Status Change Date:	19880805
Land Type:	Not reported
Description of Facility Site Location:	6757 Airport Blvd, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	CESQG
Type of Generator:	NON INDUS
Company Name:	CONTINENTAL CARS LTD
Contact Name:	DON BECKER
Contact Telephone Number:	512-4546821
Mailing Address:	6757 AIRPORT BLVD
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787523602
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	27272
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040617
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CONTINENTAL CARS LTD
Operator Address:	6757 AIRPORT BLVD
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4546821
Operator Fax Number:	1-512-4542878
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	32014348521
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CONTINENTAL CARS LTD
Owner Mailing Address:	6757 AIRPORT BLVD
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4546821
Owner Fax:	1-512-4542878
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	32014348521
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	6757 AIRPORT BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4546821
Contact Fax:	1-512-4542878
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	6757 AIRPORT BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4546821
Contact Fax:	1-512-4542878
Contact Email:	Not reported

Contact Name:	DON BECKER
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	6757 AIRPORT BLVD
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4546821
Contact Fax:	1-512-4542878
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	139585
Texas Waste Code:	Not reported
Texas Waste Code 2:	0501203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	SPENT SOLVENT
Standard Industrial Code:	55110
Primary Source:	G09
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012111
Primary NAICS Code:	441110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139586
Texas Waste Code:	Not reported
Texas Waste Code 2:	0523211H
Waste Code Status:	INACTIVE
Waste Form:	211
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	PAINT WASTE
Standard Industrial Code:	75320
Primary Source:	G06
Primary Measurement Point:	Not reported

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169411167
Primary NAICS Code:	811121
EPA Waste Form Code:	W211
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	139587
Texas Waste Code:	Not reported
Texas Waste Code 2:	0566203H
Waste Code Status:	INACTIVE
Waste Form:	203
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	IMMERSION CLEANER
Standard Industrial Code:	55110
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	6169012111
Primary NAICS Code:	441110
EPA Waste Form Code:	W203
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Waste ID:	156046
Texas Waste Code:	Not reported
Texas Waste Code 2:	0839102H
Waste Code Status:	INACTIVE
Waste Form:	102

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Brake cleaner; aqueous brake solution used to clean brakes during repair process
Standard Industrial Code:	50120
Primary Source:	G01
Primary Measurement Point:	Not reported
Primary Origin:	1
Primary System Type:	Not reported
New Chemical Substance:	0
Audit Performed:	0
Company Waste ID:	Not reported
Primary NAICS Code:	423110
EPA Waste Form Code:	W101
Reason Waste Form No Longer Gen:	UNKNOWN

Ind. Haz Waste:

Ind. Haz Waste:

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6757 AIRPORT BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000312242
Principal Name:	CONTINENTAL CARS LTD
Attention Name:	Not reported
Attention Suffix:	HWG

Contact Name:	Not reported
Contact Title:	Not reported
Contact Telephone:	Not reported
Mailing Address:	6757 AIRPORT BLVD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000312242
Principal Name:	CONTINENTAL CARS LTD
Attention Name:	Not reported
Attention Suffix:	NWG

CENTRAL REGISTRY:

Regulated Entity Number:	RN100708072
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3602
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/21/2003
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	423110
Primary NAICS Industry Type Description:	Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description:	6757 Airport Blvd, Austin, TX

Regulated Entity Number:	RN100708072
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3602
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/21/2003
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	423110
Primary NAICS Industry Type Description:	Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description:	6757 Airport Blvd, Austin, TX

Regulated Entity Number:	RN100708072
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3602
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/21/2003
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	423110
Primary NAICS Industry Type Description:	Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description:	6757 Airport Blvd, Austin, TX

Regulated Entity Number:	RN100708072
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3602
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601256514
Customer Name:	CONTINENTAL IMPORTS INC
Customer Legal Name:	Continental Imports, Inc.
Customer Ownership Type:	CORPORATION

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Affiliation Begin Date: 10/21/1991
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN601256514
Customer Name: CONTINENTAL IMPORTS INC
Customer Legal Name: Continental Imports, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 10/21/1991
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN601256514
Customer Name: CONTINENTAL IMPORTS INC
Customer Legal Name: Continental Imports, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 10/21/1991
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN604383521
Customer Name: WLE LLC
Customer Legal Name: Wle LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/23/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN604383521
Customer Name: WLE LLC
Customer Legal Name: Wle LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/23/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN604383521
Customer Name: WLE LLC
Customer Legal Name: Wle LLC
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 9/23/2022
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

Regulated Entity Number: RN100708072
Name: MERCEDES BENZ OF AUSTIN
Address: 6757 AIRPORT BLVD
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3602
Status: ACTIVE
Status Date: ##########
Customer Number: CN604446906
Customer Name: CONTINENTAL CARS
Customer Legal Name: Continental Cars
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 423110
Primary NAICS Industry Type Description: Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description: 6757 Airport Blvd, Austin, TX

MERCEDES BENZ OF AUSTIN (Continued) **1000412782**

Regulated Entity Number:	RN100708072
Name:	MERCEDES BENZ OF AUSTIN
Address:	6757 AIRPORT BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3602
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604446906
Customer Name:	CONTINENTAL CARS
Customer Legal Name:	Continental Cars
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	423110
Primary NAICS Industry Type Description:	Automobile and Other Motor Vehicle Merchant Wholesalers
Physical Location Description:	6757 Airport Blvd, Austin, TX

Click this hyperlink while viewing on your computer to access
14 additional TX CENTRAL REG: record(s) in the EDR Site Report.

TO3197 **FORMER AIRPORT EXXON** **TX VCP** **S123820012**
East **2511 HWY 71 E** **N/A**
1/4-1/2 **DEL VALLE, TX 78617**
0.339 mi.
1788 ft. **Site 1 of 3 in cluster TO**

Actual:
509 ft.

Focus Map:
20

VCP TCEQ:

Name:	FORMER AIRPORT EXXON
Address:	2511 HWY 71 E
City,State,Zip:	DEL VALLE, TX 78617
Region:	REGION 11 - AUSTIN
Facility ID:	2672
VCP Record Date:	05/12/2014
Facility Type:	GAS STATION
PCA Number:	34864
Project Manager:	DCHRISTI
Phase:	WITHDRAWN
Acres at Site:	0.9313
REM Program:	VCP
RN Number:	RN101510188
Former Facility Type:	GAS STATION
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	Not reported
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported

FORMER AIRPORT EXXON (Continued) **S123820012**

Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	Not reported
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	05/09/2014
GW Target COC Class:	VOCS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2014-06-23 00:00:00
Soil Target COC Class:	VOCS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2672
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	348640
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D2/211N
Latitude:	30.21
Longitude:	-97.66

Contact:

REM Program:	VCP
Program ID:	2672
RN Number:	RN101510188
CN Number:	CN604593533
CN Name:	RUSSELL INTERESTS INC
Role Code:	APPLCONT
Contact Name:	RUSSELL, WILLIAM
Contact Title:	PRESIDENT
Organization Name:	Not reported
Mailing Address:	1440 MOUNT LARSON RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Contact Telephone:	(512) 347-7744
Contact Telephone Ext:	0

TO3198 **FORMER AIRPORT EXXON** **TX LPST** **S116701129**
East **2511 HIGHWAY 71 E** **N/A**
1/4-1/2 **DEL VALLE, TX**
0.339 mi.
1788 ft. **Site 2 of 3 in cluster TO**

Actual:
509 ft.

Focus Map:
20

LPST:

Name:	FORMER AIRPORT EXXON
Address:	2511 HIGHWAY 71 E
City,State,Zip:	DEL VALLE, TX
Facility ID:	0067980
LPST Id:	117952
Facility Location:	2511 HWY 71 E
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/21/2008

FORMER AIRPORT EXXON (Continued) **S116701129**

Entered Date:	01/22/2009
Reported Date:	12/29/2008
Closure Date:	02/04/2010
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	EM2
Responsible Party Name:	Not reported
Responsible Party Contact:	DEREK LIN
Responsible Party Address:	3215 WINDSOR RD
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/423-0932
Reported Date:	12/29/2008
Case Start Date:	02/04/2010
Reference Number:	RN101510188
Project Manager:	EMILLER

TO3199 **STATE HIGHWAY 71 E 2511** **US BROWNFIELDS** **1011995390**
East **2511 HIGHWAY 71 E** **FINDS** **N/A**
1/4-1/2 **DEL VALLE, TX 78617**
0.339 mi.
1788 ft. **Site 3 of 3 in cluster TO**

Actual:
509 ft.

Focus Map:
20

US BROWNFIELDS:

Name:	STATE HIGHWAY 71 E 2511
Address:	2511 HIGHWAY 71 E
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	291978
Parcel size:	0.93
Latitude:	30.213187
Longitude:	-97.658037
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	This former Mobil service station and convenience store has been vacant for two years. The new owners are working to remove the underground storage tanks. The property is available for lease or purchase. In addition to the service station and convenience store, the other onsite building is a former Mexican Restaurant located on the east of the property. Only a short distance from the Austin Bergstrom International Airport ABIA, the property has unlimited reuse potential. Revitalization within the ABIA corridor has been sluggish due to economic factors, but it is expected to improve within the next few years. The property sits at the ABIA entrance. The property owner is planning to remove the tanks and market the property for purchase. Former Use: The property houses a closed service station with restaurant and convenient store facilities.
Datum:	North American Datum of 1983
Acres Property ID:	67843
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	John Chen
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	12/27/1995
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	2/4/2010
Contaminant Found:	PAHs Petroleum Products VOCs
Contaminant Cleanup:	PAHs Petroleum Products VOCs
Media Affected:	Ground Water
Media Cleanup:	Ground Water
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.93
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property houses a closed service station with restaurant and convenient store facilities.
Below Poverty Number:	211
Below Poverty Percent:	49.88
Meidan Income:	24611
Meidan Income Number:	268
Meidan Income Percent:	63.36

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Vacant Housing Number:	21
Vacant Housing Percent:	13.25
Unemployed Number:	26
Unemployed Percent:	6.15
Name:	STATE HIGHWAY 71 E 2511
Address:	2511 HIGHWAY 71 E
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	291978
Parcel size:	0.93
Latitude:	30.213187
Longitude:	-97.658037
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	This former Mobil service station and convenience store has been vacant for two years. The new owners are working to remove the underground storage tanks. The property is available for lease or purchase. In addition to the service station and convenience store, the other onsite building is a former Mexican Restaurant located on the east of the property. Only a short distance from the Austin Bergstrom International Airport ABIA, the property has unlimited reuse potential. Revitalization within the ABIA corridor has been sluggish due to economic factors, but it is expected to improve within the next few years. The property sits at the ABIA entrance. The property owner is planning to remove the tanks and market the property for purchase. Former Use: The property houses a closed service station with restaurant and convenient store facilities.
Datum:	North American Datum of 1983
Acres Property ID:	67843
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	5820
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	96600601
Start Date:	12/5/2007
Ownership Entity:	Private
Completion Date:	3/28/2008
Current Owner:	John Chen
Did Owner Change:	N

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	12/27/1995
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	2/4/2010
Contaminant Found:	PAHs Petroleum Products VOCs
Contaminant Cleanup:	PAHs Petroleum Products VOCs
Media Affected:	Ground Water
Media Cleanup:	Ground Water
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.93
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property houses a closed service station with restaurant and convenient store facilities.
Below Poverty Number:	211
Below Poverty Percent:	49.88
Meidan Income:	24611
Meidan Income Number:	268
Meidan Income Percent:	63.36
Vacant Housing Number:	21
Vacant Housing Percent:	13.25
Unemployed Number:	26
Unemployed Percent:	6.15
Name:	STATE HIGHWAY 71 E 2511
Address:	2511 HIGHWAY 71 E
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	291978
Parcel size:	0.93
Latitude:	30.213187
Longitude:	-97.658037
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	This former Mobil service station and convenience store has been vacant for two years. The new owners are working to remove the underground storage tanks. The property is available for lease or purchase. In addition to the service station and convenience store,

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

	the other onsite building is a former Mexican Restaurant located on the east of the property. Only a short distance from the Austin Bergstrom International Airport ABIA, the property has unlimited reuse potential. Revitalization within the ABIA corridor has been sluggish due to economic factors, but it is expected to improve within the next few years. The property sits at the ABIA entrance. The property owner is planning to remove the tanks and market the property for purchase. Former Use: The property houses a closed service station with restaurant and convenient store facilities.
Datum:	North American Datum of 1983
Acres Property ID:	67843
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	John Chen
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	12/27/1995
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	2/4/2010
Contaminant Found:	PAHs Petroleum Products VOCs
Contaminant Cleanup:	PAHs Petroleum Products VOCs
Media Affected:	Ground Water
Media Cleanup:	Ground Water
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.93

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property houses a closed service station with restaurant and convenient store facilities.
Below Poverty Number:	211
Below Poverty Percent:	49.88
Meidan Income:	24611
Meidan Income Number:	268
Meidan Income Percent:	63.36
Vacant Housing Number:	21
Vacant Housing Percent:	13.25
Unemployed Number:	26
Unemployed Percent:	6.15
Name:	STATE HIGHWAY 71 E 2511
Address:	2511 HIGHWAY 71 E
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	291978
Parcel size:	0.93
Latitude:	30.213187
Longitude:	-97.658037
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	This former Mobil service station and convenience store has been vacant for two years. The new owners are working to remove the underground storage tanks. The property is available for lease or purchase. In addition to the service station and convenience store, the other onsite building is a former Mexican Restaurant located on the east of the property. Only a short distance from the Austin Bergstrom International Airport ABIA, the property has unlimited reuse potential. Revitalization within the ABIA corridor has been sluggish due to economic factors, but it is expected to improve within the next few years. The property sits at the ABIA entrance. The property owner is planning to remove the tanks and market the property for purchase. Former Use: The property houses a closed service station with restaurant and convenient store facilities.
Datum:	North American Datum of 1983
Acres Property ID:	67843
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	22551
Assessment Funding Source:	EPA

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	96600601
Start Date:	6/13/2008
Ownership Entity:	Private
Completion Date:	9/19/2008
Current Owner:	John Chen
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	12/27/1995
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	2/4/2010
Contaminant Found:	PAHs Petroleum Products VOCs
Contaminant Cleanup:	PAHs Petroleum Products VOCs
Media Affected:	Ground Water
Media Cleanup:	Ground Water
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.93
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property houses a closed service station with restaurant and convenient store facilities.
Below Poverty Number:	211
Below Poverty Percent:	49.88
Meidan Income:	24611
Meidan Income Number:	268
Meidan Income Percent:	63.36
Vacant Housing Number:	21
Vacant Housing Percent:	13.25
Unemployed Number:	26
Unemployed Percent:	6.15
Name:	STATE HIGHWAY 71 E 2511

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

Address:	2511 HIGHWAY 71 E
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	291978
Parcel size:	0.93
Latitude:	30.213187
Longitude:	-97.658037
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	This former Mobil service station and convenience store has been vacant for two years. The new owners are working to remove the underground storage tanks. The property is available for lease or purchase. In addition to the service station and convenience store, the other onsite building is a former Mexican Restaurant located on the east of the property. Only a short distance from the Austin Bergstrom International Airport ABIA, the property has unlimited reuse potential. Revitalization within the ABIA corridor has been sluggish due to economic factors, but it is expected to improve within the next few years. The property sits at the ABIA entrance. The property owner is planning to remove the tanks and market the property for purchase. Former Use: The property houses a closed service station with restaurant and convenient store facilities.
Datum:	North American Datum of 1983
Acres Property ID:	67843
IC Data Access:	PST Registration Database http://www.tceq.state.tx.us/permitting/registration/pst/pst_query.html
Start Date:	1/1/2009
Redev Completition Date:	Not reported
Completed Date:	2/4/2010
Acres Cleaned Up:	0.93
Cleanup Funding:	25000
Cleanup Funding Source:	Mr. John Chen & Lin Derek, Lmtd.
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Private/Other Funding
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	96600601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	John Chen
Did Owner Change:	N
Cleanup Required:	Y
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Y

STATE HIGHWAY 71 E 2511 (Continued) **1011995390**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	12/27/1995
IC in place:	Y
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	2/4/2010
Contaminant Found:	PAHs Petroleum Products VOCs
Contaminant Cleanup:	PAHs Petroleum Products VOCs
Media Affected:	Ground Water
Media Cleanup:	Ground Water
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.93
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property houses a closed service station with restaurant and convenient store facilities.
Below Poverty Number:	211
Below Poverty Percent:	49.88
Meidan Income:	24611
Meidan Income Number:	268
Meidan Income Percent:	63.36
Vacant Housing Number:	21
Vacant Housing Percent:	13.25
Unemployed Number:	26
Unemployed Percent:	6.15

FINDS:
Registry ID: 110038718876

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3200 SW 1/4-1/2 0.341 mi. 1799 ft.

Actual: 575 ft.

Focus Map: 14

OLTORF FOOD MART
2225 E OLTORF ST
AUSTIN, TX 78741

TX LPST **U003149009**
TX UST **N/A**
TX HIST UST
TX ASBESTOS
TX Financial Assurance
TX GCC
TX RDR

LPST:

Name:	SPEEDY STOP 218
Address:	2225 E OLTORF ST

OLTORF FOOD MART (Continued) **U003149009**

City,State,Zip:	AUSTIN, TX 78723
Facility ID:	0025762
LPST Id:	117966
Facility Location:	2225 E OLTORF ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/10/2008
Entered Date:	02/02/2009
Reported Date:	11/17/2008
Closure Date:	05/21/2009
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	MWB
Responsible Party Name:	Not reported
Responsible Party Contact:	CARLTON LABEFF
Responsible Party Address:	PO BOX 1876
Responsible Party City,St,Zip:	VICTORIA, TX 77902 1876
Responsible Party Telephone:	361/582-5121
Reported Date:	11/17/2008
Case Start Date:	05/21/2009
Reference Number:	RN101499465
Project Manager:	MBRATBER

UST:

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 787414543
AI Number:	25762
Facility Type:	RETAIL
Facility Begin Date:	01/01/1980
Facility Status:	ACTIVE
Additional ID:	180512422002054
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	RAHIMBHAL MOMIN,MGR
Contact Organization Name:	OLTORF FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5129037063
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/10/2021
Signature Name/Title On Earliest Reg Form:	ALI KARIM,REP

OLTORF FOOD MART (Continued) **U003149009**

Application Received Date On Earliest Reg Form: 03/11/2021
Signature Role On Earliest Reg Form: LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: No
Facility Not Inspectable: No

Operator:
Princ ID: 360510842019063
Additional ID: 180512422002054
Ai Number: 25762
Operator CN: CN605631993
Operator Name: SRA BUSINESS INC
Operator Effective Begin Date: 11/01/2018
Operator Type: CO
Operator Role: Not reported
Contact Name: /
Contact Organization Name: Not reported
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: -
Contact Phone Country Code: Not reported
Contact Phone Area Code: Not reported
Contact Phone Number: Not reported
Contact Phone Extension: Not reported
Contact Fax Country Code: Not reported
Contact Fax Area Code: Not reported
Contact Fax Number: Not reported
Contact Fax Extension: Not reported
Contact Email Address: Not reported
Contact Address Deliverable: Not reported

Owner:
Owner CN: CN603742180
Owner Last Name: ENTRUST HOLDINGS INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported
Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 167357632010302
Additional ID: 180512422002054
AI Number: 25762
Owner Effective Begin Date: 10/31/2008
State Tax ID: 32037799767
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

OLTORF FOOD MART (Continued) **U003149009**

Self Certification:

Self Cert ID:	75932
Cert ID:	366838
AI Number:	25762
Self Certification Date:	02/07/2022
Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	351607
AI Number:	25762
Self Certification Date:	03/10/2021
Signature Name/Title:	ALI KARIM REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	332904
AI Number:	25762
Self Certification Date:	01/24/2020
Signature Name/Title:	ASMITA MAREDIA REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	317439
AI Number:	25762
Self Certification Date:	03/04/2019
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	300817
AI Number:	25762
Self Certification Date:	03/05/2018
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	283816
AI Number:	25762
Self Certification Date:	03/07/2017
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	266364
AI Number:	25762
Self Certification Date:	02/19/2016
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	250819
AI Number:	25762
Self Certification Date:	03/09/2015
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	75932
Cert ID:	232398
AI Number:	25762
Self Certification Date:	02/19/2014
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	110738
AI Number:	25762
Self Certification Date:	03/11/2013
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110737
AI Number:	25762
Self Certification Date:	02/14/2012
Signature Name/Title:	ISMAIL ALI PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110736
AI Number:	25762
Self Certification Date:	02/28/2011
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	110735
AI Number:	25762
Self Certification Date:	01/25/2010
Signature Name/Title:	ISMAIL ALI PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110734
AI Number:	25762
Self Certification Date:	03/23/2009
Signature Name/Title:	MOHAMMED ALI MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110733
AI Number:	25762
Self Certification Date:	01/28/2008
Signature Name/Title:	CARLTON LABEFF AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	110732
AI Number:	25762
Self Certification Date:	01/02/2007
Signature Name/Title:	CARLTON L LABEFF AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110731
AI Number:	25762
Self Certification Date:	01/27/2006
Signature Name/Title:	CARLTON L LABEFF OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110730
AI Number:	25762
Self Certification Date:	12/22/2004
Signature Name/Title:	CARLTON L LABEFF OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	110729
AI Number:	25762
Self Certification Date:	12/30/2003
Signature Name/Title:	CARLTON L LABEFF AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110728
AI Number:	25762
Self Certification Date:	12/27/2002
Signature Name/Title:	CARLTON LABEFF AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110727
AI Number:	25762
Self Certification Date:	06/18/2002
Signature Name/Title:	CARLTON LABEFF AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Self Cert ID:	75932
Cert ID:	110726
AI Number:	25762
Self Certification Date:	05/01/2002
Signature Name/Title:	ROBERT J BYRNES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	10/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	75932
Cert ID:	110725
AI Number:	25762
Self Certification Date:	01/02/2001
Signature Name/Title:	RHONDA PAXTON ENVIR MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1980
Tank Registration Date:	12/11/1987
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	66114
Facility ID:	75932
Ai Number:	25762
Tank Id:	3
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	10/25/2022
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N

OLTORF FOOD MART (Continued) **U003149009**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	9816
UST Comprt ID:	121530
UST ID:	66114
AI Number:	25762
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

OLTORF FOOD MART (Continued) **U003149009**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1980
Tank Registration Date:	12/11/1987
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	66116
Facility ID:	75932
Ai Number:	25762
Tank Id:	1
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	10/25/2022
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y

OLTORF FOOD MART (Continued) **U003149009**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	9816
UST Comprt ID:	121532
UST ID:	66116
AI Number:	25762
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

OLTORF FOOD MART (Continued) **U003149009**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1980
Tank Registration Date:	12/11/1987
Number of Compartments:	1
Tank Capacity:	9816
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	66115
Facility ID:	75932
Ai Number:	25762
Tank Id:	2
Tank Status (Current):	TEMP OUT OF SERVICE
Tank Status Date:	10/25/2022
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

OLTORF FOOD MART (Continued) **U003149009**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	9816
UST Comprt ID:	121531
UST ID:	66115
AI Number:	25762
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

OLTORF FOOD MART (Continued) **U003149009**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	10902
Facility ID:	75932
AI Number:	25762
Application Received Date:	10/16/2002
Scheduled Construction Date:	11/15/2002
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M21016016
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21589
General Desc Of Prop Construct:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ENTRUST HOLDINGS INC
Contact Mailing Address (Delivery):	8870 BUSINESS PARK DR STE 100
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78759 7519
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	75932
Additional ID:	180512422002054

OLTORF FOOD MART (Continued) **U003149009**

Princ ID:	167357632010302
AI Number:	25762
Facility Name:	OLTORF FOOD MART
AR Number:	69663
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ISMAIL ALI/

HIST UST AUSTIN:

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	3013
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	03/19/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/27/2013
Date Routed by Supervisor:	03/27/2013
Date Routed to PSQA:	04/01/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Date of inspection:	04/15/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/22/2014
Date Routed by Supervisor:	04/23/2014
Date Routed to PSQA:	04/24/2014

OLTORF FOOD MART (Continued) **U003149009**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	264431
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported

OLTORF FOOD MART (Continued) **U003149009**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2021
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000023660
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	247577
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2020
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000014314
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	227739
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2019
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

OLTORF FOOD MART (Continued) **U003149009**

Policy Number:	04-TOP-000005596
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	211144
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2018
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-000108794
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	194093
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2017
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000103474
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741

OLTORF FOOD MART (Continued) **U003149009**

Region:	2
Facility ID:	75932
Finass ID:	176795
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2016
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00098964
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	158112
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2015
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04to00094674
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	141810
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

OLTORF FOOD MART (Continued) **U003149009**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2014
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-90453
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	123602
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2013
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 979 7762626
Policy Number:	04-TO-00086412
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	7721
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2012
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00082453
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/03/2013

OLTORF FOOD MART (Continued) **U003149009**

Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	60621
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2009
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 979 7762626
Policy Number:	04-TO-071455
Coverage Amount:	1000000
Coverage Expiration Date:	11/03/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	60622
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/03/2008
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 979 7762626
Policy Number:	84165
Coverage Amount:	1000000
Coverage Expiration Date:	11/03/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	60623

OLTORF FOOD MART (Continued) **U003149009**

AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/2007
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 0 0
Policy Number:	17722
Coverage Amount:	2000000
Coverage Expiration Date:	12/31/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	OLTORF FOOD MART
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78741
Region:	2
Facility ID:	75932
Finass ID:	60624
AI:	25762
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/11/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	SPEEDY STOP FOOD STORES LTD
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	*
File Number:	117966
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	2/2/2009
Enforcement Status - Level Of Agency Response:	6 -
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

OLTORF FOOD MART (Continued) **U003149009**

Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

RDR:

RDR ID:	17777
Facility ID:	25762
RN:	Not reported
CN:	Not reported
Name:	SPEEDY STOP 218
Address:	2225 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/17/2008
Due Date:	1/16/2009
Tank Owner:	SPEEDY STOP FOOD STORE
Contact Person:	CARLTON LABEFF
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	2/2/2009
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	117966
Pre-Existing LPST Number:	Not reported
Comments:	LADSCREEN SENT 2/12/09
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3201 North 1/4-1/2 0.342 mi. 1805 ft. **SOUTHWESTERN BELL 650 BASTROP HWY AUSTIN, TX** **TX RDR** **S127526380 N/A**

Actual: 457 ft.

Focus Map: 15

RDR:

RDR ID:	1674
Facility ID:	19347
RN:	Not reported
CN:	Not reported
Name:	SOUTHWESTERN BELL
Address:	650 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/1/1901
Due Date:	3/2/1901
Tank Owner:	SOUTHWESTERN BELL
Contact Person:	JONELL WESTERBERG
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	4/21/1997
Project Manager:	Not reported

SOUTHWESTERN BELL (Continued) **S127526380**

Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	SENT TO STATE LIBRARY BOX 20
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	4/21/1997
Region:	Not reported
DKC RDR (misfiled):	Not reported

3202 SE 1/4-1/2 0.345 mi. 1819 ft. **RED ARROW FREIGHT LINES**
8080 PURNELL DR
AUSTIN, TX 78753

TX LPST **U001242949**
TX UST **N/A**
TX HIST UST
TX Ind. Haz Waste

Actual: 733 ft.

Focus Map: 6

LPST:

Name:	RED ARROW FREIGHT LINES
Address:	8080 PURNELL DR
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0006440
LPST Id:	094319
Facility Location:	8080 PURNELL DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/20/1989
Entered Date:	01/16/1990
Reported Date:	12/20/1989
Closure Date:	02/10/1999
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	SMR
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE BURGER
Responsible Party Address:	PO BOX 10338
Responsible Party City,St,Zip:	JEFFERSON, LA 70181
Responsible Party Telephone:	504/837-4400
Reported Date:	12/20/1989
Case Start Date:	02/10/1999
Reference Number:	RN101698389
Project Manager:	SRAINEY

UST:

Name:	RED ARROW FREIGHT LINES
Address:	8080 PURNELL DR
City,State,Zip:	AUSTIN, TX 787536328
AI Number:	6440
Facility Type:	UNKNOWN
Facility Begin Date:	01/28/1986
Facility Status:	INACTIVE

RED ARROW FREIGHT LINES (Continued) **U001242949**

Additional ID:	752451062002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/1986
Signature Name/Title On Earliest Reg Form:	MICHAEL PIERCE,DIRECTOR MAINTENANCE
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600355069
Owner Last Name:	RED ARROW FREIGHT LINES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	353323402001309
Additional ID:	752451062002075
AI Number:	6440
Owner Effective Begin Date:	01/28/1986
State Tax ID:	17408545709
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1

RED ARROW FREIGHT LINES (Continued) **U001242949**

Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	16648
Facility ID:	41608
Ai Number:	6440
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

RED ARROW FREIGHT LINES (Continued) **U001242949**

Tank Tested Flag:	Y
Installation Signature Date:	05/10/1991
Compartment Records:	
Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	10456
UST ID:	16648
AI Number:	6440
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	16649
Facility ID:	41608
Ai Number:	6440
Tank Id:	2

RED ARROW FREIGHT LINES (Continued) **U001242949**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/10/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	10457
UST ID:	16649
AI Number:	6440

RED ARROW FREIGHT LINES (Continued) **U001242949**

Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	16650
Facility ID:	41608
Ai Number:	6440
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

RED ARROW FREIGHT LINES (Continued) **U001242949**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/10/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	8000
UST Comprt ID:	10458
UST ID:	16650
AI Number:	6440
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

RED ARROW FREIGHT LINES (Continued) **U001242949**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1970
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	16651
Facility ID:	41608
Ai Number:	6440
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/31/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

RED ARROW FREIGHT LINES (Continued) **U001242949**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/10/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	10459
UST ID:	16651
AI Number:	6440
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

RED ARROW FREIGHT LINES (Continued) **U001242949**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	RED ARROW FREIGHT LINES INC
Contact Mailing Address (Delivery):	PO BOX 697
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	CHERRYVILLE, NC 28021 0697
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	41608
Additional ID:	752451062002075
Princ ID:	353323402001309
AI Number:	6440
Facility Name:	RED ARROW FREIGHT LINES
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	WADE STROUPE/

HIST UST AUSTIN:

Name:	RED ARROW FREIGHT LINES
Address:	8080 PURNELL DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0171
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

Ind. Haz Waste:

Name:	SAIA MOTOR FREIGHT LINE
Address:	8080 PURNELL DR
City,State,Zip:	AUSTIN, TX 78753

RED ARROW FREIGHT LINES (Continued) **U001242949**

Permit Number:	Not reported
Registration Number:	41394
Registration Initial Notification Date:	04/03/1989
Registration Last Amendment Date:	07/14/2022
EPA Identification:	TXD982564965
Primary NAICS Code:	484110
Status Change Date:	19890403
Land Type:	PRIVATE
Description of Facility Site Location:	8080 Purnell Dr, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	Not reported
Company Name:	OVERNITE TRANSPORTATION COMPANY
Contact Name:	LARRY MATHIS
Contact Telephone Number:	512-8737748
Mailing Address:	8080 PURNELL DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787536328
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17785
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20220714
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	1
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	OVERNITE TRANSPORTATION COMPANY
Operator Address:	8080 PURNELL DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78753
Operator Country:	UNITED STA
Operator Telephone:	1-512-8737748
Operator Fax Number:	Not reported

RED ARROW FREIGHT LINES (Continued) **U001242949**

Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	Not reported
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	OVERNITE TRANSPORTATION COMPANY
Owner Mailing Address:	8080 PURNELL DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78753
Owner Country:	UNITED STA
Owner Telephone:	1-512-8737748
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	Not reported
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	8080 PURNELL DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8737748
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	8080 PURNELL DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8737748
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	LARRY MATHIS
Contact Title:	ENVIRONMENTAL MANAGER
Contact Role:	PRICONT
Contact Address:	8080 PURNELL DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78753
Contact Phone:	1-512-8737748
Contact Fax:	Not reported
Contact Email:	Not reported

Ind. Haz Waste:

Waste ID:	433377
Texas Waste Code:	Not reported

RED ARROW FREIGHT LINES (Continued) **U001242949**

Texas Waste Code 2:	0001003H
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Lab packs/loose freight
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	RCRA LAB PACKS LOOSE
Primary NAICS Code:	484110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	433378
Texas Waste Code:	Not reported
Texas Waste Code 2:	00020031
Waste Code Status:	ACTIVE
Waste Form:	003
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	Non rcra waste
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	NON HAZ
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	433379
Texas Waste Code:	Not reported
Texas Waste Code 2:	00037011
Waste Code Status:	ACTIVE
Waste Form:	701
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	carbon dioxide
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported

RED ARROW FREIGHT LINES (Continued) **U001242949**

New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	CYLINDER
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

Waste ID:	433430
Texas Waste Code:	Not reported
Texas Waste Code 2:	0004104H
Waste Code Status:	ACTIVE
Waste Form:	104
Waste Classification:	H
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	acid
Standard Industrial Code:	Not reported
Primary Source:	G32
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	ACID
Primary NAICS Code:	484110
EPA Waste Form Code:	W001
Reason Waste Form No Longer Gen:	Not reported

Ind. Haz Waste:

Waste ID:	433429
Texas Waste Code:	Not reported
Texas Waste Code 2:	00058011
Waste Code Status:	ACTIVE
Waste Form:	801
Waste Classification:	1
Waste is Radioactive:	0
Waste Treated Off Site:	1
Generators Waste Description:	poly cylinders
Standard Industrial Code:	Not reported
Primary Source:	Not reported
Primary Measurement Point:	Not reported
Primary Origin:	2
Primary System Type:	Not reported
New Chemical Substance:	1
Audit Performed:	0
Company Waste ID:	POLY CYLINDERS
Primary NAICS Code:	Not reported
EPA Waste Form Code:	Not reported
Reason Waste Form No Longer Gen:	Not reported

3203 ESE 1/4-1/2 0.349 mi. 1841 ft. | **MERCEDES BENZ OF AUSTIN**
412 PAMPA DR
AUSTIN, TX 78752 | **TX TANKS**
TX HIST UST
TX COMP HIST
TX CENTRAL REGISTRY | **S126965724**
N/A

Actual: 698 ft.

Focus Map: 6

TANKS:

Facility ID:	136178
Name:	MERCEDES BENZ OF AUSTIN
Address:	412 PAMPA DR
City,State,Zip:	AUSTIN, TX 787523026
Total UST:	Not reported
Additional ID:	323477122020036
AI Number:	91072
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

HIST UST AUSTIN:

Name:	MERCEDES BENZ OF AUSTIN
Address:	412 PAMPA DR.
City,State,Zip:	AUSTIN, TX
Id UST:	3436
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

COMP HIST:

RN Number:	RN110953627
Name:	MERCEDES BENZ OF AUSTIN

MERCEDES BENZ OF AUSTIN (Continued) **S126965724**

Address:	Not reported
City,State,Zip:	TX
Region:	REGION 11 - AUSTIN
CN Number:	CN601256514
CN Name:	CONTINENTAL IMPORTS INC
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	236115
SIC Code:	1521
Related Number:	91072,91072

CENTRAL REGISTRY:

Regulated Entity Number:	RN110953627
Name:	MERCEDES BENZ OF AUSTIN
Address:	412 PAMPA DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3026
Status:	ACTIVE
Status Date:	2/5/2020
Customer Number:	CN601256514
Customer Name:	CONTINENTAL IMPORTS INC
Customer Legal Name:	Continental Imports, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2/4/2020
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

3204 WNW 1/4-1/2 0.349 mi. 1842 ft. **DOUGHERTY ARTS CENTER 1110 BARTON SPRINGS RD AUSTIN, TX 78704** **TX SWF/LF TX ASBESTOS** **S116230977 N/A**

Actual: 458 ft.

Focus Map: 11

SWF/LF:

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS RD
City,State,Zip:	AUSTIN, TX 78704-1150
Region:	11
Permit Number:	65032
Facility Status:	ACTIVE
Facility Type:	CR
Permit Status:	ISSUED
Status Date:	11/24/2014
Mailing Address:	Not reported
Client Name:	Not reported
Client Address:	Not reported
Client Telephone:	N/A
Business Type:	CITY

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Area Served:	TRAVIS COUNTY
Estimated Closure Date:	Not reported
Permit Acreage:	NA
Permit Start:	02/28/2014
Permit End:	11/24/2014
Polution Served:	Not reported
Tons per Day:	NA
Yards per Day:	NA
Application:	NEW APPLICATION
Lat/Long:	30.26093 / -97.75605

ASBESTOS:

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	03/20/2020
Notification Number:	2020001994
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/17/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/17/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/19/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	03/20/2020
Notification Number:	2020001994
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/04/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/04/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	03/19/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	12/07/2020
Notification Number:	2020006825
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Inspector Name:	Not reported
Date Report Received:	12/07/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/07/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/07/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Complaint Date:	12/08/2020
Notification Number:	2020006825
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	11/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/12/2020
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/07/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2017/06/24
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	06/24/2017

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Client Code:	1500
Client Name:	Environmental Notification
License Number:	2017004285
File Number:	20782
License Status Description:	Paid
Expiration Date:	06/25/2017
Original Date:	06/06/2017
Rank Effective Date:	06/06/2017
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	6724
Inspection Status:	Open
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Pass
Inspection Number Grade:	0
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	06/24/2017
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	06/25/2017
Notification Number:	2017004285
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/14/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/14/2017

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/24/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ART CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	06/24/2017
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	06/23/2017
Notification Number:	2017004285
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/06/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/06/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	06/22/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	06/14/2022
Notification Number:	2022003848
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/12/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	06/12/2022
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	06/13/2022
Notification Number:	2022003848
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/08/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/08/2022
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/10/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	12/22/2017
Notification Number:	2017008743
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/08/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/08/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	12/22/2017
Notification Number:	2017008743
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/28/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/28/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	21
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	12/18/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Joseph Thomas
Violation:	Not reported
Complaint Date:	12/31/2020
Notification Number:	2020004088
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/12/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	O & M
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/12/2020
Certification Statement Phone:	512-974-9187
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	2
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	06/27/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	09/19/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/21/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	08/21/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/03/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/10/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/10/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	09/30/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/10/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	09/23/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Abatement

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	09/23/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/07/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/25/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/04/2019

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	4
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/04/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/22/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	10/30/2019
Notification Number:	2019006055

DOUGHERTY ARTS CENTER (Continued) **S116230977**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/18/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	5
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/18/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	08/26/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	08/07/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	08/07/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	5
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	08/24/2019
Client Code:	Not reported
Client Name:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	11/02/2019
Notification Number:	2019006055
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/28/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	6
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	10/28/2019
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Region:	07
Priority:	HIGH
ARU:	6
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	10/28/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS RD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	11/19/2019
Notification Number:	2019008149
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/04/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	11/04/2019
Certification Statement Phone:	512-974-2904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	11/18/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	DOUGHERTY ARTS CENTER
Address:	1110 BARTON SPRINGS ROAD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Odeyda Reyes
Violation:	Not reported
Complaint Date:	10/09/2022
Notification Number:	2022006522
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported

DOUGHERTY ARTS CENTER (Continued) **S116230977**

Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	10/07/2022
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	10/07/2022
Certification Statement Phone:	5129742904
Is The Facility a School or K-12?:	N
Region:	07
Priority:	TOP
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	Y
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	10/08/2022
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

3205 East 1/4-1/2 0.349 mi. 1845 ft. | **JULIOS CAFE 4220 DUVAL ST AUSTIN, TX** | **TX HIST UST TX RDR** | **S127542925 N/A**

Actual: 614 ft.

Focus Map: 8

HIST UST AUSTIN:

Name:	JULIO'S CAFE'
Address:	4220 DUVAL ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3299
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

RDR:

RDR ID:	15016
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	JULIOS CAFE
Address:	4220 DUVAL ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	1/10/2006
Due Date:	3/11/2006
Tank Owner:	ED SHAW
Contact Person:	ED SHAW
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/21/2006
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/21/2006
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3206 WNW 1/4-1/2 0.361 mi. 1908 ft. | **G S TYPESETTERS 410 BAYLOR ST AUSTIN, TX 78703** | **TX LPST** | **S116701698 N/A**

Actual: 473 ft.

Focus Map: 11

LPST:

Name:	G S TYPESETTERS
Address:	410 BAYLOR ST
City,State,Zip:	AUSTIN, TX 78703
Facility ID:	0029436
LPST Id:	091181
Facility Location:	410 BAYLOR
TCEQ Region# and City:	REGION 11 - AUSTIN

G S TYPESETTERS (Continued) **S116701698**

Region City:	AUSTIN
Discovered Date:	12/07/1986
Entered Date:	12/16/1986
Reported Date:	12/15/1986
Closure Date:	06/29/1987
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	410 BAYLOR
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/478-5341
Reported Date:	12/15/1986
Case Start Date:	06/29/1987
Reference Number:	RN101493138
Project Manager:	HWELCH

TP3207 **FORMER 7-ELEVEN 39068** **TX RDR** **S127539785**
SW **120 W SLAUGHTER LN** **N/A**
1/4-1/2 **AUSTIN, TX**
0.362 mi.
1911 ft. **Site 1 of 2 in cluster TP**

Actual:
648 ft.

Focus Map:
21

RDR:

RDR ID:	18737
Facility ID:	75395
RN:	Not reported
CN:	Not reported
Name:	FORMER 7-ELEVEN 39068
Address:	120 W SLAUGHTER LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/24/2010
Due Date:	4/25/2010
Tank Owner:	CONGRESS SLAUGHTER L
Contact Person:	JASON LIAHAN
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	4/29/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	118297
Pre-Existing LPST Number:	Not reported
Comments:	LAD SENT 5/5/10
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TP3208 **WALGREENS** **TX LPST** **S110376982**
SW **120 W SLAUGHTER LN** **TX ASBESTOS** **N/A**
1/4-1/2 **AUSTIN, TX 78748** **TX GCC**
0.362 mi.
1911 ft. **Site 2 of 2 in cluster TP**

Actual:
648 ft.

Focus Map:
21

LPST:

Name:	7 ELEVEN 39068
Address:	120 W SLAUGHTER LN
City,State,Zip:	AUSTIN, TX 78748
Facility ID:	0075395
LPST Id:	118297
Facility Location:	120 W SLAUGHTER LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/11/2009
Entered Date:	04/29/2010
Reported Date:	02/24/2010
Closure Date:	07/14/2010
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	MWB
Responsible Party Name:	Not reported
Responsible Party Contact:	JASON LINAHAN
Responsible Party Address:	12050 VANCE JACKSON STE 102
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78230
Responsible Party Telephone:	210/525-0131
Reported Date:	02/24/2010
Case Start Date:	07/14/2010
Reference Number:	RN102901220
Project Manager:	MBRATBER

ASBESTOS:

Name:	WALGREENS
Address:	120 W SLAUGHTER LN
City,State,Zip:	AUSTIN, TX 78748
Date of inspection:	01/09/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	01/16/2013

WALGREENS (Continued) **S110376982**

Date Routed by Supervisor:	01/18/2013
Date Routed to PSQA:	01/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	WALGREENS
Address:	120 W SLAUGHTER LN
City,State,Zip:	AUSTIN, TX 78748
Date of inspection:	02/06/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported

WALGREENS (Continued) **S110376982**

ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	02
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/10/2014
Date Routed by Supervisor:	02/12/2014
Date Routed to PSQA:	02/12/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported

WALGREENS (Continued) **S110376982**

Inspection Secondary Class Code: Not reported
Inspection Secondary Class Code Description: Not reported
Results: Not reported
Inspection Number Grade: Not reported

GCC:
Name: CONGRESS SLAUGHTER LP
Address: 120 W SLAUGHTER LN
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 118297
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 4/29/2010
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: CONGRESS SLAUGHTER LP
Address: 120 W SLAUGHTER LN
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: *
File Number: 118297
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 4/29/2010
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

TQ3209 **FIRST TEXAS HONDA** **TX LPST** **S116696720**
WNW **1301 W KOENIG LN** **TX CENTRAL REGISTRY** **N/A**
1/4-1/2 **AUSTIN, TX 78756**
0.364 mi.
1920 ft. **Site 1 of 2 in cluster TQ**

Actual:
671 ft.

Focus Map:
8

LPST:
Name: FIRST TEXAS HONDA
Address: 1301 W KOENIG LN
City,State,Zip: AUSTIN, TX 78756
Facility ID: 0060813

FIRST TEXAS HONDA (Continued) **S116696720**

LPST Id:	104653
Facility Location:	1301 KOENING LANE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/03/1992
Entered Date:	10/27/1992
Reported Date:	09/03/1992
Closure Date:	11/17/1992
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	JOHN BISSONNET
Responsible Party Address:	1301 KOENIG LN
Responsible Party City,St,Zip:	AUSTIN, TX 78756
Responsible Party Telephone:	512/458-2511
Reported Date:	09/03/1992
Case Start Date:	11/17/1992
Reference Number:	RN100523851
Project Manager:	HWELCH

CENTRAL REGISTRY:

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000

FIRST TEXAS HONDA (Continued) **S116696720**

Customer Status:	UNVALD
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603447053
Customer Name:	CONTINENTAL CARS INC
Customer Legal Name:	Continental Cars, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/24/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603447053
Customer Name:	CONTINENTAL CARS INC
Customer Legal Name:	Continental Cars, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/24/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers

FIRST TEXAS HONDA (Continued) **S116696720**

Physical Location Description: 1301 WEST KOENIG

Regulated Entity Number: RN100523851
Name: FIRST TEXAS HONDA
Address: 1301 W KOENIG LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78756-0005
Status: ACTIVE
Status Date: ##########
Customer Number: CN603447053
Customer Name: CONTINENTAL CARS INC
Customer Legal Name: Continental Cars, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 10/24/1991
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 44111
Primary NAICS Industry Type Description: New Car Dealers
Physical Location Description: 1301 WEST KOENIG

Regulated Entity Number: RN100523851
Name: FIRST TEXAS HONDA
Address: 1301 W KOENIG LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78756-0005
Status: ACTIVE
Status Date: ##########
Customer Number: CN600267132
Customer Name: CONTINENTAL CARS LTD
Customer Legal Name: Continental Cars, Ltd.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: 44111
Primary NAICS Industry Type Description: New Car Dealers
Physical Location Description: 1301 WEST KOENIG

Regulated Entity Number: RN100523851
Name: FIRST TEXAS HONDA
Address: 1301 W KOENIG LN
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78756-0005
Status: ACTIVE
Status Date: ##########
Customer Number: CN603447053
Customer Name: CONTINENTAL CARS INC
Customer Legal Name: Continental Cars, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 10/24/1991
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 44111
Primary NAICS Industry Type Description: New Car Dealers
Physical Location Description: 1301 WEST KOENIG

Regulated Entity Number: RN100523851

FIRST TEXAS HONDA (Continued) **S116696720**

Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN603447053
Customer Name:	CONTINENTAL CARS INC
Customer Legal Name:	Continental Cars, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	10/24/1991
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Regulated Entity Number:	RN100523851
Name:	FIRST TEXAS HONDA
Address:	1301 W KOENIG LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-0005
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	44111
Primary NAICS Industry Type Description:	New Car Dealers
Physical Location Description:	1301 WEST KOENIG

Click this hyperlink while viewing on your computer to access
4 additional TX CENTRAL REG: record(s) in the EDR Site Report.

3210 NW 1/4-1/2 0.364 mi. 1920 ft.

VARGAS FOOD STORE
809 VARGAS RD
AUSTIN, TX 78741

TX LPST **U001262925**
TX UST **N/A**
TX HIST UST

Actual: 480 ft.

Focus Map: 15

LPST:

Name:	VARGAS FOOD STORE
Address:	809 VARGAS RD
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0029356
LPST Id:	096413
Facility Location:	809 VARGAS RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/01/1990
Entered Date:	08/10/1990
Reported Date:	08/01/1990
Closure Date:	06/06/2000
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1/2
Coordinators RPR:	JAF
Responsible Party Name:	Not reported
Responsible Party Contact:	STACY OLIVER
Responsible Party Address:	201 W STASSNEY LN STE 512
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/457-1977
Reported Date:	08/01/1990
Case Start Date:	06/06/2000
Reference Number:	RN101495760
Project Manager:	JAF

UST:

Name:	VARGAS FOOD STORE
Address:	809 VARGAS RD
City,State,Zip:	AUSTIN, TX 787412428
AI Number:	29356
Facility Type:	UNKNOWN
Facility Begin Date:	08/31/1987
Facility Status:	INACTIVE
Additional ID:	30692372002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	SHAUKAT PRASLA,
Contact Organization Name:	VARGAS FOOD STORE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

VARGAS FOOD STORE (Continued) **U001262925**

Contact Telephone:	5123891091
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/14/1986
Signature Name/Title On Earliest Reg Form:	R L WOERNER,PRES.
Application Received Date On Earliest Reg Form:	05/16/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600783500
Owner Last Name:	VARGAS FOOD STORE
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	21692362002053
Additional ID:	30692372002053
AI Number:	29356
Owner Effective Begin Date:	09/01/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1969
Tank Registration Date:	05/16/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	77533
Facility ID:	97140
Ai Number:	29356
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/10/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

VARGAS FOOD STORE (Continued) **U001262925**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	152938
UST ID:	77533
AI Number:	29356
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

VARGAS FOOD STORE (Continued) **U001262925**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	11136
Cert ID:	22273
UST Comprt ID:	69597
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22272
UST Comprt ID:	69596
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22271
UST Comprt ID:	69592
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22270

VARGAS FOOD STORE (Continued) **U001262925**

UST Comprt ID:	69595
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22281
UST Comprt ID:	69586
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22279
UST Comprt ID:	69588
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22278
UST Comprt ID:	69589
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22277
UST Comprt ID:	69590
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22276
UST Comprt ID:	69591
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22275
UST Comprt ID:	69593
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22274
UST Comprt ID:	69594

VARGAS FOOD STORE (Continued) **U001262925**

UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22280
UST Comprt ID:	69587
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1969
Tank Registration Date:	05/16/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	77534
Facility ID:	97140
Ai Number:	29356
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/10/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

VARGAS FOOD STORE (Continued) **U001262925**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	152939
UST ID:	77534
AI Number:	29356
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N

VARGAS FOOD STORE (Continued) **U001262925**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	11136
Cert ID:	22273
UST Comprt ID:	69597
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22272
UST Comprt ID:	69596
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22271
UST Comprt ID:	69592
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22270
UST Comprt ID:	69595
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22281
UST Comprt ID:	69586
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22279
UST Comprt ID:	69588
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22278
UST Comprt ID:	69589

VARGAS FOOD STORE (Continued) **U001262925**

UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22277
UST Comprt ID:	69590
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22276
UST Comprt ID:	69591
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22275
UST Comprt ID:	69593
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22274
UST Comprt ID:	69594
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22280
UST Comprt ID:	69587
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1969
Tank Registration Date:	05/16/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	77535
Facility ID:	97140
Ai Number:	29356
Tank Id:	3

VARGAS FOOD STORE (Continued) **U001262925**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/10/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	03/30/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	152940
UST ID:	77535
AI Number:	29356

VARGAS FOOD STORE (Continued) **U001262925**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	11136
Cert ID:	22273
UST Comprt ID:	69597
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22272
UST Comprt ID:	69596
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22271
UST Comprt ID:	69592

VARGAS FOOD STORE (Continued) **U001262925**

UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22270
UST Comprt ID:	69595
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22281
UST Comprt ID:	69586
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22279
UST Comprt ID:	69588
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22278
UST Comprt ID:	69589
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22277
UST Comprt ID:	69590
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22276
UST Comprt ID:	69591
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22275
UST Comprt ID:	69593
UST ID:	24072

VARGAS FOOD STORE (Continued) **U001262925**

AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22274
UST Comprt ID:	69594
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A
Self Cert ID:	11136
Cert ID:	22280
UST Comprt ID:	69587
UST ID:	24072
AI Number:	29356
Tank ID:	1
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	VARGAS FOOD STORE
Contact Mailing Address (Delivery):	809 VARGAS RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78741 2428
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	97140
Additional ID:	30692372002053
Princ ID:	21692362002053
AI Number:	29356
Facility Name:	VARGAS FOOD STORE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SHAUKAT PRASLA/

HIST UST AUSTIN:

Name:	VARGAS FOOD STORE
Address:	809 VARGAS RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0537
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TR3211 **FORMER BRACKENRIDGE HOSPITAL** **TX RDR** **S127538266**
ESE **601 E 15TH ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.365 mi.
1926 ft. **Site 1 of 4 in cluster TR**

Actual:
511 ft.

Focus Map:
11

RDR:

RDR ID:	27634
Facility ID:	6
RN:	Not reported
CN:	Not reported
Name:	FORMER BRACKENRIDGE HOSPITAL
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/21/2019
Due Date:	12/20/2019
Tank Owner:	TRAVIS COUNTY HEALTHCARE DISTRICT
Contact Person:	STEVEN LAMP
Report:	RDR/UST REMOVAL
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/5/2019
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TR3212 **FORMER BRACKENRIDGE HOSPITAL CAMPUS** **TX LPST** **U001829132**
ESE **601 E 15TH ST** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78701** **TX HIST UST**
0.365 mi. **TX AIRS**
1926 ft. **Site 2 of 4 in cluster TR** **TX ASBESTOS**
TX ENF
Actual: **TX Financial Assurance**
511 ft. **TX IHW CORR ACTION**
TX COMP HIST

Focus Map:
11

LPST:

Name:	BRACKENRIDGE HOSPTIAL
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0000006
LPST Id:	109025
Facility Location:	601 E 15TH ST CONTACT JIM GLOVER
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	01/11/1995
Entered Date:	01/12/1995
Reported Date:	01/11/1995
Closure Date:	09/18/1995
Priority:	2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program:	1 - RPR

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected and a public or domestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	RONNIE EASON
Responsible Party Name:	Not reported
Responsible Party Contact:	MARC CHILDERS
Responsible Party Address:	6301 A HAROLD CT
Responsible Party City,St,Zip:	AUSTIN, TX 78721
Responsible Party Telephone:	512/928-1492
Reported Date:	01/11/1995
Case Start Date:	09/18/1995
Reference Number:	RN100549658
Project Manager:	REASON

UST:

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 787011930
AI Number:	6
Facility Type:	EMERGENCY GENERATOR
Facility Begin Date:	01/01/1976
Facility Status:	INACTIVE
Additional ID:	575786012002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	CHRIS SCHEFFEL,
Contact Organization Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123247322
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	CHRIS.SCHEFFEL@MEDXCELFM.COM
Signature Date On Earliest Reg Form:	02/10/2021
Signature Name/Title On Earliest Reg Form:	STEPHANIE MCDONALD,MNGR
Application Received Date On Earliest Reg Form:	05/26/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	807562242013309
Additional ID:	575786012002149
Ai Number:	6
Operator CN:	CN604397935
Operator Name:	ASCENSION TEXAS

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Operator Effective Begin Date:	11/29/2011
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN605420983
Owner Last Name:	TRAVIS COUNTY HEATLTHCARE DISTRICT
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	763338732017268
Additional ID:	575786012002149
AI Number:	6
Owner Effective Begin Date:	05/05/2016
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	37545
Cert ID:	320933
AI Number:	6
Self Certification Date:	04/16/2019
Signature Name/Title:	MARK WEHNER REG HAZMAT SAFTEY OFFIC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37545
Cert ID:	310197
AI Number:	6
Self Certification Date:	09/19/2018
Signature Name/Title:	MARK WEHNER REG HAZ SAFETY
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37545
Cert ID:	293698
AI Number:	6
Self Certification Date:	09/22/2017
Signature Name/Title:	MARK WEHNER NETWORK HAZMAT SAF OF
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	37545
Cert ID:	270134
AI Number:	6
Self Certification Date:	05/02/2016
Signature Name/Title:	MARK WEHNER NETWORK HAZMAT SO
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37545
Cert ID:	252981
AI Number:	6
Self Certification Date:	05/05/2015
Signature Name/Title:	MARK A WEHNER NETWORK HAZMAT SFT O
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37545
Cert ID:	235944
AI Number:	6
Self Certification Date:	05/08/2014
Signature Name/Title:	MARK A WEHNER HAZMAT SAFETY OFFICE
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	37545
Cert ID:	219226
AI Number:	6
Self Certification Date:	03/27/2013
Signature Name/Title:	MARK A WEHNER HAZMAT SAFETY OFFICE
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	37545
Cert ID:	343
AI Number:	6
Self Certification Date:	06/22/2012
Signature Name/Title:	MARK A WEHNER NETWORK HAZMAT
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37545
Cert ID:	342
AI Number:	6
Self Certification Date:	02/16/2011
Signature Name/Title:	MARK A WEHNER NTWK SFTY OFCR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	37545
Cert ID:	341
AI Number:	6
Self Certification Date:	11/10/2010
Signature Name/Title:	MARK A WEHNER NETWORK SAF OFFIC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	340
AI Number:	6
Self Certification Date:	01/26/2010
Signature Name/Title:	MARK A WEHNER NETWORK SAF OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	339
AI Number:	6
Self Certification Date:	09/10/2008
Signature Name/Title:	MARK A WEHNER SAFETY OFFICER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	338
AI Number:	6
Self Certification Date:	05/01/2007
Signature Name/Title:	MARK A WEHNER HAZMAT SAFETY OFFICE
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	337
AI Number:	6
Self Certification Date:	04/17/2006
Signature Name/Title:	MARK A WEHNER SAFETY OFFICER
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	336
AI Number:	6
Self Certification Date:	04/14/2004
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	335
AI Number:	6
Self Certification Date:	04/15/2003
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFF
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	334
AI Number:	6
Self Certification Date:	07/04/2002
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFF
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	37545
Cert ID:	333
AI Number:	6
Self Certification Date:	01/11/2001
Signature Name/Title:	MARK A WEHNER NETWORK SAFETY OFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1986
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	6
Facility ID:	37545

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Ai Number:	6
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/19/2019
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	228

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

UST ID:	6
AI Number:	6
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	6
Cert ID:	335
UST Comprt ID:	1194
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	333
UST Comprt ID:	1192
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Cert ID:	336
UST Comprt ID:	1191
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	334
UST Comprt ID:	1193
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4320
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	G
UST ID:	8
Facility ID:	37545
Ai Number:	6
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/20/2021
Empty:	N
Tank Regulatory Status:	EMERG POWER GENERATOR
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4320
UST Comprt ID:	230
UST ID:	8
AI Number:	6
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	6
Cert ID:	335
UST Comprt ID:	1194
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	333
UST Comprt ID:	1192
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	336
UST Comprt ID:	1191
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	334
UST Comprt ID:	1193
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	7
Facility ID:	37545
Ai Number:	6
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/23/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	1000
UST Comprt ID:	229
UST ID:	7
AI Number:	6
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	6
Cert ID:	335
UST Comprt ID:	1194
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	333
UST Comprt ID:	1192
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A
Self Cert ID:	6
Cert ID:	336
UST Comprt ID:	1191
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Self Cert ID:	6
Cert ID:	334
UST Comprt ID:	1193
UST ID:	228
AI Number:	6
Tank ID:	1
Compartment ID:	A

Construction Notification:

NOC ID:	37175
Facility ID:	37545
AI Number:	6
Application Received Date:	10/13/2020
Scheduled Construction Date:	11/10/2020
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	10/13/2020
Signature Date On Form:	10/07/2020
Signature Name On Form:	ERIKA CUELLAR
Signature Company On Form:	Not reported
Signature Title On Form:	PM
Signature Role:	Not reported
Owner Name At Time Of Construction:	TRAVIS COUNTY HEATLTHCARE DISTRICT
Owner CN At Time Of Construction:	CN605420983
Owner AR At Time Of Construction:	79181
General Desc Of Prop Construct:	REMOVE 4000 UST

NOC ID:	35232
Facility ID:	37545
AI Number:	6
Application Received Date:	08/16/2019
Scheduled Construction Date:	08/26/2019
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Form Received Date:	10/13/2020
Signature Date On Form:	10/07/2020
Signature Name On Form:	ERIKA CUELLAR
Signature Company On Form:	Not reported
Signature Title On Form:	PM
Signature Role:	Not reported
Owner Name At Time Of Construction:	TRAVIS COUNTY HEATLTHCARE DISTRICT
Owner CN At Time Of Construction:	CN605420983
Owner AR At Time Of Construction:	79181
General Desc Of Prop Construct:	REMOVE 10,000 GAL UST CONTAINING DIESEL - REQUEST 30 DAY WAIVER

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	88220
UST ID:	Not reported
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	ERLING SALES & SERVICE
Representative Name:	ERIKA CUELLAR
Mailing Address (Delivery):	2330 PATTERSON INDUSTRIAL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	PFLUGERVILLE
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	737
Phone Number:	2269550
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	83536
UST ID:	Not reported
NOC ID:	35232
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	EXCELL ENVIRONMENTAL INC
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 1675
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805231
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	512

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Fax Number:	2803580
Email Address:	INFO@EXCELLFUELINGSYSTEMS.COM
Cont/Cons/Installer ID:	88228
UST ID:	224901
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	S & W CONTRACTS
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	88223
UST ID:	224898
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000148
Company Name:	WILLBORN BROTHERS COMPANY
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 2089
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AMARILLO
Mailing State:	TX
Mailing Zip:	79105
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	806
Phone Number:	3724311
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	88226
UST ID:	224900
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Company Name:	S & W CONTRACTS
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	88225
UST ID:	224899
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000148
Company Name:	WILLBORN BROTHERS COMPANY
Representative Name:	Not reported
Mailing Address (Delivery):	PO BOX 2089
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AMARILLO
Mailing State:	TX
Mailing Zip:	79105
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	806
Phone Number:	3724311
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	88221
UST ID:	Not reported
NOC ID:	37175
AI Number:	6
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	ERLING SALES & SERVICE
Representative Name:	DAVID KMIEC
Mailing Address (Delivery):	2330 PATTERSON INDUSTRIAL DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	PFLUGERVILLE
Mailing State:	TX
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Phone Number Country Code:	1
Phone Number Area Code:	832
Phone Number:	6065098
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	88229
UST ID:	224901
NOC ID:	37175
AI Number:	6
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	RILEY TENNISON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	88224
UST ID:	224899
NOC ID:	37175
AI Number:	6
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	NATHAN BIRCHFIELD
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Cont/Cons/Installer ID:	88227
UST ID:	224900
NOC ID:	37175
AI Number:	6
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	RILEY TENNISON
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	83535
UST ID:	Not reported
NOC ID:	35232
AI Number:	6
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001166
Company Name:	ROLLINS RICHARD C
Representative Name:	Not reported
Mailing Address (Delivery):	120 MONTGOMERY CT
Mailing Address (Internal Delivery):	Not reported
Mailing City:	BUDA
Mailing State:	TX
Mailing Zip:	78610
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2805230
Phone Number Extension:	0
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	RICK.ROLLINS@EXCELLFUELINGSYSTEMS.COM

Cont/Cons/Installer ID:	88222
UST ID:	224898
NOC ID:	37175
AI Number:	6
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	NATHAN BIRCHFIELD
Mailing Address (Delivery):	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TRAVIS COUNTY HEATLTHCARE DISTRICT
Contact Mailing Address (Delivery):	1111 E CESAR CHAVEZ ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78702 4209
Phone Number/Ext:	512 9788177/0
Contact Fax Number/Ext:	512 3245657/0
Contact Email Address:	GARY.BRADY@CENTRALHEALTH.NET
Contact Address Deliverable:	Y
Facility ID:	37545
Additional ID:	575786012002149
Princ ID:	763338732017268
AI Number:	6
Facility Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
AR Number:	79181
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GARY BRADY/

HIST UST AUSTIN:

Name:	UNIVERSITY MEDICAL CENTER BRACKENRIDGE
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX
Id UST:	934
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

AIRS:

Name:	BRACKENRIDGE HOSPITAL
Address:	601 E 15TH ST
City,State,Zip:	TX
Permit Num:	119440
Regulated Id:	RN100549658
Permit Type:	PBR
Permit Status:	EFFECTIVE
Permit Issued Date:	06/25/2014
Expiration Date:	12/31/3000
Customer Id:	CN604397935

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Company Name:	SETON HEALTHCARE FAMILY
Physical Location Desc:	601 E 15TH STREET
Rep Official(RO):	NETWORK HAZMAT SAFETY OFFICER
RO Name:	MR MARK A WEHNER
RO Delivery Address:	4200 N LAMAR BLVD STE 250
RO City/State/Zip:	AUSTIN, T 78756-343
RO Phone:	Not reported
RO Ext Num:	0
RO EMail Address:	MWEHNER@SETON.ORG
Lat Dec Coord Num:	0
Long Dec Coord Num:	0

ASBESTOS:

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/05/14
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Notified
Inspector Name:	RODRIGUEZ, FRANK
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	05/14/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018008931
File Number:	36510
License Status Description:	Paid
Expiration Date:	06/28/2019
Original Date:	12/06/2018
Rank Effective Date:	12/06/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	frodriguez
Inspection Number:	16225
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AB
Inspection Secondary Class Code Description:	Asbestos Both
Results:	Pass
Inspection Number Grade:	Not reported

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2019/01/16
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Complaint/Incident
Inspector Name:	MONTEMAYOR, JORGE
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/16/2019
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2018008931
File Number:	36510
License Status Description:	Paid
Expiration Date:	06/28/2019
Original Date:	12/06/2018
Rank Effective Date:	12/06/2018
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	jmontemayo
Inspection Number:	14068
Inspection Status:	Closed
Disposition:	0050 - Completed Complaint Open
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AT
Inspection Secondary Class Code Description:	Asbestos TAHPR
Results:	Fail
Inspection Number Grade:	0
Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Not reported
Violation:	Not reported
Complaint Date:	2020/01/10
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Facility Type:	Notified
Inspector Name:	MALDONADO, SKYLER
Date Report Received:	Not reported
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Region 7
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	01/10/2020
Client Code:	1500
Client Name:	Environmental Notification
License Number:	2019008635
File Number:	47195
License Status Description:	Current
Expiration Date:	06/30/2021
Original Date:	11/21/2019
Rank Effective Date:	11/21/2019
Mod Code:	ANOT
Area:	Area 09
Staff Operator ID:	smaldonado
Inspection Number:	20691
Inspection Status:	Closed
Disposition:	I090 - Completed Inspection
Inspection Class Descriptio:	Environmental
Inspection Secondary Class Code:	AN
Inspection Secondary Class Code Description:	Asbestos NESHAP
Results:	Pass
Inspection Number Grade:	Not reported
Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/28/2022
Reason for Inspection:	Joe Ramon III

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Violation:	Not reported
Complaint Date:	06/30/2021
Notification Number:	2019008635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/04/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	4
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	05/28/2021
Certification Statement Phone:	210-225-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/28/2022
Reason for Inspection:	Joe Ramon III
Violation:	Not reported
Complaint Date:	11/30/2020
Notification Number:	2019008635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/06/2019
Certification Statement Phone:	210-225-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/28/2022
Reason for Inspection:	Joe Ramon III
Violation:	Not reported
Complaint Date:	04/02/2021
Notification Number:	2019008635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/23/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Certification Statement Date:	12/16/2020
Certification Statement Phone:	210-225-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/28/2022
Reason for Inspection:	Joe Ramon III
Violation:	Not reported
Complaint Date:	05/30/2021
Notification Number:	2019008635
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/11/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	3
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	04/01/2021
Certification Statement Phone:	210-225-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/16/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BRECKENRIDGE HOSPITAL FACILITY
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	06/28/2022
Reason for Inspection:	Joe Ramon III
Violation:	Not reported
Complaint Date:	11/30/2020
Notification Number:	2019008635
ASB Priority:	Not reported
PIF State:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	11/21/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	11/21/2019
Certification Statement Phone:	210-225-1583
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/09/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/03/2021
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	05/14/2020
Notification Number:	2020002313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	04/30/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	04/30/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	81
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/31/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/03/2021
Reason for Inspection:	Brenda Troth
Violation:	Not reported
Complaint Date:	04/30/2020
Notification Number:	2020002313
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/17/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	03/17/2020
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

ARU:	81
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/31/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	BRACKENRIDGE HOSPITAL
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/19/2021
Notification Number:	2020007822
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	01/20/2021
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/20/2021
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	BRACKENRIDGE HOSPITAL
Address:	601 EAST 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/22/2021
Notification Number:	2020007822
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/28/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	12/28/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/30/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	BRACKENRIDGE HOSPITAL
Address:	601 EAST 15TH STREET

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Frank Wiget
Violation:	Not reported
Complaint Date:	01/08/2021
Notification Number:	2020007822
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/15/2020
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/15/2020
Certification Statement Phone:	512-576-2019
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containtment with RFCI
Analytical Method:	PLM
Start Date:	12/29/2020
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E. 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/14/2019
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	06/28/2019
Notification Number:	2018008931
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	05/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	3
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/29/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	419
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/14/2019
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	05/24/2019
Notification Number:	2018008931
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	01/31/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	01/25/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	419
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/14/2019
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	06/14/2019
Notification Number:	2018008931
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Date Report Received:	05/29/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	2
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	05/22/2019
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	419
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	CENTRAL HEALTH DOWNTOWN CAMPUS
Address:	601 E 15TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	05/14/2019
Reason for Inspection:	DON DANIEL
Violation:	Not reported
Complaint Date:	05/24/2019

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Notification Number:	2018008931
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/06/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/03/2018
Certification Statement Phone:	512-260-6202
Is The Facility a School or K-12?:	N
Region:	07
Priority:	HIGH
ARU:	1593
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	Y
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

ENFORCEMENT:

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701-1930
Unique TCEQ Ref Number Of Customer:	CN604397935
Unique TCEQ Ref Number Of Reg. Entity:	RN100549658
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	ASCENSION TEXAS
Regulated Entity Associated With An NOV:	Not reported
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001429513
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	624,582,882,017,226.00
Role Code:	Not reported
Date Notice Of Violation Issued:	08/18/2017
Description 1:	Failure to comply with temporary removal from service requirements.
Description 2:	On August 30, 2017, documentation was received demonstrating that the UST was emptied. On September 25, 2017, PST Registration updated Tank 1 status to temporarily out of service. The violation was resolved September 29, 2017.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.54
Status Of The NOV:	DAPPROVED
Investigation:	1429513
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported
Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

TX Financial Assurance 2:

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Finass ID:	214534
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2018
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 646 8266600
Policy Number:	003207101
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	203797
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	07/01/2018
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 617 6915680
Policy Number:	003207101
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	186833
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Financial Assurance Begin Date:	07/01/2017
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 617 3915680
Policy Number:	003207100
Coverage Amount:	1,000,000
Coverage Expiration Date:	07/01/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	162412
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/22/2015
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 314 7338710
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	144123
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2014
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 314 7338800
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	127090
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/15/2013
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/15/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	107788
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/28/2012
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/28/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	284
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/28/2012
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	OVER 2,000,000
Coverage Expiration Date:	09/28/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	107489
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/28/2012
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	Not reported
Policy Number:	Not reported
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/28/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	17402
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/30/2011
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	09/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	17403
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	LOCAL GOV FIN TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/2010
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	10/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	17404
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/04/2010
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	02/04/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Region:	2
Facility ID:	37545
Finass ID:	17405
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/19/2008
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 512 3248905
Policy Number:	None
Coverage Amount:	0
Coverage Expiration Date:	09/19/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Region:	2
Facility ID:	37545
Finass ID:	17406
AI:	6
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	05/26/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

IHW CORR ACTION:

Name:	UNIVERSITY MEDICAL CENTER BRACKENRIDGE
Address:	601 E 15TH ST
City,State,Zip:	AUSTIN, TX 78701
Program Id:	69915
Location Desc:	Not reported
RN NUM:	RN100549658
Status:	INACTIVE
Status Date:	11/06/2017
EDR Link ID:	69915
Project Phase:	COMPLETED WORKLOAD
Phase Status Date:	11/06/2017

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Soil COC Class: Not reported
Soil Remediation: Not reported
GW COC Class: Not reported
GW Remediation: Not reported

COMP HIST:

RN Number: RN100549658
Name: FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address: 601 E 15TH ST
City,State,Zip: TX 78701-1930
Region: REGION 11 - AUSTIN
CN Number: CN600330625
CN Name: J R JOE RAMON & SONS INC
CN Rating: 0
Classification: UNCLASSIFIED
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: UNCLASSIFIED
Date Rated 2: 09/01/2022
Date Published to Web 2: 11/15/2022
NAICS Code: 62211
SIC Code: 1521
Related Number: TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

RN Number: RN100549658
Name: FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address: 601 E 15TH ST
City,State,Zip: TX 78701-1930
Region: REGION 11 - AUSTIN
CN Number: CN605420983
CN Name: TRAVIS COUNTY HEATLTHCARE DISTRICT
CN Rating: 0
Classification: HIGH
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: HIGH
Date Rated 2: 09/01/2022
Date Published to Web 2: 11/15/2022
NAICS Code: 62211
SIC Code: 1611
Related Number: TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

RN Number: RN100549658
Name: FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address: 601 E 15TH ST
City,State,Zip: TX 78701-1930
Region: REGION 11 - AUSTIN
CN Number: CN601238181
CN Name: ASCENSION SETON
CN Rating: 0
Classification: HIGH
Date Calculated: 09/01/2022
Date Published to Web: 11/15/2022
Rating: 0
Classification 2: UNCLASSIFIED

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	62211
SIC Code:	2051
Related Number:	TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

RN Number:	RN100549658
Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	TX 78701-1930
Region:	REGION 11 - AUSTIN
CN Number:	CN604397935
CN Name:	ASCENSION TEXAS
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	HIGH
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	62211
SIC Code:	2051
Related Number:	TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

RN Number:	RN100549658
Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	TX 78701-1930
Region:	REGION 11 - AUSTIN
CN Number:	CN600129118
CN Name:	CITY OF AUSTIN DBA AUSTIN ENERGY
CN Rating:	0
Classification:	HIGH
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	62211
SIC Code:	1623
Related Number:	TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

RN Number:	RN100549658
Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	TX 78701-1930
Region:	REGION 11 - AUSTIN
CN Number:	CN600135198
CN Name:	CITY OF AUSTIN
CN Rating:	3.38
Classification:	SATISFACTORY
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **U001829132**

Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	62211
SIC Code:	5171
Related Number:	TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP
RN Number:	RN100549658
Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 E 15TH ST
City,State,Zip:	TX 78701-1930
Region:	REGION 11 - AUSTIN
CN Number:	CN603858630
CN Name:	DAUGHTERS OF CHARITY HEALTH SERVICES OF AUSTIN
CN Rating:	0
Classification:	UNCLASSIFIED
Date Calculated:	09/01/2022
Date Published to Web:	11/15/2022
Rating:	0
Classification 2:	UNCLASSIFIED
Date Rated 2:	09/01/2022
Date Published to Web 2:	11/15/2022
NAICS Code:	62211
SIC Code:	1521
Related Number:	TXD039422399,61763,66709,119440,TXR1546BP,TXR1546BP

TR3213 **CENTRAL HEALTH - BRACKENRIDGE CAMPUS** **US BROWNFIELDS** **1025442186**
ESE **601 E. 15TH STREET** **N/A**
1/4-1/2 **AUSTIN, TX 78701**
0.365 mi.
1926 ft. **Site 3 of 4 in cluster TR**

Actual:
511 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42
Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

	groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42
Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	42843.49
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	11/27/2017
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	160000000
Redev. Funding Source:	Central Health
Redev. Funding Entity Name:	Private/Other Funding

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Redevelopment Start Date:	2/3/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	648
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	11489
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	11/27/2017
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Unemployed Percent:	5.42
Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Click this hyperlink while viewing on your computer to access
4 additional US BROWNFIELDS: record(s) in the EDR Site Report.

Name:	CENTRAL HEALTH - BRACKENRIDGE CAMPUS
Address:	601 E. 15TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	14.3
Latitude:	30.274544
Longitude:	-97.7336075
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The redevelopment of the 17 story tower is currently underway. When the entire complex is complete, it will have cost $800m and create 2,800 new jobs. The redevelopment of the site will include demolishing over time most, if not all, of the existing buildings. Phase II ESA sampled multiple historical RECs, including previous dry cleaners, gas stations, jet fuel and diesel tanks, and areas of stressed vegetation. Contamination was not detected in soil or groundwater. Given the age of the buildings, asbestos and lead-based paint are likely present, but ABRO did not complete an asbestos/LBP survey. Due to the number and size of buildings, ACM/LBP abatement costs would be outside the grant budget.
Datum:	Not reported
Acres Property ID:	231321
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	42843.49
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous & Petroleum
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F90901
Start Date:	11/27/2017

CENTRAL HEALTH - BRACKENRIDGE CAMPUS (Continued) **1025442186**

Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Central Health
Did Owner Change:	N
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos No Contaminants Petroleum Products
Contaminant Cleanup:	Asbestos Petroleum Products
Media Affected:	Building Materials Other Media
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	14.3
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	14.3
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	208
Below Poverty Percent:	11.51
Meidan Income:	1991
Meidan Income Number:	321
Meidan Income Percent:	17.76
Vacant Housing Number:	64
Vacant Housing Percent:	12.9
Unemployed Number:	98
Unemployed Percent:	5.42

Click this hyperlink while viewing on your computer to access
4 additional US BROWNFIELDS: record(s) in the EDR Site Report.

TR3214 **FORMER BRACKENRIDGE HOSPITAL CAMPUS** **TX RDR** **S127538265**
ESE **601 EAST 15TH ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.365 mi.
1926 ft. **Site 4 of 4 in cluster TR**

Actual:
511 ft.

Focus Map:
11

RDR:

RDR ID:	30157
Facility ID:	6
RN:	100549658
CN:	605420983

FORMER BRACKENRIDGE HOSPITAL CAMPUS (Continued) **S127538265**

Name:	FORMER BRACKENRIDGE HOSPITAL CAMPUS
Address:	601 EAST 15TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/27/2021
Due Date:	7/26/2021
Tank Owner:	TRAVIS COUNTY HEALTHCARE DISTRICT
Contact Person:	STEVEN LAMP
Report:	Tank Closure
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/28/2021
Project Manager:	Rodney Bryant
Team:	Team 1
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TQ3215 **FORMER FIRST TEXAS HONDA** **US BROWNFIELDS** **1024247045**
WNW **1303 W. KOENIG** **N/A**
1/4-1/2 **AUSTIN, TX 78756**
0.365 mi.
1927 ft. **Site 2 of 2 in cluster TQ**

Actual:
671 ft.

Focus Map:
8

US BROWNFIELDS:

Name:	FORMER FIRST TEXAS HONDA
Address:	1303 W. KOENIG
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	228728
Parcel size:	0.5
Latitude:	30.329818
Longitude:	-97.7308
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The 0.46-acre subject property formerly operated as a used car dealership from 1987 through 2012 and has been vacant since closure in 2012. The subject property currently consists of a portion (approximately 1,785 square feet) of a 3,570-square-foot used car sales building surrounded by asphalt parking and drives. The used car sales building is generally separated into an office area and car wash garage. The subject property was agricultural land from at least 1940 until construction of a multi-tenant commercial building in the southeast portion of the subject property. The multi-tenant commercial building was demolished when the property was developed with the used car sales buildings in 1987. The Phase I and Limited Phase II had data gaps that may need to be investigated regarding groundwater and soils. Former Use: The property was most recently part of the First Texas Honda car dealership from 1987 until 2012 and has been vacant since that time.Two monitor wells were identified on

FORMER FIRST TEXAS HONDA (Continued) **1024247045**

	the Subject Property. Data gaps were identified during the Phase I ESA. The location of Fashion Dry Cleaners, which was identified as a historical dry-cleaner, was not confirmed during this Phase I ESA based on historical sources of information. A previous Phase I ESA reported that the location of Fashion Dry Cleaners was on the Subject Property; however, this was not confirmed. Additionally, omissions of data in the previous Phase I and II ESA reports led to the questioning of the usability of the data in these reports. It is recommended that the monitor wells on site be properly plugged and abandoned.
Datum:	Not reported
Acres Property ID:	234521
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	8651
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	00F91001
Start Date:	6/1/2017
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Brian Hardeman
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5

FORMER FIRST TEXAS HONDA (Continued) **1024247045**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.5
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was most recently part of the First Texas Honda car dealership from 1987 until 2012 and has been vacant since that time.Two monitor wells were identified on the Subject Property. Data gaps were identified during the Phase I ESA. The location of Fashion Dry Cleaners, which was identified as a historical dry-cleaner, was not confirmed during this Phase I ESA based on historical sources of information. A previous Phase I ESA reported that the location of Fashion Dry Cleaners was on the Subject Property; however, this was not confirmed. Additionally, omissions of data in the previous Phase I and II ESA reports led to the questioning of the usability of the data in these reports. It is recommended that the monitor wells on site be properly plugged and abandoned.
Below Poverty Number:	595
Below Poverty Percent:	15.75
Meidan Income:	4723
Meidan Income Number:	1201
Meidan Income Percent:	31.79
Vacant Housing Number:	41
Vacant Housing Percent:	2.05
Unemployed Number:	111
Unemployed Percent:	2.94

Name:	FORMER FIRST TEXAS HONDA
Address:	1303 W. KOENIG
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	228728
Parcel size:	0.5
Latitude:	30.329818
Longitude:	-97.7308
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The 0.46-acre subject property formerly operated as a used car dealership from 1987 through 2012 and has been vacant since closure in 2012. The subject property currently consists of a portion (approximately 1,785 square feet) of a 3,570-square-foot used car sales building surrounded by asphalt parking and drives. The used car sales building is generally separated into an office area and car wash garage. The subject property was agricultural land from at least 1940 until construction of a multi-tenant commercial building in the southeast portion of the subject property. The multi-tenant commercial building was demolished when the property was developed with the used car sales buildings in 1987. The Phase I and Limited Phase II had data gaps that may need to be investigated regarding groundwater and soils. Former Use: The property was most recently part of the First Texas Honda car dealership from 1987 until 2012 and has been vacant since that time.Two monitor wells were identified on

FORMER FIRST TEXAS HONDA (Continued) **1024247045**

	the Subject Property. Data gaps were identified during the Phase I ESA. The location of Fashion Dry Cleaners, which was identified as a historical dry-cleaner, was not confirmed during this Phase I ESA based on historical sources of information. A previous Phase I ESA reported that the location of Fashion Dry Cleaners was on the Subject Property; however, this was not confirmed. Additionally, omissions of data in the previous Phase I and II ESA reports led to the questioning of the usability of the data in these reports. It is recommended that the monitor wells on site be properly plugged and abandoned.
Datum:	Not reported
Acres Property ID:	234521
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F91001
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Brian Hardeman
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.5

FORMER FIRST TEXAS HONDA (Continued) **1024247045**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	0.5
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The property was most recently part of the First Texas Honda car dealership from 1987 until 2012 and has been vacant since that time.Two monitor wells were identified on the Subject Property. Data gaps were identified during the Phase I ESA. The location of Fashion Dry Cleaners, which was identified as a historical dry-cleaner, was not confirmed during this Phase I ESA based on historical sources of information. A previous Phase I ESA reported that the location of Fashion Dry Cleaners was on the Subject Property; however, this was not confirmed. Additionally, omissions of data in the previous Phase I and II ESA reports led to the questioning of the usability of the data in these reports. It is recommended that the monitor wells on site be properly plugged and abandoned.
Below Poverty Number:	595
Below Poverty Percent:	15.75
Meidan Income:	4723
Meidan Income Number:	1201
Meidan Income Percent:	31.79
Vacant Housing Number:	41
Vacant Housing Percent:	2.05
Unemployed Number:	111
Unemployed Percent:	2.94

3216
ESE
1/4-1/2
0.370 mi.
1956 ft.

CAPITOL CHEVROLET PARTS BUILDING
700 N BLUFF DR
AUSTIN, TX 78745

TX TANKS **S126931342**
TX CENTRAL REGISTRY **N/A**

Actual:
629 ft.

Focus Map:
17

TANKS:

Facility ID:	134902
Name:	CAPITOL CHEVROLET PARTS BUILDING
Address:	700 N BLUFF DR
City,State,Zip:	AUSTIN, TX 787454164
Total UST:	Not reported
Additional ID:	287489002018072
AI Number:	89791
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported

CAPITOL CHEVROLET PARTS BUILDING (Continued) **S126931342**

Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN110289097
Name:	CAPITOL CHEVROLET PARTS BUILDING
Address:	700 N BLUFF DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-4164
Status:	ACTIVE
Status Date:	3/13/2018
Customer Number:	CN600246029
Customer Name:	CAPITOL CHEVROLET INC
Customer Legal Name:	Capitol Chevrolet, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

3217 WNW 1/4-1/2 0.371 mi. 1961 ft. | **ROOSEVELT GARDENS 5606 ROOSEVELT AVENUE AUSTIN, TX 78756** | **US BROWNFIELDS FINDS ECHO** | **1026704007 N/A**

Actual: 668 ft.

Focus Map: 8

US BROWNFIELDS:

Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS.

ROOSEVELT GARDENS (Continued) **1026704007**

Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.

Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

ROOSEVELT GARDENS (Continued) **1026704007**

Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported
Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	8/4/2020
Redev Completition Date:	Not reported
Completed Date:	9/18/2020
Acres Cleaned Up:	1
Cleanup Funding:	95412.5
Cleanup Funding Source:	Project Transitions (Owner)
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported

ROOSEVELT GARDENS (Continued) **1026704007**

Cleanup Funding Entity:	Cost Share
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1

ROOSEVELT GARDENS (Continued) **1026704007**

Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos

ROOSEVELT GARDENS (Continued) **1026704007**

Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	8/4/2020
Redev Completition Date:	Not reported
Completed Date:	9/18/2020
Acres Cleaned Up:	1
Cleanup Funding:	100000
Cleanup Funding Source:	EPA

ROOSEVELT GARDENS (Continued) **1026704007**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Brownfields RLF Grant Funds Subgranted
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

ROOSEVELT GARDENS (Continued) **1026704007**

Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	5300000
Redev. Funding Source:	City of Austin Bond funding
Redev. Funding Entity Name:	Local Funding
Redevelopment Start Date:	9/21/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

ROOSEVELT GARDENS (Continued) **1026704007**

IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported
Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060

ROOSEVELT GARDENS (Continued) **1026704007**

IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported

ROOSEVELT GARDENS (Continued) **1026704007**

Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported
Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVENUE
Recipient name:	Austin, City of
Grant type:	BCRLF
Region:	6
Property Number:	228855
Parcel size:	1
Latitude:	30.328201
Longitude:	-97.732484
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	Project Transitions currently owns this property in North Austin that provides housing for low-income people living with HIV and AIDS. Project Transitions is a nonprofit dedicated to providing supportive living, housing, recuperative care and hospice in compassionate and caring environments for persons/families with HIV/AIDS. ABRO provided a cleanup sub-grant to assist with their affordable housing funding application through City of Austin Neighborhood Housing and Community Development/HUD. Project Transitions plans to move the current tenants to other facilities they manage, demolish the existing building, construct the new facility, and move the tenants back to the new and improved Roosevelt Gardens property within one year.
Datum:	Not reported
Acres Property ID:	241060
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	2405969
Redev. Funding Source:	Private lenders, Grants
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	9/21/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F21301
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	Y

ROOSEVELT GARDENS (Continued) **1026704007**

Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Asbestos
Contaminant Cleanup:	Asbestos
Media Affected:	Building Materials
Media Cleanup:	Building Materials
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

FINDS:
Registry ID: 110070884280

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ROOSEVELT GARDENS (Continued) **1026704007**

ECHO:

Envid:	1026704007
Registry ID:	110070884280
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070884280
Name:	ROOSEVELT GARDENS
Address:	5606 ROOSEVELT AVE
City,State,Zip:	AUSTIN, TX 78756

3218 WNW 1/4-1/2 0.373 mi. 1969 ft. | **SS6 1483** | **TX LPST** | **U001260038**
530 W BEN WHITE BLVD | **TX UST** | **N/A**
AUSTIN, TX 78704 | **TX HIST UST**

Actual: 685 ft.

Focus Map: 13

LPST:

Name:	EXXON 6 1483
Address:	530 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0026030
LPST Id:	096813
Facility Location:	530 W BEN WHITE BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/24/1990
Entered Date:	09/28/1990
Reported Date:	09/24/1990
Closure Date:	07/31/1995
Priority:	2A - GROUNDWATER OTHER THAN 1B SITE CHARACTERIZATION INCOMPLETE
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	GROUNDWATER OTHER THAN 1B, SITE CHARACTERIZATION INCOMPLETE
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	IKE IKEMBA
Responsible Party Name:	Not reported
Responsible Party Contact:	ERNIE VILLASENOR
Responsible Party Address:	PO BOX 2180
Responsible Party City,St,Zip:	HOUSTON, TX 77252 2180
Responsible Party Telephone:	713/656-7701
Reported Date:	09/24/1990
Case Start Date:	07/31/1995
Reference Number:	RN100656776
Project Manager:	UIKEMBA

UST:

Name:	SS6 1483
Address:	530 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047030
AI Number:	26030
Facility Type:	RETAIL
Facility Begin Date:	10/13/1986
Facility Status:	INACTIVE
Additional ID:	326653842002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

SS6 1483 (Continued) **U001260038**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	M BLANCK,DEALER
Contact Organization Name:	SS6 1483
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124443404
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/26/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,ENG SUPERVISOR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600123939
Owner Last Name:	EXXON MOBIL CORPORATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	679380312001134
Additional ID:	326653842002175
AI Number:	26030
Owner Effective Begin Date:	10/13/1986
State Tax ID:	11354090059
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66909

SS6 1483 (Continued) **U001260038**

Facility ID:	47920
Ai Number:	26030
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	6000

SS6 1483 (Continued) **U001260038**

UST Comprt ID:	34919
UST ID:	66909
AI Number:	26030
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66910
Facility ID:	47920
Ai Number:	26030
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

SS6 1483 (Continued) **U001260038**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	1000
UST Comprt ID:	34920
UST ID:	66910
AI Number:	26030
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

SS6 1483 (Continued) **U001260038**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66913
Facility ID:	47920
Ai Number:	26030
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

SS6 1483 (Continued) **U001260038**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	34923
UST ID:	66913
AI Number:	26030
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

SS6 1483 (Continued) **U001260038**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66912
Facility ID:	47920
Ai Number:	26030
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y

SS6 1483 (Continued) **U001260038**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	34922
UST ID:	66912
AI Number:	26030
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

SS6 1483 (Continued) **U001260038**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1964
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	66911
Facility ID:	47920
Ai Number:	26030
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

SS6 1483 (Continued) **U001260038**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	34921
UST ID:	66911
AI Number:	26030
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

SS6 1483 (Continued) **U001260038**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	EXXON MOBIL CORPORATION
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47920
Additional ID:	326653842002175
Princ ID:	679380312001134
AI Number:	26030
Facility Name:	SS6 1483
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	HEATHER GILMORE/

HIST UST AUSTIN:

Name:	EXXON #1483
Address:	530 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0193
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3219 ESE 1/4-1/2 0.374 mi. 1977 ft. **BIG LOTS** **801 E WILLIAM CANNON DR** **AUSTIN, TX 78745** **TX VCP** **TX HIST UST** **TX ASBESTOS** **S103169077** **N/A**

Actual: 669 ft.

Focus Map: 17

VCP TCEQ:

Name:	CENTURY SOUTH SHOPPING CENTER
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	REGION 11 - AUSTIN
Facility ID:	611
VCP Record Date:	09/15/1997
Facility Type:	RETAIL STORE/SHOPPING CENTER
PCA Number:	31521
Project Manager:	RSCHARLA
Phase:	COMPLETED
Acres at Site:	19.758

BIG LOTS (Continued) **S103169077**

REM Program:	VCP
RN Number:	RN102743697
Former Facility Type:	Not reported
Site Address Description:	801 EAST WILLIAM CANNON DRIVE
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	09/15/1997
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	RRR
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	01/14/1999
Standards:	3
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	09/15/1997
GW Target COC Class:	CHLORINATED SOLVENTS; METALS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Y
Application Accepted Date:	1997-10-15 00:00:00
Soil Target COC Class:	CHLORINATED SOLVENTS; METALS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	611
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	315210
Off Site?:	Not reported
Media:	MICROFILM
IOP Number:	Not reported
File Location:	CR
Latitude:	30.19
Longitude:	-97.78

Contact:

REM Program:	VCP
Program ID:	611
RN Number:	RN102743697
CN Number:	CN600411128
CN Name:	KEYSTONE-AUSTIN PROPERTY HOLDING CORP
Role Code:	BILLCONT
Contact Name:	ARCHER, KEVIN
Contact Title:	Not reported
Organization Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Mailing Address:	3267 BEE CAVES RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Contact Telephone:	(512) 328-2020

BIG LOTS (Continued) **S103169077**

Contact Telephone Ext:	0
REM Program:	VCP
Program ID:	611
RN Number:	RN102743697
CN Number:	CN603010695
CN Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Role Code:	BILLCONT
Contact Name:	ARCHER, KEVIN
Contact Title:	Not reported
Organization Name:	KEYSTONE AUSTIN PROPERTY HOLDING CORP
Mailing Address:	3267 BEE CAVES RD
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78746
Contact Telephone:	(512) 328-2020
Contact Telephone Ext:	0

HIST UST AUSTIN:

Name:	MICHAEL'S (FORMER WOOLCO)
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX
Id UST:	C0559
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	BIG LOTS
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/01/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/05/2013
Date Routed by Supervisor:	02/07/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported

BIG LOTS (Continued) **S103169077**

Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	BIG LOTS
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/20/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5

BIG LOTS (Continued) **S103169077**

Travel Time:	0.1
Mileage:	0.2
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

BIG LOTS (Continued) **S103169077**

Name:	ACADEMY SPORTS & OUTDOORS
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/20/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported

BIG LOTS (Continued) **S103169077**

Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	RENT A CENTER
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/01/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	02/05/2013
Date Routed by Supervisor:	02/07/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported

BIG LOTS (Continued) **S103169077**

Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	RENT A CENTER
Address:	801 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/20/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Bedding
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported

BIG LOTS (Continued) **S103169077**

Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TS3220 **SUNRISE MINI MART 7** **TX LPST** **U003040322**
SE **102 W POWELL LN** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78753** **TX HIST UST**
0.375 mi. **TX ENF**
1981 ft. **Site 1 of 2 in cluster TS** **TX Financial Assurance**

Actual:
722 ft.

Focus Map:
6

LPST:

Name:	STOP N GO 2154
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0039569
LPST Id:	091221
Facility Location:	102 POWELL LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/04/1987
Entered Date:	02/05/1987
Reported Date:	02/04/1987
Closure Date:	02/22/1988

SUNRISE MINI MART 7 (Continued) **U003040322**

Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	JOHN WILLRODT
Responsible Party Address:	PO BOX 758
Responsible Party City,St,Zip:	HOUSTON, TX 77001 0758
Responsible Party Telephone:	713/863-2318
Reported Date:	02/04/1987
Case Start Date:	02/22/1988
Reference Number:	RN102372182
Project Manager:	REGION

UST:

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 787535929
AI Number:	39569
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	ACTIVE
Additional ID:	647785852002149
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	KARIM KAROVALIYA,MGR
Contact Organization Name:	SUNRISE MINI MART 7
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124901530
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	SUNRISEMINIMART@HOTMAIL.COM
Signature Date On Earliest Reg Form:	05/16/2021
Signature Name/Title On Earliest Reg Form:	ABDUL K PATEL,PRESIDENT
Application Received Date On Earliest Reg Form:	05/19/2021
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	877292052005250
Additional ID:	647785852002149
Ai Number:	39569
Operator CN:	CN602904633

SUNRISE MINI MART 7 (Continued) **U003040322**

Operator Name:	AZAN INC
Operator Effective Begin Date:	11/01/2004
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	ABDUL PATEL/OWNER
Contact Organization Name:	AZAN INC
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-5325
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4417515
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN602904633
Owner Last Name:	AZAN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	5325
Contact Phone Number/Ext:	1 512 4417515/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	877292052005250
Additional ID:	647785852002149
AI Number:	39569
Owner Effective Begin Date:	11/01/2004
State Tax ID:	13200936626
Contact Role:	OWNOPRCON
Contact Name/Title:	ABDUL PATEL/OWNER
Contact Organization Name:	AZAN INC

Self Certification:

Self Cert ID:	61087
Cert ID:	371841
AI Number:	39569
Self Certification Date:	05/02/2022
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	354254
AI Number:	39569
Self Certification Date:	05/16/2021
Signature Name/Title:	ABDUL K PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	320702
AI Number:	39569
Self Certification Date:	04/24/2019
Signature Name/Title:	ABDUL K PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	303332
AI Number:	39569
Self Certification Date:	04/25/2018
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	289601
AI Number:	39569
Self Certification Date:	07/24/2017
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	270927
AI Number:	39569
Self Certification Date:	05/11/2016
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	255421
AI Number:	39569
Self Certification Date:	07/16/2015
Signature Name/Title:	ABDUL PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	254047
AI Number:	39569
Self Certification Date:	02/06/2015
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	237591
AI Number:	39569
Self Certification Date:	05/14/2014
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61087
Cert ID:	219515
AI Number:	39569
Self Certification Date:	05/03/2013
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	61087
Cert ID:	63431
AI Number:	39569
Self Certification Date:	06/29/2012
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61087
Cert ID:	63430
AI Number:	39569
Self Certification Date:	07/12/2011
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61087
Cert ID:	63429
AI Number:	39569
Self Certification Date:	06/30/2010
Signature Name/Title:	ABDUL PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63428
AI Number:	39569
Self Certification Date:	03/02/2010
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63427
AI Number:	39569
Self Certification Date:	06/26/2008
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63426
AI Number:	39569
Self Certification Date:	06/26/2007
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63425
AI Number:	39569
Self Certification Date:	01/10/2005
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63424
AI Number:	39569
Self Certification Date:	01/09/2005
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63423
AI Number:	39569
Self Certification Date:	08/09/2004
Signature Name/Title:	KENT HAMEL O&E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63422
AI Number:	39569
Self Certification Date:	08/05/2003
Signature Name/Title:	CHRIS TRINKLE O & E SPECIALIST
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63421
AI Number:	39569
Self Certification Date:	07/24/2002
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	61087
Cert ID:	63420
AI Number:	39569
Self Certification Date:	12/29/2000
Signature Name/Title:	CHRIS TRINKLE O & E SPEC
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	03/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104615
Facility ID:	61087
Ai Number:	39569
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/15/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

SUNRISE MINI MART 7 (Continued) **U003040322**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8081
UST Comprt ID:	54720
UST ID:	104615
AI Number:	39569
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM

SUNRISE MINI MART 7 (Continued) **U003040322**

Stage 1 Installation Date:	Not reported
Install Date:	03/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8081
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104616
Facility ID:	61087
Ai Number:	39569
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/15/2004
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

SUNRISE MINI MART 7 (Continued) **U003040322**

Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8081
UST Comprt ID:	54721
UST ID:	104616
AI Number:	39569
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/09/2005
Tank Registration Date:	02/21/2006
Number of Compartments:	2
Tank Capacity:	14000
Tank Singlewall:	N

SUNRISE MINI MART 7 (Continued) **U003040322**

Tank Doublewall:	Y
Pipe Type:	P
UST ID:	206315
Facility ID:	61087
Ai Number:	39569
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/09/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/01/2004

SUNRISE MINI MART 7 (Continued) **U003040322**

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	54722
UST ID:	206315
AI Number:	39569
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/09/2005

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	54723
UST ID:	206315
AI Number:	39569
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N

SUNRISE MINI MART 7 (Continued) **U003040322**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	01/09/2005

Construction Notification:

NOC ID:	7052
Facility ID:	61087
AI Number:	39569
Application Received Date:	06/03/2004
Scheduled Construction Date:	07/20/2004
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M40603007
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	21599

SUNRISE MINI MART 7 (Continued) **U003040322**

General Desc Of Prop Construct: Not reported

NOC ID:	7051
Facility ID:	61087
AI Number:	39569
Application Received Date:	11/03/2004
Scheduled Construction Date:	11/04/2004
UST Improvement:	N
UST Installation:	Y
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M41103002
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	65456

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	7595
UST ID:	Not reported
NOC ID:	7051
AI Number:	39569
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID: 28473

SUNRISE MINI MART 7 (Continued) **U003040322**

UST ID:	206315
NOC ID:	Not reported
AI Number:	39569
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000029
Company Name:	FUEL TEX
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	43641
UST ID:	206315
NOC ID:	Not reported
AI Number:	39569
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	RAYMOND HUDD
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	AZAN INC
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5325
Phone Number/Ext:	512 4417515/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61087

SUNRISE MINI MART 7 (Continued) **U003040322**

Additional ID:	647785852002149
Princ ID:	877292052005250
AI Number:	39569
Facility Name:	SUNRISE MINI MART 7
AR Number:	65456
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ABDUL PATEL/

HIST UST AUSTIN:

Name:	SUNRISE MINI MART #7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX
Id UST:	1177
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ENFORCEMENT:

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753-5929
Unique TCEQ Ref Number Of Customer:	CN602904633
Unique TCEQ Ref Number Of Reg. Entity:	RN102372182
Contact Person For The Reg. Entity:	Not reported
Owner/operator Of A Regulated Entity:	AZAN INC
Regulated Entity Associated With An NOV:	RETAIL
Org Title Of The Contact Person:	Not reported
Physical Location:	Not reported
Near City:	Not reported
Investigation Number:	000000001548307
Status Code:	RESOLVED
Status Date:	Not reported
Violation Tracking Number:	Not reported
Violation Category:	Not reported
Nov ID:	868,633,992,019,101.00
Role Code:	Not reported
Date Notice Of Violation Issued:	04/12/2019
Description 1:	Failure to maintain spill containment liquid tight.
Description 2:	This violation has been resolved and received compliance paperwork on November 05, 2019.
Category of the NOV:	Moderate
Method Of Notice Issuance:	WRITTEN
TCEQ Prog Area Monitoring Violation:	Not reported
TCEQ Rule Number Cited For The Violation:	334.51(a)(6)
Status Of The NOV:	DAPPROVED
Investigation:	1548307
Investigation ID:	Not reported
Regulated Entity ID:	Not reported
Date of Notice Enforcement:	Not reported
Violation Date:	Not reported
Rejected:	Not reported
Type Code:	Not reported
Date Resolved:	Not reported

SUNRISE MINI MART 7 (Continued) **U003040322**

Assessed Amount:	Not reported
Deferred Amount:	Not reported
Payable Amount:	Not reported
Supplemental Env Project Offset Amount:	Not reported
Nov Type:	B

TX Financial Assurance 2:

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	269653
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2022
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP688935-15
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	250838
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2021
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP688935-14
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN

SUNRISE MINI MART 7 (Continued) **U003040322**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	214303
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2019
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP688935-12
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	196648
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2018
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68893511
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	182791
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2017
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	800 577 6614
Policy Number:	PP688935-10
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	163437
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2016
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68893509
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	146415
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2015
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-08
Coverage Amount:	1,000,000

SUNRISE MINI MART 7 (Continued) **U003040322**

Coverage Expiration Date:	02/19/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	145120
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2015
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68883508
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	129064
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2014
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-07
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087

SUNRISE MINI MART 7 (Continued) **U003040322**

Finass ID:	108088
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2013
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP68893506
Coverage Amount:	1,000,000
Coverage Expiration Date:	02/19/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	4998
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2012
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-05
Coverage Amount:	1000000
Coverage Expiration Date:	02/19/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	43478
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SUNRISE MINI MART 7 (Continued) **U003040322**

Financial Assurance Begin Date:	02/19/2011
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-04
Coverage Amount:	1000000
Coverage Expiration Date:	02/19/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	43479
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2010
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-03
Coverage Amount:	1000000
Coverage Expiration Date:	02/19/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	43480
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/19/2008
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688935-01
Coverage Amount:	1000000
Coverage Expiration Date:	02/19/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

SUNRISE MINI MART 7 (Continued) **U003040322**

Name:	SUNRISE MINI MART 7
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	61087
Finass ID:	43481
AI:	39569
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	05/19/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

TS3221 **DIAMOND SHAMROCK 2154** **TX RDR** **S127532156**
SE **102 W POWELL LN** **N/A**
1/4-1/2 **AUSTIN, TX**
0.375 mi.
1981 ft. **Site 2 of 2 in cluster TS**

Actual:
722 ft.

Focus Map:
6

RDR:

RDR ID:	14060
Facility ID:	39569
RN:	Not reported
CN:	Not reported
Name:	DIAMOND SHAMROCK 2154
Address:	102 W POWELL LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/6/2004
Due Date:	2/4/2005
Tank Owner:	DIAMOND SHAMROCK STATIONS
Contact Person:	C SHAY WIDEMAN
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/26/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	91221
Comments:	6A REOPEN OR NEW LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	1/26/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3222 WNW 1/4-1/2 0.386 mi. 2036 ft. | **THE CORNER STORE 525 W BEN WHITE BLVD AUSTIN, TX 78704** | **TX LPST TX UST TX ASBESTOS TX Financial Assurance TX GCC** | **U001267910 N/A**

Actual: 684 ft.

Focus Map: 13

LPST:

Name:	FORMER SHOPPERS MART 8
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0034917
LPST Id:	097504
Facility Location:	525 W BEN WHITE BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/19/1990
Entered Date:	12/12/1990
Reported Date:	11/19/1990
Closure Date:	02/05/2016
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6P - FINAL PENDING WELL PLUG
Priority Description:	Groundwater is affected.
Status:	**MONITORING**
Coordinators Primary:	1/1P/1/1P/1/2
Coordinators RPR:	SDC
Responsible Party Name:	Not reported
Responsible Party Contact:	ALLEN SMITH
Responsible Party Address:	PO BOX 6156
Responsible Party City,St,Zip:	AUSTIN, TX 78762
Responsible Party Telephone:	512/385-2020
Reported Date:	11/19/1990
Case Start Date:	02/05/2016
Reference Number:	RN102833407
Project Manager:	DCRAWFOR

UST:

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047029
AI Number:	34917
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	815366162002231
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	JOSE CARRANZA,PRESIDENT
Contact Organization Name:	THE CORNER STORE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

THE CORNER STORE (Continued) **U001267910**

Contact Telephone:	5127892390
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	05/06/2022
Signature Name/Title On Earliest Reg Form:	JOSE CARRANZA,PRES
Application Received Date On Earliest Reg Form:	05/06/2022
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	166422332010130
Additional ID:	815366162002231
Ai Number:	34917
Operator CN:	CN603668310
Operator Name:	UNION HERITAGE INC
Operator Effective Begin Date:	05/17/2011
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	JOSE CARRANZA/PRESIDENT
Contact Organization Name:	UNION HERITAGE INC
Contact Mailing Address (Delivery):	7717 MARBLE CREST DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78747-4075
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	7892390
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603668310
Owner Last Name:	UNION HERITAGE INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	7717 MARBLE CREST DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78747
Contact Mailing Zip5:	4075
Contact Phone Number/Ext:	1 512 7892390/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	166422332010130
Additional ID:	815366162002231
AI Number:	34917

THE CORNER STORE (Continued) **U001267910**

Owner Effective Begin Date:	05/17/2011
State Tax ID:	32040422415
Contact Role:	OWNCON
Contact Name/Title:	JOSE CARRANZA/PRESIDENT
Contact Organization Name:	UNION HERITAGE INC

Self Certification:

Self Cert ID:	77353
Cert ID:	371986
AI Number:	34917
Self Certification Date:	05/06/2022
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	354664
AI Number:	34917
Self Certification Date:	05/04/2021
Signature Name/Title:	JOSE CARRANZA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	336878
AI Number:	34917
Self Certification Date:	05/03/2020
Signature Name/Title:	JOSE CARRANZA OWNER/PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2021

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	319871
AI Number:	34917
Self Certification Date:	04/30/2019
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	303800
AI Number:	34917
Self Certification Date:	05/08/2018
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	286750
AI Number:	34917
Self Certification Date:	04/29/2017
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2018

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	270029
AI Number:	34917
Self Certification Date:	04/29/2016
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	253148
AI Number:	34917
Self Certification Date:	04/29/2015
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	236933
AI Number:	34917
Self Certification Date:	05/13/2014
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2015

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	77353
Cert ID:	219176
AI Number:	34917
Self Certification Date:	04/29/2013
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	N

Self Cert ID:	77353
Cert ID:	115349
AI Number:	34917
Self Certification Date:	06/17/2012
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115348
AI Number:	34917
Self Certification Date:	05/18/2011
Signature Name/Title:	JOSE CARRANZA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2012

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115347
AI Number:	34917
Self Certification Date:	05/17/2011
Signature Name/Title:	JOSE CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115346
AI Number:	34917
Self Certification Date:	04/24/2010
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115345
AI Number:	34917
Self Certification Date:	04/23/2010
Signature Name/Title:	JOSE CARRANZA PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2010

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115344
AI Number:	34917
Self Certification Date:	11/23/2009
Signature Name/Title:	LILLIAN CARRANZA PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	05/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115343
AI Number:	34917
Self Certification Date:	06/04/2007
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115342
AI Number:	34917
Self Certification Date:	07/01/2006
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115341
AI Number:	34917
Self Certification Date:	06/30/2005
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115340
AI Number:	34917
Self Certification Date:	06/24/2004
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115339
AI Number:	34917
Self Certification Date:	06/30/2003
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004

THE CORNER STORE (Continued) **U001267910**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115338
AI Number:	34917
Self Certification Date:	06/06/2002
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	77353
Cert ID:	115337
AI Number:	34917
Self Certification Date:	12/19/2000
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92279
Facility ID:	77353
Ai Number:	34917
Tank Id:	1A

THE CORNER STORE (Continued) **U001267910**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	120106
UST ID:	92279
AI Number:	34917

THE CORNER STORE (Continued) **U001267910**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92280
Facility ID:	77353
Ai Number:	34917
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

THE CORNER STORE (Continued) **U001267910**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	2A
Tank Capacity:	10000
UST Comprt ID:	120107
UST ID:	92280
AI Number:	34917
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

THE CORNER STORE (Continued) **U001267910**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92281
Facility ID:	77353
Ai Number:	34917
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

THE CORNER STORE (Continued) **U001267910**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/20/1990

Compartment Records:

Tank ID:	3A
Tank Capacity:	4000
UST Comprt ID:	120108
UST ID:	92281
AI Number:	34917
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

THE CORNER STORE (Continued) **U001267910**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1991
Tank Registration Date:	12/22/2000
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196080
Facility ID:	77353
Ai Number:	34917
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

THE CORNER STORE (Continued) **U001267910**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	120109
UST ID:	196080
AI Number:	34917
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

THE CORNER STORE (Continued) **U001267910**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1991
Tank Registration Date:	12/22/2000
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196137
Facility ID:	77353
Ai Number:	34917
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

THE CORNER STORE (Continued) **U001267910**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	120110
UST ID:	196137
AI Number:	34917
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

THE CORNER STORE (Continued) **U001267910**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1991
Tank Registration Date:	12/22/2000
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196138
Facility ID:	77353
Ai Number:	34917
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N

THE CORNER STORE (Continued) **U001267910**

PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	120111
UST ID:	196138
AI Number:	34917
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1991
Tank Registration Date:	12/22/2000

THE CORNER STORE (Continued) **U001267910**

Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	196139
Facility ID:	77353
Ai Number:	34917
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

THE CORNER STORE (Continued) **U001267910**

Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	120112
UST ID:	196139
AI Number:	34917
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	10910
Facility ID:	77353
AI Number:	34917
Application Received Date:	12/01/2009
Scheduled Construction Date:	11/27/2009
UST Improvement:	N
UST Installation:	N
UST Removal:	N

THE CORNER STORE (Continued) **U001267910**

UST Repair:	N
UST Return To Service:	N
UST Replacement:	Y
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M91201013
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22907
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	30082
UST ID:	196137
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	11740
UST ID:	Not reported
NOC ID:	10910
AI Number:	34917
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported

THE CORNER STORE (Continued) **U001267910**

Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	30083
UST ID:	196138
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	30084
UST ID:	196139
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000078
Company Name:	AUS-TEX SERVICE STATION
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported

THE CORNER STORE (Continued) **U001267910**

Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45246
UST ID:	196139
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45245
UST ID:	196138
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	45244
UST ID:	196137
NOC ID:	Not reported
AI Number:	34917
Type Of Contact:	INSTALLER

THE CORNER STORE (Continued) **U001267910**

Contractor CRP Number Or Installer ILP Number:	ILP000100
Company Name:	Not reported
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	UNION HERITAGE INC
Contact Mailing Address (Delivery):	7717 MARBLE CREST DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78747 4075
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	77353
Additional ID:	815366162002231
Princ ID:	166422332010130
AI Number:	34917
Facility Name:	THE CORNER STORE
AR Number:	70956
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	JOSE CARRANZA/

ASBESTOS:

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/14/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.2
Reg:	07

THE CORNER STORE (Continued) **U001267910**

Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/19/2013
Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704

THE CORNER STORE (Continued) **U001267910**

Date of inspection:	03/12/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.7
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/17/2014
Date Routed by Supervisor:	03/18/2014
Date Routed to PSQA:	03/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

THE CORNER STORE (Continued) **U001267910**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	269798
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2022
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000028806
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2023
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	251255
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2021
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000019191
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2022
Ins Premium Pre-Paid For Entire Yr:	Yes

THE CORNER STORE (Continued) **U001267910**

Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	231724
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2020
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000010237
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	213512
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2018
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000106143
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	179722
AI:	34917

THE CORNER STORE (Continued) **U001267910**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2017
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000101256
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	197151
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2017
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000106143
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	162302
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2016
Date Financial Assurance Form Rec:	05/06/2022

THE CORNER STORE (Continued) **U001267910**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-96954
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	144203
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2015
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00088607
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	128449
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2014
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00088607
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE

THE CORNER STORE (Continued) **U001267910**

Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	107696
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2012
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7491233
Policy Number:	04TO00080681
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	10315
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2012
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 512 4264750
Policy Number:	04-TO-00080681
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/15/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	62924
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

THE CORNER STORE (Continued) **U001267910**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2011
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 512 4264750
Policy Number:	04-TO-77994
Coverage Amount:	1000000
Coverage Expiration Date:	05/15/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	62925
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2009
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 512 4264750
Policy Number:	PP3641044-02
Coverage Amount:	1000000
Coverage Expiration Date:	05/15/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	62926
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/15/2009
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP3641044-01

THE CORNER STORE (Continued) **U001267910**

Coverage Amount:	1000000
Coverage Expiration Date:	05/15/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	62927
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2008
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	THE CORNER STORE
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	77353
Finass ID:	62928
AI:	34917
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/1994
Date Financial Assurance Form Rec:	05/06/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	TRIPLE S PETROLEUM
Address:	525 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX

THE CORNER STORE (Continued) **U001267910**

Division: RMD/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2A - Staff Action - an information request of the entity
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: FORMER SHOPPERS MART 8
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 97504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 11/19/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TRIPLE S PETROLEUM
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TRIPLE S PETROLEUM

THE CORNER STORE (Continued) **U001267910**

Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TRIPLE S PETROLEUM
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: FORMER SHOPPERS MART 8
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 97504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 11/19/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported

THE CORNER STORE (Continued) **U001267910**

Data Quality 2: Not reported

Name: FORMER SHOPPERS MART 8
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 97504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: FORMER SHOPPERS MART 8
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: REM/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: TRIPLE S PETROLEUM
Address: 525 W BEN WHITE BLVD
City,State,Zip: AUSTIN, TX
Division: RMD/PST
New Cases: Not reported
File Number: 097504
Contamination Description: GASOLINE
Date Of Earliest Known Contamination Confirmation: 12/12/1990
Enforcement Status - Level Of Agency Response: 2A - Staff Action - an information request of the entity
Enforcement Status - Site Activity Status: 2A -
Data Quality 1: E,Q
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported

THE CORNER STORE (Continued) **U001267910**

Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

TT3223 **SERVICE CENTER 11** **TX LPST** **U001542523**
WNW **3616 S 1ST ST** **TX ASBESTOS** **N/A**
1/4-1/2 **AUSTIN, TX 78767**
0.388 mi.
2048 ft. **Site 1 of 2 in cluster TT**

Actual:
674 ft.

Focus Map:
13

LPST:

Name:	SERVICE CENTER 11
Address:	3616 S 1ST ST
City,State,Zip:	AUSTIN, TX 78767
Facility ID:	0018148
LPST Id:	093394
Facility Location:	3616 S 1ST ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	05/31/1989
Entered Date:	08/07/1989
Reported Date:	05/31/1989
Closure Date:	07/29/1997
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2/1/2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	MARC CHILDERS
Responsible Party Address:	6301A HAROLD CT
Responsible Party City,St,Zip:	AUSTIN, TX 78721
Responsible Party Telephone:	512/928-1492
Reported Date:	05/31/1989
Case Start Date:	07/29/1997
Reference Number:	RN103154134
Project Manager:	HWELCH

ASBESTOS:

Name:	AUSTIN WATER UTILITY - SOUTH SERVICE CENTER
Address:	3616 S. 1ST STREET
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	07/29/2017
Notification Number:	2017004515
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported

SERVICE CENTER 11 (Continued) **U001542523**

Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	07/03/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	07/03/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	19
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/17/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	AUSTIN WATER UTILITY - SOUTH SERVICE CENTER

SERVICE CENTER 11 (Continued) **U001542523**

Address:	3616 S. 1ST STREET
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	07/11/2017
Notification Number:	2017004515
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	06/14/2017
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	06/14/2017
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	7
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	07/05/2017
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported

SERVICE CENTER 11 (Continued) **U001542523**

Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN WATER UTILITY - SOUTH SERVICE CENTER
Address:	3616 SOUTH 1ST STREET
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	03/21/2018
Notification Number:	2018001641
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	03/12/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Abatement
Notification Type:	Amendment
Work Type Flag:	A
Certification Statement Date:	03/12/2018
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N

SERVICE CENTER 11 (Continued) **U001542523**

Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/19/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	AUSTIN WATER UTILITY - SOUTH SERVICE CENTER
Address:	3616 SOUTH 1ST STREET
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	Not reported
Reason for Inspection:	Omar Almouslli
Violation:	Not reported
Complaint Date:	03/14/2018
Notification Number:	2018001641
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	02/26/2018
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment

SERVICE CENTER 11 (Continued) **U001542523**

Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	02/26/2018
Certification Statement Phone:	512-974-7137
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM
Start Date:	03/13/2018
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TT3224 **SOUTH 1ST STREET SERVICE CTR TOW** **TX LPST** **S116698231**
WNW **3616A S 1ST ST** **N/A**
1/4-1/2 **AUSTIN, TX 78704**
0.388 mi.
2049 ft. **Site 2 of 2 in cluster TT**

Actual:
674 ft.

Focus Map:
13

LPST:

Name:	SOUTH 1ST STREET SERVICE CTR TOW
Address:	3616A S 1ST ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0057732
LPST Id:	109091
Facility Location:	3616 S 1ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/03/1994
Entered Date:	03/31/1995
Reported Date:	03/04/1994
Closure Date:	01/30/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS

SOUTH 1ST STREET SERVICE CTR TOW (Continued) **S116698231**

Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	MARC CHILDERS
Responsible Party Address:	6301 HAROLD CT
Responsible Party City,St,Zip:	AUSTIN, TX 78721
Responsible Party Telephone:	512/928-1492
Reported Date:	03/04/1994
Case Start Date:	01/30/1995
Reference Number:	RN102379963
Project Manager:	HWELCH

3225 NE 1/4-1/2 0.394 mi. 2078 ft. **ATT AUSTIN FACILITY** **TX LPST** **S116696793**
705 E 12TH ST **TX ASBESTOS** **N/A**
AUSTIN, TX 78701

Actual: 507 ft.

Focus Map: 11

LPST:

Name:	ATT AUSTIN FACILITY
Address:	705 E 12TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0063615
LPST Id:	104852
Facility Location:	705 E 12TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/15/1992
Entered Date:	03/25/1993
Reported Date:	09/15/1992
Closure Date:	11/03/1992
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JAMES OSBORNE
Responsible Party Address:	5429 LBJ FWY STE 760
Responsible Party City,St,Zip:	DALLAS, TX 75240
Responsible Party Telephone:	214/308-2168
Reported Date:	09/15/1992
Case Start Date:	11/03/1992
Reference Number:	RN102939071
Project Manager:	HWELCH

ASBESTOS:

Name:	VELOCITY CREDIT UNION
Address:	705 EAST 12TH STREET
City,State,Zip:	AUSTIN, TX 78701

ATT AUSTIN FACILITY (Continued) **S116696793**

Date of inspection:	Not reported
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	12/23/2019
Notification Number:	2019008848
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/17/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	1
Notification Work Type:	Demolition
Notification Type:	Amendment
Work Type Flag:	D
Certification Statement Date:	12/17/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/19/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

ATT AUSTIN FACILITY (Continued) **S116696793**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	VELOCITY CREDIT UNION
Address:	705 EAST 12TH STREET
City,State,Zip:	AUSTIN, TX 78701
Date of inspection:	Not reported
Reason for Inspection:	Greg Brooks
Violation:	Not reported
Complaint Date:	12/23/2019
Notification Number:	2019008848
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	NESHAP
Inspector Name:	Not reported
Date Report Received:	12/03/2019
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current/Has Amendment
Amendo:	0
Notification Work Type:	Demolition
Notification Type:	Original
Work Type Flag:	D
Certification Statement Date:	12/03/2019
Certification Statement Phone:	512-260-7171
Is The Facility a School or K-12?:	N
Region:	07
Priority:	NONE
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N

ATT AUSTIN FACILITY (Continued) **S116696793**

Ref Method:	Not reported
Analytical Method:	PLM
Start Date:	12/17/2019
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

3226 **CAPITOL METAL FINISHING INC** **SEMS-ARCHIVE** **1000264753**
ESE **3909 WAREHOUSE ROW** **CORRACTS** **TXD048452064**
1/4-1/2 **AUSTIN, TX 78704** **RCRA NonGen / NLR**
0.395 mi.
2083 ft.

Actual:
656 ft.

Focus Map:
18

SEMS Archive:

Site ID:	0604124
EPA ID:	TXD048452064
Name:	CAPITOL METAL FINISHING, INC.
Address:	3909 A WAREHOUSE ROW
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78767
Cong District:	02
FIPS Code:	48453
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	06
Site ID:	0604124
EPA ID:	TXD048452064
Site Name:	CAPITOL METAL FINISHING, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	2000-08-17 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

CAPITOL METAL FINISHING INC (Continued) **1000264753**

Region:	06
Site ID:	0604124
EPA ID:	TXD048452064
Site Name:	CAPITOL METAL FINISHING, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1990-04-01 05:00:00
Finish Date:	1990-04-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0604124
EPA ID:	TXD048452064
Site Name:	CAPITOL METAL FINISHING, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1991-10-01 04:00:00
Finish Date:	1991-10-01 04:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	06
Site ID:	0604124
EPA ID:	TXD048452064
Site Name:	CAPITOL METAL FINISHING, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	Not reported
Finish Date:	1997-10-09 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

CORRACTS:

Name:	CAPITOL METAL FINISHING INC
Address:	3909 WAREHOUSE ROW
Address 2:	Not reported
EPA ID:	TXD048452064
Area Name:	ENTIRE FACILITY
Corrective Action:	CA PRIORITIZATION-LOW CA PRIORITY
Actual Date:	19940926
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported

CAPITOL METAL FINISHING INC (Continued) **1000264753**

Surface Water Release Indicator: Not reported

Name: CAPITOL METAL FINISHING INC
Address: 3909 WAREHOUSE ROW
Address 2: Not reported
EPA ID: TXD048452064
Area Name: ENTIRE FACILITY
Corrective Action: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date: 19980911
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

RCRA Listings:

Date Form Received by Agency:	20010214
Handler Name:	Capitol Metal Finishing Inc
Handler Address:	WAREHOUSE ROW
Handler City,State,Zip:	AUSTIN, TX 78704
EPA ID:	TXD048452064
Contact Name:	FRANK WETHINGTON
Contact Address:	WAREHOUSE ROW
Contact City,State,Zip:	AUSTIN, TX 78704
Contact Telephone:	512-444-6516
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	WAREHOUSE ROW
Mailing City,State,Zip:	AUSTIN, TX 78704
Owner Name:	Capitol Metal Finishing Inc
Owner Type:	Private
Operator Name:	Capitol Metal Finishing Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

CAPITOL METAL FINISHING INC (Continued) **1000264753**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	Low
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	F006
Waste Description:	Wastewater Treatment Sludges From Electroplating Operations, Except From The Following Processes: (1) Sulfuric Acid Anodizing Of Aluminum; (2) Tin Plating On Carbon Steel; (3) Zinc Plating (Segregated Basis) On Carbon Steel; (4) Aluminum Or Zinc-Aluminum Plating On Carbon Steel; (5) Cleaning/Stripping Associated With Tin, Zinc, And Aluminum Plating On Carbon Steel; And (6) Chemical Etching And Milling Of Aluminum.
Waste Code:	F007
Waste Description:	Spent Cyanide Plating Bath Solutions From Electroplating Operations.
Waste Code:	F008
Waste Description:	Plating Bath Residues From The Bottom Of Plating Baths From Electroplating Operations In Which Cyanides Are Used In The Process.
Waste Code:	F009
Waste Description:	Spent Stripping And Cleaning Bath Solutions From Electroplating Operations In Which Cyanides Are Used In The Process.
Waste Code:	F019
Waste Description:	Wastewater Treatment Sludges From The Chemical Conversion Coating Of Aluminum, Except From Zirconium Phosphating In Aluminum Can Washing

CAPITOL METAL FINISHING INC (Continued) **1000264753**

When Such Phosphating Is An Exclusive Conversion Coating Process.

Waste Code: P029
Waste Description: Copper Cyanide (Or) Copper Cyanide Cu(Cn)

Waste Code: P030
Waste Description: Cyanides (Soluble Cyanide Salts), Not Otherwise Specified

Waste Code: P098
Waste Description: Potassium Cyanide (Or) Potassium Cyanide K(Cn)

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: P121
Waste Description: Zinc Cyanide (Or) Zinc Cyanide Zn(Cn)2

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CAPITOL METAL FINISHING INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 3909 WAREHOUSE ROW
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-444-6516
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CAPITOL METAL FINISHING INC
Legal Status: Private
Date Became Current: 20010214
Date Ended Current: Not reported
Owner/Operator Address: 3909 WAREHOUSE ROW
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-444-6516
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JAMES T LONG
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3909 WAREHOUSE ROW
Owner/Operator City,State,Zip: AUSTIN, TX 78704
Owner/Operator Telephone: 512-444-6516
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: LONG, JAMES T.
Legal Status: Private

CAPITOL METAL FINISHING INC (Continued) **1000264753**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3909 WAREHOUSE ROW
Owner/Operator City,State,Zip:	UNKNOWN, TX 00000-0000
Owner/Operator Telephone:	512-444-6516
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960625
Handler Name:	CAPITOL METAL FINISHING
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010214
Handler Name:	CAPITOL METAL FINISHING INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Tx
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19900301
Handler Name:	CAPITOL MTL FNSHNG
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	332813
NAICS Description:	ELECTROPLATING, PLATING, POLISHING, ANODIZING, AND COLORING

NAICS Code:	333298
NAICS Description:	ALL OTHER INDUSTRIAL MACHINERY MANUFACTURING

CAPITOL METAL FINISHING INC (Continued) **1000264753**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

3227 WNW 1/4-1/2 0.395 mi. 2085 ft. **RICK HOFF**
4333 S 1ST ST
AUSTIN, TX 78745
TX LPST **U001292429**
TX UST **N/A**

Actual: 668 ft.

Focus Map: 17

LPST:

Name:	FORMER RICK HOFF AUTO SERVICE
Address:	4333 S 1ST ST
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0063366
LPST Id:	104510
Facility Location:	4333 SOUTH FIRST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/25/1992
Entered Date:	09/30/1992
Reported Date:	08/25/1992
Closure Date:	04/30/2003
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1P/1/2
Coordinators RPR:	TSH
Responsible Party Name:	Not reported
Responsible Party Contact:	CARMEN HOFF
Responsible Party Address:	4333 S 1ST ST
Responsible Party City,St,Zip:	AUSTIN, TX 78745
Responsible Party Telephone:	512/441-3019
Reported Date:	08/25/1992
Case Start Date:	04/30/2003
Reference Number:	RN101491512
Project Manager:	TSH

UST:

Name:	RICK HOFF
Address:	4333 S 1ST ST
City,State,Zip:	AUSTIN, TX 787451128
AI Number:	63366
Facility Type:	RETAIL
Facility Begin Date:	07/24/1992
Facility Status:	INACTIVE
Additional ID:	603588982002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

RICK HOFF (Continued) **U001292429**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	RICK HOFF,
Contact Organization Name:	RICK HOFF
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124413019
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/23/1992
Signature Name/Title On Earliest Reg Form:	MARIE KLECK,
Application Received Date On Earliest Reg Form:	07/24/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780118
Owner Last Name:	HOFF RICK
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	594588972002053
Additional ID:	603588982002053
AI Number:	63366
Owner Effective Begin Date:	07/24/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	07/24/1992
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	146316

RICK HOFF (Continued) **U001292429**

Facility ID:	93882
Ai Number:	63366
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	550

RICK HOFF (Continued) **U001292429**

UST Comprt ID:	159456
UST ID:	146316
AI Number:	63366
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24640
Cert ID:	68868
UST Comprt ID:	181146
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A

Self Cert ID:	24640
Cert ID:	68867
UST Comprt ID:	181147
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A

RICK HOFF (Continued) **U001292429**

Self Cert ID:	24640
Cert ID:	68866
UST Comprt ID:	181148
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	221309
UST Comprt ID:	634662
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68863
UST Comprt ID:	181149
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68865
UST Comprt ID:	181151
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68871
UST Comprt ID:	181143
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	235026
UST Comprt ID:	674612
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68869
UST Comprt ID:	181145
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640

RICK HOFF (Continued) **U001292429**

Cert ID:	251712
UST Comprt ID:	723692
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68873
UST Comprt ID:	181142
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68870
UST Comprt ID:	181144
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68864
UST Comprt ID:	181150
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A

Install Date:	08/31/1987
Tank Registration Date:	07/24/1992
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	146317
Facility ID:	93882
Ai Number:	63366
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

RICK HOFF (Continued) **U001292429**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	2000
UST Comprt ID:	159457
UST ID:	146317
AI Number:	63366
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

RICK HOFF (Continued) **U001292429**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24640
Cert ID:	68868
UST Comprt ID:	181146
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68867
UST Comprt ID:	181147
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68866
UST Comprt ID:	181148
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	221309
UST Comprt ID:	634662
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640

RICK HOFF (Continued) **U001292429**

Cert ID: 68863
UST Comprt ID: 181149
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 68865
UST Comprt ID: 181151
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 68871
UST Comprt ID: 181143
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 235026
UST Comprt ID: 674612
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 68869
UST Comprt ID: 181145
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 251712
UST Comprt ID: 723692
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 68873
UST Comprt ID: 181142
UST ID: 60750
AI Number: 63366
Tank ID: 4
Compartment ID: A

Self Cert ID: 24640
Cert ID: 68870

RICK HOFF (Continued) **U001292429**

UST Comprt ID:	181144
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68864
UST Comprt ID:	181150
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	07/24/1992
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	146318
Facility ID:	93882
Ai Number:	63366
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

RICK HOFF (Continued) **U001292429**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	2000
UST Comprt ID:	159458
UST ID:	146318
AI Number:	63366
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

RICK HOFF (Continued) **U001292429**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24640
Cert ID:	68868
UST Comprt ID:	181146
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68867
UST Comprt ID:	181147
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68866
UST Comprt ID:	181148
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	221309
UST Comprt ID:	634662
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68863
UST Comprt ID:	181149
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68865
UST Comprt ID:	181151
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68871

RICK HOFF (Continued) **U001292429**

UST Comprt ID:	181143
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	235026
UST Comprt ID:	674612
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68869
UST Comprt ID:	181145
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	251712
UST Comprt ID:	723692
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68873
UST Comprt ID:	181142
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68870
UST Comprt ID:	181144
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68864
UST Comprt ID:	181150
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	07/24/1992

RICK HOFF (Continued) **U001292429**

Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	146319
Facility ID:	93882
Ai Number:	63366
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/26/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N

RICK HOFF (Continued) **U001292429**

Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/06/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	4000
UST Comprt ID:	159459
UST ID:	146319
AI Number:	63366
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	24640
Cert ID:	68868
UST Comprt ID:	181146
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640

RICK HOFF (Continued) **U001292429**

Cert ID:	68867
UST Comprt ID:	181147
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68866
UST Comprt ID:	181148
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	221309
UST Comprt ID:	634662
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68863
UST Comprt ID:	181149
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68865
UST Comprt ID:	181151
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68871
UST Comprt ID:	181143
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	235026
UST Comprt ID:	674612
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68869

RICK HOFF (Continued) **U001292429**

UST Comprt ID:	181145
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	251712
UST Comprt ID:	723692
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68873
UST Comprt ID:	181142
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68870
UST Comprt ID:	181144
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A
Self Cert ID:	24640
Cert ID:	68864
UST Comprt ID:	181150
UST ID:	60750
AI Number:	63366
Tank ID:	4
Compartment ID:	A

Facility Billing Contacts:

Contact Organization Name:	HOFF RICK
Contact Mailing Address (Delivery):	4333 S 1ST ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78745 1128
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93882
Additional ID:	603588982002053
Princ ID:	594588972002053
AI Number:	63366
Facility Name:	RICK HOFF
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	RICK HOFF/

3228 ESE 1/4-1/2 0.397 mi. 2095 ft. | **BEKINS MOVING STORAGE**
201 E ANDERSON LN
AUSTIN, TX 78752 | **TX LPST** | **S116702437**
N/A

Actual: 722 ft.

Focus Map: 6

LPST:

Name:	BEKINS MOVING STORAGE
Address:	201 E ANDERSON LN
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0035428
LPST Id:	093515
Facility Location:	201 E ANDERSON LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/23/1989
Entered Date:	08/31/1989
Reported Date:	08/23/1989
Closure Date:	09/25/1989
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	CAMILLE AUSTEN
Responsible Party Address:	777 FLOWER ST
Responsible Party City,St,Zip:	GLENDALE, CA 91201
Responsible Party Telephone:	818/545-3270
Reported Date:	08/23/1989
Case Start Date:	09/25/1989
Reference Number:	RN102431244
Project Manager:	HWELCH

3229 WNW 1/4-1/2 0.401 mi. 2117 ft. | **C STORE**
4111 S 1ST
AUSTIN, TX | **TX RDR** | **S127533603**
N/A

Actual: 684 ft.

Focus Map: 13

RDR:

RDR ID:	27679
Facility ID:	45208
RN:	Not reported
CN:	Not reported
Name:	C STORE
Address:	4111 S 1ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	11/4/2019
Due Date:	1/3/2020
Tank Owner:	809 VARGAS LC
Contact Person:	PATRICK OLIVER
Report:	RDR
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	12/30/2019
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported

C STORE (Continued) **S127533603**

Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TU3230 **PLAZA SALTILLO BLK 5** **TX RDR** **S127541140**
East **1301 E 5TH ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.408 mi.
2153 ft. **Site 1 of 2 in cluster TU**

Actual:
473 ft.

Focus Map:
11

RDR:

RDR ID:	24873
Facility ID:	89304
RN:	Not reported
CN:	Not reported
Name:	PLAZA SALTILLO BLK 5
Address:	1301 E 5TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/17/2017
Due Date:	10/16/2017
Tank Owner:	PLAZA SALTILLO TOD LTD
Contact Person:	DON BULLOCH
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	3/7/2018
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not able to locate at this time.
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TU3231 **PLAZA SALTILLO** **TX TANKS** **S126921047**
East **1301 E 5TH ST** **TX HIST UST** **N/A**
1/4-1/2 **AUSTIN, TX 78702** **TX CENTRAL REGISTRY**
0.408 mi.
2153 ft. **Site 2 of 2 in cluster TU**

Actual:
473 ft.

Focus Map:
11

TANKS:

Facility ID:	134417
Name:	PLAZA SALTILLO
Address:	1301 E 5TH ST

PLAZA SALTILLO (Continued) **S126921047**

City,State,Zip:	AUSTIN, TX 78702
Total UST:	Not reported
Additional ID:	907339852017188
AI Number:	89304
Facility Type:	Not reported
Facility Begin Date:	Not reported
Facility Status:	PENDING
Facility Exempt Status:	Not reported
Records Off-Site:	N
UST Financial Assurance Required:	Not reported
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address 1:	Not reported
Contact Mailing Address 2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Facility Contact Address Deliverable:	Not reported
Application Received Date On Earliest Reg Form:	Not reported
Signature Date On Earliest Reg Form:	Not reported
Signature Name/Title On Earliest Reg Form:	,
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	N
Enforcement Action Date:	Not reported
Facility Not Inspectable:	N
Facility Not Inspectable Reason A:	Not reported
Facility Not Inspectable Reason B:	Not reported

HIST UST AUSTIN:

Name:	PLAZA SALTILLO
Address:	1301 E. 5TH ST.
City,State,Zip:	AUSTIN, TX
Id UST:	3416
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN109836981
Name:	PLAZA SALTILLO
Address:	1301 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-
Status:	ACTIVE
Status Date:	7/7/2017
Customer Number:	CN605386887
Customer Name:	PS TOD VENTURES LTD
Customer Legal Name:	PS TOD Ventures, Ltd.

PLAZA SALTILLO (Continued) **S126921047**

Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	6/29/2017
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109836981
Name:	PLAZA SALTILLO
Address:	1301 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-
Status:	ACTIVE
Status Date:	7/7/2017
Customer Number:	CN602866634
Customer Name:	ROGERS-OBRIEN CONSTRUCTION COMPANY LTD
Customer Legal Name:	Rogers-O'Brien Construction Company, Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	5/11/2018
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109836981
Name:	PLAZA SALTILLO
Address:	1301 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-
Status:	ACTIVE
Status Date:	2017-07-07
Customer Number:	CN605386887
Customer Name:	PS TOD VENTURES LTD
Customer Legal Name:	PS TOD Ventures, Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2017-06-29
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN109836981
Name:	PLAZA SALTILLO
Address:	1301 E 5TH ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78702-
Status:	ACTIVE
Status Date:	2017-07-07
Customer Number:	CN602866634
Customer Name:	ROGERS-OBRIEN CONSTRUCTION COMPANY LTD
Customer Legal Name:	Rogers-O'Brien Construction Company, Ltd.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	2018-05-11
Affiliation End Date:	3000-12-31

PLAZA SALTILLO (Continued) **S126921047**

Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

3232 NE 1/4-1/2 0.411 mi. 2170 ft.

MR MCS GROCERY & MARKET
2109 HOLLY ST
AUSTIN, TX 78702

TX UST **U001253704**
TX HIST UST **N/A**
TX ASBESTOS
TX Financial Assurance
TX RDR

Actual: 456 ft.

Focus Map: 15

UST:

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 787025524
AI Number:	18793
Facility Type:	RETAIL
Facility Begin Date:	01/01/1978
Facility Status:	INACTIVE
Additional ID:	957610022002053
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	MR MCS GROCERY & MARKET
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124748482
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	07/06/2018
Signature Name/Title On Earliest Reg Form:	GUY OLIVER,PRES
Application Received Date On Earliest Reg Form:	07/09/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	335739642002204
Additional ID:	957610022002053
Ai Number:	18793
Operator CN:	CN601413677
Operator Name:	720 LAMAR PLACE LC
Operator Effective Begin Date:	12/09/2008
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	GUY OLIVER/
Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137

MR MCS GROCERY & MARKET (Continued) **U001253704**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78746-6771
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	9276100
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601413677
Owner Last Name:	720 LAMAR PLACE LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6110
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6110
Contact Phone Number/Ext:	1 512 9276100/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	335739642002204
Additional ID:	957610022002053
AI Number:	18793
Owner Effective Begin Date:	12/09/2008
State Tax ID:	30118952057
Contact Role:	OWNCON
Contact Name/Title:	GUY OLIVER/AUTH REP
Contact Organization Name:	720 LAMAR PLACE L C

Self Certification:

Self Cert ID:	80378
Cert ID:	290407
AI Number:	18793
Self Certification Date:	08/15/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	80378
Cert ID:	273437
AI Number:	18793
Self Certification Date:	08/11/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	80378
Cert ID:	255686
AI Number:	18793
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	80378
Cert ID:	238875
AI Number:	18793
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80378
Cert ID:	223213
AI Number:	18793
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	80378
Cert ID:	131819
AI Number:	18793
Self Certification Date:	07/13/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	80378
Cert ID:	131818
AI Number:	18793
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131817
AI Number:	18793
Self Certification Date:	07/27/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131816
AI Number:	18793
Self Certification Date:	05/28/2009
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131815
AI Number:	18793
Self Certification Date:	12/12/2008
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131814
AI Number:	18793
Self Certification Date:	09/05/2005
Signature Name/Title:	ABDUL HUSSAINI MGR
Signature Type Role:	LEGAL AUTH REP OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131813
AI Number:	18793
Self Certification Date:	12/01/2004
Signature Name/Title:	FAHD LAKHANI
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131812
AI Number:	18793
Self Certification Date:	07/31/2003
Signature Name/Title:	KHALID TAREEN MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131811
AI Number:	18793
Self Certification Date:	08/30/2002
Signature Name/Title:	KHUSHI MOHAMMAD SUPR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131810
AI Number:	18793
Self Certification Date:	08/29/2002
Signature Name/Title:	KHUSHI MOHAMMAD SUPR
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	80378
Cert ID:	131809
AI Number:	18793
Self Certification Date:	01/22/2001
Signature Name/Title:	GODFREY THOMAS STORE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	48836
Facility ID:	80378
Ai Number:	18793
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/04/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

MR MCS GROCERY & MARKET (Continued) **U001253704**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	11/26/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	130422
UST ID:	48836
AI Number:	18793
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	7233
Cert ID:	366080
UST Comprt ID:	1065846

MR MCS GROCERY & MARKET (Continued) **U001253704**

UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111999
UST Comprt ID:	333988
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	247631
UST Comprt ID:	711891
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111995
UST Comprt ID:	333990
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	350378
UST Comprt ID:	1018547
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	231585
UST Comprt ID:	664857
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112007
UST Comprt ID:	333980
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	332341
UST Comprt ID:	963701
UST ID:	122425

MR MCS GROCERY & MARKET (Continued) **U001253704**

AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112006
UST Comprt ID:	333981
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111998
UST Comprt ID:	333989
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112005
UST Comprt ID:	333982
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	313992
UST Comprt ID:	908812
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112004
UST Comprt ID:	333983
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	383940
UST Comprt ID:	1120251
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112003
UST Comprt ID:	333984
UST ID:	122425
AI Number:	18793

MR MCS GROCERY & MARKET (Continued) **U001253704**

Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111996
UST Comprt ID:	333991
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112002
UST Comprt ID:	333985
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	298824
UST Comprt ID:	863498
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112001
UST Comprt ID:	333986
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111997
UST Comprt ID:	333992
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112000
UST Comprt ID:	333987
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	281503
UST Comprt ID:	811984
UST ID:	122425
AI Number:	18793
Tank ID:	2

MR MCS GROCERY & MARKET (Continued) **U001253704**

Compartment ID:	A
Self Cert ID:	7233
Cert ID:	265202
UST Comprt ID:	763901
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Install Date:	01/01/1978
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	48835
Facility ID:	80378
Ai Number:	18793
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/04/2018
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

MR MCS GROCERY & MARKET (Continued) **U001253704**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	Y
Installation Signature Date:	11/26/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	130421
UST ID:	48835
AI Number:	18793
Compartment ID:	A
Substance Stored1:	Not reported
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM

MR MCS GROCERY & MARKET (Continued) **U001253704**

Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID:	7233
Cert ID:	366080
UST Comprt ID:	1065846
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111999
UST Comprt ID:	333988
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	247631
UST Comprt ID:	711891
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111995
UST Comprt ID:	333990
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	350378
UST Comprt ID:	1018547
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	231585
UST Comprt ID:	664857
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112007
UST Comprt ID:	333980
UST ID:	122425
AI Number:	18793
Tank ID:	2

MR MCS GROCERY & MARKET (Continued) **U001253704**

Compartment ID:	A
Self Cert ID:	7233
Cert ID:	332341
UST Comprt ID:	963701
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112006
UST Comprt ID:	333981
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111998
UST Comprt ID:	333989
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112005
UST Comprt ID:	333982
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	313992
UST Comprt ID:	908812
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112004
UST Comprt ID:	333983
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	383940
UST Comprt ID:	1120251
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A

MR MCS GROCERY & MARKET (Continued) **U001253704**

Self Cert ID:	7233
Cert ID:	112003
UST Comprt ID:	333984
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111996
UST Comprt ID:	333991
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112002
UST Comprt ID:	333985
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	298824
UST Comprt ID:	863498
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112001
UST Comprt ID:	333986
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	111997
UST Comprt ID:	333992
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	112000
UST Comprt ID:	333987
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233

MR MCS GROCERY & MARKET (Continued) **U001253704**

Cert ID:	281503
UST Comprt ID:	811984
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A
Self Cert ID:	7233
Cert ID:	265202
UST Comprt ID:	763901
UST ID:	122425
AI Number:	18793
Tank ID:	2
Compartment ID:	A

Construction Notification:

NOC ID:	32711
Facility ID:	80378
AI Number:	18793
Application Received Date:	03/07/2018
Scheduled Construction Date:	03/13/2018
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	03/07/2018
Signature Date On Form:	03/07/2018
Signature Name On Form:	CAROLYN NADAU
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	720 LAMAR PLACE LC
Owner CN At Time Of Construction:	CN601413677
Owner AR At Time Of Construction:	50118
General Desc Of Prop Construct:	**REQUESTING 30-DAY WAIVER** REMOVE FROM SITE (2) 8000 GALLON STEEL USTs AND DESTROY

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	77364
UST ID:	Not reported
NOC ID:	32711
AI Number:	18793
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	C&J PETROLEUM
Representative Name:	CHUCK NADEAU

MR MCS GROCERY & MARKET (Continued) **U001253704**

Mailing Address (Delivery):	PO BOX 1470
Mailing Address (Internal Delivery):	Not reported
Mailing City:	TEMPLE
Mailing State:	TX
Mailing Zip:	76603
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	254
Phone Number:	7219939
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	512 6372010/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	80378
Additional ID:	957610022002053
Princ ID:	335739642002204
AI Number:	18793
Facility Name:	MR MCS GROCERY & MARKET
AR Number:	50118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	MR. MC'S GROCERY
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX
Id UST:	372
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	MR MACS
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Date of inspection:	04/05/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.5
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/09/2013
Date Routed by Supervisor:	04/09/2013
Date Routed to PSQA:	04/10/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported

MR MCS GROCERY & MARKET (Continued) **U001253704**

Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	199570
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	182950
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2

MR MCS GROCERY & MARKET (Continued) **U001253704**

Facility ID:	80378
Finass ID:	165378
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	146476
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	130215
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

MR MCS GROCERY & MARKET (Continued) **U001253704**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	112246
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	112296
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No

MR MCS GROCERY & MARKET (Continued) **U001253704**

Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	9484
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73352
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73353
AI:	18793

MR MCS GROCERY & MARKET (Continued) **U001253704**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73354
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73356
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	07/09/2018

MR MCS GROCERY & MARKET (Continued) **U001253704**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 0 0
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73355
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX 78702
Region:	2
Facility ID:	80378
Finass ID:	73357
AI:	18793
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	07/09/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

MR MCS GROCERY & MARKET (Continued) **U001253704**

RDR:

RDR ID:	25838
Facility ID:	18793
RN:	Not reported
CN:	Not reported
Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/15/2018
Due Date:	8/14/2018
Tank Owner:	720 LAMAR PLACE LC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/26/2018
Project Manager:	Kim Fross
Team:	Team 3
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	21828
Facility ID:	18793
RN:	Not reported
CN:	Not reported
Name:	MR MCS GROCERY & MARKET
Address:	2109 HOLLY ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/5/2014
Due Date:	7/4/2014
Tank Owner:	720 LAMAR PLACE LC
Contact Person:	VICKI OLIVER
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/27/2014
Project Manager:	Denise Crawford
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RDR 2/18/14; DEF LTR 4/6/14, PHASE I 5/5/14
Review Coordinator:	SDC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3233 ESE 1/4-1/2 0.414 mi. 2185 ft. | **OLD SEARS WAREHOUSE 108 DENSON DR AUSTIN, TX 78752** | **TX LPST TX UST** | **U001286107 N/A**

Actual: 681 ft.

Focus Map: 9

LPST:

Name:	OLD SEARS WAREHOUSE
Address:	108 DENSON DR
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0055939
LPST Id:	096481
Facility Location:	108 DENSON DR
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	08/15/1990
Entered Date:	08/16/1990
Reported Date:	08/15/1990
Closure Date:	05/27/1999
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	HJM
Responsible Party Name:	Not reported
Responsible Party Contact:	WILL HOUSTON
Responsible Party Address:	4202 SPICEWOOD SPRINGS RD STE 100
Responsible Party City,St,Zip:	AUSTIN, TX 78759
Responsible Party Telephone:	512/346-3858
Reported Date:	08/15/1990
Case Start Date:	05/27/1999
Reference Number:	RN101490084
Project Manager:	HJM

UST:

Name:	OLD SEARS WAREHOUSE
Address:	108 DENSON DR
City,State,Zip:	AUSTIN, TX 787524149
AI Number:	55939
Facility Type:	RETAIL
Facility Begin Date:	10/01/1990
Facility Status:	INACTIVE
Additional ID:	403555162002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

OLD SEARS WAREHOUSE (Continued) **U001286107**

Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/29/1990
Signature Name/Title On Earliest Reg Form:	W B HOUSTON,PARTNER
Application Received Date On Earliest Reg Form:	09/07/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600778930
Owner Last Name:	POWELL-HOUSTON PROPERTIES CO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	395555152002053
Additional ID:	403555162002053
AI Number:	55939
Owner Effective Begin Date:	10/01/1990
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	09/07/1990
Number of Compartments:	1
Tank Capacity:	5000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	135756
Facility ID:	85761
Ai Number:	55939
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/08/1990
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

OLD SEARS WAREHOUSE (Continued) **U001286107**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	05/25/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	5000
UST Comprt ID:	132159
UST ID:	135756
AI Number:	55939
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

OLD SEARS WAREHOUSE (Continued) **U001286107**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	POWELL-HOUSTON PROPERTIES CO
Contact Mailing Address (Delivery):	504 W 7TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78701 2851
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	85761
Additional ID:	403555162002053
Princ ID:	395555152002053
AI Number:	55939
Facility Name:	OLD SEARS WAREHOUSE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	W B HOUSTON/

3234 WNW 1/4-1/2 0.414 mi. 2185 ft. | **FORMER QUIKIE PICKIE**
600 W BEN WHITE
AUSTIN, TX 78745 | **TX LPST** **TX UST** | **U001292699** **N/A**

Actual: 683 ft.

Focus Map: 13

LPST:

Name:	FORMER QUIKIE PICKIE
Address:	600 W BEN WHITE
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0063839
LPST Id:	105609
Facility Location:	600 WEST BEN WHITE BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/16/1992
Entered Date:	01/29/1993
Reported Date:	12/17/1992
Closure Date:	10/13/2005
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE SPRINGFIELD
Responsible Party Address:	1101 E ANDERSON LN
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/483-3756
Reported Date:	12/17/1992
Case Start Date:	10/13/2005
Reference Number:	RN101697043
Project Manager:	HWELCH

UST:

Name:	FORMER QUIKIE PICKIE
Address:	600 W BEN WHITE
City,State,Zip:	AUSTIN, TX 78745
AI Number:	63839
Facility Type:	RETAIL
Facility Begin Date:	11/12/1992
Facility Status:	INACTIVE
Additional ID:	550401372002075
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	,
Contact Organization Name:	FORMER QUIKIE PICKIE
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

FORMER QUIKIE PICKIE (Continued) **U001292699**

Contact Telephone:	5124833756
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/29/1992
Signature Name/Title On Earliest Reg Form:	ROBERT HARWOOD,DISTRICT ADMIN
Application Received Date On Earliest Reg Form:	10/29/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600803456
Owner Last Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	SG
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	976653722002061
Additional ID:	550401372002075
AI Number:	63839
Owner Effective Begin Date:	11/12/1992
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	10/29/1992
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147138
Facility ID:	73771
Ai Number:	63839
Tank Id:	3
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/04/1992

Compartment Records:

Tank ID:	3
Tank Capacity:	Not reported
UST Comprt ID:	104265
UST ID:	147138
AI Number:	63839
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/29/1992
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147139
Facility ID:	73771
Ai Number:	63839
Tank Id:	4
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/04/1992

Compartment Records:

Tank ID:	4
Tank Capacity:	Not reported
UST Comprt ID:	104266
UST ID:	147139
AI Number:	63839
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/29/1992
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147140
Facility ID:	73771
Ai Number:	63839
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/04/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	104267
UST ID:	147140
AI Number:	63839
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	10/29/1992
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	147141
Facility ID:	73771
Ai Number:	63839
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	08/31/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/04/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	104268
UST ID:	147141
AI Number:	63839
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N

FORMER QUIKIE PICKIE (Continued) **U001292699**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS DEPARTMENT OF TRANSPORTATION
Contact Mailing Address (Delivery):	PO BOX 15426
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78761 5426
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	73771
Additional ID:	550401372002075
Princ ID:	976653722002061
AI Number:	63839
Facility Name:	FORMER QUIKIE PICKIE
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GENE STABENO/

3235 SW 1/4-1/2 0.420 mi. 2217 ft. **LUBE PIT STOP 1951 E OLTORF AUSTIN, TX** **TX RDR** **S127528014 N/A**

Actual: 600 ft.

Focus Map: 14

RDR:

RDR ID:	18528
Facility ID:	25153
RN:	Not reported
CN:	Not reported
Name:	LUBE PIT STOP
Address:	1951 E OLTORF
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/29/2009
Due Date:	12/28/2009
Tank Owner:	GARY HUNT
Contact Person:	GARY HUNT
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	1/21/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported

LUBE PIT STOP (Continued) **S127528014**

NOLPST Letter Date:	1/21/2010
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TV3236 WSW 1/4-1/2 0.423 mi. 2231 ft. **FORMER HAROLD TIEDT SERVICE CENTER** **TX RDR** **S127528369**
302 S LAMAR BLVD **N/A**
AUSTIN, TX

Site 1 of 2 in cluster TV

Actual: 456 ft.

Focus Map: 11

RDR:

RDR ID:	16241
Facility ID:	26133
RN:	Not reported
CN:	Not reported
Name:	FORMER HAROLD TIEDT SERVICE CENTER
Address:	302 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	6/29/2007
Due Date:	8/28/2007
Tank Owner:	PPC LAND VENTURES INC
Contact Person:	MR GREG JONES
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/28/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED AN LPST#? REL DET
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/28/2007
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TW3237 ESE 1/4-1/2 0.423 mi. 2233 ft. **BEN WHITE LOTS 1,2,3,4,5** **TX VCP** **S108273107**
500 E BEN WHITE BLVD **TX GCC** **N/A**
AUSTIN, TX 78704 **TX IOP**

Site 1 of 2 in cluster TW

Actual: 668 ft.

Focus Map: 18

VCP TCEQ:

Name:	BEN WHITE LOTS 1,2,3,4,5
Address:	500 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	REGION 11 - AUSTIN
Facility ID:	2025
VCP Record Date:	02/05/2007
Facility Type:	RETAIL
PCA Number:	34221
Project Manager:	MRIGGLE

BEN WHITE LOTS 1,2,3,4,5 (Continued) **S108273107**

Phase:	COMPLETED
Acres at Site:	12.306
REM Program:	VCP
RN Number:	RN104722301
Former Facility Type:	Not reported
Site Address Description:	500 E BEN WHITE, 3700 AND 3900 PAYLOAD PASS
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	02/05/2007
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	TRRP
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	73960
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	2
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	07/30/2010; 11/16/2007
Standards:	B
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	02/02/2007
GW Target COC Class:	METALS; CHLORINATED SOLVENTS
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2007-02-06 00:00:00
Soil Target COC Class:	METALS; CHLORINATED SOLVENTS
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2025
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	342210
Off Site?:	Not reported
Media:	MICROFILM; PAPER
IOP Number:	580
File Location:	D/200-12; CR
Latitude:	30.22
Longitude:	-97.75

Contact:

REM Program:	VCP
Program ID:	2025
RN Number:	RN104722301
CN Number:	CN602890451
CN Name:	KMS RETAIL-BEN WHITE LP
Role Code:	APPLCONT
Contact Name:	FOOSE, BILL
Contact Title:	PARTNER
Organization Name:	KMS RETAIL BEN WHITE LP
Mailing Address:	8350 N CENTRAL EXPY STE 1275
Mailing City:	DALLAS
Mailing State:	TX

BEN WHITE LOTS 1,2,3,4,5 (Continued) **S108273107**

Mailing Zip: 75206
Contact Telephone: (214) 363-3900
Contact Telephone Ext: 0

GCC:
Name: KMS RETAIL PAYLOAD PASS
Address: 500 E BEN WHITE, 3700, 3900 PAYLOAD
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 580
Contamination Description: VOCS, METALS
Date Of Earliest Known Contamination Confirmation: 10/17/2006
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: KMS RETAIL PAYLOAD PASS
Address: 500 E BEN WHITE, 3700, 3900 PAYLOAD
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 580
Contamination Description: VOCS, METALS
Date Of Earliest Known Contamination Confirmation: 10/17/2006
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: KMS RETAIL PAYLOAD PASS
Address: 500 E BEN WHITE, 3700, 3900 PAYLOAD
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 580
Contamination Description: VOCS, METALS
Date Of Earliest Known Contamination Confirmation: 10/17/2006
Enforcement Status - Level Of Agency Response: 1B -
Enforcement Status - Site Activity Status: 1B -
Data Quality 1: E

BEN WHITE LOTS 1,2,3,4,5 (Continued) **S108273107**

Section 5236: Not reported
Type: TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

Name: KMS RETAIL PAYLOAD PASS
Address: 500 E BEN WHITE, 3700, 3900 PAYLOAD
City,State,Zip: AUSTIN, TX
Division: RMD/VCIO
New Cases: Not reported
File Number: 580
Contamination Description: VOCS, METALS
Date Of Earliest Known Contamination Confirmation: 10/17/2006
Enforcement Status - Level Of Agency Response: -
Enforcement Status - Site Activity Status: 6 -
Data Quality 1: E
Section 5236: Not reported
Type: GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

IOP:
Name: KMS RETAIL PAYLOAD PASS
Address: 500 E BEN WHITE BLVD
City,State,Zip: AUSTIN, TX 78704
Program ID: 580
Date IOP Received: Not reported
Region: REGION 11 - AUSTIN
Phase: COMPLETED
Interest In Site: Not reported
PCA Number: 32580
Property Use: PROPERTY COMMERCIAL
Project Manager: MRIGGLE
Project Number: 325800
Latitude: 30.22
Longitude: -97.75
Acres: 9.965
Media Affected: Not reported
LPST Number: 14327; 63849; 19600
VCP ID: Not reported
Cert Issued: 04/27/2010; 05/17/2010
Solid Waste Regn Number: Not reported
EPA TX ID/Cerclis regn Number: Not reported
Contaminant Categories: Not reported
Applicant Information: Not reported
Applicant First Name: Not reported
Applicant Last Name: Not reported
Applicant Title: Not reported
Applicant Address: Not reported
Applicant City,State,Zip: Not reported

BEN WHITE LOTS 1,2,3,4,5 (Continued) **S108273107**

Applicant Phone:	Not reported
Applicant Fax:	Not reported
Consultant/Attorney:	Not reported
Consultant/Attorney First Name:	Not reported
Consultant/Attorney Last Name:	Not reported
Consultant/Attorney Title:	Not reported
Consultant/Attorney Address:	Not reported
Consultant/Attorney City,State,Zip:	Not reported
REM Program:	IOP
RN Number:	RN104722301
Consultant/Attorney Phone:	Not reported
Site Address Description:	500 E BEN WHITE, 3700 AND 3900 PAYLOAD PASS
Administrative Status:	INACTIVE
Consultant/Attorney Fax:	Not reported
Cashier Received Date:	10/17/2006
Application Received Date:	10/17/2006
Application Acceptance Date:	Not reported
IOP Application Accepted:	Not reported
SWR Number:	Not reported
GW COCS in Certificate:	Not reported
Sediment COCS in Certificate:	Not reported
Soil COCS in Certificate:	Not reported
EPA TXD Cerclis Number:	Not reported
File Media:	PAPER; MICROFILM
File Location:	CR

Customer:

REM Program:	IOP
Program ID:	580
RN Number:	RN104722301
CN Number:	CN602890451
CN Name:	KMS RETAIL-BEN WHITE LP
Role CD:	APPLCONT
Contact Name:	FOOSE, BILL
Contact Title:	PARTNER
Organization Name:	KMS RETAIL BEN WHITE LP
Mailing Address:	8350 N CENTRAL EXPY STE 1275
Mailing City:	DALLAS
Mailing State:	TX
Mailing Zip:	75206
Contact Phone:	(214) 363-3900
Contact Ext:	0

3238 **7-ELEVEN 35805** **TX LPST** **U001280238**
North **13641 N IH 35** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78753** **TX Financial Assurance**
0.425 mi.
2244 ft.

Actual:
782 ft.

Focus Map:
2

LPST:

Name:	QUIX 492
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Facility ID:	0049321
LPST Id:	099597
Facility Location:	N IH 35 @ HOWARD LN W ACCESS RD CORNER
TCEQ Region# and City:	REGION 11 - AUSTIN

7-ELEVEN 35805 (Continued) **U001280238**

Region City:	AUSTIN
Discovered Date:	07/18/1991
Entered Date:	07/22/1991
Reported Date:	07/18/1991
Closure Date:	09/16/2003
Priority:	4.0 - ASSESSMENT INCOMPLETE NO APPARENT RECEPTORS IMPACTED
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	4.0
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P/1
Coordinators RPR:	TSH
Responsible Party Name:	Not reported
Responsible Party Contact:	MELINDA GREGER
Responsible Party Address:	PO BOX 6117
Responsible Party City,St,Zip:	TEMPLE, TX 76503 6117
Responsible Party Telephone:	254/778-3547
Reported Date:	07/18/1991
Case Start Date:	09/16/2003
Reference Number:	RN102401098
Project Manager:	TSH

UST:

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 787531017
AI Number:	49321
Facility Type:	RETAIL
Facility Begin Date:	11/09/1989
Facility Status:	ACTIVE
Additional ID:	204772282002150
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78753
Contact Name/Title:	PEGGIE BETZ,ENV COMP SPEC
Contact Organization Name:	7-ELEVEN 35805
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/17/2018
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,REGION COMP MGR
Application Received Date On Earliest Reg Form:	10/29/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

7-ELEVEN 35805 (Continued) **U001280238**

Operator:

Princ ID:	959578622001257
Additional ID:	204772282002150
Ai Number:	49321
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	06/04/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	204772282002150
AI Number:	49321
Owner Effective Begin Date:	06/04/2012
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	52622
Cert ID:	382009
AI Number:	49321
Self Certification Date:	01/12/2023

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	52622
Cert ID:	364691
AI Number:	49321
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	52622
Cert ID:	348343
AI Number:	49321
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	52622
Cert ID:	330747
AI Number:	49321
Self Certification Date:	01/09/2020

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	314633
AI Number:	49321
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	295967
AI Number:	49321
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	281162
AI Number:	49321
Self Certification Date:	01/20/2017

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	263785
AI Number:	49321
Self Certification Date:	01/19/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	247326
AI Number:	49321
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	52622
Cert ID:	229652
AI Number:	49321
Self Certification Date:	01/06/2014

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	52622
Cert ID:	50248
AI Number:	49321
Self Certification Date:	01/04/2013
Signature Name/Title:	SCOTT T JOHNSON GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	52622
Cert ID:	50247
AI Number:	49321
Self Certification Date:	06/08/2012
Signature Name/Title:	SCOTT JOHNSON GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	52622
Cert ID:	50246
AI Number:	49321
Self Certification Date:	07/27/2011

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50245
AI Number:	49321
Self Certification Date:	07/27/2010
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50244
AI Number:	49321
Self Certification Date:	07/21/2009
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50243
AI Number:	49321
Self Certification Date:	07/02/2008

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50242
AI Number:	49321
Self Certification Date:	07/09/2007
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50241
AI Number:	49321
Self Certification Date:	07/21/2006
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50240
AI Number:	49321
Self Certification Date:	07/19/2005

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	GREGG STRASBURGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	52622
Cert ID:	50239
AI Number:	49321
Self Certification Date:	08/04/2004
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	52622
Cert ID:	50238
AI Number:	49321
Self Certification Date:	08/25/2003
Signature Name/Title:	GREGG STRASBURGER VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	52622
Cert ID:	50237
AI Number:	49321
Self Certification Date:	08/28/2002

7-ELEVEN 35805 (Continued) **U001280238**

Signature Name/Title:	GREGG STRASBURGER VICE PRESIDENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	52622
Cert ID:	50236
AI Number:	49321
Self Certification Date:	01/17/2001
Signature Name/Title:	GREGG STRASBURGER VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	11/01/1988
Tank Registration Date:	10/30/1989
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	128075
Facility ID:	52622
Ai Number:	49321
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	11/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

7-ELEVEN 35805 (Continued) **U001280238**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	49926
UST ID:	128075
AI Number:	49321
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

7-ELEVEN 35805 (Continued) **U001280238**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/01/1988

Install Date:	11/01/1988
Tank Registration Date:	10/30/1989
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	128076
Facility ID:	52622
Ai Number:	49321
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	11/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

7-ELEVEN 35805 (Continued) **U001280238**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	10000
UST Comprt ID:	49927
UST ID:	128076
AI Number:	49321
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N

7-ELEVEN 35805 (Continued) **U001280238**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	11/01/1988
Tank Registration Date:	10/30/1989
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	128073
Facility ID:	52622
Ai Number:	49321
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	11/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

7-ELEVEN 35805 (Continued) **U001280238**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	49924
UST ID:	128073
AI Number:	49321
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

7-ELEVEN 35805 (Continued) **U001280238**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	11/01/1988

Install Date:	11/01/1988
Tank Registration Date:	10/30/1989
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	128074
Facility ID:	52622
Ai Number:	49321
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	11/01/1988
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

7-ELEVEN 35805 (Continued) **U001280238**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	49925
UST ID:	128074
AI Number:	49321
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM

7-ELEVEN 35805 (Continued) **U001280238**

Stage 1 Installation Date: 11/01/1988

Construction Notification:

NOC ID:	4442
Facility ID:	52622
AI Number:	49321
Application Received Date:	05/21/2012
Scheduled Construction Date:	05/23/2012
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	6589
General Desc Of Prop Construct:	REPAIR STP SUMP ENTRY BOOTS & TEST. REPLACE STP FLEX CONNECTORS AND SHEAR VALVE OM #1.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	4818
UST ID:	Not reported
NOC ID:	4442
AI Number:	49321
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001443
Company Name:	UNITED PUMP SUPPLY
Representative Name:	GLENN FARMER
Mailing Address (Delivery):	17300 BELL NORTH DR
Mailing Address (Internal Delivery):	Not reported
Mailing City:	SCHERTZ
Mailing State:	TX
Mailing Zip:	78154
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	210
Phone Number:	6513882
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported

7-ELEVEN 35805 (Continued) **U001280238**

Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	4819
UST ID:	Not reported
NOC ID:	4442
AI Number:	49321
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001443
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	52622
Additional ID:	204772282002150
Princ ID:	959578622001257
AI Number:	49321
Facility Name:	7-ELEVEN 35805
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

TX Financial Assurance 2:

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	279134
AI:	49321
Mechanism Type Other:	Not reported

7-ELEVEN 35805 (Continued) **U001280238**

Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	261989
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	242013
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO

7-ELEVEN 35805 (Continued) **U001280238**

Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	224540
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	223940
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35

7-ELEVEN 35805 (Continued) **U001280238**

City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	207707
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	189087
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	173279
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

7-ELEVEN 35805 (Continued) **U001280238**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	154417
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	138083
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000

7-ELEVEN 35805 (Continued) **U001280238**

Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	118246
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	120539
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622

7-ELEVEN 35805 (Continued) **U001280238**

Finass ID:	3280
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37976
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2012
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	1235400
Coverage Amount:	2000000
Coverage Expiration Date:	12/18/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37977
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

7-ELEVEN 35805 (Continued) **U001280238**

Financial Assurance Begin Date:	11/30/2011
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	9951293
Coverage Amount:	2000000
Coverage Expiration Date:	11/30/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37978
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2010
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	9951293
Coverage Amount:	2000000
Coverage Expiration Date:	11/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37979
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2009
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	9951293
Coverage Amount:	2000000
Coverage Expiration Date:	11/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

7-ELEVEN 35805 (Continued) **U001280238**

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37980
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2008
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	9951293
Coverage Amount:	2000000
Coverage Expiration Date:	11/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37981
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/2007
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3371337
Policy Number:	9951293
Coverage Amount:	1000000
Coverage Expiration Date:	11/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 35805
Address:	13641 N IH 35
City,State,Zip:	AUSTIN, TX 78753
Region:	2
Facility ID:	52622
Finass ID:	37982
AI:	49321
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

7-ELEVEN 35805 (Continued) **U001280238**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/30/1993
Date Financial Assurance Form Rec:	10/29/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

TW3239 **FORMER TRUCK CITY DEALERSHIP** **TX LPST** **S103499913**
ESE **502 E BEN WHITE BLVD** **N/A**
1/4-1/2 **AUSTIN, TX 78704**
0.428 mi.
2261 ft. **Site 2 of 2 in cluster TW**

Actual:
669 ft.

Focus Map:
18

LPST:

Name:	FORMER TRUCK CITY DEALERSHIP
Address:	502 E BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	Not reported
LPST Id:	107201
Facility Location:	502 E BEN WHITE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/31/3000
Entered Date:	05/29/1996
Reported Date:	08/04/1993
Closure Date:	10/06/1993
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	XYZ
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE SPRINGFIELD
Responsible Party Address:	1101 E ANDERSON LN
Responsible Party City,St,Zip:	AUSTIN, TX
Responsible Party Telephone:	/-
Reported Date:	08/04/1993
Case Start Date:	10/06/1993
Reference Number:	RN103018792
Project Manager:	XYZ

3240 East 1/4-1/2 0.431 mi. 2276 ft. | **HYDE PARK TEXACO 4500 DUVAL ST AUSTIN, TX 78751** | **TX LPST TX UST TX HIST UST** | **U001249564 N/A**

Actual: 606 ft.

Focus Map: 8

LPST:

Name:	HYDE PARK TEXACO STATION
Address:	4500 DUVAL ST
City,State,Zip:	AUSTIN, TX 78727
Facility ID:	0014109
LPST Id:	102703
Facility Location:	4500 DUVAL
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/20/1992
Entered Date:	04/22/1992
Reported Date:	04/20/1992
Closure Date:	02/08/2002
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	PSJ
Responsible Party Name:	Not reported
Responsible Party Contact:	GUY OLIVER
Responsible Party Address:	PO BOX 3338
Responsible Party City,St,Zip:	AUSTIN, TX 78764
Responsible Party Telephone:	512/927-6100
Reported Date:	04/20/1992
Case Start Date:	02/08/2002
Reference Number:	RN100634963
Project Manager:	PSJ

UST:

Name:	HYDE PARK TEXACO
Address:	4500 DUVAL ST
City,State,Zip:	AUSTIN, TX 787513204
AI Number:	14109
Facility Type:	UNKNOWN
Facility Begin Date:	09/01/1987
Facility Status:	INACTIVE
Additional ID:	895306252003072
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	SCOTT NORWOOD,
Contact Organization Name:	HYDE PARK TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

HYDE PARK TEXACO (Continued) **U001249564**

Contact Telephone:	5124531932
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/17/1986
Signature Name/Title On Earliest Reg Form:	ROBERT V MORGAN,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601552862
Owner Last Name:	NORWOOD JOHN SCOTT
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	886306242003072
Additional ID:	895306252003072
AI Number:	14109
Owner Effective Begin Date:	09/01/1987
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	36346
Facility ID:	89502
Ai Number:	14109
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N

HYDE PARK TEXACO (Continued) **U001249564**

Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	150758
UST ID:	36346
AI Number:	14109
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N

HYDE PARK TEXACO (Continued) **U001249564**

CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	36345
Facility ID:	89502
Ai Number:	14109
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	08/31/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N

HYDE PARK TEXACO (Continued) **U001249564**

Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	150757
UST ID:	36345
AI Number:	14109
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N

HYDE PARK TEXACO (Continued) **U001249564**

PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	NORWOOD JOHN SCOTT
Contact Mailing Address (Delivery):	3417 ANDTREE BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78724 2501
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	89502
Additional ID:	895306252003072
Princ ID:	886306242003072
AI Number:	14109
Facility Name:	HYDE PARK TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	SCOTT NORWOOD/

HIST UST AUSTIN:

Name:	HYDE PARK TEXACO
Address:	4500 DUVAL ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0314
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX3241 **BERGSTROM 2** **TX HIST LF** **S129374123**
SE **SITE AT N END OF BASE B/W THE END OF THE RUNWAY AND BERGSTRO** **N/A**
1/4-1/2 **TRAVIS (County), TX**
0.431 mi.
2276 ft. **Site 1 of 3 in cluster TX**

Actual:
537 ft.

Focus Map:
20

HIST LF:

Name:	BERGSTROM 2
Name 2:	MILITARY
Address:	SITE AT N END OF BASE B/W THE END OF THE RUNWAY AND BERGSTROM 1
City,State,Zip:	TX
Latitude:	30.214667
Longitude:	-97.677333
Lat Deg:	30
Lat MM:	12.88
Lon DD:	97
Lon MM:	40.64
UNUM:	2582
Comments:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES. FROM BERGSTROM AFB IRP SITE PROFILE.
Inspection:	Not reported
COG Number:	12
COOR CD:	Not reported
TWC District:	Not reported
Owner Name:	MILITARY
Owner Code:	Not reported
Open Date:	1946
Close Date:	1952
Acres:	16
Yards:	0
Parties:	Not reported
Household:	Y
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Y
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	N
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Update:	Military Data
Reviewer:	Not reported
Accuracy:	Geocoded at Southwest Texas State University (SWTSU) from good location information, high confidence level
Source:	5

TX3242 **BERGSTROM 2** **TX CLI** **S103259020**
SE **SITE AT N END OF BASE B/W THE END OF THE RUNWAY AND BERGSTRO** **N/A**
1/4-1/2 **, TX**
0.431 mi.
2276 ft. **Site 2 of 3 in cluster TX**

Actual:
537 ft.

Focus Map:
20

CLI:

Name:	BERGSTROM 2
Address:	SITE AT N END OF BASE B/W THE END OF THE RUNWAY AND BERGSTROM 1
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	MILITARY
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported
Engineer:	Not reported
Source:	5
Source Code:	Not reported
Date Opened:	1946
Date Closed:	1952
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	12.88
Long Deg:	97
Long Min:	40.64
Lat/Long (deg):	30.214667 / -97.677333
Owner:	MILITARY
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	**********
Code for Landfill:	2
Parties:	Not reported
Accepts House Hold:	Yes
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported

BERGSTROM 2 (Continued) **S103259020**

Accepts Tires:	Not reported
Accepts Agriculture:	Yes
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Yes
Legal:	No
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported
Inspc Comments:	Not reported
Comments:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES. FROM BERGSTROM AFB IRP SITE PROFILE.
Update:	8
Reviewer:	Not reported
Flag:	Not reported

TX3243 **BERGSTROM 2** **TX CLI** **S119135261**
SE **NORTH END OF FORMER BERGSTROM AFB** **N/A**
1/4-1/2 **TRAVIS (County), TX**
0.431 mi.
2276 ft. **Site 3 of 3 in cluster TX**

Actual:
537 ft.

Focus Map:
20

CAPCOG LI:

Name:	BERGSTROM 2
Address:	NORTH END OF FORMER BERGSTROM AFB
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	1946
Date Close:	1952
Unum:	2582
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	12.880000000000001
Longitude Deg:	97
Longitude Min:	40.640000000000001
Lat Dd:	30.214666999999999
Long Dd:	-97.677333000000004
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	5
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported

BERGSTROM 2 (Continued) **S119135261**

Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	City of Austin
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	8
Reviewer1:	Not reported
Confidence:	GENERAL DESRCIPTION
Cog1:	12
Twc Dist:	0
Size Acres:	16
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Y
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Y
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	N
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Inspection:	Not reported
Comment:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES. FROM BERGSTROM AFB IRP SITE PROFILE.
Latitude:	30.21463333
Longitude:	-97.67735
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=327

3244 North 1/4-1/2 0.432 mi. 2280 ft. | **PATHMARK 34**
609 BASTROP HWY
AUSTIN, TX | **TX RDR** | **S127537307**
N/A

Actual: 471 ft.

Focus Map: 15

RDR:

RDR ID:	24487
Facility ID:	65215
RN:	Not reported
CN:	Not reported
Name:	PATHMARK 34
Address:	609 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/27/2017
Due Date:	5/26/2017
Tank Owner:	TEXAS ENTERPRISES
Contact Person:	PAUL PEMBERTON
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	5/23/2017
Project Manager:	Yongrui Tan
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3245 ENE 1/4-1/2 0.432 mi. 2281 ft. | **EBENEZAR BAPTIST CHURCH**
1011 SAN MARCOS ST
AUSTIN, TX 78702 | **TX LPST**
TX UST | **U003421952**
N/A

Actual: 544 ft.

Focus Map: 11

LPST:

Name:	EBENEZER BAPTIST CHURCH
Address:	1011 SAN MARCOS ST
City,State,Zip:	AUSTIN, TX 78702
Facility ID:	0062742
LPST Id:	107418
Facility Location:	1011 SAN MARCOS ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/06/1993
Entered Date:	01/18/1994
Reported Date:	11/06/1993
Closure Date:	03/28/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

Coordinators Primary:	1/2
Coordinators RPR:	BOD
Responsible Party Name:	Not reported
Responsible Party Contact:	MARVIN GRIFFIN
Responsible Party Address:	1010 E 10TH
Responsible Party City,St,Zip:	AUSTIN, TX 78702
Responsible Party Telephone:	512/478-1875
Reported Date:	11/06/1993
Case Start Date:	03/28/1995
Reference Number:	RN101494524
Project Manager:	BOD

UST:

Name:	EBENEZAR BAPTIST CHURCH
Address:	1011 SAN MARCOS ST
City,State,Zip:	AUSTIN, TX 78702
AI Number:	62742
Facility Type:	RETAIL
Facility Begin Date:	04/06/1992
Facility Status:	INACTIVE
Additional ID:	45656892002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78702
Contact Name/Title:	,
Contact Organization Name:	EBENEZAR BAPTIST CHURCH
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124781875
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/29/1992
Signature Name/Title On Earliest Reg Form:	MARVIN C GRIFFIN,
Application Received Date On Earliest Reg Form:	04/01/1992
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600782460
Owner Last Name:	EBENEZER BAPTIST CHURCH
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	35656892002053
Additional ID:	45656892002053
AI Number:	62742
Owner Effective Begin Date:	04/06/1992
State Tax ID:	32011382994
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	04/01/1992
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145227
Facility ID:	93263
Ai Number:	62742
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/04/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	2
Tank Capacity:	9999
UST Comprt ID:	139005
UST ID:	145227
AI Number:	62742
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	04/01/1992
Number of Compartments:	1
Tank Capacity:	9999
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	145228
Facility ID:	93263
Ai Number:	62742
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/04/1993
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/14/1992

Compartment Records:

Tank ID:	1
Tank Capacity:	9999
UST Comprt ID:	139006
UST ID:	145228
AI Number:	62742
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

EBENEZAR BAPTIST CHURCH (Continued) **U003421952**

Facility Billing Contacts:

Contact Organization Name:	EBENEZER BAPTIST CHURCH
Contact Mailing Address (Delivery):	1010 E 10TH ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78702 2641
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93263
Additional ID:	45656892002053
Princ ID:	35656892002053
AI Number:	62742
Facility Name:	EBENEZAR BAPTIST CHURCH
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MARVIN C GRIFFIN/

3246 WNW 1/4-1/2 0.433 mi. 2287 ft. | **PHOENIX MOTOR WORKS**
1127 W 6TH ST
AUSTIN, TX 78703 | **TX LPST** **TX UST** **TX HIST UST** | **U001829307** **N/A**

Actual: 484 ft.

Focus Map: 11

LPST:

Name:	PHOENIX MOTOR WORKS
Address:	1127 W 6TH ST
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0065501
LPST Id:	102019
Facility Location:	1127 W 6TH ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/17/1992
Entered Date:	03/31/1992
Reported Date:	02/17/1992
Closure Date:	04/01/1994
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BOB FAIR
Responsible Party Address:	501 W 5TH ST
Responsible Party City,St,Zip:	AUSTIN, TX 78701
Responsible Party Telephone:	512/476-4761
Reported Date:	02/17/1992
Case Start Date:	04/01/1994
Reference Number:	RN100706399
Project Manager:	HWELCH

PHOENIX MOTOR WORKS (Continued) **U001829307**

UST:

Name:	PHOENIX MOTOR WORKS
Address:	1127 W 6TH ST
City,State,Zip:	AUSTIN, TX 787035338
AI Number:	65501
Facility Type:	FLEET REFUELING
Facility Begin Date:	03/21/1994
Facility Status:	INACTIVE
Additional ID:	862160472002118
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78703
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/10/1994
Signature Name/Title On Earliest Reg Form:	DOUG WEAVER,PRES/EXCELL ENVIRON
Application Received Date On Earliest Reg Form:	03/16/1994
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600781876
Owner Last Name:	COVERT BUICK INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	916637702002053
Additional ID:	862160472002118
AI Number:	65501
Owner Effective Begin Date:	03/21/1994
State Tax ID:	17419827419

PHOENIX MOTOR WORKS (Continued) **U001829307**

Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	08/31/1987
Tank Registration Date:	03/16/1994
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149706
Facility ID:	42962
Ai Number:	65501
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/25/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N

PHOENIX MOTOR WORKS (Continued) **U001829307**

PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	14104
UST ID:	149706
AI Number:	65501
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25511
Cert ID:	69659

PHOENIX MOTOR WORKS (Continued) **U001829307**

UST Comprt ID:	217031
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	284806
UST Comprt ID:	821898
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	234490
UST Comprt ID:	673042
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69667
UST Comprt ID:	217023
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69666
UST Comprt ID:	217024
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69665
UST Comprt ID:	217025
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69664
UST Comprt ID:	217026
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69663
UST Comprt ID:	217027

PHOENIX MOTOR WORKS (Continued) **U001829307**

UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69662
UST Comprt ID:	217028
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69661
UST Comprt ID:	217029
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69660
UST Comprt ID:	217030
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	301990
UST Comprt ID:	873309
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69658
UST Comprt ID:	217032
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69657
UST Comprt ID:	217035
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69656
UST Comprt ID:	217034
UST ID:	80338

PHOENIX MOTOR WORKS (Continued) **U001829307**

AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	335487
UST Comprt ID:	973413
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	319032
UST Comprt ID:	924024
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	369825
UST Comprt ID:	1076892
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	352707
UST Comprt ID:	1025394
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	268100
UST Comprt ID:	772259
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	251846
UST Comprt ID:	724089
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69655
UST Comprt ID:	217033
UST ID:	80338
AI Number:	65501

PHOENIX MOTOR WORKS (Continued) **U001829307**

Tank ID:	1
Compartment ID:	A
Install Date:	08/31/1987
Tank Registration Date:	03/16/1994
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	149707
Facility ID:	42962
Ai Number:	65501
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/25/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

PHOENIX MOTOR WORKS (Continued) **U001829307**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	550
UST Comprt ID:	14105
UST ID:	149707
AI Number:	65501
Compartment ID:	A
Substance Stored1:	UNKNOWN
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	25511
Cert ID:	69659
UST Comprt ID:	217031

PHOENIX MOTOR WORKS (Continued) **U001829307**

UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	284806
UST Comprt ID:	821898
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	234490
UST Comprt ID:	673042
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69667
UST Comprt ID:	217023
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69666
UST Comprt ID:	217024
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69665
UST Comprt ID:	217025
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69664
UST Comprt ID:	217026
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69663
UST Comprt ID:	217027
UST ID:	80338

PHOENIX MOTOR WORKS (Continued) **U001829307**

AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69662
UST Comprt ID:	217028
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69661
UST Comprt ID:	217029
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69660
UST Comprt ID:	217030
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	301990
UST Comprt ID:	873309
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69658
UST Comprt ID:	217032
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69657
UST Comprt ID:	217035
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69656
UST Comprt ID:	217034
UST ID:	80338
AI Number:	65501

PHOENIX MOTOR WORKS (Continued) **U001829307**

Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	335487
UST Comprt ID:	973413
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	319032
UST Comprt ID:	924024
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	369825
UST Comprt ID:	1076892
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	352707
UST Comprt ID:	1025394
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	268100
UST Comprt ID:	772259
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	251846
UST Comprt ID:	724089
UST ID:	80338
AI Number:	65501
Tank ID:	1
Compartment ID:	A
Self Cert ID:	25511
Cert ID:	69655
UST Comprt ID:	217033
UST ID:	80338
AI Number:	65501
Tank ID:	1

PHOENIX MOTOR WORKS (Continued) **U001829307**

Compartment ID: A

Facility Billing Contacts:

Contact Organization Name:	COVERT BUICK INC
Contact Mailing Address (Delivery):	11750A RESEARCH BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78759 2446
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	42962
Additional ID:	862160472002118
Princ ID:	916637702002053
AI Number:	65501
Facility Name:	PHOENIX MOTOR WORKS
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	PAUL MATHEWS/

HIST UST AUSTIN:

Name:	FORMER COVERT BUICK
Address:	1127 W. 6TH ST.
City,State,Zip:	AUSTIN, TX
Id UST:	C0712
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TY3247 **TEXACO RETAIL FAC** **TX RDR** **S127530927**
ESE **800 E WILLIAM CANNON** **N/A**
1/4-1/2 **AUSTIN, TX**
0.434 mi.
2290 ft. **Site 1 of 2 in cluster TY**

Actual:
664 ft.

Focus Map:
17

RDR:

RDR ID:	12533
Facility ID:	34931
RN:	Not reported
CN:	Not reported
Name:	TEXACO RETAIL FAC
Address:	800 E WILLIAM CANNON
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/7/2003
Due Date:	9/5/2003
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	SCOTT BURKEY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	2/2/2004
Project Manager:	Trudy Hasan
Team:	#N/A
New LPST Number:	Not reported

TEXACO RETAIL FAC (Continued) **S127530927**

Pre-Existing LPST Number:	96325
Comments:	6A; NO LEAKER.
Review Coordinator:	TSH/TSR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	2/2/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

TY3248 **TOWN FOOD MART** **TX LPST** **U001267924**
ESE **800 E WILLIAM CANNON DR** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78745** **TX HIST UST**
0.434 mi. **TX ASBESTOS**
2290 ft. **Site 2 of 2 in cluster TY** **TX Financial Assurance**

Actual:
664 ft.

Focus Map:
17

LPST:

Name:	SHOPPERS MART 23
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0034931
LPST Id:	096235
Facility Location:	800 E WILLIAM CANNON
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/16/1990
Entered Date:	07/24/1990
Reported Date:	07/16/1990
Closure Date:	11/13/1990
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2/5/2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	MICHAEL HAWTHORNE
Responsible Party Address:	PO BOX 152045
Responsible Party City,St,Zip:	IRVING, TX 75015 2045
Responsible Party Telephone:	214/650-0200
Reported Date:	07/16/1990
Case Start Date:	11/13/1990
Reference Number:	RN102321288
Project Manager:	HWELCH

UST:

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 787455738
AI Number:	34931
Facility Type:	RETAIL
Facility Begin Date:	12/10/1986
Facility Status:	ACTIVE
Additional ID:	520244842002208
Facility Exempt Status:	N

TOWN FOOD MART (Continued) **U001267924**

Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	PAUL PEMBERTON,DIR OF MAINT
Contact Organization Name:	TOWN FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123852020
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/06/2022
Signature Name/Title On Earliest Reg Form:	PAUL PEMBERTON,DIRECTOR
Application Received Date On Earliest Reg Form:	09/21/2022
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	365520692002075
Additional ID:	520244842002208
Ai Number:	34931
Operator CN:	CN600918452
Operator Name:	TEXAS ENTERPRISES INC
Operator Effective Begin Date:	05/14/2012
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	BROCK ISBELL/SITE REP
Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	2702 INDUSTRIAL BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ABILENE TX 79605-7213
Contact Phone Country Code:	1
Contact Phone Area Code:	325
Contact Phone Number:	6950150
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600918452
Owner Last Name:	TEXAS ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6156

TOWN FOOD MART (Continued) **U001267924**

Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6156
Contact Phone Number/Ext:	1 512 3852020/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	365520692002075
Additional ID:	520244842002208
AI Number:	34931
Owner Effective Begin Date:	05/14/2012
State Tax ID:	17418588749
Contact Role:	OWNOPRCON
Contact Name/Title:	PAUL PEMBERTON/
Contact Organization Name:	TEXAS ENTERPRISES INC

Self Certification:

Self Cert ID:	79666
Cert ID:	376831
AI Number:	34931
Self Certification Date:	09/06/2022
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	358224
AI Number:	34931
Self Certification Date:	08/02/2021
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	343139
AI Number:	34931
Self Certification Date:	08/28/2020
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	324439
AI Number:	34931
Self Certification Date:	07/30/2019
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	308580
AI Number:	34931
Self Certification Date:	08/21/2018
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMPLIANCE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	292041
AI Number:	34931
Self Certification Date:	08/23/2017
Signature Name/Title:	PAUL PEMBERTON DIR OF ENVIRONMENTAL COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	274761
AI Number:	34931
Self Certification Date:	08/08/2016
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	259990
AI Number:	34931
Self Certification Date:	08/27/2015
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	242155
AI Number:	34931
Self Certification Date:	07/24/2014
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	224732
AI Number:	34931
Self Certification Date:	08/15/2013
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79666
Cert ID:	124009
AI Number:	34931
Self Certification Date:	06/29/2012
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	124008
AI Number:	34931
Self Certification Date:	05/31/2012
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124007
AI Number:	34931
Self Certification Date:	06/08/2011
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124006
AI Number:	34931
Self Certification Date:	07/09/2010
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	124005
AI Number:	34931
Self Certification Date:	06/18/2009
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124004
AI Number:	34931
Self Certification Date:	05/16/2008
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124003
AI Number:	34931
Self Certification Date:	06/04/2007
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	124002
AI Number:	34931
Self Certification Date:	07/01/2006
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124001
AI Number:	34931
Self Certification Date:	06/30/2005
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	124000
AI Number:	34931
Self Certification Date:	06/24/2004
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	123999
AI Number:	34931
Self Certification Date:	07/01/2003
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	123998
AI Number:	34931
Self Certification Date:	03/04/2003
Signature Name/Title:	SCOTT HAGGERTON HSE COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	79666
Cert ID:	123997
AI Number:	34931
Self Certification Date:	03/01/2002
Signature Name/Title:	GEORGE CARTWRIGHT SHE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Self Cert ID:	79666
Cert ID:	123996
AI Number:	34931
Self Certification Date:	11/27/2000
Signature Name/Title:	R I RENEAU SH & E COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92349
Facility ID:	79666
Ai Number:	34931
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N

TOWN FOOD MART (Continued) **U001267924**

Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	6000
UST Comprt ID:	123203
UST ID:	92349
AI Number:	34931
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y

TOWN FOOD MART (Continued) **U001267924**

SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92350
Facility ID:	79666
Ai Number:	34931
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N

TOWN FOOD MART (Continued) **U001267924**

TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	123204
UST ID:	92350
AI Number:	34931
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N

TOWN FOOD MART (Continued) **U001267924**

Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported
Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92351
Facility ID:	79666
Ai Number:	34931
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N

TOWN FOOD MART (Continued) **U001267924**

PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	123205
UST ID:	92351
AI Number:	34931
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000

TOWN FOOD MART (Continued) **U001267924**

Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	92352
Facility ID:	79666
Ai Number:	34931
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y

TOWN FOOD MART (Continued) **U001267924**

Installation Signature Date:	07/10/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	123206
UST ID:	92352
AI Number:	34931
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	39844
Facility ID:	79666
AI Number:	34931
Application Received Date:	04/28/2022
Scheduled Construction Date:	04/26/2022
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N

TOWN FOOD MART (Continued) **U001267924**

UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	04/28/2022
Signature Date On Form:	04/28/2022
Signature Name On Form:	BREANNA HALL
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	TEXAS ENTERPRISES INC
Owner CN At Time Of Construction:	CN600918452
Owner AR At Time Of Construction:	18379
General Desc Of Prop Construct:	Not reported

NOC ID:	12246
Facility ID:	79666
AI Number:	34931
Application Received Date:	03/22/2001
Scheduled Construction Date:	03/26/2001
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M10322006
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	04/28/2022
Signature Date On Form:	04/28/2022
Signature Name On Form:	BREANNA HALL
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	LEGAL AUTH REP OWNER
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22907
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	13042
UST ID:	Not reported
NOC ID:	12246
AI Number:	34931
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001306
Company Name:	Not reported
Representative Name:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	95089
UST ID:	Not reported
NOC ID:	39844
AI Number:	34931
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	JF PETROLEUM GROUP
Representative Name:	Not reported
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	95088
UST ID:	Not reported
NOC ID:	39844
AI Number:	34931
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	Not reported
Representative Name:	BREANNA HALL
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512

TOWN FOOD MART (Continued) **U001267924**

Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79666
Additional ID:	520244842002208
Princ ID:	365520692002075
AI Number:	34931
Facility Name:	TOWN FOOD MART
AR Number:	18379
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PAUL PEMBERTON/

HIST UST AUSTIN:

Name:	K & Z TOWN FOOD MART #23
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX
Id UST:	303
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	01/31/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.7
Reg:	07
Init:	EJ
Seq:	01

TOWN FOOD MART (Continued) **U001267924**

Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/05/2013
Date Routed by Supervisor:	02/06/2013
Date Routed to PSQA:	02/07/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Descriptio:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/20/2014
Reason for Inspection:	Routine

TOWN FOOD MART (Continued) **U001267924**

Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.7
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/24/2014
Date Routed by Supervisor:	02/25/2014
Date Routed to PSQA:	02/26/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	274634
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2022
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000028792
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	254979
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2021
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000019174
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

TOWN FOOD MART (Continued) **U001267924**

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	237529
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2020
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000010223
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	218116
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2019
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-005000860
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	202038
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

TOWN FOOD MART (Continued) **U001267924**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2018
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	185165
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2017
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	167104
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2016
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported

TOWN FOOD MART (Continued) **U001267924**

Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	151560
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2015
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	133274
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2014
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745

TOWN FOOD MART (Continued) **U001267924**

Region:	2
Facility ID:	79666
Finass ID:	114323
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2013
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	8694
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2012
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 0 0
Policy Number:	9989929
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/14/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	65257
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

TOWN FOOD MART (Continued) **U001267924**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2011
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	65258
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2010
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	65259
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2009
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2010

TOWN FOOD MART (Continued) **U001267924**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	65260
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2008
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	TOWN FOOD MART
Address:	800 E WILLIAM CANNON DR
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	79666
Finass ID:	65261
AI:	34931
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1994
Date Financial Assurance Form Rec:	09/21/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

3249 WNW 1/4-1/2 0.434 mi. 2290 ft. | **USPS S AUSTIN STATION**
1806 S 5TH ST
AUSTIN, TX 78704 | **TX LPST** | **S105049914**
N/A

Actual: 532 ft.

Focus Map: 14

LPST:

Name:	USPS S AUSTIN STATION
Address:	1806 S 5TH ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0025438
LPST Id:	098418
Facility Location:	S 5TH ST @ ST MARYS ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	04/01/1991
Entered Date:	04/02/1991
Reported Date:	04/01/1991
Closure Date:	11/30/1994
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	LAS
Responsible Party Name:	Not reported
Responsible Party Contact:	MIKE GOODWIN
Responsible Party Address:	8055 E TUFTS AVE STE 400
Responsible Party City,St,Zip:	DENVER, CO 80237 2881
Responsible Party Telephone:	602/223-3543
Reported Date:	04/01/1991
Case Start Date:	11/30/1994
Reference Number:	RN101696771
Project Manager:	LAS

TZ3250 WNW 1/4-1/2 0.434 mi. 2292 ft. | **ANDYS FOOD MART**
611 W STASSNEY LN
AUSTIN, TX 78745
Site 1 of 2 in cluster TZ | **TX RDR**
TX CENTRAL REGISTRY | **S126586325**
N/A

Actual: 640 ft.

Focus Map: 17

RDR:

RDR ID:	16594
Facility ID:	10999
RN:	Not reported
CN:	Not reported
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/8/2007
Due Date:	12/7/2007
Tank Owner:	TWIN OAKS ASSOCIATES
Contact Person:	MR SCOTT JUNG
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	10/29/2007
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	117469

ANDYS FOOD MART (Continued) **S126586325**

Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED AN LPST #? MONIT ANNL, APAR;LAD SENT 11/01/07
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN600778591
Customer Name:	TWIN OAKS ASSOCIATES
Customer Legal Name:	Twin Oaks Associates
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1990
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN601349418
Customer Name:	DHUKKA MEHDI MOHAMMAD
Customer Legal Name:	Dhukka Mehdi Mohammad
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/10/1996
Affiliation End Date:	3/18/2003
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN601561426
Customer Name:	DHUKKA, MEHDI MOHAMMAD

ANDYS FOOD MART (Continued) **S126586325**

Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	9/10/1996
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN600134456
Customer Name:	CIRCLE K STORES INC
Customer Legal Name:	Circle K Stores Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1990
Affiliation End Date:	8/31/1990
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN600778591
Customer Name:	TWIN OAKS ASSOCIATES
Customer Legal Name:	Twin Oaks Associates
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/1/1990
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN601349418
Customer Name:	DHUKKA MEHDI MOHAMMAD
Customer Legal Name:	Dhukka Mehdi Mohammad
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/10/1996

ANDYS FOOD MART (Continued) **S126586325**

Affiliation End Date:	3/18/2003
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN601561426
Customer Name:	DHUKKA, MEHDI MOHAMMAD
Customer Legal Name:	Not reported
Customer Ownership Type:	INDIVIDUAL OWNER TYPE
Affiliation Begin Date:	9/10/1996
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

Regulated Entity Number:	RN102651957
Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-3148
Status:	ACTIVE
Status Date:	6/24/2002
Customer Number:	CN600134456
Customer Name:	CIRCLE K STORES INC
Customer Legal Name:	Circle K Stores Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1990
Affiliation End Date:	8/31/1990
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

TZ3251 **ANDYS FOOD MART** **TX LPST** **U003373828**
WNW **611 W STASSNEY LN** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78745** **TX HIST UST**
0.434 mi. **TX Financial Assurance**
2292 ft. **Site 2 of 2 in cluster TZ** **TX GCC**

Actual:
640 ft.

Focus Map:
17

LPST:

Name:	FORMER ANDYS FOOD MART
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0010999
LPST Id:	117469
Facility Location:	611 W STASSNEY LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/04/2005

ANDYS FOOD MART (Continued) **U003373828**

Entered Date:	10/29/2007
Reported Date:	11/10/2005
Closure Date:	03/31/2010
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT 500F
Program:	1P - PRIVATIZATION CONTRACTOR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater or storm water runoff is affected and discharges within 500 feet of the known extent of contamination to a surface water body used for human drinking water, contact recreation, habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1P
Coordinators RPR:	TH2
Responsible Party Name:	Not reported
Responsible Party Contact:	SCOTT JUNG
Responsible Party Address:	PO BOX 41149
Responsible Party City,St,Zip:	AUSTIN, TX 78704
Responsible Party Telephone:	512/442-6779
Reported Date:	11/10/2005
Case Start Date:	03/31/2010
Reference Number:	RN102651957
Project Manager:	THASAN

UST:

Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX 787453148
AI Number:	10999
Facility Type:	RETAIL
Facility Begin Date:	08/31/1990
Facility Status:	INACTIVE
Additional ID:	543475352002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	MEHDI DHUKKA,
Contact Organization Name:	ANDYS FOOD MART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124443636
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/03/1986
Signature Name/Title On Earliest Reg Form:	DON ESPERSON,GAS FAC MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

ANDYS FOOD MART (Continued) **U003373828**

Operator:

Princ ID:	243484362003077
Additional ID:	543475352002175
Ai Number:	10999
Operator CN:	CN601561426
Operator Name:	MEHDI MOHAMMAD DHUKKA
Operator Effective Begin Date:	09/10/1996
Operator Type:	IN
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600778591
Owner Last Name:	TWIN OAKS ASSOCIATES
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	752542972002053
Additional ID:	543475352002175
AI Number:	10999
Owner Effective Begin Date:	09/01/1990
State Tax ID:	17422145940
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	93067
Cert ID:	148809
AI Number:	10999
Self Certification Date:	07/23/2004

ANDYS FOOD MART (Continued) **U003373828**

Signature Name/Title:	MEHDI MOHAMMAD DHUKKA
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93067
Cert ID:	148808
AI Number:	10999
Self Certification Date:	08/09/2003
Signature Name/Title:	MOHAMMAD MEHDI DHUKKA OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93067
Cert ID:	148807
AI Number:	10999
Self Certification Date:	07/31/2002
Signature Name/Title:	MEHDI MOHAMMAD DHUKKA FAC BUS OWNER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93067
Cert ID:	148806
AI Number:	10999
Self Certification Date:	08/03/2001

ANDYS FOOD MART (Continued) **U003373828**

Signature Name/Title:	MEHDI MOHAMMAD DHUKKA
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	06/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	28926
Facility ID:	93067
Ai Number:	10999
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

ANDYS FOOD MART (Continued) **U003373828**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	151198
UST ID:	28926
AI Number:	10999
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y

ANDYS FOOD MART (Continued) **U003373828**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	06/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	28925
Facility ID:	93067
Ai Number:	10999
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	09/30/2005
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y

ANDYS FOOD MART (Continued) **U003373828**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	08/27/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	151197
UST ID:	28925
AI Number:	10999
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	Y
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

ANDYS FOOD MART (Continued) **U003373828**

Construction Notification:

NOC ID:	14713
Facility ID:	93067
AI Number:	10999
Application Received Date:	07/22/2005
Scheduled Construction Date:	09/20/2005
UST Improvement:	N
UST Installation:	N
UST Removal:	Y
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M50722004
Waiver Flag:	N
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	37879

General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	15785
UST ID:	Not reported
NOC ID:	14713
AI Number:	10999
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001073
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

ANDYS FOOD MART (Continued) **U003373828**

Facility Billing Contacts:

Contact Organization Name:	TWIN OAKS ASSOCIATES
Contact Mailing Address (Delivery):	PO BOX 41149
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 0020
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	93067
Additional ID:	543475352002175
Princ ID:	752542972002053
AI Number:	10999
Facility Name:	ANDYS FOOD MART
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	JOE C JUNG/

HIST UST AUSTIN:

Name:	ANDY'S FOOD MART
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Id UST:	643
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	ANDYS FOOD MART
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX 78745
Region:	2
Facility ID:	93067
Finass ID:	74182
AI:	10999
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

ANDYS FOOD MART (Continued) **U003373828**

GCC:

Name:	TWIN OAKS ASSOCIATES
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	Not reported
File Number:	117469
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	10/29/2007
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	TWIN OAKS ASSOCIATES
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	*
File Number:	117469
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	10/29/2007
Enforcement Status - Level Of Agency Response:	2A - Staff Action - an information request of the entity
Enforcement Status - Site Activity Status:	2A -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

Name:	TWIN OAKS ASSOCIATES
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	Not reported
File Number:	117469
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	10/29/2007
Enforcement Status - Level Of Agency Response:	2 - Staff Action
Enforcement Status - Site Activity Status:	6 -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported

ANDYS FOOD MART (Continued) **U003373828**

Location:	Not reported
Data Quality 2:	Not reported
Name:	TWIN OAKS ASSOCIATES
Address:	611 W STASSNEY LN
City,State,Zip:	AUSTIN, TX
Division:	RMD/PST
New Cases:	Not reported
File Number:	117469
Contamination Description:	GASOLINE
Date Of Earliest Known Contamination Confirmation:	10/29/2007
Enforcement Status - Level Of Agency Response:	2A - Staff Action - an information request of the entity
Enforcement Status - Site Activity Status:	2A -
Data Quality 1:	E,Q
Section 5236:	Not reported
Type:	GROUNDWATER CONTAMINATION CASE DESCRIPTION BY COUNTY TEXAS COMMISSION ON ENVIRONMENTAL QUALITY
Agency:	Not reported
Section:	Not reported
Year Deleted:	Not reported
Location:	Not reported
Data Quality 2:	Not reported

UA3252 **7 ELEVEN 26353** **TX RDR** **S127535729**
WNW **601 W BEN WHITE BLVD** **N/A**
1/4-1/2 **AUSTIN, TX**
0.436 mi.
2303 ft. **Site 1 of 2 in cluster UA**

Actual:
681 ft.

Focus Map:
13

RDR:

RDR ID:	18842
Facility ID:	55616
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/16/2010
Due Date:	6/15/2010
Tank Owner:	7 ELEVEN INC
Contact Person:	KEN HILLIARD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	6/18/2010
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	100227
Comments:	FSC 12/1/2010
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	6/18/2010
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UA3253 **7-ELEVEN 26353** **TX LPST** **U001285840**
WNW **601 W BEN WHITE BLVD** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78704** **TX HIST UST**
0.436 mi. **TX ASBESTOS**
2303 ft. **Site 2 of 2 in cluster UA** **TX Financial Assurance**

Actual:
681 ft.

Focus Map:
13

LPST:

Name:	7 11 STORE 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0055616
LPST Id:	100227
Facility Location:	W BEN WHITE BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	09/17/1991
Entered Date:	10/04/1991
Reported Date:	09/17/1991
Closure Date:	02/14/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P/1/1P/1/2
Coordinators RPR:	RWD
Responsible Party Name:	Not reported
Responsible Party Contact:	JANE LOMAS
Responsible Party Address:	1201 BELTLINE RD
Responsible Party City,St,Zip:	COPPELL, TX 75019
Responsible Party Telephone:	817/341-8314
Reported Date:	09/17/1991
Case Start Date:	02/14/2001
Reference Number:	RN102041019
Project Manager:	RWD

UST:

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 787047031
AI Number:	55616
Facility Type:	RETAIL
Facility Begin Date:	08/28/1990
Facility Status:	ACTIVE
Additional ID:	923773572002117
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	08/23/1990
Signature Name/Title On Earliest Reg Form:	MIKE RYAN,DEVELOPMENT MGR
Application Received Date On Earliest Reg Form:	08/24/1990
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	923773572002117
Ai Number:	55616
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	08/28/1990
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257
Additional ID:	923773572002117
AI Number:	55616

7-ELEVEN 26353 (Continued) **U001285840**

Owner Effective Begin Date:	08/28/1990
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	46534
Cert ID:	382032
AI Number:	55616
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	364715
AI Number:	55616
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	348344
AI Number:	55616
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	331202
AI Number:	55616
Self Certification Date:	01/10/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	314591
AI Number:	55616
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	296505
AI Number:	55616
Self Certification Date:	12/28/2017
Signature Name/Title:	Raymond Mcniece Env. Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	280773
AI Number:	55616
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	263430
AI Number:	55616
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	247222
AI Number:	55616
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	229723
AI Number:	55616
Self Certification Date:	01/06/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46534
Cert ID:	28827
AI Number:	55616
Self Certification Date:	12/19/2012
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28826
AI Number:	55616
Self Certification Date:	12/18/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28825
AI Number:	55616
Self Certification Date:	01/05/2011
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28824
AI Number:	55616
Self Certification Date:	01/07/2010
Signature Name/Title:	SCOTT T JOHNSON REGION GAS MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28823
AI Number:	55616
Self Certification Date:	01/05/2009
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2010

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46534
Cert ID:	28822
AI Number:	55616
Self Certification Date:	12/18/2007
Signature Name/Title:	SHANE PARTRIDGE GAS COMPLIANCE MGR.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46534
Cert ID:	28821
AI Number:	55616
Self Certification Date:	11/20/2006
Signature Name/Title:	SHANE PARTRIDGE GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46534
Cert ID:	28820
AI Number:	55616
Self Certification Date:	12/08/2005
Signature Name/Title:	RON FULENCHEK GAS & ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2007

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28819
AI Number:	55616
Self Certification Date:	12/10/2004
Signature Name/Title:	RON FULENCHEK ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28818
AI Number:	55616
Self Certification Date:	11/03/2003
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28817
AI Number:	55616
Self Certification Date:	11/14/2002
Signature Name/Title:	WILLO A SMITH
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2004

7-ELEVEN 26353 (Continued) **U001285840**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28816
AI Number:	55616
Self Certification Date:	11/28/2001
Signature Name/Title:	WILLO A SMITH ENVIRONMENTAL MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46534
Cert ID:	28815
AI Number:	55616
Self Certification Date:	01/10/2001
Signature Name/Title:	WILLO A SMITH ENV MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1987
Tank Registration Date:	08/24/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	135158
Facility ID:	46534
Ai Number:	55616
Tank Id:	3

7-ELEVEN 26353 (Continued) **U001285840**

Tank Status (Current):	IN USE
Tank Status Date:	01/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/10/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	34694
UST ID:	135158
AI Number:	55616

7-ELEVEN 26353 (Continued) **U001285840**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1987
Tank Registration Date:	08/24/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	135159
Facility ID:	46534
Ai Number:	55616
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

7-ELEVEN 26353 (Continued) **U001285840**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/10/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	34695
UST ID:	135159
AI Number:	55616
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y

7-ELEVEN 26353 (Continued) **U001285840**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1987
Tank Registration Date:	08/24/1990
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	135157
Facility ID:	46534
Ai Number:	55616
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1987
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

7-ELEVEN 26353 (Continued) **U001285840**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/10/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	34693
UST ID:	135157
AI Number:	55616
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

7-ELEVEN 26353 (Continued) **U001285840**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	39650
Facility ID:	46534
AI Number:	55616
Application Received Date:	03/18/2022
Scheduled Construction Date:	03/21/2022
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Y
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971,3971
General Desc Of Prop Construct:	Not reported

NOC ID:	2968
Facility ID:	46534
AI Number:	55616
Application Received Date:	01/20/2010
Scheduled Construction Date:	01/25/2010

7-ELEVEN 26353 (Continued) **U001285840**

UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	REVISION OF PREVIOUSLY SUBMITTED CONSTRUCTION NOTIFICATION: REMOVE AND REPLACE A LL TANK TOP EQUIPMENT AND PIPING.VERBAL WAIVER GIVEN BY STELLA ORTEGON REGION 11.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	3349
UST ID:	Not reported
NOC ID:	2968
AI Number:	55616
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	SHAW ENVIRONMENTAL
Representative Name:	JENNIFER DARI
Mailing Address (Delivery):	6330 COMMERCE ST
Mailing Address (Internal Delivery):	STE 190
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	214
Phone Number:	2777848
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	94535
UST ID:	Not reported
NOC ID:	39650
AI Number:	55616
Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	AMELIA.BEARD@JFPETROGROUP.COM

Cont/Cons/Installer ID:	94536
UST ID:	Not reported
NOC ID:	39650
AI Number:	55616
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES INC
Representative Name:	NATE LAWSON
Mailing Address (Delivery):	1001 SPINKS RD STE 220
Mailing Address (Internal Delivery):	Not reported
Mailing City:	FLOWER MOUND
Mailing State:	TX
Mailing Zip:	75028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	972
Fax Number:	9290723
Email Address:	AMELIA.BEARD@JFPETROGROUP.COM

Cont/Cons/Installer ID:	3348
UST ID:	Not reported
NOC ID:	2968
AI Number:	55616
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001100
Company Name:	MCCON BUILDING AND PETROLEUM SERVICES
Representative Name:	BOBBY STOVALL
Mailing Address (Delivery):	8426 STERLING ST
Mailing Address (Internal Delivery):	Not reported
Mailing City:	IRVING
Mailing State:	TX
Mailing Zip:	75063
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Phone Number Country Code:	1
Phone Number Area Code:	972
Phone Number:	9290646
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	3350
UST ID:	Not reported
NOC ID:	2968
AI Number:	55616
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001100
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	46534
Additional ID:	923773572002117
Princ ID:	959578622001257
AI Number:	55616
Facility Name:	7-ELEVEN 26353
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/

HIST UST AUSTIN:

Name:	SEVEN ELEVEN #26353
Address:	601 W BEN WHITE BLVD

7-ELEVEN 26353 (Continued) **U001285840**

City,State,Zip:	AUSTIN, TX
Id UST:	2045
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/14/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/19/2013
Date Routed by Supervisor:	02/19/2013
Date Routed to PSQA:	02/22/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Name:	7-ELEVEN
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/13/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/17/2014
Date Routed by Supervisor:	03/18/2014
Date Routed to PSQA:	03/19/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	279157
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes

7-ELEVEN 26353 (Continued) **U001285840**

Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	262013
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	242036
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	224563
AI:	55616

7-ELEVEN 26353 (Continued) **U001285840**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	223963
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	207736
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	Not reported

7-ELEVEN 26353 (Continued) **U001285840**

Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	189103
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	172731
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353

7-ELEVEN 26353 (Continued) **U001285840**

Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	154215
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	138107
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	118214
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000

7-ELEVEN 26353 (Continued) **U001285840**

Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	120470
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	2441
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/17/2012
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401

7-ELEVEN 26353 (Continued) **U001285840**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	28585
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2011
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A006
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	28586
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2010
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A005
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2

7-ELEVEN 26353 (Continued) **U001285840**

Facility ID:	46534
Finass ID:	28587
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 215 6401000
Policy Number:	UST-G2379486A004
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	28588
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 003
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	28589
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

7-ELEVEN 26353 (Continued) **U001285840**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2007
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	ILLINOIS UNION INS CO
Issuer Phone:	1 214 8611277
Policy Number:	UST G2379486A 002
Coverage Amount:	2000000
Coverage Expiration Date:	04/30/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN 26353
Address:	601 W BEN WHITE BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46534
Finass ID:	28590
AI:	55616
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	Not reported
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

UB3254 **908 E. 11TH ST (11TH STREET 900 BLK)** **US BROWNFIELDS FINDS** **1016347359**
NE **908 E. 11TH ST** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.438 mi.
2312 ft. **Site 1 of 9 in cluster UB**

Actual:
515 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	908 E. 11TH ST (11TH STREET 900 BLK)
Address:	908 E. 11TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197219, 02080616120000
Parcel size:	0.12
Latitude:	30.270025
Longitude:	-97.730983
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 908 E. 11th St (900 BLK), 3/28/07) Former Use: Several properties are combined in

908 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347359**

	this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46681
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/4/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported

908 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347359**

Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	429
Below Poverty Percent:	17.76
Meidan Income:	7178
Meidan Income Number:	661
Meidan Income Percent:	27.37
Vacant Housing Number:	194
Vacant Housing Percent:	14.71
Unemployed Number:	94
Unemployed Percent:	3.89
Name:	908 E. 11TH ST (11TH STREET 900 BLK)
Address:	908 E. 11TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197219, 02080616120000
Parcel size:	0.12
Latitude:	30.270025
Longitude:	-97.730983
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 908 E. 11th St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46681
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y

908 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347359**

Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	429
Below Poverty Percent:	17.76
Meidan Income:	7178
Meidan Income Number:	661
Meidan Income Percent:	27.37
Vacant Housing Number:	194
Vacant Housing Percent:	14.71
Unemployed Number:	94
Unemployed Percent:	3.89

FINDS:
Registry ID: 110038721050

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UB3255 **912 E. 11TH STREET** **US BROWNFIELDS** **1010157579**
NE **912 E. 11TH STREET** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.444 mi.
2345 ft. **Site 2 of 9 in cluster UB**

Actual:
517 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	912 E. 11TH STREET
Address:	912 E. 11TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197218, 0208061611
Parcel size:	0.12
Latitude:	30.27
Longitude:	-97.7309
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The 912 E. 11th Street property is a dedicated historical site purchased by the City of Austin in Septemer 2004. The 916 site is vacant. Both sites are part of the 11th Street 11-1 block targeted for redevelopment mixed use projects in the future. (PPF- 912 E. 11th Street, 3/28/2007) Former Use: One of two properties located in a down-gradient location from the former Ritter Filling Station that impacted the site and a former dry cleaning facility.
Datum:	North American Datum of 1983
Acres Property ID:	40921
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6271.57
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	11/1/2006
Ownership Entity:	Government
Completion Date:	12/28/2006
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported

912 E. 11TH STREET (Continued) **1010157579**

IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals Petroleum Products VOCs
Contaminant Cleanup:	Not reported
Media Affected:	Ground Water Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	One of two properties located in a down-gradient location from the former Ritter Filling Station that impacted the site and a former dry cleaning facility.
Below Poverty Number:	428
Below Poverty Percent:	17.76
Meidan Income:	7163
Meidan Income Number:	660
Meidan Income Percent:	27.39
Vacant Housing Number:	193
Vacant Housing Percent:	14.67
Unemployed Number:	94
Unemployed Percent:	3.9
Name:	912 E. 11TH STREET
Address:	912 E. 11TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197218, 0208061611
Parcel size:	0.12
Latitude:	30.27
Longitude:	-97.7309
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	The 912 E. 11th Street property is a dedicated historical site purchased by the City of Austin in Septemer 2004. The 916 site is vacant. Both sites are part of the 11th Street 11-1 block targeted for redevelopment mixed use projects in the future. (PPF- 912 E. 11th Street, 3/28/2007) Former Use: One of two properties located in a down-gradient location from the former Ritter Filling Station that impacted the site and a former dry cleaning facility.
Datum:	North American Datum of 1983
Acres Property ID:	40921
IC Data Access:	Not reported

912 E. 11TH STREET (Continued) **1010157579**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	189.38
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	8/1/2006
Ownership Entity:	Government
Completion Date:	10/31/2006
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals Petroleum Products VOCs
Contaminant Cleanup:	Not reported
Media Affected:	Ground Water Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	One of two properties located in a down-gradient location from the former Ritter Filling Station that impacted the site and a former dry cleaning facility.
Below Poverty Number:	428
Below Poverty Percent:	17.76

912 E. 11TH STREET (Continued) **1010157579**

Meidan Income:	7163
Meidan Income Number:	660
Meidan Income Percent:	27.39
Vacant Housing Number:	193
Vacant Housing Percent:	14.67
Unemployed Number:	94
Unemployed Percent:	3.9

3256 ESE 1/4-1/2 0.446 mi. 2354 ft. **WENCO DISTRIBUTORS OF TEXAS N**
600 INDUSTRIAL BLVD
AUSTIN, TX 78745

TX LPST **U001238063**
TX UST **N/A**
TX HIST UST
TX ASBESTOS
TX CENTRAL REGISTRY

Actual: 672 ft.

Focus Map: 18

LPST:

Name:	WENCO DISTRIBUTING
Address:	600 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 78767
Facility ID:	0000803
LPST Id:	100669
Facility Location:	SOUTH OF BEN WHITE WEST OF IH 35 600 INDUSTRIAL BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/22/1991
Entered Date:	11/15/1991
Reported Date:	10/22/1991
Closure Date:	01/30/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	PHILLIP J HUBNIK
Responsible Party Address:	600 INDUSTRIAL BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78767
Responsible Party Telephone:	512/444-6701
Reported Date:	10/22/1991
Case Start Date:	01/30/1992
Reference Number:	RN100721265
Project Manager:	HWELCH

UST:

Name:	WENCO DISTRIBUTORS OF TEXAS N
Address:	600 INDUSTRIAL BLVD
City,State,Zip:	AUSTIN, TX 787451299
AI Number:	803
Facility Type:	UNKNOWN
Facility Begin Date:	08/31/1988
Facility Status:	INACTIVE
Additional ID:	556600092004079
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78767
Contact Name/Title:	WAYNE MOHR,OPERATIONS MGR
Contact Organization Name:	WENCO DISTRIBUTORS OF TEXAS N
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124446701
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/17/1986
Signature Name/Title On Earliest Reg Form:	PHILLIP HUBNIK,MANAGER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602584674
Owner Last Name:	WENCO DISTRIBUTORS OF TEXAS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	636350692004070
Additional ID:	556600092004079
AI Number:	803
Owner Effective Begin Date:	09/01/1988
State Tax ID:	17425141516
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	1979

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Facility ID:	83804
Ai Number:	803
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	2000

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

UST Comprt ID:	129244
UST ID:	1979
AI Number:	803
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	2000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	1980
Facility ID:	83804
Ai Number:	803
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	10/03/1991
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	2000
UST Comprt ID:	129245
UST ID:	1980
AI Number:	803
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	WENCO DISTRIBUTORS OF TEXAS INC
Contact Mailing Address (Delivery):	2250 CHIPLEY CIR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78217 4917
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	83804
Additional ID:	556600092004079
Princ ID:	636350692004070
AI Number:	803
Facility Name:	WENCO DISTRIBUTORS OF TEXAS N
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	GARY MILLER/

HIST UST AUSTIN:

Name:	WENCO DISTRIBUTORS
Address:	600 INDUSTRIAL BLVD

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

City,State,Zip:	AUSTIN, TX
Id UST:	C0279
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	600 INDUSTRIAL BLVD. SUITE B
Address:	600 INDUSTRIAL BLVD. SUITE B
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	Not reported
Reason for Inspection:	Bill J. Post
Violation:	Not reported
Complaint Date:	12/30/2016
Notification Number:	2016010219
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	Not reported
Travel Time:	Not reported
Mileage:	Not reported
Reg:	Not reported
Init:	Not reported
Seq:	Not reported
Facility Type:	Public
Inspector Name:	Not reported
Date Report Received:	12/16/2016
Date Routed by Supervisor:	Not reported
Date Routed to PSQA:	Not reported
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Current
Amendo:	0
Notification Work Type:	Abatement
Notification Type:	Original
Work Type Flag:	A
Certification Statement Date:	12/16/2016
Certification Statement Phone:	512-778-6800
Is The Facility a School or K-12?:	N
Region:	07
Priority:	LOW
ARU:	0
Is this a phased abatement project?:	N
Ordered:	N
Is This Project an Emergency?:	N
Is Building Occupied?:	N
High Profile:	N
Ref Method:	Full Containment
Analytical Method:	PLM

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Start Date:	12/30/2016
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600617534
Customer Name:	JELD-WEN INC
Customer Legal Name:	Jeld-Wen, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602584674
Customer Name:	WENCO DISTRIBUTORS OF TEXAS INC
Customer Legal Name:	Wenco Distributors Of Texas, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604242875
Customer Name:	DAVIDSON TEXAS INC
Customer Legal Name:	DAVIDSON TEXAS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1988
Affiliation End Date:	8/31/1988
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427153
Customer Name:	WENCO DISTRIBUTING
Customer Legal Name:	Wenco Distributing
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600617534
Customer Name:	JELD-WEN INC
Customer Legal Name:	Jeld-Wen, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602584674
Customer Name:	WENCO DISTRIBUTORS OF TEXAS INC
Customer Legal Name:	Wenco Distributors Of Texas, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604242875
Customer Name:	DAVIDSON TEXAS INC
Customer Legal Name:	DAVIDSON TEXAS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1988
Affiliation End Date:	8/31/1988
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604427153
Customer Name:	WENCO DISTRIBUTING
Customer Legal Name:	Wenco Distributing
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	##########
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE

WENCO DISTRIBUTORS OF TEXAS N (Continued) **U001238063**

Status Date:	##########
Customer Number:	CN600617534
Customer Name:	JELD-WEN INC
Customer Legal Name:	Jeld-Wen, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	7/27/1980
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN602584674
Customer Name:	WENCO DISTRIBUTORS OF TEXAS INC
Customer Legal Name:	Wenco Distributors Of Texas, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	9/1/1988
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Regulated Entity Number:	RN100721265
Name:	WENCO DISTRIBUTORS OF TX
Address:	600 INDUSTRIAL BLVD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78745-1299
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN604242875
Customer Name:	DAVIDSON TEXAS INC
Customer Legal Name:	DAVIDSON TEXAS, INC.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/30/1988
Affiliation End Date:	8/31/1988
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	321999
Primary NAICS Industry Type Description:	All Other Miscellaneous Wood Product Manufacturing
Physical Location Description:	600 INDUSTRIAL BLVD.

Click this hyperlink while viewing on your computer to access
2 additional TX CENTRAL REG: record(s) in the EDR Site Report.

UB3257 **916 E. 11TH STREET** **US BROWNFIELDS** **1010157580**
NE **916 E. 11TH STREET** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.449 mi.
2372 ft. **Site 3 of 9 in cluster UB**

Actual:
518 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	916 E. 11TH STREET
Address:	916 E. 11TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197217, 020806161000
Parcel size:	0.12
Latitude:	30.2699
Longitude:	-97.7307
HCM Label:	Address Matching-Other
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	The 916 site is vacant and is part of the 11th Street 11-1 block targeted for redevelopment mixed use projects in the future. (PPF-916 E. 11th Street, 3/28/07) Former Use: Group with 912 E. 11th for ESA located in a down-gradient location from the former Ritter Filling Station that impacted the property and a former dry cleaning facility.
Datum:	North American Datum of 1983
Acres Property ID:	42121
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	189.38
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	8/1/2006
Ownership Entity:	Government
Completion Date:	10/31/2006
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

916 E. 11TH STREET (Continued) **1010157580**

IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals Petroleum Products VOCs
Contaminant Cleanup:	Not reported
Media Affected:	Ground Water Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Group with 912 E. 11th for ESA located in a down-gradient location from the former Ritter Filling Station that impacted the property and a former dry cleaning facility.
Below Poverty Number:	434
Below Poverty Percent:	17.87
Meidan Income:	7330
Meidan Income Number:	669
Meidan Income Percent:	27.54
Vacant Housing Number:	193
Vacant Housing Percent:	14.58
Unemployed Number:	94
Unemployed Percent:	3.87
Name:	916 E. 11TH STREET
Address:	916 E. 11TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197217, 020806161000
Parcel size:	0.12
Latitude:	30.2699
Longitude:	-97.7307
HCM Label:	Address Matching-Other
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	The 916 site is vacant and is part of the 11th Street 11-1 block targeted for redevelopment mixed use projects in the future. (PPF-916 E. 11th Street, 3/28/07) Former Use: Group with 912 E. 11th for ESA located in a down-gradient location from the former Ritter Filling Station that impacted the property and a former dry cleaning facility.
Datum:	North American Datum of 1983
Acres Property ID:	42121
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported

916 E. 11TH STREET (Continued) **1010157580**

Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6271.57
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	11/1/2006
Ownership Entity:	Government
Completion Date:	12/28/2006
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals Petroleum Products VOCs
Contaminant Cleanup:	Not reported
Media Affected:	Ground Water Soil
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Group with 912 E. 11th for ESA located in a down-gradient location from the former Ritter Filling Station that impacted the property and a former dry cleaning facility.
Below Poverty Number:	434
Below Poverty Percent:	17.87
Meidan Income:	7330
Meidan Income Number:	669

916 E. 11TH STREET (Continued) **1010157580**

Meidan Income Percent:	27.54
Vacant Housing Number:	193
Vacant Housing Percent:	14.58
Unemployed Number:	94
Unemployed Percent:	3.87

UC3258 **STOP N GO #2207** **TX RDR** **S127532158**
East **4429 DUVAL ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.451 mi.
2381 ft. **Site 1 of 3 in cluster UC**

Actual:
603 ft.

Focus Map:
9

RDR:

RDR ID:	5535
Facility ID:	39570
RN:	Not reported
CN:	Not reported
Name:	STOP N GO #2207
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/28/1999
Due Date:	12/27/1999
Tank Owner:	NATIONAL CONVENIENCE STOR
Contact Person:	MACK BRICE
Report:	RDR
Latest TCEQ Letter:	Not reported
Date of Latest TCEQ Letter:	Not reported
Project Manager:	Not reported
Team:	Not reported
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UC3259 **SUNRISE SUPER STOP** **TX LPST** **U003040323**
East **4429 DUVAL ST** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78751** **TX HIST UST**
0.451 mi. **TX Financial Assurance**
2381 ft. **Site 2 of 3 in cluster UC**

Actual:
603 ft.

Focus Map:
9

LPST:

Name:	STOP N GO 2207
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Facility ID:	0039570
LPST Id:	114818
Facility Location:	4429 DUVAL
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Austin

SUNRISE SUPER STOP (Continued) **U003040323**

Discovered Date:	11/02/1998
Entered Date:	12/01/1999
Reported Date:	12/22/1998
Closure Date:	04/11/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/1P
Coordinators RPR:	RWD
Responsible Party Name:	Not reported
Responsible Party Contact:	MACK BRICE
Responsible Party Address:	PO BOX 696000
Responsible Party City,St,Zip:	SAN ANTONIO, TX 78269 6000
Responsible Party Telephone:	972/252-1880
Reported Date:	12/22/1998
Case Start Date:	04/11/2001
Reference Number:	RN102817657
Project Manager:	RWD

UST:

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 787513917
AI Number:	39570
Facility Type:	RETAIL
Facility Begin Date:	01/14/1987
Facility Status:	ACTIVE
Additional ID:	398500862002221
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	5
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78751
Contact Name/Title:	,
Contact Organization Name:	Not reported
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	Not reported
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	10/01/2018
Signature Name/Title On Earliest Reg Form:	GUY OLIVER,AUTH REP
Application Received Date On Earliest Reg Form:	10/04/2018
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

SUNRISE SUPER STOP (Continued) **U003040323**

Princ ID:	264324162020029
Additional ID:	398500862002221
Ai Number:	39570
Operator CN:	CN605745975
Operator Name:	GOZIG HOLDINGS LLC
Operator Effective Begin Date:	01/01/2020
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601413677
Owner Last Name:	720 LAMAR PLACE LC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	335739642002204
Additional ID:	398500862002221
AI Number:	39570
Owner Effective Begin Date:	08/08/2012
State Tax ID:	30118952057
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	61088
Cert ID:	373763
AI Number:	39570
Self Certification Date:	08/02/2022
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENTATIVE

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	361283
AI Number:	39570
Self Certification Date:	09/29/2021
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	341776
AI Number:	39570
Self Certification Date:	08/31/2020
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	332212
AI Number:	39570
Self Certification Date:	01/15/2020
Signature Name/Title:	GUY OLIVER AUTH REP

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	AMENDMENT
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	323877
AI Number:	39570
Self Certification Date:	07/31/2019
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	306300
AI Number:	39570
Self Certification Date:	07/09/2018
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	290411
AI Number:	39570
Self Certification Date:	08/15/2017
Signature Name/Title:	Guy Oliver Legal Authorized Rep

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	273442
AI Number:	39570
Self Certification Date:	08/11/2016
Signature Name/Title:	Guy Oliver Legal Authorized Rep
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	255691
AI Number:	39570
Self Certification Date:	07/24/2015
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	238880
AI Number:	39570
Self Certification Date:	07/16/2014
Signature Name/Title:	Guy Oliver Legal Authorized Rep

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	223218
AI Number:	39570
Self Certification Date:	08/06/2013
Signature Name/Title:	Guy Oliver Authorized Represent
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2014
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	61088
Cert ID:	63445
AI Number:	39570
Self Certification Date:	07/13/2012
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63444
AI Number:	39570
Self Certification Date:	07/12/2011
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63443
AI Number:	39570
Self Certification Date:	07/27/2010
Signature Name/Title:	GUY OLIVER AUTHORIZED REPRESENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63442
AI Number:	39570
Self Certification Date:	05/28/2009
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63441
AI Number:	39570
Self Certification Date:	05/02/2008
Signature Name/Title:	GUY OLIVER AUTH REP

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63440
AI Number:	39570
Self Certification Date:	05/01/2008
Signature Name/Title:	GUY OLIVER AUTH REP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63439
AI Number:	39570
Self Certification Date:	05/27/2007
Signature Name/Title:	NICK MOMIN MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63438
AI Number:	39570
Self Certification Date:	05/14/2006
Signature Name/Title:	NICK MOMIN OWNER

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63437
AI Number:	39570
Self Certification Date:	04/26/2005
Signature Name/Title:	VIRGINIA HALE REPRESENTIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63436
AI Number:	39570
Self Certification Date:	05/11/2004
Signature Name/Title:	KARIM ALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63435
AI Number:	39570
Self Certification Date:	04/30/2003
Signature Name/Title:	BRUNO T TOWA ENV ENGR

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63434
AI Number:	39570
Self Certification Date:	05/23/2002
Signature Name/Title:	BRUNO T TOWA ENV ENGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63433
AI Number:	39570
Self Certification Date:	05/22/2002
Signature Name/Title:	BRUNO T TOWA ENV ENGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	06/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	61088
Cert ID:	63432
AI Number:	39570
Self Certification Date:	01/18/2001
Signature Name/Title:	PETER OTTO PRESIDENT

SUNRISE SUPER STOP (Continued) **U003040323**

Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	05/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104617
Facility ID:	61088
Ai Number:	39570
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	05/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N

SUNRISE SUPER STOP (Continued) **U003040323**

TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	4000
UST Comprt ID:	54724
UST ID:	104617
AI Number:	39570
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y

SUNRISE SUPER STOP (Continued) **U003040323**

Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	05/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104619
Facility ID:	61088
Ai Number:	39570
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	05/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y

SUNRISE SUPER STOP (Continued) **U003040323**

PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	54726
UST ID:	104619
AI Number:	39570
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	02/01/1984

SUNRISE SUPER STOP (Continued) **U003040323**

Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104620
Facility ID:	61088
Ai Number:	39570
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	02/01/1984
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N

SUNRISE SUPER STOP (Continued) **U003040323**

Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	54727
UST ID:	104620
AI Number:	39570
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	05/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104621
Facility ID:	61088

SUNRISE SUPER STOP (Continued) **U003040323**

Ai Number:	39570
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	05/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	4000
UST Comprt ID:	54728

SUNRISE SUPER STOP (Continued) **U003040323**

UST ID:	104621
AI Number:	39570
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Install Date:	05/01/1973
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	104618
Facility ID:	61088
Ai Number:	39570
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	05/01/1973
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N

SUNRISE SUPER STOP (Continued) **U003040323**

Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	54725
UST ID:	104618
AI Number:	39570
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

SUNRISE SUPER STOP (Continued) **U003040323**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	7053
Facility ID:	61088
AI Number:	39570
Application Received Date:	12/14/2009
Scheduled Construction Date:	12/14/2009
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported

SUNRISE SUPER STOP (Continued) **U003040323**

Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	50118
General Desc Of Prop Construct:	REPIPE W/ 2" DOUBLE WALL PIPE. INSTALL TWO (2) NEW DISPENSERS. INSTALL SENSOR SUMPS AND SUBMERSIBLE PUMP SUMPS.

Facility Billing Contacts:

Contact Organization Name:	720 LAMAR PLACE L C
Contact Mailing Address (Delivery):	3201 BEE CAVES RD STE 162137
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78746 6771
Phone Number/Ext:	512 6372010/0
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61088
Additional ID:	398500862002221
Princ ID:	335739642002204
AI Number:	39570
Facility Name:	SUNRISE SUPER STOP
AR Number:	50118
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	GUY OLIVER/

HIST UST AUSTIN:

Name:	MINI'S FOOD MART
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX
Id UST:	3107
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

TX Financial Assurance 2:

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	271612
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2021
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000015381

SUNRISE SUPER STOP (Continued) **U003040323**

Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	255485
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2020
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-000015381
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	227176
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2

SUNRISE SUPER STOP (Continued) **U003040323**

Facility ID:	61088
Finass ID:	236741
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2019
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04top000006446
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	216568
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2018
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO000109456
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	205122
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y

SUNRISE SUPER STOP (Continued) **U003040323**

3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/27/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	199575
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2017
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000104009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	182955
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2016
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to000099530
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2017
Ins Premium Pre-Paid For Entire Yr:	No

SUNRISE SUPER STOP (Continued) **U003040323**

Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	165383
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2015
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00095141
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	146481
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2014
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TO-00091009
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	130220
AI:	39570

SUNRISE SUPER STOP (Continued) **U003040323**

Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2013
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00086907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	112251
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TO00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	112301
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2012
Date Financial Assurance Form Rec:	10/04/2018

SUNRISE SUPER STOP (Continued) **U003040323**

Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04to00082907
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/22/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	4999
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2011
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO79114
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43482
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP

SUNRISE SUPER STOP (Continued) **U003040323**

Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43483
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2010
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO75364
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43716
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43715
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported

SUNRISE SUPER STOP (Continued) **U003040323**

Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2009
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO71832
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43717
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2008
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO69185
Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43718
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/22/2007
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 3381733
Policy Number:	04-TO-66839

SUNRISE SUPER STOP (Continued) **U003040323**

Coverage Amount:	1000000
Coverage Expiration Date:	12/22/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SUNRISE SUPER STOP
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX 78751
Region:	2
Facility ID:	61088
Finass ID:	43719
AI:	39570
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/30/1993
Date Financial Assurance Form Rec:	10/04/2018
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

UC3260 **MINIS FOOD MART** **TX RDR** **S127532157**
East **4429 DUVAL ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.451 mi.
2381 ft. **Site 3 of 3 in cluster UC**

Actual:
603 ft.

Focus Map:
9

RDR:

RDR ID:	20065
Facility ID:	39570
RN:	Not reported
CN:	Not reported
Name:	MINIS FOOD MART
Address:	4429 DUVAL ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/24/2011
Due Date:	12/23/2011
Tank Owner:	720 LAMAR PLACE LLC
Contact Person:	GUY OLIVER
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	1/6/2012
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	114818
Comments:	SIR LTR SENT 1/6/12 NO FURTHER SITE CHECK REQUIRED
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported

MINIS FOOD MART (Continued) **S127532157**

Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	1/6/2012
Region:	Not reported
DKC RDR (misfiled):	Not reported

3261 ESE 1/4-1/2 0.452 mi. 2384 ft.

MR SAMS FOODMART
6515 AIRPORT BLVD
AUSTIN, TX 78752

TX LPST **U003421915**
TX UST **N/A**
TX HIST UST
TX ASBESTOS
TX Financial Assurance

Actual: 693 ft.

Focus Map: 9

LPST:

Name:	MR G TEXACO STATION
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78700
Facility ID:	0019629
LPST Id:	101816
Facility Location:	6515 AIRPORT BLVD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/06/1992
Entered Date:	04/09/1992
Reported Date:	02/06/1992
Closure Date:	08/31/2004
Priority:	2.6 - IMPACTED GW DISCHARGE TO SW USED BY HUMANENDGR SPEC LT 500F
Program:	3 - STATE LEAD
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater or storm water runoff is affected and discharges within 500 feet of the known extent of contamination to a surface water body used for human drinking water, contact recreation, habitat to a protected or listed endangered plant and animal species.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	3/1/4/3
Coordinators RPR:	RWS
Responsible Party Name:	Not reported
Responsible Party Contact:	ROBERT GHASEMI
Responsible Party Address:	6515 AIRPORT BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/467-2230
Reported Date:	02/06/1992
Case Start Date:	08/31/2004
Reference Number:	RN102466745
Project Manager:	RSHAVER

UST:

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 787523614
AI Number:	19629
Facility Type:	RETAIL
Facility Begin Date:	08/31/1988
Facility Status:	ACTIVE
Additional ID:	638172202002156
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes

MR SAMS FOODMART (Continued) **U003421915**

Number Of Active UST:	4
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	AZIZ SALEH,STORE MGR
Contact Organization Name:	MR SAMS FOODMART
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127890990
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	09/15/2022
Signature Name/Title On Earliest Reg Form:	AZIZ SALEH,MNGR
Application Received Date On Earliest Reg Form:	09/17/2022
Signature Role On Earliest Reg Form:	OPERATOR
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	301494812014301
Additional ID:	638172202002156
Ai Number:	19629
Operator CN:	CN604693994
Operator Name:	MR SAMS FOOD MART LLC
Operator Effective Begin Date:	10/01/2021
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	AZIZ SALEH/MGR
Contact Organization Name:	MR SAMS FOOD MART LLC
Contact Mailing Address (Delivery):	10040 LACHLAN DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78717-4501
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	7890990
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	AZIZ1328@YAHOO.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN604693994
Owner Last Name:	MR SAMS FOOD MART LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	10040 LACHLAN DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN

MR SAMS FOODMART (Continued) **U003421915**

Contact Mailing State:	TX
Contact Mailing Zip:	78717
Contact Mailing Zip5:	4501
Contact Phone Number/Ext:	1 512 7890990/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	AZIZ1328@YAHOO.COM
Contact Address Deliverable:	Not reported
Princ ID:	301494812014301
Additional ID:	638172202002156
AI Number:	19629
Owner Effective Begin Date:	10/01/2021
State Tax ID:	32054104149
Contact Role:	OWNOPRCON
Contact Name/Title:	AZIZ SALEH/MGR
Contact Organization Name:	MR SAMS FOOD MART LLC

Self Certification:

Self Cert ID:	93047
Cert ID:	379866
AI Number:	19629
Self Certification Date:	09/15/2022
Signature Name/Title:	AZIZ SALEH MNGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	362041
AI Number:	19629
Self Certification Date:	10/10/2021
Signature Name/Title:	MITRA KOOKMA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	343683
AI Number:	19629
Self Certification Date:	08/04/2020
Signature Name/Title:	AZIZ SALEH OPERATOR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	324716
AI Number:	19629
Self Certification Date:	07/23/2019
Signature Name/Title:	STEVEN M BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	308027
AI Number:	19629
Self Certification Date:	08/01/2018
Signature Name/Title:	AZIZ SALEH MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	293339
AI Number:	19629
Self Certification Date:	09/18/2017
Signature Name/Title:	STEVEN BOWEN MGR
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	274793
AI Number:	19629
Self Certification Date:	08/16/2016
Signature Name/Title:	STEVENS BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	260106
AI Number:	19629
Self Certification Date:	09/10/2015
Signature Name/Title:	STEVEN BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	241714
AI Number:	19629
Self Certification Date:	09/10/2014
Signature Name/Title:	AZIZ SALEH MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	225019
AI Number:	19629
Self Certification Date:	09/09/2013
Signature Name/Title:	AZIZ SALEH MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	93047
Cert ID:	148468
AI Number:	19629
Self Certification Date:	09/04/2012
Signature Name/Title:	STEVE BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	148467
AI Number:	19629
Self Certification Date:	08/31/2011
Signature Name/Title:	STEVEN M BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148466
AI Number:	19629
Self Certification Date:	08/20/2010
Signature Name/Title:	AZIZ SALEH MANAGER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148465
AI Number:	19629
Self Certification Date:	07/20/2008
Signature Name/Title:	AZIZ SALEH MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	148464
AI Number:	19629
Self Certification Date:	08/20/2007
Signature Name/Title:	AZIZ SALEH MGR
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148463
AI Number:	19629
Self Certification Date:	08/23/2006
Signature Name/Title:	STEVE BOWERS OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148462
AI Number:	19629
Self Certification Date:	07/19/2005
Signature Name/Title:	CHAD FERGUSON VP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	148461
AI Number:	19629
Self Certification Date:	01/26/2005
Signature Name/Title:	CHAD FERGUSON MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148460
AI Number:	19629
Self Certification Date:	08/18/2004
Signature Name/Title:	AZIZ SALEH MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148459
AI Number:	19629
Self Certification Date:	07/25/2003
Signature Name/Title:	ROBERT GHASEMI VICE PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047

MR SAMS FOODMART (Continued) **U003421915**

Cert ID:	148458
AI Number:	19629
Self Certification Date:	06/26/2002
Signature Name/Title:	ROBERT GHASEMI VP
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	93047
Cert ID:	148457
AI Number:	19629
Self Certification Date:	09/03/2000
Signature Name/Title:	ROBERT GHASEMI VP
Signature Type Role:	OPERATOR
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	08/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50506
Facility ID:	93047
Ai Number:	19629
Tank Id:	4
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	01/01/1986
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

MR SAMS FOODMART (Continued) **U003421915**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	4000
UST Comprt ID:	150451
UST ID:	50506
AI Number:	19629
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

MR SAMS FOODMART (Continued) **U003421915**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/03/1986

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50509
Facility ID:	93047
Ai Number:	19629
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	01/01/1986
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y

MR SAMS FOODMART (Continued) **U003421915**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	150454
UST ID:	50509
AI Number:	19629
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

MR SAMS FOODMART (Continued) **U003421915**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/03/1986

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	4000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50508
Facility ID:	93047
Ai Number:	19629
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	01/01/1986
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

MR SAMS FOODMART (Continued) **U003421915**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	4000
UST Comprt ID:	150453
UST ID:	50508
AI Number:	19629
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

MR SAMS FOODMART (Continued) **U003421915**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/03/1986

Install Date:	01/01/1985
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	50507
Facility ID:	93047
Ai Number:	19629
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	01/01/1985
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	01/01/1986
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	Y
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N

MR SAMS FOODMART (Continued) **U003421915**

TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	02/22/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	150452
UST ID:	50507
AI Number:	19629
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N

MR SAMS FOODMART (Continued) **U003421915**

Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	03/03/1986

Construction Notification:

NOC ID:	14710
Facility ID:	93047
AI Number:	19629
Application Received Date:	11/16/2004
Scheduled Construction Date:	11/02/2004
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	M41116005
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	63074
General Desc Of Prop Construct:	Not reported

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	15782
UST ID:	Not reported
NOC ID:	14710
AI Number:	19629
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP001249
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported

MR SAMS FOODMART (Continued) **U003421915**

Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MR SAMS FOOD MART LLC
Contact Mailing Address (Delivery):	10040 LACHLAN DR
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78717 4501
Phone Number/Ext:	512 7890990/0
Contact Fax Number/Ext:	/
Contact Email Address:	AZIZ1328@YAHOO.COM
Contact Address Deliverable:	Y
Facility ID:	93047
Additional ID:	638172202002156
Princ ID:	301494812014301
AI Number:	19629
Facility Name:	MR SAMS FOODMART
AR Number:	83988
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	AZIZ SALEH/MGR

HIST UST AUSTIN:

Name:	MR. SAM'S FOOD MART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	836
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Date of inspection:	06/28/2013
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson

MR SAMS FOODMART (Continued) **U003421915**

Date Report Received:	07/01/2013
Date Routed by Supervisor:	07/01/2013
Date Routed to PSQA:	07/09/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Descriptio:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	277040

MR SAMS FOODMART (Continued) **U003421915**

AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2022
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04TOP000033144
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	259069
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2021
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000023287
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	238186
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2019

MR SAMS FOODMART (Continued) **U003421915**

Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	TUDOR INS CO
Issuer Phone:	1 919 6939400
Policy Number:	CPG1010521
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	218883
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2018
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	TUDOR INS CO
Issuer Phone:	1 919 6394400
Policy Number:	CPG1010212
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	201423
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	10/19/2017
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	TUDOR INS CO
Issuer Phone:	Not reported
Policy Number:	CPG1009939
Coverage Amount:	1,000,000
Coverage Expiration Date:	10/19/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

MR SAMS FOODMART (Continued) **U003421915**

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	186439
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	11/10/2016
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP219200
Coverage Amount:	1,000,000
Coverage Expiration Date:	11/10/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	151696
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/23/2015
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP217610
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/23/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	167138
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

MR SAMS FOODMART (Continued) **U003421915**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	09/23/2015
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP217610
Coverage Amount:	1,000,000
Coverage Expiration Date:	09/23/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	132861
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/2014
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP214832
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/24/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	114600
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/2013
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614

MR SAMS FOODMART (Continued) **U003421915**

Policy Number:	PP214832
Coverage Amount:	1,000,000
Coverage Expiration Date:	01/24/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	10743
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/2012
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP214832
Coverage Amount:	1000000
Coverage Expiration Date:	01/24/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	73933
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/2011
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP214832
Coverage Amount:	1000000
Coverage Expiration Date:	01/24/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752

MR SAMS FOODMART (Continued) **U003421915**

Region:	2
Facility ID:	93047
Finass ID:	74164
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/2008
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP210396
Coverage Amount:	1000000
Coverage Expiration Date:	01/24/2009
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	MR SAMS FOODMART
Address:	6515 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Region:	2
Facility ID:	93047
Finass ID:	74165
AI:	19629
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	09/17/2022
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

UD3262 **CUTLER AUTOMOTIVE** **TX RDR** **S126523768**
NNW **4416 BURNET RD** **TX CENTRAL REGISTRY** **N/A**
1/4-1/2 **AUSTIN, TX 78756**
0.453 mi.
2390 ft. **Site 1 of 2 in cluster UD**

Actual:
662 ft.

Focus Map:
8

RDR:

RDR ID:	2520
Facility ID:	23279
RN:	Not reported
CN:	Not reported
Name:	CUTLER AUTOMOTIVE
Address:	4416 BURNET RD

CUTLER AUTOMOTIVE (Continued) **S126523768**

City,State,Zip:	AUSTIN, TX
Date Report Received:	5/29/2001
Due Date:	7/28/2001
Tank Owner:	MURRAY INVESTMENTS
Contact Person:	MRS JOE BAILEY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/18/2001
Project Manager:	Stacey Jagge
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	RECOMMEND CLEAN CLOSURE; PENDING 2ND REVIEW--6/18
Review Coordinator:	SRJ
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	7/18/2001
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

CENTRAL REGISTRY:

Regulated Entity Number:	RN101492502
Name:	CUTLER AUTOMOTIVE
Address:	4416 BURNET RD
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78756-3319
Status:	ACTIVE
Status Date:	2/22/2002
Customer Number:	CN600780977
Customer Name:	MURRAY JONES INVESTMENTS INC
Customer Legal Name:	Murray Jones Investments Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	9/25/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	Not reported

UB3263 **920 E. 11TH ST (11TH STREET 900 BLK)** **US BROWNFIELDS FINDS** **1016347360**
ENE **920 E. 11TH ST** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.453 mi.
2393 ft. **Site 4 of 9 in cluster UB**

Actual:
520 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	920 E. 11TH ST (11TH STREET 900 BLK)
Address:	920 E. 11TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197216, 02080616090000
Parcel size:	0.12
Latitude:	30.269831
Longitude:	-97.730581

920 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347360**

HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 920 E. 11th St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46701
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

920 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347360**

Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	U
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	440
Below Poverty Percent:	17.75
Meidan Income:	7325
Meidan Income Number:	682
Meidan Income Percent:	27.51
Vacant Housing Number:	196
Vacant Housing Percent:	14.54
Unemployed Number:	96
Unemployed Percent:	3.87

Name:	920 E. 11TH ST (11TH STREET 900 BLK)
Address:	920 E. 11TH ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197216, 02080616090000
Parcel size:	0.12
Latitude:	30.269831
Longitude:	-97.730581
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 920 E. 11th St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46701
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment

920 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347360**

Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	U
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	440
Below Poverty Percent:	17.75
Meidan Income:	7325
Meidan Income Number:	682
Meidan Income Percent:	27.51
Vacant Housing Number:	196
Vacant Housing Percent:	14.54
Unemployed Number:	96
Unemployed Percent:	3.87

FINDS:
Registry ID: 110038721069

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to

920 E. 11TH ST (11TH STREET 900 BLK) (Continued) **1016347360**

electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UD3264 **TETCO #1169** **TX RDR** **S127525776**
NNW **1309 W. 45TH ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.454 mi.
2398 ft. **Site 2 of 2 in cluster UD**

Actual:
666 ft.

Focus Map:
8

RDR:

RDR ID:	1309
Facility ID:	17724
RN:	Not reported
CN:	Not reported
Name:	TETCO #1169
Address:	1309 W. 45TH ST
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/8/1999
Due Date:	9/6/1999
Tank Owner:	TETCO STORES LP
Contact Person:	MICHAEL K GARROTT
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/5/1999
Project Manager:	Brent Rice
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	BJR
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/5/1999
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3265 **ABANDONED** **TX RDR** **S127541709**
WNW **1401 W KOENIG LN** **N/A**
1/4-1/2 **AUSTIN, TX**
0.455 mi.
2400 ft.

Actual:
665 ft.

Focus Map:
8

RDR:

RDR ID:	14625
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	ABANDONED
Address:	1401 W KOENIG LN
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/11/2005
Due Date:	9/9/2005
Tank Owner:	BILL STRINGER

ABANDONED (Continued) **S127541709**

Contact Person:	BILL STRINGER
Report:	RDR
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	8/23/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	116617
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?;LAD NOAPAR SENT 9/30/05
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UB3266 **903 JUNIPER ST (11TH ST 900 BLK)** **US BROWNFIELDS FINDS** **1012091548**
NE **903 JUNIPER ST** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.456 mi.
2407 ft. **Site 5 of 9 in cluster UB**

Actual:
509 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	903 JUNIPER ST (11TH ST 900 BLK)
Address:	903 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.12
Latitude:	30.270394
Longitude:	-97.730847
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Property is a corner commercial lot which is being consolidated with surrounding vacant residential lots to compile an entire city block. Once consolidation is complete, entire block will be mixed-use project (commercial and residential). Property is conveniently located to the down town business district. Attached to PPF - 11th Street Redevelopment Corridor (900 blk) is a diagram of the area. (PPF - 11th Street Redevelopment Corridor (900 blk), 2/8/06) Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 903 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency. Past use was residential.
Datum:	North American Datum of 1983
Acres Property ID:	18581
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported

903 JUNIPER ST (11TH ST 900 BLK) (Continued) **1012091548**

Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	U
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency. Past use was residential.
Below Poverty Number:	439
Below Poverty Percent:	18.02
Meidan Income:	7616
Meidan Income Number:	682
Meidan Income Percent:	28
Vacant Housing Number:	192

903 JUNIPER ST (11TH ST 900 BLK) (Continued) **1012091548**

Vacant Housing Percent:	14.46
Unemployed Number:	92
Unemployed Percent:	3.78
Name:	903 JUNIPER ST (11TH ST 900 BLK)
Address:	903 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.12
Latitude:	30.270394
Longitude:	-97.730847
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Property is a corner commercial lot which is being consolidated with surrounding vacant residential lots to compile an entire city block. Once consolidation is complete, entire block will be mixed-use project (commercial and residential). Property is conveniently located to the down town business district. Attached to PPF - 11th Street Redevelopment Corridor (900 blk) is a diagram of the area. (PPF - 11th Street Redevelopment Corridor (900 blk), 2/8/06) Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 903 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency. Past use was residential.
Datum:	North American Datum of 1983
Acres Property ID:	18581
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N

903 JUNIPER ST (11TH ST 900 BLK) (Continued) **1012091548**

Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	U
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency. Past use was residential.
Below Poverty Number:	439
Below Poverty Percent:	18.02
Meidan Income:	7616
Meidan Income Number:	682
Meidan Income Percent:	28
Vacant Housing Number:	192
Vacant Housing Percent:	14.46
Unemployed Number:	92
Unemployed Percent:	3.78

FINDS:

Registry ID: 110038702044

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3267 WSW 1/4-1/2 0.456 mi. 2408 ft. | **WHIP IN 2 100148**
1950 S IH 35
AUSTIN, TX 78704 | **TX LPST**
TX UST
TX HIST UST | **U001249764**
N/A

Actual: 552 ft.

Focus Map: 14

LPST:

Name:	WHIP IN 2 100148
Address:	1950 S IH 35
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0014317
LPST Id:	108190
Facility Location:	1950 S IH 950 S
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/08/1993
Entered Date:	06/24/1994
Reported Date:	05/16/1994
Closure Date:	06/03/1994
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	JIM SHIFLET
Responsible Party Address:	2550 N LOOP W #600
Responsible Party City,St,Zip:	HOUSTON, TX 77092
Responsible Party Telephone:	713/684-4362
Reported Date:	05/16/1994
Case Start Date:	06/03/1994
Reference Number:	RN102482742
Project Manager:	HWELCH

UST:

Name:	WHIP IN 2 100148
Address:	1950 S IH 35
City,State,Zip:	AUSTIN, TX 787043628
AI Number:	14317
Facility Type:	RETAIL
Facility Begin Date:	08/12/1986
Facility Status:	INACTIVE
Additional ID:	264717392002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	WHIP IN 2 100148
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported

WHIP IN 2 100148 (Continued) **U001249764**

Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124425337
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/07/1986
Signature Name/Title On Earliest Reg Form:	TONY MCMILLAN,V.P. SALES ADM.
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601275076
Owner Last Name:	E-Z SERVE PETROLEUM MARKETING COMPANY
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	56579202002156
Additional ID:	264717392002156
AI Number:	14317
Owner Effective Begin Date:	08/12/1986
State Tax ID:	17513720684
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36867
Facility ID:	38825
Ai Number:	14317
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/08/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y

WHIP IN 2 100148 (Continued) **U001249764**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	10000
UST Comprt ID:	3048
UST ID:	36867
AI Number:	14317
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

WHIP IN 2 100148 (Continued) **U001249764**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1979
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	36866
Facility ID:	38825
Ai Number:	14317
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	12/08/1993
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

WHIP IN 2 100148 (Continued) **U001249764**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	12/18/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	3047
UST ID:	36866
AI Number:	14317
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

WHIP IN 2 100148 (Continued) **U001249764**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	E-Z SERVE PETROLEUM MARKETING COMPANY
Contact Mailing Address (Delivery):	1824 HILLANDALE RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DURHAM, NC 27705 2650
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	38825
Additional ID:	264717392002156
Princ ID:	56579202002156
AI Number:	14317
Facility Name:	WHIP IN 2 100148
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	LINA HITCHCOCK/

HIST UST AUSTIN:

Name:	WHIP IN
Address:	1950 S IH 35
City,State,Zip:	AUSTIN, TX
Id UST:	C0430
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3268 WNW 1/4-1/2 0.457 mi. 2415 ft. | **SUNRISE MINI MART 2**
915 W OLTORF ST
AUSTIN, TX 78704

TX LPST | **U001243558**
TX UST | **N/A**
TX ASBESTOS
TX Financial Assurance

Actual: 571 ft.

Focus Map: 14

LPST:

Name:	7 11 12701
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0007135
LPST Id:	103773
Facility Location:	915 W OLTORF
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	07/09/1992
Entered Date:	07/26/1992
Reported Date:	07/10/1992
Closure Date:	09/03/1992
Priority:	6 - MINOR SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION - NO REMEDIAL ACTION REQUIRED
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	VICTOR RUIZ
Responsible Party Address:	2201 N CENTRAL EXPY STE 171
Responsible Party City,St,Zip:	RICHARDSON, TX 75080
Responsible Party Telephone:	214/907-0711
Reported Date:	07/10/1992
Case Start Date:	09/03/1992
Reference Number:	RN102368651
Project Manager:	HWELCH

UST:

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 787045325
AI Number:	7135
Facility Type:	RETAIL
Facility Begin Date:	07/03/1986
Facility Status:	ACTIVE
Additional ID:	792728252002149
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	Yes
Number Of Active UST:	1
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	ABDUL PATEL,PRESIDENT
Contact Organization Name:	SUNRISE MINI MART 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported

SUNRISE MINI MART 2 (Continued) **U001243558**

Contact Telephone:	5124417515
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Signature Date On Earliest Reg Form:	02/03/2023
Signature Name/Title On Earliest Reg Form:	ABDUL PATEL,OWN
Application Received Date On Earliest Reg Form:	02/09/2023
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	901358802003139
Additional ID:	792728252002149
Ai Number:	7135
Operator CN:	CN601678378
Operator Name:	ANAZ INCORPORATED
Operator Effective Begin Date:	08/31/1996
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	ABDUL PATEL/OWNER
Contact Organization Name:	ANAZ INCORPORATED
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN TX 78704-5325
Contact Phone Country Code:	1
Contact Phone Area Code:	512
Contact Phone Number:	4417515
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN601678378
Owner Last Name:	ANAZ INCORPORATED
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78704
Contact Mailing Zip5:	5325
Contact Phone Number/Ext:	1 512 4417515/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Contact Address Deliverable:	Not reported
Princ ID:	901358802003139
Additional ID:	792728252002149
AI Number:	7135

SUNRISE MINI MART 2 (Continued) **U001243558**

Owner Effective Begin Date:	08/31/1996
State Tax ID:	17427240100
Contact Role:	OWNCON
Contact Name/Title:	ABDUL PATEL/OWNER
Contact Organization Name:	ANAZ INCORPORATED

Self Certification:

Self Cert ID:	46140
Cert ID:	384962
AI Number:	7135
Self Certification Date:	02/03/2023
Signature Name/Title:	ABDUL PATEL OWN
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2024
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	367624
AI Number:	7135
Self Certification Date:	02/10/2022
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	351563
AI Number:	7135
Self Certification Date:	02/01/2021
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2022

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	333142
AI Number:	7135
Self Certification Date:	01/27/2020
Signature Name/Title:	ABDUL PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	317510
AI Number:	7135
Self Certification Date:	02/13/2019
Signature Name/Title:	ABDUL PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	299172
AI Number:	7135
Self Certification Date:	02/05/2018
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2019

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	283245
AI Number:	7135
Self Certification Date:	01/27/2017
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	266226
AI Number:	7135
Self Certification Date:	02/09/2016
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	249594
AI Number:	7135
Self Certification Date:	01/26/2015
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2016

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	232104
AI Number:	7135
Self Certification Date:	01/27/2014
Signature Name/Title:	ABDUL PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	46140
Cert ID:	26630
AI Number:	7135
Self Certification Date:	02/28/2013
Signature Name/Title:	ABDUL PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26629
AI Number:	7135
Self Certification Date:	03/29/2012
Signature Name/Title:	AMIN N MOMIN OPERATOR MANAGER
Signature Type Role:	OPERATOR
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2013

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26628
AI Number:	7135
Self Certification Date:	03/30/2011
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26627
AI Number:	7135
Self Certification Date:	01/21/2010
Signature Name/Title:	ABDUL K PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26626
AI Number:	7135
Self Certification Date:	03/26/2009
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2010

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26625
AI Number:	7135
Self Certification Date:	03/26/2008
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26624
AI Number:	7135
Self Certification Date:	03/27/2007
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26623
AI Number:	7135
Self Certification Date:	02/13/2006
Signature Name/Title:	ABDUL K PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2007

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26622
AI Number:	7135
Self Certification Date:	04/05/2005
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26621
AI Number:	7135
Self Certification Date:	04/05/2004
Signature Name/Title:	ABDUL PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	46140
Cert ID:	26620
AI Number:	7135
Self Certification Date:	04/01/2003
Signature Name/Title:	ABDUL K PATEL OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2004

SUNRISE MINI MART 2 (Continued) **U001243558**

Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26619
AI Number:	7135
Self Certification Date:	01/16/2002
Signature Name/Title:	ABDUL K PATEL PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	46140
Cert ID:	26618
AI Number:	7135
Self Certification Date:	07/24/2000
Signature Name/Title:	ABDUL K. PATEL PRESIDENT
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	03/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18487
Facility ID:	46140
Ai Number:	7135
Tank Id:	1A

SUNRISE MINI MART 2 (Continued) **U001243558**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/07/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	25945
UST ID:	18487
AI Number:	7135

SUNRISE MINI MART 2 (Continued) **U001243558**

Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	04/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18488
Facility ID:	46140
Ai Number:	7135
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/07/1994
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

SUNRISE MINI MART 2 (Continued) **U001243558**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	10000
UST Comprt ID:	25946
UST ID:	18488
AI Number:	7135
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

SUNRISE MINI MART 2 (Continued) **U001243558**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1976
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	18489
Facility ID:	46140
Ai Number:	7135
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/07/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

SUNRISE MINI MART 2 (Continued) **U001243558**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	08/14/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	10000
UST Comprt ID:	25947
UST ID:	18489
AI Number:	7135
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

SUNRISE MINI MART 2 (Continued) **U001243558**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	09/01/1996
Tank Registration Date:	04/20/1999
Number of Compartments:	2
Tank Capacity:	28000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	190878
Facility ID:	46140
Ai Number:	7135
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	09/01/1996
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N

SUNRISE MINI MART 2 (Continued) **U001243558**

PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/15/1999

Compartment Records:

Tank ID:	1
Tank Capacity:	14000
UST Comprt ID:	25948
UST ID:	190878
AI Number:	7135
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y

SUNRISE MINI MART 2 (Continued) **U001243558**

SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

Tank ID:	1
Tank Capacity:	14000
UST Comprt ID:	25949
UST ID:	190878
AI Number:	7135
Compartment ID:	B
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	Not reported

SUNRISE MINI MART 2 (Continued) **U001243558**

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	27066
UST ID:	190878
NOC ID:	Not reported
AI Number:	7135
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000668
Company Name:	Petro-Tech
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	42234
UST ID:	190878
NOC ID:	Not reported
AI Number:	7135
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000319
Company Name:	Not reported
Representative Name:	GARY HARDY
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	ANAZ INCORPORATED
Contact Mailing Address (Delivery):	915 W OLTORF ST
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78704 5325
Phone Number/Ext:	512 4417515/0
Contact Fax Number/Ext:	/

SUNRISE MINI MART 2 (Continued) **U001243558**

Contact Email Address:	SUNRISEMINIMART2@HOTMAIL.COM
Contact Address Deliverable:	Y
Facility ID:	46140
Additional ID:	792728252002149
Princ ID:	901358802003139
AI Number:	7135
Facility Name:	SUNRISE MINI MART 2
AR Number:	54003
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	ABDUL PATEL/

ASBESTOS:

Name:	SUNRISE MINI MART
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/08/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.4
Reg:	07
Init:	EJ
Seq:	06
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/13/2013
Date Routed by Supervisor:	03/13/2013
Date Routed to PSQA:	03/14/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported

SUNRISE MINI MART 2 (Continued) **U001243558**

Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	282097
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2022
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP686639
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140

SUNRISE MINI MART 2 (Continued) **U001243558**

Finass ID:	265232
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2021
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663914
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	247535
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2020
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663913
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	228044
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SUNRISE MINI MART 2 (Continued) **U001243558**

Financial Assurance Begin Date:	08/29/2019
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663912
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	211234
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2018
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663911
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	192570
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2017
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663910
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

SUNRISE MINI MART 2 (Continued) **U001243558**

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	176047
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2016
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	800 577 6614
Policy Number:	PP68663909
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	157944
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/23/2015
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663908
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/23/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	140889
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SUNRISE MINI MART 2 (Continued) **U001243558**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2014
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	Not reported
Policy Number:	PP68663907
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	123141
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2013
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP68663906
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	1516
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2012
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614

SUNRISE MINI MART 2 (Continued) **U001243558**

Policy Number:	PP 68663905
Coverage Amount:	1,000,000
Coverage Expiration Date:	08/29/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	28209
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2011
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 68663904
Coverage Amount:	1000000
Coverage Expiration Date:	08/29/2012
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	28210
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2010
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 68663903
Coverage Amount:	1000000
Coverage Expiration Date:	08/29/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704

SUNRISE MINI MART 2 (Continued) **U001243558**

Region:	2
Facility ID:	46140
Finass ID:	28211
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2009
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 68663902
Coverage Amount:	1000000
Coverage Expiration Date:	08/29/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	28212
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2008
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 68663901
Coverage Amount:	1000000
Coverage Expiration Date:	08/29/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	28213
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

SUNRISE MINI MART 2 (Continued) **U001243558**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	08/29/2007
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP 686639
Coverage Amount:	1000000
Coverage Expiration Date:	08/29/2008
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	SUNRISE MINI MART 2
Address:	915 W OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	46140
Finass ID:	28214
AI:	7135
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/24/1991
Date Financial Assurance Form Rec:	02/09/2023
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

TV3269 **300-302 S LAMAR** **TX RDR** **S127528368**
WSW **300 S LAMAR** **N/A**
1/4-1/2 **AUSTIN, TX**
0.460 mi.
2428 ft. **Site 2 of 2 in cluster TV**

Actual:
454 ft.

Focus Map:
11

RDR:

RDR ID:	17324
Facility ID:	26133
RN:	Not reported
CN:	Not reported
Name:	300-302 S LAMAR
Address:	300 S LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	5/12/2008
Due Date:	7/11/2008
Tank Owner:	PHOENIX PROPERTY CO
Contact Person:	MR GREG JONES
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	7/18/2008
Project Manager:	PST Privitization Contract

300-302 S LAMAR (Continued) **S127528368**

Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	DOES THIS NEED A LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	7/18/2008
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UB3270 **905 JUNIPER ST (11TH STREET 900 BLK)** **US BROWNFIELDS FINDS** **1016347354**
NE **905 JUNIPER ST.** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.461 mi.
2432 ft. **Site 6 of 9 in cluster UB**

Actual:
510 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	905 JUNIPER ST (11TH STREET 900 BLK)
Address:	905 JUNIPER ST.
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197211, 02080616040000
Parcel size:	0.12
Latitude:	30.270342
Longitude:	-97.730647
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 905 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46621
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N

905 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347354**

Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720
Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7
Name:	905 JUNIPER ST (11TH STREET 900 BLK)
Address:	905 JUNIPER ST.
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197211, 02080616040000
Parcel size:	0.12
Latitude:	30.270342
Longitude:	-97.730647

905 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347354**

HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 905 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46621
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

905 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347354**

Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720
Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7

FINDS:
Registry ID: 110038721005

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3271 ESE 1/4-1/2 0.462 mi. 2437 ft. | **HABITAT FOR HUMANITY 1407-1411 E. 4TH STREET AUSTIN, TX 78702** | **US BROWNFIELDS FINDS** | **1023619914 N/A**

Actual: 469 ft.

Focus Map: 11

US BROWNFIELDS:

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists

HABITAT FOR HUMANITY (Continued) **1023619914**

of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047

HABITAT FOR HUMANITY (Continued) **1023619914**

Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to

HABITAT FOR HUMANITY (Continued) **1023619914**

store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	200000
Redev. Funding Source:	Cielo Group
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	5/20/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	45
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property

HABITAT FOR HUMANITY (Continued) **1023619914**

owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	1500000
Redev. Funding Source:	Habitat for Humanity
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	5/20/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	45
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03

HABITAT FOR HUMANITY (Continued) **1023619914**

Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work

HABITAT FOR HUMANITY (Continued) **1023619914**

crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	10927
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	00F90901
Start Date:	11/2/2015
Ownership Entity:	Private
Completion Date:	12/7/2015
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved

HABITAT FOR HUMANITY (Continued) **1023619914**

with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901

HABITAT FOR HUMANITY (Continued) **1023619914**

Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809

HABITAT FOR HUMANITY (Continued) **1023619914**

Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site

HABITAT FOR HUMANITY (Continued) **1023619914**

	reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	8500000
Redev. Funding Source:	Habitat for Humanity
Redev. Funding Entity Name:	Private/Other Funding
Redevelopment Start Date:	5/20/2020
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	45
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5

HABITAT FOR HUMANITY (Continued) **1023619914**

Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common

HABITAT FOR HUMANITY (Continued) **1023619914**

ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.

Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520

HABITAT FOR HUMANITY (Continued) **1023619914**

Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

Name:	HABITAT FOR HUMANITY
Address:	1407-1411 E. 4TH STREET
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.5
Latitude:	30.261475
Longitude:	-97.728908
HCM Label:	Address Matching-House Number
Map Scale:	Not reported
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	the 6 story loft building will provide families with affordable housing with a market-rate appearance, immediately adjacent to Plaza Saltillo light rail. Condo prices will range between $125,000 to $175,000 - with interest-free mortgages - depending on a homebuyer's income. There will be one-, two- and three-bedroom units. All of the homebuyers' monthly housing expenses cannot exceed 30 percent of the buyer's income under Habitat's program. The subject property consists of three adjoining equally sized parcels of land, with two property owners. The 1409 ? 1411 East 4th Street parcels are currently paved with a perimeter chain link security fence that are under common ownership. The 1407 East 4th Street tract is a grassy, vacant lot that is apparently being used as a side yard for the 1405 East 4th Street tract. It is owned by a different entity than the owner of the 1409 ? 1411 East 4th Street tracts. Review of Sanborn maps indicates this tract was previously a residential property; no structures other than a bird coop are currently present. According to the Travis County Appraisal District, the pavement and fencing on the 1409 ? 1411 East 4th Street lots were completed in 1971. Review of aerial photographs indicates the paved area was first used as a parking lot. Most recently, the paved area had been used by Habitat for Humanity to store home improvement construction materials for their "Reuse Store". As of December 2016, plans call for a 5-story housing complex. Current zoning allows for only 3 stories, so they need a variance. If allowed, the 5 stories will house about 55 people. The approximate cost for the housing units is $8,500,000. Former Use: The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant?s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel

HABITAT FOR HUMANITY (Continued) **1023619914**

	is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Datum:	North American Datum of 1983
Acres Property ID:	205061
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Hazardous
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	00F90901
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Cielo Properties & RC Beall
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.25
Past use commercial acreage:	0.25
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	0.5
Future use commercial acreage:	Not reported

HABITAT FOR HUMANITY (Continued) **1023619914**

Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	The subject property consists of three 0.1664-acre parcels of real property totaling approximately 0.5 acre. The parcels of land located at 1409 and 1411 are owned by Cielo Property Group and the parcel of land located at 1407 East 4th Street is owned by Mr. R.C. Beall. There are no structures present on any of the subject property tracts. The parcels located at 1409 and 1411 East 4th Street are paved with asphalt and contained with a perimeter chain link security fence. According to the Travis County Appraisal District, the pavement and fencing were completed in 1971. Based on the observation of aerial photographs, the paved area was initially used as a parking lot. Currently, the paved area is used by Habitat for Humanity to store home improvement construction materials that are for sale. Work crews were actively clearing these lots during the consultant s site reconnaissance for the Phase I ESA. The 1407 East 4th Street parcel is a vacant lot mostly covered with grassy vegetation that contained a basketball goal, lawn furniture, an older-model work truck, and a bird coop. This property appears to be used as a side yard for the house located at 1405 East 4th Street. A commercial laundry service previously existed at this adjoining property and several underground storage tanks were registered for fleet fuel storage.
Below Poverty Number:	1047
Below Poverty Percent:	29.03
Meidan Income:	1809
Meidan Income Number:	1520
Meidan Income Percent:	42.15
Vacant Housing Number:	156
Vacant Housing Percent:	9.72
Unemployed Number:	217
Unemployed Percent:	6.02

FINDS:
Registry ID: 110070057800

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3272 **E-Z STOP 2** **TX LPST** **U001240828**
WNW **1200 KRAMER LN STE 1** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78758** **TX HIST UST**
0.462 mi. **TX ED AQUIF**
2440 ft. **TX Financial Assurance**

Actual:
772 ft.

Focus Map:
3

LPST:

Name:	TEXAN MARKET 9
Address:	1200 KRAMER LN
City,State,Zip:	AUSTIN, TX 78758
Facility ID:	0004054
LPST Id:	102762

E-Z STOP 2 (Continued) **U001240828**

Facility Location:	1200 KRAMER LN
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	03/23/1992
Entered Date:	04/24/1992
Reported Date:	03/23/1992
Closure Date:	12/15/1995
Priority:	4.2 - NO GW IMPACT NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	The vertical extent of contamination has been defined and the assessment results document that groundwater is not affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	BILL LONGSHORE
Responsible Party Address:	1100 GATTIS SCHOOL RD STE 300C
Responsible Party City,St,Zip:	ROUND ROCK, TX 78664 7000
Responsible Party Telephone:	512/447-1193
Reported Date:	03/23/1992
Case Start Date:	12/15/1995
Reference Number:	RN102484243
Project Manager:	HWELCH

UST:

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 787584700
AI Number:	4054
Facility Type:	RETAIL
Facility Begin Date:	06/17/1986
Facility Status:	ACTIVE
Additional ID:	71751292002156
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78758
Contact Name/Title:	NAVROZ KARIMALI,OWNER
Contact Organization Name:	E-Z STOP 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5127199077
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	03/04/2021
Signature Name/Title On Earliest Reg Form:	NAVROZ KARIMALI,OWNER
Application Received Date On Earliest Reg Form:	03/08/2021
Signature Role On Earliest Reg Form:	OWNER
Signature Company On Earliest Reg Form:	Not reported

E-Z STOP 2 (Continued) **U001240828**

Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	110343642011172
Additional ID:	71751292002156
Ai Number:	4054
Operator CN:	CN603870148
Operator Name:	NAAIL INC
Operator Effective Begin Date:	05/01/2011
Operator Type:	CO
Operator Role:	Not reported
Contact Name:	/
Contact Organization Name:	Not reported
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	-
Contact Phone Country Code:	Not reported
Contact Phone Area Code:	Not reported
Contact Phone Number:	Not reported
Contact Phone Extension:	Not reported
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN603870130
Owner Last Name:	KARIMALI REALESTATE INVESTMENTS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	921342532011172
Additional ID:	71751292002156
AI Number:	4054
Owner Effective Begin Date:	05/01/2011
State Tax ID:	32018059793
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Self Certification:

Self Cert ID:	42762
Cert ID:	368789

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	03/22/2022
Signature Name/Title:	AL TAILOR REPRESENTATIVE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	351556
AI Number:	4054
Self Certification Date:	03/04/2021
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	334256
AI Number:	4054
Self Certification Date:	02/25/2020
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	318026

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	03/12/2019
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	301505
AI Number:	4054
Self Certification Date:	03/07/2018
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	284300
AI Number:	4054
Self Certification Date:	02/28/2017
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	267666

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	02/22/2016
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	250921
AI Number:	4054
Self Certification Date:	03/23/2015
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	233006
AI Number:	4054
Self Certification Date:	03/04/2014
Signature Name/Title:	NAUROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	42762
Cert ID:	18474

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	02/26/2013
Signature Name/Title:	NAUROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18473
AI Number:	4054
Self Certification Date:	03/05/2012
Signature Name/Title:	NAVROZ KARIMALI OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18472
AI Number:	4054
Self Certification Date:	05/23/2011
Signature Name/Title:	NAVROZ KARIMAIL OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18471

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	06/10/2010
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18470
AI Number:	4054
Self Certification Date:	05/24/2009
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18469
AI Number:	4054
Self Certification Date:	05/20/2008
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18468

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	06/06/2007
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18467
AI Number:	4054
Self Certification Date:	05/23/2006
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18466
AI Number:	4054
Self Certification Date:	05/08/2005
Signature Name/Title:	NAUSHAD PRASLA
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18465

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	06/28/2004
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18464
AI Number:	4054
Self Certification Date:	05/29/2003
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18463
AI Number:	4054
Self Certification Date:	06/11/2002
Signature Name/Title:	NAUSHAD PRASLA
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	42762
Cert ID:	18462

E-Z STOP 2 (Continued) **U001240828**

AI Number:	4054
Self Certification Date:	01/26/2001
Signature Name/Title:	NAUSHAD PRASLA OWNER
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	9868
Facility ID:	42762
Ai Number:	4054
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/26/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

E-Z STOP 2 (Continued) **U001240828**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	13622
UST ID:	9868
AI Number:	4054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

E-Z STOP 2 (Continued) **U001240828**

Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	9869
Facility ID:	42762
Ai Number:	4054
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/26/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

E-Z STOP 2 (Continued) **U001240828**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	2A
Tank Capacity:	8000
UST Comprt ID:	13623
UST ID:	9869
AI Number:	4054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

E-Z STOP 2 (Continued) **U001240828**

Install Date:	01/01/1984
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	9870
Facility ID:	42762
Ai Number:	4054
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/26/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

E-Z STOP 2 (Continued) **U001240828**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	04/29/1994

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	13624
UST ID:	9870
AI Number:	4054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	12/01/1995
Tank Registration Date:	12/10/1998
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	189091

E-Z STOP 2 (Continued) **U001240828**

Facility ID:	42762
Ai Number:	4054
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	Y
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	Y
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/17/1998

Compartment Records:

Tank ID:	1
Tank Capacity:	12000

E-Z STOP 2 (Continued) **U001240828**

UST Comprt ID:	13625
UST ID:	189091
AI Number:	4054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	12/01/1995

Install Date:	12/01/1995
Tank Registration Date:	12/10/1998
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	189092
Facility ID:	42762
Ai Number:	4054
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	12/01/1995
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

E-Z STOP 2 (Continued) **U001240828**

Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	Y
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	Y
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	Y
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	Y
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	Y
PCPMeth(Isolated Open Area/2nd Containment):	Y
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	11/17/1998

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	13626
UST ID:	189092
AI Number:	4054
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	Y

E-Z STOP 2 (Continued) **U001240828**

CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	Y
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	Y
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	Y
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	Y
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	Y
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	Y
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	Y
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	EXEMPT BY TCEQ RULE
Stage 1 Installation Date:	12/01/1995

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	26436
UST ID:	189092
NOC ID:	Not reported
AI Number:	4054
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000139
Company Name:	UNITED PUMP SUPPLY INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

E-Z STOP 2 (Continued) **U001240828**

Cont/Cons/Installer ID:	26435
UST ID:	189091
NOC ID:	Not reported
AI Number:	4054
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000139
Company Name:	UNITED PUMP SUPPLY INC
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	41604
UST ID:	189092
NOC ID:	Not reported
AI Number:	4054
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001896
Company Name:	Not reported
Representative Name:	RITCHIE ROGERS
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	41603
UST ID:	189091
NOC ID:	Not reported
AI Number:	4054
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP001896
Company Name:	Not reported
Representative Name:	RITCHIE ROGERS
Mailing Address (Delivery):	Not reported

E-Z STOP 2 (Continued) **U001240828**

Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	KARIMALI REALESTATE INVESTMENTS INC
Contact Mailing Address (Delivery):	1200 KRAMER LN STE 1
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78758 4700
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	42762
Additional ID:	71751292002156
Princ ID:	921342532011172
AI Number:	4054
Facility Name:	E-Z STOP 2
AR Number:	72254
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	NAVROZ KARIMALI/

HIST UST AUSTIN:

Name:	E-Z STOP #2
Address:	1200 KRAMER LN
City,State,Zip:	AUSTIN, TX
Id UST:	3181
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ED AQUIF:

Name:	E-Z STOP 2
Address:	1200 KRAMER LN
City,State,Zip:	AUSTIN, TX 78758
Permit Number:	11-96021403
Primary SIC Code:	Not reported
Primary NAICS Code:	Not reported
Regulated entity #:	RN102484243
Type Of Project:	UNDERGROUND STORAGE TANK FACILITY PLAN
Receive Date:	02/14/1996
General Location:	Not reported

E-Z STOP 2 (Continued) **U001240828**

Mailing Address:	Not reported
Mailing Address2:	Not reported
Mailing City,St,Zip:	Not reported
Lat/Long:	0.0000 / 0.0000
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Application Phone:	Not reported
Region:	REGION 11 - AUSTIN
Status Code:	ACTIVE
LGL Status Code:	APPROVED

TX Financial Assurance 2:

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	266443
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2021
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	0 918 5877221
Policy Number:	04-TOP-000019981
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2022
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	247527
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2020

E-Z STOP 2 (Continued) **U001240828**

Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000010972
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2021
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	229174
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2019
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-top-000002665
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2020
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	211695
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2018
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000106744
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2019
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

E-Z STOP 2 (Continued) **U001240828**

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	194713
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2017
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-000101710
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	177225
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2016
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00097248
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	159400
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

E-Z STOP 2 (Continued) **U001240828**

Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2015
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	800 722 4994
Policy Number:	04-TO-00093044
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	141897
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2014
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TO00088972
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	124030
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	1,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2013
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994

E-Z STOP 2 (Continued) **U001240828**

Policy Number:	04TO00084866
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2014
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	922
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	06/14/2012
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TO-00080982
Coverage Amount:	1,000,000
Coverage Expiration Date:	06/14/2013
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	23268
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/08/2010
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688925-03
Coverage Amount:	1000000
Coverage Expiration Date:	02/08/2011
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758

E-Z STOP 2 (Continued) **U001240828**

Region:	2
Facility ID:	42762
Finass ID:	23269
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/08/2009
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688925-02
Coverage Amount:	1000000
Coverage Expiration Date:	02/08/2010
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	No

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	23271
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/08/2008
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688925-01
Coverage Amount:	1000000
Coverage Expiration Date:	02/08/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	23270
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

E-Z STOP 2 (Continued) **U001240828**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	02/08/2008
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	COLONY INS CO
Issuer Phone:	1 800 5776614
Policy Number:	PP688925-01
Coverage Amount:	1000000
Coverage Expiration Date:	02/08/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

Name:	E-Z STOP 2
Address:	1200 KRAMER LN STE 1
City,State,Zip:	AUSTIN, TX 78758
Region:	2
Facility ID:	42762
Finass ID:	23272
AI:	4054
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1901
Date Financial Assurance Form Rec:	03/08/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

UE3273 **B R CAPPS TEXACO** **TX LPST** **U001259197**
North **520 BASTROP HWY N** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78741** **TX HIST UST**
0.463 mi.
2444 ft. **Site 1 of 2 in cluster UE**

Actual:
479 ft.

Focus Map:
15

LPST:

Name:	CAPPS B R TEXACO STATION
Address:	520 BASTROP HWY N
City,State,Zip:	AUSTIN, TX 78741
Facility ID:	0025063
LPST Id:	100595
Facility Location:	520 BASTROP HWY SAME AS E HWY 183
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	10/22/1991
Entered Date:	11/05/1991
Reported Date:	10/22/1991
Closure Date:	04/19/2000
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED

B R CAPPS TEXACO (Continued) **U001259197**

Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1/2
Coordinators RPR:	EBF
Responsible Party Name:	Not reported
Responsible Party Contact:	BILLY CAPPS
Responsible Party Address:	520 BASTROP HWY
Responsible Party City,St,Zip:	AUSTIN, TX 78741
Responsible Party Telephone:	512/385-9057
Reported Date:	10/22/1991
Case Start Date:	04/19/2000
Reference Number:	RN102436201
Project Manager:	EBF

UST:

Name:	B R CAPPS TEXACO
Address:	520 BASTROP HWY N
City,State,Zip:	AUSTIN, TX 787413653
AI Number:	25063
Facility Type:	RETAIL
Facility Begin Date:	10/07/1986
Facility Status:	INACTIVE
Additional ID:	576022542002153
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78741
Contact Name/Title:	B R CAPPS,OWNER
Contact Organization Name:	B R CAPPS TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123859057
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/14/1986
Signature Name/Title On Earliest Reg Form:	B R CAPPS,OWNER
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN601258205
Owner Last Name:	B R CAPPS TEXACO
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported

B R CAPPS TEXACO (Continued) **U001259197**

Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	585022532002153
Additional ID:	576022542002153
AI Number:	25063
Owner Effective Begin Date:	10/07/1986
State Tax ID:	17412677035
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64514
Facility ID:	61765
Ai Number:	25063
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N

B R CAPPS TEXACO (Continued) **U001259197**

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	76717
UST ID:	64514
AI Number:	25063
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N

B R CAPPS TEXACO (Continued) **U001259197**

SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64516
Facility ID:	61765
Ai Number:	25063
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N

B R CAPPS TEXACO (Continued) **U001259197**

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	76719
UST ID:	64516
AI Number:	25063
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported

B R CAPPS TEXACO (Continued) **U001259197**

Stage 1 Installation Date:	Not reported
Install Date:	01/01/1963
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	64515
Facility ID:	61765
Ai Number:	25063
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	04/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N

B R CAPPS TEXACO (Continued) **U001259197**

Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	10/09/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	76718
UST ID:	64515
AI Number:	25063
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	B R CAPPS TEXACO
Contact Mailing Address (Delivery):	520 BASTROP HWY N
Contact Mailing Address (Internal Delivery):	Not reported

B R CAPPS TEXACO (Continued) **U001259197**

Contact Mailing City/State/Zip:	AUSTIN, TX 78741 3653
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	61765
Additional ID:	576022542002153
Princ ID:	585022532002153
AI Number:	25063
Facility Name:	B R CAPPS TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	KILLGORE & CAPPS
Address:	520 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Id UST:	C0390
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

UE3274 **FORMER CAPPS TEXACO** **TX RDR** **S127528005**
North **520 BASTROP HWY** **N/A**
1/4-1/2 **AUSTIN, TX**
0.463 mi.
2444 ft. **Site 2 of 2 in cluster UE**

Actual:
479 ft.

Focus Map:
15

RDR:

RDR ID:	14791
Facility ID:	25063
RN:	Not reported
CN:	Not reported
Name:	FORMER CAPPS TEXACO
Address:	520 BASTROP HWY
City,State,Zip:	AUSTIN, TX
Date Report Received:	9/6/2005
Due Date:	11/5/2005
Tank Owner:	TXDOT
Contact Person:	RANDALL POTTS
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/24/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	100595
Comments:	6A REOPEN OR NEW LPST#?
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	10/24/2005

FORMER CAPPS TEXACO (Continued) **S127528005**

Date Report Returned: Not reported
Region: Not reported
DKC RDR (misfiled): Not reported

UF3275 **BERGSTROM 1** **TX CLI** **S119135260**
SW **NORTH END OF FORMER BERGSTROM AFB** **N/A**
1/4-1/2 **TRAVIS (County), TX**
0.465 mi.
2455 ft. **Site 1 of 3 in cluster UF**

Actual:
534 ft.

Focus Map:
20

CAPCOG LI:

Name:	BERGSTROM 1
Address:	NORTH END OF FORMER BERGSTROM AFB
City,State,Zip:	TX
Type Facility:	Not reported
Site Status:	Not reported
Date Open:	1943
Date Close:	1946
Unum:	2581
Near City:	Not reported
Latitude Deg:	30
Latitude Min:	12.83
Longitude Deg:	97
Longitude Min:	40.560000000000002
Lat Dd:	30.213833000000001
Long Dd:	-97.676000000000002
Accuracy:	Not reported
Date Rec:	Not reported
County Cd:	Not reported
Region Cd:	Not reported
Etj1:	Not reported
Amendment:	Not reported
Source:	5
App Name:	Not reported
App Addres:	Not reported
App City:	Not reported
App State:	Not reported
App Zip:	Not reported
App Areacd:	Not reported
App Phone:	Not reported
Per Status:	Not reported
Orig Acres:	Not reported
Pop Served:	Not reported
Area Serve:	Not reported
Tons Day:	Not reported
Yds Day:	Not reported
Est Cl Dt:	Not reported
River Cd:	Not reported
Bus Cd:	Not reported
Owner Name:	City of Austin
Owner Add:	Not reported
Owner City/State/Zip:	Not reported
Stat Rem:	Not reported
Resp Eng:	Not reported
Stat date:	Not reported
A Open Dat:	Not reported
A Close Da:	Not reported
Update:	8

BERGSTROM 1 (Continued) **S119135260**

Reviewer1:	Not reported
Confidence:	GENERAL DESRCIPTION
Cog1:	12
Twc Dist:	0
Size Acres:	2
Size Cuyds:	Not reported
Parties1:	Not reported
Household:	Y
Const Demo:	Not reported
Industrial1:	Not reported
Tires1:	Not reported
Agriculture:	Y
Brush:	Not reported
Other:	Not reported
Other Des:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	N
Unauthor:	Not reported
Max Depth:	0
Depth Cd:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Inspection:	Not reported
Comment:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES
Latitude:	30.21378333
Longitude:	-97.67598333
PDF:	https://www.capcog.org/wp-content/uploads/2019/11/Travis-County-CLI-Complete_Part2.pdf#page=319

UF3276 **BERGSTROM 1** **TX CLI** **S103259019**
SW **SITE ON N END OF BASE IN APRON E. AREA.** **N/A**
1/4-1/2 **, TX**
0.465 mi.
2455 ft. **Site 2 of 3 in cluster UF**

Actual:
534 ft.

Focus Map:
20

CLI:

Name:	BERGSTROM 1
Address:	SITE ON N END OF BASE IN APRON E. AREA.
City,State,Zip:	TX
Facility ID:	Not reported
Facility Name2:	MILITARY
Site Status:	Not reported
Date Recieved:	Not reported
County:	Not reported
Region:	Not reported
Near City:	Not reported
Organic Acres:	Not reported
Area Served:	Not reported
Population Srvd:	Not reported
Tons per Day:	Not reported
Yards per Day:	Not reported
Permit Status:	Not reported
Removal Status:	Not reported
Status Date:	Not reported

BERGSTROM 1 (Continued) **S103259019**

Engineer:	Not reported
Source:	5
Source Code:	Not reported
Date Opened:	1943
Date Closed:	1946
Size - Acres:	Not reported
Size - Cubic Yrds:	Not reported
Lat Deg:	30
Lat Min:	12.83
Long Deg:	97
Long Min:	40.56
Lat/Long (deg):	30.213833 / -97.676000
Owner:	MILITARY
Owner Address:	Not reported
Owner C,S,Z:	Not reported
Business Type:	Not reported
Facility Type:	Not reported
Version of Amendment:	Not reported
Extra Territorial Jurisdiction:	Not reported
Applicant Name:	Not reported
Applicant Address:	Not reported
Applicant City,St,Zip:	Not reported
Applicant Phone:	Not reported
Est Cleanup Date:	Not reported
River Basin Code:	Not reported
Earliest Date in the Records:	Not reported
Last Date in Records Site Accepted Waste:	Not reported
Texas Counsil of Government Code:	12
Texas Water Commision District Code:	**********
Code for Landfill:	2
Parties:	Not reported
Accepts House Hold:	Yes
Accepts Construction Demolition:	Not reported
Accepts Industrial Waste:	Not reported
Accepts Tires:	Not reported
Accepts Agriculture:	Yes
Accepts Brush:	Not reported
Accepts Other:	Not reported
Accepts Other Description:	Not reported
Haz Waste Unlikey:	Not reported
Haz Waste Probably:	Not reported
Haz Waste Likey:	Yes
Legal:	No
Maximum Depth:	**********
Depth Code:	Not reported
Final Cover Has Been Applied:	Not reported
Minimun Thickness of Final Cover:	Not reported
In Use Inspector:	Not reported
Inspc Comments:	Not reported
Comments:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES
Update:	8
Reviewer:	Not reported
Flag:	Not reported

UF3277 **BERGSTROM 1** **TX HIST LF** **S129374122**
SW **SITE ON N END OF BASE IN APRON E. AREA.** **N/A**
1/4-1/2 **TRAVIS (County), TX**
0.465 mi.
2455 ft. **Site 3 of 3 in cluster UF**

Actual:
534 ft.

Focus Map:
20

HIST LF:

Name:	BERGSTROM 1
Name 2:	MILITARY
Address:	SITE ON N END OF BASE IN APRON E. AREA.
City,State,Zip:	TX
Latitude:	30.213833
Longitude:	-97.676000
Lat Deg:	30
Lat MM:	12.83
Lon DD:	97
Lon MM:	40.56
UNUM:	2581
Comments:	CONTAINS DOMESTIC AND INDUSTRIAL SHOP WASTES. WASTES WERE BURNED AND BURIED IN TRENCHES
Inspection:	Not reported
COG Number:	12
COOR CD:	Not reported
TWC District:	Not reported
Owner Name:	MILITARY
Owner Code:	Not reported
Open Date:	1943
Close Date:	1946
Acres:	2
Yards:	0
Parties:	Not reported
Household:	Y
Construct Demo:	Not reported
Industrial:	Not reported
Tires:	Not reported
Agriculture:	Y
Brush:	Not reported
Other:	Not reported
Other Description:	Not reported
Haz Unlike:	Not reported
Haz Prob:	Not reported
Haz Cert:	Y
Legal:	N
Un-Author:	Not reported
Max Depth:	Not reported
Depth Code:	Not reported
Final Cov:	Not reported
Min Thick:	Not reported
Use:	Not reported
Update:	Military Data
Reviewer:	Not reported
Accuracy:	Geocoded at Southwest Texas State University (SWTSU) from good location information, high confidence level
Source:	5

UB3278 **907 JUNIPER ST (11TH STREET 900 BLK)** **US BROWNFIELDS** **1016347355**
NE **907 JUNIPER ST** **FINDS** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.466 mi.
2459 ft. **Site 7 of 9 in cluster UB**

Actual:
510 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	907 JUNIPER ST (11TH STREET 900 BLK)
Address:	907 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197212, 02080616050000
Parcel size:	0.12
Latitude:	30.2703
Longitude:	-97.730525
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 907 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46641
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

907 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347355**

IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720
Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7
Name:	907 JUNIPER ST (11TH STREET 900 BLK)
Address:	907 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197212, 02080616050000
Parcel size:	0.12
Latitude:	30.2703
Longitude:	-97.730525
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 907 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46641
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported

907 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347355**

Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	Y
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.12
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	N
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720

907 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347355**

Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7

FINDS:
Registry ID: 110038721014

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3279 ESE 1/4-1/2 0.468 mi. 2469 ft. | **EXXON RS 67897**
1104 EAST AVE
AUSTIN, TX 78701 | **TX LPST** **U001260135**
TX UST **N/A**

Actual: 521 ft.

Focus Map: 11

LPST:

Name:	EXXON STATION 67897
Address:	1104 EAST AVE
City,State,Zip:	AUSTIN, TX 78701
Facility ID:	0026131
LPST Id:	094253
Facility Location:	1104 EAST AVE
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/21/1989
Entered Date:	01/09/1990
Reported Date:	11/21/1989
Closure Date:	08/02/1993
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	SL
Responsible Party Name:	Not reported
Responsible Party Contact:	ERNIE VILLASENOR
Responsible Party Address:	PO BOX 2180
Responsible Party City,St,Zip:	HOUSTON, TX 77252 2180
Responsible Party Telephone:	713/656-7701
Reported Date:	11/21/1989
Case Start Date:	08/02/1993
Reference Number:	RN100714864
Project Manager:	SL

UST:

Name:	EXXON RS 67897
Address:	1104 EAST AVE

EXXON RS 67897 (Continued) **U001260135**

City,State,Zip:	AUSTIN, TX 787010004
AI Number:	26131
Facility Type:	RETAIL
Facility Begin Date:	10/06/1986
Facility Status:	INACTIVE
Additional ID:	968648042002175
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78701
Contact Name/Title:	,
Contact Organization Name:	EXXON RS 67897
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9725793680
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/30/1986
Signature Name/Title On Earliest Reg Form:	R N ATHERTON,E SUPV
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN602941379
Owner Last Name:	JOHANNA LOUETTA SMITH TRUST
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	833588842005319
Additional ID:	968648042002175
AI Number:	26131
Owner Effective Begin Date:	10/26/1998
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

EXXON RS 67897 (Continued) **U001260135**

Tank:

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67384
Facility ID:	47996
Ai Number:	26131
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y

EXXON RS 67897 (Continued) **U001260135**

Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	36660
UST ID:	67384
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported

EXXON RS 67897 (Continued) **U001260135**

UST ID:	67385
Facility ID:	47996
Ai Number:	26131
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4

EXXON RS 67897 (Continued) **U001260135**

Tank Capacity:	1000
UST Comprt ID:	36661
UST ID:	67385
AI Number:	26131
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67386
Facility ID:	47996
Ai Number:	26131
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1989
Empty:	N
Tank Regulatory Status:	FULLY REGULATED

EXXON RS 67897 (Continued) **U001260135**

Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	6000
UST Comprt ID:	36662
UST ID:	67386
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported

EXXON RS 67897 (Continued) **U001260135**

CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	11/29/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	67391
Facility ID:	47996
Ai Number:	26131
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

EXXON RS 67897 (Continued) **U001260135**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3A
Tank Capacity:	12000
UST Comprt ID:	36667
UST ID:	67391
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N

EXXON RS 67897 (Continued) **U001260135**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	11/29/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	67388
Facility ID:	47996
Ai Number:	26131
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N

EXXON RS 67897 (Continued) **U001260135**

Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2A
Tank Capacity:	12000
UST Comprt ID:	36664
UST ID:	67388
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y

EXXON RS 67897 (Continued) **U001260135**

PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	11/29/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	67389
Facility ID:	47996
Ai Number:	26131
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N

EXXON RS 67897 (Continued) **U001260135**

TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	12000
UST Comprt ID:	36665
UST ID:	67389
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N

EXXON RS 67897 (Continued) **U001260135**

Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	11/29/1989
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	Not reported
UST ID:	67390
Facility ID:	47996
Ai Number:	26131
Tank Id:	4A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N

EXXON RS 67897 (Continued) **U001260135**

Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4A
Tank Capacity:	1000
UST Comprt ID:	36666
UST ID:	67390
AI Number:	26131
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	Y
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

EXXON RS 67897 (Continued) **U001260135**

Install Date:	01/01/1966
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67387
Facility ID:	47996
Ai Number:	26131
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	05/22/1998
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

EXXON RS 67897 (Continued) **U001260135**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	36663
UST ID:	67387
AI Number:	26131
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	JOHANNA LOUETTA SMITH TRUST
Contact Mailing Address (Delivery):	PO BOX 47531
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	SAN ANTONIO, TX 78265 7531
Phone Number/Ext:	/
Contact Fax Number/Ext:	/

EXXON RS 67897 (Continued) **U001260135**

Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	47996
Additional ID:	968648042002175
Princ ID:	833588842005319
AI Number:	26131
Facility Name:	EXXON RS 67897
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	KYLE GUBERNATOR/

3280 WNW 1/4-1/2 0.468 mi. 2469 ft. **TEXACO** **5600 S 1ST ST** **AUSTIN, TX 78745** **TX LPST** **TX UST** **TX HIST UST** **TX ASBESTOS** **U003566277** **N/A**

Actual: 644 ft.

Focus Map: 17

LPST:

Name:	TEXACO
Address:	5600 S 1ST ST
City,State,Zip:	AUSTIN, TX 78745
Facility ID:	0023197
LPST Id:	105337
Facility Location:	5600 S 1ST ST
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	11/12/1992
Entered Date:	01/11/1993
Reported Date:	11/12/1992
Closure Date:	03/16/1993
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	C S SCOTT
Responsible Party Address:	PO BOX 152045
Responsible Party City,St,Zip:	IRVING, TX 75015
Responsible Party Telephone:	214/650-0200
Reported Date:	11/12/1992
Case Start Date:	03/16/1993
Reference Number:	RN102793460
Project Manager:	HWELCH

UST:

Name:	TEXACO
Address:	5600 S 1ST ST
City,State,Zip:	AUSTIN, TX 787453108
AI Number:	23197
Facility Type:	RETAIL
Facility Begin Date:	09/24/1986
Facility Status:	INACTIVE

TEXACO (Continued) **U003566277**

Additional ID:	259668142002207
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78745
Contact Name/Title:	J C HILBIG,RETAILER
Contact Organization Name:	TEXACO
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124474959
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/16/1986
Signature Name/Title On Earliest Reg Form:	ROGER EBERT,DIV MGR
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600124051
Owner Last Name:	MOTIVA ENTERPRISES LLC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	504380502001134
Additional ID:	259668142002207
AI Number:	23197
Owner Effective Begin Date:	09/24/1986
State Tax ID:	17602624904
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1

TEXACO (Continued) **U003566277**

Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59688
Facility ID:	79648
Ai Number:	23197
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N

TEXACO (Continued) **U003566277**

Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	8000
UST Comprt ID:	123098
UST ID:	59688
AI Number:	23197
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	550
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59691
Facility ID:	79648
Ai Number:	23197
Tank Id:	4

TEXACO (Continued) **U003566277**

Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	550
UST Comprt ID:	123101
UST ID:	59691
AI Number:	23197

TEXACO (Continued) **U003566277**

Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59690
Facility ID:	79648
Ai Number:	23197
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N

TEXACO (Continued) **U003566277**

Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	8000
UST Comprt ID:	123100
UST ID:	59690
AI Number:	23197
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N

TEXACO (Continued) **U003566277**

CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1972
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	59689
Facility ID:	79648
Ai Number:	23197
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	11/30/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N

TEXACO (Continued) **U003566277**

Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	06/12/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	8000
UST Comprt ID:	123099
UST ID:	59689
AI Number:	23197
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N

TEXACO (Continued) **U003566277**

PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	MOTIVA ENTERPRISES LLC
Contact Mailing Address (Delivery):	PO BOX 22087
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	GREENSBORO, NC 27420 2087
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79648
Additional ID:	259668142002207
Princ ID:	504380502001134
AI Number:	23197
Facility Name:	TEXACO
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	TEXACO
Address:	5600 S 1ST ST
City,State,Zip:	AUSTIN, TX
Id UST:	C0364
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	WALGREENS
Address:	5600 S 1ST ST
City,State,Zip:	AUSTIN, TX 78745

TEXACO (Continued) **U003566277**

Date of inspection:	02/08/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	05
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	02/11/2013
Date Routed by Supervisor:	02/11/2013
Date Routed to PSQA:	02/11/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported

TEXACO (Continued) **U003566277**

Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	WALGREENS
Address:	5600 S 1ST ST
City,State,Zip:	AUSTIN, TX 78745
Date of inspection:	02/28/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0.1
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2014
Date Routed by Supervisor:	03/04/2014
Date Routed to PSQA:	03/05/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

TEXACO (Continued) **U003566277**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

UB3281 **909 JUNIPER ST (11TH STREET 900 BLK)** **US BROWNFIELDS FINDS** **1016347356**
NE **909 JUNIPER ST** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.470 mi.
2479 ft. **Site 8 of 9 in cluster UB**

Actual:
512 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	909 JUNIPER ST (11TH STREET 900 BLK)
Address:	909 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197213, 02080616060000
Parcel size:	0.06
Latitude:	30.270272
Longitude:	-97.730444
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 909 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46661
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9

909 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347356**

Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.06
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720
Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7

909 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347356**

Name:	909 JUNIPER ST (11TH STREET 900 BLK)
Address:	909 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197213, 02080616060000
Parcel size:	0.06
Latitude:	30.270272
Longitude:	-97.730444
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 909 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46661
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

909 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347356**

Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.06
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	464
Below Poverty Percent:	18.26
Meidan Income:	8222
Meidan Income Number:	720
Meidan Income Percent:	28.34
Vacant Housing Number:	196
Vacant Housing Percent:	14.25
Unemployed Number:	94
Unemployed Percent:	3.7

FINDS:
Registry ID: 110038721023

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UB3282 **911 JUNIPER ST (11TH STREET 900 BLK)** **US BROWNFIELDS** **1016347357**
NE **911 JUNIPER ST** **FINDS** **N/A**
1/4-1/2 **AUSTIN, TX 78702**
0.472 mi.
2493 ft. **Site 9 of 9 in cluster UB**

Actual:
513 ft.

Focus Map:
11

US BROWNFIELDS:

Name:	911 JUNIPER ST (11TH STREET 900 BLK)
Address:	911 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197214, 02080616070000
Parcel size:	0.06
Latitude:	30.270239
Longitude:	-97.730328
HCM Label:	Address Matching-Primary Name

911 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347357**

Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 911 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46662
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.06
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported

911 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347357**

Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	473
Below Poverty Percent:	18.19
Meidan Income:	8222
Meidan Income Number:	742
Meidan Income Percent:	28.53
Vacant Housing Number:	200
Vacant Housing Percent:	14.21
Unemployed Number:	94
Unemployed Percent:	3.61

Name:	911 JUNIPER ST (11TH STREET 900 BLK)
Address:	911 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197214, 02080616070000
Parcel size:	0.06
Latitude:	30.270239
Longitude:	-97.730328
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 911 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46662
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N

911 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347357**

Cooperative Agreement Number:	98609301
Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals PAHs
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	0.06
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	473
Below Poverty Percent:	18.19
Meidan Income:	8222
Meidan Income Number:	742
Meidan Income Percent:	28.53
Vacant Housing Number:	200
Vacant Housing Percent:	14.21
Unemployed Number:	94
Unemployed Percent:	3.61

FINDS:
Registry ID: 110038721032

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

911 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347357**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3283 WNW 1/4-1/2 0.477 mi. 2520 ft. **FORMER MUFFIN MUFFLER SHOP 4818 BURNET RD AUSTIN, TX** **TX RDR** **S127542511 N/A**

Actual: 680 ft.

Focus Map: 8

RDR:

RDR ID:	14743
Facility ID:	0
RN:	Not reported
CN:	Not reported
Name:	FORMER MUFFIN MUFFLER SHOP
Address:	4818 BURNET RD
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/22/2005
Due Date:	10/21/2005
Tank Owner:	WILDER PROPERTIES
Contact Person:	DIANE HOWARD
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	10/17/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	10/17/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

3284 ENE 1/4-1/2 0.479 mi. 2527 ft. **913 JUNIPER ST (11TH STREET 900 BLK) 913 JUNIPER ST AUSTIN, TX 78702** **US BROWNFIELDS FINDS** **1016347358 N/A**

Actual: 517 ft.

Focus Map: 11

US BROWNFIELDS:

Name:	913 JUNIPER ST (11TH STREET 900 BLK)
Address:	913 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197215, 02080616080000
Parcel size:	0.48
Latitude:	30.269951
Longitude:	-97.730251
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported

913 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347358**

Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 913 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	4741.25
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase II Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301
Start Date:	2/1/2004
Ownership Entity:	Government
Completion Date:	4/1/2004
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.48
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported

913 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347358**

Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	477
Below Poverty Percent:	18.12
Meidan Income:	8222
Meidan Income Number:	749
Meidan Income Percent:	28.46
Vacant Housing Number:	201
Vacant Housing Percent:	14.14
Unemployed Number:	96
Unemployed Percent:	3.65

Name:	913 JUNIPER ST (11TH STREET 900 BLK)
Address:	913 JUNIPER ST
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	197215, 02080616080000
Parcel size:	0.48
Latitude:	30.269951
Longitude:	-97.730251
HCM Label:	Address Matching-Primary Name
Map Scale:	Not reported
Point of Reference:	Other Point
Highlights:	Target sites for redevelopment mixed-use project by the City of Austin through the Urban Renewal Agency. property is a corner commercial lot. Web site: http://www.austinrev.org (PPF- 913 Juniper St (900 BLK), 3/28/07) Former Use: Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Datum:	North American Datum of 1983
Acres Property ID:	46663
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	1066.9
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	98609301

913 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347358**

Start Date:	1/10/2003
Ownership Entity:	Government
Completion Date:	1/11/2003
Current Owner:	City of Austin, Urban Renewal Agency
Did Owner Change:	N
Cleanup Required:	N
Video Available:	N
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	N
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Lead Other Contaminants Other Metals
Contaminant Cleanup:	Not reported
Media Affected:	Soil Surface Water
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	0.48
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Several properties are combined in this assessment area. Sites are currently targeted for mixed use project by the City of Austin through the Urban Renewal Agency
Below Poverty Number:	477
Below Poverty Percent:	18.12
Meidan Income:	8222
Meidan Income Number:	749
Meidan Income Percent:	28.46
Vacant Housing Number:	201
Vacant Housing Percent:	14.14
Unemployed Number:	96
Unemployed Percent:	3.65

FINDS:

Registry ID: 110038721041

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

913 JUNIPER ST (11TH STREET 900 BLK) (Continued) **1016347358**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3285 NNE 1/4-1/2 0.480 mi. 2532 ft. | **6301 CIRCULO DE AMISTAD**
6301 CIRCULO DE AMISTAD
AUSTIN, TX 78741 | **US BROWNFIELDS** | **1026109926**
N/A

Actual: 490 ft.

Focus Map: 15

US BROWNFIELDS:

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2750.46
Assessment Funding Source:	City of Austin/ABRO
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Local Funding
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601
Start Date:	1/30/2020
Ownership Entity:	Private
Completion Date:	4/2/2020
Current Owner:	Not reported
Did Owner Change:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.

Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95
Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	2750.45
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F37601

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Start Date:	1/30/2020
Ownership Entity:	Private
Completion Date:	4/2/2020
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

Name:	6301 CIRCULO DE AMISTAD
Address:	6301 CIRCULO DE AMISTAD
Recipient name:	Austin, City of
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	0.68
Latitude:	30.23456896
Longitude:	-97.69722918
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The property, located near the Montopolis Recreation Center, was purchased by Austin Habitat for Humanity (AHFH) and developed into an affordable housing neighborhood serving families making 80% of the area median income. A larger L-shaped portion of the property currently has single family homes built by by AHFH. Each of the 24 homes were sold to the individual families to assist persons with barriers to home ownership. This .68 acre parcel, which is currently vacant, will have 6 duplexes (12 total units) built using City of Austin 2018 Affordable Housing bond funding. The duplexes will eventually be sold to families earning 80% of the area median income.
Datum:	Not reported
Acres Property ID:	242586
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported

6301 CIRCULO DE AMISTAD (Continued) **1026109926**

Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Petroleum
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F37601
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	N
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	No Contaminants
Contaminant Cleanup:	Not reported
Media Affected:	Other Media
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	0.68
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	2278
Below Poverty Percent:	52.26
Meidan Income:	3568
Meidan Income Number:	3304
Meidan Income Percent:	75.8
Vacant Housing Number:	133
Vacant Housing Percent:	9.09
Unemployed Number:	172
Unemployed Percent:	3.95

3286 WNW 1/4-1/2 0.480 mi. 2537 ft. | **STENGER TRACT 1406 N IH 35 AUSTIN, TX 78701** | **TX VCP** | **S123819947 N/A**

Actual: 662 ft.

Focus Map: 8

VCP TCEQ:

Name:	STENGER TRACT
Address:	1406 N IH 35
City,State,Zip:	AUSTIN, TX 78701
Region:	REGION 11 - AUSTIN
Facility ID:	2395
VCP Record Date:	03/09/2011
Facility Type:	PARKING/TRANSIT CENTER
PCA Number:	34588
Project Manager:	SSETTEME
Phase:	COMPLETED
Acres at Site:	0.6113
REM Program:	VCP
RN Number:	RN106104037
Former Facility Type:	Not reported
Site Address Description:	Not reported
Near City Name:	AUSTIN
Administrative Status:	INACTIVE
Region Notified of Application:	03/08/2011
RCRIS Number:	Not reported
Air REM Method:	Not reported
GW REM Method:	Not reported
EPA Texas ID/CERCLIS Registration:	Not reported
Soil REM Method:	Not reported
Surf Water REM Method:	Not reported
CCOC Date:	Not reported
Risk Reduction or Petroleum Storage Tank:	PST
Air Inst Eng Controls:	Not reported
TNRCC Solid Waste Registration:	Not reported
GW Inst Eng Controls:	Not reported
TX Risk Reduction Program:	Not reported
Sediment Inst Eng Controls:	Not reported
Soil Inst Eng Controls:	Not reported
Certificate of Completion Date:	09/25/2012
Standards:	Not reported
Surf Water Inst Eng Controls:	Not reported
Remedy Type:	Not reported
Air Target COC Class:	Not reported
Date Cashier Check Received:	03/08/2011
GW Target COC Class:	VOCS; METALS; TPH
Sediment Target COC Class:	Not reported
Application Accepted?:	Not reported
Application Accepted Date:	2011-04-13 00:00:00
Soil Target COC Class:	METALS; VOCS; TPH
Surface Water Target COC Class:	Not reported
Alternate VCP ID:	2395
Leaking Petroleum Storage Registration Tank:	Not reported
Project Number:	345880
Off Site?:	Not reported
Media:	PAPER
IOP Number:	Not reported
File Location:	D/200-12
Latitude:	30.16

STENGER TRACT (Continued) **S123819947**

Longitude: -97.44

3287 ESE 1/4-1/2 0.481 mi. 2541 ft. | **PERRY ROSE TIRE HIGHLAND MALL**
6401 AIRPORT BLVD
AUSTIN, TX 78752

TX LPST **U001256787**
TX UST **N/A**
TX HIST UST

Actual: 689 ft.

Focus Map: 9

LPST:

Name:	PERRY ROSE TIRE HIGHLAND MALL
Address:	6401 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0022276
LPST Id:	102170
Facility Location:	6401 AIRPORT
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	02/24/1992
Entered Date:	04/03/1992
Reported Date:	03/05/1992
Closure Date:	10/13/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	RPR
Responsible Party Name:	Not reported
Responsible Party Contact:	KATHLEEN SCHENTZON
Responsible Party Address:	1200 FIRESTONE PKWY
Responsible Party City,St,Zip:	AKRON, OH 44317
Responsible Party Telephone:	216/379-3737
Reported Date:	03/05/1992
Case Start Date:	10/13/1992
Reference Number:	RN101497279
Project Manager:	HWELCH

UST:

Name:	PERRY ROSE TIRE HIGHLAND MALL
Address:	6401 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX 787524215
AI Number:	22276
Facility Type:	OTHER
Facility Begin Date:	09/18/1986
Facility Status:	INACTIVE
Additional ID:	405727392002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78752
Contact Name/Title:	J F CASIMIN,PRES

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

Contact Organization Name:	PERRY ROSE TIRE HIGHLAND MALL
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124678017
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/25/1986
Signature Name/Title On Earliest Reg Form:	J F CASIMIN,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600784656
Owner Last Name:	PERRY ROSE HIGHLAND MALL INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	396727382002053
Additional ID:	405727392002053
AI Number:	22276
Owner Effective Begin Date:	09/18/1986
State Tax ID:	Not reported
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	500
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57059
Facility ID:	58901
Ai Number:	22276
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	01/30/1992
Empty:	N

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	500
UST Comprt ID:	64716
UST ID:	57059
AI Number:	22276
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57061
Facility ID:	58901
Ai Number:	22276
Tank Id:	1
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/31/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	Not reported
UST Comprt ID:	64718
UST ID:	57061
AI Number:	22276
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	57060
Facility ID:	58901
Ai Number:	22276
Tank Id:	2
Tank Status (Current):	PERM FILLED IN PLACE
Tank Status Date:	05/31/1982
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	10/26/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	Not reported
UST Comprt ID:	64717
UST ID:	57060
AI Number:	22276
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N

PERRY ROSE TIRE HIGHLAND MALL (Continued) **U001256787**

PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Facility Billing Contacts:

Contact Organization Name:	PERRY ROSE TIRE HIGHLAND MALL
Contact Mailing Address (Delivery):	6401 AIRPORT BLVD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78752 4215
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	58901
Additional ID:	405727392002053
Princ ID:	396727382002053
AI Number:	22276
Facility Name:	PERRY ROSE TIRE HIGHLAND MALL
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	/

HIST UST AUSTIN:

Name:	FIRESTONE MASTERCARE STORE
Address:	6401 AIRPORT BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	C0310
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

3288 ESE 1/4-1/2 0.483 mi. 2548 ft. | **INDOOR SMALL ARMS RANGE (BUILDING 1810) (SWMU 120)** | **UXO** | **1024717577** **N/A**

AUSTIN, TX

Actual: 486 ft.

Focus Map: 20

UXO:

DoD Component:	Air Force
Installation Name:	BERGSTROM
Name:	INDOOR SMALL ARMS RANGE (BUILDING 1810) (SWMU 120)
Address:	Not reported
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX
Site ID:	SR402
Site Type:	Small Arms Range
Latitude:	30.202740
Longitude:	-97.659044

3289 NNW 1/4-1/2 0.484 mi. 2555 ft. | **LESTER BROWN PHILLIPS 66** | **TX LPST** | **U001259441**
4500 BURNET RD | **TX UST** | **N/A**
AUSTIN, TX 78756 | **TX HIST UST**

Actual: 668 ft.

Focus Map: 8

LPST:

Name:	LESTER BROWN AUTOMOTIVE
Address:	4500 BURNET RD
City,State,Zip:	AUSTIN, TX 78756
Facility ID:	0025353
LPST Id:	103903
Facility Location:	4502 BURNET RD
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/26/1992
Entered Date:	01/26/1993
Reported Date:	06/26/1992
Closure Date:	01/26/1993
Priority:	4A - SOIL CONTAMINATION ONLY REQUIRES FULL SITE ASSESSMENT RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	JOE BAILEY
Responsible Party Address:	1905 HILL OAKS CT
Responsible Party City,St,Zip:	AUSTIN, TX 78703
Responsible Party Telephone:	512/266-1132
Reported Date:	06/26/1992
Case Start Date:	01/26/1993
Reference Number:	RN101492734
Project Manager:	HWELCH

UST:

Name:	LESTER BROWN PHILLIPS 66
Address:	4500 BURNET RD
City,State,Zip:	AUSTIN, TX 787563025
AI Number:	25353

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Facility Type:	UNKNOWN
Facility Begin Date:	10/08/1986
Facility Status:	INACTIVE
Additional ID:	495616912002053
Facility Exempt Status:	N
Records Off-Site:	No
UST Financial Assurance Required:	No
Number Of Active UST:	0
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78756
Contact Name/Title:	,
Contact Organization Name:	LESTER BROWN PHILLIPS 66
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5124597717
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported
Signature Date On Earliest Reg Form:	04/15/1986
Signature Name/Title On Earliest Reg Form:	R V MURRAY,PRES
Application Received Date On Earliest Reg Form:	05/08/1986
Signature Role On Earliest Reg Form:	Not reported
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	Not reported
Facility Not Inspectable:	No

Owner:

Owner CN:	CN600780977
Owner Last Name:	MURRAY JONES INVESTMENTS INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	OR
Contact Mailing Address (Delivery):	Not reported
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	Not reported
Contact Mailing State:	Not reported
Contact Mailing Zip:	Not reported
Contact Mailing Zip5:	Not reported
Contact Phone Number/Ext:	/
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	130612452002053
Additional ID:	495616912002053
AI Number:	25353
Owner Effective Begin Date:	10/08/1986
State Tax ID:	30116658714
Contact Role:	Not reported
Contact Name/Title:	/
Contact Organization Name:	Not reported

Tank:

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Install Date:	08/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	65135
Facility ID:	59647
Ai Number:	25353
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1
Tank Capacity:	3000
UST Comprt ID:	56920
UST ID:	65135
AI Number:	25353
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	65140

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Facility ID:	59647
Ai Number:	25353
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	3000

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

UST Comprt ID:	56925
UST ID:	65140
AI Number:	25353
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	65141
Facility ID:	59647
Ai Number:	25353
Tank Id:	7
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	7
Tank Capacity:	1000
UST Comprt ID:	56926
UST ID:	65141
AI Number:	25353
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	65139
Facility ID:	59647
Ai Number:	25353
Tank Id:	5
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	5
Tank Capacity:	1000
UST Comprt ID:	56924
UST ID:	65139
AI Number:	25353
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	65137
Facility ID:	59647
Ai Number:	25353
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2
Tank Capacity:	3000
UST Comprt ID:	56922
UST ID:	65137
AI Number:	25353
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/31/1987
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	65138
Facility ID:	59647
Ai Number:	25353
Tank Id:	6
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	Y
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	6
Tank Capacity:	1000
UST Comprt ID:	56923
UST ID:	65138
AI Number:	25353
Compartment ID:	A
Substance Stored1:	EMPTY
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	08/01/1971
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	S
UST ID:	65136
Facility ID:	59647
Ai Number:	25353
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1992
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	56921
UST ID:	65136
AI Number:	25353
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	N
SOPE(Spill Cont/Bucket/Sump):	N
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	N
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	N
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

LESTER BROWN PHILLIPS 66 (Continued) **U001259441**

Facility Billing Contacts:

Contact Organization Name:	MURRAY INVESTMENTS
Contact Mailing Address (Delivery):	14610 AGARITA RD
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78734 2008
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	59647
Additional ID:	495616912002053
Princ ID:	130612452002053
AI Number:	25353
Facility Name:	LESTER BROWN PHILLIPS 66
AR Number:	Not reported
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	Not reported
Contact Name/Title:	MARGARET BAILEY/

HIST UST AUSTIN:

Name:	LESTER BROWN AUTOMOTIVE
Address:	4500 BURNET RD
City,State,Zip:	AUSTIN, TX
Id UST:	C0334
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

UG3290 **EXXON MOBIL 67278** **TX LPST** **S102757843**
ESE **1320 E OLTORF ST** **TX ASBESTOS** **N/A**
1/4-1/2 **AUSTIN, TX 78704** **TX Ind. Haz Waste**
0.489 mi.
2583 ft. **Site 1 of 4 in cluster UG**

Actual:
627 ft.

Focus Map:
14

LPST:

Name:	EXXON 67278
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Facility ID:	0026115
LPST Id:	111245
Facility Location:	1320 E OLTORF @ IH 35
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	06/13/1996
Entered Date:	06/28/1996
Reported Date:	06/14/1996
Closure Date:	01/04/2001
Priority:	4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Groundwater is affected.
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	1
Coordinators RPR:	DMR
Responsible Party Name:	Not reported

EXXON MOBIL 67278 (Continued) **S102757843**

Responsible Party Contact:	DALE GOMM
Responsible Party Address:	PO BOX 4552
Responsible Party City,St,Zip:	HOUSTON, TX 77210 4552
Responsible Party Telephone:	713/656-9219
Reported Date:	06/14/1996
Case Start Date:	01/04/2001
Reference Number:	RN100535251
Project Manager:	DMR

ASBESTOS:

Name:	SPEEDY STOP
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	02/28/2013
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	3.8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/04/2013
Date Routed by Supervisor:	03/04/2013
Date Routed to PSQA:	03/05/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

EXXON MOBIL 67278 (Continued) **S102757843**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

Ind. Haz Waste:

Name:	EXXON MOBIL 67278
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Permit Number:	Not reported
Registration Number:	77158
Registration Initial Notification Date:	06/28/1991
Registration Last Amendment Date:	12/11/2013
EPA Identification:	TXD988031928
Primary NAICS Code:	424710
Status Change Date:	20140130
Land Type:	PRIVATE
Description of Facility Site Location:	1320 E Oltorf, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	EXXON MOBIL CORPORATION
Contact Name:	ALDA S POOL
Contact Telephone Number:	713-6567709
Mailing Address:	PO BOX 4415
Mailing Address2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 772104415
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES

EXXON MOBIL 67278 (Continued) **S102757843**

TNRCC Facility ID:	31466
Site Owner Tax ID:	135409005
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20191101
Ind. Waste Permit Number:	Not reported
Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Ind. Haz Waste:

Operator Name:	EXXON MOBIL CORPORATION
Operator Address:	PO BOX 4415
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	HOUSTON, TX 77210
Operator Country:	UNITED STA
Operator Telephone:	1-713-6567709
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Corporation
Operator Tax ID:	11354090059
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	EXXON MOBIL CORPORATION
Owner Mailing Address:	PO BOX 4415
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	HOUSTON, TX 77210
Owner Country:	UNITED STA
Owner Telephone:	1-713-6567709
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax ID:	11354090059
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Unit Number:	001
Unit Type Code:	14
Unit Status:	INACTIVE
Unit Regulatory Status:	UNKNOWN
UIC Permit Number:	Not reported
Capacity:	Not reported

EXXON MOBIL 67278 (Continued) **S102757843**

Capacity Measurement:	Not reported
Off Site Hazardous Waste:	Not reported
Off Site Class 1 Waste:	Not reported
Off Site Class 2 Waste:	Not reported
Off Site Class 3 Waste:	Not reported
Off Site Non Industrial Solid Waste:	Not reported
System Type Code 1:	Not reported
System Type Code 2:	Not reported
System Type Code 3:	Not reported
System Type Code 4:	Not reported
System Type Code:	Not reported
Permit Sequence Number:	Not reported
Unit Description:	Not reported
Unit Description 2:	Not reported
Unit Description 3:	Not reported
Last Changed Date:	20131211
Deed Record Needed:	Not reported
Deed Recording Date:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNOPRCON
Contact Address:	PO BOX 4415
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	ALDA POOL
Contact Title:	STAFF ASSISTANT
Contact Role:	PRICONT
Contact Address:	PO BOX 4415
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	HOUSTON, TX 77210
Contact Phone:	1-713-6567709
Contact Fax:	Not reported
Contact Email:	Not reported

UG3291 **7 ELEVEN STORE 36636** **TX RDR** **S127528353**
ESE **1320 E OLTORF ST** **N/A**
1/4-1/2 **AUSTIN, TX**
0.489 mi.
2583 ft. **Site 2 of 4 in cluster UG**

Actual:
627 ft.

Focus Map:
14

RDR:

RDR ID:	25218
Facility ID:	26115
RN:	Not reported
CN:	Not reported
Name:	7 ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX

7 ELEVEN STORE 36636 (Continued) **S127528353**

Date Report Received:	12/13/2017
Due Date:	2/11/2018
Tank Owner:	7 ELEVEN INC
Contact Person:	JOSE RIOS
Report:	RDR
Latest TCEQ Letter:	Deficiency
Date of Latest TCEQ Letter:	2/8/2018
Project Manager:	Stacey Dunahoo
Team:	Team A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UG3292 **7-ELEVEN INC STORE NO 36636** **TX RDR** **S127537074**
ESE **1320 E OLTORF STREET** **N/A**
1/4-1/2 **AUSTIN, TX**
0.489 mi.
2583 ft. **Site 3 of 4 in cluster UG**

Actual:
627 ft.

Focus Map:
14

RDR:

RDR ID:	28812
Facility ID:	6384
RN:	Not reported
CN:	Not reported
Name:	7-ELEVEN INC STORE NO 36636
Address:	1320 E OLTORF STREET
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/3/2020
Due Date:	8/28/2020
Tank Owner:	7-ELEVEN INC
Contact Person:	SHELLENA HUSSEIN
Report:	RDR/DWSR/RBA
Latest TCEQ Letter:	New LPST
Date of Latest TCEQ Letter:	8/28/2020
Project Manager:	Ryan Kraft
Team:	#N/A
New LPST Number:	121023
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UG3293 **7-ELEVEN STORE 36636** **TX LPST** **U003040354**
ESE **1320 E OLTORF ST** **TX UST** **N/A**
1/4-1/2 **AUSTIN, TX 78704** **TX HIST UST**
0.489 mi. **TX ASBESTOS**
2583 ft. **Site 4 of 4 in cluster UG** **TX Financial Assurance**
TX GCC
Actual: **TX CENTRAL REGISTRY**
627 ft.

Focus Map: **14**

LPST:

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Facility ID:	Not reported
LPST Id:	121023
Facility Location:	Not reported
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	Not reported
Discovered Date:	11/07/2017
Entered Date:	08/28/2020
Reported Date:	11/10/2017
Closure Date:	10/06/2021
Priority:	3.1 - GW IMPACT PUB/DOM WATER SUPPLY WELL W/IN .25 - .5MI
Program:	1 - RPR
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	Not reported
Status:	**Not reported**
Coordinators Primary:	Not reported
Coordinators RPR:	Not reported
Responsible Party Name:	Not reported
Responsible Party Contact:	Not reported
Responsible Party Address:	Not reported
Responsible Party City,St,Zip:	Not reported
Responsible Party Telephone:	Not reported
Reported Date:	11/10/2017
Case Start Date:	10/06/2021
Reference Number:	RN100535251
Project Manager:	RKRAFT

UST:

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 787045714
AI Number:	26115
Facility Type:	RETAIL
Facility Begin Date:	10/06/1986
Facility Status:	ACTIVE
Additional ID:	2595362002175
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	No
Number Of Active UST:	3
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	PEGGIE BETZ,ENV SPEC
Contact Organization Name:	7-ELEVEN STORE 36636
Contact Mailing Address1:	Not reported

7-ELEVEN STORE 36636 (Continued) **U003040354**

Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	9728287805
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	PEGGIE.BETZ@7-11.COM
Signature Date On Earliest Reg Form:	01/07/2019
Signature Name/Title On Earliest Reg Form:	RAYMOND MCNIECE,REG COMP MGR
Application Received Date On Earliest Reg Form:	01/11/2019
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	959578622001257
Additional ID:	2595362002175
Ai Number:	26115
Operator CN:	CN600240329
Operator Name:	7-ELEVEN INC
Operator Effective Begin Date:	12/28/2012
Operator Type:	CO
Operator Role:	OWNOPRCON
Contact Name:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS TX 75221-0711
Contact Phone Country Code:	1
Contact Phone Area Code:	210
Contact Phone Number:	5070913
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600240329
Owner Last Name:	7-ELEVEN INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	DALLAS
Contact Mailing State:	TX
Contact Mailing Zip:	75221
Contact Mailing Zip5:	0711
Contact Phone Number/Ext:	1 210 5070913/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Not reported
Princ ID:	959578622001257

7-ELEVEN STORE 36636 (Continued) **U003040354**

Additional ID:	2595362002175
AI Number:	26115
Owner Effective Begin Date:	12/28/2012
State Tax ID:	17510851318
Contact Role:	OWNOPRCON
Contact Name/Title:	RAY MCNIECE/REGION COMPLIANCE MANAGER
Contact Organization Name:	7-ELEVEN INC

Self Certification:

Self Cert ID:	47983
Cert ID:	381803
AI Number:	26115
Self Certification Date:	01/12/2023
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL COMPLIANCE MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2024
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	364483
AI Number:	26115
Self Certification Date:	01/18/2022
Signature Name/Title:	RAYMOND MCNIECE ENVIRONMENTAL MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2023
Reporting Method:	E
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	348472
AI Number:	26115
Self Certification Date:	01/20/2021
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2022
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	330785
AI Number:	26115
Self Certification Date:	01/09/2020
Signature Name/Title:	Raymond Mcniece Env.Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2021
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	314472
AI Number:	26115
Self Certification Date:	01/23/2019
Signature Name/Title:	Raymond Mcniece Env. Mgr.
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2020
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	295948
AI Number:	26115
Self Certification Date:	12/20/2017
Signature Name/Title:	Raymond Mcniece Env.Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2019
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	280730
AI Number:	26115
Self Certification Date:	01/19/2017
Signature Name/Title:	Raymond Mcniece Environmental Manage
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2018
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	263406
AI Number:	26115
Self Certification Date:	01/15/2016
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2017
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	247211
AI Number:	26115
Self Certification Date:	01/19/2015
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2016
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	230773
AI Number:	26115
Self Certification Date:	01/23/2014
Signature Name/Title:	Raymond Mcniece Environmental Mgr
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2015
Reporting Method:	S
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	47983
Cert ID:	34623
AI Number:	26115
Self Certification Date:	01/23/2013
Signature Name/Title:	RAYMOND MCNIECE GAS ENV COMP MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2014
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Self Cert ID:	47983
Cert ID:	34622
AI Number:	26115
Self Certification Date:	01/09/2012
Signature Name/Title:	CARLTON LABEFF
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	01/31/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34621
AI Number:	26115
Self Certification Date:	04/01/2011
Signature Name/Title:	TARONZA L GRAVES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34620
AI Number:	26115
Self Certification Date:	03/15/2010
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34619
AI Number:	26115
Self Certification Date:	03/27/2009
Signature Name/Title:	TARONZA L GRAVES AUTHORIZED AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34618
AI Number:	26115
Self Certification Date:	03/28/2008
Signature Name/Title:	JOEY WEISMAN OWNERS AUTH AGENT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34617
AI Number:	26115
Self Certification Date:	04/01/2007
Signature Name/Title:	HEATHER GILLMORE OWNER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34616
AI Number:	26115
Self Certification Date:	03/06/2006
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34615
AI Number:	26115
Self Certification Date:	03/15/2005
Signature Name/Title:	ERIC M MCPHEE PERMITTING MANAGER
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34614
AI Number:	26115
Self Certification Date:	03/12/2004
Signature Name/Title:	ERIC M. MCPHEE CMS PERMITTING MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34613
AI Number:	26115
Self Certification Date:	03/05/2003
Signature Name/Title:	ERIC M. MCPHEE PERMIT TEAM LEAD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34612
AI Number:	26115
Self Certification Date:	03/13/2002
Signature Name/Title:	WENDY SALAS
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	47983
Cert ID:	34611
AI Number:	26115
Self Certification Date:	11/17/2000
Signature Name/Title:	DAPHYNE JENKINS PROG MGR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	07/20/1999
Tank Registration Date:	03/16/2000
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	193784
Facility ID:	47983

7-ELEVEN STORE 36636 (Continued) **U003040354**

Ai Number:	26115
Tank Id:	3
Tank Status (Current):	IN USE
Tank Status Date:	07/20/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	Y
Technical Compliance Flag:	Y
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	3
Tank Capacity:	12000
UST Comprt ID:	36599

7-ELEVEN STORE 36636 (Continued) **U003040354**

UST ID:	193784
AI Number:	26115
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/20/1999

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	67308
Facility ID:	47983
Ai Number:	26115
Tank Id:	1A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	1A
Tank Capacity:	10000
UST Comprt ID:	36593
UST ID:	67308
AI Number:	26115
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	1000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67309
Facility ID:	47983
Ai Number:	26115
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y

7-ELEVEN STORE 36636 (Continued) **U003040354**

Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	4
Tank Capacity:	1000
UST Comprt ID:	36594
UST ID:	67309
AI Number:	26115
Compartment ID:	A
Substance Stored1:	USED OIL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/20/1999
Tank Registration Date:	03/16/2000
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	193783
Facility ID:	47983
Ai Number:	26115
Tank Id:	2
Tank Status (Current):	IN USE
Tank Status Date:	07/20/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	2
Tank Capacity:	12000
UST Comprt ID:	36598
UST ID:	193783
AI Number:	26115
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/20/1999

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	8000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67311
Facility ID:	47983
Ai Number:	26115
Tank Id:	2A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	2A
Tank Capacity:	8000
UST Comprt ID:	36596
UST ID:	67311
AI Number:	26115
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Install Date:	07/20/1999
Tank Registration Date:	03/16/2000
Number of Compartments:	1
Tank Capacity:	12000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	193782
Facility ID:	47983
Ai Number:	26115
Tank Id:	1
Tank Status (Current):	IN USE
Tank Status Date:	07/20/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	Y
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	1
Tank Capacity:	12000
UST Comprt ID:	36597
UST ID:	193782
AI Number:	26115
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	Y
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	TWO POINT SYSTEM
Stage 1 Installation Date:	07/20/1999

7-ELEVEN STORE 36636 (Continued) **U003040354**

Install Date:	01/01/1974
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	Not reported
UST ID:	67310
Facility ID:	47983
Ai Number:	26115
Tank Id:	3A
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	06/22/1999
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	Y
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	Y
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	02/01/1991

Compartment Records:

Tank ID:	3A
Tank Capacity:	6000
UST Comprt ID:	36595
UST ID:	67310
AI Number:	26115
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	Y
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	N
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

Construction Notification:

NOC ID:	32133
Facility ID:	47983
AI Number:	26115
Application Received Date:	11/07/2017
Scheduled Construction Date:	11/07/2017
UST Improvement:	N

7-ELEVEN STORE 36636 (Continued) **U003040354**

UST Installation:	N
UST Removal:	N
UST Repair:	Y
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	Not reported
Waiver Flag:	Not reported
Late Filing Flag:	Y
Form Received Date:	11/07/2017
Signature Date On Form:	11/06/2017
Signature Name On Form:	DARYELA SARABIA
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	7-ELEVEN INC
Owner CN At Time Of Construction:	CN600240329
Owner AR At Time Of Construction:	3971
General Desc Of Prop Construct:	MAKE REPAIRS TO UNL PRODUCT LINE AFTER LINE TESTING DID NOT PASS.

NOC ID:	3617
Facility ID:	47983
AI Number:	26115
Application Received Date:	01/12/2011
Scheduled Construction Date:	01/19/2011
UST Improvement:	Y
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	Y
Late Filing Flag:	N
Form Received Date:	11/07/2017
Signature Date On Form:	11/06/2017
Signature Name On Form:	DARYELA SARABIA
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	4194
General Desc Of Prop Construct:	MAKE REPAIR TO SUPER UNLEADED TANK.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	75930
UST ID:	Not reported
NOC ID:	32133
AI Number:	26115

7-ELEVEN STORE 36636 (Continued) **U003040354**

Type Of Contact:	CONSULTANT
Contractor CRP Number Or Installer ILP Number:	Not reported
Company Name:	APTIM
Representative Name:	MONIKA UGRINSKA
Mailing Address (Delivery):	1250 CAPITAL OF TEXAS HWY SOUTH BLDG 3
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78720
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	305
Phone Number:	5252075
Phone Number Extension:	Not reported
Fax Number Country Code:	1
Fax Number Area Code:	512
Fax Number:	3062061
Email Address:	Not reported

Cont/Cons/Installer ID:	75931
UST ID:	Not reported
NOC ID:	32133
AI Number:	26115
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000396
Company Name:	PETROLEUM EQUIPMENT SERVICE INC
Representative Name:	NATHAN PAVLICA
Mailing Address (Delivery):	1901 MEMORIAL BLVD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	KERRVILLE
Mailing State:	TX
Mailing Zip:	78028
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	0
Phone Number Area Code:	830
Phone Number:	3702265
Phone Number Extension:	0
Fax Number Country Code:	1
Fax Number Area Code:	830
Fax Number:	2577875
Email Address:	PETEQUIP@KTC.COM

Cont/Cons/Installer ID:	3989
UST ID:	Not reported
NOC ID:	3617
AI Number:	26115
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721

7-ELEVEN STORE 36636 (Continued) **U003040354**

Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported
Cont/Cons/Installer ID:	3990
UST ID:	Not reported
NOC ID:	3617
AI Number:	26115
Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	7-ELEVEN INC
Contact Mailing Address (Delivery):	PO BOX 711
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	DALLAS, TX 75221 0711
Phone Number/Ext:	210 8293545/0
Contact Fax Number/Ext:	/
Contact Email Address:	raymond.mcniece@7-11.com
Contact Address Deliverable:	Y
Facility ID:	47983
Additional ID:	2595362002175
Princ ID:	959578622001257
AI Number:	26115
Facility Name:	7-ELEVEN STORE 36636
AR Number:	3971
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	RAYMOND MCNIECE/ENV MGR

HIST UST AUSTIN:

7-ELEVEN STORE 36636 (Continued) **U003040354**

Name:	7-ELEVEN #36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Id UST:	753
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	7-ELEVEN
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/25/2014
Reason for Inspection:	Routine
Violation:	No
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.2
Mileage:	3.8
Reg:	07
Init:	EJ
Seq:	01
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/07/2014
Date Routed by Supervisor:	04/07/2014
Date Routed to PSQA:	04/07/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported

7-ELEVEN STORE 36636 (Continued) **U003040354**

Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	278928
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2021
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	261781
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	Not reported

7-ELEVEN STORE 36636 (Continued) **U003040354**

Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	0 877 4166411
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	241801
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2020
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	ISPILLSB5FGE001
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	223740
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported

7-ELEVEN STORE 36636 (Continued) **U003040354**

Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	224340
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2018
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	207501
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2017
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704

7-ELEVEN STORE 36636 (Continued) **U003040354**

Region:	2
Facility ID:	47983
Finass ID:	188978
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2016
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2018
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	173184
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2017
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	154617
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION

7-ELEVEN STORE 36636 (Continued) **U003040354**

Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2015
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235402
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2016
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	137980
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2014
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2015
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	120522
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2013
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	Not reported
Policy Number:	001235401
Coverage Amount:	1,000,000
Coverage Expiration Date:	12/18/2014

7-ELEVEN STORE 36636 (Continued) **U003040354**

Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	2175
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/18/2012
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	IRONSHORE SPECIALTY INS CO
Issuer Phone:	1 877 4166411
Policy Number:	001235401
Coverage Amount:	2,000,000
Coverage Expiration Date:	12/18/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31316
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2012
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31317

7-ELEVEN STORE 36636 (Continued) **U003040354**

AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/12/2011
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	GREAT AMERICAN ALLIANCE INS CO
Issuer Phone:	1 800 3361337
Policy Number:	17722
Coverage Amount:	1000000
Coverage Expiration Date:	12/12/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31318
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31319
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2010

7-ELEVEN STORE 36636 (Continued) **U003040354**

Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31320
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2009
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31321
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/09/2009
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/09/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

7-ELEVEN STORE 36636 (Continued) **U003040354**

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31322
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	04/30/2008
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	SELF(FIN TEST OR LOCAL GOV FT)
Issuer Phone:	1 703 8463000
Policy Number:	None
Coverage Amount:	10000000
Coverage Expiration Date:	04/30/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	47983
Finass ID:	31323
AI:	26115
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	FINANCIAL TEST
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	12/31/1992
Date Financial Assurance Form Rec:	01/11/2019
Issuer Name:	Not reported
Issuer Phone:	Not reported
Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

GCC:

Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
City,State,Zip:	AUSTIN, TX
Division:	REM/PST
New Cases:	*
File Number:	121023
Contamination Description: GASOLINE	
Date Of Earliest Known Contamination Confirmation:	11/10/2017

7-ELEVEN STORE 36636 (Continued) **U003040354**

Enforcement Status - Level Of Agency Response: 2 - Staff Action
Enforcement Status - Site Activity Status: 6 - Action Completed
Data Quality 1: E,Q
Section 5236: Not reported
Type: Not reported
Agency: Not reported
Section: Not reported
Year Deleted: Not reported
Location: Not reported
Data Quality 2: Not reported

CENTRAL REGISTRY:

Regulated Entity Number: RN100535251
Name: 7-ELEVEN STORE 36636
Address: 1320 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5714
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN605018936
Customer Name: SHAMS EXXON
Customer Legal Name: Shams Exxon
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 424710
Primary NAICS Industry Type Description: Petroleum Bulk Stations and Terminals
Physical Location Description: 1320 EAST OLTORF

Regulated Entity Number: RN100535251
Name: 7-ELEVEN STORE 36636
Address: 1320 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5714
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN605010636
Customer Name: OLTORF SERVICE CENTER INC
Customer Legal Name: Oltorf Service Center Inc
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 424710
Primary NAICS Industry Type Description: Petroleum Bulk Stations and Terminals
Physical Location Description: 1320 EAST OLTORF

Regulated Entity Number: RN100535251
Name: 7-ELEVEN STORE 36636
Address: 1320 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5714
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN605010636
Customer Name: OLTORF SERVICE CENTER INC

7-ELEVEN STORE 36636 (Continued) **U003040354**

Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01

7-ELEVEN STORE 36636 (Continued) **U003040354**

Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710
Primary NAICS Industry Type Description:	Petroleum Bulk Stations and Terminals
Physical Location Description:	1320 EAST OLTORF

Regulated Entity Number:	RN100535251
Name:	7-ELEVEN STORE 36636
Address:	1320 E OLTORF ST
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78704-5714
Status:	ACTIVE
Status Date:	2001-01-01
Customer Number:	CN605010636
Customer Name:	OLTORF SERVICE CENTER INC
Customer Legal Name:	Oltorf Service Center Inc
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	1800-01-01
Affiliation End Date:	3000-12-31
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	424710

7-ELEVEN STORE 36636 (Continued) **U003040354**

Primary NAICS Industry Type Description: Petroleum Bulk Stations and Terminals
Physical Location Description: 1320 EAST OLTORF

Regulated Entity Number: RN100535251
Name: 7-ELEVEN STORE 36636
Address: 1320 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5714
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN605010636
Customer Name: OLTORF SERVICE CENTER INC
Customer Legal Name: Oltorf Service Center Inc
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 424710
Primary NAICS Industry Type Description: Petroleum Bulk Stations and Terminals
Physical Location Description: 1320 EAST OLTORF

Regulated Entity Number: RN100535251
Name: 7-ELEVEN STORE 36636
Address: 1320 E OLTORF ST
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78704-5714
Status: ACTIVE
Status Date: 2001-01-01
Customer Number: CN600251987
Customer Name: SHAMS UL HAQ EXXON
Customer Legal Name: Shams Ul Haq Exxon
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 1800-01-01
Affiliation End Date: 3000-12-31
Customer Status: ACTIVE
Primary NAICS Industry Type Code: 424710
Primary NAICS Industry Type Description: Petroleum Bulk Stations and Terminals
Physical Location Description: 1320 EAST OLTORF

Click this hyperlink while viewing on your computer to access
104 additional TX CENTRAL REG: record(s) in the EDR Site Report.

3294 WSW 1/4-1/2 0.492 mi. 2596 ft. | **DOUGHERTY ARTS CENTER - BUTLER SHORES** | **US BROWNFIELDS FINDS** | **1027559205 N/A**
1500 TOOMEY RD
AUSTIN, TX 78704

Actual: 450 ft.
Focus Map: 11

US BROWNFIELDS:
Name: DOUGHERTY ARTS CENTER - BUTLER SHORES
Address: 1500 TOOMEY RD
Recipient name: City of Austin dba Austin Resource Recovery
Grant type: Assessment
Region: 6
Property Number: Not reported
Parcel size: 1
Latitude: 30.26415902
Longitude: -97.75892103

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City of Austin Parks and Recreation Department is moving the Dougherty Arts Center (DAC) out of the its current aging location and into a newly envisioned building that will be constructed on Butler Shores Park (the site). Butler Shores Park currently has ballfields, and parking. It is near Town Lake and Austin's hike & bike trail. The DAC offers arts experiences for a broad audience through its three main components: The Dougherty Theater, Julia C. Butridge Gallery and the Dougherty Arts School. The building currently housing DAC is beyond repair. It was established as a temporary structure meant to be razed in the 1970s but was adopted as a permanent home that has outlived its viability. PARD will provide a new facility to continue to provide arts center services in a safe, healthy and sustainable environment. This project follows on the heels of the 2018 community engagement process and City Council direction in spring 2019. It is expected construction of the new DAC will be completed in 2024
Datum:	Not reported
Acres Property ID:	253245
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	DOUGHERTY ARTS CENTER - BUTLER SHORES
Address:	1500 TOOMEY RD
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.26415902
Longitude:	-97.75892103
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City of Austin Parks and Recreation Department is moving the Dougherty Arts Center (DAC) out of the its current aging location and into a newly envisioned building that will be constructed on Butler Shores Park (the site). Butler Shores Park currently has ballfields, and parking. It is near Town Lake and Austin's hike & bike trail. The DAC offers arts experiences for a broad audience through its three main components: The Dougherty Theater, Julia C. Butridge Gallery and the Dougherty Arts School. The building currently housing DAC is beyond repair. It was established as a temporary structure meant to be razed in the 1970s but was adopted as a permanent home that has outlived its viability. PARD will provide a new facility to continue to provide arts center services in a safe, healthy and sustainable environment. This project follows on the heels of the 2018 community engagement process and City Council direction in spring 2019. It is expected construction of the new DAC will be completed in 2024
Datum:	Not reported
Acres Property ID:	253245
IC Data Access:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported
Name:	DOUGHERTY ARTS CENTER - BUTLER SHORES
Address:	1500 TOOMEY RD
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.26415902
Longitude:	-97.75892103
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City of Austin Parks and Recreation Department is moving the Dougherty Arts Center (DAC) out of the its current aging location and into a newly envisioned building that will be constructed on Butler Shores Park (the site). Butler Shores Park currently has ballfields, and parking. It is near Town Lake and Austin's hike & bike trail. The DAC offers arts experiences for a broad audience through its three main components: The Dougherty Theater, Julia C. Butridge Gallery and the Dougherty Arts School. The building currently housing DAC is beyond repair. It was established as a temporary structure meant to be razed in the 1970s but was adopted as a permanent home that has outlived its viability. PARD will provide a new facility to continue to provide arts center services in a safe, healthy and sustainable environment. This project follows on the heels of the 2018 community engagement process and City Council direction in spring 2019. It is expected construction of the new DAC will be completed in 2024
Datum:	Not reported
Acres Property ID:	253245
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	6586.08
Assessment Funding Source:	EPA
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	US EPA - Brownfields Assessment Cooperative Agreement
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	Y
Cooperative Agreement Number:	01F96301
Start Date:	3/10/2022
Ownership Entity:	Not reported
Completion Date:	6/21/2022

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	DOUGHERTY ARTS CENTER - BUTLER SHORES
Address:	1500 TOOMEY RD
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.26415902
Longitude:	-97.75892103
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City of Austin Parks and Recreation Department is moving the Dougherty Arts Center (DAC) out of the its current aging location and into a newly envisioned building that will be constructed on Butler

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Shores Park (the site). Butler Shores Park currently has ballfields, and parking. It is near Town Lake and Austin's hike & bike trail. The DAC offers arts experiences for a broad audience through its three main components: The Dougherty Theater, Julia C. Butridge Gallery and the Dougherty Arts School. The building currently housing DAC is beyond repair. It was established as a temporary structure meant to be razed in the 1970s but was adopted as a permanent home that has outlived its viability. PARD will provide a new facility to continue to provide arts center services in a safe, healthy and sustainable environment. This project follows on the heels of the 2018 community engagement process and City Council direction in spring 2019. It is expected construction of the new DAC will be completed in 2024

Datum:	Not reported
Acres Property ID:	253245
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

Name:	DOUGHERTY ARTS CENTER - BUTLER SHORES
Address:	1500 TOOMEY RD
Recipient name:	City of Austin dba Austin Resource Recovery
Grant type:	Assessment
Region:	6
Property Number:	Not reported
Parcel size:	1
Latitude:	30.26415902
Longitude:	-97.75892103
HCM Label:	Not reported
Map Scale:	Not reported
Point of Reference:	Not reported
Highlights:	The City of Austin Parks and Recreation Department is moving the Dougherty Arts Center (DAC) out of the its current aging location and into a newly envisioned building that will be constructed on Butler Shores Park (the site). Butler Shores Park currently has ballfields, and parking. It is near Town Lake and Austin's hike & bike trail. The DAC offers arts experiences for a broad audience through its three main components: The Dougherty Theater, Julia C. Butridge Gallery and the Dougherty Arts School. The building currently housing DAC is beyond repair. It was established as a temporary structure meant to be razed in the 1970s but was adopted as a permanent home that has outlived its viability. PARD will provide a new facility to continue to provide arts center services in a safe, healthy and sustainable environment. This project follows on the heels of the 2018 community engagement process and City Council direction in spring 2019. It is expected construction of the new DAC will be completed in 2024
Datum:	Not reported
Acres Property ID:	253245
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	Not reported
Accomplishment Type:	Not reported
Accomplishment Count:	Not reported
Cooperative Agreement Number:	01F96301
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Not reported
Did Owner Change:	Not reported
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Contaminant Found:	Not reported
Contaminant Cleanup:	Not reported
Media Affected:	Not reported
Media Cleanup:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Superfund Fed. landowner flag:	Not reported
Future Use: Multistory	Not reported
Past Use: Multistory	Not reported
Property Description:	Not reported
Below Poverty Number:	Not reported
Below Poverty Percent:	Not reported
Meidan Income:	Not reported
Meidan Income Number:	Not reported
Meidan Income Percent:	Not reported
Vacant Housing Number:	Not reported
Vacant Housing Percent:	Not reported
Unemployed Number:	Not reported
Unemployed Percent:	Not reported

DOUGHERTY ARTS CENTER - BUTLER SHORES (Continued) **1027559205**

FINDS:
Registry ID: 110071325694

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3295 ESE 1/4-1/2 0.493 mi. 2602 ft.

Actual: 700 ft.

Focus Map: 9

CONTINENTAL CARS
200 W HUNTLAND
AUSTIN, TX 78752

TX LPST **1000412779**
RCRA NonGen / NLR **TXD026014704**
FINDS
ECHO
TX Ind. Haz Waste
TX CENTRAL REGISTRY

LPST:

Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
City,State,Zip:	AUSTIN, TX 78752
Facility ID:	0015519
LPST Id:	101182
Facility Location:	200 W HUNTLAND
TCEQ Region# and City:	REGION 11 - AUSTIN
Region City:	AUSTIN
Discovered Date:	12/10/1991
Entered Date:	01/13/1992
Reported Date:	12/10/1991
Closure Date:	09/29/1992
Priority:	5 - MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Program:	2 - REGION
CA Status:	6A - FINAL CONCURRENCE ISSUED
Priority Description:	MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
Status:	**FINAL CONCURRENCE ISSUED, CASE CLOSED**
Coordinators Primary:	2
Coordinators RPR:	HELEN WELCH
Responsible Party Name:	Not reported
Responsible Party Contact:	BRYAN HARDEMAN
Responsible Party Address:	6757 AIRPORT BLVD
Responsible Party City,St,Zip:	AUSTIN, TX 78752
Responsible Party Telephone:	512/454-6821
Reported Date:	12/10/1991
Case Start Date:	09/29/1992
Reference Number:	RN100556224
Project Manager:	HWELCH

RCRA Listings:

Date Form Received by Agency:	20010823
Handler Name:	Continental Cars
Handler Address:	W HUNTLAND
Handler City,State,Zip:	AUSTIN, TX 78752
EPA ID:	TXD026014704
Contact Name:	MURRAY BINSON
Contact Address:	W HUNTLAND

CONTINENTAL CARS (Continued) **1000412779**

Contact City,State,Zip:	AUSTIN, TX 78752
Contact Telephone:	512-458-2511
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Tx
State District:	11
Mailing Address:	W HUNTLAND
Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Name:	Continental Cars
Owner Type:	Private
Operator Name:	Continental Cars
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20040325
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CONTINENTAL CARS (Continued) **1000412779**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONTINENTAL CARS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 200 W HUNTLAND
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-458-2511
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONTINENTAL CARS
Legal Status: Private
Date Became Current: 20010823
Date Ended Current: Not reported
Owner/Operator Address: 200 W HUNTLAND
Owner/Operator City,State,Zip: AUSTIN, TX 78752
Owner/Operator Telephone: 512-458-2511
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

CONTINENTAL CARS (Continued) **1000412779**

Owner/Operator Name: BRYAN HARDEMAN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19841024
Handler Name: CONTINENTAL CARS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010823
Handler Name: CONTINENTAL CARS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Tx
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110005041427

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

CONTINENTAL CARS (Continued) **1000412779**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000412779
Registry ID:	110005041427
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005041427
Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND
City,State,Zip:	AUSTIN, TX 78752

Ind. Haz Waste:

Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
City,State,Zip:	AUSTIN, TX 78752
Permit Number:	Not reported
Registration Number:	66186
Registration Initial Notification Date:	09/18/1984
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD026014704
Primary NAICS Code:	Not reported
Status Change Date:	19840918
Land Type:	PRIVATE
Description of Facility Site Location:	200 W Huntland, Austin, TX
Site Primary Standard Industrial Code:	Not reported
Registration is Generator of Waste:	1
TNRCC Region Number:	11
Registration is Receivers of Waste:	1
Registration is Transporter of Waste:	1
Registration is Transfer Facility:	1
Facility is STEERS Reporter:	1
Reqired to Submit Annual Waste Summary:	1
Facility Involved In Recycling:	1
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator HW:	SQG
Type of Generator:	NON INDUS
Company Name:	CONTINENTAL CARS LTD
Contact Name:	MURRAY BINSON
Contact Telephone Number:	512-4582511
Mailing Address:	200 W HUNTLAND DR
Mailing Address2:	Not reported
Mailing City,State,Zip:	AUSTIN, TX 787523622
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	21483
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020123
Ind. Waste Permit Number:	Not reported

CONTINENTAL CARS (Continued) **1000412779**

Mun Waste Permit Number:	Not reported
Non Notifier:	1
MSW:	Not reported
Medical Waste:	Not reported
Other:	Not reported
Sludge:	Not reported
Used Oil:	Not reported
Used Tires:	Not reported
Permit Status:	Not reported
Receiver Type:	Not reported
Transporter for Hire:	0
Transport Own Waste:	0

Ind. Haz Waste:

Operator Name:	CONTINENTAL CARS LTD
Operator Address:	200 W HUNTLAND DR
Operator Address 2:	Not reported
Operator Address 3:	Not reported
Operator City,State,Zip:	AUSTIN, TX 78752
Operator Country:	UNITED STA
Operator Telephone:	1-512-4582511
Operator Fax Number:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax ID:	32014348521
Operator Bankruptcy Code:	Not reported

Ind. Haz Waste:

Owner Name:	CONTINENTAL CARS LTD
Owner Mailing Address:	200 W HUNTLAND DR
Owner Mailing Address 2:	Not reported
Owner Mailing Address 3:	Not reported
Owner Mailing City,State,Zip:	AUSTIN, TX 78752
Owner Country:	UNITED STA
Owner Telephone:	1-512-4582511
Owner Fax:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax ID:	32014348521
Owner Bankruptcy Code:	Not reported

Ind. Haz Waste:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	200 W HUNTLAND DR
Contact Address 2:	Not reported
Contact Address 3:	Not reported
Contact City,State,Zip:	AUSTIN, TX 78752
Contact Phone:	1-512-4582511
Contact Fax:	Not reported
Contact Email:	Not reported

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	200 W HUNTLAND DR

CONTINENTAL CARS (Continued) **1000412779**

Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78752
Contact Phone: 1-512-4582511
Contact Fax: Not reported
Contact Email: Not reported

Contact Name: MURRAY BINSON
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 200 W HUNTLAND DR
Contact Address 2: Not reported
Contact Address 3: Not reported
Contact City,State,Zip: AUSTIN, TX 78752
Contact Phone: 1-512-4582511
Contact Fax: Not reported
Contact Email: Not reported

Ind. Haz Waste:
Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: Not reported
Mailing Address: 6757 AIRPORT BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: AUSTIN, TX 78752
AR Number: 0000302649
Principal Name: CONTINENTAL CARS LTD
Attention Name: Not reported
Attention Suffix: NWG

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: Not reported
Mailing Address: 6757 AIRPORT BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: AUSTIN, TX 78752
AR Number: 0000302649
Principal Name: CONTINENTAL CARS LTD
Attention Name: Not reported
Attention Suffix: HWG

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: Not reported
Mailing Address: 6757 AIRPORT BLVD
Mailing Address 2: Not reported
Mailing City,St,Zip: AUSTIN, TX 78752
AR Number: 0000302649
Principal Name: CONTINENTAL CARS LTD
Attention Name: Not reported
Attention Suffix: HWF

Contact Name: Not reported
Contact Title: Not reported
Contact Telephone: Not reported
Mailing Address: 6757 AIRPORT BLVD
Mailing Address 2: Not reported

CONTINENTAL CARS (Continued) **1000412779**

Mailing City,St,Zip:	AUSTIN, TX 78752
AR Number:	0000302649
Principal Name:	CONTINENTAL CARS LTD
Attention Name:	Not reported
Attention Suffix:	NWF

CENTRAL REGISTRY:

Regulated Entity Number:	RN100556224
Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3622
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	200 W Huntland, Austin, TX

Regulated Entity Number:	RN100556224
Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3622
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	200 W Huntland, Austin, TX

Regulated Entity Number:	RN100556224
Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3622
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601256514
Customer Name:	CONTINENTAL IMPORTS INC
Customer Legal Name:	Continental Imports, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000

CONTINENTAL CARS (Continued) **1000412779**

Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN601256514
Customer Name: CONTINENTAL IMPORTS INC
Customer Legal Name: Continental Imports, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/15/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN603447053
Customer Name: CONTINENTAL CARS INC
Customer Legal Name: Continental Cars, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN603447053
Customer Name: CONTINENTAL CARS INC
Customer Legal Name: Continental Cars, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported

CONTINENTAL CARS (Continued) **1000412779**

Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN600267132
Customer Name: CONTINENTAL CARS LTD
Customer Legal Name: Continental Cars, Ltd.
Customer Ownership Type: ORGANIZATION
Affiliation Begin Date: 8/23/2001
Affiliation End Date: 12/31/3000
Customer Status: UNVALD
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN601256514
Customer Name: CONTINENTAL IMPORTS INC
Customer Legal Name: Continental Imports, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: 8/15/1986
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224
Name: CONTINENTAL CARS
Address: 200 W HUNTLAND DR
Address 2: Not reported
City,State,Zip: AUSTIN, TX 78752-3622
Status: ACTIVE
Status Date: ##########
Customer Number: CN603447053
Customer Name: CONTINENTAL CARS INC
Customer Legal Name: Continental Cars, Inc.
Customer Ownership Type: CORPORATION
Affiliation Begin Date: ##########
Affiliation End Date: 12/31/3000
Customer Status: ACTIVE
Primary NAICS Industry Type Code: Not reported
Primary NAICS Industry Type Description: Not reported
Physical Location Description: 200 W Huntland, Austin, TX

Regulated Entity Number: RN100556224

CONTINENTAL CARS (Continued) **1000412779**

Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3622
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN600267132
Customer Name:	CONTINENTAL CARS LTD
Customer Legal Name:	Continental Cars, Ltd.
Customer Ownership Type:	ORGANIZATION
Affiliation Begin Date:	8/23/2001
Affiliation End Date:	12/31/3000
Customer Status:	UNVALD
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	200 W Huntland, Austin, TX

Regulated Entity Number:	RN100556224
Name:	CONTINENTAL CARS
Address:	200 W HUNTLAND DR
Address 2:	Not reported
City,State,Zip:	AUSTIN, TX 78752-3622
Status:	ACTIVE
Status Date:	##########
Customer Number:	CN601256514
Customer Name:	CONTINENTAL IMPORTS INC
Customer Legal Name:	Continental Imports, Inc.
Customer Ownership Type:	CORPORATION
Affiliation Begin Date:	8/15/1986
Affiliation End Date:	12/31/3000
Customer Status:	ACTIVE
Primary NAICS Industry Type Code:	Not reported
Primary NAICS Industry Type Description:	Not reported
Physical Location Description:	200 W Huntland, Austin, TX

Click this hyperlink while viewing on your computer to access
5 additional TX CENTRAL REG: record(s) in the EDR Site Report.

3296 **SHELL** **TX RDR** **S127527615**
WNW **500 W WILLIAM CANNON** **N/A**
1/4-1/2 **AUSTIN, TX**
0.493 mi.
2605 ft.

Actual:
701 ft.

Focus Map:
17

RDR:

RDR ID:	14680
Facility ID:	23189
RN:	Not reported
CN:	Not reported
Name:	SHELL
Address:	500 W WILLIAM CANNON
City,State,Zip:	AUSTIN, TX
Date Report Received:	8/4/2005
Due Date:	10/3/2005
Tank Owner:	SHELL OIL PRODUCTS US
Contact Person:	JOYCE DAVIS
Report:	RDR
Latest TCEQ Letter:	No Leaker

SHELL (Continued) **S127527615**

Date of Latest TCEQ Letter:	9/1/2005
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	PPC
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	9/1/2005
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UH3297 **SIGNATURE 2** **TX RDR** **S127530903**
WNW **608 S LAMAR AVE** **N/A**
1/4-1/2 **AUSTIN, TX**
0.496 mi.
2621 ft. **Site 1 of 3 in cluster UH**

Actual:
488 ft.

Focus Map:
11

RDR:

RDR ID:	28375
Facility ID:	34911
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 2
Address:	608 S LAMAR AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	3/12/2020
Due Date:	5/11/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	SUSPECTED RELEASE
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	4/7/2020
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	28480
Facility ID:	34911
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 2
Address:	608 S LAMAR AVE
City,State,Zip:	AUSTIN, TX
Date Report Received:	4/14/2020

SIGNATURE 2 (Continued) **S127530903**

Due Date:	6/13/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	SUSPECTED RELEASE
Latest TCEQ Letter:	NO SYSTEM/SITE CHECK
Date of Latest TCEQ Letter:	5/12/2020
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UH3298 **TEXACO RETAIL FAC** **TX RDR** **S127530904**
WNW **608 S LAMAR** **N/A**
1/4-1/2 **AUSTIN, TX**
0.496 mi.
2621 ft. **Site 2 of 3 in cluster UH**

Actual:
488 ft.

Focus Map:
11

RDR:

RDR ID:	12535
Facility ID:	34911
RN:	Not reported
CN:	Not reported
Name:	TEXACO RETAIL FAC
Address:	608 S LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	7/7/2003
Due Date:	9/5/2003
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	SCOTT BURKEY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	12/23/2003
Project Manager:	PST Privitization Contract
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	NEW RDR REC 10/24/03 NEW REL 7/28/03
Review Coordinator:	PPC/EAE
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	12/23/2003
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	12939
Facility ID:	34911
RN:	Not reported

TEXACO RETAIL FAC (Continued) **S127530904**

CN:	Not reported
Name:	TEXACO RETAIL FAC
Address:	608 S LAMAR
City,State,Zip:	AUSTIN, TX
Date Report Received:	10/27/2003
Due Date:	12/26/2003
Tank Owner:	MOTIVA ENTERPRISES
Contact Person:	SCOTT BURKEY
Report:	RDR
Latest TCEQ Letter:	No Leaker
Date of Latest TCEQ Letter:	8/27/2004
Project Manager:	Trudy Hasan
Team:	#N/A
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	1ST RDR REC 7/7/03 NOL 12/23/03. THIS RDR ALSO NOL.
Review Coordinator:	TH2
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	8/27/2004
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

UH3299 **SIGNATURE 2** **TX UST** **U003566301**
WNW **608 S LAMAR BLVD** **TX HIST UST** **N/A**
1/4-1/2 **AUSTIN, TX 78704** **TX ASBESTOS**
0.496 mi. **TX Financial Assurance**
2621 ft. **Site 3 of 3 in cluster UH** **TX RDR**

Actual:
488 ft.

Focus Map:
11

UST:

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 787041506
AI Number:	34911
Facility Type:	RETAIL
Facility Begin Date:	09/01/1988
Facility Status:	ACTIVE
Additional ID:	194064982002139
Facility Exempt Status:	N
Records Off-Site:	Yes
UST Financial Assurance Required:	Yes
Number Of Active UST:	2
Site Location Description:	Not reported
Site Location (Nearest City Name):	Not reported
Site Location (County Name):	TRAVIS
Site Location (Tceq Region):	11
Site Location (Location Zip):	78704
Contact Name/Title:	,
Contact Organization Name:	SIGNATURE 2
Contact Mailing Address1:	Not reported
Contact Mailing Address2:	Not reported
Contact Mailing City/State/Zip:	Not reported
Contact Telephone:	5123852020
Facility Contact Address Deliverable:	Not reported
Contact Fax Number:	Not reported
Contact Email Address:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Signature Date On Earliest Reg Form:	08/02/2021
Signature Name/Title On Earliest Reg Form:	PAUL PEMBERTON,DIRECTOR
Application Received Date On Earliest Reg Form:	08/04/2021
Signature Role On Earliest Reg Form:	LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form:	Not reported
Enforcement Action:	No
Facility Not Inspectable:	No

Operator:

Princ ID:	365520692002075
Additional ID:	194064982002139
Ai Number:	34911
Operator CN:	CN600918452
Operator Name:	TEXAS ENTERPRISES INC
Operator Effective Begin Date:	05/14/2012
Operator Type:	CO
Operator Role:	OPRCON
Contact Name:	BROCK ISBELL/SITE REP
Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	2702 INDUSTRIAL BLVD STE A
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	ABILENE TX 79605-7213
Contact Phone Country Code:	1
Contact Phone Area Code:	325
Contact Phone Number:	6950150
Contact Phone Extension:	0
Contact Fax Country Code:	Not reported
Contact Fax Area Code:	Not reported
Contact Fax Number:	Not reported
Contact Fax Extension:	Not reported
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported

Owner:

Owner CN:	CN600918452
Owner Last Name:	TEXAS ENTERPRISES INC
Owner First Name:	Not reported
Owner Middle Name:	Not reported
Owner Type:	CO
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City:	AUSTIN
Contact Mailing State:	TX
Contact Mailing Zip:	78762
Contact Mailing Zip5:	6156
Contact Phone Number/Ext:	1 512 3852020/0
Contact Fax Country Code:	Not reported
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Not reported
Princ ID:	365520692002075
Additional ID:	194064982002139
AI Number:	34911
Owner Effective Begin Date:	05/14/2012
State Tax ID:	17418588749
Contact Role:	OWNOPRCON
Contact Name/Title:	PAUL PEMBERTON/

SIGNATURE 2 (Continued) **U003566301**

Contact Organization Name: TEXAS ENTERPRISES INC

Self Certification:

Self Cert ID:	79657
Cert ID:	376656
AI Number:	34911
Self Certification Date:	09/06/2022
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2023
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	358220
AI Number:	34911
Self Certification Date:	08/02/2021
Signature Name/Title:	PAUL PEMBERTON DIRECTOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2022
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	343136
AI Number:	34911
Self Certification Date:	08/28/2020
Signature Name/Title:	PAUL PEMBERTON DIR OF ENVCOMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2021
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	324433
AI Number:	34911
Self Certification Date:	07/30/2019
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2020
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	308565
AI Number:	34911
Self Certification Date:	08/21/2018
Signature Name/Title:	PAUL PEMBERTON DIR OF ENV COMPLIANCE
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2019
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	292032
AI Number:	34911
Self Certification Date:	08/23/2017
Signature Name/Title:	PAUL PEMBERTON DIR OF ENVIRONMENTAL COMP
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2018
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	274755
AI Number:	34911
Self Certification Date:	08/08/2016
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2017
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	259985
AI Number:	34911
Self Certification Date:	08/27/2015
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2016
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y
Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y

Self Cert ID:	79657
Cert ID:	242138
AI Number:	34911
Self Certification Date:	07/24/2014
Signature Name/Title:	PAUL PEMBERTON DIR OF MAINT
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2015
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	Y

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	N
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	79657
Cert ID:	224730
AI Number:	34911
Self Certification Date:	08/15/2013
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2014
Reporting Method:	P
Tank Corrosion Protection Compliance:	Y
Piping Corrosion Protection Compliance:	Y
Compartment Release Detection Compliance:	N
Piping Release Detection Compliance:	Y
Spill Prevention/Overfill Compliance:	Y
Self Cert ID:	79657
Cert ID:	128464
AI Number:	34911
Self Certification Date:	06/29/2012
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2013
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128463
AI Number:	34911
Self Certification Date:	05/31/2012
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	09/30/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128462
AI Number:	34911
Self Certification Date:	06/08/2011
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2012
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128461
AI Number:	34911
Self Certification Date:	06/29/2010
Signature Name/Title:	FORD SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2011
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128460
AI Number:	34911
Self Certification Date:	06/09/2009
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2010
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128459
AI Number:	34911
Self Certification Date:	05/16/2008
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2009
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128458
AI Number:	34911
Self Certification Date:	05/18/2007
Signature Name/Title:	FORD SMITH JR PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2008
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128457
AI Number:	34911
Self Certification Date:	07/01/2006
Signature Name/Title:	FORD SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2007
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128456
AI Number:	34911
Self Certification Date:	06/23/2005
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2006
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128455
AI Number:	34911
Self Certification Date:	06/24/2004
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2005
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128454
AI Number:	34911
Self Certification Date:	07/01/2003
Signature Name/Title:	ALLEN W SMITH PRESIDENT
Signature Type Role:	OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128453
AI Number:	34911
Self Certification Date:	06/30/2003
Signature Name/Title:	ALLEN W SMITH PRES
Signature Type Role:	OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	07/31/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128452
AI Number:	34911
Self Certification Date:	03/04/2003
Signature Name/Title:	SCOTT HAGGERTON HSE COMP COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2004
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128451
AI Number:	34911
Self Certification Date:	03/01/2002
Signature Name/Title:	GEORGE CARTWRIGHT SHE COORD
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	RENEWAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2003
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported
Self Cert ID:	79657
Cert ID:	128450
AI Number:	34911
Self Certification Date:	11/27/2000
Signature Name/Title:	R I RENEAU SH & E COMP COOR
Signature Type Role:	LEGAL AUTH REP OWNER
Filing Status:	INITIAL
Registration Self Certification Flag:	Y
Facility Fees Self Certification Flag:	Y
Financial Assurance Self Certification Flag:	Y
Technical Standards Self Certification Flag:	Y
Delivery Certificate Expiration Date:	04/30/2002
Reporting Method:	Not reported
Tank Corrosion Protection Compliance:	Not reported
Piping Corrosion Protection Compliance:	Not reported
Compartment Release Detection Compliance:	Not reported
Piping Release Detection Compliance:	Not reported
Spill Prevention/Overfill Compliance:	Not reported

Tank:

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	92252
Facility ID:	79657
Ai Number:	34911
Tank Id:	1
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/28/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N

SIGNATURE 2 (Continued) **U003566301**

Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	1
Tank Capacity:	6000
UST Comprt ID:	123147
UST ID:	92252
AI Number:	34911
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y

SIGNATURE 2 (Continued) **U003566301**

SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	92253
Facility ID:	79657
Ai Number:	34911
Tank Id:	3
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/28/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y

SIGNATURE 2 (Continued) **U003566301**

Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	3
Tank Capacity:	3000
UST Comprt ID:	123148
UST ID:	92253
AI Number:	34911
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y

SIGNATURE 2 (Continued) **U003566301**

CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A

SIGNATURE 2 (Continued) **U003566301**

Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	6000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	92254
Facility ID:	79657
Ai Number:	34911
Tank Id:	2
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/28/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N

SIGNATURE 2 (Continued) **U003566301**

Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	2
Tank Capacity:	6000
UST Comprt ID:	123149
UST ID:	92254
AI Number:	34911
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A

SIGNATURE 2 (Continued) **U003566301**

Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Install Date:	01/01/1983
Tank Registration Date:	05/08/1986
Number of Compartments:	1
Tank Capacity:	3000
Tank Singlewall:	Y
Tank Doublewall:	N
Pipe Type:	P
UST ID:	92255
Facility ID:	79657
Ai Number:	34911
Tank Id:	4
Tank Status (Current):	REMOVED FROM GROUND
Tank Status Date:	07/28/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	Y
Piping Design (Double Wall):	N
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	Y
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	N
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	Y
Piping Mat(Frp(Fiberglass Reinforced Plastic):	N
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N

SIGNATURE 2 (Continued) **U003566301**

TCPM(Cathodic Prot-FacInstallation):	N
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	N
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	N
Piping Corr Prot Compliance Flag:	N
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	Y
Installation Signature Date:	07/09/1990

Compartment Records:

Tank ID:	4
Tank Capacity:	3000
UST Comprt ID:	123150
UST ID:	92255
AI Number:	34911
Compartment ID:	A
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	Y
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	Y
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	N
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	Y
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	Y
PRDM(Sir(StatInv Recon)/Inv Control)):	N
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y

SIGNATURE 2 (Continued) **U003566301**

Piping Release Detection Compliance Flag):	Y
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	Not reported
Stage 1 Installation Date:	Not reported

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A

Install Date:	08/01/2003
Tank Registration Date:	07/27/2004
Number of Compartments:	1
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y
Pipe Type:	P
UST ID:	203438
Facility ID:	79657
Ai Number:	34911
Tank Id:	5
Tank Status (Current):	IN USE
Tank Status Date:	08/01/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N

SIGNATURE 2 (Continued) **U003566301**

Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

Compartment Records:

Tank ID:	5
Tank Capacity:	10000
UST Comprt ID:	123151
UST ID:	203438
AI Number:	34911
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y

SIGNATURE 2 (Continued) **U003566301**

PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	08/01/2003

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Install Date:	08/01/2003
Tank Registration Date:	07/27/2004
Number of Compartments:	2
Tank Capacity:	10000
Tank Singlewall:	N
Tank Doublewall:	Y

SIGNATURE 2 (Continued) **U003566301**

Pipe Type:	P
UST ID:	203439
Facility ID:	79657
Ai Number:	34911
Tank Id:	6
Tank Status (Current):	IN USE
Tank Status Date:	08/01/2003
Empty:	N
Tank Regulatory Status:	FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date):	Not reported
Piping Design (Single Wall):	N
Piping Design (Double Wall):	Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket):	N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Tank Ext Cont(Tank Vault/Rigid Trench Liner):	N
Piping Ext Cont(Fac-Built Nonmetallic Jacket):	N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner):	N
Piping Ext Cont(Tank Vault/Rigid Trench Liner):	N
Tank Material (Steel):	N
Tank Material(Frp(Fiberglass-Reinforced Plastic):	N
Tank Mat(Composite (Steel W/Ext Frp Cladding)):	Y
Tank Mat(Concrete):	N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)):	N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)):	N
Piping Material (Steel):	N
Piping Mat(Frp(Fiberglass Reinforced Plastic):	Y
Piping Mat(Concrete):	N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)):	N
Piping Mat(Nonmetallic Flex Piping):	N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)):	N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)):	N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)):	N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation):	N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap):	N
TCPM(Cathodic Prot-FacInstallation):	Y
TCPM(Composite Tank(Steel W/Frp Ext Laminate):	Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate):	N
TCPM(FRP Tank Or Piping(Noncorrodible)):	N
TCPM(Ext Nonmetallic Jacket):	N
TCPMeth(Unnecessary Per Corrosion Prot Spec):	N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap):	N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install):	N
PCPM(Cathodic Prot-Field Install):	N
PCPMethod (FRP Tank Or Piping(Noncorrodible):	Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)):	N
PCPMeth(Isolated Open Area/2nd Containment):	N
PCPM (Dual Protected):	N
PCPM(Unnec Per Corrosion Prot Specialist):	N
Tank Corr Prot Compliance Flag:	Y
Piping Corr Prot Compliance Flag:	Y
Tank Corrosion Prot Variance:	N
Piping Corrosion Prot Variance:	N
Temp Out Of Service Compliance:	N
Technical Compliance Flag:	N
Tank Tested Flag:	N
Installation Signature Date:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Compartment Records:

Tank ID:	6
Tank Capacity:	5000
UST Comprt ID:	123152
UST ID:	203439
AI Number:	34911
Compartment ID:	A
Substance Stored1:	GASOLINE
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N
CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	08/01/2003

Tank ID:	6
Tank Capacity:	5000
UST Comprt ID:	123153
UST ID:	203439
AI Number:	34911
Compartment ID:	B
Substance Stored1:	DIESEL
Substance Stored2:	Not reported
Substance Stored3:	Not reported
CompartmentReleaseDetectionMethod(Vapor):	N
CRDM(GW Monitoring):	N
CRDM(Monitoring Of Secondary Cont Barrier):	N
CRDM(Auto Tank Gauge Test/Inv Control):	N
CRDM(Interstitial Monitoring SecWall/Jacket):	N

SIGNATURE 2 (Continued) **U003566301**

CRDM(Wkly Manual Gauging(Tanks<=1000 G):	N
CRDM(Mthly Tank Gauging(Emer Gen Tanks):	N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control):	Y
PipingReleaseDetectionMethod(PRDM)(Vapor):	N
PRDM(Groundwater Monitoring):	N
PRDM(Monitoring Sec Containment Barrier):	N
PRDM(InterstitialMonitoring w/in SecWall/Jacket):	N
PRDM(Mthly Piping Tightness Test)@.2Gph:	N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph:	N
PRDM(TriennialTightTest(Suction/GravityPiping):	N
PRDM AutoLineLeakDet(3.0 Gph PressPiping):	N
PRDM(Sir(StatInv Recon)/Inv Control)):	Y
PRDM(Exempt System Suction:	N
Spill Overfill Prevention Equip(SOPE):	Y
SOPE(Spill Cont/Bucket/Sump):	Y
SOPE(DelShut-Off Valve)):	N
SOPE(FlowRestrictorValue:	Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b:	N
SOPE(N/A Deliveries To Tank<=25G):	N
Compartment Release Det Compliance Flag:	Y
Piping Release Detection Compliance Flag):	N
Spill/OverfillPreventionCompliance Flag:	Y
Compartment Release Detection Variance:	N
Piping Release Detection Variance:	N
Spill And Overfill Prevention Variance:	N
Stage I Vapor Recovery:	COAXIAL SYSTEM
Stage 1 Installation Date:	08/01/2003

More Self Certification:

Self Cert ID:	13507
Cert ID:	125776
UST Comprt ID:	345721
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125777
UST Comprt ID:	345722
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A
Self Cert ID:	13507
Cert ID:	125778
UST Comprt ID:	345723
UST ID:	117935
AI Number:	34911
Tank ID:	3
Compartment ID:	A

Construction Notification:

NOC ID:	12237

SIGNATURE 2 (Continued) **U003566301**

Facility ID:	79657
AI Number:	34911
Application Received Date:	05/27/2010
Scheduled Construction Date:	05/27/2010
UST Improvement:	N
UST Installation:	N
UST Removal:	N
UST Repair:	N
UST Return To Service:	N
UST Replacement:	N
UST Abandonment:	N
UST Stage I:	N
AST Installation:	N
AST Stage I:	N
Historical Tracking Number:	NONE
Waiver Flag:	N
Late Filing Flag:	Y
Form Received Date:	Not reported
Signature Date On Form:	Not reported
Signature Name On Form:	Not reported
Signature Company On Form:	Not reported
Signature Title On Form:	Not reported
Signature Role:	Not reported
Owner Name At Time Of Construction:	Not reported
Owner CN At Time Of Construction:	Not reported
Owner AR At Time Of Construction:	22907
General Desc Of Prop Construct:	INVESTIGATE AND REPAIR WATER INTRUSION INTO DIESEL DOUBLE-WALL PIPE.

Contractor, Consultant and Installer:

Cont/Cons/Installer ID:	13036
UST ID:	Not reported
NOC ID:	12237
AI Number:	34911
Type Of Contact:	CONTRACTOR
Contractor CRP Number Or Installer ILP Number:	CRP000821
Company Name:	PETROLEUM SOLUTIONS INC
Representative Name:	BRENT PEFFER
Mailing Address (Delivery):	1804 SMITH RD
Mailing Address (Internal Delivery):	Not reported
Mailing City:	AUSTIN
Mailing State:	TX
Mailing Zip:	78721
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	1
Phone Number Area Code:	512
Phone Number:	2781000
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Cont/Cons/Installer ID:	13037
UST ID:	Not reported
NOC ID:	12237
AI Number:	34911

SIGNATURE 2 (Continued) **U003566301**

Type Of Contact:	INSTALLER
Contractor CRP Number Or Installer ILP Number:	ILP000821
Company Name:	Not reported
Representative Name:	Not reported
Mailing Address (Delivery):	Not reported
Mailing Address (Internal Delivery):	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Foreign Postal Code:	Not reported
Mailing County Code:	Not reported
Phone Number Country Code:	Not reported
Phone Number Area Code:	Not reported
Phone Number:	Not reported
Phone Number Extension:	Not reported
Fax Number Country Code:	Not reported
Fax Number Area Code:	Not reported
Fax Number:	Not reported
Email Address:	Not reported

Facility Billing Contacts:

Contact Organization Name:	TEXAS ENTERPRISES INC
Contact Mailing Address (Delivery):	PO BOX 6156
Contact Mailing Address (Internal Delivery):	Not reported
Contact Mailing City/State/Zip:	AUSTIN, TX 78762 6156
Phone Number/Ext:	/
Contact Fax Number/Ext:	/
Contact Email Address:	Not reported
Contact Address Deliverable:	Y
Facility ID:	79657
Additional ID:	194064982002139
Princ ID:	365520692002075
AI Number:	34911
Facility Name:	SIGNATURE 2
AR Number:	18379
AR UST Number Suffix:	Not reported
AR AST Number Suffix:	U
Contact Name/Title:	PAUL PEMBERTON/

HIST UST AUSTIN:

Name:	SIGNATURE # 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Id UST:	319
HID UST:	Not reported
Inspection:	Not reported
Due:	Not reported

ASBESTOS:

Name:	SIGNATURE #2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	03/14/2013
Reason for Inspection:	Routine

SIGNATURE 2 (Continued) **U003566301**

Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	0
Reg:	07
Init:	EJ
Seq:	03
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	03/18/2013
Date Routed by Supervisor:	03/18/2013
Date Routed to PSQA:	03/18/2013
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported
Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported
Name:	SIGNATURE #2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Date of inspection:	04/08/2014
Reason for Inspection:	Routine
Violation:	Yes
Complaint Date:	Not reported
Notification Number:	Not reported
ASB Priority:	Not reported
PIF State:	Not reported
Detained:	Not reported
Product Name:	Not reported
Time Spent:	0.5
Travel Time:	0.1
Mileage:	1.8
Reg:	07
Init:	EJ
Seq:	04
Facility Type:	Abusible Volitile Chemicals
Inspector Name:	Eddie Jackson
Date Report Received:	04/14/2014
Date Routed by Supervisor:	04/16/2014
Date Routed to PSQA:	04/17/2014
Date Reviewed by PSQA:	Not reported
Date Routed by Supervisor1:	Not reported
Date Rtnd to Inspector Corrections:	Not reported
Date Rcvd Back:	Not reported
Date Rtnd to Inspector Corrections2:	Not reported
Date Rcvd Back 2:	Not reported
Date Rtnd to Inspector Corrections 3:	Not reported
Date Rcvd Back 3:	Not reported
Notification Status:	Not reported
Amendo:	Not reported
Notification Work Type:	Not reported
Notification Type:	Not reported
Work Type Flag:	Not reported
Certification Statement Date:	Not reported
Certification Statement Phone:	Not reported
Is The Facility a School or K-12?:	Not reported
Region:	Not reported
Priority:	Not reported
ARU:	Not reported
Is this a phased abatement project?:	Not reported
Ordered:	Not reported
Is This Project an Emergency?:	Not reported
Is Building Occupied?:	Not reported
High Profile:	Not reported
Ref Method:	Not reported
Analytical Method:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Start Date:	Not reported
Client Code:	Not reported
Client Name:	Not reported
License Number:	Not reported
File Number:	Not reported
License Status Description:	Not reported
Expiration Date:	Not reported
Original Date:	Not reported
Rank Effective Date:	Not reported
Mod Code:	Not reported
Area:	Not reported
Staff Operator ID:	Not reported
Inspection Number:	Not reported
Inspection Status:	Not reported
Disposition:	Not reported
Inspection Class Descriptio:	Not reported
Inspection Secondary Class Code:	Not reported
Inspection Secondary Class Code Description:	Not reported
Results:	Not reported
Inspection Number Grade:	Not reported

TX Financial Assurance 2:

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	274456
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2022
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04 TOP 000028792
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2023
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	254975
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y

SIGNATURE 2 (Continued) **U003566301**

Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2021
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04-TOP-000019174
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2022
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	237526
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2020
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	1 800 7224994
Policy Number:	04TOP000010223
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2021
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	218113
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2019
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	MID-CONTINENT INS CO
Issuer Phone:	Not reported
Policy Number:	04-TOP-005000860
Coverage Amount:	1,000,000

SIGNATURE 2 (Continued) **U003566301**

Coverage Expiration Date:	05/14/2020
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	202032
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2018
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2019
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	185161
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2017
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361336
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2018
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657

SIGNATURE 2 (Continued) **U003566301**

Finass ID:	167101
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2016
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2017
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	151557
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2015
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2016
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	133259
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y

SIGNATURE 2 (Continued) **U003566301**

Financial Assurance Begin Date:	05/14/2014
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2015
Ins Premium Pre-Paid For Entire Yr:	Yes
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	114320
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	2,000,000
Meets Financial Assurance Req Flag:	Y
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2013
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	Not reported
Policy Number:	9989929
Coverage Amount:	1,000,000
Coverage Expiration Date:	05/14/2014
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	8687
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	05/14/2012
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 0 0
Policy Number:	9989929
Coverage Amount:	2,000,000
Coverage Expiration Date:	05/14/2013
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

SIGNATURE 2 (Continued) **U003566301**

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	64997
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2011
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2012
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	64998
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2010
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2011
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	64999
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N

SIGNATURE 2 (Continued) **U003566301**

Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2009
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2010
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	65000
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	03/01/2008
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	TANK OWNERS MEMBERS INS CO
Issuer Phone:	1 800 3361338
Policy Number:	00241
Coverage Amount:	2000000
Coverage Expiration Date:	03/01/2009
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	Yes

Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX 78704
Region:	2
Facility ID:	79657
Finass ID:	65001
AI:	34911
Mechanism Type Other:	Not reported
Multiple Mechanism Types:	N
Coverage Amt per Annual Aggregate:	Not reported
Meets Financial Assurance Req Flag:	Not reported
Financial Responsibility Type:	INSURANCE OR RISK RETENTION
Corrective Action MET Flag:	Y
3rd Party MET Flag:	Y
Financial Assurance Begin Date:	01/01/1994
Date Financial Assurance Form Rec:	08/04/2021
Issuer Name:	Not reported
Issuer Phone:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Policy Number:	Unknown
Coverage Amount:	0
Coverage Expiration Date:	01/01/1901
Ins Premium Pre-Paid For Entire Yr:	No
Proof of Financial Assurance:	No

RDR:

RDR ID:	28230
Facility ID:	34911
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	2/14/2020
Due Date:	4/14/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	2/28/2020
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported
Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

RDR ID:	27935
Facility ID:	34911
RN:	Not reported
CN:	Not reported
Name:	SIGNATURE 2
Address:	608 S LAMAR BLVD
City,State,Zip:	AUSTIN, TX
Date Report Received:	12/13/2019
Due Date:	2/11/2020
Tank Owner:	TEXAS ENTERPRISES INC
Contact Person:	PAUL PEMBERTON
Report:	Suspected Release
Latest TCEQ Letter:	No system/site check
Date of Latest TCEQ Letter:	1/22/2020
Project Manager:	Marisol Marrero
Team:	Team 2
New LPST Number:	Not reported
Pre-Existing LPST Number:	Not reported
Comments:	Not reported
Review Coordinator:	Not reported
Date Release Reported:	Not reported
Suspected:	Not reported

SIGNATURE 2 (Continued) **U003566301**

Confirmed:	Not reported
NOLPST Letter Date:	Not reported
Date Report Returned:	Not reported
Region:	Not reported
DKC RDR (misfiled):	Not reported

Count: 1158 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSITN	S126810835	E 7TH STREET - NORTHWESTERN TO PLEASANT VALLEY	E. 7TH ST FROM NORTHWESTERN TO 400' EAST OF PLEASANT VALLEY.GONZALES ST FROM CALLES ST TO RAMOS ST.PLEASANT VALLEY RD FROM E. 7TH ST TO 400' SOUTH OF E. 7TH ST.407 SHADY LN - INCLUDES ALL OF PROPERTY	78702	TX CENTRAL REGISTRY
AUSTIN	S126754467	RAYMOND CONSTRUCTION 24 HOUR FITNESS-PFLUGERVILLE	12400 INTERSTATE 35 HWY	78741	TX CENTRAL REGISTRY
AUSTIN	S126568064	WALNUT CREEK PARK MAINT	1401 CEDAR BEND DR	78767	TX CENTRAL REGISTRY
AUSTIN	S128993583	SUMMIT AT WEST RIM ON MOUNT LARSON	SITE IS LOCATED APPROXIMATELY 0.25 MILES NORTH OF THE INTERSECTION OF THE HIGH ROAD AND WESTLAKE DRIVE ON THE EAST SIDE OF THE HIGH ROAD.	78746	TX CENTRAL REGISTRY
AUSTIN	S126953671	ALL STOR WESTLAKE SELF STORAGE	SOUTHSIDE OF BEE CAVES ROAD, 150 FEET EAST OF CRYSTAL CREEK DRIVE	78746	TX CENTRAL REGISTRY
AUSTIN	S126884217	WESTLAKE ATHLETIC AND COMMUNITY CENTER	SITE IS LOCATED JUST EAST OF THE INTERSECTION OF LOOP 360 AND WESTBANK DRIVE.	78746	TX CENTRAL REGISTRY
AUSTIN	S126864293	ISLAND AT WESTLAKE	SITE IS LOCATED APPROXIMATELY .10 MILES EAST OF THE INTERSECTION OF WESTLAKE DRIVE AND ISLAND KNOLL DRIVE.	78746	TX CENTRAL REGISTRY
AUSTIN	S128261622	1901 WESTLAKE DRIVE	SITE IS LOCATED APPROXIMATELY 0.4 MILES EAST OF THE INTERSECTION OF WESTLAKE DRIVE AND THE HIGH ROAD ON THE SOUTH SIDE OF WESTLAKE DRIVE.	78746	TX CENTRAL REGISTRY
AUSTIN	S126823922	DAVENPORT RANCH	LOCATED APPROXIMATELY 1 MILES SOUTH OF THE INTERSECTION OF LOOP 360 AND WESTLAKE ON THE EAST SIDE OF LOOP 360.	78746	TX CENTRAL REGISTRY
AUSTIN	S127057518	HALLAM HOMEBUILDING	FROM ITS INTERSECTION WITH LOOP 360, TRAVEL EAST ON WAYMAKER WAY, THEN TURN RIGHT ONTO FAR GALLANT DRIVE AND THEN PROCEED TO THE ADDRESS ON HALLAM OR SCENIC VIEW	78746	TX CENTRAL REGISTRY
AUSTIN	S126712437	PK-RE GREENSHORES ON LAKE AUSTIN	ON INTX PAPPYS WAY & BAREFOOT COVE TO EAST	78746	TX CENTRAL REGISTRY
AUSTIN	S126794355	REDEEMER PRESBYTERIAN PHASE I BUILDINGS	0.6 MILES EAST OF IH 35 ON MANOR ROAD, AT INTERSECTION OF ALEXANDER AVE. AND MANOR RD.	78722	TX CENTRAL REGISTRY
AUSTIN	S126943196	LENOX OAKS - WATER AND WASTEWATER & PONCA ST	PONCA STREET EAST FROM VALDEZ STREET	78741	TX CENTRAL REGISTRY
AUSTIN	S126834998	TXDOT-AUS-CSJ 0113-13-149	SH 71 IN TRAVIS COUNTY FROM EAST OF MONTOPOLIS DRIVE TO US 183	78741	TX CENTRAL REGISTRY
AUSTIN	S126806236	ROY G GUERRERO COLORADO RIVER PARK	ENTRANCE LOCATED JUST EAST OF THE INTERSECTION OF S. PLEASANT VALLEY RD. AND S. LAKESHORE BLVD.	78741	TX CENTRAL REGISTRY
AUSTIN	S123951860	STN NO 60107138	PORTABLE 2300 EAST BEN WHITE BLVD	78741	TX CENTRAL REGISTRY
AUSTIN	S128258669	PHASE 1 LAKE FRONT TRAIL IMPROVEMENTS	FAR EAST HOLLY STREET AND SOUTH FROM HOLLY ALONG THE TOWN LAKE BANK	78702	TX CENTRAL REGISTRY
AUSTIN	S126945161	EAST CESAR CHAVEZ	3309-3513 EAST CESAR CHAVES	78702	TX CENTRAL REGISTRY
AUSTIN	S123847590	MOTIVA ENTERPRISE	701 EAST AVE	78702	TX CENTRAL REGISTRY
AUSTIN	S123939791	CHERRY CREEK SEC 9-F	OFF 2700 BLOCK OF DAVIS LANE	78701	TX CENTRAL REGISTRY
AUSTIN	S126568792	AUSTIN CONVENTION CENTER EXPANSION	THIRD ST RED RIVER	78701	TX CENTRAL REGISTRY
AUSTIN	S126933651	CAPITOL CITY STEEL	INTERSECTION OF IH 35 EXIT 221 AUSTIN TX 78764	78764	TX CENTRAL REGISTRY
AUSTIN	S123953854	BEN WHITE	AUSTIN	78764	TX CENTRAL REGISTRY
AUSTIN	S126932979	VON TIRE	246 A BASTROP HIGHWAY AUSTIN TX 78741	78741	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126907249	RIVERSIDE III CONDOMINIUMS EASTWOOD AT RIVERSIDE	SITE IS LOCATED APPROXIMATELY 0.5 MILES WEST OF THE INTERSECTION OF RIVERSIDE DRIVE AND E. BEN WHITE BLVD.	78741	TX CENTRAL REGISTRY
AUSTIN	S126878019	BEN WHITE STORAGE	SITE IS LOCATED 0.10 MILES WEST OF THE INTERSECTION OF E. BEN WHITE BLVD. AND MONTOPOLIS DR. ON THE NORTH SIDE OF E. BEN WHITE BLVD.	78741	TX CENTRAL REGISTRY
AUSTIN	S126709794	TXDOT CSJ 013313069	ON SH 71 EAST FROM 0.25 MILES WEST OF BURLESON RD TO 0.87 MILES WEST OF BURLESON RD	78741	TX CENTRAL REGISTRY
AUSTIN	S126928769	BURLESON ROAD PRESSURE CONVERSION PHASE	LOCATED ALONG AND WITHIN THE RIGHTS-OF-WAY ALONG PORTIONS OF GROVE BLVD, MONTOPOLIS DRIVE, BURLESON ROAD, ALVIN DEVANE BLVD, AND EAST OLTORF STREET IN AUSTIN, TRAVIS COUNTY, TX.	78741	TX CENTRAL REGISTRY
AUSTIN	S126936909	METRO TIRE SERVICE	1220 BASTROP HWY E AUSTIN TX 78741	78741	TX CENTRAL REGISTRY
AUSTIN	S129000553	COUNTRY CLUB CREEK WEST	2,800 LINEAR FEET OF COUNTRY CLUB WEST CREEK FROM ITS HEADCUT TO ITS COLORADO RIVER CONFLUENCE. ACCESS SITE FROM ROY GUERRERO PARK. 400 GROVE BLVD.	78741	TX CENTRAL REGISTRY
AUSTIN	S126882220	PARK PLACE AT RIVERSIDE SUBDIVISION	LOCATED AT THE NORTHWEST CORNER OF E. RIVERSIDE DRIVE AND FRONTIER VALLEY DRIVE.	78741	TX CENTRAL REGISTRY
AUSTIN	S126568993	KENNETH A ROBERTSON JR	RIVERSIDE & BURTON	78741	TX CENTRAL REGISTRY
AUSTIN	S126703317	GREEN TREE PROPERTIES THE TRACE AT AUSTIN CONDOMINIUMS	ON NE RIVERSIDE DR & CROSSING PL	78741	TX CENTRAL REGISTRY
AUSTIN	S126904584	WALSH TARLTON OFFICE BUILDING	ON THE WEST SIDE OF WALSH TARLTON LN, APPROXIMATELY 0.10 MILES NORTH OF ITS INTERSECTION WITH HWY 360 S. CAPITAL OF TEXAS HWY.	78746	TX CENTRAL REGISTRY
AUSTIN	S126796598	RM 2244 TRAVIS COUNTY CSJ 2102-01-058	FROM 2000 FEET WEST OF LOOP 360 TO REDBUD TRAIL, EAST OF LOOP 360	78746	TX CENTRAL REGISTRY
AUSTIN	S126768579	BISHOP ABBEY HOMES CALERA OF BARTON CREEK	ON BARTON CREEK BLVD 0.5 MILES WEST OF LOST CREEK	78746	TX CENTRAL REGISTRY
AUSTIN	S126903096	LEDGEWAY	SITE IS LOCATED APPROXIMATELY .5 MILES WEST OF THE INTERSECTION OF LAUREL VALLEY ROAD AND WESTLAKE DRIVE ON THE NORTH SIDDE OF LEDGEWAY ST W.	78746	TX CENTRAL REGISTRY
AUSTIN	S126512002	WESTLAKE CENTER WASTEWATER TREATMENT FACILITY	LIFT STATION AT 701 S CAPITOL OF TEXAS HWY AUSTIN TX	78746	TX CENTRAL REGISTRY
AUSTIN	S126690260	EANES ISD FIRE LINE IMPROVEMENTS	ON LOOP 360 & WEST BANK DR	78746	TX CENTRAL REGISTRY
AUSTIN	S126783268	TRAVIS COUNTY WCID 20 MS4	FULL AREA WITHIN THE LEGAL BOUNDARIES OF TRAVIS COUNTY WCID 20 WITHIN THE AUSTIN URBANIZED AREA	78746	TX CENTRAL REGISTRY
AUSTIN	S126711770	CANYON RUN	ON APPROX .25 MILES WEST OF THE INTERSECTION OF BURNEY AND MESA OFF BURNEY	78746	TX CENTRAL REGISTRY
AUSTIN	S126587325	CITY OF ROLLINGWOOD	NORTH OF FM 2244 OFF EDGE GROVE ROAD IN ROLLINGWOOD AUSTIN TEXAS	78746	TX CENTRAL REGISTRY
AUSTIN	S126712442	MASTER BUILDERS SEVEN OAKS	APPROX 3 MILES WEST OF HWY 360 ON BEE CAVES ROAD	78746	TX CENTRAL REGISTRY
AUSTIN	S126712639	SEVEN OAKS	ON APPROX 3 MILES WEST OF HWY 360 AND BEE CAVES RD	78746	TX CENTRAL REGISTRY
AUSTIN	S126763704	CITY OF AUSTIN DAVENPORT HDD IMPROVEMENTS	ON DAVENPORT WASTEWATER LINE CONSTRUCTION IN CITY OF AUSTIN	78746	TX CENTRAL REGISTRY
AUSTIN	S126866821	CAPITAL RIDGE OFFICE	WEST SIDE OF HIGHWAY 360 0.25 MILE NORTH OF BEE CAVE ROAD	78746	TX CENTRAL REGISTRY
AUSTIN	S126812168	LOST CREEK MUD MS4	AREA WITHIN THE LOST CREEK SUBDIVISION IN TRAVIS COUNTY LIMITS THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78746	TX CENTRAL REGISTRY
AUSTIN	S126767008	SUN BUILDERS TARGET AT SOUTH PARK	ON SW CORNER OF SOUTH I-35 & WEST SLAUGHTER LN	78746	TX CENTRAL REGISTRY
AUSTIN	S126694322	SAN CLEMENTE AT DAVENPORT	ON 4320 WEST LAKE DR	78746	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126934450	SAMS TIRE & RADIATOR	608 ROBERT MARTINEZ JR ST AUSTIN TX 78702	78702	TX CENTRAL REGISTRY
AUSTIN	S126772632	CAPITAL METROPOLITAN TRANSPORTATION AUTHORITY RADAM LANE RECONSTRUCTION	ON RADAM LN AT CONGRESS AVE	78702	TX CENTRAL REGISTRY
AUSTIN	S128262953	T3 ATX EASTSIDE	SEC OF WALLER ST. AND E. 4TH ST.	78702	TX CENTRAL REGISTRY
AUSTIN	S126785082	ACWP GOVALLE 4 E 7TH ST AREA WASTEWATER IMPROV AND E 7TH ST AREA WATER REHAB	FROM THE INT. OF E. 7TH ST. AND CHICON ST. HEADING EAST ON E. 7TH ST. TO THE INT. OF E. 7TH ST. AND PLEASANT VALLY RD. AND NOTH ON PROSPECT AVE. TO 8TH ST AND WEST ON 8TH ST.	78702	TX CENTRAL REGISTRY
AUSTIN	S126762167	J&G MCLEAN CONSTRUCTION ACWP-GOVALLE 4 E 12TH ST ALLEY WASTEWATER IMPROVEMENTS	ON E 12TH ST ALLEY BETWEEN SALINA ST & POQUITO ST	78702	TX CENTRAL REGISTRY
AUSTIN	S126523584	CITY VENDING	7TH	78702	TX CENTRAL REGISTRY
AUSTIN	S126762364	AUSTIN UNDERGROUND E 13TH STREET ALLEY WASTEWATER	ON E 13TH ST ALLEY FROM POQUITO ST TO CHESTNUT ST	78702	TX CENTRAL REGISTRY
AUSTIN	S126931614	UPPER BOGGY CREEK MULTI-USE TRAIL PHASE 1	PROJECT STARTS AT 2804 E 12TH ST AND ENDS AT 1719 ALEXANDER AVE WINDING BEHIND EXISTING PARK FACILITIES, MAIN ENTRANCE IS AT 1316 1/2 ALEXANDER AVE	78702	TX CENTRAL REGISTRY
AUSTIN	S126811621	EAST 7TH STREET IMPROVEMENTS	EAST 7TH STREET FROM NAVASOTA STREET TO NORTHWESTERN AVENUE	78702	TX CENTRAL REGISTRY
AUSTIN	S126812079	LADY BIRD LAKEEAST 4TH ST DRAINAGE IMPROVEMENTS	FROM METZ PARK RUNNING WEST ON CANTERBURY ST TO MILDRED ST, THEN NORTH ON MILDRED ST TO SANTA RITA ST THEN WEST ON SANTA RITA ST TO MATAMOROS ST THEN NORTH ON MATAMOROS ST TO E. 5TH ST. THEN NORTHEAST	78702	TX CENTRAL REGISTRY
AUSTIN	S128207503	RAD TEC	AUSTIN TX 78702	78702	TX CENTRAL REGISTRY
AUSTIN	S126846779	5TH STREET FROM IH-35 TO ONION ST RECONSTRUCTION	SITE IS FROM 800 - 1500 EAST 5TH STREET FROM IH-35 EAST APPROX 0.5 MILES	78702	TX CENTRAL REGISTRY
AUSTIN	S123848377	PLANT NO 1	AUSTIN	78702	TX CENTRAL REGISTRY
AUSTIN	S128263000	CHEVRON HEARNE PIPELINE MP79.56	INTERSECTION OF SHADY LN AND EAST 1ST ST E CAESAR CHAVEZ	78702	TX CENTRAL REGISTRY
AUSTIN	S126832357	GUADALUPE-SALDANA AFFORDABLE HOMES	AT GOODWIN AVE WEBBERVILLE RD AUSTIN TX 78702	78702	TX CENTRAL REGISTRY
AUSTIN	S126879748	EASTSIDE VILLAGE - OFFICE	SITE IS LOCATED AT THE SOUTHEAST CORNER OF THE INTERSECTION OF COMAL ST. AND E. 6TH ST.	78702	TX CENTRAL REGISTRY
AUSTIN	S126915201	PLAZA SALTILLO BLOCKS A-E	ON THE SOUTH SIDE OF EAST 5TH STREET EXTENDING EAST OF IH 35	78702	TX CENTRAL REGISTRY
AUSTIN	S129001200	RED BLUFF ROW IMPROVEMENTS	EAST ALONG RED BLUFF ROAD FROM EAST CESAR CHAVEZ STREET	78702	TX CENTRAL REGISTRY
AUSTIN	S126955801	PUBLIC UTILITY COMMISSION WATER UTILITY REGULATION	1701 NORTH CONGRESS AVENUE	78711	TX CENTRAL REGISTRY
AUSTIN	S126514896	CITY OF AUSTIN WATER & WASTEWATER	APPROXIMATELY 1.75 MILES NORTH OF US HIGHWAY 290 EAST AND 0.75 MILE WEST OF THE INTERSECTION OF GILES ROAD AND BOYCE LANE IN TRAVIS COUNTY	78767	TX CENTRAL REGISTRY
AUSTIN	S128240308	FROST TIRES	SITE LOCATED IN AUSTIN TX	78714	TX CENTRAL REGISTRY
AUSTIN	S126699094	UT GREGORY GYMNASIUM AQUATICS COMPLEX	ON SPEEDWAY NE CORNER OF 21ST STREET	78712	TX CENTRAL REGISTRY
AUSTIN	S126767837	AUSTIN UNDERGROUND ACWP EAST 11TH STREET ALLEY	ON E 11TH ALLEY AND PROSECT AVE	78705	TX CENTRAL REGISTRY
AUSTIN	S126790430	JEFFERSON AT WEST CAMPUS	NW OF INTERSECTION NUECES ST & 26TH ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126758533	JPI JEFFERSON AT WEST CAMPUS	ON NW OF THE INTEX OF NUECES ST AND 26TH ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126781179	J&G MCLEAN ACWP WEST 5TH AND 6TH STREET AREA SANITARY SEWER REPLACEMENT	W 5TH & 6TH ST AND A SHORT SEGMENT ALONG WESTLAKE DR	78705	TX CENTRAL REGISTRY
AUSTIN	S126866429	DELL MEDICAL CENTER AT THE UNIV OF TX AT AUSTIN	AREA BOUNDED BY TRINITY ST E MLKI JR BLVD IH 35 AND E 15TH ST	78705	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126751174	OSCAR RENDA CONTRACTING DOWNTOWN WHITE HORSE TRAIL WASTEWATER IMPROVEMENTS PH 1	ON BETWEEN CESAR CHAVES ST TO CONGRESS AND 9TH ST TO LAVACA ST	78701	TX CENTRAL REGISTRY
AUSTIN	S126807067	BRAZOS STREETSCAPE	ON BRAZOS STREET FROM 3RD STREET TO 11TH STREET	78701	TX CENTRAL REGISTRY
AUSTIN	S123848206	HOWARD SYSTEMS 4TH ST PLT	4TH STREET PLANT	78701	TX CENTRAL REGISTRY
AUSTIN	S123848767	AUSTIN NURSING CENTER	LIVE OAK AT SO CONGRESS	78701	TX CENTRAL REGISTRY
AUSTIN	S123922113	PIONEER CONCRETE OF TEXAS	OLD SAN ANTONIO HWY	78701	TX CENTRAL REGISTRY
AUSTIN	S127060313	RED RIVER SOUTH REALIGNMENT 15TH TO 12TH STREET	RED RIVER REALIGNMENT BETWEEN 15TH STREET AND 12TH STREET	78701	TX CENTRAL REGISTRY
AUSTIN	S126599239	AUSTIN JCT RADIO RELAY STATION	10TH & LYNN ST	78701	TX CENTRAL REGISTRY
AUSTIN	S126860420	MOBIL STATION	E 7TH ST	78701	TX CENTRAL REGISTRY
AUSTIN	S126734864	CITY OF AUSTIN RIVERSIDE & BARTON SPRINGS RD STREET RECONST & UTILITY ADJUSTMENT	ON RIVERSIDE DR & BARTON SPRINGS RD BTWN S CONGRESS & S 1ST ST	78704	TX CENTRAL REGISTRY
AUSTIN	S128212419	TOWN LAKE BETWEEN CONGRESS & SOUTH FIRST STREETS	TOWN LAKE BETWEEN CONGRESS & SOUTH FIRST STREETS	78704	TX CENTRAL REGISTRY
AUSTIN	S126736187	PEABODY GENERAL CONTRACTORS ACWP GOVALL S 2ND ST TOWN LAKE PARK SEGMENT	ON NE CORNER OF BARTON SPRINGS & DAWSON	78704	TX CENTRAL REGISTRY
AUSTIN	S126691752	DITTMAR ROAD STREET & DRAINAGE IMPROVEMENTS	ON S 1ST ST TO MANCHACA RD	78704	TX CENTRAL REGISTRY
AUSTIN	S126782180	THE CROSSING AT BOULDIN CREEK	0.2 MI W OF INTERSECTION BARTON SKYWAY & S 5TH ST OFF OF BARTON SKYWAY	78704	TX CENTRAL REGISTRY
AUSTIN	S126707268	CITY OF AUSTIN SOUTH 1ST STREET STREET RECONSTRUCTION & UTILITY	ON INX OF SOUTH 1ST AND BEN WHITE W	78704	TX CENTRAL REGISTRY
AUSTIN	S126743317	FACILITIES REHABILITATION GOVALLE3 MONTOPOLIS DR AREA COUNTRY CLUB CREEK CHANNEL	ON RIVERSIDE & GROVE	78704	TX CENTRAL REGISTRY
AUSTIN	S126790640	ORC - GOVALLE 1 NEWTON STREET	INTERSECTION OF W. ELIZABETH AND SOUTH 1ST STREET	78704	TX CENTRAL REGISTRY
AUSTIN	S126866092	SOUTH CENTRAL WATERFRONT	NEC OF S FIRST ST AND E RIVERSIDE	78704	TX CENTRAL REGISTRY
AUSTIN	S126780744	CASH CONSTRUCTION WEST BOULDIN CREEK WASTEWATER INTERCEPTOR PHASE B IMPROVEMENTS	0.5 MI W OF CUMBERLAND RD & S 1ST ST	78704	TX CENTRAL REGISTRY
AUSTIN	S126789515	THE SOUTH 5TH	NE CORNER OF INTERSECTION OF S 5TH ST & W OLTORF ST	78704	TX CENTRAL REGISTRY
AUSTIN	S126898883	ELIZA SPRING DAYLIGHTING	N SIDE OF BARTON SPRINGS POOL	78704	TX CENTRAL REGISTRY
AUSTIN	S126701098	SOUTH 1ST STREET STREET RECONSTRUCTION & UTILITY ADJUSTMENT	ON BEN WHITE BLVD W & S 1ST ST	78704	TX CENTRAL REGISTRY
AUSTIN	S126786743	GOVALLE 2 HARPERS BRANCH AREA WASTEWATER LINE IMPROVEMENTS TUNNELING PROJECT	HARPERS BRANCH CREEK ALONG W FRONTAGE RD OF I 35 S APPROX 2150 FT S FROM INTEX WITH RIVERSIDE	78704	TX CENTRAL REGISTRY
AUSTIN	S126805820	BRAZOS STREETSCAPE	BRAZOS STREET FROM LADY BIRD LAKE TO 11TH STREET	78704	TX CENTRAL REGISTRY
AUSTIN	S126860551	ENVIROMENTAL IMPACT	18TH SAN ANTONIO		TX CENTRAL REGISTRY
AUSTIN	S126860535	ENVIRONMENTAL IMPACT IN WALLER CK	BETWEEN 6TH 7TH STREETS IN WALLER CREEK		TX CENTRAL REGISTRY
AUSTIN	S127539005	GATEWAY APARTMENTS	1618 W/ 6TH ST.		TX RDR
AUSTIN	S127531241	COMMERCIAL PROPERTY	6500 E 5TH ST		TX RDR
AUSTIN	S127539888	MURPHY USA 7015	626 N CESAR CHAVEZ RD		TX RDR
AUSTIN	S127538649	SPEEDI STOP TP 2535	1621 CESAR CHAVEZ		TX RDR
AUSTIN	S127536226	EXXON	9404 SOUTH CONGRESS		TX RDR
AUSTIN	S123848604	BROCK CONSULTING GROUP EAST OLTORF	EAST OLTORF	78701	TX CENTRAL REGISTRY
AUSTIN	S123848530	ABM MACHINERY	2325-A EAST BEN WHITE	78701	TX CENTRAL REGISTRY
AUSTIN	S126953609	CMTA DOWNTOWN STATION IMPROVEMENTS	LOCATED ALONG 4TH STREET, FROM ITS INTERSECTION WITH TRINITY STREET AND CONTINUING EAST TO ITS INTERSECTION WITH IH-35 SOUTH BOUND FRONTAGE ROAD	78701	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S123848268	CROSS COUNTRY INNS	6201 HWY 290 EAST	78701	TX CENTRAL REGISTRY
AUSTIN	S123941264	8103 RESEARCH BLVD	1401 YARRINGTON ROAD, EAST OF IH-35, (EXIT 210) KYLE, TX 78640	78701	TX CENTRAL REGISTRY
AUSTIN	S126925567	WALLER CREEK PARK	WALLER CREEK FROM EAST 15TH STREET TO EAST 12TH STREET	78701	TX CENTRAL REGISTRY
AUSTIN	S123941620	ONION CREEK READY MIX	508 EAST DESSAU RD	78701	TX CENTRAL REGISTRY
AUSTIN	S123848896	S HARI	6201 HWY 290 EAST	78701	TX CENTRAL REGISTRY
AUSTIN	S126523708	JAMES DREW RENTAL	406 EAST AVE	78701	TX CENTRAL REGISTRY
AUSTIN	S126890499	I M LEOS EXXON	1104 EAST AVE # IH35	78701	TX CENTRAL REGISTRY
AUSTIN	S126776145	CASH CONSTRUCTION CITY OF AUSTIN WINDSOR AREA WASTEWATER IMPROVEMENTS PHASE TWO	ON EAST OF THE INTERSECTION OF MO PAC EXPY AND WINDSOR RD OFF WINDSOR RD	78703	TX CENTRAL REGISTRY
AUSTIN	S128996923	WILDHORSE RANCH PARKSIDE TRACT A - SECTION 1	EAST OF THE INTERSECTION OF DECKER LANE AND LINDELL LANE	78704	TX CENTRAL REGISTRY
AUSTIN	S128997285	WILDHORSE RANCH PARKSIDE TRACT A - SECTION 1	EAST OF THE INTERSECTION OF DECKER LANE AND LINDELL LANE	78704	TX CENTRAL REGISTRY
AUSTIN	S126913121	TXDOT-AUS- I-35 NH 2016 108 CSJ 0015-13-378	I35 AT EAST OF OLTORF STREET	78704	TX CENTRAL REGISTRY
AUSTIN	S126685697	ZILKER PARK LANDFILL REMEDIATION	ON STRATFORD DR AND MOPAC ROW EAST	78704	TX CENTRAL REGISTRY
AUSTIN	S126511806	SHADY HOLLOW MUD	SOUTH OF SLAUGHTER LANE AND EAST OF BRODIE LANE		TX CENTRAL REGISTRY
AUSTIN	S126872695	ELIJA STREET IMPROVEMENTS	EAST OF THE INTERSECTION OF DUNN ST AT ELIJA STREET		TX CENTRAL REGISTRY
AUSTIN	S126526157	AUSTIN REHAB CNT	LOCATED APPROX 3.3 MILES EAST OF THE INTERSECTION OF IH-35 AND FM ROAD 1327, AND APPROX 1.4 MILES SOUTH OF THE INTERSECTION OF FM ROAD 1327 AND WRIGHT ROAD		TX CENTRAL REGISTRY
AUSTIN	S127528365	EXXON # 6-7897	1104 EAST		TX RDR
AUSTIN	S126940701	TFC CAPITOL EXPANSION PROJECT	SEC OF MARTIN LUTHER KING BLVD AND COLORADO STREET	78701	TX CENTRAL REGISTRY
AUSTIN	S127056140	TFC CAPITOL EXPANSION PROJECT	SOUTHEAST OF THE INTERSECTION OF E. MARTIN LUTHER KING JR. BLVD. AND COLORADO STREET	78701	TX CENTRAL REGISTRY
AUSTIN	S126736245	LONE STAR INFRASTRUCTURE MUELLER SECTION : DECONSTRUCTION PHASE 4	ON SEC OF IH35 & E 51ST ST	78722	TX CENTRAL REGISTRY
AUSTIN	S126712225	CATELLUS AUSTIN MUELLER SECTION 1 PHASE A SUBDIVISION	ON THE SE INT OF IH 35 AND EAST 51ST STREET	78722	TX CENTRAL REGISTRY
AUSTIN	S126726484	CATELLUS AUSTIN MUELLAR SECTION 1 DECONSTRUCTION PHASE 4	ON SE CORNER OF IH-35 & EAST 51ST ST	78722	TX CENTRAL REGISTRY
AUSTIN	S126734845	CATELLUS AUSTIN MUELLER SECTION 1 DECONSTRUCTION PLAN PHASES 2 & 3	ON SE OF INTX OF IH-35 & E 51ST ST	78722	TX CENTRAL REGISTRY
AUSTIN	S126761095	LEWIS CONTRACTORS AIRPORT BOULEVARD WASTEWATER PROJECT	ON 38TH 1/2 ST & AIRPORT BLVD	78722	TX CENTRAL REGISTRY
AUSTIN	S123848450	S LAMAR	S LAMAR	78701	TX CENTRAL REGISTRY
AUSTIN	S126060347	BRAZOS POINT	PORTABLE 2 MI WEST OF INTX FM200 & FM1434	78701	TX CENTRAL REGISTRY
AUSTIN	S123848559	5TH & PEDERNALES	AUSTIN	78701	TX CENTRAL REGISTRY
AUSTIN	S123848573	ONE STOP MOTERS	AUSTIN	78701	TX CENTRAL REGISTRY
AUSTIN	S124293666	THE UNIVERSITY OF TEXAS AT AUSTIN OIL SPILL RED RIVER ST AUSTIN TX	ON THE WEST SIDE OF RED RIVER ST APPRROXIMATELY 240 FEET SOUTH OF THE INTERSECTION OF MARTIN LUTHER KING JR BLVD AND RED RIVER ST	78701	TX CENTRAL REGISTRY
AUSTIN	S123848656	FM 1431 LAGO VISTA	FM 1431 10 MI WEST OF HWY 183	78701	TX CENTRAL REGISTRY
AUSTIN	S126073981	THOMAS C GREEN WATER TREATMENT PLANT DECOMMISSION	LOCATED JUST SOUTH OF THE INTERSECTION OF W. 2ND ST. AND SAN ANTONIO ST., ALONG THE WEST SIDE OF SAN ANTONIO ST.	78701	TX CENTRAL REGISTRY
AUSTIN	S123848923	EAGLE BODY AND PAINT SHOP	CORNER OF WEST MONROE AND SOUTH FIRST	78701	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S123943953	BLDG 794 CAPITOL UNIT	BLDG 794 CAPITOL UNIT 45TH & LAMAR	78701	TX CENTRAL REGISTRY
AUSTIN	S126855083	CITY OF AUSTIN NEW CENTRAL LIBRARY	NORTH SIDE OF CESAR CHAVEZ STREET WEST OF SHOAL CREEK	78701	TX CENTRAL REGISTRY
AUSTIN	S126759403	AUSTIN ENERGY WYE TRACT	BOUNDED BY 800 BLK 3RD ST TO THE NORTH UPRR TRACKS TO THE WEST AND SEAHOLM POWER PLANT TO THE EAST	78701	TX CENTRAL REGISTRY
AUSTIN	S126571700	SEAHOLM DISTRICT UPRR	NO ADDRESS RAILROAD RIGHT OF WAY AND POWER PLANT SOUTH SIDE OF 3RD ST BETWEEN WEST AVENUE AND LAMAR	78701	TX CENTRAL REGISTRY
AUSTIN	S126894424	MAINS TO CAPITOL COMPLEXAISD RECLAIMED WATER MAIN	AREA TO EAST AND SOUTH OF TEXAS CAPITOL BUILDING COMPLEX	78701	TX CENTRAL REGISTRY
AUSTIN	S123890165	CENTEX INGRAM	RR- 12 NORTH	78701	TX CENTRAL REGISTRY
AUSTIN	S126788957	SPRINGWOODS MUD MS4	491.54 ACRES OF LAND LOCATED WITHIN THE EXTRATERRITORIAL JURISDICTION OF AUSTIN LOCATED WITHIN THE AUSTIN URBANIZED AREA	78701	TX CENTRAL REGISTRY
AUSTIN	S123848420	PAUL WELC H RESIDENCE	AUSTIN	78701	TX CENTRAL REGISTRY
AUSTIN	S126809884	HEARNE PIPELINE MP 76.2 - AUSTIN	WOODED AREA ADJ TO MCBEE RD S OF FM 969 AUSTIN TRAVIS CO TX	78701	TX CENTRAL REGISTRY
AUSTIN	S123848954	ACE READY MIX	IH-35 NORTH	78701	TX CENTRAL REGISTRY
AUSTIN	S126762423	TEXAS ROAD & UTILITIES SEAHOLM UTILITY REDEVELOPMENT	ON INTEX OF 3RD ST & WEST AVE AT SEAHOLM POWER PLANT	78701	TX CENTRAL REGISTRY
AUSTIN	S123955710	GAREY CONSTRUCTION	WEST OF DEER LANE	78701	TX CENTRAL REGISTRY
AUSTIN	S123848974	VEHICLE REPAIR & REFINISH	10805-B NORTH LAMAR	78701	TX CENTRAL REGISTRY
AUSTIN	S123848543	9715 BURNET RD	AUSTIN	78701	TX CENTRAL REGISTRY
AUSTIN	S123906131	CAPITAL MEMORIAL PARK	14501 IH 35 NORTH	78701	TX CENTRAL REGISTRY
AUSTIN	S123848390	GENERATOR UNIT	10 MI WEST OF ANDICE	78701	TX CENTRAL REGISTRY
AUSTIN	S126844834	GROUP 17 STREET RECONSTRUCTION	8TH STREET BETWEEN WEST AVENUE AND CONGRESS AVENUE	78701	TX CENTRAL REGISTRY
AUSTIN	S123847497	AUTSIN ISD AUSTIN HIGH SCHOOL	1715 WEST AVE LOT ST	78701	TX CENTRAL REGISTRY
AUSTIN	S126742751	CRESTVIEW STATION CRESTVIEW STATION	ON BW INTX OF LAMAR BLVD & AIRPORT BLVD & LAMAR BLVD & MORROW ST	78731	TX CENTRAL REGISTRY
AUSTIN	S126927862	RENAISSANCE PARK	SITE IS LOCATED APPROXIMATELY 0.75 MILES SOUTHEAST OF THE INTERSECTION OF RANCH ROAD 2222 AND N CAPITOL OF TEXAS HIGHWAY.	78731	TX CENTRAL REGISTRY
AUSTIN	S126929282	GROVES AT SHOAL CREEK	LOCATED APPROXIMATELY 0.25 MILES SOUTHEAST OF THE INTERSECTION OF MOPAC AND W. 45TH STREET	78731	TX CENTRAL REGISTRY
AUSTIN	S126958414	BULL CREEK ROAD AND 45TH STREET ROW IMPROVEMENTS	SITE IS LOCATED AT THE INTERSECTION OF BULL CREEK ROAD AND 45TH STREET.	78731	TX CENTRAL REGISTRY
AUSTIN	S126775799	GRANDVIEW STREET PARTNERS GRANDVIEW CONDOMINIUMS	ON 1 BLK E OF INTX OF W 32ND ST & N LAMAR BLVD AT CONER OF W 32ND ST & GRANDVIEW	78731	TX CENTRAL REGISTRY
AUSTIN	S126930357	BULL CREEK OFF-SITE 12 INCH WATER DISTRIBUTION PIPELINE	LOCATED APPROXIMATELY 0.15 MILES SOUTHEAST OF THE INTERSECTION OF MOPAC AND W. 44TH STREET ALONG BULL CREEK ROAD FROM W. 44TH STREET NORTH TO W. 45TH STREET	78731	TX CENTRAL REGISTRY
AUSTIN	S126933352	AMERICAN CAR CARE	400 SOUTH FLORES AUSTIN TX 78731	78731	TX CENTRAL REGISTRY
AUSTIN	S126855868	BRADLEY RESIDENCE	5000 FAR WEST BLVD	78731	TX CENTRAL REGISTRY
AUSTIN	S126688736	UNIVERSITY OF TEXAS AT AUSTIN MS4	COVERS ALL AREAS OF THE UNIVERSITY OF TEXAS AT AUSTIN'S MS4	78712	TX CENTRAL REGISTRY
AUSTIN	S126822455	CAMP MABRY MS4	AREA WITHIN CITY OF AUSTIN LIMITS THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78703	TX CENTRAL REGISTRY
AUSTIN	S126750251	EIX & BLACKWELL 1902 & 1904 W 34TH STREET	ON 1902 & 1904 WEST 34TH STREET	78703	TX CENTRAL REGISTRY
AUSTIN	S126785044	AUSTIN CLEAN WATER PROJECT - GOVALLE WETHERSFIELD-HARTFORD PROJECT	EASON ALLEY, WEST LYNN, WINDSOR RD, HARTFORD RD, JARRATT AVE, HARRIS BLVD, WOOLDRIDGE ST, HARDOUIN AVE, WETHERSFIELD RD, NILES RD, HARTFORD RD, POLO RD.	78703	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126780159	PEABODY GENERAL CONTRACTORS ACWP-UPPER WALLER SSO ABATEMENT	ON GUADALUPE FROM 24TH ST TO 34TH ST	78703	TX CENTRAL REGISTRY
AUSTIN	S126713731	W L HAILEY SHOAL CREEK WASTE WATER IMPROVEMENTS 29TH TO 34TH ST TUNNEL	ON THE INT OF 29TH AND LAMAR	78703	TX CENTRAL REGISTRY
AUSTIN	S126685502	ENFIELD ROAD RECONSTRUCTION UTILITY ADJUSTMENTS AND STORM DRAIN IMPROVEMENTS	ON ENFIELD ROAD FROM EXPOSITION BLVD TO THE WEST END OF THE LAMAR BRIDGE	78703	TX CENTRAL REGISTRY
AUSTIN	S128213445	1101 A MONFRAIS ST AUSTIN TEXAS	1101 A MONFRAIS ST AUSTIN TEXAS 78703	78703	TX CENTRAL REGISTRY
AUSTIN	S126833178	AUSTIN ENERGY CRESCENT TRACT	CESAR CHAVEZ ST AND WALTER SEAHOLM DR AUSTIN TX 78703	78703	TX CENTRAL REGISTRY
AUSTIN	S126878585	SHOPS AT MARCUS ABRAMS	THE SUBJECT SITE IS LOCATED AT THE SOUTHWEST CORNER OF MARCUS ABRAMS BLVD AND MANCHACA ROAD IN AUSTIN TRAVIS COUNTY TEXAS	78703	TX CENTRAL REGISTRY
AUSTIN	S128998777	ST GEORGE MULTIFAMILY	ALONG THE EAST SIDE OF BURNET ROAD, JUST NORTH OF CULLEN AVENUE	78757	TX CENTRAL REGISTRY
AUSTIN	S126795476	TXDOT AUS CSJ 2102-01-058	RM 2244 FROM WEST OF LOOP 360 TO REDBUD TRAIL, EAST OF LOOP 360	78757	TX CENTRAL REGISTRY
AUSTIN	S126741366	JAY-REESE CONTRACTORS SHOAL CREEK ROSEDA STORMWATER IMPROVEMENTS PH 1	ON W 40TH STR ROSEDALE AVE WEST 39 AND SEIDERS AVE	78752	TX CENTRAL REGISTRY
AUSTIN	S126715129	CC CARLTON WALLER WASTEWATER IMPROVEMEN	ON AREA ALONG WALLER CREEK BTWN 46TH AND 45TH	78751	TX CENTRAL REGISTRY
AUSTIN	S126890378	WHITAKER FIELD & TENNIS COMPLEX RENOVATION AT UT AUSTIN	SOUTH OF THE INTERSECTION OF GUADALUPE ST AND 51ST STREET	78751	TX CENTRAL REGISTRY
AUSTIN	S126746506	CC CARLTON INDUSTRIES UPPER WEST WALLER-45TH AND SPEEDWAY WASTEWATER IMPROVMENTS	ON ALONG WALLER CREEK STARTING AT 46TH AND ENDING AT 45TH ST AND AVE H	78751	TX CENTRAL REGISTRY
AUSTIN	S129000288	KOENIG TOWNHOMES	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF THE INTERSECTION OF KOENIG LANE AND GUADALUPE STREET ON THE SOUTH SIDE OF KOENIG LANE.	78751	TX CENTRAL REGISTRY
AUSTIN	S126707330	CITY OF AUSTIN ACWP UPPER SHOAL LOWER HANCOCK BRANCH AT NORTH LOOP BLVD	ON 1600 BLK OF W NORTH LOOP BLVD	78751	TX CENTRAL REGISTRY
AUSTIN	S129000883	KOENIG TOWNHOMES	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF THE INTERSECTION OF KOENIG LANE AND GUADALUPE STREET ON THE SOUTH SIDE OF KOENIG LANE.	78751	TX CENTRAL REGISTRY
AUSTIN	S126766504	MAIN STREET HOMES-CS SENATE HILLS SECTION ONE	ON 4700 BLOCK OF E 51ST STREET	78751	TX CENTRAL REGISTRY
AUSTIN	S129000289	KOENIG TOWNHOMES	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF THE INTERSECTION OF KOENIG LANE AND GUADALUPE STREET ON THE SOUTH SIDE OF KOENIG LANE.	78751	TX CENTRAL REGISTRY
AUSTIN	S126776638	URBUILD CASWELL TOWNHOMES	ON CASWELL AVE & 47TH ST	78751	TX CENTRAL REGISTRY
AUSTIN	S126807265	WRI CENTRAL PHASE 3A RED RIVER TO UT TRANS MAIN	5012 NORTH IH 35	78751	TX CENTRAL REGISTRY
AUSTIN	S126701650	30TH STREET RECONSTUCTION N LAMAR BLVD TO SPEEDWAY	FROM N LAMAR BLVD TO SPEEDWAY ON 30TH ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126750211	NE CONSTRUCTION THE TRIANGLE BLOCK F IMPROVEMENTS	ON N OF TRIANGLE AVE & E OF 47TH ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126764616	BLOCK 21	BOUNDED BY W 3RD ST TO THE NORTH, WEST 2ND ST TO THE SOUTH, GUADALUPE ST TO THE WEST AND LAVACA ST TO THE EAST	78705	TX CENTRAL REGISTRY
AUSTIN	S126786395	WEST 5TH AND 6TH STREET AREA SANITARY SEWER REPLACEMENT	WEST 5TH AND 6TH STREET AND WESTLAKE DRIVE	78705	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126583500	U S P & F O FOR TX	35TH	78705	TX CENTRAL REGISTRY
AUSTIN	S126838693	EAST AVENUE SUBDIVISION IMPROVEMENTS	3400 NORTH IH 35 SOUTH BOUND SERVICE ROAD	78705	TX CENTRAL REGISTRY
AUSTIN	S126703938	CITY OF AUSTIN PUBLIC WORKS 30TH STREET RECONSTRUCTION	ON 30TH ST FROM N LAMAR BLVD TO SPEEDWAY	78705	TX CENTRAL REGISTRY
AUSTIN	S126710318	HAEGELIN CONSTRUCTION W UNIVERSITY AREA OVERFLOW ABATEMENT II LAMAR SIDEWALK	ON LAMAR BLVD AT SAN GABRIEL ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126754470	INTEGRATED BUILDERS BUCKINGHAM SQUARE APARTMENTS	711 N 32ND ST	78705	TX CENTRAL REGISTRY
AUSTIN	S126785162	THE CROSSING AT BOULDIN CREEK	0.2 MILES WEST OF THE INTERSECTION OF BARTON SKYWAY AND S. 5TH STREET, OFF OF BARTON SKYWAY.	78704	TX CENTRAL REGISTRY
AUSTIN	S126691922	TXDOT CSJ 001601091	ON IH-35 FROM SLAUGHTER LN TO NORTH OF LP 4	78704	TX CENTRAL REGISTRY
AUSTIN	S126784474	OSCAR RENDA CONTRACTING	RIVERSIDE DRIVE AND ALAMEDA DRIVE, WEST OF I.H. 35	78704	TX CENTRAL REGISTRY
AUSTIN	S126749744	ACE OFFICE	OFF HWY 290 WEST BRODIE LANE	78704	TX CENTRAL REGISTRY
AUSTIN	S126781139	2301 SOUTH 5TH STREET THE SOUTH 5TH	NEAR THE NORTHEAST CORNER OF THE INTERSECTION OF SOUTH 5TH ST & WEST OLTORF ST	78704	TX CENTRAL REGISTRY
AUSTIN	S126782299	GOVALLE 1-SOUTH 2ND ST WASTEWATER RE-ROUT & AREA IMPROVEMENTS SOUTH PHASE	SOUTH 2ND STREET (OLTORF TO WEST MONROE ST.)	78704	TX CENTRAL REGISTRY
AUSTIN	S126785261	GOVALLE 1-SOUTH 2ND STREET WASTEWATER RE-ROUTE & AREA IMPROVEMENTS NORTH PHASE	SOUTH 2ND STREET (WEST MONROE ST. TO BARTON SPRINGS RD.)	78704	TX CENTRAL REGISTRY
AUSTIN	S126701176	TEXAS ROAD & UTILITIES AUSTIN CLEAN WATER PROGRAM UPPER TANNEHILL	ON THE INTX OF E 51ST ST & OLD MANOR RD AT THE 5000 BLK OF OLD MANOR RD	78704	TX CENTRAL REGISTRY
AUSTIN	S126790204	SH 71 WEST ARROYO CANYON UPLANDS RIDGE	SH 71 WEST FROM ARROYO CANYON TO UPLANDS RIDGE		TX CENTRAL REGISTRY
AUSTIN	S126839843	US 290 WEST FM 1826 TO CONVICT HILL	SH 71 WEST FROM ARROYO CANYON TO UPLANDS RIDGE		TX CENTRAL REGISTRY
AUSTIN	S127525777	EXXON NO. 6-2013	7114 IH-35 NORTH		TX RDR
AUSTIN	S127524281	SUPER K GRO	6700 A GUADALUPE ST		TX RDR
AUSTIN	S128221430	WEST COW PATH WATER QUALITY POND	EAST OF WEST COW PATH AND NORTH OF DUVAL RD		TX CENTRAL REGISTRY
AUSTIN	S126749752	PECAN PARK CONDOMINIUMS & OFFICE PARK	PECAN PARK BLVD WEST OF US HIGHWAY 183 ON THE SOUTH PORTION OF PECAN PARK BLVD		TX CENTRAL REGISTRY
AUSTIN	S128209210	32ND ST 1 BLOCK FROM HARRIS	32ND ST 1 BLOCK FROM HARRIS	-	TX CENTRAL REGISTRY
AUSTIN	S126853116	SH71 SEGMENTS	SH 71 WEST VAIL DIVIDE TO SCENIC BROOK		TX CENTRAL REGISTRY
AUSTIN	S128213040	NORTH IH 35 ONION CREEK	NORTH IH 35 AT ONION CREEK		TX CENTRAL REGISTRY
AUSTIN	S126886515	LOOP 360 AT LOOP 1	LOOP 360 SOUTH OF LOOP 1 TO NORTH OF WALSH TARLTON		TX CENTRAL REGISTRY
AUSTIN	S126560939	NORTHWEST TRAVIS COUNTY MUD 2 PLANT 3	LOCATED APPROX 1500 FT WEST OF THE INTERX OF OF PLUMEWOOD DR AND SPICEWOOD CLUB DR IN THE SPICEWOOD AT BALCONES SUBDIVISION		TX CENTRAL REGISTRY
AUSTIN	S126840612	LOOP 1 AT ARBOR WALK	NBFE LOOP 1 NORTH OF US 183		TX CENTRAL REGISTRY
AUSTIN	S123846150	LONGHORN COMMUNITY DISP	5 MILES EAST US HIGHWAY 183 AND STATE HIGHWAY 71 INTERSECTION 0.25 MILES NORTH STATE HIGHWAY 71	0	TX CENTRAL REGISTRY
AUSTIN	S127526177	FORMER MONTGOMERY WARD	2901 CAPITOL OF TX HWY		TX RDR
AUSTIN	S127528356	EXXON 6-7450	1901 GUADALUPE & MLK		TX RDR
AUSTIN	S127538591	LAKE CREEK SHELL	13201 FM 620 NORTH		TX RDR
AUSTIN	S127535693	LEIF JOHNSON FORD	501 KOENIG LN		TX RDR
AUSTIN	S126516382	HIGHWAY 71 STORAGE & MHP	NORTH SIDE OF HWY 71 AT BOBWIRE RD		TX CENTRAL REGISTRY
AUSTIN	S127533750	CIRCLE K #2742103	11139 NORTH IH 35		TX RDR
AUSTIN	S127538406	CEFCO CONVENIENCE	14200 FM 620 WEST		TX RDR
AUSTIN	S126820078	SH 45 OCONNOR DRIVE	ALONG SH 45 TOLL WEST OF O CONNOR DRIVE		TX CENTRAL REGISTRY
AUSTIN	S127532346	TXDOT PARCEL 87 FORMER GRACELAND GROCERY	8600 US 290 WEST		TX RDR

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S123848535	9222 JAMESTOWN	AUSTIN	78718	TX CENTRAL REGISTRY
AUSTIN	S126717835	THE TRIANGLE	TRIANGLE TRACT OF LAND ON N LAMAR BLVD W GUADALUPE ST AND W 45TH ST	78751	TX CENTRAL REGISTRY
AUSTIN	S126845232	AUSTIN TRIANGLE APARTMENTS	THE SITE IS LOCATE4527 N LAMAR, AUSTIN, TX 78751 SITE IS LOCATED APPROXIMATELY .10 MILES NORTH OF THE INTERSECTION OF N LAMAR BLVD AND W 45TH STREET ON THE EAST SIDE OF N LAMAR BLVD. D AT	78751	TX CENTRAL REGISTRY
AUSTIN	S126701500	2001 TRIANGLE THE TRIANGLE	ON BETWEEN N LAMAR & W GUADALIPE & W 45TH ST	78751	TX CENTRAL REGISTRY
AUSTIN	S126766866	LAUGHLIN-THYSSEN BRIDGEPORT FAIRFIELD DRIVE WW IMPROVEMENTS ACWP	ON FROM 8803 BRIDGEPORT DR SOUTH 1741 FEET TO 816 FAIRFIELD DR	78758	TX CENTRAL REGISTRY
AUSTIN	S128999263	MORROW AND GAULT WATER & WASTEWATER PIPELINE RENEW	NORTHWEST OF THE INTERSECTION OF N. LAMAR BLVD. AND MORROW STREET	78757	TX CENTRAL REGISTRY
AUSTIN	S126710359	TXDOT CSJ 011401045	ON SPUR 69 FROM 1100 W OF LAMAR TO AIRPORT BLVD ON	78757	TX CENTRAL REGISTRY
AUSTIN	S126882878	IDEA PUBLIC SCHOOLS - RUNDBERG	SITE IS LOCATED APPROXIMATELY 0.25 MILES NORTH OF THE INTERSECTION OF IH-35 AND RUNDBERG LN.	78753	TX CENTRAL REGISTRY
AUSTIN	S123848162	AIRPORT	AUSTIN	78752	TX CENTRAL REGISTRY
AUSTIN	S126839336	CRESTVIEW STATION LOT 7 PHASE I	WEST OF THE INTERSECTION OF N. LAMAR BLVD. AND BANYON STREET	78752	TX CENTRAL REGISTRY
AUSTIN	S126855567	CRESTVIEW STATION LOT 7 PHASE 2	WEST OF THE INTERSECTION OF N LAMAR BLVD AND BANYON STREET	78752	TX CENTRAL REGISTRY
AUSTIN	S126888554	HIGHLAND INFRASTRUCTURE PHASE A	NE FROM THE INTERSECTION OF AIRPORT BLVD. AND HIGHLAND MALL BLVD.	78752	TX CENTRAL REGISTRY
AUSTIN	S126725881	CRESTVIEW STATION	TRIANGULAR PIECE OF LAND BOUNDED BY NORTH LAMAR TO THE EAST, RAILROAD TRACKS TO THE WEST AND MORROW ROAD TO THE NORTH	78752	TX CENTRAL REGISTRY
AUSTIN	S128995441	AIRPORT BLVD - N LAMAR TO 55TH ST	AIRPORT BLVD. - N. LAMAR TO 55TH ST.	78752	TX CENTRAL REGISTRY
AUSTIN	S126580244	BEKINS MOVING & STORAGE	201 ANDERSON LN	78752	TX CENTRAL REGISTRY
AUSTIN	S126610447	ECKERDS AT CEDAR BREAKS ROAD AND WILLIAMS DRIVE	SE CORNER OF CEDAR BREAKS RD AND WILLIAMS DR		TX CENTRAL REGISTRY
AUSTIN	S128209711	LAKE TRAVIS	LAKE TRAVIS NEAR ANDERSON MILL MARINA	-	TX CENTRAL REGISTRY
AUSTIN	S126724765	RM 620	RM 620 S OF ANDERSON MILL ROAD		TX CENTRAL REGISTRY
AUSTIN	S126743788	GABRIELS GROVE SECTION I	WEST OF INTERSECTION OF WILLIAMS DR & CR 245		TX CENTRAL REGISTRY
AUSTIN	S126561390	OLER PROPERTY	WEST OF 9150 RESEARCH BOULEVARD VACANT TRACT 6 ACRES		TX CENTRAL REGISTRY
AUSTIN	S127525778	SPEEDY STOP 410	7114 IH 35 N @ ST JOHNS		TX RDR
AUSTIN	S127526137	DIAMOND SHAMROCK 1322	8925 ANDERSON MILLRD		TX RDR
AUSTIN	S126921648	SRG MARAVILLA AT THE DOMAIN	ON THE SEC OF NEWMAN DRIVE AND KRAMER LN	78758	TX CENTRAL REGISTRY
AUSTIN	S126746451	HOME DEPOT USA THE HOME DEPOT-AUSTIN ARBO WALK	ON SEQ LOOP 1-MOPAC EXPY & W BRAKER LN	78758	TX CENTRAL REGISTRY
AUSTIN	S126849348	DOMAIN STEINER PAD	NW CORNER OF BRAKER LANE AND DOMAIN DRIVE	78758	TX CENTRAL REGISTRY
AUSTIN	S126817016	BRAKER LANE RIGHT TURN LANE AT HWY 183	4500 4618 BLOCK OF WEST BRAKER LANE	78758	TX CENTRAL REGISTRY
AUSTIN	S126846731	RANDOLPH BROOKS FEDERAL CREDIT UNION	NORTH OF THE INTERSECTION OF BURNET ROAD AND WEST BRAKER LANE	78758	TX CENTRAL REGISTRY
AUSTIN	S126696797	NORTH SERVICE CENTER	ON 10414 MCKALLA PL FROM HIGHWAY 183 NORTH BURNETTURN RIGHT UNNAMED ST JUST BEFORE BRAKER LN	78758	TX CENTRAL REGISTRY
AUSTIN	S126745550	JR HEINEMAN & SONS THE HOME DEPOT-AUSTIN ARBOR WALK TX	ON SEQ OF LOOP 1 7 W BRAKER LN	78758	TX CENTRAL REGISTRY
AUSTIN	S126924490	MEDICAL OAKS PAVILION PHASE IV	ON THE SWC OF RENFERT WAY AND CEDAR BEND DR.	78758	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126862825	FORT DESSAU	NORTHWEST INTERSECTION OF DESSAU RD AND CRYSTAL BEND DR	78753	TX CENTRAL REGISTRY
AUSTIN	S126801663	FERGUSON ROAD TUSCANY WAY ROW	FERGUSON RD. AT TUSCANY WAY	78753	TX CENTRAL REGISTRY
AUSTIN	S126704359	PIONEER CROSSING WEST ONE	ON BRAKER AT DESSAU RD	78753	TX CENTRAL REGISTRY
AUSTIN	S126919102	FORT DESSAU CONDOS	NORTHWEST OF THE INTERSECTION OF DESSAU ROAD AND CRYSTAL BEND DRIVE	78753	TX CENTRAL REGISTRY
AUSTIN	S126710822	PIONEER AUSTIN PIONEER CROSSING WEST SECTION 4	ON SE INTER DESSAU RD AND BRAKER LN	78704	TX CENTRAL REGISTRY
AUSTIN	S126572687	CITY OF AUSTIN RESOURCE RECOVERY INCINERATION FACILITY	HORNSBY BEND AREA NE COLORADO RIVER NW OF FM 973		TX CENTRAL REGISTRY
AUSTIN	S126514687	AUSTIN Y M B L SUNSHINE 2	THERMON BEND RD SPICEWOOD TEXAS		TX CENTRAL REGISTRY
AUSTIN	S126751984	QUENTIN CANYON RIDGE DRIVE SOUTH EXTENSION	ON E OF INTX OF IH-35 & E YAGER LN	78753	TX CENTRAL REGISTRY
AUSTIN	S126791036	WHITE ROCK AT CANYON RIDGE	SW OF INTERSECTION OF E YAGER LN & COPPERFIELD DR	78753	TX CENTRAL REGISTRY
AUSTIN	S126941248	IDEA YAGER	SW CORNER OF E. PALMER LN. AND E. YAGER LN.	78753	TX CENTRAL REGISTRY
AUSTIN	S126735787	TXDOT AUS CSJ 0015-13-259	ON IH 35 AT YAGER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126751087	CAPITAL EXCAVATION CANYON RIDGE DRIVE SOUTH EXTENSION	ON E OF INTEX OF IH 35 AND E YAGER LN	78753	TX CENTRAL REGISTRY
AUSTIN	S126867088	THE SPRINGS OF WALNUT CREEK PHASE 4	SW INTERSECTION OF E YAGER LN & COPPERFIELD DR	78753	TX CENTRAL REGISTRY
AUSTIN	S126863982	THE SPRINGS OF WALNUT CREEK PHASE 4	SOUTHWEST OF THE INTERSECTION OF YAGER LANE AND COPPERFIELD DRIVE	78753	TX CENTRAL REGISTRY
AUSTIN	S126781183	ALLIANCE RESIDENTIAL BUILDERS BROADSTONE GRAND AVENUE APARTMENTS	1710 GRAND AVE PKWY AUSTIN TX 78728	78728	TX CENTRAL REGISTRY
AUSTIN	S126726714	TRAVIS COUNTY TRANSPORTATION AND NATURAL RESOURCES SCOFIELD RIDGE PKWY	ON HOWARD LN BETWEEN SCOFIELD RIDGE PKWY & I-35 FRONTAGE	78728	TX CENTRAL REGISTRY
AUSTIN	S126767164	LINCOLN VISTA BUSINESS PARK	FROM I-35 GO WEST ON GRAND AVENUE PKWY, NORTH ON LONG VISTA DRIVE	78728	TX CENTRAL REGISTRY
AUSTIN	S126904602	WELLS BRANCH CENTER	WEST OF I-35 AND TO THE NORTHWEST OF CHEDDAR LOOP RD	78728	TX CENTRAL REGISTRY
AUSTIN	S129001172	CALIBER COLLISION - AUSTIN - WELLS BRANCH 0714	1916 CHEDDAR LOOP AUSTIN, TX 78728	78728	TX CENTRAL REGISTRY
AUSTIN	S126905574	WELLS BRANCH CENTER LD	WEST OF I-35 AND TO THE NORTHWEST OF CHEDDAR LOOP RD AUSTIN 78728	78728	TX CENTRAL REGISTRY
AUSTIN	S126781107	VIF II BROADSTONE AT GRAND AVENUE BROADSTONE GRAND AVENUE APARTMENTS	1710 GRAND AVE PKWY AUSTIN TX 78728	78728	TX CENTRAL REGISTRY
AUSTIN	S126843454	RACEWAY SINGLE FAMILY SUBDIVISION SECTION 1	GRAND AVENUE PARKWAY 800 FT. SOUTHEAST OF QUICK HILL RD & SOUTH OF AUSTIN RACEWAY PARK	78728	TX CENTRAL REGISTRY
AUSTIN	S126912079	TRAVESIA SUBDIVISION	LOCATED SOUTHEAST CORNER OF THE INTERSECTION OF GRAND AVENUE PARKWAY AND QUICK HILL ROAD OF AUSTIN 2 MILE ETJ AUSTIN 78728	78728	TX CENTRAL REGISTRY
AUSTIN	S126786235	WELLS BRANCH MUD MS4	AREA WITHIN THE WELLS BRANCH MUNICIPAL UTILITY DISTRICT BOUNDARIES WITHIN THE AUSTIN URBANIZED AREA	78728	TX CENTRAL REGISTRY
AUSTIN	S126909329	TRAVESIA SUBDIVISION	LOCATED SOUTH CORNER OF THE INTERSECTION OF GRAND AVENUE PARKWAY AND CANBERRA TRAIL CITY OF AUSTIN 2 MILE ETJ	78728	TX CENTRAL REGISTRY
AUSTIN	S126791432	NORTHTOWN MUD MS4	AREA WITHIN THE ETJ OF THE CITY OF AUSTIN THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
AUSTIN	S126870650	ABDALLAH OFFICE CONDOS	SITE IS LOCATED 0.1 MILES SOUTHEAST OF THE INTERSECTION AT FM 685 AND OLD AUSTIN HUTTO ROAD	78660	TX CENTRAL REGISTRY
AUSTIN	S126790994	TRAVIS COUNTY MS4	ALL AREAS WITHIN TRAVIS COUNTY LOCATED OUTSIDE FULLY-ANNEXED MUNICIPAL LIMITS INCLUDING THE UN-ANNEXED PORTION OF THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S123948226	TURNER	AUSTIN	78758	TX CENTRAL REGISTRY
AUSTIN	S126754968	NORTH FORK OFFICE	NW OF THE INTERSECTION OF N MOPAC AND PARMER LN S OF OAK CREEK DR	78758	TX CENTRAL REGISTRY
AUSTIN	S126763771	JC EVANS CONSTRUCTION SCOFIELD FARM VILLAS	ON W OF PARMER LN & E OF SCOFIELD FARMS DR	78758	TX CENTRAL REGISTRY
AUSTIN	S126862289	MOPAC IMPROVEMENT PROJECT MIP	PROJECT STARTS AT MOPAC LOOP1 AT PARMER LANE SOUTH TO CESAR CHAVES ST	78758	TX CENTRAL REGISTRY
AUSTIN	S123848929	NOVA BODY SHOP	AUSTIN	78758	TX CENTRAL REGISTRY
AUSTIN	S129000253	POINT SIX	SITE IS LOCATED APPROXIMATELY 0.25 MILES SOUTH OF THE INTERSECTION OF PARMER LANE AND SCOFIELD FARMS DRIVE.	78758	TX CENTRAL REGISTRY
AUSTIN	S126780847	MCNEIL TO GILLELAND CREEK T-147 TRANSMISSION LINE UPGRADE	7.6 M ELECTRIC LINE STARTING AT MCNEIL SUBSTATION (11900 KNOLLPARK, AUSTIN TX) HEADING E TO GILLELAND CREEK SUBSTATION	78758	TX CENTRAL REGISTRY
AUSTIN	S129000285	POINT SIX	SITE IS LOCATED APPROXIMATELY 0.25 MILES SOUTH OF THE INTERSECTION OF PARMER LANE AND SCOFIELD FARMS DRIVE.	78758	TX CENTRAL REGISTRY
AUSTIN	S126787096	SCOFIELD VILLAS	0.25 MILES WEST OF THE INTERSECTION OF W.PARMER LN. AND N. LAMAR BLVD. ON THE NORTH SIDE OF W. PARMER LN.	78758	TX CENTRAL REGISTRY
AUSTIN	S126773945	THE DOMAIN - 6.9 ACRE TRACT	SE CORNER OF DOMAIN DR AT ESPERANZA DR - AUSTIN TEXAS	78758	TX CENTRAL REGISTRY
AUSTIN	S126913102	DAVIES RANCH APARTMENT HOMES	SOUTH OF THE INTERSECTION OF PARMER LANE FM 734 AND DESSAU ROAD	78753	TX CENTRAL REGISTRY
AUSTIN	S126848070	DESSAU 38	NORTH OF THE INTERSECTION OF E PARMER LANE AND DESSAU ROAD	78753	TX CENTRAL REGISTRY
AUSTIN	S128243745	NORTHTOWN MUD FORCE MAIN REPLACEMENT	ALONG DESSAU ROAD AND HOWARD LANE, NORTH OF PARMER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126737028	AUSTECH BUSINESS PARK CENTRAL PARK NORTH II	ON 1 BLK E OF INTX OF N LAMAR BLVD AND W POWELL LN	78753	TX CENTRAL REGISTRY
AUSTIN	S126900392	PARMER 3.1 OFFICE BUILDING	NORTHEAST QUADRANT OF PARMER LANE AND MCCALLEN PASS	78753	TX CENTRAL REGISTRY
AUSTIN	S126868371	HOMEWOOD SUITES TECH RIDGE	SITE IS LOCATED APPROXIMATELY 0.5 MILES EAST THE INTERSECTION OF E. PARMER LANE AND IH 35 ON THE NORTH SIDE OF E. PARMER LANE.	78753	TX CENTRAL REGISTRY
AUSTIN	S126871085	AMBITION PARK 3A	THIS PROJECT IS BEING CONSTRUCTED ON TWO ADJACENT LOTS: 8312 CONNOR LANE AUSTIN, TEXAS 78753 1231 SHELDON COVE AUSTIN, TEXAS 78753	78753	TX CENTRAL REGISTRY
AUSTIN	S126834572	WELLS BRANCH CREEK APARTMENTS	NORTHWEST OF THE INTERSECTION OF N. LAMAR BLVD. AND W. PARMER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126811934	TXDOT - AUS - CSJ 3417-03-014	ON FM 734 FROM IH 35 TO DESSAU RD.	78753	TX CENTRAL REGISTRY
AUSTIN	S126864872	TXDOT-AUS-CSJ 0015-13-362	IH 35 FROM HOWARD LANE TO .2 MILES SOUTH OF PARMER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126899513	WALNUT PARK CROSSING EXTENSION	FROM WALNUT CREEK CROSSING TO LAMAR BLVD	78753	TX CENTRAL REGISTRY
AUSTIN	S126832932	TXDOT-AUS-CSJ-3417-03-015	FM 734 HARRIS BRANCH ROAD TO US 290	78753	TX CENTRAL REGISTRY
AUSTIN	S126758606	AUSTIN FILTER SYSTEMS REBID UPPER WALNUT REGIONAL DETENTION FACILITY	ON BETWEEN HOWARD LN AND PARMER LN W OF UNION PACIFIC RAILROAD	78753	TX CENTRAL REGISTRY
AUSTIN	S126072478	AARON PUGMILL 1 SN1264500BT	PORTABLE1 4 MI E OF SAMSUNG ON NORTH SIDE OF PARMER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126909421	TXDOT-AUS-CSJ 0914-04-298	US 290 AND FM 734 VARIOUS LOCATIONS IN TRAVIS COUNTY	78753	TX CENTRAL REGISTRY
AUSTIN	S126883647	WASHATOPIA - PARMER LANE	SITE IS LOCATED 0.25 MILES NORTHWEST OF THE INTERSECTION OF DESSAU RD. AND PARMER LANE ON THE NORTH SIDE OF PARMER LANE.	78753	TX CENTRAL REGISTRY
AUSTIN	S126917118	PARMER NORTH INFRASTRUCTURE	NORTHEAST QUADRANT ON PARMER LANE AND MCCALLEN PASS	78753	TX CENTRAL REGISTRY
AUSTIN	S126825076	VILLAGE AT NORTHTOWN POND - HARRIS RIDGE BLVD IMPROVEMENTS	14700 1/2 HARRIS RIDGE BLVD.AUSTIN, TX 78753	78753	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126898646	RETREAT AT TECH RIDGE SECTION 3 AND OFFSITE WATER LINE	NORTHEAST OF THE INTERSECTION OF E PARMER LANE AND DESSAU RD	78753	TX CENTRAL REGISTRY
AUSTIN	S126762837	AUS CSJ 3136-01-144	LP 1 .474 MI S OF DUVAL RD TO .95 MI N. OF PARMER LN	78753	TX CENTRAL REGISTRY
AUSTIN	S126866094	RESTORE RUNDBURG	SEC OF LAMAR AND BRAKER	78753	TX CENTRAL REGISTRY
AUSTIN	S126959471	IH35 & PARMER LN 0015-13-396	IH35 & PARMER LN, 0015-13-396	78753	TX CENTRAL REGISTRY
AUSTIN	S128246682	CAMBER RANCH	SOUTHEAST CORNER OF EAST PARMER LANE AND EAST YAGER LANE	78753	TX CENTRAL REGISTRY
AUSTIN	S126685797	HARRIS RIDGE BOULEVARD	ON INTERSECTION OF E PARMER LANE & HARRIS RIDGE BLVD	78753	TX CENTRAL REGISTRY
AUSTIN	S128254998	PARMER SECTOR 2	12829 PARMER RIDGE DRIVE	78753	TX CENTRAL REGISTRY
AUSTIN	S126824145	UNIVERSITY FEDERAL CREDIT UNION SCOFIELD FARMS	EAST OF THE INTERSECTION OF W PARMER LANE AND SCOFIELD FARMS DRIVE	78727	TX CENTRAL REGISTRY
AUSTIN	S126813575	PARMER LANE INTERCEPTOR	PHASE 1A ALONG PARMER LANE APPROXIMATELY 12000 LINEAR FEET FROM LAKE CREEK TO WALNUT CREEK	78727	TX CENTRAL REGISTRY
AUSTIN	S126950029	ANDYS 4	SITE IS LOCATED AT THE NORTHEAST CORNER OF THE INTERSECTION OF PARMER LANE AND METRIC BLVD.	78727	TX CENTRAL REGISTRY
AUSTIN	S126711758	NORTHWOOD RESERVE THE RESERVE AT NORTHW	ON 3000 BLOCK OF WEST PARMER LN	78727	TX CENTRAL REGISTRY
AUSTIN	S126785192	PARMER LANE FAMILY DENTISTRY	NS OF PARMER LN BTWN MOPAC AND AMHERST	78727	TX CENTRAL REGISTRY
AUSTIN	S126774159	RIATA VISTA OFFICE COMPLEX	S SIDE OF PARMER BETWEEN RIATA CIRCLE ON W	78727	TX CENTRAL REGISTRY
AUSTIN	S126890359	FM 734 AT LEGENDARY DRIVE	PARMER LN WEST OF LEGENDARY DR	78727	TX CENTRAL REGISTRY
AUSTIN	S128244421	ALLEGRO PARMER	SW OF AMHERST DR AND W PARMER LN	78727	TX CENTRAL REGISTRY
AUSTIN	S123848879	M & M	PARMER	78727	TX CENTRAL REGISTRY
AUSTIN	S126770501	AUSTIN ENGINEERING ENCHANTED FOREST SUBDIVISION	ON WEST INTEX OF W PARMER LN & AMHERST DR	78727	TX CENTRAL REGISTRY
AUSTIN	S126820792	NATIONAL INSTRUMENTS	12109 TECHNOLOYG BLVD AUSTIN TX 78727	78727	TX CENTRAL REGISTRY
AUSTIN	S126720416	SILVER CREEK SHOPPING CENTER II	W OF SILVER CREEK AND PARMER LANE	78727	TX CENTRAL REGISTRY
AUSTIN	S126703368	CC CARLTON WALNUT CREEK WELLS BRNACH EROSION FLOOD CONTROL DAM	W OF INT ON IH35 & PARMER LN	78727	TX CENTRAL REGISTRY
AUSTIN	S123848201	LAMAR	AUSTIN	78704	TX CENTRAL REGISTRY
AUSTIN	S126787132	LAMARBLUEBONNETTMANCHACA WATERWASTEWA IMP	MANCHACA @ S LAMAR, S LAMAR FROM MANCHACA - W MARY. BLUEBONNETT FROM S LAMAR - WRIGHT	78704	TX CENTRAL REGISTRY
AUSTIN	S126777008	GOVALLE 1-EAST OF LAMAR	11 AREAS BETWEEN S. LAMAR, 1ST STREET, MANCHACA, AND BARTON SPRINGS	78704	TX CENTRAL REGISTRY
AUSTIN	S128243910	SOUTH LAMAR RECONSTRUCTION - BARTON SPRINGS TO RIVERSIDE	SOUTH LAMAR BLVD. BETWEEN BARTON SPRINGS AND RIVERSIDE	78704	TX CENTRAL REGISTRY
AUSTIN	S129002204	SOUTH LAMAR BOULEVARD	SOUTH LAMAR BOULEVARD FROM RIVERSIDE DRIVE TO HIGHWAY 290	78704	TX CENTRAL REGISTRY
AUSTIN	S126810937	DOWNTOWN WASTEWATER TUNNEL PHASE 2	BEGINNING 500' S. OFLONGHOM DAM THAT/ADJACENT TO S. PLEASANT VALLEY RD.& ENDING NEAR THE INTERSECTION OF CESAR CHAVEZ ST. AND LAMAR BLVD.	78704	TX CENTRAL REGISTRY
AUSTIN	S126701126	CAPITAL EXCAVATION LAMAR BOULEVARD	INT N ON LAMAR & 24TH ST	78704	TX CENTRAL REGISTRY
AUSTIN	S126912254	TXDOT TRAVIS CO BEN WHITE & IH 35 LANDSCAPE DEV	FROM THE INTERSECTION OF IH 35 BEN WHITE BLVD IN SOUTH AUSTIN, THE JOB IS 2.5 MILES WEST OF IH 35 ON BEN WHITE BLVD BETWEEN THE SERVICE ROADS AND MAINLANES OF BEN WHITE.	78704	TX CENTRAL REGISTRY
AUSTIN	S126699923	DEL CURTO PLACE	ON DEL CURTO RD FROM I 35 & W 290 TAKE 290 W TO LAMAR TURN RIGHT	78704	TX CENTRAL REGISTRY
AUSTIN	S128213991	FUTURE WAL-MART @ 13000 N IH 35 AUSTIN	13000 N IH 35 AUSTIN TEXAS BLDG 1		TX CENTRAL REGISTRY
AUSTIN	S124132393	PORTABLE NIXON 2	NE CORNER FM 620 AND US 183 AUSTIN TX		TX CENTRAL REGISTRY
AUSTIN	S128240865	CHEM INTR PROD	AUSTIN TX		TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S124281504	ZACHARY-H394	PARADISE COVE MARINA ROCKY RIDGE RD AUSTIN TX SLIP D13		TX CENTRAL REGISTRY
AUSTIN	S124309256	YUNIET TRUCKING	HWY 290 & PARMER OVERPASS		TX CENTRAL REGISTRY
AUSTIN	S126948859	BERGSTROM AFB NIKE BATTERY BG-80	7 MI W OF AUSTIN		TX CENTRAL REGISTRY
AUSTIN	S128240796	THYSSEN DITCHING	AUSTIN TX		TX CENTRAL REGISTRY
AUSTIN	S126746989	THE VILLAGE	S INTERSECTION OF W PARMER LANE AND FM 620		TX CENTRAL REGISTRY
AUSTIN	S126728921	AVERY RANCH BOULEVARD EXTENSION	AT THE WESTERN END OF AVERY RANCH BOULEVARD (WEST OF PARMER LANE) CONTINUING APPROX 1300 LF TO 183 A		TX CENTRAL REGISTRY
AUSTIN	S128236895	TRAVIS COUNTY MUD 18	HWY 71 AT DEL DIOS DR AUSTIN TX		TX CENTRAL REGISTRY
AUSTIN	S126812639	WRTP FM 812 LANDFILL CLOSURE	AT ONION CREEK NEAR INTX OF MOORES BRIDGE RD AND FM 973 SE OF AUSTIN		TX CENTRAL REGISTRY
AUSTIN	S128212288	MILWOOD SECTION 15A PUD	COMMON LOT 167 @ HEINEMANN & SHREVEPORT DR IN AUSTIN		TX CENTRAL REGISTRY
AUSTIN	S128207552	MADRONE RANCH ESTATES	4 MI OFF HWY 71 ON HAMILTON POOL ROAD AUSTIN TX		TX CENTRAL REGISTRY
AUSTIN	S126948693	BERGSTROM AFB NIKE BATTERY BG-40	14 MI SE OF AUSTIN		TX CENTRAL REGISTRY
AUSTIN	S126062998	0.25 MILE SOUTH OF INTERSECTION OF TRACKS & W ANDERSON LN AUSTIN TEXAS	0.25 MILE SOUTH OF INTERSECTION OF TRACKS & WEST ANDERSON LANE AUSTIN TEXAS		TX CENTRAL REGISTRY
AUSTIN	S128214864	FM 969 AND DECKER LN AUSTIN	FM 969 AND DECKER LN AUSTIN TEXAS		TX CENTRAL REGISTRY
AUSTIN	S124282439	PERVIER-E787	AUSTIN YACHT CLUB		TX CENTRAL REGISTRY
AUSTIN	S128210462	EXXON STATION @ CORNER OF 183 & BURLESON RD	CORNER OF 183 & BURLESON RD AUSTIN TX		TX CENTRAL REGISTRY
AUSTIN	S127540171	AUSTIN VNK ALSF	AUSTIN BERGSTROM AIRPORT		TX RDR
AUSTIN	S111678556	ARCHIE FITZGERALD	-4632 S CONGRESS AVE		TX HIST UST
AUSTIN	S128729233	JULIAN PECINA	E 5TH& PLEASANT VALLEY		TX HIST UST
AUSTIN	S128728787	3131 EAST HWY 71 CONVENIENCE STORE	3131 EAST HWY 71		TX HIST UST
AUSTIN	S128729201	*********	BRAZOS, NORTH OF DRISKILL		TX HIST UST
AUSTIN	S128728848	LEOS SERVICE STATION	1149.5 AIRPORT BLVD		TX HIST UST
AUSTIN	S128729505		2200 ANDERSON LANE		TX HIST UST
AUSTIN	S128728780	QUIKTRIP NO 4126	861 BRAKER LN		TX HIST UST
AUSTIN	1003875589	AUSTIN GAS LIGHT CO.	CORNER OF 2ND AND COLORADO	78701	SEMS-ARCHIVE
AUSTIN	1027474730	APPLE	S SIDE OF PARMER BETWEEN RIATA CIRCLE ON W	78727	RCRA-VSQG
AUSTIN	2004730822		BARTON SPRINGS STREET		ERNS
AUSTIN	93169973		1ST ST AND STASSNEY		ERNS
AUSTIN	2008877180		1200 BLOCK OF WEST MARY ST.		ERNS
AUSTIN	9160844		32ND ST		ERNS
AUSTIN	2022348036		SUBDIVISION: WEST		ERNS
AUSTIN	89100619		CAMP MABRY, 35TH ST AND MOPAC		ERNS
AUSTIN	2018222124		1200 WEST 6TH STREET		ERNS
AUSTIN	2016149898		WEST BOULDIN CREEK		ERNS
AUSTIN	2015123719		I 35 NORTH		ERNS
AUSTIN	2013056978		HWY 1 AND WEST SLAUGHTER LANE		ERNS
AUSTIN	98422198		1.5 MI NORTH AND .75 MI		ERNS
AUSTIN	98423604		OFF WEST STAFFNEY ROAD		ERNS
AUSTIN	98452743		1200 OF WEST MARY ST		ERNS
AUSTIN	99479639		NEAR 3818 FAR WEST BLVD		ERNS
AUSTIN	99474064		2312 WEST PALMER LANE		ERNS
AUSTIN	98458277		WEST RIVERSIDE DR		ERNS
AUSTIN	2007840883		8600 BLOCK OF RESEARCH BLVD/HWY 183		ERNS
AUSTIN	2017200825		ANDERSON LANE		ERNS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	95314417		PICKLE RESEARCH CAMPUS		ERNS
AUSTIN	2019256708		10000 RESEARCH BLVD		ERNS
AUSTIN	2019256868		10000 RESEARCH BLVD		ERNS
AUSTIN	94234803		WEST ANDERSON LANE AND		ERNS
AUSTIN	2018224526		803 BATTLE BEND BLVD		ERNS
AUSTIN	96361212		AUSTIN SUB.		ERNS
AUSTIN	95294919		AUSTIN SUBDIVISION		ERNS
AUSTIN	2005749455		PARMER LANE		ERNS
AUSTIN	93153378		AUSTIN SWITCH YARD		ERNS
AUSTIN	93186416		AUSTIN SUB DIVISION		ERNS
AUSTIN	2020274663		I-35 SB		ERNS
AUSTIN	2023356875		PARMER ROAD & SAMSUNG PLANT ROAD		ERNS
AUSTIN	2023359593		INTERSTATE 35 AND		ERNS
AUSTIN	2001569337		I-35 / SOUTHBOUND		ERNS
AUSTIN	879167		30-14N 97-58W WEST OF HWY 290, WEST OF AUSTIN		ERNS
AUSTIN	2019256441		AUSTIN-BERGSTROM INTERNATIONAL AIRPORT		ERNS
AUSTIN	2014086590		AUSTIN TERMINAL		ERNS
AUSTIN	2022329422		SUBDIVISION: AUSTIN		ERNS
AUSTIN	2012010253		INTERSTATE 35 NB AT SLAUGHTER CREE IN AU		ERNS
AUSTIN	99476077		AUSTIN SUB / NEAREST		ERNS
AUSTIN	99471872		NORTH LAMAR AND		ERNS
AUSTIN	98458304		AUSTIN SUBDIVISION		ERNS
AUSTIN	97377181		AUSTIN SUB		ERNS
AUSTIN	97382864		HIGHWAY 290 ONTO I-35		ERNS
AUSTIN	2022356191		PARMER LANE AND SAMSUNG PLANT RD		ERNS
AUSTIN	S116697074	29WAT R907222	4TH	78701	TX LPST
AUSTIN	A100122086	HAYS CITY DBA TEX CON OIL	AUSTIN		TX AST
AUSTIN	S126880342	PROPOSED FAIRMONT HOTEL BLOCK 11	NEC CESAR CHAVEZ AND RED RIVER AUSTIN TX 78701	78701	TX TANKS, TX CENTRAL REGISTRY
AUSTIN	1027609119	FOUNDATION COMMUNITIES - AIRPORT	5900 & 5906 AIRPORT	78752	US BROWNFIELDS
AUSTIN	90060566		IH 35 & 1ST ST		HMIRS
AUSTIN	96030319		4909 B EAST CESAR CHAVES		HMIRS
AUSTIN	96120286		1901 E 51ST ST HANGER #2		HMIRS
AUSTIN	2022041083	7TH ST. WEST OF NECHES STREET	7TH ST. WEST OF NECHES STREET		HMIRS
AUSTIN	9900016928		NEW AIRPORT DR		HMIRS
AUSTIN	94050448		JCT BURNET RD AND BRAKER LANE		HMIRS
AUSTIN	9998110310		BRAKER LA		HMIRS
AUSTIN	2014003313	I-35 EXIT #248 TEXACO TRUCK ST	I-35 EXIT #248 TEXACO TRUCK ST		HMIRS
AUSTIN	S108891178	SIXTH STREET EXCHANGE	APPROX 15 YARDS NE OF THE INTERSECTION OF THE CAPITAL METRO AND EAST 6TH ST	78702	TX SPILLS, TX CENTRAL REGISTRY
AUSTIN	S106949303	CITY OF AUSTIN WATER & WASTEWATER	APPROXIMATELY 1.75 MILES NORTH OF US HIGHWAY 290 EAST AND 0.75 MILE WEST OF THE INTERSECTION OF GILES ROAD AND BOYCE LANE IN TRAVIS COUNTY	78767	TX SPILLS, TX ENF
AUSTIN	S107498531	TOWN LAKE BETWEEN CONGRESS & SOUTH FIRST STREETS	TOWN LAKE BETWEEN CONGRESS & SOUTH FIRST STREETS	78704	TX SPILLS
AUSTIN	S110507356	HORNSBY BEND SLUDGE FACILITY	LOCATED APPROX 0.9 MI NW OF THE INTERSECTION OF FM 973 AND SH 71 ON THE N BANK OF THE COLORADO RIVER		TX SPILLS
AUSTIN	S111326216	SHADY HOLLOW MUD	SOUTH OF SLAUGHTER LANE AND EAST OF BRODIE LANE		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S107499782	3310 EMMIT SHELTON BRIDGE AUSTIN TEXAS 78703	3310 EMMIT SHELTON BRIDGE AUSTIN TEXAS 78703	78703	TX SPILLS
AUSTIN	S113430398	PARKING LOT @ WALSH BOAT LANDING	END OF ENFIELD RD PARKING LOT ON RIGHT @ PARKING LOT OF WALSH BOAT LANDING AUSTIN TX 78703	78703	TX SPILLS
AUSTIN	S113434220	1101 A MONFRAIS ST AUSTIN TEXAS	1101 A MONFRAIS ST AUSTIN TEXAS 78703	78703	TX SPILLS
AUSTIN	S113439083	WEST COW PATH WATER QUALITY POND	EAST OF WEST COW PATH AND NORTH OF DUVAL RD		TX SPILLS
AUSTIN	S113435368	HART LN & FAR WEST BLVD INTERSECTION	HART LN & FAR WEST BLVD INTERSECTION		TX SPILLS
AUSTIN	S106951482	HARRIS BRANCH WWTP	LOCATED APPROX 1.75 MILES NORTH OF US HWY 290E AND .25 MILE WEST OF THE INTX OF GILES RD AND BOYCE LANE IN TRAVIS COUNTY.		TX SPILLS, TX ENF
AUSTIN	S106949938	SOUTH AUSTIN REGIONAL WWTP	BETWEEN ONION CREEK AND THE COLORADO RIVER, APPROXIMATELY 2 MILES WEST OF THEIR CONFLUENCE, APPROXIMATELY 2 MILES EAST OF THE FARM-TO-MARKET RD 973 CROSSING OF THE COLORADO RIVER AND 2 MILES NORTH OF		TX SPILLS, TX COMP HIST
AUSTIN	S113433319	EL REGIO	MIDDLE FISKVILLE AND RUNDBERG LN	78758	TX SPILLS
AUSTIN	S113429512	2900 BLOCK OF ANDERSON LANE	NEAR SCUBALAND BEHIND STRIP CENTER @ 2900 W ANDERSON LANE	78757	TX SPILLS
AUSTIN	S107640277	ANDERSON MILL WWTP	1700 FT SW OF THE INTERSECTION OF US HWY 183 AND FM 620 AND 5800 FT NW OF THE INTERSECTION OF US HWY 183 AND ANDERSON MILL RD		TX SPILLS, TX NPDES, TX COMP HIST
AUSTIN	S113440143	ANNIHILATOR CUSTOMS	SOUTHBOUND IH 35 BETWEEN BRAKER AND RUNDBERG	78753	TX SPILLS
AUSTIN	S113429530	TRAVEL TIME TOURS	EAST SIDE OF BRAKER LANE NEAR GRAHAM ELEMENTARY SCHOOL		TX SPILLS
AUSTIN	S113431487	CAR IN LAKE TRAVIS @ PACE BEND PARK	PACE BEND PARK		TX SPILLS
AUSTIN	S113429939	JIFFY LUBE 2480	10111 B NORTH LAMAR	78753	TX SPILLS
AUSTIN	S113437141	TRAVIS CAR CONNECTION	9725 N IH 35, AUSTIN, TX 78753	78753	TX SPILLS
AUSTIN	S113435370	12410 ALMEDA TRACE CIRCLE	12410 ALMEDA TRACE CIRCLE AUSTIN TEXAS 78727	78727	TX SPILLS
AUSTIN	S113437793	DOWNTOWN AUTOMOTIVE	SOUTHERN CORNER OF THE PROPERTY ON LAMAR	78704	TX SPILLS
AUSTIN	S112056420	UPRR LADY BIRD LAKE RAIL BRIDGE	RAIL BRIDGE SPANNING LADY BIRD LAKE AUSTIN TX 78704	78704	TX SPILLS, TX CENTRAL REGISTRY
AUSTIN	S113430579	DAVENPORT WATER RECLAMATION PLANT	LOCATED APPROX 2500 FT E OF CAPITAL OF TEXAS HWY LOOP 360 AND APPROX 730 FT N OF WESTLAKE DRIVE IN AUSTIN TX		TX SPILLS
AUSTIN	S121978758	SACHEM, 821 EAST WOODWARD, AUSTIN, TEXAS	SACHEM, 821 EAST WOODWARD, AUSTIN, TEXAS		TX SPILLS
AUSTIN	S113431331	PIONEER AUSTIN DEVELOPMENT LIMITED PROPERTY	DESSAU RD & SPRINKLE CUTOFF AUSTIN TX		TX SPILLS
AUSTIN	S121977459	9400 NORTH IH-35 @ RUNDBERG LANE, AUSTIN	9400 NORTH IH-35 @ RUNDBERG LANE, AUSTIN		TX SPILLS
AUSTIN	S113428796	SAIL HAVEN	POCAHONTAS DRIVE NEAR AUSTIN TEXAS		TX SPILLS
AUSTIN	S121977087	1420 AUSTIN PKWY., FT BEND CO.	1420 AUSTIN PKWY., FT BEND CO.		TX SPILLS
AUSTIN	S121977018	1150 JAIN LANE, AUSTIN	1150 JAIN LANE, AUSTIN		TX SPILLS
AUSTIN	S108528392	GULF STATION AT 3324 NORTHLAND DRIVE, AUSTIN	GULF STATION AT 3324 NORTHLAND DRIVE, AUSTIN		TX SPILLS
AUSTIN	S108528738	IBM PLANT SITE, BURNET RD., AUSTIN, TX.	IBM PLANT SITE, BURNET RD., AUSTIN, TX.		TX SPILLS
AUSTIN	S108528741	AT TEXAS INSTRUMENT FACILITY ON RESEARCH BLVD. IN AUSTIN	AT TEXAS INSTRUMENT FACILITY ON RESEARCH BLVD. IN AUSTIN		TX SPILLS
AUSTIN	S108529923	IN PARKING LOT OF CITY OF AUSTIN MAINT FAC #13 2412 KRAMER LA	IN PARKING LOT OF CITY OF AUSTIN MAINT FAC #13 2412 KRAMER LA		TX SPILLS
AUSTIN	S108529125	EAST AUSTIN TERMINAL, AIRPORT BLVD., AUSTIN	EAST AUSTIN TERMINAL, AIRPORT BLVD., AUSTIN		TX SPILLS
AUSTIN	S108529128	EAST AUSTIN TANK FARM, AIRPORT BLVD, MOBIL BULK TERMINAL, AUSTIN	EAST AUSTIN TANK FARM, AIRPORT BLVD, MOBIL BULK TERMINAL, AUSTIN		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S125339332	ABBOTT LABS, 3900 HOWARD LANE, AUSTIN RELEASE WENT TO ORNAMEN	ABBOTT LABS, 3900 HOWARD LANE, AUSTIN RELEASE WENT TO ORNAMEN		TX SPILLS
AUSTIN	S121978877	TEXAS INSTRUMENTS 12501 RESEARCH BLVD., AUSTIN	TEXAS INSTRUMENTS 12501 RESEARCH BLVD., AUSTIN		TX SPILLS
AUSTIN	S121978969	WESTLAKE DRIVE, .8 MI. E OF HWY 360,AUSTIN TX	WESTLAKE DRIVE, .8 MI. E OF HWY 360,AUSTIN TX		TX SPILLS
AUSTIN	S121977942	IH 35 @ 1ST ST., AUSTIN	IH 35 @ 1ST ST., AUSTIN		TX SPILLS
AUSTIN	S113428022	TRAVIS COUNTY LANDFILL	N OF US HIGHWAY 290 3 MILES W OF GILES ROAD 1.5 MILES E OF AUSTIN CITY LIMITS		TX SPILLS
AUSTIN	S121978759	SACHEM, 821 EAST WOODWARD, AUSTIN, TX	SACHEM, 821 EAST WOODWARD, AUSTIN, TX		TX SPILLS
AUSTIN	S113429778	BLUNN CREEK IN STACY PARK	EASTSIDE ST @ EAST ANNIE AUSTIN STACY PARK AUSTIN TX 78704		TX SPILLS
AUSTIN	S121977392	6300 BLOCK OF HWY 290 WEST @ WILLIAMSON CREEK, AUSTIN	6300 BLOCK OF HWY 290 WEST @ WILLIAMSON CREEK, AUSTIN		TX SPILLS
AUSTIN	S121977549	AT 3M PLANT, 6801 RIVER PLACE BLVD., AUSTIN, TX	AT 3M PLANT, 6801 RIVER PLACE BLVD., AUSTIN, TX		TX SPILLS
AUSTIN	S121978878	TEXAS INSTRUMENTS, 12501 RESEARCH BLVD., AUSTIN,TX	TEXAS INSTRUMENTS, 12501 RESEARCH BLVD., AUSTIN,TX		TX SPILLS
AUSTIN	S121978757	SACHEM, 821 E. WOODWARD, AUSTIN	SACHEM, 821 E. WOODWARD, AUSTIN		TX SPILLS
AUSTIN	S125339331	ABBOTT LABS FACILITY, 3900 HOWARD LANE,AUSTIN,TX 78728	ABBOTT LABS FACILITY, 3900 HOWARD LANE,AUSTIN,TX 78728		TX SPILLS
AUSTIN	S116231615	SACHEM FACIILITY, 821 E. WOODWARD, AUSTIN	SACHEM FACIILITY, 821 E. WOODWARD, AUSTIN		TX SPILLS
AUSTIN	S116231616	SACHEM, 821 E. WOODWARD, AUSTIN,TX	SACHEM, 821 E. WOODWARD, AUSTIN,TX		TX SPILLS
AUSTIN	S116231637	STATE HIGHWAY 290 AND JOHNNY MORRIS ROAD, AUSTIN, TX	STATE HIGHWAY 290 AND JOHNNY MORRIS ROAD, AUSTIN, TX		TX SPILLS
AUSTIN	S116231670	TETCO MOBIL RETAIL FACILITY 14701 BURNET ROAD, AUSTIN, TEXAS	TETCO MOBIL RETAIL FACILITY 14701 BURNET ROAD, AUSTIN, TEXAS		TX SPILLS
AUSTIN	S116231175	7211 FRED MORSE, AUSTIN (HWYS 183 & 290)	7211 FRED MORSE, AUSTIN (HWYS 183 & 290)		TX SPILLS
AUSTIN	S116231538	MOTOROLA GACILITY, 3501 ED. BLUESTEIN BLVD. AUSTIN	MOTOROLA GACILITY, 3501 ED. BLUESTEIN BLVD. AUSTIN		TX SPILLS
AUSTIN	S116231539	MOTOROLA, 3501 ED BLUESTEIN, BLVD., AUSTIN, 78721	MOTOROLA, 3501 ED BLUESTEIN, BLVD., AUSTIN, 78721		TX SPILLS
AUSTIN	S113434421	16500 BLOCK OF CAMERON ROAD AUSTIN	16500 BLOCK OF CAMERON ROAD AUSTIN		TX SPILLS
AUSTIN	S113433158	MOPAC @ MERRILTOWN RD	MOPAC @ MERRILTOWN RD AUSTIN TX		TX SPILLS
AUSTIN	S121978945	UT BALCONES RESEARCH CENTER,10100 BURNET ROAD IN AUSTIN, 78758	UT BALCONES RESEARCH CENTER,10100 BURNET ROAD IN AUSTIN, 78758		TX SPILLS
AUSTIN	S106991392	BETWEEN 7TH & MLK ON TERMINAL R-O-W, AUSTIN	BETWEEN 7TH & MLK ON TERMINAL R-O-W, AUSTIN		TX SPILLS
AUSTIN	S106993618	CONVICT HILL RD AT MOPAC, AUSTIN	CONVICT HILL RD AT MOPAC, AUSTIN		TX SPILLS
AUSTIN	S106995588	HWY 183 AND BURNET ROAD, AUSTIN	HWY 183 AND BURNET ROAD, AUSTIN		TX SPILLS
AUSTIN	S106995593	HWY 183 AND BURNET ROAD, AUSTIN	HWY 183 AND BURNET ROAD, AUSTIN		TX SPILLS
AUSTIN	S106988953	ROBERT MUELLER AIRPORT, AUSTIN	ROBERT MUELLER AIRPORT, AUSTIN		TX SPILLS
AUSTIN	S106990236	11159 BLOCK OF IH-35 NORTH, AUSTIN	11159 BLOCK OF IH-35 NORTH, AUSTIN		TX SPILLS
AUSTIN	S106995673	BEHIND STRIP CENTER AT 1818 W BEN WHITE BLVD., AUSTIN	BEHIND STRIP CENTER AT 1818 W BEN WHITE BLVD., AUSTIN		TX SPILLS
AUSTIN	S106990355	SHOPPER'S MART @ 4036 SOUTH IH-35, AUSTIN	SHOPPER'S MART @ 4036 SOUTH IH-35, AUSTIN		TX SPILLS
AUSTIN	S106992708	STORM SEWER AT 1ST & AUSTIN, BIG SPRING	STORM SEWER AT 1ST & AUSTIN, BIG SPRING		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S106993741	SHOAL CREEK ADJACENT TO TOM GREEN WATER TREATMENT PLANT, AUSTIN	SHOAL CREEK ADJACENT TO TOM GREEN WATER TREATMENT PLANT, AUSTIN		TX SPILLS
AUSTIN	S106995745	10900 FM 2222, AUSTIN (4 POINTS BOAT AND CAMPER STORAGE)	10900 FM 2222, AUSTIN (4 POINTS BOAT AND CAMPER STORAGE)		TX SPILLS
AUSTIN	S106987887	CREEK BEHIND 9721 MEADOW HEATH, AUSTIN	CREEK BEHIND 9721 MEADOW HEATH, AUSTIN		TX SPILLS
AUSTIN	S106987894	STOP-N-GO #915 AT 102 WEST POWELL LANE, AUSTIN	STOP-N-GO #915 AT 102 WEST POWELL LANE, AUSTIN		TX SPILLS
AUSTIN	S106990425	N OF MANOR ROAD ALONG WEST ACCESS ROAD OI IH-35, AUSTIN	N OF MANOR ROAD ALONG WEST ACCESS ROAD OF IH-35, AUSTIN		TX SPILLS
AUSTIN	S106990463	CITY ELECTRIC DEPARTMENT SERVICE YARD ON KRAMER LANE, AUSTIN	CITY ELECTRIC DEPARTMENT SERVICE YARD ON KRAMER LANE, AUSTIN		TX SPILLS
AUSTIN	S106990474	SEAHOLM POWER PLANT @ 1ST & WEST AVENUE, AUSTIN	SEAHOLM POWER PLANT @ 1ST & WEST AVENUE, AUSTIN		TX SPILLS
AUSTIN	S106991620	TODD LANE AND ST. ELMO, AUSTIN	TODD LANE AND ST. ELMO, AUSTIN		TX SPILLS
AUSTIN	S106993815	ROXIE DR. OFF HWY 183 NORTH, AUSTIN	ROXIE DR. OFF HWY 183 NORTH, AUSTIN		TX SPILLS
AUSTIN	S106994800	HIKE & BIKE TRAIL NEAR TOM GREEN WATER PLANT, AUSTIN	HIKE & BIKE TRAIL NEAR TOM GREEN WATER PLANT, AUSTIN		TX SPILLS
AUSTIN	S106989263	STATION #0107149 @ 2817 GUADALUPE, AUSTIN	STATION #0107149 @ 2817 GUADALUPE, AUSTIN		TX SPILLS
AUSTIN	S106994834	PARMER LANE AND RATTAN CREEK NORTHWEST O AUSTIN	PARMER LANE AND RATTAN CREEK NORTHWEST OF AUSTIN		TX SPILLS
AUSTIN	S106995897	TRAVIS COUNTRY TREATMENT PLANT, AUSTIN	TRAVIS COUNTRY TREATMENT PLANT, AUSTIN		TX SPILLS
AUSTIN	S106987990	BASEMENT SUMP AT 817 W. NORTH LOOP, AUSTIN	BASEMENT SUMP AT 817 W. NORTH LOOP, AUSTIN		TX SPILLS
AUSTIN	S106988020	SOUTHWESTERN BELL BUILDING @ 817 NORTH LOOP, AUSTIN	SOUTHWESTERN BELL BUILDING @ 817 NORTH LOOP, AUSTIN		TX SPILLS
AUSTIN	S106988068	TERMINAL AT 1135 SPRINGDALE ROAD, AUSTIN	TERMINAL AT 1135 SPRINGDALE ROAD, AUSTIN		TX SPILLS
AUSTIN	S106993911	SOUTHSIDE OF BEE CAVES RD. IN 3100 BLOCK, AUSTIN	SOUTHSIDE OF BEE CAVES RD. IN 3100 BLOCK, AUSTIN		TX SPILLS
AUSTIN	S106994946	WEST BOLDIN CREEK AT 500 BLOCK OF WEST LIVE OAK, AUSTIN	WEST BOLDIN CREEK AT 500 BLOCK OF WEST LIVE OAK, AUSTIN		TX SPILLS
AUSTIN	S106988106	ROBERT MUELLER AIRPORT AT 3600 BLK OF MANOR ROAD, AUSTIN	ROBERT MUELLER AIRPORT AT 3600 BLK OF MANOR ROAD, AUSTIN		TX SPILLS
AUSTIN	S106991868	INTERSECTION OF CINDY & TOMANET STREETS, AUSTIN	INTERSECTION OF CINDY & TOMANET STREETS, AUSTIN		TX SPILLS
AUSTIN	S106993946	443 CAPEHORN OFF E DESSAU RD., AUSTIN	443 CAPEHORN OFF E DESSAU RD., AUSTIN		TX SPILLS
AUSTIN	S106993950	TEXACO ON RR620, AUSTIN TX	TEXACO ON RR620, AUSTIN TX		TX SPILLS
AUSTIN	S106993991	HOLLY ST POWER PLANT WASTEWATER DISCHARG OUTFALL 101, AUSTIN	HOLLY ST POWER PLANT WASTEWATER DISCHARGE OUTFALL 101, AUSTIN		TX SPILLS
AUSTIN	S106994990	SOUTH 1ST & RIVERSIDE ON HIKE-AND-BIKE TRAIL, AUSTIN	SOUTH 1ST & RIVERSIDE ON HIKE-AND-BIKE TRAIL, AUSTIN		TX SPILLS
AUSTIN	S106988170	BLDG. 8, ROOM 105 AT CAMP HUBBARD, AUSTIN	BLDG. 8, ROOM 105 AT CAMP HUBBARD, AUSTIN		TX SPILLS
AUSTIN	S106989470	MLK TO FM 965 8 MI. E OF AUSTIN	MLK TO FM 965 8 MI. E OF AUSTIN		TX SPILLS
AUSTIN	S106990792	FOODLAND @ 9414 PARKFIELD, AUSTIN	FOODLAND @ 9414 PARKFIELD, AUSTIN		TX SPILLS
AUSTIN	S106995077	SOUTH SAN GABRIEL RIVER BRIDGE ON US 183 NW OF AUSTIN	SOUTH SAN GABRIEL RIVER BRIDGE ON US 183 NW OF AUSTIN		TX SPILLS
AUSTIN	S106988271	SUBSTATION AT IBM NEAR BRAKER LANE, AUSTIN	SUBSTATION AT IBM NEAR BRAKER LANE, AUSTIN		TX SPILLS
AUSTIN	S106990859	CO. RD. 208 TOWARDS FM 2004 @ AUSTIN BAYOU, DANBURY	CO. RD. 208 TOWARDS FM 2004 @ AUSTIN BAYOU, DANBURY		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S106990894	NEAR INTERSECTION OF RED BUD TRAIL & WESTLAKE DRIVE, AUSTIN	NEAR INTERSECTION OF RED BUD TRAIL & WESTLAKE DRIVE, AUSTIN		TX SPILLS
AUSTIN	S106991997	19TH & SAN JACINTO ON UT CAMPUS, AUSTIN	19TH & SAN JACINTO ON UT CAMPUS, AUSTIN		TX SPILLS
AUSTIN	S106994074	BERGSTROM AFB BASE EXCHANGE GARDEN SHOP, AUSTIN	BERGSTROM AFB BASE EXCHANGE GARDEN SHOP, AUSTIN		TX SPILLS
AUSTIN	S106995163	HWY 71 AND 620 OUTSIDE OF AUSTIN	HWY 71 AND 620 OUTSIDE OF AUSTIN		TX SPILLS
AUSTIN	S106989636	SHAMROCK STATION #962 @ 8538 RESEARCH BLVD., AUSTIN	SHAMROCK STATION #962 @ 8538 RESEARCH BLVD., AUSTIN		TX SPILLS
AUSTIN	S106989637	SHAMROCK STATION #963 @ 3706 GUADALUPE, AUSTIN	SHAMROCK STATION #963 @ 3706 GUADALUPE, AUSTIN		TX SPILLS
AUSTIN	S106990915	IH-35 @ MILE MARKER 249.5 OFF NORTHBOUND RAMP, AUSTIN	IH-35 @ MILE MARKER 249.5 OFF NORTHBOUND RAMP, AUSTIN		TX SPILLS
AUSTIN	S106990971	BULL CREEK & FM 2222, AUSTIN	BULL CREEK & FM 2222, AUSTIN		TX SPILLS
AUSTIN	S106995194	KRAMER LANE SERVICE CENTER, AUSTIN	KRAMER LANE SERVICE CENTER, AUSTIN		TX SPILLS
AUSTIN	S106995216	PARK @ QUAIL CREEK TOWNHOMES, AUSTIN	PARK @ QUAIL CREEK TOWNHOMES, AUSTIN		TX SPILLS
AUSTIN	S106988399	WEST OF LOOP 360 AND EAST OF LAKE AUSTIN	WEST OF LOOP 360 AND EAST OF LAKE AUSTIN		TX SPILLS
AUSTIN	S106989755	18TH & GUADALUPE BEHIND ARBY'S ROAST BEEF, AUSTIN	18TH & GUADALUPE BEHIND ARBY'S ROAST BEEF, AUSTIN		TX SPILLS
AUSTIN	S106992210	CONGRESS AVE. & S. FIRST STREET BRIDGE, AUSTIN	CONGRESS AVE. & S. FIRST STREET BRIDGE, AUSTIN		TX SPILLS
AUSTIN	S106992221	CANDLEWICK APARTMENTS 1516 BURTON DR., AUSTIN	CANDLEWICK APARTMENTS 1516 BURTON DR., AUSTIN		TX SPILLS
AUSTIN	S106995252	US 71 AND FM 973 SE AUSTIN, TRAVIS CO.	US 71 AND FM 973 SE AUSTIN, TRAVIS CO.		TX SPILLS
AUSTIN	S106988543	20-ACRE TRANSFORMER SERVICE YARD ON KRAME LANE, AUSTIN	20-ACRE TRANSFORMER SERVICE YARD ON KRAMER LANE, AUSTIN		TX SPILLS
AUSTIN	S106989782	EXXON #6-4743 (DOUG MILLIGAN EXXON) @ 3720 FM 2222, AUSTIN	EXXON #6-4743 (DOUG MILLIGAN EXXON) @ 3720 FM 2222, AUSTIN		TX SPILLS
AUSTIN	S106989823	SHAMROCK STATION #80 @ 3909 GUADALUPE, AUSTIN	SHAMROCK STATION #80 @ 3909 GUADALUPE, AUSTIN		TX SPILLS
AUSTIN	S106992249	34TH STREET AT SHOAL CREEK, AUSTIN	34TH STREET AT SHOAL CREEK, AUSTIN		TX SPILLS
AUSTIN	S106992257	HOLLY ST. POWER PLANT, AUSTIN	HOLLY ST. POWER PLANT, AUSTIN		TX SPILLS
AUSTIN	S106995322	ELECTRIC SUBSTATION AT US 183 AND BURNET ROAD, AUSTIN, 78758	ELECTRIC SUBSTATION AT US 183 AND BURNET ROAD, AUSTIN, 78758		TX SPILLS
AUSTIN	S106999639	IH-35 NORTH @ PARMER LANE, AUSTIN	IH-35 NORTH @ PARMER LANE, AUSTIN		TX SPILLS
AUSTIN	S106999649	COUNTY FLOOD CONTROL DITCH,1115 NEBRASKA @ AUSTIN ST, SOUTH H	COUNTY FLOOD CONTROL DITCH,1115 NEBRASKA @ AUSTIN ST, SOUTH H		TX SPILLS
AUSTIN	S107008118	FROM TRASH CONPACTOR, TEXAS INSTRUMENTS FACILITY IN AUSTIN, TX	FROM TRASH CONPACTOR, TEXAS INSTRUMENTS FACILITY IN AUSTIN, TX		TX SPILLS
AUSTIN	S107013604	PARMER LANE BETWEEN LAMPLIGHT VILLAGE AND KINERIDE, AUSTIN	PARMER LANE BETWEEN LAMPLIGHT VILLAGE AND KINERIDE, AUSTIN		TX SPILLS
AUSTIN	S107014631	NTW, 7930 NORTH 183, AUSTIN,TX (7930 ANDERSON SQUARE RD.)	NTW, 7930 NORTH 183, AUSTIN,TX (7930 ANDERSON SQUARE RD.)		TX SPILLS
AUSTIN	S107014886	AUSTIN COMM LANDFILL NORTH SIDE OF CELL IV-3-D, AUSTIN	AUSTIN COMM LANDFILL NORTH SIDE OF CELL IV-3-D, AUSTIN		TX SPILLS
AUSTIN	S107015065	AUSTIN, COMM LANDFILL, NORTH SIDE OF CELL IV-3-D, AUSTIN	AUSTIN, COMM LANDFILL, NORTH SIDE OF CELL IV-3-D, AUSTIN		TX SPILLS
AUSTIN	S107015087	CADILLAC DRIVE, BEHIND 7005 WELLS TRACE, KENNEDY ESTATES, AUSTIN,	CADILLAC DRIVE, BEHIND 7005 WELLS TRACE, KENNEDY ESTATES, AUSTIN,		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S107015172	CIRCLE K #32839 - 9105 HWY 290 E., AUSTIN	CIRCLE K #32839 - 9105 HWY 290 E., AUSTIN		TX SPILLS
AUSTIN	S107015525	16 MILES NW OF AUSTIN	16 MILES NW OF AUSTIN		TX SPILLS
AUSTIN	S107015534	IRS, 3651 IH 35 S., AUSTIN TX 78706	IRS, 3651 IH 35 S., AUSTIN TX 78706		TX SPILLS
AUSTIN	S107015635	APRON B. JP4 PIPELINE, BERGSTROM AFB, AUSTIN TX 78719	APRON B. JP4 PIPELINE, BERGSTROM AFB, AUSTIN TX 78719		TX SPILLS
AUSTIN	S106998630	FIRST STREET BRIDGE CONSTRUCTION SITE OVER TOWN LAKE, AUSTIN	FIRST STREET BRIDGE CONSTRUCTION SITE OVER TOWN LAKE, AUSTIN		TX SPILLS
AUSTIN	S106999657	4301 CRESTWOOD, AUSTIN	4301 CRESTWOOD, AUSTIN		TX SPILLS
AUSTIN	S107000622	DIAMOND SHAMROCK #80 3909 GUADALUPE, AUSTIN	DIAMOND SHAMROCK #80 3909 GUADALUPE, AUSTIN		TX SPILLS
AUSTIN	S107000662	4211 GILLIS, AUSTIN	4211 GILLIS, AUSTIN		TX SPILLS
AUSTIN	S107004817	ROADSIDE DITCH, WESTER KIRK DR., AUSTIN, TX AT LOW BRIDGE ST.	ROADSIDE DITCH, WESTER KIRK DR., AUSTIN, TX AT LOW BRIDGE ST.		TX SPILLS
AUSTIN	S107005946	PRINTING ROOM OF THE AMERICAN STATESMAN, S CONGRESS, AUSTIN	PRINTING ROOM OF THE AMERICAN STATESMAN, S CONGRESS, AUSTIN		TX SPILLS
AUSTIN	S107007048	IH-10 - COLORADO/AUSTIN COUNTY LINE ON SAN BERNARD RIVER BRID	IH-10 - COLORADO/AUSTIN COUNTY LINE ON SAN BERNARD RIVER BRID		TX SPILLS
AUSTIN	S107008182	2201 BEN WHITE, AUSTIN, TEXACO SERVICE STATION	2201 BEN WHITE, AUSTIN, TEXACO SERVICE STATION		TX SPILLS
AUSTIN	S107000715	HUDSON BEND & HIGHLINE, AUSTIN	HUDSON BEND & HIGHLINE, AUSTIN		TX SPILLS
AUSTIN	S107000728	INT. OF SPICEWOOD & SCOTLAND WELLS, AUSTIN	INT. OF SPICEWOOD & SCOTLAND WELLS, AUSTIN		TX SPILLS
AUSTIN	S107000747	1910 - 1912 HEARTHSIDE, AUSTIN	1910 - 1912 HEARTHSIDE, AUSTIN		TX SPILLS
AUSTIN	S107001705	ENGINEERING BLDG. U.T 204 E 26TH AUSTIN	ENGINEERING BLDG. U.T 204 E 26TH AUSTIN		TX SPILLS
AUSTIN	S107002772	E OF I-35 BETWEEN SOILLMAN LN. AND OAK HILL LN. IN S AUSTIN	E OF I-35 BETWEEN SOILLMAN LN. AND OAK HILL LN. IN S AUSTIN		TX SPILLS
AUSTIN	S107008247	MC DONALDS AT 520 WILLIAM CANNON, AUSTIN	MC DONALDS AT 520 WILLIAM CANNON, AUSTIN		TX SPILLS
AUSTIN	S107000794	N W CORNER LOOP 360 AT US290 AUSTIN,	N W CORNER LOOP 360 AT US290 AUSTIN,		TX SPILLS
AUSTIN	S107001775	HOTEL PARKING LOT @ IH-35 & RUNDBERG LN., AUSTIN	HOTEL PARKING LOT @ IH-35 & RUNDBERG LN., AUSTIN		TX SPILLS
AUSTIN	S107003854	MEDICAL ARTS SQUARE, KINKO'S 2901 RED RIVER AUSTIN	MEDICAL ARTS SQUARE, KINKO'S 2901 RED RIVER AUSTIN		TX SPILLS
AUSTIN	S107011708	LCRA SERVICE CENTER, 3505 MONTOPOLIS, AUSTIN,TX 78744	LCRA SERVICE CENTER, 3505 MONTOPOLIS, AUSTIN,TX 78744		TX SPILLS
AUSTIN	S107012745	SOUTHBOUND FRONTAGE ROAD & HWY 183 + BALCONES WOODS, AUSTIN, TX	SOUTHBOUND FRONTAGE ROAD & HWY 183 + BALCONES WOODS, AUSTIN, TX		TX SPILLS
AUSTIN	S107013763	BULL CREEK, AUSTIN, TX, OLD SPICEWOODS & HWY 360, EAST SIDE	BULL CREEK, AUSTIN, TX, OLD SPICEWOODS & HWY 360, EAST SIDE		TX SPILLS
AUSTIN	S107012806	BARTON CREEK BLVD., OFF BEE CAVE RD. AUSTIN	BARTON CREEK BLVD., OFF BEE CAVE RD. AUSTIN		TX SPILLS
AUSTIN	S107012866	MOTOROLA, OAK HILL PLANT, AUSTIN, TX (6730 HWY 290 WEST)	MOTOROLA, OAK HILL PLANT, AUSTIN, TX (6730 HWY 290 WEST)		TX SPILLS
AUSTIN	S106999944	ADAMS EXTRACT, 11206 IH35 SOUTH, AUSTIN	ADAMS EXTRACT, 11206 IH35 SOUTH, AUSTIN		TX SPILLS
AUSTIN	S106999949	HYDE PARK, 4308 AVE. D., AUSTIN	HYDE PARK, 4308 AVE. D., AUSTIN		TX SPILLS
AUSTIN	S107009586	1705 STONE RIDGE, AUSTIN,TX 78746	1705 STONE RIDGE, AUSTIN,TX 78746		TX SPILLS
AUSTIN	S107010687	STAR ENTERPRISE-13296 RESEARCH BLVD., AUSTIN,TEXAS	STAR ENTERPRISE-13296 RESEARCH BLVD., AUSTIN,TEXAS		TX SPILLS
AUSTIN	S107011868	DECKER LAKE, (LAKE LONG) DECKER CREEK POWER PLANT, AUSTIN	DECKER LAKE, (LAKE LONG) DECKER CREEK POWER PLANT, AUSTIN		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S106997824	SUBSTATION IN RICE 0.25 MILE NORTH OF FM 1126, NORTH AUSTIN	SUBSTATION IN RICE 0.25 MILE NORTH OF FM 1126, NORTH AUSTIN		TX SPILLS
AUSTIN	S106999020	NEAR SYMPHONY SQ., RED RIVER ST. BET. 11 & 12TH ST, AUSTIN	NEAR SYMPHONY SQ., RED RIVER ST. BET. 11 & 12TH ST, AUSTIN		TX SPILLS
AUSTIN	S107003095	WEST OF AUSTIN OF HWY 71, SO OF THE HWY & WEST SIDE OF BEE CREEK	WEST OF AUSTIN OF HWY 71, SO OF THE HWY & WEST SIDE OF BEE CREEK		TX SPILLS
AUSTIN	S107010791	DPS, KOEING & LAMAR, AUSTIN,TX	DPS, KOEING & LAMAR, AUSTIN,TX		TX SPILLS
AUSTIN	S107012980	BOULDIN CREEK DAWSON & RIVERSIDE 1017 BARTON SPRINGS RD., AUSTIN	BOULDIN CREEK DAWSON & RIVERSIDE 1017 BARTON SPRINGS RD., AUSTIN		TX SPILLS
AUSTIN	S107000113	TOM MILLER DAM, LAKE AUSTIN	TOM MILLER DAM, LAKE AUSTIN		TX SPILLS
AUSTIN	S107000126	AUSTIN AERO @ ROBERT MUELLER AIRPORT	AUSTIN AERO @ ROBERT MUELLER AIRPORT		TX SPILLS
AUSTIN	S107003172	2222 & BELL MOUTAIN,W. OF 2222 & 360 APPROX. 1 MI., AUSTIN	2222 & BELL MOUTAIN,W. OF 2222 & 360 APPROX. 1 MI., AUSTIN		TX SPILLS
AUSTIN	S107006421	ELF ASPHALT FACILITY-8803 N MOPAC-AUSTIN	ELF ASPHALT FACILITY-8803 N MOPAC-AUSTIN		TX SPILLS
AUSTIN	S107010859	BALCONES LIFT STATION, 7113 FM 967, AUSTIN, TX	BALCONES LIFT STATION, 7113 FM 967, AUSTIN, TX		TX SPILLS
AUSTIN	S107011975	RUBACH TATUM #1, GIDDING - AUSTIN CHALK FIELD, CR119, SOUTH O	RUBACH TATUM #1, GIDDING - AUSTIN CHALK FIELD, CR119, SOUTH O		TX SPILLS
AUSTIN	S107013031	REACTOR 28 PREHEATER, 7114 N. LAMAR, AUSTIN,TX,	REACTOR 28 PREHEATER, 7114 N. LAMAR, AUSTIN,TX,		TX SPILLS
AUSTIN	S106997995	AUSTIN CO. COURTHOUSE IN BELLVILLE, ST HWY 36	AUSTIN CO. COURTHOUSE IN BELLVILLE, ST HWY 36		TX SPILLS
AUSTIN	S107008730	TEXACO CHEMICAL, NORTH LAMAR & ST.JOHNS, AUSTIN, TX.	TEXACO CHEMICAL, NORTH LAMAR & ST.JOHNS, AUSTIN, TX.		TX SPILLS
AUSTIN	S107013080	CIRCLE K TRUCK STOP, HWY 290E, OUTSIDE AUSTIN CITY LIMITS	CIRCLE K TRUCK STOP, HWY 290E, OUTSIDE AUSTIN CITY LIMITS		TX SPILLS
AUSTIN	S107013105	825 B ED BLUESTEIN, AUSTIN,TX, 78721	825 B ED BLUESTEIN, AUSTIN,TX, 78721		TX SPILLS
AUSTIN	S106998051	LOOP 360 AT WEST BANK DR., AUSTIN, TX.	LOOP 360 AT WEST BANK DR., AUSTIN, TX.		TX SPILLS
AUSTIN	S107000239	I-35 AT SOUTH CONGRESS, AUSTIN 78745	I-35 AT SOUTH CONGRESS, AUSTIN 78745		TX SPILLS
AUSTIN	S107000283	BETWEEN 32ND AND 26TH ST AND IH-35 AND MEDICAL ARTS ST., AUSTIN	BETWEEN 32ND AND 26TH ST AND IH-35 AND MEDICAL ARTS ST., AUSTIN		TX SPILLS
AUSTIN	S107003317	AUSTIN COUNTY BELLVILLE NORTH ON HWY 36 9 MILES JUST OVER KEN	AUSTIN COUNTY BELLVILLE NORTH ON HWY 36 9 MILES JUST OVER KEN		TX SPILLS
AUSTIN	S107012206	CHALMER & EAST 2ND STREET, AUSTIN	CHALMER & EAST 2ND STREET, AUSTIN		TX SPILLS
AUSTIN	S107014288	I-35 & RIVERSIDE NO.BOUND LANE, AUSTIN, TX.	I-35 & RIVERSIDE NO.BOUND LANE, AUSTIN, TX.		TX SPILLS
AUSTIN	S107000348	500 ROBERT MARTINEZ BLVD., AUSTIN TX 78702	500 ROBERT MARTINEZ BLVD., AUSTIN TX 78702		TX SPILLS
AUSTIN	S107000362	ROBERT MUELLER AIRPORT, AUSTIN,	ROBERT MUELLER AIRPORT, AUSTIN,		TX SPILLS
AUSTIN	S107013319	SOUTHBOUND I-35, TOWN LAKE BRIDGE, AUSTIN	SOUTHBOUND I-35, TOWN LAKE BRIDGE, AUSTIN		TX SPILLS
AUSTIN	S107007891	8 MI. E. OF CLADWELL ON HWY 21 TO CR 218, AUSTIN CHALK FIELD	8 MI. E. OF CLADWELL ON HWY 21 TO CR 218, AUSTIN CHALK FIELD		TX SPILLS
AUSTIN	S107002457	BACK IN A FLASH 9TH & LAMAR, AUSTIN	BACK IN A FLASH 9TH & LAMAR, AUSTIN		TX SPILLS
AUSTIN	S107002470	SOUTHWESTERN BELL MANHOLE 12TH STREET AND LEONA AUSTIN	SOUTHWESTERN BELL MANHOLE 12TH STREET AND LEONA AUSTIN		TX SPILLS
AUSTIN	S107010221	CJC INC., IH-35 S., AUSTIN	CJC INC., IH-35 S., AUSTIN		TX SPILLS
AUSTIN	S107012441	MOTOROLA, ED BLUESTEIN SITE, AUSTIN, TX 78762	MOTOROLA, ED BLUESTEIN SITE, AUSTIN, TX 78762		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S107013412	3100 BLOCK OF MANCHACA, AUSTIN, TX	3100 BLOCK OF MANCHACA, AUSTIN, TX		TX SPILLS
AUSTIN	S106999579	BRIDGE ON SW PARKWAY 1 MILE E OF HWY 71, AUSTIN	BRIDGE ON SW PARKWAY 1 MILE E OF HWY 71, AUSTIN		TX SPILLS
AUSTIN	S117045801	IBM EASEMENT ON WEST SIDE OF BURNET RD @ IBM, AUSTIN	IBM EASEMENT ON WEST SIDE OF BURNET RD @ IBM, AUSTIN		TX SPILLS
AUSTIN	S117045861	KINGSBURY SUB STATION, 5001 ALF ST., AUSTIN	KINGSBURY SUB STATION, 5001 ALF ST., AUSTIN		TX SPILLS
AUSTIN	S117045865	LALLA CONVALESCENT CENTER, 2915 WEBBERVILLE RD., AUSTIN 78702	LALLA CONVALESCENT CENTER, 2915 WEBBERVILLE RD., AUSTIN 78702		TX SPILLS
AUSTIN	S117044979	1621 FESTIVAL BEACH, AUSTIN, TX.	1621 FESTIVAL BEACH, AUSTIN, TX.		TX SPILLS
AUSTIN	S117045363	AUSTIN AND 6TH, KAUFMAN	AUSTIN AND 6TH, KAUFMAN		TX SPILLS
AUSTIN	S117046295	SUB STATION. 3001 NORTHLAND, SE OF MOPAC & HWY 2222, AUSTIN	SUB STATION. 3001 NORTHLAND, SE OF MOPAC & HWY 2222, AUSTIN		TX SPILLS
AUSTIN	S112167919	0.25 MILE SOUTH OF INTERSECTION OF TRACKS & W ANDERSON LN AUSTIN TEXAS	0.25 MILE SOUTH OF INTERSECTION OF TRACKS & WEST ANDERSON LANE AUSTIN TEXAS		TX SPILLS
AUSTIN	S113430263	SEWER CONNECTION @ LOT 89 AUSTIN HILL MHP	LOT 89 AUSTIN HILL MOBILE HOME PARK		TX SPILLS
AUSTIN	S121978760	SACHEM, 821 EAST WOODWARD, AUSTIN,TX	SACHEM, 821 EAST WOODWARD, AUSTIN,TX		TX SPILLS
AUSTIN	S121977259	3 M, 6801 RIVER PLACE BLVD., AUSTIN	3 M, 6801 RIVER PLACE BLVD., AUSTIN		TX SPILLS
AUSTIN	S101722245	6816 DUNBARTON DRIVE, AUSTIN	6816 DUNBARTON DRIVE, AUSTIN		TX SPILLS
AUSTIN	S101733419	TDH COMPLEX, 1100 W. 49TH ST, AUSTIN	TDH COMPLEX, 1100 W. 49TH ST, AUSTIN		TX SPILLS
AUSTIN	S107016847	CAMP MABRY, AUSTIN	CAMP MABRY, AUSTIN		TX SPILLS
AUSTIN	S107016898	BOGGY CREEK AT HWY. 183 CROSSING, AUSTIN, 78721	BOGGY CREEK AT HWY. 183 CROSSING, AUSTIN, 78721		TX SPILLS
AUSTIN	S107016942	DIAMOND SHAMROCK #966, 8101 MESA, AUSTIN, 78731	DIAMOND SHAMROCK #966, 8101 MESA, AUSTIN, 78731		TX SPILLS
AUSTIN	S107018184	UNIVERSITY OF TEXAS CAMPUS, AUSTIN	UNIVERSITY OF TEXAS CAMPUS, AUSTIN		TX SPILLS
AUSTIN	S107015953	4700 BLOCK OF SO. LAMAR BLVD., AUSTIN TX	4700 BLOCK OF SO. LAMAR BLVD., AUSTIN TX		TX SPILLS
AUSTIN	S107015996	TEXACO AT IH-35 & E 9TH ST., AUSTIN,	TEXACO AT IH-35 & E 9TH ST., AUSTIN,		TX SPILLS
AUSTIN	S107016022	SW OF LANDFILL ON BERGSTROM AIR FORCE BASE, AUSTIN	SW OF LANDFILL ON BERGSTROM AIR FORCE BASE, AUSTIN		TX SPILLS
AUSTIN	S107018318	SOUTHBOUND FRONTAGE OF IH 35, SOUTH OF ONION CREEK, AUSTIN	SOUTHBOUND FRONTAGE OF IH 35, SOUTH OF ONION CREEK, AUSTIN		TX SPILLS
AUSTIN	S107018550	SOUTH BOUND FRONTAGE @ I-35 AND WILLIAM CANNON, AUSTIN	SOUTH BOUND FRONTAGE @ I-35 AND WILLIAM CANNON, AUSTIN		TX SPILLS
AUSTIN	S107017358	DESSAU MOBILE HOME PARK, 508 E. DESSAU RD., AUSTIN	DESSAU MOBILE HOME PARK, 508 E. DESSAU RD., AUSTIN		TX SPILLS
AUSTIN	S107016377	ADVANCED MICRO DEVICES (AMD), AUSTIN	ADVANCED MICRO DEVICES (AMD), AUSTIN		TX SPILLS
AUSTIN	S107016404	PARKING LOT ADJACENT TO CHEM. STORAGE BLDG. SMU #5, TI, AUSTIN	PARKING LOT ADJACENT TO CHEM. STORAGE BLDG. SMU #5, TI, AUSTIN		TX SPILLS
AUSTIN	S107017516	ARBORETUM PARKING LOT, GREAT HILS & US HWY 183, AUSTIN TX	ARBORETUM PARKING LOT, GREAT HILS & US HWY 183, AUSTIN TX		TX SPILLS
AUSTIN	S107016539	S.BOUND MAIN LANE, IH35 S, S. OF OLTORF., AUSTIN TX	S.BOUND MAIN LANE, IH35 S, S. OF OLTORF., AUSTIN TX		TX SPILLS
AUSTIN	S107016710	HEB REAR PARKING LOT, 2110 NEW SLAUGHTER LN., AUSTIN	HEB REAR PARKING LOT, 2110 NEW SLAUGHTER LN., AUSTIN		TX SPILLS
AUSTIN	S107016758	AUSTIN DIGNOSTIC CLINC MOPAC, AUSTIN, TX	AUSTIN DIGNOSTIC CLINC MOPAC, AUSTIN, TX		TX SPILLS
AUSTIN	S107016828	PARKING LOT, BLDG. 810, BERGSTROM AFB, S. SIDE OF BLDG., AUSTIN	PARKING LOT, BLDG. 810, BERGSTROM AFB, S. SIDE OF BLDG., AUSTIN		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S106988570	8810 N. LAMAR & PEYTON GIN ROAD, AUSTIN	8810 N. LAMAR & PEYTON GIN ROAD, AUSTIN		TX SPILLS
AUSTIN	S106988595	DECKER POWER PLANT @ 8003 DECKER LANE, AUSTIN	DECKER POWER PLANT @ 8003 DECKER LANE, AUSTIN		TX SPILLS
AUSTIN	S106988624	BASEMENT STORM DRAIN SUMP @ 817 WEST NORT LOOP, AUSTIN	BASEMENT STORM DRAIN SUMP @ 817 WEST NORTH LOOP, AUSTIN		TX SPILLS
AUSTIN	S106989889	HWY 183 AT COTTONMOUTH CREEK, SOUTH AUSTIN	HWY 183 AT COTTONMOUTH CREEK, SOUTH AUSTIN		TX SPILLS
AUSTIN	S106989904	S & C AUTO @ 1201 S. AUSTIN, HOWE	S & C AUTO @ 1201 S. AUSTIN, HOWE		TX SPILLS
AUSTIN	S106989922	SOUTHWOOD EXXON #4779 @ 1421 WEST BEN WHITE BLVD., AUSTIN	SOUTHWOOD EXXON #4779 @ 1421 WEST BEN WHITE BLVD., AUSTIN		TX SPILLS
AUSTIN	S106992335	7125 SCENIC LOOP, AUSTIN	7125 SCENIC LOOP, AUSTIN		TX SPILLS
AUSTIN	S106997356	3004 PENNY LANE, AUSTIN	3004 PENNY LANE, AUSTIN		TX SPILLS
AUSTIN	S106997407	STREET @ FRONT OF 13902 CONNER DOWNS, AUSTIN ETJ	STREET @ FRONT OF 13902 CONNER DOWNS, AUSTIN ETJ		TX SPILLS
AUSTIN	S106996588	SAN BERNARD RIVER BRIDGE ON IH-10, AUSTIN/COLORADO COUNTY LIN	SAN BERNARD RIVER BRIDGE ON IH-10, AUSTIN/COLORADO COUNTY LIN		TX SPILLS
AUSTIN	S106996809	STACY PARK POOL IN STACY PARK AT 300 E. LIVE OAK, AUSTIN, TX.	STACY PARK POOL IN STACY PARK AT 300 E. LIVE OAK, AUSTIN, TX.		TX SPILLS
AUSTIN	S106997010	LAKE WALTER E LONG (DECKER LAKE), EAST OF AUSTIN	LAKE WALTER E LONG (DECKER LAKE), EAST OF AUSTIN		TX SPILLS
AUSTIN	S106997095	RR 2244 W OF AUSTIN	RR 2244 W OF AUSTIN		TX SPILLS
AUSTIN	S106988708	SEAHOLM POWER PLANT @ 800 W. 1ST STREET, AUSTIN	SEAHOLM POWER PLANT @ 800 W. 1ST STREET, AUSTIN		TX SPILLS
AUSTIN	S106991199	ONE BLOCK EAST OF IH-35 ON WILLIAM CANNON DRIVE, AUSTIN	ONE BLOCK EAST OF IH-35 ON WILLIAM CANNON DRIVE, AUSTIN		TX SPILLS
AUSTIN	S106991229	CAMP MABRY, JUST OFF 35TH & MOPAC IN AUSTIN	CAMP MABRY, JUST OFF 35TH & MOPAC IN AUSTIN		TX SPILLS
AUSTIN	S106995481	SHOAL CREEK @ 34TH STREET, AUSTIN, 78756	SHOAL CREEK @ 34TH STREET, AUSTIN, 78756		TX SPILLS
AUSTIN	S106995492	BALCONES RESEARCH CENTER, AUSTIN, 78758	BALCONES RESEARCH CENTER, AUSTIN, 78758		TX SPILLS
AUSTIN	S106988755	0.5 MI. W OF BRODIE LANE NEAR NEW SLAUGHTER LANE, AUSTIN	0.5 MI. W OF BRODIE LANE NEAR NEW SLAUGHTER LANE, AUSTIN		TX SPILLS
AUSTIN	S106990057	5500 BLOCK OF IH-35, AUSTIN	5500 BLOCK OF IH-35, AUSTIN		TX SPILLS
AUSTIN	S106990124	EASTWOOD PARK @ LEONARD STREET, AUSTIN	EASTWOOD PARK @ LEONARD STREET, AUSTIN		TX SPILLS
AUSTIN	S106992480	26TH ST. NEAR UT LAW LIBRARY, AUSTIN	26TH ST. NEAR UT LAW LIBRARY, AUSTIN		TX SPILLS
AUSTIN	S106992491	WALNUT CREEK STP ON WEBBERVILLE RD., AUSTIN	WALNUT CREEK STP ON WEBBERVILLE RD., AUSTIN		TX SPILLS
AUSTIN	S106993555	STOP-N-GO @ SLAUGHTER & BRODIE, AUSTIN	STOP-N-GO @ SLAUGHTER & BRODIE, AUSTIN		TX SPILLS
AUSTIN	S106997280	3M- AUSTIN CENTER, 6801 RIVERPLACE BLVD., AUSTIN, TX.	3M- AUSTIN CENTER, 6801 RIVERPLACE BLVD., AUSTIN, TX.		TX SPILLS
AUSTIN	S113428574	AVERY RANCH	PARMER LANE BETWEEN RR620 & BRUSHY CREEK RD		TX SPILLS
AUSTIN	S113429560	HWY RIGHT OF WAY ON N SIDE OF 2222 100 YDS W OF 360 AUSTIN	N SIDE OF 2222 100 YARDS WEST OF 360 AUSTIN		TX SPILLS
AUSTIN	S113429513	EXXON @ WELLS BRANCH & IH 35 DETENTION POND	DETENTION POND BEHIND EXXON @ WELLS BRANCH AND IH35 AUSTIN TX		TX SPILLS
AUSTIN	S113433138	MILWOOD SECTION 15A PUD	COMMON LOT 167 @ HEINEMANN & SHREVEPORT DR IN AUSTIN		TX SPILLS
AUSTIN	S113432528	COLORADO RIVER @ LAMAR BRIDGE	COLORADO RIVER WEST OF LAMAR BRIDGE APPROXIMATELY 100 FT WEST TOWARDS MOPAC AUSTIN TX		TX SPILLS
AUSTIN	S113428312	MADRONE RANCH ESTATES	4 MI OFF HWY 71 ON HAMILTON POOL ROAD AUSTIN TX		TX SPILLS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S113429936	JORDAN CONTRACTORS	2ND STREET, BETWEEN BRAZOS AND SAN JACINTO, AUSTIN, TX		TX SPILLS
AUSTIN	S113429519	NAPA DR & CARLSBAD DRIVE DETENTION POND AUSTIN	DETENTION POND AT NAPA DRIVE AND CARLSBAD DRIVE AUSTIN		TX SPILLS
AUSTIN	S113428322	EL REGIOS	MIDDLE FISKVILLE ROAD ABOUT 50 YEARDS BEHIND JACK IN THE BOX AUSTIN		TX SPILLS
AUSTIN	S113430422	HACKETT PROPERTY	12210 & 12300 CALDVIS RD TRAVIS COUNTY AUSTIN TX		TX SPILLS
AUSTIN	S112301085		TEXACO AT IH-35 & E 9TH ST.		TX SPILLS 90
AUSTIN	S112301766	TEXAS CONSTRUCTION SERVICE	IH 35 @ 1ST ST.		TX SPILLS 90
AUSTIN	S112301640	WASTE MANAGEMENT OF TEXAS INC	290 EAST		TX SPILLS 90
AUSTIN	S112323149	UNIV OF TEX, BALCONES RESEARCH	WEST SIDE OF BLDG.133		TX SPILLS 90
AUSTIN	S112300214	UNK	BETWEEN 32ND AND 26TH ST AND IH-35 AND M		TX SPILLS 90
AUSTIN	S112310893	CHEMLAWN	LOOP 360 AT WEST BANK DR.		TX SPILLS 90
AUSTIN	S112305680	UNKNOWN	ROXIE DR. OFF HWY 183 NORTH		TX SPILLS 90
AUSTIN	S112314939	TEXAS INSTRUMENTS	TEXAS INSTRUMENTS 12501 RESEARCH BLVD.		TX SPILLS 90
AUSTIN	S112298669	LIQUID ENVIRONMENTAL SOLUTIONS OF TEXAS	LOTS 1 AND 2 AIRPORT TWO SUBDIVISION LOCATION OF EVNIRO-WASTE BUILDING		TX SPILLS 90
AUSTIN	S112310689	CITY OF AUSTIN PUBLIC WORKS	HOTEL PARKING LOT @ IH-35 & RUNDBERG LN.		TX SPILLS 90
AUSTIN	S112306156	MIKE ORUKE	707 RIVER BEND RD.		TX SPILLS 90
AUSTIN	S112318022	CITY OF SUGARLAND	1420 AUSTIN PKWY.		TX SPILLS 90
AUSTIN	S112320623	BORDER TO BORDER TRUCKING	IH-35 NORTH @ PARMER LANE		TX SPILLS 90
AUSTIN	S112322238	COASTAL TRANSPORT	TEXACO 2201 WEST BEN WHITE BLVD. AUSTIN		TX SPILLS 90
AUSTIN	S112317260	UNKNOWN	I-35 AND MANOR ROAD		TX SPILLS 90
AUSTIN	S112316156	UNK	IH-10 - COLORADO/AUSTIN COUNTY LINE ON S		TX SPILLS 90
AUSTIN	S112318844	SAFETY KLEEN	IN PARKING LOT OF CITY OF AUSTIN MAINT F		TX SPILLS 90
AUSTIN	S112316341	ELLA CONTRACTING	E OF I-35 BETWEEN SOILLMAN LN. AND OAK H		TX SPILLS 90
AUSTIN	S112309335	PROSOURCE DISTRIBUTION SERVICE	183 SOUTH FROM I-35 TO N.LAMAR BLVD.		TX SPILLS 90
AUSTIN	S112300828	FRANK S HEART OF TEXAS RENTALS	4700 BLOCK OF SO. LAMAR BLVD.		TX SPILLS 90
AUSTIN	S112638956	SOUTHLAND CORPORATION	1747 EAST OLTORF AT 7-11 #1661-12702		TX SPILLS 80
AUSTIN	S112649682	MODERN METAL REFINISHING	WEST SIDE OF PROPERTY AT 7432 BLUFF SPRI		TX SPILLS 80
AUSTIN	S112649830	M TRIPLE M LIMITED	WEST SIDE OF PROPERTY AT 7432 BLUFF SPRI		TX SPILLS 80
AUSTIN	S112639443	UNKNOWN	IH35 NORTH & 44TH STREET		TX SPILLS 80
AUSTIN	S112642640	UNKNOWN CITY CONTRACTOR	ELECTRIC SUBSTATION AT 11908 N. LAMAR		TX SPILLS 80
AUSTIN	S112642937	DON STEWART INC.	AUSTIN-1/2 MILE E OF HWY 1325 & HOWARD L		TX SPILLS 80
AUSTIN	S112639077	UNKNOWN	6517 US 290 WEST AUSTIN TEXAS		TX SPILLS 80
AUSTIN	S112651404	FUEL DISTRIBUTORS, INC.	ZIPPY FOOD STORE 6600 N. LAMAR		TX SPILLS 80
AUSTIN	S112645355	LAMBERTH OIL COMPANY	AUSTIN- INTERSECTION OF HWY 71 HWY 183		TX SPILLS 80
AUSTIN	S112647513	TEXAS PIPELINE COMPANY	AUSTIN-1/2 MILE W OF MONTOPOLIS BRIDGE O		TX SPILLS 80
AUSTIN	1004785567	EXXON MOBIL CORPORATION	1104 EAST AVE	78701	RCRA NonGen / NLR
AUSTIN	1000134111	TIP TOP CLEANERS LAUNDERERS INC	1014 F N LAMAR BLVD	78703	RCRA NonGen / NLR
AUSTIN	1014914165	AUSTIN DISTRICT OFFICE	AUSTIN DISTRICT OFFICE	78753	EPA WATCH LIST
AUSTIN	1026643595	TEXAS DEPARTMENT OF AGRICULTURE	1700 N. CONGRESS AVE. FLOOR 9	78711	PRP
AUSTIN	1026602374	HERCULES OFFSHORE CORPORATION	CORPORATION SERVICE CO.,REG.AGENT 800 BRAZOS	78701	PRP
AUSTIN	1026575595	BROYHILL FURNITURE, INC.	INTERCO, INC. 18 EAST ALPINE ROAD	78704	PRP
AUSTIN	1026644322	THE UNIVERSITY OF TEXAS @ DALLAS	C/O THE UNIVERSITY OF TEXAS SYSTEM 201 WEST 7TH ST.	78701	PRP
AUSTIN	1026642411	T H AGRICULTURE & NUTRITION COMPANY	BROWN MARONEY & OAKS HARTHINE 1400 FRANKLIN PLAZA 111 CONGRESS AVENUE	78701	PRP
AUSTIN	1026626875	PEPPER RENDERING	1300 ONE REPUBLIC PLAZA, 333 GUADALUPE	78701	PRP

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	1026612760	LIBERTY WASTE DISPOSAL CO.	1300 CAPITOL CENTER, 919 CONGRESS AVE.	78701	PRP
AUSTIN	1006261219	AUSTIN, CITY OF	ONION CREEK AND COLORADO RIVER, 2 M E OF FM 973	78767	ICIS, FINDS, ECHO
AUSTIN	1016985492	AUSTIN DISTRICT OFFICE	AUSTIN DISTRICT OFFICE	78753	ICIS, FINDS, ECHO
AUSTIN	1015858916	UNIVERSITY OF TEXAS AT AUSTIN	CORPORATE BOUNDARY OF CITY OF AUSTIN	00000	ICIS, FINDS, ECHO
AUSTIN	1009525272	UNIV OF TEXAS (BALCONES RESEARCH CNTR)	2617 SPEEDWAY & 10100 BURNETT RD	78702	FTTS, HIST FTTS
AUSTIN	1010005315	HOWARD SYSTEMS CORP	2700 E 6TH ST PO BOX 6308	78762	FTTS
AUSTIN	1004604510	TEXAS STATE BUILDING & PROPERTY	101 W 15TH ST & CONGRESS AVE	78701	FTTS, HIST FTTS
AUSTIN	1009523905	ST GEORGE'S EPISCOPAL	4301 NORTH IH 35	78722	HIST FTTS
AUSTIN	1009635761		300 BLOCK OF BRAZOS	78701	DOT OPS
AUSTIN	1009636060		2000 BLK OF SOUTH CONGRESS AVE		DOT OPS
AUSTIN	1009649014		"LOOP 1, NORTH OF WESTOVER"	0	DOT OPS
AUSTIN	1026699408	HALLAM HOMEBUILDING	FROM ITS INTERSECTION WITH LOOP 360, TRAVEL EAST O	78746	FINDS
AUSTIN	1025454278	ALL STOR WESTLAKE SELF STORAGE	SOUTHSIDE OF BEE CAVES ROAD, 150 FEET EAST OF CRYS	78746	FINDS
AUSTIN	1024194403	TXDOT-AUS-CSJ 0113-13-149	SH 71 IN TRAVIS COUNTY FROM EAST OF MONTOPOLIS DRI	78741	FINDS
AUSTIN	1024175068	STN NO 60107138	PORTABLE2300 EAST BEN WHITE BLVD	78741	FINDS
AUSTIN	1027129866	PHASE 1 LAKE FRONT TRAIL IMPROVEMENTS	FAR EAST HOLLY STREET AND SOUTH FROM HOLLY ALONG T	78702	FINDS, ECHO
AUSTIN	1024180805	MOTIVA ENTERPRISE	701 EAST AVE	78702	FINDS
AUSTIN	1026399494	102-1233 - UT RED RIVER REALIGNMENT	RED RIVER REALIGNMENT BETWEEN MLK BOULEVARD AND DE	78712	FINDS
AUSTIN	1010759031	GREIF YOUNG	SE AUSTIN	78741	FINDS
AUSTIN	1027554251	COUNTRY CLUB CREEK WEST	2,800 LINEAR FEET OF COUNTRY CLUB WEST CREEK FROM	78741	FINDS
AUSTIN	1027674581	CITY OF AUSTIN - OLTORF STREET RECLAIMED WATER MAIN PH 1	WATER MAIN RUNS EAST-WEST ALONG OLTORF STREET FROM	78741	FINDS
AUSTIN	1018132609	TXI PORTABLE 130	NE CORNER INTX HWY 71 & E RIVERSIDE DR	78741	FINDS, ECHO
AUSTIN	1024187465	TXDOT CSJ 013313069	ON SH 71 EAST FROM 0.25 MILES WEST OF BURLESON RD	78741	FINDS
AUSTIN	1024206974	ECO LAND	PATRIC PIKE RD BETWEEN ROBERTS AUSTIN TX 78746	78746	FINDS
AUSTIN	1027168821	T3 ATX EASTSIDE	SEC OF WALLER ST. AND E. 4TH ST.	78702	FINDS
AUSTIN	1024444000	PLAZA SALTILLO BLOCKS A-E	ON THE SOUTH SIDE OF EAST 5TH STREET EXTENDING EAS	78702	FINDS, ECHO
AUSTIN	1024444755	PLAZA SALTILLO BLOCKS A THROUGH E	ON THE SOUTH SIDE OF EAST 5TH STREET EXTENDING EAS	78702	FINDS, ECHO
AUSTIN	1024440347	UPPER BOGGY CREEK MULTI-USE TRAIL PHASE 1	PROJECT STARTS AT 2804 E 12TH ST AND ENDS AT 1719	78702	FINDS, ECHO
AUSTIN	1027557747	RED BLUFF ROW IMPROVEMENTS	EAST ALONG RED BLUFF ROAD FROM EAST CESAR CHAVEZ S	78702	FINDS
AUSTIN	1027650453	CSW 5TH STREET MIXED USE	5211 E 7TH STREET	78702	FINDS
AUSTIN	1026969146	ROY AND MATIAS VELASQUEZ PLAZA	1020 E 5TH ST	78702	FINDS
AUSTIN	1024215265	PRISM DEVELOPMENT INC.	2705, 2709, 2711, 2713 EAST 5TH	78702	FINDS
AUSTIN	1026973316	1515 EAST CESAR CHAVEZ OFFICE	1515 E CESAR CHAVEZ ST	78702	FINDS
AUSTIN	1024199663	DELL MEDICAL CENTER AT THE UNIV OF TX AT AUSTIN	AREA BOUNDED BY TRINITY ST E MLKI JR BLVD IH 35 AN	78705	FINDS
AUSTIN	1026974221	TEXAS BANKERS ASSOCIATION HEADQUARTERS	203 W 10TH ST	78701	FINDS
AUSTIN	1027026483	BANANA PRODUCTS LLC	501 CONGRESS AVENUE SUITE 150	78701	FINDS
AUSTIN	1025456057	CMTA DOWNTOWN STATION IMPROVEMENTS	LOCATED ALONG 4TH STREET, FROM ITS INTERSECTION WI	78701	FINDS
AUSTIN	1027018933	PURACY LLC	904 SAN ANTONIO STREET	78701	FINDS
AUSTIN	1024208088	WALLER CREEK PARK	WALLER CREEK FROM EAST 15TH STREET TO EAST 12TH ST	78701	FINDS, ECHO
AUSTIN	1024082447	STATE HIGHWAY 130 NATURAL GAS PIPELINE	ALONG EAST SIDE OF STATE HIGHWAY 130 NEAR MOORE RO	78751	FINDS, ECHO
AUSTIN	1024204994	TXDOT-AUS- I-35 NH 2016 108 CSJ 0015-13-378	I35 AT EAST OF OLTORF STREET	78704	FINDS, ECHO
AUSTIN	1024448195	TFC CAPITOL EXPANSION PROJECT	SEC OF MARTIN LUTHER KING BLVD AND COLORADO STREET	78701	FINDS, ECHO
AUSTIN	1027675957	MEXICAN AMERICAN CULTURAL CENTER PHASE 2 IMPROVEMENTS	APPROXIMATELY 0.08 MILES WEST OF BIERCE STREET, OF	78701	FINDS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	1010694457	1101 A MONFRAIS ST AUSTIN TEXAS	1101 A MONFRAIS ST AUSTIN TEXAS 78703	78703	FINDS
AUSTIN	1011904052	AUSTIN CLEAN WATER PROJECT - GOVALLE WETHERSFIELD-HARTFORD PROJECT	EASON ALLEY, WEST LYNN, WINDSOR RD, HARTFORD RD, J	78703	FINDS
AUSTIN	1027548873	ST GEORGE MULTIFAMILY	ALONG THE EAST SIDE OF BURNET ROAD, JUST NORTH OF	78757	FINDS
AUSTIN	1024453676	THE PEARL	WEST OF GROVER LN. AND W. KOENIG LN. 1301 E. KOENI	78756	FINDS, ECHO
AUSTIN	1027024385	ELIZABET NEY MUSEUM	304 E. 44TH STREET	78751	FINDS
AUSTIN	1024184669	U S P & F O FOR TX	35TH	78705	FINDS
AUSTIN	1027021251	MEDICAL PARK TOWER CAMPUS UPGRADES	1301 W 38TH ST	78705	FINDS
AUSTIN	1026419995	TX SCHOOL FOR THE DEAF EARLY LEANING CTR & CENTRAL SVCS CTR	SITE IS LOCATED APPROXIMATELY 0.35 MILES NORTH OF	78704	FINDS
AUSTIN	1024186637	TXDOT CSJ 001601091	ON IH-35 FROM SLAUGHTER LN TO NORTH OF LP 4	78704	FINDS
AUSTIN	1011982516	THE CROSSING AT BOULDIN CREEK	0.2 MILES WEST OF THE INTERSECTION OF BARTON SKYWA	78704	FINDS
AUSTIN	1024176328	SH 71 WEST ARROYO CANYON UPLANDS RIDGE	SH 71 WEST FROM ARROYO CANYON TO UPLANDS RIDGE		FINDS
AUSTIN	1024197617	SH71 SEGMENTS	SH 71 WEST VAIL DIVIDE TO SCENIC BROOK		FINDS
AUSTIN	1024195157	LOOP 1 AT ARBOR WALK	NBFE LOOP 1 NORTH OF US 183		FINDS
AUSTIN	1024195042	US 290 WEST FM 1826 TO CONVICT HILL	SH 71 WEST FROM ARROYO CANYON TO UPLANDS RIDGE		FINDS
AUSTIN	1024202380	LOOP 360 AT LOOP 1	LOOP 360 SOUTH OF LOOP 1 TO NORTH OF WALSH TARLTON		FINDS
AUSTIN	1024191011	SH 45 OCONNOR DRIVE	ALONG SH 45 TOLL WEST OF O CONNOR DRIVE		FINDS
AUSTIN	1009443357	THE BAUERLE RANCH - PH. 4	SO. WEST OF MANCHACA RD. & .	00000	FINDS, ECHO
AUSTIN	1026456881	BRENTWOOD WATER & WASTEWATER PIPELINE RENEWAL	WITH BRENTWOOD PARK ARCADIA AVE FROM ARROYO SECO T	78757	FINDS
AUSTIN	1024187548	TXDOT CSJ 011401045	ON SPUR 69 FROM 1100 W OF LAMAR TO AIRPORT BLVD ON	78757	FINDS
AUSTIN	1027294676	AIRPORT BLVD - N LAMAR TO 55TH ST	AIRPORT BLVD. - N. LAMAR TO 55TH ST.	78752	FINDS
AUSTIN	1027652253	FOUNDATION COMMUNITIES - AIRPORT	5900 & 5906 AIRPORT	78752	FINDS
AUSTIN	1024175934	RM 620	RM 620 S OF ANDERSON MILL ROAD		FINDS
AUSTIN	1010774750	IBC BANK SITE	NWC BRAKER LANE AND BURNET RD ADJACENT TO IMB LOC	78758	FINDS
AUSTIN	1024440602	SRG MARAVILLA AT THE DOMAIN	ON THE SEC OF NEWMAN DRIVE AND KRAMER LN	78758	FINDS, ECHO
AUSTIN	1024446812	IDEA YAGER	SW CORNER OF E. PALMER LN. AND E. YAGER LN.	78753	FINDS, ECHO
AUSTIN	1023707096	WELLS BRANCH COMMERCIAL CENTER	CHEDDAR LOOP ROAD AT I-35 SERVICE ROAD	78728	FINDS, ECHO
AUSTIN	1024437035	WELLS BRANCH CENTER	WEST OF I-35 AND TO THE NORTHWEST OF CHEDDAR LOOP	78728	FINDS, ECHO
AUSTIN	1012071203	WELLS BRANCH MUD MS4	AUSTIN & ROUND ROCK WITHIN IH-	78728	FINDS, ECHO
AUSTIN	1011357929	NORTH FORK OFFICE	NW OF THE INTERSECTION OF N MOPAC AND PARMER LN S	78758	FINDS
AUSTIN	1011337064	RECYCLED RUBBER MATS	AUSTIN TX 78758	78758	FINDS
AUSTIN	1026437322	CITY OF AUSTIN 2016 BOND INTERSECTION SAFETY IMP	PARKER LN AT E. OLTORF-- N. LAMAR AT PEYTON GIN RO	78758	FINDS
AUSTIN	1024440448	MOPAC IMPROVEMENT PROJECT MIP	PROJECT STARTS AT MOPAC LOOP1 AT PARMER LANE SOUTH	78758	FINDS, ECHO
AUSTIN	1010745338	AUS CSJ 3136-01-144	LP 1 .474 MI S OF DUVAL RD TO .95 MI N. OF PARMER	78753	FINDS
AUSTIN	1026977933	PARMER VILLAGE	900 E PARMER LANE	78753	FINDS
AUSTIN	1024199483	TXDOT-AUS-CSJ 0015-13-362	IH 35 FROM HOWARD LANE TO .2 MILES SOUTH OF PARMER	78753	FINDS
AUSTIN	1024193838	TXDOT-AUS-CSJ-3417-03-015	FM 734 HARRIS BRANCH ROAD TO US 290	78753	FINDS
AUSTIN	1024204471	TXDOT-AUS-CSJ 0914-04-298	US 290 AND FM 734 VARIOUS LOCATIONS IN TRAVIS COUN	78753	FINDS
AUSTIN	1025984595	IH35 & PARMER LN 0015-13-396	IH35 & PARMER LN, 0015-13-396	78753	FINDS
AUSTIN	1026977890	CAMBER RANCH	SOUTHEAST CORNER OF EAST PARMER LANE AND EAST YAGE	78753	FINDS
AUSTIN	1012312487	PARMER DAM	12032 WEST PARMER LANE, AUSTIN TX	78753	FINDS
AUSTIN	1026700433	AVID HOTEL - AUSTIN	SE OF TECH RIDGE BLVD. & N. I-35 FRONTAGE ROAD	78753	FINDS
AUSTIN	1027112357	PARMER SECTOR 2	12829 PARMER RIDGE DRIVE	78753	FINDS
AUSTIN	1026792024	NORTHTOWN MUD FORCE MAIN REPLACEMENT	ALONG DESSAU ROAD AND HOWARD LANE, NORTH OF PARMER	78753	FINDS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	1027114163	PARMER SECTOR 5	E SIDE OF PARMER RIDGE DRIVE, APPROX 0.19 MILES N	78753	FINDS
AUSTIN	1027545301	APPLE	S SIDE OF PARMER BETWEEN RIATA CIRCLE ON W	78727	FINDS
AUSTIN	1011981410	PARMER LANE FAMILY DENTISTRY	NS OF PARMER LN BTWN MOPAC AND AMHERST	78727	FINDS
AUSTIN	1027020095	218 SOUTH LAMAR	218 S LAMAR BLVD	78704	FINDS
AUSTIN	1026795922	SOUTH LAMAR RECONSTRUCTION - BARTON SPRINGS TO RIVERSIDE	SOUTH LAMAR BLVD. BETWEEN BARTON SPRINGS AND RIVER	78704	FINDS
AUSTIN	1026665349	HALLAM HOMEBUILDING	FROM ITS INTERSECTION WITH LOOP 360, TRAVEL EAST O	78746	ECHO
AUSTIN	1024929667	ALL STOR WESTLAKE SELF STORAGE	SOUTHSIDE OF BEE CAVES ROAD, 150 FEET EAST OF CRYS	78746	ECHO
AUSTIN	1026122554	3232 EAST CESAR CHAVEZ	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF T	78702	ECHO
AUSTIN	1026110555	102-1233 - UT RED RIVER REALIGNMENT	RED RIVER REALIGNMENT BETWEEN MLK BOULEVARD AND DE	78712	ECHO
AUSTIN	1027496307	COUNTRY CLUB CREEK WEST	2,800 LINEAR FEET OF COUNTRY CLUB WEST CREEK FROM	78741	ECHO
AUSTIN	1027618282	CSW 5TH STREET MIXED USE	5211 E 7TH STREET	78702	ECHO
AUSTIN	1027197327	T3 ATX EASTSIDE	SEC OF WALLER ST. AND E. 4TH ST.	78702	ECHO
AUSTIN	1027500143	RED BLUFF ROW IMPROVEMENTS	EAST ALONG RED BLUFF ROAD FROM EAST CESAR CHAVEZ S	78702	ECHO
AUSTIN	1024930721	CMTA DOWNTOWN STATION IMPROVEMENTS	LOCATED ALONG 4TH STREET, FROM ITS INTERSECTION WI	78701	ECHO
AUSTIN	1026735089	RED RIVER SOUTH REALIGNMENT 15TH TO 12TH STREET	RED RIVER REALIGNMENT BETWEEN 15TH STREET AND 12TH	78701	ECHO
AUSTIN	1027496183	KOENIG TOWNHOMES	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF T	78751	ECHO
AUSTIN	1027268054	WILDHORSE RANCH PARKSIDE TRACT A - SECTION 1	EAST OF THE INTERSECTION OF DECKER LANE AND LINDEL	78704	ECHO
AUSTIN	1027491040	ST GEORGE MULTIFAMILY	ALONG THE EAST SIDE OF BURNET ROAD, JUST NORTH OF	78757	ECHO
AUSTIN	1026182683	TX SCHOOL FOR THE DEAF EARLY LEANING CTR & CENTRAL SVCS CTR	SITE IS LOCATED APPROXIMATELY 0.35 MILES NORTH OF	78704	ECHO
AUSTIN	1026220459	BRENTWOOD WATER & WASTEWATER PIPELINE RENEWAL	WITH BRENTWOOD PARK ARCADIA AVE FROM ARROYO SECO T	78757	ECHO
AUSTIN	1027490069	MORROW AND GAULT WATER & WASTEWATER PIPELINE RENEW	NORTHWEST OF THE INTERSECTION OF N. LAMAR BLVD. AN	78757	ECHO
AUSTIN	1027256035	AIRPORT BLVD - N LAMAR TO 55TH ST	AIRPORT BLVD. - N. LAMAR TO 55TH ST.	78752	ECHO
AUSTIN	1026123662	NYOS PUBLIC WATERLINE	EAST OF THE INTERSECTION OF CHIMNEY ROCK DRIVE AND	78758	ECHO
AUSTIN	1026210084	CITY OF AUSTIN 2016 BOND INTERSECTION SAFETY IMP	PARKER LN AT E. OLTORF-- N. LAMAR AT PEYTON GIN RO	78758	ECHO
AUSTIN	1026666504	AVID HOTEL - AUSTIN	SE OF TECH RIDGE BLVD. & N. I-35 FRONTAGE ROAD	78753	ECHO
AUSTIN	1026932252	PARMER SECTOR 5	E SIDE OF PARMER RIDGE DRIVE, APPROX 0.19 MILES N	78753	ECHO
AUSTIN	1026930314	PARMER SECTOR 2	12829 PARMER RIDGE DRIVE	78753	ECHO
AUSTIN	1025915299	IH35 & PARMER LN 0015-13-396	IH35 & PARMER LN, 0015-13-396	78753	ECHO
AUSTIN	1026756939	NORTHTOWN MUD FORCE MAIN REPLACEMENT	ALONG DESSAU ROAD AND HOWARD LANE, NORTH OF PARMER	78753	ECHO
AUSTIN	1026848110	CAMBER RANCH	SOUTHEAST CORNER OF EAST PARMER LANE AND EAST YAGE	78753	ECHO
AUSTIN	1027487329	APPLE	S SIDE OF PARMER BETWEEN RIATA CIRCLE ON W	78727	ECHO
AUSTIN	1026761547	SOUTH LAMAR RECONSTRUCTION - BARTON SPRINGS TO RIVERSIDE	SOUTH LAMAR BLVD. BETWEEN BARTON SPRINGS AND RIVER	78704	ECHO
AUSTIN	S116382325	FORMER JACK BROWN CLEANERS	3315 NORTHLAND, AUSTIN, TX NE INTX OF NORTHALND & BALCONES DR	78731	TX APAR
AUSTIN	S121361207	J.T. PATTERSON LABS BUILDING (CP631872)	2415 SPEEDWAY	78712	TX ASBESTOS
AUSTIN	S121359982	COLLEGE OF BUSINESS ADMINISTRATION	2110 SPEEDWAY	78705	TX ASBESTOS
AUSTIN	S125389959	AC PIPE	SABINE STREET	78702	TX ASBESTOS
AUSTIN	S119136977	75 1/2 RAINEY STREET FORMER RESIDENCE	75.5 RAINEY ST.	78701	TX ASBESTOS
AUSTIN	S128931358	SOFIA APARTMENTS	8201 WILLOW CREEK DR	78741	TX ASBESTOS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126248116	PALMS CAR WASH	WILLOW CREEK DRIVE	78741	TX ASBESTOS
AUSTIN	S119140304	BUILDING 1 FORMER HAIR SALON	4306.5 RED RIVER	78751	TX ASBESTOS
AUSTIN	S127558890	FORMER SAFARI GRILL	3231 E. 29TH ST.,	78702	TX ASBESTOS
AUSTIN	S129335852	UT AUSTIN - GEORGE SANCHEZ BUILDING	UNIVERSITY AND MLK	78705	TX ASBESTOS
AUSTIN	S125391239	FACILITY COMPLEX BLDG 6	1301 E. DEAN KEETON	78722	TX ASBESTOS
AUSTIN	S121360460	THE UNIVERSITY OF TEXAS AT AUSTIN	1301 E DEAN KEETON ST .	78722	TX ASBESTOS
AUSTIN	S121360462	FACILITIES COMPLEX BLDG. 1	1301 E. DEAN KEETON	78722	TX ASBESTOS
AUSTIN	S121360461	FACILITIES COMPLEX BLDG 2	1301 E. DEAN KEETON ST.	78722	TX ASBESTOS
AUSTIN	S121360656	FORMER FAST FOOD RESTAURANT	1701 E. RIVERSIDE DRIVE	78741	TX ASBESTOS
AUSTIN	S125395055	ZILKER PARK CAFE	2100 BARTON SPRINGS RD	78746	TX ASBESTOS
AUSTIN	S121359069	1401 AND 1403 EAST 6TH STREET BUILDINGS	1401 & 1403 EAST 6TH STREET	78702	TX ASBESTOS
AUSTIN	S121361372	LAKESIDE APARTMENTS	85 TRINITY	78702	TX ASBESTOS
AUSTIN	S121359608	BLANCA HAIR SALON	3321 E CESAR CHAVEZ	78702	TX ASBESTOS
AUSTIN	S121363111	TWC MLK WAREHOUSE	2810 MARTIN LUTHER KING JR. BLVD.	78702	TX ASBESTOS
AUSTIN	S121363334	VACANT BUILDING	1224 E 12TH STREET	78702	TX ASBESTOS
AUSTIN	S121363387	VACANT BUILDINGS	1200 EAST 12TH STREET	78702	TX ASBESTOS
AUSTIN	S121363335	VACANT BUILDING	1224 EAST 12TH STREET	78702	TX ASBESTOS
AUSTIN	S121361449	LIGHT OFFICE BUILDING AT 1211 EAST 11TH STREET	1211 EAST 11TH STREET	78702	TX ASBESTOS
AUSTIN	S125390464	CAP METRO DOWNTOWN STATION -AC PIPE REMOVAL	4TH ST FROM IH 35 TO TRINITY S	78702	TX ASBESTOS
AUSTIN	S125922073	FORMER FORD PLUMBING SUPPLY & FORD LIME SCOOTER BLDG.	4708 & 4800 E. 7TH ST.	78702	TX ASBESTOS
AUSTIN	S127559467	SUBJECT PROPERTY	1505&1519 EAST CESAR CHAVEZ	78702	TX ASBESTOS
AUSTIN	S122367117	SB 7TH STREET BRIDGE OVER CEASER CHAVEZ	SB 7TH STREET	78702	TX ASBESTOS
AUSTIN	S121510620	SB AIRPORT BLVD. OVER 7TH STREET	SB AIRPORT AND 7TH STREET	78702	TX ASBESTOS
AUSTIN	S122366867	PATHWAYS AT CHALMERS COURT	1640 A EAST 2ND STREET	78702	TX ASBESTOS
AUSTIN	S121360602	FORMER APPLIANCE STORE	3309 E CESAR CHAVEZ	78702	TX ASBESTOS
AUSTIN	S122569729	PATHWAYS AT CHALMERS COURTS SOUTH	1604 B EAST 2ND STREET	78702	TX ASBESTOS
AUSTIN	S122569728	PATHWAYS AT CHALMERS COURTS SOUTH	1604 A EAST 2ND STREET	78702	TX ASBESTOS
AUSTIN	S121363112	TWC TRINITY BLDG	1117 TRINITY	78778	TX ASBESTOS
AUSTIN	S119146715	GATEWAY APARTMENTS	1642 W. 6TH ST., #1622-C & D	78703	TX ASBESTOS
AUSTIN	S119146716	GATEWAY APARTMENTS	1642 W. 6TH ST., #1624-K & M	78703	TX ASBESTOS
AUSTIN	S125393947	SWEDISH HILL BAKERY	1118 &1120 W. 6TH ST	78703	TX ASBESTOS
AUSTIN	S129335863	UTILITY TUNNEL	15TH ST. AT TRINITY ST.	78712	TX ASBESTOS
AUSTIN	S129335862	UTILITY TUNNEL WALL	14 E 23RD ST	78712	TX ASBESTOS
AUSTIN	S126246721	2 - 4PLEXES AND RESTAURANT	613 24 1/2 STREET & 2400 SETON	78705	TX ASBESTOS
AUSTIN	S125394836	VILLA RIO PROJECT	2107 & 2109 W. 22ND ST.	78705	TX ASBESTOS
AUSTIN	S125394837	VILLA RIO PROJECT	609,607 W. 22ND ST.	78705	TX ASBESTOS
AUSTIN	S122365465	1202 AND 1204 SAN ANTONIO STREET BUILDINGS	1202 & 1204 SAN ANTONIO STREET	78701	TX ASBESTOS
AUSTIN	S121362222	RADISSON AUSTIN	111 E. CESAR CHAVEZ SREET	78701	TX ASBESTOS
AUSTIN	S119152809	OLD GLO WAREHOUSE	40 E. CESAR CHAVEZ	78701	TX ASBESTOS
AUSTIN	S119155598	RIVER CITY TATTOO	718.5 CONGRESS AVE	78701	TX ASBESTOS
AUSTIN	S123213514	VACANT STRUCTURES	1202,1204 SAN ANTONIO & 1205 NUECES ST	78701	TX ASBESTOS
AUSTIN	S123213205	PHARMACY BUILDING	24TH AND UNIVERSITY	78701	TX ASBESTOS
AUSTIN	S121363800	WILLIAM B. TRAVIS BUILDING	1701 CONGRESS AVE.	78701	TX ASBESTOS
AUSTIN	S121359047	1123	SOUTH CONGRESS AVE	78704	TX ASBESTOS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S121360766	FORMER SPILLAR CUSTOM HITCHES FACILITY (VACANT)	2701 S. CONGRESS	78704	TX ASBESTOS
AUSTIN	S128135407	VACANT STRUCTURES	2201, 2209 S 1ST STREET	78704	TX ASBESTOS
AUSTIN	S125390120	AUSTIN HOTEL	1204.5 SOUTH CONGRESS AVE	78704	TX ASBESTOS
AUSTIN	S127559683	VACANT STRUCTURE	605 BARTON SPRINGS	78704	TX ASBESTOS
AUSTIN	S128135406	VACANT STRUCTURES	2201, 2209 S 15TH STREET	78704	TX ASBESTOS
AUSTIN	S121363494	VACANT OFFICE BUILDING	153 E. RIVERSIDE DRIVE	78704	TX ASBESTOS
AUSTIN	S121361723	MUSEUM OF THE WIERD	1101 SOUTH CONGRESS AVE	78704	TX ASBESTOS
AUSTIN	S122569227	FORMER CVS	2301 A S. CONGRESS AVENUE	78704	TX ASBESTOS
AUSTIN	S119148155	HOMEWOOD HOTEL	78 & 80 EAST AVENUE	78701	TX ASBESTOS
AUSTIN	S125921349	42 & 44 EAST PROJECT	42 & 44 EAST AVENUE	78701	TX ASBESTOS
AUSTIN	S125921350	42 & 44 EAST PROJECT	44 & 44 EAST AVENUE	78701	TX ASBESTOS
AUSTIN	S129329097	COMMERCIAL BUILDING	78 & 80 EAST AVENUE	78701	TX ASBESTOS
AUSTIN	S122569315	GRADUATE SCHOOL OF BUSINESS	EAST 21ST AND UNIVERSITY	78701	TX ASBESTOS
AUSTIN	S121361213	JACKSON GEOLOGICAL SCIENCES BLDG (WO# 38086285)	#10 EAST MALL	78712	TX ASBESTOS
AUSTIN	S121360972	HANCOCK RECREATION CENTER	811 EAST 41TH STREET	78751	TX ASBESTOS
AUSTIN	S125390826	COMPUTATION CENTER	#1 EAST MALL	78705	TX ASBESTOS
AUSTIN	S121360848	FULMORE MIDDLE SCHOOL	201 EAST MARY	78704	TX ASBESTOS
AUSTIN	S126247318	DEMO PORTION OF TWIN OAKS SHOPPING CENTER	102&104 EAST OLTORFF	78704	TX ASBESTOS
AUSTIN	S127036742	FAITH PRESBYTERIAN CHURCH	1314 EAST OL 1314 EAST OLTORF STREET	78704	TX ASBESTOS
AUSTIN	S129334617	SINGLE FAMILY RESIDENCE - RIO GRANDE	1909, 1911, 1913 RIO GRANDE ST	78705	TX ASBESTOS
AUSTIN	S122366105	EL RIO APARTMENTS	2405 & 2401 RIO GRANDE	78705	TX ASBESTOS
AUSTIN	S121363289	UT ANIMAL RESEARCH CENTER	29TH & SAN JACINTO	78701	TX ASBESTOS
AUSTIN	S121361209	JACK BROWN CLEANERS	615 WEST MLK	78701	TX ASBESTOS
AUSTIN	S125390127	AUSTIN REPUBLIC SQUARE	301,303,305 WEST 5TH STREET	78701	TX ASBESTOS
AUSTIN	S125922600	MUNICIPAL BUILDING	700/800 BLOCK OF NORTH	78701	TX ASBESTOS
AUSTIN	S121361233	JEFFERSON BUILDING	1600 WEST 38TH	78731	TX ASBESTOS
AUSTIN	S121363488	VACANT LEASE SPACE	3918 FAR WEST BLVD, SUITE C AND D	78731	TX ASBESTOS
AUSTIN	S121363489	VACANT LEASE SPACE	3918 FAR WEST BLVD, SUITE D	78731	TX ASBESTOS
AUSTIN	S125391051	DOSS ELEMENTARY	7500 NORTH LEDGE DRIVE	78731	TX ASBESTOS
AUSTIN	S129159685	CITADEL	6805 NORTH CAPITOL OF TEXAS HWY	78731	TX ASBESTOS
AUSTIN	S125923514	WEST MALL OFFICE BUILDING	#3 WEST MALL	78712	TX ASBESTOS
AUSTIN	S121363480	VACANT INDUSTRIAL BLDG	1301 WEST 5TH	78703	TX ASBESTOS
AUSTIN	S121359818	CAMP MABRY BUILDING 34	2200 W 35TH STREET, BLDG 34	78703	TX ASBESTOS
AUSTIN	S121361552	MATHEWS ELEMENTARY	906 WEST LYNN	78703	TX ASBESTOS
AUSTIN	S129329632	DOUBLETREE HOTEL	6505 IH-35 NORTH	78752	TX ASBESTOS
AUSTIN	S126409735	HYDE PARK PLACE	4400 AVENUE B UNIT 107 & 207	78751	TX ASBESTOS
AUSTIN	S128928776	ATX FENTON THE RETREAT UNIT 101	400 AVENUE A UNIT 101	78751	TX ASBESTOS
AUSTIN	S119149675	LA QUINTA INN & SUITES (#136 & 137)	5812 NORTH IH 35	78751	TX ASBESTOS
AUSTIN	S128133583	DELWOOD STATION	38 1/2 E 38 1/2 STREET	78751	TX ASBESTOS
AUSTIN	S121063625	OLD SHELL STATION	5740 NORTH IH35	78751	TX ASBESTOS
AUSTIN	S122569064	COMMUNE	101 NORTH LOOP	78751	TX ASBESTOS
AUSTIN	S121359548	BATTLE HALL - QUARANTINE RM	#1 WEST MALL	78705	TX ASBESTOS
AUSTIN	S121361558	MCCLENDO PRICE HOUSE	1606 PEARL STREET	78705	TX ASBESTOS
AUSTIN	S128928774	ATX FENTON THE 407 UNIT 204	W 38TH W 38TH ST,	78705	TX ASBESTOS
AUSTIN	S119146788	GEOLOGY BUILDING	24TH N.E. CORNER ST. AND WHITIS	78705	TX ASBESTOS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S119148888	JESSE H. JONES COMM. CTR.	2504-A WHITIS AVE.	78705	TX ASBESTOS
AUSTIN	S119139391	BELO CENTER FOR NEW MEDIA	2504A & 2504B WHITIS AVE.	78705	TX ASBESTOS
AUSTIN	S129327976	BATTLE HALL (WO# 37490138)	#1 WEST MALL	78705	TX ASBESTOS
AUSTIN	S122570068	UNION BUILDING	#4 WEST MALL	78705	TX ASBESTOS
AUSTIN	S121360143	COMMERCIAL STRUCTURE	2116 GUADALUPE STREET	78705	TX ASBESTOS
AUSTIN	S122569367	HILTON CANOPY	604&612 WEST 6TH STREET	78705	TX ASBESTOS
AUSTIN	S121062845	FIRST ENGLISH LUTHERN CHURCH	301 WHITIS AVE	78705	TX ASBESTOS
AUSTIN	S121359568	BECKER ELEMENTARY	906 WEST MILTON	78704	TX ASBESTOS
AUSTIN	S127559685	VACANT STRUCTURES	4803,909/911 AIRPORT & GENE JOHNSON	78751	TX ASBESTOS
AUSTIN	S119149771	LAMAR VILLAGE	CITY BLOCK-LAMAR & MEDICAL PARKWAY	78756	TX ASBESTOS
AUSTIN	S126248011	NORTHWEST WIC CLINIC	8701-A RESEARCH BLVD	78758	TX ASBESTOS
AUSTIN	S125921940	DURANGO DOORS HEADQUARTERS	25300 RUTLAND DRIVE, SUITE 178	78758	TX ASBESTOS
AUSTIN	S121360987	HARMONY SCIENCE ACADEMY	930 EAST RUNDBERG LANE	78753	TX ASBESTOS
AUSTIN	S121363727	WEITZMAN GROUP BUILDING	5826 AIRPORT BOULEVARD	78752	TX ASBESTOS
AUSTIN	S121361781	NORTH SERVICE CENTER ANNEX	5700 NORTH LAMAR BLVD	78752	TX ASBESTOS
AUSTIN	S121359340	ACC HIGHLAND CAMPUS	6101 AIRPORT BLVD	78752	TX ASBESTOS
AUSTIN	S121363846	WPR CHILLING PLANT	3925 W. BRAKER LANE	78758	TX ASBESTOS
AUSTIN	S125392288	KRAMER III	1825 A KRAMER LANE	78758	TX ASBESTOS
AUSTIN	S126246997	BRIDGE 1422700151341	E PARMER LN AT IH35	78753	TX ASBESTOS
AUSTIN	S121362129	PIZZA HUT	8500 N LAMAR	78753	TX ASBESTOS
AUSTIN	S121359353	ADVANCED AUTO PARTS	9316 N LAMAR	78753	TX ASBESTOS
AUSTIN	S121360507	FIRE STATION #28	2410 PARMER LN	78727	TX ASBESTOS
AUSTIN	S121361377	LAMAR EXPRESS	2238 SOUTH LAMAR	78704	TX ASBESTOS
AUSTIN	S119136602	1300,1234, & 1232 SOUTH LAMAR BLDGS.	1300,1234, & 1232 S. LAMAR BLVD.	78704	TX ASBESTOS
AUSTIN	S128133287	CAR WASH, JIFFY LUBE, REPAIR SHOP	1303,11,1401 S. LAMAR	78704	TX ASBESTOS
AUSTIN	S128133288	CAR WASH, JIFFY LUBE, REPAIR SHOP	S. LAMAR	78704	TX ASBESTOS
AUSTIN	S107649391	LOOP 360 WSC	LOCATED WITHIN THE AUSTIN COUNTRY CLUB GOLF COURSE	78746	TX ENF
AUSTIN	S107649392	INVERNESS POINT WATER SYSTEM	EAST OF HWY 71, ON BEE CREEK RD		TX ENF
AUSTIN	S107654147	SENTINEL WASTE	FM 973 APPROX 0.25 TO 0.50 MILE EAST OF HWY 183 IN SE TRAVIS COUNTY		TX ENF
AUSTIN	S107636129	JEFFERSON AT RIVER OAKS	EAST SIDE OF BRODIE LANE		TX ENF
AUSTIN	S108238635	WILD HORSE RANCH WWTP	FACILITY IS LOCATED APPROX. 4,800 FEET EAST OF THE INTERSECTION OF BLUE BLUFF ROAD AND LINDEL LANE A		TX ENF, TX COMP HIST
AUSTIN	S108105236	PRYOR CUSTOM HOMES LAKEPOINTE	APPROXIMATELY 0.75 MILES EAST OF HWY 71 AND FM 2244 OFF OF FM 2244		TX ENF
AUSTIN	S108105242	PREMIER PARTNERS CUSTOM HOMES LAKEPOINTE	APPROXIMATELY 0.75 MILES EAST OF HWY 71 & FM 2244 INTERSECTION OFF OF FM 2244		TX ENF
AUSTIN	S108105239	OLYMPIA HOMES LAKEPOINTE	APPROXIMATELY 0.75 MILES EAST OF HWY 71 & FM 2244 OFF OF FM 2244		TX ENF
AUSTIN	S108105235	TIERRA CUSTOM HOMES LAKEPOINTE	APPROXIMATELY 0.75 EAST OF HWY 71 & FM 2244 INTERSECTION OFF OF FM 2244		TX ENF
AUSTIN	S119136047	SH 71 EXPRESS TOLL LANES	SH 71 FROM PRESIDENTIAL BLVD TO EAST OF SH 130 AND FM 973 FORM JUST SOUTH OF THE COLORADO RIVER TO A POINT APPROXIMATELY .5 MILE SOUTH OF CURRENT SH 71/FM 973 INTERSECTION.		TX ENF, TX COMP HIST
AUSTIN	S108105237	VILLA NOVA BUILDERS LAKEPOINTE	APPROXIMATELY 0.75 MILES EAST OF HWY 71 & FM 2244 OFF OF FM 2244		TX ENF

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S108105238	ECHELON HOMES LAKEPOINTE	APPROXIMATELY 0.75 MILES EAST OF HWY 71 & FM 2244, OFF OF FM 2244		TX ENF
AUSTIN	S126428907	TFC CAPITOL EXPANSION PROJECT	SEC OF MARTIN LUTHER KING BLVD AND COLORADO STREET		TX ENF
AUSTIN	S110147856	BLOCK 21	BOUNDED BY W 3RD ST TO THE NORTH, WEST 2ND ST TO THE SOUTH, GUADALUPE ST TO THE WEST AND LAVACA ST TO THE EAST	78705	TX ENF, TX COMP HIST
AUSTIN	S107652635	CAPITAL AGGREGATES	FM 2769 NORTH OF 620		TX ENF
AUSTIN	S126423316	TRAVIS COUNTY MUD 4 SOUTH WWTP	FACILITY IS LOCATED APPROXIMATELY 13000 FT WNW OF THE INTX OF MOPAC EXPRESSWAY LOOP 1 AMD LOOP 360 CAPITOL OF TEXAS HIGHWAYS		TX ENF
AUSTIN	S115812393	AVANA	EAST AND WEST SIDE OF ESCARPMENT AND SOUTH OF STATE HWY 45 ALSO IN COUNTY OF HAYS		TX ENF, TX COMP HIST
AUSTIN	S125821218	PARTEN RANCH PHASE 2	SITE IS LOCATED APPROXIMATELY 1 MILE SOUTHWEST OF THE INTERSECTION OF RM 1826 AND NUTTY BROWN ROAD ON THE NORTH SIDE OF RM 1826.		TX ENF
AUSTIN	S125821142	TXDOT-AUS- IH-35 CSJ-0015-13-379	IH35 FROM NORTH OF STASSNEY LANE TO SOUTH OF WILLIAM CANNON DR		TX ENF
AUSTIN	S119135959	JESTER KING CRAFT BREWERY	2 MILE WEST OF 290 ON FITZHUGH RD		TX ENF, TX COMP HIST
AUSTIN	S109597582	PECAN PARK CONDOMINIUMS & OFFICE PARK	PECAN PARK BLVD WEST OF US HIGHWAY 183 ON THE SOUTH PORTION OF PECAN PARK BLVD		TX ENF, TX COMP HIST
AUSTIN	S106951931	HOLLY STREET SES	LOCATED AT 4200 HOLLY ST. ON THE NORTH SIDE OF TOWN LAKE, IMMEDIATELY UPSTREAM FROM LONGHORN DAM IN		TX ENF, TX COMP HIST
AUSTIN	S108105240	DIMENSION BUILDERS 2116 SEA EAGLE VIEW	NORTH OF THE INTERSECTION OF FM 2244 & RESACA BLVD		TX ENF, TX COMP HIST
AUSTIN	S107637365	HILL OAKS MOBILE ESTATES	NORTH OF HIGHWAY 290 ON CIRCLE DR NEAR THOMAS SPRINGS RD		TX ENF
AUSTIN	S118665804	KEY RANCH SECTION 2	NORTH OF THE INTERSECTION OF US HIGHWAY 290 AND TRAUTWEIN ROAD		TX ENF, TX COMP HIST
AUSTIN	S108892500	TAYLOR WOODROW COMMUNITIES STEINER RANCH RIVER DANCE PHASE 6A	ON SE OF THE INX OF NORTH QUINLAN PARK ROAD AND BELLA MAR TRAIL		TX ENF, TX COMP HIST
AUSTIN	S108703317	HIGHWAY 71 STORAGE & MHP	NORTH SIDE OF HWY 71 AT BOBWIRE RD		TX ENF
AUSTIN	S108892499	TAYLOR WOODROW COMMUNITIES STEINER RANCH STEINER RANCH PHASE 1 SECTION 6G	ON WEST OF THE INX OF STEINER RANCH BLVD AND FLAT TOP RANCH ROAD		TX ENF, TX COMP HIST
AUSTIN	S109115659	BELTERRA PHASE 4 SECTION 18	PHASE 4 SECTION 18 WEST OF THE INTERSECTION OF HARRIS DRIVE AND BELTERRA DRIVE BORDERED ON SOUTH BY BELTERRA DRIVE		TX ENF, TX COMP HIST
AUSTIN	S127144138	ANDERSON MILL WWTP	1700 FT SW OF THE INTERSECTION OF US HWY 183 AND FM 620 AND 5800 FT NW OF THE INTERSECTION OF US HWY 183 AND ANDERSON MILL RD		TX ENF
AUSTIN	S121972848	7-ELEVEN STORE 36599	NE CORNER RM 620 AND ANDERSON MILL RD		TX ENF, TX COMP HIST
AUSTIN	S112166204	RUDYS COUNTRY STORE AND BAR-B-Q	E OF RESEARCH BLVD		TX ENF, TX COMP HIST
AUSTIN	S107636477	AUSTIN Y M B L SUNSHINE 2	THERMON BEND RD SPICEWOOD TEXAS		TX ENF
AUSTIN	S117842386	FORT DESSAU	NORTHWEST INTERSECTION OF DESSAU RD AND CRYSTAL BEND DR		TX ENF, TX COMP HIST
AUSTIN	S107656563	HAMILTON SUBSTATION	EAST OF US 183 BETWEEN HAMILTON AND BRAKER		TX ENF, TX COMP HIST
AUSTIN	S107639054	LOREDO TRUSS	FROM 183 & CAMERON HEAD NORTH ON CAMERON TURN RIGHT ON FERGUSON GO .25 MILES		TX ENF, TX COMP HIST
AUSTIN	S126424124	QUARRY OAKS MADISON TRACT	NW CORNER OF BRAKER LN & STONELAKE BLVD		TX ENF
AUSTIN	S120821509	NORTHTOWN MUD MS4	AREA WITHIN THE ETJ OF THE CITY OF AUSTIN THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78660	TX ENF, TX COMP HIST
AUSTIN	S126427966	YUNIET TRUCKING	HWY 290 & PARMER OVERPASS		TX ENF

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S106951586	AVERY RANCH BOULEVARD FAR WEST SECTION	APPROXIMATELY 10600 PARMER LANE		TX ENF, TX COMP HIST
AUSTIN	S111100777	WILLIAMSON TRAVIS COUNTIES MUD 1 MS4	AREA WITHIN WILLIAMSON TRAVIS COUNTIES MUD 1 LOCATED WITHIN THE AUSTIN URBANIZED AREA IN TRAVIS AND WILLIAMSON COUNTIES		TX ENF
AUSTIN	S121202628	UNIVERSITY OF TEXAS AT AUSTIN MS4	COVERS ALL AREAS OF THE UNIVERSITY OF TEXAS AT AUSTIN'S MS4		TX ENF, TX COMP HIST
AUSTIN	S125155795	FERN BLUFF MUD MS4	AREA WITHIN THE CITY OF ROUND ROCK ETJ AND WITHIN THE AUSTIN URBANIZED AREA		TX ENF
AUSTIN	S121202636	LAKELINE BLVD EXTENSION	FROM LYNDHURST DR TO 0.11 MILES W OF PARMER LANE		TX ENF, TX COMP HIST
AUSTIN	S118466636	SH 45 PARMER LANE TO RIDGELINE BLVD	ALONG FM 620 FROM PARMER LANE TO RIDGELINE BLVD		TX ENF, TX COMP HIST
AUSTIN	S112166528	LIFE TIME FITNESS	W OF INTERSECTION RM 620 AND PARMER LANE		TX ENF, TX COMP HIST
AUSTIN	S107650048	AVERY RANCH BOULEVARD EAST	E OF 10600 PARMER LANE		TX ENF, TX COMP HIST
AUSTIN	S110301608	TRAVIS COUNTY MS4	ALL AREAS WITHIN TRAVIS COUNTY LOCATED OUTSIDE FULLY-ANNEXED MUNICIPAL LIMITS INCLUDING THE UN-ANNEXED PORTION OF THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
AUSTIN	S121973238	LAND RESTORATION	AUSTIN TX		TX ENF
AUSTIN	S126424761	WRTP FM 812 LANDFILL CLOSURE	AT ONION CREEK NEAR INTX OF MOORES BRIDGE RD AND FM 973 SE OF AUSTIN		TX ENF, TX COMP HIST
AUSTIN	S125820925	CITY OF ROLLINGWOOD	NORTH OF FM 2244 OFF EDGE GROVE ROAD IN ROLLINGWOOD AUSTIN TEXAS		TX ENF
AUSTIN	S108238456	COOL RIVER CAFE	SW OF INTERSECTION OF PARMER LANE & AMHERST DR		TX ENF, TX COMP HIST
AUSTIN	S107655647	620 PARMER CROSSING	300' NORTH OF RM 620 ON THE WEST SIDE OF PARMER LANE		TX ENF, TX COMP HIST
AUSTIN	S111100831	LOST CREEK MUD MS4	AREA WITHIN THE LOST CREEK SUBDIVISION IN TRAVIS COUNTY LIMITS THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
AUSTIN	S113455355	RIATA VISTA OFFICE COMPLEX	S SIDE OF PARMER BETWEEN RIATA CIRCLE ON W		TX ENF, TX COMP HIST
AUSTIN	S126426277	ABIA NEW EMPLOYEE PARKING LOT	THE PROJECT IS LOCATED IN THE AUSTIN BERGSTROM INTERNATIONAL AIRPORT COMPLEX AND IS ON THE NORTHEAST SIDE OF THE PRESIDENTIAL BLVD. LOOP.		TX ENF
AUSTIN	S107638997	DUNLAP RD WISIAN BFU SITE	APPROX 10 MI EAST OF AUSTIN TX 0.5 MI S OF INTERSECTION OF FM 969 & DUNLAP RD		TX ENF, TX COMP HIST
AUSTIN	S106952183	THE PLAZA AT AVERY RANCH II	NW INTERSECTION OF AVERY RANCH BLVD AND PARMER LN		TX ENF, TX COMP HIST
AUSTIN	S110148702	DRAKE CONDOMINIUMS	68-76 (EVANS) RAINEY STREET		TX GCC
AUSTIN	S111380502	AUSTIN MUSEUM OF ART	400 BLOCK W 3RD ST		TX GCC
AUSTIN	S113912010	CESAR CHAVEZ ST & WALTER SEAHOLM DR	CESAR CHAVEZ ST & WALTER SEAHOLM DR		TX GCC
AUSTIN	S113912499	LINCOLN PROPERTIES	CONGRESS AVENUE		TX GCC
AUSTIN	S111381288	TILLEY STREET TANNEHILL BRANCH	2000 BLOCK 51ST ST		TX GCC
AUSTIN	S110148744	EAST AUSTIN TANK FARM (GOVALLE PARK)	AIRPORT BLVD		TX GCC
AUSTIN	S111380603	CITY OF AUSTIN (FORMER MW-4)	SE OF BERGSTROM AFB, ALONG THE W SIDE OF FM 973, BETW FM 812 AND ONION CREEK, AUSTIN		TX GCC
AUSTIN	S111381214	SOUTH LAMAR @ MANCHACA	2810 MACHACA, 2801 - 2805 S LAMAR		TX GCC
AUSTIN	S128127894	HEREFORD MUNICIPAL WATER SUPPLY	41-CAUSEY & AUSTIN		TX GCC
AUSTIN	S128694200		1701-A EAST 22ND ST	78722	TX LEAD
AUSTIN	S120704402	HOLLY STREET SES	LOCATED AT 2401 HOLLY ST ON THE N SIDE OF TOWN LAKE UPSTREAM FROM LONGHORN DAM IN THE CITY OF AUSTIN		TX NPDES
AUSTIN	S108876029	LEIF JOHNSON FORD	501 EAST KOENING LANE	78751	TX TIER 2
AUSTIN	S109199336	TOWN NORTH NISSAN	9160 BUILDING A RESEARCH BLVD	78758	TX TIER 2
AUSTIN	S113677629	SUBSTATION; TECH RIDGE	13625-1/2,%CENTER LINE PASS		TX TIER 2

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AUSTIN	S126966373	3232 EAST CESAR CHAVEZ	SITE IS LOCATED APPROXIMATELY 0.35 MILES EAST OF THE INTERSECTION OF E. CESAR CHAVEZ STREET AND PLEASANT VALLEY ROAD ON THE NORTH SIDE OF E. CESAR CHAVEZ STREET.	78702	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S123231978	TFC CAPITOL EXPANSION PROJECT	SEC OF MARTIN LUTHER KING BLVD AND COLORADO STREET		TX COMP HIST
AUSTIN	S126969334	HIGHLAND PARK WATER & WASTEWATER IMPROV F 1	ALONG BALCONES DR FROM NORTHLAND DRIVE NORTHEAST TO EAST HILLS DR TO NORTH HILLS DR TO END WEST OF VILLAGE CENTER DR AND WOOD HOLLOW DR FROMNORTH HILLS DRIVE TO FAR WEST BLVD	78731	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S126968671	TX SCHOOL FOR THE DEAF EARLY LEANING CTR & CENTRAL SVCS CTR	SITE IS LOCATED APPROXIMATELY 0.35 MILES NORTH OF THE INTERSECTION OF S. CONGRESS AVE AND RIVERSIDE DRIVE ON THE WEST SIDE OF S. CONGRESS AVE.	78704	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S122202516	TXDOT-AUS- IH-35 CSJ-0015-13-379	IH35 FROM NORTH OF STASSNEY LANE TO SOUTH OF WILLIAM CANNON DR		TX COMP HIST
AUSTIN	S128557154	HARRIS BRANCH WWTP	LOCATED APPROX 1.75 MILES NORTH OF US HWY 290E AND .25 MILE WEST OF THE INTX OF		TX COMP HIST
AUSTIN	S126971231	BRENTWOOD WATER & WASTEWATER PIPELINE RENEWAL	WITH BRENTWOOD PARK ARCADIA AVE FROM ARROYO SECO TO WILD ST., BRENTWOOD ST. FROM ARROY SECO TO N. LAMAR BLVD., HALL ST. / GOODNIGHT LANE FROM ARROYO SECO TOPAYNE AVE. AND ARROYO SECO FROM ALGUNO ROAD	78757	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S126963532	TOWNPLACE SUITES AT BRAKER LANE	SITE IS LOCATED APPROXIMATELY 0.10 MILES EAST OF THE INTERSECTION OF BRAKER LANE AND KRAMER LANE.	78758	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S126961376	DOMAIN SOUTH END DISTRICT D	ON THE SOUTH WEST CORNER OF ALTERRA PARKWAY AND KRAMER LANE INTERSECTION	78758	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S126961417	THE BOWEN	3000 GRACIE KILTZ LANE 0.07 MILES SSW FROM ALTERRA PARKWAY AND KRAMER LANE	78758	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S128557046	EMERALD POINT MARINA WWTP	WEST SIDE OF HI-LINE RD OFF OF HUDSON BEND RD APPROXIMATELY .075 MILE NORTH-NORT		TX COMP HIST
AUSTIN	S127029774	QUARRY OAKS MADISON TRACT	NW CORNER OF BRAKER LN & STONELAKE BLVD		TX COMP HIST
AUSTIN	S126970292	CITY OF AUSTIN 2016 BOND INTERSECTION SAFETY IMP	PARKER LN AT E. OLTORF-- N. LAMAR AT PEYTON GIN ROAD-- BRAKER LN AT STONELAKE BLVD.-- W. ST. JOHN AVE. AT N. LAMAR	78758	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S126966601	NYOS PUBLIC WATERLINE	EAST OF THE INTERSECTION OF CHIMNEY ROCK DRIVE AND NORTH LAMAR BLVD.	78758	TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN	S111100772	FERN BLUFF MUD MS4	AREA WITHIN THE CITY OF ROUND ROCK ETJ AND WITHIN THE AUSTIN URBANIZED AREA		TX COMP HIST
AUSTIN	S115812518	ABIA NEW EMPLOYEE PARKING LOT	THE PROJECT IS LOCATED IN THE AUSTIN BERGSTROM INTERNATIONAL AIRPORT COMPLEX AND		TX COMP HIST
AUSTIN	S126962023	AUSTIN COMMUNICTY COLLEGE RGC	1204 & 1206 WEST AVE AUSTIN TX 78701		TX COMP HIST, TX CENTRAL REGISTRY
AUSTIN ETJ	S128260853	1724 CHEDDAR LOOP	NORTHWEST OF S I-35 FRONTAGE RD & CHEDDER LOOP RD	78728	TX CENTRAL REGISTRY
AUSTIN ETJ	1027156962	1724 CHEDDAR LOOP	NORTHWEST OF S I-35 FRONTAGE RD & CHEDDER LOOP RD	78728	FINDS, ECHO
AUSTN	S126813065	TXDOT - AUS - CSJ 0113-13-106	US 290/SH 71 IN TRAVIS COUNTY FROM .74 MI W. OF SOUTH CONGRESS AVE. TO WEST OF BURLESON ROAD	78741	TX CENTRAL REGISTRY
AUTIN	1027581659	RED LINE COMMUTER RAIL MCKALLA STATION	ALONG EXISTING CAP METRO RAIL N. FROM WEST BRAKER	78758	FINDS, ECHO
BROWNSVILLE	S128993454	MOTUS T-3	FROM INTERSECTION OF SH 550 AND STATE HIGHWAY 48 DRIVE SOUTH ON SH 550 .2 MILES, THEN EAST ON FARM TO MARKET ROAD 1792 .6 MILES	78751	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CITRUS CITY	S124055204	FOY MORGAN COMPRESSOR STATION	W ON HWY 83 FROM MISSION TURN RIGHT ON TOM GILL RD GO FIVE MI SITE APPROX 38 FT TO WEST OF RD	78752	TX CENTRAL REGISTRY
COUNTY	S123844722	STATE DEPT OF HWYS & TRANS	EDMUND TATE SITE, AUSTIN, TX	78711	TX CENTRAL REGISTRY
COUNTY	S126532873	THOMPSON GRAPHICS	FM 210, AUSTIN, TX	78701	TX CENTRAL REGISTRY
DECATUR	S124220073	PATRICIA BARNETT NO 1 TANK BATTERY	FROM DECATUR, TRAVEL NORTHEAST ON FM 51 FOR 15.7 MILES. TURN NORTH ON COUNTY LINE AND TRAVEL 1.9 MILES. TURN WEST ON CR 2937 AND TRAVEL 0.4 MILE TO SITE.	78746	TX CENTRAL REGISTRY
DECATUR	S124220072	KNOX NO 1 TANK BATTERY	FROM DECATUR, TRAVEL NORTHEAST ON FM 51 FOR 15.7 MILES. TURN NORTH ON COUNTY LINE ROAD AND TRAVEL 1.9 MILES. TURN WEST ON CR 2937 AND TRAVEL 0.7 MILE. TURN SOUTH ON LEASE ROAD AND TRAVEL 0.5 MILE TO S	78746	TX CENTRAL REGISTRY
GALVESTON	97374594		EAST BEACH ATFELT PARK	78711	ERNS
HUTTO	S126789664	WILLIAMSON COUNTY WSID DISTRICT 3 MS4	AREA WITHIN THE DISTRICT BOUNDARIES APPROX 732 ACRES IN SE WILLIAMSON COUNTY AND NE TRAVIS COUNTY 2 MILES SOUTH OF HWY 79 WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
LEANDER	S126699770	HEB LEANDER ROADWAY PROJECT	950 FT NORTH OF THE INTERSECTION ON US 183 AND WEST BROADE STREET	78764	TX CENTRAL REGISTRY
LOCKHART	S126691050	WINDRIDGE ADDITION SECTION 3	ON W SAN ANTONIO & MOCKINGBIRD DRIVE	78746	TX CENTRAL REGISTRY
LOCKHART	1024186539	WINDRIDGE ADDITION SECTION 3	ON W SAN ANTONIO & MOCKINGBIRD DRIVE	78746	FINDS
MARBLE FALLS	S126894574	SAVAGE RANCH PIT	FROM THE INTERSECTION OF FM 1431 AND CR 122, TRAVEL NORTH ON CR 122 FOR ~ 2 MILES. SITE IS LOCATED ON THE WEST SIDE OF THE ROAD.	78765	TX CENTRAL REGISTRY
MASON	S126906924	CSJ 0577-01-026 SH71 AT RM386	.1190MILES SOUTH OF SH71 TO .303 MILES EAST OF RM386	78768	TX CENTRAL REGISTRY
MASON	1024204139	CSJ 0577-01-026 SH71 AT RM386	.1190MILES SOUTH OF SH71 TO .303 MILES EAST OF RM3	78768	FINDS
MIDLAND	S126081461	SPANISH TRAIL 25-36H BATTERY	FROM TX-158 AND TX-191 INTERSECTION, GO WEST ON TX-191 FRONTAGE RD TURN RIGHT ONTO TX-349N RANCH ROAD 188N AND DRIVE 1.7 MILES TO SITE	78701	TX CENTRAL REGISTRY
MISSION	S113434428	CITY OF MISSION	1.25 MILES NORTH OF HOLLAND ROAD	78752	TX SPILLS
MISSION	1011264093	CITY OF MISSION	1.25 MILES NORTH OF HOLLAND ROAD,	78752	FINDS
MONAHANS	S124104175	JACK EDWARDS J SATELLITE BATTERY	FROM I-20 & HWY 18 INTX , DRIVE SOUTH APPRX 0.9 M, TURN EAST& DRIVE 0.7 M, TURN SOUTH AT CATTLEGUARD & DRIVE 0.5 M, TURN E AT 4-WAY INTX & DR 4.1 M , TURN SOUTH AT "Y" INTX & DRIVE 0.4 M TO SITE	78756	TX CENTRAL REGISTRY
OAK HILL	S123866884	JOE MCDANIEL CONSTRUCTION	HWY 71 WEST	78701	TX CENTRAL REGISTRY
OLIVIA	S126613113	KELLER CREEK TANK BATTERY	LOCATED ON STATE HIGHWAY 314 .5 MILES EAST OF JUNCTION OF COUNTY ROAD 314 AND STATE HWY 172	78701	TX CENTRAL REGISTRY
PEGGY	S126690282	ESSE AML REGRADE PROJECT	EAST OF PIT & SPOIL PILE ON COUNTY RD 262	78711	TX CENTRAL REGISTRY
PFLUGERVILLE	S129002471	AUTO NATION	SOUTHWEST CORNER OF GRAND AVE PKWY AND S I-35 FRONTAGE RD	78728	TX CENTRAL REGISTRY
PFLUGERVILLE	S126706625	RODMAN EXCAVATION THE RANCH AT BRUSHY CREEK SECTION 1	ON E SIDE OF PARMER LN 1.1 M N OF BRUSHY CREEK RD	78728	TX CENTRAL REGISTRY
PFLUGERVILLE	S126873378	NORTHEAST TRAVIS COUNTY UTILITY DISTRICT MS4	AREA EAST OF THE CITY OF PFLUGERVILLE LIMITS THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126783719	LAKESIDE WCID 2-B MS4	N OF INTERX OF KENNEMER DR & BUTLER NATIONAL S OF ROWE LN OFF FM 685 WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126871470	LAKESIDE WCID 2-D MS4	AREA SW OF THE INTERX OF HODDE LN AND SPEIDEL DR WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
PFLUGERVILLE	S126783768	LAKESIDE WCID 2-C MS4	AREA S OF THE INTERX OF ROWE LN AND MARTIN LN AND E OF FM 685 WITHIN THE ETJ OF THE CITY OF PFULGERVILLE LIMITS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126874938	KELLY LANE WCID 2 MS4	AREA WITHIN THE CITY OF PFLUGERVILLE ETJ THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126783715	LAKESIDE WCID 1 MS4	N OF INTERX OF KENNEMER DR & BUTLER NATIONAL S OF ROWE LN OFF FM 685 WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S127056665	CITY OF PFLUGERVILLE - OLD AUSTIN-HUTTO RD	PROJECT START IS LOCATED NORTH OF THE INTERSECTION OF E PECAN ST FM 1825 AND OLD AUSTIN-HUTTO RD AND EXTENDS NORTHEAST FOR 4294 FT, TERMINATING AT THE INTERSECTION OF FM 685 & OLD AUSTIN-HUTTO RD	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126783138	KELLY LANE WCID 1 MS4	AREA LOCATED W OF WEISS LN N OF KELLY LN AND E OF THE CITY OF PFLUGERVILLE LIMITS IN THE AUSTIN URBANIZED AREA	78660	TX CENTRAL REGISTRY
PFLUGERVILLE	S126692508	TXDOT CSJ 313601126	ON FM 1325 FROM PARMER LN NORTH TO MERRILTOWN RD	78727	TX CENTRAL REGISTRY
PFLUGERVILLE	S112056413	GENERAL TRUCKING I-35 TRUCK FIRE AND SPILL	LOCATED ON THE NORTH BOUND SIDE OF I-35 APPROXIMATELY 800 FEET NORTH OF GRAND AVENUE PKWY	78660	TX SPILLS, TX CENTRAL REGISTRY
PFLUGERVILLE	1027568380	AUTO NATION	SOUTHWEST CORNER OF GRAND AVE PKWY AND S I-35 FRON	78728	FINDS, ECHO
PFLUGERVILLE	1024186831	TXDOT CSJ 313601126	ON FM 1325 FROM PARMER LN NORTH TO MERRILTOWN RD	78727	FINDS
PFLUGERVILLE	S119153866	PFLUGERVILLE ISD PARMER LANE ELEMENTARY	1807 PARMER LANE	78660	TX ASBESTOS
PFLUGERVILLE	S120692233	CITY OF PFLUGERVILLE MS4	AREA WITHIN LIMITS OF THE CITY OF PFLUGERVILLE THAT IS LOCATED WITHIN THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
PFLUGERVILLE	S121973129	LAKESIDE WCID 2-D MS4	AREA SW OF THE INTERX OF HODDE LN AND SPEIDEL DR WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
PFLUGERVILLE	S121973031	LAKESIDE WCID 1 MS4	N OF INTERX OF KENNEMER DR & BUTLER NATIONAL S OF ROWE LN OFF FM 685 WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
PFLUGERVILLE	S121973032	LAKESIDE WCID 2-B MS4	N OF INTERX OF KENNEMER DR & BUTLER NATIONAL S OF ROWE LN OFF FM 685 WITHIN THE ETJ OF THE CITY OF PFLUGERVILLE LIMITS WITHIN AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
PFLUGERVILLE	S121973033	LAKESIDE WCID 2-C MS4	AREA S OF THE INTERX OF ROWE LN AND MARTIN LN AND E OF FM 685 WITHIN THE ETJ OF THE CITY OF PFULGERVILLE LIMITS LOCATED WITHIN THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
ROLLINGWOOD	S126783820	CITY OF ROLLILNGWOOD MS4	AREAS WITHIN THE CITY OF ROLLINGWOOOD AND ETJ BOUNDARIES THAT ARE LOCATED WITHIN THE AUSTIN URBANIZED AREA	78746	TX CENTRAL REGISTRY
ROLLINGWOOD	S110506009	CITY OF ROLLILNGWOOD MS4	AREAS WITHIN THE CITY OF ROLLINGWOOOD AND ETJ BOUNDARIES THAT ARE LOCATED WITHIN THE AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
TRAVIS COUNTY	2007840885		8600 BLOCK OF RESEARCH BLVD		ERNS
TRAVIS COUNTY	S103258945	HIGHWAY 71 LAND	HWY 71 WEST		TX CLI
TRAVIS COUNTY	S119135321	MANORWOOD DEVELOPMENT	POINT NORTH DR., E OF JOHNNY MORRIS RD		TX CLI
TRAVIS COUNTY	S108890991	WALNUT CREEK WWTP	APPROXIMATELY 1 MILE EAST OF THE INTERSECTION OF FARM-TO-MARKET RD 969 & US HIGHWAY 183 ON THE SOUT		TX SPILLS
TRAVIS COUNTY	S108890990	SOUTH AUSTIN REGIONAL WWTP	BETWEEN ONION CREEK AND THE COLORADO RIVER APPROXIMATELY 2 MILES WEST OF THEIR CONFLUENCE APPROXIM		TX SPILLS
TRAVIS COUNTY	M300005573	CEMEX, INC.	RIO COLORADO		US MINES
TRAVIS COUNTY	1024176097	LOOP 1 MAINTENANCE CSJ 3136 01 115	LOOP1 COLORADO R TO SOUTHWEST PARKWAY		FINDS

City	EDR ID	Site Name	Site Address	Zip	Database(s)
TRAVIS COUNTY	1024176055	US 290 SIDEWALK EXCEPTION	BETWEEN BRODIE LANE AND LAMAR BLVD		FINDS
TRAVIS COUNTY	1024176347	WILL DAVIS ELEMENTARY SCHOOL NATURE TRAIL	E OF WEST COW PATH AND N OF DUVAL RD AUSTIN		FINDS
TRAVIS COUNTY	1024176146	LOOP 1 EXTENSION PARMER LANE TO TANDEM BOULEVARD	ALONG FM 1325 FROM PARMER LN TO TANDEM BLVD		FINDS
TRAVIS COUNTY	1024203588	DWAYNE LOCKHART	AUSTIN TX		FINDS
TRAVIS COUNTY	1024204608	DAVID SHEIVES	AUSTIN TX		FINDS
TRAVIS COUNTY	1024176005	FM 734 AT MCNEIL DRIVE	FM 734 AT MCNEIL DR		FINDS
TRAVIS COUNTY	1024207254	WALMART AUTO CENTER 2133	5017 W HIGHWAY 290 AUSTIN		FINDS
TRAVIS COUNTY	1024205828	LAND RESTORATION	AUSTIN TX		FINDS
TRAVIS COUNTY	1024177117	EVERYDAY STORE NUMBER 5208	11643 US 183 AUSTIN TX		FINDS
TRAVIS COUNTY	1024204086	ANTONIO VELASQUES	AUSTIN TX		FINDS
TRAVIS COUNTY	1024176361	TEXAS DEPT OF TRANSPORTATION BASTROP HWY AUSTIN	780 BASTROP HIGHWAY AUSTIN TX 78743		FINDS
TRAVIS COUNTY	S128645177	80 RAINEY STREET	78 80 82 AND 84 RAINEY ST		TX APAR
TRAVIS COUNTY	S127375939	5TH AND COLORADO	107 W 5TH ST 409 & 419 COLORADO ST		TX APAR
TRAVIS COUNTY	S116764827	FORMER FEATHERLITE	2901 MARTIN LUTHER KING BLVD		TX APAR
TRAVIS COUNTY	S126511159	CRESTVIEW STATION	TRIANGULAR PIECE OF LAND BOUNDED BY NORTH LAMAR TO THE EAST, RAILROAD TRACKS TO THE WEST AND MORROW ROAD TO THE NORTH		TX APAR
TRAVIS COUNTY	S122490157	AUSTIN ENERGY CRESCENT TRACT	CESAR CHAVEZ ST AND WALTER SEAHOLM DR AUSTIN TX 78703		TX APAR
TRAVIS COUNTY	S106951409	WW BRODIE MULTI FAMILY	BRODIE LN APPROX 450 FT N OF BRODIE & DAVIS LN INT		TX ENF, TX COMP HIST
TRAVIS COUNTY	S127146401	MOODY ARENA UT MLK AT IH 35	MOODY ARENA UT 15TH AT IH 35	78701	TX ENF, TX COMP HIST
TRAVIS COUNTY	S107649451	RIVER PLACE MUD	SOUTH OF RM 2222 ONE MILE EAST OF FM 620 N		TX ENF
TRAVIS COUNTY	S107637135	THE PIER	NORTH OF FM 2244 AT RIVER HILLS RD		TX ENF
TRAVIS COUNTY	S127143800	FOREST OAKS VILLAGE MH COMMUNITY	NORTH OF FM 1626 2 MILES WEST OF IH 35		TX ENF
TRAVIS COUNTY	S110651534	5800 GIBBS HOLLOW	SOUTH OF LONG CANYON DR AND WEST OF RR 2222		TX ENF
TRAVIS COUNTY	S109115444	GLENVILLE WATER	6 MILES WEST OF HAMILTON POOL ST ON HWY 71		TX ENF, TX COMP HIST
TRAVIS COUNTY	S107646426	LCRA PACE BEND RECREATION AREA	PACE BEND ROAD, SPICEWOOD, TRAVIS		TX ENF
TRAVIS COUNTY	S118665633	DWAYNE LOCKHART	AUSTIN TX		TX ENF
TRAVIS COUNTY	S110651041	HIDDEN LAKE	11.5 MI NORTHWEST OF AUSTIN, TX		TX ENF
TRAVIS COUNTY	S107643558	SENDERA SECTION 11 SEDIMENTATION POND	BEHIND 8509 COPANO DRIVE AUSTIN		TX ENF, TX COMP HIST
TRAVIS COUNTY	S107654262	PERFECT LAWNS OF AUSTIN	UNLICENSED INSTALLER 2521 CUERNAVACA AUSTIN		TX ENF
TRAVIS COUNTY	S110650806	APACHE LAKE DAM	APPROXIMATELY 200 FEET EAST OF THE INTERSECTION OF GREAT EAGLE TRAIL AND GERONIMO TRAIL IN CITY LIMITS OF AUSTIN		TX ENF
TRAVIS COUNTY	S127144788	CITY OF AUSTIN SEWAGE COLLECTION SYSTEM	CITY OF AUSTIN WASTEWATER COLLECTION SYSTEM		TX ENF, TX COMP HIST
TRAVIS COUNTY	S110651957	COLD SPRINGS	COLORADO RIVER		TX GCC
TRAVIS COUNTY	S110149871	TECHNICOATS SITE	301 NORTHEAST 6TH STREET		TX GCC
TRAVIS COUNTY	S110148209	AUTO IMPROVEMENTS	1018 WEST NORTHWEST HIGHWAY		TX GCC
TRAVIS COUNTY	S110651959	COLORADO RIVER HORNSBY BEND	0.9 MILES NORTHWEST OF THE INTERSECTION OF FM 973 AND HWY 71 ON HORNSBY BEND EAST OF THE COLORADO RI		TX GCC
TRAVIS COUNTY	S125363462	COLORADO RIVER HORNSBY BEND	0.9 MI NORTHWEST OF THE INTERSECTION OF FM 973 AND HWY 71 ON HORNSBY BEND EAST OF THE COLORADO RIVER		TX GCC
TRAVIS COUNTY	S127023458	COLORADO RIVER HORNSBY BEND	0.9 MI NW OF THE INTERSECTION OF FM 973 AND HWY 71 ON HORNSBY BEND EAST OF THE COLORADO RIVER		TX GCC
TRAVIS COUNTY	S110651953	COASTAL STATES CRUDE GATHERING CO	AUSTIN		TX GCC
TRAVIS COUNTY	S126222511	GOVALLE WWTP	LOCATED N OF THE COLORADO RIVER APPROX 1 MILE E OF THE US HWY 183 CROSSING OF THE COLORADO RIVER		TX NPDES

City	EDR ID	Site Name	Site Address	Zip	Database(s)
TRAVIS COUNTY	S126222645	NEW SWEDEN WWTP	LOCATED 2500 FT EAST OF THE INTERSECTION OF FM 973 & NEW SWEDEN CHURCH RD		TX NPDES
TRAVIS COUNTY	S121293792	MADRONE RANCH WWTP	LOCATED ON HAMILTON POOL RD APPROX 1.3 MI WEST OF CRUMLEY RANCH RD & 1.0 MI E OFRR 12		TX NPDES
TRAVIS COUNTY	S127508522	FLINTROCK WWTP	LOCATED APPROX 600 FT WEST OF THE INTERSECTION OF RANCH RD 620 & LOHMANS CROSSING RD, APPROX 1400 FT S OF THE CROSSING OF LOHMANS CROSSING RD WITH YAUPON CREEK		TX NPDES
TRAVIS COUNTY	S121293856	THE WOODS OF GREENSHORES WWTP	LOCATED 3100 FEET SE OF THE INTERX OF CITY PARK RD & OAK SHORES DR W OF CONNORS CREEK & BETWEEN LAKE AUSTIN METROPOLITAN PARK & LAKE AUSTIN		TX NPDES
TRAVIS COUNTY	S126222465	CITY OF AUSTIN MS4	INCLUDING ALL AREAS EXCEPT FOR AGRICULTURAL LANDS LOCATED WITHIN THE CORPORATE BOUNDARY OF THE CITY OF AUSTIN SERVED BY OR OTHERWISE CONTRIBUTING TO DISCHARGES TO THE MS4 OWNED OR OPERATED BY THE PERM		TX NPDES
TRAVIS COUNTY	S127508599	EMBARCADERO WWTP	LOCATED S OF LK AUSTIN. 120 FT E OF RIVER HILLS RD, 0.65 MILES NE OF INTERX OF RIVER HILLS RD & SUMNER CT. & 685 FT SW OF INTERX OF RIVER HILLS RD & TAYLOR RD IN TRAVIS CNTY		TX NPDES
UNAVAILABLE	S113436288	NEXT TO 501 DRAWBRIDGE RD AUSTIN TEXAS	NEXT TO 501 DRAWBRIDGE RD AUSTIN TEXAS 78746	78746	TX SPILLS
WESLACO	S126766863	BALLARD STREET EXPANSION	BALLARD STREET FROM ALLEY EAST TO BRIDGE AVENUE	78756	TX CENTRAL REGISTRY
WEST LAKE HILLS	S126907532	ST JOHN NEUMANN CATHOLIC CHURCH - RECTORY AND PARKING	EAST OF THE INTERSECTION OF LOOP 360 S. CAPITAL OF TEXAS HIGHWAY AND LAS CIMAS PARKWAY	78746	TX CENTRAL REGISTRY
WEST LAKE HILLS	S126839932	STRATFORD RESERVE PLACE	LOCATED APPROXIMATELY .45 MILES SOUTH OF THE INTERSECTION OF RED BUD TRAIL AND STRATFORD DRIVE ON THE WEST SIDE OF STRATFORD RESERVE PLACE.	78746	TX CENTRAL REGISTRY
WEST LAKE HILLS	S126555015	RIVERCREST WS	512 HILLBILLY LANE WEST LAKE HILLS TEXAS	78746	TX CENTRAL REGISTRY
WEST LAKE HILLS	S126819934	CITY OF WEST LAKE HILLS MS4	AREA WITHIN WEST LAKE HILLS CITY LIMITS LOCATED WITHIN AUSTIN URBANIZED AREA	78746	TX CENTRAL REGISTRY
WEST LAKE HILLS	1015982036	CITY OF WEST LAKE HILLS MS4	WITHIN WEST LAKE HILLS CITY LIMITS LOCATED WITHIN	78746	FINDS, ECHO
WEST LAKE HILLS	S111325941	CITY OF WEST LAKE HILLS MS4	AREA WITHIN WEST LAKE HILLS CITY LIMITS LOCATED WITHIN AUSTIN URBANIZED AREA		TX ENF, TX COMP HIST
WESTLAKE HILLS	S126910463	RM 2244 STP 1502 598 CSJ 2102-01-066 ETC	RM 2244 0.1 MILE EAST OF REDBUD TRAIL TO WALSH TARLETON LANE	78746	TX CENTRAL REGISTRY
WESTLAKE HILLS	S126690550	WESTLAKE HILLS WASTEWATER COLLECTION SYSTEM PHASE 1	ON RIDGEWOOD AT GENTRY & WEST OF ROLLINGWOOD TEXAS	78746	TX CENTRAL REGISTRY
WESTLAKE HILLS	S126694714	WESTLAKE HILLS WASTEWATER COLLECTION SYSTEM PHASE I	ON RIDGEWOOD AT GENTRY & WEST OF ROLLINGWOOD TEXAS	78746	TX CENTRAL REGISTRY
WESTLAKE HILLS	1024204675	RM 2244 STP 1502 598 CSJ 2102-01-066 ETC	RM 2244 0.1 MILE EAST OF REDBUD TRAIL TO 1000 FT.	78746	FINDS, ECHO
WHITSETT	S126683871	HOT MIX PLANT 6 WHITSETT	ON HIGHWAY 281, 1.5 MILES NORTH OF THREE RIVERS	78705	TX CENTRAL REGISTRY
WILLIAMSON COUNTY	1024180687	STATE DEPT OF HWYS & TRANS	EDMUND TATE SITE, AUSTIN, TX	78711	FINDS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2023
Date Data Arrived at EDR: 03/28/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/23/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/25/2023
Date Data Arrived at EDR: 05/31/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 54

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/12/2023
Date Data Arrived at EDR: 06/20/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 55

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of state- and tribal (Superfund) equivalent sites

SHWS: State Superfund Registry

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 03/23/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/20/2023
Number of Days to Update: 83

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5680
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Semi-Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Permitted Solid Waste Facilities

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 04/20/2023
Date Made Active in Reports: 07/12/2023
Number of Days to Update: 83

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6706
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Quarterly

DEBRIS: Approved Debris Management Sites Locations

A listing of temporary debris management sites and MSW landfills for debris resulting from Hurricane Harvey.

Date of Government Version: 03/27/2018
Date Data Arrived at EDR: 04/04/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 65

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6840
Last EDR Contact: 06/01/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

CLI: Closed Landfill Inventory

Closed and abandoned landfills (permitted as well as unauthorized) across the state of Texas. For current information regarding any of the sites included in this database, contact the appropriate Council of Governments agency.

Date of Government Version: 08/30/1999
Date Data Arrived at EDR: 09/28/2000
Date Made Active in Reports: 10/30/2000
Number of Days to Update: 32

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/26/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: No Update Planned

H-GAC CLI: Houston-Galveston Closed Landfill Inventory
Closed Landfill Inventory for the Houston-Galveston Area Council Region. In 1993, the Texas Legislature passed House Bill (HB) 2537, which required Councils of Governments (COGs) to develop an inventory of closed municipal solid waste landfills for their regional solid waste management plans.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/13/2023
Number of Days to Update: 76

Source: Houston-Galveston Area Council
Telephone: 832-681-2518
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

WASTE MGMT: Commercial Hazardous & Solid Waste Management Facilities
This list contains commercial recycling facilities and facilities permitted or authorized (interim status) by the Texas Natural Resource Conservation Commission.

Date of Government Version: 10/16/2019
Date Data Arrived at EDR: 01/10/2020
Date Made Active in Reports: 03/18/2020
Number of Days to Update: 68

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2920
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

Lists of state and tribal leaking storage tanks

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

LPST: Leaking Petroleum Storage Tank Database
An inventory of reported leaking petroleum storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 03/28/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 04/04/2023
Number of Days to Update: 6

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2200
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RDR: Release Determination Report Listing
An owner-operator permanently removing an underground storage tank system from service must determine whether a release of a stored regulated substance has occurred. Assemble and submit documentation of tank removal and release determination?including the details of all excavation, removal, and sampling activities?to the TCEQ using the PST Program?s Release Determination Report form (TCEQ-00621).

Date of Government Version: 03/29/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/04/2023
Number of Days to Update: 5

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2081
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 03/08/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 82

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

UST: Petroleum Storage Tank Database
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 03/02/2023
Date Data Arrived at EDR: 03/22/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 77

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

AST: Petroleum Storage Tank Database
Registered Aboveground Storage Tanks.

Date of Government Version: 03/02/2023
Date Data Arrived at EDR: 03/22/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 77

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

TANKS: Petroleum Storage Tanks Listing

A list of facilities included on the Petroleum Storage Tank database that have no association as either underground or aboveground tanks.

Date of Government Version: 03/02/2023
Date Data Arrived at EDR: 03/22/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 77

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0985
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

AUL: Sites with Controls
Activity and use limitations include both engineering controls and institutional controls.

Date of Government Version: 04/06/2023
Date Data Arrived at EDR: 04/06/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 76

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

VCP RRC: Voluntary Cleanup Program Sites
The Voluntary Cleanup Program (RRC-VCP) provides an incentive to remediate Oil & Gas related pollution by participants as long as they did not cause or contribute to the contamination. Applicants to the program receive a release of liability to the state in exchange for a successful cleanup.

Date of Government Version: 04/01/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 06/29/2023
Number of Days to Update: 78

Source: Railroad Commission of Texas
Telephone: 512-463-6969
Last EDR Contact: 07/11/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

VCP TCEQ: Voluntary Cleanup Program Database
The Texas Voluntary Cleanup Program was established to provide administrative, technical, and legal incentives to encourage the cleanup of contaminated sites in Texas.

Date of Government Version: 06/23/2023
Date Data Arrived at EDR: 06/27/2023
Date Made Active in Reports: 07/11/2023
Number of Days to Update: 14

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site Assessments
Brownfield site assessments that are being cleaned under EPA grant monies.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 5

Source: TCEQ
Telephone: 512-239-5872
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 04/06/2023
Date Data Arrived at EDR: 04/13/2023
Date Made Active in Reports: 04/19/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/08/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

CAPCOG LI: Capitol Area Landfill Inventory

Permitted and unpermitted landfills for the CAPCOG region. Serving Bastrop, Blanco, Burnet, Caldwell, Fayette, Hays, Lee, Llano, Travis, and Williamson Counties.

Date of Government Version: 11/11/2022
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 06/05/2023
Number of Days to Update: 13

Source: Capital Area Council of Governments
Telephone: 512-916-6000
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

NCTCOG LI: North Central Landfill Inventory

North Central Texas Council of Governments landfill database.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/14/2023
Number of Days to Update: 77

Source: North Central Texas Council of Governments
Telephone: 817-695-9223
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

SWRCY: Recycling Facility Listing

A listing of recycling facilities in the state.

Date of Government Version: 05/08/2023
Date Data Arrived at EDR: 05/10/2023
Date Made Active in Reports: 08/03/2023
Number of Days to Update: 85

Source: TCEQ
Telephone: 512-239-6700
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

HIST LF: Historical Information About Municipal Solid Waste Facilities

An historical information listing old, closed unnumbered MSW landfills that were operated before permits were required, as well as unauthorized landfills and miscellaneous illegal dumps and disposal sites.

Date of Government Version: 02/01/2022
Date Data Arrived at EDR: 09/28/2022
Date Made Active in Reports: 05/24/2023
Number of Days to Update: 238

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2335
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/11/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: No Update Planned

CDL: Clandestine Drug Site Locations Listing
A listing of former clandestine drug site locations

Date of Government Version: 09/07/2021
Date Data Arrived at EDR: 12/09/2021
Date Made Active in Reports: 03/01/2022
Number of Days to Update: 82

Source: Department of Public Safety
Telephone: 512-424-2144
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

PRIORITY CLEANERS: Dry Cleaner Remediation Program Prioritization List
A listing of dry cleaner related contaminated sites.

Date of Government Version: 09/01/2022
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 75

Source: Texas Commisision on Environmenatl Quality
Telephone: 512-239-5658
Last EDR Contact: 05/30/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DEL SHWS: Deleted Superfund Registry Sites
Sites have been deleted from the state Superfund registry in accordance with the Act, 361.189

Date of Government Version: 03/23/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/20/2023
Number of Days to Update: 83

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0666
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Quarterly

CENTRAL REGISTRY: The Central Registry
The Central Registry, a common record area of the TCEQ, maintains information about TCEQ customers and regulated activities, such as company names, addresses, and telephone numbers. This information is commonly referred to as "core data". The Central Registry provides the regulated community with a central access point within the agency to check core data and make changes when necessary.

Date of Government Version: 09/30/2022
Date Data Arrived at EDR: 10/04/2022
Date Made Active in Reports: 12/27/2022
Number of Days to Update: 84

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5175
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

NON REGIST PST: Petroleum Storage Tank Non Registered
A listing of non-registered petroleum storage tank site locations.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/22/2023
Number of Days to Update: 79

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2081
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

Local Land Records

HIST LIENS: Environmental Liens Listing
This listing contains information fields that are no longer tracked in the LIENS database.

Date of Government Version: 03/23/2007
Date Data Arrived at EDR: 03/23/2007
Date Made Active in Reports: 05/02/2007
Number of Days to Update: 40

Source: Texas Commission on Environmental Qualilty
Telephone: 512-239-2209
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

LIENS: Environmental Liens Listing

The listing covers TCEQ liens placed against either State Superfund sites or Federal Superfund sites to recover cost incurred by TCEQ.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 5

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2209
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/19/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Database

Spills reported to the Emergency Response Division.

Date of Government Version: 04/10/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 06/29/2023
Number of Days to Update: 78

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5100
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 10/23/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 05/15/2005
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/08/2023
Date Data Arrived at EDR: 05/16/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 55

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/16/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/10/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/01/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/19/2023
Date Data Arrived at EDR: 06/20/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 55

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/03/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/16/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 75

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/19/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/17/2023
Date Data Arrived at EDR: 04/18/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 83

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/18/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/07/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/15/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 04/14/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/03/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/25/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/20/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/26/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites
A listing of former lead smelter site locations.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites
A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/03/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2023
Date Data Arrived at EDR: 05/24/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 61

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 01/07/2022
Date Data Arrived at EDR: 02/24/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 82

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/13/2023
Date Data Arrived at EDR: 06/14/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 61

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/04/2023
Date Data Arrived at EDR: 05/25/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 60

Source: EPA
Telephone: (214) 665-2200
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/25/2023
Date Data Arrived at EDR: 03/31/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 05/17/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 54

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information
EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information
Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information
EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 04/27/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

PFOS and PFOA stand for perfluorooctane sulfonate and perfluorooctanoic acid, respectively. Both are fluorinated organic chemicals, part of a larger family of compounds referred to as perfluoroalkyl substances (PFASs).

Date of Government Version: 03/01/2023
Date Data Arrived at EDR: 03/08/2023
Date Made Active in Reports: 05/31/2023
Number of Days to Update: 84

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2341
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

AQUEOUS FOAM: AFFF Sites Listing
A list of Aqueous Film Forming Foam (AFFF) sites.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/15/2023
Date Made Active in Reports: 06/05/2023
Number of Days to Update: 82

Source: Texas Commission on Environmental Quality
Telephone: 512-239-1913
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

AIRS: Current Emission Inventory Data
The database lists by company, along with their actual emissions, the TNRCC air accounts that emit EPA criteria pollutants.

Date of Government Version: 03/09/2023
Date Data Arrived at EDR: 03/15/2023
Date Made Active in Reports: 05/31/2023
Number of Days to Update: 77

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Semi-Annually

APAR: Affected Property Assessment Report Site Listing
Listing of Sites That Have Received an APAR (Affected Property Assessment Report)

Date of Government Version: 04/03/2023
Date Data Arrived at EDR: 04/06/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 76

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5872
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

ASBESTOS: Asbestos Notification Listing
A listing of asbestos notification site locations.

Date of Government Version: 02/23/2023
Date Data Arrived at EDR: 02/28/2023
Date Made Active in Reports: 05/18/2023
Number of Days to Update: 79

Source: Department of State Health Services
Telephone: 512-834-6787
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Sites
A listing of facilities that use surface impoundments or landfills to dispose of coal ash.

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 04/26/2023
Date Made Active in Reports: 07/17/2023
Number of Days to Update: 82

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6624
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

DRYCLEANERS: Drycleaner Registration Database Listing
A listing of drycleaning facilities.

Date of Government Version: 01/11/2023
Date Data Arrived at EDR: 02/22/2023
Date Made Active in Reports: 05/16/2023
Number of Days to Update: 83

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

ED AQUIF: Edwards Aquifer Permits
A listing of permits in the Edwards Aquifer Protection Program database. The information provided is for the counties located in the Austin Region (Hays, Travis, and Williamson counties).

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 03/31/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 3

Source: Texas Commission on Environmental Quality, Austin Region
Telephone: 512-339-2929
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

ENFORCEMENT: Notice of Violations Listing
A listing of permit violations.

Date of Government Version: 03/17/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/23/2023
Number of Days to Update: 86

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6012
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 03/21/2023
Date Data Arrived at EDR: 03/23/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 11

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6239
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing
Financial Assurance information for underground storage tank facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay

Date of Government Version: 03/02/2023
Date Data Arrived at EDR: 03/22/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 77

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0986
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

GCC: Groundwater Contamination Cases
Texas Water Code, Section 26.406 requires the annual report to describe the current status of groundwater monitoring activities conducted or required by each agency at regulated facilities or associated with regulated activities. The report is required to contain a description of each case of groundwater contamination documented during the previous calendar year. Also to be included, is a description of each case of contamination documented during previous periods for which voluntary clean up action was incomplete at the time the preceding report was issued. The report is also required to indicate the status of enforcement action for each listed case.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 08/29/2022
Date Made Active in Reports: 11/16/2022
Number of Days to Update: 79

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5690
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Annually

IOP: Innocent Owner/Operator Program
Contains information on all sites that are in the IOP. An IOP is an innocent owner or operator whose property is contaminated as a result of a release or migration of contaminants from a source or sources not located on the property, and they did not cause or contribute to the source or sources of contamination.

Date of Government Version: 03/24/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 5

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5894
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

LEAD: Lead Inspection Listing
Lead inspection sites

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 75

Source: Department of State Health Services
Telephone: 512-834-6600
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Varies

Ind. Haz Waste: Industrial & Hazardous Waste Database
Summary reports reported by waste handlers, generators and shippers in Texas.

Date of Government Version: 03/14/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 07/11/2023
Number of Days to Update: 90

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0985
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

MSD: Municipal Settings Designations Database
An MSD is an official state designation given to property within a municipality or its extraterritorial jurisdiction that certifies that designated groundwater at the property is not use as potable water, and is prohibited from future use as potatable water because that groundwater is contaminated in excess of the applicable potable-water protective concentration level.

Date of Government Version: 05/11/2023
Date Data Arrived at EDR: 05/11/2023
Date Made Active in Reports: 05/15/2023
Number of Days to Update: 4

Source: Texas Commission on Environmental Quality
Telephone: 512-239-4982
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

NPDES: NPDES Facility List
Permitted wastewater outfalls.

Date of Government Version: 08/02/2023
Date Data Arrived at EDR: 08/02/2023
Date Made Active in Reports: 08/03/2023
Number of Days to Update: 1

Source: Texas Commission on Environmental Quality
Telephone: 512-239-4591
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

RWS: Radioactive Waste Sites
Sites in the State of Texas that have been designated as Radioactive Waste sites.

Date of Government Version: 07/24/2006
Date Data Arrived at EDR: 12/14/2006
Date Made Active in Reports: 01/23/2007
Number of Days to Update: 40

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0859
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Semi-Annually

TIER 2: Tier 2 Chemical Inventory Reports
A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 06/07/2013
Date Made Active in Reports: 07/22/2013
Number of Days to Update: 45

Source: Department of State Health Services
Telephone: 512-834-6603
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Annually

UIC: Underground Injection Wells Database Listing
Class V injection wells regulated by the TCEQ. Class V wells are used to inject non-hazardous fluids underground. Most Class V wells are used to dispose of wastes into or above underground sources of drinking water and can pose a threat to ground water quality, if not managed properly.

Date of Government Version: 08/09/2022
Date Data Arrived at EDR: 08/10/2022
Date Made Active in Reports: 11/01/2022
Number of Days to Update: 83

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6627
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

IHW CORR ACTION: Industrial and Hazardous Waste Corrective Action Information
Industrial hazardous waste facilities with corrective actions.

Date of Government Version: 03/24/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 04/04/2023
Number of Days to Update: 6

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5872
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

PST STAGE 2: PST Stage 2
State II Vapor Recovery. Decommissioning of Stage II Rule - Gasoline dispensing facilities (GDFs) may begin the process of removing Stage II equipment on May 16, 2014 providing that all other requirements for decommissioning have been met, including appropriate notification.

Date of Government Version: 07/17/2019
Date Data Arrived at EDR: 07/18/2019
Date Made Active in Reports: 09/24/2019
Number of Days to Update: 68

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

COMP HIST: Compliance History Listing
A listing of compliance histories of regulated entities

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/14/2023
Number of Days to Update: 84

Source: Txas Commission on Environmental Quality
Telephone: 512-239-3282
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI
Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: No Update Planned

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Texas Commission of Environmental Quality in Texas formerly known as Texas Natural Resources Conservation Commission which changed in 2002.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/26/2013
Number of Days to Update: 178

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Texas Commission of Environmental Quality in Texas formerly known as Texas Natural Resources Conservation Commission which changed in 2002.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

TRAVIS COUNTY:

HIST UST AUSTIN: Historic Tank Records

A listing of historic records from the City of Austin.

Date of Government Version: 02/27/2023
Date Data Arrived at EDR: 03/01/2023
Date Made Active in Reports: 05/16/2023
Number of Days to Update: 76

Source: Department of Planning & Development Review
Telephone: 512-974-2715
Last EDR Contact: 05/30/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/06/2023
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/10/2022
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/01/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Child Care Facility List
Source: Department of Protective & Regulatory Services
Telephone: 512-438-3269

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Texas General Land Office
Telephone: 512-463-0745

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.